List of EASA Supplemental Type Certificates

easa.europa.eu

Important Note: Information displayed in this report may be truncated/incomplete due to a technical field limitation to 300 characters. Truncated/incomplete text is indicated by three dots […] at the end instead of one. If you need to consult the full text for a specific approval, please send an email request to applicant.services@easa.europa.eu.

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10013930 (EASA.A.S.00277)	AERODATA AG	REV. 2		B300	Installation of Aerodata Automatic Flight Inspection SystemAD-AFIS-112.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2 (elected to comply by the applicant, not required by21A.101) The requirements for environmental protection and the asso...	Installation Manual ,,,,,, HB-A/C-1087, Rev. 0Master Document List ,,,,,, MDL-A/C-067, Rev. 8Maintenance Manual Supplement,, AMM-1088, Rev. 0Flight Manual Supplement,,,, AFM-124, Rev. 1,,or later revisions of the above listed documents approved by EASA.	None	06/05/2011	Active	10013930
10013945 (EASA.A.S.00387)	AIRBUS S.A.S.	REV. 10	LBA TA0441 ISSUE 4	A300 F4-622R A300 F4-622 R A300 B4-620, A300 B4-622 A300 B4-605R, A300 B4-622R A300 B4-601, A300 B4-603	Conversion of A300B4-600 and A300B4-600R aircraft from a Passengerversion to a Freighter version (P2F conversion).This approval was originally issued by the German Luftfahrt Bundesamtunder STC reference TA0441:this STC (issue4) was transferred to EASA under referenceEASA.A.S.00387."- Rev. 1 covered t...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Certification Summary Document EAA2/400/000/001/COS Issue08, dated 16January 2007.- Airbus Deutschland Engineering Order Nr. PFM 00400A Issue 09, dated 07May 2007.- Aircraft Flight Manual Supplement for Airbus A300-600, Revision 07,dated 15 January 2007.- Supplemental Airworthiness Limitations It...	In cases where an AMOC in the AMOC SUMMAY LIST is describesas partialcompliance to the AD requirements, the remaining mandatory actions mustbe performed as indicated within the airworthiness directive.Limitations mentioned in the A300-600P to F – Weight and Balance ManualSupplement.Prior to instal...	06/07/2021	Active	10013945
10013954 (EASA.A.S.00494)	TROYES AVIATION S.A.R.L.	REV. 3		CESSNA F177RG	Installation of a camera sight door under the fuselage.Addition of new aircraft to STC EASA.A.S.00494 Revision 2.	CS23The Certification Basis for the original product remains applicable tothis certificate/ approval.	File ref: FAM N° 59CHANGE FILE N° 53 ISSUE JUNE 2006 - EASA.A.S.00494 R1 and R2MINOR CHANGE N°41	Applicability F177RG S/N 0112, 0065, 103, 087 F-BURU and S/N 51 F-HBAG.	29/03/2010	Active	10013954
10013960 (EASA.A.S.00634)	AIRBUS S.A.S.	REV. 6		A310-304/-308/-324/-325 A310-203/-221/-222	EASA STC 10013960 Revision 6 (A310-200 series and -300 seriesaeroplanes, Passenger to Freighter conversion)(Ref. to former Luftfahrt Bundesamt STC TA0383 Issue 9)- The STC EASA.A.S.00634 has covered the transfer of the STC TA0383Issue 9 (original Aviation Authority reference) from the originalAviati...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.See Certification Summary Documents referenced in Associated TechnicalDocumentation sectionThe requirements for environmental protectionc...	For A310-200 series Aeroplanes- Certification Summary Document (except MSN 349): GQ21213151000-0011COS Rev G. dated 10/02/2009.- Certification Summary Document (for MSN 349) : EQM/001/000-003/COS.dated 16 April 2004.- Airbus Deutschland Engineering Order Nr. PFM 08093A Issue 14. dated 31July 2008.-D...	None	27/06/2012	Active	10013960
10013963 (EASA.A.S.00652)	DOA AESGLOBAL LIMITED	REV. 3		767-300	Introduction of Matsushita In-Flight Entertainment SystemRev 3: Transfer from AES Ltd. to new STC holder AES Global Ltd.		Aerospace Engineering Solutions Master Data List AES-767-367MDL or later approved revision.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	28/04/2021	Active	10013963

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10013964 (EASA.A.S.00654)	LUFTHANSA TECHNIK AG	REV. 3		A340	Installation of non-electrical Floor Path Marking System		- STC TA0018-Supplemental Type Definition Document STDD33-97/01M, Issue 07 dated09.11.2006- Applicant's Declaration ofCompliance dated 15.11.2006- Airplane Flight Manual Supplement A-33-06/367-AFM-Instructions for Continued Airworthinessor later revisions of the above listed documents approved by...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	05/03/2014	Active	10013964
10013967 (EASA.A.S.00701)	LUFTHANSA TECHNIK AG	REV. 3		747-300, 747-400, 747-8	Radome installation for Live TV antennaRev. 1: Incorporation of B747-300 in the applicability listRev. 2: Incorporationof B747-8 in the applicability list and STCoriginal number EASA.A.S. 00701 replaced by new number 10013967Rev. 3: Extension of 747-8 ALI task, based on reassessment of DTAanalysis w...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	B747-300:Supplemental Type Design Document STDD53-12/20M Issue 01 rev 05Maintenance requirements document C-AAL900-MR rev IRB747-400:Supplemental Type Design Document STDD53-12/20M Issue 01 rev 05Instruction for Continued Airworthiness ICA53-0215-01 rev IRB747-8:Supplemental Type Design Document ST...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/11/2020	Active	10013967
10013970 (EASA.A.S.00741)	PROTOPLANE SPECIAL MISSION AIRCRAFT	REV. 3		BEECH 200 B200	Photo Conversion (creation of two hatches for camera).Rev. 3: Transfer of EASA.A.S.00741 Issue 1 for S/N BB-1181and EASA.A.S.00741 Revision 2 for S/N BB221 and BB1607	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	. For S/N BB-1181: EISA-16-PRE-F045 Rev 3 dated 18/12/2008.For S/N BB-221 and BB-1607: - EISA-16-MDL-F050 Rev 1 dated 17/12/08 - EISA-16-AFM-F050 Rev 3 dated 18/12/08- EISA-16-AMM-F050 Rev 1 dated 17/12/08 - EISA-16-ICA-F050 Rev 1 dated 17/12/08or later revisions of the above liste...	Applicable to B200 S/N BB-1181, BB-221, BB-1607;Utilisationof Intercom prohibited in dense traffic areas.Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no a...	16/04/2024	Active	10013970
10013975 (EASA.A.S.00774)	SMA AERO ENGINES GMBH	REV. 15		F182P, F182Q B) F182P, F182Q A) 182M, 182N, 182P, 182Q,182R 182M, 182N, 182P, 182Q, 182R	Installation of SMA Diesel Engine SR305-230 or SR305—230E andMT-Propeller MTV-9-BS/198-58B.Rev. 14: Transfer of STC 10013975 rev 12 from Safran Aircraft EnginesSAS to SMA Aero Engines GmbH.Rev. 15: Update of annex 1 for typos and incorrectreferences.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- SMA Mod. AM 16-082-Flight Manual Supplements: see Appendix dated 17/02/2021- Airworthiness Limitation Information asper Aircraft Service ManualC182-ASMS-01E, Rev. 6, Section 2SMA-AL-Installation Instructions: see Appendix dated 17/02/2021- Aircraft Service Manual C182-ASMS-01E, latest revision....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/09/2023	Active	10013975
10013976 (EASA.A.S.0097)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 2		S550 (CITATION S/II) 560 (CITATION V) 560 (CITATION ULTRA) 550 (CITATION II) 550 (CITATION BRAVO)	Installation of an L3 Digital Flight Data RecorderRevision 2 was raised due to missing technical document references inRevision 1	EASA TCDS IM.A.207The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalJAR 25 at change 15The requirements for environmental protection and the associatedcertificated noise and/ or emissionsu...	- Master Documents List 2018778-01 DOC issue 8, dated 27 Sept. 2010-Engineering Order 2018778-EO-01 Issue 5, dated 26 Sept. 2010-Airplane Flight Manual Supplement 2018778-AM-01A, issue 5 from 19January 2010 for 115 VAC or alternative Airplane Flight ManualSupplement 2018778-AM-01B, issue 2 from 19...	Limited to:S/N 550-0001 through 550-0733 (Citation II)S/N 550-0801 through 550-1136 (Citation Bravo)S/N 560-0001 through 560-0259 (Citation V)S/N 560-0260 through 560-0538 (Citation Ultra)S/N S550-0001 through S550-0160 (Citation S/II)	05/10/2010	Active	10013976

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10013987 (EASA.A.S.01019)	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	737-700	Replacement of a Lufthansa Technik IFE System with an ITAN IFE SystemRevision 1: certificate re-issued after DOA changed its name to H4Aerospace		-BBJ383 Issue 2 dated 21 February 2005 or later approved revision-Flight Manual Supplement BBJFMS014 Issue I/R	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	14/11/2013	Active	10013987
10013993 (EASA.A.S.01024)	AERODATA AG	REV.11		DORNIER 328-100	Installation of Maritime Surveillance System on Dornier 328-100including SAR Radar, FLIR, and optional IR/UV ScannerRevision 4:Functional/optional upgrade to the radar system and mission software tooptimize search and rescue operation. Hardware upgrade to components ofthe ELTA weather & mission rada...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List ref MDL-A/C-089 Rev. 13.- Flight Manual Supplement ref AFM-077 Rev. 10.- Aerodata Maintenance Manual Supplement AMM-782 Rev. 9 dated September2012or later revisions of the above listed documents approved by EASA	Applicable to Aircraft Serials 3051, 3052, 3053, 3057 and 3059 asmodified by Aerodata Modification D328-2.xx for AMSA Mission Purpose.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change...	29/01/2013	Active	10013993
10014001 (EASA.A.S.01038)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		757-200	Installation of Enhanced Mode S TranspondersRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Aviation Traders Ltd Definition Document DD/ 021/9162 Issue2-Aviation Traders Ltd AFM Supplement Number 31 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/11/2021	Active	10014001
10014002 (EASA.A.S.01039)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		737-700	Installation of Enhanced Mode S TranspondersRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Aviation Traders Ltd Definition Document DD/ 022/9218 Issue2-Aviation Traders Ltd AFM Supplement Number 29 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/11/2021	Active	10014002
10014003 (EASA.A.S.01040)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		737-300	Installation of Enhanced Mode S TranspondersRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Aviation Traders Ltd Definition Document DD/ 023/9219/ Issue 2-Aviation Traders Ltd AFM Supplement Number 30 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/11/2021	Active	10014003
10014007 (EASA.A.S.01047)	GROWING ENGINEERING PARTNERS GmbH	REV. 2		B747-400	Reconfiguration of Virgin Atlantic Airways B747-400 from LHR to LGWconfiguration in accordance with SR Technics Master Data ListC747-25-1001-MDL-01, Rev 3 or later approved revisionsRev. 2: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis for the original product remains applicable tothis certificate/ approval.	C747-25-1001-CCS, Rev 3.C747-25-1001-MDL-01, Rev 3or later revisions of the above listed documents approved by EASA	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/04/2021	Active	10014007

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014011 (EASA.A.S.01054)	airplus engineering GmbH	REV. 1		PA-23-250	Installation of1. COM/VOR/ILS/GPS-System Garmin GNS 4302. ELT Kannad 406AF		Engineering Order 003-04 Rev 1EASA approved FMS Emergency Locator Transmitter Kannad 406AF Doc No PO0011-000406 Rev 0 or later EASA approved issuesEASA approved FMS Garmin GNS 430VHF Communications Transceiver/VOR/ILS Receiver/GPS ReceiverDoc-No. PO 0011-000430 Rev. 0 or later EASA approved issues...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	17/02/2021	Active	10014011
10014012 (EASA.A.S.01055)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		337G	Change to the complete avionics set installed by a new one last generation GARMIN and HONEYWELL	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	"Documento Técnico CMA014, Issue 1" (Aircraft Flight ManualSupplement"CMA014-AFMS, Issue 1" included) or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	Restricted to: s/n FTB3370020, FTB3370021, FTB3370022, FTB3370023, FTB3370024 & FTB3370025	15/01/2019	Active	10014012
10014013 (EASA.A.S.01056)	LUFTHANSA TECHNIK AG	REV. 3		A321-271NX/-272NX A321-271N/-272N A321-251NX/-252NX/-253NX A321-251N/-252N/-253N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318/A319/A320/A321 A318-111/-112/-121/-122	Installation of non-electrical Floor Path Marking System-Configuration 1: All GuideU series; all models except NEO-Configuration 2: GuideU series 1000, all modelsRevision 01 and 02: Editorial correctionsRevision 03: Extended applicability (A320 family NEO models)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:For Configuration 1: EASA CS 25.029(a), 25.301(a)(b)(c), 25.303,25.305(a)(b)(c), 25.307 (a)(d), 25.561(a)(b)(c...	Supplemental Type Design Definition STDD33-04/03M issue 03 rev. 00Instructions for Cont. Airworthiness ICA33-04/03M issue 01 rev. 01Airplane Flight manual Supplement A-33-04/4621-AFM issue 01 rev. 01Master Minimum Equipment List SupplementA-33-04/4621-MMEL rev. 01Flight Crew Data A-33-04/4621-FCD i...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/04/2023	Active	10014013
10014023 (EASA.A.S.01078)	AIRBUS S.A.S.	REV. 2		A319-133	Airbus Corporate Jet Centre Modification CJ2072 - AL SALAM - CONVERSIONPRIVATE TO PUBLIC AND VICE VERSA.	The Certification Basis for the original product as amendedby theadditional or alternative airworthiness requirements as listed in theGeneral CRI G-4103 “ACJC Project Certification Basis”.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the...	- Modification Approval sheet CJ2072 issue 01 - CONVERSION PRIVATE TOPUBLIC AND VICE VERSA, Issue 01, dated 30th May 2016- AFM Supplement FM-S MOD SOG-00-1030 dated MAY 01/16or later revisions of the above listed documents approved by EASA.	This STC approval is limited to A319-133 MSN 2421.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produc...	30/05/2016	Active	10014023
10014034 (EASA.A.S.01107)	RUAG AEROSPACE SERVICES GmbH	REV. 1		CESNA 550	Introduction of TCAS II Change 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/ approval	Master Document List, RUAG Aerospace document No. 0147C-MDL, Revision 0,dated 9 February 2015.Aircraft Flight Manual Supplement, RUAG Aerospace document No.0147C-AFMS, Revision 0,dated 6 February 2015.or later revisions of the above listed documents approved by EASA.	None	20/02/2015	Active	10014034

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014040 (EASA.A.S.01114)	SAFRAN SEATS	REV. 1		767-300	Introduction of Stowage 4B and infill panel to British Airways aircraft as defined in the modification definition document and Declaration of Design and Performance (DDP)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Heath Tecna Modification document C935 and associated DDP dated26/01/2005 or later approved revisions	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/03/2019	Active	10014040
10014046 (EASA.A.S.01128)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		CESSNA 208, 208B	1. Installation of the MTV-16-1-E-C-F-R (P)/CFR250-55 full feathering andreversible 4-blade constant speed propeller2. Extension of Installation 1 on MTV-16-1-E-C-F-R(P)/ CFR250-55propellers equipped with fluid deice system.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23 includingamendment 34 (not required by 21A.101, elected tocomply by the applicant).This certificate/ approval involves a change t...	Installation 1:-Instructions for Continued Airworthiness and Installation InstructionsNo E-1169-Airplane Flight Manual Supplement No E-1168Installation 2:--Instructions for Continued Airworthiness and Installation InstructionsNo E-1169, Revision 2-Airplane Flight Manual Supplement No E-1168, Revisio...	None	12/04/2011	Active	10014046
10014049 (EASA.A.S.01131)	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		BEECH B300 BEECH 300	Installation of KLN 900 GPS with EFIS-85 according to STCEASA.A.S.01131.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:FAR 23 Amdt . 23-62The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this cer...	File ref.: BCA 26 Rev 2 dated 03/10/2011AFM SUPPLEMENT FOR GPS BENDIX / KING KLN-900 Ed. 01/12 - P/N BCA26 Rev2SMV.	BEECH 300 /B300 - F-GPRH - SN FA 226.	06/02/2012	Active	10014049
10014059 (EASA.A.S.01143)	DOA AESGLOBAL LIMITED	REV. 3		757-200	Introduction of Pegasus Flight Management Computers & MultiModeReceivers (MMRs)Rev 3: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-25 Initial Issue25.581(b) - 25.601, 25.603, 25.605(a), 25.607, 25.609(a), 25.613(a)(b),25.789(a), 25.869(a)(4), 25.899...	AES Flight Manual Supplement No. 71 Issue 2or later revisions of the above listed documents approved by EASA.AES Modification No. AES-757-376 Issue 8AES Master Data List AES-757-376MDL Issue 15	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2021	Active	10014059
10014066 (EASA.A.S.01153)	MAGNETIC MRO AS	REV. 2		747-400	Modification of Cabin to Install Zone B Cabin Class Dividers, Zone BStowage & Dogbox, Door 2 Port & Starboard Dividers & Upper Deck Dogbox.Revision: Transfer of Certificate to Magnetic MRO AS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Leaflet 04ML110.	1. Compliance with the following Requirements has not been established.:1.1. Viewing of all apllicable placards & signage to in compliance withFAR/JAR 25.791.1.2. Weight, centre of Gravity & Weight Distribution, to be incompliance with JAR25.1519.1.3. Compliance with JAR/FAR25.785 (d)(3). The elimin...	19/09/2019	Active	10014066
10014074 (EASA.A.S.01166)	ALAMO ENGINEERING GmbH	REV. 3		JETSTREAM 3200 SERIES JETSTREAM 3100 SERIES	Installation of Airborne Collision Avoidance System (ACASII).Revision 1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 12:JAR 25.301, JAR 25.303, JAR 25.305, JAR 25.307, JAR 25.571, JAR 25.603,JAR 25.605, JAR 25.607, JAR 25.609, JAR 25.611, JAR 25.1301, JAR25.1309, JAR 25.132...	- Avionics Mobile Services Definition Document Part 21-002/1485-01 Issue1-Avionics Mobile Services AFM Supplement Part21-008/011 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014074

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014078 (EASA.A.S.01170)	SAFRAN SEATS	REV. 1		747-400	Reconfiguration of Cabin Interior from current 387SIA passenger cabin configuration (16F+58B+313Y for RT 514) to a 383 (12F+47B+324Y), Cathy Pacific Boing 747-400 fleet standard passenger cabin configuration.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Heath Tecna Modification document C933 and associated DDP dated 21/6/05or later approved revisions.	As defined in DDP, Aircraft Serial MSN 26548. Zero Occupancy. For thismodification to be accepted on an EU registered aircraft, requires theoperator to confirm that all the associate FAA and Hong Kong CDAmodifications have been EASA approved.Prior to installation of this design change it must be det...	14/03/2019	Active	10014078
10014090 (EASA.A.S.01187)	ROEDER PRAEZISION GMBH	REV. 1		SA227-BC, SA227-DC, SA227-TT SA226-TC, SA227-AC, SA227-AT, SA226-AT, SA226-T(B), SA226-T,	Installation of Thommen Air Data Display and Altimeter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement Doc No SA226/227-NY-0212-08, Rev. 0, or laterEASA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	25/09/2017	Active	10014090
10014097 (EASA.A.S.01195)	SAFRAN SEATS	REV 2		767-300	Introduction G3 Wardrobe to British Airways aircraft as defined in the modification definition document and Declarationof Design and Performance (DDP)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Heath Tecna Modification Document C936 and associated DDP, dated 24March 2005, or later approved revisions.	As defined in the DDP.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	14/03/2019	Active	10014097
10014122 (EASA.A.S.01232)	DOA AESGLOBAL LIMITED	REV. 2		767-300	Introduction of 258 Passenger Configuration & Associated Cabin Changes.Rev. 1: FAR Part 26 Validation for EASA STC EASA.A.S.01232.Rev. 2: Transfer from AES Ltd. to new STC holderAES Global Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AES Ltd. Master Data List No. AES-767-330MDL Issue 6 dated 14 December2012;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	27/04/2021	Active	10014122
10014123 (EASA.A.S.01233)	DOA AESGLOBAL LIMITED	REV. 1		767-300	Introduction of Matsushita in-Flight Entertainment SystemRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.		AES Master Data List AES-767-355MDL Issue 2 or later EASA approved revision	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/04/2021	Active	10014123
10014125 (EASA.A.S.01235)	SABENA TECHNICS BGC	REV. 1		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-233 A320-211/-212/-214/-231/-232 A319-131/-132/-133 A319-111/-112/-113/-114/-115	ELT Antenna InstallationInstallation of an Emergency Locator Transmitter external RAYAN antennaP/N: 2624-82, structuralelements only.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Initial Issue (refer to associated Certification Plan0243-01-A-2101-R02 section 5).The requ...	Master Data List, ref : 0243-01-A-2103-R02Instructions for Continued Airworthiness, ref : 0243-01-A-2211-R02.	Airworthiness Limitations inspection requirements apply forExtendedService Goal aircraft, as described in section 3 ofInstructions forContinued Airworthiness (Supplement), ref: 0243-01-A-2211-R02.Prior to installation of this change/ repair it must be determined thatthe interrelationship between th...	08/02/2019	Active	10014125
10014138 (EASA.A.S.01249)	ACC COLUMBIA Jet Service GmbH	REV. 2		35/ 35A	Installation of Honeywell MST-67A dual Mode S XPDR/CAS-67A TCAS II System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. ACC Master Document List ACC-LR35-50096, Revision 0, or later EASAapproved revisions.2. ACC AFMS LR35-50096-820-S-MF, Revision 0, or later EASA approvedrevisions.3. ACC AFMS LR35-50096-830-S-MF, Revision 0, or later EASA approvedrevisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/01/2022	Active	10014138

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014139 (EASA.A.S.01252)	ALAMO ENGINEERING GmbH	REV. 3		650 550 AND 650 550	Installation of an Airborne Collision Avoidance System (ACAS II).Revision 1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 17:JAR 25.301, JAR 25.303, JAR 25.305, JAR 25.307, JAR 25.571, JAR 25.603,JAR 25.605, JAR 25.607, JAR 25.609, JAR 25.611, JAR 25.1301, JAR25.1309, JAR 25.132...	Avionics Mobile Services Project Certification Plan AM/1493. AvionicsMobile Services AFM Supplement Number Part21-008/008.or later revisions of the above listed document(s) approved/acceptedunder the EASA system	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014139
10014142 (EASA.A.S.01256)	ROEDER PRAEZISION GMBH	REV. 2		A330-322	Cabin reconfiguration from a 18 B/C + 331 Y/C layout to a 18 B/C +343Y/C layout.This STC installs a new cabin arrangement.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.As per EASA TCDS A. 004Elect to Comply with CS25 (Original Issue) requirements: 25.0811(d)/ 25.812(d)(e)/ 25.813 (a)(b)(e)/ 25.851(a)/25.853(a)(c)(f)(h)/ 25.869(a)(b)(c).The requirements for environmen...	Master Document List, ref. MDL330-25-01-05 Revision 2, dated 27 Apr.2005<(>,<)>or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	15/06/2018	Active	10014142
10014143 (EASA.A.S.01261)	SAFRAN SEATS	REV. 1		747-400	Heath Tecna Modification C943 - Cathay Interiors Modification.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Heath Tecna Modification Document C943 & associated DDP, dated 1 August2005 or later approved revision.	As defined in DDP Aircraft Serial Numbers 25172 & 25128. Zero Occupancy.For this modification to be accepted on an EU registered aircraftrequires the operator to confirm that all the associated FAA & Hong KingCAD modifications have been EASA approved.Prior to installation of this design change it mu...	14/03/2019	Active	10014143
10014147 (EASA.A.S.01266)	ATELIER CHABORD	REV. 3		DR 400/2+2 DR 400/120, DR 400/120 D DR 400/120 D, DR 400/2+2 DR 400/100, DR 400/120 DR 300/108, DR 315, DR 400/100 DR 300/108, DR 315	Installation of exhaust system according to Chabord modificationSTC-DR420-2015-01Rev. 3:,,- Enhanced silent blocks- Alternative anti corrosion surface treatment- Enhanced materialon different parts- Enhanced shape of central structural part in muffler- Additional bracket on double rod tube.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 23 Amdt 3 § 607,611, 783, 807, 867, 1101, 1121, 1123, 1125, 1529.The requirements for environmental protection and th...	Technical Dossier ref. STC-DR420-2015-01 Revision D dated 04 January2022<(>,<)>Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	24/01/2022	Active	10014147
10014148 (EASA.A.S.01268)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		2. SA227-TT 2. SA226-T(B), SA227-AT 2. A226-T, SA226-AT 1. SA227-BC 1. SA226-TC, SA227-AC	Installation of Honeywell CAS 67A ACAS II System with dual Mode STransponder	Design:Non-significant changeThe Certification Basis of theoriginal product and the followingadditional /,,alternativeair worthiness requirements are applicable tothis changeFor the change CS-23 has been elected to comply with where possible.Environmental Protection:The certificated noise and/ or e...	EASA approved Engineering Order, Doc. No. 2027046-EO, issue2, dated25-Oct-2010, or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No.2027046-AM-01A, Issue 2, dated 07-Jun-2005<(>,<)> or later approvedissue, andEASA approved Aircraft Flight Manual Supplement, Doc. No.20270...	This change is limited to the configuration of aircraft / equipment typeas listed under Chapter 4. in EASA approved Engineering Order, Doc. No. 2027046-EO, Issue 2, dated 25-Oct-2010, or later approved issue.	08/11/2010	Active	10014148
10014159 (EASA.A.S.01290)	TELEDYNE UK LIMITED	REV. 2	CAA UK RESPONSIBILITY	BOEING 767-300 767-300	Installation of Teledyne Controls OQAR (Controls Optical Quick AccessRecorder) Rev. 1: Transfer of Approval Certificate to new Certificate Holder (fromTeledyne Ltd to Teledyne UK Ltd).Rev. 2: Correction of the Applicant name and address.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List STC-MDL-015-02 dated 27 September 2005<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/11/2020	Active	10014159

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014160 (EASA.A.S.01292)	ACC COLUMBIA Jet Service GmbH	REV. 1		F27MK500	Installation of an ARTEX ELT C406-1/-2.Rev. 1: Transfer of STC from Gomolzig Aircraft Services GmbH to ACCColumbia Jet Service GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	None.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/03/2022	Active	10014160
10014163 (EASA.A.S.01295)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		767-300	Installation of Teledyne Flight Data Acquisition Unit P/N 2233000-811 toprovide parameters to the FDRRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	None	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	08/11/2021	Active	10014163
10014175 (EASA.A.S.01310)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		114B	Wing auxiliary Spar RepairRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification Summary Sheet - ALT/COM/M001or later revisionsof the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014175
10014184 (EASA.IM.A.S.01322)	ALAMO ENGINEERING GmbH	REV. 3		HAWKER 800XP	Installation of an Airborne Collision Avoidance System (ACAS II).Revision 1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 17:JAR 25.301, JAR 25.303, JAR 25.305, JAR 25.307, JAR 25.571, JAR 25.603,JAR 25.605, JAR 25.607, JAR 25.609, JAR 25.611, JAR 25.1301, JAR25.1309, JAR 25.132...	- Avionics Mobile Services Project Certification Plan AM/1498 ReferencePART21-003/1498-01- Avionics Mobile Services AFMSupplement reference AFM PART21-008 Issue2or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014184
10014191 (EASA.A.S.01333)	LUFTHANSA TECHNIK AG	REV. 2		767 SERIES	Installation of non-electrical Floor Path Marking System.		STDDNo. 33-05/02M, Issue 2AFMS Doc. No.A-33-05/314-AFMAFM Supplement for Boeing 767 SeriesLHT Doc. No. A-33-05/331-AFM,dated October 31/05 or later approved revision		05/03/2014	Active	10014191
10014198 (EASA.A.S.01341)	ALAMO ENGINEERING GmbH	REV. 3		HAWKER 800XP	Installation of an Airborne Collision Avoidance System (ACAS II).Revision 1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 4: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 17:JAR 25.301, JAR 25.303, JAR 25.305, JAR 25.307, JAR 25.571, JAR 25.603,JAR 25.605, JAR 25.607, JAR 25.609, JAR 25.611, JAR 25.1301, JAR25.1309, JAR 25.132...	- Avionics Mobile Services Project Certification Plan AM/1498 ReferencePART21-003/1498-01- Avionics Mobile Services AFMSupplement reference AFM PART21-008/001Issue 2or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014198

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014208 (EASA.A.S.01360)	DOA AESGLOBAL LIMITED	REV. 1		767-300	Introduction of 279 passenger configurationRev 1: Transferfrom AES Ltd. to new STC holder AES Global Ltd.		Aerospace Engineering Solutions Modification AES-767-426 dated April 13 2005 or later approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/04/2021	Active	10014208
10014214 (EASA.A.S.01374)	ACC COLUMBIA Jet Service GmbH	REV. 2		CESSNA F182-Q CESSNA F182-P CESSNA 182Q CESSNA 182P CESSNA 182N CESSNA 182M CESSNA 182L CESSNA 182K CESSNA 182J CESSNA 182H CESSNA 182G CESSNA 182F CESSNA 182E	Installation of Noise Reduction Kit C182-606650		- Anhang zum Flughandbuch SPOH_12498_IO550_HM-Anhang zum Flughandbuch SPOH_12498_IO550_NQ-Anhang zum Flughandbuch SPOH_12498_O550_EM-Anhang zum Flughandbuch SPOH_12498_O550_NQ-Umrüstungsanweisung II_12498	1. The approval is valid only in combination with the installation of FAA STC SA009133SC (Texas Skyways Inc) or STC SA00152WI (Air Plains Services Corp.) Both with own EASA approval.2. The approval for the models Cessna 182 E, F and G is not valid for the combination with the installation of S...	03/02/2022	Active	10014214
10014215 (EASA.A.S.01376)	ALAMO ENGINEERING GmbH	REV. 3		650 550 AND 560 550	Avionics Mobile Services Modification AM/1478. Installationof anAirborne Collision Avoidance System (ACAS II).Revision1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 12:JAR 25.301, JAR 25.303, JAR 25.305, JAR 25.307, JAR 25.571, JAR 25.603,JAR 25.605, JAR 25.607, JAR 25.609, JAR 25.611, JAR 25.1301, JAR25.1309, JAR 25.132...	- Avionics Mobile Services Ltd Project Certification Plan AM/1478reference PART21-003/1478-01.- Avionics Mobile Services Ltd AFM Supplement PART21-008/008 dated April08 2005or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014215
10014218 (EASA.A.S.01379)	LUFTHANSA TECHNIK AG	REV. 1		AIRBUS A340-600	Installation of Antenna, Receiver Transmit System, and Network services.This STC installs through the cabin a set of equipment to allow dataexchange.The Revision 1 has introduced some modifications through the initial STCdesign by upgrading the existing Wireless Access Points (WAPs) tosupport the IE...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Definition Document, ref. STDD46-11/14, Issue 1;Instruction for Continued Airworthiness, ref. R-00-04/120, Revision 5;Aircraft Fligth Manual Supplement, ref. A-00-04/133-AFM, Revision 2;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2013	Active	10014218
10014219 (EASA.A.S.01380)	CEAPR	REV. 12		DR 400/RP DR 400/200 R DR 400/180 R, DR 400/200 R DR 400/180 R DR 400/140 B DR 400/120 D, DR 400/140 B DR 400/120 D	1. Installation of TAE 125 engine2. Installation of TAE 125-02-99 engine and installation of FADEC BackupBattery3. Installation of TAE 125-02-1 14 engineRevision 9 follows implementation of DET 211005 Amdt F dated 12/03/2024.Revision 10 follows implementation of DET 211005 Rev1 dated 17/07/2024.Revi...	The Type and OSD Certification Bases for the original product as amendedby the following additional oralternative airworthiness requirements:The following paragraph(s) at a later amendment: JAR 23, Amdt. 1 InitialIssue(not required by 21A. 101, elected to comply by the applicant)This certificate! app...	For TAE 125-01 engine:1. Type Design Definition TDD-60-01 Issue 4 Revision 102. Supplemental Pilot's Operating Handbookfor DR400/120D/140B/180R/ 200Requipped with TAE 125-01 or TAE 125-02-99 n °1001639 Issue 3 Revision 0dated July 20143. Supplemental Aircraft Maintenance Manual AMM-60-01 Issue 3 Revi...	Installation of TAE 125-02-114 is limited to DR 400 models with S/N 2574and upwards.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	13/10/2025	Active	10014219
10014238 (EASA.A.S.01402)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 2		1. DV20 & 2. DA20-A1	Extension of EASA STC EASA.A.S. 01402Installation of the 2-blade MTV-21-A/170-05	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-VLA, Amendment 1 (not required by 21A.101, elected to comply by theapplicant)This certificate/ approval involves a change to the requi...	- Aircraft Flight Manual Supplement, Doc. No. E-1909, rev 0, 14.09.2010- Instructions for Continued Airworthiness, Doc.No. E-1911, rev. 0,14.09.2010or later revisions of the above listed documents approved by EASA	none	04/11/2010	Active	10014238

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014248 (EASA.A.S.01470)	AEROTEC & CONCEPT	REV. 4		SEE EASA APPROVED MODEL LIST	Cabin Baby Bassinet InstallationRev. 4: Revision of EASA Approved Model List (AML) to cover followingA/C Type: A350, B787 & EMB-190.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- MASTER DATA LIST AE19081MDL Rev. 2- INSTRUCTION FOR CONTINUED AIRWORTHINESS AE19081ICA Rev. 1- INSTRUCTIONS FOR CCOM SUPPLEMENT AE19081ST Rev. 1- MASTER DRAWING LIST AE19081MDWLRev. 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Configuration: A/C with provision for Baby Bassinet Installation.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repairwill introduce no adverseeffect upon the airworthiness of th...	31/01/2022	Active	10014248
10014250 (EASA.A.S.01472)	FTI ENGINEERING NETWORK GmbH	REV. 3		B200	Installation of cloud research and seeding system.Rev 2 reflects the transfer of EASA.A.S.01472 Rev 1 from ScandinavianAvionics GmbH to Beechcraft Berlin Aviation GmbH.Rev 3 reflects the transfer from Beechcraft Berlin Aviation GmbH to FTIEngineering Network GmbH.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Airplane Flight Manual Supplement, Document 2023287-AM-01 Issue 5, datedAugust 2005;Continued Airworthiness Document 2023287-CA-01;Engineering Order Document 2023287-EO-01or laterrevisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/03/2025	Active	10014250
10014254 (EASA.A.S.01479)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		707-300	Avionics UpgradeRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. ATL Modification ATL/ 707/M127.2. Compliance Plan CP/032/9501 Issue 63. Flight Manual Supplement ATL AFM Supplement Number 34 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014254
10014256 (EASA.A.S.01483)	LUFTHANSA TECHNIK AG	REV. 2		FOKKER F.28 MARK 0100 FOKKER F.28 MARK 0070	Installation of non-electrical Floor Path Marking System		1. Supplemental Type Definition Document STDD33-05/01M, issue 01 dated03.03.20062. Airplane Flight Manuel Supplement A-33-05/328-AFM3. Applicant's Declaration of Compliance dated 17.03.2006or later revisions of the above listed documents approved by EASA		05/03/2014	Active	10014256
10014266 (EASA.A.S.01495)	TROYES AVIATION S.A.R.L.	REV. 4		F177RG	Rev 4: Provisions for three attachments in the right side of theinstrument panel in accordance with the STC EASA.A.S. 01495R1: Additionof applicability to F177RG S/N 047	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	-Supplement Flight Manual Rev.1 dated 16/11/2005or later revisions of the above listed documents approved by EASA.-Troyes Aviation REF 51.-Minor Change Troyes Aviation REF 51 Revision 2 July 2009-Minor Change Troyes Aviation REF 45 approved under EASA.A.S.01495Revision 1	FR177RG S/N 0112, 0065, 103, 153 and 087 F-BURU; S/N 051 D-EMEN; S/N 047The installation of this modification by third persons is subject towritten permission of the approval holder and holding and disposal ofthe approved appropriate documentationThe approval holder shall fulfill the obligations of2...	07/05/2018	Active	10014266
10014271 (EASA.A.S.01501)	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH	REV. 1		525, 525A	Installation of Honeywell KMH 880 or KMH-980	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR-23The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original productu...	Installation Procedure 2003-10-1, Rev. CFlight Manual Supplement 2003-10-8, Rev. DMaintenance Manual Supplement 2003-10-10, Rev. Bor later revisions of the above listed documents approved by EASA	none	27/06/2011	Active	10014271

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014281 (EASA.A.S.01518)	LUFTHANSA TECHNIK AG	REV. 3		737 SERIES 737-900/-900ER/-8/-9 737-500/-600/-700/-800 737-100/-200/-200C/-300/-400	Installation of non-electrical FPM SystemRev. 1: product name updatedRev. 2: applicability extended to the “Max” models737-8 and 737-9.Rev. 3: typos corrected	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplemental Type Definition Document STDD33-05/03M Issue 2Rev 1Airplane Flight Manual Supplement A-33-05/324-AFM Issue IR Rev 0Instructions for Continued Airworthiness ICA33-05/03M Rev 2Master Minimum Equipment List Supplement A-00-19/68-MMEL Rev 2or later revisions of the above listed document(s)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/03/2021	Active	10014281
10014282 (EASA.A.S.01519)	LUFTHANSA TECHNIK AG	REV. 1		BOEING 747-400 747-400	VVIP Cabin installationRev. 1: Replacement of conductive oxygen flex-hoses with non-conductiveones.Renumbering the certificate from EASA.A.S.01519 to 10014282.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-1.1 “Isolated Compartments” Issue 1, CRID-1.2 "Integration of large nonstructural” Issue 1.- Deviation(s): CRI D-1.3 “Firm Handhold” Issue 1...	Generic Documents:STDD 25-05/06M Issue 2 Rev. 2Cabin installation documents: STDD 25-05/19 Issue 1AFM Supplement A-00-06/181-AFM Issue 1 rev 5ICA document A-00-06/137 Issue 1 rev 0Oxygen flex hoses replacements: CPL 35-20/07M Rev 0or later revisions of the above listed document(s) approved/ acceptedun...	As per AFM Supplement A-00-06/181-AFM.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	18/11/2020	Active	10014282
10014287 (EASA.A.S.01527)	CONTINENTAL AEROSPACE TECHNOLOGIES	REV. 15	LBA EMZ SA1295	F172L, F172M, F172N, F172P F172F, F172G, F172H, F172K 172R, 172S 172L, 172M, 172N, 172P 172F, 172G, 172H, 172I, 172K	Major Change to STC EASA.A.S.01527, Revision 5:1. Installation of engine TAE 125-01 in accordance with InstallationManual IM-20-01 and Type Design Definition Doc. No. TDD-20-01;2.Installation of engine TAE 125-02-99 in accordance with InstallationManual IM-20-02 and Type Design Definition Doc. No.3...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI A-01Issue 7 (Dec 13, 2007).- Equivalent Safety Finding (s): CRI A-01Issue 7 (Dec 13, 2007).- The following paragraph (s) at a later amendment: JA...	Instructions for operation:Cessna (F) 172-N, -P with TAE 125-01 installation:- Anhang Flughandbuch für (Reims) Cessna (F) 172 N & P mit TAE 125Installation, TAE Nr: 20-0310-20011,Ausgabe 1, LBA anerkannt am31.10.2002 oder jede spätere LBA/EASA-anerkannte Ausgabe.- Supplement Pilot's Operating Handb...	This STC supersedes LBA-EMZ SA 1295.Limitations for TAE 125-01 & TAE 125-02-99:- Take off power: 99 KW at 2300 min-1 (Propellerspeed)- Max. continuous power: 99 KW at 2300 min-1 (Propellerspeed)- Fuel: Service Bulletin TM TAE 601-0005For Cessna 172S and for increased weight versions of 172R (perLuft...	21/01/2020	Active	10014287
10014292 (EASA.A.S.01534)	LUFTHANSA TECHNIK AG	REV. 1		B737-700 IGW	Revision of EASA.A.S.01534 IR per Major Change 0010002739-001:Operationat 8.99 psi maximum cabin differential pressure (Lower Cabin Altitude,LCA)Original STC Title: B737-700 IGW VIP Cabin 19 Pax.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-CRI-D01 (Doors between Passenger Compartments)-CRI D-02 (Isolated Compartments)-CRI F-01 (Executive Power System)-TGL No.17 (Passenger S...	- Supplemental Type Definition Doc STDD00-05/07M Issue 03, dtd Oct 22,2012;- AFM Supplement Doc A-00-06/100-AFM, Revision 03, dated Jul 18/06;- Instructions for Continued Airworthiness (ICA) Doc A-00-06/100-ICAIssue 01, dated June 2, 2010;or later revisions of the above listed documents approved by...	Once LCA is activated (installation of FAA STC ST01697SE asvalidatedper EASA STC 10042295) on an individual aircraft, the maintenancerequirements defined in Doc A-00-06/100-ICA will apply for the life ofthis aircraft. This limitation remains valid also in case ofdeactivation of FAA STC ST01697SE as...	03/12/2012	Active	10014292
10014298 (EASA.A.S.01542)	SAFRAN SEATS	REV. 1		767-300	Business Class Footstool Assemblies on British Airways Boeing 767-300	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Heath Tecna Modification document C973 & associated DDP<(>,<)> Issue 1<(>,<)> or later approved revision.	This STC is limited to S/N 24340, 24341, 25204, 25444, 25442, 25732,25826, 25828, 25829, 27140, 24335, 24336, 25831 and25834.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or...	14/03/2019	Active	10014298

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014302 (EASA.A.S.01546)	ACC COLUMBIA Jet Service GmbH	REV. 3		DR400/2+2, DR400NGL, DR400/100 DR400/180S DR400/180, DR400/180R DR400/160, DR400/160D DR400/140, DR400/140B DR400/120, DR400/120A DR400/120D, DR400/125 DR315, DR340, DR360, DR380 DR300/140, DR300/180R DR300/125 DR300/108, DR300/120	DR300/400 MOGAS OperationInstallation of a modification kitto allow the operation with MOGASi.a.w. EN228 to aircrafts models and variants as listed above. Theinstallation can be performed to aircrafts of the existing fleet and toaircraftsin production.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	General: Master Document List MDOCL_2030326_rev1_20130815Model DR300() and DR315 - no wing tanks; retrofitFlight ManualSupplement SPOH_8696_DR300_ rev1_20130415Installation Instruction II_2030326_DR300_RF_FT _rev0_20130415Maintenance Manual Supplement MMS_2030326_rev0_20130415Model DR340; DR360 and...	According limitation section of AFMMust be maintained iaw. Original MM and in addition iaw SupplementalMaintenance Manual MMS_2030326_rev0_20130415 or later approved revisionsPrior to installation of this modification it must be determinedthatthe interrelationship between this modification and anyi...	03/02/2022	Active	10014302
10014303 (EASA.A.S.01547)	ALAMO ENGINEERING GmbH	REV. 3		PA-31T2 (CHEYENNE IIXL)	Certification of FAA Approved field modifications for the issue of anEASA C of A.Revision 1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:EASA Certification Specification CS-23 Initial Release Sections: 23.301,307, 23.365, 23.441, 23.603-609, 23.625, 23.1301, 23.1309, 23.1321,23.1322, 23.1351(a), 23.1357, 23...	Avionics Mobile Services AFM supplement Part 21-008 014 GNS-530.Avionics Mobile Services AFM supplement Part 21-008 015KMH-880.Avionics Mobile Services AFM supplement Part 21-, 008 016 SN3308.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014303
10014305 (EASA.A.S.01549)	FOKKER SERVICES B.V.	REV. 2		737 SERIES	Number 1 Cockpit Windshields. Addition of layers of polyurethaneinterlayer to the existing qualified designs to improvein-servicereliability.Rev. 2: Transfer from GKN Aerospace to Fokker Services	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	GKN Aerospace Modification C/R 014or later revisions of theabove listed documents approved by EASA.	None.	17/07/2017	Active	10014305
10014312 (EASA.A.S.01557)	TENENCIA Ltd.	REV. 1	CAA UK RESPONSIBILITY	3. BEECH G58 2. BEECH 58/58A 1. BEECH 58PA	Hawker Beechcraft Baron Steep Approach Landing CertificationThis Certification at Revision 1 of the STC ref. EASA.A.S.01557 includesadditional aeroplane models compared to the initial issue of the STC	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Tenencia Ltd Modification TEN 426, "Hawker Beechcraft BaronSteepApproach Landing Certification", Issue 4 dated 20 May 2010.Tenencia Ltd AFM Supplement 1 Issue 2 to the Beech 58PAPilot'sOperating Handbook and FAA Approved Airplane Flight Manual P/ N102-590000-41Tenencia Ltd AFM Supplement 1 Issue 1P...	Hawker Beechcraft Model 58PA S/N TJ-256 andHawker Beechcraft Model 58 S/N TH-1967 only.	26/05/2010	Active	10014312
10014320 (EASA.A.S.01571)	MAP AIRCRAFT PART 21 AS	REV. 3		737-800	Change of the cabin layout to Swedish National Air Medevac (SNAM) SASProject number737-2520-01 and SAS Project number 737-2520-02Revision 2: Transfer of STC from Scandinavian Airlines System to SASTechnical Services AB.Revision 3: Transferof STC from SAS Technical Services AB to MAPAircraft Part 21...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SAS Project number 737-2520-01-SAS Technical Order MTO-255155E-SAS Technical Order MTO-255491A-SAS Flight Manual Supplement for Boeing 737-800 Supplement No.SAS-737-SNAM, Project No. SAS-737-2520-01-SAS drawing "737-800 Air Medevac Cabin Configuration", No. GE-737-1010SAS project number 737-2520-01-...	SAS Project Number 737-2520-01: s/n 28318, 28324, 28325, 28326, 28327,28328, 30195, 30196, 30197, 30469, 30470, 30471, 32276, 32277 and 32278.SAS Project Number 737-2520-02: s/n 28318, 28323, 28324, 28325, 28326,28327, 28328, 30194, 30195,30196, 30197, 30467, 30468, 30469, 30470,30471, 32276, 32277...	14/12/2017	Active	10014320

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014322 (EASA.A.S.01575)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		A300 B4-103, A300 B4-203	Introduction of Enhanced Mode S TransponderRev. 2: Transferof STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Aviation Traders Limited Modification 9613<(>,<)>-ATL AFM Supplement 35 Issue 3, SSR Mode S Elementary & EnhancedSurveillance (Without LHAS-STC ST01149LA Installed)<(>,<)>-ATL AFM Supplement 47 Issue 1, SSR Mode S Elementary EnhancedSurveillance (With LHAS-STC ST01149LA Installed).or later revision...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	09/11/2021	Active	10014322
10014323 (EASA.A.S.01576)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		727 SERIES	Introduction of Terrain Awareness & Warning System (TAWS)Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Aviation Traders Modification ATL/727/M165 Issue 3-Aviation Traders AFM Supplement No 37or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014323
10014325 (EASA.A.S.01578)	LUFTHANSA TECHNIK AG	REV. 3		747-400, 747-400F	Installation of non-electrical Floor Path Marking System		Supplemental Type definition Document STDD33-02/05M, issue 03 dated21/03/2006Airplane Flight Manual Supplement A-33-05/340-AFMApplicant's Declaration of Compliance dated 30/03/2006or later revisions of the above listed documents approved by EASA		05/03/2014	Active	10014325
10014330 (EASA.A.S.01583)	SAAB AB	REV. 1		LEARJET 35A 35A	Installation of Target Mission Operators ConsoleRev. 1: Transfer from Saab Nyge Aero AB to SAAB AB.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval wi...	Saab Nyge Aero Technical Directive-Modification, TDM03-03.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/12/2023	Active	10014330
10014357 (EASA.A.S.01622)	GAMA ENGINEERING Ltd.	REV. 2	CAA UK RESPONSIBILITY	200, 300	Installation of a Ground Use Battery (GUB) system Gama Aviation Mod refHL/MOD/1370.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with GAMA Aviation Modification HL/MOD/1370,as defined by Master Drawing List (MDL) ref MDL-1370 Issue 1, dated 5January 2015, and installation instructions IPI-1370 Issue 1, dated 5January 2015.Operation in accordance with GAMA Aviation Flight Manual Supplement refAFMS-13...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/02/2015	Active	10014357
10014358 (EASA.A.S.01623)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		757-200	Introduction of Enhanced Mode S TransponderRev. 1: Transferof STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Modification 9673 ATL AFM Supplement 36or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014358

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014362 (EASA.A.S.01629)	SEGELFLUG GRUPPE SIEMENS MÜNCHENE.V.	REV. 1		HK 36 TC	Optional operation with skis with directional control and breakingsystem instead of wheels in winter	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ergänzung 1 zum Wartungshandbuch, Version 2 vom 04.02.2012Ergänzung 5 zum Flughandbuch, Version 2 vom 30.11.2012or later revisions of the above listed documents approved by EASA.	Limited to S/N 36730 fitted with Skis.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	29/01/2014	Active	10014362
10014364 (EASA.A.S.01632)	CONTINENTAL AEROSPACE TECHNOLOGIES	REV. 17	LBA-EMZ SA 1377	PA-28-181 (ARCHER III) PA-28-180 (CHEROKEE) PA-28-180 (ARCHER) PA-28-161 (WARRIOR II) PA-28-161 PA-28-160 (CHEROKEE) PA-28-151 (CHEROKEE WARRIOR) PA-28-150 (CHEROKEE) PA-28-140 (CHEROKEE CRUISER)	1. Installation of engine TAE 125-01 in accordance with InstallationManual IM-40-01 and Type Design Definition Doc. No.: TDD 40-01.2. Installation of engine TAE 125-02 in accordance with InstallationManual IM-40-02 and Type Design Definition Doc. No.:TDD 40-02.3. Installation of a FADEC Backup Batte...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI A-01 Issue 7 (March 07,2008)- Equivalent Safety Finding(s): CRI A-01 Issue 7 (March 07,2008)- The following paragraph(s) at a later amendment:T...	Instructions for operation:1. For PA-28-161 with TAE 125-01installation:Anhang Flughandbuch für Piper PA-28-161 mit TAE 125 Installation;Ausgabe 1, Rev. 0 Approved March 8, 2004 or each later EASA approvedissue (see TM TAE 000-0004).Supplement Pilot's Operating Handbook for the Piper PA-28-161 Equi...	1. This STC supersedes LBA-EMZ SA 1377 and former EASA STC A.S.01632.2. Power/Rotational Speed:For TAE 125-01 and 125-02-99 installations:Take off power: 99 KW at 2300 min-1 (Propeller speed)Max. continuous power: 99 KW at 2300 min-1 (Propeller speed)For TAE 125-02-114 installations:Take off Power:M...	12/08/2019	Active	10014364
10014371 (EASA.A.S.01645)	365 AEROSPACE DDS LIMITED	REV. 3		737-600/-700/-800/-900/-900ER	Installation of an Enhanced Surveillance Mode S SystemRev 3: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDS Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 1225.869, 25.1301, 25.1307, 25.1309, 25.1321, 25.1333, 25.1351, 25.1353,25.1355, 25.1357, 25.1431, 25.1529, 25.1581, 25.1701, 25.1703, 25.1705,25.1707, 25....	Aerospace Design & Engineering ConsultantsAFM Supplement 1 FMA-0014-001 Issue AAerospace Design & Engineering ConsultantsFlight Manual Supplement FMA-1370-083 Revision 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.Aerospace Design & Engineering Consultan...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/08/2019	Active	10014371
10014372 (EASA.A.S.01646)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		747-200	Introduction of a Litton 72R INS in a Boeing 747-200 seriesaircraftRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. Compliance Plan Inertial Navigation System - Litton LTN-72R, ATLdocument CP/037/9732, Issue 1.2. AFL AFM Supplement Number 39 Inertial Navigation System, ATL documentATL/747/M032, Issue 13. Engineering Order Inertial Navigation System -Litton LTN-72R, ATLdocument ATL/747/EO032, Issue 14. Supplem...	A copy of this Certificate and the EASA Approved Flight ManualSupplement (AFMS) must be maintained as part of the permanent recordsfor the modified aircraft.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	09/11/2021	Active	10014372
10014373 (EASA.A.S.01647)	LUFTHANSA TECHNIK AG	REV. 3		DC-9, MD-88, MD-90-30 B717-200	Installation of non-electrical Floor Path Marking System		Supplemental Type Definition Document STDD33-05/05M, issue 02 dated27/03/2006Airplane Flight Manual Supplement A-33-05/326-AFMApplicant's Declaration of Compliance dated 28/03/2006or later revisions of the above listed documents approved by EASA		31/01/2017	Active	10014373

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014379 (EASA.A.S.01657)	TUI AIRLINES BELGIUM N.V.	REV. 1		757-200	MOD/757/1272, Installation of Security Cameras in accordance withThomson Airways Modification Summary MOD/ 757/1272 at issue 3.History: the EASA STC A.S.01657 (based upon CAA-UK Approval Note No.28803 issue 2) was granted to Britannia Airways Ltd on the 07 Dec. 2005.The STC Holder name then changed f...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Thomson Airways Modification Summary MOD/757/1272 at issue 3or later revisions of the above listed documents approved by EASA.	The FlightVu camera system must be selected 'OFF' for take-off andlanding.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the air...	23/12/2016	Active	10014379
10014387 (EASA.A.S.01673)	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		1900D	Installation of a TCAS II System in accordance with Business & CommuterAircraft document BCA53-00, at revision 2, datedJune 25, 2015.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement Business & Commuter Aircraft documentBCA53-AFMS, at revision 1, dated April 02, 2015;or later revisions of the above listed documents approved byEASAInstructions for Continued Airworthiness Business & Commuter Aircraftdocument BCA53-ICA, at revision 0, April 04, 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/06/2015	Active	10014387
10014389 (EASA.A.S.01675)	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBILITY	BAE.125 SERIES 800	Title: Upgrade of the dual Flight Management System (FMS).Description of change: The original dual Honeywell FMZ-900 FMS isupgraded to a dual Honeywell FMZ-2000 FMS.	CS-25The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installed in accordance with Gama Engineering Ltd modificationHL/MOD/689, reference the Master Documents List (MDL), documentreference: MDL-689-01, Issue 1. Other technical documentation:Operation in accordance with Aircraft Flight ManualSupplement, documentreference: AFMS689001, Issue 2.Maintaind...	The installer must determine whether this design change is compatiblewith previously approved modifications.	05/10/2012	Active	10014389
10014392 (EASA.A.S.01681)	TÄBY AIRMAINTENANCE AKTIEBOLAG	REV. 3		SAAB SF340A SAAB 340B	Saab 340 Class E Cargo Compartment (as defined in document S21MDL-0033). This is a major change of the EASA STC EASA.A.S.01681. It isdesigned by STC Twenty One Limited and will document changes to thelocation of rapid decompression vents for planned future bulk cargoloading operations.This STC appro...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-,,S21 FMS-0013 issue 2 Flight Manual Supplement-,,S21 MMEL-0005 issue 1 Master Minimum Equipment List Supplement-,,S21TREP-0064 issue 1 Mass and Balance Report-,,S21.TEC-0027 Supplement Manual Issue 4 - Instructions for ContinuedAirworthiness-,,Maintenance Programme-,,Maintenance Manual-,,Wiring/S...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraphs "Description" and"Associated Technical Documentation". Compatibility with otheraircraft/engine configurations shallbe determined by the installer.	17/02/2020	Active	10014392
10014398 (EASA.A.S.01692)	LUFTHANSA TECHNIK AG	REV. 2		BOEING 747-400 747-400	"Bahrain Royal Flight" VIP cabin installationRev 1: Replacement of conductive oxygen flex-hoses with non-conductiveones. Certificate renumbering from EASA.A.S.01692.Rev. 2: typo corrected	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:As per CRI A-1 Issue 1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain appli...	Generic documents:STDD 00-03/17M Issue 02 Rev 02VIP Cabin installation documents:AFM supplement A-00-05/319-AFM rev 02Instructions for continued airworthiness ICA-0-03/17 IssueOxygen hoses replacement documents:CPL-35-20/06M Rev 0or later revisions of the above listed document (s) approved/acceptedun...	As per AFM supplement A-00-05/319-AFMPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	15/01/2021	Active	10014398

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014403 (EASA.A.S.01698)	GROWING ENGINEERING PARTNERS GmbH	REV. 1		737-300	Reconfiguration of six Boeing 737-33V from 149TC to 16BC/100TC includinginstallation of G2, G7 and LAV ERev.1: Transferof STC from SR Technics Switzerland to groWINGEngineering Partners GmbH		SR Technics (Irl) documentsC737-25-1024-CCS, Rev 3C737-25-1024-MDL-01, Rev 3	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/04/2021	Active	10014403
10014405 (EASA.A.S.01700)	365 AEROSPACE DDS LIMITED	REV. 2		737-200/-300/-400/-500/-600	Installation of Dual High Frequency (HF) Communications SystemRev 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDS Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aerospace Design <(>&<)> Engineering Consultants Modification SummaryMOD-0001 Revision B dated 16th May 2007	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/08/2019	Active	10014405
10014408 (EASA.A.S.01703)	AIRBUS TRANSPORT INTERNATIONAL SNC	REV. 1		A300F4-608ST	Installation of ISIS on A300-600STInstallation of two Integrated Stand-by Instrument System (ISIS) in replacement of the stand by speed, attitude and altitude.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Change Approval Sheet, ref: ST34MOD015 Issue 1AFM Supplement ref: ST34MOD015, dated 19 October 2006Change CertificationSynthesis: ST34MOD044_CCS Issue 3, dated 07.07.2016or laterrevisions of the above listed documents approved by EASA.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	11/07/2016	Active	10014408
10014409 (EASA.A.S.01705)	RUAG AEROSPACE SERVICES GmbH	REV. 1		CESSNA 650	Upgrade of two existing Mode S transponders, Rockwell CollinsTDR-94D byRockwell Collins SB 501.Replacement of Mode S Controller CTL-92 by CTL-92E along withinstallation of new wiring for Enhances SurveillanceRevision 1 to include EASA AD 2009-0173, Rockwell Collins SBTDR-94D-34-509 to ensure correct...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Document List 163A-MDL, Rev. A from 27 October 2010Airplane Flight Manual Supplement 163A-AFMS, Rev. A from 26 October 2010or later revisions of the above listed documents approved by EASA	Aircraft Serial Numbers 650-7001 through 650-7119	29/10/2010	Active	10014409
10014411 (EASA.A.S.01708)	TUI AIRLINES BELGIUM N.V.	REV. 1		767-300	Introduction of BE Aerospace Spectrum Seat in accordance with ThomsonflyLtd Modification Summary MS/767/1462 issue 3.History: The STC certificate A.S. 01708 is re-issued because ThomsonAirways (previously known as Thomsonfly Ltd) part of the TUI Group,relinquishes and transfers the STC to another TUI...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approvalThise...	Thomsonfly Ltd Modification MOD/ 767/1462 issue 3or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/12/2016	Active	10014411
10014417 (EASA.A.S.01738)	TÄBY AIRMAINTENANCE AKTIEBOLAG	REV. 3		SAAB SF340A SAAB 340B	Introduction of Alternate Cargo Net Location LayoutRev 1: to add an additional configuration that extends bay lengths byutilising nets installed only in five of the eight positions.Rev. 2: correction of typeRev. 3: Transfer of Certificate	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA Approved:- STC Twenty One Ltd Flight Manual SupplementNo. S21.FMS-0014 Issue 6;- STC Twenty One Ltd Supplement Manual – ICA No. S21.TEC-0116 Issue 8;EASA Accepted:- STC Twenty One Ltd Master Document List No. S21. MDL-1508 Issue 2;orlater revisions of the above listed document(s) approved/ acc...	This design change is applicable only to Saab SF340A and 340B aircraftconverted to Class E under STC Twenty One Limitedmajor changeS21.25-63-1015 approved under EASA STC 10014392(formerlyEASA.A.S. 01681).Prior to installation of this change/repair it must be determined thatthe interrelationship bet...	17/02/2020	Active	10014417

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014422 (EASA.IM.A.S.01771)	RUAG AG	REV. 2		PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12 PC-12, PC-12/45 PC-12/47, PC-12/47E	Installation of Dual Garmin GNS-530 COM/NAV/GPS SystemNote:This STC is the Revision 2 of EASA STC 2004-4674, dated 03/05/2004	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Engineering Technical Order TSA PC12-34.60.02EO Revision Cor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph “Description”.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and...	01/02/2021	Active	10014422
10014423 (EASA.IM.A.S.02039)	ISRAEL AEROSPACE INDUSTRIES, LTD.IAI	REV. 5	CAA ISRAEL STC SA152	747-400	Conversion from Passenger to Special Freighter Configuration.Revision 1: Boeing 747-400SF conversion from PAX to Freighter CAAI STCSA152/EASA STC EASA.IM.A.S.02039Revision 2: Increase of Max. Taxi Weight and Max. Take-Off Weight from873.000 / 870.000 Lbs to 878.000 / 875.000 Lbs for aircraft with GE...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Israel Civil Aviation Authority STC SA152 dated October 27,2006<(>,<)>- MDL: IAI MDL-366-00-00-A3673 Revision AL<(>,<)>- AFM-S 1: IAI Doc. No. 366-00-00-A3663-481 revision 1, October 24, 2012-Supplement to Airplane FlightManual D6U10002.481 for IAI B747-400SF with GE engines<(>,<)>- AFM-S 2: IAI Do...	Refer to the limitation section of the applicable AFM Supplement asapproved for this STC depending on the serial numberof the aircraftPrior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design chang...	08/04/2019	Active	10014423
10014426 (EASA.A.S.02471)	ROEDER PRAEZISION GMBH	REV. 1		441	Installation of Dual Mode S Transponder GTX 330D	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Engineering Order C441-NY-0124- AFM-S C441-NY-0124-08, Rev. 0, approved 14. February 2006, or laterEASA approved revision- Maintenance Procedures C441-NY-0124-07, Rev. 0, or later approvedrevision.	1. Limitation according AFM-S C441-NY-0124-082. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product....	25/09/2017	Active	10014426
10014427 (EASA.A.S.02472)	RHEINLAND AIR SERVICE GmbH	REV. 3		208, 208B	Installation of a FLIR System, Inc. Ultramedia III/HD television camera.New Pilot Operating Handbook Supplement PO-0023-250000.Rev. 3: Revision to account for the transfer from airplus engineeringGmbH to Rheinland Air Service GmbH.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MD-0023-000000 of 05 Feb. 2006 and test and certification reports listed in it.DOA Declaration of compliance DC-0023-250000 of Feb. 2006.	VFR; no AP, Max speed (camera operation) 115 KIAS, 2 pilotsand max 4passengers (see POH Supplement for full Limitations text).	23/07/2025	Active	10014427
10014431 (EASA.A.S.02479)	ALAMO ENGINEERING GmbH	REV. 3		1124A	Installation of Airborne Collision Avoidance System (ACAS II).Revision 1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMOEngineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amdt. 1:CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS 25.571, CS 25.603, CS25.605,CS 25.607, CS 25.609,CS 25.611, CS 25.1301, CS 25.1309, CS 25.1321, CS25.1322, CS...	Avionics Mobile Services Modification AM/ 1486.Avionics Mobile Services AFM Supplement No. PART21-008/017 Revision -dated April 08 2005or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014431
10014439 (EASA.A.S.02489)	ROEDER PRAEZISION GMBH	REV. 2		HAWKER 800/-800XP/-850XP BAE.125 SERIES 800A/-800B BAE.125 SERIES 1000A/-1000B	Installation of wing mounted Xenon Taxi/ Landing Light and/or Radommounted Taxi Light	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Engineering Order H800-NY-0125-05- AFM-S H800-NY-0125-08,Rev 0 approved 07/04/2006- Maintenance Procedures H800-NY-0125-07, Rev 0or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2018	Active	10014439

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014440 (EASA.A.S.02490)	ROEDER PRAEZISION GMBH	REV. 1		HAWKER 800/-800XP BAE.125 SERIES 800A/-800B BAE.125 SERIES 1000A/-1000B	Installation of Iridium Satcom C1000	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Engineering Order H800-NY-0126-01- AFM-S H800-NY-0126-08,Rev. 0, approved 12. May 2006- Maintenance Procedures H800-NY-0125-07, Rev. 0or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2018	Active	10014440
10014442 (EASA.A.S.02492)	THIELERT AIRCRAFT ENGINES GmbH	REV. 1		SR22	Installation of engine Centurion 4.0 in accordance to Type DesignDefinition Doc. No.: TDD-70-01Engine: Centurion 4.0Propeller: MTV-14-D/ 195-30bCertification Basis: see CRI A-1max. Take Off Power: 228 kw at 2300 min-1 (Propeller-RPM)max. Continuous Power: 228 kw at 2300 min-1 (Propell...		- Supplement Pilot's Operating Handbook for the Cirrus SR 22 equipped with TAE Centurion 4.0 installation; Doc. No.: 70-0310-70021, issue 1 or later approved issue- Supplement Maintenance Manual Cirrus SR 22 / Centurion 4.0, Doc. No.: AMM-70-01- Operation & Maintenance Manual Centurion 4.0,...		19/08/2013	Active	10014442
10014445 (EASA.A.S.02498)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 3		P.68-TC "OBSERVER", P. 68C-TC P.68 "OBSERVER", P.68 "VICTOR" P.68 "OBSERVER 2", P. 68C P.68B "VICTOR", P.68R "VICTOR"	Installation of 3-blade constant speed propeller MTV-12-B-C-F/CF183-59bon Vulcanair S.P.A. P.68 “Victor”, P.68B “Victor”, P.68C, P.68“Observer”, P.68 “Observer 2”.Installation of 3-blade constant speed propeller MTV-12-B-C-F/ CF183-53and optional installation of Liese 75x8x100 muffler for noise reduc...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS-36, Amendment 4.FAR 36, Amendment 36-30.This certificate/ approval involves a change to the requirements forenvironmenta...	According to MT-Propeller Master Documentation List No. E-2783, Rev 3;To be operated in accordance with MT-Propeller AFM-S Document No.E-1370, Rev 2 when the MTV-12-B-C-F/ CF183-59b has been installed;According to MT-Propeller Master Documentation List No. E-2783, Rev 3;To be operated in accordance w...	According limitation section of AFM-S.Optional Liese muffler is not applicable to P.68R model with AFMsupplement AN installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or...	30/11/2017	Active	10014445
10014460 (EASA.A.S.02518)	365 AEROSPACE DDS LIMITED	REV. 4		737-300, 737-400, 737-500	Installation of an Enhanced Surveillance Mode S System / Installation ofnew Mode S Transponders, components and data link wiring which willprovide the ATC System with additional parameters necessary to complywith TGL N 18 Revision 1, datedAugust 3, 2003.Rev 4: Transfer of STC from 365 Aerospace Ltd...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aerospace Design & Engineering Consultants Flight Manual SupplementFMA-0031 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.Aerospace Design & Engineering Consultants Modification Summary MOD-0031 Issue A dated 21st February 2006Aerospace Design & Eng...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph “Description”.Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this design change it must be determined thatt...	05/08/2019	Active	10014460
10014480 (EASA.A.S.02543)	ALAMO ENGINEERING GmbH	REV. 5		HS.125 SERIES 700B HS.125 SERIES 700A/B HS.125 SERIES 700A	Installation of an Airborne Collision Avoidance System (ACASII).Revision 3: Transfer to 328 DESIGN GmbHRevision 4: Transfer to 328 SUPPORT SERVICES GmbHRevision 5: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amdt. 1:CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS 25.571, CS 25.603, CS25.605,CS 25.607, CS 25.609,CS 25.611, CS 25.1301, CS 25.1309, CS 25.1321, CS25.1322, CS...	Avionics Mobile Services Limited Modification AM/ 1517Avionics Mobile Services Limited AFM Supplements ref. PART21-008/018Issue 1 & PART21-008/001 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014480
10014481 (EASA.A.S.02544)	ALAMO ENGINEERING GmbH	REV. 3		HS.125 SERIES 700B HS.125 SERIES 700A/B HS.125 SERIES 700A	Installation of a Digital Air Data Display System.Revision 1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMO EngineeringGmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:EASA Certification Specifications CS-25 Amdt 1 Section: 25.1, 25.301,25.303, 25.305, 25.307, 25.365, 25.601, 25.603, 25.607, 25.609, 25.611,25.613, 25.1301, 25.1303, 25.13...	Avionics Mobile Services Modification AM/ 1518Avionics Mobile Services AFM Supplement PART21-008/019 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10014481

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014483 (EASA.A.S.02546)	ACC COLUMBIA Jet Service GmbH	REV. 1		PIPER PA-23-250	Modification 13452Alteration of Piper PA-23-250 aircraft toaerial work with a Leica ADS40 digital camera installation in addition to the installation of ZeissRMK 15 Top Cameras based on EASA approval No. 2004-9428Transfer to ACC Columbia Jet Service GmbH		Certification Program CP 13452 REV0 22/11/2005Compliance Record CR 13452 REV0 02/03/2006Master Drawing List MDRWL 13452REV0 28/02/2006Supplement to POH SPOH 13452 REV0 22/11/2005Installation Instruction II 13452 REV0 20060224.docStructural Report SR 13452 REV1 20060223.mcd		19/01/2022	Active	10014483
10014488 (EASA.A.S.02550)	SAAB AB	REV. 2		BEECH A100 A100-1	Installation of avionics in accordance with Saab Aerotech AB, TDM06-04Rev. 1: Transfer from SAAB Aerotech AB to SAAB AKTIEBOLAG.Rev. 2: Correction of DOA reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AFM-supplement:TDM06-04-3-AFMS1 (Garmin GNS-530)<(>,<)>TDM06-04-3AFMS2 (Garmin GNS-430)<(>,<)>ATS813, 2005-03-30, BeechA100, s/n B-217 (Sandel ST3400).	This STC is limited to Beech A100, s/n B-217.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	07/12/2023	Active	10014488
10014489 (EASA.A.S.02551)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		MODEL 36, MODEL 36A. MODEL 35, MODEL 35A,	Installation of Dual Universal UNS-1E FMS in Learjet 35/35A/36/36AMajor Change to existing STC by additional certification for P-RNAVoperations by showing compliance with JAA TGL-10.Defined in Engineering Order 2032349-EO, issue 5, dated 18 April 2013.The following UNS-1 FMS is part of this installa...	Certification Basis for the change: CS25, Amdt. 01.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original productareunchanged and remain applicable to this certificate/ approval.	Scandinavian Avionics, AFM Supplement 2032349-AM , issue 2,dated 30March 2006Scandinavian Avionics, AFM Supplement 2032349-AM B, issue 1, dated 23November 2007Scandinavian Avionics, AFM Supplement 2032349-AM C, issue 2, dated 10April 2013Scandinavian Avionics, Drawing List 2032349-DL, issue 3, date...	1. The system must utilize software version 801.X (for X 0-9) or 802.X(for X 6-9) (ref Scandinavian Avionics, AFM Supplement 2032349-AM C,limitations section, issue 2, dated 10 April 2013)2. Software Limitation of original AFMS (2032349-AMor 2032349-AM-B) ishereby extended to software version 802.X...	07/05/2013	Active	10014489
10014495 (EASA.A.S.02557)	DOA AESGLOBAL LIMITED	REV. 1		767-300	Introduction of 290 passenger place interior configurationRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.		Aerospace Engineering Solutions Modification AES-767-492	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/04/2021	Active	10014495
10014499 (EASA.A.S.02564)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		P.68B "VICTOR", P.68C/-TC	Camera Port InstallationRev. 2: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	None	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014499
10014500 (EASA.A.S.02565)	THIELERT AIRCRAFT ENGINES GmbH	REV. 3		U206H, T206H U206G, TU206F U206F, TU206G	For Cessna U206F and TU206F:Engine: Centurion 4.0 BE-221Propeller: MTV-9-D/210-58Certification Basis: See CRI A-Imax. Take Off Power 221 kW at 2300 min-1 (Propeller RPM)max. Continuous Power 221 kWat 2300 min-1 (Propeller RPM)Fuel: See Service Letter SL TAE 720-0001For Cessna U206G...		1. Supplement Pilot's Operating Handbook for the Cessna 206 equipped with TAE Centurion 4.0 installation.; Doc. No.: 72-0310-72021, issue 1 or later approved issue;2. Supplement Maintenance Manual Cessna 206 / Centurion 4.0, Doc. No.: AMM-72-01;3. Operation & Maintenance Manual Centurion 4....		19/08/2013	Active	10014500

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014505 (EASA.A.S.02575)	DASSAULT FALCON SERVICE	REV. 1		MF900 & F900EX	220 VAC ELECTRICAL DISTRIBUTION ON AIRCRAFTSTC EASA.A.S 02575 revision for applicability extension and addition ofversion 2.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval§25.869 (a) (1)&(4) at JAR 25 Change 14.The requirements for environmental protection and the associatedcertificated noise and/ or emissio...	DFS Change Approval Sheet DFS9511-CAS Issue A dated 12.10.2010DFS Modification Sheet DFS 9511, Issue A dated 07.10.2010.DFS Airplane Flight Manual Supplement (Falcon 900) N°24 Rev. 2 dated07.10.2010or later revisions of the above listed documents approved by EASA	None	13/10/2010	Active	10014505
10014507 (EASA.A.S.02580)	LUFTHANSA TECHNIK AG	REV. 3		A330 SERIES A330-841/-941 A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-243 A330-201/-202/-203	Installation of non-electrical Floor Path Marking System-Configuration 1: GuideU series 300/400/800/900/1000; all models exceptA330-841 and A330-941-Configuration 2: GuideU series1000, all modelsRevision 3: Extended applicability (A330-841 and A330-941 models)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: For Configuration 1:EASA CS 25.029 (a), 25.301(a)(b), 25.303, 25.305 (a)(b), 25.307(a)(d),25.561(a)(b)(c), 25.6...	Supplemental Type Design Definition STDD33-03/01M issue 04 rev. 00Instructions for Cont. Airworthiness ICA33-03/01M issue 01 rev. 01Airplane Flight manual Supplement A-33-05/348-AFM issue 00 rev. 00Master Minimum Equipment List Supplement A-00-23/06-MMEL rev. 00Flight Crew Data A-00-23/06-FCD issueC...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/11/2023	Active	10014507
10014508 (EASA.A.S.02582)	SAAB AB	REV. 1		LEARJET 35A 35A	Mission PowerRev. 1: Transfer from SAAB Aerotech AB to SAABAB.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	SAAB Aerotech Modification TDM06-01-1-CP.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/12/2023	Active	10014508
10014519 (EASA.A.S.02600)	SAFRAN SEATS	REV. 2		747-400	Cathay Pacific B747 Cabin Re-Configuration	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification C1030 Revision 1	1. Restricted to MSN 27132, MSN 27069 & MSN 265522. Zero occupancy3. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworth...	13/03/2019	Active	10014519
10014527 (EASA.A.S.02612)	ROEDER PRAEZISION GMBH	REV. 1		CL-600-2D24 (RJ SERIES 900) CL-600-2C10 (RJ 700,701,702) CL-600-2B19 (RJ SERIES 100)	Installation of RAAS compatible EPGWS Computer in CL-600-2B19/-2C10/-2D24 Series Aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Document Inventory List CRJ-NY-0429 Revision 1, dated 09.02.2007- Flight Manual Supplement CRJ-NY-0429-08 Revision 00or later revisions of the above listed documents approved byEASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2018	Active	10014527
10014528 (EASA.A.S.02613)	ROEDER PRAEZISION GMBH	REV. 1		AVRO 146-RJ85 AVRO 146-RJ100	Activation of RAAS function of EGPWS computer in AVRO-RJ85/AVRO-RJ100Series Aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM - RJ85-NY-0428-08 Rev 1Master Document List RJ85-NY-0428-Rev 0	1. As listed in the AFM.2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installeddesign change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	25/09/2017	Active	10014528

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014537 (EASA.A.S.02624)	ROEDER PRAEZISION GMBH	REV. 2		RJ85/100	Installation of RAAS compatible EGPWS Computer in AVRO RJ85/100 SeriesAircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFM - RJ85-NY-0427-08 Rev. 0- Master Document List RJ85-NY-0427-08 Rev. 0or later revisions of the above listed documents approved by EASA.	- As listed in the AFM.- Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	10/10/2017	Active	10014537
10014538 (EASA.A.S.02625)	ROEDER PRAEZISION GMBH	REV. 1		CL-600-2D24 (RJ SERIES 900) CL-600-2C10 (RJ 700,701,702) CL-600-2B19 (RJ SERIES 100)	Activation of RAAS function of EGPWS Computer in CL-600-2B19/-2C10/-2D24 Series Aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Document Inventory List CRJ-NY-0432 Revision 1, dated 09.02.2007- Flight Manual Supplement CRJ-NY-0432-08 Revision 00or later revisions of the above listed documents approved byEASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2018	Active	10014538
10014542 (EASA.A.S.02629)	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBILITY	A340-311, A340-312, A340-313.	Child Restraint System - CRS - Installation in A340-300	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CRI F-01, "Child Restraint System".The requirements for environmental protection and the associatedcertificated noise and/ or emissionsu...	- Certification Plan, ref. doc. No. TN1785-004, Rev. H, dated 15thDecember 2006- Certification Compliance Check List, ref. doc. No. TN1785-005, Rev. E,dated 8th June 2007- Declaration of Design and Performance, ref. doc. No. DDP-1785-026,Rev. H, dated 22nd August 2007or later revisions of the above...	Limitations in accordance with § 4 - Limitations of the above mentionedDDP, ref. No. DDP-1785-026.All cabin interiors must be evaluated for compatibility of the ChildRestraint System (CRS). The CRS is not approved for aeroplanes that arenot defined by § 4 of the above referenced DDP.	10/12/2012	Active	10014542
10014543 (EASA.A.S.02630)	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBILITY	A340-643	Child Restraint System - CRS - Installation in A340-600	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CRI F-01, "Child Restraint System".The requirements for environmental protection and the associatedcertificated noise and/ or emissionsu...	- Certification Plan, ref. doc. No. TN1785-004, Rev. H, dated 15thDecember 2006- Certification Compliance Check List, ref. doc. No. TN1785-005, Rev. E,dated 8th June 2007- Declaration of Design and Performance, ref. doc. No. DDP-1785-026,Rev. H, dated 22nd August 2007or later revisions of the above...	Limitations in accordance with § 4 - Limitations of the above mentionedDDP, ref. No. DDP-1785-026.All cabin interiors must be evaluated for compatibility of the ChildRestraint System (CRS). The CRS is not approved for aeroplanes that arenot defined by § 4 of the above referenced DDP.	10/12/2012	Active	10014543
10014544 (EASA.A.S.02631)	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBILITY	B747-400	Installation of MAGE Child Restraint System as detailed in ModificationLeaflet for Modification no. B744-1795.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	As defined in Mann Aviation Group (Engineering) Ltd. (MAGE) ModificationLeaflet for Modification No. B744-1795or later revisions of the above listed documents approved by EASA	1. This STC only covers the installation of the MAGE Child RestraintSystem on Virgin Atlantic Airways Boeing 747-400 Aircraft, as defined inMAGE DDP1785-026 and in accordance withthe instructions and limitationsdefined in MAGE Crew ManualSupplement TN 1785-023.2. This STC is approved only for thet...	20/06/2012	Active	10014544
10014557 (EASA.A.S.02655)	DOA AESGLOBAL LIMITED	REV. 1		767-300	Introduction of Main/APU Battery Paralleling for Extended Standby PowerTime Capability.Rev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.		Aerospace Engineering Solutions Modification AES-767-469	none	28/04/2021	Active	10014557

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014558 (EASA.A.S.02657)	SCAI TECH (SOUDURE CHAUDRONNERIE ALU INOX)	REV. 5		DR 400/180 S, DR 400/ NGL DR 400/180, DR 400/180 R DR 400/160, DR 400/160 D DR 400/140, DR 400/140 B DR 400/120, DR 400/120 A DR 400/120 D, DR 400/125 DR 360, DR 380, DR 400/100 DR 300/180 R, DR 315, DR 340 DR 300/125, DR 300/140 DR 300/108, DR 300/120 DR 250 B, DR 250 B-160 DR 250-160, DR 253, DR 253 B DR 221, DR 221 B, DR 250	SCAI-DR315_DR300-108, 120, 125, 140_DR340_DR360-FM-A,SCAI-DR380_DR300-180R-FM-A, SCAI-DR412-FM-B, SCAI-DR416-414-FM-B,SCAI-DR418-FM-B, SCAI-DR221_DR221B-FM-A.Rev. 5: Extension to DR250/ DR250B/ DR250B-160/ DR250-160/ DR253/DR253Bmodels.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Supplément au manuel de maintenance SCAI-DR315_DR300-108, 120, 125<(>,<) >140_DR340_DR360-MIM-ASupplément au manuel de maintenance SCAI-DR380_DR300-180R-MIM-ASupplément au manuel de maintenance SCAI-DR412-MIM-BSupplément au manuel de maintenance SCAI-DR416-DR414-MIM-BSupplément au manuel de maintenan...	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the a...	29/10/2020	Active	10014558
10014563 (EASA.A.S.02663)	LUFTHANSA TECHNIK AG	REV. 2		A300 SERIES, A310 SERIES	Installation of non-electrical Floor Path Marking System		1. Supplemental Type Definition Document STDD33-06/02M, issue 01 dated16.05.20062. Airplane Flight Manual Supplement A-33-06/264-AFM3. Applicant's Declaration of Compliance dated 20.06.2006or later revisions of the above listed documents approved by EASA		05/03/2014	Active	10014563
10014568 (EASA.A.S.02672)	GROWING ENGINEERING PARTNERS GmbH	REV. 2		A319-112	In-Flight telecommunication equipment - antenna installation(partial removal of GTE Airfone System installed by FAA STCST00129NY-Dand SA1693GL)The Revision 1 was issued to reflect the transfer from SR TechnicsIreland to SR Technics Switzerland LTDRev. 2: Transfer of STC from SR Technics Switzerlan...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	GTE Airfone STC Documentation Checklist: AFD70-0016-00, Rev.3SR Technics Doc.: C320-23-1005-CCS-01 Rev.00or later revisions of the above listed documents approved by EASA	none	20/04/2021	Active	10014568
10014590 (EASA.A.S.02699)	ACC COLUMBIA Jet Service GmbH	REV. 1		HK 36 TTC-ECO HK 36 (RESTRICTED)	Modification of the Dimona HK 36 R "Super Dimona" equipped with theengine Rotax 912 A3 with the alternative Propeller MTV-21-A-CF/C175-05.Rev. 1 Transfer to ACC Columbia Jet Service GmbH		Service Bulletin: GFM SB 2008-2Anhang zum Flughandbuch für den Motorsegler HK 36 R SPOH_14326_rev0_23082007 Ausgabe 08.2007.Wartungshandbuch für den Motorsegler HK 36 R. 30204-r13-HK36-WHB, Ausgabe 25. Juni 1990Umrüstunganweisung, Modification 14326	All S/N of the variant: HK 36 R "Super Dimona"Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	19/01/2022	Active	10014590
10014593 (EASA.A.S.02705)	LUFTHANSA TECHNIK AG	REV. 1		BOEING 737-700 IGW BOEING 737-700 737-700	Upgrade of existing VIP cabin configuration from private operations tocommercial operations.Rev. 1: Replacement of conductive oxygen flex-hoses with non-conductiveones.Renumberingcertificate from EASA.A.S.02705 to 10014593.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- As defined in CRI A-100 Issue 2 dated June 11th 2001The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the produ...	Generic documents:STDD00_00_02M Issue 07 rev 03For the change to commercial operations:CP_25_06_17M Issue 03CRL 25_06_17M Issue 01STDD 25_06_17M Issue 01 rev 00A_00_01_311 AFM supplement Cabin TT<(>&<)>L Issue 03A_25_06_17M AFM supplement Cabin TT<(>&<)>L Issue IRA_00_01_311_AMM supplement Rev 12For...	- Limitations as per AFM supplements A_00_01_311 and A_25_06_17M-The Luftfahrt BundesAmt STC LBA. 21E2.TA0307 is a prerequisite for thisinstallation.Prior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed...	17/11/2020	Active	10014593

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014594 (EASA.A.S.02706)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		BAE 146 SERIES	Honeywell TCAS IIRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ATL Modification ATL/146/ M058ATL AFM Supplement Number 43 Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014594
10014595 (EASA.A.S.02712)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		DC 8-60	Installation of Honeywell MKVII EGPWS.Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Airplane Flight Manual Supplement No. 44 Issue 1, dated 7thSeptember2006.ATL Definition Document No. DD/038/10031 dated 7th September 2006.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	1. Compatibility of this design change with other previously approvedmodifications must be determined by the installer.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraphs "Description" and"Associated Technical Documentation"....	09/11/2021	Active	10014595
10014598 (EASA.A.S.02718)	AVIATION ENGINEERING AS	REV. 2		B200CGT, B200CT, B200T A200C, A200CT, B200, B200C 200, 200C, 200CT, 200T, A200	Installation of Navaids Flight inspection system UNIFIS 3000Installation in Aircraft includes:Two static inverters for power supply;A vertical gyro VG400;Electrical installation with Relays and fuse panel;An advisory light and shut-off switch in the cockpit front panel;Interface panel for connection...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23amendment 23-0 unless otherwise noted:CS23.301(a), 23.303, 23.305(a)(b), 23.307(a), 23.333 (a), 23.603,23.605(a), 23.607, 23.609(a), 23.613, 23.619, 25.625 (a), 23.785(...	- Air Alpha design package EO-B200-25-105- Flight Manual supplement: FMS.EO.B200-25-105- Unifis 3000 Installation and Maintenance Manual version 1 Aug 2006- Unifis 3000 Operator Manual version 1, Aug 2006- Supplemental Installation & Maintenance Manual for King Air 2000: AirAlpha N. ATP25.0102or lat...	1. Installed unit, UNIFIS 3000 must comply with requirements in JAA TGLN.17.2. Antenna installations and pilot aids as a CDI with annunciator andintercom must be approved separately.3. This STC is approved only for the product configuration as defined inthe approved design data referred to in the pa...	13/03/2019	Active	10014598
10014604 (EASA.A.S.02727)	ROEDER PRAEZISION GMBH	REV. 2		DC-3C-R1830-90C	Installation of emergency exit signs and floor escape path markings at DC3C series aircraftInstallation of emergency exit signs light with power source and installation of fluorescent floor path markings	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List DC3-NY-0532 Rev. 0 dated 20 Nov 2006or later revisions of the above listed documents approved byEASA.- Engineering Order DC3-NY-0532-05 Rev.0- Mechanical Installation DC3-NY-0532-03 Rev. 0- Electrical Drawings DC3-NY-0531-02 Rev. 0- Weight & Balance DC3-NY-0532-09 Rev. 0	The system must be maintained in accordance with Maintenance ProceduresDC3-NY-0532-07 Rev. 0 dated 20 Nov 2006 or laterapproved revision.The system must be operated in accordancewith AFM supplementDC3-NY-0532-08 Rev. 0 dated 20 Nov 2006 or later approved revision.Prior to installation of this desi...	08/10/2018	Active	10014604
10014607 (EASA.A.S.02732)	FOKKER TECHNIEK B.V.	REV. 3		CL-600-2C10 (RJ 700,701,702)	VIP conversion of Bombardier CL600-2C10 (CRJ-700) for ConsolidatedContractors Company, as detailed in Fokker Services Engineering ReportFS-N594. Description of the modification.Revision 2: Wireless handsets in the Aircell telephone installation in aCRJ-700 for consolidated Contractors Company (provi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement n07-FS1-1: Airplane Flight Manual SupplementBombardierCL600-2C10 Aircraft.CRR-0018, issue 1, certification of provision for wireless telephonecommunication system dated 20/01/2010.	If the utilization of the VIP converted aircraft deviates from theassumed utilization (e.g. flight hours or flight profile) supporting thescheduled maintenance requirements as defined by Bombardier, theoperator of the aircraft will have toreview the adequacy of thesemaintenance tasks with the aircr...	05/12/2019	Active	10014607
10014608 (EASA.A.S.02734)	AERODISA S.L.	REV. 1		EMB-120RT EMB-120ER EMB-120, EMB-120ER, EMB-120RT EMB-120	AED2006-03M: TAWS Installation on EMBRAER 120.Rev. 1: Part 26 compliance concerning STC EASA.A.S. 02734	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: 26.330,26.331 (a)(b)(c)(d), 26.332(a)(b), 26.333The requirements for environmental protection and the associat...	Master Data List AED2024-27M-MDL Rev. A0 dtd. 12/02/25Supplement to MPG for EMB-120 AED2024-27M-MPGS Rev. A0 dtd. 23/07/2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Per Supplement to MPG for EMB-120 (MPGS): AED2024-27M-MPGS	05/08/2025	Active	10014608

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014612 (EASA.A.S.02739)	ROEDER PRAEZISION GMBH	REV. 1		200, 300, 1900	Installation of HID Nose Gear Lights.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation to be in accordance with Nayak Engineering Order refBE200/300-NY-0733-05, Rev 0 dated 12 September 2006,or later approvedrevision.- Instructions for Continued Airworthiness as defined in NayakMaintenance Procedures ref BE200/300-NY-0733-07, Rev 0 dated 12September 2006, or later appr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	30/10/2017	Active	10014612
10014613 (EASA.A.S.02740)	JET AVIATION AG	REV. 2		S/N 32774, P4-KAZ 737-700IGW (737-7EJ),	Cabin Modification - Galley installation in the LH FWD Entrance Area -High Cabinet installation in the FWD RH Cabin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFMS BPKAZ003-201-08or later revisions of the above listed documents approved by EASA.	1. Approval valid only for s/n 32774 with FAA-STC No. ST09981SCinstalled.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".3. Prior to installation of this design change it must be determinedthat the interrelat...	29/07/2016	Active	10014613
10014618 (EASA.A.S.02750)	AVIATION ENGINEERING AS	REV. 2		B200	Antennas - Relocation and Installation in accordance with EO-B200-25-106 and DWG. No. EN-B200-25-106-01 to support UNIFIS 3000 Flight Inspection System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 23amendment 23-0: CS23.301(a), 23.303, 23.305,23.307, 23.335(b), 23.337,23.365, 23.571(c), 23.603, 23.605, 23.609, 23.611, 23.613, 23.627, 23.1525, 23.1529, 23 App GT...	· Flight Manual supplement FMS.EO-B200-25-106, Rev.0, 07 June 06;· Supplemental Maintenance Manual SMM ATP25.0104, Rev.0, 07 June 06or later revisions of the above listed documents approved by EASA.	MSN BB1221 only.This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft configurations shall be determined bythe installer.The installation of this modification by third persons is subj...	13/03/2019	Active	10014618
10014620 (EASA.A.S.02752)	LUFTHANSA TECHNIK AG	REV. 5		B737-700 IGW	Revision of EASA.A.S.02752 Rev.4 per Major Change 0010002741-001:Operation at 8.99 psi maximum cabin differential pressure (Lower CabinAltitude, LCA)Original STC Title: Design andImplementation of VIP interior andmiscellaneous aircraft systems.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI A-01, dated 6th March 2008 plus CRI D-01 (ESF for Width of Aisle).The certificated noise and/ or emissions levels of the original pro...	- Supplemental Type Definition Doc STDD00-06/10M Issue 03, dated Oct 22,2012;- AFM Supplement Doc A-00-07/784-AFM, Revision 10, dated Oct 21/11;- Instructions for Continued Airworthiness (ICA) Doc A-00-07/784-ICAIssue 02< (>,<)> dated April26, 2010;or later revisions of the above listed documents app...	Once LCA is activated (installation of FAA STC ST01697SE asvalidatedper EASA STC 10042295) on an individual aircraft, the maintenancerequirements defined in Doc A-00-07/784-ICA will apply for the life ofthis aircraft. This limitation remains valid also in case ofdeactivation of FAA STC ST01697SE as...	03/12/2012	Active	10014620
10014633 (EASA.A.S.02775)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		BAE 146 SERIES	Installation of dual AlliedSignal GNS-XLS Flight ManagementSystemRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Modification ATL/146/ M063Aviation Traders AFM Supplement Number 49or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Restricted to VH-JJY ASN E2113.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014633
10014635 (EASA.A.S.02779)	ACC COLUMBIA Jet Service GmbH	REV. 1		CESSNA 172S	Installation of Noise Reduction Kit C172S-606560Rev. 1 Transfer to ACC Columbia Jet Service GmbH		- Anhang zum Flughandbuch Larmminderungskit C172S-606560-Umrüstanweisung 14768	None	19/01/2022	Active	10014635

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014652 (EASA.A.S.02807)	JET AVIATION AG, BASEL	REV. 1		MF900	Wireless Access Service Point (WASP) Wireless LAN (WLAN) Activation STC EASA.A.S.02807, Revision toincorporate the S/N:-002 & 004	The Certification Basis for the original product remains applicable tothis certificate/ approval.Derogation to latest amendment (Part 21A.101): Do not materiallycontribute to safety.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this ce...	- Master Data List, Doc. No. BCD01023-001, Rev. B, dated 04.04.2014- AFMS (S/N 109), Doc. No. B3202403-201-13, Rev. IR,Date of Approval- ICA (S/N 109), Doc. No. BCD01023-150-13, Rev. A, dated 05.09.2006- AFMS (S/N 002 & 004), Doc. No. JBSL-M-00122AFM-01, REV. 1, Date ofApproval- ICA (S/N 002 & 004)...	S/N: 002 / 004 / 109Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designchange and/ or repair will introduce noadverse effect upon the airworthiness of the product.	29/04/2014	Active	10014652
10014659 (EASA.A.S.02816)	JET AVIATION AG	REV. 2		737-700/-800/-900/-900ER	Wireless LAN (WLAN) ActivationExpanding demonstration of the existing immunity to IEEE 802.11 a/b/g/ nfrom the B737-700 to the B737-800/900/900ER and expand the immunity toIEEE 802.11 ac.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Data List, Doc. No. BB73723261-001, Rev. D, dated 08. May 2014- AFMS, Doc. NO. JBSL-M-00141AFM-01, Rev. 1or later revisions of the above listed documents approved by EASA	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	10/05/2016	Active	10014659
10014660 (EASA.A.S.02817)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		737-300, 737-400, 737-500	Mode 'S' Transponder System for Elementary and Enhanced SurveillanceRev. 1: 737-400 added to STCRev. 2: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Modification Summary ATL/737/M556 Issue 8, dated 1st May 2009.- ATL AFM Supplement Number 48 Issue 1, “SSR Mode “S”Elementary and Enhanced Surveillance”, for B-737-300 series.EASA Form 96 Post-TC Technical Visa Page 3/7Issue 2, 25.02.2008- ATL AFM Supplement 11350-AFM-00001 Issue 1, “SSR Mode “S”E...	In accordance with Paragraphs 3, 9, 10, 13 & 16 of the ModificationSummary ATL/737/ M556 Issue 1, dated 9th October 2006Compatibility of this design change with other previously approvedmodifications must be determined by the installer.Prior to installation of this change/ repair it must be determined...	09/11/2021	Active	10014660
10014665 (EASA.A.S.02822)	H4 AEROSPACE (UK) Ltd.	REV. 3	CAA UK RESPONSIBILITY	757-200	Cabin Reconfiguration on Boeing 757-200 aircraftRevision 3:correction of model	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	BBJ Design Services Ltd Modification BBJ807.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/10/2020	Active	10014665
10014670 (EASA.A.S.02829)	ACC COLUMBIA Jet Service GmbH	REV. 5		172RG	Modification 14839Installation of Low Noise Silencer Kit "System Gomolzig" C172RG_606520Additional Propeller MTV	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Low Noise Silencer Kit C172RG_606520Master Document List MDOCL_14839_rev2_20130601Flight Manual Supplement SPOH_14839_rev2_20130601 (German version) orSPOHen_14839_ rev2_20130601 (English version)Installation Instruction II_14839_ rev2_20130601or later revisions of the above listed documents appro...	According limitation section of AFM.Must be maintained iaw.Original Cessna MM and in addition iawSupplemental Maintenance Manual SMM_14839_ rev1_20130601or laterapproved revisions.Prior to installation of this modification it must be determined thatthe interrelationship between this modification an...	03/02/2022	Active	10014670
10014676 (EASA.A.S.02837)	ROEDER PRAEZISION GMBH	REV. 1		737-300	Installation of Galley G2 Varig p/n 25-30-3154 inside aircraft between STA 333.25 and STA 350.50	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Documentation according to "Uebersicht der Dokumente" Rev. 3 dated30.01.07- Compliance Check List B737-NY-0936-01A, Rev. 2 dated 30.01.07- Declaration of Completion B737-NY-0936, dated 30.01.07or later revisions of the above listed documents approved by EASA.	This STC is limited to Boeing 737-300 MSN 23827Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	13/02/2018	Active	10014676

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014677 (EASA.A.S.02838)	FOKKER SERVICES B.V.	REV. 1		747-8F/-SP/-SR 747-8/-100/-300/-400/-100 B 747-200F/-400 BCF/-400D/-400F 747-100B SUD/-200B/-200C	Introduction of cockpit windows with improved design for Boeing 747series aircraft. GKN p/n 06314 and 06315 as replacement for Boeing p/n65B27042() and 65B27046() and GKN p/n 06316 and 06317 as replacement forBoeing p/n 065B27043() and 65B27047().Revision 1: Transfer from GKN to Fokker Services	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	747 No. 2 and 3 supplement IPC747 No. 2 and 3 window ACMMorlater revisions of the above listed documents approved by EASA.	None	17/07/2017	Active	10014677
10014686 (EASA.A.S.02849)	AIRBUS S.A.S.	REV. 2		A319-115, A-319-133	Airbus Corporate Jet Centre – Modification CJ2053– A319 SATTV TAILWIND550 ANTENNAApplicability update (A319-115) for installation of antenna structuralprovisions and radome for the installation of the Airshow live TV systemTAILWIND 550 previously approved on A319-133	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Approval Sheet, ref. CJ2053, Issue 2, dated 25th April2016- MPD Supp SAT TV Ref : MPD-S MOD CJ2053 dated25/11/2015- Technical Repercussion Sheet No. 53-1296, IssueA, dated 2nd October2006or later revisions of the above listed documents approved by EASA.	None	26/04/2016	Active	10014686
10014691 (EASA.A.S.02855)	JET AVIATION AG, BASEL	REV. 1		A319	Cabin interior outfitting		Master Data List BCJ02921-001-REV.B, dated 25.08.2009Airplane Flight Manual Supplement BCJ02921-201-01-REV.IRInstructions for Continued Airworthiness BCJ02921-150-0-REV.IRor laterrevisions of the above listed documents approved by EASA	Limited to Reg. P4-VNL, S/N 2921	02/11/2010	Active	10014691
10014694 (EASA.A.S.02860)	GROWING ENGINEERING PARTNERS GmbH	REV. 1		747-400	Reconfiguration of five Boeing B747-400 aircraft to 54J/62W/228Y.Rev.1: Transfer of STC from SR Technics Switzerland togroWINGEngineering Partners GmbH		C747-25-1002-CCS, Revision 0, or later approved revision.C747-25-1002-MDL, Revision 0, or later approved revision	The following EASA approved STC's must be installed concurrently withthis design change:EASA.A.S. 03165EASA.IM.A.S.02572	20/04/2021	Active	10014694
10014696 (EASA.A.S.02863)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		2. SA227-BC 2. SA226-TC, SA227-AC 1. SA227-TT 1. SA226-T(B), SA227-AT 1. A226-T, SA226-AT	Installation of Sandel ST3400 TAWS System	Design:Non-significant changeThe Certification Basis of theoriginal product and the followingadditional /,,alternativeair worthiness requirements are applicable tothis changeFor the change CS-23 has been elected to comply with where possible.Environmental Protection:The certificated noise and/ or e...	EASA approved Engineering Order, Doc. No. 2035640-EO, issue4, dated25-Oct-2010, or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2035640-AM-A,Issue 4, dated 15-Jul-2010<(>,<)> or later approved issue, orEASA approved Aircraft Flight Manual Supplement, Doc. No. 203564...	This change is limited to the configuration of aircraft / equipment typeas listed under Chapter 4. in EASA approved Engineering Order, Doc. No. 2035640-EO, issue 4, dated 25-Oct-2010, or later approved issue.	08/11/2010	Active	10014696
10014699 (EASA.A.S.02866)	SABENA TECHNICS BGC	REV. 3		A330 ALL MODELS	Installation of Aeromobile GSM Connectivity System onboard Airbus A330AircraftRevision of the EASA STC 10014699 Rev. 2 to remove EWIS limitation	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS"The requirements for envir...	- Master Data List, ref. doc. No. 0313-01-A-2103-R16, Rev. R16, dated16th September 2010- Certification Plan, ref. doc.No. 0313-01-A-2101-F01-R01, Rev. R01,dated 1st February 2010- Compliance Records, ref.doc. No. 0313-01-A-2104-F01-R02, Rev. 02,dated 16th February 2010- Aircraft Flight Manual Supp...	Not applicable	17/09/2010	Active	10014699

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014707 (EASA.A.S.02879)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		747-400 SERIES	Installation of a Bendix / King CAS-81 TCAS II System and Dual Bendix /King TRA-67 Mode S TransponderThe provisions forthe antenna installation in accordance with Boeing SB747-34-2309 are not part of this STC.Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ATL Master Document List ATL/MDL-046 at issue 1Master Drawing List Drawing No. 699-50021, initial releaseMaster DrawingList, Drawing 699-50020, initial releaseATL Airplane FlightManual Supplement Nr. 54 Issue 1 to Boeing AFMD6-U10003.or later revisions of the above listed document(s) approved/ acce...	Prior to installation of the STC Boeing SB 747-34-2309 mustbeinstalled.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ orrepair will introduce no adverseeffect upon the airworthines...	09/11/2021	Active	10014707
10014708 (EASA.A.S.02880)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		747-400 SERIES	RTA-44D VHF Data Radio System.Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List Ref ATL/ 747/MDL047or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph 4: SpecificationAircraft/ Modification. Compatibility with other aircraft/ engineconfigurations shall be determined bythe installer.Prior to installation of this change/ repair it...	09/11/2021	Active	10014708
10014709 (EASA.A.S.02881)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		747-400 SERIES 747-400	Certification of Collins Data Link ACARS Installation in the B747-400Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List Ref ATL/ 747/MDL048or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014709
10014713 (EASA.A.S.02886)	LUFTHANSA TECHNIK AG	REV. 2		757-200, 757-300	Installation of non-electrical Floor Path Marking System		Supplemental Type Definition Document STDD33-06/03M Issue 01 24/11/2006or later revisions of the above listed documentsapproved by EASA	Lufthansa Technik AG AFM Supplement A-33-06/472-AFM	05/03/2014	Active	10014713
10014727 (EASA.A.S.02905)	LUFTHANSA TECHNIK AG	REV. 2		ATR 72-212/-212A ATR 72-101/-102/-201/-202/-211 ATR 42-200/-300/-320/-400/-500	Installation of non-electrical Floor Path Marking System		-Supplemental Type Definition Document STDD33-06/04M, Issue01-Certification Program CP33-06/04M, Issue 01-Compliance Record List CRL33-06/04M, Issue 01-Airplane Flight Manual Supplement AFMS A-33-06/497-AFM Initial Revision-Instructions for Continued Airworthiness ICA33-06/04M Initial Revision-Engi...	ATR42/72 except those aircraft with convertible seats whichdo not have a fixed lateral position.See Airplane Flight Manual Supplement AFMS A-33-06/497-AFM Initial Revision or later approved revisions.Instructions for Continued Airworthiness ICA33-06/04M Initial Revision or later approved revisionsS...	05/03/2014	Active	10014727
10014734 (EASA.A.S.02917)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		757-200	238 PAX LOPA InstallationRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Ltd. ATL Modification ATL/757/152 at Issue1 dated 16March 2007Aviation Traders Ltd. Master Document List ATL/ 757/MDL054 at Issue 1dated 20 March 2007or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014734

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014737 (EASA.A.S.02920)	AIRLEC AIR ESPACE	REV. 1		550	Single Pilot Operations and Associated modificationsThis STC is a transfer from Aci Systémes in Villefrancoeur France toAirlec Air Espace in Langon France.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aci Systémes AFM Supplement ACI-00-AFM-M-021-Rev.1Aci Systémes Compliance Checklist ACI-00-CCL-M-021-Rev.3, dated05/06/2007or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	12/11/2013	Active	10014737
10014752 (EASA.A.S.02937)	FOKKER TECHNIEK B.V.	REV. 4		A319-115	Changes to Airbus A319CJ in addition to the VIP Conversion introduced byEASA STC A.S.02937 as described in Fokker Services B.V. EngineeringReport A319-SAG-CRR-0002 Issue 1.This STC has been revised to clarify the text in the Limitations andConditions.Revision 3: MMEL Supplement addedRevision 4: Tran...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The following paragraph (s) at later amendment: CS-MMELThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and rem...	AFM Supplement A319CJ 0.01.00 for STC P-EASA.A.S. 02937.MMELSupplement A319-FOK-MMEL-S-001 Revision 2, Chapter 6, dated25.08.2017or later revisions of the above listed documents approved by EASA.	The activation of the Zonal Dryer/Humidification System is not part ofthis Major Change. The installation of the Zonal Dryer/HumidificationSystem is certified, however the correctuse and functioning is notcertified. Therefore the Zonal Dryer/Humidification System may not beactivated.Prior to instal...	05/12/2019	Active	10014752
10014753 (EASA.A.S.02939)	ROEDER PRAEZISION GMBH	REV. 1		DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Installation of flight ID capable XPDR and CTRL		Ubersicht der Dokumente No. MD80-NY-1137 dated 14.02.2007AFMS No. MD80-NY-1137-08 dated 14.02.2007or later revisions ofthe above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/11/2017	Active	10014753
10014757 (EASA.A.S.02945)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		757-200 757	201PAX LOPA InstallationRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List Ref MDL/ 757/053, issue 1or later revisionsof the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014757
10014764 (EASA.A.S.02954)	ACC COLUMBIA Jet Service GmbH	REV. 2		35/ 35A/ 36/ 36A	Installation of Honeywell EGPWS Mk. VIII (in combination with anexisting Weather Redar display).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Document List LR35-60514-000-LP, Rev. 1.2. AFM Supplement LR35-60514-800-MF, Rev. 1.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/01/2022	Active	10014764
10014779 (EASA.A.S.02977)	AIRBUS S.A.S.	REV. 1	LBA STC TA0015 ISSUE 4	A300 B4-605R/-622R A300 B4-601/-603/-620/-622	- EASA STC EASA.A.S.02977 revision 1-(Ref. to former Luftfahrt Bundesamt STC TA0015 Issue 4)- The STC EASA.A.S. 02977 has covered the transfer of the STC TA0015Issue 4 (original Aviation Authority reference) from the originalAviation Authority (LBA) to the EASA allowing the conversion of A300B2 /B4c...	- The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- See Certification Summary Document referenced in Associated TechnicalDocumentation section- The certificated noise and/or emissions lev...	- Certification Summary Document EQM 236/000-001/COS Issue 06.- Airbus Deutschland Engineering Order Nr. PFM 04296A Issue 04.- Aircraft Flight Manual Supplement for Airbus A300B2 / B4< (>,<)>Revision 07, dated 15 July 2006.- Supplemental Airworthiness Limitation Items for A/C A300B2 / B4 Ref:SEMD-033...	N/A	26/02/2010	Active	10014779

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014782 (EASA.A.S.02980)	FOKKER SERVICES B.V.	REV. 1		737-600/-700/-800/-900 737-100/-200/-300/-400/-500	Number 2 Cockpit Windshields Addition of Layers of PolyrethaneInterlayer to the Existing Qualified Design to improve In-Servicereliability.Rev. 1: Transfer from GKN Aerospace to Fokker Services	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Certification Plan TN/TA/ 07/05 Issue 3General Arrangement Drawing 08924/5 Issue 3Test Report TN/TA/07/31 Issue 01Test Report TN/TA/ 88/142Compliance Checklist C/R 016 Issue 02MajorChange Approval C/R 016 Issue 02CMM B737 Flight CompartmentNo. 2 Sliding Window Part No. 08924, 08925or later revisions...	None.	17/07/2017	Active	10014782
10014784 (EASA.A.S.02984)	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	757-200	Installation of fixed Emergency Locator Transmitter		Modification BBJ866. Technical Publication Supplements BBJMS058.	N/A	30/07/2019	Active	10014784
10014798 (EASA.A.S.03001)	AVIATION ENGINEERING AS	REV. 2		B200	Installation of UNIFIS 3000 Flight Inspection System including antennasin Beech B200.The system is used to check and calibrate ground based navigation aids.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23 amendment 23-0 unless otherwise noted: CS23.251, 23.301, 23.303,23.305, 23.307, 23.365, 23.561, 23.571 (c), 23.572(a), 23.573(b), 23.575, 23.603, 23.605, 23.607, 23.6...	· Air Alpha Master Drawing No. EN-B200-25-116-01, Rev.1, dated 30 August2007 Modification Front sheet for modification EO-B200-25-116 withcomplete listing of Declaration of Compliance, Report EO-B200-25-116.· Air Alpha Flight Manual Supplement for Beechcraft B200 with flightinspection system UNIFIS0...	Limited to B200 S/N BB-829.The installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.,,Prior to installation of this modification it must be determined thatthe interrelationship between this mod...	13/03/2019	Active	10014798
10014804 (EASA.A.S.03007)	ROEDER PRAEZISION GMBH	REV. 1		425	Installation of GTX 330D Mode S Transponder	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Doc. No. EO C425-NY-1240-05, R0.- EASA approved NAYAK AFM-S Doc. No. C425-NY-1240-08, or later approvedrevision.- NAYAK Maintenance Procedures. Doc. No. C425-NY-1240-07, or laterapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	30/10/2017	Active	10014804
10014805 (EASA.A.S.03008)	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Cabin Interior Refurbishment applicable to Dassault Aviation Falcon20-E5 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dossier de Demonstration de Conformite DDC-002-07 Revision 1 or later approved revisions.Master Data List MDL.002.07 Revision 1 or later approved revisions.Aircraft Flight Manual Supplement UAE-AFMS-07-001 Original Issue or later approved revisions.	This STC is approved only for Mystere Falcon 20-E5 aircraftserialnumber 302.Prior to installation of this modificationthe installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthine...	05/01/2015	Active	10014805
10014808 (EASA.A.S.03012)	LUFTHANSA TECHNIK AG	REV. 4		CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700,701,702) CL-600-2B19 (RJ SERIES 100)	Installation of non-electrical Floor Path Marking - FPMRev.4: new colours for light strips and carpet protectors, update ofdocumentation, plus addition of model 2E25.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	• Supplemental Type Definition Document ref. doc. STDD33-07/01MIss03Rev00, dated 21st March 2017• Instructions for Continued Airworthiness ref. doc. ICA33-07/02M Rev02• ComplianceRecord List ref. doc. CRL33-16/34M Iss01Rev00, dated 21stMarch 2017• Airplane Flight Manual Supplement ref. doc. A-33-07...	None	27/03/2017	Active	10014808

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014818 (EASA.A.S.03026)	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges	REV. 2		A320 MODELS	Installation of an In-Flight Entertainment System (Live TV)on AirbusA320 Aircraft	Certification Basis as per EASA TCDS A.064The CertificationBasis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applic...	- Engineering Order, ref. doc. No. EO_M06800106_CKA_06082010, Revision0, dated 4th November 2010- Airplane Flight Manual Supplement, ref. doc. No.AFS_M06800105_CKA_21052010, Revision 0, dated 14th July 2010- Instruction for Continued Airworthiness, ref. doc. No.ICA_M06800106_MGR_31082010, Revision 0...	Not applicable	05/11/2010	Active	10014818
10014821 (EASA.A.S.03032)	JET AVIATION AG, BASEL	REV. 1		A330-202	Cabin Interior Outfitting		-Certification Plan, ref. doc. No. B3300605, Rev. B, dated 05.11.2008-Master Document List, ref. No. B3300605-001, Rev.IR, dated 03.11.2008-Airplane Flight Manual Supplement, ref. doc. No. B3300605-201-01, Rev.IR, dated 22.10.2008- Applicant's Declaration of Compliance - CAF 2492 - Cabin InteriorOut...	None	02/11/2010	Active	10014821
10014832 (EASA.A.S.03047)	ACC COLUMBIA Jet Service GmbH	REV. 3		2. PA-34-220T (SENECA V) 1. PA-34-220T (SENECA IV) 1. PA-34-220T (SENECA III) 1. PA-34-200T (SENECA II)	System PA-34-812000Installation of Penta Camera SystemSystem PA-34-813000 Version 2024425Camera Hatch and Equipment Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.FAR 23 iaw, TCDS EASA.IM.A.090 and FAA A7SOThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain appl...	System PA-34-812000Flight Manual Supplement SPOH_14043_rev0_06112006Installation Instruction II14043_rev0_06112006System PA-34-813000Master Document List MDOCL_2024425_rev0_20111201Flight Manual Supplement SPOH_2024425_rev0_20110915Installation Instruction II14043_2024425_rev0_20110915or later revis...	As referred in AFM-S	03/02/2022	Active	10014832
10014836 (EASA.A.S.03052)	ACC COLUMBIA Jet Service GmbH	REV. 1		CESSNA 182	Towing Kit Cessna 182 "System Gomolzig" C182-820000".The Cessna 182 and its series equipped with the SMA Diesel engine shallbe equipped with a towing system for banning towing andsailplanes up to850 kg MTOW.Rev. 1 Transfer to ACC ColumbiaJet Service GmbH		Anhang zum Flughandbuch Modifikation 15530, Towing Kit "System Gomolzig" C182-820000, Ausgabe: 08.07 Doc.-No. SPOH_15530_rev1_16082007.Umrüstunganweisung Modifikation 15530 TowingKit "System Gomolzig" C182-820000, Ausgabe: 08.07 Doc-No.: II_15530_rev0_23052007.	Cessna 182M, N,P,Q,R, equipped with SMA SR 305-23-MA01 Diesel engine according to STC EASA.A.S.00774.	19/01/2022	Active	10014836
10014844 (EASA.A.S.03062)	AIR SERVICE VAMDRUP APS	REV. 2		PC-12/47 PC-12/45	Oxygen fill point modification (to remove limitation for installation ofSTC 10014844 (previous EASA.A.S.03062).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:As per EASA STC 10014844 (former EASA.A.S.03062)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pr...	-,,Engineering order EO-PC12-31-121, 1 March 2007;-,,Masterdrawing EN-PC12-31-121-01;-,,Airplane Flight Manual supplement, FMS.EO-PC12-31-121;-,,Supplemental Maintenance Manual ATP31.0114 Rev.0, 21 June 2007;-,,MEL Supplement EO-PC12-31-121, Report N. MEL0101;-,,When modification "Oxygen fill point...	Only eligible for PC-12/45 and PC-12/47 without the Oxygen systeminstallation in the Rear fuselage, unless modification"Oxygen fillpoint modification (to remove limitation for installation of STC10014844 (previous EASA.A.S.03062)" is installed.The installation of this modification by third personsw...	03/06/2013	Active	10014844

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014848 (EASA.A.S.03070)	airplus engineering GmbH	REV. 1		B200	TDR-94D-007 Mode S Transponder Dual Installation.		Installation must be in accordance with AIRplus Master Document List MD-0109-000000 Rev. 2, dated 02.07.07 or later Approved Revisions.Operation must be in accordance with AIRplusFlight Manual Supplement for TDR94D-007, PO-0109-343300 Iss.2 dated 02.07.07 or later approved revision.Maintenance must...	None	17/02/2021	Active	10014848
10014849 (EASA.A.S.03071)	airplus engineering GmbH	REV. 1		T303	Installation of GNS480 COM/NAV/GPS, TAWS8000, Sky 497 Skywatch, KCS55A Compass System, SL30 COM/NAV, KN63DME, GWX68 Radar, MX200 MFD and GMA 347 Audio System. This installation includes also one Digiflow and Engine monitoring system.		Installation must be in accordance with AirPlus Master Document List MD-0121-000000 Rev. 3 dated 17.Sep.07 or later Approved Revisions.Operation must be in accordance with Flight Manual Supplement PO-0121-340100 to PO-0121-340900 Rev. 1, or later approved revision.Maintenance must be in accordance M...	None	17/02/2021	Active	10014849
10014851 (EASA.A.S.03073)	airplus engineering GmbH	REV. 2		690, 690A, 690B, 690C, 690D	Installation of Garmin GTX 330 Mode S Transponder		Flight Manual Supplement Garmin GTX 330 Mode S Transponder Doc-No: PO-0124-343300, Rev 0, dated 27/06/2007	None	17/02/2021	Active	10014851
10014854 (EASA.A.S.03078)	DOA AESGLOBAL LIMITED	REV. 1		767-300	Introduction of 290 Pac Place Interior ConfigurationRev 1:Transfer from AES Ltd. to new STC holder AES Global Ltd.		Modification AES-767-787Reports: AES-TR-0250, AES-TR-0251, AES-TR-0252, AES-TR-0258, AES-TR-0277.	none	28/04/2021	Active	10014854
10014857 (EASA.A.S.03081)	AIR ALLIANCE GmbH	REV. 4		208, 208B	Conversion of airplane for parachute operationsConversion of airplane for parachute operations. Installation ofPARAKITNAY001 or Parakit C208-83 00 00 “System Gomolzig”	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For “Parakit NAY001“:- According to Master Document List ref. “Master Data List PARAKITNAY001”, revision 00, 29.03.1997.- To be operated and maintained in accordance with LBA approved AirplaneFlight Manual Supplement ref. “PARAKIT NAY001”,revision 00, 20.03.1997.For “Parakit C208-83 00 00 - System-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/08/2020	Active	10014857
10014863 (EASA.A.S.03087)	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV. 4	CAA UK RESPONSIBILITY	B747-400, -400F B747-100, -200B/C/F, -300,	STC EASA.A.S.03087: This modification introduces a Universal CockpitDisplay System (Electronic Flight Bag) into the aircraft consisting of 2Flight Deck Displays, an Application Server Unit, an Accessible DataUnit, an external video camera and associated wiring as detailed inCompliance Document Summa...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-25 Amendment 2 for the areas of changeThe requirements for environmental protection and the associatedcertificated noise and/ or emiss...	FMS-468-38 Rev. 5 Airplane Flight Manual SupplementUniversal Avionics Systems Corporation Service Bulletin 340.06.02-3284Installation of SCN 32.2 and Mod 2 in the ASUor later revisions of the above listed documents approved by EASA.	None.	21/05/2012	Active	10014863

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014881 (EASA.A.S.03109)	ROEDER PRAEZISION GMBH	REV. 1		MU-2B-40, MU-2B-60	Installation of XPDR Mode-S System with Diversity, Garmin GTX 330 D(single or optional dual installation possible).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- EASA approved Compliance Check List / Compliance Statement, Doc. No.MU2-NY-0243-01A, Revision 0, dated 20 February 2007 or later approvedrevision.- EASA approved Airplane FlightManual Supplement, Doc. No.MU2-NY-0243-08, dated 20-February 2007, or later approved revision.- Approved Amendment to Air...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	30/10/2017	Active	10014881
10014884 (EASA.A.S.03112)	CESKA LETECKA SERVISNI A.S.	REV. 1		560XL	Installation of UNIFIS 3000 Flight Inspection System: Console, cockpitindication system, antennaThis STC is a transfer of EASA STC A.S. 03112 from Air Alpha MaintenanceA/S.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-AFM Supplement FMS.EO-C560XL-25-117-Certification Plan CP-C560XL-25-117-Compliance Checklist CCL-C560XL-25-117or laterrevisions of the above listed documents approved by EASA.	None	21/09/2017	Active	10014884
10014887 (EASA.A.S.03116)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		BAE 146/AVRO 146 MODELS	95 Passenger LOPA Installation.Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ATL/1467067 Issue 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014887
10014897 (EASA.A.S.03127)	LUFTHANSA TECHNIK AG	REV. 3		777-200/-200LR/-300/-300ER	Installation of non-electrical floor path marking systemRev1: System commercial name changedRev 2: System commercial name removedRev 3: Extension of existing STC to models 777-200LR and 777-300ER	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Design Document STDD33-07/03M Issue 3-AFM supplement A-33-07/530-AFM Issue 1-MMEL Supplement A-00-19/41-MMEL Issue 00- Instructions for continued Airworthiness ICA33-07/03M Issue/rev 01/02or later revisions of the above listed document (s) approved/ acceptedunder the EASA system....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/05/2019	Active	10014897
10014906 (EASA.A.S.03142)	LUFTHANSA TECHNIK AG	REV. 6		A318-112	Structural Floor Panel Reconfiguration	Type Certification Basis in accordance with the TCDS No. A. 064 plus:- CRI D-01 "Door between passenger compartments with integrated blockingfunctionality"- CRI D-03 "Isolated Compartments"- CRI D-04 "Firm Handhold"- CRI F-01 "Executive Power System"plus voluntarily by applicant:- FAR 25.981 (a) (b)-...	- Supplemental Type Definition Document, Doc. No. STDD00-07/13M, issue08, dated 28 September 2009, or later approved revisions- Aeroplane Flight Manual Supplement A-00-07/702-AFM revision 6, dated30 September 2008, or later approved revision- Instructions for Continued Airworthiness, ref. Doc. No. R...	None	07/10/2009	Active	10014906

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014907 (EASA.A.S.03145)	ACC COLUMBIA Jet Service GmbH	REV. 4		U206, U206A, U206B, U206D U206E, U206F, U206G TU206B, TU206E, TU206F, TU206G T206H, TP206C, TP206D, TP206E P206C, P206D, P206E,	Installation of Cessna 206 Exhaust System	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmentalprotection and the associated certificated noise and/ or emissionslevels of the original product are unchanged and remain applicable tothis certificate/ approval.	1. TP206C-E; TU206B, E-G Exhaust System with Extension C() 206-6065802.T206H Low Noise Silencer Kit CT206H-6065703.P206C; P206D; P206E; U206; U206A; U206B; U206D; U206E; U206F; U206GLow Noise Silencer Kit C206-6065001. TP206C-E; TU206B, E-GExhaust System with Extension C() 206()-606580MDOCL_ 2028022_...	None	19/01/2022	Active	10014907
10014911 (EASA.A.S.03155)	AIRBUS S.A.S.	REV. 1		A320-214	Airbus Corporate Jet Centre Modification CJ0103 - VIP Interior -"Shining Star No. 2"Revision due to update of AFM-S andMPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI G-2102 "ACJC Project Certification Basis".The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	-Modification Approval Sheet ref.: CJ0103 Issue 4, dated 24th October2013-AFM Supplement: FM-S MOD CJ0103<(>,<)> Revision 05, dated 1st October2013-MPD-S MOD CJ0103<(>,<)> Revision 02, dated 1st May 2012-AMM-S MOD CJ0103, dated 01st November 2007or later revisions of the above listed documents appro...	This STC is limited to MSN 764Prior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The installation o...	22/11/2013	Active	10014911
10014924 (EASA.A.S.03172)	ROEDER PRAEZISION GMBH	REV. 2		A330-322	Business Class extension to a 30 B/C + 295 Y/C layout.This STC modifies cabin arrangement from a 18 B/C +343 Y/C layoutto a30 B/C +295 Y/C layout with new B/C seat and stowage compartmentinstallations.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS25 Amdt 3.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original p...	Master Document List, ref. MDL330-25-01-07 Revision 1, dated 25 Oct.2007<(>,<) >or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	15/06/2018	Active	10014924
10014936 (EASA.A.S.03192)	SAAB AB	REV. 3		CESSNA 560 560	Replacement of SSR Mode S Transponders for compliance with EnhancedSurveillance.Rev. 1: Transfer from Saab Aerotech Aircraft Services to SAABAKTIEBOLAG.Rev. 2: Correction of DOA reference.Rev. 3: Correction of Associated Technical Documentation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval. Therequirements forenvironmental protection and the associatedcertified noise and/ oremissions levels of the product are unchanged and remain applicable tothis certificate/ approval w...	SAAB AB TDM07-18, revision defined in TDM07-18-O-LEP, rev. A, 2007/11/01.AFM Supplement TDM07-18-3-AFMS, rev. A 2007-08-15.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/04/2024	Active	10014936
10014937 (EASA.A.S.03193)	SAAB AB	REV. 3		CESSNA 650 650	Replacement of SSR Mode S Transponders for compliance with EnhancedSurveillance.Rev. 1: Transfer from Saab Aerotech Aircraft Services to SAABAKTIEBOLAG.Rev. 2: Correction of DOA reference.Rev. 3: Correction of Associated Technical Documentation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Saab AB TDM07-19, revision defined in TDM07-19-0-LEP, Rev. A, 2007-11-01.AFM supplement TDM07-19-3-AFMS, rev. A, 2007-08-15.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/04/2024	Active	10014937
10014940 (EASA.A.S.03198)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		737-73S 737-700	148 Pax LOPA InstallationRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Modification Summary ATL/737/605 Issue 2-DRN10512-001 Issue 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Compatibility of this design change with other previously approvedmodifications must be determined by the installer.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intr...	09/11/2021	Active	10014940

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014942 (EASA.A.S.03201)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		757-200	219 PAX LOPA Installation.Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ATL Modification Summary Sheet ATL/757/180, issue 1, 02/08/2007.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC is limited to aircraft s/ n 26270.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014942
10014949 (EASA.A.S.03212)	DOA AESGLOBAL LIMITED	REV. 1		757-200	Introduction of alternative EGPWS Mode 6 Callout MenuRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.		AES Modification AES-757-894, issue 2 01/08/2007AES AFM Supplement No.6 issue 1	FAA STC ST00381SE must be installed prior to the installation of thisSTCvalidated as EASA.IM.A.S.2731 (10016402)	28/04/2021	Active	10014949
10014950 (EASA.A.S.03213)	DSA A.S.	REV. 1		T303	COMM/NAV/GPS GNS 530, GNS 430, Navigation Indicator GI 106,S-mode GTX 330 Transponder, GMA 340 ICS, and ELT Kannad 406AF installation into Cessna T303.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplement to Airplane Flight Manual No. 7, 8, 9, 10, 11, 12 ref. S7 LDA02/07/T-303 revise 3S8 LDA 02/07/T303 revise 3S9 LDA 02/07/T303 revise 3S10 LDA 02/07/T303 revise 3S11 LDA 02/07/ T303 revise 3S12 LDA 02/07/T303 revise 3or later revisions of the above listed document(s) approved/ acceptedunder t...	S/N: T303 00205.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	08/05/2020	Active	10014950
10014951 (EASA.A.S.03215)	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Antenna and Cables Installation provisions for satellite communicationsystem applicable to Dassault Aviation MF50 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Uni Air Enterprise Master Data List MDL-016-07 Revision 4, dated 10June 2008 ;2. Installation instructions in accordance with Unir Air EnterpriseService Bulletin SB-UAE-016-07-01 Revision 3, dated 9 June 2008 ;3. Unir Air Enterprise Maintenance Manual Supplement UAE-AMMS-07-004Revision 3, dated 2...	1. STC nor applicable to Falcon 50EX version aircraft;2. Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product. T...	05/01/2015	Active	10014951
10014952 (EASA.A.S.03216)	airplus engineering GmbH	REV. 1		S550 (CITATION S/II)	Installation of Bendix/King KLN 900, Shadin ADC-200 and Garmin GNS 530A.		• Master Document List, Rev. 01, dated 4 September 2007,or later approved revision.• Maintenance Manual Supplement Navigation System KLN 900, MM-0175-340100, Rev. 0, or later approved revision.• Maintenance Manual Supplement COM/VOR/ ILS/GPS/TAWS Garmin GNS-530A, MM-0175-340200, Rev. 0 or l...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	17/02/2021	Active	10014952
10014953 (EASA.A.S.03217)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 6		PC-12/47E PC-12/47 PC-12/45 PC-12	Installation of MTV-27-( ) or MTV-47-( ) propeller on Pilatus PC-12Series equipped with PT6A-67( ) or PT6E-67XP engine.Updated AFMS Performance Section for Pilatus PC-12 Series equipped withMTV-47-( ) propeller and PT6A-67( ) or PT6E-67XP engines.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase...	For all PC-12 models with PT6A-67( ) engine and MTV-27-( ) Propeller:According to MT-Propeller Master Documentation List No. E-1822 Rev. 14To be operated in accordance with MT-Propeller AFM-S Document No. E-1823Rev. 7To be installed i.a.w.MT-Propeller Installation Instruction Doc. No.E-1824 Rev. 10...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/03/2023	Active	10014953

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014958 (EASA.A.S.03228)	DSA A.S.	REV. 1		T206H	Installation of Leica RC30 with IPAS 10 and FCMS options.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplement to Airplane Flight Manual No. 9 (ref. S9 LDA/04/07/T206H)or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	S/N T20608636.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	08/05/2020	Active	10014958
10014963 (EASA.A.S.03234)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		CL-600-2B16	Introduction of Honeywell Mark V EGPWS.Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Ltd Modification ATL/ 600/002ATL AFM Supplement No63 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aviation Traders Ltd Modification ATL/600/003 (EASA.A.S.03244) must beembodied prior to, or concurrently with, Modification ATL/600/002.Prior to installation of this change/repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/...	09/11/2021	Active	10014963
10014966 (EASA.A.S.03241)	MAGNETIC MRO AS	REV. 2		757-200	Installation of Galley 1B and Forward RH Wardrobe.Revision:Transfer of Certificate to Magnetic MRO AS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MacCarthy Interiors Modification Leaflet 07ML149.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/09/2019	Active	10014966
10014967 (EASA.A.S.03244)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		CL-600-2B16	EFIS, GPS approach scaling and EGPWS displayRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Ltd Modification ATL/600/003or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10014967
10014971 (EASA.A.S.03251)	ROEDER PRAEZISION GMBH	REV. 1		SA227-AT, SA227-TT, SA227-DC SA226-T, SA226-AT, SA226-T(B),	Installation of Honeywell MK IV EGPWS, together with MFD and Thommen Air Data Computer	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA approved „Übersicht der Dokumente“, Project No. SA226/227-NY-0808,Revision 0, dated 07-Nov-2007, or later approvedrevisionEASA approved Airplane Flight Manual Supplement, Doc. No.SA226/227-NY-0808-08, Revision 0, dated 31-May-2007, or later approvedrevisionMaintenance Procedures, Doc. No. SA22...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/11/2017	Active	10014971
10014973 (EASA.A.S.03259)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 5		737-700, -800, -900 737-300, -400, -500, -600	Installation of a Dual navAero Electronic and logging display system.Change consisting in installing a dual portable Class 2 EFB's t.BagC2system	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis approval :CRI H-1 dated 7/11/2011The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate...	- Engineering order and certification program 2067424-EO issue 1 dated22/08/2011- AFM supplement 2067424-AM-A issue 2 dated 14/10/2011- AFM supplement with 3G automatic 2067424-AM-B issue 2 dated 14/10/2011- Instructions for Continuing Airworthiness 2067424-CA issue 2 dated13/10/2011or later revisio...	Not Applicable	14/11/2011	Active	10014973

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10014975 (EASA.A.S.03262)	AVIATION ENGINEERING AS	REV. 2		B200	Garmin GWX-68 Radar, Garmin GMX-200 Multi-Function Display,and AvidyneTAS620 Traffic Advisory System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 23amendment 23-0: CS23.251, 23.301, 23.303, 23.305, 23.307, 23.341,23.365, 23.561, 23.571(a), 23.573(b), 23.601, 23.603, 23.605, 23.607,23.611, 23.613, 23.627, 23.867,...	Flight Manual Supplement FMS.EO-B200-34-118.Engineering Order (EO-B200-34-118) and related documentsor later revisions of the above listed documents approved by EASA.	Limited to S/N BB829.The installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.,,Prior to installation of this modification it must be determined thatthe interrelationship between this modificat...	13/03/2019	Active	10014975
10014976 (EASA.A.S.03264)	AVIATION ENGINEERING AS	REV. 2		B200	Installation of two Sandel SN3500 EHSI (Electronic Horizontal SituationIndicator) replacing existing HSI displays.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23 amendment 23-0:CS23.301, 23.303, 23.305, 23.307, 23.341, 23.561, 23.601, 23.603,23.605, 23.607, 23.611, 23.613, 23.1301, 23.1309, 23.1311, 23.1321,23.1322, 23.1331,2...	· Flight Manual Supplement FMS.EO-B200-34-119, Revision1 and Revision2.· Engineering Order (EO-B200-34-119) and relateddocuments.or later revisions of the above listed documents approved by EASA.Note: Revision 2 of the AFMS has been approved with minor changeEASA.A.A.01890.	Limited to S/N BB829.The installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.,,Prior to installation of this modification it must be determined thatthe interrelationship between this modificat...	13/03/2019	Active	10014976
10014993 (EASA.A.S.03290)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		335, 340, 340A	Installation of 4-blade MT-Propeller Model MTV-14-D-C-F/CF188-30g onCessna 335, 340, 340A.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.CS-36 Amdt.2 and FAR 36 Amdt. 28This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	According to MT-Propeller Master Document List No. E-2460 andMT-Propeller Installation Instructions Doc. No. E-1530, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-1529To be maintained i.a.w. MT-Propeller ICA Document No. E-1531or later revisions of the above li...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The install...	19/12/2013	Active	10014993
10014994 (EASA.A.S.03291)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 3		757-200	Passenger/ Cargo Combi ConfigurationRev. 3: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:For changed areas Certification Basisis CS 25 amendment 2; includingthe following:CRI D-01: Special Condition: Cargo Compartment ClassificationCRI H-01: Spec...	ATL Master Document List: MDL-11630-00001, Issue 3, 04/02/2011ATL Modification Summary Sheet: MOD-11630-00001, Issue 2,04/02/2011or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC is limited to a/c serial number 25621 onlyATL Minor Modification MOD/11630/00003 must be installed concurrentlywith this STC.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ o...	09/11/2021	Active	10014994
10014998 (EASA.A.S.03298)	SAFRAN SEATS	REV. 1		DC-9	Meridiana DC-9 Stow Bin Extension.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Heath Tecna modification record C1037.	Restricted to ASN 49247,49248, 49531, 49669, 49740, 49901, 49902, 49903,53064, 49808, 53182, 49785, 49792, 49935, 49951, 49854, 53013.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change...	14/03/2019	Active	10014998
10015004 (EASA.A.S.03304)	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		FALCON 10	Falcon 10 EHS Mode S Capability.EASA.A.S.03304 has been reissued with reference 10015004, Rev. 1following a transfer from ACI Systèmes to Business & Commuter Aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement ACI-05-AFM-M-048-Rev0ACI-05-TD-M-048-Rev0	Applicabilty for Falcon 10 that are already Mode A<(>,<)> Cand ELS ModeS certified and equipped with a dual transponder system.	02/07/2013	Active	10015004

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015011 (EASA.A.S.03313)	LUFTHANSA TECHNIK AG	REV. 2		EMB-135/-145 SERIES	Installation of non-electrical Floor Path Marking System		Supplemental Type Definition Document STDD33-07/05M, issue 02.Airplane Flight Manual Supplement A-33-07/709-AFM.Applicant's Declaration of Compliance dated 20.11.2007.or later revisions of the above listed documents approved by EASA		05/03/2014	Active	10015011
10015012 (EASA.A.S.03314)	RUAG AG	REV. 1		DHC-6 SERIES 300 BOMBARDIER DHC-6 SERIES 300	Avionics system upgrade- In: Weather Radar System incl. ART-2000, AA-2012V, CM-2000; GarminGMX-200 Multi Function Display system; Avidyne TAS-620 system incl.Heading Adapter AHRS-500; Garmin GTX-330 Mode S Transponder system;Collins DME IND-42 system; UNS-1K+ FMS Upgrade; Bendix/ King EHSI KI-825incl...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Master Document List No. 131435-00 of 30.01.2009-Instructions for Continued Airworthiness No. 131435-60 of 19.03.2008-AFM Supplement No. 131435-50 of 14.03.2008or later revisionsof the above listed document(s) approved/acceptedunder the EASA system.	Reg.: T-741 S/N: 466Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changeand/ or repair will introduce no adverseeffect upon the airworthiness of the product.	29/01/2021	Active	10015012
10015022 (EASA.A.S.03328)	ACC COLUMBIA Jet Service GmbH	REV. 1		CESSNA 425 CESSNA 421C CESSNA 421B CESSNA 421A CESSNA 421 CESSNA 414A CESSNA 414 CESSNA 411A CESSNA 411 CESSNA 402C CESSNA 402B CESSNA 402A CESSNA 402 CESSNA 401B CESSNA 401A CESSNA 401	Alternative Supplemental Inspection Document (A-SID).Rev. 1Transfer to ACC Columbia Jet Service GmbH		- According to Gomolzig MDL Document No. MDOCL17070_REV0_0412 2008 or later EASA approved Revisions.- To be operated and maintained in accordance with approved Gomolzig Document No. A7CE_A-SID_Master Manual_17070, Original Issueor later EASA approved Revisions.	1. Alteration to A-SID is subject to written permission of approval holder.2. This modification is only limited to S/N listed in EASA approved Gomolzig Document No. 17070_Master Aircraft Application Control List_01122008_ rev0, or later EASA approved Revisions.3. Prior to installation of th...	20/01/2022	Active	10015022
10015025 (EASA.A.S.03332)	AIRBUS S.A.S.	REV. 1		A320-214	Airbus Corporate Jet Centre Modification CJ0145 - VIP Interior -"Shining Star No. 1"Revision due to update of AFM-S andMPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI G-2103 "ACJC Project Certification Basis"The requirements for environmental protection and the associatedcertified noise and/ or emissions leve...	-Modification Approval Sheet ref.: CJ0145 Issue 4, dated 24th October2013-AFM Supplement ref.: FM-S MOD CJ0145, Revision 06, dated 1st October2013-MPD Supplement ref.: MPD-S MOD CJ0145, Revision 06, dated 1st October2013-MPD Supplement SATTV ref: MPD-S MOD CJ0277 dated 01/10/08or later revisions of...	This STC is limited to MSN 3164Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The installationw...	22/11/2013	Active	10015025
10015027 (EASA.A.S.03334)	ACC COLUMBIA Jet Service GmbH	REV. 5		208, 208 B	Installation of Dual Camera Hatches C208-812000 with sliding doors andmission power supplyInstallation of Single CameraHatch C208-812100 with sliding door andmission power supply	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For Textron 208B S/N 208B0001 through 208B4999 except 208B2197 modifiedwith Camera Hatches C208-812000 before November 1 2014 (excludingaircraft registered in Japan)-Flight ManualSupplement SPOH_17000_rev1_12122007, dated 12.12.2007 orlater approved revision-Installation Instruction "Umrüstanweisun...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/01/2022	Active	10015027

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015028 (EASA.A.S.03335)	INTERNATIONAL ENGINEERINGAS SISTANCE (IEA)	REV. 3		PIPER PA-28	Rudder Hand Control and Brake System updated Engineering designdrawings.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Data list FA 37/2007, rev.2 dated 03/06/2008 and as modified byMaster Data List: IEA-233 RevB, dated 12/12/2016Flight Manual supplement AFM-37-2007-002, rev.2 dated 03/06/2008Instruction for Continued Airworthiness ICA-37-2007-000, rev.0 dated25/10/2007or later revisions of the above listed d...	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.	12/12/2016	Active	10015028
10015031 (EASA.A.S.03343)	ACC COLUMBIA Jet Service GmbH	REV. 4		DO 28 D-2	Do 28-G92 H75 Engine InstallationTurbine Conversion of Do 28 D-2 (model marketing name Do 28-G92) intofollowing variants:-G92-A-1900-G92-A-1950-G92-B-1800-G92-B-1950-G92-H75-200With associated implementation of an inspection program to ensurecontinued airworthiness through early detection of structu...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	To be operated in accordance withDo 28-G92-A-1900, G92-A-1900, G92-A-1950Flight Manual: Dornier Do 28-G92 Airplane Flight Manual approved by theHGCAA for each individual airplane including approved AFM-Supplements orlater approved revisions,,Do 28-G92-B-1800, G92-B-1950Flight Manual: Dornier Do 28-G...	Technical Characteristics and Limitations:The following technical characteristics and limitations deviant from thebasicaircraft apply for variants G92-A-1900, G92-A-1950, G92-B-1800,G92-B-1950Engine model:,,,,,,,,Walter M601 D-2 turbopropenginesEngine Type Certificate:,,,,,,EASA.E. 070Engine limita...	19/01/2022	Active	10015031
10015034 (EASA.A.S.03347)	ACC COLUMBIA Jet Service GmbH	REV. 2		BEECH B99 BEECH 99	Installation of P&W PT6A-34 Engine		Flight Manual Supplement SPOH_08959_15022008_rev 0 , dated 15.02.2008Installation Instructions II_08959_15022008_rev0, dated 15.02.2008	This STC is limited to Beech 99 / B99 models equiped with Propeller McCauley 4HFR34C769/94LMA-4 i.a.w. FAA STC SA1351GL.	20/01/2022	Active	10015034
10015036 (EASA.A.S.03349)	BUSINESS AND COMMUTER AIRCRAFT	REV. 2		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Installation of 220 VAC Electrical Power Supply and Distribution inCabin applicable to Dassault Aviation MF50 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Uni Air Enterprise Master Data List MDL-023-07 Revision 5, dated 17thFebruary 2012.Configuration 1:Installation Instructions in accordance with Uni Air Enterprise ServiceBulletin SB-UAE-023-07-01 Revision 3, dated 07th March 2008.Uni Air Enterprise Airplane Flight Manual Supplement UAE-AFMS-07-006Re...	The approval holder shall fulfil the obligations of Part 21, Paragraph21.A109.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the ai...	05/01/2015	Active	10015036
10015037 (EASA.A.S.03350)	BUSINESS AND COMMUTER AIRCRAFT	REV. 2		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Installation of an In-Flight Passenger Entertainment Systemin cabinapplicable to Dassault Aviation MF50 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Uni Air Enterprise Master Data List MDL-022-07 Revision 3, dated 23January2012.Configuration 1:Installation Instructions in accordance with Uni Air Enterprise ServiceBulletin SB-UAE-022-07-01 Revision 2, dated 18th March 2008.Uni Air Enterprise Airplane Flight Manual Supplement UAE-AFMS-07-005Revisi...	STC limited to those Mystere Falcon 50 (MF50) aircraft on which UniAirSTC 10015036 Revision 1 "Installation of 220 VAC Electrical Power Supplyand Distribution in Cabin" has been embodied.The approval holder shall fulfil the obligations of Part 21,Paragraph21.A109.Prior to installation of this modifi...	05/01/2015	Active	10015037

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015053 (EASA.A.S.03374)	AIRBUS S.A.S.	REV. 1		A319-115	Airbus Corporate Jet Centre Modification CJ0222 - VIP Interior -ResidenceRevision due to update of AFM-S and MPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A-4301-019 "ACJC Project Certification Basis".CRI H-01 - ICA on EWISThe requirements for environmental protection and the associatedcertified n...	-Modification Approval Sheet ref.: CJ0222 Issue 3, “Top ModificationResidence”, dated 24th October 2013-AFM Supplement ref.: FM-S MOD CJ0222, Revision 02, dated 1st October2013-MPD Supplement ref.: MPD-S MOD CJ0222, Revision 04, dated 1st October2013-MPD Supplement ref.: MPD-S MOD CJ0310 dated 1st M...	This STC is limited to MSN 3356Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The installationw...	22/11/2013	Active	10015053
10015062 (EASA.A.S.03388)	airplus engineering GmbH	REV. 1		690A	GPS Antenna Installation.		Installation must be in accordance with AirPlus Master Document List MD-0224-000000 Rev. 1 dated 05.Feb.08 or later Approved Revisions.Maintenance must be in accordance Manual Supplement MM-0224-530512 Iss. 0 dated 05. Jan 08 or later approved revision.		17/02/2021	Active	10015062
10015090 (EASA.A.S.03427)	JET AVIATION AG	REV. 1		CL-600-2B16	Iridium Antenna Installation Aircell ST2100.		Instruction for Continued AirworthinessJBSL Doc. No. BCL6153301-150-01	None	30/07/2018	Active	10015090
10015093 (EASA.A.S.03430)	AEROTEC & CONCEPT	REV. 2		C-212-DD (C212-300) C-212-CC (C-212-200)	MOD 0803: Navigation/Communication (NAV/COM) set replacement and HFCommunication set (provisions) installationThis STC replaces a previous NAV/COM system by an up-to-date one, andinstalls a new HF Communication set (provision).Rev. 1 of this STC restored the aircraft IFR capability by removing theli...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 4AC 43.13The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and...	MASTER DATA LIST: AE0803MDL Rev. 6 Dated 22. Sept. 2016For MSN 387:-INSTRUCTIONS POUR LE MAINTIEN DE LA NAVIGABILTE: AE0803 IPMN REV 2dated 27. Oct. 2008-SUPPLEMENT AU MANUEL DE VOL: AE0803 SMV REV 4 dated 19. Nov. 2008For MSN 139:-AIRCRAFT FLIGHT MANUAL SUPPLEMENT: AE0803AFMS_2 REV 0 dated 22. Jul....	1. This STC is limited to MSN 387 and MSN 1392. HF communication set (subpart of this STC) is not approved (notinstalled / not operational wiring provisions are accepted) Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any o...	26/10/2016	Active	10015093
10015096 (EASA.A.S.03433)	airplus engineering GmbH	REV. 1		B200	Installation of SKY899 Transmitter Receiver Computer and Directional Antenna NY164 Installation.		Installation in accordance with AirPlus Master Document List Doc-No-MD-0238-000000, Rev 1, or later approved Revisions.To be operated in accordance with AirPlus Airplane Flight Manual Supplement Doc-No. PO-0238-348990, Rev 0, or later approved revisions.To be maintained i.a.w. AirPlusMaintenance Man...		17/02/2021	Active	10015096
10015097 (EASA.A.S.03436)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		A310-325 A310-324 A310-322, A310-324 A310-322 A310-308 A310-304, A310-308 A310-304 A310-222 A310-221, A310-222 A310-221 A310-204 A310-203C A310-203, A310-203C A310-203	Bluesky D1000 Satcom installationThe Supplemental Type Certificate EASA.A.S. 03436 embodied provisions fora further configuration installing BlueSky Network Satcom System D1000withan Intercom Integration option.Rev. 1: approval of the activation of the installed device.Rev. 2: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Cf. DGAC-F TCDS n° 145CRI H-01: ICA on EWISThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the pro...	Master Drawing List, ref. MDL/A31/017, Issue 6Aircraft flight Manual Supplement, ref: 11301-AFM-00001, Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10015097

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015103 (EASA.A.S.03446)	AIM AVIATION (JECCO) LIMITED	REV. 1	CAA UK RESPONSIBILITY	A330-243	Major Change to STC EASA.A.S.03446 (AIM Major Change MM384-07)date of issue 14 November 2008.Introduce decorative finish change to Contour 0995 series BusinessClass Seats.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA Special condition for seat heat release requirements (CRID-4322-001) for areas and parts affected by the change.The requirements for...	- AIM MAJOR Change ref. Doc. MM481-10 Issue C dated 21 December 2010.- AIM Certification and Compliance Check List, ref. Doc. Appendix toMM481-10Issue C dated 21 December 2010.- Declaration of compliance, page 24 of AIM Certification and ComplianceCheckList, ref. Doc. Appendix to MM481-10 Issue C da...	EASA Supplemental Type Certificate EASA.A.S.03446 (AIM Major ChangeMM384-07) must be embodied prior to the installationof this MajorChange.As per indications stated in AIM MAJOR Change ref. Doc. MM481-10 IssueC.	22/12/2010	Active	10015103
10015115 (EASA.A.S.03464)	TÄBY AIRMAINTENANCE AKTIEBOLAG	REV. 1		SAAB SF340A SAAB 340B	Rework of Class E cargo role of QC variantRev. 1: Transfer of Certificate	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	S21.FMS-0038 Flight Manual SupplementS21.MMEL-0011 Master Minimum Equipment List SupplementS21.TEC-0185 Supplement Manual for Continued AirworthinessS21.TEC-0206 Weight and Balance Manualor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	1. SAAB SF340A with Saab Modification 1461 embodied2. The installation of this modification by third persons is subjecttowritten permission of the approval holder.This Certificate shall remain valid unless otherwise surrendered orrevoked.Prior to installation of this change/repair it must be determ...	17/02/2020	Active	10015115
10015116 (EASA.A.S.03465)	SAAB AB	REV. 2		LEARJET 35A 35A	Installation of Honeywell MK VIII EGPWS and Mission InhibitSystem.Rev. 2: Transfer from SAAB AB- Saab Aerotech to SAABAB.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchanged and remain applicable to this certificate/ approval w...	TDM08-06 with revision as described in TDM08-06-0-LEP, Rev. A, 2008-08-22.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/12/2023	Active	10015116
10015120 (EASA.A.S.03469)	LUFTHANSA TECHNIK AG	REV. 2		D328 SERIES	Installation of non-electrical Floor Path Marking System		Type Definition Document STDD33-08/01M Issue 01Airplane Flight Manual Supplement A-33-08/034-AFM dated JAN 28/08Instructions for Continued Airworthiness ICA33-08/01M dated FEB 04/08 orlater revision.or later revisions of the above listed documents approved by EASA		05/03/2014	Active	10015120
10015121 (EASA.A.S.03470)	ACC COLUMBIA Jet Service GmbH	REV. 1	EASA STC 2004-1522	CESSNA 402C CESSNA 402B CESSNA 402A CESSNA 402	Use of Aerial Survey Camera Kit C402-812000 for installation of ZeissRMK Top 15 and Top 30 cameras.Note: Change to the existing EASA STC 2004-1522 to enable optionaloperation of digital camera systems or laser scanners in accordance withMDL MDRWL_14631_revC_10102007.Rev. 1 Transfer to ACC Columbia J...		Flight Manual Supplement to the Pilot Operating Handbook - Aerial Survey Camera Kit C402-812000 Rev. D, dated 25/01/2008.Installation and Maintenance Instructions: Umruestanweisung Kameraruestsatz System Gomolzig C402-812000 Rev. C, dated 25/01/2008.		26/01/2022	Active	10015121
10015122 (EASA.A.S.03471)	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV. 2	CAA UK RESPONSIBILITY	737-300	B1/B2 Engine Thrust Programming Connector Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance document BAC/737/091 Issue 5 dated 22 January 2013.Instructions for Continued Airworthiness:For Group 1 aircraft refer to ICA/ 050/544For Group 2 aircraft refer to BAC-544ICA01or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	24/01/2013	Active	10015122

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015123 (EASA.A.S.03472)	SAAB AB	REV. 2		MU-2B MITSUBISHI MU-2B	Garmin GTX 330/330D (SSR Mode S Transponder) upgrades for compliancewith Enhanced Surveillance (EHS) requirements.Rev. 1: Transfer from SAAB Aerotech AB to SAAB AKTIEBOLAG.Rev. 2:Correction of DOA reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Saab AB TDM08-03, with revisions defined in TDM08-03-0-LEP,Rev. A, 2008-02-22AFM Supplement TDM08-03-3AFMS, Rev A, 2008-01-28.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/approval w...	07/12/2023	Active	10015123
10015126 (EASA.A.S.03476)	HAWKER BEECHCRAFT Ltd.	REV. 1	CAA UK RESPONSIBILITY	HAWKER 750	Installation of Steep Approach Capability	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft with Honeywell EGPWS installed-Installed to Major Change SC0316A at issue 1 or later.- Operated to Airplane Flight Manual Supplement 1 for Flight Manual140-590039-0005.- Aircraft Crew Manual Supplement - Crew Manual - Series 750.-Maintained in accordance with Instructions for Continued Airwor...	None	05/05/2011	Active	10015126
10015127 (EASA.A.S.03477)	HAWKER BEECHCRAFT Ltd.	REV. 1	CAA UK RESPONSIBILITY	HAWKER 900 XP	Installation of Steep Approach Capability	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft with Honeywell EGPWS installed-Installed to Major Change SC0317A at issue 1 or later.- Operated to Airplane Flight Manual Supplement 1 for Flight Manual140-590037-0005.- Aircraft Crew Manual Supplement - Crew Manual - Series 900XP.-Maintained in accordance with Instructions for Continued Airw...	None	05/05/2011	Active	10015127
10015131 (EASA.A.S.03482)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		BEECH B300C BEECH B300 BEECH 300LW BEECH 300 300LW, B300, B300C, 300	Digital FDR InstallationThis revision is made to introduce a new type of Flight Data Recorder -FDR (Adaptive Aerospace Series 200 FDR) where Garmin G1000 (NXI)avionics is data source for all data parameters.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Technical Order, document 2045502-TO_B, Issue 3, date 30.04.2025Airplane Flight Manual Supplement, document 2045502-AM_C, Issue 2, date18.07.2025Instructions for Continued Airworthiness, document 2045502-CA_B, Issue1, date 12.02.2025Maintenance Manual Supplement, document 2045502-MM_B, Issue 3, date...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This change is limited to the configuration of aircraft...	04/08/2025	Active	10015131
10015134 (EASA.A.S.C.01008)	BLUE SKIES AVIATION OY	REV. 2		B. A150L, A150L, A150M B. 150H, 150J, 150L, 150M B. 150D, 150E, 150F, 150G A. FA150M A. F150M, FA150K, FA150L A. F150J, F150K, F150L A. F150F, F150G, F150H	Installation of engine Rotax 912 F3 and installation of PropellerHoffmann HO-V352F/170FQ on Cessna Models 150H, F150H, A150K, FA150K,A150L, FA150L, 150K, F150K, 150L and F150L only.Installation of engine Rotax 912 S3 (100PS) and installation ofPropeller Hoffmann HO-V352F/170FQ+10 on all a.m. models....	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: FAR 23 Amendment 33.This certificate/ approval involves a change to the requirements forenvironmental protection or a chan...	Aircraft installed with Rotax 912 F3:Cessna 150H, F150H - Flight Manual Operation Instruction Hoffmann No.605 Issue 09.98, LBA approved 06.10.1998;- Cessna A150K, FA150K, A150L, FA150L - Flight Manual and OperationInstruction Cessna A150K and FA150K, A150L and FA150L, SDF No. 131,issue 1/20.01.1999,...	- Spin is prohibited to all models.- Aerobatic including Spin is prohibited to Cessna A150K, FA150K, A150Land FA150L.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andany otherpreviously installed change and/ or repair will int...	18/07/2018	Active	10015134

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015136 (EASA.A.S.03489)	AERODATA AG	REV. 3		B200, B200C, B200GT	Installation of Aerodata Flight Inspection System- AD-AFIS-120, Mod. No. B200-11.01, or- AD-AFIS-250, Mod. No. B200-12.01, or- AD-AFIS-250, Mod. No. B200-12.02, or- AD-AFIS-250, Mod. No. B200-14.01	Design:Non-significant changeThe Certification Basis of theoriginal product and the followingadditional / alternative airworthiness requirements are applicable tothis change.CS-23, Amdt. 1, except 23.561 (kept FAR 23.561 at Amdt. 7) is elected tocomply with for the items affected by the change.Envi...	For AD-AFIS-120, Mod. No. B200-11.01:EASA approved Master Document List, Installation of Aerodata FIS, Doc.No. MDL-A/ C-129, Rev. 3, dated 27-Nov-2009, or later approved revisionEASA approved Airplane Flight Manual Supplement, Doc. No. AFM-094, Rev.4, dated 27-Nov-2009, or later approved revisionAppr...	For AD-AFIS-120, Mod. No. B200-11.01:Only applicable for aircraft model B200 and B200GT, and when equippedwith Collins Proline 21<(>,<)> and preconditions as defined in DesignDescription, Installation of Aerodata FIS, Doc. No. DES-A/C-836,Rev. 2,dated 27-Mai-2008, or later approved revision<(>,<)>F...	08/06/2011	Active	10015136
10015149 (EASA.A.S.03509)	DIEHL AVIATION LAUPHEIM GmbH	REV. 2		777-200	Installation of Galleys and Closets on BAW B777-236, Kit P/N 190331-51	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Program and Compliance Check list CP 190331 dated February27th, 2008or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/07/2019	Active	10015149
10015162 (EASA.A.S.03532)	SAAB AB	REV. 1		LEARJET 35A 35A	Mode S Enhanced Surveillance (EHS) Upgrade.Rev. 1: Transferfrom Saab Aerotech Aircraft Services to SAAB AB.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AFM Supplement as per TDM08-02-03-AFMS, Issue A (or later approved revisions).	EHS Non-Capable.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	06/12/2023	Active	10015162
10015164 (EASA.A.S.03535)	CESKA LETECKA SERVISNI A.S.	REV. 1		560XL	Printer Stand InstallationThis is a transfer of EASA.A.S.03535 from Air Alpha Maintenance A/S	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-STC Definition Document EO-B200-C560-25-124-EO-124 Supplemental Maintenance Manual-EO-124 Drawing Listor later revisions of the above listed documents approved by EASA.	None	21/09/2017	Active	10015164
10015172 (EASA.A.S.03546)	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Installation of a passenger entertainment audio and video system in thecabin applicable to Dassault Aviation Mystère Falcon 20 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Uni Air Enterprise Master Data List MDL-008-08 Revision 1, dated 15thMay 2008.Installation instructions in accordance with Uni Air Enterprise ServiceBulletin SB-UAE-008-08-001 Revision 1, dated 16th May 2008.Uni Air Enterprise Airplane Flight Manual Supplement UAE-AFMS-08-0022Revision original dated...	Design change applicable to Mystere Falcon 20 aircraft serial number311.	05/01/2015	Active	10015172
10015174 (EASA.A.S.03547)	J & C ENGINEERING SERVICES Ltd.	REV. 2	UK.STC.00325	R2160, R2160D, R2160I, R2120U R2160D, R2120U HR200-120, R2160, R2160I	REMOVAL OF VFR LIMITATION FROM AFM APPROVED OPERATIONS SECTION	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-23 Amendment 4:CS23.611, CS23.771, CS23.773, CS23.867, CS23.1301, CS23.1303, CS23.1309,CS23.1321, CS23.1...	Kind of operations - VFR and IFR by Day and by Night in nonicingconditions - in accordance with J & C ENGINEERING SERVICES Ltd.document JC/CP/1444, at Issue 3.0, dated February 15, 2024;Aircraft Flight Manual Supplements:JC/FMS/1444 Iss 1.1 Operation of the Aircraft under IFR (R2160i) Dated24-01-2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/08/2025	Active	10015174

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015184 (EASA.A.S.03564)	SABENA TECHNICS BGC	REV. 2		ATR 72-212, ATR 72-212 A ATR 42-500, ATR 72-202 ATR 42-300, ATR 42-320	Floor To Floor Nets installation on “Quick Change” ATR42 & 72.This STC consists in installing the floor to floor nets instead of thecontainer cargo system. The nets are installed in the container zonedefined by ATR through their Class E Quick Change configuration.Revision 1 adds some aircraft models...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4paragraphs: 25.23, 25.25, 25.27, 25.29,25.301, 25.303, 25.305, 25.561,25.601, 25.603, 25.607, 25.61...	- Master Data List, AEROCONSEIL document No. 4174-01-A-2103-R05, dated13 October 2020;- Instructions for Continued Airworthiness, AEROCONSEIL document No.4174-01-A-2211-R02,dated 09 October 2020- Weight and Balance Manual Supplement, AEROCONSEIL document No.4174-01-A-2305-R02dated 13 October 2020 (f...	Limited to those ATR A/C model shaving the following modificationembodied :For ATR 42-300 & ATR 42-320:• Optionone:o ATR Mod 1393 - Reinforce all floor panels to 400 Kg/m2, ando ATR Mod 1769 - Modify a/c for Cargo Container Loading, ando ATR Mod 2080 - Modifying Actuating Mechanism fo...	21/10/2020	Active	10015184
10015207 (EASA.A.S.03620)	AVINCIS AVIATION ITALIA S.P.A	REV. 3		500	STC EASA.A.S.03620 dated 2 June 2009 "Satellite Telephone System"Rev. 2 is an administrative re-issuance to reflect therecent namechange from INAER Aviation Italia S.p.A. Divisione Ala Fissa.Rev. 3: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS-25. 1309The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain app...	Master Drawing List MDL-23-00-0802-A dated 26 May 2009	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/02/2024	Active	10015207
10015216 (EASA.A.S.03631)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 3		3. SA227-CC, SA227-DC 2. SA227-AC, SA227-BC 1. SA227-TT, SA226-T(B) 1. SA227-AT	Installation of 5-blade MT-Propellers ModelMTV-27-1-E-C-F-R(G)/ CFRL250-103	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.	For Model SA226-T(B), SA227-TT:According to MT-Propeller Master Operation Manual List Doc. No. E-2084and MT-Propeller Installation Instructions Doc. No. E-2085, or laterRevisionsTo be operated in accordance with MT-Propeller AFM-S DocumentNo.E-2069, or later approved RevisionsTo be maintained i.a.w...	Model SA227-TT and SA226-T (B) limited to "Normal Category" with MTOW12500 lbsAccording limitation section of AFM-S	09/12/2011	Active	10015216
10015219 (EASA.A.S.03634)	airplus engineering GmbH	REV. 1		PA-42 (CHEYENNE III)	Installation of the Garmin GNS530, Junction Boxes, GMA 340,EX-500 and GTX330D in Piper PA-42 Series.		Installation must be in accordance with AirPlus Master Document List MD-0356-000001 Rev. 1 dated 29.April 2009 or laterApproved Revisions.Operation must be in accordance with theFlight Manual Supplements listed in the MDL MD-0356-000001.Maintenance must be in accordance Manual Supplements listed i...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	17/02/2021	Active	10015219
10015221 (EASA.A.S.03638)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH	REV. 1		650 (CITATION III)	Primus 880 WX & MFRD installationRemoved existing Weather Radar Equipment:- i.a.w Installation Instructions, Doc. No. OPM-003New Installed Weather Radar Equipment:- Primus 880 Weather Radar System- Honeywell Multi Function Display, P/N 80-5204-XX-Xi.a.w Installation Instructions, Doc. No. OPM-003Rev...	FAA TCDS A9NMThe Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	- Master Document List, Doc. No. MDL-059, Rev. B or latest approvedRevision- AFMS, Doc. No. FMS-035, Rev. A or latest approved Revision- ICA, Doc. No. ICA-027, Rev. IR or latest approved Revision- Installation Instructions, Doc. No. OPM-003, Rev. B or latest approvedRevisionor later revisions of the...	None	23/02/2012	Active	10015221

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015222 (EASA.A.S.03639)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH	REV. 2		650 (CITATION III)	MK VII EGPWS Installation.Removed existing Equipment:i.a.w.Installation Instructions, Doc. No. OPM-004New installed EGPWS Equipment:- Honeywell MK-VII EGPWSi.a.w. Installation Instructions, Doc. No. OPM-004Revision 1: By revising the interface between the Vertical Gyro and theEGPWC and adapt the Gr...	FAA TCDS A9NMThe Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	- Master data List, Doc. No. MDL-060, Rev. B- AFMS, Doc. No. FMS-036, Rev. A- ICA, Doc. No. ICA-028, Rev. IR- Installation Instructions, Doc. No. OPM-004, Rev. Aor later revisionsof the above listed documents approved by EASA	None	23/02/2012	Active	10015222
10015223 (EASA.A.S.03640)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH	REV. 1		650 (CITATION III)	RAAS activation on the Honeywell MK-VII EGPWSi.a.w. Installation Instructions, Doc. No. OPM-005Revision 1 has been issued to reflect the transfer of STC.	FAA TCDS A9NMThe Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	- Master Document List, Doc. No. MDL-061, Rev. A- AFMS, Doc. No. FMS-037, Rev. IR- ICA, Doc. No. ICA-029, Rev. IR- Installation Instructions, Doc. No. OPM-005, Rev. IRor later revisions of the above listed documents approved by EASA	None	23/02/2012	Active	10015223
10015224 (EASA.A.S.03641)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH	REV. 3		650	P-RNAV Compliance in installed GNS-XLS(s) FMS, i.a.w. InstallationInstructions, Doc No. OPM-006Revision 2 has been issued to reflect the removal of the limitation toC650 (CitationIII up to S/N -199), AFMS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Jet Aviation Flight manual Supplement, FMS-038, rev. B, date 12December 2012- Jet Aviation Master Document List, MDL-062, rev. B, date 12 December2012-Jet Aviation Installation Procedure, OPM-006, rev. A, date 12 December2012-Jet Aviation Maintenance Manual Supplement, ICA-030, rev. B, date 12Decemb...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	01/03/2013	Active	10015224
10015225 (EASA.A.S.03642)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH	REV. 1		650 (CITATION III)	FA2100 CVR installationRemoved Equipment:- i.a.w. Installation Instructions, Doc. No. OPM-007New Installed Equipment:- FA2100 Cockpit Voice Recorder Systemi.a.w. Installation Instructions, Doc. No. OPM-007Revision 1 has been issued to reflect the transfer of STC.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List, Doc. No. MDL-063, Rev. A- AFMS, Doc. No. FMS-039, Rev. IR- ICA, Doc. No. ICA-031, Rev. IR- Installation Instructions, Doc. No. OPM-007, Rev. Aor later revisions of the above listed documents approved by EASA	None	23/02/2012	Active	10015225
10015227 (EASA.A.S.03644)	BUCHER LEICHTBAU AG	REV. 5		PC-12/47E	Bucher EMS Equipment PC-12/47E - P/N 0127001-400 / 0127001-450 / 0127001-460- Change to EMS variants P/Ns 0127001-400 & -450 to include provisionsfor use with RVSM capable PC-12 variants- Introduction of new EMS variant P/N 0127001-460	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Config. P/N 0127001-400:- Aircraft Flight Manual SupplementFMS 0127001-400 Rev. C, dated Apr28th, 2015- Component Maintenance Manual CMM E016-21-08 Rev. 7, dated Dec 01st,2014- Vendor Service Bulletin 0127001-25-004 Rev. 01, dated Apr 28,2015- Master Document List E034-04-08 Rev. IConfig. P/N 0127...	Compliance with Vendor Service Bulletin 0127001-25-004 is aprerequisitefor restoring RVSM capabilities for RVSM equipped PC-12 variants whenequipped with Bucher Leichtbau AG EMS P/Ns 0127001-400 / 0127001-450Prior to installation of this modification it must be determined thatthe interrelationshipi...	04/05/2015	Active	10015227
10015236 (EASA.A.S.03662)	DOA AESGLOBAL LIMITED	REV. 1		757-200	Introduction of Flight Control Computer (FCC) Interlock2.Rev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.		AES Master Data List, AES-757-1187MDL, Issue 1, 04/08/2008.	• Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.• The installation of this modification by third...	28/04/2021	Active	10015236

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015240 (EASA.A.S.03667)	airplus engineering GmbH	REV. 1		B200	Installation of Dual Garmin COMM/ NAV/GPS GNS430AW or GNS430Wand/ or Avidyne EX500 MFD interfaced withexisting WX Radarand/or L3-Com A100S Cockpit Voice Recorderand/or Single Counter Pointer Drum Altimeter Aerosonic p/n 10450- 11951and/orand/orand/or...		Flight Manual Supplements:HPB200-AM-3160-01-01 Issue 1HPB200-AM-2310-01-01 Issue 1HPB200-AM-3130-01-01 Issue 1HPB200-AM-3470-01-01 Issue 1HPB200-AM-34/23-01-01 Issue 1HPB200-AM-3430-01-01 Issue 1HPB200-AM-3450-01-01 Issue 1HPB200-AM-3400-01-01 Issue 1HPB200-AM-3401-01-01 Issue 1Engineering Order:HPB...	1. Restricted to aircraft which have already approved antenna locations for thenew equipment.GNS430(A)W installations restricted to aircraft which have already the followingequipment installed, completely independend from the Garmin GNS430(A)W units:VHF transceiver or VOR receiver and DME transceive...	17/02/2021	Active	10015240
10015241 (EASA.A.S.03669)	BUSINESS AND COMMUTER AIRCRAFT	REV. 2		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Iridium telecommunication system installation applicable toDassaultAviation MF50 aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Uni Air Enterprise Master Data List MDL-016-08 Revision 2,dated 20thJuly 2010.-Installation instructions in accordance with Uni Air Enterprise ServiceBulletin SB-UAE-016-08-01 Revision 0, dated 26th September 2008.-Uni Air Enterprise Airplane Flight Manual (AFM) SupplementUAE-AFMS-08-007 Revisiono...	Installation limited to those Mystere Falcon 50 (MF50) aircraftpreviously modified i.a.w. Uni Air Enterprise S.A.S. Supplemental TypeCertificate (STC) "Antenna and cables installation provisions forsatellite communication system" approved under EASA.A.S.03215.This STC is not applicable to Mystere Fa...	05/01/2015	Active	10015241
10015249 (EASA.A.S.03688)	ALAMO ENGINEERING GmbH	REV. 3		JETSTREAM 4100 SERIES	Mode-S Enhanced Surveillance (EHS) Upgrade.Rev. 3: Transferfrom "Deutsche Aircraft GmbH" to "Alamo EngineeringGmbH"	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25, Initial Issue: 25.1, 25.301, 25.303, 25.305, 25.307, 25.365,25.561, 25.603, 25.605, 25.607, 25.609, 25.625, 25.1301, 25.1309,25.1321, 25.1322, 25.1333, 25.1351, 25....	Certification Program AM1577003A-01.Instructions for Continued Airworthiness AM1557007A-01.Flight Manual Supplement AM1557008A-01.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10015249
10015253 (EASA.A.S.03698)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		747-100, 747-200	Installation of a Solid State Cockpit Voice Recorder and Control Unit inBoeing 747-100 and –200 series aircraft per ATLMaster Document ListMDL-11053-00001 at Issue 1 or later approved revisions.Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List Ref MDL-11053-00001or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The installation of this modification by third personsw...	09/11/2021	Active	10015253
10015254 (EASA.A.S.03700)	APTOZ EHF.	REV. 1		BOEING 757-200 757-200	Reconfigure seating layout to 52/10 Pax arrangement (VIP & Lounge)Rev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change/Repair Approval, CRA-757-2520-276, Revision B, 28/11/2008Continued Airworthiness Instructions, CAI-757-2520-276,Revision I/R,30/09/2008or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The installation of this modification by third personsw...	27/05/2025	Active	10015254

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015256 (EASA.A.S.03709)	ROEDER-PRAEZISION GMBH	REV. 1		SA226-T(B)	Installation of SLAR Surveillance System quick change roll.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- EASA approved „Übersicht der Dokumente“, Project No. SA226-NY-10117,Revision 1, dated 19 February 2009, or later approved revision.- EASA approved Airplane Flight Manual Supplement, Doc. No.SA226-NY-10117-08, Revision 2, dated 22 December 2008, or later approved revision.- Maintenance Procedures, 0...	1. Limited to Serial Number T294.2. With SLAR equipment installed, maximum cabin seating is 4 + 1.Operator Seat must not be occupied during take-off and landing.3. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherprev...	30/10/2017	Active	10015256
10015257 (EASA.A.S.03710)	ROEDER PRAEZISION GMBH	REV. 1		PA-34-200 /-200T/-220T	Replacement of existing Garmin COM/ NAV and existing Garmin GPS system by Garmin GNS 530w COM/NAV/GPS system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Approved Engineering Order, Doc. No. PA34-NY-10118-05, Revision 1,dated 26 January 2009, or later approved revision.- EASA approved Airplane Flight Manual Supplement, Doc. No.PA34-NY-10118-08, Revision 2, dated 27 January 2009 or later approvedrevision.- Approved Maintenance Procedure, Doc. No. PA...	1. Limited to “Single GNS” – Installation only.2. Prior to installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product...	30/10/2017	Active	10015257
10015261 (EASA.A.S.03719)	ACC COLUMBIA Jet Service GmbH	REV. 1	LBA STC 0279/2038	BRITTEN NORMAN BN-2B-26 ISLAND BRITTEN NORMAN BN-2B-20 ISLAND BRITTEN NORMAN BN-2A-27 ISLAND BRITTEN NORMAN BN-2A-26 ISLAND BRITTEN NORMAN BN-2A-21 ISLAND	Installation of Exhaust System Gomolzig BN2-606500.Rev. 1: Transfer to ACC COLUMBIA Jet Service GmbH		- According to Gomolzig Master Document List MDOCL_19057_rev0_2711 2008, or later Revisions.- To be operated and maintained in accordance with approved Gomolzig Documents Flight Manual Supplement SPOH_19057_rev0_27112 008and Installation Instruction II_19057_rev0_27112008 or later approved Revis...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by...	26/01/2022	Active	10015261
10015264 (EASA.A.S.03726)	JET AVIATION AG	REV. 2		GV	Iridium Antenna InstallationA dual Iridium antenna has beeninstalled on top of the fuselage located between Sta. 539.5& Sta. 554.5.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Iridium Antenna Installation In accordance with JET AVIATION Master DataList No.: BGLF553301-001 Rev I R, dated 14th December 2008 or laterapproved revisions.Instructions for Continued Airworthiness ref BGLF553301-150-01No AFMS has been generated for this modification.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.	15/06/2016	Active	10015264
10015265 (EASA.A.S.03727)	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	BOEING 747-400 SERIES 747-400	Installation of 3 AD Aerospace FV-0315 External Camera’s and 1 ADAerospace FV-0610 Video Transmission UnitRev. 1: transferred from Tenencia Ltd. to STC Twenty One Ltd.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval. Therequirements forenvironmental protection and the associatedcertified noise and/ oremissions levels of the product are unchanged and remain applicable tothis certificate/ approval w...	- Tenencia Ltd modification TEN 587 Issue 1- Tenencia Ltd. Instruction for Continued Airworthiness, Report TEN587/4, issue 1, shall be incorporated in the aircraft maintenancedocumentation .- Tenencia Ltd Operations Manual Supplement, report TEN 587/7 Iss. 1,shall be incorporated in the Aircraft Oper...	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.	14/11/2022	Active	10015265

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015280 (EASA.A.S.03806)	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)	REV. 2		206 & 210 (CENTURION)	Installation of Aspen Avionics EFD 1000 system (STC to cover now CessnaC-206 & newly added Cessna C-210 series)	FAR 23The Certification Basis for the original product remains applicable tothis certificate/ approval.Minor Change to EASA.A.S.03806 Revision 1 to include C-210 seriesThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appr...	Master Data List: Doc Number 801-049 Rev. BAFMS EFD 1000 System: Doc Number 801-071 Rev. BInstructions for continued airworthiness: Doc Number 801-085 Rev. B	Not valid if the Garmin 1000 ICS option is installed.	25/06/2010	Active	10015280
10015281 (EASA.A.S.03813)	AIRBUS S.A.S.		LBA STC NO. 2830/0009 ISSUE 1	A300C4-203	- Ref. to former Luftfarhrt Bundesamt STC 2830/0009 Issue 1- This EASA STC keeps the certificated design of the LBA STC2830/0009Issue 1, which consisted in the installation of structure and systemprovisions to change the loading system toan integrated side by side / single row system, and reflectsL...	- The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- See Certification Summary Document referenced in Associated TechnicalDocumentation section.- The certificated noise and/ or emissionsp...	- Daimler-Benz Aerospace Airbus Engineering Order Nr. SAA 03696A Issue1, dated 30 August 1996.Or later revisions of theabove listed documents approved by EASA	Limited to MSN 212	26/02/2010	Active	10015281
10015282 (EASA.A.S.03814)	AIRBUS S.A.S.		LBA STC NO.TA0466	A300F4-605R	- Ref. to former Luftfahrt Bundesamt STC TA0466- This EASA STC keeps the certificated design of the LBA STC TA0466,which consisted in theretrofit of the Lower Deck Cargo Compartment (LDCC) - Cargo LoadingSystem (CLS), andreflects the changes induced by the transfer of LBA STC TA0466 fromAirbus Deuts...	- The Certification Basis for the original product and the followingadditional oralternative airworthiness requirementsare applicable to thiscertificate/ approval- The certificated noise and/ or emissions levels of the originalproduct areunchanged and remain applicable to this certificate/ approval...	- Certification Summary Document : EAA2/433/010/255/COS Issue 01- Airbus Engineering Order Nr. FDX 128/99A, Issue 06Or later revisions of the above listed documents approved by EASA	Limited to the aircraft model operated by Federal Express (FedEX)	26/02/2010	Active	10015282
10015283 (EASA.A.S.03816)	AIRBUS S.A.S.		LBA STC NO. TA0217	A319-132	Equipment / Furnishing - Passenger Compartment - VIP-Kit for A319Kharafi Group KuwaitRevision to Luftfahrt Bundesamt STC TA0217 Issue 2.This EASA STC keeps the certificated designof the LBA STC TA0217 issue2, which consisted in the aircraft VIP cabin reconfiguration, andreflects the changes induced...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.See Engineering Order referenced in Associated Technical Documentationsection.The certificated noise and/ or emissions levels of the orig...	DASA Engineering Order Nr. K9G003/99A, Issue 2 or later revisions of theabove listed documents approved by EASA.	Limited to MSN 913.	12/05/2010	Active	10015283
10015284 (EASA.A.S.03817)	AIRBUS S.A.S.		LBA STC NO. TA0265	A319-133	Equipment / Furnishings - Passenger Compartment - Install cabinfurnishing for Daimler Chrysler AviationRevision to Luftfahrt Bundesamt STC TA0265This EASA STC keeps the certificated design of the LBA STC TA0231 whichconsisted in the aircraft cabin reconfiguration, and reflects thechanges induced byA...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.See Engineering Order referenced in Associated Technical Documentationsection.The certificated noise and/ or emissions levels of the orig...	DASA Engineering Order Nr. L4C015/99A, Issue 1or later revisions of the above listed documents approved by EASA	None.	12/05/2010	Active	10015284
10015285 (EASA.A.S.03818)	AIRBUS S.A.S.		LBA STC NO. TA0269	A319-133	Equipment / Furnishing - Passenger Compartment - Install baggagecontainer for Daimlerchrysler Aviation.Revision to Luftfahrt Bundesamt STC TA0269 Issue 2.This EASA STC keeps the certificated design of the LBA STC TA0269 Issue2 which consisted in the installation of 2 ATR containers for luggageand th...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.See Engineering Order referenced in Associated Technical Documentationsection.The certificated noise and/ or emissions levels of the orig...	DASA Engineering Order Nr. C8A00100A, Issue 2.or later revisions of the above listed documents approved by EASA	Limited to MSN 1053	12/05/2010	Active	10015285
10015286 (EASA.A.S.03819)	AIRBUS S.A.S.		LBA STC NO. TA0231	A320-232	Equipment/ Furnishings - Passenger Compartment - VIP-kit for A320 Syria.Revision to Luftfahrt Bundesamt STC TA0231.ThisEASA STC keeps the certificated design of the LBA STC TA0231 whichconsisted in the aircraft cabin VIP reconfiguration, and reflects thechanges induced by the transfer of LBA STC TA...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Deviation to theCertification requirements :- JAR 25.785 h)1),,- JAR 25.853a)- JAR 25.813 e),,,,- JAR 25.853 a) 1)See Engineering Orders...	DASA Engineering Order Nr. SYR037/98Aor later revisions of the above listed documents approved by EASA	Limited to MSN 886, 918, 1032, and 1075	12/05/2010	Active	10015286

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015287 (EASA.A.S.03820)	AIRBUS S.A.S.		LBA STC NO. TA0228	A330-223	(Ref. to former Luftfarhrt Bundesamt STC TA0228)This EASA STC keeps the certificated design of the LBA STC TA0228 whichconsisted in the aircraft cabin reconfiguration, and reflects thechanges induced by the transfer of LBA STC TA0228 fromDaimlerChryslerAerospace to Airbus SAS.	The Certification Basis for the original product remains applicable tothis certificate/ approvalSee Certification Program Document referenced in Associated TechnicalDocumentation section.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to thi...	DASA Engineering Order Nr. SWR010/99A Issue 3or later revisions of the above listed documents approved by EASA	Limited to MSN 240, 249, 253, 255, 262, 275, 288, 291, and 366	31/08/2010	Active	10015287
10015288 (EASA.A.S.03821)	AIRBUS S.A.S.		LBA STC TA0261	A310-304	GLARE demonstrator panel installationRevision to Luftfahrt Bundesamt STC TA0261.This EASA STC keeps the certificated design of the LBA STC TA0261, whichconsisted in the installation of the Glare demonstrator panel fortesting purpose, and reflects the changes induced by the transfer of LBASTC TA0261...	The Certification Basis for the original product remains applicable tothis certificate/ approval.See Certification Program Document referenced in Associated TechnicalDocumentationsection.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to th...	Certification Program : EAA484/530/001/GLARE, dated 17 March 1999- Glare panel installation :Daimler-Chrysler AerospaceAirbus Engineering Order Nr. GAF06698A, Issue02- Glare panel replacement :Airbus Engineering Order Nr. GAF030/08A, Issue 01or later revisions of the above listed documents approved...	Limited to MSN 484.	12/05/2010	Active	10015288
10015290 (EASA.A.S.03825)	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV. 1		A320	Installation of 148 PAX Layout of Passenger Accommodation (LOPA)This STC is revised in order to remove the EWIS Limitation	- Type Certification Basis in accordance with the TCDS No. A. 064 issue 8that includes CRI H-01 / Special Condition "Enhanced AirworthinessProgramme for Aeroplane System -ICA on EWIS"The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the ori...	- Compliance Document Summary Sheet, ref. doc. BAC/ABUS/020, Issue 5,dated 30th August 2012- Compliance Check List, ref. doc. CCL/001/628, Issue 5, dated 30thAugust 2012- Instruction for Continued Airworthiness, ref. doc. ICA/072/628, Issue3, dated 30th August 2012or later revisions of the above lis...	none	12/11/2012	Active	10015290
10015291 (EASA.A.S.03830)	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		200C	BCA112 revision 2, dated 15 July 2012 : underwings, rooftopand PODantennas installation and belly antennas relocation.Major Change of STC EASA.A.S.03830.	The Certification Basis for the original product remains applicable tothis certificate / approval.The certificated noiseand/or emissions level of the original productare unchangedandremain applicable to this certificate / approval.	BCA112-04: Airplane Maintenance Manual Supplement, revision2 dated 15July 2012;BCA112-05: Airplane Flight Manual Supplement, revision 1 dated 19 March2003;or later revisions of the above listed documents approved by EASA.	Limitation to sn BB-1473	25/07/2012	Active	10015291
10015297 (EASA.A.S.03847)	365 AEROSPACE DDS LIMITED	REV. 5		A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-215/-216/-231/-232/-233 A320-111/-211/-212/-214 A319-115/-131/-132/-133 A319/-111/-112/-113/-114 A318-111/-112/-121/-122	Installation of an Enhanced Surveillance Mode S SystemRev. 5: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 1225.869, 25.1301, 25.1307, 25.1309, 25.1321, 25.1333, 25.1351, 25.1353,25.1355, 25.1357, 25.1431, 25.1529, 25.1581, 25.1701, 25.1703, 25.1705,25.1707, 25....	Aerospace Design & Engineering Consultants Flight Manual Supplement FMA-0544-062 Revision 1 dated 13th March 2009Aerospace Design & Engineering Consultants Flight Manual Supplement FMA-1374-085 Revision 1Aerospace Design & Engineering Consultants Flight Manual Supplement FMA-1374-086 Revision 1Aeros...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	05/08/2019	Active	10015297

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015302 (EASA.A.S.03866)	E A D AEROSPACE AIRWORTHINESS	REV. 3		A340	Installation of Advanced Mission Display System Phase A- AMDS/ARevision of the EASA STC EASA.A.S.03866 Revision 2 to remove EWISlimitation	Certification Basis in accordance with EASA Type Certificate Data SheetsA.015.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI H-01 "Enhanced Airworthiness Programme for Aeroplanel...	- Master Drawing List, ref. 01274-EAS-A-MDL, Revision K, dated 26thNovember 2010- Compliance Check List, ref. 01274-EAS-A-CCL-01, Revision B, dated 18thJune 2009- Airplane Flight Manual Supplement, ref. 01274-EAS-A-AFM-01, RevisionD, dated18th June 2009- Declaration of Compliance, ref. 01274-EAS-A-...	Not applicable	02/12/2010	Active	10015302
10015303 (EASA.A.S.03868)	ROEDER PRAEZISION GMBH	REV. 1		A319-112	Change of the Cabin Configuration (150 Pax).The cabin configuration will be changed to increase the certified 145pax configuration to a 150 pax configuration with minimum Cabin Crew of3 Flight Attendants.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Report, ref. doc. A319-CR25-03-2009, Issue 1, dated 17thMarch 2009.- Design Modification Document, ref.doc. A319-DMD25-03-2009, Issue 1,dated 17th March 2009.- Compliance Record Document, Issue 2, dated 5th May 2009.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.The installation of this modification by third persons is s...	15/06/2018	Active	10015303
10015305 (EASA.A.S.03894)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		2. B200, B200C, B300, B300C 1. 200, 200C, 300, 300LW	Dual TDR-94D Mode S ELS/EHS Transponder System Upgrade, andoptional forADS-B	The Certification Basis of the original product and the followingadditional / alternative airworthiness requirements are applicable tothis change.For the change CS-23, Amdt. 2, has been elected to comply with wherepossibleThe certificated noise and/ or emissions levels of the original productare unc...	EASA approved Engineering Order, Doc. No. 2053779-EO, issue2, dated21-Feb-2012, or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2053779-AM-A,Issue 1, dated 27-Apr-2009<(>,<)> or later approved issue, for ELS onlyEASA approved Aircraft Flight Manual Supplement, Doc.I...	This change is limited to the configuration of aircraft / equipment typeas listed under Chapter 4. in EASA approved Engineering Order, Doc. No. 2073065-EO, Issue 1, dated 22-Mar-2012, or later approved issue forinstallations without ADS-B, or Issue 2, dated 21-Feb-2012, or laterapproved issue for ins...	30/03/2012	Active	10015305
10015311 (EASA.E.S.01001)	HÉLICOPTÈRES GUIMBAL	REV. 3		O-360-J2A	Installation of an electronic ignition system, an a/c compressor and anoil filter adaptor<(>,<)> and Increase of the Take-off Power (5 min) to119 kW (160 HP), in accordance with Hélicoptères Guimbal Installation,Operator's and Maintenance Manual J45-001 and Type Design DefinitionDoc. No. J45-002	CS-E, issue 1 dated 24 October 2003, for all affected areas, asidentified in document Hélicoptères Guimbal No. J00-002	HG Manual J45-001 Issue 5or later revisions of the above listed documents approved by EASA.	Limitations: The data in the FAA TCDS E-286 remains valid, except thefollowing:Rating:Take-off (5 min.), at sea level pressure altitude:119 kW (160 HP) at 2400 rpm (27.9 inHg) to 2700 rpm (26.3 inHg) Dimensions:Overall Height: 602 mm (23.7 in.)Fuels:Aviation Gasoline, 100 or 100LL per ASTM D910, B95/...	27/04/2017	Active	10015311
10015314 (EASA.IM.A.S.00184)	B/E AEROSPACE, Inc.	REV. 1	FAA ST00221AT	727-100, 727-200	Installation of a Digital Flight Data Recorder Upgrade from6 to 11channels.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Engineering Report No. 92MJT.003R-1, Revision B, dated May 4, 1993.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015314
10015315 (EASA.IM.A.S.00185)	B/E AEROSPACE, Inc.	REV. 1	FAA ST02006AT	727-100, 727-200	Installation of a Honeywell (formally Allied Signal) 18 Channel FlightData Recorder (Upgrade) for Aircraft not containing a Flight DataAcquisition Unit.Revision 1 transferred fromEMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EMTEQ (formally Avitas) Engineering Report No. 99AMJT.040R-1, Rev. C,dated November 23, 2005.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015315

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015316 (EASA.IM.A.S.00188)	B/E AEROSPACE, Inc.	REV. 1	FAA ST02869AT	767-300	Installation of a passenger cabin interior arrangement (290TC).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EMTEQ Engineering Master Drawing List (MDL) No. ANST-048-MDL, RevisionC, dated May 27, 2004.Instructions for Continued Airworthiness, EMTEQ Engineering reportANST048-CAW, dated April 5, 2004.	Limited to 767-33A, Serial No. 25535.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	02/03/2016	Active	10015316
10015318 (EASA.IM.A.S.00254)	GLOBAL AIRWORKS, Inc.	REV. 2	FAA STC ST01626LA	CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2C10 (RJ 700/701/702) CL-600-2B19 (RJ SERIES 100)	Installation of AirWorks Cockpit Door Surveillance System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AirWorks Airplane Flight Manual Supplement Document No. AFMS230015<(>,<)> Revision Original dated 2 April 2004<(>,<)> or later approved revision is required as part of this modificationor AirWorks Airplane Flight Manual Supplement DocumentNo.AFMS230099 <(>,<)> Revision A dated 24 November 2015<(>,<)...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/02/2016	Active	10015318
10015321 (EASA.IM.A.S.00269)	S-TEC CORPORATION	REV. 2	FAA STC SA8906SW-D	PA-28-236 PA-28-181, PA-28-201T PA-28-151, PA-28-161	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem Model ST-568.	The Certification Basis for the original product remains applicable tothis certificate/ approval	- FAA/DAS Approved S-TEC Bulletin No. 668 Revision 3, dated21 July 2001or later revision- FAA/DAS Approved S-TEC Master Drawing List No. 92748 Revision C, dated21 July 2001 or later revision- FAA/DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891144, dated 10 F...	None	14/09/2010	Active	10015321
10015323 (EASA.IM.A.S.00279)	AVIATION PARTNERS BOEINGWINGLETS COMPANY, LLC	REV. 18	FAA STC ST00830SE	737-700/-800/-900/-900ER	Installation of Aviation Partners Boeing winglets:-Blended Winglets design-Split Scimitar Winglets designRevision 1: approved 737-800 performance data when CFM56-7B27 enginesare installedRevision 2: approved 737-800 performance data when CFM56-7B27 engineswith bump rating are installedRevision 3: ap...	Blended WingletsThe baseline of the certification basis forthe approvals is as follows:-JAR 25 Change 14, effective 27May 1994-Orange Paper 96/1, effective 19 April 1996-JAR AWOChange 2, effective 1 August 1996-JAA IL-23 RVSM, effectiveApril 1994737-700: "-1","-2", "-3a", "-3b", "-3c"Additionall...	All relevant manuals and Master Drawing Lists are referenced in APB'sdocument AP37.1-E620 "Document List737-NG with Blended or Split Scimitar Winglets (EASA Design Standards &Continuing Airworthiness Manuals)"rev. F or later revisions of the above listed documents approved by EASAin accordance with2...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/10/2019	Active	10015323
10015324 (EASA.IM.A.S.0028)	SAFRAN CABIN INC.	REV. 4	FAA STC ST01415LA	CL-600-2E25/ CL-600-2D15 CL-600-2C10/ CL-600-2D24	Flight Deck Access System (FDAS) Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	MDL 9391000, Revision W, dated 26 October 2010 or latter FAA approvedrevision.For Model CL-600-2C10 Airplane Flight Manual Supplement No.939-1-AFMS-001 dated 5 December 2002 or later FAA approved revision.Model CL-600-2D24 is added with Revision 1<(>,<)> dated 13 March 2003.For Models CL-600-2C10, C...	Equipment Functional Check Intervals as defined in FAA approved C & DInteriors Report CDR9397-69, Revision A, dated November 8, 2002,"Certification Maintenance Requirements", or any later FAA approvedrevision, shall not be extended. Later revisions to C & D AerospaceReport CDR9397-69 may be used onl...	09/05/2019	Active	10015324

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015330 (EASA.IM.A.S.00323)	LEARJET Inc.	REV. 5	FAA STC SA8168NM-D	CL-600-2B16 (CL-604)	Installation of a Complete Custom Aircraft Interior	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Modification Applicability List CC-0001-TUS, Revision DM dated 23September 2008-MDL CC54495000, Revision A, (for MSN 5449)-MDL DC55105000, Revision B, (for MSN 5510)-MDL DC55235000, Revision E, (for MSN 5523)-MDL DC55395000, Revision E, (for MSN 5539)-MDL DC55705000, Revision C, (for MSN 5572)-MDL-...	Restricted to MSN 5449, 5510, 5523, 5539, 5572, 5577, 5585	04/03/2010	Active	10015330
10015333 (EASA.IM.A.S.00354)	VISIONSAFE LLC	REV. 16	FAA ST00892LA	SEE FAA AML	Installation of Emergency Vision Assurance System (EVAS)Validation of FAA STC ST00892LA Approved Model List as applicable forthe EASA approved models.Rev. 9 adds BOEING 777-200/-300/-300ER/-200LR, 777F; 757-200/-200PF;MD-11 and MD-11 F.Rev. 10 adds Gulfstream G280 and Dornier Model 328-100,F.Rev. 11...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Visionsafe Corporation Master Drawing Lists and Airplane Flight ManualSupplements required for the modification are listed on FAA ApprovedModel List No. ST00892LA<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implementati...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	02/07/2025	Active	10015333
10015337 (EASA.IM.A.S.00364)	BEECHCRAFT CORPORATION	REV. 2	FAA SA2824SW-D	HAWKER HS 125-700 HAWKER 800, 800XP, 850XP BAE 125 SERIES 800A	Installation of a Long Range Oxygen System	FAA CAR 4b <(>&<)> FAR Part 25	Master Drawing List 125-012 Revision T or later approved revisionOperation in accordance with Flight Manual Supplement 800-250 Rev R6 orlater approved revision.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	18/02/2010	Active	10015337
10015353 (EASA.IM.A.S.00601)	WIPAIRE Inc.	REV. 4	FAA STC SA01795CH	AT-802, AT-802A	Installation of Wipaire Model 10000 Amphibious floats per Wipaire Inc.STC SA01795CH, FAA approved July 8, 2011.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No.SA01795CH amended July 8, 2011.For Model AT-802A: Installation of Wipaire Model 10000 Amphibious Floatsin accordance with Wipaire, Inc. Installation Drawing No. 7D1-4251, NoRevision, dated January 13, 2003. Operations with the floats removed arepermitted when the aircraft is modified in a...	FAA STC No. SA01795CH "Limitations and Conditions", amendedJuly 8,2011.1. FAA approved Airplane Flight Manual Supplements:AT-802A amphibian, dated March 13, 2003AT-802A landplane, dated October 7, 2003AT-802 amphibian, dated September 29,2008AT-802 landplane, dated September 29, 2008AT-802A amphib...	31/08/2011	Active	10015353
10015374 (EASA.IM.A.S.01031)	SECURAPLANE TECHNOLOGIES, Inc.	REV. 2	TCCA SA04-3 ISSUE 3	ATR 72-201, ATR 72-202. ATR 72-101, ATR 72-102, ATR 42-300, ATR 42-320,	Installation of Hawker sealed Lead-Acid batteries.This STC installs Hawker sealed Lead - Acid batteries P/N 9750W0538 (24V - 40 Ah) and P/N 9750W0350-5 (24 V - 18 Ah).The Revision1 retains the certificated design of the EASA.IM.A.S. 01031and capture the transfer of STC ownership from Stephen D. MacS...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, ref. 170-0403-01 Revision L, dated 26 Feb. 2009Certification Data List, ref : 170-0410-01 Revision F,dated 29 Oct 2008Instruction for Continued Airworthiness, ref : 290-0251-01 Revision D,dated 26 February 2009or later revisions of the above listed documents approved by EASA inacc...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	27/11/2014	Active	10015374

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015404 (EASA.IM.A.S.01115)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02780AT	757-200	Installation of Honeywell Mark V Enhanced Ground Proximity WarningSystem (EGPWS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Flight Manual Supplement EMTQ-015B-FMS Initial Release or laterapproved revisionor later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/or the Technical Implementation Procedures of EU/USA Bilater...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	02/03/2016	Active	10015404
10015405 (EASA.IM.A.S.01116)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02761AT	MD-81/-82/-83/-87/-88 767-200/-300 757-200	Installation of Honeywell RESCU 406AF Emergency Locator Transmitter (ELT).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EMTQ Engineering Master Drawing List EMTQ-030-MDL Revision B datedJanuary 27 2004	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015405
10015407 (EASA.IM.A.S.01118)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02896AT	A321-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-111/-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of a Kannad Model 406-AF Emergency Locator Transmitter (ELT).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing No. 2-23982-001 Revision B dated July 7, 2004	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015407
10015408 (EASA.IM.A.S.01122)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02896AT	FOKKER F.28 MARK 0100	Installation of a Kannad Model 406-AF Emergency Locator Transmitter(ELT) in accordance with FAA STC ST02896AT dated 22/07/05 or laterEASA-approved revision.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Data package containing the following documents, and additionalsupporting data:1. Master Drawing List for a KANNAD 406 AF Emergency Locator Transmitter(ELT) installation on various fleet types, EMTEQ document 2-23982-001,Revision E.2. Structural Substantiation Report ELT Antenna Installation in Fokk...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015408
10015416 (EASA.IM.A.S.01138)	GLOBAL AIRWORKS, Inc.	REV. 1	FAA STC ST01739LA	777-200, 777-300, 777-300ER	Installation of AirWorks Cockpit Door Surveillance System and AdvancedCockpit Door Surveillance System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Airworks AFM Supplement Document Number AFMS230089 Revision Originaldated January 21, 2005 or AFMS230034 Revision Original dated June 04,2015- Airworks Weight & Balance Report Ref MDL230089 Document No WBR230089Revision A dated August 20, 2004 or WBR230034 Revision B dated March 16,2015or later re...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/03/2016	Active	10015416
10015426 (EASA.IM.A.S.01159)	AVIONICS GROUP INC.	REV. 1	FAA ST02198AT	757-200, 757-200PF	Installation of a Teledyne Digital Flight Data Acquisition Unit, PartNumber 2233000-811	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateAs per the TCDS plus:CRI H-01: ICA on EWISThe requirements for environmental protectionand the associatedcertificated noise and/ or emissions level...	Avionic Master Drawing List AG-31-1058.MDL, Revision B, 10/07/2007or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	08/02/2011	Active	10015426

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015430 (EASA.IM.A.S.01164)	STG AEROSPACE Inc.AKA SAFTGLO, Inc.	REV. 1	FAA STC ST02529AT	ATR 72-212/-212A ATR 72-101/-102/-201/-202/-211 ATR 42-200/-300/-320/-500	Installation of SafTGlo Photoluminescent Floor Proximity EmergencyEscape Path Marking System (PFPEEPMS).(Validation of FAA STC ST02529AT)The STC installs a photoluminescent aisle path marking system(PFPEEPMS).This revision 01 adds ATR 72 aircraft models in the STC applicability.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-SafTGlo Master Drawing List, ref: P12-2 Revision C, dated 23 April 2007-EASA Aircraft Flight Manual Supplement, ref: EASA P12-11, dated 14April 2011-Instruction for Continued Airworthiness, ref: P12-10 Revision C, dated23 April 2007or later revisions of the above listed documents approved by EASA	None	15/04/2011	Active	10015430
10015439 (EASA.IM.A.S.01179)	STG AEROSPACE Inc.AKA SAFTGLO, Inc.	REV. 1	FAA ST02406AT	F28 MARK 4000 F28 MARK 3000 F28 MARK 2000 F28 MARK 1000 F28 MARK 0100	Installation of SAF-T-GLO photoluminescent floor proximity emergencyescape path marking system (FPEEPMS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- STG Aerospace drawing SG-F28, revision D.- STG Aerospace Master Drawing List (MDL) Report Number H61-2, revisionF.- STG Aerospace Instructions for Continued Airworthiness H61-10,revision E.- STG Aerospace Airplane Flight Manual Supplement H61-11, revision A- STG Aerospace Compliance Inspection Pro...	The photoluminescent FPEEPMS is only eligible for installation onaircraft model numbers with interior arrangements approved in the STGAerospace Master Drawing List (MDL) Report Number H61-2, revision F,incorporating STG Aerospace drawing SG-F28, revision D<(>,<)> or laterrevisions of these documents...	03/11/2014	Active	10015439
10015530 (EASA.IM.A.S.01409)	ROCKWELL COLLINS, Inc.	REV. 3	FAA STC ST00673WI-D	SEE EASA APPROVED MODEL LIST	Modification of VHF-22A/VHF-22B VHF COMMVHF COMM Receiver Transmitter with CTL-22 Control Pro Line II SystemInstallation to a Collins VHF-22/ VHF-22D VHF COMM Receiver Transmitterwith CTL-22C 8.33 kHz Pro Line II System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Collins Installation Instructions as listed on the MDL defined in theApproved Model List (AML)or later revisions of theabove listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures ofU...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/01/2017	Active	10015530
10015539 (EASA.IM.A.S.01423)	PRECISION CONVERSIONS, LLC	REV. 1	FAA STC ST1529SE	757-200	Conversion of a Boeing 757-200 series passenger configuration to afreighter configuration (including main deck cargo door, crew entrydoor, interior, and associated systems)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI D-02 Carriage of "Supernumeraries" in Flight CompartmentJAR 25 Change 15 withthe following paragraphs at later amendments:CS 25 Amendment...	Federal Aviation Administration (FAA) Statement of Compliance (SOC)120S-14-449 dtd. Jul 24, 2014Master Drawing List (MDL) PC-0118-09, Revision DM, dated May 23, 2014Flight Operations:Airplane Flight Manual Supplement, Document OL0181, OEMSN ( )Airplane Weight and Balance and Loading Manual Supplemen...	-See Precision Conversions, LLC Drawing Number 007B1004 foreligibleairplane serial numbers-This modification is to be installed concurrently with EASA STCEASA.IM.A.S.01536 (original FAA STC ST01490SE)-Compatibility between this STC and the EASA validated FAA STC ST01518SE(Aviation Partners Boeing /...	30/07/2014	Active	10015539
10015542 (EASA.IM.A.S.01426)	ISRAEL AEROSPACE INDUSTRIES, LTD.IAI	REV. 5		B737-300	Conversion from Passenger configuration to Special Freighter (SF),Special Freighter with Rigid Barrier and to Quick Change (QC)configuration and approval of increased weight limitationsSummary of EASA STC Revisions:Original EASA approval: CAA UK STC No CAA. 21NE1.00092STC EASA.IM.A.S.01426 Revision 1...	EASA STC Certification Basis, as recorded in EASA CRI A-OI,dated2007-11-02The Certification Basis for the original product remains applicable tothis certificate/approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ a...	- Master Document List TR 365-2100-92100 Revision "BB", dated October28, 2010- List of added converted airplanes TR 365-00-00-99312 Revision "AE"dated September 18, 2007or later revisions of the above listed documents approved by EASA	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.If the holder agrees to permit another person to use this certificate t...	23/04/2012	Active	10015542

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015551 (EASA.IM.A.S.01445)	LIFEPORT, LLC	REV. 2	FAA STC SA00273WI	SEE FAA AML SEE EASA APPROVED MODEL LIST	Installation of Stretcher, Patient Loading, and Support systemRev. 2 adds the Textron model B200GT to the to the subject's STC'sapproved model list.		LifePort, Inc. Master Drawing List 520-9000, Revision C, dated June 27,1994, or later FAAapproved revision.Airplane Flight Manual Supplement (AFMS) 35 and Supplement No. 5 with aFAA Approval date of December 28, 1994, or later FAA approvedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/02/2022	Active	10015551
10015558 (EASA.IM.A.S.01455)	S-TEC CORPORATION	REV. 2	FAA SA09628AC	690D, 695, 695A, 690C	Installation of the S-TEC 01304 Digital Flight Control System (DFCS), inaccordance with Master Data List 921128, rev. 12.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- S-TEC Master Data List 921128, Rev. 12, dated May 21st, 2014- Airplane Flight Manual Supplement No. 892134, Rev. 3, dated May 21st,2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or t...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/07/2016	Active	10015558
10015560 (EASA.IM.A.S.01457)	FLINT AERO, INC.	REV. 1	FAA STC SA3232NM	TU206F, TU206G, U206F, U206G 206H, T206H	Installation of 14.9 gallon usable fuel-contained in lightning-resistantwing tip tanksRevision 1 adds the model TU206F.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase.	Installation in accordance with FAA sealed Flint Aero, Inc.MasterDrawing List FALS206, no revision, dated March 4, 1986.For Operation at Increase in the takeoff gross weight (SeeLimitations)from 3,600 to 3,800 pounds for landplane, floatplane, amphibian, and skiplane versions of noted models. TheA...	Any FAA STC's referenced below that may be used in conjunction with thisSTC, are not automatically accepted by EASA it is the Aircraft Operatorsresponsibility to establish they are EASA approved or accepted prior toinstallation.For EU registered aircraft, if operation at Increased Gross Weights (MTOW...	21/04/2020	Active	10015560
10015566 (EASA.IM.A.S.01470)	B/E AEROSPACE, Inc.	REV. 1	FAA STC SA03020AT	BAE JETSTREAM 3201 BAE JETSTREAM 3101	Installation of Sandel Model ST3400 Terrain Awareness and Warning System (TAWS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approv...	1. EMTEQ Engineering Approved Model List (AML) Document No. 2-25975-002Rev. IR dated January 14 2005<(>,<)> or later approved revision.2. EMTEQ Engineering AFM Supplement DocumentNo. 2-25975-909 Rev. IRdated January 14 2005 or later approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015566
10015568 (EASA.IM.A.S.01475)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02793AT	BEECH 1900D	Installation of Honeywell Mk VI Enhanced Ground Proximity Warning System (EGPWS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. EMTEQ Engineering Master Drawing List EMTQ-028-MDL, Revision C, dated7 July 2004 or later FAA approved revision.2. FAA Approved Flight Manual Supplement for Raytheon Aircraft CompanyModel 1900D Aircraft with Honeywell Model MK VI EGPWS, EMTEQ DocumentNo. EMTQ-028-FMS, Revision IR, dated February...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015568
10015569 (EASA.IM.A.S.01476)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03022AT	EMB-120	Installation of Sandel Model ST3400 Terrain Awareness and Warning System (TAWS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. EMTEQ Engineering Master Drawing List (MDL) 2-25979-001,Rev. A,dated January 8, 2005.2. FAA Approved Flight Manual Supplement (AFMS) for Embraer EMB-120Series Aircraft, EMTEQ Document No. 2-25979-001 Rev. IR, dated January20, 2005.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015569

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015570 (EASA.IM.A.S.01477)	B/E AEROSPACE, Inc.	REV. 1	FAA STC SA02821AT	BEECH 1900D	Installation of Sandel Model ST3400 Terrain Awareness and Warning System (TAWS), with optional capability as a Traffic Collision Avoidance System (TCAS) Control Display Unit (CDU) or Radio Magnetic Indicator (RMI).Revision 1 transferred fromEMTEQ to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	1. EMTEQ Engineering Master Drawing List EMTQ-036-MDL, Revision B, datedMarch 19, 2004 or later FAA approved revision.2. FAA Approved Flight Manual Supplement (AFMS) for Raytheon AircraftCompany Model 1900 Series Aircraft installed as a TAWS/TCAS CDU, EMTEQDocument No. EMTQ-036A-FMS, Revision IR, da...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015570
10015571 (EASA.IM.A.S.01478)	B/E AEROSPACE, Inc.	REV. 1	FAA ST03003AT	767-200, 767-300	Installation of a Honeywell Mark V Enhanced Ground Proximity WarningSystem (EGPWS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplements (AFMS) for Boeing 767 series aircraft, EMTEQDocument No. 2-26425-908, Rev. JR, dated December10, 2004or later revisions of the above listed documents approved by EASA.EMTEQ Engineering Master Drawing List (MDL) 2-26425-001, Rev. A, datedDecember 05, 2004.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015571
10015576 (EASA.IM.A.S.01487)	AVIATION FABRICATORS, Inc.	REV. 1	FAA SA2629CE	2. 300, 300LW, B200, B200C 2. 200, 200C, B200CT, B200T 1. B300, B300C 1. B200,B200C, B200GT, B200CGT	Installation of two place side-facing divan.	FAR 23	Aviation Fabricators Drawing Number D10002B approved on 30 MAY 1990 orAviation Fabricators STC data package AF-113, Rev. D or later approvedrevision.	1) Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2) The installation of this modification by third person...	08/10/2009	Active	10015576
10015577 (EASA.IM.A.S.01488)	AVIATION FABRICATORS, Inc.	REV. 1	FAA SA00622WI	SEE APPROVED MODEL LIST	Installation of shoulder harness kit	CAR 3 and FAR 23	Installation in accordance with Aviation Fabricators, Inc FAA approvedDrawing List AF-203 F, dated 6 October 2009 or later approved revision.	None	11/12/2009	Active	10015577
10015600 (EASA.IM.A.S.01536)	AIM AVIATION RENTON, INC.	REV. 1	FAA ST01490SE	757-200 SERIES	Installation of a flight deck lavatory.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. AIM Aviation Inc. Master Data List AIM-DL-14485 RevisionA, dated 17December 2004, or later FAA approved revision. 2.AIM Aviation, Inc. Drawing List AIM-DL-14485, Revision A, dated 17December 2004, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Precision Conversions Supplemental Type Certific...	08/04/2020	Active	10015600
10015627 (EASA.IM.A.S.01579)	AAR CARGO SYSTEMS	REV. 1	FAA STC ST02021CH	MD-11	Installation of a Main Deck Cargo Handling System (FAA STC ST02021CH)	The Certification Basis for the original product remains applicable tothis certificate/ approval	AAR Report 1826 Instruction for Continued Airworthiness	None	10/12/2010	Active	10015627
10015635 (EASA.IM.A.S.01591)	LB AIRCRAFT ENGINEERING LLC	REV. 2	FAA ST02959AT	737-300/-400/-500	Installation of Collins Model 700 High Frequency (HF) CommunicationSystem and HF AntennaRevision 1: Transfer of STC 10015635 (IM.A.S.01591) from ARC AvionicsCorporation to AIRCRAFT RADIO & AVIONICS, LLCRevision 2: STC Transfer from "Aircraft Radio & Avionics, LLC" to "LBAircraft Engineering, LLC".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-ARC Avionics Master Drawing List, Ref. ARC-HF. 001-MDL, Rev. E dated 19December 2005-ARC Avionics Airplane Flight Manual Supplement, Ref. ARCHF.001-FMS,dated 26 May 2006or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revi...	As per Airplane Flight Manual Supplement, Ref. ARCHF.001-FMS.Prior to installation of this design change it must be determined thatthe interrelationship between this design changeand any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of...	01/03/2024	Active	10015635

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015638 (EASA.IM.A.S.01595)	B/E AEROSPACE, Inc.	REV. 2	FAA ST02929AT	MD-88/-90, MD-11 SERIES DC-9-80, DC-10-30 SERIES DC-9-10/-20/-30/-40/-50 SERIES BAE JETSTREAM MODELS 3101/3201 777-200 SERIES 767-200/-300 SERIES 757-200 SERIES 747-200F/-300/-SP/-400 SERIES 747-100/-200B/-200C SERIES 737-500/-600/-700/-800 SERIES 737-100/-200/-300/-400 SERIES 727-100/-200 SERIES	Installation of an ARTEX Model C406-1 ELT Emergency LocatorTransmitter (ELT).	See FAA Approved Model List (AML) No. 2-22566-002 Rev. K, 12/08/2011.	See FAA Approved Model List (AML) No. 2-22566-002, Rev. K, 12/08/2011.	The STC is valid for those aircraft types and models approved by EASAwithin the FAA Approved Model List (AML) No. 2-22566-002, Rev. K,12/08/2011.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed de...	02/03/2016	Active	10015638
10015642 (EASA.IM.A.S.01606)	BOMBARDIER INC.	REV. 1	TCCA STC C-LSA05-391/D	BD-700-1A10	Aircraft Completion, 13 Passenger Interior Configuration	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	- EASA STC No. EASA.IM.A.S.01606- Transport Canada SoC ref.C-10-0444 dated 25 June 2010- Transport Canada STC No. C-LSA05-391/D Issue 1 dated 22 December 2005- Aero Consulting Services Master Drawing List E659000 Revision D dated3 June 2010- Flight Manual Supplement G-FM25000134 Rev. N/C-Maintenan...	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.2. The installation is limited to S/N 9169	07/07/2010	Active	10015642
10015645 (EASA.IM.A.S.01609)	B/E AEROSPACE, Inc.	REV. 2	FAA ST02019AT	767-300	Installation of Passenger Cabin Interior Arrangement.Revision 2 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avitas Engineering Master Drawing List (MDL) No. 99GECS.019MDL RevisionE, 17th February 2000.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015645
10015647 (EASA.IM.A.S.01620)	ASTECH ENGINEERED PRODUCTS Inc.	REV. 1	FAA STC ST01802LA	AIRBUS A321 AIRBUS A320 AIRBUS A319 AIRBUS A318 A318_A319_A320_A321	Replacement CFM56-5B Inlet Barrel Lower Panel Assembly (Part Number030-13001-1) Replacement CFM56-5B Inlet Barrel LowerPanel Assembly(Part Number 030-13001-1) Rev. 1: Transfer from "GKN Aerospace Chem-Tronics, Inc." to "AstechEngineered Products, Inc."		Master Drawing List ref MDL030-13014 revision D, dated April 20, 2005<(>,<) >or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/08/2024	Active	10015647
10015654 (EASA.IM.A.S.0163)	ALAMO ENGINEERING GmbH	REV. 4		HS.125 SERIES 700B HS.125 SERIES 700A/B HS.125 SERIES 700A	Installation of a Rockwell Collins TCAS-4000 Traffic Alert and CollisionAvoidance System (TCAS-II).Revision 2: Transferto 328 DESIGN GmbHRevision 3: Transfer to 328 SUPPORT SERVICES GmbHRevision 4: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 16:JAR 25.301, JAR 25.303, JAR 25.305, JAR 25.307, JAR 25.571, JAR 25.603,JAR 25.605,JAR 25.607,JAR 25.609, JAR 25.611, JAR 25.1301, JAR 25.1309, JAR25.1321...	Avionics Mobile Services Limited modification AM/ 1469.Avionics Mobile Services Limited AFM Supplement, reference:PART21-008/001 or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10015654

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015659 (EASA.IM.A.S.01636)	AVIATION PARTNERS BOEINGWINGLETS COMPANY, LLC	REV. 6	FAA STC ST01518SE	757-200/-300	Install of Aviation Partners Boeing Winglets on B757-200 and B757-300Aeroplanes	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Model 757-200 (-1,-2, and -5 kits)Parts, components, systems or areas not modified or affected by theinstallation of the APB winglet retrofit kit will comply through thesa...	Aviation Partners Boeing Instructions for Continued Airworthiness:AP57.2-0802, Revision DAviation Partners Boeing Configuration Deviation List Supplement (CDLS): 757-200-1 and 757-300-1 Kits: No CDLS supplement, see FAA TCDS A2NM757-200-2 and 757-200-5 Kit: AP57-CDLS, July 2009757-300-2 Kit: AP57-CDL...	The Partial Wing Retrofit Installation (757-300 -1 Kit only) is approvedfor Rolls Royce RB211-535 powered a/c. See the following AviationPartners Boeing drawings for eligible Aircraft Serial Numbers: 757-200-1 and 757-200-2 Kits: 757-2007<(>,<)> Rev IR757-200-5 kit: 757-2027<(>,<)> Rev IR757-300-1 an...	10/05/2016	Active	10015659
10015662 (EASA.IM.A.S.01639)	HONEYWELL INTERNATIONAL Inc.	REV. 4	FAA STC ST01773CH	777F 777-300 / 777-300ER 777-200 / 777-200LR	Installation of Honeywell RESCU 406AF/ AFN/AFN2 Emergency LocatorTransmitter (ELT) System.Revision 1 transfers this STC from Armstrong Aerospace to CertifyNation,LLC.Revision 2 adds installation eligibility for Boeing 777-200LR/-300ER,777F series aircraft for MDL Configuration Group 8, RESCU 406AFN2u...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CertifyNation Master Data List, Doc. No CN19-039MDL-00, Revision 0,dated 20 December 2019;Airplane Flight Manual Supplement as identified in CertifyNation MasterData List, Doc. No. CN19-039MDL-00, Revision 0, dated 20 December 2019;Instructions for Continued Airworthiness as identified in CertifyNat...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/09/2024	Active	10015662
10015663 (EASA.IM.A.S.0164)	ALAMO ENGINEERING GmbH	REV. 4		HS.125 SERIES 700B HS.125 SERIES 700A/B HS.125 SERIES 700A	Installation of a Ground Proximity Warning System (GPWS) and TerrainAwareness Warning System (TAWS).Revision 2: Transfer to 328 Design GmbHRevision 3: Transfer to 328 SUPPORT SERVICES GmbHRevision 4: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAA Joint Aviation Requirements JAR-25 Change 17 Sections: 25.1, 25.301,25.303, 25.305, 25.307, 25.601, 25.603, 25.605, 25.607, 25.609, 25.611,25.1301, 25.1303, 25.1309, 2...	Avionics Mobile Services Limited modification AM/ 1470.Avionics Mobile Services Limited AFM Supplement, reference:PART21-008/006 or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatt...	05/11/2024	Active	10015663
10015664 (EASA.IM.A.S.01640)	ARMSTRONG AEROSPACE Inc.	REV. 1	FAA STC ST02108CH	767-200, 767-300, 767-300F	Installation of Honeywell RESCU 406AF / AFN Emergency LocatorTransmitter (ELT) System.Revision 1 extends the applicability to the models 767-200 and 767-300F.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	- Armstrong Aerospace Master Data List Doc. No. DC104-3058-00<(>,<)>Revision N<(>,<)> dated 14 February 2008 or later FAA approved revision.- FAA approved Airplane Flight Manual Supplement as identified inArmstrong Aerospace Master Data List, Doc. No. DC104-3058-00, RevisionN, dated 14 February 2008...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/01/2019	Active	10015664
10015692 (EASA.IM.A.S.01680)	CARLISLE INTERCONNECT TECHNOLOGIES	REV. 4	FAA STC ST02162CH	737-800 737-300/-400/-500/-600/-700	Installation of Elementary or Enhanced Surveillance Mode S TranspondersRev. 1: Configurations 5 and 8 addedRev. 2: Configurations 7 and 9 addedRev. 3: Configuration 6 addedRev. 4:,,All configurations include EWIS compliance	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amdt 0: 25.869, 25.981, 25.1301, 25.1309, 25.1322, 25.1333,25.1351, 25.1353, 25.1355, 25.1357, 25.1381, 25.1431, 25.1529, 25.1555,25.1581, 25.1585The requirements for...	- Master Data List ECS-203150, Rev. AK- AFM Supplement ECS-203502 rev B (configurations 2, 7, 8)- AFM Supplement ECS-203501 rev B (configurations 1, 4, 5, 9)- AFM Supplement ECS-208623 rev N/C (configuration 6)- ICA document ECS-203162 revJ (configurations 1,2,4,5,6,7,8,9)or later revisions of thea...	Only Configurations 1, 2, 4, 5, 6, 7, 8 and 9 are deemed tobe approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	11/07/2016	Active	10015692

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015695 (EASA.IM.A.S.01683)	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA STC ST03027AT-D	GIV-X	Installation of Broad Band Multi-Link (BBML) SystemSTC revision of the EASA STC EASA.IM.A.S.01683 REV. 1 for systemupdgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC ST03027AT-D, amended on 9th August 2010-FAA Statement of Compliance, ref. 100G-14-189, dated 9th June 2014-Installed in accordance with Gulfstream Aerospace Corporation IndexList, ref. GC413038002, Revision AK, dated 4th March 2014-Airplane Flight Manual Supplement, ref. GC41303M001, Revisi...	It is the installer responsibility to ensure that all STCs fitted areEASA approved.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upo...	12/06/2014	Active	10015695
10015713 (EASA.IM.A.S.01710)	FOKKER 50 FREIGHTER STC CORP.	REV. 2	FAA STC ST01916LA	FOKKER 50	Installation of Large Cargo door.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Maintenance Manual Supplement nr. MMS 222 Rev. B;2. FAA approved Airplane Flight Manual Supplement document nr. FMS 223dated October 30, 2006;3. FAA approved Fokker 50 Freighter STC Corporation Master Drawing List24B500 revision NC dated September 14, 2006;or later revisions of the above listed d...	1. To allow the carriage of cargo STC IM.A.S.01711 shall beincorporated;2. The maximum number of occupants in the aircraft including crewmembers is 3;3. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraphs "Description" and“Assoc...	12/07/2016	Active	10015713
10015717 (EASA.IM.A.S.01714)	CASCADE AEROSPACE Inc.	REV. 2	TCCA STC SA00-69	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-103, DHC-8-106 DHC-8-102	Environmental Control System Performance Improvement ModificationRevision 01: Editorial Changes to include Issue 04 of TCCA STC SA00-69Revision 02: Applicability list corrected, minor change to includeEnvironmental Control System performance improvements from Issue 05 ofTCCA STC SA00-69	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	The change is defined with Revision 17 of Cascade AerospaceInc. MasterData List Document MDL 2302.Maintenanance shall be accomplished in accordance with Revision 4 ofCascade Aerospace Inc. maintenance manual supplement document MMS 2302Orlater revisions of the above listed document(s) approved/ acc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/02/2021	Active	10015717
10015720 (EASA.IM.A.S.01719)	B/E AEROSPACE, Inc. - FSI	REV. 3	FAA ST01849SE	777-200	Business Class Seat Installation	IM.A.003The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI-H01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the ori...	FAA STC No. ST01849SE, dated 30 January 2012.Flight Structures, Inc. Master Drawing Lists A5FS520-D01, Revision Edated June 15, 2009, or later approved revision, and B0FS015-D01,Revision IR, dated October 20, 2011 or later revision.The Supplemental Instructions for Continued Airworthiness (ICA), Fli...	Boeing Structural Compliance summary Report Document DLR-36718 revisionNew dated 17 March 2008 must be accomplished concurrently with this STCBoeing Structural Compliance Summary Report Document DLR-36718 RevisionNew dated 17 March 2008 must be accomplished concurrently with this STC.Concurrent Inst...	02/02/2012	Active	10015720
10015727 (EASA.IM.A.S.01743)	ROCKWELL COLLINS AEROSPACE &ELECTRONICS, Inc.	REV. 3	FAA STC ST01390LA	CL-600-2D24, CL-600-2E25 CL-600-2C10, CL-600-2D15	Installation of Head-Up Guidance System (HGS) Model 4200.Addition of CL-600-2E25 (CRJ 1000) to HGS 4200 STC	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI A-1000-01-HGSThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	-EASA STC no. EASA.IM.A.S.01743 Revision 1 dated 31 May 2007-FAA STC no. ST01390LA dated 28 December 2010-Rockwell Collins Master Drawing List No. 9701-1099 at Revision N orlater approved revisions-Rockwell Collins Airplane Flight Manual Supplement No. 9701-1152 atRevision E or later approved revisi...	None	21/04/2011	Active	10015727

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015728 (EASA.IM.A.S.01745)	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 2	FAA STC SA02177CH	JETSTREAM 3201	Removal of passenger seats and installation of Spectrum Aeromed medicalsystems	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02177CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Document List 6034-1A, Revision 1, dated July 6, 2005,Spectrum Aeromed Inc AFM supplement 6034-1FMSSpectrum Aeromed Instructions for Continued Airworthiness Manual 6043-1MMor later revision of the above listed documents approved by EASA in accordance with EASA ED decision 2004/04/CF (or subse...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2019	Active	10015728
10015732 (EASA.IM.A.S.01754)	AERONAUTICAL ENGINEERS Inc.	REV. 4	FAA ST01827LA	737-300, 737-400	BOEING 737-300/-400 FREIGHTER WITH OPTIONAL CARGO CONTAINERCONFIGURATION.Modification of notch frames to accommodate 88x125" container indisposition 10 (rear)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 Issue 1:Special Condition - EWIS ICAThe requirements for environmental protection and the associatedcertificated noise and/ or e...	- AEI Cargo Modification Drawing List R-668, Revision L, dated June 21,2010 for B737-300 aircraft.- AEI Cargo Modification Drawing List R-811, Revision E, dated June 21,2010 for B737-400 aircraft.- AEI Inspection Instructions Document R-834, Revision A, datedSeptember 22, 2010.or later revisions ofa...	Limited to B737-300/400 modified with EASA STC IM.A.S.01754Rev 3 (FAAST01827LA)	24/09/2010	Active	10015732
10015747 (EASA.IM.A.S.01779)	DAYTON-GRANGER Inc.	REV. 5	FAA STC NO. ST02241NY	CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700/701/702) CL-600-2B19 (RJ SERIES 100)	Installation of Winglet and Horizontal Stabilizer End Cap LightningProtection Kits	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. For Configuration 1:a) Maintenance must be in accordancewith Dayton Granger Instructionsfor Continued Airworthiness701620<(>,<)> Rev-A<(>,<)> dated 16 May 2006b) Operate in accordance with Dayton Granger Airplane Flight ManualSupplement AFMS 701626<(>,<)> Rev-B<(>,<)> approved 5 June 20152. For...	None	31/03/2016	Active	10015747
10015754 (EASA.IM.A.S.01787)	FIELD AVIATION EAST, LTD.	REV. 3	SA04-125 ISSUE 5	DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Retrofit of Collins Elementary Surveillance and ADSB capable TDR-94D,Dual Mode-S Transponders and associated Collins CTL92E, or Universal RCUControllers.Revision 3 incorporates ADSB capability via Configuration-C.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Initial Issue of CSACNS.D.ADSB.001, CS ACNS.D.ADSB.010, CS ACNS.D.ADSB.020, CSACNS.D.ADSB.025, CS ACNS.D.ADSB.030, CS ACNS...	Configuration A, Elementary Surveillance Capable Transponders withCTL92EDHC-8-100, -200 and -300 SeriesThe change is defined with Revision M of FAEL Master Drawing Data Listdocument DDL-1128.Maintenance shall be performed in accordance with FAEL MaintenanceManual Supplement designated MMS20105, Revi...	Configuration A, Elementary Surveillance Capable Transponders withCTL92E Controller andConfiguration B, ADS-B Capable Transponders with CTL92E or Universal RCUControllers:The installation of Field Aviation STC SA98-72, TCAS II/ACAS II and DualMode-S Transponders or the fitment of Bombardier Factoryl...	06/09/2019	Active	10015754
10015763 (EASA.IM.A.S.01799)	ACORN WELDING Ltd.	REV. 1	TCCA STC SA04-63	182R 182L/182M/182M/182N/ 182P/182Q 182E/182F/182G/182H/ 182J/182K	Installation of Aerocet 3400 Amphibious Float Conversion.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	In accordance with Amtech Aeronautical Limited (AAL) Installation Instructions EO333901 dated May 10, 2004, and Master Data List MDL33301 Rev 2 dated November 10, 2004, or later approved revisions.TCCA approved Flight Manual Supplement FMS333902 dated May 10, 2004 is required for Cessna Models 182E...	1. This STC confers no Operational Approval, that must be sought from the National Airworthiness Authority of the country of registration.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility...	14/06/2017	Active	10015763

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015764 (EASA.IM.A.S.01800)	AEROLITE AG	REV. 3		35A	EMS Equipment InstallationCabin installation of Patient Unit P/N 250071-506, Power Box P/N250080-501 and Cabinet P/N 250073-504	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- According to Aerolite Master Document List No.MDL-06-001,Rev C- To be operated in accordance with Aerolite AFM-S Document No.FMS-06-001, Rev B- To be maintained i.a.w. AeroliteICA Document No. OPM-06-001, Rev Cor later revisions of theabove listed document(s) approved/ acceptedunder the EASA sys...	Limited to: S/N 628, 663, 656.Prior to installation of thischange/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	07/08/2019	Active	10015764
10015775 (EASA.IM.A.S.01819)	JET AVIATION AG	REV. 3		A320-271N/-272N/-273N A320-251N/-252N/-253N A320-233 A320-231/-232/-233 A320-214, A320-231, A320-232 A320-211/-212/-214/-215/-216 A320-111, A320-211, A320-212 A319-151N/-153N A319-132, A319-133 A319-131/-132/-133 A319-114, A319-115, A319-131 A319-111, A319-112, A319-113 A319-111/-112/-113/-114/-115	Camera Installations on A319 and A320This Major Change to EASA STC 10015775 includes the following changes:Include new camera part numbers from OTONOMY vendor:-Tail Camera: 1000-1300-001/003 P/Ns added-Quad Camera: 1000-1210-002 P/N added-Zoom Camera: 1000-1400-001/002 P/Ns addedInclude the NEO mode...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 Amdt. 23:25.23, 25.29, 25.301, 25.302, 25.303, 25.305, 25.307, 25.321, 25.365,25.561, 25.571, 25.581, 25.601, 25.603,...	JBSL-M-01019ICA-01 Rev 3 Instructions for Cont. AirworthinessBA32023391-001 Rev I Master Data ListOr later revisions ofthe above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/09/2020	Active	10015775
10015815 (EASA.IM.A.S.01886)	AEROMECH Inc.	REV. 1	FAA SA00558DE-D	B300C B200CT/B200T/ 300/300LW/B300 200/200C/200CT/B200/ B200C	Installation of a Pilot and Co-Pilot Digital Air Data Unit	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00558DE-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	- Master Data List, document No 34-00-0002-00, Revision IR,dated 23July 2004 or later approved revision.- Instructionsfor Continued Airworthiness, document 34-02-0002-00, Rev4.0dated 16 July 2004 or 34-02-0002-10 Rev 1.0 dated 28 June 2005, orlater approved revision.- Airplane Flight Manual Suppl...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/04/2019	Active	10015815
10015823 (EASA.IM.A.S.01895)	HONEYWELL INTERNATIONAL Inc.	REV. 2	FAA STC ST01872CH	737-800, 737-900, 737-900ER 737-500, 737-600, 737-700, 737-500, 737-600, 737-700 737-200C, 737-300, 737-400, 737-200C, 737-300, 737-400 737-200	Installation of a Honeywell RESCU 406AF/AFN/AFN2 Emergency LocatorTransmitter (ELT) System.Rev. 2: Transfer from "Armstrong Aeropspace, Inc. d/b/a to AstronicsArmsstrong Aerospace" to "Honeywell International, Inc."	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS 25 amdt.0 for paragraphs:25.1, 25.29, 25.303, 25.561(c),25.571(a, b), 25.601, 25.603(a-c),25.605(a), 25.609(a-b), 25...	Astronics Armstrong Aerospace Master Data List (MDL), DC104-1005-00,Revision ABAFMS DC303-1005-00 Revision BWeight/Balance DC304-9807A1-00 Revision –Electrical Effects Statement DC305-9807A1-00 Revision –ICA DC113-9807A1-00 Revision Cor later revisions of the above listed document(s) approved/ accept...	As per AFMS DC303-1005-00 Revision B. In particular: The ELT does notneed to be manually activated for test purposes. Manual activation, ifdesired, is limited to the first five minutes of the hour and is to beof very short duration (5-10 seconds).As per ICA DC113-9807A1-00 Revision C. In particular:...	25/07/2025	Active	10015823
10015828 (EASA.IM.A.S.01917)	B/E AEROSPACE, Inc.	REV. 1	FAA ST03212AT	737-300, 737-400, 737-500	Installation of an Active Noise Reduction (ANR) Headset.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EMTEQ Engineering Master Drawing List (MDL) 2-31582-001<(>,<)> Rev. A,dated January 06, 2006.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015828

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015832 (EASA.IM.A.S.01923)	WIPAIRE Inc.	REV. 1	FAA STC SA2CH	DHC-6 SERIES 400 DHC-6 SERIES 300	Installation of Wipline 13000 Amphibian Floats or Installation ofWipline 13000 Seaplane Floats on DeHavilland DHC-6 Series 300 and 400.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:FAR 23 atAmdt. 8: 23.1529;Amdt. 36: 23.2;Amdt. 45: 23.521 - 23.537;Amdt. 49: 23.1359;Amdt. 50: 23.1555 - 23.1559, 23.1581 -...	Wipaire Installation Drawing No. 7C1-3002, Rev. L, dated July 20, 2012 (Amphibian)Wipaire Installation Drawing No. 7C1-3100, Rev J, dated July 20, 2012(Seaplane) Wipaire Installation Drawing No. 7C1-3004, Rev. H, dated July 20, 2012 (Operation with removed floats)Airplane Flight Manual Supplements:forA...	For DHC-6 Series 300:Restricted to Amphibious or seaplane Operation for Aircraft with PT6-27Engines only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduc...	05/03/2015	Active	10015832
10015833 (EASA.IM.A.S.01924)	WIPAIRE Inc.	REV. 3	FAA SA39CH	SEE EASA APPROVED MODEL LIST	Installation of an Amphibian Gear Position Advisory System MKII andLaser Gear Advisory System in accordance with Wipaire Inc. MasterDrawing List W-MD151, Rev. C and the drawings listed on AML to this STCor later FAA approved revisions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23, Amdt. 4:23.305(a)(b), 23.601, 23.603, 23.607, 23.609, 23.611, 23.613,23.729(d)(e), 23.1301(a), 23.1322, 23.1351(a),...	Airplane Flight Manual Supplement POHSA39CH Rev. J, FAA approved October1, 2015Installation Instruction: refer to AMLorlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Impleme...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/01/2016	Active	10015833
10015840 (EASA.IM.A.S.01934)	A.A.E., LTD.	REV. 1	FAA ST03001AT	F28 MARK 0100 F28 MARK 0070	Installation of an AAE, Ltd smoke detection and halon fire suppressionsystem into the lower baggage compartments of theaircraft to establisha class C cargo compartment classification.The installation includes a control head installed in the aircraftcockpit for monitoring and operation of the system...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AAE, Ltd Airplane Flight Manual Supplement, No. TFA09-0087,Rev IR,dated January 14, 2005 or later revisions of the above listed documentsapproved by EASA in accordance with EASA ED Decision 2004/04/CF (orsubsequent revisions of this decision) and/ or the TechnicalImplementation Procedures of EU/ U...	Refer to the limitation section of AAE, Ltd Airplane FlightManualSupplement, No. TFA09-0087, Rev IR, dated January 14,2005.Prior to installation of this design change it must bedetermined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/11/2015	Active	10015840
10015843 (EASA.IM.A.S.01938)	BOMBARDIER Inc.	REV. 3	TCCA SA06-14 ISSUE 2	BD-100-1A10	Installation of an ARTEX ELT c-406-with a navigation interface.Revision of the EASA STC IM.A.S.01938 REV 1 in order to delete thestructural provisions approved under STC TCCA SA-05-28 as a prerequisite to TCCA STC SA 06-14 for future a/c deliveries.Rev. 3 removes the commercial designation from the...	Certification Basis as per EASA TCDS IM.A.080 plus:The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and rem...	- Transport Canada Supplemental Type Certificate SA06-14 Issue 2, dated9th September 2010;- Modification Data Summary E618000 Revision D dated 10th September2009;- Compliance Check List E618065 Revision D dated 25th August 2010;- Instructions for Continued Airworthiness RAL-BV100-25601-IFCA Revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/04/2018	Active	10015843
10015849 (EASA.IM.A.S.01949)	FIELD AVIATION EAST, LTD.	REV. 3	TCCA SA05-42	DHC-8-202 DHC-8-106, DHC-8-201 DHC-8-102, DHC-8-103	Installation of Dual Universal GLS-1250 DGPS Receivers (SCAT-1) (TCCASTC SA05-42, Issue 4)Revision 3 was issued to include Configuration C	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Configuration A – (Electrical and Structural Provisions only)Installation must be performed in accordance with FAEL Master Drawingand Data List designated DDL-1136 Revision A.Instructions for Continuing AirworthinessMaintenance must be performed in accordance with FAEL Maintenance ManualSupplementsM...	For Configuration A and Configuration B: FAEL (Dual UNS-1F FMS forSoftware versions 801/802 and 803) STC EASA.IM.AS.3183, Issue 1 or laterEASA approved revision must be installed as a prerequisite to theinstallation of the Dual GLS-1250 DGPS (SCAT-1) modification.For Configuration C: EASA STC 100271...	08/11/2019	Active	10015849

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015869 (EASA.IM.A.S.01984)	BEECHCRAFT CORPORATION	REV. 3	FAA ST09262SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of a Third and Fourth 750 Liter Oxygen Bottle in AftEquipment Bay.	FAA CAR 4b <(>&<)> FAR Part 25	-Installation inn accordance with Master Drawing List 800-152 Revision For later approved revision.- Operation in accordance with Airplane Flight Manual Supplement 800-264Revision R7 or later approved revision.- Maintain in accordance with Maintenance Manual Addendum: 35-06-01.	-101 and -103 installation: Model Hawker 750; Hawker 800XP;Hawker 850XP-105 installation: Model Hawker 900XP	18/02/2010	Active	10015869
10015881 (EASA.IM.A.S.01997)	BEECHCRAFT CORPORATION	REV. 3	FAA ST10001SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of a Honeywell Solid State Flight Data Recorder withInterface to Collins Proline 21.	FAA CAR 4b & 14 CFR Part 25The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this c...	1. Installation of the Honeywell Solid State Flight Data Recorder withinterface to Collins Proline 21 in accordance with the Hawker BeechcraftSTC Master Drawing List 800-199, Revision AJ.2. For -101, -105, and -107 Installations: Models: Hawker 750, 800XP and850XP-Flight Manual Supplement No. 800-30...	For Hawker 800XP model, installation is limited to aircraftequippedwith Collins Proline 21 Avionics	19/09/2011	Active	10015881
10015892 (EASA.IM.A.S.02012)	GENERAL AVIATION SERVICE ApS	REV. 1	FAA SA564NE	F172P 172K, 172L, 172M, 172N, 172P 172E, 172F, 172G, 172H, 172I	Installation of a Textron Lycoming Model O-360-A4A, -A4M or-A4N engineand a Sensinech Model 76EM8S14-0-60 fixed Pitch metal propeller.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation in accordance with Alphin Aircraft Inc. Drawing List No.AA-89-1 Revision B, dated August 28, 1990.Operation in accordance with:1 .,,FAA Approved Supplemental Flight Manual No. 1 for the Models 1721,K and L<(>,<) > revised February 16, 1990.2.,,FAA Approved Supplemental Flight Manual No.M...	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	10/06/2024	Active	10015892
10015899 (EASA.IM.A.S.02020)	ROSEMOUNT AEROSPACE, Inc.	REV. 1	FAA STC ST02368CH	737-900/ 737-900ER 737-600/ 737-700/ 737-800 737-300/ 737-400/ 737-500	Installation of Rosemount Aerospace Cockpit Door Surveillance System (CDSS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02368CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Rosemount Aerospace Master Data List, Doc. No. D06400594, Revision G,dated 2 January 2008, or later FAA approved revision.2. Rosemount Aerospace Airplane Flight Manual Supplement, Doc. No.D06400184, Revision A, approved 4 January 2007< (>,<)> or later FAAapproved revision< (>,<)> or Rosemount Aeros...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This modification may not be installed aft...	18/06/2019	Active	10015899
10015911 (EASA.IM.A.S.02040)	ISRAEL AEROSPACE INDUSTRIES, Ltd.BEDEK AVIATION GROUP	REV. 2		747-400	Conversion of Boeing 747-400 Aircraft from Combi to SpecialFreighterConfiguration.This certificate is a re-edition of EASA STC ref. EASA.IM.A.S.02040Revision 1 to update the reference to the associated Supplemental TypeCertificate Data Sheet		- Master Document List Number 366-00-00-A3550 Revision "New" or laterapproved revision< (>,<)>- Airplane Flight Manual Supplement Number 366-00-00A2911 Revision A orlater approved revision.	1. Supplemental Type Certificate Data Sheet STCDS.IM.A.S.02040 applies. 2. This STC is approved only for the product configuration as defined inthe approved design data referred toin the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the install...	11/11/2019	Active	10015911
10015915 (EASA.IM.A.S.02045)	FLY IN VACATIONS	REV. 1	FAA STC SA5202NM	COMMANDER 112	Validation of FAA STC SA5202NM: Installation of Lycoming engine model IO-360-C1D6 modified in accordance with STC SE5203NM & Propeller Hartzell HC-E3YR-1RF/F7392.		AFM Supplement No. 1, dated 2 February 1991 and Supplement No. 2, dated23 February 1998.Installation Manual, Installation Drawings, Parts List, RCM-1000.	See AFM Supplement No. 1.	29/07/2015	Active	10015915

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10015918 (EASA.IM.A.S.02051)	BLR AEROSPACE, L.L.C.	REV. 4	FAA SA01615SE	SEE FAA AML B. 200, 200C, 300, 300LW A. B200GT A. B200, B200C, B200CGT	Installation of winglets and associated changes in wing andaileronstructures and related system changes on Raytheon Model 200 200C, B200,B200C, 300 and 300LW airplanes.Revision 1adds models B200GT, B200CGT.Revision 2 updates the STC holder's name and address.Revision 3 updates the STC holder's add...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	BLR Aircraft Flight Manual Supplements Reference AFMS A200-1, Rev. IR;AFMS 300-2, Rev. E; AFMS B200-2, Rev D; AFMS B200-3, Rev. 3; AFMSB200-5, Rev. IR< (>,<)>Instructions for Continued Airworthiness in accordance with BLRDocuments ReferenceBLR-200-950, Rev. E revisions and BLR-300-950, Rev.B<(>,<) >B...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/03/2024	Active	10015918
10015951 (EASA.IM.A.S.02093)	B/E AEROSPACE, Inc.	REV. 1	FAA ST03269AT	JETSTREAM SERIES 3200 JETSTREAM SERIES 3100	Installation of a Honeywell CAS 67A Traffic Alert and CollisionAvoidance System IT (TCAS IT) and Dual Mode MST 67A ModeS Transponder.Revision 1 transferred from EMTEQ Engineeringto B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplements (AFMS) for a CAS 67A TCAS IT and MST67A Mode S, EMTEQ Document No. 2.37239-903, Rev.IR, dated May 15, 2006.EMTEQ Master Drawing List (MDL) No. 2-37239-001, Rev. B, dated May 12<(>,<)> 2006.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10015951
10015956 (EASA.IM.A.S.02099)	BOMBARDIER Inc.	REV. 3	TCCA SA06-37	BD-700-1A10/ BD-700-1A11 BD-700-1A10, BD-700-1A11	Installation, Structural Provisions Security Syst. Antenna	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impactt...	Modification to be completed in accordance with Aero Consulting ServicesModification Data Summary Number E448000 Revision F ,,Equipment iaw. 1. MMMS G-TM05104501 Rev. NC 2.MMMS G-TM05104505 Rev. B 3. MMMS G-TM05104507 Rev. NCor later revisions of the above listed documents approved by EAS...	1. Refer to the airworthiness limitations contained in the requiredMaintenance Manual Supplement.2. This approval is limited to the structural provisions for an antenna.Installation of an antenna requires a separate airworthiness approval.Prior to installation of this design change it must be determ...	17/09/2021	Active	10015956
10015977 (EASA.IM.A.S.02129)	ROCKY MOUNTAIN AIRCRAFT	REV. 1	TCCA STC SA02-128	DHC 6-100, 6-200, 6-300	Installation of Single or Dual Sandel ST3400 Terrain Awareness WarningSystem (TAWS)/RMI System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Revision to EASA STC IM.A.S.02129 validating Transport Canada STCSA02-128 Issue 2.Modification Instruction 181710 Revision MEngineering Data Summary E100300 at initial revision dated 12 March2010.Drawing 1873419 incorporating DCN RMA1873419/1.Drawing 1873420 incorporating DCN RMA1873420/2.Drawing 18...	The audio for dual TAWS configuration must be from a singlesource inaccordance with drawings 1873419, 1873420 and 1873421 incorporatingDCN's RMA1873419/1, RMA18173420/2 and RMA18173422/1 respectively.	17/03/2010	Active	10015977
10015989 (EASA.IM.A.S.02143)	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST02049CH-D	GIV-X, GV-SP	Installation of Securaplane Security System in Gulfstream models GIV-Xand GV-SP	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gulfstream Aerospace Corporation MasterDrawing List No. GC514566000, Revision G, dated January 28, 2010, orlater approved revisions.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions...	None	24/02/2011	Active	10015989

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016001 (EASA.IM.A.S.02161)	GOODRICH INTERIORS	REV. 2	FAA STC ST01691LA	B767-200/-300	Installation of "Sentry One" Flight Deck Door Camera Surveillance System	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	- Hollingsead International, Inc. Master Data List, Document No.2765-01, Revision NC, dated October 19, 2004- AFM Supplement, Document No. 2765-AFM, revision NC, 5th November 2004or later revisions of the above listed documents approved byEASA inaccordance with EASA ED Decision 2004/04/CF (or subse...	None	16/08/2012	Active	10016001
10016004 (EASA.IM.A.S.02167)	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST02796AT-D	GV-SP	Installation of Board Band Multi-Link System (BBML)Revisionof the EASA STC EASA.IM.A.S.02167	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC ST02796AT-D- In accordance with Gulfstream Aerospace Corporation Index ListGC513038002, Revision AH, dated July30, 2010-FAA approved Flight Manual Supplement, GC51303M001, Revision A, datedJuly 24, 2006 (required for the -501 configuration).-FAA approved Flight Manual Supplement, GC51303M00...	None	20/08/2012	Active	10016004
10016008 (EASA.IM.A.S.02173)	ASTECH ENGINEERED PRODUCTS Inc.	REV. 1	FAA STC ST01189LA	MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-81/82 BOEING MD-88 BOEING DC-9-87 (MD-87) BOEING DC-9-83 (MD-83) BOEING DC-9-81/82	Installation of ASTECH Manufacturing, Inc. inlet assemblyRev. 1: Transfer from "GKN Aerospace Chem-Tronics, Inc." to "AstechEngineered Products<(>,<)> Inc."	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	- ASTECH Manufacturing , Inc. Document No. MDL-030-06009 titled:"Master Drawing List - MD-80 Series Inlet", RevisionA00, dated June20, 2001<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/08/2024	Active	10016008
10016009 (EASA.IM.A.S.02174)	GULFSTREAM AEROSPACE CORPORATION	REV. 3	FAA STC ST03238AT-D	GIV-X / GV-SP	Installation of Cabin Communication System.Revision 1: Editorial changes in Associated Technical Documentation andDescription fields. New STC number (previous number was IM.A.S. 02174).Revision 2: Editorial changes in Model applicability section.Revision 3: Editorial changes in Applicant address andT...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.Rev....	-Gulfstream Aerospace Corporation Index List GC41 3038007, Revision M,dated April 29, 2015.- Flight Manual Supplement, GC41 303M007, Revision C, dated April 29,2015 for GIV-X aircraft.-Flight Manual Supplement, GC51 303M005, Revision C, dated April 29,2015 for GV-SP aircraft.-ICA document, GC41 303A0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/06/2016	Active	10016009
10016019 (EASA.IM.A.S.02186)	BOMBARDIER Inc.	REV. 66	TCCA SA06-90	CL-600-2B16 (604 VARIANT)	Installation of Complete Customized Aircraft Interior.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): Transport Canada SCA 2022-06 Non-RechargeableLithium Batteries.The requirements for environmental protection and the associatedcertifi...	According Aero Consulting Services Ltd. Configuration Definition ListRef E934000 Rev RK dated 9 Dec 2019To be operated iaw. - Bombardier AFMS EFM-2500-4000, Rev C and/or - Aero Consulting Services Ltd. AFMS E973091 Rev BTo be maintained iaw. - Mandatory MM-S E934070 Rev C and/oror...	See those of TCCA STC SA 06-90.The EASA approved configurations are identified in the ConfigurationDefinition List document Ref E934000Aircraft issued with a CofA on or after 18 May 2019 must be equippedwith Halon Free extinguishersPrior to installation of this change/repair it must be determined th...	24/10/2022	Active	10016019

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016038 (EASA.IM.A.S.02207)	WHELEN AEROSPACE TECHNOLOGIES LLC	REV. 8	FAA STC ST02893AT	SEE FAA AML SEE EASA APPROVED MODEL LIST	Installation of a Boom Beam Taxi/Landing Light SystemRev. 8: Change of Address and sequential technical amended validation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List Report No. 47, rev. AX<(>,<) >dated 30 June 2025<(>,<) >Instructions for Continued Airworthiness LSM-500-12, Rev. IR<(>,<)>dated 4 September 2024<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implementat...	The STC is valid for aircraft types and models approved by EASA andlisted on the latest approved FAA Aircraft Model List.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairand any otherpreviously installed change and/ or repair will...	07/11/2025	Active	10016038
10016064 (EASA.IM.A.S.02243)	AEROMECH Inc.	REV. 3	FAA STC ST01526SE	S550 (CITATION S/II) 560 (CITATION V) 550 (CITATION II) 500 (CITATION I)	Group Aircraft Approval for Reduced Vertical Separation Minimum (RVSM)for Cessna Model 500/550/S550/560.This STC is an update of STC EASA.IM.A.S. 02243 Rev 1, and incorporatesanadded class of avionics as applicable to the RVSM Group approval inaccordancewith Aeromech document AMI-QD-CS-0307, rev F.	EASA TCDS IM.A.207The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate...	1) Applicant Technical Documentation (Aeromech) : AMI-QD-CS-0307, Rev F2) Instructions for Initial and Continued Airworthiness: Depending onthe class of installed avionics on the aircraft- AMI-IICA-CS-0509 : for Class 1 airframe (group airframes equipped withdual Shad in ADC 6000 air data computersa...	none	08/08/2011	Active	10016064
10016083 (EASA.IM.A.S.02267)	LB AIRCRAFT ENGINEERING LLC	REV. 2	FAA STC03354AT	737-300/-400 737-300	Installation of a single Universal Avionics Class “A” TAWS systemRevision 1: Transf. STC 10016083 (EASA.IM.A.S. 02267) from ARC AvionicsCorporation to AIRCRAFT RADIO & AVIONICS, LLCRevision 2: STC Transfer from "Aircraft Radio & Avionics, LLC" to "LBAircraft Engineering, LLC".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-ARC Avionics Master Data List 760-061505, Rev I, dated 8 April 2008<(>,<)>-Flight Manual Supplement Doc 730-061505, Rev B, dated 25 April 2008<(>,<) >or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decisi...	The aircraft has to be equipped with an EASA-approved Universal EFIS todisplay the TAWS terrain.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadver...	29/02/2024	Active	10016083
10016084 (EASA.IM.A.S.02269)	LB AIRCRAFT ENGINEERING LLC	REV. 2	FAA ST03356AT	737-300	Installation of a dual Universal Avionics UNS-1F FMS sys onBoeing737-300 aircraft. Installation includes 2 Nav ControlUnits (NCU) in theEE bay and 2 GPS antennas. Center pedestal pilot and co-pilot ControlDisplay Units (CDU).Revision 1: Transf. STC 10016084 (EASA.IM.A.S.02269) from ARC AvionicsCor...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-ARC Avionics Master Data List 750-120605, rev I, dated 8 April 2008- Flight Manual Supplement, ARC Avionics 730-120605, rev-A, dated 25April 2008-ARC Avionics Instructions for Continued Airworthiness 2-37356-903,rev-B, dated 19 October 2006or later revisions of the above listed documents approveda...	The aircraft has to be equipped with an EASA-approved Universal AvionicsEFIS as it provides the Navigation Displays andData Concentrator Unitsto integrate the aircraft sensors and communications.Prior to installation of this design changeit must be determined thatthe interrelationship between this...	29/02/2024	Active	10016084
10016085 (EASA.IM.A.S.02270)	LB AIRCRAFT ENGINEERING LLC	REV. 4	FAA ST03362AT	737-200, 737-300 737-200/-300	Installation of a dual Universal Avionics UNS-1F Flight ManagementSystem (FMS), or UNS-1Fw WAAS capabe FMS, on:- Boeing737-200 and 737-300 aircraft without EFIS (Configuration I), or- Boeing 737-300 aircraft with original Honeywell or collins EFIS(Configuration II) Installation includes:-2 Nav Contr...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI H-01 issue 3 dated 07 March 2011: Special condition - EnhancedAirworthiness Programmefor Aeroplane Systems – ICA on EWISThe requirements for envi...	Master Data List:-MDL 752-120605 Rev C, dated 02 April 2009(B737-200 and B737-300 A/Cwithout EFIS)-MDL 752-022310 Rev E, dated 22 Jan 2020 (B737-300 A/C with EFIS) Flight Manual Supplements:-AFMS 732-022310, Rev C dated 28 Jun 2013 (B737-300 A/C with EFIS)-AFMS 732-120605 Rev B dated 07 May 2009 (B7...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/02/2024	Active	10016085

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016086 (EASA.IM.A.S.02271)	AIRCRAFT RADIO & AVIONICS, LLC	REV. 1	FAA ST03363AT	737-200	Installation of a single Universal Avionics Class “A” TAWS system on737-200 series aircraftRevision 1: Transf. of STC 10016086 (EASA.IM.A.S.02271) from ARCAvionics Corporation to AIRCRAFT RADIO & AVIONICS, LLC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ARC Avionics Master Data List 762-061505, Rev –I/R, dated01 November2006,- Flight Manual Supplement Doc 732-061505 Rev A, dated 08 February 2007or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/ CF (or subsequent revisions ofthis decision...	The aircraft has to be equipped with a Universal EFIS to display in thecenter pedestal in order to display the TAWS terrain. This MFD can bepart of this installation, or pre-existing as the 737-200 seriesAircraft.Prior to installation of this design change it must be determined thatthe interrelation...	29/09/2017	Active	10016086
10016091 (EASA.IM.A.S.02278)	AIR ALLIANCE GmbH	REV. 3		PA-42-720	Extension of pressurized fuselage life limit to account forthe changein operational usage from Alitalia Airlines Training to Normal Usage byany operator.Note: This STC supersedesSTC EASA.IM.A.S.02278 Rev 2 and indicates thetransfer of anapplicable S/N to a new STC holdership by AirAlliance.	The Certification Basis for the original product remains applicable tothis certificate/ approval.FAR 23 Amdt 1 to 16Therequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalproduct areunchanged and remain applicable to this certifica...	Air Alliance GmbH Report No AARD-1, Rev A dated 28 Dec 2006"AirAlliance PA-42-720 Aircraft - Fuselage Life Substantiation"Air Alliance GmbH Report no AARD-2, Rev B dated 28 Dec 2006 "AirAlliance PA-42-720 Aircraft - Pressurized Fuselage Cabin Instructionsfor Continued Airworthiness"AirAlliance MDLo...	This STC is limited only to airplane S/N 42-5501046 and 42-5501047operated by any operator.Operation in normal usage upto a life-limit of 21.452 hours for S/N42-5501046 and 21.561 hours for S/N 42-5501047.Air Alliance GmbH Report No AARD-2 Rev B dated 28 Dec 2006 "Air AlliancePA-42-720 Aircraft - P...	19/07/2011	Active	10016091
10016093 (EASA.IM.A.S.02280)	PRECISE FLIGHT, Inc.	REV. 2	FAA STC SA01708SE	SR22, SR22T	Installation of Cirrus Fixed Oxygen System	The Certification Basis for the original product remains applicable tothis certificate/ approvalCS 23, EASA certification basis defined in TCDS IM.A.007 ref CRI A-01This certificate/ approval involves a change to the certificated noiseand/or emissions levels	Manufactured in accordance with Precise Flight Engineering Drawing Lists102N0000-Rev. F, 100N0000-Rev. AH, 051A0000-Rev. B, 027N0000-Rev. E, 026N0000-Rev. E, 020N0000-Rev. G, 010N0000-Rev. H, 016N0000-Rec.C, 012N0000-Rev IR, 011N0000-Rev. A, 010A0000-Rev. IR, 009N0000-Rev. CInstalled in accordance wit...	- according limitation section of AFM-S- max altitude extension up to 25.000 ft, if operated acc. Limitationsection of AFM-S	03/08/2010	Active	10016093
10016095 (EASA.IM.A.S.02284)	TELEDYNE CONTROLS, LLC	REV. 3	FAA STC ST01547LA	BD-700-1A10	Installation of EMS Technologies High Speed Data Satellite Communicationsystem HSD-64 and HSD-128 and validation of FAASTC ST01547LA.This STC supersedes EASA.IM.A.S.02284 following a change in theapplicant's address.	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchangedand remain applicable to thiscertificate/ approval.	MDL: MDL246759 Rev -, dated August 1, 2003or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/04/2016	Active	10016095
10016111 (EASA.IM.A.S.02301)	B/E AEROSPACE, Inc.	REV. 1	FAA ST03345AT	767-200, 767-300	Installation of an Enhanced Surveillance System (EHS) to expandTransponder Mode-S functionality.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement (AFMS) for an EHS Installation, asrecorded in EMTEQ AML Document No. 2-38842-002, Rev. IR.EMTEQ Master Drawing List (MDL) No. 2-38842-001, Rev. A, Dated October03, 2006.	None Prior to installation of this design change it must bedeterminedthat the interrelationship between this design change and any otherpreviously installed design change and/ orrepair will introduce noadverse effect upon the airworthiness of the product.	02/03/2016	Active	10016111
10016113 (EASA.IM.A.S.02303)	B/E AEROSPACE, Inc.	REV. 1	FAA ST02297AT	A300-B4-103 A300-B2-203, A300-B4-203	This installation added three additional parameters to be recorded bythe existing Flight Data Recorder.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avitas Engineering Master Drawing List No. 313AV30-MDL, Revision C,dated March 8, 2001.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10016113

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016114 (EASA.IM.A.S.02304)	ANCRA INTERNATIONAL LLC	REV.1	FAA ST01890LA	737-400 SERIES	Installation of cargo loading system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Ancra International LLC Controlled Drawing List DL84670-10, RevisionB, dated March 22, 2006.	1. STCs EASA.IM.A.S.02438 (FAA SA2968SO), EASA.IM.A.S.02439 (FAASA2969SO) and EASA.IM.A.S.02440(FAA SA2970SO) must be installed in conjunction with this installation. 2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any othe...	18/03/2016	Active	10016114
10016123 (EASA.IM.A.S.02316)	FLYHT AEROSPACE SOLUTIONS Ltd.	REV. 1	TCCA STC SA06-33	A321-111/-112/-211 A320-211/-212/-214/-231/-232 A319-111/-112/-113/-114	AFIRS 220/228 Automated Flight Information Reporting SystemInstallationwith Optional Global Voice and Global Text Satellite Communications	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	-AFIRS 220 system - Master Document List, FlyHT Aerospace document No.121-0029, Revision H, dated 9 August 2014-AFIRS 220 system - Instructions for Continued Airworthiness, FlyHTAerospace document No. 153-0029, Revision E, dated 10 April 2013-AFIRS 228 system - Master Document List, FlyHT Aerospace1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/11/2014	Active	10016123
10016129 (EASA.IM.A.S.02323)	FIELD AVIATION EAST, LTD.	REV. 5	TCCA STC SA07-80	DHC-8-311	Retrofit of Swedish Coastguard Maritime Partol Modifications.Note: Initial EASA Supplemental Certificate was issued with CertificateNumber: EASA.IM.A.S. 02323Revision 01: EditorialChangesRevision 02: Added navAero t-Bag C2 to aircraft configuration.Revision 03: Editorial ChangeRevision 04: Upgrade F...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-02, Service Compartmentthe following paragraph(s) at a later amendment: CS 25.869 at InitialIssueThe requirements for environmental pr...	DHC-8- 311 Baseline ConfigurationInstallation must be performed in accordance with FAEL Master Drawingand Data Lists designated DDL-1141 Rev HH dated September 29, 2021.Flight Operations must be performed in accordance with FAEL FlightManual Supplements as followsFMS 20115 Rev B EGPWS Override Contr...	This STC does not constitute an Operational Approval. IndividualOperational Approvals, including the COTS equipment suitability, must beissued by the competent NAA.UNS-1F Flight Management Systems approved for En-route, Terminal and NonPrecision approach operations only.External Mission LAN System n...	07/06/2023	Active	10016129
10016140 (EASA.IM.A.S.02336)	LEARJET Inc.	REV. 6	FAA SA8164NM-D	BD-700-1A10	Installation of a Complete Custom Aircraft InteriorRev. 5: Addition of ACSN 9049 and an update to the holder’s address.Rev. 6: Addition of ACSN 9023.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA8164NM-D.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	FAA STC No. SA8164NM-D dated 26 August 2002.Bombardier Master Drawing List No. GC90205000 Revision L dated February2002.Airplane Flight Manual Supplements required for this installation arelisted on the approved Bombardier Modification Applicability ListGC-0001-TUS.For Instructions of Continued Airw...	Restricted to ASN 9016, 9020, 9036, 9054, 9098, 9106, 9049,9023.The following STC's are a concurrent requirement with this STC.- EASA STC 10016535 (FAA STC ST00941LA) - Floor Proximity EmergencyEscape Path Marking System is applicable to all aircraft serial numbersapproved under this STC No. 1001614...	09/10/2023	Active	10016140
10016155 (EASA.IM.A.S.02357)	VISIONSAFE LLC	REV. 1	FAA STC ST00731LA	767-200/-300/-300F	Installation of Emergency Vision Assurance System (EVAS)Revision 1: Model B767-300F added	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.853 at amdt 0, CS 25.1713(c) at amdt 5The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original produc...	Master Drawing List 144 Rev C dated June 9, 1999Drawing List 110 rev U dated July 6, 2012AFM supplements:- for B767-200/300: AFMS No. 1 rev. Original dated Sept 1, 2005- for B767-300F: AFMS No 8999-144 rev. Original dated Feb 28, 2013Instructions for Continued Airworthiness Document No. 8017 rev. 10...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/09/2015	Active	10016155

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016174 (EASA.IM.A.S.02401)	TELEDYNE CONTROLS, LLC	REV. 2	FAA STC ST00334LA	747-400	Installation of Aircraft Communications, Addressing and ReportingSystems (ACARS).This STC supersedes EASA.IM.A.S.02401 following a change in theapplicant's address.	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchangedand remain applicable to thiscertificate/ approval.	AFM TDY-ACARS-747-ANA-1 Airplane Flight Manual Supplement, datedDecember 30, 1996.Teledyne Controls Master Data List No. MDL 2231500-14C initial release,dated November 14, 1996.orlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequ...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/04/2016	Active	10016174
10016180 (EASA.IM.A.S.02409)	B/E AEROSPACE, Inc.	REV. 1	FAA ST03394AT	JETSTREAM 4100	Installation of an Avionics Innovations DMP-100/-200 Digital MediaPlayer (DMP) for the reproduction of Boarding Music and Cabin Briefings.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EMTEQ Master Drawing List (MDL) No. 2-43923-001, Rev. D.Instructions for Continued Airworthiness:- 2-43923-902 (Installation)- 2-43923-910 (AMM)- 2-43923-911 (IPC)	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10016180
10016190 (EASA.IM.A.S.02421)	SAFRAN CABIN INC.	REV. 2	FAA ST02144LA	B777-200	Pantry installation P/N C801001-101, P/ N C801001-103 and C802001-101	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing list C801000 rev. F dated April 22, 2008C< (>&<)>D Zodiac drawing List number C802000 Rev. C dated October 20,2008FAA amended STC No. ST02144LAor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decisi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/11/2013	Active	10016190
10016215 (EASA.IM.A.S.02463)	DASSAULT FALCON JET CORPORATION-COMPLETION CENTER– (HANGAR 2 AND	REV. 1	FAA STC ST09304SC-D	MYSTERE FALCON 50 (MF50)	Installation of the Inertial Reference System Modifications(installation of Securaplane XL-245 batteries in lieu of Saft batteriesto provide backup power) in accordance with Drawing List report No.F50-01188 Revision NC dated 23rd July 1999or later approved revisions.		FAA STC ST9304SC-D.Airplane Maintenance Manual Supplement Report No. 36606 (SecuraplaneXL245 Battery) dated 30th June 1999 or later approved revisions.	As per FAA STC ST09304SC-D	04/05/2012	Active	10016215
10016223 (EASA.IM.A.S.02471)	CHEYENNE TECH	REV. 1	FAA SA01379WI	PA-42-720 (CHEYENNE IIIA) PA-42-1000 (CHEYENNE 400LS)	Dual Digital Air Data System Installation Qualified for Operation inRVSM Airspace.Installation number 4 for equipment configuration: Dual Garmin G600integrated display system, AL-285 Altitude Alerter, Skylight ADC-602AAIU, APS-65 FD/AP.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS8000-34254, IR/ 7 September 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.- Master...	This revision 1 is limited to Installation 4 as per MDL8000-34254, Rev.S/ 15 August 2011 for equipment configuration: Dual Garmin G600integrated display system, AL-285 Altitude Alerter, Skylight ADC-602AAIU, APS-65 FD/ AP.Prior to installation of this design change it must be determined thatthe inte...	14/03/2016	Active	10016223
10016227 (EASA.IM.A.S.02479)	ISRAEL AEROSPACE INDUSTRIES, LTD.IAI	REV. 5	CAA ISRAEL STC SA160	B737-400	Major Change to STC 10016227 Revision 4 for the IAI 737-400conversionto freighter aircraft. Update of the MDL TR 365-00-00-B4200 from issue Nto Issue T.All design changes being of level 2 and approved by the CAAI, theworking arrangement (EASA/CAAI 22Nov2004) applies.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	MDL TR 365-00-00-B4200 issue Tor later revisions of the above listed documents approved by EASA	Not Applicable	27/03/2012	Active	10016227

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016239 (EASA.IM.A.S.02508)	BOMBARDIER INC.	REV. 4	TCCA STC SA07-117	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	Installation of Class 2 Electronic Flight Bag (EFB).	EASA TCDS No. IM.A.009The Certification Basis for the original product remains applicable tothis certificate.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate.	EASA STC No. EASA.IM.A.S.02508 (10016239) Rev 2 dated 24 September 2009.TCCA STC No. SA07-117 Issue 6 dated 30 July 2009.TCCA SoC reference C-10-0345 dated 04 May 2010.Aero Consulting Services Modification Data Summary Number F376000Revision M dated 28 April 2010.Bombardier Airplane Flight Manual Su...	This installation approval does not constitute operational approval forany use of the EFB. This approval is for the EFBsystem structuralmounting and interconnect wiring only.	17/02/2011	Active	10016239
10016241 (EASA.IM.A.S.02513)	DECRANE AEROSPACE PATS AIRCRAFT,LLC	REV. 1	FAA STC ST00741LA-D	BOEING 737-700	Installation of Canadian Marconi CMA-2101 High Gain SATCOM Antenna.This STC revises and supersedes EASA STC EASA.IM.A.S. 02513. The revisionwas issued to reflect the transfer from Hollingshead International toDecrane Aerospace PATS Aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Hollingsead Master Data List 12094 Rev. C dated July 02, 1999or later revision of the above document approved by EASA in accordancewith EASA ED decision 2004/04/CF (or subsequent revisions of thisdecision).	None.	18/11/2009	Active	10016241
10016246 (EASA.IM.A.S.02521)	RAISBECK ENGINEERING Inc.	REV. 4	FAA STC SA3593NM	2. C90A, C90GT, C90GTI 1. 65-A90, B90, C90, E90	Installation of Raisbeck/Hartzell Quiet Turbofan Propellersor SweptBlade Turbofan Propellers and optional Increased Gross Weight inaccordance with Raisbeck Engineering Master Drawing List 86-2500.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Installation of Raisbeck/ Hartzell Quiet Turbofan Propellersor SweptBlade Turbofan Propellers, and optional Increased Gross Weight inaccordance with Raisbeck Engineering Master Drawing List 86-2500,Revision AM, dated October 13, 2009;Aircraft must be operated in accordance with the applicable FAA-	Propellers and Propeller Limitations:Either 2 Hartzell HC-D4N-3C Hubs with Hartzell D9290K Blades in Pairs,or 2 Hartzell HC-D4N-3C Hubs with Hartzell D9510SK Blades in Pairs.For 2Hartzell HC-D4N-3C Hubs with Hartzell D9290K Blades in Pairs.Diameter 93.0 in. (Maximum); Minimum allowable for repair:N...	19/02/2016	Active	10016246
10016260 (EASA.IM.A.S.02539)	JET AVIATION ST. LOUIS, Inc.	REV. 1	FAA STC ST02543CH-D	CL-600-2B16 (604 VARIANT)	Installation of a Cabin Interior Arrangement, Passenger Oxygen System,and Emergency Lighting.Rev. 1: Editorial changes including name change and Major Level 2changes from FAA STC.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Jet Aviation St. Louis, Inc. Index List 41-299G004, Revision G, dated1 June 2011 or later FAA approved revision.2. FAA approved Airplane Flight Manual Supplements 41-424M001 RevisionNC, dated 9 April 2008 applicable to configurations 1,2, 3, 4, 5, 6, 8& 9; 41-261M002, Revision A, dated 10 Aprilc...	Restricted to ASN 5701 and subsequent aircraft.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	31/03/2017	Active	10016260
10016263 (EASA.IM.A.S.02543)	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST10316SC-D	GULFSTREAM G150	Installation of an Executive cabin interior in accordance withGulfstream Index List GA322048000.Reason for revision 1: The Satcom system is now an optionalinstallation, revised Limitation and Conditions section, Instructionsfor continued airworthiness more detailed and STC holder addresschanged.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for theSpecial Condition(s):D-03: Side Facing Single Occupant Seat.Equivalent Safety Finding(s):D-04: Frangible Lavatory Door.D-05: Emergency Exit Marker, Locator signs.De...	Gulfstream Index List GA322048000, Rev"-", dated 14 Aug 2006.Flight Manual Supplement GA31204M000, Rev J , dated 12 Nov2007.Instructions for Continued Airworthiness:GA32204A202, Rev "B" dated August 7, 2006 (-101 Configuration);GA32204A206, Rev "A" dated September 26, 2006 (-111 Configuration);GA32...	Installation of this STC requires incorporation of:1) When optional ICG/Iridium Satcom is installed, ICG/Iridium SatcomAntenna is required per STC EASA.IM.A.S.02485 (ST10314SC-D)<(>,<)>2) When optional XM radio system is installed, XM antenna installationis required per STC EASA.IM.A.S.02663 (ST1031...	12/07/2017	Active	10016263
10016292 (EASA.IM.A.S.02588)	SAFRAN CABIN GALLEYS US, INC.	REV. 1	FAA STC ST00843LA	BOEING 757-200 SERIES	Galley installation.		Driessen Master Data List MDLI-101152 Revision C, 23/06/2000.	None.	18/02/2010	Active	10016292

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016295 (EASA.IM.A.S.02592)	STG AEROSPACE Inc.AKA SAFTGLO, Inc.	REV. 2	FAA STC ST03465AT	B737-700/-800/-900 B737-300/-400/-500	Installation of an STG Aerospace PowerSmart Wireless Emergency PrimaryPower System (WEPPS) in accordance with STG Master Drawing List (MDL)No. 71430000	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The certification basis was updated in accordance with FAA policy forsignificant changes in FAA Order 8110.48. FAR 25 Amendment 25-0 thro...	-Master Drawing List (MDL) STG Doc. No. 71430000 Rev. G dated October 5< (>,<)> 2009-Instructions for Continued Airworthiness (ICA) STG Doc. No. 71436006Rev. B dated August 5, 2009-Enhanced Zonal Analysis Procedure (EZAP) Ref. 0710436002 Rev. IR-FAA STC ST03465AT as amended July 29, 2010or later revi...	None	08/08/2011	Active	10016295
10016304 (EASA.IM.A.S.02601)	BOMBARDIER INC.	REV. 1	TCCA STC C-LSA07-285/D	BD-700-1A10	Aircraft Completion, 14 Passenger Interior Configuration.	EASA IM.A.009.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	EASA STC No. EASA.IM.A.S.02601.TCCA STC No. C-LSA07-285/D Issue 1 dated 02 November 2007.TCCA SoC ref. C-10-0426 dated 01 June 2010.Aero Consulting Services Modification Data Summary F461000 Revision Adated 27 April 2010.Aero Consulting Services Flight Manual Supplement G-FM25000160 RevisionNC or la...	Restricted to ASN 9237.This does not constitute an operational approval of the Wireless LocalArea Network (WLAN) system. It is the operator's responsibility toobtain operational approval for the airborne use of transmittingportable electronic devices in accordance with the operating rules ofthe appl...	07/06/2010	Active	10016304
10016312 (EASA.IM.A.S.02616)	ASTECH ENGINEERED PRODUCTS Inc.	REV. 1	FAA STC SA5818NM	MD-88	FAA STC SA5818NM “Installation of Astech/MCI tailpipe assembly.Rev. 1: Transfer form "GKN Chem-Tronics, Inc." to "Astech EngineeredProducts, Inc."	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Astech/MCI doc. no. ER-92-716 „Drawing list - MD 80 Series tailpipe, RevN/C dated July 10, 1992<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalfof EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/08/2024	Active	10016312
10016316 (EASA.IM.A.S.02622)	BOMBARDIER INC. - COMPLETION CENTREMONTREAL	REV. 7	TCCA STC SA07-119	BD100 CHALLENGER 300	Installation, In-Service Improvement ModificationsIn-service design improvements to cabin interior featuresRevision of the EASA STC 10016316, Rev. 6 due to revised technicaldata (Modification Data Summary F344000 Rev. H)	EASA TCDS IM.A.080 Issue 3, 26th October 2010The Certification Basis for the original product remains applicable tothiscertificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain ap...	- Transport Canada Supplemental Type Certificate SA07-119 Issue 2, dated20th October 2010.- Transport Canada Approved Aero Consulting Services Ltd. ModificationData Summary F344000 Revision H, dated 28th September 2010or later revisions ofthe above listed documents approved by EASA inaccordance wit...	Not applicable	28/10/2010	Active	10016316
10016318 (EASA.IM.A.S.02624)	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02404NY-D	B767-300	Installation of Panasonic Avionics Overhead In-Flight EntertainmentSystem	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateAs defined in the TCDS plusthe following for changed areasFAR Section,,Title,,At Amendment,,§25.831,,Ventilation, ,25-89,,§25.853,,Compartment inter...	MDL 0144-06099-2153, revision F, 08/10/2010ICA 0744-06105-2153, Rev Cor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Limited to installation on aircraft already fitted with HeathTechnaNuLook interior (Configuration 4) ref EASA STC IM.A.S.02474	11/02/2011	Active	10016318

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016319 (EASA.IM.A.S.02627)	B/E AEROSPACE, Inc. - FSI	REV. 6	FAA ST01950SE	777-200	Installation of an overhead flight crew rest above Door 1Rev 5: The new OFCRs will have B/E Lighting and Integrated Systems (B/ELIS) LED lighting and Panasonic Avionics (PAC) IFE components installedcompatible with the IFE system installedunder concurrent main deck B/E– FSI STC 10064791.Rev. 6: cor...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- As per TCDS and the following requirements at a later amendment:JAR 25 at change 13: 25.811 (b)(c)(d)(1)(2)(g), 25.812(a)(1)(b)(1)(i)(c)(e)(i), Appendix F Part IICS 25 a...	Master Drawing List A7FS700-D01 rev BKAFM Supplement TP07-700AFM rev 2B/E-FSI Top Collector A700000-001 rev CICA Supplement A7FS700-D15 rev L.B/E-FSI Top Collector B761000-0001 rev -	- Boeing Service Bulletin 777-25-0429, dated October 15, 2008.- Boeing Service Bulletin 777-21-0191, Revision Original Issue, datedDecember 2, 2019 and the following Boeing Installation DeviationRecords: 777-21-0191-WB037-0001, dated December 24, 2019777-21-0191-WB037-0002, dated August 18, 2020777-2...	09/10/2020	Active	10016319
10016332 (EASA.IM.A.S.02641)	BOMBARDIER AEROSPACE	REV. 1	TCCA C-LSA07-229/D	BD-700-1A11	Installation, Interior Completions In-Service Improvement Modificationsfor ASN 9249.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	-EASA STC no. EASA.IM.A.S.02641-TCCA STC no. C-LSA07-229/D Issue 1 dated 19 December 2007-ACS-NAI Ltd. Modification Data Summary F428000 Revision B or laterapproved revision.- Bombardier Airplane Flight Manual Supplement G-FM25000163 Revision N/C.-Instructions for Continued Airworthiness GC92490000-I...	Restricted to ASN 9249	20/04/2011	Active	10016332
10016347 (EASA.IM.A.S.02664)	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC ST01248CH	BAE 125 SERIES 1000B BAE 125 SERIES 1000A	Installation of an air ambulance conversion	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01248CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Spectrum Aeromed Inc. Drawing 6036-DMS, No Revision, dated Janury 26,2000 or later revision of the above listed document approved by EASA inaccordance with EASA ED decision 2004/04/CF (or subsequent revisions ofthis decision).- AFM Supplement dated August 4, 2007 or later approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2019	Active	10016347
10016348 (EASA.IM.A.S.02666)	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC ST01607CH; LBA STC TA0	31, 31A, 35 , 35A	Installation of an air ambulance conversion	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01607CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Spectrum Aeromed Inc. Drawing 6017-DMS-Z1, Revision 2, dated December 2, 2001 or later revision of the above listed documents approved by EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).	1. AFM Supplement dated December 7, 2001 or later approved revision isrequired.2. Installation requires previous or concurrent installation per LBA STCTA0512 (STC ST01026WI).3. Prior to installation of this design change it must be determinedthat the interrelationship between this design change andp...	23/04/2019	Active	10016348
10016349 (EASA.IM.A.S.02668)	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA00882CH	SEE FAA AML	Install Air Ambulance Conversion	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00882CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Sprectrum Aeromed Inc. drawings as listed on AML SA00882CH,dated 28February 2019, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	24/04/2019	Active	10016349

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016350 (EASA.IM.A.S.02669)	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA00972CH	PA-42, PA-42-1000, PA-42-720	Install Air Ambulance Conversion	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00972CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Spectrum Aeromed Master Drawing List 6004DL, Revision 2, dated 10 July2012, or later FAA approved revision.- AirplaneFlight Manual Supplement, 6004FMS, Revision 2, dated 22August 2012, or later FAA approved revision.- Instructions for Continued Airworthiness, Manual 6004MM, No Revision,dated 10 J...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/04/2019	Active	10016350
10016379 (EASA.IM.A.S.02703)	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01431WI-D	SEE EASA APPROVED MODEL LIST	EASA validation of FAA STC ST01431WI-D. Modification of a RockwellCollins, Inc. Data Base Unit (DBU) installation, in accordance withRockwell Collins, Inc. Drawing Index RCA-0123-001 Rev G or laterapproved revisions.The FAA STC ST01431WI-Dwas initially validated by EASA on 15th October2008. This in...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rockwell Collins, Inc. Drawing Index RCA-0123-001 Rev G, andSee the associated EASA Approved Model List (AML) attached to thisapproval certificate which contains the list of aeroplane models onwhich this airworthiness approval applies, theapplicable installationdata requirements and specific limita...	See those of original FAA STC ST01431WI-D as well as those of thedocuments listed above under associated technical documentation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/...	24/05/2017	Active	10016379
10016381 (EASA.IM.A.S.02705)	BLACKHAWK MODIFICATIONS Inc.	REV. 1	FAA SA10560SC	C90GTI	Installation of Wing Mounted Auxiliary Fuel Transfer Tank in BeechC90GTi. This project is to amend EASA STC No. EASA.IM.A.S.02705.	CS-23	Installation of Wing Mounted Auxiliary Fuel Transfer Tank in accordancewith Master Drawing List No. 8007-II-000, Rev. B, dated 13. December2008 or later approved revision.Type Design Data is provided in Master Drawing 8007-00-000, Rev. C,dated 13. December 2008 or later approved revision.Operation m...	None	16/09/2011	Active	10016381
10016387 (EASA.IM.A.S.02715)	LEARJET Inc.	REV. 1	FAA ST01737LA-D	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10 BD-700-1A10	Installation of Honeywell / EMS HD-710 High-Speed Data Satcom System.Rev. 1: Additional of -2 Configuration for MCS-7120 SATCOM Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01737LA-D dated 23 September 2023.The requirements for environmental protection and the associatedcertified noise and/ oru...	Flight Manual Supplement BAS67040130, Revision NC, dated 06June 2007Master Document List BAS67010038, Rev. G, dated 20September 2023Maintenance Instructions for Continued Airworthiness (ICA)- for the for the MDL BAS67010038-1 Configuration is contained inDocument BAS67010038-IFCA-1,Revision NC, da...	The installation of an EASA approved Router/ LAN System is aprerequisite/ concurrent requirement to the installation ofthe -1 and-2 Configuration.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installede...	11/10/2023	Active	10016387
10016394 (EASA.IM.A.S.02723)	APB WINGLETS COMPANY, LLC	REV. 7	FAA STC ST01920SE	BOEING 767-300, -300F	Installation of Aviation Partners Boeing Winglets, wing structuralreinforcement and related system changes (formerly IM.A.S.02723)Revision 4: compatibility with BCF modification as per STC 10043661 isconfirmed. CRI A-01 updated. Associateddocumentation updated.Replacement of LED modules:-P/N 32-45...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:As detailed in CRI A-01 Issue 7 dated 06 Aug 2015,the followingapplies:-,,For parts changed or affected by this STC the Certification Basisbaseline is EASA CS 25 amendmen...	Approved Model Lists: - 767-300 and -300BCF „Partial Wing Retrofit Installation(767-300-1 Kit)“: AP67.3-AML1920 RevIR, 15th October 2008 - 767-300F „Partial Wing RetrofitInstallation (767-300F-1 Kit)“:AP67.3F-AML1920, 8th July 2009 - 767-300 and -300BCF „Winglet Installation (767-300-2...	Operational/ Performance limitations are defined within theAFMsupplement.This STC is approved for a/c equipped with General Electric CF6-80C2series engines or Pratt and Whitney PW 4000 series engines with noengine strut vibration isolators installed only.The STC is approved for 767-300F airplanes t...	10/08/2015	Active	10016394

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016397 (EASA.IM.A.S.02726)	ROCKWELL COLLINS, Inc.	REV. 1	FAA SA01430WI-D	SEE APPROVED MODEL LIST	Modification of a Collins DBU-4000 or DBU-4100 Data Base Unitinstallation to a Collins DBU-5000 Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with: Collins Master Drawing List ref AML NoEASA.IM.A.S.02726, dated 15 October 2008, or later approved revision;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ o...	1. Prior installation of Collins DBU-4000 part numbers 622-9865-001/-002or DBU-4100 part numbers 822-0014-101/-102/-103/-104 is a prerequisiteto this STC.2. Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and anyother previo...	14/02/2017	Active	10016397
10016400 (EASA.IM.A.S.02729)	ROCKY MOUNTAIN AIRCRAFT	REV. 1	TCCA STC SA07-131	DHC-6-100, DHC-6-200,DHC-6-300	Installation of single or dual Sandel SN4500 primary navigationdisplay(s) (EHSI) with optional SA4550 primary attitude display(s)(EADI)	FAR 23	-Installation in accordance with Rocky Mountain Aircraft (RMA)Modification Instruction E100010, Rev-, Transport Canada Civil Aviation(TCCA) approved March 10, 2010, or later approved revisions.- Operation in accordance with Rocky Mountain Aircraft (RMA) FlightManual Supplement E100030, Rev-, Transpor...	None	03/08/2010	Active	10016400
10016403 (EASA.IM.A.S.02732)	BLACKHAWK MODIFICATIONS Inc.	REV. 1	FAA SA10737SC	B. B200CT, B200T B. A200, A200C, A200CT B. 200, 200C, 200CT, 200T A. B200, B200CT	Installation of Pratt and Whitney PT6A-61 engines in Beech 200 Series.This project is to amend EASA STC No. EASA.IM.A.S. 02732.	CS-23	-Installation of Pratt & Whitney PT6A-61 engines in accordance withMaster Drawing List No. 06010050, Rev. B, dated 27. May 2008 or laterapproved revision.-Operation must be in accordance with Aircraft Flight Manual Supplementcontained in Drawing No. 06010000 Rev. B dated 27. May 2008 or laterapprove...	None	05/07/2010	Active	10016403
10016409 (EASA.IM.A.S.02741)	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY	REV. 5	FAA STC ST02112LA	SEE FAA AML A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-231/-232/-233 A320-111/-211/-212/-214 A319-115/-131/-132/-133 A319-111/-112/-113/-114 A318-111/-112/-121/-122	Installation of Cabin Interior Noise Reduction Kit.Revision5: Addition of model A319-153N in the applicability list.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List AC25-NRA319-1000 Rev. K, dated July 11,2012Instruction for Continued Airworthiness MMS-A319-1380 Rev. E, datedJanuary 4, 2011or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/07/2020	Active	10016409
10016410 (EASA.IM.A.S.02742)	ROSEMOUNT AEROSPACE, Inc.	REV. 3	FAA STC ST02649CH	A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-231/-232/-233 A320-111/-211/-212/-214 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of Rosemount Aerospace 8700C2-4 Laptop DockingStation - Electronic Flight Bag (EFB) System Provisions.A319/ A320 / A321 Series 8700C2-4 Laptop Docking Station (LDS) - Electronic Flight Bag (EFB) System Provisions.Revision of the EASA STC 10016410 Rev. 2 to add new aircraft serialnumber e...	Certification Basis in accordance with EASA Type Certificate Data SheetsA.064.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI F-01 "Installed Resources for EFB Class 2 Provisions"...	- FAA STC ST02649CH amended July 13, 2009- Rosemount Aerospace Master Data List, ref. doc. No. D06402677,Revision L, dated 9th November 2010- FAA Approved Airplane Flight Manual Supplement (AFMS), ref. Rosemount Aerospace Doc. D06402688, Revision B, dated 13th July 2009- Rosemount Aerospace EAPAS An...	Not applicable	18/11/2010	Active	10016410

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016419 (EASA.IM.A.S.02752)	FIELD AVIATION COMPANY Inc.	REV. 3	TCCA C-LSA06-010/D	DHC-8-311	Installation of a 320cuft baggage compartment and installation of PBE'sand O2 bottle into the cabin (Ref. TCCA LSTC C-LSA06-010/D).		Installation of 320cuft baggage compartment must be performed iawModification Instruction 202410 Revision C*) Installation of O2 bottle and PBE into the cabin must be performed iawModification Instruction 202610 Revision C*)Maintenance mustbe performed iaw DHC-8-300 Maintenance Manual PSM1-83-2 sect...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/05/2017	Active	10016419
10016423 (EASA.IM.A.S.02761)	BOMBARDIER Inc.	REV. 42	TCCA SA04-112	BD-100-1A10	Installation of Complete Customized Aircraft Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):TCCA SCA 2020-04 Dated 8 october 2020D-10053642-1 Issue 1: Installation of large glass items in the cabin- Equivalent Safety Finding(s):D-08 Issue 2...	According Aero Consulting Services Ltd. Configuration Definition ListRef D921000 Rev AMT dated 11 Oct 2019To be operated iaw. Aero Consulting Services Ltd.- AFMS D921090 Rev F and/orTo be maintained iaw.- For specific aircraft applicability of the Instructions for ContinuedAirworthiness as reference...	See those of TCCA STC SA04-112.The EASA approved configurations are identified in the ConfigurationDefinition List document Ref D921000Aircraft issued with a CofA on or after 18 May 2019 must be equippedwith Halon Free extinguishersPrior to installation of this change/repair it must be determined th...	10/10/2022	Active	10016423
10016430 (EASA.IM.A.S.02769)	FIELD AVIATION COMPANY Inc.	REV. 1	TCCA STC C-LSA08-056/D	DHC-8-202, DHC-8-311	Honeywell AHRS to SFIM APIRS Conversion ProvisionsTCCA STC C-LSA08-056/D, Issue 2	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation of the Conversion Provisions for Honeywell AHRS to SFIMAPIRS Retrofit must be in accordance with TransportCanada CivilAviation (TCCA) approved Field Aviation Companyinc (FACi) ModificationInstructions 215710, Revision B, dated Nov 7, 2011 revision.Conversion from SFIM APIRS back to th...	Installation is limited to Serial Numbers 435, 440, 441 and407	23/05/2012	Active	10016430
10016433 (EASA.IM.A.S.02773)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03462AT	767-200/-300/-400	Install the RAAS software in the Runway Awareness & Advisory System (RAAS).Revision 1 transferred from EMTEQ Engineeringto B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement, EMTEQ Document No. 2-41556-814, Rev IR, 07th November2007.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or theTechnical Implementation Procedures of EU/USA Bilateral Agre...	This STC is only valid for software versions -224-224 to -226-226.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthine...	02/03/2016	Active	10016433
10016434 (EASA.IM.A.S.02774)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03461AT	757-200/-300	Installation of the Honeywell Runway Awareness & Advisory System (RAAS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement, EMTEQ Document No. 2-41556-807, Rev IR, 27th November2007or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agree...	This STC is only valid for software versions -224-224 to -226-226.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthine...	02/03/2016	Active	10016434

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016440 (EASA.IM.A.S.02781)	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03535AT-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5177.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514915177, Rev. F, dated March 31,2008 or later FAA approved revision.	Aircraft Serial Number 5177 only.The following STC's are a required part of this STC:ST02796AT-T,ST02697AT-D,ST02715AT-D,ST03290AT-D,ST03238AT-Dand ST02696AT-D.It is the installers' responsibility to ensure these STC's are all EASA approved.	06/10/2010	Active	10016440
10016441 (EASA.IM.A.S.02786)	ASTECH ENGINEERED PRODUCTS Inc.	REV. 1	FAA STC ST01898LA	AIRBUS A321 AIRBUS A320 AIRBUS A319 A319_A320_A321	Installation of ASTECH Engineered Products fan cowl door inaccordancewith ASTECH's Master Drawing List V2500 Cowl DoorAssembly No.MDL030-16103, Revision "A".Rev. 1: Transfer from "GKN Chem-Tronics, Inc." to "Astech EngineeredProducts, Inc."	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Master Drawing List V2500 Cowl Door Assembly Drawing List ref. No.MDL030-16103, Revision A, dated 18 April 2006<(>,<)>Engineering Order ref. No. 030-16103, Revision C02, dated 2 November2006<(>,<)>Component Maintenance Manual, ref. No. ER05-941, Revision A, dated 2June 2006<(>,<)>or later revisionsb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/08/2024	Active	10016441
10016447 (EASA.IM.A.S.02793)	SIERRA INDUSTRIES Ltd.	REV. 1	FAA STC SA8829SW	CESSNA 550 CITATION II CESSNA 500	Installation of Inertial Reel Assy.´s on Pilot and Co-PilotShoulderHarnessIn accordance with Sierra Master Drawing List, SI220-000, rev. A, date28 March 1994.Validation of FAA approval STC SA8829SW.This is an amendment to EASA.IM.A.S.02793 to include Cessna Model 500 asan approved model.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Sierra Master Drawing List, SI220-000, rev. A, date 28 March 1994;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	06/12/2012	Active	10016447
10016458 (EASA.IM.A.S.02804)	BOMBARDIER COMPLETION CENTRE INC	REV. 3	TCCA STC NO. SA04-113	BD-700-1A10	Customized Interior Completion - ACSN 9272.	EASA TCDS No. IM.A.009 - The certificated noise and/or emissions levels of the originalproduct are unchanged and remainapplicable to this approval.	1. TCCA SoC letter C-09-0997 dated 24 November 2009.2. AeroConsulting Services Configuration Definition List D954000Revision CA dated 25 November 2008.3. Bombardier Airplane Flight Manual Supplement G-FM25004001 Revision B.4. Instructionsfor Continued Airworthiness GC92720000-IFCA.Or later revisio...	1. Restricted to ACSN 9272.2. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.3. WLAN systems are compatible only to IEEE 802.11(b).	18/12/2009	Active	10016458
10016460 (EASA.IM.A.S.02806)	RAISBECK ENGINEERING Inc.	REV. 1	FAA STC SA4362NM	B200CT, B200T A200C, A200CT, B200, B200C, 200, 200C, 200CT, 200T, A200,	Installation of Butterfield Industries Oil Residue Collection System KitP/N BI 1011-1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original certificate/approval.	- Installation Data Package BI 1013, Revision C, dated 20 December 2017or later approved FAA versions-Drawing List BI 1012, Revision D, dated 4 November 2013 or later FAAapprovedversions.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.	06/08/2018	Active	10016460
10016461 (EASA.IM.A.S.02807)	RAISBECK ENGINEERING Inc.	REV. 1	FAA STC SA00829CH	B200CT, B200T A200C, A200CT, B200, B200C, 200, 200C, 200CT, 200T, A200,	Installation of Butterfield Industries Air/Oil Separator System Kit P/N BI 6001-1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation Data Package BI 6003, Revision H, dated 12 November 2007or later FAA approved versions-Drawing List BI 6004, Revision I, dated 12 November 2013 or laterapproved FAA versions.	- Aircraft which are not modified by STC SA4362NM, will also requireinstallation of an oil collection tank;- Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no ad...	06/08/2018	Active	10016461

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016462 (EASA.IM.A.S.02808)	GOODRICH INTERIORS	REV. 1	FAA STC ST01788LA	MD-88, MD-90-30. DC-9-87 (MD-87), DC-9-83 (MD-83), DC-9-82 (MD-82), DC-9-81 (MD-81),	Installation of Sentry One Flight Deck Door Surveillance Camera System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Hollingsead International Master Data List No. 2788-01 dated 15 March2005- Flight Manual Supplement Document No. 2788-AFM dated 03 May 2005or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None	08/11/2012	Active	10016462
10016464 (EASA.IM.A.S.02810)	SIERRA INDUSTRIES Ltd.	REV. 1	FAA STC ST09011SC	CESSNA CITATION 550 AND S550 CESSNA 500	Pilot's Control Wheel Mounted Alternate Gear Horn Silence Switch.In accordance with Sierra Master Drawing List, SI260-000, rev. IR, date25 Jan 1994.Validation of FAA approval STC ST09011SC.Amend EASA.IMAS.02810 to include the Cessna Model 500 as an approvedmodel.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ref. LBA STC nr. STA 1309 of 30 January 2003;Sierra Master Drawing List, SI260-000, rev. IR, date 25 Jan 1994;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2013	Active	10016464
10016465 (EASA.IM.A.S.02811)	SIERRA INDUSTRIES Ltd.	REV. 1	FAA STC SA09229SC	CESSNA S550 (CITATION S/II) CESSNA 550 CITATION II CESSNA 500	Installation of Gas Cylinder Nose baggage Door OpenersIn accordance with Sierra Master Drawing List, SI380-000, rev. C,date24 Sept 1996.Validation of FAA approval STC SA09229SC.This is an amendment to EASA.IM.A.S.02811 to include Cessna Model 500 asan approved model.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Sierra Master Drawing List, SI380-00, rev C, date 24 Sept. 1996;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (orsubsequent revisions ofthis decision).	None.	06/12/2012	Active	10016465
10016476 (EASA.IM.A.S.02826)	BOMBARDIER AEROSPACE	REV. 2	TCCA SA08-35 ISSUE 3	BD-100-1A10	Observer Seat Installation, Model 409-0001 /Installation ofan observer seat between the avionics racks, forward ofthe main passenger cabin.Revision of EASA STC 10016476, Rev. 1 due to revised technical data(Modification Data Summary F797000 Rev. D).	Certification Basis as per EASA TCDS IM.A.080 Issue 2, 8th October 2008The Certification Basis for the original productremains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product a...	- Transport Canada Supplemental Type Certificate SA08-35 Issue 3, dated4th November 2010.- Transport Canada Approved Aero Consulting Services Ltd. ModificationData Summary E797000Revision D, dated 1st November 2010.- Transport Canada Approved Aero Consulting Services Ltd Airplane FlightManual Suppl...	Observer Seat for crew use only	21/01/2011	Active	10016476
10016477 (EASA.IM.A.S.02828)	BOMBARDIER AEROSPACE	REV. 1	TCCA STC SA08-58 ISSUE 2	CL600-2B16 (604 VARIANT)	Installation of AVS-470 Tail Camera System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aero Consulting Services Modification Data Summary F782001 Revision A- Instruction for Continued Airworthiness Document F396-IFCA Revision Blor later revisions of the above listed documents approved by EASA inaccordance with the Canada/EU TIP for Airworthiness and EnvironmentalCertification.	For Configuration -2, -3 and -5, the modification defined by SA97-71must be embodied as a prerequisite.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce nou...	11/06/2013	Active	10016477
10016478 (EASA.IM.A.S.02830)	BOMBARDIER AEROSPACE	REV. 4	TCCA SA04-113	BD-700-1A10	Aircraft Completion, 13 Passenger Interior Configuration	EASA IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-EASA STC No. IM.A.S. 02830 (10016478) Revision 2 dated 17 June 2010.- TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.-Aero Consulting Services Configuration Definition List D954000 RevisionGG dated 18 February 2011.-Instructions for Continued Airworthiness GC92740000-IFCA.or later revisions of t...	Restricted to ASN 9274 and1) Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2) WLAN system is compatible only to IEEE 802.11(b).	12/04/2011	Active	10016478

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016495 (EASA.IM.A.S.02857)	SMA AERO ENGINES GMBH	REV. 1		182R 182Q, 182R 182Q	Installation of of Société de Motorisations Aéronautiques (SMA) AircraftDiesel Engine (ADE) model SR305-230-1 (or SR305-230 converted to modelSR305-230-1 by incorporation of SMA Service Bulletin SB-01-76-002), MTPropeller model MTV-9-BS/198-58B propeller and other minormodifications.Rev. 1: Transfer...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation Instructions “SMA Engines Inc. Airplane Installation Manualfor Cessna 182 fitted with an SMA SR305-230-1 Engine” Rev. Basic Issuedated June 30, 2006SMA Master DrawingList SP01170314-0 Rev B, dated June 9, 2006SMA Pilot’s Operating Handbook and Airplane Flight Manual Supplement,dated No...	Cessna model 182Q airplanes eligible for this approval are:S/N’s18263479, and 18265966 through 18267715, except for 18267302.Cessna model 182R airplanes eligible for this approval are S/N’s18267716 through 18268586, and 18267302.Prior to installation of this change/repair it must be determined that...	14/04/2021	Active	10016495
10016501 (EASA.IM.A.S.02863)	BEECHCRAFT CORPORATION	REV. 5	FAA SA10747SC	2. C90, E90 1. C90A, C90GT, C90GTI	Increase Operating Gross Weight Approval(as defined in the attached table)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Increase in gross weight installation in accordance with Cen TexAerospace Incorporated (Inc.) Drawing No 030-0000-0000, Rev G.-Operation in accordance with Cen Tex Aerospace Incorporated (Inc.)Aircraft Flight Manual Supplement defined in Drawing No 030-0000-1000,Rev G.-For C90A (PT6A-135A), C90GT a...	None	09/02/2015	Active	10016501
10016505 (EASA.IM.A.S.02869)	GOODRICH INTERIORS	REV. 1	FAA STC ST01007LA-D	737-800	Installation of Hollingsead Sentry One Cabin Video Camera System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Hollingsead International Drawing List 2712-02, Revision A dated03/06/2003- Flight Manual Supplement Hollingsead International Inc. document No.2712-AFM, revision N/C dated 03/06/2003or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or...	None	08/11/2012	Active	10016505
10016517 (EASA.IM.A.S.02888)	ROCKWELL COLLINS, Inc.	REV. 1	FAA SA01434WI-D	SEE APPROVED MODEL LIST	Modification of Collins GPS-4000 or GPS-4000A Global Positioning Sensor (GPS) system installation to a Collins GPS-4000SGlobal PositioningSensor (GPS) system installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Collins Drawing Index RCA-0124-001 Rev-A, dated February 14th, 2007,or latest revision level of the Drawing Index- AFM Supplement ACC-07-009 Rev-A dated April 2nd, 2007 or laterFAAapproved revisions;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decisi...	1. This STC does not approve WAAS LPV.2. Prior FAA approvedinstallation of Collins GPS-4000 part numbers822-0931-001/-002/-003 or GPS-4000A part number 822-1377-001 is aprerequisite to this STC.3. Prior to installation of this modification the installer mustdetermine that the interrelationship betw...	15/02/2017	Active	10016517
10016518 (EASA.IM.A.S.02889)	ROCKWELL COLLINS, Inc.	REV. 2	FAA ST01433WI-D	SEE EASA APPROVED MODEL LIST	Modification of Rockwell Collins GPS-4000 or GPS-4000A - RockwellCollins GPS-4000S Global Positioning Sensor installationRevision 1 due to additional models applicability.Revision2 due to correction of model list.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA STC ST01433WI-D, amended January 24th 2012;- FAA Approved Model List (AML), RCA-0396, Revision J, November 6th,2012;- Collins Drawing Index, ref. Doc. RCA-0125-001, Rev. K;Airplane Flight Manual Supplement, ref. Doc. ACC-07-010, Rev.B or laterrevisions of the above listed document(s) approved...	None	21/03/2019	Active	10016518

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016523 (EASA.IM.A.S.02896)	GOODRICH INTERIORS	REV. 1	FAA STC ST01638LA	737-300, 737-400, 737-500	Installation of Hollinsead Sentry One Cabin mounted Video Camera System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Hollingsead International Master Data List 2767-01, Revision NC dated18/05/2004- Flight Manual Supplement HollingseadInternational Inc. document No.2767-AFM, revision Original dated 02/06/2004or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004...	None	07/11/2012	Active	10016523
10016535 (EASA.IM.A.S.02912)	BRUCE AEROSPACE Inc.	REV. 1	FAA STC ST00941LA	BD-700-1A10	Installation of Floor Proximity Emergency Escape Path Marking System.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	EASA STC No. EASA.IM.A.S.02912 dated 15 September 2008.FAA STC No. ST00941LA dated 07 May 2008.Bruce Aerospace Master Drawing List No. 710-002 at the followingrevisions:-Rev G, Item 1, dated 1 May 2000-Rev L, Item 4, dated 7 July 2000-Rev AN, Item 22, dated 14 March 2001-Rev BF, Item 33, dated 21 No...	Seat Mounted Proximity Lighting System:-Exit identifiers and flood lights (e.g. part number BR9279-series): aminimum oftwo out of five lamps in each part must be operative.-All light modules (e.g. part number BR9644-series): a minimum of oneout of two lamps in each part must be operative.	30/06/2011	Active	10016535
10016544 (EASA.IM.A.S.02923)	BOMBARDIER Inc.	REV. 5	TCCA SA08-48	BD-700-1A10, BD-700-1A11	Installation, Interior Completions In-Service Improvement Modifications	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA SoC ref. C-11-0232 dated 27 April 2011TCCA STC No. SA08-48 Issue 2 dated 27 August 2009ACS-NAI Ltd. Modification Data Summary Number F727000 Revision H orlater approved revisionor later revisions of the above listed documents approvedby EASA inaccordance with EASA ED Decision 2004/02/CF (or su...	None	11/05/2011	Active	10016544
10016549 (EASA.IM.A.S.02929)	JETAIRE AEROSPACE, LLC	REV. 2	FAA STC ST01466LA-D	B737-300/-400	Installation of fire protection systems, lower cargo compartment Class Dto Class C conversion.Original FAA STC ST01466LA-D for B737-300;this revision is implementing the validation of FAA STC ST00749LA-D forB737-400.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	B737-300:- Hollingsead International Master Data List No. 2708-01, Revision NC,dated 26 JAN 2004-Hollingsead International FAA Approved Flight Manual Supplement No. 2708-AFM, Revision NC, dated 26 JAN 2004-Hollingsead International Instructions for Continued Airworthiness No.2708-14, Revision C, da...	None.	29/08/2012	Active	10016549
10016559 (EASA.IM.A.S.02944)	BLACKHAWK MODIFICATIONS Inc.	REV. 1	FAA SA5786SW	425 (CONQUEST)	Installation of Pratt and Whitney Canada (P<(>&<)>WC) PT6A-135 orPT6A-135A engines and McCauley 4HFR34C762/94LMA-4 propellers on theCessna 425 airplanes considering current ICAO Annex 16 Chapter 10 noiselevel.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	BMI AFM Supplement CE-425-1, Rev. A, FAA approved September7, 1999Engine instrument markings iaw. FAA STC SA5786SWEngineering Drawing List DL425000, Rev. 1 dated August 13, 1984;BMI report (201410-016 Rev IR) Acoustical Substantiation of C425 asmodified by EASA STC IM.A.S.02944.	Engine and propeller limits refer to FAA STC SA5786SWPrior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willintroduce noadverse effect upon the airworthiness of the pro...	19/11/2014	Active	10016559

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016565 (EASA.IM.A.S.02956)	BOMBARDIER INC.	REV. 1	TCCA STC C-LSA03-458/D	BD-700-1A10	Installation of Thales Integrated Electronic Standby Instrument withGoodrich PS-855B Emergency Power Supply	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Refer to original Transport Canada Supplemental Type CertificateC-LSA03-458/D Issue 3, initially approved on 30th September 2003. TheIssue 3 of the TCCA STC is dated 01st October2013 which is the revisionstatus validated through this EASA approval certificate.Modification to be completed in accord...	The Transport Canada's STC C-LSA03-458/D at issue 1 was originallyvalidated by EASA through STC EASA.IM.A.02956 which was issued on 23rdDecember 2008, and both STC's were initially restricted to aircraftserial number (ASN) 9120.The TCCA STC C-LSA03-458/D last issue 3 is now applicable to ASN 9003and...	18/12/2013	Active	10016565
10016571 (EASA.IM.A.S.02969)	ASTECH ENGINEERED PRODUCTS Inc.	REV. 1	FAA STC ST01578LA	AIRBUS A320-212 AIRBUS A320-211 AIRBUS A320-111 AIRBUS A319-114 AIRBUS A319-113 A320-211, A320-212 A319-113, A319-114	Installation of ASTECH Engineered Products, Inc. Inlet Inner BarrelAssembly in accordance with Master Drawing List, A320/CFM56-5ASeries Engine Inlet, Drawing List Number MDL030-11030 Revision C.Rev. 1: Transfer from "GKN Chem-Tronics, Inc." to "Astech EngineeredProducts, Inc."	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Master Drawing List A320 CFM56-5A Series Engine Inlet, ref.No.MDL030-11030, Revision C, dated 2 April 2008<(>,<)>Engineering Order ref. No. 030-11002, Revision D, dated 2 April 2008<(>,<)>or later revisions of the above listed document(s)approved/ accepted onbehalf of EASA in accordance with the Te...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/08/2024	Active	10016571
10016576 (EASA.IM.A.S.02974)	MICRO AERODYNAMICS, INC.	REV. 1	FAA STC SA01266SE	PIPER PA-32R-301(SP) PA-32R-301(HP), PA-32R-301T PA-32-301, PA-32-301T PA-32-301FT, PA-32-301XTC	Installation of vortex generators on the wings and tail surfaces inaccordance with the provisions of AML SA01266SE.	CS-23	Installation of vortex generators on the wings and tail surfaces of theabove model Aircraft in accordance with Micro AeroDynamics DrawingPackage MA2188, Revision A, dated 26 October 2009 and InstallationManual MA2189, Revision B, dated 26 October 2009 or later EASA approuvedrevisions.A copy of thisp...	If more than five vortex generators are damaged or missing,the Aircraftis not airworthy.	10/02/2010	Active	10016576
10016578 (EASA.IM.A.S.02977)	LIFEPORT, LLC	REV. 1	FAA STC SA00528SE	PA-42, PA-42-1000 PA-31T2, PA-31T3, PA-31P-350, PA-31P, PA-31T, PA-31T1, PA-31, PA-31-300, PA-31-350,	Emergency Medical System (The Emergency Medical System attaches only to the existing aircraft seat tracks. The system will be a free standing unit that can be rapidly installed and removed from the cabin).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- FAA Approved Flight Manual Supplement AFMS for Life Port PLUS System,Supplement No.13, Rev. E, July 21 2004.- Master Drawing List for PLUS/Aero Sled Installation in the Piper PA-31and PA-42 Series Aircraft, Doc. Nr. EGR-556-00, FAA Approved 20. June2008.- Instructions for Continued Airworthiness f...	None.	30/04/2010	Active	10016578
10016580 (EASA.IM.A.S.02984)	RAISBECK ENGINEERING Inc.	REV. 2	FAA SA3857NM	B200GT, B200CGT B200C, B200CT, B200T A200, A200C, A200CT 200C, 200CT, 200T 200, B200	Installation of nacelle overwing storage lockers and lower flap fairing.		1. Installed in accordance with Raisbeck installation manualInstallation Manual 200-5421 Rev. D, dated November 5, 20072. Approved Flight Manual Supplement 87-105 Rev. C dated December 20073. Instructions for Continued Airworthiness ref. Raisbeck MaintenanceManual 85-120 Rev. G, dated January 20084....	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	19/09/2019	Active	10016580

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016582 (EASA.IM.A.S.02987)	RAISBECK ENGINEERING Inc.	REV. 2	FAA STC SA4010NM	2. C90A, C90GT, C90GTI 1. 65-90, 65-A90, B90, E90	Installation of dual aft body strakes on the 90 series KingAir aircraftper Raisbeck Engineering Inc. STC SA4010 NM.		1. Installed in accordance with Raisbeck installation manualInstallation Manual 87-2024 Rev. E, dated 12/19/072. Instructions for Continued airworthiness ref. Raisbeck MaintenanceManual 85-120 Rev. G. Dated January 20083. IPC 85-119 dated April 2004Or later approved revisions of the above listed doc...	none	26/04/2011	Active	10016582
10016590 (EASA.IM.A.S.03000)	AIRWOLF FILTER CORP	REV. 1	FAA STC SA02268CH	SEE EASA AML SEE APPROVED MODEL LIST (AML)	Installation of Airwolf Filter Corp Air Oil Separator	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmental protectionand the associated certified noise and/ or emissions levels of theoriginal product are unchanged and remain applicable to thiscertificate/ approval.	Installation in accordance with Airwolf Filter Corp. InstallationInstructions as listed on EASA AML, dated 19 February 2009, or laterapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	26/06/2020	Active	10016590
10016598 (EASA.IM.A.S.03011)	BEECHCRAFT CORPORATION	REV. 4	FAA STC ST 10596SC-D	HAWKER 900XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800	Installation of an Aircell Axxess Voice/ Data CommunicationsSystem.	As defined on FAA STC ST10596SC-DFAA CAR 4b & 14 CFR Part 25 per EASA TCDS IM.A.085	In accordance with: STC Required Documents List (RDL) No. 230-2001 Rev. 37 dated September 23, 2011 or later approved revision.Aircraft Flight Manual Supplement No. 230-3001 Rev. R9 dated September23, 2011 or later approved revision, or 230-3002 Rev. R1 dated September23, 2011 or later approved revis...	This modification is only applicable to aircraft equipped with theCollins Proline 21 or Honeywell SPZ-8000 avionics packages.RDL 230-2001-103 and-107 Installation requires the aircraft be equippedwith Collins Proline 21 radios with the IFIS STC ST01342WI-D and theData Link Communications option AAC-...	30/10/2012	Active	10016598
10016599 (EASA.IM.A.S.03012)	RAISBECK ENGINEERING Inc.	REV. 3	FAA STC SA3591NM	B200T, B200T, B200CT, B200T, B200T, B200CT B200GT, B200CGT, B200GT, B200CGT A200C, A200CT, B200, B200C, 200, 200C, 200T, 200CT, A200, 200, 200C, 200T, 200CT, A200	Installation of lower aft fuselage strakes.Rev. 3: Correction of address and document references		1. Installed in accordance with Raisbeck installation manual215BC-53-004< (>,<)> Rev. E dated July 24, 2025 or later approvedrevisions;2. Approved Flight Manual Supplement 85-111 Revision C dated December2007 or later approved revision;3. Instructions for Continued Airworthiness ref. Raisbeck Mainten...	None	15/10/2025	Active	10016599
10016610 (EASA.IM.A.S.03030)	B/E AEROSPACE, Inc. - FSI	REV. 2	FAA ST02004SE	777-200	Remove EWIS limitation for EASA STC No. EASA. IM.A.S.03030 - Door 3Overhead Attendant Rest Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original p...	FAA STC ST02004SEFSI Master drawing List A7FS714-D01 revision R dated 5 March 2010Airplane Flight Manual FSI document TP07-714 AFM dated 16 January 2009A7FS714-D15 Revision D dated 26 July 2010 Supplemental Instructions forContinued Airworthinessor later revisions of the above listed documents appro...	The Main deck seating arrangement must be installed in accordance withBritish Airways drawing 3-302-342 revision 10 dated 12 February 2009FSI STC 10016319 rev. 2 (FAA STC number ST01950SE) for the FSI Door 1Overhead Flight Crew Rest Installation (OFCR) must be accomplishedconcurrently with this STC....	07/10/2010	Active	10016610

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016617 (EASA.IM.A.S.03044)	ROSEMOUNT AEROSPACE, Inc.	REV. 2	FAA STC ST02675CH	A340-541, -642 A340-311, -312, -313 A340-211, -212, -213	Installation of Rosemount Aerospace 8700C2-3 Laptop DockingStation - Electronic Flight Bag (EFB) System ProvisionsRevision of the EASA STC 10016617, Rev. 1 to remove EWIS Limitation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI SE-81 "Installed Resources for EFB Class 2 Provisions"2. CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems -ICA on E...	- FAA STC ST02675CH-Rosemount Aerospace Master Data List, ref. doc. No. D06402676,Revision H, dated 5th August 2009- FAA Approved Airplane Flight Manual Supplement (AFMS), ref. RosemountAerospace Doc. D06403401, Revision B, dated 7th August 2009- EWIS Assessment Document, ref. Doc. D06405259, Revis...	This installation approval does not cover the Electronic Flight Bagcomputers, only the Electronic Flight Bag mounting and wiring. Theoperational approval of the Electronic Flight Bag computers shouldfollow the guidance in the Temporary Guidance Leaflet TGL 36	26/08/2010	Active	10016617
10016625 (EASA.IM.A.S.03058)	BEECHCRAFT CORPORATION	REV. 2	FAA SA03622AT	B300, B300C	Installation of an Air Conditioning Evaporator Blower MotorRF NoiseFilter into a Hawker Beechcraft Model B300 / B300C aircraft .		In accordance with Master Data List Number HBS 003-2151-101-00 Revision 1.0, dated 09/16/08 or later approved revision.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	31/10/2014	Active	10016625
10016626 (EASA.IM.A.S.03061)	TRUATLANTIC MFG., LLC	REV. 2	FAA ST00026AT	208, 208B	Installation of Passenger Interior and Cargo Door Modification in CessnaCaravan (Cargo Conversion)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Atlantic Aero Master Drawing List208199203, Revision B, dated October 28, 1993.FAA approved Aircraft Flight Manual Supplements:a) 20893057, Rev. A,dated December 13, 1993 (Cessna 208, S/N 20800061and on)*b) 20893058, Rev. A, dated December 13, 1993 (Cessna 208, S/N 2...	a) This approval should not be extended to other aircraft of this modelon which other previously approved modificationsare incorporated,unless it is determine by the installer that the interrelationshipbetween this change and any other previously approved modifications willproduce no adverse effect...	28/04/2016	Active	10016626
10016627 (EASA.IM.A.S.03062)	TRUATLANTIC MFG., LLC	REV. 2	FAA STC SA000154AT	208, 208B	Installation of Cabin Windows in the Cargo versions of Cessna 208series.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Atlantic Aero document No. 208199204,Master Drawing List, Rev. G, dated November 16, 2006.or later revisions of the above listed documents approvedby EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Im...	a) This approval should not be extended to other aircraft of this modelon which other previously approved modificationsare incorporated,unless it is determine by the installer that the interrelationshipbetween this change and any other previously approved modifications willproduce no adverse effect...	28/04/2016	Active	10016627
10016646 (EASA.IM.A.S.03089)	ROCKWELL COLLINS AEROSPACEAND ELECTRONICS, INC.	REV. 2	FAA STC ST01100SE	DHC-8-401 & DHC-8-402	Updates for Flight Management System (FMS) HGS 4100.FAA acceptance letter 130S-09-387, dated 21.09.2009.	JAR/CS-25 as per EASA.IM.A. 191The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and theassociatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this...	EASA approved AFM Supplement No. 9701-1192, Rev. C.or laterrevisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	12/04/2010	Active	10016646
10016648 (EASA.IM.A.S.03092)	FIELD AVIATION COMPANY Inc.	REV. 2	TCCA C-LSA08-018/D	DHC-8-402	Galley (G3) Water System Installation (Major Change to EASA STC 10016648, Rev. 1)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation or Modification of the Galley G3 Water System must be inaccordance with TCCA approved FACI Master Data List 213000, Revision N.Instructions for Continued Airworthiness:Maintenance must be in accordance with FACI ICA 213033, Revision B, andFor 213011-1 Configuration aircraft, Maintenance...	Limited to Ser. Nr. 4054, 4062, 4063, 4183, 4244, 4266, 4273, 4286,4290, 4337, 4392.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect up...	28/03/2014	Active	10016648

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016649 (EASA.IM.A.S.03093)	DECRANE AEROSPACE PATS AIRCRAFT,LLC	REV. 1	FAA STC ST02057LA	BOEING 737-800 SERIES BOEING 737-700 SERIES	Installation of Electronic Equipment Rack in Aft Bulk CargoCompartment.This STC revises and supersedes EASA STC EASA.IM.A.S.03093. The revisionwas issued to reflect the transfer from Hollingshead International toDecrane Aerospace PATS Aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Hollingsead Master Data List 2878-01 Rev. A dated June 07, 2007Instructions for Continued Airworthiness 2878-14 Rev. A dated June 14,2007or later revision of the above document approved by EASA in accordancewith EASA ED decision 2004/04/CF(or subsequent revisions of thisdecision).	None.	18/11/2009	Active	10016649
10016651 (EASA.IM.A.S.03099)	LEARJET Inc.	REV. 2	FAA STC SA8199NM-D	BD-700-1A10	FAA STC SA8199NM-D, Installation of a Full Authority Cabin Temp Control.	EASA TCDS EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certif...	-FAA STC No. SA8199NM-D dated 01 May 2002.-FAA SoC reference 150L-08-394 dated 10 December 2008.-Bombardier Master Document List No. BAS67010007, Revision D, dated 24August 2004 or later approved revision.-Bombardier AFMS No. BAS67040007, Revision NC or later approvedrevision.or later revisions of t...	None	16/12/2010	Active	10016651
10016654 (EASA.IM.A.S.03103)	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01276WI-D	SEE FAA APPROVED MODEL LIST	Modification of Rockwell Collins Communication Management Unit (CMU-900)Aircraft Communications Addressing and Reporting System (ACARS) CoreSoftwareRev. 1 updates the CMU-900 fromsoftware Core 14 to Core 16	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing Index ref. RCA-0048-001 revision F2. Approved Model List RCA-0404 revision G	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List RCA-0404 (FAASTC ST01276WI-D).Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and...	19/05/2020	Active	10016654
10016658 (EASA.IM.A.S.03119)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03660AT	PC-12	Installation of a Flight Components/ EMTEQ LED Position (Navigation)Lights into a Pilatus PC-12 Series Aircraft and associated hardware.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	Based on 14 CFR §§ 21.115 and 21.101, and the FAA policy for significantchanges in FAA Order 8110.48, the certificationbasis for the PilatusPC-12 passenger to Freighter is as follows:a. The type certification basis for Pilatus PC-12 airplanes is shown onTCDS A78EU for parts not changed or not affec...	1. Master Drawing List 2-56640-001 Revision A dated October13, 2008 orlater FAA approved drawing revisions.2. Instructions for Continued Airworthiness (ICA), EMTEQ EngineeringDocument No. 2-56640-905, Rev. IR, dated July 11, 2008 or laterFAAaccepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10016658

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016659 (EASA.IM.A.S.03120)	CARLISLE INTERCONNECT TECHNOLOGIES	REV. 1	FAA ST02612CH	AIRBUS A321-232 AIRBUS A321-231 AIRBUS A321-213 AIRBUS A321-212 AIRBUS A321-211 AIRBUS A321-131 AIRBUS A321-112 AIRBUS A321-111 AIRBUS A320-233 AIRBUS A320-232 AIRBUS A320-231 AIRBUS A320-214 AIRBUS A320-212 AIRBUS A320-211 AIRBUS A320-111 AIRBUS A319-133 AIRBUS A319-132 AIRBUS A319-131 AIRBUS A319-115 AIRBUS A319-114 AIRBUS A319-113 AIRBUS A319-112 AIRBUS A319-111 AIRBUS A318-122 AIRBUS A318-121 AIRBUS A318-112 AIRBUS A318-111 A321-253N/271N/-272N A321-213/-231/-232/-251N /-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N /-252N A320-111/-211/-212/-214/-216 A319-231/-232/-233 A319-151N/-153N/-171N A319-111/-112/113/-114/-115 A318-111/-112/-121/-122	Installation of AD Aerospace Cockpit Door Monitoring SystemRev. 1 updates the name and address of the Design Approval Holder fromElectronic Cable Specialists, Inc. to Carlisle InterconnectTechnologies, Inc. and expands installation eligibility to include otherAirbus models which are New Engine Optio...	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements:CS 25 amdt. 0: 25.301(a)(b)(c), 25.303, 25.305(a)(b)(c) , 25.307(a) ,25.561(b)(c)(d) , 25.601, 25.603(a)(b)(c) , 25.605 (a) , 25.609(a)(b) ,25.611, 25.613 (a)(b) , 25.625(a)2...	Master Data List, ref. doc. ECS-206333, Revision Y, dated 18 January2023< (>,<)>CarlisleIT Airplane Flight Manual Supplement (AFMS), ECS-206336,Revision A,dated 12 September 2022<(>,<)>Instruction for Continued Airworthiness, ref. Doc. 206328, Revision E,dated 4 August 2022< (>,<)>or later revisions o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/02/2023	Active	10016659
10016660 (EASA.IM.A.S.03121)	BOMBARDIER INC.	REV. 1	TCCA STC SA05-60	BD-700-1A11	Installation, Complete Custom Aircraft Interior (S/N 9311).	EASA.IM.A.009.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	EASA STC No. EASA.IM.A.S.03121.TCCA STC No. SA05-60 Issue 1.Aero Consulting Services Ltd Configuration Definition List No. E025000Revision CT dated 31 May 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions oft...	Restricted to ASN 9311.	04/06/2010	Active	10016660
10016665 (EASA.IM.A.S.03135)	B/E AEROSPACE LIMITED	REV. 1	TCCA C-LSA09-031/D ISS. 2	CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-031/D Issue 2 dated 17 June 2013.AeroConsulting Services Ltd. Modification Data Summary G120000 RevisionH.Midcoast Aviation Inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior Installation, 33-299M007 Rev NC.Aero Consulting Services Ltd. Mandatory M...	Restricted to ASN 8088.Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.	16/08/2013	Active	10016665

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016669 (EASA.IM.A.S.03151)	ACS-NAI Ltd.	REV. 1	LSTC C-LSA09-009/D ISSUE 2	CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada LSTC C-LSA09-009/D Issue 2 dated 28 September 2012.Aero Consulting Services Ltd. Modification Data Summary G099000 Rev E.Midcoast Aviation Inc. Flight Manual Supplement 33-299M006 Rev NC.or later revisions of the above listed documents approved by EASA inaccordance with the Technica...	Restricted to ASN 8081.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	24/05/2013	Active	10016669
10016678 (EASA.IM.A.S.03201)	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03646AT-D	GIV-X	Installation of Cabin/Baggage Compartment	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Install in accordance with Gulfstream Aerospace Corporation Index ListGC420004142<(>,<)> Rev. D, dated January 30, 2009-Operation in accordance with Airplane Flight Manual Supplement,GC41204M000, Rev. NC dated January 30, 2009or later revisions of the above listed documents approved by EASA inaccor...	This Cabin/Baggage Compartment Multiple STC, (FAA ref ST03646AT-D), doesnot approve the entire airplane interior installation and has thefollowing limitations as defined in document GC422040204, "Guidance forFollow on Installation, Cabin/ Baggage Compartment Multiple STC":1. A complete airplane inter...	08/02/2012	Active	10016678
10016679 (EASA.IM.A.S.03202)	GULFSTREAM SERVICES CORPORATION	REV. 1	FAA STC ST03648AT-D	GIV-X	Installation of Cabin/Baggage Compartment (AG)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Install in accordance with Gulfstream Aerospace Corporation Index ListGC420004144<(>,<)> Rev. L, dated 26 February 2010-Operation in accordance with Airplane Flight Manual Supplement,GC41204M001, Rev. NC dated 4 February 2010or later revisions of the above listed documents approved by EASA inaccord...	This Cabin/Baggage Compartment Multiple STC, (FAA ref ST03648AT-D), doesnot approve the entire airplane interior installation and has thefollowing limitations as defined in document GC422040205, "Guidance forFollow on Installation, Cabin/ Baggage Compartment Multiple STC":1. A complete airplane inter...	08/02/2012	Active	10016679
10016684 (EASA.IM.A.S.C.01059)	GLOBAL AIRWORKS, Inc.	REV. 1	FAA STC ST01585LA	A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-223, A330-243, A330-301 A330-201, A330-202, A330-203	Installation of AirWorks Cockpit Door Surveillance Systems (Validationof the FAA STC ST01585LA).This STC installs a CDSS.The Revision 1 has been issued to correct the references of AssociatedTechnical Documents.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchangedand remain applicable to this certificate/ approval.	Index Document List (IDL) No. IL23009 revision D, dated 11 October 2009Aircraft Flight Manual Supplement, ref: AFMS230019 Revision A, dated 24March 2005Instruction for Continued Airworthiness, ref: ICA230078, dated 20 August2003Instructionfor Continued Airworthiness, ref: ICA230042 Revision A,dated...	Prior to the installation of this modification it must be determinedthat the interrelationship between this modification and any otherpreviously installed modification and/or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/11/2011	Active	10016684
10016700 (EASA.IM.E.S.01014)	FLY IN VACATIONS	REV. 1	FAA STC SE5203NM	IO-360-C1D6	Installation of turbocharger and induction air intercooler in accordancewith "Drawing List Report No. 1" Dated August 20, 1990, or later FAAapproved revision.		Installation Manual, Installation Drawings, Parts List, RCM-1000Continued Airworthiness Instructions	Compatibility of this design change with previously approvedmodifications must bedetermined by the installer. The installation should not be incorporatedin any engine unless itis determined that the interrelationship between this installation andany previously approvedconfiguration will not introduc...	08/06/2015	Active	10016700

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016706 (EASA.IM.R.S.00457)	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC NO SR01424SE	AS355 F2, AS355 N, AS355 NP AS355 E, AS355 F, AS355 F1,	Cargo Hook Kit model 200-292-01	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	155-104-00 revision 11 dated 9 April 2010 - Master Drawing List;120-112-01 revision 4 dated 28 May 2010 - Owners Manual; 123-017-01 revision 4 dated 28 May 2010 - Instructions for ContinuedAirworthiness; 122-005-00 revision 17 dated 9 March 2010 - Cargo Hook Service Manual;121-019-01 revision 1 dated...	None	21/07/2010	Active	10016706
10016709 (EASA.IM.R.S.00553)	ONBOARD SYSTEMS INTERNATIONAL	REV. 2	FAA SR00699SE	SEE FAA APPROVED MODEL LIST	Fabrication of Onboard Systems Model 200-246-00 cargo hook kit.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00699SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Onboard Systems Master Drawing List No. 155-047-00, Revision 21, dated26 March 2013<(>,<) > or later FAA approved revision.Onboard Systems Manual No. 120-083-00, Revision 9, dated 15 February2013, or later FAA approved revision.Section 4 Onboard Systems Service Manual No. 122-004-00, Revision 21,date...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	21/06/2019	Active	10016709
10016714 (EASA.IM.R.S.01008)	DONALDSON COMPANY, Inc.	REV. 2	FAA STC SR09421RC	BELL 206L-4 206L-3, 206L-4	Installation of Aerospace Filtration System (AFS) Engine Inlet BarrierFilter (IBF) systemRevision 2 reflects the name and address change from AerospaceFiltration Systems, Inc. to Donaldson Company, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. AFS Drawing Number 10600, Revision B dated 17/6/2004 or laterapproved revision.2. Installation Procedure AFS-BH206L3L4-IBF-KIT-IP, initial releasedated 16/8/2004 or later approved3. Rotorcraft Flight Manual Supplement (RFMS) AFS-BH206L3L4-IBF-KIT-FMSinitial release dated 25/8/2004 or later approv...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/01/2018	Active	10016714
10016715 (EASA.IM.R.S.01009)	DONALDSON COMPANY, Inc.	REV. 2	FAA STC SR09368RC	407	Installation of Aerospace Filtration System (AFS) Engine Inlet BarrierFilter (IBF) systemRevision 1 reflects the name and address change from AerospaceFiltration Systems, Inc. to Donaldson Company, Inc.Revision 2 updates the Associated Technical Documentation with regardsto "later revisions"	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. AFS Drawing Number 106000, Revision A dated 8/4/2003;2. Installation Procedure AFS-BH407-IBF-KIT-IP, initial releasedated11/4/2003;3. Rotorcraft Flight Manual Supplement (RFMS) AFS-BH407-IBF-KIT-FMSinitial release dated 10/12/2003;4. Instructions for continued airworthiness (ICA) AFS-BH407-IBF-K...	Rotorcraft Flight Manual Supplement dated 10/12/2003 is a required partof this STC."Instructions for continued airworthiness" AFS-BH407-IBF-KIT-ICA is alsorequired part of this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design changep...	10/11/2021	Active	10016715
10016725 (EASA.IM.R.S.01023)	AIRBUS HELICOPTERS CANADA LIMITED	REV. 2	TCCA SH96-32 ISSUE 13	AS350 BA, AS350 B2, AS350 B3 AS 350 BA AS 350 B2, AS 350 B3	Left Side Pilot Configuration (P/N 350 400004, 350 400074, & 350 400164) EASA.IM.R.S.01023: validation of TCCA STC SH 96-32 at issue 7.Revision 1: validation of TCCA STC SH 96-32 at issue 11.Revision 2: validation of TCCA STC SH 96-32 at issue 13. This revisionincorporates new configuration for Post-...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Configuration and installation documentation:For AS 350 BA and B2: Installation and configuration must be performedinaccordance with Airbus Helicopters Canada Limited Master Drawing ListMDL 96 003, Issue Y.For AS 350 B3: Installation and configuration must be performed inaccordance with Airbus He...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/11/2024	Active	10016725

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016726 (EASA.IM.R.S.01027)	ONBOARD SYSTEMS INTERNATIONAL	REV. 2	FAA STC SR00886SE	EC130B4 AS350B, AS350BA, AS350B1 AS350B2, AS350B3, AS350D	Installation of Cargo Hook Kit Model 200-261-00, 200-261-01, and200-353-00This STC is a revision to EASA STC EASA.IM.R.S.01027 Revision 1 throughthe validation of amendment dated 11 August, 2009 to FAA STC SR00886SE.	The original product certification basis as per EASA TCDS.R.008 Issue04, 23 November 2009.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to thi...	Definition and installation:Onboard Systems Master Drawing List Doc. No. 155-060-00, Rev. 11, datedJune 11, 2009Installation of the 200-261-00 Cargo Hook Kit in accordance with OnboardSystems Owner's Manual No. 120-094-00, Rev. 7 dated September 05, 2006Installation of the 200-261-01 Cargo Hook KitK...	The cargo hook kits approved under this STC can be installed on AS 350B, BA, B1, B2, and D helicopters equipped with Eurocopter swing or slingtype systems, or on AS350B3 equipped with Eurocopter sling type systemonly, or on EC 130B4 equipped with Eurocopter swing type system only,those sling or swin...	13/01/2010	Active	10016726
10016728 (EASA.IM.R.S.01031)	AIRBUS HELICOPTERS CANADA LIMITED	REV. 2	TCCA SH97-15	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B, AS 350 B1 AS 350 BA, AS 350 D AS 350 B3, AS 350 BA, AS 350 D AS 350 B2, AS 350 B3	Installation of LH and/or RH Cargo Pods.Rev. 1: Minor Changes embodied and new name of STCH.Rev. 2: added Compatibilityof a sliding door with the LH/ RH Cargo PodInstallation for AS 350 B2 and AS 350 B3 helicopters only.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List MDL-97-004 rev. I, TCCA approved.FlightManual Supplement FMS-ECL-9 Rev. 10, TCCA approved.Instructions for Continued Airworthiness ICA-AHCA-294 Rev. 2, TCCAacceptedor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Techni...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/08/2023	Active	10016728
10016731 (EASA.IM.R.S.01055)	FARGO MANUFACTURING CO.	REV. 2	FAA SR01926CH	MD900	Install 61.8 gallon crashworthy auxiliary fuel tank on the aft cabinbaggage bay floor.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Fargo Installation Instructions A-900-3CW, Revision C dated 8 January2004.- Fargo Manufacturing Drawing List A-900-3CW Revision 2 dated 14 October2003.- Fargo Manufacturing RFM Supplement No.Rev dated 9 January 2004Or later revisions of the above listed document(s) approved/ accepted onbehalf of EA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/06/2020	Active	10016731
10016732 (EASA.IM.R.S.01056)	SAFRAN ELECTRONICS & DEFENSE,AVIONICS USA, LLC	REV. 4	FAA STC SR09263RC-D	EC120B	SFIM two-axis VFR Autopilot System (SAGEM PA85)Nota:,,- Original STC: FAA STC SR09263RC-D, amended 9 February, 2011- Existing EASA STC: 10016732 rev 3- Revision 4 incorporates 2 new configurations related to minor changeto the FAA STC.	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Installation of a SFIM VFR autopilot system in accordance with:-AEC Master Drawing List 120A82-8010 revision E, dated June 02, 2006.- Instructions for Continued Airworthiness PA85-120MMS-001 revision B,dated June 06, 2002, or later accepted revisions-Flight Manual Supplement 120FMS-012 revision B,...	Installation of FAA STC SR09450RC (EASA.IM.R.S.01527) is mandatory forconfigurations -01<(>,<)> -02of SAGEM Installation Drawing 120-1002Installation of FAA STC SR09450RC (EASA.IM.R.S.01527) is mandatory forconfigurations -03, -04 of SAGEMInstallation Drawing 120-1002	14/03/2011	Active	10016732
10016741 (EASA.IM.R.S.01067)	DONALDSON COMPANY, Inc.	REV. 1	FAA STC SR01394LA	369HM, 369HS 369D, 369E, 369FF, 369H, 369HE	Installation of Aerospace Filtration Systems Inlet Barrier Filter Systeminstead of Engine Air Separator (with or without Mist Eliminator) or FODScreen.Revision 1 reflects the nameand address change from AerospaceFiltration Systems, Inc. to Donaldson Company, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List: MD500-IBF-KIT-MDL, Rev. D, dated 30.09.2004 orlater FAA approved revision.2. Flight Manual Supplement MD500-IBF-KIT-FMS Rev. B FAA approved 12April 2005 or later FAA approved revision.3. Operation & Maintenance Manual/IPL MD500-IBF-KIT-OMM/IPL Rev. A,dated 28 June 2002 or later...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/01/2018	Active	10016741

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016747 (EASA.IM.R.S.01073)	AIRBUS HELICOPTERS CANADA LIMITED	REV. 3	TCCA SH96-31	AS 355 F2 AS355 E/ F/ F1/ F2 AS 355 E, AS 355 F, AS 355 F1 AS350 B/ BA/ B1/ B2/ B3/ D AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Relocation of higher capacity battery to tail boom (Mod. P/N 350-700324and P/N 355-700324).EASA STC 10016747.Revision 1: validation of TCCA STC SH96-31 at issue 9.Revision 2: validation of TCCA STC SH96-31 at issue 10. This revisionincorporates new configuration for compatibility with avionics Stepm...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation and configuration must be performed in accordance with thefollowing:For AS 355 series: Airbus Helicopters Canada Limited Master Drawing ListMDL-96-001, Issue O,approved on August 27, 2024.For AS 350 series: Airbus Helicopters Canada Limited Master Drawing ListMDL-04-003, Issue I,approve...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Installation on the AS 355 series model is only valid f...	26/03/2025	Active	10016747
10016764 (EASA.IM.R.S.01095)	AEROLITE AG	REV. 1		MBB-BK 117 C-2	Installation of EC 145 EMS Equipment P/ N 145121-501.This STC revision is issued for the purpose of transferring the STCtoAerolite AG.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approvalThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval..	Flight Manual Supplement FMS-506or later revisions of the above listed documents approved by EASA.	- No Smoking when Medical Oxygen Cabinet is installed.- TheLOX System can only be operated during flight when appropriatelytrained medical crew are on board.- This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description ofD...	15/03/2016	Active	10016764
10016765 (EASA.IM.R.S.01096)	AEROLITE AG	REV. 3		MBB-BK 117 C-2	EMS Equipment P/N 145146-501,,This change to STC introducesmodification on existing cabinconfigurations and introducestwo new similar cabin configurations.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FMS-505 Rev BChapter 4 (Airworthiness Limitations) of OPM-504 Rev Bor later revisions of the above listed documents approved by EASA.Certification Program CPR-16-005 Rev BMaster Document List MDL-504 Rev CInstructions for Continued Airworthiness included in OPM-504 Rev B	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/09/2016	Active	10016765
10016772 (EASA.IM.R.S.01107)	DART AEROSPACE ULC	REV. 2	TCCA SH24-6	AB412 EP AB412 AB212 412EP 412 2. AB412, AB412EP 212 1. 212, 412, 412EP, (412CF)	Installation of Emergency Float KitsSTC transferred to DARTAerospace ULC.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	RFMS412-41, Revision G, dated July 15, 2024MD412-41, Revision Z, dated September 03, 2024II412-41, Revision W, dated February 29, 2024ICA412-41, Revision AB, dated January 10, 2024or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical I...	Installation of the Bell Helicopter Textron, Inc. Step Assembly, PartNumber 222-036-044-101/-102 is not authorized.BellHelicopter Textron, Inc., High Skid Landing Gear with LightweightFlotation Skid Tubes, Part Number 412-050-015-111/-112<(>,<) >orDart Aerospace Float Skid Tubes, Part NumberD412-742...	29/11/2024	Active	10016772
10016786 (EASA.IM.R.S.01128)	SPACECAM SYSTEMS INC.	REV. 1	TCCA STC SH02-6	AS 355 N AS 355 F2 AS 355 F1 AS 355 F AS 355 E AS 350 D AS 350 BA AS 350 B3 AS 350 B2 AS 350 B1 AS 350 B	Spacecam RAMS Installation		Defintion and Installation:DECA Aviation Modification Summary MS01071, revision 3, June 6th 2005 or later Transport Canada (TCCA) approved revisions.DECA Aviation Installation instructions II 01071, revision 2, June 6 2005 or later Transport Canada (TCCA accepted revision.Operation:DECA Aviation Fli...	Eurocopter (Aerospatiale) Service Bulletin N° 53-05 and 53-06 (for Tail Boom Balast) are required as part of this installation.This STC is the EASA Validation of Transport Canada STC n° SH02-6 Issue 2, dated June 28, 2005	25/08/2009	Active	10016786
10016793 (EASA.IM.R.S.01143)	AEROLITE AG	REV. 2		MBB-BK 117 C-2	Installation of alternative Swivelling Adapter P/N 001-0019851-501 andalternative Floor Plate Assy P/N 007-0020988-501 for EMS Equipment P/ N145181-501	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AEROLITE MAX BUCHER AG FMS-507 rev. Cor later revisions of the above listed documents approved by EASACompliance Check List: CPR-14-010 rev. N/ CMaster Document List: MDL-507 Rev. C	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/10/2014	Active	10016793

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016794 (EASA.IM.R.S.01144)	AEROLITE AG	REV. 1		A109S	A109S EMS equipment P/N 109115-50X. This revision 1 of EASASTCEASA.IM.R.S.01144 is related to the introduction of stretcherconfiguration Aerolite P/N 1090117-503.	As defined in EASA TCDS R. 005.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement - FMS-508 Revision COperation and Maintenance Manual - OPM-508 Revision BMDL-508 Revision Bor later revisions of the above listed documents approved by EASA	The Agusta provision for EMS kits (Aerolite) P/N 109-0814-22-501 has tobe installed.	18/01/2010	Active	10016794
10016796 (EASA.IM.R.S.01149)	HELI-ONE (NORWAY) AS	REV. 1		AS 332 L, AS 332 L1	BPOL 33211 Police Equipment Installation as per Mod. AHSE-52400Rev. 0 of this STC consists of the full installation of the equipmentlisted in Configuration Control AHSE-52408Rev. 1 of this STC, in accordance with AHSE-68487, allows installationof the following equipment only:- AP155 Autopilot Instal...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For Rev. 0 of the STC:AHS-005 09/05/2006,,TDR-94D ATC Transponder ,,,,AHS-027 08/05/2006 ,,Aerodata Aerophone Iridium installation,,AHS-053 12/10/2006 ,,AeroNav II with GPS,,,,,,AHS-055 04/04/2006 ,,VHF COM Wulfsberg Series IIIAHS-056 04/04/2006 ,,VHF NAV Wulfsberg Series IIIAHS-057 04/04/2006 ,,ADF...	Helicopters modified in accordance with this STC are not approved forNVG operations.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect up...	24/11/2015	Active	10016796
10016798 (EASA.IM.R.S.01151)	SKYTRAC SYSTEMS LTD.	REV. 4	TCCA STC SH03-30	SEE EASA APPROVED MODEL LIST	Installation of SkyTrac ISAT-100/ ISAT-200 AIRBORNE POSITION/ DATACOMMUNICATORRevision 1 to add: BK-117 A-1, A-3, B-1, and B-2 modelsRevision 2 to add: Eurocopter SA 365 C, C1, N, EC 155BRevision 3:1) Adding ISAT-200 Airborne Position/Data Communicator as a retrofitoption.2) Adding the following mode...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition on Lithium Batteries as per EASACRI F-01 Issue 2The requirements for environmental protection and the associatedcertified noise and/ or emissions levels...	See EASA Approved Model List	None	06/04/2018	Active	10016798
10016801 (EASA.IM.R.S.01160)	AIRFILM CAMERA SYSTEMS, INC	REV. 1	FAA STC SR01785LA	SEE FAA AML	Installation of Airfilm Single Pole Utility Bracket.Revision 1 of this STC (former EASA approval number EASA.IM.R.S. 01160)is issued to validate FAA STC SR01785LA amended to incorporate majorchanges to the type design data.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved Master Drawing List No. AFSP-010, Revision N/C, dated 17February 2005 and a copy of FAA approved Rotorcraft Flight ManualSupplement No. AFSP-005, issued 12 May 2005 or later FAA approvedrevisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Airfilm Single Pole Utility Bracket Install...	26/06/2018	Active	10016801
10016802 (EASA.IM.R.S.01162)	AIRFILM CAMERA SYSTEMS, INC	REV. 1	FAA STC SR01654LA	407 206L, 206L-1,206L-3, 206L-4, 206, 206A, 206B, 206B-1,	Installation of Airfilm Model G1 Nose Mount Utility Bracketand/or G3Landing Light on Bell 206/407 Series Rotorcraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	FAA approved Airfilm Camera Systems Master Drawing List No.AF-G1-010,Revision N/C, dated 14 April 2004 and/or AF-G3-010, Revision N/C, dated14 April 2004.Rotorcraft Flight ManualG1-206-005, dated 8 September 2004, or laterFAA approved revision.Instructions for Continued Airworthiness AF-G1-008, Re...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/10/2018	Active	10016802
10016805 (EASA.IM.R.S.01165)	GENESYS AEROSYSTEMS, INC.	REV. 2	FAA SR02209AK	BELL 407 BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206L BELL 206B BELL 206A 206L-3, 206-L4, 407 206A, 206B, 206L, 206L-1	Installation of Genesis Aerosystems FlightLogic Electronic FlightInstrument System (EFIS)Rev. 2 upgrades the software to version 9.0A on the dual IntegratedDisplay Unit (IDU)-450 and IDU-680 configurations.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List ref. 651-045950 Rev. N, dated 19 April 2021- Flight Manual Supplements: . Document 17-209FMS-0450 (IDU-450), Rev. A, dated 12 July 2021 . Document 17-209FMS-0680 (IDU-680), Rev. A, dated 12 July 2021- Instructions for Continued Airworthiness: . IDU-450 - Installation Docu...	EFIS/AIU integration with the autopilot is approved only when configuredwith the 902-00028-01 Control Panel.Activation of Fuel Flow functions requires installation of separatelyapproved fuel flow transducers.Installation is not permitted on Instrument Flight Rules (IFR) certifiedrotorcraft.Prior tot...	15/11/2021	Active	10016805

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016817 (EASA.IM.R.S.01182)	AEROLITE AG	REV. 5		MBB-BK117 C-2 MBB-BK 117 C-2	EMS Equipment P/N 145212-501.Installation of EMS Equipment P/N 145212-501 with variousconfigurations.Rev. 2 introduced the following changes to the EMS Equipment P/N145212-501 (EASA approved under STC No. 10016817, Rev. 1):(1) Modificationof configuration no. 2. (2) Introduction of derivative config...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI D-01 [“Passenger Emergency Exits (EMSinstallation)”] is raised and closed at issue 3.The requirements for environmental prot...	Certification Program CPR-14-007 Rev. N/C dated 21/07/2014<(>,<)>Certification Program CPR-21-038 Rev. E dated 16/09/2022<(>,<)>Flight Manual Supplement FMS-06-002 Rev. F dated 01/06/2022<(>,<)>Instructions for Continued Airworthiness and Operations ManualOPM-06-002 Chapter 04 dated 13/04/2006<(>,<)...	The following are pre-requisite installations for the embodiment of thedesign change leading to the Rev. 5 of this STC 10016817:- Airbus Helicopters Deutschland (AHD) floor (*) for the floorprotection installation P/N 145-0047223-504.- Cabinet provisions P/N 145-0052560-501 for the cabinet installat...	20/09/2022	Active	10016817
10016828 (EASA.IM.R.S.01198)	DART AEROSPACE Ltd.	REV. 1	TCCA SH03-6, ISSUE 4	3. 214B, 214B-1 2. 212, 412, 412EP 1. 204B, 205A-1	D205-594 Extended height landing GearNote: This certificateis revision of STC EASA.IM.R.S.01198 forextension of applicability to 412 and 412EP helicopter models.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List MDL-D205-594, Rev. J, dated 17 June 2013-Installation Instructions IIN-D205-594, Rev. E, dated 7 May 2013-Instructions for Continued Airworthiness ICA-D205-594, Rev. 4, dated 7May 2013-Flight Manual Supplement FMS-D214-594, Rev. A, dated 14 July 2005or later revisions of the ab...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/01/2014	Active	10016828
10016829 (EASA.IM.R.S.01199)	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE	REV. 2	FAA STC SR01855LA	EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Emergency Floats KitsInstallation of Apical Industries, Inc. Emergency Floats Kits inaccordance with FAA STC SR01855LA Apical Master Document List MD 135-1provides for different installations either with liferafts or without.REV. 1: Amendment of the initial STC in order to add the EC135 MidHeight La...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	REV. 1:Rotorcraft Flight Manual Supplement RFMS 135-1, Rev.CREV. 2:Rotorcraft Flight Manual Supplement RFMS 135-1, Rev. FAirworthiness Limitations Section 2.0 of ICA 135-1, Rev. Qor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subs...	1. The installation is not approved for helicopters equipped with highskid landing gear.2. Metro Aviation, Inc., Landing Gear Skid Extensions, Part Number135M-110, must be installed in accordance with STC EASA.IM.R.S.01377(FAA STC SR09230RC) prior to the installation of this STC, unless AirbusHelico...	31/07/2017	Active	10016829
10016846 (EASA.IM.R.S.01222)	CERT WORKS, LLC	REV. 1	FAA SR01647SE	EUROCOPTER FRANCE AS 350 B2 AS 350 B2	Installation of Honeywell LTS101-700D-2 engine on AS 350 B2.Rev 1. Transfer of STC to Cert Works, LLC.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Drawing List 900-100, Revision C, dated September 25, 2006Maintenance & Overhaul Supplement S2021H, Revision 1, dated September,2006Rotorcraft Flight Manual Supplement S2020H, Revision 1, dated April 6,2006or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA i...	See attached Annex Issue 01 dated 27/11/2020.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	27/11/2020	Active	10016846
10016858 (EASA.IM.R.S.01234)	PRECISE FLIGHT, Inc.	REV. 2	FAA STC SH3319NM	SEE FAA AML SEE EASA APPROVED MODEL LIST	Precise Flight PulseLite Control System. Adding MDHI 369 and 500Nmodels.Rev. 2: adds the AW139 to the AML.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificat...	Precise Flight Engineering Drawing Lists 002P0000, RevisionH, dated 11July 2001<(>,<)>005P0000, Revision D, dated 12 December 1998, 006P0000, Revision C,dated 11 July 2001, 0010P0000. Revision F, dated 13 March 2002,015P0000, Revision J, dated 19 April 2002; 020P0000, Revision M, dated 6September 2...	Approval for the physical installation of the PulseLite Control Unitwill be required if there is no specific reference provided inEngineering Drawing List 001P0001, revision B, dated May 1, 2002.Prior to installation of this change/repair it must be determined thatthe interrelationship between thisp...	03/02/2025	Active	10016858

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016867 (EASA.IM.R.S.01243)	RSG PRODUCTS, Inc.D/B/A INTEGRATED FLIGHT SYSTEMS, IN	REV. 1	FAA STC SH3509SW	EUROCOPTER FRANCE EC 130 B4 EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 C EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B AS 350 D, AS 350 D1, EC 130 B4 AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 C	Installation of a Single and Dual Condenser Blower Air ConditioningSystemRev. 1: update companies' address and documents		For Single Condenser Configurations the following Flight ManualSupplements (FMSs) and revisions are required accordingly: AS350B, C, D,D1: FMS 19-350-21-002-011, Rev. D, dated 17 November 2014<(>,<)>AS350B1: FMS 19-350-21-004-011, Rev. C, dated 17 November 2014<(>,<) >AS350B2: FMS 19-350-21-006-011,F...	1. VFR Operations only2. This STC is approved only for the product configuration as definedin the approved designdata referred to in the paragraphs "Description"and “Associated Technical Documentation”. Compatibility with otheraircraft/engine configurations shall be determined by the installe...	28/07/2025	Active	10016867
10016870 (EASA.IM.R.S.01246)	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC SR01393SE	AS350B, AS350BA, AS350B1 AS350B2, AS350B3, AS350D	Onboard Systems cargo hook kits P/N 200-286-01 (with cargo hook P/ N528-023-01) and P/N 200-286-02 (with cargo hook P/N 528-029-00)Revision 1 - introduces cargo hook kit P/N 200-286-02This STC is the validation of FAA STC SR01393SE (issued on April 05,2004 and last amended on June 29, 2010).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Change under revision 1 complies with FAR Part 27, amdts 27-1 through27-39The requirements for environmental protection and the associate...	Definition and installation:Onboard Systems Master Drawing List No. 155-093-00, Rev. 8 datedNovember 16, 2010 andfor cargo hook kit P/N 200-286-01:Onboard Systems Owner's Manual No. 120-107-01 Rev. 6 dated September 01,2010for cargo hook kit P/N 200-286-02:Onboard Systems Owner's Manual No. 120-107-...	None	04/02/2011	Active	10016870
10016878 (EASA.IM.R.S.01255)	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE	REV. 3	FAA SR01812LA	A109E/ A109K2/ A109S/ AW109SP A109/ A109A/ A109AII/ A109C	Installation of Apical Industries, Inc. Emergency Float Kit.Revision 2 of this STC is issued to add additional models and introduceeditorial changes.Revision 3 of this STC is issued to make A109 Series Float Systemcompatible on A109S with Trekker Kit p/n 109G0000F01 installed.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Document List MD109-1, Revision D, dated 18 August 2005Rotorcraft Flight Manual Supplement, RFMSA109-1, RevisionN/ C, dated 24August 2005Instruction for Continued Airworthiness, ICA109-1, Revision A, dated 19August 2005or later revisions of the above listed document(s) approved/accepted onbeh...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/04/2021	Active	10016878
10016879 (EASA.IM.R.S.01256)	SIKORSKY GLOBAL HELICOPTERS Inc.	REV. 1	FAA STC SR02408NY-D	S-92A	Installation of Spectrolab Nightsun II XP SearchlightNote: This certificate revises and supersedes STC no. EASA.IM.R.S. 01256,aiming to update the Associated Technical Documentation as listed below	The Certification Basis for the original product remains applicable tothis certificate/ approval	- FAA approved Rotorcraft Flight Manual Supplement No.FM01231 rev. 2dated September 16, 2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)- Keystone Helicopter Installation Drawing List IDL0123...	None	22/11/2010	Active	10016879

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016900 (EASA.IM.R.S.01277)	SIKORSKY AIRCRAFT CORPORATION	REV. 2	FAA SR02402NY	S-92A	Installation of Alternate Utility Interior (AUI).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI D-01, Issue 3 dated May 17, 2016 – “Type III Emergency Exits forDitching”The requirements for environmental protection and the associatedc...	-Rotorcraft Flight Manual< (>,<)> Supplement No. FM01228 Rev. 10 datedDecember 23, 2013;- Rotorcraft Flight Manual< (>,<)>Supplement No. FM01299 Rev. 1 datedMarch 29, 2008 or Supplement No. 15 Rev – dated June 3, 2011;- Rotorcraft Flight Manual< (>,<)> Supplement No. EASA FM01228 Rev. - dated August 25,o...	1. Compliance with the following regulations has not been demonstrated:JAR29 [Change 1] §29.1411 f) and §29.1415 b);2. The Equivalent Level Of Safety (ELOS) finding to JAR 29.807 d)2) perCRI D-01:- requires approved life rafts stored external to the rotorcraft whenever-water operation is conducted;-...	25/08/2017	Active	10016900
10016901 (EASA.IM.R.S.01278)	DART AEROSPACE USA, Inc.	REV. 2	FAA SR01709SE	EUROCOPTER DEUTSCHLAND EC-135-EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of Skidtube and Skidtube extension in accordance withMaster Document List MDL-D135-751Revision 1:Initial approval of STC.Revision 2:- Extension of applicability to EC135 P3 and EC135 T3- Correction of STC holder designation from Dart Aerospace Ltd., Canadato Dart Aerospace USA, Inc.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Drawing List MDL-D135-751, Revision I, dated 27 May 2025.Installation Instructions IIN-D135-751, Revision D, dated 13 August2024.Instructions for Continued Airworthiness ICA-D135-751, Revision 4, dated27 May 2025;or later revisions of the above listed document(s) approved/ accepted onbehalf of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	23/06/2025	Active	10016901
10016903 (EASA.IM.R.S.01280)	DART AEROSPACE Ltd.	REV. 2	TCCA STC SH06-27	AS355F, AS355F1, AS355F2 AS355E, AS355N, AS355NP AS350B, AS350B1, AS350B2 AS350B3, AS350BA, AS350D	Cross Tube Installation in accordance with Transport CanadaSTC SH06-27,Issue 1, dated 16 August 2006.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-MDL-D350-748 rev F dated 30 June 2010 - Master Document List-IIN-D350-748 rev B dated 15 June 2007 - Installation Instructions-ICA-D350-748 rev 1 dated 29 June 2010 - Instructions for ContinuedAirworthinessor later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	None	03/09/2010	Active	10016903
10016908 (EASA.IM.R.S.01289)	DART AEROSPACE Ltd.	REV. 1	TCCA STC SH06-39 ISSUE 2	AGUSTA A119, AW119 MKII	TCA STC No. SH06-39 Issue 2 - "Heli-Utility Basket Installation" - Thisinstallation consists in a box, fixed to the landing gear, for goodstransportation.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCA STC No. SH06-39 Issue 2 dated 2 July 2009FMS-D119-756-EASA Rev. A, ICA-D119-756-EASA Rev. 0, MDL-D119-756-EASARev. Aor later revisions of the above listed documents approved by EASAor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or...	None	10/02/2011	Active	10016908
10016917 (EASA.IM.R.S.01302)	BAE SYSTEMS LAND & ARMAMENTS L.P.	REV. 3	FAA SR01906LA	MBB-BK117 D-2 MBB-BK117 C-2	Initial issue) Installation of Multiple-place Utility TroopSeatingSystem.Rev.1) Inclusion of fifteen new Troop Seat and Interface Frame designs.Rev.2) Inclusion of MBB-BK117 D-2.Rev.3) Company name change from BAE Systems Aerospace & Defense GroupInc. to BAE Systems Land & Armaments L.P.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	• Master Drawing List Number TD-05175 Revision P dated September 24,2008• MBB-BK 117 C-2 Rotorcraft Flight Manual Supplement Document No.TD-05174 Revision D dated December 10, 2008• MBB-BK 117 D-2 Rotorcraft Flight Manual Supplement Document No.14150-30-2 initial issue dated February 3, 2015or later...	A copy of this STC must be included in the permanent records of themodified aircraft. If the holder agrees to permit another person to usethis certificate to alter the product, the holder shall give the otherperson written evidence of thatpermission. The following BAE SystemsAerospace & Defense Gro...	07/10/2021	Active	10016917

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016929 (EASA.IM.R.S.01315)	DONALDSON COMPANY, Inc.	REV. 1	FAA STC SR09451RC	206B	Installation of Aerospace Filtration Systems (AFS) Engine Inlet BarrierFilter (IBF) on Bell 206B helicopters.Revision 1reflects the name and address change from AerospaceFiltration Systems, Inc. to Donaldson Company, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. AFS drawing number 109000, revision A, dated August 16, 2005 or laterapproved revision.2. Installation procedures AFS-BH06B-IBF-KIT-IP, revision A, datedOctober 25, 2005 or later approved revision.3. Instruction for continued Airworthiness documentAFS-BH06B-IBF-KIT-ICA, are required.4. Airworthin...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/01/2018	Active	10016929
10016937 (EASA.IM.R.S.01324)	ONBOARD SYSTEMS INTERNATIONAL	REV. 3	FAA STC SR01164SE	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B, AS 350 B1 AS 350 BA, AS 350 D AS 350 B3, AS 350 BA, AS 350 D AS 350 B2, AS 350 B3	External Load Swing Suspension System models 200-280-01 and-04 (withKeeperless Cargo Hooks) and model 200-280-02 and -03 (with HydraulicCargo Hooks)Revision 1 - introduced cargo hook kit 200-280-03 with a collectivefriction knob and a newrelease lever to accommodate the AS350B3 stylecollective con...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Definition and installation:Onboard Systems International Master Drawing List No. 155-086-00, Rev.50, dated 12 May 2021Onboard Systems International Owner's Manual:No. 120-104-01,Rev. 17, dated 9 May 2014 (for system model 200-280-01),orNo. 120-104-02, Rev. 37, dated 10 May 2021 (for system model 2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Installation and operation of the system on AS350B3 wit...	13/09/2022	Active	10016937
10016948 (EASA.IM.R.S.01343)	EAGLE COPTERS USA, INC.	REV. 3	FAA SH4747NM	AS350B, AS350B1, AS350B2 AS350B3, AS350BA, AS350D	Installation of consoles, toggle switches, circuit breakersandreplacement wiring harnesses in accordance with Geneva Aviation MasterDrawing List GA107.This STC is the validation of FAA STC No. SH4747NM (issued on July 26,1989) Revision 2 follows re-issuance of FAA STC No. SH4747NM on October 28,2015...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Geneva Aviation Master Drawing List (MDL) GA107, Revision Q, datedFebruary 12, 2013For AS350B, AS350BA, AS350D, AS350B1, AS350B2, AS350B3 with P122 Consoleinstalled and PRE-MOD AMS 07-4280 configuration:- Rotorcraft Flight Manual Supplement GA107-2 Revision N dated04/03/2011- Instructions for Contin...	In all cases where works have been carried out on the collective lock,locking strap or central console:- the locking strap height must be adjusted as required in AHMaintenance Manual 67.10.00.501 or 67.10.00.501 (as appropriate),section 3.3: and- a minimum gap of 0.15 inches (4mm) between the end of...	18/03/2016	Active	10016948
10016959 (EASA.IM.R.S.01356)	AIR COMM CORPORATION L.L.C	REV. 1	FAA STC SR00565DE	EC135 T2, EC135 T2+ EC135 T2, EC1356 T2+ EC135 P2, EC135 P2+	Installation of Cabin Air Conditioning System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00565DE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Air Comm Corporation Master Drawing List Report No.DL-EC135, Revision A,dated 19 October 2004, FAA approved 24 November2004, or later FAAapproved revision.Instructions for Continued Airworthiness, Air Comm Corporation ReportEC135-200M-1, Revision -, dated 25 August 2004, FAA accepted 24 November200...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/06/2020	Active	10016959
10016960 (EASA.IM.R.S.01357)	EAGLE COPTERS USA, INC.	REV. 1	FAA STC SR00474SE	AS355F2, AS355N AS355E, AS355F, AS355F1 AS350B, AS350B1, AS350B2 AS350BA, AS350B3, AS350D	Modular Equipment Rack Installation per MDL GA179.Notes:1. The STC was initially issued to Geneva Aviation, Inc. (initialreference: EASA.IM.R.S.01357).2. Revision 1 to this STC reflects the transfer of EASA.IM.R.S.01357from Geneva Aviation, Inc. to Eagle Copters USA, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List GA179 Rev. B dated November 20, 2002Rotorcraft Flight Manual Supplement GA179-3 Rev. D February 15,2007or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (orsubsequent revisions ofthis decision) and/ or the TechnicalU...	This STC provides approval for structural provisions only. A separateapproval is required for the installation of any equipment in themodular equipment rack.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslya...	12/03/2015	Active	10016960

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016961 (EASA.IM.R.S.01359)	EAGLE COPTERS USA, INC.	REV. 1	FAA STC SR00326SE	AS355F2 AS355E, AS355F, AS355F1 AS350B, AS350B1, AS350B2 AS350BA, AS350D	Microwave System Installation per MDL GA170.Notes:1. The STC was initially issued to Geneva Aviation, Inc. (initialreference: EASA.IM.R.S.01359).2. Revision 1 to this STC reflectsincorporation of minor changesapproved under FAA/EASA TIP and the transfer of EASA.IM.R.S.01359 fromGeneva Aviation, Inc...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List GA170 Rev. D dated February 11, 2009Rotorcraft Flight Manual Supplement GA170-3 Rev. B dated May 14, 2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/03/2015	Active	10016961
10016972 (EASA.IM.R.S.01373)	DART AEROSPACE USA, Inc.	REV. 1	FAA STC SH4748NM	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D.	Installation of a replacement instrument panel visor.This STC is a validation of FAA STC SH4748NM	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Geneva Aviation Master Drawing List, doc. ref. GA127, Revision D, datedMarch 8, 2008Installation Instructions, doc. ref. GA127-3, Revision B, dated March 8,2008Compliance Checklist, doc. ref. CCL-127, Revision -, dated August 17,2007or later revisions of the above listed documents.	None	15/04/2013	Active	10016972
10016973 (EASA.IM.R.S.01374)	EAGLE COPTERS USA, INC.	REV. 1	FAA STC SR00222SE	AS350B, AS350BA, AS350D AS350B1, AS350B2, AS350B3	Installation of a supplemental avionics console between thefront seatsin accordance with Geneva Aviation Master Drawing List GA158.This STC is the validation of FAA STC No. SR00222SE.Revision 1 follows re-issuance of FAA STC No. SR00222SEon October 28,2015. It confirms the transfer of the STC from...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Geneva Aviation Master Drawing List (MDL) GA158, Revision C, dated April14, 2008Compliance Checklist CCL-158 Rev. -, dated August 16, 2007or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or...	This STC provides approval for structural provisions only. A separateapproval is required for the installation of any equipment in thesupplemental avionics console.The installation of this modification by third persons is subject towrittenpermission of the approval holder and holding and disposal o...	06/05/2016	Active	10016973
10016984 (EASA.IM.R.S.01389)	DART AEROSPACE Ltd.	REV. 2	TCCA SH93-4 ISSUE 10	AS355 F2, AS355 N, AS355 NP AS355 E, AS355 F, AS355 F1 AS350 D, EC130 B4, EC130 T2 AS350 B, AS350 B1, AS350 B2 AS350 B3, AS350 BA	Bearpaw InstallationRevision 2 extends the applicability tothe EC130T2 type model.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AS350 and AS355 models:- Master Document List, doc. ref. MDL-D350-578, Rev. A, dated June 11th,2010- Installation Instructions, doc. ref. D350-578, Rev. F, dated August28th , 2008- Instructions for Continued Airworthiness, doc. ref. ICA-D350-578, Rev.1, dated August 28th, 2008EC130B4 and EC130T2 mod...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/10/2015	Active	10016984
10016988 (EASA.IM.R.S.01394)	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SR176CH; DGAC FRANCE S	212, 412	Installation of an air ambulance unit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Spectrum Aeromed Report No. SI2055A, dated May 20, 1993 or later approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/04/2019	Active	10016988

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10016992 (EASA.IM.R.S.01401)	EAGLE COPTERS USA, INC.	REV. 1	FAA STC SR00388SE	AS350B, AS350B1, AS350B2 AS350B3, AS350BA, AS350D	Installation of a Rear Communication Console per MDL GA178.Notes:1. The STC was initially issued to Geneva Aviation, Inc. (initialreference: EASA.IM.R.S.01401).2. Revision 1 to this STC reflects incorporation of minor changesapproved underFAA/EASA TIP and the transfer of EASA.IM.R.S.01401 fromGenev...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List GA178 Rev. C dated February 09, 2009Rotorcraft Flight Manual Supplement GA178-3 Rev. C dated March 14, 2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technic...	This STC provides approval for structural provisions only. A separateapproval is required for the installation of any equipment in thecommunication console.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously i...	12/03/2015	Active	10016992
10016996 (EASA.IM.R.S.01405)	DART AEROSPACE Ltd.	REV. 3	TCCA STC SH94-14	EC130B4, EC130T2 AS355E/F/F1/F2/N/NP AS350B/B1/B2/B3/BA/D	D350-607 and D130-701 Heli-Utility Basket and Long Cargo TubeInstallationsRevision 2 adds the models AS355N and NP.Revision 3 adds model EC130T2, modifies vne restrictions, increases thecapacity of the existing D350-607-44X/54X Heli-Utility Basket Kits by100 lbs and introduces the D350-607-641 Quick...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:For AS350 and AS355 models: FAR 27 up to and including Amendment 27-23for the affected areas.For EC130B4 and EC130T2 models: FAR27 up to and including Amendment27-32 for t...	AS350 and AS355 models:-,,AS350 Flight Manual Supplement, doc. ref. FMS-D350-607 Revision G,dated December 6, 2013-,,AS355 Flight Manual Supplement, doc. ref. FMS-D355-607 Revision G,dated December 6, 2013-,,Master Document List, doc. ref.MDL-D350-607 Revision M, datedDecember 6, 2013-,,Installatio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/10/2015	Active	10016996
10017002 (EASA.IM.R.S.01413)	EAGLE COPTERS USA, INC.	REV. 1	FAA STC SR00361SE	AS355 F2, AS355 N AS355 E, AS355 F, AS355 F1 AS350 B, AS350 B1, AS350 B2 AS350 B3, AS350 BA, AS350 D	Utility Rack Installation per MDL GA164.Notes:1. The STC was initially issued to Geneva Aviation, Inc. (initialreference: EASA.IM.R.S.01413).2. Revision 1 to this STC reflects thetransfer of EASA.IM.R.S.01413from Geneva Aviation, Inc. to Eagle Copters USA, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List GA164 Rev. B dated May 16, 2008Rotorcraft Flight Manual Supplement GA164-3 Rev. - initial release datedMay 15, 2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the...	This STC provides approval for Utility Rack installation only. Aseparate approval is required for the installation of any equipment inthe utility rack.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously instal...	10/03/2015	Active	10017002
10017003 (EASA.IM.R.S.01414)	DART AEROSPACE USA, Inc.	REV. 1	FAA STC SH4785NM	AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D.	Installation of replacement dome light/air vent assembly.This STC is a validation of FAA STC SH4785NM.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Geneva Aviation Master Drawing List, doc. ref. GA129, Revision B, datedSeptember 22, 2011Installation Instructions, doc. ref. GA129-2, Revision C, datedSeptember 22, 2011Compliance Checklist, doc. ref. CCL-129, Revision B, dated 15 February, 2008Instructions for Continued Airworthiness, doc. ref. ICA...	None	15/04/2013	Active	10017003
10017018 (EASA.IM.R.S.01436)	SIKORSKY GLOBAL HELICOPTERS Inc.	REV. 1	FAA STC SR01949NY-D	EUROCOPTER FRANCE AS 365N3 EUROCOPTER FRANCE AS 365N2 EUROCOPTER FRANCE AS 365N1	Installation of a Honeywell Chadwick Model 15175 VXP System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. FM00771 revision - dated 1/11/ 2005 or later approvedrevision -Flight manual Supplement;2. IC00771 revision -dated 11/09/2004 or later approved revision - Instructions for Continued Airworthiness;3. IDL 00771 revision - dated 11/09/2004 or later approved revision - Installation Drawing L...	none	29/06/2011	Active	10017018

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017020 (EASA.IM.R.S.01438)	ONBOARD SYSTEMS INTERNATIONAL	REV. 3	FAA SR01808SE	R44, R44 II	Cargo Hook System KitsThe installation as defined in MDL 155-124-00 provides for differentoptional Cargo Hook System kits depending on aircraft voltage system,with and without load weighing system and the respective cargo hook inaccordancewith FAA STC SR01808SE.With revision 2 of EASA STC 10017020S...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List (MDL) No. 155-124-00, Revision 19, dated 31 March2017, or later FAA approved revision.2. Continued Airworthiness (ICA), Document No. 123-030-00, Revision 10,dated 28 March 2017, or later FAA accepted revision.3. Rotorcraft Flight Manual Supplements, Document No. 121-048-00,Rev...	Approval of this change in type design applies only to those Robinsonrotorcraft models listed above which are equipped with Robinson hardpoint/tie down block Part Number (P/N) D134-1.Cargo Hook Kit models 200-324-00 and 200-326-00 are eligible forinstallation on those rotorcraft with 14 volt electri...	08/05/2018	Active	10017020
10017028 (EASA.IM.R.S.01447)	BLR AEROSPACE, L.L.C.	REV. 1	FAA STC SR01508SE	SEE EASA APPROVED MODEL LIST	Installation of dual tailboom strakesRevision 1 updates theSTC holder's address	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See EASA Approved Model List	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/05/2019	Active	10017028
10017039 (EASA.IM.R.S.01463)	NORTHEAST ENGINEERING & DEVELOPMENTL TD.	REV. 1	TCCA STC SH97-59	R44, R44II, R66	Bear Paw Installation.With revision 1 of this STC the R66 is added as applicable type/model.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For initial revision (Bear Paw installation for R44, R44II):- Master Drawing List 96051 Issue 2, dated 04 November 2004- Instructions for Continued Airworthiness 96051ICA Issue 2,dated 16January 2008For revision 1 (Bear Paw installation for R66):- Master Drawing List 96051 Issue 4, dated 27 July 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/03/2018	Active	10017039
10017050 (EASA.IM.R.S.01474)	AKV, Inc.	REV. 1	FAA STC SR01958LA	AS 350 B2	Installation of AKV, Inc. Ng/Np Cycle Counter P/N 350NGLTSB2Rev. 1 updates the STC holder's address	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List (MDL) No. LTS-001-B2, Rev. NC, datedSeptember13, 2006, or later approved revisions2. LTS101 Cycle Counter Installation Instructions Doc. No. 350B2-800Rev. NC or later approved revisions3. LTS101 Cycle Counter Instructions for Continued Airworthiness (ICA)Doc. No. 350B2-900 Re...	AS350B2 modification iaw STC EASA.IM.R.S.01222 issued on 20March 2008is required prior to the installation of the Ng/Np Cycle Counter.The Ng/Np Cycle Counter can only be installed on day/night VFR aircraftwith non-FADEC equipped engine.The Ng/Np Cycle Counter is for ground crew to perform maintenan...	13/09/2018	Active	10017050
10017057 (EASA.IM.R.S.01489)	AIRFILM CAMERA SYSTEMS, INC	REV. 3	FAA STC SR02137LA	SEE FAA AML	Installation of Utility Step MountRev. 1 to EASA STC 10017057 adds model MBB-BK 117 D-2.Rev. 2 to EASA STC 10017057 updates the references of master drawinglist, installation instructions and RFM supplement.Rev. 3 to EASA STC 10017057 addsmodel MBB-BK 117 D-3.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List AF145-210, Rev. F, dated 1 December 2022<(>,<) >Installation Instructions AF117-206, Rev. F, dated 1December 2022<(>,<) >Rotorcraft Flight Manual Supplement (RFMS) AF 145-207E, Rev. N/C, dated3 July 2024<(>,<) >Instructions for Continued Airworthiness (ICA) AF145-208, Rev. C, dated...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	04/07/2024	Active	10017057

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017058 (EASA.IM.R.S.01490)	AIRFILM CAMERA SYSTEMS, INC	REV. 2	FAA STC SR02138LA	T1, T2, T2+, T3 SEE FAA AML EC635 T1 (CPDS), T2+, P2+ EC135 P1, P2, P2+, P3	Installation of Utility Step Mount	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Airfilm Camera Systems Master Drawing List No. AF135-010, Revision A,dated 3 May 2008;2. Installation Manual No. AF135-006 dated 1 May 2008;3. Instructions for Continued Airworthiness AF135-008, dated 10 March2008;4. Flight Manual Supplement No. Document Number RFMS135-007, dated 24April 2008;ora...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	17/09/2021	Active	10017058
10017063 (EASA.IM.R.S.01499)	DART AEROSPACE USA, Inc.	REV. 3	FAA STC SR01853SE	MBB-BK117 D-2/D-3 MBB-BK117 D-2 MBB-BK117 B-1/B-2/C-1/C-2 MBB-BK117 A-1/A-3/A-4	Skidtube Installation ref. D117-762Rev. 1: Eligibility extended to MBB-BK117 C-2Rev. 2: Eligibility extended to MBB-BK117 D-2Rev. 3: installs Dart Skidtubes Part Number D117/D145-762-XXX Skidtubesonto the MBB-BK117 D-3 model rotorcraft.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	- Master Drawing list (MDL) MDL-D117-762, Revision M, dated22 July 2024<(>,<)>- Installation Instructions IIN-D117-762, Revision G, dated 22 July 2024<(>,<)>- Instructions for Continued Airworthiness (ICA) ICA-D117-762, Revision7, dated 05 February 2025<(>,<)>or later revisions of the above listedb...	This approval is allowed with Airbus MBB-BK117 D-2, Modification E-4449that increases MTOW to 3800Kgs.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no advers...	25/02/2025	Active	10017063
10017064 (EASA.IM.R.S.01500)	MAX-VIZ Inc.	REV. 1	FAA STC SR00532DE	212, 412, 412EP	Enhanced Vision Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. DL-212/412EV-100 revision G dated 11 July 2008 or later EASA approvedrevision – Master Data List;2. PR-212/412EV-120M revision 3 dated 7 May 2007 or later EASA approvedrevision– Instructions for Continued Airworthiness;3. PR-212/412EV-100M revision 1 dated 3 July 2007 or later EASA approvedrevis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2018	Active	10017064
10017065 (EASA.IM.R.S.01501)	MAX-VIZ Inc.	REV. 1	FAA STC SR00603DE	206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	Enhanced Vision Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. DL-206/407EV-100 revision N/C dated 10 April 2006 or later EASAapproved revision – Master Drawing List;2. PR-206/407EV-100M revision N/C dated 28 July 2006 or later EASAapproved revision – Flight Manual Supplement; 3. PR-206/407EV-120M revision O dated 10 April 2006 or later EASAapproved revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2018	Active	10017065
10017067 (EASA.IM.R.S.01503)	FARGO MANUFACTURING CO.	REV. 2	FAA SR01813CH	MD900	Installation of Auxiliary Fuel System Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Fargo Installation Instructions , Doc No. A-900-224, Rev A, dated 24thApril 2008.- EASA approved Flight Manual Supplement, EASA Doc No.900, dated 24November 2008.Or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationPro...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/06/2020	Active	10017067

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017071 (EASA.IM.R.S.01507)	L-3 WESCAM INC.	REV. 1	TCCA STC SH04-29	SEE EASA APPROVED MODEL LIST	MX-Series Camera Installation (Structural Provisions Only)Note: This revision to the STC adds a second Downlink antenna (OMNIAntenna) and a MX-10 Camera applicability.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FMS02146 revision 3 dated 4 October 2010 - Flight Manual Supplementor later revisions of the above listed documents approved by EASAMS02146 revision 6 dated 4 October 2010 - Engineering ModificationSummaryICA02146 revision 3 dated 4 October 2010 - Instructions for ContinuedAirworthiness	This STC is for structural provisions only. Functional and electricalaspects will require separate airworthiness approval.VNE limited to 126ktsVFR OnlyCategory A operations prohibited	14/01/2011	Active	10017071
10017072 (EASA.IM.R.S.01509)	DONALDSON COMPANY, Inc.	REV. 2	FAA STC SR02393CH	AS350 B, AS350 B1, AS350 B2 AS350 B3, AS350 BA	Installation of Inlet Barrier Filter systemRevision 1 reflects the name and address change from AerospaceFiltration Systems, Inc. to Donaldson Company, Inc.Revision 2 is a change to the process for acceptance of revision to thetechnical documentation to reflect the provisions of the currentbilateral...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List No. AFS-AS350B-IBF-MDL Revision F dated5 May 2008;2. Rotorcraft Flight Manual Supplement No. AFS-AS350B-IBF-FMS Revision Bdated 8 Sep. 2008;3. Instructions for Continued Airworthiness No. AFS-AS350B-IBF-ICARevision B dated 5 May 2007;or later revisions of the above listed docume...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/08/2021	Active	10017072
10017074 (EASA.IM.R.S.01516)	DART AEROSPACE Ltd.	REV. 1	TCCA STC SH91-20	AS355F2, AS355N, AS355NP AS355E, AS355F, AS355F1 AS350D, AS350D1 AS350B3, AS350BA , AS350C AS350 AS350B1, AS350B2	D350-561 Cargo Mirror installations.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MDL-D350-561 revision A dated 16 June 2010 - Master Document List;D350-561 revision D dated 16 June 2010 - InstallationInstructions;ICA-D350-561 revision 0 dated 16 June 2010 - Instructions for ContinuedAirworthiness.or later revisions ofthe above listed documents approved by EASA inaccordance wit...	none	03/09/2010	Active	10017074
10017077 (EASA.IM.R.S.01526)	DART AEROSPACE Ltd.	REV. 2	TCCA STC SH92-16	3. 214B, 214B-1 2. 212, 412, 412EP 1. 204B, 205A-1	D212-580 Cargo Mirror/LED Pulse Light InstallationThis revision adds the LED Pulse light installation to the CargoMirrors.	FAR 29 up to and including Amendment 29-51 for the affectedareasThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of theoriginal product areunchanged and remain applicable to thiscertificate/ approval.	MDL-D212-580 revision D dated 13 August 2010 - Master Document List;IIN-D21-580 revision D dated 8 February 2010 - InstallationInstructions;ICA-D212-580 revision 2 dated 20 July 2010 - Instructions for ContinuedAirworthiness;or later revisions of the above listed documents approved by EASA inaccorda...	None	26/11/2010	Active	10017077
10017080 (EASA.IM.R.S.01531)	ONBOARD SYSTEMS INTERNATIONAL	REV. 2	FAA SR01943SE	BELL 407 407	Installation of Onboard Systems Int. Cargo Hook Kits and Load WeighKits.Revision 2 issued to add a cargo hook model with a hydraulic releasesystem as the Backup Quick Release System (BQRS) and optional time-delaycircuit in the Primary Quick Release System (PQRS) and to add the C-40load weigh indicat...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List (MDL) No. 155-125-00, Rev. 22, dated October 15,2021;EASA Rotorcraft Flight Manual Supplement No. 121-050-01, Rev. 0, datedSeptember 12, 2024, orEASA Rotorcraft Flight Manual Supplement No. 121-061-01, Rev. 0, datedSeptember 12, 2024;Instructions for Continued Airworthiness (ICA)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/09/2024	Active	10017080

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017085 (EASA.R.S.00397)	AEROLITE AG	REV. 3		EC135 T2(CPDS) EC135 T1(CPDS) EC135 T1(CDS) EC135 P2+, EC135 T2+ EC135 P2(CPDS) EC135 P1(CPDS) EC135 P1(CDS)	EMS Equipment P/N 135405-501/-502.Major Changes to EASA STC10017085:STC Rev. 1: To extend approval from P1/P2, T1/T2 to all EC135 models.STC Rev. 2: Introduction of reversible C/P seat installationconfiguration P/N 135331-503 into EMS equipment configuration P/N135405-501 and introduction of Integr...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approvalThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Flight Manual Supplement FMS-202 Revision H (EMS-EquipmentP/ N135405-501)-Flight Manual Supplement FMS-410 Revision F (EMS-Equipment P/ N135405-502)or later revisions of the abovelisted documents approved by EASA-Operation Manual OPM-202 Revision H-Master Document List MDL-201 Revision L	EMS-Equipment P/N 135405-501: Installation in Rotorcraft upto andincluding S/N 0336EMS-Equipment P/N 135405-502: Installation in Rotorcraft after andincluding S/N 0337P/N 135301-503 and P/N 135543-503 are only valid from the rotorcraft S/N870 and subsequent.	25/11/2016	Active	10017085
10017086 (EASA.R.S.00461)	AIR AMBULANCE TECHNOLOGY GmbH	REV. 4		AS 332 L2, SA 330 J, EC 225 LP AS 332 C, AS 332 C1, AS 332 L1	Cabin Interior "Quick Conversion" kits, installing either AAT AirAmbulance Equipment or AAT Mission Equipment cabin layout configurationsNotes:Rev. 3 superseded previous EASA.R.S.00461 Rev. 2, underlining AssociatedTechnical Documentation updates.Rev.4 corrects minor typographic error in the Continu...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	See attached STC Continuation Sheet for Associated TechnicalDocumentation according to cabin conversion kits Parts Number (P/N) andaircraft models	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	01/04/2020	Active	10017086
10017087 (EASA.R.S.00462)	AIR AMBULANCE TECHNOLOGY GmbH	REV. 12		EC635 T2+/EC635 T3 EC635 T2, EC635 T2+, EC635 T3 EC635 P2+/EC635 P3/ EC635 T1 EC635 P2+, EC635 P3, EC635 T1 EC135 T2+/EC135 T3 EC135 T2+, EC135 T3 EC135 P3/EC135 T1/ EC135 T2 EC135 P3, EC135 T1, EC135 T2 EC135 P1/EC135 P2/ EC135 P2+ EC135 P1, EC135 P2, EC135 P2+	Installation of Air Ambulance Equipment, Mission Equipment,AirborneRadiation Measuring EquipmentRevision 1:Introduction of Mission Equipment and Airborne Radiation MeasuringEquipmentRevision 2:Introduction of VIP Interior P/N 135-25-20-5000-900 incl. flooring,seats, fairing and cabinetsRevision 3:I...	See Appendix 1 to STC 10017087 Rev. 12.The requirements forenvironmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See Appendix 2 to STC 10017087 Rev. 12or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	For Air Ambulance Equipment P/N 135-25-20-107.000-500 series theinstallation of EASA STC 10063854 is prerequisite.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introd...	23/05/2022	Active	10017087
10017088 (EASA.R.S.0057)	AEROLITE AG	REV. 8		EC 135 T3 (CPDS) EC135 T2+, EC135 T3 EC 135 T2 (CPDS) EC 135 T2+ EC 135 T1 (CPDS) EC 135 T1 (CDS) EC135 P3, EC135 T1, EC135 T2 EC 135 P3 EC 135 P2 (CPDS) EC 135 P2+ EC135 P1, EC135 P2, EC135 P2+ EC 135 P1 (CPDS) EC 135 P1 (CDS)	Installation of Emergency Medical Service (EMS) equipmentInitial Issue:EMS Equipment P/N 135375-501/-502The presented EMS Equipment describes a fully integrated interior ofmedicalsupport devices.See Flight Manual Supplement FMS-002, FMS-412.Due to various operations different stretcher systems andc...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	For EMS Equipment P/N 135375-501:- Flight Manual SupplementFMS-002 Revision M- Operations Manual OPM-002 Revision I- Master Document List MDL-002 Revision AFFor EMS Equipment P/N135375-502:- Flight Manual Supplement FMS-412 Revision H-Operations Manual OPM-002 Revision I-Master Document List MDL...	1. Limited to helicopters with CDS/CPDS cockpit variant2. EMS configuration P/N 135375-501 is eligible for installationintohelicopter with S/N up to andincluding S/N 3363. EMS configuration P/N 135375-502 is eligible for installation intohelicopter with S/N after andincluding S/N 3374. Swivelling A...	02/05/2024	Active	10017088
10017090 (EASA.R.S.00753)	DART AEROSPACE Ltd.	REV. 3	TCCA SH07-11 ISSUE 4	AS350B, AS350B1, AS350B2 AS350B3, AS350BA, EC130B4.	Installation of Sand Filter (Engine air inlet protection)Notes:1. The STC was initially issued to CGTM (initial reference:EASA.R.S.00753)2. Revision 1 to this STC (issued under reference EASA.R.S.00753 Rev. 1)reflected: a) the transfer of EASA STC EASA.R.S.00753 from CGTM to Turbomeca b) updat...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Definition of the type design change: Dart Aerospace Ltd. Master Document List MDL-QB0777 Revision A datedMay 7, 2014Installation of the Sand Filter: Dart Aerospace Ltd. Installation Instructions IIN-QB0777 Revision Adated May 5, 2014Operation of the Sand Filter: Dart Aerospace Ltd. Flight Manual Su...	This STC is not applicable to AS350B3 model helicopters withmodification OP4305 (Arriel 2D engine installation) incorporated.Prior to installation of this design change it must bedetermined thatthe interrelationship between this design change and any otherpreviously installed design change and/ ora...	17/12/2014	Active	10017090

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017093 (EASA.R.S.01005)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 2		BO 105 C	Installation of FLIR Ultra force II SystemThe existing FLIRUltra 400 system installation is adapted to use theFLIR Ultra Force II system. UF2 platform, adapter plate, CEU, CEUmounting tray, LCU and power supply panel are new installed. Bolster,step, dovetail block, skin and pedestal break panels, V...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Doc No. CMA021 "Documento Técnico", Ed. 1, dated 27 July 2004- Doc No. CMA021-ID "Informe sobre el Diseño", Ed. 1Installation Instructions in accordance with:- Doc No. CMA021-ID"Boletin de Ingenieria", Edición 1- Doc No. CMA021-MID "Instrucciones de Mantenimiento e Instalación" Ed.1-UltraForcell...	Subjected to the conditions, limitations and procedures contained in DocNo. CMA021-AFMS "Supplement for FLIR System - Ultra Force II", Iss 1Rev. 0Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed c...	01/02/2019	Active	10017093
10017094 (EASA.R.S.01006)	AVIATION SUPPORT GmbH	REV. 1		BO105 S (CBS-4, CBS-5)	Installation of CHARM I - Gas Detection System.CHARM I (CH4Airborne Remote Monitor) is a laser-assisted technology forremote airborne surveillance / monitoring of gas transport pipelines.The system is installed within passenger and baggage compartment. Thesensor head is located in the area of the h...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-27, Amendment 4<(>,<)> (not required by Part 21.101) - 27.1, 21, 25, 27, 29, 251, 301, 303, 305, 307, 309, 321, 562, 60...	Ergänzung zum Flughandbuch FMS-ASE-90411, Rev. 1-0<(>,<)>orlater revisions of the above listed documents approved by EASA.- Installationsanleitung REP-ASE-91018-4, Rev. -.- Instructions for Continued Airworthiness ICA-ASE-90411, Rev. 1-0.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product	23/06/2017	Active	10017094
10017100 (EASA.R.S.01056)	ACC COLUMBIA Jet Service GmbH	REV. 1		HUGHES 369D, HUGHES 369E	Installation of Isolator Washing PlatformRev. 1 Transfer toACC Columbia Jet Service GmbH		- Flight Manual Supplement SPOH_12155, dated 31.07.2006 orlater EASA approved revision- Umrüstunganweisung (Installation Manual) II_12155	Helicopter must be eqipped with- High Skid Landing Gear and- McDonnel Douglas Helicopter Cargo Hook Kit P/N 369H90072-505	24/02/2022	Active	10017100
10017101 (EASA.R.S.01071)	HELI AUSTRIA GmbH	REV. 3		MD900	Upgrading of existing Single Cargo Hook to Dual Hook SystemRev. 1: Transfer of STC to GVH Aerospace (Ireland) Ltd., Pembroke Place10, DO2 ED86 Dublin Eire.Rev. 2: Transfer of STC from Nova System & Engineering Ltd previouslyGVH Aerospace (Ireland) Ltd. to Heli Austria GmbH, Heliport, 5600St.Johann i...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-27, Initial Issue: 27.561, 27.685, 27.771, 27.773, 27.777, 27.1301, 27.1309, 27.1321,27.1351, 27.1357, 27.1365, 27.136...	- Bournemouth Aviation Consultants Modification BAC/MD/003-Bournemouth Aviation Consultants AFM Supplement FMS/ 253/28,Revision 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/02/2023	Active	10017101
10017102 (EASA.R.S.01072)	AIRLIFT A/S	REV. 1		SA 365 C,SA 365 C1,SA 365 C2 SA 365 C3,SA 365 N,SA 365 N1 AS 365 N2,AS 365 N3	EMS-Installation/Installation of Medical Equipment and associatedattachment and supports.Note: this STC is issued for the purpose of transferring STC No.EASA.R.S.01072 of Lufttransport AS to the above identified newholder.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplements :- EMS Installation kit 555 -25-212-001 N° LT36525-032.-Incubator Transport System NF02 Lateral Configuration 555-25-200-100N °LT36525-029.-IVA Stretcher 555-25-201-100 N°LT 36525-030.or later revisions of the above listed documents approved by EASATechnical Order N °365-25-0...	none	23/08/2012	Active	10017102
10017113 (EASA.R.S.01090)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		2. 212, 412, 412 EP 1. AB412	Installation of a pitot heater failure warning indicatorRev. 1: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Associated Technical Documentation listed on Technical Document CMA077Issue 1 Rev. 0.Installation / Instructions for Continued Airworthiness in accordancewith:- Engineering Bulletin CMA077-BI Issue 1 Rev. 0<(>,<)>-Maintenance Instructions CMA077-IM Issue 1 Rev. 0<(>,<)>-Drawing CMA077-01-01-00 rev. 0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/02/2019	Active	10017113

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017114 (EASA.R.S.01094)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		2. 212, 412, 412EP 1. AB412	Installation of a standby horizon emergency power supply warningindicator.Rev. 1: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Associated Technical Documentation listed on Technical Document CMA078Issue 1 Rev. 0.Installation / Instructions for Continued Airworthiness in accordancewith:- Engineering Bulletin CMA078-BI Issue 1 Rev. 0<(>,<)>-Drawing CMA078-01-00-00 rev. 0, andOperation in accordance with:-Flight Manual Suppleme...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/02/2019	Active	10017114
10017118 (EASA.R.S.01125)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		S-61N	External hoist P/N 76378-260-D replacement by P/N 76378-500Rev. 1: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CMA095-AFMS Supplement for Air Equipment Electric Hoist Goodrich P/ N76378-500.CMA095-MID Maintenance and installation/Removal Manual.or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Sikorsky S-61N operated by HELICSA (S/N 61756, 61758, 61299, 61361 &61741).Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthi...	01/02/2019	Surrendered	10017118
10017129 (EASA.R.S.01219)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	AB139 VIP 28 P/N 6AB1KT003-001 Interior Configuration.This STC supersedes EASA STC EASA.R.S. 01219.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement No 6AB1RFM-1-1	Approval of this change in type design applies only to those AB139rotorcraft previously equipped with EASA approved Installation of AgustaKit VIP PROVISION P/N 4G2520F00511.	09/06/2010	Active	10017129
10017130 (EASA.R.S.01220)	MECAER AVIATION GROUP S.p.A.	REV. 5		AB139, AW139	VIP 29 Interiors P/N 6AB1KT004-001The revision 5 introducesan eleven passenger configuration<(>,<)> arelocation of thefire extinguisher positions and installation of newcarpets.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Design Data Sheet Report DDS-2019-007 Issue ASupplement Flight Manual 6AB1RFM-1-2 revision ALOwner's Manual (ICA) 6AB1WNM-2-2, Reissue 2 Rev. AEor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/11/2019	Active	10017130
10017131 (EASA.R.S.01224)	BRISTOW HELICOPTERS Ltd.	REV. 1	CAA UK RESPONSIBILITY	AS 332 L, AS 332 L1	Rockwell Collins TCAS II, TCAS 4000 System software upgradefrom Version7.0 to 7.1.Rev 1 covers modification of Rockwell Collins TCAS-4000 TCAS II updateto version 7.1software. Modification : MOD/332/34.5538	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Bristow AS 332L/L1 Flight Manual Supplement No. 36-Rockwell CollinsTCAS II, issue 4;- Bristow AS 332L/L1 Flight Manual Supplement No. 39-Rockwell CollinsTCAS II Version 7.1,initial issue;or later revisions of the above listed documentsapproved by EASA.- Certification Plan for MOD/ 332/34/345538-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/08/2013	Active	10017131
10017135 (EASA.R.S.01229)	RTERESEAU DE TRANSPORT D'ELECTRICITE	REV. 1		AS 332 C1	Installation for Human External Cargo (HEC) applicationsNote: STC Rev.1 is re-issuance of the original STC certificateEASA.R.S.01229 and approves compatibility of the STC with AS 332 C1helicopters when equipped with the following optional equipment: AirbusHelicopters avionics suite AHCAS and Multi-p...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: JAR 29 Amdt. 3,requirement 29.21, 29.25, 29.27, 29.29, 29.49, 29.51 (c), 29.55, 29.64,29.65, 29.67, 29.75, 29.141, 29.143,2...	- RTE „Master Drawing List", report no.NT-MAINLA-CNER-STH-PAMM-05-01270, ind. 3.0- RTE „Instructions Techniques de Montage", report no.NT-MAINLA-CNER-STH-PAMM-05-01263, ind. 3.0- RTE „Manuel de Maintenance", report no.DT-ETUD-CNER-STH-PAMM-05-01430, ind. 6.0- RTE „Supplément au Manuel de Vol", repor...	Installation of this STC requires that the helicopter is equipped withAirbus Helicopters optional equipment for Transport of External Load(4500kg) – SUP. 10.6 or SUP.20 as applicable to helicopter configuration.Prior to installation of thischange/repair it must be determined thatthe interrelationshi...	26/06/2019	Active	10017135

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017136 (EASA.R.S.01230)	AIRBUS HELICOPTERS UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	EC135 T1, EC135 T2, EC135 T2+ EC135 P1+, EC135 P2+	Change to existing EASA STC EASA.R.S.01230 - NVG CompatibleLightingSystem - to extend the approved Night Vision Goggletypes to allowsingle pilot operations and to include the latest EC135 types.	As per EC135 TCDSThe Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Modification DefinitionDesign Report DR/135900-001 Issue C dated 2 September 2009Flight Manual Supplements-ECUK RFMS No. 28 Issue 2 dated 18 November 2009For dual pilot operationsusing Northrop Grumman M949 NVG on EC135 T1,T2 and T2+-ECUKRFMS No. 29 Issue 2 dated 19 November 2009For single pilot o...	None	20/11/2009	Active	10017136
10017140 (EASA.R.S.01242)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	VIP 37 Interiors P/N 6AB1KT005-001: Cabin interiors modification.This STC supersedes EASA STC EASA.R.S. 01242.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Publication No. 6AB1RFM-1-3 - Supplement to AB139/ AW138 RFM- Publication No. 6AB1WNM-2-3 - Owner's Manual	The change in type design applies only to those AB139/ AW139Rotorcraftpreviously equipped with Agusta "Kit VIP Cabin Passenger Provision P/ N4G2520F00711".	09/06/2010	Active	10017140
10017148 (EASA.R.S.01251)	SWISS HELICOPTER ENGINEERING AG	REV. 2	FOCA STC 56-30-01	AS 350 B3	Bubble Window RH Installation P/N 030603/350BW according FOCA Data Sheet56-30-01.Installation of P/N 030603/350BW according to FOCA data sheet 56-30-01at issue 3.Revision 1: This is a change to EASA.R.S.01251 issued 23/03/2006 whichwas based on STC FOCA 56-30-01 at issue 2, dated 24/12/2004. The cha...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- RFMS, bubble window kit 030603/350BW, Eurocopter Helicopter ModelAS350B3, issue 2 dated 1/05/2006or later revisions of the above listed documents approved by EASA- FOCA data sheet 56-30-01 issue 3 dated 10.5.2006- Bubble Window Kit, rev.01 dated 20.06.2004 including installationmanual, instructio...	1. When the bubble window is used for vertical reference, the followingapplies: If the pilot cannot firmly hold the collective pitch lever whenin the position intended for vertical reference through the bubblewindow, an approved collectivepitch lever extension must be installed.2. With the bubble w...	22/11/2023	Active	10017148
10017149 (EASA.R.S.01252)	MECAER AVIATION GROUP S.p.A.	REV. 2		A109S, AW109SP	Cabinet Installation P/N 6A10AD001-001.Extension of the STC10017149 to the AW109SP model that is part of thesame TC Number EASA.R.005	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Report 6A10RAD-002 Rev. B "Cabin Cabinet Interiors ConfigurationDescription"Report 6A10AD-001 Issue B "NDC Cabinet Installation 6A1OAD001-001"Report 6A10WNM-2-1 Rev. A "Owners manual""or later revisions of the above listed documents approved by EASA"	None	01/03/2011	Active	10017149
10017150 (EASA.R.S.01253)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	CD Player Installation P/N 6AB1EL017-001 the change consists in theinstallation of a CD Player into passenger cabin.This STC supersedes EASA STC EASA.R.S.01253.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	None	The change in type design applies only to those AB139 Rotorcraft previously equipped with Agusta provision P/N 3G2520A00311	09/06/2010	Active	10017150
10017152 (EASA.R.S.01255)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		SA 330 J	Installation of an external basket and external reinforcement of thestructure (as necessary) to carry a Bambi Bucket and its accessoriesduring fire fighting operations.Rev. 1: Transfer of STC		Flight manual Supplement CMA098-AFMS/1 Issue 1 Revision 0 dated 6February 2008Maintenance & Installation/Removal instructions CMA098-MID issue 1revision 0Technical Document CMA098Issue 1 revision 0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/02/2019	Active	10017152

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017153 (EASA.R.S.01256)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		269D	Introduction of EAC-333-000 Airborne Camera SystemRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Modification ATL/33/M003 & Definition Document refDD/001/9700 dated 14 March 2006Aviation Traders RFM Supplement Number 042 Issue 1 dated September 15or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Restricted to: G-TAMA ASN 051A, G-TAMB ASN 052A, G-TAMC ASN054A, G-TAMDASN 056A & G-TAME ASN 035APrior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseef...	09/11/2021	Active	10017153
10017155 (EASA.R.S.01261)	PREMIAIR AIRCRAFT ENGINEERINGLIMITED	REV. 2	CAA UK RESPONSIBILITY	AS365N2, AS365N3, SA365N1	Installation of Honeywell MK XXI EGPWSNote: This revision is to amend an existing EASA STC (RefP-EASA.R.S. 01261 rev. 1)to add the AS 365N3 model	The Certification Basis for the original product stated in TCDS N. 159remains applicable to this certificate/ approval	-Installation in accordance with PremiAir Aircraft Engineering Modification reference 09-026 issue 2.- PremiAir Aircraft Engineering RFM Supplement 09-AS365N3-03 Issue 1- Installation in accordance with PremiAir Aircraft EngineeringModification reference 06-013-PremiAir Aircraft Engineering RFM Suppl...	None	01/02/2010	Active	10017155
10017156 (EASA.R.S.01263)	ZODIAC AEROSAFETY SYSTEMS	REV. 12		S-92A	Installation of AERAZUR Internal Auxiliary Fuel System (IAFS) completionkit p/n 508617 or 508617-1 or 508617-2 or 508617-3.STC revision 1 introduces kit p/n 508617-1 and revised documentation.STC revision 2 introduces edition 15 of RFM supplement.STC revision 3 introduces kit p/n 508617-2 and revise...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Special Conditions (s):IAFS CRI C-1 Issue 3 - Crash conditions - fitting factorIAFS CRI E-1 Issue 3 - Fuel system crash resistance - Rearw...	S-92A Flight Manual Supplement n° 060S437, edition 16 dated06 December2010, and temporary revision dated October 24, 2014.or later revisions of the above listed documents approved by EASA.AERAZUR Organigramme Technique n° 508617-1, edition 11 dated 23 July2008.AERAZUR Organigramme Technique n° 5086...	The IAFS Completion Kit can be installed only on S-92A helicoptersequipped with:- S-92A Avionics Management System (AMS) version n° 091-2527-007 orlater approved version, and- AERAZUR IAFS Provision Kit p/n 509429-02 or 509429-03 approved underEASA STC n° 10017259 revision 3 or later.When including5...	08/01/2015	Active	10017156
10017157 (EASA.R.S.01265)	AEROLITE AG	REV. 1		MBB-BK 117 C-2	EMS Equipment P/N 145221-501.,,This revision 1 to STC EASA.R.S.01265 introduces modification onexisting cabin configuration and introduces two new cabinconfigurations. See MDL-06-006 Rev. C.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	FMS-06-005 Rev. B.Chapter 04 (Airworthiness Limitations) ofOPM-06-007 Rev. Bor later revisions of the above listed documents approved by EASA.Certification program CPR-16-006 Rev. B.Master Drawing List DWL-16-006 Rev. C.Instruction for Continued Airworthiness included in OPM-06-007 Rev. B.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/10/2016	Active	10017157
10017161 (EASA.R.S.01269)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	Cabinet Utility Installation P/N 6AB1AD004-001.This STC supersedes EASA STC EASA.R.S.01269.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- NDC n. 6AB1AD-001-Utility Cabinet Installation Owner's Manual, document n. 6AB1WNM-2-6	Cabinet Utility Installation P/N 6AB1AD004-001 is compatible with AgustaS.p.A. cabin arrangements n. 3G2520F00111 and 3G2520F00211.	09/06/2010	Active	10017161
10017162 (EASA.R.S.01270)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	115V AC Power Installation.Electrical power connectors installation in the passenger compartment.This STC supersedes EASA STC EASA.R.S. 01270.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Technical file per S.E.I.NDC n. 6AB1EL-004/ III- Drawing n. 6AB1EL026-001- Owner's Manual n. 6AB1WNM-2-9	None.	09/06/2010	Active	10017162

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017163 (EASA.R.S.01271)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	ICS Installation. Intercommunication System in the passengercompartment.This STC supersedes EASA STC EASA.R.S. 01271.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Technical file per S.E.I.NDC n. 6AB1EL-003/ III- Drawing n. 6AB1EL020-001- Owner's Manual n. 6AB1WNM-2-10	None.	09/06/2010	Active	10017163
10017170 (EASA.R.S.01278)	MECAER AVIATION GROUP S.p.A.	REV. 3		AB139/ AW139	VIP 43 Interiors P/N 6AB1AD006-001. Customization passengercabininteriors (upholstering, installing decorative liners and bulkheads.SAT-COM headsets, small cabinet and other minor items)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFM Supplement VIP 43 Interiors 6AB1RFM-1-4, Rev. Uor laterrevisions of the above listed documents approved by EASA.Owner's Manual VIP 43 Interiors 6AB1WNM-2-8, Re-Issue 2, Rev. O(Instruction of Continued Airworthiness) NDC 6AB1AD-217/III,Issue C, dated 02.04.2015 (Master Document List)VIP 43 Major...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/04/2015	Active	10017170
10017171 (EASA.R.S.01282)	KUERZI AVIONICS AG	REV. 3		SA 330 J	Avionics UpgradeGPS, Monitor, Cabin Intercom, EMS, SAT111 Tracking System, HF Radio, WXRadar, Power Connector, FM RadioReason for STC re-issue:Transfer of EASA.R.S.01282 Rev. 2 from KUERZI AVIONICS DEUTSCHLAND GMBHto KUERZI AVIONICS A.G. (EASA.21J.365)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document and Drawing List No. MDL-200616059 Rev. C or laterapproved revisionsFlight Manual Supplement Garmin GPS165 No. FMS-200616059 Rev. A or laterapproved revisions	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/06/2018	Active	10017171
10017172 (EASA.R.S.01286)	AEROLITE AG	REV. 2		EC135 T3 EC135 T1, EC135 T2, EC135 T2+ EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+ EC135 P1, EC135 P2	Installation of Emergency Medical Services (EMS) Equipment P/ N135500-501 or P/N 135500-502Revision 1Extension of applicability to Airbus Helicopter Deutschland EC135 P2+and EC135 T2+Revision 2- Change of STC holder from "Aerolite Max Bucher AG" to "Aerolite AG"- Extension of applicability of EMS Equ...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Rotorcraft Flight Manual Supplement FMS-210 Revision E applicable toP/N 135500-501- Rotorcraft Flight Manual Supplement FMS-407 Revision D applicable toP/N 135500-502- OperationManual OPM-210 Revision E- Master Document List MDL-210 Revision For later revisions of the above listed document(s) app...	The initial issue of this STC supersedes EASA STC 2004-242 and MajorModification No. 2004-11064.Limited to helicopters with CDS/CPDS cockpit variants.Extension of applicability toEC135 T3(CPDS) introduced with Revision 2of this STC is limited to rotorcraft S/N 0420.Prior to installation of this cha...	06/07/2022	Active	10017172
10017173 (EASA.R.S.01288)	ECMS AVIATION SYSTEMS GMBH	REV. 1		EC635 T3(CPDS) EC635 T2+ EC635 T1 (CPDS) EC635 P3 (CPDS) EC635 P2+ EC135 T3 (CPDS) EC135 T2 (CPDS) EC135 T2+ EC135 T1 (CPDS) EC135 P3 (CPDS) EC135 P2 (CPDS) EC135 P2+ EC135 P1 (CPDS)	Balance Weighing System BWS02Note: Revision 1 of the original STC EASA.R.S. 01288 is issued to extendthe applicability of the original STC to the EC 135 T3/P3 and EC 635T3/P3 models.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:For the EC135 T3/ P3 & EC635 T3/P3 models:CS 27 Amendment 2:27.25/27/141/231/241/251/301/303/305/307/341/571/609/610/611/613/865/1301/1323/1325/1351/1357/1501/1581CS 29 App...	Flight Manual Supplement BWS02_fms, issue 01-07-2007or later revisions of the above listed documents approved by EASA-,,Master Drawing List BWS02_MDL_EASA Revision 2-,,Installation Instructions BWS02_inst.-,,Maintenance Manual & User GuideBWS02_mm_ug	1) The Balance Weighting System BWS02 is compatible with the followingEC135 cargo hook installations:-Dual External cargo Hook (AHD FMS 9.2-47) or-External Cargo Hook (AHD FMS 9.2-19)2) Fixed provisions including internal wiring harness are required forinstallation (AHD P/N L851M1886051 or equivalen...	11/05/2015	Active	10017173
10017174 (EASA.R.S.01289)	PREMIAIR AIRCRAFT ENGINEERINGLIMITED	REV. 2	CAA UK RESPONSIBILITY	AS365N2, AS365N3, SA365N1	Installation of Honeywell KTA 870 Traffic Advisory SystemNote: This revision is to amend an existing EASA STC (RefP-EASA.R.S.01289 rev. 1) to add the AS365N3 model	The Certification Basis for the original product stated in TCDS N. 159remains applicable to this certificate/ approval	-Installation in accordance with PremiAir Aircraft EngineeringModification reference 09-025 issue 2.- PremiAir Aircraft Engineering RFM Supplement 09-AS365N3-02 Issue 1- Installation in accordance with PremiAir Aircraft EngineeringModification reference 07-009-PremiAir Aircraft Engineering RFM Supplem...	None	01/02/2010	Active	10017174

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017175 (EASA.R.S.01290)	PREMIAIR AIRCRAFT ENGINEERINGLIMITED	REV. 2	CAA UK RESPONSIBILITY	AS365N2, AS365N3, SA365N1	Installation of Honeywell KMD 850 Multi Function DisplayNote: This revision is to amend an existing EASA STC (RefP-EASA.R.S.01290 rev. 1) to add the AS 365N3 model	The Certification Basis for the original product stated in TCDS N. 159remains applicable to this certificate/ approval	-Installation in accordance with PremiAir Aircraft EngineeringModification reference 09-024 issue 2.-PremiAir Aircraft Engineering RFM Supplement 09-AS365N3-01 Issue 1-Installation in accordance with PremiAir Aircraft EngineeringModification reference 07-008-PremiAir Aircraft Engineering RFM Supplem...	None	01/02/2010	Active	10017175
10017176 (EASA.R.S.01294)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	VIP 55 Interiors P/N 6AB1AD007-001The change consists in customizing passenger cabin interiors(personalized seat layout, carpet and liners, devices, adding a smallcabinet and others minor items).This STC supersedes EASA STC EASA.R.S.01294.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Publication nr. 6AB1RFM-1-5 - Supplement RFM	The change in type design applies only to those AB139/ AW139Rotorcrafts previously equipped with EASA "Kit VIP Provision P/N 4G2520F01311".	09/06/2010	Active	10017176
10017178 (EASA.R.S.01296)	ACC COLUMBIA Jet Service GmbH	REV. 2		EC135 P1/ EC135 P2/ EC135 T1	Revision 1 of this STC is due to the transfer of EASA STCEASA.R.S.01296: Installation of a HeliMap.MIDI.P0252 Moving Map System.Revision 2: Transfer to ACC COLUMBIA Jet Service GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Rotorcraft Flight Manual Supplement P1, P2, T1 (CDS, CPDS), EC135-69008-800-S-MF Rev. 0.2. Instructions for Continued Airworthiness EC 135-69008-810-S-MM Rev.0.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/02/2022	Active	10017178
10017179 (EASA.R.S.01297)	ACC COLUMBIA Jet Service GmbH	REV. 2		MBB-BK117 B-2	Revision 1 of this STC is due to the transfer of EASA STCEASA.R.S.01297: Installation of a Heli.Map.MIDI.P0252 Moving Map System.Revision 2. Transfer to ACC COLUMBIA Jet Service GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Rotorcraft Flight Manual Supplement BK117 B-2, BK 117-69007-800-S-MF.2. Instructions for Continued Airworthiness BK117-69007-810-S-MM.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/02/2022	Active	10017179
10017183 (EASA.R.S.01316)	AEROLITE AG	REV. 1		MBB-BK 117 C-2	Installation of NATO Stretcher Retainer.This STC revision is issued for the purpose of transferring the STC toAerolite AG.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment: CS 27 Amdt. 2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levelsu...	Flight Manual Supplement FMS-06-008, Rev. N/C, dated 27.09.2006or later revisions of the above listed documents approved by EASA.Instructions for Continued Airworthiness and Operation ManualOPM-06-010, dated 04.10.2006.	The NATO Stretcher (NSN 6530-01-380-7309) referred to in thisinstallation is not part of this STC.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadv...	15/03/2016	Active	10017183
10017184 (EASA.R.S.01317)	AIRBUS HELICOPTERS	REV. 1		EC135 T2, EC135 T2+ EC135 P2, EC135 P2+	Daylight Camera Installation (Ultramedia III) (Structural and ElectricalProvisions): Installation of a camera Ultramedia II/III/ HD in accordancewith ECE Master Document List DL L853H0001E01, Rev. B.Rev. 1: Transfer of STC 10017184 from Airbus Helicopters España toAirbus Helicopters		Flight Manual Supplement: "Supplement for FSI UM II/ III/HD Gyro Stabilised Camera", FMA 11.100.Installation Instructions: Master Document List DL L853H0001E01, Rev. B.Instructionsfor Continuous Airworthiness "Flir Manual FSI UM II/III/ HD", Rev. A.		09/06/2022	Active	10017184

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017187 (EASA.R.S.01324)	AEROLITE AG	REV. 4		EC635 T2+/ T3(CPDS) EC635 P2+/ P3(CPDS)/ T1(CPDS) EC135 T2(CPDS)/ T3 (CPDS) EC135 T1(CDS)/ T1 (CPDS)/ T2+ EC135 P2(CPDS)/ P3 (CPDS) EC135 P1(CDS)/ P1 (CPDS)/ P2+	EMS equipment P/N 135572-501.Revision 4 of the EASA STC 10017187 enhances the applicability of EMSEquipment P/N 135572-501 for the EC135 P3/T3 models / variants andintroduces the following modifications / components:- Aeration Cover Inst. P/N 135-0227093-501.- Window Bay Rack Inst. P/N 135-0215599-5...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment: CS 27 Amdt. 2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levelsu...	Flight Manual Supplement: FMS-06-007, Rev. F, Issue date July 31st, 2016or later revisions of the above listed documents approved by EASA.Master Document List MDL-06-019 Revision G, dated October 14th, 2016.Instructions for Continued Airworthiness: OPM-06-009 Rev. F, dated 31stJuly, 2016.	S/N: 337 and up.The TC holder optional Air Conditioning System is not compatible withthis installation up to and including S/N 869.New installations of this STC are only allowed with the revision coveredby this approval or later approved revisions.Prior to installation of this design change it mustt...	21/10/2016	Active	10017187
10017194 (EASA.R.S.01331)	AEROLITE AG	REV. 5		AW139, AB139 AB 139, AW 139	EMS Medical Rack Installation P/N 139099-501.Rev. 1 to reflect STC holder name change.Rev. 2 to introduce a new cylinder rack P/N 139-0250648-501 into thecabin of an AB/AW139 rotorcraft.Rev. 3 Introduction of a new Equipment Rack Installation P/N139-0281111-501 and Backpack HolderInstallation P/N 13...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement, FMS-06-012 rev. GInstructions forContinued Airworthiness and Operations Manual ,OPM-06-014 rev. HMaster Document List, MDL-06-024 Rev. HCertification Programme Report, CPR-22-006 Rev. Dor later revisions of the above listed document(s) approved/acceptedunder the EASA syst...	Leonardo Helicopter EMS (MEDEVAC) ELECTRICAL PROVISIONS 3G2564A01411must be installed with modifications according to 3G2564W00201 (Page 1only).For long nose AW139, electrical provision P/N 4G2564A00112 plus EMS KitP/N 4G2564A00214 must beinstalled.For short nose AW139 Forward Upper Panel LHD P/N 3...	02/08/2023	Active	10017194
10017198 (EASA.R.S.01341)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	VIP 87 Interiors P/N 6AB1AD008-001.This STC supersedes EASASTC EASA.R.S.01341.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Publication No. 6AB1RFM-1-6 Supplement to AW139 RFMPublication No. 6AB1WNM-2-12 Owner's Manual	This STC is only applicable to the AB139 and AW139 helicopters equippedwith the Agusta provision for VIP Cabin Interiors P/N 4G2520F01511.	09/06/2010	Active	10017198
10017200 (EASA.R.S.01349)	ECMS AVIATION SYSTEMS GMBH	REV. 4		EC635 P2+/-P3/-T1/-T2+/ T3 EC135 T2+/-T3 EC135 P1/-P2/-P2+/-P3/-T1/-T2	Load Attachment Device EAD01.Provides attachment provisionson rotorcraft for fast roping/ rappellingand Human ExternalCargo operations.Rev. 1:Revision of previous LBA STC No. RC1234, dated 24 Nov 2003,EASA-approval No. 1025. New STC No EASA.R.S.01349 Rev 1. The technicalchanges were:- the system-...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement for External Abseil Device EAD01 onEC135/EC635, EAD01_FMS_EC135_635_EASA, Revision 5or later revisions of the above listed documents approved by EASA.Master Document List for EAD01 for rotorcraft EC135 and EC145,EAD01_MDL_EASA, Revision 10.Installation Instructions for the E...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/08/2017	Active	10017200
10017202 (EASA.R.S.01351)	AIRBUS HELICOPTERS	REV. 2		EC135 T2, EC135 T2+ EC135 T2 , EC135 T2+ EC135 P2, EC135 P2+	Daylight Camera Installation (MX-15i Wescam) (Structural & ElectricalProvisions) and Operator Work Station.Installationof a Camera MX15i Wescam and related Operator WorkStationinaccordance with ECE Master Document Lists DL L853H0002E01 Rev.B and DL L854H0001E01 Rev.B.Rev. 2: Transfer of STC 100172...		Flight Manual Supplement:Supplement for Forward Looking Infrared Wescam System LX-15i" FMA 11.101Installation instructions:Master Document Lists DL L853H0002E01 Rev. B and DL L854H0001E01 Rev. BInstructions for continuous Airworthiness"Flir Manual Wescam MX-15i" Rev. A	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/06/2022	Active	10017202
10017213 (EASA.R.S.01369)	ACC COLUMBIA Jet Service GmbH	REV. 2		MBB-BK117 B-2/ MBB-BK117 C-1	Revision 1 of this STC is due to the transfer of EASA STCEASA.R.S. 01369:Installation of an EAE Heli.Map.MDI.P0252 system with extension box (foradvisory only).Installation of a moving map system into BK117B-2 and BK117C-1 models.Revision 2: ACC COLUMBIA Jet Service GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement Eurocopter BK117B-2/C-1ACC-BK117-79003-800-S-MF Rev. 1, dated 31.05.2007.Instructions for Continued Airworthiness ACC-BK117-79003-810-S-MM Rev.0, dated 03.04.2007.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/02/2022	Active	10017213

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017217 (EASA.R.S.01374)	AEROLITE AG	REV. 3		EC 135 T2 (CPDS) EC 135 T2+ EC 135 T1 (CPDS) EC 135 T1 (CDS) EC 135 P2 (CPDS) EC 135 P2+ EC 135 P1 (CPDS) EC 135 P1 (CDS)	EMS Stretcher Inst. P/ N135525-501/502/503/504This STC 10017217 Rev. 2 is revision of STC No. EASA.R.S.01374 Rev. 1,introducing the following components/modification:- Modificationof the pre-requisite for the Secondary Carbon StretcherInstallation P/N 135525-501/-502/-503/-504.- Introduction of Seco...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement: FMS 06-006 rev Bor later revisions of the above listed documents approved by EASAInstruction for Continued Airworthiness: OPM-06-008 rev BInstallation Instructions: IM-06-009 rev B	S/N:Installations P/N 135525-501 to -504 are valid for installation on theAerolite Integral Floor Inst. P/N 135301-50X with the followinglimitations:- P/N 135525-501 and -503 are eligible for installation on all EC135models up to and including S/N 336.- P/N 135525-502 and -504 are eligible for insta...	12/02/2019	Active	10017217
10017221 (EASA.R.S.01382)	KUERZI AVIONICS AG	REV. 1		BELL 206B JET RANGER III	SeLA II and Archer Z-150 System Installation.The present major change approval updates the existing HELLAS systeminstallation (STC EASA.R.S. 01382) with a helmet helmet-mounted displayand sighting system (Archer Z-150) and installation of asensor-basedlanding aid (SeLA II).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement FMS-200717081 Rev. C 18/07/2014or later revisions of the above listed documents approved by EASA.- Declaration of Compliance Form DOC-201313150 REV NC- Compliance Verification Sheet CVS-201313150 Rev. N/C- MasterDocument List MDL-201313150 Rev. N/C- Master Document List M...	Valid only for D-HEDC S/N 4197Prior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	31/07/2014	Active	10017221
10017222 (EASA.R.S.01386)	CALEDONIAN AIRBORNE SYSTEMS LTD	REV. 2	CAA UK RESPONSIBILITY	AGUSTA-BELL 212 & 412	Installation of CAS CPT 900 ELT.	FAR 29	- Drawing List F005/214/001 Revision A dated 31 May 2007- Installation Manual 214-AB41-IM (25-60-00)- Flight Manual Supplement F014/214/001 Revision A dated 29 June 2007 orlater approved revisions- Maintenance Manual Supplement 214-AB41-ICA Revision 2 dated 28February 2008	None	21/04/2010	Active	10017222
10017223 (EASA.R.S.01388)	CALEDONIAN AIRBORNE SYSTEMS LTD	REV. 2	CAA UK RESPONSIBILITY	BELL 212, BELL 412	Installation of CAS CPT 900 ELT	FAR 29	- Drawing List F005/214/002 Revision A dated 05 June 2007- Installation Manual 214-AB41-IM (25-60-00)- Flight Manual Supplement F014/214/002 Revision A dated 02 August 2007or later approved revisions- Maintenance Manual Supplement 214-AB41-ICA Revision 2 dated 28February 2008	None	21/04/2010	Active	10017223
10017224 (EASA.R.S.01389)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		2. 412, 412EP 1. AB412	CMA 135 "Radio Altimeter Audio Warning Indicator".Rev. 1: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Technical Document CMA 135 Issue 1.Installation instructions for continued airworthiness in accordance withEngineering Bulletin CMA 135-BI Issue 1Drawing CMA135-02-00-00.Operation in accordance with RFM Supplement CMA135-RFMS Issue 1.or later revisions of the above listed document(s) approved/ accept...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/02/2019	Active	10017224

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017226 (EASA.R.S.01395)	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBILITY	BO 105 S (CBS-4)	The Pyrotechnic Display System:Carriage and deployment of static flares and roman candle typepyrotechnics, installed each side on external dispenser mounts attachedto landing gearskids and interfaced with cabin control box to sequenceignition.Note: this Rev. 1 is made for STC transfer purpose, tran...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Flight Manual Supplement GSSL-FMS-BO105-190, issue 1 dated 1 March2008or later revisions of the above listed documents approved by EASA2. Modification GSSL-MAJ-BO105-190, issue1 dated 12 March 20083. Continued Airworthiness Instructions GSSL-CAW-BO105-190, issue 1dated 20 February 2008	none	24/02/2011	Active	10017226
10017228 (EASA.R.S.01399)	NSE	REV. 5		AS 355 N, AS 355 NP AS 355 F1, AS 355 F2	Installation of BRITE SAVER 2 Data Monitoring SystemRevision 1 – Covered a documentary change to STCRevision 2 – Covered torque and memory management minor change.Revision 3 – Covered installation of ultrasonic air/ ground switch,second possible location on the BRITE SAVER 2 on the instrument panelan...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: FAR 27FAR 27.29 Amdt 27-14,,,,,,,,FAR 27.301 Original issueFAR 27.303 Original issue,,,,,,FAR 27.305 Original issueFAR 27....	- Note explicative relative au (Description note) STC MinorChange ref. 00028476AA Rev. 02dated 26 June2019- BRITE SAVER2 RECORDER Definition file Ref. : DD-0027-92 Rev. 18 dated04 January 2018- COMPONENT MAINTENANCE MANULA WITH ILLUSTRATED PARTS LIST ref. CMM31-30-01 Rev. 02dated 14 March 2018- BRI...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/10/2019	Active	10017228
10017230 (EASA.R.S.01401)	NSE	REV. 7		AS 350 BB, AS 350 D AS 350 B, AS 350 B1, AS 350 B2 AS 350 B, AS 350 B1 AS 350 BA, AS 350 BB, AS 350 D AS 350 B2, AS 350 BA	Installation of BRITE SAVER 2 Usage Monitoring SystemRevision 1 – Included torque and memory management minor change.Revision 2 – included addition of the possibility to install theultrasonic air/ ground switch and second source for SUBD connectors andhood.Revision 3 – Included embedded software evol...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Note explicative relative aux (Description Note) STC Minor Change Ref00028476AA Rev 02 dated 26 June2019.- BRITE SAVER 2 RECORDER DEFINITION FILE Ref DD-0027-92-EN Rev 18 dated04 January 2018- Component Maintenance Manual with Illustrated Part List RefCMM31-30-01 Rev 02 dated 14 March 2018- BRITEp...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/08/2022	Active	10017230
10017231 (EASA.R.S.01403)	AEROLITE AG	REV. 3		AB139, AW139	Installation P/N 139084-501 for 3 stretcher units with relevant cabinfloor rails and featuring each, dedicated oxygen and electricaldistribution systems and oxygen bottles stowageprovisions.Rev. 1 is made to rectify associated technical documentation references.Rev. 2 is made to change the STC hold...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MDL-07-007 Rev. G- Instructions for Continued Airworthiness and Operations ManualOPM-07-010 rev.C- Service Bulletin SB-21-017 Rev.Cor later revisions of theabove listed document (s) approved/ acceptedunder the EASA system.	1. Leonardo EMS (Medevac) electrical provisions 3G2564A01411 must beinstalled with modifications according 3G2564W00201.2. When oxygen is installed, 'No smoking' is permitted.3. Required minimum crew is defined in FMS-07-008.4. The dimensional limitations for medical rails are defined inOPM-07-010.P...	08/11/2022	Active	10017231
10017232 (EASA.R.S.01406)	AEROLITE AG	REV. 1		EC635 P2+, EC635 T1, EC635 T2+ EC135 T2+, EC135 P2+, EC135 T2 EC135 P2, EC135 T1, EC135 P1	EMS Stretcher Installation P/N 135591-501.Introduction of the Cirrus Stretcher Model CI-1 01 0-123-01 into thealready certified Cirrus 1010 Stretcher Installation P/ N135574-501/-502/-503/-504 (STC EASA.R.S.01406)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Flight manual supplement FMS-07-007 Revision A or later revisions of theabove listed document approved by EASAInstructions for Continued Airworthiness OPM-07-009 Revision AMaster Document List (for configuration) MDL-07-006 Revision A	To ensure patient head protection from injuries during crash, there mustbe at least 200mm of space between the forward end of each installedstretchers and any equipment installed forward of the stretchers.	20/04/2010	Active	10017232

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017236 (EASA.R.S.01415)	RUAG AG	REV. 1		SA 365 N EUROCOPTER FRANCE SA 365N	Enhanced navigation systemRemoved Equipment:- Pilot & Copilot HSI 651-Trimble 2101 GPS with MD41 Annunciator Control Unit and MD40 CDI-KTR 908 VHF COM System with KSF 598 Control Unit- KEA 346 Encoding Altimeter- Badin Crouzet Encoding Altimeter- KAS 297A Altitude Selector-Narco ELT 10 System- CD...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Documents List, Doc. No. 308-05001 Rev. 2- RFMS, Doc. No. 308-05500 Rev. 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	T-771 S/N: 6146Valid for this S/N.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	18/01/2021	Active	10017236
10017240 (EASA.R.S.01428)	BUCHER LEICHTBAU AG	REV. 3		EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of medical and rescue equipmentInitial approval of this installation was granted by FOCA STC Z-25-2062to EC135 P1/T1 and EC135 P2/T2.STC EASA.R.S.01428 (former: FOCA STC Z-25-2062) was issued to extend thecertification to EC135 P2+/ T2+.Rev. 1:,,STC 10017240 (former: EASA.R.S.01428) wasc...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMA-2 for Bucher Police EquipmentEC135-AC62-POL, Revision H, dated 13 April 2017<(>,<)>or later revisions of the above listed documents approved by EASA.-Master Document List (MDoc) E034-06-07 Revision D.- Operation and Maintenance Manual E014-19-01, Rev 04.- Operation and...	- Limited to Variants (CDS) and (CPDS).- The quick release hook P/N 1351070 and Rope Down Device P/N 1351080are not approved as external load attaching means and are not approvedfor Non-Human or Human External Cargo application.Prior to installation of this design change it must be determined thatth...	06/06/2017	Active	10017240
10017241 (EASA.R.S.01429)	AEROLITE AG	REV. 4		AB139, AW139	EMS Kit Light Lateral Stretcher P/N 139127-501This STC revision is issued for the purpose of transferring the STC toAerolite AG.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement: FMS-07-011 Rev. C dated 20 March 2013or later revisions of the above listed documents approved by EASAMaster Document List MDL-07-011 Rev C.Instruction for Continuous Airworthiness and Operation Manual:OPM-07-013 Rev. C dated 20 March 2013	The installation of this modification by third persons is subject towritten permission of the approval holder.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introd...	15/03/2016	Active	10017241
10017243 (EASA.R.S.01440)	NSE INDUSTRIES S.A.	REV. 1		SA 365 N, SA 365 N1. AS 365 N2, AS 365 N3,	Installation of Brite Saver 2 Usage Monitoring SystemRev. 0: Revision of EASA.R.S.01440. Covers software upgrade andapplicability modificationRev. 1: Incorporates the definition file of the installation kit anddifferent documentary changes	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: FAR Part 29, amdts. 29-0 through 29-55: Sec. 29.29, 29.301, 29.303, 29.305, 29.561, 29.607,29.609, 29.611, 29.855, 29.1301,...	NSE Industries AS365 Flight Manual Supplement doc. ref. RFMS-ARA-365Rev. 02 dtd.10 May 2013 or later revisions of the above listed documentsapproved by EASA.Conformity Statement and Documentary Architecture AS365, doc. ref.CONFAD-0079-92 Rev. 06 dtd. 30/04/2013.	None	13/05/2013	Active	10017243
10017248 (EASA.R.S.01446)	NSE	REV. 6		AS 350 B3, EC 130 B4	Installation of BRITE SAVER 2 Data Monitoring System (DMS).Rev. 1 was issued in order to extend the certificate to include themodel EC130 B4.Rev. 2 was issued in order to include Software Evolution and upgrade ofCPU and analog card.Rev. 3 was issued to extend eligibility to AS350 B3 with OP-4305 (Ar...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement RFMS-ARA0-AS350B3/ EC130B4-EN, Rev 02Instruction for Continued Airworthiness ICA-REC-ARA0-B3/B4, Rev 00.Brite Saver 2 AS350B3 Mounting Instruction IM-KIT-ARA0-350B3-EN, Rev 08.Brite Saver 2 EC130B4 Mounting Instruction IM-KIT-ARA0-EC130B4-EN, Rev02.Brite Saver 2 Operating Man...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/08/2022	Active	10017248

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017251 (EASA.R.S.01452)	AEROTEC & CONCEPT	REV. 1		SA 365 N	AEROTEC modification IRB (installation radio de bord) n° 0928.(Note for internal record: This application is to amend an existing EASASTC (Ref P-EASA.R.S. 01452) to add the S/N 6147)	FAR 29 amendment 16The Certification Basis for the originalproduct stated in TCDS N. 159remains applicable to this certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Installation-Aerotec Master Data List AE 0809 MDL Rev. 4 dated 23/03/09-Aerotec Master Data List AE 0928 MDL Rev. 0 dated 23/02/10Operation-Aerotec Flight Manual Supplement AE 0809 AFMS Rev. 1, dated 23/03/09 orlater approved revision.-Aerotec Flight Manual Supplement AE 0928 AFMS Rev. 0, dated 02/1...	This STC is limited to SA 365N S/N 6080 <(>&<)> S/N 6147 and can beinstalled only by AEROTEC technical staff in accordance with:-AEROTEC STC file Mod n° 0809. for S/N 6080-AEROTECSTC file Mod n ° 0928. for S/N 6147	01/03/2010	Active	10017251
10017252 (EASA.R.S.01454)	AEROLITE AG	REV. 2		EC135 T2, EC135 T2+ EC135 T1, EC135 T1 (CPDS) EC135 P2, EC135 P2+ EC135 P1, EC135 P1 (CPDS)	Change to Installation of EMS Equipment Aerolite P/N 135602-502Change comprises of:- Introduction of Support Panel AssyP/N 004191-501 into DC Power SystemInst. P/N 135615-501-Introduction of EMS Integralfloor Inst. P/N 135301-503- Introduction of Reversible Copilot Seat Inst. P/N 135331-501/-503--...	JAR 27The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificatednoise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS-08-001 Revision B, dated May 6th, 2011or later revisions of the above listed documents sections approved byEASAMaster Document List MDL-08-004Equipment List EQL-08-004Operations Manual OPM-08-001 Revision B, dated May 6th, 2011	This STC is limited to S/N 337 and above.	15/10/2012	Active	10017252
10017255 (EASA.R.S.01461)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	Interiors Configuration Vip 131 P/N 6AB1AD009-001.This STC supersedes EASA STC EASA.R.S.01461.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- RFM Supplement No. 6AB1RFM-1-7 Rev. A dated 16 May 2008 or later approved revision.-Owner's Manual No. 6AB1WNM-2-14 Rev. A dated 16 May 2008.	Agusta provision P/N 4G2520F03311 must be installed.	09/06/2010	Active	10017255
10017258 (EASA.R.S.01465)	AERODATA AG	REV. 1		EC155 B1	Installation of Aerodata Airborne Observation Equipment in EC155 B1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement "Integration of AOP in Maritime EC155, A/CType: EC155 B1, Aerodata Modification Ident: EC155-04"or later revisions of the above listed documents approved by EASA.Certification Plan „CP-EC155-04.01", Revision 1, 12/06/2015	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/02/2016	Active	10017258
10017259 (EASA.R.S.01466)	ZODIAC AEROSAFETY SYSTEMS	REV. 11		S-92A	Installation of Provision Kit p/n 509429-02 or p/n 509429-03 of InternalAuxiliary Fuel System (IAFS).STC revisions 1 and 2 introduce minor design modifications for kit p/n509429-02 and revised documentation.STC revision 3 introduces kit p/n 509429-03 and revised documentation.STC revision 4 clarifie...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aerazur Organigramme Technique ref. 509429-03 issue 13 dated 05 July2013; Aerazur Organigramme Technique ref. 509429-02issue 12 dated 26May 2010.IAFS - High Profile (HP) version - Maintenance Manual Supplement forprovision kit - chapter 11, 21,25,28,31 and 71, issue 8 dated 14 Feb2014IAFS- Provis...	Refer to applicable installation instructions for compatibility of theIAFS provision kit with S-92A cabin interior panels as stated in STC10017259 revisions 1 to 9The installationof this modification by third persons is subject towritten permission of the approval holder.The approval holder shall f...	08/10/2014	Active	10017259
10017261 (EASA.R.S.01470)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	AB/AW139 Seat Armrests Installation P/N 6AB1AD011-001.This STC supersedes EASA STC EASA.R.S.01470.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Owner's Manual for Armrests Installation P/N 6AB1AD011-001	This STC can only be installed on the AB/AW139 12-seat configuration P/ N3G2520F00111 that embodies seats P/N 3G2520V00131.	09/06/2010	Active	10017261

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017265 (EASA.R.S.01479)	AEROLITE AG	REV. 4		AB139, AW139	AW 139 EMS Kit P/N 139097-501Revision 1 relates changes:- Stretcher Inst. P/N 139190-501/-503/-505/-507/-511/-513/-515/-517/-601/-603/-605/-607/-611/-613/-615/-617-Cargo Platform Inst. P/N 139191-501-Toughbook Retainer Inst. P/N 139192-501-Toughbook Retainer Inst. P/N 139225-501/-502-GPS/GSM-Antenna-...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Initial technical documentation:FMS-08-005 Revision NCOPM-08-005 Revision NC, dated May 19, 2008Revision 1 related technical documentation:FMS-08-005 Revision B, dated Oct 15, 2010OPM-08-005 Revision B, dated Oct 1, 2010Revision 2 related technical documentation:FMS-08-005 Revision C, dated May 25,O...	-As prerequisite for installation of Aerolite AW 139 EMS Kit P/N139097-501, the Aerolite EMS Provisions Kit P/N 139125-501 must bepreviously installed. Prior to installation of this modification it mustbe determined that the interrelationship between this modification andany other previously install...	20/12/2019	Active	10017265
10017267 (EASA.R.S.01486)	MECAER AVIATION GROUP S.p.A.	REV. 4		AB139/ AW139	VIP 37 Plus Interior Configuration P/N 6AB1AD012	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ oremissions levels of the original product are unchanged and remainapplicable to thiscertificate/ approval	- Supplement to RFM doc. No. 6AB 1 RFM-1-8 Revision ACor later revisions of the above listed documents approved by EASA.- Owner's Manual doc. No. 6AB1WNM-2-16 Re-issue 1 Revision X-Change Description doc. No. 6AB1 RAD-216 Revision E- Notice of Design Change (NDC) doc. No. 6AB1AD-204 issue A	Prior to installation of this modification it must be determined thattheinterrelationship between this modification andany other previouslyinstalledmodification and/or repair will introduce no adverse effect upon theairworthinessof the product.	08/09/2014	Active	10017267
10017272 (EASA.R.S.01494)	NSE INDUSTRIES S.A.	REV. 2		2- R44, R44 II 1- R22, R22 ALPHA, R22 BETA 1- R22 MARINER	Replacement of ECT logo by NSE logoModification of Maintenance Manual Supplement reference from"MM1-0023-08BE58-EN" to "MMS-PE-R22-R44-EN"Modification of Data Monitoring System (DMS) by Usage Monitoring System(UMS)Update of documentation due to new fittings and electronic componentsAddition of an RF...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFMS-PE-R22-R44 Rev 01 dated 24/11/2014 or later revisions of the abovelisted documents approved by EASA.CONFAD-0014-08B E58-EN Rev 05 dated 24/11/2014	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/12/2014	Active	10017272
10017273 (EASA.R.S.01503)	ECMS AVIATION SYSTEMS GMBH	REV. 1		EC635 T1, EC635 T2+, EC635 T3 EC635 P2+, EC635 P3 EC135 T1, EC135 T2, EC135 T2+ EC135 P3, EC135 T3 EC135 P1, EC135 P2, EC135 P2+	Installation of HEC Rope System HRS01Rev. 1:Extension of applicability to EC135 P3, EC135 T3, EC635 P3, EC635 T3.Addition and removal of components and introduction of a new high loadvariant. Associated change to RFMS and CMM.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 Amendment 2 for27.625(a), (d)The requirements for environmental protection and the associatedcertified noise and/ or...	- Compliance Program, Doc. Ref. HRS01_MOC_EC135_EASA Revision 5- Flight Manual Supplement for HEC Rope System HRS01 on EC135/ EC635,Doc. Ref. HRS01_RFMS_EC135_EASA Revision 1- Airworthiness Limitations - Lifetime of PCDS components, Doc. Ref.PCDS_Lifetime_Limitations_EASA Revision 2- Equipment List f...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/08/2019	Active	10017273
10017278 (EASA.R.S.01524)	AEROLITE AG	REV. 3		AB139, AW139	EMS Equipment 139172-501/-502Revision 1 to incorporate PAX seat configurations Aerolite P/N139117-505, 139117-506 and 139117-507 of 12, 14 and 15 PAX seats (as perSTC EASA.R.S.01524 Revision 1) Revision 2 to introduce Ceiling Unit Assy configuration P/N 006224-506,equipped with NVG friendly cabin lig...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement FMS-08-008 Cor later revisions of the above document approved by EASA- Operations Manual OPM-08-010 D- Master Document List MDL-08-015 D	EMS Fixed Provisions Kit P/N 139125-502 (STC EASA.R.S.01474and AeroliteSADD-12-027) must be installed as a prerequisite for configurations asdefined in applicable design data.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and a...	30/07/2015	Active	10017278

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017279 (EASA.R.S.01525)	SABENA TECHNICS BOD	REV. 1		AS 365N AS 365 N	GPS Stand alone BRNAV FREEFLIGHT TNL 2001. Approach plus I/OInstallation	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	-Dossier de Modification M003-34-08-365N Revision 2.-Heli-Union Supplement Manuel de Vol BRNAV SA 365N, 365HU-PMV-34-07 (08-44).Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/03/2025	Active	10017279
10017280 (EASA.R.S.01528)	AEROLITE AG	REV. 5		MBB-BK 117 C-2	Stylence Package (VIP Kit) Aerolite P/N 145305-501/-502 (Revision toEASA.R.S. 01528)Passenger Seat Modification P/N 021376-502, Curtain Inst. P/N 145319-502and Finishing P/N 145302-506/-507.This STC revision is issued for the purpose of transferring the STC toAerolite AG.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approvalThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual FMS-08-009 Revision Bor later revisions of the above listed documents approved by EASA.Operation Manual OPM-08-011 Revision CMaster Document List MDL-08-017 Revision E	When the Cargo Separation Wall is installed the original MBB-BK117 C-2smoke detector kit must be installed in the cargocompartment.When operating the rotorcraft with the doors open or removed, thelimitations given in Flight Manual Supplement No. FMS 9.1-2 must befollowed.For Single Pilot operationT...	15/03/2016	Active	10017280
10017282 (EASA.R.S.01530)	ECMS AVIATION SYSTEMS GMBH	REV. 2		MBB-BK 117 D-2M MBB-BK 117 D-2 MBB-BK 117 C-2E MBB-BK 117 C-2 MBB-BK 117 C-1 MBB-BK 117 B-2 MBB-BK 117 B-1 MBB-BK 117 A-4 MBB-BK 117 A-3 MBB-BK 117 A-1	Installation of HEC Rope System HRS01Rev. 1: Extension of applicability to BK117 C-2e, BK117 D-2 and BK117D-2mRev. 2: Addition and removal of components, introduction of a new highload variant. Associated change to RFMS and CMM.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS29 amendment 3:29.25, 29.27, 29.65, 29.141, 29.251, 29.301,29.303, 29.305, 29.307,29.309, 29.337, 29.341, 29.571, 29.60...	-Flight Manual Supplement, Doc No. HRS01_FMS_BK117_EASA_R3 Stand20181009, Revision 3<(>,<)> dated 01.06.2018- Lifetime Limitations for Personnel Carrying Devices and associatedequipment, Doc. No. PCDS_Lifetime_Limitations_EASA_R1, Revision1< (>,<)>dated 03.07.2018- HRS01 Equipment List, Doc. No. HRS0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/10/2018	Active	10017282
10017284 (EASA.R.S.01532)	AIRBUS HELICOPTERS UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	EC 135 T2+, EC 135 P2+	Installation of Spectrolab Nightsun XP Skid Mounted System.Equipmentinspection and re-certification to close the requirement for AD No.2010-0183R1.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Maintenance Requirements Document MR/ 135/1151-001, Issue B,dated03/11/2010Design Report DR/1351151-001, Issue B, dated11.11.2010	None	15/11/2010	Active	10017284
10017286	AEROLITE AG	REV. 5		MBB-BK 117 C-2	Installation of EMS equipment P/N 145030-501 consists of a stretcherplatform, medical seats, medical cabinets and a medical supply unit.Revision 1 of the STC supersedes original issue of EASA.R.S. 01535.Revision 2 relates to Major Change APC-13-014 that introduces newequipment part numbers to EMS Equ...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Flight Manual SupplementFMS-216, rev. J (minor revision approved under DO privileges) Operations Manual (incl. ICA)OPM-216 rev. N (minor revision approved under DO privileges),,or later revisions of the above listed documents approved by EASA.Master Document List MDL-216 Rev. PCertification Plan CPR-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	22/02/2019	Active	10017286
10017290 (EASA.R.S.01545)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	AW139 VIP 221 Interiors, P/N 6AB1AD013-001.This STC supersedes EASA STC EASA.R.S.01545.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	NDC 6AB1AD-032 Iss. AOwner's manual 6AB1WNM-2-18 Rev. ARFM Supplement 6AB1RFM-1-10 Rev. A	The VIP 221 interiors can only be installed on AB/AW 139 helicoptersequipped with Agusta provision P/N 4G2520F00411.	09/06/2010	Active	10017290

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10017291 (EASA.R.S.01548)	AIR AMBULANCE TECHNOLOGY GmbH	REV. 1		AB139, AW139	Installation of Air Ambulance Equipment, Mission Equipment "Quick -Conversion", P/N AW139-25-20-37.000-60x model	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 Amdt 2CS 29.1, CS 29.21, CS 29.25, CS 29.29,CS 29.301, CS 29.303, CS 29.305,CS 29.307, CS 29.321, CS 29.471, CS 29.562, CS 29.571, CS 29.601, CS29.603, CS 29.605, C...	Master Data List AB/AW 139 Air Ambulance Equipment Doc. No."MDL-AW139-37_000-60X", Rev. 0Rotorcraft Flight Manual Supplement AB/AW 139 Air Ambulance Equipment"Quick Conversion", Doc. No. "FMS AAT 52", Rev. 1Component-, Installation-, Operation-Manual and Illustrated Part CatalogAB/ AW 139 Air Ambulan...	Limitations as prescribed in see Rotorcraft Flight Manual SupplementAB/AW 139 Air Ambulance Equipment "Quick Conversion", Doc. No. "FMS AAT52", Rev. 1 and Component-, Installation-, Operation-Manual andIllustrated Part Catalog AB/ AW 139 Air Ambulance Equipment, Doc. No."CMM-AW139-AAT 71", Rev. 2 ord...	10/12/2013	Active	10017291
10017292 (EASA.R.S.01554)	AEROLITE AG	REV. 2	FOCA STC 25-20-65	EC135 T3(CPDS) EC135 T2(CPDS), EC135 T2+, EC135 T1(CDS), T1 (CPDS), EC135 P3(CPDS), EC135 P2(CPDS), P2+, EC135 P1(CDS), P1 (CPDS),	Initial Issue:Clamshell Door Lock installation P/N 135065-501/-502.Note: This STC is based on the FOCA STC Z 25-20-65. Its applicability isextended to P2+ and T2+ models.Revision 1 to STC:Extension of the applicability of the Clamshell Door Lock InstallationP/N 135065-501/-502 to the T3 and P3 varia...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Initial Issue:Installation Manual Doc No. IM-901MaintenanceManual Doc. No. 52-31-01Revision 1 to STC:CPR-15-036 Revision AMaster Document List MDL-807 Revision DEquipment List EQL-15-013 Revision NCMaster Drawing List DWL-807 Revision FInstallation Manual IM-901 Revision FMaintenance Manual CMM-52-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/02/2019	Active	10017292
10026757 (EASA.IM.A.S.03086)	AEROMECH Inc.		FAA STC SA01602SE	CESSNA 441 SERIES	Group Approval for Reduced Vertical Separation Minimum (RVSM)	FAR Part 23	Airplane Flight Manual Supplement as per AEROMECH document·,,AM0114-FM01 - for Class 1 airframes dated 08 June 2009, orlater EASAapproved revision;·,,AM0114-FM02 - for Class 2 airframes, dated 08 June 2009, or laterEASA approved revision.Instructions for continued airworthiness as per AEROMECH docu...	This approval is issued based on the FAA STC SA01602SE, issued on 26October 2005 and later amended on 17 November 2006.	06/08/2009	Active	10026757
10026761 (EASA.A.S.03837)	DSA A.S.	REV. 1		172RG	Avionics Upgrade - GNS430W, KX165A, GMA340, GI106A, KN62A, GTX330,KANNAD406AF Compact Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Flight manual supplement:S21 LDA03/09/ C172RGGNS 430 W VHF COMM Transceiver, VOR/ ILS and GPS ReceiverS22 LDA 03/09/C172RGKX 165A VHF COMM TRANSCEIVER/ NAV RECEIVERS23 LDA 03/09/ C172RGGI 106A NAV indicatorS24 LDA 03/09/ C172RGGMA 340 AUDIO PANELS25 LDA 03/09/ C172RGGTX 330 S-MODE TRANSPONDERS26 LDA 03/0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/05/2020	Active	10026761
10026764 (EASA.IM.A.S.03249)	AVIONICS SUPPORT GROUP, Inc.		FAA ST03700AT	747-400, 747-400F	Installation of an International communications Group ICS-220A IridiumSATCOM System in a B747-400/-400F series aircraftin accordance withAvionics Support Group, Inc. Master Data List 28546-MDL, Revision A,dated March 16, 2009, or later FAA approved revision.Validation of FAA STC03700AT	Per FAA TCDS A20WE	-28546-AFMS Rev. IR dated May 14, 2009 Airplane Flight ManualSupplement.-ASG Inc Aircraft Maintenance Manual Supplement23-15-00-DER Services, Inc. Report SR-A-2008-083-2 Rev. IR Damage ToleranceAnalyses for Iridium Antenna Installation.	After Installation of this STC the operator is required to incorporatein the Airworthiness Limitations Section of the Instructions forContinued Airworthiness applicable to the existing Maintenance Program adetailed inspection item at a threshold of 8400 Flight Cycles followingmodification and repeat...	10/08/2009	Active	10026764

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10026769 (EASA.IM.A.S.03137)	B/E AEROSPACE LIMITED	REV. 1	TCCA LSTC C-LSA09-026, ISS. 1	CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	TCCA LSTC No. C-LSA09-026 Issue 1 dated 04 August 2009.AeroConsulting Services Ltd. Modification Data Summary G103000 RevisionG.Midcoast Aviation Inc./ Aero Consulting Services Ltd Airplane FlightManual Supplement for the Complete Custom Aircraft InteriorInstallation, 33-299M009 Rev A.Aero Consul...	Restricted to ASN 8079.	16/08/2013	Active	10026769
10026784 (EASA.A.S.03917)	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		PA-46-500TP, PA-46R-350T PA-46-310P, PA-46-350P	Installation of Single or Dual Garmin G500 / G600 Avionics System(including SVS) and Dual Garmin GNS4/530(A)W GPS/COMM/NAV.	The Certification Basis of the original product and the followingadditional / alternative airworthiness requirements are applicable tothis change- For those areas affected by the change compliance showing against CS23has been elected.- EASA Guidance Material GA/G/ 001, Rev. 2 has been followedThe cer...	-EASA approved Master Document List, Doc. No. ASR-2009-075-MDL-01-00,Amdt. Level 00, dated 20-Jan-2010, or later approved amdt. level-EASA approved Instructions for Installation, Doc. No.ASR-2009-075-IFI-10-00, Amdt. Level 00, dated 18-Jun-2009, or laterapproved amdt. level-EASA approved Flight Manu...	This STC is limited to the configuration of aircraft, equipment type,and functions as listed in EASA approved Instructions for Installation,Doc. No. ASR-2009-075-IFI-10-00, Amdt. Level 00, dated 18-Jun-2009,especially as mentioned in Item 2. of this document, or later approvedamdt. levelFor applicab...	23/04/2010	Active	10026784
10026785 (EASA.A.S.03902)	MT-PROPELLER ENTWICKLUNG GmbH			95-C55, D55, E55, 58, G58	Installation of 4-blade MTV-14-D-C-F-/CF 188-30g propellerson HawkerBeechcraft Model 95-C55, D55, E55, 58, G58.	FAR 23 including amendment 34	Airplane Flight Manual Supplement E-1789, Issue 09-07-2009 or laterapproved revision.Instructions for Continued Airworthiness E-1791, Issue 10-07-2009 orlater approved revision.Installation Instructions E-1790, Issue 09-07-2009.	None.	10/08/2009	Active	10026785
10026805 (EASA.A.S.03944)	DANSK FLY ELEKTRONIK ApS			BEECH 1900D	Installation of Skytrac ISAT-100 GPS/ Iridium communicator system	As defined in the FAA TCDS A24CE	-Design Order Package DFE-DO-0361-DOP-00, dated 15-06-09-Declaration of Compliance, dated 11-07-09	None	11/08/2009	Active	10026805
10026811 (EASA.A.S.03841)	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	BOEING 767-300	Installation of Lifeport Stretcher.	As per TCDS.	Modification Summary Sheet, MOD H4A1197, Issue 2, 06/08/2009Instructions for Continued Airworthiness, H4ADR446, Issue 1, 05/06/2009.	None.	12/08/2009	Active	10026811
10026831 (EASA.A.S.3878)	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	PA-24, PA-24-250, PA-24-260, PA-24-400	Approval of an Aspen EFD1000 Primary Flight Display (PFD)	CS 23	-Master Document List: MDL.00809-Aiplane Flight Manual Supplement FMS. 00809 Rev A or later EASA approvedversion-Instructions for Continued Airworthiness ICA.00809	STC approved for Piper PA24 series	13/08/2009	Active	10026831
10026840	ACS-NAI Ltd.	REV. 1	TCCA LSTC C-LSA09-028/ D, ISS.1	BOMBARDIER CL-600-2B19	Installation, Complete Custom Aircraft Interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-028/D Issue 1 dated 04 August 2009.Aero Consulting Services Ltd. Modification Data Summary G100000 RevisionE.Midcoast Aviation Inc/Aero Consulting Services Ltd Airplane FlightManual Supplement for the Complete Custom Aircraft InteriorInstallation, 33-299M007 Rev NC.Aero Consult...	Restricted to ASN 8070.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/08/2013	Active	10026840

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10026846 (EASA.A.S.03879)	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	F182-P, F182-Q, FR-182	Approval of an Aspen EFD1000 Primary Flight Display (PFD)	CS 23	Master Document List: MDL.00609•Airplane Flight Manual Supplement FMS. 00609 Rev A or later EASA approvedversion.Instructions for Continued Airworthiness ICA.00609	STC approved for F182P, F182Q and FR182 series types only	17/08/2009	Active	10026846
10026853 (EASA.A.S.03708)	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	BOMBARDIER CL-600-2B19	Introduction of Wireless Local Area Network.	EASA.IM.023 plus CRI F-01.	- S21.25-89-1302.- MDL-0580 Issue 4.		20/08/2009	Active	10026853
10026859 (EASA.IM.A.S.03106)	GOODRICH CORPORATION		FAA STC ST00989SE-D	B767-300F	Installation of the CHS (Cargo Handling System) on the B767-300FMD: MDL7N10000FAA STC: ST00989SE-D	The Certification Basis has been determined and is defined in CRI A-01.The Certification Basis for the original productand the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The Certification Basis has been determined within CRI A-01. Due to...	FAA:"or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)"	The operation of the STC is only approved when installed ontheprovisions of the Boeing A/C B767-300F.	18/08/2009	Active	10026859
10026864 (EASA.A.S.03938)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		CESSNA 500, 550	GARMIN GPS 400W/500W installationRevision 1 supersedes the previous issue of this STC to delete the modelS550 from the applicability list for correction.	Certification Basis as per EASA TCDS IM.A.207 Issue 2 from 5 March 2009	Master Document List "2054628 DOC" issue 1 from 17 August 2009Aircraft Flight Manual Supplement "2054628-AM" issue 1 from 11 August2009Instructions for Continued Airworthiness "2054628-CA" issue 1 from 11August 2009or later revisions of the above listed documents approved by EASA	The limitations according to Aircraft Flight Manual Supplement2054628-AM are applicable.	18/08/2009	Active	10026864
10026867 (EASA.IM.A.S.03211)	DUNCAN AVIATION, INC.		FAA STC ST00703WI	CESSNA 650	Installation of an AlliedSignal Enhanced Ground Proximity Warning System (EGPWS)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	FAA STC ST00703WIDocument List 10051900 Revision K from 12 June 1998Airplane Flight Manual Supplement (AFMS) 40189700 Revision D from 16Sept. 1998Instructions for Continued Airworthiness (ICA) 44500400 from 12 June1998or later revisions ofthe above listed documents approved by EASA inaccordance wit...	According to associated technical documentation, FAA STC, AFMS and ICA	18/08/2009	Active	10026867
10026871 (EASA.IM.A.S.03213)	CHIPPEWA AEROSPACE, Inc.		FAA STC ST03280AT	HAWKER 900 XP HAWKER 850 XP HAWKER 800 XP HAWKER 800 HAWKER 750 BAE 125-800B BAE 125-800A BAE 125-800 BAE 125-700	Installation of a Honeywell Flitelink Engine Condition Trend Monitoring- Data Downloader (ECTM-DD)	FAR 25	Installation in accordance with Chippewa Aerospace Master Drawing List(MDL) No H800-7610-01-0001, Rev 11, dated February 26, 2009, or laterapproved revisions.Instructions for Continued airworthiness in accordance with ChippewaAerospace Instructions for Continued airworthiness (ICA) NoH800-7610-01-00...	None.	19/08/2009	Active	10026871
10026878 (EASA.IM.A.S.03243)	HAWKER BEECHCRAFT SERVICES		FAA STC SA01525WI	HAWKER BEECHCRAFT B200GT, B200 BEECH B300C, BEECH B200CT, B200T, B300, BEECH 300, 300LW, B200, B200C, BEECH 200, 200C, 200CT, 200T	Installation of AirLock Secure Entry Door Lock System in place oforiginal equipment locks for the main cabin door, noseavionics doors,and aft equipment door.	FAR 23	Installation in accordance with Hawker Beechcraft Services Master DateList Document NO 007-5200-L01-00 Revision 1, dated December 9, 2008, orlater approved revisions.	None	13/08/2009	Active	10026878

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10026882 (EASA.IM.A.S.03218)	CHIPPEWA AEROSPACE, Inc.	REV. 1	FAA STC ST03573AT	CL-600-2D15, CL-600-2D24. CL-600-2B19, CL-600-2C10,	Installation of Goodrich Class II EFB System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRIsH-01 - EWIS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain a...	- FAA STC No. ST03573AT dated 05 August 2010.- Chippewa Aerospace Master Data List (MDL) 601-4620-01-0001, Revision4, dated 26 February 2009.- Chippewa Aerospace Airplane Flight Manual Supplement No. 601-4620-0012B Revision IR.- Instructions for Continued Airworthiness (ICA), Chippewa AerospaceInc. D...	Restricted to Configuration 2 as defined in Chippewa AerospaceCertification Plan No 601-4620-CP Revision D, dated 24 March 2009.	14/01/2013	Active	10026882
10026883 (EASA.IM.R.S.01147)	CARSON HELICOPTERS, INC.		FAA STC SR02057NY	S-61N, S-61NM	Upgrade of the S6135-20600 main gearbox by replacing input freewheelingunits.	CAR 7, August 1, 1956, including Amendments 7-1 through 7-4	IFWU Installation Carson S61 No. CHI-R-001, no revision, dated 15 Dec2004 and Carson Installation Instructions Report CHI-R-INSTALL, norevision, dated 14 Dec 2004.	None.	19/08/2009	Active	10026883
10026892 (EASA.IM.A.S.03271)	ROSEN SUNVISOR SYSTEMS L.L.C.			FAN JET FALCON C, D, E, F, G	EASA Validation of FAA STC SA2652NMCockpit Sun Visor Installation i.a.w. Rosen Drawing List No. RF 20-00DL, Revision D dated 14th November 2008 or later revisions approved byEASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or subsequentrevisions to these decisions)	Original EASA Certification Basis for Fan Jet Falcon and Fan Jet FalconC, D, E, F and G as per French DGAC TCDS's Number 103 Issue 13 datedApril 1981 and TCDS's Number 103 bis Issue 6, dated October 1986.	See those of original FAA STC SA2652NM	None	19/08/2009	Active	10026892
10026895 (EASA.IM.R.S.01495)	DONALDSON COMPANY, Inc.	REV. 1	FAA STC SR02526CH	MD900	Installation of engine inlet barrier filter (IBF) systemRevision 1 reflects the name and address change from AerospaceFiltration Systems, Inc. to Donaldson Company, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List Inlet Barrier Filter system AFS-MD900-IBF-MDL Rev Ddated 15 July 2009.2. Aircraft Flight Manual Supplement AFS-MD900-IBF-FMS Rev A approved bythe FAA on 21 July 2009.3. Instructions for Continued Airworthiness AFS-MD900-IBF-ICA Rev IRdated 20 October 2006.or later revisions of th...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/01/2018	Active	10026895
10026896 (EASA.A.S.03967)	CESSNA ZURICH CITATION SERVICE CENTGMBH			HS 125 SERIES 700B	Cockpit Voice Recorder InstallationBy installing a new L3 FA2100 Cockpit Voice Recorder (CVR)	FAA CAR-4b, FAR 25 for the Change	- Master Document List, Doc. No. MDL-068, Rev. B or latestapprovedRevision - AFMS, Doc. No. FMS-041, Rev. IR or latest approved Revision - ICA, Doc. No. ICA-034, Rev. IR or latest approved Revision	None	20/08/2009	Active	10026896
10026904 (EASA.IM.A.S.03136)	ACS-NAI Ltd.	REV. 1	TCCA LSTC C-LSA09-032/ D	BOMBARDIER CL-600-2B19	Installation, Complete Custom Aircraft Interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-032/D Issue 1 dated 12 August 2009.Aero Consulting Services Ltd. Modification Data Summary G121000 RevisionD.Midcoast Aviation Inc Airplane Flight Manual Supplement for the CompleteCustom Aircraft Interior Installation, 33-299M007 Rev NC.Aero Consulting Services Ltd. MandatoryG...	Restricted to ASN 8089.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/08/2013	Active	10026904

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10026905 (EASA.A.S.03161)	JET AVIATION AG	REV. 1		737-700 IGW	Activation of Runway Awareness and Advisory System (RAAS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Jet Aviation Documents:- Master Data List: BB73734461-001 Rev. B dated 31 July 2009- AFM Supplement: BB73734461-201-01 Rev. IRor later revisions of the above listed documents approved by EASA.	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	25/04/2016	Active	10026905
10026907 (EASA.IM.R.S.01559)	AIR COMM CORPORATION LLC		FAA STC SR00230DE	BELL 407	Bell Helicopter Model 407 Cabin Ventilation System.	FAR 27	DL-407V revision L dated 16 April 2009 or later approved revision -Master Document list;407V-1 revision 2 dated 19 May 2000 or later approved revision - FlightManual Supplement;407V-300M revision 0 dated 11 April 2000 or later approved revision -Instructions for Continued Airworthiness.	None	21/08/2009	Active	10026907
10026912 (EASA.IM.A.S.03087)	ROSEMOUNT AEROSPACE, Inc.	REV. 1	FAA STC ST02743CH	B737-600, -700, -800, -900	Validation of major change to FAA STC concerning EFB 'Installation of8700A1-3 Electronic Flight Bag'The change to EFB STC adds the following features:- implementation of Display Module (DM) ON/OFF backlight- connections to WOW and Door Open discretes	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Master Document List D06403434 rev G- Airplane Flight Manual Supplement D06403451 rev Bor later revisions of the above listed documents approved by EASA	Not Applicable	01/07/2011	Active	10026912
10026913 (EASA.IM.A.S.03179)	TROLLTUNE CORPORATION		FAA STC SA03608AT	182P AND 182Q (SEE ATTACHMENT)	Increased Maximum Gross Takeoff Weight (MGTOW). This STC allows a 150 lbIncrease in MGTOW from 2950 to 3100 lbs. There is no change to themaximum landing weight of 2950 lbs.	CAR 3 as defined on FAA STC and CS-36.	In accordance with Trolltune Corporation Master Data List (MDL),Document Number ED5000-SW, Revision 6, dated August 20,2008 or laterapproved revisions.Operation in accordance with Trolltune Corporation Airplane FlightManual Supplements (AFMS), dated August 22, 2008 or later approvedrevisions for th...	None.	21/08/2009	Active	10026913
10026920 (EASA.R.S.01550)	RUAG AG	REV. 1		AS 332 C1	Pilot and Co-pilot Upper/Lower Cargo Hook Release modification.Rev 1: Transfer of STC to a new legal entity that is holder of a new DOA(EASA.21J.760)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List 156447-00, rev. 000, dated 26.06.2009Rotorcraft Flight Manual Supplement 156447-50, rev. 000, dated28.04.2009Instructions for Continued Airworthiness 156447-60, rev. 000, dated26.06.2009or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	18/01/2021	Active	10026920
10026923 (EASA.R.S.01571)	AEROLITE AG	REV. 6		EC635 T2+ EC135 T2(CPDS), EC135 T2+ EC135 T1(CPDS), EC635 T1(CPDS) EC135 P3(CPDS), EC635 P3(CPDS) EC135 P2+, EC635 P2+ EC135 P1(CPDS), EC135 P2(CPDS)	EC135 Emergency Medical Service (EMS) KitAEROLITE P/N 135652-502Note 1: STC EASA.R.S. 01571 Rev. 1 (EASA 10026923, Rev. 1):Introduction of EC135 EMS KIT: Aerolite P/N 135652-502 components listedMDL-09-008 Rev. N/C,Applicable to EC 135 models except EC 135 P3/ T3Note 2: STC Revision 2 (EASA 10026923 R...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS-09-004, Revision F: EMS KIT LPR P/ N135652-502or later revisions of the above listed documents approved by EASA- Master Drawing List MDL-09-008, Revision H.1, dated 15th June 2016.- OPM-09-008 Rev. G, dated 6th June 2016.- Declaration of Compliance Form 067 V1.6, Dated 16...	S/N: 337 and onwards only,,,,Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.,,	20/06/2016	Active	10026923

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10026925 (EASA.IM.R.S.01142)	CARSON HELICOPTERS, INC.		FAA STC SR00331NY	S-61N	Installation of improved parts for rotor transmission support inaccordance with Carson Services Inc. Drawing Number 22000, Revision B,dated July 22,1994.	FAA Part 29	None.	Repetitive Inspections required in accordance with SikorskyServiceBulletin 61B20-3F, Revision No. 6, dated December 1,1978 or laterapproved revision.	25/08/2009	Active	10026925
10026941 (EASA.A.S.03675)	AVIONIK STRAUBING ENTWICKLUNGS GmbH			60, A60, B60	Installation of Garmin GNS430W / GNS430AW / GNS430 / GNS530W / GNS530AW/ GNS530, with Installation of Garmin GA35/GA56 GPS Antenna.	CS-23	Installation must be in accordance with Master Document List EngineeringOrder No. ASR 2006-088-MDL-01-00 Amendment 00 dated 08-01-2009 or laterApproved Revisions.Operation must bein accordance with Flight Manual Supplement No. ASR2007-088-FMS-05.1-00 Amendment 00 dated 20-10-2008 or ASR 2007-088-FM...	None	25/08/2009	Active	10026941
10026943 (EASA.IM.A.S.03257)	PATS AIRCRAFT L.L.C.	REV. 3	FAA ST01713NY	737-800	1. Installation of Auxiliary Fuel Systems in Boeing 737-800(BBJ2)aircraft, 25.981 amendment 25-125 Compliant. All configurations listedbelow are approved with or without Boeing Nitrogen Generations System(NGS) installed.2. Configuration 1: Installation of a Four-Cell Auxiliary Fuel System(One Forwa...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplements1. PATS Aircraft, LLC Airplane Flight Manual Supplement No. 132 for aFour-Cell (1 Fwd/3 Aft) Auxiliary Fuel System, FAA approved revision IRdatedFebruary 6, 2006, or later FAA approved revision, is required withConfiguration 1.2. PATS Aircraft, LLC Airplane FlightF...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The installation of the auxiliary fuel tan...	06/07/2021	Active	10026943
10026953 (EASA.IM.A.S.03229)	PRATT & WHITNEY		FAA STC ST00261BO	FALCON 2000EX	EASA Validation of FAA STC ST00261BO:Installation of Pratt <(>&<)> Whitney EngineServices, Inc DataTransmission Unit (DTU) in accordance with Pratt <(>&<)> Whitney EngineServices, Inc, Master Document List DTU-T-100-6, Revision F dated 23rdJuly 2009, or later revisions approved by EASA in accordanc...	On an elect to comply with basis, compliance has been shownwith EASACS25 up to amendment 6 level, as per Pratt <(>&<) >Whitney EngineServices, Inc "EASA STC Compliance Report DTU-T-139-2 Revision B dated16th July 2009"The certificated noise and/ or emissions levels of the original productare unchan...	-Pratt <(>&<)> Whitney Engine Services, Inc Installation InstructionsDTU-G-010-7, Revision C dated 26th May 2009-Pratt<(>&<)> Whitney Engine Services, Inc Instructions for ContinuedAirworthiness (ICA) DTU-G-260-7, Revision C dated 26th May 2009or later revisions of the above listed documents appro...	Instructions for Continued Airworthiness (ICA) DTU-G-260-7,Revision Cdated 26th May 2009 or later revisions shall be made available to theoperator at the time of installation	26/08/2009	Active	10026953
10027008 (EASA.A.S.02941)	MT-PROPELLER ENTWICKLUNG GmbH			PA-46-350P (MALIBU MIRAGE) PA-46-310P (MALIBU)	Installation of 4 blade MTV-16-1-E-C-F-R (P)/CFR206-58a on airplanePA-46-310P and PA-46-350P modified with Pratt & Whitney PT6A-21, -34 or-35 engine per FAA STC ST00541SE.	FAR 23 up to and including amendment 25 plus FAR 23.1529 atamendment26.	- Airplane Flight Manual Supplement E-1802, Issue 04. August 2009 orlater approved revision-Instruction for Continued Airworthiness E-1804, Issue 04. August 2009or later approvedrevision-Installation Instruction E-1803, Issue 04. August2009	Prerequisite for the installation of this STC is the installation of aPratt & Whitney PT6A-21, -34 or -35 engine per FAA STC ST00541SE.	28/08/2009	Active	10027008
10027014 (EASA.A.S.03849)	SCANDINAVIAN AVIONICS DESIGN ApS			500 (CITATION AND CITATION I)	Installation of Honeywell MST 67A Dual Mode S XPDR transponder.	Certification Basis as per EASA TCDS IM.A.207	- Engineering Order 2052922-EO Issue 1 from 10 June 2009- List of Certification Documents 2052922-DOC Issue 2 from 28. August2009- AFM Supplements 2052922-AM A Issue 1 from 03 March 2009, 2052922-AM BIssue 1 from 03 March 2009, 2052922-AM C Issue 1 from 03 June 2009-Instruction for Continued Airwor...	None	31/08/2009	Active	10027014

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027057 (EASA.IM.A.S.03259)	CASCADE AVIATION SERVICES INC.		FAA STC ST01133SE	DHC-8-301, -311, 314, 315 DHC-8-201 DHC-8-102, -103, -106	Installation of an increased security cockpit doorFAA STCST01133SE	FAR Part 25 as per TCDS EASA.IM.A.191 for DHC-8-100/200/300Series	Installation must be preformed in accordance with Cascade AviationServices, Inc.Master Drawing List 01CAS029-MDL, Rev. H, dated 16.02.2006*) Operation must be performed in accordance with AFM Supplement Doc. No.01CAS029-D 80*) Maintenance must be performed in accordance with Instructions forContinued*...	None	02/09/2009	Active	10027057
10027058 (EASA.IM.A.S.03192)	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA04-113	BD-700-1A10	Installation, complete Custom Aircraft Interior	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI A-100, CRI D-100, CRI D-200, CRI D-300, CRI D-500, CRI F-100, CRIF-200Thecertificated noise and/ or emissions levels of the originala...	-Transport Canada SoC reference C-09-0069 dated 27 August 2009.-TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.-Aero Consulting Services Configuration Definition List D954000RevisionDI dated 20 August 2009.-Instructions for ContinuedAirworthiness GC93060000-ICA.or later revisions of the above...	Restricted to ASN 9306.1. Refer to the Limitations sectionsof the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).3. Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and...	02/09/2009	Active	10027058
10027063 (EASA.IM.R.S.01493)	DART AEROSPACE Ltd.	REV. 1	TCCA STC SH08-38	412, 412EP 205A-1, 205B, 212,	SH08-38 Issue 1 "D412-769 Aft Facing Seat Installation"	FAR 29	-,,Installation Instructions; IIN-D412-769 Rev. B dated 24 June 2008-,,Master Document/Master Drawing List, MDL-D412-769 Rev. B dated 5 June2008-,,Instructions for Continued Airworthiness, ICA-D412-769 Rev. 0 dated24 June 2008	For Instructions for Continued Airworthiness see Report ICA-D412-769Rev. 0 dated 24 June 2008.	05/11/2009	Active	10027063
10027064 (EASA.A.S.03925)	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)	REV. 1		RALLYE 235 A, C, E, E-D, F MS894 A, C, E MS893 A, B, E, E-D	Reduction of maximum take off and landing weights to 1000 kg.	FAR 23.	SEGA Flight Manual Supplement A-05-09-1000kg, ed. 0, dtd. 20-07-2009, ENand FR version.SEGA Installations Instructions A-05-09-1000kg, ed. 0, dtd. 20-07-2009.SEGA Modification File A-05-09-1000kg, ed. 0, dtd. 20-07-2009.	MS894 models: seating capacity limited to 3 persons, pilot included.Rallye 235 models: seating capacity limited to 3 persons, pilotincluded. Fuel tanks capacity limited to 240 l (2*120l).The airplane configurations listed in attachment 1 are excluded from theapplicability of this STC because their m...	08/01/2010	Active	10027064
10027065 (EASA.IM.A.S.03148)	GULFSTREAM AEROSPACE CORPORATION			GV-SP (G550)	Installation of Custom Cabin Interior and Aircraft Completion forAircraft Serial 5224.	JAR 25	Install in accordance with Gulfstream Aerospace Report GC52000K634, Rev.N/C, dated 11 June 2009 and Index List GC520008647 Rev. G, dated06-08-09, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual SupplementGC52000M098 , Revision N/C, dated June 10, 2009, or lat...	Aircraft Serial Number 5224 only.	03/09/2009	Active	10027065

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027086 (EASA.IM.A.S.03165)	B/E AEROSPACE LIMITED	REV. 2	TCCA LSTC NO. C-LSA09-033/D	CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-033/D Issue 2 dated 24 September 2010.Aero Consulting Services Ltd. Modification Data Summary G122000 RevisionF.Midcoast Aviation Inc Airplane Flight Manual Supplement for the CompleteCustom Aircraft Interior Installation, 33-299M011 Rev NC.Aero Consulting Services Ltd. Mandato...	Restricted to ASN 8085.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/08/2013	Active	10027086
10027108 (EASA.IM.A.S.03188)	LEARJET Inc.		FAA STC ST01716LA-D	BD-100-1A10 (CHALLEGER 300)	- Installation of a Passenger Seat Upgrade- Validation of FAA STC ST01716LA-D	Certification Basis as per EASA TCDS IM.A.080 Issue 2, 8th October 2008(JAR 25 Change 15 plus other airworthiness requirements, SpecialConditions and Equivalent Safety Findings)	- FAA STC ST01716LA-D-Master Drawing List, ref. Doc. BAS68010001, Revision C, dated 28thFebruary 2005-Maintenance Requirements - Instruction for Continued Airworthiness,ref. doc. BAS68010001-IFCA-1, dated 24th February 2005 (*) or later revisions approved by EASA in accordance with EASA EDdecision...	None	07/09/2009	Active	10027108
10027110 (EASA.IM.A.S.02993)	DASSAULT FALCON JET CORP		FAA STC SA8300SW-D	FALCON 900EX	EASA Validation of FAA STC SA8300SW-D:Installation of the Automatic Cabin Electrical Load Shed System inaccordance withDrawing List Report No. F9EX-01023, Revision E dated28th September 2000 or later revisions approved by EASA in accordancewith EASA ED Decision 2004/04/CF (or subsequent revisions o...	- The Certification Basis for the original product remains applicable tothis certificate/ approval- The certificated noise and/or emissions levels of the original productare unchanged and remain applicable to this certificate/approval	- Aeroplane Flight Manual Supplement, Report No. 36571-1, RevisionOriginal dated 05th June 1997 is required for -501 aircraft installationas per defined on Drawing List F9EX-1023-Aeroplane Flight Manual Supplement, Report No. 36571-2, Revision Adated 12th November 1999 is required for -503 aircraft...	See those of original FAA STC SA8300SW-D	07/09/2009	Active	10027110
10027112 (EASA.IM.A.S.02997)	DASSAULT FALCON JET CORP		FAA STC SA8283SW-D	FALCON 900EX	EASA Validation of FAA STC SA8283SW-D:Installation of the Auxiliary Light Modifications in accordance withDrawing List Report No. F9EX-1011, dated 16th October 1996 or laterrevisions approved by EASA in accordance with EASA ED Decision2004/04/CF (or subsequent revisions of this decision)	- The Certification Basis for the original product remains applicable tothis certificate- The certificated noise and/oremissions levels of the original productare unchanged and remain applicable to this certificate	See those of original FAA STC SA8283SW-D as originally issued on 26thOctober 1996- or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	See those of original FAA STC SA8283SW-D	07/09/2009	Active	10027112
10027113 (EASA.A.S.03842)	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	PA-28	Aspen EFD1000 System	- JAA Interim Policies INT/POL/23/1, INT/POL/23/2 and INT/POL/23/3- FAA AC 23.1309-1D; FAA AC 23.1311-1B; FAA AC 23-23-AMC 20-115BThe certificated noise and/or emissions levels of the original productare unchanged and remain applicable tothis certificate	- Master Data List MDL1059-01 Issue 1-Instructions for Continued Airworthiness ICA1059-01 Issue 1- Flight Manual Supplement AFMS1059-01 Issue 1- Or later revisions of the above listed documents approved by EASA	None	07/09/2009	Active	10027113
10027115 (EASA.A.S.03705)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			500, 550, S550, 560	Installation of a TAWS System Honeywell Mark VIII EGPWS	FAR-25	Installation Procedure: 2008-11-1, Rev. AFlight Manual Supplement: 2008-11-8, Rev. BMaintenance Manual Supplement: 2008-11-10, Rev. A	Restricted to aircraft which already have installed a suitablemultifunction display.	08/09/2009	Active	10027115

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027116 (EASA.A.S.03730)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			500, 550, S550, 560	Installation of an FMS System Universal UNS-1M	FAR-25The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Installation Procedure: 2008-7-1, Rev. BFlight Manual Supplement: 2008-7-8, Rev. BMaintenance Manual Supplement: 2008-7-10, Rev. Aor later revisions of the above listed documents approved by EASA	None	08/09/2009	Active	10027116
10027121 (EASA.IM.A.S.03144)	AIRCRAFT PERFORMANCE MODIFICATIONS,INC.	REV. 4	FAA SA01935LA	SEE FAA AML	Installation of external aft body strakes, in accordance with FAAapproved Aircraft Performance Modifications Master Drawing List aslisted in AML No. SA01935LA, Revision IR, or later FAA approvedrevision.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	FAA accepted Instructions for Continued Airworthiness, as listed in FAAAML No. SA01935LA, Revision D, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	14/03/2019	Active	10027121
10027122 (EASA.IM.A.S.03183)	FIELD AVIATION COMPANY Inc.	REV. 3	TCCA STC SA02-48	DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Retrofit installation of Universal Avionics SystemsUNS-1F/UNS-1F(w)Flight Management System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Config. A – EFIS Equipped Aircraft, Single UNS-1F (Provisions Only) DHC-8-100 SeriesInstallation must be performed in accordance with Field Aviation MasterDrawing and Data List designated DDL-1073, Rev. F.DHC-8-300 SeriesInstallation must be performed in accordance with Field Aviation MasterDrawing a...	Configuration B Single UNS-1F with Software Version SCN 801, EFISEquipped Aircraft-de Havilland factory installed single UNS-1B or UNS-1B+ FlightManagement System Electrical and Structural provisions are aprerequisite to the Universal UNS-1F Flight Management System retrofit.-Approved for IFR En Rou...	26/08/2019	Active	10027122
10027141	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE	REV. 1	TCCA SA00-126; CAA NL SA0014NL	DHC-8-301, -311, -314, -315 DHC-8-102, -103, -106	QAR/ASAP Monitoring SystemTCCA SA00-126, Is. 4	FAR Part 25 as per TCDS EASA.IM.A.191 for DHC-8-100/200/300Series	A) Models: DHC -8- 102, -103, -106Installation must be performed in accordance with DECA AviationModification Summary MS00I0952, Revision 12 *)<(>,<)>This modification must be maintained in accordance with DECA MaintenanceManual SupplementDECA-4903-02 Revision 3 *)B) Models: DHC -8- 201, -202Instal...	The QAR system configurations are compatible with each of the followingFDR/FDAU combinations:For Model DHC -8- 102, -103, -106, -201, -202L3 FDR No: 2100-4043-00 with Plessey FDAUNo: 612/1/49780/102 (ModelPA3810BI/Post Mod 8/1876).For Model DHC -8 -301, -311, -314, -315L3 FDR No: 2100-4043-00 withP...	04/01/2010	Active	10027141
10027152 (EASA.R.S.01558)	AVIATION SUPPORT GmbH			600N	Installation of HD Camera System and right side dual utility mount MD600N, as per Master Document List Ref MDL-ASE-90819, dated 08.09.2009	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Instruction for Continued Airworthiness Ref. ICA-ASE-90819, Rev 0.3,dated 08.09.2009.- Flight Manual Supplement Ref FMS-ASE-90819, Rev 0.4, dated 08.09.2009or later revisions ofthe above listed documents approved by EASA	Approval limited to S/N RN073	10/09/2009	Active	10027152
10027156 (EASA.IM.A.S.01665)	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST00646CH	L1011-385-1, L1011-385-1-14 L1011-385-1-15, L1011-385-3	Installation of a single or dual Honeywell/ Trimble HT900 GlobalNavigation System, configurations 1, 2 or 3 in accordance withElectronic Cable Speciatlists Master Data List, ECS-960151, Rev. H datedJanuary 8, 1999 or later FAA approved revisionsValidation of FAA STC ST00646CH	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalThe applicant hasalso shown compliance to Guidance Material AMC 20-5.	Airplane Flight Manual Supplement, document ECS-960150Aircraft Maintenance Manual Supplement, document ECS-960169or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentrevisions ofthis decision)	None	10/09/2009	Active	10027156

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027158 (EASA.A.S.03970)	RUAG AEROSPACE SERVICES GmbH	REV. 1		CESSNA 525	Honeywell GNS-XLS P-RNAV Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-202B-AFMS, Rev. N/C Airplane Flight Manual Supplementor later revisions of the above listed documents approved by EASA.-202B-CN, Rev. N/C Change Note (Approval for Aircraft Modification) orlater approved revisions-202B-EO, Rev. N/C Engineering Order or later approved revisions	Restricted to aircraft with S/N 0001 to 0599 which already have an FMSHoneywell GNS-XLS installedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadve...	29/01/2014	Active	10027158
10027192 (EASA.A.S.03963)	RUAG AEROSPACE SERVICES GmbH			BD-700-1A10, -1A11	EGPWS MK V Enhancement with RAASUpgrade of the existing Honeywell Enhanced Ground Proximity WarningSystem (EGPWS) MK V with the Honeywell Runway Awareness and AdvisorySystem (RAAS). Installation of an optional RAAS Advisory Mute switchintothe center pedestal.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Master Document List, 29IC-MDL Revision A dated 10 September 2009.-Approval for Aircraft Modification, 29IC-CN Revision A dated 10September 2009.or later revisions of the above listed documents approved by EASA	- BD-700-1A10: S/N 9002 and subsequent- BD-700-1A11: S/N 9127 and subsequent	14/09/2009	Active	10027192
10027193 (EASA.IM.A.S.03219)	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA2614NM	2. MYSTERE FALCON 50 1. MYSTERE FALCON 200	EASA Validation of FAA STC SA2614NM:Cockpit Sun Visor Installation in accordance with Rosen Drawing List No.RF 50/200-00DL, Revision C dated 26th August 2009 or later revisionsapproved by EASA in accordance with EASA ED Decision 2004/04/CF(orsubsequent revisions of this decision)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	See those of original FAA STC SA2614NMor later revisions ofthe above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	This EASA approval is also applicable to the Falcon 50EX version of theMF50 aircraft model as per this aircraft versiondefinition described onEASA TCDS.A.062	15/09/2009	Active	10027193
10027196	TIMCO AVIATION SERVICES INC.		FAA STC ST00696AT-D	B747-400	Installation of Collins SAT-906 SatCom System with Ball Antenna's inaccordance with Timco Master Data List MDL-01068, Revision M, datedOctober 27, 1999 or later approved revision.	The Certification Basis for the original product remains applicable tothis certificate/ approval	None	None	14/09/2009	Active	10027196
10027199 (EASA.A.S.03743)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			P.180 AVANTI II	Installation of Garmin GPS-400 / 400W System	The Certification Basis of the original product remains applicable tothis ,,changeThe certificated noise and/ or emissions levels of the original productare ,,unchanged and remainapplicable to this certificate/ approval	-EASA approved Engineering Order, Doc. No. 2008-13, Revision A, dated01-Nov-2008, or later approved Issue-EASA approvedAirplane Flight Manual Supplement, Doc. No. 2008138,Revision A, dated 01-Nov-2008, or later approved Issue-Maintenance Manual Supplement, Doc. No. 2008-13-10, Revision A, dated01-N...	None	14/09/2009	Active	10027199
10027200 (EASA.R.S.01582)	RUAG AG	REV. 1		MD900	TV Broadcasting Equipment Installation (camera adaptation on existingmount and certification of the operators rack)Rev 1: Transfer of STC to a new legal entity that is holder of anew DOA(EASA.21J.760)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-27 Amdt. 2 dated 17.11.2008The requirements forenvironmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand rema...	-Rotorcraft Flight Manual Supplement (RFMS) Doc. No. 1872438-50-Installation Instruction Doc. No. 1872438-61or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The Installation TV Broadcasting Equipment is limited to: S/N 900-00131Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness...	18/01/2021	Active	10027200
10027205 (EASA.A.S.03982)	PREMIAIR AIRCRAFT ENGINEERINGLIMITED		CAA UK RESPONSIBILITY	BEECH 390 (PREMIER 1)	Cabin configuration change	CS 23	Configuration change in accordance with PremiAir modification No 09-015.Operation in accordance with PremiAir Flight Manual Supplement No09-RA390-01 Issue 1, dated 24 August 2009,or later approved revisions.	None	14/09/2009	Active	10027205

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027209 (EASA.IM.A.S.03096)	DV AVIATION, Inc.DBA NORTHPOINT AVIATION	REV. 3	FAA STC SA01878SE	T206H 206H, T206H 206H	Installation of Rolls-Royce 250-B17F/2 series engine with aHartzellModel HC-B3TF-7A/T10173FN(K)-11R PropellerRev. 3: Transfer from "Fifty-Ten-Yankee, LLC" to "DV Aviation, Inc."	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01878SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- Soloy Master Drawing List 766-100<(>,<)> Revision 0, dated October2008.- Aircraft Flight Manual Supplement S2010F, Revision 0, dated 24 October2008.- Maintenance & Overhaul Supplement S2012F, First Edition, Revision 0,dated October 2008.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2023	Active	10027209
10027216 (EASA.IM.A.S.03160)	B/E AEROSPACE LIMITED		TCCA C-LSA09-079/D	BD-700-1A11	Installation 16G Side Facing Divan	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-TCCA STC No C-LSA09-079/D Issue 2 dated 14 August 2009.-TCCA SoC ref. C-09-0745 dated 24 August 2009.-Aero Consulting Services Ltd. Modification Data Summary Number G198000Revision A.-Aero Consulting Services Ltd. Airplane Flight Manual Supplement G198090Revision N/C.- Savannah Air Center Instructio...	Restricted to: ASN 9289	14/09/2009	Active	10027216
10027217 (EASA.A.S.03905)	AIR ALLIANCE GmbH	REV. 1		TB9, TB10, TB 20, TB21, TB200	Installation of Aspen EFD 1000 PRO	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appro...	-Engineering Order: 2009_039_A51EU_0500, Rev. 0-Aircraft Flight Manual Supplement: 2009_039_A51EU_0506, Rev. 0-Instructions for Continued Airworthiness: 2009_039_A51EU_0507, Rev. 0or later revisions of the above listed documents approved by EASA	None	12/04/2010	Active	10027217
10027220	VIDEO TECHNOLOGY SERVICES, Inc.		FAA STC ST02720NY	B767-200, 300	Installation of Digital Video Player (DVP) on a B767 a/c	Certification Basis in accordance with EASA TCDS IM.A.035 plus:CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval...	- Video Technology Services, Inc. Master Technical Drawing List DocumentN° 205-D-400, Revision C dated July 9, 2009- Video Technology Services, Inc. Instructions for ContinuedAirworthiness Document N° 205-D-417, dated March 15, 2009- VideoTechnology Services, Inc. Airplane Flight Manual SupplementD...	None	15/09/2009	Active	10027220
10027222 (EASA.IM.A.S.03142)	PATS AIRCRAFT L.L.C.d/b/a PATS AIRCRAFT SYSTEMSd/b/a ALOFT AEROARCHITECTS	REV. 1	FAA STC ST00365NY-D	CL-600-2B19	Revisions to Auxiliary Fuel System Structural Provisions	IM.A.023The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	EASA STC No. 10027222 dated 15 September 2009.FAA STC No. ST00365NY-D dated 14 January 2011.Configuration 6. Installation of a two tank Auxiliary Fuel System withinthe fuselage pressure vessel forward of the baggage compartment inaccordance with PATS Aircraft, LLC. Master Drawing List, Drawing No. 60...	PATS Aircraft, LLC. Airplane Flight Manual Supplement No. 200, RevisionB, FAA approved 11 June 2009, is required with configurations 5 and 6.	12/07/2012	Active	10027222

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027223 (EASA.IM.A.S.03235)	PATS AIRCRAFT L.L.C.d/b/a PATS AIRCRAFT SYSTEMSd/b/a ALOFT AEROARCHITECTS	REV. 2	FAA STC ST01730NY-D	CL-600-2B19	Installation of an Executive Interior	EASA IM.A.023The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the or...	Configuration 1:EASA STC No. 10027223 Revision 1 dated 08 February 2010.FAA STC No. ST01730NY-D dated 14 January 2011.PATS Aircraft, LLC Master Drawing List 6049-0001-MDL, revision F dated01 July 2009.PATS Aircraft, LLC. Airplane Flight Manual Supplement No. 212 for anExecutive Interior, FAA approve...	In this installation the maximum passenger seating capacityis limitedto 15.	12/07/2012	Active	10027223
10027252 (EASA.IM.A.S.02934)	FIELD AVIATION COMPANY Inc.		TCCA STC SA09-15	DHC-8-314	Icelandic Coast Guard Maritime Patrol ModificationTCCA STC Number: SA09-15, Issue 1 dated 29. April 2009	FAR 25 as per TCDS EASA.IM.A. 191 plus EASA Special Condition "ServiceCompartment" as defined in CRI D-02, Issue 2, Annex 1.The Certification Basis for the original product and thefollowingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalThe certificate...	Installation must be performed in accordance with FAEL Master Drawingand Data List designated DDL-1185, Rev CFlight Operations must be performed in accordance with FAEL FlightManual Supplements as follows:FMS 20164 Rev IR,,Mission LandingGear Warning Horn Override ControlFMS 20165 Rev IR,,SRT-610...	UNS-1F(w) Flight Management Systems approved for En-route, Terminal andNon Precision approach operations only.External LAN System not approved for airborne operations.External Nokia Cellular Telephone System not approved for airborne use.The authorization to carry flares and other disposable storesb...	16/09/2009	Active	10027252
10027267 (EASA.IM.A.S.03252)	BOMBARDIER AEROSPACE		TCCA SA09-43	BD-100-1A10	VHF COMM 3 Power Source RelocationEASA Validation of:Transport Canada Supplemental Type Certificate SA09-43, Issue 1 dated20th May 2009 in accordance with Aero Consulting ServicesLtd.Modification Data Summary F912000 Revision N/C.	Certification Basis as per EASA TCDS IM.A.080 Issue 2, 8th October 2008(JAR 25 Change 15 plus other airworthiness requirements, SpecialConditions and Equivalent Safety Findings).	- Transport Canada Supplemental Type Certificate SA09-43, Issue 1 dated20th May 2009- Aero Consulting Modification DataSummary, ref. No. F912000 RevisionN/C, dated 12th May 2009 or later Transport Canada approved revision- Instructions for Continued Airworthiness, ref. No. BAS68050005-ICA,Revision...	None	17/09/2009	Active	10027267
10027268	STANDARD AERO		FAA STC ST02756CH-D	737-900ER 737-600, -700, -800, -900,	Installation of an in flight entertainment (IFE) system	In accordance with TCDSThe Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Standard Aero Documents:Master Data List MDL1104-100 Rev. Bdated September 09, 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	see limitations and conditions on STC FAA ST02756CH-D	17/09/2009	Active	10027268
10027270 (EASA.IM.A.S.03122)	ELECTRONIC CABLE SPECIALISTS, Inc.	REV. 1	FAA STC ST02637CH	737-900, 737-900ER 737-600, 737-700, 737-800 737-300, 737-400, 737-500 737-100, 737-200, 737-200C	Installation of ECS EZMount Mechanical Mounting AssembliesConfigurations :-1: Master Kit, EZMount® Slider 737-2: MasterKit, EZMount® Pivot 737-3: Master Kit, EZMount® Slider 737 ClassicRevision1: addition of configuration 4 Master Kit, EZMount Pivot for737-300/400/500	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The applicant elected to comply to the following paragraphs at CS25amendment 0:Configuration 1:25.301(a)(b), 25.303, 25.305(a)(b), 25.307(a), 25.561(c), 25.601,25.603, 25....	-Master Data List ECS-206467 Rev. U dated May 23,2013-AFM Supplement ECS-206471 Rev. A (Configurations 1 & 3)-AFM Supplement ECS-207424 Rev. A (Configuration 2)-AFM Supplement ECS-207423 Rev. N/C (Configuration 4)-Instruction for ContinuedAirworthiness ECS-206472 Rev. C (configurations 1, 2 & 3)-Ins...	The equipment for which these provisions are intended has not beencertified. An additional approval is required for theinstallation ofthis equipment and must be evaluated to assure satisfactory compliancewith applicable airworthiness requirements.Prior to installation of this design change it mustt...	04/06/2014	Active	10027270

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027284 (EASA.A.S.03927)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 3		A320-232	Airbus A320 12C/8J/36Y LOPARevision due to the introductionof cosmetic refurbishment includingre-painting of small seat panels and trim, and the replacement of theend bay side panels of First Class seats in order to satisfy therequirements of CRI D-2317.Rev. 3: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):CRI H-01 “Enhanced Airworthiness Programme for Aeroplane Systems – ICAon EWIS”CRI D-2317 – “Application of Heat Release and Smoke Density...	-Modification Summary Sheet, ref. doc. MOD-11490-00001, Issue 4, dated6th October 2017-Certification Programme, ref. doc. CP-11490-00001, Issue 2, dated 6thOctober 2017-ComplianceRecord, ref. doc. No. CR-11490-00001, Issue 3, dated 13thJuly 2017.-Master Document List, ref. doc. MDL-11490-00001, Iss...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10027284
10027294 (EASA.IM.A.S.03187)	INFLIGHT CANADA Inc.	REV. 4	TCCA STC SA09-28	737-800	Rockwell Collins dPAVES Overhead Passenger Entertainment System, TCCASTC Number: SA09-28 Issue 3 dated Nov 16, 2009. This revision consistsin removing the limitation on EWIS ICA	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Certification Basis in accordance with the EASA TCDS IM.A.120 plus: CRIH01/Special Condition H01 "Enhanced Airworthiness Programme forAer...	Inflight Canada / DECA Aviation Documents:Master Data List MDL08119-STC Rev.12Airplane Flight Manual Supplement FMS08119-STC Rev. 2Instructions for Continued Airworthiness ICA08119-STC Rev.3or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF...	none	04/06/2012	Active	10027294
10027295 (EASA.A.S.03975)	SOCIETE AIR FRANCE S.A.	REV. 2		A320	Cabin Reconfiguration from Dragon Aviation Leasing to Juneyao Standard (DKH)Revision of the EASA STC 10027295 to remove EWIS limitation	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The...	- Certification Program, ref. doc. No. CP-A320-09-009, Revision 02,dated 31st August 2009- Statement of Compliance, ref. doc. No. SOCPL-A320-09-009-005, dated31st August 2009-Instruction for Continued Airworthiness, ref. doc. No. ICA-A320-09-009Rev. 02, dated 11th August 2010-Enhanced Zonal Analys...	None	23/11/2010	Active	10027295
10027297 (EASA.IM.A.S.03026)	DECRANE AEROSPACE PATS AIRCRAFT,LLC	REV. 4	FAA STC ST01727NY-D	ERJ 190-100 ECJ	Installation of an Executive InteriorMajor Change to FAA STC ST01727NY-DUpdate of EASA STC 10027297 Rev 3: Compliance with EWIS ICA SpecialCondition H-01	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-1 IM.A.S. 03026The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remai...	Configuration 1:-Master Drawing List 5950-0000-MDL Rev. G dtd. 16.April 2009 (*)-Airplane Flight Manual Supplement No. 215, Rev. D dtd. 12. March 2010(*)-Maintenance Manual Supplement TO-3163 Rev. IR dtd. 1.May 2008 (*) withTR20-1001 dtd. 10.April 2009----------Configu...	Configuration 1:- Concurrent installation of STC ST01728NY-D (Class "C" CargoCompartment) iaw. Master Drawing List 6071-0000-MDL Rev. IR dtd.7.October 2008 is required.- Commercialoperation under EASA rules requires installation of PATS SBST0172NY-D-25-SB-001 "Modification of Pocket Doors to support...	24/06/2013	Active	10027297
10027298 (EASA.IM.A.S.03027)	DECRANE AEROSPACE PATS AIRCRAFT,LLC	REV. 2	FAA STC ST01728NY-D	ERJ 190-100ECJ	Modification of the Class C Forward Cargo Compartment to accommodate anAuxiliary Fuel Tank and Installation of a new Class C Cargo Compartmentat the Rear of the Main CabinMajor Change to FAA STC ST01728NY-DUpdate of EASA STC 10027298 Rev 1: Compliance with EWIS ICA SpecialCondition H-01	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-1 IM.A.S. 03026The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remai...	Configuration 1:Modification of the Class C Forward Cargo Compartment to accommodate anAuxiliary Fuel Tank and Installation of a new Class C Cargo Compartmentat the Rear of the Main Cabin.- Master Drawing List 6071-0000MDL Rev. IR dtd. 7.October 2008 (*)-Airplane Flight Manual Supplement No. 211, R...	Configuration 1:- Concurrent installation of STC ST01727NY-D (Installation of anExecutive Interior) iaw. Master DrawingList 5950-0000-MDL revision Gdtd. 16.April 2009 is required----------Configuration 2:- Concurrent installation of STC ST01727NY-D (Installation of an...	24/06/2013	Active	10027298

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027299 (EASA.IM.A.S.03028)	DECRANE AEROSPACE PATS AIRCRAFT,LLC	REV. 2	FAA STC ST01729NY-D	ERJ 190-100ECJ	Installation of a Passenger Gaseous Oxygen Supply SystemMajor Change to FAA STC ST01729NY-DUpdate of EASA STC 10027299 Rev 1: Compliance with EWIS ICA SpecialCondition H-01	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-1 IM.A.S. 03026The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remai...	- Master Drawing List 6072-0000MDL Rev. A dtd. 15.December 2008 (*)- Airplane Flight Manual Supplement No. 226, Rev. IRdtd. 17.April 2009(*)- Maintenance Manual Supplement TO-3163 Rev. IR dtd. 1.May 2008 (*) withTR20-1001 dtd. 10.April 2009(*) or later revisions of the above listed documents approv...	- Concurrent installation of STC's ST01727NY-D (Installation of anExecutive Interior) and ST01728NY-D (Class "C" Cargo Compartment) isrequired- For aircraft under FAA jurisdictionthis modification may not beinstalled after 30.August 2010 unless:(1) previously approved electrical wiring interconnect...	24/06/2013	Active	10027299
10027300	OREGON AERO, INC.	REV. 2	FAA STC SA01597SE	LC42-550FG, T240 LC40-550FG, LC41-550FG	Installation of replacement seats	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-According to Oregon Aero, Inc. Master Drawing List 6MDL-HG-10, Rev.K.02or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agree...	The installation of this modification by third persons is subject towritten permission of the approval holder and holding and disposal ofthe approved appropriate documentation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and a...	20/01/2017	Active	10027300
10027304	AVIATION SUPPORT GmbH		FOCA STC Z25-70-09	AS 350B, -B1, -B2, -B3	Ski carrier rack, P/N AV11300.Note: STC transferred from R.Sarbach, Mechanische Werkstaette toAviation Support GmbH.	FAR 27 amendment 10 as defined in TCDS EASA.R.008.	Drawing Data Set No. VA11300.Rotorcraft Flight Manual Supplement (RFMS) Doc. No. FMS SUP 5, revisiondated 08/08/2002.		18/09/2009	Active	10027304
10027314	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	PIPER PA32 ALL SERIES	Installation of Aspen EFD1000 PFD	CS-23. The Certification Basis for the original product andthefollowing additional or alternative airworthiness requirements areapplicable to this certificate/ approval.JAA Interim Policies INT/POL/23/1, INT/POL/23/2 and INT/POL/23/3FAA AC 23.1309-1DFAA AC 23.1311-1BFAA AC 23-23FAA AC 20-136AAMC 20...	Master Data List MDL1099-01Instructions for Continued Airworthiness ICA1099-01Flight Manual Supplement AFMS1099-01 Issue 1or later revisions of the above listed documents approvedby EASA		21/09/2009	Active	10027314
10027320 (EASA.IM.A.S.03251)	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03710AT-D	GULFSTREAM GIV-X	Installation of an Airplane Interior and completion for Aircraft SerialNumber 4161.	JAR 25. The Certification Basis for the original product remainsapplicable to this certificate. The certificated noise and/ or emissionslevels of the original product are unchanged and remain applicable tothis certificate.	Installed in accordance with Gulfstream Aerospace Corporation IndexList, GC420004161, Rev D, dated August 25, 2009.To be operated in accordance with Airplane Flight Manual SupplementGC41204M006 , Rev NC, date August 25, 2009.or later revisions of the above listed documents approved by EASA inaccordan...	Aircraft Serial Number 4161 only. The following STCs are a required partof this STC: ST02987AT-D, ST03290AT-D, ST02979AT-D, ST03410AT-D andST03647AT-D.It is the installer's responsibility to check these STC's are EASAApproved.	21/09/2009	Active	10027320
10027323	BUSINESS AND COMMUTER AIRCRAFT			B300	HF-9000 installation on Beech B300 Series PROLINE 21 Equipped	FAR Part 23 and FAR Part 25- The Certification Basis for the original product remains applicable tothis certificate- The certificated noise and/or emissions levels of the originalproductare unchanged and remain applicable to this certificate	BCA 115 modification file or later revisions of the above listeddocuments approved by EASA	Modification applicable to B300 equipped with Proline 21, serial numberFL-1 and after and FM-1 and after	21/09/2009	Active	10027323

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027337	BOMBARDIER INC.		TCCA STC SA04-113	BOMBARDIER BD-700-1A10	Installation, Complete Custom Aircraft Interior	EASA IM.A.009.The Certification Basis for the original product and the followingadditional or alternative airworthinessrequirements are applicable tothis certificate.CRI A-100, CRI D-100, CRI D-200, CRI D-300, CRI D-500, CRI F-100, CRIF-200.	Transport Canada SoC reference C-09-0070 dated 14 September2009.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000RevisionDK dated 08 September 2009.Instructions for Continued Airworthiness GC93090000-ICA.or later revisions of the abo...	Restricted to ASN 9309.Refer to the Limitations sections ofthe required AFM Supplement and tothe referenced FCOMS.WLANsystem is compatible only to IEEE 802.11 (b)	22/09/2009	Active	10027337
10027343 (EASA.A.S.03706)	E A D AEROSPACE AIRWORTHINESS			A330	Installation of Advanced Mission Display System - Phase A (AMDS/A)	In accordance with EASA TCDS A.004	- Master Drawing List, ref. 01250-EAS-A-MDL, Revision C, dated 22ndSeptember 2009- Design Similarity Statement, ref. 01250-EAS-A-DSS-01, Revision A,dated 31st July 2009- Airplane Flight Manual Supplement, ref. 01250-EAS-A-AFM-01, RevisionA, dated 31st July 2009- Declaration of Compliance, ref. 01250...	None	23/09/2009	Active	10027343
10027345 (EASA.A.S.03346)	LUFTHANSA TECHNIK AG			CL-600-2D24	Introduction of Datalink 2000+	EASA TCDS No. IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	LHT Declaration of Compliance No. 2035 dated 17 September 2009.LHT Supplemental Type Definition Document No. STDD23-07-07M Issue 2dated 15 September 2009.LHT Airplane Flight Manual Supplement No. A-23-07/0741-AFM Revision 2dated 06 August 2009.LHT ICA No. CA23-1580-02 Issue 1 dated 18 January 2008.A...	Not Applicable	23/09/2009	Active	10027345
10027347 (EASA.A.S.03887)	ACC COLUMBIA Jet Service GmbH	REV. 2		SA226T	Installation of MX20 Camera system.Installation of Wescam MX series (10, 15, 20) Gimbal Cameras with manualextension/retraction mechanism, operator console and downlink antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MDOCL_19719_rev1_20130501- AFM Supplement SPOH_19719_rev1_20130501- Installation Instruction II_19719_rev1_20130501or later revisions of the above listed documents approved by EASA.	According limitation section of AFM.Aircraft must be previously modified with camera hatches i.a.w.Swearingen Camera Hole Modification.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design chang...	19/01/2022	Active	10027347
10027351 (EASA.A.S.03939)	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	P-RNAV Capability	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Compliance has been shown in accordance with the requisites laid down byJAA Temporary Guidance Leaflet n. 10 "Airworthiness and Operation...	·,,DFS Change Approval Sheet DFS 5659-CAS Issue A, dated 21st September2009·,,DFS Aeroplane Flight Manual Supplement Number 48, Issue 2, dated 21stSeptember 2009	This EASA approval is applicable on those Mystere Falcon 50aircraftwhich have previously incorporated the Mod DFS 5598(approved underEASA.A.S.00615) with:·,,Collins Autopilot APS 85·,,EFIS 86 C14 and·,,Version 802.X for the FMS UNS-1L SoftwareThis design change is not applicable on the F50EX aircr...	24/09/2009	Active	10027351

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027352 (P-EASA.IM.A.S.03242)	BOMBARDIER INC.		TCCA STC SA08-90	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	Installation of Cockpit Speaker Mute Switch.	EASA TCDS No. IM.A.009The Certification Basis for the original product remains applicable tothis certificate.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate.	TCCA STC No. SA08-90 Issue 1 dated 18 December 2008.TCCA SoC reference C-09-0522 dated 17 September 2009.Aero Consulting Services Modification Data Summary Number G076000Revision N/C.Aero Consulting Services Instructions for Continued AirworthinessG076000-ICA.or later revisions of the above listed d...	None.	24/09/2009	Active	10027352
10027356 (EASA.A.S.03904)	AEROSERVIS, S.R.O.			F172N	Installation of NAV/COM Equipment:GNS 430 (NAV/COM/GPS), KX155 (NAV/COM), KR87 (ADF),KMA 24 (AUDIO/MKR)	FAR Part 23, Amdt. 50, dated 11 March 1996	Pilot's Operating Handbook Supplements:- No: STC AE/088-DLP1 (GNS 430)- No: STC AE/088-DLP2 (KX 155)- No: STC AE/088-DLP3 (KR 87)- No: STC AE/088-DLP4 (KMA 24)	none	24/09/2009	Active	10027356
10027368 (P-EASA.IM.A.S.03217)	MILLENNIUM CONCEPTS, INC.		FAA STC SA1507WI	CESSNA 208B CESSNA 208	Installation of aft cabin seats in Cessna Models 208 and 208B (Caravan)aircraft.	FAR 23.	Installation in accordance with Millennium Concepts Inc Master Drawinglist 2015-MDL036, Revision B, dated August 6 2008, or later approvedrevisions.Operate in accordance with AFM Supplement 2013-AFMS-S1, Revision IR,dated September 29, 2008, or later approved revisions.Instructions for continued air...	None.	25/09/2009	Active	10027368
10027371 (P-EASA.IM.A.S.01004)	BEECHCRAFT CORPORATION		FAA STC ST09450SC	BAE125-1000A	Installation of TCAS 2000 TCAS II System	14 Code of Federal Regulations Part 25.	Installation as defined in Hawker Beechcraft Services Master DrawingList 98-1000-100, Revision C, dated March 16, 2000,or later approvedrevision.Operation in accordance with Flight Manual Supplement as defined indocument ref 98-1000-102, Revision A, dated April 6, 2000 or laterapproved revisions.In...	None.	25/09/2009	Active	10027371
10027373 (EASA.IM.A.S.03273)	EMBRAER ENGINEERING & TECHNOLOGYCENTER USA, INC.	REV. 1	FAA STC SA03008CE	EMB-500	Installation of a Honeywell HF Communications System, ModelKHF-1050 andoptionally the Avtech Corporation SELCAL decoder, Model CSD-714.This STC was originally issued as a validation of Brazilian CTS (STC)No. 2009S05-14 (29 May 2009), and transferred to a United States basedDesign Approval Holder (D...	The Certification Basis for the original product remains applicable tothis certificate/approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/approval.	- Master Document List No TR0116, Rev J, dated 7 November 2018.- ANAC approved Airplane Flight Manual Supplement (AFMS)Document NumberH.02-2921-0/ANAC/2009, Rev I.R., dated 29 May 2009.- Instructions for Continued Airworthiness (ICA), Document NumberICA-006, Revision B, dated 6 November 2018.- Requ...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/11/2019	Active	10027373

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027379 (EASA.A.S.03915)	DANSK FLY ELEKTRONIK ApS			PIPER PA-28S-180 PIPER PA-28S-160 PIPER PA-28RT-201T PIPER PA-28RT-201 PIPER PA-28R-201T PIPER PA-28R-201 PIPER PA-28R-200 PIPER PA-28R-180 PIPER PA-28-236 PIPER PA-28-235 PIPER PA-28-181 PIPER PA-28-180 PIPER PA-28-161 PIPER PA-28-160 PIPER PA-28-151 PIPER PA-28-150 PIPER PA-28-140	Installation of ASPEN EFD1000 PRO Flight display	CS 23 Ammendment 1	DFE-DO-0345 Complete Design Package	None	25/09/2009	Active	10027379
10027391 (EASA.A.S.03654)	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			500, 550, 560	Installation of Honeywell KLN-94-GPS	EASA TCDS IM.A.207The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Engineering Data Report 2008-8 Revision E from 25 September 2009- Airplane Flight Manual Supplement 2008-8-8 RevisionC from 30 April2009- Maintenance Manual Supplement 2008-8-10 Revision B from 25 September2009- Declaration of Compliance to project 2008-8 from 31 August 2009"or later revisions of...	The installation is limited to Cessna models 500, 550 and 560 equippedwith Honeywell SPZ 500 Auto Pilot /Flight Director system and RD600 / RD44 Horizontal Situation Indicator systemLimitations according to AFMS 2008-8-8	28/09/2009	Active	10027391
10027395 (EASA.IM.A.S.03264)	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC SA8279SW-D	MF900, F900EX	EASA Validation of FAA STC SA8279SW-D:Installation of the Auxiliary Battery System in accordance with DrawingList Report No. F9EX-01008, Revision K dated 26th September 2002 orlater revisions approved by EASA in accordance with EASA ED Decision2004/04/CF (or subsequent revisions of this decision)	The Certification Basis for the original product remains applicable tothis certificate/ approvalDefine the additional airworthiness requirements SCs and accepted ESFs.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appro...	Drawing List Report No. F9EX-01008, Revision K dated 26th September2002.Aeroplane Flight Manual Supplement, Report No. 36500-1, Revision B dated04th February 2000."or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions...	This design change is also applicable on the Falcon 900C designation asdefined on EASA TCDS.A.062	28/09/2009	Active	10027395
10027397	BOMBARDIER INC.		TCCA STC SA04-113	BOMBARDIER BD-700-1A10	Installation, Complete Custom Aircraft Interior	EASA.IM.A.009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate.	Transport Canada SoC reference C-09-0544 dated 15 September2009.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000RevisionDL dated 09 September 2009.Instructions for Continued Airworthiness GC93030000-ICA.or later revisions of the abo...	Restricted to ASN 9303.Refer to the Limitations sections ofthe required AFM Supplement and tothe referenced FCOMS.WLANsystem is compatible only to IEEE 802.11 (b).	28/09/2009	Active	10027397
10027406 (EASA.R.S.01417)	NSE	REV. 6		EC 120 B	Installation of NSE UMS P/N REC-ARAO-TT-00Rev. 1: Software change in the Data Monitoring System “Brite Saver 2”and an RFM Supplement added.Rev. 2: Usage Monitoring System for EC120 – “Brite Saver 2, Amdt 4”added.Rev. 3: Technical documentation revision numbers corrected.Rev. 4: STC holder change fro...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-27 Amdt. 4 (electedto comply): CS 27.1316, CS 27.1317.The requirements for environmental protection and the associatedc...	NSE Flight Manual Supplement RFMS-REC-ARA-EC120-EN, Rev 3, dated 2 May2016<(>,<)>or later revisions of the above listeddocuments approved by EASA.- NSE Definition File DD-0027-92-EN, Rev 17.- NSE Conformity Statement CONFAD-0096-92-EN, Rev 08 dated 08/03/2018.- NSE Mounting Instructions IM-KIT-ARA-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/06/2018	Active	10027406

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027409 (EASA.A.S.03795)	AERODATA AG			B300	Installation of Aerodata Flight Inspection System AD-AFIS-150	The following new Certification Basis is applicable to thischange (*)CS-23, Amdt. 1, is elected to comply with for theitems affected by thechangeThe certificated noise and/ or emissions levels of the original productare ,,unchanged and remain applicable to this certificate/ approval	-EASA approved Master Document List, Doc. No. MDL-A/C-145, Rev. 1, dated25-Aug-2009, or later approved revision-EASA approved Airplane Flight Manual Supplement, Doc. No. AFM-106, Rev.1, dated 25-Aug-2009, or later approved revision-Approved Maintenance Manual Supplement, Doc. No. AMM-1009, Rev. 0,da...	Only applicable for aircraft / preconditions as defined in DesignDescription, Doc. No. DES-A/C-884, Rev. 1, dated 03-Aug-2009, or laterapproved revision	29/09/2009	Active	10027409
10027424 (EASA.A.S.03401)	TELEDYNE CONTROLS - FLIGHT DATACOMPANY		CAA UK RESPONSIBILITY	MD-80 SERIES	Installation of Wireless Quick Access Recorder.	FAR 25.	Master Drawing List MOD-MDL-022-02 Issue 1 dated 30 June 2009.	None.	12/09/2009	Surrendered	10027424
10027431 (EASA.R.S.01543)	ISEI			AS350 B3, EC130 B4	-Installation of Safetyplane Equipment-Installation of a system for tracking a set of flight and systemparameters during operation of the rotorcraft. The modification is basedon ISEI change N-EC130 AS350B3 as defined in Dossier de Définition de laModification-F-A-03, dated 26.06.2009.	EASA Certifcation Basis as per EASA TCDS.R.008The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicabletothis certificate/ approvalThe change complies with CS27 First IssueThe certificated noise and/ or emissions levels ofa...	-Dossier d'approbation de modification N-EC130 AS350B3Approbation-F-A-02, dated 23.07.2009-Dossier de Définition de la Modification N-EC130 AS350B3Définition-F-A-03, dated 26.06.2009-Dossier d'Installation N-EC130 AS350B3 Installation F-A-04, dated28.07.2009or later revisions of the above listed doc...	None	30/09/2009	Active	10027431
10027439 (EASA.A.S.03889)	MT-PROPELLER ENTWICKLUNG GmbH			BAE JETSTREAM 3100, 3200	Installation of 5-blade MTV-27-1-E-C-F-R (G)/CFRL250-103() propellers	FAR 23, Amdt 1 through 34The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicabletothis certificate/ approvalThis certificate/ approval involves a change to the certificated noiseand/ or emissions levels	-According to MT-Propeller Master Document List Doc. No. E-1764, Rev 1and MT-Propeller Installation Instructions Doc. No. E-1766, Rev 1,-To be operated in accordance with MT-Propeller AFM-S Document No.E-1765, Original Issue, or later approved Revisions-To be maintained i.a.w. MT-Propeller ICA Docum...	None	30/09/2009	Active	10027439
10027446 (EASA.R.S.01370)	BRISTOW HELICOPTERS Ltd.	REV. 1	CAA UK RESPONSIBILITY	AS 332 L1	ECT Night Vision Imaging System InstallationMaster Drawing NOR-0450 Rev. ENote: STC revised due to new ownership Bristow Helicopters	As defined in TCDS EASA.R.002The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of theoriginal product areunchanged and remain applicable to this...	Flight Manual Supplement AS332L-PMV-SUPP-002Dor later revisions of the above listed documents approved by EASAMaster Drawing NOR-0450 Rev. EMinimum Equipment List Supplement AS332L1-MEL-SUPP-002 Rev. BInstructions for Continued Airworthiness NOR-0462 Rev. BMaintenance Instructions Supplement MIS-006...	None	27/10/2011	Active	10027446
10027449	RUECKER AEROSPACE GmbH			DORNIER 228-101	Installation of UHF Research Mission Equipment	The following new Certification Basis is applicable to thischangeCS-23, Amdt. 1, is elected to comply with for the items affected by thechangeThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	EASA approved Master Document List, Doc. No. MDL-890-00002-000, Issue D,or later approved issue	Limited to serial number 7083	01/10/2009	Active	10027449

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027451	RUECKER AEROSPACE GmbH			208B	Installation of UHF Research Mission Equipment	The following new Certification Basis is applicable to thischangeCS-23, Amdt. 1, is elected to comply with for the items affected by thechangeThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	EASA approved Master Document List, Doc. No. MDL-890-00001-000, Issue E,or later approved issue.EASA approved Aircraft Flight Manual Supplement, Doc. No.AFMS-890-00001-000A	Limited to serial number 708	01/10/2009	Active	10027451
10027470 (EASA.IM.A.S.03268)	SECURAPLANE TECHNOLOGIES, Inc.	REV. 1	FAA ST01809LA	SEE APPROVED MODEL LIST (AML)	Installation of Hawker 975W0640 Sealed Lead Acid Battery	FAR 25	Installation in accordance with Approved Master Data List (MDL) DocumentNo 170-0402-01 Revision "-", dated April 13, 2005, or later approvedrevisions.	This approval is limited to those aircraft listed in the AML andequipped with lead acid battery.Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effectt...	27/11/2014	Active	10027470
10027495	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	B737-800	Introduction of Recaro Economy Passenger Seats on Boeing 737-800, inaccordance with project H4A1239 (Revision of STC 10027495 to remove EWIS Limitation)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The certificated noise and/ or emissi...	Modification Summary Sheet: H4A1239 Issue 1 signed 02 October 2009.Instructions for Continued Airworthiness: H4ADR493 Issue 2.or later revisions of the above listed documents approved by EASA	None	09/03/2011	Active	10027495
10027505 (EASA.A.S.03912)	LUFTHANSA TECHNIK AG			FOKKER F27 MARK 050	Installation of self-illuminating Floor Path Marking System.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CS-25, Amendment 5 (elect to comply).The certificated noise and/ or emissions levels of the original productare unchanged and remain...	Supplemental Type Definition Document STDD33-09/01M, Issue 01, Rev. 01Engineering Bulletin F50-EB33-0343, Revision 01Airplane Flight Manual Supplement A-00-09/066-AFM, Revision IRCompliance Record List CRL33-09/01M, Issue 01, Rev. 01*or later revisions of the above listed documents approved by EASA...	Fokker F50 (F27 Mark 050) aircraft series in standard airline cabinconfiguration described as typical cabin layout in Engineering BulletinF50-EB33-0343, Rev. 01, CH. 4.2. Cabin layout with convertible seats(non fixed lateral position may result in covering the fixed Guideline®strips) or VIP cabin la...	06/10/2009	Active	10027505
10027509 (EASA.IM.R.S.01527)	SAGEM AVIONICS, L.L.C.	REV. 3	FAA STC SR09450RC	EC120B	SAGEM Integrated Cockpit Display System ICDS-8A Installation.Initial STC: Installation of SAGEM ICDS-8A Integrated Cockpit DisplaySystem (ICDS) coupled to SAGEM Autopilot per FAA STC SR09263RC-D(EASA.IM.R.S. 01056) in accordance with SAGEM MDL 120-0002, Rev. D, and:1. Configuration per SAGEM drawing2...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Supplement for Airbus Helicopters Model EC120 Bequipped with SAGEM ICDS-8A Integrated Cockpit DisplaySystem (SoftwareVersion EC120-AP85-5-B), SA-ER-050722-01, Rev 00, dated 8 December 2016or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	For Night VFR operations the helicopter must be fitted witha back-upinstrument permitting attitude control, such as a stand-by attitudeindicator or a slip/skid indicator.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any ot...	18/01/2017	Active	10027509
10027535 (EASA.IM.A.S.03159)	ROSEMOUNT AEROSPACE, Inc.		FAA STC ST02761CH	737-300, 400, 500	Installation of Rosemount 8700C2-7 Series Laptop Docking Station (LDS) - Electronic Flight Bag (EFB) System. Validation of FAA STC ST02761CH	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Refer to list ofchanges on FAA ST02761CH.The certificated noise and/ or emissions levels of the original productare unchanged and remain...	Rosemount Aerospace Documents:Master Data List D06403164 Rev. CApproved Airplane Flight Manual Supplement D06403463 Rev. AInstructions for Continued Airworthiness D06403964 Rev. B*or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or sub...	Refer to limitations and conditions on FAA ST02761CH.	08/10/2009	Active	10027535

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027558 (EASA.A.S.03680)	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	DHC-8-102	Traffic Alert and Collision Avoidance System (TCAS II) Installation.	The Certification Basis for the original product remains applicable tothis certificate, CS25 elected to comply.	Aerospace Design and Engineering Consultants (AeroDEC®) Ltd.Modification Summary, MOD-0468, Rev. C or later approved Revision andAerospace Design and Engineering Consultants (AeroDEC®) Ltd. FlightManual Supplement No.1, FMA -0468-058 Rev. 2 or later approved Revisionor later revisions of the above l...		09/10/2009	Active	10027558
10027571 (EASA.A.S.03848)	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special Transports / Transports Speciaux. (This STC, ref. ST25MOD020ed.01 (Applicant reference), has been developed, reviewed, tested andfound compliant with the Certification Basis to deal with non-Airbussub-assemblies transport. On case by case basis, this STC had to beamended to cover any new non...	As per EASA TCDS A.014 + CRI D-10 Issue 01.The Certification Basis for the original product and the followingadditionalor alternative airworthiness requirements are applicable tothis certificate/ approval. The certificated noise and/ or emissionslevels of the original product are unchanged and rema...	Change Approval Sheet, ref ST25MOD020, Issue 48 or later revisions ofthis document approved by EASA.		12/10/2009	Active	10027571
10027594 (EASA.R.S.01487)	NSE	REV. 13		EC120 B EC 120 B	Installation of Night Image Vision System kit, allowing Night VFR flightwith Night Vision Goggles.Rev. 2: Changes temperature limitation in Rotorcraft Flight Manual.Rev. 3: Incorporates Minor Changes to NVIS Shunt and LACU.Rev. 4: Displaysadministrative changes to include all applicabledocumentatio...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program CP-NAF2400124-A2, dated 06 May 2025.EC 120 NVIS STC DATA LIST, SDL-57B-1000-000, Rev. 09.ROTORCRAFT FLIGHT MANUAL SUPPPLEMENT, RFMS-0010-09BE10-EN, Rev. 21.or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limitations:Refer to applicable RFM for list of equipme...	09/07/2025	Active	10027594
10027600 (EASA.IM.A.S.02677)	PREMIER AIRCRAFT, LLC		FAA STC ST01951LA	MF50 BASIC CONFIGURATION	EASA Validation of FAA STC ST01951LA:Installation of TFE731-4-1C engine part number 3075900-1, per HoneywellService Bulletin TFE731-72-3703, dated January 19, 2007 on the MF50basic aircraft configuration in accordance with Flight Test Associates,Inc. Master Drawing List (MDL) No. PA-00100, RevisionO...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThis certificate/ approval involves a change to the certificated noiseand/ or emissions levels	- Flight Test Associates, Inc. Master Drawing List (MDL) No. PA-00100,Revision A, dated 03rd October 2006- Aeroplane Flight Manual Supplement Document No. FTA-PA-001019 RevisionC dated 30th September 2009- Flight Test Associates, Inc. Instructions for Continued Airworthiness,FTA-PA-001014, Revision"...	Not Applicable	13/10/2009	Active	10027600
10027602 (EASA.IM.A.S.02776)	MAX-VIZ Inc.		FAA STC ST01523LA	F900EX, MF50, MF900	EASA Validation of FAA STC ST01523LA:Installation of Max-Viz Enhanced Vision System (EVS) 1000 in accordancewith MasterDrawing List Document number 3038-00025 Revision 5, dated14th October 2008 or later revisions approved by EASA in accordance withEASA ED Decision 2004/04/CF (or subsequent revision...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Master Drawing List Document number 3038-00025 Revision 5,dated 14thOctober 2008- Aeroplane Flight Manual Supplement Document No. 3038-00026, Revision Adated 16 December 2008 forthe basic Mystere Falcon 50 aircraftconfiguration- AeroplaneFlight Manual Supplement Document No. 3038-00027, Revision A...	This design change is also applicable on the Mystere Falcon50EXdesignation as defined on EASA TCDS.A.062 but limited to the serialnumber aircraft MSN 286. For this MSN 286 aircraft the applicable EASAFlight Manual Supplement is the initial release of Document No.3038-00047 or later EASA approved re...	13/10/2009	Active	10027602

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027603 (EASA.R.S.01447)	INGENIEURBÜRO FÜR LUFTFAHRTMANF RED BLEYER	REV. 5		AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 B3 AS 350 B1, AS 350 B2	Installation of an airborne laser scanning equipment in AS350/355 serieshelicopterRev. 1: Component change airborne laser system (alternative camera)Rev. 2: Replacement of variousequipment like data recorder, GNSSmodule, flight path display, controller laptop. Restriction regardingAS350 B3 mod OP-3...	For all effected AS 350 models:The Certification Basis for the original product as amended by thefollowing additional or alternative airworthiness requirements: 27.25 CS27 first issue - 27.27 CS 27 first issue - 27.65 (b) CS 27 first issue-27.67 FAR Part 27 Amdt 23 - 27.71 CS 27 first issue - 27.75...	- Engineering Summary Report: ESR-35X-2001, Rev. 0.3- Flight Manual Supplement FMS-35X-2001, Rev. 4- Installation Instruction: IIS-35X-2001, Rev.0- Instructions for continued airworthiness: ICA-35X-1901, Rev 0Or later revisions of the above listed document(s) approved/acceptedunder the EASA system	Service Bulletin No. 25.00.62 is a prerequisite and must beinstalledprior this modification.Any alteration of installed equipment leads to noncompliance ofcommitted and approved design and therefore requires reinvestigation andchange approval prior use.CAT A Procedures with external pod installed a...	30/05/2022	Active	10027603
10027605 (EASA.R.S.01336)	AVIATION SUPPORT GmbH			AS 350 BB, AS 350 D AS 350 B, AS 350 B1, AS350 B2 AS 350 B3, AS 350 BA	Installation of a 3D laser measurement system in an external cargo pod.	FAR 27The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-ICA-ASE-90603 Revision - Instructions for Continued Airworthiness;-MDL-ASE-90603 Revision - Master Document List (Liste der gültigenDokumente);-FMS-ASE-90603 Revision - or later EASA approved revision - FlightManual Supplement"or later revisions of the above listed documents approved by EASA" forFM...	None	13/10/2009	Active	10027605
10027628 (EASA.A.S.03677)	AEROSPACE DESIGN AND ENGINEERINGCO NSULTANTS Ltd.	REV. 1	CAA UK RESPONSIBIL ITY	A330-223	Introduction of a change from a 48C/182Y dual class seatingconfiguration to a 24C/ 242Y passenger seating configuration.	Certification Basis in accordance with the EASA Type Certification dataSheet TCDS A.004 issue 16 with CS25 Amendment 4 for the areas affectedby the change (plus reversion to aircraft's TC basis for §25.785 (3) (c)(2) head impact criteria).	-Modification Summary, doc. No MOD-0475 Revision D dated 15/10/09-Aircraft Manual Supplement Document No: AMS-330-294-299 dated 01/07/09or later revisions of the above listed documents approved by EASA	None	03/12/2009	Active	10027628
10027637 (EASA.A.S.03763)	GAMA ENGINEERING Ltd.	REV. 2	CAA UK RESPONSIBIL ITY	F28 MARK 0070	Interior Refurbishment and System Upgrade	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emission levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Change Leaflet 1838 Release A, 15/08/2009 (per original certificate)- Continued Airworthiness TN1838-091 Release B, 15/10/2009 (per originalcertificate)- Certification Plan TN1838-026 Release A15 December 2009- Flight Manual Supplement FMS1838-095 Issue 2- EASA Terms of Approval 21J.174 Issue 7, 1...	None.	26/11/2012	Active	10027637
10027657	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBIL ITY	PA-E23-25 PA-23-235, PA-23-250	Installation of Garmin G500/G600 EFIS PFD/ND	CS-23The Certification Basis for the original product remains applicable tothis certificate/ approvalNon-significantTherequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalproduct areunchanged and remain applicable to this certifica...	Master Data List MDL1087-02 Issue 1Change Statement CS1087-02 Issue 1Instructions for Continued Airworthiness ICA1087-02 Issue 1Flight Manual Supplement AFMS1087-02 Issue 1or later revisions of the above listed documents approved by EASA	None	21/10/2010	Active	10027657

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027658	BEECHCRAFT CORPORATION	REV. 1	FAA STC SA02253LA	B300/B300C	Installation of Belly Radome.	FAR 23The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificatednoise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Installation in accordance with Master Data List 300E368671 Revision8, dated September 14, 2009, or later approved revisions.- Operation in accordance with Airplane Flight Manual Supplement, 130-590031-327, September 2009, for 16,500 lb MTOW Configuration.- Operation in accordance with Airplane Fli...	none	05/10/2011	Active	10027658
10027677 (EASA.R.S.01499)	HELIKOPTER AIR TRANSPORT GMBH			EC 135 T2 (CPDS) EC 135 T2+ EC 135 T1 (CDS)	Engineering Order EO 85-002, dated 21 September 2009 "Replacement ofSiren Hooks with Onboard Talon Systems".	JAR 27 first issue - 06. September, JAR 27 Appendix C for Category AOperation, and JAR 27 Appendix B for operation under IFR; CS 27.1(a) inconnection with CS 27.2(b)(2)(i) elect to comply ace. to CRI A-6.The Certification Basis for the original product remains applicable tothis certificate/ approval...	Installation Manual IM 85-002, dated 08.09.09; OnBoard CMM 528-023-01,Rev. 15, dated 23.04.09; Indraero Siren CMM SL07-3, dated 22.06.05; AFMSupplement 85-002 T1 (CDS), dated 08.07.09; AFM Supplement 85-002 T2(CPDS), dated 08.07.09; AFM Supplement 85-002 T2+, dated 08.07.09; PartsOverview 85-002-001...	Installation does not constitute operational approval.Approval of PCDS (Personal Carrying Device System) for external loadoperation must be granted by the competent authority.	20/10/2009	Active	10027677
10027678 (EASA.A.S.03803)	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges	REV. 1		A330-223	Airbus A330 - 200 B/C ISPSS Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The certificated noise and/ or emis...	- Engineering Bulletin, ref. doc. No. EB_M06500111_MBO_02062009 /ABLD_24279_04, Revision 1, dated 20th October 2009- Engineering Order, ref. doc. No. EO_M06500111_MBO_04062009, Revision0, dated 20th October 2009- Certification Program, ref. doc. No. CEP_M06500111_MGR_15042010,Revision D01, dated 29t...	This STC is limited to the following Serial Numbers:MSN 403, 432, 444, 454, 469, 476, 493	25/05/2010	Active	10027678
10027687 (EASA.R.S.01307)	HELI-ONE (NORWAY) AS			AS332L1 AS332L AS332C1 AS332C	EFIS 520 Installation.	FAR 29.	AHS-028 original issue dated 14 July 2009 or later approvedrevision -Flight Manual Supplement;52200 revision H dated 9March 2009 - Master Drawing;AHSE-54559 Original issue dated10 October 2009 - Instructions forContinued Airworthiness;AHSB-3420-055 original issue dated 6 December 2008 - Service B...	None.	21/10/2009	Active	10027687
10027691	BUCHER LEICHTBAU AG	REV. 5	FOCA 25-20-102 REV 3	SEE AIRCRAFT ALLOCATION TABLE E043-01-12 REV. F DTD 25/09/12	16G New Generation Stretcher P/N 1120030 -000 / -010 / -020Minor Change to EASA STC 10027691 Rev. 4- Integration approval on A320-214	JAR 25 Amdt 15<(>,<)> except §25.562 as addressed per TGM/ 25/12The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List MDoc-1120030 Rev. L<(>,<)> dated 02/09/2013-Master Drawing List E015-01-03 Rev. C, dated 06/08/2013-Aircraft Allocation Table E043-01-12 Rev. F, dated 25/09/2012-Project Certification Plan E026-05-12 Rev. A<(>,<)> dated 02/09/2013-Statement of Compliance E026-05-12 Appendix I R...	This STC constitutes an approval for installation only for aircraftserial numbers as stated in the Master Document List. For any additionalconfigurations as per Aircraft Allocation Table, the requirements asstated in the Master Document List have to be demonstrated through adesign approval.No electr...	14/10/2013	Active	10027691

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027700 (EASA.A.S.03909)	AERO VODOCHODY AEROSPACE A.S.	REV. 2		EMB-135BJ	EFB class2 navAero- t.BagC2² Electronic Bag System implementation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCert Basis CS-25 AMDT 4 plus:-TGL-36 "Electronic Flight Bag"-CRI F-1/03909 "Installed resources"The certificated noise and/ or emissions l...	-Master Data List AM001-00-00-PA002 Rev. A dtd. 18. Sep 09-AFM Supplement AM001-00-00-LM001 Rev. A dtd. 30. Sep 09-AMM Supplement AM001-00-00-LM002 Rev. A dtd. 1. Oct 09or later revisions of the above listed documents approved by EASA	-Application of Electronic Checklist/ECL and WLAN need a separateapproval-No external devises are approved to be connected to the display duringmovement/flight of the aircraft.	17/06/2013	Active	10027700
10027714 (EASA.A.S.03957)	AIR ALLIANCE GmbH			TBM 700	Installation of GPS Antenna for Situational Awareness Tool.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Engineering Work Order 2009_025_A.010_500 Rev. 0;Instructions for Continued Airworthiness 2009_025_A.101.507 Rev. 0or later revisions of the above listed documents approved by EASA	None.	26/10/2009	Active	10027714
10027715	AERO CONSULTING SERVICES LTD.		TCCA LSTC C-LSA09-099/ D	BD-700-1A10	Installation, 16 G Side Facing Divan.	EASA TCDS No IM.A.009.The Certification Basis for the original product remains applicable tothis certificate.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate.	TCCA STC No. C-LSA09-099/D Issue 1 dated 14 October 2009.TCCA SoC ref. C-09-0969 dated 21 October 2009.Aero Consulting Services Ltd. Modification Data Summary Number G255000Revision N/C or later approved revision.Aero Consulting Services Ltd. Airplane Flight Manual Supplement G255090Revision N/C orS...	None.	26/10/2009	Active	10027715
10027723	CESSNA ZURICH CITATION SERVICE CENTGMBH			525 / 525A / 525B	MINIQAR installation; By installing an Avionica miniQAR MK II and the MKIII according to the Installation Instructions OPM-009.	FAR 23.The Certification Basis for the original product remains applicable tothis approval.Derogation to latest amendment (Part 21A.101): non significant change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Document List, Doc. No. MDL-069- ICA, Doc. No. ICA-036or later revisions of the above listed documents approved by EASA.	S/N 525-0600 & ON, 525A-0001 & ON, 525B-0135 & ON.	26/10/2009	Active	10027723
10027731 (EASA.IM.A.S.03254)	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02705CH-D	GV-SP	Aircraft Serial No 5240 completion and cabin interior installation.	JAR 25The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/or emissions levels of the original productare unchanged and remain applicable to this certificate/approval.	- Installation in accordance with Gulfstream Aerospace CorporationMaster Drawing List No. GC52 2046146, Revision B, dated October 6, 2009,or later approved revisions.- Operation to be in accordance with Gulfstream Flight Manual SupplementGC52 204M044, Original Release, dated October 6, 2009, or late...	GV-SP Serial No. 5240 Only.	26/10/2009	Active	10027731
10027739 (EASA.A.S.03929)	AEROSERVIS, S.R.O.			L 410 UVP-E, L 410 UVP-E9	The set of the safety modifications in order to prepare thealternativemean of the compliance to EASA AD 2008-0104 and EASA AD 2008-0105.	FAR Part 23 Amdt. 34, dated 17 February 1987 through Amdt. 49, dated 11March 1996.	L 410 UVP-E Flight Manual Supplement No. STC AE/ 090-DLP1L 410 UVP-E9 Flight Manual Supplement No. STC AE/090-DLP2L 410 UVP-E, E9 Wiring Manual Supplement No. STC AE/090-DAE1L 410 UVP-E, E9 Maintenance Manual Supplement No. STC AE/090-DTP1L410 UVP-E, E9 Maintenance Schedule Supplement No. STC AE/090...		26/10/2009	Active	10027739

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027744 (EASA.IM.A.S.03198)	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02643NY-D	A340-300	Update of a Panasonic System 2000E In-Flight PassengerEntertainment System to a System 2000E HybridMajor Change to the EASA STC 10027744 to remove EWIS limitation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01/ SpecialCondition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The requirements for environmental p...	-FAA STC ST02643NY-D dated 19th September 2009-Delta Engineering Master Data List, ref. doc. No. 0152-06526-2199,Revision B, dated 19th September 2009-Compliance Summary Report, ref. doc. No. 6652-06713-2199, Revision A,dated 21st October 2009-Substantiation Report "EASA Leaflet 17", ref. doc. No. 6...	None	04/04/2012	Active	10027744
10027745 (EASA.IM.A.S.03199)	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02642NY-D	A330-200	Update of a Panasonic System 2000E In-Flight PassengerEntertainment System to a System 2000E HybridMajor Change to the EASA STC 10027746 to remove EWIS limitation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01/ SpecialCondition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The requirements for environmental p...	-FAA STC ST02642NY-D dated 3rd August 2009-Delta Engineering Master Data List, ref. doc. No. 0154-06517-2198,Revision A, dated 1st August 2009-Compliance Summary Report, ref. doc.No. 6600-06711-2198, Revision A ,dated 21st October 2009-Substantiation Report "EASA Leaflet 17", ref. doc. No. 6600-067...	The STC holder shall provide by 7th June 2010 Instructions for ContinuedAirworthiness on Electrical Wiring Interconnection System - EWIS ICA -in accordance with Special Condition H-01 "Enhanced AirworthinessProgramme for Aeroplane Systems - ICA on EWIS".	04/04/2012	Active	10027745
10027746 (EASA.IM.A.S.03200)	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02642NY-D	A330-200	Update of a Panasonic System 2000E In-Flight PassengerEntertainment System to a System 2000E HybridMajor Change to the EASA STC 10027746 to remove EWIS limitation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01/ SpecialCondition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The requirements for environmental p...	-FAA STC ST02642NY-D dated 13th July 2009-Delta EngineeringMaster Data List, ref. doc. No. 0154-06517-2198 (Configuration 2), Revision - , dated 10th July 2009-Compliance Summary Report, ref. doc. No. 6600-06711-2198, Revision A ,dated 21st October 2009-Substantiation Report "EASA Leaflet 17", ref.R...	None	04/04/2012	Active	10027746
10027762	BOMBARDIER INC.	REV. 1	TCCA STC SA05-60	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9343	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	TCCA STC No. SA05-60 Issue 1, dated 14 June 2005.Aero Consulting Services Ltd Configuration Definition List No. E025000Revision DB dated 31 May 2010.Bombardier's Airplane Flight Manual Supplement G-FM25004501 RevisionN/ C.GC93430000-IFCA Instructions for Continued Airworthinessor later revisions of t...	Restricted to ASN 9343.	04/06/2010	Active	10027762
10027764 (EASA.R.S.01588)	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	EC135 T2+, EC135 P2+	Title: Installation of an External Camera and related ENG equipmentDescription: Installation of an Axsys Technologies Cineflex V14 Camerabased on EC UK change MHL/135/1200 as defined in Drw. No.A3/1351200-100-1 Issue A and installation of the related ENG equipmentbased on EC UK change MHL/ 135/1198 a...	JAR27 First Issue as per TCDS EASA.R.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Flight Manual Supplement:- EC135 FMS No. 53 Rev. 0 or later revisions approved by EASAICA:-Maintenance Requirement Document MR/1351200-001 Issue A-Maintenance Requirement Document MR/ 1351198-001 Issue C	None	30/10/2009	Active	10027764

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027778 (EASA.A.S.03977)	STIRLING DYNAMICS GMBH	REV. 4	FAA STC SA02782NY	PC-12, PC-12/45, PC-12/47 PC-12, PC-12/45, PC-12/47, PC-12/47E PC-12/47E	Heavy Duty Floor for PC-12 AircraftsRev. 4: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Engineering Order BUPC12-EO-0001-01-02 Issue 02-Aircraft Flight Manual Supplement BUPC12-AM-5300-01-03 Issue 3or laterrevisions of the above listed documents approved by EASA	Heavy Duty Floor P/N 0127258 is limited to from S/N 101 to S/N 999except S/N 545 with configuration in accordance with Bucher OMME014-16-01Heavy Duty Floor P/N 0127470 and P/N 0127470-401 is limited to from S/N1001 on which configuration in accordance with Bucher CMM E016-19-08Prior to installationt...	15/06/2022	Active	10027778
10027805	RAM AIRCRAFT, LIMITED PARTNERSHIP		FAA STC SE10746SC-D	IO-520-B -, -BB, -C, -CB	Conversion of Teledyne Continental Motors (TCM) models IO-520-B, -BB toRAM model IO-550-B-RA engine, or conversion of TCM models IO-520-C, -CBto RAM model IO-550-C-RA engine in accordance with RAM Master DrawingList 2691, Revision I.R. dated November 7, 2006, or later FAA approvedrevision.	The Certification Basis for the original product remains applicable tothis certificate/ approval	Operator's Manual Supplement for RAM IO-550 series engines:RAM Document2729, Rev. A dated August 29, 2007 or later approved revisionInstructions for Continued Airworthiness: RAM Document 2692, datedNovember 7, 2006, or later approved revisionOverhaul Manual Supplement for Conversion of IO-520-B, -B...	The RAM model IO-550-B-RA engine is identical to and has the sameratings, limitations, and installation interfaces as TCM model IO-550-Bengine. The RAM model IO-550-C-RA is identical to and has the sameratings, limitations, and installation interfaces as TCM model IO-550-Cengine.	17/11/2009	Active	10027805
10027816 (EASA.IM.A.S.03147)	ASSOCIATED AIR CENTER, L.P.	REV. 1	FAA ST10895SC-D	A319-115	Major Change to the EASA STC 10027816 (FAA STC ST10895SC-D)to introducethe Decrane's side facing divan (FAA STC ST01450CH) within the"Executive Style Interior" configuration.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.- CRI D-4301-004/ Deviation 'Installation of Interior Doors'- CRI D-4302-004/Special Condition 'Isolated Compartments'- CRI D-4305-004/ De...	-,,FAA Supplemental Type Certificate ST10895SC-D amended 10th May 2012-,,Master Document List, ref. doc. 2578000000, Revision C, dated 10thMay 2012-,,Airplane Flight Manual Supplement, ref. doc. 2578021090, Revision IR,dated 21st September 2009-,,Instructions for Continued Airworthiness, ref. doc.R...	This approval is limited only to the installation made in Airbus ModelNumber A319-115, Serial Number 3133	11/07/2012	Active	10027816
10027818	GAMA ENGINEERING Ltd.	REV. 2	CAA UK RESPONSIBILITY	PA32 ALL SERIES	Installation of Garmin G500/G600 PFD/ND	CS-23The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.JAA Interim Policies INT/POL/23/1, INT/POL/23/2 and INT/POL/23/3FAA AC 23.1309-1DFAA AC 23.1311-1BFAA AC 23-23AMC 20-115BCRI F85 hasE...	-Master Data List MDL1100-02 Issue 4-Change Statement CS1100-02 Issue 2-Instructions for Continued Airworthiness ICA1100-02 Issue 1-Flight Manual Supplement AFMS1100-02 Issue 4or later revisions of the above listed documents approved by EASA	This change is limited to the configuration defined in Change StatementCS1100-02 Issue 2 or later approved revision.	01/04/2010	Active	10027818
10027820 (EASA.A.S.03974)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		757-200	205 Passenger LOPARev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Master Document List, MDL-11532-00001, Issue 1, 23/10/2009-Modification Summary Sheet, MOD-11532-0001, Issue 1, 23/10/2009or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The STC holder shall submit to the agency before 7th June 2010 finalinstructions of instructions for continued airworthiness on ElectricalWiring Interconnection System (EWIS) in accordance with the specialcondition (H-01).Prior to installation of this change/repair it must be determined thatthe inte...	09/11/2021	Active	10027820
10027822 (EASA.A.S.03734)	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	BAE JETSTREAM 3100	Installation of Satcom System	BCAR DThe Certification Basis for the original product remains applicable tothis certificate/ approval	Cranfield Modification No CaeM/Jetstream/1286Type Design Definition AddendumCA/DD/DR0054 Issue Aor later revisions of the above listed documents approved by EASA	None	09/11/2009	Active	10027822

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027823 (EASA.IM.R.S.01517)	L-3 WESCAM INC.	REV. 1	TCCA STC SH97-31	2. AS355 E, F, F1, F2, N, NP 1. AS350 B, B1, B2, B3, BA, D	MX-Series Camera Installation (Structural Provisions Only)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	FMS02146 revision 3 dated 4 October 2010 - Flight Manual Supplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision) MS02146 revision 6 dated 4 October 2010 - Engineering ModificationSummaryICA0214...	This STC is for structural provisions only. Functional and electricalaspects will require separate airworthiness approval.VNE limited to 126ktsVFR OnlyCategory A operations prohibited	04/01/2011	Active	10027823
10027824	RUAG AEROSPACE SERVICES GmbH			CL-600-2B16	Installation of Honeywell Aircraft Flight Information System (AFIS)	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- RUAG Master Document List No. 078L-MDL Revision N/C dated23/10/2009.- RUAG AFMS No. 078L-AFMS Revision N/C dated 20/10/2009.- RUAG SoC ref. 078L-CN Revision N/C dated 23/10/2009.or later revisions of the above listed documents approved by EASA	None.	09/11/2009	Active	10027824
10027825 (EASA.A.S.03855)	RUECKER AEROSPACE GmbH			B777-200	Installation of 2 single B/E Aerospace DS9000 steam ovens and 2 OCM9000Oven Control Modules per B/E Aerospace Engineering OrderEO-253-00004-001 Rev. D. or later approved revision.	The Certification Basis for the original product remains applicable tothis certificate/ approvalCRI H-01 Enhanced Airworthiness Programme for Aeroplane Systems - ICA onEWIS for oven installation	-B/E Aerospace Aircraft Maintenance Manual Supplement 43208-SM-01-B/E Aerospace Component Maintenance Manual for basic partnumber 4329102	None	09/11/2009	Active	10027825
10027831	NORTHERN AVIONICS S.R.L.			A109S	NAV-396 "Installation of Helicopter Egress Light System (HEEL)"	The Certification Basis for the original product remains applicable tothis certificate.	- RFM Supplement NAV-396 Rev. 0 or later revisions of the above document approved by EASA- Modification Bulletin NAV-396 Rev. 0	None.	09/11/2009	Active	10027831
10027876	BOMBARDIER AEROSPACE		TCCA STC SA09-53 ISSUE 1	CL-600-2B16	Optional Fuel Quantity Display in Kilograms	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/approval.The certificated noise and/or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- TCCA STC No. SA09-53 Issue 1 dated 29 June 2009.- Aero Consulting Services Ltd. Modification Data Summary G336000Revision N/C or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis d...	Not Applicable.	11/11/2009	Active	10027876
10027877 (EASA.A.S.03965)	KUERZI AVIATION AG			LEARJET 55	Installation of Satellite Tracking System SAT-111	As specified in PCP-200931957, rev. A (or later approved revisions)The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificatednoise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval...	As specified in MDL-200931957, rev. N/ Cor later revisions of the above listed documents approved by EASA	None	11/11/2009	Active	10027877

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027883	DOA AESGLOBAL LIMITED	REV. 2		A320-214	Introduction of Rockwell Collins dPAVES IFE SystemRevision of the EASA STC 10027883 to remove EWIS limitationRev 2: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems -ICA on EWIS"The requirements for environmental protection and the ass...	- Modification Summary ref. Modification No. AES-320-1522, Issue 4,dated 21st March 2011- Master Data List, ref. doc. No. AES-320-1522MDL, Issue 4, dated 23rdApril 2010- Project Specific Certification Plan (PSCP), ref. doc. No. AES-TR-0600,Issue 4, dated 12th October 2009- Certification Compliance R...	Not applicable	27/04/2021	Active	10027883
10027884 (EASA.A.S.03796)	BUCHER LEICHTBAU AG	REV. 12		SEE AIRCRAFT ALLOCATION TABLE E043-04-12	16G NGS XL Stretcher P/N 1120030-SeriesMajor Change to EASASTC 10027884 Revision 11 through:-Addition of A319-100N, A320-200N, A321-200N, A321-200NX aircraft to theEASA STC 10027884 Aircraft Allocation Table E043-04-12.-Addition of 737-8,737-9, 737-8200 aircraft to the EASA STC 10027884Aircraft Al...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: for details see below25.1, 25.21, 25.23, 25.25, 25.27, 25.301(a)(b)(c), 25.303,25.305(a)(b)(c), 25.307(a), 25...	-Master Document List E034-03-08 Rev. V dated 03.11.2023-Aircraft Allocation Table E043-04-12 Rev T dated 30.10.2023-User Manual E017-07-09 Rev. 09 dated Nov 01/2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	-Per User Manual E017-07-09- This STC constitutes an approval for installation only for aircraftserial numbers as statedin the Aircraft Allocation Table. Foradditional aircraft serial numbers, the requirements for full compliancehave to bedemonstrated through a design approval.-No electrical / medi...	10/11/2023	Active	10027884
10027889	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 4		EC 120 B	Installation of flight data monitoring and transmitting systemRev -: installation of SafetyPlane / Helicom V1 (PN4400).Rev 1: introduced name change from SafetyPlane to Helicom V1, andinstallation of Helicom V2 NUM (PN4700-E or PN4710-E (Satellite option).Rev 2: introduced installation of Helicom V2...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Lithium Battery Installation (from Rev2 and up).The requirements for environmental protection and the associatedcertified noise and/ or em...	For SafetyPlane/Helicom V1 (P/N4400):- Design Document: N EC120 Design Document E-A-07;- Installation Manual: N EC120 Installation Document E-A-07;- ICA: N EC120 Supplement to Maintenance Manual E-A-O5;- MDL, RF MS: --;For Helicom V2 (PN4700-E or PN4710-E (Satellite option)):- Design Document: N3-EC...	Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any other previously installed change and/ or repairwill introduce no adverse effect uponthe airworthiness of the product.	27/02/2020	Active	10027889
10027890 (EASA.IM.A.S.03272)	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 1	FAA STC SA01376CH	PC-12, PC-12/45, PC-12, PC-12/45 PC-12/47, PC-12/47E PC-12, -45, -47, -47E,	EASA Validation of STC SA01376CHRev. 1: Transfer from "Parker Hanifin Corporation Aircraft Wheel & BrakeDivision" to "Kaman Corporation Aircraft Wheel & Brake Division"	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Airplane Flight Manual Supplement AFMS199-241Airplane Maintenance Manual Supplement AMMS199-241Installation Manual IM 199-241Component Maintenance Manuals: CM 30-244 / CM 40-424	None	25/09/2024	Active	10027890
10027898 (EASA.A.S.03693)	UNIAIR			MF900	Installation of a Flight Data Recorder	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Master Data List Document MDL-019-07 Revision 5, dated 09th October2009-Aeroplane Flight Manual Supplement UAE-AFMS-08-006, Revision 2 dated07th August 2009.-Aeroplane Maintenance Manual Supplement UAE-AMMS-08-002, Revision 2dated 21st September 2009or later revisions of the above listed documents...	This design change is applicable on the basic Mystere Falcon 900aircraft, as per MF900 designation on EASA TCDS.A.062	13/11/2009	Active	10027898

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027900	TELEDYNE CONTROLS, LLC	REV. 2	FAA ST02172LA	747-400, 747-400F 747-300/-400/-400F/-8/-8F 747-200C, 747-200F, 747-300 747-100, 747-200, 747-200B 747-100/-200/-200B/-200C /-200F	Installation of Teledyne Controls Wireless Ground Link - Quick AccessRecorder (WQAR)Rev. 2 adds 747-8/-8F models.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List MDL2243800-747, Revision H, dated 01 October 2021<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/04/2022	Active	10027900
10027902	AERONAUTICAL ACCESSORIES, INC	REV. 1	FAA STC SR01515AT	BELL 407	Expanded Area Instrument Panel	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	AA-97129 revision F dated 28 May 2009 - Drawing List, ExpandedInstrument Panel for Bell Helicopter Textron 407 Model Helicopters;AA97130 revision F dated 18 April 2008 - Installation Instructions forExpanded Instrument panel;AA-02052 revision A dated 30 July 2004 - Instructions for ContinuedAirworth...	None	01/12/2009	Active	10027902
10027904 (EASA.IM.A.S.03184)	FLYHT AEROSPACE SOLUTIONS Ltd.	REV. 4	TCCA STC SA08-7	HAWKER 900XP HAWKER 850XP HAWKER 800XP HAWKER 750	AFIRS 220 / AFIRS 228 Automated Flight Information Reporting SystemInstallation With Optional Global Voice and Global Text SatelliteCommunications.	AFIRS 220 System installation is FAR 25 including Amendments 25-1through 25-97.AFIRS 228 System installation is FAR 25 including Amendments 25-1through 25-97 and FAR 25.981 at Amendment 25-102.	AFIRS 220 System Installation:- Installation of AFIRS 220 system must be in accordance withAeroMechanical Services Ltd ("FLYHT"), Installation Instructions151-0032, Rev. E, Transport Canada (TCCA) approved 18 October 2010, orlater TCCA approved revisions.- Maintenance of AFIRS 220 system must be ina...	None.	29/08/2012	Active	10027904
10027913	AERONAUTICAL ACCESSORIES, INC	REV. 1	FAA STC SR09533RC-D	BELL 407	Vertical Fin Cap with LED Light Kit	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	AA-04133 revision A dated 18 February 2009 - Drawing List, Vertical FinCap with LED Light Kit;AA-97130 revision F dated18 April 2008 - Installation Instructions forExpanded Instrument panel;AA-06111 no revision dated 23 February 2009 - Instructions for ContinuedAirworthiness Vertical Fin Cap with L...	None	01/12/2009	Active	10027913
10027933	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			525A	Upgrade of existing Dual Garmin GTX 330D Transponder Systemfor EHS	The Certification Basis of the original product remains applicable tothis changeThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	EASA approved Engineering Order, Doc. No. 2009-6, Revision A, dated05-Jun-2009, or later approved IssueEASA approved Airplane Flight Manual Supplement, Doc. No. 200968,Revision A,dated 05-Jun-2009, or later approved IssueMaintenance Manual Supplement, Doc. No. 2009-6-10, Revision A, dated05-Jun-200...	None	17/11/2009	Active	10027933

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10027954 (EASA.A.S.03798)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 3		BAE 146 SERIES 200	BAE 146 VIP Cabin Interior /.Revision due to the removal ofthe EWIS limitation on EASA STC 10027954Rev. 1.Rev. 3: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): CRI H-01, “Enhanced Airworthiness Programme forAeroplane Systems – ICA on EWIS”.The requirements for environmental protection and the as...	Master Document List MDL-11193-00001 Issue 4<(>,<)>or laterrevisions of the above listed document (s) approved/ acceptedunder the EASA system.- Modification Summary Sheet MOD-11193-00001 Issue 4.- Master Document List MDL-11193-00001 Issue 4.- Compliance records CR-11193-00001 Issue 2.- Enhanced Zona...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10027954
10027985	DANSK FLY ELEKTRONIK ApS			F172P F172K, F172L, F172M, F172N, F172D, F172E, F172F, F172H,	ASPEN EFD1000 Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appro...	DFE Design order DFE-DO-00372 dated 01-09-2009 including AFMS,Instructions fro Continuing Airworthiness etc.	Not Applicable	23/11/2009	Active	10027985
10027987 (EASA.A.S.03960)	AERODATA AG			B300	Installation of Aerodata Flight Inspection System AD-AFIS-260	The following new Certification Basis is applicable to thischangeCS-23, Amdt. 1, except 23.561 and 23.785 (kept FAR 23.561 and FAR23.785) is elected to comply with for the items affected by the changeThe certificated noise and/ or emissions levels of the original productare unchanged and remain app...	EASA approved Master Document List, Integration of AD-AFIS-260, Doc. No.MDL-A/C-149, Rev. 1, dated 13-Nov-2009, or later approved revisionEASA approved Airplane Flight Manual Supplement, Doc. No. AFM-108, Rev.0, dated 06-Oct-2009, or laterapproved revisionApproved Maintenance Manual Supplement, Doc...	Only applicable for aircraft / preconditions as defined in DesignDescription, Integration of AD-AFIS-260, Doc. No. DES-A/C-887, Rev. 2,dated 19-Oct-2009, or later approved revision	23/11/2009	Active	10027987
10027989 (EASA.A.S.03973)	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			DHC-8-100, -200, -300	Installation of ELT KANNAD 406 AF-COMPACT or ARTEX ME406	CS 25 Amendment 6 as defined in 21A.101(a) has been used instead of TCDSEASA.IM.A.191The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this cert...	A-BALISES406-DHC8; KANNAD DOC08038C; ARTEX 570-1600 Rev. Gor later revisions of the above listed documents approved by EASA	None	24/11/2009	Active	10027989
10028007	DEVORE AVIATION CORPORATION OFAMERICA		FAA STC SR09557RC	R44II	Installation of Tail/Rotor, Forward Facing Recognition and FuselageFloodlights in accordance with DeVore Aviation Corporation DrawingNumber 44000001. This installation is based onFAA STC SR09557RC.	FAR 27 as per EASA TCDSThe Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Flight Manual Supplement DR-708 Rev. IR, dated July 29, 2009DeVore Aviation Corporation Drawing Number 44000001, Revision A, datedJuly 20, 2009.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)Ins...	None	24/11/2009	Active	10028007

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028014 (EASA.A.S.03964)	LAST REFUGE Ltd.	REV. 1	CAA UK RESPONSIBILITY	FR172J, R172K, 182, 206, 208	Approval of Flight Manual Supplements for Last Refuge Ltd Wing Strutmounted camera installation.	BCAR Section K	Flight Manual Supplements:--,,LAST REFUGE Ltd. WING STRUT MOUNTED CAMERA SYSTEM (MARK II) FORCESSNA AIRCRAFT , SUPPLEMENT to CESSNA FR172J Reims Rocket, WITHCONTINENTAL IO-360 210HP, FLIGHT MANUAL, AAE SUPPLEMENT 1, ISSUE 2,dated 20 August 2009-,,LAST REFUGE Ltd. WING STRUT MOUNTED CAMERA SYSTEM (M...	None	25/11/2009	Active	10028014
10028026 (EASA.R.S.01508)	ALIDAUNIA S.R.L.			A109S	BM No. 020/AL/2008 Installation of a "Ginevri" Incubator Type "BabyShuttle Intensive Care"	The Certification Basis for the original product remains applicable tothis certificate/ approval	RFM Supplement No. FMS/ ALI/020 Rev. 0	None	26/11/2009	Active	10028026
10028029	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	PA-34-220T PA-34-200, PA-34-200T,	Installation of Aspen EFD1000 PFD as add on	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	EASA approved Master Document List, Doc. No. MDL1106-01, Issue 1, dated04-Nov-2009, or later approved issueEASA approved Flight Manual Supplement, Doc. No. AFMS1106-01, Issue 2,dated 04-Nov-2009, or later approved issueApproved Instructions for Continued Airworthiness, Doc. No. IAC1106-01,Issue 1, d...	Only applicable for airplanes/ preconditions as defined Section 1.1,"Installation planning" of Doc. No. CS1106-01, "Change Statement", Issue2, or later approved issueFor approved Software Level of Aspen EFD1000 refer to "Limitations,Conditions, Exemptions" of Doc. No. CS1106-01, "Change Statement"	26/11/2009	Active	10028029
10028068 (EASA.A.S.03732)	SCANDINAVIAN AVIONICS DESIGN ApS			650 (CITATION VII)	Software upgrade of installed Honeywell GNS-XL or GNX-XLS FMS system forP-RNAV operation	CS 25 amendment 4The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Engineering Order 2050529-EO Issue 2 from 27 November 2009List of STC documents "2050529 STC" issue 2 from 27 November 2009AFM Supplement 2050529-AM-A issue 2 from 27 November 2009 for GNS-XL FMSAFM Supplement 2050529-AM-B issue 2 from 27 November 2009 for GNS-XLSFMSDeclaration of Compliance from 27...	Limited to: S/N 650-7001 thru 650-7119This STC applies onlyfor Single or Dual FMS GNS-XL or GNS-XLSconfiguration, approved for B-RNAV operation. Intermixing with other FMSis not approved within this STC.	30/11/2009	Active	10028068
10028069	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	182 SERIES	Installation of Aspen EFD1000 PFD	CS-23The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalJAA Interim Policies INT/ POL/23/1, INT/POL/23/2 and INT/ POL/23/3FAA AC 23.1309-1DFAA AC 23.1311-1BFAA AC 23-23AMC 20-115BAMC 20-4AMC...	Master Data List MDL1119-01Change Statement CS1119-01Instructions for Continued Airworthiness ICA1119-01Flight Manual Supplement AFMS1119-01 Issue 1or later revisions of the abovelisted documents approved by EASA	None	30/11/2009	Active	10028069
10028070 (EASA.A.S.03815)	SABENA TECHNICS BOD	REV. 8		A340-311/-312/-313	IAGOS ModificationThis STC installs the Integration of routine Aircraft measurements intoa Global Observing System. TheInitial Release of the STC was approvingthe technical provisions installing the IAGOS system.This Revision 1 approved the activation of the IAGOS system, andupdating some of the li...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Approval Sheet, ref. : S-00-2071, Issue 9 dated 26 February2014Aircraft Flight Manual Supplement, ref : AFM-S-F4030-01 Rev 04, dated 07October 2013Instruction for Continued Airworthiness, ref : ICA-F4030-00-01 issue B,dated 30May 2011or later revisions of the above listed documents app...	The modification is applicable to the following aircraft Serial Numbers:MSN 221, 304, 327, 335, 347, 352, 354, 355, 377, 379, 390, 433, 434, and447Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installeda...	27/02/2014	Active	10028070

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028083 (EASA.A.S.03930)	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			35A	Installation of Artex ELT C406-02 (Cobham).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.As specified in Certification Program 900-080, rev. A (or later approvedrevisions).The certificated noise and/ or emissions levels of the...	As specified in MDL 900-049, rev. Aor later revisions of the above listed documents approved by EASA	None.	01/12/2009	Active	10028083
10028084 (EASA.A.S.03936)	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			L35A	Installation of ART 2000 Weather Radar with KMD 850 MFD (Honeywell).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.As specified in Certification Program 912-080, rev. A (or later approvedrevisions).The certificated noise and/ or emissions levels of the...	As specified in MDL 912-049, rev. Aor later revisions of the above listed documents approved by EASA	None.	01/12/2009	Active	10028084
10028085 (EASA.A.S.03933)	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			35A	Installation of SSFDR F1000 (L-3 Communications).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.As specified in Certification Program 848-080, rev. A (or later approvedrevisions).The certificated noise and/ or emissions levels of the...	As specified in MDL 848-049, rev. Aor later revisions of the above listed documents approved by EASA	None.	01/12/2009	Active	10028085
10028086 (EASA.A.S.03932)	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			35A	Installation of EGPWS Mk VIII (Honeywell).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.As specified in Certification Program 911-080, rev. A (or later approvedrevisions.The certificated noise and/ or emissions levels of thea...	As specified in MDL 911-049, rev. Aor later revisions of the above listed documents approved by EASA	None.	01/12/2009	Active	10028086
10028088 (P-EASA.A.S.03931)	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			LEARJET 35A	Installation of CVR-30B (UASC).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.As specified in Certification Program 851-080, rev. A (or later approvedrevisions).The certificated noise and/ or emissions levels of the...	As specified in MDL 851-049, rev. Aor later revisions of the above listed documents approved by EASA.	None.	01/12/2009	Active	10028088
10028092	PATS AIRCRAFT L.L.C.	REV. 1	FAA ST00405LA-D	737-700 IGW	Alteration of Fire Protection Systems, Lower Cargo Compartments.This STC revises and supersedes LBA STC LBA. 21NE1.TA0682. The revisionwas issued to reflect the transfer from Hollingshead International toDecrane Aerospace PATS Aircraft.Rev 1: Added reference to MMEL Supplement	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- CRI A-01, B737-700, Issue 9, 13 February 1998.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are...	Hollingshead Master Data List 12106 Rev. M dated August 01,2002FAA Airplane Flight Manual Supplement 20629 Rev. NCInstructions for Continued Airworthiness 20689 Rev. CMMEL Supplement TM-8110-MMEL Rev. G dated 03 March 2021Or later revisions of the above listed document(s) approved/ accepted onbehalf...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/04/2021	Active	10028092

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028093	PATS AIRCRAFT L.L.C.	REV. 2	FAA ST01184LA	737-800	Alteration of Fire Protection Systems, Lower Cargo Compartments.Rev. 0: This STC revises and supersedes LBA STC LBA.21NE1.TA0511. Therevision was issued to reflect the transfer from HollingsheadInternational to Decrane Aerospace PATS Aircraft.Rev. 1 adds an additional metered fire bottle to both the...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Configuration 1 per MDL 2554-01, Rev E, dated 12 June 2001- Configuration 2 per MDL 2544-01, Rev G dated 14 October 2008- Configuration 3 Non-ETOPS Converted Freighters per MDL 2544-01, Rev Kdated 22 July 2020 and Configuration Matrix 8149-26-CFGX-001 Revision Bdated 21 August 2020- Configurationd...	Configuration 1 - NoneConfiguration 2 - NoneConfigurations 3 & 4 - installation of FAA STC ST02690LA (Freighterconversion) is a prerequisite. STC ST02690LA must be EASA-validated toallow the aircraft registration in Europe.Prior to installation of this change/repair it must be determined thatthe int...	13/04/2021	Active	10028093
10028096 (EASA.A.S.03901)	MT-PROPELLER ENTWICKLUNG GmbH			MXT-7-180, MXT-7-180A MX-7-180, MX-7-180 A, MX-7-180 B, MX-7-180 C,	Installation of a 2-blade MTV-15-B/203-58 propeller on Maule M-4 ModelsMX-7-180, MX-7-180A, MX-7-180B, MX-7-180C, MXT-7-180, and MX-7-180A	FAR-23The Certification Basis for the original product remains applicable tothis certificate/ approvalThis certificate/approval involves a change to the certificated noiseand/ oremissions levels	-Airplane Flight Manual Supplement E-1780, Original Issue dated 09.September 2009 or later approved revision-Instruction for Continued Airworthiness E-1782, Original Issue dated09. September 2009 or later approved revision-Installation Instruction E-1781, Original Issue dated 09. September2009or lat...	None	01/12/2009	Active	10028096
10028097 (EASA.IM.A.S.03269)	S-TEC CORPORATION		FAA STC SA5357SW-D	PA-28-201T PA-28-181, PA-28-236, PA-28-151, PA-28-161,	Installation of S-TEC Manual Electric Trim System, Model ST-156 (14 VoltSystem)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Applicable revisions:-FAA Approved S-TEC Bulletin No. 256, dated 21-Nov-84, Initial Issue, orlater revision-FAA Approved S-TEC Master Drawing List No. 92306, dated 21-Nov-84,Initial Issue, or later revision-FAA Approved Supplement to Pilot's Operating Handbook and/or FAAApproved Airplane Flight Manu...	Compatibility of this modification with other previously approvedmodifications must be determined by the installer.The Approval of the installation of this system is not applicable tospecific aircraft having other previously approved modifications, unlessit is determined by the installer that the in...	01/12/2009	Active	10028097
10028110	JET AVIATION AG			GULFSTREAM GV	Mid Cabin Door	CS-25The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Master Data List BGLF525001-001 Rev. AAirplane Flight Manual Supplement BGLF525001-201-01 Rev. IRInstructions for Continued Airworthiness BGLF525001-150-01 Rev. Aor later revisions of the above listed documents approved by EASA	None	11/12/2009	Active	10028110
10028128 (EASA.A.S.03435)	LUFTHANSA TECHNIK AG			A330-243	A330-200 - VIP Cabin Interior Completion	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalSupplemental TypeCertification Basis CRI A-01 for P-EASA.A.S.03435The certificated noise and/ or emissions levels of the original product...	-Supplemental Type Definition Document, ref. Doc. No. STDD00-08/02M,issue 01, revision 00, dated 16 November 2009<(>,<)>-Aeroplane Flight Manual Supplement ref.Doc. A-00-09/009-AFM issue 5,revision IR dated 12. November 2009<(>,<)>-Instructions for Continued Airworthiness, ref. Doc. No.A-00-09/009-I...	as per AFMS A-00-09/009-AFM issue 5 as listed in the associatedtechnical documentation	03/12/2009	Active	10028128

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028136	SAVANNAH AIR CENTER, L.L.C.		FAA STC ST03818AT	BOMBARDIER BD-700-1A10	Complete Custom Aircraft Interior - ASN 9287.	EASA IM.A.009 and EASA MOC CRI F-01The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levelsof the original productare unchanged and remain applicable to this certificate/ approval.	FAA STC No. ST03818AT dated 29 October 2009.FAA SoC ref. ST03818AT dated 30 November 2009.Savannah Air Center Master Drawing List, XRS9287-MDL-2500001, Rev Adated 14 October 2009 or later approved revision.Instructions for Continued Airworthiness, Bombardier Global ExpressDocument Number XRS9287-ICA...	Restricted to ASN 9287 for a total of 15 passengers.	04/12/2009	Active	10028136
10028137 (EASA.A.S.03954)	MOTORFLUG BADEN-BADEN GmbH	REV. 4		P.180 AVANTI II	Operator Seat and Additional Changes (Revision 2 to EASA STCNo. 10028137)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, 1st issueCS23.301, 23.303, 23.305, 23.307, 23.321, 23.341, 23.561, 23.562 (seatonly), 23.575, 23.601, 23.603, 23.605, 23.607, 23.609, 23.611, 23.613,23.625, 23.853,...	- Aircraft Flight Manual Supplement 281F93072-0601, Rev. 7or later revisions of the above listed documents approved by EASA.- Instructions for Continued Airworthiness 281F93072-0701, Rev. 6- Installation Manual 28145F133028-1001, Rev. 1	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	11/11/2013	Active	10028137
10028151	RUAG AEROSPACE SERVICES GmbH	REV. 1		EMB-135BJ	AXE4-869/2009-mk (297A-RFC): Electronic Flight Bag	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCert Basis per TCDS IM.A.032 plus:-CRI H-1/1324 "EWIS"-CRI F-28/1324 "EFB"Thecertificated noise and/ or emissions levels of the originala...	- Master Document List 297A-MDL Rev. B dtd. 7.5.2010- AFM Supplement 297A-AFMS Rev. N/C dtd. 23.10.09- AMM Supplement 297A-AMMS Rev. A dtd. 7.5.2010or later revisions of the abovelisted documents approved by EASA	None.	30/06/2010	Active	10028151
10028164 (EASA.IM.R.S.01555)	AKV, Inc.	REV. 1	FAA STC SR00631DE-D	MBB-BK117 C-2 MBB-BK117 B-2, MBB-BK117 C-1 MBB-BK117 A-4, MBB-BK117 B-1 MBB-BK117 A-1, MBB-BK117 A-3	Dual Engine Cycle Counter.Installation of AKV, Inc. Dual Engine Cycle Counter BK1172XCC systemused to accrue engine cycles by coupling to the existing engine speedsignals for gas producer and free turbineNote: The recommendation for approval is given based on a reviewperformed in accordance with the...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. AKV Inc. Master Data Index MDI 711-9049 Rev. C, dated 13.10.2008, FAAapproved 06.04.2009 or later FAA approved revision.2. Flight Manual Supplement: RFMS 080-0401, Rev. B, FAA approved13.08.2008 or later approved revision.3. Installation Instructions and Instructions for ContinuedAirworthiness: R...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Re-location of the equipment due to installation of the...	13/09/2018	Active	10028164
10028167	STANDARD AERO		FAA STC ST01991CH	MF50	EASA Validation of FAA STC ST01991CHInstallation of an L3 Communications (Fairchild) Model F1000 Flight DataRecorder (FDR) System in accordance with Garrett Aviation ServicesDrawing List, Doc. Number 1002382 Revision H, dated 04th June 2004 orlater revisions approved by EASA in accordance with EASA2...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Garrett Aviation Services Drawing List, Doc. Number 1002382 Revision H,dated 04th June 2004-Aeroplane Flight Manual Supplement, Garrett Aviation Services Doc. No.1002752, Revision A, originally approved 03rd June 2004-Airworthiness Limitations Garrett Aviation Services Doc. No. 1002750,Revision B,o...	None	07/12/2009	Active	10028167
10028171	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE	REV. 1	FAA STC SR02244LA	MBB-BK117 C-2, MBB-BK117 D-2	Installation of Emergency Float Kits.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	FAA approved Apical Industries, Inc. Master Document List MD145-1,Revision B, dated 29 June 2009, or later FAA approvedrevision.Rotorcraft Flight Manual Supplement RFMS145-1, Revision N/C, approved on20 July 2009 or later FAA approved revision.	This approval requires the inspections and overhaul schedules to beperformed as mandated by Apical Industries, Inc. dbaDart Aerospace'sInstructions for Continued Airworthiness asfollows:- MBB-BK 117 C-2 with P/N 646.4100 series installed:Document ICA145-1 Instructions for Continued Airworthiness,N...	24/05/2018	Active	10028171

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028181	BOMBARDIER INC.		TCCA STC SA05-60	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9231	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	TCCA STC No SA05-60 Issue 1 dated 14 June 2005.TCCA SoC refC-09-1021 dated 2 December 2009.Aero Consulting Services Ltd. Configuration Definition List E025000Revision CC.Aero Consulting Services Ltd. Airplane Flight Manual SupplementG-FM25004501 Revision N/C or later approved revision.GC92310000-IF...	Restricted to ASN 9231	07/12/2009	Active	10028181
10028197 (EASA.A.S.03875)	AVIONIK STRAUBING ENTWICKLUNGS GmbH			B. B90, C90, E90, H90 A. C90A, C90GT, C90GTI	Installation of an FMS System Universal UNS-1Lw and an EGPWS KGP 560	CS-23 Amdt. 1The Certification Basis for the original product remains applicable tothis certificate/ approvalThe Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalThe certificated noise and/ o...	-Instructions for Installation ASR-2009-031-IFI-10-00-AFM-Supplement ASR-2009-031-FMS-05.1-00 (UNS-1Lw)-AFM-Supplement ASR-2009-031-FMS-05.2-00 (KGP 560)-Instructions for Continued Airworthiness ASR-2009-031-ICM-11.1-00(UNS-1Lw)-Instructions for Continued Airworthiness ASR-2009-031-ICM-11.2-00 (KGP5...	None	08/12/2009	Active	10028197
10028200	ISEI			R44, R44 II	Title: Installation of Safetyplane EquipmentDescription: Installation of a system for tracking a set of flight andsystem parameters during operation of the rotorcraft. The modificationis based on ISEI change N-R44 as defined in the Master Document ListN1-R44-Reference Documents-E-A-02, dated 19.11.2...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Installation Instructions, N6-R44-Installation Document E-A-02-Instructions for Continued Airworthiness, N7-R44-Maintenance manualsupplement E-A-02-N2-R44-Approval Change Document E-A-02- N3-R44-Experience Feedback E-A-02- N4-R44-Safety Assessment document E-A-02- N5-R44-Design Document E-A-02or...	None	08/12/2009	Active	10028200
10028206 (EASA.R.S.01586)	SCANDINAVIAN AVIONICS DESIGN ApS			R22 BETA	Title: Camera with supportDescription: Optional Installation of a camera turret, related recorderand data link transmitter system in accordance with Master Document List2053852 DOC issue 2, dated 04.12.2009. The installation is based onScandinavian Avionics change no. 2053852	CS27 Amdt. 2The certificated noise and/ or emissions levelsof the original productare unchanged and remain applicable to this certificate/ approval	- POH Supplement Robinson Model R22 Beta Doc. 2053852-AM Iss. 2or later revisions of the above listed documents approved by EASA- Instructions for Continued Airworthiness 2053852-CA, Iss. 1 or laterrevision,,- Installation Instructions 2053852 STC Iss. 1 or later revision	- S/N 0501 and subsequent,,- Pitot heat and Search Light must not be installed,,	10/12/2009	Active	10028206
10028207 (EASA.A.S.03152)	AERODISA S.L.	REV. 1		FALCON 2000	Pocket Door Installation for Falcon 2000In accordance with Aerodisa Master Data List AED2007-09M_MDL Revision 3,dated 04th December 2009 or later revisions approved by EASA	EASA CS25 amendment 1 plus EASA Certification Review Item (CRI) D-01Issue 02 "Installation of Interior Door" for thoseareas, systems,parts and appliances of the original Falcon 2000 design affected by thisdesign change.The certificated noise and/ or emissions levels of the original productare unch...	- Aerodisa Master Data List AED2007-09M_MDL Revision 3, dated 04thDecember 2009.- Aeroplane Flight Manual Supplement, AED2007-09M_AFMS Revision 01,dated 24th June 2009- Weight andBalance Supplement AED2007-09M_W<(>&<)>B Revision 00, dated03rd April 2009.Applicable revisionsEASA:"or later revisions...	Design Change limited to Falcon 2000 aircraft serial number55	21/12/2009	Active	10028207

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028220	NSE INDUSTRIES S.A.	REV. 2		2- 206 1- U206E, U206F, U206G 1- U206A, U206B, U206C, U206D 1- TU206E, TU206G, TU206F 1- TU206C, TU206D 1- TU206A, TU206B, 1- TP206C, PT206D, TP206E 1- TP206A, TP206B 1- P206C, P206D, P206E, T206H 1- 206H, P206, P206A, P206B	STC 10028220 revision 2 for STC DTS and DTS-V2 Cessna 206 - InstallationTracking System,Description: Change of Corporate Name and location, replacement of DTSV2documentation reference, addition of TCDS USA A4CE to reflect all modelslisted,incorporation of MC 1004126 and remove of associated technic...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:FAR 23 Amdt 0-50The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	SDL-DTSV2-C206 Rev.00 dated 20/06/2013AFMS-DTSV2-C206 Rev.00or later revisions of the above listed documents approved by EASA	The approval holder shall fulfill the obligations of Part 21, Paragraph21A.109.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the a...	05/08/2013	Active	10028220
10028237 (EASA.A.S.03898)	VAN RIEMSDIJK ROTTERDAM B.V.			B747-400F	NXE-0506 Special Cargo Container 125” X 196” with part number 136.020.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	W<(>&<)>B Control and Loading Manual supplement RRM510 Issue 2CMM/IPL NXE Cool Container 136.020 doc. Nr RRM510 Issue 1or later revisions of the above listed documents approved byEASA.	The location of the cargo container is limited to the positionsmentioned in the W<(>&<)>B Control and Loading Manual supplementRRM510.	10/12/2009	Active	10028237
10028238 (EASA.A.S.03774)	LUFTHANSA TECHNIK AG	REV. 1		A318-112	A318-112 - Elite 11 - VIP Cabin Completion	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA SupplementalType Certification Basis CRI A-5301-006 Issue 1- plus voluntarily by applicant:,, FAR 25.981 (a) (b) Amdt. 102 FAR 25....	- Supplemental Type Definition Document , ref. Doc. No STDD00-09/01M,issue 02, dated Apr. 23/ 2010- Airplane Flight Manual Supplement, ref. Doc. No. A-00-09/053-AFMiss.04 rev.01, dated Nov. 25/ 2009- Instructions for Continued Airworthiness, ref. Doc. No.A-00-09/053-ICA, issue 04, dated Mar. 30/ 201...	Not applicable	26/04/2010	Active	10028238
10028245 (EASA.A.S.03961)	SOCATA SAS	REV. 2		TBM 700 N	Installation of a Honeywell HF KHF 1050 communication system on aircraftTBM 700 N equipped with Garmin 1000 Glass Cockpit System - Update forICA inclusion	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-Daher-Socata A/S Instructions for Continued Airworthiness ref.Z00.DMNSTC01PEE0R0, original issue dated July 2010-Daher-Socata A/S Modification File No STC. 23.001.09, edition 1, dated09/12/2009or later revisions of the above listed documents approved by EASA	None	26/08/2010	Active	10028245
10028267	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03740AT-D	GV-SP	Aircraft Serial No 5246 completion and cabin interior installation.	JAR 25The Certification Basis for the original product remains applicable tothis certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation MasterDrawing List No. GC52 2046159, Revision B, datedNovember 30, 2009, orlater approved revisions.Operation to be in accordance with Gulfstream Flight Manual SupplementGC52 204M047, Original Release, dated December 7, 2009, or later...	GV-SP Serial No. 5246 Only.	14/12/2009	Active	10028267
10028268 (EASA.IM.A.S.03109)	DASSAULT FALCON JET - WILMINGTONCORP		FAA STC ST01795NY-D	F900EX	EASA Validation of FAA STC ST01795NY-DInstallation of Decrane Aircraft Seating Company, Inc, Model 80A42S2three place partial berthing divan installation in accordance withDassault Falcon Jet-Wilmington Master Drawing List, 197900904 RevisionB, dated 29th May 2008 or later revisions approved by EASA...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Instructions for Continued Airworthiness (ICA) 197900902, dated 18thApril 2008.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision2004/04/CF (or subsequent revisions ofthis decision)	This design change is applicable to Dassault Aviation Mystere Falcon 900aircraft which have previously been equipped with Dassault AviationModification M3000 (Falcon 900EX definition)	14/12/2009	Active	10028268

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028296 (EASA.A.S.03978)	STIRLING DYNAMICS GMBH	REV. 4		ERJ170-200STD, ERJ170-200LR ERJ170-100STD, ERJ170-100LR	Installation of a removable stretcherRev. 4: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:EASA CS-25 Amdt. 6The requirements for environmental protection and the associatedcertified noiseand/ or emissions levels of the original product areunchange...	Engineering Order: BUE170-EO-0001-01-01, Issue 01Master Drawing List: BUE170-CS-2520-05-01, Issue 01Installation Instructions: BUE170-TO-0001-01-01, Issue 01Continued Airworthiness Document: BUE170-CS-2520-02-01, Issue 01User Manual: BUE170-CS-2520-01-01, Issue 01or later revisions of the above list...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2022	Active	10028296
10028304 (EASA.IM.A.S.03267)	KNOTS ACQUISITION LTD.			PA-32R-301T PA-32-301 T, PA-32R-301, PA-28-RT-201T, PA-32-301 PA-28R-201T, PA-28RT-201, PA-28-236, PA-28R-201 PA-28-181, PA-28-201T, PA-28-151, PA-28-161,	Piper Wing Tips with Landing / Recognition Lights	CS-23.B NSC	Installation instructions as listed on AML-SA2356NM issued 2008-08-14 orlater FAA approved revision.	None	16/12/2009	Active	10028304
10028318	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA TCDS T00001SE	B777-200	Installation of SafTGlo, Inc photoluminescent floor proximity emergencyescape path marking system	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	FAA STC ST03684ATSTG report AC37-2 Master Drawing List rev.DAFM supplement AC37-11 dated May 5, 2009-12-16 Instructionfor ContinuedAirworthiness AC37-20 dated March 16, 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequen...	None	17/12/2009	Active	10028318
10028319 (EASA.A.S.03500)	AIRBUS S.A.S.	REV. 3		A319-115	ACJ Centre Modification CJ0300 - "VIP Cabin Interior - ALF"ACJ Centre Modification CJ0392 - "Private to Public Conversion"-,,Correction of design defect identified: use of additional seatingpositions during TTOL	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:General CRI G-4110 "ACJC Project Certification Basis"The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origin...	Modification Approval Sheet CJ0300, Issue 5, "Top Modification ALF",dated 04/07/2014Modification Approval Sheet CJ0392,Issue 2, "Conversion Private toPublic", dated 05/12/2013Airplane Flight Manual - FM-S MOD CJ0300, Rev. 3, dated 01/07/2014Maintenance Planning Document - MPD-S MOD CJ0300, dated 01...	The approval is limited to MSN 3243Operations under EU-OPS are possible after the application of theConversion Instruction CI 00CJ002 (Aircraft in Public Configuration)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any other...	04/07/2014	Active	10028319
10028330 (EASA.A.S.03956)	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	BEECH 200	Design data to provide European approval of FAA STC: SA5254NM	IM.A.277The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAA AC.23.1309-1CFAA AC.23.1311-1BINT/POL/23/1INT/POL/23/3The certificated noise and/ or emissions levels of the original producta...	Master Data List TAL-TAD 014/09 Rev B.Instructions for Continued Airworthiness ICA 01409 Rev B.Flight Manual Supplement01409 Rev Aor later revisions of the above listed documentsapproved by EASA	Serial number BB-877 only	17/12/2009	Active	10028330

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028331	S-TEC CORPORATION		FAA STC SA09401AC-D (ST-853)	402A, 402B, 402C 401, 401A, 401B	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-853 (28 Volt System)	The Certification Basis for the original product remains applicable tothis certificate/ approval	Applicable revisions-FAA Approved S-TEC Bulletin No. 953, dated 08-Mar-99, Initial Issue, orlater revision-FAA ApprovedS-TEC Master Drawing List No. 921151, dated 08-Mar-99,Initial Issue, or later revision-FAA/DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 8918...	Compatibility of this modification with other previously approvedmodifications must be determined by the installer.The Approval of the installation of this system is not applicable tospecific aircraft having other previously approved modifications, unlessit is determined by the installer that the in...	17/12/2009	Active	10028331
10028338	FLYING COLOURS CORP.	REV. 2	TCCA LSTC C-LSA09-326/ D	CL-600-2B19	Installation, Complete Custom Aircraft Interior	EASA.IM.A.023The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASACRI No H-01The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of...	TCCA LSTC No. C-LSA09-326/D Issue 1 dated 24 November 2009.Aero Consulting Services Ltd. Modification Data Summary G288000 RevisionG.Flying Colours Corp. Airplane Flight Manual Supplement for the CompleteCustom Aircraft Interior G288091 Revision NC or later approvedrevisions.Flying Colours Corp. Ins...	Restricted to ASN 8092	14/12/2011	Active	10028338
10028342 (EASA.IM.A.S.03206)	LEARJET Inc.	REV. 1	FAA STC ST01255LA-D	BD-100-1A10 (CHALLENGER 300)	Installation of a Baseline Executive Interior.Validation ofFAA STC ST01255LA-D (-2 Configuration)Revision of the EASA STC 10028342 to include -2 Configuration	Certification Basis as per EASA TCDS IM.A.080 Issue 2, 8th October 2008plus:The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI D-07 Issue 2 (Deviation) Personal Injury Criteria of Side-...	- FAA STC ST01255LA-D issued 20th December 2003- Master Drawing List ref. doc. HC200065000 Revision U (-2Configuration), dated 16th September 2004-Airplane Flight Manual Supplement ref. doc. H-FM25285002, Revision A,dated 29th July 2004orlater revisions of the above listed documents approved by EA...	Not Applicable	15/03/2010	Active	10028342
10028344	BOMBARDIER INC.			BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9320	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Transport Canada SoC reference C-09-0275 dated 09 December 2009.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionDQ dated 08 December 2009.Instructions for ContinuedAirworthiness GC93200000-IFCA.or later revisions of the abov...	Restricted to ASN 9320 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).3. Prior to installation of this modification the installer mustdetermine that the interrelationship between this modificationo...	18/12/2009	Active	10028344
10028350	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special Transports / Transports SpeciauxThis STC, ref. ST25MOD020 ed.01 (Applicant reference), has beendeveloped, reviewed, tested and found compliant with the CertificationBasis to deal with non-Airbus sub-assemblies transport. On case bycasebasis, this STC had to be amended to cover any new non-A...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalas per EASA TCDS A. 014 + CRI F-06 Issue 01The certificated noise and/ or emissions levels of the original productare unchanged and remain...	Change Approval Sheet, ref: ST25MOD020<(>,<)> Issue 49	None	18/12/2009	Active	10028350

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028355	DV AVIATION, Inc.DBA NORTHPOINT AVIATION	REV. 3	FAA STC SA01985SE	206H, T206H, U206G, TU206G 206H, T206H	Installation of New Rear Observation Seat in Textron 206Rev. 3: Transfer from "Fifty-Ten-Yankee, LLC" to "DV Aviation, Inc.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Soloy, LLC Master Drawing List 910-100, Rev. N, dated 23 August 2012-Service Instruction No. 910-01, dated 19 March 2009.	Weight and Balance:Equipment RemovedItem,,Weight (lb),,Station(in)Seat, 2nd Row (2 Seats),,57,,78.0Seat, 3rd Row (Bench),, 36,,105.2Equipment InstalledItem,,Weight (lb),,Station (in)Seat Assembly with Armrests,,34.0,,81.7Base Plate Assembly,, 23.2,,81.9Swivel Plate Assembly,,25.3,,81.5Seat Rail Attach...	14/06/2023	Active	10028355
10028359 (EASA.A.S.03791)	AMAC AEROSPACE SWITZERLAND AG	REV. 1		A320 MODELS	Humidification and Zonal Dryer System Installation(see project description document PD-AA3201-2100)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Master Data List doc. No MDL-A3201-2100-1 Rev D dated 25/02/2010-Instructions for Continued Airworthiness doc. No ICA-A3201-2100 Rev Cdated 24/02/2010-Declaration of Compliance Form AA-DO-77 - Rev B dated 03/03/2010 withreference to Master Data List MDL-A3201-2100-1 Rev Dor later revisions of the a...	According to doc. No ICA-A3201-2100 as listed under associated technicaldocumentation	04/03/2010	Active	10028359
10028361	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA05-60	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9353	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.-TCCA SoC ref C-09-0926 dated 15 December 2009.-Aero Consulting Services Ltd. Configuration Definition List E025000Revision CF.-Aero Consulting Services Ltd. Airplane Flight Manual SupplementG-FM25004501 Revision N/C or later approved revision.-GC9353...	Restricted to ASN 9353	21/12/2009	Active	10028361
10028365 (EASA.A.S.03792)	AMAC AEROSPACE SWITZERLAND AG	REV. 1		A320-232	Interior Outfitting(see project description document PD-AA01-2500-1)The limitation for use of Supplemental Water Tanks has been removed atRev. 1 of EASA STC 10028365.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA SupplementalType Certification Basis CRI A-2301-001 Issue 2The certificated noise and/ or emissions levels of the original productar...	-Master Data List doc. N° MDL-AA01-2500-1 Rev E dated 05/01/2010-Instructions for Continued Airworthiness doc. N° ICA-AA01-2500 Rev Cdated 17/12/2009-Airplane Flight Manual Supplement doc. N ° AFMS-AA01-2500-1 Rev A dated04/12/09-Declaration of Compliance Form AA-DO-77 Rev A dated 08/01/10 withrefere...	Restricted to MSN 3379	08/01/2010	Active	10028365
10028366 (EASA.A.S.03910)	MAGNETIC MRO AS	REV. 3		A320-232	Installation of Galley G1 and Galley G5.Revision of the EASA STC to remove EWIS limitation.Revision: Transfer of Certificate to Magnetic MRO AS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI H-01/SC H-01 "Enhanced Airworthiness Programmefor Aeroplane Systems- ICA on EWIS"The requirements for environmental protection and the associatedcertified noise and/u...	- Drawing & Document Control Report doc. No. 09DC089, dated21/12/2009- Drawing & Document Control Report doc. No. 09DC090, dated 21/12/2009- Declaration of Design and Performancedoc. No. 09DD301, Issue B, dated18/12/2009-Declaration of Design and Performance doc. No. 09DD302, Issue B, dated18/12/...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/09/2019	Active	10028366

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028374 (EASA.IM.A.S.03246)	CANARD AEROSPACE CORPORATION	REV. 1	FAA STC ST01331CH	DHC-8-201, DHC-8-202	Installation of Honeywell Mark VII Enhanced Ground Proximity WarningSystem to replace the existing Mark II Ground Proximity Warning System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with Canard Aerospace DocumentControl Drawing No. 40094, Revision O, dated December 12th, 2012Operation must be performed in accordance with FAAapproved AirplaneFlight Manual Supplement, Canard AerospaceNo. 34-3250-24, Revision A,dated September 24th, 2012Mainten...	Electronic Flight Information Systems (EFIS) symbol generator upgradedto Part Number (PIN) 7004544.314 in accordance with Honeywell ServiceBulletin (SB) 7004544.34-48 (modification BC) is required prior to, orconcurrent with, accomplishment of this modification.EFIS display controller updated to PIN...	26/03/2013	Active	10028374
10028376 (EASA.IM.R.S.01543)	AERO DYNAMIX, Inc.		FAA STC SR09480RC	MD900	Installation of Night Image Vision System (NVIS) / Night Vision Goggles(NVG) Cockpit lighting.Validation of FAA STC SR09480RC.	JAR27 1st amendmentThe certificated noise and/ or emissionslevels of the original productare unchanged and remain applicable to this certificate/ approval	-Aero Dynamix, Inc. Master drawing list MDL 1775-01, Revision M, dated21 September 2009, or later approved revisions (*)-Aero Dynamix, Inc. Instructions for continued airworthiness (ICA),document No. ICA MD900-01, Revision N, dated 22 December 2009, or lateraccepted revisions (*)-Rotorcraft Flight M...	Refer to applicable RFMS for list of equipment mandatory for NightVision Image System certification	23/12/2009	Active	10028376
10028392	EJM AEROSPACE SERVICES		FAA STC ST02531AT	B747-400	Installation of a Matsushita Avionics Systems Corporation System 3000In-Flight Entertainment system on a Singapore Airlines Boeing 747-400type aircraft in accordance with Master Drawing List MDL10270, Rev. G,dated 06 June 2003 or later FAAapproved revision.Validation of FAA STC ST02531AT	The Certification Basis for the original product remains applicable tothis certificate/ approval	MAS Document Nr. 14526007 Rev E Instructions for Continued Airworthinessfor MAS Corp System 3000 IFEMAS Document Nr. 14526003 Rev. IR Airplane Flight Manual Supplement forMAS CorpSystem 3000 IFEor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004...	Not Applicable	04/01/2010	Active	10028392
10028394	MOTORFLUG BADEN-BADEN GmbH	REV. 1		PIAGGIO P.180 AVANTI II	Upgrade of TCAS-4000 to Software Change 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Master Document List (MDL)281F93887-0109 Rev. 1, and Installation Manual 281F93887-1001Rev. 1< (>,<)>Operation in accordance with AC Flight Manual Suppl. (AFMS) 281F93887-0601 Rev. 0< (>,<)>Instructions for Continued Airworthiness. (ICA) ref 281F93887-0701 Rev.0<(>,<)>F...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/01/2016	Active	10028394
10028415 (EASA.A.S.03966)	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 1		A320-232	Interior Reconfiguration and In Flight Entertainment (IFE) Installationon Etihad Airways A320-232 AircraftRevision of the EASA 10028415 to remove EWIS limitation	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The...	- NAT Certification Summary, ref. doc. N0340-D90, Revision -, dated 5thJanuary 2010- NAT Master Drawing List, ref. doc.N0340-D10, Revision E, dated 1stApril 2010- NAT EAPAS/FTS ICA document, ref. doc. N0340-D10-D79, Revision -, dated2nd June 2010or later revisions of the above listed documents appr...	None	05/08/2010	Active	10028415

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028416	BOMBARDIER INC.	REV. 2	TCCA STC SA04-113	BD-700-1A10	Modification to install the Fwd Pocket door and Mid Pocket door on aseparate circuitInstallation, Complete Custom Aircraft Interior - Revision to EASASupplemental Type Certificate10028416 to incorporate missing drawingson the MDL - ASN 9329	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-EASA STC No. 10028416 Rev. 1 dated 3 February 2010-Transport Canada SoC reference C-10-0158 dated 17 May 2010.-TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.-Aero Consulting Services Configuration Definition List D954000 RevisionEG dated 09 April 2010.-Instructions for Continued Airworthiness...	Restricted to ASN 9329 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	19/05/2010	Active	10028416
10028420	LUFTHANSA TECHNIK AG	REV. 2	FAA STC ST10964SC	A318-112	Installation of provisions for an Executive Power System	Certification Basis as per EASA TCDS A.064The CertificationBasis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA o...	- FAA Supplemental Type Certificate ST10964SC-Master Data List, ref. doc. 1110000100, Revision D, dated 17th August2010-Airplane Flight Manual Supplement, ref. doc. 1112021090, Revision IR,dated 18th December 2009- ICA Source Document, ref. doc. 1110050093, Rev. IR, dated 24th May2010or later revi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/04/2019	Active	10028420
10028421	LUFTHANSA TECHNIK AG	REV. 2	FAA STC ST10963SC	A318-112	Installation of a Miltope Wireless Access Point	Certification Basis as per EASA TCDS A.064The CertificationBasis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA o...	- FAA Supplemental Type Certificate ST10963SC-Master Data List, ref. doc. 1110000200, Revision L, dated 13th July2010-Airplane Flight Manual Supplement, ref. doc. 1111021090, Revision IR,dated 18th December 2009- ICA Source Document, ref. doc. 1110050091, Rev. IR, dated 20th May2010or later revisi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/04/2019	Active	10028421
10028425	LUFTHANSA TECHNIK AG	REV. 11		A319-133 / -115 A318-112, A319-115, A319-133 A318-112	Installation of an executive style interior on Airbus A318/A319 aircraftper Configurations -001 through -009Rev. 11: Transfer of STC (FAA ref. ST10958SC) from BIZJET Internationalto Lufthansa Technik AG.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:-Special Condition(s): CRI H-01 “Enhanced Airworthiness Programme forAeroplane Systems – ICA on EWIS”CRI D-5302-007 “Isolated Compartments”CRI D-5310-007 “Gl...	- Master Data List, ref. doc. 1110000010, Revision W, dated23 August2013-Airplane Flight Manual Supplement, ref. doc. 1350021091, Rev IR, dated14 June 2013-Electrical Wiring Interconnection Systems (EWIS) ICA Source Document,ref.doc. 1260050095, Rev B,dated 14 June 2013- Instructions for Continue...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/01/2022	Active	10028425
10028430 (EASA.IM.A.S.02477)	ISRAEL AEROSPACE INDUSTRIES, Ltd. (IAI)	REV. 8	CAAI SA218	B767-300 767-300	Conversion of Boeing 767-300 from passenger configuration to SpecialFreighter (BDSF) with main deck class E cargo compartment, includingaircraft equipped with APB winglets.Rev. 1:EWIS Instructions for Continued Airworthiness included. AMOCapproved.Rev. 2: AFM Supplement updated to Rev 1 and STC Dat...	As per STC Datasheet 10028430. In particular:for Significantly Changed Areas, Certification Basis is CS25 Amendment2, including:- Special ConditionsD-02, Fuselage DoorsH-01, ICA on EWIS-Equivalent Safety FindingsD-01, Supernumerary Seating AreaD-04, Flammability Standards for Thermal/ Acoustic Insu...	- B767-300 Conversion from PAX to SF- Master Document List,371-00-00-C0010, Rev HM-Instructions for Continued Airworthiness, 371-00-00-C004, Revision NEW- AFM Supplement, 371-00-00-C0490, Rev 4Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	An approved Cargo Loading System must be installed.Incorporation of this STC constitutes an AMOC for the list of affectedADs as published in the STC Datasheet 10028430.Mod Nr. M0234 (for conversion of aircrafts with standard Forward LowerCargo Door) is only applicable to aircrafts equipped with APB(...	21/11/2024	Active	10028430

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028433 (EASA.IM.A.S.03180)	TELAIR US LLC	REV. 1	FAA STC ST02767CH	B767-300	Install Main Deck Cargo Loading System.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate.NEW-PAGECertification basis is as defined in EASA STC 10028430.The certificated noise and/ or emissions levels of the original product are unchange...	Drawing List Report Number 3255, Revision C, 30/09/2009Applicable revisionsor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	To be installed on a/c converted by IAI Freighter Conversion (EASA STC10028430).	25/04/2016	Active	10028433
10028446 (EASA.A.S.03971)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		BEECH B200GT BEECH B200C, BEECH B200CGT BEECH 200, BEECH B200	Installation of Blue Sky Network (BSN) D1000(A) Iridium SatelliteCommunication and Tracking	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23.B NSCThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applica...	Installation in accordance with the data listed in Section 4.1 of theAir Alpha A/S Master Data List Numbered: MDL.EO-B200-23-132 Rev: 07.Operation in accordance with Air Alpha A/SFlight Manual SupplementNumbered: FMS.EO-B200-23-132 Rev: 00.Instructions for Continued Airworthiness i.a.w. Air Alpha A...	The installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.,,Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other pre...	15/08/2013	Active	10028446
10028447 (EASA.A.S.03759)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		A318, A319, A320, A321	Installation of provisions for the use of Dual navAero Electronic FlightBag Class 2 (EFB) System	In accordance with the EASA TCDSThe Certification Basis forthe original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Engineering Order & Certification Program, ref. doc. 2051375-EO, Issue1, dated 22nd December 2009- Airplane Flight Manual Supplement, ref. doc. 2051375-AM, Issue 3,dated 15th December 2009- Instruction for Continued Airworthiness, ref. doc. 2051375-CA, Issue2, dated 2nd November 2009Applicable rev...	Not Applicable	12/01/2010	Active	10028447
10028448 (EASA.IM.A.S.03237)	DV AVIATION, Inc.DBA NORTHPOINT AVIATION	REV. 3	FAA STC SA01688SE	206H, T206H	Installation of a revised shoulder harness restraint systemand new rearcabin headliner in Textron 206H/T206HRev. 3: Transfer from "Fifty-Ten-Yankee, LLC" to "DV Aviation, Inc.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Soloy, LLC Master Drawing List 912-100, dated 31 May 2006.Service Instructions No. 912-01, dated 24 May 2006.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2023	Active	10028448
10028449 (EASA.IM.A.S.03236)	DV AVIATION, Inc.DBA NORTHPOINT AVIATION	REV. 3	FAA STC SA00858SE	U206F, TU206C, U206G U206A, TU206G, 206H, T206H U206A, TU206G, TU206D, TU206E, U206, TU206F, TU206D, TU206E, U206, TU206F TU206B, U206F, TU206C, U206G, TU206A, U206E, TU206B 206, U206B, U206C, U206D 206H, T206H, TU206A, U206E,	Install Observation WindowRev. 3: Transfer from "Fifty-Ten-Yankee, LLC" to "DV Aviation, Inc."	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Soloy, LLC Master Drawing List, 901-100, Rev. B, dated 15 November 2000.Manufacturing Inspection Order for Part 901-1011, dated 6 December 2000.	This modification has been determined to be compatible withFAA STCSA2353NM and airplanes in landplane, floatplane and skiplaneconfiguration, when modified in accordance with FAA approved data.Prior to installation of this design change itmust be determined thatthe interrelationship between this de...	14/06/2023	Active	10028449

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028452 (EASA.R.S.01580)	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		EC 120 B	Replacement of existing SAFT Ni-Cad. battery with Concorde lead acidbattery RG-350.Note: this STC is issued for the purpose of transfering STC No. 10028452from Airalpha A/S (DOA 21J. 268) to new STC holder Scandinavian AvionicsDesign GmbH (DOA 21J.014)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS 27.301 (a),CS27 303, CS 27.305 (a), CS 27.307(a), CS 27.561, CS27.601, CS27.603, CS 27.605(a), CS 27.609, CS 27.611, CS 27.613 (a),(b...	Operation in accordance with:- Air Alpha A/S Flight Manual Sup. FMS.EO-EC120-24-133 Rev.00or later revisions of the above listed documents approved by EASA.Definition and Installation in accordance with:- Air Alpha A/S Master Data List MDL.EO-EC120-24-133 Rev. 01- Air Alpha A/S Accomplishment Ins...	None	12/12/2012	Active	10028452
10028464	ANCRA INTERNATIONAL LLC		FAA STC ST02279LA	B767-300	Install Main Deck Cargo Loading System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateCertification basis is as defined in EASA STC 10028430The certificated noise and/ or emissions levels of the original productare unchanged and remai...	Ancra International LLC Controlled data List DL85000, Revision D, 21/12/2009Applicable revisions"or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisdecision)"	To be installed on a/c converted by IAI Freighter Conversion (EASA STC10028430)	13/01/2010	Active	10028464
10028465	AERO CONSULTING SERVICES LTD.		TCCA LSTC C-LSA08-007/ D	LEARJET 60	Installation of Chelton HSD Satcom System.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain. applicable to this certificate/ approval.	F616000 Rev D - Modification Data SummaryF616071 Rev B - Instructions for Continued AirworthinessF616072 Rev A - Mandatory Maintenance Manual Supplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis deci...	Approval is valid for s/n 60-328 only.	13/01/2010	Active	10028465
10028486	AVIONIK STRAUBING ENTWICKLUNGS GMBH			SEE ATTACHED MODEL LIST	Installation of an Aspen EFD-1000 ProSystem.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Initial Issue (not required by 21A.101, elected to comply by theapplicant).The certificated noise and/ or emissions levels of thea...	Aircraft Model List: ASR-2009-047-AML-24-00 (attached)Installation Instructions: ASR-2009-047-IFI-10-00Instructions forContinued Airworthiness: ASR-2009-047-ICA-11-00Flight Manual Supplement: ASR-2009-047-FMS-05-00or later revisions of the above listed documents approved by EASA	None.	15/01/2010	Active	10028486
10028488 (EASA.IM.A.S.02713)	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03699AT	GULFSTREAM 150	G150 Steep Approach Landing	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalSee CRI D-06 Special Condition "Steep Approach Landing"	FAA Approved Airplane Flight Manual Steep Approach Supplement 2009-01for Gulfstream Model G150, Rev 1, FAA approved 4 Sept 09.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	27/01/2010	Active	10028488

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028491	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA09-091/D	BD-700-1A10	Bandit Mask Paint Scheme - ASN 9332.	EASA.IM.A.009.The Certification Basis for the original product and the followingadditional or alternative airworthinessrequirements are applicable tothis certificate/ approval.CRI D-600 - Emergency Exit Markings - Interruption of Two-InchBandOutlining Main Entrance Door.The certificated noise and/...	Transport Canada SoC reference C-09-1183 dated 12 January 2010.TCCA LSTC No C-LSA09-091/D Issue 1 dated 10 November 2009.ACS-NAI Ltd Modification Data Summary Number G064000 Revision N/C.*or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CFt...	Restricted to ASN 9332.	15/01/2010	Active	10028491
10028492	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9332.	EASA.IM.A.009.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Transport Canada SoC reference C-09-0992 dated 12 January 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.AeroConsulting Services Configuration Definition List D954000 RevisionDT dated 22 December 2009.Instructions for Continued Airworthiness GC93320000-IFCA.*or later revisions of the abov...	Restricted to ASN 9332.Refer to the Limitations sections ofthe required AFM Supplement and tothe referenced FCOMS.WLANsystem is compatible only to IEEE 802.11 (b).	15/01/2010	Active	10028492
10028493	APICAL INDUSTRIES, Inc.		FAA STC SR00645LA	AS355F2, AS355N, AS355NP AS355E, AS355F, AS355F1	Emergency Float Kit	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MD355(1) revision F dated 1 July 1998 - Master Document List;FMS-355(1) dated 29 July 1998 - Flight Manual Supplement;ICA350-1 revision C dated 12 January 1998 - Instructions for ContinuedAirworthiness;ICA350-20 revision B dated 3 December2004 - Instructions for ContinuedAirworthiness.or later revi...	Not Applicable	16/03/2011	Active	10028493
10028498 (EASA.IM.R.S.01562)	KEYSTONE HELICOPTER CORPORATION	REV. 1	FAA STC SR01127NY-D	S-76A, S-76B, S-76C	Installation of a Keystone Medical Interior - See Conditions	The Certification Basis for the original product remains applicable tothis certificate/ approval	Modification DefinitionKeytech Installation drawings List IDL00549, dated September 16th 2002.Flight Manual SupplementsFor the S76A, S76B or S76C - RFMS No. 00549 dated September 16th 2002<(>,<) >or later revision of this RFMS N° 00549 document approved by EASA inaccordance with EASA ED Decision 2004...	As specified in the approved RFMS.	03/02/2010	Active	10028498
10028501 (EASA.IM.R.S.01563)	KEYSTONE HELICOPTER CORPORATION		FAA STC SR00910NY	S-76A, S-76B, S-76C	Structural provisions for the installation of a Spectrolab SX5Searchlight to the left or right side of the S76.	The Certification Basis for the original product remains applicable tothis certificate/ approval	Modification DefinitionKeytech Installation drawings List IDL00242, Rev A, dated February 7th2000.Flight Manual SupplementsFor the S76A - RFMS No. 00242 dated Nov 19 1998For the S76B - RFMS No. 00242.1 dated Nov 19 1998For the S76C - RFMS No. 00242.2 dated Nov 19 1998or later revisions of these docu...	As specified in the approved RFMS.	18/01/2010	Active	10028501

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028503 (EASA.IM.R.S.01564)	KEYSTONE HELICOPTER CORPORATION		FAA STC SR00642NY	S-76A, S-76B, S-76C	Installation of a Liquid Oxygen System for Medevac use	The Certification Basis for the original product remains applicable tothis certificate/ approval	Modification DefinitionKeytech Installation drawings List IDL00114 dated April 3rd 1997.Flight Manual SupplementsFor the S76A, S76B or S76C - RFMS No. 00114 dated April 3rd 1997 orlater revisions of these documents approved by EASA in accordance withEASA ED Decision 2004/04/CF (or subsequent revisio...	- This approval should not be incorporated in any aircraft of thisspecific model on which other approved modifications are incorporated,unless it is determined that the interrelationship between this changeand any other previously incorporated approved modification will notintroduce any adverse effe...	18/01/2010	Active	10028503
10028505	GULFSTREAM AEROSPACE CORPORATION		FAA STC NO. ST03746AT-D	GV-SP	Completion and Installation of an Airplane Interior for Aircraft Serial5242.	JAR 25	Install in accordance with Gulfstream Aerospace CorporationMaster IndexList, GC514915242 Rev C, dated December 17, 2009, or later approvedrevisions.To be operated in accordance with FAA approved Airplane Flight ManualSupplement, ref. GC51468M008, Rev. NC dated December 17, 2009 or laterapproved rev...	Aircraft Serial Number 5242 only.	18/01/2010	Active	10028505
10028509 (EASA.IM.R.S.01532)	CARSON HELICOPTERS, INC.		FAA STC SR02487NY	SIKORSKY S61N AND S61NM	Increased Category A Performance.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: FAR 29 at Am 35.	Modification DefinitionCarson Helicopters Inc. Certification Plan for S61N Increased Category APerformance when equipped with Carson Composite Main Blades - Ref.Report CHI-04-1000Rev B Dated 08/29/2006Flight Manual SupplementsCarson Helicopters Inc RFMS No. 7 Rev 1 dated Jan 27 2009 or laterrevisio...	As specified in the approved RFMS.	18/01/2010	Active	10028509
10028519	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9333	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalNon-significantThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Transport Canada SoC reference C-09-0993 dated 14 January 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.AeroConsulting Services Configuration Definition List D954000 RevisionDU dated 23 December 2009.Instructions for Continued Airworthiness GC93330000-IFCA.Or later revisions of the above...	Restricted to ASN 9333 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).	21/01/2010	Active	10028519
10028521	STC TWENTY ONE LIMITED	REV. 1	UK.STC.00230	BD-700-1A10	Customized Aircraft Completion - ASN 9251.Rev. 1: Removal of Oxygen Altitude AFMS Limitation (S21.35-95-1010)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- STC Twenty One Limited Certification Programme, Doc Ref:S21.PROG-1708, Revision 2, dated 30 October 2023- STC TwentyOne Limited Master Document List, Doc Ref: S21.MDL-1708,Issue 1, dated 30 October 2023- STC Twenty One Limited Flight Manual Supplement, Doc Ref:S21.FMS-0057, Issue 2, dated 30 Oct...	Applicable to BD-700-1A10 with Design change S21.25-95-1387, installedunder EASA STC 10028521.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	12/03/2024	Active	10028521

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028553	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9115	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalNon-significantThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Transport Canada SoC reference C-09-0721 dated 14 January 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.AeroConsulting Services Configuration Definition List D954000 RevisionDG dated 29 July 2009.Instructions for Continued Airworthiness GC91150000-IFCA.Or later revisions of the above lis...	Restricted to ASN 9115 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).	21/01/2010	Active	10028553
10028563 (EASA.A.S.03652)	DASSAULT FALCON SERVICE			MYSTERE FALCON 900	Mode S dual transponder installation with elementary and enhancedsurveillance capabilities	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCompliance has been shown in accordance with the requisites laid down byJAA Temporary Guidance Leaflet JAA Leaflet TGL 13 Certification of...	- DFS Change Approval Sheet DFS 9550-CAS Issue A, dated 20th January2010- DFS Modification Sheet DFS 9550 Issue A, dated 20th January 2010- DFS Aeroplane Flight Manual Supplement Number DFS F900-030, Originalissue, dated 18th January 2010or later revisions of the above listed documents approved by E...	This EASA approval is applicable on those Basic Mystere Falcon 900aircraft previously equipped with:- Dual ATC Transponders Honeywell MST-67A P/N 066-01143-0601 withantenna diversity installation- 2 IRS and 2 ADC AZ 810As per DFS Change Approval Sheet DFS 9550-CAS Issue A, dated 20thJanuary 2010 or...	22/01/2010	Active	10028563
10028579	BOMBARDIER INC.	REV. 2	TCCA STC SA05-60	BD-700-1A11	Installation, Interior Completions In-Service Improvement Modifications- ASN 9334	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalproduct areunchanged and remain applicable to this certifica...	TCCA STC No SA05-60 Issue 1 dated 14 June 2005.Aero Consulting Services Ltd. Configuration Definition List E025000Revision EW dated 22 June 2011.Bombardier Airplane Flight Manual Supplement G-FM25004501 Revision N/Cor later approved revision.GC93340000-IFCA Instructions for Continued Airworthiness.o...	Restricted to ASN 9334	08/08/2011	Active	10028579
10028585 (EASA.R.S.01444)	AEROSPACE DESIGN FACILITIES Ltd.	REV. 2	CAA UK RESPONSIBILITY	2. AS355 F2, AS355 N, AS355 NP 2. AS355 E, AS355 F, AS355 F1 1. AS350 D, EC130 B4 1. AS350 B, B1, B2, BA, BB, B3	Cowling - Secondary Latching	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Modification DefinitionAerospace Design Change Instruction Sheet ADF2007-021 Issue 1Flight Manual SupplementsNot Applicable.MaintenanceAerospace Design Airworthiness Inspection Schedule ADF/ AIS2007-021 issue3	None	14/09/2010	Active	10028585
10028593	WESTERN AVIONICS		TCCA STC SA09-65	DHC-8-301, -311, -314, -315 DHC-8-201, -202 DHC-8-102, -103, -106	Standby Altimeter InstallationTCCA STC SA09-65, dated 07 August 2009	FAR-25 as per EASA.IM.A.191The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Installation:Must be in accordance with Western Avionics Engineering Order119975-401, Initial Issue, TCCA approved 07 August 2009Operation:Must be in accordance with Western Avionics Flight Manual Supplement119975-801, Initial Issue, TCCA approved 07 August 2009.Maintenance:Must be in accordance wit...	None	27/01/2010	Active	10028593

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028594 (EASA.IM.A.S.03223)	ADVANCED AVIONICS TECHNOLOGIESC /O ASM	REV. 1	FAA STC ST09365SC	DHC-8-201, DHC-8-202	Installation of dual Collins Mode S TranspondersFAA STC ST09365SC, IR, August 14, 1997	FAR 25 as per EASA.IM.A.191, Issue 4 (incl. SC H-01 ICA on EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areuncha...	-Installation of dual Collins Mode S Transponders iaw. AAT MasterDrawing List 1101-000, Rev. B, dated September 18, 2000-Airplane Flight Manual Supplement Doc. No. 1101-916, Rev. IR, August14, 1997Maintenance iaw Bombardier Maintenance Manual PSM 1-82-2.or later revisions of the above listed documen...	None	19/07/2011	Active	10028594
10028595 (EASA.IM.A.S.03220)	ADVANCED AVIONICS TECHNOLOGIESC /O ASM	REV. 2	FAA STC ST09326SC	DHC-8-201, DHC-8-202	Installation of Dual Universal Navigation UNS-1C Flight ManagementSystemFAA STC ST09326SC, Rev. 1, dated 14 November 2000	FAR 25 as per EASA.IM.A.191, Issue 4 (incl. SC H-01 ICA on EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areuncha...	-Installation of Dual Universal Navigation UNS-1C Flight ManagementSystem iaw AAT Master Drawing List 1061-000, Rev. G-Airplane Flight Manual Supplement Doc. No. 1061-916, Rev. B-Maintenance iaw Bombardier Airplane Maintenance Manual PSM 1-82-2.or later revisions of the above listed documents appro...	None	20/07/2011	Active	10028595
10028603 (EASA.IM.A.S.03118)	AIRLIFT A/S			AS365, EC 155	Installation of Latitude Skynode Satcom and Tracking System	CS 29, Amendment 2, with reversion to FAR 29.561 (b)(3) at amendment29-16The certificated noise and/ or emissions levels of the original productare unchanged and remain applicableto this certificate/ approval	MDL DO-365-23-104, Revision 0, dated 26/01/2010Flight Manual Supplement FMS-365-23-104, Rev 0, dated 22/09/2009	None	28/01/2010	Active	10028603
10028633	STG AEROSPACE Inc.AKA SAFTGLO, Inc.	REV. 2	FAA STC ST03629AT	B767-200, -300	Installation of STG Aerospace PowerSmart Emergency Primary Power System(WEPPS).	The Certification Basis for the original product remains applicable tothis certificateThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval	Master Drawing List 71670000 rev. D dated 29 October 2009Instruction for Continued Airworthiness 71676006 rev. D dated 29 October2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	03/03/2011	Active	10028633
10028634	STG AEROSPACE Inc.AKA SAFTGLO, Inc.	REV. 1	FAA STC ST03692AT	B757-200	Installation of STG Aerospace PowerSmart Emergency Primary Power System(WEPPS).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this approval.	-Master Drawing List 71440000 rev. C-Instruction for Continued Airworthiness 71446006 rev. Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None	23/03/2011	Active	10028634
10028641	AERONAUTICAL ACCESSORIES, INC			BELL 206 A & B	Installation of Aft Passenger Seat Shoulder Harness/Lap Belt Assemblyfor Bell Helicopter Textron 206 A / B Models	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	AAI Report Number AA-88090, Revision H, dated 8-21-06, "Drawing List,Passenger Seat Shoulder Harness/Lap Belt Assembly for Bell HelicopterTextron 206 A / B Models"or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisionst...	None	29/01/2010	Active	10028641

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028642	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03739AT-D	G150	Installation of an International Communications Group (ICG). Inc.NxtMail Server	JAR 25, Change 15The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Index List GA314288000, Rev. B, dated 05. November 2009-AFMS GA31428M001, Initial Release, dated 05. November 2009- Instructions for continued airworthiness GA34428A000, Initial Release,dated 05 October 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	Installation of Cabin Interior STC EASA.IM.A.S.02543 (FAA STCST10316SC-D) is required prior to installation of this NxtMail Serverarrangement.	01/02/2010	Active	10028642
10028645	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		B200, B200C, B200GT, B200CGT	Air Alpha STC Definition Document EO-B200-23-138 for Intercominstallation and modification. Intercom installation in cabin forspecial mission Aircraft. The cabin intercom interfaces to the cockpitintercom.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 has been elected apart from CS-23-561 where FAR Part 23.561 Amdt23.7 is used.The requirements for environmental protection and the associatedcertified noise and/ oru...	AirAlpha Master Data List No. MDL.EO-B200-23-138or later revisions of the above listed documents approved by EASA	The installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.,,Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other pre...	15/08/2013	Active	10028645
10028652	TRUATLANTIC MFG., LLC	REV. 2	FAA STC ST02635AT	35, 35A, 36, 36A	Deactivation of Aeronca (Learjet) Thrust ReversersAllow thedeactivation of the Aercona (Learjet) Thrust Reversers inaccordance with Atlantic Aero Master Drawing List 21193001, rev E, dated8 February 2003This STC is a transfer from Atlantic Aero, Greensboro USA, toTruAtlantic Mfg., Kernersville USA...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Airplane Flight Manual Supplement 21193100, rev. IRInstruction for Continued Airworthiness 21193010, rev. Cor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (orsubsequent revisions ofthis decision)"and/ or the Technical ImplementationPro...	Not Applicable	28/04/2016	Active	10028652
10028688 (EASA.A.S.03382)	SABENA TECHNICS BGC			A318/A319/A320/A321	Approval of Installation Provisions for the use of EFB Class 2 on AirbusA318/A319/ A320/A321	In accordance with the EASA TCDSThe Certification Basis forthe original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Master Data List, ref. doc. No. 0316-01-A-2103-R02, Revision R02,dated 3rd February 2010- Airplane Flight Manual Supplement, ref. doc. No. 0316-01-A-2301-R01,Revision R01, dated10th December 2009- Instruction for Continued Airworthiness, ref. doc. No. 0316-01-A-2211-R01, Revision R01, dated 22nd J...	Not Applicable	03/02/2010	Active	10028688
10028693 (EASA.A.S.03921)	LUFTHANSA TECHNIK AG	REV. 1		B737-300	Zonal Dryer System Installation in accordance with 737-EB21-0212	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The requirements for environmental pr...	Supplemental Type Definition Document STDD21-09/01M Iss. 02Engineering Bulletin 737-EB21-0212 Rev.03or later revisions of the above listed documents approved by EASA	None	20/10/2010	Active	10028693
10028703	FORCED AEROMOTIVE TECHNOLOGIES		FAA STC SE10926SC	IO-550-N	Installation of BAR Air, LLC supercharger system on Teledyne ContinentalMotors IO-550-N Engines in accordance with Master Drawing ListMDL-SR22-1-E, Revision A, dated April 4, 2008or later FAA approvedrevision - EASA Validation of FAA STC SE10926SC.	JAR-E Change 9 dated May 4, 1990The Certification Basis forthe original product remains applicable tothis certificate except for JAR-E 10, E 20, E 25, E 40, E 70, E 220, E270, E 360 which are amended by JAR-E Change 10	Instructions for Continued Airworthiness are contained in Document No.22007-30, Revision N/C, dated December 1, 2007 orlater revisionsapproved by EASA in accordance with EASA ED Decision 2004/04/CF (orsubsequent revisions of this decision)	The supercharged IO-550-N engine is limited to 29.6 in Hg (204 kPa) MAPand 2700 RPM or 310 HP (231 kW).	03/02/2010	Active	10028703

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028706	ECMS AVIATION SYSTEMS GMBH			BELL 212, 412	Load Attachment Device BRD01	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA CS 29 Amdt. 2The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certi...	Flight Manual Supplement for External Load Device BRD01 on Bell 212 andBell 412, Doc. No. BRD01_FMS_EASA_R0, dated 01.12.2009or later revisions of the above listed documents approved by EASA	None	04/02/2010	Active	10028706
10028707 (EASA.A.S.03752)	KUERZI AVIATION AG	REV. 7		PC-6/B2-H4 PC-6-B2-H2, PC-6-B2-H4 PC-6/B2-H2	Transfer of 10028707 Rev. 5.PC-6 Synthetic Vision for G950 STC Rev.5 Baseline STC:Garmin G 950 InstallationIntegration of a new Garmin G950 Integrated Flight Deck and legacysystems on the Pilatus PC-6/B2-H4 model. The G950 system (a derivate ofthe G1000 system) combines primary flight instrumentatio...	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval withou...	- Master Data List MDL-200830764 REV M-Flight Manual Supplement FMS-201212616 REV F-Flight Manual Supplement FMS-200830764 REV IOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Required pre-modifications:-Pilatus PC-6 pitch trim warning system according SB-180.-Electrical stall warning system,type Safe Flight 1-02-0005 No. 164(Transmitter) and C-73113(Buzzer).-Electrical power distribution system (MCA 06/24/130).-Electrical flap control according SB-95 (plus-differen...	29/11/2023	Active	10028707
10028717	AIR COMM CORPORATION LLC		FAA STC SR00693DE	BELL HELICOPTER 429	Installation of Cabin Air Conditioning System Provisions	CS27 Change 1The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	DL-429C, Section 1 revision B dated 5 June 2009 - Master Drawing List; 429EC-200M-1 revision 1 dated 8 September 2009 - Instructions forContinued Airworthiness;429EC-100M revision 0 dated 4 September 2009 - Flight Manual Supplement.or laterrevisions of the above listed documents approved by EASA ina...	None	04/02/2010	Active	10028717
10028730	BOMBARDIER AEROSPACE		TCCA LSTC C-LSA08-338/ D	CL-600-2B16	Installation, Complete Custom Aircraft Interior - ASN 5506	EASA.IM.A.023The Certification Basis for the original product remains applicableto this certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-TCCA LSTC No. C-LSA08-338/D Issue 1 dated 18 December 2008.-Aero Consulting Services Ltd. Modification Data Summary F962000Revision N/C or later approved revision.-Transport Canada approved Aero Consulting Services Ltd. Airplane FlightManual Supplement C73090 Revision A or later approved revision.-...	Restricted to ASN 5506.Aircraft must be fitted with an approved means to disconnect the cabinAC and DC utility buses asa prerequisite to this modification.	05/02/2010	Active	10028730
10028747	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		737 ALL MODELS 737-900 737-700, 737-800 737-500, 737-600 737-300, 737-400 737-200C, 737-900ER 737-100, 737-200	Blue Sky Network Satcom installation.This STC installs Satcom communications at the captain and F/O station.Rev. 2: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS-25 Amendment 7The requirements forenvironmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand rema...	- Modification Summary Sheet, ref: MOD-11619-00001 Issue 2.- Master Drawing List, ref: MDL-11619-00001 Issue 2-Aircraft Flight Manual Supplement, Ref: 11619-AFM-00001 Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10028747
10028758 (EASA.IM.R.S.01457)	CERT WORKS, LLC	REV. 1	FAA SR00805SE	AS350BA AS 350 BA	Installation of Honeywell LTS101-600A-3A engine on AS 350 BA.Rev 1. Transfer of STC to Cert Works, LLC.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Modifications completed prior to January 31, 2007:Installation instructions EHDA-199-B, Revision 1, dated February 16,2005.Maintenance Manual Supplement EHDA-197-B, Revision 2, dated February 18,2005<(>,<)>Modifications completed after January 31, 2007:Master Drawing List 920-100, Revision N/C, date...	See attached Annex Issue 01 dated 27/11/2020.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	27/11/2020	Active	10028758

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028761 (EASA.IM.A.S.03154)	B/E AEROSPACE LIMITED	REV. 1	TCCA LSTC C-LSA09-004D, ISS. 2	CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-004D Issue 2 dated 22 July 2009.Aero Consulting Services Ltd. Modification Data Summary G115000 RevisionB.Savannah Air Center Inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior, G115090 Revision A, and Savannah AirCenter Inc. Airplane Flight ManualF...	Restricted to ASN 8083.	16/08/2013	Active	10028761
10028762 (EASA.IM.A.S.03131)	ACS-NAI Ltd.	REV. 1	TCCA LSTC NO. C-LSA09-023/D	BOMBARDIER CL-600-2B19	Installation, Complete Custom Aircraft Interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-023/D Issue 1 dated 02 July 2009.AeroConsulting Services Ltd. Modification Data Summary G098000 RevisionD.Midcoast Aviation inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior Installation, 33-299M007 Rev NC.Aero Consulting Services Ltd. Mandatory M...	Restricted to ASN 8065.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/08/2013	Active	10028762
10028763 (EASA.IM.A.S.03134)	ACS-NAI Ltd.	REV. 1	TCCA LSTC NO. C-LSA09-030/D	BOMBARDIER CL-600-2B19	Installation, Complete Custom Aircraft Interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-030/D Issue 2 dated 21 July 2009.AeroConsulting Services Ltd. Modification Data Summary G119000 RevisionC.Midcoast Aviation Inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior Installation, 33-299M010 Rev A.Aero Consulting Services Ltd. Mandatory Ma...	Restricted to ASN 8078.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/08/2013	Active	10028763
10028781	ROEDER PRAEZISION GMBH	REV. 1		210	Post Installation Approval and conformity check of avionic system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Flight Manual Supplement: C210-NY-07136-08, Rev. 1.-Instructions for Continued Airworthiness: C210-NY-07136-07, Rev. 0.-Installation Manual: C210-NY-07136-05, Rev. 1or later revisions of the above listed documents approved by EASA.	Limited to S.N 57339.Prior to installation of this modification it must be determined thatthe interrelationship betweenthis modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	15/11/2017	Active	10028781
10028789	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 6		AS 350 BB AS 350 B, AS 350 BA AS 350 B1, AS 350 B2	Installation of flight data monitoring and transmitting systemSAFETYPLANE or HELICOM V2 ANA or HELICOM V2+ ANA.The original revision of this STC approves the installation of the“SAFETYPLANE” equipment.Revision 1 of this STC incorporates the latest evolutions of thissystem, identified as:HELICOM V2 A...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for:- Special Condition(s): CRI F-01 Lithium Battery.- The following paragraph (s) at a later amendment:CS 27 initial issue 27.25, 27.27, 27.301, 27.303, 27.305, 27.307,27....	Rotorcraft Flight Manual Supplement for HELICOM V2 ANA and HELICOM V2+ANA, doc. ref. N8-AS350 B BA BB B1 B2, E-C-03, Rev 7 dated 13/06/2017Reference Documents doc. ref. N1-AS350 BBA BB B1 B2 E-C-06 dated13/06/2017Or later revisions of theabove listed document(s) approved/acceptedunder the EASA sys...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2020	Active	10028789

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028790	WIPAIRE Inc.		FAA STC SA01397NY	208, 208B	Installation of ERDA, Inc. Executive Seat, Model 3058 and folding tablesin acc. with FAA STC SA01397NY.	As defined in FAA TCDS A37CEThe Certification Basis for theoriginal product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Wipaire, Inc. Document Control List SU8003DCL, Rev. C, dated November5, 2009.-FAA approved Wipaire, Inc. Flight ManualSupplement SU8003FMS, Rev. C,dated November 24, 2009.-FAA accepted Wipaire, Inc. Instructions for Continued AirworthinessSU8003ICA, Rev. A, dated February 8, 2007.or later revision...	None	09/02/2010	Active	10028790
10028796	AERONAUTICAL ACCESSORIES, INC		FAA STC SR02162LA	BELL 407	Installation of Mounting Provisions for a Tail Boom Radar Altimeter inaccordance with Meeker Aviation Drawing List for Radar Altimeter MountKit, AA-TBA-16-010, and Document List of Radar Altimeter Mount Kit<(>,<)> AA-TBA-16-011.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Meeker Aviation Drawing List for Radar Altimeter Mount Kit,AA-TBA-16-010, Revision A, dated August 18, 2008- DocumentList of Radar Altimeter Mount Kit, AA-TBA-16-011, RevisionIR, dated February 20, 2008- Instructions for Continued Airworthiness Report Number AA-TBA-16-008,Revision IR, Dated Janua...	This STC provides mounting provisions only; it does not allow the holderto install an altimeter or any wiring to power an altimeter.	10/02/2010	Active	10028796
10028797	AERONAUTICAL ACCESSORIES, INC		FAA STC ST02121LA	BELL 407	Installation of a Tail Boom Antenna Mount Kit in accordancewith MeekerAviation MDL for VHF Communication Antenna MountKit, AA-TBA-010.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Meeker Aviation MDL for VHF Communication Antenna Mount Kit,AA-TBA-010, Revision IR, dated January 15, 2008- Instructions for Continued Airworthiness Report Number AA-TBA-008, RevIR, dated January 11, 2008.or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDt...	This STC provides mounting provisions only; it does not allow theholder to install an antenna or any wiring to power an antenna.	10/02/2010	Active	10028797
10028799	AERO CONSULTING SERVICES LTD.		TCCA STC C-LSA10-006/D	900XP	Installation of Dual Lifeport Patient Loading and Utility System (PLUS)	CAR 4b and FAR 25	- Installation in accordance with Aero Consulting Services LtdModification Data Summary G569000 Rev N/C or later approved revisions- Operation in accordance with Aero Consulting Services Ltd FlightManual Supplement G569090 Rev N/C or laterapproved revisions- Maintenance in accordance with Aero Cons...	Aircraft Serial Number HA-0114 Only	10/02/2010	Active	10028799
10028814 (EASA.R.S.01492)	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)	REV. 3		2. AS355 F2, AS355 N, AS355 NP 2. AS355 E, AS355 F, AS355 F1 1. AS350 D, AS350 BB 1. AS350 B, AS350 B1, AS350 B2 1. AS350 B3, AS350 BA	Modifications H-25-05-06-SFP and H-25-05-06-SFPAnt - Installation of arack and transmitting/receiving antennaeNotes:Initial issue of this STC covered installation of a rack - modificationH-25-05-06-SFPRevision 1 to this STC added installation of transmitting/receivingantennae - modification H-25-05-...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	H-25-05-06-SFP Flight Manual Supplement - RFMS for Installation of anElectronic Rack for Reception/Sending on Eurocopter AS350/AS355 (Ed. 0dtd 10 Dec 2009 - document in English) H-25-05-06-SFPAnt Flight Manual Supplement - RFMS for Installation ofReception/Broadcasting Antennas with Actuator on Euro...	This STC is not applicable to AS350B3 model helicopters withmodification OP-4305 (Arriel 2D engine installation) incorporated.	26/07/2012	Active	10028814

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028816 (EASA.A.S.03916)	AVIONIK STRAUBING ENTWICKLUNGS GmbH			B. M20J, M20K, M20L, M20S B. M20C, M20E, M20F, M20G A. M20M, M20R	Installation of Aspen EFD1000 PRO System.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Initial issue (not required by 21A.101, elected to comply by theapplicant)The certificated noise and/ or emissions levels of the o...	Instructions for Installation: ASR-2009-046-IFI-10-00, Rev.: 00Instructions for Continued Airworthiness: ASR-2009-046-ICA-11-00, Rev.00Flight Manual Supplement: ASR-2009-046-FMS-05-00, Rev. 00or later revisions of the above listed documents approved by EASA	None.	11/02/2010	Active	10028816
10028823 (EASA.IM.R.S.01554)	DART AEROSPACE Ltd.		TCCA STC SH09-16	EC130B4	Traffic Advisory System Installation.	The original product certification basis as per EASA TCDS.R.008 Issue03, 12 October 2007.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this...	Definition and installation:DART Aerospace Ltd. Master Document List MDL-D130-787, Rev. B datedApril 20, 2009DART Aerospace Ltd. Installation Instructions IIN-D130-787, Rev. B datedApril 06, 2009Inspection and maintenance:Inspections for Continued Airworthiness contained in DART Aerospace Ltd.docume...	None.	12/02/2010	Active	10028823
10028830 (EASA.A.S.03761)	LUFTHANSA TECHNIK AG	REV. 3		A319-133	A319-133 ‘GAF’ VIP Cabin CompletionRev. 1: Closure of post certification action D-08-01Rev. 2: Updated Instructions forContinued AirworthinessRev. 3: Updated Instructions for Continued Airworthiness	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-4302-002 ‘Isolated Compartments’; D-4310-002‘Glass Screen of Display/Monitors’; D-4314-002 ‘Shower Installation’Equivalent Safety Find...	Supplemental Type Design Definition STDD00-08/17M Issue 04,rev. 00Airplane Flight Manual Supplement A-00-09/136-AFM Issue 01, rev. 01Instructions for Continued Airworthiness A-00-09/136-ICA Issue 07, rev.00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/04/2023	Active	10028830
10028837 (EASA.A.S.03864)	DUNLOP AIRCRAFT TYRES LIMITED	REV. 6	CAA UK RESPONSIBILITY	ERJ 190-200STD ERJ 190-200LR ERJ 190-200IGW ERJ 190-100STD ERJ 190-100 SR ERJ 190-100LR ERJ 190-100IGW	Installation of Radial MLG (DZ32930T & DZ32923T) and NLG (DZ32816T)tyre.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dunlop Aircraft Tyres Ltd Master Document List No. DATL PR 13 MDLrevision IR dated 08 March 2016or later revisions of the above listed documents approved by EASA.	Refer to DATL-PR13 Dunlop Tyre Supplement Manual for approvedinterchangeability and mixability of Main Landing Gear tyres.	27/06/2016	Active	10028837
10028844 (EASA.IM.A.S.02043)	AVIATION PARTNERS, INC.	REV. 3	FAA ST01987SE	FALCON 2000, FALCON 2000EX	Revision of EASA STC EASA.IM.A.S. 02043 ("FAA STC ST01987SE:Installationof blended winglet on Dassault Falcon 2000 and 2000EX Series airplanes,including 2000EX EASy designation airplanes") to include Falcon 2000Winglets Airplane Flight Manual (AFM) Revision for Forward Center ofGravity (CG) Limitati...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: CS 36 amendmentI...	Master Drawing List Revision F dtd. 3 April 2009.For Falcon2000 airplanes with CFE 738 Engines: AFM supplement APF2-0601Rev. 1, Code 9002,dtd. 7. February 2014.For Falcon 2000EX airplanes: AFM supplement APF2-0601 Rev. 6, Code 001,dtd. 7.February 2014.Supplement to Dassault Aviation Structural Rep...	Significant Change, Certification basis as per CRI - A1 IM.A.S. 02043- Steep approach Operation with Winglets installed is not approved- HUD/ CATIII Operation with Winglets installed is not approvedPrior to installation of this design changeit must be determined thatthe interrelationship between this...	29/04/2024	Active	10028844
10028847 (EASA.A.S.03872)	TENENCIA Ltd.	REV. 2		AVRO 146-RJ100	Avro 146-RJ100 Amiri Flight VIP Installation.	EASA TCDS A.182The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01 Instructions for Continued Airworthiness (ICA) on ElectricalWiring Interconnection Systems (EWIS), Issue 2 datedT...	Modification TEN 621, BAE Systems Avro 146-RJ100 Amiri Flight VIPInstallation, Issue 5 dated 24 January 2011or later revisions of the above listed documents approved by EASA	Serial number E3387 only.	26/01/2011	Active	10028847

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028850 (P-EASA.R.S.01572)	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	BK117 C-2	STAR SAFIRE FLIR SystemInstallation of FSI Star Safire HD FLIR onto right hand utility stepbased on EC UK Major Change MHL/145/1166 into the BK117 C-2.	The Certification Basis for the original product remains applicable tothis certificate/ approval	-BK117 C-2 EC UK Flight Manual Supplement No. 6 "FSI Star Safire HD FLIRSurveillance System (Mounted on RHS ACS/ Meeker Step)", Iss. 1or later revisions of the above listed documents approved by EASA-Master Drawing A1/1451166-001-Design Report DR/1451166-001 Iss. A-Instructions for Continued Airworth...	The following pre-modifications are required for the installation ofthis STC:-ACS/Meeker Utility Step on the right handside, p/n AFM-SM117A-11installed i.a.w. EASA.IM.R.S.01489-ACS/ Meeker Arm p/n AF-SM117-C10 on the forward position of the aboveutility step	16/02/2010	Active	10028850
10028851 (P-EASA.R.S.01573)	AIRBUS HELICOPTERS UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	MBB-BK117 C-2	Installation of Spectrolab Nightsun XP Skid Mounted System.Equipmentinspection and re-certification to close the requirement for AD No.2010-0183R1.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness ICAW/ 1451167-001, Issue B,dated 10.11.2010 or later revisions of the above listed documentsapproved by EASA.Design Report DR/ 145/1167-001,Issue B, dated 10.11.2010	none	15/11/2010	Active	10028851
10028856	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	BK117 C-2	Cabin ConfigurationDefinition of permissible configurationsand combinations ofindividually approved changes based on EC UK Major Change MHL/145/1229Iss. A into the BK117 C-2.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	-BK117 C-2 EC UK Flight Manual Supplement No. 14 "Cabin Configuration",Iss. 1or later revisions of the above listed documents approved by EASA-Design Report DR/1451229-001 Iss. A	None	16/02/2010	Active	10028856
10028872	AERONAUTICAL ACCESSORIES, INC		FAA STC SR09325RC	BELL 407	Installation of Bulged Skylight in accordance with AeronauticalAccessories, Inc. Drawing List, Report No AA-01070	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Instructions for Continued Airworthiness Bulged Skylight Kit ReportAA-01069, Rev B, dated 4-18-2007or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	16/02/2010	Active	10028872
10028873	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR02028SE	EC 120 B	Cargo hook kit Model 200-351-00	As specified in TCDS DGAC No 189The Certification Basis forthe original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Definition and Installation:- Onboard Systems Master Drawing List No. 155-144-00, Rev. 0, dated July22, 2009- Onboard Systems Owner's Manual No. 120-139-00, Rev. 0, dated June 16,2009Inspection and Maintenance:- Onboard Systems Instructions for Continued Airworthiness No.123-034-00, Rev. 0, dated Ju...	EASA-approved EC 120 B Flight Manual External Load Transport "CargoSling" FM Supplement is required.	16/02/2010	Active	10028873
10028891	AERONAUTICAL ACCESSORIES, INC		FAA STC SR09326RC	BELL 407	Development and Installation of High Visibility Crew Door in accordancewith Aeronautical Accessories, Inc. Drawing List, Report No AA-01073	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Drawing List, Report No AA-01073, Revision G, dated 10th, December 2009-Instructions for Continued Airworthiness, Report No AA-01072, Rev D,dated 7th, December 2009.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisio...	None	17/02/2010	Active	10028891

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028893	AERONAUTICAL ACCESSORIES, INC		FAA STC SR09376RC-D	BELL 407	High Visibility Door Kits in accordance with Aeronautical Accessories,Inc. Drawing List Report No AA-05155	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Drawing List Report No AA-05155, Revision K dated 14th, December 2009.-Instructions for Continued Airworthiness for High Visibility Door Kiton Bell Helicopter Textron Model 407 Helicopters, Report No AA-5158,Rev B, dated 12th , October 2009.or later revisions of the above listed documents approved...	None	17/02/2010	Active	10028893
10028910	LATITUDE TECHNOLOGIES CORPORATION			212, 412	Skynode S200-xxx SATPHONE/ TRACKER system product design in accordancewith Latitude Technologies Corporation Skynode S200-xxx Master DocumentList No S200-000-001 Revision 1.09, dated Aug 10, 2009.	As defined in FAA TCDS H4SWThe Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Latitude Technologies Corporation Skynode S200-xxx Rotorcraft FlightManual Supplement No S200-402-002, Revision 01. (EASA specific RFMSupplement).or later revisions of the abovelisted documents approved by EASA- Latitude Technologies Corporation Skynode S200-xxx Master DocumentList No S200-000-00...	None	18/02/2010	Active	10028910
10028911 (EASA.IM.A.S.03222)	ADVANCED AVIONICS TECHNOLOGIESC /O ASM	REV. 2	FAA STC ST09347SC	DHC-8-401, DHC-8-402 DHC-8-201, DHC-8-202	Installation of Coltech ATSCALL SystemFAA STC ST09347SC, Rev. 1, dated May 08, 2001.	FAR Part 25 as per TCDS EASA.IM.A.191, Issue 4 (including SpecialConditions H-01 "Enhanced Airworthiness Programme for Aeroplane Systems- ICA on EWIS") for DHC-8-100/200/300 SeriesCS 25/ JAR 25 as per TCDS EASA.IM.A. 191 Issue 4 (including SpecialConditions H-01 "Enhanced Airworthiness Programme for A...	-Installation of Coltech ATSCALL iaw. AAT Master Drawing List 1078-000,Rev. B, dated February 01, 2001.-Airplane FlightManual Supplement Doc. No. 1078-916, Rev. A, dated May06, 2001.-Maintenance iaw Bombardier Airplane Maintenance ManualPSM 1-82-2, PSM1-84-7.or later revisions of the above listed...	None	20/07/2011	Active	10028911
10028917 (EASA.IM.R.S.01556)	DART AEROSPACE Ltd.		TCCA STC SH09-04	BELL 412, 412EP BELL 212, 214B, 214B-1, BELL 204B, 205A-1,	"Full Vertical Reference Door for Left Hand Vertical ReferenceOperations"	As defined on FAA TCDS H4SW and H1SWThe Certification Basisfor the original product remains applicable tothis certificate/ approval.	-FMS-D205-761 Rev. A dated 26.01.2009 and TCCA approved 02.02.2009-FMS-D412-761 Rev. A dated 29.01.2009 and TCCA approved 02.02.2009-FMS-D214-761 Rev. A dated 29.01.2009 and TCCA approved 02.02.2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2...	Full compliance has not been demonstrated for airworthinessstandards29.1303 (g)(h)(i)(j), 29.1321(b) and 29.1523(b) forsingle pilotoperation from the Left Seat resulting in a Restricted Categoryclassification. When conducting vertical reference work from thisposition with a single pilot, the rotorc...	10/03/2010	Active	10028917
10028925 (EASA.R.S.01590)	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	BK117 C-2	Bucher 16G stretcher	FAR 29The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Flight Manual; EC UK BK117-C2(EC145) Supplement No.11or later revisions of the above listed documents approved by EASA-Build standard/top drwg; A3/1451194-01-1-ICA; Maintenance requirements MR/ 145/1194-001	None	19/02/2010	Active	10028925

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10028927 (EASA.IM.A.S.03046)	DUNCAN AVIATION, INC.		FAA STC ST01409WI-D	MYSTERE FALCON MF900	EASA Validation of FAA STC ST01409WI-DInstallation of an L3Communications, GH-3100 Electronic StandbyInstrument System(ESIS) in accordance with Duncan Aviation Inc MasterDocument List No 06062208, Revision C, dated February 19th, 2008or later revisions approved by EASA in accordance with EASA ED D...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Duncan Aviation Master Document List No 06062208, RevisionC, datedFebruary 19th, 2008-Duncan Aviation Aeroplane Flight Manual Supplement, No. 060622020,Revision A, originally approved October 10th, 2006or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Deci...	Validation limited to Basic Mystere Falcon MF900 aircraft model	19/02/2010	Active	10028927
10028933 (EASA.A.S.03609)	airplus engineering GmbH	REV. 1		PA-46-310P	Installation of Garmin GNS530W, GNS430W and GMA347.	CS-23	Installation must be in accordance with AirPlus Master Document ListMD-0359-340530 Rev. 3 dated 19th Feb. 2010 or laterApproved Revisions.Operation must be in accordance with AirPlus Flight Manual SupplementPO-0359-340347, PO-0359-340430,PO-0359-340530 and PO-0359-340401 Rev. 0dated 03rd Sept. 200...	None	07/02/2021	Active	10028933
10028945	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			P.180 AVANTI, AVANTI II	Installation of In-Flight Entertainment System in accordance withEngineering Order, Doc. No. 2009-9	The Certification Basis of the original product remains applicable tothis changeThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-EASA approved Engineering Order, Doc. No. 2009-9, RevisionB, dated05-Jan-2010, or later approved Issue-EASA approved Airplane Flight Manual Supplement, Doc. No. 200998,Revision A, dated 05-Oct-2009, or later approved Issue-Maintenance Manual Supplement, Doc. No. 2009-9-10, Revision A, dated05-Oct-...	None	22/02/2010	Active	10028945
10028946	TQAS - TOTAL QUALITY AND AIRCRAFTSOLUTIONS, LDA			B737-500	Installation of Floor proximity emergency photo luminescentpath.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalAdditional Certification Requirements as agreed for FAA and TransportCanada have been accounted for. If specific AFM pages exist, those ar...	Design Dossier CG-008-09-CPO dated February 11th 2010.AFM Supplement CG-008-09-AFM Iss.1or later revisions of the abovelisted documents approved by EASA	None	22/02/2010	Active	10028946
10028999 (EASA.A.S.03735)	AIRBUS S.A.S.	REV. 2		A319-115	ACJ Centre Modification CJ0400 - VIP Cabin Interior - "ACROPOLIS"Revision due to update of AFM-S and MPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI G-4111 "ACJC Project Certification Basis".The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	1. Modification Approval Sheet ref: CJ0400, Issue 3 "Top ModificationACROPOLIS" dated 24th October 20132. AFM Supplement Ref: FM-S MOD CJ0400, Rev. 02, dated 1st October 20133. MPD Supplement Ref: MPD-S MOD CJ0400, Rev. 03, dated 1st October 2013or later revisions of the above listed documents appro...	This STC is limited to Airbus A319 MSN 3826Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducenoadverse effect upon the airworthiness of the product.The i...	22/11/2013	Active	10028999

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029002	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	PA-31	Installation of defence aid antennas and systems	CS-23The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Master Data List MDL1116-01 Issue 2- Change Statement CS1116-01 Issue 2- Instructions for Continued Airworthiness ICA1116-01or later revisions of the above listed documents approved by EASA	None	25/02/2010	Active	10029002
10029004	airplus engineering GmbH	REV. 1		CESSNA 501, 551	Installation of Avidyne TAS 620 and Honeywell KGP 860	EASA CS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable tothis certificate/ approval	Flight Manual Supplements:PO-0673-340 001, Rev. 1PO-0673-340002, Rev. 1Installation Manual and Instructions for Continued Airworthiness:EW-0673-34 0000, Rev. 3or later revisions of the above listed documents approved by EASA	None	07/02/2021	Active	10029004
10029007	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH 58P	STC 2589/09 - Radio B-RNAV avec couplage PA	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appro...	Supplément au manuel de vol SEAM/SMV/2789/09 rev 1 du 24/02/2010or later revisions of the above listed documents approved by EASA	Limited to: S/N TJ-74	25/02/2010	Active	10029007
10029061	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03752AT-D	GIV-X	Aircraft completion and installation of an Airplane Interior, S/N 4180	JAR 25The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Install in accordance with Master Index List GC414914180, Revision D,dated 10 February, 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	This approval is limited to S/N 4180 only.The following STC's are required part of this STC:ST02979AT-D, ST02980AT-D, ST02987AT-D, ST03027AT-D, ST03047AT-D,ST03290AT-D, ST03410AT-D, ST03532AT-D, and ST03647AT-D.It is he installers responsibility to ensure all these STC's are EASAapproved.	11/06/2010	Active	10029061
10029069	GROWING ENGINEERING PARTNERS GmbH	REV. 2		B747-400	Reconfiguration of Virgin Atlantic Airlines B747-400 Aft Upper Deck inaccordance with SR Technics Master Data List C747-25-1005-MDL Rev. 0. orlater approved revisionsRev.2: Transfer of STC from SR Technics Switzerland to groWINGEngineeringPartners GmbH	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The applicant elected to comply to FAR Part 25 at amendment 128 exceptfor the following requirements which remain at TCDS level.25.305, 2...	C747-25-1005-ICA-01 Instructions for Continued Airworthiness Rev. 0C747-25-1005-WBR-01 Weight and Balance report Rev. 0or later revisions of the above listed documents approved byEASA	Approval of the Life Vests is not a part of this STC.	20/04/2021	Active	10029069
10029073 (EASA.A.S.03952)	PROTOPLANE SPECIAL MISSION AIRCRAFT	REV. 1		BEECH 200 B200	Video transmission mast under B200.Rev. 1: Revision to Maintenance Manual and Flight Manual	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual supplement ref PP-012-AFM-09 rev 10 dated 13/3/2025Maintenance Manual supplement ref PP-012-AMM-04 rev 4 dated 13/3/2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The approval holder shall fulfil the obligations of Par...	02/06/2025	Active	10029073

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029091 (EASA.A.S.03891)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		747-400	Introduction of changes to the cabin layout in accordance with ATLModification Summary MOD-11427-00001Part A: introduces a seating configuration of 22 business class and 440economy classPart B: introduces all emergency equipment necessary to comply with therequirements for 22C 440Y passengers operat...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The certification basis is CS25 at change 4 for changed parts except forthe following requirement:FAR 25.835(d) at amndt 59The requirements for environmentalc...	EASA AFM supplement 11427-AFM-0001 Issue 1, Installation ofPhoto-luminescent Aisle Path Marking System, shall be used with theaircraftInstructions for Continues Airworthiness included in ATL Mod SummaryMOD11427-00001 Issue 4 shall be incorporated in the technicaldocumentation of the aircraft.or late...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10029091
10029092	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	PA-31	ATC transponder upgrade for Mode S enhanced surveillance	CS-23The certificated noise and/ or emissions levels of theoriginal productare unchanged and remain applicable to thiscertificate/ approval	-Master Data List MDL1120-01 Issue 1-Change Statement CS1120-01 Issue 1-Flight Manual Supplement AFMS-1120-01 Issue1-Instructions for Continued Airworthiness ICA1120-01 Issue 1or later revisions of the above listed documents approved by EASA	Not Applicable	03/03/2010	Active	10029092
10029093 (EASA.A.S.03846)	AERODATA AG			1329-25	Avionics Upgrade for RVSM CompatibilityDesign definition: Aerodata's documents reference MDL-A/C-075 Rev. 3,23/02/2010,Master Document List	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalAs defined in "Lockheed 1329-25 Jetstar II Avionics Upgrade for RVSMCompatibility (P-EASA.A.S.03846) CRI A-01", issue 1.B, 26/02/2010The c...	Aerodata's documents reference:-AFM-069 Rev. 2, 11/02/2010,EASA approved supplement to Flight Manualand-AMM-748 Rev. 2, 22/02/2010, supplement to Maintenance Manual, includingEASapproved Chapter 5, "Time Limits/ Maintenance Checks"or later revisions of the above listed documents approved by EASA	Limited to: S/N 5226	03/03/2010	Active	10029093
10029094 (EASA.IM.A.S.02978)	B/E AEROSPACE, Inc. - FSI	REV. 1	FAA STC ST02051SE	777-200	Remove EWIS limitation for EASA STC No. 10029094 - First Class SeatInstallation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original p...	FAA STC ST02051SEFSI Master drawing List A7FS703-D01 Revision D dated 21 June 2010A7FS703-D15 Revision C dated 13 July 2010 Supplemental Instructions forContinued Airworthinessor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subseque...	Concurrent installation of EASA STC No. 10029095 (EASA Project No.P-EASA.IM.A.S. 03043) is requiredConcurrent installation of EASA STC No. EASA.IM.A.S.01797 is required	04/10/2010	Active	10029094
10029095 (EASA.IM.A.S.03043)	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02052SE	B777-200	First Class Cabin Upgrade - BA 777-200 Aircraft	EASA TCDS No. IM.A.003The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-FAA STC No. ST02052SE dated 24 February 2010.-FAA SoC dated 26 February 2010.-Northwest Aerospace Technologies, Inc. (NAT) Master Drawing ListN0305-D10, Revision D dated 2 February 2010 or later approved revision.or later revisions of theabove listed documents approved by EASA inaccordance with EA...	Concurrent installation of EASA STC No. 10029094 (EASA Project NoP-EASA.IM.A.S. 02978) is required.Concurrent installation of EASA STC No. EASA.IM.A.S.01797 is required.This modification may not be installed after 30 August 2010 unless (1)previously approved electrical wiring interconnect system (EWI...	03/03/2010	Active	10029095

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029101 (EASA.A.S.03979)	AEROLITE AG	REV. 5		B200, B200GT	Emergency Medical Services Interior Equipment Kit: P/N 230001-501 andP/N 230001-502.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation of EMS equipment in accordance with Aerolite documentMDL-09-009, at revision G, dated February 13, 2020;Operation and Maintenance of Kit P/N 230001-501 in accordance with Aircraft Flight Manual Supplement, Aerolite document FMS-09-005,at revision B, dated June 25, 2015; Oper...	P/N 230001-501 applicable to Beechcraft model B200 MSN BB-1868, BB-2001and subsequent; P/N 230001-502 applicable to Beechcraft model B200GT.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changee...	03/03/2020	Active	10029101
10029103	H4 AEROSPACE (UK) Ltd.	REV. 2	CAA UK RESPONSIBILITY	A319, A320, A321	Installation of Runway Turnoff and Logo Lights. Minor Change to EASA STC10029103, Rev.1 issue date 31.03.2010 granted to H4 Aerospace (UK) Ltd.Minor change approval is sought to reflect the up issue wording of theinstructions of continued airworthiness including the FAA approval intheir airworthines...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 / SC Enhanced Airworthiness Programme for Aeroplane Systems -ICA on EWIS.The certificated noise and/ or emissions levels of the o...	- Modification Summary Sheet and Declaration of Compliance doc. N °H4A1269 Issue 5 dated 10/09/10.- Instructions for Continued Airworthiness doc. N° H4ADR512 Issue 3dated 10/09/2010 and N °H4ADR513 Issue 3 dated 10/09/2010.- Master Document List doc. N °H4ADR525 Issue 5 and N° H4ADR526 Issue 4.- Master...	Restricted to the aircraft listed in doc. N° H4ADR530 - MasterEffectivity List for Goodrich RTO and Logo Light Installation.	20/10/2010	Active	10029103
10029105	NASCO AIRCRAFT BRAKE, INC.		FAA STC ST02664LA	747-300 SERIES 747-200F SERIES, 747-200C SERIES, 747-200B SERIES, 747-100 SERIES,	Installation and Replacement of Steel Brake Components in accordancewith NASCO's Configuration Control Drawing, Report Number NCC 009,Revision A, dated December 2, 2009, or later FAA approved revision.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	NASCO Components Maintenance Manual 747001 shall be used with thesebrakesor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	05/03/2010	Active	10029105
10029107	DART AEROSPACE USA, Inc.	REV. 1	FAA SR00949SE	A119, AW119MKII A109S/ A119/ AW119MKII	Fabrication of DART Aerospace USA, Inc. D119-647-011/-013 Bearpaws andinstallation of this modification.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Document List MDL-D119-647, Revision G, dated 5 March 2020, orlater FAA approved revision.2. Installation Instructions IIN-D119-647, Revision B, dated 1 November2019, orlater FAA approved revision.3. Instructions for Continued Airworthiness, ICA-D119-647<(>,<)>Revision 1, dated 25 Februar...	1. Model A109S must be operated in accordance with Rotorcraft FlightManual Supplement (RFMS) FMS-D109-647, Revision A, dated 8 April 2020,or later FAA approved revision.2. Model A109S must have Trekker kit part number 109G0000F01 installed.3. Prior to installation of this design change it must be de...	14/05/2020	Active	10029107
10029112	CESKA LETECKA SERVISNI A.S.			L-420 L-410 UVP-E-LW, L-410 UVP-E20, L-410 UVP-E9, L-410 UVP-LW, L-410M, L-410 UVP, L-410 UVP-E	Dual Mode-S Transponder upgrade for EHS capability	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23, Amdt 1, dated 12/02/2009Special Conditions: EASA INT POL 23/1 (HIRF)	Flight Manual Supplements:-No. AC186-2501: FMS Unit UNS-1Fw, issued January 2010-No. AC186-2502: Supplement No.5 - TCAS-94 (SW7.0) a odpovídač S ModuTDR-94D Rockwell Collins, issued January 2010MEL Supplement:-No. AC186-2801: MODE S EHS, issued January 2010	None	05/03/2010	Active	10029112

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029133 (EASA.R.S.01515)	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	AS355F2, AS355N, AS355NP AS355E, AS355F, AS355F1,	Installation of Skywatch L3 Traffic avoidance and Honeywell's KMD250 MFD	As specified on EASA TCDS R.146The Certification Basis for the original product remains applicable tothis certificate/ approvalCS-27 change 2 dated 17 November 2008 used for this STCThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this cer...	-PADS/FMS/AS355/001 revision A - Flight Manual Supplementorlater revisions of the above listed documents approved by EASA-PADS/MDL/ 1115/001 revision A dated 26 February 2008 - Master Documentlist;-PADS/CP/ 1115 revision B dated 26 February2008 - Change Embodiment andApproval Sheet;-PADS/ICA/ 1115/00...	Not Applicable	08/03/2010	Active	10029133
10029134	LUFTHANSA TECHNIK AG	REV. 1		A340-600	A340-600 Cabin Retrofit Etihad ETD06EASA STC 10029134 revision due to removal of EWIS limitation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI E-19 "Mini suites"- the following paragraph(s) at a later amendment: CS-25 Amdt. 5,Appendix H "Electrical Wiring Interconnection System".The re...	-,,Supplemental Type Definition Document, ref. Doc. No STDD00-09/20M,Issue 1, dated 24th February 2010-,,Compliance Record List ref. doc. No. CRL 00-09/20M iss.2, dated 24thApril 2013-,,Instructions for Continued Airworthiness, ref. Doc. No.A-25-10/011-ICA, Issue 1, dated 15th February. 2010-,,EWISA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/05/2013	Active	10029134
10029165 (EASA.R.S.01591)	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	MBB-BK117-C2	Martin Baker Swivelling Passenger Seats	EASA TCDS R.010The Certification Basis for the original product remains applicable tothis certificate/ approval	-ECUK RFMS Number 9, Issue 1or later revisions of the abovelisted documents approved by EASA-Eurocpter UK Design Report DR/145/1196 Iss A.	None	09/03/2010	Active	10029165
10029201	ROEDER PRAEZISION GMBH			CESSNA P210N	Ferry Tank Provisioning	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Engineering Order 725EO280010-01A-"POH Supplement for Cessna P210N, S/N P21000629", Doc. No. 7725 AM 280010 01A, Revision 1, dated 18 February 2010or later revisions of the abovelisted documents approved by EASA	Limited to Aircraft S/N P210 00629	11/03/2010	Active	10029201
10029207 (EASA.IM.R.S.01485)	DART AEROSPACE Ltd.		TCCA STC SH99-11 ISSUE 5	204B, 205A-1	"Adjustable Engine Mount Kit"	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-MDL-D205-708 Rev. C Master Document List-IIN-D205-708 Rev.A Installation Instructions-ICA-D205-708 Rev. 0 Instructions for Continued Airworthiness	None	11/03/2010	Active	10029207
10029211	BUCHER LEICHTBAU AG	REV. 14		EC635 T1, EC635 T2+, EC635 T3 EC635 P2+, EC635 P3 EC135 T2+, EC135 T3 EC135 T1, EC135 T2 EC135 P2+, EC135 P3 EC135 P1, EC135 P2	Bucher Ambulance and Rescue System (EMS Installation) ARA-EC135-AC67List of revisions to STC 10029211 for EMS Bucher Ambulance & RescueSystem P/N ARA-EC135-AC67:Initial Revision:-The presented EMS Equipment describes a fully integrated interior ofmedical support devices. See Equipment List E015-55-...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Flight Manual Supplement FMS-AC67FLEX Revision C- Flight Manual Supplement FMS-AC67 Revision AL- Master Document ListE0012480 Revision NC- Operation Manual Supplement E014-01-20 Revision 02or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/04/2021	Active	10029211

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029212	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03738AT-D	GIV-X, GV-SP	Installation of Fwd & Aft Lavatory Smoke Detectors.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Installed in accordance with Gulfstream Aerospace Corporation IndexList, ref. GC414558002, Revision G, dated 13th September 2010-Instruction for Continued Airworthiness, ref. GC42455A000, Revision A,dated 28th July 2010or later revisions of the above listed documents approved by EASA inaccordance w...	None	10/05/2012	Active	10029212
10029213	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03667AT-D	GULFSTREAM GV-SP, GIV-X	Installation of a Generation 3, Broad Band Multi-Link (BBML) System.	JAR 25.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Install in accordance with Gulfstream Aerospace CorporationIndex ListGC413038009, Revision E, dated 10 September, 2009.Aircraft to be operated in accordance with:-Airplane FlightManual Supplement, GC41303M012, Revision NC, datedSeptember10, 2009, orAirplane Flight Manual Supplement, GC41303M013,S...	The installer must determine whether this design change is compatiblewith previously approved modifications. If the holder agrees to permitanother person to use this certificate to alter the product, the holdershall give the other person written evidence of that permission.	12/03/2010	Active	10029213
10029215	BEECHCRAFT CORPORATION		FAA STC SA01502WI-D	B300 SERIES	STC SA01502WI-D issued to allow modification of the FGC-3000 units as asolution to eliminate nuisance pitch trim wheel movement.	FAR 23.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation Instructions Replacement of FGC-3000 in a Hawker BeechcraftCorporation King Air B300/B300C, P/N RCA-2463, dated January 28, 2008Instructions for Initial and ContinuedAirworthiness, P/ NAMI-STC-B2B3P21, Rev 9 dated September 18, 2009 or later approvedrevisions.Instructions for Initial an...	None.	12/03/2010	Active	10029215
10029220	BEECHCRAFT CORPORATION		FAA STC ST03749AT-D	GIV-X	Installation of cabin interior and Airplane Completion for Serial 4175.	JAR 25.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Install in accordance with Master Index List GC414914175, Revision H,dated January 27, 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	This approval is limited to only the installation made in GulfstreamGIV-X, Serial No 4175.The following STC's are a required part of this STC: ST02228CH-D, ,,ST02979AT-D, ST02980AT-D, ST02987AT-D, ST03047AT-D, ST03290AT-D, ST03410AT-D, ST03532AT-D, ST03542AT-D, ST03648AT-D,ST03649AT-D, ST03667AT-D,...	12/03/2010	Active	10029220
10029239	AERO CONSULTING SERVICES LTD.		TCCA LSTC C-LSA10-010/ D	PC-12/47E	Installation, Lifeport PLUS Units in Tandem Configuration	Canadian Airworthiness Manual Chapter 523, Change 3 dated January 2,1992 which is equivalent to 14 CFR 23, Normal Category, effectiveFebruary 4, 1991, including Amendments 23-1 through 23-42.The Certification Basis for the original productand the followingadditional or alternative airworthiness req...	-Installation in accordance with ACS-NAI Ltd. Modification Data SummaryG456000 Rev N/ C or later approved revisions.-Operation in accordance with Pilot's Operating Handbook andTCCA-Approved Airplane Flight Manual Supplement EGR-855-11-02 Rev A "PLUS Installation" Pilatus PC-12/47E for aircraft S/N 11...	The applicability of the present STC is limited to AircraftS/N: 1165Refer to the Limitations section in the TCCA-approved Airplane FlightManual Supplement listed in associated technical documentation	15/03/2010	Active	10029239

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029243 (EASA.A.S.03962)	SOCATA	REV. 4		TB 21 TB 20	Installation of Garmin G500 EFIS Interfaced with a dual Garmin GNS430W/ 530W communication and navigation system, for IFR B-RNAV/P-RNAVoperations with coupling to autopilot.Revision 3 of the STC including the extent to RNP LNAV and LPV approachoperations.Revision 4 correcting typographic mistakes ind...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS 23The Certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ app...	Installation Instructions n °STC 34.001.09.010, Edition 1 Revision 0dated 05/10/2012 ;Instructions for continued airworthiness n °STC 34.001.09.006 Edition 1Revision 0, dated 05/01/2010;LRU software versions listing n°STC 34.001.09.009 Edition 3 Revision 0dated 12/07/2012 ;Master Drawing list and Part...	The modified airplane must be equipped with:- an attitude indicator, an airspeed indicator, an altitude indicator, amagnetic heading indicator and a radionavigation indicator independentfrom the G500 EFIS<(>,<)>- a third radionavigation orradiocommunciation equipment independentfrom and not similar...	23/10/2012	Active	10029243
10029250	AERO TECHNICS DESIGN LIMITED		CAA UK RESPONSIBILITY	B767, L100/L1011, B777 B747-400, DC-8, DC-10.MD-11, A300, A310	Introduction of Instone Airservices Airstable Horse/FreightContainerP/N 73-90-343.	Various as applicable to aircraft types listed for installationThe Certification Basis for the original product remainsapplicable tothis certificate/ approval.	Certification Plan ATD0311 or later revisions of the above listeddocuments approved by EASA	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph 'Description'. Compatibility with all aircraft configurations shall be determined bythe installer.	26/03/2010	Active	10029250
10029263 (EASA.IM.A.S.03221)	ADVANCED AVIONICS TECHNOLOGIESC /O ASM	REV. 2	FAA STC ST09346SC	DHC-8-201, DHC-8-202	Installation of Honeywell Traffic Alert and Collision Avoidance System,TCAS IIFAA STC ST09326SC, Rev.1, dated 14 November 2000.	FAR-25 as per EASA.IM.A.191, Issue 4 (incl. SC H-01 ICA on EWIS).The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunch...	Installation of Honeywell Traffic Alert and Collision Avoidance System,TCAS II iaw. AAT Master Drawing List 1065-000, Rev. B, dated March 17,1997.Airplane Flight Manual SupplementDoc. No. 1065-916, Rev. IR.- Maintenance iaw Bombardier Airplane Maintenance Manual PSM 1-82-2.or later revisions of the...	none	20/07/2011	Active	10029263
10029265 (EASA.A.S.03811)	airplus engineering GmbH	REV. 2		SEE APPROVED MODEL LIST (AML)	Enabeling of SVT Functionalities on Garmin G5/600 System (Revision ofEASA STC 10029265)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23 Amendment 2(not required by 21A.101)The certificated noise and/ or emissions levels of the original productare unchanged and remain...	-Flight Manual Supplement: PO-0328-340000, Rev. 3or later revisions of the above listed documents approved by EASA-Description of Modification: DE-0328-000000, Rev. 4- Engineering Work Order: EW-0328-340000, Rev. 3	The aircraft must have been already equipped with Garmin G5/600System(s) according to EASA STC 10029265.	10/02/2021	Active	10029265
10029272 (EASA.A.S.02790)	AIRBUS DEFENCE AND SPACE S.A.	REV. 9		A330-202, A330-203, A330-243	Conversion of A330-200 Series A/C to A330 Multi Role Transport Tanker(MRTT) RAAF (Royal Australian Air Force), RSAF (Royal Saudi Arabian AirForce) and UAE (United Arabic Emirates Force)- Rev. 1 of this STC has been issued in order to add Configuration 2.- Rev. 2 of this STC has been issued in ordera...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.0562 Initial Issue for affected areas by this STC;CS 25.0853 Initial Issue for affected areas by chang...	For Configuration 1 RAAF (Tranche 1 and Tranche 2)- “Aircraft A330 MRTT Design Definition for STC” document ref.DT-FA-ANC-09077 Issue B.- Airplane Flight Manual Supplement “EASA Approved A330 MRTT AirplaneFlight Manual” documentref. DT-FA-C00-08025, Issue as referenced in STC 10069541 AMLTEA-FA-AW-1...	This STC only covers the installation of external aerodynamic devices(two underwing pods, boom, receptacle for refueling, antennas, fairings,in case they are equipped with) with the associated structuralmodifications, the modification of some basic aircraft systems, theinstallation of some inoperati...	25/07/2023	Active	10029272
10029274 (EASA.IM.A.S.03255)	TRIUMPH INSTRUMENTS BURBANK Inc.	REV. 1	FAA STC ST02236LA	CL-600-2D15, CL-600-2D24 CL-600-2B19, CL-600-2C10	Triumph Replacement Hydraulic Accumulators.	EASA.IM.A.023.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	EASA STC No. EASA.IM.A.S.03255 dated 27 July 2009.FAA STC No. ST02236LA dated 23 April 2009.FAA Approved Model List (AML) ST02236LA dated 29 December 2009.Instructions for Continued Airworthiness (ICA), Triumph Master ReportNumber ICAW-MR-STI3664, Revision NC dated 23 April 2009 or laterapproved rev...	None.	17/03/2010	Active	10029274

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029275	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9323.	EASA.IM.A.009.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Transport Canada SoC reference C-10-0011 dated 11 March 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionDY dated 03 March 2010.Instructions for Continued Airworthiness GC93230000-IFCA.or later revisions of the above list...	Restricted to ASN 9323.Refer to the Limitations sections ofthe required AFM Supplement and tothe referenced FCOMS.WLANsystem is compatible only to IEEE 802.11 (b).	17/03/2010	Active	10029275
10029282	BOMBARDIER AEROSPACE		TCCA STC SA10-21	CL-600-2B16	Installation, Un-Upholstered Headliner, Rockwell Collins HUD.	EASA IM.A.023.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA10-21 Issue 1 dated 04 March 2010.ACS-NAI Ltd. Modification Data Summary Number G523000 Revision NC orlater approved revision.For Instructions for Continued Airworthiness, refer to ACS-NAI Ltd.G523070-ICA Revision NC or later approved revision.or later revisions of the abo...	None.	17/03/2010	Active	10029282
10029290	FORCED AEROMOTIVE TECHNOLOGIES		FAA STC SA10925SC	SR22	Installation of BAR Air, LLC modified Teledyne Continental MotorsIO-550-N iaw. MDL-SR22-1-A, Rev. E or later FAA approved revisions.Installation requires EASA STC 10028703 to be installed.	CS-23.BThe Certification Basis for the original product andthe followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ ap...	MDL-SR22-1-A, Rev EAirplane Flight Manual Supplement 22006,Rev AICA 22006-30, Rev Eor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	As referred in limitations section of the AFM-S 22006Enginemust be modified acc. EASA STC 10028703	17/03/2010	Active	10029290
10029315	FIELD AVIATION COMPANY INC.		TCCA STC SA02-86	DHC-8-315 DHC-8-202, -301, -311, -314 DHC-8-102, -103, -106, -201	Installation of a HF Antenna into the Vertical Stabilizer Leading Edgefor an Allied Signal KHF-950 HF Transceiver.TCCA STC SA02-86, Issue 2	FAR-25 as per EASA.IM.A. 191.The Certification Basis for theoriginal product and the followingadditional or alternativeairworthiness requirements are applicable tothis certificate/ approval.Special Condition H-01 "Enhanced Airworthiness Programme for AeroplaneSystems - ICA on EWIS" as detailed in C...	Installation must be in accordance with Field Aviation Company Inc.Modification Instructions 178010, Rev. AMaintenance must be in accordance with Field Aviation Company Inc.Maintenance Manual Supplement 178031, dated 15 January 2002.or later revisions of the above listed documents approved by EASA i...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	18/03/2010	Active	10029315
10029324 (EASA.A.S.03854)	BELL TEXTRON PRAGUE, a.s.			L 200 A, L 200 D	Installation of Aspen EDF-1000 "PRO" and EFD-1000 "PILOT", GNS 430W, GTX330, KR 87, KN 62A and ELT ME406 systems.	CS-23, Amdt. 1, dated 12 February 2009 including JAA Interim PoliciesNo: INT/POL/23/1 (HIRF) and INT/POL/23/3 (IEL).	L 200 D Flight Manual Supplements No.:·,,FM 34 20/01 001 Primary Flight System EFD1000 Pro, dated Nov 27/09·,,FM 34 20/01 002 Primary Flight System EFD1000 Pilot, dated Nov 27/09·,,FM 34 50/01 001 GPS/WAAS NAV COMM GNS 430W, dated Nov 27/09·,,FM 34 50/01 002 Mode-S Transponder GTX 330, dated Nov 27/...	None.	18/03/2010	Active	10029324

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029325 (EASA.IM.A.S.02962)	SILVERHAWK CONVERSIONS		FAA STC SA10741SC	C90, E90, C90A AIRCRAFT BEECHCRAFT KING AIR	Installation of Pratt and Whitney Canada PT6A - 135A Engines.	CS-23.B NSC	Installation of Pratt & Whitney PT6A-135 engines in accordance withDrawing No. 70101-00, Rev. IR, dated 06. June 2007 or later approvedrevision.Operation must be in accordance with Aircraft Flight Manual SupplementNo. AFMS 70101-C90 dated 20. September 2007 or later approved revisionfor the Model C9...	None	18/03/2010	Active	10029325
10029332	WESTERN AVIONICS	REV. 1	TCCA STC SA03-53 ISSUE 1	DHC-8-311, -314, -315 DHC-8-201, -202, -301, DHC-8-102, -103, -106,	Primus 800 Weather Radar InstallationTCCA STC SA03-53, Issue 1, dated 28.05.2003.Removal of the limitation for Instructions for Continued Airworthinesson Electrical Wiring Interconnection System - EWIS ICA - in accordancewith Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Syst...	FAR-25 as per EASA.IM.A. 191The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalSpecial Condition H-01 "Enhanced Airworthiness Programme for AeroplaneSystems - ICA on EWIS" as detailed in CRI...	Installation must be in accordance with Western Avionics EngineeringOrder 90404-401, Rev. 2.Maintenance must be in accordance with Western Avionics MaintenanceManual Supplement 90404-701, Rev.2.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/...	A previously approved Weather Radar System installation is aprerequisite for the installation.	30/11/2010	Active	10029332
10029335	ACC COLUMBIA Jet Service GmbH	REV. 1		T310P, T310Q, T310R E310H, E310J 310P, 310Q, 310R 310J, 310J-1, 310K, 310L, 310N 310E, 310F, 310G, 310H, 310I, 310, 310A, 310B, 310C, 310D,	Alternative Supplemenal Inspection Document (A-SID)Rev. 1 Transfer to ACC Columbia Jet Service GmbH	CS-23.BThe Certification Basis for the original product remains applicable tothis certificate/ approval	According to Gomolzig MDL Document No. MDOCL21530_REV0_1512 2009To be operated and maintained in accordance with approved GomolzigDocument No. 3A10_A-SID_Maintenance Manual Supplement_21530, OriginalIssueCP_21530_rev_0_15112009or later revisions of the above listed documents approved by EASA	As referred in limitations section of the 3A10_A-SID_Maintenance ManualSupplement_21530Alteration to A-SID is subject to written permission of approval holderThis modification is only limited to S/N listed in EASA approvedGomolzig DocumentNo. 21530_Master Aircraft Application ControlList_REV0_15122...	20/01/2022	Active	10029335
10029339	AERO MEDICAL PRODUCTS Co. Inc.		FAA STC ST01188CH	CESSNA 501, 551	Installation of Air Ambulance Conversion iaw. Aero Medical Products MfgInstallation Drawing List Report 006-1 or later FAA approved revisions	CS-23.BThe Certification Basis for the original product remains applicable tothis certificate/ approval	Installation Drawing List Report 006-1Airplane Flight Manual Supplement to ST01188CH (EA Form 171-C)MMS to ST01188CHor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	As referred in limitations section of the AFM-SPrior to thefirst flight of each modified aircraft, and after eachchange to any of the communication, Navigational, or Med Pack equipment,a ground EMI test must be conducted iaw. EA Form 173.A copy of EA Form173 must be kept with the aircraft records...	19/03/2010	Active	10029339
10029348	APICAL INDUSTRIES, Inc.		FAA STC SR02271LA	206L-3, 206L-4 206A, 206B, 206L, 206L-1,	Bell 206 Cable Cutter Kit	FAR 27The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-MD206-21, revision A dated 10 November 2009 - Master Document List;- ICA206-21 revision N/C dated 16 July 2009 - Instructions for ContinuedAirworthiness.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis dec...	None	19/03/2010	Active	10029348

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029380	ACC COLUMBIA Jet Service GmbH	REV. 1		CESSNA T182T CESSNA 182R, -S, T, T182 CESSNA 182L, -M, -N, -P, -Q, CESSNA 182F, -G, -H, -J, -K, CESSNA 182, -A, -B, -C, -D, -E	Camera Modification KitRev. 1 Transfer to ACC Columbia Jet Service GmbH	CS-23.CThe Certification Basis for the original product remains applicable tothis certificate/ approval	-Master Document List MDOCL_2022177_rev0_01022010-Airplane Flight Manual Supplement SPOH_2022177_rev0_01022010 for Cessna182S, T and T182T-Anhang zum Flughandbuch KameraumrüstsatzC182-812000 Ausgabe 21.03.97for Cessna 182, -A, -B, -C, -D,-E, -F, -G, -H, -J ,-K, -L, -M, -N, -P,-Q, -R, T182-Installa...	As referred in limitations section of the AFM-S:Airplane Flight Manual Supplement SPOH_2022177_rev0_01022010 for Cessna182S, T and T182TAnhang zum Flughandbuch Kameraumrüstsatz C182-812000 Ausgabe 21.03.97for Cessna 182, -A, -B, -C, -D, -E, -F, -G, -H, -J ,-K, -L, -M, -N, -P,-Q, -R, T182	26/01/2022	Active	10029380
10029398	U.S. TECHNICAL CONSULTANTS, INC.		FAA STC ST02161LA	B757-200, B757-300	Installation of navAero t.BagC2 Electronic Flight Bag	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-FAA STC ST02161LA-Master Drawing List 4913-23-000 rev B dated 05/02/08-AFMS U-10-0171 dated 08/11/08or later revisionsof the above listed documents approved by EASA inaccordancewith EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Not Applicable	23/03/2010	Active	10029398
10029406	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBILITY	9. 58TC 8. 95-C55, D55, E55, 58, 58P 7. 95-55, 95-A55, 95-B55 6. 36, A36, A36TC, B36TC 5. S35, V35, V35A, V35B 4. J35, K35, M35, N35, P35 3. E33C, F33, F33A, F33C, H35 2. 35-C33, 35-C33A, E33, E33A 1. 35-33, 35-A33, 35-B33	Amendment to existing STC 10029406 to add TAWS-B functionality andinclude optional GAD43 autopilot interface unit.	CS23The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Data List MDL1112-02 Issue 1Change Statement CS1112-02 Issue 1Instructions for Continued Airworthiness ICA1112-02 Issue 1Flight Manual Supplement AFMS1112-02 Issue 1or later revisions of the above listed documents approved by EASA	None	03/01/2011	Active	10029406
10029416 (EASA.A.S.03895)	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BD-700-1A10	Customized Aircraft Completion - ASN 9266	EASA.IM.A.009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI F-01 "Installation of Wireless System"CRI D-01 "Installationof Interior Door"CRI D-02 "Isolated Compartments"The certifi...	STC Twenty One Ltd Master Document List No. S21.MDL-0655.STC Twenty One Ltd Airplane Flight Manual Supplement No. S21.FMS-0054.Instructions for Continued Airworthiness Midcoast Aviation Inc.Supplemental Maintenance Manual No. 35-027E134.orlater revisions of the above listed documents approved by EA...	None.	24/03/2010	Active	10029416
10029418 (EASA.A.S.03569)	BINDER MOTORENBAU GmbH	REV. 2		NIMBUS-3DM	Replacement of engine-control-unit ILECA new Engine controlunit “ILEC MCU-N3DM” can be installed in NIMBUS-3DMmotorgliders with SOLO 2625/2 engines. Therefore, an adapted wiring willbe introduced.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Technische Mitteilung (TM Triebwerk-B4) Solo-Umbau –Triebwerksbedieneinheit ILEC MCU-N3DM und Motorelektrik, Ausgabe10.02.2023 Zusatz zum Flughandbuch für den Motorsegler Nimbus 3DM – Umbau von Rotax535C auf Solo 2625/2, Ausgabe 2 vom 10.02.2023 Zusatz zum Wartungshandbuch für den Motorsegler Nimbuso...	None	05/04/2023	Active	10029418

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029434 (EASA.IM.A.S.02996)	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC SA8285SW-D	FALCON 900EX	EASA Validation of FAA STC SA8285SW-D Revision1:Installation of the Security System (Structural Provisions) inaccordance with Drawing List Report No. F9EX-01021, Revision B dated13th June 1997 or later revisions approved by EASA in accordance withEASA ED Decision 2004/04/CF (or subsequent revisions...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	See those of original FAA STC 8285SW-D Revision1 as amendedby the FAAon 14th June 1997or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None.	24/03/2010	Active	10029434
10029450	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	M20, M20A, M20B, M20C, M20D M20L, M20R, M20S, M20TN M20E, M20F, M20G, M20J, M20K	Installation of Aspen EFD1000 Primary Flight Display (PFD)	The Certification Basis of the original product and the followingadditional / alternative airworthiness requirements are applicable tothis changeCS-23 has been elected to comply with for those areas affected by thechange unless otherwise statedEASA GM GA/G/001 has been followedThe certificated noise...	EASA approved Design Report with Installation Instructions,Doc. No.TAD. 02209, Revision B, dated 23-Mar-2010, or later approved revisionEASA approved Airplane Flight Manual Supplement, Doc. No. FMS.02209,Revision A, dated 20-Nov-2009,or later approved revisionApproved Instructions for Continued Airw...	This change is limited to the configuration of aircraft, equipment type,functions and software versions as listed in EASA approved DesignReport, Doc. No. TAD.02209, Revision B, dated 23-Mar-2010	25/03/2010	Active	10029450
10029451	BLR AEROSPACE, L.L.C.	REV. 3	FAA STC SA02054SE	E90 C90GTI C90GT C90A, C90GT, C90GTI C90A C90	Installation of winglets and related systems changes. Installation ofthe LED tail position and anti-collision lighting system.Revision 2 updates the STC holder's address.Revision 3 includes installation of the LED tail position andanti-collision lighting system and extends the STC applicability toTe...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:[Amdt 23-0]: 23.21, 23.171, 23.231(a), 23.303, 23.307, 23.471, 23.477,23.479, 23.481, 23.483, 23.493, 23.499<(>,<)>23.601, 23.609, 23.627, 23.641, 23.651, 23....	Installed in accordance with the applicable Master Drawing List (MDL) aslisted on FAA AML SA02054SE.Operation in accordance with Airplane Flight Manual Supplement (AFMS) aslisted on FAA AML SA02054SE.Instructions for Continued Airworthiness (ICA) as listed on FAA AMLSA02054SEor later revisions of th...	Eligible Serial Numbers are defined in Master Drawing List,documentBLR-KA90W-002 King Air 90 Winglets MDL REV AD, or later approvedrevisions.This STC has been shown to be compatible with Hawker Beechcraft/CentexAerospace, Inc. STC SA10747SC for the gross weight increase to 10,545lbs Maximum Ramp We...	01/10/2024	Active	10029451
10029479 (EASA.R.S.01541)	ECT INDUSTRIES			AS355F2, AS355N, AS355NP AS355E, AS355F, AS355F1	STC DTS AS 355 - Installation of a Tracking system.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS27 Change 1.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certific...	RFMS-DTS-355-EN revision 0 – Rotorcraft Flight Manual Supplement.or later revisions of the above listed documents approved by EASACONFAD-0021-053670-EN revision 3 dated 26 January2010 – ConformityStatement;IM-0011-053670-EN revision 5 dated 9 November 2009 – MountingInstructions;MUL-0013-053670-ENM...	None.	26/03/2010	Active	10029479
10029480	SOCIETE D'ETUDE ET DE GESTIONAERONAUTIQUE (SEGA)			AS350 B2	Installation system for "EC120 type" seats on Eurocopter AS350B2 -modification H-08-09-Siège	As per EASA TCDS.R.008 Issue 03, 12 October 2007.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation system for EC120 seats on Eurocopter AS350(Modification H-08-09-Siège - Ed. 0 dated February 25th 2010) Application document H-08-09-Siege_DA - Ed.0 - February 25th 2010	None.	26/03/2010	Active	10029480

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029481	APTOZ EHF.	REV. 1		B757-200 757-200	Navigation - Dependant Position Determining - Activation ofthe ADS-Bout function of the Transponder system.Rev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Applicant elected to comply with CS25amt 7.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the pr...	AFMS - AFM-757-3450-30 rev. AContinued Airworthiness Instructions CAI-757-3450-30 rev. BChange Approval CRA-757-3450-30rev. BCertification Plan 757-34-50-30 rev. BDrawing DWG-757-3450-30-1 rev. BDrawing DWG-757-3450-30-2 rev. Bor later revisions of the above listed document(s) approved/acceptedunde...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10029481
10029499	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	BEECH 90	Navigation/ communications systems upgrade.	CS-23The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.AMC20-4AMC20-5AMC 20-13The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to...	MDL1130-01 Issue 2CP-1130-01 Issue 1IPI-1130-01 Issue 1ICA-1130-01 Issue 1AFMS-1130-01 Issue 1AFMS-1130-02 Issue 2AFMS-1130-03 Issue 2or later revisions of the above listed documents approved by EASA.	None.	29/03/2010	Active	10029499
10029513 (EASA.A.S.02904)	M&D FLUGZEUGBAU GmbH & CO. KG			GLASFLUEGEL 304B	Modification of Glasfluegel 304B, S/N 324: retrofitting with winglets -modified wing tips: winglets.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.	STC "Nachruesten mit Winglets/ Retrofitting with Winglets" of sailplaneGlasfluegel 304B, S/N 324 by APDOAP EASA.AP.175.Amended Flight Manula for sailplane Glasfluegel 304B S/N 324; issueMarch 2010, EASA approved.Amended flutter statement by Prof. Dr. N. Niedbal, issued 15 March 2010.	Limited to Glasfluegel 304B, S/ N 324.	29/03/2010	Active	10029513
10029540	JET AVIATION AG, BASEL			MYSTERE FALCON 50 (MF50)	Runway Awareness and Advisory System (RAAS). Smart Runway Activation.i.a.w. Jet Aviation Master Data List BF5EX34461-001 Revision B or laterEASA Approved revisions.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.In addition compliance has been shown i.a.w. EASA CRI F-01 Issue 02"Activation of the Runway Awareness and Advisory System (RAAS)" that i...	See:·,,Jet Aviation Master Data List BF5EX34461-001 Revision B and·,,Jet Aviation Aeroplane Flight Manual Supplement BF5EX34461-201-01Revision IR·,,Jet Aviation Engineering Order (installation) BF5EX34461-344600Revision Bor later revisionsof the above listed documents approved by EASA	·,,This Jet Aviation Supplemental Type Certificate is applicable onMystere Falcon 50 EX (F50EX) version airplanes with an existing anddesign approved Honeywell EGPWS Mark V installation.·,,Caution alerts, terrain display text messages, take-off flapsconfiguration monitor, stabilized approach monitor...	30/03/2010	Active	10029540
10029541 (EASA.IM.A.S.02553)	AVIATION TECHNICAL SERVICES, Inc.		FAA STC ST00051SE	BOEING 737-400	Installation of a Collins Traffic Alert and Collision Avoidance System(TCAS II) Transmitter/Receiver per Goodrich ATS, Inc Top Drawing 93046Revision F dated 05 January 2001.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Goodrich ATS, Inc Top Drawing 93046 Revision F dated 05 January 2001- Airplane Flight Manual Supplement: Document D2000-181 OriginalRevision Approved by FAA on 22 February 2001.or later revisions of the above listed documents approved byEASA inaccordance with EASA ED Decision 2004/04/CF (or subse...	None.	30/03/2010	Active	10029541

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029542 (EASA.IM.A.S.02918)	SANDEL AVIONICS, Inc.		FAA STC ST01930LA	S550	Installation of Sandel Avionics SA4550 Primary Attitude Display andSandel Avionics SN4500 Primary Navigation Display.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Drawing List ST12361LA-T-01 Rev. M from 14 August 2008Airplane Flight Manual Supplement ST12361LA-T-10 Rev. Original from 04June 2007 for SA4550Airplane Flight Manual Supplement ST12361LA-T-30 Rev. Original from 30October 2006 for SN4500Instructions for Continued Airworthiness ST12361LA-T-05A...	None.	30/03/2010	Active	10029542
10029545	CASCADE AEROSPACE Inc.		TCCA STC SA01-40	DHC-8-3-1, -302 DHC-8-201, -202 DHC-8-102, -103, -106	Ground Air Connection ModificationTCCA STC SA01-40, Is.1, dated 14 March 2001	FAR 25 as per EASA.IM.A. 191The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this c...	-Installation of Air Ground Connection Modification is to be carried outin accordance with Conair Aerospace EngineeringOrder EO 2846, Rev. 1,dated 01 August 2002.-Maintenance is to be carried out in accordance with Conair AerospaceEngineering Maintenance Manual Supplement, MMS 2864-1, Rev. NIL, dat...	Placards have to be installed in accordance with Conair AerospaceEngineering drawing 2854D21501, Rev. D.	31/03/2010	Active	10029545
10029547 (EASA.A.S.03579)	SHORT BROTHERS PLCt/ a BOMBARDIER AEROSTRUCTURES &ENGINEERING SERVICES - BELFAST	REV. 1	CAA UK RESPONSIBILITY	A321-271N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-251N/-271N A320-216/-231/-232/-233 A320-111/-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115	V2500 NACELLE - RTI MONOLITHIC FAN COWL DOORRev. 1: Associated technical documents references amendment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Certification Compliance Checklist, Ref Doc SB-AWQ-ESTC-001, RevisionNC, 11th Dec 2009.2. Master Data List, ref, doc SB-V33SE-037, Revision NC, 11th Dec 20093. Maintenance Manual 71-13-03 Revision 0, 1st July 20164. Instructions for Continued Airworthiness, ref, doc, 71-13-03-ICA,Revision 0, 1st...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/12/2016	Active	10029547
10029548	365 AEROSPACE DDS LIMITED	REV. 3		737-600/-700/-800/-900	Introduction of a Dual Battery SystemRev. 3: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Conditions:CRI H-01 Issue 2 / Special Condition H-01 “Enhanced AirworthinessProgramme for Aeroplane Systems – ICA on EWIS”The requirements for environmental protec...	Aerospace Design <(>&<)> Engineering Consultants Modification SummaryMOD- 0702 Revision C dated 22nd March 2010Aerospace Design <(>&<)> Engineering Consultants EZA-0702 Revision Adated 10th November 2011	The STC holder shall monitor all documentary changes of thebasic AFMand related operational documentation issued by the TC-holder to assurethat those documents remain suitable tobe used operationally for theinstallation of dual batteriesunder this STC.Prior to installation of this design change i...	05/08/2019	Active	10029548
10029549 (EASA.R.S.01549)	MECAER AVIATION GROUP S.p.A.			MD HELICOPTERS 369HS	Installation of Emergency Locator Transmitter (ELT), Artex C406-2HM, P/ N369-25543-101	The Certification Basis for the original product remains applicable tothis certificate/ approval	-SEI RFMS - 369HS-1-1 at Rev A or later EASA approved revision-Report - SEI Description and CCL - ELT C406-2 Rev B dated 24 March 2010or later EASA approved revision-Report - SEI Notice of Design Change - NDC 369-005/1-or later revisions of the above listed documents approved by EASA	Not Applicable	31/03/2010	Active	10029549

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029552	ST ENGINEERING AEROSPACE LTD.			A320	Passenger Compartment Reconfiguration	In accordance with the EASA TCDS A.064 plus:The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval-CRI H-01/ Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICAT...	A320 LOPA STC Certification Plan, ref. doc. No. 360A023/AED/ 002,Revision C, dated 31st March 2010	None	31/03/2010	Active	10029552
10029553 (EASA.A.S.03788)	JET AVIATION AG, BASEL	REV. 1		B737-800	EMS SATCOM AMT-3800 Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 Issue 2 / Special Condition H-01 "Enhanced AirworthinessProgramme forAeroplane Systems - ICA on EWIS"The certificated noise and/ a...	Jet Aviation Master Data List No.: BB73723263-001, Rev. C, 07.06.2010or later revisions of the above listed documents approved by EASA	Not Applicable	12/07/2010	Active	10029553
10029554 (EASA.A.S.03517)	JET AVIATION AG, BASEL	REV. 1		AIRBUS A319-115	Airbus A319-115 "BCJ03513" VIP Cabin Interior CompletionRevision 1: Update of the Instructions for Continued Airworthiness	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCertification Review Item (CRI) G-4301-001 Issue 2 from 04 Nov. 2009"EASA Supplemental Type Certification Basis for Boutsen 1&2 VIP CabinI...	Airplane Flight Manual Supplement BCJ03513-201-01 Revision IR from 15March 2010Instructions for Continued AirworthinessBCJ03513-150-01 Revision C from02 Aug. 2010Master Data List BCJ03513-001 Revision C from 03 Aug. 2010Declaration of Compliance CAF 3607 from 03 Aug. 2010or later revisions of the...	Not Applicable	04/08/2010	Active	10029554
10029555	AIR COMM CORPORATION LLC		FAA STC SR00543DE	EC 130 B4	Installation of Cabin Air Conditioning System	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Air Comm Corporation Master Drawing List Report No DL-EC-130, RevisionU, dated 12/18/2009- Report EC130-03-10, dated March 16, 2010- Rotorcraft Flight Manual Supplement DocumentNo EC130B4-1 dated April1, 2004- Rotorcraft Flight Manual Supplement Document No EC130B4-2 dated March30, 2006 (Condense...	None	12/04/2010	Active	10029555
10029557	TRUATLANTIC MFG., LLC	REV. 2	FAA STC SA01539AT-D	U206, U206A, U206B, U206C U206D, U206E, U206F, U206G TU206E, TU206F, TU206G TU206A, TU206B, TU206C, TU206D TP206E TP206A, TP206B, TP206C, TP206D P206D, P206E 206, P206, P206A, P206B, P206C	Installation of Remote Oil Cooler in accordance with Atlantic Aero, Inc.Master Drawing List 16693001 Rev. Basic dated December 5, 1997, or laterFAA Approved revision	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA Approved Supplemental Flight Manual dated April 15, 1998 for thefollowing Models and Serial Numbers:Cessna U206E through U206G, TU206E through TU206G (Serial NumbersU20601445 through U20604649): Document 16693100FAA Approved Pilots Operating Handbook and FAA Approved Flight ManualSupplement date...	a) This approval should not be extended to other aircraft of this modelon which other previously approved modificationsare incorporated,unless it is determine by the installer that the interrelationshipbetween this change and any other previously approved modifications willproduce no adverse effect...	28/04/2016	Active	10029557

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029562	BUSINESS AND COMMUTER AIRCRAFT			BEECH C90A	BCA117 rev 0 - GPS replacement and aircraft capacity validation forB-RNAV, P-RNAV and GNSS approaches prodecures	The Certification Basis for the original product remains applicable tothis certificate/ approvalThis certificate/ approval involves a change to the certificated noiseand/ or emissions levels	-BCA117-06 rev 0 dated 10/12/2009 Airplane Flight Manual Supplement-BCA117-09 rev 0 dated 10/12/2009 Airplane Flight Maintenance ManualSupplementor later revisions of the above listed documents approved by EASA	Limited to: S/N LJ-1660	01/04/2010	Active	10029562
10029566	LEES AVIONICS Ltd.		CAA UK RESPONSIBILITY	COMMANDER 112, 114	Installation of Garmin G500/G600 PFD/ ND	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23EASA GM/G/001 has been applied.The certificated noise and/ or emissions levels of the original productare unchanged and remain applic...	-Master Data List MDL1097-01 Issue 3-Change Statement CS1097-01 Issue 2-Instructions for Continued Airworthiness ICA1097-01 Issue 1-Flight Manual Supplement AFMS1097-01 Issue 3or later revisions of the above listed documents approved by EASA	This change is limited to the configuration defined in Change StatementCS1097-01 Issue 2 or later approved revision.	01/04/2010	Active	10029566
10029569	AIR METHODS CORPORATION	REV. 1	FAA STC SR00705DE-D	S-76A, S-76B, S-76C	Installation of Articulated Patient Loading System (APLS).Note: The STC amendment adds an ALLFA litter as an option.	As described in FAA TCDS H1NEThe Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval14CFR Part 29 §29.785 (a),(b),(e),(k)(1)<(>,<)>(k)(2), which wereaddressed at the latest amendment 29-0 throug...	-Rotorcraft Flight Manual Supplement No. 080-0476, revisionA, datedJune 9, 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)-Master Drawing List S-76 APLS w/ Pedestal and AMC litter, Report N...	Required pre-modification Sikorsky cabin medical interior GA dwg. no.09076B10E001-1	19/08/2011	Active	10029569
10029570	ACC COLUMBIA Jet Service GmbH	REV. 1		HUSKY A-1, A-1A, A-1B, A-1C	Husky A1 Silencer STC Ext. To Variant A, B and CRev. 1 Transfer to ACC Columbia Jet Service GmbH	CS-23.CThe Certification Basis for the original product remains applicable tothis certificate/ approval	-Master Document List MDOCL_21750_rev0_2010 0301-Airplane Flight Manual Supplement SPOH_21750_rev0_20100 301-InstallationInstruction II_21750_rev0_20100301or later approved revisions of the above listed documents	As referred in limitations section of the AFM-S:Airplane Flight Manual Supplement SPOH_21750_rev0_20100301	20/01/2022	Active	10029570
10029583 (EASA.A.S.03461)	AIR ALLIANCE GmbH			LEARJET 35A	Installation of new avionics (FDR, TAWS, FMS, RDR/KMD)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalTGL No. 10 (P-RNAV) TGL No. 12 (TAWS)AMC 20-4 (B-RNAV)TGM 21/07 (Electrical Wiring)The certificated noise and/ or emissions levels of the o...	Refer to Master Document List 2008_006_A10CE AA Form 2 (Rev. 7)or later revisions of the above listed documents approved by EASA	Approval valid for s/n 35A-616 only	02/04/2010	Active	10029583
10029589	BOMBARDIER INC.		TCCA STC SA10-19	BD-700-1A10	Installation, Upgrade from Swift 63 to Swift Broadband	EASA IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-TCCA STC No. SA10-19 Issue 1 dated 08 February 2010.-TCAA SoC ref. C-10-0232 dated 24 March 2010.-ACS-NAI Ltd. Modification Data Summary Number G541000 Revision NC orlater approved revision.-Instructions for Continued Airworthiness G541071 Revision NC or laterrevision.or later revisions of the abov...	None	02/04/2010	Active	10029589

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029611 (EASA.IM.R.S.01407)	RSG PRODUCTS, Inc.	REV. 1	US SR09178RC	600N	Integrated Flight Systems Vapor Cycle Air Conditioning System	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Master Drawing list DL-44 Rev B, 15th March 2001.Electricalrouting Drawing 2-MDHS 600NStructural Substantiation reportIFS-600S-01Structural Substantiation report IFS-600S-02Structural Substantiation report IFS-600S-03Structural Substantiation report IFS-600S-04Structural Substantiation report IFS-...	None	29/06/2010	Active	10029611
10029619 (EASA.IM.A.S.03127)	MCCAULEY PROPELLER SYSTEMS		FAA STC SA01511WI	C400 (LC41-550FG)	Installation of McCauley C447	CS-23.CThe Certification Basis for the original product remains applicable tothis certificate/ approvalThis certificate/ approval involves a change to the certificated noiseand/ or emissions levels	-Installation Instructions No 985 Rev (B) including-Airplane Flight Manual Supplement No 988, Rev (IR)-Maintenance Manual Supplement No 989 Rev (A)or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)...	As referred in limitations section of the AFM-S	06/04/2010	Active	10029619
10029626 (EASA.IM.A.S.02964)	WINGLET TECHNOLOGY, LLC	REV. 1	FAA STC ST01545WI	750	Installation of winglets, wing structural reinforcement, and relatedsystem changes.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Winglet Technology Master Drawing List D10-2000, Rev. B, dated 16 June2009, or later FAA approved revision.FAA approvedAirplane Flight Manual (AFM) Supplements and Weight andBalance Manual Supplements.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.See Winglet Technology Maintenance Manual Supple...	25/10/2018	Active	10029626
10029628	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9336	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Transport Canada SoC reference C-10-0275 dated 07 April 2010.-TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.-Aero Consulting Services Configuration Definition List D954000 RevisionED dated 31 March 2010.-Instructions for Continued Airworthiness GC93360000-IFCA.or later revisions of the abovea...	Restricted to ASN 9336 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	08/04/2010	Active	10029628
10029629	BERINGER AERO	REV. 7		PC-6/B2-H2, PC-6/B2-H4 PC-6/A2-H2, PC-6/B1-H2	Installation of Beringer brakes.Revision 1: Update with an optional small main wheel.Revision 2: Update with an optional axle, update of manuals.Revision 3: Update with an additional brake disc.Revision 4: Update with an additional brake pad.Revision 5: Update with wear limit modification.Revision 6...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification file: DM-STC-002 rev 7 dated 08 Dec. 2022;Installation and Instructions for Continued Airworthiness: ICA-STC-002rev 09 dated 13 Dec. 2022;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2022	Active	10029629
10029641	KEYSTONE HELICOPTER CORPORATION		FAA STC SR02588NY-D	S-76C	Installation of Goodrich Auxiliary Utility Hoist	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalAs specified on FAA STC SR02588NY-DThe certificated noise and/ or emissions levels of the original productare unchanged and remain applica...	-RFMS FM01464 Rev 0 dated 2 Oct 2009 or later approved revision.-Instructions for Continued Airworthiness IC01464 Rev 0dated 15 May2009.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision.-Installat...	As specified in the approved RFMS	08/04/2010	Active	10029641

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029642	WIPAIRE Inc.		FAA STC SA914NE	CESSNA 206 SERIES	Installation of Wipaire, Inc. wing tip extensions in accordance to FAASTC SA914NE.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Wipaire, Inc. Master Drawing List number W-MD126, dated April 30, 2001or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Placard "VNE = 165 Knots" is required with this installation.	08/04/2010	Active	10029642
10029659	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE		TCCA LSTC O-LSA09-37/D	B737-800	Interior Reconfiguration & miscelaneous Cabin Alterations /Modification and relocation of the passenger seats along withrelocation/installation of emergency equipments.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-TCCA LSTC Number: O-LSA09-37/D Issue 1 dated Feb 03, 2009-DECA Modification summary MS08165 dated Feb 03, 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision)	Valid for MSN 30292 only	09/04/2010	Active	10029659
10029662 (EASA.A.S.03876)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		737-300	B737 STC - ATL- Remove EWIS LimitationRev. 2: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Modification Summary Sheet: MOD-11348-00001 Issue 3 dated16 July 2015- Master Document List: MDL-11348-00001 Issue 3dated 15 July 2015- Airplane Flight Manual Supplement: 11348-AFM-00001 Issue 2- Enhanced Zonal Analysis: EZA-11348-00001, Issue 3, dated 15 August2013.or later revisions of the abo...	Limited to following aircraft S/N only: 737-300 MSN 23774.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the produ...	10/11/2021	Active	10029662
10029669 (EASA.A.S.03764)	DASSAULT FALCON SERVICE			FALCON 900EX	F900EX Serial Number 111 aircraft completion definition	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCompliance has been shown in accordance with the requisites laid down byEASA CRI F-002 "In-Seat Power Supply Systems (ISPSS)" Issue 2 andC...	-DFS Change Approval Sheet DFS 9565-CAS Issue A dated 30th March 2010-DFS Master Document List DFS-DE-17-FE-9565, IssueA dated 16th October2009-DFS Modification Sheet DFS 9565, Issue A dated 29th October 2009or later revisions of the above listed documents approved by EASA	This EASA design change airworthiness approval is applicable on Falcon900EX serial number aircraft 111	12/04/2010	Active	10029669
10029675	COMPAGNIA GENERALE RIPRESEAEREES .p.A. - CGR S.p.A.			PA 31-350	GPS Garmin 430 for IFR	EASA CS 23 Amendment 1The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval	AFMS P/N CGR P003-00-SICA P/N CGR P003-00-lor later revisions of the above listed documents approved by EASA	The installation of EASA approved modification EASA.A.C.07903 isrequired.	12/04/2010	Active	10029675
10029676	MT-PROPELLER ENTWICKLUNG GmbH			206H, T206H	Installation of 5-blade MTV-5-1-D-C-F-R (A)/CFR210-56 propeller on CessnaModel 206H, T206H equipped with Rolls-Royce 250-B17F/2 series engine perFAA STC No. SA01878SE	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR 23, Amendment54This certificate/ approval involves a change to the certificated noiseand/ or emissions levels	-Airplane Flight Manual Supplement, Doc. No. E-1830, Original Issuedated 01.12.2009- Installation Instructions, Doc. No.E-1831, Original Issue dated01.12.2009- Instructions for Continued Airworthiness, Doc. No. E-1832, OriginalIssue dated 01.12.2009or later revisions of the above listed documents app...	Prior to installation of this STC modification i.a.w. EASA STC 10027209(Soloy Mark II Turbine Conversion) is required	12/04/2010	Active	10029676

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029677	LUFTHANSA TECHNIK AG			A310-304	Fuselage - Structural provisions and Satcom antenna installation, Satcomequipment rack installation and VHF antenna installation.This STC installs Satcom and VHF antennae, as wellas the provision forthe future support of a Satcom system installation.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 Issue 1The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certifi...	-Supplement Type Definition Document, ref : STDD53-09/01M, Issue 1,dated 02 March 2010-Engineering Bulletin, ref: A310-EB53-0308 Issue 3-Engineering Bulletin, ref: A310-EB53-0309 Issue 2-Engineering Bulletin, ref: A310-EB53-0311 Issue 1-Instruction for Continued Airworthiness:-Maintenance Requiremen...	Limited to: MSN 484	12/04/2010	Active	10029677
10029679	WIPAIRE Inc.		FAA STC SA1470GL	U206E, U206F, U206G, TP206A, U206A, U206B, U206C, U206D, TU206E, TU206F, TU206G TP206C, TP206D, TU206C, TU206D P206B, P206D, P206E, U206, 2) CESSNA 206, P206, P206A, 1) CESSNA 206H, T206H	Installation of right front cabin door in accordance with Wipaire, Inc.installation drawing number 3D1-1101	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation drawing number 3D1-1101, no revision, dated February 15,1990or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	12/04/2010	Active	10029679
10029680	AVIATION ENGINEERING AS	REV. 1		AS365N SERIES AS 365 N2, AS 365 N3	EMS Cabin Layout Kit DO-365-25-105Rev. 1: Transfer from AIRLIFT AS to AVIATION ENGINEERING AS.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement, FMS-365-25-105 Revision 3Instructions for Continued Airworthiness, ICA-365-25-105-01 Revision2Master Document List, MDL-365-25-105 Revision 3EngineeringOrder, EO-365-25-105 Revision 2Or later revisions of the above listed document(s) approved/acceptedunder the EASA system...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/06/2025	Active	10029680
10029681	AEROLITE AG	REV. 3		EC135T2(CPDS), EC135T2+ EC135T1(CDS), EC135T1 (CPDS), EC135P2(CPDS), EC135P2+ EC135P1(CDS), EC135P1 (CPDS),	Utility Missions Interior P/N 135736-502Revision 1:This major change to EASA STC No. 10029681 dated 12.04.2010 covers theintroduction/ modification of the following components into the UtilityMissions Interior P/N 135736-502:- Introductionof the Seat FWD LH, RH and MID in the forward part of thepas...	JAR 27 Arndt: 1st issueThe Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement: FMS-135736-502 rev N/C dated 24 April 2012;Airworthiness Limitation: OPM-135736-502 rev N/C dated 26 April 2012;or later revisions of the above listed documents approved by EASAMaster Document List: MDL-10-002 revA dated 18 July 2012;	None.	02/07/2019	Active	10029681
10029687 (EASA.A.S.03810)	RUECKER AEROSPACE GmbH			B747-400	Installation of 2 single B/E Aerospace DS9000 steam ovens and 2 OCM9000Oven Control Modules per B/E Aerospace Engineering OrderEO-253-00002-001 Rev. A. or later approved revision	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01 Enhanced Airworthiness Programme for Aeroplane Systems – ICA onEWISfor oven installation.	B/E Aerospace Aircraft Maintenance Manual Supplement 43208-SM-01B/E Aerospace Component Maintenance Manual CMM 25-35-75or later revisions of the above listed documents approved byEASA	None.	13/04/2010	Active	10029687
10029701 (EASA.A.S.03951)	CESKA LETECKA SERVISNI A.S.			SUKHOI SU-31	Avionics upgrade.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23.	AC190-2501 GARMIN SL 40 Comm Transceiver (COM), December, 2009AC190-2502 GARMIN GTX 328 mode S transponder (XPDR), December, 2009	None.	14/04/2010	Active	10029701

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029711	ERWIN AERO INTERNATIONAL LTD.	REV. 1	TCCA LSTC C-LSA09-321/ D	DHC-6-300	Avionics to installed in acc. with PAA Design Group Modification DataSummary: R0910773, Issue A, approved 31 December 2009 with TransportCanada approved Flight Manual Supplements in acc. to TCCA STCC-LSA09-321/D	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Flight Manual Supplements:-R0910775, Issue A, Collins DME-42 Distance Measurement Equipment-R0910776, Issue A, Collins ALT-55 Radio Altimeter-R0910777, Issue A, Collins ADF-60 Automatic Direction Finder-R0910778, Issue A, Collins TDR-90 Transponder-R0910779, Issue A, Bendix RDS-82 WX Radar-R0910780,...	Limited to: S/N 840 only	19/04/2010	Active	10029711
10029712 (EASA.IM.R.S.01380)	DART AEROSPACE Ltd.		TCCA STC SH07-36	A119 & AW119 MKII	TCA STC SH07-36 Issue 2 "Replacement Windows Kit" - D119-755-011/-14 -This STC involves removing of the existing windowand installing a flatwindow (-011) in LH or RH crew door orinstalling a bubble window (-14)in the RH crew door)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	FMS - D119-755 Rev. Cor later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision)	Not Applicable	15/04/2010	Active	10029712
10029716 (EASA.A.S.03907)	airplus engineering GmbH	REV. 2		SEE APPROVED MODEL LIST (AML)	Enabling of SVT Functionalities on Garmin G5/600 Avionics System (Revision of EASA STC 10029716)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS-23 Amendment02 (not required by21A.101).The requirement for environmental protection and the associatedcertificated noise and/ or em...	Flight Manual Supplement PO-0491-340000 Rev. 2or later revisions of the above listed documents approved by EASAEngineering Work Order EW-0491-340000 Rev. 2Description of modification: DE-0491-0000000, Rev. 2	The aircraft must have been already equipped with Garmin G5/600System(s) according to EASA STC 10029716	10/02/2021	Active	10029716
10029724 (EASA.A.S.03861)	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBIL ITY	PA-28	Installation of Garmin G500/G600 EFIS PFD/ND.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23.EASA GM GA/G/ 001 has been applied.The certificated noise and/ or emissions levels of the original productare unchanged and remain a...	Master Data List MDL1050-02 Issue 1Change Statement CS1050-02 Issue 1Instructions for Continued Airworthiness ICA1050-02 Issue 1Flight Manual Supplement AFMS1050-02 Issue 1or later revisions of the above listed documents approved by EASA	This change is limited to the configuration defined in Change StatementCS1050-02 Issue 1 or later approved revision.	15/04/2010	Active	10029724
10029726	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBIL ITY	PIPER PA-28					16/04/2010	Active	10029726
10029736 (EASA.A.S.03144)	ACC COLUMBIA Jet Service GmbH	REV. 1		CESSNA 421B	Installation of Silver Jodide Generators on Cessna 421BRev.1 Transfer to ACC Columbia Jet Service GmbH	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR 23, amendments 1 through 7 (not required by 21A. 101, elected tocomply by the applicant)This certificate/ approval involves a change to...	- Flight Manual Supplement SPOH_16351_rev1_15032 009 (dated 15.03.2009)- Master Document List MDOCL_16351_rev1_1204 2010or later revisions of the above listed documents approved by EASA	Not Applicable	26/01/2022	Active	10029736
10029773	B/E AEROSPACE LIMITED	REV. 2	TCCA STC SA10-4 ISSUE 2	PC-12/47E	Main battery No. 2 relocation.Validation of the TCCA STC SA10-4: Relocation of the main battery No 2from the tail section to the engine compartment.	FAR 23The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirementsfor environmental protection and the associatedcertificatednoise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	- Modification Data Summery, Doc. No. G409000 Rev. C- Pilot's Operating Handbook Supplement, Doc. No. G409091 Rev. N/C-ICA: Maintenance Manual Supplement, Doc. No. G409071 Rev. B& IPC,Doc. No. G409072 Rev. Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED...	None.	17/03/2021	Active	10029773

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029774	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9341	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Transport Canada SoC reference C-10-0151 dated 08 April 2010.-TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.-Aero Consulting Services Configuration Definition List D954000 RevisionEE dated 31 March 2010.-Instructions for Continued Airworthiness GC93410000-IFCA.or later revisions of the abovea...	Restricted to ASN 9341 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	20/04/2010	Active	10029774
10029784	BEECHCRAFT CORPORATION		FAA STC REF SA02277LA	B300 KING AIR	Installation of High Definition Audio Video (HDAV-3002) LRUUnit as aninterface with the Rockwell Collins Venue Cabin Management System.	FAR 23The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Install in accordance with Rockwell Collins System Drawing List ref441-0130, Rev B, dated December 15, 2009Continued Airworthiness Document, General Aviation - Rockwell CollinsCabin Systems, P/N 442-1306-001, Rev New, dated 11/11/09or later revisions of the above listed documents approved by EASA in...	Only applicable to King Air Model B300 aircraft equipped with theRockwell Collins Venue Cabin Management System.	20/04/2010	Active	10029784
10029795	AEROACOUSTICS AIRCRAFT SYSTEMS, INC		FAA STC SA02042SE	CESSNA 208	Aircraft Payload Extender (APE) STOL System for Cessna 208 and 208A inacc. to FAA STC SA02042SE	The Certification Basis for the original product remains applicable tothis certificate/ approvalThis certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels	-AASI Master Drawing List No. AA2034, Rev. B, dated December 15, 2009-AASI Installation and Maintenance Manual No. 2014, Rev. B, datedJanuary 6, 2010-AFMS-C208-45, "Aircraft with PT6A-114A (675 SHP) engine", dated January6, 2010-AFMS-C208-46, "Aircraft with PT6A-114 (600 SHP) engine", dated January6...	Note 1:This modification is also applicable to the following aircraft that havebeen modified with Wipaire, Inc. STC No.SA149CH (675 SHP PT6A-114AEngine Installation).Model,,Serial Number,,,,,,Note208,,,,2080001 through 20800060,,Eligible only if modified with CessnaKit SK-208-12,,,,20800061 and up2...	21/04/2010	Active	10029795
10029799	INDIGOSAT			208 / 208B	Installation of IndigoOne Satellite Tracking and Communication System(Kit Part No. IGO1_MA1236_01R1-1) in accordance with CASA (Australia)STC SVA 513	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation Manual IS-IM-2007-001, Issue B, dated 27. February 2008or later revisions of the above listed documents approved by EASA	Effected S/N see in Installation Manual IS-IM-2007-001, Issue C	21/04/2010	Active	10029799
10029813	LE BOZEC FILTRATION & SYSTEMES SAS	REV. 2	FAA STC ST09864SC	737-400, -500 737-100, -200, -200C, -300	Rain Repellent System Modification - Modification of Rain RepellentSystem in accordance with "Le Bozec, Inc." documents.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	B737 series Rain repellent Installation- Top Drawing List - Ref. 990110000 Rev.A dated 18/04/2001-Engineering order -Ref. 99010800 Rev.A dated 11/04/2001or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis d...	Only applicable to Rain repellent systems that were installed at time ofairplane production under TC EASA IM.A.120 or FAA TC A16WE.	06/08/2012	Active	10029813

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029814	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-46-500TP, PA-46R-350T PA-46-310P, -350P,	Installation of a Stormscope Avidyne TWX670	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23, Initial Issue (not required by 21A.101, elected to comply by theapplicant)The certificated noise and/ or emissions levels of the or...	Project Description: ASR-2009-015-PRD-04-00, Rev. 00Instructions for Installation: ASR-2009-015-IFI-10-00, Rev. 00Instructions for Continued Airworthiness: ASR-2009-015-ICA-11-00,Rev.00Flight Manual Supplement: ASR-2009-015-FMS-05-00, Rev. 00or later revisions of the above listed documents approved...	None	22/04/2010	Active	10029814
10029817	AVIATION FABRICATORS, Inc.	REV. 1	FAA STC ST01572WI	400A 400	Change to STC 10029817Beechjet 400 Cabin Configurations, Divan Installations.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of four (4) model 400A OEM seats, one (1) two place divan,one (1) three place divan, one (1) aft toilet, one (1) set of aft pocketdoor dividers, one (1) set of forward pocket door dividers, or LEDlighting, per the following:-1),,Master Data List AF-475, Rev D, dated December 11, 2009 o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/05/2013	Active	10029817
10029820 (EASA.IM.R.S.01450)	VIH AEROSPACE Inc.		TCCA STC SH06-26	S-92A	Auxiliary Fuel Tank Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	VS92-371-FMS revision 5 dated 22 August 2007 - Flight manual Supplementor later revisions of the above listed documentsapproved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision) VS92-371-MDL revision 5 dated 17 September 2007 - Master Drawing List;VS92-3...	None.	22/04/2010	Active	10029820
10029821	AEROACOUSTICS AIRCRAFT SYSTEMS, INC	REV. 2	FAA SA01805SE	208B	Fabrication and installation of AeroAcoustics Aircraft Systems, Inc. (AASI) Aircraft Payload Extender STOL System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Manufacture in accordance with AASI Master Drawing List No. AA1977,Revision J, dated July 22, 2016, and installed inaccordance with AASIInstallation and Maintenance Manual No.AA1976, Revision J< (>,<)>dated March 16, 2016.2. Operation in accordance with Approved Aircraft Flighty ManualSupplement...	It is the installers responsibility to ensure any Textron kits or STC'sreferenced in this STC and installed on the aircraft have been EASAapproved.Limitations Pertaining to all eligible models: -LIMIT SPEEDS (IAS): Maneuvering Speed at 9062 lb, 143 KIASLIMIT FACTORS (g's): Flaps up: +3.36, -1.34LIMI...	09/04/2021	Active	10029821
10029833	AERO CONSULTING SERVICES LTD.		TCCA STC SA10-9	CL600-2B16 CL600-1A11, CL600-2A12,	Transport Canada STC No. SA10-9 Issue 1 dated 08 February 2010.ACS-NAI Ltd. Modification Data Summary Number G373000 Revision N/C orlater approved revision.Instructions for Continued Airworthiness G373071 Revision A and G373072Revision N/C, or later approved revisions.or later revisions of the above...	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval		None	23/04/2010	Active	10029833
10029836	GVH AEROSPACE LIMITED			BOEING 737-800	164 Passenger Layout.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Compliance Document BAC/737/131 Issue 7- Instructions forContinued Airworthiness ICA/114/681 Issue1or later revisions of the above listed documents approved by EASA	None.	23/04/2010	Active	10029836

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029849	AIR CRUISERS COMPANY		FAA STC SR02538NY	BELL 407	Bell 407 Emergency Float Kit P/N 67432-101Note: This STC isfor the installation of the Pneumatic ActivationSystem only.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	EDN3379 revision IR dated 27 June 2008 - Rotorcraft Flight ManualSupplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) EDR No. 20-1457 revision B dated 17 April 2008 - Installation Data List;...	For installation only on Bell 407 models previously equipped with theBell Emergency Float Gear Skid tubes BHT P/N 206-053-184-121 and206-053-184-122 or approved equivalents.The ACC Bell 407 Emergency Float Installation Kit is used in conjunctionwith the float bags Type Certified per TCCA TC H-92 (Be...	26/04/2010	Active	10029849
10029850 (EASA.IM.A.S.02613)	AVIATION TECHNICAL SERVICES, Inc.		FAA ST00631SE-D	737-800	Interior Reconfiguration - Installation of an Interior Arrangement,Entertainment System Components and Avionics Components.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Goodrich Master Data List 2001-335 Rev. E dated 21/10/2002or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Not Applicable	26/04/2010	Active	10029850
10029856	AVIONIK STRAUBING ENTWICKLUNGS GmbH			2) M20M, M20R, M20S 1) M20J, M20K, M20L, 1) M20C, M20E, M20F, M20G,	Installation of a Garmin G500 System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23, Initial Issue (not required by 21A.101, elected to comply by theapplicant)The certificated noise and/ or emissions levels of the or...	Instruction for Installation: ASR-2010-010-IFI-10-00, Rev. 00Instructions for Continued Airworthiness: ASR-2010-010-ICA-11-00, Rev.00Flight Manual Supplement:ASR-2010-010 -FMS-05.1-00, Rev. 00ASR-2010-010-FMS-05.2-00, Rev. 00or later revisions of the above listed documents approved by EASA	None	26/04/2010	Active	10029856
10029869	AVIATION FABRICATORS, Inc.		FAA STC NO. SA00961WI	PA-42, PA-42-720, PA-42-1000 PA-31T2, PA-31T3, PA-31 PA-31P, PA-31T, PA-31T1 PA-31-325, PA-31-350	Stretcher Installation per Aviation Fabricators, Inc. STC Drawing List,Doc. No. AF-204	Design:Non-significant changeThe Certification Basis of theoriginal product remains applicable tothis changeEnvironmental Protection:The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	FAA approved STC Drawing List, Doc. No. AF-204, Rev. (D), dated20Jan-2010, or later FAA approved revisionApproved Instructions for Continued Airworthiness, Doc. No. AF-489, Rev.(A), dated 07-Jan-2010, or later approved revision	The installer is responsible for ensuring that the installation complieswith any supplemental oxygen requirements as required for operation	27/04/2010	Active	10029869
10029872	ELLIOTT AVIATION		FAA STC STC02784CH	BEECHJET 400/400A	Installation of Honeywell Digital Flight Data RecorderValidation of FAA STC STC02784CH	The Certification Basis for the original product remains applicable tothis certificate/ approval	-Elliott Aviation Master Data List, Report No. MDL-3001-573, Rev. B,dated December 16, 2009-FAA Approved Flight Manual Supplement, Elliott Aviation Report No.FMS-3001-573, Revision IR, approved December 14, 2009-Instructions for Continued Airworthiness Limitations, Elliott AviationReport No. ICA-300...	None	28/04/2010	Active	10029872
10029873	ELLIOTT AVIATION		FAA STC STC02783CH	BEECHJET 400	Installation of an Artex C406-2 Emergency Locator Transmitter (ELT) Validation of FAA STC STC02783CH	The Certification Basis for the original product remains applicable tothis certificate/ approval	-Elliott Aviation Master Data List, Report No. MDL-3010-578, Rev. A,dated November 30, 2009-FAA Approved Flight Manual Supplement, Elliott Aviation Report No.FMS-3010-578, Revision IR, approved December 2, 2009-Instructions for Continued Airworthiness Limitations, Elliott AviationReport No. ICA-3010...	None	28/04/2010	Active	10029873

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029877	ARMSTRONG AEROSPACE Inc.		FAA STC ST02776CH	B737-300, B737-500	Activation of Honeywell Runway Awareness and Advisory System (RAAS)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The certificated noise and/ or emissi...	Armstrong Aerospace documents:-Master Data List - DC104-7006-00 Rev D dated 10 Nov 2009-AFM Supplement document DC303-7006-00 approved on 04 Nov 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decisio...	None	28/04/2010	Active	10029877
10029878	FORCED AEROMOTIVE TECHNOLOGIES		FAA STC SE10233SC	O-470-L, -R, -S, -U	Installation of a Belt-Driven Vortech V-1S supercharger assembly on theTeledyne Continental Motors (TCM) O-470-L, O-470-R, O-470-S, and O-470-Uengines in accordance with Type Inspection Data contained in MasterDrawing List No. MDL-182-1-E,Rev. D, dated January 4, 2005, or laterFAA approved revision...	CAR 13The Certification Basis for the original product remains applicable tothis certificate except for JAR-E 10, E 20,E 25, E 40, E100(b), E80, E70, E 220, E 270, E 360 which are amended by JAR-E Change 10	Instructions for Continued Airworthiness are contained in Document No.22002-05, Rev. A, dated January 4, 2005, or laterrevisions approved byEASA in accordance with EASA ED Decision 2004/04/CF (or subsequentrevisions of this decision)	The supercharged O-470-L, -R, -S, and -U engines are limited to 28 inHg(193 kPa) MAP and 2600 RPM or 230 HP (171.5 kW) with minimum fuel gradeAvgas 100LL.	28/04/2010	Active	10029878
10029879	STANDARD AERO		FAA STC SE02357NY	PT6A-135A	Installation of the Pratt & Whitney Canada, PT6A-135, dual fuel feedline configuration in accordance with Standard Aero, Inc. EngineeringReport, 001-07-01, Rev. 0, dated February 07, 2007.	FAR Part 33, effective 1 February 1965, and Amendments 33-1to 33-5inclusiveThe Certification Basis for the original product remains applicable tothis certificate/ approval	Standard Aero, Inc. Instructions for Continued Airworthiness, ReportNumber 001-07-ICA, Rev. 0., dated February 07, 2007,or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Not Applicable	28/04/2010	Active	10029879
10029892 (EASA.A.S.03869)	COMPAGNIE FRANCE AVIATION			GARDAN GY80-160	Installation of Aspen Avionics EFD1000 PRO, 1 Garmin GMA340, 1 GarminGNS 430 and 1 Kannad 406MHZ AF Compact in the GARDAN GY-80 series.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	AFM temporaire N1AFM temporaire N2Limitation VFR de jouror later revisions of the above listed documents approved by EASA	None.	30/04/2010	Active	10029892
10029901	GOODRICH INTERIORS	REV. 1	FAA STC ST01472LA-D	747-300, 747-400, 747-SP 747-100B SUD, 747-200B, 747-100, 747-100B,	Installation of Hollingsead International Sentry One Cockpit Entry DoorSurveillance Camera System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Hollingsead International Master Data List No. 2763-01, Revision NCdated 25/05/2004- Hollingsead International FAA Flight Manual Supplement, document No.2763-AFM< (>,<)> revisionNC, dated May 25, 2004- Hollingsead International Flight Manual Supplement, document No. 2763-AFM-1, revision NC, dated J...	None	08/11/2012	Active	10029901
10029915	AEROLITE AG			EC135 T2(CPDS), EC135 T2+ EC135 T1(CDS), EC135 T1(CPDS), EC135 P2(CPDS), EC135 P2+, EC135 P1(CDS), EC135 P1(CPDS),	EMS Equipment P/N 135710-502	JAR 27 Issue 01 i.a.w. TCDS EASA.R.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Flight Manual Supplement FMS-10-001 Rev. N/Cor later revisions of the above listed documents approved by EASA-Operations Manual OPM-10-001 Rev N/C-Master Document List MDL-10-001Rev. N/C	Limited to: S/N 870 and subsequent	03/05/2010	Active	10029915
10029917	BEECHCRAFT CORPORATION		FAA STC ST10599SC-D	800XP, 850XP, 900XP	Installation of an Espresso Maker	FAA CAR 4b <(>&<)> 14 CFR Part 25	Installation of an Espresso Maker in accordance with STC RequiredDocuments List (RDL) No. 230-2003 Revision 5 dated January 14, 2010, orlater approved revision.	This modification requires the installation of FAA STC ST10385SC-D,Installation of a Rockwell Collins CMS-1 Cabin Management System.	03/05/2010	Active	10029917

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029922	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE	REV. 1	TCCA LSTC O-LSA09-040/ D	B737-800	Sliding Carpet Loading System Removal/ Deactivation.Revision1: Removal of limitation on aeroplane MSN.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	TCCA STC O-LSA09-040/ D, issue 3, dated 02 April 2012DECA Modification Summary MS09024 Rev. 5DECA Instructions for Continued Airworthiness ICA9024 Rev. 4or later revisions of the above listed documents approved by EASA inaccordance with theTechnical Implementation Procedures of EU/ CanadaBilateral A...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/01/2018	Active	10029922
10029931	EUROCOPTER UK Ltd.	REV. 1	CAA UK RESPONSIBILITY	MBB-BK117 C-2	Cabin Configuration - Installation of Police or Emergency Medical SystemRole Equipment	The Certification Basis for the original product remains applicable tothis certificate/ approval	-Flight Manual Supplement No. 16, Issue No. 1-Design ReportDR/1451230-001 Issue A dated 15 May 2010or later revisions of the above listed documents approved by EASA	None	11/06/2010	Active	10029931
10029935	SAAB AB	REV. 2		MU-2B	Installation Provisions/Video Signal in Mitsubishi MU-2B rear pressurebulkheadRev. 1: Transfer from SAAB AB, NYKÖPING to SAAB AKTIEBOLAG.Rev. 2: Correction of DOA reference.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23 Amdt. 1, dated 12 February 2009.The requirements for environmental protection and the associatedcertif...	TDM10-03 as described in TDM10-03-LEP Revision A dated 2010-04-30.	Target Towing provisions according to Swedish CAA approval C6A/71 mustbe installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the a...	07/12/2023	Active	10029935
10029936	NSE INDUSTRIES S.A.	REV. 4		AS350 B, AS350 B1, AS350 B2, AS350 B3, AS350 BA, AS350 BB.	Installation of DTSV2 Data Transmission systemNote: Rev. 4 of this STC covers DTSV2 system upgrade due to componentsobsolescence, software update, small hardware changes and revision ofSTC Data List SDL-DTSV2-AS350.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS27 Amdt 2. paragraphs 27.29, 27.301, 27.303, 27.305, 27.307, 27.561,27.773, 27.1301, 27.1309, 27.1351, 27.1357, 27.1361,...	Rotorcraft Flight Manual Supplement for DTSV2 Data Transmission System,doc. RFMS-DTSV2-AS350 Rev.00 dated 28 October 2013or later revisions of the above listed documents approved by EASA.STC Data List: SDL-DTSV2-AS350 Rev 01 dated 02/09/14	Modification not approved for aircraft equipped with Weather Radar orAFCS (Automatic Flight Control System) incorporated.The installation of this modification by third persons is subject t...	29/09/2014	Active	10029936
10029937	S-TEC CORPORATION		FAA STC SA09140AC-D	210, 210A, 210B, 210C	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-621 (14 Volt System)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-FAA Approved S-TEC Bulletin No. 721, dated 18-July-01, Revision 3, orlater revision-FAA Approved S-TEC Master Drawing List No. 92899, dated 18-July-01,Revision C, or later revision-FAA Approved Supplemental Flight Manual, P/N 891234, Revision 2, dated18-July-01 or later approved revision is require...	None	04/05/2010	Active	10029937
10029942	DRF STIFTUNG LUFTRETTUNGGEMEINNUETZIGE GmbH			MBB-BK 117 B-2, MBB-BK 117 C-1	Installation of Garmin GNS 530 FMS COM/NAV System and TCAS-1 Sky 899TCAS	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS29 Amdt. 2Thecertificated noise and/ or emissions levels of the originalproductare unchanged and remain applicable to this certifica...	-Flight Manual Supplement SKY-899 TCAS I FMS-10-DRF-003 Rev. A-Flight Manual Supplement GNS-530W, FMS-10-DRF-004 Rev. Aor later revisions of the above listed documents approved byEASA-Master Document List MD-117-34-60-00001 Rev. A-ICA CA-117-34-50-00012 Rev. A-ICA CA-117-34-60-00001 Rev. A	Not Applicable	04/05/2010	Active	10029942

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029947	AVIONIK STRAUBING ENTWICKLUNGS GmbH			CESSNA 340, 340A	Installation of Thommen AD32 Air Data Display/Altimeter andAvionikStraubing Altitude Preselect System APS4A	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23, Amdt. 1Thecertificated noise and/ or emissions levels of the originalproductare unchanged and remain applicable to this certifica...	-Instructions for Installation: ASR-2009-025-IFI-10-00, Rev. 0-Flight Manual Supplements: ASR-2009-025-FMS-05-00, Rev. 0-Instructions for Continued Airworthiness: ASR-2009-025-ICA-11-00, Rev.0or later revisions of the above listed documents approved by EASA	None	05/05/2010	Active	10029947
10029953 (EASA.A.S.03531)	JET AVIATION AG, BASEL	REV. 1		B737-800	VIP Cabin Interior Outfitting	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI A-01 Issue 4for this project dated 09.07.2010.The requirements for environmental protection and the associatedcertificated noise and...	Jet Aviation Documents:- Master Data List: BBJ37545-001 Rev.D dated 09. July 2010-AFM Supplement: BBJ37545-201 Rev. E-Inst. for Continued Airworthiness: BBJ37545-150-01 Rev. IRor later revisions of the above listed documents approved by EASA	Limited to: S/N 37545	12/07/2010	Active	10029953
10029956	AIR CRUISERS COMPANY		FAA STC SR02633NY	BELL 206 L-4	Bell 206L-4 Emergency Float Kit P/N 67585-101	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-EDN3358 revision IR dated 22 December 2008 - Rotorcraft Flight ManualSupplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)- EDR No. 20-1462 revision B dated 3 October 2008 - Installation Dat...	The ACC Bell 206L-4 Emergency Float Installation Kit is fortheinstallation of the Pneumatic Activation System only, and is used inconjunction with the float bags Type Certified per TCCA TC H-92 (BellP/Ns 206-706-210-113).	06/05/2010	Active	10029956
10029957	BOMBARDIER AEROSPACE		TCCA STC SA10-36	CL-600-2B16	Installation, Quick Access Recorder (QAR)	EASA TCDS No. IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Transport Canada STC No. SA10-36 Issue 1 dated 19 April 2010.-ACS-NAI Ltd. Modification Data Summary G551000 Rev N/ C, dated 19 April2010, or later approved revision.-For Instructions for Continued Airworthiness, Refer to Bombardierdocument TE-3130001-ICA.or later revisions of the above listed docum...	None	06/05/2010	Active	10029957
10029964 (EASA.IM.A.S.03045)	B/E AEROSPACE, Inc. - FSI	REV. 1	FAA ST02060SE	747-400	Amendment of STC 10029964 in order to remove EWIS Limitations and updatethe MDL reference	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original p...	FAA STC No. ST02060SE dated 23 April 2010FAA SoC dated 03 May 2010Flight Structure Inc. Master Drawing List A7FS702-D01Revision H datedSeptember 22, 2010The Supplemental Instruction for Continued Airworthiness FSI DocumentA7FS702-D15 Revision C dated August 20, 2010or later revisions of the above l...	Concurrent Installation of EASA STC No. 10029975 is requiredConcurrent installation of FAA STC ST00720LA (EASA approvedundergrandfather rights by CAA Airworthiness Approval Note No. 26656 dated 8March 1999) is required	04/10/2010	Active	10029964
10029965	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		B757-200 757-200	Boeing 757-200 229Y Passenger ConfigurationRev. 1: Transferof STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The requirements for environmental protection and the ass...	-ATL Modification Summary Sheet, Doc. No. MOD-11682-00001, Issue 3 dated6th May 2010-ATL Master Document List, Doc. No.MDL-11682-00001, Issue 3 dated 5thMay 2010or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	As per associated Technical documentation for weight and balance(maximum allowable limit in the forward and aft cargo area is to beamended as per indicated in doc. N° MOD-11682-00001, Issue 3).Limited to: MSN 27973Prior to installation of this change/ repair it must be determined thatthe interrelatio...	10/11/2021	Active	10029965

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10029975 (EASA.IM.A.S.03214)	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST10594SE-T	B747-400	First Class Cabin Upgrade BA 747-400 aircraft	EASA TCDS No. IM.A.196The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-FAA STC Number ST02063SE dated 30 April 2010.-FAA SoC dated 03 May 2010.-Northwest Aerospace Technologies, Inc. (NAT) Master Drawing ListN0313-D10, Revision D dated 04 April 2010or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	Concurrent installation of EASA STC 10029964 is required.This modification may not be installed after 30 August 2010 unless (1)previously approved electrical wiring interconnect system (EWIS)instructions for continued airworthiness (ICA) have been evaluated anddetermined to be adequate for this inst...	07/05/2010	Active	10029975
10029999 (EASA.R.S.01419)	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH			BK 117 C-2	FLIR Mission Work Station PTA-THInstallation of a FLIR StarSafire HD System and an Operator Console inaccordance with ESG GmbH MDL 0005-MDL-006 based on ESG change no. 0005.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Flight Manual Supplement No. 0005-FMS-025 Iss. 2or later revisions of the above listed documents approved by EASA-Meansof Compliance/ Certification Program 0005-MOCP-005 Iss. 2-Master Drawing List 0005-MDL-006, Iss. 3-Installation Instructions 0005-IIO-024	-ESG GmbH Minor Change 0003 and STC EASA.IM.R.S. 01489 have to beinstalled as prerequisite for the installation of this modification.-This approval does not include the operation of laser pointer or laserilluminator devices.	10/05/2010	Active	10029999
10030001	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9339	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Transport Canada SoC reference C-10-0317 dated 06 May 2010.-TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.-Aero Consulting Services Configuration Definition List D954000 RevisionEJ dated 23 April 2010.-Instructions for Continued Airworthiness GC93390000-IFCA.or later revisions of the above li...	Restricted to ASN 9339 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	10/05/2010	Active	10030001
10030002	BEECHCRAFT CORPORATION		FAA STC SA10969SC	KING AIR C90GTI	Installation of an upgraded Flight Management System (Version 4.0). This upgrade will offer a standard Flight Management Computer and willinclude an option for Search and Rescue Mission Profiles.	FAR 23.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation in accordance with in accordance with master drawing list338-00-0001, revision IR, dated January 27, 2010,or later approved revisions.Operation in accordance with Airplane Flight Manual Supplement forCollins FMS-3000 LPV Upgrade, P/N 338-00-0014 – dated February 2010,and:-Airplane Flig...	None.	10/05/2010	Active	10030002
10030003	BEECHCRAFT CORPORATION		FAA STC SA10970SC	KING AIR B200 AND B300	Installation of an upgraded Flight Management System (Version 4.0) . This upgrade will offer a standard Flight Management Computer and willinclude an option for Search and Rescue Mission Profiles.	FAR 23The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Installation in accordance with in accordance with master drawing list337-00-0001, revision IR, dated January 27, 2010,or later approvedrevisions.Operation in accordance with Airplane Flight Manual Supplement forCollins FMS-3000 LPV Upgrade, P/N 337-00-0014 - February 2010 and:-Airplane Flight Manu...	None.	10/05/2010	Active	10030003

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030005	FORCED AEROMOTIVE TECHNOLOGIES		FAA-STC SE10233SC	182Q, 182R 182K, 182L, 182M, 182N, 182P, 182E, 182F, 182G, 182H, 182J,	Installation of Rod Sage Supercharged Teledyne Continental Motors (TCM) O-470-L, O-470-R, O-470-S and O-470-U Engines inacc. with FAA STCSA10232SC	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Drawing List MDL-182-1-A, Rev. F, dated January 4, 2005Supercharger Installation Instructions, Drwg. No. II-182,Rev. F, datedJanuary 4, 2005Supercharger Installation Instructions, Drwg. No. EI-182, Rev. B, datedJanuary 4, 2005Instruction for Continued Airworthiness (FAA-STC SE10233SC), FATDo...	This Supplemental Type Certificate requires installation ofEASA STC10029878 (see also FAA-STC SE10233SC)	10/05/2010	Active	10030005
10030011	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02654NY-D	B757-300	Installation of Panasonic Avionics Corporation System Digital MPES IIPassenger Entertainment System.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateAs per the TCDS and SpecialCondition H-01 "EWIS"The requirements for environmental protection and the associatedcertificated noise and/ or emission...	Delta Engineering Master Data List 0145-06759-2212, Revision D,09/12/2010Aeroplane Flight Manual Supplement, 0645-06766-2212, 15/03/2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Finnair Minor Modifications (EASA.21J.263) EO 15330FR 1 andEO 15383 Fmust be installed prior to or concurrent with theinstallation of thisSTC.	25/01/2011	Active	10030011
10030025	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-31T2, PA-31T3, PA-31, PA-31P, PA-31T, PA-31T1, PA-31-325, PA31-350	Installation of Avidyne TAS 610/620/9900BX, Transponder Couplers andBottom/Top TAS Antennas	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CS-23, Amendment 1.The requirements for environmental protection and theassociatedcertificated noise and/ or emissions levels of the...	Instructions for installation: ASR-2010-007-IFI-10-00, Rev.0Flight Manual Supplement: ASR-2010-007-FMS-05-00, Rev. 0Instructions for Continued Airworthiness: ASR-2010-007-ICA-11-00, Rev. 0or later revisions of the above listed documents approved by EASA	Restricted to aircraft which have Avidyne EX500/600 MFD, Garmin GDU620PFD, Garmin GNS430(A)W or Garmin GNS530(A)W system installed in orderto display the information.	12/05/2010	Active	10030025
10030032	RUECKER AEROSPACE GmbH			SEE ATTACHED AML	Fullsize/ Halfsize ATLAS trolley installation approval.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Engineering order EO-253-00007-001, Issue BDrawing List DRW-253-00007-001, Issue BTrolley Stowage Information DE-253-00007-001, Issue A	See Interface Control Drawing AIS-09-03, Issue C.	13/05/2010	Active	10030032
10030040	BOMBARDIER INC.		TCCA STC NO. SA10-15	BD-700-1A10/-1A11	Modification, External Airstair Door Switch	EASA IM.A.009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificat...	TCCA SoC ref. C-10-0116 dated 23 April 2010.TCCA STC No. SA10-15 Issue 1 dated 02 February 2010.ACS-NAI Ltd. Modification Data Summary Number G572000 Revision NC orlater approved revision.ACS-NAI Ltd Instructions for Continued Airworthiness G572071 Revision NCor later revision.or later revisions ofa...	None	17/05/2010	Active	10030040
10030045	RUAG AEROSPACE SERVICES GmbH			CL-600-1A11 / -2A12 / -2B16	EASA AD 2009-0097 and AD 2009-0173 for Transponder TDR-94D	EASA IM.A.023.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	RUAG SoC reference 316A-CN Revision N/C dated 07 May 2010.RUAG MDL No. 316A-MDL Revision N/C dated 07 May 2010.or laterrevisions of the above listed documents approved by EASA	None.	17/05/2010	Active	10030045

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030059 (EASA.IM.A.S.03276)	West Pacific Air, LLC		FAA STC SA01156SE	B36TC B36	Installation of a Pratt and Whitney PT6A-21 engine flat rated to 500HPat 2,200 RPM, and Hartzell model HC-E4N-3N/D8292 and HC-E4N-3N/D8292 (B,K)-2 propellers.This certificate has been first issued on 17 May 2010 but has beenre-issued for administrative reasons due to the loss of the original.	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.	Installation in accordance with Rocket Engineering Master Drawing List450.00.000, Revision S, dated June 30, 2007, or later approvedrevisions.Operation in accordance with TurbineAir/West Pacific Air LLC FlightManual Supplement ref 450.1001, Change 9, dated July 16, 2007, or laterapproved revisions.o...	Model B36TC OnlyThe MT propeller option on the original FAASTC is not EASA approved atthis time. In order to install the MT propeller compliance with EU noiseand environmental standards must be shown.	24/04/2012	Active	10030059
10030066	ROEDER PRAEZISION GMBH	REV. 2		ATR 72-212, ATR 72-212A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-300, ATR 42-320	Installation of single HF-9000 Communication Transceiver System in ATR42 and ATR 72This STC installs an additional HF communication device.This revision has added some ATR 42 aircraft models within the initialSTC applicability.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): H-01: Enhanced AirworthinessProgramme forAeroplane Systems - ICA on EWISCS 25 Amdt 4:25.21, .25, . 27, .301, .303 to .307, .561, .571, . 581, 25.601 t...	-Master Document List, ref: ATR72-NY-02155 Revision 7 dated16 April2013-Aircraft Flight Manual Supplement, ref: ATR72-NY-02155-08 Revision 5dated 09 August 2012-Instructions for Continued Airworthiness, ref: ATR72-NY-02155-07Revision 6 dated 20 November 2012-Weight & Balance Supplement, ref: ATR72-...	ATR Modification 2028 (Fuselage-Provide basic provisions for HF antennastrap insulator) and Mod ATR Modification 3138 (Communications-HF systeminstallation of basic antenna) must embodied on the aircraft at the timeof this STC installation.Prior to installation of this design change it must be deter...	15/11/2017	Active	10030066
10030074	HAWKER BEECHCRAFT CORPORATION (HBC)		FAA STC SA01566WI-D	KING AIR B200 SERIES	Installation of modified Rockwell Collins Flight Guidance Computers(FGC-3000 units) as a solution to eliminate nuisancepitch trim wheelmovement.	FAR 23.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation Instructions for Replacement of FGC-3000 in HawkerBeechcraft Corporation King Air Models B200/B200C/ B200GT/B200CGT, inaccordance with Rockwell Collins Inc Master Drawing List ref P/NRCA-0241, Revision - , dated September 15, 2009.Instructions for Initial and Continued Airworthiness, ref...	Prior approved installation of a Rockwell Collins Inc FGC-3000 FlightGuidance Computer Module (CPN 822-1108-031) is a prerequisite to thisSTC.	19/05/2010	Active	10030074
10030078	BOMBARDIER INC.		TCCA STC C-LSA02-396/D	BD-700-1A10	Modification, 13 Passenger Interior Configuration	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	TCCA STC No. C-LSA02-398/D Issue 1 dated 14 November 2002.TCCA SoC ref. C-10-0369 dated 17 May 2010.Aero Consulting Services (ACS) Modification Data Summary D12050 RevisionN/C or later approved revision.ACS Flight Manual Supplement "Conversion: 13 Passenger Configuration"G-FM25000052 Rev N/C or late...	Restricted to ASN 9102.1. Previous Embodiment of EASA STC No. 10030079 "Aircraft Completion, 10Passenger Interior Configuration" is required.2. Bombardier Service Bulletin 700-31-018 Modification - IntegratedAvionics Computers - Avionics 2001 Batch 1 IAC Upgrade must be embodied.	19/05/2010	Active	10030078
10030079	BOMBARDIER INC.		TCCA STC C-LSA02-330/D	BD-700-1A10	Aircraft Completion, 10 Passenger Interior Configuration	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-TCCA STC No. C-LSA02-330/D Issue 1 dated 24 October 2002.-TCCA SoC ref. C-10-0368 dated 14 May 2010.-Aero Consulting Services (ACS) Modification Data Summary D12000Revision C or later approved revision.The following ACS Flight Manual Supplements are required:-G-FM24000033 Rev N/C* Cabin Master Powe...	Restricted to ASN 9102	19/05/2010	Active	10030079

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030080	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9331	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Transport Canada SoC reference C-09-0994 dated 13 May 2010.-TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.-Aero Consulting Services Configuration Definition List D954000 RevisionEI dated 16 April 2010.-Instructions for Continued Airworthiness GC93310000-IFCA.or later revisions of the above li...	Restricted to ASN 9331 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	19/05/2010	Active	10030080
10030084	ACC COLUMBIA Jet Service GmbH	REV. 3	LBA STC 0060/549B	SEE EASA APPROVED MODEL LIST	Upwards Opening Door for Parachutist DroppingThis STC at revision 1 revises and supersedes LBA STC 0060/549b.Revision 2extends the scope of approval to additional C182 models	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MDOCL_2022824_rev2_20180601, 09.08.2018- Master Drawing List MDRWL_2022824_rev1_20161001, 15.10.2016- Installation Instruction II_2022824_rev2_20180601, Edition 01.08.2018- Flight Manual Supplement SPOH_2022824_rev1_20180601, Edition01.08.2018or later revisions of the above li...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/01/2022	Active	10030084
10030085	ACC COLUMBIA Jet Service GmbH	REV. 4	LBA STC 0059/549B	SEE EASA APPROVED MODEL LIST	Dropping of max 4 Parachutists with Manual or Automatic Release.This STC revises and supersedes LBA STC 0059/549B.Revision 2 extends the scope of approval to additional C182 modelsRevision 3 Transfer to ACC Columbia Jet Service GmbHRevision 4 typo in company name	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MDOCL_2022926_rev1_20180601, 09.08.2018- Master Drawing List MDRWL_2022926_revO_20161001, 15.10.2016- Installation Instruction II_2022926_rev2_20180601, Edition 01.08.2018- Flight Manual Supplement SPOH_2022926_rev1_20180601, Edition01.06.2018or later revisions of the above li...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/01/2022	Active	10030085
10030088	PIAGGIO AMERICA, Inc.		FAA STC SA10955SC	P.180 AVANTI & AVANTI II	FAA STC SA10955SC "Installation of a passenger seating system to replacefive existing Decrane single seats with Model FS1101 single seats"	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	W & B Manual update Doc. AN-1802-WB-01 Rev. IRInstructions for Continued Airworthiness Doc. AN-1802-ICA-01 Rev. IRor later revisions of the above listed documents approved by EASAor later revisions of the above listed documents approved byEASA inaccordance with EASA ED Decision 2004/04/CF (or subse...	None	20/05/2010	Active	10030088
10030091	FEDERATION FRANCAISE DE VOL A VOILE (FFVV)			ASW20F	STC M-01/09-A01 Winglet Installation on ASW20F	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Dossier STC M-01/09-A01or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	20/05/2010	Active	10030091
10030093	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	BAE 146-200	New Cabin Configuration	JAR 25 Change 10The Certification Basis for the original product remains applicable tothis certificate/ approval	Certification Program JN223ADC12(1) Issue 3or later revisions of the above listed documents approved by EASA	None	21/05/2010	Active	10030093

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030095	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139, AW139	AW139 VIP 305 INTERIORS P/N 6AB1AD015-001, Rev. J	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	RFM Supplement VIP 305 6AB1RFM-1-11, Rev. Hor later revisions of the above listed documents approved by EASA.-Owner's Manual VIP 305 6AB1WNM-2-19, Rev. H-Design Data Set DDS-15-018, Issue C, dated 14.10.2015 (Sect. A, MasterDocument List; Sect B, Master Drawing List)-NDC 6AB1AD-222/I, Issue C-NDC 6A...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/10/2015	Active	10030095
10030099	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			MBB-BK 117 C-1	Cabin Interior RetrofitInstallation of a cabin interior retrofit based on AIEC engineeringorder 854-062.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	MBB-BK117 C-1 Rotorcraft Flight Manual Supplement - Doc. Number: 854-071Rev.: Aor later revisions of the above listed documents approved by EASACertification Compliance Sheet - Doc. 854-075 Rev. B, 19.05.2010Certification Program - Doc. 854-080 Rev. B dated 19.05.2010Master Data List - Doc. 854-049...	S/N 7541	21/05/2010	Active	10030099
10030100	AERO CONSULTING SERVICES LTD.		TCCA STC NO. C-LSA10-048/D	BD-700-1A10	Installation, Complete Custom Aircraft Interior	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	TCCA STC No. C-LSA10-048/D Issue 1 dated 07 May 2010.TCCA SoC ref. C-10-0416 dated 19 May 2010.ACS-NAI Ltd. Modification Data Summary G568000 Revision NC or laterapproved revision.Midcoast Aviation Inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior, G568091 Revision NC o...	Restricted to ASN 9319	21/05/2010	Active	10030100
10030118	AMICALE DE VOLTIGE AERIENNE(AVA)	REV. 1		CAP 232	Evolution of of CAP 232 to CAP 332 SC.Revision 1: Modifications majeures applicables aux CAP23X et 332 SC	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ ap...	Airplane Flight Manual Supplement CAP 332 SCAirplane Maintenance Manual Supplement CAP332 SCor later revisions of the above listed documents approved by EASA	None.	28/07/2011	Active	10030118
10030124 (EASA.IM.A.S.02986)	RAISBECK ENGINEERING Inc.	REV. 3	FAA STC SA4175NM	B300, B300C B200T, B200CT, B200GT, B200CGT A200C, A200CT, B200, B200C 200, 200C, 200T, 200CT, A200	Installation of fully enclosed main landing gear door system forhigh-flotation gear equipped aircraft.	FAR 23.	Installed in accordance with Raisbeck Installation Manual R81-1005 Rev.N, dated 10 March 2010;Instructions for Continued Airworthiness ref. Raisbeck MaintenanceManual 85-120 Rev. G. Dated January 2008;IPC 85-119 dated April 2004or later revisions of the above listed documents approved by EASA inacco...	None.	10/08/2011	Active	10030124

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030130	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		412EP	Installation of Weather Radar Bendix-King model RDR1400C inBell 412EPhelicopters.Rev. 1: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	INAER.210-LMD Rev. 0 (Master Document List) INAER.210-BI, Rev. 0 (Engineering Bulletin) INAER.210-FMS, Rev. 0 (Supplementto RFM) INAER.210-ICA, Rev. 0 (Instructions for Continued Airworthiness)or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/02/2019	Active	10030130
10030139	AERO CONSULTING SERVICES LTD.		TCCA STC NO. C-LSA10-041/D	BD-700-1A11	Installation, Complete Custom Aircraft Interior	EASA.IM.A.009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI F-01 "Installation of Wireless System"The certificated noiseand/ or emissions levels of the original productare unchange...	TCCA STC No. C-LSA10-041/D Issue 1 dated 07 May 2010.TCCA SoC ref. C-10-0427 dated 21 May 2010.ACS-NAI Ltd. Modification Data Summary G383000 Revision NC.Savannah Air Center Airplane Flight Manual Supplement for the CompleteCustom AircraftInterior, G383090 Revision NC.Savannah Air Center Airplane F...	Restricted to ASN 9324	27/05/2010	Active	10030139
10030143	NSE	REV. 2		AS 355 N, AS 355 NP AS 355 F1, AS 355 F2	Installation of DTSV2 Data Transmission SystemRevision 1: The DTSV2 system is described in document IM-DTSV2-AS355 andit is defined in documents DD-411683 and DD-KIT-DTS-AS355.Revision 2: Replacement of obsolete components, software update, smallhardware changes and revision of STC Data List SDL-DTS...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: FAR 27FAR 27.29 Amdt 27-14,,,,,,FAR 27.301 Original issueFAR 27.303 Original issue,,,,FAR 27.305 Original issueFAR 27.307F...	Definition Dossier DD-411683 Revision 2 dated 20 June 2014Certification Plan PCERT-DTSV2-AS355 Revision 1 dated 25 March 2020Qualification Tests Result QTR-411683 Revision 0_Amdt D dated 09September 2014STC Data List SDL-DTSV2-AS355 Revision 1 dated 25 January 2020Or later revisions of the above lis...	This change is applicable to all MSN except MSN equipped with weatherradar and except MSN equipped with Automatic Flight Control System (AFCS).The approval holder shall fulfill theobligations of Part 21, Point21.A.109.Prior to installationof this change/repair it must be determined thatthe interrel...	17/09/2020	Active	10030143
10030147 (EASA.A.S.03949)	AIRBUS S.A.S.			A320-200	Airbus Corporate Jet Centre Modification CJ0531 Issue 1 - VIP KIT - RAFOProject	In accordance with the EASA TCDS A.064 plus:The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- Certification Review Item CRI A-2301-003 "ACJC Centre ConversionProject Certification Basis"...	1. Modification Approval Sheet ref. CJ0531 Issue 1< (>,<)> dated 27th May20102. AFM Supplement Ref: FM-S MOD CJ0531, dated May 01/10or later revisions of the above listed documentsapproved by EASA	This STC is limited to Airbus A320-200 MSN 3723 & MSN 4117	28/05/2010	Active	10030147
10030154	SAFRAN CABIN INC.	REV. 1	FAA STC ST01989LA-D	SEE EASA APPROVED MODEL LIST	Validation of FAA STC ST01989LA-D: Adjustable Cargo Net InstallationRevision 1 is an administrative re-issuance to reflect the name changefrom C & D ZODIAC, INC to SAFRAN CABIN, INC.	The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the productare unchangedand remain applicable to this certificate/ approval without any impacton the noise database.For the airworthiness requirements, see attached EASA Approved ModelList.	-Master Drawing List MDL A141000 Rev.C dtd. 30. April 2010 & detailedconfiguration per attached EASA approved Model List-ICA Report CDRA149-78 Rev. A dtd. 6. May 2010or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/12/2023	Active	10030154

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030156 (EASA.IM.A.S.03250)	HARTZELL PROPELLER LLC		FAA STC SA02677CH-D	PA-46-350P, PA-46R-350T	EASA validation of FAA STC SA02677CH-DInstallation of Hartzell Propellers HCI3YR-1N/N7605(K) +2,HCI3Y1R-1N/N7605(K)+2	CS-23.B NSC	Field Installation Instructions:1. INST_080808_97FLDfor PA-46-350P, S/N 4622001 to 4622200, 4636001 to 46361312. INST_080808_98FLDfor PA-46-350P, S/N 4636132 and upfor PA-46R-350T, S/N 4692001 and upFactory Installation Instructions:1. INST_080808_FACfor PA-46-350P, S/N 4636132 and upfor PA-46R-350T...	For further limitations see applicable associated technicaldocumentation	31/05/2010	Active	10030156
10030161	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	2. REIMS CESSNA 337 1. CESSNA 337	Introduction of Bubble Windows	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	STC Twenty One Limited Master Document List No. S21.MDL-0752 at InitialIssue dated 26 May 2010or later revisions of theabove listed documents approved by EASA	Restricted to un-pressurized versions of the Cessna/Cessna Reims 337aircraft	31/05/2010	Active	10030161
10030166	AIR COMM CORPORATION LLC		FAA STC SR00463DE	A119, AW119 MKII	FAA STC No. SR00463DE Installation of Air Conditioning System	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	-FM Supplement Doc. No. A119-1, Rev. 6, 11 June 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)-FAA STC No. SR00463DE amended 27 November 2007-Air Comm Corp. Master Drawing List Report No. D...	None	31/05/2010	Active	10030166
10030206 (EASA.A.S.03549)	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.			747-400	Reconfiguration of compartment zone A in accordance with AerodecModification summary MOD-0386 Rev. B dated 29 March 2010 or laterapproved revision.This STC validates FAA STC ST01829SE.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI D-1 Width ofAisle for EASA.A.S.03549	Jamco America Inc. Instructions for Continued Airworthiness, documentsnumber JD-09AC03 Rev. New, dated March 06, 2008orlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	02/06/2010	Active	10030206
10030208 (EASA.A.S.03776)	LUFTHANSA TECHNIK AG	REV. 2		A318-112	Installation of a VIP cabin for a maximum of 19 passengers.The designdetails are described in General Description C-AAA057-SPA.Deletion of the Airworthiness Limitation Item reference 530000-01-S forA318-112 Elite 14 MSN 4169	EASA TCDS A.064The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI A5301-008 EASA Supplemental Type Certification Basisplus voluntarily by applicant:FAR 25.981 (a)(b) Amdt. 102FAR 25.856...	- Supplemental Type Definition Document, ref. Doc. No. STDD00-09/02M,issue 01, revision 01 dated 02 June 2010- Aeroplane Flight Manual Supplement A-00-09/167-AFM issue 1, revisionIR, dated 19 April 2010<(>,<)>- Instructions for Continued Airworthiness, ref. Doc. No.A-00-09/167-ICA, issue 2, revision...	None	19/07/2011	Active	10030208

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030228	LUFTHANSA TECHNIK AG			A380-841/ -842	Installation of Class 2 EFB Laptop Cradle	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateAs per TCDS EASA. A.110 andCertification review Item CRI F-57.The requirements for environmental protection and the associatedcertificated noise an...	Supplemental Type Definition Document, STDD46-09/01M, Issue1Airplane Flight Manual Supplement, A-00-10/120-AFM, Issue 1Instructions for Continued Airworthiness, A-00-10/120-ICA, Issue 01Applicant's Declaration of Compliance No. 2927, dated 02 June 2010or later revisions of the above listed document...	This STC is only intended for the defined Class 2 EFB with Type A andType B software applications, in accordance with JAA Temporary GuidanceLeaflet TGL-36 and FAA Advisory Circular AC120-76A.Operation of type C software applications in accordance with FAAAdvisory Circular AC120-76A is prohibited onT...	03/06/2010	Active	10030228
10030229 (EASA.A.S.03972)	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	B757-200/ -300	Introduction of Air Conditioning Filter	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateAs per FAA TCDS A2NM and asmodified by CRI D-01 and CRI H-01The requirements for environmental protection and the associatedcertificated noise and/...	STC 21 Compliance Record, S21.COMP-0694, Issue 1, 03/06/2010STC 21 Master Document List, S21.MDL-0694, Issue 1, 03/06/2010or later revisions of the above listed documents approvedby EASA	Installation of STC21 Limited Minor Change S21.21-15-1004, must beembodied prior to<(>,<)> or concurrent with<(>,<)> this STC	04/06/2010	Active	10030229
10030237 (EASA.A.S.03926)	TÄBY AIRMAINTENANCE AKTIEBOLAG	REV. 1		SAAB SF340A, SAAB 340B	Rework of the Class E Compartment for inclusion of a courier seatingarea for up to 5 occupants, S21.25-63-1355.Rev. 1 Transfer of Certificate	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI D-02 and CRI H-01CS 25 Amendment 2The requirements for environmental protection and the associatedcertificated noise and/ or emissions...	S21.MDL-0663 Issue 1 Master Document List, dated 28 May 2010 includingreference to AFM Supplement, MMEL, Maintenance Manual including ICA andEWIS ICA, W<(>&<)>B Manual, etc.or later revisions of the above listed documents approved by EASA	STC 10014392 and 10014417 must be installed.This Certificate shall remain valid unless otherwise surrendered orrevoked.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will i...	17/02/2020	Active	10030237
10030239 (EASA.IM.A.S.03164)	BOMBARDIER INC.	REV. 1	TCCA STC SA05-60	BD-700-1A11	Installation, Interior Completions.	EASA.IM.A.009.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	EASA STC No. EASA.IM.A.S.03164.TCCA STC No. SA05-60 Issue 1.Aero Consulting Services Ltd Configuration Definition List No. E025000Revision CV dated 31 May 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions oft...	Restricted to ASN 9318.	04/06/2010	Active	10030239
10030240 (EASA.IM.A.S.03162)	BOMBARDIER INC.		TCCA STC SA05-60	BD-700-1A11	Installation, Interior Completions.	EASA.IM.A.009.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	EASA STC No. EASA.IM.A.S.03162.TCCA STC No. SA05-60 Issue 1.Aero Consulting Services Ltd Configuration Definition List No. E025000Revision CU dated 31 May 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions oft...	Restricted to ASN 9315.	04/06/2010	Active	10030240
10030246	AIR SUPPORT INTERNATIONAL S.r.l.			PA -30	ASI BMA 01/B/10 "Installation of Garmin GNS 430W approved for B-RNAV andother avionic equipment".	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The applicant elected to comply with CS-23 par. 1301, 1309, 1321, 1322,1329, 1351, 1353, 1357, 1365, 1367, 1381 1529; EASA AMC 20-4; EASAA...	AFM Supplement Garmin GNS 430WInstructions for Continued Airworthiness BMA 01/B/10or later revisions of the above listed documents approved by EASA	None.	07/06/2010	Active	10030246

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030248	AIR SUPPORT INTERNATIONAL S.r.l.			PA-30		The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The applicant elected to comply with CS-23 par. 1301, 1309, 1321, 1322,1329, 1351, 1353, 1357, 1365, 1367, 1381 1529.The requirements forc...	AFM Supplement "Aspen Avionics EFD 1000 Pro"Instructions for Continued Airworthiness BMA 04/B/09or later revisions of the above listed documents approved by EASA	None.	07/06/2010	Active	10030248
10030259	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH			MBB-BK 117 B-2	Star SAFIRE and Mission Console BK117Installation of FLIR Star Safire HD System on a bolster step on the RHside, mission console, equipment rack, operator and observer seats onadapter plates in the cabin, in accordance with ESG GmbH MDL0012-MDL-006 based on ESG change no. 0012.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement No. 0012-FMS-070 Iss. 3 or later revisionsapproved by EASAList of Compliance Documents 0012-LCD-003 Iss. 4Means of Compliance Record 0012-MOCR-005 Iss. 3Master Drawing List 0012-MDL-006, Iss. 3Installation Instructions 0012-INI-080 Iss. 2Instructions for Continued Airworthin...	This approval does not include the operation of laser pointer or laserilluminator devices.	07/06/2010	Active	10030259
10030272	WIPAIRE Inc.		FAA STC SA00059WI	CESSNA 208, 208B	Installation of the Wipaire Single Point Fueling System on Cessna 208i.a.w. FAA STC SA00059WI	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	-Airplane Flight Manual Supplement, Doc.-No. 1004430, Rev. A, datedMarch 21, 2010-Master Drawing List & Parts Manufacturer Approval List W-MD137, Rev. B,reissued February 19, 2010-Wipaire, Inc. Installation Manual, Doc.-No. 1004433, Rev. A, datedFebruary 19, 2010-Wipaire, Inc. Installation Manual fo...	None	08/06/2010	Active	10030272
10030280 (EASA.R.S.00484)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	Cabin Configuration VIP-4 P/N 6-A0201KI0101-003.This STC supersedes EASA STC EASA.R.S.00484.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The requirementsfor environmental protection and the associatedcertificatednoise and/ or emissions levels of the original product areun...	SFM 6-A02RFM-1-8	Approval of this change in type design applies only to those AB 139rotorcraft previously equipped with EASA approved installation of AgustaKit Vip Cabin interior (Namibia) P/N 3G2520F00411.	09/06/2010	Active	10030280
10030281 (EASA.R.S.00485)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	Cabin Configuration VIP-3 P/N 6-A0201KI0101-001.This STC supersedes EASA STC EASA.R.S.00485.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The requirementsfor environmental protection and the associatedcertificatednoise and/ or emissions levels of the original product areun...	SFM 6-A02RFM-1-7	Approval of this change in type design applies only to those AB 139rotorcraft previously equipped with EASA approved installation of AgustaKit Vip Cabin interior (Namibia) P/N 3G2520F00411.	09/06/2010	Active	10030281
10030287	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	MBB-BK 117 C-2	Wescam HDi FLIR camera system.Installation of Wescam HDi FLIR camera system with build standards foralternate installation of MX-15 Analogue system in accordance with EC UKchange no. MHL/145/1211, Master Drawings A3/1451211-100-1&-2. Theinstallation is including FLIR turret, hand controller, a GPS A...	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Eurocopter UK BK117 C-2 (EC145) Supplement No. 18, Issue 1or later revisions of the above listed documents approved by EASA-Instructions for Continued Airworthiness-ICAW/1451211-001, Iss. A-Design Report DR/ 1451211-001, Iss. A	1. Following items must be installed on the aircraft prior toincorporation of this change:ACS/MEEKER Utility step on the right hand side, p/n AFM/SM117A-11 andrelated Arm p/n AF-SM117-C10 installed i.a.w. STC EASA.IM.R.S.014892. This approval does not include the operation of laser pointer orlaser i...	09/06/2010	Active	10030287

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030289 (EASA.R.S.01472)	GAMA AVIATION (ENGINEERING) LIMITED	REV. 2	CAA UK RESPONSIBILITY	AS350B2	System Configuration Modification No. MOD/350/00.5696 includinginstallation of several avionics and electrical equipment items andmiscellaneous equipment as specified in the Modification SheetMOD/ 350/00.5696.Revision 1 to this STC introduces AS350B2 Series Flight Manual ChangeSheet No. 15.Revision 2...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Change Complies with BCAR Section G.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunc...	Bristow Helicopters Ltd. AS350B2 Series Flight Manual Supplement No.1 - Introduction of radio altimeter with dual indicator (Honeywell KRA-405B)- initial issue.Bristow Helicopters Ltd. AS350B2 Series Flight Manual Change Sheet No.6- Additional system activation during starting - initial issue.Bristow...	Limited to Serial Numbers 1902 and 2312.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	01/03/2016	Surrendered	10030289
10030294	AVIDYNE CORPORATION	REV. 1	FAA STC SA00269BO	2.SR22T 1. SR20, SR22	Installation of Avidyne 700-00033-() Tactical Weather Detection System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List AVTWX-003, Rev. 14, Avidyne 700-00033-() TacticalWeather Detection System-Instructions for Continued Airworthiness AVTWX-004, Rev. 7, Avidyne700-00033-() TWX-Avidyne Installation Manual 600-00165-000, Rev. 15or later revisions of the above listed documents approved by EASA inac...	As indicated in FAA STC SA00269BO	21/12/2010	Active	10030294
10030311	DINAN AVIATION			PA28 R 201 T	M05-2009 Rev. 0 modernisation du système de communication.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Supplement au manuel de vol PA28 Rev0 edition Octobre 2009 or laterrevisions of the above listed documents approved by EASA.	None.	10/06/2010	Active	10030311
10030326	ASSOCIATED AIR CENTER, L.P.		FAA STC ST10900SC-D	A319-115	Installation of an Executive Interior	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI A-4301-007 - EASA Supplemental Type Certification Basis for AACInstallation of Executive InteriorThe certificated noise and/ or emis...	- FAA STC ST10900SC-D, dated 8th June 2010- Master DocumentList, ref. doc. No. 2731000000, Revision IR, dated 8thJune 2010- Airplane Flight Manual Supplement, ref. doc. No. 2731021090, RevisionIR, dated 8th June 2010- Instruction for Continued Airworthiness, ref. doc. 2731050090,Revision D, dated 3...	This approval is limited to only the installation made in Airbus ModelNumber A319-115, Serial Number 3957Airworthiness Limitation inspection to be performed in all the locationsofthe Cabin Interior Primary Structure Elements attachments for every3000 FC using High Frequency Eddy Current in accordan...	10/06/2010	Active	10030326
10030338 (EASA.R.S.01510)	NSE			AS350B, AS350B1, AS350B2, AS350BA, AS350BB, AS350B3	Installation of a tracking system (DTS - Data Transmission System)	As per EASA TCDS.R.008 Issue 04, 23 November 2009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Change complies with CS27 Amdt 1The requirements for environmental protection and the as...	Definition and installation-DTS Definition file, doc. DD-0018-053670-EN, rev. 02 dated 19/04/2010-DTS AS 350 and AS 355mounting Instruction, doc. IM-0011-053670-EN,rev. 08 dated 28/04/2010Inspection, maintenance, and operation-Operating and Maintenance Manual for DTS, doc. MUL-0012-053670-EN, Rev.0...	Modification not approved for aircraft equipped with weather radar orAFCS (Automatic Flight Control System)	11/06/2010	Active	10030338
10030339 (EASA.R.S.00486)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	Cabin Configuration VIP-2 P/N 6-A0301KI0101-003.This STC supersedes EASA STC EASA.R.S.00486.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	SFM 6-A03RFM-1-6.	Approval of this change in type design applies only to those AB 139rotorcraft previously equipped with EASA approved installation of AgustaKit Vip Cabin interior (UAE) P/N 3G2520F00511.	09/06/2010	Active	10030339

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030340 (EASA.R.S.00487)	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	Cabin Configuration VIP-1 P/N 6-A0301KI0101-001.This STC supersedes EASA STC EASA.R.S.00487.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	SFM 6-A03RFM-1-7.	Approval of this change in type design applies only to those AB 139rotorcraft previously equipped with EASA approved installation of AgustaKit Vip Cabin interior (UAE) P/N 3G2520F00511.	09/06/2010	Active	10030340
10030342 (EASA.R.S.01226)	MECAER AVIATION GROUP S.p.A.	REV. 2		AB139/ AW139	FWD Bulkhead P/N 6AB1AD005-001 Installation.This STC supersedes EASA STC EASA.R.S.01226.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Owner's Manual P/N 6AB1WNM-2-4.	None.	09/06/2010	Active	10030342
10030343	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	BK117 C-2 (EC145)	Dual Martin Baker Swivelling Passenger Seats	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-ECUK RFMS Number 19 Issue 1or later revisions approved by EASA-DR/ 145/1196-002 Issue A	As identified in RFMS 19	11/06/2010	Active	10030343
10030363	TECH-TOOL PLASTICS, Inc.		FAA STC SR09127RC-D	AS350 B, AS350 B1, AS350 B2 AS350 B3, AS350 BA, AS350 D	Installation of a Vertical Sliding Window in the Right and/or Left HandSliding DoorFAA STC SR09127RC-D	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Drawing List 350A82-1750, Rev B, dated August 25, 2000- Rotorcraft Flight MFanual Supplement (FMS) 350FMS-066, Revision B,dated July 24, 2008- ICA, Doc Number TTPICA-350-001, dated July 27, 1999or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 200...	None	11/06/2010	Active	10030363
10030371 (EASA.R.S.01534)	MECAER AVIATION GROUP S.p.A.	REV. 2		AB139/ AW139	Liners Silens P/N 6AB1AD010-001Rev. 1: Supersedure of EASA STC EASA.R.S. 01534Rev. 2: Introduction of trim panel system compatibility to AW139helicopter sliding door configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement 6AB1RFM-1-9 Rev. Eor later revisions of the above listed documents approved by EASA.NDC-6AB1AD-241/1 , Issue A Change Definition (Description, Configuration) NDC-6AB1AD-241/2, Issue A Certification Program (CCL & MOC) NDC-6AB1AD-241/3, Issue A Change Approval (Master...	None	29/05/2017	Active	10030371
10030372	AIR METHODS CORPORATION		FAA STC SR00250DE-D	MD900	Installation of an EMS Interior in a MD902 Helicopter	As described in FAA TCDS H19NMThe Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-Master Drawing List Report No. 231-9000-001, revision J, dated March 5,2010-Rotorcraft Flight Manual Supplement "EMS Interior", No. 080-0209,revision E, dated June 5, 2008-Rotorcraft Flight Manual Supplement "Aft Equipment Frame", No. 080-0220, revision A, dated May 9, 2007-Instructions for Continue...	If damage or excess wear warrants structural repair or alteration to thefloor system, pre-approval authorized by the holder of this STC isrequired in accordance with AMMS 050-0167, Rev. (-), dated June 13, 1996or later FAA accepted revision.The multi-purpose floor STC LBA 0767/3066 "Einbau einerMehr...	11/06/2010	Active	10030372
10030374	LUFTHANSA TECHNIK AG			A340-500	A340-500 Cabin retrofit ETD03This STC modifies the cabin layout by replacing First Class seats andall associated seat monuments.	EASA TCDS A.015 Issue 16Special Conditions:-E-19 (Mini Suite)-D-1304-004 (Flight Crew Rest Compartments)The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval...	Supplemental Type Definition Document, ref STDD00-10/10M Issue 1Instruction for Continued Airworthiness, ref A00-10/134-ICA Issue 1or later revisions of the above listed documentsapproved by EASA	None	11/06/2010	Active	10030374

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030404	AVIONIK STRAUBING ENTWICKLUNGS GmbH			EC 120 B	Panel Modification including position change of ApolloMX20 (GarminGMX200),HSI Indicator KI 525 and installation of new Attitude Indicator and Moving Terrain MT-Vision MFD.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 27 Amd. 02.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original...	Definition and Installation in accordance with:-Avionik Straubing GmbH Master Documents List ASR-2010-005-MDL -01-00dtd16/03/10-Avionik Straubing GmbH Installation Instruction ASR-2010-005-IFI -10-00Inspection and Maintenance in accordance with:-Avionik Straubing GmbH Instructions for Continued Air...	None	15/06/2010	Active	10030404
10030405	BENZ AIRBORNE SYSTEMS		FAA STC SA01969CH	DHC-6-100, -200, -300	Installation of Torque Pressure System on DHC-6 in acc. to FAA STCSA01969CH	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Armstrong Aerospace Master Data List No. DC104-3021-00, Rev. B, datedJuly 18, 2005Benz Airborne Systems, Engine Torque Pressure Indicating SystemDHC-6-300, Aircraft Maintenance Manual Supplement, Rev A, March 10, 2004or later revisions of the above listed documents approved by EASA inaccordance with...	For models DHC-6-100 and DHC-6-200, this installation is only applicablewhen the airplane has been modified with PT6A-27 engines.	15/06/2010	Active	10030405
10030407	TIMCO AVIATION SERVICES INC.		FAA STC ST03820AT-D	B767-300	Interior reconfiguration, B767-300Validation of FAA STC ST03820AT-DThe aircraft will have the seating configuration changed to addadditional coach (Y) class seating, additional seat track installationwith associated structural modifications, removal of a lavatory (MS-12)at the R2 door, installationc...	As per EASA TCDS IM.A.035For this STC the following CRI/Special Condition is applicable and ispart of the certificationbasis:CRI H-01 "Enhanced Airworthiness Programme for Aeroplane System - ICA onEWIS"The requirements for environmental protection and the associatedcertificated noise and/or emissio...	-Master Data List 09T116L001, Rev IR, dated June 11th, 2010-TIMCO's Instructions for Continued Airworthiness 09T116R009, Rev IRdated April 23, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)...	As per FAA STC ST03820AT-D	15/06/2010	Active	10030407
10030408	BENZ AIRBORNE SYSTEMS		FAA STC SA01970CH	DHC-6-100, -200, -300	Installation of Engine Oil Pressure System on DHC-6 in acc.to FAA STCSA01970CH	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Armstrong Aerospace Master Data List No. DC104-3020-00, Rev. B, datedJuly 18, 2005Benz Airborne Systems, Engine Oil Pressure Indicating System DHC-6-300,Aircraft Maintenance Manual Supplement, Rev A, March 10, 2004or later revisions of theabove listed documents approved by EASA inaccordance with EA...	For models DHC-6-100 and DHC-6-200, this installation is only applicablewhen the airplane has been modified with PT6A-27 engines.	15/06/2010	Active	10030408
10030420	SCHERDEL ENGINEERING Ltd.			ASK 21, ASK 21 MI	ASK 21 Front Instrument Panel Modification - Modification of the ASK 21front seat instrument panel to allow more leg space for the pilot	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Doc No 10_ASK21 FIP-001	None	15/06/2010	Active	10030420
10030424 (EASA.IM.A.S.03224)	PETERSEN AVIATION, INC.		FAA STC SA00214WI	CESSNA F182P	Operation of airplane on unleaded automotive gasoline, 87 minimumantiknock index and leaded automotive gasoline, 88 minimum antiknockindex (RON + MON) /2 per ASTM Specification D-439 in acc. to FAA STCSA00214WI.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	EASA approved AFMS for Reims-Cessna F182 P, Doc.No. 182P-SA00214WI,Issue 1, dated June 10, 2010Petersen Drawing No. C718984 dated July 1, 1984, revised December 15,1992or later revisions of the above listed documents approved by EASA	1. Limited to those airplanes equipped with gravity fuel feed to thecarburettor and certificated (original or STC) EASAapproved engineinstallations. All engines must have separate approval for operation onautomotive gasoline in the form of Supplemental or Type Certificateapproval.2. Alcohol/ ethanol...	15/06/2010	Active	10030424

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030455	WESTERN AVIONICS		TCCA STC SA03-42	DHC-8-301, DHC-8-302 DHC-8-201, DHC-8-202, DHC-8-106, DHC-8-102, DHC-8-103,	Collins Proline II InstallationTCCA STC SA03-42, Is. 1, dated 8 May 2003	FAR-25 as per EASA.IM.A. 191The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalSpecial Condition H-01 "Enhanced Airworthiness Programme for AeroplaneSystems - ICA on EWIS" as detailed in CRI...	Installation must be in accordance with Western Avionics EngineeringOrder 89596-401, Rev. 1, dated April 24, 2003, or later Transport Canadaapproved revision.Maintenance must be in accordance with Western Avionics MaintenanceManual Supplement, 89596-701, Rev. 1, accepted May 8, 2003, 89596-702,Rev.8...	None	16/06/2010	Active	10030455
10030456	AEROTEC & CONCEPT	REV. 1		B200, B200GT	Air Alpha STC Definition Document EO-B200-25-145. Flight InspectionSystem Interface Installation King Air 200 Series.	The Certification Basis for the original product remains applicable tothis certificate/ approval. The certificated noise and/ or emissionslevels of the original product are unchanged and remain applicable tothis certificate/ approval.	Air Alpha Master Data List No. MDL.EO-B200-25-145, Rev: 06 or laterrevisions of the above listed documents approved by EASA.	None.	12/01/2016	Active	10030456
10030465 (EASA.R.S.01596)	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	BO105	Mounting boom for camera installation.Certification of the installation of a mounting boom which can be usedfor installation of a camera. The camera installation provisions and themaximum weight and frontal area of cameras which can be used with themounting boom are part of this STC. No special came...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalThe applicant hasshown compliance with the current EASA certificationspecification CS-27, Amendment 2.The requirements for environmentalc...	Rotorcraft Flight Manual Supplement: RFMS 1089-01, Issue 1.Instructions for Continued Airworthiness: ICA 1089-01, Issue1Installation/ Post-Installation Procedures: IPI 1089-01, Issue 1Master Document List: MDL 1089-01, Issue 1or later revisions of the above listed documents approved by EASA	CAT-A-operation is prohibited (CAT-A-operation is excluded fromcertification).Maximum weight for cameras used is 43.1 kg and maximum frontal area is1470 sqcm.The used camera has to be certified separately.	16/06/2010	Active	10030465
10030470 (EASA.A.S.03969)	AEROTEC & CONCEPT	REV. 1		B200, B200GT 200	Provision for Flight Inspection use of MLS navigation input	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Air Alpha A/S Master Data List Numbered: MDL.EO-B200-25-129 Rev: 04dated 04 June 2010;- Installation in accordance with the Accomplishment Instructions Ref.AI.EO-B200-25-129 Rev01 dated 19 May 2010- Operation in accordance with Air Alpha A/S Flight Manual SupplementNumbered: FMS.EO-B200-25-129 Re...	MINIMUM FLIGHT CREW: FIS MLS Navigation may only be used with two (2)flight crew members seated in the cockpitMLS/FIS NOT FOR PRIMARY NAVIGATION. FLIGHT INSPECTION GUIDANCE ONLY.STC Holder approval required prior to application by any other party.Prior to installation of this modification it must be...	19/07/2016	Active	10030470
10030471 (EASA.A.S.03942)	AEROTEC & CONCEPT	REV. 1		B200, B200GT 200	MD-124F Direction Finder Antenna Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Air Alpha A/S Master Data List MDL.EO-B200-25-125 Rev: 03dated 09June 2010- Installation in accordance with Accomplishment Instructions Ref.AI.EO-B200-25-125 Rev 00 dated 08 July 2009- Instructions for Continued Airworthiness i.a.w. AirAlpha A/ SMaintenance Manual Supplement Ref. ATP25.0123 Rev:o...	STC Holder approval required prior to application by any other party.Prior to installation of this modification it mustbe determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthine...	19/07/2016	Active	10030471
10030474	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	EC135 T2(CPDS), EC135 T2+	Engine Usage Monitoring SystemInstallation of an Engine Usage Monitoring System in accordance withchange number BOND/MOD/010 as defined in DL/010-099 to monitor certainengine parameters, further described in Design Report DR/010-001.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS 27 Amdt. 2 forthe ChangeThe requirements for environmental protection andthe associatedcertificated noise and/ or emissions levels of...	- Flight Manual Supplement EC135 T2, T2+ "Engine Usage MonitoringSystem", FMS/010-002, Issue 1or later revisions of theabove listed documents approved by EASA- Post installation Actions PIA/010-009 Iss. 1- Instructions for Continued Airworthiness ICA/010-010 Iss. 2- System Operating Instructions SO...	None	17/06/2010	Active	10030474

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030478	RUAG AEROSPACE SERVICES GmbH			BD-700-1A11	Stone Flooring	EASA IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-RUAG Master Document List No. 313B-MDL Rev. N/C dated 14 June 2010.-RUAG Approval for Aircraft Modification No. 313B-CN Rev. N/C dated 14June 2010.-RUAG Airplane Maintenance Manual Supplement No. 313B-AMMSor later revisions of the above listed documents approved by EASA	None	17/06/2010	Active	10030478
10030479 (EASA.IM.R.S.01510)	EAGLE COPTERS USA, INC.	REV. 1	FAA STC SR00219SE	2. AS355F2, AS355N 2. AS355E, AS355F, AS355F1, 1. AS350B, AS350B1, AS350B2 1. AS350BA, AS350D	Horizontal Stabilizer Colour Camera Mount per MDL GA161.Notes:1. The STC was initially issued to Geneva Aviation, Inc. (initialreference: 10030479).2. Revision 1 to this STC reflects the transfer of 10030479 from GenevaAviation, Inc. to Eagle Copters USA, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List GA161 Rev. - initial release dated 21/07/1995or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/03/2015	Active	10030479
10030483	VISIONSAFE LLC		FAA STC ST00892LA	BD100-1A10	Installation of Emergency Vision Assurance System (EVAS) Model107STC-235 and 107STC-236 on Bombardier BD-100-1A10EASA Validation of FAA approved Supplemental Type Certificate ST00892LA	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	-FAA STC ST0892LA with Approved Model List. See AML page 11of 13 forBD-100-1A10.-Master Drawing List Number 226 for Vision Safe Corporation EVAS Model107STC-235 and 107STC-236 onBombardier Aerospace BD-100-1A10, RevisionC dated 14th March 2007-BD-100-1A10 Airplane Flight Manual Supplement EVAS STC...	None	17/06/2010	Active	10030483
10030495 (EASA.A.S.03958)	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A319-132	Interior Reconfiguration and In Flight Entertainment (IFE) Installationon Etihad Airways A319-132 Aircraft	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The c...	NAT Certification Summary, ref. doc. N0338-D90, Revision -,dated 17thJune 2010NAT Master Drawing List, ref. doc. N0338-D10, Revision C, dated 16thJune 2010or later revisions of the above listed documents approved by EASA	None.	18/06/2010	Active	10030495
10030503	APICAL INDUSTRIES, Inc.		FAA STC SR02289LA	BELL 412, BELL 412EP BELL 214B-1, BELL 205A-1 BELL 212, BELL 214B BELL 204B	Installation of Cable Cutters Kit in accordance with MasterDocumentList MD412-101, Revision B, dated May 12, 2010 or later FAA approvedrevision.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval (*)FAR 29 per Apical PSCP412-101, Rev. C	Instructions for Continued Airworthiness ICA412-101, Revision N/C, datedJanuary 5, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None.	21/06/2010	Active	10030503
10030504 (EASA.IM.R.S.00542)	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC SR01165SE	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Revision of STC EASA.IM.R.S.00542 introducing additional cargo hook kit200-282-03.	As specified in TCDS R.008The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Definition and Installation:-Onboard Systems Master Drawing List No. 155-087-00, Rev. 13, datedOctober 30, 2009.For kit P/N 200-282-00-Onboard Systems Owner’s Manual No. 120-105-00, Rev. 12, dated June 20,2008.For kit P/N 200-282-03- Onboard Systems Owner’s Manual No. 120-105-01, Rev. 0, dated Oct...	EASA-approved AS 350 Flight Manual and<External Load Transport: Cargo Sling> FM supplement are required.This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations sha...	21/06/2010	Active	10030504

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030509	VIH AEROSPACE Inc.		TCCA STC SH09-54	S92A	Triple Stacking Litter System InstallationValidation of TCCA STC SH09-54 Issue 1	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	-MS08036-01 revision 1 - DECA Aviation Modification Summary;-FMS08036 revision 2 dated 19 November 2009 - Flight ManualSupplement;-CH192-0308-01-2520-ICA revision 2 dated 24 December 2009 - CougarHelicopters Instructions for Continued Airworthinessor later revisions of the above listed documents ap...	None	21/06/2010	Active	10030509
10030519	AVIATION SUPPORT GmbH	REV. 3		AS 350 BB, AS 350 D AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA	Cargo Mirror Set - Type Air Zermatt (ref. ASE-90824)Rev. 1.- Tailboom mirror version 02 and new installation kit for FrontMirror added (ref. ASE 91502)Rev. 2.- Relocation of the position of the electric connector for thecargo mirror wiring, renumbering/rationalisation of installation kitsP/N and con...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS27 Amdt. 7: CS 27.1, CS 27.21, CS 27.25 (a), CS 27.27 (b), CS 27.29,CS 27.251, CS 27.301, CS 27.303,CS 27.305 (a), CS 27...	Original, Revision 1 and Revision 2:Drawing List DL-ASE-90824, Rev. 1-1, dated 22 March 2019Flight Manual Supplement FMS-ASE-90824, Rev 1-1, dated 27 July 2017Instructions for continued Airworthiness ICA-ASE-90824, Rev 1-2, dated22 March 2019Master Document List MDL-ASE-91810, Rev -, dated 06 June 2...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/06/2021	Active	10030519
10030532 (EASA.IM.R.S.00593)	ONBOARD SYSTEMS INTERNATIONAL	REV. 2	FAA STC SR00896SE	206 A/ 206 B	Installation of Onboard Systems International replacement Cargo Hook kitand Load Weight Kit for Bell 206A and 206B in accordance with OnboardMaster Drawing List No. 15506300.With Revision 2, the Kit Part Numbers included in this approval are:200-267-00, 200-267-01, 200-267-02, 200-389-00, and 200-39...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For System Part Numbers 200-267-00:· Rotorcraft Flight Manual Supplement Document Number 121-08-00 Revision2, dated November 30, 2015.For System Part Numbers 200-267-01:· Rotorcraft Flight Manual Supplement Document Number 121-008-01,Revision 1, dated November 30, 2015.For System Part Numbers: 200-2...	Approval of this change applies only to Bell Helicopter models 206A and206B previously equipped with Bell cargo suspension systems, Part Number(P/N) 206-072-900-1, 206-072-900-101, or 206-072-900-103; Bell cargohook provision kit, P/N 206-706-335-3, 206-706-335-5, or206-706-335-105; and Breeze-Easte...	28/02/2017	Active	10030532
10030534	INFLIGHT CANADA Inc.	REV. 1	TCCA STC O-LSA08-045/D	767-300	Audio Video on Demand (AVOD) and In-Seat Power Supply (ISPS) SystemInstallation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateAs per the EASA TCDS including EWIS ICA requirements (CRI H-01)The requirements for environmental protection and the associatedcertificated noise an...	Master Data List, MDL05217, Revision 11, 29/03/2010Aeroplane Flight Manual Supplement, FMS05217, Revision 3, 25/02/2010EWIS ICA, EWIS ICA05217, Revision 1, 14/11/2011or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ Can...	none	10/09/2012	Active	10030534
10030547 (EASA.A.S.03903)	AERODATA AG			L-410 UVP-E	Installation of Aerodata Flight Inspection System AD-AFIS-130	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA CS-23 and FAR Part 23 Arndt. 34, §23.561 & 23.785 (choosen byapplicant)The requirements for environmental protection and the associat...	Airplane Flight Manual Supplement (AFM-110 Rev 0)Airplane Maintenance Manual (AMM-1010 Rev 0) or later revisions of the above listed documents approved by EASA	Limited to serial no. 892318 and 892329	23/06/2010	Active	10030547

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030551	S4A SOLUTIONS FOR AVIATION, S.L.			EC135 P2+	Installation of an Iridium Satellite Telephone on board	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Master Drawing List Ref 13504-RPT04, Edition 2, dated 19/01/2010Service Bulletin Ref: 13504-SB01, Edition 2, dated 01/02/2010Rotorcraft Flight Manual Supplement Ref: 13504-HDK01, Edition 2, dated01/02/2010or later revisions of the above listed documents approved by EASA	Not Applicable	23/06/2010	Active	10030551
10030602	AVIATION SERVICE A.S.			L410 UVP-E, L410 UVP-E9, L410 UVP-E20	TCAS II CAS67A, Mode S transponder MST67A, and Air Data Display UnitAD32 installation to comply with regulation requirements.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval-FAR Part 23, Amdt. 49	-FM34 40/01 001,, Flight Manual Supplement CAS 67A and MST 67A-FM34 40/01 002,, Doplněk Letové příručky CAS 67A a MST 67A-FM34 10/01 001,, Flight Manual Supplement AD 32-FM34 10/01 002 Doplněk Letové příručky AD 32	None	24/06/2010	Active	10030602
10030614	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE		TCCA STC O-LSA06-007/D	B737-800	Passenger Seating Arrangement - Installation / Relocation of passengerSeats in 186-189 Pax Configuration and installation of EmergencyEquipments	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.	DECA Modification Summary No. MS05289 Rev.16 dated 06 January 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision)	Only valid for MSN 28373, 28375, 29351, 29642, 29883, 30637, 30671,33003, 33029, 33699, 34704, 35093	25/06/2010	Active	10030614
10030620	BOMBARDIER AEROSPACE			BD-100-1A10 (CHALLENGER 300)	Installation of Miniature Quick Access Recorder	Certification Basis as per EASA TCDS IM.A.080 Issue 2, 8th October 2008plus:The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/...	-Transport Canada Supplemental Type Certificate SA10-37 Issue 1, dated22nd April 2010-Transport Canada Approved Aero Consulting Services Ltd. Modificationdata Summary ref. G293000dated 22nd April 2010, Revision N/C.-Instructions for Continued Airworthiness ref. RAL-BV100-31311-ICA,Revision FIor lat...	None	28/06/2010	Active	10030620
10030622	AEROSERVIS, S.R.O.			L 410 UVP	The set of the safety modifications in order to prepare thealternativemean of the compliance to the EASA AD 2008-0103.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR Part 23 Amdt.34, dated 17 February 1987 through Amdt. 49, dated 11March 1996	-L 410 UVP Flight Manual Supplement No. STC AE/ 103-DLP1, dated March15/10-L 410 UVP Wiring Manual Supplement No. STC AE/103-DAE1, dated March2010-L 410 UVP Maintenance Manual Supplement No. STC AE/ 103-DTP1, datedMarch 2010-L 410 UVP Maintenance Schedule Supplement No. STC AE/ 103-DPU1, datedMarch 201...	None	28/06/2010	Active	10030622
10030640	LATITUDE TECHNOLOGIES CORPORATION		TCCA STC SH10-16	AS355F2, AS355N, AS355NP AS355E, AS355F, AS355F1,	Installation of Latitude Technologies S100 Tracking System	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	1117-MDL-001 revision N/C dated 7 April 2010 - Master Drawing List; 1117-400-004 revision 01 dated 7 April 2010 - Instructions for ContinuedAirworthiness	None.	29/06/2010	Active	10030640

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030644	LATITUDE TECHNOLOGIES CORPORATION	REV. 1	TCCA STC SH10-16	206L-3, 206L-4, 407 206B-1, 206L, 206L-1 206, 206A, 206A-1, 206B	Installation of Latitude Technologies S100 Tracking System	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	1117-MDL-001 revision N/ C dated 7 April 2010 - Master Drawing List; 1117-400-004 revision 01 dated 7 April 2010 - Instructions for ContinuedAirworthiness	None	14/07/2010	Active	10030644
10030647	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03731AT-D	GIV-X	Installation of an Audio Video Distribution System	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Index List GC415028001,Revision D, dated 10 September 2009or later revisionsof the above listed documents approved by EASA inaccordancewith EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None.	29/06/2010	Active	10030647
10030649	SIERRA INDUSTRIES Ltd.	REV. 1	FAA STC SA3634SW	U206 LANDPLANES E, F, G U206 LANDPLANES A, B, D P206 A, D, E LANDPLANES 206H, T206H LANDPLANES	Auxiliary Fuel System: Installation of three auxiliary bladder type fueltanks in each wing in accordance with FAA STC SA3634SW, revision 4,dated 30.03.2010.This EASA STC is a revision of LBA STC (EMZ) 0393/673, 673a, dated05.05.1993.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Drawing List No. SI10600, Revision N, dated January 27,2006- Installation Instruction No. SI10665, Revision D, dated July 18, 1986- Airplane Flight Manual Supplements for CessnaP206 A, D and E modellandplanes (S/N P206-0161 through P206-00647):,,- for aircraft with standard range bladder type fue...	- Cessna P206 A, D and E model landplanes (S/N P206-0161 throughP206-00647)- Cessna U206 model landplanes A, B, D<(>,<)> E, F, G (S/N U206-0438through U206-04649)- Cessna 206H andT206H model landplanes (S/N 206-08001 to present andS/N T206-08001 to present)- Cessna 206H and T206H model landplanes w...	17/10/2012	Active	10030649
10030668	KEYSTONE HELICOPTER CORPORATION		FAA STC SR02597NY-D	S92A	Installation of a tail mounted, forward facing camera.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	IDL01702 revision - dated 12 March 2010 - Installation Drawing List;IC01702 rev - dated 1 January 2010 - Instructions for ContinuedAirworthiness;FM 01702 rev - dated 21 May 2010 - Flight Manual Supplement.	None.	30/06/2010	Active	10030668
10030689 (EASA.A.S.03797)	BUCHER LEICHTBAU AG			SEE EASA APPROVED MODEL LIST	16g New Generation Stretcher P/N 1120020-300 - (NGS)	JAR 25 Change 15 except 25.562 addressed per TGM/25/12The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Sys...	- Master Document List ref. doc. No. E034-02-08 Rev. NC, dated 29thJune 2010- User Manual ref. doc. No. E017-08-09 Rev. 02or later revisions of the above listed documents approved by EASA	This STC does not constitute an approval for installation. Compliancewith following requirements below need to be demonstrated through adesign approval for Stretcher installation in aircraft per approvedModel list:§ 25.561(d) § 25.785(a)§ 25.785(h)§ 25.785 (j)§ 25.791§ 25.807§ 25.813§ 25.815§ 25.1447§...	01/07/2010	Active	10030689
10030690	GULFSTREAM AEROSPACE CORPORATION		FAA STC REF ST03737AT-D	GIV-X AND GV-SP	Installation of a Honeywell/EMS HD-710 combined SATCOM Swift BroadbandHigh Speed Data System.	JAR 25The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Install in accordance with Gulfstream Aerospace Index List refGC513038009, Revision B, dated 10/09/09.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Not Applicable	02/07/2010	Active	10030690

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030691 (EASA.IM.A.S.03225)	GULFSTREAM AEROSPACE CORPORATION		FAA STC REF ST03685AT-D	GV-SP (G550)	Installation of Flight Crew Sleeping Facilities.	JAR 25The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Install in accordance with Gulfstream Aerospace Index List refGC515018000, Revision E, dated 06/18/09.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Not Applicable	02/07/2010	Active	10030691
10030694	ANCRA INTERNATIONAL LLC		FAA STC ST02304LA	B737-300	Installation of main deck cargo loading system.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Ancra International LLC Controlled Data List DL84990 Rev. Cdated June2, 2010Instructions for Continued Airworthiness ICA Report 9494 Rev. Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	01/07/2010	Active	10030694
10030714	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	B737-400	Fuselage skin GPS antenna structural provisions	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01- issue 2: Special Condition “Enhanced Airworthiness programmefor aeroplane Systems – ICA on EWIS”The requirements for environmen...	Master Data List - MDL-0070-10 Rev.00 dated 23 April 2010 (*)Drawing N °10098804 Rev.00 dated 23 April 2010 (*) StructureDesign Report ESS -1711-PGB Rev.00 dated 20 April 2010 (*) Compliance check list ESS-1710-PGB Rev.00 dated 20 April 2010(*)(*) or later revisions of the above listed documents appr...	None	02/07/2010	Active	10030714
10030757 (EASA.IM.A.S.03226)	ZODIAC AEROSAFETY SYSTEMS	REV. 5	TCCA STC SA92-23	DHC-8-100/-200/-300 SERIES	De-icer Boot Installation,Installation of Aerazur Type 51 Wing and Tail De- Icer Boots(Configuration 1)Installation of an alternative PN 51SP209 for Aerazur Wing and TailDe-Icer Boots (Configuration 2)Transfer of STC 10030757 Rev 4 from Field Aviation to Zodiac AerosafetySystems	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Configuration 1:Installation of Aerazur Type 51 De-Ice Boots in accordance with FieldsAviation Company inc. Drawing List No. 33644; Issue 2 *) Instructions for Continued AirworthinessMaintenance must be done in accordance with Fields Aviation Company inc.Maintenance Manual Supplement, P/N FACi-6679-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/12/2016	Active	10030757
10030758 (EASA.A.S.03712)	BUCHER LEICHTBAU AG	REV. 1		TABLE E043-01-17 SEE AIRCRAFT ALLOCATION	Change to STC EASA.A.S.03712 through:1. Extension of the STC approval to all aircraft models of the EmbraerERJ 190-Series2. Installation approvals for specific MSNs of the EmbraerERJ 170 and190-Series3. Standardisation of the product documentation package of the 9G NGS XLStepX Stretcher 1120050-Ser...	CS-25 Amendment 20The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List E034-05-08 Rev B dtd. 22.02.2018-Aircraft Allocation Table E043-01-17 Rev NC dtd. 31.01.2018-User Manual 25-67-43 Rev. 02 dtd. Jan 26/2018or later revisionsof the above listed documents approved by EASA.	-Per User Manual E017-01-08-This STC constitutes an approval for installation only for aircraftserial numbers as statedin the Aircraft Allocation Table. Foradditional aircraft serial numbers the requirements for full compliancehave to be demonstrated through a design approval.-Installation of thisr...	26/02/2018	Active	10030758
10030765	LATITUDE TECHNOLOGIES CORPORATION		TCCA STC SH10-16	AS350D1 AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D,	Installation of Latitude Technologies S100 Tracking System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1117-MDL-001 revision N/C dated 7 April 2010 - Master Drawing List; 1117-400-004 revision 01 dated 7 April 2010 - Instructions for ContinuedAirworthiness	None	07/07/2010	Active	10030765

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030772	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR02035SE	AS355F2, AS355N, AS355NP AS355E, AS355F, AS355F1,	Cargo Hook Kit model 200-352-00	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	155-145-00 revision 1 dated 28 May 2010 - Master Drawing List; 120-140-00 revision 0 dated 9 September 2009 - Owners Manual; 123-035-00 revision 0 dated 18 November 2009 - Service Manual;121-054-00 revision 1 dated 11 June 2010 - Rotorcraft Flight ManualSupplement.	None	07/07/2010	Active	10030772
10030781	BOMBARDIER INC.	REV. 1	TCCA STC SA04-113	BD-700-1A10	Installation, Interior Completions In-Service Improvements Modifications-ASN 9348	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Transport Canada SoC reference C-11-0065 dated 17 February 2011.EASA STC No. 10030781.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionGD dated 01 February 2011.Instructions for Continued Airworthiness GC93480000-IFCA.or later...	Restricted to ASN 9348 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	25/02/2011	Active	10030781
10030810	BUCHER LEICHTBAU AG	REV. 1	FOCA Z25-20-57	EC135 T1, EC135 T2, EC135 T2+ EC135 P2(CPDS), EC135 P2+ EC135 P1(CDS), EC135 P1(CPDS)	Installation of ARA-EC135-AC60 Ambulance and Rescue SystemNew revision covers:STC issuance under EASA format at revision 0, Exchange of Suction Unitwith new P/N 1355185<(>,<) >adding P2+ and T2+ at the list of EC135 models.This STC revokes the STC 10030489.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-Rotorcraft Flight Manual Supplement FMA-1 Rev. Cor later revisions of the above listed documents approved by EASA-Operation and Maintenance Manual E014-01-05 Rev. 00-Master Document List MDOC-AC60-Equipment List ARA-EC135-AC60	None	29/11/2011	Active	10030810
10030815	ROCKWELL COLLINS INC.		FAA STC NO. ST01838LA	B747-400 SERIES	Installation of Rockwell Collins enhanced Total Entertainment System inaccordance with System List 1309713-002/-004, Revision Y, datedSeptember 8, 2005 or later FAA approved revisions.Validation of FAA STC ST01838LA	The Certification Basis for the original product remains applicable tothis certificate/ approval	Instructions for Continued Airworthiness document nr. 1304944Aircraft Maintenance Manual Supplement 44-00-75or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	08/07/2010	Active	10030815
10030818	DYN'AVIATION			DR400/200R, DR400/500 DR400/180R, DR400/2+2, DR400/160, DR400/180, DR400/125I, DR400/140B, DR400/125, DR400/140, DR400/120D, DR400/180S, DR400/120A, DR400/160D, DR400/100, DR400RP, DR400NGL, DR340, DR315, DR360, DR380, DR300/140, DR300/125, DR300/120, DR400/120, DR300/108, DR300/180R,	MD09F0001 050210 - New flaps and control system	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	SI10A00001 - Instructions de maintenanceor later revisions of the above listed documents approved by EASA	None	08/07/2010	Active	10030818
10030822 (EASA.R.S.01551)	AEROLITE AG	REV. 3		AW109SP	EMS Kit AW109SP REGA P/N 1090150-501Changes related to Rev.1:- Introduction of the Propaq MD Retainer Inst. P/N 1090170-503 and anadditional 'Training Configuration 2' into the already certified EMSEquipment P/N 1090150-501 (STC EASA.R.S.01551). Modifications of BaggageCompartment Inst. P/N 1090190-...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	FMS-09-001 Rev. D dated 17 September 2013or later revisionsof the above listed documents approved by EASAOPM-09-002 Rev. F dated 23 July 2013	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/09/2013	Active	10030822

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030847	ROEDER PRAEZISION GMBH	REV. 1		206H, T206H	Provisioning for implementation and operation with a "Turtle Pac160-ferry tank"	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Initial Issue (not required y 21A.101, elected to comply by theapplicant)The requirements for environmental protection and the ass...	-Engineering Order 1704EO280010-01A, dated 26.06.2010-POH Supplement: "Anhang zum Flughandbuch für Cessna 206H and T206H",Doc. No. 1704 AM 2800 10 01A, dated 18.05.2010or later revisions of the above listed documents approved by EASA	Installation of the ferry tank is not subject of this STC.	14/07/2010	Active	10030847
10030863 (EASA.A.S.03823)	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	EXTRA EA-300 / L	External camera installation	The Certification Basis for the original product remains applicable tothis certificate/ approval	Master Documents List Drg No MDL 1054-01 Issue 1ICA-1054-01Issue 1 Instructions for Continued AirworthinessAFMS-1054-01 Flight Manual Supplementor later revisions of the above listed documents approved by EASA	None	09/07/2010	Active	10030863
10030900	BOMBARDIER INC.	REV. 3	TCCA STC SA05-60	BD-700-1A11	Installation, Interior Completions In-Service Improvements Modifications-ASN 9359	EASA TCDS No. IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certifi...	TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.EASA STC No. 10030900 Rev.1.TCAA SoC ref. C-11-0062 dated 16 February 2011.Aero Consulting Services Ltd. Configuration Definition List E025000Revision EK dated 1 February 2011.Bombardier Aerospace Airplane Flight Manual Supplement G-FM25004501RevisionG...	Restricted to ASN 9359	02/03/2011	Active	10030900
10030917	SKYTRAC SYSTEMS LTD.		TCCA STC SA09-93	DHC-6-200 DHC-6-100	SkyTrac Flight Following / SATCOM Installation in acc. withTCCA STCSA09-93:ISAT-100 transceiver installed in aft zone of aircraft, Dual elementGPS/Iridium antenna installed on upper fuselage, optional DVI-250 andCDP-250 control panels installed at centre radio panel.	The Certification Basis for the original product remains applicable tothis certificate/ approval.Additional requirements for the use of Lithium Ion Battery: TCCA IssuePaper IP09074-1, Revision N/C (technically identical with EASA CRI F-56)The requirements for environmental protection and the associa...	Master Drawing List MDL09074, Revision A, dated May 12, 2010Flight Manual Supplement FMS09074-1, Revision A, TCCA approved May 14,2010Instructions of Continued Airworthiness ICA09074-1, Revision A, datedMay 11, 2010or later revisions of the above listed documents approved by EASA inaccordance with E...	None	12/07/2010	Active	10030917
10030918	SKYTRAC SYSTEMS LTD.		TCCA STC SA09-80	CESSNA 208, 208B	SkyTrac Flight Following / SATCOM Installation in acc. withTCCA STCSA09-80, Issue 1:ISAT-100 transceiver installed in aft zone of aircraft, Dual elementGPS/Iridium antenna installed on upper fuselage, optional DVI-250 andCDP-250 control panels installed at centre radio panel.	The Certification Basis for the original product remains applicable tothis certificate/ approval.Additional requirements for the use of Lithium Ion Battery: TCCA IssuePaper IP09075-1, Revision N/C (technically identical with EASA CRI F-56)The requirements for environmental protection and the associa...	Master Drawing List MDL09075, Revision A, dated May 11, 2010Flight Manual Supplement FMS09075-1, Revision A, TCCA approved May 11,2010Instructions of Continued Airworthiness ICA09075-1, Revision A, datedApril 20, 2010or later revisions of the above listed documents approved by EASA inaccordance with...	None	12/07/2010	Active	10030918

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030934	BOMBARDIER AEROSPACE	REV. 1	TCCA STC SA10-50	BD100-1A10	Activation of Wireless Local Area Network Access Point on BombardierBD-100-1A10Revision of the EASA STC 10030934, EASA Validation of TCAA approvedSupplemental Type Certificate SA10-50	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Transport Canada Supplemental Type Certificate SA10-50 Issue 1, dated08th June 2010.- Transport Canada approved ACS-NAI Ltd. Modification Data SummaryNumber G762000, Rev. A, dated 12th August 2010.- Transport Canada approved ACS-NAI Ltd.Airplane Flight ManualSupplement G756090<(>,<)> Rev. A, date...	None	23/09/2010	Active	10030934
10030938	BOMBARDIER AEROSPACE	REV. 1	TCCA STC SA10-44	BD100-1A10 CHALLENGER 300	Installation of Mechanical Provisions and LRU Installation,AircellAir-to-Ground Communication System and Immarsat Satcom System.Revision of the EASA STC 10030938<(>,<)> validation of TCAA approvedSupplemental Type Certificate SA10-44	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Transport Canada Supplemental Type Certificate SA10-44 Issue 1, dated19th May 2010.- Transport Canada approved ACS-NAI Ltd. Modification Data SummaryNumber G573000, Rev. A, dated 16th August 2010.- Instructions for Continued Airworthiness as per ACS-NAI Ltd.Modification Data Summary Number G573000...	None	23/09/2010	Active	10030938
10030942	LIFEPORT, LLC		FAA STC ST01891LA-D	SEE EASA APPROVED MODEL LIST	Multi Models Commercial Medical StretcherValidation of FAA STC ST01891LA-D	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Certification basis as per TCDS except:-§25.562 (when relevant) addressed per TGM/ 25/12.-CRI H-01/Special Condition H-01 "Enhanced Airwor...	-FAA approved Model List (AML) No. ST01891LA-D, dated May 27, 2010-FAA approved Airplane Flight Manual Supplement No. EGR-808-11, Rev Ddated May 27, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis dec...	This STC does not constitute an approval for installation. Compliancewith following requirements below need to be demonstrated through adesign approval for commercial medical stretcher installation in eachaircraft model per approved Model list:§ 25.561 (d) / § 25.785(a) / § 25.785(h) / § 25.785(j) /2...	15/07/2010	Active	10030942
10030951	TASS Inc.		FAA STC ST00593SE-D	B747-400	Active Noise Reduction Headset Installation Provisions in accordancewith BF Goodrich Master Drawing List D2000-396, sheet 1, Revision New,dated November 22, 2000 or later FAA/DAS approved revision.Validation of FAA STC ST00593SE-D	The Certification Basis for the original product remains applicable tothis certificate/ approval.	None	None	15/07/2010	Active	10030951
10030954	APTOZ EHF.	REV. 1		GA8 AIRVAN	Installation of TopScan Camera SystemRev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS-23, Amdt. 1, is elected to comply with for the items affected by thechangeThe requirements forenvironmental protection and the associatedcertified noise a...	EASA approved Master Document List, Doc. No. S21.MDL-0769, Issue 1,dated 07-Apr-2010,EASA approved Engineering Order, Doc. No. EO-GTA-2520-03, Rev. IR, dated28-Jun-2010,EASA approved Flight Manual Supplement, Doc. No. AFM-GTA-2520-03, Rev.IR, dated 06-Jul-2010,Approved Continued Airworthiness Instru...	Only applicable for aircraft / preconditions as defined in EngineeringOrder, Doc. No. EO-GTA-2520-03, Rev. IR, dated 28-Jun-2010, or laterapproved revision.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously i...	27/05/2025	Active	10030954

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030955	WESTERN AVIONICS		TCCA STC SA04-96	DHC-8-301/-302 DHC-8-201/-202 DHC-8-102/-103/-106	Second ADF InstallationTCCA STC SA04-98, Issue 1 dated 23 December 2004	FAR 25 as per EASA.IM.A. 191The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this ce...	Installation of Second Collins ADF-60A or Honeywell (Bendix/King) KDF-806 ADF Systems must be in accordance with TCCA approved WesternAvionics Engineering Order 99459-401, originalissue dated 31 August2004.Maintenance must be in accordancewith Bombardier/ DeHavilland AircraftMaintenance Manual, Cha...	None	16/07/2010	Active	10030955
10030956	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST02067SE	B747-400	LCD Monitor installation on Boeing Model 747-400 series aircraft inaccordance with Heath Tecna, Inc. Master Drawing List HPD-DL-136,Revision E, dated May 5, 2010, or later FAA approved revisions.Validation of FAA STC ST02067SE	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.§ 25.812(a)(1)(b)(1)(c)(i)(k)(l)(1)(2) Amdt 25-58§ 25.853(a)(d)(e) Amdt 25-58§ 25.869(a)(1)(4) Amdt 25-113§ 25.1353(a)(1)(b)(c) Amdt 25-1...	ICA Supplement HTM957 Revision A, dated March 1, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentrevisions ofthis decision)	None	16/07/2010	Active	10030956
10030961	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BEECH 200	Installation of HySpex Camera System (NEO)	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-EASA approved Master Data List, Doc. No. CV877-049, Rev. A, dated14-Jul-2010, or later approved revision-EASA approvedEngineering Order, Doc. no. CV877-062, Rev. A, dated14-Jul-2010, or later approved revision-EASA approved Airplane Flight Manual Supplement, Doc. No. CV877-071,Rev. IR, or later ap...	Only aeroplanes in compliance with the preconditions as listed inChapter C of Engineering Order, Doc. No. CV877-062, Revision A, dated14-Jul-2010, or later approved revision, are eligible for this change.	16/07/2010	Active	10030961
10030964 (EASA.A.S.03518)	JET AVIATION AG	REV. 2		A319-115	Airbus A319-115 "BCJ03632" VIP Cabin Interior CompletionRevision 1: Update of the Instructions for Continued AirworthinessRevision 2: Bedroom Reconfiguration Transformation of bedroom fromNon-TTOL to TTOL area by removing one single bed and installing twosingle seats.	As per CRI G-4301-001 Issue 5 "EASA Supplemental Type CertificationBasis for Boutsen 1 < (>&<)>2 VIP Cabin Interior Completion.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate...	JBSL-M-01444MDL-003 ISSUE B MASTER DATA LISTBCJ03632-201-01ISSUE C AIRPLANE FLIGHT MANUAL SUPPLEMENTBCJ03632-150-01 ISSUE C INSTRUCTIONS FOR CONTINUED AIRWORTHINESSJBSL-M-01444CCS-003 ISSUE A CERTIFICATION COMPLIANCE SHEETOr later revisions of the above listed document(s) approved/acceptedunder the...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/05/2023	Active	10030964
10030966 (EASA.A.S.00749)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		CESSNA U 206G, TU 206G	Installation of Propeller MTV-5-1-E-C-F-R (M)/CFR220-54 orMTV-5-1-E-C-F/ CF220-54		MTV-5-1-E-C-F-R(M)/ CFR220-54:-Instructions for Continued Airworthiness and Installation InstructionsNo E-1031-Airplane Flight Manual Supplement No E-1032MTV-5-1-E-C-F/ CF220-54:-Instructions for Continued Airworthiness and Installation InstructionsNo E-1115-Airplane Flight Manual Supplemnet No E-1114...	1. This STC is applicable to Cessna U 206G, TU 206G both equipped withR/R Allison 250-C20S (Soloy Turbine PAC) in accordance with LBA EMZ (STC) 0082/673a only.2.This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Com...	19/07/2010	Active	10030966

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10030973	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST02066SE	B747-400	Seat Installation and interior reconfiguration on Boeing Model 747-400series aircraft in accordance with Heath Tecna, Inc. Master Drawing ListHPD-DL-137, Revision B dated May 11, 2010, or later FAA approvedrevisions.Validation of FAA STC ST02066SE	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.§ 25.812(a)(1) -FAR Amdt 25-58§ 25.853(a)(c)(d)(e) - FAR Amdt 25-58§ 25.869(a)(1)(4) - FAR Amdt 25-83§ 25.1353(a)(b)(d) - FAR Amdt 25-11...	ICA Supplement HTM960 Revision E, dated May 20, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	19/07/2010	Active	10030973
10030985	RUAG AG	REV. 1		P.180 AVANTI II P 180 AVANTI II	In-Flight Entert. System Installation by installing a ROSEN“RosenViewVX” moving Map and DVD System, an IR-Eye, One FLIGHT DISPLAYSYSTEM 10.2 inch LCD and two 7 inch LCD’s and a FLIGHT DISPLAY SYSTEMwireless audio transmitter for audio distribution to SENNHEISER HDR140wireless Headsets.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Master Document List: Nr. 163206-00, Rev. 000, 16.07.10-Instructions for Continuous Airworthiness: Nr. 163206-60, Rev. 000,02.10.09-Declaration of Compliance: Nr. 163415-4100, Rev. 000-Aircraft Flight Manual Supplement: Nr. 163206-50, Rev. 000, 21.06.10or later revisions of the above listed documen...	The approval holder shall fulfill the obligations of Part 21, Point21A.109.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthi...	02/02/2021	Active	10030985
10030991	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	L-410 UVP, L-410 UVP-E, L-410 UVP-E9 L-410 UVP-E20 CARGO	Introduction of under wing emergency exits.	CS-23 Amendment 1The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Compliance Record: S21.COMP-0704 Issue 1 Dated 15 July 2010Master Documents List: S21.MDL-0704 Dated 5 July 2010.FlightManual Supplement: S21.FMS-0062 Issue 1 Dated 15 July 2010.Supplement Manual: S21.TEC-0233 Issue 1 Dated 15 July 2010.or later revisions of the above listed documents approved by E...	None	11/06/2012	Active	10030991
10030992	AEROLITE AG	REV. 3		MBB-BK 117 C-2	EMS Equipment P/N 145341-501/-502This Major Change to EASA STC 10030992, Rev. 2 introduces the followingmodifications /components to EMS Equipment P/N 145341-501/-502:For P/N 145341-501:-Addition of a new configurations "2A" and "2D" with3 medical seats andone stretcher<(>,<)>-The existing configu...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI D-1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunc...	For configuration P/N 145341-501:Flight Manual Supplement FMS-10-003 Rev. BOperation and Installation Manual OPM-10-04 Rev. BFor configuration P/N 145341-502:Flight Manual Supplement FMS-11-001 Rev. AOperation and Installation Manual OPM-11-01 Rev. Bor later revisions of the above listed documents a...	Compatibility with NVIS has not been demonstrated.Compatibility with TC-holder 3-seat bench has not been demonstrated forconfiguration P/N 145341-501Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installe...	26/01/2017	Active	10030992
10031010	AMSAFE, Inc.	REV. 1	FAA STC SA02276AK	SEE FAA AML	Installation of AMSAFE Inflatable Restraint Systems in accordance withModel Specific Master Data List identified on AMLSA02276AK	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AMSAFE Flight Manual Supplement Document Number E509433, Revision NC,dated 25 August 2006<(>,<)>- AMSAFE Instructionsfor Continued Airworthiness Document NumberE509424, Revision F, dated 3 June 2016<(>,<)>or later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in acc...	1). The STC is valid for those aircraft types and models approved byEASA as defined on EASA Product Lists, that are contained in the FAAApproved Model List SA02276AK, rev. T, dated 30 December 2016 or laterFAA approved revision.2). If the holder agrees to permit another person to use thiscertificate...	13/09/2018	Active	10031010
10031018	ZIM FLUGSITZ GmbH			A310-300	Replacement of E/C seats by ZIM E/C seats, Type ECO-01This STC consists in replacing the existing seats by Type ECO-01seat.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Declaration of Compliance, ref : 502101-COC-003 Issue 0A, dated 27 July2010or later revisions of the above listed documents approved by EASA	None	21/07/2010	Active	10031018

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031050	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR02767NY	AW119MKII	Installation of an Artex ME406P ELT	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Agusta Aerospace Corporation installation master drawing list, reportno. AAC-ENG-09-031, rev - , dated 08 October 2009- Agusta Aerospace Corporation Instructions for Continued Airworthiness,report no. AAC-ENG-09-038, rev - , dated 7 October 2009 , FAAaccepted 18 December 2009or later accepted r...	none	23/07/2010	Active	10031050
10031056	TELEDYNE CONTROLS, LLC	REV. 1	FAA STC ST00498LA	B757-200	Installation of Aircraft Communications, Addressing and Reporting System (ACARS)	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	Teledyne Control's Master Data List No. MDL 2231500-820 Revision B, 12/10/1998.Teledyne Controls AFM Supplement TDY-ACARS-757-COA-2 dated 30/09/1998.or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/ CF (or subsequent revisions ofthis decision...	None	23/07/2010	Active	10031056
10031080 (EASA.IM.A.S.03186)	BLACKHAWK MODIFICATIONS Inc.		FAA SA4705SW	65-A90, B90, C90	Upgrade King Air 65-A90, B90 and C90 airplanes with PT6A-28engines	FAR 23	Installation of Pratt and Whitney PT6A-27 or PT6A-28 engines in ModelC90 in accordance with drawing 02-001, Revision B,dated June 5, 2008 orlater approved revisions.Or PT6A-27 orPT6A-28 engines in Model 65-A90 or B90 in accordance withdrawing 04-001, Revision B, dated June 5, 2008 or later approve...	Engines can be either type certified Pratt and Whitney PT6A-27 orPT6A-28 engines, or converted PT6A-27 or PT6A-28 engines from PT6A-21engines in accordance with Atlantic Turbines International Inc STCSE02290NY, or converted PT6A-27 or PT6A-28 engines from PT6A-11 enginesin accordance with Atlantic T...	26/07/2010	Active	10031080
10031088	BOMBARDIER INC.	REV. 1	TCCA STC SA05-60	BD-700-1A11	Installation, Interior Completions In-Service Improvements Modifications-ASN 9373	EASA TCDS No. IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certifi...	TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.TCCA SoC ref. C-11-0063 dated 16 February 2011.EASA STC No. 10031088.Aero Consulting Services Ltd Configuration Definition List E025000Revision EL dated 01 February 2011.Bombardier Aerospace Airplane Flight Manual Supplement G-FM25004501Revision N/C or...	Restricted to ASN 9373	24/02/2011	Active	10031088
10031092	DANSK FLY ELEKTRONIK ApS			PA-42, PA-42-720, PA-42-1000	Installation of Avidyne EX500 MFD	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appr...	DFE Design Order DFE-DO-0375DFE-DO-0375 Design package Rev.00 or later revisions	None	27/07/2010	Active	10031092
10031093	DANSK FLY ELEKTRONIK ApS			PA-42, PA-42-720, PA-42-1000	Installation of one or two Garmin GTX 330D Mode-S transponder	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appr...	DFE Design Order DFE-DO-0367DFE-DO-0367 Design Package Rev.00 or later revisions	None	27/07/2010	Active	10031093

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031105 (EASA.IM.A.S.03036)	BOMBARDIER INC.	REV. 1	TCCA STC SA 08-65	BD700-1A10	Water Tank Modification	EASA TCDS No EASA.IM.A. 009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this cer...	-EASA STC No. EASA.IM.A.S.03036 dated 02 June 2009.-TCCA STC No. SA08-65 Issue 3 dated 02 July 2010.-TCCA SoC referenceC-10-0260 dated 21 July 2010.-Aero Consulting Services Modification Data Summary Number F250000Revision C or later approved revision.-Bombardier Instructions for Continued Airworth...	None	27/07/2010	Active	10031105
10031114	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR02777NY	AW119MKII	Installation of a SX-5 Searchlight and cargo Hook Heated rearview mirror	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Agusta Aerospace Corporation installation master drawing list, reportno. AAC-ENG-09-041, rev A , dated dated 20 December 2009- Agusta Aerospace Corporation Rotorcraft Flight Manual, report no.AAC-ENG-09-048, rev - , dated FAA approved March 15, 2010 or laterrevisions of the above listed document a...	none	28/07/2010	Active	10031114
10031128	SCANDINAVIAN AVIONICS DESIGN ApS			ATR 42-200/300/320	Installation of Rockwell Collins TCAS-94 System with SingleTDR-94DSystem, as per Scandinavian Avionics Engineering Order 2056096-EO issue1 dated 27th September 2010 or later EASAapproved revisions.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA CS25 amendment 4 plus:- EASA Special Condition CRI F-001 Issue 3 "HIRF Protection" and- EASA Special Condition CRI H-001 Issue 2 "Enh...	See Scandinavian Avionics Design documents:- Certification Documents 2056096 DOC issue 2- Engineering Order 2056096-EO Issue 1- Aircraft Flight Manual Supplement (XPDR) 2056096-AM-A Issue 2- Aircraft Flight Manual Supplement (XPDR) 2056096-AM-B Issue 3- Continued Airworthiness 2056096-CA issue 2- Ma...	None	11/10/2010	Active	10031128
10031129 (EASA.A.S.03981)	DANSK FLY ELEKTRONIK ApS			PA-42, PA-42-1000, PA-42-720	Installation of dual Garmin GNS 430AW, dual Garmin GNS 530AW or GarminGNS 430AW and GNS 530AW	CS-23	DFE-DO-0366 Data Package Rev. 00 or later revisions	For PA-42 with Bendix King EFIS only	28/07/2010	Active	10031129
10031133	WIPAIRE Inc.		FAA STC SA02808CH	DHC-6-200, -300	Installation of nine passenger executive seating system in accordancewith FAA STC SA02808CH	The Certification Basis for the original product remains applicable tothis certificate/ approvala) The type certification basis for the DHC-6-200 and DHC-6-300 is asshown on TCCA TCDS A-82 for parts not changed or not affected by thechange.b) The certification basis for parts changed for affected by...	FAA approved Flight Manual Supplement, Document Number W056144-25, norevision, dated February 8,2010Instructions for Continued Airworthiness, Document Number W056144-24, norevision, dated February 11, 2010Installation in accordance with Wipair, Inc. Drawing No. 1004310,Revision B, dated January 10,R...	none	28/07/2010	Active	10031133
10031140 (EASA.IM.A.S.02821)	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03713-AT	G150	Installation of Enhanced Vision System (EVS) II	The Certification Basis for the original product remains applicable tothis certificate/ approvalJAR 25 Change 15 (referto TCDS)The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to th...	G150 EVS II Master Program Drawing List, G150-GER-0039, dated 26. March2009EVS II Flight Manual Supplement 2009-02, Revision 1, dated 05 May 2010Instructions for Continued Airworthiness, G150-GER-0037, Rev. -- dated05. Jan. 2009or later revisions of the above listed documents approved by EASA inacco...	This approval does not constitute any operation credit	28/07/2010	Active	10031140

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031149	ACS-NAI Ltd.		TCCA STC SA10-26	CL-600-2B19	Installation, CMC Electronics Pilot view Class II Electronics Flight Bag	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	TCCA SoC ref. C-10-0364 dated 20 July 2010.TCCA STC ref. SA10-26 Issue 1 dated 19 March 2010.ACS-NAI Ltd Modification Data Summary Number G370000 Revision A.Savannah Air Center Airplane Flight Manual Supplement for Class 2Electronic FlightBag (EFB), G115091 Revision NC.Savannah Air Center Instructi...	None	29/07/2010	Active	10031149
10031167	MT-PROPELLER ENTWICKLUNG GmbH			PC-6/B2-H4 PC-6/B1-H2, PC-6/B2-H2	Installation of 4-blade MTV-16-1-E-C-F-R (P)/CFR240-55() propeller onPilatus PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23, Amendment 1-34 (not required by 21A.101, elected to comply bythe applicant) This certificate/ approval involves a change to the ce...	-Airplane Flight Manual Supplement, Doc. No. E-1861, dated 17.03.2010-Airplane Flight Manual Supplement (propeller speed reduction). Doc. No.E-1861-1, dated 17.03.2010-Instructions for Continued Airworthiness, Doc. No. E-1863, Revision 0,dated 17.03.2010or later revisions of the above listed documen...	None	29/07/2010	Active	10031167
10031180	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		2. PA-31T2 2. PA-31P, PA-31T, PA-31T1 1. PA-31, PA-31-325, PA-31-350	Dual/Single installation of Garmin GNS430(A)W/530(A)W with GPS AntennaGarmin GA35 and Roll Steering Converter DAC GDC31.	CS-23	Installation must be in accordance with Master Document List EngineeringOrder No. ASR 2008-163-MDL-01-00 Amend. 00 dated 24.March 2010 or laterApproved Revisions.Operation must bein accordance with Flight Manual Supplement No. ASR2008-163-FMS-05.1-00 dated 28.01.2010 (for GNS430(A)W/530(A)W) and AS...	none	13/09/2010	Active	10031180
10031182 (EASA.A.S.03940)	F. LIST GERMANY GmbH	REV. 1		DORNIER 328-300 DORNIER 328-100	Change seat cushions bottom and backrest, JB6 series and AMP 1300 seriesfor DORNIER 328-100 and 328-300.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	OHS Master Documents List ASE04-10-MDL-01-xx, Revision 4 dated18.06.2010<(>,<)>or later revisions of the above listed documents approved by EASA.-STC10031182_Transfer signed by CEO of F. List Germany GmbH.-STC10031182_OHS Aviation Services GmbH Affidavit_31052017.-STC10031182_F. List Germany GmbH...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/12/2017	Active	10031182
10031184	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9351	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Transport Canada SoC reference C-10-0355 dated 29 July 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionFN dated 27 July 2010.Instructions for Continued Airworthiness GC93510000-IFCA.or later revisions of the above liste...	Restricted to ASN 9351 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).3.Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and...	30/07/2010	Active	10031184

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031201	LUFTHANSA TECHNIK AG			A340-213	A340-200 - Installation of provisions for Live TV, Satcom, and W-LANThis STC installs several structural provisions forLive TV, Satcom, andW-LAN systems, relocates the existing upper Anti-Collision Light (ACL)and installs a additional upper ACL.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Elect to Comply:- CS 25.1729 Amdt 08- CS 25 App H 25.5 Amdt 08Means of Compliance:- F-2304-003 Iss 1 (Wireless Local Area Network generic...	Supplemental Type Definition Document, ref : STDD 00-10/07MIssue 1,dated 22 July 2010Instruction for Continued Airworthiness, ref : A-00-10_131-ICA Issue 1,dated 06 July 2010or later revisions of the above listed documents approved by EASA	Limited to MSN 151	30/07/2010	Active	10031201
10031209 (EASA.A.S.03618)	SAAB AB	REV. 4		382	Installation of Saab Missile Protection System. The installationconsists of a forward sensor fairing on both sides of the nose and arear sensor installation in the tail. The dispensers are installed onboth sides under the rear edge of the wing.Inside the aircraft a Control panel has been installed i...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- CS-25 Am 6.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the product are unchangedand remain a...	Installation In accordance with Saab Aerotech Modification refTDM07-37-ID rev B, dated 2010-02-15Operation in accordance with Flight Manual TDM07-37-4-AFMS rev D, dated2010-04-19To be Maintained in accordance with TDM07-37-4-ICA rev D, dated2010-06-08or later revisions of the above listed document(s...	Aircraft Serial 4954 OnlyThe STC grants no operational approval, the aircraft operator will needto obtain operational approval from the Agency or Authority responsiblefrom the State of registry and the State in whose airspace it is to beoperated.Prior to installation of this change/repair it must be...	12/09/2023	Active	10031209
10031215	MARSHALL OF CAMBRIDGE AEROSPACELIMITED		CAA UK RESPONSIBILITY	A340-300	Structural Installation of 2 IFF Antennae	CS 25 Amendment 6The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Certificate of Design MA 1903, CD/A340(1903)/ 09/0625 Issue 2 dated 28July 2010.Instructions for Continued Airworthiness, SBM23-009.or later revisions of the above listed documentsapproved by EASA	none	02/08/2010	Active	10031215
10031221	AIRCRAFT SYSTEMS AND MANUFACTURING,Inc.		FAA STC ST09040SC	B737-300, -400, -500	Installation of Digital Flight Data Recorder System (DFDR) using aTeledyne Digital Flight Data Acquisition Unit (DFDAU)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 Issue 2:Special Condition - Enhanced Airworthiness program forAeroplane System - ICA on EWIS.The requirements for environmentalc...	FAA STC ST09040SC dated September 08, 2006Aircraft Systems & Manufacturing Top Drawing List No. Q4010-000-00, Rev.R dated December 11, 2006or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision2004/04/CF (or subsequent revisions ofthis decision)	none	03/08/2010	Active	10031221
10031227	MARSHALL OF CAMBRIDGE AEROSPACELIMITED		CAA UK RESPONSIBILITY	A340-300	Structural Installation of a V/UHF Antenna	CS-25 Amendment 6The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Certificate of Design MA 1904, CD/A340(1904)/ 09/0627 Issue 2 dated 28July 2010.Instructions for Continued Airworthiness, SBM23-010.or later revisions of the above listed documentsapproved by EASA	none	03/08/2010	Active	10031227
10031230	KNOTS ACQUISITION LTD.		FAA SA1217GL	2. PA-32R-301, PA-32R-301(SP) 2. PA-32-301, PA-32-301T 1. PA-32R-301T(TC) 1. PA-32R-301(HP) 1. PA-32-301FT, PA-32-301XTC	Installation of wing root fairings in accordance with FAA STC SA1217GL (Revision of LBA EMZ 1221, issue 1, dated July 20, 2001).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Knots2U, Ltd. Installation and Maintenance Manual, documentnumber32WR-M, revision E, dated May 2, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisionsofthis decision)	None	03/08/2010	Active	10031230

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031235	KNOTS ACQUISITION LTD.		FAA STC SA1521GL	2. PA-32R-301, PA-32R-301(SP) 2. PA-32-301, PA-32-301T 1. PA-32R-301T(TC) 1. PA-32R-301(HP) 1. PA-32-301FT, PA-32-301XTC	Installation of flaps, aileron, flap/fuselage and stabilator gap sealsin accordance with FAA STC SA1521GL.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Knots2U, Ltd. Installation and Maintenance Manual, documentnumber32FGS-M, revision F, dated May 2, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	03/08/2010	Active	10031235
10031236	KNOTS ACQUISITION LTD.		FAA SA1195GL	2. PA-32RT-300T 2. PA-32R-301T(SP), PA-32R-300 2. PA-32R-301(SP), PA-32S-300 2. PA-32R-300, PA-32RT-300 2. PA-32-301, PA-32-301T 2. PA-32-260, PA-32-300 1. PA-32R-301T(TC) 1. PA-32R-301(HP) 1. PA-32-301FT, PA-32-301XTC	Installation of Flap Hinge Fairing seals in accordance withFAA STCSA1195GL (Revision of LBA EMZ 1222, issue 1, dated July 20, 2001).	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Knots2U, Ltd. Installation and Maintenance Manual, documentnumber32HF-M, revision D, dated February 10, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	03/08/2010	Active	10031236
10031240	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	B737-400	B737 GPS UPGRADE OF EGPWS	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01- issue 2: Special Condition "Enhanced Airworthiness programmefor aeroplane Systems - ICA on EWIS"The requirements for environmen...	-Master Data List MDL-0069-10 Rev. 00 dated 23/04/2010 (plus EDI10105822)-Service Bulletin BA-737-34-0015 Rev. 00-AFM manual change request, BA Ref: 10098651or later revisions of the above listed documents approved by EASA	None	05/08/2010	Active	10031240
10031241 (EASA.IM.A.S.02712)	FLINT AERO, INC.		FAA STC SA3226NM	T210L, T210M, T210N, P210N T210G, T210H, T210J, T210K 210M, 210N 210G, 210H, 210J, 210K, 210L	Installation of 16,25 US Gallon usable fuel lightning resistant wing tipfuel tanks	The Certification Basis for the original product remains applicable tothis certificate/ approval.CAR 3The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	Installed in accordance with Flint Aero Master Drawing ListMDL FALS210N/CFAA approved Flint Aero AFM-S dated 16 Jan 1984or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	According limitation section of AFM-SFor P210N and T210N following limitation additionally apply:-Wing Tip Aux/ Aux Tank either is less than 7 gals MTOW 3730lbs, MLW3530lbs-Wing Tip Aux/ Aux Tank both are 7 gals or more MTOW 4000lbs, MLW3800lbs	03/08/2010	Active	10031241
10031247	SKYTRAC SYSTEMS LTD.	REV. 2	TCCA STC SH10-24 ISSUE 2	407 206L, 206L-1, 206L-3, 206L-4, 206A, 206A-1, 206B, 206B-1,	SkyTrac ISAT Airborne Position/Data Communicator	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	MDL10033 revision N/C dated 10 May 2010 - Master Drawing List;FMS10033-2 revision N/C dated 11 May 2010 - Flight ManualSupplement;ICA10033-2 revision N/C dated 11 May 2010 - Instructions for ContinuedAirworthiness.	STC EASA.IM.R.S.01137 is a prerequisite to this installation.	22/12/2010	Active	10031247
10031251 (EASA.IM.A.S.03270)	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA00871SE	SEE FAA AML SEE EASA APPROVED MODEL LIST	Installation of cockpit sunvisors	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rosen Products LLC drawing lists per the attached FAA AML No. SA00187SE<(>,<)> reissued1 July 2022<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/04/2023	Active	10031251

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031253	AIRMOTIVE ENGINEERING CORPORATION	REV. 1	FAA STC SE10129SC	SEE EASA APPROVED MODEL LIST	Installation of rotocoil, valve springs, ni-resist valve guide, exhaustvalve with chrome flash on stem, and rocker shaft with thrust buttons inaccordance with ECi Drawing Number AEC65314, Rev E, dated February 6,2003, or later FAA approvedrevision - EASA Validation of FAA STCSE10129SC	CAR 13 / FAR 33The Certification Basis for the original products remain applicable tothis certificate.	Installation data and Instructions for Continued Airworthiness arecontained in ECi Service Instruction 02-8, Rev. IR, dated February 5,2003<(>,<)> or later revisions approved by EASA in accordance with EASAED Decision 2004/04/CF (or subsequent revisions of this decision)	none	04/11/2010	Active	10031253
10031258	RUAG AEROSPACE SERVICES GmbH			DC-9-83 (MD 83)	Cabin Layout/Interior Change -DC-9-83	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-001/SC H-001	RUAG Doc. No. 293B-SD; 293B-MDL; 293B-AMMSor later revisions of the above listed documents approved by EASA	none	05/08/2010	Active	10031258
10031264	ROEDER PRAEZISION GMBH	REV. 1		C90A, C90GT, C90GTI, C90	Installation of an Avidyne Traffic Advisory System TAS 600/610/620	The Certification Basis of the original product and the followingadditional / alternative airworthiness requirements are applicable tothis change.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain ap...	Master Document List, Project No. C90-NY-07137, Rev. 1, dated 03 August2010, or later approved revision.Master DocumentList, Project No. C90-NY-07137, Rev. 1, dated 3 August2010,or later approved revision.Flight Manual Supplement, Doc. No. C90-NY-07137-08, Rev. 1, dated 2August 2010, or later appr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	15/11/2017	Active	10031264
10031271	LEARJET Inc.		FAA STC SA8117NM-D	CL-600-2B16	Installation of the RH Forward Lavatory	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	FAA STC No. SA8117NM-D dated 24 June 1998.Learjet Master Drawing List No. CA-3068e-TUC Revision A dated 10 June1998 or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	06/08/2010	Active	10031271
10031274	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR02265NY	A119/AW119MKII	Installation of pedal extensions on A119, AW119MKII helicopters	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	For A119 helicopter:- Agusta Aerospace Corporation installation master data list, report no.AAC-ENG-05-091, rev - , dated 24 April 2006For AW119MKII helicopter:- Agusta Aerospace Corporation installation master data list, report no.AAC-ENG-08-086, rev - , dated 30 January 2009For A119 helicopter:- A...	none	06/08/2010	Active	10031274
10031275 (EASA.IM.A.S.00765)	RAISBECK ENGINEERING Inc.	REV. 5	FAA STC SA2698NM-S	B) B200CGT B) B200, B200C, B200GT, B) B200, B200C, B200GT A) A200, B200T, B200CT A) 200, 200C, 200T, 200CT, A) 200, 200C, 200T, 200CT	Installation of a set of Hartzell/Raisbeck Quiet Turbofan Propellers orSwept Turbofan Propellers or Five-Blade Swept Turbofan Propellers. Theinstallation consists of Hartzell/Raisbeck 4-bladed or 5-bladedpropellers and aluminium hubs with spinners, and a propeller de-icingsystem.Revision to STC 1002...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: ICAO Annex 16,A...	Installation in accordance with Raisbeck Engineering Drawing List85-1500, Revision BV, dated September 13, 2019.Operation in accordance with the applicable FAA approved Airplane FlightManual Supplement (AFMS) in accordance with AML SA2698NM-S, or previousversions of this STC.Continued AirworthinessN...	Limitations List:Compatibility between this supplemental type certificate (STC) and STCsSA1783NM, SA10737SC, SA00433AT,SA10824SC, and SA10842SC has beendemonstrated. A copy of this certificate, and the appropriate AFMSdetermined from AML SA2698NM-S must be maintained with the permanentrecords of th...	14/11/2023	Active	10031275

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031277	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR02789NY	AW119MKII	Installation of a Border Guard Configuration	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Agusta Aerospace Corporation installation master data list, report no.AAC-ENG-09-011, rev A, dated 2 February 2010- Agusta Aerospace Corporation Rotorcraft Flight Manual, reportno.AAC-ENG-09-018, rev - , dated 02 April 2010 or later revisions of theabove listed documents approved by EASA in accor...	none	06/08/2010	Active	10031277
10031298	AERO DYNAMIX, Inc.	REV. 2	FAA STC SR09519RC	AW119MKII	Installation of Night Image Vision System (NVIS) / Night Vision Goggles(NVG) Cockpit lighting.Revision 1: Minor change to FAA STC SR09519RC to cover addition of a newconfiguration.Revision 2: Revision to EASA RFMS, introducing Appendix No.RFMSAAW119MKII-01-07, Rev. A- to cover the update to the Fin...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List, MDL 2370-01, Rev. V, dated 04.05.2021- RFMS AW119MKII-01-EASA Revision A, dated 10.09.2019- RFMSA AW119MKII-01-EASA-04, Revision IR, dated 10.09.2019- RFMSAAW119MKII-01-EASA-07, Revision A, dated 28.06.2021or later revisions of the above listed document(s) approved/ accepted o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/07/2021	Active	10031298
10031299	LEARJET Inc.		FAA STC SA8118NM-D	CL-600-2B16	Installation of the RH Forward Galley	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	FAA STC No. SA8118NM-D dated 25 June 1998.Learjet Master Drawing List No. CA-3067e-TUC Revision B dated 24 June1998 or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	09/08/2010	Active	10031299
10031307	RAISBECK ENGINEERING Inc.		FAA STC ST01182LA	A320-232	A320 bin extension systemInstallation of a bin extension system in accordance with FAASupplemental Type Certificate ST01182LA issued 10 July 2001.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Raisbeck Commercial Air Group (RCAG) Project Specific CertificationPlan report number 200A-2540 revision C dated 5 January 2001.- A320 Bin Extension Installation Part List 200A-2500 Rev. E dated 11March 2002.- Master Data List 200A-2010 Rev. G dated 11 November 2002.- RACG Component Maintenance Ma...	- Refer to paragraph "Limitations & Conditions" listed in the FAA STCST01182LA;The Maintenance Instructions for Continued Airworthiness are containedin the RCAG Component Maintenance Manual 200A-2560. These maintenanceinstructions must be included in the operator's Aircraft MaintenanceManual and the...	09/08/2010	Active	10031307
10031316	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR02428NY	A119 / AW119MKII	EASA Validation FAA STC SR02428NY for A119 / AW119MKII - High VisibilityCrew Doors	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirement for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions for the High Visibility Crew Doors, Report n.AA-04051, Revision F, dated March 27, 2007 for the A119.Installation Instructions for the High Visibility Crew Doors, Report n.AAC-ENG-08-075, Revision -, dated November 12, 2008 for the AW119MKII.Instructions for Continued Airwo...	None	09/08/2010	Active	10031316

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031318	LEARJET INC		FAA STC SA8119NM-D	CL-600-2B16	Installation of the Bulkhead F.S.353	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	FAA STC No. SA8119NM-D dated 24 June 1998.Learjet Master Drawing List No. CA-3059a-TUC Revision (-) dated 04 May1998 orlater approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	10/08/2010	Active	10031318
10031319	LEARJET INC		FAA STC SA8120NM-D	CL-600-2B16	Interior Installation - Main Cabin	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	FAA STC No. SA8120NM-D dated 25 June 1998.Learjet Master Drawing List No. CA-3003f-TUC Revision B dated 24 June1998 or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	10/08/2010	Active	10031319
10031320	LEARJET INC		FAA STC SA8122NM-D	CL-600-2B16	Installation of the Armledge / Dado	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	FAA STC No. SA8122NM-D dated 24 June 1998.Learjet Master Drawing List No. CA-3065f-TUC revision A dated 10 June1998 or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	10/08/2010	Active	10031320
10031322 (EASA.R.S.01547)	RUAG AG	REV. 1		500 N	IRIS Camera Installation.Installed: L3 Avionics System TypeA100 IRIS Camera System.Rev 1: Transfer of STC to a new legal entity that is holder of a new DOA (EASA.21J.760)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Master Document List: RUAG Doc. Nr. 1864441-00-Instructions for Continued Airworthiness: RUAG Doc. Nr. 1864441-60-Rotorcraft Flight Manual Supplement: RUAG Doc. Nr. 1864441-50or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Serial number: LN088Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changeand/ or repair will introduce no adverseeffect upon the airworthiness of the product.	18/01/2021	Active	10031322
10031332 (EASA.A.S.03317)	FOKKER TECHNIEK B.V.	REV. 1		A318-112	A318-112 VIP conversion, for description see Chapter 1.1 of. ComplianceRecord Report A18-MAK-CRR-0001 issue 5 d.d. 29-5-2009Revision 1: Transfer of STC from Fokker Services B.V. (EASA.21J. 059) toFokker Techniek B.V. (EASA.21J. 667)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Compliance Record Report A18-MAK-CRR-0001 issue 5 d.d. 29-5-2009-AFM Supplement Airbus A318 Model A318-112 Aircraft for the VIPConversion As installed in Serial number 3238 issue5 d.d. 29-5-2009-MMEL Supplement Airbus A318 Model A318-112Aircraft for the VIPConversion As installed in Serial number...	1. Refer to Chapter 2, Limitations of the AFM Supplement Airbus A318Model A318-112 Aircraft for the VIP Conversion As installed in Serialnumber 3238 issue 5 d.d. 29-5-20092. The STC is approved only for the product configuration as definedinthe approved design data referred to in paragraph “Descrip...	05/12/2019	Active	10031332

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031335 (EASA.A.S.00306)	BUSINESS AND COMMUTER AIRCRAFT	REV. 2		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Installation of a multi-functions display Honeywell type KMD-850applicable to Cessna Citation II model 550 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	UAE 015 03 E3 R4, or later approved revisions.	1. AFM Supplement UAE No 47 issue 1 Revision 1 dated 14 September 2004or later EASA-approved revision, is a required part of this STC2. Or AFM Supplement UAE No 15 issue 2 revision 2 (for MSN 0609) orrevision 5 (for MSN 0190) or later EASA-approved revision, is a requiredpart of this STC.3. The audi...	05/01/2015	Active	10031335
10031342	ACC COLUMBIA Jet Service GmbH	REV. 3		208B	208B Ferry Fuel Tank Installation – Rev 3Rev 2: Introduces a 300 Gal Ferry Tank and electrical connection ofauxiliary fuel pump to existing 28 VDC auxiliary power outletRev 3: Administrative corrections to STC limitations.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificat...	Installed and maintained in accordance with Document Number: Installation Instruction II_2023163_Rev2, Revision 2, Dated 17th June2022.Operated in accordance with Document Number:Flight Manual Supplement,SPOH_2023163_Rev2, Revision 2, Dated 17th June 2022or later revisions of the above listed docum...	This STC is applicable to Textron Aviation Cessna 208B aircraft with thefollowing engines installed:- Pratt & Whitney PT6A-PT6A-114A or<(>,<)>- Pratt & Whitney PT6A-PT6A-140 or<(>,<)>- Honeywell TPE331-12JR in accordance with FAA STC SA10841SCAnd the following embodied pre-requisites:- FAA STC SA003...	23/02/2023	Active	10031342
10031354	E A D AEROSPACE AIRWORTHINESS	REV. 1		A320	Installation of Advanced Mission Display System Phase A- AMDS/A on A320Series AircraftRevision of the EASA STC 10031354to remove EWIS limitation	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The...	- Master Drawing List, ref. 01272-EAS-A-MDL, Revision C, dated 22ndNovember 2010- Compliance Check List, ref. 01272-EAS-A-CCL-01, Revision A, dated 9thApril 2010- Airplane Flight Manual Supplement, ref. 01272-EAS-A-AFM-01, RevisionA, dated9th April 2010- Declaration of Compliance, ref. 01272-EAS-A-...	None	29/11/2010	Active	10031354
10031359	ROCKWELL COLLINS INC.		FAA STC ST01829LA	B747-400	Installation of Rockwell Collins enhanced Total Entertainment System inaccordance with System List 1304631, Revision N/C, dated August16, 2005or later FAA approved revisions.Validation of FAA STC ST01829LA	The Certification Basis for the original product remains applicable tothis certificate/ approval	Instructions for a Continued Airworthiness document nr. 1304944 Rev. ABAircraft Maintenance Manual Supplement 44-00-75or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	11/08/2010	Active	10031359
10031360	VAN RIEMSDIJK ROTTERDAM B.V.	REV. 9		B747-200F/-400F/-400BCF/-8F 747-400, 747-8F 747-200F, 747-400F	RZX-0506 Special Cargo Container 125”X196”Approval of NXE-0506 Special Cargo container 125” x 196” with PartNumber 136.020 and RZX-0506 SpecialCargo container 125” x 196” with Part Number 136.050 for use in B747freighter.Rev 5: Minor changes improving fuel level indicator and generator fueldrain sys...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Compliance Record Ref. CR-100136 issue 6- document Statement CST 0506 issue 2- CMM / IPL RZX Container P/N 136.050-080,Ref. 25-55-06 / RRM506-80issue 9- CMM / IPL RZX Container P/N 136.020-000 and P/N 136.050-000, Ref. 25-55-06 / RRM506 issue 20- CMM / IPL RZX Container P/N 136.050-081, Ref. 25-55-0...	Applicability to Model 747-400 limited to cargo configuration as perBoeing Service Bulletin 747-00-2004 "747-400BCF” or“747-400SF”.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ ore...	19/06/2024	Active	10031360
10031364	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC ST01911LA	B747-400	Installation of ACSS Mode S Transponder with ELS/EHS capability toreplace Mode S Transponder in existing ACSS Traffic Alert and CollisionAvoidance system TCAS II in accordance with FAA approval ACSS MasterData List Document No. 8900019-001, Revision B, dated August 2, 2006 ofIndex of Master Data Lis...	The Certification Basis for the original product remains applicable tothis certificate/ approval.	None	See Limitation Section of FAA approved ACSS Master Data List No. 8900019	11/08/2010	Active	10031364

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031371	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 350 B3	Coupling of the existing Sagem/SFIM Autopilot installation with theGarmin GNS530	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Drawing List A4/3501234-001, issue A, dated 10.08.2010- Instructions for Continued Airworthiness ICAW/ 3501234-001, issue B,dated 29.07.2010- Supplement No. 17 to the Approved Flight Manual AS 350B3 Helicopter,issue 1, dated 3.08.2010	none	12/08/2010	Active	10031371
10031404	DANSK FLY ELEKTRONIK ApS			B200, B200C	Installation of L-3 Skywatch HP Traffic Alert & Collision AvoidanceSystem, Model SKY899A.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23 Amendment 1The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certif...	DFE Design Order DFE-DO-0410 Design Package or later revisions of theabove listed documents approved by EASA	Garmin G1000 retrofit STC must be installed in aircraft prior toinstalling this STC.	13/08/2010	Active	10031404
10031405	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD	REV. 1	TCCA STC O-LSA10-185/D	BD-700-1A10, ASN 9287 HB-JGE	I-Ku System Installation with Viasat VMT 1500 Ku Band System andHoneywell MHC Cabin Management.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. O-LSA10-185/D Issue 1 dated 23 June 2010.Installation must be in accordance with Innotech Aviation Drawing ListMDL-9287-156 Revision F, or later approved revision.Operation must be in accordance with Innotech Aviation Airplane FlightManual Supplement FM010-002, Revision C or...	Restricted to ASN 9287	23/05/2011	Active	10031405
10031425	RAM AIRCRAFT, LP	REV. 2	FAA STC SA8125SW-D	CESSNA 414A	Installation of vortex generators in acc. with FAA STC SA8125SW-D, lastissue, dated May 12, 2008:Option 1: Modificationin acc. with RAM Master Drawing No. 1507,Revision C, dated 11/03/1992.Option 2: Modification in acc. with RAM Master Drawing No. 1507,Revision C, dated 11/03/1992(a) not approved(b...	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.	Option 1: No change to original Airplane Flight ManualOption 2: (a),,reserved(b),,reserved (c),,reserved(d),,RAM AFMS 1027, dated 16/03/1992(e),,reserved (f),,RAM AFMS 1029, dated 16/03/1992or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (...	None	12/11/2010	Active	10031425
10031457	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02079SE	B777-300	First and Business Class Cabin Interior - BA 777-300 aircraft	EASA TCDS No. IM.A.003The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certifi...	-FAA STC Number ST02079SE dated 10 August 2010-FAA SoC dated 17 August 2010- Northwest Aerospace Technologies Inc. (NAT) Master Drawing ListN0333-D10, Revision B dated 25 July 2010or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	None	17/08/2010	Active	10031457
10031459	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	F 406	Installation of Thales I-MASTER A-Flight Radar Turret	EASA TCDS No EASA.A.109The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certif...	STC Twenty One LimitedMaster Document List No. S21.MDL-0780Issue 1 dated 13 August 2010STC Twenty One LimitedFlight Manual Supplement No. S21.FMS-0063or later revisions of the above listed documents approved by EASA	none	17/08/2010	Active	10031459

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031460 (EASA.IM.A.S.03209)	BLACKHAWK MODIFICATIONS Inc.		FAA STC SA01248SE	PA-31T1 PA-31T	EASA Validation of FAA STC SA01248SE - Installation of two HartzellHC-E4N-3N/D8990SB propellers	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchangedand remain applicable to this certificate/ approval.	AFM Supplement AFMS-158P, Rev. 1Instructions for Continued Airworthiness Doc. ICA-150-5c, Rev. Aor later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisdecision)	none	17/08/2010	Active	10031460
10031462 (EASA.IM.A.S.03208)	BLACKHAWK MODIFICATIONS Inc.		FAA SA00863SE	PA-31T (CHEYENNE/ CHEYENNE II) PA-31T2 (CHEYENNE IIXL) PA-31T1 (CHEY. I/ CHEYENNE IA)	EASA Validation of FAA STC SA00863SE- Installation of two Pratt &Whitney PT6A-135 or PT6A-135A engines and two HartzellHC-B3TN-3B/ T10178B-8R or HC-E4N-3N/D8990SB propellers	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR23.1, 23.21, 23.51, 23.143, 23.149, 23.711, 23.905, 23.929, 23.933,23.930, 23.1027, 23.1041, 23.1045, 23.1141, 23.1163, 23.1183, 23.13...	- AFM Supplements: AFMS-150T-135, Rev. IR; AFMS-150T-135A, Rev. IR;AFMS-151T-135, Rev. IR; AFMS-151T-135A, Rev. IR; AFMS-152T-135A, Rev. 2,all dated 25 February 2009- Instructionsfor Continued Airworthiness Doc. ICA-150-5b, Rev. Aor later revisions of the above listed documents approved by EASA in...	none	17/08/2010	Active	10031462
10031510	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9349	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada SoC reference C-10-0308 dated 21 July 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionFH dated09 July 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Deci...	Restricted to ASN 93491.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS. 2.WLAN system is compatible only to IEEE 802.11 (b).	20/08/2010	Active	10031510
10031513	RAM AIRCRAFT, LP	REV. 1	FAA STC SA09105SC-D	CESSNA 414A	Modification in acc. with FAA STC SA09105SC-D: Aircraft modified inaccordance with RAM Master Drawing No. 1765, Revision B, dated20/09/1995 and Installation of modified TCM enginemodel TSIO-520-NB:Option 1: Cessna 414A modified by FAA STCSE09104SC-D or SE09261SC-D,FAA STC SA8125SW-D (Vortex Genera...	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.	-Option 1: RAM AFMS 1080, dated 25/09/1995- Option 2: RAM AFMS 1082, dated 25/09/1995- Option 3: reserved-Option 4: RAM AFMS 1098, dated 25/09/1995or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	This approval is limited to Hartzell PHC-C3YF-2UF/ FC7663D(B)-2Q or PHC-C3YF-2UF/FC7693DF(B) propellers.	12/11/2010	Active	10031513
10031514	DART AEROSPACE Ltd.		TCCA STC SH05-4	AS350 B, B1, B2, B3, BA, D	Installation of an Auxiliary Side Locker Fuel Tank.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MDL-D350-794, revision D, dated 09.08.2010- Flight Manual Supplement FMS-D350-794, revision C, dated 09.08.2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision) Instructions2...	none	20/08/2010	Active	10031514
10031517	DOA AESGLOBAL LIMITED	REV. 1		757-220	Introduction of Driessen G1A and G4B GalleysRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	FAA TCDS No. A2NMThe Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate...	AES Ltd MDL No. AES-757-1771 MDL Issue 4 dated 15 August 2010 or laterrevisions of the above listed documents approved by EASA	none	27/04/2021	Active	10031517

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031520	STG AEROSPACE Inc.AKA SAFTGLO, Inc.	REV. 1	FAA STC ST02311AT	DHC-8-402 DHC-8-202, -301, -302, -401 DHC-8-102, -103, -106, -201	Installation of SaftGlo Inc. Photoluminescent floor proximity EscapePath Marking System (PFEEPMS)	FAR 25 as per EASA.IM.A.191 for DHC-8-100/200/300 SeriesJAR/ CS-25 as per EASA.IM.A.191 for DHC-8-400 SeriesThe Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emiss...	Installation must be in accordance with SaftGlo MDL, ReportNumberM07-2, Rev. H, dated 1 August 2007.Operation must be in accordance with AFM Supplement SaftGlo Report No.M07-11, Rev. B, dated 25 October 2004, andFlight Attendant Manual Supplement, SaftGlo Report No. M07-13, Rev. E,dated 1 August 20...	Cabin interior arrangement must be approved in accordance with SaftGloMDL, Report Number M07-2, Rev. H, dated 1 August 2007 incorporatingSaftGlo drawing SG-DHC8, Rev. E, dated 1 August 2007.Electrically-lit door exit marker lighting levelsand cabin lightinglevels must be acceptable in accordance wi...	16/03/2011	Active	10031520
10031521	AIR AMBULANCE TECHNOLOGY GmbH	REV. 2		G100/ASTRA SPX	Installation of EMS interior for Gulfstream G100/Astra SPXReason for Revision 2: for each configuration (-501 or -503) a dedicatedComponent, Operation-, Installation- Maintenance Manual is issuedPrerequisites for each configuration are defined in the AFMS and therespective installation manual, there...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25, Amdt 4 - CS25.21, CS 25.25, CS 25.27, CS 25.301, CS 25.303, CS 25.305, CS 25.307,CS 25.321, CS 25.341, CS 25.471, C...	Master Data List MDL-G100-EMS, Rev. 0for config -501 Doc. no. EMS G100-25-20-40.000-501, Rev. 0for config -503 Doc. no.EMS G100-25-20-40.000-503, Rev. 0Airplane Flight Manual Supplement, Doc No. FMS AAT55, Part I Rev. 2,Part II Rev. 1, Annex 1, Rev. 0Component-, Operation-, Installation-, Maintenan...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/06/2016	Active	10031521
10031522	E & B HELICOPTERS LTD.		TCCA STC SH07-38	407	Audio Alert System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FMS703.91 revision 2 dated 24 August 2010 - Flight Manual SupplementDCL703 revision 3 dated 21 September 2007 - Document Control listor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision) CP703 revision...	None	27/08/2010	Active	10031522
10031536 (EASA.IM.A.S.01131)	HONEYWELL INTERNATIONAL INC.		FAA STC ST01280SE	B737-600/-700/-800/-900	Installation of the XK516 HF Transceiver System in accordance withMaster Drawing List 756-0173-001 (and FAA STC ST01280SE dated 15 October2003)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List ref. 756-0173-001, Revision F- Instructions for Continued Airworthiness Supplements as referencedinMaster Drawing List ref. 756-0173-001or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofth...	None	24/08/2010	Active	10031536
10031538	AERODISA S.L.			DC9-80 (MD80)	Aeronautical Capsat Transceiver	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CRI H-001/ SC.H-001	-AED2009-24M_AMMS Maintenance Manual Supplement-AED2009-24M_MDL Master Data List-AED2009-24M_MDLO Master Data List for Operators-AED2009-24M_W<(>&<) >B Weight & Balance-AED2009-24M_DIM Installation Manual-AED2009-24M_AWDS Wiring Diagram Supplementor later revisions of the above listed documents appro...	None	24/08/2010	Active	10031538

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031549	MICRO AERODYNAMICS, INC.		FAA STC SA01065SE	2. FA150K, FA150L, F152, FA152 2. F150K, F150L, F150M, 2. F150G, F150H, F150J 1. A150L, A150M, 152, A152 1. 150K, 150L, 150M, A150K 1. 150F, 150G, 150H, 150J	Installation of vortex generators on the wings and verticaltailsurfaces on Cessna 150/152 (see applicabel Model list).	CS-23.C	Installation of vortex generators on the wings and verticaltailsurfaces in accordance with Drawing Package MA2081, Revision IR, dated15th January 2002, and Installation Manual MA2082, Revision A, dated17th April 2002 or later approuved revision.Maintainace in accordance with Instruction of Continue...	Approval of this change in type design applies to the aircraft listed onAML SA01065SE only. This approval should not beextended to otheraircraft on which other previously approved modification areincorporated unless it is determined that the relationship between thischange and any other previouslyi...	25/08/2010	Active	10031549
10031570 (EASA.A.S.03968)	328 SUPPORT SERVICES GmbH	REV. 2		DORNIER 328-100/-300	Installation of Emergency Lighting Power Supply System.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CRI H-01/Special Condition H-01 "EnhancedAirworthiness Programme for Aeroplane Systems - ICA on EWIS".The requirements for environmental...	Master Document List - AM1561010A-01 Issue 2 dated 16 AUG 2010AFM Supplement - AM1561008A-01 Issue 1;Instructions for Continued Airworthiness - AM1561007A Issue A;or later revisions of the above listed documents approved by EASA.	None	27/09/2018	Active	10031570
10031606 (EASA.IM.A.S.03021)	BEECHCRAFT CORPORATION	REV. 2	FAA STC ST10922SC-D	MODEL 4000	Installation of Cabin Interior Furnishings and Systems.	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	Master Documents List (MDL) No. 240-2001 Rev. 69.Configuration 3:Configuration Drawing 240-044300 Rev.3Airplane Flight Maunual Supplement (AFMS) 240-590001-0007 Rev.3Completions Manual 23-10-65-HBC10003P dated August 2010 and44-30-20-HBC10009 dated January 2012Configuration 6:Configuration Drawing 24...	Only configuration 3, 6, 8 and 9 installations are EASA approved.Airworthiness Limitations inspections are contained inChapter 4 of theCompletions Manual.Airworthiness Limitations:for configurations 6 and 8 per 240-590011-0003C approved August 2010;for configurations 3 and 9 per 23-10-65-HBC10003P4...	16/10/2012	Active	10031606
10031609	TASS Inc.		FAA STC ST00583SE-D	B757-200	Installation of Passenger Accommodations - STC ST00583SE-D	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA Statement of Compliance reference 1505-10-233 dated 18May 2010.-FAA STC No. ST00583SE-D dated 07 May 2010.-BF Goodrich Master Data List 99-060, pages 1-20, Revision A dated 30July 1999.-TASS Inc document TASS-BAB-10-GQG01, Revision 00 dated 17 August 2010'Installation of Passenger Accommodatio...	None	30/08/2010	Active	10031609
10031612	AERO TECHNICS DESIGN LIMITED	REV. 2	CAA UK RESPONSIBILITY	B737-500	Cabin Seating Reconfiguration from 120Y to 16C/28C layout (44C)Rev. 1 was issued to remove limitation.Rev. 2 was issuedto change address on the certificate.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ATDDR0382_issue1 - Design Report dated August-2010ATDCCL0382_Issue 6 - Compliance Check List dated August-2010or later revisions of the above listed documents approved by EASA	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	05/08/2014	Active	10031612

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031614	AERO TWIN, Inc.		FAA STC SA4625NM	CESSNA 208, 208B	Fabrication and Installation of Aero Twin, Inc EB8-200 extended baggagekit in accordance to FAA STC SA4625NM	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement EB8-200-AFMS, Rev. B dated October 14,2004Instructions for Continued Airworthiness EB8-200-ICA, last revisiondated October 14, 2004Master DrawingList MDL EB8-200, last revision dated March 6, 2009or laterrevisions of the above listed documents approved by EASA ina...	None	31/08/2010	Active	10031614
10031622 (EASA.IM.A.S.03239)	EMBRAER S.A.		ANAC N °2009S0S-07	EMB-500	Installation of a Rockwell Collins Automatic Direction Finder ADF-462model		Installation in accordance with Master Document List No TR0083, Rev J,dated 14 May 2009 or later approved revisions.Operation in accordance with Embraer EASA Airplane Flight ManualSupplement (AFMS) for Rockwell Collins ADF-462 ADF system, Rev IR, dated19 June 2009 or later approvedrevisions.Instruct.. .	1. Required Markings and Placards:-.In close proximity to the 5A ADF breaker in breaker panel placard "ADF".2. Prior toinstallation of this modification the installer mustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce nou...	01/09/2009	Active	10031622
10031633	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	MBB-BK 117C2	Skyshout SystemInstallation of a Skyshout System. With internal cabin control andexternal loudspeaker array, installed on aircraft RHS and configuredwith low skid landing gear	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement No 17, dated 24th August 2010 orlater revisions of the above listed documents approved by EASA- Design Report DR/ 1451232-001 Issue A, dated 4th March 2010	none	01/09/2010	Active	10031633
10031637	1263343 ALBERTA INC DBA ENERJET		TCCA STC C-LSA10-077/D ISSUE 1	B737-700	Bucher LH Windscreen /Closet Modification	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01 Issue 1: Special Condition - EWIS ICAThe requirements for environmental protection and the associatedcertificated noise and/ oru...	Modification Data Summary R1004821 issue A dated April 2010Modification Review Continued Airworthiness & Safety Improvement R1006846 issue A dated June 2010or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/02/CF (or subsequent revisions ofthis...	Limited to B737-700 aircraft S/N 33920Maintenance of the Bucher Closet is to be performed by Boeing AircraftMaintenanceManual D633A101-CQT<(>,<)> and Bucher Component MaintenanceManual 25-30-65	01/09/2010	Active	10031637
10031638	1263343 ALBERTA INC DBA ENERJET		TCCA STC C-LSA08-311/D ISSUE	B737-700	131, 137 <(>&<)> 145 Passenger Seating Reconfiguration	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01 Issue 1: Special Condition - EWIS ICAThe requirements for environmental protection and the associatedcertificated noise and/ oru...	Modification Data Summary R0810701 issue C dated April 2010Modification Review Continued Airworthiness <(>&<)> Safety Improvement R1006845 issue A dated June 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions o...	Limited to B737-700 aircraft S/N 33920Maintenance of the Recaro seats are to be performed per Recaro ComponentMaintenance Manual 25-22-11, 25-25-81 and 25-24-79	01/09/2010	Active	10031638

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031639	1263343 ALBERTA INC DBA ENERJET		TCCA STC C-LSA08-310/D ISSUE	B737-700	Artex C406-2 ELT Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01 Issue 1: Special Condition - EWIS ICAThe requirements for environmental protection and the associatedcertificated noise and/ oru...	-Modification Data Summary R0810709 issue A dated November 2008.-Modification Review Continued Airworthiness & Safety ImprovementR1006844 issue A dated June 2010.-Aircraft Maintenance Manual Supplement R0809001 issue A.-ARTEX Maintenance Manual 570-5000 rev B and 870-4010 Rev A.or later revisions of...	Limited to B737-700 aircraft S/N 33920 and 34480	02/09/2010	Active	10031639
10031640	1263343 ALBERTA INC DBA ENERJET		TCCA STC C-LSA10-078/D ISSUE	B737-700	TIA Model 1545 oven Installation in forward LH monument.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01 Issue 1: Special Condition - EWIS ICAThe requirements for environmental protection and the associatedcertificated noise and/ oru...	Modification Data Summary R1004825 issue A dated April 2010Modification Review Continued Airworthiness <(>&<)> Safety Improvement R1006847 issue A dated June 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions o...	Limited to B737-700 aircraft S/N 33920Maintenance of the TIA Model 1545 Oven is to be performed per TIAComponent Maintenance Manual 25-30-61	01/09/2010	Active	10031640
10031662	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CL-600-2B16	Introduction of Swift Broadband	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	STC Twenty One Ltd Master Document List S21.MDL-0786 Issue 1 dated 26August 2010.STC Twenty One Ltd Flight Manual Supplement S21.FMS-0067or later revisions of the above listed documents approved by EASA	1. The Airworthiness Approval of the wireless system does not constituteOperational Approval for the use of transmitting PEDs on board of theaircraft. Operational Approval must beobtained from the responsibledivision of the operational authority of the aircraft's country ofregistration prior to con...	02/09/2010	Active	10031662
10031663	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9364	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada SoC reference C-10-0310 dated 30 August 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionFQ dated 18 August 2010.Instructions for Continued Airworthiness GC93640000-IFCA.or later revisions of the above li...	Restricted to ASN 9364 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).3.Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and...	02/09/2010	Active	10031663
10031668	CHIPPEWA AEROSPACE, Inc.	REV. 1	FAA STC SA03859AT	LIBERTY XL-2	Garmin GTX 330	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The certificatednoise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval....	Chippewa Aerospace Master Data List (MDL) XL2-3454-01-001, Rev. IR,dated 02/10/2010 or later revisions of the above listed documentsapproved by EASA in accordance with EASA ED Decision 2004/04/CF (orsubsequent revisions of this decision).	None	05/11/2010	Active	10031668
10031674	LUFTHANSA TECHNIK AG			B747-400	Trial installation of 2 rows of the BE/ Aerospace V-seats model BE 15.0PN series 1012121 as replacement for 3 rows of Recaro EC seat model 3410in Section B of the Lufthansa B747-400 reg D-ABVW, in accordance withLHT document STDD00-10/16M Issue 01	The Certification Basis for the original product remains applicable tothis certificate/ approval	None	This STC is limited to Lufthansa B747-400 aircraft sn 629493, reg D-ABVWThe approval for this trial is valid until November 30, 2010Compliance with CS 25.853 (heat release/smoke density) has not beenshown, in accordance with the certification basisThe seat approval is valid only for use in this tria...	03/09/2010	Active	10031674

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031686	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA STC SA10-18	BD-700-1A10	I-CAIR System Installation with JetAir Bio-Protection (BPS)System	EASA IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. SA10-18 Issue 1 dated 09 February 2010.Transport Canada SoC ref. 5010-O-10-0427 dated 31 May 2010.Innotech Aviation Drawing List MDL-BD700-151 Revision NCdated 15January 2010.Innotech Aviation Airplane Flight Manual Supplement FM09-010 Revision NCapproved 8 February 2010.In...	none	03/09/2010	Active	10031686
10031729	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	PIPER PA-34 ALL SERIES	Installation of Garmin G500/G600 PFD/ND	The Certification Basis for the original product remains applicable tothis certificate/ approvalCS 23Non-significantTherequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalproduct areunchanged and remain applicable to this certifica...	Master Data List MDL1101-01 Issue 1Change Statement CS1101-01 Issue 1Instructions for Continued Airworthiness ICA1101-01 Issue 1Flight Manual Supplement AFMS1101-01 Issue 1or later revisions of the above listed documents approved by EASA	This change is limited to the configuration defined in Change StatementCS1101-01 Issue 1 or later approved revision.	08/09/2010	Active	10031729
10031738	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	B300	Review of modifications installed prior to import	The Certification Basis for the original product remains applicable tothis certificate/ approval.	1) Systems installation and testing in accordance with aeroDAC FormJN222 ADC34 (1) Iss 1 dated 29/03/102) Operating Instructions defined in the following Airplane FlightManual Supplements:-a. Supplement No 001: aeroDAC Form JN222 ADC29 (1)Iss 1 dated 31/08/10b. Supplement No 002: aeroDAC Form JN222...	Aircraft Serial Number FL-327 Only	09/09/2010	Active	10031738
10031744	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Enhanced Mode "S" compliance upgrade applicable to DassaultAviationMystère Falcon 20 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Uni Air Enterprise Master Data List MDL-011-10 Revision IR,dated 26thAugust 2010.Uni Air Enterprise Compliance Design Document DDC-011-10 Revision IR,dated 23rd August 2010.Uni Air Enterprise Airplane Flight Manual (AFM) SupplementUAEAFMS-10-002 Revision IR, dated 23rd August 2010.or later revision...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	05/01/2015	Active	10031744
10031745 (EASA.A.S.03661)	EADS ELBE FLUGZEUGWERKE GmbH			A310-304/ -308/ -324/ -325 A300B4-605R/ -622R A300B4-601/ -603/ -620/ -622	Courier Stowage installationThis STC consists in modifying the Courier Area of aircraft converted byAirbus Pax to Freighter STCs by installing a Courier Stowage	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS25 Amendment 4Complementary Condition CC12-1: Crash design conditionsSpecial Condition CRI S2 Issue 2: Installation of Courier AreaFAR 2...	Engineering Order, ref: EFW-EO-0020-001, Issue Bor later revisions of the above listed documents approved by EASA	The current STC needs specific aircraft configuration as aprerequisite:- To install this STC on A310 aircraft models, embodiment of EASA STCref: 10013945, Rev 4 (or any further EASA approved revision) isrequired.- To install this STC on A300-600 aircraft models, EASA STC ref:10013960, Rev 5 (or any...	09/09/2010	Active	10031745

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031747	BELL HELICOPTER TEXTRON, Inc.	REV. 1	FAA STC SR00646AT	AB412, AB412EP, 205A-1, 212, 412, 412EP	Installation of replacement low skid landing gear crosstubes.Rev.1: Extension of scope of validity by 205A-1, 212, 412 and 412EP.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeronautical Accessories, Inc. Drawing List, Report No. AA-94042,Revision B, dated 20 January 1995 or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/08/2017	Active	10031747
10031757 (EASA.A.S.03984)	BUCHER LEICHTBAU AG	REV. 22		SEE AIRCRAFT ALLOCATION TABLE E043-04-12 E043-02-12	Installation of Bucher Leichtbau 16G ATS Stretcher 1123000-SeriesMajor Change to STC 10031757 with the following tasks:- Addition of the Airbus A321-253NY and A321-271NY aircraft models- Raising of the Certification Basis from current CS 25 Amdt 21 to newCS 25 Amdt 28.- Introduction of emergency eva...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:25.1, 25.21, 25.23, 25.25, 25.27, 25.301(a)(b)(c), 25.303,25.305(a)(b)(c), 25.307(a), 25.341, 25.561(b)(c)(d),...	-Master Document List E034-01-08 Rev. DH dated 02.09.2025-Aircraft Allocation Table E043-02-12 Rev. CC dated 22.05.2025-User Manual 25-67-47(E017-05-09) Rev. 27 dated Mar 11/2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.-Per User Manual 25-67-47 (E017-05-09)-This STC constit...	04/09/2025	Active	10031757
10031769	GAMA ENGINEERING Ltd.	REV. 3	CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	Child Restraint Systems (CRS) - Installation in Various AircraftRev 2: Installation in Additional AircraftRev 3: Installation in B787 (787-8 & 787-9)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Proposal Document CPD-CRS-01, Rev. 3-Certification Plan, ref. doc. No. TN 1898-005, Rev. C-Declaration of Design and Performance - DDP, ref. doc. No.DDP-1898-012, Rev. C-MDL: MDL-CRS-01, issue 1-ICA: refer to the associated ICA in MDL reference MDL-CRS-01, issue 1.or later revisions o...	1) Limitations in accordance with § 4 - Limitations of the abovementioned DDP, ref. No. DDP-1898-0122) All cabin interiors must be evaluated for compatibility of the ChildRestraint System (CRS). The CRS is not approved for aeroplanes that arenot defined by § 4 of the above referenced DDP3) Procedure...	10/10/2014	Active	10031769
10031773 (EASA.A.S.00307)	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE	REV. 1		CESSNA 550 (CITATION II)	Installation of Honeywell EGPWS Mark VIIIThe STC has been revised to implement the alternative EGPWS computer P/N965-1210-020 and the alternative EGPWS Configuration Module P/N700-1710-020.	EASA TCDS IM.A.207The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificat...	Master Data List MDL-004-02, Revision 6 from 08 September 2010Aeroplane Flight Manual Supplements-AFMS UAE No.15, Edition 2, Revision 2 from 24 May 2004 for S/N 550-0609-AFMS UAE No.15, Edition 2, Revision 6 from 06 April 2004 for S/N550-0190-AFMS UAE No.47, Edition 1, Revision 1 from 14 September 2...	Limited to: S/N 550-0001 through 550-0733The maintenance tasks referred in Supplement to Cessna 550 MaintenanceManual ref. EGPWS UAE No 4 Revision 6 are required. The audio declutterfunction must be disabled.	10/09/2010	Active	10031773
10031790	TQAS - TOTAL QUALITY AND AIRCRAFTSOLUTIONS, LDA			A310-304	Cabin Modification to Full EconomyCabin Reconfiguration from a 18C/184Y seats configuration to a 224Yseats configuration	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Design Dossier<(>,<)> ref. CG-001-010, dated 08 June 2010.Change/Repair Approval Sheet, ref. CG-001-10-MAS Issue 3, dated 07 June2010.Service Bulletin, ref. CG-001-10-SRB Issue 5,dated 07 June 2010.or later revisions of the above listed documents approved by EASA	Limited to MSN 573	14/09/2010	Active	10031790

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031791	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD	REV. 2	TCCA STC N° C-LSA10-022/ D	BD-700-1A10	Installation, Complete Custom Aircraft Interior	EASA TCDS No. IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certifi...	EASA STC No. 10031791.TCCA SoC ref. C-10-0936 dated 14 December 2010.TCCA STC No. C-LSA10-022/D Issue 1 dated 06 August2010.ACS-NAI Ltd. Modification Data Summary G481000 Revision B.Flight Manual Supplement for Interior Completion, FMS-IA700-9352Revision NC.Flight Manual Supplement for CMC Electron...	Restricted to ASN 9352.1. Refer to the Limitations sectionsof the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	31/01/2011	Active	10031791
10031793	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE	REV. 1	FAA STC SR02307LA	EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Cable Cutters KitInstallation of Apical Industries, Inc. Cable Cutters Kit withdeflectors on skids and wiper in accordance with Master Document ListMD135-2, based on FAA STC SR02307LA.REV. 1: Amendment of the STC in order to add the applicability to EC135T3 & P3 models.This revised EASA STC is based...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Revision 1:- Master Document List MD135-2, Rev. D- Instructions for Continued Airworthiness ICA135-21, Rev. C- Installation Instructions II135-21, Rev. F	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/08/2017	Active	10031793
10031798	SAVANNAH AIR CENTER, L.L.C.		FAA STC ST12210AT-T	BD-700-1A10	Installation, Complete Custom Interior, ASN 9347 Configuration.	EASA TCDS No. IM.A.009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of theu...	FAA SoC ref. ST12210AT-T dated 13 September 2010.FAA STC No. ST03870AT dated 13 August 2010.Savannah Air Center MDL, XRS9347-MDL-2500001, Rev. A dated 06 August2010.Instructions for Continued Airworthiness, Bombardier Global ExpressDocument Number XRS9347-ICA-0001, Revision IR dated 02 March 2010.or...	Restricted to ASN 93471.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS. 2.WLAN system is compatible only to IEEE 802.11(b).	14/09/2010	Active	10031798
10031804	SKYTRAC SYSTEMS Ltd.	REV. 1	TCCA SA06-85	B300, B300C B200, B200C, B200GT, B200CGT A200CT, B200T, B200CT A200CT/B200/B200C/ B200T/B200CT 300/300LW/B300/B300C/ 1900D 300, 300LW, 1900D, 200, 200C 200CT, 200T, A200, A200C 200/200C/200T/200CT/ A200/A200C	SkyTrac ISAT Position Data Communicator System InstallationRev 1 adds B200GT and B200CGT models.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation in accordance with Avionics Design Services LTD. MasterDrawing List MDL06103 Revision P, Transport Canada approved August 6,2019.For the 1900D:Operation in accordancewith SkyTrac Systems Ltd. Flight ManualSupplement FMS06103-1 Revision D, Transport Canada approved June 28,2019Maintenan...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/04/2022	Active	10031804
10031808	AMSAFE, Inc.	REV. 2	FAA STC ST02152LA	SEE EASA APPROVED MODEL LIST	Installation of AmSafe Seatbelt Airbag System (previously denominated asAmSafe Aviation Inflatable Restraint System, AAIR)Rev. 1: Applicability extended to Reynard Reverb seats fitted onA330-300 aircraftRev. 2: Applicability extended to Boeing 747-8, 777-200LR, 777-300ERaircraft model series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-01 “HIC Compliance Inflatable Restraint System” and CRI F-116“Non-rechargeable Lithium Battery Installations”The requirements for environmentalc...	AmSafe Master Data Lists:- E510380 Rev. A, dated Dec 20th 2016, for Boeing737-500/-600/-700/-800/-900/-900ER series- E511046 Rev. B, dated Dec 20th 2016, for Airbus A330-200/-300 series- E511507 Rev. B, dated Dec 20th 2016, for Airbus A330-300 seriesaircraft equipped with Reynard Reverb seats-E513215 R...	- For the installation of approved seats modified by installation of theAmSafe Seatbelt Airbag System in a specific cabin layout, compliance to25.561 must be demonstrated for the individual seat at its specificlocation within the approval project for the cabin layout. In addition,it must be demonstr...	22/08/2017	Active	10031808

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031815 (EASA.IM.A.S.03215)	B/E AEROSPACE, Inc. - FSI		FAA ST02038SE	A330-300	Installation of an Interior Reconfiguration in A330-300 Series aircraft	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS"The requirements for envir...	- FAA STC ST02038SE, dated 24th December 2009- Master Drawing List, ref. doc. No. A8FS827-D01, Revision P, dated 7thJuly 2010- Airplane Flight Manual Supplement, ref. doc. No. TP08-827AFM, Revision1, dated 6th January 2010- Supplemental Instruction for Continued Airworthiness, ref. doc. No.A8FS827-D...	Not applicable	17/09/2010	Active	10031815
10031816 (2004-5141)	FIELD AVIATION COMPANY Inc.		TCCA STC SH88-1	AS 332 L, AS 332 L1	Installation of 4 Place Auxiliary Seat TankThis EASA STC revises CAA STC 2004-5141 dated 14 may 2004 and adds modelAS332L1.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Tank Installation 300151-3-6346 revision D dated 14 October 1987 - Drawing List;-E300151 revision G dated September 1987 - Master Drawing;-FACL-6346-01 amendment 1 dated 6 November 1987 - Rotorcraft FlightManual Supplement;- FACL-6346-02 amendment 1 dated 6 November 1987 - Maintenance ManualSuppleme...	None	22/12/2010	Active	10031816
10031819	DRF STIFTUNG LUFTRETTUNGG EMEINNUETZIGE GmbH			MBB-BK117B-2, MBB-BK117 C-1	Installation of second directional gyro systemInstallation of a second directional gyro system for IFR operation basedon DRF Major Change Project 240 and defined in MD-117-34-20-00001.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS 29 Amdt. 2 forthe change.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels o...	Flight Manual Supplement 10-DRF-05, Rev. 1.0or later revisions of the above listed documents approved by EASA- Installation Manual IM-117-34-20-00001, Rev. 00- Instr. f. ContinuedAirworthiness CA-117-34-20-00001, Rev. A- Master Document List MD-117-34-20-00001, Rev. Aor later revisions of the above...	None	16/09/2010	Active	10031819
10031834	GROWING ENGINEERING PARTNERS GmbH	REV. 4		767-300	Cabin reconfiguration - Air Seychelles 767-300Aircraft reconfiguration by replacing the existing J-class seat with anewelectrically powered seat. There are adaptations to the existingPSU, Y-class cabins to suit new layout.Rev.4: Transfer of STC from SR Technics Switzerland to groWINGEngineering Par...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate.Certification basis as perTCDS plus:- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The req...	- Change Classification and Certification Sheet doc. Ref. C767-25-1010Rev 03 dated 18 November 2010;- Master Data List doc. Ref. C767-25-1010-MDL Rev 03 dated 18 November2010;- Instructions for Continued Airworthiness doc. Ref. C767-25-1010-ICA-01Rev 01 dated 08 Nov 2010;or later revisions of the ab...	None.	20/04/2021	Active	10031834
10031836	DELTA ENGINEERING CORPORATION		FAA STC ST02755NY	A330-300	Update of a Panasonic System eX2 In-Flight Passenger EntertainmentSystem	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS"The requirements for envir...	- FAA STC ST02755NY, dated 5th January 2010- Master Data List, ref. doc. No. 0154-06550-2200, Revision B, dated30th December 2009- Electrical Wiring Interconnection System (EWIS) Assessment, ref. doc.No. 6654-07006-2200, Revision -, dated 1st July 2010or later revisions of the above listed documents...	Not applicable	17/09/2010	Active	10031836

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031840 (EASA.A.S.03950)	AIRBUS S.A.S.	REV. 1		A320-232	Airbus Corporate Jet Centre Modification CJ0540 Issue 4 - VIP Interior -"QATAR"Revision due to update of AFM-S and MPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A-2301-002 "ACJC Project Certification Basis".The requirements for environmental protection and the associatedcertified noise and/ or emissions...	-,,Modification Approval Sheet ref.: CJ0540 Issue 4, dated 24th October2013-,,AFM Supplement Ref : FM-S MOD CJ0540, Revision 03, dated 1st October2013-,,MPD Supplement Ref : MPD-SMOD CJ0540, Revision 04, dated 1st October2013-,,MPD Supplement SAT TV Ref : MPD-S MOD CJ0277, dated 1st May 2012or late...	This STC is limited to A320-232 MSN 4170Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	25/10/2013	Active	10031840
10031863	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	B757-200	Introduction of CabinVu-123 Cabin Surveillance System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"	- Master Document List, doc. N° S21.MDL-0766 Issue 3 dated September14th, 2010.- Compliance Record, doc N° S21.COMP-0766 Issue 2 dated June 9th<(>,<) >2010.or later revisions of the above listed documents approved by EASA	None	20/09/2010	Active	10031863
10031894	LEARJET Inc.D/B/A BOMBARDIER AIRCRAFT SERVICES	REV. 1	FAA STC ST02025LA-D	31A	Installation of Northrop Grumman Dual LITEF LCR-100 AHRSFAASTC ST02025LA-D (issued March 10, 2010)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR 25.1316 Amendment 80FAR 25.1317 Amendment 122The requirements for environmental protection and the associatedcertificated noise and/ o...	Refer to FAA STC ST02025LA-Dor later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision.	Previous or concurrent requirement for this installation isan approvedinstallation of the LCR-93 AHRS in accordance with Learjet ECR 4467.	20/09/2010	Active	10031894
10031899	SCANDINAVIAN AVIONICS DESIGN ApS			HAWKER 800XP	Installation of an International Communications Group Inc, ICS-100Iridium Satellite Telephone.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalElect to Comply with CS-25 Am 4.The requirements for environmental protectionand the associatedcertificated noise and/ or emissions level...	Installation in accordance with Scandinavian Avionics Design documentref 2056325 STC (STC Document List)Operation in accordance with Scandinavian Avionics Design document ref2056325-AM (Aircraft Flight Manual Supplement) Instructions for Continued Airworthiness in accordance with ScandinavianAvionics...	Model Hawker 800XP, S/N: 258358	20/09/2010	Active	10031899
10031900	BOMBARDIER INC.		TCCA STC SA05-60 ISSUE 1	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9379	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certific...	TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.TCCA SoC ref. C-10-0356 dated 17 September 2010.Aero Consulting Services Ltd Configuration Definition List E025000Revision DR dated30 July 2010.Bombardier Aerospace Aeroplane Flight Manual Supplement G-FM25004501Revision N/C or later approved revision...	Restricted to ASN 9379	20/09/2010	Active	10031900

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031901	WORLDWIDE AIRCRAFT SERVICES Inc.		FAA STC SA4872SW	SA226-T, SA226-AT	Installation of 2 Garrett AiResearch engines Model TPE 331-10UA-501G orTPE 331-10UA-511G	The Certification Basis for the original product remains applicable tothis certificate/ approval.CAR 3This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.	SA226-T:Installed iaw KMA Information and Instructions No 401AD01, Rev EFAA approved AFM-S, dated 20 Dec 1982SA 226-AT:Installed iaw KMA Information and Instructions No 401BD01, Rev EFAA approved AFM-S, dated 15 Apr 1985or later revisions of the above listed documents approved by EASA inaccordance w...	according limitation section of AFM-S	21/09/2010	Active	10031901
10031903	AVIATION SERVICE A.S.			407	Installation of alternate static port for VFR night operation	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	FM 30 30/01 001 revision 0 dated 24 August 2010 - Flight ManualSupplement - alternate static port;or later revisions ofthe above listed documents approved by EASAAS 228 001P issue 0 dated 14 July 2010 - Instructions for fabrication,Installation and check;CP 228 Issue 0 dated 14 July 2010 - Certific...	None	21/09/2010	Active	10031903
10031914	CHRISTEN-AIRTECH AG			TBM 700 A	Avionics UpgradeOut: Dual COM-NAV Bendix-King KX-165A, GPS Apollo MNS2101, MFD ApolloMX20, Encoder Shadin 8800-TIn: COM-NAV-GPS Garmin GNS-530W & 430W, MFD Garmin GMX-200, EncoderACKA-30 Mod. 8 serial	CS 23The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Master Document List CAT-207.1698-EOMDL-01 Rev. 0 of 15.06.2010Instructions for Continued Airworthiness CAT-210.2483-CA-01 Rev. 0 of15.09.2010AFM Supplement Doc. No.: 210.2483-FS-01(530W)-00 & -02(430W)-00or later revisions of the above listed documents approved by EASA	Reg.: D-FIRE,,S/N: 137	21/09/2010	Active	10031914
10031917	AVIATION FABRICATORS, Inc.		FAA STC SA2818SW	441	Installation of 1, 2 or 3 place side seating divans in accordance withFAA STC SA2818SW	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Drawing list. AF-294, Rev. E, dated September 1, 2010Installation instructions: D-10273, Rev. C, dated September 1,2010Installation location instruction (1 place, 2 place, 3 place divan):AF-497, AF-498, AF-499 accordingly, no Rev., all dated March 26, 2010Instruction for Continued Airworthiness...	none	22/09/2010	Active	10031917
10031933	ASI INNOVATION			T206H	ASI-fam-0009-01 Installation of FLIR MX10 mechanical provision on T206Haircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/or emissions level of the original productsare unchangedand remain applicable to this certificate/approval.		Limitation to Cessna T206H serial number 445 and 446	23/09/2010	Active	10031933
10031938	MECAER AVIATION GROUP S.p.A.			AW139 / AB139	IFEEL Entertainment System Installation P/N 6AB1AD016-001	The Certification Basis for the original product remains applicable tothis certificate/ approval.	- 6AB1RAD-176 Rev. C "IFEEL System Description-6AB1WNM-2-20A Rev. A "IFEEL Owner's Manualor later revisions of the above listed documents approved by EASA	none	23/09/2010	Active	10031938

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031942	AIR METHODS CORPORATION		FAA STC SR00702DE-D	BELL 429	Installation of Supplemental Strobe Lights	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	080-0471 revision IR dated 11 March 2010 - Flight Manual Supplement;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF(or subsequent revisions ofthis decision) 291-9016 issue IR dated 1 February 2010 - Master Drawing List;050-0540 revision...	None	23/09/2010	Active	10031942
10031944	ACS-NAI Ltd.		TCCA STC #C-LSA10-034/D ISS 1	BD-700-1A10	Installation of Two 16G Side Facing Divans	EASA TCDS No EASA.IM.A. 009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this cer...	Transport Canada SoC ref. C-10-0708 dated 22 September 2010.Transport Canada STC No. C-LSA10-034/D Issue 1 dated 16 August 2010.ACS-NAI Ltd. Modification Data Summary Number G471000 Revision NC orlater approved revision. Refer to drawings listed in "COMPATABILITYDATA" section of Modification Data Su...	Restricted to ASN 9347	23/09/2010	Active	10031944
10031945	BLACKHAWK MODIFICATIONS Inc.		FAA STC SA10816SC	425	Installation of Ultra Electronics engine torque indicators in Cessna 425in accordance with FAA STC SA10816SC	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.except for 14 CFR Part 23 paragraphs 23.1, 23.29, 23.301, 23.303,23.305, 23.307, 23.363, 23.601, 23.603, 23.605, 23.627, 23.771, 23.1183,...	Installation Drawing No. 200707-05, Revision IR, dated July24, 2007Airplane Flight Manual Supplement 200707, Revision IR, dated February28, 2008Instruction for Continued Airworthiness, Doc. No. 200707-30, Rev. IR,dated January 22, 2008or later revisions of the above listed documents approved by EAS...	none	24/09/2010	Active	10031945
10031947	GOODRICH CORPORATIONS ENSORS AND INTEGRATED SYSTEMS	REV. 1	TCCA STC SA10-3	DHC-8-401, DHC-8-402	Installation of Goodrich De-Icer boots on the Aircraft Wings, HorizontalStabilizer and Vertical StabilizerFAA STC ST02834NY, reissued September 20, 2010(identical with TCCA STC SA10-3, Issue 2)	JAR/CS-25 as per EASA.IM.A. 191, Issue 4 (incl. SC H-01 "EWIS")The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements forenvironmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchan...	Installation of the Goodrich De-Icer boots must be in accordance withTCCA approved "Goodrich Corporation Installation and MaintenanceInstructions, Pneumatic De-Icers for DHC-8 Q 400", Report ER-2010-041,Revision B, dated June 03, 2010.Maintenance of the Goodrich De-Icer boots must be in accordance w...	None	20/06/2012	Active	10031947
10031949	BOND HELICOPTERS EUROPE Ltd.	REV. 2	CAA UK RESPONSIBILITY	AS 332 L2	Honeywell TCAS II Installation in accordance with BOND/MOD/018Rev.1: new Build Standard BD/018-100-05 includedRev. 2: installation of TCAS II equipment with logic version 7.1 asalternative to the already approved logic version 7.0.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition: CRI F-01 "Protection from theeffects of HIRF",dated 21 September 2010.- The following paragraph(s) at a later amendment: CS 29 Amendment 2,dated 17 N...	For TCAS II with logic version 7.0:Flight Manual SupplementFMS/018-002 “Honeywell TCAS II installation“,Issue 1For TCAS II with logic version 7.1:Flight Manual Supplement FMS/018-017 “Honeywell TCAS II installationwith ACAS II logic version 7.1“, Issue 1or later revisions of the above listed docume...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/12/2015	Active	10031949

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031961	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BD-700-1A10	Customized Aircraft Completion - ASN 9365	EASA.IM.A.009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRIF-01 "Installation of Wireless System"CRI D-01 "Installation of Interior Door"CRI D-02 "Isolated Compartments"CRI D-03 "...	STC Twenty One Ltd Master Document List No. S21.MDL-0795.STC Twenty One Ltd Airplane Flight Manual Supplement No. S21.FMS-0068.Instructions for Continued Airworthiness Midcoast Aviation Inc.Supplemental Maintenance Manual No. 35-027E225.orlater revisions of the above listed documents approved by EA...	none	27/09/2010	Active	10031961
10031966	ARMSTRONG AEROSPACE Inc.		FAA STC ST02778CH	747-400F 747-400, 747-400 (BCF)	Activation of Honeywell Runway Awareness & Advisory System (RAAS) inaccordance with Armstrong Aerospace Master Data List DOC No.DC104-7007-00 Revision D,dated November 9,2009 or later FAA aproved revision.Validation of FAA STC ST02778CH	The Certification Basis for the original product remains applicable tothis certificate/ approval	or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	27/09/2010	Active	10031966
10031972 (EASA.A.S.03959)	SABENA TECHNICS BGC			A330-200/-300	Humidification System Installation on A330 aircraft	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- EASA CS 25 Amendment 4 for areas and parts affected by the change.- CRI H-01 Special Condition Enhanced Airworthiness Programme forAerop...	- Master Data List doc. Ref. N°0435-01-A-2103-R01, Rev.1 dated 21September 2010.- Instructions for Continued Airworthiness doc. Ref. N°0435-01-A-2211,Rev 00 dated 06 August 2010.or later revisions of the above listed documents approved by EASA	None	28/09/2010	Active	10031972
10031982	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02525CH-D	GULFSTREAM GV-SP (G 550)	Installation of an Aft Lavatory Compartment.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC524048003, Rev F, dated May 6, 2010.or later revisionsof the above listed documents approved by EASA inaccordancewith EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	29/09/2010	Active	10031982
10031983	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03743AT-D	GV-SP	Installation of an 18 Passenger Aircraft Cabin Compartment.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC520008667, Rev F, dated November 24, 2009.Operation in accordance with Gulfstream Aerospace Corporation AircraftFlight Manual Supplement ref GC52000M112, OriginalRelease, datedNovember 24, 2009.OrOperation in accordance wi...	None	23/02/2012	Active	10031983
10031985	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02190LA-D	GULFSTREAM GV-SP (G 550)	Installation of the Forward Vestibule Compartment.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC520008140, Revision F, dated July 2, 2009.Operation in accordance with Gulfstream Aerospace Corporation AircraftFlight Manual Supplement ref GC52484M001, OriginalRelease, dated July2, 2009.or later revisions of the above l...	none	29/09/2010	Active	10031985

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10031995	ARMSTRONG AEROSPACE Inc.		FAA STC ST02376CH	ATR72-201,ATR72-202,ATR72-212	EASA Validation of FAA STC ST02376CH (as amended by FAA on 24th June2010) regarding:Installation of a Rockwell Collins HF-9000 HF Radio System in accordancewith Armstrong Aerospace Master Data List, Doc. Number DC104-4033-00,Revision E, dated 27th May 2010, or later approved revisions	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalAn EASA Special Condition CRI H-001 Issue 01 "Enhanced AirworthinessProgrammefor Aeroplane Systems - ICAs on EWIS" is applicable to theEA...	Armstrong Aerospace Master Data List, Doc. Number DC104-4033-00,Revision E, dated 27th May 2010Aeroplane Flight Manual Supplement, Armstrong Aerospace Doc. No.DC303-4033-00, Revision B<(>,<)>or later revisions of the above listed documentsapproved by EASA inaccordance with EASA ED Decision 2004/04/...	None	30/09/2010	Active	10031995
10032001	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	MD-88, MD-90-30, 717-200 DC-9-83(MD-83),DC-9-87 (MD-87), DC-9-81(MD-81),DC-9-82 (MD-82), DC-9-41, DC-9-51, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32 (VC-9C), DC-9-32F, DC-9-32F (C-9A, C-9B), DC-9-21, DC-9-31, DC-9-32, DC-9-14, DC-9-15, DC-9-15F, DC-9-11, DC-9-12, DC-9-13,	Introduction of Cabin Vu-123 Cabin Surveillance System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-001/SC H-001	Master Document List S. 21.MDL-0787or later revisions of theabove listed documents approved by EASA	None	30/09/2010	Active	10032001
10032016	MAGNETIC MRO AS	REV. 3		A319-133	Revision of EASA STC 10032016.Removal of the G1, G2 & G5 galleys' loads established on initial issueof EASA STC 10032016 date of issue 01.10.2010 granted to MacCarthyInteriors Ltd.Revision: Transfer of Certificate to Magnetic MRO AS	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCertification basis as per TCDS plus:- CRI H-01/Special Condition H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWI...	- Drawing & Document Control Report doc. N° 09DC111 Issue Cdated18/10/2010 (Galley G1)- Drawing & Document Control Report doc. N° 09DC112 Issue C dated18/10/2010 (Galley G2)- Drawing & Document Control Report doc. N° 09DC113 Issue C dated18/10/2010 (Galley G5)- Declaration of Design and Performance...	Approval limited to MSN4114.Prior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	19/09/2019	Active	10032016
10032031	AVIATION SUPPORT GmbH	REV. 1		MD900	Installation of an O2 Rack	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-27 Amendment 2for the changeThe requirements for environmental protectionand the associatedcertificated noise and/ or emissions level...	RFM Supplement; FMS-ASE-91 001or later revisions of the above listed documents approved by EASAMaster drawing list; DL-ASE-91001 (22.3.10) Compliance Report; CR-ASE-91001 (6.9.10)ICA; I CA-ASE-91 001 (30.8.10)	This change is restricted to Serial number 900-00105 only.	08/12/2010	Active	10032031
10032043	AMAC AEROSPACE SWITZERLAND AG	REV. 1		A319-133	MSN4114 Interior OutfittingThe change consists in a complete cabin interior outfitting with a 28passenger VIP interior including two medical stretcher units.Major Change to EASA STC 10032043: Certification for commercialoperation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Certification basis as described in CRI A-4301-003 ("EASA SupplementalType Certification Basis")The requirements for environmental protection and the associatedcertified n...	- Master Data List MDL-AI01-2500 Rev E dated 19.10.2016- Flight Manual Supplement FMS-AI01-2500 Rev B dated 12.10.2016-Instructions for Continued Airworthiness ICA-AI01-2500 Rev B dated04.10.2010or later revisions of the above listed documents approved by EASA.	- Limited to MSN 4114- Per Flight Manual Supplement FMS-AI01-2500 Rev B dated 12.10.2016- For commercial operation, AMAC Minor modification AI08-2520 needs tobe incorporated.Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any...	26/10/2016	Active	10032043

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032054	LUFTHANSA TECHNIK AG	REV. 1		MD-11	Activation of ADS-B Out capability via 1090MHz Extended Squitter inaccordance with Lufthansa Supplement Type DefinitionDocumentSTDD34-10/01M Iss. 2, dated Sep. 20, 2010 or later approved revision	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Doc. No. A-00-10/153 Rev IR Airplane Flight Manual Supplement Doc. No.A-00-10/153-ICA IR Instructions for Continued Airworthinessor later revisions of the above listed documents approved by EASA	none	12/10/2010	Active	10032054
10032055	ALTITUDE AEROSPACE INTERIORS Ltd.	REV. 2		747-400	Installation of Honeywell / Racal MSC6000 SatCom System perAltitudeAerospace Interiors Master Data List MDL 22001052 Rev. BRev. 2 to include aircraft serial number	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval .	Master Data List MDL 22001149_ASubstantiation Report SR 21001439_AICA reference: TR 35001213 Rev B	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	10/07/2015	Active	10032055
10032056	GFD GmbH	REV. 1		35A, 36A 35A / 36A	COMJAM System InstallationRev. 1: Transfer to GFD GmbH	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Refer to Certification Program 856-080, rev. IR.The requirements for environmental protection and the associatedcertificated noise and/ o...	Master Data List 856-049, Rev. A<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This COMJAM system installation approval is only applicableto thefollowing aircraft equipped with certain special mission provisions(including electrical power supply, harnesses and wiring, workstationand antennas): s/n's 35A-139, 35A-179, 35A-268, 35A-331, 35A-387,36A-062 and 36A-063.Prior to inst...	23/08/2022	Active	10032056
10032060	RUAG AEROSPACE SERVICES GmbH			CL600-2B16, CL-600-2A12 CL-600-1A11	Installation of Satcom Iridium System Simphone DUO	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	RUAG Master Document List No. 078R-MDL Revision N/C dated 04 October2010.RUAG AFMS No. 078R-AFMS Revision N/C dated 17 August 2010.RUAG SoC ref. 078R-CN Revision N/C dated 30 September 2010.or later revisions of the above listed documents approved by EASA	none	06/10/2010	Active	10032060
10032061	RUAG AEROSPACE SERVICES GmbH			CL600-2B16, CL-600-2A12 CL-600-1A11	Electronic Flight Bag NavAero tBagC2 (EFB) - Class II	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	RUAG Master Document List No. 078S-MDL Revision N/C dated 16 September2010.RUAG AFMS No. 078S-AFMS Revision N/C dated 01 October 2010.RUAG SoC ref. 078S-CN Revision N/C dated 04 October 2010.or later revisions of the above listed documentsapproved by EASA	none	06/10/2010	Active	10032061
10032064	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE		TCCA STC O-LSA10-43	DHC-6-300	Radar Antenna Installation - Structural Provisions i.a.w. TCCA STCO-LSA10-043/D	The Certification Basis for the original product remains applicable tothis certificate/ approval.	-See TCCA STC O-LSA10-043/D, issue 1-DECA Aviation Engineering Ltd. Modification Summary MS09082 Rev. 1-DECA Aviation Engineering Ltd. Flight Manual Supplement SDC-AFMS-0703Rev. NCPlacard (see Drwg. No. 9003717) in view of pilot: "Aircraftnot to beoperated in the proximity of populated or built upw...	a) For serial number 235 only.b) Flight in kwon icing conditions are not approved.	06/10/2010	Active	10032064

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032066	A.I.M.S. INTERNATIONAL Corp.		FAA ST02675AT	BD-700-1A10	Sound Reduction Kit	EASA IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	FAA SoC dated 30 September 2010.FAA STC No. ST02675AT dated22 April 2004.AIMS International Corp engineering top-leveldrawing 53G2521522 Rev I/Rdated 15 March 2003 and installation instruction document No.AIMS-INST-1 Rev I/R dated 16 April 2003 or later approved revisions.AIMS International Corp M...	None	06/10/2010	Active	10032066
10032069	ALTITUDE AEROSPACE INTERIORS Ltd.			B747-400	Refurbishment of the B747-400 Upper and Main deck interior installationand seating configuration in accordance with Altitude AerospaceInteriors Master Data List MDL 22001038 Rev. A or later EAWSA approvedrevision.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.-CRI D-01 Width of Aisle front seats Zone A-CRI D-02 Inflatable Restraint fro Head Injury Protection, CAA-UKSpecial Condition CAA-SC-A-03...	Instructions for Continued Airworthiness Altitude report TR35001213Rev. B shall be incorporated in the airplane maintenance documentationor later revisions of the above listed documents approved by EASA	This STC is applicable to A/C Serial Numbers 24855, 24896, 24957, 25605,26910, 27602 and 29375.Several parts installed with this STC deviate from Part 21A.804regarding EPA marking. The responsible NAA grant a 14.4 exemptions toaccept the aircraft on its register. As this will be a permanentexemption...	06/10/2010	Active	10032069
10032074	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04204AT-D	GV-SP	Installation of the Aircraft Cabin Compartment for Gulfstream GV-SPSerial Number 5284.	The Certification Basis for the original product remains applicable tothis certificate/ approval.JAR 25 Amd 15The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Installation in accordance with Gulfstream Aerospace Corporation IndexList No. GC520008702 Rev F, dated September 27, 2010.Operation in accordance with Gulfstream Aerospace Corporation AircraftFlight Manual Supplement No. GC52000M145 Rev -, dated September 27,2010.Instructions for Continued Airworth...	Aircraft Serial Number 5284 Only.	23/02/2012	Active	10032074
10032075	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC NO. ST03793AT-D	GULFSTREAM GV-SP	Installation of an Airplane Interior for aircraft S/N 5277	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Install in accordance with Master Index List GC514915277, Revision C,dated August 27, 2010.To be operated in accordancewith FAA approved Airplane Flight ManualSupplement, GC51468M014, Rev "-", dated August 26, 2010.or later revisions of the above listed documents approved by EASA inaccordance witht...	This approval is limited to only the installation made in Gulfstream,GV-SP, A/C 5277The following STC's are a required part of this STC:ST02696AT-D, ST02697AT-D, ST03533AT-D, ST02796AT-D, ST02715AT-D, andST03290AT-DIt is the installers responsibility to ensure these STC's are EASAapproved.	06/10/2010	Active	10032075
10032076	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST02292CH-D	GV-SP	Installation of the 115V AC/60Hz Outlets Multiple STC for GulfstreamGV-SP model aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.JAR 25 Amd 15The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Installation in accordance with Gulfstream Aerospace Corporation IndexList No. GC514948000 Rev D, dated May 30,2008.Operation in accordance with Gulfstream Aerospace Corporation AircraftFlight Manual Supplement No. GC41494M000 Rev -, dated November 17, 2006 (-401). or GC41494M002 Rev A, dated May...	none	23/02/2012	Active	10032076

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032077	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03794AT-D	GV-SP	Installation of the Aircraft Cabin Compartment for Gulfstream GV-SPmodel aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approvalJAR 25 Amd 15The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Installation in accordance with Gulfstream Aerospace Corporation IndexList No. GC520008695 Rev E, dated September 3, 2010.Operation in accordance with Gulfstream Aerospace Corporation AircraftFlight Manual Supplement No. GC52000M137 Rev -,dated September 3, 2010.Instructions for Continued Airworthi...	None	23/02/2012	Active	10032077
10032080	AEROLITE AG			AW139	EMS Equipment P/N 139200-501	JAR 29 Amdt. 3The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement FMS-10-004 Revision N/Cor later revisions of the above listed documents approved byEASAOperating Manual OPM-10-005 Rev. N/ CEquipment List EQL-10-004Master Document List MDL-10-004	Limited to: S/N 41226 onwards	06/10/2010	Active	10032080
10032086	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST03759AT-D	GV-SP	Installation of the Audio Video Distribution System (AVDS) Multiple STCfor Gulfstream GV-SP model aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approvalJAR 25 Amd 15The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Installation in accordance with Gulfstream Aerospace Corporation IndexList No. GC525128001 Rev B, dated March 19, 2010.Operation in accordance with Gulfstream Aerospace Corporation AircraftFlight Manual Supplement No. GC51512M001 Rev -, dated March 19, 2010.Instructions for Continued Airworthiness i...	None	23/02/2012	Active	10032086
10032094	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC NO. ST00411LA	B747-400	Installation of Honeywell Traffic Alert and Collision Avoidance System(TCASII)	The Certification Basis for the original product remains applicable tothis certificate/ approval.	FAA approved Air New Zealand Master Drawing List TX30031 Revision A,dated June 26, 1996 or later approved revision.For appropriate FAA approved Airplane Flight Manual Supplement refer toassociated section of the Air New Zealand Master Drawing List Document.	none	07/10/2010	Active	10032094
10032098	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOMBARDIER CL600-2B19	Removal of Divan Seating Restriction	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	STC 21.MDL-0793 Issue 1 dated 30 September 2010.or later revisions of the above listed documents approved by EASA	This design change will allow the removal of an existing limitation onoccupation of the forwardmost seating position onthe installed divan(EASA STC No. EASA.A.S.03452 and EASA.A.S.03022 refers).If the arrester block installation assembly becomes unserviceable andcannot be fitted, the forwardmost se...	07/10/2010	Active	10032098
10032104	JAMCO AMERICA, INC.		FAA STC ST01094SE	747-400	Installation of an interior reconfiguration of the main andupper decksin 747-400 airplanes in accordance with Jamco America, Inc. MasterDrawing List no. IA-072MDL, Revision AD dated 19 September 2008 or laterapproved revisionValidation ofFAA STC ST01094SE	The Certification Basis for the original product remains applicable tothis certificate/ approval	or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	07/10/2010	Active	10032104

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032105	HONEYWELL INTERNATIONAL INC.	REV. 2	FAA STC SR03333AT	S-76A, S-76B, S-76C	Installation of the Sky Connect Satellite Phone and Tracking System.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	EASA RFM Supplement RFM-A2005-091, Rev IR, dated 9/22/2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.Icarus In...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/08/2015	Active	10032105
10032131	DASSAULT FALCON SERVICE			MF50 AND FALCON 50EX	Stretchers installation.Provide the ability to install in the aircraft one or two stretchers forair ambulance accordingto two configurations:- One stretcher is installed in the LH side instead of the two LH fwdseats.- Two stretchers are installed in the LH side instead of the four LHseat.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	DFS Change Approval Sheet DFS5691-CAS Issue A dated 11.10.2010.DFS Modification Sheet DFS5691, Issue A dated 11.10.2010.or later revisions of the above listed documents approved by EASA	This modification is applicable on Mystère Falcon 50 and Falcon 50EXaircraft equipped with four seats installed in the LH side and two seatsand a sofa installed in the RH side as defined in the Modification SheetDFS5691.This installation does not cover any medical equipment installation.This modific...	12/10/2010	Active	10032131
10032163	DASSAULT FALCON SERVICE			MF900 & F900EX	230VAC electrical distribution for galley.An inverter and aGFI are installed to provide 230AC power on one outletin the galley.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- §25X1360 & §25x1499 at JAR 25 change 13- §25.869 (a) (1)&(4) at JAR 25 Change 14.The requirements for environmental protection and the a...	DFS Change Approval Sheet DFS9621-CAS Issue A dated 12.10.2010.DFS Modification Sheet DFS9621, Issue A dated 07.10.2010.or later revisions of the above listed documents approved by EASA	Modification applicable to MF900, F900EX aircraft with :- 1400W available on A4 bus, and- Master switch in cockpit to switch off components electricallysupplied in Galley area, and- Master switch in cockpit to switch off all 115/230VAC distributioncircuit during TO and Landing, and/or- It is possibl...	13/10/2010	Active	10032163
10032176	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		2. PA-32-301XTC, PA-32-301FT 1. PA-32RT-300T, PA-32R-301 1. PA-32R-301T, PA-32-301 1. PA-32R-300, PA-32RT-300 1. PA-32-260, PA-32-300	Dual/Single Installation of Garmin GNS430(A)W / GNS530(A)W	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CS-23, Amdt. 1The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	Instruction for Installation: ASR-2010-022-IFI-10-00, Rev. 0Flight Manual Supplement: ASR-2010-022-FMS-05-00, Rev. 0Instructions for Continued airworthiness: ASR-2010-022-ICA-11-00, Rev. 0or later revisions of the above listed documents approved by EASA	none	18/10/2010	Active	10032176
10032203	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special Transports / Transports SpeciauxThis STC, ref. ST25MOD020 ed.01 (Applicant reference), has beendeveloped, reviewed, tested and found compliant with the CertificationBasis to deal with non-Airbus sub-assemblies transport. On case bycasebasis, this STC had to be amended to cover any new non-A...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Change Approval Sheet, ref : ST25MOD020<(>,<)> Issue 50or later revisions of the above listed documents approved by EASA	None	15/10/2010	Active	10032203
10032204	DASSAULT FALCON SERVICE			F900EX	F900EX S/N 086 Cabin Layout Modification.New interior cabinconfiguration features a 12-passenger and 3-crewaccommodation.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- §25.853 (a) (b)+ App F Part I and II at JAR 25 Change 14.The requirements for environmental protection and the associatedcertificated n...	DFS Change Approval Sheet DFS9613-CAS Issue A dated 15.10.2010DFS Modification Sheet DFS9613, Issue A dated 15.10.2010DFS Master Data List DFS-DE-17-F9-9613, Issue A dated 11.10.2010or later revisions of the above listed documents approvedby EASA	Modification applicable to F900EX S/N 086 with a pre mod configurationas described in DFS Modification Sheet DFS9613, Issue A.	15/10/2010	Active	10032204

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032214	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A320-232	Cabin Interior Reconfiguration and In Flight Entertainment (IFE)Modifications on Etihad Airways A320-232 Aircraft	Certification Basis as per EASA TCDS A.064The CertificationBasis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:- CS 25 Appendix H and AMC Appendix H25.5The requirements for environmental protection and thec...	- NAT Certification Summary, ref. doc. N0362-D90, Revision -, dated 17thOctober 2010- NAT Master Drawing List, ref. doc. N0362-D10, Revision B, dated 15thOctober 2010or later revisions of the above listed documents approved by EASA	Not applicable	18/10/2010	Active	10032214
10032216	SABENA TECHNICS BOD			F28 MK0100	Modification wireless telephones installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification plan DO-N-2009-174-PDE Issue 2 dated 15 September 2010AFM Supplement FK100-25-LAIKA-01-FM Issue K dated 29 March 2010or later revisions of the above listed documentsapproved by EASA	PER AFM Supplement FK100-25-LAIKA-01-FM Issue K dated 29 March 2010Applicable only to MSN 11368, 11403 and 11406	18/10/2010	Active	10032216
10032232	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CESSNA 206H, T206H	Introduction of Stand-By Battery Power Supply in accordancewithS21.MDL-0770, issue 2, dated 14/10/2010	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Flight Manual Supplement S21.FMS-0070, issue 1Installation Manual OAS-30-206-9, issue C, dated 06/10/2002Instruction for Continued Airworthiness PAVCO document OAS-30-23-1529or later revisions of the above listed documents approved by EASA	None	19/10/2010	Active	10032232
10032241	CHIPPEWA AEROSPACE, Inc.		FAA STC SA03860AT	LIBERTY XL-2	Honeywell KN-62A DME	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The certificatednoise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval....	Honeywell KN-62A DME Instructions for Continued AirworthinessXL2-3453-01-002AFMS XL2-3453-01-1012 Rev IR dated July 06 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	05/11/2010	Active	10032241
10032246	BEECHCRAFT CORPORATION		FAA STC ST10598SC-D	4000	Installation of Flight Camera System	The Certification Basis for the original product remains applicable tothis certificateThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	STC Required Documents List (RDL) No. 240-2002-1, revision 11, October13, 2009.Completions Manual Chapter 44-20-30-H4000, August 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	19/10/2010	Active	10032246
10032248	BOMBARDIER INC.	REV. 1	TCCA STC NO. SA05-60	BD-700-1A11	Modification to incorporate changes to the installation of CustomAircraft Interior - ASN 9370. Revision to EASA STC 10032248	EASA TCDS No. IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certif...	-TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.-TCAA SoC ref. C-10-0926 dated 1 November 2010.-Aero Consulting Services Ltd. Configuration Definition List E025000Revision DY dated 26 October 2010.-Bombardier Aerospace Airplane Flight Manual Supplement G-FM25004501Revision N/C or later approved rev...	Restricted to ASN 9370	09/11/2010	Active	10032248

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032253	DART AEROSPACE Ltd.		TCCA STC SH09-37 ISSUE 1	3. 204B, 205A-1 2. 212, 412, 412 EP 1. 214B, 214B-1	D412-791 Safety Enhancement kits	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FMS-D205-791 rev. A, FMS-D412-791 rev. A, FMS-D212-791 rev.A, ICAD-412-791 rev. 0, MDL-D412-791 rev. A, IIN-D412-791 rev. Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (orsubsequent revisions ofthis decision)	None	05/11/2010	Active	10032253
10032264	AIRCRAFT TECHNICAL DEVELOPMENT Inc.	REV. 1	FAA STC ST02317LA	A330-223, -243, -343 A330-201, -202, -203	Installation of Cabin Interior Noise Reduction KitRev. 1 adds the A330-343 model	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:- CRI A-4301-001 "EASA Supplemental Type Certification Basis for AeroconA330-200 Cabin Interior Noise Reductio...	- Aerocon Engineering Company's Master Drawing (MDL) List No.AC25-NRA330-1000, Revision C, dated 3 June 2010;- Instructions for Continued Airworthiness (ICA), Aerocon EngineeringCompany Maintenance Manual Supplement Document No. MMS-A330-1502<(>,<) >Revision NC, dated 22 July 2009;or later revisionsb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	18/07/2025	Active	10032264
10032268	AIRBUS HELICOPTERS UK LIMITED	REV. 3	CAA UK RESPONSIBILITY	EC135 T2+, EC135 P2+	NVIS Certification EC135 P2+ / EC135 T2+Note 1: Rev 1 of EASA STC No. 10032268 is implementing administrativechangesNote 2: Rev 2 of EASA STC No.10032268 is raised in order to modify theSTC as follows: 1. Extend applicability from EC135 T2+ to EC135 P2+ model. 2. Introduce a third Night Vi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	- RFMS EC135 Supplement 56, Issue 2 (SINGLE PILOT OPERATIONS TO 500ftABOVE GROUND LEVEL NVIS COCKPIT USING NIGHT VISIONGOGGLES) forconfigurations controlled by ICAW/1351242 documents.- RFMS AHUK/ 135-FMS-103 Rev 0 (EC 135 NVIS OPERATIONS TO GROUND LEVEL toGround Level) for configurations controlled5...	a) Aircraft Build StandardPrior to installation of either AHUK options, the aircraft must have thefollowing AHD factoryinstalled options:- L3347-001-00; NVG Friendly External Lighting Kit- L3312-003-00; Cockpit Layout NVG Standard- L3111-002-211; NVG Friendly Cabin and Cargo CompartmentAHUK Options...	29/11/2016	Active	10032268
10032277	FIBERGLAS-TECHNIK RUDOLF LINDNERGMBH & CO. KG			GROB G 103 "TWIN II"	STC "Reparatur Twin II"	The Certification Basis for the original product remains applicable tothis certificate/ approval.	- STC "Reparatur Twin II"- Flight manual prepared for the S/N of the fuselage and fitting with"Twin II"- Flughandbuch zusammengestellt für die Werknummer des Rumpfes undpassend zum "Twin II"- Maintenance manual prepared fort he S/N of the wing and fitting with"Twin II"- Wartungshandbuch zusammengest...	Even if parts from a "Twin II "Acro" are used, the combinedsailplanewill be always a "Twin II" (without Acro). / Auch wenn Teile eines TwinII "Acro" verwendet werden, das neu entstandene Segelflugzeug ist immerein "Twin II" (ohne Acro).	22/10/2010	Active	10032277
10032278	FLYING COLOURS CORP.	REV. 1	TCCA STC NO. SA10-66	CL-600-2B19	Installation, Equipment Bay Catwalk	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA SoC ref. C-10-0781 dated 07 October 2010.TCCA STC No. SA10-66 Issue 1 dated 31 August 2010.ACS-NAI Ltd Modification Data Summary, G744000 Revision A.Flying Colours Corp. Equipment Bay Catwalk Instructions for ContinuedAirworthiness, G744071 Revision NC.or later revisions of the above listed doc...	none	28/10/2010	Active	10032278

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032279	FLYING COLOURS CORP.	REV. 1	TCCA STC NO. SA10-67	CL-600-2B19	Installation, Equipment Bay Ladder	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA SoC ref. C-10-0780 dated 07 October 2010.TCCA STC No. SA10-67 Issue 1 dated 31 August 2010.ACS-NAI Ltd. Modifications Data Summary G745000 Revision A.Flying Colours Corp. Equipment Bay Ladder Stowage ProvisionsInstructions for Continued Airworthiness, G745071 Revision NC.or later revisions of t...	Prior embodiment of EASA STC No. 10032278 'Installation, Equipment BayCatwalk' is required.	28/10/2010	Active	10032279
10032280	FLYING COLOURS CORP.	REV. 1	TCCA STC NO. SA10-65	CL-600-2B19	Installation, Equipment Bay Access Door Steps	EASA IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA SoC ref. C-10-0779 dated 07 October 2010.TCCA STC No. SA10-65 Issue 1 dated 01 September 2010.ACS-NAI Ltd. Modification Data Summary, G743000 Revision A.Flying Colours Corp. Equipment Bay Access Door Steps Instructions forContinued Airworthiness, G743071 Revision NC.or later revisions of the ab...	none	28/10/2010	Active	10032280
10032285	SCANDINAVIAN AVIONICS DESIGN ApS			SF340A AND 340B	Installation of Collins TCAS-94 system with dual Collins TDR-94Dtransponders.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-25, am 4CRI H-01, Issue 2The requirements for environmental protection andthe associatedcertificated noise and/ or emissions levels of...	Engineering Order and Certification Program 2055179-EO, Issue 1;List of Certification Documents 2055179DOC, Issue 1;List of Installation Documents 2055179STC, Issue 1;AFM-supplement 2055179-AM-A, Issue 2;AFM-supplement 2055179-AM-B, Issue 2.or later revisions of the above listed documents approved b...	Transponder system NOT approved for ELS or EHS.	22/10/2010	Active	10032285
10032286	S-TEC CORPORATION		FAA STC SA8910SW-D	BEECH S35, V35, V35A AND V35B	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-577 (14 Volt System)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	FAA-Approved S-TEC Bulletin No. 677, dated 04-Dec-09, Revision 6, orlater approved revisionFAA-Approved S-TEC Master Drawing List No. 92756, dated 04-Dec-09,Revision F, or later approved revisionFAA-Approved Pilot's Operating Handbook and/or Airplane Flight ManualSupplement, P/N 891151, Revision 2,r...	This STC is also eligible on Beech models S35, V35, V35A, and V35B whenmodified by STC SA1035WE (turbocharged engine) or STC SA5223NM (turbonormalizing system) and any combinationof the following STCs: STCSA09074SC (vortex generators), STC SA4-1629 (tip tanks).	22/10/2010	Active	10032286
10032292	AIR AMBULANCE TECHNOLOGY GmbH			A330-200/ -300	Air Ambulance Equipment "quick conversion"P/N A330-25-20-10.000 515 - Intensive Care Module P/ NA330-25-20-10.300-603	CS-25 Amdt. 4 except 25.562 addressed per TGM/25/12The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and rema...	- Compliance Record, ref. doc. CR-A330-10.000-515, Revision6, dated25th October 2010- Component, Installation and Operation Manual, ref. doc. CMM-A330-AAT73, Rev. 1, dated August2010- Aircraft Flight Manual Supplement, ref. doc. AFM-AAT 54, Rev. 0or later revisions of the above listed documents ap...	This STC does not constitute an approval for installation. Compliancewith the following requirements will be demonstrated and covered by theDOA responsible for the medical stretcher installation on the aircraftA330 through a design approval:§ 25.561(d)§ 25.785(a)§ 25.785(h)§ 25.785(j) § 25.791§ 25.80...	25/10/2010	Active	10032292

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032295 (EASA.IM.A.S.03152)	B/E AEROSPACE LIMITED	REV. 2	TCCA C-LSA09-021/D ISS.3	CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA STC No. C-LSA09-021/D Issue 3 dated 17 June 2013.ACS-NAI Ltd. Modification Data Summary G116000 Revision F.Aero Consulting Services Ltd. Mandatory Maintenance Manual SupplementG116070 Revision NC.Savannah Air Center Inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior...	Restricted to ASN 8080	16/08/2013	Active	10032295
10032318	365 AEROSPACE DDS LIMITED	REV. 2		DHC-8-401, DHC-8-402	Installation of Ground Recognition LightsRev. 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 8 for changed areasThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunch...	Aerospace Design & Engineering Consultants Ltd Aircraft ManualSupplement No. AMS-DHC-8-Q 400-FLYBE, dated 01 August 2010or later revisions of the above listed document(s) approved/acceptedunder the EASA system.Aerospace Design & Engineering Consultants Ltd Modification Summary,MOD-0753, Revision B	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/08/2019	Active	10032318
10032322	SAVANNAH AIR CENTER, L.L.C.	REV. 1	FAA STC ST03881AT	BD-700-1A10	Installation, Complete Custom Interior, S/N 9345 Configuration	EASA TCDS No IM.A.009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI F-01 - Installation of Wireless SystemThe requirements for environmental protection and the associatedcertificate...	FAA SoC ref. ST12210AT-T dated 21 October 2010.FAA STC No. ST03881AT dated 26 October 2010.Savannah Air Center MDL, XRS9345-MDL-2500001, Rev. A dated 13 September2010.Instructions for Continued Airworthiness, Bombardier Global ExpressDocument Number XRS9345-ICA-0001, Revision IR dated 26 March 2010....	Restricted to ASN 9345 and1. Refer to the Limitations sections of the required AFM Supplement andto the following FCOMS:G862081 Rev NC - FCOMS - WLAN SystemG862092 Rev A - FCOMS -Mid-Cabin Door2. WLAN system is compatible only to IEEE 802.11(b)	29/03/2011	Active	10032322
10032327	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9360	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada SoC reference C-10-0424 dated 21 October 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.AeroConsulting Services Configuration Definition List D954000 RevisionFS dated 18 October 2010.Instructions for Continued Airworthiness GC93600000-IFCA.or later revisions of the abovea...	Restricted to ASN 9360 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).3.Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and...	27/10/2010	Active	10032327
10032329	SWS CERTIFICATION SERVICES Ltd.	REV. 1	CAA UK RESPONSIBILITY	BOEING B747-400 BOEING B747-300	Installation of SaftGlo Inc. Photoluminescent Floor Proximity EmergencyEscape Path Marking System (FPEEPMS) in accordance with SWSCertification Services Design Report 3046-DR-01 Rev. 2, dated 27 August2010 or later approved revision.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	3046-MMS-01 Issue 1, Maintenance Manual Supplement3046-CMS-01 Issue 1, Crew Manual Supplement3046-SB-01 Issue 1, Service Bulletinor later revisions of the above listed documents approved by EASA	none	08/11/2010	Active	10032329

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032331	JET AVIATION AG	REV. 2		747-400	Replacement of a dual Allied Signal High Frequency (HF) Radio by DualRockwell Collins Air Transport (RCAT) HFS-900D HF Radio Equipment (ARINC753) with HF Data Link activation in accordance with Jet Aviation MasterData List Doc. No. B7428343-006 Rev. D, dated 20 October 2010 or laterapproved revision...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List B7428343-006 Rev. D, dated 20 October 2010< (>,<)>or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/11/2017	Active	10032331
10032336	S-TEC CORPORATION		FAA STC SA09320AC-D	CESSNA F182P, F182Q	Installation of S-TEC System 20/30 Single and Two Axis Automatic FlightGuidance Systems, Model ST-762-20/30 (14 Volt System)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	FAA-approved S-TEC Bulletin No. 862, dated 29-May-09, Revision 6FAA-approved S-TEC Master Drawing List No. 921057, dated 10-Dec-09,Revision GFor S-TEC System 20: FAA-approved Pilot's Operating Handbook and/ orAirplane Flight Manual Supplement, P/N 891621, Revision 3, dated18-June-02 or later approved...	This STC is also eligible on Cessna models F182P and F182Q when modifiedby: 1. STC SA485SW (Wren conversion) and STC SA3825SW (260 H.P. engineconversion) or 2. STC SA950CE (HortonSTOL) and/or STC SA2285CE (Hortonflap gap seals) and STC SA3825SW (260 H.P. engine conversion) or 3. STCSA1382WE (Robert...	28/10/2010	Active	10032336
10032345	EICHELSDOERFER GmbHFLUGZEUGBAU			RF5	STC "Installation engine Rotax 912 and propeller HO-V352F-S1/S170FQ inthe powered sailplane Fournier RF 5"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- STC "Technische Mitteilung 002-09-01" dated 27. April 2010.- Einbauanweisung 002-09-01, Einbau eines Rotax 912 A3 mitPropellerHO-V352F-S1/ S170FQ in den Motorsegler RF 5.- Zeichnungsliste zum RF5-Rotax-Umbau-Flughandbuch für den Motorsegler Fournier RF 5, Rotax, HO-V352 vom14.04.2010-Wartungshan...	Limited to Fournier RF 5, S/N 5012	28/10/2010	Active	10032345
10032348	RAM AIRCRAFT, LP	REV. 1	FAA STC SA09971SC-D	2. CESSNA 414, 414A, 402C 1. CESSNA 340, 340A	Installation of Hartzell propeller PHC-C3YF-2UF/FC7693DF(B)inaccordance with FAA STC SA09971SC-D	The Certification Basis for the original product remains applicable tothis certificate/ approvalThis certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels	RAM Drawing No. 2549, Revision D, dated May 24, 2001Airplane Flight Manual Supplement AFMS 1096, Revision A, dated December2, 2002The Instruction of Continued Airworthiness are contained in HartzellPropeller's Overhaul and Maintenance Manual No. 117D (ATA 61-10-17),Revision 4, dated May 1999.or late...	1. Hartzell Modell PHC-C3YF-2UF/FC7693DF or PHC-C3YF-2UF/ FC7693DFBpropellers are limited to aircraft that are previously FAA approved toinstall 78-inch (198 cm) diameter propellers and have TCM model TSIO-520series engines with maximum rated power from 285 HP to 350 HP. Thismodification is compatibl...	02/11/2010	Active	10032348
10032352 (EASA.IM.A.S.01058)	WIPAIRE Inc.		US SA01916CH	AIR TRACTOR AT-802, AT-802A	Installation of vortex generators. Installation of Wipaire stallimprovement array in accordance with Wipaire installation drawing No.7A1-4407 Revision B, dated April 27,2010 for the AT-802A model andinstallation drawing No. 1004245, Revision B, dated April 27,2010 forthe AT-802 model	The Certification Basis for the original product remains applicable tothis certificate/ approval	FAA STC No. SA01916CH amended May 24, 2010 "Installation ofWipaireStall Improvement Array" for AT-802 and AT-802A models.W-AT802-67F-1424-VG. FAA approved AFMS for the AT-802 with PT6A-67F (1424shp) engine and Wipaire stall improvement array dated May 10, 2010.W-AT802-67F-1600-VG. FAA approved AFMSs...	FAA STC No. SA01916CH "Limitations and conditions", amendedMay 24, 2010	05/11/2010	Active	10032352

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032363	SOCIETE AIR FRANCE S.A.			A340-211, A340-212	A340 Royal Jordanian - New IFE and Cabin reconfigurationThis STC consists in a cabin reconfiguration by installing newecoconomic class seat and a new In-Flight Entertainment (IFE)system(Sicma Aero IFE SiT).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CS 25 Amendment8- Special Condition H-01 : Enhanced Airworthiness Program for AeroplaneSystems - ICA on EWISThe requirements for enviro...	Change Approval Sheet, Ref : CAS-A340-09-009 Rev 00, dated 29 October2010Air France Service Bulletin, Ref : AFSB-A340-09-009-25-001or later revisions of the above listed documentsapproved by EASA	This STC is applicable to the following aircraft MSNs :,,- MSN 14,,- MSN 22,,- MSN 38,,- MSN 43	29/10/2010	Active	10032363
10032387	TENENCIA Ltd.		CAA UK RESPONSIBILITY	MK050, MK0502	Installation of a Universal Avionics Terrain Awareness and WarningSystem (TAWS)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Electronic Wiring Interconnection System (EWIS) as defined in CS 25.1701in accordance with CS-25 Appendix H paragraph H25.5 and AMC appen...	- Certification Plan CP/ TEN/645 Issue 1- Ten supplement 1 issue 1 to the Fokker F27 Mk 0502 flight manualor later revisions of the above listed documents approved by EASA	As contained in Ten supplement 1 issue 1 to the Fokker F27 Mk 0502flight manual	02/11/2010	Active	10032387
10032391 (EASA.A.S.03671)	SABENA TECHNICS BOD	REV. 2		A330-223	A330-223 "P710" VIP Cabin CompletionThis STC installs a VIPcabin configuration.Revision 1 was issued to update the Limitation Section.Revision 2 is issued to capture a design evolution (9000 VU change) andassociated documentation update.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA TCDS A.004CRI A-4301-002 EASA Supplemental Type Certification BasisThe requirements for environmental protection and the associatedce...	Modification Approval Sheet, Ref: S-00-2046, Issue 7, dated25 April. 2012Airplane Flight Manual Supplement, Ref: AFM-S F3028 MOD00-2046, Rev D,dated 24 April 2012.Instructions forContinued Airworthiness, Ref: MPDS-P710, Issue 4 from02 Nov. 2010Damage-Tolerant Airworthiness Limitation Items, Ref: AL...	None	26/04/2012	Active	10032391
10032401 (EASA.R.S.01594)	AEROTEC & CONCEPT	REV. 2		AS355 F2, AS355 N, AS355 NP AS355 E, AS355 F, AS355 F1	Installation of Indraero Siren IS10-100 Cargo Hook.This STCrevision is issued for the purpose of transferring the STC toAerotec Concept.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ADC12 issue 2 dated 8 December 2010 - Certification ProgramADC17 Issue 1 dated 14 December 2010 - Master Data ListADC54-27 issue 1 dated 16 November 2010 - Instructions for ContinuedAirworthinessADC34A issue 1 dated 14 December 2010 - Installation Instructions	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/03/2016	Active	10032401
10032416	SAVANNAH AIR CENTER, L.L.C.		FAA STC ST03628AT	BD700-1A10	Installation, Complete Custom Interior, S/N 9260 Configuration	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certifi...	FAA SoC ref. ST10844AT-T dated 02 November 2010.FAA STC No.ST03628AT dated 20 October 2008.Savannah Air Center MDL, XRS9260-MDL-2500001, Rev. A dated 03 October2008.Instructions for Continued Airworthiness, Bombardier Global ExpressDocument Number XRS9260-ICA-0001, Revision IR dated 28 August 2008....	Restricted to ASN 9260 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	04/11/2010	Active	10032416
10032418	TELEDYNE CONTROLS, LLC	REV.4	FAA STC ST02239LA	777F 777-200, -300, -300ER, -200LR 777-200/-200LR/-300/-300 ER	Installation of Wireless Ground Link - Quick Access Recorder (WQAR)This STC consists in the installation of the WQAR onBoeing 777 series.Rev. 4: adds additional WQAR p/n 2243800-462 and 2243800-464 to thelimitation section.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Special Condition H-01: Enhanced Airworthiness Program for AeroplaneSystems - ICA on EWISThe requirements for environmental protection an...	Master Data List, Ref: MDL2243800-777, Rev. D, Appendix C<(>,<)>dated 12 June 2019Instructions for Continued Airworthiness for EWIS, Ref: EW2243800-B7-1<(>,<)> Revision B, dated 7February 2019or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with th...	This STC is applicable to the following WQAR p/n (2243800-xxx):- 2243800-61- 2243800-62- 2243800-63- 2243800-64- 2243800-71- 2243800-73- 2243800-77- 2243800-79- 2243800-81- 2243800-360- 2243800-362- 2243800-364- 2243800-462- 2243800-464Prior to installation of this modification it must be determined...	13/01/2022	Active	10032418

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032443	S-TEC CORPORATION		FAA STC SA7818SW-D	35-C33, F33C	Installation of S-TEC System 40/50 Single and Two Axis Automatic FlightGuidance Systems, Model ST-492-40/50 (28 Volt System)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance withFAA Approved S-TEC Bulletin No. 592, dated 18-June-92.FAA Approved S-TEC Master Drawing List No. 92565, dated 18-June-92.Operation in accordance withFAA Approved Airplane Flight Manual Supplement, P/N 89975, dated26-June-92 is required for Beech models 35-C33 and F33C4...	none	08/11/2010	Active	10032443
10032444	S-TEC CORPORATION		FAA STC SA7819SW-D	35-C33, F33C	Installation of S-TEC Manual Electric Trim System, Model ST-493 (28 VoltSystem)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance withFAA Approved S-TEC Bulletin No. 593, dated 18-June-92FAA Approved S-TEC Master Drawing List No. 92566, dated 18-June-92Operation in accordance withFAA Approved Airplane Flight Manual Supplement, P/N 89977, dated26-June-92 is required for Beech models 35-C33 and F33C.or...	none	08/11/2010	Active	10032444
10032445	SCANDINAVIAN AVIONICS DESIGN ApS			SA26-AT, SA226-T, SA226-AT SA226-T(B), SA227-AT, SA227-TT	Installation of Garmin GNS 530AW / GNS 430AW as dual installationtogether with a Honeywell KMR 675 Marker Beacon Receiver	Design:Non-significant changeThe Certification Basis of theoriginal product and the followingadditional /,,alternativeair worthiness requirements are applicable tothis changeFor the change CS-23 has been elected to comply with where possible.Environmental Protection:The certificated noise and/ or e...	EASA approved Engineering Order, Doc. No. 2061255-EO, issue1, dated26-Oct-2010, or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2061255-AMA,Issue1, dated 25-Oct-2010<(>,<)> or later approved issue, for GNS 430AWand GNS 530AWEASA approved Aircraft Flight Manual Supp...	This change is limited to the configuration of aircraft / equipment typeas listed under Chapter 4. in EASA approved Engineering Order, Doc. No. 2061255-EO, issue 1, dated 26-Oct-2010, or later approved issue.	08/11/2010	Active	10032445
10032446	AVIATION FABRICATORS, Inc.		FAA STC SA2774CE	2. B300, B300C 2. B200C, B200CGT, B200GT 1. B200CT, B200T, 300, 300LW 1. A200, A200C, A200CT, B200 1. 200, 200C, 200CT, 200T	Installation of Passenger Seats with Hinged Backrest.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Aviation Fabricators Drawing List NumberAF-151 FAA Approved 12 November 1991 or later revisions of the abovelisted documents approved by EASA in accordance with EASA ED Decision2004/04/CF (or subsequent revisions of this decision)	none	08/11/2010	Active	10032446
10032468	APICAL INDUSTRIES, Inc.	REV. 1	FAA STC SR02290LA	MBB-BK 117 C-2	Cable Cutters KitInstallation of Cable Cutters Kit with deflectors on skids and wiper inaccordance with Master DocumentList MD145-2, based on FAA STCSR02290LA.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Master Document List MD145-2, Rev. A, dated August 16, 2010-Instructions for Continued Airworthiness ICA145-21, Rev.N/C, datedSeptember 23, 2010or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision...	None	19/11/2010	Active	10032468
10032469	BUSINESS AND COMMUTER AIRCRAFT			C90	BCA118-00 - ADF system upgrade on beech S/N LJ - 894	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.		Limitation to beech C90 SN LJ-894	09/11/2010	Active	10032469

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032471	AIRLIFT A/S			AS 350 B, AS 350 BA, AS 350 B1 AS 350 B2, AS 350 B3	Installation of Geophysical Equipments in accordance with MasterDocument List DO-350-25-107, revision 0, dated 09.11.2010	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Flight Manual Supplement FMS-350-25-107, Revision 2, dated 10.08.2010Instructions for Continued Airworthiness ICA-350-25-107-01, Revision 2,dated 20.09.2010	A cargo mirror allowing in-flight observation of the spectrometer and EM/ magnetometer sensors must be installed	11/11/2010	Active	10032471
10032484	STANDARD AERO	REV. 1	FAA STC SA02367NY	F90 KING AIR	Installation of Pratt and Whitney Canada PT6A-135A Engines.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-Modified with dual fuel feed lines, in accordance with Standard AeroInc, Installation Instructions, Report, 55055-8, Rev 0 dated 26 February2007.-PT6A-135A engines must be modified in accordance with Supplemental TypeCertificate SE02357NYprior to installation.Note, it is the installers responsibil...	None	23/11/2010	Active	10032484
10032496 (EASA.R.S.01593)	AEROTEC & CONCEPT	REV. 1		AS 350 B/D/B1/B2/BA/BB/ B3	Installation of Indraero Siren IS10-100 Cargo HookRevision 1: Transfer of EASA STC 10032496 from AERODAC to AEROTECCONCEPT	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ADC12 issue 2 dated 8 October 2010 - Certification ProgramADC17 Issue 1 dated 8 October 2010 - Master Data ListADC54-27issue 1 dated 8 October 2010 - Instructions for ContinuedAirworthinessADC34A issue 1 dated 16 September 2010 - Installation Instructions	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/03/2016	Active	10032496
10032519	ACS-NAI Ltd.		TCCA STC NO. SA10-25	DHC-8-401, DHC-8-402	Installation of LED Lavatory Light System	JAR/CS-25 as per EASA.IM.A.191The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.plus:Special Condition H-01 "Enhanced Airworthiness Programme for AeroplaneSystems - ICA on EWIS" as detail...	Installation must be in accordance with ACS-NAI Ltd. TCCA approvedModification Data Summary Number E 998000, Rev. N/ CMaintenance must be in accordance with Instructions for ContinuedAirworthiness E 998071, Rev. A, E 998073 Rev. A andE 998074, Rev.Aor later revisions of the above listed docume...	none	12/11/2010	Active	10032519
10032527	VIKING AIR LIMITED		TCCA STC SA10-69	DHC-6 SERIES 400	Installation of RW Martin Air Conditioning System in accordance withTCCA STC SA10-69.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Title 14 CFR Part 23Amendment 23-0 23.303, 23.307, 23.601, 23.609, 23.1367Amendment 23-7 23.619, 23.625Amendment 23-14 23.771Am...	Flight Manual Supplement AC-64-1A, Initial issue, TCCA approvedSeptember 9, 2010Instruction of Continued Airworthiness AC-64-11, Initial issue, datedAugust 4, 2010R.W. Martin Inc.Drawing List, Report ER218-2502V, Revision 3, datedSeptember 7, 2010	None	12/11/2010	Active	10032527

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032531	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD	REV.1	TCCA STC NO. C-LSA10-207/D	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9374	EASA TCDS No. IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.Non-significantThe requirements for environmental protectionand the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable...	TCCA SoC ref. C-10-1069 dated 12 January 2011.TCCA STC No. C-LSA10-207/D Issue 1 dated 05 November 2010.ACS-NAI Ltd. Modification Data Summary G902000 Revision NA.Flight Manual Supplement for Interior Completion, FMS-IA700-9374Revision NC.Flight Manual Supplement for CMC Electronic Flight Bag, FM10-...	Restricted to ASN 93741.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS. 2.WLAN system is compatible only to IEEE 802.11(b).	17/01/2011	Active	10032531
10032532	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9377	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.Non-significantThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of theoriginal product areunchanged and remain applicable to this...	Transport Canada SoC referenceC-10-0644 dated 10 November 2010.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.AeroConsulting Services Configuration Definition List D954000 RevisionFT dated 04 November 2010.Instructions for Continued Airworthiness GC93770000-IFCA.or later revisions of the above...	Restricted to ASN 9377 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).	12/11/2010	Active	10032532
10032536 (EASA.A.S.03438)	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BOEING 747-300 BOEING 747-200	Installation of a Dual Honeywell HT-9100 FMS per ModificationDescription TEN 539 Boeing 747-200 Dual Honeywell HT9100 GNSS NavigationManagement System Installation, Issue 4 dated 10 November 2010	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR Part 25 Amendment 39JAA Guidance Material TGL 10, November 1, 2000 Airworthiness andoperational approval for precision RNAV operations...	AFM supplement TEN SUPPLEMENT 1 ISSUE 3 for the Boeing 747 series FlightManualsReport TEN 539 /7 Issue 2, Operations Manual Supplement Boeing 747HT9100 FMS Installationor later revisions of the above listed documents approved by EASA	This STC is applicable to aircraft that have previously been modified inaccordance with STC ST01841CH / IM.A.S. 01660 GPS Antenna Provisionsinstallation and have dual Honeywell Roll Computers P/N 2590623-914 or-915	12/11/2010	Active	10032536
10032537	C&D ASSOCIATES, Inc.		FAA STC SA02816CH	G58	Installation of C<(>&<)>D Associates Combustion Heater PartNumberCD50000K33.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with C<(>&<)>D Associates InstallationInstructions ref IN50000K33, Revision A, dated February 9, 2010.Operation in accordance with C<(>&<)>D Associates Approved AircraftFlight Manual Supplement Revision A, dated June 16, 2009.Instructions for Continued Airworthiness in acc...	None	12/11/2010	Active	10032537
10032538	AIRBUS HELICOPTERS TECHNIK GMBH	REV. 2		MBB-BK 117 C-2	Main Gear Box Eurocopter BK117 C2Conversion of the Main Gear Box from MBB-BK117 C-1 built standard PartNumber (P/N) 1171200501 to MBB-BK117 C-2 built standard P/ NB632K1001-051 within the scope of a major overhaul, as documented in theZF Luftfahrttechnik (ZFL) major change STC03, in accordance with t...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airworthiness Limitations:- ZFL doc. no. STC03-1682-1109, "Supplement for ECD Master ServicingManual MBB-BK117 C-2, Chapter 04-00-00, 2-1", Issue 2or later revisions of the above listed documents approved by EASA- Instructions for Continued Airworthiness, ZFL doc. no. STC03-1794-1106"Supplement for-...	- This conversion can only be performed by the STC holder.- After conversion to Main Gear Box P/N B632K1001-051 this isonly to beinstalled on MBB-BK117 C-2 helicopters.	13/06/2012	Active	10032538

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032541 (EASA.A.S.03947)	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	BOEING 767-341	Review of modifications installed prior to import (B767-341Installationof SELL Galley, Crew Rest, 221 LOPA & ELT)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS".The requirements for environmental protection and the assoc...	Master Data List, doc. JN189 ADC17 Issue 4 14/10/2010.Flight Manual Supplement, doc. JN189 ADC29 Issue 1 dated 16/11/09Instructions for Continued Airworthiness, doc. JN189 ADC54-25 Issue 5dated 14/10/2010Declaration of Compliance, doc. JN189 ADC58 Issue 2 dated 14/10/2010.or later revisions of the a...	Limitations as per associated technical documentation:- Flight Manual Supplement, doc. JN189 ADC29 Issue 1 dated 16/11/09- Instructions for Continued Airworthiness, doc. JN189 ADC54-25 Issue 5dated 14/10/2010.Restricted to S/N 24753	15/11/2010	Active	10032541
10032548	CENTURY FLIGHT SYSTEMS, INC		AK 847 STC SA 3389SW-D	PA-31, PA-31-325, PA-31-350	AK 847 Validation / Century 41 Installation in Piper, Type CertificateNumber A20SO models PA-31, PA-31-325, PA-31-350	The Certification Basis for the original product remains applicable tothis certificate/ approvalNo additional airworthiness requirements or special conditions areassociated with this changeIn accordance with Annex to 1702/2003 21A.101 (b) and associated GM thecertification specifications of the origi...	68S803 Pilot's Operating Handbook, January 1985 - OriginalFAA Approved Supplement to Pilot's Operating Handbook and/or FAAApproved Airplane Flight Manual Supplement, P/N 68S926, Revsion 1, dated8-5-81 is required for Piper Models PA-31 S/ N712 and Up and PA-31-325FAA Approved Supplement to Pilot Ope...	1. This STC is limited to aircraft Models PA-31, PA-31-325 and PA-31-350<(>,<)>2. Piper Model PA-31 is limited to S/N 712 and Up<(>,<)>3. Placard 13A990-1 stating "conduct trim check prior to first flight ofday (see POH)" is required	15/11/2010	Active	10032548
10032602	AVINCIS AVIATION ITALIA S.P.A	REV. 3		650	Enhanced Ground Proximity Warning System (EGPWS) Honeywell MK VIIIinstallation.Honeywell EGPWS MK VIII installation in replacement of Honeywell GPWS MKVI.Rev. 2 is an administrative re-issuance to reflect the recent namechange from INAER Aviation Italia S.p.A. Divisione Ala Fissa.Rev. 3: Transfer of...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Master Drawing List MDL-34-44-1003-A, Revision 00 from 10 Nov. 2010-Aircraft Flight Manual Supplement FMS-34-44-1003-A, Revision 00 from 18May 2010-Instructions for Continued Airworthiness ICA-34-44-1003-A, Revision 00from 04 June 2010-SAN statement of compliance to DOA SAN project No. 34-44-1003-A...	STC is applicable to S/N 650-0216 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	22/02/2024	Active	10032602
10032603	AIR METHODS CORPORATION		FAA STC SR00701DE-D	429	Installation of a controllable Searchlight	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	291-9010 revision IR dated 3 February 2010 - Master DrawingList;080-0468 revision IR dated 15 March 2010 - Flight Manual Supplement;050-0537 revision A dated 23 February 2010 - Instructions for ContinuedAirworthiness.or later revisions ofthe above listed documents approved by EASA inaccordance wit...	none	17/11/2010	Active	10032603
10032604	TDG AEROSPACE INC		FAA STC ST02285LA	B767-200, -300, -300F	Installation of Universal Fault Interrupter (UFI) for Centre Wing FuelTank Electrical Fault Protection.	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	UFI 767 Installation Kit Master Drawing List, 10-3206-0002,Revision B, 18/03/2010Airplane Flight Manual Supplement, 20-3206-0002, 26/02/2010Instructions for Continued Airworthiness, 20-3206-0001, Revision E, 04/02/2010 (EWIS Compliant).or later revisions of the above listed documents approved by EASA...	If the aeroplane has supplemental (high flow) jettison pumps installed,the installation of this STC requires them to bedeactivated.This STC approves accomplishment of the deactivation procedures for thesupplemental (high flow) jettison pumps (designator M1730 and M 1731)required by this STC as an A...	17/11/2010	Active	10032604

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032609	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04209AT-D	GIV-X	Aircraft Completion and Installation of an Airplane Interior	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation MasterIndex List GC4149144200, Revision E, dated October 20, 2010.Instructions for Continued Airworthiness Deviations SupplementGC42801A432, Revision A, dated October 19, 2010.or later revisions of the above listed documents approved b...	You may not use descriptive data about this design change to duplicateto other products.This approval is limited to aircraft Serial 4200.This STC does not permit manufacturing of parts for multipleinstallations.	17/11/2010	Active	10032609
10032617	AIR METHODS CORPORATION		FAA STC SR00704DE-D	BELL 429	Installation of Emergency Medical Services Interior and Systems	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	291-9002 revision IR dated 9 March 2010 - Master Drawing List;080-0464 revision IR dated 17 March 2010 - Flight Manual Supplement;050-0530 revision C dated 4 March 2010 - Instructions for ContinuedAirworthiness.or later revisions of the above listed documents approved by EASA inaccordance with EASAt...	None	17/11/2010	Active	10032617
10032620	AIR METHODS CORPORATION		FAA STC SR00710DE-D	BELL 429	Installation of Scene and Patient Loading Lights	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	291-9012 revision IR dated 1 February 2010 - Master DrawingList;080-0469 revision IR dated 17 February 2010 - Flight Manual Supplement; 050-0538 revision A dated 23 February 2010 - Instructions for ContinuedAirworthiness.or later revisionsof the above listed documents approved by EASA inaccordancet...	None	17/11/2010	Active	10032620
10032621	AIR METHODS CORPORATION		FAA STC SR00698DE-D	BELL 429	Installation of Patient Loading System	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	291-9004 revision IR dated 1 March 2010 - Master Drawing List;080-0465 revision IR dated 12 March 2010 - Flight Manual Supplement;050-0532 revision A dated 4 March 2010 - Instructions for ContinuedAirworthiness.or later revisions of the above listed documents approved by EASA inaccordance with EASAt...	None	17/11/2010	Active	10032621
10032628	LUFTHANSA TECHNIK AG			A319, A320, A321	New European Cabin Modification	Certification Basis in accordance with EASA Type Certificate Data SheetsA.064.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI H-01 "Enhanced Airworthiness Programme for AeroplaneI...	- Supplemental Type Definition Document, ref. doc. STDD25-10/21M, Issue1, dated 17th November 2010- Compliance Record List, ref. doc. CRL25-10/21M, Issue 1, dated 17thNovember 2010- Applicant's Declaration of Compliance No. 3001, dated 18th November2010or later revisions of the above listed document...	Not applicable	18/11/2010	Active	10032628

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032631	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04213AT-D	GIV-X	Aircraft Completion and Installation of Airplane Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation MasterIndex List GC414914202, Revision J, dated November 06, 2010.Instructions for Continued Airworthiness Deviations Supplement,GC42801A443 , Revision A, dated November 05, 2010.or later revisions of the above listed documents approved...	You cannot use descriptive data about this design change toduplicate toother ,,products.This approval is limited to Gulfstream GIV-X, Serial 4202.This STC does not permit manufacturing of parts for multipleinstallations.	18/11/2010	Active	10032631
10032651	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03742AT-D	GIV-X	Installation of a Cabin/Baggage Compartment.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC420004171, Revision G, dated November 02, 2010.Operation in accordance with Airplane Flight Manual SupplementGC41204M009 , Revision NC, dated November 20, 2009.or later revisions of the above listed documents approved by EAS...	None	19/11/2010	Active	10032651
10032680	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		PA-31P	Installation of two 4-blade MTV-16-1-E-C-F/CFL225-37a propellers onPiper PA-31PChange of Certification Basis.	The Certification Basis for the original product remains applicable tothis certificate/ approvalCAR 3 Amdt 1 through 8 as defined in FAA TCDS A8EAThis certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions le...	According to MT-Propeller Master Operation Manual List Doc.No. E-1951,Rev 0 and MT-Propeller Installation InstructionsDoc. No. E-1953, Rev 0or later revisions.To be operated in accordance with MT-Propeller AFM Supplement DocumentNo. E-1952-1 and Pilot´s Operating Handbook Supplement No. E-1952-2,0...	According limitation section of AFM-S and POH-S.	10/08/2011	Active	10032680
10032691	LUFTHANSA TECHNIK AG			A340-600	A340-600 Cabin Retrofit - ETD05	Certification Basis in accordance with EASA Type Certificate Data SheetsA.015.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI H-01 "Enhanced Airworthiness Programme for AeroplaneI...	- Supplemental Type Definition Document, ref. doc. STDD00-10/23M, Issue1, dated 23rd November 2010- Compliance Record List, ref. doc. CRL00-10/23M, Issue 1, dated 23rdNovember 2010- Applicant's Declaration of Compliance No. 2961, dated 23rd November2010or later revisions of the above listed document...	Not applicable	23/11/2010	Active	10032691
10032736 (EASA.IM.A.S.03130)	ACS-NAI Ltd.	REV. 2	TCCA LSTC C-LSA09-024/ D, ISS.3	BOMBARDIER CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-024/D Issue 3 dated 20 October 2010.Aero Consulting Services Ltd. Modification Data Summary G102000 RevisionG.Midcoast Aviation Inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior Installation, 33-299M008 Rev NC.Aero Consulting Services Ltd. Mandator...	Restricted to ASN 8077.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/08/2013	Active	10032736

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032737 (EASA.IM.R.S.00592)	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC SR00850SE	407 206L, 206L-1, 206L-3, 206L-4	Cargo Hook Kit model 200-260-00 and 200-260-01This change adds an additional cargo hook	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	155-057-00 revision 19 dated 30 October 2009 - Master Drawing List; 120-093-00 revision 8 dated 15 September 2009 - Owners Manual; 123-001-00 revision 4 dated 11 August 2009 - Instructions for ContinuedAirworthiness; 122-005-00 revision 15 dated 23 April 2009 - Cargo Hook Service Manual; 121-002-00 revi...	Applies only to those Bell Helicopter models listed above previouslyequipped with Bell Helicopter Cargo Hook SuspensionSystem206-706-341-5, 206-706-341-101 or 206-706-341-109 andeitherBreeze-Eastern cargo hooks 17149-2, 17149-6 or Onboard Systems Cargohooks 528-010-04 or 528-023-01	26/11/2010	Active	10032737
10032763	SABENA TECHNICS BGC			777-300ER	Onboard Mobile Phone system installation on Boeing 777-300ER aircraftprovisioned by Boeing	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalSpecial ConditionCRI H-01 EWISThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable...	MDL 0333-02-A-2103-R00 dated 25/11/2010Certification Plan 0333-02-A-2101 rev 01Aircraft Flight Manual Supplement (AFMS) 0333-02-A-2301 rev 02Aircraft Maintenance Manual Supplement0333-02-A-2304 initial issueInstruction for Continued Airworthiness (ICA) 0333-02-A-2211 rev. 01	The applicability of this STC is limited to Boeing 777-31HER aircraftMSN38983, MSN38984 and MSN35595	30/11/2010	Active	10032763
10032771	LIFEPORT, LLC		FAA STC ST02286LA	CESSNA 680	Installation of a Medical Patient Loading and Utility System (PLUS)	EASA TCDS IM.A.033The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificat...	Master Drawing List MDL-845-00, Revision T from 11 Nov. 2009Airplane Flight Manual Supplement EGR-845-11, Revision A from 22 Feb. 2010Instructions for Continued Airworthiness EGR-845-12, Revision A from 25Jan. 2010or later revisions of the above listed documents approved by EASA inaccordance with EAS...	None	30/11/2010	Active	10032771
10032781	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			DR400/NGL DR400/2+2, DR400/500, DR400/180 S, DR400/200 R, DR400/180, DR400/180 R, DR400/160, DR400/160 D, DR400/140, DR400/140 B, DR400/120, DR400/120 A, DR400/120 D, DR400/125, DR360, DR380, DR400/100, DR300/180 R, DR315, DR340, DR300/125, DR300/140 DR300/108, DR300/120,	A-07-09-Filtre Ed. 0 - Installation of remote oil filter kit	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Document d'Application A-07-09-Filtre_DA du 15 Novembre 2010or later revisions of the above listed documents approved by EASA	None	01/12/2010	Active	10032781
10032786	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	737-700	Interior Reconfiguration from 18 to 22 Passenger Capacity on Boeing737-700 Aircraft	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CS25 Amdt. 4 requirements as defined in the Certification PlanH4ACP062 issue 6 dated 04th October 2010- CRI D-01 issue 2 Deviation: Heat...	- Airplane Flight Manual Supplement Ref. H4AFMS020 Issue IR-Certification Plan Ref. H4ACP062 issue 6 dated 04th October 2010-Modification Summary Ref. H4A1303 Issue 4 dated 21 October 2010or later revisions of the above listed documents approved by EASA	None	03/12/2010	Active	10032786

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032788	AAXICO TECHNICAL SERVICES INC.	REV. 2	FAA ST03574AT	SEE EASA APPROVED MODEL LIST	Anti Collision Lights installation:This STC installs a new model of anti-collision light.Rev 1: Addition of 737, DC9, MD80 and MD90 types to the EASA-approvedmodels list (list andassociated documents updated).Rev. 2: Transfer of STC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): H-01 ICA on EWISthe following paragraph(s) at a later amendment: affected paragraphs atCS25 amdt. 4: 25.601, 25.603, 25.605, 25.609, 25.613, 25.1301,...	Master Data List, ref: MDL-001, Revision 7Airbus A300 / A310: Installation Instructions A0-001 Revision 2, dated01 October 2010Airbus A318 / A319 / A320 / A321: Installation Instructions A2-001Revision 2, dated 01 October 2010Airbus A330 / A340: Installation Instructions A3-001 Revision 2, dated01 O...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/06/2021	Active	10032788
10032795	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBILITY	114, 114A, 114B, 114TC 112, 112TC, 112B, 112TCA,	Aspen EFD1000 Software Version 2.3.1 upgrade	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	Flight Manual Supplement AFMS-1108, Issue 2Instructions forContinued Airworthiness ICA-1108, Issue 2or later revisionsof the above listed documents approved by EASA.	None	03/05/2012	Active	10032795
10032842	VAN RIEMSDIJK ROTTERDAM B.V.	REV. 16		777F 747-8F 747-400F 747-200F 2. 777F 1. 747-200F/-400F/-8F	RGX-0517 Special Cargo ContainerCargo container with a pallet size of 238.5” x 96” with P/N 136.080-000,P/N 136.080-080, P/N 136.080-085, P/N 136.080-100, P/N 136.080-110 and P/N 136.080-200 and P/N 136.080-086.Rev 1: typo corrected in thelimitations sectionRev 2: B747-8F and 777F added to the appl...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- CMM / IPL RGX Coolcontainer P/N 136.080-000, Ref. 25-55-17 / RRM517issue 18- CMM / IPL RGX Coolcontainer P/N 136.080-080, Ref. 25-55-17 /RRM517-080 issue 10- CMM / IPL RGX Coolcontainer P/N 136.080-085, Ref. 25-55-17 / RRM517-85issue 6- CMM / IPL RGX Coolcontainer P/N 136.080-086, Ref. 25-55-17 /i...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The loading limitations from the RGX container are acco...	12/09/2025	Active	10032842
10032879	ROTORCRAFT SUPPORT, Inc.		FAA STC SR01456LA	407	Installation of Concorde RG407 Battery	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	RS407-010 revision C dated 30 June 2003 - Master Document List;RS407-006 revision NC dated 20 May 2003 - Installation Instructions;RS407-007 revision NC dated 30 June 2003 - Flight Manual Supplement;5-0144 revision E dated 19 October 2004 - Concorde Instructions forContinued Airworthinessor later re...	None	06/12/2010	Active	10032879
10032887	LUFTHANSA TECHNIK AG			B737-500	DLH New European Cabin for 737-500 Aircraft.Modification ofthe Aircraft seat layout to increase the seat capacityfrom currently 111 seats to 120 new seats, produced by RecaroAircraftseating, Germany.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Supplemental Type Definition Document Ref. STDD00-10/03M issue 01dated 01 December 2010- Compliance Record Document Ref.CRL00-10/03M dated 01 December 2010- Applicant's Declaration of Compliance No.2770 dated 02 December 2010or later revisions of the above listed documents approved by EASA	Not Applicable	06/12/2010	Active	10032887

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032893	INNOVATIVE SOLUTIONSAND SUPPORT, Inc.		FAA STC SA02255NY	PC-12	PC-12 IS<(>&<)>S PFD (FAA SA02255NY)Configuration A - Dual 15" Flat Panel Display System (Pilot and CopilotPositions)Installation of Innovative Solutions & Support - (IS<(>&<)>S) Dual 15"Flat Panel Display System in accordance with IS<(>&<)>S Master Drawinglist, ID-06319 Revision 9, dated March 27,C...	FAR 23The certificated noise and l or emissions levels of the original productareunchanged and remain applicable to this certificatel approval	Configuration A - Dual 15" Flat Panel Display System (Pilotand CopilotPositions) IS<(>&<)>S Airplane Flight Manual Supplement Document No. 1D-06314,revision C, FAA Approved April 7, 2009 is required with thisinstallation.Configuratio n B - 10" Flat Panel Display System (Pilot and Copilot/ PilotSide On...	Reg.: \-\ S/N: PC-12, /45, /47	08/12/2010	Active	10032893
10032896	B/E AEROSPACE, Inc. - FSI		FAA STC ST02160SE-D	B737-500	Interior Reconfiguration in accordance with Flight structures, Inc.(FSI) Master Drawing List B0FS003-D01Installation ofnew windscreen, stowage bin, stowage bin extension kits,moveable under-bin class divider, sidewall panel, lowered ceiling paneland associated installation hardware.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Flight structures, Inc. (FSI) Master Drawing List B0FS003-D01 Rev.Cdated 01-Dec-2010- Certification Plan Summary B0FS003-D10-1 Rev.C dated 02 December 2010- Supplement to Instructions for Continued Airworthiness (ICA)B0FS003-D15 rev.B dated 19 November 2010.or later revisions of the above listed d...	Not Applicable	07/12/2010	Active	10032896
10032902	airplus engineering GmbH	REV. 1		SC 01, SC 01B	Inspection Program to increase operating hoursMM Modification of chapter IV Airworthiness Limitations - Implementationof Inspection Program to increase operating hours	The Certification Basis for the original product remains applicable tothis certificate/ approval.FAR 23, Amdt. 1-23The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate...	Maintenance Manual Supplement MM-1005-000000, Rev. 1or later revisions of the above listed documents approved by EASA	None	08/02/2021	Active	10032902
10032903	AVIATION FABRICATORS, Inc.		FAA STC REF SA4157SW	SEE EASA APPROVED MODEL LIST	Installation of one, two, or three place side facing seat (frame only).	FAR 23, plus Amendments listed in the EASA or FAA TCDS, as appropriateto the ModelThe Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	Installation in accordance with Aviation Fabricators Drawing ref B6912dated 7/4/80, or drawing list AF-291, no revision, dated August 14, 2002or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None	07/12/2010	Active	10032903
10032904	ASI INNOVATION			F406	ASI-FAM-0015-02 Provision installation of console PMR/DMR and UHFantenna	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	None	Limited to: F406 S/N 006-017-025-039-042-070-074-075-077-086	07/12/2010	Active	10032904
10032905	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			PA-28RT, PA-201T,	Avionic modification: dual installation of Garmin GNS 430W (with GA 35antennas) for B-RNAV operation with coupling to autopilot, installationof GMA 340 audio Intercom, KN 62A DME receiver and WX 500 stormsocpewith NY163 antenna	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	SEAM Flight Manual Supplement No 3049/10, Revision 1, dated22 October2010SEAM Modification File No 3049/10, Revision 1, dated 22 October 2010or later revisions of the above listed documents approved by EASA	The installation is limited to aircraft PA-28RT/PA-28T S/N 28R813143.The aircraft must be equipped with a third radionavigation orradiocommunicator mean independent from the two GNS 430 units.The GNS 430W software version must be No 3.3. Installation of a furtherversion must be approved.	07/12/2010	Active	10032905

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032907	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9367	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada SoC reference C-10-0643 dated 02 December 2010TCCA STC No. SA04-113 Issue 1 dated 28 October 2004Aero Consulting Services Configuration Definition List D954000 RevisionFW dated 26 November 2010Instructions for Continued Airworthiness GC93670000-IFCAor later revisions of the above li...	Restricted to ASN 9367 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).3.Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and...	07/12/2010	Active	10032907
10032919	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9371	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada SoC reference C-10-0641 dated 25 November 2010TCCA STC No. SA04-113 Issue 1 dated 28 October 2004Aero Consulting Services Configuration Definition List D954000 RevisionFU dated 19 November 2010Instructions for Continued Airworthiness GC93710000-IFCAor later revisions of the above li...	Restricted to ASN 9371 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).3.Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and...	08/12/2010	Active	10032919
10032950	LITEAIR AVIATION PRODUCTS Inc.		FAA STC ST02073SE	777-200, -300, -200LR, -300ER	Lightweight window plug Installation	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	FAA STC ST02073SE. dated July 26,2010LiteAir Certification Plan, LAP1009-R10. Revision A, dated March 11,2010LiteAir Master Drawing List, LAP 1009-D01, Revision A, dated June 23,2010LiteAir Installation Drawing. LAP2009. Revision B, dated June 23, 2010or later revisions of the above listed documents...	None	09/12/2010	Active	10032950
10032965	FIELD AVIATION COMPANY INC.		TCCA LSTC C-LSA09-212/ D	DHC-8-311	Installation of Aft Baggage Bay Divider NetsTCCA LSTC C-LSA09-212/D	FAR 25 as per EASA.IM.A. 191The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this c...	Installation must be in accordance with TCCA approved FieldAviationCompany Inc. Modification Instruction 218110, IR, dated 30 June 2009.Maintenance must be in accordance with TCCA accepted Field AviationCompany Inc. Maintenance Manual Supplement 218131, IR, dated 30 June2009.or later revisions of t...	The modification is applicable only when the necessary structuralprovisions are pre-existing.	10/12/2010	Active	10032965
10032968	BAYO S.A.S.		STC 2010-006	HR 100/285 TIARA HR100/250 TR, HR 100/285 C HR 100/210, HR 100/210 D HR 100/200, HR100/200 B	Installation of single EFIS Aspen EFD1000 Pro for VFR navigation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Bayo AFM supplement n °2010-006, revision 3 dated 09/12/2010Bayo Master list n° 2010-006-ML, revision 4 dated 09/12/2010Bayo modification file n° 2010-006-DEF, revision 2 dated 30/09/2010	Approved software version for ACU and PFD units is 1.1.Navigation coupling to automatic pilot is limited to heading mode.	10/12/2010	Active	10032968
10032969	H4 AEROSPACE (UK) Ltd.	REV. 2	CAA UK RESPONSIBILITY	BD-700-1A10	Activation of Nicemate WLAN System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	H4 Aerospace Modification Summary No. MOD H4A1334 Issue 4 dated 05 May2011H4 AFMS No. H4AFMS023H4 ICA No. H4ADR560 Issue 2or later revisions of the above listed documents approvedby EASA	Restricted to ASN 9011.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	14/06/2016	Active	10032969

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10032980	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04215AT-D	GIV-X	Aircraft Completion and Installation of an Airplane Interior on AircraftSerial 4203.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gulfstream Aerospace Corporation MasterIndex List GC414914203, Revision F, dated November 09, 2010.Aircraft to be maintained in accordance with Instructions for ContinuedAirworthiness Deviations Supplement GC42801A431, Revision A, datedNovember 09, 2010.or later revis...	You cannot use descriptive data about this design change toduplicateother products. This approval is limited to only the installation madein Gulfstream GIV-X, A/C 4203. This STC does not permit manufacturing ofparts for multiple installations.	13/12/2010	Active	10032980
10032984	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	B200, B300	Installation of Thrane & Thrane Aviator 200/300 Inmarsat Satcom withWi-Fi capability on Beechcraft King Air B200/ B300	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installed to Major Change SC0353A at issue 1.Operation in accordance with Hawker Beechcraft Limited Airplane FlightManual Supplements:-King Air B200:101-590168 Supplement 1, Issue1.King Air B300: 130-590031 Supplement 1, Issue 1.Aircraft to be maintained in accordance with Instructions for Continue...	This modification is only applicable to aircraft equipped with theCollins Proline 21 avionics package. Refer to aircraft defined in HawkerBeechcraft major change SC0353A.	13/12/2010	Active	10032984
10033022	AVIATION SERVICE A.S.			AN-26B	An-26 Aircraft Upgrade; TCASII CAS-67A, Mode S Transpon. MST-67A andKT73, EGPWS Mk-VI, NAV/COMM KX165A, GPS155XL, Audiopanel KMA28, WxRadar ART2000, MFD KMD540, ADF KR87, DME KN63, Air Data Display AD32,RAlt KRA405B, Airspeed Ind. LUN110, ELT C406-2;	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI A-100The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original produ...	CP226 and CHH226	None	15/12/2010	Active	10033022
10033032	SABENA TECHNICS BOD			A321 ALL MODELS A320 ALL MODELS A319 ALL MODELS A318 ALL MODELS	Full provision for EFB Class 2 on Single Aisle Aircraft	Certification Basis in accordance with EASA Type Certificate Data SheetsA.064.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI H-01 "Enhanced Airworthiness Programme for Aeroplanel...	- Modification Approval Sheet, ref. Modification S-46-2102,Issue 2,dated 10th December 2010- Certification Program, ref. DO/N/2009/226/DZ, Issue 3, dated 10thDecember 2010- Airplane Flight Manual Supplement, ref. AFM-S-D9032-01, Rev. Cor later revisions of the above listed documents approved by EAS...	Not applicable	15/12/2010	Active	10033032
10033035	B/E AEROSPACE, Inc. - FSI		FAA STC ST02161SE-D	B737-300	Interior Reconfiguration in accordance with Flight Structure, Inc. (FSI)Master Drawing List B0FS003-D02Installation of new windscreen, stowage bin, stowage bin extension kits,moveable under-bin class divider, sidewall panel, lowered ceiling paneland associated installation hardware.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- FSI Master Drawing List B0FS003-D02 Rev.C dated 11-Dec-2010- Certification Plan Summary B0FS003-D10-2 Rev. C dated 13-Dec-2010- Supplement to Instructions for Continued Airworthiness (ICA) B0FS003-D15 Rev. B dated 19 November 2010.FAA:"orlater revisions of the above listed documents approved by EA...	None	15/12/2010	Active	10033035

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033038	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		TBM 700 N TBM 700 C1, TBM 700 C2, TBM 700 A, TBM 700 B,	Installation of 5-blade constant speed propellerMTV-27-1-E-C-F-R(P)/ CFR225-55f propeller on TBM 700 A, TBM 700 B, TBMC1, TBM C2, TBM 700 N (tradename TBM850), TBM 700 N (tradenameTBM850G1000), TBM 700 N (tradename TBM900)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.CS 36, Amdt 3 and FAR 36 Amdt 30	According to MT-Propeller Master Document List No. E-2011 Rev.1To be operated in accordance with MT-Propeller AFM-S Document No. E-1878or later revisions of the above listed documents approved by EASA.To be installed iaw. Installation Instructions Doc. No. E-1879, or laterRevisionsTo be maintained i...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	07/09/2015	Active	10033038
10033096	PETERSEN AVIATION, INC.		FAA STC SA2670CE	2. A-1C-180 1. A-1, A-1A, A-1B	Operation of airplanes using automotive gasoline according US STCSA2670CE	The Certification Basis for the original product remains applicable tothis certificate/ approval.FAR 23The requirementsfor environmental protection and the associatedcertificatednoise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	Installed iaw Petersen Drawing No. A-1, dated 12 Nov 1990,FAA approved AFM-S No 1, dated 27 Nov 1990 orFAA approved AFM-S No 2, Rev (-), dated 4 Apr 2010,or later revisions of theabove listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis de...	-According limitation section of AFM-S-Limited to those airplanes equipped with gravity fuel feed tocarburetor only-Notapproved for 82UL or mixtures with 82UL-Limitation as indicated in FAA STC SA2670CE also apply	17/12/2010	Active	10033096
10033098	AEROLITE AG			EC135	VIP Equipment P/N 135748-501	JAR 27 Issue 1The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productareunchanged and remain applicable to this certificatel/ approval	EQL-1 0-01 0 Revision N/ CIM-10-004 Revision N/ CMDL-10-010	Reg.: \-\ ,,S/N:	17/12/2010	Active	10033098
10033112 (EASA.A.S.03762)	LUFTHANSA TECHNIK AG	REV. 1		A340-313 A340-300	A340-300 – “GAF” VIP Cabin Interior CompletionRev. 1 introduces a reduction of the Minimum Cabin Crew on a number of8.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.App.S25.50 (a)at Amdt 19.- CRI A-2301-002EASA Supplemental Type Certification Basis forLufthansa Tech...	Supplemental Type Design Document, STDD00-08/15M Issue 02, Rev 00, dated25 Oct 2021Airplane Flight Manual, A-00-09/138-AFM Issue 02, Rev 00, dated 20 Oct2021Instructions for Continued Airworthiness, A-00-09/138-ICA Issue 03, RevIR, dated 08 Sep 2011or later revisions of the above listed document(s) u...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/11/2021	Active	10033112
10033140	AVIDYNE CORPORATION	REV. 1	FAA STC SA00296BO	SR20, SR22	Installation of:-Avidyne Model DFC90 Autopilot P/N 700-00170-000 System, loaded withRelease 2 software-Avidyne Model DFC100 Autopilot P/N 700-00170-001 System, loaded withRelease 2 software	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with: Avidyne Master Document List AVDFC-019,Rev. 10Operation in accordance with:-For DFC90:Avidyne AFM-S Document 600-00249-000, Rev 03-For DFC100: Avidyne AFM-S Document 600-00271-000, Rev 02Instructions for Continued Airworthiness as defined in: AvidyneAVDFC-030, Rev.o...	As indicated in FAA STC SA00296BOAircraft must be configured with an existing S-TEC Manual Electric Trim(MET) System and with an existing STEC Autopilot as follows in order toaccomplish this STC:Avidyne Corporation Autopilot,,Existing S-TEC,,S-TEC Part NumberFor DFC90,,System 20 with 30ALT,,01260-(,...	06/03/2014	Active	10033140

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033154	ROEDER PRAEZISION GMBH	REV. 1		SA26-T, SA26-AT, SA226-T SA227-TT, SA227-AC, SA227-DC SA227-AT SA226-AT, SA226-T(B), SA226-TC	Dual Installation of GNS 430 WAAS in SA226/227 Series	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The requirementsfor environmental protection and the associatedcertificatednoise and/or emissions levels of the original product areunc...	Instructions for Installation: GNS430-NY-03157-05, Rev. 2, dated05.08.2010Flight Manual Supplements: GNS430-NY-03157-08, Rev. 3, dated 05.08.2010Instructions for Continued Airworthiness: GNS430-NY-03157-07, Rev. 1,dated 05.08.2010or later revisions of the above listed documents approved by EASA	Installation of 3rd dissimilar and independent COM system required toIFR operation.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon...	15/11/2017	Active	10033154
10033155	AVIONITEC AG			T303	Avionics RetrofitRemoved:-Garmin GNS 430 NAV/COM/GPS-King KX 165 NAV/ COM with King KI 206 Indicator-ARC RTA 476A DME-ARC R-446A ADF with ARC IN 346A IndicatorInstalled:-Garmin GNS530W NAV/COM/GPS (upgrade from a Garmin GNS 430)-Garmin GNS430W NAV/COM/GPS with Garmin GI 106A Ind.-King KN62A DME	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-Master Document List: Doc. No PI91405-017, Rev. 0-Instructions for Continued Airworthiness: Doc. No. PI91405-015, Rev.0-Airplane Flight Manual Supplement: Doc. No. PI91405-011, Rev. 1or later revisions of the above listed documents approved by EASA	Limited to: HB-LUV, S/N T30300058	21/12/2010	Active	10033155
10033158 (EASA.IM.A.S.03191)	GARMIN INTERNATIONAL, Inc.	REV. 10	FAA SA01535WI-D	B. A200, A200CT B. 200, 200C, 300, 300LW A. B200GT, B300, B300C A. B200, B200C, B200CGT	Installation of the Garmin G1000 Integrated Avionics Systemand GFC 700Automatic Flight Control System and optional Electronic Stability andProtection (ESP).Rev.7 adds two new models and updates the Master Data Lists (MDL) forthe B200 and B300 models.Rev. 8 is a correction and re-introduces the ment...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:-Special Condition(s): FAA Special Condition 23-291-SC/EASA SpecialCondition F23.1329-01.-Equivalent Safety Finding(s): PCRI-0000399-0060090175 3D SafeTaxi....	Required Data for Model 200 Series:(1) Garmin Master Drawing List (MDL) 005-00421-00, Revision 3, dated 14March 2009;(2) For installations with system software version 0985.00 or later,Garmin Airplane Flight Manual Supplement(AFMS) 190-00915-02, Revision 1, dated 14 March 2009;(3) For installationsG...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	28/02/2025	Active	10033158
10033161	ANCRA INTERNATIONAL LLC		FAA STC ST02319LA	B737-400	Installation of main deck cargo loading system	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Controlled Data List DL84991 Rev. C, dated 27/09/2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentrevisions ofthis decision)	EASA validated equivalent to FAA STC ST01827LA must be installed inconjunction with this STC	21/12/2010	Active	10033161
10033164 (EASA.R.S.01505)	NSE	REV. 7		EC135 T3 (CPDS) EC135 T3 EC135 T2 (CPDS) EC135 T1, EC135 T2, EC135 T2+ EC135 T1 (CPDS) EC135 P2+, EC135 T2+ EC135 P2 (CPDS) EC135 P1, EC135 P2, EC135 P2+ EC135 P1 (CPDS)	Installation of a Night Vision Imaging System (NVIS) enabling operationwith Night Vision Googles (NVG)Initial: Introduction of NVIS configuration EC135 NVIS Lighting SystemP/N 60D-1000-000 amendment 03Rev. 1: Introduction of NVIS configuration EC135 NVIS Lighting SystemP/N 60D-1000-000 amendment 04R...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	PCERT-EC135-NVIS-3132-01 REV A2 Certification Program 23/04/2025SD-EC135-NVIS-2132-01 REV A2 System Description 23/04/2025SDL-EC135-NVIS-2132 REV B2 STC Data List 23/04/2025RFM-EC135-NVIS-2132 REV 01 Rotorcraft Flight Manual Supplement18/02/2025ICA-EC135-NVIS-2132 REV B1 Instruction For Continued Ai...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The approval holder shall fulfill the obligations of Pa...	28/04/2025	Active	10033164

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033170 (EASA.IM.A.S.03020)	INNOVATIVE SOLUTIONSAND SUPPORT, Inc.	REV. 3	FAA ST02372CH	757-200, 757-300 757-200, 757-200PF, 757-300	Installation of an Innovative Solutions and Support (IS<(>&<)>S)Integrated Flat Panel Display System (IFPDS) and of an L-3 AvionicsSystems GH-3100 Electronic Standby Instrument System (ESIS)Rev. 1 rephrases the paragraph on limitations.Rev. 2 corrects a typographical error.Rev. 3 adds the model 757-...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments.For changed area the certification basis is CS25 initial issue.Applicable requirements are:25.301, 25.303, 25.305, 25.307, 25.561, 25.601, 25.603, 2...	- Master Data List (MDL) Document 1D-07687, Revision 33, dated 08February 2021- Aircraft Flight Manual Supplement (AFMS) Document 1D-07718, Revision7, dated 10 February 2021- IS<(>&<)>S Instructions for Continued Airworthiness (ICA) DocumentID-07688, Revision 15, dated 08 February 2021- IS<(>&<) >S E...	Refer to FAA Advisory Circular (AC) 20-188 for compatibility of thisdesign change with previously approved modifications.To comply with the EASA Certification Basis above (CRI F-01 inparticular), aeroplanes modified with this STC must havethe followingLine Replaceable Units (LRUs) installed:- Integ...	22/03/2021	Active	10033170
10033177	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9369	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada SoC reference C-10-1060 dated 16 December 2010TCCA STC No. SA04-113 Issue 1 dated 28 October 2004Aero Consulting Services Configuration Definition List D954000 RevisionFX dated 14 December 2010Instructions for Continued Airworthiness GC93690000-IFCAor later revisions of the above li...	Restricted to ASN 9369 and1.Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).	21/12/2010	Active	10033177
10033185	ROW 44, Inc.	REV. 3	FAA STC ST02829CH	B737-700/-800/-900/-900ER	Installation of Row 44 broadband antenna system provisions.Revision 1: Transfer of ownership from Armstrong Aerospace to Row 44Inc.Revision 2: Validates the configurations with Boeing's optional cabinceiling life raft installed. EASA Certification basis formally upgradedfrom CS25 amdt. 1 to amdt. 2....	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): H-01 "Enhanced airworthinessprogramme foraeroplane systems - ICA on EWIS".The followingparagraph(s) at a later amendment: CS 25 amdt. 2 for theaffe...	Master Data Index Listing (MDIL) Doc. No. DC104-7023-00, Revision Y,dated August 12, 2015.Instructions for Continued Airworthiness, Section 2, AirworthinessLimitations, as identified in Row 44 individual configuration Masterdata List contained within Master Data Index Listing, Document No.DC104-7023...	- The equipment for which these provisions are intended hasnot beencertified. Additional approval is required for the installation of thisequipment and must be evaluated to assure satisfactory compliance withthe applicable airworthiness standards.- For effective aircraft NOT fitted with Low Cabin A...	15/02/2017	Active	10033185
10033186	ROW 44, Inc.	REV. 6	FAA ST02836CH-D	-700/ -800/ -900/ -900ER	Installation and Activation of a Row 44 broadband system.Revision 1: Limitation about Honeywell displays P/N 4091900-xxx added.Revision 2: Transfer of ownership from Armstrong Aerospace to Row 44Inc.Revision 3: Validation of the configurations with the option to installa new ROW44 High Power Tran...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):. H-01 "Enhanced airworthiness programme for aeroplane systems – ICA onEWIS" Issue 2.. F-01 "Installation of Wireless Area Networks (WLAN)" Issue 3.Th...	- Master Data Index Listing (MDIL) Doc. No.DC104-7024-00, Revision AH,dated December 28, 2016.- Instructions for Continued Airworthiness as identified in each MasterData List referenced in the MDIL Doc. No.DC104-7024-00, Revision AHdated December 28, 2016.- Airplane Flight Manual Supplements as iden...	- The Row 44 Wireless Broadband System is intended to provide internetconnection and email services to the airplane's cabin using portableelectronic devices (PEDs). Any other use of this equipment requiresadditional approval.- Row 44 Broadband Antenna System Provisions installation must beaccomplish...	07/11/2018	Active	10033186
10033194 (EASA.A.S.03937)	TELEDYNE UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	B737-600/-700/-800/-900/-900ER 737-900, 737-900ER 737-600, 737-700, 737-800	Installation of enhanced airborne data loaderRev. 1: Transfer from Teledyne Limited to Teledyne UK Limited.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- CS 25.1713 Amdt 5 - EWIS Fire Protection, Wire Insulation flammability- CRI H-1 Enhanced Airworthiness Programme for Aeroplane Systems – ICAon EWIS- D2006/ CPRO/LAP/PME/5...	- Master Data List MOD-MDL-024-02 Issue 2 dtd. 12 Oct 2010-Instructions for Continued Airworthiness MOD-ICA-024 Rev. 1dtd. 12Feb 2010or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This modification is only applicable to 737 aircraft that already havean ADL installed or have provisions for installation of an ADL.Compatibility must be established for each aircraft.	26/11/2020	Active	10033194

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033212	KUERZI AVIATION AG	REV. 1		MDD 500N	MD520N Gyro camera & equipment inst. (Gyrocam "Turret Assy" for filming or live broadcasting)	CAR 6 dated December 20, 1956, including Amendments 6-1 through 6-4 andSpecial Conditions.The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this...	- Flight Manual Supplement Doc. No. FMS 201032936;or later revisions of the above listed documents approved by EASA.- Operating Instructions Doc. No. OPI-201032936;- Master data list Doc. MDL-201032936;	Reg.: \-\ S/N: LN052; LN 068; LN069Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The insta...	14/02/2013	Active	10033212
10033224	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE		O-LSA07-225/ D,ISSUE 1	P-180 AVANTI II	TCA STC No. O-LSA07-225/D Issue 1 "Import Configuration - InteriorCompletion (including various cabin installations)"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement No. FMS10131.1, Rev. 1 dated 7 December 2010Weight & Balance Manual Supplement No. WBS10131, Rev. 1 dated 7 December2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision)	None	04/01/2011	Active	10033224
10033225	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	PA-44-180 & PA-44-180T	Installation of Garmin G500/G600 PFD/ ND	CS-23The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Data List MDL1151-01 Issue 1Change Statement CS1151-01 Issue 1Instructions for Continued Airworthiness ICA1151-01 Issue 1Flight Manual Supplement AFMS1151-01 Issue 1or later revisions of the above listed documents approved by EASA	None	05/01/2011	Active	10033225
10033233	TENENCIA Ltd.		CAA UK RESPONSIBILITY	AVRO 146-RJ85	Modification TEN 655, AVRO 146-RJ85, Installation of 3R and4R Galleysand No. 3 VHF COMM	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalJAR-25 at Change 10 in lieu of JAR-25 at Change 5.Electronic Wiring Interconnection System (EWIS) requirements in CS-25Amendment 8 Appendi...	Modification TEN 655, AVRO 146-RJ85, 3R and 4R Galley and No 3 VHF CommInstallation. Tenencia Ltd document number TEN 655, Issue 3 dated 24thDecember 2010.or later revisions of the above listed documents approved by EASA	Serial numbers E2323 and E2325 only.	05/01/2011	Active	10033233
10033237	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS LTD		CAA UK RESPONSIBILITY	B767-300	Installation of First Class Seating	The Certification Basis for the original product remains applicable tothis certificateThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval	Modification Summary, MOD-836, Revision A, 12/10/2010or later revisions of the above listed documents approved by EASA	None	05/01/2011	Active	10033237
10033242	ST ENGINEERING AEROSPACE LTD.			A321	Passenger Compartment Reconfiguration	Certification Basis in accordance with EASA Type Certificate Data SheetsA.064.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI H-01 "Enhanced Airworthiness Programme for Aeroplanel...	- Master Document List, ref. doc. 386/003/AED/002, Rev. A, dated 17thDecember 2010- LOPA STC Certification Plan, ref. 386/003/AED/001, Rev. B, dated 17thDecember 2010or later revisions of the above listed documents approved by EASA	Not applicable	06/01/2011	Active	10033242
10033253	DART AEROSPACE Ltd.		TCCA STC SH10-44	L, L1, L3, L4, 407 206, A, A1, B, B1	Automatic Door Opener Kits (Cabin and Baggage Doors).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR 27 amendment 27-45The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the o...	MDL-D407-802 revision A dated 17 November 2010 - Master Document List;IIN-D407-802 revision A dated 13 October 2010 - InstallationInstructions;ICA-D407-802 revision 0 dated13 October 2010 - Instructions forContinued Airworthiness.	None	07/01/2011	Active	10033253

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033267	SUPERVAN SYSTEMS, Ltd.	REV. 4	FAA SA10841SC	208 AND 208B 208, 208B	The modification consists of removal of the Pratt & WhitneyPT6A-114/114A engine to install a Honeywell TPE331-12JR engine andHartzell propeller, identified below, along with associated installationcomponents in accordance with Supervan Master Data ListSSL-MDL-208-4001, Rev. Q, dated December 28, 202...	The following paragraph(s) at a later amendment:Based on 14CFR §§ 21.101 and 21.115, and the FAA policy for significantchanges in FAA Order 8110.48, the certification basis for the Cessna 208and 208B modified in accordance with Supervan Master Data List,SSL-MDL-208-4001, Rev. Q, dated December 28,r...	Airplane Flight Manual Supplements: The following FAA-Approved Manual Supplements, at the indicatedrevision level or later FAA-approved revision, are required forairplanes with the 900 SHP (-702TT or -704TT) engines installed: For 208 Model Landplane: Document SSL-FMS-208-12JR LandplaneRev....	STC Compatibility with other STCs: Model 208 airplanes:Compatible with gross weight increase changesper STC SA270CH. Model 208 airplanes: Compatible with Wipaire float modification STCSA1311GL. Wipaire Service Kit 25 must be installed on aircraft withserial number 20800329 and earlier.per...	30/09/2022	Active	10033267
10033276	SKYTRAC SYSTEMS Ltd.	REV. 1	TCCA STC SH10-24 ISSUE 2	EC 120 B	Sky Track ISAT AIRBORNE POSITION / COMMUNICATION UPGRADEThemodification upgrades an existing ISAT-100 Airborne Position / DataCommunicator system installation to an ISAT-200 system(This EASA approval validates the TCCA STC SH10-24, Issue 2)Revision 1 is an administrative re-issuance to update the a...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Special Condition on Lythium Batteries as per EASA CRI F-01 Issue 2The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the produc...	- Avionics Design Services LTD Master Drawing List MDL10033, Revision B,Issue 1, dated December 17, 2010. (relative to the EC 120B);- Avionics Design Services LTD Drawing List DL10033-1, Revision A, Issue1, dated December 17, 2010;- FlightManual Supplement FMS10033-1, Revision A, dated November 24,...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/05/2024	Active	10033276
10033281 (EASA.A.S.03943)	SABENA TECHNICS BOD			F28 MK 0100	Fokker 100 CABIN VIP (premod EASA STC A.S.02677)	JAR 25 Change 11	CRI D-04 dated 7 January 2011AFM Supplement FMS-FK-1003-25-001 dated 7 January 2011	This Change to STC A.S.02677 does not require a technical change to theaircraft.Private use only, max 30 passengers	11/01/2011	Active	10033281
10033288 (EASA.R.S.01542)	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 5		AS 355 NP	INSTALLATION OF HELICOMV2-NUMInstallation of a System for Tracking and Recording a set of flight andsystem parameters during operation of the rotorcraftRev. 5: STC holder name change from I.S.E.I International Services toSAFRAN ELECTRONICS& DEFENSE BUSINESS UNIT - HELICOPTERS DATA MANAGEMENTSOLUTIO...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition(s): CRI F-01 for Lithium Battery Installation dated17/05/2013.The requirements for environmental protection and the associatedcertificated noise and/ o...	- Design change N3-AS355 NP-HV2 NUM-E-B-03-Installation Manual N7-AS355 NP-HV2 NUM-E-B-03- Maintenance Manual Supplement N8-AS355 NP-HV2 NUM-E-B-03.	The system does not replace standard maintenance records and pilotreporting. Any broadcasting must be done in accordance with Nationalregulations.The approval holder shall fulfillthe obligations of Part 21, Paragraph21A.109.Prior to installation of this modification it must be determined thatthe in...	27/02/2020	Active	10033288
10033290	DELTA ENGINEERING CORPORATION		FAA STC ST01662NY	B747-400	Modification of existing Mode S Transponders & TCAS by installation ofHoneywell/ACSS P/N 7517800-10004 ATDL Transponders & 4066010-910 TCAS inaccordance with Delta Engineering Master Drawing List 0107-05185-2059,Rev A, dated April 18,2003.Validation of FAA STC ST01662NY	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Maintenance Manual Supplement Doc. No. 0707-05223-2059, dated February12, 2003 or later revisions of the above listed documents approved byEASA in accordance with EASA ED Decision2004/04/CF (or subsequentrevisions of this decision).	This approval is for the replacement of the Transponder Units and TCAS.This approval does not include the transponder and TCAS system, wiring,trays, antennas, structural provisions, etc.	11/01/2011	Active	10033290
10033295 (EASA.IM.A.S.02690)	RANDIGO LLC	REV. 1	FAA STC SA02291AK	208B 208, 208B 208	Installation of Honeywell TPE331-12JR turbine engine and HartzellHC-B4TN-5QL/LT10890N(K) or HC-B4TN-5QL/LT10891N(K) propeller andassociated structure and equipment in accordance with FAA STC SA02291AK.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:14CFR Part 23 effective February 1, 1965, as amended by Amendments 23-1through 23-28.Additionally, 12 CFR Part 23 effectiv...	Aero Twin, Inc. Master Descriptive Data List 850-MDDL, issue 10, datedMay 14, 2012.For Cessna 208: FAA approved Airplane Flight Manual Supplement, Doc.No. 850-AFMS, Rev. C, FAA approved June 11, 2012, with Supplement 9-1for Flight Into Known Icing (FIKI), Rev. A, dated November 20, 2012.For Cessna9...	This modification is not compatible with:i. Cessna 208 serial numbers 20800001 through 20800013, 20800416,20800500 and greaterii. Cessna 208B serial numbers 208B1190, 208B1216, 208B2000 and greateriii. FAA STC SA01478WIb) This modificationhas been verified to be compatible with both theoriginal whe...	03/03/2021	Active	10033295

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033323	AEROLITE AG	REV. 2		429	EMS Equipment P/N 429020-501/-502The following modifications to the EMS Equipment P/N 429020-501 areincluded:- Introduction of Cargo Platform P/N 429022-502- Modification of Electrical Power System- Introduction of additional door light- Introduction of Stowage Net P/N 429045-501/503This STC revisio...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approvalThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For EMS Equipment P/N 429020-501:- Flight Manual-Supplement: FMS-429020-501, Rev. A- Airworthiness Limitations, AWL-429020-501, Rev. A, dated 19.02.2011For EMS Equipment P/N 429020-502:- Flight Manual-Supplement: FMS-429020-502, Rev. 0- Airworthiness Limitations, AWL-429020-502, Rev. 0, dated 19.02....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/03/2016	Active	10033323
10033384	LEES AVIONICS Ltd.		CAA UK RESPONSIBILITY	LEARJET 35, LEARJET 35A	Installation of single or dual Universal Avionics UNS-1Lor UNS-1LW FMS (Flight Management System)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalRefer to Certification Plan CP-1159, issue 1, and Compliance RecordCR-1159, issueThe requirements for environmental protection and the ass...	Refer to Master Documents List MDL-1159, issue 1or later revisions of the above listed documents approved by EASA	Refer to Flight Manual Change Sheet FCMS-1159, issue 1	17/12/2010	Active	10033384
10033395	SCANDINAVIAN AVIONICS DESIGN ApS	REV.1		CESSNA S550 CESSNA 550 CESSNA 500	GPS / Navigation / Communication, Dual Garmin GNS 430/530 AWinstallationThe installation includes GPS antenna and single marker beacon receiver(KMR 675 or 51Z6) installation	EASA TCDS IM.A.207The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate...	·,,Master Document List "2053445 DOC" Issue 3 from 20 Jan. 2011·,,Aircraft Flight Manual Supplement for GNS 430/530 AW,VHFCommunication Receiver, VOR/ILS Receiver / GPS Receiver "2053445-AM A"Issue 1 from 01 June 2010·,,Aircraft Flight Manual Supplement for Collins 51Z6 Marker BeaconReceiver "20534...	None	21/01/2011	Active	10033395
10033397	NASCO AIRCRAFT BRAKE, INC.		FAA STC ST02321LA	MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	FAA STC No. ST02321LA Validation "Installation and replacement of brakeComponents"	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.For parts not changed or not affected by the change refer to FAA TCDSA6WE; for parts changed or affected by the change since the reference...	Nasco MD80 Compliance check list FAA project ST13341LA-T; NascoConfiguration Control Drawing-Record of drawing changes Doc, NCC010Revision NC, dated 30 September 2010, Nasco Component Maintenance Manualcontaining Instruction for Continued Airworthiness (ICA), Doc. CMMMD8001, Revision IR, date 30 Sep...	Refer to FAA STC ST02321LA	18/01/2011	Active	10033397
10033410	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA3529NM	DHC-6-100, -200, -300	Cockpit Sun Visor installation in accordance with FAA STC SA3529NM	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rosen Drawing List Number RTO-00DL, Rev. A, dated June 29, 2010Rosen Sunvisor Systems Installation Instruction, Doc. 9041-0169-001,Rev. A, dated June 29, 2010or later revisions ofthe above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthi...	none	19/01/2011	Active	10033410

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033420	W-MOTOR SERVICE, s.r.o.	REV. 1		M 337, M 337A, M 337AK M 332, M 332A, M 332AK M 137A, M 137AZ 3. M 337, M 337A, M 337AK 2. M 332, M 332A, M 332AK 1. M 137A, M 137AZ	Prolongation of TBO for the M137, M332 and M337 engines in serviceaccording to the procedure No. WMS - OS/09/04 (Definition document)under the AP DOA W-MOTOR SERVICE organization No. M332, 137, 337/001	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.	Walter-Motor-Service procedure No.WMS-OS-09/04, Rev. 2, 27.10.2010Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system	None	26/09/2024	Active	10033420
10033430	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02647NY	ATR 72-212A ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102 ATR 42-320, ATR 42-500 ATR 42-200, ATR 42-300	Installation of Delta Engineering Synchro's and Sagem ED36 AFDAU withAPM (Aircraft Performance Monitor) EASA Validation of FAA STC ST02647NY - amended on 04th October 2013This STC installs Delta Engineering Synchro's in several areas forrecording control position data for the flight data recorder sys...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List, ref: 0101-06413-2166 Revision J,dated October 25th, 2013.Aircraft Flight Manual Supplement, ref: 0601-08709-2166, October 04th2013Instructions for continued airworthiness, ref: 0701-06417-2166 RevisionF,dated October 24th 2013.or later revisions of the above list...	1- The APM function, included in Sagem ED36 AFDAU, is advisory only2- Following the various configurations supported bythis STC, whetherthe Delta Engineering Synchro's are interfaces with the Sagem ED36AFDAU, whether the Delta EngineeringSynchro's must interface with theSagem ED 35 ADFAU component...	05/06/2014	Active	10033430
10033449	AIRBUS S.A.S.	REV. 1		A319-133	Airbus Corporate Jet Centre Modification CJ0615 - "VIP Interior - HNA"Revision due to update of AFM-S and MPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI G-4113 "ACJC Project Certification Basis".The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	-Modification Approval Sheet, ref.: CJ0615 Issue 5, dated 24th October2013-Airplane Flight Manual - AFM Supplement, ref.: FM-S MOD CJ0615, dated1st October 2013-Maintenance Planning Document - MPD Supplement, ref.: MPD-S MOD CJ0615,dated 1st October 2013or later revisions of the above listed documen...	This STC is limited to A319-133 MSN 4042Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The inst...	22/11/2013	Active	10033449
10033452	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	B757-200	Carriage of Horses & Grooms in Freighter a/c	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateFor changed areas these additional Special Conditions are part of thedefined Certification Basis,,D-01, Protection of Essential Systems,,D-02, Insta...	Master Document List, S21.MDL-0846, Initial Issue, 19/01/2011Airplane Flight Manual Supplement, S21.FMS-0071, Issue 2, 19/01/2011Instructions for Continued Airworthiness, S21.TEC-0286, Issue 1,17/12/2010or later revisions of the above listed documents approved by EASA	This design change is applicable to Boeing 757-200 aircraftconvertedunder Boeing's Special Freighter Programme, approved by the UK CAA underAirworthiness Approval Note AAN 27308 (acceptable to EASA under the EASAGrandfather provisions).	21/01/2011	Active	10033452
10033463	S-TEC CORPORATION		FAA STC SA8401SW-D	TB9, TB10, TB20, TB21, TB200	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-547 (28 Volt System)	The Certification Basis for the original product remains applicable tothis certificate/ approval.	1) Installation in accordance with both:- FAA Approved S-TEC Bulletin No. 647, dated 02-Nov-09, Revision 4- FAA Approved S-TEC Master Drawing List No. 92697, dated 02-Nov-09,Revision D2) Operation in accordance with:a) For Socata models TB9, TB 10, and TB 200 (Group Aerospatiale): FAAapproved Pilot...	Optional Autotrim System not eligible on Socata model TB 9,TB 10, andTB 200 (Group Aerospatiale)	24/01/2011	Active	10033463
10033485	ADAC LUFTFAHRT TECHNIK GmbH			EC135T2 (CPDS), EC135 T2+ EC135P2 (CPDS), EC135 P2+,	Installation of Dual Garmin GNS 430W into EC 135 with MEGHAS cockpitInstallation of two GNS430W linked with indication on the FCDSas definedin the Master Drawing List EC135-01 066-005-LIN and based on ALT MajorChange EC135-01066.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Flight Manual Supplement:-,,EC135-01066-025-MFS-00 Rev. 0orlater revisions of the above listed documents approved by EASA·,,EC135-01066-023-MMS Rev. 0 Instructions for Continued Airworthiness·,,EC135-01066-004-DIN Rev. 0 Installation Instructionsor later revisions of the above listed documents.	None	25/01/2011	Active	10033485

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033486	HAECO CABIN SOLUTIONS, LLC	REV. 1	FAA STC ST03143AT-D	747-400F 747-400, 747-400 (BCF),	Installation of a Rockwell Collins Aero H+ Satcom System inaccordancewith TIMCO Master Data List 04T089L01, Rev. IR, dated November 25, 2005or later FAA approved revision	The Certification Basis for the original product remains applicable tothis certificate/ approval	N.A.	None	04/02/2011	Active	10033486
10033488	B/E AEROSPACE, INC.		FAA STC ST14379LA-T	777-300, 777-300ER	Installation of B/E Aerospace Pantry Air Chiller P/N 470-1	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalSpecial ConditionCRI H-01 EWISThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable...	Master drawing List ECS470-42 revision A dated June 3, 2010Instruction for Continued Airworthiness ECS470-43 revision Cdated July9, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Not Applicable	25/01/2011	Active	10033488
10033490	HELIKOPTER AIR TRANSPORT GESELLSCHAm.b.H.	REV. 4		EC135 T2+, EC135 T3 EC135 T1, EC135 T2 EC135 P3, EC135 T1, EC135 T2 EC135 P2+, EC135 P3 EC135 P1, EC135 P2, EC135 P2+ EC135 P1, EC135 P2	Replacement of Onboard Talon System with improved IAOSI hook AS 21-17.Rev. 1: Modification of double hook beam and release mechanism.Rev. 2: Modification of the design of the Push-Pull Cables of theMechanical Release System to optimize itsperformance and flexibility.Rev. 3: Adds wiring & Installati...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-AFM Supplement 9.2-85-004 Revision 3 dated 04.05.2020-Engineering Order 85-004 R4 dated 22.08.2022-Instructions for Continued Airworthiness, Chapter 11 Instructions forContinued Airworthiness: "11.1 Daily Check" of EO 85-004 R4 dated22.08.2022 and "11.2 Intermediate Inspections" of EO 85-004 R4 dat...	Installation does not constitute operational approval.Approval of PCDS (Personal Carrying Device System) for external loadoperation must be granted by the competent authority.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and an...	06/05/2020	Active	10033490
10033501 (EASA.IM.A.S.03101)	CARLISLE INTERCONNECT TECHNOLOGIES	REV. 4	FAA STC ST02626CH	A321-272N/-272NX A321-253N/-253NX/-271N/-271NX A321-251N/-251NX/-252N/-252NX A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-216 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of ECS EZMount® mechanical mounting assemblieson lowerframes of cockpit sliding windowsRev. 3: Addition of “Neo” models to the applicability listRev. 4: Correction of models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 amdt 0: 25.29 (b), 25.301(a)(b), 25.303, 25.305 (a)(b), 25.307(a),25.561(b)(3)(c), 25.601, 25.603, 25.605(a), 25.609 (a)(...	Master Data List ECS-206919, Revision AA, dated August 11, 2020ICA supplement ECS-206923 revision E, dated August 05, 2014Configuration 1 AFM supplement ECS-206922 Revision B, dated August 31,2020Configuration 2 AFM supplement ECS-208318 Revision B, dated August 31,2020Configuration 3 AFM supplement...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The equipment for which these provisions are int...	05/01/2021	Active	10033501
10033551	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	737-300, -400, -500, -800	Introduction of Cockpit Door Surveillance and Cabin WitnessSystem	EASA TCDS IM.A.120The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate...	H4 Aerospace Modification Summary No. MOD H4A1356 Issue 2 dated 24January 2011.H4 AFMS No. H4AFMS024H4 ICA No. H4ADR585or later revisions of the above listed documents approved byEASA	None	01/02/2012	Active	10033551
10033558	BOMBARDIER AEROSPACE	REV. 1	TCCA STC SA10-109	CL-600-2B16	Dual Power for Electronic Flight Bag (EFB) - Challenger 604/605	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	-Transport Canada STC No. SA10-109 Issue 1 dated 22 December 2010.-ACS-NAI Ltd. Modification Data Summary Number G918000 Revision A dated30 May 2011 or later approved revision.-ACS-NAI Ltd. Airplane Flight Manual Supplement G918090 Revision A orlater approved revision.-Instructions for Continued Air...	The complete custom aircraft interior defined by EASA STC No. 10016019must be installed concurrently or as a pre-requisite.	11/08/2011	Active	10033558

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033580	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T2, EC135 T2+ EC135 T1, EC135 T1 (CPDS)	Installation of Spectrolab Nightsun XP on EC135 equipped with ECUKequipment pod. Equipment inspection and re-certification to close therequirement for AD No. 2010-0183R1.Note: Identical to STC with ref. 10032575, re-issued for administrativepurposes.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Maintenance Requirements Document MR/135787-001, Issue C, dated05.11.2010Design Report DR/135787-001, Issue E, dated 02.11.2010	None	16/11/2010	Active	10033580
10033582	S-TEC CORPORATION		FAA STC SA5210SW-D	H35, J35, K35, M35, N35, P35	Installation of S-TEC 40/50 Single and Two Axis Automatic FlightGuidance Systems, Model ST-188-40/50 (14V - System)	Design:Non-significant changeThe Certification Basis of theoriginal product remains applicable tothis changeEnvironmental Protection:The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	FAA approved S-TEC Bulletin No.288, dated 20-Jul-1983, Initial Issue, orlater approved revisionFAA approved S-TEC Master Drawing List No. 92216, dated 20-Jul-1983,Initial Issue, or later approved revisionFAA Approved Supplement to Pilot's Operating Handbook and/or FAAApproved Airplane Flight Manual0...	None	28/01/2011	Active	10033582
10033617	AIRFILM CAMERA SYSTEMS, INC		FAA STC SR02297LA	2. AB412 AND AB412EP 1. BELL 212, 412 AND 412EP	Nose Mount Utility Bracket	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	AF412NM-010 revision N/C dated 1 October 2009 - Master Drawing List;AF412NM-006 revision IR dated 25 May 2010 - Installation Instructions;AF412NM-007 revision N/C dated 25 May 2010 - Flight Manual Supplement;AF412NM-008 revision N/C dated 15 April 2010 - Instructions forContinued Airworthiness.	None	31/01/2011	Active	10033617
10033622	KUERZI AVIATION AG			AS 350 B2, AS 350 B3	G500H Avionic Retrofit (Option 1 & 2) Option 1Out:Original OEM installed-Airspeed Indicator-Gyro Horizon-Altimeter-Turn & Bank Indicator-Directional Gyro-Vertical Speed IndicatorIn:-Garmin G500H system including PFD/MFD GDU 620-Attitude heading Reference System GRS 77H-Air Data System GDC 74H-L3 Elec...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI A-01 - G500HAvionics Retrofit, Issue 3, 11 January 2011The certificatednoise and/ or emissions levels of the original productare un...	Flight Manual Supplement Doc. No.: FMS-201034169 Rev. Originalor later revisions of the above listed documents approvedby EASAMaster Document List Doc. No.: MDL-201034169 Rev. N/ CInstructions for Continued Airworthiness Doc. No.: ICA-201034169 Rev.N/C	None	31/01/2011	Active	10033622
10033638	AERODATA AG	REV. 1		HAWKER 800 (U125) BAE.125 SERIES 800A	Installation of Aerodata FIS (Flight Inspection System).TheFIS installation consists of non-essential sensor systems in thecabin and a camera system in the tail cone to enable calibrationmissions for navigation equipment.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Aerodata Master document list,MDL-A/ C-155, Rev. 2Operation in accordance with Aerodata Flight Manual Supplement, AFM-113,Rev. 1Continued Airworthiness in accordance with Aerodata Aircraft MaintenanceManual Supplement, AMM-1045, Rev 0or later revisions of the above lis...	none	25/02/2011	Active	10033638
10033641 (EASA.A.S.03896)	RUAG AEROSPACE SERVICES GmbH			EMB-135BJ	Modification 289A: Thrane & Thrane Aero SB Lite Satcom Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.Cert Basis per TCDS IM.A.032 plus:CRI F-29/03896 "WLAN"Voluntary compliance to CRIH-1 "EWIS"The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to...	Modification 289A "Thrane & Thrane Aero SB Lite Satcom Installation"Master Document List 289A-MDL Rev. D dtd. 26.01.11-AFM Supplement 289A-AFMS Rev. N/C dtd. 16.10.09-AMM Supplement with Airworthiness Limitations 289A-AMMS Rev. C dtd. 24.01.11or later revisions of the above listed documents approved...	None	01/02/2011	Active	10033641

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033659 (EASA.R.S.01507)	AERLYPER S.A.	REV. 1		EC135 P2, EC135 P2+	Installation of STAR SAFIRE HD Camera System & Digital TransmissionSystem	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalJAR 27 Amendment 3, dated 01/04/2002, for paragraphs 27.561 & 27.602JAR 27 Amendment 2, dated 01/05/2001, for paragraphs 27.610, 27.805 &2...	- Document: «Lista de Documentos y Planos», n°: 101499, Edition: 03,Date: 28-01-2011- Document: «Suplemento al Manual de Vuelo», n°: 101511, Edition: 00,Date: 28-01-2011- Document: «Instrucciones de Aeronavegabilidad Continuada», n°: 101512,Edition: 00, Date: 28-01-2011or later revisions of the abov...	None	02/03/2011	Active	10033659
10033667	AVIATION SUPPORT GmbH			MD900	Installation of an Equipment Rack	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-27 Amdt.2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original pr...	Master drawing list; MDL-ASE-90906 Rev0-1Compliance Report;CR-ASE-90906 Rev 0-1ICA; ICA-ASE-90906 Rev 0-2RFM Supplement; FMS-ASE-90906 Rev 0-2or later revisions of the above listed documents approved by EASA	None	02/02/2011	Active	10033667
10033670	AVIATION SUPPORT GmbH	REV. 2		AB206 A, AB206 B 206A, 206B	Installation of ALMA G2 system (Airborne Laser Methane Assessment) – GasDetection System as described in document PB-ASE-90902.The purpose of Revision 1 is to correct the identification of thereferenced documentation.Revision 2 is to correct a typo in the associated technicaldocumentation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27.25, CS 27.27, CS 27.29, CS 27.31, CS 27.601,CS 27.603, CS 27.605<(>,<)>CS 27.607, CS 27.609, CS 27.610,CS 27.611, CS 27.613, CS 27.629, CS27.771<(>,<)>CS 27.773, C...	FMS-ASE-90902 revision 0-2 dated 17 August 2015 – Flight ManualSupplement;ICA-ASE-90902 revision 0.5 dated 17 August 2015 – Instructions forContinued Airworthiness;or later revisions of the above listed documents approved by EASA.PB-ASE-90902 Rev 0-1 dated 17 August 2015 – Project DescriptionMDL-ASE...	With ALMA G2 system INSTALLED, Vne=100KIASWith ALMA G2 system RUNNING, VFR DAY ONLYWith the D-BOX installed on the LH AFT seat, the use of the AFT middleseat is prohibited for passenger transport.Prior to installation of this design changeit must be determined thatthe interrelationship between this...	18/08/2015	Active	10033670
10033691	LUFTHANSA TECHNIK AG	REV. 2		DHC-8-401, -402 DHC-8-301, -311, -314, -315 DHC-8-201, -202 DHC-8-102, -103, -106	Installation of non-electrical Floor Path Marking SystemDescription of change in rev. 1 was "Installation of PhotoluminecentEmergency Floor Path Marking System Guideline".This revision also changes the document structure, allowing theSupplemental Type Definition Document STD33-10/03M to replace theE...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Change 9 and FAR 25.1301(a)(4), amdt. 123The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original prod...	Installation must be in accordance with LHT Supplemental Type DefinitionDocument STDD33-10/03M Issue 01, Revision 04<(>,<)> dated 13 April 2011Operation must be in accordance withLHT AFM Supplement A-33-10/222-AFM,revision IR dated 03 February 2011Maintenance must be in accordance with LHT Instruct...	Not Applicable	17/01/2014	Active	10033691
10033697	SAAB AB	REV. 1		AS 355 N, AS 355 NP AS 355 F2, AS 355 N, AS 355 NP AS 355 F1, AS 355 F2 AS 355 E, AS 355 F, AS 355 F1 AS 355 E, AS 355 F	Installation of New TopEye Mission Box	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-27 Amendment 2The requirements for environmental protection and the associatedcertified noise and/ or emis...	TDM08-30-1-CP revision E dated 09 August 2010-Certification Plan;TDM08-30-3-RFMS-Flight Manual Supplement;TDM08-30-3-ICA revision B dated 10 May 2010 – Instruction for ContinuedAirworthinessOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/10/2023	Active	10033697

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033707	AERONAUTICAL ACCESSORIES, INC		FAA STC SH1281SO	206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	Maintenance Step.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	KR-154 revision S dated 10 November 2010 - Drawing List;AA-87036 revision R dated 4 April 2003 - Installation Instructions forPre-Flight Step/Handle on Bell 206A and B models;AA-87040 revision C dated 4 October 1999 - Installation Instructions forMaintenance Step on Bell 206A and B models;AA-87041 r...	None.	04/02/2011	Active	10033707
10033710	BOMBARDIER INC.		TCCA STC NO. SA04-113 ISSUE 1	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9385	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Transport Canada SoC reference C-10-0758 dated 02 February 2011.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionGB dated 28 January 2011.Instructions for Continued Airworthiness GC93850000-IFCA.or later revisions of the above...	Restricted to ASN 9385 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	04/02/2011	Active	10033710
10033724	BRISTOL AEROSPACE LTD.	REV. 1	STC SH10-4	429	Installation of Wire Strike Protection System.Revision 1: Administrative Revision to add details in associatedTechnicalDocumentation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EM106490 issue D dated 18 October 2010 - Modification Data Summary;PM-965-067 issue G dated 14 October 2010 - Instructions for ContinuedAirworthiness;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	09/05/2019	Active	10033724
10033738	LUFTHANSA TECHNIK AG	REV. 2		B747-400	Activation of ADS-B Out capability via 1090MHz Extended Squitter inaccordance with Lufthansa Supplemental Type Definition DocumentSTDD34-10/02M Issue 01, Rev 02, dated Feb. 10, 2011 or later approvedrevision.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Doc. No. A-00-10/225 Rev IR Airplane Flight Manual SupplementDoc. No. A-00-10/225-ICA Issue 1, Rev. IR Instructions forContinuedAirworthinessor later revisions of the above listed documents approved by EASA	none	17/02/2011	Active	10033738
10033754 (EASA.IM.A.S.03248)	ELECTRONIC CABLE SPECIALISTS, Inc.	REV. 1	FAA STC ST02708CH	MD-11	Installation of EZMount (TM) Arm mechanical mounting assemblies on lowerframe of cockpit sliding window in accordance with Electronic CableSpecialists Master Data List ECS-207476 Rev. A, dated March 4, 2009, orlater FAA approved revisions.Validation of FAA STC ST02708CH	Per FAA TCDS A22WE for parts not changed or affected by this changeThe certification basis for the parts changed or affected by this changesince the reference date of application,February 4, 2008 is shown onTCDS A22WE. In addition, the applicant has complied with 14CFR Part 25as amended by amendmen...	AFM Supplement as listed in Appendix A of ECS Master Data ListECS-207476 Rev. A	AFM Supplement as listed in Appendix A of Electronic Cable SpecialistsMaster Data List ECS-207476, Rev. A, dated March 4, 2009 or later FAAapproved revision, is required on board the modified aircraftThe equipment for which these provisions are intended is not part ofthis approval. Additional EASA a...	12/08/2013	Active	10033754
10033764	AIRBORNE TECHNOLOGIES GmbH	REV. 1		P.68TC "OBSERVER"	Change of cabin layout /For the installation of different mission equipment in a VulcanairP.68TC aircraft, the aircraftcabin has to be modified and provisions toaccommodate Mission Equipment have to be installed. This modificationincludesthe removal of three cabin seats. Repercussions on aircrafts...	Elected to comply: CS 23, Amdt. 2 and FAR 23, effective 1stFeb. 1965for 23.337, 23.341 and 23.561The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions leve...	Engineering Order ABVP68-EO-2500-01-03, Issue 3AFM Supplement ABVP68-AM-2500-01-02, Issue 2Interface Definition ABVP68-DE-2500-02-02, Issue 2Technical Order ABVP68-TO-2460-01-01, Issue 1or later revisions of the above listed documents approved by EASA	Limited to S/N 454, 456 and 459	04/01/2012	Active	10033764

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033789	TENENCIA Ltd.		CAA UK RESPONSIBILITY	F27 MK 050 & F27 MK 0502	Installation of a Single UNS-1Lw Universal Avionics Flight ManagementSystem.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan CP/TEN/ 644 issue 1Installation report and Statement of Compliance DF/ENG/014 Issue 7System Safety Assessment 387-01-0008 Revision BMaster Drawing List 288-00-0001 of 31 March 2009AFM Supplement TEN/FOKKER F27/002 Issue 1Additional supporting technical documentationor later revisio...	AFM Supplement TEN/ FOKKER F27/002 Issue 1	08/02/2011	Active	10033789
10033800	ACS-NAI Ltd.		TCCA STC NO.C-LSA11-040/D	BD700-1A11	Cabin Modifications for Wheelchair Access	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA SoC ref. C-10-1061 dated 08 February 2011TCCA STC No.C-LSA11-040/D Issue 1 dated 02 February 2011ACS-NAI Ltd. Modification Data Summary G950000 Revision NC or laterapprovedrevisionor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF...	Restricted to ASN 9373.Previous embodiment of EASA STC No. 10031088 (TCCA STC SA05-60).	09/02/2011	Active	10033800
10033802	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03282AT	737-600/-700/-800/-900	Installation of Dual Collins HFS-900 High Frequency (HF) communicationsystemRevision1: Transfer of EASA STC 10033802 from EMTEQ ENGINEERING to B/EAEROSPACE	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):H-01 “Enhanced Airworthiness Programm for Aeroplane Systems – ICA onEWIS” issue 2:The requirements for environmental protection and the associatedcert...	EMTEQ Master Data List (MDL) Document No. 2-36870-001 Revision D DatedJanuary 10, 2011EMTEQ Airplane Flight Manual Supplement (AFMS) Document No. 2-36870-849dated June 19, 2006or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequen...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/08/2015	Active	10033802
10033805	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	B300	Observer Training Platform Mod.-B300.	CS-23.B	Installation must be in accordance with Master Document List included inthe Design Change Statement DC-0166 Iss.1 dated21st January 2011 orlater Approved Revisions.Operation mustbe in accordance with Pilots Operating HandbookSupplement No. FRAH/FM/0120 Rev. 0: Dated 18th January 2011 or laterappr...	The approval is limited to the Aircraft Serial Numbers: FL-597<(>,<)>FL-618, FL-629 and FL-633.	09/02/2011	Active	10033805
10033818	AIR ALLIANCE GmbH			PA-42-1000	Installation of SAT antenna (Data-Link) into pressurized fuselage.	The Certification Basis of the original product and the followingadditional/ alternative airworthiness requirements areapplicable tothis change.For the areas affected by the change CS-23 has been elected to complywith where possible.The certificated noise and/ or emissions levels of the original pr...	EASA approved Master Document List, Doc. No. 2010_040_PA42 AAForm 2 Master Doc List, Revision 1, approved 10-Jan-2011Engineering Order, Doc. No. 2010_040_PA42_500, Rev. 1, released24-Nov-2010Instructions for continued Airworthiness, Doc. No. 2010_040_PA42_0507, Rev. 0, released 27-Sep-2010or later re...	None.	10/02/2011	Active	10033818

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033819 (EASA.IM.A.S.02736)	ROSEMOUNT AEROSPACE, Inc.	REV. 4	FAA ST02668CH	777F 777-300, 777-300ER 777-200, 777-200LR	Installation of Rosemount Aerospace EFB Systems.Rev. 4: adds three new configurations, Configurations M, N and P, andwould also revise certain aspects of previously approved ConfigurationsD and H	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS-25 Amdt 3 in case of applicable MDL configuration A and B for25.301(a)-(c); 25.303; 25.305(a)-(c);25.307(a); 25.337; 25....	- Master Data List, Rosemount Aerospace document No. D06402489, RevisionAW, dated 11 April 2025.AFMS:- Airplane Flight Manual Supplement, Rosemount Aerospace document No.D06425539, Revision B (configurations C and D).- Airplane Flight Manual Supplement, Rosemount Aerospace document No.D06426828, Rev...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.-Limitations as per ICA documents.-For Rosemount...	16/07/2025	Active	10033819
10033820	S-TEC CORPORATION		FAA STC SA09285AC-D	PA-31, PA-31-300, PA-31-325 PA-31-350	Installation of S-TEC 20/30 Single and Two Axis Automatic FlightGuidance Systems, Model ST-727-20/30 (28V - System)	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved S-TEC Bulletin No.827, Revision 4, dated 26-Apr-2001, orlater approved revisionFAA approved S-TEC Master Drawing List No. 921029, Revision D, dated26-Apr-2001, later approved revisionFAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891538, Revis...	This STC is also eligible on models PA-31 and PA-31-300 when modifiedper FAA STC SA970SO (350 H.P. Colemill Conversion)This STC is also eligible on model PA-31-325 when modified per FAA STCSA00048SE (Vortex Generator System)This STC is also eligible on models PA-31-350 when modified per FAA STCSA115...	10/02/2011	Active	10033820
10033826	AEROACOUSTICS AIRCRAFT SYSTEMS, INC		FAA STC SA01239SE	208	Fabrication and installation of AeroAcoustics Aircraft Systems (AAIS) Aircraft Payload Extender III (APE III) system in acc. with FAA STCSA01239SE.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AASI Master Drawing List No. AA1680, Rev. C, dated January 15, 2010AASI Installation and Maintenance Manual No. 1679, Rev. D, datedDecember 20, 2009AFMS-C208-25, "Landplane with PT6A-114 (600 SHP) engine", Revision C,dated December 9, 2010AFMS-C208-26, "Landplane with PT6A-114A (675 SHP) engine", Re...	This modification is limited to the following landplanes (serialnumbers) only:20800001 through 20800060 (eligible only if modified with Cessna KitSK-208-12)20800061 and upSpeed limits: Maneuvering Speed @ 8.362 lbs: 143 KIASCG Range: Takeoff and Flight +175.68 inches to +184.35 inches @ 8.362 lbMa...	10/02/2011	Active	10033826
10033827	AEROACOUSTICS AIRCRAFT SYSTEMS, INC		FAA STC SA01180SE	208	Fabrication and installation of AeroAcoustics Aircraft Systems (AAIS) Aircraft Payload Extender II (APE II) system in acc. with FAA STCSA01180SE.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AASI Master Drawing List No. AA1662, Rev. G, dated January 20, 2010AASI Installation and Maintenance Manual No. 1663, Rev. F, datedDecember 20, 2009AFMS-C208-19, "Landplane with PT6A-114 (600 SHP) engine", Revision B,dated December 9, 2010AFMS-C208-20, "Landplane with PT6A-114 (600 SHP) engine", Rev...	Additional limitation: Refer to original FAA STC SA01180SESerial Number: 20800001 through 20800060 (eligible only if modified with Cessna KitSK-208-12) 20800061 and upThis modification is also applicable to the following aircraft equippedwith Wipline Model 8000 amphibious floats in acc. with FAA STC S...	10/02/2011	Active	10033827
10033835 (EASA.A.S.03935)	DASSAULT FALCON SERVICE	REV. 1		FALCON 900EX	Falcon 900EX aircraft serial numbers 065 and 073 - CompletionDefinition.Revision 1 : to remove limitation on S/N 073 further to : - compliance of Passenger seat cushions (Qty 8 seats P/ N2524-014-184XX) with JAR 25.853 (b) (c), approved under minor changeDFS9557 Issue B, and - LH Divan cushion...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- DFS Change Approval Sheet DFS 9557-CAS Issue B dated 02ndJune 2017;- DFS Master Document List DFS-DE-17-FE-9557, Issue B dated 02 May 2017;- DFS Modification Sheet DFS 9557, Issue B dated 2nd May 2017;or later revisions of the above listed documents approved by EASA.	This EASA design change airworthiness approval is applicable only onFalcon 900EX aircraft serial numbers 065 and 073.Associated limitation: Non-commercial air transportation use for S/ N065.Prior to installation of this modification it mustbe determined thatthe interrelationship between this modific...	25/01/2018	Active	10033835

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033844	AIRBORNE TECHNOLOGIES GmbH	REV. 2		T182T	Camera Hatch Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.FAA Certification Basis 3A13; FAR 23 effective February 1, 1965, asamended y 23-1 through 23-6 except as otherwise defined in the TCDS.Howeverthe applicant elected to comply with CS-23 amendment 1.The r...	2058039-EO, Issue 2: ,,Engineering Order2058039-CA, Issue 1:,,Continuous Airworthiness Instructions2058039-MM, Issue 1:,,Maintenance Manualor later revisions of the above listed documents approved by EASA	none	24/05/2012	Active	10033844
10033847	JCB AERO SA			A320	Installation of Hi-Low Table for VIP cabin interior	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	·,,Master Drawing List, ref. doc. A320ALL01-MDL-01, Revision B, dated4th February 2011·,,Project Data List, ref. doc. A320ALL01-PDL-01, Revision A, dated 7thFebruary 2011·,,Declaration of Compliance for Project A320ALL01, dated 11th February2011or later revisions of the above listed documents approv...	none	14/02/2011	Active	10033847
10033865	SKYTRAC SYSTEMS LTD.		TCCA STC NO. SH10-24	EC 135 T2(CPDS),EC 135 T2+ EC 135 T1(CDS),EC 135 T1(CPDS) EC 135 P2(CPDS),EC 135 P2+ EC 135 P1(CDS),EC 135 P1(CPDS)	Sky Track ISAT AIRBORNE POSITION / COMMUNICATION UPGRADEThemodification upgrades an existing ISAT-100 Airborne Position / DataCommunicator system installation to an ISAT-200 system(This EASA approval validates the TCCA STC SH10-24, Issue 2)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Special Condition on Lithium Batteries as per project related EASA CRIF-01The requirements for environmental protection and the associate...	- Avionics Design Services LTD Master Drawing List MDL10033, Revision C,Issue 1, dated February 02, 2011- Avionics Design Services LTD Drawing List DL10033-3, Revision A, Issue1, dated February 02, 2011- Flight Manual Supplement FMS10033-3, Revision A, dated February 02,2011- Sky Track Systems Ltd.r...	none	15/02/2011	Active	10033865
10033870 (EASA.R.S.01568)	AIRBUS HELICOPTERS DEUTSCHLAND GmbH			EC 120 B	Installation on an EC120B helicopter of a ETSO-certified (ETSO C113)Moving Map system (MT VisionAir EPIII)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Flight Manual Supplement, SK-MIC-110-SUP-P-245 dated 1/10/2010or later revisions of the above listed documents approved by EASA-Declaration of Compliance, SK-MAC-106-DC-P-187 dated 4/10/2010-Compliance Report, SK-MIC-110-CRP-P-246A dated 30/9/2010	None	15/02/2011	Active	10033870
10033883	MOTORFLUG BADEN-BADEN GmbH			407	Installation of Antenna Mount on Tailboom	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	28107F103283-1001 revision 0 dated 25 May 2010 - Installation Manual28107F103283-070 1 revision 0 dated 25 May 2010 - Instructions forContinued Airworthiness28107F10328 3-0101 revision 0 dated 25 May 2010 - Compliance Program	none	16/02/2011	Active	10033883
10033889	BOMBARDIER AEROSPACE		TCCA STC NO. SA11-1 ISSUE 1	CL-600-2B16	Activation of Wireless Local Area Network Acces Point ICG NXT MailServer System	EASA.IM.A.023The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASAGeneric WLAN CRI No. F-01The requirements for environmentalprotection and the associatedcertificated noise and/ or emis...	TCCA STC No. SA11-1 Issue 1 dated 04 January 2011.ACS-NAI Ltd Modification Data Summary Number G975000 Revision N/C dated04 January 2011 or later approved revision.ACS-NAI Ltd Airplane Flight Manual Supplement G975090 Revision N/C orlater approved revision.ACS-NAI Ltd. Document G975070-ICA Revisionr...	Structural and electrical provisions must be installed in accordancewith EASA STC No. 10016019 (TCCA STC No. SA06-90)	16/02/2011	Active	10033889

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033895	AIRBUS HELICOPTERS, Inc.		FAA STC SR09094RC-D	EC 135 T2 (CPDS) EC 135 T2+ EC 135 T1 (CPDS) EC 135 T1 (CDS) EC 135 P2 (CPDS) EC 135 P2+ EC 135 P1 (CPDS) EC 135 P1 (CDS)	Installation of a collective activated tenth hourmeter in accordancewith AEC Drawing List 135A82-8006.This EASA STC is based on FAA STC SR9094RC-D.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AEC Drawing List 135A82-8006, Revision D, dated 03/18/98-Instructions for Continued Airworthiness 135MMS-006, dated 05 June2007or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	17/02/2011	Active	10033895
10033896	AIRCRAFT DESIGN CERTIFICATION GmbH	REV. 2		VENTUS CM	Steerable Tail Wheel	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Annex to the Flight Manual Ventus cM, issue 25 January 2011.Powered Sailplanes Maintenance manuals, Annex for Schempp- Hirth VentuscM; equipped with ADxC-DC-38-001 steerable tail wheel.Anhang zum Flughandbuch Ventus cM, Ausgabe 25 Januar 2011.Motorsegler Wartungshandbuch, Anhang für Schempp-Hirth Ve...	Ventus cM with Schempp-Hirth technical Note 825-6.	19/07/2018	Active	10033896
10033897	U.S. TECHNICAL CONSULTANTS, INC.		FAA STC ST02320LA	B767-200, -300, -300F, -400ER	Installation of Class 2 Electronic Flight Bag (EFB) provisions.	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	US Technical Master Drawing List (MDL), Document No. 4914-23-000,Revision C, 20/08/2010Aeroplane AFM Supplement, Document No. U10-0175, Revision NC, 27/10/2010Instructions for Continued Airworthiness, Document No.U10-0195, RevisionNC, 08/04/2010or later revisions of the above listed documents approv...	Any equipment that is connected to the electrical power provisionscertified by this STC must be tested in accordance with therequirementsof navAero Inc.'s Electrical and EnvironmentalSubstantiation for Lithium based battery in navAero t-bag C22 EFB SystemDocument No. E-1525-11-0325-00, revision C, 0...	17/02/2011	Active	10033897
10033913	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	Design Data for the Approval of a Honeywell KFD840 Primary FlightDisplay (PFD).	CS-23The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	Installation Manual IM. 00910 Revision CMaster Document ListMDL.00910 Revision AInstructions for Continued Airworthiness ICA.00910 Revision AFlight Manual Supplement FMS. 00910 Revision Aor later revisions of the above listed documents approved by EASA.	None	17/02/2011	Active	10033913
10033914 (EASA.IM.A.S.01234)	TELEDYNE CONTROLS, LLC	REV. 1	FAA STC ST01778LA	A310-304, -322, -324, -325 A310-203, -204, -221, -222 A300F4-605R, -622R A300C4-605 VARIANT F A300B4-620, -622R A300B4-601, -603, -605R A300B4-2C, -103, -203 A300B2K-3C A300B2-1A, -1C, -203	Installation of Wireless Ground Link - Quick Access Recorder (WQAR)This STC consists in the installation of the WQAR onAirbusA300/A310/A300-600 series.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, Ref: MDL2243800-31X, dated 14 March 2005Instruction for Continued Airworthiness, Ref: ICA2243800-A1-1, dated 23February 2005.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	This STC is applicable to the following WQAR p/n (2243800-xxx):- 2243800-21- 2243800-31- 2243800-33- 2243800-35- 2243800-37- 2243800-39- 2243800-42- 2243800-43- 2243800-44- 2243800-62- 2243800-63- 2243800-64- 2243800-71- 2243800-73- 2243800-75- 2243800-77- 2243800-79- 2243800-81- 2234572-001Prior to...	12/04/2016	Active	10033914

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033937	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		3202,3206,3207,3212,3216,3217 3109,3110,3112,3116,3201 3101,3102,3103,3107,3108	Dual/Single Installation of Garmin GNS430(A)W I GNS530(A)W and optionalInstallation of Marker Receiver Honeywell (Bendix/King) KMR675	The Certification Basis for the original product and the followingadditional oralternative airworthiness requirements are applicable to thiscertificate/ approval.EASA CS-23, Amendment 2 (elected to comply by the applicant, notrequired by 21A.101)The requirements for environmental protection and thec...	Instructions for Installation: ,,ASR-2010-061-IFI-10-00, Rev. 0Flight Manual Supplement: ,,ASR-2010-061-FMS-05.1-00, Rev. 0ASR-2010-061-FMS-O5.2-00, Rev. 0Instructions for Continued Airworthiness: ,,ASR-2010-061-ICA-11.1-00, Rev. 0ASR-2010-061-ICA-11.2-00, Rev. 0or later revisions of the above liste...	none	24/02/2011	Active	10033937
10033942	DART AEROSPACE USA, Inc.		FAA STC SR00646SE	2. AS355 F2, AS355 N, AS355 NP 2. AS355 E, AS355 F, AS355 F1 1. AS350 B, AS350 B1, AS350 B2 1. AS350 B3, AS350 BA, AS350 D	D350-636 Skidtube InstallationsNote: This STC supersedes CAA Approval Notes 28081 and 28082 and addsmodels AS355N and NP to applicability.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-MDL-D350-636 revision N dated 1 September 2010 - Master Document List;-IIN-D350-636 revision H dated 26 July 2010 - Installation Instructions;-ICA-D350-636 revision 1 dated 26 July 2010 - Instructions for ContinuedAirworthiness.	None	21/02/2011	Active	10033942
10033945	BOGGI S.R.L.			AS 365 N3	Kit P/N MDS365-P002-00 ,External rear view mirror.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Boggi s.r.l. Rotorcraft Flight Manual Supplement ,Owner Manual,section 4, Edition 2,Rev. 0 dtd 12/01/2011 or later revisions of theabove listed document approved by EASA.- Boggis.r.l Master Drawing List Kit MDS365-P-002-00 Technical ReportPart 1B, edition 1<(>,<)> dtd. 18/10/2007- Installation in...	- as defined in -Boggi s.r.l. Rotorcraft Flight Manual Supplement,Owner Manual,section 4, Edition 2,Rev. 0 dtd 12/01/2011	21/02/2011	Active	10033945
10033946	ROEDER PRAEZISION GMBH	REV. 1		421A/421B/421C/425 402C/411/411A/414/414A/421 401/401A/401B/402/402A/402B	Installation of a Traffic Advisory System Avidyne TAS610/620.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Engineering Order C421-NY-08167-05, Rev. 1.Maintenance Procedures C421-NY-08167-07, Rev. 1.Flight Manual Supplement C421-NY-08167-07, Rev. 1or later revisions of the above listed documents approved by EASA.	A compatible Multi Function Display (MFD) must have been alreadyinstalled.Prior to installation of this modification itmust be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airwor...	15/11/2017	Active	10033946
10033951	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			FR182	STC 3005/10 rev 0 - Modification d'installation des équipements radio etBRNAV avec couplage au pilote automatique.	The Certification Basis for the original product remains applicable tothis certificate/ approval.CS 23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Supplément Manuel de Vol SEAM/SMV/3005/10 Revision 0 dated 22 April 2010or later revisions of the above listed documents approved by EASA.	Limitation to Cessna FR182 equipped with ASPEN EFD 1000 andNAVOMATIC300A.	22/02/2011	Active	10033951
10033960	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		B200/ B300	Provisions for and installation of a SLAR and a Homer antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Engineering Order, Doc. No. 2063299-EO<(>,<)> Issue 2, dated 19 April2018<(>,<)> or later approved issue.Aircraft Flight Manual Supplement. Doc No 2063299-AM B, Issue 1, dated14 November 2017, or later approved issue.Instruction for Continued Airworthiness, Doc No. 2063299-CA B, Issue 1,dated 15 Nov...	The installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previ...	02/05/2018	Active	10033960

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033970	ROEDER PRAEZISION GMBH	REV. 3		421A/421B/421C/425 402C/411/411A/414/414A/ 421 401/401A/401B/402/402A/ 402B	Single installation of Garmin GNS 430 (A) W/GNS 530 (A)W and optionalinstallation of Roll Steering Converter GDC31.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Engineering Order C421-NY-08168-05, Rev. 2.Flight Manual Supplement: C421-NY-08168-08a, Rev. 2; C421-NY-08168-08b,Rev. 1.Maintenance Procedures: C421-NY-08168-07, Rev. 1or later revisions of the above listed documents approved by EASA.	An independent COMM or NAV/ DME or ADF/DME must have been alreadyinstalled.Prior to installation of this modification itmust be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airwor...	15/11/2017	Active	10033970
10033973	CRANE AEROSPACE & ELECTRONICS		FAA STC ST02316LA	LEARJET 60	Installation of Tire Pressure SensorFAA STC ST02316LA (Dateof issuance: September 28, 2010)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Refer to Master Data List 83-216-01, rev. Kor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisionsofthis decision).	None	23/02/2011	Active	10033973
10033974	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 4		A109E, A109S, AW109SP A109E, A109S	Flight Data Monitoring and Transmitting System HELICOM V1, HELICOM V2NUM and HELICOM V2+ NUM.Revision 1: Change in system name (Safetyplane became HELICOM V1), newV2 version and associated documentation.Revision 2: Introduction of new components, new locations for antennasand extends eligibility toR...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- RFMS N11-A109E_S HV2 HV2+NUM version E, edition A, rev 01dated 10thJune 2016.- Master Document List N10-A109E_S HV2 HV2+NUM version E, edition A, rev03 dated 14th June 2016.- Installation Manuals N7-A109E HVI version E, edition A, rev 06andN7-A109E_S HV2 HV2+NUM version E, edition B, rev 02.- Mai...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/10/2020	Active	10033974
10033979 (2004-3846)	POLICE AVIATION SERVICES Ltd.	REV. 1	CAA UK RESPONSIBILITY	EC 635 T2+ EC 135 T2 (CPDS) EC 135 T2+ EC 135 T1 (CPDS) EC 135 T1 (CDS) EC 135 P2 (CPDS) EC 135 P2+ EC 135 P1 (CPDS) EC 135 P1 (CDS)	Incubator Installation EC 135Transfer of EASA STC No 2004 3846 (dated 16/04/2004) from PAS Ltd toBond Aviation Group Ltd	The Certification Basis for the original product remains applicable tothis certificate. The requirements for environmental protection and theassociated certificated noise and/ or emissions levels of the originalproduct are unchanged and remain applicable to this certificate.	CAA.21NE2.00089; EASA Approval number 2004-03846; dated 16 April 2004(for PAS modification PAS/MOD/388)		28/02/2010	Active	10033979
10033988	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04225AT-D	GV-SP	Aircraft Serial No 5302 completion and cabin interior installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gulfstream Aerospace Corporation MasterDrawing List No. GC522046210, Revision A, dated January 24, 2011, orlater approved revisions.Operation to bein accordance with Gulfstream Flight Manual SupplementGC52204M061 , Original Release, dated January 25, 2011, or later ap...	GV-SP Serial No. 5302 Only	24/02/2011	Active	10033988
10033989	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04221AT-D	GV-SP	Aircraft Serial No 5294 completion and cabin interior installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gulfstream Aerospace Corporation MasterDrawing List No. GC522046203, Revision A, dated December 7, 2010, orlater approved revisions.Operation to bein accordance with Gulfstream Flight Manual SupplementGC52204M059 , Original Release, dated December 9, 2010, or later ap...	GV-SP Serial No. 5294 Only	04/03/2011	Active	10033989

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10033995	BOMBARDIER INC.		TCCA STC SA04-113, ISSUE 1	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9380.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada SoC reference C-10-0842 dated 17 February 2011.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionGE dated 09 February 2011.Instructions for ContinuedAirworthiness GC93800000-IFCA.or later revisions of the abov...	Restricted to ASN 9380 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	24/02/2011	Active	10033995
10033998	BOMBARDIER INC.	REV. 1	TCCA STC SA05-60	BD-700-1A11	Aft Lavatory Backsplash replacementInstallation, Complete Custom Aircraft Interior - ASN 9405	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certific...	TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.Aero Consulting Services Ltd Configuration Definition List E025000Revision EU dated 03 June 2011.Bombardier Aerospace Aeroplane Flight Manual Supplement G-FM25004501Revision N/C or later approved revision.GC94050000-IFCA Instructions for Continued Airw...	Restricted to ASN 9405.	29/06/2011	Active	10033998
10034024	airplus engineering GmbH	REV. 1		EASA APPROVED MODEL LIST	Dual Installation of Garmin GNS 430 (A) W/GNS 530 (A)W (TAWS).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CS-23, Amendment 2 (elected to comply by the applicant, notrequired by 21A.101)The requirements for environmental protection and the...	Engineering Work Order ,,,,,,EW-1126-340000, Rev.1Flight Manual Supplement: ,,,,,,PO-1126-340000, Rev.1Maintenance Manual Supplement:,,,,MM-1126-340000, Rev.1or later revisions ofthe above listed documents approved by EASA.	None	16/02/2021	Active	10034024
10034031 (EASA.IM.R.S.01426)	APICAL INDUSTRIES, Inc.		FAA SR00471LA	600N	Emergency Floats	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Document List MD600-1, Revision B, dated September 30, 1997,plus:- Report AI600N-3, Rev A, dated 03/31/09- Report AI600N-1, Rev D, dated 03/31/09- Rotorcraft Flight manual Supplement FMS-600(1) Rev C- Instructions for Continued Airworthiness ICA600-1, Rev 1, dated11/03/09or later revisions of...	None	01/03/2011	Active	10034031
10034052 (EASA.A.S.03621)	DOA AESGLOBAL LIMITED	REV. 2		757-200	Introduction of IFE System Circuit Breaker, Relays and Wiring.Rev 2: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateFor changed areas the defined certification basis is CS25 Amendment 4CRI H-01 ICA on for EWISThe requirements for environmental protection and the a...	AES Master Data List, AES-757-1072MDL, issue 3, 16/09/2010or later revisions of the above listed documents approved by EASA	None	27/04/2021	Active	10034052
10034074	RUAG AEROSPACE SERVICES GmbH			525A 525	Installation of High Speed SATCOM system with on-board WLANInterface.	The Certification Basis for the original product and the followingadditional oralternative airworthiness requirements are applicable to thiscertificate/ approval.CRI F-101 (MOC) "WLAN Implementation in Cessna 525, 525A"The requirements forenvironmental protection and the associatedcertificated nois...	Engineering Work Order: RUAG Doc.No. 355A-EO, Rev.: -FlightManual Supplement: RUAG Doc.No. 355A-AFMS, Rev.: -Maintenance Manual Supplement: RUAG Doc.No. 355A-AMMS, Rev.: -or later revisions of the above listed documents approved by EASA.	STC limited to S/N 525-0516The WLAN clients (Handsets, Laptops, etc) are not covered by this STC.The usage of these components is requiring operational approval.	04/03/2011	Active	10034074

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034082	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9394	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionGI dated 01 March 2011.Instructions for Continued Airworthiness GC93940000-IFCA.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decis...	Restricted to ASN 9394 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	04/03/2011	Active	10034082
10034086	EUROCOPTER UK Ltd.	REV. 1	CAA UK RESPONSIBILITY	EC 130 B4	Installation of Sagem Cockpit Display System MHL/130/1245 and revisionto Eurocopter UK EC130B4 Supplement No. 1	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Eurocopter UK EC130B4 RFM Supplement No. 1 Issue 2 dtd 04.03.2011 - GPSGarmin GNS 530WEurocopter UK EC130B4 RFM Supplement No. 3 Issue 1 dtd 04.03.2011 -Sagem Integrated Cockpit Display System (ICDS)or later revisions of the above listed documents approved by EASAEurocopter UK Declaration of complia...	Prerequisite changes:MHL/ 130/1246,,,,,,TWX670 Weather detection systemMHL/ 130/1070,,,,,,KRA405B Radio AltimeterMHL/ 130//1069,,,,,,Avidyne TAS620 Traffic Advisory SystemMHL/ 130/952,,,,,,Replacement of GNS430 with GNS530WSTC EASA.IM.R.S. 01061,,Installation of Sagem Autopilot EC130	04/03/2011	Active	10034086
10034098	C.A. FLOR FLORDELIS		FAA STC ST01786LA	B737-300, -400, -500 SERIES B737-100, -200, -200C SERIES	Upgrade Flight Data Recorder System Parameters	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Master Drawing List document No. FF-050209MDL, Rev. B dtd. 2.April 2005or later revisions of the above listed documentsapproved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Not Applicable	08/03/2011	Active	10034098
10034100	APICAL INDUSTRIES, Inc.	REV. 1	FAA STC SR02291LA	BELL 407	Cable Cutters KitThe Bell 407 Cable Cutter kit provides a means of protecting thehelicopter during a wire strike by providing the capability to cut acable or wire before catastrophic damage occurs.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MD407-41, Revision A, dated 23 November 2010;- Instructions for Continued Airworthiness ICA407-41, Revision N/C,dated 8 February 2010;- Installation Instructions II407-41 revision A dated 22 November 2010.or later revisions to the above.	None.	21/03/2011	Active	10034100
10034112	ACC COLUMBIA Jet Service GmbH	REV. 1		CL-600-2B16/ CL-600-2B19	Installation of a combined IRIDIUM-GPS Antenna as provisionof anoptional Sky Tracking System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. ACC Master Document List ACC-CRJ200-09016 Revision 0 dated 24February 2011.2. ACC ICA CRJ200-09016-810-MM Revision 0dated 29 November 2010or later revisions of the above listed documents approved by EASA.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/10/2018	Active	10034112
10034119	ROEDER PRAEZISION GMBH	REV. 1		PIPER PA-31-350 (CHIEFTAIN)	Provision for Camera Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation in accordance with Master Record List Document No. 71335MR 5300 10 01B- Operation in accordance with Supplement to Pilot Operating HandbookPOH, Document No. 71335 AM 5300 10 01B- Maintenance in accordance with Instructions for ContinuedAirworthiness No. 71335 CA 5300 10 01Bor later re...	This STC revision includes only the structural changes. It does notinclude any installation of equipment (e.g. Laser scanner, computer,cameras)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed chan...	10/08/2018	Active	10034119

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034125	DASSAULT FALCON SERVICE		FAA STC ST02863CH	MF50, FALCON 50EX	Stretchers installation for medical evacuation.Provide the ability to install in the aircraft one or two stretchers forair ambulance operations.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet DFS5697-CAS Issue B dated 25 January 2011DFS Modification Sheet DFS5697, Issue B dated 25 January 2011or later revisions of the above listed documents approved by EASA.	This STC does not cover the qualification of the installed stretcher. Itis to be used in conjunction with EASA STC covering the validation ofFAA STC ST02863CH.This modification does not cover the use of any auxiliary medicalequipment to beused in conjunction with the installed stretchers.This modif...	09/03/2011	Active	10034125
10034127 (EASA.A.S.03836)	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	B737-800	Introduction of Interior with 56 Recaro Business class seats andassociated systems(Revison of STC EASA.A.S. 03836 to remove EWIS Limitation)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalTGM/25/10 and TGL17The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this cer...	- Modification Summary Sheet: H4A1165 Issue 2.- Instructions for Continued Airworthiness: H4ADR441 Issue 2.or later revisions of the above listed documents approved by EASA	- The STC is limited to MSN 33016 (YJ935) and MSN 33021 (YJ936).- Changes to MMEL or MEL are not covered under the STC approval andrequire an additional approval, if deemed necessary.	09/03/2011	Active	10034127
10034128	AERO MEDICAL PRODUCTS MFG. Inc.		FAA STC ST02863CH	MYSTÈRE FALCON 50 (MF50)	Aircraft Medical stretcher for MF 50 aircraftFAA STC ST02863CH	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeromedical Products doc. "Compliance Check List Falcon 50 - projectnumber ST744CH-T" Revision 6 dated 02/03/2011Aeromedical Products Mfg., Inc. Drawing List Report 007 Rev 0 dated22/12/2010.FAA approved Airplane Flight Manual Supplement dated 28.06.2010 andAircraft Maintenance Manual Supplements da...	This STC does not constitute an approval for installation.Compliance with minimum following requirements below need to bedemonstrated through a design approval for installation ineach aircraftmodel to be equipped with this medical stretcher assembly part:§ 25.561 / § 25.785 / § 25.791 / § 25.803/ §...	09/03/2011	Active	10034128
10034129	KAWAK AVIATION TECHNOLOGIES, INC.	REV. 1	FAA STC SR01561SE	KAMAN K-1200	Title: Auxiliary Hydraulic System, K-Max K1200 Helicopter Model 36300,DWG 36300, REV B, 25th June 2005Description: Auxiliary hydraulic power source provides hydraulic powerfor external implements used in fire fighting, logging, and agriculturaloperation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Approval of Rotorcraft Flight Manual Supplement:FAA Approved Rotorcraft Flight Manual Supplement for the Kaman ModelK-1200 Helicopter, KATI-FM-632, Revision A, FAA-approved on 17th May2007or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CFt...	None	21/03/2011	Active	10034129
10034165	SABENA TECHNICS BGC			F2000	FALCON 2000 S/N 226 INTERIOR MATERIAL CHANGESChange consists in refurbishing certain panels- Windows Panels & Valance Panels (lower and upper)- Glass Carbon 250/56%/G874 panels.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI D-119 Flammability testing of aircraft cabin interior usingsurrogate panelsThe requirements for environmental protection and the assoc...	Aeroconseil Master Data List doc. N° 4322-01-A-2103-R00 dated March 11th2011or later revisions of the above listed documents approved by EASA	Restricted to S/N 226	14/03/2011	Active	10034165
10034166	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	B757-200	Installation of a Crew Galley in the G1A Position on a FreighterConversion a/c	The Certification Basis for the original product remains applicable tothis certificateThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval	AIM Aviation (Henshalls) STC Definition Document, DD 1189, Issue New, 04/02/2011.Instructions for Continued Airworthiness, ICA/PR/7002, Rev New, Feb2011.or later revisions of the above listed documents approved by EASA	None	14/03/2011	Active	10034166

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034187	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A330-300	Virgin Atlantic Airways (VAA) A330-300 EIS Cabin Reconfiguration (59W / 255Y).This STC reconfigures the cabin layout from 48 W class seat / 265 Yclass seat to 59 W class seat / 255Y class seat, with associatedadaptations.Rev.1: Transfer ofSTC from SR Technics Switzerland to groWINGEngineering Partn...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI D-3323-001 :Special Condition applicable to the installation of theAmSafe Aviation Inflatable Restraint (AAIR)CRI F-3302-001 : Speci...	SR Technics Master Document List, ref : S.OSMD.000001-MDL,deated 14March 2011or later revisions of the above listed documents approved by EASA	1-,,This STC must be implemented together with EASA STC ref: 10031808Rev 01 (and associated Approved Model List), or later revisions approvedby EASA.	20/04/2021	Active	10034187
10034192	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9391	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionGH dated 22 February 2011.Instructions for Continued Airworthiness GC93910000-IFCA.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED De...	Restricted to ASN 9391 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).	15/03/2011	Active	10034192
10034209	DANSK FLY ELEKTRONIK ApS			B200 KING AIR	Installation of Garmin DUAL GPS 400. GPS 1 is linked to the autopilotsystem. Ref. DFE-DO-0401-PS-00 Product Specification.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 23 Amendment 1The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	Design Package DFE-DO-0401, including DFE-DD-0401–AFMS-00 Flight ManualSupplement Garmin GPS-400 and DFE-DD-0401-ICA-00Instructions forContinued Airworthiness.or later revisions of the above listed documents approved by EASA	None	16/03/2011	Active	10034209
10034210	DANSK FLY ELEKTRONIK ApS			B200 KING AIR	Installation of Bendix/Kings KGP 560 EGPWS system with Avidyne EX500display. Ref. DFE-DO-0400-PS-00 Product Specification.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 23 Amendment 1The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	Design Package DFE-DO-0400, including DFE-DD-0400 – AFMS1-00FlightManual Supplement Avidyne EX-500, DFE-DD-0400 – AFMS2-00 Flight ManualSupplement KP560 EGPWS and DFE-DD-0400-ICA-00 Instructions for ContinuedAirworthiness.or later revisionsof the above listed documents approved by EASA	None	16/03/2011	Active	10034210
10034211	AERO-DYNE REPAIR SERVICES LTD.	REV. 1	TCCA STC SH08-41	BELL 407	External MGT and Torque Indicating System Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FMS403101 revision IR dated 4 April 2008 - Flight Manual Supplement;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision)-EO403101 revision 1 dated 8 October 2008 - Engineering Order (includesInstall...	None	02/08/2011	Active	10034211

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034212	BOMBARDIER AEROSPACE		TCCA STC SA10-93	CL-600-2B16	WLAN Activation & Incorporation of Aircell Components	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. SA10-93 Issue 1 dated 27 October 2010.ACS-NAI Ltd. Modification Data Summary Number G904000 Revision N/C orlater approved revision.ACS-NAI Ltd. Airplane Flight Manual Supplement G904090 Revision N/C orlater approved revision.Instructions for Continued Airworthiness, refer to...	Structural and electrical provisions must be installed in accordancewith EASA STC No. 10016019 (TCCA STC No. SA06-90) concurrently or as apre-requisite.	16/03/2011	Active	10034212
10034213	AEROSPACE TECHNOLOGIES GROUP, INC.		FAA STC ST03910AT	A320-231, -232, -233 A320-215, -216 A320-111, -211, -212, -214	Installation of Passenger Cabin electrically powered WindowShades	The Certification Basis for the original product remains applicable tothis certificate/ approval	FAA STC ST03910AT-Aerospace Technologies Group (ATG) Engineering Drawing ListLTS-EDL-48-001, Rev. G dtd. 2.Nov 2010- Aerospace Technologies Group Document PRD-CAW-48-001, Rev. E dtd. 28.Feb 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 200...	None	16/03/2011	Active	10034213
10034237	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		1900D	Double GARMIN GPS400W Installation for B-RNAV and P-RNAV and RNPApproach LNAV procedures, according to modification No BCA 121.Revision 1 adding the coupling to Rockwell Collins FYD-65 H flightdirector.	The Certification Basis for the original product remains applicable tothis certificate.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	AFM Supplement No. BCA-121-06 revision 1 dated 24/04/2012;AMM Supplement No. BCA-121-05 revision 0 dated 23/12/2010;Master Drawing List No. BCA-121-00 revision 1 dated 24/04/2012;or later revisions of the above listed documents approved byEASA.	Installation limited to Beech 1900D equipped with Rockwell CollinsAPC-65H autopilot or FYD-65 H flight director and EFIS Rockwell CollinsDPU 84, upgraded for GPS approach through Rockwell Collins SB 77 (523-0805196) and SB 81 (523-0805046).	15/06/2012	Active	10034237
10034238	BUSINESS AND COMMUTER AIRCRAFT			1900C, 1900D	BCA 120 revision 0 - 28-230 volts inverter (s) Installation on Beech 1900Series.	The Certification Basis for the original product remains applicable tothis certificate.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Airplane Flight Manual supplement BCA120-A revision 0 dated09 March2011Airplane Flight Manual supplement BCA120-B revision 0 dated 09 March2011or later revisions of the above listed documents approved by EASA.	Not applicable	17/03/2011	Active	10034238
10034242 (EASA.A.S.03722)	FOKKER TECHNIEK B.V.	REV. 2		A320-232	AIRBUS A320-232 – VIP conversion.Revision 1: update of applicable MMEL supplement, approved as OSD-MMEL.Revision 2: Transfer of STC from Fokker Services B.V. (EASA. 21J.059) toFokker Techniek B.V. (EASA. 21J.667)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25 Change 11CRI C-01 Large Display Monitors.CRI D-01 Isolated Compartments.CRI D-02 Installation of interior doors.CRI D-03 Crew Rest Compartment.CRI D-04 Heat Release...	- A320-CAI-CRR-0001 issue 3, approval date 17th March 2011.- A320-CAI-AFM-S-APPROVAL issue 1, dated 15th March 2011.- A320-CAI-MMEL-S-APPROVAL revision 3, dated 16th February 2017.- ICA Supplement document: SE-712 issue 2, dated 18th February 2011;or later revisions of the above listed document(s) a...	Refer to limitations section of the approved AFM supplement:A320-CAI-AFM-S_APPROVAL issue 1, dated 15th March 2011.The aircraft type, model and manufacturer serial number for which thischange is applicable is: Airbus A320-232 with Manufacturer Serial Number1868.Prior to installation of this change/r...	05/12/2019	Active	10034242

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034246	HONEYWELL INTERNATIONAL INC.		FAA STC SR02114NY-D	EC135 T2(CPDS), EC135 T2+ EC135 P2(CPDS), EC135 P2+	Installation of a Honeywell Model 15175 VXP SystemThe Honeywell Model 15175 VXP System is a Health and Usage MonitoringSystem that monitors vibration characteristics of the aircraft toprovide data to aid aircraft maintenance. The information provided bythe system is supplementary in nature and doesm...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Keystone Helicopter Installation Drawing List IDL01152, revision B-Honeywell Master Drawing List 159-08340-0001, revision -- Instructions for Continued Airworthiness: - Helicopter Instruction for Continued Airworthiness, HoneywellChadwick Model 15175 VCP System Installed in Eurocopter Model EC13...	None.	28/03/2011	Active	10034246
10034248	AERODATA AG	REV. 3		B200	Midlife Mission System Upgrade AD-MS-0110 (Installation of two L bandantennas for Horizon Satphone reception; Installation of additional rackwith Horizon Satphone receiver; Modification of existing equipmentconsole, workstation and cable looms with additional components andreplacement of obsolete co...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDL-A/C-157, Rev. 17Flight Manual Supplement AFM-116, Rev. 8Instructions for Continued Airworthiness AMM-1060, Rev. 10or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Only applicable to B200 aircraft S/N BB-2016 and BB-2018Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product...	16/02/2024	Active	10034248
10034252	BINDER MOTORENBAU GmbH			ASH 25 E	Conversion from hand starter to electric starter.Umbau Handstarter auf Elektrostarter.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC "ASH 25 E E-Starter", issue 27.01.2011 included drawings no. 1-9Ergänzende Musterprüfung "ASH 25 E E-Starter", Ausgabe 27.01.2011einschliesslich Zeichnungen 1-9Addition of the Flight Manual, on STC "Retrofit Electric starter for thepowered sailplane ASH 25 E"Addition of the Maintenance Manual, on...	None.	21/03/2011	Active	10034252
10034285	AVIONITEC AG	REV. 1		PA-46-310P	Avionics RetrofitRemoved Equipment:-,,Dual KX 165 NAV/COM System-,,WX 1000 Stormscope System-,,Argus 5000 Moving Map-,,KMA 24 Audio Panel-,,PM 2000 IntercomNew installed Equipment:-,,GNS 530W NAV/ COM/GPS System 1-,,GNS 430W NAV/ COM/GPS System 2-,,GDC 31 GPS Steering Converter-,,KN 63 DME System-,,...	FAR 23,, Amdt: 25 (tick one of the boxes below if applicable)The Certification Basis for the original product remains applicable tothis certificate/ approval.Derogation to latest amendment (Part 21A.101): Do not materiallycontribute to safety.	- Master Document List, Doc. No. PI01470-017, Rev. 0, 17.02.2011- Declaration of Compliance, Doc. No. PI01470-60, Rev. 0, 17.02.2011- ICA, Doc. No. PI01470-015, Rev. 0, 17.02.2011- AFMS Dual GNS 530W/430W, Doc. No. PI01470-011, Rev. 0, 17.02.2011- AFMS Avidyne TAS 610, Doc. No. PI01470-012, Rev, 0,-...	S/N: HB-PJW	25/03/2011	Active	10034285
10034286 (EASA.A.S.03832)	STEINBEIS GmbH & Co. KGFUER TECHNOLOGIETRANSFER			LS 6 & LS 6-A	STC: "Winglet Retrofit" / "Nachrüstung mit Winglets"	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalJAR-22.375 from amendment 22/90/1 (for the winglets) of the JAE 22Change 4	- STC "Winglet Retrofit" / "Nachrüstung mit Winglets" EASA.A.S.03832- Supplement to the flight manual of the sailplane LS6 / LS6-a withretrofitted winglets "LS6-wl"- Ergänzung desFlughandbuchs für das Segelflugzeug LS6 / LS6-a mitnachgerüsteten Winglets "LS6-wl"- Supplement to the maintenance manua...	None	23/03/2011	Active	10034286
10034322	LUFTHANSA TECHNIK AG			A330-343	Thai Airways A330-300 - Seat exchange and electrical adaptionThis STC installs 263 Y class seats, with associated electricaladaptations.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCf. TCDS EASA.A.004CRI F-4302-004: IFE and ISPSSThe requirements for environmental protection and the associatedcertificated noise and/ or...	Supplemental Type Definition Document, ref: STDD00-10/29M Issue 01,dated 17 March 2011or later revisions of the above listed documents approved by EASA	None	24/03/2011	Active	10034322

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034324	POLICE AVIATION SERVICES Ltd.		CAA UK RESPONSIBILITY	MD902 CONFIG. P&W 206&207	Aircraft Role Configuration	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-27 Amdt.2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original p...	RFM Supplement; FMS/ 592-002 Rev A.or later revisions of theabove listed documents approved by EASABuild standard; PAS/ 592-100-07.Compliance Report; DR/592-001 Rev C.ICA; MSS/592-008 Rev A.	none	25/03/2011	Active	10034324
10034337	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	Navigation/Communications Upgrade.	The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List MDL-1208 Issue 1Change Statement CS1208 Issue 1Instructions for Continued Airworthiness ICA-1208 Issue1Flight Manual Supplement AFMS-1208-01 Issue 1Flight ManualSupplement AFMS-1208-02 Issue 1Flight Manual Supplement AFMS-1208-03 Issue 1or later revisions of the above listed docum...	None	25/03/2011	Active	10034337
10034340	DART AEROSPACE Ltd.		TCCA STC SH10-49	429	Installation of UltraPaws.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS27/29 Change 2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	MDL-D429-793 revision A dated 27 October 2010 - Master Document List;IIN-D429-793 revision B dated 25 October 2010 - InstallationInstructions;ICA-D429-793 revision 0 dated 19 October 2010 - Instructions forContinued Airworthiness.	None.	25/03/2011	Active	10034340
10034368	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	B737-400	Installation of a two-class seating arrangement	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Modification Summary Sheet and Declaration of Compliance Mod H4A1381issue 1 dated 14/03/2011or later revisions of theabove listed documents approved by EASA	Not Applicable	29/03/2011	Active	10034368
10034376	ARCHEION HOLDINGS, L.L.C.		FAA STC ST03529AT	2. B757-300 1. B757-200	Installation of an Avionica satLINK Communication Management System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateFor changed areas the certification basis is CS 25 amendment 2< (>,<)>25.301, 25.303, 25.305, 25.307, 25.561, 25.1301, 25.1209, 25.1351,25.1353, 25.1...	Archeion Holdings LLC Master Drawing List doc. N ° 27005-MDLrevision Gdated 18th Aug. 2010AFM Supplement, 072950-503, Revision C, 28th march 2011ICA 27005-ICA, revision F, 25th June 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (o...	None	30/03/2011	Active	10034376
10034382	airplus engineering GmbH	REV. 1		2. 58P, 58PA, 58TC, 58TCA 1. 58, 58A, G58	Dual Installation of Garmin GNS430(A) W / GNS530(A)W(TAWS)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CS-23, Amendment 2 (elected to comply by the applicant, notrequired by 21A.101)The requirements for environmental protection and the...	Engineering Work Order: EW-1173-000000, Rev. 1Flight ManualSupplement: PO-1173-000000, Rev. 1Maintenance Manual Supplement: MM-1173-000000, Rev. 1or later revisions of the above listed documents approved by EASA	None	18/02/2021	Active	10034382

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034392	KUERZI AVIATION AG			MYSTÈRE-FALCON 50	FMS upgradeUpdate of the existing UNS-1k to UNS-1LW. Installation of a second FMS.Upgrade of the existing Collins VIR-31 1/2 and DME-41 1/2 to VIR-32and DME-42 so that ARINC429 can be used to interface with the dual FMS.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document/Drawing List doc N° MDL-201034519 Rev A dated30/03/2011Master Package List doc N° MPL-201034519 Rev N/C dated 30/03/2011Aircraft Flight Manual Supplement doc N° FMS-201034519 Rev 0 dated 28March 2011.Instructions for Continued Airworthiness, doc N° ICA-201034519 Rev N/Cdated 10 Marc...	Restricted to MF50 S/N 183.	31/03/2011	Active	10034392
10034394	HARTZELL PROPELLER LLC		FAA STC SA10551SC	58, 58A, G58	Installation of Hartzell PHC-J3YF-2UF/ FFC7391D(B, K) propellers	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the certificated noiseand/ or emissions levels.	FAA approved Drawing No. 20002-0000, Rev. A, dated 20-Apr-2006,FAA approved Airplane Flight Manual Supplement AFMS20002-1, Rev. IR,dated 06-Jul-2006, is required for Baron 58, 58A, and G58 airplanes,serial number TH-1389, TH-1396 and afterInstructions for Continued Airworthiness, Doc. No. 20002-30,d...	Only aircraft equipped with a Teledyne Continental IO-550-Cengine areeligible for this STC.	31/03/2011	Active	10034394
10034408	AVIATION ENGINEERING AS			AS 350 B2 & AS 350 B3	Installation of Electromagnetic Ground Ice Thickness Sensor	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR 27 at amendments as specified in Aviation Engineering AS COMPLIANCECHECK LIST doc. No. 2587-02-323, rev. 0 dtd 08.01.2011 - applicable...	Aviation Engineering AS Flight Manual Supplement AS350B2, B3 PostModification Eurocopter SBT 25.00.62 - doc. No. 2587-02-353, rev. 0 dtd21.01.2011or later revisions of the above listed documents approved by EASAAviation Engineering AS Master Drawing List - doc. No. 2587-02-324, rev. 0 dtd 14.01.2011...	AS350B2 and AS350B3 post mod Eurocopter SBT 25.00.62	01/04/2011	Active	10034408
10034421	SHADIN AVIONICS	REV. 1	FAA STC SE578GL	2. 250-C47B, 250-C47M 2. 250-C30P, 250-C40B 2. 250-C30G/2, 250-C30M 2. 250-C28B, 250-C28C 1. 250-C300/A1	Installation of Shadin fuel flow transducer in the fuel line between thefuel control unit (FCU) and the fuel injector. Addition to the EASAApproved Model List (AML) 10034421 of the Rolls-Royce Corporation enginemodel 250-C300/A1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC SE578GL-Application letter "Request for EASA STC Major Change Level 1" from Mr.Brad Jacobson (Shadin Avionics)to Ms. Khailaa Hosny (FAA), dated May10th, 2017	None	12/06/2017	Active	10034421
10034434	MT-PROPELLER ENTWICKLUNG GmbH	REV. 2	LBA STC (EMZ) SA0786 ISSUE 3	PA-46-310P	1) Installation of MTV-14-D/190-17 on PA-46-310P2) Installation of MTV-14-D/ 195-30a on PA-46-310P3) Installation of MTV-14-D/195-30a on PA-46-310P equipped with TCMTSIO-550-C i.a.w. FAA STC SA00380AT4) Installation of MTV-14-D/195-30b on PA-46-310P5) Installation of MTV-14-D/195-30b on PA-46-310P eq...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23 includingAmendment 34 (not required by 21A.101, elected tocomply by the applicant)This certificate/ approval involves a change to...	For installation 1 and 2:- "Anhang zum Flughandbuch Nr. E-512", Issue 30.09.1996- "Umrüstanweisung No E-511" Issue 30.09.1996For installation 3:- "Anhang zum Flughandbuch Nr. E-566", Issue 22.09.1997- "Umrüstanweisung No. E-565", Issue 22.09.1997For installation 4 and 5:- Airplane Flight Manual Supp...	None	25/05/2011	Active	10034434

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034435	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1	LBA STC (EMZ) SA0626 ISSUE 4	PA-46-350P, PA-46R-350T	1) Installation of MTV-14-B/190-172) Installation of MTV-14-B/195-30a3) Installation of MTV-14-B/195-30bFor installation 3 optional reduction of take-off propeller speed to2400 rpm is included	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23 includingAmendment 34 (not required by 21A.101, elected tocomply by the applicant)This certificate/ approval involves a change to...	For installation 1:- "Anhang zum Flughandbuch Nr. E-466", Issue 01.06.1995- Umrüstanweisung No. E 467" Issue 01.06.1995For installation 1 and 2:- "Anhang zum Flughandbuch Nr. E-466", Issue 20.02.1998- "Umrüstanweisung No. E-467", Issue 20.02.1998For installation 3:- Airplane Flight Manual Supplement...	None	07/04/2011	Active	10034435
10034437	JET AVIATION AG, BASEL			A319-100	GSM Securaplane Antenna Installation	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS"The requirements for envir...	- Master Data List ref. doc. BA31953001-001, Rev. C< (>,<)> dated 30thMarch 2011- Certification Plan ref. doc. BA31953001, Rev. A, dated 31st March 2011- Certification Compliance Sheet, ref. doc. BA31953001-102-01, Rev. A,dated 29th March 2011- Declaration of Compliance Project BA31953001, dated 30th...	None	05/04/2011	Active	10034437
10034446	TENENCIA Ltd.		CAA UK RESPONSIBILITY	B737-700, -800, -900 B737-300, -400, -500, -600	Cockpit Door Surveillance System	Certification Basis as per EASA TCDS IM.A.080 Issue 3, 26thOctober 2010plus:The applicant elected to comply with JAR 25 at change 15 for all models.In addition, CRI H1 issue 2 dated 23/02/2011 on 'Enhanced AirworthinessProgramme for Aeroplane Systems - ICA on EWIS' applies.The requirements for envi...	- Modification TEN 660 B737 Series Cockpit Door Surveillance Systemissue 2 dated 25 February 2011- Report TEN 660/1 Certification Compliance Report B737 Series CockpitDoor Surveillance System issue 1 dated 4 February 2011- Certification Plan CP/TEN/ 660 issue 1 B737 Series Cockpit DoorSurveillance Sy...	Not applicable	05/04/2011	Active	10034446
10034447	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC	REV. 1	CAA UK RESPONSIBILITY	B737-700	Cabin certification for aircraft use in Commercial operations	The Certification Basis for the original product is unchanged and remainapplicable to this certificateThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate	- Master Data List JN314-002 ADC17 Issue 2 dated 4/04/2011-AFM supplement JN314-002 ADC29 Issue 1	Refer to AFM supplement JN314-002 ADC29 Issue 1	12/04/2011	Active	10034447
10034457	SHADIN AVIONICS		FAA STC SH582GL	BELL 407 BELL 206B, B-1, L, L-1, L-3	Installation of Digital Fuel Flow Meter.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	4045 revision E dated 15 December 2010 - Installation Instructions forBell 206 Models;4119 revision C dated 15 December2010 - Installation Instructions forBell 407.	None.	08/04/2011	Active	10034457
10034472	TRIUMPH INSULATION SYSTEMS, L.L.C.	REV. 1	FAA STC ST02013LA	B767-200	Insulation Blanket Installation	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	Mexmil Company's Index List, Report Number B2000-3 RevisionA 22/07/2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	11/04/2011	Active	10034472

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034473	CALIFORNIA SHOCK TRAUMA AIR RESCUE (CALSTAR)		FAA STC SR02160LA	BO 105 LS A-3	Engine Upgrade:Removal of two (2) Rolls-Royce engine models250-C28C and installing two(2) Rolls-Royce engine models 250-C30P in accordance with FAA STCSR02160LA, dated March 11, 2011.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- CALSTAR FAA approved Rotorcraft Flight Manual Supplement,CAL204,Revisi on I/R, dated July 30, 2008or later revisions of the above listed documents approved by EASA.- CALSTAR Master Drawing List CAL201, Revision B, dated May 16, 2008- Installation of (2) Rolls-Royce 250-C30P Engines, Calstar 203-IC...	None.	11/04/2011	Active	10034473
10034482	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBIL ITY	SEE EASA APPROVED MODEL LIST	Design Data for the Approval of a Honeywell KFD840 Primary FlightDisplay (PFD).	CS-23The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of theoriginal product areunchanged and remain applicable to thiscertificate/ approval.	Installation Manual IM. 01510 Revision AMaster Document ListMDL.01510 Revision BInstructions for Continued Airworthiness ICA.01510 Revision AFlight Manual Supplement FMS. 01510 Revision Aor later revisions of the above listed documents approved by EASA.	None.	07/04/2011	Active	10034482
10034483	ROEDER PRAEZISION GMBH	REV. 1		560XL	Installation of HID/LED LDG/REC/TAXI light.Replacement of existing conventional LDG/REC/TAXI lights by low powerHID/LEDlights.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List to project C560XL-NY-1170, Rev. 3 from07 April2011.ICA C560XL-NY-1170-07, Rev. 1 from 07 April 2011or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	15/11/2017	Active	10034483
10034509	REGENT AEROSPACE CORPORATION		FAA STC ST02274LA	B777-222	Interior modifications in accordance with Regent Aerospace CorporationMaster Data List MDL-4100, Revision E, dated November 25, 2009. FAA STCST02274LA refers.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Regent Aerospace Corporation MDL-4100, Revision E Regent AerospaceCorporation CMM 25-21-01, Revision 4or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Limited to B777-222 aircraft serial number 30214 only	08/04/2011	Active	10034509
10034531	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBIL ITY	SEE EASA APPROVED MODEL LIST	Installation of Garmin G500 EFIS PFD/ ND.	CS-23 Amendment 1The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List MDL-1211 Issue 1Change Statement CS1211-01Issue 1Instructions for Continued Airworthiness ICA-1211-01Issue 1Flight Manual Supplement AFMS-1211-01 Issue 1or later revisions of the above listed documents approved by EASA.	None.	11/04/2011	Active	10034531
10034544	AIR SERVICE CENTER S.R.L.	REV. 1		182 SERIES	Installation of Vaccine Dispersal Kit.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement & Maintenance Manual Supplement for Air Service CenterKit ASC182-P001-00, included in Doc. ASC182-P001-00-Owm-01or later revisions of the above listed documents approved by EASA.	None.	11/05/2011	Active	10034544

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034547	AIR SERVICE CENTER S.R.L.	REV. 1		AS 350 B3	Installation of Vaccine Dispersal Kit.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement & Maintenance Manual Supplement for Air Service CenterKit ASC350-P003-00, included in Doc. ASC350-P003-00-Owm-01or later revisions of the above listed documents approved by EASA.	None.	11/05/2011	Active	10034547
10034553 (EASA.A.S.03845)	AIRBUS S.A.S.	REV. 1		A319-115	Airbus Corporate Jet Centre Modification CJ0500 Issue 3 - VIP Interior -"ORION"Revision due to update of AFM-S and MPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI G-4112 "ACJC Project Certification Basis.Special Condition(s): CRI H-01 - ICA on EWISThe requirements for environmental protection and the asso...	-,,Modification Approval Sheet ref: MAS CJ0500 Issue 3 "TOPMODIFICATIONORION" dated 24th October 2013;-,,Modification Approval Sheet ref: MAS CJ0526 "CONVERSION PRIVATE /PUBLIC"-,,AFM Supplement ref: FM-S MOD CJ0500 dated 1st October 2013-,,MPD Supplement ref: MPD-S MOD CJ0500 dated 1st October 201...	This STC is limited to A319-115 MSN 3994Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	25/10/2013	Active	10034553
10034584	BOMBARDIER INC.		TCCA STC NO. SA05-60	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9408	EASA TCDS No. IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certifi...	TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.Aero Consulting Services Ltd Configuration Definition List E025000Revision ER dated 24 March 2011.Bombardier Aerospace Aeroplane Flight Manual Supplement G-FM25004501Revision N/ C.GC94080000-IFCA Instructions for Continued Airworthiness.or later revisio...	Restricted to ASN 9408.	13/04/2011	Active	10034584
10034588	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	747-200, -300	Installation of a CabinVu-123 Cockpit Door Monitoring System and aFlightVu Witness Cabin Surveillance System in accordance with H4Aerospace Modification Summary document nr. H4A1333 Rev. 1, dated 18 052010 or later approved revision.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H1 Enhanced Airworthiness Programme for Aeroplane Systems -ICA onEWIS	H4AFMS022 Flight Manual SupplementH4ADR548 Instructions forContinued Airworthinessor later revisions of the above listed documents approved by EASA	None	13/04/2011	Active	10034588
10034590	AVIONITEC AG			M20K	Avionics RetrofitRemoved: ,,- King KX 165 NAV/COM with KingKI 206 CDI<(>,<)>- King KR 87 ADF with King KI 229 Indicator- Garmin GNS530 NAV/COM/GPSInstalled: ,,- Garmin 530W NAV/COM/GPS- Garmin 430W NAV/COM/GPS with GI 106A IndicatorVertically guided RNAV (GNSS) approaches to LNAV/VNAV or LPV minima...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List: No. PI91407-017, date 11.04.2011Airplane Flight Manual Supplement: No PI91407-11, date 11.02.2010Instruction for continued airworthiness: No. PI91407-015, date11.02.2010or later revisions of the above listed documentsapproved by EASA.	S/N: 25-1170 HB-DHG	13/04/2011	Active	10034590
10034601	AVIONIK STRAUBING ENTWICKLUNGS GmbH			T210F, G, H, J, K, L, M, N, R P210N, R 210K, L, M, N, R 210A, B, C, D, E, F, G, H, J 210, 210-5, -5A	Dual/Single Installation of Garmin GNS430(A)W / GNS530(A)W.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CS-23, Arndt. 2 (elected to comply by the applicant, not requiredby 21A.101) The requirements for environmental protection and the as...	Instructions for Installation: ASR-2010-067-IFI-10-00, Rev.00Flight Manual Supplement: ASR-2010-067-FMS-05-00, Rev. 00Instructions for Continued Airworthiness: ASR-2010-067-ICA-11-00, Rev.00or later revisions of the above listed documentsapproved by EASA.	None.	14/04/2011	Active	10034601

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034622	BUSINESS AND COMMUTER AIRCRAFT			BEECH 1900D	BCA 85 rev 3 - Full VIP Cabin Installation Beech 1900D	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	None	None	18/04/2011	Active	10034622
10034623	airplus engineering GmbH	REV. 1		114, 114A, 114B, 114TC 112, 112B, 112TC, 112TCA	Dual installation of Garmin GNS430(A)W/ GNS530(A)W(TAWS)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CS-23, Amendment 2 (elected to comply by the applicant, notrequired by 21A.101).The requirements for environmental protection and th...	Engineering Work Order: EW-1162-000000, Rev. 1Flight ManualSupplement: PO-1162-000000, Rev. 1Maintenance Manual Supplement: MM-1162-000000, Rev. 1or later revisions of the above listed documents approved by EASA	None	16/02/2021	Active	10034623
10034628 (EASA.A.S.03924)	AEROTEC - T. UHL GMBH & CO. KG	REV. 2		206H, T206H	Sky Diving Kit for Cessna 206HInstallation of components torelease sky divers.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Pilot's Operating Handbook Supplement, Doc. No. PO-206H-530001;Installation and Continuing Airworthiness Instructions, Doc. No.MM-206H-530001;or later revisions of the above listed documents approved by EASA.	None	27/08/2012	Active	10034628
10034631	AIRBORNE TECHNOLOGIES GmbH	REV. 3		P2006T	STC-AT-003, Provisions for surveillance configurationFor standard analogue instruments equipped aircraft:Installation of a camera hatch, electric doors, and a 28V mission powersystem and installation of an electric camera lift (Step 1 & 2) Reason for Revision 1:Addition of Garmin G950 equipped aircra...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Depending on aircraft instrument panel configuration (analogueinstruments or Garmin G950) and extend of modification one or more ofthe following documents are required:Installed in accordance with "Provisions for surveillanceconfiguration", Doc. No. STC-AT-003-Rev2, Rev. 10, dated 23.01.2013 and"Ins...	The installation of steps 1, 3, 5, or 7 of this STC must becarried outwhile production of the aircraft at the facilities of the airplanemanufacturer. Conversions from step 1 or 3to step 5 or 7 of this STCcan either be performed while production of the aircraft at thefacilities of the airplane manu...	24/03/2020	Active	10034631
10034638 (EASA.R.S.01356)	BRISTOW HELICOPTERS LIMITED	REV. 1	CAA UK RESPONSIBILITY	S-76C	Qualification of the Garmin GNS-530 Series GPS for En-routeNavigationand Non-precision approaches.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS29 Amendment 2applicable to the change.The requirements for environmentalprotection and the associatedcertificated noise and/ or emis...	Bristow Helicopters Limited Sikorsky S76 Flight Manual Supplement No17,Issue 3.or later revisions of the above listed documents approved by EASA.Modification MOD/ S76/34.5635, Issue 5, dated 21 December 2011.Certification Plan BHL/S76.4153<(>,<)> Issue d, dated 23 August 2011.	None.	29/03/2012	Active	10034638
10034641	2 EXCEL DESIGN LIMITED	REV. 5	CAA UK RESPONSIBILITY	PA-31	Introduction of Chin Mount and re-located Pitot tubes.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List S21.MDL-0825 Issue 10- Flight ManualSupplement S21.FMS-0072 Issue 5- Compliance Record S21.COMP-0825 Issue 5- Instructions for Continuing Airworthiness S21.TEC-0305 Issue 3or later revisions of the above listed documents approved by EASA	Flight Manual Supplement S21.FMS-0072 Issue 5The installation and subsequent operation of a sensor turret requires aseparate approval.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change...	25/08/2017	Active	10034641

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034642	LETH & ASSOCIATES, LLC	REV. 1	FAA STC ST01857SE	757-200	Maximum zero fuel weight increase	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List, Leth & Associates document No. OL0226, Revision NC<(>,<) > dated 19 June 2008.- Airplane Flight Manual Supplement, Leth & Associates document No.OL0224()<(>,<)> Revision NC, dated 15 June 2008.or later revisions of the above listed documents approved by EASA inaccordance with EAS...	This approval may only be applied to aircraft which have been convertedunder the EASA validated Precision Conversions, LLC, STC NumberST01529SE.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed des...	29/04/2015	Active	10034642
10034643 (EASA.R.S.01019)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		AS 365N3	Adaption of a FLIR ULTRA 4000 system installation provisions for a FLIRULTRA FORCE II. This modification is a minor change of the STC FLIRULTRA 4000 - 365N3 REF. AHSE-50300 of ASTEC HELICOPTER SERVICES AS,keeping the supporting structure and the electrical provisions for FLIRULTRA 4000.Rev. 1: Trans...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airworthiness Document CMA034-AAA E1 ROEngineering BulletinCMA034-BI E1 ROMaintenance and Installation/ UninstallationInstructions CMA034-MID E1RODrawings ZW-4003-01 A HELICSA, ZW-2010-01 H, ZW-2009-01 H2 & VCR FOR LEOIIAFM Supplement CMA034-AFMS E1 ROor later revisions of the above listed documen...	FLIR ULTRA 4000 must be previously fitted according to the STC FUR ULTRA4000 - 365N3 REF. AHSE-50300 of ASTEC HELICOPTER SERVICES ASPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ ore...	01/02/2019	Active	10034643
10034649	JET AVIATION AG, BASEL			MF900 (EXCEPTED F900C)	NZ2000 6.1 upgrade with CD820 CDU replacement.Existing dualor triple Honeywell NZ2000 Flight Management System isupgraded as follows:- NCU NZ2000 FMS 1&2 version NZ5.2 or later is replaced with versionNZ6.1- CD800/ CD810 1&2 CDU replaced with CD820.No change in sensors and capabilities.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List Doc. No. BF90034623-001 Rev. B dated 01.02.2011Instructions for Continued Airworthiness Doc. No. BF90034623-150-01dated 20.12.2010Airplane Flight Manual Supplement Doc. No. BF90034623-201-01 Rev. IRdated 17.03.2011or laterrevisions of the above listed documents approved by EASA.	As per AFMS Doc. No. BF90034623-201-01 Rev. IR dated 17.03.2011.	18/04/2011	Active	10034649
10034657	HELIKOPTER AIR TRANSPORT GmbH			EC135 T2	Dual GNS430W Installation in Autopilot helicopter	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFMS 34-002, Revision 0or later revisions of the above listed documents approved by EASAEngineering Order EO 34-002, Revision 0, including referenced drawingsand Appendix A and BInstallation Manual EO 34-002CMM 34-002 Maintenance Instructions	The installation is limited to Aircraft Serial Numbers 0220and 0221	18/04/2011	Active	10034657
10034668	AEROTEC & CONCEPT	REV. 1		C-212-DD (C212-300) C-212-CC (C-212-200)	MOD 0921: EGPWS installationThis revision extends the applicability to add C-212-CC (C-212-200) MSN139.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain a...	MASTER DATA LIST: AE0921MDL Rev. 10 Dated 22. Sept. 2016ForMSN 387:-SUPPLEMENT AU MANUEL DE MAINTENANCE: AE0921 IPMN REV 0 dated 09. Oct. 2009-SUPPLEMENT AU MANUEL DE VOL: AE0921 SMV REV 0 dated 20. Apr. 2011For MSN 139:- AIRCRAFT FLIGHT MANUAL SUPPLEMENT: AE0921AFMS_2 REV 0 dated 22. Jul.2016- INSTRU...	This STC is limited to MSN 387 and MSN 139Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	26/10/2016	Active	10034668

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034669	RUECKER AEROSPACE GmbH			328-300	Modification to certificated LOPA	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Declaration of Compliance of Ruecker Aerospace EntwicklungsbetriebEASA. 21J.296 dated 18.04.2011	none	19/04/2011	Active	10034669
10034675	AEROTEC & CONCEPT			C90A	Installation d'une antenne SATCOM iridium - dossier aerotec1082rev1	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 23 303, 305, 307, 365, 571, 573, 603, 605, 607, 609The certificated noiseand/ or emissions levels of the original productare unchange...	none	none	19/04/2011	Active	10034675
10034682	OGMA, INDUSTRIA AERONAUTICA DEPORTUGAL, S.A.			EMB-135BJ	Change Number 1086.07 - "Installation of coffee maker & associated watertank"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Change approval sheet: CAS-A1.50C-1086.07-25.00-001 dated14Apr2011- Change Dossier: CD-A1.50C-1086.07-25.00-001 Rev.A dated 14Apr2011- Aircraft Maintenance Manual Supplement: MS-A1.50C-1086.07-00.00-002initial issue, dated 23Nov2010.or later revisions of the above listed documents approved by EAS...	none	19/04/2011	Active	10034682
10034690 (EASA.A.S.03608)	AIRBUS DEFENCE AND SPACE S.A.	REV. 21		A330-243	A330 MRTT FSTA Modification STC1Rev. 1: Deletion of a previous limitation on the occupation of medicalstretchers.Rev. 2: Introduction of the role change capability. Therefore, it ispossible for an aircraft to move from the military register (INTATechnical Certificate configuration) to the civil regi...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.0853 InitialIssue for affected areas by change DCV1086-E.This certificate/approval involves a changed...	- “Conversion Definition A330MRTT FSTA” document ref. ME-FU-DT-110145,issue A- ALS Repository “A330 FSTA EASA STC1 Airworthiness Limitation Section”,document DT-FU-C00-0019, issueC- ALS Part 1 Supplement “A330 FSTA Safe-Life AirworthinessLimitationItems Supplement for EASA STC1”, document DT-FU-C0...	This approval includes the possibility for aircraft and aircraft parttransfer from military operation(INTA Technical Certificate configuration) to civil operation (thisSTC´s configuration).For aircraft transfer from military to civil operation: - the conditionsand transfer rules as defined in ALS Pa...	27/02/2025	Active	10034690
10034699	AERONAUTICAL ACCESSORIES, INC		FAA STC SR09536RC-D	429	Installation of Health and Usage Monitoring System (HUMS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-AA-09040 revision 0 dated 9 November 2010 - Flight Manual Supplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)-AA-09033 revision D dated 26 October 2010 - Master Document List-AA-09041 rev...	The HUMS kit is installed on a non-required/non-hazardous basis. Theutilization of the HUMS kit for maintenance credit is limited to: 1)main rotor track and balance; 2) tail rotordynamic balance; and 3) frahm vibration absorber tuning. HUMS data may not be used for usagehealth or condition - based ma...	20/04/2011	Active	10034699

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034703	ACS-NAI Ltd.	REV. 1	TCCA STC SA07-40	PC-12/45, PC-12/47, PC-12/47E	Installation Utility DoorExisting Cargo door modified to incorporate a utility door (990 mm highby 635 mm wide)	FAR 23The Certification Basis for the original product remains applicable tothis certificate/ approval.	Flight manual supplement Doc. No. F195090;Modification datasummary Doc. No. F195000;Maintenance manual supplement Doc.No.E550070-MMS;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision).	none	28/11/2012	Active	10034703
10034706 (EASA.R.S.00470)	AIR AMBULANCE TECHNOLOGY GmbH	REV.2		AS 350 B, AS 350 B1, AS 350 BA, EC 130 B4 AS 350 B2, AS 350 B3,	Installation of Air Ambulance Equipment (removable stretcher)	The Certification Basis (CB) for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:JAR 27 firstissue application to the modification (for AS 350 models)CS27 amdt. 2 applicable to the modification (for EC 130 model)...	For AS 350 models:Flight Manual AS350 Supplement, Air Ambulance Equipment P/ N350-25-24-1000, FMS SUP.AAT3. Part I, Rev 04, dated May 2018Appendix 1 to FMS SUP.AAT3<(>,<) >Appendix 2 to FMS SUP.AAT3<(>,<)>or Rotorcraft Flight Manual Supplement for quick conversion kit P/ N350-25-24-1000AR 11/97Componen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/07/2018	Active	10034706
10034714	2 EXCEL DESIGN LIMITED	REV. 4	CAA UK RESPONSIBILITY	PA-31	Introduction of enlarged window and sensor turret provisions	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List S21.MDL-0914 Issue 7Flight Manual Supplement S21.FMS-0077 Issue 4Compliance Record S21.COMP-0914 Issue 3Instructions for Continuing Airworthiness S21.TEC-0374Issue 2or later revisions of the above listed documents approved by EASA.	With a sensor turret with diameter greater than 15.5" installed, flightinto known or forecast icing conditions is prohibited.Limitations as defined in AFMS S21.FMS-0077 Issue 4.The installation and subsequent operation of a sensor turret requires aseparate approval.Prior to installation of this modi...	25/08/2017	Active	10034714
10034734	2 EXCEL DESIGN LIMITED	REV. 2	CAA UK RESPONSIBILITY	PA-31	Introduction of a Belly Pod	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List S21.MDL-0915 Issue 3 dated 13/11/2012- Flight Manual Supplement S21.FMS-0080 Issue 2 dated 31/10/2012- Compliance Record S21.COMP-0915 Issue 2 dated 13/11/2012- Instructions for Continuing Airworthiness S21.TEC-0311 Issue 1 dated20/04/2011or later revisions of the above listed...	Not to be flown in icing conditions with the belly pod installedLimitations as defined in AFMS S21.FMS-0080 Issue 2 dated 31/10/2012.Prior to installation of this design change itmust be determined thatthe interrelationship between this design change and any otherpreviously installed design changea...	25/08/2017	Active	10034734
10034747	ARMSTRONG AEROSPACE Inc.		FAA STC ST02939CH-D	B737-800	Validation of FAA STC ST02939CH-DPANASONIC DMPES - In flight Entertainment System installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Cf. EASA TCDS IM.A. 120 and:-CRI H-01 issue 01 on EWIS<(>,<)>-CRI F-01 issue 01 on IFEThe requirements for environmental protection and th...	-Master Data List, Ref: DC104-8084-00 Rev B, dated 22 April2011- Airplane Flight Manual Supplement, Ref: DC303-8084-00,dated 15 April2011-Instruction for Continued Airworthiness Supplement, Ref: DC113-8084-00,Rev A, dated 15 April 2011or later revisions of the above listed documents approved by EAS...	None	27/04/2011	Active	10034747

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034751	PROTOPLANE SPECIAL MISSION AIRCRAFT	REV. 3		AS 350 BB AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of video transmission equipment PP-013Rev. 01 New cabin rack U12 (PN PP-10-A405) addedRev. 02 Renumbering of elements and enhancement of installationinstructionsRev. 03 correction of typo concerning Rotorcraft Flight ManualSupplement	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List PP-013-MDL2-00 issue 0 dated 02 June 2021Instruction for Continued Airworthiness PP-013-ICA2-00 issue 0 dated 02June 2021Rotorcraft Flight Manual Supplement PP-013-AFM-03 issue 3 dated 30 March2020or later revisions of theabove listed document(s) approved/ acceptedunder the EASA sys...	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	30/06/2021	Active	10034751
10034796	LUFTHANSA TECHNIK AG			A380-841, A380-842	DLH Stretcher Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate.CRI D-51 Special Conditionon Stretcher InstallationsThe requirements for environmental protection and the associatedcertificated noise and/ or emi...	Definition Document, STDD25-10/23M, Issue 1, Rev 0, 15/04/2011Declaration of Compliance No. 3153, 18/04/2011or later revisions of the above listed documents approved by EASA	None	29/04/2011	Active	10034796
10034806	AERIGO SOLUTIONS INC	REV. 2	TCCA STC SA02-80	PC-12, PC-12/45 PC-12/47, PC-12/47E	PC-12 EASA STC10034806 Rev. 1_Canadian Holder transfer to AerigoDue to a Canadian STC Holder transfer (from ACS-NAI LtdTo AerigoSolutions Inc), this STC has to be updated to Revision 2. In additionthere was a clarification on the configuration that needed a new"editorial" limitation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	G504000 Rev C Master Doc ListG504000 Rev B AFMS "Installation Feather Inhibit System"G504071 Rev C Maintenance Manual Supplement "Installation FeatherInhibit System"or later revisions of the above listed documents approved by EASA.	This approval is applicable only for all propellers listed on thePilatus PC-12 TCDS EASA A.089 at Issue 06 and EASA STCEASA.A.S.03217(MT Propellers MT-Propeller Entwicklung GmbH)issued 16 Mar 2009 andfuture propellers owning a strictly identical feathering mechanism.Prior to installation of this d...	20/01/2016	Active	10034806
10034814	GAMA AVIATION (ENGINEERING) LIMITED	REV. 1	CAA UK RESPONSIBILITY	SEE APPROVED MODEL LIST	Navigation/ communications upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	All of the documents detailed in GAMA Aviation Master Document List (MDL) MDL- 1224 Issue 4.	Applicable to the aircraft types and variants detailed in GAMA AviationMultiple Model List (MML) MML-1224 Issue 3 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair...	17/03/2015	Active	10034814
10034839	AMTECH AERONAUTICAL LIMITED		TCCA STC SA09-51, ISSUE NO. 1	CL-600-2D24 CL-600-2D15 CL-600-2C10	Installation of a Rosemount Aerospace Angle of Attack Sensor.	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Rosemount Aerospace Inc. (RMTAERO) Master Data List D06404350, RevisionA or later approved revision<(>,<)>Rosemount Aerospace Inc. Maintenance Manual Supplement and Instructionsfor Continued Airworthiness D06404348, Revision A or later approvedrevision<(>,<)>or later revisions of the above listed do...	None.	05/05/2011	Active	10034839
10034865	ACS-NAI Ltd.		TCCA STC SA98-60 ISSUE 2	DHC-8-401,-402 DHC-8-301,-311,-314,-315 DHC-8-201,-202 DHC-8-102,-103,-106	Flight Deck Manual Stowage BoxTCCA STC SA98-60, Issue 2, dated 12.02.2001.	FAR 25 as per EASA.IM.A.191, Iss. 4 for DHC-8-100/200/300 SeriesJAR-CS-25 as per EASA.IM.A.191, ISS, 4 for DHC-8-400 SeriesThe Certification Basis for the original product remainsapplicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noi...	Installation must be in accordance with ACS-NAI Ltd. TCCA approvedModification Data Summary B 78600, Rev. H<(>,<)>Maintenance must be in accordance with Instructions for ContinuedAirworthiness MMS B 78671<(>,<)>or later revisions of the above listed documents approved by EASA inaccordance with EASAt...	None.	06/05/2011	Active	10034865

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034876 (EASA.A.S.03826)	AEROTEC & CONCEPT	REV. 1		C-212-DD (C212-300) C-212-CC (C-212-200)	MOD 0906: Installation of a Honeywell CAS67A TCASII system and ATC ModeS transponder MST67AThis revision extends the applicability to add C-212-CC (C-212-200) MSN139.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MASTER DATA LIST: AE0906MDL Rev. 11 Dated 22. Sept. 2016ForMSN 387:-INSTRUCTIONS FOR AIRWORTHINESS MAINTAIN: AE0906IPMN REV 3 dated 04.Apr. 2011-FLIGHT MANUAL SUPPLEMENT: AE0906SMV REV 2 dated 17. Mar. 2011For MSN 139:-AIRCRAFT FLIGHT MANUAL SUPPLEMENT: AE0906AFMS_2 REV 0 dated 22. Jul.2016-INSTRUC...	This STC is limited to MSN 387 and MSN 139Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	26/10/2016	Active	10034876
10034881	AERO DYNAMIX, Inc.		FAA STC SR09543RC	S-76C	Installation of Night Vision Imaging System (NVIS) / Night Vision Goggle (NVG) compatible lighting system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List (MDL), Aero Dynamix, Inc. drawing number MDL4783-01, revision D, dated 8 December 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)-Rotorcraft Flight Manual Supplement (RF...	Refer to applicable Rotorcraft Flight Manual Supplement (RFMS) for listof equipment mandatory for Night Vision Imaging System (NVIS) certification.	10/05/2011	Active	10034881
10034885	MICRO AERODYNAMICS, INC.		FAA STC SA02098SE	C90GTI, E90, H90 B90, C90, C90A, C90GT 65-A90-2, 65-A90-3, 65-A90-4 65-90, 65-A90, 65-A90-1	Installation of Vortex Generators on the wings and tail surfaces, andstrakes on the engine nacelles.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Micro AeroDynamics Drawing PackageMA2236, Revision IR, dated October 06, 2010, and Installation ManualMA2237, Revision IR, dated December 01, 2010.Instructions for Continued Airworthiness in accordance with MicroAeroDynamics Document MA0666, Revision A.or later revisi...	If more than five vortex generators, or either nacelle stake are damagedor missing, the aircraft is no longer airworthy.	10/05/2011	Active	10034885
10034891	AEROTEC & CONCEPT			A340-313	Installation of EFB class IIThis STC installs the RosemountAerospace 8700C2-3 Laptop DockingStation (System provision)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA TCDS EASA.A.015CRI F-2305-002: 'Installed Provisions for EFB Class 2 Provisions'The requirements for environmental protection and th...	Master Data List, ref : AE1098MDL, dated 09 May 2011Aircraft Flight Manual Supplement, ref : AE1098SMV, dated 18 March 2011Instruction for Continued Airworthiness, ref : AE1098IPMN, dated 17March 2011or later revisions of the above listed documents approved by EASA	None	10/05/2011	Active	10034891
10034892	LUFTHANSA TECHNIK AG			A330-200	A330-200 Cabin retrofit ETD01	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- EASA TCDS A.004Issue 25- Special Condition E-1014 Issue 4 (Inflatable SeatBelt)The requirements for environmental protection and the a...	Supplemental Type Definition Document, ref STDD00-10/26M Issue 1 orlater revisions of the above listed documents approved by EASA	None	10/05/2011	Active	10034892

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034893	DASSAULT FALCON SERVICE			F2000, F2000EX	115VAC electrical distribution for galley.DFSD144 A consists in installing a 28VDC/115VAC inverter, the associatedprotections and an outlet in the galley area.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	DFS Change Approval Sheet DFSD144-CAS Issue A dated 10.05.2011.DFS Modification Sheet DFSD144, Issue A dated 10.05.2011.or later revisions of the above listed documents approved by EASA	Modification applicable to F2000 & F2000 EX aircraft with:-1400W available on A4 bus (version 1) or 1280W (version 2),and- Master switch in cockpit to switch off components electricallysuppliedin Galley area, and- Master switch in cockpit to switch off all 115/230VAC distributioncircuit during TO-...	11/05/2011	Active	10034893
10034902	BOMBARDIER INC.		TCCA STC C-LSA11-024/D	BD-700-1A11	Installation, Antenna Provisions	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	Transport Canada STC No. C-LSA11-024/D Issue 1 dated 02 May2011ACS-NAI Ltd. Modification Data Summary G731000 Rev NC or later approvedrevisionSupplemental Airworthiness Limitations, G731000-AWL Revision IR or laterapproved revisionInstructions for Continued Airworthiness refer to G731000-ICA Revisi...	None	11/05/2011	Active	10034902
10034913	LUFTHANSA TECHNIK AG			747-400	Upgrade of first class cabin replacing 16 first class seatsby 8modified first class seats and installation of 8 singlebeds and halfsize partitions in accordance with STDD25-10/13M Issue 01, rev 00<(>,<) >d.d. 11-05-2011	The Certification Basis for the original product remains applicable tothis certificate/ Approval	CP25-10_13M LH FC Update Rev02Application Declaration of Compliance ADoC 3162 d.d. 11-05-2011or later revisions of the above listed documents approved by EASA	None	12/05/2011	Active	10034913
10034914 (EASA.R.S.01544)	SAFRAN ELECTRONICS & DEFENSE SAS	REV. 12		EC135 T3 EC135 T2+, EC135 T3 EC135 T2+ EC135 T2 EC135 T1, EC135 T2 EC135 T1 EC135 P3 EC135 P2+, EC135 P3 EC135 P2+ EC135 P2 EC135 P1, EC135 P2 EC135 P1	Installation of Flight Data Monitoring system HELICOM V2 NUM or HELICOMV2+ NUM, or HELICOM V3.Revision 1:- Introductionof reference to Special Condition for Lithium BatteryInstallations, which was inadvertently omitted during the initialcertification.Revision 2:- Extension of the applicability of t...	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.	Applicable documentation for installation of HELICOM V2 NUMand V2+ NUMon EC 135 P2+, EC 135 T1 (CPDS), EC 135 T2 (CPDS),EC 135 T2+, EC135P1(CPDS), EC135 P2(CPDS), EC135 T3 (CPDS), EC135 P3 (CPDS):- Rotorcraft Flight Manual Supplement N11-EC135 V2-HV2 NUM E-D-04, dated13 August 2020- Instructions for C...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The approval holder shall fulfill the obligations of Pa...	21/10/2025	Active	10034914
10034918	BEECHCRAFT CORPORATION	REV. 1	FAA STC SA01595WI-D	G36	G1000 Integrated Avionics System update with options including SyntheticVision and Pathways and GTS 820 Traffic Advisory SystemEASA Approval of SBAS based LNAV/VNAV and LPV Functionality.Revision 1: Transfer from Garmin International Inc. to BeechcraftCorporation	The Certification Basis for the original product remains applicable tothis certificate/ approval	Installation in accordance with Garmin Master Drawing List (MDL) 005-00620-18, Revision 1, dated July 21, 2010.Operationin accordance with Garmin FAA Approved Flight ManualSupplement 190-01258-00, Revision 1, dated July 21, 2010, and EASAspecific Flight Manual Supplement ref 190-01258-02 Revision 1....	Aircraft modified with this STC must be maintained in accordance withthe instructions for continued airworthiness (ICA)listed in the GarminMDL identified above.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previous...	11/06/2015	Active	10034918

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034921	RUAG AG	REV. 1		PC-6, PC-6/350, PC-6/350-H1 PC-6/C-H2, PC-6/C1-H2 PC-6/B2-H2, PC-6/B2-H4 PC-6/A, PC-6/A-H1, PC-6/A-H2 PC-6 ALL SERIES PC-6/A2-H2, PC-6/B1-H2 PC-6/A1-H2, PC-6/A2-H2 PC-6/350-H2, PC-6-H1, PC-6-H2	Avionics upgrade with Aspen EFD1000Removed:-Various Equipment (if installed) i.a.w. DIC 1898256-101Installed:-Aspen EFD1000 Electronic Flight Instrument System-Dual Garmin GNS430WCOM/NAV/GPS-Garmin GMA 340 Audio Panel	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: FAR 23 Amdt.54 and FAR23.1308 Amdt.57The requirements for environmental protection and the associatedcertified noise and/a...	Engineering Order: 1898256-01, dated 11.04.2011Airplane Flight Manual Supplement: 1898256-50 dated 11.04.2011Instructions for continued airworthiness: 1898256-60 dated 01.04.2011or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	S/N: All- One independent Communication or Navigation System needs to beinstalled in addition to the two GNS430W.-RNAV(GPS) Approaches to LNAV, LNAV/VNAV or LPV minima are notapproved.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/re...	29/01/2021	Active	10034921
10034925	ROEDER PRAEZISION GMBH	REV. 2		T303	Installation of1. Dual GPS/NAV/COMM Garmin GNS430/530(A)W2.E-HSI Sandel SN3308 with Directional Gyro Century NSD360A3.Various other NAV/COMM related Avionic Components	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Engineering Order: C303-NY-07165-05, Rev. 1-Flight Manual Supplements:C303-NY-07165-08a, Rev. 1C303-NY-07165-08b, Rev.1C303-NY-07165-08c, Rev. 1C303-NY-07165-08d, Rev. 1C303-NY-07165-08e, Rev. 1C303-NY-07165-08f, Rev. 1-Maintenance Procedures: C303-NY-07165-07, Rev. 1or later revisions of the abov...	This STC consists of three blocks (see title) which may be installedindependently from each other. The components of the third block (seeEquipment List) may also be installed independently.The third block of this STC includes the installation of:Honeywell (Bendix/King) ADF KR-87 with indicator KI227...	15/11/2017	Active	10034925
10034927	FLINT AERO, INC.		FAA STC SA2529WE	185E, A185E, A185F 185, 185A, 185B, 185C, 185D	Installation of twelve (12) gallon auxiliary fuel tank in each wing inacc. with FAA STC SA2529WE.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instruction Flint Aero, Inc. Doc. No. FA180, Rev. L, datedSeptember 4, 2007Operational Limitation: see placards in acc. with Flint Aero, Inc. Doc.No. FA180, Rev. L, dated September 4, 2007Maintenance Instruction in acc. with Flint Aero, Inc. Doc. No. FA180,Rev. L, dated September 4, 200...	The limitations and conditions of FAA TCDS 3A24 apply, except asoutlined below:a) Model 185 through A185F S/N 18502262 - 89 gal. (85 gal. useable); two32.5 gal. main tanks in wings at (+48) and two 12 gal. (11.5 gal.usable) aux. tanks in wings at (+50).b) Model A185F S/N 18502263 through 18502838, e...	13/05/2011	Active	10034927
10034950	SABENA TECHNICS BGC			AS 365N3	Installation of structural provisions (floor fittings) for cabin layoutModification in accordance with AEROCONSEIL Installation ServiceBulletin 2018-01-A-3101.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Aeroconseil Master Data List (MDL) 2018-01-A-2103-R00-Aeroconseil Installation Service Bulletin 2018-01-A-3101-R00-Aeroconseil Instruction for Continued Airworthiness (ICA)2018-01-A-2211-R00	None	16/05/2011	Active	10034950
10034980	AVIATION SUPPORT GmbH	REV. 1		SA 365 N	Title: SA 365 EMS Equipment.Description: Installation of anEMS Equipment fixed at the seat andcargo attachment points of the passenger compartment.The System is installed at the location of the first and second seatrow.The aft seat row remains for the health personnel.The medical equipment is insta...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight manual Supplement, EMS Equipment, SA365N, ASE-91012,FMS-ASE-91012, Revision 0-3 dated 5th May 2011<(>,<)>or later revisions of the above listed documents approved by EASA.Liste der gültigen Dokumente (Master Document List), ASE-91012, EMSEquipment, SA365N, MDL-ASE-91012, Revision 0-2 dated 5t...	This STC is applicable for the Serial Number 6100.The use of the electrical components of the medical equipment is limitedto VFR Operations.The use of a hoist is not possible if the EMS Equipment is installed.	24/05/2011	Active	10034980

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10034986	BEECHCRAFT CORPORATION	REV. 1	FAA STC SA01584WI-D	G58	G1000 Integrated Avionics System update with options including SyntheticVision and Pathways and GTS 820 Traffic Advisory SystemEASA Approval of SBAS based LNAV/VNAV and LPV Functionality.Revision 1: Transfer from Garmin International Inc. to BeechcraftCorporation	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Garmin Master Drawing List (MDL) 005-00606-01, Revision 1, dated June 4, 2010.Operation in accordance with Garmin FAA Approved Flight ManualSupplement 190-01180-01, Revision 1, dated June 4, 2010, and EASAspecific Flight Manual Supplement ref 190-01180-05 Revision 1.or...	Aircraft modified with this STC must be maintained in accordance withthe instructions for continued airworthiness (ICA)listed in the GarminMDL identified above.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previous...	12/06/2015	Active	10034986
10034991	AVIONIK STRAUBING ENTWICKLUNGS GmbH			SEE EASA APPROVED MODEL LIST	Installation of PFD Aspen EFD1000 PRO.	The Certification Basis for the original product remains applicable tothis certificate/ approval.CS-23, Amendment 2 (not required by 21A.101)The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain app...	Flight Manual Supplement: ASR-2011-020-FMS-05-00Aircraft Model List: ASR-2011-020-AML-24-00Instructions for Installation: ASR-2011-020-IFI-10-00Instructions for Continued airworthiness: ASR-2011-020-ICA-11-00or later revisions of the abovelisted documents approved by EASA.	None.	18/05/2011	Active	10034991
10034998	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A318, A319, A320, A321	1 NET In-flight Entertainment (IFE) System Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems -ICA on EWIS"The requirements for environmental protection and the ass...	- Modification TEN 646, ref report TEN 646, Issue 1, dated 17th May 2011- Certification Compliance Report, ref. report TEN 646/1, Issue 1, dated6th May 2011- Electrical Wiring Interconnection System (EWIS) ICA, ref. report646/26A, Issue 1,dated 11th October 2010or later revisions of the above liste...	Not applicable	18/05/2011	Active	10034998
10035000	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		SA 330 J	Modification of transponder wiring installation to comply with EASA ADNo 2010-0067Rev. 1: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master document list INAER.M11/010/34-LMD, Revision 0-Engineering bulletin INAER.M11/010/34-BI 0, Revision 0-Declaration of compliance INAER.M11/010/34/DoC-1 dated 17 May 2011or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/02/2019	Active	10035000
10035015	AIRBUS HELICOPTERS, Inc.	REV. 1	FAA STC NO. SR09262RC-D	EC135 T2(CPDS), EC135 T2+ EC135 T1(CDS), EC135 T1(CPDS), EC135 P2(CPDS), EC135 P2+, EC135 P1(CDS), EC135 P1(CPDS),	Installation of a Belly and Fin Strobe lights in accordancewith AECDrawing List 135A82-8018.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AEC Drawing List 135A82-8018, Revision A, dated 08/20/01-Instructions for Continued Airworthiness 135MMS-014, dated 07/31/01or later revisions of the above listed documents.	None.	23/05/2011	Active	10035015

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035016	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC N° ST10262SC-D	F2000EX	Oxygen system installation.Installation of added portion ofthe continuous flow, dropout typeoxygen system for the cabin and lavatory. This system connects to theexisting TC aircraft oxygen system.Validation of FAA STC N° ST10262SC-D, Revision 2 Issue date April 14,2011	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	DFJ Certification Data List doc. N° F2EX-01006 Revision K dated March31, 2011.Instructions for Continued Airworthiness doc. N° ICA-F2EX-01006-503Revision Original, dated January 25, 2011.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (...	As per FAA STC N° ST10262SC-D, Revision 2 Issue date April 14, 2011.	19/05/2011	Active	10035016
10035017	DASSAULT FALCON JET CORPORATION		FAA STC ST10657SC-D	2. FALCON 900EX 1. FALCON 2000EX	Assist Handle Installation:Configuration -501: Main entry door assist handle installationConfiguration -503: Aft lavatory assist handle installationValidation of FAA STC N°ST10657SC-D	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFJ Certification Data List doc. N° F00-01013 Revision J dated April 7,2011.Instructions for Continued Airworthiness doc. N° ICA-F00-01013-501/503Revisio n Original, dated January 25, 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (...	none	19/05/2011	Active	10035017
10035018	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC N° ST10584SC-D	F2000EX & F900EX	Console table installation.Installation of a Console Table in the main cabin area of the aircraftside ledge. This tabledesign will typically be located between twosingle seats and is not designed to be installed in front of theemergency escape hatch.Validation of FAA STC N °ST10584SC-D	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	DFJ Certification Data List doc. N° F00-01008 Revision K dated April 2,2011.Instructions for Continued Airworthiness doc. N° ICA-F00-01008-501Revision Original, dated January 25, 2011.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (ort...	None	19/05/2011	Active	10035018
10035047	TENENCIA Ltd.	REV. 1	CAA UK RESPONSIBILITY	A321-271N/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319, A320, A321 ALL MODELS A319-171N A319-131/-132/-133/-151N/-153N A319-111/-112/-113/-114/-115	Installation of provision for the use of a Class 2 Dual GoodrichElectronic Flight Bag (EFB) Smart Display SystemRev. 1:Extension of model applicability list (A319-151N / -153N / -171N-A320-251N / -252N / -253N / -271N / -272N / -273N - A321-251N / -252N/ -253N / -271N / -272N / -251NX / -252NX / -...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	TEN 674 Issue 38 – Modification Report (Master Data List) dated07.12.2020TEN 674-01 Issue 5 – Certification Compliance Report dated 30.11.2020TEN 674-47 Issue1 – AFM Supplement Report dated 02.20.2020or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/12/2020	Active	10035047
10035077	NSE	REV. 3		AS365N3 AS 365 N3	Installation of NVIS Lighting system in accordance with Airlift MOC.DO-365-33-104.Revision 1: Introduction of new helicopter configurations.Revision 2: Introduction of new helicopter configurations.Revision 3: Transfer of certificate to new holder.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Initial revision:Airlift Flight Manual Supplement: FMS-365-33-104-01, Rev. 1Airlift AS 365N3 NVIS Lighting System Installation: MOD. DO-365-33-104Rev.1.Airlift Instruction for Continued Airworthiness: ICA-365-33-104-01Rev. 0.Airlift Master Document for List for DO - 365 -33-104 Rev. 0.Revision 1:A...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Refer to applicable Flight Manual Supplement (FMS) form...	16/07/2025	Active	10035077

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035079	FLINT AERO, INC.		FAA STC SA1614WE	SEE EASA APPROVED MODEL LIST	Installation of one twelve (12) gallon auxiliary fuel tank in eachoutboard wing panel in acc. with FAA STC SA1614WE.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Flint Aero Master Drawing List 15171821, Rev. A, FAA approved November5, 2007orSealed Flint Aero Master Drawing List FA170, last Rev.Installation instructions FA180, Rev. L, datedSeptember 4, 2007Airplane Flight Manual Supplement FTC453.001, IR, FAA approved May 8,2006For earlier installations:a) F...	The limitations and conditions of FAA Aircraft Specification A-799, FAAData Sheets 3A12, 3A17, or FAA Data Sheets A4EU and A18EU or EASA TCDSIM.A.051 apply, except as outlined below of this STC:1. Fuel CapacityAdd "24 gal. (23 gal. useable); two 12 gal. aux. tanks in wings at(+50)" to quantities sho...	24/05/2011	Active	10035079
10035080 (EASA.R.S.01514)	NSE	REV. 1		AS 365 N2	Installation of NVI Lighting System in accordance with Airlift MOD.DO-365-33-101.Revision 1: Transfer of certificate tonew holder.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Airlift Flight Manual supplement: FMS-365-33-1.1, Rev. 0.Airlift AS 365N2 NVIS Lighting System Installation: MOD DO-365-33-101,Rev. 0Airlift Instruction for Continued Airworthiness: ICA-365-33-101-01, Rev. 1.Airlift Master Document List as per DO-365-33-101, Rev. 0.or later revisions of the above lis...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Initial issueRefer to applicable FMS for list of equipm...	16/07/2025	Active	10035080
10035081	STC ACQUISITION, LLC		FAA STC ST01567LA	G-1159 (GULFSTREAM II) G-1159B (GULFSTREAM IIB) G-1159A (GULFSTREAM III)	Installation of a pylon mounted ejector system with new design thrustreversers, to show compliance with ICAO Annex 16, Volume 1, Amendment 9,Chapter 3 noise requirements.	The Certification Basis for the original product remains applicable tothis certificate/ approval.CAR 4b and FAR 25 and FAA Issue Paper P-1 as defined in FAA STCST01567LA.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated n...	Installation in accordance with Master Drawing List ref A<(>&<)>C-00-00-051 Rev N, dated 17 March, 2005.Operation in accordance with Aircraft Flight Manual Supplement ref A<(>&<)>C-01-00-270, dated 16 May, 2005 for model G-1159 (GulfstreamII)Operation in accordance with Aircraft Flight Manual Suppl...	Model G-1159, (Gulfstream II) 1),,Aircraft without Aircraft Service Change (ASC) 81, “62,500 PoundIncreased Gross WeightModifications, or those with a Maximum (ramp)weight less than 62,500 lb are not eligible for this modification. 2),,Aircraft with ASC 200, “Fuel Tip Tanks - Installation off” are no...	24/05/2011	Active	10035081
10035091	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	TYPE: FAN JET FALCON BASIC, D AND E SERIES	Extended underwing stores carriage (flutter clearance)The goal is to approve the flutter clearance of underwing storeconfigurations installed onto Fan Jet Falcon aircraft with existingunderwing hard points. This design definition establishes an envelope ofacceptable stores properties based on knownc...	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Design Change Statement doc. N° DC-0194 Issue 1 dated 20.05.2011Compliance Record doc. N° CR-0194 Issue A dated 20.05.2011or later revisions of the above listed documents approvedby EASA.	This approval only addresses the clearance of the pod configurationswith respect to flutter, all other aspects of the certification process,such as structural strength<(>,<)> effects on aircraft handling andperformance, system safety and environmental protection require furtherinvestigation.	30/05/2011	Active	10035091
10035106	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST02072SE	A330-223, A330-243 A330-201, A330-202, A330-203	Installation of New J Class Crew Rest for Qantas Airlines A330-200seriesThis STC installs a removable crew rest curtainand curtain header	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, ref : HPD-DL-141 Revision E, dated 14 June 2010Instruction for Continued Airworthiness, ref : HTM963,dated 14 May 2010or later revisions of the above listed documents approved by EASA	none	26/05/2011	Active	10035106
10035120 (EASA.A.S.03596)	airplus engineering GmbH	REV. 1		DHC-8-315	VIP Cabin Interior Modification as detailed in AIRplus DescriptionDocument DE-0348-250001, Revision 3, dated 03.05.2011Rev1: transfer to new STC holder from “Airplus Maintenance	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Elected to comply CS 25, Amendment 4 for changed areasThe requirements for environmental protection and the associatedcertificated noiseu...	Installation must be in accordance with-AIRplus Modification Package EW-0348-000010, Revision 3, dated31.08.2009-AIRplus Master Drawing List MD-0348-000001, Revision 9, dated11.08.2010-V-Plane IFE System Description APDHC8-DE-4420-01-02, dated 10.08.2010Operation must be in accordance with-V-Plane A...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of theproduct	10/02/2021	Active	10035120

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035124	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03070AT	GIV-X	Installation of a Honeywell LSZ-860 Lightning Sensor System.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC412258000, Revision F, dated March 28, 2005.Operation in accordance to Gulfstream Flight Manual supplement ref GC41225M000 dated 05 April 2005. "Honeywell LSZ-860Lightning SensorSystem".or later revisions of the above list...	This approval should not be extended to other aircraft of this model onwhich other previously approved modifications are incorporated, unlessit is determined by the installer thatthe interrelationship betweenthis change and any other previously approved modifications will produceno adverse effect u...	27/05/2011	Active	10035124
10035125	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03566AT-D	GIV-X	Installation of a Custom Cabin Interior and completion of AircraftSerial Number 4121.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC420004121, Revision E, dated August 21, 2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	You cannot use descriptive data about this design change toduplicateother products. This approval is limited to only the installation madein Gulfstream GIV-X, A/C 4121. This STC does not permit manufacturing ofparts for multiple installations.	27/05/2011	Active	10035125
10035128	LEARJET Inc.D/B/ A BOMBARDIER AIRCRAFT SERVICES		FAA STC SA8182NM-D	BD-700-1A10	Modification of the Forward Water Fill Panel	EASA TCDS IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate...	FAA STC No. SA8182NM-D dated 23 January 2001.Bombardier Aerospace Master Drawing List BAS67010003 revision A dated 21December 2000 or later approved revision.or later revisions ofthe above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthi...	This installation modifies the existing water fill panel installationinstalled by Bombardier Inc. Engineering Drawing MDC9000-0142-1 only (Previously approved under EASA STC No. EASA.IM.A.S. 02336)	27/05/2011	Active	10035128
10035154	BEECHCRAFT CORPORATION	REV. 1	FAA STC SA00526DE	390 (PREMIER IA) 390 (PREMIER I)	Installation of an AirCell telephone system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Master Data List, Document No.GEN-030317-MDL, Revision B dated September 5, 2003Maintain in accordance with Document No GEN-030317-018 Rev. A, dated,September 5, 2003.Aircraft to be operated in accordance with Flight Manual Supplement refGEN-030317-020, Rev IR, datedo...	Serial Number RB-73 OnlyHawker Beechcraft Ltd. Minor Modification SC0392A must be embodied.	15/11/2012	Active	10035154
10035155	STANDARD AERO		FAA STC ST02803CH-D	EMB-145LR, EMB-145XR EMB-145ER, EMB-145MR, EMB-145, EMB-145MP, EMB-145EP, EMB-135KE, EMB-135KL, EMB-135ER, EMB-135LR,	Installation of a Honeywell KHF-1050 HF System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.EASA TCDS IM.A. 032The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Data List : 1018147 Rev.A dated 05 February 2010- Airplane Flight Manual Supplement : 1018197 Rev.A dated 21 February2010- Instruction for Continued Airworthiness : 1018140 Rev.A dated 13January 2010- EWIS ICA : 1019049 Rev.B dated 23 July 2010- Airworthiness Limitations : 1018206 Rev.A dat...	None.	30/05/2011	Active	10035155

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035156 (EASA.R.S.01356)	BRISTOW HELICOPTERS LIMITED		CAA UK RESPONSIBILITY	SIKORSKY S-76C	Qualification of the Garmin 400 Series GPS for enroute navigation andnon-precision approach.	CS29The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Bristow Helicopters Limited Sikorsky S76 Flight Manual Supplement No 20Issue 1or later revisions of the above listed documents approved by EASAModification MOO/ S76/34.5794 Issue 1Certification Plan BHLIS76.4504 Issue A	None.	30/05/2011	Active	10035156
10035157	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	3. PA-34-200, PA-34-200T 2. PA-34-220T 1. PA-44-180, PA-44-180T	Design data for the approval of a Honeywell KFD840 Primary FlightDisplay (PFD)	CS-23The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of theoriginal product areunchanged and remain applicable to thiscertificate/ approval.	Installation Manual IM. 02510 Revision AMaster Document ListMDL.02510 Revision AInstructions for Continued Airworthiness ICA.02510 Revision AFlight Manual Supplement FMS. 02510 Revision Aor later revisions of the above listed documents approved by EASA	None	30/05/2011	Active	10035157
10035162	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-28RT-201, -201T PA-28R-180, -200, -201, -201T PA-28-236, -151 PA-28-180, -181, -161, -140 PA-28-150, -160, -235, -201T	Installation of dual GPS/NAV/COMM Garmin GNS430/530(A)W.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2 (not required by 21A.101)The requirements for environmental protection and the associatedcertificated noise and/ or em...	Flight Manual-Supplement: ASR-2010-058-FMS-05-00, Amendment00Project Description: ASR-2010-058-PRD-04-00, Amendment 00Instructions for Installation: ASR-2010-058-IFI-10-00, Amendment 00Instructions for Continued Airworthiness: ASR-2010-058-ICA-11-00,Amendment 00or later revisions of the above liste...	None.	31/05/2011	Active	10035162
10035173	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	B737-300	Introduction of Number 2 Galley Assembly	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR 25.1529 at Amdt 21CRI H-1 - Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS	-S21.MDL-0809 Issue 2 Master Document List dtd. 17.May 2011-S21.COMP-0809 Issue 2 Compliance Record dtd. 19.May 2011-S21.TEC-0316 Initial Issue 1 Supplemental Manual dtd. 18.May 2011or later revisions of the above listed documents approvedby EASA	None	01/06/2011	Active	10035173
10035182	SABENA TECHNICS BGC			A300 F4-605 R, A300 F4-622 R A300 C4-620, A300 C4-605 R VARIANT F, A300 B4-622 R, A300 B4-605 R, A300 B4-620, A300 B4-622, A300 B4-601, A300 B4-603,	Aeroconseil STC 0490-1 Aircell ST3100 SATCOM Installation on A300-600s.This STC covers the installation of a Satellite Telephone SystemTransceiver, a Telephone adapter with Display, a Base cradle for theCordless Handset and a Satellite antenna in accordance with Master DataList Ref.0490-01-A-2103 Re...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.- EASA - Certification Specification CS 25 Amdt 4.- Special condition S/C H01. (Enhanced airworthiness programme foraeroplane Systems -El...	- A300-600 Flight Manual Supplement Ref.0490-01-A-2301 Rev.00- Instruction for Continued Airworthiness Document Ref.0490-01-A-2211- Compliance Records Ref.0490-01-A-2104 Rev.01- Master Data List Ref.0490-01-A-2103 Rev.01or later revisions of the above listed documents approved by EASA.	None.	01/06/2011	Active	10035182
10035193	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	EMB-145	Introduction on EMB-145 of Saftglo photoluminescent FPEEPMS	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List doc. S21.MDL-0842 dated 24.05.2011Aircraft Flight Manual Supplement doc. S21.FMS-0075 Issue 1Compliance Record doc. S21.COMP-0842 dated 24.05.2011or later revisions of the above listed documents approved by EASA	none	03/06/2011	Active	10035193

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035215	PRECISE FLIGHT, Inc.	REV. 1	FAA SA2622NM	FALCON 50 DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-103, DHC-8-106 DHC-7-103, DHC-8-102 DHC-7-100, DHC-7-101	Installation of Precise Flight Pulselite Control SystemRev.1 updates the applicability to DHC-7 and DHC-8 models.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Engineering Drawing List ref. 250P0000 rev. A, dated 22 February 2010- Instructions for Continued Airworthiness ref. 000PMAN0002 rev. G,dated 06 May 2020- Aircraft Flight ManualSupplement listed on FAA AML N° SA2622NM dated06 December 2004.- Installation Manual listed on FAA AML N° SA2622NM dated...	This approval is restricted to the following Pulselite units: 2400-25-4-4 / 2400-25-4-4-1 / 240-25-4-4-2 / 2401S / 2401.This approval does not cover the physical installation of the system.Physical installation of the system in the aircraftshould be dulysubstantiated by an appropriate entity and app...	16/11/2021	Active	10035215
10035229	ASI INNOVATION			T206H	ASI-FAM-0002-01 Installation of Flir MX10 on Cessna T206H.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement ASI-AFM-0002-03 dated 22 April 2011ASI-SDL-0002-05Maintenance Planning Supplement ASI-MPS-0002-01 dated 17 March 2011or later revisions of the above listed documents approved by EASA.	Limitation to Cessna T206H serial numbers 445 and 446.	07/06/2011	Active	10035229
10035243	DANSK FLY ELEKTRONIK ApS			CESSNA 414, 414A	Installation of Garmin GTX330D Transponder	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Design Order Package DFE-DO-0439 including Aircraft Flight ManualSupplement (DFE-DO-0439-AFMS) and Instructions for ContinuedAirworthiness (DFE-DO-0439-ICA)or later revisions of the above listed documents approved by EASA	None	07/06/2011	Active	10035243
10035249	KUERZI AVIATION AG			PC-6-B2-H4	Cold weather operation package (230VAC or 110VAC)By installation of:- One TANIS TAS200 Battery Heater system- One TANISTAS300 Turbine Preheat system- One Power receptacle in the cabin front right	CAR 3,,Amdt: 3-1 through 3-5The Certification Basis for theoriginal product and the followingadditional or alternativeairworthiness requirements are applicable tothis certificate/ approvalSCs or ESFs: For this change, voluntary compliance to CS23 Amdt. 0 wasshown.The certificated noise and/ or emi...	Master Document List: MDL-201110187, dated 08.06.2011Project Installation Manual: PIM-201110187, dated 08.06.2011Instruction for continued airworthiness: ICA-201110187, dated 08.06.2011Airplane Flight Manual Supplement: FMS-201110187, dated 08.06.2011or later revisions of the above listed documents...	S/N: all	08/06/2011	Active	10035249
10035253	ALIDAUNIA S.R.L.			A109A II	MB 022/ALI/2010 "Installation of Alternate Static Pressure Source forthe Indicator: Altimeter, Airspeed & Vertical Speed"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement Doc. FMS/ALI/022 Rev. 0or later revisions of the above listed documents approved by EASABT DocDR/ALI/ 022 Rev. 0Maintenance Manual Supplement Doc. MMS/ALI/022 Rev. 0	None	15/07/2011	Active	10035253
10035259	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA02935CH	441	Air Ambulance Conversion in accordance with Spectrum Aeromed DrawingList	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved Master Drawing List, Doc. No. 6078DL, Rev. -, dated 16February 2010<(>,<) >FAA Approved Aircraft Flight Manual Supplement, Doc. No. 6078FMS, Rev.-, dated 12 July 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subseq...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2019	Active	10035259

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035276	HELI-ONE		TCCA STC SH05-46	S-61N	Sealed Lead Acid Battery Installation	CAR-7The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	Flight Manual Supplement CHS61-24-016 Revision Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision)CHC Approval Control Document CHS61-24-016 Revision AInstructions for Continued Airworthiness Conco...	none	15/06/2011	Active	10035276
10035279	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03795AT-D	GV-SP	Aircraft Completion and Installation of an Airplane Interior	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation of an Airplane Interior in accordance with GulfstreamAerospace Corporation Index List GC520005280, Revision D, datedSeptember 23, 2010.Operation in accordance with Gulfstream Aircraft Flight ManualSupplement ref GC51 468M015, dated 23 September 2010.Instructions for Continued Airworthin...	The installer must determine whether this design change is compatiblewith previously approved modifications.If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.	10/06/2011	Active	10035279
10035287	SAFRAN ELECTRONICS & DEFENSE SAS	REV. 10		EC 130 T2 EC 130 B4, EC 130 T2 EC 130 B4 AS 350 B3 AS 350 B2, AS 350 B3 AS 350 B2	Installation of Flight Data Monitoring system HELICOM V2 NUM or HELICOMV2+ NUM, or HELICOM V3.Revision 1: Introduction of alternate positions for antennasRevision 2: Correction ofminor discrepancies in associateddocumentationRevision 3: Addition of "Instruction for Continued Airworthiness NoN8-AS35...	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.	Certification Program N2-AS350EC130_HV3-E-A-Revision 05 (with MDLincluded)Rotorcraft Flight Manual Supplement N11-AS350EC130_HV3-E-B Revision 01(RFMS) Instructions for continued Airworthiness N8-AS350EC130_HV3-E-B Revision01 (ICA)Installation Manual N7-AS350EC130_HV3-E-B Revision 01Or later revisions...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The approval holder shall fulfill the obligations of Pa...	25/02/2025	Active	10035287
10035295	AIRCRAFT DESIGN CERTIFICATION GmbH	REV. 2		L-13 "BLANÍK"	Modification and inspection program for compliance with EASAAD-2010-0185-E.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification and inspection program for compliance with EASAAD-2010-0185-E:ADxC-39-001-AFM - 30 Mar 11 - Airplane Flight Manual SupplementADxC-39-001-AMM - 11 Jun 11 - Sailplane Maintenance Manual SupplementADxC-39-EO-013 Issue A - 01 Apr 11 - Template for Installation ofstructural modificationADxC-...	According to the applicable AFM Supplement.	17/07/2018	Active	10035295
10035296	ROCKWELL COLLINS, Inc.		FAA STC ST01886LA	B767-300	Installation of Rockwell Collins CMU-900 Communications ManagementSystem, APM-900 Airplane Personality Module, IDC-900 Integrated DatalinkController & Teledyne TP-4499 Printer.	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	Hollingsead International Master Data List 2853-01, Revision NC, 04/04/2006Flight Manual Supplement, Document No. 2853-AFM, Revision NC, 12/05/2006or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)...	none	14/06/2011	Active	10035296

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035308	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA02897CH	510	Air Ambulance Conversion according FAA STC SA02897CH.	The Certification Basis for the original product remains applicable tothis certificate/ approval.CS 23 as defined in CRI A-01 and indicated in TCDS EASA.IM.A.502The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunch...	Installed iaw. Spectrum Aeromed Master Drawing List 6053DL,dated 21 Apr2010Operated iaw. FAA approved AFM-S 6053FMS, dated 26 Oct 2010Maintained iaw. FAA accepted Inst. for ContAW, Manual 6053MM, dated 21Apr 2010or later revisions of the above listed documents approved by EASA inaccordance with EAS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2019	Active	10035308
10035310	ACS-NAI Ltd.	REV. 1	TCCA STC C-LSA11-075/D ISS1	BD-700-1A10	Installation, Complete Custom Aircraft Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA STC No. C-LSA11-075/D Issue 1 dated 13 May 2011.ACS-NAI Ltd. Modification Data Summary G789000 Revision NC or laterapproved revision.ACS-NAI Ltd. Airplane Flight Manual Supplement for the Complete CustomAircraft Interior, G789091 Revision B or later approved revision.Instructions for ContinuedC...	Restricted to ASN 9403.This system is intended to provide internet connectivity and emailservices to the airplane's cabin using portable electronic devices(PEDs). Any other intended function of this equipment will require are-examination of the certification basis.Embodiment of EASA STC No. EASA.IM....	15/06/2011	Active	10035310
10035325	NORTHERN AVIONICS S.R.L.	REV. 1		AW109SP	Installation of a Relay box and Control Panel for ICS VIP application.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement for ICS VIP Miscellaneous ControlPanel (KIT P/N KNAV-418), RFMS NAV 436 Rev. 0or later revisions of the above listed documents approved by EASA.Instructions for Continuous Airworthiness ICA-NAV436, Revision 0, dated15 June 2011Installation Instructions II-NAV436-1...	Required pre-modification: Agusta electrical/mechanical provision nº109-B810-30-( )	05/08/2011	Active	10035325
10035332 (2004-3750)	PEMCO WORLD AIR SERVICES	REV. 1	FAA STC SA2971SO	B737-300	Installation of a Cargo Loading System in acc with MDL 2337rev X dated12/07/2010Modification of the STC FAA SA2971SO to increase from 121 pax to 148 paxaccording to drawing 90945-507/607	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Refer to Airworthiness Approval Note 24984 Addendum 1 (enclosed)The certificated noise and/ or emissions levels of the original productar...	-Project Specific Certification Plan for up-date of STC SA2971SO toinclude 148 passenger configuration of the Quick Change Handling/ loadingsystem for B737-300 S/N 23522 and 23523 - Report No. ER-5085 rev 3 dated06/09/2011-Drawing 90945-507/607 as described in master Drawing List for B737-200and B737...	None	16/06/2011	Active	10035332
10035344	DOA21 LIMITED	REV. 1		A320-214	Custom Interior A320 JubileeRev. 1: Transfer of STC holder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following EASA Certification Review Items (CRIs) are part of thecertification basis for this design change:- Deviation CRI D-01 Issue 1 "Installation of i...	STC Twenty One Limited documents:- Master Document List S21.MDL-0909 initial issue dated 02nd June 2011.- Aeroplane Flight Manual (AFM) Supplement S21.FMS-0079 Issue 1.- For documents and supplement manuals related with instructions forcontinued airworthiness see references on Master Document ListS2...	This design change approval is applicable on Aircraft modelAirbusA320-214, aircraft serial number 4199.This STC has associated a supplement to the original TC Holder's EWISInstructions for Continued Airworthiness. This supplement is included inthe document JUBL-CCR-400-EWA "Instructions for continu...	24/10/2023	Active	10035344

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035406	JET AVIATION AG, BASEL			FALCON 2000	Iridium antenna installation.Structural justification of the installation of an Aircell low profiledual patch antenna on top of the fuselage between frames 17 and 18.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List Doc. No. BOSIR001-002 Rev. A dated 16.06.2011Certification Compliance Sheet Doc. No. BOSIR001-102-02 Rev. A dated28.01.2011Instructions for Continued Airworthiness Doc. No. BOSIR001-150-02 Rev.IR dated 09.06.2011or later revisions of the above listed documents approved by EASA	Restricted to S/N 173This approval only covers the structural installation of the antenna.Installation and activation of any related Satcom system must bejustified and covered by another suitable approval.	21/06/2011	Active	10035406
10035421	GULFSTREAM AEROSPACE CORPORATION		FAA STC NO. ST04238AT-D	GV-SP (G550)	Installation of Cabin Interior and Aircraft Completion for GulfstreamGV-SP model Aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation IndexList No. GC520008724 Rev G, dated June 8, 2011.Operation in accordance with Gulfstream Aerospace Corporation AircraftFlight Manual Supplement No. GC52000M149 Rev -, dated June 8, 2011.Instructions for Continued Airworthiness in ac...	None	21/06/2011	Active	10035421
10035429	DART AEROSPACE Ltd.	REV. 2	TCCA STC SH11-1	407 206L, 206L-1, 206L-3, 206L-4	D407-797 Heli Utility Basket and Heli Access Step Installation, Revisionto STC 10035429 to add D407-797-311 Heli AccessStep.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:The applicant complied voluntarily with the following paragraphs of FAR27 amendment 27-45:27.1, 27.21, 27.25, 27.27, 27.29, 27.45, 27.51,...	FMS-D407-797 revision A dated 12 January 2011 - Flight Manual Supplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision).IIN-D407-797 revision C dated 29 July 2011 - Installation Instructions;ICA...	None.	28/11/2011	Active	10035429
10035437	AMAC AEROSPACE SWITZERLAND AG			A319-133	Satcom and LAN / WLAN System Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems -ICA on EWIS"The requirements for environmental protection and the ass...	- Master Data List, ref. doc. MDL-BL01-2300, Rev. A, dated 1st June 2011- Certification Plan, ref. doc. CP-BL01-2300, Rev. B, dated 20th June2011- Compliance Check List, ref. doc.CCL-BL01-2300, Rev. B, dated 23rdMarch 2011- Declaration ofCompliance - Project Satcom and LAN / WLAN SystemInstallatio...	Not Applicable	22/06/2011	Active	10035437
10035456	AVIONIK STRAUBING ENTWICKLUNGS GmbH			F406	Cockpit Upgrade basing on dual Garmin G600 and GNS430W	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA CS-23, Amndt. 1The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the ori...	Project Description ASR-2011-033-PRD-04-00, Rev. 00Instruction for Installation ASR-2011-033-IFI-10-00, Rev. 00Instructions for Continued Airworthiness ASR-2011-033-ICA-11-00<(>,<)>Rev. 00Flight Manual Supplement ASR-2011-033-FMS-05-00, Rev. 00or later revisions of the above listed documents a...	Only applicable for Aircraft S/N 097 and up	24/06/2011	Active	10035456

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035461	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC N° ST10583SC-D	2. F900EX 1. F2000EX	Galley pocket door installationValidation of FAA STC N°ST10583SC-D	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	DFJ Certification Data List doc. N° F00-01005 Revision AR dated April03, 2011.Instructions for Continued Airworthiness doc. N° ICA-F00-01005-501Revision Original, dated January 25, 2011Airplane Flight Manual Supplement doc. N °37887-1 datedJuly 16, 2007or later revisions of the above listed document...	Approval is limited to the "-501" configuration.	24/06/2011	Active	10035461
10035471 (EASA.R.S.01467)	BRISTOW HELICOPTERS LIMITED	REV. 1	CAA UK RESPONSIBILITY	S-92A	Installation of Rockwell Collins TCAS II systemRev. 1 covers modification of Rockwell Collins TCAS-4000 TCAS II updateto version 7.1 software - Modification S92/34.5702	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	S92 Flight Manual Supplement No 2 issue 3 - for software version 7.0S92 Flight Manual Supplement No 4 initial issue - for software version7.1or later revisions of the above listeddocuments approved by EASABHL/S92.0106 issue a dated 24 September 2010 - Certification PlanBHL/ S92.0311 initial issue da...	None	18/07/2012	Active	10035471
10035483	SKYE AVIONICS Ltd.		TCCA STC SH11-14	BELL 407	Installation of "Check Engine Instruments" Audio Alert System.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	AER-FMS-023 revision 01 dated 29 April 2011 - Flight ManualSupplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision) AER-MDL-034 revision NC dated 2 May 2011 - Master Document List;AER-2011-008C...	None	27/06/2011	Active	10035483
10035488	KUERZI AVIATION AG			DHC-6-300	Installation of two Aspen Electronic Flight Display (EFD1000 Pro, oneGarmin GNS530W (GPS, COM, NAV), one Garmin GNS430W(GPS, COM, NAV), oneGarmin GTX330 (XPDR) and one Garmin GTS800 (TAS)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalFAR-23, Amdt. 0elect to complyFAR23.1308 Amdt. 57FAR23.1309 Amdt. 41FAR23.1311 Amdt. 41FAR23.1322 Amdt. 17FAR23.1326 Amdt. 49FAR23.1529 Am...	Master document list MDL-201034120, Initial issueProduct Installation Manual PIM-201034120, Initial issueFlight Manual Supplement FMS-201034120, Initial issueInstruction of Continued Airworthiness ICA-201034120, Initial issue Ior later revisions of the above listed documents approved by EASA	None	27/06/2011	Active	10035488
10035500	NORTHERN AVIONICS S.R.L.			AB206B	NAV 427 "Installation of Alternate Static System" - This kits consistsin the installation of an additional line to the original static lineand a 3-way valve/ switch (with the air inlet port) to pick up the staticpressure in the cabin when the external ports occluded (for ice or otherreasons). This va...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-27 Amdt. 2 (Ref. NAV-427 Rev. 0 Sec. VIII)The requirements for environmental protection and the associatedcertificated noise and/ or em...	RFMS NAV 427 Rev. 0 (RFM Supplement & Supplemento al Manuale di Volo)Technical Modification Bulletin NAV-427 Rev. 0or later revisions of the above listed documents approved by EASA	This STC is applicable only to the helicopters S/Ns from 8590 to 8758.	27/06/2011	Active	10035500
10035543	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			EC135 P2+	GNS-530 & GNS-430A InstallationOut: Garmin GNS-530W & GNS-430WIn: Garmin GNS-530 & GNS-430AComplete retrofit done by American Eurocopter under FAA Form 337 dated11.12.2009 and FAAForm 8110-3 dated 11.12.2009	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Data List Doc. No.: EV5126-049 Rev. IRInstructions for Continued Airworthiness Doc. No.: EV5126-085 Rev. IRRotorcraft Flight manual Supplement Doc. No.: EV5126-071.01 Rev. IRor later revisions of the above listed documents approved by EASA	This EASA STC is only valid after EASA Validation of FAA STC SR09137RC-D(Extended R/H Side Instrument Panel).S/ N: 0684	29/06/2011	Active	10035543

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035563	MICHELIN NORTH AMERICA, INC.		FAA STC ST03642AT	CL-600-2D24 CL-600-2C10, CL-600-2D15	Installation of Michelin's tire(s) P/N 029-901-0 on the main gear and/orP/N 036-897-0 on the nose landing gear of Bombardier CL-600-2C10,CL-600-2D15, CL-600-2D24 aircraft wheel assembly.	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	FAA STC No. SA03642AT dated 10 March 2010.Aircraft Braking Systems Corporation (ABCS) Component Maintenance Manual(CMM) AP-843, Revision 1, dated 20 April 2004, AP-794, Revision 1dated1 April 2003, AP-795 dated 1 February 2001, and Michelin North America,Inc. Service Bulletin STC SB 2008-10-15 Revi...	none	30/06/2011	Active	10035563
10035568	DASSAULT FALCON SERVICE	REV. 2		MF900, F900EX	WiFi activation on MF900 and F900EX.This revision 2 of the EASA STC 10035568 approves the extension ofapplicability of the change to the F900EX model, EASy version.NEW-PAGE	The following JAR 25 requirements at Change 14 are applicable to theparts introduced by this design change:25.1301 (a) (d)25.1309 (a)(g)25.132225.1353 (a)25.1431 (a) (c)The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product...	Master Data List DFS-DE-17-F9-9609 issue D, dated 9 July 2015	MF900 model (F900B configuration) equipped with WiFi equipmentsinstallation compliant with prerequisite note DT-001-11.MF900 model (F900C version) and F900EX model (non EASy version) equippedwith WiFi equipments installation compliant withprerequisite noteDT-003-10F900EX model (EASy version) equipp...	13/07/2015	Active	10035568
10035585	BOMBARDIER INC.	REV. 1	TCCA STC NO. C-LSA02-261/D	BD-700-1A10	Approval of Side Facing Divan Seating Limitations	EASA IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. C-LSA02-261/D Issue 2 dated 12 November 2003.Aero Consulting Services Modification Data Summary Number D04100Revision A or later approved revision.Aero Consulting Services Flight Manual Supplement D04191 Revision Aorlater approved revision.or later revisions of the above li...	Restricted to ASN 9054.Previous embodiment of EASA STC No. 10016140 (FAA STC No SA8164NM-D)	06/07/2011	Active	10035585
10035593	AMES - AEROSPACE AND MECHANICALEN GINEERING SERVICES ING. WALTERSTARZA CHER GesmbH	REV. 1		737-700 AND 737-800	B737-800/-700 Live TV System Removal / Major Change to EASASTC 10035593to implement B737-700 as effective aircraftAMESwill use FAA approved Live TV documentation such as but notlimitedto: Drawings, Structural substantiation reports, ELAand W<(>&<) >B forcompliance demonstration.	The Certification Basis for the original product remains applicable tothis certificate/ approval.No additional Airworthiness Requirements have been added and/or acceptteddue to thecurrent change.The change is classified as non-significant and therefore the applicantselected the Amendment of the CS a...	The required documents are specified in Engineering OrderEO_M08300110_MGR_09052011, Revision 2 dated 24.10.2012or laterrevisions of the above listed documents approved by EASA- The modifications shall be done in accordance with the instructionsdefined in Engineering Bulletin EB_M08300110_DBE_260920...	This STC is only applicable for aircraft which have been previouslymodified with FAA Supplemental Type Certificate ST02887AT.	09/11/2012	Active	10035593
10035617	AIRBUS HELICOPTERS, Inc.		FAA STC SH8171SW-D	SA 365 N1,AS 365 N2	Installation of Bendix /King EFIS 40 Electronic Flight InstrumentationSystem in accordance with AEC Drawing List 365A73-9051Revision B dated10/1/93 or Bendix /King EFIS 50 Electronic Flight InstrumentationSystem in accordance with AEC Drawing List 365A73-9056 Revision B dated6/28/94.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement 365FMS-017 Rev.A1, dated06/15/2011 for EFIS 40 installation.- Rotorcraft Flight Manual Supplement 365FMS-018 Rev.A1 dated 06/15/2011for EFIS 50 installationor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/0...	none	05/07/2011	Active	10035617

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035624	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BD-700-1A11	Customized Interior Completion - ASN 9308	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	STC Twenty One Ltd Master Document List No S21.MDL-0794 Issue 1STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0084 Issue 1Midcoast Aviation Inc. Instructions for Continued Airworthiness No35-027E205or later revisions of the above listed documents approved by EASA	Restricted to ASN 9308	05/07/2011	Active	10035624
10035635	HELI AUSTRIA GmbH	REV. 2		AS 355 F1, AS 355 F2	Compliance of C20R installation with BCAR Section G and confirmation ofability of C20R to fly one engine inoperative profiles.Reason for Rev. 1: transfer of STC to Heli Austria GmbHReason for Rev. 2: Limitation to helicopter serial numbers	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: BCAR Section GThe requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	AS 355 F1 SUPP 11.2 – Take-off and Landing Procedures and PerformanceData on Clear Airfield and Helipad with One EngineInoperativeAS 355 F2 SUPP 11.2 – Take-off and Landing Procedures and PerformanceData on Clear Airfield and Helipad withOne Engine InoperativeOr later revisions of the above listed...	Limited to serial number 5161 & 5478Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/04/2023	Active	10035635
10035636 (2003-1912)	BRUCE AEROSPACE Inc.		FAA STC SA6011NM	CL-600-2B16	Installation of Floor Proximity Emergency Escape Path Marking System	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Bruce Aerospace Master Drawing List CL600, Revision CE, Item 41, dated12 December 2006.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	This system has been determined to comply with the applicableairworthiness requirements with the following operative lightassemblies:- Floor Mounted Proximity Lighting SystemExit identifiers and/or flood lights - 2 bulbs operative, light trackred modules - 50% operative (1 bulb in each 2 bulb groupe...	06/07/2011	Active	10035636
10035638	LUFTHANSA TECHNIK AG			A318-112	A318-112 - ELITE 16 MSN 4503Installation of a VIP Cabin Interior Completion.	Certification Basis in accordance with EASA Type Certificate Data SheetsA.064.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. CRI A-5301-010 "EASA Supplemental Type Certification Basi...	- Supplemental Type Definition Document, ref. Doc. No STDD00-10/24M,issue 01 revision 02, dated Jul. 01/ 2011,- Airplane Flight Manual Supplement, ref. Doc. No. A-00-10/258-AFM issue01 revision 02, dated May 31/ 2011,- Instructions for Continued Airworthiness, ref. Doc. No.A-00-10/258-ICA, issue 01-...	Not applicable	06/07/2011	Active	10035638
10035643 (EASA.IM.A.S.02343)	LEARJET Inc.		FAA STC ST01239LA-D	CL-600-2B16	FAA STC ST01239LA-D, Complete Custom Aircraft Interior	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	FAA STC No. ST01239LA-D dated 02 December 2002.Learjet Inc.Master Document List DC55415000 Revision E dated 02December2002 or later approved revision.Airplane Flight Manual Supplements required for this installation arelisted on the Electrical Drawing Index, TM4500-5124, as listed on theMaster Doc...	Restricted to ASN 5541.A concurrent requirement to this STCis the installation of BruceAerospace EASA STC No. 10035636(FAA STC SA6011NM) (ref. EASA PN0010011393) Floor ProximityEmergency Escape Path Marking System.	06/07/2011	Active	10035643
10035661	BUSINESS AND COMMUTER AIRCRAFT			B200	Installation of a ADF60 on a Beech 200	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	none	none	08/07/2011	Active	10035661

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035662	BUSINESS AND COMMUTER AIRCRAFT			B200	Installation of a ALT4000 on a Beech 200	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	none	none	08/07/2011	Active	10035662
10035665	BUSINESS AND COMMUTER AIRCRAFT			B200	Installation of a DME4000 on a Beech 200	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	none	none	08/07/2011	Active	10035665
10035668	SKY IMD Inc.	REV. 1		SEE APPROVED MODEL LIST	Installation of Sensor Pod and wiring for passenger operated monitoringsystem	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List (MDL) Document No. PD01 revision H, dated December13, 2010.Approved Model List (AML) No. SA02248LArevision A, dated February 16,2011Instructions for Continued Airworthiness (ICA) Document No. 622 revisionE, dated November 15, 2010.Flight Manual Supplement PD45, revision IR, dat...	This STC is for installation of the sensor pod and wiring from thesensor pod into fuselage. This STC does not include power to the sensorpod or the sensor control unit.Limitationsas defined in the applicable Aircraft Flight ManualSupplements.	08/07/2011	Active	10035668
10035671	ADAC LUFTFAHRT TECHNIK GmbH			EC135 T2(CPDS) EC135 T2+ EC135 T1(CPDS) EC135 T1(CDS) EC135 P2(CPDS) EC135 P2+ EC135 P1(CPDS) EC135 P1(CDS)	Installation of fixed Landing Lights on the forward crosstube.Installation of a second fixed landing light on the forward cross tubeas defined in the MDL EC135-01072-001-LMD and based on ALT changeproject EC135-01072.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement:-,,EC135-01072-025-MFS-00 Rev. 0orlater revisions of the above listed documents approved by EASA.-EC135-01072-023-MMS Rev. 0 Instructions for Continued Airworthiness<(>,<)>- EC135-01072-004-DIN Rev. 0 Installation Instructionsor later revisions of the above listed document...	None	08/07/2011	Active	10035671
10035677	MARSHALL OF CAMBRIDGE AEROSPACELIMITED	REV. 4	CAA UK RESPONSIBILITY	A318-112	“Installation of an Auxiliary Fuel Centre Tank system on A318-112aircraft”Major Change to EASA STC10035677 Rev 3This Major Change covers the introduction of a change to A318 ACTSupplement to Maintenance Manual document N° MTM 0167.It removes the maintenance task MA281100-1-01 requiring the leak moni...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Certification Review Item CRI A-5301-009EASA Supplemental Type Certification Basis for A318 Auxiliary FuelCentre Tank SystemThe requirements for environmental protection a...	Certificate of Design doc. N° CD/A318(2179)/14/0925 Issue 1dated22/05/2015Airplane Flight Manual Supplement doc. N°AFM/A318(1778)/ 10/0943 Rev 4dated 14/02/2014Instructions for Continuing Airworthiness – Supplement to MaintenanceManuals doc. N° MTM 0167 Rev 9 dated 31/03/2015or later revisions of th...	Restricted to A318-112 aircraft with Airbus modifications 151462 and151387 embodied.Installation on aircraft fitted with a Flammability Reduction System isonly approved when Airbus modifications 152986 and 151311 have beenembodied on the aircraft.	31/05/2016	Active	10035677
10035678	CALEDONIAN AIRBORNE SYSTEMS LTD		CAA UK RESPONSIBILITY	JETSTREAM 4100	Installation of Role Equipment for Maritime Patrol Training	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI C-02, Installation of Standard Passenger Seats in a ReconfiguredCabin Layout.The certificated noise and/ or emissions levels of the o...	Caledonian Airborne Systems Compliance Document and AccomplishmentInstructions, F005/222/001, Issue F dated 7th July 2011.Caledonian Airborne Systems Flight Manual Supplement F014/222/001 IssueB dated 14th June 2011or later revisions of the above listed documents approved by EASA	Serial numbers 41022 and 41025 only.	11/07/2011	Active	10035678

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035689	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BAE 146 SERIES 200	EWIS Assessment for VIP Cabin Interior	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Electronic Wiring Interconnection System (EWIS) requirements in CS-25Amendment 8 Appendix H, paragraph H25.5 and AMC Appendix H paragraph...	Modification TEN 664, EWIS Assessment for VIP Cabin Interior EASA STC10027954. Tenencia Ltd document number TEN 664, Issue 1 dated 25thJanuary 2011.Aviation Traders Limited VIP Cabin Interior Modification Summary SheetIssue 2 for MOD-11193-00001.or later revisions of the above listed documents appro...	Serial number E2079 only.	12/07/2011	Active	10035689
10035701	BOMBARDIER INC.	REV. 1	TCCA STC NO. SA11-30	BD-700-1A11 BD-700-1A10	Installation, Portable Water System UV Filter	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Transport Canada STC No. SA11-30 Issue 1 dated 13 April 2011.ACS-NAI Ltd. Modification Data Summary G560000 Revision NCor laterapproved revision.ACS-NAI Ltd. Instructions for Continued Airworthiness G560070-ICARevision NC or later approved revision.or later revisions of the above listed documents a...	Prior to the installation of this modification it must be determinedthat the aircraft interior has been approved by theissuance of an EASASTC that corresponds to one of the Transport Canada STCs listed onTransport Canada STC No. SA11-30.	14/07/2011	Active	10035701
10035704	BOMBARDIER INC.		TCCA STC NO. C-LSA11-025/D	BD-700-1A11	Installation, Avionics Systems	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Transport Canada STC No. C-LSA11-025/D Issue 1 dated 07 July 2011.ACS-NAI Ltd. Modification Data Summary G732000 Revision NC or laterapproved revision.Bombardier Aerospace Flight Manual Supplement for V/UHF Radio, TACAN andDual Mode S/IFF Transponder System, G-FM25104502 Revision A or lateraprovedB...	1. Restricted to ASNs 9395, 9404, 9411, 94172. Embodiment of EASA STC No. 10034902 (Transport Canada STC No.C-LSA11-024/D)	13/07/2011	Active	10035704
10035711	BOMBARDIER INC.		TCCA STC NO. C-LSA11-022/D	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASNs 9395, 9404, 9411,9417	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Transport Canada STC No. C-LSA11-022/D Issue 1 dated 13 May2011.ACS-NAI Ltd. Modification Data Summary G729000 Revision NC or laterapproved revision.Bombardier Aerospace AirplaneFlight Manual Supplement for InteriorCompletion, G-FM25004503 Revision NC or later approved revision.Bombardier Aerospac...	1. Restricted to ASNs 9395, 9404, 9411, 9417.2. Embodiment of EASA STC No. EASA.IM.A.S.02172	13/07/2011	Active	10035711
10035712	BOMBARDIER INC.		TCCA STC NO. C-LSA11-023/D	BD-700-1A11	Installation, Medical Evacuation Configuration Provisions	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Transport Canada STC No. C-LSA11-023/D Issue 1 dated 13 May2011.ACS-NAI Ltd. Modification Data Summary G730000 Revision NC or laterapproved revision.Bombardier Aerospace Flight Manual Supplement for the Provisions forMedical Evacuation Configuration, G-FM25004504 Revision NC or laterapproved revisi...	1. Restricted to ASNs 9395, 9404, 9411, 9417.2. Embodiment of EASA STC No. 10035711 (refers to PN 0010007349)(TransportCanada STC No. C-LSA11-022/D)	13/07/2011	Active	10035712

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035729	MARSHALL OF CAMBRIDGE AEROSPACELIMITED	REV. 2	CAA UK RESPONSIBILITY	A340-313	Iberia Airways Interior Reconfiguration	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS25 Amendment 10, except for CS 25.785 (b)(d) requirements whichretain the Certification Basis iaw EASA A. 015 TCDS.The requirements forc...	Certificate of design CD/ A340(1941)/11/0290 Issue 1or laterrevisions of the above listed documents approved by EASA	1. This STC must be installed in conjunction with EASA STC No.EASA.A.S.00654.2. This STC is limited to the aircraft MSN125, 134, 145, 146, 217, 221,and 329	16/07/2012	Active	10035729
10035731	ASSOCIATED AIR CENTER, L.P.	REV. 1	FAA STC ST10906SC-D	A319-115	Installation of an Executive Style InteriorEASA validation of FAA STC ST10906SC-D	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA CRI A-4301-009 (STC Certification Basis)The requirements for environmental protection and the associatedcertificated noise and/ or em...	Master Data List doc. N° 2634000000 Rev. B dated July 19, 2011.Instructions for Continued Airworthiness doc. N° 2634050090 Rev. A datedDecember 22, 2010.Airplane Flight Manual Supplement doc. N ° 2634021090 Rev. B dated July18, 2011.EASA Compliance Checklist doc. N° 2634000095 Rev. A dated July 13, 2...	restricted to MSN 3542	19/07/2011	Active	10035731
10035741	NORTHERN AVIONICS S.R.L.	REV. 1		AW109SP	Installation of In-flight Entertainment System (IES) (composed by kitP/N KNAV-419 and KNAV-420)Certificate rev. 1 issued due to change of Modification BulletinRevision level.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Bulletin NAV-437, Rev. 1, dated 13 October 2011	Must be installed in conjunction with Northern Avionics kitP/N KNAV-418	21/10/2011	Active	10035741
10035777	BOMBARDIER INC.		TCCA STC NO. SA05-60	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9418	EASA TCDS No IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certific...	TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.Aero Consulting Services Ltd Configuration Definition List E025000Revision EV dated 15 June 2011.Bombardier Aerospace Aeroplane Flight Manual Supplement G-FM25004501Revision N/C or later approved revision.GC94180000-IFCA Instructions for Continued Airw...	Restricted to ASN 9418	19/07/2011	Active	10035777
10035779	AIR ALLIANCE GmbH			PA-42-720	Extension of pressurized fuselage life limit to account forthe changein operational usage from Alitalia Airlines Training to Normal Usage byany operatorNote: This STC indicates the transfer of an applicable S/N from STCEASA.IM.A.S.02278 Rev 2 to this STC holdership by AirAlliance	The Certification Basis for the original product remains applicable tothis certificate/ approval.FAR 23 Amdt 1 to 16Therequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalproduct areunchanged and remain applicable to this certifica...	Air Alliance GmbH Report No AARD-1, Rev A dated 28 Dec 2006"AirAlliance PA-42-720 Aircraft - Fuselage Life Substantiation"Air Alliance GmbH Report no AARD-2, Rev B dated 28 Dec 2006 "AirAlliance PA-42-720 Aircraft - Pressurized Fuselage Cabin Instructionsfor Continued Airworthiness"AirAlliance MDLo...	This STC is limited only to airplane S/N 42-5501045 operated by anyoperator.Operation in normal usage up to a life-limit of 21.563 hours for S/ N42-5501045.Air Alliance GmbH ReportNo AARD-2 Rev B dated 28 Dec 2006 "Air AlliancePA-42-720 Aircraft - Pressurized Fuselage Cabin Instructions forContinued...	19/07/2011	Active	10035779
10035798	BOGGI S.R.L.			AS365N3	Installation of Draeger TI 500 "Globetrotter" incubator on AS 365N3(ref. Change 365-M003-00).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Boggi s.r.l. Rotorcraft Flight Manual Supplement 365M00300-FMS-01, issue1 dated 24th June 2011or later revisions of theabove listed document approved by EASA-Boggi s.r.l. Master Document List (MDL) 365M00300-MdL-02, issue 2 dated14th July< (>,<)> 2011.-Boggi s.r.l Installation Service Bulletin 365M0...	Limited to:-Incubator model Draeger TI 500 P/N TI 500, S/N 002-Helicopter model AS365N3 S/N 6609 & 6356	19/07/2011	Active	10035798

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035812	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03906AT	CL-600-2B19	Installation of EMTEQ LED Anti-collision/ Position (Navigation) Light inthe Bombardier Regional Jet Series 100/200/440 Aircraft.Revision 1 transferred from EMTEQ Engineering to B/EAerospace.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC No. ST03906AT dated 04 February 2011.-EMTEQ Engineering Master Drawing List 2-83710-001 Revision B dated 28December 2010-Instructions for Continued Airworthiness (ICA), EMTEQ EngineeringDocument No. 2-83710-805 Revision B dated 28December 2010or later revisions of the above listed document...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10035812
10035813	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA STC Q-LSA06-059/D	BD-700-1A10	Cabin Management System Upgrade - ASN 9020	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	-Transport Canada STC No. Q-LSA06-059/D Issue 4 dated 31 August 2009.-Kmlex Aviation Master Document List No. MDL26147002 - Cabin ManagementSystem Upgrade on Global Express, ASN 9020, Revision C, dated 31 August2009 or later approved revision.-Kmlex Aviation Time Limits and Maintenance Checks No. TL...	Restricted to ASN 9020	19/07/2011	Active	10035813
10035880	SABENA TECHNICS BGC			B777-300, B777-300ER B777-200, B777-200LR	0555-01: Provisions of OnAir GSM/ Internet System on B777	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.-CS 25 Amdt. 4-CRI H-1 - ICA on EWISThe certificated noise and/ or emissionslevels of the original productare unchanged and remain appli...	0555-01 "Provisions of OnAir GSM/Internet System on B777"-Master Document List 555-01-A-2103-R01 dtd. 04.Jul. 2011-Instructions for Continued Airworthiness 555-01-A-2211-R00 dtd. 04.Jul.2011or later revisions of the above listed documents approved by EASA	None	25/07/2011	Active	10035880
10035883	BRISTOW U.S. L.L.C.	REV. 1	FAA STC SR09577RC	S-76A, S-76C	Installation of an Automatic Deployable Emergency Transmitter (ADELT).Rev. 1: Changes 'System interface Unit' p/n to 503-24-A to comply withEASA AD 2014-0095R1.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: As per TCDSEASA.IM.R.113<(>,<)> plus CS 29.610, Amdt. 2.The requirements for environmental protection and the associatedce...	Rotorcraft Flight Manual Supplement, RFMS-76-2009-01, Rev IR<(>,<)>or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2017	Active	10035883
10035887	FIELD AVIATION COMPANY Inc.	REV. 1		DHC-8-301/-302 DHC-8--201/-202 DHC-8-102/-103/-106	Auxilliary Power Unit (APU) RemovalTCCA STC SA98-30, Issue 3	FAR 25 as per EASA.IM.A.191, Issue 4 (incl. SC H-01 ICA on EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areuncha...	-APU removal in the DHC-8-100 and 200 series must be done in accordancewith TCCA approved Field Aviation Company Inc. Engineering Order 141103,Revision G, dated 29 June 2005.-APU removal in the DHC-8-300 series must be done in accordance withTCCA approved Field Aviation Company Inc. Engineering Orde...	The modification is applicable only when the necessary structuralprovisions are pre-existing	28/07/2011	Active	10035887

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035902	HAECO CABIN SOLUTIONS, LLC		FAA STC ST00552AT	B747-400 SERIES	Installation of a Collins Satcom update from 900 SDU to 906SDU (dataonly) in accordance with Page Avjet Master DrawingList 94-17, InitialRelease, dated June 17, 1994, or later FAA approved Revision. ,,	The Certification Basis for the original product remains applicable tothis certificate/ approval.,,	Master Drawing List Page Avjet 94-17, Initial Release, dated June 17,1994or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	26/07/2011	Active	10035902
10035914	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	777-200	Introduction of an Aerospace Cockpit Door and Cabin Surveillance onBoeing 777-200.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-1-ICA on EWISThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this cer...	- H4A1332 Issue 2 dtd. 17. June 2011 Modification Summary- H4AFMS021 Issue IR dtd. 2. June 2011 Flight Manual Supplement- H4ADR547 Issue 1 dtd. 8. December 2010 Instructions for ContinuedAirworthinessor later revisions of the above listed documents approved by EASA	none	27/07/2011	Active	10035914
10035915	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.	REV. 1	FAA STC ST10903SC-D	A319-133	Modification of an Executive Interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Document List, Associated Air Center document No. 2708000000,Revision A dated 30 November 2017.2. Airplane Flight Manual Supplement (AFMS), document No. 2708021090,Revision IR dated 27 October 2010.3. Instructions for Continued Airworthiness, Associated Air Centerdocument No. 2708050090<(>...	The items identified in document "Summary of Commercial OffThe Shelf (COTS) Nonessential Equipment", document number 1689R25M02, Revision IRdated 13 October 2010, are considered inadequate for duplication and islimited to aircraft Serial Number 910 only.The wireless LAN installation is intended to p...	13/02/2018	Active	10035915
10035923	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			C90	Installation of a passenger information display, a Sigma-Tek 5000B-36attitude indicator, a Garmin GMA 340 audio panel, a Collins ADF-60Anavigation system, a Garmin GTX 330 transponder, a Garmin G600 primaryand navigation system with coupling to automatic pilot for BRNAV, PRNAVand RNP APCH-LNAV opera...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 23-867, 1301, 1303, 1309, 1311,CRI B5...	AFM supplement Garmin G600 ref. SEAM/SMV/ 3381/10-2, Revision 2 dated20/07/2011AFM supplement GNS 430 W ref. SEAM/SMV/3381/10, Revision 2 dated20/07/2011SEAM modification sheet n° 3381/10, Revision 2 dated 20/07/2011or later revisions of the above listed documents approved by EASA	This STC is limited to airplane s/n LJ-972.RNP APCH-VNAV and LPV Approach operations are not authorised.A third radionavigation or radiocommunication system independent fromGNS 430 W units must be installed.Mechanical instruments must be installed to back-up airspeed, altitudeand attitude indication...	27/07/2011	Active	10035923
10035929	LIBERTY AEROSPACE INC.		FAA STC SA03488AT	XL-2	S-TEC system 30 autopilot installation on Liberty XL-2 series inaccordance with the following:Option 1 (for use with S-Tec Model ST-901 GPS Steering Converter Unit):Chippewa Aerospace Master Data List (MDL) n° XL2-2210-01-0001, revision4, dated November 20, 2008 or later FAA approved revision, orOpt...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	AFM Supplement for S-TEC System 30 autopilot (DG Only) P/N 135A-970-530Initial releaseAFM Supplement for S-TEC System 30 autopilot integrated with an AspenEFD1000 PFD/MFD P/N 135A-970-531 Initial releaseor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decis...	Option 1: Chippewa Aerospace Inc Document XL2-2210-01-0002 Rev IR, datedJune 18, 2007<(>,<)> or later FAA approved revision - Instructions forContinued Airworthiness (ICA).Option 2: Liberty Aerospace Document 135A-970-110, rev D. dated July 19,2010, or later FAA approved revision - Instructions forA...	28/07/2011	Active	10035929

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035939	FIELD AVIATION COMPANY Inc.			DHC-8-102/-103/-106	Installation of Right Hand Ground Air ConnectionTCCA STC C-LSA11-043/D, Issue 1	FAR 25 as per EASA.IM.A.191, Issue 4 (incl. SC H-01 ICA on EWIS)The approval holder shall fulfil the obligations of Part 21, Paragraph21.A109.The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associa...	Installation of the Right Hand Ground Air Connection must be inaccordance with Transport CanadaCivil Aviation (TCCA) app roved Field Aviation Modification Instruction218210, Revision IR, dated July 21, 2010Maintenance of the Ground Air System is unchanged from the instructionsprovided in the Bombard...	OEM installed APU must be removed in accordance with EASA STC 10035887or TCCA STC SA98-30, Issue 3.	29/07/2011	Active	10035939
10035941	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BD-700-1A11	Cabin Reconfiguration	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Jet Aviation Declaration of Compliance No. 2011-3 dated 27/07/11.Jet Aviation Engineering Order No. 2011-3 Revision A.or later revisions of the above listed documents approved by EASA	Restricted to ASN 9166A prerequisite for this approval is Transport Canada STC No. SA05-60(FAA STC No ST02140NY) as applicable to ASN 9166. However EASA has notapproved this STC for ASN9166 and if this aircraft is to be entered onan EU register then the STC must be approved by EASA.For Non-EU Countr...	29/07/2011	Active	10035941
10035945 (EASA.A.S.03607)	AIRBUS DEFENCE AND SPACE S.A.	REV. 19		A330-243	A330 MRTT FSTA Modification STC2Rev. 1 introduces the following changes:- Deletion of previous limitation no. 4 on Autoland / CAT III function- Replacement of temporary conservative Noise levels by final values- Partial deletion of previous limitation no. 1 on occupation of seatsin the aeromedical a...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.0853 InitialIssue for affected areas by change DCV1086-EThis certificate/approval involves a change wit...	- “Conversion Definition A330MRTT FSTA (STC2)” document ref. ME-FU-DT110148 issue D- ALS Part 1 Supplement “A330 FSTA Safe-Life Airworthiness LimitationItems Supplement for EASA STC2”, doc. no. ME-FU-DT-110099 Issue F- TE-FU-DT-220004 'Variation 01 to Issue F of A330 FSTA Safe-LifeAirworthiness Limi...	- Based on the conditions established in CRI G-01 with respect to thedefinition of the Airworthiness Limitation Sectionof the ContinuedAirworthiness the following limitations apply:1. As the modifications of this STC are intended for military role, nooperation in the civil register of the aircrafti...	17/01/2024	Active	10035945
10035962	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA02930CH	CESSNA 208, 208B	Air Ambulance Conversion in accordance with Spectrum Aeromed DrawingList	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved Master Drawing List, Doc. No. 6006DL, Rev. 3, dated 24 Jan2011<(>,<)>FAA approved Aircraft Flight Manual Supplement, Doc. No. 6006FMS, Rev.-, dated 30 Nov 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent r...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/04/2019	Active	10035962
10035987	AIR ALLIANCE GmbH			LEARJET 35A	Installation of Honeywell GNS-XLS second FMS system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Air Alliance Master Document List 2011_006_LJ35 AA Form 2 Rev. 0;Aeroplane Flight Manual Supplement No: AA 2011_006_LJ35_0506 dated May13, 2011or later revisions of the above listed documents approved by EASA.	Limited to 35A-421 and 35A-616.	03/08/2011	Active	10035987

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10035996	AIRBUS HELICOPTERS, Inc.		FAA STC SR09306RC-D	MBB-BK 117-C2	Installation of tailboom mounted aft ballast in accordance with AmericanEurocopter Drawing List 145A82-8006.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Flight Manual Supplement 117FMS-224, Rev. A dated 17 Mar 2009or later revisions of the above listed documents approvedby EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)- AEC Drawing List 145A82-8006, Revision B, dated 21 March 2007- Instructions for Conti...	None	03/08/2011	Active	10035996
10036025	AEROTEC & CONCEPT			PA 30	PFD ASPEN EFD 1000 PRO INSTALLATION on Piper PA 30.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Data List « INSTALLATION PFD ASPEN EFD 1000 PRO SUR PIPER PA 30 »Ref. AE 1010 MDL Rev. 5 dated 10/02/2011Installation in accordance with SERVICE BULLETIN Ref. AE 1010 SB Rev. 0dated 02/04/2011Maintenance in accordance with the Instructions for ContinuousAirworthiness « INSTRUCTIONS POUR LE M...	In case of malfunction of the Aspen EFD 1000 Pro PFD or divergence ofindications, use standard instruments for reference.AHRS reset prohibited in flight.LPV Approaches are not authorized.RSM GPS to be used only in case of emergency.	05/08/2011	Active	10036025
10036039	MID-CANADA MOD CENTER			CESSNA 550, S550	Installation of Rockwell Collins Proline 21 Integrated Display Systemwith new VHF communication transceivers, Navigation Receivers withintegral ADF, Distance Measuring Equipment Transceivers and Mode STransponders with Elementary Surveillance capability, Rockwell CollinsTCAS 4000, dual AHRS 3000San...	EASA TCDS IM.A.207The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI F-02: Airworthiness Criteria for RNAV Equipment supporting LPVOperationsCRI F-03: Airworthiness Criteria for RNAV E...	Avionics Design Services Ltd. Master Drawing List MDL09001 Issue 1,Revision B from 29 July 2011Mid Canada Mod Center Flight Manual Supplement FMS09001-1 Revision Afrom 29 July 2011Avionics Design Services Ltd. Instructions for Continued AirworthinessICA09001-1 Revision 1 from 01 March 2010.or latera...	None	08/08/2011	Active	10036039
10036054	BOMBARDIER INC.	REV. 1	TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9406	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	TCCA STC SA04-113 Issue 1 dated 28 October 2004Aero Consulting Services Configuration Definition List D954000 RevisionHL dated 13 July 2011Instructions for Continued AirworthinessGC94060000-IFCAor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004...	Restricted to ASN 94061. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS2. WLAN system is compatible only to IEEE 802.11(b)	08/08/2011	Active	10036054
10036058	BOMBARDIER INC.		TCCA STC SA05-60	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9421	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.Aero Consulting Services Ltd Configuration Definition List E025000Revision FC dated 22 July 2011.Bombardier Aerospace Aeroplane Flight Manual Supplement G-FM25004501Revision N/C or later approved revision.GC94210000-IFCA Instructions for Continued Airw...	Restricted to ASN 9421	09/08/2011	Active	10036058

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036059	B/E AEROSPACE, Inc. - FSI		FAA STC SA5738NM	B747-400	Installation of an extended upper deck crew rest in accordance withFlight Structures Inc. Master Drawing List 90SF004-D01, Revision E,dated July 13, 1992, or later FAA approved revisions.Validation of FAA STC SA5738NM. ,,	The Certification Basis for the original product remains applicable tothis certificate/ approval.	None.	None.	09/08/2011	Active	10036059
10036060	BOMBARDIER INC.	REV. 1	TCCA STC SA04-113	BD-700-1A10	Installation of cabin systems and custom furnishings applicable toBD-700-1A10 serial number 9393	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionHH dated 22 June 2011.Instructions for Continued Airworthiness GC93930000-IFCA.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decisi...	Restricted to ASN 93931. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS. 2.WLAN system is compatible only to IEEE 802.11(b).	09/08/2011	Active	10036060
10036061	AMAC AEROSPACE SWITZERLAND AG			B737-700IGW	VIP seat change / Replacement of single seat by one with massagefeature.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Data List: MDL-AY01-2520 rev. B dated 20.01.2011or later revisions of the above listed documents approved by EASA.	This approval is limited to Aircraft B737-700IGW, Serial Number 36027.	09/08/2011	Active	10036061
10036081	ASSOCIATED AIR CENTER, L.P.	REV. 2	FAA STC ST10897SC-D	B737-700	Change to EASA STC 0010036081 (Installation of an ExecutiveInterior onB737700IGW aircraft : Project No.AAC-08-06-DAS):Installation of theERDA Model 4402 Single occupant Side facing divan.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI A-01 Issue 3dated April 18, 2011: EASA Supplemental TypeCertification Basis for Associated Air Center B737-700 "Perolux"Executive Ca...	- Certification Plan, Reference 2964000090, initial revision, dated 27October 2011- Airplane Flight Manual Supplement, Reference 2582021090, Revision A,dated 12 November 2010- Master Data List, Reference 2582000000, Revision C, dated 19 April2012- Instructions for Continued Airworthiness, ReferenceR...	1) This approval is limited to Aircraft B737-700, Serial number 36027.2) The aircraft operator must perform the instructions for continuedairworthiness and comply with the Airworthiness Limitation Items as perthe Instruction Continued Airworthiness, Reference 2582050090, RevisionD, dated 9 January 2...	29/06/2012	Active	10036081
10036090	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		TCCA STC O-LSA07-336/D	BD-700-1A10	ICG BD700 Satcom Upgrade.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. O-LSA07-336/D Issue 1 dated 18 December 2007.Innotech Aviation, a Division of IMP Group Ltd. Master Drawing ListMLGX-9028-126 Revision N/C, dated 18 December 2007, orlater approvedrevision.Maintenance must be in accordance with Innotech Aviation, a Division ofIMP Group Ltd. Instruction...	Restricted to ASN 9028.	10/08/2011	Active	10036090
10036091	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		TCCA STC O-LSA08-197/D	BD-700-1A10	Software and DLNA Upgrade to Existing HSD-400 Satcom Installation.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. O-LSA08-197/D Issue 1 dated 29 August 2008.Avionics Design Services Ltd. Master Drawing List MDL08080 Revision N/ Cdated 29 August 2008 or later approved revisionor later revisions of the above listed documents approved by EASAinaccordance with EASA ED Decision 2004/02/CF (or subsequent...	Restricted to ASN 9028.	10/08/2011	Active	10036091

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036095	BOMBARDIER INC.		TCCA STC C-LSA01-452/D	BD-700-1A10	Interior Modification - ASN 9020 - Installation, Modifications to APUBay Light, Galley Oven, Smoke Detector Wiring and Equipment BayProvisions	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No C-LSA01-452/D Issue 3 dated 02 June2011.Aero Consulting Services Modification Data Summary Number D21500Revision A dated 02 June 2011 or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (o...	Restricted to ASN 9020.Previous embodiment of EASA STC No. 10016140 (refers to PN 0010011877) (Installation of a Complete Custom Aircraft Interior in accordance withFAA STC SA8164NM-D) is mandatory.	10/08/2011	Active	10036095
10036096	BOMBARDIER INC.		TCCA STC Q-LSA02-065/D	BD-700-1A10	Miscellaneous Cabin Modifications	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No Q-LSA02-065/D Issue 2 dated 05 August 2003.Aerocas Master Document List MDL02164002 - Miscellaneous CabinModifications on Bombardier Global Express BD-700-1A10, ASN 9020,Revision A dated 16 July 2003.or later revisions of the above listed documents approved by EASA inaccordan...	Restricted to ASN 9020.Previous embodiment of EASA STC No. 10016140 (refers to PN 0010011877) (Installation of a Complete Custom Aircraft Interior in accordance withFAA STC SA8164NM-D) is mandatory.	10/08/2011	Active	10036096
10036101	ACS-NAI Ltd.		TCCA STC C-LSA11-134/D	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9412	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. C-LSA11-134/D Issue 1 dated 03 August 2011.ACS-NAI Ltd. Modification Data Summary H039000 Revision NC or laterapproved revision.ACS-NAI Ltd. Airplane Flight Manual Supplement for the Complete CustomAircraft Interior, G789091 Revision B or later approved revision.Instructions for Continu...	Restricted to ASN 9412.The Wireless Local Area Network (WLAN) system is intended to provideinternet connectivity and email services to the airplane's cabin usingportable electronic devices (PEDs). Any other intended function of thisequipment will require a re-examination of the certification basis.E...	11/08/2011	Active	10036101
10036102	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		DA 40, 40D, 40F	Installation of PFD Aspen EFD1000 PRO.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS-23, Amendment 2.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the or...	Flight Manual Supplement ASR-2010-069-FMS-05-00, Rev.00or later revisions of the above listed documents approved by EASA.Instructions for Installation: ASR-2010-069-IFI-10-00, Rev. 00Instructions for Continued Airworthiness: ASR-2010-069-ICA-11-00, Rev.00	None.	17/08/2011	Active	10036102
10036103	AERODATA AG	REV. 1		B300	Installation of Aerodata Automatic Flight Inspection SystemAD-AFIS-112.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS-23, Amendment 2.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the or...	- Flight Manual Supplement: AFM-126, Rev. 1- Installation Manual HB-A/C-1101, Rev. 0- Master Document List MDL-A/C-0161, Rev. 2- Maintenance Manual Supplement AMM-1099, Rev. 1or later revisions of the above listed documents approved by EASA.	None.	16/08/2011	Active	10036103

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036110	BINDER MOTORENBAU GmbH			ETA		Design:Non-significant changeThe Certification Basis of theoriginal product remains applicable tothis change.Environmental Protection:The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Binder Motorenbau STC "eta Umrüstung SKB" 12.02.2011Beschreibung der Umrüstung und Zeichnung eta 2.023aErgänzung des Flughandbuches betreffend STC "Umrüstung SKB" für denMotorsegler eta 12.02.2011.	None.	11/08/2011	Active	10036110
10036114	AIRWOLF AEROSPACE L.L.C.	REV. 1	FAA STC SR02964CH	206L-1, 206L-3, 206L-4 206A, 206B, 206L	TENSION-TORSION STRAP - REPLACEMENT OF LIFE-LIMITED PARTAmended Airworthiness Limitation Section of the Instruction forContinued Airworthiness AA-206-ICA	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airworthiness Limitation Section of the Instruction for ContinuedAirworthiness AA-206-ICA Rev. E, FAA Approved on 19 November 2012;or later revisions of the above listed documentsapproved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Tec...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/02/2013	Active	10036114
10036121	LUFTHANSA TECHNIK AG			B747-400 SERIES	Replacement of Global Positioning System Sensor Unit and GPS Antenna.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Lufthansa Supplemental Type Definition Document STDD34-10/05M Issue 1,Rev 0, dated Aug. 11, 2011.Compliance Record ListCRL34-10/05M Iss01 Rev0 dated 11 August 2011.ICA A-00-11/029_ICA Iss01 Rev IR dated 25 March 2011.or later revisions ofthe above listed documents approved by EASA.	None.	19/08/2011	Active	10036121
10036123	CLIPPER AVIATION, Inc.		FAA STC ST02318NY	B747-400	Installation of seating configuration on Upper Deck of B747-400 Boeingconverted Special Freighter	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Master Data List CLI-2006-003, Revision D, dated May 23, 2011Airplane Flight Manual Supplement CLI-2007-015 Rev. IRor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	12/08/2011	Active	10036123
10036129	airplus engineering GmbH	REV. 1		SEE EASA APPROVEL MODEL LIST SEE EASA APPROVED MODEL LIST	Installation of Honeywell EGPWS MK VI System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23 Amendment 02.The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	- Flight Manual Supplement: PO-1106-340000- Engineering Work Order: EW-1106-340000- Description of Modification: DE-1106-000000- Maintenance Manual Supplement: MM-1106-000000or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft must have been already equipped with a suitable display andsuitable sensors.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	10/02/2021	Active	10036129
10036149	AVIONIK STRAUBING ENTWICKLUNGS GmbH			SR20, SR22	Installation of a Primary Function Display Avidyne EXP5000	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	Flight Manual Supplement: ASR-2011-028-FMS-05-00or later revisions of the above listed documents approved by EASAInstructions for Installation: ASR-2011-028-IFI-10-00Instructions for Continued Airworthiness: ASR-2011-028-ICA-11-00	The aircraft must have been already equipped with suitable GPS system.	16/08/2011	Active	10036149

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036162	AIRLIFT A/S			EC130B4 AS350B3 AS350B2 AS350B1	Installation of Bendix/King KRA 405B Radar Altimeter.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Requirements of CS 27 at amdt. 2 are complied with by the modification.The requirements for environmental protection and the associatedce...	Airlift AS Master Document List MDL-130-34-100 revision 0 dtd08.08.2011.	AS350B3 - only aircraft with Arriel 2B and Arriel 2B1 engines installed.	17/08/2011	Active	10036162
10036188	VIDEO TECHNOLOGY SERVICES, Inc.		FAA STC ST03006NY	A340-200/300/600	Title: LCD Monitor SystemsDescription: Installation of LCD Monitors and Digital Player replacingCRT Monitors and Cassette Recorders in the same locations using the samemounting provisions, cables and connectors.Validation of FAA ST03006NY dated August 4, 2011.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Associated documents of Video Technology Services, Inc.:- Cert plan 205-D460 Rev B. Dated 20-5-2011- Master Technical List document 205-D-463 Rev B, dated 25-5-2011- Instructions for Continued Airworthiness 205-D-467 Rev.- dated2-3-2011	None.	18/08/2011	Active	10036188
10036196	MT-PROPELLER ENTWICKLUNG GmbH			B200CGT,B200CT,B200GT,B200T A200CT (RC-12H),B200,B200C A200CT (RC-12G) A200CT (FWC-12D) A200CT (C-12F),A200CT (RC-12D) A200 (C-12C),A200CT (C-12D) 200,200C,200CT, 200T,A200 (12A)	Installation of 5 blade MTV-27-1-E-C-F-R (P)/CFR225-55f propellers	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.14 CFR Part 23 Amdt. 1 thru Amdt. 34 (elected to comply by theapplicant)FAR 25.929 Initial Issue and FAR 25.1419 Amdt. 23 remain unchange...	E-2041; Airplane Flight Manual Supplement, revision 0, dated 21.06.2011E-2042: Installation Instruction, Revision 0, dated 21.06.2011E-2043: Instructions for Continued Airworthiness, Revision 0, dated21.06.2011or later revisions of the above listed documents approved by EASA	none	19/08/2011	Active	10036196
10036223 (EASA.IM.A.S.03107)	INNOVATIVE SOLUTIONS AND SUPPORT, I		FAA STC ST02165NY	B767-200/-300/-300F	Installation of Flat Panel Display System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate.For changed areas the certification basis is CS25 Initial Issue;25.301 - 25.303 - 25.305 - 25.307 - 25.561 - 25.601 - 25.60325.605 - 25.609 - 25.61...	Master Data List (MDL), Document 1D-07792, rev 11, 15/03/2011<(>,<) >Instructions for Continued Airworthiness (ICA), Document 1D-07793,Revision 6, 14/01/2011Aeroplane Flight ManualSupplement (AFMS), Document 1D-07125, Revision5, 28/07/2010or later revisions of the above listed documents approved bya...	Installation Configuration 6 approved only.The Smiths Aerospace Limited Integrated Standby Instrument System (ISIS)is not approved for installation under this STC.No earlier revisions of the listed documents are approved under thisSTC.	23/08/2011	Active	10036223
10036230	AVIONIK STRAUBING ENTWICKLUNGS GmbH			501, 551	Installation of a TAS SystemL3 Communication SKY899	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	Flight Manual Supplement: ASR-2011-009-FMS-05-00 rev. 00or later revisions of the above listed documents approved by EASAInstructions for Installation: ASR-2011-009-IFI-10-00 Rev. 00Instructions for Continued Airworthiness: ASR-2011-009-ICA-11-00 Rev. 00	The aircraft must have been already equipped with a suitableMultifunction Display.	23/08/2011	Active	10036230
10036231	AVIONIK STRAUBING ENTWICKLUNGS GmbH			208, 208B	Installation of a Satellite Antenna Chelton HGA-7000	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	Flight Manual Supplement: ASR-2011-012-FMS-05-00 Rev.00or later revisions of the above listed documents approved by EASAInstructions for Installation: ASR-2011-012-IFI-10-00 Rev. 00Instructions for Continued Airworthiness: ASR-2011-012-ICA-11-00 Rev.00	none	23/08/2011	Active	10036231

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036234	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	767-300	Omnibus Modification for the Approval of Air New Zealand EngineeringOrders Embodied on the A/C	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/or emissions levels of the original product areunchanged and remain applicable to this approval.	Master Document List, S21. MDL-0810, Issue 1, 15/07/2011or later revisions of the above listed documents approved by EASA	none	24/08/2011	Active	10036234
10036235 (EASA.IM.A.S.03066)	TELAIR INTERNATIONAL, LLC	REV. 1	FAA STC 02365LA	B747-8F	Lower Deck Cargo Handling System, Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/approval.EASA CRI A-100The requirements for environmental protection and the associatedcertificated noise and/or emissions levels of the original...	PSCP 192100CPP-8F and FAA STC 02365LAor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	26/08/2011	Active	10036235
10036236 (EASA.IM.A.S.03067)	TELAIR INTERNATIONAL, LLC	REV. 1	FAA STC 02367LA	B747-8F	Main Deck Cargo Handling System, Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/approval.EASA CRI A-100The requirements for environmental protection and the associatedcertificated noise and/or emissions levels of the original...	PSCP 193100CPP-8F and FAA STC 02367LAor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	26/08/2011	Active	10036236
10036239	AIRBUS S.A.S.			A320-200	Airbus Corporate Jet Centre Modification CJ1000 Issue 1 -VIP Interior - "RAFO 3".	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/approval:- CRI A 2301-004 "ACJC Centre Conversion Project Certification Basis".The requirements for environmentalc...	- Modification Approval Sheet, ref.: CJ1000, Issue 1, dated23rd August2011- AFM Supplement, ref.: FM-S MOD CJ1000, Revision 00, dated August 2011- Conversion Instruction, ref.: CI 00CJ007, Revision A, dated 25th July2011or later revisionsof the above listed documents approved by EASA.	This STC is limited to A320-214 MSN 4795.	24/08/2011	Active	10036239
10036250	RUAG AEROSPACE SERVICES GmbH			BD 100-1A10 (CHALLENGER 300)	Installation of EGPWS MK-V with Runway Awareness and Advisory System (RAAS).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate: CRI-RAAS issue 3 dated 19/08/2011.The requirements for environmental protection and the associatedcertificated noise and/or emissions levels of t...	- Master Document List (MDL) 326A-MDL dated 22/08/2011- Airplane Flight Manual Supplement 326A-FMS dated 5/08/2011or later revisions of the above listed documents approved by EASA.	None.	25/08/2011	Active	10036250
10036272	SABENA TECHNICS BGC	REV. 1		A340-311/-312/-313	A340 Cabin Reconfiguration & Zodiac SiT In-Flight EntertainmentInstallationThe modification consists in reconfiguring the A340 cabin compartment byreplacing the economy class seats, from 218 Y/C seats to 215 Y/C seatswith Sicma 3537 seriesseats, and installing Zodiac SIT In-FlightEntertainment syst...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/approval.CS 25 Amdt 4Except for the following requirements, which are as per TCDS EASA.A.015:-25.562<(>,<)>-Special Condition H-01: EWIS ICAThe re...	Master Data List, ref: 7048-01-A-2103-R02Instruction for Continued Airworthiness, ref: 7048-01-A-2211-R00or later revisions of the above listed documents approved by EASA	1. Aeroconseil Modification, ref: MOD 7049-01, must be installed<(>,<)>being a pre-requisite to this STC.2. This STC islimited to the A340-300 MSNs 197 and 378	09/08/2012	Active	10036272

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036296 (EASA.A.S.03809)	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			F90	STC 2465/08 Rev 5GNS530W TAWS - GNS530W - Radar GWX 68 - TAS KTA 870 Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Dossier 2465/08 Rev 5 dated 18 July 2011Supplément manuel de vol n· 1 SEAM/SMV/ 2465/08 Rev 5 dated 18 July 2011Supplément manuel de vol n· 2 SEAM/ SMV/2465/08 Rev 3 dated 9 October2009or later revisions of the above listed documents approved by EASA.	Limitation to Beech F90 equipped with SPZ200 autopilot and modifiedaccording SEAM STC 2589/09 Dual G600 Installation.	29/08/2011	Active	10036296
10036300	AMES - AEROSPACE AND MECHANICALEN GINEERING SERVICES			767-300	B767-300 Astronics EMPower 110VAC activation.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI H-01 Enhanced Airworthiness Programme for Airplane Systems - ICA onEWIS has been applied to the current changeJAA TGL 17 - PassengerJ...	The installation shall be performed in accordance with EngineeringBulletin EB_M15400110_MGR_200 42011, Revision 0The aircraft shall be maintained in accordance with Instructions forContinued Airworthiness document ICA_M15400110_DBE_190 52011, Revision 0The aircraft shall be operated in accordance with...	EASA STC EASA.IM.A.S.01257 must be installed prior to the accomplishmentof the changes of this approval, andThe installation of the In-Seat components is not covered with thisapproval and must be approved prior to the accomplishment of thechangesdetailed with this approval.	29/08/2011	Active	10036300
10036302	SIERRA INDUSTRIES Ltd.		FAA STC ST02363LA	HAWKER 800XP	Installation of Honeywell TFE731-50R Engines.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CAR 4b and FAR 25 as defined on the FAA STC certificate ST02363LAThis certificate/ approval involves a change to the requirements forenvi...	Installation in accordance with Sierra Industries, Ltd Master DrawingList No 201-005, Rev F dated July 13, 2011.Operation in accordance with Sierra Industries, Ltd Aircraft FlightManual Supplement No 201-191<(>,<)> dated August 09, 2011.Instructions for Continued Airworthiness in accordance with Sie...	Limited to Hawker 800XP aircraft fitted with Honeywell SPZ-8000 AvionicsSystem, and:Winglets installed under Hawker Beechcraft (HBC) Mod Kit 140-1703 -Service Bulletin 57-3810, EASA approval ref EASA.IM.A.C.01451.	30/08/2011	Active	10036302
10036324	AEROLITE AG	REV. 3		AW139 AB 139, AW 139	EMS Equipment P/N 139250-501 with Base Plate P/N 139252-501Rev. 2: Transfer to Aerolite AG.Rev. 3: New EMS Equipment P/N 139250-502 added.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement FMS-139250-501 Revision A, dated June 28, 2013Flight Manual Supplement FMS-139250-502 RevisionBAirworthiness Limitation AWL-139250-501 Revision N/Cor later revisions of the above listed documents approved by EASAMaster Document List MDL 10-009 Revision CMaster Drawing ListE...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/08/2025	Active	10036324
10036326	BLACKHAWK MODIFICATIONS Inc.		FAA STC SA01946LA	PA-31T, PA-31T1, PA31T2	Installation of Powerplant Indication System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation In Accordance with Blackhawk Modifications Master DrawingList ref 200815-000, Rev A, dated 12-07-09.Operation In Accordance with Blackhawk Modifications Aircraft FlightManual Supplement ref 55023-11, Rev C, dated February 23, 2010.Continued Airworthiness (ICA) as defined in Blackhawk Mo...	None.	01/09/2011	Active	10036326

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036328 (EASA.A.S.02566)	CONTINENTAL AEROSPACE TECHNOLOGIES	REV. 4		DA 40 D	Installation of engine TAE 125-02-114 in combination with propeller MTV6-A/ 187-129 or MTV 6-A/190-69Revision 1 follows a change of ownership.Revision 2 includes propeller MTV 6-A/190-69.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI A-01 for Diamond DA40, issue 21, dated22.09.2008Equivalent Safety Finding(s): CRI A-01 for Diamond DA40, issue 21, dated22.09.2008This certificat...	- Airplane Flight Manual Supplement for the DA 40 D with TAE 125-02-114engine installation, TAE Nr. 50-0310-50022, Issue 2, Revision 0- Anhang zum Flughandbuch Diamond DA 40 D mitTAE 125-02-114Installation, TAE-Nr.: 50-0310-50012, Ausgabe2, Revision 0or later EASA approved Issues/Revisions- Type D...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of theproduct.	21/01/2020	Active	10036328
10036331 (EASA.IM.R.S.01331)	DONALDSON COMPANY, Inc.	REV. 2	FAA STC SR02338CH	A119, AW119MKII	Installation of a foreign object damage (FOD) screen or an inlet barrierfilter (IBF) systemRevision 1 reflects the nameand address change from AerospaceFiltration Systems, Inc. to Donaldson Company, Inc.Revision 2 updates the Associated Technical Documentation with regardsto "later revisions"	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	1. Rotorcraft Flight Manual Supplement is the document AFS-AA119EASA-IBF-FMS Revision IR;2. Air Filtration System Inc. Master Data List Document No.AFS-AA119-IBF-MDL Revision I;orlater revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Impl...	None	10/11/2021	Active	10036331
10036344	BOMBARDIER INC.		TCCA STC NO. SA11-69	BD-700-1A10, -1A11	Installation, Structural Provisions for Shower Drain Feedthrough	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	Transport Canada STC No. SA11-69 Issue 1 dated 08 August 2011.ACS-NAI Ltd. Modification Data Summary G733000 Revision NC or laterapproved revision.Bombardier Instructions for Continued Airworthiness G733000-ICA RevisionIR or later revision.Bombardier Supplemental Airworthiness Limitations, G733000-A...	None	02/09/2011	Active	10036344
10036345	ACS-NAI Ltd.		TCCA STC C-LSA11-058/D	BD-700-1A10	Installation of Tailwind 500 System	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	-Transport Canada STC No. C-LSA11-058/ D Issue 1 dated 21 April 2011-ACS-NAI Ltd. Modification Data Summary H058000 RevN/ C or laterapproved revision.-ACS-NAI Ltd Instructions forContinued Airworthiness H058071 Rev N/C orlater approved revision.-Transport Canada STC No. C-LSA11-058/ D Issue 1 dated...	None	02/09/2011	Active	10036345
10036347	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		TCCA STC C-LSA11-079/D	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9399	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	-TCCA STC No. C-LSA11-079/D Issue 1 dated 24 May 2011.-ACS-NAI Ltd. Modification Data Summary H113000 Revision NC or laterapproved revision.-Innotech Aviation Flight Manual Supplement for Interior Completion,FMS-IA700-9399 Revision NC or later approved revision.-Innotech Aviation Flight Manual Suppl...	Restricted to ASN 9399The wireless Local Area Network (WLAN) System is intended to provideinternet connectivity and email services to the airplane's cabin usingportable electronicdevices (PEDS). Any other intended function of thisequipment will require a re-examination of the certification basis.	02/09/2011	Active	10036347

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036349	ADAC LUFTFAHRT TECHNIK GmbH	REV. 2		EC135 P3, EC135 T3 EC135 P2+, EC135 T2+	Installation of an NVIS lighting system in an Airbus Helicopter EC135 (MEGHAS).Note 1: Revision 1 of the STC introduces a filter on the display of theGN430 units (dual installation), removes the SAT phone control unit (aerophone) and corresponding software upgrade of the DMAP System anddeactivates the...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27 Amendment 3 asper Doc EC135-05162-027-RCS-02, Rev. 2.The requirements for environmental protection and the associate...	STC 10036349: (Applicable to EC135 T2+/EC135 P2+/ EC135 T2(CPDS)/ EC135P2(CPDS)) - FMS EC135-01065-025-MFS, Revision0STC 10036349 Revision 1: (Applicable to EC135 T2+) - FMS EC135-02956-025-MFS, Revision 0STC 10036349 Revision 2: (Applicable to EC135 P2+, EC135 T2+, EC135 T3 (CPDS), EC135 P3...	- Limited to helicopter with CPDS cockpit variant- STC Revision 1: EASA agrees that the extension of this approval to thehelicopters models EC 135T2(CPDS), EC135 P2 (CPDS) & EC135 P2+ can beapproved under a minor modification under the DOA of ADAC LTH, when thedesign configuration for the change on t...	02/12/2016	Active	10036349
10036361 (EASA.A.S.02912)	LEES AVIONICS Ltd.		CAA UK RESPONSIBILITY	B200CGT, B200CT, B200GT, B200T A200C, A200CT, B200, B200C 200, 200C, 200CT, 200T, A200 1900, 1900C, 1900D	TAWS-B Installation.	CS-23The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of theoriginal product areunchanged and remain applicable to thiscertificate/ approval.	Master Data ListMDL77801 Issue 2 dated 08 December '10.Change StatementCS-778 Issue 2 dated 08 December '10Instructionsfor Continued Airworthiness ICA-778 Issue 1 dated 30 April'10.Flight Manual SupplementAFMS-778-01 Issue 1 dated 30 April '10.or later revisions of the above listed documents approv...	None	02/09/2011	Active	10036361
10036367 (EASA.A.S.03923)	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			F90	STC 2589/09 Rev 4Dual EFIS G600 installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Dossier 2589/09 Rev 4 dated 18 July 2011Supplement manuel de vol SEAM/SMV/2589/09 Rev 4 dated 18 July 2011or later revisions of the above listed documents approved by EASA.	Limitation to Beech F90 equipped with SPZ200 autopilot and modifiedaccording SEAM STC 2465/08 avionics installation.	02/09/2011	Active	10036367
10036381	MARSHALL OF CAMBRIDGE AEROSPACELIMITED		CAA UK RESPONSIBILITY	B737-700	737 Medevac Role Change	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-CS25 Amdt 6-CRID-01/10000036 Medical EvacuationThe certificated noise and/or emissions levels of the original productare unchanged and...	Certificate of Design CD/ B737(1797)/09/0630 Issue 1 dated 25/05/2011AFM Supplement AFMS/ 737MED(1797)/10/0011 Rev.0 dated Jan 2011or later revisions of the above listed documents approved by EASA	None	06/09/2011	Active	10036381
10036393	HELI-ONE (NORWAY) AS	REV. 1		AS 332 L, AS 332 L1 AS332 L1/L2	Installation of STAR SAFIRE FLIR system consisting of external mount,internal and external cabling and installation of mission console inCabin.Revision 0 – initial approval applicable to AS332 L1/L2.Revision 1 – STC applicability corrected.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	AHS-124 dated 24 May 2011 – Flight Manual Supplement FLIR STAR SAPHIREHDAHSE-56756 revision C dated 30 August 2011 – Compliance ChecklistAHSE-57366 revision A dated 24 May 2011 – Continuing AirworthinessSupplement for FLIR HD InstallationCertification Plan revision (-) dated 17 December 2009AHSE-567...	Flight into known Icing Conditions prohibited.Prior to installation of this change it must be determined that theinterrelationship between this change and any other previously installedchange and/ or repair will introduce no adverse effect upon theairworthiness of the product.	01/02/2024	Active	10036393
10036411	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 2	FAA STC SA01213CH	SEE EASA APPROVED MODEL LIST	Install air ambulanceNote:1. This STC reflects the transferof STC CAA ES S374-1 from SpectrumAeromed, Inc to Snaky Creek Enterprises, LLC2. This STC supersedes STC CAA ES S374-1,EASA STC EASA.IM.A.S.C. 010163. This STC, together with EASASTCs 10036412 and 10036413 supersedeEASA STC EASA.IM.A.S. 024...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01213CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	FAA Approved Model List (AML) SA01213CH, reissued 28 February 2019., orlater FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	24/04/2019	Active	10036411

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036412	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA01213CH	SEE EASA APPROVED MODEL LIST	Install air ambulance conversionNote:1. This STC reflects the transfer of STC CAA ES S374-1 from SpectrumAeromed, Inc. to Snaky Creek Enterprises LLC.2. This STC supersedes STC CAA ES S374-1, EASA STC IM.A.S.C.01016.3. This STC, together with EASA STCs 10036411 and 10036413, supersedesEASA STC IM.A....	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01213CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	FAA Approved Model List (AML) No. SA01213CH, dated 28 February 2019, orlater FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	24/04/2019	Active	10036412
10036413	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA01213CH	SEE EASA APPROVED MODEL LIST	Installation of air ambulance conversionNote:1. STC 10036413 reflects the transfer of STC CAA ES S374-1 from SpectrumAeromed, Inc to Snaky Creek Enterprises, LLC2. STC 10036413 supersedes STC EASA.IM.A.S.C.010163. STC 10036413, together with EASA STCs 10036411 and 10036412 supersedeEASA STC EASA.IM....	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See EASA Approved Model Listor later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/ USABilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/04/2019	Active	10036413
10036439	AVCON INDUSTRIES, Inc.		FAA STC SA00415WI	B90, C90, C90A, E90, H90 300, 300LW, B300 200, 200T, A200, B200, B200T 100, A100, A100A, A100C, B100	Installation of Baggage Door.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Avcon Industries Inc, Master DrawingList No 30500, Revision C, dated 27 March 1996.Instructions for Continued Airworthiness in accordance with AvconIndustries Inc, Maintenance Manual Supplement Document No 00107025,Revision IR dated 28 May 2009.or later revisions of t...	None	08/09/2011	Active	10036439
10036443	AIRBORNE TECHNOLOGIES GmbH			P.68TC "OBSERVER" P.68 "OBSERVER 2" P.68 "OBSERVER"	Mission cabin configuration /For the installation of different mission equipment in a Vulcanair P.68aircraft, the aircraft cabin has to be modified and provisions toaccommodate Mission Equipment have to be installed. The installation ofmission equipment itself is not part of this STC.	Certification basis as per EASA TCDS: FAR 23, applicable AmendmentThe Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Applicant elected to comply CS-23, Amendment 2The requirements for envi...	Installed in accordance with Change Dossier Doc. No. STC-AT-036, Rev. 2and Installation instructions Doc. No. 036-II-STC-AT, Rev. 0Operated in accordance with Flight Manual Supplement AFM-STC-AT-036,Rev. 1Maintained in accordance with Maintenance Manual SupplementAMM-STC-AT-036, Rev. 1or later revis...	None	08/09/2011	Active	10036443
10036450	SCANDINAVIAN AVIONICS DESIGN ApS			GULFSTREAM 200 / GALAXY	UPGRADE OF ROCKWELL COLLINS TDR-94D MODE S TRANSPONDER SYSTEM FORENHANCED (EHS) SURVEILLANCE CAPABILITY.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCert base as TCDSJAR 25 Change 13Applicant elected to comply CS 25, Amdt. 5,AMC 20-13 and JAA TGL No. 13The requirements for environment...	To be installed in accordance with Engineering Order Doc. ID 2062013-EO,Issue 1 and Technical Order Doc. ID 2062013 Issue 1To be operated in accordance with Aeroplane Flight Manual SupplementDoc. ID 206213-AM, Issue 1To be maintained in accordance Continued Airworthiness Doc. ID2062013-CA, Issue 1or...	None	09/09/2011	Active	10036450

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036456 (EASA.IM.A.S.00285)	STAR AVIATION, Inc.	REV. 1	FAA STC ST02861AT	B747-400	Installation of Connexion by Boeing Next Generation Antennaand SateliteData System in accordance with Star Aviation Inc. Master Data ListR44-0163, Revision CP, Dated May 12, 2011or later approved revision	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The certification basis for parts changed or affected by the changesince thereference date of FAA application, December 8, 2009, is base...	Aircraft Flight Manual Supplement R44-0300 Rev. IR dated October 16,2004Instruction for Continued Airworthiness Star Aviation Document NoR44-0273, Rev. D, dated June 20, 2011or later revisions of the above listed documents approved by EASAinaccordance with EASA ED Decision 2004/04/CF (or subsequent...	None	09/09/2011	Active	10036456
10036469	BLACKHAWK MODIFICATIONS Inc.		FAA SA02357LA	CESSNA 208B	Replacement of the original P<(>&<)>W PT6A-114(A) engine and propellerwith P<(>&<)>W PT6A-42A and 4-blade Hartzell PropellerHC-E4N-3P/D9900(K) and associated equipment in accordance with FAA STCSA02357LA.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:FAR23, Amdt. 0: 23.21, 23.171, 23.231, 23.303, 23.307, 23.363, 23.471,23.481, 23.483, 23.493, 23.561, 23.601, 23.609, 23.627, 23.1023,23....	Master Drawing List 200803-000, Revision IR, dated June 8, 2011Flight Manual Supplement AFMS 200803, Rev. IR, dated June 22, 2011Instruction of Continued Airworthiness ICA 200803-30, Rev. A, dated May2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Deci...	1. AeroAcoustics Aircraft Systems, Inc., "Aircraft Payload Extender STOLSystem", STC SA01805SE (EASA STC No. 10029821)is required as part ofthis alteration.2. This modification is not compatible with Cessna Model 208B SerialNumber 208B1190, 208B1216, and 208B2000 and greater (Garmin 1000installati...	12/09/2011	Active	10036469
10036478	AERODATA AG		LBA EMZ NR. TA0607	FALCON 10	Change to LBA STC approval "EMZ Nr. TA0607 and AFM approvalDTM-721A"dated 26 June 2002.Change of procedures "Instructions for Continued Airworthiness" inrelation with RVSM qualification and update of the aircraftconfiguration.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.JAR 25 Change 15and JAA TGL 6The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels...	Master Data List doc. N° MDL-A/C-047, Rev. 5 dated September 06 2011.Instructions for Initial and Continued Airworthiness doc. N°HB-A/ C-650,Rev. 4 dated September 06 2011.AirplaneFlight Manual Supplement doc. N° FMS-047, Rev. 2 dated August02 2011.or later revisions of the above listed documents ap...	Restricted to S/N 183	12/09/2011	Active	10036478
10036479	AERODATA AG		LBA EMZ NR. TA0600	FALCON 10	Change to LBA STC approval "EMZ Nr. TA0600 and AFM approvalDTM-721A"dated 06 June 2002.Change of procedures "Instructions for Continued Airworthiness" inrelation with RVSM qualification and update of the aircraftconfiguration.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:JAR 25 Change 15and JAA TGL 6The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels...	Master Data List doc. N° MDL-A/C-044, Rev. 3 dated 06 September 2011.Instructions for Initial and Continued Airworthiness doc. N°HB-A/ C-645,Rev. 2 dated 06 September 2011.AirplaneFlight Manual Supplement doc. N° FMS-046, Rev. 3 dated 02August 2011.or later revisions of the above listed documents ap...	Restricted to S/N 216.	12/09/2011	Active	10036479
10036481	KUERZI AVIONICS AG			MF50	P-RNAV and RNP10 certificationCertification of P-RNAV and RNP10 for a Falcon 50 based on existing EASASTC 10034392.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List doc N° MDL-201110379 Rev N/ C dated 09 September2011.Aircraft Flight Manual Supplement doc N° FMS-201034519 Rev 1 dated 21June 2011.or later revisions of the above listed documents approved by EASA	EASA STC 10034392 is a required pre-requisite.	12/09/2011	Active	10036481

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036482 (EASA.R.S.01567)	LEES AVIONICS Ltd.		CAA UK RESPONSIBILITY	BELL 412	Installation of the Spectrolab search light SX16.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The Applicant applied as voluntary compliance the CS 29-2; for theapplicableparagraphs:CS29.1, CS29.251, CS29.305(a), CS29.561 (a), CS29...	Rotorcraft Flight Manual supplement RFMS-1041 iss. 1or later revisions of the above listed documents approved by EASA.-Lees Certification Plan CP-1041 iss. 1- MDL 1041-01 iss. 1	None.	16/09/2011	Active	10036482
10036485	SKYTRAC SYSTEMS Ltd.	REV. 1	TCCA STC SH10-24	AS 355 F2, AS 355 N AS 355 E, AS 355 F, AS 355 F1	Sky Track ISAT AIRBORNE POSITION / COMMUNICATION UPGRADEThemodification upgrades an existing ISAT-100 Airborne Position / DataCommunicator system installation to an ISAT-200 system(This EASA approval validates the TCCA STC SH10-24, Issue 3 on thetype/models referenced above) Revision 1 is an adminis...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Special Condition on Lithium Batteries as per EASA CRI F-01 Issue 1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the produc...	- Flight Manual Supplement FMS10033-5, Revision N/C dated March 14,2011;- Avionics Design Services LTD Master Drawing List MDL10033, Revision D,Issue 1, dated March 1, 2011 (relative to the EC AS 355 E, F, F1, F2,N);- Avionics Design Services LTD Drawing List DL10033-5, Revision N/ C,Issue 1, dated M...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/05/2024	Active	10036485
10036488	FIELD AVIATION COMPANY Inc.		TCCA STC NO. SA11-37	DHC-8-401, -402	Temporary Removal of Auxilliary Power Unit (APU)TCCA STC SA11-37, Issue 1	CS/JAR-25 as per EASA.IM.A. 191, Issue 4 (incl. SC H-01 ICA on EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirementsfor environmental protection and the associatedcertificatednoise and/ or emissions levels of the original product areun...	The temporary APU removal series must be done in accordancewith TCCAapproved Field Aviation Company Inc. Modification Instruction 25341000,Revision A, dated 02 June 2011.Maintenance of the APU System is unchanged from the instructionsprovided in Bombardiers DHC-8-400 Aircraft Maintenance Manual PSM...	The modification is applicable only when the necessary structuralprovisions are pre-existing	13/09/2011	Active	10036488
10036492	SKYTRAC SYSTEMS Ltd.	REV. 1	TCCA STC SH10-24	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Sky Track ISAT AIRBORNE POSITION / COMMUNICATION UPGRADEThemodification upgrades an existing ISAT-100 Airborne Position / DataCommunicator system installation to an ISAT-200 system(This EASA approval validates the TCCA STC SH10-24, Issue 3 on thetype/models referenced above) Revision 1: administrati...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Special Condition on Lithium Batteries as per EASA CRI F-01 Issue 1The requirements for environmental protection and the associatedcertif...	- Flight Manual Supplement FMS10033-4, Revision N/C dated March 14,2011.- Avionics Design Services LTD Master Drawing List MDL10033, Revision D,Issue 1, dated March 1, 2011 (relative to the EC AS 350 B, B1,B2,B3,BA,D)- Avionics Design Services LTD Drawing List DL10033-4, Revision N/ C,Issue 1, dated M...	This STC references specified interfacing equipment that isapproved viathis data. The ISAT -200 is capable of being interfaced to additionalaircraft systems for which approval isbeyond the scope of this STC.Such interfaces may need further approval.EASA.IM.R.S. 01137 Issue 2 is a pre-requisite to t...	02/11/2020	Active	10036492
10036493	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	A319	Installation of a Galley 13 and Closet C1into an Airbus A319-100 to beoperated by BMI	CS 25 Amendment 11	Change Record HEN 1208 Issue 1or later revisions of the above listed documents approved by EASA	None	13/09/2011	Active	10036493
10036501	AIRCRAFT DESIGN CERTIFICATION GmbH	REV. 1		EA 300/L, EA 300/LC EA 300, EA 300/S	Multi glider towing capacity up to 1000kg total tow mass	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List ADxC-44-001-MDL, dated August 18, 2011Airplane Flight Manual Supplement ADxC-44-001-AFM, dated August 30, 2011or later revisions of the above listed documentsapproved by EASA	Aircraft conforming to EASA TCDS.A.362 and being equipped accordingUA-300-4-95 Air-tow-release.	17/07/2018	Active	10036501

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036506 (EASA.R.S.01570)	LEES AVIONICS Ltd.		CAA UK RESPONSIBILITY	BELL 412	Installation of the UNS-1E FMS.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement RFMS-1040 Issue 1or later revisions of the above listed documents approved by EASA.Lees Certification Plan CP-1040 Issue 1 & MDL 1041-01 Issue 5.	This kit/STC can be installed on helicopter that has installed the kitDualBendix/King ED551A EHSI, EASA approved EASA.R.S.01445.	14/09/2011	Active	10036506
10036508	NORTHERN AVIONICS S.R.L.			AW109SP	NAV 434 "Installation of Helicopter Emergency Egress Light (HEEL)"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Bulletin NAV-434 Rev. 0	None	14/09/2011	Active	10036508
10036511	ALAMO ENGINEERING GmbH	REV. 4		HAWKER 850XP HAWKER 800XP, HAWKER 850XP HAWKER 800XP	Installation of a Flight Data Recorder (FDR) System.Revision 1: Transfer to 328 Design GmbHRevision 3: Transfer to 328 SUPPORT SERVICES GmbHRevision 4: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation in accordance with 328 Design GmbH EngineeringOrder refAM1581009A-01 Issue B, dated 16.12.2014;Operation in accordance with 328 Design GmbH Aircraft Flight ManualSupplement ref AM1581008A-01, dated Dec 16, 2014;Instructions for Continued airworthiness in accordance with 328 DesignGmbHo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10036511
10036542	B/E AEROSPACE, Inc.		FAA STC ST02876CH	B777F B777-300, B777-300ER B777-200, B777-200LR	Installation of B/E Aerospace, Inc., Vacuum Toilet AssemblyRetrofit Kit	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-1 EWIS ICA	Installation Instructions AMM 38-30-03 Rev. 3 dtd. 10 May 2011Instructions for Continued Airworthiness 38-30-04 Rev. 3 dtd. 2 June2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	19/09/2011	Active	10036542
10036545 (EASA.A.S.03492)	FOKKER SERVICES B.V.	REV. 2		777-200/-200LR/-300/-300ER/-F	Installation of a GKN Aerospace designed Boeing 777 No. 1 Windshieldpart No. 10702 (LH) / 10703 (RH); or Part No. 10712(LH) / 10713 (RH)Revision 2: Transfer from GKN to Fokker Services	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Major Change Approval C/R 017 Issue 1 dated 19th July 2011-ICA per GKN Component Maintenance Manual 56-11-07or later revisions of the above listed documents approved by EASA.	Replacement of a Flight Compartment Window Number 1 per this STC GKN ATSpart no. 10712 (LH) / 10713 (RH) together with the wiring loommodification constitutes an Alternative Method of Compliance (AMOC) tothe terminating action requirementsof FAA AD 2010-15-01 which has beenadopted by EASAReplacemen...	17/07/2017	Active	10036545
10036548	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02668NY-D	A330-341, -342, -343 A330-321, -322, -323 A330-301, -302, -303	Provision of a Panasonic Ex Phone System(Validation of FAA STC ST02668NY-D)This STC installs provisions (antenna and wiring) for Panasonic eX phoneSystem.The Revision 1 of this STC corrects the applicability by adding twoaircraft models, omitted at the initial approval.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, Ref : 0154-07160-2234, dated 08 September2011Instruction for Continued Airworthiness, Ref : 0754-07163-2234 RevisionAor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	This STC approval only certifies the provisions for the PanasoniceXPhone. This device activation, for which these provisions areintended, will be certified separately.	10/11/2011	Active	10036548

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036558	B/E AEROSPACE, Inc.		FAA STC ST02876CH	B737-600/700/800/900	Installation of Vacuum Toilet Assembly Retrofit Kit P/N 4100390-003.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI H-1 EWIS ICAThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certif...	- Component Certification Report Vacuum Toilet Assembly Retrofit KitCCR4100390-003 rev F released on 15-09-2011;- Master Data List MDL 4100390-001 rev A- Master Data List MDL 4100390-003 rev Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04...	None.	19/09/2011	Active	10036558
10036586	AERO-DIENST GMBH & CO. KG			LEARJET 35A	Installation of Honeywell (Allied Signal) Enhanced Ground ProximityWarning MK VIII System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Programme 105-LR Rev IR dated June 21, 2011 andEngineering Order No.: 105-LR.056.01 Rev 6 dated June 21, 2011or later revisions of the above listed documents approved by EASA	None	21/09/2011	Active	10036586
10036587	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		2. PA-31T, PA-31T1, 2. PA-31T2, PA-31T3 2. PA-31P, PA-31P-350, 1. PA-31, PA-31-300, 1. PA-31-325, PA-31-350,	Installation of one or more Avionik Straubing Heater Control Unit(s)HCU200.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	Flight Manual Supplement ASR-2010-027-FMS-05-00, Rev. 00Instructions for Installation ASR-2010-027-IFI-10-00, Rev. 00Instructions for Continued Airworthiness ASR-2010-027-ICA-11-00<(>,<)>Rev. 00or later revisions of the above listed documents approved by EASA.	None.	04/10/2011	Active	10036587
10036590	B/E AEROSPACE, Inc. - FSI		FAA STC ST00695AT-D	B747-400	Modification of Upper Deck Crew Rest Compartment in accordance withTimco Master Data List, MDL-01090, Revision E, datedJuly 22, 1996, orlater FAA approved RevisionValidation of FAA STC ST00695AT-D	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	None	None	21/09/2011	Active	10036590
10036591	LEES AVIONICS Ltd.		CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	GNS430W/GNS530W Installation for BRNAV	CS-23 Amendment 2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Multi Model List MML-1253 Issue 1, Dated 07 Sept 2011MasterData List MDL-1253 Issue 1, Dated 19 Sept 2011Change Statement CS-1253 Issue 1, Dated 02 Sept 2011Instructions for Continued Airworthiness ICA-1253 Issue1, Dated 02 Sept2011FlightManual Supplements:AFMS-1253-01 Issue 1, Dated 01 Sept 2011A...	None	30/09/2011	Active	10036591
10036603	BOMBARDIER INC.		TCCA STC SA05-60	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9427	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. SA05-60 Issue 1, dated 14 June 2005.Aero Consulting Services Ltd Configuration Definition List E025000Revision FE, dated 20 September 2011.Bombardier Aerospace Aeroplane Flight Manual Supplement G-FM25004501,Revision N/C or later approved revision.GC94270000-IFCA Instructions for Contin...	Restricted to ASN 9427	22/09/2011	Active	10036603

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036604	MOTORFLUG BADEN-BADEN GmbH	REV. 1		228-212	Installation of Mission Equipment for Maritime Surveillance.	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emission levels.	28145F103137-0601, Rev. 2,, AFM Supplement28145F103137-0701, Rev. 2,, Instruction for Continued Airworthiness28145F103137-0702, Rev. 1,, TLMCM Supplement28145F103137-1001, Rev. 0,, Installation Manualor later revisions of the above listed documents approved by EASA.	None.	11/10/2011	Active	10036604
10036609	ST ENGINEERING AEROSPACE LTD.			A320-200 SERIES	Ural Airlines' A320 Cabin Reconfiguration	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.JAR 25 Change 11and EASA CS 25 Amendments 4 and 10, as per STAerospace's Certification Plan Doc 399001/ AED/001 Revision D.In addition EA...	ST Aerospace's Master Document List 399001/ AED/002 RevisionB, dated22nd September 2011.or later revisions of the abovelisted documents approved by EASA	-,,This design change on Aircraft model Airbus A320-200 is applicable tothe following aircraft serial numbers (MSNs): 203; 220; 735; 1152; 1484;1777; 2175; 2187 and 2327.	22/09/2011	Active	10036609
10036624	TECH-TOOL PLASTICS, Inc.		FAA STC SR03641AT	EC 120 B	Replace the existing Eurocopter EC120 B windows with Tech-Tool Plastics,Inc. replacement windows(Note: This approval constitutes the EASA validation of the FAA STCSR03641AT, Issued by the FAA on June 30, 2011)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Master Drawing List (MDL) EC120/130-2000-100, Revision C dated October31, 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) Eurocopter EC 120-B Maintenance and Repair Manual, is also required...	None	23/09/2011	Active	10036624
10036630	NSE INTEGRATIONS			ATR 42-300	Modification in ATR42-300 MSN 049's calibration test bench	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalIn addition to the product's original certification basis, EASACertification Review Item (CRI) Special Condition CRI H-01 Issue 1 "Enhance...	NSE Intégrations's:Modification Form NSE 08-01 Edition 3, Revision 1 dated 20th September2011 andSupplement for EWIS Instructions for Continued Airworthiness: "DetailedInspection Tasks ATR42 Kit Calibration Test Benc" revision Indice B,dated 20th September 2011.or later revisions of the above listed...	This STC is limited to ATR42-300 serial number aircraft MSN049	28/09/2011	Active	10036630
10036633	RUAG AEROSPACE SERVICES GmbH	REV. 1		BD-700-1A11 BD-700-1A10	Dual Electronic Flight Bag (EFB) Installation	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	RUAG Master Document List No. 341A-MDL Rev. N/ C dated 15 September 2011.RUAG Approval for Aircraft Modification No. 341A-CN Rev. N/C dated 15September 2011RUAG Airplane Maintenance Manual Supplement No. 341A-AMMSor later revisions of the above listed documents approved by EASA	None	27/09/2011	Active	10036633

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036644	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CL-600-2B16	Introduction of Corporate Interior	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	STC Twenty One Master Document List No. S21.MDL-0954 Initial Issue,dated 22 September 2011Midcoast Aviation AFMS No. 34-424M005Midcoast Aviation AFMS No. 34-261M017or later revisions of the above listed documents approved by EASA	Restricted to ASN 5616	26/09/2011	Active	10036644
10036655	HAECO CABIN SOLUTIONS, LLC		FAA STC ST01959AT-D	747-400	Installation of a Ball Camera Entertainment system per Timco Master DataList 99T057L001 Rev. C, dated November 8, 1999 or later FAA approvedrevision.Validation of FAA STC ST01959AT-D	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	none	none	27/09/2011	Active	10036655
10036659	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02876CH	B747-400F B747-400	Installation of Vacuum Toilet Assembly Retrofit Kit P/N 4100390-003Validation FAA STC ST02876CH. ,,	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI H-01 Enhanced Airworthiness Programme for Aeroplane Systems - ICA onEWISThe requirements for environmental protection and the associa...	AMM Supplement 38-30-06 Rev 06 Instructions for Continued Airworthiness (ICA) and EWIS ICA source document, dated 20 October 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF(or subsequent revisions ofthis decision) and/ or the Techni...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/09/2016	Active	10036659
10036673 (EASA.A.S.03703)	SCANDINAVIAN AVIONICS DESIGN ApS			SD3-SHERPA, SD3-60 SHERPA SD3-30, SD3-60	Installation of GARMIN GPS-400	CS 25 Amendment 4The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Scandinavian AvionicsEngineering Order 2042759-EO Issue 1 dated 21 July 2011Flight Manual Supplements2042759-AM-A Issue2, dated 15 March 20112042759-AM-C Issue 2, dated 15 March 2011Continued Airworthiness2042759-CA Issue 2, dated 10 March 2011or later revisions of the above listed documents approv...	None	28/09/2011	Active	10036673
10036677	AVIONIK STRAUBING ENTWICKLUNGS GmbH			60, A60, B60	Installation of a Traffic Advisory System Avidyne TAS 605/615/620<(>,<)>Ryan 9900BX	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCS-23, Amendment 2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	- Flight Manual Supplement ASR-2011-016-FMS-05-00, Rev. 00-Instructions for Installation ASR-2011-016-IFI-10-00, Rev. 00-Instructions for Continued Airworthiness ASR-2011-016-ICA-11-00, Rev.00or later revisions of the above listed documents approved by EASA	None	28/09/2011	Active	10036677
10036680	ROEDER PRAEZISION GMBH	REV. 1		PA-46R-350T PA-46-310P, -350P, -500TP,	Installation of Tactical Weather Detection System (Stormscope) AvidyneTWX670.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	Flight Manual-Supplements: TWX670-NY-02180-08, Rev. 1Engineering Order: TWX670-NY-02180-05, Rev. 0Maintenance Procedures: TWX670-NY-02180-07, Rev. 0or later revisions of the abovelisted documents approved by EASA.	This STC is also applicable to Turbine Converted Aircraft (PA46-310-DLX,PA46-350DLX) according to FAA STC ST00541SE.Theaircraft must have been already equipped with a suitableMultifunction Display (MFD).Prior to installation of this modification it must be determined thatthe interrelationship betwe...	15/11/2017	Active	10036680

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036696	SOCATA SAS	REV. 1		AS 355 F2	Installation of a surveillance WESCAM MX 10 camera and operator consoleas defined in MDL STC.25.001.11.001.Rev. 0: installation of provisionsRev. 1: installation of the complete system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MANUEL DE VOL AS 355 F2 SUPPLEMENT STC 25.001.11.010, Rev. 0, dated12/12/14 or later revisions of the above listed documents approved byEASA.CCL FAR 27/ Airworthiness code compliance DAHER SOCATA N°STC. 25.001.11.002 Edition 1 Rev 7, November 2014Instructions for Continued Airworthiness DAHER SOCATAS...	Serial Numbers 5026, 5299, 5298, 5156 onlyPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/12/2014	Active	10036696
10036731	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	Design Data for the approval of a Honeywell KFD840 Primary FlightDisplay (PFD).	CS-23 Amendment 1The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval .	Installation Manual IM. 02410 Revision A, dated 09 July 2011.Master Document List MDL.02410 Revision B, dated 27 September 2011.Instructions for Continued Airworthiness ICA.02410 Revision A, dated 09July 2011.Flight Manual Supplement FMS. 02410 Revision A.or later revisions of the above listed documen...	None.	04/10/2011	Active	10036731
10036735	BHE & ASSOCIATES, LTD.	REV. 2	FAA STC SA10965SC	B300, B300C B200, B200C, B200CGT, B200GT	Installation of upgraded hardware to the Rockwell Collins Pro Line 21FMS-3000 to provide Localizer Performance with Vertical Guidance (LPV)Revision 1: This change updates and corrects the referenced TextronAviation AFM for the B300/B300C, on cover page of the EASA AFMS324-00-0023.Revision 2: Change...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA10965SC.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Drawing List 324-00-0001, Revision A, dated 12 January 2010, orlater FAA approved revision.Airplane Flight Manual Supplement, Document 324-00-0014, Revision IR,dated 12 January 2010, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This installation is limited to airplane serial numbers...	07/08/2025	Active	10036735
10036742	BEECHCRAFT CORPORATION		FAA STC SA02331LA	B300 & B300C	Installation and maintenance of Switches and wiring for anElectro-Optical/Infra-Red Lift and Turret System.	FAR 23The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificatednoise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation in accordance with Master Data List 300E404584, Rev 3,dated November 9, 2010.Operation in accordance with Airplane Flight Manual Supplement for EO/IRLift Electrical System, P/N 130-590031-403, dated, December 3, 2010.or later revisions of the above listed documents approved by EASA inac...	none	05/10/2011	Active	10036742
10036765 (EASA.R.S.01575)	NORTHERN AVIONICS S.R.L.	REV. 1		A109A, A109 AII, A109C	Installation of a retractable swivelling landing light (searchlight).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Rotorcraft Flight Manual Supplement RFMS NAV-371 Rev. 0-Instructions for Continued Airworthiness ICA-NAV371R0, dated 01 July2011or later revisions of the above listed documents approved by EASA-Installation Instructions II-NAV371-1R0, dated July 2011-Installation Instructions II-NAV371-2R0 (only fo...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	15/04/2013	Active	10036765

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036781	HAWKER BEECHCRAFT SERVICES		FAA STC SA00857WI	BEECH 1900D	Installation of Universal Avionics System Corp UNS-1K Flight ManagementSystem.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Raytheon Aircraft Services MasterDrawing List ref 148-100013, Revision B, dated February 24, 2000.Operation in accordance with Raytheon Aircraft Services Flight ManualSupplement ref FMS002048UE368, dated March 2, 2000.or later revisions of the above listed documents a...	None.	06/10/2011	Active	10036781
10036782	HAWKER BEECHCRAFT SERVICES		FAA STC SA00878WI	BEECH 1900D	Installation of a forward double or triple club executive style interiorconfiguration.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Raytheon Aircraft Services MasterDrawing List ref RAS19D1000, Revision A, dated May 24,2000.Operation in accordance with Raytheon Aircraft Services Flight ManualSupplement ref RAS19D10FMS, dated May 24, 2000.or later revisions of the above listed documents approved b...	None.	06/10/2011	Active	10036782
10036784	AVIONIK STRAUBING ENTWICKLUNGS GmbH			BEECH 60, A60, AND B60	Installation of Garmin G600 System with Synthetic Vision Technology(SVT).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Avionik Straubing Engineering Order refASR-2011-015, Amendment 00 dated 4/4/11.Operation in accordance with Avionik Straubing Flight Manual Supplementref ASR-2010-015-FMS-05-00, Amendment 00, dated 4/4/11.Instructions for Continued Airworthiness in accordance with Avi...	None.	06/10/2011	Active	10036784
10036787	E A D AEROSPACE AIRWORTHINESS			A320 SERIES	Cabin Modification 174 to 168 PAX on A320	In accordance with the current EASA TCDSThe Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicab...	- Master Drawing List, ref. 01346-EAS-A-MDL, Revision C, dated 4thOctober 2011- Compliance Check List, ref. 01346-EAS-A-CCL-01, Revision C, dated 4thOctober 2011- Supplemental Type Design, ref. 01346-EAS-A-STD-01, Revision B, dated4th October 2011- Declaration of Compliance, ref. 01346-EAS-A-DCL, Re...	None	06/10/2011	Active	10036787
10036788	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)	REV. 1		1900 SERIES	Installation of a partition in the rear cabin area.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with SEGA Modification File A-25-Cloison_DA,dated September 2011;Instructions for continued airworthiness as defined in SEGA documentA-25-Cloison< (>,<)>dated September 2011;or later revisions of the above listeddocuments approved by EASA.	None.	03/01/2012	Active	10036788

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036793	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	B777-300, B777-300ER, B777F B777-200, B777-200LR,	Introduction of CabinVu 123 Cabin Surveillance System.	EASA.IM.A.003The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Generic CRI H-01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions le...	STC Twenty One Ltd Master Document List No. S21.MDL-0857 Issue 2, dated08 September 2011or later revisions of the abovelisted documents approved by EASA.	None.	06/10/2011	Active	10036793
10036806 (EASA.IM.R.S.01362)	GENEVA AVIATION Inc.	REV. 2	FAA STC SR00521SE	SEE EASA APPROVED MODEL LIST	Installation of Geneva Aviation Audio System on CS-27/Part-27 CategoryRotorcraft in accordance with the enclosed EASA Approved Model List (AML).The purpose of this revision 2 is toremove CS-29/Part 29 CategoryRotorcraft from this approval. Previously included CS-29/Part 29Category Rotorcraft are re...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Please see enclosed (page 5 of 7 of this document) EASA approved CS-27Part 27 Rotorcraft model list (AML) for Geneva Aviation Audio SystemROTORCRAFT FLIGHT MANUALS SEE EASA APPROVED MODEL LISTor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04...	The applicability of this STC does not include the model AS350B3incorporating modification OP-4305 (Arriel 2D engine installation).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change an...	27/01/2016	Active	10036806
10036814	DOA AESGLOBAL LIMITED	REV. 5	CAA UK CAA. 21NE2.00057	757-200	FAR Part 26 Validation for EASA STC CAA.21NE2.00057Rev 4: Transfer from AES Ltd. to new STC holder AES Global Ltd.Rev 5: corrected model	FAA TCDS A2NMThe Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Generic CRI H-01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions le...	AES Ltd Master Data List No: AES-757-172MDL, Issue 1, dated20 September2011.or later revisions of the above listed documents approved by EASA	None	28/04/2021	Active	10036814
10036823	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD	REV. 3	TCCA STC NO. SA10-8	BD700-1A10/-1A11 BD-700-1A10/-1A11	I-KU System Installation with VIASAT VMT 1500 KU Band System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	INNOTECH AVIATION MASTER DRAWING LIST MDL-BD700-148 REV. ADTRANSPORTCANADA 01 DECEMBER 2015INNOTECH AVIATION FLIGHT MANUAL SUPPLEMENT NO. FM09-008 REV. K TRANSPORTCANADA APPROVED01 DECEMBER 2015INNOTECH AVIATION INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA09-010 REVQ DATED 24 SEPTEMBER 2015or late...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2020	Active	10036823
10036826	DSA A.S.	REV. 1		L 200A, L 200 D	Avionics Upgrade, GNS 430W, GMA 347, WX 500, KCS 55A, ELT 406, MID4200-10 Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-S1-LDA01/11/L200 COMM/NAV/GPS GARMIN GNS 430W, Rev.0-S2-LDA01/11/L200 AUDIO PANEL GARMIN GMA 347, Rev.0-S3-LDA01/11/L200 SYSTÉM GYROMAGNETICKÉHO KOMPASU A HSI KCS55A, Rev.0-S4-LDA01/11/L200 UMĚLÝ HORIZONT MID 4200-10, Rev.0-S5-LDA01/11/L200 STORMSCOPE WX 500, Rev.0-S6 -LDA01/11/L200 POLOHOVÝ MAJÁKo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/05/2020	Active	10036826

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036834	POLICE AVIATION SERVICES Ltd.	REV. 1	CAA UK RESPONSIBILITY	VULCANAIR P.68.TC 'OBSERVER'	Airborne Surveillance System Installation	CS-23 Amendment 2 dated 28 September 2010The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applica...	Modification Leaflet and Certificate of Design PAS/ MOD/643Compliance Checklist CCL/643-003 Issue BMaintenance Schedule Supplement MSS/643-007 Issue AAircraft Flight Manual NOR.10.707-4B Supplement FMS/643.002 Issue Bor later revisions of the above listed documents approved by EASA	None	24/11/2011	Active	10036834
10036838	B/E AEROSPACE, Inc.	REV. 2	FAA STC ST03918AT	777-300/-300ER 777-200/-200LR	FAA STC ST03918AT: Installation of the Honeywell MCS-7200 SATCOM System.Revision 2 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt 4CRI H-1 EWIS ICAThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged a...	-FAA STC ST03918AT-MDL 78144-001 Rev. A dtd. 13. May 2011-ICA 2-78144-804 Rev. IR dtd. 10. Feb 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10036838
10036858	AVIONIK STRAUBING ENTWICKLUNGS GmbH			60, A60, B60	Installation of a Satellite Data Link System Garmin GSR56.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	Flight Manual Supplement: ASR-2011-051-FMS-05-00, Rev. 00Instructions for Installation: ASR-2011-051-IFI-10-00, Rev. 00Instructions for Continued Airworthiness: ASR-2011-051-ICA-11-00, Rev.00or later revisions of the above listed documentsapproved by EASA.	None.	12/10/2011	Active	10036858
10036867	CHRISTEN-AIRTECH AG			414A	Inst.Traffic alerting system/ StormscopeRemoved:- NILInstalled:- Garmin GTS800 Traffic Alerting System- L-3 WX500 Stormscope System	CS 23,, Amdt: 2The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalSCs or ESFs: For this modification, voluntary compliance to CS23 Amdt. 2was shownThe certificated noise and/ or emissions l...	Master Document List: Doc. Nr. CAT-211.2949-EOMDL-01, Rev. 0Instructions for continued airworthiness:- For the Garmin GTS 800, Doc. Nr. CAT-211.2949-CA-01- For the L-3 WX500, Doc Nr. CAT-211.2949-CA-02 Rev 0	S/N: 414A-0233,,,,D-IMUB	13/10/2011	Active	10036867
10036868 (EASA.IM.R.S.01400)	EAGLE COPTERS USA, INC.	REV. 1	FAA STC SR00643SE	4. BELL 407 4. BELL 206L-3/-L-4 4. BELL 206A/-A-1/-B/-L/-L-1 3. BO105 LS A-3 3. BO105 A/-C/-S/-LS A-1 2. AS355E/-F/-F1/-F2 1. AS350B/-B1/-B2/-BA/-D	Installation of Geneva Aviation Video System per MDL GA183.Notes:1. The STC was initially issued to Geneva Aviation, Inc. (initialreference: 10036868). 2. Revision 1 to this STC reflects the transfer of 10036868 from GenevaAviation, Inc. toEagle Copters USA, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List GA183 Rev. K dated May 22, 2010Rotorcraft Flight Manual Supplement for AS350/355<(>,<)> GA183-3 Rev. Bdated December 10, 2009 (for AS350/AS355 model aircraft)Rotorcraft Flight Manual Supplement for BO-105<(>,<)> GA183-5Rev. Adated June 30, 2009 (for BO-105 model aircraft)Rotorcr...	Any optional modifications listed in Installation Instructionsreferenced in Master Drawing List GA183, to be installed in conjunctionwith this STC, shall be EASA approved.This STCcovers installation of the complete set of equipment items asdefined by this STC or a subset of those equipment items.Th...	31/03/2015	Active	10036868
10036912	AEROLITE AG	REV. 1		AW139/AB139	EMS Equipment P/N 139-0003670-501This STC covers 4 EMS cabin configurations and 3 PAX configurations asdescribed in theFMS-139-0003670-501 and according to the Masterdocument list MDL-11-016 rev N/C.Rev. 1 changes the name of the STC holder from "Aerolite Max Bucher AG"to "Aerolite AG".	The certification basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FMS: FMS-139-0003670-501 rev N/CAirworthiness limitations: AWL-139-0003670-501-0 initial issueor later revisions of theabove listed documents approved by EASAOperations manual: OPM-139-0003670-501 rev A	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/02/2019	Active	10036912

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036936	ROEDER PRAEZISION GMBH	REV. 1		F27 MK050	Installation of cabin divider	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Cabin divider installation according to EO F50-NY-12177-05Incorporation of maintenance instructions according to EOF50-NY-12177-07	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/11/2017	Active	10036936
10036940	KUERZI AVIONICS AG	REV. 1		EC 130 T2 EC 130 B4	Garmin 500H installation including PFD/ MFD GDU 620, AHRS GRS77H, Airdata system GDC 74H.Revision 1 extends the applicability of the STC to model EC 130 T2.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS 27 Amdt 0 for the changeThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to...	Master Document List MDL-201110617, rev B, dated 23 November 2018Instruction for continued Airworthiness ICA-201110617,REV B, dated 09July 2018Flight Manual Supplement FMS-201110617, REV 3, dated 21 November 2018or later revisions of the above listed document(s) approved/ acceptedunder the EASA syst...	At least a GPS/WAAS navigator, compatible with G500H, must be installedas pre-requisite.A standby attitude instrument must be installed. This can be either theOEM horizon or an integrated instrument EFD1000H.Altitude and airspeed standby instruments must be installed. Option 1: REVUE THOMMEN 3A4...	26/11/2018	Active	10036940
10036941	TELAIR INTERNATIONAL, LLC	REV. 1	FAA STC ST02367LA	747-8F	Main Deck Cargo Handling System, Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA CRI A-100Therequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalu...	PSCP 193100CPP-81F, FAA STC 14144LA-T and Index List 193100-8 Revision Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	20/10/2011	Active	10036941
10036942	TELAIR INTERNATIONAL, LLC	REV. 1	FAA STC ST02365LA	747-8F	Lower Deck Cargo Handling System, Installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA CRI A-100Therequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalu...	PSCP 192100CPP-705, FAA STC 14522LA-T and Index List 192100-8 RevisionB;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	20/10/2011	Active	10036942
10036958	SCANDINAVIAN AVIONICS DESIGN ApS			BAE 146, AVRO 146-RJ	Provision for a Dual NAVAERO t.BagC2 Class 2 Electronic Flight BagSystem	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA Certification Specification CS-25 Amendment 4CRI H-01 Instructions for Continued Airworthiness (ICA) on ElectricalWiring Interconnec...	Scandinavian Avionics Engineering Order and Certification Program,Provision for a Dual NAVAERO t.BagC2 Class 2 EFB System in a BAe 146 /Avro 146-RJ Series, 2064098-EO Issue 2 dated 18 October 2011Scandinavian Avionics Certification Documents, 2064098 DOC Issue 1 dated19 October 2011Scandinavian Avio...	None	19/10/2011	Active	10036958
10036974	AEROTEC & CONCEPT			C90A	Installation of Honeywell TCAS II ATC and GPWS MK VI according toAerotec modification n° MOD 1085.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS_23 amdt 1: 301, 303, 305, 337, 561, 571, 603, 607, 867, 1351, 1353,1357, 1365, 1367, 1301, 1323, 1325, 1327, 1381, 1431, 1529, 771, 773...	Flight Manual Supplement n° AE1085SMV Revision 1 dated 21/03/2011.Instruction for continued airworthiness n° AE1085IPMN revision 1 dated11/04/2011.Master Data List n° AE1085MDL revision 1 dated 22/03/2011or later revisions of the above listed documents approved by EASA.	This change is applicable to aircraft s/n LJ1066.	21/10/2011	Active	10036974

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10036985	CESSNA ZURICH CITATION SERVICE CENTGMBH			CESSNA 525	Removed Equipment:-Aerosonic VSI 1 & 2-Skywatch 497 TCASI SystemNew installed equipment:-Honeywell TA/VSI Indicator 1 & 2-PS-578A XPDR/TCAS Control HeadCAS-67A TCAS II System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.SCs or ESFs: Voluntary compliance to CS-23 First Issue for the changeDerogation to latest amendment (Part 21A.101):Do not materially cont...	- Master Document List, Doc. No. MDL-075, Rev. B- ICA, Doc.No. ICA-040, Rev. A- AFMS EHS, Doc. No. FMS-042, Rev. IRor later revisions of the above listed documents approved by EASA	S/N: 525-0322 F-HCPB	24/10/2011	Active	10036985
10037000 (EASA.A.S.03714)	JET AVIATION AG, BASEL			B747-400	Installation of Cabin Interior Doors in accordance with JetAviationMaster Data List BHHM1001-001 Rev. B, dated 19th October, 2011 forB747-400 S/N 28343	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI-D-01 Doors between passenger compartmentsCRI-D-02 Isolated Compartment	BHHM1001-201-02 Rev. IR - Airplane Flight Manual SupplementBHHM1001-150-02 Rev. IR - Instructions for Continued Airworthinessor later revisions of the above listed documents approved by EASA	This aircraft is not eligible for registration in a European country,because it does not comply with the JAA Special Conditions 1 and 2.	24/10/2011	Active	10037000
10037001	AERO TWIN, Inc.		FAA STC SA4626NM	CESSNA 208, 208B	Fabrication and Installation of Auxiliary dry air pump kit AP8-100 inaccordance to FAA STC SA4626NM.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement, Rev. B, dated November 27, 2006Instructions for Continued Airworthiness, Doc. No. AP8-ICA, Rev. D datedJune 22, 2004Master Drawing List No. AP8-100, dated October 13, 2006Installation Instructions, Doc. No. AP8-1M, Rev. F, dated October 13,2006or later revisions of...	None.	24/10/2011	Active	10037001
10037002	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			HAWKER 900XP	Cabin Interior Removal and Modification.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:Refer to Certification Program 5143-080, rev. BThe requirements for environmental protection and the associatedcertificated noise and/ or...	Modification in accordance with Master Data List Doc. No. 5143-049, Rev.AInstructions for Continued Airworthiness ref Doc. No. 5143-085, Rev. IRor later revisions of the above listed documents approved by EASA.	None.	24/10/2011	Active	10037002
10037011	RUAG AG	REV. 1		EC 130 B4	Avionics RetrofitOut: Garmin GTX·330 Mode S Transponder & GMA·340 Audio/ Marker system;Honeywell KX·165A VHF·COM/NAV systemIn: Aspen EFD 1000H EFIS system; Garmin GNS 430W VHF COM/NAV & GPSsystem; Garmin GSR 56 Iridium system; PS Engineering PMA 8000BAudio/Marker system; Avidyne TAS 620 system; Becke...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.SCs or ESFs: Voluntary compliance CS 27 Arndt 0 for the changeCS 27.1<(>,<)>.21<(>,<)> .27<(>,<)> .29<(>,<)> .251<(>,<)> .301<(>,<)>.303...	Flight Manual Supplement: FMS-1900810-01 Rev. AMaster Document List: MDL-1900810-01 Rev. AInstructions for Continued Airworthiness: ICA-1900810-01 Rev. Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	S/N 7214Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	18/01/2021	Active	10037011
10037015	AIRBUS S.A.S.	REV. 1		A319-133	Airbus Corporate Jet Centre Modification CJ0700 Issue 3 -VIP Interior - "OPTIMA PROJECT"Revision due to update of AFM-Sand MPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A-4301-004 "ACJC Project Certification Basis.The requirements for environmental protection and the associatedcertified noise and/ or emissionsu...	-,,Modification Approval Sheet, ref. CJ0700, Issue 3, dated24th October2013-,,Airplane Flight Manual - AFM - Supplement, ref.: FM-S MOD CJ0700,Revision 02, dated 1st October 2013-,,Maintenance Planning Document - MPD - Supplement, ref. MPD-S MODCJ0700, Revision 02, dated 1st October 2013-,,Master M...	This STC is limited to A319-133 MSN 4319Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	25/10/2013	Active	10037015

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037018	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03253AT	757-200PF, 757-300 757-200, 757-200CB	Installation of the Honeywell MK II Aircraft Communication Addressingand Reporting System (ACARS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement 2-35716-807 Revision IR, dated 20 April 2006.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).EMTEQ Engineering Master Drawing List 2-35716-001 Revision C, dated 16Novemb...	Compliance with EASA AMC 20-9 and AMC 20-10 has not been shown.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness...	02/03/2016	Active	10037018
10037027	AEROTEC & CONCEPT	REV. 1		C90A	Installation of Garmin G600 EFIS and Garmin GNS 430 W COM/NAV/ GPSsystem.STC original issue: initial installation with authorization for IFRB-RNAV operations (Aerotec modification no. AE1084)STC revision 1: authorization for IFR P-NAV, RNP approach LNAV and LPVoperations (Aerotec modification no. AE1...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS 23 amdt 1: 301, 303, 305, 337, 561, 571, 603, 607, 771, 773, 867,1301, 1303, 1309, 1311, 1321, 1322, 1323, 1325, 1327, 1351, 1353, 135...	Flight Manual supplement No. AE1084SMV revision 2 dated 21/06/2011Flight Manual Supplement No. AE12041SMV revision 0 dated 03/04/2013Instructions for Continued Airworthiness No. AE1084IPMN revision 1 dated11/04/2011Master Data List No. AE1084MDL revision 4 dated 21/10/2011Master Data List No. AE1204...	1. This change is applicable to aircraft s/n LJ 1066 and itis approvedfor IFR B-RNAV, P-RNAV, RNP approach LNAV and LPV operations.2. RNP approach with APV baro VNAV is not authorized.3. The airplane must be equipped with:- an altitude indicator, an airspeed indicator and an altimeterindependent fr...	16/05/2014	Active	10037027
10037034	HELI-ONE CANADA ULC			S-61L & N	Lower Housing Weld Repair	The Certification Basis for the original product remains applicable tothis certificate/ approval.CAR 7 & FAR Part 29 (As per FAA TCDS 1H15)The requirements for environmental protection and the associatedcertificated noise and/ or emissionslevels of the original product areunchanged and remain appli...	Heli-One Engineering Order, E0 No: H1E-021 Rev .0, Transport CanadaApproved 12 April 2007.	Applicable only to Sikorsky S-61N Lower Housing Assembly Part No'sS6135-20670-9, S6135-20670-42, S6135-20670-43, S6135-20629-102,S6135-20629-104.	26/10/2011	Active	10037034
10037035	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE			200	Installation of gear override and steep approach switches on TWASTW-950.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement No. UAE-AFMS-11-002 revision IR dated18/07/2011.Master Data List No. MDL-009-11 revision 1 dated 13/09/2011.Service Bulletin No. SB-UAE-009-11-01 dated 18/07/2011.or later revisions of the above listed documents approved by EASA.	This STC is applicable to aircraft s/n BY-91.	26/10/2011	Active	10037035
10037040	BOMBARDIER INC.		TCCA STC NO. SA04-113 ISSUE 1	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9413	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	TCCA STC No. SA04-113 Issue 1, dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionJF, dated 06 October 2011.Instructions for Continued Airworthiness GC94130000-IFCA.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	Restricted to ASN 9413 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN System is compatible only to IEEE 802.11(b).	26/10/2011	Active	10037040
10037049	B/E AEROSPACE, Inc. - FSI		FAA STC ST00840SE	B747-400	Reconfiguration of the Main Deck of the B747-400 series airplane inaccordance with Flight Structures, Inc. Master Drawing List 99FS908-D01Rev. E, dated 10 November 2009 or a laterFAA approved revision.Validation of FAA STC ST00840SE ,,	The Certification Basis for the original product remains applicable tothis certificate/ approval.,,	Flight Structures, Inc. Master Data List MDL 99FS908-D01 Rev. Eor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	27/10/2011	Active	10037049

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037055	BOMBARDIER INC.		TCCA STC NO. SA04-113 ISSUE 1	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9238	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	TCCA STC No. SA04-113 Issue 1, dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionJH, dated 07 October 2011.Instructions for Continued Airworthiness GC92380000-IFCA.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	Restricted to ASN 9238 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN System is compatible only to IEEE 802.11(b).	27/10/2011	Active	10037055
10037056	DASSAULT FALCON SERVICE			F900B, F900C & F900EX	Cabin Master installation.A Cabin Master Switch is installed on Co-pilot console.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	DFS Change Approval Sheet DFS9646-CAS Issue A dated 30.06.2011.DFS Modification Sheet DFS9646, Issue A dated 30.06.2011.DFS Airplane Flight Manual Supplement N° F900-031 dated 30.06.2011or later revisions of the above listed documents approved by EASA	Not applicable	27/10/2011	Active	10037056
10037086	TECH-TOOL PLASTICS, Inc.		FAA STC SR03640AT	EC130 B4	Installation of Replacement WindowsThis STC is the validation of FAA STC SR03640AT	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Tech-Tool Plastics, Inc. Master Drawing List (MDL), EC120/130-2000-100,Revision C dated October 31, 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	31/10/2011	Active	10037086
10037095	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01957AT-D	B747-400	Installation of Collins SAT-906 Satcom Systems provisions in accordancewith Timco Master Data List MDL 99T045L001, Rev.C, dated October 21,1999 or later approved FAA revisions.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Rockwell Collins RCA-280 Rev. - dated March 5, 2010 Instructions forcontinued airworthiness, Damage Tolerance Inspection.Timco Maintenance Manual Supplement to Chapter 25-00-00-001, September15, 1999.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision...	None.	13/04/2012	Active	10037095
10037096	BOMBARDIER INC.		TCCA STC NO. SA04-113	BOMBARDIER BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9420.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA STC No. SA04-113 Issue 1, dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionJG, dated 07 October 2011.Instructions for Continued Airworthiness GC94200000-IFCA.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	Restricted to ASN 9420 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN System is compatible only to IEEE 802.11(b).	02/11/2011	Active	10037096
10037106	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04244AT-D	GULFSTREAM GV-SP	Executive Aircraft Completion, Multiple STC.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC522048010, Revision -, dated October 18, 2011.Operation to be in accordance with Gulfstream Flight Manual SupplementGC52204M068, Original Release, dated October 18, 2011.The following Instructions for Continued Airworthines...	None	03/11/2011	Active	10037106

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037113	BOMBARDIER AEROSPACE	REV. 1	TCCA STC SA11-41	BD-100-1A10 (CHALLENGER 300)	Activation of Wireless Local Area Network Access Point, ICGNxtMailServer System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI F-01 "Installation of Wireless System", Issue 2 dated 29/09/2011The requirements for environmental protection and the associatedcerti...	-Modification Data Summary H11000 rev N/C dated 8 June 2011-Instructions for Continued Airworthiness ref. H110070-ICA rev N/C-Airplane Flight Manual Supplement ref. H110090 rev NCor later revisions of the above listed documents approved byEASA inaccordance with the Canada/EU TIP for Airworthiness a...	This system is intended to provide cached internet content and e-mailservices to Portable Electronic Devises. Any otheruse of this equipmentwill require a re-examination of the certificate basis.this STC is a design certification approvalfor the activation of theNxtMail Server wireless function. O...	07/11/2011	Active	10037113
10037122	BOMBARDIER INC.		TCCA STC NO. C-LSA05-030/D	BD-700-1A11	Aircraft Completion, 13 Passenger Interior Configuration.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. C-LSA05-030/D Issue 5 dated 01 November 2011.Aero Consulting Services Modification Data Summary D452001 revision D orlater approved revision.Bombardier Aerospace Flight Manual Supplement G-FM25000121 Revision NCor later approved revision.Instructions for Continued Airworthin...	Restricted to ASN 9130.Drawing B170044250045 Rev N/C "WD-MOD. TO WIRELESS CABIN NETWORK WIRINGPROVISION" disables the Wireless LAN system by disconnecting, cappingStowing the WLU electrical connector. In lieu of conformity to drawingB17004420045 Rev N/C, the WLU circuit breaker may be "locked out" i...	04/11/2011	Active	10037122
10037123	AMAC AEROSPACE SWITZERLAND AG			A319-133	Monitor Replacement / Exchange of Plasma-TV with LCD-TV screens in VIPcabin.	JAR25,, Amdt: 11The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI-D 4310-009The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable...	Master Document List BK02-4420Engineering Order EO-BK-4420or later revisions of the above listed documents approved by EASA.	S/N: 2421	04/11/2011	Active	10037123
10037159	ROEDER PRAEZISION GMBH	REV. 1		A320-214	A320 Cabin Reconfiguration for AZAL.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalJAR 25 Change 11 and EASA CS 25.853 Initial Issue, as per Air BerlinTechnik'sCertification Report A320-CR25-06-2011 Revision 1.In additio...	- Master Documentation List A320-MDL25-06-2011 Revision Initial dated 05November 2011; and-Engineering Order A320-EO25-06-2011 Revision 1 dated 21 October 2011;or later revisionsof the above listed documents approved by EASA.	- This design change (STC) is applicable to the following AirbusA320-214 serial number aircraft (MSNs): 2685; 2846; 2853; 2865; 2991 and3006.This STC does not require a revision or supplement to the original TCHolder's EWIS Instructions for Continued Airworthiness.Prior to installation of this modif...	15/06/2018	Active	10037159
10037166	DELTA ENGINEERING CORPORATION			A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303	Panasonic Global Communication System - System installationThis STC covers the installation of Panasonic Global CommunicationSystem (GCS) and activates the wireless portion.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product are unchanged andremain applicableto this certificate/ approval.	Master Data List, ref : 0154-06950-2224, revision A, dated 25 October2011Aircraft Flight Manual Supplement, ref : 0654-07479-2224, dated 28October 2011Instruction for Continued Airworthiness, ref: 0754-06958-2224, revisionA<(>,<)>dated 15 May 2011or later revisions of the above listed documents appr...	None	07/11/2011	Active	10037166

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037167	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02884NY-D	A330-341 / -342 / -343 A330-321 / -322 / -323 A330-301 / -302 / -303 A330-223 / -243 A330-201 / -202 / -203	Panasonic Global Communication System - Antenna installationThis STC installs a large antenna for the future use of Panasonic GlobalCommunication System (GCS), on A330-300 aircraft models.Revision 1 of this STC extends the applicability tothe A330-200aircraft models.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, ref : 0143-06498-2193, revision D, dated 21 October2011A330-200 Aircraft Flight Manual Supplement, ref : 0600-07537-2193, dated03 October 2011A330-300 Aircraft Flight Manual Supplement, ref : 0600-07478-2193, dated28 October 2011A330-200 / -300 Instruction for Continued Airworthine...	None.	16/03/2012	Active	10037167
10037201 (EASA.R.S.00464)	AIR AMBULANCE TECHNOLOGY GmbH	REV. 3		2. AB212, AB412, AB412 EP 1. 212, 412, 412EP	Installation of Air Ambulance EquipmentExtension of existing EASA.R.S.00464 Rev. 2 with Helicopter Model 412EP	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-29, Amdt. ED 2008/10/RM, 17.11.2008The requirements for environmental protection and the associatedcertificated noise and/ or emissions...	-Flight Manual Supplement Rev. 4, FS AAT 14, date: 06/2011-Instructions for Continued Airworthiness - ICA, CMM-205/212/412-AAT 18,date: 01/2010or later revisions of the above listed documents approved by EASA-Master Data List Rev. 0, MDL-Bell 412-1, date: 10.06.2011-Classification to Change to Type0...	None	11/11/2011	Active	10037201
10037223	BOMBARDIER INC.		TCCA STC SA04-113	BOMBARDIER BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9419.	The Certification Basis for the original product remains applicable tothis certificate/ approval .The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval .	TCCA STC No. SA04-113 Issue 1, dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionJJ, dated 13 October 2011.Instructions for Continued Airworthiness GC94190000-IFCA.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	Restricted to ASN 9419 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN System is compatible only to IEEE 802.11(b).	11/11/2011	Active	10037223
10037231	AIR AMBULANCE TECHNOLOGY GmbH			MYSTERE FALCON 50	Installation of Air Ambulance Equipment "quick conversion" in MF50 inthe RH Cabin Section of Aircraft.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 25 Amdt 4 ED 2007/020/R, 27.12.2007The requirements for environmental protection and the associatedcertificated noise and/ or emission...	Master Data List Rev.1, MDL- MF50-17.000-5xx, Date: 20.10.2011Certification Program Rev.1, CP-MF50-25-20-17.000-5xx, Date: 20.10.2011Classification to Change to Type design Rev.0,CL No.163, Date: 05.08.2011Compliance Record Rev.0, CR-MF50-17.000-501, Date: 05.08.2011Testreport Rev. 0, TR No. 117/11,T...	None.	11/11/2011	Active	10037231
10037255	ANUVU	REV. 4		A330-941 A330-841 A330-341/-342/-343 A330-341, -342, -343 A330-321/-322/-323 A330-321, -322, -323 A330-301/-302/-303 A330-301, -302, -303 A330-243, -243F A330-223/-223F/-243/-243 F A330-223, -223F A330-201/-202/-203 A330-201, -202, -203	Implementation of Electronic Flight Bag Class 2This STC installs provisions for Class 2 EFB (navAero T.Bag C²).Revision3: Transfer of STCRevision 4: Extension validity to models A330-941 and A330-841	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 Amdt 4 forCS25.1322 and CS25.1529, CS 25 Amdt 10 for the other paragraphs affectedby the changeThe requi...	-Engineering Change Request ECR 10037255R01-001 Rev B dated09.Mai.2022-Master Data List 1420MDLA330 Rev A signed on 28.June. 2022-Instructions for Continued Airworthiness 1420-ICA-A330 signed on19.Mai.2022-Aircraft Flight Manual 1420-AFMS-A330 Rev A signed on 18.Mai.2022or later revisions of the abo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/07/2022	Active	10037255

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037296	HAWKER BEECHCRAFT Ltd.	REV. 1	CAA UK RESPONSIBILITY	750, 800XP, 850XP, 900XP	To introduce interior and electrical provisions for Medevacstretcherrole change capability.This Change instructs the interior and electrical changes to theaircraft. Stretcher andmedical equipment installation will be certifiedby the appropriate vendor.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged an remain applicable to this certificate/ approval.	Installed in accordance with Major Change SC0399A at issue 8Maintained in accordance with Instructions for Continued Airworthinessdocument ref ASC-R-023-AW4014 at issue 3Aircraft Flight Manual Supplement 140-590037-0005 Supplement 5 Issue 1or later revisions of the above listed documents approved by...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	14/03/2013	Active	10037296
10037297	BOMBARDIER INC.		TCCA STC SA05-60	BD-700-1A11	Installation of Complete Custom Aircraft Interior - ASN 9430.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. SA05-60 Issue 1, dated 14 June 2005.Aero Consulting Services Ltd Configuration Definition List E025000Revision FJ, dated 10 November 2011.Bombardier Aerospace Aeroplane Flight Manual Supplement G-FM25004501,Revision N/C or later approved revision.GC94300000-IFCA Instructions for Continu...	Restricted to ASN 9430	17/11/2011	Active	10037297
10037304 (EASA.A.S.03890)	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			PA-44-180	Avionics upgrade including Aspen Electronic Flight Display (EFD) 1000Pro system and Garmin GNS 430 W with coupling to S-TEC 55X automaticpilot	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 23 original issue, § 303, 305, 561, 601, 603, 607, 609, 867, 1301,109, 1311, 1321, 1322, 1329, 1351, 1353, 1357, 1365, 1381, 1431, 150...	SEAM Flight Manual Supplement SMV/ 2569/09/1, revision 4, dated08/12/2009 and SMV/ 2569/09/2, revision 4, dated 20/11/09,andSMV/ 2569/09/3, revision 4 dated 27/11/09or later revisions of the above listed documents approved by EASA	1) This avionics installation if limited to aircraft S/N 44-8095025 andit is approved for BRNAV, PRNAV and RNP ApproachLNAV operations.2) The only authorized mode for GPS coupling to the S-TEC 55X automaticpilot (AP) is the NAV GPSS mode of the AP (activation by double press onNAV button of the AP)...	17/11/2011	Active	10037304
10037313	DAHER SOCATA A/S	REV. 3		AS355 F2	Modification STC.34.001.11 Version A for VFR - Installationof GNS 430Wfor VHF1/ NAV1/ILS1/GPS1, AN/ARC 210 for VHF2, BXP6401 for XPDR Modes S,Sky Connect for Iridium Sat Phone, Motorola DM3600 for UHF FM.Rev. 1: Amendment of the configuration to add Version B for IFR -Installation of GNS 430W for VH...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FMS-STC 34.001.11 Version A VFR - Flight Manual Supplement,Rev. - FMS-STC 34.001.11 Version B IFR - Flight Manual Supplement, Rev. - or later revisions of the above listed documents approved by EASA-STC 34.001.11 Version A VFR/B IFR - Installation Description Rev. 1;-STC 34.001.11 Version A VFR/B IFR...	Version A limited to VFR onlyVersion B: for IFR-operation refer also to AS355 F2 RFM Supplement 11.4"IFR Flight".Serialnumbers 5026, 5299, 5298 and 5156 onlyPrior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously...	03/07/2014	Active	10037313
10037327	GPI			AS 332 C, C1, L, L1, L2	Installation of Cargo Net in Cabin.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Voluntary compliance to the following paragraphs of CS29 Change 2 dated17 November 2008:29.1, 29.561, 29.787, 29.855 (a)(2), 29.1301(b).Th...	SFM-P-10-007 issue 1 dated 3 November 2011 - Flight Manual Supplementor later revisions of the above listed documents approved by EASA.CMM/P10007 revision 2 dated 3 November 2011 - Cargo Net ComponentMaintenance Manual;CMX/10-007 issue 4 dated 3 October 2011 - Compliance Matrix.	No Passengers allowedWeight Limitation - 294 kg;Maximum deformation - 257mm	18/11/2011	Active	10037327

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037345	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 525B	Installation of L3 FA2100 Digital FDR	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to Engineering Order No. 2068970-EO Issue 1To be operated in accordance with AFM-S Document No. 2068970-AMIssue 1To be maintained i.a.w. CA Document No. 2068970-CA Issue1or later revisions of the above listed documents approved by EASA	S/N 525B-135 and onAccording limitation section of AFM-S	18/11/2011	Active	10037345
10037356	ATELIER CHABORD	REV. 3		FA150K, FA150L, FA150M F150K, F150L, F150M F150F, F150G, F150H, F150J	STC CESSNA150-11-01 Rev. E - Dispositif de boite de réchauffagecarburateur additionnel sur ensemble collecteur d'échappement etsilencieux.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAM STCCESSNA150-11-01 Rev. E du 21 Novembre 2011;Programmed'entretien additionnel entretien-cessna150-11-01 rev C du 31Octobre 2011;or later revisions of the above listed documents approved by EASA.	Tout Reims Aviation Cessna F150F à M. FA150K à M modifié selon le STCEASA 10063405 (STC 38-SF-0001) ou toute révision ultérieure.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/...	22/12/2017	Active	10037356
10037359	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	CESSNA 421C	Installation of Initial Role Change Equipment in a Civil ContingencyAircraft - Cessna 421C as defined in Cranfield Aerospace documentCAeM/Cessna/ 1327.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:FAR 23, Amdt. 0:23.21, 23.147, 23.171, 23.179, 23.233, 23.251, 23.303,23.305, 23.307, 23.321, 23.347, 23.365, 23.391, 23.609, 23.627, 23...	Type Design Definition CA/ DD/DR0109AFMS: Supplement No. 2 to POH D1546-5-13Instructions of Continued Airworthiness CA/DD/ML1327or later revisions of the above listed documents approved by EASA.	S/N 421C-0218.	22/11/2011	Active	10037359
10037360	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	CESSNA 421C	System and Structural Provisions for a Civil Contingency Aircraft -Cessna 421C as defined in Cranfield Aerospace document CAeM/Cessna/1326.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:FAR 23, Amdt. 0:23.21, 23.147, 23.171, 23.179, 23.233, 23.251, 23.303,23.305, 23.307, 23.321, 23.347, 23.365, 23.391, 23.601, 23.609, 23...	Type Design Definition CA/ DD/DR0108AFMS: Supplement No.1 toPOH D1546-5-13Instructions of Continued Airworthiness CA/DD/ML1326or later revisions of the above listed documents approved by EASA.	S/N 421C-0218.	22/11/2011	Active	10037360
10037365	B/E AEROSPACE, Inc. - FSI		FAA STC ST00756SE	B747-400	Reconfiguration of the Main and Upper Deck of B747-400 series airplanes,in accordance with Flight Structures, Inc. Master Drawing List98FS818-D01 Rev. J, dated November 10, 2009 or a later FAA approvedrevision.Validation of FAA STC ST00756SE.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Structures, Inc. Master Data List MDL 98FS818-D01 Rev. J, datedNovember 10, 2009;Flight Structures, Inc. Instructions for Continued Airworthines98FS818-D86 Rev. G, dated November 5, 2002;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/...	None.	22/11/2011	Active	10037365
10037413 (EASA.A.S.03871)	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A300-600 SERIES	Cockpit Door Monitoring SystemInstallation of the AD Aerospace "Cabin Vu" cockpit door monitoringsystem (video monitor,monitor control panel, video switch unit andthree cameras) in accordance with Tenencia Ltd Modification Report(Master Data List) TEN 656 issue 3 and Certification Compliance Report...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 Special Condition for Enhanced Airworthiness Programme forAeroplane system - Instructions for Continued Airworthiness on EWIS.The...	Tenencia Maintenance Manual Supplement TEN 656/4 issue 1Tenencia Operations Manual Supplement TEN 656/7 issue 1TenenciaInstallation Instructions (Configuration 1) TEN 656/10.1 issue1Tenencia Illustrated Parts Catalog TEN 656/17 issue 1Tenencia Weight and Balance report TEN 656/24 issue 1or later re...	None	25/11/2011	Active	10037413

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037415	DASSAULT FALCON SERVICE			F900EX EASY F900B, F900C, F900EX	FR14 CABIN PARTITION WITH MECHANICAL POCKET SLIDING DOOR.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- § 789 (a) - 812(b)(1)(ii) - 1301 - 1309 (c) - 1322 - 1353 (a) (b) -1529 - 1541 - 1581 at JAR 25 Change 14.- CRI D-9101-002 Deviation "In...	DFS Change Approval Sheet DFS9654-CAS Issue A dated 06.08.2011.DFS Modification Sheet DFS9654, Issue A dated 28.07.2011.DFS Airplane Flight Manual Supplement N°- F900-033 dated 27.07.2011 for F900B- F900-034 dated 27.07.2011 for F900C & F900EX- F900-035 dated 13.09.2011 for F900EX EASyor later revis...	As per DFS Change Approval Sheet DFS9654-CAS Issue A dated 06.08.2011.	25/11/2011	Active	10037415
10037417	DASSAULT FALCON SERVICE			F900EX	F900EX S/N 038 Cabin Layout Modification.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- § 25.X1499 - § 25.853 (a) (b) + Appendix F Part I<(>&<) >II at JAR 25Change 14The requirements for environmental protection and the assoc...	DFS Change Approval Sheet DFS9655-CAS Issue A dated 10.09.2011.DFS Modification Sheet DFS9655, Issue A dated 20.10.2011.or later revisions of the above listed documents approved by EASA	Restricted to F900EX S/N 038	25/11/2011	Active	10037417
10037425	JET AVIATION AG, BASEL			FALCON 2000EX	Change consists in activating WLAN WiFi function of existing Satcom/LANrouter equipment.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI F-2104-001 Means of Compliance "Wireless Local Area Network (WLAN)Activation" closed at Issue 1 on 14.09.2011The requirements for envi...	Master Data List Doc. No. BF2TX23261-001 Rev. B dated 10.11.2011Instructions for Continued Airworthiness Doc. No. BF2TX23261-150-01 Rev.IR dated 28.06.2011Airplane Flight Manual Supplement Doc. No. BF2TX23261-201-01 Rev. IRdated 27.06.2011or later revisions of the above listed documents approved by...	Aircraft must be fitted with Dassault Aviation M3196 that installscomplete Aircell Axxes II system, including WiFi antennas.	25/11/2011	Active	10037425
10037473	SIERRA INDUSTRIES Ltd.		FAA STC SA1435WE	180H	Installation of drooped ailerons in flap down mode, re-contoured wingleading edge in accordance with FAA STC SA1435WE.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Owner's Manual Supplement OMS 10-4Drawing List No. 10, dated June 25, 1985or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).MaintenanceInstructions SMM 10-1	S/N 18051446 through 18052284 onlyInstallation of SC-100 Stall Warning system is not included.CG range: straight line between points- Amphibian with (+42.2) to (+43.9) @ 2950 lb.- EDO 597-2790 (+36.0) to (+43.9) @ 2258 lb. or lessControlSurface Movements - AileronsFlap Setting,,Droop from Neutral...	29/11/2011	Active	10037473
10037477	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.			BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9416	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/appr...	TCCA STC No. C-LSA11-120/D Issue 1, dated 13 October 2011.ACS-NAI Ltd Modification Data Summary H164000 Revision NC or laterapproved revision.Flight Manual Supplement for InteriorCompletion, FMS-IA700-9416Revision NC or later approved revision.Flight Manual Supplement for CMC Electronic Flight Bag,...	Restricted to ASN 9416.Refer to the Airworthiness Limitations contained in the requiredAirplane Flight Manual Supplements.The Wireless LAN System is intended to provide internet connectivity andemail services to the airplane’s cabin using portable electronic devices(PEDs). Any other intended functio...	29/11/2011	Active	10037477

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037490	TECH-TOOL PLASTICS, Inc.		FAA STC SR09133RC-D	AS 355 N AS 355 F2 AS 355 F1 AS 355 F AS 355 E	Installation of a Vertical Sliding Window in the Right Handor Left HandSliding Door in accordance with Drawing List 350A82-1750, Revision B,dated 08/25/00.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFM 355FMS-020, dated March 19, 2001or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisdecision).Drawing List 350A82-1750, Revision B, dated 08/25/00.	Both configurations cannot be installed concurrently (RightHand andLeft Hand).	30/11/2011	Active	10037490
10037491	PATS AIRCRAFT L.L.C.	REV. 1	FAA ST01725NY-D	737-900ER	Installation of ten auxiliary fuel tank system configurationsApproved configurations are the following:Configuration 1:Installation of a Five-Cell Auxiliary Fuel System inthe forward and aft cargo compartments in accordance with PATS Aircraft,LLC. Kit Installation Drawing 5942-2811-100 (Kit No. -10...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis approval :- CRI H-1 issue 3 dated 30/11/2011- CS 25.981 issue 6The requirements for environmental protection and the associatedcertified noise and/ or emission...	- Document TO-3868 revision IR dated 29 November 2011 'Boeing 737-900ER(BBJ3) index of applicable FARs and JARs (STC ST01725NY-D Validation)- Certification plan and System Description TO-4686 revision A datedNovember 17, 2011- Certification plan and System Description TO-4735 revision B dated May24,...	Configurations 1 & 5: PATS Aircraft, LLC. Airplane Flight ManualSupplement No. 221 for a Five-Cell (1 Fwd/4 Aft) Auxiliary Fuel System,revision IR dated January 30, 2009 is required. Approved for aircraftwith NGS.Configurations 2 & 6: PATS Aircraft, LLC. Airplane Flight ManualSupplement No. 222 for...	13/04/2021	Active	10037491
10037504 (EASA.A.S.03322)	JET AVIATION AG	REV. 5		737-700	EMS SATCOM AMT-3800 InstallationRevision 5 to include an additional installation area of the EMS SATCOMAMT-3800 Satcom antenna on the forward fuselage between STA 480 and STA500B crown area.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	JetAviation STC Certification Plan: JBSL-M-00789CER-02 Issue 1< (>,<)>or later revisions of the above listed document (s)approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/07/2019	Active	10037504
10037514	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03606AT	757-200/-200CB/-200PF/-300	Installation of the Iridium SATCOM Communication System in the Boeing757-200 and 757-300 Series aircraft.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List 2-68511-011, Revision M, dated November 3, 2015.2. FAA Approved Flight Manual Supplements for the Iridium SATCOMCommunications System are required parts of this STC:a. Configuration 1-2-65911-804, Revision A, dated November 15, 2011.b. Configuration 2-2-86160-805, Revision A,c...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10037514
10037518	WESTERN AVIONICS			DHC-6-1/-100/-200/-300	Installation of Garmin GPS 155XL for supplemental IFR Navigation in acc.with TCCA STC SA01-93, Issue 1	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23, Amdt. 23-0:23.1, 23.301, 23.303, 23.305, 23.307, 23.321, 23.561, 23.601, 23.603,23.605, 23.609, 23.611, 23.613, 23.619, 23.627, 2...	Western Avionics Modification data Summary 71961-900, Revision 2, datedMay 31, 2001Western Avionics Flight Manual Supplement 71961-801, Initial issue, TCCAapproved August 1, 2001or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subseq...	None	02/12/2011	Active	10037518

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037522	ROCKWELL COLLINS, Inc.		FAA STC NO. ST02177LA	CL-600-2B16	HUD/EVS Model 6605 Validation of HUD/ EVS in a Deactivated State	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	FAA STC No. ST02177LA dated 04 December 2009.Installation of Rockwell Collins Model 6605 Head-Up Display (HUD) andEnhanced Vision System (EVS) CMA-2600i Infrared Sensor System (ISS) inaccordance with FAA Approved Rockwell Collins Master Drawing List forModel 6605 Head-Up Display (HUD-6605), Document...	Restricted to ASN 5872.This approval is for the installation and deactivation of the HUD andEVS in accordance with section 9 of the Rockwell Collins Master DrawingList 9701-1267 Revision D-1.	02/12/2011	Active	10037522
10037523 (EASA.A.S.03880)	STC TWENTY ONE LIMITED		CAA UK RESPONSIBIL ITY	A318, A319, A320, A321	Introduction of an Avionica Mini Quick Access Recorder MK III withCellular Module	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval1. Special Condition SC H-01 "Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS"The requirements for environmental prote...	- Certification Programme, ref. S21.PROG-0639, Issue 3, dated 13thOctober 2011- Master Document List, ref. S21.MDL-0638, Issue 2, dated 13th October2011- Compliance Checklist, ref. S21.CCL-0638, Issue 2, dated 14th October2011- Equipment Approval, ref. S21.EAF-0254, Issue 3, dated 13th October2011or...	Not applicable	02/12/2011	Active	10037523
10037524	SABENA TECHNICS BGC			A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303	Panasonic eXPhone System activation on A330-300 with eX2 IFEThis STC installs a Panasonic eXphone System allowing, in conjunctionwith other devices, the use of cellphones during flight.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.-CS 25 Amendment4- CRI H-01 Issue 1 - Enhanced Airworthiness Programme for AeroplaneSystems - ICA on EWIS-CRI F-01 Issue 1 - Mobile Commu...	Master Data List, Ref : 0496-02-A-2103-R00, dated 01 December 2011Instruction for Continued Airworthiness, Ref : 0496-02-A-2211-R01, dated30 November 2011Aircraft Flight Manual Supplement, Ref : 0496-02-A-2301-R00, dated 05October 2011Instructions for Operation:Master Minimum Equipment List Suppleme...	The following modifications are prerequisites to the installation ofthis STC:-Airbus Minor Change ref: 200190 - Approved under Airbus DOAEASA.21J. 031, on 22 February 2011-Delta Engineering STC ref: ODA-2234-01 - EASA Approval 10036548 Rev 1or later revisions of the above listed documents approved by...	02/12/2011	Active	10037524
10037544	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBIL ITY	B757-300	Installation of Geven Piuma Seats as defined in H4ACP076	JAA TCDS JAA/25/98-019 Issue 2The Certification Basis for the original product remains applicable tothis certificate/ approval.CRI H01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissionslevels of the original product areunchanged and remain appli...	H4 Aerospace Modification Summary Sheet and Declaration of ComplianceNo. MOD H4A1469 Issue 1 dated 18 November 2011.or later revisions of the above listed documents approved by EASA	None	05/12/2011	Active	10037544
10037559	airplus engineering GmbH	REV. 4		SEE EASA APPROVED MODEL LIST	Installation of G600 Avionics System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23 Amendment 02(not required according to 21.101) - 1, 29, 301, 303, 305, 307, 335,337, 351, 365, 441, 443, 561, 603,6...	- Flight Manual Supplement PO-0972-000000, Issue 3-0- Description of Modification for STC-Rev. 3, DE-0972-000003, Issue1- Engineering Work Order EW-0972-000000, Issue 5- Maintenance Manual Supplement MM-0972-000000, Issue 3or later revisions of the above listed document(s) approved/acceptedunder th...	The Aircraft must have been already equipped with a suitable Autopilot.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwor...	10/02/2021	Active	10037559

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037572	LEARJET Inc.	REV. 1	FAA STC ST00288BO	BD100-1A10 (CHALLENGER 300)	Installation of Honeywell EGPWS with windshear and Terrain Display (MDL-1 configuration), Runway Awareness and AdvisorySystem (RAAS) (MDL -2configuration) or Runway Awareness andAdvisory System (RAAS) inhibit(MDL -3 configuration) in accordance with Bombardier Aerospace BusinessAviation Services M...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate- CRI F-1 issue 2 dated 29/11/2011The requirements for environmental protection and theassociatedcertificated noise and/ or emissions levels of the...	- FAA Supplemental Type Certificate ST00288BO dated 3, September 2009- FAA approval of MDL BAS68017001 Revision A datedFebruary 28, 2011- Master Drawing List ref. BAS68017001 Revision A dated February 28,2011- Certification plan for Bombardier Aerospace BD-100-1A10 Rev B dated 3August 2009- Instruc...	- Instructions for Continued Airworthiness ref. BAS68017001-ICA-1 rev Adated January 14, 2011 must be made available tothe operator at thetime of installation for MDL-1 configuration, EGPWS with Windshear andTerrain Display.- Instructionsfor Continued Airworthiness ref. BAS68017001-ICA-2 rev Adate...	19/03/2012	Active	10037572
10037574	GARMIN INTERNATIONAL, Inc.	REV. 12	FAA SA02019SE-D	SEE FAA AML SEE ABOVE	Installation of Garmin GTN 6XX/7XX and GTN Xi Series Navigation System.Revision 11 adds more capability and new Part 23models to the AML.Revision 12 adds the EASA AML to STC 10037574 (for EASA only models).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:See EASA Approved Annex to STC Approval dated 17/01/2024.The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	- For Aircraft in FAA AML to FAA STC SA02019SE-DGarmin Master Drawing List (MDL) 005 00533-C0, Revision 1, approved 18March 2011.The MDL identifies applicable FAA approved Airplane Flight ManualSupplements and System Maintenance Manual (including Instructions forContinued Airworthiness).The MDL, asF...	The STC is valid for those aircraft types and models approved by EASAand listed on the FAA Approved Model List SA02019SE-D, dated 11 December2020, and for aircraft types and models listed in EASA AML to EASA STC10037574 attached to this approval (which are only approved in EASASystem: “EASA only mod...	18/01/2024	Active	10037574
10037575	ROEDER PRAEZISION GMBH	REV. 2		EMB-145MK, EMB-145EU EMB-145LU EMB-145ER, EMB-145LR EMB-145EP, EMB-145MP EMB-135ER, EMB-135LR EMB-135BJ	Installation of HID Taxi/Landing light, inspection light onEMB-145aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	Master Document List doc. N° EMB145-NY-04188-MDL Rev. 2 dated 07.12.2011Airplane Flight Manual Supplement doc. N ° EMB145-NY-04188-08 Rev. 4dated 02.12.2011Instructions for Continued Airworthiness - Maintenance procedures doc.N° EMB145-NY-04188-07 Rev. 3 dated 02.12.2011or later revisions of the abov...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/11/2017	Active	10037575
10037576	AEROLITE AG	REV. 3		AW109SP	EMS Equipment P/N 109-0002060 with Swiveling Adapter P/N 001-0019851-503for the following seat installations:(1) Medical Seat Inst. RH P/N 1090120-502(2) Medical Seat inst. CenterP/N 1090120-503(3) Medical Seat Inst. Training P/N 1090120-505(4) Medical Seat Inst. LH P/N 1090120-507See Master Docume...	CS-27, Initial IssueThe Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement: FMS-109-0002060, rev A dated 10 April 2013;or later revisions of the above listed documents approved by EASA.Instruction for Continued Airworthiness and Operation Manual:OPM-109-0002060 -XXX, rev C dated 2 May 2013.	Swivelling Adapter P/N 001015-503 approved under EASA STC No. 10037576,Rev. 1 are not eligible for new installations.Prior to installation of this design change it must be determined thatthe interrelationship between this design change andany otherpreviously installed design change and/ or repair w...	15/03/2016	Active	10037576
10037579	OGMA, INDUSTRIA AERONAUTICA DEPORTUGAL, S.A.			EMB-145LU EMB-145EP, EMB-145LR	Installation of a VIP meeting room on EMB-145	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval	- Change approval sheet doc. N° 10 P15 CAS 02 001, Rev. Orig. dated24.11.2011- Change Dossier doc. N° 10 P15 CD 02 001,Rev. Orig. dated 21.11.2011- Airplane Flight Manual Supplement doc. N ° 10 P15 MS 02 010, Rev. Orig.dated 18.11.2011- Maintenance Manual Supplement doc. N° 10 P15 MS 02 020, Rev. Or...	Aircraft S/N 145076, 145084, 145129, 145135, and 145147.	08/12/2011	Active	10037579
10037582	AVIONITEC Ltd.			PA-28-236	IFR Avionics upgradeRemoved:- King KY 197A COM- King KMA 20Audio Panel- King KN 53 NAV Receiver- King KI 203 NAV Indicator- David Clark Isocom IntercomInstalled:- Garmin GNS530W GPS/COM/NAV with GA35 antenna- Garmin GMA 347 Audio Panel- King KR 87 ADF System with KA44B antenna- King KI227 ADF Indica...	FAR 23The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificatednoise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List: Doc. No. PI01488-017, dated 26.08.2011Instructions for continued airworthiness: PI01488-015, dated 26.08.2011Airplane Flight Manual Supplement: PI01488-011, dated 26.08.2011	S/N: 28-8011011 HB-PEN	08/12/2011	Active	10037582

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037583	AVIONIK STRAUBING ENTWICKLUNGS GmbH			2. PA-31T, PA-31T1, PA-31T2 2. PA-31T3 2. PA-31P, PA-31P-350 1. PA-31, PA-31-300, PA-31-325 1. PA-31-350	Installation of Garmin G600 System with Synthetic Vision (SVT)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	-Flight Manual Supplement G600: ASR-2011-033-FMS-05.1-00, Rev. 00-Flight Manual Supplement EPU6A5: ASR-2011-033-FMS-05.2-00, Rev. 00-Instruction for Installation Garmin G600: ASR-2011-033-IFI-10.1-00,Rev. 00-Instruction for Installation Garmin EPU6A5: ASR-2011-033-IFI-10.2-00,Rev. 00-Instruction for...	None	08/12/2011	Active	10037583
10037593	SABENA TECHNICS BOD	REV. 3		A340-542	VIP Tunisair upgrading projectThis STC installs a new cabinconfiguration, with presidential area.The revision1 updatedthe Associated Technical Documentation, in linewith the design evolution.The revision 2 updated some Certification documents, following theactivation of specific system.This revisi...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-1302-004: Isolated CompartmentsD-1310-003: Glass screens of displays / monitorsD-1311-001: Glass Panels in the cabinD-1314-001: Shower InstallationD...	-Modification Approval Sheet, Ref: MAS S-00-2156 Revision 6, dated 16Sep. 2013-Technical Repercussion Sheet, Ref: TRS S-00-2156 Revision D, dated 12Mar. 2012-Aircraft Flight Manual Supplement, Ref: AFMS-F4032-00-001 Revision G, 14 Mar. 2012-Airworthiness Limitation Section Supplement, Ref: ALS-F4032-...	This STC is applicable to MSN 902 onlyNote: MMEL Supplementassociated with this STC is not covered by thisSTC approval	22/07/2016	Active	10037593
10037612	AIRBUS S.A.S.			A320-214	Airbus Corporate Jet Centre Modification CJ1118 Issue 1 - Cabin SystemUpgrade	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI A-2301-005 "ACJC Centre Conversion Project Certification Basis"The requirements for environmental pr...	- Modification Approval Sheet ref.: CJ1118 Issue 1, dated 9th December2011- Airplane Flight Manual Supplement, ref.: FM-S MOD CJ1118, dated 1stDecember 2011or later revisions of the above listed documents approved by EASA	This STC is limited to A320-214 MSN 2165	12/12/2011	Active	10037612
10037640	BOMBARDIER INC.		TCCA STC NO. SA04-113	BD-700-1A10	Installation of Complete Custom Aircraft Interior - ASN 9423.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. SA04-113 Issue 1, dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionKB, dated 07 December 2011.Instructions for Continued Airworthiness GC94230000-IFCA.or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDt...	Restricted to ASN 9423 and1. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.2. WLAN System is compatible only to IEEE 802.11(b).	12/12/2011	Active	10037640
10037643	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	A330-243	Installation of new Business Class Avio EBIZ Seats and IMS Rave IFESystem.The FWD cabin is currently configured with BCand EY seats which are tobe removed and replaced with new Avio BC seats. The MAS 200E IFE systemwill be removed from the FWD Cabin and replaced with the IMS RAVE IFEsystem.There wi...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval;A330 EASA TCDS A.004 and the following CRIs:-,,F-4302-003 IFE ISPSS-,,F-4301-003 Executive Power SystemThe requirements for environmental...	Certification Programme (including Master Data List in chapter 9)JN284-001 ADC12 (1) Issue 3 dated 1st of November 2011;or later revisions of the above listed documents approved by EASA.	None.	13/12/2011	Active	10037643

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037644	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9429.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. SA04-113 Issue 1, dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 RevisionJU, dated 30 November 2011.Instructions for Continued Airworthiness GC94290000-IFCA.or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDt...	Restricted to ASN 9429 and1. Refer to the Limitations section of the required AFM Supplement andto the referenced FCOMS.2. WLAN System is compatible only to IEEE 802.11(b).	13/12/2011	Active	10037644
10037652	BELL TEXTRON, Inc.		FAA STC SR03923AT	BELL 407	Installation of Aeronautical Accessories Lighting and Vision Accessoriesfor Bell Helicopter Textron 407 Model HelicoptersAny of the following kits can be installed individually orin anycombination:- Preflight Lighting Kit per installationinstructions AA-10093, Rev. Cdated 6/17/11.- Courtesy Lighti...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The following FAR 27 paragraphs:§27.301 Amdt 27-0§27.303 Amdt 27-0§27.305 Amdt 27-0§27.561 Amdt 27-30§27.307 Amdt 27-26§27.601 Amdt 27-0§...	-RFM Supplement, Aeronautical Accessories documents AA-10082 andAA-11004 for Bell 407 series Aircraft, dated June 29, 2011or later revisions of the above listed documents approvedby EASA-MDL A-2009-095-1, Rev C, dated June 27, 2011-Drawing List AA-10080 "Lighting/Vision Accessories" Rev H, dated Ju...	None	13/12/2011	Active	10037652
10037659	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC ST10890SC-D	F2000EX	Aft RH Divan installationValidation of FAA STC N°ST10890SC-D	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Certification Review Item CRI D-2112-001 closed at issue 3 - SpecialConditions "Single place side-facing seats"The requirements for envir...	DFJ Certification Data List doc. N° F2EX-01038 Revision AJ dated October31, 2011.Instructions for Continued Airworthiness doc. N° ICA-F2EX-01038-501Revision Original, dated January 21, 2011.Airplane Flight Manual Supplement doc. N °40709-1 dated April 14, 2011.or later revisions of the above listed d...	As per FAA STC N °ST10890SC-D	14/12/2011	Active	10037659
10037660	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC ST10891SC-D	F2000EX	Avionics and interiors installationValidation of FAA STC N °ST10891SC-D	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI D-GENE-03 complied with through compliance with FAR 25 §25.856(a)The requirements for environmental protection and the associatedcert...	DFJ Certification Data List doc. N° F2EX-01039 Revision C dated December07, 2011.Supplemental Maintenance Manual reportN° SMM F2000EX-SN216, RevisionOriginal, dated January 21, 2011.Airplane Flight Manual Supplement doc. N °37159-F2EX-D514dated April 14,2011.Supplemental Illustrated Part Catalog, r...	As per FAA STC N °ST10891SC-DRestricted to F2000EX S/N 216	14/12/2011	Active	10037660
10037675	BOMBARDIER INC.		TCCA STC NO. SA05-60 ISSUE 1	BD-700-1A11	Installation, Complete Custom Aircraft Interior - ASN 9226	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	TCCA STC No. SA05-60 Issue 1, dated 14 June 2005.Aero Consulting Services Ltd Configuration Definition List E025000Revision FF, dated 23 September 2011.Bombardier Aerospace Aeroplane Flight Manual Supplement G-FM25004501,Revision N/C or later approved revisionGC92260000-IFCA Instructions for Continu...	Restricted to ASN 9226	14/12/2011	Active	10037675

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037677	AVIATION DEFENSE SERVICE	REV. 1		FAN JET FALCON BASIC	Carriage of ARPEGE pylons-only (Expanded Flight envelope)The purpose of this approval is to revise EASA STC 10037677 toclear thecarriage of the ARPEGE pylons only configuration on S/N 076 in thefollowing envelope:VMO 350 kts, MMO 0.78, FL390, n = +2g / -1g	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Change Approval Sheet doc. No. CAS-AVD-MDA20-95-FOG1A Rev. 02 Issue 5dated 29.10.2013Master Document List doc. No. MDL-AVD-FOG1A rev 2 Issue 3 dated05.11.2013Aircraft Flight Manual Supplement doc. No. SAFM-FALC20 Rev. 19or later revisions of the above listed documents approved by EASA	Restricted to S/N 076As per AFM Supplement N° SAFM-FALC20 Rev. 19.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviousiy installed design change and/ or repair will introduce noadverse effect upon the airworthine...	05/11/2013	Active	10037677
10037701	GAMA AVIATION (ENGINEERING) LIMITED	REV. 3	CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	GNS-430W/530W navigation system SBAS upgrade and certification of LPVcapability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gama Aviation Modification refHL/MOD/1259 and Master Document List (MDL) ref MDL-1259 ,Issue 8, 6February 2017.Operate in accordance with Gama Aviation Flight Manual Supplement refAFMS-1259-01, issue 8, 7 February 2017.Instructions for Continued Airworthiness (ICA)A...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/03/2017	Active	10037701
10037702 (EASA.IM.A.S.0116)	AVMOD, LLC	REV. 3		737-400, 737-500 737-200, 737-200C, 737-300	Modification of Wing Inboard and Outboard Aft Trailing EdgeFlaps.Revision 2 of the STC with reference to EASA.IM.A.S.0116 has been issuedas a result of its transfer from Aero Tech Service Inc (ATS) to AZRA LLCDBA AeroTech Services.Revision 3 of the STC has been issued as a result of its transfer fr...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AeroTech Services Inc, Master Drawing List No 52-0001 Revision Cdated 20 May 2003 (for Model 737-200, -200C and -300Series Airplanes);- AeroTech Services, Inc Master Drawing List No 52-0001, Revision E,dated 06 January 2005 (for Model737-400 and -500 Series airplanes) ;- Airplane Flight Manua...	Scheduled inspections and repairs are required in accordance with thefollowing documents:- Chapter 05 of the "737-200,-200C Aircraft Maintenance ManualSupplement", Report No. ATS 52-0008, Issue 4, dated 30 June 2005, for737-200 and -200C, with this STC modification, (and Issue 4 of ATS 52-0008 sup...	11/07/2018	Active	10037702
10037703	AIRBUS S.A.S.	REV. 1		A319-115	Airbus Corporate Jet Centre Modification CJ0800 Issue 4 - Project "2A"Revision due to AFM-S and MPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A-4301-005 "ACJC Project Certification Basis."The requirements for environmental protection and the associatedcertified noise and/ or emissions...	-,,Modification Approval Sheet ref.: CJ0800 Issue 4, dated24th October2013-,,Modification Approval Sheet "Conversion Private/Public and ViceVersa" ref.: CJ0875-,,Airplane FlightManual Supplement, ref.: FM-S MOD CJ0800, Revision02, dated1st October 2013-,,Maintenance Planning Document - MPD - Sup...	This STC is limited to A319-115 MSN 4470.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	25/10/2013	Active	10037703
10037704	DOA AESGLOBAL LIMITED	REV. 1		A319-132	Introduction of Panasonic dMPES In Flight Entertainment - IFE SystemRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS"The requirements for environmental protection and the asso...	- Modification Summary, ref. doc.: AES-319-1849, Issue 2, dated 14thDecember 2011- Master Data List, ref. doc.: AES-319-1849MDL, Issue 2, dated 14thDecember 2011or later revisionsof the above listed documents approved by EASA	None	27/04/2021	Active	10037704

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037705	BOMBARDIER AEROSPACE		TCCA STC NO. SA11-89 ISSUE 1	CL-600-2B16	Modification to Potable Water Tank Air Supply	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	TCCA STC No. SA11-89 Issue 1 dated 07 November 2011.ACS-NAILtd Modification Data Summary Number H311000 Revision N/C orlater approved revision.Instructions for Continued Airworthiness, Bombardier documentBAS63058003 Revision NC or later approved revision.or later revisions of the above listed docum...	Previous installation of a specific potable water system isrequired.Drawings listed in Modification Data Summary H311000 identify theprerequisite installations.	16/12/2011	Active	10037705
10037710	ACS-NAI Ltd.		TCCA STC C-LSA10-169/D	CL-600-2B19	Installation, Complete Custom Aircraft Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA STC No. C-LSA10-169/D Issue 1 dated 03 December 2010.ACS-NAI Ltd. Modification Data Summary G773000 Revision NC orlaterapproved revision.Aero Consulting Services Ltd. Mandatory Maintenance Manual SupplementG192070 Revision NC or later approved revision.Aero Consulting Services Ltd. Mandatory M...	Restricted to ASN 8101.	16/12/2011	Active	10037710
10037711	ACS-NAI Ltd.		TCCA STC C-LSA11-165/D	CL-600-2B19	Installation, Complete Custom Aircraft Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA STC No. C-LSA11-165/D Issue 1 dated 11 October 2011.ACS-NAI Ltd. Modification Data Summary H133000 Revision NC or laterapproved revision.Aero Consulting Services Ltd. Mandatory Maintenance Manual SupplementG192070 Revision NC or laterapproved revision.Aero Consulting Services Ltd. Mandatory Ma...	Restricted to ASN 8107.	16/12/2011	Active	10037711
10037721	LUFTHANSA TECHNIK AG			A330-341 / -342 / -343 A330-321 / -322 / -323 A330-301 / -302 / -303	Thai Airways A330-300 - Seat exchange and electrical adaption.This STC installs 263 Y class seats, with associated electricaladaptations.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.-,,TCDS EASA.A. 004-,,CS 25 Appendix H25.5 (amdt 8)-,,CRI F-3302-002 : IFE and ISPSSThe requirements for environmental protection and thec...	Supplemental Type Definition Document, ref : STDD00-11/17M Issue 01,dated 13 December 2011or later revisions of the above listed documents approved by EASA.	None.	16/12/2011	Active	10037721
10037753	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special Transports / Transports SpeciauxIssue 1 of ATI STC ref. ST25MOD020 (Applicant reference)< (>,<)>was developed, reviewed, tested and found compliant with the CertificationBasis to deal with non-Airbus sub-assemblies transport. On case by casebasis, this STC is up-issued to cover transportatio...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- Cf EASA TCDS A.014-CRI F-06 Issue 2 : Transport of Instrumented Payloads powered by theaircraft electrical supplyThe requirements for e...	Change Approval Sheet and Fiche de Modification ref : ST25MOD020, Issue51.or later revisions of the above listed documents approved by EASA	None	20/12/2011	Active	10037753

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037800	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	B) BN2A MARK III, III-1, III-2 B) BN2A MARK III-3 A) BN2T-4R, BN2T-4S A) BN2B-26, BN2B-27, BN2T A) BN2A-8, BN2A-9, BN2A-20 A) BN2A-27, BN2B-20, BN2B-21 A) BN2A-21, BN2A-26	GNS-W Navigation System Qualification in accordance with MDL-1275, Issue2.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS23 initial issue:23.1, 23.1301, 23.1309(a), (b), (d), (e), 23.1357, 23.1367(a),23.1381(a), (b), (c), 23.1529, 23.1581inclusiveCRI F-101A...	AFMS-1275-01, Issue 2AFMS-1275-02, Issue 2or later revisions of the above listed documents approved by EASAInstallationInstruction IPI-1275, Issue 2Instructions for Continued Airworthiness ICA-1275, Issue 2	None	22/12/2011	Active	10037800
10037804	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			1900, 1900C, 1900D, 200, 200C	Installation of Garmin 500 Series system with coupling to autopilotRockwell-Collins FCS 80, according to SEAM modification file n. 3541/11.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS 2323.301, 23.303, 23.305, 23.307, 23.337, 23.341, 23.625, 23.1301,23.1307,23.1309, 23.1321, 23.1322, 23.1329(h), 23.1335, 23.1351,23.1...	Flight Manual Supplement no. SEAM-3541-AFM, revision 4 dated 09/12/2011.STC Data List no. SEAM-3541-SDL, revision 6 dated 20/12/2011	Installation of this design change must be performed by SEAM technicalpersonnel.If the GNS 500 Series system is installed whereas another Garmin GNSsystem is already installed on the airplane, a third independentradiocommunicatio n or radionavigation system, not similar to GNSsystems, must also be in...	22/12/2011	Active	10037804
10037808	AEROTEC & CONCEPT	REV. 1		A320-214, -216 A319-115, -133	Advanced Mission Display System - phase B (AMDS/B) Activation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval- Electrical Wiring Interconnection System as per CS-25, Amdt 10,Subpart HTherequirements for environmental protection and the associated...	- Certification Program, ref. doc. AE11043PCDP, Rev. 3, dated 16thNovember 2011- Master Data List, ref. doc: AE11043MDL, Rev. 2, dated 1st December2011- Flight Manual Supplement, ref. doc: AE11043SMV, Rev. 0, dated 21stNovember 2011or later revisions of the above listed documents approved by EASA	None	22/12/2011	Active	10037808
10037809	AIR ALLIANCE GmbH			T337B, C, D, E, F, G, H, H-SP M337B, P337H 337, A, B, C, D, E, F, G, H	Replacement of installed Slaved Gyro system by ASPEN EFD 1000 PROPrimary Flight Display	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	-Airplane Flight Manual Supplement 2011_028_C337_506, Rev. 0or later revisions of the above listed documents approved by EASA-Installation Manual 2011_028_C337_500, Rev. 0-Instructions for Continued Airworthiness 2011_028_C337_507, Rev. 1-Master Document List 2011_028_C337_Form 2, Rev. 0	None	22/12/2011	Active	10037809
10037817	AVIONIK STRAUBING ENTWICKLUNGS GmbH			2. M20M, M20R 1. M20, M20A, M20B, M20C, M20D 1. M20K, M20L, M20S 1. M20E, M20F, M20G, M20J	Dual/Single Installation of Garmin GPS/ COMM/NAV GNS430(A)W/GNS530(A)W	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2 (not required by 21A.101)The requirements for environmental protection and the associatedcertificated noise and/ or emi...	-Flight Manual Supplement ASR-2011-054-FMS-05-00 Rev. 0or later revisions of the above listed documents approved by EASA-Instructions for Installation ASR-2011-054-IFI-10-00 Rev. 0-Instructions for Continued Airworthiness ASR-2011-054-ICA-11-00 Rev. 0	None	22/12/2011	Active	10037817
10037822	AMES - AEROSPACE AND MECHANICALENGINEERING SERVICES	REV. 1		A330-223, -243 A330-201, -202, -203	A330-200 Cabin reconfigurationThis STC installs mainly new B/C and Y/C seats and new In-FlightEntertainment system, according to various cabin configurations.The Revision 1 has taken into account a new cabin configuration, andreworded the limitations.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-4306-003 : Application of heat release and smoke densityrequirements to seat materials.The requirements for environmental protection and the associatedcertified nois...	Design Review Report, ref : DRR_M14800101_MBO_1702201DesignReview Report, ref : DRR_M14800101_MGR_21112012 Revision 01Engineering Order, ref : EO_M14800101_MBO_23032011 Revision 2Aircraft Flight Manual Supplement, ref : AFS_M14800101_MGR_06102011Revision 1Instruction for Continued Airworthiness, re...	The following modifications, in accordance with their aircraftapplicability, are prerequisites to the installation of this STC :- Lufthansa Technics STC ref : STDD33-03/01M - EASAApprovalEASA.A.S.02580- AMES Minor Change ref : M14800111.11082011 (Approved under AMES DOAEASA.21J.299)- AMES Minor Cha...	15/02/2013	Active	10037822

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10037841	NSE	REV. 5		EC635 T3 EC635 T1, EC635 T2+ EC635 P2+, EC635 P3 EC135 T2+, EC135 T3 EC135 T1, EC135 T2 EC135 P2+, EC135 P3 EC135 P1, EC135 P2	Installation of Brite Saver Usage Monitoring System.Rev. 1:Removal of the limitation “only for EC135/EC635 variants withCPDS-Cockpit”.Rev. 2: Change STC certificate holder nameRev. 3: Extension of the applicability to the EC135 P3/ EC635 P3 andEC135 T3/EC635 T3 models.Rev. 4: Software evolution in o...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 amdt. 3- 27.29- 27.301- 27.303- 27.305- 27.561- 27.607-27.609- 27.611- 27.1301- 27.1309- 27.1322- 27.1351- 27.1357-...	- BRITE SAVER 2 Kit EC135TX/PX definition file referencesDD-KIT-ARA0-EC135-EN revision 03 dated 31 October 2019.- UMS EC 135 certification plan reference PCERT-0116-92-EN revision05dated 05 November 2019.- BRITE SAVER 2 Mounting Instruction for EC135 referenceIM-KIT-ARA0-EC135-EN revision 05 dated-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/01/2020	Active	10037841
10037862	DUGAN KINETICS, L.L.C.		FAA STC ST02127SE	DC-9-81/-82/-83/-87, MD-88	Thrust Reverser/Installation of ejector thrust reverser on Pratt &Whitney Turbofan JT8D-217, -217A, 217C or -219 Engines as per FAA STCST02127SE dated 08 Apr. 2011.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dugan Kinetics Master Drawing List (MDL) No. 115-100, Revision A, dated14 Sept. 2010Dugan Kinetics Maintenance Program Supplement (MPS) Manual - Appendix BNo. MPS115-307, RevisionB, dated 25 Feb 2011Instruction for Continued Airworthiness (ICA) Manual No. ICA115-306,Revision A, dated 25 Feb. 2011or...	Refer to FAA STC ST02127SE.	03/01/2012	Active	10037862
10037893	SABENA TECHNICS BGC			747-100, -200, -200F	Installation of a CAS-81 TCAS II system and Dual TRA-67 "Mode S"transponders in accordance with Aeroconseil Master Drawing List0520-01-A-2103-R00 or later approved revisions.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Aeroconseil AFM supplement no 0520-01-A-2301-R00or later revisions of the above listed documents approved by EASA	None	04/01/2012	Active	10037893
10037908	ROCKY MOUNTAIN AIRCRAFT		TCCA STC SA11-72	DHC-6 SERIES 100, 200, 300	Installation of chip detectors on both left hand and right hand enginewith caution indication in DHC-6 series 100, 200,and 300 Twin Otteraircraft based on Engineering Data Summary E104600 in accordance withTransport Canada STC SA11-72, Issue 1	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement, Report E104630, Revision 0Modification Instruction, Report E104610, Revision 0or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision) Maintenance Manual Supplement, Report E1046...	None	05/01/2012	Active	10037908
10037970	DELTA ENGINEERING CORPORATION		FAA STC ST02888NY-D	777-300ER	STC ST02888NY-D: Activation of Panasonic nMAP's (Wi-Fi)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 ICA on EWISCRI F-01 WLAN	STC ST02888NY-D "Activation of Panasonic nMAP's (Wi-Fi)"Master Data List 0143-07446-2286 Rev. B dated Sep. 28, 2011-AFMsupplement 0643-07449-2286 Rev. - dated Sep. 27, 2011- Instructions for Continued Airworthiness 0743-07450-2286 Rev. A datedSep. 24<(>,<)> 2011or later revisions of the above listed...	Not Applicable	10/01/2012	Active	10037970

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038022	ACS-NAI Ltd.		TCCA STC NO. C-LSA11-009/D	CL-600-2B19	Installation, Complete Custom Aircraft Interior.	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. C-LSA11-009/D Issue 2 dated 22 July 2011.ACS-NAI Ltd. Modification Data Summary G583000 Revision A or laterapproved revision.ACS-NAI Ltd. Mandatory Maintenance ManualSupplement, G583070 RevisionNC or later approved revision.ACS-NAI Ltd. Mandatory Maintenance Manual Supplement, G583071N...	Restricted to ASN 81051.The Wireless Local Area Network (WLAN) system installed as part of theinterior completion is intended to provide cached internet content andemail services to Portable Electronic Devices. Any other use of thisequipment will require a re-examination of the certification basis.2...	12/01/2012	Active	10038022
10038053	FOKKER SERVICES B.V.			F28 MARK 0070	Activation of WLAN functionality of an already installed andcertificated router (ref EASA STC 10027637)The Fokker 70 aircraft contains a router that has been certificatedunder STAC 10027637. Fokker Services will activate and certificate theWLAN functionality.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Acceptable Meansof Compliance: CRI F-21 "Wireless Local AreaNetwork(WLAN)"The requirements for environmental protection and the associat...	-CRI F-21 "Wireless Local Area Network(WLAN))-CertificationPlan CP-0119 Issue 2-AFM change AFMJET2011-007 Issue 1Compliance Record Report CRR-0119 Issue 1or later revisions of the above listed documents approved by EASA	-Installation of EASA STC 10027637 is a prerequisite for this STC-Limitation of Wireless Local Area Network as documented in AFM changeAFMJET2011-007	16/01/2012	Active	10038053
10038064	AIR AMBULANCE TECHNOLOGY GmbH	REV. 1		LEARJET 45 45 (LEARJET 45)	Installation of Air Ambulance EquipmentReason for Rev. 1: added configuration for Adiposity patients.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): D-01,Lear 45 Ambulance Version,Obstruction due to Stretcher Installation to type III Exit.- The following paragraph(s) at a l...	- Master Document List LJ45-25-20-45.000-505-2_507-2 Rev. 0dtd. Nov.30, 2023- Aeroplane Flight Manual Supplement AFM-AAT-59-LJ45-EMS Rev. 2 dtd.January 2023-Component-, Operation-, Installation Manual IPC CMM-LJ45-AAT78 Rev. 2dtd. November 2023or later revisions of the above listed document(s) app...	- Per Aeroplane Flight Manual Supplement AFM-AAT-59-LJ45-EMS- No medical equipment is part of this approval.- Minor Change LR45-19010-050-LP, Installation of EMS power source mustbe installed prior this modification- AEROLITE EMS Kit, Installation of EMS power source EASA STC 10046038must be install...	05/12/2023	Active	10038064
10038070	AEROTEC & CONCEPT	REV. 1		A330-243/-301/-341/-343	This modification intends to:- Install the Ball-Mount support on the cockpit sliding windows- Install the two Pilot Terminal Units (PTU/B) in the cockpit on theirBall-Mount support- Install OWCU thin mounting tray- Install AMDP 3MCU fixed mounting tray in the E/E bay- Install AMDP/B and OWCU/B equip...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.A330 EASA TCDS A.004The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the or...	Certification Programme (including Master Data List in chapter 9) AE11061PCDPInstructions for Continued Airworthiness AE11061ICAFlight Manual Supplement AE11061SMVor later revisions of the above listed documents approved by EASA	None	05/06/2012	Active	10038070
10038071	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	767-31K ER	Installation of Geven 'Nova' & 'Puma' Series Passenger Seats 326Yconfiguration.	EASA CS25 Change 4The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval;CRI H01 Enhanced Airworthiness Program for Aeroplane Systems - ICA onEWIS.	Modification Summary Sheet and Declaration of Compliance H4A1389 Issue 1dated 04/01/12;or later revisions of the above listed documents approved by EASA.	Limited to installation on B767-31K Serial Numbers 27205, 27206 and28865.	16/01/2012	Active	10038071
10038077	TELAIR INTERNATIONAL, LLC		FAA STC ST02365LA	747-8	Installation of a Lower Deck Cargo Handling System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalEASA Certification Review Item "Telair Cargo Handling Systems/ EASACertification Basis Definition", CRI A-100 issue 3 dated 24.10.2011The r...	FAA STC Number ST02365LA dated 23.12.2011or later revisionsof the above listed documents approved by EASA inaccordancewith EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) FAA Letter Ref. 120L-11-613 dated 23.12.2011	None	17/01/2012	Active	10038077

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038094	DUNLOP AIRCRAFT TYRES LIMITED	REV. 1	CAA UK RESPONSIBILITY	CL-600-2B19 (RJ SERIES 100)	Installation, Dunlop Aircraft Tyres Ltd P/N DR27921T Main and DR15112TNose Gear TyresThis STC is issued in order to reflect the transfer of ownership fromACS-NAI Ltd to Dunlop Aircraft Tyres Ltd.Rev. 1: Update of technical documentationThis STC has previously been validated in the following European...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aero Consulting Services Modification Data Summary D08500is revisedto DATL PR06 MDL Rev IR- Dunlop Aircraft Tyres Ltd. Document Number DM1172 General ServicingInstructions.- Instructions for Continued Airworthiness KT509006ICA Rev IR isrevisedto DATL-PR-06-ICA Rev Bor later revisions of the abov...	Different nose landing gear part number tires may not be intermixed onthe same axle.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect up...	12/04/2016	Active	10038094
10038098	FIELD AVIATION COMPANY Inc.	REV. 1	TCCA STC O-LSA06-139/D	DHC-8-202 DHC-8-106	TCCA STC O-LSA06-139/D, Issue 2Retrofit installation of a Honeywell KHF-950 HF Radio System.	FAR 25 as per EASA.IM.A.191, issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation must be in accordance with TCCA approved FieldAviationEast Ltd. Master Drawing and Data List DDL-1158, Rev. C dated 15 August2011;Maintenance must be in accordance with TCCA accepted Maintenance ManualSupplement 20169, Rev. A, dated 08 July 2011;or later revisions of the above listed d...	The modification is limited to Serial numbers 335, 337, 445, 446.	19/01/2012	Active	10038098
10038103	DART AEROSPACE USA, Inc.	REV. 2	FAA STC SR01042SE	EC135 T2/ EC135 T2+/ EC135 T3 EC135 P2/ EC135 P2+/ EC135 P3 EC135 P1/ EC135 T1	Fabrication of Dart D135-692-011 Bearpaws in accordance with DartAerospace Drawing List No. MDL-D135-692 and installation of this system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Flight Manual Supplement FMS-D135-692-EASA Revision A orlaterrevisions of the above listed documents approved by EASA.2. Dart Aerospace USA, Inc. Master Document List No. MDL-D135-692,Revision H, dated 8 June 2017 or later FAA approvedrevision.3. Installation Instructions Document No IIN-D135-6...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Approval of this change in type design app...	21/08/2017	Active	10038103
10038104	FIELD AVIATION COMPANY Inc.		TCCA STC O-LSA06-111/D	DHC-8-202	TCCA STC O-LSA06-111/D, Issue 2Retrofit of AirCell ST3100 Satellite Telephone and Tracking System.	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation must be in accordance with TCCA approved FieldAviationEast Ltd. Master Drawing and Data List DDL-1155, Rev. C, dated 22 July2011;Maintenance must be in accordance with TCCA accepted Maintenance ManualSupplement 20162, Rev. B,dated 22 July 2011;or later revisions of the above listed do...	The modification is limited to Serial numbers 445, 446.	19/01/2012	Active	10038104
10038105	STANDARD AERO		FAA STC ST02912CH-D	MF50	Installation of an interior refurbishment and a pocket doorValidation of FAA STC N° ST02912CH-D	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Standard Aero Master Data List doc. N° 1019814 Revision B dated January08, 2011.Instructions for Continued Airworthiness doc. N° 1019827 Revision Bdated January 05, 2011.FAA STC N° ST02912CH-D issue dated January 09, 2011or later revisionsof the above listed documents approved by EASA inaccordancet...	None	19/01/2012	Active	10038105

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038108	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC ST02382LA	CL-600-2C10	Cabin Interior Noise Reduction Systems installation Kit in BombardierCL-600-2C10 (Regional Jet Series 700, 701 & 702) Series Aircraft	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	-FAA STC No. ST02382LA dated 18 November 2011.- Aerocon Engineering Company Master Drawing List No AC25-NRCL600-1000Revision B dated 29 October 2011 or later approved revision.- Aerocon Engineering Company Maintenance Manual Supplement Document No.MMS-CL600-1688 Revision A dated 28 October 2011 or lat...	None	19/01/2012	Active	10038108
10038123	AEROCONTROLEX GROUP, INC.		FAA STC ST02798CH	2. B777-200/-300/-300ER/-200LR 1. B767-200/-300/-400ER	Installation of an AeroControlex Potable Water Level SensorAssembly P/ N8430-000000	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-1 ICA on EWIS	8430-000000 DL Rev. Original, no date80-0215 Installation Instructions Rev. C, dtd. 27.Jan 201038-10-08 Instructions for Continued Airworthiness Rev. 2, dtd. 18.Jun 0938-10-09 Instructions for Continued Electrical Airworthiness Rev. 2 dtd. 18.Jun 09or later revisions of the above listed documents app...	None	20/01/2012	Active	10038123
10038130	HAECO CABIN SOLUTIONS, LLC	REV. 1	FAA STC ST03884AT-D	767-300	Installation of LCD Monitor Upgrade	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateCertification Basis as per the TCDS and CS 25 Amendment 5 for EWISrequirementsThe requirements for environmental protection and the associatedcertif...	TIMCO MDL 10T024L001, Revision F, 24/02/2012Instructions for Continued Airworthiness: 10T024R009, Revision C, 16/05/201110T024R509, Revision IR, 26/09/2011or later revisions of theabove listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis de...	None	21/05/2012	Active	10038130
10038134	BELL TEXTRON, Inc.	REV. 1	FAA STC SH3311SO	BELL 212, 412, 412EP	Replacement Windows	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AA92083 revision M dated 20 September 2010 - Drawing List andInstallation Instructions.	None	26/01/2012	Active	10038134
10038135	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	HAWKER 900XP HAWKER 750, 800XP, 850XP	To introduce Dual L3 Electronic Flight Bags (EFB) units in the cockpitwith power supplies.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Installed to Major Change SC0362A at issue 4 or later.-Hawker Beechcraft Limited Aircraft Flight Manual Supplement 3 to AFM140-590039-0005 (Hawker 750), or Supplement 3 to AFM 140-590032-005(Hawker 800XP), or Supplement 2 to AFM 140-590035-0005 (Hawker 850XP),or Supplement 3 to AFM 140-590037 (Hawk...	All EFB functionality and software approval will be the responsibilityof the aircraft operator. Unless approved otherwise by all RequiredManuals (Hard Copy) must still be carried in the aircraft.	23/01/2012	Active	10038135
10038140	LAZ-TEC, LLC		FAA STC SR00716DE	BELL 429	Crew Door Assist Handle	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AA-10134 revision A dated 9 February 2011 - Aeronautical AccessoriesDrawing ListAA-10133 revision IR dated 21 December 2010 - Instructions for ContinuedAirworthiness.	None	23/01/2012	Active	10038140

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038149	ACS-NAI Ltd.		TCCA STC NO. C-LSA11-179/D	BD-700-1A10	Modifications to Existing Interior Completions -ASN 9393.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA STC No. C-LSA11-179/D Issue 3, dated 12 January 2012;Aero Consulting Services Modification Data Summary H267000, Revision B,dated 22 December 2011 or later approved revision;Aero Consulting Services Mandatory Maintenance Manual Supplement forAntenna installation, Security Systems, FS 851.09, H2...	Restricted to ASN 9393 andThe Installation of EASA STC No. 10036060 is a prerequisite for theapproval of this STC.	24/01/2012	Active	10038149
10038157	SOCIETE AIR FRANCE S.A.			777-200	Alitalia Cabin Reconfiguration	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-1 ICA on EWIS, CRI E-10 Inflatable Seat Belts	Change approval sheet CAS-B777-11-003 Rev. 0 dtd. 19.Jan 12or later revisions of the above listed documents approved byEASA	777-200 MSN as defined in Change approval sheet CAS-B777-11-003	24/01/2012	Active	10038157
10038174	MT-PROPELLER ENTWICKLUNG GmbH	REV. 2		SA00863SE PA-31T*, PA-31T1*, PA-31T2* PA-31T, PA-31T1, PA-31T2 (*)MODIFIED WITH PT6A-135 OR -135A ENGINES PER FAA STC	Installation of 5-blade MTV-27-1-E-C-F-R (P)/CFR210-58d propellers	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23, Amendment 34 for the following paragraphs: 23.33, 23.45, 23.49, 23.51, 23.53, 23.65, 23.67, 23.75, 23.77, 23.867,23.901, 23.933, 2...	-Airplane Flight Manual Supplement E-1932, Revision 0, 21.09.2011-Installation Instruction E-1933, Revision 0, 21.09.2011-Instructions for Continued Airworthiness E-1934, Revision0, 21.09.2011-Master Operation Manual List E-1931, Revision0, 21.09.2011or later revisions of the above listed document...	None	09/01/2013	Active	10038174
10038180	TECH-TOOL PLASTICS, Inc.		FAA STC SH5822SW	AS355F2, AS355N AS355E, AS355F, AS355F1	Installation of Tech-Tool performed acrylic plastic windshield inaccordance with Tech-Tool Drawing List (Doc 3501-2023)No 1, Rev A,dated 08/28/09 (FAA STC SH5822SW)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Tech-Tool Drawing List (Doc 3501-2023) No 1, Rev A, dated 08/28/09	None	26/01/2012	Active	10038180
10038186	TECH-TOOL PLASTICS, Inc.		FAA STC SH5797SW	AS350B, AS350B1, AS350B2 AS350B3, AS350BA, AS350D	Installation of Tech-Tool performed acrylic plastic windshield inaccordance with Tech-Tool Drawing List (Doc 3501-2023)No 1, Rev A,dated 08/28/09 (FAA STC SH5797SW)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Tech-Tool Drawing List (Doc 3501-2023) No 1, Rev A, dated 08/28/09	None	26/01/2012	Active	10038186
10038194	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR02808NY	429	Installation of wedge Windows with Sliders into L/H and R/HPassengerDoors in accordance with Aeronautical Accessories Inc. InstallationInstructions Report Number AA-09064, Revision A, 09. (FAA STC SR02808NY)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Aeronautical Accessories Inc. Installation Instructions Report NumberAA-09064, Revision Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) ICA Report Number AA-09065, Revision 2, dated March 2010	None	26/01/2012	Active	10038194

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038222	SECURAPLANE TECHNOLOGIES, Inc.	REV. 1	FAA SA01696LA	SEE APPROVED MODEL LIST	Installation of Hawker Part Number 9750W0370 or 9750W0370-8Series24Volt 43 Ah Sealed Lead Acid Battery.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Installation Instructions ref105-1126-01, Rev C as specified by MDL listed in the AML to this STC.Operation in accordance with Flight Manual Supplement as listed in theAML to this STC.Instructions for Continued Airworthiness defined in Document Reference290-0254-01, R...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	27/11/2014	Active	10038222
10038231	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR00707DE	429	Automatic Door Openers for Crew and Passenger Doors and Pilot andCo-Pilot Floor Protectors	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AA-09025 revision B dated 6 November 2009 - Drawing List for DoorOpeners, Floor Protectors and Paint Protector;AA-09045revision B dated 7 July 2010 - Installation Instructions, CrewFloor Protector Kit;AA-09070 revision B dated 30 October 2009 - Certification Plan forAutomatic Door Openers and CrewA...	None	30/01/2012	Active	10038231
10038232	AIR COMM CORPORATION LLC		FAA STC SR00692DE	429	Installation of Bleed Air Heater	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	429H-1 issue 1 dated 8 July 2011 - Flight Manual Supplementor later revisions of the above listed documents approved byEASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) DL-429H revision F dated 23June 2009 - Master Drawing List;429H201M-1 revision 1 datedA...	None	30/01/2012	Active	10038232
10038234	EMBRAER GPX Ltda. (PC 722)	REV. 1		EMB-145ER/EU/EP/MP/ LR/LU/MK EMB-145 EMB-135BJ/LR/ER	EASA Validation of ANAC STC 2010S10-18. Electronic Flight Bag (EFB) Installation.Description as per:ESCMSC002-Rev A, dated 17th January 2012.Master Documents List ESCCCD003-Rev B, dated 17th January 2012.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ESCMSC002-Rev A, dated 17th January 2012.Master Documents List ESCCCD003-Rev B, dated 17th January 2012.Flight Manual Supplement No.: H. 02-3489-0/ANAC/2010, dated 25th March2011.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/03/CF (or subseq...	None	01/02/2012	Active	10038234
10038238	ASTRONICS - LSI	REV. 1	FAA STC SA02387AK	2- F33A, F33C 2- A36, G36, A36TC, B36TC, 1- 58, 58A, G58, 95-B55, E55	Fabrication and Installation of Exterior LED Lighting Suiteinaccordance with FAA STC SA02387AK.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: asreferenced in FAA STC SA02387AK.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunch...	Fabrication and Installation of the LSI Exterior LED Lighting Suite inaccordance with Astronics Master Data List (MDL) Doc. No. 20 16 00,Revision R7, dated November 5, 2012;Installation Instructions, One Sky Aviation, LLC document number 32 1605, Rev. IR, dated July 10, 2011;Instructions for Continu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	30/01/2013	Active	10038238

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038250	AIRBUS HELICOPTERS CANADA LIMITED	REV. 1	TCCA SH94-29	AS 355 N, AS 355 NP AS 355 F1, AS 355 F2 AS 355 E, AS 355 F AS 350 B, AS 350 B1 AS 350 BA, AS 350 D AS 350 B2, AS 350 B3	Left-Han Litter Kit installed as per Master Drawing List No. MDL-99-001.Revision 1. Changed STCH reference and updated documentation referenceto modify compatibility tablein the MDL.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Drawing List No. MDL-99-001 issue I, Transport Canada approved on8 June 2020.Rotorcraft Flight Manual SupplementFMS-ECL-107 Rev. 7, Transport Canadaapproved on 8 June 2020.Instructions for continued airworthiness ICA-ECL-127 Rev. 6, TransportCanada accepted on 8 June 2020or later revisions o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/09/2020	Active	10038250
10038251	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST02890NY-D	A321-212, -213, -231, -232 A321-111, -112, -131, -211 A320-231/-232/-233 A320-211/-212/-214 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of Panasonic Global Communications Suite (GCS) antennaThis modification installs a large antenna on top ofthe fuselage, toallow the Panasonic GCS system providing passengers with TV, phone andinternet connectivity.The Revision 1 extended the STC applicability to Airbus A320.The Revisio...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC ST02890NY-D amended December 21, 2012Master Data List document, ref : 0164-07339-2268, Rev. O, dated August20, 2015Instructions for Continued Airworthiness document, ref : 0764-07343-2268, Revision I, dated August 19, 2015A319 Airplane Flight Manual Supplement, ref : 0664-07452-2268, datedNo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/09/2015	Active	10038251
10038252 (EASA.A.S.03559)	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	HAWKER 900 XP HAWKER 850 XP HAWKER 800 XP HAWKER 750	To introduce a new forward cabin door with associated placards.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 25.813f) Amendment 25-17The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels o...	Installed in accordance with Major Change SC0319A at Issue 2 dated 23Jan 2012;Hawker Beechcraft Limited Aircraft FlightManual Supplement 4 to AFM140-590039-0005 (Hawker 750), or Supplement 5 to AFM 140-590032-005(Hawker 800XP), or Supplement 2 to AFM 140-590035-0005 (Hawker 850XP),or Supplement 4 t...	None.	01/02/2012	Active	10038252
10038255	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			F177RG	Installation of a Garmin GNS 400 series system, a Garmin GA35 or GA 56GPS antenna, a Mid Continent MD41 annunciator and a Garmin GTX 330transponder.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS 2323.301, 23.307, 23.867, 23.1301, 23.1309, 23.1321, 23.1322, 23.1351,23.1357, 23.1365, 23.1381, 23.1431, 23.1519, 23.1529, 23.1541, 2...	SEAM Flight Manual Supplement No. 3623/11, revision 0 dated02/09/2011;SEAM Modification File No. 3623/11, revision 2 dated 13/01/2012;or later revisions of the above listed documents approved by EASA.	Installation of this design change must be performed by authorised SEAMtechnical personnel.The aircraft must be equipped with at least one radionavigation orradiocommunication mean not similar to the GNS 400 series unit.This installation is approved for use in BRNAV operations (withoutcoupling of GN...	01/02/2012	Active	10038255
10038266	AVINCIS AVIATION ITALIA S.P.A	REV. 3		CL-215-6B11 (CL415 VARIANT) CL-215-6B11 (CL-415 VARIANT)	Elementary Surveillance Mode S Diversity TranspondersUpgrade/ Replacement and Installation of new transponders with Elementary Surveillance and Diversity capabilities.Rev. 1: Name change from INAER Aviation Italia S.p.A. to Babcock MissionCritical Services Italia S.p.A. Divisione Ala FIssa.Rev. 2: Ch...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Drawing List Doc. No. MDL-34-59-0912-A Rev. 01 dated 19 January2012;- Aircraft Flight Manual Supplement Doc. No. FMS-34-59-0912-A Rev. 0dated 09 January 2012;- Instruction for Continued Airworthiness ICA-34-59-0912-A Rev. 0 dated09 January 2012;- Minimum equipment list MEL-34-59-0912-A Rev....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2023	Active	10038266

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038267	THALES AVIONICS Inc.	REV. 1	FAA STC NO. ST02411LA	777-200	In-Flight Entertainment (IFE) System Installation	IM.A.003The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the or...	FAA STC No. ST02411LA, dated 20 January 2012.Thales Avionics Index List, Drawing No. 254709, Revision "A", datedDecember 16, 2011, or later approved revision.The instructions for Continued Airworthiness is called out in itsassociated Master Drawing Lists (MDL) defined in the above referencedIndex Li...	Concurrent installation of the following STCs are required for theinstallation of this STC:1) Flight Structures, Inc. EASA STC No. 10015720, Business Class SeatInstallation.2) Northwest Aerospace Technologies, Inc. EASA STC No. 10038268 (EASAProject No. 0010011923), Aircraft Interior Reconfiguration...	03/02/2012	Active	10038267
10038268	NORTHWEST AEROSPACE TECHNOLOGIESI NC.		FAA STC NO. ST02412LA	777-200	First and Economy Class Cabin Interior - BA 777-200 Aircraft	IM.A.003The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the or...	FAA STC No. ST02412LA, dated 18 January 2012.Northwest Aerospace Technologies, Inc. (NAT) Master Drawing ListN0366-D10,Rev "C", dated December 13, 2011 or later approved revisions.Instructions for Continued Airworthiness Document No. N0366-D70, Rev"--", dated September 29, 2011 or later approved re...	Concurrent installation of the following STCs are required for theinstallation of this STC:1) Flight Structures, Inc. EASA STC 10015720, Business Class SeatInstallation.2) Thales Avionics, Inc. EASA STC No. 10038267 (EASA Project No. 0010011945), Passenger Cabin IFE System Installation, and3) Northwe...	02/02/2012	Active	10038268
10038270	APTOZ EHF.	REV. 1		B757-200 757-200	Installation of Satcom and Flight Tracking System.Rev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Icelandair CRA-757-2320-43, Revision A, 30/01/2012or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10038270
10038286	RAM AIRCRAFT, LP		FAA SA09469SC-D	CESSNA 414	Modification of Cessna 414 in acc. with FAA STC SA09469SC-D: Aircraftmodified in accordance with RAM Master Drawing No.1982, Revision K, FAAapproved September 23, 2009 and Installation of modified TCM enginemodel TSIO-520-NB in accordancewith FAA STC SE09261SC-D or SE09104SC-D.	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.	-RAM AFMS 1087, Revision C, dated 25/09/1995, FAA approved September 08,2008- Installation Instruction: Master Drawing 1982, Rev. K, FAA approvedSeptember 23, 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions o...	This approval is limited to Hartzell propellers:PHC-C3YF-2UF/FC7663D(B)-2Q	03/02/2012	Active	10038286
10038287	LEARJET Inc.	REV. 8	FAA STC ST00299BO	BD-700-1A10, BD-700-1A11	Installation of a Honeywell DU-875 or DU-875AF Liquid Crystal Display(LCD) based Display System including two Cursor Control Devices (CCDs)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00299BO.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	1. Learjet, Inc. Master Document List (MDL), Document NumberBAS67040028, Revision Y, FAA approved on 15 September 2020,or later FAAapproved revision. 2. Applicable LCDs for each configurations are identified in MDLDocument Number BAS67040028, Revision Y, FAA approved on 15 September2020, or later FA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.MFD Video functionality (fixed video image) has n...	16/10/2020	Active	10038287

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038288	BOMBARDIER AEROSPACE		TCCA STC SA11-88	CL-600-2B16	Electronic Flight Bag Class II (PED) (Provisions)	IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approva...	-TCCA STC No. SA11-88 Issue 1, dated 25 October 2011.-ACS-NAI Ltd. Modification Data Summary Number H220000 Revision N/C,dated 25 October 2011 or later approved revision.-ACS-NAI Ltd. Airplane Flight Manual Supplement H220090 Revision N/C orlater approved revision.-Bombardier Airworthiness Limitatio...	None	03/02/2012	Active	10038288
10038291	EMBRAER ENGINEERING & TECHNOLOGYCENTER USA, INC.	REV. 1	FAA STC ST00011IB	EMB-135BJ	Installation of a cabinet and a 17" video monitor on EMB-135BJ aircraft"Note:This STC is revised at Rev. 1 in order torecord the transfer of theoriginal ANAC STC No. 2011S09-02 to a United States based DesignApproval Holder."	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Master Document List N° ESCCCD015, Rev. G, dated 4 December 2018-Airplane Flight Manual Supplement doc. N° H. 02-3679-0/ANAC/2011 Rev. Bdated 20 December 2018-Instruction for Continued Airworthiness (ICA), document numberESCMTD009 Rev. B, dated 4 December 2018-FAA STC No. ST00011IB, reissued on 4 No...	None	05/01/2021	Active	10038291
10038292	SOFINARE SOCIEDADE DEFINANCIAMENTOS E REPRESENTACOES SA			TR182 R182	Installation of integrated Flight System Garmin G-500 and DoubleNav/Com/GPS systems GNS-430W.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23, incl. Amdt. 2 (Corrigendum)	AFMS (GNS-430W): SOFINARE 21J. 081.0821.016a, Initial IssueAFMS (G500): SOFINARE 21J. 081.0821.016b, Initial Issueor later revisions of the above listed documents approved by EASA.Continued Airworthiness Instructions Sofinare 21J. 081.0821.010.00, EASAaccepted 02/02/2012Installation Instructions iaw. D...	None.	03/02/2012	Active	10038292
10038293	PROTOPLANE SPECIAL MISSION AIRCRAFT			BN-2	BEZU installation on a BN-2 rev2 du 27/01/2012.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	None.	None.	03/02/2012	Active	10038293
10038294	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A310-300	Amiri Flight A310-300 Cabin RefurbishmentBy refurbish the existing Cabin by:- Removal of the existing seats and installation of new seats in theFirst, Business and Economy class.-Replace the existing IFE system- Installation of a new VCC,class dividers, dog house and décor panels- Installation of-...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalSCs or ESFs: Voluntary compliance for FAR 25.853(b) to FAR 25 Amdt. 59Derogation to latest amendment (Part 21A. 101):Classified as major no...	- Master Document List, Doc. No. S.OSMV.000003-MDL, Rev. 00- AFMS, Doc. No. S.OSMV.000003-AFMS, Rev. 00- ICA, Doc. No. S.OSMV.000003-ICA, Rev. 00or later revisions of the above listed documents approved by EASA	None	20/04/2021	Active	10038294
10038296	AVIONES, PIEZAS Y ACCESORIOS, S.L.	REV. 1	DGAC-E 138	B. 206B, 206L A. AB206 B	Transfer EASA STC 10038296 - Transfer from INAER MAINTENANCE S.A.U. toAVIONES, PIEZAS Y ACCESORIOSPower lines cleaning system with high pressure water with form "DGAC-ECertificateData Sheet No. 138"SLAAP is composed by a reservoir tank, a high pressure power system, acontrollable lance to eject thes...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement (Bell 206-B series & AgustaWestland AB206-Bseries) INAER.M12/040/25-FMS-1 R3;Flight Manual Supplement (Bell 260L-3 & L-4) INAER.M12/040/25-FMS-2 R2;or later revisions of the above listed documents approved by EASA.Instructions for Continued Airworthiness (Bell 206-B series &...	None	06/05/2013	Active	10038296

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038305	BELL TEXTRON, Inc.		FAA STC SR09534RC-D	BELL 429	Installation of Cargo Mirror	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-AA-09030 revision Original dated 8 April 2010 - RotorcraftFlightManual Supplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)- AA-09029 revision B dated 14 May 2010 - Instructions for Contin...	None	06/02/2012	Active	10038305
10038317	AIRBORNE TECHNOLOGIES GmbH			P.68TC "OBSERVER" P.68 "OBSERVER 2" P.68 "OBSERVER"	Electric Camera Lift installation/ Installation of an electric camera lift, an operator console and acamera lift controlpanel.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	-Change Dossier "Electrical Camera Lift" Doc. No. STC-AT-038, Rev. 1-Installation instructions Doc. No. 038-II-STC-AT, Rev. 0-Flight Manual Supplement AFM-STC-AT-038, Rev. 1-Maintenance Manual Supplement AMM-STC-AT-038, Rev. 1or later revisions of the above listed documents approved by EASA	Airborne Technologies STC-AT-036 must be installed prior orconcurrentwith this modification	06/02/2012	Active	10038317
10038318	airplus engineering GmbH	REV. 1		500, 550, 560, 560XL, S550	Installation of Garmin Mode A/C/S Transponder GTX 330D withadditionaldiversity antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Document List: MD - 1136 - 000000 rev 4.- Flight Manual Supplement: PO - 1136 - 34000000 rev 3- Maintenance Manual Supplement: MM - 1136 - 000000 rev 2- Weight & Balance:CA - 1136 - 000002 rev 1- Aircraft Model List: ML - 1136-000000 rev 6or later revisions of the above listed document(s)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/02/2021	Active	10038318
10038324	AIRBORNE TECHNOLOGIES GmbH			P2006T	Hatch Cover.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installed in accordance with Supplemental Type Certificate STC-AT-037,Rev. 2Maintained in accordance with AMM Supplement AMM-STC-AT-037, Rev. 2or later revisions of the above listed documents approved by EASA.	STC-AT-003 must be installed prior this modification.	07/02/2012	Active	10038324
10038328	S-TEC CORPORATION		FAA STC SA8392SW-D	PA-32R-301, PA-32R-301T PA-32-301, PA-32-301T	Installation of S-TEC system 55/55X Two Axis Automatic Flight GuidanceSystems, Model ST-534 (14V - System).	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved S-TEC Bulletin No.634, Revision 4, dated 16-Mar-2011, orlater FAA approved revision.FAA approved S-TEC Master Drawing List No. 92683, Revision D, dated16-Mar-2011, orlater FAA approved revision.FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 8...	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s)	07/02/2012	Active	10038328
10038339	AVIONICS GROUP INC.		FAA STC ST03559AT	767-200, -300, -300F, -400ER	Installation of Honeywell (TRA-67A) or Collins (TPR901) Mode S EnhancedSurveillance System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificateCertification Basis as per the TCDS and CS 25 Amendment 5 for EWISrequirementsThe requirements for environmental protection and the associatedcertif...	Avionics Group MDL, AG-34-1223.MDL, Revision B, 12/03/2008AFMS, AG-34-1233.AFM, Revision IR, 26/03/2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisionsofthis decision)	None	08/02/2012	Active	10038339

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038356	AIRCRAFT CABIN MAINTENANCE GmbH			A318, A319, A320, A321	Installation of refurbished Passenger Seat Belt P/N EPA20511-2-01-33 on16g seats	CS-25The Certification Basis for the original product remains applicable tothis certificate/ approval	Refer to Master Document List E/O No. 62-146169 Rev. 0 (16.12.2011).or later revisions of the above listed documents approved by EASA	As per Service Bulletin No. 62-146169 SEB 06 00, latest revision.	08/02/2012	Active	10038356
10038359 (EASA.IM.A.S.02019)	TELEDYNE CONTROLS, LLC		FAA STC ST1030SO	125-700A, 125-800A 125-400A, 125-600A	Replacement of existing batteries with Teledyne Gill G-639E(BB639/TE)Series Lead Acid Type Batteries.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Drawing No 0100-57, no revision, andDrawing No 3702. Drawing Index, no revision and InstallationInstructions dated November 21, 1978, Drawing Control Sheet 3700-82,dated May 8, 1985.Operation in accordance with FAA Approved Airplane Flight ManualSupplement dated Septe...	None	08/02/2012	Active	10038359
10038364	MAX-VIZ Inc.	REV. 2	FAA STC SA02372AK	C90GT/ C90GTI B300/ B300C B200GT/ B200CGT B200/ B200C/ B200CT/ B200T	Installation of the Max-Viz® Enhanced Vision System (EVS) Model-1500 onBeechcraft Corporation B200/B300/ C90 Series aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmentalprotection and the associated certificated noise and/ or emissionslevels of the original product are unchanged and remain applicable tothis certificate/ approval.	Installation in accordance with One Sky Aviation, LLC Master Data Listref. Doc No 20 11 00, Rev 6, dated September 05, 2012.Operation in accordance with Aircraft Flight Manual Supplement, One SkyAviation, LLC document number 32 11 04, Rev C, dated July 09, 2012.Instructions for Continued Airworthine...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/08/2016	Active	10038364
10038365	AERO TWIN, Inc.		FAA STC SA02080AK-D	208, 208B	Fabrication and Installation of Aero Twin, Inc. Exhaust Deflector P/NED8-100 in accordance with FAA STC SA02080AK-D	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Aero Twin, Inc. Master Data List ED8-100, dated July 15, 2002or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	09/02/2012	Active	10038365
10038368	IMAGIK INTERNATIONALF AA REPAIR STATION, CORP.		FAA STC NO. ST03400AT	BOEING 767-200/-300	Installation of IMAGIK LCD Entertainment Monitors.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST03400AT dated 25 February 2008;Avionics Support Group Master Data List Drawing 26012-MDL, Revision Bdated15 May 2007;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	09/02/2012	Active	10038368
10038393	JET AVIATION AG, BASEL			A319-133	VIP Cabin Interior CompletionSee Master Data List BCJ04151-001	JAR 25,, Amdt: 11 except as noted in TCDS EASA.A.064.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI A-4301-006 EASA STCCertification BasisSCs or ESFs:CRI D-4301-006 Installation o...	Airplane Flight Manual Supplement BCJ04151-201-01 Rev. BInstructions for Continued Airworthiness BCJ04151-150-01 IREWISInstructions for Continued Airworthiness BCJ04151-150-02 Rev. Aor later revisions of the above listed documents approved by EASA.	Approval valid only for MSN 4151.The aircraft is certified for private use only, not to be operated forcommercial air transport.The aircraft is a No Smoking aircraft.For other Limitations refer to Airplane Flight Manual SupplementBCJ04151-201-01 Rev. B or later revision approved by EASA.	15/02/2012	Active	10038393

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038425	S-TEC CORPORATION		FAA STC SA09307AC-D	401/401A/401B/402A/ 402B/402C	Installation of S-TEC system 20/30 single and two axis Automatic FlightGuidance Systems. Installation Model ST-743 (28V-System) according tobulletin N. 843.	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved S-TEC Bulletin No.843, dated 11-Oct-1997, or later FAAapproved revision.FAA approved S-TEC Master Drawing List No. 921046 dated 11-Oct-1997, orlater FAA approved revision.FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891590, dated 14-Nov-1997...	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s)	15/02/2012	Active	10038425
10038427	ROEDER PRAEZISION GMBH	REV. 2		PA-46-500TP, PA-46R350T PA-46-310P, PA-46-350P,	Installation of HID Xenon LDG/TAXI and LED NAV Light	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA STC 10038427 from NAYAK Aircraft Service GmbH based on:-NAYAK PA46-NY-09199-MDL-to be operated in accordance with NAYAK AFMS PA46-NY-09199-08-to be maintained in accordance with NAYAK MM-P PA46-NY-09199-07or later revisions of the above listed documents approved by EASA.	Limitations as referred to in AFMSMust be maintained i.a.w.Original Piper MM, furthermore must bemaintained i.a.w. Maintenance Instructions in the aforementioned RepairInstructions or later approved revisions.Prior to installation of thisdesign change it must be determined thatthe interrelationshi...	02/02/2018	Active	10038427
10038431	B/E AEROSPACE, Inc.	REV. 2	FAA STC ST03345AT	737-300/-400/-500	Validation of FAA STC No. ST03345AT issued 27 October 2006.Installationof Elementary Surveillance System / Enhanced Surveillance System(ELS/ EHS) in the Boeing 737-300/-400/-500 series aircraft. Installationof EHS capable Mode S transponders and ELS capable ATC/TCAS/Flight IDcontrol panel.Revision 2...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA Certification Review Item CRI H-1 "Instruction for ContinuedAirworthiness on EWIS" issue 3 dated 08 December 2011, SpecialCondition....	Airplane Flight Manual Supplement Doc. No. 2-54717-901, Rev. IR, dated30 April 2008.Master Drawing List Doc. 2-38842-001 for installation of ELS/EHS, Rev. Ldated 11 June 2010.Approved Model List Doc. 2-38842-002 for installation of ELS/EHS, Rev. Bdated 30 April 2008.Instruction for Continued Airwort...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10038431
10038432	HONEYWELL INTERNATIONAL INC.	REV. 1	FAA STC SR09583RC	EC135 P1/P2/P2+/T1/T2/ T2+	Installation of the Sky Connect Forte Iridium Satellite Phone and /orautomated reporting system (FAA STC SR09583RC)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement RFMS-2009-300 Rev A, dated 1/17/2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agree...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/08/2015	Active	10038432
10038436	ARMSTRONG AEROSPACE Inc.	REV. 2	FAA STC ST02947CH	737-800	Validation of FAA STC ST02947CH:Installation and activationof a Panasonic Global Communications Suite(GCS) system in accordance with Armstrong Aerospace Master Data ListDC104-9043-00, Revision M, dated 17 December 2012.Revision 1 of this STC has been issued in order to add the installationand activ...	CS-25 at amendment 2, except:- JAR 25.571 (CRI A11-05) as per TCDS<(>,<)>- CRI H-01 EWIS at issue 3 dated 17 February 2012<(>,<)>- CRI WLAN at issue 3 dated 23 February 2012,- GSMCRI F-01 at issue 3 dated 03 January 2012<(>,<)>- Database CRI F-04 at issue 3 dated 03 January 2012<(>,<)>The certifica...	Master Data List, Reference DC104-9043-00, Revision M, dated 17 December2012.Instructions for Continued Airworthiness Supplement DC113-9043-00,Revision E, 23 July 2012Weight and Balance supplement DC304-9043-00, Revision C, dated 16 May2012Airplane Flight Manual Supplement DC303-9043-00, Revision A,...	1) Modification in accordance with this STC requires prior or concurrentmodifications in accordance with Armstrong Aerospace Wireless andCellular technologies "provisions" (EASA STC 10042528) and"Certification of compatibility with Cellular and Wireless DataTechnologies" STCs (EASA STC 10042919). 2S...	21/01/2013	Active	10038436

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038450	MITSUBISHI HEAVY INDUSTRIES AMERICAINC.	REV. 1	FAA STC SA01594SE	3- MU-2B-36, -36A, -40, -60 3- MU-2B-25, -26, -26A, -35 2- MU-2B-30, -35, -36 1- MU-2B-10, 15, -20, -25, -26	Fabrication of Stretched Acrylic Windows for Mitsubishi MU-2B seriesairplanes.Revision 1 installs a stretched acrylic window on the MU-2B seriesaircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Drawing APD-03101, Rev A, dated 19 May 2015 or later FAAapprovedrevision.2. Drawing MU2-11001, Rev IR, dated 28 December 2005, or later FAAapproved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/04/2020	Active	10038450
10038454	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BN-2	Installation of Garmin GNS 400 series system, GA 35 GPS antenna, GMX 200multifunction display, GMA 347 audio box, SL30 NAV/COM system, GTX 330transponder, Mld Continent MD 41 annunciator, Collins ALT 50radioaltimeter and Indigo One Tracking system, according to SEAM STCfile No. 3622/11.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:23.301, 23.303, 23.305, 23.307, 23.337, 23.341, 23.365, 23.561, 23.625,23.1301, 23.1309, 23.1321, 23.1322, 23.1329(h), 23.1351, 23.1353,2...	Flight Manual Supplement "GNS 400 SERIES-B-RNAV on BN2T" ref.SEAM-AFM-GNS, Revision 2 dated 26/07/2011;STC Data List ref. SEAM-SDL-BN2T, Revision 3 dated 27/07/2011;or later revisions of the above listed documents approved by EASA.	This design change must be installed by SEAM technical personnel.This installation as approved for use in BRNAV operations.Coupling of GNS system to autopilot is authorised only for CENTURY 2000autopilot.Installation of software updates must be approved.Installation of new VHF, VOR/LOC, Glide or Tra...	17/02/2012	Active	10038454
10038456	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		ATP	Installation of a Five Panel Universal EFI-890R EFIS For ATP Aircraftwith PW126 and PW126A EnginesRev. 1: Applicabilityextended to include both PW126 and PW126A.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):-CRI F-01 Protection from theEffects of HIRF<(>,<)> Issue 2 dated 13February 2012-CRI H-01 Instructions for Continued Airworthiness (ICA) on Electric...	-Scandinavian Avionics<(>,<)> Approved Aircraft Flight Manual Supplement<(>,<)> 2051192-AM A Issue 7 dated 14 August 2017-Scandinavian Avionics<(>,<)> Approved Aircraft Flight Manual Supplement<(>,<)> 2051192-AM B Issue 4 dated 14 August 2017-Scandinavian Avionics<(>,<)> Approved Aircraft Flight Man...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/08/2017	Active	10038456
10038463	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE		TCCA STC NO. O-LSA09-344/D	CL-600-2B19	Iridium Antenna Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. O-LSA09-344/D Issue 1 dated 19 November 2009;DECA Aviation Engineering Drawing No. 5002572, Revision A or laterapproved revisions;DECA Aviation Engineering Instructions for Continued AirworthinessICA09215, Revision1 or later approved revisions. Compliance withChapter 4 "Air...	Restricted to ASN 8092.	17/02/2012	Active	10038463
10038465	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Enhanced Mode "S" compliance upgrade applicable to DassaultAviationMF50 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Uni Air Enterprise Master Data List MDL-002-11 Revision 2, dated 09thFebruary 2012;Uni Air Enterprise Airplane Flight Manual Supplement (AFMS)UAE-AFMS-11-001 Revision IR, dated 09th December 2011;or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	05/01/2015	Active	10038465
10038488	LUFTHANSA TECHNIK AG			A340-311 / -312 / -313	A340-300 GPSSU ReplacementThis STC consists in replacing the current Global Positioning SystemSensor Unit (GPSSU) by a new standard able to transmit GPS qualityinformation.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:As per EASA TCDS: A. 015 Issue 20Elect to Comply to CS25 Amdt 8 for EWIS ICAThe requirements for environmental protection and the associa...	Supplemental Type Definition Document, ref STDD34-11/01M Issue 1, dated16 February 2012;or later revisions of the abovelisted documents approved by EASA.	None.	21/02/2012	Active	10038488

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038490	DASSAULT FALCON SERVICE	REV. 2		F900EX EASY	TCAS 2000 upgrade to TCAS change 7.1 on F900EX EASyMajor Change to EASA STC 10038490This Major Change consists in removing the former limitation (onlyVersion 1 (F900EX EASy Step 3+) was approved)	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	DFS Change Approval Sheet DFS9664-CAS Issue B dated 05.04.2012DFS Modification Sheet DFS9664, Issue B dated 05.03.2012DFS Master Document List No DFS-DE-17-F9-9664 Issue B dated 05.04.2012or later revisions of the above listed documents approved by EASA	As per DFS Change Approval Sheet DFS9664-CAS Issue B dated 05.04.2012	08/05/2012	Active	10038490
10038491	PROTOPLANE SPECIAL MISSION AIRCRAFT	REV. 1		AS355F2, AS355N, AS355NP AS355E, AS355F, AS355F1	Installation of video transmission equipment ref. PP-014.Rev 01.: New cabin rack U12 (P/N PP-10-A405) installation added.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List PP-014-MDL-01, issue 1, dated 02/04/2020.Rotorcraft Flight Manual Supplement PP-014-AFM-01, issue 1, dated02/04/2020.Instructions for Continued Airworthiness PP-014-ICA-00, issue 0, dated02/04/2020.or later revisions of the above listed document(s) approved/ acceptedunder the EASA sy...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/04/2020	Active	10038491
10038498	ALPINE AVIATION, L.L.C.		FAA STC SA00469NY	2- 33, 35, 36 1- G36	Installation of Main Landing Gear Auxiliary Landing Lights in accordancewith FAA STC SA00469NYInstallation of Main landing Fear Auxiliary Landing Lights in accordancewith Alpine Aviation, Inc. Installation Manual, Report No. 014, datedJune14, 1996.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Alpine Aviation, Inc. Installation Manual, Report No. 014, dated June14, 1996;FAA approved Alpoine Aviation, Inc. Airplane Flight Manual Supplementfor Beechcraft Model 33 series, 35 series, 36 series with Main LandingGear Auxiliary LandingLights, dated August 19, 1996;Alpine Aviation, Inc. Maintena...	None.	21/02/2012	Active	10038498
10038505	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02195SE	B747-400	Installation of a IMS RAVE In-flight Entertainment System into theeconomy class passenger seats of a Boeing 747-400 aircraft in accordancewith Northwest Aerospace Technologies Inc. Master Drawing ListN0374-D10, Rev. J dated December 27, 2011 or later approved revisions.Validation of FAA STC ST02195S...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Northwest Aerospace Technologies Inc. Master Drawing List N0374-D10,Rev. J dated December 27<(>,<)> 2011 and documents referenced in thisMDL;or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	22/02/2012	Active	10038505
10038512	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		CESSNA 425	Installation of 5-blade MTV-27-1-E-C-F-R (P)/CFR210-58d propellers.Cessna 425 aircraft and models modified by EASA STC EASA.IM.A.02944 (FAASA5786SW) to install PT6A-135 (A) engine(s).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:FAR 23.1529 Amendment 26This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to t...	Airplane Flight Manual Supplement E-2105, Revision 0, 16.01.2012Instructions for Continued Airworthiness E-2107, Revision 0, 16.01.2012Installation Instructions E-2106, Revision 0, 16.01.2012Master Operation Manual List E-2104, Revision 0,16.01.2012or later revisions of the above listed documents a...	None.	02/03/2012	Active	10038512

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038517	FIELD AVIATION EAST, LTD.	REV. 1	TCCA STC SA05-8	DHC-8-202	Maximum Gross Takeoff Weight Increase to 37.300 lbs (c/w MZFW Increaseand Ground Spoiler Options)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with FAEL Master Drawingand DataList designated DDL1124, Revision L.Flight Operations must be in accordance with FAEL Flight ManualSupplements designated FMS 20083, Revision C and FMS 20187, Revision A.Instructions for Continuing AirworthinessMaintenance must be p...	Structural Modifications in accordance with FAEL Drawing 110297 RevisionH are required as a pre-requisite to the implementation of the GrossWeight increase.Additional Placards in accordance with FAEL Drawing 710041 Revision Bare required as a pre-requisite to the implementation of the GrossWeight in...	06/08/2015	Active	10038517
10038518 (EASA.R.S.01416)	ING. MIROSLAV RUSINAK S.R.O.			BELL 427	Support unit for medical devices	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	07100103r initial release - Flight Manual Supplementor later revisions of the above listed documents approved by EASA07100101r - Compliance Checklist07100102r initial release - Maintenance Manual07100108r initial release - Mechanical Work Order (contains masterdocument list and Installation Instruct...	None	22/02/2012	Active	10038518
10038524	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03784AT-D	GV-SP	Installation of an Audio Video Distribution System	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC515128003, Revision C, dated June 23, 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	1. The installer must determine whether this design change Is compatiblewith previously approved modifications.2. If the holder agrees to permit another person to alter the product,the holder must give the other person written evidence of thatpermission.	23/02/2012	Active	10038524
10038533	FIELD AVIATION EAST, LTD.		TCCA STC O-LSA11-177/D	DHC-8-202	Cabin Drop Down Oxygen System Removal and Cabin Interior RefurbishmentTCCA STC O-LSA11-177/ D, Issue 1	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation must be in accordance with TCCA approved FieldAviationMaster Drawing and Data List 254700000, Revision A.Maintenance must be in accordance with TCCA accepted Field AviationMaintenance Manual Supplement 25473100, Revision IR.or later revisions of the above listed documents approved by E...	The modification is limited to Serial numbers 445, 446.	23/02/2012	Active	10038533
10038558	BRISTOW HELICOPTERS Ltd.	REV. 1	CAA UK RESPONSIBILITY	S-76C	Modification of Rockwell Collins TCAS-4000 TCAS II update to version 7.1software.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	S76 Flight Manual Supplement No 19 revision 1;S76 Flight Manual Supplement No 22 initial issue;or later revisions of the above listed documents approved by EASA.BHL/ S76.4552 initial issue dated 29 March 2012 - Certification Plan; andMOD/S76/34.5784 issue 4 dated 10 April 2012 - Modification Sheet.	Applicable only to the S76C with Turbomeca Arriel 2S2 engines.	17/07/2012	Active	10038558

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038566	MT-PROPELLER ENTWICKLUNG GmbH	REV. 6		SR22, SR22T	Installation of 4-blade MTV-14-D/195-30 ( ) on SR22/SR22TInstallation of 4-blade MTV-14-D/195-30( ) on SR22 with RPM Reduction to2500RPMRev. 6: Addition of SR22T to the applicability list	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows:Cert Basis for No...	MT-Propeller Master Documentation List No. E-2584To be maintained i.a.w. MT-Propeller ICA Doc. No. E-2125To be operatedin accordance with AFM-S Doc. No. E-2124 for the SR22T orE-2128 for the SR22 or E-4034 for SR22 with RPM reduction to 2500RPM.To be installed i.a.w. MT-Propeller Installation Instr...	According to limitation section of AFM-S	18/11/2024	Active	10038566
10038568	LUFTHANSA TECHNIK AG	REV. 2		777-200	Introduction of Tailwind 550 Antenna.With the revision 2 ofthis STC the previous life limit of 500 FlightCycles is removed.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document, Lufthansa Technik documentNo.STDD53-12/2 1M Issue 1, Revision 2, dated 10 January 2014- Aircraft Flight Manual Supplement, Lufthansa Technik document No.A-00-11/177-AFM Issue 2, Revision 0, dated 21 March 2012- Instructions for Continued Airworthiness, Lufthan...	This modification is limited to MSN 29953.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	06/05/2014	Active	10038568
10038569	SII DEUTSCHLAND GMBH	REV. 1		777-200	Rücker Aerospace Nr.: 102100040: Installation of CAIR (TM) system	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval-CRI H-1 ICA on EWIS	Master Document List MDL-217-00001-000A Iss. A dtd. 22.Feb 2012-ICA per AMM Supplement AMS-217-00001-000A Iss. A dtd. 16.Feb 2012or later revisions of the above listed documents approved by EASA	This modification is limited to MSN 29953.	23/11/2012	Active	10038569
10038573	MICRO AERODYNAMICS, INC.		FAA STC#SA01681 SE	3. PZL M20 03 "MEWA" 2. PA-34-220T (SENECA V) 1. PA-34-220T (SENECA IV) 1. PA-34-220T (SENECA III) 1. PA-34-200, PA-34-200T,	Installation of vortex generators on the wings, horizontal and verticaltail surfaces (all models), and an increase in maximum zero fuel weight(PA-34-200T and M20 03 only).	Design:Non-significant changeThe Certification Basis of theoriginal product remains applicable tothis change.Environmental Protection:The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation in accordance with FAA approved Micro AeroDynamics, Inc.Drawing Package MA2212, Revision A, dated 14-Aug-2006 and FAA approvedInstallation Manual MA2213, Revision A, dated 06-Oct-2006;Micro AeroDynamics POH/AFM Supplement No. MA2215, Revision IR, dated25-Oct-2006, for PA-34-200T and PZL...	If more than five vortex generators are damaged or missing,the aircraftis no longer airworthy.	27/02/2012	Active	10038573
10038574	SABENA TECHNICS BGC			A330-200, -300	A330 Tape Video Reproducer Unit Installation The change consist in areplacement of each MAS Video Tape Player (VTP) by new digital videoreproducer units manufactured by Goodrich installed in the aircraftexisting Video Contro Center.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalA330 EASA TCDS A. 004The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the ori...	Certification Plan 4311-01-A-2101-R02 dated 24th February 2012.Master Data List 4311-01-A-2103-R01 dated 27th February 2012.Instructions for Continued Airworthiness 4311-01-A-2211-R00 dated 17thFebruary 2012.Aircraft Configuration Index Document (ACID) 4311-01-A-2213.or later revisions of the above...	this change is limited to A330-200 and A330-300, providing that the VCCP/N RDAA902251 isinstalled, and still in the configuration approved by the aircraftmanufacturer (no other STCs modifying the VCC before this change).	27/02/2012	Active	10038574

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038597	BOMBARDIER AEROSPACE		TCCA STC NO. SA12-12 ISSUE 1	CL-600-2B16	Galley Modification for Microwave Overheat	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ app...	TCCA STC No. SA12-12 Issue 1 dated 23 January 2012.ACS-NAI Ltd Modification Data Summary Number H372000 Revision N/C dated23 January 2012 or later approved revision.Instructions for Continued Airworthiness, ref. to Bombardier documentBAS63058004 Revision N/C or later approved revision.or later revis...	As a prerequisite aircraft must be fitted with EASA STC No. 10016019,Installation of Complete Custom Aircraft Interior.	29/02/2012	Active	10038597
10038629	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA STC ST04251AT-D	GULFSTREAM GV-SP	Installation of an Executive Completion - Multiple STC	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Installation in accordance with Gulfstream Aerospace Corporation IndexList GC522048013, Revision A, dated 15th February 2012-Operation to be in accordance with Gulfstream Flight Manual SupplementGC52204M075 , Rev. A, dated 15th February 2012or later revisions of the above listed documents approved b...	This Executive Completion, Multiple STC, (FAA ref ST04251AT-D), does notapprove the entire airplane interior installation and has the followinglimitations as defined in document GC522043046, "Guidance for Follow-OnInstallation, Executive Completion Multiple STC":1. A complete airplane interior requi...	23/03/2012	Active	10038629
10038630	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	B777-200	Installation of new cabin interior as defined in H4ACP075	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-01 EWISTherequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalu...	H4 Aerospace Modification Summary and Declaration of Compliance No. MODH4A1439, Issue 1, dated 02 March 2012or later revisions of the above listed documents approved by EASA	None	10/07/2012	Active	10038630
10038646	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	MBB-BK 117 B-2	Installation of LTS101-850B-2 Engines into MBB-BK117 B-2 Helicopter	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List JN216 ADC17, Issue 2, Rev 2 dated 29/02/2012- ICA JN216 ADC54-29 (1), Issue 1, Rev 3 dated 05/12/2011-RFMS JN216 ADC 29 (1) Issue 1, Rev 6, dated 01/03/2012: Installationof LTS101-850B-2 Engines into MBB-BK117B-2.-RFMSJN216 ADC 29(2) Issue 1, Rev 6, dated 01/03/2012: Installati...	None	05/03/2012	Active	10038646
10038656	DART AEROSPACE USA, Inc.	REV. 2	FAA STC SR02138SE	AB139, AW139	Installation of Dart D139-799 Maintenance kitsNote: STC re-issued at Rev.2 for addition of the AB139 model	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dart Master Document List MDL-D139-799, Revision C, dated June 6, 2010;Dart Installation Instructions IIN-D139-799, Revision D, dated June 10,2011;Dart Instructions for Continued Airworthiness ICA-D139-799, Revision 3,dated May 5, 2011;or later revisions of the above listed documents approved by EAS...	None.	22/11/2017	Active	10038656

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038659	BOMBARDIER INC.	REV. 2	TCCA STC SA12-24	BD-700-1A10, BD-700-1A11	Installation of Class II Electronic Flight Bag (EFB) Systemfor Global6000 and / or Global 5000 aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-24 Issue 3, dated 15 August 2012;Bombardier Inc. Modification Data Summary Number RAZ-BM700-003 RevisionA, approved 02 March 2012;Bombardier AirplaneFlight Manual Supplement G-FM46054001 RevisionBasic;Instructions for Continued Airworthiness refer to Bombardier documen...	None.	08/11/2012	Active	10038659
10038661	FIELD AVIATION COMPANY Inc.		TCCA STC O-LSA11-232/D	DHC-8-103	Honeywell Mark VII EGPWS Annunciator Relocation and UpgradeTCCA STC O-LSA11-232/D, Issue 1	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation must be in accordance with TCCA approved FieldAviationCompany Inc. Master Drawing and Data List designated 25550000, Rev. IR.Flight operations must be conducted in accordance with FACI FlightManual Supplement designated FMS 25553000 Rev. IR.Instructions for Continuing Airworthiness:Mai...	This modification is limited to Serial number 310 with EASASTC No.MOT.21NE2.138 installed.	06/03/2012	Active	10038661
10038663	SABENA TECHNICS BGC	REV. 3		777-300, 777-300ER 777-200, 777-200LR	0411-01: Installation/activation of OnAir GSM/Internet system on B777.Configuration 1: Alna v2 GSM/ Internet (initial configuration)Configuration 2: Alna v3 GSM/Internet upgrade internetConfiguration 3: Retrofit to Alna v3.6 Internet only with GSMdeactivationRev.1: Limitations updatedRev.2: Configura...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:Applicable regulations at CS 25 Amendment 4 (for details refer toassociated Certification Plans: 0411-01-A-2101-R01 for0...	For configuration 1:- AFM Supplement 0411-01-A-2301-R01 dated 17. Jan 2012- Instructions for Continued Airworthiness 0411-01-A-2211-R00 dated 29Feb. 2012For configuration 2:- AFM Supplement 0411-01-A-2301-F02-R01 dated 18. Jul 2017- Instructions for Continued Airworthiness 0411-01-A-2211-F02-R01 dat...	Per AFM Supplement 0411-01-A-2301 for configuration 1.Per AFM Supplement 0411-01-A-2301-F02-R01 for configuration 2.PerAFM Supplement 0411-01-A-AFMS-F04-R00 for configuration 3.This modification is limited as stated below except similaritydemonstrated per document 0001-01-B-914 (Classification of M...	08/04/2025	Active	10038663
10038665	AVIATION PARTNERS, INC.	REV. 2	FAA STC ST02188SE	MF900, F900EX	F900 aircraft fitted with winglets per EASA STC 10038665Steep Approach Landing Approval	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): B-07 - Steep ApproachThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original prod...	FAA Certification Flight Test Plan ref. ATEC-12022 Rev A dated August 14,2012AFM referenced APF9-0601_Code_9001 Revision 1 April 15, 2013Master Drawing List Revision D, December 6, 2011or later revisions of the above listed documents approved by EASA	Applicable to all Dassault Aviation MF 900 and F900EX aircraft fittedwith EASA STC 10038665Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effe...	24/04/2013	Active	10038665
10038669	AVIDYNE CORPORATION		FAA STC SA00310BO	PA46-350P, PA-46R-350T	Autopilot Series / DFC 90 Autopilot P/N 700-00170-002 DFC100 AutopilotP/N 700-00170-003 as replacement for the S-Tec System 55X Autopilot P/N1192-()-() in accordance with Avidyne Corporation Master Document ListAVDFC-077	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Note: The changehas been classified and confirmed as "Basic" STC(non-significant). The changes to the STCB are on a "elect to comply"bas...	Operation must be in accordance with Avidyne Corporation Aircraft FlightManual Supplement (AFMS) as follows:For DFC90: Document 600-00285-000, Rev 00, FAA approved on November 17,2011For DFC100: Document 600-00288-000, FAA approved on November 17, 2011or later revisions of the above listed documents...	Aircraft must be configured with an existing S-TEC 55X (or 55SR)Autopilot and with an existing Avidyne Flight Display System as followsin order to accomplish this STC:For DFC90: Avidyne Primary Flight Display, p/n 700-00006-( ), loadedwithRelease 8.0.4 software (or later approved release) withmodif...	06/03/2012	Active	10038669

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038671	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 3		EC 225 LP	Installation of the Helicom V2 NUM embedded Equipment.Revision 1: Add the possibility of installing Helicom V2+ NUM with Cargorelease information (cyclic stick and collective lever).Revision 2: Adding Air Intakes data acquisition and correcting typo onICA and RFMS references.Revision 3: STC holder n...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- N9-EC225 HV2 HV2+ NUM-RFMS-E-A-03 Rev.00 dated 20 January2016 – Rotorcraft Flight Manual Supplement- N8-EC225 HV2 HV2+ NUM-E-A-03 Rev.01 dated 20 January 2016 –Instructions for Continued airworthiness- N11- EC225 HV2 HV2+ NUM E- A-02 dated 29/11/2017 – List of DocumentsOr later revisions of the ab...	The approval holder shall fulfill the obligations of Part 21, Paragraph21A.109.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	27/02/2020	Active	10038671
10038677	DSA A.S.	REV. 1		F172P F172N F172M	Avionics upgrade - installation of:GMA 340 (audio), SL 40 (VHF COMM), SL 30 (VHF NAV/COMM),MD 200-306 (CDI indicator), GTX 328 (Mode S XPNDR), CI 102 (MKRantenna), Kannad 406 AF Compact (ELT), AV 200 (ELT antenna), CI 105(XPNDR antenna).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Cessna F172 M, N, P Flight Manual Supplement No: S1 LDA 02/11/ C172GMA 340 Audio Panel, issued: May 30, 2011- Cessna F172 M, N, P Flight Manual Supplement No: S2 LDA 02/11/C172SL30 VHF COMM Transceiver/ NAV Receiver, issued: May 30, 2011- Cessna F172 M, N, P Flight Manual Supplement No: S3 LDA 02/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/05/2020	Active	10038677
10038678	SABENA TECHNICS BGC			B777-200	0527-01: eXPhone System Installation on B777-200 aircraft.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:- CS 25 Amdt 4- CRI F01 GSM System (ref AEC STC 0333-01)- CRI F02 Hardware (ref AEC STC 0333-01)- CRI F03 Software (ref AEC STC 0333-01)-...	MDL 0527-01-2103-R00 dtd. 6.Mar 2012-AFM Supplement 0527-01-A-2301-R00 dtd. 17.Feb 2012-Instructions for Continued Airworthiness 0527-01-A-2211-R00 dtd. 10.Nov2011or later revisions of the above listed documents approved by EASA.	Per AFM Supplement 0527-01-A-2301.This modification is limited to Boeing 777-200 MSN29953, exceptsimilarity demonstrated per Document 0001-01-B-0914 (Classification ofModificationChange Procedure for GSM connectivity System).	07/03/2012	Active	10038678
10038683	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	A321	Installation of Galley 2A Part No. 321BMI2AGA00 and Galley 3A Part No321BMI3AGA00 into an A321-200 to be operated by BMI.	CS 25 Amendment 11The Certification Basis for the original product remains applicable tothis certificate/ approval.	Change Record HEN 1207, Issue 1	None	07/03/2012	Active	10038683
10038702	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			DR 400/180	STC 3725/11 rev. 0 dated 04/01/2012 - Amélioration équipements radionavB-RNAV	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Supplément Manuel de Vol SMV 3725-11 rev. 0 du 04/01/2012orlater revisions of the above listed documents approved by EASA	S/N 2105	09/03/2012	Active	10038702
10038717 (EASA.A.S.00327)	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		B1900D	Installation of Two Transponders mode S RCZ-852	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23 Amdt 23-62The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certi...	File ref.: BCA 60 Rev 1 dated 11/01/2012Installation ManualRCZ-852 No. A 15-3851-001	BEECH 1900 D S/N UE 70	09/03/2012	Active	10038717
10038718	ALTITUDE AEROSPACE INC.		TCCA STC SA11-43	DHC-8-201/-202	Installation of an Oven and a Coffee Brewer in the GalleyTCCA STC SA11-43, Issue 1	FAR 25-25 as per EASA.IM.A. 191, Issue 5 (incl. SC H-01 ICA on EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areu...	Installation must be in accordance with Altitude Aerospace Inc.Modification Summary MS250044, Revision E, dated 25 April 2011.Maintenance must be in accordance with Altitude Aerospace Inc.Instructions for Continued Airworthiness ICA 250044, Rev. A, dated 17February 2010.or later revisions of the abo...	Galley PN H82530009 only	09/03/2012	Active	10038718

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038720	MT-PROPELLER ENTWICKLUNG GmbH	REV. 2	LBA STC SA 1063	T210N, T210R T210M, T210N, T210R P210N, P210R, T210M P210N, P210R	Installation of MTV-14-D/195-30( ) Propeller on Cessna 210 series.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31.This certificate/ approval involves a change with an impact on the noisedatab...	For MTV-14-D/195-30bTo be operated in accordance with MT-Propeller AFM-S Document No. E-4004Rev. 0According to MT-Propeller Master Documentation List No. E-2018 Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-2025 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	04/10/2022	Active	10038720
10038721	JET AVIATION AG	REV. 3		EMB-135BJ	VIP & Medevac Cabin ConfigurationRevision of EASA STC 10038721 Revision 2 to remove the limitation on theuse of medicalOxygen Cylinders	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI-D-4126-001 on Medical EvacuationCRI-D-4118-001 Installation of MedicalStretcher in CabinThe requirements for environmental protection and the asso...	-Master Data List JBSL-M-00826MDL-01 Issue 3 dtd. 10.08.2017-AFM Supplements JBSL-M-00826AFM-10 Issue 4 dtd. 09.08.2017andJBSL-M-00826AFM-20 Issue 4 dtd. 09.08.2017-Instructions for Continued Airworthiness JBSL-M-00826ICA-10 Issue 1dtd. 14.06.2017 and JBSL-M-00826ICA-20 Issue 1 dtd. 15.06.2017or la...	Per AFM Supplements JBSL-M-00826AFM-10 and JBSL-M-00826AFM-20.	11/08/2017	Active	10038721
10038724	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03686AT-D	GV-SP	Installation of an Airplane Cabin Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of an Airplane Interior in accordance with GulfstreamAerospace Corporation Index List GC520008657, Revision AC, dated March02, 2012, or later FAA approved revision.Operation in accordance with Airplane Flight Manual Supplement<(>,<)>GC51468M003, Revision B, dated September 20,2011, or l...	1. The approved EASA Configurations and the compatible EASAexportoption are defined in GC522040616, "EASA Validated Configuration Lists"<(>,<)> Revision "-", dated 03/02/12 or later approved revisions.2. Follow-On Installation Guide GC522040565, Revision NC, dated June 09,2009, or later FAA approve...	09/03/2012	Active	10038724
10038758	BLR AEROSPACE, L.L.C.	REV. 2	FAA STC SA02131SE	B200GT B200CGT	Installation of a BLR Aerospace Ultimate Performance Package (UPP)Revision 1 modifies the Installation Instructions andInstructions forContinued Airworthiness to add in the Rockwell Collins Pro-Line AvionicsEquipment Installations' new part numbers for Primary Displays AFD-3010and Multi-Function Di...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Certification basis defined on FAA STC SA02131SEThis certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.EAS...	Installation in accordance with Master Drawing List (MDL) DocumentBLR-KA250-005, Revision F, dated June 26, 2012. This installationrequires the adjustment of the Stall Warning System per BLR AerospaceInstallation Instructions document number BLR-KA250-004 Revision H,dated October 07, 2014.OperationA...	STC Compatibility:This use of the High Flotation landing Gear (HFG) limits the performanceof the aircraft to the performance information listed in the HFGsupplement:-Airplane Flight Manual Supplement Document AFMS-B250-3, Revision 2,dated July 24, 2013 (for aftermarket installations) or<(>,<)>Airpla...	22/05/2019	Active	10038758
10038761	TECH-TOOL PLASTICS, Inc.		FAA STC SR09046RC	AS 350 B, BA, B1, B2, B3, D	Installation of a reverse slide camera window	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Drawing List No. 3501-2035-100<(>,<)> Rev. A, dated 01/31/12or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	12/03/2012	Active	10038761
10038762	TECH-TOOL PLASTICS, Inc.		FAA STC SR09045RC	AS 355 E, F, F1, F2, N	Installation of a reverse slide camera window	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Drawing List No. 3501-2035-100<(>,<)> Rev. A, dated 01/31/12or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	12/03/2012	Active	10038762

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038764	BOMBARDIER INC.		TCCA STC C-LSA12-009/D	BD-700-1A11	Installation of Complete Custom Aircraft Interior - ASN 9401	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	-Transport Canada STC No. C-LSA12-009/D Issue 1, dated 29 February 2012.-Bombardier Inc. Modification Data Summary RAZ-BM700-9401-MDS Revision Aor later approved revision.-Bombardier Inc Airplane Flight Manual Supplement for the AircraftCompletion, G-FM25050001 Revision 1 or later approved revision....	Restricted to ASN 9401	12/03/2012	Active	10038764
10038766	SAFRAN CABIN INC.		FAA STC NO. ST02415LA	B767-300	Interior Installation and Modification to include Center Bin, CabinCeilings and Outboard Stowage Bins.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST02415LA dated 23 February 2012;C<(>&<)>D Zodiac Master Index List E751, Revision B dated 14 February2012 or later approved revisions;Instructions for Continued Airworthiness (ICA), C<(>&<)>D Zodiac ReportNo. CDRE751-78, Revision A dated 13 February 2012 or later approvedrevision;or lat...	None.	12/03/2012	Active	10038766
10038775	ACC COLUMBIA Jet Service GmbH	REV. 3	M6/91	PA-25-235, PA-25-260	Low Noise system PA-25-235-606500 Modification 2027423 applicable toPA-25-235 and PA-25-260Low Noise system PA-25-235-606560 Modification 2027423 Variant Bapplicable to PA-25-235 only	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: CS-36 Amdt 2Thec...	Low Noise system PA-25-235-606500 Modification 2027423 applicable toPA-25-235 and PA-25-260- According to Gomolzig Master Document List No. MDOCL 2027423_ 20120201and GomolzigInstallation Instructions Doc. No. Il_2027423_rev0_20120201, or laterRevisions- To be operated in accordance with Gomolzig AF...	According limitation section of AFM-S.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	15/12/2023	Active	10038775
10038783	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)	REV. 1		2. AS355F, AS355F1, AS355F2 2. AS355E, AS355N, AS355NP 1. AS350B, AS350BA, AS350BB 1. AS350B3 (SEE CONDITIONS) 1. AS350B1, AS350B2, AS350D	Front Lower Cowling Modification (Reference H-01-11-Capot)Separation of cowling in two halves reassembled by fasteners.Note: this STC is also applicable to front lower cowlings modified asper STC EASA.R.S. 01359.Revision 1 consists in a minor design change involving a modification tothe reassembly of...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	"Dossier de Modification - Front Lower Cowling ModificationonEurocopter Ecureuil" Ref. H-01-11-Capot_DM, Ed. 1, Rev. 1, dated June16th, 2014"Document d'Application" Ref. A-01-11-Capot_DA R1, Ed. 1, Rev. 1, datedJune 16th, 2014"Master Drawing List" Ref. A-01-11-Capot_MDrL, Ed. 1, Rev. 1, dated June...	AS350B3 change is also applicable to helicopters incorporatingmodifications OP-3369 and OP-4305Prior to installation ofthis design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadvers...	13/08/2014	Active	10038783
10038786	SCHERDEL ENGINEERING Ltd.			8. VENTUS BT, 9. CIRRUS 7. STANDARD CIRRUS 5. NIMBUS 4M, 6. VENTUS A 3. DISCUS BT, 4. DUO DISCUS T 1. DUO DISCUS, 2. DISCUS A	Cockpit Ventilation Modification	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-TN3 Cockpit Ventilation-Additional page to flight manual, section 9or later revisions of the above listed documents approved by EASA	None	14/03/2012	Active	10038786

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038800	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	KING AIR B300CER	To introduce increased maximum landing weight to 16,500lbs for the KingAir B300CER.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installed in accordance with Hawker Beechcraft Limited Major Change refSC0409A at issue 1;Operation in accordance with Hawker Beechcraft Limited Aircraft FlightManual Supplement 2, Issue 1 to AFM ref 130-590031-245;Maintained in accordancewith Instructions for Continued AirworthinessDocument ASC-R-...	None.	14/03/2012	Active	10038800
10038812	SABENA TECHNICS BGC	REV. 2		A330-341/-342/-343 A330-321/-322 /-323 A330-301/-302/-303	Panasonic eXPhone System activation on A330-300 with eXconnectThis STC installs a Panasonic eXphone System allowing, inconjunctionwith other devices, the use of cellphones duringflight.Revision 01: extends the STC applicability to a second aircraftconfigurationRevision 02: introduce a new configur...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI H-01 Issue 1 – Enhanced Airworthiness Programme for AeroplaneSystems – ICA on EWIS (as per TCDS EASA.A.004) The following paragraph(s) at a later a...	From Rev 1 :- Master Data List, Ref : 0496-01-A-2103-R01- Instruction for Continued Airworthiness, Ref : 0496-01-A-2211R03- Aircraft Flight Manual Supplement, Ref : 0496-01-A-2301-R03Rev 2 :In addition to Rev 1, the following documents are considered:- Master Data List, Ref : 0496-01-A-2103-R06- In...	Rev 1:The following modifications are prerequisites to the installation ofthis STC :- Delta Engineering STC ref : ODA-2224-01 – EASA Approval 10037166 Rev1, Panasonic Global Communication System – System Installation- Rev 2 :In addition toRev 1, the following GCS provisions are prerequisites totheA...	26/07/2016	Active	10038812
10038818	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV. 1	CAA UK RESPONSIBILITY	AS332 L2	Installation of Seat Rail Mounted Fuel Tank.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	BAC-761FMS-01 revision 1 dated 19 September 2011 - Flight ManualSupplementor later revisions of the above listed documents approved by EASA.BAC-761ACI01 issue 2 dated 19 September2011 - AccomplishmentInstructions;BAC-761CCL01 issue 4 dated 9 March 2012 - Compliance Check List;BAC-761ICA01 issue 1 d...	None.	20/03/2012	Active	10038818
10038822	VT MOBILE AEROSPACE ENGINEERING, Ind/b/a VT MAE	REV. 3	FAA ST03952AT	757-200	Modification of Passenger Aircraft to Cargo/ Passenger Configuration.Rev. 3: Modification of 8 Pallet/ 80 Passenger Cargo/ Passenger (Combi)to a fourteen pallet (14P) freighter configuration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): ESF against 14 CFRFAR 25.785(j), 25.813(b), 25.1447 (c)(1)" - CRI D-01 Issue 02 dated 04/02/2020 ".- The following paragraph(s) at a later...	- Project Specific Certification Plan, 336A/ CPN/011 Revision A- Master Drawing List ref. 336000010 Rev. B, dated 30 Sept. 2019- Aircraft Flight Manual Supplement ref. 757C2F-AFM-01, rev. 0 datedDecember 31, 2018- Instructions for Continuing Airworthiness ref. 757C2F-ICA-01 rev. Adated July 01, 2019o...	• This modification of Combi to a 14P Freighter configuration cannot beinstalled on Boeing 757-200 airplanes with any winglet STC installed norcan any winglet STC be installed on airplanes converted from Combi to14P configuration with thisSTC.• This approval should not be extended to other aircraft...	03/03/2020	Active	10038822
10038826	AIRBUS S.A.S.	REV. 1		A319-115	Airbus Corporate Jet Centre Modification CJ0950 - VIP Interior -"Metropole"Revision due to update of AFM-S and MPD-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A 4301-010 "ACJC Centre Conversion ProjectCertification Basis"The requirements forenvironmental protection and the associatedcertified noise a...	-,,Modification Approval Sheet, ref.: CJ0950, Issue 4, dated 24thOctober 2013-,,Airplane Flight Manual AFM Supplement, ref.: FM-S MOD CJ0950,Revision 01, dated 1st October 2013-,,Maintenance Planning Document MPD Supplement, ref.: MPD-S MOD CJ0950,dated 1st October 2013or later revisions of the abov...	This STC is limited to A319-115 MSN 4024 and MSN 4679.Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the pr...	25/10/2013	Active	10038826
10038839 (EASA.A.S.03919)	BUCHER LEICHTBAU AG	REV. 1		SEE EASA APPROVED MODEL LIST	Small person restraint system P/N 1120040 for use on 16G New GenerationStretcher P/N 1120020-XXX.	CS-25The Certification Basis for the original product remains applicable tothis certificate/ approval.	Refer to Master Document List No. E034-20-09;or later revisions of the above listed documents approved by EASA.	Small person restraint to be used only on stretcher P/N 1120020-XXX.Occupant limitations as per General Arrangement drawing 1120040 and UserManual E017-04-08.	20/03/2012	Active	10038839

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038857	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CL-600-2B16	Iridium Satcom Installation (ICG)	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	AIEC Corp Master Data List 5163-049 revision B dated 20/03/2012.AIEC Corp Engineering Order 5163-062 revision A dated 27/01/2012.AIEC Corp Instructions for Continued Airworthiness5163-085 revision Adated 27/01/2012.AIEC Corp AFM Supplement 5163-071 revision A dated 10/01/2012.or later revisions of...	None	20/03/2012	Active	10038857
10038859	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CL-600-2B16	Terrain Awareness and Warning System (TAWS) Upgrade to SCN 12.0 (UASC)	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	AIEC Corporation Master Data List No. 5173-049, Revision B,dated 19March 2012.AIEC Corporation Engineering Order No. 5173-062, Revision A, dated 16January 2012.AIEC Corporation Instructions for Continued Airworthiness No. 5173-085,Revision A, dated 16 January 2012.AIEC Corporation Aircraft Flight M...	None	20/03/2012	Active	10038859
10038860	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CL-600-2B16	CVR-120 replacement by CVR-120R (UASC)	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	AIEC Corporation Master Data List No AC5136-049, Revision B, dated 14March 2012.AIEC Corporation Engineering Order No. AC5136-062, Revision IR, dated 16June 2011.AIEC Corporation Instructions for Continued Airworthiness No.AC5136-085, Revision IR, dated 23 June 2011.AIEC Corporation Aircraft FlightR...	None	20/03/2012	Active	10038860
10038864	BOMBARDIER INC.		TCCA STC SA11-96	BD-700-1A10	Installation of a Frequency Converter Fuse	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. SA11-96 Issue 2, dated 17 January 2012.Altitude Aerospace Ltd. Modification Summary No. MS240064, Revision NC,dated 21 November 2011, or later approved revision.Altitude Aerospace Ltd. Instructions for Continued Airworthiness No.ICA240064, Revision NC, dated 17 November 2011...	None	20/03/2012	Active	10038864
10038866	VENTURA AEROSPACE, Inc.		FAA STC ST02115LA	B757-200	Installation of 9g Forward Cargo Barrier on the Main Deck	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate.For areas for areas of change the Certification Basis is CS25 Amendment2.Requirements at amendment 2 are:25.301, 25.305, 25.307, 25.561, 25.571, 25...	Master Data List 2686, revision F, 08/01/2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	To be installed on a/c converted to a Combination Passenger/ Freighterby ST Aerospace Inc, EASA STC 10038822.	20/03/2012	Active	10038866

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038867	CONCORDE BATTERY CORPORATION		FAA STC 03930AT	ATR 72-212 / -212A ATR 72-201 / -202 / -211 ATR 72-101 / -102 ATR 42-200 /-300 /-320 /-500	Installation of a Lead Acid BatteryThis STC installs a LeadAcid battery in replacement of the existingNickel-Cadmium battery.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-,,TCDS EASA.A.084-,,CS 25-1729 (Amdt 5)The requirements for environmental protection and the associatedcertificated noise and/ or emissi...	Master Drawing List (MDL), ref : 5-0372, Revision D, dated 16 September2011;Instruction for Continued Airworthiness, ref : 5-0445, Revision A, dated13 September 2011;Aircraft Flight Manual Supplement, ref : 5-0374, dated 20 June 2011;or later revisions of the above listed documents approved by EASAa...	None.	20/03/2012	Active	10038867
10038876	SABENA TECHNICS BGC			B777-200	0542-01: WiFi internet access system installation on B777-200	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-CRI F-01 / 10010868: -WiFi installation-CRI H-01: ICA on EWIS (ref AEC STC0555-01)	MDL 0542-01-2103-R00 dtd. 15.Mar 2012;- AFM Supplement 0542-01-A-2301-R00 dtd. 15.Mar 2012;- Instructions for ContinuedAirworthiness 0542-01-A-2211-R00 dtd. 15.Mar 2012;or later revisions of the above listed documents approved by EASA.	- per AFMS 0542-01-A-2301-Airworthiness Limitations per ICA Document 0542-01-A-2211 aremandatory- This modification islimited to Boeing 777-200 MSN29953, exceptsimilarity demonstrated per Document 0001-01-B-0914 (Classification ofModification Change Procedure for GSM connectivity System).	21/03/2012	Active	10038876
10038884	ANCRA INTERNATIONAL LLC		FAA STC ST02414LA	B757-200	Installation of Main Deck Cargo Loading System.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate:For areas of change the Certification Basis is CS25 amendment 10.Requirements at amendment 10 are:25.301, 25.303. 25.305, 25.307, 25.471, 25.561(*)...	Ancra International LLC Controlled Data List, DL85110, Revision B, 10/10/2011;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	To be installed on a/c converted to a Combination Passenger/ Freighterby ST Aerospace Inc, EASA STC 10038822.	21/03/2012	Active	10038884
10038891	MID-CANADA MOD CENTER		TCCA STC SA10-16	CL-600-2B19	CMC Electronics CMA-1100, Class II Electronic Flight Bag (EFB) SystemInstallation	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. SA10-16, Issue 1, dated 03 February 2010.Avionics Design Services Ltd Master Drawing List MDL09134, Revision N/C,dated 20 January 2010, or later approved revision.Avionics Design Services Ltd Flight Manual Supplement FMS09134-1,Revision N/C, approved 03 February 2010, or lat...	None	21/03/2012	Active	10038891
10038904	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	A109E	OBSERVER MOVING MAP SYSTEM INSTALLATIONThe system is manufactured by Skyforce and consists of a 5"Display/Control Head,a Processor Unit, and a Control Panel. Theequipment is CAA approved under miscellaneous approvals No. MIS00183.The installation is identified and defined in the document "SloaneHel...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Sloane Flight Manual Supplement No.6 issue 2or later revisions of the above listed documents approved by EASAModification definition and Maintenance requirements:"Sloane Modification document P017/109/MO"	The approval holder shall fulfill the obligations of Part 21, Paragraph 21A.118A.Prior to installation of this modification it must be determined thatthe interrelationship betweenthis modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the...	22/03/2012	Active	10038904
10038905	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	A109E	OXYGEN SYSTEM MODIFICATIONReplace (before) P/N 1270152-3 Oxygen cylinder with (now) "BritishOxygen Company" (BOC), Medical Gases AF size cylinder.The installation is identified and defined by the "Sloane HelicoptersLtd. Modification document No. P023/109/MO Issue 2".	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AgustaWestland supplied RFM Appendix 10 for the Emergency MedicalService (EMS) remains applicable.or later revisions ofthe above listed documents approved by EASAModification Definition and Maintenance requirements:"Sloane Modification document P023/109/MO"	None	22/03/2012	Active	10038905

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038906	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	A109E	Installation of Bendix/King RDR 2000 Weather Radar System(Bendix/King RDR 200 is CAA approved Ref. VC 01048).The installation consists of an antenna-receiver-transmitter (ART) unit,the Configuration Module, and the Control Panel. The (ART) radar unit isfitted inside the nose compartment. The instal...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Sloane Flight Manual Supplement No.7or later revisions of the above listed documents approved by EASAModification Définitions and Maintenance requirements:"Sloane Modification document P036/109/MO Issue A"	None	22/03/2012	Active	10038906
10038907	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	A109E	Trimble 2101 (IO) Approach Plus GPS (CAA approved Ref. VC01048)The installation consists of a Jeppesen data base slot card, aReceiver/Display Unit (RDU) interfaced to the EFIS via ARINC 429 andfitted on the top centre of the instrument panel. A GPS antenna ismounted on top of the tail fin. The instal...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Sloane Flight Manual Supplement No.8or later revisions of the above listed documents approved by EASAModification Definition and Maintenance requirements:"Sloane Modification document P037/109/MO Issue A"	A Placard is placed in clear view of the pilot and reads:GPS SYSTEM. USE ONLY DURING VFR OPERATIONAs specified in the Sloane Flight Manual Supplement No 8:1. The GPS systems to beused in VFR conditions only, for use as asupplemental navigation system.2. The GPS systems must not be used for approach...	22/03/2012	Active	10038907
10038909	BEECHCRAFT CORPORATION	REV. 2	FAA SA02130SE	KING AIR B200, B200C B200GT AND B200CGT	Transfer EASA STC 10038909 Rev. 1:Installation of BLR Hartzell Composite Propeller HC-E4N-3A/NC9208K.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:Certification basis defined on FAA STC SA02130SE.This certificate/ approval involves a change to the requirements forenvironmental protec...	Installation in accordance with Master Drawing List (MDL) DocumentBLR-KA250CP-002, Revision B, dated May 3, 2011, and InstallationInstructions Document BLR-KA250-006 Revision C, dated May 3, 2011;Operation in accordance with Airplane Flight Manual Supplement DocumentAFMS-B200CP-1, Revision IR, date...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	23/06/2014	Active	10038909
10038915	MECAER AVIATION GROUP S.p.A.			MBB-BK117 C-2	EC145 VIP MB Interiors Drawing No. 6EC10000X001-001	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Helicopter BK117 C-2 RFM Supplement 6EC1RFM-1-1 "EC145 VIP MB InteriorsPart Number 6EC10000X001-001" Rev. A;or later revisions of the above listed documents approved by EASA.Document 6EC10000N003 "EC145 VIP MB Style configuration Description"Revision B.Document 6EC1WNM-2-1 first issue Revision A "Ow...	None	23/03/2012	Active	10038915
10038920	AEROFDC WA LP	REV. 1	FAA STC SR02059SE	EC135 P2+, EC135 P2	Installation of an engine IBF system in accordance with theFDC/aerofilter Master Document List 1135-SERIES-MDL-5 and FDC/aerofilter Installation Instructions 1135-Series-INS-5.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For model EC135 P2+-,,Flight Manual Supplement 1135-RFMS-1,Rev. -For model EC135 P2-,,Flight Manual Supplement 1135-RFMS-1, Rev. Aor later revisions of the above listed documentsapproved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) For model EC135-...	None	27/08/2012	Active	10038920

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038928	THE NORDAM GROUP LLC	REV. 1	FAA STC ST09034SC	A319, A320, A321	Installation of C & X Band Fuselage Nose Radome Shell	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.SC-H01 Enhanced Airworthiness Programme for Aeroplane Systems - ICA onEWIS as included in TCDS EASA.A. 064...	-FAA STC ST09034SC-Master Data List, ref. doc. MDL-190-2460-2, Rev. E, dated 29th July2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	27/03/2012	Active	10038928
10038932	FIELD AVIATION COMPANY Inc.			DHC-8-301/-311/-314/315 DHC-8-102/-103/-106/-201 /-202	Auxiliary Wing Fuel Tank InstallationTCCA STC SA11-64, Issue 2	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. SC H-01)The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Special Condition CRI E-01 (Fuel Tank Safety)The requirements for environmental prote...	DHC-8-100 and 200 SeriesInstallation must be performed in accordance with FACI Master Drawingand Data List designated 25370000, Revision B.Flight Operations must be performed in accordance with FACI FlightManual Supplement FMS 20182, Revision C.Instructions for Continuing AirworthinessMaintenance mu...	None	23/03/2012	Active	10038932
10038943	AVIONIK STRAUBING ENTWICKLUNGS GmbH			SR22 SR20	Installation of PFD Aspen EFD1000 PRO.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23, Amendment2 (not required by 21A.101)The requirements for environmental protection and the associatedcertificated noise and/ or em...	Flight Manual Supplement ASR-2011-060-FMS-05-00 Rev. 00;or later revisions of the above listed documents approved by EASA.Instructions for Installation ASR-2011-060-IFI-10-00 Rev. 00.Instructions for Continued Airworthiness ASR-2011-060-ICA-11-00 Rev. 00.	None.	23/03/2012	Active	10038943
10038944	DELTA ENGINEERING CORPORATION		FAA STC ST02889NY-D	A330-223, -243 A330-201, -202, -203	Panasonic Global Communication System - System installationThis STC installs of Panasonic Global Communication System (GCS) andactivate the wireless portion.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Data List, ref : 0154-07345-2269, revision F, dated 09 February2012Aircraft Flight Manual Supplement, ref : 0654-07840-2269, dated 03October 2011 (Aircraft Configuration 1)Aircraft Flight Manual Supplement, ref : 0654-07841-2269, dated 04January 2012 (Aircraft Configuration 2 & 3)Instructi...	None	23/03/2012	Active	10038944
10038946	AEROTEC & CONCEPT			PA-23-250	Installation of Aspen EFD 1000 Pro electronic flight instrument system.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS23 amdt 1The certificated noise and/or emissions level of the original productare unchanged and remain applicable to this certificate /...	Aerotec Flight Manual Supplement No. AE11143SMV revision 2 dated07/03/2012.Aerotec Master Data List No.AE11143MDL revision 1 dated 22/03/2012.Aerotec ICA No. AE11143ICA revision 0dated 28/10/2011.or later revisions of the above listed documents approved by EASA.	Initial installation of this design change must be performed by AEROTECtechnical personnel.This installation is approved for BRNAV operations with coupling toS-TEC 55X autopilot.The modified airplane must be equipped with an attitude indicator, anairspeed indicator, an altitudeindicator, a magnetici...	30/03/2012	Active	10038946

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038951	AIR ALLIANCE GmbH			208, 208B	Installation of Honeywell KFD840 Primary Flight Display.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23 Amendment 02 (not required by 21A.101)The requirements for environmental protection and the associatedcertificated noise and/ or em...	EASA approved Aircraft Flight Manual Supplement (AFMS): 2011_026_C208_0506 Rev. 2;or later revisions of the above listeddocuments approved by EASA.Installation Manual (IM) with drawings: 2011_026_C208_0500 Rev. 0.Instructions for ContinuedAirworthiness (ICA) with componentconfiguration list 2011_02...	None.	26/03/2012	Active	10038951
10038956	HONEYWELL INTERNATIONAL INC.		FAA STC ST00806AT	B767-200/ -300	Installation of Aircraft Communications Addressing and Reporting System (ACARS) Mark II.	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	Master Drawing List 699-50097, revision M, 03/11/2005AFM Supplement 756.0181.801 Revision 'A, 17/11/2005or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	26/03/2012	Active	10038956
10038966	ROCKY MOUNTAIN AIRCRAFT			DHC-6-100/-200/-300	Installation of Dual or Single Garmin GTN 650 or GTN 750 inDHC-6 series100, 200, and 300 Twin Otter aircraft based on Engineering Data SummaryE102910 & E102911 in accordance withTransport Canada STC SA11-79, Issue1	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 23, Amdt. 23-49: 23.1309, 23.1311, 23.1322, 23.1365, 23.1529FAR 23, Amdt. 23-57: 23.1308(b)(c)The requirements for environmental prot...	RMA Flight Manual Supplement E102930, Revision 0Modification Instruction, Report E102910, Revision 0 (singleinstallation) Modification Instruction, Report E102911, Revision 0 (dualinstallation)or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/0...	None	27/03/2012	Active	10038966
10038972	SAAB AB	REV. 2		C-212-EE	TDM10-05 Rev. G titled "Cabin Layout", dated 2012-03-20."New Cabin Layout for Maritime Surveillance System in CASA C212".Installation and Mounting of Maritime Surveillance System and change ofCabin Layout to accommodate a maximum of 5 crewmembers and nopassengers in the Cabin. (Maximum number of pa...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Instructions for Continued Airworthiness TDM10-05-4-ICA Rev. B, dated2012-03-16<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	All equipment necessary for Maritime Surveillance Missions shall beinstalled or added with EASA DOA 21J.108 Minor Change ApprovalsPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or re...	12/09/2023	Active	10038972
10038985	AEROLITE AG	REV. 1		EC135 T2(CPDS), EC135 T2+ EC135 T1(CDS), EC135 T1(CPDS) EC135 P2(CPDS), EC135 P2+ EC135 P1(CDS), EC135 P1(CPDS)	EMS Equip. P/N 135-0004171-501The equipment includes up to two stretchers, two seats installed in theforward part of the cabin and stowage between the two seats.Rev. 1: Change of STC holder from "Aerolite Max Bucher AG" to "AeroliteAG".	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-Flight Manual Supplement: FMS-135-0004171-501-0 rev N/C dated 9.12.2011-Airworthiness Limitation: AWL-135-0004171-501-0 rev N/C dated 6.12.2011or later revisions of the above listed documents approved by EASA-Master Document List: MDL-11-027 rev N/C dated 22.03.2012	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously design change and/or repair will introduce no adverse effectupon the airworthiness of the product.	02/07/2019	Active	10038985
10038986	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 757-200	Installation of 21 Horse Stalls and a 10 Passenger Pallet.	The Certification Basis for the original product remains applicable tothis certificate/ approval.CRI H-01 EWISThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	BAC Ltd Master Data List No. BAC-820MDL05 Iss 1 dated 27 March 2012 orlater approved revision;or later revisions of theabove listed documents approved by EASA.	This EASA STC does not approve the installation of Horse Boxes.The following BAC Minor Modifications must be installed as aprerequisite for this approval:- Mod BAC-820MOD01- Mod BAC-820MOD02- Mod BAC-820MOD03- Mod BAC-820MOD04- Mod BAC-820MOD06	28/03/2012	Active	10038986

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10038996	AVIONITEC Ltd.	REV. 1		BEECH 35-C33A	Upgrade Garmin GNS430, repl. NAV/ COMRemoved:-Garmin GNS430 System-King KX 155 NAV/COM system-King KR 85 ADF SystemInstalled:-Dual Garmin GNS430W System-King KR 87 ADF System	FAR 23, Amendment 7The Certification Basis for the originalproduct and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this cer...	-Master Document List: Doc. No. 1098-017, Rev. 0-Airplane Flight Manual Supplement: Doc. No. 1098-011, Rev. 1-Instructions for Continued Airworthiness: Doc. No. 1098-015, Iss.24.11.2011or later revisions of the above listed documents approved by EASA	S/N CE-39, F-BNOI	05/04/2012	Active	10038996
10038999	FIELD AVIATION COMPANY Inc.		TCCA STC SA01-50	DHC-8-301/-311/-314/-315 DHC-8-201/-202 DHC-8-102/-103/-106	Installation of Variable Position Cabin Class DividerTCCA STC SA01-50, Issue 2	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	DHC-8-100/ 200 Series Aircraft:-Installation of the Variable Position Cabin Class Divider must be inaccordance with TCCA approved Field Aviation Company Inc. ModificationInstruction 173311, Rev. IR, dated 25 July 2011.-Maintenance of the Variable Position Cabin Class Divider must be inaccordance wit...	None	29/03/2012	Active	10038999
10039000	SCANDINAVIAN AVIONICS DESIGN ApS			2. B200, B200C, B300, B300C 1. 200, 200C, 300, 300LW	Installation of Universal UNS FMS System	The Certification Basis of the original product and the followingadditional / alternative airworthiness requirements are applicable tothis change.For the change CS-23, Amdt. 2, has been elected to comply with wherepossibleThe certificated noise and/ or emissions levels of the original productare unc...	EASA approved Engineering Order, Doc. No. 2073065-EO, Issue1, dated22-Mar-2012, or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2073065-AM A,Issue 1, dated 06-Mar-2012<(>,<)> or later approved issueApproved Instructions for Continued Airworthiness, Doc. No. 2073065-C...	This change is limited to the configuration of aircraft / equipment typeas listed under Chapter 4. in EASA approved Engineering Order, Doc. No. 2073065-EO, Issue 1, dated 22-Mar-2012, or later approved issue.	29/03/2012	Active	10039000
10039011	PARAVION TECHNOLOGY, INC.		FAA STC SR00743DE	BELL 429	Installation of structural provisions for a blade fold kit in accordancewith Paravion Technology Master Drawing List, Report No DL-429BF-100,Revision A, dated December 30, 2011.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Paravion Technology Master Drawing List, Report No DL-429BF-100, RevA, dated December 30, 2011;- ICA Paravion Technology Document No PR-429BF-120M, Rev 0, datedSeptember 06, 2011;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or sub...	None.	29/03/2012	Active	10039011
10039017	BERINGER AERO	REV. 4		101 P 101 D 101 BC, 101 D, 101 P 101 BC 101 B 101 AP 101 A, 101, 101 AP, 101 B 101 A 101	Installation of main wheels and brake system P/N : JA-01.Revision 1: Update with new wheel P/N : RF-002(B) with brake EA-006Ewhich supersedes the P/ N: JA-01.Revision 2: Update with new wheel P/N : RF-019 which supersedes thewheel P/N: RF-002(B).Revision 3: Update with new servicing instructions with...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification file CR-MOD001-STC-003 REV 0, dated 30 Nov 2023Installation and Instructions for Continued Airworthiness: ICA-STC-003REV 04 dated 30 Nov. 2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/02/2024	Active	10039017

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039031	B/E AEROSPACE, Inc. - FSI		FAA STC ST02164SE	A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303	A330-300 Cabin reconfiguration.This STC installs new economy class and business class seats togetherwith the replacement of the IFE system.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA TCDS A. 004Special Condition E-1014, Issue 4: HIC Compliance (InflatableRestraints)Special Condition E-130, Issue 2 rev1: Heat Releas...	Master Drawing List, Ref: B0FS014-D01, Revision E, dated 23March 2012.Instruction for Continued Airworthiness Supplement, Ref : B0FS014-D15,Revision A, dated 12 March 2012.Aircraft Flight Manual Supplement, Ref: TP10-014AFM, Revision 1, dated23 March 2012.or later revisions of the above listed docu...	None	30/03/2012	Active	10039031
10039039	PROTOPLANE SPECIAL MISSION AIRCRAFT	REV. 3		EC635 T3 EC635 T1, EC635 T2+ EC635 P2+, EC635 P3 EC135 T2+, EC135 T3 EC135 T1, EC135 T2 EC135 P2+, EC135 P3 EC135 P1, EC135 P2	Installation of a Max-Viz EVS 1500 vision enhancement systemInstallation of EVS 1500 system for Protoplane change project PP-015 asdefined in PP-015-MDL-01Rev.1: Possibility to add an external display when the helicopter is notfitted with a Thales system - replacement on the Vivisun pushbutton bysta...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement PP-015-AFM-03;Master Data List PP-015-MDL-05;Certification Plan PP-015-CP-05;Instruction for Continued Airworthiness PP-015-ICA-00;Wiring Diagrams PP-015-WD-03;Minor Change Definition PP-015-MCD4-00 Issue 0 dated 30 April 2018;ove listed document(s) approved/ accep...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/07/2018	Active	10039039
10039040	E4C AEROSPACE, Inc.	REV. 1	FAA STC ST02110LA	B767-300	Seat power, Seat Modifications and Seat track Installation	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	E4C master Data List 1063-000, revision D, 21/11/2007or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentrevisions ofthis decision)	None	15/05/2012	Active	10039040
10039042	DART AEROSPACE Ltd.	REV. 1		206 A/B/L/L1/L3/L4	Screw In Windshield Modification.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List MDL-D206-817, Rev A, Dated February 06, 2012;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision).- Approved Dart Aerospace Ltd. Installation Instructions IIN-D206-817,Rev B, da...	None.	30/04/2012	Active	10039042
10039051	AIRBUS S.A.S.			A321-200	Airbus Corporate Jet Centre Modification CJ1094 Issue 1 -Installation of Business Class Seating Area - "Gulf Air (Type C)"	In accordance with the EASA TCDS.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-,,CRI A 3301-001 "ACJC Centre Conversion Project Certification Basis".The requirements for environmenta...	-,,Modification Approval Sheet, ref.: CJ1094, Issue 1, dated 2nd April2012;-,,Airplane Flight Manual AFM Supplement, ref.: FM-S MOD CJ1094, dated1st April 2012;or later revisions of the above listed documents approved by EASA.	None.	03/04/2012	Active	10039051
10039055	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR02444NY	AW119 MKII A119	EASA Validation of FAA STC SR02444NY "Installation of the OffshoreConfiguration in accordance with Agusta Aerospace Master Data ListAAC-ENG-06-051 Rev.C"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchangedand remain applicable to this certificate/ approval.	Agusta Aerospace Master Data List AAC-ENG-06-051 Rev. C<(>,<)> datedMarch 27, 2008.Agusta Aerospace Instructions for Continued Airworthiness for theOffshore Configuration, Report No. AAC-ENG-06-057 Rev. A dated November14, 2007.Agusta Aerospace Rotorcraft Flight Manual Supplement No. AAC-ENG-06-056R...	None.	03/04/2012	Active	10039055

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039059	BLR AEROSPACE, L.L.C.	REV. 3	FAA STC SR01865SE	2. BELL 204B, BELL 205A1 1. BELL 212	Installation of Dual Tailboom Strakes and FastFin.Revision 1 adds Model 204B and changes the reference to LBA STC RC 1163to EASA STC 10040783.Revision 2 adds additional Bell 212 and 412 FMSs.Revision 3 updates the STC holder's address.	The Certification Basis (CB) for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.For components and areas affected by the change i.e. Fast Fin(SR01865SE) and DTBS (STC SR00798SE):In compliance with Commission Regu...	RFMS-212FF-1 Rev C dated 28 March 2012 - Flight Manual Supplement;RFMS-212FF-2 Rev IR dated 27 September 2012 - Flight Manual supplement;RFMS-212FF-3 Rev IR dated 27 September 2012 - Flight Manual SupplementModel 212 series with Cargo Hook212-706-103 equipped with BLR PatentedFastFin System;RFMS-21...	Day/Night VFR only, flight into known icing conditions prohibited.Must be installed in conjunction with FAA STC SR00798SE (EASA STC10040783).Prior to installation of this modification it must be determined thatthe interrelationship betweenthis modification and any other previouslyinstalled modifica...	22/05/2019	Active	10039059
10039078	RUAG AEROSPACE SERVICES GmbH			BELL 205A-1	Title: Load Attachment Device BRD01 on Bell 205A-1Description: The BRD01 is a cabin mounted device for attaching loads onBell helicopters. It is used with opened sliding doors andcan bemounted left- and righthand simultaneously.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-29, Amendment2 (voluntarily choosen)The requirements for environmental protection and the associatedcertificated noise and/ or emissio...	EASA approved Rotorcraft Flight Manual Supplement for Load AttachmentDevice BRD01 when installed in Bell Helicopters Model 205A-1 Series,Doc. No.: 349A-RFMS, Revision N/ CChapter 4- Airworthiness Limitations - of Maintenance Manual Supplementfor Load Attachment Device BRD01, Doc. No.: 349A-MMS, Revi...	None	04/04/2012	Active	10039078
10039107	MT-PROPELLER ENTWICKLUNG GmbH			TAIFUN 17 E & E II	Installation of a 2-blade MTV-1-A/L 165-06 propeller on poweredsailplane Taifun 17 E and Taifun 17 E II with Limbach L2400 EB1.AB orL2400 EF1/ DF1 engine	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/ or a change to the certificated noise a...	-Anhang zum Flughandbuch, Nr. E-2160-Airplane Flight ManualSupplement No. E-2159-Betriebs- und Einbauanweisung, MT-Propeller, Nr. E-118-Master Document List, Doc. No. E-2161or later revisions of the above listed documents approved by EASA	None	10/04/2012	Active	10039107
10039114	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 1	FAA STC SA619GL	2. B90, C90, E90, H90 (T-44A) 2. 65-A90-4 (RU-21E, RU-21H) 2. 65-A90-1 (JU-21A) 2. 65-90, 65-A90 1. C90A, C90GT, C90GTI	EASA Validation of FAA STC SA619GLInstallation of Parker Hannifin Main Wheel and Brake Conversion Kit PartNumbers 199-90 in accordance with Parker Hannifin Conversion KitInstallation Manual IM 199-90, Revision J, dated January 7, 2009, orlater FAA approved revisions.Rev. 1: Transfer from "Parker Han...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Parker Hannifin Conversion Kit Installation Manual IM 199-90, Rev. J,dated January 7, 2009.Instructions for Continued Airworthiness of the Main Wheel and MainBrake in accordance with the Parker Hannifin Conversion Kit 199-90.or later revisions of the above listed documents approved by EASA inaccorda...	None	04/11/2024	Active	10039114
10039138	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-216/-231/-232/-233 A320-111/-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115	In-Seat Power Supplies	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification TEN651 Issue 1Flight Manual Supplement TEN/A320/003 Issue 1or later revisions of the above listed documents approved by EASA	None	12/04/2012	Active	10039138

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039139	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	3. PA-44-180, PA-44-180T 2. PA-34-220T 2. PA-34-200, PA-34-200T 1. PA-34-220T	Approval of a Transponder System in accordance with AMC 20-2	CS23 Amendment 2The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	Installation Manual IM. 00611 Revision A, dated 16 January 2012.Master Document List MDL.00611, Revision A, dated 29 March 2012.Instructions for Continued Airworthiness ICA.00611, Revision A, dated 02March 2012.Flight Manual Supplement FMS. 00611, Revision A, dated 29 March 2012.or later revisions of...	None	12/04/2012	Active	10039139
10039147	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC SA00303BO	C90GT, C90GTI	ADAS for Hawker Beechcraft Model C90GT, C90GTiInstallation of the Pratt & Whitney Engine Services ADAS in accordancewith Pratt & Whitney Engine Services' Installation Manual DAAS-G-010-6,Revision B, dated April 7, 2010, or later FAA approved revision.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.As established by the FAA STC SA00303BO.The requirements for environmental protection and the associatedcertificated noise and/ or emissi...	1. 250-6 for Hawker Beechcraft Corporation Models C90GT andC90GTi Part23 aircraft, Revision A, approved July 1, 2010, or later FAA approvedrevision, is required with this modification.2. Instructions for Continued Airworthiness (ICA), Pratt & WhitneyDocument No. DAAS-G-260-6, Revision B, dated June...	None	12/04/2012	Active	10039147
10039150	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC SA00295BO	2. 300 1. B200, B200C, B300, B300C	ADAS for Hawker Beechcraft Model B200, B200C, 300, B300, B300CInstallation of the Pratt & Whitney Engine Services' Master DocumentList No. DAAS-T-100-3, Revision D, dated May 13, 2010, or laterFAA-approved revision.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.As established by FAA STC SA00295BO.The requirements for environmental protection and the associatedcertificated noise and/ or emissionsu...	1. Pratt & Whitney Engine Services, Flight Manual Supplement No.DAAS-T-250-5 for Hawker Beechcraft Corporation Models B200, B200C, 300,B300, and B300C Part 23 aircraft, Revision D, approved May 14, 2010, orlater approved revision, is required with this modification.2. Instructions for Continued Airw...	None	12/04/2012	Active	10039150
10039166	ATELIER CHABORD	REV. 2		CESSNA 172R, 172S 172R, 172S	Exhaust system and silencer installation (according to Chabordmodification STC-C172.12-01)Revision 2:-Enhanced silent blocks-Alternative anti corrosion surface treatment-Enhanced shape of central structural part in muffler	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 Amdt 3 § 607,611, 783, 807, 867, 1101, 1121, 1123, 1125and 1529The requirements for environmental protection and th...	Technical Dossier ref. STC-C172.12-01 Revision B dated 21 July 2022Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/08/2022	Active	10039166
10039175 (EASA.A.S.00200)	RUAG AG	REV. 3		DHC-6 SERIES 300 DHC-6-300	Minor change to STC EASA.A.S.00200 by adding the option to install aThommen AD32 instead of the Shadin ADC 2000Installation of TAWS class A Honeywell MK VI incl. KMD-850 indicatorinaccordance with Certification Program Doc. T6-100	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Master Document List, Doc. No. T6-000, Rev. 000, dated 15.05.2006-AFMS Doc. No. T6-500, Rev. 1, dated 15.05.2006or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/01/2021	Active	10039175
10039180	CEAPR	REV. 2		R2160, R2160D, R2160I R2100, R2100A, R2112, R2120U HR200/160 HR200/120, HR200/120B HR 200/100, HR200/100S	DET 120301 Rev. 0 - Oil pressure tranducer line R2000-HR2000 dated 7March 2012	The certification basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS 23CS 23 amdt 2The certificated noise and/or emissions level of the original productare unchanged and remain applicable to this certific...	None	Limitation to serial numbers 001 up to 378 included.	26/04/2012	Active	10039180

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039182	LUFTHANSA TECHNIK AG	REV. 1		B737-700	Cabin Completion "Tiger"	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate.Special Conditions:CRI D-02 Isolated compartmentsCRI D-06 Compartment Interiors Heat Release and Smoke EmissionCRI D-10 Glass screens of displays m...	- Compliance Record List CRL00-10/27M Issue 1- Aircraft Flight Manual Supplement A-00-10/281/ AFM Issue 1- Instructions for Continued Airworthiness A-00-10/281-ICA Issue 1or later revisions of the above listed documents approved by EASA	Refer to AFM limitations on the use of Portable Electronic devices	24/04/2012	Active	10039182
10039188	DOA21 LIMITED	REV. 2		A319-115	Introduction of Custom InteriorRev. 1: Correction of a typographical error concerning the Instructionsfor Continued Airworthiness reference under Limitations/Conditions.Rev. 2: Transfer of STC holder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following EASA Certification Review Items (CRIs) are part of thecertification basis for this design change:-Deviation CRI D-01 Issue 1 "Installation of in...	STC Twenty One Limited documents:-Master Document List S21.MDL-0868 issue 1, dated 13th April 2012.-Aeroplane Flight Manual (AFM) Supplement S21.FMS-0090 Issue 1, dated13th April 2012.-For documents and supplement manuals related with instructions forcontinued airworthiness see references on MasterS...	This design change approval is applicable on Aircraft modelAirbusA319-115, aircraft serial number 4622.Any subsequent change to the modes of operation of the WLAN approvedunder this design change will require a re-examination to determineifthe compliance demonstration and/ or the certification basi...	24/10/2023	Active	10039188
10039195	S-TEC CORPORATION	REV. 1	FAA STC SR02344LA	BELL 407	Installation of HeliSAS stability augmentation system and autopilotValidation of FAA STC SR02344LA	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 27, with following amendments and related paragraphs:Amdt 11: 1322; Amdt13: 1321, 1351, 1357; Amdt 14: 29, 1581; Amdt 18:1529; Amdt6...	-Master Data List, HeliSAS-MDL-407 revision D dated March 19, 2012-Rotorcraft Flight Manual Supplement , HeliSAS-RFMS-407 revision N/Cdated March 1, 2011-Instructions for continued Airworthiness (ICA), Document No. AA-09109Revision B datedNovember 23, 2011or later revisions of the above listed docu...	VFR only	18/04/2012	Active	10039195
10039197	STRAIGHT FLIGHT, LLC			CESSNA 510	Modification of the aircraft interior to allow for two configurations:1) Observer configuration and2) back to the Type Certificated standard Executive configuration inaccordance with Straight Flight Master Drawing List Document No. 4979-MDL-01, Revision B, dated June 15, 2010, or later FAA approvedre...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List: Doc. No. 4979-MDL-01, Revision B, dated June 15,2010.Aircraft Flight Manual Supplement: Doc No. FMS-4979-R007, Rev N/C, datedJune 16, 2010Instructions for Continued Airworthiness: Doc No. 4979-R-006, dated June7, 2010,Revision A.or later revisions of the above listed documentsa...	According limitations section of AFMS. This approval is limited to theinstallation and use of a 40 Cubic Foot occupant Oxygen supply tankonly.	17/04/2012	Active	10039197
10039198	JET AVIATION ST. LOUIS, Inc.		FAA STC ST01065WI-D	BD-700-1A10/11	Installation of a Supplemental Crew Oxygen System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST01065WI-D dated 30 November 2011.Midcoast Master Data List 35-261G001 Revision K, dated 20 September 2010Airplane Flight Manual Supplement(s) 35-261M001, Revision Original,dated 28 March 2002 (Config. 1); or 35-261M004, Revision NC, dated 24March 2006 (Config. 2); or 35-261M007, Revisi...	None	17/04/2012	Active	10039198

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039199	JET AVIATION ST. LOUIS, Inc.		FAA STC ST02658CH-D	BD-700-1A10	Installation of a Passenger Address System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST02658CH-D dated 30 November 2011.Jet AviationMaster Data List 35-411G001, Revision C, dated 5 December2008Jet Aviation Airplane Flight Manual Supplement (AFMS) 35411M001 RevisionNC, dated 6 December 2008or later revisions ofthe above listed documents approved by EASA inaccordance wit...	None	17/04/2012	Active	10039199
10039202	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		B747-400	B747-400 Cabin re-configuration in accordance with Northwest AerospaceTechnologies Inc. Master Drawing List N0375-D10 Rev. A dated April 12,2012	This certificate/ approval involves a change to the requirements forenvironmental protection and/ or a change to the certificated noise and/or emissions levels.CRI H-01 Enhanced Airworthiness Programme for Aeroplane SystemsCRI D-01 Use of FAA Policy Statement on Flammability Testing of InteriorMater...	Northwest Aerospace Technologies Inc. Master Drawing List N0375-D10 Rev.AInstructions for Continued Airworthiness - Principle Manual for theInterior Reconfiguration for Lufthansa Boeing 747-400 Aircraft N0375-D70Rev. Aor later revisions ofthe above listed documents approved by EASA	The use of the baby basinet is not permitted unless a "Remove beforeTaxi, Take-off and Landing" placard is installed either on the babybassinet or on the surface on which the babybassinet is mounted. Theuse of cabin crew procedures to show compliance with the applicableairworthiness requirements is...	07/05/2012	Active	10039202
10039222	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE			AW139	EASA Validation of FAA STC No. SR02379LA "Installation of ApicalIndustries, Inc. Cable Cutter Kit"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Apical Industries, Inc. Master Document List MD139-3 Rev. B, dated 17October 2011Apical Industries, Inc. Instructions for Continued Airworthiness, ICA139-31, Rev. N/C, dated 15 July 2012	None	18/04/2012	Active	10039222
10039230	ADAC LUFTFAHRT TECHNIK GmbH			BK117 C-2	NVIS Certification of mission equipment on an Eurocopter BK117 C2	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS29 Amdt 2 incl. App. BThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of th...	Flight Manual Supplement:-EC145-01932-025-MFS-00 Rev. 0or later revisions of the above listed documents approved by EASA-EC145-01932-023-MMS-01 rev 1 MAINTENANCE MANUAL SUPPLEMENT-EC145-01932-004-DIN-00 Rev. 0 Installation Instructionsor later revisions of the above listed documents.	Required pre-modification EASA approval 10038241 (ECD majorchange 2237)	19/04/2012	Active	10039230
10039237	S-TEC CORPORATION		FAA STC NO. SA09350 AC-D	BEECH 95/B95/B95A/ D95A/E95	Installation of S-TEC system 20/30 single and two axis Automatic FlightGuidance Systems, model ST-808-20/30, according to bulletin N. 908 rev.1dated 01-Dec-2008 and with Master Drawing List N. 921083, Rev. A, dated01-Dec-2008 or later FAA approved revision (28V - System).	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved S-TEC Bulletin N. 908, rev.1 dated 01-Dec-2008, or laterFAA approved revision.FAA approved S-TEC Master Drawing List No. 921083, Rev. A, dated01-Dec-2008, or later FAA approved revision.FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891685, da...	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s).	19/04/2012	Active	10039237
10039239	KUERZI AVIONICS AG			MF900	SATCOM Upgrade to WiFiActivation of the WLAN option of the existing AVIATOR 300 SATCOM systemon MF900 S/N 118	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List doc No. MDL-201110583 Rev N/C dated 16April 2012.Aircraft Flight Manual Supplement doc No. FMS-201110583 Rev 0 dated 29September 2011.or later revisions of the above listed documents approved by EASA	Limited to MF 900 S/N 118	19/04/2012	Active	10039239

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039242	AVIATION SUPPORT GmbH		FOCA 25-70-012	EC135 T2	Installation of an external Ski Basket Equipment P/N AV 115.00	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement Doc. Number FMS SUP.11-10- Instructions for Continued Airworthiness Doc Number AZ-ICA AZE-BasketEC 135-AV115.00 Edition 1 Rev 0, dated 12.10.2004or later revisions of the above listed documents approved by EASA- Drawing AV-115.00 Edition 1, Rev 0, dated 06.08.20...	None	19/04/2012	Active	10039242
10039248	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA2367NM	CL-600-2C10/-2D24 CL-600-1A11/-2A12/-2B16 /-2B19	Cockpit Sunvisor Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. SA2367NM dated 04 June 2004.Rosen Sunvisor Systems, Master Drawing List No. RCL 600/601-00DLRevision E, dated 29 June 2010, or later approved revision.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisionst...	None	20/04/2012	Active	10039248
10039256	HARTZELL PROPELLER LLC		FAA STC SA00470AT	A188, A188A, A188B	Installation of either a Hartzell model PHC-C3YF-1RF/F8468A()-6Rpropeller and associated spinner assembly C-3535-1(P) in accordance withFAA STC SA00470AT	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Bonaire Aviation Company Installation Instructions PropellerInstallation in Cessna 188 series, Doc. No. BOAC 1010, dated January 17,1994Bonaire Aviation Company drawing Numbers 3,6 and 7, all dated January17, 1994FAA Approved SupplementalAirplane Flight Manual, dated May 5, 1994forCessna Model A18...	None	20/04/2012	Active	10039256
10039264	S-TEC CORPORATION	REV. 1	FAA STC SA09010AC-D	SEE EASA APPROVED MODEL LIST	Installation of S-TEC system 55/55X two axis Automatic Flight GuidanceSystems, model ST-589, according to bulletin N. 689 rev.4 dated11-Jan-2010 and with Master Drawing List N. 92790, Rev. D, dated11-Jan-2010 or later FAA approved revision(14V - System).	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved S-TEC Bulletin N. 689 rev.4, dated 11-Jan-2010or later FAAapproved revision.FAA approved S-TEC Master Drawing List No. 92790, Rev. D, dated11-Jan-2010, or later FAA approved revision.FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891176, date...	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s).	25/04/2012	Active	10039264
10039269 (EASA.A.S.03779)	JET AVIATION AG	REV. 4		A340-642	Airbus A340-600 “Eminence” - VIP Cabin Interior CompletionRevision 3: Transfer STC 10039269 Rev. 2 from Jet Aviation AGto JetAviation AG, Basel Completions.Revision 4: Transfer STC 10039269 Rev. 3 from Jet Aviation AG, BaselCompletions toJet Aviation AG.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-1302-002: Isolated compartments.D-1304-002: Flight crew rest compartments.D-1310-002: Displays / Monitors glass screens.D-1311-002: Cabin glass pane...	- Master Data List, ref: B 3400924-001 Revision H, dated 01Nov. 2012;- Airplane Flight Manual Supplement, ref: B3400924-201-01 Revision H;- Instructions for Continued Airworthiness, ref: B 3400924-150-01Revision C, dated 17 Oct. 2012;- JBSL-O-00038ISR-02 issue 3 “Airbus ELA for Past Completion”;- J...	None	20/12/2017	Active	10039269

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039277	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Installation of Patch Iridium Antenna applicable to Dassault AviationMystère Falcon 20GF aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Uni Air Enterprise Master Data List MDL-011-11 Revision 5, dated 30thMarch 2012.or later revisions of the above listed documents approved by EASA	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	05/01/2015	Active	10039277
10039278	VAN HORN AVIATION, L.L.C.			206B, L, L1, L3, L4	Installation of Replacement Tail Rotor Blades	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The following paragraphs of FAR 27 amendment 27-44 have been compliedwith:27.51; 27.65; 27.71; 27.73; 27.75; 27.79; 27.141; 27.143; 27.17...	-206L1-FMS-901 original issue dated 1 December 2011 - Flight ManualSupplement;-206L3-FMS-903 revision 1 dated 24 January 2012 - Flight ManualSupplement;-206L4-FMS-904 revision 1 dated 24 January 2012 - Flight ManualSupplement;or later revisions of the above listed documents approved by EASA-206-MDL-...	When antenna holder PP-10-A601 is installed VNE is limited to 120 kts;When rack PP-10-A421 is installed, carriage of passengers in front seatsis prohibited;When racks PP-10-A401c or PP-A461 are installed, a maximum of 2passengers in rear seats is permitted.	23/04/2012	Active	10039278
10039279	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			DA40D	Installation of two Garmin GNS 430 W systems, two GA 35 GPSantennas, aGMA 340 audiopanel, a GTX 330 Mode S transponder, a King KN-62A DME andCobham antennas CI 292-2 (VHF), CI 105 (DME), CI 102 (MKR)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appr...	Flight Manual Supplement No SEAM-FMV3723/11 revision 0 dated 28/11/2011SEAM Modification File No 3723/11 revision 1 dated 30/12/2011or later revisions of the above listed documents approved by EASA	Installation of this design change is limited to airplane S/N D4-002 andit must be performed by authorised SEAM technical personnel.This design change is approved for B-RNAV operation without coupling ofthe GNS 430 W systems to an autopilot.The airplane must be equipped with at least one radio navig...	23/04/2012	Active	10039279
10039284	FIELD AVIATION EAST, LTD.	REV. 2	TCCA STC O-LSA11-147/D	DHC-8-202	Air Iceland Avionics UpgradeTCCA STC O-LSA11-147/D, Issue 3	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Configuration A, DHC-8-202, SN 445 and SN 446 onlyInstallation must be performed in accordance with FAEL Master DrawingList designated 25380000 Rev. CFlight Operations must be conducted in accordance with FAEL FlightManual Supplements as follows: 25383000, Rev IR – Collins TCAS II (Change 7) 25383001,...	The modification is limited to aircraft serial numbers 445,446 and 450Universal UNS-1E(w) Flight Management Systems are approved for IFREn-route, Terminal and Non Precision approach operationPrior to installation of this design change it must be determined thatthe interrelationship between this des...	02/03/2018	Active	10039284
10039286	SEGINUS Inc.		FAA STC ST02954CH	BN2T/-4R/-4S BN2B-20/-21/-26/-27 BN2A-8/-9/-20/-21/-26/-27	Installation of a replacement pitot static probe P/N DU130-24 inaccordance with FAA STC ST02954CH.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Drawing EH130-24, Rev.: -, dated August 5, 2010Component Installation Manual SEG130, Rev.: -, dated October 1, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF(or subsequent revisions ofthis decision) Instructions of Con...	None	23/04/2012	Active	10039286
10039303	E A D AEROSPACE AIRWORTHINESS	REV. 3		747-400	Installation of Cobham SATCOM antenna type HGA-7001 in accordance withAerotec MDL AE11110MDL Rev.2, dated 23 April 2012.	The certification basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchangedand remain applicable to this certificate/ approval.	Master Data List MDL AE11110MDL rev. 2 dated 23 April 2012AE11110SB Instructions for Continued Airworthiness, dated 14 December2011.IPC Supplement 01366-IST-A-IPC-04 Rev BAMM Supplement 01366-IST-A-AMM-01 Rev Bor later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	30/07/2015	Active	10039303

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039304	LUFTHANSA TECHNIK AG			A340-311/-312/-313	Navigation - ADS-B Out (Automatic Dependent Surveillance Broadcast) Capability on A340-300This STC consists in installing AOS-B Out capability.This surveillance function is based on the aircraft capability tobroadcast, without any ground request, aircraft parameters enhancing theAir Traffic Control S...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS25 Amdt 10.Therequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original p...	Supplemental Type Definition Document, ref STDD34-11/02M Issue 1, dated27 February 2012.Aircraft Flight Manual Supplement, ref. A-00-11/159-AFM Issue 01, dated07 September 2011.Instruction for Continued Airworthiness, ref. A-00-11/159-ICA Issue 01,dated 06 September 2011.or later revisions of the ab...	None.	24/04/2012	Active	10039304
10039313	AMTECH AERONAUTICAL LIMITED	REV. 1	TCCA STC C-LSA06-188/D	MF900	Artex C406-N ELT and Flight Displays FD600 Video Camera Installations.EASA validation of TCCA Limited STC No C-LSA06-188/D Issue 1 dated 23May 2006.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Amtech Aeronautical Limited (AAL) Master Data List doc No. MDL392801,Rev. IR dated 23 May 2006.Instructions for Continued Airworthiness, doc No. 060509023, Rev. Ødated 09 May 2006.Aircraft Flight Manual Supplement doc No. FMS392801, Rev. IR dated 09January 2012 as approved by TCCA on 14 Feb. 2012.or...	Limited to S/N 141	27/04/2012	Active	10039313
10039317	S-TEC CORPORATION		FAA STC SA8364SW-D	402A, 402B, 402C 401, 401A, 401B	Installation of S-TEC system 40/50 single and two axis Automatic FlightGuidance Systems. Installation Model ST-505-40/50 (28V - System)according to bulletin N. 605 rev.6 dated 21-Jan-2010 and master drawinglist n. 92582 rev. F, dated 21-Jan-2010 or later FAA approved revisionof above documents	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved S-TEC Bulletin No.505 Rev. 6 dated 21-Jan-2010, or laterFAA approved revision.FAA approved S-TEC Master Drawing List n. 92582 Rev. F dated21-Jan-2010, or later FAA approved revision.FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891011, dated4...	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s)	25/04/2012	Active	10039317
10039322	RAISBECK ENGINEERING Inc.	REV. 1	FAA STC SA02215SE	SEE FAA AML	Installation of Butterfield Industries Inspection Panel KitP/N BI9501-001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Fabrication of inspection Panel Kit BI 9501-001, in accordance withDrawing List BI 9025, Revision A, dated 17 February 2012 or later FAAapproved revisions;- Installation in accordance with Installation Instructions BI 9020,Revision A,dated 17 February 2012 or later FAA accepted revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	06/08/2018	Active	10039322
10039327	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY	REV. 2	FAA STC ST02361LA	A340-541. A340-311, A340-312, A340-313,	Installation of On-Board AirstairThis modification installsan On-Board Airstair.This STC installed the airstairs for agiven configuration (aircraftmodel / cabin location).The Revision 1 of this STC reworded the limitation section.The Revision 2 of this STC adds a new configuration (new aircraft mo...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List, Ref. 1423-7000 Revision F.Instruction for Continued Airworthiness, Service and Operational Manual,Ref. MMS-A340-1452 revision C.Lift Module Instruction for Continued Airworthiness, Service andOperational Manual, Ref. MMS-A340LIFT-1713.Airstair Weight and Balance Supplement, Ref....	Interaction of this STC with cabin arrangement features hasnot beenevaluated.Should this STC be part of a cabin arrangement, the interactions betweenthis STC and any cabin or seating arrangements must be evaluated forcompliance with applicable certification requirements in the frame ofthe cabin arr...	06/02/2013	Active	10039327

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039335	DASSAULT FALCON SERVICE			F2000EX EASY	TCAS 2000 upgrade to TCAS change 7.1 on F2000EX EASy	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet DFSD149-CAS Issue A dated 07 March 2012DFS Modification Sheet DFSD149 Issue A dated 07 March 2012DFS Master Document List N °DFS-DE-17-FD-D149 Issue A dated 20 April 2012or later revisions of the above listed documents approved by EASA	As per DFS Change Approval Sheet DFSD149-CAS Issue A dated 07 March 2012	26/04/2012	Active	10039335
10039339	FIELD AVIATION COMPANY Inc.	REV. 3	TCCA STC SA11-27, ISSUE 5	DHC-8-301, -311, -314, -315 DHC-8-201, -202 DHC-8-102, -103, -106,	Universal EFI-890R EFIS Cockpit Upgrade.Inclusion of MMS 25203110 Rev. IR, corrections of minor typographicerrors and editorial changes.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI F-002 (HIRF) CS 25.1316 Amdt. 1The requirementsfor environmental protection and the associatedcertified noise and/ or emissions levels of the original product areuncha...	DHC-8-100 and 200 SeriesInstallation must be performed in accordance with FACI Master Drawingand Data List designated 25200000 Rev K.Flight Operations must be performed in accordance with FACI FlightManual Supplements listed as follows:25203000 Rev B ,,,,EFI-890R Electronic Flight Instrument System2...	The Installation of the DHC-8-314 MPA configuration is limited to Serialnumber 0660.The installation of dual, UniversalUNS-1E, or UNS-1E (w) or UNS-1F orUNS-1F(w) Flight Management Systems are a prerequisite to theinstallation of the EFI 890R Electronic Flight Instrument Suite.Prior to installationt...	25/10/2013	Active	10039339
10039340	FIELD AVIATION COMPANY Inc.	REV. 1	TCCA STC C-LSA12-014/D	DHC-8-202	Installation of upgraded Cabin Floor PanelsTCCA STC C-LSA12-014/D, Issue 1	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation must be in accordance with TCCA approved FieldAviationCompany Inc. Master Data List 25500000, Rev. A *), dated 23 April 2012.Maintenance is unchanged from the instructions provided in theBombardier DHC-8-200 Maintenance Manual PSM 1-82-1. Zonal inspectionsare unchanged from the instruc...	The modification is limited to Serial numbers 445, 446 withpost-1990Hunting interiors only.Floor loads of 75 lbs/ft(s) only in conjunction with underfloor supportstructure modified per Bombardier CR 853CH2003 or equivalent.	03/05/2012	Active	10039340
10039353	LUFTHANSA TECHNIK AG	REV. 1		A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-216/-231/-232/-233 A320-111/-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Replacement of Litton MK-1 Global Positioning System SensorUnit (GPSSU) by CMC Electronics GPSSU CMA-5024 (STC revised for validity extension to A319 and A321 models)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD34-11/21M Issue2 Rev. 2dated 07.08.2012- Compliance Record List CRL34-11/21M Issue 2 Rev. 2 dated 07.08.2012- Instructions for Continued Airworthiness A-00-12/01-ICA Issue 1 Rev. 2dated 02.08.2012- Declaration of Compliance N. 3476 dated 07.08.2012or late...	None	08/08/2012	Active	10039353
10039356	JET AVIATION AG, BASEL			A340-311, A340-312, A340-313 A340-211, A340-212, A340-213	Camera Unit and Structural provision installationThis STC installs one camera on the tail of the aircraft, watchingforward. This covers the mechanical installation of the camera unit andthe penetration of the pressure.	The certification basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchangedand remain applicable to this certificate/ approval.	Master Data List, BA34031701-001 Issue A, dated 26.04.2012Instructions for Continuous Airworthiness, BA34031701-150-01 Issue A,dated 26.04.2012or later revisions of the above listed documents approved by EASA.	None.	30/04/2012	Active	10039356
10039357	JET AVIATION AG, BASEL			A340-311, A340-312, A340-313 A340-211, A340-212, A340-213	Tailwind 550/560 antenna installationThis STC installs a tailwind SAT TV antenna and radome on top of thefuselage.	The certification basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchangedand remain applicable to this certificate/ approval.	Master Data List, BA34053203-001 Issue A, dated 26.04.2012Instructions for Continuous Airworthiness, BA34053203-150-01 Issue A,dated 26.04.2012or later revisions of the above listed documents approved by EASA.	None.	30/04/2012	Active	10039357

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039373	PROTOPLANE SPECIAL MISSION AIRCRAFT			MF50	Attachment provisions on Falcon 50 S/N 011.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List N °PP-033-MDL-01 Issue 1 dated 20.04.2012Instructions for Continued Airworthiness N° PP-033-ICA-00 Issue 0 dated01.04.2012or later revisions of the above listed documents approved by EASA.	Limited to S/N 011.	30/04/2012	Active	10039373
10039386	ISOLAIR Inc., ISOLAIR HELICOPTER SY		FAA STC SR02813CH	ENSTROM 480B ENSTROM 480	Title: Installation of 3900-480 Spray SystemDescription: The installation of the 3900-480 Spray System pertains tothe installation of an agricultural spray system onto the Enstrom480and 480B rotorcraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement No. 3900-480FMS-EASA;Chapter 4 "Airworthiness Limitations" of the Instructions For ContinuedAirworthiness, ICA Manual No. 3900-480-EASA ICA, Rev. A dated 7th March2012;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Deci...	Restricted to agricultural use.	02/05/2012	Active	10039386
10039387	DUNLOP AIRCRAFT TYRES LIMITED		CAA UK RESPONSIBILITY	ATR 42-200/-300/-320/-400/-500	Installation of Dunlop Aircraft Tyres on ATR 42 seriesThe STC installs Dunlop Aircraft Tyres Ltd P/N DZ33012T (Main LandingGear) and P/N DR15520T (Nose Landing Gear).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, ref. KT509009MDL, dated 11 April 2012Instruction for Continued Airworthiness, ref. KT509009ICA, dated 11April 2012or later revisions of the above listed documents approved by EASA	None	02/05/2012	Active	10039387
10039405	ASI INNOVATION			F150L, FA150L	ASI-FAM-082-04 - Installation of EFIS Aspen EFD 1000 on Cessna 150	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	None	The EFD 1000 must not be used as primary flight and navigation source.Independent and dissimilar instruments must be installed for primaryindication of attitude, altitude, airspeed, vertical speed, magneticheading and navigation data, as required for day and night VFR flights.	02/05/2012	Active	10039405
10039407	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC ST02068CH	HS.125 SERIES F600B HS.125 SERIES F403B HS.125 SERIES F400B HS.125 SERIES 700B HS.125 SERIES 700A HS.125 SERIES 600B/3 HS.125 SERIES 600B/2 HS.125 SERIES 600B/1 HS.125 SERIES 600B HS.125 SERIES 600A HS.125 SERIES 403B HS.125 SERIES 403A(C) HS.125 SERIES 401B HS.125 SERIES 400B/1 HS.125 SERIES 400B HAWKER 900XP HAWKER 850XP HAWKER 800XP HAWKER 800 HAWKER 1000 DH.125 SERIES 400A BH.125 SERIES 600A BH.125 SERIES 400A BAE.125 SERIES 800B BAE.125 SERIES 800A BAE.125 SERIES 1000B BAE.125 SERIES 1000A	To Install an Air Ambulance Conversion.This Change instructs the interior and electrical changes to theaircraft. Stretcher and medical equipment installation will be certifiedby the appropriate vendor.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installed in accordance with Spectrum Aeromed Inc Master Document list6033-2DL, Revision 3, dated September 26, 2011;Operation in accordance with Spectrum Aeromed Inc Approved Flight ManualSupplement 6033-2FMS, Revision 2, dated September 15, 2011;Maintained in accordance with Instructions for Conti...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/04/2019	Active	10039407

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039421	BRITISH AIRWAYS PLC	REV. 2	CAA UK RESPONSIBILITY	A321-212, -231 A320-214, -216, -232 A319-111, -131	Airbus TCAS Change 7.1 UpdateRev. 1: Honeywell TCAS computer changed part number from 940-0351-001 to940-0351-005 to correct False RA issueRev. 2: Editorial correction	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 amendment 11 for therequirements affected by this change.	- Master Data List – Airbus TCAS Change 7.1 Update, Report Ref:BA-320-34-0006-MDL dated 14 September 2017, Issue 05- STC Definition & Certification Document, Doc Ref: BA-320-34-0006-STC,Issue 05.or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/10/2017	Active	10039421
10039428	AIRFILM CAMERA SYSTEMS, INC		FAA STC SR02377LA	429	Airfilm Nose Utility Mount	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List AFM-NM429-10, Rev N/C, dated August 1, 2011- Installation Instructions AFM-NM-006, dated October 7, 2011Instructions for Continued Airworthiness AFM-NM-008, dated August 1,2011- Rotorcraft Flight Manual Supplement AFM-NM-005, dated October 17, 2011or later revisions of the abov...	None	03/05/2012	Active	10039428
10039429	AIRFILM CAMERA SYSTEMS, INC		FAA STC SR02376LA	429	Airfilm Tail Utility Mount	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List AFM-AM429-10, Rev N/C, dated August 1, 2011- Installation Instructions AFM-AM-006, dated October 7, 2011- Instructions for Continued Airworthiness AFM-NM-008, dated August 1,2011- Rotorcraft Flight Manual Supplement AFM-AM-005, dated October 17, 2011or later revisions of the ab...	None	03/05/2012	Active	10039429
10039436 (EASA.A.S.03778)	JET AVIATION AG, BASEL	REV. 2		A340-300	Airbus A340-300 "Olbia" VIP Cabin Interior CompletionThis STC installs a VIP cabin interior.The Revision 1 removed a limitation.The Revision 2 has introduced two configurations regarding the Crew RestCompartment utilisation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-2302-001,,Isolated CompartmentsD-2304-001,,Crew Rest CompartmentsD-2310-001,,Glass Screens of Displays/ MonitorsD-2311-001,,Installation of Glass Pan...	Master Data List, ref : B3400955-001 Revision H, dated 17 July 2013Airplane Flight Manual Supplement, ref : B3400955-201-01 Revision E,dated 28 May 2013Instructions for Continued Airworthiness B3400955-150-01 Revision A,dated 26 April 2012Weight and Balance Manual Supplement, ref : AFG-15M, dated 09...	Airstairs installation is not part of the approved configuration	19/07/2013	Active	10039436
10039438	MECAER AVIATION GROUP S.p.A.	REV. 1		AW109SP	Installation of Cabinet Five Star P/N 6A10AD002-001 in AW109SP.Modification in accordance with MECAER Notice of Design Change NDC6A10AD-003 issue A dated 24/04/2012.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	"Owner's Manual for Cabinet Five Star Installation P/N 6A10AD002-001" P/N 6A10WNM-2-2 First Issue Rev. A dated 04/05/2012 or later approvedrevision."Notice of Design Change" Ref. NDC 6A10AD-003 Issue A dated 24/04/2012."AW109SP Cabinet Five Star Compliance Checklist" Ref. 6A10RAD-010Rev. D dated 24/...	This STC approval does not include the installation of the in-flightentertainment equipment inside the Cabinet Five Star.	16/05/2012	Active	10039438

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039454	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	EC135 P1	Installation of Kelvin 275 Camera per Drawing List DL/1352044-001, IssueA	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement EC 135 P1 SupplementNo. 58,Issue 1or later revisions of the above listed documents approved by EASA- Instructions for Continued Airworthiness ICAW/ 1352044-001 Issue A- Drawing List DL/ 1352044-001, Issue A	-Day/Night VFR operation only- Operation of the Kelvin 275 camera approved under this STC (EC UKmodification EC UK/135/2044) has to be done, in conjunction with EC UKmodificationsEC UK/ 135/2045 and EC UK/135/2043	04/05/2012	Active	10039454
10039466	BELL HELICOPTER TEXTRON, Inc.		FAA SR02810NY	429	Installation of Hardpoint and Spotter Fixtures in accordance withAeronautical Accessories Inc. Installation Drawing List for HardpointFixture Kit, Ceiling Spotter Fixture Kit, Floor Spotter Fixture Kit,Report Number AA-09043, Rev C, dated June 29, 2010.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aeronautical Accessories Inc. Installation Drawing List for HardpointFixture Kit, Ceiling Spotter Fixture Kit, Floor Spotter Fixture Kit,Report Number AA-09043, Rev C, dated June 29, 2010 ;- Lawson Aerospace LLC Instructions for Continued Airworthiness (ICA)for Hardpoint Fixture Kit, Ceiling Spott...	None	07/05/2012	Active	10039466
10039479	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 2		AS 355 F, AS 355 F1 AS 355 F2, AS 355 N	HELICOM V2 ANA / V2+ ANA.HELICOM V2 ANA / V2+ ANA is a flight data recorder and transmitter offlight-and-systems parameters.Revision 1: Extension of the capabilities of the systemby introducingPN 4720P-xx and PN 4730P-xx (HELICOM V2+ ANA).Revision 2: STC holder name change from I.S.E.I Internationa...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Issue 3 - LithiumBatteryInstallations.The requirements for environmental protection and the associatedcertified noise and/ or emissions l...	N9-AS355 ANA-HV2 ANA ON PANEL Edit A Revision 04 - Flight ManualSupplementRevision 01:N9-AS355 HV2 HV2+ ANA E-B-01 Rev.03 dated 14/12/2015 - Flight ManualSupplement.or later revisions of the above listed documents approved by EASA.N2-AS355ANA-HV2 ANA ON PANEL Edit A Revision 04 - CertificationProgr...	The system does not replace standard maintenance records and pilotreporting.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the a...	27/02/2020	Active	10039479
10039483 (EASA.R.S.01391)	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)	REV. 1		2- AS355F2, AS355N, AS355NP 2- AS355E, AS355F, AS355F1 1- AS350BB, AS350B1, AS350B2 1- AS350B, AS350BA 1- AS350B3, AS350D	Installation of an Outside Aerial Picture System.Revision 1adds installation of AILIMOUNT III camera system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SUPPLEMENT MANUEL DE VOL - INSTALLATION SUPPORTS SYSTEME DECAMERA -AS350B, BA, BB, B1, B2, B3, D, AS355E, F, F1, F2, N, NP (Modification:H-25-03-07-Aile Image), Ed.0 R1 / Janvier2012;or later revisions of the above listed documents approved by EASA.PLANS DE DEFINITION ET PIECES JUSTIFICATIVES - IN...	This STC does not approve Installation of an Outside AerialPictureSystem on AS350B3 helicopters incorporating modification OP-4305(Arriel2D engine installation). Compliance against the requirements ofapplicable certification basis for AS350B3 helicopters incorporatingOP4305 hasn't been verified.	07/05/2012	Active	10039483
10039495	GFD GmbH	REV. 2		35A/36A 35A, 36A	Enhanced Surveillance Upgrade to MST 67A Transponder (Honeywell)Rev. 2: Transfer to GFD GmbH.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AIEC Master Data List: ref 5187-049, rev A, date 17 April 2012;AIEC AFM Supplement: ref 5187-071, rev IR, date 26 March2012;AIEC Instructions for Continued Airworthiness: ref 5187-085, rev IR,date 23 March 2012;or later revisions of the above listed document(s) approved/ acceptedunder the EASA syste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10039495

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039496	GFD GmbH	REV.2		36A 35A, 36A 35A	Replacement of UNS-1M or UNS-1B by UNS-1Fw MMMSRev. 2: Transfer to GFD GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	According to AIEC Master Data List No. 5183-049, Rev. A or5183-049.01_Rev.IR;To be installed i.a.w. AIEC drawing list 5183-082, Rev B or 5183-082.01,Rev IR;To be operated i.a.w. AIEC AFMS 5183-071, Rev B and 5183-071.01, Rev IRor 5183-071.02, Rev IR ;To be maintained i.a.w. AIEC ICA Document No. 518...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10039496
10039502	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	BN.2A MARK III TRISLANDER, BN.2A MARK III-3 TRISLANDER. BN.2A MARK III-2 TRISLANDER, BN.2A MARK III-1 TRISLANDER,	Installation of Aspen EFD1000 Electronic Primary Flight Display	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS23 Amendment 2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	Master Data List MDL-1282 Issue 1, dated 04 May 2012 ;Change Statement CS-1282 Issue 1, dated 04 May 2012 ;Flight Manual Supplement AFMS-1282 Issue 1 ;or later revisions of the above listed documents approved by EASA	None	08/05/2012	Active	10039502
10039505	MACH TECHNICAL DESIGN S.L.			BELL 412	Surveillance Camera Installation according to MDL-FAA-0110 Rev. B(The modification consists in the installation of a camera to captureimages and the associated equipment to process and send them to a groundstation.)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Rotorcraft Flight Manual Supplement FMS-FAA-0110, Issue 1 , dated02/03/2012or later revisions of the above listed documents approved by EASA-MDL-FAA-0110, Rev B dated 07/05/2012-OT-FAA-0110, Rev 00, dated 19/12/2011-DIP-FAA-0110, Rev 0, dated 01/12/2010	The installation of this STC is compatible with the installation of theTCCA STC SH96-57 (LBA STC RC.1182): Installationof Heli-Access StepsP/N D205-0633-011 in accordance with Dart Aerospace Ltd. DrawingIIN-D205-633, Rev A.Prior to installation of this modification it must be determined thatthe in...	08/05/2012	Active	10039505
10039512 (EASA.A.S.01198)	TELEDYNE UK LIMITED	REV. 2	CAA UK RESPONSIBILITY	767-200, 767-300, 767-300F 767-200, 767-300/-300F	Installation of Wireless Quick Access RecorderRev. 2: Transfer from Teledyne Limited to Teledyne UK Limited.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Teledyne Controls Master Data List STC-MDL-013-15 Issue 15,dated 04January 2012<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/11/2020	Active	10039512
10039513	AIRBORNE TECHNOLOGIES GmbH			P2006T	Police cabin configuration/Installation of a camera lift for 10" gimbals, operator console andreplacement of hatch doors by fixed coversFor standard analogue instruments equipped aircraft step 1 of this STCis applicable, for Garmin G950 equipped aircraft step 2 is applicable	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Depending on aircraft instrument panel configuration (analogueinstruments or Garmin G950) the following documents are required:"Police cabin configuration", Doc. No. STC-AT-045, Rev. 2"Installation Instructions", Doc. No. 045-II-STC-AT, Rev. 0AFM Supplements Doc. No. AFM1-STC-AT-045, Rev. 0 or AFM2-...	Airborne Technologies STC no. "STC-AT-003", step 1 (analogueinstruments) or step 3 (Garmin G950 version) of latest approved revisionmust be installed prior this modification.	08/05/2012	Active	10039513
10039535	SAFRAN CABIN BELLINGHAM, INC.		FAA ST02227SE	747-400	Installation of 2 new avionics racks in the EE bay of a Boeing 747-400series aircraft in accordance with Heath Tecna Inc. Master Data ListHPD-DL-162 Rev. A, dated April 12, 2012 or later approved revision.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.§25.571(a)(b),,,,Amdt 25-86,,,,§25.853(a),,,,Amdt 25-83§25.869(a)(4),,,,Amdt25-113,,,,§25.1353,,,,Amdt 25-113§25.1431(c)(d),,,,Amdt 25-1...	Heath Tecna Inc. Master Data List HPD-DL-162 Rev.A, dated April 12, 2012Instructions for Continued Airworthiness Heath Tecna Inc. Doc HTM 1004,Revision B, dated April 4<(>,<)> 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subs...	Approval of this change applies to Boeing 747-400 aircraft listed inHPD-DL-162 Rev.A, dated April 12, 2012 or later approved revisions only	10/05/2012	Active	10039535

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039546	ROEDER PRAEZISION GMBH			TU206F	Installation of an additional Alternator with Battery for MissionPurposes	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement 01271AM240030-01Aor later revisions of the above listed documents approved by EASAInstructionsfor Continued Airworthiness 01271CA240030-01AEngineering Order 01271EO240030-01A	None	10/05/2012	Active	10039546
10039554	ROEDER PRAEZISION GMBH			172S	Installation of provision for the installation of a camera in the lowerfuselage as described in description document 14576DE 5300 10 00D.	The Certification Basis of the original product remains applicable tothis change.This certificate/ approval involves a change to the certificated noiseand/ or emissions levels.	Master record list Rev A C172S 14576 MR 5300 10 01C (rev.C) dated10.05.2012.EASA approved Supplement to Pilot's Operating Handbook 14576 AM 5300 1001C (rev.C) dated 27.04.2012 andany later EASA approved revision.Instruction for Continued Airworthiness 14576 CA 5300 10 01B (rev.B)dated 10.04.2012.	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s).This STC is limited to S/N 172S8186.This STC provides instructions only for the installation of theprovisionfor a camera. Further instructions for the completion of the...	10/05/2012	Active	10039554
10039562	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)	REV. 1		1900	Installation of a galley in accordance with SOCIETE D'ETUDEET DEGESTION AERONAUTIQUE (SEGA) Master Document ListA-11-03-TwinJet-GalleyII_MDoL Edition 1 April 2012	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Procedure: Installation sur avion Hawker Beechcraft 1900d'une armoire self-service, ref.SEGA A-11-03-TwinJet-GalleyII_DA,Edition 1, April 2012<(>,<)>Aircraft Flight Manual Supplement: Supplement manuel de vol, ref. SEGA,A-11-03-TwinJet-GalleyII_AFMS, Edition 1, January 2012<(>,<)>Instru...	None	05/06/2012	Active	10039562
10039575	AIRCRAFT CABIN MAINTENANCE GmbH	REV. 1		3. B767 2. B737 1. A330	Installation of refurbished Passenger Seat Belt P/N EPA20511-2-01-20 on16g seats	CS-25The Certification Basis for the original product remains applicable tothis certificate/ approval.	Refer to Master Document List E/O No. 82-1000845 Rev. 0 (11.04.2012)or later revisions of the above listed documents approved by EASA	As per Service Bulletin No. 82-1000845 SEB 06 00, latest revision	21/05/2012	Active	10039575
10039579	NEW SYSTEMS ENGINEERING	REV. 1	FAA STC ST10977SC	DHC-8-301/-311/-314/-315 DHC-8-201/-202 DHC-8-102/-103/-106	Installation of Dual Universal Avionics Flight Management Systems (FMS)with Global Positioning System (GPS)FAA STC ST10977SC	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. SC H-01)The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 25, Amendment 123Therequirements for environmental protection and the associated...	Installation in accordance with New Systems Master Drawing List379-00-0001, dated 02.05.2012 *)Flight Operations in accordance with New Systems Flight ManualSupplement 379-00-0004, Rev. IR, dated 01.06.2010 *) Instructions for Continuing Airworthiness:Maintenance must be conducted in accordance withd...	Installation is limited to serial numbers listed in the latest approvedversion of FMS Instruction Top Drawing 379-02-0001.	21/05/2012	Active	10039579
10039607	AVIDYNE CORPORATION	REV. 1	FAA STC SA0282BO	PA-46R-350T	Integrated Flight Display	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.For those portions of the airplane that are unchanged from the basicPA-46R-350T the applicable certification is in accordance with EASA T...	Operation of the aircraft must be in accordance with Avidyne AirplaneFlight Manual Supplement P/N 600-00263-001 Rev. 00, for PiperPA-46R-350T Matrix with Avidyne Integrated FlightDisplays P/ N700-00083-XXX and Control Display Unit P/N 700-00150-XXX. The AFMS mustbe carried in the aircraft during all...	Enhanced Vision System (EVS) is not included in the scope of thisapprovalCompatibility with Mode 5 alerts must be shownwhen a TAWS Class A isinstalled.	11/10/2012	Active	10039607

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039614	365 AEROSPACE DDS LIMITED	REV. 25		SEE EASA APPROVED MODEL LIST	Installation of Donica Digital Media Reproducer	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification DN-DMR-23-000 Issue 17 dated 19th April 2019.Instructions for Continued Airworthiness V. 07 dated 12 January 2019DN-MD90-23-0000-01 V.02 Installation of DMR onto MD-90-30 (Eva Air) DN-737-23-0000-02 V.02 Installation of DMR ontoBoeing 737 (Neos)DN-767-23-0000-03 V.01 Installation of DMRD...	Amendment to the STC is required in order to extend the applicability ofthis STC to the following types, A318 (EASA.A. 064), B747(EASA.IM.A.196). The amendment to the STC shall provide the installationinstructions and ICA to supplement the common data package that isdefined within Modification DN- DM...	02/12/2019	Active	10039614
10039615	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	B200 KING AIR	Installation of polyurethane reticulated foam into fuel tanks, asdefined by:JN323 ADC17 (1) Master Data List	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation in accordance with JN323 ADC34 (1) Issue 1<(>,<)>Modification InstructionsOperation in accordance with JN323 ADC29 (1) Issue 1, Flight ManualSupplementMaintain in accordance with JN323 ADC54-23 (1) Issue 1<(>,<)>Instructions for Continued airworthiness (ICA)or later revisions of the abo...	This STC grants no credit for any fuel tank flammability reduction.	14/05/2012	Active	10039615
10039631	ACS-NAI Ltd.		TCCA STC C-LSA05-318/D	CL-600-2B16	Aircraft Completion ASN 5618, 12 Passenger Interior Configuration.	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. C-LSA05-318/D Issue 2, dated 21 July 2006.AeroConsulting Services Ltd Modification Data Summary 610000 RevisionA, dated 18 July 2006.Midcoast Aviation Airplane Flight Manual Supplement 34-424M005 RevisionA.Midcoast Aviation Airplane Flight Manual Supplement 34-261M017 RevisionA.Aero Co...	Restricted to ASN 5618	15/05/2012	Active	10039631
10039633	AIRBUS HELICOPTERS DEUTSCHLAND GmbH		LBA STC EMZ NR. 0654/3058	BO 105 LS A-3	Title: Superlifter Conversion Kit 105-8003331Description:Original STC: The model B0105 LS A-3 is changed in accordance withdrawing No. 105-800331. The changed model is called "Superlifter".Revision 1: The Airworthiness Limitations related to EMZ Nr. 0654/3058has been changed and approved.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Original STC:Flight Manual BO 105 LS A-3, DOT-approved dated 25th February 199'j orlater DOT approved versions until 29th June 2009FMA 12-1 "Appendix for BO 105-LS A-3 SuperlifterOperation",LBA-approved dated 6th October 1995 or later LBAapproved versions until27th September 2003Change:Chapter 101...	The implementation of the modified cargo hook 105-803101 isonlyapproved after conversion of the helicopter in accordance with drawingNo. 105-800331.This STC is valid in conjunction with the EASA TCDS R.011 in theapplicable version.This Supplemental Type Certificate is approved only for the productc...	24/05/2012	Active	10039633
10039634	AERODATA AG			B300	Installation of Aerodata Automatic Flight Inspection SystemAD-AFIS-0270	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2 (not required by 21A.101)The requirements for environmental protection and the associatedcertificated noise and/ or em...	Flight Manual-Supplement: AFM-130, Rev.1or later revisions of the above listed documents approved by EASA.Installation Manual,,,,,,HB-A/C-1118, Rev.0Master Document List,,,,,,MDL-A/C-0177, Rev.3Maintenance Manual Supplement,,AMM-1117, Rev.0	None	15/05/2012	Active	10039634

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039666	AIRBUS S.A.S.			A320-214	Airbus Corporate Jet Centre Modification CJ1100 Issue 1 -Installation of Business Class Seating Area - "Gulf Air - TypeA"	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI A 2301-006 "ACJC Centre Conversion Project Certification Basis"The requirements for environmental pro...	-Modification Approval Sheet, ref.: CJ1100<(>,<)> Issue 1, dated 16thMay 2012-Airplane Flight Manual AFM Supplement< (>,<)> ref.: FM-S MOD CJ1100,dated 1st May 2012or later revisions of the above listed documents approved by EASA	This STC is limited to MSN 4827, MSN 4860, MSN 4865	16/05/2012	Active	10039666
10039667	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		208, 208B	Installation of 5-blade MT-Propeller ModelMTV-27-1-E-C-F-R(P)/CFR245-55a on Cessna 208, 208B equipped with andwithout TKS de-icing system or electric de-icing system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to MT-Propeller Master Documentation List No. E-2110, Rev 0To be operated in accordance with MT-Propeller AFM-S Document No.E-2094, Rev 1or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No. E-2095, Rev 2,or later Revisio...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	21/12/2016	Active	10039667
10039669	NORTHERN AVIONICS S.R.L.			AW109SP	Installation of In-flight Entertainment System (IES) (composed by KitPIN KNAV-419 and KNAV-442).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Bulletin NAV-442 Rev. 0, dated May 2012.	None.	16/05/2012	Active	10039669
10039703	ACS-NAI Ltd.		TCCA STC NO. C-LSA12-038/D	BD-700-1A10	Installation of Complete Custom Aircraft Interior - ASN 9434	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	TCCA STC No. C-LSA12-038/D Issue 1, dated 30 April 2012.Aero Consulting Services Ltd Configuration Definition List H282000Revision NC.Aeroplane Flight Manual Supplement H282090, Revision N/ C.Instructions for Continued Airworthiness for theinstallation, CompleteCustom Aircraft Interior, 35-027E300 R...	Restricted to ASN 9434.The Wireless Local Area Network (WLAN) system is intended to provideinternet connectivity and email services to the airplane's cabin usingportable devices (PEDs). Any other intended function of this equipmentwill require a re-examination of the certification basis.	18/05/2012	Active	10039703
10039704	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	EC 135 P1	Cabin ConfigurationInstallation of equipment rack and pedestal mounted LCD monitor in theforward cabin, as per ECD design change EC UK/135/2043	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EC UK RFM Supplement Nº59, dated 10 May 2012or later revisions of the above listed documents approved by EASA.- Design Report Nº DR/1352043-001, Issue B, dated 09 May 2012- Instructions for Continued Airworthiness ICAW/ 1352043-001	None	18/05/2012	Active	10039704
10039705	SABENA TECHNICS BGC			A330-223 / -243 A330-201 / -202 / -203	Panasonic eXPhone System activation on A330 with eXConnect and Rack P/NRD-AA903023This STC installs a Panasonic eXphoneSystem allowing, in conjunctionwith other devices, the use of cellphones during flight.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-,,CS 25 Amendment 4-,,CRI H-01 Issue 1 - Enhanced Airworthiness Programme for AeroplaneSystems - ICA on EWIS-,,CRI F-01 Issue 1 - Mobile...	Master Data List, Ref : 0585-01-A-2103-R00, dated 15 May 2012;Instruction for Continued Airworthiness, Ref : 0585-01-A-2211-R00, dated06 April 2012;Aircraft Flight Manual Supplement, Ref : 0585-01-A-2301-R00, dated 16May 2012;or later revisions of the above listed documents approved by EASA.	None.	18/05/2012	Active	10039705

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039706	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02923CH	737-600/-700/-800/-900/-900ER	Validation of FAA STC ST02923CH: EFB Installation of ECS EZMountTMMechanical Mounting Assemblies	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-,,Master Data List ECS-209276, Revision C, dated 26 January 2011-,,AFM Supplement ECS-209177, Initial release, dated 11 February 2011-,,EWIS Assessment ECS-209278, Revision A, dated 26 January 2011-,,ICA ECS-209223, Revision A, dated 7 January 2011-,,Weight and Balance Manual ECS-209277, Revision2...	1) This approval constitutes approval for the EZMountTM MechanicalMounting Assemblies only. The capability of any system attached to theEZMountTM Mechanical Mounting Assembly requires additional EASAapproval.2) The maximum allowed weight of any device to be attached to eachEZMountTM Mechanical Mount...	18/05/2012	Active	10039706
10039707	AIRBUS HELICOPTERS ITALIA S.R.L.	REV. 1		AS 365N2 AS 365 N2	Initial revision:Installation of Audio Voice Warning on Radar Altimeter Thales AHV-8(ref. Change HI-365-34-01) Revision 1: Transfer of Certificate for New Company Ownership.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Rotorcraft Flight Manual Supplement HI 365-34-01 FMS Rev.1 dated 16thJanuary 2012.Master Document List HI-365-34-01-MDLRev.02 dated 14th February 2012.Installation of Change HI-365-34-01-INS Rev.02 dated 14th February 2012.Instruction forContinued Airworthiness HI-365-34-01-ICA Rev.1 dated16th Jan...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limited to S/N 6414.	10/06/2025	Active	10039707
10039715	JET AVIATION AG, BASEL			FALCON 2000	WLAN activationFor WLAN working in the 2.4 GHz frequency band	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Data List, Doc. No. BF2TH23262-001, Rev. IR, 20.04.2012- AFMS, Doc. No. BF2TH23262-201-01, Rev. IR, 29.02.2012- ICA, Doc. No. BF2TH23262-150-01, Rev. IR, 27.02.2012or later revisions of the above listed documents approved by EASA.		24/05/2012	Active	10039715
10039716	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SR02982CH	AW109SP	Installation of equipment rails and mounts.EASA STC 10039716 Rev.1 reflects the transfer of EASA STC 10039716 fromSNAKYCREEK ENTERPRISES, LLC d/b/a/ SPECTRUM AEROMED to SPECTRUMAEROMED, LCC d/b/a SPECTRUM AEROMED.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. RSG AeroDesign Master Document List 00A02160002<(>,<)> No Revision,dated February 23 2011;2. RFM Supplement 19A0210001, dated June 15 2011;3. Instructions for Continued Airworthiness, Document No. 16A02160002,No Revision, dated April 192011;or later revisions of the above listed document(s) appr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2019	Active	10039716
10039717	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SR02981CH	AW109SP	Installation of a medical seat, fire extinguisher, utility track andcylinder mount.EASA STC 10039717 Rev.1 reflects thetransfer of EASA STC 10039717 fromSNAKY CREEK ENTERPRISES, LLC d/b/a/ SPECTRUM AEROMED to SPECTRUMAEROMED, LCC d/b/a SPECTRUM AEROMED.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. RSG AeroDesign Master Document List 00A02390001, No Revision, datedFebruary 23 2011;2. RFM Supplement 19A02390001, dated June 15 2011;3. Instructions for Continued Airworthiness, Document No. 16A02390001,No Revision, dated March 4 2011;or later revisions of the above listed document(s) approved/a...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2019	Active	10039717

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039718	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 2	FAA STC SR02974CH	A109S/ AW109SP	Installation of Air Ambulance Conversion.Rev.1 reflects thetransfer of EASA STC 10039718 from SNAKY CREEKENTERPRISES, LLC d/b/a/ SPECTRUM AEROMED to SPECTRUM AEROMED, LCC d/b/aSPECTRUM AEROMED.Rev. 2 allows installation of an Air Ambulance Conversion modificationin Leonardo S.p.a. (Agusta) model A1...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Spectrum Aeromed Master Drawing List 7011DL, Revision 4,dated 29 May2014, or later approved revisions.2. Flight Manual Supplement 7011 FMS, Revision 3<(>,<)> dated 30 July2014, or later approved revisions.3. Instructions for Continued Airworthiness, Manual 7011MM, Revision 5,dated 29 May 2014, o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/04/2020	Active	10039718
10039719	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SR02978CH	AW109SP	Installation of shore power mechanical provisions.EASA STC 10039719 Rev.1 reflects the transfer of EASA STC 10039719 fromSNAKY CREEK ENTERPRISES, LLC d/b/a/ SPECTRUM AEROMED to SPECTRUMAEROMED, LCC d/b/a SPECTRUM AEROMED.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. RSG AeroDesign Master Document List 00A02240001, No Revision, datedFebruary 23<(>,<)> 2011;2. Instructions for Continued Airworthiness, Document No. 16A02240001,No Revision, dated April 19< (>,<)> 2011;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accorda...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2019	Active	10039719
10039720	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SR02977CH	AW109SP	Installation of a medical floor liner.EASA STC 10039720 Rev.1 reflects the transfer of EASA STC 10039720 fromSNAKY CREEK ENTERPRISES, LLC d/b/a/ SPECTRUM AEROMED to SPECTRUMAEROMED, LCC d/b/a SPECTRUM AEROMED.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. RSG AeroDesign Master Document List 00A02160003, No Revision, datedFebruary 23 2011<(>,<)>2. instructions for Continued Airworthiness, Document No. 16A02160003,No Revision, dated April 19 2011;or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2019	Active	10039720
10039721	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SR02980CH	AW109SP	Installation of an interior panel system.EASA STC 10039721 Rev.1 reflects the transfer of EASA STC 10039721 fromSNAKY CREEK ENTERPRISES, LLC d/b/a/ SPECTRUM AEROMED to SPECTRUMAEROMED, LCC d/b/a SPECTRUM AEROMED.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. RSG AeroDesign Master Document List 00A02160001, No Revision, datedFebruary 23 2011<(>,<)>2. Instructions for Continued Airworthiness, Document No. 16A02160001,No Revision, dated April 19 2011;or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2019	Active	10039721
10039722	EMBRAER ENGINEERING & TECHNOLOGYCE NTER USA, INC.	REV. 1	FAA STC ST00013IB	EMB-135BJ	Installation of an Enflite Refrigerator“Note:This STC is revised at Rev. 1 in order to record the transfer of theoriginal ANAC STC No. 2009S10-20 to a United States based DesignApproval Holder.”	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Master Document List ref. TR0152 Rev. F dated 14 November 2018-FAA STC No. ST00013IB, reissued on 4 November 2019or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Nnone	05/01/2021	Active	10039722

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039731	FIELD AVIATION COMPANY Inc.		TCCA STC C-LSA12-017/D	DHC-8-202	Fleet Standardization ModificationTCCA STC C-LSA12-017/D, Issue 1	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS).The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and rema...	Installation must be in accordance with TCCA approved FieldAviationMaster Data List 25440000, Rev. IR, dated 26 March 2012;Maintenance of the Fleet Standardization Modification Installation mustbe in accordance with Field Aviation Maintenance Manual Supplement25443100, Rev. IR, dated 22 December 20...	The modification is limited to Serial numbers 435, 440 and 441.	21/05/2012	Active	10039731
10039755 (EASA.A.S.00504)	ROEDER PRAEZISION GMBH	REV. 2		A330-322	Cabin reconfiguration from a 387 Y/C layout to a 18 B/C + 331 Y/Clayout.This STC installs a new cabin arrangement with in-seat video andadditional galley installations.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.As per EASA TCDSA. 004.Elect to Comply with CS25 (Original Issue) requirements: 25.811 (d) / 25.812 (d) (e) / 25.813 (a) (b) (e) / 25.851(...	Master Document List, ref. MDL330-25-01-04 Revision 1, dated 09 Dec.2004<(>,<) >or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	15/06/2018	Active	10039755
10039763 (EASA.IM.R.S.0153)	TECH-TOOL PLASTICS, Inc.	REV. 1		MBB-BK 117 C-2 MBB-BK 117 C-1 MBB-BK 117 B-2 MBB-BK 117 B-1 MBB-BK 117 A-4 MBB-BK 117 A-3 MBB-BK 117 A-1	Installation of Tech-Tool Plastics, Inc.Replacement Windowsin EUROCOPTER MBB-BK 117Installation of windows in accordance with Tech-Tool Plastics, Inc.Master Drawing List No. BK117-1000-100 i.a.w. FAA STC No. SR02867AT	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Tech-Tool Plastics, Inc. Master Drawing List No. BK117-1000-100, dated23 September 2003, or later approved revisions.	None.	22/05/2012	Active	10039763
10039764	BOMBARDIER INC.		TCCA STC SA12-16, ISSUE 2	BD-700-1A10	Installation, Aircraft Completion Modifications - ASN 9440.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-16 Issue 2 dated 20 March 2012;Bombardier Configuration Definition Record RAZ-BM700-001 Revision Edated 09 May 2012;Bombardier Airplane Flight ManualSupplement G-FM25054001 RevisionBASIC;Instructions for Continued Airworthiness document GC94400000-ICA;or later revision...	Restricted to ASN 9440.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs). Any other intended function of this equipmentwillrequire a re-examination of the certification basis.	22/05/2012	Active	10039764
10039781	AERO PACIFIC		FAA STC SR01688LA	206L-1, 206L-3, 206L-4, 407 206, 206A, 206B, 206B-1, 206L	Installation of Aero Pacific Belly Utility Mount AP206UM02(Validation of FAA STC SR01688LA)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- RFM Supplement N °AP206-UM02-10, issued March 22, 2005or later revisions of the above listed documents approved by EASA-,,Master Drawing List N°20602, Revision A, dated February 1, 2005-,,AML N° SR01688LA-,,Instructions for Continued Airworthiness P/N AP206UM02-ICA, doc N°206UM02-02, dated 12/14/04...	- This Belly utility Mount Installation is approved for a maximum weightof not more than 150 pounds and a frontal area of 2.5 square feet.- This STC only addresses structural, performance and handling qualitiesrequirements. No system or electrical requirements are specified.Placement of the actual e...	23/05/2012	Active	10039781
10039783	PREMIAIR AIRCRAFT ENGINEERING		CAA UK RESPONSIBILITY	A-60+	Installation of Cabin Safety Equipment	The Certification Basis for the original product remains applicable tothis certificate/ approval.	- Certification Program 12-007, Issue 3, 8 May 2012- Change/Repair amendment Form 12-007, Issue 2, 8 May 2012- Technical Report 12-007-002-002, Issue 2, 8 May 2012- Technical Report 12-007-002-006, Issue 1, 16 April 2012	None	23/05/2012	Active	10039783

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039788	TECH-TOOL PLASTICS, Inc.	REV. 1	FAA STC SH8755SW	AS 355 N AS 355 F2 AS 355 F1 AS 355 F AS 355 E	Installation of aft Cabin Comfort Windows	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List No. 3501CC-2027-100, Rev A, dated 02/04/12	none	25/05/2012	Active	10039788
10039789	TECH-TOOL PLASTICS, Inc.		FAA STC SH8754SW	AS 350 D AS 350 BA AS 350 B3 AS 350 B2 AS 350 B1 AS350 B	Installation of aft Cabin Comfort Windows	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List No. 3501CC-2027-100, Rev A dated 02/04/12	none	23/05/2012	Active	10039789
10039790	BOMBARDIER INC.		TCCA STC Q-LSA00-009/D ISSUE 1	BD-700-1A10	Transport Canada STC No. Q-LSA00-009/D - Installation of Interior andAvionics.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. Q-LSA00-009/D Issue 1 dated 23 June 2000.Modification List ML100569 for the Interior and Avionics Installationinto Bombardier Global Express BD-700-1A10, Revision B, dated 22 June2000.-,,BD700-BCCM-546 Rev A - FMS - Gaseous Oxygen System-,,BD700-BCCM-547 Rev NC - FMS - Smoke...	Restricted to ASN 9028.Installation of EASA STC No. 10039791 is a pre-requisite.	23/05/2012	Active	10039790
10039791	BOMBARDIER INC.		TCCA STC C-LSA12-040/D ISSUE 1	BD-700-1A10	Installation, Modifications to Interior Completion - ASN 9028.	The Certification Basis for the original product remains applicable tothis certificate/ approval .The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. C-LSA12-040/D Issue 1 dated 10 February 2012.ACS-NAI Ltd. Modification Data Summary H224000 Revision NC.Instructions for Continued Airworthiness document 9028-ICA Revision NC.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision...	Restricted to ASN 9028. Installation of EASA STC No. 10039790 is apre-requisite.	23/05/2012	Active	10039791
10039792	BOMBARDIER Inc.	REV. 2	TCCA STC LSA01-329 ISSUE 3	BD-700-1A10	Seating Limitations for Aft RHS DivanThe TCCA LSTC was revised to allow for Occupation of Divans Center andAft Seats During Taxi, Take-off and Landing in all Operations.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Approved - Aero Consulting Services Flight Manual Supplement D00691Revision A.Accepted - Aero Consulting Services Modification Data Summary NumberD00600 Revision B.or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationPro...	Restricted to ASN 9028Previous installation of EASA STC no.10039790 and EASA STC no. 10039791are pre-requisites.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introdu...	14/02/2020	Active	10039792

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039798	LUFTHANSA TECHNIK AG	REV. 1		B747-8	Installation of class 2 EFB docking station with display, cockpit doorsurveillance cameras an taxi aid cameras at vertical stabilizer and atfuselage belly.	The Certification Basis for the original product and the followingadditional oralternative airworthiness requirements are applicable to thiscertificate/ approval.CS25 Amendment 5 Appendix H25.5 (EWIS)The requirements for environmental protection and the associatedcertificated noiseand/ or emissionsr...	Aircraft Flight Manual Supplement A-00-12-15-AFM - Issue 01,Instructions for Continued Airworthiness A-00-12-23-ICA - Issue 01,Modification Document STDD46-11/13M Issue01, Certification programCP46-11/13M issue01, or later revisions of theabove listed documentsapproved by EASA.	Only for EFB installation. No installation of the belly andtail fincamera in the frame of this STC.	17/07/2012	Active	10039798
10039808	BOMBARDIER INC.		TCCA STC SA12-16, ISSUE 2	BD-700-1A11	Installation, Aircraft Completion Modifications - ASN 9453	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-16 Issue 2 dated 20 March 2012;Bombardier Configuration Definition Record RAZ-BM700-001 Revision Ddated 04 May 2012;Bombardier Airplane Flight ManualSupplement G-FM25054001 RevisionBASIC;Instructions for Continued Airworthiness document GC94530000-ICA;or later revision...	Restricted to ASN 9453.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs). Any other intended function of this equipmentwillrequire a re-examination of the certification basis.	24/05/2012	Active	10039808
10039812	STC TWENTY ONE LIMITED	REV. 4	CAA UK RESPONSIBILITY	737-900/ 737-900ER 737-600/ 737-700/ 737-800 737-300/ 737-400/ 737-500	Activation of a Controller-Pilot Data-Link Communications [CPDLC]capability on Spectralux "D-LINK" ACARS VDL Mode 2 transceiver.Revision 4 addition of 737-900 and 737-900ER in theapplicability list.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Programme S21.PROG-0813, Issue 3, dated 12 February 2012-Compliance Check List, S21.CCL, Issue 2, dated 22 February 2012-Master Data List S21.MDL-0813, Issue 1, dated 19 April 2012-AFM Supplement S21.FMS-0069, Issue 3, dated7 March 2013or later revisions of the above listed documents...	This change is applicable to aircraft with CPDLC provisionsor anexisting Spectralux DLINK with ACARS function previously installed bySTC Twenty One.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installe...	25/03/2020	Active	10039812
10039843	OGMA, INDUSTRIA AERONAUTICA DEPORTUGAL, S.A.			EMB-145LU EMB-145LR EMB-145EU EMB-145EP	Nespresso Coffe Maker InstallationDescription as per ChangeDossier, ref. 11P05CD00001 initial issue<(>,<)> dated 23th May 2012.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Change Dossier, ref. 11P05CD00001 initial issue, dated 23thMay 2012;or later revisions of the above listed documents approved by EASA.	Applicability for the following S/N: 145076, 145084, 145129, 145135,145147<(>,<)> 145242, 145258.	29/05/2012	Active	10039843
10039850	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	EC 635 T2+ EC 635 T1 EC 635 P2+ EC 135 T2+ EC 135 T2 EC 135 T1 EC 135 P2+ EC 135 P2 EC 135 P1	BOND/MOD/060 "Martin- Baker Rotating Seat Installation, EC 135"	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS 27 Amendment 2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	- Rotorcraft Flight Manual Supplement FMS/060-002, dated May 3rd, 2012;or later revisions of the above listed documentsapproved by EASA.- Design Report DR/060-001, Issue 1, datedMay 3rd 2012.- Drawing List DL/060-099, Issue 1- Instructions for Continued Airworthiness ICA/060-008, Issue 1	None.	29/05/2012	Active	10039850
10039852	FLYING COLOURS CORP.		TCCA STC NO. SA12-33	CL-600-2B19	Installation, Aft Equipment Bay Tow Bar Stowage Provisions	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. SA12-33 Issue 1 dated 11 April 2012.ACS-NAI Ltd. Modification Data Summary H477000 Revision NC.Flying Colours Corp. Instructions for Continued Airworthiness for theInstallation, Tow Bar Stowage Provisions, H477071-ICA Revision NC.or later revisions of the above listed docume...	none	30/05/2012	Active	10039852

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039855	AIRBUS HELICOPTERS, Inc.		FAA STC SR09137RC-D	EC 135 T2+, EC 135 P1 EC 135 T1, EC 135 T2 EC 135 P2, EC 135 P2+	Installation of an Extended Right Hand side Instrument Panel inaccordance with AEC Drawing List 135A82-8020.This EASA STC is based on validation of FAA STC SR09137RC-D (Amdt.10-May-2012) iaw the TIP.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,AEC Drawing List 135A82-8020, No Revision, dated 07/05/01or later revisions of the above listed documents.	none	30/05/2012	Active	10039855
10039894	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS LTD	REV. 1	CAA UK RESPONSIBILITY	A330-243	Revise the passenger seat place cabin configuration from8FC/24JCL/183YCL (215 pax) to 8FC/247YCL (255 pax) passenger placestogether with associated changes to the complete aircraft interior.Installation of 64 passenger places of newly manufactured Sicma Aero -3541 series Economy Class seats into Row...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.A330 EASA TCDS A. 004The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the or...	Modification Compliance List Issue A, dated 30th May 2012Modification Summary MOD-1083 Issue A, dated 29th May 2012or later revisions of the above listed documents approved by EASA	None	31/05/2012	Active	10039894
10039903	S-TEC CORPORATION		FAA STC SA09540 AC-D	A99A, B99, C99	Installation of S-TEC system 30 two axis Automatic Flight GuidanceSystems (ST-923), in accordance with Master Data ListNo. ST-923-L-0001,Revision A, dated 24-Aug-06 or later FAA approved revision (28V -System).	The Certification Basis of the original product remains applicable tothis changeThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-FAA approved S-TEC Master Data List No. ST-923-L-0001, Revision A,dated 24-Aug-06 or later FAA approved revision.- FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement No. ST-923-M-0001 Revision-, dated 23-Aug-2006 orlater FAA approved revision.- Instruction for Conti...	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s).If the holder agrees to permit another person touse this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.	31/05/2012	Active	10039903
10039911 (EASA.A.S.03922)	LUFTHANSA TECHNIK AG			777-200 AS PER 777-EB-21-0228	STDD 21-09/02M: B-777-200 - Zonal Drying System Installation	The Certification Basis for the original product and the followingadditional oralternative airworthiness requirements are applicable to thiscertificate/ approval.CRI H-1 ICA for EWISThe certificated noise and/ or emissions levels of the original productare unchangedand remain applicable to this cert...	STDD 21-09/02M Iss. 01, Rev 00 dtd. May 25, 2012-Instructions for Continued Airworthiness A-00-12/14-ICA Iss. 02 Rev.IR dtd. May25, 2012or later revisions of the above listed documents approved by EASA	none	01/06/2012	Active	10039911
10039917	AEROTEC & CONCEPT			210N	Installation of a Garmin G500 EFIS, two Garmin GNS 430 W systems andassociated GA 35 GPS antennas, a Garmin GTX 330 mode S transponder, aGarmin GMA 340 audiopanel, a Honeywell KN62A DME receiver, a HoneywellKR 87 ADF receiver and associated KA 44B antenna.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS 23The Certificated noise and/or emissions levels of the original productare unchanged and remain applicable to this certificate/ appro...	Aerotec Flight Manual Supplement Nr. AE11094SMV revision 2 dated21/05/2012;Aerotec Instructions for continued airworthiness Nr. AE11094IPMNrevision 1 dated 10/02/2012;Aerotec Master Data List Nr. AE11094MDL revision 0 dated 22/05/2012;or later revisions of the above listed documents approved by EASA...	This STC is limited to aircraft s/n 62969.This avionics installation is approved for BRNAV operations withcoupling to S-TEC 55X autopilot.The aircraft must be equipped with:- back-up airspeed, altitude, attitude, magnetic heading and navigationindicators independent from the G500 display system<(>,<...	01/06/2012	Active	10039917
10039929	AEROLITE AG	REV. 3		AW119MKII A119, AW109SP A109N, A109S A109K2, A109LUH A109C, A109E A109, A109A, A109AII	EMS Equipment P/N 109-0008662-501This major change to the EASA STC 10039929 Rev. 2 includes the followingmodifications:- Extends the existing and approved EMS Equipment P/N 109-0008662-501installation to A109S-helicopters equipped with Trekker kit LHD P/N109G0000F01.- Add one Stretcher configuration...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Program CPR-19-052- Issue BMaster Document List MDL- 12-001- Issue C dated 09-09-2020Flight Manual Supplement FMS-109-0008662-501-Issue BOperations Manual OPM-109-0008662-501-Issue C dated 01-09-2020Declaration of compliance-DEC-EASA 60073278- N/C dated 02-10-2020 orlater revisions of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/10/2020	Active	10039929

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10039936	LEES AVIONICS Ltd.		CAA UK RESPONSIBILITY	BN2B-21, BN2B-26, BN2B-27 BN2A-9, BN2B-20, BN2A-27, BN2A-8, BN2A-20, BN2A-21, BN2A-26,	Garmin G600 PFD/ND.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS23 Amendment 2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	Master Data List: MDL-1260 Issue 1 dated 31May12;Change Statement: CS-1260 Issue 1 dated 31May12;Flight Manual Supplement: AFMS-1260 Issue 1;or later revisions of the above listeddocuments approved by EASA.	None.	04/06/2012	Active	10039936
10039943	AMAC AEROSPACE SWITZERLAND AG			A319-133	Interior RefurbishmentBy:- Carpet and Curtain replacement- Seat re-upholstery- Replacement of 4 double seats by 2 L-Shape Divans- VCC (IFE) Cabinet relocation- IFE upgrade- Additional Power Outlets installation- Emergency Equipment replacement	JAR 25, Chg.: 11, except as noted in TCDS EASA.A.064The Certification Basis for the original product remains applicabletothis certificate/ approval.The certificated noise and/ oremissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Data List, Doc. No. MDL-CF01-2500, Rev. B, dated, 01.06.2012;- AFMS, Doc. No. AFMS-CF01-2500, Rev. A, dated 01.06.2012;- ICA, Doc. No. ICA-CF01-2500, Rev. A, 31.05.2012;or later revisions of the above listed documents approved by EASA.	S/N: 1335 ,,A7-HHJ	04/06/2012	Active	10039943
10039944	AEROLITE AG	REV. 1	LBA STC RC 1240	MBB-BK117 C-2	Change to LBA STC No.RC 1240 on EMS Equipment P/N 145170-501:Addition of variant P/N 145169-501This change introduces:EMS variant P/N 145169-501 composed by:- Introduction of the new Cargo Platform Inst. P/N 145-0000835-501- Introduction of the new Cover Inst. P/N 145-0001005-501- Removal of Medical...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	For EMS Equipment P/N 145170-501: FMS-302 (Flight Manual Supplement) For EMS Equipment P/N 145169-501: FMS-509 (Flight Manual Supplement) or later revisions of the above listed documents approved by EASA.For EMS Equipment P/N 145170-501:OPM-302 (Operations Manual) EQL-302 (Equipment List) For EMS Equipm...	Not applicable	04/06/2012	Active	10039944
10039948	SOFINARE SOCIEDADE DEFINANCIAMENTOS E REPRESENTACOES SA			1900D	INSTALLATION OF TERRAIN AWARENESS AND WARNING SYSTEM (TAWS).	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Technical Documents to be Approved by EASA:-,,SOFINARE 21J.081.0869.003 Definition Document-,,SOFINARE 21J.081.0869.016AFM Supplementor later revisions of the above listed documents approved by EASA.-,,SOFINARE 21J.081.0869.010 ContinuousAirworthiness Instructions-,,SOFINARE 21J.081.0869.008 MEL A...	None (Applicable to All Models Beechcraft 1900D Airplanes)	04/06/2012	Active	10039948
10039983	FIELD AVIATION COMPANY Inc.		TCCA STC C-LSA12-006/D	DHC-8-202	RH Rear Facing Seat Installation.TCCA STC C-LSA12-006/D, Issue 1.	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation must be in accordance with TCCA approved FieldAviationMaster Data List 25410000, Revision A.Maintenance must be in accordance with TCCA accepted Field AviationAircraft Maintenance Manual Supplement 25413100, Revision IR.or later revisions of the above listed documents approved by EASAa...	The modification is limited to Serial numbers 435, 440 and 441 withpost-1990 Hunting or C<(>&<)>D interiors only.,,	05/06/2012	Active	10039983
10040003	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		B300 B200	Installation of Special Mission antennas and Drop Tube in accordancewith Certification documents 2069789 DOC, at issue 3, dated 18 August2016	The Certification Basis for the original product as amendedby thefollowing paragraphs apply:CS 23.1 amdt. 2, CS 23.29 amdt. 2, CS 23.49 amdt. 2, CS 23.63 amdt. 2,CS 23.149 amdt. 2,CS 23.301 amdt. 2, CS 23.303 amdt. 2, CS 23.305 amdt. 2, CS 23.307 amdt. 2, CS 23.335 amdt. 2, CS 23.337 amdt. 2, CS 23....	Approved Aircraft Flight Manual Supplement for Drop Tube installationDoc. 2069789-AM B, at issue 2, dated 18 July 2016or later revisions of the above listed documents approved by EASAAirplane Maintenance Manual Supplement Doc. 2069789-MM B, at issue 1,dated 15 July 2016	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/08/2016	Active	10040003

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040010	HELI-ONE (NORWAY) AS	REV. 5		EC 225 LP, AS 332 C1, AS 332 C	Installation of LH or RH or both Vertical Reference Door inaccordancewith modification AHSE-62230Rev. 4 is made for removal of a Flight Manual Supplement Limitation.Rev. 5 is made for addition of models AS 332 C and AS 332 C1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement H1NO-165 Rev. L dated 27.04.2018or later revisions of the above listed document(s) approved under theEASA system.Product Change Declaration AHSE-62230Declaration Of Compliance AHSE-62231 Rev. E dated 11.04.2018Up to Revision 4 of this STC:- Certification Program AHS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/05/2018	Active	10040010
10040043	E A D AEROSPACE AIRWORTHINESS	REV. 2		747-400	Swift broadband Satcom installation in accordance with Aerotec MasterData List AE11111MDL Rev 2, dated April 3, 2012	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-25 Amdt. 1 for areas of changeThe requirements for environmental protection and the associatedcertificated noise and/ or emissions leve...	- Master Data List AE11111MDL Rev 2, dated April 3, 2012- IPC Supplement 01367-IST-A-IPC-02 Rev A- AMM Supplement 01367-IST-A-AMM-01 Rev D- WDM Supplement DWG290-00222 Rev Bor later revisions of the above listed documents approved by EASA.	S/N: 30885, 32337, 32338, 32339, 32340, 28757, 29406	30/07/2015	Active	10040043
10040057	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.	REV. 2		P.68 TC (OBSERVER) P.68 R (VICTOR), P.68 (VICTOR) P.68 OBSERVER, P.68 OBSERVER2 P.68 C, P.68 C-TC P.68 B (VICTOR) AP68TP-600 (VIATOR) AP68TP-300 (SPARTACUS)	Installation of Aspen EFD 1000 Pro EFIS and Mid Continent MD41annunciator according to SEAM modification n° 2622/11.Revision 2 extending applicability to all models of P68 aircraft typethrough SEAM modification n° 4001/12.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Data list n° SEAM 2622 SDL revision 3 dated 259/05/2012Modification approval sheet n° 4001/12 revision 0 dated 03/12/2012or later revisions of the above listed documents approved by EASA	Initial installation of this design change must be performed byauthorised SEAM technical personal.This installation is approved for BRNAV operations with coupling toGarmin GNS 430 or GNS 430 W system and to Century III autopilot.The modified airplane must be equipped with altitude, airspeed,altitud...	12/03/2013	Active	10040057
10040082	NORTHWEST AEROSPACE TECHNOLOGIESINC.			B747-400	Interior Reconfiguration of VAA 747-400 Aircraft: Cabin Configurationand Passenger Amenities Upgrade and Standardization in accordance withNAT Master Data List N0377-D10 Rev. B , dated May 22, 2012	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI H-01 Enhanced Airworthiness Programme for Aeroplane SystemsThe requirements for environmental protection and the associatedcertificat...	N0377-D10 Rev B, dated May 22, 2012 Master Data List;N0377-D70 Rev. A, dated March 6, 2012 Instructions for ContinuedAirworthiness - Principle Manual for the Interior Reconfiguration ofVirgin Atlantic Airways (VAA) Boeing 747-400 Aircraft;N0377-D71 IR, dated February 20, 2012 Supplement to VAA Aircr...	A/C serial numbers: 30885, 32337, 32338, 32339, 32340, 28757 and 29406.	12/06/2012	Active	10040082
10040102	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02903NY-D	B747-400	Installation of Panasonic eX2 In-Flight Entertainment system witheXPhone in accordance with Delta Engineering Master Data list0107-07608-2280 Rev. E, dated September 13, 2012 or later FAA approvedrevisions.Validation of FAA STC ST02903NY-D.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:Section ,,Title ,,,,,,,,,,,,,,At Amendment§25.831 ,,Ventilation , ,,,,,,,,,,, 25-89§25.853 ,,Compartment interiors ,,,,,,,,25-116§25.869 ,,...	0107-07608-2280.Rev E, dated September 13, 2012 Master DataList; 0107-07609-2280 Rev. B, dated August 5, 2012 Instructions for ContinuedAirworthiness for Panasonic eX2 IFE system; 0607-07662-2280 Rev. A, dated September 6, 2012 Airplane Flight ManualSupplement;or later revisions of the above listed d...	The Panasonic eXPhone system must interface with the following existingsystems/ components which must be installed in a manner acceptable to theauthorities. The below listed required existing systems are not approvedby this STC.Required Supplemental Type Certificate covering the interface withexistin...	30/10/2012	Active	10040102
10040161	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			B90, C90, E90	Installation of a Garmin GTS 8xx series Traffic Advisory System	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appr...	AFM Supplement No SEAM 3747/11 Revision 2 dated 14/06/2012STC Data List No SEAM 3747/11 SDL Revision 4 dated 14/06/2012or later revisions of the above listed documents approved byEASA	Initial Installation of this design change must be performed byauthorized SEAM technical personnel.The modified aircraft must be equipped with:-TAS antennas installed according toSEAM modification No. 2465/11approved under EASA. 10014783-AGarmin G600 EFIS and a GNS 430/530 series systemThis STC cov...	14/06/2012	Active	10040161

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040166	JET AVIATION AG, BASEL			737-800	Iridium Antenna Structural Provisionsbetween fuselage station BS 727C & 727D	JAR 25 Change 13The Certification Basis for the original product remains applicable tothis certificate/ approval.SCs orESFs: Derogation to latest amendment (Part 21A.101):Do not materially contribute to safety.The certificated noise and/ or emissions levels of the original productare unchanged and...	Instructions for Continued Airworthiness Doc. No.BB73723266-150-01or later revisions of the above listed documents approved by EASA	none	26/06/2012	Active	10040166
10040171	BOMBARDIER INC.		TCCA STC NO. SA12-16	BD-700-1A10	Installation, Aircraft Completion Modifications - ASN 9450	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. SA12-16 Issue 2 dated 20 March 2012.Bombardier Configuration Definition Record RAZ-BM700-001 Revision Kdated 05 June 2012.Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC.Instructions for Continued Airworthiness document GC94500000-ICA.or later revisio...	Restricted to ASN 9450The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs). Any other intended function of this equipmentwill require a re-examination of the certification basis.	15/06/2012	Active	10040171
10040172	BOMBARDIER INC.		TCCA STC NO. SA12-16	BD-700-1A10	Installation, Aircraft Completion Modification - ASN 9441	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. SA12-16 Issue 2 dated 20 March 2012.Bombardier Configuration Definition Record RAZ-BM700-001 Revision Jdated 31 May 2012.Bombardier Airplane Flight ManualSupplement G-FM25054001 RevisionBASIC.Instructions for Continued Airworthiness document GC94410000-ICA.or later revision...	Restricted to ASN 9441.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs). Any other intended function of this equipmentwillrequire a re-examination of the certification basis.	15/06/2012	Active	10040172
10040176	KUERZI AVIONICS AG			B737-300	GSM mail tracker installation:a small GSM device integratedinto the aircraft and able to report itscurrent position bymeans of GSM cell information.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.- CRI F-01 (Special Condition/Interpretive Material) Issue 03 "Lithiumbatteries installation"The certificated noise and/ or emissions lev...	Project and Order Description POD-201033911 rev. BMaster Document List 201033911 rev. NCInstructions for Continued Airworthiness ICA201033911 rev. NCor later revisions of the above listed documents approved by EASA	None	18/06/2012	Active	10040176
10040181	STANDARD AERO		FAA STC SA02715CH-D	2. B200C 2. B200 1. 200C 1. 200	Installation of Pratt & Whitney PT6A-52 Engines in accordance withStandard Aero Master Data List document number 1016151, Revision "A",dated June 01, 2009 or later FAA approved revision.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval;as established by FAA STC SA02715CH-DThis certificate/ approval involves a change to the requirements forenvironmental protection and/ oro...	Airplane Flight Manual Supplement document number 1016494 Revision "A"dated June 08, 2009<(>,<)>Instructions for Continued Airworthiness document number 1016175,Revision "A"<(>,<)>TCDSN EASA.IM.A.277 records C10727 through C10730<(>,<)>or later revisions of the above listed documents approved by EAS...	None.	15/06/2012	Active	10040181
10040183	INTERNATIONAL ENGINEERINGAS SISTANCE (IEA)			F177RG	IEA/STC/ERHC/01/2010 revision 00 - Electric Rudder Hand Control.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS 23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appr...	Supplément au manuel de maintenance SUP-ERHC-MANUEL DEMAINTENANCE-CESSNA177RG-2010 issue D;Supplément au manuel de vol SUP-ERHC-MANUEL DE VOL-CESSNA177RG Issue G;or later revisions of the above listed documents approved by EASA.	Limitation to F177RG serial number 0016.	15/06/2012	Active	10040183

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040185	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03846AT	ATR 72-211/-212/-212A ATR 72-101/-102/-201/-202 ATR 42-200/-300/-320/-500	Installation of the IMS Flight Deck Ressources SkyTab 3201 ElectronicFlight Bag (EFB) System.This STC is installing theSkyTab 3201 EFB mount arm/device andelectrical supply, as well as a Satellite Weather Receiver together withits antenna.Revision 1 transferred from EMTEQ Engineering to B/E Aerospa...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List, ref. 2-68788-001 Revision G, dated 26 March 2012Instruction for Continued Airworthiness, ref. 2-68788-804 revision G,dated 26 March 2012EASA Aircraft Flight Manual Supplement, ref. 2-68788-850, dated 06 April2012or later revisions of the above listed documents approved by EASA i...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10040185
10040189	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	B757-200	Installation of VIP Bedroom and Bathroom	EASA.IM.A.205 at Issue 2.The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI D-01 SC for Isolated CompartmentsNon-significantThe requirements for environmental protection and the associ...	AeroDac Master Data List No. JN312 ADC17(1), Issue 2, dated14 June2012.Instructions for Continued Airworthiness Including EWIS ICA No. JN312ADC54-25(1) Issue 1or later revisions of the above listed documents approved by EASA	None	15/06/2012	Active	10040189
10040198	AIRBORNE TECHNOLOGIES GmbH			P2006T	Title: Provisions for radar operationDescription: Installation of a radome below the photogrammetric hatch,activation of the rear hatch (installed with EO-AT-047), installation ofa ventral fin, upgraded mission power supply system and removal of hatchdoors and hatch door mechanism (certified with ST...	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.	Change Dossier, STC-AT-044, Rev. 3Supplement to the AFM, AFM1-STC-AT-044, Rev. 2Supplement to the AMM, AMM1-STC-AT-044,Rev. 1Installation instructions, 044-II-STC-AT, Rev. 0or later revisions of the above listed documents approved by EASA	STC-AT-003 step 1 or step 3 and EO-AT-047 must be installedprior thismodification.	18/06/2012	Active	10040198
10040214	DELTA ENGINEERING CORPORATION		FAA STC ST02901NY-D	B747-400	Installation of a Panasonic eX2 In-Flight Entertainment System inaccordance with Delta Engineering Master Data List 0107-07459-2283Revision B, dated May 9, 2012 or later FAA approved revisionsValidation of FAA STC ST02901NY-D	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Section ,,Title ,,,,,,At Amendment§25.831 ,,Ventilation , ,,,,,,,,,,, 25-89§25.853 ,,Compartment interiors ,,,,,,,, 25-116§25.869 ,,Fire pro...	0107-07459-2283.Rev B, dated May 9, 2012 Master Data List0107-07464-2283 Rev. A, dated May 17, 2012 Instructions for ContinuedAirworthiness for Panasonic eX2 IFE system0607-07463-2283 Rev.- Airplane Flight Manual Supplement-or later revisions of the above listed documents approved by EASA inaccordan...	None	18/06/2012	Active	10040214
10040231	JET AVIONICS AVIATION & MARINESERVICE CENTER S.r.l.			PA-31T CHEYENNE II	General avionic improvement/installation - Replacement of GPS, MovingMap, Stormscope, Weather Radar system, TCAI I.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CAR 3 and CS 23.365, 561, 571, 573, 867, 1309, 1311, 1351, 1431, 1529initialamendment.The requirements for environmental protection andc...	Mater Drawing List BDI 001-10-01 Issue 19.03.2010, Maintenance ManualSupplement BDI 001-10-14 Issue 11.04.2011, Flight Supplement for GPS 155BDI 001-10-16/1 Issue 19 March 2010, Flight Manual Supplement for Sky497 BDI 001-10-16/2 Issue 19 March 2010;or later revisions of the above listed documents a...	None.	19/06/2012	Active	10040231
10040247	ROCKY MOUNTAIN AIRCRAFT	REV. 1	TCCA SA11-80 ISSUE 2	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of Universal Avionics CVR-120A/R or KAPTURE Cockpit VoiceRecorder with RIPS Option in accordance with Transport Canada STCSA11-80 Issue 2	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification Instruction E103110, Rev DMaintenance Manual Supplement E103131, Rev Eor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/04/2023	Active	10040247

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040249	CESSNA ZURICH CITATION SERVICE CENTGMBH	REV. 1		B300, B300C B200, B200C, B200GT, B200CGT	ADS-B-OUT ComplianceOut: Dual Collins TDR-94D Transponder Mode S P/N 822-9210-008In: Dual Collins TDR-94D Transponder Mode S P/N 622-9210-409 & 1 dualannunciator/switch ADS-B 1/ ADS-B 2 inhibit	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.SCs or ESFs: CS 23 for the changeThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicab...	Master Document List MDL-100 Rev. B 12.06.2012Instructions for continued Airworthiness ICA-100 Rev. A of 02.05.2012AFM Supplement FMS-100 Rev. IR of 22.05.2012or later revisions of the above listed documents approved by EASA	none	11/09/2012	Active	10040249
10040250	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA SR02217SE	EC635 T2+ EC635 T1 (CPDS), EC635 P2+ EC135 T2+, EC135 T3 EC135 T2(CPDS), EC135 T2+ EC135 T1(CDS), EC135 T1(CPDS) EC135 P3, EC135 T1, EC135 T2 EC135 P2 (CPDS), EC135 P2+ EC135 P1, EC135 P2, EC135 P2+ EC135 P1(CDS), EC135 P1(CPDS)	Cargo Hook KitInitial IssueInstallation of a Single Cargo Hook kit for non-human external cargo(NHEC) in accordance with Master Drawing List 155-170-00 and FAA STCSR02217SERevision 1Introduction of Dual Cargo Hook kit with PCDS components for carrying ofhuman external cargo (HEC) in accordance with1...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-For initial STC:- Master Drawing List 155-170-00 Revision 1- Rotorcraft Flight Manual Supplement 121-057-00 Revision 0- Owner's Manual 120-143-00 Revision 1- Instructions for Continued Airworthiness (ICA) 123-037-00 Revision 0- Component Maintenance Manual 122-025-00 Revision 0For Revision 1:- Mast...	For initial STC:Limited to helicopters with CDS/CPDS cockpit variants.Limited to helicopters equipped with cargo hook assembly P/N AS22-44.For Revision 1:Limited to helicopters with CDS/CPDS cockpit variants.Limited to helicopters equippedwith Siren cargo hook P/Ns AS21-8-B,AS22-52-21, or AS21-17.P...	20/12/2022	Active	10040250
10040254	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	B757-200	Passenger cabin reconfiguration on Openskies B757	The original Certification Basis was updated by CRI H-01 (EnhancedAirworthiness Programme for Aeroplane system Instruction for ContinuedAirworthiness on EWIS) and CRI D-03 (Cabin layout-distribution ofpassenger seats – Interpretative Material)	H4ACP079 - Certification PlanH4ADR689 - Emergency Evacuation ReviewH4ADR724 - Enhanced Zonal Analysis procedureH4AFMS0027 - Flight Manual Supplement757ME25200233 - Certification Review DrawingH4A1491 - Modification SummaryH4ACCL552 - Compliance Checklist	None	20/06/2012	Active	10040254
10040256	BOMBARDIER INC.		TCCA STC NO. SA12-16	BD-700-1A10	Installation, Aircraft Completion Modifications - ASN 9455.	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. SA12-16 Issue 2 dated 20 March 2012.Bombardier Configuration Definition Record RAZ-BM700-001 Revision Ndated 12 June 2012.Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC.Instructions for Continued Airworthiness document GC94550000-ICA.or later revisio...	Restricted to ASN 9455.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs). Any other intended function of this equipmentwillrequire a re-examination of the certification basis.	21/06/2012	Active	10040256
10040257	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOFFICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	777-200	B777 TCAS Change 7.1 update	CS25 Amendment 11The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	Master Data List BA-777-34-0003-MDL Issue 00, dated 20 March 2012.or later revisions of the above listed documents approved by EASA	none	21/06/2012	Active	10040257
10040290	CESSNA ZURICH CITATION SERVICE CENTGMBH			B300, B300C B200, B200C, B200GT, B200CGT	Mini Quick Access Recorder (QAR) InstallationIn: Single or Dual Avionica P/N 804-1205 miniQAR Mk III	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appr...	Master Document List MDL-102 Rev. B 12.06.2012Instructions for Continued Airworthiness ICA-102 Rev. N/C of 16.04.2012orlater revisions of the above listed documents approved by EASA	None	22/06/2012	Active	10040290

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040294	DART AEROSPACE USA, Inc.	REV. 1	FAA STC SR02024SE	A119, AW119MKII	Validation of FAA STC SR02024SE: D119-646 Replacement Sikdtube Ins.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC SR02024SE dated 11 August 2009MDL-D119-646 Rev. GICA-D119-646 Rev. 1IIN-D119-646 Rev. Bor later revisions of the above listed documents approved by EASA inaccordance with EASAED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	06/07/2012	Active	10040294
10040295	NORTHWEST AEROSPACE TECHNOLOGIESINC.			B777-300ER	N0401: Certification of Deployment of In-Seat Video Monitors DuringTaxi, Take-Off and Landing - Business Class Seats onCathay PacificB777-300(ER) Aircraft	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI H-1 - ICA onEWIS	N0401-D90, Revision -, dated June 6, 2012 - Certification Summary forthe Deployment of In-Seat Video Monitors During Taxi, Take-Off andLanding - Business Class Seats on Cathay Pacific B777-300 (ER) Aircraftor later revisions of the above listed documents approved by EASA	Limited to 777-300ER as per EO 20N00968	22/06/2012	Active	10040295
10040296	BOMBARDIER INC.		TCCA STC NO. SA12-16	BD-700-1A10	Installation of Aircraft Completion Modifications - ASN 9437.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-16 Issue 2 dated 20 March 2012;Bombardier Configuration Definition Record RAZ-BM700-001 Revision Ldated 11 June 2012;Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC;Instructions for Continued Airworthiness document GC94370000-ICA;or later revisio...	Restricted to ASN 9437.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs). Any other intended function of this equipmentwillrequire a re-examination of the certification basis.	22/06/2012	Active	10040296
10040305	DELTA ENGINEERING CORPORATION	REV. 1	FAA ST03085CH	747-400	Installation of provisions for Panasonic Global Communications Suite(GCS) System.Rev.1: STC Transfer from Armstrong Aerospace Inc. to Delta EngineeringCorporation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Regulations at the latest amendment FAR Part 25-0 through 25-119:25.23(a)-(b); 25.29(a)-(b); 25.111(a)-(d); 25.113 (a)-(c); 25.121(a)-(d);25.123(a)-(c); 25.147(a)-(f); 25.1...	- DC104-9027-00 Rev. D, Master Data List dated April 25, 2012.- DC113-9027-00 Rev. C, Instructions for Continued Airworthiness,Section 2 “Airworthiness Limitations”, dated February 23, 2012.- DC303-9027-00 Rev. “-”, Airplane Flight Manual Supplement, dated April23 2012;or later revisions of the abov...	• These provisions are for a Panasonic Global Communications Suite (GCS) System. The installation and activation of theGCS system is to be in accordance with a separate approval.Additionalapproval is required for the installation of additional GCS systemequipment and for the activation of these pr...	07/06/2017	Active	10040305
10040318	SWS CERTIFICATION SERVICES Ltd.	REV. 2	CAA UK RESPONSIBILITY	A340-312	This modification covers:- Installation of Recaro 3410 785 Economy (E/C) seats and Avio BusinessClass (B/C) seats, fitted with Panasonic EX2 IFE, onto TAP A340-300aircraft.- Installation of AmSafe Airbag System to demonstrate compliance toCS25.562(c)(5) when the Panasonic eX2 seatback monitor is ins...	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Compliance Report 3091-COM-01 Issue 1<(>,<)> dated 12 Oct2012.- Maintenance Manual 3091-MMS-01 Issue 1, dated 12 Oct2012.- Declaration of compliance SWS-C-3091 Issue A, dated 16 Oct 2012.or later revisions of the above listed documentsapproved by EASA	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	30/04/2013	Active	10040318
10040330	STG AEROSPACE Inc.AKA SAFTGLO, Inc.	REV. 1	FAA STC ST03684AT	777-200/300/300ER	Validation of FAA STC ST03684AT (Installation of SafTGloPhotoluminescent Escape Path Marking System)	The Certification Basis for the original product remains applicable tothis certificate/ approval.	FAA STC ST03684AT, Amendment November 3, 2011STG report AC37-2 Rev. F (Master Drawing List)AFM supplement AC37-11 Rev. B (Airplane Flight Manual Supplement) Or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04//CF (or subsequent revisions ofthis...	none	25/07/2012	Active	10040330

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040333	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		P.68 OBSERVER 2 P.68 OBSERVER P.68 C	"External load mount". Installation of a mount to hold external loads inthe existing photogrammetric hatch, according to Certification Plan"INAER.M11/037/25-PdC", Revision 0, Date: 21/06/2012.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Document List INAER.M11/037/25-LMD, Revision 0, Date: 21/06/2012.2. Instructions for continued airworthiness INAER.M11/037/25-ICA,Revision 0, Date: 21/06/2012.3. Flight manual supplement INAER.M11/037/25-FMS, Revision 0, Date: 21/06/2012.or later revisions of the above listed document(s) app...	None	15/01/2019	Active	10040333
10040358	VIH AEROSPACE Inc.	REV. 1	TCCA SH08-29	S-92A	LHS Crew Bubble Window Installation.Revision 1 is to add limitations for flight into known icing conditionsand for night time operations per TCCA STC Issue 5 dated October 05,2018.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	VS92-0803-MDL Rev. 7 dated Jan 10, 2014 – Master Document List;VS92-0803-FMS Rev. 3 dated Sep 17, 2018 – Flight Manual Supplement;VS92-0803-ICA Rev. 4 dated Jan 10, 2014 – Instructions for ContinuedAirworthinessor later revisions of the above listed document(s) approved/accepted onbehalf of EASA inP...	Flight into known or forecasted icing conditions not approved with theBubble Window installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	29/05/2020	Active	10040358
10040364	AERODATA AG			B300	Installation of Aerodata Automatic Flight Inspection SystemAD-AFIS-0280	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	- Flight Manual Supplement: AFM-121, Rev. 2or later revisions of the above listed documents approved by EASA- Installation Manual HB-A/ C-1090, Rev. 0- Master Document List MDL-A/ C-0170, Rev. 2- Maintenance Manual Supplement AMM-1125, Rev. 0	none	28/06/2012	Active	10040364
10040380	ALTRAN LABt/a AIRCAD			F900EX	Partial Cabin Entertainment and Galley equipment upgrade	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	File ref.: 12006Certification Program CP-12006 Revision A, dated 27/06/2012.Service Bulletin ACD-SB-12006 Revision A, dated 27/06/2012.or later revisions of the above listed documents approved by EASA	Falcon 900EX S/N 054	28/06/2012	Active	10040380
10040394	HELI-ONE (NORWAY) AS			AS 332 L, AS 332 L1	Goodrich Dual Hoist Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement AHS-090, dated 07.04.2011Continued Airworthiness Supplement No: AHSE-55211, Rev: B, dated12.01.2012or later revisions of the above listed documents approved by EASAMaster Drawing AHSE-55200, Rev: B, dated 20.06.2012	None	29/06/2012	Active	10040394
10040405	LEARJET Inc.		FAA STC SA8192NM-D	BD-700-1A10	Installation of a Sextant Integrated Electronic Standby InstrumentSystem	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	FAA STC No. SA8192NM-D dated 02 August 2001.Learjet Master Document List GC34235001 Revision G dated 01 August 2001.Learjet Airplane Flight Manual Supplement G-FM34235001 revision(-) dated 27 July 2001.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decisi...	none	02/07/2012	Active	10040405

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040411	AAR AIRCRAFT SERVICES		FAA STC ST03119CH	B717-200	Interior Reconfiguration	EASA.IM.A.211The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	FAA STC No. ST03119CH dated 25 June 2012.AAR Engineering Services Master Data List ERP 11-062 Revision C dated 23June 2012.Instructions for Continued Airworthiness (ICA), AAR Aircraft ServicesReport No. ERP 11-068 Revision IR, dated 28 March 2012.or later revisions of the above listed documents appr...	None	02/07/2012	Active	10040411
10040413	SAAB AB	REV. 2		MU-2B-20, MU-2B-26	Installation of Aft Pressure Bulkhead and Cabin Pressure Skin Feed Thruprovisions for Antenna / Electrical ConnectorsRev. 1: Transfer from SAAB AB, NYKÖPING to SAAB AKTIEBOLAG.Rev. 2: Correction of DOA reference.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23 amendment 2, dated 28 September 2010.The requirements for environmental protection and the associatedc...	TDM11-15 as described in TDM11-15-0-LEP Revision 0 dated 11th June 2012.Instructions for Continued Airworthiness: TDM11-15-4-ICA Revision Adated 21 June 2011.	Limited to Mitsubishi MU-2B, S/N: 283, 287, 289, 293, 299, 320, 337 and345.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthi...	07/12/2023	Active	10040413
10040427	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	B747-400	Installation of Galley 2A, 2B, 4B, 4C and 4D and ceilings in the G4complex in a Boeing 747-400 to be operated by VirginAtlantic Airways inaccordance with AIM Henshalls STC Definition Document DD 1198<(>,<)>dated 3 January 2012	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA Supplemental Type Certificate Definition Document DD 1198<(>,<)>dated 3 January 2012or later revisions of the above listed documents approved by EASA	None	02/07/2012	Surrendered	10040427
10040431	AIM ALTITUDE UK LIMITED		CAA UK RESPONSIBILITY	747-400	Installation of a single isolation switch in accordance with AIMAviation Service Bulletin B747-24-011 dated April 23, 2012 asreplacement for AIM Aviation Service Bulletin B747-24-04 or B747-24-05in order to comply to FAA AD 2009-15-12.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchangedand remain applicable to this certificate/ approval.	Service Bulletin B747-24-011 dated April 23, 2012Flight Manual Supplement Document Nr 11184 Issue A, dated 28 May<(>,<)>2012	none	03/07/2012	Active	10040431
10040440	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01694SE	BO 105 S, BO 105 LS A-3	Validation of FAA STC SR01694SE - Cargo Hook Kits	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 27 includingamendment 37The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels o...	- FAA approved Onboard Systems Rotorcraft Flight Manual Supplement RFMS121-029-00, dated March 1, 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)- FAA approved Onboard Systems Master Drawing...	This STC is restricted to installation of cargo hook kits model200-387-00 and model 200-388-00. Not included are cargo hook kits model200-302-00 and model 200-303-00.	03/07/2012	Active	10040440
10040450	MARSHALL OF CAMBRIDGE AEROSPACELIMITED	REV. 1	CAA UK RESPONSIBILITY	A340-312	This modification intends to:This modification will installSeat Electronics Boxes (SEB) (PanasoniceX2) on to modified existing Avio business class seats and will removeexisting Zone Terminators (ZT) (installed under Marshall ModificationMA1951).Modification to business class passenger cabin in acco...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Engineering Report ER/A340(1971)/12/0588, dated 12 Oct 2012.- Modification Sheet MA 1971 issue 1.pdf, dated 25 Oct 2012.or later revisions of the above listed documents approvedby EASA	none	25/10/2012	Active	10040450

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040456	AEROTEC & CONCEPT			EC225LP	SYSTEME ANTI-GIRATOIRESling load stabilization system	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 29 Issue 2 paragraphs:301, 303, 305, 307, 337, 603, 610, 865, 1351, 1353,1357, 1301, 1309,1322, 1505, 1523, 1529, 1541, 1581The requi...	-Flight Manual Supplement EC 225 LP MOD AEROTEC CONCEPT No. 1078'SYSTEME ANTIGIRATOIRE', document AE1078SMV rev 0 dated02/05/2012or later revisions of the above listed documents approved by EASA-INSTRUCTIONS FOR CONTINUED AIRWORTHINESS 'MOD 1078 EC225 LP POUR RTE /STH SYSTEME ANTI-GIRATOIRE SUIVI D...	S/N 2797 and 2824VFR onlyRequired pre-modification: Aerotec minor modification AE11142MAS(Logging EC255 LP) and use ofthe dedicated RFM 'SELECTEUR DE MISSION:UPPER/LOWER (Transport de charge externe à l'élingue)', EASA approval10037964	04/07/2012	Active	10040456
10040468	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-42, PA-42-720, PA-42-1000	Installation of Garmin G600 System with Synthetic Vision (SVT)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amendment2 (not required by 21A.101)The requirements for environmental protection and the associatedcertificated noise and/ or emi...	Flight Manual Supplement G600: ASR-2012-016-FMS-05-00, Rev.00or later revisions of the above listed documents approvedby EASA- Instructions for Installation: ASR-2012-016-IFI-10-00, Rev.00- Instructions for Continued Airworthiness: ASR-2012-016-ICA-11-00,Rev.00	none	05/07/2012	Active	10040468
10040470	ARMSTRONG AEROSPACE Inc.		FAA STC ST02948CH	767-300	Installation of Board Connect In-Flight Entertainment System	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	Master Drawing List DC104-9024-00, Revision B, 22/01/2012AFM Supplement DC303-9024-00, Revision -, 16/02/2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	This system is intended to provide internet connection and e-mailservices using portable electronic devices (PEDs). Any other intendedfunction of this equipment will require further certification approval.	05/07/2012	Active	10040470
10040472	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		MU-300 (DIAMOND IA) MU-300 (DIAMOND I)	Digital FDR Installation	The Certification Basis of the original product and the followingadditional /alternative airworthiness requirements areapplicable tothis change.For the change CS-25, Amdt. 4, hasbeen elected to comply with wherepossible.The certificated noise and/ or emissions levels of the original productare ,,u...	Installation in accordance with EASA approved Engineering Order, Doc.No. 2076242-EO, Issue 1, dated 26-June-2012, or later approved issue.Operation in accordance with EASA approved Aircraft Flight ManualSupplement, Doc. No. 2076242-AM , Issue 1, dated 12-June-2012<(>,<)> orlater approved issue.Maint...	This change is limited to the configuration of aircraft / equipment typeas listed under Chapter 4. in EASA approved Engineering Order, Doc. No. 2076242-EO, Issue 1, dated 26-June-2012, or later approved issue.	09/07/2012	Active	10040472
10040478	BOMBARDIER INC.		TCCA STC NO. SA12-16	BD-700-1A11	Installation, Aircraft Completion Modifications - ASN 9457	EASA.IM.A.009	Transport Canada STC No. SA12-16 Issue 2, dated 20 March 2012.Bombardier Configuration Definition Record RAZ-BM700-001 Revision H,dated 28 May 2012.Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC.Instructions for Continued Airworthiness Document GC94570000-ICA.or later revisi...	Restricted to ASN 9457.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs).Any other intended function of this equipment willrequire are-examination of the certification basis.	05/07/2012	Active	10040478

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040493	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CL-600-2A12	Introduction of Swift Broadband	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	STC Twenty One Ltd Master Document List No. S21.MDL-0879 Issue 3.Flight Manual Supplement No. S21.FMS-0078 Issue 1.or later revisions of the above listed documents approved by EASA	none	06/07/2012	Active	10040493
10040510	AAR CARGO SYSTEMS	REV. 1	FAA STC ST02665CH	A300B4-622, A300B4-622 R A300B4-605 R, A300B4-620 A300B4-601, A300B4-603	Validation of FAA Supplemental Type Certificate (STC) ST02665CHInstall a Main Deck Cargo Loading System (AAR Part Number 58535-101) onAirbus A300-600 series aeroplanes in accordance with AAR Master DrawingList Report Number 2149 Revision B, dated 15 December 2008.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AAR Weight & Balance Report A300-600 FSI Main Deck Cargo Loading System(MDCLS) P/N 58535-101 No.2147 Rev.A, dated 25 Aug. 2008.AAR Instructions For Continued Airworthiness A300-600 FSI MDCLS P/N58535-101 No.2148 original issue, dated 16 July 2007.or later revisions of the above listed documents appr...	none	13/07/2012	Active	10040510
10040513	3S CERTIFICATION, LLC	REV. 2	FAA STC ST03047CH	747-400	Certification of Compatibility with Cellular and Wireless DataTechnologies.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at the later amendment:25.1309(a) of CS-25at amendment 2 and 25.1529 of CS-25 at amendment 2.The requirements for environmental protection andc...	Armstrong Aerospace Master Data List DC104-9026-00, Revision G, dated 19January 2013Armstrong Aerospace Aircraft Equipment Compatibility List DC370-9026-01,Revision B, dated 18 January 2013Armstrong Aerospace Aircraft Equipment Compatibility List DC370-9026-02,Revision B, dated 18 January 2013or lat...	The following are the limitations associated with this typedesignchange.1.,,This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane instal...	05/09/2014	Active	10040513
10040515	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA STC NO. Q-LSA07-040/D	BD-700-1A10	Installation of Iridium Phone System and interior modification - ASN9028	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. Q-LSA07-040/D Issue 3, dated 07 June 2011.Innotech Aviation MDL27127002 Master Document List -Installation ofIridium Phone System and Minor Interior Modifications on ACSN 9028,Revision B, dated 07 June 2011.Innotech Aviation TL27127-004, Time Limits and Maintenance Checks -...	Restricted to ASN 9028.Previous installation of EASA STC No. 10039790 and EASA STC No. 10039791are pre-requisites.	06/07/2012	Active	10040515
10040526	ACC COLUMBIA Jet Service GmbH	REV. 1		PA-31T	PA-31T Camera Hole ModificationChange Note CN_2025593_rev0_20120201Rev. 1 Transfer to ACC Columbia Jet Service GmbH	The Certification Basis for the original product remains applicable tothis certificate/ approval.FAR 23 Amdt 1-7The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	MDOCL_2025593_rev0_20120201Installation Instructions II_2025593_rev0_20120201To be operated iaw SPOH_2025593_rev0_20120201To be maintained iaw II_2025593_rev0_20120201or later revisions of the above listed documents approved by EASA	as referred in AFM-S	26/01/2022	Active	10040526
10040531	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	767-200, -300	Introduction of an AD Aerospace Cockpit Door and Cabin SurveillanceSystem on Boeing B767-200/300.	EASA.IM.A.035The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	H4 Aerospace Modification Summary and Declaration of Compliance No. MODH4A1360 Issue 3, dated 06 July 2012.or later revisions of the above listed documents approved by EASA	none	09/07/2012	Active	10040531

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040541	AIR METHODS CORPORATION		FAA STC SR00523DE	SA365N, SA365N1, AS365N2	Installation of Emergency Medical Interior	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-080-0295 revision A dated 18 May 2012, Flight Manual Supplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (orsubsequent revisions ofthis decision)-241-9001 revision J dated 18 May 2012 - Master Data Index EMS Interior;-241-9005 r...	None	09/07/2012	Active	10040541
10040543	AIR METHODS CORPORATION		FAA STC SR00525DE	SA365N, SA365N1, AS365N2	Installation of two (2) aft jump seats	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-080-0295 revision A dated 18 May 2012, Flight Manual Supplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (orsubsequent revisions ofthis decision)-241-9007 revision B dated 2 September 2003 - Master Data Index;-241-9006 revision-...	None	09/07/2012	Active	10040543
10040545	AIR METHODS CORPORATION		FAA STC SR00524DE	SA365N, SA365N1, AS365N2	Installation of Articulating Patient Loading System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-080-0295 revision A dated 18 May 2012, Flight Manual Supplementor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (orsubsequent revisions ofthis decision)-241-9003 revision F dated 18 May 2012 - Master Data Index EMS Interior;-241-9002 r...	None	09/07/2012	Active	10040545
10040578	ALEBCO CORPORATION A/S	REV. 1		208B	Installation of Video Transmission Unit in accordance with Master DataList PP-008-MDL-04, Issue 4, dated 11 July 2012 or later approvedrevision.	The Certification Basis of the original product remains applicable tothis change.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of Video Transmission Unit in accordance with Master DataList PP-008-MDL-04, issue 4, dated 11. July 2012Operation must be in accordance with Aircraft Flight Manual SupplementPP-008-AFM-07, issue 7, dated 28. June 2012Maintenance must be in accordance with supplement to Maintenance Manu...	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s).	21/01/2013	Active	10040578
10040583	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special Transport - Instrumented Airbus SectionsIssue 1 of ATI modification ST25MOD020 (applicant's reference)<(>,<)>was developed, reviewed, tested and found compliant with theCertification Basis to deal with non-Airbussub-assemblies transport. On case by case basis, this modification isup-issu...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.- Cf. EASA TCDS A.014-CRI F-06 Issue 2 : Transport of Instrumented Payloadspowered by theaircraft electrical supplyThe requirements for...	Change Approval Sheet and Fiche de Modification ref : ST25MOD020, Issue52a.or later revisions of the above listed documents approved by EASA	none	06/12/2021	Active	10040583

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040585	S-TEC CORPORATION		FAA STC SR002346LA	BELL 206L-3, 206L-4 BELL 206B, 206L, 206L-1,	Installation of HeliSAS stability augmentation system and autopilot.Validation of FAA STC SR02346LA	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.FAR 27, with following amendments and related paragraphs:Amdt 11: 1322; Amdt13: 1321, 1351, 1357; Amdt 14: 29, 1581; Amdt 18:1529; Amdt6...	- Rotorcraft Flight Manual Supplement, HeliSAS-RFMS-206 revision N/ Cdated March 1, 2011- Master Data List, HeliSAS-MDL-206B revision E dated March 19, 2012- Instructions for Continued Airworthiness (ICA), Document No. AA-09021Revision B dated November 23, 2011or later revisions of the above listed d...	VFR only	17/07/2012	Active	10040585
10040586	AIRCRAFT STRUCTURES INTERNATIONAL CORP.		FAA STC SA10840SC	CESSNA 208, CESSNA 208B	Installation of Jack Pads on Cessna 208 Series aircraft in accordancewith FAA STC SA10840SC	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASIC Master Data List ASIC-351 MDL, Rev. 5, dated March 23,2010 orlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (orsubsequent revisions ofthis decision).	None	11/07/2012	Active	10040586
10040589	LUFTHANSA TECHNIK AG			B747-8	Camera installation in the vertical stabilizer for ground manoeuvringservice.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product are unchanged andremain applicableto this certificate/ approval.	Supplemental Type Definition Document STDD55-11/20M Issue 01< (>,<)>Design Review C-ABJ275-DR rev. 0or later revisions of the above listed documents approved by EASA	none	12/07/2012	Active	10040589
10040592	SABENA TECHNICS BGC			A330-223 / -243 A330-201 / -202 / -203	Panasonic eXPhone System Activation on A330 with eX2 IFE and eXconnect.This STC installs a Panasonic eXphone System allowing, in conjunctionwith other devices, the use of cellphones during flight.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-,,CS 25 Amendment 4-,,CRI H-01 Issue 1 - Enhanced Airworthiness Programme for AeroplaneSystems - ICA on EWIS (as per TCDS EASA.A.004)-,,...	Master Data List, Ref : 0496-03-A-2103-R00, dated 11 July 2012;Instruction for Continued Airworthiness, Ref : 0496-03-A-2211-R00, dated10 July 2012;Aircraft Flight Manual Supplement, Ref : 0496-03-A-2301-R00, dated 10July 2012;Weight and Balance Report, Ref. 0496-03-A-3401-R00, dated 10 July 2012;or...	None.	12/07/2012	Active	10040592
10040601	BOMBARDIER INC.		TCCA STC SA12-16 ISSUE 2	BD-700-1A11	Installation, Aircraft Completion Modifications - ASN 9461	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-16 Issue 2, dated 20 March 2012Bombardier Configuration Definition Record RAZ-BM700-001 Revision M,dated 11 June 2012Bombardier Airplane Flight Manual Supplement G-FM25054001 Revision BASICInstructions for Continued Airworthiness Documents GC94610000-ICA orlater revisio...	Restricted to ASN 9461The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin portableelectronic devices (PEDs).Any other intended function of this equipment will require are-examination of the certification basis.	12/07/2012	Active	10040601
10040602	PMV ENGINEERING	REV. 1		A330-200, A330-300	Installation of provisions for the use of EFB Class 2 on Airbus A330.This modification deals with the installation of adual Class 2Electronic Flight Bag (EFB) CMC Esterline 'Pilot View' system on AirbusA330-200/300.The modification is defined as follows:-Installation of the Arm Mounts in the cockpi...	The Certification Basis for the original product remains applicable tothis certificate/ approval.A330 EASA TCDS A. 004Therequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalproduct areunchanged and remain applicable to this certifica...	-Certification Investigation Report AVI-0034-CIR-R04 Issue 6, dated12/07/2012- Instructions for Continued Airworthiness AVI-0034-ICA-R02 Issue 2,dated 25/06/2012-Aircraft Flight Manual Supplement AFMS AVI-0034-AFMS-R02 Issue 2, dated09/03/2012-Aircraft Maintenance Manual Supplement AMMS AVI-0034-AMMS...	This certificate does not cover the installation of EDUs which will becover by the operational evaluation.	13/07/2012	Active	10040602

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040607	JET AVIATION ST. LOUIS, Inc.		FAA STC ST01376WI-D	BD-700-1A10	Installation of a Cabin Interior Arrangement, Passenger Oxygen Systemand Emergency Lighting	EASA.IM.A.009The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.EASA Generic CRIs D-01, D-02, D-03The requirements for environmental protection and the associatedcertificated noise and/ or...	FAA STC No. ST01376WI-D dated 30 November 2011.Jet AviationIndex List 35-299G009, Revision N, dated 29 May 2011.Jet Aviation Master Drawing List 35-299G013, Revision D.Jet Aviation Airplane Flight Manual Supplement 35-174M003, Revision NC,dated 25 October 2009 (Configuration 13).or later revisionsa...	Restricted to ASN 9267 (Configuration 13)	13/07/2012	Active	10040607
10040608	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03779AT-D	GIV-X	Installation of an AirCell High Speed Internet System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC ST03779AT-D, issued 4th June 2010- Installation in accordance with Gulfstream Aerospace Corporation IndexList GC413028000, Revision B, dated 4th June 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions o...	EASA STC number EASA.IM.A.S.02633 is required for installation of thisSTC	13/07/2012	Active	10040608
10040616	ASI INNOVATION			2. B90, E90 1. C90, C90A, C90GT, C90GTI	VHF, UHF and GPS antennas installation provisions accordingto ASImodification no ASI-FAM-0096-00	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement no ASI-AFM-0096, original issue dated 20 June2012STC data list no ASI-SDL-0096, revision 0 dated 25 June 2012or later revisions of the above listed documents approved by EASA	This change is applicable to aircraft:-B90 S/N LJ-318 to LJ-501-C90 S/N LJ-502 to LJ-1062-C90A S/N LJ-1062 to LJ-1726, LJ-1727 to LJ-1753 and LJ-1755-C90GT S/N LJ-1727, LJ-1754, LJ-1756 and after-C90GTi S/N LJ-1847, LJ-1853 and after-E90 S/N LW-1 and afterequipped with standard 250 VA Inverter	13/07/2012	Active	10040616
10040624	ALTRAN LABt/a AIRCAD	REV. 1		F2000	Installation of a sliding door, main entryway door removableworkshelves, installation or replacement of galleys equipment and IFEequipment, RH and annex RH galleys shelves rearrangement.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Program CP-12001 Revision A, dated 13 July 2012;Service Bulletin ACD-SB-12001 Revision B;or later revisions of the above listed documents approved by EASA.	Falcon 2000 S/N 111.	19/07/2012	Active	10040624
10040625	DOA AESGLOBAL LIMITED	REV. 1		A321-231	Introduction of Panasonic MPES IFE systemRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Project Specific Certification Plan, ref. doc. AES-TR-1024, Issue 2dated 15/05/2012- Master Data List, ref. doc. AES-321-2443MDL, Issue 1, dated 29/06/2012- Instructions for Continued Airworthiness - Principal Document, ref.doc. AES-TR-1031, Issue 1 dated 13/06/2012- Airplane Flight Manual Supplem...	None	27/04/2021	Active	10040625
10040627	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST00803LA-D	GV	Installation of Satcom Antenna (Racal).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA STC ST00803LA-D, issued 1st September 1999;- Installed in accordance with Gulfstream Aerospace Corporation IndexList, ref. IL11011575, Revision C, dated 31st August 1999;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subseque...	None.	16/07/2012	Active	10040627

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040628	LUFTHANSA TECHNIK AG			319-133	A319-133 ANJI VIP Cabin Completion	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The EASA Certification Basis for this STC are defined in EASA CRI A-01for LHT Project 0010011424 which was closed at issue 1, and consist...	Lufthansa Technik's documents:- Supplemental Type Definition Document STDD00-11/18M, issue 2, Revision00 dated 13th July 2012 and- Airplane Flight Manual (AFM) Supplement A-00-11/172-AFM Issue 1,Revision 01 dated 30th May 2012, and- Instructions for continued airworthiness A-00-11/172-ICA Issue 2,Re...	- This design change approval is applicable on Aircraft model AirbusA319-133 CJ, aircraft serial number 4428.	16/07/2012	Active	10040628
10040630	PFW ENGINEERING DO GmbH	REV. 1		319-100	General Fin Camera Installation on Airbus A319	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Original certification basis for A319-100 as per TCDS's EASA.A.064 issue07 plus CS 25.1729 as per EASA CS 25 amendment 10.The requirement...	GCT's documents:- Master Drawing List A319A-MDR-233000 Issue A, dated 12th July 2012 and- Master Equipment List A319A-MEQ-233000 Issue A, dated 31st March 2012,and- STC Operators Manual A319A-COM-B, Issue 30th June 2012, comprising:- Instructions for Continued Airworthiness A319A-ICA-A, Revision 0,d...	This design change approval is applicable on Aircraft modelAirbusA319-100, aircraft serial number 4428.	11/10/2013	Active	10040630
10040641	WESTERN AVIONICS		TCCA STC SA10-104	DHC-8-311,DHC-8-314,DHC-8-315 DHC-8-201,DHC-8-202,DHC-8-301 DHC-8-102,DHC-8-103,DHC-8-106	Installation of a Western Avionics PicoCube Communications SystemTCCA STC SA10-104, Issue 2	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation:Must be in accordance with Western Avionics Engineering Order120760-401, Revision 1, Transport Canada approved 2010 December 15.Operation:Must be in accordance with approved Western Avionics Flight ManualSupplement 120760-802,IR, Transport Canada approved 2010 December 15.Maintenance:M...	Structual and antenna provision in accordance with the latest applicableissue of EASA STC MOT.21NE2.139 are required.	16/07/2012	Active	10040641
10040646	AEROLITE AG	REV. 2		EC 635 T2+ EC 635 T1 EC 635 P2+ EC 135 T2+ EC 135 T2 EC 135 T1 EC 135 P2+ EC 135 P2 EC 135 P1	Ballast Platform Installation P/N 135-0012762-501.Revision 1: Administrative CorrectionRevision 2: Change of STC holderfrom "Aerolite Max Bucher AG" to"Aerolite AG".	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement FMS-135-0012762-501, Revision N/C, dated July6th 2012;or later revisions of the above listeddocuments approved by EASA.- Master Document List MDL-12-010 Revision N/C, dated 12/07/2012;- Weight and Balance manualWBM-135-0012762-501, Initial Issue, datedJuly 6th, 2012.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously design change and/or repair will introduce no adverse effectupon the airworthiness of the product.	06/05/2019	Active	10040646
10040647	S-TEC CORPORATION	REV. 1	FAA STC NO. SA7178SW-D	T210K 210K	Installation of S-TEC manual Electric trim system, (ST-433), accordingto Bulletin n. 533, dated 11-May-1988 and Master Drawing List No. 92474,dated 11-May-1988 or later FAA approved revision (14V - System).	Design:Non-significant changeThe Certification Basis of theoriginal product remains applicable tothis change.Environmental Protection:The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved S-TEC Master Drawing List No. 92474 dated 11-May-1988 orlater FAA approved revision.FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement No. 89784 dated 18-May-1988 or later FAA approvedrevision.	T210K is eligible also when modified per STC SA2689SW (RAMmodification).Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s).If the holder agrees to permit another person to use this certificate toalter the product, the ho...	17/07/2012	Active	10040647

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040651	AERODISA S.L.			B300	FMS Upgrade for King Air B300.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Technical Documents to be Approved by EASA:AERODISA Master Data List AED2O11-17M_MDL ED/ Rev 0/4or later revisions of the above listed documents approved by EASA.Other:AERODISA AED2O11-17M Airplane Flight Manual Supplement	S/N Limitation:AIRPLANE MODEL HAWKER BEECHCRAFT B300 S/N FL-255	16/07/2012	Active	10040651
10040655	SOCATA			DHC-6 SERIES 300	Avionics upgrade based on Garmin G600 EFIS and GNS 430 W system,according to SOCATA modification file n° STC. 00.001.11	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 23Standard CRIs B52, F51, F52, F54, F58, F84The certificated noise and/ or emissions levels of the original productare unchanged and r...	Socata Flight Manual Supplement n°38, Issue 1 dated 15 March 2012.Socata Maintenance Manual Supplement revision 0 dated15 February 2012.Socata Modification Sheet n° STC. 001001.11, Edition 1 dated 4 July 2012or later revisions of the abovelisted documents approved by EASA	This design change is limited to airplanes s/n 292, 298, 300, 730 and745.Initial installation must be performed by authorised Socata technicalpersonel.This avionics installation is approved for IFR operations in BRNAV,PRNAV, RNP approach LNAV and LPV approach with coupling to autopilot.The airplanes...	17/07/2012	Active	10040655
10040678	BRISTOW HELICOPTERS LIMITED		CAA UK RESPONSIBILITY	S-61N	Activation of ADS-B Function using Mode S Extended Squitter	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS29 Amendment 2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origin...	Bristow Helicopters Limited Sikorsky S61N Flight Manual Supplement No30Initial Issueor later revisions of the above listed documents approved by EASAModification MOD/ S61/34.5719 Issue 1 dated 23 May 2012Certification Plan BHL/S61.5607 Initial Issue dated 23 Mar 2012	none	18/07/2012	Active	10040678
10040680	PFW ENGINEERING DO GmbH	REV. 2		747-8	Structural provisions for 747-8i belly camera installation between theNLG bay and the belly fairing at the lowest pointof the fuselage. Itcontains:- Attachment to the aircraft structure through brackets- Outside fairing- Installation of awiring feed-through	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Description Document DE-530-B747A Issue 01<(>,<)>MasterDocument List CCN-B747A-MCDL Issue 01<(>,<)>STC Operators Manual B747A-COM-A dated 31 Jan 2012<(>,<)>or later revisionsof the above listed documents approved by EASA.	none	11/10/2013	Active	10040680
10040685 (EASA.IM.R.S.00273)	AEROFDC WA LP	REV. 2	FAA STC SR00811SE	AS350 B, AS350 B1, AS350 B2 AS350 B3, AS350 BA	Revision to EASA STC 10040685, rev. 1:Installation of an engine air filter in accordance with FDC Master DataList No. 1350-1001 and FDC Installation Instructions 1350-INST-1Notes:1. This STC was initially issued to INTEC Helicopters, Inc. on 28October 2004 under reference EASA.IM.R.S.00273 and was t...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Design and Installation documentation:FDC Master Data List No. 1350-1001 revision N dtd 20 May, 2011FDC Installation Instructions 1350-INST-1, revision H dtd 20 May, 2011Maintenance documentation:FDC Instructions for Continued Airworthiness 1350-SERIES-ICA-1, revisionE dtd April 20, 2011or later rev...	This STC is not applicable to AS350B3 model helicopters fitted withArriel 2B engine and incorporating dual hydraulic systemThis STC is not applicable to AS350B3 model helicopters incorporatingmodification OP-4305 (Arriel2D engine installation)Prior to installation of this design change it must be de...	31/01/2014	Active	10040685
10040686	ACS-NAI Ltd.		TCCA SA01-77/JAA ACG. 21NE2.084	DHC-8-301,-311,-314,-315 DHC-8-201,-202, DHC-8-102,-103,-106	Installation of an improved Aft Jet Pipe SupportTCCA STC N° SA01-77, Issue 3	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	InstallationMust be in accordance with Aero Consulting Service Ltd. ModificationData Summary N° C 54600, Revision B.Maintenance:Must be in accordance with Aero Consulting Service Ltd. MaintenanceManual Supplement N° C 54672, N/ C.or later revisions of the above listed documents approved by EASA inacc...	None.	19/07/2012	Active	10040686

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040691	2 EXCEL DESIGN LIMITED	REV. 3	CAA UK RESPONSIBILITY	PA-31	Provisions for the installation of a Sensor Turret	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List S21.MDL-1027 Issue 6- Flight Manual Supplement S21.FMS-0091 Issue 4- Compliance Record S21.COMP-1027 Issue 4- Instructions for Continuing Airworthiness S21.TEC-0374 Issue 2or later revisions of the above listed documents approved by EASA.	With a sensor turret with diameter greater then 15.5" installed,flight into known or forecast icing conditions is prohibited.Limitations as defined in AFMS S21.FMS-0091 Issue 4The installation and subsequent operation of a sensor turret requires aseparate approval.Prior to installation of this mod...	25/08/2017	Active	10040691
10040700	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BAE 146 SERIES 300 BAE 146 SERIES 200 BAE 146 SERIES 100 AVRO 146 SERIES RJ85 AVRO 146 SERIES RJ70 AVRO 146 SERIES RJ115 AVRO 146 SERIES RJ100	ADS-B Out Surveillance	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification TEN 706 Issue 1 dated 13 June 2012.Flight Manual Supplement TEN/146/016 Issue 1or later revisions of the above listed documents approved by EASA	Configuration using transponder part number 751-7800-11005 does not meetEASA AMC 20-24 for ADS-B NRA. Emergency Status/Emergency Indicator arenot provided.	20/07/2012	Active	10040700
10040704	DOA AESGLOBAL LIMITED	REV. 1		A321-231	Introduction of Twin Class Cabin Interior Configuration.Rev1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval plus:1.,,CRI D-3306-001 "Application of Heat Release and Smoke DensityRequirements to Seat Material" - Special Condition2.,,CRI E-13 "Ins...	- Modification Summary ref. Modification No. AES-321-2059, Issue 2,dated 19th July 2012;- Master Data List, ref. doc. No. AES-321-2059MDL, Issue 2, dated 19thJuly 2012;- Project Specific Certification Plan (PSCP), ref. doc. No. AES-TR-0844,Issue 3, dated 10th July 2012;- Certification Compliance Rep...	The EASA STC 10038683 is a prerequisite for the installation of thisSTC.	27/04/2021	Active	10040704
10040714	PROTOPLANE SPECIAL MISSION AIRCRAFT			B200C	Removing of the metal parts of a cargo pod and provisions for theinstallation of signal transmission antennas inside the pod.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, PP-022-MDL-00, Issue 2, dated 23/07/2012Aircraft Flight Manual Supplement, PP-022-AFM-02, Issue 2, dated23/07/2012or later revisions of the above listed documents approved by EASA	Limited to serial numbers BL 49 and BB 1473It is forbidden to use the modified pod to carry baggage or cargo.This modification does not include power to the antennas installed onthe pod. The operation of the antennas is not include in thisapprovaland must be approved by a separate change.	23/07/2012	Active	10040714
10040716	JET AVIATION AG, BASEL			A319-115	VIP Cabin Interior Completion.See Master Data List BCJ03856-001.	JAR 25, Ch.11 except as noted in TDCS EASA.A.064The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI A-4301-016 EASA STC Certification BasisSCs or ESFs:CRI D-4301-016 Installation of Int...	Airplane Flight Manual Supplement BCJ03856-201-01 Rev. C;Instructions for Continued Airworthiness BCJ03856-150-01 IR;EWIS Instructions for Continued Airworthiness BCJ03856-150-02 Rev. IR;or later revisions of the above listed documents approved by EASA.	Approval valid only for MSN 3856.The aircraft is certified for private use only, not to be operated forcommercial air transport.The aircraft is a No Smoking aircraft.For other Limitations refer to Airplane Flight Manual SupplementBCJ03856-201-01 Rev. C or later revision approved by EASA.	23/07/2012	Active	10040716
10040720	BOMBARDIER INC.		TCCA STC NO. SA12-16	BD-700-1A10	Installation, Aircraft Completion Modifications - ASN 9443.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-16 Issue 2 dated 20 March 2012;Bombardier Configuration Definition Record RAZ-BM700-001 Revision Tdated 10 July 2012;Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC;Instructions for Continued Airworthiness document GC94430000-ICA;or later revisio...	Restricted to ASN 9443.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs). Any other intended function of this equipmentwillrequire a re-examination of the certification basis.	24/07/2012	Active	10040720

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040722	BOMBARDIER INC.		TCCA STC NO. SA12-31	BD-700-1A10/-1A11	Modification, Electronic Wiring Heater Current / Brake TemperatureMonitor Unit (HBMU).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-31 Issue 2 dated 25 May 2012.ACS-NAI Ltd. Modification Data Summary H119000 Revision N/ C,dated 30March 2012;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision2004/02/ CF (or subsequent revisions ofthis decision).	None.	24/07/2012	Active	10040722
10040724	JET AVIATION ST. LOUIS, Inc.		FAA STC NO. ST02744CH-D	BD-700-1A10	Installation of a Rockwell Collins Wireless Local Area Network (WLAN).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST02744CH-D dated 30 November 2011;Midcoast Aviation Index List 35-409G007, Revision NC dated 05 August2009;Midcoast Airplane Flight Manual Supplement 35-409M004, Revision NC dated06 August 2009;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED D...	None.	24/07/2012	Active	10040724
10040738	CONCORDE BATTERY CORPORATION		FAA STC NO. SA01633WI	EMB 500	Installation of Concorde RG-390E VRSLA Batteries in the Embraer 500 inaccordance with Concorde Battery Corporation Master Drawing List, DWGNo. 5-0359, Revision NC, dated August 25, 2010 or later FAA approvedrevisions.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Concorde Battery Corporation Master Drawing List, DWG No. 5-0359,Revision NC, dated August 25, 2010;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	24/07/2012	Active	10040738
10040777	AIRBUS S.A.S.			A320-214	Airbus Corporate Jet Centre Modification CJ1108 Issue 1 -Installation of Business Class Seating Area - "Gulf Air - TypeB"	In accordance with the EASA TCDSThe Certification Basis forthe original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI A 2301-007 "ACJC Centre Conversion Project Certification Basis"The requirements for environmental pro...	-Modification Approval Sheet, ref.: CJ1108, Issue 1, dated 25th July2012-Airplane Flight Manual AFM Supplement, ref.: FM-S MOD CJ1108, dated 1stJuly 2012or later revisions of the above listed documents approved by EASA	This STC is limited to MSN 5171, MSN 5175	26/07/2012	Active	10040777
10040780	JET AVIATION AG, BASEL			B737-800	Forward VIP Lavatory reconfiguration- new shower system- relocation of handspray system- new vanity light system- new shower light system- new pax sign inside shower- adaptation of existing systems	JAR 25,, Amdt: Change 13, except as noted in EASA TCDS IM.A.120The Certification Basis for the original product and thefollowingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI D-01 Shower InstallationCRI H-01 Instruction for Continued Airworthine...	Instructions for continued airworthiness ref. B6AUH003-150-19;Master Data List B6AUH003-019;Flight attendant handbook ref. WH-04;or later revisions of the above listed documents approved by EASA.	S/N: 33473 (A6-AUH)	26/07/2012	Active	10040780
10040781	CONCORDE BATTERY CORPORATION		FAA STC ST01643WI	DHC-8-301, -311, -314, -315 DHC-8-201, -202 DHC-8-102, -103, -106	Installation of Concorde RG-380E/44 (42AH) or RG-380E/60L (48AH) SeriesValve Regulated Sealed Lead-Acid (VRSLA) batteries as replacement of OEMbatteries.FAA STC ST01643WI	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	InstallationMust be in accordance with Concorde Battery Corporation Master Data List(MDL) Drawing N° 5-0284-1, 5-0284-3Rev. A.Operation:Must be in accordance with Airplane FlightManual Supplement (AFMS) Drawing N° 5-0285, Rev. NC.Maintenance:Must be in accordance with Component Maintenance Manu...	none	26/07/2012	Active	10040781

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040783	BLR AEROSPACE, L.L.C.	REV. 1	FAA STC SR00798SE/ LBA RC 1163	2. 212, 412, 412EP 1. 204B, 205A-1	Installation of Dual Tailboom Strakes. This STC revises andsupersedesLBA STC RC 1163 to add the Bell Helicopter Textron Inc. Model 204B, 412and 412EP. The AB 212 is removed as itis not included in the FAA STC.Rev. 1 updates the STC holder's address.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFMS-BH205-1a revision B dated 8 January 2002 - Flight Manual Supplementfor all models;RFMS-BH205-2a revision IR dated 12 March 2004 - Flight Manual Supplementfor Model 205A-1 Performance Improvement;RFMS-BH205-3a revision IR dated 12 March 2004 - Flight Manual Supplementfor Model 204B Performance I...	Day/Night VFR only, flight into known icing conditions prohibited.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of t...	22/05/2019	Active	10040783
10040787	NORTH FLIGHT DATA SYSTEMS, L.L.C.		FAA STC SR09468RC	EC135 T2, EC135 T2+ EC135 P2+, EC135 T1, EC135 P1, EC135 P2,	Installation of the Outerlink Corporation CP-3 or CP-3i Automatic FlightFollowing System, Optional Electronic Flight Bag Provisions, and FlightData System in accordance with NorthFlight Data System, LLC MasterInstallation List, Document N° NL462073006, Revision M, dated October10, 2011 or later app...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- North Flight Data System, LLC Master Installation List, Document N °NL462073006, Revision M, dated October 10, 2011.- North Flight Data Systems, LLC Instructions for ContinuedAirworthiness, Document N° NM462073006, Revision E, dated October 20,2011.- Rotorcraft Flight Manual Supplement NF462073003...	none	26/07/2012	Active	10040787
10040822	AVIATION DEFENSE SERVICE	REV. 1		FAN JET FALCON BASIC	Carriage of PIRATE pylons-only (Expanded Flight envelope)The purpose of this approval is to revise EASA STC 10040822 toclear thecarriage of the PIRATE pylons only configuration (with ferry fairing) onS/N 076 in the following envelope:VMO 350 kts, MMO 0.78, FL390, n = +2g / -1g	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt 10 §631 and FAR 25 Amdt 41 §1323, 1325 and 1529The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Change Approval Sheet doc. N° CAS-AVD-MDA20-95-FOG5A rev 02Issue 03dated 29.10.2013Master Document List doc. N° MDL-AVD-FOG5A rev 2 Issue 2 dated05.11.2013Aircraft Flight Manual Supplement doc. N° SAFM-FALC20 Rev. 19or later revisions of the above listed documents approved by EASA.	Restricted to S/N 076As per AFM Supplement N° SAFM-FALC20 Rev. 19.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthine...	06/11/2013	Active	10040822
10040826	ACC COLUMBIA Jet Service GmbH	REV. 1	LBA STC EMZ SA 0100/2025	340A	1. Camera Modification Kit System C340-8120002. C340 CameraHatch Installation System C340-812500Change Note CN_2027313_rev0_20120402Rev. 1 Transfer to ACC Columbia Jet Service GmbH	The Certification Basis for the original product remains applicable tothis certificate/ approval.FAR 23 Amdt 1-7The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	1. System C340-812000AFM-Supplement: Luftbildversion Gomolzig C340-812000 Ausgabe 27.12.1988Installation Instruction: Umrüstanweisung zum KameraumrüstsatzC340-81 2000 Ausgabe 12/882. System C340-812500MDOCL_ 2027313_rev0_20120402In stallation Instructions II_2027313_rev0_2012040 2AFM-Supplement:SPOH_20...	As referred in AFMPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	26/01/2022	Active	10040826
10040831	SAFRAN CABIN INC.		FAA STC ST00869SE	B757-200	Validation of FAA STC ST00869SE (Modification to Overhead Stowage Binslocated in the passenger cabin in order to extendthe bins inboard).	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Northwest Composite Incorporated Master Drawing List A076000 Rev G dated2-17-11;or later revision of the above listed document approved by EASA inaccordance with EASA ED Decision 2004/04//CF (or subsequent revisions ofthis decision).	None.	30/07/2012	Active	10040831

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040859	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Installation of an Iridium Satcom for voice and ACARS on A300-600ST	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Change Approval Sheet ST23MOD021<(>,<)> rev 1, date 30 July2012Airplane Flight Manual Supplement as in, ST23MOD021 Annex 7, rev 1, date30 July 2012or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/ CF (or subsequent revisions ofthis decision...	None	31/07/2012	Active	10040859
10040867	SABENA TECHNICS BOD	REV. 2		A320-214	Structural provisions for the installation of SATCOM Antenna AMT3800.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan PC-D0088-001, Issue 8, dated 17/09/2013- Master Drawing List MDL-S-53-2258-1, Issue D, dated 20/07/2012- Master Drawing List MDL-S-53-2258-2, Issue B, dated 06/11/2012- Instructions for Continued Airworthiness ICA-D0088-00-002, Issue B,dated 05/09/2013- Airworthiness Limitation1...	This approval is limited to MSN 764 and MSN 3164.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product...	20/09/2013	Active	10040867
10040868	SABENA TECHNICS BOD			A320-214	Installation of SATCOM system	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Plan PC-D0088-002 Issue 4 dated 20/07/2012-Master Drawing List MDL-S-00-2261 Issue B dated 26/07/2012- Instructions for Continued Airworthiness (ICA) ICA-D0088-00-001 Issue Adated 26/06/2012- Modification Approval Sheet MAS-S-00-2261 Issue 3 dated 20/07/2012or later revisions of the ab...	This modification can be installed only concurrently with themodifications approved under EASA STC 10040867 (EASA project0010016700).This approval is limited only to MSN 3164.	31/07/2012	Active	10040868
10040869	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 560XL	Installation of a Moving Map System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Jet Aviation Master Data List: ref 2012-4-16, rev IR, date 30 July 2012;Jet Aviation AFM Supplement: ref 2012-4-8, rev A, date 21 July 2012;Jet Aviation Maintenance Manual Supplement, ref 2012-4-10, rev A, date21 July 2012;or later revisions of the above listed documents approved by EASA inaccordanc...	None.	31/07/2012	Active	10040869
10040870	ORCON CORPORATION			B737-200/-200C/-300/-400 /-500	Thermal/acoustic insulation system for Boeing 737 series aircraft:insulation blankets installation.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS25.856(a) (amendment 6) "Thermal/acoustic insulation materials"The certificated noise and/ or emissions levels of the original producta...	Master Drawings List MDL-8000 revision H<(>,<)>Continued Airworthiness instructions CAI-8002 revision E<(>,<)>or later revisions of the above listed documents approved by EASA	None	31/07/2012	Active	10040870
10040891	ASI INNOVATION			P2006T	ASI-0084-03 dated 30 July 2012 - Installation of removable missionconsole (without equipments) in the aircraft cabin inplace of passengerseat.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/or emissions level of the original productare unchangedand remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement ASI-AFM-0084-00 dated 07 June 2012STC Data List ASI-SDL-0084-03or later revisions of the above listed documents approved by EASA.	This STC shall be used only by ASI Innovation.	01/08/2012	Active	10040891

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040901	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02907CH	B747-400F B747-400	Installation of ECS EZMount mechanical mounting assemblies in accordancewith Electronic Cable Specialists, Inc. Master Data List ECS 209135,Revision H, dated November 29, 2011 or later approved revisionValidation of FAA STC ST02907CH	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.14 CFR Part 25 Amendment 25-119 for the following requirements25.301(a)(b); 25.303; 25.305(a)(b); 35.307(a); 25.561(c); 25.562(c)(5);25.6...	Master Data List ECS 209135, Revision H, Dated November 29,2011AFM Supplement ECS 208936 for Boeing 747-400 series Aircraft equippedwith ECS EZMount tiltECS-209136 Rev. NC Instructions for Continued Airworthiness ECS EZMountfor Boeing 747-400, -400F series Aircraftor later revisions of the above l...	The equipment for which these provisions are installed has not beencertified. Additional approval is required for the installation of thisequipment and must be evaluated to assuresatisfactory compliance withapplicable airworthiness standards.	02/08/2012	Active	10040901
10040905	NEXTANT AEROSPACE L.L.C.		FAA STC ST03960AT	400A	Installation of Rockwell Collins Venue In-Flight Entertainment (IFE),Aircell Axxess Cabin II Iridium Phone and High Speed Internet Systemwith Wireless Local Area Network (WLAN) Astronics 115V AC 60 Hz CabinInverter, and Emteq LED Cabin Lighting System.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval;FAR 25 Amendmentlevel as defined in FAA STC ST03960AT.The requirements for environmental protection and the associatedcertificated noise...	Installation in accordance with Nextant Aerospace LLC Master DrawingList Doc No DB1002067 Revision E, dated January 26,2012;Operation in accordance with Nextant Aerospace LLC FAAApproved FlightManual Supplements:-When Rockwell Collins Venue System is installed Airplane Flight ManualSupplement DB1...	This STC is intended to provide internet connection and E-Mail servicesto the aircraft cabin using portable electronic devices (PED's). Anyother intended function of this equipment will require a re-examinationof the certification basis.	02/08/2012	Active	10040905
10040906	NEXTANT AEROSPACE L.L.C.		FAA STC ST03110CH	400A	Installation of L3 Communications Digital Flight Data Recorder.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:FAR 25 Amendments as detailed on FAA STC ref ST03110CH.The requirements for environmental protection and the associatedcertificated noise...	Installation in accordance with Nextant Aerospace LLC Master DrawingList Doc No NX1111001 Revision 1, dated May 29, 2012;Operation in accordance with Nextant Aerospace LLC FAA Approved FlightManual Supplement No NX1111004 Revision IR, dated May 17, 2012;or later revisions of the above listed documen...	None.	02/08/2012	Active	10040906
10040912	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE	REV. 1	TCCA STC NO. O-LSA00-829/D	BD-700-1A10	Baggage Door Locking System Modification	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. O-LSA00-829/D Issue 2 dated 04 January 2002.DECA Modification Summary MS0009938 Issue 1 dated 08 November 2000.DECA Maintenance Manual Supplement DECA-4885-02 Revision 2, TC accepted19 December 2001.or later revisions of the above listed documents approved by EASA inaccordan...	Restricted to ASN 9003	28/08/2012	Active	10040912
10040913	SWS CERTIFICATION SERVICES Ltd.	REV. 5	CAA UK RESPONSIBILITY	747-8	Installation of the Aeroloft™ Overhead Sleeping Compartmentimmediatelyforward of the Overhead Crew Rest.Two following configurations are certified (1287, 1036, 1044, 1532):1. With lounge module (1036, 1287 and 1532)<(>,<)>1.1 For 1287 and1532, the following peculiarities are included: IFE andPC Po...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-100 “Installation of overhead sleepingcompartment” issue 2CRI A-100 “EASA certification basis definition” issue 2The requirements for environmental...	Config 1036:Certification Plan 3069-CEP-01 Issue 023069-MCS-01 issue 05 Master Configuration scheme3069-FMS-01 Issue 1 Flight Manual Supplement3069-MMS-01 Issue 01 Maintenance Manual Supplement (including EWIS andICAW) 3069-MMS-02 Issue 02 Maintenance Manual Supplement (including EWIS andICAW)3069-MM...	As per AFMS, andFor configurations 1036, 1044, 1287 and 1532 limitations as per SpecialConditions CRI D-100, in particular:1) Occupancy of the Overhead sleeping compartment (OSC) is not allowedduring Taxi Take-Off and Landing phases2) Occupancy during flight is limited to one person per sleeping mod...	26/10/2020	Active	10040913

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040920	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD	REV. 1	TCCA STC C-LSA12-105	BD-700-A110	Installation, Complete Custom Aircraft Interior - ASN 9433	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. C-LSA12-105 Issue 1 dated 09 July 2012.ACS-NAI Ltd. Modification Data Summary H430000 RevisionNC.Innotech Aviation Flight Manual Supplement for Interior Completion,AFMS-IA6000-9433 Revision BASIC.For Instructions for Continued Airworthiness for the Aircraft Completionrefero...	Restricted to ASN 9433.The Wireless LAN System is intended to provide internet connectivity andemail services to the airplane's cabin using portable electronic devices (PEDs). Any other intended function of this equipment will require are-examination of the certification basis.	09/08/2012	Active	10040920
10040926	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 2		B200GT	"Stretcher kit Avfab 32-0117". Installation of a stretcher kit replacingLH seats (rows 2 and 3), according to Certification Plan "INAER.M12/044/25-PdC", Revision 0, Date: 27/07/2012.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Document List INAER.M12/044/25-LMD, Revision 0, Date: 27/07/2012.2. Instructions for continued airworthiness INAER.M12/044/25-ICA,Revision 0, Date: 27/07/2012.3. Flight manual supplement INAER.M12/044/25-FMS, Revision 0, Date: 27/07/2012.or later revisions of the above listed document(s) app...	None	15/01/2019	Active	10040926
10040927	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	C90GTI	To introduce L3 Electronic Standby Instrument System (ESIS)in lieu ofexisting Meggitt Mk II Secondary Flight Display (SFD) System.The existing Meggitt Mk II SFD (part number 39221-01-01) is removed andreplaced with L3 GH-3900.2 ESIS (Partnumber 9200-34500-0401.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Hawker Beechcraft Ltd., UK<(>,<)> Change document no SC0413A at issue 3<(>,<)>-Hawker Beechcraft Ltd., UK, Instructions for Continued Airworthinessdocument no ASC-R-018-AW4121 atIssue 1<(>,<)>-Hawker Beechcraft Ltd., UK, Aircraft Flight Manual Supplement documentno HBL-90-1 at Issue 1<(>,<)>or lat...	None	03/08/2012	Active	10040927
10040934	EIRTECH AVIATION SERVICES LIMITED	REV. 1		737-600,-700,-800,-900,-900ER	Cabin Altitude and Take-off Configuration warnings and indications -Activation.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The applicant elected to comply with CS 25 Amendment 11The requirements for environmental protection and the associatedcertificated noise...	Eirtech Aviation Services Ltd Change ERT/CNG/153, Master Data ListMDL/ 153-099 Issue 9or later revisions of the above listed documents approved by EASA	This change is not applicable to an aircraft with High Altitude LandingCapability.	26/10/2012	Active	10040934
10040935	DUNCAN AVIATION, INC.		FAA STC ST00600CH-D	MF 900 & F900EX	EASA validation of FAA STC ST00600CH-D issue dated 12 Sept 2008Installation of Honeywell Enhanced Ground Proximity Warning System withWindshear Detection and optional Terrain Display (S/W level -218-218)and optional Runway Advisory Awareness System (RAAS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Duncan Aviation Master Drawing List KA9611-23R, revision J dated July24, 2012FAA approved Airplane Flight Manual Supplement, KA9611-27R, Revision E,dated April 2, 2004, FAA approved May 18, 2004or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/...	As per FAA STC ST00600CH-D issue dated 12 Sept 2008	06/08/2012	Active	10040935

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040937	F&M ENTERPRISES INC.		FAA STC SE7559SW	2. C090 SERIES, O-200 SERIES 1. C-75 SERIES, C-85 SERIES	Install adapter to permit use of a spin-on oil filter in accordance withF. & M. Enterprises' Installation Instructions for Model TAF-Long OilFilter, dated October 26, 1998, or later FAA approved revision.EASA Validation of FAA STC SE7559SW	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Installation Instructions for Model TAF-Long Oil Filter, dated October26, 1998FM2007-01 Instructions for Continued Airworthiness, Rev. B, dated May09, 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis d...	Engines modified in accordance with this STC will not differ inperformance or operating limitations for unmodified engines.Only the following filters are eligible for this installation:Champion No. CH48108A.C No. OF-53A	06/08/2012	Active	10040937
10040938	F&M ENTERPRISES INC.		FAA STC SE09356SC	3. IO-520 SERIES 2. IO-470 SERIES 1. O-470 SERIES	Install F. & M. Enterprises' Model C6LC, C6LC-S, or C6LC-L oil filteradapter for a spin-on oil filter in accordance with F. & M. Enterprises'Installation Instructions dated October 26, 1998, or later FAA approvedrevision.EASA Validation ofFAA STC SE09356SC	The Certification Basis for the original product remains applicable tothis certificate/ approval.	C6LC<(>,<)> C6LC-S, C6LC-L Installation Instructions dated Oct 26, 1998FM2007-01 Instructions for Continued Airworthiness, Rev. B, dated May09, 2011or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision...	None	06/08/2012	Active	10040938
10040939	F&M ENTERPRISES INC.		FAA STC SE8409SW	5. TSIO-360 SERIES 4. IO-360 SERIES 3. GO-300 SERIES 2. C-145 SERIES, O-300 SERIES 1. C-125 SERIES	Installation of F. & M. Enterprises Model CO-300 or C6SC spin-on oilfilter adapter, in accordance with F. & M. Enterprises installationinstructions for Model CO-300 dated October 26<(>,<)> 1998, or ModelC6SC dated October 5, 2005, or laterFAA approved revisions.EASA Validation of FAA STC SE08409SW...	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Installation Instructions for Model CO-300 dated October 26<(>,<)> 1998Installation Instructions for Model C6SC dated October 5, 2005FM2007-01 Instructions for Continued Airworthiness, Rev. B, dated May09, 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA E...	Engines modified in accordance with this STC will not differ inperformance or operating limitations for unmodified engines.	06/08/2012	Active	10040939
10040949	MICRO AERODYNAMICS, INC.	REV. 2	FAA STC SA01161SE	PA-32S-300, PA-32R-300 PA-32-260, PA-32-300	Installation of Vortex Generators on the wing and tail surface accordingto drawing package MA2174, revision IR dated 06-Sep-2002 andinstallation manual MA2175 revision A dated 27-Aug-2003 or later FAAapproved revision to either of these documents.	The Certification Basis of the original product remains applicable tothis change.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved drawing package MA2174, revision IR dated 06-Sep-2002.FAA Approved installation manual MA2175 revision A dated 27-Aug-2003.Instruction for continued airworthiness MA0666."or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (ort...	If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.If more than 5vortex generators are damaged or missing, the A/C is notairworthy.	11/09/2012	Active	10040949
10040951 (EASA STC NO. 1426)	LEARJET Inc.	REV. 1	FAA STC ST01122SE-D	LEARJET 35/35A/36/36A	Group Aircraft Approval for RVSM.Validation of FAA STC ST01122SE-D dated 14 April 2010.Note: This approval constitutes an update to EASA STC ref. N° 1426 dated2 December 2003 (LBASTC TA0751, dated 27 November 2003) in order toreflect the compatibility of this STC's installation with other STCsliste...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AeroMech Document AMI-QD-LJ-0213, Rev "new", dated May 2,2003;- Master Document List BAS35015040, Rev B, dated May 19, 2004;- Airplane Flight Manual Supplement AeroMech document AMI-03-ALJ3536SRev "original", FAA approved May 8, 2003;- Instructions for Continued Airworthiness AeroMech documentAMI...	The following items listed in the Limitations and Conditions section ofthe FAA STC ST01122SE-D, dated April 14 2010, are excluded from EASAapproval of this STC, because they are related to a configuration(C-21A) that has not been validatedby EASA:§ 4 Group of STCs according to table, the "ST00033MC...	07/08/2012	Active	10040951

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040955	AIRBORNE TECHNOLOGIES GmbH			P.68 C, P.68 C-TC	Title: Mission cabin configuration P.68 C / Description: This STC consists of 3 steps:Step 1: To install different mission equipment in a Vulcanair P.68aircraft, step 1 modifies the aircraft cabin and installs provisions toaccommodate Mission Equipment.Step 2: Optional installation of an equipment mo...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Change Dossier - Supplemental Type Certificate" Doc. No. STC-AT-050,Rev. 3Supplement to the AFM -Step 1, Doc No. AFM1-STC-AT-050, Rev. 1Supplement to the AFM -Step 2, Doc No. AFM2-STC-AT-050, Rev. 0Supplement to the AFM - Step 3, Doc No. AFM3-STC-AT-050, Rev. 0Supplement to the AMM - Step 1, Doc. No.S...	Vulcanair SB-163 must be carried out prior this STC.	07/08/2012	Active	10040955
10040961	ANUVU	REV. 3		A310-322/-304/-324/-308/-325 A300 SERIES, A310 SERIES A300 F4-605 R/-622 R A300 C4-620/-605 R VARIANT F A300 B4-620/-622/-622 R A300 B4-601/-603/-605 R	Implementation of provisions for EFB Class2, NavAero T.Bag C2 inaccordance with Aero Vodochody MDL AM003-MDL Rev 4.Rev.1: Installation of power switches to the 28V DC bus for safe poweroff for the EFB-system.Rev. 2: Name change of the DOA.Rev. 3: Transfer of STC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI H-01 Enhanced Airworthiness Programme forAeroplane system – Instructions for Continued Airworthiness on EWISThe requirements for environmental pr...	Documents for initial issue of this approval:Aero VodochodyMaintenance Manual Supplement AM003-MM, Rev. 02Aero Vodochody Aircraft Flight Manual Supplement AM003-AM, Rev. 05Aero Vodochody Wiring Diagram Supplement AM003-WMS, Rev. 03Aero Vodochody Instruction for Continued Airworthiness AM003-CA, Rev...	For MSN 0554, 0560, 0614 and 0667, Revision 1 of this approval is validonly under the following condition: accomplishment of installation ofswitches according to Aero Vodochody Minor Change A-STC-Z 0058 for MSN0554, A-STC-Z-0059 for MSN 0560, A-STC-Z 0060 for MSN 0614 and A-STC-Z0057 for MSN 0667.Fo...	05/05/2021	Active	10040961
10040968	B/E AEROSPACE, Inc.		FAA STC ST02876CH	B767-200/-300/-300F/-400 ER	Installation of BE Aerospace Inc. Vacuum Toilet Assembly Retrofit Kit	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	BE Aerospace Installation Instructions, AMM 38-30-07, Revision 01,11/08/2011.BE Aerospace ICA document, AMM 38-30-08, Revision 01, 11/04/2011or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	09/08/2012	Active	10040968
10040970	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	B737-400	B737 TCAS Change 7.1 Update.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS25 Amendment 11	Master Data List BA-737-34-0016-MDL Issue 00 dated 01May12;or later revisions of the above listed documents approved byEASA.	None.	09/08/2012	Active	10040970
10040972	HAECO CABIN SOLUTIONS, LLC		FAA STC NO. ST03928AT-D	777-300	Audio/Video On-Demand & In-seat Power System Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	TIMCO Aerosystems Instructions for Continued Airworthiness 11T133R009,Rev. A dated September 29, 2011or later revision of the above listed document approved by EASA inaccordance with EASA ED Decision 2004/04//CF (or subsequent revisions ofthis decision)	none	10/08/2012	Active	10040972
10040973	SCANDINAVIAN AVIONICS DESIGN ApS			ATP	FMS Upgrade for P-RNAV	CS 25 Amendment 4The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the origi...	Scandinavian Avionics Engineering Order 2071338-EO Issue 1 dated 05Jul12Flight Manual Supplement 2071338-AM Issue 1 dated 29May12Continued Airworthiness 2071338-CA Issue 1 dated 05Dec11or later revisions of the above listed documents approved by EASA	none	10/08/2012	Active	10040973

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10040974	JET AVIATION AG, BASEL	REV. 1		A330-223, A330-243 A330-201, A330-202, A330-203	EMS Satcom AMT-3800 antenna installation.This modification installs EMS Satcom AMT-3800 high gain antenna,Diplexer Low Noise Amplifier, and associated structural provision.The revision has withdrawn the STC limitations following additionalsubstantiations delivery.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, ref : BA33023261-001, Revision EInstruction for Continued Airworthiness, ref : BA33023261-150-01,Revision CWeight & Balance Statement, ref : BA33023261-121-01.orlater revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	23/01/2013	Active	10040974
10040981	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A340-541	VIP Cabin RefurbishmentThe modification consist of the following items:-,,Refurbishment of existing cabin materials-,,Deletion of a double seat and installation of aft stowage-,,Installation of a book cabinet-,,Upgrade of the IFE equipment(monitors, players, switch panels, etc.)-,,Upgrade Airshow 4...	JAR 25,, Amdt: 14The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.SCs or ESFs:-,,CRI A-1301-003, Existing Exemption & Deviation, ESF/Deviation-,,CRI D-1310-005, Glass Screens of Displays...	- Master Document List, Doc. No. S.OAEV.000008-MDL, Rev_01-AFMS, Doc. No. S.OAEV.000008-AFM, Rev_00- ICA, Doc. No. S.OAEV.000008-ICA, Rev_00or later revisions of the above listeddocuments approved by EASA	none	20/04/2021	Active	10040981
10040999	ASI INNOVATION			EMB-135LR	Oven installationDescription as per:ASI SDL, STC Data List ref. ASI-SDL-0087-03, dated 01/08/2012.ASI MDL, Master Drawing List ref. ASI-MDL-0087-01, dated 01/08/2012.ASI TechnicalDossier ref. ASI-TD-0087-02, dated 01/08/2012.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASI SDL, STC Data List ref. ASI-SDL-0087-03, dated 01/08/2012.ASI MDL, Master Drawing List ref. ASI-MDL-0087-01, dated 01/08/2012.ASI Technical Dossier ref. ASI-TD-0087-02, dated 01/08/2012.or later revisions of the above listed documents approved by EASA	Applicability limited to EMB-135LR S/N 886	14/08/2012	Active	10040999
10041017	HONEYWELL INTERNATIONAL INC.	REV. 1	FAA STC SR02569NY	AS350B, AS350BA, AS350B1 AS350B2, AS350B3, AS350D	Installation of Sky Connect Tracking System in accordance with MasterDrawing List MDL07094.Revision 1 of the STC is issued to reflect a change of STC Holder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Definition and installation, Inspection and Maintenance:-Avionics Design Services Ltd. Master Drawing List MDL07094 Rev. C,Issue 1, dated July 02, 2008-Avionics Design Services Ltd. Instructions for Continued AirworthinessICA07094-1 Rev. B, dated January 09, 2009or later revisions of the above list...	This STC is not applicable to AS350B3 model helicopters withmodification OP4305 (Arriel 2D engine installation) incorporated.Prior to installation of this design change it must bedetermined thatthe interrelationship between this design change and any otherpreviously installed design change and/ ora...	29/10/2015	Active	10041017
10041028	HOWARD J. FULLER, JR.	REV. 1	FAA STC SR00086BO	R44	Operation of rotorcraft on unleaded automotive gasoline, 91minimumantiknock index (RON + MON)/2 per ASTM SpecificationD-439 or D-4814 inaccordance with Howard. J. Fuller Installation Instructions No HJF97044.(This STC is based on FAA STCSR00086BO dated July 25, 2002)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Howard. J. Fuller, Jr., Rotorcraft Flight Manual SupplementNo. 44-1,Rev. 2, dated July 25, 2002or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisdecision) Howard. J. Fuller Installation Instructions No HJF9...	1. This approval is limited to those model helicopters equipped withLycoming O-540-F1B5 engines modified IAW STC SE00663WI(EASA.IM.E.S. 01002). This approval is applicable only with the followingengine power ratings:-,,Maximum Continuous Power 205 HP (24.7 in. Hg.) @ 2692 RPM-,,Takeoff 225 HP (26.3 i...	17/08/2012	Active	10041028
10041031	BOMBARDIER INC.		TCCA STC NO. O-LSA02-400	BD-700-1A10	Chairman Interior Installation	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. O-LSA02-400 Issue 6 dated 29 June 2012.DECA Aviation Engineering Limited Modification Summary MS01050, Revision7 dated 28 April 2003.Aero Consulting Services Ltd. Modification Data Summary G151000 RevisionN/C.ACS-NAI Ltd. Modification Data Summary G837000 Revision N/ C.ACS-NA...	Restricted to ASN 9003Previous embodiment of JAA (EASA) Accepted Bombardier Service Bulletin700-23-001, Satellite Communications System - Installation is aprequisite.The Public Address System does not comply with requirements of JAR25.1423. It is not usable for any operations that require a PublicAd...	16/08/2012	Active	10041031

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041036	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	B757-200	Cabin Re-configuration and Airvod IFE System Installation	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	H4 Aerospace Modification Summary Sheet, H4A1503, Issue 1, 16/08/2012AFM Supplement, H4AFMS026, Issue IR, 16/08/2012or later revisions of the above listed documents approved by EASA	None	17/08/2012	Active	10041036
10041044	LUFTHANSA TECHNIK AG			737-800	VIP Cabin Interior Completion BBJ2	The Certification Basis for the original product and the followingadditional oralternative airworthiness requirements are applicable to thiscertificate/ approval.Additional requirements are detailed in CRI A-01 Issue05, in particular:Special Conditions:- CRI D-02 Isolated compartments- CRI D-10 Gl...	- Supplemental Type Definition Document STDD00-10/12M, Issue 01, Rev 00- Aircraft Flight Manual Supplement A-00-11/006-AFM,Issue 05, Rev 00- Instructions for Continued Airworthiness A-00-11/006-ICA, Issue 05,Rev 00or later revisions of theabove listed documents approved by EASA.	1) As per AFM limitations A-00-11/006-AFM, Issue05, Rev 00 :- The aircraft is certified for non-commercial use.- Required Crew: in case passengers are on board one (1) cabin attendantis required and has to be seated at door 1, left hand side.- Cabin WLAN: the use of wireless LAN devices - including...	17/08/2012	Active	10041044
10041049	AVIONIK STRAUBING ENTWICKLUNGS GmbH			DA40, DA40D, DA40F	Dual/Single Installation of Garmin GPS/ COMM/NAV GNS430W / GNS530W.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23, Amendment2The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	Flight Manual Supplement ASR-2012-052-FMS-05-00, Rev. 00;orlater revisions of the above listed documents approved by EASA.Instructions for Installation ASR-2012-052-IFI-10-00, Rev. 00;Instructions for Continued Airworthiness ASR-2012-052-ICA-11-00, Rev.00.	None.	17/08/2012	Active	10041049
10041062	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03771AT-D	GV-SP	Installation of an Airplane Interior	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.-CRI D-50 "Seat deformation into the overwing Emergency Exits andEmergency Egress." - Equivalent Level of Safety/MoC-CRI F-55 "In cabin /...	-FAA STC ST03771AT-D issued 5th May 2010-Installation in accordance with Gulfstream Aerospace Corporation IndexList GC520005266, Revision C, dated May 5, 2010-Operation to be in accordance with Gulfstream Flight Manual SupplementGC51468M012 , Rev. NC, dated May 5, 2010or later revisions of the abovea...	Limitations are defined in document GC522040593, "Follow-OnInstallationGuide", Revision NC, dated May 5, 20101. The installer must determine whether this design change is compatiblewith previously approved modifications.2. If the holder agrees to permit another person to use this certificateto alte...	20/08/2012	Active	10041062
10041063	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02884AT-D	GV	Installation of a Transponder Flight Identification	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC ST02884AT-D, amended 21st October 2009-Installed in accordance with Gulfstream Aerospace Corporation IndexListCE51 1268000, Revision J, dated October 21, 2009-Airplane Flight Manual Supplement CE51 126M000, Revision NC, dated July12, 2004-Airplane Flight Manual Supplement CE51 126M001, Rev...	None	20/08/2012	Active	10041063
10041087	AERODISA S.L.			DC 9-87, MD88 DC9-81, DC9-82, DC9-83,	Equipment update for MD80 series SatCom System - Update forMD80 SeriesSatCom System approved under EASA STC	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalCRI H-001The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original produ...	Aerodisa Doc. AED2011_14_MDL Master Data ListAED2011_14M_AFMS Aircraft Flight Manual Supplementor later revisions of the above listed documents approved by EASA.	This STC is applicable only to aeroplanes that have alreadyincorporatedAerodisa STC certified as EASA STC 10031538 dated 24 August 2010	20/08/2012	Active	10041087

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041096	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09537RC-D	429	Installation of High Frequency (HF) Antenna Kit (P/N 429-007-001) forBell Helicopter Textron Model 429 Helicopters.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Rotorcraft Flight Manual Supplement Report No. AA-11021 Rev. NR, datedJune 22, 2011;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).- Bell Helicopter Drawing List Report No. AA-11015 Rev. D, dat...	Only the installation of the HF Antenna Kit is included in this STC. Theantenna is capable of interfacing with many different types of HFradios; therefore, the compatibility of anHF radio installation withthe HF Antenna Kit is the responsibility of the installer and shall becovered by a separate ap...	22/08/2012	Active	10041096
10041097	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR00739DE	429	Installation of Sliding Door Push-Out WindowsKit (P/N 429-563-001/2/3/4/5/6/7/8/9)for Bell Helicopter Textron Model 429Helicopters.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Drawing List Laz-Tec, LLC Report No. AA-11062 Rev. B, dated November23, 2011, FAA Approved December 19, 2011;- Instructions for Continued Airworthiness Laz-Tec, LLC Document No.AA-11065 Rev. A dated December 02, 2011, FAA accepted December06, 2011.	None.	22/08/2012	Active	10041097
10041098	SNAKY CREEK ENTERPRISES, LLCd/b/a SPECTRUM AEROMED		FAA STC SA02488CH	PC-12/47 PC-12/45 PC-12	Air Ambulance ConversionInstall air ambulance conversion inaccordance with Spectrum AeromedInc. Master Drawing List 6045DL, dated July 23, 2007 or later FAAapproved revisions.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved Aircraft Flight Manual Supplement, 6045FMS, dated September21, 2007;FAA accepted Instructions for Continued Airworthiness, Manual 6045MM,dated May 30, 2007;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revi...	None.	21/08/2012	Active	10041098
10041101	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04263AT-D	GV-SP	Executive Completion, Multiple STC.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-,,CRI D-50 "Seat deformation into the overwing Emergency Exits andEmergencyEgress." - Equivalent Level of Safety/ MoC-,,CRI F-55 "In cab...	-,,FAA STC ST04263AT-D issued 14th August 2012;-,,Installation in accordance with Gulfstream Aerospace CorporationIndexList GC522048017, Revision A, dated August 14, 2012;-,,Operation to be in accordance with Gulfstream Flight ManualSupplement GC52204M081, Rev. -, dated August 14, 2012;-,,Instructi...	Limitations are defined in document GC522043055, "Follow-OnInstallationGuide", Revision NC, dated August 7, 20121.,,The installer must determine whether this design change iscompatible with previously approved modifications.2.,,If the holder agrees to permit another person to use thiscertificate to...	21/08/2012	Active	10041101
10041121	AIRCRAFT WHEEL AND BRAKE, LLC		FAA STC SH363NE	SA 365N, SA 365N1 AS 365N2, AS 365N3	Installation of Parker 1C44-2 fuel pump in accordance withInstallation Manual SP1C44-2.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation Instructions Airborne SP1C44-2 Fuel Boost Pump, revisionB, dated August 17,2000.	None.	22/08/2012	Active	10041121
10041124	BELL HELICOPTER TEXTRON, Inc.		FAA SR00740DE	BELL 429	Installation of Aft Cabin Floor Protectors Kit (P/N 429-457-001) forBell Helicopter Textron Model 429 Helicopters.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Drawing List Laz-Tec Report No. AA-11059 Rev. B dated December 07,2011, FAA Approved December 16, 2011.- Instructions for Continued Airworthiness Laz-Tec, LLC Document No.AA-11061Rev. A, dated December 02, 2011, FAA accepted December 06,2011.	None	22/08/2012	Active	10041124

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041125	BELL HELICOPTER TEXTRON, Inc.		FAA SR00741DE	BELL 429	Removable Crew Door Installation Kit (P/N 429-650-001/3/4) for BellHelicopter Textron Model 429 Helicopters.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Flight Manual Supplement, Document No. AA-11070, Revision NR, datedJanuary 19, 2012, FAA Approved January 19, 2012.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)-Drawing List Laz-Tec Report No...	None	22/08/2012	Active	10041125
10041143	MOTORFLUG BADEN-BADEN GmbH			204B	Exchange of engine torque and temperature indicator.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS29 change 1 dated 30 November 2007:29.1, 29.29, 29.305, 29.361, 29.561, 29.601, 29.603, 29.607, 29.609,29.611, 29.613, 29.619, 29.625,2...	127472-01-0601 revision 0 dated 13 August 2012, Flight Manual SupplementApplicable revisionsor later revisions of the above listed documents approved by EASA127472-01-1001 revision 0 dated 13 August 2012 - Installation Manual; 127472-01-0109 revision 4 dated 21 August 2012 - Master Document List; 1274...	none	23/08/2012	Active	10041143
10041145	AIRCRAFT WHEEL AND BRAKE, LLC		FAA STC SH362NE	AS355F2 AS355E, AS355F, AS355F1,	Installation of Parker 1C44-2 Fuel Pump	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions for 1C44-2 Centrifugal Fuel BoostPump -revision B dated 17 August 2000.	None	23/08/2012	Active	10041145
10041148	AIRCRAFT WHEEL AND BRAKE, LLC		FAA STC SR153CH	AS 332 L, AS 332 L1	Installation of Parker 1C64-15 Fuel Pump	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions for 1C64-15 Centrifugal Fuel Boost Pump -revision - dated 25 March 2002.	None	24/08/2012	Active	10041148
10041159	MILLENNIUM CONCEPTS, INC.	REV. 1	FAA STC SA01671WI - D	2- G58 - BARON 1- G36 - BONANZA	Installation of interior configuration per Master Drawing List2033-MDL040, rev. P, dated 8 February 2012.	Design:Non-significant change.The Certification Basis of the original product and the followingadditional airworthinessrequirements are applicable to this change.As defined in the STC certification basis approved by FAA.Environmental Protection:The certificated noise and/ or emissions levels of the...	FAA approved Master Drawing List 2033-MDL040, rev.P, dated 8 February2012;FAA Approved AFM Supplement 2033-AFMS-S1 dated 8 February 2012 (For G36Bonanza);FAA Approved AFM Supplement 2033-AFMS-S2 dated 8 February 2012 (For G58Baron);Instruction for continued airworthiness 2033-ICA003 rev.A (For G36Bo...	If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.	27/08/2012	Active	10041159
10041160	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			B95, B95A, D95A, E95 95-C55A, D55, D55A, E55, E55A, 95-B55A, 95-B55B, 95-C55, 95-55, 95-A55, 95-B55, 56TC, A56TC, 58, 58A, G58, 95,	Installation of Garmin GNS 430 W system, GA 35 GPS antenna,GMA 340audiopanel and Mid Continent MD 41 annunciator according to SEAMmodification n°3823/12.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23 Amdt 2The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificat...	SEAM Flight Manual Supplement n°SEAM-SMV 3823/12, revision 0 dated02/05/2012SEAM modification file n°3823/12 revision 0dated 02/05/2012or later revisions of the above listed documents approved by EASA.	Installation of this design change must be performed by authorised SEAMtechnical personnel.This installation is approved for BRNAV operations without coupling toan autopilot.Used of GPS for SID/STAR and approach procedures is not authorised.Software upgrades introducing new functions at equipment le...	24/08/2012	Active	10041160

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041163	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	P2006T	Wingtip pyrotechnics & LED lights.	CS - 23 Issue 2The Certification Basis for the original product remains applicable tothis certificate/ approval.CS - 23as per TCDS EASA.A.185 Major.	Certification Plan - CP-1305 issue 1;Substantiation report SUB-1306 issue 1;Flight test Report FTR-1306;Master Documents List - MDL-1306;Flight Manual Supplement AFMS-1306;Instructions for Continued Airworthiness ICA-1306;or later revisions of the above listed documents approved by EASA.	As per: Flight manual supplement AFMS -1306 & Instructions for ContinuedAirworthiness ICA-1306.	24/08/2012	Active	10041163
10041170	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV. 1	CAA UK RESPONSIBILITY	A109A II	AVIONICS UPGRADE FOR A109A IIInstallation of 2 x Garmin GNS430 Nav/ Com/GPS, 1 x Garmin GTX327Transponder, 1 x Garmin GMA340 Audio Panel, Skymap KMD150 and Kannad 406AF-H ELT. AlsoKing KNI 582-01. Removal of 2 x Collins Comms, 2 xCollins Navs, Collins Transponder, 2 x RMI, 2 x Audio Boxes, King GPS....	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SLOANE FLIGHT MANUAL SUPPLEMENT No. 11or later revisions ofthe above listed documents approved by EASADOCUMENTATION OFMODIFICATION P055/109/MO	ONE PLACARD WITH THE WORDS "GPS LIMITED TO VFR ONLY" POSITIONED ON THEINSTRUMENT PANEL NEAR THE KMD 150	03/09/2012	Active	10041170
10041183	DASSAULT FALCON SERVICE			MYSTERE-FALCON 50	Mode S transponder upgrade to comply with Elementary and EnhancedSurveillance.Honeywell transponder MST-67A version is upgraded and ATC/TCAS ControlBox is replaced by new Honeywell PS-578A unit.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet DFS5712-CAS Issue A dated July 31st<(>,<) >2012.DFS Modification Sheet DFS5712, Issue A dated July 31st, 2012.DFS Airplane Flight Manual Supplement N°F50-62 dated July 31st, 2012.or later revisions of the above listed documents approved by EASA	none	28/08/2012	Active	10041183
10041185	AVIDYNE CORPORATION		FAA STC SA00282BO	SR20, SR22	Installation of Avidyne Corporation 700-00083-XXX Entegra IntegratedFlight Display System on Cirrus SR20 and SR22 according Avidyne Doc. NoAVIFD-006 in latest FAA approved Revision	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.For those portions of the airplane that are unchanged from the basicSR20/ SR22 the applicable certification is in accordance with EASA Ty...	In accordance with Avidyne Master Document List AVIFD-005Avidyne AFM-S Document 600-00712-000Avidyne Instructions for Continued Airworthiness AVIFD-016Avidyne Installation Manual 600-00160-000or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04...	As indicated in FAA STC SA00282BOEnhanced Vision System (EVS) is not included in the scope of thisapprovalCompatibilitywith Mode 5 alerts must be shown when a TAWS Class A isinstalled.	28/08/2012	Active	10041185
10041205	THALES AVIONICS Inc.		FAA STC ST02431LA	A321-232 A321-213, A321-231, A321-211, A321-212,	Installation of Thales Avionics IFS TopSeries In-Flight Entertainment(IFE) System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA Supplemental Type Certificate ST02431LA issued 9th August 2012- PSCP-2011-1001 Rev.F, dated 9th July 2012- Index List 255058 Rev.B, dated 8th August 2012- Reference Data List 500440-103RDL Rev.J, dated 18th July 2012- Master Drawing List 500440-103MDL Rev.T, dated 8th August 2012- Instructions...	This STC must be installed in conjunction with EASA STC 10040704 -Aerospace Engineering Solutions (AES) - Introduction of Twin Class CabinConfiguration	29/08/2012	Active	10041205

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041215	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09541RC	407	Passenger Sliding Doors Kit P/N 407-270-003 for Bell Helicopter TextronModel 407 Helicopters.Reference FAA STC SR0941RC.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement for Passenger SlidingDoors KitP/N 407-270-003, Report No. AA-10101 Rev. NR, dated April 10, 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).- Master Dr...	1. The Passenger Sliding Doors Kit P/N 407-270-003 modifiesthe hingedpassenger doors for the Bell Helicopter Textron Canada Limited (BHTCL)Model 407 Helicopters. A Personnel attachment Fixture mounted in thepassenger compartment is not intended to secure cargo or supportrappelling operations.2. Ins...	30/08/2012	Active	10041215
10041217	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09540RC	407	Crew Area Hardpoints Kit BHTI P/N 407-240-001Internal Hardpoint Kit BHTI P/N 407-638-001External Hardpoint Kit BHTI P/N407-230-001 and P/N 407-230-100Pylon Hardpoint Kit BHTI P/ N407-854-001/2/3Reference FAA STC SR09540RC	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement for External Hardpoint KIT P/ N407-230-001 and P/N 407-230-100, Report No. AA-10114 Rev. NR, datedApril 10, 2012- Rotorcraft Flight Manual Supplement for Pylon Hardpoints Kit P/ N407-854-001/2/3 Report No. AA-10121 Rev. NR, dated April 10, 2012or later revisions o...	1. High skid landing gear is required for BHTI P/N 407-638-001 ExternalHardpoint Kit installation.2. Installation of BHTI P/N 407-270-003 Passenger Sliding Doors Kit (separate STC)is a co-requisite for BHTI P/N 407-854-001/2/3 PylonHardpoints Kit installation. 3. The present STC makes provisions ford...	30/08/2012	Active	10041217
10041234	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01105LA-D	GV	Installation of a 13 Passenger Cabin Interior	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA STC ST01105LA-D, issued 26th June 2001- Installed in accordance with Gulfstream Aerospace Corporation IndexList ref. GC520008262, Revision A, dated 25th June 2001or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revis...	The approval of this modification applied only to Model GV S/N 622	31/08/2012	Active	10041234
10041237	STANDARD AERO	REV. 2	FAA STC ST03038CH-D	GV	Reconfiguration of a Cabin Floorplan Arrangement	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC ST03038CH-D issued 19th December 2011-Installationin accordance with Standard Aero Master Data List - MDL1021004, Revision H, dated 19th December 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions oft...	1. The installer must determine whether this design change is compatiblewith previously approved modifications.2. If the holder agrees to permit another person to use this certificateto alter the product, the holder shall give the other person writtenevidence of that permission.3. It is the installe...	05/09/2012	Active	10041237
10041238 (EASA.IM.A.S.01208)	BOMBARDIER INC.	REV. 1	TCCA STC C-LSA05-104/D	BD700-1A10	Cabin Interior Completion / Furnishings	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ref.: Limited Supplemental Type Certificate by TCCA - No. C-LSA05-104/DFM-S: G-FM25000127 A*ALI: G-TM05100066 N/C*FCOM-S: G-MS25000019 N/ C*ICA: GC91470001-IFCA*or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions oft...	Restricted to ASN 9147	17/09/2012	Active	10041238

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041239 (EASA.IM.A.S.01230)	BOMBARDIER INC.	REV. 1	TCCA STC C-LSA05-169/D	BD700-1A10	Passenger Occupancy of the Crew Rest Area	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ref.: Limited Supplemental Type Certificate by TCCA - No. C-LSA05-169/DFCOM-S: G-MS25000020 N/C**or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/02/CF (or subsequent revisions ofthis decision).	Restricted to ASN 9147	17/09/2012	Active	10041239
10041241	B/E AEROSPACE, Inc. - FSI	REV. 2	FAA STC ST01941SE	A300 B4-620/-622/-622R A300 B4-601/-603/-605R	Validation of FAA Supplemental Type Certificate (STC) ST01941SE.Conversion of an Airbus A300B4-600 series aeroplane from a passengerconfiguration to a freighter configuration (including main deck cargodoor, interior, and associated systems), in accordance with FlightStructures, Inc. Certification Pl...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):Special Conditions CRIs: D-01Cargo Barrier Net and Occupants, D-02Design Standards for Fuselage Doors, E-01 Class E Cargo CompartmentsFire Protectio...	Flight Structures, Inc Master Drawing List (MDL) A5FS524-D01, RevisionBV, dated July 2014B/E Aerospace A300-600 Aeroplane Flight Crew Operating Manual SupplementDocument TP5-524FCOM Revision 4.B/E Aerospace A300-600 Airplane Flight Manual Supplement DocumentTP5-524 AFM Revision 1.AAR Instructions Fo...	-For those aeroplanes that were passenger-to-freighter converted inaccordance with the initial issue or revision 1 of this STC:-Before further flight after 13 August 2014, the three A300B4-600series model aeroplanes, Manufacturer Serial Number (MSN) 734, 739 and756 shall be modified to embody Fli...	13/08/2014	Active	10041241
10041261	AIRBUS HELICOPTERS, Inc.	REV. 1	FAA STC SR09104RC-D	EC135 P3, T3 EC135 P1, P2, P2+, T1, T2, T2+	Installation of a pulsed engine and gearbox chip detector system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Drawing List 135A82-8009, Revision U, dated 17 November 2017, or laterODA approved revision.- Instructions for Continued Airworthiness (ICA) 135MMS-008, Rev. I,dated 20 December2017, or later ODA or AEG accepted revision isrequired.- For EC135 P1, P2, T1, and T2 models, Rotorcraft Flight ManualSu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/03/2018	Active	10041261
10041267	BOMBARDIER INC.	REV. 1	TCCA STC SA03-113	CL-600-2B16	Installation of Complete Customized Aircraft Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aero Consulting Services Ltd. Configuration Definition List ref.D817000 dated 19 Jan 2007, Revision AD;- Aero Consulting Services Ltd. Airplane Flight Manual Supplement AFMSD817090 rev A;- Mandatory Maintenance Manual Supplement ref. D817070. Rev A andTE-XXXX5000-SMM : Supplemental Maintenance Man...	This STC is limited to aircraft Bombardier CL-600-2B16 (604variant),Serial Number 5580, 5589, 5591, 5628, 5636 and 5655.	14/12/2012	Active	10041267
10041271	BUCHER LEICHTBAU AG	REV. 1	FOCA STC 25.20.42 ISSUE 5	SEE APPROVED MODEL LIST	ATL Airtransport Litter System P/N 123000 - Seriesincludingcustomers options:P/N 123000-000 (Demo ATL)P/N 123000-110 (Lufthansa)P/N 123000-241 (AUA-2)P/N 123000-271 (Emirates-2)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Component Maintenance Manual E016-10-96 Rev 01, replaced by:Component Maintenance Manual E016-21-12 Rev 00, dated August 31, 2012User Manual E017-01-94, Rev 02, replaced by:User Manual E017-03-12 Rev 00, dated July 31, 2012Master Document Register TS27 RG Revision A, replaced by:Master Document List...	1. This STC does not constitute an approval for installation. Compliancewith following requirements below need to be demonstrated by a designapproval for Stretcher installation inaircraft per applicable approvedmodel list:JAR 25.561(d)JAR25.785 (a), JAR 25.785(h)(1), JAR 35.785(d)JAR 25.791JAR 25.8...	15/03/2013	Active	10041271

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041273	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBIL ITY	747-400	B747-400 TCAS change 7.1 update	The Certification Basis for the original product remains applicable tothis certificate/ approval.CS25 Amendment 11The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate...	Master Data ListBA-747-34-0008-MDL Issue 00 dated 12Jun12orlater revisions of the above listed documents approved by EASA	none	03/09/2012	Active	10041273
10041282	AVIONICS INTEGRATION & ENGINEERINGCO RPORATION AG (AIEC)			CL-600-2B16	CPDLC System Capability	FAR 25The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirementsfor environmental protection and the associatedcertificatednoise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	Master Data List: AC5211-049 Rev B dated 03Sep12Airplane Flight Manual Supplement: AC5211-071 Rev BInstructions for Continued Airworthiness: AC5211-085 Rev A dated 27Aug12Compliance Declaration: AC5211-016 Rev IR dated 03Sep12CertificationCompl iance Sheet: AC5211-075 Rev B dated 03Sep12or later rev...	CPDLC system not compliant with Commission Regulation (EC) 29/2009	04/09/2012	Active	10041282
10041283	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR02405LA	407	Survivor Window Raft Kit P/N 407-567-002 for Bell Helicopter TextronModel 407 Helicopters.Reference FAA STC SR02405LA.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Rotorcraft Flight Manual Supplement to the Bell 407 Helicopter FlightManual when equipped with the Survivor Window Raft Kit. Document No.AA-10078 Rev. NR, dated December 6, 2011.or later revisions of the above listed documents approved byEASA inaccordance with EASA ED Decision 2004/04/CF (or subse...	None	04/09/2012	Active	10041283
10041311	NSE	REV. 2		MBB-BK117 C-2, MBB-BK117 D-3 MBB-BK 117 C-2	Night Vision Imaging System (NVIS) certification in order to enableNight Vision Goggles (NVG) operation on MBB-BK117 C-2 helicopters.Revision 1: NVIS certification on MBB-BK117 D-3 helicopters withconfiguration described in the Configuration Control DocumentCCD-145-33-101-100 Revision 3 dated 26/02/...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Initial issueAirlift A/S Flight Manual Supplement (FMS): FMS-145-33-101-01, Rev. 1,23rd April 2012.Airlift A/S MBB-BK117 C-2 NVIS Lighting System Installation:DO-145-33-101 DesignOrder, Rev. 0,25th August 2011.Airlift A/S Instructions forContinued Airworthiness: ICA-145-33-101-01,Rev. 1, 27th Augu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Initial issue Refer to applicable FMS for list of equip...	16/07/2025	Active	10041311
10041316	ARMSTRONG AEROSPACE Inc.	REV. 1	FAA STC ST03086CH	B747-400	Installation and activation of a Panasonic Global Communication Suite(GCS) System<(>,<)> including the Panasonic eXPhone system in accordancewith Armstrong Aerospace Master Data List Doc. No. DC 104-9034-00Revision H, dated December 14, 2012.The addition (installation and activation of the eXPhone s...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:For the areas of change: the following requirementis complied with atamendment 45 of FAA 14 CFR Part 2525.571(a) - (b)For the areas of change: the following requirementst...	- Certification Plan E11058-2500-C001, Rev. D (initial STC)- Certification Plan E12066-2500-C001, Rev. B- Armstrong Aerospace Master Data List: DC104-9034-00 Revision H, datedDecember 14, 2012<(>,<)>- Aircraft Maintenance Manual Supplement: Doc. No. 1000253 revision 1,dated February 1, 2012<(>,<)>-A...	Modification of the aircraft in accordance with this STC requires prioror concurrent modifications in accordance with FAA STCs 10040513 (FAASTC ST03047CH) and 10040305 (FAA STC ST03085CH).FAA approved Airplane Flight Manual Supplement DC303-9034-00 Revision A(configuration A), or DC303-9034-10 Revis...	10/04/2013	Active	10041316

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041328	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02961CH	B737-600/-700/-800/-900/-900ER	Validation of FAA STC ST02961CH - Approved configurations are thefollowing:-Configuration 1: Replacement of Honeywell Weather Radar System RDR-4Bwith Honeywell Honeywell Weather Radar RDR-4000< (>,<)>-Configuration 2: Software upgrade to Honeywell WRS RDR-4000. ExistingWeather Radar Processor will be...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Configurations 1 and 2:- Master Data List ECS-208688, Revision G, dated 23 January 2012-ICA Baseline ECS-208699, Revision D, dated 7 October 2011Configuration 1:-AFM Supplement ECS-208698, Initial release, dated 27 May 2011-EWIS/ICA ECS-209692, Revision B, dated 21 June 2011Configuration 2:-AFM Suppl...	None	07/09/2012	Active	10041328
10041337	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		MYSTERE FALCON 20 E5, 20 GF MF50, MF900 C550 CITATION II	Installation of Iridium Satcom System ICS-120B applicable to DassaultAviation MF900 aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Description as per MDL ref. MDL-008-11 Rev. 2, dated 21/08/2012;AFMS ref. UAE-AFMS-11-003 Rev. 2, dated 21/08/2012;Note: document reference UAE-CD-E-0004-11 Rev. 1 was modified on06/09/2012 to record test results;or later revisions of the above listed documents approved by EASA.	None.	05/01/2015	Active	10041337
10041344	BOMBARDIER INC.		TCCA STC SA12-16	BD-700-1A10	Installation, Aircraft Completion Modifications - ASN 9456.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-16 Issue 2 dated 20 March 2012;Bombardier Configuration Definition Record RAZ-BM700-001 Revision Ydated 27 August 2012;Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC;Instructions for Continued Airworthiness document GC94560000-ICA;or later revis...	Restricted to ASN 9456.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDS). Any other intended function of this equipmentwillrequire a re-examination of the certification basis.	10/09/2012	Active	10041344
10041362	TC INTER-INFORMATICS A.S.	REV. 1		737-800	D27 Cabin layout reconfigurationRevision 1: major update ofthe Instructions for Continued Airworthinessin document D27-D01. Associated technical documentation and STClimitations updated.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Definition document, reference D27-D01 revision 5, dated 30October 2012Project Compliance Checklist, reference D27-D03revision 2, dated 30October 2012Declaration of Compliance, reference D27-D05 revision 5, dated 30October 2012FCOM Supplement to D6-27370-86N-TSF-II revision 0, dated 10 September20...	LimitationsApplicability of this STC is limited to the aircraft serial numberslisted in Definition Document D27-D01.Conditions:Prior to installation of this STC it must be determined that theinterrelationship between this STC and any otherpreviously installedmodification and/or repair will introduc...	05/02/2013	Active	10041362
10041363	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	B757-200/-200PF/-300	Introduction of Antenna Mounting Provision	The Certification Basis for the original product remains applicable tothis certificate/ approval.	S21.MDL-1029 Issue 1S21.ACC-0470 Issue 1S21.TEC-0349 Issue 1S21.COMP-1029 Issue 153-15-10108 Issue A23-00-10256 Issue A23-15-10346 Issue A23-15-10335 Issue Aor later revisions of the above listed documents approved by EASA	None	11/09/2012	Active	10041363

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041373	JAMCO AMERICA, INC.		FAA STC ST02107SE-D	B777-300	Validation of FAA STC ST02107SE-D related to Interior Reconfiguration.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Requirements at a later amendment level than specified in TCDSEASA.IM.A.003 are listed below:§25.853(a)(c)(d)(e)(f) (g) ,,Amdt. 25-116 - e...	Jamco America, Inc. Master Drawing List (MDL) mdl 1724-1, Revision B,dated November 3, 2011;Airplane Flight Manual Supplement, document AFM1724-1, Rev. 1, datedOctober 6, 2011;Supplemental Instruction for Continued Airworthiness (ICA), documentnumber ICA1724-1, Revision 0, dated September 19, 2011;o...	Approval of this change in type design is applicable to theabove modelaircraft only.	11/09/2012	Active	10041373
10041380	INFLIGHT WARNING SYSTEMS, Inc.		FAA STC ST02300LA	B777-200, 200LR, 300, 300ER	Validation of FAA STC ST02300LA related to Installation of Fan VibrationMonitor Unit.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Master Drawing List 217700, Revision D, dated May 21, 2010;Instruction for Continued Airworthiness 13705, Revision A, dated May 21,2010;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	12/09/2012	Active	10041380
10041414	BERINGER AERO	REV. 4		ASW 20 F, ASW 20 FL ASW 20 CL, ASW 20 L ASW 20 C, ASW 20 CL, ASW 20 L ASW 20 BL, ASW 20 C ASW 20, ASW 20 B, ASW 20 BL ASW 20, ASW 20 B	Installation of main wheels and brake system P/N : JA-01.Revision 1: Update with new wheel P/N : RF-002(B) with brake EA-006Ewhich supersedes the P/ N: JA-01.Revision 2: Update with new wheel P/N : RF-019 which supersedes thewheel P/N: RF-002(B).Revision 3: Update with new servicing instructions with...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification file CR-MOD001-STC-005 REV 0, dated 30 Nov 2023Installation and Instructions for Continued Airworthiness: ICA-STC-005REV 03 dated 12 Jan.2024.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/02/2024	Active	10041414
10041441	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		650	Dual Installation of Flight management System Universal UNS-1Lw	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avionik Straubing Master Document List: ref ASR-2012-028-MDL-01-01, rev01, date 20 September 2012Avionik Straubing AFM Supplement: ref ASR-2012-028-FMS-05-01, rev 01,date 20 September 2012Avionik Straubing Instructions for Continued Airworthiness, refASR-2012-028-ICA-11-00, rev 00, date 25 June 2012...	none	20/09/2012	Active	10041441
10041447	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST02964NY-D	MF50	Installation of Crane Eldec "SmartStem" Tire Pressure Sensor (TPS) System.Validation of FAA STC N° ST02964NY-D.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dassault Falcon Jet-Wilmington Mater Drawing List, F5XW-D0011-005Revision I/R dated January 06, 2012;Instructions for Continued Airworthiness doc. N° F5XW-D0011-155Revision B dated December 13, 2011;FAA STC N° ST02964NY-D issue dated February 21, 2012or later revisions of the above listed documentsa...	None.	18/09/2012	Active	10041447

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041470	AIRCRAFT STRUCTURES INTERNATIONAL CORP.		FAA STC NO. SA011054SC	208, 208B	Installation of an internal Cargo Pod lighting system.	Design:Non-significant changeThe Certification Basis of theoriginal product and the followingadditional / alternative airworthiness requirements are applicable tothis change: As specified in the original FAA STC No. SA011054SC dated02-Jul-2012.Environmental Protection:The certificated noise and/ or...	FAA approved installation data list document DL1819M02, rev. IR, dated28 June 2012;FAA approved Compliance data list document DL1819M00, rev. IR, dated 28June 2012;FAA approved Instruction for continued airworthiness 02010000-ICA rev.A, dated 8 May 2012.or later revisions of the above listed documen...	If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.	19/09/2012	Active	10041470
10041473	KMLEX AVIATION INC.		TCCA STC Q-LSA10-047/D	FALCON 50EX	Relocation of Radio Altimeter ConverterValidation of TCCA STC N° Q-LSA10-047/D issue dated November 04, 2010.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List MDL30158002 - Relocation of Radio AltimeterConverter on Falcon 50 aircraft S/N 278<(>,<)> revisionNC datedNovember 04, 2010.TCCA STC N° Q-LSA10-047/D issue dated November 04, 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decisi...	Restricted to S/N 278	19/09/2012	Active	10041473
10041474	ACS-NAI Ltd.	REV. 1	TCCA STC SA12-17	PC-6/B2-H4 PC-6/B2-H2	Installation of Vapour Cycle Air Conditioner System.	US CAR 3 dated May 15, 1956 Arndt: 3-1 to 3-5and Special Conditions notified by the FAA to the Swiss FOCAThe Certification Basis for the original product remains applicable tothiscertificate/ approval.Derogation to latest amendment (Part 21 A.101):The certificated noise and/ or emissions levels ofa...	Airplane Flight Manual Supplement H404091 Revision N/C;Maintenance Manual Supplement H404071 Revision N/C and H404072 RevisionN/ C;Wiring Diagram Manual Supplement H404073 RevisionN/C;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2012/002/C (ort...	Refer to the Airworthiness Limitations contained in Airplane FlightManual Supplement H404091 Revision N/C.	04/10/2012	Active	10041474
10041475	KMLEX AVIATION INC.		TCCA STC Q-LSA10-048/D	FALCON 50EX	Replacement of Aft lavatory faucet adapter - Dassault Falcon 50EXaircraft MSN 278Validation of TCCA STC N° Q-LSA10-048/D issue dated November 04, 2010.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List MDL30159002 - Replacement of Aft lavatory faucetadapter on Falcon 50 aircraft S/N 278<(>,<)> revision NC dated November04, 2010.TCCA STC N° Q-LSA10-048/D issue dated November 04, 2010.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Dec...	Restricted to S/N 278	19/09/2012	Active	10041475
10041476	HAWKER BEECHCRAFT Ltd.	REV. 1	CAA UK RESPONSIBILITY	B200GT B200	Introduce Rockwell Collins TCAS 4000, Traffic Collision Avoidance System (TCAS) II System.	FAR-23, per TCDSThe Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Change No. SC0427A, Issue 1, July 2012;ICA ASC-R-018-AW4178, Issue 1, August 2012;or later revisions of the above listed documents approved by EASA.	STC does not provide compliance with Commission Regulation (EC)1332/2011 as regards to ACAS II equipment.	05/10/2012	Active	10041476

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041482	LUFTHANSA TECHNIK AG			A318-112	A318-100 - ELITE - Project Comlux3. Green aircraft completion to a VIPcabin configuration.		- Supplement Type Definition Document, ref. Doc. No STDD00-08/16M, issue01, dated 03. Jul. 2009, or later approved revisions- Airplane Flight Manual Supplement, ref. Doc. No. A-00-08/877-AFM issue01, dated 23. Jun. 2009, or later approved revisions- Instructions for Continued Airworthiness, ref. Doc...		07/07/2009	Active	10041482
10041486	DUNLOP AIRCRAFT TYRES LIMITED		CAA UK RESPONSIBILITY	ERJ 170-200 STD. ERJ 170-200 LR, ERJ 170-100 STD, ERJ 170-100 LR,	Dunlop Aircraft Tyres Limited P/N DZ32816T Radial Nose Landing Gearinstallation on ERJ 170.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List 170 PR5 MDL Rev IR dated 11 September 2012or later revisions of the above listed documents approved by EASA.	It is not allowable to mix different tyre types (radial andbias) in thenose landing gear leg.	20/09/2012	Active	10041486
10041500	BOMBARDIER INC.	REV. 1	TCCA STC SA-12-16 ISSUE 2	BD-700-1A10	Installation, Aircraft Completion Modifications - ASN 9464	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA-12-16 Issue 2, dated 20 March 2012.Bombardier Configuration Definition Record RAZ-BM700-001Revision AD,dated 14 September 2012.Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC.Instructions for Continued Airworthiness Document GC94640000-ICAor later...	Restricted to ASN 9464	24/09/2012	Active	10041500
10041512	BOMBARDIER INC.		TCCA STC SA-12-16 ISSUE 2	BD-700-1A11	Installation, Aircraft Completion Modifications - ASN 9462	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA-12-16 Issue 2, dated 20 March 2012.Bombardier Configuration definition Record RAZ-BM700-001Revision ABdated 06 September 2012.Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC.Instructions for Continued Airworthiness Document GC94620000-ICA.Or later...	Restricted to ASN 9462.	24/09/2012	Active	10041512
10041522	INFLIGHT WARNING SYSTEMS, Inc.			A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-111/-211/-212/-214 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of Inflight Warning System Fan Vibration Monitor Unit (VMU)model n. 216001-400	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA Supplemental Type Certificate ST02356LA issued 5th December 2011-PSCP-216001 Rev. G, dated 17th May 2011-Master Data List 13601 Rev. A, dated 31st May 2011-Instructions for Continued Airworthiness 13608 Rev. A, dated 25th April2011or later revisions of the above listed documents approved by EAS...	None	25/09/2012	Active	10041522

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041532	ORCON CORPORATION		FAA STC ST01834LA	B757-200/-200PF	Validation of FAA STC ST01834LA related to Installation of InsulationBlanket	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Orcon Corporation's Index List, Document No. F83005, Revision H, dated23 April, 2012Orcon Corporation's Master Drawing List, Document No. MDL-9000, RevisionH, dated April 23, 2012Orcon Corporation's Continued Airworthiness Instructions, Document No.CAI-9000 Revision C, dated August 12, 2010or latera...	None	25/09/2012	Active	10041532
10041533	ATLANTIC AERO, Inc.		FAA STC SA03931AT-D	TBM 700 A/B/C1/C2/N	Installation of modified battery heat shield	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Atlantic Aero Instructions for Continued Airworthiness no 26493010revision IR dated 15 September 2011Atlantic Aero Master Drawing List no 26493001 revision IR dated 26September 2011or later revisions of the above listed documents approved by EASA	None	25/09/2012	Active	10041533
10041546	GLOBAL AIRWORKS, Inc.		FAA STC ST3042CH	ATR 72-212A. ATR 72-211, ATR 72-212, ATR 72-201, ATR 72-202, ATR 72-101, ATR 72-102, ATR 42-320, ATR 42-500 ATR 42-200, ATR 42-300,	Installation of a Global AirWorks Cockpit Door SurveillanceSystemThis STC installs a cockpit door surveillance system (CDSS) allowingcrew to view video images of the area outsidethe cockpit door.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Standard Aero Master Data List, ref : MDL230071, Rev F., dated 01February 2012Standard Aero Aircraft Fligth Manual Supplement, ref : AFMS230071, RevA, dated 14 February 2012Instruction for Continued Airworthiness, ref : ICA 230071, Rev BStandard Aero Weight & Balance Report. ref : WBR230071, Rev Aor...	None	26/09/2012	Active	10041546
10041560	FIELD AVIATION COMPANY Inc.		TCCA STC C-LSA12-128/D	DHC-8-202	Auxiliary Ground Heater SystemTCCA STC C-LSA12-128/D, Issue1	FAR 25 as per EASA.IM.A.191, Issue 5 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation must be in accordance with Field Aviation Master Data List25390000, Revision IRMaintenance must be in accordance with Field Aviation AircraftMaintenance Manual Supplement 25393100, Revision IRor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Dec...	Installation is limited to Serial Numbers 435, 440, 441, 445 and 446	26/09/2012	Active	10041560
10041576	JET AVIATION AG, BASEL	REV. 1		FALCON 10	Exchange to Universal Avionics FMS UNS-1LwOut: Universal Avionics FMS UNS-1Msp systemIn: Universal Avionics FMS UNS-1Lw system	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Data List Doc. No. BSDYB004-004 Rev. C of 21.02.2013Instructions for Continued Airworthiness Doc. No. BSDYB004-150-04 Rev. Aof 24.01.2013Airplane Flight Manual Supplement Doc. No. BSDYB004-201-04 Rev. A of01.02.2013Declaration of Compliance Project BSDYB004/BSDVP003 of 21.02.2013Service Bulle...	S/N: 216, 224The approval holder shall fulfil the obligations of Part 21, Point21.A.109 or 21.A.451(b).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducea...	25/02/2013	Active	10041576

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041590	FIELD AVIATION COMPANY Inc.	REV. 1	TCCA STC SA-12-57	DHC-8-106. DHC-8-102, DHC-8-103,	Installation of Protective Breathing Equipment (PBE)TCCA STC SA 12-57, Issue 1	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with Field Aviation Master Data List25680000, Revision IR, dated 05 September 2012;Maintenance must be in accordance with Field Aviation AircraftMaintenance Manual Supplement 25683100, Revision IR, dated 27 August2012;or later revisions of the above listed document...	None	15/10/2012	Active	10041590
10041595	JET AVIATION AG, BASEL	REV. 1		B737-900ER	EMS SATCOM AMT-3800 Installation.	FAR 25 Amdt: 25-108The Certification Basis for the originalproduct remains applicable tothis certificate/ approval.Do not materially contribute to safety.The certificated noise and/ or emissions levels of the original productare unchangedand remain applicable to this certificate/ approval	Instructions for Continued Airworthiness BB73723265-06, IRor later revisions of the above listed documents approved by EASA.	1) This STC has been assessed for compatibility for installation onaircrafts, which are equipped for lower cabin altitude LOC under FAA STCST01697SE. However, EASA has not yet approved the lower cabin altitudeSTC. Therefore, if such an aircraft is to be entered on an EU register,operations must be c...	18/01/2013	Active	10041595
10041598	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 767-200/-300	Introduction of Iridium Antenna.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Ltd Master Document List No. S21.MDL-1080 Issue 3;or later revisions of the above listed documents approved by EASA.	None.	01/10/2012	Active	10041598
10041603	ASI INNOVATION			EMB-120ER	"P-RNAV Certification"Description as per documents in "Associated Technical Documentation".	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC data list reference ASI-SDL-0089-08, dated 26/09/2012;Technical Dossier ASI-TD-0089, issue 4, dated 26/09/2012;AFM Supplement ASI-AFM-0089, issue 6, dated 18/09/2012;or later revisions of the above listed documents approved by EASA.	Applicability restricted to the following S/Ns: 012, 013, 027, 158.	01/10/2012	Active	10041603
10041604	JET AVIATION AG, BASEL	REV. 1		B737-900ER	VIP Cabin interior installation.Installation of table leaf adjacent to RH over-wing exit.See Master Data List BBJ37560-001 Rev. C (or later approved revision).	FAR 25,, Amdt: 25-108The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI A-01 EASA STC Certification BasisSCs or ESFs:CRI C-01 Interface between seats and floor (means of compliance)CR...	Airplane Flight Manual Supplement BBJ37560-201-01 Rev. D;Instructions for Continued Airworthiness BBJ37560-150-01 Rev. IR;EWIS Instructions for Continued Airworthiness BBJ37560-150-02 or laterrevisions of the above listed documents approved by EASA.	S/N: 37560	05/11/2012	Active	10041604
10041623	DASSAULT FALCON SERVICE			F2000, F2000EX	WiFi activation on Falcon 2000, F2000EX aircraft.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.§ 25.1301 (a) (d) - 1309 (a) (g) - 1322 - 1353 (a) - 1431 (a) (c) at JAR25 Change 14.The requirements for environmental protection and th...	DFS Change Approval Sheet DFS151-CAS Issue A dated 07.08.2012DFS Modification Sheet DFS151, Issue A dated 07.08.2012DFSMaster Data List DFS-DE-17-FD-D151, Issue A dated 07.08.2012or later revisions of the above listed documents approved by EASA	F2000 and F2000EX aircraft equipped with WiFi equipments installationcompliant with prerequisite note DT-001-12.	02/10/2012	Active	10041623

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041628	NORTHWEST AEROSPACE TECHNOLOGIESINC.			777-300ER	N0419 Cabin Interior Modifications on Jet Airways Boeing 777-300ERAircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.	N0419-D90, Rev A, dtd Oct 2, 2012- Certification Summary for the CabinInteriorModifications on Jet Airways Boeing B777-300(ER) AircraftDrawing List N0419-D10 Rev. A dtd. Sep 29, 2012Instructions for Continued Airworthiness N0419-D70 Rev. Adtd. Aug 31,2012or later revisions of the above listed docum...	None	03/10/2012	Active	10041628
10041637	EUROCOPTER CANADA Ltd.		TCCA STC SH12-10	EC130B4	Door handle installation (P/N 120-200014)This STC is the validation of TCCA STC SH12-10 (issue date - February 10,2012)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Definition and installation:ECL Master Drawing List - doc. ref. MDL-10-015 Issue BInstallation Procedure - RH Door Handle Installation - EC130B4 – doc.ref. IP-ECL-127 Rev. 2Inspection and Maintenance:Instructions for Continued Airworthiness - RH Door Handle Installation -EC130B4 - doc. ref. ICA-ECL-...	None	03/10/2012	Active	10041637
10041648 (EASA.IM.A.S.00286)	STAR AVIATION, Inc.	REV. 1	FAA STC ST02942AT	747-400	Installation of Cabin Wireless Local Area Network (CWLAN) in accordancewith Star Aviation Inc. Master Data List R44-0175, Revision G, datedOctober 13, 2004, or later FAA approved revisions and Provisionalinstallation of a Panasonic Avionics Corporation eXPhone system inaccordance with Star AviationD...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval14 CFR Part 25 Amendment 25-0 through 123 for the following requirements25.23,,,,25.29,,,,25.301,,25.303,,25.307,,25.561,,25.601 25.603,,2...	Master Data List R44-0175, Revision G, dated October 13, 2004<(>,<)>Master Data List R44-0613, Revision D, dated July 19, 2012<(>,<)>AFM Supplement R44-0293, Revision A, datedOctober 18, 2004Instructions for Continued Airworthiness Document R44-0182 Rev. IRdated June 16, 2004, Document R44-...	None	23/10/2012	Active	10041648
10041649	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01822AT-D	GV AND GV-SP	Installation of APU Fire Bottle	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installed in accordance with Gulfstream Aerospace Corporation Index ListGC514428001, Revision L, dated July 31, 2011.Operation in accordance with AFM GC51442M001, dated April 8, 1999 orlater FAA approved revision required for fully operationalconfigurations (non-spare).For model GV, ICA GC51442A001,...	1- The installer must determine whether this design change is compatiblewith previously approved modifications2- If theholder agrees to permit another person to alter the product,the holder must give the other person written evidence of thatpermission.	04/10/2012	Active	10041649
10041655	AEROCONSEIL			777-200LR & 777-300ER	0465-01: eXPhone System Activation on B777-200LR/300ER	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 25 Amdt 4CRI-F01: PANASONIC EXPHONE SYSTEM INSTALLATIONCRI-F02: HARDWARECRI-F03: SOFTWARECRI-F04: DATABASES ANDThe certificated noisea...	MDL 0465-01-A-2103-R01 dtd. 3.Oct 12AFMS 0465-01-A-2301-R00dtd. 23.Jul 12ICA 0465-01-B-2211-R00 dtd. 26.Jul 12or laterrevisions of the above listed documents approved by EASA	per AFMS 0465-01-A-2301	04/10/2012	Active	10041655

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041674	JET AVIATION ST. LOUIS, Inc.		FAA STC ST02868CH-D	CL-600-2B16 (CL-604 VARIANT)	Installation of Drain Mast	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	FAA STC No. ST02868CH-D.Jet Aviation St. Louis, Inc. MasterData List 41-260G001, Rev C dated 09February 2012.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	05/10/2012	Active	10041674
10041706	SKYTRAC SYSTEMS LTD.		TCCA STC SH10-51	AW139	Installation of a SkyTrac ISAT-100/ ISAT-200 Position Data Communicator (Canadian STC SH10-51 issue 2)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List, document HP 139-23-00-104 Revision A, dated May 11,2012 and Transport Canada approved May 28, 2012Rotorcraft Flight Manual Supplement, document FMS HP 139-23-301 RevisionA, dated October 7, 2011 and Transport Canada approved May 28, 2012Services Instructions for Continued Airwor...	None	09/10/2012	Active	10041706
10041707	BERINGER AERO	REV. 4		VENTUS A, VENTUS 2A DISCUS A, DISCUS 2A 2. VENTUS A, VENTUS 2A 1. DISCUS A, DISCUS 2A	Installation of main wheels and brake system P/N: JA-02.Revision 1: Update with new wheel P/N: RF-007(B) with brake EA-006Ewhich supersedes the P/ N: JA-02.Revision 2: Update with new wheel P/N: RF-020 which supersedes the wheelP/N: RF-007.Revision 3: Update with new servicing instructions within ICA...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification File: CR-MOD001-STC-007 REV 0, dated 30 Nov. 2023AFM Supplement: FM-STC-007 REV 0, dated 12 Sept. 2012Installation and Instructions for Continued Airworthiness: ICA-STC-007REV 05, dated 11 Aug. 2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/03/2024	Active	10041707
10041711	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC NO. ST01514WI-D	CL600-2B19 REGIONAL JET A21EA	Installation of Rockwell Collins FMS-4200 to provide WAAS/LPAcapability.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST01514WI-D dated 10 April 2009;Master Drawing List RCA-0179-001, Revision -, dated 8 October 2008;AirplaneFlight Manual Supplement ACC-08-025, Revision -, dated 17December 2008;or later revisions of the above listed documentsapproved by EASA inaccordance with EASA ED Decision 2004/04/...	Installation and approval of WAAS compatible GPS antennas is requiredprior to or concurrent with this modification.ThisSTC approves the installation of DBU-5000 Part Number 822-2215-602(Flip Door/Gray/No AFIS/ Ethernet).Installation and approval of a Rockwell Collins DBU-5000 is requiredprior to or8...	12/10/2012	Active	10041711
10041712	ROCKWELL COLLINS, Inc.		FAA STC NO. ST01505WI-D	CL-600-2B16 (CL-604 VARIANT)	Installation of Rockwell Collins FMS-6000 to provide SBAS LPVcapability.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST01505WI-D dated 05 November 2010;Master Drawing List RCA-0150-001, Revision H, dated 1 October 2010;Airplane Flight Manual Supplement ACC-09-107, Revision B, dated 19 May2010 or RCA-0289, Revision -, dated 01 October 2010;Instructions for Continued Airworthiness RCA-0141, Revision A, d...	Restricted to Serial Numbers 5301-5699, 5701 and subsequent.Installation and approval of WAAS compatible GPS receivers/antennas arerequired prior to or concurrent with this modification.DBU-4000 and DBU-4100 Data Base Units are incompatible with the FMC-6000(Flight Management Computer) installed byt...	09/10/2012	Active	10041712

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041722	DASSAULT AIRCRAFT SERVICES (DAS)	REV. 3	FAA STC ST02962NY	FALCON 2000, FALCON 2000EX	Validation of FAA STC ST02962NY.Installation of ADS-B Out System on aircraft equipped with RockwellCollins Pro Line 4 or Pro Line 21 series avionics system.Revision 1: Installation of ADS-B Out System compliant with DO-260B.Revision 2: Correction of FAA STC number.Revision 3: Introduction of EASA ST...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-AFMS ref. F2XW-D0006-150 initial revision, dated 10 October 2011 (DO-260A).-AFMS ref. F2XW-D0020-150, revision A, dated21 December 2015 (DO-260B).-Instruction for Continued Airworthiness F2XW-D0006-155 Rev. G, dated14.Dec.2015-STC Master Data List ref. F2XW-D0006-005 revision F, dated 10 May 2016or...	The installation of the EASA STC ref. EASA.IM.A.S.02889 (validation ofFAA STC ST01433WI-D) or EASA STC 10064001 (validation of FAA STCST01833WI) for the installation of Rockwell Collins GPS Landing SystemSensor Unit (GLSSU) is a pre-requisite for this design change.	11/02/2019	Active	10041722
10041723	DASSAULT AIRCRAFT SERVICES (DAS)	REV. 3	FAA ST02963NY	MYSTERE FALCON 50	Validation of FAA STC ST02963NY.Installation of ADS-B Out System in Dassault Aviation Mystere-Falcon 50aircraft equipped with Rockwell Collins Pro Line 4 or Pro Line 21Avionics System.Revision 1: Installation of ADS-B Out System compliant with DO-260B.Revision 2: Correction of FAA STC number.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFM Supplement ref. F5XW-D0008-150 Rev. A, dated 29 April2013;- AFM Supplement ref. F5XW-D0017-150-1, Rev. A, dated 14 October 2015 (DO-260B);- STC Master Data List ref. F5XW-D0008-005 Rev. L, dated 14 October2015;- Instructions for Continued Airworthiness (ICA) F5XW-D0008-155 Rev. G,dated 30 Sept...	The installation of the EASA STC ref. EASA.IM.A.S.02889 or EASA STC No.10064001 (validation of FAA STC ST01433WI-D or ST01833WI) for theinstallation of Rockwell Collins GPS Landing System Sensor Unit (GLSSU)is a pre-requisite for this design change.Prior to installation of this design change it must...	07/01/2019	Active	10041723
10041736	EUROCOPTER CANADA Ltd.		TCCA STC SH11-35	EC130B4	Glare Shield Modification P/N 130-885114This STC is the validation of TCCA STC SH11-35 (issue No. 1 dtdSeptember 20, 2011)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Operation:Eurocopter Canada Limited Flight Manual Supplement - Adjustable GlareShield Mod EC130 - doc. ref. FMS-ECL-148Rev. 0Definition and installation:Eurocopter Canada LimitedMaster Drawing List - Adjustable Glare ShieldMod EC130B4 - doc. ref. MDL-11-016 Issue BEurocopter Canada Limited Install...	None	11/10/2012	Active	10041736
10041743	MID-CANADA MOD CENTER		TCCA STC O-LSA09-348/D	CL-600-2B19	TrueNorth Satphone Installation	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No. O-LSA09-348/D Issue 2 dated 13 June 2012.Avionics Design Services Ltd. Master Drawing List MDL09014, Revision C,dated 13 June 2012.Mid Canada Mod Center Flight Manual Supplement FMS09014-1, Revision N/C,dated 12 June 2012.or later revisions of the above listed documents appr...	Restricted to ASN 8092.EASA STC Nos.10038463 and 10028338 Rev. 2 (Transport Canada STC Nos.O-LSA09-344/D and C-LSA09-326/D) are pre-requisites to this approval.	12/10/2012	Active	10041743
10041776	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02714NY	737-800, 737-900, 737-900ER 737-600, 737-700, 737-8,	Installation of provisions for navAero Electronic Flight Bags.Rev. 1: Model 737-8 and additional configurations are included.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List 0106-06191-2169 Revision AD dated 31 July 2017.- Instructions for Continued Airworthiness/ Wiring Interconnect SystemSource Document Ref. 0706-09844-2169 Rev. F, dated 16 August 2017.- Airplane Flight Manual, Ref. 0606-09837-2169 Rev. A, dated 29 June2017or later revisions of th...	Installation of NavAero Mount “Configuration 1” (as per Master Data List0106-06191-2169 Revision AD) is not covered by the EASA validation.This STC does not approve the use of applications or approve theinstallation of the navAero display or docking station.Prior to installation of this design chang...	07/12/2017	Active	10041776

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041778	ASI INNOVATION			EMB-135LR	Cabin interior modification.Description as per Associated Technical Documentation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASI SDL, STC Data List ref. ASI-SDL-0059-01, dated 12/10/2012;ASI MDL, Master Drawing List ref. ASI-MDL-0059-02, dated 01/10/2012;ASI Technical Dossier ref. ASI-TD-0059-01, dated 09/10/2012;ASI AFMS ref. ASI-AFM-0059 issue 0, dated 27/06/2012;or later revisions of the above listed documents approved...	Applicability limited to EMB-135LR S/N 886.	15/10/2012	Active	10041778
10041796	NOUVELLE MANUFACTURE D'AEROSTATS	REV. 1		T-SERIES N-SERIES M-SERIES	Transfer of STC 10041796_Nouvelle Manufacture d'AérostatsDescription of Design Change:Modification « Diners à bord », 2-guests kit and 16-guests kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	Supplement Flight Manual NMA 01-2012or later revisions of the above listed documents approved by EASA.Master Drawing List MDL-01-2012	2-guests kit applicable on Ultramagic C5, C5L, C7, C8, C8L,C9 and C11baskets, all s/n, and Cameron CB 8202 « Thunder &Colt 40+B" basketslimited to s/n 943 and s/n 183416-guests kit applicable on Ultramagic C12 basket, all s/n	03/04/2017	Active	10041796
10041797	AMAC AEROSPACE SWITZERLAND AG			B777-200LR	Interior Outfitting project BA01-2500 (S/N 40753)The changeconsists in a complete cabin interior outfitting of B777-200LR S/N 40753 aircraft with a 125 passengers, plus 16 crew seatingarrangement in a new "VVIP" Cabin Interior suitable for"Private/Smoking" operation.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approvalAs per CRI A-01 "EASA Supplemental Type Certification Basis for AMACAerospaceAG B777-200 LR project "BA01-2500 Interior Outfitting" close...	Master Data List doc. N° MDL-BA01-2500 Rev. C dated 16.10.2012;or later revisions of the above listed documents approved by EASA.	S/N 40753	16/10/2012	Active	10041797
10041806	JAMCO AMERICA, INC.		FAA STC ST01884SE-D	747-400	Installation of a galley modification on Boeing 747-400 series aircraftin accordance with Jamco America, Inc. Master Drawing List (MDL) 1419-1,Rev.E, dated May 25, 2012, or later FAA approved revision.Validation of FAA STC ST01884SE-D	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:§ 25.853(a)(b)(c) Amdt 25-72 ; § 25.853(g) Amdt 25-116 ; § 25.853(h)Amdt 25-83;§ 25.854(a) Amdt 25-74 ; § 25.856 (a) Amdt 25-111 ; § 25.8...	Jamco America, Inc. Master Drawing List 1419-1, Rev.E, dated May 25,2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	S/N 29262	17/10/2012	Active	10041806
10041824	ROSEMOUNT AEROSPACE, Inc.		FAA STC ST02944CH	777-300ER, 777F 777-200, 777-200LR, 777-300	Installation of an AC-DC Converter.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.Special Condition CRI H-01 EWIS	Rosemount Aerospace Master Data List, Doc. No. D06408653, Revision B,dated 21.December 2011;Airplane Flight Manual Supplement, Rosemount Aerospace Doc. No.D06408872, Revision A dated 23.December 2011;Instruction for Continued Airworthiness (ICA) / EWIS source documentD06408730 rev. D. dated 20. Dece...	Aircraft modification iaw Rosemount Aerospace Master Data List, Doc. No.D06408653 Configuration A requires concurrent installation of a systemor of equipment utilizing the DC power provided by the AC-DC powerconverter;Aircraft modificationiaw Rosemount Aerospace Master Data List, Doc. No.D06408653a...	18/10/2012	Active	10041824
10041846	MICRO AERODYNAMICS, INC.		FAA STC SA02226SE	DA 42, DA 42NG, DA 42M-NG	Installation of vortex generators on the wings and tail surfaces.FAA STC SA02226SE	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement MA 2243, dated October 01, 2012or later revisions of the above listed documents approved by EASADrawing Package MA2240, Revision IR, September 30,2011Installation Manual MA2241, Revision IR, November 21,2011or later revisions of the above listed documents approved by EASA inaccordance...	None	19/10/2012	Active	10041846

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041858	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	A139	Introduction of SX16 Searchlight System	CS-29 Initial IssueThe Certification Basis for the originalproduct and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The following paragraphs of CS29 Initial issue29.1, 29.25<(>,<)> 29.27< (>,<)> 29.45, 29.49, 29.51, 29.53, 29.55,29.59,...	Flight Manual Supplement; PADS/FMS/139/002 Rev A.or later revisions of the above listed documents approved by EASAMaster Drawing List; PADS/MDL/ 1197 Rev. BICA; PADS/ ICA/1197 Rev A& PADS/ MMS/1197/001 Rev A.	none	11/12/2012	Active	10041858
10041863	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	AW 139	Introduction of an electronic message sign.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The following paragraphs of CS29 Initial issue29.1, 29.25, 29.45, 29.49, 29.51, 29.53, 29.55, 29.59, 29.60, 29.61,29.62, 29.65, 29.67, 29...	Flight manual supplement; PADS/FMS/139/001 Rev. A;or later revisions of the above listed documents approved by EASA.Master drwg. List; PADS/MDL/ 1193 Rev. CICA; PADS/ ICA/1193 Rev. A & PADS/ MMS/1193/001 Rev. B	None.	11/12/2012	Active	10041863
10041899	EUROCOPTER DEUTSCHLAND GmbH			EC 120 B	Installation of GTN 650 Unit on EC 120B	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- SK-MIC-136-SUP-P-623 Flight Manual Supplement, Revision B, dated08-2012.or later revisions of the above listed documents approved by EASA- P347-001.00000-00 GTN Installation (Top Drawing)- SK-MIC-136-EO-P-616 Engineering Order- SK-MIC-136-CM-P-620 Customization Manual	none	23/10/2012	Active	10041899
10041900	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST00673LA-D	GV	Installation of Honeywell TCAS 2000 TCAS II System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC ST00673LA-D<(>,<)> issued 17th May 1999-Installed in accordance with Gulfstream Aerospace Corporation IndexList ref. GC51 1298001, Revision C, dated 26th April 1999-Airplane Flight Manual Supplement, ref. GC51 129M001, Rev. A, dated26th February 2000or later revisions of the above listed do...	None	23/10/2012	Active	10041900
10041955	BERINGER AERO	REV. 3		R3000/160 S, R3000/180 R3000/140, R3000/160 R3000/120, R3000/120D R3000/100 R2160, R2160D, R2160I R2100, R2100A, R2112, R2120U R1180T DR400-NGL/-RP DR400-200R/-2+2/-500 DR400-180/-180R/-180S DR400-160/ 160D DR400-125/-125I/-140/-140B DR400-100/-120/-120A/-120D DR 300/180R	Replacement of brake unitRevision 1: Addition of R 1000 series, R2000 series and R3000 seriesaircraft modelsRevision 2:Addition of DR 300/180RRevision 3: Update with new servicing instructions within ICA document	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Refer toCS paragraphs listed on document DM-STC-006(8).The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Modification file: DM-STC-006 rev 09 dated 11 Mar. 2022;Installation and Instructions for Continued Airworthiness: ICA-STC-006rev 01 dated 22 Oct. 2021;or later revisions of the above listed documents approved by EASA.	The approval holder shall fulfill the obligations of Part 21, Point21.A.109 or 21.A.451(b) (as applicable).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introd...	18/03/2022	Active	10041955

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041959	APICAL INDUSTRIES, Inc.		FAA STC NO. SR02425LA	A119, A119 MK II	EASA Validation of FAA STC No. SR02425LA "Installation of ApicalIndustries, Inc. Cable Cutter Kit".	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Apical Industries, Inc. Master Document List MD119-2 Rev. B, dated 17April 2012;Apical Industries, Inc. Instructions for Continued Airworthiness, ICA119-2, Rev. A, dated 19 April 2012;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (ort...	None.	26/10/2012	Active	10041959
10041960	WIPAIRE Inc.	REV. 3	FAA STC SA1311GL	SEE FAA AML	Installation of Wipaire Model 8000 Amphibian/Seaplane floats or WipaireModel 8750 Amphibian/Seaplane floats	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Wipaire Inc. Installation Drawing as listed on the AML No. SA1311GL,issued 8 May 2013 or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/03/2019	Active	10041960
10041970	DRF STIFTUNG LUFTRETTUNGG EMEINNUETZIGE GmbH			MB BK 117 C-2	Installation of a TETRA Digital Radio System into a NVIS certifiedCockpit.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI on NVIS dated 11.09.2012The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels o...	-,,FMA 11-5-1 APPENDIX FOR TETRA Communication System rev. A dated27.08.2012;or later revisions of the above listed documents approved by EASA.-,,Instructions for Continued Airworthiness Doc. N°: CA-117-23-10-00025Revision: 00;or later approved revisions of the above listed documents.	Required premodification: EASA approval EASA 10034057 (ECDmajor changeE-1807).This rotorcraft employs Night Vision Imaging System lighting, commonlynamed NVIS lighting, that hasbeen certified to ensure the aircraft iscompatible with night vision goggles (NVG). For this reasonmodifications that ad...	29/10/2012	Active	10041970
10041971	S-TEC CORPORATION	REV. 2	FAA STC SR02345LA	EC 130 B4, EC 130 T2 AS 350 B, AS 350 B1 AS 350 BA, AS 350 D AS 350 B2, AS 350 B3	Installation of S-TEC HeliSAS Stability augmentation systemandautopilot.Revision 1 extends the applicability to AirbusHelicopters EC130T2 typemodel.Revision 2 implements corrections on Limitations/ Conditions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):EASA 0010014645 CRI Int/Pol 27/29 issue 3 - HIRFEASA 0010014645 CRI CS27.1309 (FAA Special Condition 27-026-SC)For the installation in AS350B1, AS350B...	Rotorcraft Flight Manual Supplement, doc. ref. HeliSAS-RFMS-AS350/ EC130Rev. C, dated 30 April, 2015.For Airbus Helicopters type models AS350B, AS350BA, AS350D, AS350B1,AS350B2, AS350B3:-Master Data List, doc. ref. HeliSAS-MDL-AS350 Rev. D,dated 04 October2012-Instructions for Continued Airworthines...	IMC flight is not authorizedExternal load operations are not authorizedIf the HeliSAS installation interfaces with the Garmin 500H system, thelatter must be equipped with GDU SW v7.00 or later to output label 114as True Track not Magnetic.Prior to installation of this design change it must be determ...	10/08/2015	Active	10041971
10041972	KUERZI AVIONICS AG			R 90-230RG	Avionic upgradeRemoved:- Original flight instrument including KCS55 pictorial navigationsystem, attitude indication (with flight director), electrical attitudeindication, encodingAltimeter 2x, mechanical AS, VS and turn and bank.- Original vacuum system- Existing navigation system- Existing ATC tra...	FAR 23,, Amdt: 35The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.SCs or ESFs: For this change compliance to FAR 23 Amdt 35 and FAR 23.561Amdt 36, 23.1306 Amdt 61, 23.1308 Amdt 57, 23.13...	Master Document List: MDL-201110675, Rev. B, dated 26.10.2012;Instructions for continued airworthiness: ICA-201110675, Rev N/C, dated27.06.2012;Airplane Flight Manual Supplements for - Garmin 500 PFD/MFD: FMS-201110675.1 Rev. 0, dated 18.09.2012 - Garmin GTN750/650 FMS-201110675.2 Rev. 0, dated 18.0...	None.	29/10/2012	Active	10041972

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10041975	BOMBARDIER INC.		TCCA STC NO. SA12-16	BD-700-1A11	Installation, Aircraft Completion Modifications - ASN 9458.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-16 Issue 2, dated 20 March 2012.Bombardier Configuration Definition Record RAZ-BM700-001 Revision U,dated 24 July 2012;Bombardier Airplane Flight Manual Supplement G-FM25054001 RevisionBASIC;Instructions for Continued Airworthiness Document GC94580000-ICA;or later revis...	Restricted to ASN 9458.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplane's cabin using portableelectronic devices (PEDs).Any other intended function of this equipment willrequire are-examination of the certification basis.	29/10/2012	Active	10041975
10041983	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		767-300	Installation y 276 PAX LOPARev. 1: Transfer from GVH Aerospace Ltd (Formerly Bournemouth AviationConsultants Ltd) to GVH Aerospace (Ireland) Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	BAC Ltd Master Data List No. BAC-784MDL02 Issue 4 dated 24 October 2012< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The following minor modifications are prerequisites for thismodification:(1) Mod BAC-784MOD12 Revision of Emergency safety Equipment Layout.(2) Mod BAC-784MOD06 Revision of Emergency Floor Path Lighting. (3) Mod BAC-784MOD18 Revision of thePSU (overhead passenger serviceunit) installation.Prior to i...	06/10/2021	Active	10041983
10041988	AIRBORNE MAINTENANCE ANDENGINEERING SERVICES, Inc. (AMES)		FAA STC ST01096CH	767-200/ -300	Upgrade of Teledyne Digital Flight Data Acquisition Unit	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	AMES Master Drawing List RPT-99-06040, Revision G, 22/04/2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	none	30/10/2012	Active	10041988
10041989	AIRBORNE MAINTENANCE ANDENGINEERING SERVICES, Inc. (AMES)	REV. 1	FAA STC ST02325CH	767-200/ -300	Installation of Electronic Standby Instrument System (ESIS)	The Certification Basis for the original product remains applicable tothis certificate.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this approval.	ABX Air Master Data List RPT-06-07507, Revision B, 16/08/2006AFM Supplement, ABX Air, Inc. Document No. RPT-06-07516, Revision IR<(>,<)> 06/09/2006or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)...	Only to be installed on a/c with EASA STC 10036223 installed.	05/11/2012	Active	10041989
10042007	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		767-300	In Flight Entertainment and In Seat Power Supply RevisionRev 1: Transfer from GVH Aerospace Ltd (Formerly Bournemouth AviationConsultants Ltd) to GVH Aerospace (Ireland) Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- BAC Ltd Master Data List No. BAC-829MDL02, Issue 4 dated 29 October2012.- BAC Ltd Flight Manual Supplement No. BAC-829FMS02 Rev 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The following STC is a prerequisite for this modification: ModBAC-784MOD02 (EASA Approval ref. 10041983 Rev. 1).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	07/10/2021	Active	10042007
10042009	AIRBORNE TECHNOLOGIES GmbH	REV. 2		EC 635 T2+ EC 635 P2+, EC 635 T1 EC 135 T2+ EC 135 T1, EC 135 T2 EC 135 P2+, EC 135 P1, EC 135 P2	Title: STC-AT-054-RevB<(>,<)> Provisions for surveillance operationsDescription:Installation of provisions for surveillance operation, consisting of thefollowing parts:Step 1: Provisions for surveillance operationStep 2: Cabin provisionsStep 2a: Alternative operator deskStep 3: Trim mass installatio...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27, Amendment 2CS 27.29, CS 27.301, CS 27.303, CS 27.305, CS 27.307, CS 27.309, CS27.321, CS 27.337, CS 27.341, CS 27.561, CS 27.601, CS 27.613, CS27.623, CS 27.625, CS...	Supplement to the AFM - Provisions for surveillance operation, Doc. No.AFM1-STC-AT-054, Rev. 5 dated 04.05.2015Supplement to the AFM - Cabin Provisions, Doc. No. AFM2-STC-AT-054, Rev.3 dated 09.03.2015Supplement to the AFM - Alternative operator desk, Doc. No.AFM2a-STC-AT-054, Rev. 1 dated 04.05.201...	Installation of Step 1 is prerequisite for Step 2 or Step 2aInstallation of Step 2 or Step 2a is prerequisite for Step 4Installation of Step 5 is prerequisite for Step 6Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any othe...	18/05/2015	Active	10042009

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042012	NSE INDUSTRIES S.A.	REV. 1		AS 350 B,AS 350 B1,AS 350 B2 AS 350 B3,AS 350 BA,AS 350 BB	Installation of Data Tracking System DTS-Alpha.Modificationas defined in STC Data List, doc. SDL-DTSALPHA-AS350 Rev.04Revision 1 is a re-print following a change of name and address.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.This modification complies with CS-27 Amdt. 2 requirements as specifiedin Certification Plan PCERT-DTSALPHA-AS350 Rev. 04, dated 29/10/20...	Definition and installation:Kit Part List, doc. NOM KIT-DTSA-03-00 Ind. 00Definition Document DTS Alpha P/N 412695 Amdt. B, doc. DD-412695 Rev.00STC Data List, doc. SDL-DTSALPHA-AS350 Rev. 04DTS Alpha Installation Manual on AS350, doc. IM-DTSALPHA-AS350 Rev. 02Inspection, Maintenance and Operation:...	Modification not approved for rotorcraft equipped with AFCS (AutomaticFlight Control System) or Weather Radar.Modification not approved for AS350B3 model helicopters withmodification OP-4305 (Arriel 2D engine installation) incorporated.Prior to installation of this modification it must be determined...	14/08/2013	Active	10042012
10042013	S-TEC CORPORATION		FAA STC NO. SA5301SW-D	58A 58	Installation of S-TEC system 40/50, model ST-224-40/50, according tobulletin n. 324 dated 22-Sep-1983 and Master Drawing List No. 92252,dated 22-Sep-1983 (28V - System).	Design:Non-significant changeThe Certification Basis of theoriginal product remains applicable tothis change.Environmental Protection:The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	FAA approved S-TEC Master Drawing List No. 92252, dated 22-Sep-1983 (28V- System);FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement No. 89350 dated 5-Apr-1984 for system 40;FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement No. 8...	FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement No. 89350 dated 5-Apr-1984 is required for system 40.FAA / DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement No. 89351 dated 5-Apr-1984 is required for system 50.Installer must check a...	31/10/2012	Active	10042013
10042023	MECAER AVIATION GROUP S.p.A.			AW139	Ballast Installation P/N 6AB1AD018-001	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- NDC 6AB1AD-146 Issue A;- Owner's Manual P/N 6AB1WNM-2-21 Revision A;or later approved revision.- RFM Supplement 6AB1RFM-1-12 Revision A;or later revisions of the above listed documents approved by EASA.	This STC is only installable on AW139 Helicopters equipped withAgustaWestland Active Vibration Control System P/N 4G1830F00111 or4G1830F00211.	05/11/2012	Active	10042023
10042037	FLYBE LIMITED	REV. 1	CAA UK RESPONSIBILITY	ERJ 190-200 STD/LR/IGW ERJ 190-100 STD/LR/ IGW/ECJ/SR	Embraer ERJ 190 - Installation of Tropospheric Airborne Data ReportingSystemThis EASA approval is an update of the EASAapproval ref. 10042037Description as per Associated Technical Documentation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. RE2088-06 Issue 3, dated 07/11/2012AFM Supplement RE2088-18 Issue 2, dated 06/11/2012.ICA Supplement RE2088-17 Issue 3, dated 01/10/2012.or later revisions of the above listed documents approved by EASA	ALS update as stated in ICA Supplement RE2088-17 Issue 3, dated01/10/2012.	08/11/2012	Active	10042037
10042039	ORCON CORPORATION		FAA STC ST02350LA	CL600-2B19	Orcon Thermal/Acoustic Insulation System for Bombardier Challenger 850Series Aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST02350LA dated 6th May 2011.Orcon Corporation's Index List, No. F83008, Revision B, dated April 20,2011.Orcon Corporation's Continued Airworthiness Instructions, Document No.CAI-CL850 Revsion A, dated January 5, 2011or later revisions of the above listed documents approved by EASA inacc...	None	05/11/2012	Active	10042039
10042045	ASI INNOVATION	REV. 2		E90	Mast with relay antenna installation.Revision 1 : Update ofdrawings on ASI-MDL-0101-07<(>,<) >Extension of applicability to all MSN on ASI-AFM-0101-01 and;Update of above technical documentation on SDL ASI-SDL-0101-03 toreflect the changes.Revision 2 was issued to correct a typing mistake in Rev. 1....	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASI-FAM-0101-03 dated 23/07/2013ASI-SDL-0101-03 dated 23/07/2013ASI-AFM-0101-01 dated 24/06/2013or later revisions of the above listed documents approved by EASA.	The approval holder shall fulfill the obligations of Part 21, Paragraph21A.109.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the a...	28/08/2013	Active	10042045

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042075 (EASA.IM.A.S.00252)	ARMSTRONG AEROSPACE Inc.	REV. 2	FAA STC ST01997CH	DC.9-83 (MD-83)	Installation of Honeywell Rescu 406AF/ AFN system on DC-9-83(MD-83).This Rev. 2 is to correct a typo in the original STC number.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DC104-3063-00 Rev. G dated 30 October 2012 Master Data List;DC113-7000-00 dated 10 August 2009 Instruction for ContinuedAirworthiness;DC 303-3063-00 Rev. C Aircraft Flight Manual Supplement;DC304-7000-0 0 dated 15 June 2009 Weight and Balance Manual Supplement;ARM88-7000-00 dated 15 June 2009 Aircraft...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/03/2013	Active	10042075
10042079	AEROLITE AG	REV. 2		AW139	EMS Equipment P/N 139-0004728-501This STC revision is issued for the purpose of transferring the STC toAerolite AG.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- RFM Supplement Doc. FMS-139-0004728-501 Revision Cor later revisions of the above listed documents approved by EASA.-Operations Manual Doc. OPM-139-0004728-501 Revision C- Master Document List MDL-11-026 Revision C	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/03/2016	Active	10042079
10042091	NEXTANT AEROSPACE L.L.C.		FAA STC ST10959SC	BEECHJET 400A	Installation of Rockwell Collins Pro Line 21 Electronic FlightInstrument System (EFIS) with Rockwell Collins FMS-6100, Localiserperformance with Vertical Guidance (LPV) approach capability andUniversal Systems Company (UASC) Terrain awareness warning System (TAWS).	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:FAR 25 Amendments 25-1 through 25-40FAR 25.1335, 25.1351(d), 25.1353(c)(5), 25.1447, at Am 41FAR 25.29, 25.255, 25.1353(c)(6), at Am 42FA...	Installation in accordance with Nextant Aerospace LLC Master DrawingList Doc No 373-00-001 Rev W, dated March 29, 2012;Operation in accordance with:-For aircraft equipped with Pratt & Whitney JT15D Engines FAA ApprovedFlight Manual Supplement, Nextant Aerospace LLC Doc No 373-00-0008Revision IR, dat...	None.	07/11/2012	Active	10042091
10042094	JAMCO AMERICA, INC.		FAA STC ST01514SE	B747-400	Lavatory and galley modification of 747-400 series airplanes inaccordance with Jamco America, Inc. Master Data List IA-102MDL, Rev. D,dated March 15,2005, or later FAA approved revision.Validation of FAA STC ST01514SE.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Jamco America, Inc. Master Data List IA-102MDL, Rev. D, dated March 15,2005;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	FAA STC ST01492SE, interior reconfiguration of passenger seating, mustbe installed concurrently with this STC.	07/11/2012	Active	10042094
10042096	B/E AEROSPACE, Inc. - FSI		FAA STC ST02166SE	747-400	Installation of additional Crew Rest Bunks in the Door 5 Overhead CrewRest.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.The Certification basis for this modification is in accordance with TypeCertificate Data Sheet A20WE, in addition the following amendment...	Validation of FAA STC ST02166SECert Plan B1FS103-D10 d.d 23-9-2012Master Drawing List B1FS103-D01 Revision B d.d. 26-10-2012The Airplane Flight Manual Supplement, FSI document TP11-103AFM d.d. 24-10-2011The supplemental Instructions for Continued Airworthiness, FSI documentB1FS103D15 d.d. 22-11-2012o...	Maximum number of occupants of the Door 5 overhead crew rest is eightpersons.	08/11/2012	Active	10042096

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042099	CONCORDE BATTERY CORPORATION		FAA STC SA01118WI	SEE EASA APPROVED MODEL LIST	Installation of the Concorde FLA or VRSLA RG series batteries in CessnaSingle Engine Airplanes listed on the attached Approved Model List (AML) in accordance with Concorde Battery Corporation, Master Drawing ListDwg. No. 5-0148, Revision A,dated August 16, 2002, or later FAAapproved revisions.Valida...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Concorde Battery Corporation, Master Drawing List Dwg. No. 5-0148,Revision A, dated August 16, 2002;Concorde Battery Corporation, Instructions for Continuing Airworthinessfor the RG series batteries Doc. No. 5-0171, Revision M, dated March15,2012;Concorde Battery Corporation, Instructions for Conti...	None.	08/11/2012	Active	10042099
10042101	CHIPPEWA AEROSPACE, Inc.		FAA STC ST02604AT	DHC-8-301,-311,-314,-315 DHC-8-201,-202 DHC-8-102,-103,-106	Installation of a Honeywell MK VIII Enhanced Ground Proximity WarningSystem (EGPWS).	FAR 25 as per EASA.IM.A.191, Issue 6 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation:Must be in accordance with Chippewa Aerospace Inc. Master Drawing ListD8-3443-0001 and Engineering Order B8-3443-1001<(>,<)> Rev. IR, dated28. October 2002.Operation:Must be in accordance with approved Chippewa Aerospace Inc. FlightManual Supplement D8-3443-01-1012, Rev. 5 dated 12. Mar...	The aircraft must be equipped with the factory installed HoneywellGround Proximity Warning System (GPWS).	08/11/2012	Active	10042101
10042160	FOKKER SERVICES B.V.			B737-600/-700/-800/-900/-900ER	Introduction of LED light assembles in the Boeing B737 NG aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan CP-0101, Issue 1Certification Record Report CRR-0101, Issue 1ICA Supplement SE-755or later revisionsof the above listed documents approved by EASA	none	12/11/2012	Active	10042160
10042171	S4A SOLUTIONS FOR AVIATION, S.L.			C-212-200	"Installation of Iridium satellite phone". A satellite phone is added tothe airplane. This satellite phone is not located in the cockpit and itis used only by an operator located at the rear of the passenger cabin,according to "Plan de Certification A1203-CPL01", Edición 6, Date: 12/11/2012.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1.,,"Plan de Certification A1203-CPL01", Ed 6, Date: 12/11/2012;2.,,"Suplemento al Manual de Vuelo A1203-HDK01", Ed 3, Date: 10/05/2012;3.,,"Suplemento al Manual de Mantenimiento A1203-HDK02", Ed 2, Date: 07/05/2012;4.,,"Suplemento al Manual de Cableado A1203-HDK03", Edición 3, Date:04/09/2012;or lat...	None.	12/11/2012	Active	10042171
10042191	DELTA ENGINEERING CORPORATION		FAA STC ST02049NY	B747-400	Installation of Panasonic Avionics Corporation System 3000iPassengerEntertainment System in accordance with Delta Engineering Master DrawingList 0107-05381-2073, Revision D, dated June 08, 2005 or later approvedrevision.Validation of FAA STC ST02049NY.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:Title 14 CFRPart25 including amendments 25-1 through 117 for25.301, 25.303,25.305, 25.307, 25.365, 25.601, 25.603, 25.605, 25.609,25.61...	0107-05381-2073.Rev D, dated June 8, 2005 Master Data List;0707-05387-2073 Rev. -, dated March 24, 2005 Instructions for ContinuedAirworthiness;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None.	14/11/2012	Active	10042191
10042194	AIRCRAFT CABIN MAINTENANCE GmbH			SEE APPROVED MODEL LIST	Installation of refurbished Passenger Seat Belt P/N EPA 6488-2-01-40 on16g seats	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Refer to Master Document List E/O No. 104-1001541 Rev. 0 (12.11.2012) orlater revisions of the above listed documents approved by EASA	As per Service Bulletin No. 104-1001541 SEB 06 00, latest revision	14/11/2012	Active	10042194

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042211	ARMSTRONG AEROSPACE Inc.	REV. 1	FAA STC ST02377CH	A320-232, A321-232 A319-131, A319-133	EASA validation of FAA STC ST02377CH "Installation of a Rockwell CollinsTailwind 560 Satellite System and modification of a Thales Top Seriesi3000/i4000 In flight Entertainment (IFE) System"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See Armstrong Aerospace's documents:- Master Data List Doc.No. DC104-4038-00, Revision C dated July 31st2007 and- Airplane Flight Manual (AFM) Supplement Doc. No. DC303-4038-00Revision A, FAA approved August 21st, 2007 and- Instructions for continued airworthiness Doc. No. DC113-4038-00,Section 2,"...	- The FAA STC ST02314CH validated through EASA STC Approval10042212 forAft Cargo Bay Equipment Rack Installation must be installed on aircraftprior or in conjunction with this STC design change.Prior to installation of this modification it must be determined thatthe interrelationship between this m...	20/08/2013	Active	10042211
10042212	ARMSTRONG AEROSPACE Inc.		FAA STC ST02314CH	A321-231,-232 A320-232,-233 A320-111,-211,-212,-214,-231 A319-131,-132,-133 A319-111,-112,-113,-114,-115	EASA validation of FAA STC ST02314CH "Installation of an Aft Cargo BayEquipment Rack"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See Armstrong Aerospace's documents:- Master Data List Doc.No. DC104-3095-00, Revision D dated April 09th2007"or laterrevisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/or the Technical Implementatio...	none	15/11/2012	Active	10042212
10042279	PMV ENGINEERING			B747-400	Installation of provisions for the use of EFB Class 2.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:EASA CS 25 Amendment 4JAA TGL 36 : "Approval of Electronics Flight Bag (EFB)"The requirements for environmental protection and the associ...	AVI-0035-CIR-R03AVI-0035-AFMS-R01AVI-0035-ICA-R01AVI-0035-MELS-R00AVI-0035-AMMS-R00or later revisions of the above listed documents approved by EASA.	EASA STC 10040901 is a prerequisite for this modification.	20/11/2012	Active	10042279
10042281	SOCIETE AIR FRANCE S.A.			747-400	CorsairFly cabin reconfiguration and SiT IFE installation.Cabin refurbishment and new IFE system installation.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CRI D-GEN02 PTC (HR/ SD seat materials)CRI E-22 (Cabin Attendant Direct View)The requirements for environmental protection and the associa...	CAS-B747-11-012 revision 0, dated 20th November 2012 - Change ApprovalSheetSOCPL-B747-11-012-037 rev 1, dated 15th November 2012 - Instructions forContinued Airworthiness.or laterrevisions of the above listed documents approved by EASA	none	21/11/2012	Active	10042281
10042290	RUAG AEROSPACE SERVICES GmbH	REV. 1		CL-600-2B16 CL-600-1A11, CL-600-2A12	Flight Management System NZ-2000 - Upgrade to SW 6.1	As per TCDSThe Certification Basis for the original productremains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original productareunchanged and remain applicable to this certificate/ appr...	RUAG Master Document List133F-MDL Rev N/C dated 19 November2012RUAG Approval for Aircraft Modification133F-CN Rev N/C dated 19 November 2012RUAG Airplane Flight Manual Supplement133F-AFMS Rev N/C dated 13 November 2012or later revisions of the above listed documents approved by EASA	none	21/11/2012	Active	10042290

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042291	RUAG AEROSPACE SERVICES GmbH			CL-600-2B16 CL-600-1A11, CL-600-2A12	ACSS TCAS II / 2000 Change 7.1	As per TCDSThe Certification Basis for the original productremains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original productareunchanged and remain applicable to this certificate/ appr...	RUAG Master Document List133G-MDL Rev N/C dated 19 November2012RUAG Approval for Aircraft Modification133G-CN Rev N/C dated 19 November 2012RUAG Airplane Flight Manual Supplement133G-AFMS Rev N/C dated 13 November 2012or later revisions of the above listed documents approved by EASA	none	21/11/2012	Active	10042291
10042292	LUFTHANSA TECHNIK ENGINE SERVICES,INC.		FAA STC ST09033SC	MYSTERE FALCON 50	Installation of a quick drain kit on Environmental Control UnitValidation of FAA STC ST09033SC	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Bizjet Master Drawing List N° BJ21-215001, Rev. A dated 06 Feb. 1995or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF(or subsequent revisions ofthis decision).	None	21/11/2012	Active	10042292
10042295 (EASA.IM.A.S.03158)	THE BOEING COMPANY	REV. 1	FAA STC ST01697SE	737-700/-800/-900ER	Lower Cabin Altitude (LCA) modification: cabin altitude reversion to 6,500 ft in lieu of 8,000 ft at 41,000 ft flight altitude. Modification in accordance with Boeing's Master Document Listfor Lower Cabin Altitude modification D926A200.Lower Cabin AltitudeModification Certificate history:- Initial i...	B737-700/-800: The Certification Basis (CB) for the original productremains applicable to this certificate/ approval.B737-900ER: The applicable certification basis is detailed in the annexto this certificate.ANNEXThe applicable Certification Basis for the B737-900ER aircraft isrecorded in the CRI A0...	-"Master Drawing List"; Figure 1 of “Master Document List for LowerCabin Altitude Modification, Boeing Model 737 Airplanes” D926A200revision AM dated September 17, 2012-"737-700 FAA Approved Airplane Flight Manual" D631A001 unique to eachBBJ aeroplane serial number-"737-800 FAA Approved Airplane Fl...	-Approval of this change in type design is limited to the eligibleaeroplane serial numbers listed in Figure 1 of D926A200-It is the Operator’s responsibility to ensure that all future repairs,alterations and modifications (RAM) affecting the pressure vessel aresubstantiated and approved for the incr...	04/07/2013	Active	10042295
10042297 (EASA.IM.A.S.01059)	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 3	FAA ST01646LA	ATR 72-212A ATR 72-212 ATR 72-202, ATR 72-212 ATR 72-202 ATR 42-320 ATR 42-300, ATR 42-320 ATR 42-300	Installation of ACSS Terrain and Traffic Collision Avoidance System(T2CAS) on ATR 42 / 72 aircraft.This modification installs an ACSS T2CAS.The revision 1 introduced an AFM Supplement update.The Revision 2 updates the ACSS T2CAS software from TCAS Version 7.0functionality to Version 7.1 functionalit...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-ACSS Master Data List document, ref: 8900038-004, RevisionC, dated 17October 2014<(>,<)>-EASA Airplane Flight Manual Supplement (AFMS), ref: 8004809-001,Revision B-Instructions for Continued Airworthiness (ICA) document, ref: 8009150-600,dated 08 September 2014-ACSS OSD-MMEL Supplement ref. 801011...	None	10/06/2022	Active	10042297
10042309	ASSOCIATED AIR CENTER, L.P.	REV. 4	FAA STC ST10913SC	A319-133	Validation of FAA STC ST10913SC - Amendment to VIP InteriorSTC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-4302-010 Isolated CompartmentsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunc...	-,,FAA Supplemental Type Certificate ST10913SC, amended November 17,2014-,,Master Document List, reference document 2925000001 Rev. E, datedNovember 17, 2014-,,JAR Part 25 Compliance Check List, reference document 2925000099 Rev.A, dated November 17, 2014-,,FAR/JAR Part 25 Analysis, reference docume...	This modification is applicable to MSN 4992Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducenoadverse effect upon the airworthiness of the product.	21/11/2014	Active	10042309

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042314	BOMBARDIER Inc.	REV. 7	TCCA SA12-16	BD-700-1A10, BD-700-1A11	Installation, Aircraft Completion Modifications – EASA.IM.A. 009BD-700-1A10 and BD-700-1A11Revision 2 includes the installation of large glass items in the cabinapplicable to Aircraft S/N 60003Revision 3 updates the certification basis for fire extinguishersaccording CS 25.851(a) and (c) at Amdt 12Re...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s):CRI D-100 Issue 2, Doors between Passenger CompartmentsCRI D-200 Issue 2, Side Facing DivansCRI D-300 Issue 2, Passenger Information Si...	-TCCA STC SA12-16 issue 3-Common Design Change Record Revision Notification - Installation ofHalon-free Fire Extinguishers Ref: P906062 Rev C dated 18-Feb-2025-Configuration Definition Record – Bombardier BD-700-1A10 andBD-700-1A11 Aircraft Completion Modifications Ref: RAZ-BM700-001 Rev AHEdated 01...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.EASA approved configurations are identified in Configur...	07/04/2025	Active	10042314
10042345	TAMARACK AEROSPACE GROUP, INC.		FAA STC SA02216SE	SR20/SR22	Removal of mechanical link between engine throttle control and propeller RPM control. Installation of a separate RPM control lever, linkagebetween Cirrus RPM cable/cam followers, center console to accommodatethree-lever configuration, new knobs for all levers, and newinstallation hardware.FAA STC SA...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List: TAG-CSQ-301, revision B, dated March 7, 2012;Installation Manual/ Instructions for Continued AirworthinessSupplement: TAG-CSQ-203, revision IR, dated January 30, 2012;Airplane Flight Manual Supplement: TAG-CSQ-201, revision IR, datedFebruary 9, 2012;or later revisions of the abo...	SR20 serial numbers 1005 through 1885;SR22 serial numbers 0002 and subsequent without Garmin PerspectiveAvionics Installation;SR20 airplanes equipped with Hartzell BHC-J2YF-1BF/F7694 propellerassemblies must have a placard installed reading "Avoid operationbetween 1900 and 2200 rpm above 24" manifo...	26/11/2012	Active	10042345
10042346	ACS-NAI Ltd.		TCCA SA02-127 / ACG. 21NE2.108	DHC-8-301,-311,-314,-315 DHC-8-201,-202 DHC-8-102,-103,-106	Installation of an Improved Gound Power Current Limiter(ACS-NAI Ltd. Modification Data Summary D 11900)TCCA STC SA02-127, Issue 1	FAR 25 as per EASA.IM.A.191, Issue 6 (incl. EWIS)The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remai...	Installation:Must be in accordance with-,,ACS-NAI Ltd. Modification Data Summary D 11900, Revision C, dated22.03.2012 and-,,ACS-NAI Ltd. Installation Instructions D 11981, Rev. E,dated23.03.2012.Maintenance:Must be in accordance with-,,ACS Ltd. Maintenance Manual Supplement D 11971, Revision A, dat...	None.	26/11/2012	Active	10042346
10042353	NEXTANT AEROSPACE, L.L.C.	REV. 1	FAA STC ST02371LA	400A	Installation of Williams International FJ44-3AP engines as replacementfor the original Pratt & Whitney Canada JT15D-5 units and associatedsystems (Configuration A) and (/or) installation of Nextant Winglets(Configuration B).	See Annex.	Installation according to the Nextant Aerospace Master Drawing ListMDL-NXT-001 Revision IR dated 22/08/2011.Operation according to the Flight Manual Supplements for the applicableinstalled configuration(s):- NXT-AFMS, Rev IR, dated 15/09/2011<(>,<)>-NX0047-AFMS-0101, Rev IR dated 10/03/2017Maintena...	- Nextant Aerospace FAA amended STC ST10959SC (EASA Approval 10042091),dated 26/09/2011 or later FAA approved revisionsis required as part ofthis alteration- The new Vmca and Vmcg values are 94 KIAS and 93 KIAS respectively.- The new engine minimum rated thrust is 3,031 lb at sea level, flatrated t...	23/08/2017	Active	10042353
10042362	DART AEROSPACE Ltd.	REV. 1	TCCA SH 90-4 ISSUE 4	AS355F2, AS355N, AS355NP. AS355E, AS355F, AS355F1,	Installation of rear locker extender as defined in Dart Aerospace LtdMaster Document List No. MDL-D350-604 Rev. C.Note 1.This approval amends DGAC STC 168-SI0994 to add the AS355Nand AS355NPaircraft models.Note 2.This STC is the validation of TCCA STC SH90-4 Issue 4.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FMS D350-604 Rear Locker Rev. B dated 15/11/2011or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU /CanadaBilateral Agreement.	None	27/11/2012	Active	10042362

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042367	SERAM SARL			SEE EASA APPROVED MODEL LIST	Installation of a Garmin GNS 430/A/W/ AW system, a GA 35/56 GPS antenna,a GI 106A CDI indicator, a Bendix/King KX 155 NAV/COM system, aKI-203/4/8/9 VOR/ILS indicator, a KN 62A DME receiver, GPS annunciationlights and AV22, KA60, CI 105 antennas.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/or emissions level of the original productare unchanged and remain applicable to this certificate/ approval.	AFM supplement FM406R for BRNAV/PRNAV/ RNPapp operations revision 0 dated30/10/2012;AFM supplement FM406R for IFR operations revision 0 dated 30/10/2012;AFM supplement FM406R for VFR operations, revision 0 dated 11 /06/2012;SERAM modification approval sheet n° FM406R dated 26/11/2012;or later revisio...	Initial installation of this design change must be performed byauthorised SERAM technical personnel.This installation is approved for VFR, IFR, RNAV and RNP Approachoperations without coupling of navigation systems to an autopilot or aflight director. LPV approaches are authorised only with GNS 430s...	27/11/2012	Active	10042367
10042374	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST01751LA-D	GIV-X & GV-SP	Installation of EROS Convertible MLD20 Series Crew Oxygen Mask -Regulator with Detachable Smoke GogglesSTC revision of the EASA STC 10042374 to include GIV-X model	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,FAA STC ST01751LA-D, amended on 13th May 2014-,,FAA Statement of Compliance, ref. 100G-14-179, dated 28th May 2014-,,Installed in accordance with Gulfstream Aerospace Corporation IndexList, ref. GC544538000, Revision G, dated 12th May 2014-,,EASA/JAR Compliance Report, ref. CE528043005, RevisionN...	It is the installer responsibility to ensure that all STCs fitted areEASA approved.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upo...	30/05/2014	Active	10042374
10042377	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01957CH-D	GV, GV-SP	Installation of an Airshow RF/IF Remote Controller	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC ST01957CH-D, re-issued 31st July 2012-Installed inaccordance with Gulfstream Aerospace Corporation MasterDrawing List GC516028000, Rev. A, dated 8th September 2004.-EASA/JAR Compliance Report, ref. CE528043004, Revision -, dated 7thNovember 2012-Instruction for Continued Airworthiness, ref...	None	28/11/2012	Active	10042377
10042407	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02518CH-D	GV-SP	Installation of a 16 Passenger Corporate Aircraft Interior	JAR 25, Change 15The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate...	-FAA STC ST02518CH-D, re-issued 9th October 2012-Installation in accordance with Gulfstream Aerospace Corporation MasterDrawing List GC522046078, Revision A, dated March 13, 2008-EASA/JAR Compliance Report, ref. CE528043003, Revision -, dated 16thNovember 2012-Airplane Flight Manual Supplement, ref....	This STC approval is limited to the installation in GV-SP Serial NumberSN 5171	29/11/2012	Active	10042407
10042409 (EASA.R.S.01577)	ESG ELEKTRONIKSYS TEM-UND LOGISTIK-GmbH			EC135 T2, EC135 T2+. EC135 P2+, EC135 T1, EC135 P1, EC135 P2,	Trakka A800 Searchlight InstallationGimbal installation of a 800W searchlight and related electrical andmechanical provisions.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EC135 Flight Manual Supplement "Trakka A800 Searchlight Installation"0010-FMS-070, Rev. 0or later revisions of the above listed documents approved by EASA-Instructions for Continued Airworthiness (AMM, WDM, IPC Supplements)0010-ICA-081, Rev. 01-Installation Instruction - ESG Modification 135-0010S...	- Activation and/or use of IR-Filter is not approved-Activation and/or use of Laser is not approved	29/11/2012	Active	10042409

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042417	LUFTHANSA TECHNIK AG			A320-211	Integration of the W-IFE (Wireless In-Flight Entertainment)system onA320.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Declaration of Compliance ADC 3491 Rev. IR, dated 28/11/2012;- Compliance Record List CRL23-12/31M Issue 1 Rev. 0, dated 27/11/2012;- Supplemental Type Definition Document STDD23-12/31M Issue 1 Rev. 0,dated 28/11/2012;- Airplane Flight Manual Supplement A-00-12/45-AFM Issue 1 Rev. 1, dated21/11/20...	This approval is limited to MSN 0110.	29/11/2012	Active	10042417
10042418	JET AVIATION AG, BASEL	REV. 1		A319-115	Change to VIP Cabin Interior OutfittingThis change to STC 10042418 allows dual operation Private or Commercial.Conversion from Private to Commercial Operation and from Commercial toPrivate requires a maintenance action.See Master Data ListBCJ04353-001 Rev. E	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Conditions or Equivalent Safety Findings:CRI D-4301-017 DEV Installation of Interior DoorsCRI D-4302-017 SC Isolated CompartmentsCRI D-4305-017 DEV Firm HandholdCR...	Aircraft Flight Manual Supplement: BCJ04353-201-01 Rev. F;Instruction for Continued Airworthiness: BCJ04353-150-01 Rev.A;EWIS Instructions for Continued Airworthiness: BCJ04353-150-02 Rev. A;Cabin Attendant Operating Manual AIY-04 Rev. E;Conversion Manual, Private - Commercial Operation AIY-07 Rev....	S/N: 4353Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	29/11/2013	Active	10042418
10042428	APPAREO SYSTEMS, L.L.C.		FAA SR02797CH	AS 350 B3, AS 350 BA AS 350 B1, AS 350 B2	Installation of Vision 1000 System in accordance with Vision 1000 MasterDocument List 606586-000011This STC is the validation of FAA STC SR02797CH (date of issuanceDecember 28, 2009)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Appareo Systems Vision 1000 Master Document List 606586-000011, Revision1.10 dtd 27 April, 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	None	30/11/2012	Active	10042428
10042436	EADS-CASA			A330-243	Installation of a Cockpit Door Surveillance System in the A330	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Airbus Military Document Ref. ME-FU-DT-120055, dated 29/10/2012"A330 Cockpit Door Surveillance System Certification"2. EADS - CASA Declaration of Compliance for the EASA Project0010019789-001 dated 29.11.2012	None	30/11/2012	Active	10042436
10042442	BINDER MOTORENBAU GmbH	REV. 1		DG-500 M	TM-Triebwerk-B3 - Improved Engine MountingExchange of the engine mounting plate from an aluminium version	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Technische Mitteilung (TM Triebwerk- B3) Solo-Umbau – CfK-Frontplatteor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None.	25/10/2019	Active	10042442
10042466	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	A340-300	Installation of new Business Class Avio EBIZ Seats and IMS Rave IFESystem.The FWD cabin is currently configured with BCand EY seats which will beremoved and replaced with new Avio BC seats. The Rockwell Collins IFEsystem will be removed from the FWD Cabin and replaced with the IMS RAVEIFE system. I...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	JN284-002 ADC17 (1) Issue 3 Master Data List dated 30th of November2012.JN284-002 ADC57 (1) Issue 1 Compliance Evaluation Report dated 4th ofApril 2012.or later revisions of the above listed documents approved by EASA	None	03/12/2012	Active	10042466

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042467	KUERZI AVIONICS AG	REV. 1		PC-12/45	Additional Functions to STC 10042467- New Universal Avionics Software Release EFI890 SCN 1017.1.7 installed- TAWS Alerts inhibit switch installed- TAWS Speaker Alerts inhibit switch installed- ADS-B "Out" inhibit switch installed	FAR 23 Amdt: 42The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:SCs or ESFs: For this change compliance to FAR 23 Amdt 42 andFAR 23.562 (d) Amdt 44, FAR 23.571(c) Amdt. 48, FAR 23.573(b)...	Master Document List 1: MDL-201110853, Rev. A, dated 19.06.2014Master Document List 2: MDL-201314477, Rev. N/C, dated 19.06.2014Instructions for continued airworthiness: ICA-201110853, Rev. A, dated26.11.2012Airplane Flight Manual Supplement: FMS- 201110853, Rev. A, dated28.05.2014or later revisions...	S/N: 134; HB-FOGThe approval holder shall fulfill the obligations of Part 21 §21.A118.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupo...	23/06/2014	Active	10042467
10042477	S-TEC CORPORATION			BN-2B-20, BN-2B-26 BN-2A-6 BN-2A-2, BN-2A-8 BN-2A-20, BN-2A-26	Installation of S-TEC System 55/55X Two-Axis Automatic Flight GuidanceSystem Model ST572.		- Bulletin No 672 Revision 2 dated August 21,2002 & M.D.L. No 92744Revision B dated August 21,2002 or later approved revision- AFM Supplement EASA891140 dated May 05,2005 or laterEASA approvedrevision	Only applicable to Model BN-2A-6 when modification NB/ M/430and NB/M/631are installed.	31/05/2005	Active	10042477
10042497	OGMA, INDUSTRIA AERONAUTICA DEPORTUGAL, S.A.			EMB-145EP,EMB-145LR, EMB-145LU	VIP room extension and Iridium Satphone system installationon EMB-145	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Change Dossier doc. N° 12P06 CD 00 001, Rev. Orig. dated 30.11.2012- Airplane Flight Manual Supplement doc. N° 12P06 MS 00 010, Rev. Orig.dated 15.11.2012- Maintenance Manual Supplement doc. N° 12P06 MS 00 020, Rev. Orig.dated 30.11.2012or later revisions of the above listed documents approved by...	The change is applicable to the following aircraft having OGMA STC10037579 incorporated, and that do not have flux valve sensors: A/C SN145076, 145084, 145129, 145135, and 145147	05/12/2012	Active	10042497
10042498	UNIAIR			B300	Installation of 230 V AC - 50 Hz electrical distribution onaircraft, toallow passengers to plug personal electronic devices. According toSB-UAE-003-12-001.	The Certification Basis of the original product and the followingadditional airworthiness requirements are applicable to this change.Special Condition "Power supplies for cabin (TGM/25/10)" applied throughCRI F-64.The certificated noise and/ or emissions levels of the original productare unchanged a...	Master data list MDL 003 12 rev.3 dated 28.Nov. 2012;Airplane Flight Manual Supplement UAE-AFMS-12-001 rev. 1;Airplane Maintenance Manual Supplement UAE-AMMS-12-002 rev.1.	If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.	05/12/2012	Active	10042498
10042507	AVIDYNE CORPORATION	REV. 1	FAA STC SA00323BO	182Q, 182R, 182S, 182T, R182 182K, 182L, 182M, 182N, 182P, 182E, 182F, 182G, 182H, 182J,	Installation of Avidyne Corporation Autopilot; model DFC90,p/ n700-00170-022 (28-Volt Electrical system) or p/n 700-00170-024 (14-VoltElectrical system), loaded with Release 0 Software, as a replacement forthe S-Tec Autopilot.	The Certification Basis of the original product and the followingadditional / alternative airworthiness requirements are applicable tothis change: As specified in the original FAASTC No. SA00323BO dated01-October-2012.The certificated noise and/ or emissions levels of the original productare ,,unch...	FAA approved S-TEC Master Document List No. AVDFC - 115 rev.00, dated25-Sep -2012.FAA Approved Airplane Flight Manual Supplement No. 600-00293-000, rev. 00dated 01-October-2012.Instruction for Continued Airworthiness No AVDFC-125, rev.00 dated09-August-2012.or later revisions of the above listed docu...	Operation must be in accordance with Avidyne Corporation AFMS documentNo. 600-00293-000, rev.00 dated 01-October-2012.The AFMS must be carried in the Aircraft during all flights.Maintenance must be in accordance with ICA document AVDFC-125, rev. 00dated 09-August-2012.The ICA must be made available t...	03/12/2014	Active	10042507
10042509	AIR ALLIANCE GmbH			PA-44-180T PA-44-180	Replacement of installed Gyro system by ASPEN EFD 1000 Pro PrimaryFlight Display.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23, Amendment3The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	- Airplane Flight Manual Supplement 2012_014_PA44_506, Rev. 0or later revisions of the above listed documents approved by EASA.- Installation Manual 2012_014_PA44_500 , Rev. 0- Instructions for Continued Airworthiness 2012_014_PA44_507, Rev. 0- Master Document List 2012_014 PA44_Form 2, Rev. 0	None.	05/12/2012	Active	10042509

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042513	ASI INNOVATION	REV. 4		ATR 72-201 ATR 42-300, ATR 42-500	Radio Honeywell HF 950 InstallationThis modification consists in installing the Bendix/King KHF950 HF/ SSBCommunication System. This includes mainly the embodiment of HF antenna,control unit, receiver, amplifier coupler and electrical protection.Revision 1 extends the applicability of the STC to ATRR...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:ATR Special Condition H-01: Instructions for Continued Airworthiness forElectrical Wiring Interconnection System (EWIS).CS 25 Amdt. 4 (Applicable requirements as per ASI d...	STC Data List (ATR 42-300), ref : ASI-SDL-0095 Issue 04, dated 04December2012Aircraft Flight Manual Supplement (ATR 42-300), ref : ASI-AFM-0095,dated July2012Instruction for Continued Airworthiness (ATR 42-300), ref : ASI-MPS-0095Revision 01, dated October 2012STC Data List (ATR 42-500), ref : ASI-S...	This STC is limited to : MSN 148, MSN 227, MSN 559, MSN 643andMSN 667.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwor...	07/06/2013	Active	10042513
10042519	JET AVIATION ST. LOUIS, Inc.		FAA STC SA02789CE	MYSTERE FALCON MF 50	EASA validation of FAA originally approved STC SA02789CE "Installationof a Bendix/King CAS-81 TCAS System".	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See original FAA approved STC SA02789CE documents:-,,Jet Aviation Certification Drawing List No. AD910011, Revision Fdated March 11th, 2011 and-,,Jet Aviation Report No 13-328M001, Revision F, FAA Flight ManualSupplement dated May 13th, 2011 and-,,Instructions for Continued Airworthiness, Jet Aviat...	Aeroplanes modified in accordance with this STC must be maintained inaccordance with Approved Instructions for Continued Airworthiness, JetAviation Report No. 13-027E054, SectionO - Airworthiness Limitations,Revision NC dated June 03rd 2011 or later revisions approved by EASA inaccordance with EAS...	06/12/2012	Active	10042519
10042528	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST03056CH	737-800	Validation of FAA STC ST003056CH: Installation of PanasonicGlobalCommunications suite (GCS) System Provisions in accordance withArmstrong Aerospace Master Data List DC104-9041-00, Revision B, dated 22December 2011.Revision 1: Transfer of STC 10038435 from Armstrong Aerospace as per FAASTC ST003056C...	CS-25 amendment 2 for affected parts, except:- JAR 25.571 (CRI A11-05) and JAR 25.581 (change 13) as per TCDS- CRI H-01EWIS at issue 3 dated 17 Feb 2012The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Data List DC104-9041-00, Revision B, dated 22 December 2011;- AFM Supplement DC303-9041-00, Initial release, dated 19 December 2011;- EWIS/ ICA source document DC113-9041-00, Revision A, dated 28 October2011;- Structural Repair Manual SRM for the B737-800 dorsal GBS radomeattachment skirt as...	1) The Panasonic Global Communication Suite System for which theseprovisions are installed and these provisions activated in accordancewith a separate STC, EASA STC 10038436.2) The aircraft operator must perform the instructions for continuedairworthiness and comply with the Airworthiness Limitation...	25/01/2013	Active	10042528
10042532	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02992CH	B737-600/-700/-800/-900/-900ER	Validation of FAA STC ST02992CH - Installation of dual Electronic FlightBag (EFB) System Provisions.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS" Issue 03 dated 20/08/2012The certificated noise and/ or em...	- Master Data List (MDL), Reference ECS-209329, Revision K,FAA approvedthe 28 August 2012- Instructions for Continued Airworthiness (ICA), Reference ECS-209337<(>,<)> Revision G,dated 22 August 2012- EWIS ICA, Reference ECS-209751, Revision N/C, dated 08 July 2011or later revisions of the above li...	1) The aircraft operator must perform the instructions for continuedairworthiness and comply with the Airworthiness Limitation Items as perthe Instructions for Continued Airworthiness (ICA), ReferenceECS-209337, Revision G, dated 22 August2012.2) Additional EASA approval is required for the complet...	06/12/2012	Active	10042532
10042547	THALES AVIONICS Inc.			A321-211,-212,-213,-231,-232	Installation of Thales Avionics IFS TopSeries In-Flight Entertainment(IFE) System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA Supplemental Type Certificate ST02435LA issued 21st November 2012- PSCP-2011-1003 Rev. H, dated 10th August 2012-Index List 255193 Rev. A, dated 21st November 2012- Reference Data List 500440-101RDL rev. L, dated 21st November2012- Master Drawing List 500440-101MDL Rev. V, dated 21stNovember-...	This STC must be installed in conjunction with EASA STC 10040704 -Aerospace Engineering Solutions (AES) - Introduction of Twin Class CabinConfiguration.	07/12/2012	Active	10042547

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042553 (EASA.IM.A.S.01044)	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 1	FAA STC SA5530NM	B737-100/200/300/400/500	FAA STC SA5530NM validation - Installation of the ACSS TCASII Systemwith Change 7.1 software	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- ACSS Index of Master Data Lists (IMDL), Reference 8900010, Revision J,FAA approved the 06 July 2010;- Airplane FlightManual Supplement (AFMS) according to Honeywell MasterData List (MDL), Reference ML4075161, Revision AH, dated 14 May 2002;- ACSS, Reference TCAS-APPS-0294, FAA approved the 24 Feb...	None.	14/12/2012	Active	10042553
10042556 (EASA.IM.A.S.00527)	SALENIA AIR CARGO AB	REV. 3	FAA STC ST09441SC	F27 MK 050	Installation of a Single Universal Avionics Flight Manual System withintegrated GPS.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List 228-00-0001 Revision H, dated 6 August 2004, orlater approved revision.2. Airplane Flight ManualSupplement No. 228-00-0011 Revision A dated 12August 2004, or later approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/03/2019	Active	10042556
10042561 (EASA.IM.A.S.01015)	B/E AEROSPACE, Inc.	REV. 1	FAA ST02716AT	737-400, 737-500 737-200, 737-300	Installation of Honeywell Ground Proximity Warning System (EGPWS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EMTEQ AFMS for Boeing 737 Series Aircraft with Honeywell Mark V or MarkVII EGPWS:- Doc. No. EMTQ-015A-FMS, dated Sept. 30, 2003 (Configuration 1 for737-300/-400/-500);- Doc. No. EMTQ-031-FMS, dated Feb. 12, 2004 (Config. 2 for 737-300);- Doc. No. EMTQ-033-FMS, dated May 6, 2004 (Config. 3 & 4 for 73...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10042561
10042562 (EASA.IM.A.S.01016)	B/E AEROSPACE, Inc.	REV. 1		737-300/-400/-500	Installation of EMTEQ Engineering dual GPS Antenna Provisions.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA STC ST02723AT-Avitas Engineering MDL Report No EMTEQ-012-MDL, Rev B	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10042562
10042564 (EASA.IM.A.S.01043)	DECA AVIATION ENGINEERING Ltd.	REV. 1		A320-200	174 Passenger - All Economy Class Passenger Seating Arrangement,O-LSA04-318/D iss 03		-Instructions for Continued Airworthiness 04230-02 Rev 1-Instructions for Continued Airworthiness 04230-03 Rev 1-Instructions for Continued Airworthiness 04230-04 Rev 1	1. This STC is limited to aircraft S/N 645, 579 and 525.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	05/02/2013	Active	10042564
10042575	AIRBUS HELICOPTERS CANADA LIMITED	REV. 1	TCCA SH96-61/LBA STC RC 1019	2. AS355E, F, F1, F2 1. AS350B, BA, B1, B2, B3, D	Installation of Left Hand and/or Right Hand Cargo Mirrors as defined inEurocopter Canada Limited Master Drawing List MDL-96-005.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ECL Master Drawing List No. MDL096-005, Issue FECL Instructions for Continued Airworthiness No. ICA-ECL-131, Rev. 0	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/09/2013	Active	10042575

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042576	AEROLITE AG			EC635T1 (CPDS) EC135 T1, EC135 T1 (CPDS) EC135 P2, EC135 T2 EC135 P1, EC135P1 (CPDS)	EMS Equipment P/N 135411-501Note: This major change to FOCASTC 25-20-85, Issue 2<(>,<)> introducesan alternative SeatSwivelling Adapter and several stowage and retainingprovisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS-204, Rev. Eor later revisions of the above listed documents approved by EASA.-Master Drawing List MDL-203 Revision D-Operations Manual OPM-204 Rev F, (Operation and Maintenance): EMSEquipment P/N 135411-501	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/06/2014	Active	10042576
10042580 (EASA.IM.A.S.00389)	AVIATION FABRICATORS, Inc.	REV. 3	FAA SA00635WI	SEE APPROVED MODEL LIST	Beech 90 Series RH Aft Jump Seat Installation KitInstallation of RH Aft Jump Seat into the aft cargo area of thepassenger cabin. Kit includes modification to the floor structure, newfloor boards, side wall structure, and shoulder harness attachment inthe aft bulkhead. Also includes additional plug i...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation, Operation and Maintenance in accordance with theapplicable STC Drawing List referred in the EASA ApprovedModel List ;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Te...	- Installation per STC drawing List AF-209 limited to aircraft withBeech (Raytheon) factory installed oxygen system forjump seatlocations.- Aircraft configured for more than 14 total occupants must be equippedwith a 49 cubic foot (or greater) oxygen system.- Compatibility of this design change with...	30/06/2014	Active	10042580
10042584 (EASA.A.S.00649)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		737-800	Mode S Transponder System for Elementary and Enhanced SurveillanceRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Aviation Traders Ltd definition Document DD/ 010/9010 Issue 2- Aviation Traders Ltd AFM Supplement Number 23 Issue 1orlater revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configurations shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatth...	10/11/2021	Active	10042584
10042597	SIERRA INDUSTRIES Ltd.		FAA STC SA09630AC	CESSNA 500	Installation of Meggitt Engine Indicating Display System.Inaccordance with Sierra Master Drawing List, SI400-001, rev.B, date29 Jan 2008.Validation of FAA approval STC SA09630AC.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Sierra Master Drawing List, SI400-001, rev. B, date 29 Jan 2008;Sierra AFM Supplement, ref 115-601, rev 2, date 7 May 2007;Sierra Maintenance Manual Supplement, ref SM-400-MMS, issue 1, date 12May 2004;Sierra Instruction for Continued Airworthiness, ref SM-400-ICA, issue 1,dated 12 May 2004;or later...	None.	10/12/2012	Active	10042597
10042599	BERINGER AERO	REV. 2		B) DHC-6 SERIES 400 A) DHC-6 SERIES 300/310/320 A) DHC-6 SERIES 200/210 A) DHC-6 SERIES 1/100/110	Replacement of nose wheel BF Goodrich 8.90-12.5 P/N 3-1197 by Beringerwheel assembly P/N: RA-008.Revision 2: Update with new servicing instructions within ICA document	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification file: DM-STC-008 rev 04 dated 11 Mar. 2022;Installation and Instructions for Continued Airworthiness: ICA-STC-008rev 03 dated 19 Oct. 2021;or later revisions of the above listed documents approved by EASA.	None	18/03/2022	Active	10042599
10042618	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04280AT-D	GV-SP	Installation of an Executive Completion	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.-CRI D-50 "Seat deformation into the overwing Emergency Exits andEmergency Egress." - Equivalent Level of Safety/MoC-CRI F-55 "In cabin /...	-FAA STC ST04280AT-D issued 19th November 2012-EASA/JAR Compliance Report, ref. GC528043076, Revision -, dated 20thNovember 2012-Installation in accordance with Gulfstream Aerospace Corporation IndexList GC522048019, Revision -, dated 15thNovember 2012-Operation to be in accordance with GulfstreamG...	1. The installer must determine whether this design change is compatiblewith previously approved modifications.2. If the holder agrees to permit another person to use this certificateto alter the product, the holder shall give the other person writtenevidence of that permission.3. It is the installe...	11/12/2012	Active	10042618

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042639	SOCIETE AIR FRANCE S.A.			A321-111, A321-212. A320-211, A320-212, A319-111, A319-113,	Installation of the ACARS (Aircraft Communication Addressing andReporting System) CMU-900 to replace the Teledyne MUA45B	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Program CP-A320-12-003 Rev. 2, dated 03/10/2012- Change Approval Sheet CAS-A320-12-003 Rev. 0, dated 19/10/2012- Airplane Flight Manual Supplement AFMS-A320-12-003-001 Rev.0, dated23/07/2012- Compliance Check List CCL-A320-12-003 Rev. 0, dated 11/10/2012or later revisions of the abov...	This approval is applicable to the following MSN:61 ; 63 ; 102 ; 115 ; 144 ; 145 ; 155 ; 186 ; 187 ; 214 ; 227 ; 236 ; 237 ; 239 ; 270 ; 278 ; 285 ; 286 ; 287 ; 337 ; 352 ; 377 ; 491 ; 498 ;509 ; 521 ; 529 ; 544 ; 598 ; 600 ; 608; 618 ; 625 ; 637 ; 777 ; 796 ;938 ; 985 ; 998 ; 1000 ; 1020 ; 1025 ; 1...	12/12/2012	Active	10042639
10042660	CHIPPEWA AEROSPACE, Inc.		FAA STC ST02046AT	DHC-8-315. DHC-8-311, DHC-8-314, DHC-8-202, DHC-8-301, DHC-8-106, DHC-8-201, DHC-8-102, DHC-8-103,	Installation of a ground service busFAA STC ST02046AT	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	InstallationMust be in accordance with Aviation Technologies Group Master DrawingList DHC8-0001, dated 20.05.1999or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentrevisions ofthis decision)	None	12/12/2012	Active	10042660
10042689	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04249AT-D	G350 AND G450	Installation of a Cabin Interior and Airplane Completion.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:Special Condition No. 25-450-SC (Gulfstream Aerospace Corporation, ModelGIV-X Airplane; Isolation or Aircraft Electronic System SecurityP...	Installation in accordance with Gulfstream Aerospace Corporation IndexList GC420004225, Revision "-", dated January 19,2012.Operation in accordance with Airplane Flight Manual Supplement,GC41204M015, Revision "-", dated January 20, 2012, is required.or later revisions of the above listed documentsa...	1. The installer must determine whether this design change is compatiblewith previously approved modifications.2. The instructions contained in the Guidance for Follow-On Installation<(>,<)> GC422040227, Revision A, dated January 19, 2012 or later FAA approved revision must be followed for subsequen...	13/12/2012	Active	10042689
10042711	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 5	FAA STC ST02406LA	SEE EASA APPROVED MODEL LIST	Installation of Traffic Alert and Collision Avoidance Systems (TCAS II)version 7.1Revision to incorporate additional aircraft model to the Approved ModelList: 1. Hawker Beechcraft Corporation: BAe 125 Series 800Aand to revise the Master Data List, to include additional interfaceequipment part numbers...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA STC ST02406LA, issued 6th February 2012-FAA Approved Model List AML No. ST02406LA, dated 25th September 2013-Master Data List ref. doc. 8900067-002, Rev. E, dated 7th August2013-Aircraft Flight Manual Supplement ref. doc. 8008565-001, Rev. IR, dated9th August 2012or later revisions of the abo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	28/11/2013	Active	10042711
10042720	AVIONIK STRAUBING ENTWICKLUNGS GmbH			SC7 SERIES 3	Installation of PFD ASPEN EFD1000 C3	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23, Amendment3The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the orig...	- Flight Manual Supplement PFD ASR-2012-004-FMS-05.1-00, Rev. 00-Flight Manual Supplement MFD ASR-2012-004-FMS-05.2-00, Rev. 00or later revisions of the above listed documents approved by EASA.- Instructions for Installation ASR-2012-004-IFI-10-00, Rev. 00-Instructions for Continued Airworthiness0...	None.	14/12/2012	Active	10042720

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042727	SOCATA			TB20, TB21	Installation of TAS Garmin GTS800	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Garmin Instructions for Continued Airworthiness for GTS 8XXTrafficSystem, revision 2 dated 29 October 2010Socata Flight Manual Supplement S2, Edition 1 Revision 2 dated 15November 2012, English version p/n Z00.182S23T0E1R2Socata Flight Manual Supplement S2, Edition 1 Revision 2 dated 15November 201...	This STC is not applicable to airplanes equipped with a 14 V electricalsystem.Initial Installation of this design change must be performed byauthorized SOCATA personal.Modified airplanes must be equipped with Socata modification No.34-001-009 approved under EASA STC No. 10029243, rev. 3 (or laterrev...	14/12/2012	Active	10042727
10042728	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	EC135 T1,-T2,-T2+,-P1,-P2,-P2+	"East Anglia Air Ambulance Role Equipment, EC 135" for installation ofNVIS equipment based on modification BOND/MOD/063as defined inDL/ 063-099.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 27 Amdt. 2 for 27.1, . 21, .251, .301, .303, .305, .321, . 337, .341,.351, .561, .601, .603, . 605, .609, .610, .611, .613, .771, . 773, ...	- Rotorcraft Flight Manual Supplement "NIGHT VISION IMAGINGSYSTEM,POWERLINE DETECTION SYSTEM, ENGINE USAGE MONITORING", FMS/ 063-002 Issue1or later revisions of the above listed documents approved by EASA- Design Report DR/ 063-001, Issue 6- Drawing List DL/063-099, Issue 3- Instructions for Continue...	Limited to Aircraft with CPDS and FCDS installed.- This STCapplies only to the models listed above. This rotorcraftemploys Night Vision Imaging System lighting, commonly named NVISlighting, that has been certified to ensure the aircraft is compatiblewith night vision goggles (NVG). For this reasono...	14/12/2012	Active	10042728
10042732	JCB AERO SA			A330-223	Galley G11 Installation* Installation of structural provisions for galley G11* Installation of Galley G11 (dry galley)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environment protection and the associatedcertificate noise and/or emissions level of the original product areunchanged andremain applicable to this certificate/ approval.	* Certification Plan A332-00229-02-CP-01, Rev.1, dated 11stDecember2012* Project Data List A332-00229-02-PDL-01, Rev. B, dated 14th December2012* Declaration of Compliance A332-00229-02-DC-01, Initial Revision, dated12th December 2012* Instructions for Continued Airworthiness A332-00229-01-ICA-01,R...	The Pre-Mod status for this modification must be without seats or otherfurnishing.	14/12/2012	Active	10042732
10042733	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges	REV. 1		A330-223	Cabin reconfiguration and IFE installation.Description - Summary : This is a Major Change to EASA STC 10042733 toinclude new A/C Layout into approved configurations, and considersimilar IFE System, B/C and Y/C seats. Due to different Pre-Mod cabinlayout configuration the LOPA differs to the previous...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Engineering Order EO_M17300103_RSP_23072012, rev 1 (Master document)- ICA, ref ICA_M17300103_CKA_10052012, rev 2- Aircraft Flight Manual Supplement, ref AFS_M17300103_CKA_30082012, rev1or later revisions of the above listed documents approved by EASA.	1) Prior to installation of this modification it must be determined thatthe interrelationship between this modificationand any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of the product.2) This modification must be implemented in conju...	04/06/2013	Active	10042733
10042753	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A, 525B 525, 525A	Single Installation of GPS/COMM/NAV System Garmin GTN725/750.	he Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:CS-23, Amendment 2 (not required by 21A.101)The requirements for environmental protection and the associatedcertificated noise and/ or emi...	Flight Manual Supplement ASR-2012-053-FMS-05-00 Rev. 00;or later revisions of the above listed documents approved by EASA.Instructions for Installation ASR-2012-053-IFI-10-00 Rev. 00Instructions for Continued Airworthiness ASR-2012-053-ICA-11-00 Rev. 00	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	17/12/2012	Active	10042753

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042766	APICAL INDUSTRIES, Inc.		FAA STC SR02373LA	EC130B4	Installation of Fresh Air Vents in accordance with Apical Industries,Inc. Master Document List MD130-3.This STC is the validation of FAA STC SR02373LA (date of issuanceSeptember 12, 2012).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Apical Industries, Inc. Master Document List MD130 3 Rev. Fdtd17/07/2012;Apical Industries, Inc. Rotorcraft Flight Manual Supplement RFMS130 31Rev. N/C dtd 03/08/2012;Apical Industries, Inc. Instructions for Continued Airworthiness ICA1303 Rev. B dtd 30/08/2012;or later revisions of the above liste...	None.	18/12/2012	Active	10042766
10042768	HAWKER BEECHCRAFT CORPORATION		FAA STC SA00782WI-D	EASA APPROVED MODEL LIST	Modification of Collins VHF-22A/VHF-22B VHF COMM Receiver Transmitterwith CTL-22 Control Pro Line II System Installation to a CollinsVHF-22C/ VHF-22D VHF COMM Receiver Transmitter with CTL-22C Control 8.33kHz Pro Line II System Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Collins Installation InstructionsDrawing List no. AAC-0178-001or later revisions of theabove listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)	A VHF-22C unit can be installed to replace either an existing VHF-22A orVHF-22B unit. A VHF-22D unit can only be installed to replace anexisting VHF-22B unit.	18/12/2012	Active	10042768
10042771	SABENA TECHNICS BGC			A320-216,-231,-232,-233 A320-111,-211,-212,-214,-215	Installation of SICMA Dragonfly seats for Indigo on A320	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 25 Amdt 4 (except for §25.785 applicable at JAR 25 Amdt 11)The requirements for environmental protection and the associatedcertificate...	-,,Certification Plan n. 4490-01-A-2101-R00 dated 05/09/2012-,,Compliance Records n.4490-01-A-2104-R01 dated 07/12/2012-,,Master Data List n.4490-01-A-2103-R00 dated 14/12/2012-,,Instructions for Continued Airworthiness n..4490-01-A-2211-R00 dated11/12/2012or later revisions of the above listed docum...	none	18/12/2012	Active	10042771
10042785	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS LTD		CAA UK RESPONSIBILITY	747-400	Certification of drainmast p/n 24E507589G02 against 25.1455on Boeing747-467ERF MSN 37299 in order to nullify Hong KongCivil AviationDepartment Variation No VAR/ 2012/133.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MCP-1216 Rev B (Modification Certification Plan)MCR-1216 (Modification Classification Request)MOD-1216 Rev A (Modification Summary) MCL-1216 Rev B (Modification Compliance List)or later revisions of the above listed documents approved by EASA	STC is only valid for B747-467F MSN37299	18/12/2012	Active	10042785
10042791	DELTA ENGINEERING CORPORATION	REV. 3	FAA ST02926NY-D	A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-223, A330-243 A330-201, A330-202, A330-203	Activation of a Panasonic Global Communication Suite System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	- Master Data List 0154-07776-2293, Rev. C, dated 28/01/2013;- Aircraft Flight Manual 0654-07783-2293, Rev. A, dated 25,01,2013;- Instructions for Continued airworthiness 0754-07784-2293, Rev. A,dated 19/09/2012;or later revisions of the above listed documents approved by EASA inaccordance with EASA...	Operational approval to use T-PEDs must be obtained separately from thisSTC.The Panasonic GCS must interface with the following systems/ components:- T-PED FAA STC ST03106CH as validated by EASA under project ref0010015818-001- Antenna FAA STC ST02884NY-D as validated by EASA STC 10037167Prior to ins...	20/03/2013	Active	10042791
10042792	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			525A 525	WX-950 Stormscope installation.	CS 23 Amdt: 40The Certification Basis for the original product remains applicable tothis certificate/ approval.Derogation to latest amendment (Part 21A.101):Do not materially contribute to safety.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicab...	- Master Data List, Doc. No. 2016-6-16, Rev. IR, dated 12.12.2012;- AFMS, Doc. No. 2016-6-8, Rev. A, dated 25.10.2012;-ICA, Doc. No. 2016-6-10, Rev. IR, dated 27.11.2012;or laterrevisions of the above listed documents approved by EASA.	None.	18/12/2012	Active	10042792

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042804	AERO DYNAMIX, Inc.		FAA STC SR09566RC	429	Installation of Night Vision Imaging System (NVIS) / Night Vision Goggle (NVG) compatible lighting system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List (MDL), Aero Dynamix, Inc. drawing number MDL5600-01 revision J, dated 12 November 2012;-RotorcraftFlight Manual Supplement (RFMS), document number RFMS429-02, revision IR, dated 13 June 2012;or later revisions of the above listed documents approved by EASA inaccordance with EAS...	Refer to applicable Rotorcraft Flight Manual Supplement (RFMS) for listof equipment mandatory for Night Vision Imaging System (NVIS) certification.	19/12/2012	Active	10042804
10042813	CUSTOM FIBERGLASS MOLDING INC.		FAA STC SA02391CH	MX-7-180B, MX-7-180C MX-7-180A, MX-7-235 MX-7-160, MX-7-180 M-7-235, M-7-235B M-5-235C, M-5-180C, M-6-235 M-4C, M-4S, M-4T M-4-220S, M-4-180V M-4-220, M-4-220C M-4-210, M-4-210C BEE DEE M-4, M-4	Installation of Custom Fiberglass Molding Skis, Model 3000,according toMaster Drawing List CFMI 3000-9, Rev D dated 04th April 2011 or laterFAA approved revision.Installation of Custom Fiberglass Molding Skis, Model 3000-01(A/B),accordingto Master Drawing List CFMI 3000-10, Rev F dated 04th April2...	Design:Non-significant changeThe Certification Basis of theoriginal product remains applicable tothis change.Environmental Protection:The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Installation of Custom Fiberglass Molding Skis, Model 3000,according toMaster Drawing List CFMI 3000-9, Rev D dated 04th April 2011 or laterFAA approved revision.Installation of Custom Fiberglass Molding Skis, Model 3000-01(A/B),accordingto Master Drawing List CFMI 3000-10, Rev F dated 04th April2...	Installer must check availability of EASA-approval for one or morereferenced STC when airplane is modified per that / those STC(s).	19/12/2012	Active	10042813
10042830	BEECHCRAFT BERLIN AVIATION GmbH	REV. 2		C90GTI	Upgrade to INCAS Mission System Suite	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23 Amendment 4: 1306,1308This ce...	- System Description D02-B17-01, Issue 02-Installation Instructions D42-B17-01, Issue 03-Flight Manual Supplement D30-B17-01, Issue 05-Maintenance Manual Supplement D31-B17-01,Issue 02Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/03/2020	Active	10042830
10042831	GROWING ENGINEERING PARTNERS GmbH	REV. 2		A330-223	Cabin reconfigurationBy changing the existing Air Berlin Business Class InteriorConfiguration into a new Etihad Business Class Interior Configuration.Rev.2: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	JAR 25 Amdt: 13The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Data List, Doc. No. S.OAEZ.000180-MDL, Rev. 02, dated03.05.2013- ICA, Doc. No. S OAEZ 000180-ICA, Rev. 00, dated 06.11.2012- ICA, Doc. No. C OAEZ 000516-ICA<(>,<) > Rev. 00, dated 02.04.2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	20/04/2021	Active	10042831
10042832	MT-PROPELLER ENTWICKLUNG GmbH			MX-7-235, MT-7-235 M-6-235, M-7-235, M-7-235B	Installation of 3-blade MT-Propeller Model MTV-9-B/198-52	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.Compliance with the following requirements,r...	According to MT-Propeller Master Document List No. E-2196 andMT-Propeller Installation Instructions Doc. No. E-2193, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2192To be maintained i.a.w. MT-Propeller ICA Document No. E-2194or later revisions of the above li...	according limitation section of AFM-S	20/12/2012	Active	10042832

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042833	MT-PROPELLER ENTWICKLUNG GmbH			M20R, M20S	Installation of 4-blade MT-Propeller Model MTV-14-D/188-30b	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.Compliance with the following requirements,r...	According to MT-Propeller Master Document List No. E-2182 andMT-Propeller Installation Instructions Doc. No. E-2179, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2178To be maintained i.a.w. MT-Propeller ICA Document No. E-2180or later revisions of the above li...	according limitation section of AFM-S	20/12/2012	Active	10042833
10042834	MT-PROPELLER ENTWICKLUNG GmbH			LC41-550FG	Installation of 4-blade MT-Propeller Model MTV-14-D/195-30b	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.Compliance with the following requirements,r...	According to MT-Propeller Master Document List No. E-2206 andMT-Propeller Installation Instructions Doc. No. E-2203, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2202To be maintained i.a.w. MT-Propeller ICA Document No. E-2204or later revisions of the above li...		20/12/2012	Active	10042834
10042835	BOMBARDIER INC.		STC NO C-LSA03-348/D	BD-700-1A10	Aircraft Completion, 13 Passenger Interior Configuration	EASA.IM.A.009The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	Transport Canada STC No C-LSA03-348/D Issue 2 dated 19 January 2004.Aero Consulting Services Modification Data Summary D49100 Revision A.Bombardier Aerospace Flight Manual Supplements:G-FM24000044 Rev N/C Cabin Master Power SwitchG-FM25000072 Rev A Interior CompletionG-FM26000045 Rev N/C Smoke Detec...	Restricted to ASN 9093.Bombardier Service Bulletin 700-31-018 Modification - IntegratedAvionics Computers - Avionics 2001 Batch 1 IAC Upgrade must be embodied.	20/12/2012	Active	10042835
10042836	ROCKY MOUNTAIN AIRCRAFT		TCCA STC SA05-54	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of a L-3 Skywatch HP TCAS 1 System in accordance with TCCASTC SA05-54	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement, Doc. No. E101430, TCCA approved March 19, 2012Modification Instruction for Installation of L-3 Communications SkywatchHP Model SKY899, Doc. No. E101410, Rev. A, TCCA approved Sept. 25, 2012or later revisions of the above listed documents approved by EASA inaccordance with E...	none	20/12/2012	Active	10042836
10042845	ZIM FLUGSITZ GmbH	REV. 1		B737-800	Installation of ZIM Flugsitz ECO-01 EC Seats in a B737-800 Cabin	The Certification Basis for the original product and the followingadditional oralternative airworthiness requirements are applicable to thiscertificate/ approval:- CRI F-01 on IFEdate 19 December 2012The certificated noise and/ or emissions levels of the original productare unchangedand remain appl...	- Master Document List (MDL), Reference 505402-MDL-002, Revision 0D,dated 19 December 2012- Airplane Flight Manual Supplement (AFMS), Reference 505402-AFM-001,Revision 0B, dated 17 December 2012- Weight and Balance Manual, Reference 505402-WBM-001, Revision 0A,dated 19 December 2012- Service Bulleti...	1) The In-Seat IFE system shall not be used during Taxi, Take-Off andLanding.2) The ZIM Flugsitz ECO-01 EC Seats installation in accordance with thisSTC islimited to the followingB737-800 aircraft S/N 41047 and 41190.	21/12/2012	Active	10042845

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042850	JET AVIATION AG, BASEL	REV. 1		GV-SP	MDL BDBMW002-001 Rev. IR	JAR-25 Change 15 and JAR AWO Change 2 with the exceptions as per EASATCDS IM.A.070The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certif...	Rosen Aviation Remote Display STM 105478 Rev. Aor later revisions of the above listed documents approved by EASA	S/N: 5336	21/12/2012	Active	10042850
10042851	AVION RESEARCH, Inc.	REV. 1	FAA STC SA170CH	2. 175, 175A/B/C 1. 172A/B/C/D/E/F/G/H/I/K/L/M 1. 172	Installation of a Control Yoke and Instrument Panel in accordance withFAA STC SA170CH	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AVION Research International Drawing List C172ML0001, Rev. 2, dated May5, 1994, FAA approved July 8, 1994AVION ResearchInternational Installation Instructions C172/175-8001,Rev. 2, dated May 5, 1994, FAA approved July 8, 1994or later revisions of the above listed documents approved by EASA inaccord...	None	21/12/2012	Active	10042851
10042854	AVIATION ENGINEERING AS			AS365 N1, N2, N3	Modification of Helidyne DPL Litter P/N HD365-15-1036 Approved under STCLFVS 21E2.003 (Sweden). Rebuilding of the Helidyne DPL Litter tofacilitate Aerolite Platform P/N 007-0002633-501 (EMS Patient Platform).	The Certification Basis for the original product remains applicable tothis certificate/ approval.	2524-03-320 dated 25 April 2012 - Certification Plan2524-03-322 Design Change Report	STC EASA.R.S.01072 to be installed	20/12/2012	Active	10042854
10042855	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		228-200/-201/-202/-212	Installation of GARMIN GTN750 / GTN650 and Sandel SN4500 EHSI	The Certification Basis of the original product and the followingadditional / airworthiness requirements are applicableto this change.Compliance to CS 23 Amdt.3 has been shown for all the paragraphsaffected by this change, except for the following paragraphs, for whichcompliance was shown with FARA...	-Engineering Order and Certification Program, Doc. No. 2077918-EO, Issue1, dated 17-Dec-2012-Airplane Flight Manual Supplement, Doc. No. 2077918-AM A, Issue 2,dated 20-Dec-2012, for Garmin GTN 750 and GTN 650-Airplane Flight Manual Supplement, Doc. No. 2077918-AM B, Issue 1,dated 19-Nov-2012, for Du...	- This change is limited to the configuration of aircraft and equipmentas defined in the Engineering Order, Doc. No. 2077918-EO, Section 4- LNAV/ VNAV or LPV is not permittedIf theholder agrees to permit another person to use this certificate toalter the product, the holder shall give the other pers...	28/10/2013	Active	10042855
10042873	CESSNA ZURICH CITATION SERVICE CENTGMBH			B300, B300C B200, B200C, B200GT, B200CGT	BARO-VNAV Temp. Comp. Activation & RF Legs AuthorizationActivation of Temperature Compensation on already approved APV BARO-VNAVsystem andRF Legs Authorization (This functionalitycan be used in the initial andintermediate approach segments, the final phase of the missed approach,SIDs and STARs)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/or emissions levels of the original productare unchangedand remain applicable to this certificate/approval.	Master Document List MDL-101 Rev. BAFM Supplement:Barometric Temperature Compensation/Correction FMS-101-1 Rev. IRAFM Supplement:Authorization for Radius to Fix Legs (RF-Legs) FMS-101-2 Rev. IRor later revisions of the above listed documents approved by EASA	S/N: same as EASA TCDS with Rockwell Collins Proline 21 Avionics	21/12/2012	Active	10042873
10042880	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		B200, B200C, B200GT, B200CGT	Installation of Flight Management System Universal UNS-1Lw	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 2 (not required by 21A.201)The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original prod...	Flight Manual Supplement ASR-2012-057-FMS-05-00 Rev. 00or later revisions of the above listed documents approved by EASA.Instructions for Installation ASR-2012-057-IFI-10-00 Rev. 00Instructions for Continued Airworthiness ASR-2012-057-ICA-11-01 (Rev.01) dated 17th March 2017	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10042880

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042902	COMPAGNIA GENERALE RIPRESEAEREES .p.A. - CGR S.p.A.			402C	CGR-P005-00 "Installation of an aerial survey camera kit type UltraCamXp for Aerial Work Survey"	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Report Change CGR-P-005-00 Issue 0 dated 6 August 2010, including FlightManual Supplement "Change CGR-P005-00 Issue 0" Rev.0or later revisions of the above listed documents approved by EASA	Registration Marks EC-DKP	02/01/2013	Active	10042902
10042908	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)	REV. 1		L35A, L36A	Multiple Antenna Installation Provision Lear 35A/ 36AAntennas are installed at the following location:1. UHF antennas at the bottom fuselage:between FR 13 and 13E-As option A: antenna located between FR 13B and 13A center fuselage.-As option B: antenna located between FR 13C and 13D center fuselage....	FAR 25The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificatednoise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	ICA Instruction for continued airworthiness Document No. 5223-085revision IRor later revisions of the above listed documents approved by EASA	None	07/01/2013	Active	10042908
10042919	ARMSTRONG AEROSPACE Inc.	REV. 1	FAA STC ST02946CH	737-900ER 737-900 737-800 737-700 737-600	Certification of Compatibility with Cellular and Wireless DataTechnologiesRevision 1: B737-900ER applicability added. List of technicaldocumentation and limitations updated.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 at amendment 2:25.1309(a), 25.1529The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product ar...	- Master Data List, Reference DC104-9047-00, Revision G, dated April 29,2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Ag...	1) For Group 1 aircraft, a wifi and cellular systems do need to beinstalled concurrently, but the limitation implies that they need to beinstalled in the same "base station". Theinstalled systems usuallyhave a pico cell installed and multiple wireless access points.2) Group 3 is for systems who on...	08/08/2014	Active	10042919
10042953 (EASA.IM.A.S.01135)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02995-AT	727 SERIES	Installation of a Honeywell Mark VII Enhanced Ground Proximity WarningSystem (EGPWS).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. EMTEQ Engineering Master Drawing List Doc No 2-26236-001Rev A, datedNovember 20, 2004.2. FAA approved Flight ManualSupplement for Boeing 727 Series Aircraft,EMTEQ Doc. No. 2-26236-902 Rev JR<(>,<) > dated December 02<(>,<) > 2004<(>,<)>or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10042953
10042956 (EASA.IM.A.S.01162)	STG AEROSPACE Inc.AKA SAFTGLO, Inc.	REV. 1	FAA STC ST02292AT	A321-212 / -213 / -231 / -232 A321-111 / -112 / -131 / -211 A320-231 / -232 / -233 A320-214 / -215 / -216 A320-111 / -211 / -212 A319-115 / -131 / -132 / -133 A319-111 / -112 / -113 / -114 A318-111 / -112 / -121 / -122	Installation of SafTGlo photoluminescent floor proximity emergencyescape path marking system (FPEEPMS) - Validation of FAA STC N ST02292AT	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC ST02292AT, amended May 25, 2011Certification Plan 0713186000, Rev. A, dated March 16, 2011Master Drawing List L67-2, Rev. L, dated October 18, 2011Instructions for Continued Airworthiness L67-10, Rev. G, dated November18, 2010EWIS ICA 0713186001, Rev. IR, dated November 22, 2010Airplane Flig...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/06/2013	Active	10042956
10042960 (EASA.A.S.00733)	AIR AMBULANCE TECHNOLOGY GmbH	REV. 2		CL-600 ALL MODELS CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Installation of Air Ambulance EquipmentRevision 1: This revision adds four additional cabin configurations tothe STC and updates the STC document package to an updated Air AmbulanceTechnology format also considering the requirements of EASA SpecialCondition D-01Revision 2: Editorial correction to cl...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): For configuration CL600-25-20-21.000-600 only:D-01 Medical Evacuation Configuration.The requirements for environmental protection andc...	Configuration P/N CL-25-20-21.000-500: - Component-, Installation-, Operation-Manual, illustrated PartCatalog Air Ambulance Equipment CHALLENGER 600 "quick conversion" P/N CL-25-20-21.000,CMM-CL-AAT30, CMM-CL-AAT31 - AirplaneFlight Manual CHALLENGER Supplement Air Ambulance "quickconv...	Configuration P/N CL-25-20-21.000-500 is applicable only for models:CL-600-1A11 (600), CL-600-2A12 (601 Variant), CL-600-2B16 (601-3AVariant), CL-600-2B16 (601-3R Variant) Configuration P/N CL600-25-20-21.000-600 is applicable only for model:CL-600-2B16 (604 Variant).Prior to installation of this cha...	30/07/2024	Active	10042960

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042964 (EASA.R.S.00467)	AIR AMBULANCE TECHNOLOGY GmbH	REV. 3		SA 365 N, AS 365 N2 SA 365 N1, AS 365 N3 EC 155 B, EC 155 B1	Installation of Air Ambulance Equipment, VIP Interior, MissionEquipment.Revision 2: - introduces explicit references to the helicopter models forwhich this STC is applicable. - corrects minor typos.Revision 3: - correction of typo in Associated Technical Documentation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplements: - Air Ambulance Equipment "quick conversion" P/N 365-25-24-2000-500FMS 10AAT7 Rev. 1; - Air Ambulance Equipment "quick conversion" P/N 365-25-24-2000-511FMS 10AAT11 rev. 1; - Mission Equipment "quick conversion" P/N 155-25-24-2000-700 modelFMS 10AAT27 Rev. 4; - Mou...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/06/2018	Active	10042964
10042965 (EASA.R.S.00468)	AIR AMBULANCE TECHNOLOGY GmbH	REV. 9		MBB-BK117 D-3M MBB-BK117 D-2, MBB-BK117 D-3 MBB-BK 117 D-2 MBB-BK 117 C-2 MBB-BK117 B-2, MBB-BK117 C-2 MBB-BK 117 B-2	Installation of EMS interior and VIP interior called by AATas “QuickConversion” kits.Revision 8 and 9: To correct typoin Continuation Sheet document.Revision 7: To correct the approval applicability and documentsreferences. This revisionalso includes conditions for the STCapplicability.Revision 6...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Rev 6 to Rev. 9 of this STC:- Declaration of compliance DoC-D-3(m) extension of BK117 D-2(m) STC(VIP)-501-1Rev.0 dated 17.12.2021- Master Data list-MDL-D3(m) extension of BK117-D2(m) STC (VIP)-501-1Rev.0 dated 15.12.2021Further documents toidentify applicability with regards to rotorcraftmodels areR...	The EMS interior installation kit is applicable to MBB-BK117 B-2 andMBB-BK117 C-2 models.The VIP interior installation kit is applicable to MBB-BK117 C-2,MBB-BK117 D-2, MBB-BK117 D-3 andMBB-BK117 D-3m models and MBB-BK117 D-2m variant.Prior to installation of this design change it must be determined...	20/01/2022	Active	10042965
10042970	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 2	FAA STC ST01612CH	CL-600-2B19 CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Air Ambulance ConversionReason for rev. 2: Change of ownership from Snaky Creek Enterprises, LLCto Spectrum Aeromed, LLC d/b/a Spectrum Aeromed.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Spectrum Aeromed Inc< (>,<)> Master Drawing List 6041DL, Revision 7,dated 20 August 2012, or later FAA approved revision.- Spectrum Aeromed Inc. Flight Manual Supplement 6041 FMS, Revision 7dated 16 October 2012, or later FAA approved revision.- Spectrum Aeromed Inc. Instructions for Continued Airw...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/04/2019	Active	10042970
10042981 (EASA.IM.A.S.01751)	PATS AIRCRAFT L.L.C.	REV. 2	FAA ST00936NY-D	B737-700 737-700 IGW	Installation of Auxiliary Fuel SystemsRev 2: Added reference to MMEL Supplement	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Configuration 1-A: Installation of structural provisionsonly, for aThree (3) Auxiliary Fuel System in the aft cargocompartment inaccordance with PATS, Inc., Master Drawing List No. BBJ0003, Rev. G,dated 17 February 1999 or later FAA approved revision.2. Configuration 1-B: Installation of struct...	Configurations 1-A, 1-B, 1-C, 1-D, 1-E, 1-F, 1-G, and 1-H: - These installations are life limited to five hundred aircraftcycles. - No liquids, semi liquids or solids may be loaded in the tanks atany time.All Configurations: - The aircraft must be inspected in accordance with requirement...	13/04/2021	Active	10042981
10042987 (EASA.IM.A.S.01964)	MTI POLYFAB Inc.	REV. 1	TCCA STC SA05-68	BD700-1A10, BD700-1A11	Thermal Acoustic Insulation Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA05-68 Issue 3 dated 10 May 2007MTI-Polyfab Inc. Modification Summaries as listed below or laterapproved revisions.Model,,,,,,Modification Summary No.,,,,Revision No.BD-700-1A10,,,,MS01010607,,,,,,,,,,NC,,BD-700-1a11,,,,MS03052005,,,,,,,,,NC,,MTI-Polyfab Inc. Aircraft Main...	None	01/10/2013	Active	10042987

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10042992 (EASA.A.S.0080)	ACC COLUMBIA Jet Service GmbH	REV. 2		DR 400 RP	Installation of engine Lycoming O-540 A4D5 or O-540 J3A5	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	-"Flughandbuch DR 400 RP mit Motor O-540 A4D5/ J3A5, Ausgabe08.04.2002"-"Anhang zum Flughandbuch DR 400 RP, S/N 1766 mit Motor O-540 J3A5",Doc. No. SPOH_08834_rev0_20121201.docor later revisions of the above listed documents approved by EASA-Modification Instruction: "Umrüstanweisung zur Umrüstung D...	None	26/01/2022	Active	10042992
10042994	DART AEROSPACE Ltd.		TCCA STC SH 96-10 REV. 3	AS355 E/F/F1/F2/N/NP	Emergency Litter InstallationsInstallation of an Emergency Litter Kit as defined in Dart AerospaceLtd. Master Document List MDL-D350-616.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 27 including amendments 27-1 through 27-20, 27.807, 27.1585 and27.1587 at amendment 27-21The requirements for environmental protection and the associatedcertified nois...	Flight Manual Supplement FMS-D350-616 revision Bor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.-Installation Instructions IIN-D350-616 Rev. D-Instructions for Continued Airworthiness ICA-D35...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	03/07/2013	Active	10042994
10042996 (EASA.P.S.00580)	THIELERT AIRCRAFT ENGINES GmbH	REV. 1		MTV-6-A	Installation of a Constant Speed Unit CSU TAE-125Revision 1follows a change of ownership.		Manual for Installation and Operation Instruction - Constant Speed UnitCSU TAE-125, 02-6120-16001RX (X=Version No.), Issue 2, Revision 0 dated27 April 2004	1. The CSU is limited to the case when the Propeller is driven by a TAE125 engine.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by...	19/08/2013	Active	10042996
10042997	TECH-TOOL PLASTICS, Inc.		FAA STC SR09000RC	AS350B/BA/B1/B2/B3	Installation of miscellaneous windows in accordance with Tech-ToolPlastics, Inc. MDL 3501-2000-1.This STC is the re-issuance of LBA-Germany STC RC 1108 issued on 27September 1999.		MDL No. 3501-2000-1, Rev. A, dated 21/08/1998	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/07/2013	Active	10042997
10042998	TECH-TOOL PLASTICS, Inc.		FAA STC SR09003RC	AS 355 E/F/F1/F2/N	Installation of miscellaneous windows in accordance with Tech-ToolPlastics, Inc. MDL 3501-2000-1.This STC is the re-issuance of LBA-Germany STC RC 1117 issued on 27September 1999.		MDL No. 3501-2000-1, Rev. A, dated 21/08/1998	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/07/2013	Active	10042998
10042999	TECH-TOOL PLASTICS, Inc.		FAA STC SH8967SW	AS355E/F/F1/F2/N	Installation of aft Cabin Comfort Windows in accordance with Tech-ToolPlastics, Inc. MDL 3501CC-2032-100.This STC is the re-issuance of LBA-Germany STC RC 1113 issued on 27September 1999.		MDL No. 3501CC-2032-100, Rev. I.R., dated 15/07/1994	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/07/2013	Active	10042999

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043000	TECH-TOOL PLASTICS, Inc.		FAA STC SH8966SW	AS350B/BA/B1/B2/B3	Installation of aft Cabin Comfort Windows in accordance with Tech-ToolPlastics, Inc. MDL 3501CC-2032-100.This STC is the re-issuance of LBA-Germany STC RC 1099 issued on 27September 1999.		-MDL No. 3501CC-2032-100, Rev. I/R dated 15/07/1994-Tech-Tool Plastics, Inc. Installation Instructions for Part Number3501CC-2032-3, -4, -6 Aft Sliding Cabin Comfort Windows, Report TTP-IRev. I/R - 07/11/94	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/07/2013	Active	10043000
10043003 (2004-2305)	PMV ENGINEERING	REV. 14		ATR 72-212A ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202	ATR72 Cargo Conversion – Large Cargo Door (LCD)This STC converts ATR72 main cabin into a cargo compartment and modifiesthe fuselage structure to include a large cargo door (LCD).Rev. 1 retains the certificated design of the ENAC STC No. CS-074 andcapture the owner companyname change (from Alenia Aer...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: As per CRI A-01 Issue 7dated 14 Dec 2022The requirements for environmental protection and the associatedcerti...	-Type Design Definition 54/NT/0000/N316c/020154, Issue 4, 04/03/2004referencing Master Drawing List 54/DC/0000/N310c/020121, Issue B,14/06/2002- Master Drawing Lists 54/DC/0000/N310C/040009 Issue 1, dated 29 March2004-Data List ASI-SDL-0356-01 dated 12/2016- AFM Supplement P2F-00090-AFMS-S01 Rev 02-...	This STC is identical to FAA STC ST01761NY configuration B when inaccordance with Type Design Definition 54/DO/OO00/N316C/040097Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repa...	16/06/2023	Active	10043003
10043004 (EASA 2004-5062/ENAC CS-095)	LEONARDO S.p.A.	REV. 2		ATR 42-400, ATR 42-500	ATR 42 – Airborne Thematic Mapper for ATR 42MP (Multi-Purpose)This STC installs on ATR 42-400 and -500 MP (multi-purpose: see ENAC STCNo. CS-094) an ATM system (Airborne Thematic Mapper).The Revision 2 retains the certificated design of the ENAC STC No.CS-095 and capture the owner company name chang...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: JAR 25 Change 15 for:- 25X20, 25.21- from 25.301 to 25.581 except 25.373, 25.445, 25.477, 25.497- from 25.601 to 25.629 ex...	- Type Design Definition Dossier No. 8766 Issue 3 dated 26 January 2004.- Type Design Definition Dossier No. 8769 Issue2 dated 26 January 2004.- ATR 42-400MP /-500MP with ATM installed Mandatory AirworthinessLimitations Supplement, ref: No. 53/NT/0000/N316C/040073 Issue 1, dated16 April 2004;or lat...	This STC can be installed only on aircraft already modifiedby ENAC STCNo. CS-094.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon...	30/03/2017	Active	10043004
10043005	PMV ENGINEERING	REV. 5		ATR 42-300, ATR 42-320	ATR 42 Cargo conversion - Large cargo door (LCD).This STC converts ATR 42-300 /-320 models main cabin into a cargocompartment and modifies the fuselage structure to include a large cargodoor.The Revision 1 retains the certificated design of the ENAC STC No.CS-086 and capture the owner company name c...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: as perENAC CRI-A01 issue 2 dated May 2002:JAR 25 Change 15 for: 25.1, 25.2, 25.23, 25.25, 25.27, 25.31, 25.301,25.303, 25.305, 25.307, 25.365, 25.561, 25.571, 25.581, 25....	ATR 42 Large Cargo Door Supplemental Type Design Definition, ref: No.54/NT/0000/N316c/020412 Issue 2, dated 14 March 2003ATR 42 LCD Master Drawing List, ref: No. 54/DC/0000/N310c/020326 Issue3, dated 25 September 2003ATR 42-300 /-320 CARGOLCD AFM Supplement, Normal Revision 00, datedMarch 2003ATR 4...	The installation of this modification by third persons is subject towritten permission of the approval holder.This STC is identical to FAA STC ST01761NY configuration A when inaccordance with Type Design Definition 54/DO/0000/N316C/030189.Prior to installation of this design change it must be determ...	27/03/2019	Active	10043005
10043006 (EASA 2004-5061/ENAC CS-094)	LEONARDO S.p.A.	REV. 2		ATR 42-400, ATR 42-500	ATR 42 – Multi-PurposeThis STC modifies ATR 42-400 and -500models to obtain a “multi-purpose”(MP) model enabling passenger transportation, cargo transportation andmaritime patrol.The Revision 2 retains the certificated design of the ENAC STC No.CS-094 and capture the owner company name change (from...	The Certification Basis for the original product as amendedper ENAC-RAICRI A-01 for ATR42-400/-500 MP, issue 6, dated March 2004.The requirements for environmental protection andthe associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to thi...	- ATR 42 Multi-Purpose Supplemental Type Design Definition,ref: No.53/DO/0000/N316c/030165 Issue 1, dated 27 April 2004.- ATR 42 Multi-Purpose Master Drawing List, ref: 53/DC/0000/N310c/040138Issue 1, dated 27 April 2004.- ATR 42-400 /-500 AFM Supplement, Normal Revision 03, dated March2004.ATR 42...	1- Type Design Definition document referred in the Associated TechnicalDocumentation section lists the ATR modifications which must be embodiedon aircraft to allow for MP conversion.2- This STC supersedes ENAC COTS CS-033, dated 15 October1999.Prior to installation of this design change it must bet...	30/03/2017	Active	10043006
10043008	GULFSTREAM AEROSPACE Corp.		FAA STC TC10047SC-D	GULFSTREAM 200 GALAXY	Installation of Tail mounted AVS Camera System		-FAA STC TC10045SC-D-Index List GA215058000, Rev. C, dated 12/07/04, or later FAA approvedrevision-FAA approved Flight Manual Supplement GA21505M000, Rev. "None" or laterFAA approved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.	09/02/2005	Active	10043008

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043009	GULFSTREAM AEROSPACE Corp.		FAA STC ST09749SC	GULFSTREAM 200 GALAZY	Installation of a jumpseat in the forward L/H radio rack		-FAA STC ST09749SC-STC Data List 30-1100006, Revision C, dated April 18, 2000 or later FAAapproved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.	09/02/2005	Active	10043009
10043019 (EASA.IM.A.S.00753)	S-TEC CORPORATION	REV. 1	FAA SA8903SW-D	3. BN-2B-20, BN-2B-26, BN-2T 3. BN-2A-8, BN-2A-20, BN-2A-26 2. BN-2A-6 1. BN-2A-2	Installation of S-TEC System 55/55X Two-Axis Automatic Flight GuidanceSystem Model ST-572	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List (MDL) No. 92744, Rev. F, dated July 3, 2013AFM Supplements:a) FAA approved Supplement to CAA or FAAapproved AFM for Britten NormanModels BN-2A-2, BN-2A-8, BN-2A-20, BN-2A-26, BN-2B-20, and BN-2B-26: P/N891140, dated January 31, 1995 (Optional: P/N EASA891140, EASA approvedMay 3,...	1. Only applicable to Model BN-2A-6 when modification NB/M/430 andNB/M/631 are installed.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined3...	19/12/2013	Active	10043019
10043023 (FOCA STC MOD 03-126-HAH)	AIR-GLACIERS S.A.			SA 315B	Installation of external mirrorThis installation was previously approved by FOCA for specific SA 315BS/N under FOCA Major Change MOD 03-126-hah.This minor change extends the installation to SA 315B S/N 2522 and S/N2486.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 27 Amdt. 40The certificated noise and/ or emissions levels of the original productare unchanged and remainapplicable to this certificate/ approval.	Work Order Nr. 559 dated 7.10.2003Manuel de vol supplément no. 20 dated 7.10.2003or later revisions of the above listeddocuments approved by EASA.	S/N: 2522, 2486Only already existing parts manufactured andapproved under FOCA MOD03-126-hah can be installed. No new part can be produced under this EASAapproval.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprev...	23/01/2014	Active	10043023
10043025	LUFTHANSA TECHNIK AG			757-200	Installation of a Zonal Drying System P/N B757-02-2 designed andmanufactured by CTT Systems (Sweden)				26/01/2005	Active	10043025
10043027	MADELEC AERO S.A.S.	REV. 2	DGAC-F STC IM.208-SF-002	CL-600-2B19	Replacement of existing Floor Proximity Emergency Exit PathMarking(FPEEPM); Add new MSN in the frame of Madelec Aero STC for Air NostrumCompany.Rev. 1 adds MSN 7200 to EASA STC No. 10043027.Rev. 2 stats the complete applicability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Madelec Aero Certification Documentation List No. CDL-9909 Issue 6 dated19 June 2017.	Applicable to MSNs 7003, 7020, 7053, 7057, 7081, 7084, 7126, 7144, 7164,7177, 7182, 7183, 7184, 7197, 7200, 7223, 7249,7252, 7309, 7316, 7320,7323, 7332, 7343, 7350, 7430, 7466, 7493, 7514, 7529, 7547, 7563, 7591,7622, 7661, 7700, 7705, 7706, 7732, 7746, 7785, 7851, 7866 and 7915.Prior to installat...	06/07/2017	Active	10043027
10043028	HARTZELL PROPELLER LLC		FAA SA00773AT	T210H, T210J, T210K, T210L 210L, 210M, 210N, T210F,T210G, 210F, 210G, 210H, 210J, 210K,	Installation of a Hartzell PHC-J3YF-1RF/F7691( ) Model Propeller andC-4582-(P) Spinner.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Hartzell Propeller Inc. Installation Instructions HP1012P, Rev. B, datedJune 15, 2008Airplane Flight Manual Supplements:a. For Cessna model 210K with S/Ns 21059200 thru 21059502 and 210L withS/Ns 21059503 thru 21061039: Supplemental Airplane Flight Manual, datedMay 17, 1995;b. For Cessna model 210LS...	1. Compatibility of this design change with previously approvedmodifications must be determined by the installer.2. This approval is limited to Cessna 210F - 210N, and T210F - T210Lwith Teledyne Continental IO-520-A, -J, -L, or TSIO-520-C,or -H modelengines only.3. If the holder agrees to permit an...	28/03/2014	Active	10043028
10043029 (2004-5729)	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	B200 AND 200	Installation of a PAS Incubator Part No. A0/388-500-().	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Definition Document: Gama Support Services Ltd Substantiation ReportNo. GAMA/GSS/SR 04-001 or later revisions of the above listed documentsapproved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/05/2014	Active	10043029

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043032 (EASA.R.S.00261)	AEROLITE AG	REV. 7		EC135 T3 EC135 T1, EC135 T2, EC135 T2+ EC135 P1, EC135 P2, EC135 P2+	Emergency Medical Service (EMS) Cabin ConfigurationInitial issue as EASA.R.S. 00261Installation of EMS equipment P/N 135520-501 or 135520-502 in accordancewith Master Drawing List DWL-303 dated 16 September 2004 or laterEASA-approved revision.Revision 1 as EASA.R.S.00261 rev 1Introduction of: EMS Equ...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Document List MDL-303 Revision URotorcraft Flight Manual Supplements:- For EMS Equipment P/N 135520-501: FMS-303 Revision F- For EMS Equipment P/N 135520-502: FMS-408 Revision N- For EMS Equipment P/N 135520-503: FMS-501 Revision F- For EMS Equipment P/N 135520-504: FMS-135520-504 RevisionI...	- EMS Equipment P/N 135520-501 is eligible for installationon all EC135models up to and including S/N 336- EMS Equipment P/N 135520-502 is eligible for installation on all EC135models from S/N 337- EMS Equipment P/N 135520-503 is eligiblefor installation on all EC135models up to and including S/N-...	30/06/2023	Active	10043032
10043038 (EASA.R.S.01241)	AEROLITE AG	REV. 2		MBB-BK 117 C-2	Installation of a dedicated EMS equipment P/N 145121-50-502.This STC revision is issued for the purpose of transferringthe STC toAerolite AG.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approvalThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS-506, Rev. C, dated 07.09.2006or later revisions of the above listed documents approved by EASA.Operation Manual OPM-506, Rev. C or later for p/n 145121-501Operation Manual OPM-06-011, Rev. n/c or later for p/n 145121-502.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/03/2016	Active	10043038
10043039 (EASA.R.S.01093)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		A109E	Installation of an image capture system (ARGUS 275 Camera) byadaptations of the previous installation of a SX-16 searchlight &transmission system.Rev. 1: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- CMA015-AFMS Supplement for an Image Capture System (Argus275) andTransmission System-CMA015-BI Engineering Bulletin- CMA015-MID Installation/Maintenance Manualor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The installation of the supporting structure (P/N 109-0709-21-101 andP/N 109-0709-24-101) and reinforcements (P/N 109-0709-66-101, P/ N1090709-23-109, P/N 109-0709-23-113, and P/N 109-0858-65-113) related tothe Agusta optional equipment searchlight SX-16 is necessary for theinstallationof this system...	01/02/2019	Active	10043039
10043046 (EASA.IM.R.S.01455)	VIH AEROSPACE Inc.	REV. 2	TCCA SH08-10 ISSUE 7	S-92A	Passenger Seating Configurations.Rev. 1: Re-issuance of EASA STC No. EASA.IM.R.S.01455 with additionalinterior layouts per TCCA STC SH08-10 Issue 6.Rev. 2: Revised to include the new floorplan layouts No. SD 2 thru SD 4per TCCA STC SH08-10Issue 7.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	VS92-371-PLN-MDL Revision N/R – Master Document List;- for Seating Configuration No. 1 to 18:VS92-371-PLN Revision 6 – Installation drawingVS92-371-PLN-FMS Revision 7 dated Oct 29, 2019 – Flight ManualSupplement- for Seating Configuration No. SD 1 to SD 4:VS92-2234A-PLN Revision A – Installation dra...	Prior installation of- Auxiliary Fuel Tank Installation (approved under EASA STC 10029820);- SAR Console and operator'sseat (approved under EASA STC 10052427);- Triple Litter Stacker Installation (approved under EASA STC 10030509);- GKN Sliding Entry Door Installation (approved under EASA STCEASA.I...	10/01/2025	Active	10043046
10043054 (EASA.A.S.00612)	DOA AESGLOBAL LIMITED	REV. 2		767-300	Installation of Enhanced Ground Proximity Warning system (EGPWS).Rev. 1: FAR Part 26 Validation for the EASA STC EASA.A.S.00612.Rev. 2: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AES-767-346 Issue 1-AFM Supplement No 4 Issue 1;- AES Ltd. Master Data List No. AES-767-346MDL Issue 5 dated 30 October2012;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	27/04/2021	Active	10043054

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043060 (EASA.IM.A.S.03094)	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA00560CH	PA-31T2, PA-31T3, PA-31P-350 PA-31P, PA-31T, PA-31T1,	Air Ambulance Conversion.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation must be in accordance with Master Drawing List 2003DLRev.1, dated 2 April 2008 or later approved revisions.- Operation must be in accordance with Aircraft Flight Manual Supplement2003FMS Rev. 1<(>,<)> or later approved revision.- Maintenance must be in accordance with Instruction for C...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/04/2019	Active	10043060
10043062 (EASA.IM.A.S.02965)	ROSEMOUNT AEROSPACE, Inc.	REV. 2	FAA STC ST02667CH	A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322/ A330-243/-243F/ A330-201/-202/-203/-223/-223F/	Installation of Rosemount Aerospace 8700C2-2 Laptop DockingStation - Electronic Flight Bag (EFB) System provisions.Thismodification installs the electrical and mechanical provisions forEFB class II connection.The Revision 2 deals with thechange of the docking station power supplysource.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissionslevels of the original product are unchanged and remain applicable tothis certificate/approval	Rosemount Aerospace Master Data List, ref : D06402672 Revision T, dated13 March 2014Aircraft Flight Manual Supplements :-Document ref : D06402689 revision C (Configuration A before ServiceBulletin 8700C2-46-01 embodiment).-Document ref : D06403259 revision C (Configuration B before ServiceBulletin 8...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/11/2014	Active	10043062
10043064 (EASA.IM.A.S.02495)	GDC TECHNICS, LLC.	REV. 1	FAA STC ST10831SC	A320-214	Installation of an Executive Interior on Airbus A320-214 MSN 3199Revision due to removal of EWIS limitation and editorial correction onprevious approval	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirementsSpecial Condition (s):CRI H-01 "Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS"The requirements for environmental protection and the associatedcertified...	-FAA STC ST10831SC, amended on 29th January 2014-Gore Design Certification Drawing List, GCD-429-03, Rev. K, dated 3rdSeptember 2008-Gore Design Substantiation Report List, GCD-429-04, Rev. C, dated 27thJanuary 2014-Instruction for Continued Airworthiness, ref. No. GCD-429-05, Rev. G,dated 25th June...	This STC is limited to MSN 3199.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The installation...	25/02/2014	Active	10043064
10043068 (EASA.IM.A.S.03207)	THUNDER BAY AVIATION Ltd.	REV. 1	TCCA SA05-30	DHC-6-300 DHC-6-100, DHC-6-200,	Installation, Substitute Composite Floor Panels.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation to be completed as per Aero Consulting ServicesModification Data Summary E061000, Rev. E, January 2008, orlaterTransport Canada approved revision.Instructions for continuing airworthiness as per Aero ConsultingServices ReportE061071, Rev. B, November 2007, or later TransportCanada app...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/05/2015	Active	10043068
10043074 (EASA.IM.A.S.03133)	ACS-NAI Ltd.	REV. 1	TCCA STC C-LSA09-029/D, ISS.2	CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-029/D Issue 2 dated 17 June 2013.AeroConsulting Services Ltd. Modification Data Summary G118000 RevisionD.Midcoast Aviation Inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior Installation, 33-299M007 Rev NC.Aero Consulting Services Ltd. Mandatory M...	Restricted to ASN 8087.	16/08/2013	Active	10043074

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043075 (EASA.IM.A.S.03132)	ACS-NAI Ltd.	REV. 1	TCCA STC C-LSA09-027/D, ISS. 2	CL-600-2B19	Installation, Complete Custom Aircraft Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA LSTC No. C-LSA09-027/D Issue 2 dated 17 June 2013.AeroConsulting Services Ltd. Modification Data Summary G117000 RevisionH.Midcoast Aviation Inc. Airplane Flight Manual Supplement for theComplete Custom Aircraft Interior Installation, 33-299M009 Rev NC.Aero Consulting Services Ltd. Mandatory M...	Restricted to ASN 8084.	16/08/2013	Active	10043075
10043076 (EASA.IM.A.S.03116)	AVMAX AVIATION SERVICES Inc.	REV. 1	TCCA STC SA08-82	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103 DHC-8-102,-103,-106	Replacement of the existing Honeywell AH-600 Attitude and HeadingReference System (AHRS) with the installation of a SFIM Industries F227Aircraft Piloting Inertial Reference Sensor (APIRS).Revision 1: Addition of DHC-8-200 and DHC-8-300 models	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: FAR 25.29, 25.301,25.303, 25.305, 25.307, 25.471, 25.561, 25.571, 25.601, 25.603, 25.605,25.607, 25.609, 25.6...	The change is defined with Issue 15 of Avmax Aviation Services Inc. TopDocument List document 117334-400.Installation:In accordance with Avmax Aviation Services Inc Engineering Order117334-401, Issue 10Operation:In accordance with Avmax Aviation Services Inc Flight Manual Supplement117334-801, Issue...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/09/2025	Active	10043076
10043079 (EASA.IM.A.S.02885)	LAKE CENTRAL AIR SERVICES	REV. 1	TCCA STC SA06-47	208, 208B	Installation of externally mounted survey equipmenta) Tail mounted survey boom & optional video camera<(>,<)>b) Wingtipmounted pods<(>,<)>c) Externally mounted survey belly pod.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Flight Manual Supplements:a) - c): CF-LCA-045or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/CanadaBilateral Agreement.Master Drawing Lists:a) LCA00303, Rev.5; b) LCA00317, Rev. 3; c) LCA00331, Rev. 1Type Specific Par...	1. Eligibility of specific items of externally mounted survey equipmentmust be in accordance with latest TCCA approved Eligibility ListLCA-SFW-1.2. This STC approves only the structural installation of the deactivatedsystem components. Separate approval is required for the activation ofelectrical an...	20/08/2014	Active	10043079
10043106 (EASA.A.S.02493)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		CESSNA 414A 414A	Extension of the existing EASA STC EASA.A.S.02493:Installation of MTV-14-D-C-F/CF188-30( ) Propeller on Cessna 414A.Installation of MTV-14-D-C-F/ CF188-30( ) Propeller on Cessna 414Amodified by FAA STC SA4546SW (RAM 4).Installation of MTV-14-D-C-F/ CF188-30( ) Propeller on Cessna 414Amodified byFAA ST...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31.This certificate/ approval involves a change with an impact on the noisedatab...	According to MT-Propeller Master Documentation List No. E-1757 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-1758Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-1759 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-1760 Rev. 0or later...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	07/11/2023	Active	10043106
10043115 (EASA.A.S.02769)	ROEDER PRAEZISION GMBH	REV. 1		737-800/-900 737-400/-500/-600/-700 737-100/-200/-200C/-300	737-DMD34-0 1-2006: Activation of Enhanced Surveillance Parameter.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Design Modification Document 737-DMD34-01-2006 Rev IR dated. 27.11.2006;-AFM supplement 737-AFM34-01-2006 Rev. IR dated. 27.11.2006;or later revision(s) of the above listed documents approved by EASA.	- Compliance to NP A 20-12a was shown.- Applicable to 737 models as per Design Modification Document737-DMD34-0 1-2006.- This STC is approved only for the product configuration asdefined inthe approved design data referred to in the paragraphs "Description" and"Associated Technical Documentation".C...	15/06/2018	Active	10043115

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043118 (EASA.A.S.01322)	ALAMO ENGINEERING GmbH	REV. 3		CN-235-100	Installation of a Ground Proximity Warning System (GPWS) & TerrainAwareness Warning System (TAWS).Rev. 3: transfers theSTC from "Deutsche Aircraft GmbH" to "AlamoEngineering GmbH".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25, Initial Issue: 25.1, 25.301, 25.303, 25.305, 25.307, 25.365,25.561, 25.603, 25.605, 25.607, 25.609, 25.625, 25.1301, 25.1309,25.1321, 25.1322, 25.1333, 25.1351, 25....	Avionics Mobile Services Definition Document PART21-002/1504-01, Issue1, dated September 9, 2005 or later approved revision.Avionics Mobile Services AFM Supplement PART21-008-012,Revision 1 orlater approved revision.	1. Aircraft Registrations A40-CU and A40-CV.2. This STC is approved only for the product configuration as defined intheapproved design data referred to in the paragraph "Description".Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repa...	20/11/2024	Active	10043118
10043123	S-TEC CORPORATION		FAA STC NO. SA5229SW-D	185D, 185E, A185E, A185F 185, 185A, 185B, 185C	Installation of S-TEC System 40/50 Single and Two Axis Automatic FlightGuidance System, Model ST-196-40/50.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CAR Part 3	Bulletin No. 296, dated 8-19-83 or approved revision.MasterDrawing List No. 92232, dated 8-19-83, or later approved revision (14 Volt System)FAA/DAS Approved Pilot's Operating Handbook and / or Airplane FlightManual Supplemental, P/N 89304, dated 10-17-83, is required for CessnaModels 185, 185A, 185...	It is the installers responsibility to ensure other STC's referenced bythis STC are EASA Approved.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadv...	17/12/2013	Active	10043123
10043125 (EASA.A.S.0106)	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV. 1	CAA UK RESPONSIBILITY	A321-212 / -213 / -231 / -232 A321-111 / -112 / -131 / -211 A320-231 / -232 / -233 A320-214 / -215 / -216 A320-111 / -211 / -212 A319-115 / -131 / -132 / -133 A319-111 / -112 / -113 / -114	Installation of "SkyCam" Video Monitoring System-,,Introduction of A319 type/ models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 25Amdt 4 for the paragraphs affected by the changeThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origi...	Master Data List J203MDL01 Issue 1, dated 17/12/2013Certification Program J203CP01 Issue 1, dated 22/11/2013Instructions for Continued Airworthiness J203ICA01, Issue 1, dated20/11/2013Compliance Check List J203CCL01 Issue 1, dated 20/11/2013or later revisions of the above listed documents approved b...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/12/2013	Active	10043125
10043128 (EASA.A.S.00455)	PMV ENGINEERING	REV. 13		ATR 72-212, ATR 72-212 A ATR 72-212 A ATR 72-202, ATR 72-212 ATR 72-202	ATR72 "Bulk Freighter Conversion" (BFC): main cabin conversion into aclass E cargo compartment.Rev. 2 retains the certified design of the EASA.A.S.00422 and capturethe STC holder change from AleniaAeronautica to Alenia Aermacchi S.p.a.Rev.3: STC holder change from Alenia Aermacchi S.p.a to IPR Conv...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:As per CRI A-01 Issue 6 dated 7 Sept 2022.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the prod...	- ATR 72 BFC Supplemental Type Design Definition, ref: No.54/NT/0000/N316c/040148 Issue 1<(>,<)>dated 1st December 2004- ATR 72 BFC Master Drawing List, ref: No. 54/DC/0000/N310c/040332 Issue1, dated 21st December 2004- AFM Supplement P2F-00090-AFMS-S02-R01 (Rev 01)- Instructions for Continued Airwo...	As per AFM Supplement P2F-00090-AFMS-S02, Instructions for ContinuedAirworthiness P2F-00090-ICA-S02 and W<(>&<)>B Manual supplementP2F-00090-WBMS-S02.Prior to installation of thischange/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously install...	21/06/2023	Active	10043128
10043137 (2003-2150)	ALAMO ENGINEERING GmbH	REV. 3		JETSTREAM 4100 SERIES	Installation of Honeywell MK VI Enhanced Ground Proximity WarningSystem. STC CAA.21NE2.00044.Rev. 3: transfers the STC from "Deutsche Aircraft GmbH" to "AlamoEngineering GmbH".	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ a...	Avionics Mobile Services Definition Document PART21-002/1419-01, Issue1, dated December 1, 2003.Avionics Mobile Services AFM Supplement PART21-008/1419-01, Issue 1,dated December 31, 2003 or later approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/12/2024	Active	10043137
10043139 (2004-2293)	ALAMO ENGINEERING GmbH	REV. 3		BAE.125 SERIES 800B	Installation of a Honeywell Airborne Collision Avoidance System (ACASII).Revision 1: Transfer to 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	N/A	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10043139

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043140 (2004-5548)	328 SUPPORT SERVICES GmbH	REV. 2		DORNIER 328-100	Installation of a Honeywell MK VI Enhanced Ground ProximityWarningSystem (EGPWS).	The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Definition Document PART21-003/1459-01.		27/09/2018	Active	10043140
10043148 (EASA.IM.A.S.0077)	SAFRAN CABIN INC.	REV. 1	FAA STC ST01409LA	145XR/145EP 145/145ER/145MP/ 145MR/145LR 135ER/135LR/135KE/ 135KL/135BJ	Installation of a reinforced cockpit door.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	C & D Interiors Controlled Drawing List, 7192000, Revision E, dated 25November 2002, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Equipment Functional Check intervals as definedI...	06/04/2018	Active	10043148
10043150 (EASA.IM.A.S.0128)	TELEDYNE CONTROLS, LLC	REV. 4	FAA STC ST01620LA	A321-271N/-272N/-271NX /-272NX A321-253N/-251NX/-252N X/-253NX A321-213/-231/-232/-251N /-252N A321-111/-112/-131/-211/- 212 A320-273N A320-252N/-253N/-271N/- 272N A320-216/-231/-232/-233/- 251N A320-111/-211/-212/-214/- 215 A319-131/-132/-133/-151N /153N A319-131/-132/-133/-151N /-153N A319-111/-112/-113/-114/- 115 A318-111/-112/-121/-122	Installation of Teledyne Controls' Wireless Ground Link Quick AccessRecorder.This STC supersedes EASA.IM.A.S. 0128.Revision 3 : additional Airbus models are added to STC. Revision 4: addsA319-171N, A319-173N, A321-253NY, A321-271NY and removes A320-111.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01620LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Data List No. MDL2243800-32X, revision "-", dated 8 March 2004 orlater FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/11/2025	Active	10043150
10043151 (EASA.A.S.00251)	DOA AESGLOBAL LIMITED	REV. 1		757-200	Aerospace Engineering Solutions Modification AES-757-165 Issue 6Introduction of Enhartced Ground Proximity Warning System (EGPWS)Rev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.		Aerospace Engineering Solutions AES-757-165 Issue ('idated>June 02 2005or later EASAApproved Revision.AES AFM Supplement Number 3 or later approved revision.	This STC is approved only for the product configuration as defined inthe approved design datareferred to in the paragraph "Description". Compatibility with otheraircraft/ engineconfigurations shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orrevok...	28/04/2021	Active	10043151
10043159 (EASA.IM.A.S.0092)	TELEDYNE CONTROLS, LLC	REV. 2	ST01632LA	757-200, 757-200PF, 757-300	Installation of Teledyne Controls Wireless Groundlink - Quick AccessRecorder in accordance with FAA ST01632LA.This STC supersedes EASA.IM.A.S.0092 following a change in theapplicant's address.	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchangedand remain applicable to thiscertificate/ approval.	Master Data List Drawing No MDL2243800-757, revision "-", dated 3 March2004,or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Ag...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/04/2016	Active	10043159

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043160 (EASA.IM.A.S.00194)	TELEDYNE CONTROLS, LLC	REV. 4	FAA STC ST01633LA	A330-343, A330-302/ A330-303 A330-323/A330-341/ A330-342 A330-301/A330-321/ A330-322 A330-223/A330-243/ A330-243F A330-201/A330-202/ A330-203	Installation of Teledyne Controls' Wireless Ground Link Quick AccessRecorder.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List No. MDL2243800-330<(>,<)> Revision "-", dated 3 March2004, or later FAA approved revisions.The Airplane Flight Manual Supplement and Instructions for ContinuedAirworthiness are called out in the respective Master Drawing List MDL2243800-330 Appendices.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/09/2018	Active	10043160
10043161	TELEDYNE CONTROLS, LLC	REV. 4	FAA STC SA8030NM	737-900/-900ER 737-500/-600/-700/-800 737-100/-200C/-300/-400	Requirement for the installation of Teledyne Controls Digital FlightData Acquisition Unit (DFDAU) and Digital Flight Data Management Unit (DFDMU).This STC supersedes UK CAA's certificate CAA.21NE2.00007.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List Document No. MDL2233000-737 revision A, Appendix C< (>,<)> dated 26 June 2000 or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/10/2019	Active	10043161
10043162 (2004-5756)	TELEDYNE CONTROLS, LLC	REV. 3	ST01268LA	737-900 737-600/ 737-700/ 737-800 737-300/ 737-400/ 737-500 737-100/ 737-200/ 737-200C	Installation of Teledyne Controls Wireless Ground Link-Quick AccessRecorder (WGL-QAR).This STC supersedes Luftfahrt-Bundesamt (LBA) certificate LBA.21NE1.TA0743 and follows EASA approval letter 2004-5756 due to a change inthe applicant's address.	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchangedand remain applicable to thiscertificate/ approval.	Teledyne Controls MDL 2243800-737, Revision "B", Appendix A, Nov. 16,2001or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agree...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/04/2016	Active	10043162
10043163	TELEDYNE CONTROLS, LLC	REV. 2	FAA STC SA6084NM	MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Validation of STC Teledyne Controls Optical Quick Access Recorder (OQAR) P/N 2248000-40 on McDonnell Douglas MD-80.This STC was previously approved by Registro Aeronautico Italianoaccording to their letter No.93/514/ MAV and has been issued by EASAfollowing a change in the applicant's address.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved Teledyne Controls Master Data List No. MDL 2248000-MD-80,Revision "B", dated November 10, 1993or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Pr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/04/2016	Active	10043163
10043168	ATELIER CHABORD	REV. 2		F152, FA152 152	Exhaust system and silencer installation (according to Chabordmodification STC CESSNA 152-17-01)Revision 1: Changes of raw material and coating.Revision 2:-Enhanced silent blocks-Alternative anti corrosion surface treatment-Enhanced shape of central structural part in muffler	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 Amdt 3 § 607,611, 783, 807, 867, 1101, 1121, 1123, 1125, 1529The requirements for environmental protection and the a...	Technical Dossier ref. STC CESSNA 152-17-01 Revision B dated 09 June2022Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	27/07/2022	Active	10043168
10043177	ACS-NAI Ltd.			CL-600-2B16 (604 VARIANT)	Installation, Aircell Communication System	EASA.IM.A.023The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	-Transport Canada STC No. C-LSA12-046/D, Issue 1 dated 12 July 2012.-ACS-NAI Ltd Modification Data Summary H048000 Revision NC.-ACS-NAI Ltd Mandatory Maintenance Manual Supplementfor theinstallation, Iridium Antenna FS 580, H048075 Revision N/C.-ACS-NAI Ltd Instructions for Continued AirworthinessI...	Restricted to ASN 5541	09/01/2013	Active	10043177

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043181	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	EC 135 T2+	ECUK/135/2047 Installation of RTE Aircraft:Installation of LH and RH Meeker steps, EASA STC EASA.IM.R.S. 01490refers. AnSWE Systems Camera system is installed with Turret attachedto the front of the Left Hand Meeker Step via Meeker A11 Utility Mount,Meeker DT-1 Dovetail adapter and EC UK Adapter Pla...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Design Report N° DR/ 1352047-001, Issue A, dated 7 December 2012.- Instructions for Continued Airworthiness ICAW/ 1352047-001, Issue A,dated 14th December 2012.- Supplement N° 60 to the approved EC 135 T2+ RFM: "Installation RTEAircraft", Issue 1, dated 18th December 2012.	For Day/Night VFR only.	09/01/2013	Active	10043181
10043207	PRATT & WHITNEY ENGINE SERVICES, IN	REV. 2	FAA STC ST11053SC	DHC-8-401/-402 DHC-8-301/-311/-314/-315 DHC-8-201/-202	Installation of a P & W Flight Data Acquisition, Storage andTransmission System (FAST)Extension to models DHC-8-200/300Series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.1 (a) Amdt. 25/11, CS 25.23 (b), CS 25.301 (a)(b)(c) Amdt. 25/1,CS 25.303, CS 25.305 (a)(b) Amdt. 25/1, CS 25.307 (a) Amdt. 25/1, CS25.341 (a) Amdt. 25/12, CS 25.561...	Installation in accordance with Installation Data List GN4-T-100-1, Rev.B or GN4-T-100-2, Rev. B.Operation in accordance with AFMS GN4-T-250-1, Rev. A or GN4-T-250-2,Rev. A.Instructions for Continued Airworthiness in accordance with GN4-T-260-2,Rev. B or GN4-T-260-3, Rev. C.or later revisions of the...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/10/2014	Active	10043207
10043211	SABENA TECHNICS BOD			A320-214	Installation of new 9101VU & 9102VU racks in cargo area	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan PC-D0087-003 Issue 3 dated 07/01/2013-Master Drawing List MDL-S-53-2269-01 Issue D dated 03/01/2013-Instructions for Continued Airworthiness (ICA) ICA-D0087-00-002 IssueA dated 07/12/2012-Modification Approval SheetMAS-S-53-2269 Issue 4 dated 07/01/2013or later revisions of...	This approval is limited only to MSN 764	11/01/2013	Active	10043211
10043212	SABENA TECHNICS BOD	REV. 1		A320-214	Structural provisions for Live TV Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan PC-D0087-001, Issue 7, dated 16/09/2013- Master Drawing List MDL-S-53-2270, Issue D, dated 03/01/2013- Instructions for Continued Airworthiness ICA-D0087-00-003, Issue B,dated 05/09/2013-Airworthiness Limitation Supplement ALS-D-0087-53-001, Issue B, dated12/07/2013-Modificati...	This approval is limited to MSN 764.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/09/2013	Active	10043212
10043216	PRO STAR AVIATION, L.L.C.		FAA STC SA00321BO	PC-12/45, PC-12/47, PC-12/47E	STC Prostar Aviator 200 inst. on PC-12/45/47/47ESwift Broadband Communication with WiFi and Phone through SATCOM.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: FAA MoC IP S-1 stage 4 "Installation WLAN".The certificated noise and/ or emissions levels of the original productare unchanged and rema...	FAA AFMS "Aviator 200 Swiftbroadband Sys" Doc. 21037-FMS-01Rev. IRor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	S/N: all legacy MSN	14/01/2013	Active	10043216

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043218	SABENA TECHNICS BOD			A320-214	Installation of new forward INMARSAT SATCOM system, aft SATCOM SBBupgrade, new Live TV system and upgrade of the IFE and CMS	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchangedand remain applicable to this certificate/ approval.	- Certification Plan PC-D0087-002 Issue 3 dated 07/01/2013-Master Drawing List MDL-S-00-2230 Issue A dated 07/01/2013-Instructions for Continued Airworthiness (ICA) ICA-D0087-00-001 IssueA dated 06/12/2012-Modification Approval Sheet MAS-S-00-2230 Issue 4 dated 07/01/2013or later revisions of the...	This approval is limited only to MSN 764This modification can be installed only concurrently with themodifications approved under EASA STC 10043212 (EASA project0010016696).	11/01/2013	Active	10043218
10043232	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA STC SA12-63	BD-700-1A10	Installation, Aircraft Completion Modifications.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS25Amendment 1 - Various.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged an...	Transport Canada STC No. SA12-63, Issue 1, dated 17 October2012.Innotech Aviation Configuration Definition Record CER-BD700-001 RevisionA.Innotech Aviation Airplane Flight ManualSupplement AFMS-IA6000-2500Revision A.Instructions for Continued Airworthiness Document GC94820000-ICA.or later revision...	Restricted to ASN 9482 - The WLAN System is intended to provide internetconnectivity and e-mail services to the airplane's cabin using PortableElectronic Devices (PEDS). Any otherintended function of this equipmentwill require a re-examination of the certification basis.	14/01/2013	Active	10043232
10043246	AERO-DIENST GMBH & CO. KG	REV. 1		BD 100-1A10 (CHALLENGER 300)	Installation of a Thrane and Thrane Aviator 300 Swift BroadBand -satcom system with WLAN capability.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,Engineering Order 264-CL.056.01 rev 1 dated 28/12/2012-,,Instructions for Continued Airworthiness ref. AG959-085 revIR-,,Airplane Flight Manual Supplement AFMS AG959-071 rev IROr later revisions of the above listed documents approved by EASA.	Refer to AFMS AG959-071 rev IR.	16/01/2013	Active	10043246
10043261	FIELD AVIATION EAST, LTD.		TCCA STC O-LSA12-130/D	DHC-8-202	Dual Universal UNS-1E(w) Flight Management System Upgrade	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be performed in accordance with FACI Master Drawingand Data List N° 25670000, Rev. IR<(>,<) >Operations must be performed in accordance with FACI Flight ManualSupplement N° 25673000, Rev. IR<(>,<) >Maintenance must be performed in accordance with FACI Maintenance ManualSupplements...	Limited to Serial Numbers 477, 488, 496, 498 and 504 with EASA STC10028595 (Advanced Avionics Technology) installed.	16/01/2013	Active	10043261
10043262	NSE INDUSTRIES S.A.			A109E	Installation of Night Image Vision System kit, allowing night VFR flight with Night Vision Goggles	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-ROTORCRAFT FLIGHT MANUAL SUPPPLEMENT A109 , document RFMS-0020-12AF02Rev. 04or later revisions of the above listed documents approved by EASA.-CONFORMITY STATEMENT AND DOCUMENTARY ARCHITECTURE A109, DocumentReference CONFAD-01A-1000-000 Rev. 01-INSTRUCTION FOR CONTINUED AIRWORTHINESS NVIS A109E, do...	Refer to applicable RFM for list of equipment mandatory forNight VisionImage System certificationInstallation of NVIS/ NVG compatible lighting does not include or implyapproval for flight operations with Night Vision Goggles (NVG). Theoperator must receive approval for the Civil Aviation operational...	17/01/2013	Active	10043262

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043263	MT-PROPELLER ENTWICKLUNG GmbH			G 115E	Installation of 3-blade MT-Propeller Model MTV-12-B-C/C183-17e	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/ approval involves a change to the requirements forenvironmental protection and/or a change to the certificated noise and/or emissions levels.Compliance with the following requirements,r...	According to MT-Propeller Master Document List No. E-2266 andMT-Propeller Installation Instructions Doc. No. E-2264, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2263To be maintained i.a.w. MT-Propeller ICA Document No. E-2265or later revisions of the above li...	according limitation section of AFM-S	17/01/2013	Active	10043263
10043265	ROSEMOUNT AEROSPACE, Inc.		FAA STC NO. ST02199CH	717-200	Installation of Rosemount Aerospace Inc, 8400E1 Cockpit DoorSurveillance System in Boeing 717-200 Series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST02199CH dated 28 October 2005.Rosemount Aerospace Master Data List, Doc. No D0530319, Revision B,dated 28October 2005.Airplane Flight Manual Supplement, Rosemount Aerospace Doc. No.D0530334, Revision A, dated 28 October 2005.or later revisions of the above listed documents approved by...	none	17/01/2013	Active	10043265
10043267	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST02904NY	777-200/-200LR/-300/-300 ER	Installation of a Panasonic Avionics Corporation Global CommunicationsSuite (GCS)Rev.1: Adds the 777-200/-200LR to the list of applicable models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:For the 777-200/-200LR modelsThe Certification Basis for the original product as amended by thefollowing additional or alternative airworthiness requirements:the following...	- Master Document List 0143-07644-2282 Rev. Q dtd. 19.Nov 2016- AFM Supplement 0643-07650-2282 Rev. C dtd. 20.Oct 2016- Instructions for Continued Airworthiness & Airworthiness Limitations0743-07645-2282 Rev. I dtd. 17.Nov 2016or later revisions of the above listed documents approved by EASA inaccor...	The Panasonic GCS must interface with the following systems/components:- T-PED FAA STC ST03048CH as validated by EASA STC Ref. 10043422- Antenna FAA STC ST02905NY-D as validated by EASA STC Ref. 10043555Rev. 1Prior to installation of this design change it must be determined thatthe interrelationship...	13/03/2019	Active	10043267
10043269	JET AVIATION AG, BASEL			MF50 (EX-VERSION)	WLAN activationElectro-Magnetic Compatibility demonstrationof aeroplane's requiredsystems immunity to worst case WLAN IEEE 802.11 a/b/g/n passengerscarry-on TPED transmissions.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Data List, Doc. No. BFSLA001-002, Rev. IR, dated 11.01.2013- AFMS, Doc. No. BFLSA001-201-02, Rev. IR, dated 11.01.2013- ICA, Doc. No. BFLSA001-150-02, Rev. IR, dated 10.12.2012or later revisions of the above listed documents approved by EASA.	S/N: 348 F-GLSA	17/01/2013	Active	10043269
10043270	AVIONIK STRAUBING ENTWICKLUNGS GmbH			MBB-BK 117 B-1, B-2, C-1, C-2 MBB-BK 117 A-1, A-3, A-4	Installation of Cockpit Voice Recorder L-3 FA2100CVR as defined inASR-2012-093-PRD-04-00.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASR-2012-093-TCP-06-00 dated 08/11/2012ASR-2012-093-PRD-04-00 dated 14/11/2012ASR-2012-093-COR-07-00 dated 10/01/2013ASR-2012-093-MDL-01-00 dated 10/01/2013	None	17/01/2013	Active	10043270
10043286	AVIONITEC Ltd.			335	Compliance showing to AMC20-28 for certification of existing equipmentfor RNAV (GNSS) Approaches down to LPV Minima.Compliance showing to AMC20-27, resp. CRI F-10 (Airworthiness Criteriafor RNAV Equipment supporting APV BARO VNAV approaches to LNAV/ VNAVminima with VNAV provided through SBAS Augmente...	FAR 23<(>,<)> Amdt: 23The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List: Doc. No. 2307-017, dated 14.12.2012Instructions for continued airworthiness: Doc. No. 1193-015, dated08.12.2011Airplane Flight Manual Supplement for dual GNS430W Installation: Doc.No. 1193-011, dated 14.12.2012	S/N: HB-LHA	17/01/2013	Active	10043286

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043289 (EASA.A.S.03339)	A Y M AVIONICS, SL	REV. 1		PA-34-200	Installation of Dual COM/NAV/GPS GARMIN GNS 430 & GNS 530	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Technical Documents to be Approved by EASA:- SERVICE BULLETIN BI Nº: 19/07 R1- SMV Nº 19/07 R1, Airplane Flight Manual Supplement for IFR operationswith Dual Garmin GNS 530 & Garmin GNS 430. or later revisions of the above listed documentsapproved by EASA	Approval limited to Airplane Model PA-34-200, S/N 34-7250309	19/02/2013	Active	10043289
10043290 (EASA.R.S.01538)	STIRLING DYNAMICS GMBH	REV. 3		BELL 206B	Avionics Systems Exchange/Installation - CNI EquipmentInstallation and Interfacing of the following:GARMIN DUAL 430AW with MD-41-1488A and GAD-42Sandel SN4500 EHSI, SG102-200DG Compass System with MT102GARMIN Dual GTX-330 Mode-S Transponders with SSD120-30N-RS232 EncoderGarmin GMA340H Audio/Marker p...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-AA1327-02-01R3 dated 06 March 2009 – Technical order (containsinstallation instructions);-HP2061-AM-2350-01-01 issue 2dated 16 March 2009 – Flight ManualSupplement GMA340H;-HP2061-AM-3010-01-01 issue 2 dated 16 March 2009 – Flight ManualSupplement Alternate Static Air Valve;-HP2061-AM-3400-01-01 i...	1. Prior to installation of this change/repair it must be determinedthat the interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of theproduct.2. The installation of this modification by third pe...	15/06/2022	Active	10043290
10043296	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 1	FAA STC SA890GL	2- A200C, A200CT, B200CT,B200T 2- 200, 200C, 200CT, 200T,A200 1- B200, B200C, B200GT,B200CGT	Installation of Parker Hannifin Corporation, Aircraft Wheel& BrakeDivision Conversion Kit 199-110, revision AB, dated June 18, 2010, andif applicable, installation of Parker Hannifin Corporation, AircraftWheel & Brake Division Hot Air Manifold Kit 199-168, revision F, datedJune 18, 2010.Rev. 1: Tra...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Installation in accordance with Installation Drawing 50-79,revision N,dated June 18, 2010; Continued Airworthiness in accordance with ParkerHannifin Corporation, Component Maintenance Manual CM30-146, revision D,dated January 19, 2011 andComponent Maintenance Manual CM40-289,revision B, dated Augu...	This installation is restricted to those aircraft with standard landinggear (18x5.5 Main Wheel & Brakes).	11/11/2024	Active	10043296
10043300	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	A330-202	Stretcher installation and Aircraft cabin reconfiguration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 4 - VariousThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged an...	EASA STC 10043300H4 Aerospace Modification Summary and Declaration of Compliance No. MODH4A1567 Issue 4 dated 10 March 2013H4 Airplane Flight Manual Supplement No. H4AFMS028H4 Instructions for Continued Airworthiness No. H4ADR739or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	10/04/2013	Active	10043300
10043307	EUROCOPTER CANADA Ltd.		TCCA STC SH12-9	EC120B	Door Handle installation (P/N 120-200014)Validation of TCCASTC SH12-9 Issue 1 dated 09/02/2012To correct handling problems induced by the serial design of theright-hand cabin door handle, Eurocopter Canada Ltd has designed a newdoor handle.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Definition and Installation in accordance with:- EurocopterCanada Limited Master Drawing List MDL-10-014, Issue B- Eurocopter Canada Limited Installation Procedure IP-ECL-126, Revision1Maintenance in accordance with:- Eurocopter Canada Limited Instructions for Continued AirworthinesslCA-ECL-203, Re...	None	18/01/2013	Active	10043307

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043325 (EASA.IM.A.S.03181)	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03678AT	757-300 757-200	Installation of the Spectralux DLink + ACARS System into Boeing757-200/-300 Series Aircraft and associated hardware.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List 2-59475-001 Revision A, dated January 22, 20092. FAA Approved Airplane Flight Manual Supplement for the SpectraluxDLink+ ACARS, 2-59475-805, revision IR, dated March 11, 20093. Instructions for Continued Airworthiness (ICA) EMTEQ EngineeringDocument No. 2-59475-902, Rev. A, da...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10043325
10043326 (EASA.A.S.03863)	ACC COLUMBIA Jet Service GmbH	REV. 1		CESSNA 340A CESSNA 340	Alternative Supplemental Inspection Document (A-SID)Rev. 1 Transfer to ACC Columbia Jet Service GmbH		- According to Gomolzig MDL Document No. MDOCL20100_REVO_300 42009 orlaterEASA approved Revisions- To be operated and maintained in accordance with approved GomolzigDocument No. 3A2S_A-SID_Master ManuaL20100_revO or later EASA approved Revisions	1. Alteration to A-SID is subject to written permission of approvalholder2. This modification is only limited to SIN listed in EASA approvedGomolzig Document No.20100_Master Aircraft Application Control3. Ust_30042009_ revO, or later EASA approved Revisions4. Prior to installation of this modificati...	26/01/2022	Active	10043326
10043338	CONCORDE BATTERY CORPORATION		FAA STC SA03971AT	DHC-6 SERIES 1, 100, 200, 300	Replace NiCd or Lead Acid battery with Concorde Lead Acid battery andassociated hardware in accordance with Master Drawing List 5-0398Revision E, dated May 4, 2012 or later FAA approved drawing revisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness (ICA), Concorde BatteryCorporation No. 5-0446, Rev. NC, dated September 29, 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Im...	none	22/01/2013	Active	10043338
10043346	BERINGER AERO	REV. 8		SR20, SR22, SR22T	Installation of main wheels (RF-006(A)), nose wheel (RA-002(A)) andbrake system (EA-003.4N(A))Revision 1: Upgrade of the brake system: EA-003.4N (B) supersedesEA-003.4N(A)Revision 2: Update of maintenance manual and part listRevision 3: Maintenance manuals updates and introduction of an aircraftfligh...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Associated documents as listed in the Master Data List:Document Number MDL-STC-004, Revision 6, dated 15th November 2024.<(>,<)>or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/12/2024	Active	10043346
10043347	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A310-304	Avionics and Cabin Systems Upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-01, Glass Screens of Displays/MonitorsCRI H-01, Enhanced Airworthiness Programme for Aeroplane Systems –ICAon EWISSpecified paragraphs from FAR 25 Amendment 54 (see...	Modification TEN 687, Airbus A310-304 Avionics and Cabin SystemsUpgrade, Issue 2 dated 17 January 2013Report TEN 687/1,Certification Compliance Report, Avionics and CabinSystems Upgrade, Issue 2 dated 17 January 2013or later revisions of the above listed documents approved by EASA.	Aircraft Serial Number 431 only.	22/01/2013	Active	10043347

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043355	WESTERN AVIONICS		TCCA STC SH11-20 ISSUE 1	R44 & R44 II	Installation of Aspen Avionics EFD 1000H/500H Electronic Flight DisplaySystems in accordance with Western Avionics Engineering Order CE13-401.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 27.610 at Amdt. 37The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and rem...	Flight Manual Supplements:Configuration, , ,,,,,, ,,Supplement,, ,,,,Approval DateEFD1000H PFD,,,,,,,,,CE13-801,,,,,2011 June 23EFD1000H PFD & EFD1000H MFD,,CE13-802,,,,,2011 June 23EFD1000H PFD & EFD500H MFD,,,,CE13-803,,,,,2011 June 23,,or later revisions of the above listed documents appro...	none	23/01/2013	Active	10043355
10043360	DART AEROSPACE Ltd.	REV. 3	TCCA SH12-58 ISSUE 5	429	INSTALLATION OF EXTERNAL ATTACHMENT PROVISIONS, CARGO BASKET AND CABINSTEPSCONFIGURATION A - External Attachment Provisions Only: Installation asdefined in DCL959-2.CONFIGURATION B - External Cargo Basket: Installation as defined inDCL959-1 and modifications eligible in accordance with DCL704-429.CO...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	CONFIGURATION A:-Aero Design Ltd. Document Control List, DCL959-2, Rev. 2, dated 12September 2014CONFIGURATION B:-Aero Design Ltd. Document Control List, DCL959-1, Rev. 2, dated 12September 2014<(>,<)>-Aero Design Ltd. Document Control List, DCL704-429, Rev. 1, dated 12September 2014CONFIGURATIONS A...	1. Installation of Configuration A, external attachment provisions, is apre-requisite for installation of ConfigurationB, external cargobasket.2. Installation of Configuration A,external attachment provisions, is apre-requisite for installation of Configuration C, cabin steps.3. Installation of th...	10/11/2021	Active	10043360
10043374	JCB AERO SA			737-800	VIP Cabin ReconfigurationSee Project Data List B738-35792-01-PDL-01 rev G.	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.SCs or ESFs:CRI D-002 SC Isolated CompartmentsCRI D-012 SC Injury Criteria for Single Place Side Facing SeatsCRI H-001 SC EWISCRI D-001 D...	Aircraft Flight Manual Supplement: B738-35792-01-AFMS-01 rev BInstructions for Continued Airworthiness: B738-35792-01-ICA-01 rev CCabin Attendant Operating Manual: B738-35792-01-CAOM-01 rev Cor later revisions of the above listed documentsapproved by EASA	S/N: 35792Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.This Supplemental Type Certificate is app...	24/01/2013	Active	10043374
10043375	BOMBARDIER INC.		TCCA STC NO. C-LSA12-011	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9381	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-600 Shower InstallationThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged...	TCCA STC No. C-LSA12-011/D Issue 1 dated 17 February 2012.Bombardier Inc. Modification Data Summary RAZ-BM700-9381-MDS RevisionNC.Airplane Flight Manual Supplement for the Aircraft Completion,G-FM25060001 Revision NC.Instructions for Continued Airworthiness for the Aircraft InteriorCompletion, GC938...	Restricted to ASN 9381.Installation of structural provisions for the shower drain feedthroughin accordance with EASA Supplemental Type Certificate number 10036344 (TCCA STC No. SA11-69) is a prerequisite for this STC.Prior to installation of this design change it must be determined thatthe interrelat...	24/01/2013	Active	10043375
10043377	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 2		777-300	Interior Reconfiguration for Cathay Pacific Boeing 777-300 Aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List Interior Reconfiguration Cathay Pacific AirwaysBoeing 777- 300 Aircraft - N0435-D10, Revision B- Airways Boeing 777-300 Aircraft Instructions for ContinuedAirworthiness - Principle Manual for an Interior Reconfiguration onCathay Pacific Airways, LTD. (CAT) B777-300 Aircraft - N...	The STC is limited to the following serial numbers: 27504-27510,33702-33704, 34243, 34244.Prior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse eff...	01/02/2013	Active	10043377

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043384	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SA02488CH	PC-12, PC-12/45, PC-12/47 PC-12/47E	Air ambulance conversion in accordance FAA STC SA02488CH.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement, Spectrum Aeromed Manual, 6045FMS,Initial Release, dated September 21, 2007;Instructions for Continued Airworthiness, Spectrum Aeromed Manual6045MM, Initial Release, dated May 30, 2007;or later revisions of the above listed documents approved by EASA inaccordance wi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/04/2019	Active	10043384
10043385	CONCORDE BATTERY CORPORATION	REV. 2	FAA STC SR03072NY	AB139, AW139	Replacement of NICAD battery with Concorde Lead-Acid batteryNote: this STC revision is done for transfer of original EASA STC10043385 Rev. 1 to new holder, Concorde Battery Corporation.Rev. 3: adds an additional configuration to the airframe (-005).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For Rotorcraft with RG-380E/44L main battery installed:DECAAviation Engineering Flight Manual Supplement, FMS11143-01,Revision 2 dated July 10, 2012.For Rotorcraft with RG-380E/ 60L main battery installed:DECA Aviation Engineering Flight Manual Supplement, FMS11143-02,Revision 2 dated July 10, 2012o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/07/2024	Active	10043385
10043392 (EASA.R.S.01439)	NSE	REV. 1		206B, L, L-1, L-3, L-4	Installation of Usage Monitoring System Brite Saver 2, recorder box P/NREC-ARA0-TT-00 up to Amdt 07.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement Bell 206, RFMS-ARA0-BELL206-ENrevision 00or later revisions of the above listed documents approved by EASA.Instruction for Continued Airworthiness ICA-REC-ARA0-206 revision 00 (noALS associated with thisSTC) Mounting Instruction IM-KIT-ARA0-206-EN revision 05Opera...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/08/2016	Active	10043392
10043402	LUFTHANSA TECHNIK AG			A319-112	Installation of NEK cabin modification.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,Declaration of Compliance ADC 3499 Rev. IR, dated 18/01/2013;-,,Compliance Record List CRL25-12/30M Issue 1 Rev. 0,dated 18/01/2013;-,,Supplemental Type Definition Document STDD25-12/30M Issue 1 Rev. 0,dated 18/01/2013;-,,Instructionsfo r Continued Airworthiness A-00-12/46-ICA Issue 1 Rev.IR, d...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	25/01/2013	Active	10043402
10043408	SABENA TECHNICS BOD	REV. 2		ATR 42-500	Cabin and Communication systems upgradeThis modification consists in installing SATCOM and cabin telephonycapacity, as well as a modification of the rear galley area (new galleyand seat arrangement reconfiguration).The Revision 1 relaxed the initial terms of limitations, from 3 to 6months.The Revis...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Approval Sheet, ref : MAS-S-00-2282 Issue 7, dated 22 April2013Aircraft Flight Manual Supplement, ref : AFMS-S4014-00-001 Issue 3,dated 17 January 2013Instruction forContinued Airworthiness, ref : ICA-S4014-00-011 Issue A,dated 20 December 2012Airworthiness Limitations Sections, ref :d...	The embodiment of this STC is limited to MSN 859Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	24/07/2013	Active	10043408

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043418	E A D AEROSPACE AIRWORTHINESS	REV. 1		A340-541	Description for the initial approval:Installation of GSM System in an A340GSMConnex is solution that provides GSM services to aircraft passengersand crew. It consists of hardware and software parts for both theaircraft and the ground, withthe airborne GSM network being connectedto ground network vi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Documentation related to the initial approval not totally superseded bythe revision A:Compliance Check List 01388-EAS-A-CCL-01, Isse D, dated 24th January2013.Documentation related to revision A:Airplane Flight Manual 01388-EAS-A-AFM-01, Rev.C, dated 23rd April 2013.Master Drawing List 01388-EAS-A-M...	This approval is limited to the aircraft MSN 495 (A340-541) configuredaccording to the ICA document 01388-EAS-A-ICA-01-C. As is stated in thisdocument the aircraft must be equipped only with those elements provedto be compatible with the GSMConnex installed.For Cockpit and Cabin CIDS handests, the P...	06/05/2013	Active	10043418
10043419	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			C90A, C90GT, C90GTI. B90, E90, C90,	STC 3807/12 revision 3 - Installation STC EASA 10037574	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS 23 Amdt 2Therequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalu...	Supplément manuel de vol SMV 3807-12 Rev3 du 22 Jan. 2013orlater revisions of the above listed documents approved by EASA.	The STC is approved for aircraft equipped with EFIS/EHSI and automaticpilot defined in GARMIN IM 190-01007-A3 and 190-01007-02 and STC 2807/12annex C2.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously instal...	28/01/2013	Active	10043419
10043422	ARMSTRONG AEROSPACE Inc.		FAA STC ST03048CH	B777-200/-200LR/-300/-300ER	Certification of Compatibility with Cellular and Wireless DataTechnologies	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Armstrong Aerospace Master Data List DC104-9044-00, Revision E dtd.21.December 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)) and/or the Technical Implementation Procedures of EU/USA Bila...	1) Honeywell Display Unit, P/N 4091900-xxx (Example P/Ns 4091900-931,4091900-932, 4091900-933 and 4091900-934), has exhibited susceptibilityduring 4 watt EIRP Personal Electronic Devices (PEDs) wireless dataradio frequency compatibility tests2) This STC does not constitute installation approval of a...	28/01/2013	Active	10043422
10043426	AIRBUS HELICOPTERS CANADA LIMITED	REV. 2	TCCA SH96-126	EC 130 B4, EC 130 T2 AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Validation of STC SH96-126 “Blade Tie Down provisions kit”,TCCAapprovedThis STC revision 02 is issued to validate the eligibility extension ofBLADE TIE-DOWN PROVISIONS KIT as defined in Master Drawing ListMDL-96-012 Rev I, to EC130 T2 helicopters.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List MDL-96-012 Rev IInstruction for Continued Airworthiness ICA-ECL-237 Rev 02Stress Analysis Report TR-E-0355 Rev E	This modification is compatible only with main rotor bladesequippedwith tracking fingers p/n 350A11-1248-20 or 355A11-2013-20.The tie-down ropes are placarded to indicate that they are not to beused in winds above 40 knots.Prior to installation of this design change it must be determined thatthe in...	18/04/2016	Active	10043426
10043461	BUSINESS AND COMMUTER AIRCRAFT			B200, B200C, B200T. 200, 200T,	BCA 139 Revision 0b dated 28 jan. 2013 - Rockwell Collins TCAS 4000installation	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS 23 Amdt 3Therequirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the originalu...	Airplane Flight Manual Supplement BCA 139-07 revision 0b dated 28 Jan. 2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined ADCcompatibility with transponder.Prior to installation of this modification it must be determined thatthe aircraft total load electrical consumption does not exceed 80% ofthe total aircraft electrical capacity.Installation of new soft...	30/01/2013	Active	10043461
10043462	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	LEARJET MODEL 60	STC Twenty One Limited Project No. S21.53-115-1037Installation of Satcom AntennaThis design change introduce a satcom antenna to the crown skin of theaircraft. The design change is limited to the mechanical changes to theaircraft only.The antenna will be used in connection with a separate design cha...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Limited, Master Drawing List S21.MDL-1073 issue 1, dated30 January 2013STC Twenty One Limited<(>,<)> Supplement Manual S21.TEC-0371, issue 1,dated 28 January 2013orlater revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	30/01/2013	Active	10043462

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043464	STANDARD AERO		FAA STC ST03033CH-D	G-1159A, G-IV, GV, GV-SP,GIV-X	Installation of a True North Simphone System with Global SwiftBroadband.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,Standard Aero Master Data List, ref.doc. 1021093, Revision D, dated16th December 2011;-,,FAA Approved Airplane Flight Manual Supplement, ref. doc. 1021218,Revision A, dated 16th December 2011;-,,Airworthiness Limitations specified in Standard Aero document ref.1021335, Revision B, dated 30th Nove...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	30/01/2013	Active	10043464
10043471	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST02257SE	777-200	Title: Austrian Interior ReconfigurationDescription: Interior Reconfiguration as detailed in Project SpecificCertification Plan SR1360-CP	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): E-01, Installation of Inflatable Restraints25.853(a)(d)(e) CS 25, Amdt 125.869(a)(1)(4) CS 25 Amdt 425.1357(a)(b)(c) CS 25 Amdt 425.1431(a)(c) CS 25,...	Master Data List, Doc. No. HPD-DL-157, Rev. L, dated 20.12.2012Instructions for Continued Airworthiness, Doc. No. HTM1012, Rev. A,dated 20.12.2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)"...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	01/04/2014	Active	10043471
10043472	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	DHC-8-401, DHC-8-402	Introduction of CabinVu 123 Cabin Surveillance System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with STC Twenty One Master DocumentList S21.MDL-0826,Issue 3;Maintenance must be in accordance with Supplement Manual S21.TEC-0278,Issue 3;Operation must be in accordance with AD Aerospace Operating Manual CabinVu 123, latest Issue;or later revisions of the above l...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	31/01/2013	Active	10043472
10043477	AEROTEC & CONCEPT			A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	A330 Air China WiFi SystemThe modification deals with the installation of a WIFI system on AirChina A330 aircraft. The WIFI system is built with 2 LRU installed inElectronic Bay (AMDP and PoE) and 7 WIFI Access Points dispatched in thepassage cabin aera.The Power Over Ethernet (PoE) hosts an Etherne...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List AE12072MDL Rev.0, dated 23/01/2013.Flight manual supplement AE12072AFMS Rev. 0, dated 23/01/2013.Instructions for Continued Airworthiness AE12072ICA Rev. 0, dated23/01/2013.or later revisions of the above listed documents approved by EASA.	None	31/01/2013	Active	10043477
10043481	VIDEO TECHNOLOGY SERVICES, Inc.		FAA ST03223NY	B767-200/ -300	Installation of LCD Monitors.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.305, 25.307, 25.561, 25.603, 25.605, 25.613, 25.625, 25.785, 25.789,25.853, 25.1351, 25.1529 at Amendment 11.The requirements for environmental protection and the assoc...	Technical Drawing List 205-D-480, Revision -, 30/03/2012;ICA Document 205-D-481, Revision B, 15/07/2012;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Proc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	31/01/2013	Active	10043481

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043502	DASSAULT FALCON SERVICE			F2000, F200EX	LIFEPORT Powered Loading System InstallationPatient Lift System is installed on PAX door for boarding patients. Thewhole system is self-powered and independent of the A/C electricalsystem. It is disposable for ground use only.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet DFS153-CAS Issue A dated 31.01.2013;DFS Modification Sheet DFS153, Issue A dated 25.01.2013;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	01/02/2013	Active	10043502
10043505	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		2. B200, B200C, B200T, B200GT 1. 200,200T	BCA 136 Revision 0 dated 28 Jan 2013 - Flight Display Systems FD200CPU-8and FD102CV Moving Map cabin installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement BCA136-02 Rev 0 dated 28 Jan 2013or later revisions of the above listed documents approved by EASA	Installation limited to Proline 21 equipped aeroplanes.Prior to installation of this modification it must be determinedthatthe aircraft total load electrical consumption does notexceed 80% ofthe total aircraft electrical capability.Priorto installation of this design change it must be determinedt...	02/03/2015	Active	10043505
10043526	STANDARD AERO		FAA STC ST03175CH-D	A330-342, A330-343 A330-322, A330-323, A330-341, A330-301, A330-302, A330-303,	Installation of the ARINC Cabin Connect provisions.Installation of the ARINC Cabin Connect in-flight entertainment systemprovisions in preparation for activation on-board Airbus A330-300 seriesaircraft.The connection or activation of the components installed by thi...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List DC104-9157-00, dated 01/17/2013.FAA Approval ST03175 CH-D, dated of 30/01/2013.Statement of Compliance, latter 20130201 Foreign Valid 3175 EASA,received 01/02/2013.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or sub...	The connection or activation of the components installed bythismodification is not covered by this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce...	04/02/2013	Active	10043526
10043534	AEROSPACE DESIGN AND CERTIFICATIONLtd. T/A AERODAC		CAA UK RESPONSIBILITY	BELL 429	Bell 429 Human External Cargo HookaeroDAC Modification DualCargo Hook Described in Master Data List JN382Issue 1, 10 January 2013	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRI F-01HIRF ProtectionThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and r...	- Flight Manual Supplement No.1 aeroDAC Modification NumberJN382 DualCargo Hook, ISSUE 1, dated 04 February 2013or later revisions of the above listed documents approved by EASA.- Master Data List Dual Cargo Hook JN382 Issue 1, 10 January2013.- Installation Instruction Dual Cargo Hook JN382 Issue2...	- Hover performance data and hooks operationsare not provided.- Operation with persons attached to the dual cargo hook system shallnot be conducted without approval by the responsible authority inaccordance with the operational regulations.- The aeroDAC Modification Dual Ca...	04/02/2013	Active	10043534
10043536	SABENA TECHNICS BOD	REV. 1		MBB-BK117 C-2	Replacement of the FLIR analogue video recorder SONY DSR-20MDP by adigital video recorder SKYQUEST VDRV-3000-01, as detailed inM004-85-11-145.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	- Dossier de Modification M004-85-11-145 Rev. 2;- Installation instructions and Instructions for ContinuedAirworthiness: Service Bulletin "Installation VRDV EC145",145HU-SB-85-68 Rev. 1;Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.,,	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/03/2025	Active	10043536
10043539	SIMPLEX MANUFACTURING CO.	REV. 1	FAA STC SR0227SE	AS 355 N, AS 355 NP AS 355 F1, AS 355 F2, AS 355 E, AS 355 F, AS 350 B3, AS 350 B1, AS 350 B2,	Installation of an airborne high-pressure spray system (Simplex Model510) capable of cleaning debris from the insulators on electrical powertransmission towers. The system consists mainly of an external watertank, a power pack and a turretwith spray boom.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFMS 510-102003-002, Rev. IRor later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.MDL510-001, Rev. H or later revisionsPS...	The rotorcraft must have STC EASA.IM.R.S.00622 (Validation of FAA STCSR01289SE) installed to ensure proper operation ofthe pitot-staticinstruments.With the Model 510 Spray Systeminstalled the rotorcraft is certifiedfor day VFR operationsonly.With the Model 510 installed no spray or flight operati...	14/02/2013	Active	10043539

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043542	B/E AEROSPACE, Inc.	REV. 2	FAA STC 03980AT	777-300, 777-300ER. 777-200, 777-200LR,	Installation of the Honeywell MCS-7147 SATCOM SystemDESCRIPTION: Removes and Replaces the existing Honeywell MCS-6000 orMCS-7000 SATCOM System's Satellite Data Unit (SDU) and HighPowerAmplifier (HPA) with the MCS- 7147 SATCOM System's SDUand HPA/HighSpeed Data Terminal (HSDT).Revision 2 transferre...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: 25.23(a), 25.301(a), 25.561(c), 25.601, 25.603(a)(b)(c), 25.605(a), 25.607, 25.609(a), 25.613(a)(b)(c), 25.863(a)(b), 25.135...	- Master Drawing List 2-95373-001 Revision B, dated September 12, 2012- Instructions for Continued Airworthiness (ICA), EMTEQ EngineeringDrawing No. 2-95373-804, Revision A, dated September 12, 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decisiont...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	02/03/2016	Active	10043542
10043552	PROTOPLANE SPECIAL MISSION AIRCRAFT	REV. 1		B300, B300C (KING AIR) B200, B200C, B200GT, B200CGT	Installation of a radar and a turret on a B350ER	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Master Document List: PP-026-MDL-05Instructions for Continued Airworthiness: PP-026-ICA-01Flight Manual Supplement: PP-026-AFM-06or later revisions of the above listed documents approved by EASA	Limited to S/N FL708Limitations according to Flight Manual Supplement PP-026-AFM-06.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect up...	12/02/2013	Active	10043552
10043555	DELTA ENGINEERING CORPORATION	REV. 1	FAA ST02905NY	777-300, 777-300ER 777-200, 777-200LR	Installation of a Panasonic Ku-Band Radome / Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST02905NYDelta Engineering Master Data List No.0143-07375-2278 Revision I dated12 February 2014.	None	06/10/2015	Active	10043555
10043560	GAMA AVIATION (ENGINEERING) LIMITED	REV. 1	CAA UK RESPONSIBILITY	206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	Spill Detection and Environmental Protection (SDEP) system for Bell206/407.Installation 1281, identified in MDL-1281, and installation 1387,identified in MDL-1387, are based upon the Thales Sweepir 20 infra-redsensor suite. This revision also extends the applicability of theseinstallations to the Be...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Installation 1281: EASA CS-27 amendment 2 (as in Certification ProgramCP-1281 Issue 2)Installation 1387: EASA CS-27 amendment 3 (as in Certification ProgramCP-1387 Issue 1...	For installation 1281: Rotorcraft Flight Manual Supplement ReferenceRFMS-1281-01 issue 02For installation 1387: Rotorcraft Flight Manual Supplement ReferenceRFMS-1387-01 issue 01or later revisions of the above listed documents approved by EASA.For installation 1281:Master Document List MDL-1281 Issu...	- The nose mounted equipment must only be installed on aircraft fittedwith high skid gear or high skid gear with emergency flotation equipmentto give adequate ground clearance.- The Spill Detection and Environmental Protection (SDEP) systemequipment is not approved for operating above 15000 ft altit...	20/05/2015	Active	10043560
10043568	JAMCO AMERICA, INC.		FAA STC ST01494SE	777-200, 777-200LR	Lavatory and Galley Modification	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	JAMCO America, Inc., Master Drawing List IA-118MDL, Revision C, datedDecember 29, 2004or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA B...	EASA validated version of FAA STC ST01493SE, interior reconfiguration ofthe passenger seating, must be installed concurrently with this STC.Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designa...	07/02/2013	Active	10043568
10043585	SCANDINAVIAN AVIONICS DESIGN ApS			DHC-8-401, DHC-8-402	Dual NAVAERO EFB Class 2 System Provisions	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with Technical Order Doc. 2068119-TO,Issue 3.Operation must be in accordance with AFM Supplement Doc. 2068119-AM A,Issue 3 or Doc. 2068119-AM B,Issue 3.Maintenance must be in accordance with MM Supplement Doc. 2068119-MM,Issue 2.or later revisions of the above lis...	This STC does not constitute an Operational Approval. IndividualOperational Approvals, including the COTS equipment suitability, must beissued by the competent NAA.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprev...	08/02/2013	Active	10043585

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043586	ARMSTRONG AEROSPACE Inc.		FAA STC ST03106CH	A330-341, A330-342, A330-343. A330-321, A330-322, A330-323, A330-301, A330-302, A330-303, A330-223, A330-243, A330-201, A330-202, A330-203,	Certification of Compatibility with Cellular and Wireless DataTechnologies	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Armstrong Aerospace Master Data List DC104-9045-00, Revision A dated 20December 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bila...	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane installed base station using the cellularand/or wireless technologies is concurr...	08/02/2013	Active	10043586
10043587	PMV ENGINEERING			A330-341, A330-342, A330-343. A330-321, A330-322, A330-323, A330-301, A330-302, A330-303, A330-223, A330-243, A330-201, A330-202, A330-203,	Installation of ECS EZMount mechanical mounting on Airbus A330.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Certification Investigation Report AVI-00250-CIR, Revision 0, dated24/09/2012.Instructio ns for Continued Airworthiness AVI-00250-ICA, Revision 0,dated 24/09/2012.Aircraft Flight Manual Supplement AVI-00250-AFMS, Revision 0, dated24/09/2012or later revisions of the above listed documents approved by...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	08/02/2013	Active	10043587
10043603	FEDERATION FRANCAISE DE VOL A VOILE (FFVV)			101	Polyurethane paint - M02-12-A01	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions level of the original productare unchanged and remain applicable to this certificate/ approval.	Supplément au Manuel d'Entretien C101 PEGASE Rev 1-1.doc;orlater revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	12/02/2013	Active	10043603
10043604	FEDERATION FRANCAISE DE VOL ENPLANEUR			ASW 20F, ASW 20 FL	Polyurethane paint - M03-12-A01	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions level of the original productare unchanged and remain applicable to this certificatel approval.	Supplément au Manuel d'Entretien ASW 20 F FL Rev 1or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	12/02/2013	Active	10043604
10043605	KUERZI AVIONICS AG			MD 500N	Avionic upgrade with Garmin 500HRemoved equipment:,,- OEM Attitude indicator<(>,<)>,,- OEM Directional Gyro<(>,<)>,,- OEM Vertical Speed indicatorInstalled equipment:,,- Garmin 500H System which includes,,,,- GDU 620 PFD/MFD,,,,- GRS 77H AHRS,,,,- GMU 44 Magnetometer,,,,- GDC 74H ADC,,,,- GTP 59 OAT...	The Certification Basis for the original product and the followingvoluntary compliance to FAR 27 was shown.The actual Amdt. used for each § is indicated after the FAR §. E.g.FAR27.1317 / 42 means Amdt 42 was used.FAR27.29 /0, FAR27.143 / 21,FAR27.251 /0, FAR27.301 /0, FAR27.303 /0,FAR27.305 /0, FAR27...	- Flight Manual Supplement: FMS-200932756, Original Issue, dated 11.02.2013;or later revisions of the above listed documents approved by EASA.- Master Data List: MDL-200932756, Rev. A, dated 11.02.2013;- Instructions for continued airworthiness: ICA-200932756, Rev. A, dated11.02.2013.	S/N: all- At least one SBAS capable Garmin GPS unit must beinstalled as aprerequisite.- This STC can only be installedon helicopter with a left hand command"T"- Instrument Panel(no slim line panel).- Rotorcraft modified under this G500HSTC are restricted to VFR only,including rotorcraft that may...	14/02/2013	Active	10043605

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043626	CORPORATION LOGIC AIR Inc.	REV. 1	TCCA SA11-92	737-300/737-400/737-500 737-30,0 737-400, 737-500	Installation of Dual CMC SBAS Landing System with CMA-5024 GLSSU sensorsandDual CMC CMA-5025 control panels.Configuration 1: Dual CMC GPS sensor (RNP) systemConfiguration 2: Dual CMC SBAS landing system (SLS) Rev 1: as per Rev 4 and 5 of certificate SA11-92, introduction of asoftware upgrade and of a...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Configuration 1:Installation Document List MDL-34436-2 rev 2Aircraft Flight Manual supplement 34436-AFMS-1 rev 0Maintenance Manual Supplement MMS-34436-1 rev 2Configuration 2:Installation Document List MDL-34436-5 rev 1Aircraft Flight Manual supplement 34436-AFMS-5 rev 0Maintenance Manual Supplement...	Configuration 1: limitations as per AFMS 34436-1Configuration 2: limitations as per AFMS 34436-5 and adapter NAV-550 P/N500-50000, installed by drawing 0-34280-5, must be at modificationstatus J (or later revision)Prior to installation of this change/repair it must be determined thatthe interrelatio...	21/05/2021	Active	10043626
10043627	ANUVU	REV. 2		A340-642, A340-643 A340-541, A340-542 A340-541/-542/-642/-643 A340-311, A340-312, A340-313 A340-311/-312/-313 A340-211, A340-212, A340-213 A340-211/-212/-213	Implementation of provisions of EFB Class 2Installation of provisions for detachable Electronic Flight Bag Class 2on both pilot and co-pilot stations.Rev. 2: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List AM004-MDL, Rev. 3, dated 08/02/2013-Aircraft Flight Manual Supplement AM004-AM, Rev. 1, dated 01/11/2012-Instructions for Continued Airworthiness AM004-CA, Rev. 0, dated20/08/2012-Maintenance Manual Supplement AM004-MM, Rev. 1, dated 07/11/2012or later revisions of the above listed...	The display, the software and the applications included in the deviceinstalled are not covered by this approval.This Supplemental Type Certificate is approved only for the productconfiguration as defined in the approved design data referred to in theparagraph “Description”.The installation of this m...	05/05/2021	Active	10043627
10043630	AVIATION ENGINEERING AS	REV. 2		B300	Installation of FIS UNIFIS 3000 Flight Inspection SystemTransfer from Beechcraft Berlin Aviation GmbH to Aviation Engineering	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List, Doc. No. D11-B17-09, Issue 02, dated 18-Dec-2019<(>,<) >Airplane Flight Manual Supplement, Doc. No. D30-B17-09, Issue 03, dated12-Dec-2019<(>,<) >Maintenance Manual Supplement, Doc. No. D31-B17-09, Issue 02, dated12-Dec-2019.or later revisions of the above listed document(s) appr...	For limitations see AFMS, Doc. No. D30-B17-09.Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	14/03/2023	Active	10043630
10043637	AERO-DIENST GMBH & CO. KG	REV. 1		B300	Alternate Position for ACAS and XPDR Antennas.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associated certified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Engineering Order: 265-BE.056.01 Rev. 2, or later approved revisions.Instructions for Continued Airworthiness: AG962-085 IR, or laterapproved revisions.Declaration of Compliance for Project 265-BE 08.02.2013.	Restricted to S/N FL-101, FL-130 - LBA STC SA 1356 must have beenalready installed.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upo...	21/02/2013	Active	10043637
10043650	ACC COLUMBIA Jet Service GmbH	REV. 1		O-540-J3A5	Use of Automotive Gasoline RON 98 per EN228 for Lycoming EngineO-540-J3A5D (S/N L24488-40A)Rev. 1: STC Transfer from Gomolzig Flugzeug- und Maschinenbau GmbH toACC Columbia Jet Services GmbH.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment - FAR 33 Amendment 18for the following affectedareas: 33.1 Applicability, 33.3 General, 33.5 Instruction man...	Instructions for operation, maintenance and inspection:Gomolzig Supplement to Lycoming Operator’s and Maintenance Manual SOM2027338, initial issue;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The data in the FAA TCDS E-295 remains valid, except the following:Fuels:Aviation Gasoline, 100, 100LL or 100VLL per ASTM D910, AutomotiveGasoline RON 98 per EN228 (max 1% alcohol), see Gomolzig Supplement toLycoming Operator’s and Maintenance Manual SOM 2027338, initial issue orlater approved revis...	17/01/2022	Active	10043650

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043664	MOTORFLUG BADEN-BADEN GmbH	REV. 1		A109S	Installation of Max-Viz EVS-1500 infrared camera.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The modification is compliant with the requirements of JAR 27 Amendment3 paragraphs: 25, 29, 65, 67, 141, 143,171, 173, 177, 251, 301, 303,305, 307, 341, 561, 601, 603, 6...	- RFM Supplement doc. 25105F101554-0601 Revision 0, dated 15.010.2013;or later revisions of the above listed documents approved by EASA.- Master Document List doc. 25105F101554-0109 Revision 3, dated15.01.2013;- Instructions for Continued Airworthiness doc. 25105F101554-0701Revision 0, dated 15.01.2...	None.	25/02/2013	Active	10043664
10043676	NATIONAL AIRCRAFT SERVICES, INC.		FAA STC ST02646CH	747-400F 747-200C, 747-300, 747-400 747-100, 747-200B, 747-200F	NASI Pack Flow Control System.Modification of the PneumaticAir Cycle Systems by a National AircraftService, Inc B747 Flow Control System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, NK-MDL24, Revision NCAirplane Flight Manual Supplement, NK24AFMS, Revision DICA: Maintenance Manual Supplement, NK-747-MM24, Revision AEWIS Compliance Plan NK-ER24-7, Revision Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	18/02/2013	Active	10043676
10043705	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	767-300	B767-336 TCAS change 7.1 update	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 12:CS 25.581CS 25.869CS 25.899CS 25.1301CS 25.1309CS 25.1316CS 25.1322CS 25.1351CS 25.1353CS 25.1357CS 25.1431CS 25.1529CS 25.1581CS 25.1585CS 25.1703CS 25...	Master Data ListBA-767-34-0009-MDL Issue 01or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	19/02/2013	Active	10043705
10043713	ANCRA INTERNATIONAL LLC		FAA STC ST00152LA	MD-11F	Installation of mechanical cargo loading system Main DeckInstallation of mechanical cargo loading system Part Number 81990-seriesin accordance with FAA approved Ancra International LLC Controlled DataList DL81990 Rev J (dated 9/21/2011).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ancra International LLC Controlled Data List DL81990 Rev J (dated9/21/2011) and FAA approved 29 February 2012;Instruction for Continued Airworthiness Report 8284, Rev. B, dated12/07/1998;Instruction for Continued Airworthiness Report 9548,Rev. B, dated10/26/2011;or later revisions of the above list...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This Supplemental Type Certificate is approved o...	19/02/2013	Active	10043713
10043722	DOA AESGLOBAL LIMITED	REV. 2		767-300	Introduction Of "RAVE" IFE System.Rev 2: Transfer from AESLtd. to new STC holder AES Global Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AES Ltd. Master Data List No. AES-767-2525 MDL Issue 8 dated 28 October2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	27/04/2021	Active	10043722

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043724	AIRCRAFT STRUCTURES INTERNATIONAL CORP.		FAA STC SA11115SC	CESSNA 208/208B	Installation of a Standby Flap Travel Limiting System in accordance withFAA STC SA11115SC.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements / thefollowing paragraph(s) at a later amendment: FAR 23.305(a)(b), Amdt. 45,FAR 23.1309(d)(e)(f), Amdt. 49.The requirements for environmental protection and the associate...	Master Data List ASIC208-6000-01MDL, Revision D, released September 22,2011;Instructions for Continued Airworthiness, ASIC-002ICA, Revision C,released January 6, 2012;AFM Supplement ASIC208-6000-29, Revision IR, dated December 13, 2012;or later revisions of the above listed documents approved by EAS...	The installer must determine whether this design change is compatiblewith previously approved modifications.If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.Prior to installation of th...	19/02/2013	Active	10043724
10043733	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04254AT-D	GVI (G650) G650	Installation of a Broadband Multi-Link System on GulfstreamGVI.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- FAA STC ST04254AT-D-GDL100000004<(>,<)> Revision P, dated 10 November 2021-GCD000022635, Rev –, EASA Validated Configurations List ST04254AT-D- Airplane Flight Manual Supplement GC61303M001, Revision B, dated 16January 2013-Instructions for Continued Airworthiness GC61303A001, Revision H,datedo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2022	Active	10043733
10043740	B/E AEROSPACE, Inc. - FSI		FAA STC ST01493SE	777-200/-200LR	Interior Reconfiguration[description: Installation of business class seats<(>,<)> new RH & LHclosets, fold down tables,sidewall up wash and ceiling downwash, fullspectrum, digital LED lighting system, new economy class quintuple seats& economy class double seats and all supporting interior and stru...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List, Flight Structures Document A2FS237-D01, RevisionT, dated July 19, 2010-Supplemental Instructions for Continued Airworthiness, FlightStructures Document A2FS237-D15, Revision A, dated January 6, 2005-Airplane FlightManual Supplement, Flight Structures DocumentTP2-237AFM, dat...	EASA validated version of FAA STC ST01494SE for installation of alavatory and STC ST02044NY for installation of an inflight entertainmentsystem must be installed concurrently withthis STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design...	21/02/2013	Active	10043740
10043741	ASI INNOVATION			B300	Replacement of the Universial FMS UNS-1M by the FMS UNS-1EWincludingP-RNAV capability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Service Bulletin, ASI Innovationdocument ASI-SB-B300-3400-0106, Revision 01, dated February 13, 2013;Aircraft Flight Manual Supplement, ASI Innovation document ASI-AFM-0106,Revision 0, dated October 2012;Instructions for Continued Airworthiness Supplement, ASI Innovat...	Limited to Serial Number FL-120Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.This Supplemental...	21/02/2013	Active	10043741
10043743	AIRLIFT A/S			AS 350 B, BA, B1, B2, B3	Installation of REMOVABLE EXTERNAL MOUNTDescribed in AIRLIFT A/S Design Order DO-350-25-115 Rev. 0 Dated 01 June2011.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airlift A/S Rotorcraft Flight Manual Supplement FMS-350-25-115-01 Rev. 5Dated 20 February 2013;or later revisions of theabove listed documents approved by EASA.Design Order DO-350-25-115 Rev. 0 Dated 01 June 2011;Instructions for continuedAirworthiness ICA-350-25-115-01 Rev. 3 Dated20 February 2013...	OPERATION WITH A LOAD ATTACHED TO THE REMOVABLE MOUNT MUST BE CONDUCTEDIN ACCORDANCE WITH THE APPROPRIATE OPERATING RULES FOR EXTERNAL LOADS.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design...	21/02/2013	Active	10043743

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043755	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04277AT-D	GVI (G650)	Honeywell LSZ-860 Lightning Sensor System	The Certification Basis for the original product remains applicable tothis certificate/ approval.	FAA Statement of Compliance letter 100G-13-030, dated 19/02/2013.Airplane Flight Manual Supplement GC61225M001, Revision-, dated01/11/2012.Instructions for Continued AirworthinessGC61225A001, Revision -, dated27/09/2013 or later revisionsof the above listed documents approved by EASA inaccordancet...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	22/02/2013	Active	10043755
10043757	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04253AT-D	GVI (G650)	Honeywell AIS-2000 Satellite TV System	The Certification Basis for the original product remains applicable tothis certificate/ approval.	FAA Statement of Compliance letter 100G-13-023, dated 19/02/2013Airplane Flight Manual Supplement GC61507M001, Revision-, dated26/10/2012.Instructions for Continued Airworthiness GC61507A001, Revision-, dated26/10/2012or later revisions ofthe above listed documents approved by EASA inaccordance wit...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	22/02/2013	Active	10043757
10043766	SCANDINAVIAN AVIONICS DESIGN ApS			S550 (CITATION S/II) 550 (CITATION V) 550 (CITATION ULTRA) 550 (CITATION II) 500 (CITATION I) 500 (CITATION)	Installation of Universal UNS-1Lw FMS System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Scandinavian Avionics, AFM Supplement 2080144-AM A , issue 2 dated 23January 2013Scandinavian Avionics, Continued Airworthiness 2080144-CA A, Issue 1,dated 13 December 2012Scandinavian Avionics, Maintenance Manual Supplement 2080144-MM A, issue1 , dated 13 December 2012Scandinavian Avionics, Install...	See Scandinavian Avionics AFM Supplement 2080144-AM APrior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willintroduce noadverse effect upon the airworthiness of the pro...	22/02/2013	Active	10043766
10043783	AEROTEC & CONCEPT			TB 20	Installation of a Garmin GNS 530W system, a GPS GA 35 antenna and a KindKN 62A DME	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23 Amdt. 2Thecertificated noise and/ or emissions levels of the originalproductare unchanged and remain applicable to this certifica...	Flight Manual Supplement No AE12087SMVGNS 530W, revision 0 dated02/08/2012Installation Instructions No AE12087SB, revision 0 dated 02/08/2012Instructions for Continued Airworthiness No AE12087IPMN, revision 0dated 02/08/2012Master Data List No AE12087MDL, revision 0 dated 02/08/2012or later revision...	This installation is limited to airplane TB20 S/N 1088 and it isapproved for IFR B-RNAV operations with coupling to a King KFC 150autopilot and to an Aspen EFD 1000 Pro displaySoftware upgrades introducing new functions at equipment level must bethe subject of other EASA approvals.Prior to installat...	25/02/2013	Active	10043783
10043786	AEROTEC & CONCEPT			TB20	Installation of an Aspen Evolution 2000 display system	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS-23, Amdt. 2The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certific...	Flight Manual Supplement No AE12096SMV, revision 0 dated 17/09/2012Installation Instructions No AE12096SB, revision 0 dated 17/09/2012Instructions for Continued Airworthiness No AE12096CA, revision 0 dated17/09/2012Master Data List No AE12096MDL, revision 0 dated 17/09/2012	The airplane must be equipped with standby altitude, airspeed, attitude,heading and navigation indicators independent from and not similar tothe Aspen primary display.Software upgrades introducing new functions at equipment level must bethe subject of other EASA approvals.Prior to installation of th...	25/02/2013	Active	10043786

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043842	AERODATA AG			HAWKER 750	Installation of AD-AFIS-355 consisting of operator console and equipmentconsole for Flight Inspection System (FIS) withrelated antennainstallations and installation of camera tube (GHT) in the tail cone.Along with associated modificationsto cockpit and electricalinterfaces.	The Certification Basis applicable to this certificate/ approval isdefined by:-CS 25 Amdt. 11 excluding Subpart H and with the following reversions.-25.561 FAR-25 Amdt.0 as defined on TCDS IM.A.085-25.785 FAR-25 Amdt.20 as defined on TCDS IM.A.085-25.789 FAR-25 Amdt.32 voluntarilyThe requirements fo...	Installation of Aerodata AD-FIS-355 under modification H125-3.01 asdefined in Aerodata MDL-A/C-185 Rev 2 dated 15 February 2013.Operation in accordance with Aerodata Flight ManualSupplementAFM-13 2 Rev 0 dated February 2013.Maintenance in accordance with Aerodata Aircraft Maintenance ManualSupplemen...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	28/02/2013	Active	10043842
10043852	ROEDER PRAEZISION GMBH	REV. 1		114, 114A, 114B, 114TC 112, 112B, 112TC, 112TCA	Installation of HID Xenon LDG/TAXI and LED NAV Lights.Replacement of existing installation with a new HID and LEDinstallation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, Nayak GmbH, document RC114-NY-10202, rev. 1, datedJanuary 2, 2013;Instructions for Continued Airworthiness and Installation according toNayak GmbH, document RC114-NY-10202, rev. 0, dated October 26, 2011;Aircraft Flight Manual Supplement, Nayak GmbH, documentRC114-NY-10202-08,o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/11/2017	Active	10043852
10043855	MT-PROPELLER ENTWICKLUNG GmbH			MU-2B-35, -36, -36A, 40, -60 MU-2B-20, -25, -26, 26A, -30,	Installation of 5-blade MT-Propeller Model MTV-27-1-E-C-F-R(G)/CFR(...)on MU-2B.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The following paragraph (s) at a later amendment:FAR 23.1529 Amdt. 26CS-36 Amdt.2 and FAR 36 Amdt. 28This certificate/ approval involves achange to the requirements forenvironmental protection or al...	According to MT-Propeller Master Document List No. E-2252 andMT-Propeller Installation Instructions Doc. No. E-2246 andE-2306, orlater Revisions;To be operated in accordance withMT-Propeller AFM-S Document No. E-2245and E-2305;To be maintained i.a.w. MT-Propeller ICA Document No. E-2247 and E-2307...	According limitation section of AFM-S.	28/02/2013	Active	10043855
10043864	LUFTHANSA TECHNIK AG			B747-8	NG Stretcher installation in aft area of the main deck	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:D-103 "Installation of medical stretcher in cabin"The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the originalu...	Description document STDD25-12/32M Issue 01 Rev. 00Certification Program CP25-12/32M Issue 01 Rev. 00Compliance Record List CRL25-12/32M Issue 01 Rev. 00Engineering Bulletin 747-EB25-1536 Rev 0or later revisions of the above listed documents approved by EASA	Conditions1. All equipment (stretcher, oxygen bottles, etc.) must be approvedagainst the appropriate qualification standard, if any.2. The stretcher shall provide an adequate restraining means for theperson, using such devices as a shoulder harness, the appropriate numberof body-belts and/or end boa...	01/03/2013	Active	10043864
10043876	BERINGER AERO	REV. 11		DA 40 NG DA 40 F, DA 40 NG DA 40, DA 40 D, DA 40 F DA 40, DA 40 D	Original Issue: STC-009(1) dated 04 Feb 2013 – Installationof RF-006(A)nose wheel with EA-004N brake system on DA40NG.Revision 6: Update applicability to cover all versions of DIAMOND DA40.Revision 7: DA40 – 1/4'' fitting screws + MP-001.5.DA40NG – M6 fitting screws replaced by 1/4'' screws & intro...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any i...	Modification file: DM-STC-009 REV 10 dated 11 Mar 2022Service Bulletin: SB-034 REV 1, dated 09 Dec 2024Installation andInstructions for Continued Airworthiness: ICA-STC-009REV. 08 dated 12 Dec 2024or later revisions of the above listed documents approved by EASA.	In accordance with SB-034;The approval holder shall fulfillthe obligations of Part 21, Point21.A.109.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adver...	17/12/2024	Active	10043876

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043917	RHEINLAND AIR SERVICE GmbH			MT-7-235	Installation of EDM930Installation of J.P. Instruments (JPI) Primary Engine Data ManagementSystem in accordance with JPI Installation Manual for the EDM 900/930,Report 908, dated September 9, 2004.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:CS 23 Amendment 3 forfollowing paragraphs: 23,301,601,603,611,613,771,773, 867,1301,1305,1309,1311,1321,1 351,1353,1365,143...	- Airplane Flight Manual Supplement No. 930-0001, Revision C, FAAapproved 10.12.2004;or later revisions of the above listed documents approved by EASA.- Description of Installation RAS-12-03-02-DOI-01, dated 27.1.2013 orlater approved Revisions.- Master Document List RAS-12-03-02-MDL-03, dated 7.02....	This approval shall be limited to aircraft MT-7-235 MSN 18087C.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness...	05/03/2013	Active	10043917
10043924	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		MBB BK117 B-2	Adaptation of FLIR operator desk and aft seat.In order to operate the FLIR with the long range fuel tanks (TC holderoptional installation noº801), the after seats have to be movedforwardand modified to fit in the new attachment points.Also the operator console is redesigned to fit in the availableR...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement CMA041 - FMS R0Master document list CMA041 - LMD R0Engineering bulleting CMA041 - BI R0Instructions for Continuous Airworthiness CMA041 - ICA R0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Only applicable to s/n 7176Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installedchange and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	01/02/2019	Active	10043924
10043927	TAMARACK AEROSPACE GROUP, INC.		FAA STC SA02247SE	SR20, SR22, SR22T	Cargo Conversion.Removal of rear seats and installation of cargo shelf and restraintsystem in accordance with FAA STC SA02247SE.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Removal of rear seats and installation of cargo shelf and restraintsystem controlled by Cirrus Master Drawing List (MDL) TAG-CRT-205,Revision B, dated October 23, 2012;Installation in accordance with Cirrus InstallationInstructions/ Instructions for Continued Airworthiness (ICA) SupplementTAG-CRT-201...	This STC is applicable to the following serial blocks of Cirrus Designaircraft:- Cirrus SR20: Serial Numbers 1005 and subsequent.- Cirrus SR22: Serial Numbers 0002 and subsequent.- Cirrus SR22T: Serial Numbers 0001 and subsequent.Prior to installation of this design change it must be determined that...	05/03/2013	Active	10043927
10043930	SABENA TECHNICS BGC			AS 365 N3	White Strobe Light Installation on the Underside Fuselage	The Certification Basis for the original product remains applicable tothis certificate/ approval.the following paragraph (s) at a later amendment: CS 29 Amt.2 paragraphs:29.1, 29.27, 29.29, 29.601, 29.603, 29.605, 29.607, 29.609, 29.610,29.777, 29.1301, 29.1309, 29.1351, 29.1353, 29.1357, 29.1359, 29...	Rotorcraft Flight Manual Supplement, document no. 2027-01-A-2301-R02dated 26 April 2012 or later revisions approved by EASA.Master Certification Data Sheet, document no. 2027-01-A-2115-R03 dated04 March 2013Instructions for Continued Airworthiness, document no.2027-01-A-2211-R00 dated 20 December 20...	- Modification limited to AS365N3 with Serial Numbers SN6687 and SN6690.- The use of the white strobe light system withNight Vision ImageSystems (NVIS) or Night Vision Goggles (NVG) is forbidden.- The operation of the white strobe light on the underside in cloudyconditions is forbidden.Prior to ins...	06/03/2013	Active	10043930
10043931	SABENA TECHNICS BGC			AS 365 N3	Passenger Address System Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:CS 29 Amt. 2paragraphs: 29.1,29.27,29.29,29.607,29.610,2 9.777,29.831,29.1301,29.1309,29. 1321,29.1351,29.1353,29.1357< (>,<...	Master Certification Data Sheet, document no. 2026-01-A-2115-R03,Revision 03;Instructions for Continued Airworthiness, document no.2026-01-A-2211-R02 Revision 02;Service Bulletin,document no. 2026-01-A-3101-R02 Revision 02;or later approved revisions of the above listed documents.	Modification limited to AS365N3 with Serial Numbers SN6687 and SN6690.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwort...	06/03/2013	Active	10043931

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043935	MCCAULEY PROPELLER SYSTEMS			LC42-550FG	Installation of McCauley Model D3A34C444/78MLA-0	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	According to McCauley Installation Instructions Doc. No. 969 Rev -, orlater RevisionsTo be operated in accordance with McCauley AFM-S Document No. 970, RevIRTo be maintained i.a.w. McCauley ICA Document No. 975, Rev A.or later revisions ofthe above listed documents approved by EASA inaccordance wit...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/03/2013	Active	10043935
10043936	ARMSTRONG AEROSPACE Inc.		FAA STC ST03109CH	A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-223, A330-243 A330-201, A330-202, A330-203	Certification of Compatibility with Cellular and Wireless DataTechnologies.	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Armstrong Aerospace Master Data List DC104-9209-00, Revision B dtd.14.December 2012;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bil...	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane installed base station using the cellularand/or wireless technologies is concurr...	06/03/2013	Active	10043936
10043964	MT-PROPELLER ENTWICKLUNG GmbH			DHC-6 SERIES 400 DHC-6 SERIES 300, 310, 320 DHC-6 SERIES 200, 210 DHC-6 SERIES 1, 100, 110	Installation of 4-blade MT-Propeller Model MTV-16-1-E-C-F-R(P)/CFR240-55on Viking Air Limited DHC-6	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	According to MT-Propeller Master Document List No. E-2291 andMT-Propeller Installation Instructions Doc. No. E-2294, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2293To be maintained i.a.w. MT-Propeller ICA Document No. E-2295.or later revisions of the above l...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	08/03/2013	Active	10043964
10043965	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		GA8-TC 320 GA8	MTV-9-B/200-58 on GA8 Airvan Model GA8 and GA8-TC 320	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	MT-Propeller Master Document List No. E-2217 (Rev.3)GA8 Airvan Model GA8 to be operated in accordance with MT-PropellerAFM-S Document No. E-2642GA8 Airvan Model GA8-TC 320 to be operated in accordance withMT-Propeller AFM-S Document No. E-2214or later revisions of the above listed documents approved...	According limitation section of AFM-S	09/04/2015	Active	10043965
10043973	STANDARD AERO (ALLIANCE), INC.		FAA STC ST03176CH-D	A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322	Activation for the ARINC Cabin Connect System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	-FAA Approval ST03176CH-D, dated 14/02/2013-Instructions for Continued Airworthiness DC113-9268-00, Rev. A, dated07/02/2013-Aircraft Flight Manual Supplement DC303-9268-00, Initial Release, dated14/02/02013-Master Data List DC104-9268-00, Rev. D, dated 12/02/2013-Aircraft Maintenance Manual Suppleme...	Before the installation of this STC shall be applied the following STCs:-10043526 provisions for Cabin ARINC Connect System-10043936 Compatibility with wireless and cellular data technologiesPrior to installation of this design change it must be determined thatthe interrelationship between this desi...	08/03/2013	Active	10043973

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10043975	REIMS AVIATION INDUSTRIES		TCCA SA12-74	BD-700-1A10, BD-700-1A11	Installation, Provisions for P/N 444-DMC57-1 Securaplane Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. SA12-74 Issue 1 dated 24 October 2012;ACS-NAI Ltd. Modification Data Summary number H791000 Revision N/C;Mandatory Maintenance Manual Supplement H791070 revision N/C;or later revisions of the above listed documentsapproved by EASA inaccordance with the Technical Implementat...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/03/2013	Active	10043975
10043977	ROCKWELL COLLINS, Inc.	REV. 1	FAA ST02177LA	CL-600-2B16 (604 VARIANT)	HUD/EVS Model HGS-6605 Validation on CL-605 and CL-650 aircraft.This revision is to include marketing/common designation of the CL-650on this STC in line with the Bombardier CL-600 TCDS IM.A.023.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA STC ST02177-L, dated 7th Dec. 2015;- Rockwell CollinsMaster Drawing List for Model 6605 Head-Up DisplaySystem, Doc. No. 9701-1267, Rev. P, dated 18th July 2016;- Airplane Flight Manual Supplement (AFMS) for Installation of HUD orHUDwith EFVS doc. No. 9701-1304, Rev. A;- Instruction for Conti...	The performance of the Model 6605 HUD system has demonstratedacceptability as supplementary display of primary information. The EVShas demonstrated that the EVS image does not degrade the safety of theflight or interfere with the required pilot tasks during any phase offlight. Only the configuration...	16/03/2018	Active	10043977
10044017	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR02135NY	A119/AW119MKII	Pilot and Crew Doors removed	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Rotorcraft Flight Manual Supplement Reports No.:AAC-ENG-04-046 Rev. B (FAA approved on June 30, 2005) for the A119 modelAAC-ENG-08-084 Rev. - (FAA approved on March 4, 2009) for the AW119MKIImodelor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 20...	None	08/04/2013	Active	10044017
10044028	FEDERATION FRANCAISE DE VOL A VOILE (FFVV)			STANDARD CIRRUS CS 11-75L	Winglets Retro Fitting - CS 11/75 L	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	SUPPLEMENT AU MANUEL DE VOL CIRRUS.,,docor later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2013	Active	10044028
10044029	AEROTEC & CONCEPT			DR 400/500	Installation of an EFIS Aspen EFD 1000 Pro and a Garmin GTN650 systemwith associated antennas, according to Aerotec modification n° AE12079.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement n° AE12079SMV EFD 1000, revision 0dated04/03/2013Flight Manual Supplement n° AE12079SMV GTN 650, revision 0 dated04/03/2013Instructions for continued airworthiness n° AE12079ICA revision 1 dated26/10/2012Master Data List n° AE12079MDL revision 2 dated 04/03/2013or later rev...	This STC is limited to airplane DR400/500 s/n 41.Initial installation on aircraft must be performed by authorised Aerotectechnical personnel.The installation is approved for IFR BRNAV, PRNAV, RNP approach LNAV andLPV operations.LNAV/VNAV APV Baro approach operations are not authorised.Coupling to S-...	13/03/2013	Active	10044029
10044032	DASSAULT FALCON SERVICE	REV. 3		MF50	Previous 2 main FMS UNS-1L/K with integrated GPS are replaced by two newFMS UNS-1Lw (SCN 1000.X with X ≥ 6) with integrated GPS / WAAS receiver.A third one with deactivated integrated GPS receiver can be installed (Version 2).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet DFS5687-CAS Issue C dated January13th, 2015.DFS Airplane Flight Manual Supplement N °F50-60 dated March 8th, 2013.or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/01/2015	Active	10044032

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044033	DASSAULT FALCON SERVICE			MF50	P-RNAV CapabilityTo demonstrate compliance with TGL N°10 Rev 1 concerning P-RNAVoperations "Airworthiness and operational approval for Precision RNAVoperations in designated European airspace"	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-DFS Change Approval Sheet DFS5659-CAS Issue B dated March 08th, 2013.-DFS Modification Sheet DFS5659, Issue B dated March 08th, 2013.-DFS Airplane Flight Manual Supplement N°F50-61 dated March 08th, 2013(for applicability on A/C with DFS 5687 dedicated to P-RNAV and inaddition to AFMS N°F50-060 (DF...	As per DFS Change Approval Sheet DFS5659-CAS Issue B dated March 08th,2013.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the ai...	13/03/2013	Active	10044033
10044034	DASSAULT FALCON SERVICE			MF50	COMPLIANCE WITH AC 90-100ATo demonstrate compliance with the RNAV 1 and RNAV 2 regulationdescribed in ICAO document 9613 AN/937 "Performance-based Navigation(PBN) Manual" for Falcon 50 aircraft equipped with FMS UNS-1Lw software1000.X (X≥6) according to DFS 5687 issue A or after.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet DFS5688-CAS Issue A dated March 08th, 2013.DFS Modification Sheet DFS5688, Issue A dated March 08th, 2013.DFS Airplane Flight Manual Supplement N °F50-63 dated March 08th, 2013.or later revisions of the above listed documents approved by EASA	As per DFS Change Approval Sheet DFS5688-CAS Issue A dated March 08th,2013.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the ai...	13/03/2013	Active	10044034
10044035	DASSAULT FALCON SERVICE			MF50	RNP-10 and RNP-4 capabilityTo demonstrate compliance with the RNP-10 and RNP-4 regulations forFalcon 50 aircraft equipped with FMS UNS-1Lw software 1000.X (X≥6)according to DFS 5687 issue A or after.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet DFS5689-CAS Issue A dated March 08th, 2013.DFS Modification Sheet DFS5689, Issue A dated March 08th, 2013.DFS Airplane Flight Manual Supplement N °F50-64 dated March 08th, 2013.or later revisions of the above listed documents approved by EASA.	As per DFS Change Approval Sheet DFS5689-CAS Issue A dated March 08th,2013.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the ai...	13/03/2013	Active	10044035
10044036	DASSAULT FALCON SERVICE			MF50	RNP APP CapabilityDescription as per Associated Technical Documentation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet DFS5690-CAS Issue A dated March 08th, 2013.DFS Modification Sheet DFS5690, Issue A dated March 08th, 2013.DFS Airplane Flight Manual Supplement N °F50-65 dated March 08th, 2013.or later revisions of the above listed documents approved by EASA	As per DFS Change Approval Sheet DFS5690-CAS Issue A dated March 08th,2013 and DFS Airplane Flight Manual Supplement N°F50-65 dated March08th, 2013.Prior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed...	04/04/2013	Active	10044036
10044038	ROW 44, Inc.	REV. 1	FAA STC ST2904CH	757-200, 757-300	Installation of a Row 44 Wireless Broadband System Provisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, Row 44 document No. SIE-346-703, Revision P, dated11 March 2015.- Instructions for Continued Airworthiness, Row 44 document No.SIE-407-607, Revision B, dated 02 February 2015- Instructions for Continued Airworthiness, Row 44 document No.SIE-407-609, Revision IR, dated 02 February...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/09/2015	Active	10044038

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044049	DELTA ENGINEERING CORPORATION	REV. 4	FAA STC ST02251SE	767-300	Austrian Interior Reconfiguration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):E-01: Installation of Inflatable Restraints25.307(a) - @ Amdt 125.365(g) - @ Amdt 1325.571(a)(b) - @ Amdt 1325.613(a)(b) - @ Amdt 1325.791 - @ Amdt 13...	Master Data List, Doc. No. HPD-DL-156, Rev. V, Dated 03.08.2013ICA, Doc. No. HTM1010, rev F, Dated 10.07.2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	12/12/2013	Active	10044049
10044051	B/E AEROSPACE LIMITED	REV. 1	TCCA STC SA12-40	BD-700-1A10, BD-700-1A11	Installation, Complete Custom Aircraft InteriorRevision 1 is an administrative re-issuance following a name change fromACS-NAI Limited to B/E Aerospace Limited.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 1Special Condition(s): CRI D-02 Issue 2, Side Facing DivansEquivalent Safety Finding (s): CRI D-04 Issue 2, Emergency Exit SignsDeviation(s): CRI D-01 Issue...	Transport Canada STC No. SA12-40 Issue 1, dated 08 June 2012ACS-NAI Configuration Definition Record H525001 Revision NC, dated 07June 2012ACS-NAI Airplane Flight Manual SupplementH525090 Revision NCInstructions for Continued Airworthinessdocument ICA-XXXX where XXXX isa unique identifier for eacho...	EASA approved configurations are identified in Configuration DefinitionRecord H525001.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplanes cabin using portableelectronic devices (PEDs). Any other intended function of this equipmentwil...	12/03/2024	Active	10044051
10044060	MONARCH AIRCRAFT ENGINEERING LTD	REV. 1	CAA UK RESPONSIBILITY	A321-231 A320-212/-214/-232/-233 A319-115	Installation of the Wireless IFE System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 12CS 25.1703; CS 25.1707CS 25.1709; CS 25.1711CS 25.1713; CS 25.1715CS 25.1717; CS 25.1719CS 25.1721; CS 25.1729The requirements for environmental protecti...	Monarch Design Services Flight Manual Supplement MON-23-36-3396 No. 1Issue Bor later revisions of the above listed documents approved by EASAMonarch Design Services Modification Approval DocumentMON/320/23/ MAD/3383 Issue F and all referenced documents	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2015	Active	10044060
10044062	AIRCRAFT CABIN MAINTENANCE GmbH			SEE EASA APPROVED MODEL LIST	Installation of refurbished Passenger Seat Belt P/N EPA 27511-2-01-70 on16 g seats	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Refer to Master Document List E/O No. 112-1003111 Rev. 0 (27.02.2013)or later revisions of the above listed documents approved by EASA	As per Service Bulletin No. 112-1003111 SEB 06 00, latest revisionPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthine...	14/03/2013	Active	10044062
10044063	A/C SYSTEMS L.L.C.		FAA STC SA03065CH-D	G58, 58, 58A, D055, E55, E55A	Installation of an A/C Systems Air-conditioning System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Standard Aero Master Drawing List1021376 Rev (I), dated 20 April 2012.Operation in accordance with FAA Approved Airplane Flight ManualSupplement number FTA-010-6 Rev (IR) dated 23 April 2012.Maintain in accordance with A/C Systems LLC ICA and MM Supplement refFTA-010-...	The installer must determine whether this design change is compatiblewith previously approved modifications.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will intro...	14/03/2013	Active	10044063

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044069	A/C SYSTEMS L.L.C.		FAA STC SA00257BO	2- F33A, A36 1- G36	Installation of an A/C Systems Air-conditioning System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with A/C Systems Master Drawing ListFTA-000-1 Rev C, dated 07 June 2012;Operation in accordance with FAA Approved Airplane Flight ManualSupplement number FTA-010-2 Rev (I) dated 25 April 2012;Maintain in accordance with A/C Systems LLC ICA and MM Supplement refFTA-010-3 Is...	Model F33A Applicability Serials CE-748, CE-772 and after.Model A36 Applicability Serials E1111, E-1241 through E-3635,excludingE-3630.Model G36 All Serials.The installer must determine whether this design change is compatiblewith previously approved modifications.Prior to installation of this desi...	15/03/2013	Active	10044069
10044092 (EASA.R.S.01280)	KUERZI AVIONICS AG			SA 330 J	NVIS Cockpit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement Doc. No. FMS-200717408 Rev. N/Cor later revisions of the above listed documents approved by EASAMaster Document List Doc. No. MDL-200717408 Rev. CInstructions for Continued Airworthiness Doc. No. ICA-200717408 Rev.C	Refer to applicable RFM for list of equipment mandatory forNight VisionImage System certification.Installation of NVIS/ NVG compatible lighting does not include or implyapproval for flight operations with Night Vision Goggles (NVG). Theoperator must receive approval from the Civil Aviation operation...	18/03/2013	Active	10044092
10044141	ALAMO ENGINEERING GmbH	REV. 2		CL-600-2B19	Cabin Modification to VIP.Rev. 3: transfers the STC from "Deutsche Aircraft GmbH" to "AlamoEngineering GmbH".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.1701 to CS25.1729 at Amendment 11.The requirements for environmental protection and the associatedcertified noise an...	Declaration of Compliance, Doc. No. DC-10D003Z0001, Issue Bdated20.03.2013;Master Document List, Doc. No. MDL003Z0001,Issue A dated 19.03.2013;Instructions for Continued Airworthiness, Doc. No. ICA010D259Z0001,Issue A dated 19.03.2013;AFM Supplement, Doc. No. AFMS010D043Z0001, Initial Release date...	Aircraft Serial Number 7617 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverseeffect upon the airworthiness of the product.	18/12/2023	Active	10044141
10044173	AVIONIK STRAUBING ENTWICKLUNGS GmbH			421A/421B/421C/425 402C/411/411A/414/414A/ 421/ 401/401A/401B/402/402A/ 402B/	Installation of Garmin GTS820 with GPA65 and Dual Garmin GA58, GarminGDL69, DAC GDC31, Garmin GA36, Garmin GA37 and Comant CI 490-1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amendment 3 for following paragraphs: 23.301,303, 305, 307, 365, 561, 571, 575, 603, 605, 607, 609, 611,613,771, 773, 843, 863, 867, 1182, 1301, 1309, 1321, 1322, 1...	-Flight Manual Supplement Garmin GTS820 ASR-2013-015-FMS-05.1-00, Rev. 0-Flight Manual Supplement GDC31 ASR-2013-015-FMS-05.2-00, Rev. 0or later revisions of the above listed documents approved by EASA-Instructions for Installation ASR-2013-015-IFI-10-00, Rev. 0, or laterapproved revisions-Instructi...	None	22/03/2013	Active	10044173
10044177	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	MYSTERE FALCON 900	Upgrade To Existing VIP Interior.This Rev. 1 is to amend a typographical error in "Description of Designchange".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): D-05 Glass Screens of Displays and MonitorsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels...	STC Twenty One Master Document List No. S21.MDL-1118 Initial Issue,dated 21 March 2013;Instructions for Continued Airworthiness, Jet Aviation SaintLouis Inc Instructions for Continued Airworthiness document reference14-027E061;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/03/2013	Active	10044177

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044180	BOMBARDIER INC.	REV. 1	TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-200 Issue 2, Side Facing DivansEquivalent Safety Finding(s): CRI D-500 Issue 2, Emergency Exit SignsDeviation (s):-CRI D-100 Issue 2, Doors Betw...	-Transport Canada STC No. SA04-113 Issue 1, dated 28 October 2004-ACS-NAI Configuration Definition List D954000 Revision LP, dated 07March 2013-Airplane Flight Manual Supplement G-FM25004001 Revision NC-Mandatory Maintenance Manual Supplement G-TM05104001-Instructions for Continued Airworthiness doc...	The EASA Approved Configurations are identified in ACS-NAI ConfigurationDefinition List D954000.The Wireless Local AreaNetwork (WLAN) is intended to provide internetconnectivity and email services to the airplanes cabin using portableelectronic devices (PEDs). Any other intended function of this eq...	15/04/2013	Active	10044180
10044195	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			550B	Installation of an Iridium Antenna on the top of the fuselage.According to Master Document List 2013-1-16, rev IR, dated 18 March2013.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Jet Aviation Master Document List 2013-1-16, rev IR, dated 18 March2013;Jet Aviation Maintenance Manual Supplement, 2013-1-10, Rev A, dated 06March 2013;Jet Aviation Installation Procedure, 2013-1-1, rev IR, dated 25 January2013;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/03/2013	Active	10044195
10044206	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04261AT-D	GV-SP	Installation of Airplane CompletionRevision to address novel and unusual design features associated withthe shower installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01 "Shower Installation"Equivalent Safety Finding(s):CRI D-50 "Cabin Egress and Seatencroachment."The requirements for environmental protection...	-,,FAA STC ST04261AT-D, issued 27th June 2012-,,Gulfstream Aerospace Corporation Index List GC5210005365, Revision F,dated 14th November 2013-,,GV-SP Airplane Flight Manual Supplement GC51204M006, Revision D,dated 14th November 2013-,,Instruction for Continued AirworthinessGC52801A765, Revision A, d...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	18/11/2013	Active	10044206
10044217	AVINCIS AVIATION ITALIA S.P.A	REV. 2		AB 412 EP	EMS Configuration as per Master Drawing List MDL-25-00-1213-A, revision00, dated 22 March 2013.Rev. 1 is an administrative re-issuance to reflect the recent namechange from INAER Aviation Italia S.p.A. Divisione Ala Fissa to BabcockMissionCritical Services Italia S.p.A Divisione Ala Fissa.Rev. 2 is...	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Rotorcraft Flight Manual Supplement FMS-25-00-1213-A, revision 00, dated07 March 2013;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.Instruction for Continued Airworthiness ICA-25-00-1213-A, revision 01,dated 13 March 2013.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/06/2023	Active	10044217
10044218	TENENCIA Ltd.		CAA UK RESPONSIBILITY	ISLANDER, BN2A-8, BN2A-26	Aerial Spray Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:Applicable paragraphsof BCAR Section D Issue 14 and BCAR Section K Issue 7The requirements for environmental protectionc...	Modification TEN 718, BN2A Aerial Spray Installation, Report TEN 718,Issue 3 dated 25 March 2013;Maintenance Manual Supplement, Islander BN2A, BN2 Spray System, ReportTEN 718/4, Issue 2 dated 23 March 2013;Flight Manual Supplement, Aerial Spray Installation, Report TEN 718/47,Issue 3 dated 20 Marcho...	Only non flammable and non toxic detergents are to be used in thisinstallation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	26/03/2013	Active	10044218

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044229	365 AEROSPACE DDS LIMITED	REV. 2		767-200/-300/-300F/-400ER	Introduction of Controller-Pilot Data-Link CommunicationsRev. 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Conditions:CRI F-01 Data Link Services forthe Single European SkyCS-25 Amendment 1225.601, 25.611, 25.899, 25.1301, 25.1302, 25.1307, 25.1309, 25.1321,25.1322, 25...	Aerospace Design & Engineering Consultants Ltd Flight Manual SupplementFMA-1282-084 Revision 1or later revisions of theabove listed document(s) approved/ acceptedunder the EASA system.Aerospace Design & Engineering Consultants Ltd Modification SummaryMOD-1282 Revision A	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/08/2019	Active	10044229
10044260	GAMA ENGINEERING Ltd.	REV. 1	CAA UK RESPONSIBILITY	B200CGT, B300, B300C B200, B200C, B200GT		The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): SC-F23.1353-02 (as per CRI F-58)CS 23 amdt.3 paragraphs mentioned in doc CP-1312The requirements for environmental protection and the associatedcerti...	According to GAMA Master Documents List MDL-1312 is.1 dated15-Mar-2013;To be operated in accordance with GAMA AFM-S Document FCS-1312 is. 1dated 14-Mar-2013To be maintained i.a.w.GAMA ICA Document ICA-MD835-01 is. 1, dated15-Mar-2013.or later revisions of the above listed documents approved by EASA...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The install...	08/04/2013	Active	10044260
10044281	AVIONITEC Ltd.			P210N	Removed:- Sigtronics SPA400 Intercom- King KMA 24 Audio panel- King KX 165 NAV/COM- King KLN90B GPSInstalled:- Garmin GMA 350 Intercom/Audio panel- Garmin GNS 430W NAV/COM/GPS- L-3 WX-500 StormscopeCompliance showing to AMC20-28 that the installed equipment is suitablefor RNAV (GNSS) Approaches dow...	FAR 23<(>,<)> Amdt: 16The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List: Doc. No. 2259-017, dated 20.02.13Instructions for continued airworthiness: Doc. No. 2259-015, dated30.11.12Airplane Flight Manual Supplement: Doc. No. 2259-011, dated 20.02.2013or later revisions of the above listed documents approved by EASA	S/N: P210-0134<(>,<)> HB-TCSThe approval holder shall fulfill the obligations of Part 21 §21.A118Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no advers...	02/04/2013	Active	10044281
10044319	ADAC LUFTFAHRT TECHNIK GmbH			MBB-BK117 B-2, MBB-BK117 C-1	Installation of an external mirror with electrical remote control asdefined in BK117-02441-001-LMD-00.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement BK117-02441-025-MFS Rev. 0;or later revisions of the above listed documents approved by EASA.-Master Document List BK117-02441-001-LMD Rev. 0,- Certification Programme BK117-02441-003-RCP Rev. 1,- Installation Instructions BK117-02441-004-DIN Rev. 0,- Instructions for Conti...	None.	10/04/2013	Active	10044319
10044334	AEROLITE AG	REV. 3		BELL 429 429	EMS Equipment P/N 429-0011900-501.Rev. 1 introduces a new seat mounted on an adapter featuring aswivelling function. The new seat is installed in lieu of the originalAFT LH passenger seat.Rev. 2 changes the name of the STC holder from "Aerolite Max Bucher AG"to "Aerolite AG".Rev. 3 extends the appli...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Master Document List, Doc. No. MDL-12-008 Rev. E dated May 04, 2023;Certification Program, Doc. No. CPR-19-057 Rev. B dated Apr 25, 2023;Flight Manual Supplement, Doc. No. FMS-429-0011900-501 Rev. B dated Sep15, 2021;Instructions for Continued Airworthiness included in Operations Manual,Doc. No. OPM...	S/N 57067 and S/N 57330 only.The medical portable devices, including their operation, have to beapproved and compatibility with the helicopter shall be checked by theoperator for electromagnetic interference (EMI) and radio frequencyinterference (RFI).The installation of this modification by third p...	17/05/2023	Active	10044334

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044343	KUERZI AVIONICS AG			60	Skytrac ISAT-100 SatCom & flight following system installationIn: Skytrac ISAT-100 Iridium Transceiver/GPS Receiver; DVI-250 C controlunit; CDP-250G display unit and Dual Iridium/ GPS antenna	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List Doc. No.: MDL-200931669 Rev. N/C of 03.04.2013Instr. for Cont Airworthiness ICA-200931669 Rev. N/Cof 03.04.2013or later revisions of the above listed documents approved by EASA.	S/N: allPrior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ orrepair will introduce no adverse effectupon the airworthiness of the product.	05/04/2013	Active	10044343
10044362	VIPE 21 AS	REV. 1		AS 350 B, AS 350 BA AS 350 B3 AS 350 B1, AS 350 B2	Installation of Concorde RG-350 or RG-355 Lead-Acid aircraft battery asreplacement for the original Nickel-Cadmium battery.Revision 1: Transfer of STC from AIRLIFT A/S, Førde Lufthavn, 6977Bygstad, Norway.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List DO-350-24-101, Rev. 0, date 14 February 2013;Flight Manual Supplement FMS-350-24-101-01, Rev. 1;Instructions for Continued Airworthiness ICA-350-24-101-01, Rev. 1;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/10/2025	Active	10044362
10044402	LEARJET Inc.		FAA STC ST01605LA-D	BD-100-1A-10	Installation of an executive interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:-Equivalent Safety Finding(s): D-08 issue 3, dated3/04/2013-Deviation(s):D-07 issue 3, dated 3/04/2013D-09 issue 3, dated 3/04/2013D-10 issue 3, dated 3/04/2013The requir...	-MDL HC200155000 Rev N, dated 25/06/2004-AFM supplements H-FM25285002 Rev NC dated 18/12/2003 and H-FM25285003Rev NC dated 25/06/2004-ICA200155000-IFCA-1or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis dec...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	10/04/2013	Active	10044402
10044405	DOA AESGLOBAL LIMITED	REV. 2		767-300	Introduction of Crew Rest BunksRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.Rev 2: corrected model	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01 Installation of Crew Rest CompartmentsCS-25 Amendment 11 - VariousThe requirements for environmental protection and the associatedcertifiedu...	AES Ltd Master Data List No. AES-767-2349 MDL Issue 3 dated5 April 2013AES Instruction for Continued Airworthiness No.AES-TR-1062 Issue 1or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	27/04/2021	Active	10044405
10044411 (EASA.IM.A.S.02563)	JET AVIATION ST. LOUIS, Inc.	REV. 1	FAA STC ST02574CH-D	CL-600-2B16	Installation of 40 Cubic Foot Oxygen Bottle.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST02574CH-D dated 30 January 2013.Jet Aviation St. Louis, Inc. Master Data List 41-261G001, Revision G,dated 30 November 2012.Airplane Flight Manual Supplement 41-261M001, Revision NC, dated 4 June2008.Instructions for Continued Airworthiness: 41-027E018.or later revisions of the above l...	Restricted to ASN 5701 and subsequent.If this STC is installed in conjunction with the Cabin Interior STC No.EASA.IM.A.S.02539 (FAA STC No. ST02543CH-D), the Oxygen system AirplaneFlight Manual Supplement from the STC EASA.IM.A.S.02539 must be replacedwith Airplane Flight Manual Supplement 41-261M00...	15/04/2013	Active	10044411
10044429	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			V35B, 36, A36, A36TC, B36TC M35, N35, P35, S35, V35, V35A F33A, F33C, G33, H35, J35, K35 35-C33A, E33, E33A, E33C, F33 35-33, 35-A33, 35-B33, 35-C33	STC 4022/12 Revision 1 - Installation GNS430W Privilege BRNAV aveccouplage au pilote automatique et EDM700	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Refer to the paragraphs listed on FAM at CS23 amdt.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original...	Supplement au manuel de vol EDM700 Rev. 1 du 28 janvier 2013Supplement au manuel de vol GNS 430W Rev. 1 du 28 janvier 2013or later revisions of the above listed documents approvedby EASA	The STC is approved for aircraft equipped with automatic pilot andequipment defined in GARMIN IM 190-00356-08 dated May2011 and up andSTC 4022/12 annex C2.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously i...	11/04/2013	Active	10044429

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044442	S-TEC CORPORATION		FAA STC SA5372SW-D	AA-5A, AA-5B	Installation of S-TEC system 60 Two Axis Autopilot model ST-278,according to bulletin N.378 rev.1 dated 3-Oct-1986 (FAASTC SA5372SW-D).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to S-TEC Master Drawing List N. 92313 rev. A dated 3-Oct-1986with optional Flight Director/ Steering Horizon;To be operated in accordance with S-TEC AFM-S P/N 89588 dated14-Feb-1985;To be operated in accordance with S-TEC AFM-S P/N 89588-1 dated10-Oct-1986;To be maintained i.a.w. Instructio...	The installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previ...	12/04/2013	Active	10044442
10044445	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	A330-200, -200F, -300	Introduction of VHF Comm & Satcom Antennas.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Limited Master Document List No. S21.MDL-0998 InitialIssue dated 07 March 2013;Instructions for Continued Airworthiness Supplement Manual No.S21.TEC-0370;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/04/2013	Active	10044445
10044460	MAGNETIC MRO AS	REV. 2		B747-400	Installation of Avio economy and business class seats with Lumexis FTTSIFE system.Installation of Lumexis Fiber-To-The-Screen (FTTS) In-Seat AVODIn-Flight Entertainment System on AVIO "Centaurus" Economy Class en"Perseus" Business Class seats and installation of Kid Systeme ISPS on"Perseus" Business...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Programme: 11CP117, issue 4 (18 March, 2013)-Compliance Checklist: 12CC178, issue 2 (March 2013-Compliance Checklist: 12CC179, issue 2 (March 2013)-Compliance Checklist: 12CC182, issue A (January 2013)-Instructions for Continued Airworthiness: 11CA059, issue C (26 March,2013)-Instruct...	STC applicable for B747-400 aircraft MSN 26637 and MSN 26638, to beoperated by Transaero.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effe...	19/09/2019	Active	10044460
10044463	ADAC LUFTFAHRT TECHNIK GmbH			EC 135 T2 (CPDS), EC 135 T2+. EC 135 T1 (CPDS), EC 135 T1 (CDS), EC 135 P2 (CPDS), EC 135 P2+, EC 135 P1 (CPDS), EC 135 P1 (CDS),	Installation of a FLARM	- CS 27 Amdt 2- Original Type Certification Basis Special Condition "Protection ofElectrical and Electronic Systems from High Intensity Radiated Fields"(CRI F-7, Issue 5)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product a...	- Flight Manual Supplement EC 135-02376-025-MFS-00, Rev 0orlater revisions of the above listed documents approved by EASA.- Master Document List EC 135-02376-001-LMD-00, Rev 0-Maintenance Manual Supplement/ICA EC 135-02376-023-MMS, Rev 0	None	15/04/2013	Active	10044463
10044480	GDC TECHNICS, LLC.	REV. 2	FAA STC ST11099SC	A340-541	Executive Interior InstallationThis STC installs a VIP cabin interior including VIP private area withbathroom, bedroom,majlis, conference/dining room, hallway, VIPgalley/lavatory, executive seating area, staff seating area, medicalarea and aft galleys.Revision 1 corrected typos.Revision 2 capturesl...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: ,,- Special Condition(s):- From the original aircraft Type Design :H-01 : Enhanced Airworthiness Programme for Aeroplane Systems - ICA onEWISP-1018 : Engine sustained imb...	Substantiation Reports List, ref : 538-SD-04 Revision C, dated 09September 2014Substantiation Reports List, ref : 538-SD-04-EASA Revision C, dated 12September 2014Instruction of Continued Airworthiness, ref : 538-TP-05 revision F,dated 20 September 2013EASA Aircraft Flight Manual Supplement, ref : 5...	The following modifications are prerequisites for this STC installation:- ATD/Aerocon STC, ref : EASA.IM.A.S.01635 (equivalent to FAA STCST01825LA), acoustic insulation package- ATD/ Aerocon STC, ref : 10039327, Revision 2 (equivalent to FAA STCST02361LA), airstair installation	12/09/2014	Active	10044480

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044488	LAKE CENTRAL AIR SERVICES	REV. 1	TCCA SA08-85	SEE EASA APPROVED MODEL LIST	Installation of internally mounted survey and research equipment andsupporting systems in accordance with TCCA STC SA08-85.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions iaw. Eligibility List LCA-SFW-2, Rev. 28,dated 19 July 2010Instructions for Continued Airworthiness Doc. No. LCA00610-CD Rev. 0or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral...	1. Unless otherwise specified, this approval includes the activation ofall electrical components of the survey system (re. also SA06-47).2. Applicable only to Beech B200 Series: The approval in this casecovers only the structural provisions that include the Gravimeterattachment, and Restraining Syst...	25/04/2013	Active	10044488
10044500	APTOZ EHF.	REV. 1		757-200	Communications - Data Transmission & Automatic Calling - DLink+ ACARS / CPDLC InstallationInstallation and activation ofa Spectralux DLink+ system which providesAircraft Communications Addressing and Reporting System (ACARS) /Controller Pilot Data Link Communications (CPDLC) with Air TrafficControlR...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI F-01 (Data Link Services for the SingleEuropean Sky)The requirements for environmental protection and the associatedcertified nois...	- Change/Repair Approval, Icelandair document No. CRA 757-2320-52,Revision C, dated 21 March 2013- Continued Airworthiness Instructions, Icelandair document No.CAI-757-2320-52 Revision B, 25 March 2013- Aircraft Flight Manual Supplement, Icelandair document No.AFM-757-2320-52, Revision C, dated 19 M...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10044500
10044506	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST03112CH	B747-400, B747-400F	Installation and activation of an Astronautics Corporation of AmericaElectronics Class 3 Electronic Flight Bag (EFB) System consisting of anElectronic Unit (EU) and a Display Unit (DU).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): An equivalent level of safety findinghas been made for the following regulation(s): CRI-ESF-D-01:25.773(a)(2), EFB3 installation (FAA Memo-...	ECS-207709, rev. F, Electronic Cable Specialist Master DataList<(>,<) >ECS-207678, rev A, Project Compliance Report<(>,<)>ECS-207718, rev C, AFM Supplement< (>,<)>ECS-207717, rev A, Instructions for Continued Airworthiness<(>,<) >ECS-210738,rev N/C, EASA Certification Comparison for FAA STC ST03112CH...	Information displayed on the EFB is not to be used for primarynavigation, and shall be used for reference only.This STCdoes not provide operational approval of the EFB system.Operational approval should follow the appropriate EASA approvedguidance.The class 3 EFB system is intended for hosting Type...	27/05/2013	Active	10044506
10044510	S-TEC CORPORATION		FAA STC SA08998AC-D	36, A36, F33A	Installation of S-TEC system 55/55X two Axis Autopilot model ST-582,according to bulletin N.682 rev.4 dated 15-Jan-2002 (FAA STCSA08998AC-D).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,According to S-TEC Master Drawing List N. 92761 rev.D dated15-Jan-2002;-,,To be operated in accordance with S-TEC AFM-S P/N 891156 dated13-Apr-1995 and AFM-S P/N 891156 rev.1 dated 20-Mar-2001 and AFM-S P/N891156 rev.2 dated 18-Jan-2002in respect of the limitations of thiscertificate;-,,To be ma...	-,,For Beech model F33A, eligibility is limited to S/N CE-316 and up;-,,Also eligible to models 36, A36 and F33A S/ N CE-316 and up whenmodified per STC SA153EA;-,,Also eligible to models 36, A36 when modified per STC SA5223NM;-,,AFMS P/N 891156 dated 13-Apr-1995 is required for model 36, A36 andF33...	17/04/2013	Active	10044510
10044536	SABENA TECHNICS BGC	REV. 2		A321-271NX/-272NX A321-271N/-272N A321-251NX/-252NX/-253 NX A321-251N/-252N/-253N A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Mechanical and electrical provision installation for Personal TabletComputer.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-25 at amendment 18paragraphs: 1, 27, 29<(>,<)> 251, 301, 303, 305, 307, 321, 337, 341,561, 571, 601, 603, 605, 607, 60...	Master Data List: 0621-01-A-2103-R02Instructions for Continued Airworthiness: 0621-01-A-2211-R06AFMS: 0621-01-A-AFMS-R00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/12/2019	Active	10044536

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044546	APTOZ EHF.	REV. 3		757-200/300 757-200/-300	Installation of Thales Integrated Electronic Stand-by Instrument (IESI,V2 Family 2) P/N C16786AAA01 or P/N C16786AAA02.Rev. 3: change of Holder, FAA Original STC number removed, Title andtechnical documentation revision updated.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. Master Document List (MDL) Document number GR0002-MDL, Rev H, datedOctober 10, 20162. Aircraft Flight Manual Supplement (AFMS) Document number GR0037-AFM,Rev B, approved on November 28, 20163. Instructions for Continued Airworthiness (ICA) Document numberGR0010-ICA, Rev B, dated March 25, 20154.G...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/10/2025	Active	10044546
10044552	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 2		369D, 500N	Installation of HELICOM V2 ANA Embedded UMS Equipment.Rev. 1: Extension to model MD369D.Rev. 2: STC holder name change from I.S.E.I International Services toSAFRAN ELECTRONICS & DEFENSE BUSINESS UNIT - HELICOPTERS DATA MANAGEMENTSOLUTIONS & SERVICES.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): MDHI 500N<(>&<)>369D HV2 ANA - CRI F-01 “LithiumBattery Installation” at Issue 3 dated02/05/2018.- The following paragraph(s) at a later amendment...	N11-MD500-369-HV2 ANA-Rotorcraft Flight Manual Supplement-E-A-01 dated06/04/2018<(>,<)>or later revisions of the above listed documents approved by EASA.Initial Issue:Certification Programme: N2-MD500-HV2-ANA (E-A-03)ICA: N8-MD500-HV2 ANA (E-A-03) Rev.1:N10-MD500-369-HV2 ANA-LIST OF DOCUMENTS-E-A-03N...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2020	Active	10044552
10044567	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	421C	Structural Provisions of NELS Antenna Installation in accordance withCAeM/ Cessna/1360	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 23 Amdt. 23-34:23.21(a); 23.29(a), (b); 23.45(b); 23.141, 23.173; 23.251; 23.303;23.305(a), (b); 23.307(a); 23.333(a), (d); 23.603(a), (b); 23.605(a);23.609(a), (b); 2...	Installation Instructions CA/DD/SB1360Pilot Operating Handbook Supplement No. 8, issue 1Instructions for Continued Airworthiness CA/DD/SB1360or later revisions of the above listeddocuments approved by EASA	Limited to Serial Number 421C-0699 and 421C-0603The installer must determine whether this design change is compatiblewith previously approved modifications.If the holder agrees topermit another person to use this certificate toalter the product, the holder shall give the other person writtenevidenc...	19/04/2013	Active	10044567
10044570	STERLING AVIATION TECHNOLOGIES Inc.		PMA APPROVAL PQ2158NM	PA-38-112	Approval of PMA P/N SA12001 (replacing P/N 77553-05) - Vertical finAttach plate between Vertical Fin Forward Spar to a Fuselage Bulkhead(PMA approval PQ2158NM - as per FAA PMA letter dated July 27 2005).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	PMA approval PQ2158NM - as per FAA PMA letter dated July 272005;Drawing n. SA12001;To be maintained according to ICA valid for P/N 77553-05;or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/U...	Lifetime limit of this part is 5000h as detailed in the approved FAAdocumentation shipped with the part.The approval holder shall fulfill the obligations of Part 21, Point21.A.118Prior to installation of this design change it must be determined thatthe interrelationship between this design change an...	19/04/2013	Active	10044570
10044593	GROWING ENGINEERING PARTNERS GmbH	REV. 2		A340-313	THT A340 Cabin & IFE RetrofitThe change consists out of:Cabin layout:- Removal of all passenger seating and installation of new Business andEconomy seats.- Removal of some monuments and installation of new build galleys,stowages & Partitions.- Rework of Cabin, including ceiling panels and side wallS...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SCD-1322-002The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Document List, Doc. No. S.OAED.000046-MDL, Rev. 01, dated15.05.2013- AFMS, Doc. No. S.OAED.000046-AFM01, Rev. 00, dated 25.03.2013- AFMS, Doc. No. S.OAED.000046-AFM02, Rev. 00, dated 28.03.2013- ICA, Doc. No. S.OAED.000046-ICA, Rev. 01, dated 09.04.2013- ICA, Doc. No. C.OAED.000175-ICA, Rev...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/04/2021	Active	10044593

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044596	AERSOLUTION GmbH			AW109SP	Quick change patient evacuation system - The installation is identifiedby the p/n 109INS-2520001. It consists in an interior modification withEMS.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	109AST-FMS-001-A RFM Supplementor later revisions of the above listed documents approved by EASA.109AST-CPL-001-E Certification Plan109AST-DOC-001 Declaration of Compliance (dated18 April 2013)109AST-MDL-001-D Master Document List109AST-ICA-001-A Operation& Maintenance Manual	The compatibility of the "Quick Change Patient Evacuation System" withother previously approved kit must be determinateby the installer.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design cha...	22/04/2013	Active	10044596
10044632	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	EC135 T2 (CPDS), EC135 T2+. EC135 P2 (CPDS), EC135 P2+,	Installation of Ultraforce 350 Camera	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- RFM Supplement N°62 – Ultraforce 350 Camera Turret on LowLandingGear, Issue 1or later revisions of the above listed documents approved by EASA.- Design Report N° DR/ 1352065-001, Issue B, dated 11 April 2013.- Instructions for Continued Airworthiness Report N° ICAW/1352065-001,Issue A, dated 25 Ma...	- Installation is limited to helicopters with low landing gearconfiguration.- The following Eurocopter Deutschland changes have to be embodied:E-1343, E-1482, E-1720, E-2144	25/04/2013	Active	10044632
10044644	TELEDYNE CONTROLS, LLC	REV. 2	FAA STC ST01805LA	767-200/-300/-300R/-400ER 767-200/-300/-300F/-400ER	Installation of Wireless Ground Link - Quick Access Recorder (WQAR)Rev. 1: STC holder's name amended.Rev. 2: Correctionof FAA STC Reference	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Teledyne Controls Master Data List, MDL 2243800-767, Revision A, 29/04/2005or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or theTechnical Implementation Procedures of EU/USA Bilateral Agre...	None	18/01/2023	Active	10044644
10044655	APTOZ EHF.	REV. 3		757-200, 757-300	Installation of Avio Seats, Zii Rave IFE and Astronics ISPSRev. 2: Applicability extended to 757-300Rev. 3: Transfer ofSTC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Paragraphs listed in CCL-757-2520-454Rev A at CS 25 Amendment 12.The requirements for environmental protection and the associatedcertified noise and/ or emis...	- Change/Repair Approval, Icelandair document No. CRA-757-2520-454,Revision D, dated 07 December 2016- Continued Airworthiness Instructions, Icelandair document No.CAI-757-2520-454, Revision C dated 04 August 2016- Aircraft Flight Manual Supplement, Icelandair document No.AFM-757-2520-454, Initial R...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10044655
10044656	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	A330-300	Installation of a Galley and associated ceiling panels intoan AirbusA330-300 to be operated by Delta.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AIM Aviation Ltd. Definition Document No. DD 1209 Issue NewDated28/03/13or later revisions of the above listed documents approved by EASA	None	26/04/2013	Surrendered	10044656

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044684	CONCORDE BATTERY CORPORATION		FAA STC ST00732DE	328-100	Replacement of original equipment nickel cadmium batteries with ConcordeModel RG-380E/44LS Lead Acid batteries.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Concorde Battery Corporation MasterDrawing List ref 5-0353, Revision B, dated September 15,2011.Operation in accordance with Concorde Battery Corporation FAA ApprovedFlight Manual Supplement ref 5-0354, Revision B, dated August 15,2011.Maintain in accordance with Co...	This modification has been reviewed and it has been determined that itdoes not necessitate a revision to the EWIS ICA that was required to bedeveloped by CRI H-1.	29/04/2013	Active	10044684
10044690	AERO MEDICAL PRODUCTS Co. Inc.		FAA STC SA1130GL	CESSNA 441	Installation of EMS stretcher system using installation kit 801,including oxygen system 807, inverters and pump kit 812 inaccordance with FAA STC SA1130GL.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation and Operating Instructions, Form EA 109K, dated April 23,2001Installation and Operating Instructions, FormEA 170, dated June 9, 2001Aircraft Flight Manual Supplementdated April 18, 2005Aircraft Maintenance Manual Supplement,Form 107, Rev 2 dated January15, 2013or later revisions of t...	Prior to the first flight of each modified aircraft, and after eachchange to any of the Communication, Navigational, orMed Pack equipment,a ground EMI test must be conducted in accordance to EA Form 173, datedNovember 15, 1993 or later FAA approved revisions. A copy of EA Form 173must be kept withT...	29/04/2013	Active	10044690
10044692	AIRBUS S.A.S.	REV. 1		A319-115	Airbus Corporate Jet Centre Modification CJ0900 - VIP Project "UAE - EMIRATES"Revision due to AFMs and MPDs updates	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A-4301-011 "ACJC Project Certification Basis".Special Condition(s):CRI E-21 - Isolated CompartmentCRI D-0314-000 - Shower InstallationCRI H-01C...	-Modification Approval Sheet, ref.: CJ0900, Issue 2, dated 11th June2014- Airplane Flight Manual - AFM Supplement, ref.:FM-S MOD CJ0900, dated1st May 2014-Maintenance Planning Document - MPD Supplement, ref.: MPD-S MOD CJ0900,dated 1st May2014or later revisions of the above listed documents approve...	This STC is limited to MSN 4822.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	12/06/2014	Active	10044692
10044694	B/E AEROSPACE, Inc.	REV. 3	FAA STC ST03983AT	777F. 777-300, 777-300ER, 777-200, 777-200LR,	Installation of the Cobham HGA-7001 High Gain SATCOM Antenna Sub-System[DESCRIPTION: Removes and Replaces the existing Canadian MarconiCMA-2102High Gain SATCOM antenna with the Cobham HGA-7001 antenna]Revision 3 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List (MDL), EMTEQ document 2-106975-001, Revision B,dated September 19, 2012- Instructions for Continued Airworthiness (ICA), EMTEQ document2-106975-803, RevisionC, dated September 19, 2012<(>,<) >or later revisions of theabove listed documents approved by EASA inaccordance with EA...	None	02/03/2016	Active	10044694
10044695	SPECIALIST AVIATION SERVICESLIMITED	REV. 1	CAA UK RESPONSIBILITY	MD 902 WITH PW 260E & 207E	Rev. 0 – MD902 NVIS (PAS/MOD/ 669).Rev. 1 – Addition of white phosphorous Night Vision Goggles inaccordance with SAS/MOD/800	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-27 Amdt.2; 1, 301,303, 305, 307, 321, 337, 341, 561, 601, 603, 605, 609, 610, 611, 613,771, 773, 777, 853, 1301, 1307,1...	Revision 0-Flight Manual Supplement FMS/669-002 Issue Cor later revisions of the above listed documents approved by EASA.-Design Report, DR/669-001 Issue A-Compliance Checklist CCL/669-003 Issue A-ICA MPS/669-008 Issue BRevision 1. For SAS/ MOD/800 only:-Certification Plan CP/800-001 Issue A-Complian...	Installation of NVIS/NVG compatible lighting does not include or implyapproval for flight operations with Night Vision Goggles (NVG). TheOperator must receive approval from the civil aviation operationalauthority to operate with NVG.Rotorcraft modified by this STC employs Night Vision Imaging System...	02/03/2017	Active	10044695

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044696	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	EC 635 T1 (CPDS), EC135 T2 (CPDS), EC 635 T2+ EC135 T1 (CPDS), EC 635 P2+ EC135 P2 (CPDS), EC135 T2+ EC135 P1 (CPDS), EC135 P2+	Trakka Searchlight on NVIS EC 135	CS 27 Amendment 3The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS/076-002, Issue 1or later revisions of the above listed documents approved by EASA.- DesignReport DR/076-001, Issue 4- Modification Leaflet & Certificate of Design BOND/MOD/076, Issue 4- Instructions for Continued Airworthiness ICA/076-012, Issue 2	None	30/04/2013	Active	10044696
10044711	DAO AVIATION A/S			M20C, M20E, M20F, M20J, M20K	Installation of Electric Flight Display, Aspen EFD 1000 Pro.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DAO Aviation A/S, Design order Package DAO-DO-0490-DOP-00, date20-09-2012 ;DAO Aviation A/S, AFM-supplement DAO-DD-0490-AFMS-00, Rev. IR, date20-09-2012 ;or later revisions of theabove listed documents approved by EASA.	None	30/04/2013	Active	10044711
10044717	ALAMO ENGINEERING GmbH	REV. 3		GIV	Cabin Refurbishment with LOPA Change, Cabin Lighting, CabinPower SupplySystem, and new In-Flight Entertainment.Revision 1 (10044717): 328 DESIGN GmbHRevision 2: Transfer to 328 SUPPORT SERVICES GmbHRevision 3: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation in accordance with 328DO Engineering Order EO-16H259Z0001and Master Data List ref MDL002Z001 Issue A dated29 April 2013;Operate in accordance with 328DO Flight Manual Supplement refAFM016H043Z0001 Initial Release, dated 29 April 2013;Maintain in accordance with 328DO ICA ref ICA016H259...	Limited to aircraft Serial number 1027.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10044717
10044718	AMTECH AERONAUTICAL LIMITED		TCCA STC C-LSA07-157/D	BD-700-1A10	Miscellaneous Avionics and other Modifications	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. C-LSA07-157/D Issue 1 dated 09 May2009.Bombardier Aerospace Master Document List BAS67017019 Revision NC dated09 May 2007.or later revisions of the abovelisted documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agree...	Restricted to ASN 9003	30/04/2013	Active	10044718
10044719	SCANDINAVIAN AVIONICS DESIGN ApS			S550 CITATION S/II 550 CITATION II 550 CITATION BRAVO	Stand-alone AVIATOR 300 Satcom system installation as identified inEngineering Order 2072808-EO	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Scandinavian Avionics, AFM Supplement 2072808-AM, issue 1 dated 06 July2012;Scandinavian Avionics, Continued Airworthiness 2072808-CA, Issue 2,dated 09 November 2012;Scandinavian Avionics, Maintenance Manual Supplement 2072808-MM, issue 2,dated 14 September 2012;Scandinavian Avionics, Drawing List,...	See Scandinavian Avionics AFM Supplement 2072808-AM	30/04/2013	Active	10044719

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044728	MAXIMUM PERFORMANCE INC		FAA STC SE7734SW	O-540-A/B/E/F/G/H/J/L SERIES IO-540-C/-D/-J/-N/-R/-T SERIES AEIO-540-D SERIES	Modification of engine for operation with ethanol fuel in accordancewith Airmotive Engineering Report No. 9003-8, Revision 2, dated March12, 1990, and Drawing. No. AE077, "Engine Modification Data", Revision3, dated March 8, 1990, for the Lycoming IO-540 series engines; orReport No. AVS O-540-001, d...	The Certification Basis for the original product remains applicable tothis certificate/ approval.	Airmotive Engineering Report No. 9003-8, Revision 2, dated March 12,1990, and Drawing. No. AE077, "Engine Modification Data", Revision 3,dated March 8, 1990, for the Lycoming IO-540 series engines; or ReportNo. AVS O-540-001, dated September 15, 1997, for the Lycoming O-540series engines, or later F...	Approved fuels are as follows: (1) Ethanol, ASTM D4806,(2) Ethanol, Brazil National Department of Fuels, Technical RegulationDNC-01/91, Specification for Anhydrous Fuel Ethanol (”AEAC”) or HydrousFuel Ethanol (“AEHC”), (3) Ethanol, EN 15376<(>,<)> (4) Aviation Gasoline 100LL, ASTM D910 or Def Stan 91-9...	02/05/2013	Active	10044728
10044745	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		A321-231	Cabin Interior modifications and In Flight Entertainment installation onDragon Air.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan N0405-D01 Rev. B, dated 20/02/2013- Certification Plan N0452-D01 Rev. -, dated 25/10/2013- Certification Summary N0405-D90 Rev. A, dated 02/05/2013- Certification Summary N0452-D90 Rev.-, dated 24/03/2014- Master Drawing List N0405-D10 Rev. L, dated 24/03/2014- Instructions for2...	The approval is limited to MSN 993, MSN 1024, MSN 633, MSN 1695, MSN1984, MSN 2021, MSN 3369 and MSN 3669.Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpreviously installed design change and/ or repair will introdu...	27/03/2014	Active	10044745
10044749	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC SA4839NM	757-200, 757-200PF	Installation of the ACSS TCAS system [description: Installation and activation of ACSS TCAS Change 7.1software and deactivation of the ACSS TCAS Change 7.0 software]	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Master Data List, Honeywell document No. ML4070373, Revision F, dated24 July 1990 ;- Aircraft Flight Manual Supplement, Honeywell document No. 5140-0885,approved on 14 July 1990;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or sub...	None	03/05/2013	Active	10044749
10044760	AEROSPACE DESIGN AND CERTIFICATIONLIMITED		CAA UK RESPONSIBILITY	A330-243	Installation of new Avio E-Biz BC Seats, Weber EY Seats, and IMS RaveIFE System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, ref : JN424 ADC17 Issue 1Instruction for Continued Airworthiness, ref : JN424 ADC54-25 Issue 1Weight and Balance Report, ref : JN424 ADC20 Issue 1or later revisions of the above listed documents approved by EASA,,,,,,	None	03/05/2013	Active	10044760
10044763	LEARJET Inc.		FAA STC SA8159NM-D	CL-600-2B16 (CL-604)	Installation of a L/H Fwd Storage Cabinet	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. SA8159NM-D dated 29 April 1999.Bombardier Completion Center Master Drawing List No. CA-3079a-TUC,Revision Bdated 26 April 1999.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)” and/U...	None	06/05/2013	Active	10044763

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044765	LEARJET Inc.		FAA STC SA8094NM-D	CL-600-2B16	Installation of Cabinets and Galley	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. SA8094NM-D dated 03 May 1997.Bombardier Completion Center Master Drawing Lists:,,,,,,,,Revision,,Date,,CA-3058d-TUC,,,,C,,,,06 February 1999,,CA-3060d-TUC,,,,C,,,,06 February 1999,,CA-3061d-TUC,,,,C,,,,06 February 1999,,CA-3065d-TUC,,,,C,,,,06 February 1999,,CA-3066d-TUC,,,,C,,,,06 Febru...	This approval is for installation of structural provisions only. Theinstallation of electrical, plumbing and ECS components must beseparately approved.	06/05/2013	Active	10044765
10044766	LEARJET Inc.		FAA STC SA8073NM-D	CL-600-2B16	Installation of Cabinets and Galley	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. SA8073NM-D dated 14 April 1997.Bombardier Completion Center Master Drawing Lists:,,,,,,,,Revision,,Date,,CA-3060b-TUC,,,,D,,,,16 March 1999,,CA-3061b-TUC,,,,G,,,,16 March 1999,,CA-3062b-TUC,,,,F,,,,16 March 1999,,CA-3064b-TUC,,,,F,,,,16 March 1999,,CA-3065b-TUC,,,,G,,,,16 March 1999,,CA-...	This approval is for installation of structural provisions only. Theinstallation of electrical, plumbing and ECS components must beseparately approved.	06/05/2013	Active	10044766
10044769	NSE	REV. 1		AW139 AW 139	Installation of Night Vision Image system (NVIS) Lighting system forAW139 helicopter.Revision 1: Transfer of certificate to new holder.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement: FMS-139-33-101-01, Rev 0, dated 14 March 2013.Design Order: DO-139-33-101. Rev. 0, dated 3 December 2012.Instructions for Continued Airworthiness: ICA-139-33-101-01, Rev.0 dated12 March 2013.Master Document List: DO-139-33-101, Rev 1 dated 10 April 2013.or later revisions o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Initial issue- Installation of NVIS Kit or NVIS/NVG com...	16/07/2025	Active	10044769
10044814	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02949CH	B737-600/-700/-800/-900/-900ER	Installation of a Rosemount Aerospace 8700E1 Class 3 Electronic FlightBag (EFB) System. - Approved configurations are the following:- Configuration 1: Installation of Dual SDU electrical power withcrosstalkcapabilities between the two units<(>,<)>- Configuration 2: Installation of Dual SDU and EFB-I...	The Certification Basis for the original product and the EWIS CRI H-01at issue 3 dated 20 August 2012.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Certification Plan, ECS-209047, Revision G, dated 27 April 2011- Project Compliance Report, ECS 209073, Revision D, dated 02 June 2011- EASA Certification Comparison for STC ST02949CH ECS-210104, RevisionB, dated 04 January 2013- Master Data List, ECS-209048, Revision L, dated 13 March 2013- EASA-...	Limitations:1) The aircraft operator must perform the instructions for continuedairworthiness as per the document ECS-209658, Revision A, dated 25 April2011.2) Information displayed on the Electronic Flight Bag is not to be usedfor primarynavigation, and shall be used for reference only.3) The USBa...	07/05/2013	Active	10044814
10044818	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	737-300	Introduction of replacement ELT Antenna P/N 2624-82-(XX) onto repairedfuselage crown skin FS837, STR1 to 2R:- configuration 1: Artex 110-328-01 fixed ELT antenna removal prior toinstallation of replacement antenna- configuration 2: CEIS 9260065 fixed ELT antenna removal prior toinstallation of repla...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance checklist S21.CCL-1129 Issue 2;Master Document List S21.MDL-1129 Issue 3;Compliance record S21.COMP-1129 Issue 2;Technical Report S21.TREP-0722 Issue2;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/11/2017	Active	10044818

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044834	LEARJET Inc.		FAA STC ST00097WI	CL-600-2A12, CL-600-2B16	Storage Cabinet, LH Aft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST00097WI dated 7th October 1996;Learjet MasterDocument List No. CA-1026-TUC Revision C dated 7th July1993;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Impl...	This approval is for installation of structural provisions only. Theinstallation of electrical, plumbing and ECS components must beseparately approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously instal...	08/05/2013	Active	10044834
10044835	LEARJET Inc.		FAA STC ST00046WI	CL600-2A12, CL-600-2B16	Installation of Left Hand Forward Wardrobe Cabinet	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST00046WI dated 7th October 1996;Learjet MasterDocument List No. CA-1022-TUC Revision G dated 27th July1993;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Imp...	This approval is for installation of structural provisions only. Theinstallation of electrical, plumbing and ECS components must beseparately approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously instal...	08/05/2013	Active	10044835
10044836	LEARJET Inc.		FAA STC ST00044WI	CL600-2A12, CL-600-2B16	Pullout Table and Sideledge	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST00044WI dated 7th October 2006;Learjet MasterDocument List No. CA-1023-TUC Revision E dated 7th July1993;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Impl...	This approval is for installation of structural provisions only. Theinstallation of electrical, plumbing and ECS components must beseparately approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously instal...	08/05/2013	Active	10044836
10044839	DELTA ENGINEERING CORPORATION		FAA STC ST03168NY-D	737-800, 737-900. 737-600, 737-700,	Installation of Bruce Aerospace cabin lighting.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List 0106-08443-2340 dated March 26, 2013.Instructions for continued airworthiness (ICA) and EWIS ICA0706-08390-2340 Rev A, applicable to configuration 1 (BR9542 and BR9545) and to configuration 2 (BR9542 and BR9543).or later revisions of the above listed documents appr...	None	10/05/2013	Active	10044839
10044847	SECURAPLANE TECHNOLOGIES, Inc.	REV. 1	FAA ST01471LA-D	SEE APPROVED MODEL LIST	Installation of Hawker PN 9750W0370 Series 24Volt/43Amp-hour SealedLead-Acid Battery	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA STC FAA ST01471LA-D, reissued 6th October 2004, with FAA ApprovedModel List (AML) AML-ST01471LA-D at Revision G- FAA Approved Master Data List (MDL) ref doc. 170-0404-01, Revision E(for Cessna Citation Series Aircraft)- CertificationData List (CDL), ref. doc. 170-0411-01, Revision D (forCessn...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/11/2014	Active	10044847

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044859	AEROTEC & CONCEPT			DC-9-83 (MD-83)	Cabin modification and refurbishing. Refurbishing of the cabin andaddition of a VIP private salon; updating airshow system; replacement ofthe path-marking system by a fluorescent one.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special conditions:D-01 Glass screen of display-monitorsD-04 Isolated compartmentsH-01 Enhanced airworthiness programme for aeroplane systems - ICAs onEWISDeviations:D-02D...	Master Data List AE12056MDL Rev. 2 dated 08.05.2013Master Drawing List AE12056MDWL Rev. 0 dated 06.05.2013Airplane Flight Manual Supplement AE12056AFMS Rev. 1 dated 08.05.2013Instruction for Continued Airworthiness AE12056ICA Rev. 2 dated15.04.2013or later revisions of the above listed documents app...	DC-9-83 (MD-83) Serial Number 49809	10/05/2013	Active	10044859
10044860	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	757-200	Installation of Astronics EmPower ISPS system[Installation of Astronics EmPower ISPS system for European AviationC2C20755 seats into B757-200 aircraft]	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:In addition to the original certification basis specified by TCDSEASA.IM.A.205 the applicant has demonstrated compliance with CS-25Amendment 7 pertaining to 25.29(a); 25.3...	- Modification Summary and Declaration of Compliance, H4 Aerospacedocument No. H4A1483, Issue 5, dated 10 May 2013- Aircraft Maintenance Manual Supplement, H4 Aerospace document No.H4AMS071, Revision 4, dated 10 May 2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/05/2013	Active	10044860
10044866	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			LEARJET MODEL 45	ISAT Satcom Antenna Installation (Reference: Master data list Doc. No. 5240-049)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: JAR 25 Change 13CRI special condition A10The requirements for environmentalprotection and the associatedcertificated noise and/ or emis...	ICA Instruction for Continued Airworthiness Doc. 5240-085ALS mandatory structural inspection requirement) Master data list Doc. No. 5240-049or later revisions of the above listed documents approved by EASA.	None	14/05/2013	Active	10044866
10044868	DIAMOND UPGRADES, L.L.C.	REV. 1	FAA SR01180LA	412	PART 1: INSTALLATION OF PRATT<(>&<)>WHITNEY CANADA PT6T-3DFTWIN-PACPOWER PLANT WITHOUT INCREASED PERFORMANCE CAPABILITY.PART 2: INSTALLATION OF PRATT<(>&<)>WHITNEY CANADA PT6T-3DF TWIN-PACPOWER PLANT AND INSTRUMENT CHANGE WITH INCREASED PERFORMANCE CAPABILITY.This STC allows for removal of the P<(>...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement for Bell Model 412 RFM AU-412010423Rev. 4 Dated July 31st, 2014 or later revisions of the above listeddocuments approved by EASA in accordance with EASA ED Decision2004/04/CF (or subsequent revisions of this decision) and/ or theTechnical Implementation Procedures...	- PART 1: Refer to the basic Bell RFM. Same performance and limitationsas the previously installed PT6T-3B, -3BE, -3BF, -3BG engine.- PART 2: Refer to RFM Supplement AU-412010423for increased OEIperformance of the PT6T-3DF with the appropriate engine instruments andmarking installed.- Airworthines...	24/06/2015	Active	10044868
10044880	AIRCRAFT CABIN MAINTENANCE GmbH	REV. 1		2. 737-800/-900/-900ER 2. 737-400/-500/-600/-700 2. 737-100/-200/-200C/-300 1. A321-212/-213/-231/-232 1. A321-111/-112/-131/-211 1. A320-232/-233 1. A320-215/-216/-231 1. A320-111/-211/-212/-214 1. A319-115/-131/-132/-133 1. A319-111/-112/-113/-114 1. A318-111/-112/-121/-122	Installation of refurbished Passenger Seat Belt P/N EPA 20031-2-01-60and EPA 20031-2-01-33 on 16g seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Refer to Master Document List E/O No. 116-1003350 Rev. 1 (08.10.2013)or later revisions of the above listed documents approved by EASA.	As per Service Bulletin No. 116-1003350 SEB 06 01, latest revision.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthin...	28/10/2013	Active	10044880

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044889	LEARJET Inc.		FAA STC ST2028LA	BD-700-1A-10, BD-700-1A-11	Installation Aviation Communication & Surveillance Systems (ACSS) TCAS2000 Computer Unit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST02028LA dated 17 December 2012.Learjet Inc. Master Data List (MDL) BAS67010058, Revision NC, dated 17December 2012.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Tech...	This modification applies to airplanes equipped with the Honeywell/ACCTCAS 2000 system only. The incorporation of Aviation Communication &Surveillance Systems (ACSS) Service Bulletin 8008229-001 (FAA AD2012-02-08 refers), in its entirety with no deviations, at Revision 02dated 28 June 2011, is a co...	15/05/2013	Active	10044889
10044895	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01926LA-D	GV-SP	Installation of 16-Passenger Cabin Interior with one additional crewseat.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-50 Cabin Egress and Seat encroachment.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original produc...	-,,FAA STC ST01926LA-D, dated 27th February 2007-,,Gulfstream Aerospace Corporation Index List GC520008555, Revision G,dated 27th February 2007-,,GV-SP Airplane Flight Manual Supplement GC52000M039, originalrelease, dated 27th February 2007.-,,Instructions for Continued Airworthiness GV-SP (G550) /G...	This approval is limited to only the installation made in GulfstreamModel GV-SP Serial No. 5129.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadver...	15/05/2013	Active	10044895
10044903	TASS Inc.		FAA STC ST00970SE-D	737-700	Installation of avionics equipment according to Virgin (VOZ) fleetstandards.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	GOODRICH Master Data List (MDL) 2002-167 Rev C Dated August19th, 2002GOODRICH Supplemental Instructions for Continued Airworthiness (ICA) D2002-205 dated July 01st, 2002TASS EU Certification Plan C737-00-0340-CP-01 dated April 23rd, 2013or later revisions of the above listed documents approved by E...	A copy of this certificate and GOODRICH MDL 2002-167 rev C dated August19th, 2002 (or later approved version) must be maintained as part as thepermanent records for the modified aircraft. The supplemental ICAGOODRICH D2002-205 dated July 01st, 2002 (or later approved version) must be incorporated in...	16/05/2013	Active	10044903
10044906	PENTASTAR AVIATION, L.L.C.		FAA ST01966CH	GIV, GV, GV-SP G-1159, G-1159A, G-1159B	Installation of provisions for dual CMC Electronics -CMA-1100 PilotViewTM Electronic Flight Bag (EFB) system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,FAA STC FAA ST01966CH, reissued 14th January 2008-,,Pentastar Aviation Top Level Report No. 03TL-004, Revision J, dated10th January 2008-,,FAA Approved Airplane Flight Manual Supplement No. 05AFM-017 RevisionB, dated 7th October 2009-,,Instructions for Continued Airworthiness No. 05CA-007, Revisi...	Compatibility of this design change with previously approvedmodifications must be determined by the installer.The equipment for which these provisions are intended has not beencertified. Additional EASA approval is required for the installation ofthis equipment and must be evaluated to assure satisf...	16/05/2013	Active	10044906
10044909	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	737-800	Introduction of SatLINK antenna in accordance with ArcheionHoldingsLLC. Iridium Antenna Installation Subkit 2604773K-1-101 Revision H	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Report 26047-ICA Rev F: Instructions for Continued Airworthiness for theinstallation of an Avionica Inc. SatLINK communication management systemwith cabin wireless capability in aBoeing 737-300/-400/-700/-800 seriesaircraftor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/05/2013	Active	10044909

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044926	S-TEC CORPORATION		FAA STC SA09521AC-D	PA-46-500TP	Installation of S-TEC digital Flight control System (autopilot) Part No. 01298-01-01-001 or 01304-01-01-001 1500 Autopilot with Autotrim and YawDamper System, per report 97-13001-003, rev.2 dated 23-Sep-2003 and inaccordance with ST-891 MDLNo. 921213, rev.D dated 24-Jul-2008	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Any paragraph indicatedin the original FAA STC SA09521AC-D dated 10-Dec-2008 or later revisionsapproved by EASA in accorda...	- According to S-TEC Master Drawing List N. 921213 rev.D dated24-Jul-2008;- To be operated in accordance with S-TEC AFM-S P/N 892112, dated21-May-2002 or S-TEC AFM-S P/N 892112, rev.1 dated 01-Oct-2003 or S-TECAFM-S P/N 892112, rev.2 dated10-Dec-2008, in accordance with thelimitations below;- To be...	- S-TEC AFM-S P/N 892112, dated 21-May-2002 is required forPiper model PA-46-500TP for Magic 1500 Autopilot;- S-TEC AFM-S P/N 892112, rev.1 dated 01-Oct-2003 is required for Pipermodel PA-46-500TP for S-TEC 1500 Autopilot;- S-TEC AFM-S P/N 892112, rev.2 dated 10-Dec-2008 for S-TEC 01298/01304Digit...	21/05/2013	Active	10044926
10044929	AIR CRUISERS COMPANY		FAA STC SR02254NY	EC130B4	Installation of Air Cruisers Company (ACC) Emergency Float InstallationKit P/N 65930-101This STC is the validation of FAA STC SR02254NY (date amended April 30,2013)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Procedures per Process Specification No P-12314 Revision C,dtd May 17, 2006ACC Rotorcraft Flight Manual Supplement EDN 3150 Revision 1, dtd04/30/2013ACC Instructions For Continued Airworthiness EDN 3131 Revision -original, dtdDecember 19, 2005or later revisions of the above listed docu...	1 - This STC does not approve the installation of an emergency flotationsystem. The STC approval is limited to the replacement of the electricmeans to activate floats of the Emergency Flotation System installed onEC130B4 with the ACC Pneumatic Activation System.2 - Eurocopter Emergency Floats P/N 21...	21/05/2013	Active	10044929
10044930	HAECO CABIN SOLUTIONS, LLC		FAA STC ST03995AT	B767-300	Floor Reinforcement in a Boeing 767-300 Series Aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Document 12T304R506 revision B Certification Plan - Floor StructureReinforcement in a Boeing 767-300 series aircraft dated 11 March 2013;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or t...	STC only applicable for the following 767-300 Serial numbers: 26991,26987, 26992, 26983, 26984, 26985, 26986, 26988 and25209The approval holder shall fulfill the obligations of Part 21, Paragraph21A.109 or 21.A.451(b) (as applicable).Prior to installation of this design change it must be determined...	21/05/2013	Active	10044930
10044932	DUNCAN AVIATION, INC.		FAA STC ST10939SC	560XL	Installation of a Norwegian Special Mission (NSM) Flight InspectionSystem UNIFIS 3000	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 768-003-MDL_560XL Revision F from 15 April 2013Airplane Flight Manual Supplement 768-023-AFMS_560XLInitial Revisionfrom 03 March 2009Instructions for Continued Airworthiness 768-025-ICA_560XL Revision Efrom 15 April 2013or later revisions of the above listed documents approved b...	Applicability limited to Variant XLS (SER 560-5501 to 560-5830)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness...	21/05/2013	Active	10044932
10044938	SABENA TECHNICS BGC			AS 365 N3	Installation of ADELT - CPI 503-16 Crash Position Indicator System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 29 Amt. 2paragraphs: 29.1, 29.27, 29.29, 29.251, 29.603, 29.605, 29.607, 29.609,29.610, 29.777, 29.855, 29.1301, 29.130...	Master Data List, document no. 2000-01-A-2103-R02, dated 25April 2013Instructions for Continued Airworthiness, document no.2000-01-A-2211-R01 dated 06 April 2012	- Modification limited to AS365N3 with Serial Numbers SN6687 and SN6690.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	21/05/2013	Active	10044938

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10044939	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	PIPER AZTEC PA23-250	Installation of a protruding camera on an approved fully provisionedlocation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CAR 3, dated November 1, 1949, including Amendments 3-1 through 3-9,dated December 15, 1952,,The requirements for environmental protection and the associatedcertified nois...	C/ER/M3125 Modification SheetJC/FTR3125 Flight test reportor later revisions of the above listed documents approved by EASA.,,	As per flight manual supplement JC/FMS/3125.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	21/05/2013	Active	10044939
10044950	CONCORDE BATTERY CORPORATION	REV. 1	FAA STC SA01260WI	SEE ATTACHED FAA AML	Installation of the Concorde RG-380E/K and RG-380E/L seriesVRSLAbatteries in the Beechcraft King Air Model Airplanes.Replacement of the existing aircraft main batteries with a ConcordeRG-380E/K or RG-380E/L series Lead Acid Battery.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of the Concorde RG-380E/K and RG-380E/L seriesVRSLAbatteries in the Beechcraft King Air Model Airplanes (see AML) inaccordance with Concorde Battery Corporation, Master Drawing List,Drawing No. 5-0177, Rev. N/C, dated May 1, 2003;Instructions for Continued Airworthiness, Concorde Batte...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/05/2013	Active	10044950
10044970	BELL HELICOPTER TEXTRON, Inc.	REV 1	FAA STC SR09598RC	206L, 206L-1, 206L-3, 206L-4 206B	Installation of a Radar Altimeter Antenna Mount Kit.Rev.1: Addition of model 206B.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List, AA-12015, Revision G, dated 2 November 2016, orlater FAA approved revision.2. Aeronautical Accessories Instructions for Continued Airworthiness,Report AA-12016, Revision B, dated 17 October 2016, or later FAAaccepted revision.	Only the installation of the Mount is approved. Installation ofequipment for which these provisions are intended is notapproved. It isthe responsibility of the Radar Altimeter System installer to obtainseparate approval for the Radar Altimeter System installation (i.e.,antenna, wiring, avionics) an...	19/10/2018	Active	10044970
10044973	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST03006CH	737-900, 737-900ER. 737-600, 737-700, 737-800,	Retrofit installation of a Dual CMC Electronics Class 3 ElectronicFlight Bag (EFB) System.	The Certification Basis for the original product and:- the EWIS CRI H-01 at issue 3 dated 20 August 2012<(>,<)>- The Lithium Battery CRI F-01 at issue 3 dated 2 April 2013.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/...	Certification Plan, ECS-209314, Revision E, dated 8 July 2011- Project Compliance Report, ECS 209313, Revision D, dated7 October2011- EASA Certification Comparison for STC ST03006CH, ECS-210121, Initialrelease, dated 23 May 2012- Master Data List, ECS-209302, Revision R, dated 17 April 2013- EASA a...	1) The Operating System (OS) for which this Class 3 EFB system isintended has not been approved. Additional EASA approval is required forthe installation of any Operating System and this must be evaluated toassure satisfactory compliance with the applicable airworthinessstandards.2) The aircraft ope...	23/05/2013	Active	10044973
10044994	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR01952AT	BELL 412	Cargo Door Retention Kit	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- RFM Supplement Report AA-99006, dated 19 July , 1999- Aeronautical Accessories Inc. Drawing List Report Number AA-98170,dated February 5, 1999.- Aeronautical Accessories Inc. Installation instructions - ReportAA-98171, Dated January 19, 1999.- Aeronautical Accessories Inc. Inspection and Maintenan...	S/N 36191 and subsequentPrior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectuponthe airworthiness of the product	24/05/2013	Active	10044994
10044995	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST03916AT	A321-212 / -213 / -231 / -232 A321-111 / -112 / -131 / -211 A320-231 / -232 / -233 A320-111 / -211 / -212 / -214 A319-115 / -131 / -132 / -133 A319-111 / -112 / -113 / -114 A318-111 / -112 / -121 / -122	Installation of the TEAC/Goodrich Digital Audio Reproducer and theTEAC/ Goodrich Digital Video Reproducer for the Passenger EntertainmentSystem (PES).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC ST03916AT Issued May 6, 2011Project Specific Validation Report 2-95307-907, Rev. IR, dated Mar. 4,2013MDL 2-95307-001, Rev. A, dated Apr. 28, 2011Instruction for ContinuedAirworthiness 2-95307-805, Rev. A, dated Mar.31, 2011EWIS ICA 2-95307-903, Rev. IR, dated Nov. 30, 2010or later revision...	None	02/03/2016	Active	10044995

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045018	SCANDINAVIAN AVIONICS DESIGN ApS			FALCON 2000, 2000EX	THRANE & THRANE AVIATOR 350 SATELLITE COMMUNICATION SYSTEM WITH WIRELESSLOCAL AREA NETWORKDescription as per AssociatedTechnical Documentation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Documents List in document ref. 2081137 DOC issue 2,dated24/05/2013.Master Drawings List in document ref. 2081137-DL issue 1, dated27/03/2013.Certification Plan ref. 2081137-EO issue 2, dated 20/05/2013.Flight Manual Supplement ref. 2081137-AM issue 2, dated 23/05/2013.Maintenance Manual Sup...	None	24/05/2013	Active	10045018
10045024	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		AA-5, AA-5A, AA-5B, AG-5B	Installation of Garmin G500 System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-23,Amendment 3 (not required by 21.A.101) 29,251,303,305,561,575,603,605,607,609,611,619,671,771,773,777,863,867,954,1182,1301,1303,1309,1311,1321,1322,1323,1325,1327,1...	- Flight Manual Supplement G500 ASR-2013-004-FMS-05.1-00 Rev. 00- Flight Manual Supplement GDL88 ASR-2013-004-FMS-05.2-00 Rev. 00or later revisions of the above listed documents approved by EASA.- Instructions for Installation ASR-2013-004-IFI-10-00 Rev. 00 or later approved revisions.- Instruction...	A suitable Garmin GPS System must have been already installed.This STC includes the installation of Garmin's Synthetic Vision (SVT) Optionand the optional installation ofa Data Link Sensor System Garmin GDL88 and/oran Avionik Straubing Altitude Preselector APS4APrior to installation of this design ch...	31/05/2013	Active	10045024
10045055	TURK HAVA YOLLARI TEKNIK A.S.TURKISH TECHNIC			A321-231	CONVERSION OF CABIN LAYOUT FROM 210 PAX FULL E/C TO 194 PAXDUAL CLASSAND MOVABLE CLASS DIVIDER (MCD) INSTALLATION.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Design Declaration CG-2520005-DD01-01, dated 20.04.2013.or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe modification by third p...	27/05/2013	Active	10045055
10045060	BOMBARDIER AEROSPACE		TCCA SA04-102 ISSUE 1	BD-100-1A10	Activation, Rockwell Collins 5000/6000 SATCOM	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Data Summary Number E026000 Revision Aor laterrevisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/05/2013	Active	10045060
10045063	MOTORFLUG BADEN-BADEN GmbH			A109S	A109S installation of EGPWS MK XXII	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-27 Amdt. 2,paragraphs 25, 29<(>,<)> 301, 303<(>,<)> 305, 307, 561, 601, 603, 605,607, 609, 610, 611, 613, 619, 625, 771...	RFMS for Installation of Honeywell MK XXII EGPWS, Document No. 28107F94078-0601, revision 0, dated 27.02.2013or later revisions of the above listed documents approved by EASA.Master Document List for Installation of Honeywell MK XXII EGPWS,Document No. 28107F94078-0109, revision 1, dated 27.02.2013IC...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/05/2013	Active	10045063

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045079	BLR AEROSPACE, L.L.C.	REV. 4	FAA STC SR009535RC-D	AB 412, AB 412 EP 412, 412EP	Installation of FastFin® System.Installation of a Dual Tailboom Strakes and FastFin® System.Revision 1 mirrors the amendment of FAA STC SR09535RC-D. An approvedmodel list was added and Rotorcraft Flight Manual Supplements wererevised to include Serial Numbers that incorporate Bell HelicopterTechnica...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: FAR29.629 Amdt. 29-40, FAR 29.571 Amdt. 29-20, Appendix A29.4 Amdt. 29-27The requirements for environmental protection and the associatedcertified noise and/ or emissions...	BLR RFM Supplement RFMS-412FF-7, Rev. IR (applicable to AB412 equippedwith PT6T-3B, operating to Agusta Flight Manual AB412)BLR RFM Supplement RFMS-412FF-8, Rev. IR (applicable toAB412 equippedwith PT6T-3BE, operating to Agusta Flight Manual AB412)BLR RFM Supplement RFMS-412FF-6, Rev. IR (applicabl...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/05/2019	Active	10045079
10045086	GFD GmbH	REV. 1		LEARJET 31A/35A/36A 31A, 35A, 36A	SM GPS Antenna ProvisionRev. 1: Transfer to GFD GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- ICA Instruction for Continued Airworthiness Doc. 5256-085- Master data list Doc. No. 5256-049or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/08/2022	Active	10045086
10045092	JCB AERO SA			A330-223	Staircase Removal Monuments Modification.Description - Summary : Some Cabin items removed (Galley G7, LavatoryL37, VCC,Staircase, Wardrobe), Lavatory L36 Modified & relocated,provisions for LDMCR (which is not installed). For further details alsorefer to Certification Plan A332-00324-01-CP-01 issue...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Project Data List A332-00324-01-PDL-01, rev CCertification Plan A332-00324-01-CP-01, issue DICA, A332-00324-01-ICA-01,Rev IROr later revisions of the above listed documents approved by EASA.	1),,Prior to installation of this modification it must be determinedthat the interrelationship between this modification and any otherpreviously installed modification and/or repair will introduce noadverse effect upon the airworthiness ofthe product2),,The installation of items on seat tracks RBLF...	29/05/2013	Active	10045092
10045119	JET AVIONICS S.R.L.			PA-31T CHEYENNE II	General avionics Improvements/ Installation/Replacement of COMM/NAV/ GPOS,TAWS/RMI, DME, Audio Panel, Multifunctional Display	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS23.365, 561, 573, 867, 1309, 1311, 1351, 1431, 1529 at their initialamendmentThe requirements for environmental protection and the associatedcertified noise and/ or emis...	-Master Drawing List BDI 003-10 Rev. 1 15.03.2013-Maintenance Manual Supplement BDI 003-10-14 Rev. 2 11.03.2013-Flight Manual Supplement GNS-530, ST3400, Flightmax FSD BDI 003-16-1(Rev. 0 30.11.2012), -2(Rev. 1 04.02.2013), -3 (Rev. 0 30.11.2012)-MMEL Update BDI 003-10-17 Rev. 1 04.02.2013or later r...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	31/05/2013	Active	10045119
10045148	BELL TEXTRON PRAGUE, a.s.			429	Dual-Color Anti-Collision Light Installation for Bell 429 rotorcraft.The change is described in Aviation Service Engineering BulletinEB-241-0 dated February 19, 2013.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aviation Service Flight Manual Supplement FM_33_40/03_001 Rev.5 DatedApril 29, 2013;or later revisions of the above listed documents approved by EASA.Engineering Bulletin EB-241 Dated 19/02/2013.Maintenance Manual Supplement MM 33_40/03_001 Rev.0 dated February 18,2013.	The EASA approval of this change does not constitute operationalapproval.Prior to installation of this design change itmust be determined thatthe interrelationship between this design change and any otherpreviously installed design changeand/ or repair will introduce noadverse effect upon the airw...	03/06/2013	Active	10045148

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045150	AVIATION SERVICE A.S.			BELL 429	Installation of WESCAM MX-10 on Meeker Nose Mount AFM-NM429-1, andSkyforce Moving Map System OB3000/3300. Aviation Service Operator workstation including F+E seat H110SU with Skyquest monitor AVDU 5008, andConvergent Nanoflash digital video recorder.The change is described in Aviation Service Engine...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Aviation Service Moving Map Flight Manual Supplement FM_34_40/03_001Rev.5, dated June 3, 2013.-Aviation Service Radio Provision Flight Manual SupplementFM_34_40/03_002 Rev. 2, dated April 17, 2013.-Aviation Service Wescam Camera Flight Manual Supplement FM_85_32/03_001Rev. 3, dated April 23, 2013.-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/06/2013	Active	10045150
10045157	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST03007CH	B737-600/-700/-800/-900/-900ER	Validation of FAA STC ST03007CHLinefit installation of a Dual CMC Electronics Class 3 Electronic FlightBag (EFB) System.	The Certification Basis for the original product and:- the EWIS CRI H-01 at issue 3 dated 20 August 2012<(>,<)>- The Lithium Battery CRI F-01 at issue 3 dated 2 April 2013.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/...	- Certification Plan, ECS-208298, Revision G, dated 11 January 2012- Project Compliance Report, ECS 208299, Revision B,dated 19 January2012- EASA Certification Comparison for STCST03007CH, ECS-210256, Initialrelease, dated 23 May 2012- Master Data List, ECS-208300, Revision U, dated 17 April 2013-...	1) The Operating System (OS) for which this Class 3 EFB system isintended has not been approved. Additional EASA approval is required forthe installation of any Operating System and this must be evaluated toassure satisfactory compliance with the applicable airworthinessstandards.2) The aircraft ope...	04/06/2013	Active	10045157
10045158	DART AEROSPACE Ltd.	REV. 1	TCCA SH12-54 ISSUE 1	AW139	AB139/AW139 Utility Interior Kits Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List document MDL-D139-816 Revision A- Instructions for Continued Airworthiness document ICA-D139-816Revision 0or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/06/2013	Active	10045158
10045164	H4 AEROSPACE (UK) Ltd.	REV. 2	CAA UK RESPONSIBILITY	A340-541/-542/-642/-643 A340-311/-312/-313 A340-211/-212/-213 A330-743L/-941 A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-223F/-243/-243F A330-201/-202/-203	Introduction of LED Logo lights on Airbus A330 and A340 aircraftThis STC replaces the original logo lights by LED logo lights	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS-25 Amendment 4:25.2925.30125.30325.30525.30725.32125.57125.58125.60325.60525.60725.60925.61325.89925.130125.130925.13512...	EASA Approved - H4 Aerospace Instructions for Continued AirworthinessNo. H4ADR611 Issue 5EASA Accepted - H4 Aerospace Modification Summary No. H4A1391 Issue 12or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/02/2020	Active	10045164
10045202	E A D AEROSPACE AIRWORTHINESS	REV. 2		A330-341 / -342 / -343 A330-321 / -322 / -323 A330-301 / -302 / -303 A330-202	Activation of GSMConnex SystemGSMConnex is a solution that provides GSM and WLAN services to aircraftpassengers. It consists of hardware and software parts for both theaircraft and the ground, with the airborne GSM and WLAN network beingconnected to ground network via satellite.The original issue of...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt 425.29 / .581 / .777(a)(c) / .791(d) / .869(a) / .899 / .1301 / .1307(c)/.1309(a)(b)(c) / .1310 / 1322(d) / .1333(c) / .1353 / .1357(a)(b)(c) /.1360 / .1381 / .1...	For A330-202 MSN 605 :. Master Drawing List, ref : 01383-EAS-A-MDL Issue D, dated 29 May 2013. Airplane Flight Manual Supplement, ref : 01383-EAS-A-AFM-01, Issue C,dated 29 May 2013. Instructions for Continued Airworthiness, ref : 01383-EAS-A-ICA-01Issue C, dated 30 May 2013For A330-300 aircraft ser...	1- Refer to respective applicable ICA documents for associatedAirworthiness Limitations and Compatible Equipment List.2- When installed on A330-202 aircraft model, this STC is onlyapplicable to MSN 605 and 487.3- Depending on the aircraft model, the following Minor Modificationsare prerequisites :,,...	29/08/2014	Active	10045202

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045229	ROEDER PRAEZISION GMBH	REV. 1		PA-28RT-201T TURBO ARROW IV PA-28RT-201 ARROW IV PA-28R-201T TURBO ARROW III PA-28R-201 ARROW III PA-28R-200 ARROW II PA-28R-200 ARROW PA-28R-180 ARROW PA-28-236 DAKOTA PA-28-235 CHEROKEE PATHFINDER PA-28-181 ARCHER III PA-28-181 ARCHER II PA-28-180 CHEROKEE PA-28-180 ARCHER PA-28-161 WARRIOR III PA-28-161 WARRIOR II PA-28-160 CHEROKEE PA-28-151 CHEROKEE WARRIOR PA-28-140 CHEROKEE CRUISER	Installation of J.P. Instruments (JPI) Primary Engine Data ManagementSystem EDM930 in accordance with Engineering OrderEDM930-NY03218-05.The EDM-930 is a combined electronic indicating system whichsimultaneously displays to the pilot powerplant and aircraft systemsoperating parameters.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23, Amendment 2 for affected paragraphs:23.21, 23.303, 23.561, 23.603, 23.773, 23.1301, 23.1305, 23.1309,23.1321, 23.1327, 23.1337, 23.1357, 23.1365, 23.1431, 23.1529,2...	Airplane Flight Manual Supplement EDM930-NY-03218-08, Revision 0,10.04.2012or later revisions of the above listed documents approved by EASA.Master Document List, Revision 0, 11.04.2012, or later approvedrevisionsInstallation Instruction:Engineering Order EDM930-NY-03218-05, Revision 0, 29.03.2012,a...	None	15/11/2017	Active	10045229
10045230	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A, 525B	Installation of Dual Garmin GTN650/GTN 750 Systems	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 323.301, 23.303, 23.305, 23.307, 23.365, 23.561, 23.571, 23.575, 23.603,23.605, 23.607, 23.609, 23.611, 23.613, 23.671, 23.771, 23.773, 23.843,23.863, 23....	Flight Manual Supplement ASR-2013-023-FMS-05-01, Amdt. 01orlater revisions of the above listed documents approved by EASA.Instructions for Installation ASR-2013-023-IFI-10-01, Amdt. 01, or laterapproved revisionsInstructions for ContinuedAirworthiness ASR-2013-023-ICA-11-00, Amdt.00, or later appr...	None	10/06/2013	Active	10045230
10045232	AVIONICARE LIMITED		CAA UK RESPONSIBILITY	727-100	Upgrade of Dual Trimble HT-9100 GNSS to Dual Universal UNS-1Lw FMS on Boeing 727 Aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI H-01 'Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWIS'- the following paragraph(s) at a later amendment:CS 25Amendment 4:CS...	Avionicare Master Document ListAVC-MDL-0004 Issue FAvionicare Flight Manual SupplementAVC-FMS-0004-001 Issue Bor laterrevisions of the above listed documents approved by EASA.	Applicable to s/n 18934 onlyPrior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	10/06/2013	Active	10045232
10045252	CONCORDE BATTERY CORPORATION	REV. 1	FAA STC SR03895AT	MD900	Installation of an Concorde replacement lead acid battery for MD900Series	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.FAR Part 27 (as defined in FAA TCDS H19NM); 27.1301 (a), (b), (c) & (d),1309(a) & (b), 1353(a), (b), (c), (d) & (e), 1529.The requirementsfor environmental protection and the associatedcertified noi...	RFM Supplement: 5-0330 23 Nov 2010or later revisions of theabove listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures ofEU/USA Bilateral Agreement.Master drawing list: 5-0329 Rev A...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/06/2013	Active	10045252
10045274	LUFTHANSA TECHNIK AG			A330-300	DLH A330 IK Retrofit.Description - Summary : installation of new Y-Class, C-Class and FirstClass seats and lining.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan CP25-12/31M iss 1 at rev 2- Supplemental Type Definition Document STDD25-12/31M issue 1 rev 0(Master document and definition)- ICA, ref A-00-12/40-ICA, rev 01- Compliance Record List CRL25-12/31M iss 1 at rev 0or laterrevisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of theproduct.	12/06/2013	Active	10045274

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045275	SUPERJET INTERNATIONAL S.P.A.	REV. 4		RRJ-95B	SSJ-100 - Italian style Interiors InstallationOriginal STC is installing Italian Style interiors in SUKHOI RRJ-95Baircraft.Change Notice CN-IJ93-0022 introduces Lavatories reinforcement andremove the AFM Limitations.Change Notice CN-IJ93-0025 introduces structural reinforcement on galleyG2 to improv...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- STC Original issueAs defined in certification programme OPS-CED-12001 Rev D dated30/05/2013, list of compliance documents OPS-CED-13105 Rev A dated30/05/2013 and the Compliance Check List OPS-CED-13118 Rev A dated10/06/2013.Supplemental Type Design Definition OPS-CDO-13042 rev B dated05/06/2013.Ma...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/03/2017	Active	10045275
10045282	DUNLOP AIRCRAFT TYRES LIMITED		CAA UK RESPONSIBILITY	ATR 72-211/-212/-212A ATR 72-101/-102/-201/-202	Installation of Dunlop Aircraft Tyres on ATR 72 seriesThe STC installs Dunlop Aircraft Tyres Ltd P/N DZ30730T (Main LandingGear) and P/N DR15520T (Nose Landing Gear).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, ref. DATL PR3 MDL Rev IR, dated 20 May 2013Instruction for Continued Airworthiness, ref. DATL PR3ICA rev IR, dated20 May 2013or later revisions of the abovelisted documents approved by EASA	None	12/06/2013	Active	10045282
10045283	CHALLENGER AVIATION PRODUCTS INC.		FAA STC SE02352CH	SEE EASA APPROVED MODEL LIST	Direct Oil Filter Replacement - EASA Validation of FAA STC SE02352CHInstallation of Challenger cleanable oil filter assembly in accordancewith Challenger Aviation Products, Inc. Installation Instructions 1124revision B, dated October 31, 2009, or later FAA approved revision.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Challenger Aviation Products, Inc.Installation Instructions 1124 revision B, dated October 31, 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedure...	1. Compatibility of this design change with previous modifications mustbe determined by the installer.2. Use of Challenger Aviation Products, Inc. Inspection and CleaningInstructions 1125, Revision C, dated October 31, 2009 or later FAAapproved revision is required.3. A copy of this certificate mus...	12/06/2013	Active	10045283
10045284	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	PA-31	Approval of an Aspen EFD-1000 Primary Flight Display against therequirements of EU-OPS for Dual Pilot Operations.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23 Amendment 3:CS 23.611CS 23.771CS 23.777CS 23.867CS 23.1301CS 23.1303CS 23.1309CS 23.1311CS 23.1321CS 23.1322CS 23.1323CS 23.1331CS 23.1351CS 23.1353CS 23.1357CS 23.1...	Master Document ListMDL. 00812 Revision BInstallation ManualIM. 00812 Revision AInstructions for Continued Airworthiness ICA. 00812 Revision AFlight Manual SupplementFMS. 00812 Revision Aor later revisions of the above listed documents approved by EASA.	None.	12/06/2013	Active	10045284
10045290	UUDS			A330-200	Contour A330-200 Business Class seat modification and bumperinstallationThis modification removes the existing RockwellCollins IFE equipment,monitors and harnesses from Contour Business class double seats ModelS20207-001 and replaces existing Amsafe seat belts. The seats aremodified to provide prov...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Modification Sheet MMS-TMC99-065-25-001-00or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/06/2013	Active	10045290
10045299	GULFSTREAM AEROSPACE CORPORATION	REV. 6	FAA ST04252AT-D	GVI (G650), GVI (G650ER) GVI (G650)	GG-VI Airplane Interior Installation:Cabinetry, Seating, Associated Electrical and Mechanical Systems andExterior MarkingsRevision 1: Shower installation approvedRevision 2: Electro-Hydraulic Passenger Seats installation approvedRevision 3: Special Condition on non-rechargeable Lithium Batteries for...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC F-10 on non-Rechargeable Lithium Batteries.The requirements for environmental protection and the associatedcertified noise and/ ora...	Supplemental Type Certificate (STC), ST04252AT-D, Installation of anAirplane Interior, Date Amended 19 OCT 2021AFM Supplement ref. GC61468M001 rev. J - dated 24 AUG 2017Instructions for Continued Airworthiness rev. GC62801A001 rev F dated 18OCT 2021EASA Validated Configuration Lists, GC622040002, re...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/11/2021	Active	10045299

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045303	MOTORFLUG BADEN-BADEN GmbH			MBB-BK 117 C-2	Installation of HATS Tracking System, used for flight tracking of theRotorcraft. The HATS consists of the Tracking Device (HATC), oneexternal installed GSM antenna and one external installed satcomantenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFMS 25102F130209-0601 Rev 2 dated 11/06/2013or later revisions of the above listed documents approved by EASA.CP 25102F130209-0101 dated 13/03/2013MDL 25102F130209-0109 Rev 2 dated 13/06/2013	During take-off and landing procedure the HATS system audiochannel hasto be switch off on pilots and co-pilots audio control unit in bothreception and transmission control.HATC'smaintenance interface shall be used only on the ground formaintenance purposes.HATS system is for supplemental safety an...	14/06/2013	Active	10045303
10045310	AVIONIK STRAUBING ENTWICKLUNGS GmbH			3. SA227-CC, -DC, 2. SA227-AC, -BC, -PC 2. SA226-TC 1. SA26-AT, -T 1. SA227-AT, -TT 1. SA226-AT, -T, -T(B)	Single Installation GPS/COMM/NAV System Garmin GTN625/635/650/725/750	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 3 (not required by 21A.101) 23.303, 23.305, 23.561, 23.575, 23.603, 23.605, 23.607, 23.609, 23.611,23.613, 23.671, 23.771, 23.773, 23.863, 23.867, 23.1301,...	Flight Manual Supplement ASR-2013-049-FMS-05-00, Rev. 00or later revisions of the above listed documents approved by EASAInstructions for Installation ASR-2013-049-IFI-10-00, Rev.00 or laterapproved revisionsInstructions for Continued Airworthiness ASR-2013-049-ICA-11-00, Rev. 00or later approved r...	The aircraft must have been already equipped with a suitable GPS Antennaand a suitable E-HSI.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverseT...	14/06/2013	Active	10045310
10045316	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.	REV. 1		B200GT, B300, B300C B200, B200C, B200CGT 200, 200C, 200CT, 200T	Revision 1 of STC 10045316, addition of applicability to models 200 200C200CT 200T under TCDS US A24CE	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 23Amdt 3-301<(>,<)>305<(>,<)> 307<(>,<)> 561<(>,<)> 601<(>,<)> 603<(>,<)> 607<(>,<)> 609<(>,<)> 1301<(>,<)> 1309<(>,<)>...	- Supplément au manuel de vol SEAM-SMV 3924/12-Rev2 du 23/02/18or later revisions of the above listed documents approved by EASA.- Annexe C8 3924-12 Rev2 du 23/02/2018	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/03/2018	Active	10045316
10045334	E A D AEROSPACE AIRWORTHINESS			B737-600/-700/-800/-900/-900ER	Upgrade to CDPLC for ATN B1 capability:upgrade of existing Communication Management Unit software for CPDLC(Pioneer version of the Rockwell-Collins solution) with an ATN B1compliant version.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): F-01 Data Link Services for the Single EuropeanSky Issue02 dated 26.03.2013- the following paragraph(s) at a later amendment: CS25 amendment 11 asp...	Master Drawing List 01406-EAS-A-MDL-BAircraft Flight ManualSupplement 01406-EAS-A-AFM-01-Aor later revisions of the above listed documents approved by EASA.	As per Aircraft Flight Manual Supplement 01406-EAS-A-AFM-01-A:"Except of following noticed hereafter, the CPDLC installation islimited to providing a supplementary means of communication; voice shallremain the primary means of communication.CPDLC shall only be used for routine datalink exchanges dur...	17/06/2013	Active	10045334
10045336	SABENA TECHNICS BOD	REV. 1		737-700	SATCOM upgrading, IFE/CMS, WIFI and GSM new systems modification	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:-,,CRI F-01 on IFE, issue 2 dated 6 June 2013<(>,<)>-,,CRI F-02 on Digital Devices Design Assurance, issue 2 dated 16 June2013<(>,<)>-,,C...	-,,Certification Program, Reference DO/N/066/2012/PHG issue6, dated 12June 2013<(>,<)>-,,Certification Matrix, Reference DO/N/066/2012/PHG dated 17 June 2012<(>,<)>-,,Airplane Flight Manual Supplement, Reference AFMS-B3024-00-050 issue2,dated 14 June 2013<(>,<)>-,,Instructions for Continuous Airw...	Limitations:1) The GSM system shall not be used below 10 000 feet pressure altitude.2) The ACARS system using the SATCOM shall not be used during any flightphase nor on ground.3) The deployable IFE screens must be stowed during take-off andlanding.4) A flight attendant must be in the cabin during al...	18/06/2013	Active	10045336
10045344	KUERZI AVIONICS AG			FALCON 7X	GSM & Wi-Fi IntegrationNew installed equipment:- TriaGnoSys, 21T810-XX-01-00 AEROBOTS+ (GSM Base Transceiver Station,BTS)- TriaGnoSys, 21T820-00-01-00 NCU (Network Control Unit)- VT Miltope, 902693-1 nMAP (Cabin Network Router)- Mobile Mark, RMM-UMB-Q4-AB GSM/WIFI TX Antenna-Mobile Mark, RMM-UMB-Q4...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	- Master Document List, Doc. No. MDL-201110599, Rev. A, 08.06.2013- AFMS, Doc. No. FMS-201110599, Rev. 0, 28.05.2013- ICA, Doc. No. ICA-201110599, Rev. N/C, 29.05.2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	19/06/2013	Active	10045344

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045364	A.S. AVIONICS SERVICES S.A.			EMB-135BJ	Installation of IWG-A4 Potable Water Treatment Unit on EMB-135BJEASA validation of ANAC STC 2012S09-08	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List ref. EMB135BJ-38-0001MD, Rev. D, dated 11/09/2012.Certification Plan ref. EMB135BJ-38-0001CP, Rev.B, dated 07/03/2012;supplemented by EASA Declaration of Compliance ref.EMB135BJ-38-0001EASA-DC, Rev. Original, dated 20/02/2013.Installation Manual ref. EMB135BJ-38-0001IM, Rev. C,...	Applicable to EMB-135BJ S/N 14500997, 14501029 and onPrior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willintroduce noadverse effect upon the airworthiness of the pro...	19/06/2013	Active	10045364
10045378	DASSAULT AIRCRAFT SERVICES (DAS)	REV. 3	FAA ST11041SC	MF50, F50EX	Installation of upgraded hardware to replace Rockwell Collins Proline 4displays with Rockwell Collins Pro Line 21 displays, add an IntegratedFlight Information System (IFIS) and enable localizer performance withvertical guidance (LPV) capability.Rev. 3: Transfer from BHE & Associated, Ltd. to Dassau...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval, except where amended by additional orlater amendments if indicated on FAA STC.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product...	- Master Drawing List 306-00-0001 rev. G dated 11 February 2011, orlater approved FAA revision.- “Airplane Flight Manual Supplement with FMS-6100 version 4.1”,document Rev. IR, dated 24 January 2011, or “Airplane Flight ManualSupplement with FMS-6100 version 4.2”, document 360-00-0087, Rev. A,dated...	The installation requires the installation of EASA STC 10064001 (FAA STCST01833WI) and/or EASA STC 10016518 (FAA STC ST01433WI-D) in order toprovide global positioning system dataenhanced with the wide areaaugmentation system.For aircraftwith no flight data recorder (FDR), or FDR with less than42P...	19/03/2020	Active	10045378
10045381	N2 DEVELOPMENT Inc.	REV. 2	FAA ST02436LA	737-700/ -800/ -900ER	Installation of Cabin Interior Noise Reduction System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. N2 Development, Inc. Master Data List N2002 Rev. D dated8 October2012 or later FAA approved revision.2. N2 Development, Inc. Instructions for Continued AirworthinessDocument N20020301 Issue "001" dated 28 April 2012 or later FAA approvedrevision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This approval is limited to Master Data Li...	18/09/2018	Active	10045381
10045384	ZIM AIRCRAFT CABIN SOLUTIONS, LLC		FAA STC ST01735AT-D	MD-11	VHF Installation - MD-11Collins VHF Transceivers and GablesRadio Tuning Panels installation toenable 8,33 kHz channel spacing in an MD-11 aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TIMCO Master Data List No. 98T058L001 Rev. B dated 29 October 1998or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)” and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	20/06/2013	Active	10045384
10045392	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	A330-200	Installation of Galleys and associated ceiling panels into an AirbusA330-200 to be operated by Delta.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AIM Aviation Ltd Definition Document No. DD1210 Issue NewDated 14 May 2013or later revisions of the above listed documents approved by EASA.,,,,,,	None	20/06/2013	Surrendered	10045392

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045396	SABENA TECHNICS BGC	REV. 4		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-216/-231/-232/-233 A320-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115	TCAS 7.1 upgrade on A319/320/321The modification consists in the upgrade of the existing TCAS 7.0 systemto TCAS 7.1 system, only computer unit is modified :Group 1: ACSS's Software Upgrade (RT-950)Group 2: HONEYWELL TCAS processor replacement-TPA-81A (7.0) to TPA-100B(7.1)Group 3: ROCKWELL COLLINS T...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:Applicable regulations at CS 25 Amendment 4 (refer to associatedCertification Plan 0594-01-A-2101-R05, section 5, for deta...	Instructions for Continued Airworthiness, ref : 0594-01-A-2211-R05or later revisions of the above listed documents approved by EASA.Master Data List, ref : 0594-01-A-2103-R05	As per design of this STC, the modifications related to TCAS 7.0 need tobe previously installed by an Airbus modification (refer to AircraftSystem Configuration Checklist reference 0594-01-A-ASCC-R06) and shallcorrespond to the descriptionincluded in System Technical Specificationreference 0594-01-...	14/02/2018	Active	10045396
10045398	FLYING COLOURS CORP.		C-LSA12-029/D	CL-600-2B19 (CRJ-200)	Corporate Shuttle Conversion	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. C-LSA12-029/D Issue 1, dated 22 August 2012.ACS-NAI Ltd. Modification Data Summary H366000 Revision NC.Flying Colours Corp Airplane Flight Manual Supplement for CorporateShuttle Conversion, H366090 Revision NC.ACS-NAI Ltd. Mandatory Maintenance Manual Supplement for Broadba...	Restricted to ASN 7478, 7494, 7625, 7629, 7862, 7864Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the prod...	21/06/2013	Active	10045398
10045413	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS			A320-231/-232/-233 A320-216/-231/-232/-233 A320-211/-212/-214/-215/-216 A320-111/-211/-212/-214/-215	GSM Activation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program 01381-EAS-CPM-01 Rev C, dated 01/03/2013Compliance Check List 01381-EAS-A-CCL-01 Rev A, dated 12/06/2013Master Drawing List 01381-EAS-A-MDL Rev C, dated 12/06/2013Aircraft Flight Manual Supplement 01381-EAS-A-AFM-01 Rev A, dated19/06/2013Instructions for Continued Airworthiness...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	21/06/2013	Active	10045413
10045423 (EASA.R.S.01501)	BRISTOW HELICOPTERS Ltd.		CAA UK RESPONSIBILITY	EC 155 B1	Activation of ADS-B Function using Mode S Extended Squitter	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 Amendment 3:CS 29.1301CS 29.1309CS 29.1431CS29.1581The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	Bristow Helicopters Limited Eurocopter EC155 Flight Manual SupplementNo1 Initial Issueor later revisions of the above listed documents approved by EASAModification MOD/155/34.5720Issue 1Certification Plan BHL/155.1075 Initial Issue	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	24/06/2013	Active	10045423
10045424	HELIFAB Inc.d/b/a ARROW AVIATION CO. LLC		FAA STC SR09485RC	BELL 212, 412, 412EP	Installation of Cabin Area Cargo Net, according to Master Drawing &Documents List HF-412-DL-101, Rev. L, in Bell 212, 412, 412EPHelicopters	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-HF-412-DL-101, Rev. L, Master Drawing & Documents List-HF-412-CCL-0003, Rev. IR, Compliance Checklist-HF-412-ST-0002, Rev. C, Load Test Plan (only Load Test results, Table1)-HF-412-I-2550-01, Rev. E, Cargo Net Installation (Drawings)	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/06/2013	Active	10045424

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045436	TELEDYNE UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	MD-11, MD-11F	Installation of Wireless Quick Access RecorderRev. 1: Transfer from Teledyne Limited to Teledyne UK Limited.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:JAR 25 Amendment 16:§25.23; §25.25; §25.27; §25.561; §25.581(b)(1); §25.603 (a),(b),(c);§25.605(b); §25.611; §25.869(a)(4...	MOD-PCP-029, issue 02 (January 25, 2013) - Project Certification PlanMOD-MDL-029, issue 01 (June 14, 2013) - Master Data ListMOD-CCL-029, issue 01 (June 10, 2013) - Compliance ChecklistMOD-EWA-029, issue 01 (December 11, 2012) - EWIS AssessmentMOD-ICA-029, issue 01 (January 14, 2013) - Instructionsa...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Compatibility has been established for the aircraft lis...	26/11/2020	Active	10045436
10045438	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK	REV. 2	CAA UK RESPONSIBILITY	DO228-202K	Introduction of Oil Spill Response Role System	FAR Part 23,, Amdt: 1-23The Certification Basis for the original product remains applicable tothis certificate/ approval.Derogation to latest amendment (Part 21A. 101).The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ appro...	AFMS FRAH/FM/0121 dated 06.Feb. 2014Instruction for Continued Airworthiness ICA-0221 dated 13.Aug. 2013or later revisionsof the above listed documents approved by EASA	The approval of this design change is conditional on the large bellyradome being installed. UK CAA Major Modification AAN 23889 refers.S/N: 8115Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modif...	10/02/2014	Active	10045438
10045439	BOMBARDIER AEROSPACE		C-LSA07-156/D	BD-700-1A10	Aircell ST3100 Satcom Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. C-LSA07-156/D, Issue 2 dated 19 December 2008.Bombardier Aerospace Master Document List BAS67017018, Revision B dated24 October 2008.Bombardier Aerospace Instructions for Continued Airworthiness DocumentBAS67057020, Revision A dated 24 October 2008.or later revisions of thea...	Restricted to ASN 9003Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The installation of this m...	25/06/2013	Active	10045439
10045443	SABENA TECHNICS BGC			777-300ER	eXPhone System activation on B777-300ER with VVIP cabin interior [Installation of eXPhone dedicated equipment and activation of thein-flight GSM connectivity system]	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	· Master Date List, Aeroconseil document No. 0616-01-A-2103, Revision 0,dated 14 June 2013.· Aircraft Flight Manual Supplement, Aeroconseil document No.0616-01-A-2301<(>,<)> Revision 1, dated 11 June 2013· Instruction for Continued Airworthiness, Aeroconseil document No.0616-01-A-2211, Revision 1, d...	Per Instruction for Continued Airworthiness, Aeroconseil document No.0616-01-A-2211 this modification is limited to theBoeing B777-200 MSN36563, with VVIP cabin interior, except similarity demonstrated perAeroconseil document 0001-01-B-0914 (Classification of ModificationChange Procedure for GSM Co...	25/06/2013	Active	10045443
10045451	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		PC-12, PC-12/45 PC-12/47, PC-12/47E	Installation of L-3 Communications WX-500 Stormscope with Antenna NY-163	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 3, 23.301, 303, 305, 307, 365, 561, 571, 575, 603, 605,607, 609, 611, 613, 671, 771, 773, 843, 863, 867, 1301, 1309, 1321,1322, 1327, 1351, 1357, 1359, 13...	Flight Manual Supplement ASR-2013-001-FMS-05-00, Amdt. 00orlater revisions of the above listed documents approved by EASA.Instructions for Continued Airworthiness ASR-2013-001-ICA-11-01 (Rev.01) dated 24th May 2017	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10045451

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045456	E A D AEROSPACE AIRWORTHINESS	REV. 2		777-300/-300ER	GSM and WIFI activation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List, EAD Aerospace document No. 01410-EAS-A-MDL,Revision F, dated 30 June 2017.-Instructions for Continued Airworthiness, EAD Aerospace document No.01410-EAS-A-ICA-01, Revision E, dated 16 June 2017-Aircraft Flight Manual Supplement, EAD Aerospace document No. 01410-EAS-A-AFM-01, Rev...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/07/2017	Active	10045456
10045472	EIRTECH AVIATION SERVICES LIMITED			737-800/-900/-900ER 737-300/-400/-500/-600/-700/	Spectralux Dlink+ w/CPDLC installation (Link2000+/ATN B1 compliant) inBoeing 737 aircraft	CS 25 Amendment 12 as amended by the following Special Conditions:F-01 High Intensity Radiated FieldsF-03 Data Link Services for the Single European SkyThe requirements for environmental protection and the associatedcertified noise and/ oremissions levels of the original product areunchanged and re...	Master Documents List MDL/282-050 Issue 04Flight Manual Supplement FMS/282-002 Issue 01Maintenance Manual Supplement MMS/ 282-012 Issue 01Service Bulletin ERT/SB-162 Issue 01or later revisions of the above listed documents approved by EASA	This CPDLC installation is limited to providing a supplementary means ofcommunication; voice shall remain the primary means of communication.CPDLC shall only be used for routine datalink exchanges during en-routeoperations in upper airspace.Prior to installation of this design change it must be dete...	27/06/2013	Active	10045472
10045473	SABENA TECHNICS BGC	REV. 3		A330-343/-941 A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-321/-322/-323/-341/-342 A330-301, A330-302, A330-303 A330-243, A330-243F A330-243/-243F/ 301/-302/-303 A330-223, A330-223F A330-201, A330-202, A330-203 A330-201/-202/-203/-223/-223F	Mechanical & Electrical provision for personal tablet computer EFB forA330 aircraftThis STC deals with the installationof provision both mechanical (mounting assembly support on lower frame of each cockpit slidingwindow) and electrical (DC/DC USB converter) for Personal TabletComputer.REV 1: It is a...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 at Amendment 18 paragraphs: 1, 29, 251, 305, 561, 571,603, 605,607, 609, 613, 625, 773, 785, 803, 807, 809, 1327,1...	Master Data List, Ref. 0632-01-A-2103-R07 dated 15th Apr. 2021- Airplane Flight Manual Supplement, Ref. 0632-01-A-2301-R06 dated 14thApr. 2021- Instructions for continued airworthiness, Ref. 0632-01-A-2211-R10dated 18th Sep. 2020- Master Minimum Equipment List Supplement Document, Ref.0632-01-A-MMEL...	Limitations as per §3 of Airplane Flight Manual Supplement document.The window frame must be inspected at 34230 FC and 16475 FC inspectioninterval (refer to associated Instructions for continued airworthiness,Ref. 0632-01-A-2211-R10, §3 for details).Prior to installation of this design change it mus...	15/04/2021	Active	10045473
10045479	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	PREMIER 1/1A	To introduce an Aviator Swift Broadband Satcom System with wi-fi.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Hawker Beechcraft Ltd ModificationSC0458A.Operation in accordance with Hawker Beechcraft Ltd Flight ManualSupplement No 2 Issue 1 to Manual 390-59001-0003.Maintain in accordance with Hawker Beechcraft Ltd ICA document refASC-C-028-AW4368 Issue 1 dated June 2013or late...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	27/06/2013	Active	10045479
10045481	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A319-133	Galley Complex Installation.Installation of Galleys G1 and G2 and a Sliding Door.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRI D-01Installation of Interior DoorsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product are...	Modification TEN 722, Airbus A319-133, Galley Complex Installation,Issue 1 dated 10 June 2013EWIS ICA, TEN 722/26A Issue 1or later revisions of the above listed documents approvedby EASA.	Airbus A319-133 serial number 4842 only.This Galley ComplexInstallation is part of another EASA STC for thisaircraft, Interior Outfitting Installation, EASA Project Number0010014342-001and EASA STC Approval 10046155 refer. This Galley ComplexInstallation must not be installed without the Interior O...	23/08/2013	Active	10045481

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045486	DELTA ENGINEERING CORPORATION		FAA STC ST02929NY-D	A330-341, A330-342, A330-343. A330-321, A330-322, A330-323, A330-301, A330-302, A330-303,	Installation of Panasonic Global Communication System in A330	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List 0154-07357-2272, Rev -, Dated 12 Jan 2013.Aircraft Flight Manual Supplement 0654-07364-2272, Rev -, Dated 9 Jan2013.Instruction for Continued Airworthiness 0754-07365-2272, Rev A, Dated 17Novor later revisions of the above listed documents approved by EASA inaccordance with EASA ED...	This Approval is linked to the approvals hereunder, which are out of thescope of this STC and must be covered by another approval:- The demonstration of compatibility of the TPEDs (Transmitting PortableElectronic Devices).- The Panasonic GCS Antenna (Ku-Band) must be covered by a separate EASASTC.-...	28/06/2013	Active	10045486
10045487	DART AEROSPACE Ltd.		TCCA STC SH13-18	MBK-BK117 A1/A3/A4/B1/ B2/C1/C2	D117-840 Bearpaw InstallationInstallation of Bearpaw as defined in Master Document List MDL-D117-840.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MDL-D117-840 Rev. A- Installation Instructions IIN-D117-840 Rev. A- Instructions for Continued Airworthiness ICA-D117-840 Rev. 0	None	28/06/2013	Active	10045487
10045488	RHEINLAND AIR SERVICE GmbH	REV. 4		208, 208B	Installation of Parachute Kit consisting of: Manual roller door,handholds, cabin benchesRevision to account for the transfer from airplus engineering GmbH toRheinland Air Service GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Parachute Operation SC-O23-div-01.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the p...	Refer to Technical Publication - Applicability Matrix IPC<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	All limitations defined in AFMS's.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product	23/07/2025	Active	10045488
10045492	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	DORNIER 228-202K	Introduction of Flight Management SystemThis Change replaces the existing R-NAV2 and GPS system with a newFlight Management System, providing an RNP5 navigation solution and anoperational B-RNAV approval. Additionally a Multi-Function Display isintroduced to provide improved situational awareness. T...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFMS FRAH/FM/0122 Rev. 0 dated 14.Jun.2013Build in accordance with Document List in DC-0223, Iss. 1, or laterapproved revision.Instruction for Continued Airworthiness ICA-0223, Iss A, dated17.Jun.2013or later revisions of the above listed documents approved by EASA.	The installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.	28/06/2013	Active	10045492
10045512	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			525, 525A	P-RNAV Approval of UNS-1K	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Airplane Flight Manual Supplement 2013-6-8, Rev. IRor later revisions of the above listed documents approved by EASA.- Engineering Order 2013-6, Rev. A, or later approved revisions-Installation Procedure 2013-6-1, Rev. IR, or later approved revisions	None	01/07/2013	Active	10045512
10045515	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		A340-313	Interior reconfiguration of Cathay Pacific A340 AircraftPremium economy class seat installation. For additional information,refer to NAT Certification Plan N0406-D01NB : As per certification plan, the applicable aircraft Manufacture'sSerial Numbers (MSN) are : 136 ; 137 ; 142 ; 147 ; 157 ; 160 ; 208...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification plan N0406-D01 rev BMaster Drawing List : refN0406-D10 rev BCertification Summary ref N0406-D90 rev AICA: ref N0406-D70 rev -(and EAPAS/FTS ICA Document : N0406-D79 rev B)or later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of theproduct.	03/07/2013	Active	10045515

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045516	BERINGER AERO	REV. 6		SR20, SR22, SR22T	Installation of main wheels (RF-006(A)), nose wheel (RA-002(A)) andbrake system (EA-003.3N)Revision 1: Upgrade of the wheel P/N: RA-002(B) supersedes RA-002(A).Revision 2: Update of maintenance manual and part list.Revision 3: Maintenance manuals updates and introduction of an aircraftflight manualR...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement: AFMS-STC-004 rev 01 dated 21 Feb. 2022;Installation and Instructions for Continued Airworthiness: ICA-STC-010rev 04 dated 19 Oct. 2021;Modification file: DM-STC-010 rev 04 dated 11 Mar. 2022;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2024	Active	10045516
10045531	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 2		551 (CITATIION II) 501 (CITATION I)	Installation of TAS System Garmin GTS825.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-23,Amendment 3 - 301, 303, 305, 307, 365, 561,571, 575, 603, 605, 607,609, 611, 613, 771, 773, 843, 863, 867, 1182, 1301, 1309, 1321, 1322,1325, 1327, 1351, 1357, 135...	Flight Manual ASR-2013-019-FMS-05-00, Rev. 00or later revisions of the above listed documents approved by EASAInstructions for Installation ASR-2013-019-IFI-10-00, Rev. 00, or laterapproved revisionsInstructions for Continued AirworthinessASR-2013-019-ICA-11-02 (Rev.02) dated 12th April 2017	The aircraft must have been already equipped with a suitable display.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworth...	30/08/2017	Active	10045531
10045534	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		CESSNA S550 CITATION S/II CESSNA 550 CITATION II CESSNA 500 CITATION/ CITATION I	Installation of Garmin Dual GTN-750 SystemRevision 1 adds the TAWS limitation to MSN 550-0672 and revokes theInitial Issue of the approval.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Scandinavian Avionics, AFM Supplement GTN-750, 2081059-AM A , issue 4,dated 12 June 2013-Scandinavian Avionics, AFM Supplement GMA-35, 2081059-AM B, issue 1,dated 25 February 2013-Scandinavian Avionics, AFM Supplement GWX-70, 2081059-AM C, issue 1,dated 25 February 2013-Scandinavian Avionics, AFM S...	Periodic Structural Inspection:GPS Antenna, Task No. 34-2081059-02Initial: At next 24 month / 800 hours inspectionThereafter: at every 24 month / 800 hours inspectionGPS Antenna, Task No. 34-2081059-03*Initial: no later than 11.000 LDG (after installation)Thereafter: every 8500 LDG*)Task No. 34-2081...	22/08/2013	Active	10045534
10045537	AMAC AEROSPACE SWITZERLAND AG	REV. 2		BOEING 777-300ER	Interior Outfitting B777-300ER, S/N 36563The following change was incorporated with Revision 2 of the STC:Open Cook TopInstallation in Aft Galley. Installation of a new opencook top with a fume hood on the upper part and an inductive hot plateon the lower part on the AFT LH Galley (G7). Existing eq...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-02 Isolated CompartmentsD-07 Glass Screens of Displays / MonitorsD-11 Shower InstallationD-16 Installation of Glass Panels in the cabinD-17 Install...	Upon completion of Revision 2:The change is defined with AMAC Master Data List MDL-AV01-2500 RevisionB amended by MDL-AV02-2520 Revision B and Master Data List MDL-AV09-2530Revision E.The aircraft shall be operated in accordance with AMAC Airplane FlightManual Supplement AFMS-AV01-2500 Revision B da...	- S/N 36563 limited to Private Use- Limitations as per AMACAirplane Flight Manual SupplementAFMS-AV01-2500 Revision B dated 8th of November 2014- Airworthiness Limitations as perInstructions for ContinuedAirworthiness ICA-AV01-2500 Rev Bdated 24th of June 2013Prior to installation of this change/...	05/11/2018	Active	10045537
10045559	HONEYWELL INTERNATIONAL, Inc.	REV. 1	FAA STC ST02696NY	GULFSTREAM G-IV	Installation of Sky Connect Forte Iridium Satellite phone trackingsystem with Network GatewayRevision 1: Transfer to new STC-Holder Honeywell International, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC FAA ST02696NY, reissued 18th November 2010Sky Connect LLC Certification Plan, Doc. No. CP-2009-400, Revision D,dated 22nd March 2010Sky Connect LLC Installation Drawing List Doc. No. GIV-2009-100-1,Revision A, dated 7th October 2009Sky Connect LLC Installation Instructions Doc No. GIV-2009-1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/05/2015	Active	10045559

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045562	TELAIR INTERNATIONAL Inc.		FAA STC ST02148LA	767-300BCF	Installation of Cargo Handling System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Telair International Index List, ER196100, Revision A, 05/06/2008or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Only applicable to B767-300 PAX a/c modified to a Boeing ConvertedFreighter (B767-300BCF).Prior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse eff...	04/07/2013	Active	10045562
10045599	ASI INNOVATION			L-1329 (JETSTAR 731)	Replacement of Flight Management System in accordance with ServiceBulletin ASI-SB-L1329-3400-0135 Rev. 2	14 CFR Part 25, Amdt 136, IAW ASI-CCL-0135-01	Servive Bulletin ASI-SB-L1329-3400-0135 Rev. 2AFM Supplement ASI-AFM-0135-00ICAs ASI-MPS-0135-00Technical File ASI-SDL-0135-02or later revisions of the above listed documents approved by EASA	Approval Limited to Airplane LOCKHEED L-1329 MSN 5092Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willintroduce noadverse effect upon the airworthiness of the pro...	05/07/2013	Active	10045599
10045652	EUROCOPTER CANADA Ltd.	REV. 1	TCCA SH10-20	EC130B4	Operation with the following cabin door configuration: LH pilot doorclosed, LH sliding door open and locked, RH doors/ panel removedThis STC is the validation of TCCA STC SH10-20 (Issue date April 22,2010)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Eurocopter Canada Limited Flight Manual Supplement FMS-ECL-137 rev. 0or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Eurocopter Canada Limited Instructions for Continued AirworthinessICA-ECL-...	This approval of operation with cabin doors / panel removeddoes notconstitute approval of installation of those doors / panel beingremoved. Installation of all doors / panels being removed in order toobtain the configuration covered by this approval shall be covered bydedicated EASA approvals.Prior...	12/07/2013	Active	10045652
10045658	AIRCRAFT CABIN MAINTENANCE GmbH			737-900, 737-900ER. 737-600, 737-700, 737-800, 737-300, 737-400, 737-500, 737-100, 737-200, 737-200C,	Installation of refurbished Passenger Seat Belt P/Ns 27741-2-01-40 andEPA 27741-2-01-60 on 16g seats	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Refer to Master Document List E/O No. 126-1003837 Rev. 0 (21.06.2013)or later revisions of the above listed documents approved by EASA.	As per Service Bulletin No. 126-1003837 SEB 06 00, latest revision.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthin...	10/07/2013	Active	10045658
10045665	STANDARD AERO		FAA STC ST03225CH	ERJ 170-200 STD ERJ 170-200 LR ERJ 170-100 STD ERJ 170-100 LR	Installation of a portable emergency locator transmitter (ELT) andmodification of interior placards.EASA validation of Basic FAA STC ST03225CH.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Standard Aero Master Data List 1024554, Revision (C), datedJune 25,2013or later revisions of the above listed documents approved by EASA.	None	10/07/2013	Active	10045665
10045666	AVIONIK STRAUBING ENTWICKLUNGS GmbH			B200, B200C, B200GT, B200CGT	Installation of Universal Avionics UNS-1E NCU, Config Module and SSDTU.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Avionics Straubing modification refASR-2013-051 Am 00 dated 15/05/2013;Operate in accordance with Avionics Straubing Flight Manual Supplementref ASR-2013-051-FMS-05-00 dated 15/05/2013;Maintain in accordancewith Avionics Straubing ICA refASR-2013-051-ICA-11-00 Am 00o...	None	10/07/2013	Active	10045666

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045671	AMERICAN AIRLINES, Inc.		FAA STC ST10486SC-D	757-200	Interior reconfiguration, new lavatories and In Flight EntertainmentEquipment upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Forapplicable regulations refer to FAA STC ST10486SC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	-Master Date List, American Airlines document No. F1470-MDL, Revision G,9 October 2012-Instructions for Continued Airworthiness, American Airlines documentNo. F1470-ICA, Revision C, 26 March 2012-Aircraft Flight Manual Supplement, AmericanAirlines document No.F1470-AFMS<(>,<)> Revision B, dated 9 O...	This STC requires an Alternative Method of Compliance (AMOC) withAirworthiness Directive (AD) 2008-10-11. The installermust obtain anAMOC with AD 2008-10-11 before installing this STC.This modification requires the floor mounted EmergencyPath LightingSystem in accordance with STC Number ST09476SCa...	11/07/2013	Active	10045671
10045675	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA2150NM	CESSNA 500, 550, S550, 560	Rosen Sunvisor SystemMonorail mounted cockpit sunvisor	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rosen Sunvisor Systems, Drawing List R500S-00DL, revision G, dated 22January 2009Rosen Sunvisor Systems, Installation Instructions for Cessna CitationMonorail Sunvisor System KitR500S-010-1, Doc. 9041-0126-001, rev D,date 21 January 2009.Rosen Sunvisor Systems, Installation Instructions for Cessn...	None	11/07/2013	Active	10045675
10045732	AVIONITEC Ltd.			PA-34-200	Dual GNS upgrade to WAAS Units incl. LPV CertificationCompliance showing to AMC20-28 that the installed equipment is suitablefor RNAV (GNSS) Approaches down to LPV Minima.Compliance showing to AMC20-27, resp. CRI F-10 (Airworthiness Criteriafor RNAV Equipment supporting APV BARO VNAV approaches to L...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List: 1418-17, dated 28.05.2013Instructionsfor continued airworthiness: 1418-015, dated 15.04.2013Airplane Flight Manual Supplement: 1418-011, dated 23.02.2013or later revisions of the above listed documents approved by EASA.	S/N: 34-7350164 HB-LQJThe approval holder shall fulfill the obligations of Part 21 §21.A118.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no advers...	15/07/2013	Active	10045732
10045753	DELTA ENGINEERING CORPORATION		FAA STC ST02044NY	777-200	Installation of Panasonic Avionics Corporation System 3000ipassengerentertainment system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Certification basis for this type design change isTitle 14 CFR Part 25including amendments 25-1 through 25-112<(>,<)> equivalent of JAR 25Change 13 for the following: 25.3...	Master Drawing List, Delta Engineering document No. 0143-05393-2074,Revision E, dated 15 April 2005.Instruction for Continued Airworthiness, Delta Engineering document No. 0743-05399-2074, Revision A, dated 3 January 2005or later revisions of the above listed documents approved by EASA inaccordance w...	FAA STC ST01493SE, appropriately approved in accordance with TechnicalImplementation Procedures of EU/USA Bilateral Agreement, is required tobe installed as a prerequisite for accomplishment this STC.Prior to installation of this design change it must be determined thatthe interrelationship betweenp...	16/07/2013	Active	10045753
10045765	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 2		551 (CITATIION II) 501 (CITATION I)	Single/Dual Installation of GPS/COMM/ NAV System Garmin GTN650/750	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 3 (not required by 21.A.101) 301,303, 305, 307, 365,561, 571, 575, 603, 605, 607, 609, 611, 613, 671, 771, 773, 843, 863,867, 1301, 1309, 1321, 1322, 132...	Flight Manual Supplement ASR-2013-018-FMS-05-00, Rev. 00or later revisions of the above listed documents approved by EASA.Instructions for Installation ASR-2013-018-IFI-10-00, Rev. 00 or laterapproved revisionsInstructions for Continued Airworthiness ASR-2013-018-ICA-11-02 (Rev.02) dated 12th April...	The aircraft must have been already equipped with (a) suitable E-HSI(s).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	30/08/2017	Active	10045765

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045766	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		501 AND 551	Installation of dual E-HSI Sandel SN4500 and single E-ADI Sandel SN4550	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23, Amendment 3 (notrequired by 21.A.101) 307, 561, 575, 603, 605, 607, 609, 611, 613, 771,773, 863, 867, 1182, 1301, 1...	Flight Manual Supplements:- ASR-2013-021-FMS-05.1-00, Rev. 00- ASR-2013-021-FMS-05.2-00, Rev. 00or later revisions of the above listed documents approved by EASA.Instructions for Installation ASR-2013-021-IFI-10-00, Rev. 00 or laterapproved revisionsInstructions for Continued Airworthiness ASR-2013-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/07/2013	Active	10045766
10045814	BOLDER MANUFACTURING L.L.C.		FAA STC ST03233CH	767-300BCF	Installation of Galley F5	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Bolder Manufacturing Master Data List, MDL-BM0804D01M2, Revision B,18/04/2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral A...	None	19/07/2013	Active	10045814
10045816	B/E AEROSPACE, Inc. - FSI		FAA STC ST02169SE	747-400	Interior reconfiguration of KLM B747-400 Aircraft Installation ofBusiness Class Ottomans, a new Closet, new Class Divider, modificationof Pilot Crew Rest, new Stowage Bin and new Upper Deck DecompressionVenting.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:14 CFR Part 25 at amendment 25-54:25.365(e)(2), (g)25.571 (a)(b)EASA CS25 Amendment level 12:25.365(a), (b),(c),(d)25.61325.853 (a)(c)(d) 25.869(a)(1)(4)25.1529The requiremen...	B2FS202-D01, Revision J, 10 July 2013 - Master Drawing ListB2FS202-D10, Revision B, 11 July 2013 - Certification PlanB2FS202-D15, Revision IR, 09 May 2013 - Instructions for ContinuedAirworthinessB2FS202ST-01, 11 July 2013 - Applicant Statement of Complianceor later revisions of the above listed doc...	This STC is a prerequisite of the KLM STC with project number0010018346-001.The following STC's should be installed simultaneously:STC EASA.IM.A.S.03182, Delta Engineering - Update of Panasonic IFE/ISPSS configuration (amendment of previous approved EASA STCEASA.IM.A.S.03182 / FAA STC ST02215NY-D)<(...	19/07/2013	Active	10045816
10045818	ATI ENGINEERING SERVICES, LLC	REV. 2	FAA SR02443NY-D	S-92A	Night Vision Goggle (NVG) compatible Lighting System.Revision 1: Modification of cockpit, cabin and external lighting systemsto be compatible with the use of night vision goggles in all phases offlight.Revision 2: Inclusion of additional NVIS configurations.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS29 Amdt. 2: 29.1,29.25(a), 29.610(a)(b)(d), 29.771(a), 29.773(a)(2), 29.777,29.853(a)(3)(4), 29.1301, 29.1309(a)(b)(2)(c...	Rotorcraft Flight Manual Supplement, Document No. FMS-100511.EASA, Rev. 1;Installation/Manufacturing Drawing List, Document No. IDL-100511, Rev. 21;Instructions for Continued Airworthiness, Document No. ICA-100511, Rev.11;Instructions for Continued Airworthiness, EASA Supplement S-1, DocumentNo. ICA-1...	Installation of NVIS/NVG compatible lighting does not include or implyapproval for flight operations with Night Vision Goggles (NVG). Theoperator must receive approval from the Civil Aviation operationalauthority to operate with NVG.Rotorcraft modified by this design change employs Night Vision Imag...	06/09/2019	Active	10045818
10045827	SCANDINAVIAN AVIONICS DESIGN ApS			ATR 42-500 ATR 42-400 ATR 42-320 ATR 42-300 ATR 42-200	Installation of Universal UNS FMS System.This STC installs a new fully integrated navigation and flightmanagement system, identified as Universal UNS-1Lw, interfaced with EFISwithor without Advisory Vertical Guidance displayed on EHSI.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt 4 (Cf applicable paragraphs identifiedthrough ComplianceRecord document, ref. 2080925-COR)The requirements for environmental protection and the associatedcerti...	Master Document list, ref : 2080925-DOC issue 1, dated 19/07/2013;FMS Configuration with advisory VNAV : Aircraft Flight ManualSupplement, ref : 2080925-AM A Issue 2;FMS Configuration without advisory VNAV : Aircraft Flight ManualSupplement, ref : 2080925-AM B Issue 2;Instruction for Continued Airwo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/07/2013	Active	10045827

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045832	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 6		777-300ER	First Class Cabin Refresh of Cathay Pacific Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List, Northwest Aerospace Technologies, Inc. documentNo. N0407-D10, Revision D, dated 16 December 2014.-Flight Manual Supplement, Northwest Aerospace Technologies,Inc.document No. N0407-D80, Revision B, dated 12 December 2014.-Instructions for Continued Airworthiness, Northwest Aero...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/02/2017	Active	10045832
10045833	RUAG AEROSPACE SERVICES GmbH			DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Cargo Seat Bag Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-01-(0010022580)- The following paragraph(s) at a later amendment: CS 25.853 Amdt 12The requirements for environmental protection and the as...	- Master Document List 411A-MDL Rev. N/C dtd. 18.07.2013- AFM Supplement 411A-AFMS Rev. N/C dtd. 14.06.2013or later revisions of the above listed documents approved by EASA.	per AFM Supplement 411A-AFMS Rev. N/C dtd. 14.06.2013Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the pr...	22/07/2013	Active	10045833
10045837	RUAG AG	REV. 1		A109E A109	RUAG UNS-1Lw A109Universal UNS-1Lw FMS and Thommen Air DataSystem AD32 InstallationRev 1: Transfer of STC to a new legal entity that is holder of a new DOA(EASA.21J.760)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement for A109E with Universal FlightManagement System (FMS) UNS-1Lw and Thommen AD32 AirData Display,Reference 1894714-50, Revision 002, dated 15.07.2013Master Documents List 1894714-00, Revision 001, dated 23.07.2013Instruction for Continued Airworthiness, Revision 0...	S/N 11106Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	18/01/2021	Active	10045837
10045841	DELTA ENGINEERING CORPORATION		FAA STC ST03172NY	747-400	Installation of Bruce Aerospace Emergency Path Lighting System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ODA-2350-01, Revision A, 3 May 2013 - Project Plan6607-08432-2350, Revision -, 10 July 2013 - Applicant Statement ofCompliance0107-08433-2350, Revision A, 10 July 2013 - Master Data List0707-08434-2350, Revision A, 03 July 2013 - Instructions for ContinuedAirworthinessor later revisions of the above...	This STC is a prerequisite of the KLM STC with project number0010018346-001.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the a...	24/07/2013	Active	10045841
10045862	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	757-200, 757-200PF, 757-300	Introduction of TCAS 2000 v7.1Revision 1 approves both ACASII change 7 and change 7.1 aspects of aTCAS 2000 system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0096 Issue 1 (757-300 series aircraft)- STC Twenty One Ltd Flight Manual Supplement No. S21.FMS - 0098 Issue 2 (757-200 series aircraft)- STC Twenty One Ltd Supplement Manual - ICA No. S21.TEC-0338 Issue 3- STC Twenty One Ltd Master Document Li...	This Revision 1 to EASA STC 10045862 is applicable to aircraft with EASASTC 10033170 installed and approves changes equivalent to those approvedunder FAA STCs SA3964SW-D and SA3235SO.This design change does not activate or approve ACAS II HybridSurveillance.Operational limitations of the TCAS are co...	04/11/2019	Active	10045862

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045863	AIRBUS TRANSPORT INTERNATIONAL SNC	REV. 2		A300F4-608ST	Modification ST25MOD069 issue 1, "Installation of a 6th seat in thecockpit".This approval covers also approval of the following modifications< (>,<)>ST35MOD006 issue 3 "Oxygen supply for 5th and 6th occupant"ST53MOD014 issue 1 "FR10.7, reinforcement of the pressure bulkhead"ST53MOD015 issue 1 "reinfo...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-301 OccupancyThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product a...	Airbus Transport International AFM Supplement "Appendix AF - Sixth Seatin the cockpit ST25MOD069" dated 10 January 2014or later revisions of the above listed documents approved byEASA.	- Aeroplanes converted by this STC must be operated in accordance withthe latest approved copy of the following documents:Airbus Transport International AFM supplement, "Appendix AF - Sixth Seatin the cockpit ST25MOD069"- DGAC France STC No. ST25MOD001 is a pre-requisite to ATI modificationST25MOD06...	20/05/2014	Active	10045863
10045868	KLM ENGINEERING & MAINTENANCE			747-400	KLM 747-400 cabin reconfigurationReplacement of Business Class seats with new, full-flat Business Classseats + related changes to cabin furniture to accommodate the new cabinlayout.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-GEN02 PTC - Application of heat releaseand smoke density requirements to seat materials- the following paragraph(s) at a later amendment:CS 2...	EA 012613, Revision 2, 10 July 2013 - Certification PlanICA-747-012613-001, Revision Org, 15 July 2013 - Instructions forContinued AirworthinessMDL-012613, Revision 2, 25 July 2013 - Master Data ListCE-18552, Revision 2, 25 July 2013 - Compliance Check ListEA012613, Revision 5, 25 July 2013 - Declar...	EASA Project number 0010018346-001 (added for reference purposes for theprerequisite STC's)The following STC's should be installed simultaneously:STC EASA.IM.A.S.03182, Delta Engineering - Update of Panasonic IFE/ISPSS configuration (amendment of previous approved EASA STCEASA.IM.A.S.03182 / FAA STC...	25/07/2013	Active	10045868
10045880	JET AVIONICS AVIATION & MARINESERVICE CENTER S.r.l.			PA-31T CHEYENNE II	General Avionics Improvements/ Installation/Replacement of COMM/NAV/ GPS,TAWS/RMI, EHSI	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS23.561, 571, 573,867, 1309, 1311, 1321, 1322, 1431, 1529 attheir initial amendment.The requirements for environmental p...	Master Drawing List BDI 002-10-01 Ed. 1, Rev. 2 16.07.2013Maintenance Manual Supplement (ICA-ALS) BDI 002-10-14 Rev. 1 17.04.2013FMS for GNS-530, Doc. BDI 002-10-16/1 Rev. 0FMS for ST-3400, Doc. BDI 002-10-16/2 Rev. 1FMS SN 3308, Doc. BDI 002-10-16/3 Rev. 0MMEL Update BDI 002-10-17 Rev. 1or later re...	Applicable only to S/N 8020038	25/07/2013	Active	10045880
10045881	AERODATA AG			B300	Installation of Aerodata Flight Inspection System AD-AFIS-261.	The Certification Basis for the original product remains applicable foritems not affected by the modification, for items affected by themodification the following new Certification Basis is elected to complywith: CS-23 Amdt. 3, except 23.561 and 23.785 (kept FAR 23.561 Amdt. 34and FAR 23.785 Amdt. 3...	Installation in accordance with Master Document List, Aerodata Doc. No.MDL-A/ C-840, Rev. 1, dated 19 July 2013;AircraftFlight Manual Supplement, Aerodata Doc. No. AFM-134, Rev. 0,dated 05 June 2013;Aircraft Maintenance Manual Supplement, Aerodata Doc No. AMM-1137, Rev.0, dated 18 July 2013;or later...	Only applicable for Serial FL-721	26/07/2013	Active	10045881
10045899	BOMBARDIER AEROSPACE		TCCA P-LSA05-163/D	BD-100-1A10	Installation of a Digital Voice Check-List Management System inaccordance with Master Document List BAS68010006 rev A dated November 3,2005	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Bombardier Business Aviation Services BBAS Master Document ListBAS68010006 rev A dated November 3, 2005- Amtech Aeronautical Limited (AAL) Flight Manual Supplement FMS388401rev IR dated 28 October 2005- Instructions for Continued Airworthiness and supplemental maintenanceinformation BAS68010006-IF...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/07/2013	Active	10045899

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045901	SABENA TECHNICS BOD	REV. 4		A318-112	Installation of cabin systems upgrade:- Satellite communication system avionics and antenna-Satellite Live TV system-In Flight Entertainment and Cabin Management system-New humidifier system-Removal of structural limitations	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-5310-010 "Glass Displays / Monitors"Deviation(s): CRI D-5305-010 "Firm Handhold"The requirements for environmental protection and the associate...	Modification Approval Sheet MAS-S-00-2294, Issue 6, dated 20/02/2014Master Drawing List MDL-S-00-2294, Issue C, dated 19/02/2014Instructions for Continued Airworthiness ICA-D8004-00-001, Issue B,dated 20/01/2014Damage Tolerant Airworthiness Limitation Items ALS-D-8004-00-004, IssueC, dated 29/07/201...	The approval is limited to MSN 2910.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	28/02/2014	Active	10045901
10045906	E A D AEROSPACE AIRWORTHINESS			737-900, 737-900ER. 737-600, 737-700, 737-800,	Activation of the GSM capability using the Triagnosys GSM Connexsolution.	The applicable certification basis (CB) is the one of the B737-900ER(JAR 25 change 15).The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remainapplicable to this certificate/ approval.	Master Drawing List 01397-EAS-A-MDL rev CAircraft Flight Manual Supplement 01397-EAS-A-AFM-01 revAInstructions for Continuous Airworthiness Supplement 01397-EAS-A-ICA-01rev Cor later revisions of the above listed documents approved by EASA.	- This approval is limited to the aircraft configurations identified indocument 01397-EAS-A-AEL-01 (last revision)- Airworthiness limitations as per 01397-EAS-A-ICA-01 rev CPrior to installation of this design change it must be determined thatthe interrelationship between this design change and anyp...	26/07/2013	Active	10045906
10045910	EAD INC.		FAA STC ST02134CH	MD-11F MD-11	ELT Installation.Installation of an ELTA ADT 406 AF/AP or ELTA A06V2 Emergency LocatorTransmitter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For Emergency Locator Transmitter ELTA ADT 406 AF/AP in Model MD-11F:- Certification Plan DC103-0670-00, Revision A, 26August 2004- Master Data List 00670-FAA-A-MDL, Revision C, 21 November 2005<(>,<)>- AFM-S DC304-0670-00, Issue A, 28 January 2005<(>,<)>- ICA DC303-0670-00, Revision B, 21 March 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/07/2013	Active	10045910
10045940	ROCKY MOUNTAIN AIRCRAFT		TCCA SA96-110	DHC-6 SERIES 300	Installation of PT6A-34 engines derated to 620 SHP on DHC-6Series 300in accordance with TCCA STC SA96-110.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Flight Manual Supplement FMS966401, Issue 1, TCCA approved August 1,1996Maintenance Manual Supplement MMS966401, Issue 1, TCCA approved August1, 1996or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agre...	Limited to serial numbers 130, 210, 231 and subsequent,,Theinstaller must determine whether this design change is compatiblewith previously approved modifications.If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writte...	30/07/2013	Active	10045940
10045947	ST ENGINEERING AEROSPACE LTD.			A330-343	Air Asia X Airbus A330-343 Passenger Compartment Reconfiguration.Certification Plan 395/ QAD/001, Air Asia X Airbus A330PassengerCompartment Reconfiguration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification plan: P395/ QAD/001, rev J-Master Drawing List: ref 39500000, rev D-Air Asia X A330 Passenger CompartmentReconfiguration ComplianceSummary Report: ref P395/QAD/ 003,rev C-ICA: P395/AED/ 001, rev -or later revisions of the above listed documents approved by EASA	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of theproduct.EEPMS approved through FAA STC ST02248AT and EASA ST...	31/07/2013	Active	10045947

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045949	SCANDINAVIAN AVIONICS DESIGN ApS			SA365 N1 SA365 N AS365 N3 AS365 N2	RDR-1400C Weather Radar Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS29 Amdt 3 all paragraphs except:-,,29.337: FAR29Amdt 16-,,29.561: FAR29 Amdt 16The requirements for environmental protection and the associatedcertified noise and/ or e...	2082416-AM issue 3 (RFM SUPPLEMENT) (29.07.2013)or later revisions of the above listed documents approved by EASA.2082416-DOC issue 1 (Certification documents list) (30.07.2013)2082416-EO issue 1 (Engineering Order) (30.07.2013) 2082416-CORissue 2 (Compliance Record) (16.07.2013)2082416-JS issue 1 (...	Weather Radar System MUST BE turned to "STBY" or "OFF" whenon theground.Prior to installation of this design change itmust be determined thatthe interrelationship between this design change and any otherpreviously installed design changeand/ or repair will introduce noadverse effect upon the airw...	02/08/2013	Active	10045949
10045954	N2 DEVELOPMENT Inc.		FAA ST02466LA	737-900ER	Installation of cabin interior noise reduction system in configuration"-3" aircraft (see MDL referenced below).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List (MDL) N2002 revision I dated May 15th, 2013Maintenance Manual Supplement N20020301 rev 002 dated March27th, 2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Tec...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/07/2013	Active	10045954
10045968	AVIONICS DESIGN SERVICES LTD.		TCCA STC SA 12-56	DHC-8-401/-402 DHC-8-301/-311/-314/-315 DHC-8-102/-103/-106/-201 /-202	Apple iPad EFB Class 2 Provisions	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with TCCA approved Avionics DesignsServices Ltd. Master Drawing List MDL 11077, Revision C.Operation must be in accordance with TCCA approved Avionics DesignsServices Ltd. Flight Manual Supplement FMS 11077-1, Revision N/ C.Maintenance must be in accordance TCCA app...	Suitability of provisions has been demonstrated for Apple iPad 1, 2 and3This STC does not constitute an Operational Approval. IndividualOperational Approval must be issued by the appropriate NAA.Prior to installation of this design change it must be determined thatthe interrelationship between thisp...	01/08/2013	Active	10045968
10045970	LANITZ-PRENA FOLIEN FACTORY GmbH	REV. 12		SEE EASA APPROVED MODEL LIST	Application of ORATEX aircraft covering system.Rev. 12 includes the ORATEX WET covering system as additional option	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 23.1, CS 23.29, CS23.251, CS 23.301, CS 23.303, CS 23.305, CS 23.307, CS 23.575, CS23.601, CS 23.603, CS 2...	- Application of ORATEX covering & coating system, Doc. No.ADxC-51-C0-001, issue M, dated 5th March 2020- ORATEX Application Manual & Airplane Maintenance Manual Supplement- Doc. No. ADxC-51-001-AMM Edition 8.0, dated 6th March 2020- ADxC-51-910-MDL issue A dated 17 June 2025- ADxC-51-910-AMM, ed. 1...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2025	Active	10045970
10045974	SABENA TECHNICS BOD	REV. 11		A330-341, A330-342, A330-343 A330-323/-341/-342/-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-301/-302/-303/-321/-322 A330-223, A330-243 A330-201, A330-202, A330-203 A330-201/-202/-203/-223/-243	IAGOS MODIFICATIONIntegration of routine Aircraft measurements into a Global ObservingSystem with two possible configurations: - IAGOS system activated - IAGOS system de-activatedThe Revision 1 extended the applicability of the modification, by addinga new MSN.The Revision 2 extended the a...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Document List MDL S-00-2275-01 Issue D- Aircraft Flight Manual Supplement AFM-S-F3034-00-01 Issue 11- Instruction for Continued Airworthiness ICA-F3034-00-05 issue Dor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The modification is applicable to the following aircraft Serial Numbers:MSN 421, 861, 989, 1259, 657, 838, 636, 997 and1835.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repaire...	11/09/2023	Active	10045974

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10045983	AIRBUS S.A.S.	REV. 1		A319-115	Airbus Corporate Jet Centre Modification CJ1620 - "MASTER MOD CJ - RELIANCE"Revision due to update of AFM-S	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A-4301-019 "ACJC Project Certification Basis".Special Condition(s): CRI H-01 - ICAon EWISThe requirements for environmental protection and the...	-,,Modification Approval Sheet, ref.: CJ1620, Issue 2, dated 24thOctober 2013-,,Airplane Flight Manual - AFM Supplement, ref.: FM-S MOD CJ1620, dated1st October 2013-,,MaintenancePlanning Document - MPD Supplement<(>,<)> ref : MPD-SMOD CJ1620, dated June 2013or later revisions of the above listed...	This STC is limited to MSN 2837.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	25/10/2013	Active	10045983
10045993	TESTORI AERO SUPPLY S.R.L.			777-200ER	Y/C CUSHION FOAMS & FABRIC SEAT COVERS KIT[Replacement of Y/C CUSHION FOAMS & FABRIC SEAT COVERS with new onedesigned and manufactured by Testori Aero Supply (TAS) ON B777 A/Cequipped with Recaro Seats.]	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,MASTER DOCUMENT LIST DOC. TAS-UN-STC-MDL-01 REV. 2 DATED25/07/2013-,,MASTER DRAWING LIST DOC. TAS-UN-STC-MWL-01 REV.0 DATED 12/05/2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/08/2013	Active	10045993
10045998	B/E AEROSPACE, Inc. - FSI		FAA STC ST02156SE-D	A330-300 A330-200	Installation of an interior Reconfiguration.ZONE A - FIRST AND BUSINESS CLASSInstallation of a new underbin closet, newVCC and new F/C and B/C seatsZONE B - TOURIST CLASSInstallation of new T/C seats, outboard closets forward of Door 2L and2R, rearrangement of existing outboard stowage bin and endc...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	. Certification Plan A8FS804-D10-EASA, rev A. MASTER DRAWING LIST, ref A8FS804-D01, rev AC. ICA A8FS804-D15, rev D. AFMSupplement, TP08-804AFM, rev 2. FAA Letter 150S-13-226, dated on 25th July 2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decisiont...	1) Prior to installation of this modification it must be determined thatthe interrelationship between this modificationand any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of the product.2) Incorporation of Airbus Service Bulletins A330...	05/08/2013	Active	10045998
10046006	MID-CANADA MOD CENTER		TCCA STC SA11-6	MF50	TrueNorth Avionics Express WiFi system installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Avionics Design Services Ltd Master Drawing List MDL10094 Rev C, datedMarch 30, 2011.-Mid Canada Mod Center Flight Manual Supplement FMS10094-1 Rev B<(>,<)>dated March 30, 2011.-Mid Canada Mod Center Instructions for Continued AirworthinessICA10094-1 Rev B, dated March 30, 2011.or later revisions o...	None	05/08/2013	Active	10046006
10046011	ASPEN AVIONICS, Inc.	REV. 5	FAA SA10822SC	SEE FAA APPROVED MODEL LIST SEE FAA AML SA10822SC	Option 1 - Installation of EFD1000 Primary Flight Display.Option 2 - Installation of EFD1000/EFD500 Evolution Flight Display(s)SystemOption 3 - Installation of EFD1000 E5 system	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): ESF-F23.1311-01 (For FAA ELOSSA02949A-A-S-1).EASA Certification Basis (Continuation):- The following paragraph(s) at a later a...	Option 1- Installation of EFD1000 Primary Flight Display inaccordancewith Aspen Avionics Installation Manual documentA-01-126-00, RevisionC, dated 3/28/2008Airplane Flight Manual Supplement document A-01-175-00, Revision B,dated 3/17/2008 or document A-01-179-00, Revision A, dated 3/17/2008<(>,...	Aircraft registered in countries under EASA authority are not eligiblefor installation of the CGlO0 "Connected Gateway"unit under FAA STCSA10822SC at this time.Activation of the Angle of Attack (AOA) indication is only permitted foraircraft with flaps.Installation of EFDl00 E5 system is approved fo...	21/12/2022	Active	10046011

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046017	ROCKWELL COLLINS, Inc.		FAA STC ST01547WI-D	750/800XP/850XP/900XP	Modification of Rockwell Collins FMS-6000 System Installation to provideSBAS/LPV Capability	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Rockwell Collins Master Drawing List(MDL) WAAS(SBAS) LPV in Pro Line 21 equipped HawkerAircraft refRCA-0166-001 Revision A, dated August 10, 2009.Operation in accordance with Rockwell Collins Airplane Flight ManualSupplements:- RCA-0224 (Hawker 750) Revision C, dated,...	DBU-4000 and DBU-4100 Data Base Units are incompatible withthe FMC-6000(Flight Management Computer) installed by this STC. Loading of the FMSdata base requires PCD-3000, CPAS, ora DBU-5000. If DBU data loadingcapability is required or desired, Rockwell Collins Inc, STC ST01431WI-D (EASA.IM.A.S.0270...	06/08/2013	Active	10046017
10046024	AIRCRAFT CABIN MAINTENANCE GmbH			SEE EASA APPROVED MODEL LIST	Installation of refurbished Cabin Attendant Restraint System P/ NEPA2121RS-4-03-XX on 16g seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Refer to Master Document List E/O No. 127-1003944 Rev. 0 (01.07.2013);or later revisions of the above listed documents approved by EASA.	As per Service Bulletin No. 127-1003944 SEB 06 00, latest revision.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthin...	07/08/2013	Active	10046024
10046038	AEROLITE AG	REV. 2		L45	EMS Equipment P/N 250-0023000-501- Addition of HIC Pad P/N 250-0032500-501- deletion of seat configuration restrictions	The Certification Basis for the original product remains applicable tothis certificate/ approval. The certificated noise and/ or emissionslevels of the original product are unchanged and remain applicable tothis certificate/ approval.	Flight Manual Supplement FMS-250-0023000-501, Rev B, of Dec19, 2013Airworthiness Limitation Section (Chapter 4) included in OperationsManual OPM-250-0023000-501, Rev A, of Dec 19, 2013or later revisions of the above listed documents approved by EASA.Configuration is controlled by:Master Document Li...	Design approval is valid from and including S/N 45-233 to and includingS/N 45-2000Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon...	21/02/2019	Active	10046038
10046041	MACH TECHNICAL DESIGN S.L.			A119, AW119MKII	Installation of an External Multipurpose Liquid Injection System withthe following main components: an external tank with attached pumpfixed to the belly of the helicopter, a control box installed in thecockpit and a remote control anchored to the cyclic stick.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS27 Amdt. 2: 27.1, 27.25, 27.27, 27.45, 27.65, 27.141, 27.143, 27.161,27.171, 27.173, 27.175, 27,177, 27,251,27.301, 27.303, 27.305(a), 27.307(a), 27.309, 27.321, 27.337,...	Rotorcraft Flight Manual Supplement, ref. FMS-FAA-0312 Rev.Original,dtd. 13/Jun/2013or later revisions of the above listed documents approved by EASAMaster Document List, ref. MDL-FAA-0312 Rev. D, dtd. 31/07/2013Orden Técnica, ref. OT-FAA-0312, Rev. D, dtd. 31/07/2013	When the External Multipurpose Liquid Injection System is installed, thenever-exceed speed Vne is limited to the value which results fromsubtracting 15KIAS from the never-exceed speed established in the BasicRotorcraft Flight Manual for each combination of altitude andtemperature.Prior to installati...	08/08/2013	Active	10046041
10046045	ROCKWELL COLLINS, Inc.		FAA STC SA01636WE-D	SEE EASA APPROVED MODEL LIST	Modification of a Rockwell Collins, Inc, VHF-4000 and VHF-4000EInstallations	As defined on FAA STC SA01636WI-DThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Rockwell Collins, Inc, Master DrawingList RCA-0359-001 as listed in the AML to this STC.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Imp...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	08/08/2013	Active	10046045
10046050	ASI INNOVATION SAS			F406	ASI-FAM-0010-01 - Replacement of the existing TBNL turret by the MX10turret.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplément Manuel de Maintenance ASI-MPS-0010-03 du 25 juillet 2013;Supplément Manuel de Vol ASI-AFM-0010-00 du 24 novembre 2010;or later revisions of the above listed documents approved by EASA.	Limitation to F406 serial number 0090.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	08/08/2013	Active	10046050

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046071	SABENA TECHNICS BOD			A319-133	Installation of a Cabin System Upgrade-,,In Flight Entertainment system-,,Cabin refurbishing-,,Cabin communication system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Approval Sheet MAS-S-00-2310, Issue 5, dated 09/08/2013;Master Drawing List MDL-S-00-2310, Issue B, dated 06/08/2013;Instructions for Continued Airworthiness ICA-D9046-00-001, Issue A,dated 02/07/2013;Airplane Flight Manual Supplement AFM-S-D9046-00-019, Revision 1, dated24/06/2013;or l...	The approval is valid for A319-133CJ MSN 1468 only.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produ...	12/08/2013	Active	10046071
10046079	NORTHERN AVIONICS S.R.L.			AW109SP	NAV 467 "Installation of Cabin WLAN and Web connection in the helicopterAW109SP"	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-RFM Supplement RFMS NAV-467or later revisions of the abovelisted documents approved by EASA.-Modification Bulletin NAV-467, Rev. 1 (including Compliance Checklist)-Ground Test Procedures (with Internet Sensor) NAV-467-005, Rev. 1-Flight Test Procedures (with Internet Sensor) NAV-467-006, Rev. 1-St...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	13/08/2013	Active	10046079
10046097	PMV ENGINEERING			B737-600/700/800/900/900ER	Boeing-CMC Class 3 EFB system Operating System installationon B737NG.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Investigation Report AVI-00450-CIR Rev.00;Instructions for continued airworthiness AVI-00450-ICA Rev.00;or later revisions of the above listed documents approved by EASA.	The installation of an EFB according to certificate 10044973 or10045157 is a prerequisite for the installation of the above-mentionedOperating System.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously instal...	14/08/2013	Active	10046097
10046100	A&M AVIONICS, SL			T310R	Installation of Dual System Garmin GNS530W in accordance withInstallation Bulletin BI 05/13	Other: 14 CFR Part 23 according to Certification Programme PC & MCU05/13The requirements for environmental protection and the associatedcertified noise and/ or emissions levels ofthe original product areunchanged and remain applicable to this certificate/ approval.	Installation Bulletin A<(>&<)>M Avionics IB 05/13Supplementto AFM A<(>&<)>M Avionics SMV 05/13or later revisions of the above listed documents approved by EASA	Approval limited to Airplane CESSNA T310R, S/N 310R-1408Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of theT...	14/08/2013	Active	10046100
10046101	AEROTEC & CONCEPT			MF50	F50 220V/50Hz installationDescription as per Associated Technical Documentation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List AE13119MDL Rev. 1, dated 02/08/2013.Certification Program AE13119PCDP Rev. 2, dated 11/07/2013.Safety Analysis AE13119AS Rev. 0, dated 03/06/2013.Electrical LoadsAnalysis AE13119ELA Rev. 0, dated 03/06/2013.Structural Analysis AE13119SA Rev. 1, dated 04/07/2013.Ground Test ProgramG...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	14/08/2013	Active	10046101

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046102 (EASA.IM.A.S.03108)	COMMUTER AIR TECHNOLOGY Inc.		FAA STC SA2735CE	BEECH 100 AND A100	Installation of External Lower Fuselage Cargo Compartment	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Installation in accordance with DeVore Drawing List Number100DL, FAAapproved dated July 2, 1991-Operate in accordancewith FAA approved Flight Manual Supplement, datedJuly 29, 1991, for Beech Models 100 and A100 with Commuter AirTechnology, inc. 60 Cubic foot external lower fuselage Baggage/ CargoC...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	14/08/2013	Active	10046102
10046106 (EASA.IM.A.S.02922)	ENGINE TECHNOLOGIES, Inc.		FAA STC SA5223NM	2. G36 1. V35B, A36TC, B36TC 1. F33A, G33, S35, V35, V35A 1. 35-C33A, 36, A36, E33A	Installation of modified Teledyne Continental engine equipped withTurbo-normalising System, optional Oxygen System and optional HartzellPHC-C3YF-1RF/F8068 propeller.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Installation in accordance with Tornado Alley Turbo Drawing List NumberTAT-B-MDL, Rev NC, dated September 29, 1999, orlater FAA approvedrevision.-Operate in accordance with Flight Manual Supplements as defined inLimitations and Conditions section.or later revisions of the above listed documents ap...	See EASA approved Annex	14/08/2013	Active	10046106
10046108	CAV AEROSPACE Inc.			B. G36 A. A36 (SERIAL E-2112 & AFTER)	Installation of TKS fluid Ice Protection System for flight into knownicing conditions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Aerospace Systems & Technologies (AS<(>&<) >T) Drawing List No 10300SL, Revision 3 datedFebruary 25, 2003.Operation in accordance with Supplement to Pilot's Operating Handbookand/or FAA Approved Flight Manual, Document No 10300-FMS, dated February26, 2003, or.Suppleme...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/08/2013	Active	10046108
10046109	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA STC SA12-63	BD-700-1A11 BD-700-1A10	Installation, Aircraft Completion Modifications.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-02 Issue 2, Side Facing Divans- Equivalent Safety Finding (s): CRI D-04 Issue 2, Emergency Exit Signs- Deviation(s):CRI D-01 Issue 2, Doors Be...	Transport Canada STC No. SA12-63 Issue 1, dated 17 October 2012;Innotech Aviation Configuration Definition Record CER-BD700-001 RevisionE;Innotech Aviation Airplane Flight Manual Supplement AFMS-IA6000-2500Revision A;Innotech Aviation Instructions for Continued Airworthiness documentGCXXXX0000-ICA (...	EASA approved configurations are identified in Configuration DefinitionRecord CER-BD700-001.The Wireless Local Area Network (WLAN) is intended to provide internetconnectivity and email services to the airplanes cabin using portableelectronic devices (PEDs). Any other intended function of thisequipm...	14/08/2013	Active	10046109
10046112	ALTRAN LABt/a AIRCAD			A330-243	A330-200 MSN 627 Cabin Reconfiguration - new seats and new IFE systeminstallation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List MDL-12007_Rev9, dated 24/07/2013;Instructions for Continued Airworthiness ICA-12007_Rev0, dated07/02/2013;Aircraft Maintenance Manual Supplement AMM-12007_Rev0, dated 04/02/2012;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/08/2013	Active	10046112

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046122	INFINION CERTIFICATION ENGINEERING	REV. 2	TCCA SA06-59, ISSUE 2	PA-31, PA-31-300 PA-31-350 (CHIEFTAIN) PA-31-325	Fuselage Camera Hole Cutout – Installation of fuselage camera hole,including20 inch x 20 inch opening and rerouting of elevator trim and rudder trimcables.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Infinion Certification Engineering Inc.Installation Instructions Piper Navajo Fuselage Cutout EO-1141-01, Issue5, dated 18 February 2019.Operation in accordance with Infinion Certification Engineering Inc.Flight Manual Supplement (PA-31, PA-31-300, PA-31-325, PA-31-35...	EASA has not certified the equipment for which these provisions areintended. You must get an additional EASA Approval to install suchequipment.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed chan...	19/11/2019	Active	10046122
10046138	AVIATION SUPPORT GmbH	REV. 3		BO105 S (VARIANTS CBS-4/-5) BO105 D (VARIANTS DBS-4/-5) BO105 D (VARIANTS DB, DB-4) BO105 C (VARIANTS CB, CB-4/-5)	Title: Camera Mount for BO105 VariantsDescription: Installation of a camera mounting device for fittingCineflex HD series (and equivalent) camera systems to the LH side of theBO105 landing gear.An existing step utility mount that already has an EASA approval for theEC135 series will be used as basis...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs at a later amendment: CS27 Amdt. 2: CS27.1,CS27.21, CS27.25, CS27.27, CS27.29, CS27.31, CS27.45, CS27.49, CS27.51,CS27.65, CS27.67, CS27.71, CS27....	- Flight Manual Supplement, ASE-91209, Camera Mount BO105, Revision 1-1or later revisions of the above listed documentsapproved by EASA.- Projektbeschreibung, ASE-91306, Camera Mount BO105 CB Series,PB-ASE-91306, Revision 0-1 dated 28th December 2014;- Liste der gültigen Dokumente ASE-91209, Camera...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/06/2015	Active	10046138
10046144	JET AVIATION AG	REV. 1		B737-700 737-700	Cabin Insulation Improvement as Defined in BB73725801-500_REV_A_ProjectDescription and MDL BB73725801-001 Master Data List.Rev. 1: Inclusion of CS 25.856 (a) compliance.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Engineering Order, Doc. No. BB73725801-500-258000, Rev. IR, 26.06.2013- Master Data List, Doc. No. MDL BB73725801-001Rev. D, 16.12.2021- Analysis Report, Doc. No. JBSL-M-03738ANA-001, Issue A, 03.12.2021- Flammability Test Report, Doc. No. JBSL-M-03738FLR-001, Issue A,03.12.2021- Declaration of C...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/12/2021	Active	10046144
10046149	SPECIALIST AVIATION SERVICESLIMITED	REV. 2	CAA UK RESPONSIBILITY	MD900 (902 CONFIGURATION)	Rev. 0 – MD902 NVIS (PAS/MOD/680). Modification of aircraftto enableNight Vision Imaging system (NVIS) certification using Class B NightVision Goggles.Rev. 1 – Addition of white phosphorous Night Vision Goggles inaccordance with SAS/MOD/800Rev. 2 – Administrative revision	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27.141, 771, 773,777, 1301, 1309, 1321, 1381, 1383, 1401, 1501, 1525, 1529, 1581, 1583,1585, plus FAA AC29.2C (Change 4...	Revision 0-Flight Manual Supplements FMS/680-002 Issue A, FMS/783-002 Issue B, andFMS/793 Issue Bor later revisions of the above listed documents approved by EASA.-Post installation Actions, document PIA/680-007 Issue B-Maintenance Programme Supplement MPS/680-008 Issue C-Drawing List DL/680-099 Iss...	Required Installation of EASA STC 10028376, Aerodynamix NVIS on MD900Installation of NVIS/NVG compatible lighting does not include or implyapproval for flight operations with Night Vision Goggles (NVG). TheOperator must receive approval from the civil aviation operationalauthority to operate with NV...	02/03/2017	Active	10046149
10046155	AMAC AEROSPACE SWITZERLAND AG			A319-133 (CJ)	Interior Outfitting on A319-133As defined in the:- Project Description, Doc. No. PD-BY01-2500, Rev. C, 12.08.2013- Master Data List, Doc. No. MDL-BY01-2500, Rev. C, 22.08.2013	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:Special Conditions:- CRI D-4302-015 Isolated Compartments- CRI D-4309-015 Improved Flammability Standard for thermal/acousticinsulation -...	- Master Data List, Doc. No. MDL-BY01-2500, Rev. C, 22.08.2013- AFMS, Doc. No. AFMS-BY01-2500, Rev. E, 22.08.2013- ICA,Doc. No. ICA-BY01-2500, Rev. A, 21.06.2013or later revisions of the above listed documents approved by EASA.	Galley G1 & G2 (Includes mechanical Installation and functional Movingof Galley Door) installed by the STC with the EASA Project Number Ref.: 0010021319-001Note: Door Status Indication, Frangibility and Decompression is part ofthe AMAC Cabin Interior Outfitting STC, for which this TV is issued andthe...	23/08/2013	Active	10046155

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046156	ROSEMOUNT AEROSPACE, Inc.	REV. 7	FAA ST02819CH	A330-343 A330-321/-322/-323/-341/-342 A330-243/-243F/-301/-302/-303 A330-201/-202/-203/-223/-223F A330-200/ -200F /-300	Installation of tablet Interface Module (TIM) Electronic Flight Bag(EFB) system.Rev. 5: among others, following changeswere implemented:- Configuration J: additional optional interface connection for theAID's existing Quick Access Recorder (QAR) flight data recorder datarecording feature- Configura...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25 Amdt. 25,Section 25.1319.The requirements for environmental protection and the associatedcertified no...	Master Data List (MDL), Rosemount Aerospace document numberD06404080Revision BL dated 14 January 2025.AFM SupplementsAirplane Flight Manual Supplements as identified in RosemountAerospaceMaster Data List, Doc No. D06404080, Revision BL dated 14 January 2025:- D06415251 Airplane Flight Manual Suppl...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.For Rosemount Aerospace Master Data List, Doc. No. D064...	22/04/2025	Active	10046156
10046157	ZODIAC AEROSAFETY SYSTEMS	REV. 1	TCCA SA99-261	DHC-8-301/-311/-314/-315 DHC-8-102/-103/-106/-201/-202	Installation of Aerazur Engine Inlet De-Icer Boot / Installation ofAerazur Engine Inlet De-Icer Boot, (PN: 51-SP-162-31-1)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness:Maintenance in accordance with respective DHC-8 Maintenance Manual andAerazur Component Maintenance Manual for P/N 51SP162 31-1, Revision 2.or later revisions of the above listed documents approved by EASA.Installation of Aerazur Engine Inlet De-Icer Boot P/N...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/10/2015	Active	10046157
10046164	AVIATION FABRICATORS, Inc.		FAA STC SA2847CE	CESSNA 208, 208B	Stretcher assembly with restraints and portable Ferno unit can beinstalled on existing cabin seat track on either side of the aircraftbetween FS 158.00 and FS 238.00 in accordancewith FAA STC SA2847CE.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions of Continued Airworthiness AF-507, Rev. B, dated October22, 2012;Drawing List AF-121, Rev. E, FAA approvedFebruary 19, 2013;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ orU...	This approval is applicable only to Cessna 208 and 208B cargo airplanesthat have a right hand cabin entry door or the Cessna kits installed topermit opening the left hand cargo door from inside the cabin.The installer must determine whether this design change is compatiblewith previously approved mo...	23/08/2013	Active	10046164
10046177	FIELD AVIATION EAST, LTD.	REV. 2	TCCA SA13-36	DHC-8-301/-311/-314/-315 DHC-8-201/-202 DHC-8-102/-103/-106	Flight Crew, Zodiac MF20-517 Full Face Oxygen/ Smoke Mask Upgrade (Introduction of AFMS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Installation must be in accordance with TCCA approved FACIMasterDrawing List designated 25780000, Revision B.-Operation must be in accordance with FACI Flight Manual Supplement25783000, IR.-Instructions for Continued Airworthiness:-Maintenance must be performed in accordance with TCCA accepted FAC...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	21/01/2014	Active	10046177
10046179	AIRBUS S.A.S.			A320-200	Airbus Corporate Jet Centre Modification CJ1467 - "MASTER MOD CJ - RAFO (Cabin & Systems Upgrade)"	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A-2301-009 "ACJC Project Certification Basis":Special Condition(s): CRI H-01 - ICAon EWISDeviation(s): CRI E-24 - Firm Handhold, CRI E-25 - He...	- Modification Approval Sheet, ref.: CJ1467, Issue 1, dated26th August2013- Airplane Flight Manual - AFM Supplement, ref.: FM-S MOD CJ1467, dated1st August 2013or later revisionsof the above listed documents approved by EASA.	This STC is limited to MSN 3723, MSN 4117 & MSN 4795.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willintroduce noadverse effect upon the airworthiness of the pro...	26/08/2013	Active	10046179

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046185	FOKKER SERVICES B.V.			DHC-8-401, DHC-8-402 DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103	Provisions for a Class 2 Electronic Flight Bag (EFB)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Reports CRR-0113, CRR-0138, CRR-0179or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/08/2013	Active	10046185
10046214	PMV ENGINEERING			A330-341 / -342 / -343 A330-321 / -322 / -323 A330-301 / -302 / -303 A330-223 / -243 A330-201 / -202 / -203	In-Flight Entertainment System Installation on A330.This STC installs IFE System, developed by the IMS Company.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Investigation Report, ref : SCA-00210-CIR Revision 5,dated 29 August 2013;Instruction for Continued Airworthiness, ref : SCA-00210-ICA, dated 16May 2013;or later revisions of the above listed documents approved by EASA.	1-,,The IFE system installation, defined in this STC, is only valid fora seat configuration identical to the one defined in PMV eng. Documentref : SCA-00210-CIR Revision 5, dated 29 August 2013.2-,,This STC does not constitute the approvalof the seat arrangement /installation, nor the implementatio...	30/08/2013	Active	10046214
10046218	LUFTHANSA TECHNIK AG			A321-212 / -213 / -231 / -232 A321-111 / -112 / -131 / -211 A320-231 / -232 / -233 A320-214 / -215 / -216 A320-111 / -211 / -212 A319-115 / -131 / -132 / -133 A319-111 / -112 / -113 / -114	Installation of HelioJet LED cabin light.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,Supplemental Type Definition Document STDD33-13/19M Issue 1 Rev 0dated 16/08/2013-,,Compliance Record List CRL33-13/19M Issue 1 Rev 0 dated 16/08/2013-,,Instructions for Continued Airworthiness A-00-13-41-ICA Issue 1 Rev0dated 14/08/2013-,,Applicant's Declaration of Compliance N. 3523 dated 16/08...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2013	Active	10046218
10046224	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 1		SA 365 N, SA 365 N1 AS 365 N2, AS 365 N3	Installation of the Helicom V2 ANA embedded Equipment.The Helicom V2 ANA consists of a recording/transmitter equipment offlight and system's parameters.Rev. 1: STC holder name change from I.S.E.I International Services toSAFRAN ELECTRONICS& DEFENSE BUSINESS UNIT - HELICOPTERS DATA MANAGEMENTSOLUTIO...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition: CRI F-01 Lithium Battery, dated 20/02/2013.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of...	Design Change Description N3-AS365 ANA-HV2-ANA-E-A-06 dated05/08/2013.Installation Manual N7-AS365 ANA-AS365-HV2-ANA-E-A-06 dated 05/08/2013.Maintenance Manual Supplement N8-AS365 ANA-AS365-ANA-E-A-06 dated05/08/2013.	The change does not replace standard maintenance records and pilotreporting. Any broadcasting must be done in accordance with Nationalregulations.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed d...	27/02/2020	Active	10046224
10046236	ALTRAN LABt/a AIRCAD	REV. 1		MF50	Thrane & Thrane TT-5006A IGA Satcom antenna installationDescription as per Associated Technical Documentation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List Ref. MDL-13002 Revision 2, dated 31/07/2013.Certification Program CP-13002 Revision 1, dated 31/07/2013.ICA Manual ICA-13002 Revision 0, dated 10/07/2013.AMM Supplement AMMS-13002 Revision 0, dated 03/07/2013.Change Approval Sheet CAS-13002 Revision 2, dated 23/08/2013or later revis...	None	24/09/2013	Active	10046236
10046307	AMAC AEROSPACE SWITZERLAND AG	REV. 1		A340-313	Interior Reconfiguration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): D-07 Glass Screens of Displays / Monitors- Deviation(s): D-06 Heat Release and Smoke DensityThe requirements for environmental protection and thec...	-Master Data List MDL-DF01-2500 Rev. B dtd 6. September 2013 as amendedby MDL-DF02-2500 Rev. B dtd 16. October 2014-Project Description Document PD-DF01-2500 Rev. E dtd. 5.September 2013-AFM supplement AFMS-DF01-2500 Rev. G dtd. 9. October 2014-Instructions of Continued Airworthiness ICA-DF01-2500...	-Limitations per AFM supplement AFMS-DF01-2500 Rev. G dtd. 9. October2014-The installation of this STC is limited to MSN 528-This STC does not constitute the approval of installations defined byFAA STC ref. ST10936SC dated 10 March 2009 that have not been modifiedor for which no new compliance demon...	22/10/2014	Active	10046307

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046326	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINE S.A.R.L.	REV. 1		PA-44-180	Certification for P-RNAV operations and RNP LPV approaches of anexisting avionics configuration based on Garmin GNS 430W system and G500EFIS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraphs at a later amendment: 23.1301, 23.1309,23.1321, 23.1322, 23.1329, 23.1353, 23.1525, 23.1581.The requirements for environmental protection and thec...	SEAM Flight Manual supplement n°SMV/ 3388/11 revision 2 dated 01/07/2013SEAM modification file n°33811/11 revision 2 dated 01/07/2013or later revisions of the above listed documents approved by EASA.	This STC is limited to aircraft s/ n 447995308By this STC, the aircraft is approved for BRNAV, PRNAV and RNPapproaches operations with coupling of the Garmin GNS 430 W and G500systems to the autopilot Altimatic IIIC.Prior to installation ofthis design change it must be determined thatthe interrelati...	12/09/2013	Active	10046326
10046342	AIRLIFT A/S			AB139, AW139	AB139/AW139 Installation of SX-5 Search Light on Short Noseconfiguration (DO-139-33-102).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aircraft Flight Manual Supplement doc. FMS-139-33-102-01 Rev. 0or later revisions of the above listed documents approved by EASA.- Master Document List doc. DO-139-33-102 Rev. 0- Instructions for Continued Airworthiness doc. ICA-139-33-102-01 Rev. 0	This STC is only applicable to AB/AW139 S/Ns from 31005 up to 31200(except 31007) and from 41001 to 41200.Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpreviously installed design change and/ or repair will introdu...	10/09/2013	Active	10046342
10046397	FOKKER SERVICES B.V.			A321-231, A321-232 A321-211, A321-212, A321-213, A321-111, A321-112, A321-131, A320-231, A320-232, A320-233, A320-214, A320-215, A320-216, A320-111, A320-211, A320-212, A319-132, A319-133, A319-114, A319-115, A319-131, A319-111, A319-112, A319-113,	Introduction of LEDs as a replacement of the existing PassengerCompartments Tube Lights.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan CP-0156 Issue 1Compliance Record Report CRR-0156 Issue 1Instructions for Continued Airworthiness report SE-760 Issue 1or later revisions of the above listed documents approved by EASA.	This STC is applicable to MSN 3151 and below only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produc...	16/09/2013	Active	10046397
10046398	B/E AEROSPACE, Inc. - FSI		FAA STC ST01492SE	747-400	Interior Reconfiguration Installation of first class seats and ottomans,minipod business class seats, VIP lavatories, sidewall credenzas, fullspectrum light system, electric window shades, In Seat Power SupplySystem, Video Control Center (VCC), overhead stowage bins, closets,class dividers, and all...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	A2FS238-D01, Revision T, 2013 August 16 - Master Drawing ListA2FS238-D10, Revision C, 2005 April 18 - Certification Plan A2FS238-D15,Revision IR, 2005 February 21 - Instructions for Continued AirworthinessTP2-238AFM, 2004 December 20 - Airplane Flight Manual Supplementor later revisions of the above...	The following STC's must be installed concurrently with this STC:- EASA STC 10042094 (FAA STC ST01514SE) - Lavatory andgalleymodificationEASA STC 10042191 (FAA STC ST02049NY) - Inflight Entertainment SystemThe following FAA approved B/E Aerospace SB must be installedconcurrently with this STC:- B3F...	16/09/2013	Active	10046398
10046400	ANUVU	REV. 2		747-400	Implementation of provisions for EFB Class 2 Provisions foruse ofdetachable Class 2 information system on both pilot stations.Rev. 2: Transfer of STC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 amdt 4: 25.25,25.27, 25.301(a), 25.303, 25.305(a)(b), 25.307(a), 25.321, 25.365(a)(d),25.561(b)(3)(c)(2), 25.571, 25...	-Engineering Order and Certification Plan AM005-46-20-EO, Rev. -, dated30/04/2013-Master Data List AM005-46-20-MDL, Rev. A, dated 11/07/2013-Aircraft Flight Manual Supplement AM005-46-20-AM, Rev. -, dated25/03/2013-Instructions for Continued Airworthiness AM005-46-20-CA, Rev. -, dated25/03/2013-Cert...	This approval covers only the Class 2 EFB mounting devices and theirpower and data connection to the aircraft. This approval does notconstitute an operational approval for the useof the EFB system.Prior to installation of this design change it must be determined thatthe interrelationship between th...	05/05/2021	Active	10046400

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046408	CHALLENGER AVIATION PRODUCTS INC.	REV. 1	FAA STC SA01669CH	SEE APPROVED MODEL LIST	Installation of Challenger re-usable air filter	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Challenger installation instructions 0402. Revision numberas per AML.Instructions for Continued Airworthiness 4003, revision D, dated August31, 2005or later revisions of the above listed documents approved by EASA inaccordance with EASAED Decision 2004/04/ CF (or subsequent revisions ofthis decis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/09/2013	Active	10046408
10046455	EIRTECH AVIATION SERVICES LIMITED	REV. 2		A321-271N/-271NX/-272N /-272NX A321-253N/-251NX/-252N X/-253NX A321-231/-232 A321-213/-231/-232/-251N /-252N A321-211/-212/-213 A321-111/-112/-131/-211/- 212 A321-111/-112/-131 A320-253N/-271N/-272N/- 273N A320-233 A320-231/-232/-233/-251N /-252N A320-215/-216/-231/-232 A320-211/-212/-214/-215/- 216 A320-111/-211/-212/-214 A319-153N/-171N A319-131/-132/-133/-151N /-152N A319-115/-131/-132/-133 A319-111/-112/-113/-114/- 115 A319-111/-112/-113/-114 A318-111/-112/-121/-122	Installation of Spectralux Dlink+ Controller Pilot Data LinkCommunication.Rev 2 includes A320 family NEO aircraft models and enables theutilisation of VHF 3 antenna position for datalink purposes.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): SC F-0311-001 Flight Recorders including DataLink Recording.- The following paragraph(s) at a later amendment: CS 25 Amendment 16:CS 25.1, CS 25.58...	- Master Document List – MDL/158-099 Issue 70, dated 22 April 2021- Declaration of Compliance – DOC/158, Issue 7, 22 April 2021- Flight Manual Supplement – Refer to MDL for applicable supplement.or later revisions of the above listed documents approved by EASA.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/04/2021	Active	10046455
10046466	SPECIALIST AVIATION SERVICES LIMITE		CAA UK RESPONSIBIL ITY	MD900	Internal Cargo Restraint System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:(By Elect to Comply); CS-27 (Amdt. 3); 1, 301, 303, 305, 307, 321, 337,341, 521, 561, 573, 601, 603, 605, 609,610, 611, 613, 785, 787, 853,855, 1301, 1525, 1529, 1541, 15...	Flight Manual Supplement: FMS/629-003 Iss. Aor later revisions of the above listed documents approved by EASA.Design Report; DR/ 629-001 Iss.ADesign Definition/Drawing list; PAS/629/099 Iss. AICA; MSS/629-004 Iss. A	902 configuration with PW 206E & 207E.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/09/2013	Active	10046466
10046468	AIRBUS S.A.S.	REV. 1		A319-115	Airbus Corporate Jet Centre – Modification CJ2054 –STC UPDATE FOR CABINMODIFICATION & DOOR LOCK INSTALL (Top Modification CJ1200 – VIP Project«BELAIR »)	The Certification Basis for the original product as amendedby theadditional or alternative airworthiness requirements as listed in theGeneral CRI A-4301-012 “ACJC Project Certification Basis”.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of...	- Modification Approval Sheet, ref. CJ2054, Issue 2, dated 8th March2016- Airplane Flight Manual - AFM Supplement, ref.: FM-S MOD CJ1200 Rev 02Issue OCT 01/15or later revisions ofthe above listed documents approved by EASA.	This STC is limited to MSN 4228	10/03/2016	Active	10046468

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046481	B/E AEROSPACE, Inc. - FSI		FAA STC ST02171SE	A340-600	Installation of Cabin Modification Provisions.Install new and modify existing electrical, structural and systemsprovisions only for the installation of a new cabin interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan B1FS115-D10, rev A- Master Drawing List, ref B1FS115-D01, rev N- ICA : Supplement To Instructions For Continued Airworthiness For TheInstallation Of Cabin Modification Provisions On Lufthansa A340-642Airplanes, ref B1FS115-D15, rev IR- FAA Letter 150S-13-289, dated on 20th Septo...	1) Prior to installation of this modification it must be determined thatthe interrelationship between this modificationand any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of the product2) ICA must be incorporated into the operator's ma...	25/09/2013	Active	10046481
10046517	AEROTEC & CONCEPT			PA-30	STC 13099 - installation GTN650	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Refer to AE13099PCDPrev. 1 for paragraphs at CS23 amdt3.The requirements for environmental protection and the associatedce...	AE130999ICA Rev 0 dated 07/05113 -Instructions for ContinuedAirworthinessAE 13099MDL Rev 2 dated 24109/13 - Master Drawing ListAE 13099SMV Rev 0 dated 29/08/13 • Airplane Flight Manual Supplementor later revisions of the above listed documents approved by EASA.	Limitation to PA-30 serial number 301251 and 301582.	27/09/2013	Active	10046517
10046518	ROW 44, Inc.	REV. 1	ST02258LA-D	757-200, 757-300	Installation of a Row 44 Wireless Broadband System Components and SystemActivation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, Row 44 document No. SIE-346-701, Revision K, dated27 May 2015- Airplane Flight Manual Supplement, Row 44 document No. SIE-346-604,Revision B, dated 15 January 2015- Instructions for Continued Airworthiness, Row 44 document No.SIE-407-603<(>,<)> Revision E, dated 20 March 2015or l...	This installation must be installed in conjunction with or after the Row44 Wireless Broadband Antenna System Provision installation FAA STCST02904CH validated by EASA.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherp...	15/09/2015	Active	10046518
10046519	SAFRAN CABIN GERMANY GmbH	REV. 1		A340-600	A340-600 DLH Galley Relocation.Description - Summary: The change is related to the Galley Relocation onLHT A340-600 aircraft for : G23, G24, G25, G26, G27 & Pelmet.Issue 1: ChangeRevision to conform Service Bulletin with type design oflower attachment of Galley Unit G23 and G24. The master document...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	-Certification Summary: CS-A-2011-066A Rev. D- Type Definition Document: TDD-1092L-25-06-07-08 Rev. D-ICA: ICAS-A-2011-066A Rev. Newor later revisions of the above listed documentsapproved by EASA.	1) Prior to installation of this modification it must be determined thatthe interrelationship between this modificationand any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of the product.2) This modification must be implemented in conju...	14/02/2014	Active	10046519
10046520	B/E AEROSPACE, Inc. - FSI		ST02170SE	A340-600	Lower Lobe Fixed Crew Rest Installation.The installation iscomprised of a new lower deck crew rest, cargoloading equipment andinstallation kit.	The Certification Basis for the original product as amendedby thefollowingadditional or alternative airworthiness requirements:Special Condition (s): D-01 : Lower Deck Crew Rest CompartmentInstallationThe requirements for environmental protection and the associatedcertifiednoise and/ or emissions le...	. Certification Plan B1FS102-D10, rev C.. Master Drawing List, ref B1FS102-D01, rev P.. ICA : Instructions For Continued Airworthiness, ref B1FS102-D15, revB.. AFM Supplement, TP11-102AFM, rev 2. FAA Letter 150S-13-288, dated on 26th September 2013or later revisions of the above listed documents app...	1) Prior to installation of this modification it must be determined thattheinterrelationship between this modification and any other previouslyinstalled modification and/or repairwill introduce no adverse effectuponthe airworthiness of the product2) ICA must be incorporated into the operator's main...	27/09/2013	Active	10046520

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046549	RUECKER AEROSPACE GmbH			DC-9-83 (MD-83)	MD 83 stowage of items in FWD cabin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ruecker Aerospace Master Document List No. MDL-252-00043-000 Issue Adated 23 September 2013.or later revisions of the above listed documents approved by EASA.	Ruecker Aerospace Modification No. EO-259-00002-000 is a prerequisitefor this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon...	30/09/2013	Active	10046549
10046552	ALAMO ENGINEERING GmbH	REV. 2		CL-600-2B16 (604 VARIANT)	Cabin refurbishment Incl LOPA change.Revision 1: 328 SUPPORT SERVICES GmbHRevision 2: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	328 Design Master Document List No. MDL006Z001 Issue A dated 25September 2013< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10046552
10046554	ACS-NAI Ltd.		TCCA C-LSA13-057/D	CL-600-2B19	Cabin Interior Re-configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. C-LSA13-057/D Issue 1 dated 6th September2013.ACS-NAI Ltd. Modification Data Summary H989000 Revision N/C or laterapproved revision.ACS-NAI Ltd. AirplaneFlight Manual Supplement H989091 Revision N/C orlater approved revision.Instructions for Continued Airworthiness CRJ7248...	Restricted to ASN 7248	30/09/2013	Active	10046554
10046576	LUFTHANSA TECHNIK AG			A340-600	DLH A340-600 Cabin Interior Reconfiguration.Description - Summary : Cabin Reconfiguration by replacing of allBusiness- andEconomy Class Seats and modification of several components, also theInflightEntertainment System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Program CP00-12/22M iss 1 at rev 4- Supplemental Type Definition Document STDD00-12/22M issue 1 rev 4- ICA, ref A-00-13/07-ICA, Issue 1 rev 0- Compliance Record List CRL00-12/22M iss 2 at rev 0or later revisions of the above listed documents approved by EASA.	1) Prior to installation of this modification it must be determined thattheinterrelationship between this modification and any other previouslyinstalledmodification and/or repair will introduce no adverse effect upon theairworthiness of the product. 2) This modification cover the Cabin Certificationi...	01/10/2013	Active	10046576
10046582	BOGGI AERONAUTICS S.R.L.	REV. 1		AVANTI II AVANTI	Antenna installation in accordance with Boggi S.R.L modification ref180P005-10.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Boggi S.R.L Master DocumentList (MDL)ref 180P00510-MDL-02 Issue 2.Maintain in accordance with Boggi S.R.L. Instructions for ContinuedAirworthiness (ICA) ref 180P00510-ICA Issue 2.or later revisions of the above listed document (s) approved/ acceptedunder the EASA syste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/07/2020	Active	10046582

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046600	INTER-TEC AERO DESIGN AND CERTIFICALIMITE D	REV. 2		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-216/-231/-232/-233 A320-111/-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of Pitch Aircraft Seating System Models QCC1300 and QCC1200SeatsRev. 2: Transfer of STC holder from INTER-TEC SERVICES Ltd to INTER-TECAERO DESIGN AND CERTIFICATION LIMITED.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Plan CP/TEN/ 689 Issue 4, dated May 29, 2013Certification Compliance Report TEN 689/1 Issue 1, dated 18 September2013Modificatio n Report and Declaration of ComplianceTEN 689 Issue 1, dated18 September 2013Instructions for Continued Airworthiness TEN 689/4 Issue 1 dated 13 June2013or la...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/12/2021	Active	10046600
10046602	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)	REV. 1		PA-31 NAVAJO	Introduction of 120 amp. Alternators on Piper PA-31 - Removal of theexisting Prestolite 70 Amp. Alternators and installNational Air Parts120 Amp. Alternators model P324RN. the mounting on the engine remainsoriginal, since the new alternator is a direct replacement. The aircraftpower wiring and prot...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MODE00050_MDL Master Data List Rev. 2 dated 9 September 2013MODE00050_AFMS Airplane Flight Manual SupplementMODE00050_I CA Instructions for Continued Airworthiness dated 26 June2013, initial issueMODE00050_WB Weight & Balance Information dated 23 July 2013, initialissueor later revisions of the above...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/10/2013	Active	10046602
10046612	ECT INDUSTRIES, SITE D'AUXERRE - BA			269C	Installation of a AGNAV GUIA differential GPS system for agriculturalspraying operation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertificated noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	Bayo Flight Manual Supplement n°2001-04-AFMS-AG-NAV revision 3 dated10/01/2013.or later revisions of the above listed documents approved by EASA.Bayo STC Master List n°2011-004-MLrevision 4 dated 11/06/2013	The AGNAV GPS is not an aeronautical navigation system.It must be used only as an information system for agricultural sprayingoperations in day VFR condition.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously...	04/10/2013	Active	10046612
10046655	TURK HAVA YOLLARI TEKNIK A.S.TURKISH TECHNIC			A340-311	CABIN LAYOUT CONVERSION FROM DUAL CLASS 270 PAX TO SINGLE CLASS 331 PAX	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Design Declaration Form C9-2520006-DD01-02, Dated 10-07-2013or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	08/10/2013	Active	10046655
10046660	AIR ALLIANCE GmbH	REV. 2		35A	Replacement of Mechanical HSI by Sandel SN4500 EHSIRevision1 of this STC corrects equipment Part Numbers installed.Revision 2 of this STC adds the MSN 35A-111 to the approved list ofaeroplanes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Air Alliance, Master Document List: 2013_004_LJ35_Form2, revision 04,dated 09 October 2015Air Alliance, AFM Supplement: 2013_004_LJ35_0506, revision 04, dated 12October 2015Air Alliance, Instructions for Continued Airworthiness: 2013_004_LJ35_0507, revision 01, dated 07 October 2015or later revisions...	This approval is limited for MSN 35A-346 and 35A-111 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repairwill introduce noadverse effect upon the airworthiness of th...	20/06/2016	Active	10046660

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046675	DOA21 LIMITED	REV. 1		737-700	Introduction of Corporate VIP InteriorRev. 1: Transfer of STC holder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):D-02 Isolated CompartmentsD-05 Glass Screens of Displays and MonitorsD-09 Injury Criteria for Side-Facing DivansD-06 Shower InstallationD...	STC Twenty One Ltd Master Document List No. S21.MDL-1081 Issue 2STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0100 Issue 1or later revisions of the above listed documents approved by EASA	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/10/2023	Active	10046675
10046679	JET AVIATION ST. LOUIS, Inc.		FAA STC ST03229CH-D	BD-700-1A10, BD-700-1A11	Cobham Aviator 700D SATCOM Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST03229CH-D dated 18 June 2013.Jet Aviation St.Louis, Inc Master Data List 35-354G001 Rev A, dated 18June 2013.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (orsubsequent revisions ofthis decision) and/ or the TechnicalU...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	10/10/2013	Active	10046679
10046684	HAECO CABIN SOLUTIONS, LLC		FAA ST04132AT	767-300	Floor Reinforcement in a Boeing 767-300 Series Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25 at Amendment 13:25.623 ; 25.625.The requirements for environmental protection and the associatedcertified noise and/u...	TIMCO Aerosystems Master Data List: 12T304L001, Revision IR, 04/10/2013TIMCO Aerosystems Instructions for Continued Airworthiness: 12T304R009,Revision IR, 08/08/2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/10/2013	Active	10046684
10046686	ALPINE AEROTECH Ltd.		TCCA SH97-80	212, 412, 412EP	Installation of Alpine Aerotech Ltd. Exhaust Ejector/Deflector Assembly	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Approval Report - Manufacture of Alpine Exhaust ejector & deflectorassemblies 191M-97-713, Rev. NI (it includes Cert. Basis, CCL, MasterDrawing List D191M-96-048, Rev. B)or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/...	This approval is limited to Bell helicopter models 212, 412and 412EP(the model 412CF is not currently EASA certified).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair...	11/10/2013	Active	10046686
10046687	DV AVIATION, Inc.DBA NORTHPOINT AVIATION	REV. 3	FAA STC SA02271SE	B) 206H, T206H A) TU206G, U206G 206H, U206G, T206H, TU206G	Fabrication and installation of Soloy wing mounted LED landing and taxilight kitsRev. 3: Transfer from "Fifty-Ten-Yankee, LLC" to "DV Aviation, Inc.	FAR-23, IR:,,23.303, 23.307, 23.333, 23.335, 23.337, 23.341, 23.609,23.615, 23.625, 23.627, 23.1351(a)(b)(c)(d), 23.1367(a)(b)(c)(d),23.1383, 23.1581, 23.1583(h)FAR-23, Amdt. 5:,,23.1585(a) FAR-23, Amdt. 7:,,23.611FAR-23, Amdt. 14:,,23.1365FAR-23, Amdt. 17:,,23.1309(a)(c)FAR-23, Amdt. 20:,,23.1301(a)...	Soloy, LLC, Master Drawing List 909-100, Revision B, dated 14 January2013.Soloy Service Instructions for Continued Airworthiness (ICA), DocumentNumber 909-01, dated 14 January 2013.Pilot's Operating Handbook and Airplane Flight Manual Supplement (AFMS),Document Number S2020A, Revision 0, dated 26 Ma...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2023	Active	10046687

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046730	BOMBARDIER AEROSPACE		TCCA STC C-LSA05-376/D	BD100-1A10	Cabin Modification for Passenger Seat Upgrade in accordancewith MasterDocument List BAS68010005 rev A dated November 3, 2005.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Bombardier Business Aviation Services BBAS Master Document ListBAS68010005 rev A dated November 3, 2005- Amtech Aeronautical Limited (AAL) document MMS387101, Revision IRdated 2005 November 1or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implement...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/10/2013	Active	10046730
10046740	SABENA TECHNICS BOD	REV. 2		MBB-BK117 C-2 MBB BK117 C-2	UHF TPM700 InstallationInstallation of a UHF TPM700 radio as defined in Dossier de DefinitionM001-23-13-145.Rev.1 Minorchange regarding installation instruction and hardware asdefined in Dossier de Modification M003-23-14-145.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	-Dossier de Modification M003-23-14-145 Ed. 1, Rev. 0, dated 06 February2014-Installation Instructions and Instructionsfor Continued Airworthiness,145HU-SB-23-69 Rev. 2, dated 16December2013Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/03/2025	Active	10046740
10046756	AERODATA AG			B300	Installation of Aerodata "AD-MS-1000" Mission SystemThe installation consists of the installation of a non-essential sensorsystem underneath the belly with, 360° Radar into Beechcraft certifiedand installed radom, EO/IR turret into Beechcraft certified liftassembly, direction finder in front of thed...	The Certification Basis for the original product remains applicable foritems not affected by the modification, for items affected by themodification the following new Certification Basis is elected to complywith: CS-23 Amdt. 3, except 23.561 and 23.785 (kept FAR 23.561 Amdt. 34and FAR 23.785 Amdt. 3...	Installation in accordance with Master Document List, Aerodata Doc. No.MDL-A/C-836, Rev. 1, dated 10 September 2013;Aircraft Flight Manual Supplement, Aerodata Doc. No AFM-135, Rev. 2,dated 11 September 2013;Aircraft Maintenance Manual Supplement, Aerodata Doc No. AMM-1138, Rev.1, dated 11 September...	Only applicable for Serial FL-795Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverseeffect upon the airworthiness of the product.The installatio...	18/10/2013	Active	10046756
10046758	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			650 CITATION III, VI, VII	P-RNAV approval of single or dual UNS-1 Csp	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cessna Düsseldorf Airplane Flight Manual Supplement, 2012-10-8, Rev A,dated 08 March 2013Cessna Düsseldorf Master Document List, 2012-10-16, Rev IR, dated 24September 2013or laterrevisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	18/10/2013	Active	10046758
10046759	MT-PROPELLER ENTWICKLUNG GmbH	REV. 2		2) F90 1) C90, C90A, C90GT, C90GTI 1) B90, E90	Installation of 5-blade MT-Propeller ModelMTV-27-1-E-C-F-R(P)/CFR210-58d on HBC King Air B90, C90, C90A, C90GT,C90GTi, E90; F90	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	According to MT-Propeller Master Document List No. E-2282 andMT-Propeller Installation Instructions Doc. No. E-2276, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2275To be maintained i.a.w. MT-Propeller ICA Document No. E-2277or later revisions of the above li...	According limitation section of AFM-S	10/02/2017	Active	10046759
10046770	DASSAULT FALCON SERVICE			MYSTERE FALCON 900	Cabin Management System Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25 Change 14:§853(a) & Appendix F, 869(a), 1353(a)(b)(d), 1423(b)(c)(d)(e)(f), 1431(a)(c)(d)CS 25 Amdt 13:§899, 1360The requirements for environmental protection and th...	DFS Change Approval Sheet doc. DFS9706-CAS Issue A dated 18October 2013DFS Modification Sheet doc. DFS9706 Issue A dated 14 October 2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/10/2013	Active	10046770

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046782	DASSAULT FALCON SERVICE			MF900B	MF900 S/N 059 Cabin Interior Modification	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25 Change 14: §853(a)(f) & Appendix F Part1< (>,<)> 1423(c), 25.X1499The requirements for environmental protection and the associatedcertified noise and/ or emissions l...	DFS Change Approval Sheet doc. DFS9705-CAS Issue A dated 21October 2013DFS Modification Sheet doc. DFS9705 Issue A dated 10 October 2013or later revisions of the above listed documents approved by EASA	S/N 059Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The installation of this modification byw...	22/10/2013	Active	10046782
10046787	NORTHWEST AEROSPACE TECHNOLOGIESI NC.			A340-311 / -312 / -313	Interior reconfiguration of Lufthansa A340 aircraft.Description: Interior cabin upgrade of Airbus A340-300 LufthansaAirlines (DLH) aircraft. The main cabin items modified by thismodification are the following:-,,Removal of existing passenger seats.-,,Removal of various passenger cabin monuments (gal...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Summary, ref : N0425-D90 rev A, dated 21 October 2013.Master Drawing List, ref : N0425-D10 rev D, dated 15 October 2013.Instruction for Continued Airworthiness, ref:I CA : ref : N0425-D70 revC, dated 14 October 2013.Weight and Balance Report, ref : N0425-D60 rev A, dated 18 September2...	1),,Prior to installation of this modification it must be determinedthat the interrelationship between this modification and any otherpreviously installed modification and/or repair will introduce noadverse effect upon the airworthiness ofthe product.2),,No passenger is allowed in the cabin, unless...	22/10/2013	Active	10046787
10046793	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			525, 525A	P-RNAV Approval of UNS-1L	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement 2013-14-8 IROr later revisions of the above listed documents approved by EASA.And:- Engineering Order: 2013-14 EO, IR, or later approved revisions- Installation Procedure: 2013-14-1, IR, or later approved revisions	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/10/2013	Active	10046793
10046796	DOA21 LIMITED	REV. 1		757-23N (757-200 SUB-MODEL) 757-200	Introduction of a custom interior.This design change converts the main passenger cabin area from acommercial air transport configuration to a custom corporate interior.Rev. 1: Transfer of STC holder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):CRI D-03 Isolated CompartmentsCRI D-04 Glass Screens of Displays and MonitorsCRI D-05 Shower InstallationDeviation(s):CRI D-02 Firm Handh...	-Master Data List, STC21 document ref. S21.MDL-1030 issue 2-Aircraft Flight Manual Supplement, STC21 document ref. S21.FMS-0103issue 1-Supplement Manual, STC21 document ref. S21.TEC-0399 issue 1, dated 17thOctober 2013 (including Instructions for Continued Airworthiness)or later revisions of the abo...	-This STC is only applicable to aircraft S/N 27972-Refer toSupplement Manual, STC21 document ref. S21.TEC-0399 issue 1,dated 17th October 2013, for Airworthiness Limitations.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and an...	24/10/2023	Active	10046796
10046805	365 AEROSPACE DDS LIMITED	REV. 3		767-300	767-300 Condor Cabin LED Lighting UpgradeRev. 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.Rev. 3: Certification basis correction.	The Type and OSD Certification Bases for the original product as amendedby the following additional oralternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt. 13:25.301(a)(b)(c), 25.303, 25.305 (a)(b)<(>,<)>25.307(a), 25.561(a) (c)(1)(2), 25.601, 25.603, 25...	AERODEC Modification Summary No. MOD-1338 Revision A<(>,<)>dated 24thOctober 2013	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/11/2023	Active	10046805
10046808	AMES - AEROSPACE AND MECHANICALEN GINEERING SERVICES ING. WALTERSTARZA CHER GesmbH	REV. 2		767-300	B767-300 Cabin reconfiguration incl. IFE, ISPSS and Seat Integration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25.853 c) at Amdt16.The requirements for environmental protection and the associatedcertified noise and/ or emissions l...	- Engineering Order B767-300 Fleet IFE and Seat IntegrationEO_M15400135 _MZI_15012013 Rev 7- Instructions for Continued Airworthiness incl. InstallationInstructions ICA_M15400135_MGR_07 032013 Rev 12- Aircraft Flight Manual Supplement AFS_M15400135_MGR_06 032013 Rev 2- Document and drawing tree B767 Up...	- For effective modification prerequisites see Document andDrawing TreeB767 Upgrade Program 15430105_REV1 Page 12.- For effective concurrent modifications see Document and Drawing TreeB767 Upgrade Program 15430105_REV1 Page 12.NOTE: Drawing Tree B767 Upgrade Program 15430105_REV1 includes projectbr...	30/06/2015	Active	10046808

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046809	AIRCRAFT CABIN MAINTENANCE GmbH			737-900, 737-900ER 737-600, 737-700, 737-800 737-300, 737-400, 737-500 737-100, 737-200, 737-200C	Exchange of webbing of Passenger Seat Belt P/N 2006-1-511-8122to P/N EPA 26511-2-01-35 for installation on Boeing 737	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Refer to Master Document list E/O No. 129-1004565 Rev. 0 (30.09.2013);or later revisions of the above listed documents approved by EASA.	As per Service Bulletin No. 129-1004565 SEB 06 00, latest revision.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthin...	25/10/2013	Active	10046809
10046814	LUFTHANSA TECHNIK AG			A340-311 / -312 / -313	A340-300 2 Class IK Retrofit.Description - Summary : Cabin reconfiguration including new Lopa, newSeats<(>,<) >new IFE, Galleys, Stowages and Carpet.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document : STDD25-12/37M Iss1, dated 18October 2013- Compliance Record List, ref : CRL25-12/37M Iss 1, dated 17 October2013.- Instruction for Continued Airworthiness, ref : A-00-13/14-ICA, Issue3, dated 09 October 2013- Weight and Balance Supplement, ref : WB-08-96/13,...	1-,,The Cabin reconfiguration, supported by this modification, must beimplemented in conjunction with STC 10046787 [or later revision approvedby EASA].2-,,Prior to installation ofthis modification it must be determinedthat the interrelationship between this modification and any otherpreviously inst...	25/10/2013	Active	10046814
10046817	SOCIETE AIR FRANCE S.A.			A330-243	ACG cabin reconfiguration with Zodiac "IMS RAVE" IFE installation.Description - Summary :The modification consists in cabin reconfiguration from 232 (36 Businessseats+ 196 Economic seats) to 321 (Economic seats) passengers coupledwith Zodiac "IMS RAVE" In-Flight Entertainment system installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Change Approval Sheet CAS-A330-13-003 rev 0, dated 25 October 2013- Instruction for Continued Airworthiness, ref : SOCPL-A330-13-003-034rev 1, dated 16 October 2013or later revisions of the above listed documents approved by EASA	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of theproduct.	25/10/2013	Active	10046817
10046820	AEROTEC & CONCEPT			F900DX	WiFi activation for AVIATOR 700 SATCOM system on F900DX aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AEROTEC Master Data List doc. N° AE13162MDL Rev. 0 dated 24.10.2013Aircraft Flight Manual Supplement doc. N ° AE13162AFMS Rev 0 dated27.09.2013or later revisions of the above listed documents approved by EASA.	F900DX S/N 617	28/10/2013	Active	10046820
10046826	OGMA, INDUSTRIA AERONAUTICA DEPORTUGAL, S.A.	REV. 1		EMB-135BJ	Upgrade from FMS UNS-1K single installation to dual FMS UNS-1Lwconfiguration on EMB-135BJNote Revision 1: This STC has been revised at Rev. 1 in order to updatethe restriction to specific aircraft S/ N.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Change Dossier doc. N° 12 P13 CD 00 001, Rev. B dated 14.09.2018- Airplane Flight Manual Supplement doc. N° 12 P13 MS12 010, Rev.Initial Issue dated 28.10.2013or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	- As per Airplane Flight Manual Supplement doc. N° 12 P13 MS 12 010<(>,<)> Rev. Initial Issue dated 28.10.2013	28/09/2018	Active	10046826
10046843	DELTA ENGINEERING CORPORATION	REV. 1	FAA ST03103CH	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-111/-211/-212/-214 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Ownership transfer of EASA STC 10046843This modification supports the compatibility of aircraft equipment withCellular and Wireless Data Technologies.This Revision 1 identifies the change of STC ownership.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.1309(a) Amdt 2and CS 25.1529 Amdt 2The requirements forenvironmental protection and the associatedcertified noise a...	Master Data List, ref. DC104-9046-00, Rev. AH dated 02 July2019<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with theTechnical ImplementationProcedures of EU/ USA Bilateral Agreement.	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane installed base station using the cellularand/or wireless technologies is concurr...	18/09/2019	Active	10046843

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046850	ANCRA INTERNATIONAL LLC	REV. 1	FAA STC ST02480LA	ATR-72-201/72-202 ATR72-201/-202/-211/-212 /-212A	Mechanical Cargo Loading System installation for aircraft in cargoversion with large cargo door implemented.Rev. 1: Applicability list extended to new models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25 Change 15 for:25.23, 25.29, 25.301, 25.303,25.305, 25.307, 25.561, 25.601, 25.603,25.605, 25.607, 25.609, 25.613, 25.619, 25.621, 25.625, 25.787, 25.793,25.853, 25...	FAA Approved Ancra International LLC Controlled Data List (CDL) CDL84231<(>,<)> Revision H, dated May 13, 2019, or later FAA approved revision.Ancra International LLC Weight and Balance Manual Supplement, No 9934<(>,<)> Issue B dated October 17, 2013, or later FAA approved revision.Ancra Internation...	This STC can only be installed on an aircraft already converted to fullcargo under EASA STC 10043003.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no advers...	30/06/2020	Active	10046850
10046867	DOA AESGLOBAL LIMITED	REV. 1		A330-243, A330-343	INTRODUCTION OF FLEET STD FWC AUTO CALLOUTS (NOT INCLUDING 500FT)Rev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 13:CS 25.869CS 25.1301CS 25.1309CS25.1322CS 25.1353CS 25.1529CS 25.1585CS 25.1701CS 25.1703CS25.1705CS 25.1707CS 25.1709CS 25.1711CS 25.1713CS 25.1719CSC...	Master Data ListAES-330-2874MDL Issue 3Principal Instructions for Continued Airworthiness DocumentAES-TR-1335 Issue 1or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2021	Active	10046867
10046868	SABENA TECHNICS BGC	REV. 3		A340-642 / -643	Panasonic eXPhone System activation on A340-600.This STC installs a Panasonic eXphone System allowing, in conjunctionwith other devices, the use of cellphones during flight.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 25Amdt. 4 : 25.23; 25.301; 25.581; 25.601; 25.603; 25.611; 25.869(a);25.899; 25.1301; 25.1307(b)(c); 25.1309; 25.1351; 25.1353; 25.1355;25.1357; 25.1360; 25.1431; 25.1...	Master Data List, Ref : 0634-01-A-2103-R01, dated 23 October 2013;Instruction for Continued Airworthiness, Ref :0634-01-A-2211-R02, dated23 October 2013;Aircraft Flight Manual Supplement, Ref : 0634-01-A-2301-R01, dated 18October 2013;or later revisions of the above listed documents approved by EASA...	The eXPhone system installation is contingent on prior installationdetailed below:-,,the installation of the CbB system;-,,the installation of the PAC eXConnect system;-,,the installation of eXPhone system partial provisions (mechanicalprovisions, electrical provisions, and Leaky Feeder Antenna prov...	11/05/2016	Active	10046868
10046873	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 1		767-300	Installation of Zodiac NuLook Interior on Condor aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: JAR 25.613(a)(b) atAmdt 11, JAR 25.853(a)(d) at Amdt 13, JAR 25.1529 at Amdt 11, JAR25.1583(a)(2) at Amdt 11.The requireme...	- Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0561-D90, Revision -, dated 14 February 2018;- Instructions for Continued Airworthiness, HeathTecnam document No.HTM142<(>,<)> Revision L, dated 13 February 2018;or later revisions of the above listed documents approved by...	FAA AD 2005-20-05 must have been complied with prior to theinstallationof this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect up...	15/02/2018	Active	10046873
10046910	JET AVIATION AG	REV. 3		737-800	Transfer STC 10046910 Rev. 2VIP Cabin Interior Outfitting as defined in:-Project Description, Doc. No. BBJ37663-500 Rev. 1, dated 21.03.2012-Master Data List, Doc. No. BBJ37663-001 Rev. B, dated 01.11.2013	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Special Condition(s):CRI D-02 Isolated Compartments, Issue 02CRI D-10 Glass Screens of Displays / Monitors, Issue 01CRI D-14 Shower Installation, Issue 01Deviation(s):CRI D-01 Installation of Interi...	-Master Data List, Doc. No. BBJ37663-001 Rev. B, dated 01.11.2013-Airplane Flight Manual Supplement, Doc. No. BBJ37663-201-01 Rev. A-Instructions for Continued Airworthiness, Doc.No. BBJ37663-150-01 Rev.IR, dated 20.09.2013-EWIS Instructions for Continued Airworthiness, Doc. No. BBJ37663-150-02Rev....	S/N 37663, D-AACMThis STC requires the installation of the STC 10046966 Rev. 2 “PassengerGaseous Oxygen System”Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will in...	13/12/2017	Active	10046910

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046919	AKV, Inc.	REV. 2	FAA SR02413LA	SEE FAA AML	Installation of an AKV Inc. Exceedance and Trend MonitoringSystem KITP/N ETM1000.Purpose of the STC revision 01 is theapplication of Exceedance andTrend Monitoring System kit P/N ETM1000 to Bell 204B and Bell 205A-1.Purpose of this STC revision 02 is the application of Exceedance andTrend Monitori...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List No. ETM1000-MDL, Rev. E, dated 11 January 2012, orlater FAA approved revisions.Rotorcraft Flight Manual Supplement for ETM1000, Rev. IR, dated 27January 2012, or later FAA approved revisions.	The Exceedance and Trend Monitoring System can only be installed onday/night VFR aircraft with non-FADEC equipped engine (unless a specificmodel FADEC rotorcraft is noted in the AML). It is for ground crew toperform maintenance functions and not intended to replace the originalindicator as certified...	15/11/2018	Active	10046919
10046964	WACO CLASSIC AIRCRAFT CORPORATION	REV. 1	FAA STC SA1000GL	WACO YMF F5C	Modify the WACO YMF to a Classic "WACO F5" or "WACO F5C" configurationaccording to Classic Drawing Number CAC-F5	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Classic Drawing Number CAC-F5, Rev. G, dated April 26, 2010Airplane Flight Manual, Doc. No. 91-AFM1, Rev. J, FAA approved November4, 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ orE...	a) Deviations from US Type Design are laid down in EASA TCDS IM.A.055,issue 4.b) Glider and Banner Towing are not approved.	28/08/2014	Active	10046964
10046966	JET AVIATION AG	REV. 3		737-800	Passenger Gaseous Oxygen System.Rev. 2: Transfer STC 10046966 Rev. 1.Rev. 3: Modification of the oxygen system due to part obsolescence andno service support from part OEM.The modification comprises of alternative pulse latch valves, removal ofsequence regulators and limitationto 39 consumers.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.869 Amdt. 05, CS 25.1301 Amdt. 02, CS 25.1309 Amdt. 06, CS 25.1411Initial Issue, CS 25.1453 Amdt. 04.T...	Master Data List BB73735201-001, Rev. CConfig. 1: Airplane Flight Manual Supplement BB73735201-201-01, Rev. CConfig. 2:Airplane Flight Manual Supplement for Config. 2JBSL-M-03999AFM-001, Rev. AInstructions for Continued Airworthiness BB73735201-150-01, Rev. CEWIS Instructions for Continued Airworth...	Config. 1: The system is certified for a maximum quantity of one hundred(100) oxygen masks, intended to serve a maximumof ninety (90) occupants(excluding cockpit occupants).Config. 2: The system is certified for a maximum quantity of thirty-nine (39) activated oxygen masks, intended to serve a maxim...	17/11/2023	Active	10046966
10046967	DELTA ENGINEERING CORPORATION		FAA STC ST02927NY-D	747-400, 747-400D, 747-400F	Panasonic Global Communications SuiteInstallation of a Panasonic Global Communications Suite Ku-Band Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ODA-2313-03, Revision -, April 10, 2013 - Project Plan0107-08069-2313, Revision E, October 8, 2013 - Master Data List6607-08478-2313, Revision -, June 2, 2013 - Compliance SummaryReport0707-08072-2313, Revision C, April 12, 2013 - Instructions for ContinuedAirworthiness0607-08762-2313<(>,<)> Revisi...	- EASA project number is 0010025133. This has been added for easyreference as this STC is a pre-requisite for EASA project number0010019164 which was processed in parallel.- This STC does not approve the operation of the antenna- For EASA registered aircraft, only the EASA approved Airplane FlightMa...	06/11/2013	Active	10046967
10046968	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST02902NY-D	747-400, 747-400D, 747-400F 747-400/-400D/-400F/ 747-8	Installation of a Panasonic In-Flight Entertainment (IFE) system and/orGlobal Communication Suite (GCS)Rev. 1: incorporates different configuration of cabin equipmentinstallation,updates the broadband controller, switches and ICA, andexpands the aircraft listing to include 747-8 models.Rev. 2: upda...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ODA-2295-02, Revision -, October 23, 2012 - Project Plan6607-08313-2295, Revision -, March 19, 2013 - Compliance Summary Report<(>,<)>0107-07683-22, Rev. W, Jul 18<(>,<)> 2024 - Master Data List<(>,<)>0707-07691-2295, Revision N, Jul 19, 2024 - Instructions for ContinuedAirworthiness<(>,<)>0607-0769...	As a precondition, the following STC's must be installed:- EASA STC 10040513 (if Cabin Wi-Fi is activated)- EASA STC 10046967 (if Antenna Connectivity is required)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprevi...	02/09/2024	Active	10046968

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10046977	SABENA TECHNICS BGC			A319-111	Cabin modification including installation of structural provisions formonuments installed in an A319.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List 4547-01-A-2103-R01, dated 18th of October 2013Aircraft Flight Manual Supplement 4547-01-A-2301-R00, dated 13th ofNovember 2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/11/2013	Active	10046977
10046978	SABENA TECHNICS BOD			A319-131	Cabin modification - Quick change	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan PC-9044-00-001, Issue 3 dated 06/11/2013Modification Approval Sheet S-25-2308, Issue 5 dated 23/10/2013Master Drawing List MDL-S-25-2308-03, Issue B dated 23/10/2013Master Drawing List MDL-S-25-2308-01, Issue C dated 23/10/2013Instructions for Continued Airworthiness ICA-D9044-25-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/11/2013	Active	10046978
10046990	AIRBORNE TECHNOLOGIES GmbH			P2006T	provisions for magnetic field measurement (Step 1) and improvement ofdirectional stability (Step 2)	- The Certification Basis for the original product as amended by thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS 23.1, Amendment 2; CS23.21, Amendment 2; CS 23.23, Amendment 2; CS 23.29 (a), Amendment 2; CS23.45, Amendment 2; CS 2...	Engineering Order Doc. No. STC-AT-056, Rev. 5, dated 21.10.2013<(>,<)>AFM Supplements Doc No. AFM1-STC-AT-056, Rev. 2, dated 01.10.2013(required for step 1 of this STC) and AFM2-STC-AT-056, Rev. 0, dated05.04.2013 (required for step 2 of this STC)< (>,<)>AMM Supplements Doc No. AMM1-STC-AT-056, Rev.(...	Prior to installation of Step1 of this STC, the following modificationshave to be installed:- Airborne Technologies Modification: STC-AT-003, Step 1 or 3 or 5 or 7,latest effective revision.- Airborne Technologies Modification: STC-AT-003,Step 9, latesteffective revision- STC-AT-056 Step 2Prior tot...	08/11/2013	Active	10046990
10046995	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST03178NY	777-200, -200LR, -300ER	Installation of a Panasonic In-Flight Entertainment SystemRevision 1 adds the 777-200LR model.	The Certification Bases for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS-25 amdt 425.831, 25.853, 25.869, 25.981, 25.1353, 25.1423,25.1431, 25.1583,1585.The requirements for environmental pro...	1. Delta Engineering Master Data List 0143-08468-2348 Revision AZ dated29 September 2021;2. Instructions for Continued Airworthiness 0743-08471-2348 Revision Tdated 24 September 2021;3. Airplane Flight Manual Supplement 0643-08470-2348 Revision D dated 14May 2020;or later revisions of the above list...	This STC is applicable to all serial numbers listed in the DeltaEngineering Master Data List.Operational approval to use T-PED's must be obtained separately fromthis STC.This STC includes activation of existing installed In-FlightEntertainment equipment installed in a configuration presented in Delt...	20/07/2022	Active	10046995
10047025	TENENCIA Ltd.		CAA UK RESPONSIBILITY	ATR 72-212A ATR 72-101/-102/-201/-212 ATR 42-200/-300/-320/-400/-500	ATR - Installation of a Single UNS-1Lw Universal Avionics FlightManagement System with LPVThe purpose of this modification is to install a single UniversalAvionics Systems Corporation (UASC) UNS-1Lw Navigation Management Systemto comply with Precision RNAV and Approach Operations to LocaliserPrecisi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, Tenecia Ltd Report 713, issue 5, dated 8 november 2013AFM supplement TEN/ ATR/005 (Precision RNAV withLPV Approach), issue 8,dated 11 november 2013AFM supplementTEN/ ATR/006 (Precision RNAV and RNP Approach), issue 7,dated 11 november 2013Instructions for Continuous Airworthiness,i...	This approval is limited to the aircraft complying with prerequisiteaircraft configuration defined in §6 of Master DataList, Tenecia LtdReport 713, issue 5, dated 8 November 2013.Prior to installation of this design change it must be determined thatthe interrelationship between this design change a...	12/11/2013	Active	10047025

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047026	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	421C GOLDEN EAGLE	Introduction of Sealed Masks into the Supplemental Oxygen System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cranfield Aerospace Ltd Modification No. CAeM/ Cessna/1354.Cranfield Aerospace Ltd Type Design Definition Addendum No. CA/DD/DR0147Dated 06 November 2013.or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	12/11/2013	Active	10047026
10047057	BLACKHAWK MODIFICATIONS Inc.		FAA STC SA02467LA	208	Replacement of the original Pratt and Whitney PT6A-114(A) engine andpropeller with a Pratt and Whitney PT6A-42A and 4-blade HartzellPropeller HC-E4N-3P/D9900(K) and associated optional equipment inaccordance with FAA STC SA02467LA.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): 23-ACE-3, Dynamic Evaluation, Engine Installation.Factors from this special condition were incorporated into the whirlmode flutter analysis per 14 CF...	AFMS 201201-1 IR<(>,<)> FAA approved June 10, 2013AFMS 201201-2 IR< (>,<)> FAA approved June 10, 2013Instructions for Continued Airworthiness ICA 201201-30, Rev.IR, datedJanuary 10, 2013, FAA accepted June 14, 2013or later revisions of the above listed documents approved by EASA inaccordance with EAS...	1) AeroAcoustics Aircraft Systems, Inc., "Aircraft Payload Extender STOLSystem", STC SA02042SE is OPTIONAL as part of this alteration.2) This modification is not compatible with Cessna Model 208 SerialNumber 2080500 and greater, aircraft equipped with Garmin 1000installations, and aircraft equipped3...	14/11/2013	Active	10047057
10047061	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		CESSNA S550 CITATION S/II CESSNA 560 CITATION V CESSNA 560 CITATION ULTRA CESSNA 550 CITATION II CESSNA 550 BRAVO CESSNA 500 CITATION/ CITATION I	Universal UNS FMS System Evaluation for P-RNAV Approval	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Scandinavian Avionics, AFM SUPPLEMENT 2084884-AM A, Issue 1, dated 09September 2013Scandinavian Avionics, Installation Documents 2084884-STC, issue 2 dated14 November 2012or laterrevisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	15/11/2013	Active	10047061
10047063	MT-PROPELLER ENTWICKLUNG GmbH			PA-24-250, PA-24-260	Installation of 3-blade MT-Propeller Model MTV-9-B/188-50	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: FAR 23.1529 Amdt. 26 ;CS-36 Amdt.2 and FAR 36 Amdt. 28This certificate/ approval involves a change to the requirements for...	According to MT-Propeller Master Document List No. E-2338 andMT-Propeller Installation Instructions Doc. No. E-2340, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2339To be maintained i.a.w. MT-Propeller ICA Document No. E-2341or later revisions of the above li...	According to limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	14/11/2013	Active	10047063
10047083	BAE SYSTEMS (OPERATIONS) LIMITED	REV. 1	CAA UK RESPONSIBILITY	737-900ER 737-500/-600/-700/-800/-900 737-100/-200/-200C/-300/-400	STM80009A - Navigation - Upgrade from TCAS II Version 7.0 to 7.1 onBoeing 737 (all series)Extension of the TCAS 7.1 equipment types covered by STC No. 10047083(BAE Systems' Major Change STM80009A)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 13CS 25.1301, CS 25.1302, CS 25.1309<(>,<)>CS 25.1322, CS 25.1333, CS 25.1431<(>,<)>CS 25.1459, CS 25.1529, CS 25.1581The requirements for environmental pr...	BAE Systems Major Change Dossier AWR/742/ B737 Addendum 1 Issue 1BAE Systems Major Change Dossier AWR/742/ B737 Issue 2	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/09/2014	Active	10047083
10047084	BAE SYSTEMS (OPERATIONS) LIMITED	REV. 2	CAA UK RESPONSIBILITY	757-200, 757-200PF, 757-300	STM80010A – Navigation – Upgrade from TCAS II Version 7.0 to 7.1 onBoeing 757 (all series)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 13CS 25.1301<(>,<)> CS 25.1302<(>,<)> CS 25.1309<(>,<)> CS 25.1322<(>,<)>CS 25.1333<(>,<)> CS 25.1431<(>,<)> CS 25.1459<(>,<)> CS 25.1529<(>,<)>CS 25.1581T...	BAE Systems Major Change Dossier AWR/ 743/757 Issue 2 dated 14th November2013BAE Systems Major Change Dossier AWR/743/757 Addendum 1 Issue 1 datedAugust 2015	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/09/2015	Active	10047084

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047098	ST ENGINEERING AEROSPACE LTD.			757-200	Modification of Boeing 757 -200CF Main Deck Cargo DoorModification of the main Deck Cargo Door to remove the Cargo Doorlimitation related to EASA STC 10038822	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Certification Basis as per EASA STC 10038822 (Temporary Deviation D-03is removed by this STC)The requirements for environmental protection and the associatedcertified nois...	ST Aerospace MDL: 3360000, Revision G, 12/11/2013AFM Supplement: 336A/TST/ AFM, Rev A, 11/11/2013ICA Supplement: 336/A/ICA/ 001, Rev L, 12/11/2013or later revisions of the above listed documents approved by EASA.	STC is limited to a/c serial number 25622 onlyIncorporationof this STC removes the 23rd December 2013 limitationrelated to the Cargo Door as imposed by EASA STC 10038822Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any oth...	18/11/2013	Active	10047098
10047100	KUERZI AVIONICS AG			F50EX	THRANE & THRANE AVIATOR 300 SATCOM system WiFi option activation onF50EX S/N 315.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Initial issue: 25.869, 25.1529The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunc...	Master Document List doc N° MDL-201212603 Rev A dated 04 November 2013;Aircraft Flight Manual Supplement doc N° FMS-201212603 Rev 0 dated 20December 2012;or later revisions of theabove listed documents approved by EASA.	Restricted to S/N 315Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect uponthe airworthiness of the product.	18/11/2013	Active	10047100
10047116	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBIL ITY	TBM 700 N TBM 700 C1, TBM 700 C2 TBM 700 A, TBM 700 B	Installation of Garmin G600 PFD/ND according to Gama Engineering Ltd.modification no. 1294	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Documents List no. MDL-1294, issue 2 dated 09/10/2013Flight Manual Supplement no. AFMS-1294, issue 1Installation/post-Installation Procedures no. IPI-1294, issue 1 dated29/04/2013Instructions for Continued Airworthiness no. ICA-1294, issue 1 dated29/04/2013or later revisions of the above list...	This installation is not compatible with SOCATA modification no.MOD70-176-00 or MOD70-276-00 (Garmin G1000 flight deck installation) Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change a...	19/11/2013	Active	10047116
10047138	THUNDER BAY AVIATION Ltd.		TCCA SA11-53 ISSUE 1	DHC-6 SERIES 300, 310, 320. DHC-6 SERIES 200, 210, DHC-6 SERIES 100, 110,	Elevator & Rudder Trim Tab Control Cable Replacement	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Thunder Bay Aviation Ltd. Master Drawing List MDL1001 Rev. D, TCCAapproved June 4, 2012or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Thunder Bay Aviation Ltd. Instructions for Continued Air...	Eligible control cables are listed on TCCA approved STC SA11-53 issue 1or later TCCA approved version.The Thunder Bay Aviation Trim Tab Control Cables to be manufactured andtestedin accordance with TCCA approved MDL 1001 (see above).Priorto installation of this design change it must be determinedt...	20/11/2013	Active	10047138
10047152	AERO VODOCHODY AEROSPACE A.S.	REV. 1		EMB-145MP. EMB-145LU, EMB-145MK, EMB-145EU, EMB-145LR, EMB-145EP, EMB-145ER, EMB-135ER, EMB-135LR, EMB-135BJ, EMB-145,	Implementations of provisions for EFB class 2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. AM007-46-20-MDL, issue b, dated 20/11/2013.Drawing List ref. AM007-46-20-DL, issue -, dated 24/06/2013.Certification Plan ref. AM007-46-20-EO, issue -, dated24/06/2013.AFM supplement ref. AM007-46-20-AM, issue -, dated 24/06/2013.AMM supplement ref. AM007-46-20-MM, issue -, da...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/11/2013	Active	10047152

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047156	PWI Inc.		FAA STC SA01634WI	300, B300, B300C	LED Lighting for Cabin OverheadInstallation of Light Emitting Diode (LED) lighting in cabin overhead.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of Light Emitting Diode (LED) lighting in cabin overhead inaccordance with Lee Products Engineering Services, Inc., Master DrawingList, 350-MDL-001, Revision IR, dated July 1, 2011;Continued Airworthiness in accordance with Instructions for ContinuedAirworthiness Lee Products Engineerin...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	20/11/2013	Active	10047156
10047157	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	A320-214	Honeywell TCAS II system upgrade to change 7.1.Installationof Honeywell TPA-100B TCAS II Traffic Computer, p/ n940-0351-005.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Summary Sheet H4A1673 Issue 2, dated 26/09/2017;Instructions for Continued Airworthiness H4ADR783 Issue 2,dated26/09/2017;Airplane Flight Manual Supplement H4AFMS033Rev. 1, dated 26/09/2017;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/12/2017	Active	10047157
10047182	RUECKER AEROSPACE GmbH			A320-232	Installation of cabin, seat and electrical system modifications insupport of the DLR SANDRA project	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List MDL-239-00007-000 Issue A, dated 11/06/2013Compliance Statement CST-239-00007-000 Issue A, dated 05/06/2013Declaration of Compliance dated 11/06/2013Instruction for Continued Airworthiness EO-239-00007-000A Issue A, dated16/05/2013Airplane Flight Manual Supplement AFS-239-00007-...	None	22/11/2013	Active	10047182
10047189	PMV ENGINEERING	REV. 1		757-200	In-Flight Entertainment System Installation on Boeing 757-200This STC changes the cabin lay-out (introduction of new seats and newLOPA), and installs an IFE System, developed by the IMS Company, withindividual displays incorporated to the new seats.Notes: 1-,,This STC constitutes an AMOC to AD 2007-1...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-02 Heat release and smoke densityrequirements to seat materialsThe requirements for environmental protection and the associatedcertified noiseu...	Master Document List, ref : SCA-00240-MDL-R01, dated 21 March 2014Instruction for Continued Airworthiness, ref : CAB-00700-ICA-R00, dated14 November 2013Instruction for Continued Airworthiness, ref : CAB-00701-ICA-R00, dated14 January 2014Instruction for Continued Airworthiness, ref : SCA-00240-ICA-...	1-,,This approval is limited to Boeing 757-200 aircraft models equippedwith three pair of Type I exits plus one pair ofimproved Type I exitsat door n° 2 as per FAA TCDS A2NM. 2-,,Airworthiness Limitations: Minimum Mandatory Cabin Crew Members induty for this cabin configuration is set to 6 and distr...	24/03/2014	Active	10047189
10047200	VECTOR AEROSPACE HELICOPTERSERVICES INC.		FAA STC SR02398AK	AS 332 C, L, L1	Installation of an Astronics Luminescent System Inc. HelicopterEmergency Egress Lighting System in accordance with Vector AerospaceHelicopter Services USA Inc. Master Drawing List, HP 332-33-50-102Revision B, dated April 2013.This STC is the validation of FAA STC SR 2398 AK.(Date amended August 22,2...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Vector Aerospace Helicopter Services USA, Inc. InstructionforContinued Airworthiness HP 332-33-50-251,Revision A dated April 22,2013.-Vector Aerospace Helicopter Services USA, Flight Manual Supplement HP332-33-50-301,Revision A dated August 22,2013or later revisions of the above listed documentsa...	The installation of this modification is considered supplementary to theexisting emergency lighting system.-Any rotorcraft incorporating this change must also be equipped with anoperational and unmodified emergency lighting system conforming to theoriginal Type Design.Prior to installation of this d...	25/11/2013	Active	10047200

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047213	AMTECH AERONAUTICAL LIMITED		TCCA C-LSA11-017/D ISSUE 1	CL-600-2B16 (604 VARIANT)	Frequency Converter System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. C-LSA11-017/D Issue 1 dated 14 January 2011Bombardier Aerospace Master Document List No. BAS63010125, Revision Adated 16 February 2011.or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBil...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/11/2013	Active	10047213
10047221	DELTA ENGINEERING CORPORATION	REV. 1	FAA ST031162NY	A340-641, A340-642 A340-541, A340-542 A340-300	Installation of Panasonic Global Communication Suite (GCS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Airplane Flight Manual Supplement No. 0661-08330-2316Revision A dated 29 September 2014Delta Engineering Instructions for Continued Airworthiness AndElectrical Wiring Interconnect System Instructions for ContinuedAirworthiness No. 0761-08331-2316 Revision F dated 02 September 2014o...	1. Operational approval to use T-PED's must be obtained separately fromthis STC.2. T-PED tolerance is approved by EASA STC 10052484 (required forconfigurations approving activation of eXConnect, eXW and/or eXPhone).,,a- When installing/activating the GCS on the aircraft the aircraft mustcomply withb...	24/11/2015	Active	10047221
10047222	STANDARD AERO	REV.1	FAA STC ST00764CH	727, 727C 727-100/ -100C/ -200/ -200F	Installation of dual Universal Avionics UNS-1D or UniversalAvionicsUNS-1F Flight Management Systems with optional Universal MFD-640.Rev. 1: RNP limitation removed.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements thefollowing paragraph(s) at a later amendment:-CS25.853 at amdt. 0 (equivalent to FAR 25 amdt. 25-116).-JAR25.1322 (b)(c)(d) at change 8 (equivalent to FAR 25 amdt. 25-3...	Master Data List 1021801 Rev. F.Airplane Flight Manual Supplement ES727-108936-100 Rev. 2.Airplane Flight Manual Supplement 1021983 Rev C.Instruction for Continued Airworthiness 1021826 Rev. B.Maintenance Manual Supplement ES727-108936-200Rev. IR -,,or later revisions of the above listed documentsa...	As per AFMS.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/12/2016	Active	10047222
10047226	MT-PROPELLER ENTWICKLUNG GmbH			PA-46-500TP	Installation of 5-blade MT-Propeller ModelMTV-27-1-E-C-F-R(P)/CFR203-58d	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	According to MT-Propeller Master Document List No. E-2173 andMT-Propeller Installation Instructions Doc. No. E-2169, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2168To be maintained i.a.w. MT-Propeller ICA Document No. E-2170or later revisions of the above li...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The install...	26/11/2013	Active	10047226
10047253	GFD GmbH	REV. 1		L31A 31A	FMS/GPS Antenna ProvisionRev. 1: Transfer to GFD GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ICA Instructions for Continued Airworthiness Doc. No.5290-085- Master data list Doc. No. 5290-049or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/08/2022	Active	10047253
10047254	GFD GmbH	REV. 1		L31A 31A	VHF Antenna ProvisionRev. 1: Transfer to GFD GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ICA Instructions for Continued Airworthiness Doc. No.5263-085- Master Data List Doc. No. 5263-049or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/08/2022	Active	10047254

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047255	GFD GmbH	REV. 1		L31A, 35A, 36A 31A, 35A, 36A	UHF Antenna ProvisionRev. 1: Transfer to GFD GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ICA Instructions for Continued Airworthiness Doc. No.5260-085- Master data list Doc. No. 5260-049or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/08/2022	Active	10047255
10047256	ANCRA INTERNATIONAL LLC		FAA ST02483LA	767-300	Installation of Mechanical Cargo Loading System Main Deck for BoeingConverted Freighters (BCF).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25.23, 25.29,25.301(a)(b), 25.303, 25.305(a)(b), 25.307(a), 25.471, 25.561, 25.601,25.603, 25.605, 25.607, 25.609, 25.6...	Ancra International LLC Controlled Data List DL85250, Revision D, 30/09/2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agr...	To be install only on a/c converted to a freighter by the BCFmodification, Boeing SB 767-00-0039Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadver...	28/11/2013	Active	10047256
10047280	AIRBUS S.A.S.			A319-115	Airbus Corporate Jet Centre - Top Modification CJ1230 - VIP Project«LAGUNA BLANCA»	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements as listedin the General CRI A-4301-013 "ACJC Project Certification Basis" inAppendix to this TV.The requirements for environmental protection and the associatedcertified n...	· Modification Approval Sheet, ref. CJ1230, Issue 1, dated 29th November2013· Airplane Flight Manual - AFM Supplement, ref.: FM-S MOD CJ1230Revision 1st November 2013· MaintenancePlanning Document - MPD Supplement, ref : MPD-S MODCJ1230 Revision 1st November 2013or later revisions of the above lis...	This STC is limited to MSN 4768.	29/11/2013	Active	10047280
10047325	CONCORDE BATTERY CORPORATION		FAA SA01703WI	EMB-505	Concorde Lead Acid Battery replacement for the existing Lead AcidBatteryon the Embraer EMB-505 "PHENOM 300"	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. Since the EASA certification basis forthe original product is different fromthe FAA Certification basis, CRIF-01 "Special condition forBattery endurance requirements" (which ispart of the origina...	Master drawing list DWG No 5-0449, revision B dated 17 July2012Instruction For Continued airworthiness 5-0453 dated 10July 2012No AFM revision is associated to this changeor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentt...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/12/2013	Active	10047325
10047327	S-TEC CORPORATION		FAA SA8404SW-D	58 AND 58A	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-550.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with S-TEC Bulletin No 650, Revision 1, dated3-16-01 and Master Drawing List No 92703, Revision A, dated 3-16-01 (28Volt System).Operation in accordancewith FAA Approved Pilot's Operating Handbookand/or AirplaneFlight Manual Supplement Part No 891091, dated 8-08-94,orFAA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/12/2013	Active	10047327

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047351	INDUSTRIAL NEOTEX S.A.		CAA UK RESPONSIBILITY	SF 25 B	Use of Unleaded Avgas in SF25B with Stamo MS1500 engine	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	To be installed in accordance with "Certification Program for STC No0010025506" dated 02.12.2013;To be operated in accordance with AFMS in appendix 2 of "CertificationProgram for STC No 0010025506" dated 02.12.2013To be maintained in accordance with ICA in appendix 3 of "CertificationProgram for STC...	As per the AFM supplementPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	04/12/2013	Active	10047351
10047365	TELEDYNE UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	767-400ER 767-200, 767-300, 767-300F 767-200/-300/-300F/-400ER	Installation of Enhanced Airborne Data LoaderRev. 1: Transfer from Teledyne Limited to Teledyne UK Limited.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:JAR25 Change 14:JAR 25.23, JAR 25.25, JAR 25.27, JAR 25.561, JAR 25.603, JAR 25.605, JAR25.869, JAR 25.1301, JAR 25.1309...	Teledyne Controls Master Data List MOD-MDL-026 Issue 02<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/11/2020	Active	10047365
10047367	AIRGLAS, Inc.		FAA STC SA02069AK	SEE EASA APPROVED MODEL LIST	Fabrication and installation of the Airglas, Inc., Landes PA32-206LANose Fork equipped with Goodyear 8.50 x 6 tire in accordance with FAASTC SA02069AK, last amended by FAA June 5,2006 or later FAA approvedissue.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airglas Master Data List PA32-206LA, Revision D, dated May 26, 2006Airplane Flight Manuals see AMLInstallation Instructions see AMLor later revisions of the above listed documentsapproved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Te...	1. Airplanes incorporating this STC may be equipped with 6.00-6, 7.00-6,8.00-6, or 8.50 x 6 tires on the nose and main wheels. The nose tiremust be the same size as the main tiresin all installations.2. Compatibility of this STC with previously approved modifications mustbe determined by the instal...	05/12/2013	Active	10047367
10047368	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-216/-231/-232/-233 A320-111/-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of HBL Power Systems Ltd P/N NCSP B 23060LM Ni-Cad Battery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Compliance Report, ref. doc. TEN 625/1, Issue 2, dated4th December 2013-Modification TEN 625, ref. doc. TEN 625, Issue 2, dated 4th December2013-Declaration of Compliance for Installation of HBL Power Systems Ltd P/NNCSP B 23060LM Ni-Cad Battery, dated 4th December 2013or later revisi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	05/12/2013	Active	10047368
10047369	BOMBARDIER INC.		TCCA STC SA07-55	BD100-1A10	Installation of a Heads Up Technologies CMS-400 Digital Voice Check-ListSystem in accordance with Modification Data Summary E522000 Revision Adated September 12, 2012.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Data Summary E522000 Revision A dated September 12, 2012-Airplane Flight Manual Supplement H639090 REV N/C dated 2 August 2012-Instructions for Continued Airworthiness and supplemental maintenanceinformation H639070-ICA REV N/C dated 10 August 2012or later revisions of the above lis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/12/2013	Active	10047369

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047374	AVIATION SUPPORT GmbH	REV. 1		MD900	Installation of Searchlight Trakkabeam A800 on MD900/902.Rev 01. Removal of CAT-A limitations	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS-ASE-90919, rev 1-0, dated 20 October 2016.or later revisions of the above listed documentsapproved by EASA.Instructions for Continued Airworthiness ICA-ASE-90919 Rev 1-0, dated 20October 2016Master Document List MDL-ASE-91610, initial issue, dated 27 June 2017	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2017	Active	10047374
10047380	GULFSTREAM AEROSPACE CORPORATION		FAA STAC ST04291AT-D	GV-SP	Installation of an Executive Completion Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01 "Shower Installation"Equivalent Safety Finding(s): CRI D-50 "Cabin regress and Seatencroachment"The requirements for environmental protectio...	-FAA Approval ST04291AT-D, Date of Issuance 13th November 2013.-FAA Statement of Compliance 100G-13-275, dated 5th December 2013.-FAA Approved Index List GC520008775, Revision J, dated 13th November2013-Airplane Flight Manual Supplement - AFMS - GC52000M142, Revision -,dated 13th November 2013-Instr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	06/12/2013	Active	10047380
10047398	JAMCO AMERICA, INC.		FAA STC FAA ST01482SE	MD-11F	Installation of a new courier module on MD-11F series airplanes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	IA-119MDL<(>,<)> Revision B, December 27, 2005 - Master Data List<(>,<)>UD-CP-083, Revision A, June 29, 2004 - Certification Plan courier module<(>,<)>UD-S-A793, Revision NEW, October 04, 2004 - Instructions for ContinuedAirworthinessor later revisions of the above listed documents approved by EASAa...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/12/2013	Active	10047398
10047400	P3 ENGINEERING GMBH			B737-800	Installation of Interior Attachment Components	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amendment 12 for the affected area.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product ar...	Instructions for Continuous Airworthiness P3V-100018-ICA-0001-AMaintenance Manual Supplement P3V-100018-MMS-0001-AMaintenance Planning Document P3V-100018-MPD-0001-AWeight and Balance Report P3V-100018-WBS-0001-BMaster Document List P3V-100018-MDL-0001-A issued December 06th, 2013or later revisions...	Maximum Loads at interface points of attachments not to be exceeded forfollowing aircraft modifications as per P3V-100018-IMA-0009-D.Prior to installation of this design change itmust be determined thatthe interrelationship between this design change and any otherpreviously installed design changea...	09/12/2013	Active	10047400
10047408	LUFTHANSA TECHNIK AG	REV. 2		777F	Installation and activation of an Electronic Flight Bag (EFB) on aB777-FThis STC installs (using provisions from OEM options) and activates aClass 2 EFB in the cockpit, composed of touch screen displays mounted atthe OEM locations for the LH and RH Class 3 EFB, and docking stationshoming personalize...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 at Amdt 3 for the following paragraphs: 25.1302The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origina...	Engineering Bulleting, Lufthansa Technik 777-EB46-0069 revision 02Engineering Bulleting, Lufthansa Technik 777-EB46-0073 revision 03Airplane Flight Manual Supplement, Lufthansa Technik A-00-13/54-AFMIssue 03 revision 00Instructions for Continued Airworthiness, Lufthansa TechnikA-00-13/54-ICA Issue 0...	1-,,The following Boeing options must be embodied on aircraft prior tothe subject modification: 4610E161A10, 4610E161A11, 4610E161A12,4610E161A20.2-,,The following Engineering Bulletins, approved as minor changes underLufthansa Technik DOA, are required to be performed prior to the subjectmodificati...	22/10/2014	Active	10047408

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047411	FLYING COLOURS CORP.		TCCA STC C-LSA13-104/D	BD-700-1A10	Modification to Existing Interior Completion	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. C-LSA13-104/D Issue 1 dated 31 October 2013ACS-NAI Ltd. Modification Data Summary J089000 Revision NCInstructions for Continued Airworthiness document J089075 Revision NCor later revisions of the above listed documents approved by EASA inaccordance with the Technical Impleme...	Restricted to ASN 9003EASA STC No. 10041031 is a pre-requisite for this modificationPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect up...	10/12/2013	Active	10047411
10047437	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 10		MBB-BK117 D-3M MBB-BK117 D-3 MBB-BK117 D-2 MBB-BK117 C-2	Installation of Flight Data Monitoring and Transmitting System HELICOMV2 NUM or HELICOM V2+ NUM.Initial: The HELICOM V2NUM consists of a recording / transmitter offlight and system's parameters.Revision 1: This change extends the capabilities of the system byintroducing PN 4723P / PN 4733P. The ext...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 "Lithium battery installations" dated11th December 2013 (raised inEASA project No. 0010026494-001 - theinitial STC) the followi...	For both systems:List of Documents, N10-EC145 HV2+ NUM, Rev. E-01For the HELICOM V2 NUM system:Certification Programme,N2-EC145 HV2-NUM-E-A-04 dated 4th December2013;Installation Manual, N7-EC145 HV2-NUM-E-A-04 dated 4th December 2013;Maintenance Manual Supplement, N8-EC145 HV2-NUM-E-A-04 dated 4th...	The installation of this modification by third persons is subject towritten permission of the approval holder.The HELICOM V2 NUM system is approved for the model MBB-BK117 C-2.TheHELICOM V2+ NUM system is approved for the models MBB-BK117C-2,MBB-BK117 D-2, MBB-BK117 D-3 and MBB-BK117 D-3m.Prior to...	24/03/2022	Active	10047437
10047440	ROCKY MOUNTAIN AIRCRAFT		TCCA STC SA12-13	DHC-6 SERIES 300 DHC-6 SERIES 100, SERIES 200,	Installation of Electronics International MVP-50T Engine Display Systemiaw. TCCA STC SA12-13	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 23 Amdt. 49: 23.1309, 23.1311, 23.1322The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original productu...	Flight Manual Supplement E101530, IR, TCCA approved February 9, 2012RMA Modification Instruction E101510, Rev. A (aircraft)RMA Modification Instruction E101511, IR (engine)or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of E...	This installation is approved for the DHC-6 airplane carrying 9passengers or less. For DHC-6 airplane carrying 10 or more passengers,Electronics International M-1T Standby Torque Indicator(s) must beinstalled to display the torque information of both engines.Prior to installation of this design chan...	12/12/2013	Active	10047440
10047441	GROWING ENGINEERING PARTNERS GmbH	REV. 1		767-200	767 Comlux Aviation Cabin Modificationas defined in the:-Project description, Doc. No. 767 Comlux Project Description_Rev 00-Master Data List, Doc. No. S.OAVED.000003-MDL_R00Rev.1: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	-Master Data List, Doc. No. S.OAVED.000003-MDL_R00-AFMS, Doc. No. S.OAVED.000003-AFMS Rev 00-ICA, Doc. No. S.OAVED.000003-ICA Rev 00or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	20/04/2021	Active	10047441
10047456	DASSAULT FALCON SERVICE			FALCON 10	Universal Avionics MFD-640 upgrade on Falcon 10	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet doc. DFS1300-CAS Issue A dated 06December2013.DFS Modification Sheet doc. DFS1300 Issue A dated 06 December 2013.or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/12/2013	Active	10047456

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047457	SABENA TECHNICS BGC	REV. 2		737-900, 737-900ER. 737-600, 737-700, 737-800,	Smart PCMCIA Card (SPC) installation for the SAGEM "Wireless ExtensionFor ACMS" system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25 amdt 4: 25.601,25.603, 25.611, 25.869(a), 25.899, 25.1301<(>,<)> 25.1307 (b)(c),25.1309, 25.1351, 25.1353, 25.1357, 2...	Master Data List 0550-01-A-2103-R00SPC Component Maintenance Manual 31-35-78 rev 00Instruction for Continued Airworthiness (ICA) 0550-01-A-2211 rev 01or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/10/2014	Active	10047457
10047459	DASSAULT FALCON SERVICE			FALCON 10	FMS UNS-1L Activation of Approach Mode on Falcon 10	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt 3: §1302 (c)The requirements for environmental protection and the associatedcertified noise and/ oremissions levels of the original product areunchanged and re...	DFS Change Approval Sheet doc. DFS1299-CAS Issue A dated 06December2013.DFS Modification Sheet doc. DFS1299 Issue A dated 06 December 2013.DFS Airplane Flight Manual Supplement N° F10-038A, Original issue dated12 December 2013.or later revisions of the above listed documents approved by EASA	FMS airworthiness compliance is demonstrated for:- RNP APCHwithout Baro-VNAV (AMC 20-27)- Conventional approaches (GPS, VOR, VOR/ DME) (AC 20-130A)- GPS overlay approaches (AMC 20-5) Approaches are authorized only in manual and without flight director.Prior to installation of this design change it mu...	13/12/2013	Active	10047459
10047463	MEGGITT SAFETY SYSTEMS, Inc.		FAA SA3499NM	727-200F	Installation of Systron Donner Smoke Detectors Part Number 7740 onBoeing 727-200F Series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Systron Donner Control Drawing 7940, Revision "B", dated October 20,1987Component Maintenance Manual 26-14-65 rev.7 dated 2012-07-15or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Te...	A mixed configuration of this installation and that of the existingsmoke detector installation is not allowed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will int...	13/12/2013	Active	10047463
10047481	LUFTHANSA TECHNIK AG			A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322	EFB ConnectivityConnection of installed EFB Class 2 to company server via aircraftdatalink (ATSU communication function)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):F-01 Data SecurityThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product are...	Compliance Record List CRL46-12/12M, Iss./Rev.: 2 / 0, Dated 4th ofDecember of 2013.or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	16/12/2013	Active	10047481
10047490	S4A SOLUTIONS FOR AVIATION, S.L.			BD-700-1A10	Aviator 350 SATCOM System Installation in Global Express BD-700	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	GEX01-SB001 Service Bulletin Ed3GEX01-HDK01 Flight Manual Supplement Ed4GEX01-HDK02 Maintenance Manual Supplement Ed4orlater revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	16/12/2013	Active	10047490
10047491	SABENA TECHNICS BGC	REV. 2		A340-311/-312/-313	eXPhone System Activation on A340-300 with eXConnect.Description - Summary :The Panasonic eXPhone system allows passengers to use their own cellphone or TPED(Transmitting PersonalElectronic Device) while in flight for cellularvoice and IPdata services.GSM (voice and text) and GPRS/Edge (data) prot...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt. 4 : 25.23; 25.301; 25.581; 25.601; 25.603; 25.611;25.869(a); 25.899; 25.1301; 25.1307(b)(c); 25.1309; 25.1351; 25.1353;25.1355; 25.1357; 25.1360; 25.1431; 25.1...	- Master Document List (MDL) : ref 0634-02-A-2103 rev 2- Instructions for Continued Airworthiness : ref 0634-02-A-2211 rev 3- Airplane Flight Manual Supplement : ref 0634-02-A-2301 rev 3or later revisions of the above listed documents approved by EASA.	1) Prior to installation of this modification it must be determined thatthe interrelationship between this modificationand any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of the product.2) The eXPhone system installation is contingentd...	11/05/2016	Active	10047491

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047494	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS	REV.1	CAA UK RESPONSIBIL ITY	A340-313, A340-642	AIRBUS TCAS 7.1 UPDATE(Honeywell TCAS computer part number changed from 940-0351-001 to940-0351-005 to correct False RAissue)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amendment 13 for the requirements affected by this changeThe requirements for environmental protection and the associ...	- Master Data List - Doc ref: BA-340-34-0001-MDL, Issue 3-STC Definition & Certification Document – Doc Ref: BA-340-34-0001-STC,Issue 3- Compliance Check List – Doc Ref: BA-340-34-0001-CCL, Version 00or later revisions of the above listed documents approved by EASA.- Service Bulletin No. BA-340-34...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/11/2017	Active	10047494
10047498	PFW ENGINEERING GmbH	REV. 1		ATR 42-500	Integration of a Flight Inspection System into an ATR 42-500The purpose of this modification is to integrate a Flight InspectionSystem from Aerodata into a VIP-configuration ATR 42-500. Theinstallation consists of an additional set of antennas, an ObserverConsole in the Cabin facing a standard doubl...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Airplane Flight Manual (AFM), PFW reference AT45A-AFM-A,revision 01, dated 21 November 2013Instructions for Continuous Airworthiness (ICA), PFW referenceAT45A-ICA-A, revision 02 dated 08 April 2014or later revisions of the above listed documents approved by EASA.Master Drawing List, PFW...	1-,,This approval is limited to ATR 42-500 MSN 6732-,,Referto AFM supplement AT45A-AFM-A section 2 for operatinglimitations3-,,Refer to ICA document AT45A-ICA-A for airworthinesslimitation itemsPrior to installation of this design changeit must be determined thatthe interrelationship between this...	27/05/2014	Active	10047498
10047501	AEROTEC & CONCEPT			B200	MOD 13126 - WIFI and Immarsat Installation	CS-23 Amdt. 3 for electrical, avionic and cabin modificationrequirements as listed on document AE13126PCDP rev. 3The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ ap...	-Master Data List AE13126MDL Rev0 dated 11/12/2013-Flight Manual Supplement AE13126AFMS Rev0 dated 13/08/2013-Instructions for Continued Airworthiness AE13126ICA Rev1 dated29/07/2013-Rear Tail Tray Installation AE13126JC-03 Rev0 dated 16/07/2013-Safety Precaution for Ferry Flight AE13126JC-01 Rev0 d...	Limitation to serial number BB-1006Prior to installation ofthis design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The installat...	17/12/2013	Active	10047501
10047524	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBIL ITY	737-800/-900/-900ER 737-300/-400/-500/-600/-7 00	TCAS System Upgrade to Change 7.1 on Boeing 737 Aircraft for HoneywellSystems	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Modification Summary Sheet MOD H4A1675 Issue 2-Airplane Flight Manual Supplements H4AFMS034 Issue IR, H4AFMS035 IssueIRor later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	22/04/2014	Active	10047524
10047525	AEROTEC & CONCEPT	REV. 1		MF20 GF	Mode EHS & ADS-BDescription:The aim of the change is to have ADS-B capabilities approved as per EASAAMC 20-24, and comprises the following set of modifications, as per theCertification Program ref. AE13192PCDP Rev. 3, dated 18/12/2013:- Installation of two GPS antennas, P/N S67-1575-145.- Installati...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. AE13192MDL Rev. 1, dated 18/12/2013orlater revisions of the above listed documents approved by EASA.	Applicability limited to Mystère Falcon 20 GF model, S/N 397.- The current ADS-B out installation has been certified in accordancewith the EASA AMC 20-24 for Non-Radar areas, with the relatedlimitations stated in the AFMS ref. AE13192AFMS Rev. 0.- Additional limitations as per AFMS ref. AE13192AFMS Re...	19/12/2013	Active	10047525
10047526	AERODATA AG			B300	Installation of Aerodata Flight Inspection System AD-AFIS-113	The Certification Basis for the original product remains applicable foritems not affected by the modification, for items affected by themodification the following new Certification Basis is elected to complywith: CS-23 Amdt. 3, except 23.561 and 23.785 (kept FAR 23.561 Amdt. 34and FAR 23.785 Amdt. 3...	Installation in accordance with Master Document List, Aerodata Doc. No.MDL-A/ C-848, Rev. 2, dated 04 December 2013;Aircraft Flight Manual Supplement, Aerodata Doc. No. AFM-139, Rev. 0,dated 26 November 2013;Aircraft Maintenance Manual Supplement, Aerodata Doc No. AMM-1144, Rev.0, dated 03 December 2...	Only applicable for Serial FL-859Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverseeffect upon the airworthiness of the product.	18/12/2013	Active	10047526

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047564	HELI-ONE (NORWAY) AS			AS332L/AS332L1	MOD AHSE -64040 ,VOR Receiver upgrade.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 amendment 3The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain a...	- Heli- One AHSE-64046 - General Arrangement.- Heli- One AHSE-64048 Rev A Embodiment instructions.- Heli- One AHSE-64043 Rev.: A Certification Plan.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	19/12/2013	Active	10047564
10047589	MT-PROPELLER ENTWICKLUNG GmbH			PA-30, PA-39 (TWIN COMANCHE)	Installation of 3-blade MT-Propeller Model MTV-12-C-C-F/CF(L)180-57 onPiper PA-30, PA-39 (Twin Comanche).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	According to MT-Propeller Master Document List No. E-2353 andMT-Propeller Installation Instructions Doc. No. E-2350, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2349To be maintained i.a.w. MT-Propeller ICA Document No. E-2351or later revisions of the above li...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/12/2013	Active	10047589
10047608	HELI-ONE (NORWAY) AS			AS332L, AS332L1	MOD AHSE - 63585 <(>,<)> EURONAV 7 Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 ;amendment 3The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain...	- Heli-One Flight Manual Supplement NºH1No-201 "EURONAV 7 INSTALLATIONAHSE-63685" Rev- dated 21 Dec. 2013or later revisions of the above listed documents approved by EASA.- Heli-One AHSE-63586 Rev - Master Drawing.- Heli-One AHSE-63594 Rev B Embodiment instructions.- Heli-One AHSE-63587 Rev A -Cer...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	23/12/2013	Active	10047608
10047619	ACS-NAI Ltd.		C-LSA10-047/ D	CL-600-2B19	Installation, Complete Custom Aircraft Interior - ASN 8103	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	Transport Canada STC No. C-LSA10-047/D Issue 1 dated 18 October 2010ACS-NAI Ltd. Modification Data Summary G425000 Revision NC.Aero Consulting Services Ltd. Mandatory Maintenance Manual SupplementG192070 Revision NCAero Consulting ServicesLtd. Mandatory Maintenance Manual SupplementG099071 Revision...	Restricted to ASN 8103Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The installation of this m...	06/01/2014	Active	10047619
10047621	AEROTEC & CONCEPT	REV. 2		SA 226T-(B)	Installation of Sandel SN 4500 EHSI and L3 Avionics SKY 899TAS.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 Amdt. 2, § 867,1301, 1309, 1311, 1321, 1322, 1327, 1351, 1353, 1357, 1365, 1387, 1431,1529, 1541, 1581The requiremen...	Master Data List AE12064MDL rev 4 dated 18.06.2018;Flight Manual Supplement AE12064SMVGNS530AW Rev.1 dated 18.12.2013;Flight Manual Supplement AE12064SMVSKY899 Rev. 0 dated 18.07.2012;Flight Manual Supplement AE12064SMVSN 4500 Rev.1 dated 17.03.2013;or later revisions of the above listed document(s)...	This installation is approved for IFR B-RNAV, P-RNAV, RNP app. LNAV andLPV operations, with coupling to AP 80 or M4D autopilot.RNP LNAV - VNAV-APV baro approaches are not authorized.The installation of this modification by third persons issubject towritten permission of the approval holder.Prior to...	25/07/2018	Active	10047621

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047652	SAFRAN POWER USA, L.L.C.		FAA ST03195CH	60	Fitment of Safran starter generator by STCInstallation of Safran starter-generator model 23091-009 and QAD kit23091-500on Learjet 60.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Goodrich drawing<(>,<)> 230910009 rev. C, dated August 9, 2013Goodrich drawing<(>,<)> 23091-500 rev. –<(>,<)> dated November 3, 2011Safran Instructions for Continued Airworthiness, LJ60-MENG-ICA-001,issue 3, dated May 2 2013.or later revisions of the above listed documents approved by EASA inaccorda...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/01/2014	Active	10047652
10047653	AIRBORNE TECHNOLOGIES GmbH	REV. 2		P.68TC "OBSERVER" P.68R "VICTOR" P.68 "OBSERVER 2" P.68 "OBSERVER" P.68C, P.68C-TC	P.68 Mission cabin configuration with Option for Flight into Known Icingfor P. 68R “VICTOR”STC-AT-071() certifies the Mission cabin configuration, prerequisitesand the general installation into the P.68.The STC-AT-071() consists of the following steps which can be performedas required.Step:1: “Missio...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-23, Amendment 3:23.21, 23.23, 23.29, 23.45, 23.49, 23.51, 23.53, 23.65, 23.67, 23.69,23.73, 23.75, 23.77, 23.141, 23.14...	Change/Repair Approval, Doc. No. STC-071C-G-AS, Rev. 0Installation Instructions, Doc. No. 071-II-STC-AT, Rev. 1, dated20.03.2018 (related to Step 1 to 7)Installation Instructions,Doc. No. STC-071C-G-II, Rev. 0, dated18.09.2019 (related only to Step 8)For Step 1 of STC-AT-071:AFM Supplement, Doc No....	The Installation of this STC-AT-071() is only allowed in aircraft wherea Letter of Authorization “STC-071()-G-LOA” has been issued by AirborneTechnologies GmbH.Prerequisites for each individual step of this STC are defined insection 1.1 ofthe installation instructions Doc. No. 071-II-STC-AT orsecti...	20/09/2019	Active	10047653
10047657	LUFTHANSA TECHNIK AG	REV. 1		737-800	"Collector" VIP Cabin CompletionRev 1: Update of referencedICA documentation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):-,,D-01 Installation of an open cooktop in the galley area of a VIPinterior-,,D-05 Isolated Compartments-,,D-06 Glass Screens of Displays / Monitors...	Supplemental Type Definition Document STDD00-12/19M issue 03AFMS A-00-11/175-AFM issue 05ICA A-00-11/175-ICA Issue 04Cabin Crew Manual A-00-11/175-CAM issue 05or later revisionsof the above listed documents approved by EASA	The installation of STC 10047400 rev.0 is a prerequisite toinstall thedesign changes considered in the above mentioneddocumentation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change...	22/07/2015	Active	10047657
10047658	TAIKOO (XIAMEN) AIRCRAFT ENGINEERINCO. LTD. d/b/a HAECO XIAMEN	REV. 1		A319-115	VIP interior reconfiguration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-4302-011 "Isolated Compartment"CRI D-4306-007 "Seat Heat Release and Smoke Density"CRI D-4310-011 "Glass Screen of Display Monitors"Deviation(s)...	-,,HKCAD STC-2013-12, Rev.3, dated 10/03/2015-,,Master Drawing List TA319-AD-MDL Rev AF, dated 18/10/2013 (for MSN5023)-,,Master Drawing List TA319-AD-MDL-002 Rev H, dated 31/07/2014 (for MSN5088 and 5907)-,,Compliance Summary Report TA319-AD-CSR Rev D, dated 6/3/2015-,,Instructions for Continued Ai...	This approval is valid for installation on A319-115 MSN 5023, 5088 and5907.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the ai...	17/11/2015	Active	10047658
10047659	WIPAIRE Inc.		FAA SA02967CH	B) 182S, 182T A) 182P, 182Q, 182R	Installation of modified engine mount in accordance with Wipaire, Inc.Installation Drawing	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Drawing:- Cessna 182P, Q, R: Drawing 1002682, Rev. C, dated 27 November 2012-Cessna 182S, T: Drawing 1002683, Rev. C, dated 17 January 2012Instruction for Continued Airworthiness: see aircraft OEM instructionor later revisions of the above listed documents approved by EASA inaccordance...	1. The installer must determine whether this design change is compatiblewith previous approved modifications.2. If the holder agrees to permit another person to use this certificateto alter the product, the holder must give the other person writtenevidence of that permission.	09/01/2014	Active	10047659

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047665	HARTZELL PROPELLER LLC	REV. 1	FAA SA03078CH	3) 182S, 182T, T182T 2) FR182 1) R182, TR182, T182	Installation of HC-(C, I, F)3YR-1(A)RF/ F8068(B, K) or HC-(C, I,F)3YR-1(A)RF/ F7693F(B, K)+2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels	Airplane Flight Manual Supplement AFMS H1010-9, Rev. IR, FAA approvedMay 4, 2012Installation Instructions H1010-3, Rev.IR, FAA approved April 26, 2012or later revisions of the above listed documents approved by EASA inaccordance with EASAED Decision 2004/04/CF (or subsequent revisions ofthis decis...	If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.	13/01/2014	Active	10047665
10047686	STANDARD AERO		FAA STC ST03491AT	BD-7001A11 BD-7001A10	Installation of the TrueNorth Simphone Chorus Cabin Communication SystemProvision into Bombardier Model BD-700-1A10 and1A11 Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No ST03491AT dated 08 February 2013.Savannah Air Center MDL. GX9022-MDL-2314001 Rev. A dated 13 September2007.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implem...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/01/2014	Active	10047686
10047688	PMV ENGINEERING	REV. 1		737-800	Activation of a Panasonic eXPhone system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Investigation Report SCA-00111-CIR Rev 03Aircraft Flight Manual Supplement SCA-00111- Rev 00Instructions for continued Airworthiness SCA-00111-ICA Rev 01or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/12/2015	Active	10047688
10047708	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST04140AT	767-200/-300/-300F	Installation of the Rockwell Collins Aircraft Communication, Addressingand Reporting System (ACARS), including Cockpit Voice Recording (CVR) Update.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.23(a)25.301(a) 25.30325.305(a)25.307(a) 25.56125.60125.603(a)(b)(c) 25.609(a)25.613(a)(b)(c)25.625(a) 25.789(a)25.853(a)25.863(a) 25.869(a)(4)25.1351(a)(1)25.1353 (a)(d)25.13...	Master Drawing List: 2-130360-001, Revision A, 04/11/2013(ACARS) AFMS: 2-130360-830, Revision IR, 04/12/20013 (CVR) AFMS: 2-130360-829, Revision IR, 04/12/2013or later revisions ofthe above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10047708
10047709	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST04139AT	767-200/-300/-300F	Installation of the Iridium Satellite Communication (SATCOM) System.Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.23(a)25.301(a) 25.30325.305(a)(b)(c)25.307(a) 25.33725.365(a)(b)(c)(d)25.561(c) 25.571(a)(b)25.581(a)(b) 25.60125.603(a)(b)(c)25.605(a) 25.60725.609(a)25.613(a)(b)(c) 25.6192...	Master Drawing List: 2-130545-001, Revision B, 30/10/2013AFMS: 2-130545-805, Revision IR, 04/12/2013ICA: 2-130545-804, Revision B, 30/10/2013or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/I...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10047709

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047724	BOGGI S.R.L.			AB139, AW139	Incubator Installation on Helicopter AW139 (Change 139P005-00)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-RFM Supplement Doc. 139P00500-RFMS-00 Issue 0or later revisions of the above listed documents approved by EASA.-MasterDocument List Doc. 139P00500-Mdl-04 Issue 4 (not EASA approved)-Instructions for Continued Airworthiness (ICA) doc. 130P00500-00-ICA-00Issue 0 (not EASA approved)	This STC requires, as prerequisite, the installation of either one ofthe following Aerolite EMS approved Cabin Configurations:-P/N 139001-502-P/N 139172-501-P/N 139172-502Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any ot...	15/01/2014	Active	10047724
10047744	H4 AEROSPACE (UK) Ltd.	REV. 2	CAA UK RESPONSIBILITY	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Honeywell TCAS II system upgrade to change 7.1.Rev. 2: Upgrade of Traffic Computer, to a new p/n 940-0351-005.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Summary Sheet H4A1656 Issue 17, dated 09/10/2017.Instructions for Continued Airworthiness H4ADR778 Issue 10, dated18/09/2017.Airplane Flight Manual Supplement H4AFMS038 Rev. 4, dated 09/10/2017.Airplane Flight Manual Supplement H4AFMS030 Rev. 6, dated 09/10/2017or later revisions of the...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/10/2017	Active	10047744
10047748	AVIONITEC AG			PA-32-301T	GNS 530 upgrade to WAAS Unit incl. LPV CertificationRemoved: Garmin GNS 530 (GPS/COM/NAV)Installed: Garmin GNS 530W (GPS/COM/NAV)Compliance showing to AMC20-28 that the installed equipment is suitablefor RNAV (GNSS) Approaches down to LPV Minima.Compliance showing to AMC20-27, resp. CRI F-10 (Airwor...	FAR 23 Amdt: 21The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List: 1268-17, dated 20.11.2013Instructionsfor continued airworthiness: 1268-015, dated 01.03.2013Airplane Flight Manual Supplement: 1268-011, dated 15.11.2013or later revisions of the above listed documents approved by EASA	S/N: 32-8224007, HB-PKJThe approval holder shall fulfill the obligations of Part 21 §21.A118.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse ef...	17/01/2014	Active	10047748
10047762	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	AS355NP	Flight with Cabin Vibration Dampers RemovedRemoval of CabinVibration Dampers by modification BOND/MOD/079 asdescribed in DR/079-001 and defined in Drawing List DL/079-099.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27.1, .251, . 301, .303, .305, .307, .601, . 603,.771, .853, .1321,.1505, . 1525, .1529, .1541, .1581, . 1583,A27.1, A27.2, A27.3, A27.4 atCS 27 Amdt. 3The requirements f...	Flight Manual Supplement AS355 NP FMS/079-002 Issue 1 dated25 Nov 13or later revisions of the above listed documents approved by EASA.-,,Design Report DR/079-001 Issue 3-,,Compliance Checklist CCL/079/003 Issue 2-,,Instructions for Continued Airworthiness ICA/079-005 Issue 2-,,Drawing List /079-099...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/01/2014	Active	10047762
10047772	AMICALE DE VOLTIGE AERIENNE(AVA)			CAP 231, CAP 231 EX, CAP 232	PROPELLER MTV14 BC C190-130 for CAP 23X	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	supplément manuel d'entretien ed 1 rev 03 du 16/01/2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/01/2014	Active	10047772
10047781	STANDARD AERO		FAA STC ST01193CH-D	MF50	Validation of FAA STC ST01193CH-D.Installation of AlliedSignal Global Airborne Flight Information System(AFIS) Satlink System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Garrett Aviation Services Certification Plan ref. 71-9103-001 rev. A,dated 10/04/2000.Garrett Aviation Services Master Drawing List ref. 71-0103-001 rev. C,dated 06/10/2000.Garrett Aviation Services Airplane Flight Manual supplement ref.71-8103-001 initial revision, dated 01/05/2000.Garrett Aviation...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	21/01/2014	Active	10047781

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047789	JCB AERO SA			A320-214	A320 cabin reconfiguration from 158 to 180 pax.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance Report A320-00883-01-CR-01 Rev. IR, dated 17/01/2014Master Drawing List A320-00883-01-MDL-01 Rev. C, dated 15/01/2014Instructions for Continued Airworthiness A320-00883-01-ICA-01 Rev. IR,dated 07/01/2014or later revisions of theabove listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/01/2014	Active	10047789
10047829	PFW ENGINEERING GmbH			767-400ER	Structural provisions for VIP Cabin Completion and for the installationof:-fin camera<(>,<)>-quad belly camera<(>,<)>-Iridium sat antenna<(>,<)>-Door locks<(>,<)>-avionic rack.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List B767A-MDR-530100 Issue B dated 16.01.2014Master Certification Document List CCN-B767A Issue 01 dated 20.01.2014Supplement to Airplane Flight Manual B767A-AFM-ARev 1 dated 22.10.2013Supplement to Instructions for Continued Airworthiness B767A-ICA-A Rev 0dated 22.10.2013or later r...	Before flight, entry and access doors must comply with the prerequisiteslisted in the AFM supplement B767A-AFM-A.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willa...	23/01/2014	Active	10047829
10047850	AIRGLAS, Inc.		FAA STC SR02422AK	R44, R44II	Fabrication and installation of composite floorboard scuff plates.Fabrication and installation of Airglas, Inc. LF2600-R44 compositefloorboard scuff plates in place of original carpet floor covering.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Descriptive Data List LF-2600-R44, revision (-) dated July 10, 2013Airglas, Inc. Installation, Maintenance, and Instructions for ContinuedAirworthiness, document number LF2600-R44-105, revision (-), dated July8, 2013or later revisions of the above listed documents approved by EASA inaccordance witht...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/01/2014	Active	10047850
10047881	EUROCOPTER CANADA Ltd.		TCCA STC SH97-33 ISSUE 3	2. AS 355 E/F/F1/F2/N/NP 1. AS350 B/D/B1/B2/BA	Rear Cargo Door Hinge and Latch Modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Eurocopter Canada Ltd Master Drawing List MDL-98-008 Issue CEurocopter Canada Ltd Instructions for Continued AirworthinessICA-ECL-207, rev. 2or later revisions of the above listeddocuments accepted by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/01/2014	Active	10047881
10047885	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 441	Installation of KHF-1050 System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Amdt. 23-20: 23.1301Amdt. 23-21: 23.1501(b) Amdt. 23-23: 23.603, 23.605Amdt. 23.26: 23.1529Amdt. 23-43: 23.57 (a),(c)Amdt. 23-45: 23.305, 23.613, 23.773Amdt. 23-48: 23.301,A...	-AFMS Report 2013-9-8, Rev. A, dated 25. November 2013or later revisions of the above listed documents approved by EASA-Master Document List, Report 2013-9-16, Rev. IR, dated 23. January 2014-Maintenance Manual Supplement, Report 2013-9-10, Rev. IR, dated 2. May2013-Installation Procedure, Report 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	27/01/2014	Active	10047885

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047886	MID-CANADA MOD CENTER	REV. 1	TCCA SA12-39	ATR 72-202 ATR 42-300, ATR 42-320	Dual UNS-1Lw FMS InstallationThe purpose of this modification is to install a dual Universal AvionicsSystems Corporation (UASC) UNS-1Lw Navigation Management System on ATRaircraft, previously equipped with Rockwell Collins or Honeywell radionavigation suite.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List, Avionics Design Services Ltd. MDL12008, RevisionB, Issue 1, Transport Canada approved May 22, 2014FOR ATR 42:- Flight Manual Supplement, Avionics Design Services Ltd. FMS12008-1,Revision A, Transport Canada approved May 15, 2014- Instructions for Continuous Airworthiness, Avio...	Compliance with Airworthiness Limitations, Avionics Design Services Ltd.AWL12008-1 (for ATR 42) or AWL12008-2 (for ATR 72), Revision N/ C ,Transport Canada approved April 26, 2012 (or later EASA approvedrevision i.a.w. TCCA bilateral agreement), is mandatory.Prior to installation of this design chang...	30/09/2016	Active	10047886
10047894 (CMS)	PRECISE FLIGHT, Inc.		FAA STC ST00453SE	B737-800/ -900/-900ER B737-400/-500/-600/-700 B737-100/-200/-200C/-300	Installation of Pulselight landing light flashing unit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness 152PMAN0018 Rev C dated May 22,2012(see attached table)or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisdecision) and/ or the Technical Implementation Procedures of...	as per AFMS:NIGHT OPERATION LIMITATIONSTurn Pulselite System Off at 500ft AGL or at Pilots Discretion DuringLanding Approach.(If TCAS/TCAD Option is installed: Also Turn Pulselite/Strobe Lightswitch out of the STROBE & STDY/ ACTIVE position.)Prior to installation of this design change it must be dete...	28/01/2014	Active	10047894
10047909	ALPINE AEROTECH LP		TCCA STC SH01-32, ISSUE 1	212, 412, 412EP	Installation of Alpine Aerotech Ltd. Exhaust Duct Assembly	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List 191M-99-004-MDL, Rev. NI, dated 14 January 1999-Maintenance Manual Supplement 191M-99-004-MMS, Rev. NC, dated 11February 2000-Installation Instructions 191M-99-004-II, Rev. NC, dated 11 February2000or later revisions of the above listed documents approved by EASA inaccordance wi...	This approval is limited to Bell helicopter models 212, 412, and 412EP(the model 412CF being not currently EASA certified).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or re...	10/02/2014	Active	10047909
10047916	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	737-700	Introduction of Emergency Locator Transmitter	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Limited Master Document List S21.MDL-0957 Initial Issue,dated 17/05/2013STC Twenty One Limited Maintenance ManualS21.TEC-0326, Iss 1, dated 1/6/2011STC Twenty One Limited Master Drawing List 4492-23-000 Rev NC, dated19/04/2005or later revisions of the above listed documents approved b...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/01/2014	Active	10047916
10047926	DOA AESGLOBAL LIMITED	REV. 1		757-200	Activation of IMS Rave IFE systemRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AES Ltd Master Data List No. AES-757-2933 MDL Issue 5, dated 28thJanuary 2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2021	Active	10047926

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10047937	SABENA TECHNICS BGC	REV. 1		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-216/-231/-232/-233 A320-211/-212/-214/-215/-216 A320-111/-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of Provisions for Class 2 Electronic Flight BagsRev.1: Transfer from Tenencia Ltd. to Aeroconseil and A320-111 removedfrom applicability list.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification TEN 738, Airbus A320 Series, Installation of Provisions forClass 2 Electronic Flight Bags, Issue 1 dated 14 January 2014Flight Manual Supplement TEN/ Supplement 6 Issue 2 to the Airbus A318/A319/ A320/A321 Flight ManualEWIS ICA,TEN 738/26A Issue 1or later revisions of the above listed do...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/05/2022	Active	10047937
10047945	WIPAIRE Inc.		FAA STC NO. SA01185CH	B) U206G, TU206G A) 206H, T206H	Installation of Wipaire Model 3450 Amphibian/Seaplane Floats andHartzell Propeller Model HC-F3YR-1RF/ F8468A-2R (see under limitations).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	A) Flight Manuals:Models 206H and T206H: Pilot's Operating Handbook and FAA ApprovedAirplane Flight Manual Supplement, dated February 25, 2000;Models U206G and TU206G: Airplane Flight Manual/Pilot's OperatingHandbook Supplement, dated August 21, 2000;Models with Soloy Turbine Pac and Soloy Mark II T...	1.,,Installation of Wipaire Model 3450 Amphibian/Seaplane Floats andHartzell Propeller Model HC-F3YR-1RF/ F8468A-2R onlyfor Cessna 206H andT206H.2.,,For Models U206G (without STC SA1482GL installed): ,,a.,,AIRSPEED LIMITS: ,,Never Exceed (VNE) ,,,,,,158 KIAS ,,,,Maximum Structural Cruising (VNO) ,,,...	30/01/2014	Active	10047945
10047981	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03770AT-D	GV-SP	Installation of a 16-passenger cabin interior with one additional crewseat	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI D-50 Issue 1 Cabin Egress and Seat encroachment.The requirements for environmental protection and the associatedcertified noise and/ or em...	-FAA STC ST03770AT-D, dated 5th May 2010-Gulfstream Aerospace Corporation Index List GC520008684, Revision H,dated 5th May 2010-GV-SP Airplane Flight Manual Supplements GC52000M117 and GC52000M135,original release, dated 5th May 2010.-Instructions for Continued Airworthiness GC52801A600, original re...	This approval is limited to only the installation made in GulfstreamModel GV-SP Serial No. 5260It is the installer responsibility to ensure that all STCs fitted areEASA approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and...	03/02/2014	Active	10047981
10048007	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOFFICE OF AIRWORTHINESS	REV. 1	CAA UK RESPONSIBILITY	BOEING 757-200	B757-200 TCAS change 7.1 update	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 13:CS 25.581, CS 25.869, CS 25.899<(>,<)> CS 25.1301, CS 25.1309, CS25.1316<(>,<)> CS 25.1322,CS 25.1351, CS 25.1353<(>,<)> CS 25.1357, CS25.1431, CS 25.1...	Master Data List BA-757-34-0007-MDL Issue 01or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/02/2014	Active	10048007
10048008	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC SA4834NM	727 SERIES 727C SERIES 727-200 SERIES 727-200F SERIES 727-100C SERIES	Installation of Honeywell Traffic Alert and Collision Avoidance SystemTCAS II change 7.1 software.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Index of Master Data Lists 8900009 rev DAirplane Flight Manual Supplement TCAS-APPS-0294 rev. Cor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures ofU...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/02/2014	Active	10048008

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048020	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC02473LA	DHC-8-102/-103/-106	Installation of Cabin Interior Noise Reduction Kit	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.611 Amdt 5, CS 25.853 Amdt 12,CS 25.856 Amdt6 and CS 25, App H25 Amdt 14The requirements for environmental protection and the associatedcertified noise and/ or emis...	Installation must be in accordance with FAA approved Aerocon EngineeringCompany Master Drawing List AC25-NRDHC8-1000, Revision B.Maintenance must be in accordance with MaintenanceManual SupplementMMS-DHC8-1805, Revision B.or later revisions of the above listed documents approved by EASA inaccordanc...	None	06/02/2014	Active	10048020
10048022	FIELD AVIATION EAST, LTD.	REV. 1	TCCA SA13-64	DHC-8-301/-311/-314/-315 DHC-8-102/-103/-106/-201 /-202	Dual Universal RCU-4120, Radio Control Unit Retrofit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with TCCA approved FieldAviationCompany Inc. Master Drawing and Data List designated 25910000, Rev. IR.Flight operations must be conducted in accordance with FACI FlightManual Supplement designated FMS 25913000 Rev. IR.Instructions for Continuing AirworthinessMain...	The following equipment must be installed as a prerequisiteto theinstallation of the Universal RCU-4120 system:-Rockwell Collins communication and navigation radio.-A Field Aviation or Bombardier OEM installation of Dual UNS-1(x) FlightManagement System with operating software SCN 802/902(x) or lat...	12/02/2014	Active	10048022
10048031 (2004-5755 / LBA SA1390)	ROEDER PRAEZISION GMBH	REV. 4		SA227-DC, SA227-AT, SA227-TT SA-226-TC, SA227-AC, SA227-BC SA226-AT, SA226-T, SA226-T(B)	Installation of TCAS II System and Mode S Transponder with upgrade ofHoneywell CAS-67A to S/W – Change 7.1Rev 2; Transfer of STC.Rev 3: Combination of STC 10048031 with STC No. 2004-5755.Rev 4: Typo correction to STC 10048031 AFM supplement reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	EASA STC 2004-5755 - Installation of TCAS II System and Mode STransponder - Installed and maintained as per LBA STC No. SA 1390 Issue 1 - Operated as per AFM Supp. CAS 67 TCAS System and MST 67A Mode SSystem for Fairchild, Doc No. SA226/227-NY-1002-08, Rev 0, dated 21st May 2004.EASA STC7...	As listed in the AFM.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	01/03/2023	Active	10048031
10048034	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBIL ITY	A321-211 A320-211/-214 A319-111	ACSS TCAS change 7.1 update	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt 13 for the paragraphs affected by the changeThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	Master Data List BA-320-34-0007-MDL, Issue 00, dated 10/10/2013Compliance Check List BA-320-34-0007-CCL, Issue 00, dated 30/10/2013STC Definition & Certification Document BA-320-34-0007-STC, Issue 00,dated 10/10/2013or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/02/2014	Active	10048034
10048043	S-TEC CORPORATION		FAA SA09225AC-D	R172E, R172F, R172G, R172H 175, 175A, 175B, 175C	Installation of S-TEC System 20/30 Single and Two Axis Automatic FlightGuidance Systems, Model ST-685-20/30 (14 Volt System)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-FAA/DAS Approved Supplemental Flight Manual, P/N 891392, dated 23 May1997 for Cessna R172E, R172F, R172G, and R172H for S-TEC System 20;-FAA/DAS Approved Supplemental Flight Manual, P/N 891393, dated 23 May1997 for Cessna 175, 175A<(>,<) >175B, and 175C for S-TEC System 20;-FAA/DAS Approved Supplem...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/02/2014	Active	10048043

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048049	GFD GmbH	REV. 2		L31A &35A &36A 31A, 35A, 36A	IFF Mode 1 System Installation (STR700) Rev. 2: Transfer to GFD GmbH	The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noiseand/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Data List Doc. No. 5308-049 Rev.A of 30.01.2014Instructions for Cont. Airworthiness Doc. No.5308-085 Rev.IR of03.12.2013AFM Supplement Doc. No. 5308-071 Rev.IR of 04.12.2013or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to S/N: 31A-205 & 31A-207, 35A-139, -179, -268, -331, -387,36A-062, -063<(>,<) > 35A-222, 35A-607, 35A-612, 35A-643 and 35A-387.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification a...	23/08/2022	Active	10048049
10048064	GYRO-STABILIZED SYSTEMS, LLC	REV. 4	FAA STC SR02420AK	R44, R44 II	ZatzWorks R44M-001 Utility Camera Mount.The ZatzWorks R44M-001 Utility Camera Mount is a forward mount forattaching cameras to the R44/R44II helicopter.Revision 1: administrative revisionRevision 2: model R44 added, update of document referencesRevision 3: transfer of EASA STC 10048064 to differentR...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement (RFMS) Zatzworks document numberR44M-107, Revision 2, dated March 2016Instructions for Continued Airworthiness (ICA), Zatzworks documentnumber R44M-008, Revision 3, dated February 09<(>,<)> 2016Master Drawing List (MDL) Zatzworks document number R44M-110, Revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/10/2022	Active	10048064
10048066	NETJETS AVIATION, INC.	REV. 1	FAA STC SA01727WI	EMB-505	Interior Alteration for installation of a Keurig Coffee Maker andmodification of “No Smoking” signs in Embraer Model EMB-505 aircraft.The STC revision is due to the transfer of FAA STC SA01727WI to a newcertificate holder.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation in accordance with Duncan Aviation Inc, Masterdocumentlist No EDOC-0000015626, Rev A, dated 28 August 2013.Operation in accordance with Duncan Aviation Inc Airplane Flight ManualSupplement No EDOC-0000015627, Rev A, dated 28 August 2013.Maintain in accordance with Duncan Aviation Inc I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/06/2022	Active	10048066
10048068	VIH AEROSPACE Inc.		TCCA STC SH10-52	205A-1 HELICOPTER	Cargo Hook Retainer Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- VIH Aerospace Inc. Master Document Drawing list V205-110-MDL, Rev. 3- VIH Aerospace Inc. Instructions for Continued AirworthinessV205-110-MM, Rev. 2or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agr...	This approval is limited to Bell helicopter model 205A-1 (the models205A and 205B being not currently EASA certified).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repaira...	10/02/2014	Active	10048068
10048069	VIH AEROSPACE Inc.		TCCA STC SH10-52	BELL 212, 412, 412EP	Cargo Hook Retainer Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- VIH Aerospace Inc. Master Document Drawing list V205-110-MDL, Rev. 3- VIH Aerospace Inc. Instructions for Continued AirworthinessV205-110-MM, Rev. 2or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/02/2014	Active	10048069

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048070	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR02818NY	BELL 212	Bell Helicopter Vibration Monitoring System (BHVM) - The Bell HelicopterVibration Monitoring Kit (BHVM) is a system that allows to monitor theairframe, rotor and drive system vibration. The BHVM is designated toallow the operator to make vibration related track and balanceadjustment between operatio...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFMS AA-08033 Rev. 02 dated 08.12.2009ICA AA-08032 Rev. 5 dated 06.05.2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or theTechnical Implementation Procedures of EU/USA Bilateral Agre...	This system (BHVM) has to be installed in accordance with theAeronautical Accessories Installation Instructions AA-07161 Rev. F dated12 Apr. 2012; it is installed on a non-required/non-hazardous basis.Under no circumstance the BHVM system is to be used for eitherincreasing Bell Helicopter's publishe...	10/02/2014	Active	10048070
10048074	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	B757-200	Change of Wing Fuel Tank Pump Relays to GFI type on Boeing 757-200Boeing SB -757-28A0078 changes the Wing and Centre Tank Fuel Pump relaysto a GFI type. This STC is dedicated to aircraft that have already hadthe Centre Tank Relays changed to the UFI type (per FAA approved TDGAerospace STC ST01950LA)...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25.981 Amendment 1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remai...	Modification Summary, H4 Aerospace ref. MOD H4A1690 issue 5, dated 06February 2014Instructions for Continuous Airworthiness, H4 Aerospace ref. H4ADR798issue 1, dated 15 October 2013or later revisions of the above listed documents approved by EASA.	1-,,In order to constitute an AMOC to FAA AD 2012-06-06, this STC mustbe embodied on aircraft together with FAA approved TDG Aerospace STCreference ST01950LA. 2-,,Airworthiness Limitations: refer to CHAPTER 04 of Instructions forContinuous Airworthiness, ref: H4ADR798, Issue 1 dated 15 October 2013Pr...	10/02/2014	Active	10048074
10048090	JCB AERO SA			A330-200	B/C and Y/C Seat Covers Modification.Description - Summary :- Removal of existing B/C and Y/C Seat Covers- Installationof new B/C and Y/C Seat Covers- Installation of identification placard on the seats	The certification Basis of the original product remains applicable tothis certificate based on the TCDS EASA.A.004, which is JAR 25 Change13, and the requirement 25.853 is amendedto comply with JAR 25 Change14.The requirements for environmental protection and the associatedcertified noise and/ or e...	Project Data List A332-00825-01-PDL-01, rev CCertification Programme A332-00825-01-CP-01, issue DICA, A332-00825-01-ICA- 01, issue Aor later revisions of the above listed documents approved by EASA.	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of theproduct.	12/02/2014	Active	10048090
10048104	AEROTEC & CONCEPT			1900D	Approval of Beech 1900D for LPV Approach Capability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Aerotec Modification ref 13180 andMaster Data List ref AE13180MDL, Rev 1, dated 04/02/2014.Operation in accordance with Aerotec Flight Manual Supplement refAE13180AFMS, Rev 0, dated February 2014.or later revisions of the above listed documents approved by EASA.	EASA STC ref 10034237 must be installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	12/02/2014	Active	10048104
10048111	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	757-256	216Y/C, 757-200 passenger cabin reconfiguration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	H4 Aerospace Modification Summary and Declaration of Compliance No. MODH4A1634 Issue 2 dated 12 February 2014.or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2014	Active	10048111
10048125	AVIATION DEFENSE SERVICE			FAN JET FALCON	Carriage of PIRATE podsThe purpose of this Change is to clear the carriage of PIRATE pods onFalcon 20 in the following envelope :VMO: 350 kts, MMO = 0,78; FL390; n=+2/-1g	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.CS 25 Amdt 11 §25.149CS 25 Amt 10 §25.631FAR 25 up to Amdt 43 §25.1323, §25.1325, §25.1529The certificated noise and/ or emissions levels...	Change Approval Sheet doc. No. CAS-AVD-MDA20-95-FOG6A Issue02 dated12.02.2014Master Document List doc. No. MDL-AVD-FOG6A Issue 2 dated 12.02.2014Aircraft Flight Manual Supplementdoc. No. SAFM-AVD-FOG Rev. 01or later revisions of the above listed documents approved by EASA	Restricted to Falcon 20 S/N 076 aircraft.As per AFM Supplement N° SAFM-AVD-FOG Rev. 01Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect...	14/02/2014	Active	10048125

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048141	MOTORFLUG BADEN-BADEN GmbH			EC120 B	Installation of PFD Aspen EFD1000H Pro	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement 27101F135024-0601 rev. 1or later revisions of the above listed documents approved byEASA.Declaration of Compliance 27101F135024 dated 10/02/2014Instructions for Continued Airworthiness 27101F135024-0701 rev. 0Installation Manual 27101F135024-1001 rev. 0	Approved types of operation: DAY / NIGHT VFRPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/02/2014	Active	10048141
10048160	BAE SYSTEMS (OPERATIONS) LIMITEDBAE SYSTEMS REGIONAL AIRCRAFT	REV. 2	CAA UK RESPONSIBILITY	737-900 737-600, 737-700, 737-800 737-300, 737-400, 737-500 737-100, 737-200, 737-200C	STM80009J - Navigation - Upgrade from TCAS II Version 7.0 to 7.1 - TCASProcessor Replacement.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 13 : CS25.1301; CS 25.1302; CS 25.1309; CS 25.1322; CS 25.1333; CS 25.1431; CS25.1459; CS 25.1529; CS 25.1...	BAE Systems Major Change Dossier: AWR/754/ B737 Issue 2 dated 01 November2018<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/11/2018	Active	10048160
10048168	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	A320-200	L and RH Closets in A320-200 for Etihad / Serbia	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AIM Aviation (Henshalls) Ltd Modification No. HEN 1278 Issue 1or later revisions of the above listed documents approvedby EASA.	Air Berlin Modification No. A320-E025-2-01-2014 is a pre-requisite.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthin...	18/02/2014	Active	10048168
10048181	BAE SYSTEMS (OPERATIONS) LIMITED		CAA UK RESPONSIBILITY	757-200, 757-200PF, 757-300	STM80010J - Navigation - Upgrade from TCAS II v7.0 to v7.1 - TCASProcessor Replacement	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 Amendment 13: CS25.1301; CS 25.1302; CS 25.1309; CS 25.1322; CS 25.1333; CS 25.1431; CS25.1459; CS 25.1529; CS 25.15...	BAE Systems Major Change DossierAWR/755/ B757 Issue 1or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/02/2014	Active	10048181
10048187	RUAG AG	REV. 2		DHC-6 SERIES 300 DHC-6-300 DHC-6-200 DHC-6-100	EASA STC 10048187 (G600 & SAM) upgrade to FHC-6-100 & -200The following equipment / functions are removed when installed:-Pilot HSI-Pilot and co-pilot ADI-Pilot and co-pilot RMI-Pilot and co-pilot altimeter-Pilot and co-pilot airspeed indicator-Pilot and co-pilot vertical speed indicator-One Vertica...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 23 Amdt 3 for thechangeThe requirements for environmental protection and the associatedcertified noise and/ or emission...	-Master Document List MDL-8001144 Rev B of 08.04.2014-Instructions for Continued Airworthiness ICA-8001152 Rev B of04.04.2014-Flight Manual Supplement G600 FMS-608582 Rev B of 03.04.2014-Flight Manual Supplement GNS-430W FMS-608770 Rev A of 13.02.2014 orequivalentor later revisions of the above list...	Effectivity: all S/N with 30 min main battery capacity afterinstallation of this STC for safe flight and landing in accordance toCS23-1353(h) The following equipment shall be installed on the aircraft prior theinstallation of the G600-GNS430W No.1 and No.2 or other approved and compatible units list...	29/01/2021	Active	10048187
10048203	FIELD AVIATION COMPANY Inc.		TCCA C-LSA13-185/D	DHC-8-402	Cabin Reconfiguration(from OEM 76 passenger configuration to standard OEM 78 passengerconfiguration)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with TCCA approved FieldAviationCompany Inc. (FACi) Master Data List designated 25830000, Rev. IR andTCCA accepted FACi Modification Instruction 25831000 Revision IR.Instructions for Continuing AirworthinessMaintenance must be in accordance with Bombardier DHC-8-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/02/2014	Active	10048203

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048207	URBE AERO GmbH	REV. 1		DA42, DA42 M	SBAS / The Garmin G1000 integrated flight deck is upgraded with SBAScapable equipment and the related operational capabilities are enabled.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The change shall be accomplished in accordance with the initial revisionof DOE/F07 (Engineering Order) and subsequent documents< (>,<)>The aircraft shall be operated in accordance with initial revision ofAFM-016-01, andThe aircraft shall bemaintained in accordance with initial revision ofAMM-016-01o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	24/02/2014	Active	10048207
10048214	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	767-300	Installation of Cabin LED Lighting System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	BAC Ltd Master Data List No. BAC-898MDL05 Issue 3 dated 19 February2014.or later revisions of the above listed documents approved by EASA	None	20/02/2014	Active	10048214
10048216	S4A SOLUTIONS FOR AVIATION, S.L.			BD100-1A10	Side Facing Divan in Challenger 300 aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-01 Installation of Side Facing Seats	Service Bulletin CL304-SB001 Ed./Iss.2Master Drawing List CL304-RPT02 Ed./Iss. 2or later revisions of the above listed documents approved by EASA.	FOR TAKEOFF AND LANDING, ONLY TWO(2) PEOPLE,SEATED AT BOTH DIVAN ENDS,ARE ALLOWED.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon...	20/02/2014	Active	10048216
10048217	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV. 1	CAA UK RESPONSIBILITY	767-300	Installation of 226 Passenger LOPA	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	BAC Ltd Master Data List No. BAC-898MDL01 Issue 5 dated 19 February 2014or later revisions of the above listed documents approved by EASA.	EASA STC No. EASA.A.S. 01333 is a pre-requisite for this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of...	21/02/2014	Active	10048217
10048218	AIR AMBULANCE TECHNOLOGY GmbH	REV. 1		LEARJET 45	LJ45 Special Equipment / Baggage Configuration LJ45Additional FCBs to EASA STC 10048218	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-01, Cargo Fire Containmentin an occupiedPassenger Cabin.The requirements for environmental protection and the associatedcertified noise and/ or em...	Air Ambulance Technology "Master Data List", ref. MDL-LJ45-45.000-60XRev. 3, dated 14 August 2014Air Ambulance Technology "Airplane Flight Manual Supplement", ref. AFMAAT 61 Rev. 2, dated February 2014Air Ambulance Technology "Content limitation list", ref.CLL-LJ45-25-20-45.000-60x Rev. 3, dated May...	1) Transportation of cargo in the passenger cabin in accordance withthis STC is only allowed for operations with humanitarian nature (ase.g. Disaster Relief Situations).2) The instructions and limitations defined in the following documentsmust be applied when transporting cargo in the passenger cabi...	05/09/2014	Active	10048218
10048228	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	737-700	Passenger Seating Layout 50 (44 B/C + 6 Y/C) PAXChange froma 149 PAX Layout to a 50 PAX Layout	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	J<(>&<)>C Engineering Services Ltd Modification No. JC/MOD/M3800 Issue1.0 dated 8th January 2014.or later revisions of the above listed documents approved by EASA	None	21/02/2014	Active	10048228

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048231	GARMIN INTERNATIONAL, Inc.	REV. 1	FAA US ST01812WI	ATR 72-211/-212/-212A ATR 72-101/-102/-201/-202 ATR 42-200/-300/-320	ATR - Installation of a dual Garmin GTN-725 GPS Navigator System forEuropean P-RNAV ComplianceThe purpose of this modification is to install a dual Garmin GTN-725 GPSnavigator system with 2 Garmin GA-36 WAAS!GPS antennas, as a replacementto the existing Honeywell GPS systems (KLN900 or KLN9OB). Thei...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt 4 for the following requirements:25.771, 25.773, 25.777, 25.1301, 25.1302, 25.1309, 25.1322, 25.1381,25.1523, 25....	,,1.,,Master Document List STC Twenty One ref. S21 .MDL-1124 issue 1,dated 21 February 2014 or later revision approved by EASA<(>,<) >2.,,Aeroplane Flight Manual (AFM) supplement for ATR 42 STC Twenty Oneref. S21.FMS-0099 issue 2, dated June 2015< (>,<)>3.,,Aeroplane Flight Manual (AFM) supplement for...	1- This approval is limited to the aircraft complying with prerequisiteaircraft configuration defined in Garmin International document “ATR42/72 Pre Modification Configuration & KLN 900 & KLN 90B GPS SystemRemoval, Dual GTN 725 Installation” ref. 005-00761-00 revision 2 datedFebruary 2014, or laterE...	02/03/2016	Active	10048231
10048232	2 EXCEL DESIGN LIMITED	REV. 1	CAA UK RESPONSIBILITY	PA-31	Introduction of modified winglets.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation in accordance with STC21 Modification S21.57-90-1001,S21.MDL-1010, issue 1, dated February 21, 2014.- Operation in accordance with Flight Manual Supplement S21.FMS-0107Issue 1, dated February 21, 2014.- Instructions for Continued Airworthiness as defined in S21.TEC-0360,Issue 1, dated...	As per Aeroplane Flight Manual Supplement S21.FMS-0107Design change S21.57-90-1002 must be installed prior to incorporation ofthis design change.The operation of the wingtip strobe lights in aircraft fitted only withwingtip strobe light needs further approval.Installation of role equipment onto thea...	25/08/2017	Active	10048232
10048260	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03693AT-D	G150	Installation of Safe Flight Autopower Automatic Throttle Control Systemin accordance with Gulfstream Aerospace Corporation Index listCEC14348000 Revision K dated September 02, 2013, or later FAA approvedrevision.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.1329 a)b)c)d) g)h)k)m) at Amdt 4The requirements for environmental protection and the associatedcertifiednoise and/ or emissions levels of the original product areun...	Operation must be in accordance with FAA approved Flight ManualSupplement , CEC1434M000, Revision B, dated March 26, 2013Installation must be in accordance with Gulfstream Aerospace CorporationIndex list CEC14348000 Revision K dated September 02, 2013Maintenance must be in accordance with Instructio...	-CATII operations with the ATS engaged are prohibited- SteepApproach Operations are prohibited below 400ft AGL (or publishedMinima, whichever is higher) with ATS engagedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any othe...	25/02/2014	Active	10048260
10048265	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	B737-300	Carriage of Horses or Other Animals	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:•,,CRI D-01 Fire protection of essential systems/ equipment within classE cargo compartments•,,CRI D-02 Installation of seats on B737- 300 converted freighter.The requireme...	STC Twenty One Limited Flight Manual Supplement S21.FMS-0102 Issue 2or later revisions of the above listed documents approved by EASA.STC Twenty One Limted Master Document List No. S21.MDL-1133 Issue 2	The Following EASA STCs must have been previously embodied or embodiedconcurrently with this design change:•,,EASA STC 10015542 Rev 4 [Freight Conversion]<(>,<)>•,,EASA STC 10015780 [Installation of Smoke Detection and FireSuppression System]<(>,<) >•,,EASA STC 10043157 [Ancra Cargo Loading System].T...	25/04/2016	Active	10048265
10048272	ASI INNOVATION			SA365 N	EHSI and GPS installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement ASI-AFM-0114-06 (date February 2014or later revisions of the above listed documentsapproved by EASA	- The use of GPS for instrument approaches is not authorized- A Minimum Equipment List must be established for B-RNAV and P-RNAVoperationPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design cha...	26/02/2014	Active	10048272

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048286	PMV ENGINEERING	REV. 3		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of a Dual Advisory Ice Detection System on Airbus A320Rev initial: System installationRev 1: System activationRev 2: Update of the applicabilityRev 3: Update of the MMEL	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List AVI-00350-MDL-R05 dated 8 June 2018Aircraft Flight Manual Supplement AVI-00350-AFMS-R01 dated 8 June 2018Instructions for Continued Airworthiness AVI-00350-CA-RO3 dated 13 March2014Master Minimum Equipment list AVI-00350-MMELS-S01-R00 dated 25 Feb. 2020Master Documentor later rev...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/04/2020	Active	10048286
10048299	B/E AEROSPACE, Inc. - FSI		FAA STC ST00736SE	727-100/-200	Installation of New Flight Crew Oxygen Masks and holders.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25 at first issue for the affected area, excepted for:- 25.1439 at JAR25 change 4 and- 25.1447 at JAR25 change 5The requirements for environmental protection and the...	Master Drawing List 99FS906-D01 rev. FStructural Drawing List 99FS906-D02 rev AElectrical Drawing List 99FS906-D03 rev IRSystems Drawing List 99FS906-D04 rev Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofth...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2014	Active	10048299
10048311	B/E AEROSPACE LIMITED	REV. 2	TCCA SA11-26, ISSUE 3	DHC-8-402	Upgrade Tail Navigation Light System.This Rev. 2 was issueddue to the company's name change from "ACS-NAILtd." to "B/EAerospace Ltd.".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Installation must be in accordance with TCCA approved ACS-NAI Ltd. Modification Data Summary designated G 855001, Revision A.Instructions for Continued AirworthinessMaintenance must be in accordance with TCCA accepted Instructions for Continued Airworthiness designated G 855072, Revision B and Illu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/03/2017	Active	10048311
10048316	URBE AERO GmbH	REV. 1		DA40D	SBAS / The Garmin G1000 integrated flight deck is upgraded with SBAScapable equipment and the related operational capabilities are enabled.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The change shall be accomplished in accordance with the initial revisionof Doc. DOE/07 Project No.: 018 and subsequent documentsThe aircraft shall be operated in accordance with initial revision ofAFM-018-01, andThe aircraft shall be maintained in accordance with initial revision ofAMM-018-01or late...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	28/02/2014	Active	10048316
10048330	RUAG AG	REV. 4		PC-12, PC-12/45, PC-12/47 PC-12, PC-12/45 PC-12/47, PC-12/47E PC-12/47E	Provisions to Aerial Survey Camera Inst.Initial STC: EASA Project No. 0010018586, MOD 12-231-mt, RUAG SF-EG0684;Provisions for Aerial Survey Camera installation on the PC-12, PC-12/45and PC-12/47.Altered with Major Change: EASA Project No. 0010041619, MOD 16-018-met,RUAG SF-EG0684/C; Correction of I...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Flight Manual Supplement PC-12/47E: Doc. No. FMS-611702, Rev. A;-Flight Manual Supplement PC-12, PC-12/45 and PC-12/47: Doc. No.FMS-608549, Rev. C;-Instructions for Continuous Airworthiness PC-12/47E Doc. No.ICA-8004361 Rev E.-Instructions for Continuous Airworthiness PC-12, PC-12/45, PC-12/47Doc.-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/01/2021	Active	10048330

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048337	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	DC.8-72	Introduction of Swift Broadband/ Installation of Satcom System, includingwireless network for occupants for use of portable electronic devicesand internet access during flight.ThisRev. 1 was issued to correct a typing error.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): SC/CRI H-01 EWIS-ICA- the following paragraph(s) at a later amendment: See Cert. ProgrammeDoc. No. S21-PROG-0869 Issue 3The requirements for enviro...	Master Document List Doc. No. S21.MDL-0869<(>,<)> Supplement Manual Doc.No. S21.TEC-0321, Flight Manual Supplement S21.FMS-0085, ComplianceRecord S21.COMP-0869, Electrical Load Analysis S21.ELA-0132, Mass &Balance Report S21.TREP-0589or later revisions of the above listed documents approved by EASA....	See Flight Manual Supplement S21.FMS-0085 and Compliance RecordS21.COMP-0869Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the a...	05/03/2014	Active	10048337
10048344	TELEDYNE UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	757-200, 757-200PF, 757-300	Installation of Enhanced Airborne Data LoaderRev. 1: Transfer from Teledyne Limited to Teledyne UK Limited.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:Note the EASA certification basis for the 757-300 is JAR 25 Change 14but it has also been applied on 757-200 and 757-200P...	Master Data List - MOD-MDL-031 Issue 01<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/11/2020	Active	10048344
10048345	ANCRA INTERNATIONAL LLC		FAA STC SA4553NM	727-200	Installation of a mechanical cargo loading system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Controlled Drawing List DL 81020, Revision "A", dated September 8, 1988Component Maintenance Manual Part Number 81020 rev 1 dated Jan 01st,1991Instructions for Continued Airworthiness ref. 10073 rev A dated January27th, 2014or later revisions of the above listed documents approved by EASA inaccordan...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	05/03/2014	Active	10048345
10048356	DART AEROSPACE USA, Inc.	REV. 1	FAA SR02233SE	412, 412EP 205A-1, 212	Installation of “LH Pilot in Command KIT” in accordance with dataprovided in Master Document List MDL-D212-803 Rev E as applicable toeach helicopter model.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement FMS-D212-803 Rev C, 23rd January2015or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreem...	EASA STC is issued just for the helicopter Types/Models currentlyapproved by EASA: 205 A-1, 212, 412, 412EP.Required items identified as pre-requisites for this STC are listed inSection 0 of FMS-D212-803 Rev C.Prior to installation of thisdesign change it must be determined thatthe interrelationshi...	26/05/2016	Active	10048356
10048363	BRISTOW HELICOPTERS Ltd.		CAA UK RESPONSIBILITY	AS 332 L/L1	Installation of a Co-Pilot alternative altimeter in accordance with Bristow Modification Document MOD/332/3976, issue 6.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Bristow Modification Document MOD/332/3976, issue 6- Bristow Certification Plan BHL/ 332.7190 Issue a- Bristow Instructions for Continued Airworthiness BHL/ 332.7191 Issue a	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/03/2014	Active	10048363
10048364	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		650 CITATION VII	Honeywell FMZ-2000 Flight Management System.P-RNAV approval for existing Honeywell FMZ-2000This REV. 1 was issued to correct a mistake in the name and address ofthe STC holder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Scandinavian Avionics AFM Supplement, 2080453-AM, issue 2, dated 27August 2013Scandinavian Avionics Installation Documents, 2080453 STC, issue 1,dated 13 February 2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/03/2014	Active	10048364

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048380	AVINCIS AVIATION ITALIA S.P.A	REV. 2		CESSNA 550 550	IRIDIUM SATCOM & TRACKER SYSTEM INSTALLATIONRev. 1 is an administrative re-issuance to reflect the recent namechange from INAER Aviation Italia S.p.A. Divisione Ala Fissa to BabcockMission Critical Services Italia S.p.A Divisione Ala Fissa.Rev. 2: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Inaer Aircraft Flight Manual Supplement, FMS-23-00-1108-A, rev 01, dated05 June 2012.Inaer Instruction for Continued Airworthiness, ICA-23-001108-A, rev 01,dated 20 June 2012.Inaer Master Drawing List, MDL-23-00-1108-A, rev 00, dated 20 February2014or later revisions of the above listed documents ap...	Inspection of the fuselage skin at the antenna location, asinstructedin the ALS of the ICA-23-00-1108-A rev. 01.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introdu...	22/02/2024	Active	10048380
10048381	DELTA ENGINEERING CORPORATION		FAA STC ST03170NY	DHC-8-400 SERIES	Installation of navAero Universal Aircraft Interface Device(UAID) andDisplay Mounts	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering, Airplane Flight Manual, document No. 0688-08449-2338,original Release, dated 10 September 2013.DeltaEngineering, Master Data List, document No. 0188-08446-2338,revision A, dated 10 September 2013.Delta Engineering, Instructions for Continued Airworthiness AndElectrical Wiring Int...	This STC is for provisions of Electronic Flight Bags and operational ofthe carry-on electronic flight bag (portable electronic device)including its battery is not approved by thisSTC.This STC only includes approval for the Universal Aircraft InterfaceDevice (UAID) for read only with existing aircra...	06/03/2014	Active	10048381
10048383	MICRO AERODYNAMICS, INC.	REV. 1	FAA STC SA00803SE	F33A, F33C, G33 B36TC, G36, 36, A36, A36TC 35-C33A, E33, E33A, E33C, F33 35-33, 35-C33, 35-A33, 35-B33	Installation of vortex generators on the wings and tail surfaces.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Micro AeroDynamics Drawing PackageMA2134, Revision A, dated October 28, 2008, and Installation ManualMA2135, Revision A, dated October 28, 2008, (35-33, 35-A33, 35-B33,35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C<(>,<)>G33, 36, A36,G36, A36TC) or Installation Man...	If more than five vortex generators are damaged or missing,the aircraftis not airworthy.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effe...	10/03/2014	Active	10048383
10048385	MEGGITT SAFETY SYSTEMS, Inc.		FAA STC ST02278LA	777-200	Project Specific Certification Plan for B777 Cargo Fire ExtinguishersB777 Cargo Fire Extinguishers	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List 51751952, Rev. B dtd. 12.January 2010Instructions for Continued Airworthiness 51751832, Rev. C dtd. 13.February 2009or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Te...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	07/03/2014	Active	10048385
10048388	APTOZ EHF.	REV. 1		757-200	Lights - Passenger Compartments - LED Lighting System UpgradeRev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Change/Repair Approval, Icelandair document No. CRA-757-3320-02,Revision A, dated 5 February 2014-Continued Airworthiness Instructions, Icelandair document No.CAI-757-3320-02, Revision A, dated 5 March 2014.or later revisions of the abovelisted document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The installation of this modification by third personsw...	27/05/2025	Active	10048388

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048391	MICRO AERODYNAMICS, INC.		FAA STC SA00849SE	PA-28S-160/-180 PA-28R-180/-200 PA-28-140/-150/-160/-180/ -235	Installation of vortex generators on the wings and tail surfaces	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Drawing Package MA2150, Revision IR,dated August 28, 2000, and Installation Manual MA2151, Revision IR,dated October 2, 2000;Instructions for Continued Airworthiness, stated on Placard MA8001or later revisions of the above listed documents approved by EASA inaccordan...	If more than five vortex generators are damaged or missing,the aircraftis not airworthy.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effe...	07/03/2014	Active	10048391
10048395	DASSAULT AIRCRAFT SERVICES (DAS)	REV. 4	FAA ST11047SC	FALCON 2000, 2000EX	Installation of upgraded hardware to replace Rockwell Collins Proline 4displays with Rockwell Collins Pro Line 21 displays, add an IntegratedFlight Information System (IFIS) and enable localizer performance withvertical guidance (LPV) capability.Rev. 4: Transfer from BHE & Associated, Ltd. to Dassau...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval, except where amended by additional orlater amendments if indicated on FAA STC.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product...	- Master Drawing List 365-00-0001 rev. C dated 01 April 2011, or laterapproved FAA revision.- “Airplane Flight Manual Supplement”, document No. 365-00-0056, Rev.IR, dated 03 May 2011, for FMS-6100 version 4.1 or document365-00-0086, Rev. IR, dated 12 December 2017 for FMS-6100 version 4.2,or latero...	For aircraft with no flight data recorder (FDR), or FDR with les than 42parameters, software version 8.0 or later is required.For aircraft with FDR with 42 parameters to 88 parameters, softwareversion 10.4 or later is required.The installation requires the installation of EASA STC 10064001 and/orEAS...	19/03/2020	Active	10048395
10048396	HARTZELL PROPELLER LLC		FAA STC SA3291CH	TBM700A, B, C1, C2, N	Installation of Harzell 5-blade composite propeller HC-E5N-3C/NC8834K	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 23.907, Amdt. 23-59This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels....	Installation Instruction INST_032513, FAA approved February11, 2014Airplane Flight Manual Supplement AFMS_032513, FAA approved February 11,2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) an...	Propeller limits:Diameter: 91 inches, no reduction permitted;Pitch setting at 30 inch radius: Low: 19.5 +/- 0.1 degreesFeather: 85.0 +/- 0.5 degreesReverse: -9.0 +/- 0.5 degreesPrior to installation of this design change it must be determined thatthe interrelationship between this design change andp...	07/03/2014	Active	10048396
10048398	P3 ENGINEERING GMBH			BD100-1A10 CHALLENGER 300	Aircell SwiftBroadband Satcom installation and WiFi NetworkactivationThe change consists in the installation of a Satcom System withSwiftBroadband capability.The Satcom antenna is installed below the fin cover on the verticalstabilizer. In addition, a new cabin network is installed withactivation o...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): SC F-02 'Security Protectionof aircraft systemsand network' issue 2 dated 4/03/2014The requirements for environmental protection and the associatedc...	- Master Document List P3V-100024-MDL-0001-B dated 7/03/2014- Aircraft Flight Manual supplement 23-13-00 referenceP3V-100024-FMS-0001-A dated 13/11/2013- Instructions for Continued Airworthiness ATA 23-13 referenceP3V-100024-ICA-0001-A dated 19/12/2013or later revisions of the above listed documents...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	07/03/2014	Active	10048398
10048406	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			550 BRAVO	P-RNAV Capability within GNS-XLS Single or Dual FMSP-RNAV approval of GNS-XLS FMS, including RNP10, RNP4, RNP1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cessna Düsseldorf Airplane Flight Manual Supplement, 2013-18-8, rev IR,dated 29 October 2013.Cessna Düsseldorf Installation Procedure, 2013-18-1, rev IR, dated 29October 2013.or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/03/2014	Active	10048406

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048423	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 1	FAA STC SA757GL	3. B200T, B200GT, B200CGT. 3. B200T, B200GT, B200CGT. 2. B200, B200C, B200CT, 2. B200, B200C, B200CT 1. 200, 200C, 200CT, 200T	Replacement of Main Wheels & Brakes and/or Nose Wheel.Rev. 1: Transfer from "Parker Hannifin Corporation" to"Kaman Aviation, Aircraft Wheel and Brake, LLC".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of Main Wheel and Brakes in accordance with Parker HannifinConversion kit 199-125 Rev R, dated September 07, 2010, per InstallationManual, Rev L, dated January 21, 2010, and Installation Drawing 50-90,Rev K, dated January 21, 2010, and/or:- Installation of Nose Wheel in accordance with P...	These modifications are approved for individual or joint installation onspecified models that are equipped with landinggear that support 10inch High Floatation equipment.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any ot...	27/07/2023	Active	10048423
10048424	AVIONICS SUPPORT GROUP, Inc.		FAA ST03081AT	737-600/-700/-800 737-300/-400/-500	Installation of an emergency Locator Transmitter (ELT) system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 24694-MDL Rev B dated 04/04/2007Flight Manual Supplement 24694-AFMS initial issueor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/03/2014	Active	10048424
10048429	ANCRA INTERNATIONAL LLC		FAA STC ST02408LA	B737-400	Installation of a main deck cargo loading system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Controlled Data List DL86190 Rev C Dated Nov. 03rd, 2011Instruction for Continued Airworthiness report 9592 Rev A datedJune25th, 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or theU...	PEMCO World Air Services' EASA STC 10016198 (formerly IM.A.S.02438 rev2) shall be installed in conjunction with the change certified throughthe present STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously i...	10/03/2014	Active	10048429
10048469	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA SA03241CH	525, 525A, 525B, 525C	Air Ambulance ConversionAir Ambulance Conversion - Textron 525	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to Spectrum Aeromed Master Document List No. 6049DL, or laterRevisionsTo be operated in accordance with AFM-SDocument No. 6049FMSTo be maintained i.a.w. ICA Document No. 6049MMor later revisions of the above listed documents approved by EASA.	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/04/2019	Active	10048469
10048472	BRISTOW U.S. L.L.C.		FAA SR09589RC	S-92A	Installation of a TDR-94D Transponder with ADS-B NRA	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement RFMS-S92A-2013-001 Rev IRor later revisions of the above listed documents approved by EASA.Master Document List S92TXP-MDL-0 Rev. EMaster Installation List S92TXP-MIL-0 Rev. EInstallation Manual S92-00-1000 Rev AInstructions for Continued Airworthiness ICA-S92-2010-01 Rev. B...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2014	Active	10048472

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048481	AEROSPACE DESIGN FACILITIES Ltd.		CAA UK RESPONSIBILITY	AS 355 F, F1, F2, N, NP	Installation of Spectrolab SX7 Searchlight as defined by ADF2013-MDL-100	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27 Amdt. 3:27.1 (a-c), 27.601 (a-b), 27.603 (a-c), 27.605 (a-b), 27.607 (a-b),27.609 (a-b), 27.610 (a-d), 27.611 (a-c), 27.613 (a-e)<(>,<)> 27.625(a-d), 27.629, 27.771(...	AS355 Flight Manual Supplement No. 12 "SPECTROLAB SX7 STARSUNSEARCHLIGHT INSTALLATION", Rev. 0or later revisions of theabove listed documents approved by EASACompliance Report ADF-CR2013-100 Issue 1AMaster Document List ADF2013-MDL-100 Issue 1AInstructions for Continued Airworthiness ADF-ICA2013-10...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	13/03/2014	Active	10048481
10048483	ASI INNOVATION			ERJ 190-100 LR	ERJ 190-100 LR MSN 130 New Cabin Configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Certificate Data List ref. ASI-SDL-0148-06, dated13/03/2014.Master Drawing List ref. ASI-MDL-0148-12,dated 13/03/2014.or later revisions of the above listed documents approved by EASA	Applicability limited to ERJ 190-100 LR MSN 130Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.T...	14/03/2014	Active	10048483
10048504	TRACES AIRCRAFT CERTIFICATIONENGINEERING SERVICES		FAA ST03298CH	737-800	Installation of a 145/165 passengers seating arrangement.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List TS1115MDL Rev A dated January 07th, 2014Instructions for Continued Airworthiness TS1115R07 Rev IR dated Aug30th, 2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/03/2014	Active	10048504
10048509	DASSAULT FALCON SERVICE			FALCON 7X	LH Galley Bulkhead installation and aircraft curtains modification.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DFS Change Approval Sheet doc. DFS7022-CAS Issue A dated 13March 2014DFS Modification Sheet doc. DFS7022 Issue A dated13 March 2014or later revisions of the above listed documents approved by EASA.	S/N 108Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/03/2014	Active	10048509
10048519	UMLAUT ENGINEERING GMBH	REV. 3		BD-700-1A10, BD-700-1A11	Honeywell Satcom SBB Upgrade and WiFi Network activation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 4:25.601; 25.1301; 25.1309; 25.1353; 25.1431;25.1529; 25.1581.The requirements for environmental protecti...	Umlaut Engineering GmbH Master Document List No. P3-AAO02-MDL-0001 IssueA dated 29/10/18 or later revisions of the above listed documentsapproved by EASA.	Refer to MDL for aircraft affectivity.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/04/2020	Active	10048519
10048520 (EASA.R.S.01502)	BRISTOW HELICOPTERS Ltd.		CAA UK RESPONSIBILITY	S-76C	Activation of ADS-B Function using Mode S Extended Squitter	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 Amendment 3:CS 29.1301; CS 29.1309; CS 29.1431; CS 29.1529; CS 29.1581The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	Bristow Helicopters Limited Sikorsky S76 Flight Manual Supplement No. 24Initial Issueor later revisions of the above listed document approved by EASAModification MOD/ S76/34.5721 Issue 3	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	18/03/2014	Active	10048520

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048525	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04293AT-D	GV-SP	Installation of an Airplane Completion.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI D-50 Issue 1 Cabin Egress and Seatencroachment.The requirements for environmental protection and the associatedcertified noise and/ or em...	-,,FAA STC ST04293AT-D, issued 4th March 2014-,,FAA Statement of Compliance, ref. 100G-14-093, dated 12th March 2014-,,Gulfstream Aerospace Corporation Index List GDL100000006, Rev -,dated 4th March 2014-,,EASA Validated Configuration List, ref. GCD000001155, Rev.-, dated5th March 2014-,,GV-SP Airpl...	It is the installer responsibility to ensure that all STCs fitted areEASA approved.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upo...	18/03/2014	Active	10048525
10048528	IKHANA GROUP, LLC	REV. 1	FAA STC SA02457LA	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Install and maintain DHC-6 Re-Life Flight Controls in accordance withFAA STC SA02457LA.RWMI DHC-6 Re-Life Flight Controls are approved replacements for VikingAir Limited (formerlyBombardier Inc. or De Havilland Inc.) flightcontrols as listed in Annex 1.Rev. 1: Name Change from "Ikhana Group Inc." t...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The certification basis for parts changed or affected by the changesince the reference date of the application, November 9, 2007, is basedupon FAR Part 23 as amended by Am...	Master Data List, Document No. ER218-1076 Revision A, datedApril 29,2013 Drawing List, Document No. ER 218-1077 Revision B, dated March 25,2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) an...	1. Approval of this modification applies to the above notedmodelairplane series only. This approval should not be extended to otherspecific airplanes of this model series on which other approvedmodifications are incorporated, unless it isdetermined that theinterrelationship between this change and...	18/06/2021	Active	10048528
10048531	FEDERATION FRANCAISE DE VOL A VOILE			101	Malonnier sur planeur Pegase	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplément Manuel de Maintenance Pegase CAB01/2014Supplément Manuel de vol Pegase CAB01/2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/03/2014	Active	10048531
10048532	LUFTHANSA TECHNIK AG			A321-212 / -213 / -231 / -232 A321-111 / -112 / -131 / -211 A320-231 / -232 / -233 A320-214 / -215 / -216 A320-111 / -211 / -212 A319-115 / -131 / -132 / -133 A319-111 / -112 / -113 / -114	ACARS CMU software upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Declaration of Compliance ADC 3530, dated 13/03/2014- Supplemental Type Definition Document STDD23-14/20M, Issue 01 Rev.00,dated 13/03/2014- Compliance Record List CRL23-14/20M,Issue 01 Rev.00, dated 13/03/2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/03/2014	Active	10048532
10048548	AIRLEC AIR ESPACE			500, 550, 560	Change of Weather Radar and indicator on Cessna 500, 550 and 560.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airlec Air Espace, Instructions for Continued Airworthiness, AAE 005ICA, rev 1, dated 18 March 2014Airlec Air Espace, STC Data List, AAE 005 SDL, rev 2, dated 18 March2014or laterrevisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	20/03/2014	Active	10048548
10048551	S4A SOLUTIONS FOR AVIATION, S.L.			CL-600-2B16	Medical berth installation in CL604	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt. 1225.60125.603 a) b) c)25.605 a) 25.607 a) b)25.609 a)25.611 a) 25.899 a) b)25.1301 a) b)25.1309 a) b)25.1357 a) b) c) g)The requirements for environmental protect...	S4A Master Drawing List No. 60404-RPT02 Issue 1 dated 9th May 2013.or later revisions of the above listed documents approved by EASA	Restricted to ASNs 5366, 5397 and 5416Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.The instal...	20/03/2014	Active	10048551

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048557	AIRGLAS, Inc.		FAA STC SH1919NM	412, 412CF, 412EP	Fabrication and installation of Airglas, Inc. P/N L6500A-1 or L8500R-1left ski and P/ N L8500A-2 or L8500R-2 right ski in accordance withAirglas, Inc. Master Drawing List No. L8500A/R.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airglas, Inc. Rotorcraft Flight Manual Supplement for Bell Model 412,Model 412EP, and Model 412CF helicopters, L8500A/R of the revisionlevel specified in the attached table.or later revisions of the above listed documents approved by EASAinaccordance with EASA ED Decision 2004/04/CF (or subsequent...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/03/2014	Active	10048557
10048558	B/E AEROSPACE, Inc. - FSI		FAA STC ST02300SE	A330-200	Interior Reconfiguration of Qatar A330-200.Installation of SPG Business Class Mini-Pod suites, Recaro tourist classseats, closets, class divider, stowage bins and installation kit. Referto Certification Plan B2FS225-D10-EASA, rev A for additionalinformation.Note 1 : ISPSS and IFE / GCS and WLAN syst...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Refer to The Compliance Checklist in Certificationplan refB2F225-D10-EASA rev A, which presents the list of paragraphs at later CS Amendment level.The requirements for en...	- Certification Plan B2FS225-D10-EASA, rev A- Master Drawing List, ref B2FS225-D01, rev N- ICA : Supplement To Instructions For Continued Airworthiness FSIDocument, ref B2FS225-D15, rev IR (Note : MMEL is out of scope for thisEASA approval)- FAA Letter 150S-14-72, dated on 20th March 2014or later re...	1) Prior to installation of this modification it must be determined thatthe interrelationship between this modificationand any other previouslyinstalled modification and/or repair will introduce no adverse effectupon the airworthiness of the product2) ICA must be incorporated into the operator's ma...	21/03/2014	Active	10048558
10048564	AVIATION COMPLETION INNOVATIONSINC.	REV. 1	FAA STC SR03060NY	AB139, AW139	Installation of Engine Wash Kit in either Configuration 1 orConfiguration 2	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR03060NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Installation Drawing Lists:- Configuration 1: Air Concepts International, Inc. Report No.41252-339-00, Revision IR, dated 7 November 2011.- Configuration 2: Aviation Completion Innovations, Inc. Report No.IL00139.12-2, Revision IR, dated 23 August 2018.Instructions for Continued Airworthiness-When...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/06/2019	Active	10048564
10048570	ASI INNOVATION			E90	Radome with relay antenna installation and provision for electricalsystem	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASI-SDL-0184-02 rev.3 dated 21.03.2014To be operated in accordance with ASI-AFM-0184-01 rev. 1 dated 21.03.2014No changeto ICAor later revisions of the above listed documents approved by EASA	As per the Flight Manual supplement ,,Other: limited to MSNLW 328 and LW 278,,Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	24/03/2014	Active	10048570
10048589	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	B300	Installation of Engine Exhaust Cowlings.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Gama Engineering ModificationHL/MOD/1162 and Installation procedures ref IPI-1162 Issue2.Operation in accordance with Gama Engineering Aircraft Flight ManualSupplement AFMS-1162-01 Issue 1.Instructions for Continued Airworthiness defined in Gama EngineeringReport ICA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/03/2014	Active	10048589

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048592	JET AVIATION AG	REV. 3		737-900ER	VIP Interior Installation B737-900ERAs defined in the: -Project Description, Doc. No. BBJ37546-500. - Master Data List, Doc. No. BBJ37546-001.Revision 1: TSO-related limitation removed.Revision 2: transfer of certificate from “Jet Aviation AG, Basel” (DOA21J.356) to “Jet Aviation AG, Basel Co...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):CRI D-02 Isolated Compartments.CRI D-10 Glass Screens of Displays / Monitors.CRI D-14 Shower Installation.- Equivalent Safety Finding(s): CRI D-09 I...	- Master Data List, Doc. No. BBJ37546-001 Rev IR;- Aeroplane Flight Manual Supplement, Doc. No. BBJ37546-201-01 Rev A;- Instructions for Continued Airworthiness, Doc. No. BBJ37546-150-01 RevIR;- EWIS Instructions for Continued Airworthiness, Doc. No.BBJ37546-150-02 Rev IR;or later revisions of the a...	S/N: 37546. The installation of this modification by third persons issubject to written permission of the approval holder.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or rep...	01/12/2017	Active	10048592
10048593	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	737-300	Deactivation and removal of cargo loading system on QC aircraft withreconfiguration to a standard LOPA.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 14 - VariousThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged a...	J <(>&<)> C Engineering Services Ltd Modification No. JC/MOD/M3746 Issue1.2 dated 11 March 2014or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	25/03/2014	Active	10048593
10048621	ALAMO ENGINEERING GmbH	REV. 2		FALCON 900EX (F900EX)	Seat Change on Dassault Falcon 900EX (SN096).Revision 1: Transfer to 328 Support Services GmbHRevision 2: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List ref. MDL016Z001 issue B, dated 26/03/2014<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system	Applicability limited to Falcon 900EX SN096.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10048621
10048622	ALAMO ENGINEERING GmbH	REV. 2		FALCON 900EX (F900EX)	Cabin Refurbishment with replacement of CMS / IFE and CabinLighting onDassault Falcon 900EX (SN096).Revision 1: Transfer to 328 Support Services GmbHRevision 2: Transfer to ALAMOEngineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List ref. MDL017Z001 issue A, dated 21/03/2014<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system	Applicability limited to Falcon 900EX SN096.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10048622
10048625	airplus engineering GmbH	REV. 2		695, 695A, 695B 690, 690A, 690B, 690C, 690D	Installation of single or dual Garmin G600 Avionics System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment: CS-23 Amdt. 02 -1, 29, 301, 303, 305, 307, 561, 603, 605, 607, 609, 611, 613, 619, 625,627, 771, 773, 853, 867, 1301, 1...	- Flight Manual Supplement PO-1569-000000, Issue 1-0- Description of Modification DE-1569-000000, Issue 1, or later approvedrevisions- Engineering Work Order EW-1569-000000, Issue1, or later approvedrevisions- Maintenance Manual Supplement MM-1569-000000, Issue 1, or laterapproved revisionsor later...	The aircraft must have been already equipped with a suitable GPSreceiver.Prior to installation of this design change itmust be determined thatthe interrelationship between this design change and any otherpreviously installed design changeand/ or repair will introduce noadverse effect upon the airw...	10/02/2021	Active	10048625
10048627	DIAMOND UPGRADES, L.L.C.		FAA SR01124LA	BELL 212	Installation of Pratt & Whitney PT6T-3DE or PT6T-3DF Twin-Pac to replacePT6T-3 or PT6T-3B Twin-PacWhile the FAA approval is granted for both the -3DE and -3DF, the EASAscope of investigation and approval is limited to the -3DF as the -3DEengine is currently not EASA approved.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFM Supplement, AU-001206, Rev. 5, dated 31.07.2013or laterrevisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.Installation Inst...	This approval is limited to the installation of PT6T-3DF Twin-Pac only(PT6T-3DE engine is currently not EASA certified). The Bell TechnicalBulletins listed in the Installation Instructions AU-001207, Rev. 4,dated 25.07.2013, or later FAA approved revisions, must be priorembodied accordingly.Prior to...	26/03/2014	Active	10048627

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048634	LUFTHANSA TECHNIK AG	REV. 1		A380-841/-842-/861	Installation of non-electrical Floor Path Marking SystemRev. 1: Extends applicable pre-change configurations to includenon-electrical or electrical floor path marking systems	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt. 13 for the affected area as defined in Ref. CRL33-16/35MIssue 1 Revision 2The requirements for environmental protection and the associatedcertified noise and/ o...	- Airplane Flight Manual Supplement, Ref. A-00-14/10-AFM Issue 01 Rev.01- Instructions for Continued Airworthiness. Ref. A-00-14/10-ICA Issue 01rev 02- Supplemental Type Definition Document, Ref. STDD33-13/28M Issue 02Rev. 01or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/05/2017	Active	10048634
10048638	AEROLITE AG	REV. 8		429	EMS Equipment P/N 429-0029300-501 and P/N 429-0029301-501.History of revisions:Original Revision consists of modular cabin EMS configurations in whichnew seats and up to two stretchers can be installed. A medical supplypanel provides EMS oxygen and electrical supply. Stowage and attachmentprovisions...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	For EMS Equipment P/N 429-0029300-501:Master Document List,MDL-13-008 Rev. P;Flight Manual Supplement, FMS-429-0029300-501 Rev. F dated APR 20/2020;Operations Manual, OPM-429-0029300-501 Rev. L;Certification Program, CPR-13-015 Rev. NC;Certification Program, CPR-14-023 Rev. NC;Certification Program...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/08/2024	Active	10048638
10048639	KUERZI AVIONICS AG	REV. 1		M20K	Certification of RNAV approach down to LPV minimaCompliancesshowing to AMC20-28 that the installed equipment is suitablefor RNAV (GNSS) Approaches down to LPV Minima.Compliance showing to AMC20-27, resp. CRI F-10 (Airworthiness CriteriaforRNAV Equipment supporting APV BARO VNAV approaches to LNAV/V...	FAR 23 Amdt. 0The Certification Basis for the original product as amended by thefollowing additional or alternative airworthiness requirements:For this non significant change, compliance to FAR 23, Amdt. 0 wasshown. In particular 23.1301, 23.1309, 23.1321, 23.1325, 23.1329,23.1431, 23.1581The certif...	Master Document List: MDL-201313468, Rev. N/C, dated 26.03.2013Airplane Flight Manual Supplement: FMS-201034533 Rev. A,dated26.03.2014or later revisions of the above listed documents approved by EASA.	Required Pre-modifications:-As a minimum dual Garmin GNS430W and a Garmin G500 Display musty beinstalled and approved.-An independent 3rd Communication or Navigation system needs to beinstalled.The approval holder shall fulfill the obligations of Part 21 §21.A118Prior to installation of this designt...	01/04/2014	Active	10048639
10048649	365 AEROSPACE DDS LIMITED	REV. 4		737-8/-8200/-9 737-600/-700/-800/-900/-900ER	Introduction of Controller-Pilot Data-Link CommunicationsRev. 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.Rev. 3: Models 737-8, 737-8200, 737-9 added to theapplicability list.Rev. 4: Correction the associated technical documentation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s):CRI F-01 - Data Link Services for the Single European Sky Issue2CRI F-02 - Flight Recorders including Data Link Recording Issue3.- TheS...	. For models 737-600/-700/-800/-900/-900ER: - Master Data List and Instructions for Continued Airworthiness inModification Summary MOD-1446 Revision C. For models 737-8/-8200/-9: - Master Data List MDL-2084 Revision A - Instructions for Continued Airworthiness ICA-2084-001 Revision A.o...	ACARS OPC Software must be installed on the Digital Electronic Unit(DEU) for correct annunciation.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadv...	19/02/2024	Active	10048649
10048650	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CITATION 550 B BRAVO	P-RNAV approval of Universal UNS-1Csp or UNS-1K	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cessna Düsseldorf Master Document List, 2013-8-16, rev IR, dated 10March 2014Cessna Düsseldorf Airplane Flight Manual, 2013-8-8, rev A, dated 31October 2013Cessna Düsseldorf Installation Procedure, 2013-8-1, rev IR, dated 28June 2013or later revisions of the above listed documents approved by EASA....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/03/2014	Active	10048650

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048661	SERAM - SOCIETE D'ENTRETIEN ETREPARATION AERONAUTIQUE MACONNAISE			TB9, TB10, TB20	Dual installation of Garmin GNS 400/500 series system and associatedantenna and indicators, and of Garmin GMA 340 audiosystem, according toSERAM modification No. 412.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SERAM Flight Manual Supplement n° 412-3 - TB9/10/20 - Use of GNS4xx A/Wand 5xx A/W in IFR BRNAV, PRNAV, RNP approach LNAV and LPV, revision 0dated, 30/10/2013.SERAM Flight Manual Supplement n° 412-1 - TB9/10/20 - Use of GNS4xx/A/Win VFR, revision 0 dated 30/10/2013.SERAM Flight Manual Supplement n°i...	Initial installation must be performed by authorised SERAM personnel.This installation is approved for VFR and for IFR B-RNAV, P-RNAV and RNPapproach LNAV operations.It is also approved for RNP approach LPV operations but only with GNS430 W/AW or GNS 530 W/ AW systems enabling GNSS vertical guidance....	28/03/2014	Active	10048661
10048669	LUFTHANSA TECHNIK AG	REV. 1		A380-841, A380-842, A380-861 A380-841/-842/-861	Installation of Data Broadband Transceiver System with fullprovisionfor On-Board Mobile Telephony SystemRev. 1 - Instructions for Continued Airworthiness revision due to themodification of an existing inspection task interval and itsintroduction into ALS section.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI C-02 - Vibration/Buffeting andFlutter Compliance Criteria.Therequirements for environmental protection and the associated...	Supplemental Type Definition Document: STDD44-13/01M Iss. 02Rev.00Instructions for continued Airworthiness: A-00-13/51-ICA Iss.03 Rev. 00AFM-Supplement: A-00-13/51-AFM Iss.02 Rev.00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/09/2024	Active	10048669
10048670	AEROTEC SARL			TB 20	Installation of two Garmin GTN650 system, a Kind KN62A DME and a GarminGMA340 audio system, according to Aerotec modification no. MOD 13258	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CSW 23 Amdt. 3 § 867, 1301, 1309, 1311, 1321, 1322, 1327, 1329, 1351,1353, 1357, 1365, 1381, 1431, 1529, 1541,1547, 1581The requirements for environmental protection andc...	Aircraft Flight Manual Supplement No. AE13258SMV revision 0dated06/12/2013Instructio ns for Continued Airworthiness No.AE13258ICA revision 0 dated06/12/2013Master Data List No. AE13258MDL revision 0 dated 06/12/2013or later revisions of the above listed documents approved by EASA.	This installation is limited to TB 20 S/N 1245.This installation is approved for IFR B-RNAV, P-RNAV, RNP approach LNAVand LPV operations, with coupling to KAP 150 autopilot and Aspen 1000Pro display system.Introduction of new functions through software upgrade must be subjectof another EASA approval...	31/03/2014	Active	10048670
10048697	INFLIGHT WARNING SYSTEMS, Inc.		FAA ST02588AT	767-200, 767-300	Installation of the inflight warning Systems Inc., Fan Vibration MonitorUnit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List MDL 211022 Rev A dated May 6, 2002Master Data List 13145 Rev IRInstructions for Continued Airworthiness ICA 13105 Rev IR Dated Sept 9,2013or later revisions ofthe above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/03/2014	Active	10048697
10048698	INFLIGHT WARNING SYSTEMS, Inc.		FAA ST02823AT	767-300F, 767-400ER. 767-200, 767-300,	Installation of an air conditioning fan monitors to monitorfan bearingperformance.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 212000 Rev D dated January 13, 2004Master Data List 13413 Rev B dated December 21, 2005Instructions for continued Airworthiness ICA 13419or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions oft...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/03/2014	Active	10048698

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048699	BOMBARDIER INC.		TCCA C-LSA02-292/D	BD-700-1A10	Aircraft Completion: 14 passenger interior configuration - EASAvalidation of Transport Canada STC C-LSA02-292/D at issue 1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): EASA Deviation CRI D-100 at issue 3 "Doors betweenpassenger compartments"The requirements for environmental protection and the associatedcertified noise and/...	Modification to be completed in accordance with Aero Consulting ServicesModification Data Summary D02000 Revision E dated 26th March 2014Required Flight Manual Supplements:- G-FM24000021 rev N/C - Cabin Master Power Switch- G-FM25000034 rev N/C - Interior Completion- G-FM26000022 rev N/C - Smoke Det...	- This STC is limited to aircraft serial number 9086.- Refer to the required Flight Manual Supplements and AirworthinessLimitations Supplements listed in associated technical documentation.- Bombardier Service Bulletin 700-31-018 (Modification – IntegratedAvionics Computers (IAC) – Avionics 2001 Ba...	31/03/2014	Active	10048699
10048705	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS LTD		CAA UK RESPONSIBILITY	A320-214	Removal of Aircraft Cabin Interior and Associated Changes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AeroDEC Modification Summary No. 1401 Revision B dated 14 April 2014or later revisions of the above listed documents approved by EASA.	Restricted to ASNs 4805, 4851, 4948The following AeroDEC Modifications are required to be concurrentlyembodied as partof this STC:MOD-1402 - Removal of Satellite TV System ProvisionsMOD-1403 - Removal of Gogo Aircell Broadband ServicesMOD-1404 - Removal of Windscreens & Class DividersMOD-1405 - Re...	15/04/2014	Active	10048705
10048730	ACC COLUMBIA Jet Service GmbH	REV. 7		DA42 DA 42	DA42 Engine RetrofitThe presently installed versions of TAE125 engine are replaced by theTAE 125-02-114 engine. This STC includes two configurations:Configuration 1: Propeller MTV-6-A-C-F/CF 187-129 without noisesuppressorConfiguration2: Propeller MTV-6-A-C-F/CF 190-69 with noise suppressorRev. 7 a...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List, Doc. No. MDRWL_25-90100, Rev. 0Master Document List, Doc. No. MDOCL_25-90100, Rev. 0Aeroplane Flight Manual Supplement, Doc. No. AFMS_23-90562, Rev. 0Maintenance Manual Supplement, Doc. No. MMS_23-90562, Rev. 1or laterrevisions of the above listed document(s) approved/acceptedu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10048730
10048732	AERODATA AG	REV. 1		B300	Installation of AD-AFIS-112 into B300 with ProLine 2 Cockpit.The installation consists of the integration of non-essential sensorsystem in the aircraft fuselage and cabin with associated indication inthe cockpit.	The Certification Basis for the original product remains applicable foritems not affected by the modification, for items affected by themodification the following new Certification Basis is elected to complywith: CS-23 Amdt. 3, except 23.561 and 23.785 (kept FAR 23.561 Amdt. 34and FAR 23.785 Amdt. 3...	Installation of AD-AFIS-112 in accordance with Master Document List,Aerodata document MDL-A/C-851 Rev. 2, dated March 20, 2014;Aircraft Flight Manual Supplement, Aerodata documentAFM-141 Rev. 0;Instructions for Continued Airworthiness, Aircraft Maintenance ManualSupplement, Aerodata document AMM-11...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/04/2014	Active	10048732
10048735	CRANFIELD AEROSPACE SOLUTIONS LIMIT	REV. 2	CAA UK RESPONSIBILITY	A340-311/-312/-313	Installation of the Rack, Cable and Server for Tracking andDataCommunications.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cranfield Aerospace Modification No. CAeM/340/1374CranfieldAerospace Ltd Type Design Definition Addendum No.CA/DD/DR0177 Issue B dated 28 February 2014or later revisions of the above listed documents approved by EASA	Installation of EASA STC 10048735 is a prerequisite for thismodification.	21/02/2017	Active	10048735

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048745	AVIONITEC AG			PA-31T, PA-31T1 PA-31T2, PA-31T3	Dual GNS 530W upgrade incl. LPV CertificationRemoved: - Dual Garmin GNS 530 (GPS/COM/NAV)Installed: - Dual Garmin GNS 530W (GPS/COM/ NAV)Compliance showing to AMC20-28 that the installed equipment is suitablefor RNAV (GNSS) Approaches down to LPV Minima.Compliance showing to AMC20-27, resp. CRI F-10f...	FAR 23 Amdt: 7The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List: No. 3493-017, dated 11.01.2014Instructions for continued airworthiness: No. 3493-015, dated 19.11.2013Airplane Flight Manual Supplement: No. 3493-011, dated 19.11.2014Modification Instruction: No.3493-050, dated 11.01.2014or later revisions of the above listed documents approve...	The approval holder shall fulfill the obligations of Part 21 §21.A118Prior to installation of this modification it mustbe determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthine...	04/04/2014	Active	10048745
10048773	RUAG AG	REV. 2		PC-12, PC-12/45, PC-12/47 PC-12, PC-12/45 PC-12/47, PC-12/47E PC-12/47E	PC-12 Antenna Installation.The initial STC approved multiple antenna installations.Rev.1 of this STC provides multiple antenna installations andrelocations options.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Instructions for Continuous Airworthiness Doc. No. ICA-8001156 Rev. D.- Master Data List Doc. No. MDL-8001143 Rev. C.orlater revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2021	Active	10048773
10048774	SCHERDEL ENGINEERING Ltd.			SEE EASA APPROVED MODEL LIST	SH Tail Aero Modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Technical Note TN 4, Rev 1 SH Tail Aero Modification-Certification Document CD_V1, Rev 1or later revisions of the above listed documents approved by EASA.	Valid only for Types listed in the Technical Note Scherdel EngineeringTN 4Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the air...	08/04/2014	Active	10048774
10048781	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBIL ITY	A109S, AW109SP	Patient Transfer SystemTo modify the existing air ambulanceinterior to conduct hospital tohospital critically ill patient transfer including stretcher and patient& equipment restraint provisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List Report No: BAC-864MDL02 Issue 2, dated 02 April 2014Instructions for Continued Airworthiness Report No: BAC-864ICA02 Issue1, dated 11 November 2013	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/04/2014	Active	10048781
10048788	LUFTHANSA TECHNIK AG	REV. 2		767-400ER	“Spinel” VIP cabin completion-Variant 1: baseline cabin design-Variant 2: baseline cabin design modified with removal of one internaldoor, redesignation of one flight attendant seat for in-flight use only,replacement of certain glass mirrors with plastic onesRevision 1: addition of variant 2Revision...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-06 Isolated compartments, D-07 Showerinstallation, D-09 Use of glass, H-01 Enhanced airworthiness programmefor aeroplane systems ICA on EWISDeviati...	Generic documents: Supplemental Type Definition Document STDD00-11/22M Issue 4 Rev 0Original installation documents- Instruction for Continued Airworthiness A-00-11/162-ICA Issue 2 Rev 7- Airplane Flight Manual A-00-11/162-AFM Issue 3 Rev 0Oxygen flex hoses replacement documents- Certification Plano...	Other: as per A-00-11/162-AFM1.GeneralA/C is certified for non-commercial operation only.2.SignsThis is a non smoking a/c. Therefore the electrical no smoking signsmust always be switched on. 3.Satellite Communication System (INMARSAT SATCOM) Satellite voice has been demonstrated for use only as suppl...	16/12/2020	Active	10048788
10048789	E A D AEROSPACE AIRWORTHINESS			B767-200/-300	Activation of GSMConnex system installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 01420-EAS-A-MDL rev C dated 03 April, 2014Aircraft Flight Manual Supplement 01420-EAS-A-AFM-01 rev A dated 28Nov., 2013Instructions for continued airworthiness01420-EAS-A-ICA-01 rev A dated28 Nov., 2013or later revisions of the above listed documents approved by EASA	This approval is limited to the aircraft MSN32954 configured accordingto the ICA document 01420-EAS-A-ICA-01. The aircraft must be equippedonly with those elements proved to be compatible with the installedGSMConnex system.Prior to installation of this design change it must be determined thatthe int...	10/04/2014	Active	10048789

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048791	AVIONICS SUPPORT GROUP, Inc.	REV.4	FAA STC ST03974AT	A321-251NX/253NX/ 271NX/272NX A321-251N/253N/271N/ 272N A321-212 / -213 / -231 / -232 A321-211/-212/-213/-231/-232 A320-273N/ A321-111/-112/-131 A320-252N/-253N/-271N/-272N A320-231/-232 /-233/-251N A320-231 / -232 / -233 A320-211/-212 /-214/ A320-211 / -212 / -214 A319-153N/-171N A319-131/-132/-133/-151N A319-115 / -131 / -132 / -133 A319-111/-112 /-113/-114/ -115 A319-111 / -112 / -113 / -114 321-111 / -112 / -131 / -211	Installation of a Collins Iridium Communications System in AirbusA319/ A320/A321 (CEO and NEO) Series AircraftRev. 1: A320-232 model added to the applicability listRev. 2: NEO models added to the applicability listRev. 3: A319 and A320 NEO models added to the applicability listRev. 4: Correction of A...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA STC ST03974AT, Issued December 17, 2021- Master Data List 210142-MDL Rev. N, dated December 15, 2021- Instructions for Continued Airworthiness 210142-ICA Rev. J, datedAugust29, 2019- Airplane Flight Manual Supplement 210142-FMS Rev B, dated December 14,2021or later revisions of the above list...	This document approves the installation of the complete ICS-120A/220AIridium Communication System. The partial antenna installation asgranted with FAA STC ST03415AT is not part ofthe approval as STCST03415AT is not being concurrently validated.Prior to installation of this design change it must bet...	04/01/2023	Active	10048791
10048793	S-TEC CORPORATION		FAA STC SA08999AC-D	F33, F33A, F33C, G33 35-C33A, E33, E33A, E33C 35-33, 35-A33, 35-B33, 35-C33	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem (Model ST-583)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Bulletin No. 683, Revision 2, dated 4-12-01 and MasterDrawing List No. 92763, Revision B, dated 4-12-01(14Volt System)or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Te...	1. Model F33A eligibility limited to S/N CE-315 and below.2. FAA/DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891158, dated 4-27-95 is required for BeechModels 35-33, 35-A33, and 35-B33 or later FAA Approved revisions of theabove supplement.3. FAA/DAS Approved...	10/04/2014	Active	10048793
10048796	VIH AEROSPACE Inc.	REV. 1	TCCA STC SH09-43	EC135 T2+, EC135 T3 EC135 T2 (CPDS), EC135 T2+ EC135 T1, EC135 T2 EC135 T1(CDS), EC135 T1(CPDS) EC135 P2+, EC135 P3 EC135 P2 (CPDS), EC135P2+ EC135 P1, EC135 P2 EC135 P1 (CPDS) EC135 P1 (CDS)	Installation of Crew Bubble Window in accordance with TCCA STC SH09-43and Master Document List V135-0811-MDLInitial Issue (in accordance with TCCA STC SH09-43 Issue 1)- Installation of Crew Bubble Window RHRevision 1 (in accordance with TCCA STC SH09-43 Issue 2)- Extension of applicability to EC135-...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Rotorcraft Flight Manual Supplement V135-0811-FMS Revision 2- Master Document List V135-0811-MDL Revision 2- Instructions for Continued Airworthiness V135-0811-ICA Revision 2or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Imple...	Limited to helicopters with CDS/ CPDS cockpit variantCrew Bubble Window is also referred to as Vertical Reference Window(VRW) in Rotorcraft Flight Manual SupplementPrior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	26/01/2022	Active	10048796
10048797	CENTEX AEROSPACE, INC.	REV. 2	FAA SA11103SC	2. B200GT 2. B200, B200C, B200CGT 1.A200C, A200CT, B200CT, B200T 1.200, 200C, 200CT, 200T, A200	Halo 250 IGW – addition of Halo 275 configuration and new weightlimitations.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Installation in accordance with CenTex Aerospace Master Drawing List(MDL) No 006-0000-0000, Rev X, and „Installation Instructions“ DrawingNo 006-0000-1000, Rev M;Operate in accordance with CenTex Aerospace “Required Airplane FlightManual Supplements” (AFMS) as listed on Drawing No 006-0000-1000, Rev...	Refer to CenTex Aerospace Drawing No 006-0000-1000, Rev M, or laterrevisions, for the approved weight limitations that apply to thespecific airplane configuration under STC Option1 and STC Option 2.Prior to installation of this change/ repair it must be determined thatthe interrelationship between t...	17/10/2018	Active	10048797

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048798	ATELIER CHABORD	REV. 3		DR 400/160, DR 400/160 D DR 400/140, DR 400/140B DR 400/140, DR 400/140 B DR 300/140, DR 340, DR 360	Installation of exhaust system according to Chabord modificationSTCDR420-2012-01REV. 3: - Enhanced silent blocks - Alternative anti corrosion surface treatment - Enhancedmaterial on different parts - Enhanced shape of central structural part in muffler - Additional bracket on double...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 23 Amdt 3 § 607,611, 783, 807, 867, 1101, 1121, 1123, 1125, 1529.The requirements for environmental protection and th...	Technical Dossier ref. STCDR420-2012-01 Revision M dated 05January 2022<(>,<)>Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	08/03/2022	Active	10048798
10048807	AEROTEC & CONCEPT			C90	Authorise RNAV (GNSS) approach to LPV minima.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	In accordance with Aerotec Modification AE13182 as defined in MDLAE13182 MDL Rev 0 dated 20/03/2014.Operate in accordance with Aerotec Aircraft Flight Manual Supplement refAE13182AFMS, Rev 0 dated 11/03/2014.or later revisions of the abovelisted documents approved by EASA.	BCA STC N° 10029562.must be installed.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	10/04/2014	Active	10048807
10048826	TURK HAVA YOLLARI TEKNIK A.S.TURKISH TECHNIC			A319-112	Conversion of cabin layout from 144 PAX full E/C to 134 PAXdual classand installation of fixed glass divider with doghouse and stowage	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Programme CG-2500002-CP01-02 Rev. 02, dated 04/04/2014- Design Declaration Form CG-2500002-DD01-00 Rev.00, dated 08/04/2014- Master Data List CG-2500002-MD01-01, dated 04/04/2014or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	14/04/2014	Active	10048826
10048833	MID-CONTINENT INSTRUMENT Co., Inc.	REV. 2	FAA SA01969SE	SEE EASA APPROVED MODEL LIST	Installation of a Mid-Continent MD302 Standby Attitude Module inaccordance with Master Data List AM0261-DL02-00, specified on theattached EASA Approved Model List (AML) issued 24th November 2015 orlater approved revisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation according to the document “Installation Instructions forthe Installation of the MD302 Standby Attitude Module on Aircraft Listedin the Aircraft Model Listing” – AM0261-IM01-00 Rev. C dated 6thDecember 2013Maintenance accordingto the document “Instructions for ContinuedAirworthiness for...	Other: Approval of this change in type design applies to the aircraftlisted on the AML only.The MD302 cannot be used asa primary display. For aircraft that requirethe pilot to hold a type rating, the candidate aircraft must be equippedwith primary flight displays that include vertical tape displays...	25/11/2015	Active	10048833
10048838	MT-PROPELLER ENTWICKLUNG GmbH			76	Installation of 3-blade MT-Propeller Model MTV-12-B-C-F/CF(L)183-59b onBeech 76	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-36 Amdt.2 and FAR 36 Amdt. 28FAR 23.1529 Amdt. 26This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certifi...	According to MT-Propeller Master Document List No. E-2329 andMT-Propeller Installation Instructions Doc. No. E-2326, orlaterRevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-2325To be maintained i.a.w. MT-Propeller ICA Document No. E-2327or later revisions of the above li...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	15/04/2014	Active	10048838

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048850	IKHANA GROUP, LLC	REV. 1	FAA STC SA02474LA	DHC-6 SERIES 100, 200, 300	Install and Maintain DHC-6 Re-Life of engine nacelles by replacement orreinforcement of fatigue critical structural components.RWMI DHC-6 Re-Nacelles are approved replacements forViking Air Limited(formerly Bombardier Inc. or De HavillandInc.) flight controls aslisted below:Nacelle Assembly ,,,,OE...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR23 at amendment 23-0 through 23-59:23.29, 23.301, 23.303, 23.305, 23.307, 23.572, 23.574, 23.575, 23.601,23.603, 23.605, 23.607, 23.609, 23.611, 23.613, 23.619, 23.623,...	Services Drawing List, Document No. ER 218-1122 Revision B,dated July15, 2013Master Data List Document No. ER2I8-1123 Revision NC, dated August 26,2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis deci...	1. Approval of this modification applies to the above notedmodelairplane series only. This approval should not be extended to otherspecific airplanes of this model series on which other approvedmodifications are incorporated, unless it isdetermined that theinterrelationship between this change and...	18/06/2021	Active	10048850
10048858	AMAC AEROSPACE SWITZERLAND AG			A318-112	Installation of external cameras	JAR 25<(>,<)> Change 11The Certification Basis for the original product remains applicable tothis certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Data List MDL-CV01-4420 Rev. BInstructions for Continued Airworthiness ICA-CV01-4420 Rev. Aor later revisions ofthe above listed documents approved by EASA	S/N: 4650Prior to installation of this modification it mustbe determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	16/04/2014	Active	10048858
10048864	TELAIR INTERNATIONAL Inc.		FAA STC ST02489LA	SEE EASA APPROVED MODEL LIST	Light Weight LD3 Cargo Container	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List MDLLD3100 Revision Bor later revisions ofthe above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Proceduresof EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	17/04/2014	Active	10048864
10048865	SUPERJET INTERNATIONAL S.P.A.			C27-J	Dual EFB (class 2) installation on C27J	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	OPS-CDO-121010 Rev. A - Supplement Type Design DefinitionOPS-CDO-10006 Rev. C - Certification ProgrammeOPS-CDO-12010 Rev. A - Project Compliance RecordSJI-AFM-EASA.A.S. 03946 Rev. A - AFM Supplementor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	17/04/2014	Active	10048865
10048873	GFD GmbH	REV. 1		35A, 36A	VHF Antenna provisions installation (for Vessel tracker mission)Rev. 1: Transfer to GFD GmbH	FAR 25 Arndt: 25-7, 25-18 and Paragraph 25.571(d) of Amendment 25-10,Special Conditions set forth in FAA TC datasheet No. FAA A10CEThe Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The certificated noise and/ or emissions levels of the original pro...	- ICA Instructions for Continued Airworthiness Doc. 5317-085 Revision IR-Master Data List Doc. No. 5317-049 Revision IRor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/08/2022	Active	10048873
10048878	LIVETV, L.L.C.		FAA STC ST03251CH	A320-233 A320-232 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211 A320-111	Installation of the LiveTV Ka-Band Connectivity System	The Certification Basis for the original product as amendedby thefollowingadditional or alternative airworthiness requirements:In addition to the original certification basis specified by TCDSEASA.A.064 the applicant has demonstrated compliance with JAR-25 Change13 pertaining to 25.305, 25.571(e)(1...	-Master Date List, LiveTV document No. 3SSK8001-MDL, Revision H, 31January 2014-Instructions for Continued Airworthiness, LiveTV document No.320K8001-NCA, Revision F, 11 March 2014-Aircraft Flight Manual Supplement, LiveTV document No. 320K8001-AFM,Revision IR, dated 29 August 2013or later revisions...	Installation of aft upper crown structural reinforcements as per LiveTVSTC ST0788SE is required concurrently or prior to the installation ofthe Ka-Band Connectivity System in Airbus A320 series airplanes wheninstalled I/A/W LiveTV document320K8001-IDL. The aft upper crownstructural reinforcement in...	18/04/2014	Active	10048878

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048882	AVIONITEC AG			P210N	Replacement of KX-155 VHF-COM/NAV No. 2 by a 2. GNS 430WOut: King KX-155 systemIn: Garmin GNS-430W system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	Master Document List No. 3150-017 Rev. 0 of 21.02.2014Instructions for Continued Airworthiness 3150-015 of 21.02.2014AFM Supplement No. 2259-011 Rev. 1 of 21.02.2014or later revisions of the above listed documents approved by EASA.	S/N: P210-0134The approval holder shall fulfil the obligations of Part 21, Point21.A.109 or 21.A.451(b) (as applicable).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repai...	22/04/2014	Active	10048882
10048912	AVIATION FABRICATORS, Inc.	REV 1	FAA SA02468LA	B300, B300C B200GT, B200CGT B200CT, B200T B200, B200C, B200CT 200, 200C, 200CT, 200T	Installation of Aviation Fabricators Aft Toilet Cabinet Seat (includingoxygen, air and light systems).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02468LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. FAA Approved Aviation Fabricators Master Data List, No. AF-482MDL,Rev B, dated 11 June 2013, or later FAA approved revision.2. Aviation Fabrications Instructions for Continued Airworthiness (ICA)Document No. AF-483, Rev A, dated 30 November 2009 or Document No.AF-570, Rev IR, dated 30 October 201...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/11/2018	Active	10048912
10048922	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST03184NY	A330-200, -300	Installation of a Panasonic eX2 In-Flight Entertainment System andGlobal Communication Suite System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:Refer to section 3 of Compliance Summary Report Project results: 6654-08810-2356<(>,<)> rev C and 6654-08908-2356 rev -Thec...	Delta Engineering Instructions for Continued Airworthiness No. 0754-08528-2356 Revision BDelta Engineering AFMS No. 0654-08968-2356 Rev –or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or th...	This STC will require the following separate approvals as pre-requisite:a. T-PED tolerance approved by a separate STC: EASA STC 10043586b. The Panasonic GCS antenna (ku-band) is installed by a separate EASASTC 10037167c. For configuration TL10741-01 Zodiac Aerospace Service Bulletin1042L-25-11 and E...	02/07/2018	Active	10048922
10048924	S-TEC CORPORATION		FAA STC SA09542AC-D	SERIALS FE-1 AND SUBSEQUENT) 2. B200, B200C 1. B200CT, B200T 1. A200CT (EXCLUDING 1. A100-1, A200, A200C 1. 200, 200C, 200CT, 200T	Installation of S-TEC 01304 Digital Flight Control System (DFCS).	As defined on FAA STC SA09542AC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged andremain applicable to this certificate/ approval.	Installation in accordance with S-TEC Master Data List refST-921-L-0001, Revision G, dated 23 March 2010.Operation in accordance with S-TEC Airplane Flight Manual SupplementST-921-M-0001, Revision A, dated 03 January 2008. Instructions forContinued airworthiness (ICA) in accordance with S-TEC (ICA)o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	23/04/2014	Active	10048924
10048929	S4A SOLUTIONS FOR AVIATION, S.L.	REV. 1		BD-100-1A10	ASPIRE 200 SATCOM SYSTEM INSTALLATION IN CHALLENGER 300	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CL301-SB001 Service Bulletin Ed4CL301-HDK01 Flight Manual Supplement Ed2or later revisions of the above listed documents approved by EASAEASA Accepted Data:CL301-HDK02 MaintenanceManual Supplement Ed2CL301-HDK03 Wiring Manual Supplement Ed2	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/04/2014	Active	10048929
10048942	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	F900EX	Introduction of Honeywell Ovation Select Cabin Management System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Master Document List No. S21.MDL-1170 Issue2 dated24/04/2014or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	25/04/2014	Active	10048942

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10048966	HELI-ONE (NORWAY) AS			AS332L1 AS332L	MOD AHSE -64610,RNAV-2 FMS Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 ;amendment 3 .(§29.561 Emergency Landing Conditions is revertedfrom CS 29 amd 3 to the FAR 29 amd 16 ofwhich the aircraft wasoriginally certified)The requirements...	- Heli-One Flight Manual Supplement NºH1No-216 "RNAV-2 INSTALLATIONAHSE-64610" Initial issue, dated 13 Feb.2014or later revisions of the above listed documents approved by EASA.-Heli- One Master Drawing AHSE-64611 Rev -.- Heli- One Embodiment instructions AHSE-64617 Rev D.- Heli-One Certification...	Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the product.	28/04/2014	Active	10048966
10048985	BOMBARDIER INC.			BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9083	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-100 Doors between passenger compartments.D-200 Side Facing DivansD-300 Passenger Information SignsThe requirements for environmental protection and the associatedcer...	Transport Canada STC No. C-LSA02-293/D Issue 4 dated 12 December 2003.Aero Consulting Services Modification Data Summaries D31350 Rev B andD31300 Revision N/ C.The following Bombardier Aerospace Flight Manual Supplements:G-FM24000038 Rev N/C Cabin Master Power SwitchG-FM25000046 Rev A Interior Comple...	Restricted to ASN 9083. Bombardier Service Bulletin 700-31-018Modification - Integrated Avionics Computers - Avionics 2001 Batch 1 IACUpgrade must be embodied.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviousl...	30/04/2014	Active	10048985
10048987	HAECO CABIN SOLUTIONS, LLC		FAA ST03665AT-D	767-300	Installation of seven (7) Upgraded Lavatories	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amdt. 12: 25.1, 25.23(a)(b)(2), 25.25, 25.27,25.301, 25.303,25.305(a)(b), 25.307(a)(d), 25.601, 25.609, 25.613(a)(b), 25.619,25.625, 25.785(f)(3), 25.791, 25.793, 25...	Master Data Lists MDL 08T052L001<(>,<)> revision L, dated September 14,2012; and 10T078L001, revision IR, dated September14, 2012Instructions for Continued Airworthiness 08T052R009, Rev. A dated June5, 2009; and 10T078R009, Rev. IR dated July 6, 2012or later revisions of the above listed documents a...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	30/04/2014	Active	10048987
10049019	RUAG AG	REV. 1		EC 120 B	Omni Antenna & Actuator Down Link System installation P/N 800-1693-02Rev 1: Transfer of STC to a new legal entity that is holder of a new DOA(EASA.21J. 760)	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:SCs or ESFs: CS 27 Amdt. 3 for the Change:27.1; 27.29; 27.251, 27.301; 27.303; 27.305; 27.307; 27.601; 27.610;27.629: 27:777; 27.1301; 27...	Rotorcraft Flight Manual Supplement No.: FMS-609034 Revision AMaster Document List No.: MDL-8001686 Revision AInstructions for Continued Airworthiness No.: ICA-8001687 Revision Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	S/N: 1045 & 1098This installation only covers the mechanical Antenna provisioninstallation (including the electrical actuator); the installation ofthe receiving and transmitting of this antenna equipment is not part ofthis approval.The approval holder shall fulfill the obligations of Part 21, § 21.A...	18/01/2021	Active	10049019
10049030	L2 AVIATION SOLUTIONS, LLC	REV. 1	FAA ST10928SC	737-900, 737-900ER 737-700, 737-800	Rev 0: Installation of an Iridium Communication System in accordancewith Master Drawing List 2322-B43-MDL rev ADRev 1: Addition of the PTA 12-100 Dialer in accordance with the MasterDrawing List 2322-B43-MDL rev AT	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25.305, CS25.365,CS25.561, CS25.571, CS25.613(a),(b),(c), CS25.773(a)(2), CS25. 869(a),CS25.1309, CS25.1316, CS25.1353(a...	- Airplane Flight Manual Supplement, Ref. 2322-B43-AFM, Revision G,dated 25 SEPT, 2013.- Instructions for Continued Airworthiness, Ref. 2322-B43-ICA, RevisionX, dated 5 AUG 2015.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subseq...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/02/2016	Active	10049030

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049031	JCB AERO SA			A320-214	A320 cabin reconfiguration from 162 to 180 pax	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Project Data List A320-03444-01-PDL-01, Rev. A, dated 29/04/2014- Compliance Report A320-03444-01-CR-01, Rev. IR, dated 25/04/2014- Instructions for Continued Airworthiness A320-03444-01-ICA-01, Rev.IR, dated 28/02/2014or later revisionsof the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	05/05/2014	Active	10049031
10049035	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED	REV. 1	CAA UK RESPONSIBILITY	AS 355 NP	Installation of a Live Line Working Rig as underslung load liftingsystem for Human External Cargo in accordance with modificationBOND/MOD/034 as defined in DL/034-099.Revision 1 is issued to grant extension of the Roblon Rope life limitsupto 4 years and approval for the use of the alternative PCDSB...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS27 Amdt. 2 for:. 1, .141, .143, .171, .251, . 301,.303, .305, .307, .321, .337, . 341,.351, .561, .571, .601, .603, . 605, .607, .609, .610, .611, .613, . 771,.773, .777, .8...	- AS355NP Flight Manual Supplement “Live-Line Working Rig”,FMS/ 034-002Issue 4 dated 25 Aug 2016;- Instructions for Continued Airworthiness, Part 2 AirworthinessLimitations, ICA/034-018 Issue 5 dated 15 July 2016.or later revisions of the above listed documents approved by EASA.- BOND/MOD/034 Modifi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/09/2016	Active	10049035
10049043	SKYLINE HELICOPTERS Ltd.			429	Long Line Control Circuit Installation.The Longline ControlCircuit SAS-429-001 is a change for the Bell 429and it is defined in accordance with Avionics Design Services Ltd.Master Drawing List MDL 12063. The change provides for the control of aremote electrical hook. The circuit consists of an armi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement Longline Hook Control SAS-429-FMS-1Rev. 0, Dated June 5th, 2012.or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Instruction for Continued Airworthiness for...	There is no change to the limitations associated with the cargo hook asa result of longline control circuit installation.Prior to installation of this design change it must be determined thatthe interrelationship between this design changeand any otherpreviously installed design change and/ or repa...	06/05/2014	Active	10049043
10049048	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			TB 9/10/20/21/200	Installation of a Garmin GTN 650 system, a GA 35 GPS antenna and aBendix/King KN62A DME receiver, according to SEAM modification file no.4020/12 revision 2 dated 15/04/2014	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23 amdt. 3 § 23.301, 305, 307, 561, 601, 606, 607, 609, 867, 1301,1309, 1321, 1322, 1351, 1353, 1357, 1365,1381, 1431, 1501, 1519, 1525,1529, 1541, 1581The requirement...	Garmin Flight Manual Supplement ref. 190-01007-E3 Rev. 1SEAM Flight Manual Supplement no. SMV-4020/12 revision 0 dated23/04/2014or later revisions of the above listed documents approved by EASA.	The installation covered by this STC is approved for IFR BRNAV, PRNAV,RNP approach LNAV and LPV operations, with coupling to autopilot BendixKing KAP 150 and to Aspen EFD 1000 Prodisplay system.Initial installation must be performed by authorised SEAM personal.Software upgrades introducing new func...	07/05/2014	Active	10049048
10049051	ELDEC LLC	REV. 1	FAA ST02293SE	SEE FAA APPROVED MODEL LIST DATED 17 OCTOBER 2013 CL-600-2B16 CL-600-1A11, CL-600-2A12 BD-700-2A12 BD-700-1A10, BD-700-1A11 BD-100-1A10	Installation of a Crane Aerospace & Electronics Tire SensorAssemblyRev. 1 updates the applicability in adding the model BD-700-2A12.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Crane Aerospace Master Document List CCL83-022-01_Bombardier, Revision -dated 12 September 2013<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalfof EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/06/2021	Active	10049051

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049061	ANUVU	REV. 3		A321-253NY/-271NY A321-253NX/-272N/ 271NX/-272NX A321-253N/-251NX/-252N X/-271N A321-213/-231/-232/-251N /-252N A321-213/-231/-232 A321-111/-112/-131/-211/- 212 A320-253N/-271N/-272N/- 273N A320-231/-232/-233/-251N /-252N A320-231/-232/-233 A320-211/-212/-214/-215/- 216 A319-171N A319-131/-132/-133/-151N /-153N A319-131/-132/-133 A319-111/-112/-113/-114/- 115 A318-111/112/-121/-122 A318-111/-112/-121/-122	Installation of provisions for the use of dual tablet Class2 EFBsystem.Rev. 1: Transfer of STCRev. 2: applicability extension to NEO and ACF models.Rev. 3: applicability extension to A321 XLR models (-253NY and -271NY)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): M-TS-0000419 issue 2.- Thefollowing paragraph(s) at a later amendment:CS 25 at Amendment 26 for the par. affected by the change (ref. 1320R02-CCL-A...	- Master Data List 1320-MDL-A320 Rev. G, dated 22 May 2025-Certification Compliance Record 1320R08-CCL-A320 Rev. A, dated 16 Jun2025-Aircraft Flight Manual Supplement 1320-AFMS-A320 Rev. E, dated 1 Mar2025- Instructions for Continued Airworthiness 1320-ICA-A320 Rev. C, dated 3Apr 2025- Flight Crew...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/06/2025	Active	10049061
10049067	DUNCAN AVIATION, INC.		FAA ST01729WI	BD-700-1A10	Installation of R/H Aft Three-Place Divan	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST01729WI dated 21 January 2014.Duncan AviationInc, STC Master Document List No. CERTDOC-0000001274,Revision B, dated 21 November 2013.Airplane Flight Manual Supplement, Duncan Aviation Inc, Doc No.EDOC-0000015899, Revision A,dated 3 October 2013.or later revisions of the above listeda...	Restricted to ASN 9110.EASA STC No. 10049703 (Ref EASA Project No. 0010029834) is apre-requisite for this STCPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will intr...	01/07/2014	Active	10049067
10049089	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		757-200, 757-200PF, 757-300	Aviator 300 WLAN function and PSS cabin outlets	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Documents, Scandinavian Avionics document No. 2078073 DOC<(>,<)> Issue 1, dated 5 May 2014-Aircraft Maintenance Manual Supplement, Scandinavian Avionics documentNo. 2078073-MM Issue 1, dated 13 February 2013	None	16/05/2014	Active	10049089
10049096	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			560XL / XLS - CITATION EXCEL	P-RNAV Capability within Universal UNS-1CSP or UNS-1K FMS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cessna Düsseldorf Airplane Flight Manual Supplement, document No. 2013-22-8,rev IR, dated 04 Dec 2013Cessna Düsseldorf Master Document List, doc. No. 2013-22-16, rev IR,dated 25 April 2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/05/2014	Active	10049096
10049097	AIRCRAFT ENGINEERING &INSTALLATION SERVICES Inc.		FAA STC ST03416AT	B767-200/-300	Installation of C16221 LA03 Thales Integrated Standby Flight Display(ISFD) on the pilot's P1-3 panel, as a replacement for the altimeter,horizon and airspeed analog standby indicators.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 234-05-0014 Rev B dated march 05, 2007AFMS 234-05-1052 dated Rev IR march 26, 2007ICA 234-05-1051 Rev A dated October 10, 2006or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) U...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/05/2014	Active	10049097

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049106	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 1		AS 365 N3	Installation of the HELICOM V2 NUM embedded Equipment for HelicopterAS365 N3+The change consists of the installation ofa Flight Data Monitoringsystem described in the document capable of acquiring flight dataparameters to be transmitted and analyzed at the end of the flight.Rev. 1: STC holder nameS...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Lithium Battery Installation DatedFebruary 24th, 2014.The requirements for environmental protection and the associatedcertified noise and/...	N0-AS365 N3+ HV2 NUM-Design Organization Edit A, Rev.04, Dated May 8th, 2014.N2-AS365 N3+ HV2 NUM-Certification Program Edit A, Rev.04, Dated May8th, 2014.N3-AS365 N3+ HV2 NUM-Design Change Edit A Rev. 04, Dated, May 8th, 2014.N7-AS365 N3+ HV2 NUM-Installation Manual-Edit A Rev. 04, Dated May 8th, 201...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2020	Active	10049106
10049107	AEROSPACE RESOURCES, INC.		FAA STC SA03114CH	2. B200CGT, B300, B300C 2. B200, B200C, B200GT 1. B200T, B200CT 1. A200C, A200CT 1. A100-1, 200, 200C, 200T	Approval of Cargo Equipment Installation on Beechcraft KingAir 200 and300 Series Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Aerospace Resources Inc, Document Listref 20-0350-1DL, revision 1a, dated May 03, 2012.Operation in accordance with Aerospace Resources Inc, FAA ApprovedAirplane Flight Manual Supplement Document No 20-0200-1FMS, Revision 0,dated May 24, 2012, or.Aerospace Resources...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/05/2014	Active	10049107
10049114	DRF STIFTUNG LUFTRETTUNGGEMEINNUETZIGE AG			BO105 S, VARIANT: CBS-4	Title: Installation of multiple external and internal mountings for testequipment BO105Description: The mounting for external mission equipment is fixed at thenose of the helicopter. And two equipment racks are installed in thepassenger compartment for various test equipment.	CS 27 Amdt. 3:CS 27.1, CS 27.21, CS 27.25, CS 27.27, CS27.29, CS27.51, CS 27.71, CS27.75, CS 27.141<(>,<)>CS 27.143, CS27.173, CS 27.175, CS 27.177, CS 27.241, CS 27.251, CS27.301, CS 27.303<(>,<)>CS 27.305, CS 27.307, CS 27.337, CS 27.471, CS 27.561, CS 27.601, CS27.603, CS 27.605<(>,<)>CS 27.607,...	-Flight Manual Supplement, FMS 10-DRF-015 Supplement for Multipleexternal and internal mountings for test equipment BO105, Ausgabe 00dated 21st January 2014or later revisions of the above listed documents approved by EASA-Compliance Checklist, Project No 0495, Doc No CC-105-85-00-00001,Ausgabe 00 da...	CAT A Equivalent is not part of this approval.Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	13/05/2014	Active	10049114
10049146	IAC - INDUSTRIAS AERONAUTICAS DECOIMBRA, Lda.			2. 182R, R182, T182, TR182 2. 182M, 182N, 182P, 182Q, 2. 182H, 182J, 182K, 182L, 2. 182D, 182E, 182F, 182G, 2. 182, 182A, 182B, 182C, 1. 182S, 182T, T182T	Modification for skydiving operationIt includes the modification of the right door to open it upwards, theremoval of the co-pilot control wheel, and the introduction of aninstrument panel protection, a static line parachutes support, and aparachutist's platform fixed to the wheel nut and in the foot...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): SC-023-div-01 Parachuting ActivityThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	AFM Supplement For Parachuting Activities IAC-C182-AFMS ED 1or later revisions of the above listed documents approved by EASA.IAC.C182.MDL - Master Document List issue 3 06-05-2014FORM IAC21.001 Project Dossier issue 2 21-04-2014IAC-C182 Annex I - Manufacturing issue 1 20-11-2013IAC-C182 Annex II -I...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/05/2014	Active	10049146
10049148	RUAG AG	REV. 2		EC120B EC 120 B	Installation of Garmin GTN650 Navigation UnitThe initial issue defined the installation of Garmin GTN650 asreplacement for the Garmin GNS430 or GNS430W.Revision 1 additionally considers the installation of Garmin GTN650 asreplacement for the Trimble 2000 GPS and the Bendix/King KX 165 NAV/COMequipme...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS27 Amdt 3 paragraphs: 27.1, 27.29, 27.251, 27.301, 27.303, 27.305,27.307, 27.321, 27.337, 27.341, 27.561, 27.601, 27.603,...	Flight Manual Supplement, doc. ref. FMS-608681 Rev. H dtd. 19/11/2014Master Data List, doc. ref. MDL-8001602, Rev. F dtd. 19/11/2014Certification Compliance Sheet, doc. ref. CCS-8001591, Rev. F dtd. 19/11/2014Instructions for Continued Airworthiness, doc. ref. ICA-8001438, Rev. Cdtd. 11/11/2014.or la...	GPS use limited to VFRGPS approaches prohibitedObstacle andFuel data only for informationAn existing installation of Garmin GNS430/ GNS430W or of Trimble 2000 GPSand Bendix/King KX 165 NAV/COM equipment is a prerequisite for this STC.Priorto installation of this design change it must be determinedt...	18/01/2021	Active	10049148

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049153	NSE	REV. 1		AS 332 L, AS 332 L1	Installation of NVIS Lighting system in accordance with Airlift MOC.DO-332-33-101.The kit comprises installation of thecockpit, external, and cabinlights, with relative NVIS Lights Control Panel, as well as cockpitfilters.Revision 1: Transfer of certificate to new holder.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Airlift Flight Manual Supplement Part 1: FMS-332-33-101, Rev.1, dated08/05/2014.- Airlift Engineering Order EO-332-33-101-00-2384 Rev 1, “Installationof NVIS Kit,” dated 26/02/2014.- Airlift Certification Plan CP-332-33-101 Rev 0, dated 4/17/2013.- Airlift Instruction for Continued Airworthiness: IC...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Initial issue- Installation of NVIS Kit does not consti...	16/07/2025	Active	10049153
10049177	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC SA01676WI	SEE FAA AML	Modification of a Rockwell Collins, Inc. File Server Unit (FSU)Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Rockwell Collins, Inc. Drawing Index RCA-0342-001, Rev (-),dated 17February 2012, or later FAA approved revisions, as listed on theattached FAA Approved Model List (AML).	Prior approved installation of a Rockwell Collins, Inc. File Server Unit(FSU) is a prerequisite to this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will intro...	22/11/2018	Active	10049177
10049194	AERO DYNAMIX, Inc.	REV. 1	FAA STC SR09365RC	412EP	Installation of an NVIS/NVG compatible interior lighting system inaccordance with Aero Dynamix, Inc., Master Drawing List MDL 1845-01 Rev.BR dated 30/04/2014Rev. 1: Minor Change to STC adding a new configuration of ‘Installationof Night Vision Goggle Compatible Interior Lighting System’ by RFMSAppen...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List, MDL 1845-01, Rev. C, dated 28 February 2020.- STC Minor Change Classification EF410-20-105 (1-2HELI 412), dated 5February 2020.- Aero Dynamix Project Notification Letter to FAA, dated 5 February 2020with enclosed Design Change Proposal (6 pages), dated 5 February 2020.- FAA Fo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/03/2020	Active	10049194
10049196	EIRTECH AVIATION SERVICES LIMITED	REV. 2		B737-800	B737NG IFE Power Control / EASA DOA EASA.21J.452 major changeERT/CNG/ 465 - Activation of an IFE power isolation switch installed inthe P5 overhead panel installed per design change ERT/CNG/ 523. Theswitch allows the crew to isolate power tothe IFE system duringemergency conditions and provides a mea...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amdt.13; 25.1(a), 25.29(b), 25.601, 25.603 (a), 25.603(b),25.603(c), 25.611 (a), 25.611(b), 25.1301(a)(1), 25.1301(a)(3),25.1301(b), 25.1309(a)(2), 25.1322(e)(1)(iii),...	Eirtech Aviation Services Ltd Change ERT/465, Master Document ListMDL/ 465-099 Issue 5, Service Bulletin ERT-SB-415 Issue 3, ERT-SB-533Issue 2, FCOM Supplement FCOM/ 465-005 Issue 4, Maintenance ManualSupplement MMS/ 465-012 Issue 2, Maintenance Manual SupplementMMS/465-013 Issue 2or later revisions of...	Applicable to B737-800 with Rockwell Collins IFE STC SA5135NM installedand B737-86J/-8Q8/-86N/-85F	18/05/2015	Active	10049196
10049198	A & C PRODUCTS		FAA STC11066SC	737-700	Installation of motorized window shades	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25 change 15: 25.561, 25.811, 25.853, 25.1309The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original p...	Master Data List 737-100-01 DL, Revision EInstructions for Continued Airworthiness document number AC3711SI,Revision IRor later revisions of the above listed documents approved byEASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Imple...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/05/2014	Active	10049198

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049203	JET AVIATION ST. LOUIS, Inc.	REV. 1	FAA STC ST01632WI	CL-600-2B16	Activation of the Wireless Fidelity (WiFi) capabilities of previouslyinstalled router(s) and Aircraft Transmitting Portable ElectronicDevices (T-PEDs) Tolerance Testing	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST01632WI dated 01 July 2011.3S Certification, Master Data List (MDL) 058-2325-L01-00, Revision IR,dated 30June 2011.3S Certification, Aircraft Flight Manual Supplement (AFMS)058-2325-A01-00 Revision IR, dated 30 June 2011.or later revisions of the above listed documents approved by EAS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	30/03/2015	Active	10049203
10049204	FEDEX EXPRESS CORP.		FAA STC SA7447SW	727-100C, 727-200F	Modifications of the Unit Loads Devices (ULD) configurations:-B727-100C: from eight ULD to nine ULD-B727-200F: from eleven ULD to twelve ULD	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	B727-100C: Dee Howard Co. Master Drawing Lists 90-001 and 90-002 datedJune 16, 1988B727-200F: Dee Howard Co. Master Drawing Lists 90-001, 900-002 and90-005 dated July 13, 1989or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequen...	This design change must be used with an approved retention systemdesigned to prevent ULD from shifting during flight.Prior to installation of this design change it must be determined thatthe interrelationship between this design change andany otherpreviously installed design change and/ or repair w...	20/05/2014	Active	10049204
10049206	FEDEX EXPRESS CORP.	REV. 1	FAA STC ST01691AT	727-100C, 727-200F	Installation of Expanded Parameter Flight Data Recorder	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Top Drawing number B27-31-081 Rev F dated 12 Sept, 2000Weight and balance supplement B27-31-086 dated 15 June 1998or later revisions of the above listed documents approved by EASAinaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementa...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/06/2014	Active	10049206
10049212	AEROTEC & CONCEPT			AS365 N3	MOD 13231 - CVFDR installation	CS29 Amdt 3The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement AE13231RFMS Issue 0, dated12/05/2014or later revisions of the above listed documents approved by EASA.Service Bulletin AE13231SB Issue 0, dated31/03/2014Instruction for Continuous Airworthiness AE13231ICA Issue 0, dated17/04/2014Master Data List AE13231MDL Issue...	S/N6636Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/05/2014	Active	10049212
10049235	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST01680SE	A320-212	Cabin Interior Modification	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25.365(e)(2) Change 14CS 25.853(a), (c), (d), (e) Amendment 1JAR 25.869 (a) (4) Change 14CS 25.981(a), (b) Amendment 1The requirements for environmental protection andc...	-Master Drawing List - AerCap A320 - Ex-Northwest Airlines to NouvelairInterior Reconfiguration, NAT document No. N0276-D10, Revision B, dated9 June 2006-Instructions for Continued Airworthiness - Continued AirworthinessAssessment for Interior Reconfiguration of AerCap A320 Aircraft, NATdocument No....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	21/05/2014	Active	10049235

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049248	INFLIGHT WARNING SYSTEMS, Inc.		FAA STC ST01820LA	747-400	Installation of a Fan Vibration Monitor Unit (VMU)Installation of Air Conditioning Fan Monitors to monitor bearingperformance for the prevention of smoke/odor/fumes into the aircraftcabin and flightdeck.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, document number 13358, Rev MMaster Drawing List, document number 212000, Rev ADInstructions for Continued Airworthiness (ICA), document number 13364,Rev B.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentt...	None.	22/05/2014	Active	10049248
10049249	ARMSTRONG AEROSPACE Inc.		FAA STC ST03284CH	A330-200, A330-300	Certification of Compatibility with Cellular and Wireless DataTechnologiesRefer also to Envoy Aerospace Certification Plan, DocumentE13084-2330-C001 rev -	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.1309(a) at CS amendment 225.1529 at CS amendment 2The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origin...	- MASTER DATA LIST : DC104-9377-00 rev - (Including the references tothe documents Aircraft Equipment List Ref DC370-9377-01 rev -, and refDC370-9377-02 rev -)- Certification Plan, Document E13084-2330-C001 rev -- FAA Letter, FAA Statementof Compliance, dated on 16th May 2014or later revisions of t...	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane installed base station using the cellularand/or wireless technologies is concurr...	22/05/2014	Active	10049249
10049255	JADE ENGINEERING PTE. LTD.			777-200	BL65 Seat Track installation and Floor Panel Modification	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.307(a) at Amdt 1425.625 (a)(b)(c) at Amdt 1425.853 (a) at Amdt 16The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	Master Drawing List JD-50AC02-1 Rev. NEW, dtd. 15 May 2014Declaration of Compliance Form JD4-F028, dtd. 22.May 2014or later revisions of the above listed documents approved by EASA	This STC replaces certain floor panel aluminum splice plates with newsplice plates made of 17-7PH TH1050 stainless steel and is approved asan Alternate Method of Compliance (AMOC) to paragraph (f) of EASAadopted FAA Airworthiness Directive(AD) 2005-18-10 for those spliceplates affected by this STC....	23/05/2014	Active	10049255
10049265	E A D AEROSPACE AIRWORTHINESS	REV. 1		B777-200	Installation of Emergency Locator Transmitter (ELT) Model ADT 406 AFfrom ELTA on B777-200 series aircraft.Revision 1 ofthis STC approval amends the limitations/conditions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List, EAD document 01429-EAS-A-MDL rev E- Airplane Flight Manual Supplement, EAD document 01429-EAS-A-AFM-01 revA- Instructions for Continuous Airworthiness, EAD document01429-EAS-A-ICA-01 rev Bor later revisions of the above listed documents approved by EASA.	1- Refer to §2.1 of relevant Airplane Flight Manual Supplement forapplicable operating limitations.2- Refer to §2 of relevant Instructions for Continuous Airworthiness forapplicable airworthiness limitations.Prior to installation of this design change it must be determined thatthe interrelationshipp...	03/11/2014	Active	10049265
10049267	AVIONITEC AG			DA 40	Exchange to dual GNS-430W & KN-62A DME InstallationOut: Garmin GNS-430 & GNC-255XL systemsIn: Dual Garmin GNS-430W & KN-62A systems	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval: CS 23 for the changeThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this c...	Master Document List No. 3802-017 Rev. 0 of 28.03.2014Instructions tor Continued Airworthiness No. 3802-017 Rev. 0 of28.03.2014AFMS No. 3802-017 Initial Issue of 28.03.2014or laterrevisions of the above listed documents approved by EASA.	S/N: 40043The approval holder shall fulfill the obligationsof Part 21 § 21 .A118Prior to installation of this modification it must be determined thatthe interrelationship betweenthis modification and any other previouslyinstalled modification and/ or repair will introduce no adverse effectupon the...	23/05/2014	Active	10049267

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049276	INFLIGHT CANADA Inc.		TCCA STC SA14-17 ISSUE 1	737-800	Cabin Reconfiguration:Installation of first class seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List MDL13167 Rev 1Flight Manual Supplement FMS13167 Rev 1Instructions for Continued Airworthiness ICA13167Weight and Balance Report WB13167 rev 1or later revisions ofthe above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilat...	Prerequisites to the installation of the design change related to thisSTC are:-Installation of FAA STC ST01829AT / EASASTC IM.A.S.02846 / TCCA STCSA99-206-Performance of Boeing SB 737-24-1147Prior to installation of this design change it must be determined thatthe interrelationship between this des...	26/05/2014	Active	10049276
10049283	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST03163NY	A340-541/-642 A340-311/-312/-313	Installation of a Panasonic Global Communications Suite Ku-Band Antenna.This modification consists in installing a Panasonic GlobalCommunication Suite (GCS) Ku-Band antenna, including the skirt, radome,adapter plate, attachment fittings, support structure and mounting ofthe KU-Band antenna.The Revis...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Refer to:- for A340-300 series, Project Results ref ODA-2315-04 Revision A, dated09 November 2015- for A340-500 series, Compliance Summary Report ref 6661-08703-2315 revE,...	Master Data List, ref : 0161-08333-2315, revision D, dated 27 October2015Instruction for Continued Airworthiness (including AirworthinessLimitations), ref : 0761-08335-2315 revision D, dated 30 September 2015Aircraft Flight Manual Supplement :-for A340-300 series, document ref : 0661-09700-2315, dat...	This STC does not activate the antenna; this is handled by the systeminstallation STC's. The only wiring part of this project is between theKU-Band antenna and the feed thru connectors. No wiring installed insidethe aircraft.Prior to installation of this design change it must be determined thatthe i...	09/12/2015	Active	10049283
10049285	ROCKWELL COLLINS, Inc.	REV. 1	FAA ST01712WI	SAAB SF340A, SAAB 340B	Installation of Rockwell Collins Attitude Heading Computer (AHC), typeAHC-3000A.This modification modifies the SAAB Attitude Heading Reference System(AHRS) by installing a Rockwell Collins AHC, type AHC-3000A, on SAABSF340A.The Revision 1 modifies the initial applicability by adding the SAAB340B air...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List, ref : RCA-0454 Revision B, dated 21 April 2014;-Instructions for Continued Airworthiness, ref : RCA-0446 Revision B,dated 21 April 2014;-FAA Airplane Flight Manual Supplement, ref : RCA-0453 Revision B,dated 21 April 2014;or later revisions of the above listed documents appr...	None.	14/03/2018	Active	10049285
10049307	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A, 525B, 525C	Installation of dual GPS/NAV/COMM Garmin GNS430/530(A)W	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amendment 223.307,365,561,575,603,607,611 ,613,671,867,1301,1309,1321,132 7,1351,1357,1365,1431,1529< (>,<)>1581,1585The requirements for environmental protection and t...	Flight Manual Supplement ASR-2011-59-FMS-05-00, Amendment 00or later revisions of the above listed documents approved by EASA.and-Instructions for Installation ASR-2011-59-IFI-10-00, Amendment 00-Instructions for Continued Airworthiness ASR-2011-59-ICA-11-00< (>,<)>Amendment 00	None.	27/05/2014	Active	10049307
10049309	JETAIRE AEROSPACE, LLC		FAA STC ST00387LA-D	B727-100/-200	Installation of provisions for smoke/fire detection/suppression system,lower cargo compartments.Installation of active smoke/fire detection/suppression system, lowercargo compartments.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Hollingshead Master Data List No. 12061, Rev. C, dated July31, 1998<(>,<) >Airplane Flight Manual Supplement 2314-04, Rev. 2, dated September 8,1999or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision...	Applicability as per above mentioned Master Data List.Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the pr...	28/05/2014	Active	10049309

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049311	BALLONBAU WOERNER GmbH			NL-STU/840 NL-STU/640 NL-STU/510 NL-STU/1000	Ultramagic CT-01 and CT-02 bottom ends beneath NL-STU Series gasballoons	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	DE:- replacement pages for FM: NL-STU, Fahrt- und Betriebshandbuch, Seiten4, 5a, 10, 12, 13, 16, 20a, Ausgabe Mai 2014- Supplement FM: NL-STU, Fahrt- und Betriebshandbuch, Anhang 1,Ultramagic Tekno Korb, Ausgabe Mai 2014EN:- replacement pages for FM: NL-STU, Flight- and Instruction Manual,pages 4, 5...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/05/2014	Active	10049311
10049320	AVIATION COMPLETION INNOVATIONSINC.	REV. 1	FAA STC SR03007NY	AB139, AW139	- Configuration 1: Installation of two Class 2 Electronic Flight Bag(EFB) mounting device arm-mounted- Configuration 2:Installation of two Apple iPAD or iPAD 2 system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR03007NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Configuration 1: Air Concepts International, Inc. Installation DrawingList Nos. 41240-00-333-01 and 41240-00-333-04, Revision IR, dated 10July 2011.- Configuration 2: Air Concepts International, Inc. Installation DrawingList No. IL00139.08, Revision IR, dated 11 February 2011.- Modified Aircraft f...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/07/2019	Active	10049320
10049362	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	B757-200	20 Bed / 20BC/ 72YC Passenger Seat Configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	H4 Aerospace Modification Summary and Declaration of Compliance No. MODH4A1691 Issue 1 dated 01 June 2014.or later revisions of the above listed documents approved by EASA.	None.	02/06/2014	Active	10049362
10049367	HARTZELL PROPELLER LLC	REV. 1	FAA STC SA02414CH-D	M20E	Installation of the Hartzell propeller model HC-C2YR-1BFP/F7497 inaccordance with Hartzell STC Installation Instructions INST_011007.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Installation of the Hartzell propeller model HC-C2YR-1BFP/F7497 inaccordance with Hartzell STC Installation Instructions INST_011007,dated July 12, 2007;Aircraft Flight Manual Supplement, Hartzell document AFMS_011007_2,dated January 10, 2007;or later revisions of the above listed documents approved...	Limited to Model M20E.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	04/06/2014	Active	10049367
10049374	AMAC AEROSPACE SWITZERLAND AG			B737-700	Replacement of two 42" Monitors.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: D-10Glass Screens of Displays / MonitorsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product a...	Engineering Order EO-AS04-4420 rev C dated 14 April 2014or later revisions of the above listed documents approved by EASA.	None.	03/06/2014	Active	10049374
10049398	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST03224CH	737-700/-800/-900/-900ER 737-300/-400/-500/-600	Installation of ECS EZMount® Tablet Cradle assemblies on existingEZMount® Pivot installations:- configuration 1: Cradle(8.0" X 10.7") provisions- configuration 2: Cradle (8.5" X 11.2") provisions	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The applicant elected to comply to the following paragraphs at CS25amendment 0:25.29(b), 25.301(a)(b), 25.303,25.305(a)(b), 25.307(a), 25.561(b)(3)(c), 25.601, 25.603, 25....	Master Data List ECS-210512 Rev. F dated May 23,2013AFM Supplement ECS-210450 Rev. dated March 05,2013Instruction for Continued Airworthiness ECS-210451 Rev. B dated May 23,2013orlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequ...	- The equipment for which these provisions are intended hasnot beencertified. An additional approval is required for the installation ofthis equipment and must be evaluated to assure satisfactory compliancewith applicable airworthiness requirements.- EASA STC 10027270 (validating FAA STC ST02637CH)...	04/06/2014	Active	10049398

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049401	PMV ENGINEERING			757-200/-200PF/-300	Electronic Flight Bag (EFB) class 2 installation on Boeing 757-200This modification deals with the installation of a dual (Captain andFirst Officer) class 2 Electronic Flight Bag (EFB) system from CMCEsterline, on Boeing B757 Aircraft. Foreach side, this system iscomposed of a mount arm located onU...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, ref: AVI-00471-MDL-R02, dated 03 June2014Instruction for Continued Airworthiness, ref: AVI-00471-ICA-R00, dated18 February 2014Aircraft Flight Manual Supplement, ref: AVI-00471-AFMS-R01, dated 26March 2014or later revisions of the above listed documents approved by EASA	1. Operations: Refer to §2 of Aircraft Flight Manual Supplement, ref:AVI-00471-AFMS-R012. Airworthiness Limitations: Refer to §6 of Instruction for ContinuedAirworthiness, ref: AVI-00471-ICA-R00Prior to installation of this design change it must be determined thatthe interrelationship between this d...	04/06/2014	Active	10049401
10049407	AERODISA S.L.			737-300/-400/-500	Installation of GE AVIATION (SMITHS AEROSPACE - CHELTENHAM)Servoed MachAirspeed Indicators (SMASI).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List AED2014-10M_MDL rev A0Supplement to FCOM AED2014-10M_FCOMS Rev A0	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/06/2014	Active	10049407
10049411	JET AVIATION AG	REV. 2		737-700	Interior ReconfigurationA) The following items are removed from the forward R/H lounge area:1. 3x place divan (STA.480) 2. Side Ledge (STA.446 to STA.520)3. Side ledge mounted PullOut Table (STA. 500C)4. Coffee table and integrated emergency floor lighting (STA.495)5. Decor panels from the R/H bulkhe...	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:SCs or ESFs: Deviation CR1D-07-c for JAR-25.815, Width of AisleDerogation to latest amendment (Part21A.101): Do not materiallycontribute t...	Master Data List, Doc. No. JBSL-M-00084MDL-01, Issue 05Aircraft Flight Manual Supplement, Doc. No. JBSL-M-00084AFM-01, Issue 03Aircraft Flight Manual Supplement, Doc. No. JBSL-M-00084AFM-02, Issue03Instructions for Continued Airworthiness, Doc. No. JBSL-M-00084ICA-01,Issue 02Or later revisions of t...	The following modifications are prerequisite to this STC:Lufthansa Technik STC LBA.21E2.TA0307Lufthansa Technik STC 10014593.Prior to installation of this modification it must be determined thatthe interrelationship between this modification and any other previouslyinstalled modification and/ or rep...	05/07/2021	Active	10049411
10049432	SABENA TECHNICS BGC			A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	LATVISION Cockpit Door Surveillance System (CDSS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, Aeroconseil document No. 0709-01-A-2103,Revision 0,6 March 2014-Instructions for Continued Airworthiness, Aeroconseil document No.0709-01-A-2211, Revision 0, 13 March 2014-Aircraft Flight Manual Supplement, Aeroconseil document No. 0709-01-A-2301<(>,<)> Revision 1, dated 27 May 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	06/06/2014	Active	10049432
10049448	AVIATION COMPLETION INNOVATIONSINC.	REV. 1	FAA STC SR02753NY	AB139, AW139	Installation of SAGEM Avionics, Inc. ICDS-10 Multi Functions Display	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02753NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Air Concepts International Inc., Installation Drawing List No.41008-103-00-INS, Revision IR, dated 6 November 2007.- Air Concepts International, Inc., Instructions for ContinuedAirworthiness, Report No. IC00139.06, Revision IR, dated 15 November2009, FAA accepted 12 March 2010.- Air Concepts Inter...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/07/2019	Active	10049448

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049449	ROCKWELL COLLINS, Inc.		FAA STC SA01684WI	3- P.180 2- B200, B200C, B300, B300C 1- 525, 525A, 525B, 525C	Installation of Rockwell Collins, Inc. Aircraft InformationManagement(AIM) System in defined Part 23 Aircraft.	Certification basis as defined in FAA STC SA01684WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	To be installed as defined in documents:-,,RCA - 0408 rev.A(for Cessna models);-,,RCA - 0409 rev.A (for Beechcraft B200 and B200C);-,,RCA - 0385 rev.A (for Beechcraft B300 and B300C);-,,RCA - 0405 rev.A (for Piaggio P. 180);No AFM Supplements have been produced for this STCTo be maintained in accord...	None.	06/06/2014	Active	10049449
10049460	DART AEROSPACE USA, Inc.		FAA STC SR02258SE	2. 206L-1, 206L-3, 206L-4 2. 206A, 206B, 206L, 407 1. A119, AW109SP, AW119MKII 1. A109E, A109K2, A109S 1. A109, A109A, A109AII, A109C	D-119-827 Tail Rotor Pedal Lockout	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Airworthiness Compliance Report ACR-D119-827-1, Rev. C-Master Document List MDL-D119-827, Rev. F-Installation Instructions IIN-D119-827, Rev. D-Instructions for Continued Airworthiness ICA-D119-827, Rev. 2 &ICA-D407-827, Rev. 0	None	10/06/2014	Active	10049460
10049462	AVIONIK STRAUBING ENTWICKLUNGS GmbH			S-76A, S-76B, S-76C	Removal of Flight Management System Universal UNS-1A and Installation ofWAAS Flight Management System Universal UNS-1Lw	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement ASR-2010-059-FMS-05-01, dated 01/04/14or later revisions of the above listed documents approved by EASAMaster Documents List ASR-2010-059-MDL-01-02, dated01/04/14	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/06/2014	Active	10049462
10049468	EICHELSDOERFER GmbHFLUGZEUGBAU			AS-K 13	Optionale Erhöhung der maximalen Abflugmasse / Optional increase ofMaximum Mass	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Beschreibung des Verfahrens zur Erhöhung der Max. Abflugmasse / Description of the procedure for the increase of the max. mass-Handschriftliche Überarbeitung des Flug- und Betriebshandbuchs für dasSegelflugzeug AS-K 13 / Handwritten Revision of the Flight and ServiceManual for the Sailplane AS-K 13o...	Limitations:The increase of the max. mass is limited by:1) The max. mass of the non-lifting parts defined in the TCDS.2) Increase of the max. 5% of the MTOW due to the difference of therequirements BVS and LFS.Conditions:The sailplane mustbe in good technical conditions and fulfill therequirement o...	11/06/2014	Active	10049468
10049473 (EASA.R.S.01504)	NSE INDUSTRIES S.A.	REV. 3		AS355F1, AS355F2, AS355N	AS355 NVIS Lighting SystemInstallation of NVIS Lighting System P/N 45A-1000-V02, defined inMDL-45A-1000-V02, or P/N 45B-1000-V02, defined in MDL-45B-1000-V02 toenable operation with Night Vision Goggles.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement RFMS-45AB-1000-V02 Rev. 02or later revisions of the above listed documents approved by EASA.-AS355 NVIS Lighting System Certification Plan - PCERT-45AB-1000-V02Rev. 03-AS355 NVIS STC Data List - SDL-45AB-1000-V02 Rev. 05-AS355 VA NVIS Master Drawing List - MDL-45...	The first installation of this kit must be supervised by the STC holderThis rotorcraft employs Night Vision Imaging System lighting (NVIS) thathas been certified to ensure the aircraft is compatible with nightvision goggles (NVG). For thisreason modifications that add or changesystems that emit ort...	22/12/2014	Active	10049473
10049475	APTOZ EHF.	REV. 1		757-200	Navigation - Independent Position Determining - Software Update orReplacement of the ACSS TCAS 2000 Computer to Comply with the TCASChange 7.1 RequirementsRev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Change/Repair Approval, Icelandair document No. CRA-757-3440-59,Revision B, dated 3 June 2014-Continued Airworthiness Instructions, Icelandair document No.CAI-757-3440-59, Revision A, dated 3 June 2014-Aircraft Flight Manual Supplement, Icelandair document No.AFM-757-3440-59, Revision A, dated 3 Ju...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10049475

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049476	SAFRAN SEATS	REV. 1		A330-343	Modification to the aircraft seat installed on Airbus A330-343	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 6, paragraphs variousThe requirements for environmental protection and the associatedcertifiednoise and/ or emissions levels of the original product areun...	Master Data List C1145MDL, Issue 1 dated 29 May 2014or later revisions of the above listed documents approved by EASA	Aircraft Serial Numbers: 1195, 1201, 1206, 1215, 1231, 1296, 1315, 1329,1341 and 1352 onlyPrior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse eff...	12/03/2019	Active	10049476
10049479	H4 AEROSPACE (UK) Ltd.	REV. 3	CAA UK RESPONSIBILITY	ALL	Installation of LED washlights	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	H4 Aerospace Modification Summary and Declaration of Compliance No. MODH4A1705 Issue 10, dated 21 June 2017	Prior to the installation of the new LED Wash Lights on aircraftequipped with a photo-luminescent floor path marking system, an analysisand/or test is required to be performed considering the impact of theinstallation on the charging capabilities of the floor path markingsystem.	11/07/2017	Active	10049479
10049481	LUFTHANSA TECHNIK AG	REV. 1		A330-200	A330-200 new model pax seats and LD-MCR1. Exchange of 285 pax 2-class seating with 275 pax 2-class seating. Newseat models Thompson Vantage (22 B/C) and ZIM Eco 01 (253 Y/C).2. Integration of Lower Deck Mobile Crew Rest (LD-MCR) containerincluding staircase and secondary escape path (hatch).3. Assoc...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD25-13/33M issue2 rev 0- ICA, ref A-00-14/16-ICA, Issue 1 rev 1- ComplianceRecord List CRL25-13/33M iss 2 rev 0or later revisions of the above listed documents approved by EASA	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2) This modification must be installed in con...	16/07/2014	Active	10049481
10049493	SOCIETE AIR FRANCE S.A.			777-200	B772 BEST Cabin reconfiguration [Installation of Zodiac SeatFrance Business class (Cirrus) and Economicclass seats (Z301). Modification of B/E Aerospace Premium Economic classseats. Installation of new partitions and stowage as well asmodification of existing galleys, lavatories<(>,<)> partitions an...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):-CRI D-02 (Single Side FacingSeats)-CRI D-03 (Seats with Inflatable Restraints)The requirements for environmental protection and the associatedcertif...	-Change Approval Sheet, Air France document No. CAS-B777-12-008,Revision 0<(>,<)> dated 11 June 2014-Aircraft Maintenance Manual Supplement, Air France document No.AMMS-B777-12-008-001, Revision 0, dated 18 April 2014or later revisions of the above listed documents approved by EASA	None	13/06/2014	Active	10049493
10049498	AEROTEC & CONCEPT			FALCON 10	EGPWS Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS Initial Issue, Subpart E, Section 1, TAWSThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original p...	AFM Supplement ref. AE14029AFMS issue 0, dated 23/04/2014.Master Data List ref. AE14029MDL issue 2, dated 11/06/2014.orlater revisions of the above listed documents approved by EASA	Applicable to Falcon 10 model, S/N 155.	13/06/2014	Active	10049498
10049505	UMLAUT ENGINEERING GMBH	REV. 2		A330-223 A330-200	A330-223 Cabin Layout ConversionThe change contains a modification of a A330 cabin after selling tospecific layout of anew operator. The change comprises: Seatreplacement, Floor covering, PSU Layout, Bar removal, Relocation ofstarlight, installation of overhead Bins, Stowage's and Linings(Configura...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Configuration 1:P3 Voith Aerospace Master Document List P3V-100021-MDL-0001-A, InitialIssueP3 Voith Aerospace Instructions for Continued AirworthinessP3V-100021-ICA-0001-A, Initial IssueConfiguration 2:Umlaut Master Document List UM-AAK01-MDL-0001Umlaut Aircraft Flight Manual Supplement (AFMS) UM-AA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Refer also to ICA document ref P3V-100021-ICA-00...	19/01/2021	Active	10049505

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049507	AERODATA AG			B300	Installation of Aerodata Advanced Flight Inspection System"AD-AFIS-0113".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amdt. 3 elected to comply with, except 23.561 and 23.785 (kept FAR23.561 Amdt. 34 and FAR 23.785 Amdt. 34)The requirements for environmental protection and the assoc...	Installation of Aerodata Advanced Flight Inspection System"AD-AFIS-0113" in accordance with Aerodata document MDL-A/C-855, atrevision 0, dated March 25, 2014Aircraft Flight ManualSupplement, Aerodata document AFM-143, atrevision 0or laterrevisions of the above listed documents approved by EASAirc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/06/2014	Active	10049507
10049522	AEROTEC & CONCEPT			PA 46-310P	MOD 13120 - Installation PFD EFD1000PRO/GTN650	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AE13120ICA Rev. 0 dated 28 Aug 2013AE13120MDL Master Data List Rev. 1 dated 17 Oct 2013AE13120SMV EFD 1000 Rev. 0 dated28 Aug 2013AE13120SMV GTN 650 Rev. 0 dated 28 Aug 2013or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/06/2014	Active	10049522
10049524	LUFTHANSA TECHNIK AG	REV. 5		A321-211, A321-231 A320-271N, A321-111, A321-131 A320-211, A320-214, A320-216 A319-112, A319-114, A319-132	Activation of Wireless IFE System Board Connect.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Configuration 1 - Supplemental Type Definition DocumentSTDD23-12/32M Issue 1 Rev.2, dated 07/08/2014; - Compliance Record List CRL23-13/32M Issue 1 Rev.2, dated11/02/2015; - Instruction for Continued Airworthiness A-00-14/02-ICA Issue 1Rev. 1, dated 08/05/2014; - Airplane Flight Ma...	The following Minor Changes approved by Lufthansa Technik with the belowreferenced documents shall be embodied on the aircraft prior to theinstallation of the subject design change for:- Configuration 1: CRAS MX-4997 at the latest revisionfor A321-231- Configuration 2: CRAS MX-5459 at the latest re...	28/11/2017	Active	10049524
10049566	AAR CARGO SYSTEMS		FAA STC ST01859CH	MD-11F	Main Deck Cargo Handling System (FAA STC No. ST01859CH)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AAR Report 1582 Revision A, July 1st, 2003 - Drawing List ReportAAR Report 1588 Issue 2, November 5th, 2013 - Instructions forContinued AirworthinessAAR Report 1591 Revision -,May 1st, 2003 - Weight and Balance Reportor later revisionsof the above listed documents approved by EASA inaccordancet...	This STC is only applicable for the model MD-11F.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product...	20/06/2014	Active	10049566
10049569	PROTOPLANE SPECIAL MISSION AIRCRAFT			BN2A-21, BN2B-21	Video system installation consisting of racks and transmitter mast	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR-23, Amdt. 1 to 23:23.21; 23.29; 23.143; 23.147; 23.301; 23.303; 23.305; 23.337; 23.341;23.561; 23.601; 23.603; 23.605; 23.625; 23.1301; 23.1309; 23.1357;23.1365; 23.15...	PP-030-AFM-03 Supplement to Aircraft Flight Manual, issue 3, dated02/05/14PP-030-MDL-05 Master Data List, issue 5, dated 02/05/14PP-030-SA-03 Structural Analysis<(>,<)> issue 3, dated 05/11/13PP-030-ESR-01 Exterior Safety Report, issue 1, dated 05/11/13PP-030-GTR-03 Ground Test Report, issue 3, date...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/06/2014	Active	10049569

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049573	DUNLOP AIRCRAFT TYRES LIMITED		CAA UK RESPONSIBILITY	CL-600-2E25 (CRJ-1000)	STC of new Dunlop Tyre on CRJ-1000	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dunlop Aircraft Tyres Master Document List No. DATL PR 10 MDL Rev Adated 12 May 2014or later revisions of the above listed documents approved by EASA	None	20/06/2014	Active	10049573
10049574	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	A321-231, A321-232 A321-211, A321-212, A321-213	Galley in A321-200 for Thomas Cook	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AIM Aviation (Henshalls) Ltd Modification No. HEN 1280 Issue 1or later revisions of the above listed documents approvedby EASA	None	20/06/2014	Active	10049574
10049581	NORTHERN AVIONICS S.R.L.			AW109SP	NAV 483 "Installation of Helicopter Emergency Egress Light (HEEL)system"	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFMS NAV 483, Rev. 0or later revisions of the above listed documents approved by EASA.Modification Bulletin NAV-483, Rev. 0Installation Instructions II-NAV-483-1R0, Part AInstallation Instructions II-NAV-483-2R0, Part BInstallation for Continuous Airworthiness ICA NAV-483, Rev. 0	None	20/06/2014	Active	10049581
10049604	S4A SOLUTIONS FOR AVIATION, S.L.			F172L, F172M, F172N. 172L, 172M, 172N,	Installation of banner towing hook TOST E85	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI O-11 Banner towingThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original produc...	- Installation in accordance with: Boletín de Servicio, ref:17201-SB001, dated October 30, 2013.- Operation in accordance with: Flight Manual Supplement, ref.17201-HDK01, edition 4, dated 5 June 2014.- Instructions for Continued Airworthiness in accordance with:Suplemento al manual de mantenimiento,...	-As per the limitations section of the Flight Manual Supplement, ref.17201-HDK01, edition 4, dated 5 June 2014,,,,-Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair wil...	23/06/2014	Active	10049604
10049605	BEECHCRAFT CORPORATION		FAA ST02506AT	400A	Installation of an Increased Ampere-Hour Recombinant Gas (RG) Lead AcidBattery.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Raytheon Aircraft Services Inc MasterDrawing List MDL-RAF01105, dated September 5, 2001.Instructions for Continued Airworthiness in accordance withRaytheonAircraft Services document "Instructions for Continued airworthiness forRaytheon Aircraft Services, Inc Installa...	Aircraft Serial RK-98 and subsequent.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	23/06/2014	Active	10049605
10049616	AVIONIK STRAUBING ENTWICKLUNGS GmbH			EC 135 T2, EC 135 T2+ EC 135 P2+, EC 135 T1 EC 135 P1, EC 135 P2	Installation of Garmin GTN650 and GTN750	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27 Amdt 3: 305 (a)(b), 561 (a)(b), 603(a)(b)(c), 605, 607, 609(a),610, 611, 613(a), 671(a)(b), 771(a)(b)(c), 773(a), 777(a)(b), 863,1301(a)(b)(c)(d), 1303(a), (b), (c),...	Rotorcraft Flight Manual Supplement ASR-2012-043-FMS-05-00,Dated17/06/2014or later revisions of the above listed documents approved by EASA.-Master Drawing List ASR-2012-043-MDL-01-01, Rev 01, dated 17/06/2014-Instructions for Continued Airworthiness ASR-2012-043-ICA-11-01, Amdt1, dated 07/08/2013...	None	24/06/2014	Active	10049616

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049617	SCANDINAVIAN AVIONICS DESIGN ApS			2. B200, B200C, B300, B300C 1. 200, 200C, 300, 300LW	Installation of Dual GARMIN GTX 33D Transponder System for Mode S ELS / EHS / ADS-B	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amdt.3:23.1, 23.29, 23.301, 23.303,23.305, 23.307, 23.601, 23.603, 23.605,23.609, 23.611, 23.613, 23.625, 23.771, 23.773, 23.853, 23.863, 23.867,23.1301, 23.1303, 2...	EASA approved Engineering Order, Doc. No. 2087300-EO, Issue1, dated23-May-2014EASA approved Aircraft Flight Manual Supplement, Doc. No. 2087300-AM<(>,<)> Initial Issue 1, dated 11-Feb-2014<(>,<)>or later revisions of the above listed documents approved by EASAApproved Instructions for Continued Air...	None	24/06/2014	Active	10049617
10049624	VOYAGEUR AVIATION CORP.		TCCA O-LSA14-027/D	DHC-8-202	TCAS II Version 7.1 / Mode S Transponder Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with TCCA approved Avionics DesignServices Ltd. Master Drawing List MDL13068, Revision N/C.Operation must be in accordance with TCCA approved Voyager AirwaysLimited Flight Manual Supplement FMS13068-1, Revision N/C.Maintenance must be performed in accordance with T...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/06/2014	Active	10049624
10049626	ROEDER PRAEZISION GMBH	REV. 1		A320-232	Galley G5 and Lavatory D installation. (Removal of galley G4, lavatory F, partition L4 and cabin attendantseat. Installation of new/refurbished galley G5, lavatory D and 2 cabinattendant seats. Modification of complete aft galley / entry area toadapt for these installations. Modification of structura...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List, AirBerlin Technik document No.A320-MDL25-06-2014, Revision 4, 23 June 2014;-Instructions for Continued Airworthiness, AirBerlin Technik documentNo. A320-ICA25-06-2014, Revision 1, 20 June 2014;or later revisions of the above listed documents approved by EASA.	Limited to MSN 2587.	15/06/2018	Active	10049626
10049629	AIRBUS TRANSPORT INTERNATIONAL SNC	REV. 1		A300F4-608ST	Auxiliary Fin Tip reengineering update.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Auxiliary Fin Tip Major Change ST55MOD007 issue 4 dated 25/06/2015 orlater revisions approved by EASA.	None	08/07/2015	Active	10049629
10049644	SKYTRAC SYSTEMS LTD.		TCCA STC SA12-45	DHC-8-401, DHC-8-402 DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103	SkyTrac Flight Following/ SATCOM System Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI F-01 Annex - Lithium Battery InstallationThe requirements for environmental protection and the associatedcertified noise and/ or emissions levelsu...	Installation must be in accordance with TCCA approved Avionics DesignServices Ltd Master Drawing List MDL 11063, Revision B.Operation must be performed in accordance with TCCA approved SkyTracSystems Ltd. Airplane Flight Manual Supplement FMS 11063-1, Revision B.Maintenance must be performed in acco...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/06/2014	Active	10049644
10049665	FOKKER SERVICES B.V.			737-500 737-400 737-300	Upgrade TCAS 7.0 (TPA 81A) to 7.1 (TPA 100B) on Boeing 737	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan CP-0223 Issue 1Compliance Record Report CRR-0223 Issueor later revisions of the above listed documents approved by EASA.	Approval is limited to EFIS equipped aeroplanes.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	27/06/2014	Active	10049665

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049666	FOKKER SERVICES B.V.			737-900, 737-900ER 737-700, 737-800 737-400, 737-500, 737-600 737-200, 737-200C, 737-300	CPDLC (Controller Pilot Data Link Communication) in the Boeing 737	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plans: CP-0212 Issue 3, CP-213 Issue 1, CP-0219 Issue 2Compliance Record Reports: CRR-0212 Issue 1, CRR-0213 Issue 1, CRR-0219Issue 1SE-779 Issue 1: Boeing 737 Classic - GPS antenna ICA Supplement733-EXS-AFM-S-001 Revision 1:AFM Supplement 737 Classic738-EXS-AFM-S-001 Revision 1: AFMo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/06/2014	Active	10049666
10049672	AVIATION COMPLETION INNOVATIONSINC.	REV. 2	FAA STC SR02325NY	AB139, AW139	Installation of Cabin Interior Sound Reduction Wall Panels System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02325NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Air Concepts International, LLC Installation Drawing List Report31021-314-INS, Revision E, dated 9 March 2010.Configuration 1, 2, & 3: IAW Installation Instructions, ReportIM00139.02, Revision B, dated 9 March 2010.- Configuration 1 Left Side Sliding Door, Left Side Only- Configuration 2 Right Sid...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/06/2019	Active	10049672
10049685	AERO TWIN, Inc.		FAA ST02559AK	C-212-CE, C-212-CF, C-212-DF. C-212-CB, C-212-CC, C-212-CD,	"CASA 212 Exhaust Deflectors".Installation of Aero Twin, Inc. CASA 212 Exhaust Deflectors, part numberAT-CASA-EXDF-1001in accordance with Aero Twin, Inc. Master Data ListNo. AT-CASA-EXDF-MDL, Original Issue, dated June 22, 2010, or later FAAapproved revision. This is an approximately 12" stainlessd...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cap. 2.0 "Airworthiness Limitations" contained in Doc."Instructions for Continued Airworthiness No. CASA-212-EXDF-ICA",Original Issue, dated June 25, 2010 ; or later revisions of the abovelisted documents approved by EASA in accordance with EASA ED Decision2004/04/ CF (or subsequent revisions of this...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/06/2014	Active	10049685
10049690	VERO BEACH AVIONICS, INC.		FAA SA04005AT	PA-46-500TP PA-46-350P, PA-46-350T	Installation of Garmin GSR 56 System / This STC installs Garmin GSR 56System which provides Iridium Satellite SATCOM phone service, SMS TextMessaging and World Wide Weather Service. The system is integrated intothe Garmin G1000 EFIS and interfaces with the aircraft audio panel.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Maintenance shall be accomplished in accordance with Avionics SupportGroup Instructions for Continued Airworthiness 212145-ICA, Rev. CThe system should be installed in accordacne with MDL-A2012-035-1, Rev.Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED De...	Installation is limited to aircraft with the Garmin G1000 EFIS.This approval should not be extended to other aircraft of this model onwhich other previously approved modifications are incorporated, unlessit is determined by the installer that the interrelationship betweenthis change and any other p...	30/06/2014	Active	10049690
10049694	PMV ENGINEERING			767-300F, 767-400ER. 767-200, 767-300,	Electronic Flight Bag (EFB) class 2 installation on Boeing 767This modification deals with the installation of a dual (Captain andFirst Officer) class 2 Electronic Flight Bag (EFB) system from CMCEsterline, on Boeing B767 Aircraft. For each side, this system iscomposed of a mount arm located on wind...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, ref : AVI-00530-MDL-R07Instruction for Continued Airworthiness, ref : AVI-00530-ICA-R00Aircraft Flight Manual Supplement, ref : AVI-00530-AFMS-R02or later revisions of the above listed documents approved by EASA.	1 - Operations: Refer to §2 of Aircraft Flight Manual Supplement, ref :AVI-00530-AFMS-R022 - Airworthiness Limitations:Refer to §6 of Instruction for ContinuedAirworthiness, ref : AVI-00530-ICA-R00Prior to installation of this design change it must be determined thatthe interrelationship between th...	30/06/2014	Active	10049694

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049699	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A320-232	Cabin Interior Modification on British Airways A320-232 Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: JAR 25 Change 13 25.562(a),(b) & (c) ; 25.853 (a),(b) & (c).The requirements for environmental protection and the associa...	Master Drawing List, Interior Reconfiguration on British Airways A320-232 aircraft, N0460-D10 Rev. B dated 29 June 2014;or later revisions of the above listed documents approved by EASA.	British Airways Service Bulletin SB A320-25-0040 must be installed atthe same time as this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadver...	01/07/2014	Active	10049699
10049703	BOMBARDIER INC.		TCCA C-LSA03-341/D	BD-700-1A10	Aircraft Completion, 8 / 10 passenger interior configuration - EASAvalidation of Transport Canada STC C-LSA03-341/D at issue 1	The Certification Basis for the original product as amendedby thefollowingadditional or alternative airworthiness requirements:Deviation(s): EASA Deviation CRI D-100 at issue 3 "Doors betweenpassenger compartments" andEASA Deviation CRI D-300 at issue 3 "Passenger information signs".The requirement...	Modification to be completed in accordance with Aero Consulting ServicesModification Data Summary D42400 Revision A dated 16th June 2014Required Flight Manual Supplements:- G-FM24000040 rev N/C - Cabin master power switch- G-FM25000061 revN/C - Interior completion- G-FM25100007 rev N/C - Flight cre...	- This STC is limited to aircraft serial number 9110.- Refer to the required Flight Manual Supplements and AirworthinessLimitations Supplements listed in associated technical documentation.- Bombardier Service Bulletin 700-31-018 (Modification - IntegratedAvionics Computers (IAC) - Avionics 2001 Bat...	01/07/2014	Active	10049703
10049704	BOMBARDIER INC.		TCCA C-LSA03-394/D	BD-700-1A10	Modifications to Heads Up Technologies CMS-400 Checklist ManagementSystem:- EASA validation of Transport Canada STC C-LSA03-394/D at issue 1.- Modification to be completed in accordance with Aero ConsultingServicesModification Data SummaryD606000 revision N/C or later approvedrevisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero Consulting Services Modification Data Summary D606000 revision N/C,and Flight Manual Supplement G-FM31200002 revision A "Checklistmanagement system"or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral A...	- This STC installation is limited to aircraft serial number 9110.- Refer to the "Limitations" sections of the EASA approved Flight ManualSupplement G-FM31200002 revision A, or later approved revisions.- Previous installation of CMS-400 Checklist Management System inaccordance with Transport Canadau...	01/07/2014	Active	10049704
10049705	DOA AESGLOBAL LIMITED	REV. 1		A321-231, A321-232 A321-211, A321-212, A321-213,	Activation of Rockwell Collins dPaves IFE SystemRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: JAR 25 Change 11, Para25.561, CS 25 Amendment 4, CS 25.29, CS25.301, CS 25.303, CS 25.305, CS25.307, CS 25.581, CS 25.601...	Modification AES-321-3008, Issue 2 dated 28 June 2014MasterData List AES-321-3008MDL, Issue 2 dated 28 June 2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2021	Active	10049705
10049719	HAECO CABIN SOLUTIONS L.L.C.		FAA STC ST11153SC	767-300	Installation of a new passenger seating configuration with inflightentertainment and in-seat power system	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amendment 13:25.23(b), 25.29, 25.301, 25.303,25.305(a)(b), 25.307(a), 25.341(a),25.561, 25.601, 25.603, 25.605, 25.607, 25.609, 25.611 (a), 25.613,25.619, 52.625, 25....	Weight report 1238S25S01 issue IRInstructions for ContinuedAirworthiness ICA-PA-13-022 rev OrigInstructions for Continued Airworthiness-EWIS ICA-PA-13-022-1 rev OrigFlight Manual Supplement 1238S25S03 Issue IROr later revisions of the above listed documents approved by EASA inaccordance with EASAt...	None	02/07/2014	Active	10049719
10049737	AVIATION COMPLETION INNOVATIONSINC.	REV. 1	FAA STC SR02751NY	AB139, AW139	- Configuration 1: Installation of Max-Viz, Inc. Enhanced Vision System (EVS) Model 1500 in accordance with Air Concepts International Inc. Installation Drawing List No. 31110-804-INS, Revision B, dated 1 August 2009 (Retractable Mount).- Configuration 2: Installation of Max-Viz, Inc. Enhanced Visio...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02751NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Rotorcraft Flight Manual Supplements:- Configuration 1: AirConcepts International, Inc. Rotorcraft FlightManual Supplement No. 00139.5< (>,<)> Revision A, FAA approved 12 July2011.- Configuration 2: Air Concepts International, Inc. Rotorcraft FlightManual Supplement No. 00139.5-1, Revision A, FAA ap...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/07/2019	Active	10049737

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049739	ROCKWELL COLLINS, Inc.		FAA STC ST01713WI	EMB-120FC, EMB-120QC EMB-120, EMB-120RT, EMB-120ER	Modification of a Rockwell Collins, Inc. AHC-85( ) (AHRS) installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC ST01713WI, issue October 11, 2013	None.	07/07/2014	Active	10049739
10049763	SWS CERTIFICATION SERVICES Ltd.	REV. 1	CAA UK RESPONSIBILITY	787-9	ANZ 787-9 Skycouch Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration SchemeNo.3106-MCS-01 Issue 1or later revisions of the above listed documents approved by EASA.	Skycouch can only be used as a sleeping area or as an accommodationarea, as detailed in SWS Certification Services Ltd Design Report, 3106-DR-01 during in-flight conditions.	07/07/2014	Active	10049763
10049767	DART AEROSPACE USA, Inc.	REV. 1	FAA STC SR02253SE	3- BELL 206L-3, L-4, 407 3- BELL 206A, A-1, B, L, L-1 2- AS355 E, F, F1, F2, N 1- AS350 B, B1, B2, B3, BA, D	Crosstube Antenna Mount Kit for AS350/355 and Bell 206/407 ModelsThe Crosstube Antenna Mounting Kit described in DART Aerospace MasterDocument List GA202 is used to install antennas on the LH/RH on the fwdor aft crosstubes of the AS350/355and Bell 206/407 rotorcraft. Thepurpose of the Revision 1 of...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List GA202 AS350/355, Bell 206/407, Rev. B,dated July12, 2013.Installation Instructions GA202-1 for AS350/355 models, Rev. A, datedMay 15th, 2013.Installation Instructions GA202-2 for Bell 206/407 models, Rev. A, datedMay 15th, 2013.Instructions for Continued Airworthiness ICA202-1R...	Maximum four kits can be installed on each aircraft.The Kitmust be installed in accordance with Installation InstructionsGA202-1 for AS350/355 models and or in accordance with InstallationInstructions GA202-2 for Bell 206/407 models.Priorto installation of this design change it must be determinedt...	10/07/2014	Active	10049767
10049772	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A	Installation of Flight Management SystemUniversal UNS-1Lw	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 2 (not required by 21A.101)301<(>,<)> 303<(>,<)> 305<(>,<)> 307<(>,<)> 365<(>,<)> 561<(>,<)> 571<(>,<)> 575<(>,<)> 603<(>,<)> 605<(>,<)> 607<(>,<)> 609<(>...	Flight Manual Supplement ASR-2011-064-FMS-05-00 Rev. 00or later revisions of the above listed documents approved by EASA.-Instructions for Installation ASR-2011-064-IFI-10-00 Rev. 00or later approved revisions-Instructions for Continued Airworthiness ASR-2011-064-ICA-11-00 Rev. 00or later approved...	A Collins Proline 21 Avionics System - as specified in chapter 2 of theInstructions for Installation (ASR-2011-064-IFI-10-00) - must have beenalready installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprevious...	07/07/2014	Active	10049772
10049776	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR02758NY	BELL 407	Cargo Shelf Kit 407-260-001 for Bell Model 407Installation of a cargo shelf in the aft fuselage behind the baggagecompartment in accordance with Bell Helicopter Drawing List of Boattailshelf Report No. AA-08066 Rev.D.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan for the Installation of a Cargo Shelf onBell Model407 helicopters Report No. AA-09049 Rev.A, dated September 20th, 2009.Installation Instructions Boattail Shelf Kit 407-260-001 for Bell Model407 helicopters Report No. AA-08064 Rev.B, dated February 24th, 2010.Instructions for Con...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/07/2014	Active	10049776
10049779	ICELANDAIR DESIGN ORGANISATION		FAA STC ST03276CH	767-300	Installation of an AVIO Interior business class and economyclassseating interior and Inflight Entertainment System (IFE)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List GR00012-MDL rev. EInstructions for Continued Airworthiness GR00013-ICA rev. IRAircraft Maintenance Manual Supplement GR00014-AMM rev. IRWeight and Balance Report GR00030-WBR rev. IRor later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decisio...	None.	07/07/2014	Active	10049779

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049792	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	FAN JET FALCON E FAN JET FALCON D FAN JET FALCON	ACAS II version 7.1 upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Initial IssueCS 25.1CS 25.1301CS 25.1309CS 25.1322CS 25.1333CS 25.1431CS 25.1459CS 25.1529CS 25.1581CS 25.1585The requirements for environmental protection and the a...	Flight Manual Supplement FRAH/FM/0124 Revision 0or later revisions of the above listed documents approved by EASA.Design Change Statement DC-0251 Issue 2	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/07/2014	Active	10049792
10049805	AIRLEC AIR ESPACE			501	P-RNAV capability of a Dual Garmin GNS 400/500AW's series installation.Compliance showing to AMC 20-28 that the installed equipment is suitablefor RNAV (GNSS) approaches down to LPV Minima, according AMC 20-27 tosupport APV BARO VNAV approaches to LNAV/VNAV minima with VNAV providedthrough SBAS, sho...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to Airlec Air Espace STC Data List No. AAE 003 SDL Rev.2 , orlater RevisionsTo be operated in accordance withAFM-S Document No. AAE 003 AFM,Original issueor later revisions of the above listed documents approved by EASA.	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	09/07/2014	Active	10049805
10049811	MT-PROPELLER ENTWICKLUNG GmbH			PA-46-350P (MALIBU MIRAGE) PA-46-310P (MALIBU)	Installation of 5-blade MTV-27-1-E-C-F-R (P)/CFR203-58d	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels	MT-Propeller Master Document List No. E-2454To be operated in accordance with MT-Propeller AFM-S Document No. E-2449or later revisions of the above listed documents approved by EASAMT-Propeller Installation Instructions Doc. No. E-2450To be maintained i.a.w. MT-Propeller ICA Document No. E-2451	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product	09/07/2014	Active	10049811
10049817	E A D AEROSPACE AIRWORTHINESS	REV. 2		A320-231, A320-232, A320-233 A320-215, A320-216 A320-211, A320-212, A320-214 A319-131, A319-132, A319-133 A319-114, A319-115 A319-111, A319-112, A319-113	Installation of High Gain Antenna - EMS SATCOM AMT-3800	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, EAD Aerospace document No. 01441-EAS-A-MDL,Revision C, dated 11 June 2019.Instructions for Continued Airworthiness, EAD Aerospace document No.01441-EAS-A-ICA-01, Revision E, dated 6 May 2019.or later revisions of the above listed document (s) approved/ acceptedunder the EASA syst...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/06/2019	Active	10049817
10049820	ROCKWELL COLLINS, Inc.	REV. 2	FAA ST01675WI	SEE FAA AML	Modification of a Rockwell Collins, Inc. File Server Unit (FSU)Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Rockwell Collins, Inc. Drawing Index RCA-0343-001, Rev. (-), dated 17February 2012, or later FAA approved revision, as listed on the attachedFAA Approved Model List (AML).	Prior EASA approved installation of a Rockwell Collins, Inc. File ServerUnit (FSU) is a prerequisite to this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willa...	27/11/2018	Active	10049820
10049821	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01641WI-D	SEE FAA AML, REV. N	Installation of Rockwell Collins, Inc. Aircraft InformationManagement(AIM) System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01641WI-D. The requirements forenvironmental protection and the associated certified noise and/ oremissions levels of thea...	1. FAA Approved Model List (AML) RCA-0386, Revision B, dated 6 July2012, or later FAA approved revision.2. Instructionsfor Continued Airworthiness as specified by FAA ApprovedModel List (AML) RCA-0386, Revision B<(>,<)> or later FAA acceptedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	24/10/2018	Active	10049821

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049822	FOKKER SERVICES B.V.			757-200, 757-200PF, 757-300	CPDLC (Controller Pilot Data Link Communication) in the Boeing 757	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plans: CP-0214 Issue 1, CP-220 Issue 2Compliance Record Reports: CRR-0214 Issue 1, CRR-02120 Issue 1SE-782 Issue 1: Boeing B757 - GPS antenna ICA SupplementB752-EXS-AFM-S-001 Revision 1: AFM Supplement B757 CPDLC installationor later revisions of the above listed documents approved by...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/07/2014	Active	10049822
10049829	LUFTHANSA TECHNIK AG			A330-300	A330-300 new model pax seats and monuments installation1. Exchange of 332 pax 2-class seating with 315 pax 2-class seating. Newseat models Thompson Vantage (B/C) and ZIM Eco 01 (Y/C) includingrelated IFE equipment. 2. Installation of monuments and associated cabin interior modifications	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD25-14/20M issue1 rev 1- ICA, ref A-00-14/17-ICA, Issue 1 rev 0- ComplianceRecord List CRL25-14/20M iss 1 rev 1or later revisions of the above listed documents approved by EASA.	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2),,This modification must be installed in co...	10/07/2014	Active	10049829
10049830	AERO MEDICAL PRODUCTS MFG. Inc.		FAA STC SA1291GL	500, 550, 560	Aircraft Medical Stretcher System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero Medical Products, Installation & Operating Instructions, EA Form109CC, rev. 1, dated 23 April 2001Aero Medical Products, Maintenance Requirements for Aircraft Litters, EAForm107, rev 1, dated 06 July 1999or later revisions of the above listed documents approved by EASA inaccordance with EASA E...	None	11/07/2014	Active	10049830
10049832	PFW ENGINEERING GmbH	REV. 2		757-200	B757-200 Cabin Interior ChangeNew LOPA in the economy classonly, including ETSO seats with embeddedLCD and in-seat power supply, new In-Flight Entertainment System for thewhole aircraft, including a control monitor unit for the cabinattendants, extra fixed LCD monitors for passenger addressing, als...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/ approval.	- Instructions for Continuous Airworthiness, PFW reference B752A-ICA-Aissue MAR 31/2014, Revision 03 dated Dec 01/2014.- Airplane Flight Manual Supplement, PFW reference B752A-AFM-A issue 01,dated March 31, 2014.or later revisions of the above listed documents approved by EASA.	1. This approval is strictly limited to the following B757-200 aircraft:Serial No 28112, 29488 and 29489, sharing the same initial cabin lay-outconfiguration.2. Operational limitations: refer to section 2 of Airplane Flight ManualSupplement B752A-AFM-A.3. Airworthiness limitations: refer to sectionB...	13/01/2015	Active	10049832
10049837	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 1		777-200	Interior Reconfiguration for Cathay Pacific Airways Boeing 777-200AircraftThis design change encompasses an interior reconfiguration on fiveBoeing 777-267 model having the same initial interior configuration: newand salvage/refreshed interior furnishings (galleys, overhead stow bins,closets, lavator...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Instructions for Continued Airworthiness, NAT reference N0446-D70 rev.B- Master Drawing List, NAT reference N0446-D10rev. Eor later revisions of the above listed documents approved by EASA- Certification summary, NAT reference N0446-D90rev. C	This approval is strictly limited to the five (5) followingB777-267aircraft: Serial No 27116, 27265, 27266, 27263, 27264.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or rep...	15/07/2014	Active	10049837
10049838	GFD GmbH	REV. 1		35A	Iridium SATCOM Dual Antenna provisionRev. 1: Transfer to GFD GmbH	FAR 25The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.- Models 35A:FAR 25 effective February 1, 1965, as amended by 25-2 and25-4.- In addition:Amendment 25-7, 25-18 and Paragraph 25.57...	- ICA Instructions for Continued Airworthiness Doc. 5328-085 Rev. A-Master Data List Doc. 5328-049 Rev. Aor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10049838

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049839	GFD GmbH	REV. 1		35A, 36A	2nd SM GPS Antenna ProvisionRev. 1: Transfer to GFD GmbH	FAR 25The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval:- Models 35A and 36A:FAR 25 effective February 1, 1965, as amended by 25-2 and 25-4.- In addition:Amendment 25-7, 25-18 and Paragra...	- ICA Instructions for Continued Airworthiness Doc. 5326-085 Rev. IR- Master Data List Doc. 5326-049 Rev. Bor later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10049839
10049852	PRO STAR AVIATION, L.L.C.	REV. 1	FAA STC SA00336BO	B200, B200C, 300, B300, B300C	Installation of a Thrane & Thrane AVIATOR 200 Swift Broadband System.	As defined in FAA STC ref SA00336BO.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Pro Star Aviation Installation Data Listref 2857-IDL-101 Rev IR, dated December 06, 2013.Operation in accordance with Pro Star Aviation Airplane Flight ManualSupplement ref 2857-FMS-101 Rev IR, dated December 07, 2013.Maintain in accordance with Pro Star Aviation Inst...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/07/2014	Active	10049852
10049855	LATITUDE TECHNOLOGIES CORPORATION		TCCA STC 13-35 ISSUE 1	EC 130 B4 AS 350 B, AS 350 B1 AS 350 BA, AS 350 D AS 350 B2, AS 350 B3	Installation of the Latitude Technology IONode Flight Data Monitoring(P/N ION100-000, -001, -002, -003, -004) as described in the LatitudeTechnology Installation Instruction 1126-400-002.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-,,Installation Instructions Latitude Technologies IONode for EurocopterAS 350B, B1, B2, B3, BA, D and D1, EC130B4, EC120, 1126-400-002 Rev. NC-,,Instructions for Continuing Airworthiness for the Installation ofLatitude Technologies IONODEFlight Data Monitor 1126-400-005 Rev. NCor later revisions o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/07/2014	Active	10049855
10049863	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	B300	Approval of Universal Avionics UNS-1Lw FMS for PRNAV Operations.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Operation in accordance with Bournemouth Aviation (Consultants) LtdFlight Manual Supplement Number BAC-906FMS001 Revision 1, dated July2014.or later revisions of the above listed documents approved by EASA.	None.	14/07/2014	Active	10049863
10049864	DELTA ENGINEERING CORPORATION		FAA STC ST03193NY	A330-200 / -300	Panasonic eXLite In-Flight Entertainment System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Refer to section 3 in Compliance Summary Report ref 6654-08714-2362 revBThe requirements for environmental protection and the associatedcertified noise and/ or emissions l...	- MASTER DATA LIST : 0154-08715-2362, rev A- ICA & EWIS forContinued Airworthiness : 0754-08723-2362, rev A- Compliance Summary Report Project results : 6654-08714-2362, rev B- AFM Supplement : 0654-08722-2362, rev A- FAA Letter "EASA Approval of FAA Supplemental Type Certificate (STC) ST03193NY", d...	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2) For The Airworthiness Limitations, refer t...	14/07/2014	Active	10049864
10049872	PILATUS BUSINESS AIRCRAFT, LTD.	REV. 2	FAA STC SA04153AT	PC-12/47E	EMTEQ eConnect In-Flight entertainment System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	To be installed according to document Master Drawing List N.2-125214-001 Rev. A dated 28 April 2014To be operated according to AFMS 2-125214-800 Rev. IR dated 16 May 2014To be maintained according to (ICA) engineering document N. N. 2-125214-802 Rev. B dated 18 April 2014or later revisions of the abo...	None	23/02/2015	Active	10049872

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049874	TRUEVIEW ENHANCED VISION SYSTEMS,L.L.C	REV. 1	FAA STC SR02615NY	407	TrueView EVS T6 Infrared Thermal Imaging SystemThe TrueViewEVS 6 is described in the Manufacturing Drawing listMDL03034 and it consists of an externally mounted thermal imaging cameracontrolled through a limited vertical range.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement Trueview EVS T6 document No. FM03034Rev.- dated February 06, 2013or later revisionsof the above listed documents approved by EASA inaccordancewith EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedur...	The TrueView EVS T6 System is intended to enhance overall situationalawareness only.The TrueView EVS T6 System in not approved to be used to maneuvering theaircraft during any phase of flight.The TrueView EVS T6 System is not approved for flight guidance,navigation, traffic avoidance, or terrain avo...	16/07/2014	Active	10049874
10049878	VIDEO TECHNOLOGY SERVICES, Inc.		FAA STC ST03351NY	A330-200, A330-300	LCD monitor system and Digital Video PlayersLCD monitor system and Digital Video Players are installed, replacingold CRT monitors and Tape Reproducers on the same locations vacated bythe obsolete equipment being removed. Existing cables and connectors areused.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.305 (a)(b) : 25 Amdt 1425.561 : CS 25 Amdt 1425.613 : CS 25 Amdt 1425.785 : CS 25 Amdt 14	-Master Drawing List: ref 205-D-498 rev A- Instructions for Continuous Airworthiness: ref 205-D-499 rev --FAA Letter "EASA Validation of FAA Supplemental Type Certificate (STC) ST03351NY", dated on Jul 14 2014 - FAA statement of compliance.or later revisions of the above listed documents approved by E...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/07/2014	Active	10049878
10049883	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	B300 / B300C	Approval of Multi-role Cabin Configurations.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with GAMA Engineering Modification refHL/MOD/ 1379 and GAMA Master Document List (MDL) ref MDL-1379<(>,<)>Issue 1< (>,<)> dated 14 April 2014.Operate in accordance with GAMA Engineering Aircraft Flight ManualSupplement ref AFMS-1379, Issue 1, dated July 2014.Maintain in acco...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/07/2014	Active	10049883
10049896	KELLY AEROSPACE THERMAL SYSTEMS, L.		FAA STC SA03093CH	PA-44-180	Installation of Electric Air Conditioning System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	To be installed according to document listed in NC-10-085 rev.K dated 20Aug 2013To be operated according to AFMS N. NC-13-029 Rev.A dated 23 Oct. 2013To be maintained according toNC-10-087or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF...	Kit KATS-11-002 (for A/C with 14VDC) can be installed only if STCSA03092CH is approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installeddesign change and/ or repair will introduce noadverse effect...	17/07/2014	Active	10049896
10049905	AIR CONCEPTS INTERNATIONAL, Inc.		FAA STC SR03260NY	AB139, AW139	"Installation of a Honeywell Zing HUMS in accordance with HoneywellInstallation Instructions Document No. 3028-0007-GP,Revision D, datedJanuary 18, 2013Installation of a Honeywell Upgrade from VXP in accordance withHoneywell Installation Instructions Document No. 3028-0011-GP, RevisionC, dated Janu...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ICA Report No. 3028-0009-GP Revision A, dated February 10, 2012, FAAaccepted February 24, 2012.RFM Supplement No. 3028-0012-GP Revision IR, FAA approved March 6, 2013.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisi...	Installation of a Honeywell Zing HUMS by means of installation of aHoneywell Upgrade from VXP is only applicable to helicopters previouslymodified in accordance with FAA STC SR02120NY-D, covering Installationof a Honeywell Chadwick Model 15175 VXP System, and incorporateselements of that previous mo...	25/07/2014	Active	10049905

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049911	LUFTHANSA TECHNIK AG			747-400	Communications - Installation of AOA SoftwareUpdate of the ACARS CMU Software	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CP23-14/23M, Issue 1, Revision 0 (2014-06-10) - Certification ProgramCRL23-14/23M, Issue 1, Revision 0 (2014-07-15) – Compliance Record ListA-00-14/22-ICA, Issue 1, Revision 0 (2014-04-28) - Instructions forContinued AirworthinessSTDD23-14/23M, Issue 1, Revision 0 (2014-07-15) - Supplemental TypeDef...	None	17/07/2014	Active	10049911
10049913	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE		O-LSA10-039/D	BD-700-1A10	Iridium Antenna Installation (Structural Provisions)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada STC No. O-LSA10-039/D Issue 2 dated 26 February 2010.Innotech Aviation Engineering Drawing IALGX-9036-015, Revision NC.DECA Aviation Engineering Instructions for Continued AirworthinessICA10019, Revision 4.or later revisions of the above listed documents approved by EASA inaccordanc...	None	17/07/2014	Active	10049913
10049916	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	767-200, 767-300, 767-300F	Introduction of Dlink + W/CPDLC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRI F-01- Data Link Services for the Single European Sky	Flight Manual Supplement S21.FMS-0094 Issue 1or later revisions of the above listed documents approved by EASA.Master Document List S21.MDL-0894 Issue 3	None.	18/07/2014	Active	10049916
10049921	AEROTEC & CONCEPT			757-200	B757 FULL BUSINESS CONFIGURATIONModification of the cabin to achieve a full business configuration (74PAX), with IFE/Moving Map system, In-Seat Power Supply, and 110V/60Hz inthe cockpit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-01 "Application of heatrelease and smoke density requirements toseat materials", issue 1 dated 03-06-2014.The requirements for environmental pr...	- Airplane Flight Manual Supplement, AEROTEC document number AE14028AFMSissue 0 dated 06/06/2014.- Instructions for Continued Airworthiness, AEROTEC document numberAE14028ICA issue 0 dated 30/04/2014.or later revisions of the above listed documents approved by EASAMaster Data List, AEROTEC document1...	- This approval is limited to aircraft model B757-256.- Airworthiness limitations: refer to section 7 of AEROTEC documentAE14028ICA.- Operational limitations: refer to section 3 of AEROTEC documentAE14028AFMS.Prior to installation of this design change it must be determined thatthe interrelationship...	21/07/2014	Active	10049921
10049937	MARSHALL OF CAMBRIDGE AEROSPACELIMITED		CAA UK RESPONSIBILITY	A330-200	A330 Cabin and In Flight Entertainment Upgrade including theintroduction of Lower Deck Mobile Crew Rest for TAP Portugal	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-01 Glass Screens of Displays and MonitorsThe requirements for environmental protection and the associatedcertified noise and/ or emissions level...	Marshall ADG Modification Sheet No. MA2064 Issue 1	Must be installed in conjunction with EASA STC 10014507: Installation ofnon-electrical Floor Path Marking System	21/07/2014	Active	10049937
10049974	RUAG AG	REV. 1		AS350D, AS350BA AS350B, AS350B1, AS350B2 AS350B3, AS350BB	Single or dual installation of Garmin GTN 650 GPS/NAV/COMRev 1: Transfer of STC to a new legal entity that is holder ofa new DOA(EASA.21J.760)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS27 Amdt 3 paragraphs: 27.1, 27.29, 27.251, 27.301, 27.303, 27.305,27.307, 27.321, 27.337, 27.341, 27.561, 27.601, 27.603, 27.605, 27.607,27.609, 27.610, 27.611, 27.613,2...	Flight Manual Supplement, doc. ref. FMS-609102 Rev. A dtd. 17/07/2014Master Data List, doc. ref. MDL-8001746, Rev. A dtd. 17/07/2014Certification Compliance Sheet doc. ref. CCS-8001740, Rev. A, dtd. 17/07/2014Instructions for Continued Airworthiness, doc. ref. ICA-8001748, Rev. Adtd. 04/07/2014or lat...	-GPS use limited to VFR-GPS approaches prohibited-Obstacle and Fuel data only for informationPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse...	18/01/2021	Active	10049974

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10049985	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC ST11044SC	FALCON 2000, FALCON 2000EX	Installation of a third Rockwell Collins AHC-3000 Attitude HeadingReference System (AHRS).Rev. 1: Change of Address	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data Package 366-00-0000 revision E, dated 03 August2011.Master Drawing List 366-00-0001 revision E, dated 03 August 2011.Airplane Flight Manual Supplement 366-00-0014 initial revision, dated 15April 2011.or later revisions of the above listed documents approved by EASA inaccordance with EAS...	Applicable to F2000 and F2000EX models with Rockwell Collins Proline 21Avionics System installedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadver...	07/08/2025	Active	10049985
10049996	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04246AT-D	GV-SP GV G-IV	Installation of an EMS AMT-700G SATCOM Antenna Subsystem.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness:Model GIV: CE41103A017 rev B dated January 4, 2013 for EMS AviationAMT-700G-01SAT COM antenna subsystem. Models GV, GV-SP: CE52103A001 revA dated November 16, 2011 for EMS Aviation AMT-700G-04 SATCOM antennasubsystem.or later revisions of the above listed doc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/07/2014	Active	10049996
10050001	STZ-AFL	REV. 1		LS 6-B	Retrofit of the Sailplane LS6-b with Winglets	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Description of the modification "STC LS6-b Winglet Retrofit"-List of certification documents dated 22.07.2014-Supplement to the Flight Manual of the sailplane LS6-b with retrofitwinglets "LS6-bwl"-Ergänzung des Flughandbuches für das Segelflugzeug LS6-b mitnachgerüsteten Winglets "LS6-bwl"-Drawingo...	Reduction of the mass of the non lifting parts by 10 kg compared to theoriginal LS6-bReduction of the max. waterballastin the wings to 110 kg compared tothe original LS6-bPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any o...	28/07/2014	Active	10050001
10050010	MICRO AERODYNAMICS, INC.		FAA STC SA5131NM	402C, 414A	Install of vortex generators on the wing and vertical tail surfaces andan increase in maximum take-off weight, maximum zero fuel weight, andmaximum ramp weight in accordance with FAA STC SA5131NM.Option: 1: No change in airspeeds; AFMS notrequired; no change inweights or centre of gravity envelope....	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Drawing List DL-402C, Rev. B, dated July 24, 1992Installation Instructions II-402C, Rev. B, dated July 24, 1992Flight Manual Supplement (option 2 only):C402C-AFMS-1, Rev. B for the 402C, dated August 19, 1996C414A-AFMS-1, Rev. B for the 414A, dated August 19, 1996or later revisions of the above list...	This STC does not cover Cessna 414A equipped with RAM engine and wingletinstallations per FAA STC SA7463SW-D and SA4934SW as long as FAA STC FAASTC SA7463SW-D is not yet EASA approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design chan...	25/07/2014	Active	10050010
10050014	DAO AVIATION A/S	REV. 1		B200	Installation of Garmin G600 PFD/MFD, GPS 500W TAWS, and GTX330D withADS-B out.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amdt. 3 elected to comply with for areas affected by the change.The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	Installation in accordance with DAO Aviation A/S documentDAO-DO-0524-MDL, at revision 00, dated July 11, 2014;Aircraft Flight Manual Supplements, DAO Aviation A/S documents,DAO-DD-0524-AFMS1, DAO-DD-0524-AFMS2, and DAO-DD-0524-AFMS3, at revisionIR, dated July 11, 2014;or later revisions of the above...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/07/2014	Active	10050014

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050018	BRISTOW HELICOPTERS Ltd.		CAA UK RESPONSIBILITY	S-76 A, B & C SERIES	Introduction of Baggage/Cargo to the Cabin Rear Bench Seat Location	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS.29 Amdt 3; 29.1, 29, 251, 301, 303, 305, 307, 561, 601, 603, 605,607, 609, 611, 613, 625, 787, 803, 807, 811, 813, 851, 853, 855, 1301,1439, 1501, 1519, 1529, 1541, 155...	Flight Manual: BHL F/m Supplement No. 23; "Baggage/Cargo carriage withinthe Cabin Bench Seat Area"or later revisions ofthe above listed documents approved by EASA.Design Definition: (Cert Plan) BHL/S76.4607 Iss. ACompliance Statement document: (CCL) BHL/S76.4619 Iss. AICA: BHL/S76.4618 Iss. A	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/07/2014	Active	10050018
10050019	DRF STIFTUNG LUFTRETTUNGGEMEINNUETZIGE AG			MBB-BK 117 C-2	Installation of GNC 255 and GTN 650 Certification Program STC N °0010029453-001	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFM MBB BK117 C-2 Supplement FMS 10-DRF-025or later revisions of the above listed documents approved by EASAMD-117-34-60-00008 - Master Document List - N° 0640_V01Certification Program STC N° 0010029453-001CC-117-34-60-0005 - Compliance Checklist - N°0640	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/07/2014	Active	10050019
10050022	ATELIER CHABORD	REV. 4		TB 10	Installation of exhaust according to Chabord modification STC-TB10-13-01Rev. 3: - Fitting bracket improvement - Enhanced silent blocks - Alternative anti corrosion surface treatment - Enhanced muffler collar - Heater improvement (2 in to 1)Rev. 4 corre...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 Amdt 3 § 21, 23,25, 29, 43, 45, 63, 65, 69, 71, 77, 201, 203, 207, 251, 301, 303, 305,307, 333, 337, 341, 471, 601,6...	- Technical Dossier ref. STC-TB10-13-01 Issue I dated 03 November 2021-Installation and maintenance manual ref. TB10-14-01 revision E dated03 November 2021Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is applicable to TB10 aeroplanes equipped with LycomingO-360-A1AD engine and with the following propellers:- Hartzell HC-C2YK-1BF/F7666A-2, or-McCauley B3D36C424/74SA-0,or-Hoffmann HO-V123K-()-()180 DT10.Prior to installation of this change/repair it must be determined thatthe interrelat...	26/11/2021	Active	10050022
10050033	SPECIALIST AVIATION SERVICES LIMITE		CAA UK RESPONSIBILITY	MD900	Lowered Patient Loading System (LPLS)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS.27 Amdt 3; 29.1, 27, 29, 301, 303, 305, 321, 341, 561, 571, 601, 603,607, 609, 611, 613, 625, 785, 1529, 1541, 1581The requirements for environmental protection and the...	Flight Manual: FMS/707-002 Iss. Aor later revisions of the above listed documents approved by EASA.Design Definition: (Cert Plan) CP/707-001 Iss. ACompliance Statement document: (CCL) CCL/707-003 Iss. AICA: MPS/707-004 Iss. A	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/07/2014	Active	10050033
10050044	SOCIETE AIR FRANCE S.A.			747-400	RAM cabin reconfiguration and ims "RAVE" IFE installationCabin rearrangement and new IFE system installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:25.853(a),(b),(c),(e) at JAR change 13 due to French retroactiveairworthiness requirements25.1423(c) at JAR change 14 follo...	CP-B747-12-007 rev 2 (15 Jul 2014) - Certification ProgramCCL-B747-12-007 rev 2 (15 Jul 2014) - Compliance Check ListAFMS-B747-12-007-001 rev 0 (15 Nov 2013) - AFM SupplementSOCPL-B747-12-007-024 rev 1 (15 JUL 2014) - ICA SupplementCAS-B747-12-007 rev 0 (28 JUL 2014) - Declaration of Complianceor la...	- IFE system SCUs (System Control Unit) cellular modem function must bedeactivated;- The SaftGlo STC EASA.A.S.01098 must be installed per drawing533120002, initial issue (installation instruction M39-10 rev F);- The SaftGlo STC EASA.A.S.01098 charging instructions per AFMSupplement AFMS-B747-12-007-...	28/07/2014	Active	10050044
10050079	SABENA TECHNICS BGC	REV. 2		A321-231	Cabin modification with ZII Rave IFE system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS 25 Amdt 4 for the paragraphs affected by the change (refer toassociated Certification Plan 4616-01-A-CP-R03, sectionT...	Master Data List 4616-01-A-2103-R03.Airplane Flight Manual Supplement 4616-01-A-2301-R05.Instruction for Continued Airworthiness 4616-01-A-2211-R01or later revisions of the above listed documents approved by EASA.	Rev. 2: The use of the Cellular Modem function of the ZII “RAVE” isallowed.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the ai...	08/09/2016	Active	10050079

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050088	RHEINLAND AIR SERVICE GmbH			CESSNA 208	Installation of single Garmin G600	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amdt. 323<(>,<)> 29<(>,<)> 301<(>,<)> 303<(>,<)> 305<(>,<)> 307<(>,<)> 561<(>,<)> 601<(>,<)> 603<(>,<)>605<(>,<)> 609<(>,<)> 611<(>,<)> 613<(>,<)> 771<(>,<)> 773<(...	- Airplane Flight Manual Supplement RAS-12-02-02-FMS-02or later revisions of the above listed documents approved by EASA.- Description of Installation RAS-12-02-02-DOI-03- Master Document List RAS-12-02-02-MDL-03- Instructions for Continued Airworthiness RAS-12-02-02-ICA-02	None.	31/07/2014	Active	10050088
10050089	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			EA 300/L	Introduction of Wing Tip Cameras on Extra EA300/L	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Design in accordance to Master Data List MODE00085_MDL Rev.Operation in accordance Flight Manual Supplement MODE00085_AFMS Rev. 2.Maintenance in accordance to Instructions for Continued airworthinessMODE00085_ICA rev. 2.or later revisionsof the above listed documents approved by EASA.	None.	31/07/2014	Active	10050089
10050094	AIRBUS S.A.S.	REV. 1		A320-232	MOD CJ1300 “MASTER MOD CJ – AL SAFAR”EASA STC update for A320 MSN 5255, including- Weight and Balance clarification fordelivery to QATAR Airways.- Correction on AIS (former ACJC)Statement of Compliance (MAS CJ1300)to EASA Certification Basis Ref A-2301-008:1)- Typo correction in Safety equipment d...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MASTER MINIMUM EQUIPMENT LIST – SUPPLEMENT - MMEL-S MOD CJ1300 AUG 01/14WEIGHT AND BALANCE MANUAL SUPPLEMENTor later revisions of the above listed document(s) approved/ accepteduder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/08/2019	Active	10050094
10050103	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	DHC-8-401, DHC-8-402	Dash 8 Q400 SkyCam Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25, Amendment 4, see AppendixThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchang...	Installation in accordance with Bournemouth Aviation (Consultants) LtdMaster Data List BAC-917MDL02, Issue 2.Maintenance in accordance with Bournemouth Aviation (Consultants) LtdInstructions for Continued Airworthiness BAC-917ICA02, Issue 2.Operation in accordance with Bournemouth Aviation (Consulta...	Provisions installed under Minor Change BAC-917 MOD01 (or staged MinorChanges BAC-917 MOD03, BAC-917 MOD04 and BAC-917 MOD05) are required.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design c...	01/08/2014	Active	10050103
10050143	JET AVIATION AG			MYSTERE FALCON 20-C5/D5/E5/F5	TCAS II (ACAS II) UPGRADE TO Version 7.1Upgrade of existingHoneywell CAS67 Traffic Alert and CollisionAvoidance Systemto incorporate 7.1 logic software:Change consists of Honeywell TPU-67A TCAS 7.0 processor P/ N066-01146-1211Upgrade to orreplacement by a TPU-67B TCAS 7.1 processor P/N066-01146-222...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and! or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List JBSL-M-00007MDL-01 Issue 1Instructions forContinued Airworthiness JBSL-M-00007ICA-01 Issue 1Airplane Flight Manual Supplement JBSL-M-00007AFM-O1 Issue 1or later revisions of the above listed documents approved by EASA.	As a pre-requisite, airplane must be fitted with existing:ACAS II compliant TCAS Honeywell TPU67A PIN 066-01146-1211, andEHS and/ or ADS-B compliant SSR ATC transponders, andAltitude data not provided through Gray/ Gilham coding.Prior to installation of this design change it must be determined thatthe...	06/08/2014	Active	10050143
10050151	AMAC AEROSPACE SWITZERLAND AG			737-800	WLAN ActivationThis Modification activates the WIFI access point built in the routerfor the 2.4 GHz and 5 GHz frequencybands. In addition a Cockpit ControlPanel — WLAN ON/OFF - will be installed to manually control the WIFIaccess point asrequired.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, Doc. No. MDL-AR07-4430, Rev. B- AFMS, Doc. No. AFMS-AR07-4430, Rev. A- ICA Doc. No. ICA-AR07-4430, Rev. Aor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/08/2014	Active	10050151

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050156	DASSAULT FALCON JET CORPORATION	REV. 1	FAA STC ST02965NY	FALCON 2000, FALCON 2000EX	Validation of FAA STC.Installation of EMTEQ LED Anti-Collision / Navigation Light.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. F2XW-D0005-005 issue A, dated 21/06/2013.Airworthiness Limitations Section included in document Instructions forContinued Airworthiness ref. F2XW-D0005-155 issue A, dated 30/04/2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decis...	Applicable to F2000 model with Dassault Aviation Service Bulletin No. 348embodied.Applicable to F2000EX model with Dassault Aviation Service BulletinNo.159 embodied.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprev...	05/12/2014	Active	10050156
10050158	DASSAULT FALCON JET CORPORATION		FAA STC ST03169CH-D	MF 50	Validation of FAA STC.Installation of Whelen Single Function LED Navigation Tail Light.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. 1022666 issue C, dated 07/12/2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/or the Technical Implementation Procedures of EU/USABilateral Agreement.	NONE	07/08/2014	Active	10050158
10050163	SCHERDEL ENGINEERING Ltd.			2- DG 500MB 1- DG 800A / DG 800B	Alternate Method of Compliance for TM 800/42 and TM500/06	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/	- Alternate Method of Compliance TM 800-42_500-06, Doc-No TN 5_ V3- additional pages to Flight Manual, chapter 9or later revisions of the above listed documents approved by EASA.-Certification Document, Rev.1: Alternate Method of Compliance for TM 800/42, 500/06, CD_V1	Only forDG 800A, DG 800B (EASA.A.067)DG 500MB (EASA.A.233)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repairwill introduce noadverse effect upon the airworthiness of th...	07/08/2014	Active	10050163
10050167	LANITZ-PRENA FOLIEN FACTORY GmbH	REV. 5		SEE EASA APPROVED MODEL LIST	Application of ORATEX covering and coating system for sailplanes andpowered sailplanesRev. 5 includes “on-condition” NDT evaluation for the lifetime of thesystem.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 22.1, CS 22.21, CS22.29, CS 22.45, CS 22.63, CS 22.143, CS22.152, CS 22.201, CS 22.203,CS 22.207, CS 22.251, CS 22.301...	-Application of ORATEX covering & coating system, Doc. No.ADxC-51-C0-001, issue M, dated 5th March 2020-ORATEX Application Manual & Airplane Maintenance Manual Supplement,Doc. No.ADxC-51-001-AMM Edition 8.0, dated 6th March 2020or later revisions of the above listed document(s) approved/ acceptedund...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/06/2020	Active	10050167
10050172	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		PA-28-181 PA-28-180 (SN 7405001-7505259) PA-28-180 PA-28-161 PA-28-151, PA-28-161, PA-28-151	Installation of Hand ControllerRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.As per CR-10514-00001 Issue 3The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable t...	MOD-10514-00001 issue 2 Modification Summary - Piper PA-28 InstallationOf HandController 10 July 2014MDL-10514-00001 Issue 3 Master Document List - Piper PA-28 InstallationOf HandController 10 July 2014CP-10514-00001 issue 2 Certification Plan - Piper PA-28 Installation OfHandController 10 July 2014...	As defined in 10514-AFM-00001 Issue 1 Flight Manual SupplementPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the p...	10/11/2021	Active	10050172

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050194	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		340A 340	Installation of Garmin GA35, Garmin GA58, L-3 Communications NY-163,Comant CI 490-1, L/H and RH Sensor Systems S67-2002	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS23, Amdt. 3:23.365(d), 23.561(a), 23,571(a)(b), 23.575, 23.603(a)(b), 23.607,23.611, 23.867, 23.1301(a)-(d),23.1309, 23.1327, 23.1351,23.1431(a)(b), 23.1529The requirem...	Master Document List ASR-2014-016-MDL-01-01 (Rev. 01) dated29th June2017Instructions for Continued Airworthiness ASR-2014-016-ICA-11-01 (Rev.01) dated 29th June 2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10050194
10050199	ASI INNOVATION			BN2A-21	Mast with relay antenna installation.	The Certification Basis (CB) for the original product remains applicableto thiscertificate approval.The requirements for environmental protection and the associatedcertifiednoise and/or emissions levels of the original product are unchanged andremain applicable to this certificate! approval.	ASI-AFM-0102-06 (aircraft flight manual supplement issue 06August 2014)or later revisions of the above listed documents approved by EASA.	Other: maximum take-off weight reduced by 800 lb (5800 lb instead of6600 lb)noise certified : 80 dB (maximum noise authorized).	13/08/2014	Active	10050199
10050203	AVIATION COMPLETION INNOVATIONSINC.	REV. 1	FAA STC SR02326NY	AB139, AW139	Installation of Cabin Door Step System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02326NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Air Concepts International, Inc. Installation Drawing List Report No.31021-806-INS, Revision D, dated 30 April 2011.Aircraft with sliding cabin doors: IAW Installation InstructionsEngineering Report IM00139.04, Revision A, dated 22 May 2007- Configuration 1 Left Side Cabin Door Step System, Left Si...	Flight into known icing conditions is permissible for all cabin stepconfigurations when installed on AB/AW139 aircraft.Prior to installation of this design change it must be determined thatthe interrelationship between this repair and any other previouslyinstalled design change and/or repair will in...	25/06/2019	Active	10050203
10050209	328 SUPPORT SERVICES GmbH	REV. 1		BD-700-1A10	Cabin refurbishment including LED Cabin lighting installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	328 Design Master Document List No. MDL021Z001 Issue A dated 08 August2014.	Restricted to ASN 9083.	27/09/2018	Active	10050209
10050212	DOA21 LIMITED	REV. 1		A321	Introduction of Corporate VIP InteriorRev. 1: Transfer of STC holder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):CRI D-02 Isolated CompartmentsCRI D-05 Glass Screen of Displays and MonitorsCRI D-06 Shower InstallationDeviation(s):CRI D-01 Installatio...	STC Twenty One Flight Manual Supplement No S21.FMS-0111 Issue 1or later revisions of the above listed documents approved by EASASTC Twenty One Master Document List No S21.MDL-1146Issue 1	Restricted to MSN5538. Operation of the aircraft in the Private categoryonlyPrior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	24/10/2023	Active	10050212
10050216	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CL-600-2B16	Dual MD302 SAM Standby Attitude Module	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertifiedRequirements noise and/or emissions levels of the original product areunchanged andremain applicable to this certificate/ appr...	AIEC AG Flight Manual Supplement No. AC5318-071 Rev A dated12June 2014.or later revisions of the above listed documents approved by EASA.AIEC AG Master Data List No. AC5318-049 Rev B dated 13 August 2014	Restricted to ASN 5042	14/08/2014	Active	10050216

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050217	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD	REV. 1	TCCA STC O-LSA11-222/D	BD-700-1A10	I-KU System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product areunchanged and remain applicable to this certificate/ approval	Innotech Aviation - A Division of LM.P. Group Ltd. Flight ManualSupplement FM11-006, Revision A, Transport Canadaapproved 9th December 2011 or later revisions of the above listeddocuments approved by EASA in accordancewith the Technical Implementation Procedures of EU/Canada BilateralAgreement.Inno...	Restricted to ASN9399	20/10/2014	Active	10050217
10050223	AEROSPACE DESIGN AND CERTIFICATION		CAA UK RESPONSIBILITY	BOEING 727-2S2F (RE)	Boeing 727 Oil Dispersant Equipment Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:See CRI A-01 Appendix AThe requirements for environmental protection and the associatedcertified noise and/ oremissions levels of the original product areunchanged and re...	AeroDAC Aircraft Flight Manual Supplement FM/ JN/491-001/002Issue E,Reference JN 491-001/002, ADC 29(1) Issue E.AeroDACInstructions for Continued Airworthiness, Paragraph 4,Airworthiness Limitations, Reference JN-001/002 ADC 54(2) Issue 2or later revisions of the above listed documents approved byM...	Aircraft Serial Number 22938 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.Installation i...	14/08/2014	Active	10050223
10050229	CRANE AEROSPACE & ELECTRONICS	REV. 1		S550 CITATION S/II CITATION VII 680 SORVEIGN/750 CITATION X/ 650 CITATION III/ CITATION VI 560XL EXCEL AND XLS/ XLS+ 560 ENCORE, 560 ENCORE + 550 CITATION II AND BRAVO, 550 CITATION AND CITATION I	Tire Pressure Sensor on Cessna Citation ModelsInstallation of a Crane Aerospace & Electronics Tire Sensor Assembly	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Crane Aerospace, Installation Manual*, IM83-201-01, rev. B,dated 11April 2013Crane Aerospace, Master Document List, CCL83-201-01, rev. C, dated 25February 2013* Including the Instructions for Continued Airworthiness (ICA).or later revisions of the above listed documents approved by EASA inaccordan...	None	03/02/2015	Active	10050229
10050244	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	FAN JET FALCON E FAN JET FALCON D FAN JET FALCON	Introduction of an Observers Seat	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s):CRI-D-01 "Width of Aisle"The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areu...	Cobham Aviation Services Aircraft Flight Manual Supplement No.FRAH/FM/ 0126 dated 08/08/14.or later revisions of the above listed documents approved by EASACobham Aviation ServicesDesign Change Statement No. DC-0245 Issue 1Dated 18/08/14.	Cobham Aviation Services Minor Modification No. DC-0089 is aPre-Requisite for this installation	19/08/2014	Active	10050244
10050247	LUFTHANSA TECHNIK AG	REV. 1		A320-232	Activation of Wireless IFE System Board Connect with Gate-to-Gatefunctionality.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD23-15/25M Issue1 Rev. 0,dated 24/09/2015- Compliance Record List CRL23-15/25M Issue 1 Rev. 0, dated 24/09/2015- Airplane Flight ManualSupplement A-00-15/46-AFM Issue 1 Rev. 0, dated16/09/2015- Instructions for Continued Airworthiness A-00-15/46-ICA Issue...	None.	29/09/2015	Active	10050247

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050248	ARMSTRONG AEROSPACE Inc.			A330-200	Installation of a Lufthansa Systems BoardConnect IFE System.The BoardConnect In-Flight Entertainment (IFE) system delivers access toinformation and entertainment for passengers via an onboard WiFinetwork, which utilizes passenger operated personal electronic devices(PED).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Refer toArmstrong document ref LT127-9207-00, dated on 16 July 2014.The requirements for environmental protection and the associatedcertified noise and/or emissions level...	Master Data List : MDL DC 104-9207-00, rev B.ICA : DC113-9207-00 rev AAFM : DC303-9207-00 rev -FAA Letter (no reference) dated 13 August 2014or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/...	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.2) Prior or Concurrent embodiment of EASA STCS...	20/08/2014	Active	10050248
10050266	HELI-ONE CANADA ULC		TCCA STC SH12-25	AS 332 L, AS 332 L1	Installation of Enhanced Ground Proximity Warning system Honeywell MarkXXII EGPWS.(This STC is the Validation of TCCA STC SH12-25 issued on September 12<(>,<)> 2012.)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Operation must be in accordance with Heli-One Flight Manual SupplementCHA332-34-02 7 FMS Rev 7 dated Aug 28, 2012, TCCAApproved September 12,2012.or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreem...	None	22/08/2014	Active	10050266
10050267	HELI-ONE	REV.1	TCCA STC SH12-21 ISSUE 2	AS 332 L, AS 332 L1	Installation of UNS-1Fw Flight Management SystemRev. 1 is issued following validation of the TCCA STC SH12-21 Issue 2for the Dual FMS installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Configuration 1 (Single FMS installation)-,,Operation must be in accordance with Heli-One Flight ManualSupplement CHA332-34-026 FMS Rev A, dated Aug 31, 2012 and TCCA ApprovedSeptember 07, 2012*.Configuration 2 (Dual FMS installation)-,,Operation must be in accordance with Heli-One Flight ManualSupp...	Configuration 2 of the UNS-1Fw installation requires EFI-890H system tobe installed as per EASA STC 10058357.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will intr...	09/08/2016	Active	10050267
10050272	PFW ENGINEERING GmbH			A330-200	Installation of a WLAN System in the A330-203 VIPThis STC installs a new WLAN system, in replacement of an existing one(same location through the aircraft). The system includes anairborneunit, WLAN access points, indication panel in cabinand switch incockpit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement, ref A332A-AFM-A dated 11July 2014 - Part of STC Operators Manual document, ref A332A-COM-A.Instructions for Continued Airworthiness Manual Supplement, A332A-ICA-A- Part of STC Operators Manual document, ref A332A-COM-A.Master Drawing List ref A332A-MDR-230000 Issu...	This approval is limited to MSN 487.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	22/08/2014	Active	10050272
10050279	ARMSTRONG AEROSPACE Inc.		FAA STC ST03333CH	A320-214	Installation of Cobham SATCOM System	The Certification Basis (CB) for the original product remains applicableto thiscertificate/ approval.The requirements for environmental protection and the associatedcertifiednoisean/ or emissions levels of the original product are unchanged andremain applicable to this certificate/ approval	· Master Data List, Armstrong Aerospace document No. DC104-9341-00,Revision C<(>,<)>dated 1 May 2014· Instructions for Continued Airworthiness, Armstrong Aerospace documentNo.DC113-9341-00, Revision B, dated 30 April 2014· Airplane Flight Manual Supplement, Armstrong Aerospace document No.DC303-9341...	· Modification in accordance with this STC requires prior or concurrentinstallation of Delta G Design, Inc. STC ST11126SC, validated by EASA<(>,<) >installation of a IGA-5001 Intermediate Gain Antenna· Modification in accordance with this STC requires prior or concurrentinstallation of Armstrong Aero...	25/08/2014	Active	10050279

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050321	AVIONIK STRAUBING ENTWICKLUNGS GmbH			340A 340	Installation of Garmin G600 System with Synthetic Vision (SVT)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 329,251<(>,<)> 303<(>,<)> 305<(>,<)> 307<(>,<)> 337<(>,<)> 561<(>,<)> 575<(>,<)> 603<(>,<)> 605<(>,<)> 607<(>,<)> 609<(>,<)> 611<(>,<)> 613<(>,<)> 671<(>,...	Flight Manual Supplement G600 ASR-2014-038-FMS-05-00, Rev. 00or later revisions of the above listed documents approved by EASA.-Instructions for Installation ASR-2014-038-IFI-10-00, Rev. 00<(>,<)>or later approved revisions-Instructions for Continued Airworthiness ASR-2014-038-ICA-11-00, Rev.00<(>,<...	A suitable Garmin GPS System must have been already installed.	27/08/2014	Active	10050321
10050325	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BD-700-1A10	Refurbishment of VIP Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-01 Glass Screens of Displays and Monitors.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pr...	STC Twenty One Flight Manual Supplement No. S21.FMS-0112 Issue 1;or later revisions of the above listed documents approved by EASA.STC Twenty One Master Document List No. S21.MDL-1188 Issue 1	Restricted to ASN 9036.EASA STC No. 10016140 Rev 4 is a pre-requisite for this modification.	27/08/2014	Active	10050325
10050326	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	B777-200ER	ANZ B777-200 Skycouch Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration Scheme No.3101-MCS-01 Issue 1	None.	27/08/2014	Active	10050326
10050344	ARMSTRONG AEROSPACE Inc.		FAA ST03247CH	A321-212 / -213 / -231 / -232 A321-111 / -112 / -131 / -211 A320-231 / -232 / -233 A320-211 / -212 / -214 A319-115 / -131 / -132 / -133 A319-111 / -112 / -113 / -114	Certification of Compatibility with Cellular and Wireless DataTechnologies.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC ST03247CH, issued August 20, 2013Master Data List DC104-9214-00, Revision -, dated August 5, 2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Proc...	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane installed base station using the cellularand/or wireless technologies is concurr...	29/08/2014	Active	10050344
10050359	AERO-DIENST GMBH & CO. KG			CL-600-2B16	Satcom Antenna AMT-1800 IGA Installation (Honeywell)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero-Dienst Engineering Order No. 271-CL.056.01 Revision 1,dated 22August 2014.	None.	01/09/2014	Active	10050359
10050377	DASSAULT AIRCRAFT SERVICES CORP.	REV. 1	FAA STC ST02966NY	MF50/MF900/F900EX	Validation of FAA STC.Installation of EMTEQ LED Anti-Collision/ Navigation Light.This Rev. 1 was issued to correct the STC approval holder name.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. F9XW-D0007-005 Rev. B dated 20 November 2013.Airworthiness Limitation Section as per Maintenance Manual Supplementref. F9XWD0007-155 Rev. C, dated 24 October2012.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or...	Applicable to MF50 model with Dassault Aviation Service Bulletin No. 481embodied.Applicable to MF900 model with Dassault Aviation Service Bulletin No.385 embodied.Applicable to F900EX model with Dassault Aviation Service Bulletin No.321 embodied.	05/12/2014	Active	10050377

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050402	S4A SOLUTIONS FOR AVIATION, S.L.			60	FDR F1000N Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	S4A Flight Manual Supplement, doc. L6001-HDK01, issue 1, dated 23 April2014S4A Master Data List, doc. L6001-RPT02, issue 1, dated 17 April 2014or later revisions of the above listed documents approved by EASA.,,,,	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/09/2014	Active	10050402
10050404	AEROSPACE DESIGN FACILITIES Ltd.		CAA UK RESPONSIBILITY	AS 350 B3	Installation of Garmin GTN 750 COM/ NAV/GPS and/or Garmin GTN 650COM/ NAV/GPS plus the following optional equipment: Garmin GMA35 RemoteMounted Audio Panel, Garmin GTX33 Remote Mounted Transponder. Theinterseat avionics console is modified to house the GTN750 equipment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS27 Amdt. 3,paragraphs:27.1, 27.29, 27.251, 27.301, 27.303, 27.305, 27.307, 27.337, 27.351,27.601, 27.603, 27.605, 27.607...	Rotorcraft Flight Manual Supplement for Garmin GTN 650/750 NAV/COM/ GPSinstallation, ref. ADF-RFMS2014-122-01, issue 1 Draft 9, dated04/09/2014.Rotorcraft Flight Manual Supplement for Garmin GTX 33, ref.ADF-RFMS2014-122-02, issue 1 Draft 4,dated 04/09/2014or later revisions of the above listed docum...	- GPS use limited to VFR and GPS approaches prohibited-GPSnavigation, obstacle, HTAWS and fuel data only for information- The terrain display shall not be predicated upon for navigation andmanoeuvring.Prior to installation of this designchange it must be determined thatthe interrelationship betwe...	05/09/2014	Active	10050404
10050412	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		ERJ 170-200 STD. ERJ 170-200 LR, ERJ 170-100 STD, ERJ 170-100 LR,	Installation of provisions for the use of dual NAVAERO t.BagC2 EFBSystem on Embraer ERJ 170 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement doc. N °2068120-AM Issue 3dated 01September 2014Certification Documents List doc. N° 2068120-DOC Issue 02 dated 05September 2014or later revisions of the above listed documents approved by EASA.	This approval does not constitute an operational approval for the use ofthe EFB system.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installeddesign change and/ or repair will introduce noadverse effect...	09/09/2014	Active	10050412
10050414	ROCKWELL COLLINS, Inc.	REV. 1	FAA ST01635WI-D	MODELS LISTED IN "LIMITATIONS" AML N°ST01635WI-D EXCEPT	Modification of Rockwell Collins VHF-4000/VHF-4000E system installation.Validation of FAA STC N °ST01635WI-D	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rockwell Collins, Inc. Master Drawing List, doc. RCA-0360-001, Rev.Orig. dated May 6, 2011.FAA STC N°ST01635WI-D dated July 27, 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Te...	As per FAA STC N °ST01635WI-DLimited to the FAA Approved Model List (AML) N°ST01635WI-D exceptfollowing models:- Lockheed-Georgia Company: 282-44A-05- Lockheed-Martin Corporation: 382/382B/382E/ 382F and L-1011-385-1-14Prior to installation of this design change it must be determined thatthe interrela...	15/09/2014	Active	10050414
10050423	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	A320-200, A321-200	A320/A321 Brand Panel and Magazine Rack Installation on monuments	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	H4 Modification Summary and Declaration of Compliance No. MOD H4A1741Issue 1 dated 22 August 2014.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/09/2014	Active	10050423
10050431	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	GLOBAL 6000	Introduction of Corporate VIP Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-02 Isolated Compartments , CRI D-04 GlassScreens of Displays and MonitorsEquivalent Safety Finding (s): CRI D-03 Emergency Exit SignsDeviation(s...	STC Twenty One Ltd Flight Manual Supplement S21.FMS-0106 Issue 1 orlater revisions of the above listed documents approved by EASA.STC Twenty One Ltd Master Document List No. S21.MDL-1161 Issue 1.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/09/2014	Active	10050431

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050434	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	A340-642, A340-643 A340-541, A340-542, A340-311, A340-312, A340-313, A340-211, A340-212, A340-213,	Honeywell TCAS II system upgrade to change 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Summary Sheet H4A1742 Issue 7, dated 19/09/2017- Instructions for Continued Airworthiness H4ADR854 Issue3, dated19/09/2017- Airplane Flight Manual Supplement H4AFMS039 Rev 2, dated 19/09/2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/10/2017	Active	10050434
10050443	DELTA ENGINEERING CORPORATION	REV. 1	FAA ST03185NY	A321-213, A321-231, A321-232. A321-131, A321-211, A321-212, A320-233, A321-111, A321-112, A320-214, A320-231, A320-232, A320-111, A320-211, A320-212, A319-131, A319-132, A319-133, A319-113, A319-114, A319-115, A318-122, A319-111, A319-112, A318-111, A318-112, A318-121,	Installation of UTC Electronic Flight Bag Display Mount forCaptain andFirst Officer.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, ref : 0164-08800-2367 Revision C, dated 28 May 2014Aircraft Flight Manual Supplement, ref : 0664-08858-2367, dated 27 April2014Instruction for Continued Airworthiness, ref : 0764-08801-2367 RevisionA, dated 19 May 2014Weight and Arm data, ref : 2264-09032-2367, dated 14 May 2014ora...	In addition to the AFMS, ref : 0664-08858-2367, dated 27 April 2014limitations the following is required :1- Aircraft operations with the Electronic Flight Bag (EFB) cradlefitted in the flight deck, without EFB system installed, is prohibited.. 2- Each Electronic Flight Bag (EFB) and cradle may not w...	29/09/2014	Active	10050443
10050453	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 2	FAA STC SA03345CH	P.180 AVANTI, P.180 AVANTI II	Installation of Air Ambulance Conversion into P.180 Avanti or P.180Avanti II in accordance with Spectrum Aeromed MasterDrawing List6054DL, Revision 1, dated 29 May 2014	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Spectrum Aeromed Master Drawing List, Doc. No. 6054DL, Revision 1, dated29-May-2014FAA approved Aircraft Flight Manual Supplement, Doc. No. 6054FMS,Original Issue, dated 08-Jan-2014FAA accepted Instructions for Continued Airworthiness, Doc. No. 6054MM,Revision "-", dated 07-Feb-2013 or later revisio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/04/2019	Active	10050453
10050454	DART AEROSPACE Ltd.		TCCA SH13-43	R 66	D066-1001 Bearpaw Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions IIN-DO66-1001 Revision B, dated November 13,2013 or later revisions of the above listed documents approved by EASAin accordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Instructions for Continued Airworthiness ICA-D066-1001 revision 0, d...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/09/2014	Active	10050454
10050458	S-TEC CORPORATION		FAA SA09544AC-D	B. C90A, C90GT A. 65-A90-4, B90, C90, E90,H90 A. 65-90, 65-A90, 65-A90-1, 65-A90-4	Installation of S-TEC 01304 Digital Flight Control System (DFCS)	For Certification Basis see FAA STC SA09544AC-DThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with S-TEC Master Data List ST-925-L-0001,Revision C, dated 1-03-08.Operation in accordance with S-TEC Flight Manual Supplement NoST-925-M-0001, Revision A, dated 1-03-08.Maintain in accordance with S-TEC Instructions for ContinuedAirworthiness No ST-925-C-0001, Revision B...	Only eligible on models:-65-90 Serials LJ-1 through LJ-113 (except LJ-76).65-A90 Serials LJ-76, and LJ-114 through LJ-317.65-A90-1 Serials LM-1 and up.65-A90-4 Serials LU-1 and up.B90 Serials LJ-318 through LJ-501.C90 Serials LJ-502 through LJ-1062.E90 Serials LW-1 and up.H90 Serials LL-1 and upC90A...	12/09/2014	Active	10050458

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050473	VECTOR AEROSPACE HELICOPTERSER VICES INC.		FAA SR02399AK	AS 332 C, AS 332 L, AS 332 L1	Garmin GNS530W Installation in accordance with Vector AerospaceHelicopter Services USA Inc. Master Drawing List HP 332-34-60 -102Rev.A.This STC is the validation of FAA STC SR02399AK.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 "HIRF Protection"The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pr...	-Vector Aerospace Helicopter Services USA, Flight Manual Supplement FMSHP 332-34-60-301 Rev A. or later revisions of the above listed documentsapproved by EASA in accordance with EASA ED Decision 2004/04/CF (orsubsequent revisions of this decision) and/ or the TechnicalImplementation Procedures of E...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/09/2014	Active	10050473
10050483	AEROTEC & CONCEPT			1900D	TCAS antenna relocation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation and maintenance according to the documentationreported inthe Master Data List AE14151MDL Rev. 0 dated 10/09/2014 or laterrevisions of the above listed documents approved by EASA.	Applicability limited to the aircraft serial numbers UE-198and UE-227.To be installed only in conjunction with the STCEASA.A.S.01673 since itconstitutes an installation provision for it.	15/09/2014	Active	10050483
10050486	LUFTHANSA TECHNIK AG			A321-213, A321-231, A321-232. A321-131, A321-211, A321-212, A320-233, A321-111, A321-112, A320-216, A320-231, A320-232, A320-212, A320-214, A320-215, A319-132, A319-133, A320-211, A319-114, A319-115, A319-131, A319-111, A319-112, A319-113,	ACARS Datalink - CPDLC activation of ATN/Mode 2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Applicants Declaration of Compliance ADoC 3547 Rev.1, dated15/09/2014Supplemental Type Definition Document STDD23-11/26M Iss.1 Rev.0 dated25/08/2014Compliance Record List CRL23-11/26M Iss.1 Rev.0 dated 25/08/2014Airplane Flight Manual Supplement A-00-12/51-AFM Iss.1 Rev. 1 dated13/08/2014Instruction ...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/09/2014	Active	10050486
10050501	TENENCIA Ltd.		CAA UK RESPONSIBIL ITY	AVRO 146 SERIES RJ85 AVRO 146 SERIES RJ70 AVRO 146 SERIES RJ100	LPV Approach	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI H-01 Electronic Wiring Interconnection System (EWIS).The requirements for environmental protection and the associatedcertified noise and/ or emiss...	Tenencia Ltd. TEN Supplement 19 Issue 3 to the Avro RJ Flight Manual BAE5.1 (Incorporated in Report TEN 750/47 Issue 3); or later revisions ofthe above listed documents approved by EASA.Tenencia Ltd. Modification TEN 750, "BAE Systems Avro 146-RJ FlightManagement System LPV Approach Capability", Is...	1. Aircraft must have Tenencia Ltd. modification TEN 467 installed priorto installing this STC.2. If an HF Comm is installed on an aircraft with modification TEN 750,confirmation must be obtained from the STC holder (Tenencia Ltd.) thatthemutual interference between the systems is acceptable.Priort...	16/09/2014	Active	10050501
10050506	ACC COLUMBIA Jet Service GmbH	REV. 1		2- FR182 1- R182	C182 MOGAS OperationInstallation of a modification kit to allow the operation with MOGASi.a.w. EN228. The aircrafts areto be operated i.a.w. the Flight ManualSupplement as listedbelow.Rev. 1 Transfer to ACC Columbia Jet Service GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR23§23.65 (Amdt. 34), §23.901 (Amdt. 43), §23.903 (Amdt. 26), §23.1047 (Amdt. 47), §23.1527 (Amdt. 7), §23.1529 (Amdt. 8)The requirements for environmental protection and...	Master Document List MDOCL_2033441_rev1_20140715Flight Manual Supplement SPOH_2033441_rev0_20140715or later revisions of the above listed documents approved by EASA.Installation Instruction II_2033441_rev0_20140715	According to limitation section of AFM.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.If the ho...	31/01/2022	Active	10050506

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050522	POLYTECH AERO SUPPORT INC.	REV. 1	TCCA SA14-33, ISSUE 1	A330-341, A330-342, A330-343 A330-301, A330-321, A330-322, A330-202, A330-243,	A330 Improved Air Filter Element installationThis modification is to substitute to the originally installed airrecirculation filter elements by improved air filter elements,manufactured by IDP Inc., without modifying the system original designand associated maintenance procedures.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 Change 14: 25-1 ;-601; -603 ; -605 ; -611 ; -613 ; -831; -853 ; -1301 ; -1309 ; -1529 ;-1541.The requirements for e...	Modification Summary, ref : MS-14-007, dated 12 May 2014Instructions for Continued Airworthiness, ref : ICA-14-007, dated 26March 2014or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/10/2014	Active	10050522
10050555	AIRWORTHINESS TECHNOLOGY S.L.			SA227-BC SA227-AC SA226-TC	Replacement of the original Aircraft Ni-Cd batteries to install ConcordeRG-390E sealed lead-acid batteries.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	2014-01-07 SA226-TC AFM Supplement Rev. 02014-01-13 SA227-ACAFM Supplement Rev. 02014-01-15 SA227-BC AFM Supplement Rev.0or later revisions of the above listed documents approved by EASA.2014-01-12 Service Bulletin Rev. 02014-01-08 SA226-TC AMM Supplement Rev. 02014-01-14 SA227-AC AMM Supplement Rev.02...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/09/2014	Surrendered	10050555
10050557	LUFTHANSA TECHNIK AG			737-300, 737-500	Upgrade of the ACARS CMU software - Installation of AOA-only softwareconfiguration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/	Instructions for Continued Airworthiness AA-00-14/18-ICA Issue 1 Rev 0or later revisions of the above listed documents approved by EASA.Supplemental Type Definition Document STDD23-14/19M Issue 1 Rev0	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe	19/09/2014	Active	10050557
10050560	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A321-231, A321-232. A321-211, A321-212, A321-213, A321-111, A321-112, A321-131, A320-231, A320-232, A320-233, A320-214, A320-215, A320-216, A320-111, A320-211, A320-212, A319-132, A319-133, A319-114, A319-115, A319-131, A319-111, A319-112, A319-113,	Tablet Interface Module (TIM) Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): SC H-01: Enhanced Airworthiness Programme forAeroplane Systems – ICA on EWIS.The requirements for environmental protection and the associatedcertifie...	Tenencia Ltd. TEN Supplement 5 Issue 1 to the Airbus A318 /A319 / A320/ A321 Flight Manual (Incorporated in Report TEN743/47 Issue 1) ; orlater revisions of the above listed documents approved by EASA.Tenencia Ltd. Modification TEN 743, "Airbus A320 Series Tablet InterfaceModule (TIM) Installation...	1.,,Following the future EFB installation, an operational assessment, inaccordance with AMC 20-25, must be conducted toassess the impact of theloss of ARINC data to the EFB system and the impact on aircraftoperation due to the loss of theEFB system, considering intendedfunction and criticality of2...	19/09/2014	Active	10050560
10050562	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A310-304	Modification TEN 701 - Airbus A310-304 GPS activation -Thismodification activates a Dual CMA-5024 GPS System - previouslyinstalled and deactivated pending Operational Requirements for P-RNAVand Non Precision Approach (NPA) - in accordance with Tenencia Ltdreport TEN 701 issue 4, dated 21 August 2...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Tenencia Ltd Flight Manual Supplement TEN/A310/002 issue 2 dated 17 June2014or later revisions of the above listed documents approved by EASA.Tenencia LtdWeight and balance reportTEN 701/24Maintenance manual supplement reference TEN 701/4Wiring Diagram Manual Supplement reference TEN 687/27Illustra...	Limitations:(a) This installation is not approved for Approach Procedures withVertical Guidance. (APV)(b) See Flight Manual Supplements reference TEN/A310/002 for limitations(c) See Operations Manual Supplement reference TEN 701/7 for limitations(d) Electrical Load Analysis: see report TEN 701 issue...	19/09/2014	Active	10050562

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050570 (EASA.R.S.01010)	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 3		B. AB 212, AB 412, AB 412 EP A. 212, 412, 412EP	External Cargo BasketRevision with new STC n° 10050570 Revision 2: Agusta Bell AB412EP addedEASA.R.S.01010, Revision 1:AB 212 addedEASA.R.S. 01010, initial issue: Bell 212, 412, 412EP and Agusta BellAB412Revision 3: Transfer of the certificate	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: FAR 29 as per TCDS USH4SW, Issue 28, for Model Bell412EP.The requirements for environmental protection and the associatedc...	INAER Flight Manual Supplement CMA005-AFMS, Revision 3INAERLista maestra de documentos CMA005-LMD, Revision 3INAER Certification Report CMA005-CR-1, Revision 0INAER Instruction for continued airworthiness CMA005-ICA, Revision 3or later revisions of the above listed document(s) approved/acceptedunde...	The installation of this design by third person is subject to writtenpermission of BABCOCK MISSION CRITICAL SERVICES FLEET MANAGEMENT S.A.U.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changee...	11/03/2019	Active	10050570
10050582	GLOBAL AVIATION TECHNOLOGIES LLC	REV. 1	FAA ST01743WI	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103	Installation of a Replacement Caution Warning Panel	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25.1316, IR - Lightning See and FAR 25.1317, Amdt 25-122 (HIRF)elected to comply by applicant, which is equivalent to SC...	Installation in accordance with Global Aviation Technologies MasterDocument List MDL 1508-31503, Revision D.Maintenancein accordance with Global Aviation Technologies Instructionsfor Continued Airworthiness ICA 1508-31503, Revision C.or later revisions of the above listed documents approved by EASA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/10/2014	Active	10050582
10050612	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges	REV. 3		737-8 737-600, 737-700, 737-800 737-300, 737-400, 737-500	Installation of Cargo Seat Bags in Boeing 737-300, 737-400,737-500,737-600, 737-700, 737-800,737-8.Revision 3 extends the applicability to 737-8 series, introduces newseat types and a new seat cargo bag and adjusts the Cert Basis.	- 737-600/-700/-800 - The Certification Basis for the original productas amended by the following additional or alternative airworthinessrequirements:- Special Condition(s):STC CRI D-01 Installation of cargo seat bags in Boeing737-300/-400/-500/-600/-700/-800/-8.STC CRI D-02 Installation of Cargo se...	- Engineering Order EO_M23800101_MZI_030420 14 Revision 3;- Instructions for Continued Airworthiness ICA_M23800101_MZI_03042014Revision 2;- Aircraft Flight Manual AFS_M23800101_MZI_02052014 Revision 2;- Aircraft Manual Supplement AMS_M23800101_MZI_02052014 Revision 2;or later revisions of the above l...	- Per Aircraft Flight Manual AFS_M23800101_MZI_02052014 Revision 2.- Instructions for Continued Airworthiness CA_M23800101_MZI_03042014Revision 2.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed d...	18/12/2018	Active	10050612
10050614	BOMBARDIER Inc.	REV. 1		CL600-2B16	Introduction of Replacement Stand by Altimeter STC transfer	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Ltd Master Document List No. S21.M02-1165 Issue 4 dated22 September 2014.	For Aircraft MSN 5001-5194: Bombardier Aerospace Service Bulletin601-0490 (Lighting Power Supplies – Separation of AC and DC Connections)must be incorporated prior to embodiment of this design change.For Aircraft MSN 5301-5320: Bombardier Aerospace Service Bulletin604-33-002 (Standby Instrument Inte...	23/09/2015	Active	10050614
10050616	AERO-DIENST GMBH & CO. KG			CL-600-2B16	Aspire 200 Satcom System installation (Honeywell)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero-Dienst AFM Supplement No 272-CL. 071 Rev IR.or later revisions of the above listed documents approved by EASA.EASA Accepted - Aero-Dienst Engineering Order No. 272-CL.056.01 Revision3 dated 24.09.2014	Installation of EASA STC No. 10050359 is a prerequisite forthis STC	25/09/2014	Active	10050616

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050628	AVIONITEC AG			M20K M20J	GNS-430/530 upgrade to GNS-430W/ 530W incl. LPV CertificationOut: GNS-430/530 system incl. non EGNOS antennaIn: GNS-430W/530W system incl. GA-35 antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement No. 3754-011 Rev.1 of 11.06.2014Modification Instruction No. 3754-011 Rev.0 of 11.06.2014or later revisions of the above listed documents approved by EASA.Master Document List No. 3754-017 Rev.0 of 11.06.2014Instructions for Continued Airworthiness No. 3754-017 Rev....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/09/2014	Active	10050628
10050643	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 727-212	Installation of a Dual Iridium Antenna	The Certification Basis for the original product as amendedby thefollowingadditional or alternative airworthiness requirements:FAR 25 at Original Issue:25.1(a), 25.25(a) , 25.27(b), 25.29(a)(1)25.301(a), 25.303, 25.305(a)&(b)25.307(a), 25.331 , 25.341, 25.35125.365,25.571,25.601,25.603(b)&(c)25.605...	Instructions for Continued Airworthiness: BAC-928ICA01 Issue 3, 'BoeingB727<(>,<)>Installation of a Dual Iridium Antenna'or later revisions of the abovelisted documents approved by EASA.	Aircraft Serial Number: 21460 only.Prior to installation ofthis design change it must be determined thattheinterrelationship between this design change and any other previouslyin-stalled design change and/or repair will introduce no adverse effectupon theairworthiness of the product.	29/09/2014	Active	10050643
10050666	SOCIETE AIR FRANCE S.A.	REV. 2		777-300ER	B773 BEST Cabin reconfiguration [Installation of B/E Aerospace First Class seats (Oasis); Zodiac SeatFrance Business class (Cirrus) and Economic class seats (Z301).Modification of B/E Aerospace Premium Economic class seats. Installationof new partitions and stowage as well as modification of existing...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):- CRI D-02 (Single Side Facing Seats)- CRI D-03 (Seats with Inflatable Restraints)The requirements for environmental protection and the associatedcert...	- Change Approval Sheet, Air France document No. CAS-B777-12-007,Revision 4, dated 12 August 2015- Aircraft MaintenanceManual Supplement, Air France document No.AMMS-B777-12-007-001, Revision 0, dated 31 July 2014or later revisions of theabove listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/08/2015	Active	10050666
10050676	AVIATION DEFENSE SERVICE			F 406	AVD-MF406-95-ISR1A Issue 01 - Carriage of Airbus D<(>&<)>S ISR missionsystem	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement SAFM-AVD-F406-ISR ed1 dated 24 Sept 2014Instruction For Continued Airworthiness ICA-AVD-F406-ISR Ed2 dated 24Sept 2014Master Document List MDR-AVD-ISR1A iss 01 dated 24 Sept 2014or later revisions of the above listed documents approved by EASA.	Limitation to serial number 0013.	30/09/2014	Active	10050676
10050677	LUFTHANSA TECHNIK AG			747-8	New Premium Economy Class for B747-8In the main cabin of the main floor on the aircraft, the change consistof the removal of 10 per cent of the Economy Class Seats between door 3and door 4 and the installation of new developed Premium Economy Seatsinstead. The new seating will have a greater pitch a...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD25-13/37M issue1 rev 1- ICA, ref A-00-14/45-ICA, Issue 1 rev 0- ComplianceRecord List CRL25-13/37M iss 1 rev 2or later revisions of the above listed documents approved by EASA.	This modification must be installed in conjunction with SB AIMB747-25-172 (Introduction of a three part class divider installation)according to the designPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously ins...	30/09/2014	Active	10050677
10050685	ARMSTRONG AEROSPACE		FAA STC ST03332CH	A320-214	Installation of a Tune Box wireless In-Flight Entertainment(IFE) System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged andremain applicable to this certificate/ approval.	- Master Data List, Armstrong Aerospace document No. DC104-9281-00,Revision D, dated 8 May 2014- Instructions for Continued Airworthiness, Armstrong Aerospace documentNo.DC113-9281-00, Revision D, dated 5 May 2014- Airplane Flight Manual Supplement, Armstrong Aerospace document No.DC303-9281-00, Rev...	- Modification in accordance with this STC requires prior or concurrentinstallation of Armstrong Aerospace STC ST03333CH, validated by EASA,installation of a Cobham SBB SATCOM System-Modification in accordance with this STC requires prioror concurrentinstallation of Armstrong Aerospace STC ST03247...	01/10/2014	Active	10050685

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050690	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	SWS/C/3134 - STG AEROSPACE PHOTOLUMINESCENT UNIVERSAL SYMBOLIC EXITIDENTIFIER SIGNS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01Other: CS 25 Amdt 14The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the originalu...	-Master Configuration Scheme 3134-MCS-01 Iss 3 dtd. 30.September 2014- Instructions for Continued Airworthiness per Maintenance ManualSupplement 3134-MMS-01 Iss 2 dtd. 29. September 2014.or later revisions of the above listed documents approved by EASA.	1.THE PHOTOLUMINESCENT EMERGENCY EXIT SIGNS OF THIS STC MAYONLY BE USEDTO REPLACE SIGNS MOUNTED ON ITEMS SUCH AS BULKHEADS, CLASS DIVIDERS ETC.IN CABIN OCATIONS AWAY FROM EMERGENCY EXITS. SUCH EMERGENCY EXIT SIGNSARE NOT REQUIRED BY CERTIFICATION REGULATIONS TO BE ELECTRICALLYILLUMINATED, ALTHOUGHS...	01/10/2014	Active	10050690
10050691	APTOZ EHF.	REV. 1		757-200	Equipment/Furnishings - Passenger Compartment - Installation of50F/4C/8Y Passenger Configuration with Avio ZEUS Lie Flat SeatsRev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Change/Repair Approval, Icelandair document No. CRA-757-2520-407,Revision A, dated 30 September 2014- Continued Airworthiness Instructions, Icelandair document No.CAI-757-2520-407, Revision A, dated 30 September 2014or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10050691
10050697	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		BD-700-1A10	Satellite Communication Systems InstallationRev. 1: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS-25 Amendment 14:25.1, 25.23, 25.25, 25.27, 25.301, 25.303<(>,<)>25.305, 25.307, 25.385, 25.561, 25.571<(>,<...	Aviation Traders Ltd - Master Document List MDL-12576-00001, Issue 4,dated 30/09/2014or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Aircraft Serial Number 9098 OnlyPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	10/11/2021	Active	10050697
10050705	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	777-300 ER	China Airlines Boeing 777-300ER Skycouch Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration SchemeNo.3128-MCS-01 Issue 2	Skycouch can only be used as a sleeping area or as an accommodationarea, as detailed in SWS Certification Services Ltd Design Report3128-DR-01, during in-flight conditions.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any o...	02/10/2014	Active	10050705
10050732	DART AEROSPACE Ltd.		TCCA SH13-44	R 66	D066-1002 Cargo Mirror Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions IIN-066-1002 Revision B, dated 13November2013 or later revisions of the above listed documents approved by EASAin accordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.- Master Document List MDL-D066-1002-1, Revision B, 31 July 2014- Airw...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/10/2014	Active	10050732

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050735	PAUSTIAN AIRTEX GmbH			A321-211	Business Class Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Report CR-DP097 Rev. 00, dated 04/10/2014Design Report DR-DP097 Rev. 00, dated 12/09/2014Master Documentation List MDL-DP097 Rev.00, dated 01/10/2014Instructions forContinued Airworthiness ICA-DP097 Rev. 01, dated01/10/2014or later revisions of the above listed documents approved by E...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/10/2014	Active	10050735
10050741	DAO AVIATION A/S			B200, B200C	Installation of Dual Garmin GTX-33D transponders for ElementarySurveillance, including ADS-B Out Functionality under DAO modificationref DAO-DO-0540.	As defined in DAO document ref DAO-DO-0540-CIP-02 dated 2.10.2014.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with DAO Aviation A/S modification 0540, asdefined in Engineering Change Order DAO-DO-0540-ECO-01 dated 25.09.2014.Operation in accordance with DAO Aviation Flight Manual Supplement(AFMS) DAO-DO-0540-AFMS-01 dated 02.10.2014.Instructions for Continued Airworthiness (ICA) a...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/10/2014	Active	10050741
10050748	DART AEROSPACE Ltd.		TCCA SH14-28	R 66	D066-1003 Interior Protector Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions IIN-D066-1003, Revision A or later revisionsof the above listed documents approved by EASA inaccordance with theTechnical Implementation Procedures of EU/ Canada Bilateral Agreement.- Master Document List MDL-D066-1003-1, Revision B, 31 July 2014- Airworthiness Compliance2...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/10/2014	Active	10050748
10050751	TESTORI AERO SUPPLY S.R.L.			B777-200ER, B777-200	Flight attendant seat cushion foams replacement	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List, Testori document No. TAS-STC-B777FA-01-2014,Revision 2, dated 22 September 2014- Master DrawingList, Testori document No. TAS-STC-B777FA-MWL-01,Revision N/A, dated 31 July 2014or later revisions of the above listeddocuments approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/10/2014	Active	10050751
10050757	AVMAX AVIATION SERVICES Inc.	REV. 1	TCCA STC SA10-97, REV. 3	DHC-8-301/-311/-314/-315 DHC-8-201/-202 DHC-8-102/-103/-106	Installation of a Universal Avionics UNS-1 Lw Flight Management System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	See EASA Approved Annex	Antenna structural provisions provided under the latest applicablerevision of EASA STC MOT.21NE2.139 are required.Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/or repair willa...	03/11/2014	Active	10050757

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050758	DART AEROSPACE Ltd.	REV. 1	TCCA SH10-48 ISSUE 4	R 44, R 44 II	CONFIGURATION A- Quick release mounting provision: Installation asdefined in Aero Design Ltd DCL906-1, Revision 1, dated 2 June 2014, orlater TCCA approved revisionCONFIGURATION B- External Cargo Basket: Installation as defined in AeroDesign DCL906-2, Revision 1, dated 2 June 2014, or later TCCA app...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CONFIGURATION AAero Design Instructions for Continued Airworthiness ICA 906.91,Revision 2, dated 27 May 2014.CONFIGURATION BAero Design Flight Manual Supplement FMS906.90, Revision 1, dated 27 May2014.Aero Design Instructions for ContinuedAirworthiness ICA906.92, Revision2, dated 27 May 2014.CONFIG...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/11/2021	Active	10050758
10050764	AIRGLAS, Inc.		FAA SR02431AK	R 44, R 44 II	Installation of the LAM-R44 Portable Device Mount	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement AI-LRSCE-R44-FM, Rev. Orig., datedAugust 20, 2014 or later revisions of the above listed documentsapproved by EASA in accordance with EASA ED Decision 2004/04/CF (orsubsequent revisions of this decision) and/ or the TechnicalImplementation Procedures of EU/ USA Bi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/10/2014	Active	10050764
10050767	LUFTHANSA TECHNIK AG	REV. 2		737-300, 737-500	TCAS II version 7.1 upgradeRev1: update of documentation listRev2: update of documentation list	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Definition Document STDD34-14/19M rev 01/00Instructions for Continued Airworthiness A-00-14/25-ICA rev 01/00or later revisions of the above listed documents approved by EASA.	- Pilots are authorized to deviate from their current ATC clearance tothe extent necessary to comply with a TCAS II resolution advisory. WhenTCAS II voice message "CLEAR OF CONFLICT" is announced, the pilot mustpromptly return to the previous ATC clearance.- Maneuvers must not be based solely on inf...	24/07/2015	Active	10050767
10050772	AVMAX AVIATION SERVICES Inc.	REV. 2	TCCA STC SA11-57, ISSUE 2	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-301/-311/-314/-315 DHC-8-201, DHC-8-202 DHC-8-201/-202 DHC-8-102, DHC-8-103 DHC-8-102/-103/-106/	Installation of a Universal Avionics UNS-1Ew Flight Management System.Revision 2: this revision was issued based on TCCA STC SA11-57, issue 4and adds an additional configuration to allow use of the MLS channel ofthe Autopilot. Configurations 117366-421, -422, -423, -424 andcorresponding AFMS 117366-...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Deviation(s): F-103, Use of “MLS” instead of “LPV”, issue 04The requirements for environmental protection and the associatedcertified noise and/ or emissions...	The change is defined with Avmax Master Data List Document 117366-400,Issue 28, dated 19/JUL/2019.The aircraft configuration is defined with one or more of the followingEngineering Orders:-) 117366-401, Rev. 10, dated 25/MAR/2014, Dual Universal AvionicsUNS-1Ew FMS Installation-) 117366-402, Rev. 6,...	This approval does not cover the structural provisions of the antennainstallation. EASA STC 10059623 or another EASA approved antennainstallation shall be installed prior to or inconjunction with thischange.Prior to installation of this change/repair it must be determined thatthe interrelationshipp...	30/06/2022	Active	10050772
10050775	TASS-EU Ltd.		CAA UK RESPONSIBILITY	A330-200	Passenger Seats - Refurbishment and Installation of IFE provisions	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt. 14: VariousThe requirements for environmental protection and the associatedcertified noise and/ oremissions levels of the original product areunchanged and re...	TASS-EU LTD Master Document List No. 132192 Issue Original dated30/09/14	Restricted to MSNs 463 and 504	10/10/2014	Active	10050775
10050777	GULFSTREAM AEROSPACE Ltd.		CAA UK RESPONSIBILITY	GV-SP	Mid Cabin Pocket Door Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): CRI D-01 Installation of Interior DoorsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origin...	Gulfstream AFMS No. GAeL 14-41-AFMS Revision -or later revisions of the above listed documents approved by EASAGulfstream Design Change Record No. GAeL 14-41-C.RCD, Revision New,Dated 09 October 2014	EASA STC No. 10015929 is a pre-requisite for this STC	10/10/2014	Active	10050777

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050778	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	A330-341/-342/-343 A330-321/-322/-323 A330-223F/-243F/-301/-302/-303 A330-201/-202/-203/-223/-243	FANS A+ Over the Iridium Network.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List - S21.MDL-1143 Issue 4.Minor Design Change S21.34-71-1188.	1. Airworthiness approval of this design change does not constituteoperational or certification approval for FANS operation. The FANSsystem must be existing and must be approved.2. Prior to the introduction of this design change it must beensuredthat the aircraft is provisioned with an ICS-220A dua...	22/05/2018	Active	10050778
10050783	PMV ENGINEERING			B737-600/-700/-800/-900	Mark II Aircraft Communications Addressing and Reporting System (ACARS)installation on B737-600/-700/-800/-900.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Allapplicable paragraph(s) at a later amendment:CS-25 at amendment 10The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	- Certification Investigation Report AVI-0008-CIR-R04 dated10/10/2014- Aircraft Flight Manual Supplement AVI-0008-AFMS-R01 dated 17/01/2011- Instructions for Continued Airworthiness AVI-0008-ICA-R02 dated8/02/2012or later revisions of theabove listed documents approved by EASA.	None	10/10/2014	Active	10050783
10050784	B.A.S., INC.		FAA STC SA01085SE	SEE EASA APPROVED MODEL LIST	Installation of BAS, Inc. Shoulder Harness in accordance with theappropriate BAS Report/Drawing as listed on EASA Approved Model List (AML), or later approved revisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with BAS Inc reports and drawings as definedin the attached AML list.or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisdecision) and/ or the Technical Implementation Procedures of...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/10/2014	Active	10050784
10050787	E A D AEROSPACE AIRWORTHINESS	REV. 1		B777-300ER	Cabin reconfiguration for LATAM in Brazil	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, EAD Aerospace document No. 01423-EAS-A-MDL, Revision B<(>,<)> dated 23 October 2014.or later revisions of the above listed documents approved by EASA.	None.	05/11/2014	Active	10050787
10050794	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02893CH	767-300F 767-300	Installation for a Rockwell Collins SATCOM 2100 System:-Configuration 1: for Aircraft without existing Boeing SATCOM provisions-Configuration 2: for Aircraft with existing Boeing SATCOM provisionswith partial Boeing SATCOM provisions (HF/SAT panel installed in P6Panel)-Configuration 3: for Aircraft(...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amdt 6: 25.29<(>,<)> 25.301<(>,<)> 25.303<(>,<)> 25.305<(>,<)>25.307<(>,<)> 25.561<(>,<)> 25.601<(>,<)> 25.603<(>,<)> 25.605<(>,<)>25.609<(>,<)> 25.611<(>,<)> 25.613<...	Master Data List ECS-207397 rev For later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.Instructions for Continued Airwort...	- Limitations as per instructions for continued airworthiness ECS-207406- FAA STC ST02893CH to be installed prior to orin conjunction with thechanges of this certificate.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any ot...	13/10/2014	Active	10050794
10050795	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02888CH	767-300F 767-300	Installation of an Intermediate Gain Antenna (IGA) subsystem:- configuration 1: for aircraft without existing SATCOM antennaprovisions from Boeing- configuration 2: for aircraft with existing SATCOM antenna provisionsfrom Boeing- configuration 3: installation of IGA provisions for aircraft withoutex...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amdt. 6: 25.29<(>,<)> 25.251<(>,<)> 25.301<(>,<)> 25.303<(>,<)>25.305<(>,<)> 25.307<(>,<)> 25.321<(>,<)> 25.365<(>,<)> 25.561<(>,<)>25.571<(>,<)> 25.581<(>,<)> 25.601...	Master Data List ECS-207305 rev For later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.Instructions for Continued Airworth...	As per instructions for Continued Airworthiness ECS-207306Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repairwill introduce noadverse effect upon the airworthiness of th...	13/10/2014	Active	10050795

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050800	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	A330-200	IFE INSTALLATION STCInstallation of a new IFE system on a cabin configuration for TurkishAirlines.Rev.1: Transfer of STC ownership from JAMCO AERO DESIGN & ENGINEERING toSTC TWENTY ONE LIMITED	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Refer tosection 7 in Certification Summary JD-40AC10-1, rev AThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	- MASTER DATA LIST : JD-40AC02-1, rev B- ICA & EWIS for Continued Airworthiness : JD-40AC04-1, rev 1- Certification Summary Report : JD-40AC10-1, rev A- AFM Supplement : AFM-THY40A-1 rev 2or later revisions of the above listed documents approved by EASA.	This STC is concurrent and must to be embodied with STC 10050775(Passenger seats - refurbishment and Installation of IFE provisions) foraircraft installation.The following are required as pre-requisite for the installation of thisSTC-EASASTC EASA.A.A01077 (Cabin modification)- Minor Change Modific...	24/05/2016	Active	10050800
10050808	DELTA ENGINEERING CORPORATION		FAA STC ST02923NY-D	A330-200/-300	Installation of Panasonic Global Communication Suite	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Refer to section 3 in Compliance Summary Report ref 6654-08521-2305 revBThe requirements for environmental protection and the associatedcertified noise and/or emissions le...	-,,MASTER DATA LIST : ref 0154-08031-2305, rev E-,,ICA & EWIS for Continued Airworthiness: ref 0754-08035-2305<(>,<)> ,,rev D- ,,Compliance Summary Report Project results: ref 6654-08521- ,, 2305, rev B- ,,AFM Supplement: ref 0654-08979-2305, rev -- ,,FAA Letter "EASA Approval of FAA Supplemental Ty...	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2) For The Airworthiness Limitations, refer t...	14/10/2014	Active	10050808
10050817	ISRAEL AEROSPACE INDUSTRIES, LTD.IAI	REV. 1	TCCA SA276	737-900 737-900ER 737-600, 737-700, 737-800 737-300, 737-400, 737-500	Rev 0: Towing airplane by towbarless tractor TaxiBot NB.Rev1: Inclusion of Boeing 737-NG Models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-01 Issue 4 dated 14.03.2016The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchan...	AFMS: “B737-300/400/500/600/700/700C/800/900/900ER AIRPLANEFLIGHTMANUAL (AFM) SUPPLEMENT No.1 - TAXIING USING TAXIBOT”, Rev. N, dated25-02-16.or later revisions of the above listed documents approved by EASA.737 Classic models (737-300/400/500) COMPLIANCE CHECK LIST (CCL), Ref. TXB090/110064, Rev.F7...	As per AFMS “B737-300/400/500/600/700/700C/800/900/900ER AIRPLANE FLIGHTMANUAL (AFM) SUPPLEMENT No.1 - TAXIING USING TAXIBOT”, Rev. N, dated25-02-16.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installe...	13/04/2016	Active	10050817
10050823	AEROTEC & CONCEPT			MF900	Self-polarizing Cabin Solar Protection System installation on MystèreFalcon 900 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AEROTEC Master Data List doc. N° AE13242MDL Rev.0 dated 10.10.2014Aircraft Flight Manual doc. N° AE13242AFMS Issue 0 dated 16.06.2014Instructions for Continued Airworthiness doc. N° AE13242ICA Issue 0dated 20.02.2014or later revisions of the above listed documents approved by EASA.	Applicable to MSN 064Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect uponthe airworthiness of the product.	14/10/2014	Active	10050823
10050837	AIRFILM CAMERA SYSTEMS, INC		FAA STC SR02452LA	BELL 429	Nose Utility Mount Light Kit AFM-NM429LK-1.The light kit consists of two mounting brackets and two Teledyne LEDwhite bulbs landing light assemblies. This installation is eligible forBell 429 helicopters with Airfilm Camera System STC 10039428 installed.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airworthiness Limitation Section of Instructions for ContinuedAirworthiness AFM-NMLK-008, Rev. N/C, dated August 25, 2012.or later revisions of the above listed documents approvedby EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Im...	This installation is only eligible for Bell 429 rotorcraft equipped withAirfilm Camera System EASA STC number 10039428Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repaira...	16/10/2014	Active	10050837

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050842	FIELD AVIATION EAST, LTD.	REV. 2	TCCA O-LSA13-137/D	DHC-8-311	Universal UNS-1E(w) and UNS-1F(w) Flight Management System Installation.The installation options are based upon converting older single or duallegacy equipment with the latest technology.Revision 1 of this STC was issued to include LPV operation (SN 592) (CRIF-102, issue 2)Revision 2 of this STC was...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): F-102, issue 2, Use of “MLS” instead of LPV.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	DHC-8-311, UNS-1E(w) Installation (SN 407, SN 493, SN 495, SN 532, SN535) (SW, SCN 1000.x) Installation must be performed in accordance with FACI Master Drawingand Data List designated25850000 Rev A.Flight operations must be performed in accordance with FACI FlightManual Supplement designated25853000...	Limited to SN 236, SN 238, SN 407, SN 493, SN 495, SN 532, SN 535, SN592DHC-8-311, UNS-1E(w) Installation (SN 407, SN 493, SN 495, SN 532, SN535)•,,UNS-1E(w) Flight Management Systems approved for IFR En-route,Terminal and Non-Precision approach operations only.•,,The installation of Honeywell Symbo...	09/10/2019	Active	10050842
10050847	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	787-9	UCS3 Berth Activation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ICA : Maintenance Manual Supplement 3132-MMS-01 issue 2Design Report 3132-DR-01 issue 1Master Configuration Scheme ref 3132-MCS-01 issue 1or later revisions of the above listed documents approved by EASA.	1) The UCS3 bed configuration is for in-flight use only andthe bed isto be returned to the seat configuration for taxi, take-off and Landing2) SWS Minor Change SWS/C/3137 (Decompression grille replacement) has tobe installed to complete the full embodiment approval of this change3) Prior to install...	16/10/2014	Active	10050847
10050848	FLYBE LIMITED		CAA UK RESPONSIBILITY	DHC-8-402 DHC-8-401	Installation of Tropospheric Airborne Meteorological Data Reporting (TAMDAR) System, DHC-8-400	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation:Must be in accordance with Flybe Engineering Order D3102-002, RevisionA.Operation:Must be in accordance with Flybe AFM Supplement RE2112-18, Issue 1.Continued Airworthiness:Must be in accordance with Flybe ICA RE2112-05, Issue1.or later revisions of the above listed documents approved...	None	17/10/2014	Active	10050848
10050849	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	787-8	STG Aerospace SafTglo Photoluminescent Floor Proximity Emergency EscapePath Marking System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amendment 14 various.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and...	SWS Certification Services Ltd Airplane Flight Manual Supplement No.3133-FMS-01 Issue 1 dated 29 September 2014.or later revisions of the above listed documents approved by EASA.SWS Certification Services Ltd Master Configuration Scheme No. 3133-MCS-01 dated 29/09/14.	None.	17/10/2014	Active	10050849
10050851	I.A.C. - INDUSTRIAS AERONAUTICAS DECOIMBRA, Lda.			CESSNA 206 SERIES	Modification for skydiving operationIt includes a sliding door, the removal of the co-pilot control wheel,and the introduction of an instrument panel protection, a static lineparachutes support, and a parachutist’s platform fixed to the wheel nutand in the foot step of the right landing gear leg. Th...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:SC-O23-div-01 Parachuting ActivityThe requirementsfor environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchan...	AFM Supplement For Parachuting Modification IAC-C206-AFMS ED 1or later revisions of the above listed documents approvedby EASA.IAC.C206.MDL Master Document List issue 1 11-02-2014FORM IAC21.001 Project Dossier issue 1 16-01-2014IAC-C206 Annex I Manufacturing issue 1 16-01-2014IAC-C206 Annex II Oper...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	17/10/2014	Active	10050851

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050855	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 2		A321-231	Cabin Interior Reconfiguration of British Airways aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0578-D90, Revision -, dated 7 February 2017.- Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0464-D70, Revision C, dated 20 January2017;or later revisions of the above listed d...	British Airways Minor Change Service Bulletins SB A321-25-0019 and SBBA-321-25-0024 shall be concurrently installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair wi...	08/02/2017	Active	10050855
10050856	S4A SOLUTIONS FOR AVIATION, S.L.			172Q, 172R, 172S 172K, 172L, 172M, 172N, 172P 172E, 172F, 172G, 172H, 172I 172, 172A, 172B, 172C, 172D	Fuselage cutouts in Cessna 172.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI O-11 Banner towingThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product...	-Installation in accordance with: Service Bulletin, ref: 17202-SB001,edition 1, dated July 16, 2014.- Instructions for Continued Airworthiness in accordance with:Maintenance ManualSupplement, ref. 17202-HDK02, edition 1, dated July17, 2014or later revisions of the above listed documents approved by...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/10/2014	Active	10050856
10050861	MT-PROPELLER ENTWICKLUNG GmbH	REV. 5		B300C B300 300LW 300/300LW, B300, B300C 300	Installation of MTV-27-1-( )-C-F-R(P)/ CFR260-65( ) Propeller onBeechcraft King Air 300, 300LW, B300, B300C Series with Pratt & WhitneyPT6A-60A engines and Maximum Take Off Weight up to 7'938 kg (17'500 lb).Installation of MTV-27-1-( )-C-F-R(P)/CFR260-65( ) Propeller onBeechcraft King Air B300, B300C...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase and/or emiss...	For P<(>&<)>WC PT6A-60A enginesAccording to MT-Propeller Master Documentation List No. E-2478 Rev. 5For B300(C) with P<(>&<)>WC PT6A-67A engines:According to MT-Propeller Master Documentation List No. E-3745 Rev. 4Applicable to all aircraft and engine models:To be operated in accordance with MT-Prop...	According to limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/01/2024	Active	10050861
10050867	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	747-8F 747-8 747-400F 747-400 (BCF) 747-400 747-300 747-200F 747-200C 747-200B 747-100	Honeywell TCAS 7.1 System Upgrade on Boeing 747 Aircraft For HoneywellSystems.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissionslevels of the original product are unchanged and remain applicable tothis certificate/approval.	Airplane Flight Manual Supplement H4AFMS036 Issue IRModification Summary Sheet MOD H4A 1715 Issue 3or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any other previouslyinstalleddesign change and! or repairwill introduce no adverse effect upon theairworthiness of the product.	21/10/2014	Active	10050867
10050868	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	757-300	Galley 4A in B757-300 for Condor	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 14 VariousThe requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and...	AIM Aviation Master Drawing List No. MDL-7573FC4AGB00 Issue1	AMES Minor Modification No. MICA-M15400166.14052014-JTU-20052014 is apre-requisite for this STC	21/10/2014	Active	10050868
10050869	EMTEQ CANADA Ltd.		TCCA STC C-LSA14-145/D ISSUE 1	BD-700-1A10	Installation, Iridium Antenna (Structural Provision)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissionslevels of the original product are unchanged and remain applicable tothis certificate/approval	EMTEQ Canada Ltd. Modification Data Summary J793000RevisionN/C	Restricted to ASN 9083	21/10/2014	Active	10050869

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050875	HAECO CABIN SOLUTIONS, LLC		FAA STC NO. ST04166AT	767-300	Interior Reconfiguration of a Boeing 767-300 Aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA STC No. ST04166AT dated 17 October 2014. TIMCO Aerosystems MasterData List 13T446L001, Revision A, dated October 17,2014.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/10/2014	Active	10050875
10050885	GE AVIATION SYSTEMS L.L.C.			727-200, 727-200C 727-100, 727-100C	Installation of a Smiths Industries Combined Voice and Flight DataRecord	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Defined in CCL attached to Applicant letter 16 June 2014, as submittedby FAA to EASA.The requirements for environmental protection and the associatedcertified noise and/ o...	AFM Supplement, Smiths Industries Doc YV1853 Rev X1, FAA approved29/08/2002Smiths Industries Drawing No. 176879, Revision B, dated July 25, 2002	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/10/2014	Active	10050885
10050890	S4A SOLUTIONS FOR AVIATION, S.L	REV. 1		AS 350 BB, AS 350 B2	Initial issue:Installation of a wire strike protection system consisting of upper andlower cable cutter, nose area deflector, optional VXP camera support,aft canopy reinforcement and windscreen wipers protections forrotorcraft model AS 350BB.Rev. 1:Expansion of the applicability to rotorcraft model...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 27 Amdt 45 paragraphs: 27.1, 27.2, 27.21, 27.25, 27.27, 27.251,27.301, 27.303, 27.305, 27.307, 27.321, 27.337, 27.471, 27.561, 27.571,27.601, 27.603, 27.605, 27.607, 2...	Flight Manual Supplement for Wire Strike Protection System in AS350BB,doc. no. 35032-HDK01 Ed. 03 dated 26/09/2014.Flight Manual Supplement for Wire Strike Protection System in AS350B2,doc. no. 35032 II-HDK01 Ed. 03 dated 24/09/2015.or later revisions of the above listed documents approved by EASAIn...	For rotorcraft model AS 350 B2 this STC is only applicable if EurocopterSB 53.00.39 is installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadve...	30/09/2015	Active	10050890
10050891	CEAPR			R 2160I R 2120U, R 2160, R 2160D R 2100, R 2100 A, R 2112 HR 200/160 HR 200/120, HR 200/120 B HR 200/100, HR 200/100 S	DET131201 Revision 0 dated 13 December 2013 - After sales parts forHR200/R2000	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	or later revisions of the above listed documents approved by EASA.	Limitations to HR200/R2000 from serial number 001 up to 378included.	22/10/2014	Active	10050891
10050902	AVIONIK STRAUBING ENTWICKLUNGS GmbH			A109E, A109S	Installation of Dual Garmin GTN 650	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:EASA CS-ACNS Subpart BThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and rem...	Approved Flight Manual Supplement for COM/NAV/ GS/GPS GarminGTN650,ASR-2014-004-FMS-05.1-00, dated 16.10.2014 (A109E S/N 11002 - 11077 withEmergency Busbar kit; S/N 11078 and above, A109S all S/N)Approved Flight Manual Supplement for COM/NAV/GS/GPS Garmin GTN650,ASR-2014-004-FMS-05.2-00, dated 16.10...	None	23/10/2014	Active	10050902
10050930	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CITATION BRAVO	P-RNAV Capability with Universal UNS-1 K+ FMS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cessna Düsseldorf Airplane Flight Manual Supplement, 2014-5-8, rev IR,dated 12 March 2014Cessna Düsseldorf Master Document List, 2014-5-16, rev IR, dated 10October 2014or later revisions of the above listed documents approved by EASA.	None	27/10/2014	Active	10050930

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050942	PMV ENGINEERING	REV. 2		A321-251N/-253N/-271N/-272N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-251N/-271N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	TCAS 7.1 upgrade installation on A320 family:Initial STC: Installation of TCAS/ ACAS 7.1 as per EC/IR 1332/2011 andcompliance to EASA AD_US_2012-02-08 recommendationsRev 1: Introduction of multiple configurations (Collins, ACSS andHoneywell)Rev 2: Introduction of a new ACSS configuration and change o...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List AVI-00690-MDL-R23, dated 05 Oct. 2017Aircraft Flight Manual Supplement AVI-00690-AFMS-R02, dated 26/03/2015Instructions for Continued Airworthiness AVI-00690-ICA-R04, dated 05Oct. 2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/10/2017	Active	10050942
10050952	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 1		BO105 LS A-1, BO105 LS A-3, BO105 A, BO105 C, BO105 D	Installation of the HELICOM V2 ANA Flight Data Monitoring andTransmitting system.The proposed change is described in ISEI document N3-BO105-HV2-ANA andconsists of two possible configurations. The first configurationcomprises P/N4720F and P/N4730F, the second configuration comprisesP/N4720P and P/N47...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Lithium Battery Installation DatedOctober 2nd, 2014.The requirements for environmental protection and the associatedcertified noise and/ o...	Rotorcraft Flight Manual Supplement FFMS N11-BO105-HV2 ANA-E-B-02-Rev.01<(>,<)>or later revisions of the above listed documents approved by EASA.Certification Program N2-BO105-HV2ANA Rev. 02, dated October 27th, 2014.Installation Manual N7-BO105-HV2 ANA E-B-02, Rev.02, dated October 27th,2014.Instru...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2020	Active	10050952
10050956	ARCHEION HOLDINGS, L.L.C.		FAA STC ST03689AT	B727-200/-200F	Installation of an Avionica satLINK Iridium SATCOM CommunicationManagement System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):H-01 ICA on EWIS- the following paragraph(s) at a later amendment:CS25 amdt 4: 25.29, 25.301, 25.303, 25.305, 25.307, 25.561, 25.571,25.581, 25.601,...	Master Data List 080920-001-MDL Rev EAirplane Flight ManualSupplement 080920-503 Rev IRInstructions for Continued Airworthiness 080920-504 Rev CWeight and Balance Change Report 080920-510 Rev Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/...	As per Instructions for Continued Airworthiness 080920-504 lastrevision.	28/10/2014	Active	10050956
10050957	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 680 -CITATION SOVEREIGN	Installation of Swift Broadband System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Declaration of Compliance, Document of Cessna Düsseldorf Citation Rev. 2dated 24.10.2014Master Document List Ref. 2014-6-16 dated 16.10.2014Engineering Order Ref. 2014-6 dated 16.10.2014or later revisions of the above listed documents approved by EASA.	None.	28/10/2014	Active	10050957
10050967	TENENCIA Ltd.		CAA UK RESPONSIBILITY	MARK 050 AND 0502	Installation of a Single UNS-1Lw Universal Avionics Flight ManagementSystem with LPV	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Report Tenencia report TEN 714 Issue 1Certification Compliance Report Tenencia report TEN 714/1 Issue 2Flight Manual Supplement Tenencia report TEN 714/47 Issue 4Instructions for Continued Airworthiness Tenencia report TEN 714/4-3Issue 1or later revisions of the above listed documents a...	As defined in Flight Manual Supplement Tenencia report TEN 714/47 Issue4Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	29/10/2014	Active	10050967

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10050970	ALTRAN LABt/a AIRCAD			A321-213	Installation of two lower L-band ATG (P/N 2439-89-03) antennas and anupper GPS (P/N C17065AA) antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance Check List CCL-13010 Rev.1, dated 01/09/2014Master Data List MDL-13010 Rev.1, dated 14/10/2014Instructions for Continued Airworthiness ICA-13010 Rev.1, dated14/10/2014or later revisions of the above listed documents approved by EASA.	None	29/10/2014	Active	10050970
10050975	ASI INNOVATION			ERJ 170-200 LR	EMBRAER 175 CABIN MODIFICATION	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Data List ref. ASI-SDL-0242-02, dated 22/10/2014.or later revisions of the above listed documents approved by EASA.	Applicability limited to ERJ 170-200 LR model, S/Ns 283 & 288	29/10/2014	Active	10050975
10050984	AEROTEC & CONCEPT			B757-200	B757 WiFi activation for Vision Systems IFE suite.This modification consists in the activation of a WiFi System on aB757-200. The system provides airborne network server access totheaircraft's cabin passengers via Portable Electronic Devices (PED). Suchdevices could include laptop computers and WiF...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, AEROTEC n° AE14100MDL rev 1 dated 29/10/2014.or later revisions of the above listed documents approved by EASA.	1. To install this modification, the aircraft must have thefollowingminor modification already embodied (prerequisite configuration):AEROTEC AE14096.2. Aircraft configuration should be continuously checked againstcompatibility with this design change: refer to §6 of Instructions forContinued Airwor...	29/10/2014	Active	10050984
10050986	BOMBARDIER INC.		TCCA STC SA14-52 ISSUE 2	BD-700-1A11	Installation - Upgrade from Swift64 to Swiftfbroadband.EASAvalidation of Transport Canada's Supplemental Type CertificateSA14-52 at issue 2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification to be completed in accordance with Transport Canadaapproved EMTEQ Canada Ltd. Modification Data Summary Number J686000Revision N/C.For instructions for continued airworthiness, refer to J686070-ICARevision N/ C.or later revisions of the above listed documents approved by EASA inaccordanc...	None.	29/10/2014	Active	10050986
10050987	DELTA G DESIGN Inc.		FAA STC ST11125SC	737-700/-800/-900/-900ER 737-300/-400/-500/-600	Structural modification necessary for the installation of aDual IridiumAntenna.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt. 0: 25.571(a)(b), 25.613, 25.1419(a) CS25Amdt. 8: 25.23, 25.301(a) (b), 25.303, 25.305(a)(b) , 25.307 (a) ,25.321(b)(c)(d) , 25.333, 25.341(a) , 25.351, 25.561(c)2...	Master Data List DGD-RDUM02-MD-01 rev CInstructions for Continued Airworthiness DGD-RDUM02-IC-01 rev CWeight and Balance Report DGD-RDUM02-WB-01 rev Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decisi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/10/2014	Active	10050987
10050989	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST02913NY	A319, A320, A321	Installation of a Panasonic Avionics Corporation In-Flight Entertainmentand/or Global Communications Suite (GCS) System(with Demot option)The Revision 1 extends the STC applicability to Airbus A321, and providethe eXphone functionality.The Revision 2 updates the Master Data List 0164-07820-2301 for...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List 0164-07820-2301, Revision BB, dated25 April 2019, or later FAA approved revisions. The Instructions forContinued Airworthiness and Airplane Flight Manual Supplement, as listedon the Master Data List, are required with this installation.	1. Operational approval to use T-PED's must be obtained separately fromthis STC.2. FAA STC ST02890NY (Antenna) is required with this STC when installedconfiguration includes eXConnect or eXPhone.3. For configurations TL10694 and TL10697 FAA STC SA1682GL (Rack) or FAASTC ST09809AC (Rack) is required....	02/08/2019	Active	10050989

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051003	SABENA TECHNICS BGC			A330-243	Full Cabin Modification with Zodiac Inflight Innovations (ZII) Rave IFEinstallation/upgrade on A330-200This STC installs the Rave IFE system, which mainly consists in theintegration through the current cabin arrangement of System ControlUnit, Seat power Unit, Seat Display Unit, Crew Panel and Seat P...	CS 25 Amendment 4, except for 25.562 and 25.785 for which thecertification basis specified in EASA TCDS A.004 issue 36 applies.For detailed applicable requirements refer to the Certification Plan ref: 4633-02-A-2101-R02 section 3.4.The requirements for environmental protection and the associatedcert...	Master Data List, ref : 4633-02-A-2103-R00, dated 27 October 2014Instruction for Continued Airworthiness, ref : 4633-02-A-2211-R00, dated17 October 2014Aircraft Flight Manual Supplement, ref : 4633-02-A-2301-R00, dated 15October 2014or later revisions of the above listed documents approved by EASA....	1) This STC is applicable to MSN 313 only.2) STC 10014507 rev 1 (or later approved revision) - Installation ofnon-electrical Floor Path Marking System Guideline - must beconcurrently embodied. 3) Prior to installation of this design change it must be determinedthat the interrelationship between thisp...	30/10/2014	Active	10051003
10051007	ECMS AVIATION SYSTEMS GMBH	REV. 1		EC 155 B1 EC 155 B	External Load System on EC155Load systems, installed on thetie-down support threads of thehelicopter frame, used as hard points.	CS 29:CS 29.25, CS 29.27, CS 29.45, CS 29.65, CS 29.141, CS29.241, CS 29.251,CS 29.301, CS 29.303, CS 29.305, CS 29.307, CS 29.309, CS 29.321, CS29.337, CS 29.341, CS 29.571, CS 29.603, CS 29.605, CS 29.609, CS29.610, CS 29.611, CS 29.613, CS 29.625, CS 29.865, CS 29.1301, CS29.1309, CS 29.1323, CS...	Flight Manual Supplement "External Load System EDX01 on EC155", OriginalIssue dated 1st October 2014or later revisions of the above fisted documents approved by EASAMaintenance Manual / User Guide for EDX01 on EC155 (EDX01 / MM)Master Document List for EDX01 Load Attachment Device for rotorcraftEC15...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/11/2014	Active	10051007
10051008	FOKKER SERVICES B.V.	REV.1		A321-231, A321-232 A321-212, A321-213 A321-112, A321-131, A321-211 A320-232, A320-233, A321-111 A320-215, A320-216, A320-231 A320-211, A320-212, A320-214 A319-131, A319-132, A319-133 A319-113, A319-114, A319-115 A318-122, A319-111, A319-112 A318-111, A318-112, A318-121	TCAS Software Upgrade to TCAS V7.1This Major Change to STC 10051008 adds the ACSS T2CAS equipped aircraftto the eligibility of the STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval .	Certification Plan CP-0266 Issue 1Compliance Record Report CRR-0266 Issue 1or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/04/2015	Active	10051008
10051015	PWI Inc.D/B/A PWI		FAA STC SA01748WI	F) F90 E) C90, E90 D) 200, 200C, 200T, B200CT C) 100, A100, B100 B) B200, B200C A) C90A	Installation of Cabin LED Downwash Lighting.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of Cabin LED Downwash Lighting in accordance with PWIMaster Document List, No. MDL6910080, Rev. IR, dated 13 April 2013<(>,<) >or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision2004/04/CF (or subsequent revisions ofthis decision) and/ or...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/10/2014	Active	10051015
10051016	NORTHERN AVIONICS S.R.L.			A109A	NAV-490 "Installation of Garmin GTN 650 COM/NAV/GPS/SBAS NavigationSystem"	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:EASA CS-ACNS Subpart BThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and rem...	Rotorcraft Flight Manual Supplement RFMS NAV-490. Rev. 0, dated22.10.2014or later revisions of the above listed documents approved by EASA.Certification Program (includes Certification Basis), NAV-490, Issue C,dated 30.07.2014Modification Bulletin NAV-490, Rev. 0, dated 29.09.2014 (includesDrawing L...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/10/2014	Active	10051016

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051018	MECAER AVIATION GROUP S.p.A.	REV. 4		MBB-BK117 D-3 MBB-BK117 D-2 MBB-BK 117 D-2	Installation of EMS Interiors P/N 6E4M0000X001-001.Revision1 is to add the installation of a side facing seat bench ontheright-hand side of the cabin.Revision 2 is to extend theapplicability to MBB-BK117 D-3.Revision 3 is to close the post-approval action item related to theTransient Pressure Lev...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): FAR 29.807 Amdt. 30 Passenger emergencyexits (CRI D-01)The requirements for environmental protection and the associatedcertified...	Declaration of Compliance document number NDC 6E4MAD-025/III issue Adated 23.07.2021.RFM Supplement for “EMS INTERIORS Part Number 6E4M0000X001-001”,Supplement Number 6E4MRFM-1-1,Issue 1, Rev. 1 dated 31.08.2023.Owner's Manual (ICA) for “EMS INTERIORS Part Number 6E4M0000X001-001”,Supplement Number...	EMS Avionic Rack Installations P/N 6E4M3920A001-001/-003/-005 and FWDFull Medical Cabinet Installation P/N 6E4M2522A001-001/-003 are noteligible for installation on MBB-BK117 D-3.Applicable to Revision 4 of this STC:- Support installation P/N 6E4M2523A002-203 is not compatible withconfigurations 6E4...	20/09/2023	Active	10051018
10051023	BOMBARDIER INC.		TCCA STC Q-LSA02-071/D ISSUE 1	BD-700-1A10	Miscellaneous Cabin Modifications.EASA validation of Transport Canada's Limited Supplemental TypeCertificate Q-LSA02-071/D at issue 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The installation must be done in accordance with:MDL02166003, Aerocas Master Document List - Miscellaneous CabinModifications, Bombardier Global Express BD-700-1A10, aircraft serialnumber 9036, revision N/C, dated 29th November 2002.or later revisions of the above listed documents approved by EASAa...	Installation limited to aircraft serial number 9036.	31/10/2014	Active	10051023
10051024	BOMBARDIER INC.		TCCA STC Q-LSA04-053/D ISSUE 1	BD-700-1A10	Miscellaneous modifications of the cabin electrical system.EASA validation of Transport Canada's Limited Supplemental TypeCertificate Q-LSA04-053/D at issue 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The installation must be done in accordance with:MDL004132002, Aerocas Master Document List - Miscellaneous modificationsof the cabin electrical system-Bombardier Global Express BD-700-1A10aircraft serial number 9036, revision N/C, dated 12th July 2004.or later revisions of the above listed documen...	Installation limited to aircraft serial number 9036.	31/10/2014	Active	10051024
10051026	ASI INNOVATION	REV. 1		ERJ 170-200 LR	SATCOM System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Data List ref. ASI-SDL-0243-04, dated 30/10/2014.AFM Supplement ref. ASI-AFM-0243-02, dated 30/10/2014.ALS Supplement included in the Maintenance Planning Supplement ref.ASI-MPS-0243-08, dated 30/10/2014.or later revisions of the abovelisted documents approved by EASA.	Applicability limited to ERJ 170-200 LR model, S/Ns 283 & 288Limitation of 4000 Flight Cycles as recorded in the ALS Supplementincluded in the Maintenance Planning Supplement ref.ASI-MPS-0243-08,dated 30/10/2014.After the embodiment of this change, any subsequent change that affectsthe aircraft pri...	05/11/2014	Active	10051026
10051041	B/E AEROSPACE, Inc. - FSI		FAA STC ST02412SE	777-200	Installation of Interior Reconfiguration for KLM	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.613 Amdt 1CS 25.853(a)(c)(d)(e)(f)(g)(h) Amdt 1CS 25.869(a)(1)(4) Amdt 1CS 25.1353(a)(b)(d) Amdt 1CS 25.1431(a)(c)(d) Amdt 1The requirements for environmental protec...	-Master Drawing List, Flight Structures Document B3FS315-D01, RevisionH, dated October 28, 2014-Supplemental Instructions for Continued Airworthiness, FlightStructures Document B3FS315-D15, Revision A, dated October 3, 2014or later revisions of the above listed documents approved by EASA inaccordanc...	Concurrent installation of the following modification is required withthis STC:-FAA STC ST03178NY, held by Delta Engineering, validated by EASA STC10046995-Boeing Service Bulletin777-25-0622, Revision 01, dated October 24,2014, or later FAA-approved revision.If the holder agrees to permit another p...	04/11/2014	Active	10051041

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051043	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		PA-31T (CHEYENNE/ CHEYENNE II) PA-31T3 PA-31T2 (CHEYENNE IIXL) PA-31T1 (CHEY. I/ CHEYENNE IA) PA-31P (PRESSURIZED NAVAJO) PA-31P-350 (MOJAVE)	Title: Installation of Garmin GSR56New installation of Garmin GSR56 with Comant CI 490-1 Comant Antenna	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23 Amendment 3: 23.301; 23.303; 23.305(a)(b); 23.307;23.365(a)(b)(d); 23.561(a)(b); 23.571(a)(b);23.575; 23.603(a)(b);23.605; 23.607; 23.609; 23.611; 23.613(a); 23.843(...	Flight Manual Supplement, ASR-2013-109-FMS-05-00, Amendment00; dated23/09/2014or later revisions of the above listed documents approved by EASAInstructions for Continued Airworthiness ASR-2013-109-ICA-11-01 (Rev.01) dated 1st June 2017Master Document List ASR-2013-109-MDL-01-01 (Rev.01) dated 1st J...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10051043
10051047	MID-CANADA MOD CENTER		TCCA STC O-LSA07-123/D ISSUE 4	F50EX	Dual Universal UNS-1 F FMS, Honeywell MK V Enhanced EGPWS and Aircell Axxess Satphone Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avionics Design Services Ltd. Master Drawing List MDL07041 Rev. F dated17.10.2014Mid Canada Mod Center Airplane Flight Manual Supplement N° FMS07041-1Rev. B dated 10.10.2014 (DualUNS-1F FMS)Mid Canada Mod Center Airplane Flight Manual Supplement N° FMS07041-2Rev. B dated 10.10.2014 (Honeywell MK-Vo...	MSN 278	04/11/2014	Active	10051047
10051055	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	717-200	TCAS System Upgrade to Change 7.1 on Boeing MD 90-30/B717-200 seriesAircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	H4 Aerospace Document No H4AFMS042 Rev I/R - Airplane Flight ManualSupplement or later revisions of the above listed documents approved byEASA.H4 Aerospace Document No H4A1749 Issue 3 - Modification Summary Sheetand Declaration of Compliance	This modification is limited to the Boeing 717-200 series aircraftdetailed in H4 Aerospace Modification Summary H4A1749Issue 3.Prior to installation of this design change it mustbe determined thatthe interrelationship between this designchange and any otherpreviously installed design change and/a...	05/11/2014	Active	10051055
10051063	SOCIETE AIR FRANCE S.A.			777-300, 777-300ER. 777-200, 777-200LR,	G700 Electronic Flight Bag activation on B777.This modification consists in activating, on Boeing 777 aircraft, anElectronic Flight Bag system based on two 10-inch displays from UTAS:the G700 SmartDisplay Units (SDU). The G700 EFB is activated as"portable" device as per the definition in EASA AMC 20...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Change Approval Sheet (including Master Data List), Air France referenceCAS-B777-14-006 revision 00 or later revisions of the above listeddocuments approved by EASA.	1. Operational limitations: refer to Airplane Flight ManualSupplement,Air France reference AFMS-B777-14-006-001.2. Theapplication of the minor modification, Air France referenceCAS-B777-14-007, named "G700 EFB Provisions", is mandatory prior toembody the present modification on aircraft.Prior to i...	06/11/2014	Active	10051063
10051064	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA Q-LSA10-019/D ISSUE 1	BD-700-1A10	Passenger Cabin Entertainment System Upgrade.EASA validation of Transport Canada's Supplemental Type CertificateQ-LSA10-019/D at issue 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification must be performed in accordance with the following: 1.,,MDL30107002 Master Document List - Passenger Cabin EntertainmentSystem Upgrade, BD-700-1A10, SN 9036, revision N/C, dated 05th March2010, and2.,,TL30107-004, Time Limits and Maintenance Checks - CabinEntertainment System Upgrade, A/...	See those of original TCCA approved STC's Q-LSA10-019-D Issue 1. ThisSTC installation is limited to aircraft serial number 9036.	06/11/2014	Active	10051064

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051065	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA Q-LSA02-067/D ISSUE 3	BD-700-1A10	Iridium Phone System Installation.EASA validation of Transport Canada's Limited Supplemental TypeCertificate Q-LSA02-067/D at issue 3.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The installation must be done in accordance with: 1.,,MDL02166004<(>,<)> Aerocas Master Document List - Iridium PhoneSystem Installation, BD-700-1A10 aircraft, serial number 9036,revisionB, dated 12th July 2004, and2.,,MMMS02166-009, Aerocas Airworthiness Limitations - MandatoryMaintenance Manual S...	See those of MMMS02166-009, Aerocas Airworthiness Limitations -Mandatory Maintenance Manual Supplement, AirCell Iridium AntennaInstallation, Aircraft Serial Number 9036, RevisionNC, dated 07th July2004.This STC installation is limited toaircraft serial number 9036.	06/11/2014	Active	10051065
10051077	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 1		MBB-BK 117 B-2, MBB-BK 117 C-1 MBB-BK 117 A-4, MBB-BK 117 B-1 MBB-BK 117 A-1, MBB-BK 117 A-3	Installation of Flight Data Monitoring and Transmitting System HELICOMV2 ANA or HELICOM V2+ ANARevision 1: STC holder name change from I.S.E.I International Servicesto SAFRAN ELECTRONICS & DEFENSE BUSINESS UNIT - HELICOPTERS DATAMANAGEMENTSOLUTIONS & SERVICES.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Issue 3 Lithium Battery Installation.The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	CERTIFICATION PROGRAM N2-BK117 HV2-ANA, Edition B Rev. 02Installation Manual N7-BK117 HV2-ANA Edition B, Rev. 02Instructions for Continued Airworthiness N8-BK117 HV2-ANA Edition B,Rev. 02	None	27/02/2020	Active	10051077
10051078	VIH AEROSPACE Inc.		TCCA SH09-29	407	Crew Bubble Window InstallationThe bubble window replaces the original right hand crew window as shownin drawing V407-0822B-000 of the VIH Aerospace Master Drawing List,V407-0822-MDL.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement VIH Aerospace No. V407-0822-FMS Rev: 0Instructions for Continued Airworthiness VIH Aerospace No. V407-0822-ICARev:0or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Mast...	None	07/11/2014	Active	10051078
10051081	AVIONITEC AG			R 90-230RG	GNS430W upgrade to WAAS Unit incl. LPVRemoved: - Garmin GNS430 (GPS/COM/NAV)Installed: - Garmin GNS 430W (GPS/COM/NAV)Compliance showing to AMC20-28 that the installed equipment is suitablefor RNAV (GNSS) Approaches down to LPV Minima.Compliance showing to AMC20-27, resp. CRI F-10 (Airworthiness Cr...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Instructions for continued airworthiness: No. 3499-015, dated06.10.2014-Airplane Flight Manual Supplement: No. 3499-011, dated 06.10.2014or later revisions of the above listed documents approved by EASA-Master Document List: No. 3499-017,dated 06.10.2014	The approval holder shall fulfill the obligations of Part 21 §21.A118Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworth...	07/11/2014	Active	10051081
10051096	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		A320-232	Cabin Interior Modification on British Airways A320-232 Aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 13, 25.562 (except (c) (5) & (c)(6)), 25.812(a) & (e),25.812 (a), (b) & (c)The requirements for environmental protection and the associatedcertified noise an...	Northwest Aerospace Technologies, Inc. Master Drawing List,InteriorReconfiguration on British Airways A320-232 Aircraft, N0482-D10, Rev. H.	Aircraft serial numbers MSN 1482, MSN 1509, MSN 1613, MSN 1663, MSN1672, MSN 1771, MSN 1804, MSN 1834, MSN 1892 and MSN1902 only.Airbus Service Bulletin A320-25-1 B42 must be incorporated concurrentlywith this STC.Prior to installation ofthis design change it must be determined thatthe interrelati...	29/02/2016	Active	10051096
10051113	HELIKOPTER AIR TRANSPORT GmbH	REV. 1		EC 135 T3 EC 135 T2+ EC 135 T2 EC 135 T1 EC 135 P2+ EC 135 P2 EC 135 P1	Cabin Interior Combination of Bucher Leichtbau EMS InstallationARA-EC135-AC60 (EASA 10030810)<(>,<)> ARA-EC135-AC61 (EASA10017211) orARA-EC135-AC65 (EASA 10017089) with cabin floor installation of AirAmbulance Technology STC EASA.R.S.00462Rev 3.Note: This revision to EASA STC 10051113 adds Bucher L...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27 Amendment 3: 27.1//27.2/27.21/27.25/27.27/27.29/27.307/27.561/27.562/27.807/27.853/27.1301/27.1529The requirements for environmental protection and the associatedcer...	Flight Manual Supplement 85-009 Revision 1or later revisions of the above listed documents approved by EASA- Engineering Order 85-009, Revision 1, dated 19 January 2015.- Component Maintenance Manual with Illustrated Parts List EO 85-009,Revision 1.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/01/2015	Active	10051113

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051144	DUNCAN AVIATION, INC.		FAA ST01648WI-D	FALCON 2000, FALCON 2000EX	Thrane & Thrane Satellite Communication System and WirelessLocal AreaNetwork Activation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List ref. 110601003 revision D, dated 12 February 2013 ;AFM Supplement ref. 110601008 revision A, dated21 October 2011 ;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or t...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/11/2014	Active	10051144
10051148	APTOZ EHF.	REV. 2		767-300 757-200/-300 767-300 757-200/-300	Data Transmission & Automatic Calling - Satcom Iridium InstallationRev. 1: 767-300 added to the applicability listRev. 2: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:- Type Certification Basis for parts not changed or not affected by thischange- For parts changed of affectedf...	(1),,For Boeing 757 series: Icelandair Master Drawing ListDWG-757-2320-60 Revision F.(2),,For Boeing 767 series: Icelandair Master Drawing ListDWG-767-2320-19 initial release- Icelandair AFM supplements ref. AFM-767-2320-19 Initial ReleaseandAFM-757-2320-60 Revision A.- Icelandair Instructions forC...	Aeroplanes modified with STC must be- Operated in accordance with Icelandair AFM supplements ref.AFM-767-2320-19 Initial Release or AFM-757-2320-60 Revision Arespectively.- Maintained in accordance with Icelandair Instructions for ContinuingAirworthiness ref. CAI-767-2320-19 I.R. or CAI-757-2320-60r...	27/05/2025	Active	10051148
10051152	KLM ENGINEERING & MAINTENANCE			BOEING 777-200	Cabin reconfiguration of KLM 777-206 aircraft[Replacement of World Business Class seats and Economy Class seats,removalandinstallation of monuments, replacement of In-Flight Entertainment System<(>,<) >replacement of décor laminates, curtains and carpet and related changestoaccommodate the new cabin...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-254 (Post TC special condition - aOverhead Crew Rest Compartments) closed on 16 April 2004, which hasadopted special condition FAA 25-230-SC.Th...	Master Data List, KLM document No. MDL-012935, Revision 8, dated 12November2014Applicable revisions for EASA or later revisions of the above listeddocuments approved by EASA	Other:On 777-200 MSN 33712 with seat P/N 3710A470-40-031, S/N 601598 and seatP/N 3710A470-40-051, S/N 601600, the use of the Overhead FlightAttendant Rest (OFAR) is prohibited unless Recaro Service Bulletin3710-25-002 has been accomplishedor armrest P/N 470-00-301-01, P/ N470-00-301-02, P/N 470-00-3...	12/11/2014	Active	10051152
10051163	AVIATION PARTNERS, INC.		FAA STC ST02241SE	MF50	Validation of FAA STC ST02241SE.Installation of Aviation Partners Inc. Blended Winglets in the DassaultAviation MystereFalcon 50.	See AppendixThis certificate/ approval involves a change tothe requirements forenvironmental protection or a change tothe certified noise or emissionslevels.	Aviation Partners, Inc. (API) Master Drawing List ref. APF5-0620, rev.A.5, dated 02 June 2014.Aviation Partners, Inc. (API) AFM Supplement ref. APF5-0601 Code 001,rev. 1, dated 14March 2013.Aviation Partners, Inc. (API) Airworthiness Limitations as recorded indocument ref. APF5-0608, rev. B, datedo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/11/2014	Active	10051163
10051167	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			AS355 E, F, F1, F2, N	Installation of ELT KANNAD 406 AF-Compact.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement H-13-01-KANNAD_ELTAS355 Ed. 1 Nov.2014or later revisions of the above listed documents approved by EASA-Dossier descriptif et justificatif H-13-01-KANNAD_ELTAS355 Ed. 1 Sep.2014-Master Drawing List H-13-01-KANNAD_ELTAS355-MDrL, Ed. 1 Sep. 2014-Document d'Application H-13-01...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/11/2014	Active	10051167

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051169	NSE	REV. 1		EC135 T1, EC135 T2, EC135 T2+ EC135 P1, EC135 P2, EC135 P2+	Data Transmission System DTS KIT EC135The DTS KIT describedin document DD-KIT-DTS-EC135 is a GeolocalizationSystem to transmits aircraft's position, speed, altitude, and bearing.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Rotorcraft Flight Manual Supplement RFMS-DTSV2-EC135, Rev. 00or later revisions of the above listed documents approved by EASA.Documentation Data List SDL-DTSV2-EC135, Rev. 01Installation Instruction IM-DTSV2-EC135, Rev. 00Operating ManualMUL-DTSV2, Rev. 02KIT Definition File DD-KIT-DTS-EC135-EN, R...	The approval holder shall fulfill the obligations of Part 21, Point21.A.109 or 21.A.451(b) (as applicable).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introd...	20/02/2015	Active	10051169
10051171	LUFTHANSA TECHNIK AG			A340-600	New Premium Economy Class for A340-600In the main cabin of the main floor on the aircraft, the change consistof the removal of 10 per cent of the Economy Class Seats between door 2and door 3 and the installation of new developed Premium Economy Seatsinstead. The new seating will have a greater pitch...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/ approval.	- Supplemental Type Definition Document STDD25-13/42M issue1 rev 1- ICA, ref A-00-14/51-ICA, Issue 1 rev 0- ComplianceRecord List CRL25-13/42M issue 1 rev 0or later revisions ofthe above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with :a) SB AIM A340--25—107 Introduction of a three part class dividerinstallation (Minor Change ref MM 636-14),b) STC 10013964, Non Electric Floor Path Marking System for A340-600,together with associate...	13/11/2014	Active	10051171
10051172	LEAT S.p.A.			F27 MARK 500	HF COM system installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/ approval	Master Data List 23-10-0513 REV 00 dated 30 October 2014Compliance Checklist 23-10-0513-1100 REV 00 dated 30 October 2014Design Office Substantiation 23-10-0513-1400 REV 00 dated 30 October2014Aircraft Flight Manual Supplement 23-10-0513-0800 REV 00 dated 30October 2014Instructions for Continued Air...	None	14/11/2014	Active	10051172
10051176	ALTRAN LABt/a AIRCAD			A320-232	Dragonair Cabin Reconfiguration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List MDL-13021 Rev.3, dated 12/11/2014Compliance Check List CCL-13021 Rev.3, dated 29/10/2014Instructions for Continued Airworthiness ICA-13021 Rev.0, dated06/11/2014or later revisions of the above listed documents approved by EASA	This STC does not constitute an approval for the installation of thePanasonic eXW IFE system, related wirings and its activation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/...	14/11/2014	Active	10051176
10051177	MARSHALL AVIATION SERVICES LIMITED		CAA UK RESPONSIBILITY	B200	Installation of Transponder Enhanced Surveilance.Installation of Transponder Enhanced Surveillance for Rockwell CollinsTDR-94D equipped King Air B200 Proline II accordance with MarshallAviation Services Ltd document SC0473B.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of Transponder Enhanced Surveillance accordance withMarshall Aviation Services Ltd document SC0473B<(>,<) >Aircraft Flight Manual Supplement, Marshall Aviation Services Ltddocument AFM 101-590010-307C Supplement 1 at Issue 1< (>,<)>or later revisions of the above listed documents approved...	None	14/11/2014	Active	10051177

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051180	ALITALIA SOCIETA AEREA ITALIANA S.p	REV. 1		A320-214, A320-216 A319-111, A319-112	Installation of AMSAFE passenger seat cargo container (P/NAC80-02207-B1) Rev. 1: Transfer of Certificate	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-0334-001 "Installationof cargo seat bags"The following paragraph(s) at a later amendment: CS-25 Amdt. 4 for theparagraphs affected by the chan...	Master Data List MM_MDL14F25S-0001 R02, dated 24/10/2014Compliance Check List MM_CCL14F25S-0029 R01, dated 18/09/2014Instructions for Continued Airworthiness MM_ICA14F25S-0026 R01, dated16/10/2014Aircraft Flight Manual Supplement MM_FMS14F25S-0004 R01, dated22/09/2014or later revisions of the above...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/02/2021	Active	10051180
10051181	PFW ENGINEERING GmbH			A380-841, A380-842, A380-861	PFW - Structural Provisions of Patient Transport Compartment (PTC) onAirbus A380	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Instructions for Continued Airworthiness, PFW reference A388A-ICA-Aissue Sep 15/2014- Master Drawing List, PFW reference A388A-MDR-530100 Issue C- Master Certification DocumentsList, PFW reference CCN-A388A-MCDLissue 1- Operators Manual, PFW reference A388A-COM-A issue Sep 15/2014or later revis...	Airworthiness limitations: Refer to section 05-10-00 of PFWdocumentA388A-ICA-A issue Jul 15/2014 or later revisions ofabove documentapproved by EASA.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously insta...	14/11/2014	Active	10051181
10051182	AIRBUS HELICOPTERS CANADA LIMITED	REV. 3	TCCA SH14-10 ISSUE 4	AS 350 B3, AS 350 B2 AS 350 B2, AS 350 B3	Installation of long line provisions to provide electrical power supplyfor optional equipment.10051182 Revision 1: validation of TCCA STC SH14-10 at issue 2.10051182 Revision 2: validation of TCCA STC SH14-10 at issue 4. Thisrevision incorporates new configuration to address changes required forcomp...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation and configuration must be performed in accordance withAirbus Helicopters Canada Limited Master Drawing List MDL-12-008, IssueF, approved on February 21, 2025.Maintenance must be performed in accordance with Airbus HelicoptersCanada Limited Instructions for Continued Airworthiness ICA-AH...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Required Equipment:As a pre-requisite, the rotorcraft m...	24/06/2025	Active	10051182
10051201	SABENA TECHNICS BGC			737-600/-700/-800/-900/-900ER	Retrofit Installation of FDAU SAGEM ED49 on B737 NG	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amdt. 4:25.29 <(>,<)> 25.581 , 25.601, 25.603, 25.607, 25.611, 25.869(a) , 25.899, 25.1301, 25.1309, 25.1351, 25.1353, 25.1357, 25.1360, 25.1431,25.1459, 25.1529, 25.1...	Master Data List 0691-01-A-2103-R00 dated 29th October, 2014Instruction for Continued Airworthiness 0691-01-A-2211-R00 dated October07th, 2014Weight and Balance Analysis 0691-01-A-3401-R00 dated July 02nd, 2014or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/11/2014	Active	10051201
10051207	AERO-DIENST GMBH & CO. KG	REV. 1		35A, 36, 36A, 35	TCAS TPU67A to B Upgrade to Version 7.1 (Honeywell)Revision1, replaces initial issue of this approval.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement, AG987-071, rev IRInstructions for Continued Airworthiness, AG987-085, IR, dated 22 Sept2014.or later revisions of the above listed documents approved by EASA.	None.	18/11/2014	Active	10051207

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051211	SOGECLAIR AEROSPACE LIMITED		CAA UK RESPONSIBILITY	F 406	Installation of Alternative Wheels and Brakes	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Documents referenced on Sogeclair Aerospace Master DocumentListBRN140192-MDL dated 14/11/2014.	Aircraft serial numbers 0036, 0080, 0094 and 0095 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the p...	17/11/2014	Active	10051211
10051266	DELTA ENGINEERING CORPORATION		FAA STC ST03188NY	737-800 737-700 737-600	Astro-Med ToughWriter 5 Printer installation.This modification consists in installing Astro-Med ToughWriter 5 printerinthe central pedestal, to get some printing capabilities from severalaircraft systems (ACARS, FMS / FMC, EFB for instance) depending on theconfiguration installed.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 change 4: 25.869; .1309; .1353; .1431CS 25 Change 13: 25.831; .853; .981; .1583; .1585The requirements for environmental protection and the associatedcertified noiseu...	Delta Engineering Master Data List, ref: 0106-08832-2365 Revision C,dated 01 July 2014Aircraft Flight Manual Supplement, ref: 0606-08894-2365, dated 09 May2014Instructions for Continued Airworthiness, ref: 0706-08896-2395 RevisionB, dated 01 July 2014or later revisions of the above listed documentsa...	None	19/11/2014	Active	10051266
10051267	DELTA ENGINEERING CORPORATION			A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-243/-243F A330-201/-202/-203/-223/-223F	Cockpit Certificate Box installation.This modification installs a box on the aft wall of the cockpit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List, ref: 0154-08916-2374, dated 12August 2014Instruction for Continued Airworthiness, ref: 0754-08917-2374 RevisionA, dated 12 June 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revis...	None	19/11/2014	Active	10051267
10051268	ROEDER PRAEZISION GMBH	REV. 1		A320-214	Installation and activation of an In-Seat Power System on existingbusiness class seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List A320-MDL25-15-2014 Rev. 01, dated 18/11/2014;Certification Report A320-CR25-15-2014 Rev. 04, dated18/11/2014;Instructions for Continued Airworthiness A320-ICA25-15-2014 Rev.Initial, dated 11/11/2014;Aircraft Flight Manual Supplement A320-AFS25-15-2014 Rev. 01, dated29/09/2014;o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/06/2018	Active	10051268
10051283	JET AVIATION AG	REV. 4		737-700 IGW	WIP Cabin Completion as defined in the:- Certification Plan, Doc. No. JBSL-M-00002CER-01, Issue 6, dated28.10.2014.- Master Document List, Doc. No. JBSL-M-00002MDL-01, Issue 1, dated17.11.2014.Rev. 4: Transfer STC 10051283 Rev. 3.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):- CRI D-02, Isolated Compartments.- CRI D-10, Glass Screens of Displays/Monitors.- CRI D-14, Shower Installation.Deviation(s):- CRI D-01, Installation...	- AFMS, Doc. No. JBSL-M-00002AFM-01, Issue 3< (>,<)>or laterrevisions of the above listed documents approved by EASA.- Master Data List, Doc. No. JBSL-M-00002MDL-01, Issue 1, dated17.11.2014.- ICA related to Ground Fault Circuit Interrupter, Doc. No. JBSL-M-00002ICA-01, dated 17.11.2014.- ICA relate...	STC valid for MSN 38408.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/10/2017	Active	10051283

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051287	STIRLING DYNAMICS GMBH	REV. 4		737-800	Installation of SatCom Blue Sky Network D1000(A) Iridium Satcom SystemRev. 4: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS-25/14 for:25.1, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341, 25.561,25.571, 25.581,25.613, 25.625, 28.899, 25.1301, 25.1309, 25.1351,25.1431, 2...	- ICA, Doc. No. 214094-C-CA-2310-001-03, Issue 3, dated 14.11.2014or later revisions of the above listed documents approved by EASA.- Engineering Order, Doc. No. 214094-C-EO-2310-001-02, Issue 2, dated07.10.2014- AFMS, Doc. No. 214094-C-AM-2310-01-01, Issue 1- Certification Documents List, Doc. No....	Change applicable for MSN 41318Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	15/06/2022	Active	10051287
10051291	ALAMO ENGINEERING GmbH	REV. 5		A320-251N A318-111, A318-112	Cobham SBB Satcom System (1-4 Channel)Rev. 3: Update of theICA and AMM-Supplement to incorporate anadditional MPD-S Task applicable to weight variant 05 with Airbus post TC modification 39195 (Elitevariant).Rev. 4: Transfer ofthe STC from "Deutsche Aircraft GmbH" to "AlamoEngineering G...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:. For A318-111/-112: CS 25 Amdt. 15 for paragraphs: §25.23, §25.301,§25.305, §25.365, §25.571, §25.901, §25.1419, §25.152...	- Master Document List: ,,,,,,MDL23A33AE-01, Rev. A- Instructions for Continued Airworthiness:,,ICA23A33AE-01, Rev. AFor A318-111/-112 only: Flight Manual Supplement FMS23A33AE-01, Issue A (Superseding previously approved AFM018H231Z0001 with no change otherthan format.)or later revisions of the abov...	For A318-111/-112: None.For 320-251N:Installation of Jet Aviation AG Completion Package, consisting of thetwo below STCs, is a prerequisite for this modification. That alsoincludes airplane flight manual supplements approved together with theseSTCs:VVIP Cabin Interior Completion – EASA STC No. 10075...	17/04/2024	Active	10051291
10051293	S-TEC CORPORATION	REV. 1	FAA STC SA09636AC-D	425	Installation of S-TEC 01304 Digital Flight Control System (DFCS), ThreeAxis Automatic Flight Guidance System Part No. 01304-04-01-007 inaccordance with FAA STC SA09636AC-D	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 23, Amdt. 0: 23.307(a)(b), 23.601, 23.609(a)(b), 23.627, 23.693<(>,<)>23.1367(a)-(d), 23.1381(a)-(c)FAR 23, Amdt. 7: 23.395(a)(1), 23.619, 23.623(b), 23.625(b),23.689...	Master Data List 921231, Rev. 11, dated September 10, 2014Installation Instructions ST-914-1, Rev. 7, dated July 25, 2014Airplane Flight Manual Supplement 892135, Rev. C, dated August 4, 2014or later revisions of the above listed documentsapproved by EASA inaccordance with EASA ED Decision 2004/04/...	a) Autopilot operation is prohibited in icing conditions.b) If the holder agrees to permit another person to use this certificateto alter the product, the holder must give the person written evidenceof that permission.Prior to installationof this design change it must be determined thatthe interrel...	26/11/2014	Active	10051293
10051300	FOKKER SERVICES B.V.	REV. 2		737-900, 737-900ER 737-600, 737-700, 737-800 737-300, 737-400, 737-500 737-100, 737-200, 737-200C	Original STC: Upgrade of TCAS to V7.1 on Boeing 737Revision1: Addition of introduction of TCAS V7.1 upgrade on T2CASequipmentRevision 2: Addition of introduction of TCAS V7.1 upgrade on ACSSTCAS2000 system for 737NG	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval .	Original STC:Certification Plan CP-0237 Issue 1Compliance Record Report CRR-0237 Issue 1Certification Plan CP-0238 Issue 2Compliance Record Report CRR-0238 Issue 1Revision 1: In addition to the above documents:Certification Plan CP-0260 Issue 2Compliance Record Report CRR-0260 Issue 2Revision 2: InC...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/08/2015	Active	10051300
10051323	DASSAULT FALCON JET CORPORATION		FAA STC ST03253CH	FALCON 2000, FALCON 2000EX	Validation of FAA STCInstallation of LED Landing Lights	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. 1024645 rev. C, dated 13 February 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this change and anyother previouslyinstalled design change will introduce no adverse effect upon theairworthiness of the product.	24/11/2014	Active	10051323

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051325	DASSAULT FALCON JET CORPORATION	REV. 1	FAA STC ST03252CH	MYSTÈRE-FALCON 900 MYSTÈRE-FALCON 50 FALCON 900EX	Validation of FAA STCInstallation of LED Landing Lights	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. 1024638 rev. B, dated 18 February 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this change and anyother previouslyinstalled design change will introduce no adverse effect upon theairworthiness of the product.	11/12/2014	Active	10051325
10051330	PMV ENGINEERING			737-700	eConnect IFE installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:D-118 Glass monitors issue 1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged a...	Master Data List SCA-00340-MDL Rev 00AFMS SCA-00340-AFMS Rev 02AMMS SCA-00340-AMMS Rev 00or later revisions of the above listed documents approved by EASA.	The use of transmitting portable electronic devices (T-PEDs):- Is allowed during non critical flight phase in the cabinbut limitedto WIFI devices.- Is NOT allowed during criticalflight phase in the cabin.- Is NOT allowed during any flight phase in the cockpit.Prior to installation of this design c...	24/11/2014	Active	10051330
10051343	AIRCRAFT STRUCTURES INTERNATIONAL CORP.		FAA STC SA01747WI	208B 208	Installation of Pilot and Co-Pilot Lower Door Panels	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASIC Installation Data List 09251000-002, Rev. 1, dated 6 January 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreemen...	If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpre...	24/11/2014	Active	10051343
10051358	SOCIETE AIR FRANCE S.A.			A330-200 (A330-243)	Thomas Cook - Cabin rearrangement / IFE installationCabin seating rearrangement ("Acro Y/C and "ZIM" Y/C Premium new seats)Zodiac "ims RAVE" and new IFE system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Change Approval Sheet CAS-A330-14-002 rev 0, dated 24 November 2014.- Instruction for Continued Airworthiness, ref : ICA-A330-14-002 rev 0,dated 21 July 2014or later revisions of the above listed documents approved by EASA.	- This STC is applicable to MSN 254; 266; 301 & 309 only.- Refer to the section "B-Concurrent Requirements" of the AIR FRANCESERVICE BULLETIN reference AFSB-A330-14-002-25-001.- Prior to installation of this design change it must be determined thatthe interrelationship between this design change an...	25/11/2014	Active	10051358
10051368	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04296AT-D	GV	Installation of Moxa AWK-6232 Series dual radio wireless access point.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Index List CE51 4288008 rev -Weight and Balance statement CE51 428W005 rev AInstructions for Continued Airworthiness CE51 428A011 rev -AFM Supplement CE51 428M011 rev -or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/11/2014	Active	10051368

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051369	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04295AT-D	G-IV	Installation of Moxa AWK-6232 series dual radio wireless access point.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Index List CE41 4288001 rev AWeight and Balance statement CE41 428W001 rev -Instructions for Continued Airworthiness CE41 428A007 rev -AFM Supplement CE41 428M004 rev Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/11/2014	Active	10051369
10051373	TENENCIA Ltd.	REV. 2	CAA UK RESPONSIBILITY	A321-272N, A321-272NX A321-271N, A321-271NX A321-253N, A321-253NX A321-252N, A321-252NX A321-251N, A321-251NX A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-251N/-252N/-271N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Wireless IFE System InstallationRevision 2: Addition of newmodels	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): Special Condition H-01: Enhanced Airworthinessprogramme for Aeroplane Systems – ICA on EWISThe requirements for environmental protection and the asso...	-Report TEN 751-47 Airplane Flight Manual Supplement, Airbus A320 SeriesWireless IFE System, Issue 09 Jan 2016-TenenciaLtd report Modification TEN 751, Airbus A320 Series WirelessIFE System Installation, Issue 1 dated 21 Nov 2014 and all referenceddocuementsor later revisions of the above listed do...	Operational approval for the use of transmitting PEDs on board theaircraft must be obtained from the responsible division of theoperational authority of the aircraft's country of registration prior toconducting this kind of operation.Priorto installation of this change/repair it must be determinedt...	13/08/2018	Active	10051373
10051391	BOGGI AERONAUTICS S.R.L.	REV. 1		AB206 B, 206B AB206 B 206B	Fatigue Testing for AW limit extensionRev. 1 extends lifetime of the kit Heliservicio SRLAT 01 P/N HWS-AP.002	FAR 27 amendment 1 to 35 for the areas affected by the change and JAR27.865 change 2.The requirements for environmentalprotection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicableto this certificate/ approval without any impact onthe noise...	The following documents supersede the associated Technical Documentationlisted in the STC 10051391dated 3 December 2014.• Airworthiness Limitations Section: 206P00210-ICA-00 - Chapter 04 -Issue 0 dated 7 May 2024.• Master Document List: 206P002-Mdl-02 issue 2 dated 3 June 2024.• Instruction for Cont...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/06/2024	Active	10051391
10051393	CESSNA ZURICH CITATION SERVICE CENTGMBH	REV. 1		CESSNA 525, 525A, 525B	Compliance to ADS-B Out was shown against EASA CS.ACNS.ADSBand FAAAC20-165A as per RTCA/ DO260BImplementation of ADS-B out capability into Rockwell Collins Pro Line 21equipped aircraft with:- single or dual Rockwell Collins GPS4000s- dual Rockwell Collins TDR94D Transponder- single or dual FMS-3000R...	The Certification Basis (CB) for the original product remains applicableto this certificate// approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/ approval	- Instructions for continued airworthiness: - ICA-111, Rev.C- Airplane Flight Manual Supplement: - FMS-111, Rev. Cor later revisions of the above listed documents approved by EASA.- Master Document List: - MDL-111, Rev. B	Applicable Serial Numbers:C525 CJ 1+ ,,: SN 0600 and onC525A CJ2+ ,,: SN 0300 and onC525B CJ3 ,,: SN 0001 thru SN0450Pro Line 21 Avionics Suite must be factory installed orretrofitted,including FMS-3000 (single or dual) and single or dual GPS4000s (EGNOS/WAAS *SBAS* capable), dual Diversity T...	11/12/2014	Active	10051393
10051425	ROEDER PRAEZISION GMBH	REV. 1		P.68 "VICTOR" P.68R "VICTOR" P.68C-TC P.68C P.68B "VICTOR" AP68TP-600 "VIATOR" AP68TP-300 "SPARTACUS"	Installation of PFD Aspen EFD1000 PRO and MFD Avidyne EX600with SatcomTransceiver MLX770 and TAS605	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-23,Amendment 3 (not required by 21A.101) 21,29,303,305,307,561,603,609,611,613,625,771,773,867,1301,1303,1309<(>,<)>1311,1321,1322,1327,1331,1351<(>,<)>1353,1357,1359,1...	Supplement to AFM: P68-NY-04249-08 Rev. 00 ,,,,or later EASA approved revisionsCompliance Program: P68-NY-04249-01 Rev.00 or later approved revisions,,Compliance Checklist: P68-NY-04249-01a Rev. 00 or later approvedrevisions,,Groundtest Requirements: P68-NY-04249-04a Rev. 00 or later approvedrevisi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/11/2017	Active	10051425

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051428	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 2		EC 155 B, EC 155 B1	Flight Data Monitoring and Transmitting System HELICOM V2 NUM / V2+ NUMInstallation.Revision 1: Introduction of the HELICOM V2+ NUM version.Revision 2: STC holder name change fromI.S.E.I International Servicesto SAFRAN ELECTRONICS & DEFENSE BUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SER...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 (Lithium Battery) Issue 5 dated14/01/2016.The requirements for environmental protection and the associatedcertified noise and/ or emission...	- Rotorcraft Flight Manual Supplement N11-EC155-HV2 HV2+ NUME-B-03-Rev.04, dated 14/01/2016< (>,<)>or later revisions ofthe above listed documents approved by EASA.- List of Documents - N10- EC155-HV2 HV2+ NUM E-C-02, dated 14/01/2016- Compliance Declaration - N9-EC155-HV2 HV2+ NUM E-C-01, dated14/0...	The approval holder shall fulfill the obligations of Part 21, Paragraph21A.109.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	27/02/2020	Active	10051428
10051429	S-TEC CORPORATION		FAA SA09536AC-D	PA-31T	Installation of S-TEC 01304 Digital Flight Control System Part N.01304-07-01-006	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- To be installed according to S-TEC Master Drawing List N.ST-917-L-0001 rev.H dated 02-Sep-2014;- To be operated in accordance with S-TEC AFM-S P/N ST-917-M-0001 rev.Cdated 04-Aug-2014;- To be maintained i.a.w. Instruction for continued AirworthinessST-917-C-0001 rev.B dated 02-Aug-2005;or later re...	- Limitations as per in original FAA STC SA09536AC-D dated 03-Sep-2014;- Installer must check availability of EASA-approval for any referencedSTC when airplane is (or needs to be)modified per that STC.Prior to installation of this design change it must be determined thatthe interrelationship betwee...	02/12/2014	Active	10051429
10051435	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	DORNIER 228-202	ACAS II Software Version 7.1 upgrade.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Installation in accordance with Cobham Modification DC-0252.Operation in accordance with Cobham Flight Manual Supplement refFRAH/FM/0125 Rev 0 dated November 2014.Maintain in accordance with Cobham ICA ref ICA-0252 Issue A dated 17November2014.or later revisions of the above listed documents approv...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and//or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/12/2014	Active	10051435
10051448	FOKKER SERVICES B.V.	REV. 1		DHC-8-401/DHC-8-402 DHC-8-315 DHC-8-301/DHC-8-311/ DHC-8-314 DHC-8-201/DHC-8-202 DHC-8-102/DHC-8-103/ DHC-8-106	Upgrade of TCAS 7.0 to 7.1 on DHC-8 100/200/300/400 Series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.1301(a)(b)(c)(d), CS 25.1309(a)(b)(c) (d),(g), CS 25.1581(a) - allat Amdt. 14The requirements for environmental protection and the associatedcertified noise and/ oru...	Installation must be in accordance with Fokker Engineering BulletinEBDHC-8-0013.Operation must be in accordance with AFM SupplementDHC-8-BTI-AFMS-S-001, Revision 2.Continued Airworthiness unchanged in accordance with OEM ICAor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/02/2015	Active	10051448
10051464	CESSNA ZURICH CITATION SERVICE CENTGMBH			560 (VARIANT ENCORE +)	Compliance to ADS-B Out was shown against EASA CS.ACNS.ADSBand FAAAC20-165A as per RTCA/ DO260BImplementation of ADS-B out capability into Rockwell Collins Pro Line 21equipped aircraft with:- single or dual Rockwell Collins GPS4000S- dual Rockwell Collins TDR94D Transponders-single or dual FMS-3000...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Instructions for continued airworthiness: - ICA-113, Rev.A- Airplane Flight Manual Supplement: - FMS-113, Rev. Aor later revisions of the above listed documents approved by EASA.- Master Document List: - MDL-113, Rev. B	Applicable Serial Numbers:C560 Encore+ ,,: SN 560-0751 and onC560 Encore+ Pro Line 21 Avionics Suite must be factory installed orretrofitted, including FMS-3000 (single or dual)and single or dualGPS4000s (EGNOS/WAAS *SBAS* capable), dual Diversity TransponderTDR-94D, and on which the additional d...	03/12/2014	Active	10051464

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051474	CESSNA ZURICH CITATION SERVICE CENTGMBH			B200CGT, B300, B300C B200 , B200C, B200GT,	Compliance to ADS-B Out was shown against EASA CS.ACNS.ADSBand FAAAC20-165A as per RTCA/ DO260BImplementation of ADS-B out capability into Rockwell Collins Pro Line 21equipped aircraft with:- single or dual Rockwell Collins GPS4000S- dual Rockwell Collins TDR94D Transponders- single or dual FMS-3000...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Instructions for continued airworthiness: - ICA-109, Rev.IR- Airplane Flight Manual Supplement: - FMS-109, Rev. Aor later revisions of the above listed documents approved by EASA.- Master Document List: - MDL-109, Rev. B	Applicable Serial Numbers:All except B200 serials BB-1385, BB-1386, BB-1387, BB-1388 and (B200C)BV-11 and BV-12 (UC-12Mwith military designation RC-12M), BU-11 andBU-12 (UF-12F with military designation RC-12F) as per TCDS IM.A.277B200(x)/B300 (X): Pro Line 21 Avionics Suite must be factory installe...	04/12/2014	Active	10051474
10051480	B/E AEROSPACE, Inc. - FSI	REV. 1	FAA STC ST02413SE	747-400	Deutsche Lufthansa 747-400 Airworthiness Limitations Inspections(ALI) (s) Update – This major change updates the ALI(s) listed in thefatigue and damage tolerance analysis and instructions for continuedairworthiness. There is no design change.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): JAR 25.365(e)(2) - Rapid Decompression asspecified in the EASA TCDS.CRI D-109 - Installation of Crew Rest Compartment. ,,CS 25.571(a)(b) – CS25 AmdtC...	-TP12-218AFM – Airplane Flight Manual for Lufthansa Airlines (2014 SEPT24)- B2FS218-D15 Chapter 10 – Airworthiness Limitations (Rev B, 2014 NOV 11)- B2FS218-D15_D - Supplement To Instructions For Continued AirworthinessFor DLH-B747-400 UpperDeck Interior Reconfiguration and Door 5 Crew Rest (revD, 29...	- As stated on FAA STC ST02413SE- As stated in section 1 ofTP12-218AFM- This STC is a pre-requisite for Lufthansa Technik STC Project Number0010022782- Please refer to the Limitations section in document B2FS218-D15_D - Supplement To Instructions For Continued Airworthiness For DLH B747-400Upper Dec...	05/11/2015	Active	10051480
10051482	SKYTRAC SYSTEMS LTD.		TCCA STC SH12-48	B0105LS A-3	Validation of TCCA STC SH12-48, Issue 2-SkyTrac ISAT Airborne Position/Data Communicator Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS11112-1, Rev. Aor later revisions of the above listed documents approved by EASA.Master Drawing List: MDL 11112 Rev. A, Issue 1Maintenance Manual Supplement: MMS11112-1, Rev. A	None.	04/12/2014	Active	10051482
10051487	DASSAULT AVIATION FALCON JET CORPORATION		FAA STC ST09302SC-D	FALCON 2000	Validation of FAA STC ST09302SC-D.Installation of Speed Indexer System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List ref. F2M010-30 rev. D, dated 27 July 2000.Airplane Flight Manual Supplement ref. 36528-1 rev. A, dated 14 June2000.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the...	The change is not authorized on aircraft equipped with head-up display(HUD) system.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upo...	05/12/2014	Active	10051487
10051492	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST02967NY	MYSTÈRE-FALCON 900 FALCON 900EX	Validation of FAA STC.Installation of Honeywell GPS/WAAS System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Master Data List F9XW-D0012-005 rev. D, dated 03 September 2013.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF(or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement....	For MF900 model, applicability limited to F900C version.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the...	05/12/2014	Active	10051492
10051493	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST02970NY	MYSTÈRE-FALCON 900	Validation of FAA STC.Installation of Honeywell GPS/WAAS System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Master Data List F9BW-D0024-005 rev. A, dated 10 December 2013.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement....	Applicable to MF900 model, except F900C versionPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	05/12/2014	Active	10051493

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051500	AMES - AEROSPACE AND MECHANICALEN GINEERING SERVICES ING. WALTERSTARZA CHER GesmbH			A319 / A320 / A321	Expliseat "Titanium" Seats Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Requirements from COL_M23500101_JTU_10042014 ,,Requirements ,,,,Level,,,,,TitleC S 25.301,,,,,,Amdt 8,,,,LoadsCS 25.303,,,,,,Amdt 8,,,,Factor of safetyCS 25.305,,,,,,Amdt 8...	-Engineering Order EO_M23500101_JTU_100 42014_Revision 0- Instructions for Continued Airworthiness ICA_JTU_10042014_Revisi on 1-Expliseat Technical Note - Composite TN-PA (10) dated 4.7.2014or later revisions of the above listed documents approved by EASA.	None	05/12/2014	Active	10051500
10051504	AERODISA S.L.			EMB-120, EMB-120ER, EMB-120RT	TCAS-II Upgrade to 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ref. AED2014-27M_MDL rev. A0 dated 05 December 2014.AFM Supplement ref. AED2014-27M_AFMS rev. A0 dated04 December 2014.or later revisions of the above listed documents approved by EASA.	The installation of EASA ref. EASA.A.S.01043 is a pre requisite for thechange approved by this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noad...	08/12/2014	Active	10051504
10051519	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		A321-271N/-272N A321-251N/-253N A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-251N/-271N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Major Change to STC for TCAS 7.1 upgradeRevision 1 - Honeywell TCAS computer changed part number from940-0351-001 to 940-0351-005 to correct False RA issue	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 4 for the requirements affected bythis changeThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	Engineering Order & Certification Program for TCAS 7.1 (ACAS II) Upgradeof Prior Existing TCAS 7.0 in Airbus A318, A319, A320, A321: Document2085803-EO Issue 6or later revisions of the above listed documents approved by EASA.Service Bulletin 2107915-SB Issue 1 - UPGRADE OF TCAS 7.1 PROCESSORTPA-100B...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/10/2017	Active	10051519
10051534	SABENA TECHNICS BGC			A330-200 (A330-243)	Y/C Cabin Modification with Zodiac Inflight Innovations (ZII) Rave IFERave installation / upgrade on A330-200This STC installs the Rave IFE system, which mainly consists in theintegration through the current cabin arrangement of System ControlUnit, Seat power Unit, Seat Display Unit, Crew Panel and...	CS 25 Amendment 4, except for 25.562 and 25.785 for which thecertification basis specified in EASA TCDS A.004 issue 36 applies.For detailed applicable requirements refer to the Certification Plan ref: 4633-01-A-2101-R01 section 3.The requirements for environmental protection and the associatedcertif...	Master Data List, ref : 4633-01-A-2103-R00Instruction for Continued Airworthiness, ref : 4633-01-A-2211-R01Aircraft Flight Manual Supplement, ref : 4633-01-A-2301-R00or later revisions of the above listed documents approved by EASA.	1) This STC is applicable only to MSN 303, MSN 306, MSN 311.2) EASA STC ref 10037643 (Initial issue, or later approved revision),Installation of new Business Class Avio EBIZ Seatsand IMS Rave IFESystem : must be concurrently embodied.3) STC 10014507 rev 2 (or later approved revision) - Installation...	09/12/2014	Active	10051534
10051568	SABENA TECHNICS BOD			A330-200 (A330-223)	AIR CARAIBES - B/C EVOLYS SEATS INSTALLALLATION.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/approval	ICA, ref : ICA-F3041-25-004, issue AModification approval sheet, ref : MAS-S-25-2367, issue 3 (Includingassociated references)Certification Plan ref CP-F3041-25-001 issue C (Including Master DataList in Section 4.5.3)or later revisions of the above listed documents approved by EASA	- Concurrent installation of Minor Change number S-25-2353,Businessclass modification (Sabena), and EASA STC 10014507 rev 2 "Installationof non-electrical Floor Path Marking System"(LHT).- This STC is applicable for MSN 0253 only.- Prior to installation of this design change it must be determined t...	10/12/2014	Active	10051568

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051584	AIRBUS HELICOPTERS ITALIA S.R.L.	REV. 1		AS 350 B3	Initial revision:Iridium Tracking System Installation with Voice and Short MessageService CapabilityThe system includesthe installation of a Garmin GSR 56H Satellite Radiounder the cabin floor on the co-pilot side, a Cobham CI 420-490 IridiumAntenna on the top of the vertical fin and a Cobham CI 25...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS27 Amdt. 3paragraphs: 27.25, 27.27, 27.29, 27.251, 27.301, 27.303, 27.305, 27.307,27.309,27.561, 27.603, 27.605, 27.60...	Flight Manual Supplement, doc. ref. HI-350-23-01/ FMS, Ed. 1, Rev. 2,dated 1st December 2014Certification Programme, doc. ref. HI-350-23-01/CP, Ed. 1, Rev. 4, dated2nd December 2014Compliance Checklist, doc. ref. HI-350-23-01-Annex 1 –CCL,Ed. 1, Rev. 4, dated 2nd December 2014Master Document List, d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The present change can only be installed on AS350B3 rot...	10/06/2025	Active	10051584
10051593	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		727-200	CPDLC InstallationRev. 1: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 Amendment 1425.601, 25.1301, 25.1302, 25.1307, 25.1309, 25.1310, 25.1322, 25.1351,25.1353, 25.1355, 25.1...	Flight Manual Supplement 12587-AFM-00001 Issue 3or later revisions of the above listed document(s) approved/acceptedunder the EASA system.Master Data List MDL-12587-00001 Issue 3	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/11/2021	Active	10051593
10051595	AIRGLAS, Inc.		FAA SR02430AK	R 44, R 44 II	Installation of LRSCE-R44 Rear Seat Cargo Extension	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement (RFMS) for Robinson models R44 andR44 II equipped with Airglas LRSCE-R44 Rear CargoSeat Extensions< (>,<)>AI-LRSCE-R44-FM, Rev. A,or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2014	Active	10051595
10051609	LUFTHANSA TECHNIK AG			BOEING 747-400	Lufthansa B747-4 IK-Retrofit -This Modification reflects anexchange of all Business Class Seats,which results in an increase of 59 passengers. A new IFE System will becomplete integrated, which also involved a modification of all Economyseats, Partitions and Monuments.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI D-101 - Width of aisle - 4 passenger configuration (closed at Issue2 on 22 JUL 2014) The following paragraph(s) at a later amendment:CFR 25...	- STDD00-13/19M - Supplemental Type Definition Document, Issue 1.0(2014-DEC-04)- CP00-13/19M - Certification Program, Issue 1.0 (2014-DEC-04)- CRL00-13/19M - Compliance Record List, Issue 1.0 (2014-DEC-04)- A-00-14/29-ICA - Instructions for Continued Airworthiness, Issue 02.00 (2014-DEC-02)or later r...	This modification must be installed in conjunction with FlightStructures Inc. EASA Supplemental Type Certificate 10051480.	12/12/2014	Active	10051609
10051622	ALOFT AEROARCHITECTS	REV. 5	FAA ST01716NY	737-700	Installation of Auxiliary Fuel Systems in Boeing 737-700 IGW (BBJ),Compliant to § 25.981 amendment 25-125- All configurations listed below are approved with or without BoeingNitrogen Generation System (NGS) installed-Configuration 1-E: Installation of a Two-Cell (One Forward, One Aft)Auxiliary Fuel...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments: Special Conditions in CRI E-101 “Flammability riskreduction”.The requirements for environmental protection and the associatedcertified noise and/ o...	Master Drawing List No. 5888-2800-001, Rev. AB dated 28 Oct2020.1. Configuration 1-E: Installation of a Two-Cell (One Forward, one Aft) Auxiliary Fuel System in the forward and aft cargo compartment inaccordance with Master Drawing List No. 5888-2800-001, Rev. G dated 4November 2011, 2A Tank System6...	The aircraft must be inspected in accordance with requirements in theAirworthiness Limitations, Section 4 and 4a in theMPDS Document No.TO-1771.This installation has no adverse effect on the previously approved ETOPScapability of the type-certificated aircraft.EASA STC 10028092, "PATS AIRCRAFT L.L....	08/06/2021	Active	10051622

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051623	DSA A.S.	REV. 1		PA-31-350 (CHIEFTAIN) PA31-325 PA31-300 PA31	Installation of an IGPS (Identification of Gross Polluting Ships)monitoring system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-COMPLIANCE CHECKLIST 0010021196-001, Doc. LDA 02/12/PA31, rev. 3.1,dated 13.11.2014-AIRPLANE FLIGHT MANUAL SUPPLEMENT TO THE PIPER PA31, IGPS -Identification of Gross Polluting Ships - System, Doc. S1 LDA 02/12/PA31ISSUED 25.09.2014or later revisions of the above listed document(s) approved/ accepte...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/05/2020	Active	10051623
10051638	PAUSTIAN AIRTEX GmbH			B737-800	Installation of placards on the aircraft cabin windows inner pane.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:D-01 Installations of placards on the aircraft cabin windowsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the...	Master Documentation List MDL-DP-016 rev 00Instructions forcontinued airworthiness ICA-DP016 rev 00or later revisions of the above listed documents approved by EASA.Scope of modification descriptive document SOM-DP016 rev 01	Pending positive results of the Entry into Service phase tests (as perdocument TP-DP016-2, this certificate is limited to:-the entry into service test phase of 6 months after issuance of thiscertificate-the aircraft MSN 29329Prior to installation of this design change it must be determined thatthe i...	15/12/2014	Active	10051638
10051639	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SR03265CH	AW139, AB139	Air Ambulance Conversion.EASA STC 10051639 Rev.1 reflects the transfer of EASA STC 10051639 fromSNAKY CREEK ENTERPRISES, LLC d/b/a/ SPECTRUM AEROMED to SPECTRUMAEROMED, LCC d/b/a SPECTRUM AEROMED.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Spectrum Aeromed Master Drawing List 7012DL, revision 1,dated 29August 2013;2. Flight Manual Supplement, document 7012FMS, dated 12 September 2013;3. Instructions for Continued Airworthiness, Manual 7012MM, no revision,dated 26 July 2011;or later revisions of the above listed document(s) approve...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2019	Active	10051639
10051642	AIRBUS HELICOPTERS CANADA LIMITED		TCCA SH14-40 ISSUE 1	EC 130 T2	Cargo Mirror InstallationThe installation consists of two mirrors mounted externally, underneaththe cabin in front of the pilot, on a support frame which is fixed tothe helicopterat four attachment points on the left hand side of theaircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Helicopters Canada Limited Compliance Program, doc. ref. CP-0386issue AAirbus Helicopters Canada Limited Master Drawing List, doc. ref.MDL-14-001 Issue AAirbus Helicopters Canada Limited Instructions for ContinuedAirworthiness, doc.ref. ICA-AHCA-274, rev. 2or later revisions of the above lis...	None	15/12/2014	Active	10051642
10051657	BUCHER LEICHTBAU AG	REV. 11		MBB-BK117 D-3M MBB-BK117 D-3 MBB-BK117 D-2 MBB BK-117 D-2	Emergency Medical System (EMS) P/N ARA-EC145-AC70Rev.1) follow on certification of the oxygen system as described inCertification Plan E026-54-14.Rev.2) follow on certification ofan additional Oxygen Bottle asdescribed in Certification Plan E026-09-15.Rev.3) follow on certification for installation...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): FAR 29.807 Amdt. 30 Passenger emergencyexits (CRI D-02).- The following paragraph(s) at a later amendment:for MBB-BK117 D-2:CS...	Flight Manual Supplement ARA-EC145-AC70 Rev. APInstructionsfor Continued Airworthiness ARA-EC145-AC70 Rev. 21Rev.0):Project Certification Plan E026-01-13 Rev. CMaster Document List E034-01-13 Rev. ACertification Compliance Sheet E026-01-13; App I Rev. ARev.1):Project Certification Plan E026-54-14 R...	For Rev.8): Subject change is only applicable to MBB-BK117 D-2rotorcraft having serial number 20050 and above or havingserial numberbelow 20050 with incorporated SB MBB-BK117 D-2-25-005_01, or laterapproved revisions.Prior to installationof this change/repair it must be determined thatthe interrel...	11/11/2021	Active	10051657

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051659	PMV ENGINEERING	REV. 1		A340-643 A340-541, A340-542, A340-642 A340-311, A340-312, A340-313 A340-211, A340-212, A340-213	TCAS 7.1 upgrade on Airbus A340.The change consists of the upgrade of the current TCAS II softwareversion 7.0 to TCAS II software version 7.1. on A340 family aircraft andto updateEASA STC ref. 10051659.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- MASTER DOCUMENT LIST, ref: AVI-01710-MDL-R06 dated 17/11/2017;- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: AVI-00710-ICA-R01 dated26/06/2017;- AIRCRAF FLIGHT MANUAL SUPPLEMENT, ref: AVI-00710-AFMS-R03 dated13/07/2017;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/11/2017	Active	10051659
10051674	GFD GmbH	REV. 1		31A/35A/36A 31A, 35A, 36A	STR 700/2000 Mode 1 IFF System InstallationRev. 1: Transferto GFD GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AFM Supplement Doc. No. 5254-071 Rev. IR of 10.12.2014 or laterrevisions of the above listed documents approved by EASA.Master Data List Doc. No. 5254-049 Rev. B of 10.12.2014Instructions for Continued Airworthiness Doc. No. 5254-085 Rev. A of11.08.2014or later revisions of the above listed document...	Limited to GFD fleet. D-24806 Hohn, Germany.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introducenoadverse effect upon the airworthiness of the product.	23/08/2022	Active	10051674
10051678	S-TEC CORPORATION	REV. 1	FAA STC SA09011AC-D	M20C, M20D, M20E	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, (Model ST-592)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation, according Bulletin No. 692, Revision 4, dated1-03-02 andMaster Drawing List No. 92792, Revision D, dated1-03-02 (14 VoltSystem).Operations and Maintenance accordingto FAA/DAS Approved Pilot'sOperating Handbook and/or Airplane Flight Manual Supplement, P/N 891177.or later revisions of...	1. Model M20D eligibility limited to aircraft modified per MooneyDrawing No. 950082 (Retractable Gear conversion). 2. FAA/DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891177, dated 6-26-95 is requiredfor MooneyModels M20C; M20D when modified per Mooney Drawing...	18/12/2014	Active	10051678
10051682	MT-PROPELLER ENTWICKLUNG GmbH			EA 300/200	Installation of 3-blade MTV-9-B-C/ C188-18B on Extra 200	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	MT-Propeller Master Document List No. E-2504To be operated in accordance with MT-Propeller AFM-S Document No. E-2500or later revisions of the above listed documents approved by EASAMT-Propeller Installation Instructions Doc. No. E-2501To be maintained i.a.w. MT-Propeller ICA Document No. E-2502	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/12/2014	Active	10051682
10051683	MT-PROPELLER ENTWICKLUNG GmbH			A36	Installation of 5-blade MTV-5-1-D-C-F-R (A)/CFR210-56 on A36Bonanza	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	MT-Propeller Master Document List No. E-2438To be operated in accordance with MT-Propeller AFM-S Document No. E-2434or later revisions of the above listed documents approved by EASA.MT-Propeller Installation Instructions Doc. No. E-2435To be maintained i.a.w. MT-Propeller ICA Document No. E-2436	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/12/2014	Active	10051683

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051684	H4 AEROSPACE (UK) Ltd.	REV. 3	UK CAA STC UK.STC.00135	BOEING 747-400 747-400, 747-8, 747-8F	Electronic Flight Bag (EFB) ProvisionsRevision 3 is a transfer from Tenencia Ltd. to H4 Aerospace (UK) Ltd.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	TEN 757 - Modification Report (Master Data List), issue 20 dated 18March 2021Tenencia Ltd Maintenance Manual SupplementNo.s TEN 757-04 (747-400)issue 7 and TEN 757-04.1-CLX (747-8) issue 1.Tenencia Ltd AFM Supplement No.s TEN 757-47 (747-400) issue 3 and TEN757-47.1 (747-8) issue 2or later revision...	See section 2 of the AFM SupplementFollowing the future EFBinstallation, an operational assessment, inaccordance with AMC 20-25, must be conducted to assess the impact of thelossof ARINC data to the EFB system and the impact on aircraftoperation due to the loss of the EFB system, considering inten...	10/12/2024	Active	10051684
10051689	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 1		A321-111 / -212 A320-214	Installation of aft galley/lavatory complex.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan N0462-D01 Rev. A, dated November 19, 2014Certification Summary N0462-D90 Rev. -, dated December 15, 2014Master Drawing List N0462-D10 Rev. B, dated December 14,2014Instructions for Continued Airworthiness N0462-D70 Rev.A, datedNovember 26, 2014or later revisions of the above lis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/12/2014	Active	10051689
10051695	NORTHWEST AEROSPACE TECHNOLOGIESI NC.			A319-131	Cabin interior modification on British Airways A319-131 Aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: JAR 25 Change 13 for:25.562 (a) and (c), 25.812 (a) and (e), 25.853 (a), (b) and (c).The requirements for environmental pr...	NAT Inc. Master Drawing List No. N0465-D10 Issue C dated 15December2014	British Airways Minor Modification No. SB A319-25-0010 mustbe embodiedconcurrently with this STC.	18/12/2014	Active	10051695
10051700	ARMSTRONG AEROSPACE Inc.		FAA STC ST03180NY	777-300ER	Installation of OnAir Inflight Connectivity System	The Certification Basis for the original product as amendedby thefollowingadditional or alternative airworthiness requirements:CS 25.831 Amdt 0, CS 25.853 Amdt 12, CS 25.869 Amdt0, CS 25.981 Amdt 0,CS 25.1353 Amdt 0, CS 25.1431 Amdt 0Therequirements for environmental protection and the associated...	-Master Data List, Armstrong Aerospace document No. DC104-9154-00,Revision E, dated 21 March 2014-Instructions for Continued Airworthiness, Armstrong Aerospace documentNo. 0743-08793-2331, Revision B, dated 16 December 2013-Airplane FlightManual Supplement, Armstrong Aerospace document No.DC303-915...	a) If the holder agrees to permit another person to use this certificateto alter a product, the holder must give the other person writtenevidence of that permission.b) Operationalapproval to use T-PED's must be obtained separately fromthis STC.c) The OnAir must interface with the following listed r...	18/12/2014	Active	10051700
10051706	DISCOVERY AIR TECHNICAL SERVICES		TCCA SA14-14	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-102, DHC-8-103,DHC-8-106	Installation - SAGEM Aircraft Piloting Inertial Reference Sensor (APIRS)F227 - AHRS Upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:For DHC-8-100/300 models: CS 25.561, 25.571, 25.1307, 25.1529 all atAmdt. 0	Installation must be in accordance with Discovery Air Technical ServicesMaster Drawing List MDL12003, Rev. BOperation must be in accordance with Discovery Air Technical ServicesFlight Manual Supplement FMS12003-01, Rev. DMaintenance must be in accordance with Discovery Air Technical ServicesInstruct...	Installation is limited to DHC-8-100/200/300 non-EFIS equipped models.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwort...	18/12/2014	Active	10051706

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051709	AIRBUS DEFENCE AND SPACE S.A.	REV. 1		A320-231/-232/-233 A320-211/-212/-214/-215/-216	Installation of V/UHF radio on Airbus Corporate Jet aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan ME-DA-DT-140003 Issue D, dated 18/12/2014Damage Tolerant Airworthiness Limitation Items SupplementME-DA-DT-140002 Issue B, dated 02/12/2014or later revisions ofthe above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/12/2014	Active	10051709
10051710	AVMAX AVIATION SERVICES Inc.		TCCA SA13-19	DHC-8-201/-202 DHC-8-102/-103/-108	Triple Litter Stacking System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Avmax Aviation Services Inc. EngineeringOrder CE14-401, Issue C.Maintenance in accordance with Avmax Aviation Services Inc. MaintenanceManual Supplement CE14-701, Initial Issue.Operation in accordance with Avmax Aviation Services Inc. Flight ManualSupplement CE14-801,...	The compatibility of stretchers to be installed must be approved by theresponsible authority.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse...	18/12/2014	Active	10051710
10051729	AVIATION SPECIALTIES UNLIMITED, INC	REV. 3	FAA SR01207SE	EC135T3, EC135P3 EC135T1, EC135T2, EC135T2+, EC135P1, EC135P2, EC135P2+,	Installation of Night Vision Imaging System (NVIS) compatible lightingRev. 1: Installation of S/N 0533 to the MDL-135004-3Rev. 2: Addition of model EC135 P3Rev. 3: Addition of model EC135 T3 with Helionix cockpit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List MDL-135004-3 Revision JF- Instructions for Continued Airworthiness ICA-135004-4 Revision F- Rotorcraft Flight Manual Supplement FMS-135004-6 Revision R- Project Specific Certification Plan ASU-PSCP-135-2043 Revision For later revisions of the above listed document(s) approved/a...	Rotorcraft modified by this design change employ Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviationfrom the cockpit or cabin configurationspecified in this des...	12/12/2019	Active	10051729
10051733	DELTA G DESIGN Inc.	REV. 1	FAA ST11126SC	A321-271N/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-271N A320-232/-233/-251N/-252N A320-231/-232/-233 A320-211/-212/-214/-216/-231 A320-211/-212/-214 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Structural modification necessary for the installation of an IGA-5001Intermediate Gain AntennaRev. 1 of this STC compiles the following design changes: - MDL Revision F . Installation Drawing, addition of note to clarify connectorinstallation - MDL Revision G . Added new ai...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.251(a)(b)(c)(d) Amdt 0, 25.305(a)(b)(e) Amdt 1, 25.307(a) Amdt 1, 25.321(b) Amdt 0, 25.333(b) Amdt 0,2...	- Master Data List, Delta G Design document No. DGD-IGA0I-MD-01,Revision K, dated 15 DEC 2023- Instructions for Continued Airworthiness, Delta G Design document No.DGD-IGA01-IC-01, Revision B<(>,<)>dated 18 JUL 2019or later revisions of the above listed document(s) approved/accepted onbehalf of EASA...	This certificate is for structural provisions only. EMI andfunctionaltesting are required as part of a separate approval when associatedcomponent parts are installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherp...	04/09/2024	Active	10051733
10051734	AIRBUS S.A.S.			A319-115	Airbus Corporate Jet Modification CJ1700 VIP Project "Butterfly"	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition(s):CRI E-21 - Isolated CompartmentsCRI D-0314-000 - Shower InstallationCRI D-4322-002 - MinisuitesEquivalent Safety Finding(s):CRI E-28 - Improved Flamma...	Modification Approval Sheet CJ1700, Issue 1, dated 18/12/2014Airplane Flight Manual - AFM Supplement FM-S MOD CJ1700, dated01/12/2014Maintenance Planning Document - MPD SupplementMPD-S MOD CJ1700, dated01/12/2014or later revisions of the above listed documents approved by EASA	This approval is limited to MSN 5768	19/12/2014	Active	10051734

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051745	LUFTHANSA TECHNIK AG			A320-231/-232/-233 A320-211/-212/-214/-215/-216	Installation of SWISS MAX cabin layout	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Definition Document STDD25-13/43M Issue 1Rev. 0,dated 03/12/2014Compliance Record List CRL25-13/43M Issue 1 Rev. 1, dated 08/12/2014Instructions for Continued Airworthiness A-00-14/53-ICA Issue 2 Rev. 0,dated 19/12/2014or later revisions of the above listed documents approved by E...	This modification must be installed in conjunction with NorthwestAerospace Technologies STC 10051689 Rev 1.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introd...	19/12/2014	Active	10051745
10051755	E A D AEROSPACE AIRWORTHINESS	REV. 2		A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Activation for GSM/WiFi Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List, EAD Aerospace document No. 01442-EAS-A-MDL,Revision A, dated 18 December 2014.-Instructions for Continued Airworthiness, EAD Aerospace document No. 01442-EAS-A-ICA-01, Revision A, dated 26 September 2014-Aircraft Flight Manual Supplement, EAD Aerospace document No.01442-EAS-A-AF...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/01/2015	Active	10051755
10051760	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			208B 208	A-14-01-AVIALAVAL_RADALT Installation of a KRA405B on Cessna 208BRevision 0 dated 19 December 2014	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement A-14-01-AVIALAVAL-RADALT Ed1 Nov 2014or later revisions of the above listed documents approved by EASA.	None	22/12/2014	Active	10051760
10051763	AEROSTRUKTUR FASERVERBUND TECHNIKGmbH			A36, A36TC	Increase of Maximum Take-off Weight (MTOW)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The CertificationBasis for the original product as amended by thefollowing additional or alternative airworthiness requirements:Regardless of the change assessed not being significant, it was elect...	POH/AFM Supplement (Document No. PO-BA36-570001)or later revisions of the above listed documents approved by EASADefinition of design change: DE-BA36-570001Information for continued airworthiness: MM-BA36-570001	None	22/12/2014	Active	10051763
10051769	AEROTEC & CONCEPT			1900C	Avionics update including GPS-400W, MD-41 ACU, Sandel SN4500 and SN3500in order to provide P-RNAV & LPV capability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with AEROTEC modification ref AE14230.Operate in accordance with AEROTEC Flight Manual Supplement refAE14230AFMS Rev 0 dated December 2014.Maintain in accordance with AEROTEC Instructions for ContinuedAirworthiness (ICA) ref AE14230ICA Rev 0 dated 20 October 2014.or later...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/12/2014	Active	10051769

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051788	AEROMECH Inc.			727C 727-200F 727-200 727-100C 727-100 727	Group Approval for Reduced Vertical Separation Minimum	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement727-03-100200 S Rev Cor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentrevisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.Aircraft System...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/12/2014	Active	10051788
10051820	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST03141CH	747-400F 747-400	Installation of a Rosemount Aerospace electronic flight bag(EFB) classIII:- Configuration 1: Installation of Dual SDU electrical power withcrosstalk capabilities between the two units- Configuration 2: Installation of Dual SDU and EFB-IU P1 connectionsonly- Configuration 3: Installation of Dual SDU...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt 0:25.29 (b), 25.301(a) , 25.303, 25.305 (a) , 25.305(b), 25.307(a),25.561 (c) , 25.562(c)(5) , 25.601, 25.603, 25.605(a), 25.607, 25.609,25.611, 25.613(a) , 25.619,...	- Master Data List ECS-209908 rev L- AFMS Configuration 1 ECS-209920 Rev B- AFMS Configuration 2 ECS-209935 Rev B- AFMSConfiguration 3 ECS-209936 Rev B- AFMS Configuration 4 ECS-210440 Rev A- AFMS Configuration 5 ECS-210542 Rev A- Instructions for continued airworthiness ECS-209921 rev C- Weight an...	- EZ Mount mechanical mounting assemblies approved by EASA STC 10040901(FAA STC ST02907CH) is a prerequisite for the design changes describedin this approval.- Information displayed on the EFB is not to be used for primarynavigation, and shall be used for reference only.- This STC does not provide o...	07/01/2015	Active	10051820
10051858	S-TEC CORPORATION		FAA SA09153AC-D	FR172 G, FR172 H. FR172 E, FR172 F,	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-616 in accordance with FAA STC SA09153AC-D	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 92925, Rev. C, dated June 1, 2010Installation Instructions Bulletin No. 716, Rev. 3, dated June 1, 2010Airplane Flight Manual Supplement 891257, Rev. 1, dated October 12, 2001or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004...	If the holder agrees to permit another person to use this certificate toalter the product, the holder must give the person written evidence ofthat permission.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously...	09/01/2015	Active	10051858
10051860	CLUB AEROSTATIQUE DE FRANCHE-COMTE			GALAXY-7	Cameron Basket CB 300 installation on a Hot Air Balloon Galaxy 7envelope.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	Aircraft Manual Supplement <<Supplément au manuel de vol V2>> dated 5January 2015or later revisions of the above listeddocuments approved by EASA.	Modification limited to the Galaxy 7 envelope, sn GLX-1737,with aCameron MK4S burner and its load frame.	09/01/2015	Active	10051860
10051871	AIRLEC AIR ESPACE			SA226-T (B) SA226-T SA226-AT	AAE004 - MVP-50T Display Engine	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:Refer to certification program AAE004 CP document for paragraphs at CS23Amdt 3.The requirements for environmental protectio...	STC Data List AAE004 SDL Rev 3 dated 08/01/2015Supplément Manuel de Vol AAE004 AFM Rev 2 dated 26/11/2014or later revisions of the above listed documents approved by EASA.Instructions Continued Airworthiness AAE004 ICA Rev 0 dated 26/11/2014Instruction Technique AAE004 IT Rev 0 dated 08/01/2015Suppl...	None	12/01/2015	Active	10051871
10051872	EMTEQ CANADA Ltd.		TCCA C-LSA14-212/D	CL-600-2D24	Removal of Optional FWD galley and lavatory	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Transport Canada, STC No. C-LSA14-212/D Issue 1 dated 05 December 2014EMTEQ Canada Modification Data Summary J983000 Revision N/Cor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.	Restricted to ASN 15065	12/01/2015	Active	10051872

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051877	SCANDINAVIAN AVIONICS DESIGN ApS			DHC-8-402 DHC-8-401 DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Upgrade of TCAS 7.0 to 7.1 on DHC-8 100/200/300/400 Series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25.1301, CS 25.1309, CS 25.1581 - all at Amendment 4.The requirements for environmental protection and the associatedcer...	Installation must be in accordance with Technical Order Doc. 2090767-TO,Issue 1.Operation must be in accordance with AFM Supplement Doc. 2090767-AM A,Issue 1.Continued Airworthiness must be in accordance with ICA Doc. 2090767-CA,Issue 1.orlater revisions of the above listed documents approved by EA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/01/2015	Active	10051877
10051880	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	JETSTREAM 4100	TCAS II Upgrade to Version 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate approval. The CertificationBasis for the originalproduct as amended by the following additional or alternativeairworthiness requirements:CS 25 Amendment 1425.1301<(>,<)> 25.1309<(>,<)> 25.1529<(>,<)> 25.1581...	Cranfield Supplement No.3 Issue 1 to EASA Approved Flight Manual Doc.No. J41.01or later revisions of the above listed documents approved by EASA.Type Design Definition Addendum CAeM/ Jetstream41/1408 Issue A	Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any other previouslyinstalleddesign change and/or repair will introduce no adverse effect upon theairworthiness of the product.	13/01/2015	Active	10051880
10051884	PMV ENGINEERING			A320-216	Tune Box IFE and Satcom SBB installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval, except for the Antenna Installation:CS 25.251(a)(b)(c)(d) Amdt 0<(>,<)> 25.305(a)(b)(e) Amdt 1, 25.307(a)Amdt 1,25.321 (b) Amdt 0, 25.333(b) Amdt 0, 25.351, Amdt 0, 25.365(e)Amdt 0,25.571(a)(b1)(b2)(...	- Master Document List SCA-00380-MDL-R00 dated 23 Dec. 2014-Aeroplane Flight Manual Supplements as per SCA-00380-MDL-R00-Instructions for Continued Airworthiness as per SCA-00380-MDL-R00or later revisions of the above listed documents approved by EASA.	- All subparts of this STC must be installed concurrently.-This installation is intended to provide wireless data technologyservices using portable electronic devices (PEDs) for passengerentertainment purposes. Any other intended functionof this equipmentwill require a re-examination of the certif...	13/01/2015	Active	10051884
10051890	DUNCAN AVIATION, INC.		FAA ST01679WI	EMB-135LR EMB-135BJ, EMB-135ER,	Enable Wireless Local Area Network (WLAN) for use with TransmittingPortable Electronic Devices (TPEDs).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Duncan Aviation Inc. Master Document List N °111122022, Revision C, datedJanuary 9, 2014Airplane Flight Manual Supplement, Duncan Aviation Inc. DocumentN °111122019, Revision A, dated March 27, 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 200...	This system is intended to provide internet connections ande-mailmessages using T-PEDs. Any other intended function ofthis system willrequire a reexamination of the certification basis.Prior to installation of this design change it must be determined thatthe interrelationship between this design c...	13/01/2015	Active	10051890
10051900	IKHANA GROUP, LLC	REV. 2	FAA STC SA02252LA	DHC-6 SERIES 200	Increase in the maximum take-off weight to 5.670 kg (12,500lb.). Thismajor design change includes installation of PT6A-27 engines operatingat 620 SHP in place of PT6A-20 engines operating at 550 SHP, and OEMmodifications that affect the airworthiness of the DHC-6 Series 200 foroperations at 12,500R...	Certification Basis: FAR 23 at:Amdt. 0: 23.171, 23.231, 23.329. 23.303, 23.307, 23.363, 23.405, 23.407,23.409, 23.471, 23.481, 23.483, 23.493, 23.601, 23.609, 23.627, 23.641,23.651, 23.659, 23.671, 23.681, 23.687, 23.693, 23.699, 23.1367,Amdt. 0: 23.1381(a)(b)(c), 23.1399, 23.1415, 23.1519, 23.1551A...	Airplane Flight Manual HG-62-1A, Rev. A, dated 29 May 2014Weight & Balance Supplement HG-62-8, IR, dated 26 June 2009Master Data List ER218-2010, Rev. B, dated October 15, 2010Drawing List ER218-2000, Rev. D, dated August 5, 2010or later revisions of the above listed documents approved by EASA inacc...	1. Approval of this modification applies to the above notedmodelairplane series only. This approval should not be extended to otherspecific airplanes of this model series on which other approvedmodifications are incorporated, unless it isdetermined that theinterrelationship between this change and...	18/06/2021	Active	10051900
10051908	SABENA TECHNICS BOD	REV. 1		A340-311/-312/-313 A330-341/-342/-343 A330-323/-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303/-321/-322 A330-301/-302/-303 A330-223/-243 A330-201/-202/-203	IAGOS - AEROSOL PROBE INSTALLATIONThe modification consistsin the replacement of the IAGOS inlet platesensor: the pre-modification is one of the Rosemount probe type, thepost-modification is an aerosol probe type.Rev 1: addition of A330-200 models to applicability list.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Drawing List MDL S-25-2273 Issue CICA document ICA-F4036-00-005 Rev Bor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	IAGOS pre-mod configurations as per-EASA STC 10028070 for A340-300 or-EASA STC 10045974 for A330-200/-300Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no ad...	13/10/2020	Active	10051908

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051930	J.P. INSTRUMENTS, INC		FAA SA00729SE	SEE APPROVED MODEL LIST	Installation of twin temperature indicating system with fuel flow.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with J P Instruments (JPI) InstallationManual Report No 760 Revision -, dated 7/20/99.Operate in accordance with JPI Flight Manual Supplement ref No760-1dated August 31, 1999.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decisi...	Cylinder head, oil, turbine inlet and/or exhaust gas temperature, fuelflow equipment, tachometer instruments, and manifold pressureinstruments required by the original type design, or if required byother approval must be installed.Prior toinstallation of this design change it must be determined tha...	16/01/2015	Active	10051930
10051935	J.P. INSTRUMENTS, INC		FAA STC SA01828SE	SEE EASA APPROVED MODEL LIST	Installation of J P Instruments (JPI) EDM-960 Primary Engine DataManagement System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with JPI Installation Manual forEDM-960,Report No 909, Revision NC, dated February 22,2009.Operate in accordance with JPI FAA approved Flight Manual Supplement No960-001, dated March 27, 2009.or later revisions of the above listed documents approved by EASA inaccordance w...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/01/2015	Active	10051935
10051937	J.P. INSTRUMENTS, INC		FAA SA00861SE	SEE EASA APPROVED MODEL LIST	Installation of J P Instruments (JPI) fuel flow indicating system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with JPI Installation Manual FS-450, ReportNo,400, Revision -,dated August 16, 2000.Operation/ in accordance with J P Instruments Flight Manual SupplementNo 1, dated December 18, 2000.or later revisions of the above listed documents approved by EASAt...	This STC requires the installation of a fuel Flow Transducer per FAA STCSA00432SE, or aircraft listed on the FAA approved AML SA00432SE and thathave been previously modified with a fuel flow transducer P/N 201-A, 201-B, 201-C or 231 are eligible for installation for the FS-450, it isthe installers re...	19/01/2015	Active	10051937
10051939	J.P. INSTRUMENTS, INC		FAA SA01435SE	SEE EASA APPROVED MODEL LIST	Installation of J P Instruments (JPI) Primary Engine Data ManagementSystem.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with JPI Installation Manual forthe EDM900/930, Report 908, dated September 9, 2004.Operation in accordance with JPI Flight Manual Supplement ref EDM-900and EDM-930, Primary Engine Data Management System, dated December 10,2004, Document Numbers 900-0001 and 930-0001 Revo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/01/2015	Active	10051939
10051947	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 2		737-700	Interior Reconfiguration of KLM	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List, Northwest Aerospace Technologies, Inc. documentNo. N0485-D10, Revision B, dated 13 January 2015.-Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0485-D90, Revision -, dated 18 January 2015.-Instructions for Continued Airworthiness, Northwest Aerospace...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/02/2017	Active	10051947

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051948	DELTA ENGINEERING CORPORATION		FAA STC ST03189NY	BOEING 767-300	Installation of a Bruce Aerospace Cabin lighting "Mood Lighting"system.This STC installs new cabin lighting, with LED modules which requireless power. These lights are for generalillumination and provide noemergency lighting. They requirepower and interface with a new controlpanel to allow crew to...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Delta Engineering Master Data List, ref : 0144-08909-2366 Revision A,dated 11 April 2014.Delta Engineering Instruction for Continued Airworthiness, ref:0744-08910-2366 Revision A,dated 11 April 2014Bruce Aerospace Weight & Balance report,Ref : 351-732 Issue B, dated 04April 2014FAA AMOC 140S-14-89...	None	20/01/2015	Active	10051948
10051957	AIR ALLIANCE GmbH	REV. 1		35, 35A	Installation of Dual Garmin GTN 750(Xi) NAVCOM and Sandel SN4500 EHSI	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List, Air Alliance GmbH document No. 2014-001-MDL,Revision 01, dated 16 March 2021Aeroplane Flight Manual Supplement, Air Alliance GmbH document No.2014-001-AFMS, Revision 01, dated 26 February 2021Instructions for Continued Airworthiness, Air Alliance GmbH document No.2014-001-ICA-0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/03/2021	Active	10051957
10051958	AIR ALLIANCE GmbH	REV. 2		35A 35, 35A 35	SOFTWARE UPGRADE FOR GARMIN GTS 8000 TCAS and GTX 3000 XPDR	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Service Bulletin – GTX 3000 and GS 8000 Software Update, Ref2014-005-SB-001 initial issue; Master Document List Ref 2014-005-MDLinitial issueor later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/05/2023	Active	10051958
10051962	AIR ALLIANCE GmbH	REV. 1		35, 35A	Installation of dual Rockwell Collins AHS-1000	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Air Alliance, Master Document List, 2014_004_LJ35_Form2, revision 02,dated 15 January 2015.Air Alliance, Aircraft Flight Manual, 2014_004_LJ35_0506, revision 00,dated 08 May 2014.Air Alliance, Instructions for Continued Airworthiness, 2014_004_LJ35_0507, revision 00, dated 09 May 2014.or later revisi...	None	04/05/2015	Active	10051962
10051963	AEROTEC & CONCEPT			737-900ER 737-800	Dual Iridium / GPS Antenna Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, Aerotec Concept document No. AE14223MDL,Revision 0,dated 21 January 2015.- Instructions for Continued Airworthiness, Aerotec Concept document No.AE14223ICA, Revision 0, dated 18 November 2014.or later revisions of the above listed documents approved by EASA	None	21/01/2015	Active	10051963

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10051976	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	757-200, 757-200PF	Introduction of T2CAS product software	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List, STC Twenty One document No. S21.MDL-1060, Issue2, 22 January 2015-Flight Manual Supplement, STC Twenty One document No. S21.FMS-0115,Issue 1, 28 November 2014or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/01/2015	Active	10051976
10051990	E A D AEROSPACE AIRWORTHINESS	REV. 1		767-300/-300F	Installation of ELT antenna and provisions for ELT beacon A06V2.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt 4 for affected area:25.1<(>,<)> 25.29<(>,<)> 25.301<(>,<)> 25.303<(>,<)> 25.305<(>,<)>25.307<(>,<)>25.337<(>,<)> 25.341<(>,<)> 25.365 (a)(b)<(>,<)> 25.561<(>,<...	Master Data List 01437-EAS-A-MDL rev BWeight and Balance analysis 01437-EAS-A-WBA-01 rev AMPD Supplement 01437-EAS-A-MPD-01 rev Aor later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/02/2015	Active	10051990
10051992	ARMSTRONG AEROSPACE Inc.	REV. 1		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214 A319-131/-132/-133 A319-111/-112/-113/-114/-115	EASA Validation of FAA STC ST03406CH, originally issued December 18th,2014.Certification of Compatibility with Cellularand Wireless DataTechnologies in accordance with Armstrong Aerospace Master Data List,Doc. No. DC104-9619-00, Revision-, dated December 4th 2014 or laterapproved revisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Armstrong Aerospace Master Data List, Doc. No. DC104-9619-00, Revision-, dated December 4th 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures o...	1) Limitations for installations utilizing both Cellular and WirelessData Technologies compatibility aspects of this STC, as defined in Group1 of Armstrong Aerospace Master Data List, Doc. No DC104-9619-00,Revision-, dated December 4th, 2014, or later approved revision:a) This STC may only be applie...	26/01/2015	Active	10051992
10051996	PATS AIRCRAFT L.L.C.		FAA STC ST02853NY	757-200	Installation of two forward and four aft tank auxiliary fuel systemconfiguration in the forward and aft cargo compartments.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.29 Amdt 0, 25.305 Amdt 1, 25.571 Amdt 0, 25.603 Amdt 0, 25.605Amdt 0<(>,<)> 25.613 Amdt 1, 25.869 Amdt 5, 25.981(a) Amdt 9, 25.994Amdt 3, 25.1305 Amdt 0<(>,<)> 23.13...	-Master Drawing List, PATS Aircraft LLC document No. 5976-0001-MDL,Revision P<(>,<)> dated July 2, 2010-Maintenance Manual Supplement, PATS Aircraft LLC document No. TO-3317<(>,<)> Revision IR, dated May 15, 2010-Airplane Flight Manual Supplement, PATS Aircraft LLC document No. 204,Revision IR, date...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/01/2015	Active	10051996
10052011	JET AVIATION AG	REV.1		LEARJET 31/31A/35/35A/36/36A	Upgrade of existing Honeywell TCAS to 7.1 Software	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmental protectionand the associated certificated noiseand/ or emissions levels of theoriginal product are unchanged and remain applicable to thiscertificate/approval	Jet Aviation, Aircraft Flight Manual Supplement, TCAS II (ACAS II)Upgrade to Version 7.1, JBSL-M-00342-AFM-01, issue 1Jet Aviation, Instructions for Continued Airworthiness,JBSL-M-00342-ICA-01, issue 1, dated 08 January 2015.Jet Aviation, Engineering Order, JBSL-M-00342-ENO-01, issue 2, dated 23Janu...	None	02/02/2015	Active	10052011

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052018	DELTA ENGINEERING CORPORATION			B757-200	Installation of a Bruce Aerospace Cabin Lighting.This STC installs new cabin lighting, with LED modules which requireless power. These lights are for general illumination and provide noemergency lighting. They require power and interface with a new controlpanel to allow crew to change the state of t...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/ approval	Delta Engineering Master Data List, ref : 0144-09012-2378 Revision D,dated 31October 2014.Delta Engineering Instructionfor Continued Airworthiness, ref: 0744-09014-2378 Revision B, dated 03 November 2014Bruce Aerospace Weight & Balance report:- Config 1 : Ref 351-737 Issue D- Config 2 : Ref 351-78...	None	27/01/2015	Active	10052018
10052022	DART AEROSPACE Ltd.	REV. 1	TCCA STC SH14-45 ISSUE 1	AW119MKII	D-119-796 Crosstube Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/approval	Master Document List MDL-D119-796, Rev. AInstallation Instructions IIN-D119-796, Rev. BInstructions for Continued Airworthiness ICA-D119-796, Rev. 0Airworthiness Compliance ReportACR-D119-796-1, Rev. A (CertificationPlan)or later revisions of the above listed documents accepted by EASA inaccordance...	None	13/02/2015	Active	10052022
10052026	ARMSTRONG AEROSPACE Inc.		FAA STC ST02276CH	B727-200F	Installation of an ELTA ADT 406 AF emergency locator transmitter (ELT) system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative -airworthiness requirements:Special Conditions: H-01 EWISThe following paragraph(s) at a later amendment:CS 25 amdt 1:25.1, 25.29, 25.301(a)-(c), 25.303, 25.305(a)-(f), 25.307(a)(b)(d), 25.365(a)-(g)...	Master Data List DC104-3164-00 rev AAFM Supplement DC303-3164-00 rev - Instructions for Continued Airworthiness DC113-3164-00 rev -or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Tec...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/01/2015	Active	10052026
10052044	J.P. INSTRUMENTS, INC		FAA STC SA2586NM	SEE EASA APPROVED MODEL LIST	Installation of J. P. Instruments temperature monitoring systems	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instruments Drawing List Report No. 100, Revision D, dated December 19,1996Flight Manual Supplement no. 1 for EGT-701 temperature indicator,Revision A, dated December 13, 1996or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequen...	Approval of this change in type design applies to the abovemodelaircraft only.This STC requires the installation of JPI temperature monitoring systemsvia FAA STC SA2586NM.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any o...	02/02/2015	Active	10052044
10052045	J.P. INSTRUMENTS, INC		FAA STC SA00432SE	SEE EASA APPROVED MODEL LIST	Fuel flow transducer	The certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	J.P. Instruments (JPI) Fuel Flow Installation Manual Report 503,Revision B, dated March 14 1997JPI Drawing List, Report No. 500, Revision B, dated 14 March 1997or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisionst...	Approval of this change in type design applies to the abovemodelaircraft onlyThis STC requires the installation of JPIfuel flow instrument via STCSA2586NMPrior to the installation of this design change it must be determinedthat the interrelationship between this design change and any otherprevious...	04/02/2015	Active	10052045

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052046	LITEAIR AVIATION PRODUCTS Inc.	REV. 2	FAA STC ST00691SE	SEE EASA APPROVED MODEL LIST	Validation of the up-issue of the FAA STC No. ST00691SE, dated 20 May2014.Installation and Maintenance of lightweight window plugs in accordancewith LiteAir Aviation Products Master Drawing List reference LAP1003-D01Revision B, dated March2014.History:The replacement window plug installation, the s...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	LiteAir Aviation Products Master Drawing List reference LAP1003-D01Revision B, dated March 2014.or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisdecision)" and/ or the Technical Implementation Procedures o...	Maintenance Instructions:LiteAir document DOC.LAP2003 Rev Bdated March 2014 or laterapproved revision Section 4 details maintenance instructions and theseshould be incorporated into the aircraft maintenance manual andMaintenance Programme.Limitations1. Lightweight window plug installation is not pe...	24/08/2015	Active	10052046
10052047	DUNLOP AIRCRAFT TYRES LIMITED	REV. 2	CAA UK RESPONSIBILITY	CL-600-2D24 CL-600-2D15 CL-600-2C10	Amendment of UK CAA STC reference CAA.21NE2.00100 with partnumbersDR32118T and DR32212T to include a new Main Landing Gear Tyre partnumber (DR32120T) and a new aircraft variant	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dunlop Aircraft Tyres Master Document List No. DATL PR07 Issue Initial	None	09/08/2016	Active	10052047
10052048 (EASA.A.S.00653)	DOA AESGLOBAL LIMITED	REV. 1		767-300	Introduction of 258 Passenger Configuration and Associated Cabin ChangesRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.		Aerospace Engineering Solution Master Data List AES-767-329MDL at Issue3 or later approved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	28/04/2021	Active	10052048
10052049	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 4		A321-211/-231 A320-214/-232/-233 A319-112/-132	Wireless In-Flight Entertainment (IFE) System Installation on LATAMAircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0506-D90, Revision A, dated 11 September 2015.-Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0494-D70, Revision C, dated 11 May 2015or later revisions of the above listed docum...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/10/2015	Active	10052049
10052055	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BAE 146 SERIES 300 BAE 146 SERIES 200 BAE 146 SERIES 100 AVRO 146 SERIES RJ85 AVRO 146 SERIES RJ70 AVRO 146 SERIES RJ115 AVRO 146 SERIES RJ100	Introduction of TCAS Change 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: JAR 25 Change 10 - JAR25.1301; JAR 25.1309; JAR 25.1431; JAR 25.1581; JAR 25.1585.The requirements for environmental prote...	"EASA Approved": STC Twenty One Flight Manual Supplement S21.FMS-0116Issue 1"EASA Accepted": STC Twenty One Master Document List S21.MDL-1221 Issue2	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/01/2015	Active	10052055
10052075	AVIATION FABRICATORS, Inc.		FAA STC SA00068WI	3. 58TC, 58TCA 2. 58, 58A 1. 36, A36, A36TC, B36TC	Installation of a stretcher on to the seat rails.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Aviation Fabricators Drawing List refNo AF-162 dated May 25, 1993 and Installation Instructions ref AF-115dated 12/28/92.Maintain in accordance with Aviation Fabricators Instructions forContinued Airworthiness (ICA) Document ref No AF-609 Rev IR datedOctober 6, 2014....	Whilst this installation provides some provisions for carriage ofmedical equipment. This STC grants no approval to installation orcarriage of that equipment. Any equipment fitted/carried will require aseparate EASA approval.Prior to installation of this design change it must be determined thatthe in...	29/01/2015	Active	10052075

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052076	TEMPUS JET CENTERS II, LLC.		FAA STC ST02481LA	A319-115	Installation of a VIP Interior Modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	FAA Supplemental Type Certificate ST02481LA issued on July 17<(>,<) >2014Master Data List 8425-ED-MDL Rev. F, dated June25, 2014Airplane Flight Manual Supplement 8245-EM-AFMS Rev.A, dated June 25,2014Instructions for Continued Airworthiness 8425-ICA Rev. IR, dated August4, 2013FAA Part 25 / EASA CS...	EASA STC EASA.A.S.00375 must be installed prior to installation of thepresent airworthiness approval	29/01/2015	Active	10052076
10052077	ANJOU AERONAUTIQUE S.R.L.			A320-214	Cabin reconfiguration	The Certification Basis (CB) for the original product remains applicableto thiscertificate/ approval. The requirements for environmental protection andtheassociated certified noiseand/or emissions levels of the originalproduct areunchangedand remain applicable to this certificate/ approval	Master Data List, AnjouAero document No. 02-401888-MDL-001 Revision 1,dated28 January 2015.Airplane Flight Manual Supplement, AnjouAero document No. 02-401888-AFMS-001, Revision 0,dated 18 November 2014.or later revisions of the above listed documents approved by EASA.	The design change is limited to MSN 3025. Extended overwater operationsare prohibited.	29/01/2015	Active	10052077
10052078	PMV ENGINEERING			767-200, 767-300	B767 Cabin interior change and In-Flight Entertainment (IFE) systeminstallationThe modification consists in the reconfiguration of the cabin from a twoclass 221 PAX (30 B/C + 191 Y/C) to a three class 197 PAX (3F/C + 30 B/C+ 164 Y/C), together with the installation of an IMS/Zodiac InflightInnovatio...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):CRI D-03 Installation of suite type seatingCRI D-02 Application of heat release and smokedensity requirements toseat materials (fully equivalent to C...	Master Document List, PMV Engineering document SCA-00320-MDL-R02 dated29 Janvier 2015.Certification Investigation Report, PMV Engineering documentSCA-00320-CIR-R05 enclosing Declaration of Compliance dated 29 Janvier2015.Certification Investigation Report, PMV Engineering documentCAB-01030-CIR-R00 e...	The following design changes are considered as part of the prerequisiteconfiguration of the aircraft and must be embodied on aircraft prior, orconcurrently, to the application of the design change covered by thisapproval:- STC FAA ST03665AT: Lavatories change- STC FAA ST02214NY: Retrofit CabinNote:r...	29/01/2015	Active	10052078
10052094	GENEVA AVIATION Inc.		FAA STC SR02301SE	EC 135 T1, EC 135 T2 EC 135 P2+, EC 135 T2+ EC 135 P1, EC 135 P2	Installation of Geneva Aviation 28-14 VDC Power Converter per GenevaAviation Master Drawing List (MDL) GA203	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Geneva Aviation Master Drawing List (MDL) GA203 Revision N/C datedJuly 2, 2013.- Instructions for Continued Airworthiness ICA203-4, Rev N/C dated July2, 2013.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/01/2015	Active	10052094
10052096	TASS Inc.		FAA STC SA7041NM-D	737-400	Installation of Dual FMS and Dual GPS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Tramco Master Drawing List (MDL) 97-001, Sheets 1, 2 and 3,Revision A,dated 10 February 1997.	None	30/01/2015	Active	10052096
10052105	ASI INNOVATION			ERJ 190-100 LR	Embraer 190 Cabin Modification to 110 Passengers	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASI STC Data List ref. ASI-SDL-0259-02 dated 08.12.2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/02/2015	Active	10052105

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052111	AEROLITE AG	REV. 9		MBB-BK117 D-3M MBB-BK117 D-3 MBB-BK117 D-2 MBB-BK 117 D-2	EMS Equipment Inst. P/N 145-0045739-50X.Original Issue - Installation of modular emergency medical system (EMS)equipment P/N 145-0045739-501 as described in CPR-14-017.Rev. 1 - Follow on certification of the oxygen system as described inCertification Program CPR-15-009.Rev. 2 - Introduces changes to...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): FAR 29.807 Amdt. 30 “Passenger emergencyexits” (CRI D-01 at Issue 2)The requirements for environmental protection and the associatedcertified...	Original Issue) CPR-14-017 rev. n/cRev. 1) CPR-15-009 rev. n/cRev. 2) CPR-15-024 rev. BRev. 3) CPR-17-025 rev. DRev. 4)CPR-17-045 rev. BRev. 5) CPR-18-023 rev. BRev. 6) CPR-19-041 rev. BRev. 7) CPR-19-048 rev. CRev. 8) CPR-21-005 rev. ARev. 9) CPR-24-032 rev. BFor all EMS Equipment configurations:M...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.For the installation of the Major Change in Rev. 9< (>,<...	24/03/2025	Active	10052111
10052125	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST02214NY-D	767-300	Interior Reconfiguration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Delta Engineering Master Data List 0144-05760-2102 RevisionN dated 3March2009	None	02/02/2015	Active	10052125
10052138	GENEVA AVIATION Inc.		FAA STC SR02301SE	BO 105 S BO 105 C BO 105 A	Installation of Geneva Aviation 28-14 VDC Power Converter per GenevaAviation Master Drawing List (MDL) GA203	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Geneva Aviation Master Drawing List (MDL) GA203 Revision N/C datedJuly 2, 2013.- Instructions for Continued Airworthiness ICA203-3, Rev N/C dated July2, 2013.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/02/2015	Active	10052138
10052139	GENEVA AVIATION Inc.		FAA STC SR02301SE	407 206L-1, 206L-3, 206L-4 206A, 206B, 206L	Installation of Geneva Aviation 28-14 VDC Power Converter per GenevaAviation Master Drawing List (MDL) GA203	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Geneva Aviation Master Drawing List (MDL) GA203 Revision N/C datedJuly 2, 2013.- Instructions for Continued Airworthiness ICA203-2, Rev N/C dated July2, 2013.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/02/2015	Active	10052139
10052140	GENEVA AVIATION Inc.		FAA STC SR02301SE	EC 130 B4, EC 130 T2 AS 350 B, AS 350 B1 AS 350 BA, AS 350 D AS 350 B2, AS 350 B3	Installation of Geneva Aviation 28-14 VDC Power Converter per GenevaAviation Master Drawing List (MDL) GA203	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Geneva Aviation Master Drawing List (MDL) GA203 Revision N/C datedJuly 2, 2013.- Instructions for Continued Airworthiness ICA203-1, Rev N/C dated July2, 2013.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/02/2015	Active	10052140
10052141	GENEVA AVIATION Inc.		FAA STC SR02301SE	AS 355 N, AS 355 NP AS 355 F1, AS 355 F2	Installation of Geneva Aviation 28-14 VDC Power Converter per GenevaAviation Master Drawing List (MDL) GA203	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Geneva Aviation Master Drawing List (MDL) GA203 Revision N/C datedJuly 2, 2013.- Instructions for Continued Airworthiness ICA203-1, Rev N/C dated July2, 2013.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/02/2015	Active	10052141

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052142	RUAG AEROSPACE SERVICES GmbH	REV. 1		650	Introduction of TCAS II Change 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List, RUAG Aerospace document No. 0163D-MDL, Revision 0<(>,<)> dated 23 January 2015.-Aircraft Flight Manual Supplement, RUAG Aerospace document No.0163D-AFMS<(>,<)> Revision 0, dated 24 December 2014.or later revisions ofthe above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/02/2015	Active	10052142
10052155	AERODATA AG	REV. 1		B200	Installation AD-AFIS-0116 on King Air B200	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following CS-23 Amdt 3 paragraphs apply:23.1, 23.3(a), 23.25(a)(2), 23.29, 23.251, 23.301(a) and (c), 23.303,23.305, 23.307, 23.337(a) and (b), 23.365(d), 23.571(c), 2...	Installation, Operation and Maintenance according to the Master DrawingList document number MDL-A/ C-857 Rev. 2 dated 3rd February 2015.or later revisions of the above listed documents approved by EASA	- Limited to A/C Serial Number BB-1988 only- The document AMM-1153 Rev.1 Chapter 04 defines additionalAirworthiness Limitations applicable	10/02/2015	Active	10052155
10052170	ASI INNOVATION			550	Certification of P-RNAV function of aircraft equipped with Garmin GNS530AW	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List, ASI Innovation document No. ASI-SDL-0240-01,Revision 0, dated 8 December 2015.-Aircraft Flight Manual Supplement, ASI Innovation document No.ASI-AFM-0240<(>,<)> Revision 0, dated 14 October 2014.or later revisions ofthe above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/02/2015	Active	10052170
10052171	AIRBORNE MAINTENANCE ANDENGINEERING SERVICES, Inc. (AMES)		FAA STC ST02130CH	767-200, 767-300, 767-300F	Installation of dual Honeywell XK516D 400W High Frequency (HF) VoiceRadio Systems:-configuration 1: installation of provisions on aircraft without HFprovisioned or aircraft provisioned for ferry kit-configuration 2: installation of provisions on aircraft with a singleBoeing HF Voice Radio System ins...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):H-01 EWISThe requirements forenvironmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged...	Master Data List RPT-04-07311 rev LInstructions for Continued Airworthiness RPT 04-07315 rev CAFM Supplement 39203AFM01rev IRor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technic...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/02/2015	Active	10052171
10052187	LUFTHANSA TECHNIK AG	REV. 2		A380-861	Activation of On-Board Mobile Telephone	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document - STDD44-14/02M- Compliance Record List - CRL44-14/02M- AFM Supplement - A-00-14/60-AFM- Instructions for Continued Airworthiness - A-00-14/60-ICA- MMEL-S - A-00-14/60-MMELor later revisions of the above listed documents approved by EASACompliance Document APV...	None	08/10/2015	Active	10052187

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052196	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)	REV. 1		1900C AND 1900D	Introduction of TCAS II Version 7.1 on Beechcraft 1900 C and D Series.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCAS 2000 Upgrade:- Installation in accordance with Medavia Service Bulletin refMODE00131R1_SB_TCAS2000 Rev 1, dated 24/08/2015.Operation in accordance with Medavia Flight Manual Supplement refMODE00131R1_FMS_TCAS2000 Rev 1, dated 24/08/2015.Instructions for Continued Airworthiness (ICA) in accordanc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/10/2015	Active	10052196
10052197	TESTORI AERO SUPPLY S.R.L.			737-900ER 737-900 737-800 737-700 737-600	Flight Attendant Seat Cushion Replacement for Boeing 737 NGseries	None	Component Maintenance Manual and IPC TAS-STC-B737NG-FA-CMM-01or later revisions of the above listed documents approved by EASAMaster Document List TAS-STC-B737NG-FA-MDL-01 Rev. 03Master Drawing List TAS-STC-B737NG-FA-MWL-01 Rev. 00	Prior to installation of this design change it must be determined thatthe interrelationship between this change and anyother previouslyinstalled design change will introduce no adverse effect upon theairworthiness of the product.	09/02/2015	Active	10052197
10052215	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	AS 332 L2 AS 332 L1 AS 332 L	Installation of Long Wire Antenna and Activation of KHF-950HF RadioSystem	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CS 29.610 Amdt. 3 equivalent to DGAC-F CS n°2 (Lightning) for the AS332L and L1CS29 Amendment 3CS 29.1, CS 29.251, CS 29.301,CS 29.303, CS 29...	Bournemouth Aviation (Consultants) Rotorcraft Flight ManualSupplementBAC-937FMS01 Revision 1or later revisions of the above listed documents approved by EASABournemouth Aviation (Consultants) Master Data List BAC-937MDL01 Issue 7	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product..	10/02/2015	Active	10052215
10052221	KITCHENER AERO AVIONICS, Ltd.		TCCA STC SH12-61	EC120B	Installation of Garmin G500H Flight Display System and simultaneousreplacing of Gyro Horizon, Directional Gyro, CDI, Airspeed indicator,Altimeter, Vertical Speed Indicator and Turn and Bank Indicator.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FMS 12037-1 Rev. AMDL 12037-1, Rev. Cor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.CP 12037-1, Rev. NCICA 12037-1, Rev. NC	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/02/2015	Active	10052221
10052228	AEROSERVIS, S.R.O.			L 410 UVP-E, -E9, -E20	Introduction of Enhanced Surveillance to existing Mode S transponder MST67A as per document AE153 001P.	The Certification Basis fort the original product as amended by thefollowing additional or alternative airworthiness requirements:FAR 23 § 301, Amdt. 48FAR 23 § 773, Amdt. 45FAR23 § 1303, Amdt. 49FAR 23 § 1309, Amdt. 49FAR 23 § 1321, Amdt. 49FAR 23 § 1325, Amdt. 50FAR 23 § 1331, Amdt. 43FAR 23 §F...	STC AE/153 Master Document List, Doc. No. AE153000X, rev D<(>,<)>dated 10.12.2014L 410 UVP-E Flight Manual Supplement Doc. No. STC AE/153-DLP1<(>,<)>SSR Mode S Enhanced Surveillance (with one AD 32 Air Data Display),initial issue, dated March 20/14L 410 UVP-E9 Flight Manual Supplement Doc. No. STC A...	The installer must determine whether this design change is compatiblewith previously approved modifications.If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.	20/02/2015	Active	10052228
10052233	GROWING ENGINEERING PARTNERS GmbH	REV. 2		A330-300	SAS A330-343 Cabin reconfigurationReplacement of Business, Premium Economy and Economy Class seats,galleys, stowages, IFE and ISPSS. Relocation of mid cabin lavatories,removal of cabin crew rest module.Rev.2: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this...	Aircraft Flight Manual Supplement S.OAED.000300-AFM, rev 00Master Document List S.OAED.000300-MDL, rev 00Instructions for Continued Airworthiness S.OAED.000300-ICA, rev 01or laterrevisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/04/2021	Active	10052233

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052261	AVIONITEC AG			M20C	Equipment Upgrade incl. AFMS Revision for IFR Operation ,,Out: Brittain autopilot system; Bendix/King DME KN-64; Bendix/ King NAVIndicator KI 203; Garmin GNS-430 system In: Bendix/King KN-62A; GarminGNS-430W system; PowerFlarm system ,,	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:FAR23 Amdt 55; 23.301, 561, 1301, 1309, 1321, 1327, 1329, 1351, 1357,1359, 1365, 1381, 1431, 1529, 1541, 1581The requireme...	AFM Supplement GNS 430W No. 4445-011 Rev. 1 of 06.01.2015AFM Supplement PowerFlarm No. 4445-012 Original Issue of 06.01.2015or later revisions of the above listed documents approved by EASA.Master Document List No.4445-017 Rev. 0 of 02.02.2015 ,,Instructions for Continued Airworthiness No. 4445-015...	Limited to S/N 3269 HB-DWCPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effectupon the airworthiness of the product.	13/02/2015	Active	10052261
10052263	JAMCO AMERICA, INC.		FAA STC ST01143SE	737-900ER 737-900 737-800 737-700 737-500 737-400 737-300 737-200	Installation of Flight Deck Security Door	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For applicability of Airplane Flight Manual Supplements refer to FAA STCNo. ST01143SE.or later revisions of the above listed documents approved by EASA.Jamco America, Inc Master Drawing List (MDL) IA-085COAMDL, Revision AZ,dated 01 December 2014.For applicability of ICA per aircraft serial number re...	Installation of this STC replaces the original cockpit doorwith a newsecurity flight deck door and is approved as an Alternate Method ofCompliance (AMOC) to Paragraph A and B of Airworthiness Directive (AD) 89-04-03. Approval of this AMOC is documented in FAA Letter 150S-14-183,dated 15 October 2014...	13/02/2015	Active	10052263
10052268	JET AVIATION FLUGZEUGWART UNG GmbH			650	Certification of P-RNAV capability of aircraft equipped with FlightManagement System Universal UNS-1D	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List, Cessna Düsseldorf document No. 2014-9-16,Revision IR, dated 12 May 2014.- Airplane Flight Manual Supplement, Cessna Düsseldorf document No. 2014-9-8, Revision IR, dated 12 May 2014.or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2015	Active	10052268
10052269	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B300/B300C	Installation of UNIFIS 3000 Flight Inspection System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Scandinavian Avionics Design EngineeringOrder ref 2078097-EO<(>,<)> Issue 1<(>,<)> dated 28.01.2015 and MasterDrawing List ref 2078097-DL<(>,<)> Issue 1<(>,<)> dated 17.03.2014.Operate in accordance with Scandinavian Avionics Design Flight ManualSupplement ref 2078097...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2015	Active	10052269
10052272	STC TWENTY ONE LIMITED		CAA UK RESPONSIBIL ITY	737-900ER 737-900 737-800 737-700 737-600 737-500 737-400 737-300 737-200C 737-200 737-100	Introduction of TCAS Change 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 Amendment 15CS 25.1301; CS 25.1309; CS 25.1322CS 25.1431; CS 25.1581; CS 25.1585The requirements for environmental pr...	STC Twenty One Flight Manual Supplement S21.FMS-0117 Issue 1or later revisions of the above listed documents approved by EASA.All of the documents detailed in STC Twenty One Master Document ListS21.MDL-1225 Issue 2	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2015	Active	10052272

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052273	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			P.180 AVANTI, P.180 AVANTI II	P-RNAV Capability within Universal UNS-1L/1K Flight Management System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement UNS-1L, 2014-14-8, Rev. IRAirplane Flight Manual Supplement UNS-1K, 2014-14-8A, Rev. IRor later revisions of the above listed documents approved by EASA.Engineering Order 2014-14, Rev. BInstallation Procedure 2014-14-1, Rev. A	None	13/02/2015	Active	10052273
10052279	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CL600-2B16	Introduction of a Corporate Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Flight Manual Supplement No. S21.FMS-0092 Issue 1or later revisions of the above listed documents approved by EASA.STC Twenty One Master Document List No. S21.MDL-1069 Issue 1	None	17/02/2015	Active	10052279
10052286	BERINGER AERO	REV. 5		EA 300/SC EA 300/LT, EA 300/S EA 300/L, EA 300/LC EA 300, EA 300/200	Replacement of wheel and brake systemRev.1 - Update with longer axle boltsRev.2 - Update with different hydraulic fittingRev.3 - Test Report ImprovementRev.4 - Update with new wheel part numberRev.5 - Update with new servicing instructionswithin ICA document andaddition of SensAIR device as an opti...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification file: DM-STC-012 rev 06 dated 11 Mar. 2022;Installation and Instructions for Continued Airworthiness: ICA-STC-012rev 04 dated 19 Oct. 2021;or later revisions of the above listed documents approved by EASA.	The approval holder shall fulfill the obligations of Part 21, Point21.A.109 or 21.A.451(b) (as applicable).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introd...	18/03/2022	Active	10052286
10052312	DART AEROSPACE Ltd.		SH14-44	R 66	D066-1004 Cargo Hook Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS-D066-1004 Revision B, dated 12Feb 2015or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Installation Instructions IIN-D066-1004 Revision B, dated June 20, 2014Inst...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/02/2015	Active	10052312
10052319	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 3		A330-201/-202/-203	Cabin Interior Reconfiguration QANTAS Airways Aircraft.Rev.3:	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-3327-002 Incorporationof ILD in DynamicSeats.The following paragraph(s) at a later amendment: CS 25.791(d)(e) at Amdt21.The requirements for e...	Certification Summary, Northwest Aerospace Technologies, Inc. documentN0453-D91, Revision N, dated 2 July 2025;Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document N0453-D70, Revision C, dated 28 February2020;or later revisions of the above listed document(s) appr...	Monitors and components of the IFE System, including In-Seat PowerSupply System are treated as pure items of mass underthis approval. Electrical connection to aircraft requires further design approvalincluding full equipment qualification.Prior to installation of this change/ repair it must be deter...	08/07/2025	Active	10052319
10052320	ROSEMOUNT AEROSPACE, Inc.	REV. 1	FAA ST03357CH	737-600/-700/-800/-900/-900ER	Electronic Flight Bag installation:- Configuration A - "Class 3" installed EFB system-Configuration B - "Class 2" EFB host platform ("provisions")	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master data list D06415967 Rev BW<(>&<)>B report D06419417 rev BConfiguration A: AFM Supplement D06419016 Rev A, Instructions forcontinued airworthiness D06423328 rev CConfiguration B: AFM Supplement D06419438 Rev A, Instructions forcontinued airworthiness D06419460 rev Cor later revisions of the ab...	This airworthiness approval does not replace the operational assessmentfor the use of the EFB system<(>,<)>and- for configuration A: Class 3 EFB-- the USB ports on the EFB displayare not approved for use duringflight-- wireless functionali ty is not approved for use during flight-- flight crew is n...	24/02/2015	Active	10052320

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052356	MARSHALL OF CAMBRIDGE AEROSPACELIMITED		CAA UK RESPONSIBILITY	A320-231/-232/-233 A320-211/-212/-214	A320 LiveTV Ka Band Wi-Fi Connectivity Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MA Supplement No. AFMS/ A320(2022)/14/0268 Rev. 1 to Airbus A320-200Series Aircraft Airplane Flight Manualor later revisions of the above listed documents approved by EASAAll documents referenced on Certificate of Design MA2022,CD/A320(2022)/ 15/0062 Issue 1 dated 17 February 2015 and TypeModification...	Must be installed in conjunction with EASA STC 10050344 andinaccordance with the limitations of that STCPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduc...	19/02/2015	Active	10052356
10052358	ALAMO ENGINEERING GmbH	REV. 2		MYSTERE FALCON 50 (MF50) MF 50EX	Interior Modification and In-Flight Entertainment System upgrade.Revision 2: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Master Document List, 328 Design GmbH document No. MDL043Z001, RevisionA, dated 19 February 2015;-Airplane Flight Manual Supplement, 328 Design GmbH document No.AFMS020C043Z001, Revision A, dated 2 February 2015;or later revisions of the above listed document(s) approved/ acceptedunder the EASA syst...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10052358
10052365	LUFTHANSA TECHNIK AG	REV. 3		ERJ 170-200 STD ERJ 170-200 LR ERJ 170-100 STD ERJ 170-100 LR	Installation of Photoluminescent Emergency Floor Path Marking System.This approval constitutes the initial Operational Suitability Data MMELapproval for EASA STC 10052365 Rev.1.	The Certification Basis for the original product as amendment by thefollowing additional or alternative airworthiness requirements:All applicable paragraphs according to CS 25 at Amendment 15 (elect tocomply).The requirements for environmental protection and the associatedcertified noise and/ or emi...	- AFMS ref. A-00-14/35-AFM issue 01, revision 00, dated 15 December 2014;-Embraer 170/175/190/195 MMEL Supplement Doc.N°A-00-14/39-MMELRevision 00 dated June 01, 2015 ;or later revisions of the above listed documents approved by EASA.ICAref. A-00-14/35-ICA issue 01, revision 02, dated 06 February...	The above referenced MMEL supplement can only be used in conjunctionwith the EASA MMEL for the Embraer 170/175 aircraftPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair...	22/06/2016	Active	10052365
10052366	LUFTHANSA TECHNIK AG	REV. 3		ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 SR ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ	Installation of Photoluminescent Emergency Floor Path Marking System.This approval constitutes the initial Operational Suitability Data MMELapproval for EASA STC 10052366 Rev.1.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:All applicable paragraphs according to CS 25 at Amendment 15 (elect tocomply).The requirements for environmental protection and the associatedcertified noise and/ or emiss...	- AFMS ref. A-00-14/36-AFM issue 01, revision 00, dated 15 December 2014;-Embraer 170/175/190/195 MMEL Supplement Doc.N° A-00-14/39-MMELRevision 00 dated June 01, 2015 ;or laterrevisions of the above listed documents approved by EASA.ICA ref. A-00-14/36-ICA issue 01, revision 02, dated 06 Februar...	The above referenced MMEL supplement can only be used in conjunctionwith the EASA MMEL for the Embraer 190/195 aircraft.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repai...	08/03/2016	Active	10052366
10052371	ICELANDAIR DESIGN ORGANISATION		FAA STC ST03340CH	737-800	Installation of an AVIO Business Class Interior (ST03340CH)-Iceland ,,Validation of an STC for a new Interior and IFESystem as defined inCertification Plan GR0050- CPL, Rev. 1,dated 02.05.2013 ,,	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.-Master Data List, Doc. No. GR0051-MDL, Rev. E, dated 05.12.2013	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/02/2015	Active	10052371

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052374	AEROLITE AG	REV. 2		EC 135 T3 (CPDS) EC135 T3	Installation of Emergency Medical Services (EMS) Equipment P/ N135-0049898-501 in accordance with Master Document List MDL-14-039Initial:This STC covers the installation of a modular EMS Equipment into thecabin of an Airbus Helicopter Deutschland GmbH EC135 rotorcraft. Theequipment features the diffe...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Rotorcraft Flight Manual Supplement FMS-135-0049898-501 Revision C- Master Document List MDL-14-039 Revision F- Instructions for Continued Airworthiness are provided with OperationManual OPM-135-0049898-501 Revision For later revisions of the above listed document(s) approved/ acceptedunder the EAS...	Applicable to helicopters with CPDS and Helionix cockpit variant.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repairwill introduce no adverseeffect upon the airworthiness of th...	26/04/2024	Active	10052374
10052381	JET AVIATION AG	REV. 3		737-800	Direct View Camera System InstallationInstallation of an ADAerospace Direct View Camera System in the cabinas defined in the documents below: - Engineering Order, Doc. No.5312-062, Rev. B, dated 19.05.2014Rev. 3: Editorial correction	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFMS, Doc. No. 5312-071, Rev. A, dated 20.06.2014or laterrevisions of the above listed documents approved by EASA.- Master Data List, Doc. No. 5312-049, Rev. C, dated 16.02.2015- Engineering Order, Doc. No. 5312-062, Rev. B, dated 19.05.2014- ICA, Doc. No. 5312-085, Rev. A, dated 19.05.2014- Cabi...	The Direct View Camera System shall not to be used as a primary meansfor the cabin crew to check that all passengers have left the aircraftin case of an emergency evacuation.Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any...	17/10/2017	Active	10052381
10052393	SCANDINAVIAN AVIONICS DESIGN ApS			DHC-8-401, DHC-8-402 DHC-8-201, DHC-8-202	Provisions for dual portable EFB	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:All at CS 25 Amdt. 4 (except § 25.341 at JAR 25 Change 14)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	Installation must be in accordance with Engineering Order Doc. 2090987-EO, Issue 1Operation must be in accordance with AFM Supplement Doc. 2090987-AM A,Issue 3.Continued Airworthiness must be in accordance with ICA Doc. 2090987-CA,Issue 2 and Airplane Maintenance Manual Supplement DOC: 2090987, Issue...	This STC does not constitute an Operational Approval. IndividualOperational Approvals, including the COTS equipment suitability, must beissued by the competent NAA.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprev...	23/02/2015	Active	10052393
10052395	SABENA TECHNICS BGC			EC 225 LP	ADS-B OUT in accordance with Master Data List 2043-01-A-2103.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29. Amd 3:§29.1/.27/.561/.771/.777/.1301/.1309/.1327/.1351/.1353/.1357/.1431/.1525/.1529/.1581.The requirements for environmental protection and the associatedcertified...	Aeroconseil Rotorcraft Flight Manual Supplement (RFMS) No 2043-01-A-2301Rev.01.or later revisions of the above listed RFM revisions approved by EASA.Certification Plan 2043-01-A-2101 - Rev 00.Master Data List (MDL) 2043-01-A-2103.Instruction for Continued Airworthiness (ICA) 2043-01-A-2211.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/02/2015	Active	10052395
10052409	JET AVIATION AG, BASEL			737-800	VIP Interior - two kinds of Operation ,,The change is intended to establish the conditions under which the cabincan be changed between "private" and "commercial" configuration basedon:- Conversion Manual, Doc. No. JBSL-M-00129DSS-01, Issue1, dated16.02.2015	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s):CRI D-01 Interior DoorsCRI D-05 Firm HandholdThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	AFMS, Doc. No. JBSL-M-00129AFR-01, Rev. 1, dated 18.02.2015or later revisions of the above listed documents approved byEASA.- MDL, Doc. No. JBSL-M-00129MDL-01, issue 2, dated 20.02.2015- Conversion Manual, Doc. No. JBSL-M-00129DSS-01, Issue 1, dated16.02.2015	Maximum Approved Passenger Seating Capacity (MAPSC):- 32 passenger for private operation- 19 passenger for commercial operationPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ o...	25/02/2015	Active	10052409

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052416	HELI-ONE (NORWAY) AS			A332L, A332L1	CVFDR installation in accordance with Modification AHSE-64750.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-29 Amendment 3.:29.1/.29/.45/.251/.301/.303/.305/.307/.321/.337/.601/.603/.605/.607/.609/.610/.613/.625/.771/.773/.1301...	- AHSE-64751 Revision C, Dated 18 February 2015, CertificationProgramme.- H1No.7.237 Revision -, Dated 01July 2014, Complementary Flight ManualSupplement.- AHSE-64779 Revision -, Dated 29 June 2014, Continued AirworthinessSupplement.- AHSE-64755 Revision -, Dated 06 June 2014, Embodiment Instructi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/02/2015	Active	10052416
10052424	E A D AEROSPACE AIRWORTHINESS	REV. 4		A340-311,-312,-313 A340-211,-212,-213	TPED Immunity Testing.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List, EAD Aerospace document No. 01451-EAS-C-MDL,Revision C, dated 8 November 2017;- Instructions for Continued Airworthiness, EAD Aerospace document No. 01451-EAS-C-ICA-02, Revision A, dated 8 November 2017;- Aircraft Flight Manual Supplement, EAD Aerospace document No.01451-EAS-C-A...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/01/2018	Active	10052424
10052427	VIH AEROSPACE Inc.		TCCA SH09-39 ISSUE 2	S-92A	SAR Equipment Installation - Nightsun and FLIR	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	'EASA Approved'VIH Aerospace Inc Rotorcraft Flight Manual Supplement, VS92-0726-NS-FMS,Rev 2, Spectrolab Nightsun II XPSearchlight SystemVIH Aerospace Inc Rotorcraft Flight Manual Supplement,VS92-0726-FLIR-FMS, Rev 4, FLIR U8500XR Airborne Imaging System & SAROperator Console.or later revisions ofa...	Configurations 1 (Nightsun Installation) and 2 (FLIR Installation) maybe installed independently or concurrently with each other.Compatibility of both of these configurations together has beendemonstrated.Prior to installation of this design change it must be determined thatthe interrelationship bet...	05/03/2015	Active	10052427
10052435	ASI INNOVATION			ATR 42-320	SATCOM System installation on ATR 42-320This modification installs a SATCOM system composed of the followingitems : SATCOM Transceiver, Mission Management Unit (MMU), ConfigurationSIM module, Diagnostic port, Iridium/GPS antenna, indicators lights, andthe associated wiring harness.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 Amdt 4 : see Compliance Check-List document, ref :ASI-CCL-0278-03, for the applicable requirementsThe requirements fo...	STC Data List, ref : ASI-SDL-0278-02, dated 25 February 2015Aircraft Flight Manual Supplement, ref : ASI-AFM-0278-01, dated 26January 2015Instructions for Continued Airworthiness,ref : ASI-MPS-0278-00, dated17 November 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2015	Active	10052435
10052436	LUFTHANSA TECHNIK AG			A380-841	New Premium Economy Class for A380-800In the main cabin of the main floor on the aircraft, the change consistof the removal of 10 per cent of the Economy Class Seats between door 2and door 3 and the installation of new developed Premium Economy Seatsinstead (with Panasonic IFE). The new seating will...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD25-13/38M issue1 rev 0- ICA, ref A-00-14/64-ICA, Issue 2 rev 0- ComplianceRecord List CRL25-13/38M iss 1 rev 1or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with STC 10048634 - Installation of 1000Series photo luminescent floor path marking), together with itsassociated post STC minor Changes references CRAS 00128564 (DLH A380 - Installation of "GuideU" FPM S...	27/02/2015	Active	10052436

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052441	AEROTEC & CONCEPT			C90GTI	PRNAV LPV Activation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-23 Amdt 3 for the paragraphs:-,,23.1301-,,23.1309-,, 23.1321-,,23.1501-,,23.1541-,, 23.1581The requirements for environmen...	Modification according to the data reported in the Certification Plan / Presentation Dossier 14191PCDP Issue 2 dated 02/02/2015Operation according to Aircraft Flight Manual Supplement AE14191AFMSIssue 0 dated 20/10/2014.or later revisions of the above listed documents approved by EASA.	- Limited to aircraft equipped with Rockwell-Collins Pro Line 21Avionics Suite- APV-Baro-VNAV and SBAS/GNSS-VNAV approaches prohibitedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change...	27/02/2015	Active	10052441
10052442	LUFTHANSA TECHNIK AG			A380-841	VC installation on A380:New Economy Class seats (Recaro CL3510) installed in the aft section ofthe upper deck aft of door 3	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Supplemental Type Definition Document STDD25-14/28M issue 1rev 0ICA, ref A-00-14/64-ICA, Issue 2 rev 0Compliance Record List CRL25-4/28M issue 1 rev 1Statement of Compliance 3559rev 1Weight and Balance Manual WB-08-31/14 rev 8or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	27/02/2015	Active	10052442
10052444	EMTEQ CANADA Ltd.		TCCA C-LSA14-206/D	DHC-8-401, DHC-8-402	Installation of Provisions for Passenger Life Vests	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with EMTEQ Modification Data Summary J954000, Revision N/C.or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2015	Active	10052444
10052449	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	DC.9-81/-82/-83/-87 & MD-88	TCAS Change 7.1 on Boeing DC9/MD80 Series/Honeywell TPA-100B TCAS IItraffic computerinstalled in place of the existing Honeywell TPA-81A computer in thesame location. The originaltray remains. TPA-100B is fully compliant with ETSO-119c including bothRTCA/ DO-185B forTCAS II change 7.1	The Certification Basis (CB) for the original product remains applicableto thiscertificate/ approval. The requirements for environmental protection andtheassociated certified noiseand/or emissions levels of the originalproduct areunchangedand remain applicable to this certificate/ approval	H4A1759 Issue 2 Modification Summary and Declaration of Compliance;H4ACCL618Issue 1 Compliance Check List; H4ACP091 Issue 2 Certification Plan;H4ADR902 Issue 1Instruction for Continued Airworthiness; H4AFMS037 Rev. IR AirplaneFlight ManualSupplementor later revisions of the above listed documents ap...	See H4AFMS037 Rev. IR Airplane Flight Manual Supplement	09/06/2015	Active	10052449
10052458	DOA21 LIMITED	REV. 1		A320-214	Rework to VIP interiorRev. 1: Transfer of STC holder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):Compliance with the following Certification Review Items applied to EASASupplemental Type Certificate EASA.A.S.10035344 is unaffected bym...	STC TWENTY ONE FLIGHT MANUAL SUPPLEMENT No. S21.FMS-0119 ISSUE 2or later revisions of the above listed documents approved by EASASTC TWENTY ONE MASTER DOCUMENT LIST No. S21.MDL-1206 ISSUE 3	1. EASA STC No.10035344 is a prerequisite for this STC.2.The new airworthiness limitations for the type of operation "PrivateCategory" only, the maximum passenger capacity of 27, and for the newlarge video monitor to be in the retracted (lowered) position for taxi,take-off and landing are to be intr...	24/10/2023	Active	10052458
10052471	AIRGLAS, Inc.		FAA STC SA02360AK	2. A-1C-200 2. A-1, A-1A, A-1B, 1-1C-180 1. 180J, 180K 1. 180E, 180F, 180G, 180H 1. 180, 180A, 180B, 180C, 180D	Fabrication and Installation of Airglas, Inc, Model GLH3000hydraulically retractable wheel skis.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Airglas, Inc, Descriptive Data List NoGLH3000, Revision G, dated September 20, 2013. Operate in accordance with Airglas, Inc, FAA Approved Airplane FlightManual Supplement (AFMS) as defined in in attached AML List.Instructions for Continued Airworthiness in accordanc...	Tyre size must be 8.50 x 6, Type III onlyPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	03/03/2015	Active	10052471

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052479	DISCOVERY AIR TECHNICAL SERVICES		TCCA SA 12-62	EMB-500	RH Forward Galley Drawer Insert	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	To be installed in accordance with Master Drawing List MDL11003 RevisionAFor A/C equipped with RH FWD Embraer Galley configuration P/ N500-29893-801·,,To be operated in accordance with Flight Manual Supplement FMS11003-01 Revision NC·,,To be maintained in accordance with Instructions for ContinuedAir...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/03/2015	Active	10052479
10052484	3S CERTIFICATION, LLC		FAA STC ST03108CH	A340-541/-642 A340-311/-312/-313 A340-211/-212/-213	Certification of Compatibility with Cellular and Wireless DataTechnologiesRefer also to Envoy Aerospace Certification Plan, DocumentE13047-2330-C001 rev -	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.1309(a) at CS amendment 225.1529 at CS amendment 2The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origin...	-MASTER DATA LIST : DC104-9054-00 rev H (Including the references to the documents Aircraft Equipment List RefDC370-9054-01 rev G, and ref DC370-9054-02 rev G)-Certification Plan, Document E13047-2330-C001 rev --FAA Letter, FAA Statement ofCompliance, dated on 26th Feb 2015or later revisions of thea...	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane installed base station using the cellularand/or wireless technologies is concurr...	04/03/2015	Active	10052484
10052493	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04288AT-D	G280	G280 FANS-1/A STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan G250-GER-0013, Rev -, Dated 6th of June 2012.AFMS G280-GER-0254, Rev 3rd of October 2015.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation P...	None	05/03/2015	Active	10052493
10052494	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04275AT-D	G280	Installation of an International Communications Group(ICG) SATCOM Systemand Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan GA41103C001, Rev A, Dated 11th of November 2014.AFMS GA44103M001, Rev A, Dated 25th of March 2014.orlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Impleme...	WLAN capability of the portable terminals installed is not covered bythis approval.	05/03/2015	Active	10052494
10052495	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04274AT-D	GULFSTREAM G280	Installation of a second Integrated Flight Information System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan GA41120C001, Rev G, Dated 30th of April 2014AFMS GA41120M001, Dated 12th of October 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Pr...	None	02/04/2015	Active	10052495

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052496	GULFSTREAM AEROSPACE Corp.		FAA STC ST04271AT-D	G280	Installation of a Jumpseat in G280.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan GA42132C001, Rev F, Dated 4th of January2014.AFMS GA42132M001<(>,<)> Rev A, Dated 3rd of November 2012.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical I...	None	05/03/2015	Active	10052496
10052498	GULFSTREAM AEROSPACE Corp.	REV. 1	FAA ST04266AT-D	GULFSTREAM G280 G280	Installation of an Executive Passenger Cabin InteriorRev. 1: New part numbers for life rafts.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): FAA special condition 25-664-SC.The requirements for environmental protection and the associatedcertified noise and/ or emissions leve...	Index List GA422048000, Rev. BTAFMS GA41204M000, Rev. RInstructions for Continued Airworthiness GA42204A000, Rev. NOr later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	The Cabin Server Wireless LAN (WLAN) system is intended to provideinternet connection and email services to the airplane's cabin andallows secondary control of some non-essential,non-required cabinsystems and equipment using portable electronic devices (PEDs). Anyother intended function of this equ...	06/02/2023	Active	10052498
10052502	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CL-600-2B16 (601-3A)	TCAS II System upgrade to Change 7.1 (Collins)The aircraft existing TCAS-94, TTR-921 TCAS processor with Collins PIN:822-1293-002 with Change 7.0 will be upgraded in accordance with CollinsSB to Change 7.1 with new part number PIN: 822-1293-033	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement Doc. No. AC5342-071 Revision IRor later revisions of the above listed documents approved by EASA.Master Data List Doc. Na. AC5342-049 Revision IRInstructions for Continued Airworthiness Doc. No. AC5342-085Revision IR	Limited to S/N 5042 HB-IKSPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effectupon the airworthiness of the product.	05/03/2015	Active	10052502
10052503	LUFTHANSA TECHNIK AG			A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of Water Vapour Sensor System II	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Definition Document STDD00-14/19M Issue 2Rev. 0,dated 05/03/2015Compliance Record List CRL00-14/19M Issue 2 Rev.0, dated 05/03/2015Instruction for Continued Airworthiness A-00-14/48-ICA Issue 2 Rev. 0,dated 16/02/2015or later revisions of the above listed documents approved by EAS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/03/2015	Active	10052503
10052509	AEROTEC GROUP S.A.S.transferred to 309218 with 707360			EC 135 T2+	Night Vision Goggles (NVG) Compatible Lighting SystemDescription: This STC adds interior and exterior lighting to thehelicopter compatible with the use of the Night Vision Goggles(NVG).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27/29 Amendment 3: 27.01/27.29/27.141/27.561/ 27.603/27.607/27.609/27.610/27.611/27.771/27.773/27.779/29.803/29.811/29.812/27.853/27.1301/27.1305/27.1309/29.1309(b)(2)...	-Flight Manual Supplement "ATG-MV-EC135-01_04", dated 09/02/2015.or later revisions of the above listed documents approved by EASA-Design Definition File "ATG-DD-EC135-01_02",dated 02/03/2015-User's Manual "ATG-DTU-005-001_R03",dated 02/03/2015.-Installation Manual "ATG-DTI-EC135-01_02",dated 02/03/...	Applicable to helicopter S/N 0285This STC applies only to the S/N listed above. This rotorcraft employsNight Vision Imaging System lighting, commonly named NVIS lighting, thathas been certified to ensure the aircraft is compatible with nightvision goggles (NVG). For this reason modifications that ad...	06/03/2015	Active	10052509

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052532	LUFTHANSA TECHNIK AG			747-8	Use of WiFi in the Cockpit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Description of Change APR01-46 rev. 0STDD46-14/14M Iss 1 Rev 00Instructions for continued airworthiness supplements:- A-00-12/23-ICA Iss 02 Rev 01- A-00-12/28-ICA Iss 02 Rev 01- A-00-12/29-ICA Iss 03 Rev 01- A-00-14/45-ICA Iss 01 Rev 01or later revisions of the above listed documents approved by EAS...	None	09/03/2015	Active	10052532
10052533	VIH AEROSPACE Inc.		TCCA SH06-40 ISSUE 1	S-61N	Installation of Diamond-J-61000-(103,104) Power Turbine InletTemperature T5 Indicators (TIT)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CAR 529 Issue 1:529.29/529.561/569.601/529.1301/529.1309/529.1321/529.1351/529.1353/529.1357/529.1359/529.1381/529.1529/52...	- Flight Manual Supplement V61-0614-FMS, Revision 02, datedOctober 3,2007 or later revisions of the above listed documents approved by EASAin accordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.- VIH Aerospace, Inc. Master Drawing List, 250-50149-00, Revision 02...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/03/2015	Active	10052533
10052535	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	EC 135 T2+	Surveillance Role Equipment installation and NVIS compatible lightingsystem as per BOND/MOD/103.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS27 Amdt 3 dated 11/12/2012:27.1, 27.21, 27.251, 27.301, 27.303, 27.305, 27.307, 27.321, 27.337,27.341, 27.351, 27.561, 2...	Flight Manual Supplement FMS/103-002 Issue 4 dated 5 March 2015or later revisions of the above listed documents approved by EASA.Design report DR/ 103-001 Issue 5 dated 5 March 2015Compliance Checklist for NVIS CCL/ 103-03 Issue 2 dated 3 March 2015Compliance Checklist for NVIS CCL/ 103-04 Issue 3 dat...	Rotorcraft modified by this STC employs Night Vision Imaging Systemlighting, commonly named NVIS lighting, which has been certified toensure the aircraft is compatible with Night Vision Goggles (NVG). Forthis reason, any deviation from thecockpit or cabin configurationspecified in this STC may affe...	10/03/2015	Active	10052535
10052539	DASSAULT AIRCRAFT SERVICES (DAS)	REV. 3	FAA ST02973NY	F900EX, MF900 (C VERSION)	Validation of FAA STC ST02973NY.Installation of ADS-B Out System on aircraft equipped with HoneywellPrimus 2000 avionics system.Revision 1: Installation of ADS-B Out System compliant with DO-260B.Revision 2: Correction of ICA revision.Revision 3: Correction of ICA reference	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.305 (a) and (b),CS 25.307 (a), CS 25.321 (a), CS 25.625(a), CS 25.1307 (c) and CS25.1581(a)(2) at amendment 15.CS 2...	- AFMS ref. F9XW-D0013-150 initial revision, dated 9 October 2014 (Config.1-DO-260A);- AFMS ref. F9XW-D0046-150 initial revision, dated 18 June 2015(Config. 2-DO-260B);- Instructionfor Continued Airworthiness F9XW-D0013-155 Rev. E, dated19 May 2017;- STC Master Data List ref. F9XW-D0013-005 revision2...	The installation of the EASA STC 10051492 (validation of FAA STCST02967NY) for the installation of Honeywell GPS Landing System SensorUnit (GLSSU) is a pre-requisite for this design change.Prior to installation of this design change it must be determined thatthe interrelationship between this design...	31/07/2017	Active	10052539
10052545	AIRBUS S.A.S.	REV. 1		A319-115	Airbus Corporate Jet Modification CJ1486 VIP Project "Highland"	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI E-21 - Isolated CompartmentsCRI D-0310 - Use of GlassCRI D-0314-000 - Shower InstallationCRI F-0307-001 - Lithium Ion Battery InstallationsEquival...	Modification Approval Sheet CJ1486, Issue 2, dated 10/03/2015Airplane Flight Manual - AFM Supplement FM-S MOD CJ1486, dated01/02/2015Maintenance Planning Document - MPD SupplementMPD-S MOD CJ1486, dated01/02/2015or later revisions of the above listed documents approved by EASA.	This approval is limited to MSN 5445Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	10/03/2015	Active	10052545

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052547	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04170AT	A320-214	Installation and activation of an EFE System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, TIMCO document No. 13T310L001 Revision IR, dated 6November 2014.- Instructions for Continued Airworthiness, TIMCO document No. 13T310L009<(>,<)> Revision A, dated 9 December 2014.or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/03/2015	Active	10052547
10052548	MARSHALL AVIATION SERVICES LIMITED		CAA UK RESPONSIBILITY	B200CGT, B300, B300C. B200, B200C, B200GT,	Introduction of Rockwell Collins TCAS-4000 (TTR-4000) with Version 7.1software as an update to an existing TCAS-4000 with Change 7.0 software,in accordance with Marshall AerospaceServices Ltd Modification NoSC0530A.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification ref SC0530A Issue 1 dated 05 March 2015.Service Bulletin ref SB.34-032 Rev -Marshall Aerospace Services Ltd Flight Manual Supplements:-Supplement 1, Issue 1 to AFM 101-590010-425 for B200/ B200C.Supplement 1, Issue 1 to AFM 101-590010-479 for B200/ B200C.Supplement 2, Issue 1 to AFM 101-5...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/03/2015	Active	10052548
10052551	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA ST02524LA	SEE APPROVED MODEL LIST	Upgrade of ACSS ACAS II Version 7.0 to incorporate FAA AD 2012-02-08(various aircraft models are included)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA AML List or later revisions of the above listed documents approvedby EASA in accordance with EASA ED Decision 2004/04/CF (or subsequentrevisions of this decision) and/ or theTechnical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/03/2015	Active	10052551
10052555	PMV ENGINEERING			767-300F, 767-400ER 767-200, 767-300	TCAS 7.1 upgrade on B767	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List AVI-00750-MDL-R03 dated 5 Mar 2015- Aeroplane Flight Manual Supplements as per AVI-00750-AFMS-R01 dated9.Feb 2015- Instructions for Continued Airworthiness as per AVI-00750-ICA-R01dated 9.Feb 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/03/2015	Active	10052555
10052558	E4C TECHNOLOGIES, L.L.C.		FAA STC ST02521LA	BOEING 767-300	Installation of seat tracks at LBL and RBL 33.0	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Master Data List MDL2138-28207-10 rev. Cor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)"and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	11/03/2015	Active	10052558

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052561	KNISLEY WELDING, Inc.		FAA STC SE5009NM	TSIO-520-R TSIO-520-M TSIO-520-H TSIO-520-G TSIO-520-C	Exhaust System ModificationInstallation of a modified exhaust system in accordance with KnisleyWeldIng, Inc., Modified Master List (MMDL) 1 Revision G, dated May 19,1993, or later FAA approved revision.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions M-2-1, Rev. B, dated March 6, 1992or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement	Approval of this change in type design is limited to enginesspecifically identified above, and does not constitute approval for installation on an aircraft. A separate approval for installation on each aircraft must be obtained.Prior to installation of this design change it must be determined thatt...	11/03/2015	Active	10052561
10052563	S-TEC CORPORATION	REV. 1	FAA STC SA09135AC-D	CESSNA FR172J, FR172K	Installation of S-TEC system 55/55X Two Axis Automatic flight guidancesystem, model ST-612, according to bulletin N. 712rev.2 dated28-Feb-2001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	To be installed according to S-TEC Master Drawing List N. 92827 rev. Bdated 28-Feb-2001(14V system);To be operated in accordance with FAA/DAS approved S-TEC AFM-S P/N891223 rev.1 dated 28-Feb-2001;To be maintained i.a.w. Instruction for continued Airworthiness 81328rev.2or later revisions of the abo...	As per AFMSPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	11/03/2015	Active	10052563
10052565	FLYING COLOURS CORP.		TCCA STC C-LSA15-001/D ISSUE 1	BOMBARDIER BD-700-1A11	Installation stone wash flooring in galley and lavatories	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/approval	TRANSPORT CANADA STC NO. C-LSA15-001/D ISSUE 1 DATED 12 JANUARY2015-03-11EMT EQ Canada Ltd. Modification Data Summary J931000 Revision N/C	RESTRICTED TO ASN 9581	12/03/2015	Active	10052565
10052568	PMV ENGINEERING			737-900ER 737-600, 737-700, 737-800 737-300, 737-400, 737-500 737-100, 737-200, 737-200C	TCAS 7.1 upgrade on B737	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List AVI-00820-MDL-R01 dated 5 Mar 2015-Aeroplane Flight Manual Supplements as per AVI-00820-AFMS-R00 dated6.Feb 2015-Instructions for Continued Airworthiness as per AVI-00820-ICA-R00 dated6.Feb 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/03/2015	Active	10052568
10052580	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02876CH	757-300 757-200PF 757-200	Installation of Vacuum Toilet Assembly Retrofit Kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, B/E Aerospace document No. MDL4100390-003, Revision E,dated 31 October 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/03/2015	Active	10052580
10052589	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	B3300, B300C	TCAS 7.0 Upgrade to TCAS 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS23 Amendment 3CS 23.1, CS 23.1301, CS 23.1309, CS 23.1311, CS23.1322, CS 23.1431, CS 23.1525, CS 23.1529, CS 23.1581, CS...	Bournemouth Aviation (Consultants) Master Data List BAC-944MDL01 Issue 3	This change is limited to aircraft with ACAS II Change 7.0 installed andcovered by Beechcraft POH No 130-590031-245 at Revision A4 or later.Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designa...	16/03/2015	Active	10052589

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052597	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	A321-231	ISPS for First and Business Class Seats	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 5CS 25.1701<(>,<)> CS 25.1703<(>,<)>CS 25.1705<(>,<)> CS 25.1707<(>,<)>CS 25.1709<(>,<)> CS 25.1711<(>,<)>CS 25.1713<(>,<)> CS 25.1715<(>,<)>CS 25.1717<(>,...	The documents and drawings at the issue status detailed in H4 AerospaceModification Summary Sheet and Declaration of Compliance formodification H4A1731 issue 3	Applicable to aircraft MSN1004 only	16/03/2015	Active	10052597
10052601	AEROTEC & CONCEPT			A321-211/-212/-213/-231/-232 A320-231/-232/-233 A320-211/-212/-214/-215/-216	Installation of Dual Iridium/GPS Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, Aerotec document No. AE14262MDL, Revision 0, dated 16February 2015-Instruction for Continued Airworthiness, Aerotec document No.AE14262ICA<(>,<)> Revision 0, dated 12 February 2015or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/03/2015	Active	10052601
10052608	IKHANA GROUP, LLC	REV. 1	FAA STC SA02380LA	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Re-Life of the Viking Air Limited Model DHC-6 Series 100, 200 and 300fuselage, horizontal stabiliser and vertical stabiliser.Rev. 1: Name Change from "Ikhana Group Inc." to “Ikhana Group LLC".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR-23Amdt. 0: 23.303, 23.307(a), 23.601, 23.609Amdt. 7: 23.619, 23.625Amdt. 21: 23.29Amdt. 23: 23.603, 23.605(a), 23.607Amdt. 26:.23.1529Amdt. 34: 23.1Amdt. 45: 23.305, 2...	Master Data List Report ER218-2101, Rev. B, FAA approved November 4,2014Drawing List Report ER218-2102, Rev. G, FAA approved May 23, 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/or t...	a) For approved replacement parts for fuselage, horizontal stabilizerand vertical stabilizer refer to FAA STC SA02380LA.b) Approval of this modification applies to the above notedmodelairplane series only. This approval should not be extended to otherspecific airplanes of this model series on which...	18/06/2021	Active	10052608
10052614	AEROTEC & CONCEPT			AIRBUS A330-300, A330-200	Dual Iridium / GPS Antenna InstallationDual Iridium / GPS Antenna Installation on the TOP FWD fuselage ofA330-200 and A330-300.Electrical wiring and coaxial cable installation arenot treated in thisapproval.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Master Data List ref AE14221MDL rev 1ICA ref AE14221ICA rev1or later revisions of the above listed documents approved by EASA.	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product2) Refer to ICA ref AE14221ICA rev 1 (or later...	17/03/2015	Active	10052614
10052619	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		A330-300	Cabin Interior Reconfiguration QANTAS Airways A330-300 AircraftCabin Interior Reconfiguration as per Certification Summary N0454-D90Rev - & Certification plan N0454-D01 Rev B.Revision 1 is an administrative re-issuance to note compatibilitybetween the Airbus SB and EASA STC 10052619 installations.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Summary, ref : N0454-D90 rev KMaster Drawing List, ref : N0454-D10 rev ABInstruction for Continued Airworthiness, ref : N0454-D70 rev C;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	1) Prior to installation of this change/repair it must be determinedthat the interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of theproduct.2) Monitors and components of the IFE System, includ...	16/04/2024	Active	10052619
10052620	ROCKWELL COLLINS, Inc.		FAA ST00748LA-D	737-700, 737-800, 737-900	Avionics LRU Removal and Replacement Boeing 737-700/-800/-900 Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:FAR 25 Amendment Original - FAR 25.331; FAR 25.341; FAR 25.351; FAR25.601; FAR 25.609; FAR 25.1301; FAR 25.1357; FAR 25.138...	Rockwell Collins Master Drawing List 12120 Revision J	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/03/2015	Active	10052620

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052623	PMV ENGINEERING			757-200, 757-200PF, 757-300	TCAS 7.1 UPGRADE ON B757	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List AVI-00760-MDL-R02 dated 12 Mar 2015-Aeroplane Flight Manual Supplement as per AVI-00760-AFMS-R00 dated3.Feb 2015- Instructions for Continued Airworthiness as per AVI-00760-ICA-R00dated 3.Feb 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/03/2015	Active	10052623
10052627	B/E AEROSPACE, Inc. - FSI		FAA ST02308SE	777-300	First class furniture trim and finish change	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:- 25.853(a)(d) - CS-25 Amendment 1- Part I of Appendix F to Part 25 - CS-25 Amendment 6- Parts IV & V of Appendix F to Part...	- Master Drawing List, Flight Structures Inc. document No. B3FS303-D01,Revision A, dated 9 February 2015- Instructions for Continued Airworthiness , Flight Structures Inc.documentNo. B3FS303-D15, Revision A, dated 27 February 2015or laterrevisions of the above listed documents approved by EASA ina...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/03/2015	Active	10052627
10052646 (EASA.A.S.03757)	BINDER MOTORENBAU GmbH			ASW 22 BLE 50R ASW 22 BL, ASW 22 BLE,	27 m Ansteckflügel ASW 22 BLE	The Certification Basis (CB) for the original product remains applicableto thiscertificate/ approval. The requirements for environmental protection andthe associated certifiednoiseand/or emissions levels of the original product are unchanged andremain applicable to this certificate/ approval	Ergänzung des Flughandbuchs betreffend STC ,"27 m Ansteckflügel für dasSegelflugzeug / den Motorsegler ASW 22 BL, ASW 22 BLE, ASW 22 BLE-50R"Ergänzung des Wartungshandbuchs betreffend STC "27 m Ansteckflügel fürdas Segelflugzeug / den Motorsegler ASW 22 BL, ASW 22 BLE, ASW 22 BLE-50R"Allgemeines zuo...	TN 8 and/or TN10 for ASW 22 BL/BLE/BLE 50R must be done before	18/03/2015	Active	10052646
10052652	LUFTHANSA TECHNIK AG	REV. 3		A318-112	Installation of a cabin VIP interior Revision 2 Major change for conversion to commercial for dual use(private and commercial) Revision 3 Administrative corrections	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-5302-010 Issue 1 “Isolated Compartments”;CRI D-5310-011 Issue 1 “Glass screens of Displays / Monitors”the following paragraph(s) at a later a...	• Compliance checklist: CCL25-19/24M Rev 2 dated 30.Mar.2020• Supplemental Type Definition Document: STDD25-19/24M Issue 1 Rev 0dated 31.Mar.2020• AFM A-00-19/95-AFM Issue 1 Rev 3dated 27.Mar. 2020• ICA A-00-19/95-ICA Issue 1 Rev 0 dated 04.Dec.2019• Compliance Checklist Report – Ref. 1360000200, Re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/04/2020	Active	10052652
10052672	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	757-200	B757-200 Cabin WiFi System Installation for IFE streaming	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	H4 AEROSPACE MODIFICATION SUMMARY AND DECLARATION OF COMPLIANCE NO.H4A1740 ISSUE 1 DATED 19 MARCH 2015.	Any future modifications must consider the Wifi 2.4GHz and 5GHz RFenvironment during the design.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadver...	20/03/2015	Active	10052672

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052694	AIRBUS TRANSPORT INTERNATIONAL SNC	REV. 1		A300F4-608ST	Installation of LPV/SBAS (Localizer Performance with Vertical Guidance/ Satellite Based Augmentation System) ILS (Instrument Landing System)look-alike function capabilities in accordance with Airbus TransportInternational (ATI) Change Approval Sheet ST34MOD036 issue 2 andannexes.The modification consi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM-S Appendix AD ref. (ST34MOD043_ADD Issue 1),,or later revisions of the above listed documents approved by EASA.See manuals listed in annex 8 of ATI Change Approval Sheet ST34MOD036issue 2See also annex 7 of ATI Change Approval Sheet ST34MOD036 issue 2 forproposal of evolution of the operator's M...	Pre-requisites: ATI Modifications ST34MOD032 & ST34MOD037	29/08/2016	Active	10052694
10052712	PMV ENGINEERING			747-8, 747-8F 747-400, 747-400F 747-300 747-200B, 747-200C, 747-200F 747-100	TCAS 7.1 upgrade on B747	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List AVI-00800-MDL-R00 dated 3 Mar 2015-Aeroplane Flight Manual Supplement as per AVI-00800-AFMS-R00 dated27.Feb 2015-Instructions for Continued Airworthiness as per AVI-00800-ICA-R00 dated27.Feb 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/03/2015	Active	10052712
10052729	STIRLING DYNAMICS GMBH	REV. 3		A109S	Installation of Auxiliary Hoist BracketRev. 3: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-RFM Supplement 214154-C-AM-2500-001-02or later revisions of the above listed documents approved by EASA.-Drawing Register (Master Drawing list) 214154-C-DR-2500-001-01-Certification Documents (Master Document List) 214154-C-DL-2500-001-01-Compliance Register (CCL) 214154-C-CL-2500-001-01-Means of C...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2022	Active	10052729
10052742	DASSAULT FALCON SERVICE			FALCON 7X	Cabin 14 Pax ConfigurationReplacement of existing cabin single seats by new ones and increase ofmaximum PAX configuration from 12 to 14.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dassault Falcon Service Change Approval Sheet DFS7035-CAS Issue A from24 March 2015or later revisions of the above listed documents approved by EASA.Dassault Falcon Service MasterDocument List DFS-DE-17-7X-7035 Issue Afrom 24 March 2015	Falcon 7X serial number 40 onlyPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	25/03/2015	Active	10052742
10052751	SCANDINAVIAN AVIONICS DESIGN ApS			2. B200, B200C, B300, B300C 1. 200, 200C, 300, 300LW	Approval of Installation of a Universal LPV Monitor in accordance withScandinavian Avionics Modification 2092019 Issue 1 dated 27 February2015.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of a Universal LPV Monitor in accordance with ScandinavianAvionics Modification 2092019 Issue 1 dated 27 February 2015, andEngineering Order 2092019-EO Issue 1, dated03 March 2015.Operate in accordance with Scandinavian Avionics Flight ManualSupplement 2092019-AM A Issue 2 dated 23 Feb...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/03/2015	Active	10052751

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052805	LUFTHANSA TECHNIK AG	REV. 1		A340-313	New Premium Economy Class for A340-300In the main cabin of the main floor on the aircraft, the change consistof the removal of 10 per cent of the Economy Class Seats between door 2and door 3 and the installation of new developed Premium Economy Seatsinstead. The new seating will have a greater pitch...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Statement of Compliance : No 3562 Rev 01Supplemental Type Definition Document STDD25-13/41M issue 1 rev 1ICA, ref A-00-15/14-ICA, Issue 02 rev 00Compliance Record List CRL25-13/41M iss 1 rev 2or later revisions of the above listed documents approved by EASA.	According to the design related to this STC. This modification must beinstalled in conjunction with :a) SB AIM A340--25-106 Introduction of a three part class dividerinstallation(Minor Change ref MM 635-14)<(>,<) >b) STC 10013964 rev 3, Installation of Non Electric Floor Path MarkingSystem, togethe...	12/09/2017	Active	10052805
10052811	RAISBECK ENGINEERING Inc.		FAA STC 10705SE-T	LEARJET 60 & 60R	Installation of Aft Fuselage Stowage Locker	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Raisbeck Engineering, Airplane Flight Manual Supplement, 09LJ-53-080,rev IR, dated 04 June 2014Raisbeck Engineering, Maintenance Manual, 09LJ-53-002, rev C, dated 30July 2014or later revisions of the above listed documents approved by EASAinaccordance with EASA ED Decision 2004/04/CF (or subsequent...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/03/2015	Active	10052811
10052812	VT DRB AVIATION CONSULTANTS, INC.		FAA STC ST11163SC	A320-232	Installation of G1 & G5 Galleys, on A320-232 aircraft model	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 1525.29(a)(b); .305(a)(b) ; 307 (a); .561(a)(b)(c) ; .613(a)(b) ; . 325 ;.853(a)(d3)(e)(h) ; .856(a) ; . 1307(c) ; .1309(a)(b) ; .1351(a1) ; 1353(a) ; .1431(c...	Data List, ref : DL1899M00 Revision F, dated 16 Dec 2014Instruction for Continued Airworthiness, ref : 1899CT25M02 Revision F,dated 11 Dec 2014 (Galley G1)Instruction for Continued Airworthiness, ref : 1899CT25M03 Revision F,dated 11 Dec 2014 (Galley G5)Weight and Balance data, ref : 1899RP25S02 Re...	1. This modification is only applicable to A320-232 MSN 43882. The following modification must be concurrently installed with thisSTC:EASA validation of FAA STC ST03394NY : Installation of a VIP CabinInterior on A320 aircraft modelsPrior to installation of this design change it must be determined th...	31/03/2015	Active	10052812
10052818	LUFTHANSA TECHNIK AG			A310-300	A310 - Zero G Modification	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-01, Zero-G cabin installationThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Lufthansa Technik, Airplane Flight manual Supplement, A-00-15/10-AFM,Issue 01, dated 04 March 2015Lufthansa Technik, Instructions for continued Airworthiness,A-00-15/10-ICA, Issue02, dated 26 March 2015Lufthansa Technik, Supplemental TypeDefinition Document, STDD00-14/23M,issue 01, dated 12 Marcho...	Lufthansa Technik, Airplane Flight manual Supplement, A-00-15/10-AFM,Section 2 - LimitationsLufthansa Technik, General Substantiation Data APB-CA-02, rev 0, dated04 March 2015; for data on Handrails (chapter 3) and Safety Nets(chapter 4)Prior to installation of this design change it must be determin...	31/03/2015	Active	10052818
10052821	NORTHERN AVIONICS S.R.L.			AS 350 B3 AS 350 B2	Installation of TV Communication Equipment for Bridge Helicopter (Configuration BH) and Shooting Helicopter (Configuration SH)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement RFMS NAV-0506, Rev. 0orlater revisions of the above listed documents approved by EASA.Instructions for Continued Airworthiness ICA-NAV 0506, Rev. 0Configuration Shooting Helicopter 25-NAV0506-00Configuration Bridge Helicopter 25-NAV0506-01Master Document List MDL...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/03/2015	Active	10052821

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052827	DELTA ENGINEERING CORPORATION		FAA STC ST03394NY	A320-231/-232/-233 A320-211/-212/-214	Installation of a VIP Cabin InteriorSTC Delta Eng - A320 VIP Cabin Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-2302-002 : Isolated compartmentsD-2310-002 : Glass Screens of Displays / MonitorsRefer to Project Results document , ref ODA-2375-01 Rev C, dated 07...	Master Data List, ref : 0164-09219-2375 Revision A, dated 17 Dec 2014Aircraft Flight Manual Supplement, ref : 595-TP-49, dated 13 Nov 2014Instruction for Continued Airworthiness, ref : 0764-09259-2375 RevisionA, dated 12 Dec 2014Weight andBalance data, ref : 595-AN-40 Revision Cor later revisions o...	The following modifications must be concurrently installed with thisSTC:- EASA validation of FAA STC ST02112LA : Installation of acousticinsulation- EASA validation of FAA STC ST11163SC : Installation of galleys- Airbus Modification 150016: Emergency Exit deactivationPrior to installation of this d...	31/03/2015	Active	10052827
10052831	FOKKER TECHNIEK B.V.	REV. 2		A319-115	VIP Cabin InstallationRevision 1: MMEL Supplement added.Revision 2: Transfer of STC from Fokker Services B.V. (EASA. 21J.059) toFokker Techniek B.V. (EASA. 21J.667)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-4302-012 Issue 1 "Isolated compartments"CRI D-4310-012 Issue 1 "Glass screen of display/monitors"Deviation (s):CRI D-4301-011 Issue 1 "Installati...	Compliance Record List A319-ALEX-CRR-0001 Issue 1, dated 24/03/2015Airplane Flight Manual A319-ALE-AFM-S-001 Issue 2, dated 05/03/2015Instructions for Continued Airworthiness SE-776 Issue 2, dated19/03/2015MMEL Supplement A319-FOK-MMEL-S-001 Revision 2, Chapter 6, dated25.08.2017or later revisions o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/12/2019	Active	10052831
10052845	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04268AT-D	GULFSTREAM G280	Installation of a Swift Broadband (SBB) System, or Installation ofStructural and Electrical provisions for a Swift Broadband System and anoption for the Radome only.Reason for Revision 1: added Radome only installation and installationof the full system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ aproval.	Gulfstream Index List GA413038000 Rev. N.Airplane Flight Manual Supplement GA41303M000 Rev.-.Instructions for ContinuedAirworthiness GA41303A000 Rev. Cor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis deci...	STC ST04266AT-D, Installation of an Executive Passenger Cabin isrequired prior to or concurrently with this installation.Prior to installation of this design change it must be determined thatthe interrelationship between this design changeand any otherpreviously installed design change and/ or repa...	12/04/2017	Active	10052845
10052853	AMAC AEROSPACE SWITZERLAND AG	REV. 4		747-8	Interior OutfittingThis change describes the installation of a VIP interior including allassociated components into a 747-8 “green aircraft”.Rev. 1: This revision is issued to remove the limitation to AircraftSerial Number 37075. All otherdeviations between the initial STC andthe new configurationR...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): For Aircraft Serial Number 37075 the followingSpecial Conditions are applicable: D-01, Issue 1 – Isolatedcompartments. D-108, Issue 1 –c...	For Aircraft Serial Number 37075:The change is defined withRevision AL of Master Data List documentMDL-CA01-2500.The aircraft mass and balance document shall be updated with Revision Gof Mass and Balance Manual Supplement document MBMS-CA01-2500.The aircraft shall be operated in accordance with Rev...	- This certificate does not cover commercial operation (private useonly)- This certificate does not cover the “Aeroloft” Overhead SleepingCompartment installation (EASA STC 10040913)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair...	25/09/2025	Active	10052853
10052854	CESSNA ZURICH CITATION SERVICE CENTGMBH			390	Compliance to ADS-B Out as per DO260BCompliance to ADS-B Out was shown against EASA CS.ACNS.ADSB and FAAAC20-165A as per RTCA/ DO260BImplementation of ADS-B out capability into Rockwell Collins Pro Line 21equipped aircraft with:-single or dual Rockwell Collins GPS4000S-dual Rockwell Collins TDR94D Tr...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS initial issue: CS-ACNS.D.ADSB.010, 020, 025, 030, 035, 040, 045,050, 055, 060, 070, 080, 085, 090, 100, 105, 110, 115, 120The requirements for environmental protec...	-Instructions for Continued Airworthiness: ICA-115, Rev. IR-Airplane Flight Manual Supplement: FMS-115, Rev. IRor laterrevisions of the above listed documents approved by EASA.-Master Document List: MDL-115, Rev. IR	Applicable Serial Numbers: All Hawker Beechcraft models B390 Premier 1Awith Pro Line 21 Avionics Suite factory installed or retrofitted,including FMS-3000 (single or dual) and single or dual GPS4000s (EGNOS/WAAS *SBAS* capable), dual Diversity Transponder TDR-94D, and onwhich the additional design ac...	02/04/2015	Active	10052854

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052869	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	EA 300SC	Wing tip pyrotechnic installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Operation in accordance to AFM Supplement JC/FMS/ 3767, Issue 1, dated02.02.2015.or later revisions of the above listed documents approved by EASA.	None	07/04/2015	Active	10052869
10052876	PALL AEROPOWER CORPORATION		FAA STC ST04168AT	737-600/-700/-800/-900	Control Bleed Air Line Filter Kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Pall Aeropower Drawing No.31630K1T Revision A dated 06 September 2013.	The installation applies to the referenced aircraft equipped with CFMInternational CFM56-7B engines.	08/04/2015	Active	10052876
10052886	B/E AEROSPACE, Inc.		FAA STC ST04194AT	757-300	Installation of the Rockwell Collins Aircraft Communication, Addressingand ReportingSystem (ACARS) with Data-link Communication Function	The Certification Basis for the original product as amendedby thefollowingadditional or alternative airworthiness requirements: the followingparagraph(s) ata later amendment:CS 25 Amendment 4: 25.23(a), 25.301(a)<(>,<)>25.303, 25.305, 25.307(a), 25.561(c)< (>,<)>25.601, 25.603(a)(b)(c), 25.609(a), 2...	- Master Drawing List, B/E Aerospace document No. 2-128822-001, RevisionA< (>,<)>dated 9 December 2014.- Airplane FlightManual Supplement, B/E Aerospace document No.2-128822-807<(>,<) >Revision IR, dated 16 January 2015.- Airplane Flight Manual Supplement, B/E Aerospace document No.2-128822-808<(>,<)...	Airplane Flight Manual Supplement, B/E Aerospace document No.2-128822-808 is only applicable to aircraft that have upgraded theirCockpit Voice Recorder (CVR) to satisfy data message recordingrequirements.Prior to installation of this design change it must be determined thatthe interrelationship betw...	09/04/2015	Active	10052886
10052888	EMTEQ CANADA Ltd.	REV. 1	TCCA STC SA14-53	BD-700-1A11 BD-700-1A10	MODIFICATION<(>,<)> CABIN EQUIPMENT UPGRADE	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-01 GLASS SCREENS OF MONITORS AND DISPLAYSTherequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pr...	TRANSPORT CANADA STC NO. SA14-53 ISSUE 1 DATED 04 JULY 2014EMTEQ CANADA LTD. MODIFICATION DATA SUMMARYJ369000 REVISION N/C	None	13/04/2015	Active	10052888
10052890	SKYTRAC SYSTEMS Ltd.	REV. 2	TCCA SA11-17	ATR72-212A ATR 72-201/-202 ATR72-101/-102/-201/-202 /-212 ATR 72-101/-102 ATR42-300/-320/-500 ATR 42-300/-320	SkyTrac Flight Following / SATCOM SystemThis modification is installing a SATCOM system allowing full duplexsatellite phone communication, automatic message reporting, two-waysmessaging, flight tracking, and other data transfers.Revision 1extends the applicability to the models ATR 42500, ATR 72-21...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- ADS Master Drawing list, ref : MDL10078 Revision M Issue 1, dated 20July 2021For ATR42-300 / -320 and -500:- AircraftFlight Manual Supplement, ref : FMS10078-1 Revision B, dated8 April 2019- Instruction for Continued Airworthiness, ref : ICA10078-1 Revision H,dated 12 March 2019- Airworthiness Li...	This STC does not include the installation in ATR 72-212A with MOD 5948“New Avionic Suite” incorporated (commercial designation “ATR 72-600”).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed desig...	29/05/2024	Active	10052890
10052895	FIBERGLAS-TECHNIK RUDOLF LINDNERGMBH & CO. KG			SEE EASA APPROVED MODEL LIST	Installation of additional coloured anti-collision markings.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation instructions Fiberglas-Technik Rudolf Lindner documentA/I-L01, dated 06 March 2015;Aircraft Flight Manual supplement Fiberglas-Technik Rudolf Lindnerdocument TM-L01_AFM, chapter 2 & 4, dated 06 March 2015.or later revisions ofthe above listed documents approved by EASA.Instructions for...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/04/2015	Active	10052895

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052896	AIRBORNE TECHNOLOGIES GmbH	REV. 1		P2006T	Title: STC-AT-074, Provisions for autonomous operationsDescription: These provisions include new connectors and structuralredesign to ease the removal of the instrument panels, servoinstallation for brakes, nose wheel steering, throttle, propeller,carburettor heat, a DC-DC converter, three small ant...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23, Amendment 2CS 23.1, CS 23.3, CS 23.21, CS 23.23, CS 23.29, CS 23.45, CS 23.141, CS23.301, CS 23.303, CS 23.305, CS...	Applicable Documents Doc. No. STC-AT-074 Rev. 2, dated 23.10.2020Maintenance Manual Supplement Doc. No. AMM1-STC-AT-074Rev. 1, dated09.10.2020Airplane Flight Manual Supplement Doc. No. AFM1-STC-AT-074 Rev. 2, dated09.10.2020Or later revisions of the above listed document(s) approved/ acceptedunder t...	Only provisions are installed by this STC, Autonomous operation of theaircraft as well as the manned operation where the control system of theautonomous operation system operates the aircraft is not part of thisSTC-AT-074.Prior to installation of this change/repair it must be determined thatthe inte...	02/11/2020	Active	10052896
10052903	GFD GmbH	REV. 1		35A	IFF System Lower Antenna InstallationRev. 1: Transfer to GFD GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ICA: EA5339-085_IR_ICA_03.1 0.2014- MDL: EA5339-049_MDL_IR_03.1 0.2014or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/08/2022	Active	10052903
10052904	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	MBB-BK 117 D-2	EastAnglia Air Ambulance NVIS installation in accordance withBOND/ MOD/109.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 Amdt 3 dated 11/12/2012:29.1, 29.21, 29.251,29.301, 29.303, 29.305, 29.307, 29.321, 29.337,29.341, 29.351, 29.561, 29.601, 29.603, 29.605, 29.609, 29.610, 29.611,29...	Flight Manual Supplement FMS/109-002 Issue 4 dated 9 April 2015or later revisions of the above listed documents approved by EASA.Design report DR/ 109-001 Issue 3 dated 1 April 2015Compliance Checklist for CS-29 CCL/ 109-03 Issue 2 dated 30 March 2015Compliance Checklist for NVIS CCL/ 109-04 Issue 1 da...	Minor Change Bond/MOD/098 and EASA STC 10052111 (Aerolite EMS equipment)must be embodied prior to installation of this Design Change.Rotorcraft modified by this STC employs Night Vision Imaging Systemlighting, commonly named NVIS lighting,which has been certified toensure the aircraft is compatible...	10/04/2015	Active	10052904
10052911	PMV ENGINEERING			747-8	Activation of TrueNorth GSM system onboard ,,The modification consists in:- Installation of GSM Base Station (BTS) on fwd RH cargo rack-Activation of the systemRefer to doc Certification Investigation Report (CIR) ref.SCA-00330-CIR-R03. Prior to this modification the installation of thefull provision...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFMS, Doc. No. SCA-00330-AFMS-R01, Rev. R01, dated 12.02.2015- ICA, Doc. No. SCA-00330-ICA-R00, Rev. R00, dated 20.10.2014or later revisions of the above listed documents approved by EASA.- Master Data List, Doc. No. SCA-00330-MDL-R03, Rev. R03, dated01.04.2015	In the Cockpit, the following restrictions apply:- The use of wireless or mobile phones in the cockpit is not permitted.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repai...	10/04/2015	Active	10052911
10052929	ROMTEX AERO S.R.L.			EMB-135BJ	Legacy 650 Passenger Seat Restraint Systems Modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	ROMTEX ANJOU AERONAUTIQUE Master Data List ref. 02-401793-MDL-0 01 Rev.01 dated 08/04/2015ROMTEX ANJOU AERONAUTIQUE Drawing ref. 02-401793-DW-0 01 dated26/03/2015or later revisions of the above listed documents approved by EASA.	The installation of new restraint system part numbers 5-02-BH08G0NIS and5-02-BH58G0NIS under this STC is limited to rearward facing single anddouble seats only as shown indrawing 02-401793-DW-001.	13/04/2015	Active	10052929
10052951	KAMATICS CORPORATION			206A, 206B	Installation of KAMATICS KAflex Main Rotor Driveshaft Kit in accordancewith drawing SKCP2782	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Flight Manual Supplement for Bell 206A/206B KAflex Main Rotor DriveshaftInstallation, Revision N/C, dated June 28, 2006or later revisions of the above listed documents approved byEASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Impl...	Bell 206 rotorcraft with tail rotor drive shaft part numbers206-040-383-101, 206-040-383-105, 206-040-387-103, 206-040-387-105 and206-040-387-107 must have the Kamatics Kaflex Inertia Kit, drawingSKCP3244 Revision C or later, installed.Prior to installation of this design change it must be determine...	14/04/2015	Active	10052951

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052954	H4 AEROSPACE (UK) Ltd.	REV.1	CAA UK RESPONSIBILITY	757-200	B757-200 Interior Reconfiguration to a full first class layout.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-02 Application of heat release and smoke density requirements toseat materials.The requirements for environmental protection and the associatedcertified noise and/ u...	H4 Aerospace Airplane Flight Manual Supplement H4AFMS041 Revision IRor later revisions of the above listed documents approved by EASA.H4 Aerospace Modification Summary and Declaration of ComplianceContinuation Sheet No. H4A1739 Issue 2 dated 08 April 2015.	Restricted to MSN26330- CAUTION Concession CON0416 has beenraised as Part P has not beenembodied on the aircraft. 12 minute Oxygen Generators remain installedin the Lavatories and Galley areas. The aircraft remains as previouslycertified for 12 minute operations- The Hi Alt system is currently deac...	16/04/2015	Active	10052954
10052955	LUFTHANSA TECHNIK AG			A319-111	Zonal Drying System Installation	The Certification Basis (CB) for the original product remains applicableto thiscertificate/ approval. The requirements for environmental protection andthe associatedcertified noise and/ or emissions levels of the original product areunchanged andremain applicable to this certificate/ approval	Supplemental Type Definition Document, Lufthansa Technik document No.STDD21-14/19M Issue 1, Revision 0, dated 27 March 2015Instructions for Continued Airworthiness, Lufthansa Technik document No.A-00-15/23-ICA Issue 1 Revision 0, dated 16 March 2015or later revisions of the above listed documents ap...	Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any other previouslyinstalleddesign change and/ or repairwill introduce no adverse effect upon theairworthiness of the product.	15/04/2015	Active	10052955
10052957	ACC COLUMBIA Jet Service GmbH	REV. 3		35/ 35A/ 36/ 36A	Upgrade TCAS II to ACAS II Change 7.1 Software.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. ACC Columbia Jet Service, Airplane Flight Manual Supplement,LR35-15002-800-MF-1, Rev I, dated 25 March 2015.2. ACC Columbia Jet Service, Instructions for Continued Airworthiness,LR35-15002-850-MI-0, Rev 0, dated 17 March 2015or later revisions of the above listed documents approved by EASA.3. ACC...	Only applicable to LR35/35A or LR 36/36A with STC SA8056NM-D (LBAvalidated as EMZ TA0462) installation of a Bendix KingTCAS II with Dual"S" transponder system installed in accordance with document list No.LJ-1007-TUC, Revision A, dated 08/02/00 or later approved revision.Prior to installation of th...	26/01/2022	Active	10052957
10052959	ROMTEX AERO S.R.L.			B737-800	Passengers safety belts installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 at amendment 14:25.561(b), 25.562, 25.625(d), 25.785(b)(d)(f3) (i), 853(a), 1301 (a),1309(a2)(b), 1529The requirements for environmental protection and the associatedc...	Master Data List 02-400003-MDL-001 rev 00Component Maintenance Manual supplement 02-400003-CMMS-001 rev 00or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/04/2015	Active	10052959
10052960	VECTOR AEROSPACE HELICOPTERSERVICES INC.		FAA STC SR02415AK	AS 332 C, AS 332 L, AS 332 L1	Installation of Cockpit Voice and Data Recorder System in accordancewith Vector Aerospace Helicopter Services USA, Inc.Master Drawing ListMDL HP 332-23-71-102, Rev. G, dated 29/01/2015	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Rotorcraft Flight Manual Supplement FMS HP 332-23-71-301, Rev. A, dated24/07/2014or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilate...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/04/2015	Active	10052960

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10052962	CESKA LETECKA SERVISNI A.S.			L-410UVP-E	Installation of the LPV monitor in order to comply with theAMC20-28 forLPV operation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-01, Issue 1, dated 15.05.2014The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunch...	Master Document List, AC 248 - 0001, rev. 1.0COMPLIANCE CHECKLIST AC 248 - 6101, rev 0.0FLIGHT MANUAL SUPPLEMENTFLIGHT MANAGEMENT SYSTEM (FMS) UNS-1Fw s LPV, AC248-2501<(>,<)>dated Březen, 2015 - rev 0.1or later revisions of the above listed documents approved by EASA.	The approval holder shall fulfill the obligations of Part 21, Point21.A.109 or 21.A.451(b) (as applicable).	16/04/2015	Active	10052962
10052971	HONEYWELL INTERNATIONAL INC.		FAA STC ST01098AT	MD-11, MD-11F	Installation of the Honeywell RTA-4A Weather Radar Receiver/Transmitterin the Boeing MD-11 series	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	699-50125, Revision B (1999 Jan 2007) - Master Drawing List(MDL) 756-0077-150, Revision - (2014 Sept 25) - EASA Certification BasisComparison Reportor later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision...	None	16/04/2015	Active	10052971
10052976	WHELEN ENGINEERING COMPANY Inc.		FAA STC SA615EA	SEE EASA APPROVED MODEL LIST	Installation of Whelen Anti-Collision Strobe Light Systems,Part Number01-0770006-( ), 01 -0770028-( ), 01-0770029-( ),01-0770062-( ), 01-0770900-( ), 01-0771055-( ), 01-0771080-(), and 01-0790520-( ) asreplacement for originally installed anti-collision lights, wheninstalled in accordance with Whe...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation and Maintenance according to Whelen Anti-Collision LightSystems InstallationAnd Service Manual" Document 05131 Rev. B (June 2010).or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) an...	1. These lights comply with the anti-collision light standards of theFARs as follows:- With the red or combined red/white lens; those effective on or priorto August 10,1971.- Withthe white lens; those effective on August 11, 1971.2. Install the following placard Whelen Part No. A421, or other FAAap...	17/04/2015	Active	10052976
10052988	BERINGER AERO	REV. 3		LAK-17B FES LAK-17AT LAK-17A, LAK-17AT, LAK-17B FES LAK-17A	Installation of main wheels and brake system P/N : RF-002(B) and EA-006Rev. 1: Update of part numbers including the newwheel P/N : RF-019(B)which supersedes the P/N : RF-002(B)Rev. 2: Update with new servicing instructions within ICA document andaddition of SensAIR device as an optionRev. 3: Updat...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification file: CR-MOD001-STC-011 REV 0, dated 30 Nov. 2023;Installation and Instructions for Continued Airworthiness: ICA-STC-011REV 03 dated 14 Aug. 2023or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/03/2024	Active	10052988
10053008	GARMIN INTERNATIONAL, Inc.	REV. 2	FAA STC SA02153LA-D	SEE FAA APPROVED MODEL LIST	Installation of Garmin G600 Primary Flight Display (PFD) andMultifunction Display (MFD) System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List, G600 PFD/MFD System AML STC, 005-C0313-00,Revision G, dated 1 February 2011;2. Airplane Flight Manual Supplement, G600 PFD/ MFD System AML STC, 190-00601-01,Revision E dated 28 January 2011;3. G600 PFD/MFD System Instructions for Continued Airworthiness, 190-00601-00, Revision4...	1. Aircraft equipped with Garmin G 1000/G950 Integrated Cockpit Systemare not eligible for this STC.2. Aircraft equipped with Rockwell Collins ProLine 21 IntegratedAvionics Systemare not eligible for this STC.3. Prior to installation of this design change it must be determinedthat the interrelation...	04/10/2018	Active	10053008

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053014	THE MONROE COMPANY, LLC	REV. 1	FAA STC ST02661CH	CESSNA S550 CESSNA 550	Williams FJ44-3A- Engine Retrofit	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI F-02, High Intensity Radiation Fields (HIRF) This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified n...	Clifford Development, Instructions for Continued Airworthiness,C550ST5672-1003R, rev IRClifford Development, Airplane Flight Manual Supplement,C550ST5672-1011R, rev IRClifford Development, Airplane Flight Manual Supplement 550-0028 only,C550ST5672-1020R, rev IRor later revisions of the above listeda...	Installation of BF Goodrich wheels and brakes in accordancewith CessnaService Bulletin SB550-32-12 is required with this STC.Installation of new cockpit glareshield in accordancewith Star AviationEASA STC 10015850 (FAA ST02989AT) is required with this STC.Installation of new aircraft battery in ac...	22/04/2015	Active	10053014
10053025	KAMATICS CORPORATION		FAA STC SH7951SW	BELL 206A, 206 B	Installation of KAMATICS Rotor Brake kit in accordance withdrawingSKCP2975	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Flight Manual Supplement for Bell 206A/206B KAflex rotor brakemodification Revision 2, dated September 30, 1994or laterrevisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)"and/ or the Technical Implementatio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/04/2015	Active	10053025
10053031	LMI AEROSPACE, INC.DBA TASS INC.		FAA STC ST00992SE-D	767-300	Installation of an In-Flight Entertainment System Power Control Switch	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR change 14: 25.869(a)(1)(4), 25.1307(c)(d), 25.1351(a)JAR change 18: 25.981 (a)The requirements for environmental protection and the associatedcertified noise and/ or em...	- Goodrich Master Drawing List (MDL) 2004-030, Revision A, dated June25, 2004- Supplemental Instructions for Continued Airworthiness, Goodrichdocument D2004-069, Revision A, datedJune 24, 2004- Flight Manual Supplement, Goodrich document D2004-075, Revision New,dated May 15, 2004or later revisionsa...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/04/2015	Active	10053031
10053036	AEROTEC & CONCEPT			A310-304	Aerotec Concept Mod 14251 issue 1, Pitch Stick Sensor Installation inaccordance with Master Data List AE14251MDL initial release dated 15April 2015.The modification consists in the physical installation of a pitch sticksensor in the avionic bay. The sensor is attached on the First Officerpitch cable...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Aircraft Flight Manual Supplement document ref. AE14251AFMSinitialreleas e dated 15 April 2015Instructions for Continuing Airworthiness document ref. AE14251ICAinitial release dated 02 April 2015or later revisions of the above listed documents approved by EASA.	As per paragraph 5.2 "Limitations"of Aerotec document ref. AE14251PCDPissue 3	21/04/2015	Active	10053036
10053040	AEROTEC & CONCEPT			B767-300	Installation of Dual Iridium/GPS Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/approval	Master Data List, Aerotec document No. AE14290MDL, Revision0, dated 21April 2015Instruction for Continued Airworthiness, Aerotec document No.AE14290ICA, Revision 0, dated 30 March 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/04/2015	Active	10053040

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053071	CENTEX AEROSPACE, INC.		FAA STC SA11142SC	SEE EASA APPROVED MODEL LIST	Construction and Installation of CenTex Aerospace Inc, Auxiliary fuelsaddle tanks.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The original aircraft certification basis as defined in the TCDS plusthe following FAR Part 23 sections (Amendment 23-58) that apply to thesaddle tank installation approve...	Construction and Installation of Auxiliary fuel saddle tanks inaccordance with Master Drawing List specified on the EASA AML byaircraft model.Aircraft to be maintained in accordance with ICA Manual specified on theEASA AML by aircraft model.Operated in accordance with the Approved Airplane Flight Ma...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2015	Active	10053071
10053072	DAO AVIATION A/S			BN2B-27 BN2B-20, BN2B-21, BN2B-26 BN2A-27, BN2A-8, BN2A-9 BN2A-20, BN2A-21, BN2A-26	Replacement of existing Weather Radar by Installation of Bendix/King ART2000 Weather Radar and Avidyne EX 500 Multi-function display inaccordance with DAO-D0-0543	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Arndt. 1 through 3:23.23, 23.303, 23.561, 23.603, 23.607, 23.609, 23.653, 23.1301, 23.1309,23.1321, 23.1351, 23.1357, 23.1359, 23.1431, 23.1529, 23.1581, 23.1583,23...	Flight Manual Supplement DAO-DD-0543-AFMS, IRInstallation instructions DAO-DD-0543-ECO-02or later revisions of the above listed documents approved by EASA.Instructions for Continued Airworthiness DAO-DD-0543-ICA-01	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2015	Active	10053072
10053088	TASS-EU Ltd.		CAA UK RESPONSIBILITY	DHC-8-202	Upgrade of TCAS 7.0 to 7.1 on DHC-8 202	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.1301(a) CS 25.1309(b)(d), CS 25.1322(a)(b)(c)(d), CS 25.1581(a) -all at Amdt. 15The requirements for environmental protection and the associatedcertified noise and/u...	Installation must be in accordance with TASS-EU Ltd Change Bulletin152016-CB-001-0.R.Flight operations must be conducted in accordance with TASS-EU LtdAircraft Flight Manual Supplement 152016-AR-003-0.R.Instructions for Continuing AirworthinessMaintenance must be in accordance with TASS-EU Ltd Main...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/04/2015	Active	10053088
10053097	AERODATA AG		EMZ TA 0523	FALCON 10	RVSM approval	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 14 for 25.1501, 25.1529<(>,<)> 25.1581, 25.1583(e)CS-ACNS Initial Issue for ACNS.A.GEN.001<(>,<)> ACNS.A.GEN.010,ACNS.E.RVSM.001<(>,<)>ACNS.E.RVSM.005The r...	-Master Document List, Aerodata document No. MDL-A/C/048, Revision 4,dated 27 November 2014-Instruction for Continued Airworthiness, Aerodata document No.HB-A/C-654<(>,<)> Revision 2, dated 27 November 2014-Aircraft Flight Manual Supplement, Aerodata document No. FMS-051,Revision 3<(>,<)> dated 27 N...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/04/2015	Active	10053097
10053101	AAXICO TECHNICAL SERVICES INC.	REV. 1	FAA ST04177AT	SEE EASA APPROVED MODEL LIST	LED Sealed Beam Replacement Lamps, for various Part 25 airplanes.Installation of a Talon Aerospace LED Replacement General Purpose LampsRev. 1: Transfer of STC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25 Amendment 15:25.29(b); .301(a)(b); .303; .305(a)(b); .307; .581(b); .601; .603;.605(a); .607; .609; .611; .613(a)(b)(...	Talon Aerospace Master Data List document, ref: MDL-728-01 Revision 6,dated 22 April 2015Instructions for Continued Airworthiness document, ref: AA-728-01Revision 1, dated 19 December 2014.or later revisions of the above listed document (s)approved/accepted onbehalf of EASA in accordance with the Te...	For the aircraft models applicability refer to the EASA Approved ModelList associated with this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverse...	29/06/2021	Active	10053101

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053107	AIRWOLF AEROSPACE L.L.C.	REV. 1	FAA STC SR03408CH	212 205A-1 204B, 205-A1, 212 204B	Replacement of Tension-Torsion Strap AssyRevision 1: Addition of new Airwolf tension-torsion strap part numbersAA-204-310-101-101C and AA-204-310-101-103C as an option to the existingAA-204-310-101-101 and AA-204-310-101-103 parts.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR03408CH.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	ALS - Instruction for Continued Airworthiness AA-204-ICA, Revision B,dated 21 January 2017.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/11/2020	Active	10053107
10053109	DELTA G DESIGN Inc.	REV. 1	FAA STC ST11121SC	737-900ER 737-900 737-800/-900/-900ER 737-800 737-700 737-600 737-500 737-400 737-300/-400/-500/-600/-700 737-300	Structural modification necessary for the Installation of an EMSAMT-3800 SATCOM Antenna.Revision 1: three additional installation locations for the HoneywellAviation AMT-3800 SATCOM Antenna consisting of one (1) new location onthe 737-900 and/or -900ER and two (2) new locations on the 737-800aircraf...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 amdt 0: 25.23,25.251(a)(b) , 25.301(a)(b) , 25.303, 25.305(a)(b)(e) , 25.307 (a) ,25.321(b)(c)(d) , 25.3...	Master Data List DGD-E38001-MD-01 rev EInstructions for Continued Airworthiness DGD-E38001-IC-01 rev EWeight and Balance report DGD-E38001-WB-01 rev Dor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/04/2022	Active	10053109
10053125	SCANDINAVIAN AVIONICS DESIGN ApS			2. BEECH 200/200C 1. BEECH B200/B200C	Installation of Dual Universal EFI-890R system interfaced with DualGarmin GTN-750 as primary navigation source (SAD Project No. 2086597)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amdt. 3 with exception of:-FAR 23.337 Amdt. 34-FAR 23.341 Amdt. 34-FAR 23.561 Amdt. 34The requirements for environmental protection and the associatedcertified noise...	-2086597-EO / Engineering Order (Installation of Dual Universal EFI-890Rsystem interfaced with Dual Garmin GTN-750 as primary navigationsource), Issue 1, Dated 27.04.2015-2086597-AM B / Model 200/B200 Series AFM Supplement (ESI-2000Electronic Standby Indicator), Issue 3, Dated 15.09.2014-2086597-AMS...	In case an UNS-1L FMS is installed on the aircraft in parallel with thisSTC (SAD No. 2086597) it could be used exclusively for special mission (e.g. Flight inspection) only. For commercial operation flight plan ofthe FMS shall not loaded.The installer must determine whether this design change is comp...	28/04/2015	Active	10053125
10053131	S4A SOLUTIONS FOR AVIATION, S.L	REV. 1		BN2A-20, BN2A-21	Installation of an MX15Di camera outside the fuselage and installationadaptation of an existing passenger seat.Rev. 1: Addition of model BN2A-20	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23, Amdt. 3:23.1 (a), 23.21(a)(b), 23.25(a)(b), 23.27 (a)-(c), 23.45(a)-(f),23.49(b)-(d), 23.51(a), 23.53, 23.59, 23.63,...	BN001-RPT02 Master Drawing List Issue 4, date 18/03/20BN001-DES01 Modification Description Issue 3, date 18/03/20BN001-HDK01 Flight Manual Supplement Issue 2, date 18/03/20BN001-HDK02 Maintenance Manual Supplement Issue 2, date 18/03/20.orlater revisions of the above listed document (s) approved/acc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/03/2020	Active	10053131
10053138 (EASA.IM.A.S.00700)	WIPAIRE Inc.	REV. 2	FAA STC SA270CH AND SA149CH	208	Installation of vortex generatorsOptional installation of Pratt & Whitney PT6A-114A engine in accordancewith EASA STC 10053138 (675 SHP).Optional installation of Pratt & Whitney PT6A-42A engine in accordancewith EASA STC 10047057 (850 SHP).Optional installation of Pratt & Whitney PT6A-140 engine inw...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA270CH.This approval involves a change with an impact on the noise database.The environmental protection requirements are a...	Wipaire Drawing No. 6B1-2025, No Revision, dated 20 June 1994 or a laterFAA Approved revision.Pilot's Operating Handbook Supplements (POHS): FAA approved POHS asoriginally issued,or later FAA Approved revisions, are required asfollows:Engine Power ,,,,Configuration ,,,,POHS No. ,,,,Approval Date600...	Aircraft incorporating this STC are authorized a maximum takeoff grossweight of 8360 lbs.AIRSPEED LIMITS: V A (Maneuvering) at 8360 lbs. = 153 KIASMAXIMUM WEIGHT: 8360 lbs. Takeoffand flight7800 lbs. Landing8395 lbs. RampAirplanes Not Incorporating EASA STC 10047057 (850 SHP):C.G.RANGE:Takeoff and f...	20/07/2021	Active	10053138

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053146	Q.C.M. DESIGN GmbH			BD-700-1A10	Cabin Management System Replacement - Installation of Honeywell Ovation®Select	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	QCM Certification Report No. BBD7-QCM23-001 Revision 0 dated 28 April2015	Restricted to ASN9084	29/04/2015	Active	10053146
10053162	AEROTEC & CONCEPT			757-200	Number 2 full business configuration, including In-Flight Entertainment,WiFi, In-Seat Power Supply Systems installationand activation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, Aerotec document No. AE14267MDL, Revision 0, dated 29April 2015-Aeroplane Flight Manual Supplement, Aerotec document No. 14267AFMS<(>,<)> Revision 0, dated 23 February 2015-Instruction for Continued Airworthiness, Aerotec document No.AE14267ICA<(>,<)> Revision 0, dated 23 February...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/05/2015	Active	10053162
10053203	AVIONIK STRAUBING ENTWICKLUNGS GmbH			C. 441 B. 404 F406 A. 421B, 421C, 425, 404, 441 A. 414, 414A, 421, 421A, 425 A. 402B, 402C, 411, 411A A. 401, 401A, 401B, 402, 402A	Single/dual installation of Garmin G600 System(s) includingSVT	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 329, 251, 303, 305,307, 561, 575,603, 605, 607, 609, 611, 613, 671, 771,773, 777, 863, 867, 1182, 1301, 1303, 1309, 1311, 1321, 1322, 1323,1325, 1327, 13...	Flight Manual Supplement ASR-2011-036-FMS-05-00, Rev. 00or later revisions of the above listed documents approved by EASA.-Project Description ASR-2011-036-PRD-04-00, Rev. 00-Instructions for Installation ASR-2011-036-IFI-10-00, Rev. 00-Instructions for Continued Airworthiness ASR-2011-036-ICA-11-00...	This STC is not applicable for aircraft equipped with 50 A alternators.For automatic AHRS monitoring a suitable Garmin GPS must have beenalready installed and be available for connection to the G600 system.	04/05/2015	Active	10053203
10053214	AERO-DIENST GMBH & CO. KG	REV. 1		45 (LEARJET 45)	TCAS TPU67A to B Upgrade to Version 7.1 (Honeywell)Upgrade of the existing TPU67A TCAS Processor from Version 7.0 to TPU67BVersion 7.1 by upgrade via Honeywell SB TPU 67A-34-28 toTPU67B orreplacement by a TPU67B.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight manual Supplement, AG994-071, rev AInstructions for Continued Airworthiness, AG994-085, rev IR, dated 01April 2015or later revisions of the above listed documents approved by EASA.Engineering Order, 281-LR.056.01, rev. 1, dated 29 April 2015	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/05/2015	Active	10053214
10053225	TC INTER-INFORMATICS A.S.	REV. 1		A330-302, A330-303, A330-323 A330-223F, A330-243F A330-201, A330-203, A330-223	A330 Improved Air Filter Element installationThis modification is to substitute to the originally installed airrecirculation filter elements by improved air filter elements EKO10-001-1<(>,<)> without modifying the system original design andassociated maintenance procedures.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 Amendment 14 -25.01 ; .601 ; .603 ; .605 ; . 611 ; .613 ; .831 ; .853 ; .1301 ; . 1309 ;.1529 ; .1541.The requirements...	Definition Document, ref: D61-D01 Revision 1, dated 6 May 2015Instructions for Continued Airworthiness, ref: ICA-14-007, dated 26March 2014or later revisions of the above listed documents approved by EASA.	None	18/05/2015	Active	10053225
10053238	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Electronic Flight Bag (EFB) Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Tenencia Ltd Report TEN 768/47 Issue 2 Flight Manual Supplementor later revisions of the above listed documents approved by EASA.Tenencia Ltd Modification TEN 768 Issue 2 and all its referenceddocuments	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/05/2015	Active	10053238

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053241	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 1		429	Installation of Flight Data Monitoring and Transmitting System HelicomV2 NUM or Helicom V2+ NUMRev. 1: STC holder name change from I.S.E.I International Services toSAFRAN ELECTRONICS & DEFENSE BUSINESS UNIT - HELICOPTERS DATA MANAGEMENTSOLUTIONS & SERVICES.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Lithium Batteries, closed at issue 3 on18/03/2015.The requirements for environmental protection and the associatedcertified noise and/ oru...	Rotorcraft Flight Manual Supplement, doc. ref. N11-BELL429 HV2 HV2+NUM-E-B-02 Rev.03 dated 24/04/2015<(>,<)>or later revisions of the above listed documents approved by EASA.- Certification Programme, doc. ref. N2-BELL429 HV2 HV2+ NUM E-B-05 Rev.05, dated 24/04/2015- Master Drawings List, doc. ref.0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2020	Active	10053241
10053243	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 1	FAA STC SA1077GL	2) C90A, C90GT, C90GTI 1) 70, B90, C90, E90, H90 1) 65, A65 1) 65-88, 65-90, 65-A90 1) 65-80, 65-A80, 65-B80	Replacement of existing Nose Wheel with Cleveland Nose Wheel Part No40-204.Rev. 1: Transfer from "Parker Hannifin Corporation" to "Aircraft Wheeland Brake, LLC"	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Parker Hannifin Conversion Kit 199-126,Revision K, dated December 4, 2009.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Pro...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.,,	11/03/2025	Active	10053243
10053269	AERODATA AG			B300	Installation of AD-AFIS-0116 into B300	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following CS-23 Amdt 3 paragraphs apply:23.1, 23.3(d), 23.25(a)(2), 23.29, 23.251, 23.301(a) and (c), 23.303,23.305, 23.307, 23.337(a) and (b), 23.341(a) and (c), 23.3...	Installation, Operation and Maintenance according to the Master DrawingList document number MDL-A/C-856 Rev. 3 dated 7th May 2015or later revisions of the above listed documents approved by EASA.	- Limited to model B300 with installed Proline21 avionics and nextgeneration interiors only.- The document AMM-1146 Rev. 2 (dated 8th May 2015) Chapter 04 definesadditional Airworthiness Limitations applicablePrior to installation of this design change it must be determined thatthe interrelationshipp...	11/05/2015	Active	10053269
10053271	AGUSTAWESTLAND PHILADELPHIACORPORATION			A109E	Installation of Enhanced Ground Proximity Warning System (EGPWS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFM Supplement AAC-ENG-03-096, Rev. B or later revisions ofthe abovelisted documents approved by EASA in accordance with EASA ED Decision2004/04/CF (or subsequent revisions of this decision) and/ or theTechnical Implementation Procedures of EU/ USA Bilateral Agreement.Instructions for Continuous Ai...	None	11/05/2015	Active	10053271
10053276	FIELD AVIATION EAST, LTD.	REV. 2	TCCA O-LSA14-142/D	DHC-8-202	Universal UNS-1E(w) Flight Management System Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with TCCA approved FieldAviationCompany Inc. Master Drawing and Data List, Doc.No. 26090000, Rev. B.Flight operations must be conducted in accordance with FACI FlightManual Supplement, Doc. No 26093000, Rev B.Instructions for Continuing AirworthinessMaintenance mu...	-Universal UNS-1E(w) Flight Management Systems are approvedfor IFREn-route, Terminal and Non-Precision approach operations only (LPV andRNP operations other than RNP APCH are notapproved).- Installation is limited to S.N° 482 and S.N° 453Prior to installation of this design change it must be determ...	25/08/2015	Active	10053276

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053278	AIRCRAFT DEVELOPMENT AND SYSTEMSENGINEERING (ADSE) B.V.			MYSTÈRE-FALCON 900	Installation of AeroGlass Lens for window panes and AeroGlass Mirror forlavatory finishes in Falcon 900 aircraft.The design change consists in replacing all protective inner windowpanes in the passenger cabin and cabinet doors with mirrorsin thelavatory with Aviation Glass & Technology laminated gl...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 14 for all affected requirementsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pr...	ADSE Design Definition List document ref. 14-DO-014 Rev 3 dated17.03.2015ADSE Design and Certification Plan ref. 14-DO-012 Rev 2 dated 09.09.2014ADSE Compliance Check List ref. 14-DO-015 Rev 5 dated 08.05.2015or later revisions of the above listed documents approved by EASA.	S/N 175	11/05/2015	Active	10053278
10053282	SABENA TECHNICS BGC	REV. 4		737-8/-9 737-600/-700/-800/-900/-900ER	Mechanical & electrical installation for personal tablet computerRevision 1: correction of project scope; only one docking station size.Revision 2: The configuration with the mechanical installation only,without the electrical provisions, can be installed.Revision 3: A new size of tablet docking-sta...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to the associated Certification Plan0659-01-A-2101-R06, sections 5 and 8...	- Master Data List, ref: 0659-01-A-2103-R06- Instructions for Continued Airworthiness (Supplement), ref:0659-01-A-2211-R06- AFM (Supplement) 0659-01-A-2301-R08or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	- Only for Electronic Flight Bag use. No other use permitted.- In case of Electro Magnetic Interference when personal tablet computeris connected to electrical installation, the power supply cord must bedisconnected from the USB outlet. Itis the operator's responsibility todetermine that the operat...	21/06/2019	Active	10053282
10053283	MECAER AVIATION GROUP S.p.A.	REV. 1		429	MAG VIP interiors P/N 6B420000X001-001 consisting of a cabin interiorVIP customization in term of furnishing, seats lay-outs andentertainment system.This STC revision 01 is issuedto include the Life Vest ProvisionInstallation P/N 6B422522A004-(XXX).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	6B42RFM-1-1 "B429 VIP Interior Rotorcraft Flight Manual Supplement",Revision 02, dated June 2016.ICA/ALS as per Chapter04 of 6B42WNM-2-1 "B429 VIP Interior Owner'sManual", Revision 04<(>,<)> dated June 2016or later revisions of the above listed documents approved by EASA.6B420000N004, Rev G, B429 V...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/06/2016	Active	10053283
10053287	ALPINE AEROTECH LP			212, 412, 412EP	Installation of C-Box Drain Reservoir. This Reservoir replaces theoriginal manifold and prevents the drain oil from immediately ventingoverboard.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions (ICA) AAL-061-502-001-II, Rev. NI, dated10.05.2001;Drawing AAL-061-502-001, Rev. NI, dated 08.05.2001 (Configuration);Compliance Report 1602-2, Issue NI,dated 23.10.2001;Maintenance Manual Supplement AAL-061-502-001-MMS, Rev. NI, dated08.05.2001P-15-0123 C-Box Drain reserv...	This approval is limited to Bell helicopter models 212, 412and 412EP(the model 412CF is not currently EASA certified).	12/05/2015	Active	10053287
10053288	AAXICO TECHNICAL SERVICES INC.	REV. 1	FAA ST04002AT	SEE EASA APPROVED MODEL LIST SEE APPROVED MODEL LIST	Installation of LED Replacement Wing And Tail Mounted Anti-Collision /Position Lights for Various Part 25 AirplanesRev. 1: Transfer of STC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 Amendment 1525.29; 25.301; 25.303; 25.30525.307; 25.581;25.601; 25.60325.605; 25.607; 25.609; 25.61125.613; 25.583;2...	Talon Aerospace Master Data List MDL-002 Revision 3 and allitsreferenced documents.Talon Aerospace EASA Certification Plan EAS-228-01 Revision 0or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2021	Active	10053288
10053293	ELISEN & ASSOCIES INC.		TCCA STC A-LSA13-015/D	CL-600-2B19	Structural Mods & Avionics Relocation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	Elisen and Associes Inc Master Data List MDL-37R2-757 revision E dated23 December 2013.	Restricted to ASN 7644	13/05/2015	Active	10053293

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053299	ELISEN & ASSOCIES INC.	REV. 1	TCCA STC A-LSA13-014/D	BOMBARDIER CL-600-2B19	Interior Reconfiguration Serial No 7644	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-01 SIDE FACING DIVANSThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged a...	Elisen and Associes Inc Flight Manual Supplement FMS-24R2-776 revision Edated 21 October 2013or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateralAgreement. Elisen and Associes Inc Master Data List MDL-24R2-...	Restricted to ASN 7644This aircraft is not certified for ditching per FAR25.801.	13/05/2015	Active	10053299
10053302	BUCHER LEICHTBAU AG	REV. 3		MBB-BK117 D-3M MBB-BK117 D-2, MBB-BK117 D-3 MBB-BK 117 D-2	Implementation of EC145-AC72-POL, Quick Release Hook Assy, consists of: - a hook, which acts as a securing device for the hoist operator /rope down operator - a quick release, which attaches the assy to the seat track railson the rotorcraftRevision 1Extension of applicability to MBB-BK117 D-...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement FMS-AC72, Revision AE034-01-15 "Master Document List"Revision 1Certification Compliance Reportfor Major Change E0013900, Revision NCMaster Document List E0013901, Revision NCInstructions for Continued Airworthiness ICA-AC72, Revision 01Flight Manual Supplement FMS-AC72, Rev...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/08/2024	Active	10053302
10053322	IKHANA GROUP, LLC	REV. 1	FAA SA00887LA	B) DHC-6 SERIES 400 A) DHC-6 SERIES 300/310/320 A) DHC-6 SERIES 200/210 A) DHC-6 SERIES 1/100/110	Installation of Pitot Heater Fail LightsRev. 1: Name Changefrom "Ikhana Group Inc." to “Ikhana Group LLC".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: FAR 23, Amdt. 1 through49: 23.1431(a)-(d), 23.1307(b), 23.1309(a)(b), 23.1322(b), 23.1326,23.1331, 23.1357, 23.1367, 23.41...	R. W. Martin, Inc. Master Drawing List PF6-1000, revision B. datedNovember 18 or later revisions of the above listed documents approved byEASA in accordance with EASA ED Decision 2004/04/CF (or subsequentrevisions of this decision) and/ or the Technical ImplementationProcedures of EU/ USA Bilateral...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/06/2021	Active	10053322
10053323	IKHANA GROUP, LLC	REV. 2	FAA STC SA00160LA	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of IKHANA Aircraft Services wing box assembly.Rev. 1: Name Change from "Ikhana Group, Inc." to "Ikhana Group, LLC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	R.W. Martin Inc. Master Drawing List WR6-1000, Issue B, dated December5, 2007 or later revisions of the above listed documents approved byEASA in accordance with EASA ED Decision 2004/04/CF (or subsequentrevisions of this decision) and/ orthe Technical ImplementationProcedures of EU/ USA BilateralT...	1. IKHANA Aircraft Services (formerly R.W. Martin, Inc.) part numbersWR6-1002-59, -61 are approved as replacement wing box assemblies forViking Air Limited (formerly Bombardier Inc. or DeHavilland Inc.) wingbox assemblies that have incorporated DHC Modification No. 6/1117.2. The life limit for IKHAN...	09/09/2021	Active	10053323
10053334	CESKA LETECKA SERVISNI A.S.			206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	LASER Illuminator provisions.The LASER illuminator is electrically disabled. LASER operation is notEASA approved. By enabling the LASER, the aircraft would transit to anEASA unapproved configuration. A Key Lock Switch is installed to ensurethat the LASER Illuminator is not activated without pilot pe...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement HC122-2500 Revision 0.0Instruction for Continued Airworthiness Laser Illuminator ProvisionsHC122-2700 Revision 0.0or later revisions of the above listed documents approved by EASA.Engineering Order and Certification Program for activation of LASERilluminator CLS-1...	By enabling the LASER illuminator the helicopter would transit to anEASA UNAPPROVED CONFIGURATIONIt is strictly prohibited to use LASER on groundThe LASER Key Lock Switch must be in OFF position on ground and can beenabled only by pilot oron pilots command.	18/05/2015	Active	10053334

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053348	KNSI AVIATION ENGINEERING LIMITED		CAA UK RESPONSIBILITY	A330-200	Modification of Economy Class Seats	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	KNSI Aviation Engineering Limited Master Document List No.14K100-MDL-001-5.R Revision 5 dated 18 May 2015	Restricted to ASN 330EASA STC No. (Reference SRT Project no. 0010033334-001) is aprerequisite for this STC.	19/05/2015	Active	10053348
10053350	AVIONITEC AG			T210R. T210K, T210L, T210M, T210N, T210F, T210G, T210H, T210J, 210N, 210R, P210N, P210R, 210H, 210J, 210K, 210L, 210M, 210C, 210D, 210E, 210F, 210G, 210, 210-5, 210-5A, 210A, 210B	GNS530/430 upgrade to WAAS incl LPV Cert.Remove:,,- Garmin GNS430 with existing Antenna,,,,- Garmin GNS530 with existing AntennaInstalled: ,,- Garmin GNS430W with GA 35 Antenna,,,,- Garmin GNS530W with GA 35 AntennaCompliance showing to AMC20-28 that the installed equipment is suitablefor RNAV (GNSS...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFMS for dual GNS 430W/530W Installation: Doc. No. 4960-011, Rev. 1 orlater revisions of the above listed documents approved by EASA.- Master Document List: Doc. No. 4960-017, Rev. 0- Instruction for Continued Airworthiness: Doc. No. 4960-015, dated14.11.2014- Modification Instruction for WAAS upg...	The approval holder shall fulfill the obligations of Part 21 § 21.A118.	19/05/2015	Active	10053350
10053355	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A330-200	Aer Lingus A330-200 Cabin ModificationRev.1: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement S.OAED. 000377-AFM Rev00Instruction for Continued Airworthiness S.OAED.000377-ICA Rev00Master Document List S.OAED.000377-MDL Rev00	EASA STC No. (Ref. EASA PN 0010034239 - KNSI seat modification &installation) is a prerequisite for the installation and compliance ofthis STC.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed desi...	20/04/2021	Active	10053355
10053360	KAMATICS CORPORATION	REV. 1	FAA STC SH8683SW	BELL 206L-1, BELL 206L-3	Installation of KAMATICS KAflex Main Rotor drive shaft KIT SKCP3052-1Installation of KAMATICS KAflex Main Rotor drive shaft KIT SKCP3052-3(with rotor brake)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Rotorcraft Flight Manual Supplement dated 13.07.1994or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)"and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.S/N 3052 Revisio...	Rotorcraft Flight Manual Supplement dated 13.07.1994 (or later FAAapproved version) is required when SKCP3052-3 KAflexdriveshaft withrotor brake modification is installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyp...	30/06/2015	Active	10053360
10053361	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 1		427	Installation of Flight Data Monitoring System HELICOM V2 NUM and V2+ NUMInstallation of a system for tracking a set of flight and systemparameters during operation of the rotorcraft.Rev. 1: STC holder name change from I.S.E.I InternationalServices toSAFRAN ELECTRONICS & DEFENSE BUSINESS UNIT - HELI...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRI F-01SC Lithium Battery.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged a...	ROTORCRAFT FLIGHT MANUAL SUPPLEMENT for the BELL HELICOPTERTEXTRONCANADA LIMITED Model 427 EQUIPPED WITH FDMS HELICOM V2 NUM or HELICOMV2+ NUM N11-BELL427 HV2-NUM-E-A-01-Rev.00<(>,<)>or later revisions of the above listed documents approved by EASA.- DECRIPTION OF THE CHANGE N1-BELL427 HV2-NUM E-A...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/02/2020	Active	10053361

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053365	SAAB AB	REV. 1		35A	ACAS II Honeywell CAS 67B Change 7.1Rev. 1: Transfer from SAAB AB, Nyköping to SAAB AB.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Program and Compliance Plan TDM14-48-1-CP Rev. B, dated05/05/2015Instruction for Continued Airworthiness TDM-14-48-4-ICA Rev. A, dated26/01/2015Flight Manual Supplement TDM-14-48-4-AFMS Rev. A, dated 19/01/2015or later revisions of the above listed document(s) approved/ acceptedunder th...	EASA STC 10015358 must be installed prior to the installation of thedesign change introduced through the present approval.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or rep...	06/12/2023	Active	10053365
10053377	S4A SOLUTIONS FOR AVIATION, S.L			ATP	Replacement Parts for Cargo Loading System in BAe TP Airplanes	See Certification Plan ATP01-CPL01 Edition10 (CS-25 Cert. Basis)	S4A ATP01-MI001 Manufacturing Instructions Edition 3S4A ATP01-SB001 Service Bulletin Edition 4	None	21/05/2015	Active	10053377
10053378	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		B) AB 206A, AB 206B A) 206L-3, 206L-4 A) 206A, 206B, 206L, 206L-1,	Installation of Aspen EFD1000H PFD System with ACU and RSMPanel-mounted EFIS with Analog Converter Unit, Remote Sensor Module, andConfiguration Module.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: EASA CS27, Amd. 03:CS27.29 (a)(b), CS27.251, CS27.303, CS27.305 (a)(b), CS27.307 (a)(b),CS27.561 (a)(b), CS27.603 (a)(b)(...	Flight Manual Supplement for Aspen Avionics EFD1000H Pro PFD System Doc.No: ASR-2013-022-FMS-05-00 or later revisions of the above listeddocuments approved by EASA.Project Description Doc. No: ASR-2013-022-PRD-04-00Instruction for Continued Airworthiness Doc. No: ASR-2013-022-11-ICA-00Instructions f...	In accordance with Flight Manual Supplement ASR-2013-022-FMS-05-00.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthin...	08/06/2015	Active	10053378
10053379	SCANDINAVIAN AVIONICS DESIGN ApS			650	TCAS II Change 7.1 upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- List of Certification Documents, Scandinavian Avionics Design ApSdocument No. 2094170-DOC, Issue 1, dated 28 April 2015.- Aircraft Flight Manual Supplement, Scandinavian Avionics Design ApSdocument No. 2094170-AM A, Issue 1, dated 28 April 2015;or later revisions of the above listed documents appr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/05/2015	Active	10053379
10053406	AERO-DIENST GMBH & CO. KG			55, 55B, 55C	TCAS TPU67A to B Upgrade to Version 7.1 (Honeywell)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeroplane Flight Manual Supplement, AG990-071, rev IRInstructions for Continued Airworthiness - ICA, AG990-085, rev IR,dated19 December 2014or later revisions of the above listeddocuments approved by EASAEngineering Order 275-LR.056.01 Rev. IR, dated 19 December 2014	This change is applicable for aircrafts equipped with approved TPU 67 Achange 7.0 and can be upgrade or replaced to TPU67B change 7.1 and isnot for new CAS 67B (TPU 67B change 7.1) system installation.Prior to installation of this design change it must be determined thatthe interrelationship betwee...	22/05/2015	Active	10053406
10053414	ASI AVIATION	REV. 1		B300	FAM 486 Initial issue - KA350 SURMAR mission equipment installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AMM Supplement MM-350-0000-01 Rev 1 dated 13 May 2015POH Supplement PO-350-950001 Rev 6 dated 13 May 2015STC Data List DL-350-000001 initial issue dated 20 May 2015or later revisions of the above listed documents approved by EASA.	Limitation to serial numbers FL-682, FL-746, FL-752, FL-777, FL-781,FL-800 and FL-802 equipped with radome kit no. 130-4015 HBC EASA STC10027658 and cabin audio system HBC FAA STCSA11049SC-D.Before installation of the HBC FAA STC SA11049SC-D cabin audio system,its EASA validation shall be checked....	29/07/2015	Active	10053414

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053445	ROMTEX ANJOU AERONAUTIQUE S.R.L.			A320-214	Cabin reconfiguration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged andremain applicable to this certificate/ approval	Master Data List, AnjouAero document No. 02-401936-MDL-001 Revision 0,dated 9 April 2015.Airplane Flight Manual Supplement, AnjouAero document No. 02-401936-AFMS- 001, Revision 0, dated 9 April 2015.or later revisions of the above listed documents approved by EASA.	The design change is limited to MSN 3891. Extended overwater operationsare prohibited.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect...	28/05/2015	Active	10053445
10053451	NORTHERN AVIONICS S.R.L.			AS 355 N AS 355 F2 AS 355 F1	Installation of TV Communication Equipment for Shooting from Helicopter	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement RFMS NAV0505-01, Rev. 0 (applicableto helicopter versions AS355F1 & AS355F2)Rotorcraft Flight Manual Supplement RFMS NAV0505-02, Rev. 0 (applicableto helicopter versions AS355N) Instructions for ContinuedAirworthiness ICA-NAV0505, Rev. 0or later revisions of the a...	None	28/05/2015	Active	10053451
10053464	DEVORE AVIATION CORPORATION OFAMERICA		FAA STC ST08994AC	FALCON 2000	Installation of tail floodlights on upper and lower surfaces ofhorizontal stabilizer	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Drawing, DeVore document No. 02000005 Revision A, dated 16January1995.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreem...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/05/2015	Active	10053464
10053470	AIRBUS S.A.S.			A320-214	Airbus Corporate Jet Centre Modification CJ1800 VIP Project"Royal ThaiAir Force"	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-2322-001 - MinisuitesCRI E-21 - Isolated CompartmentsEquivalent Safety Finding(s):CRI E-28 - Improved Flammability StandardDeviation (s):CRI E-23...	Modification Approval Sheet ref CJ1800, Issue 1, dated 28/05/2015Airplane Flight Manual - AFM Supplement ref FM-S MOD CJ1800, dated01/05/2015Maintenance Planning Document - MPD Supplement ref MPD-S MOD CJ1800,dated 01/05/2015or later revisions of the above listed documents approved by EASA.	This approval is limited to MSN 6112Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	01/06/2015	Active	10053470
10053477	VOYAGEUR AVIATION CORP.		TCCA SA14-58, ISSUE 2	DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Fuel Quantity Gauging System Replacement- Auxiliary Fuel Tanks	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s): E-01 – Fuel Tank Safetythe following paragraph(s) at a later amendment: CS 25.869, CS 25.899,CS 25.1431The requirements for environmental protectionc...	Installation must be in accordance with TCCA approved Voyageur AirwaysLimited Design Change Summary DCS 13-1774, Rev. BInstructions for Continuing AirworthinessMaintenance must be in accordance with TCCA accepted Voyageur AirwaysLimited Maintenance Manual Supplement MMS 13-1774, Rev. N/CAirworthine...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/06/2015	Active	10053477

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053486	DART AEROSPACE Ltd.		TCCA SH14-17	407 206L-1, 206L-3, 206L-4 206A, 206B, 206L	Replacement Engine Mounts.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MDL-D407-811 Rev. A- Instructions for Continued Airworthiness ICA-D407-811 Rev. 0- InstallationInstructions IIN-D407-811 Rev. B.	Installation of the Replacement Engine Mounts must be in accordance withTransport Canada Civil Aviation (TCCA) approvedDart Aerospace Ltd.Installation Instructions IIN-D407-811 Revision B, dated May 7, 2014 orlater TCCA approved revision.Maintenance of the Replacement Engine Mounts must be in accor...	01/06/2015	Active	10053486
10053498	PMV ENGINEERING			B747-8	Activation of eXPhone system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List SCA-00151-MDL Rev. 02Certification investigation report SCA-00151-CIR Rev 01AFM Supplement SCA-00151-AFMS Rev 00Instructions for continued airworthiness:-MSN 37500:SCA-00151-ICA-S01 Rev 00-MSN 37544:SCA-00151-ICA Rev 01	As per AFM supplement, the use of transmitting portable electronicdevices (T-PEDs) is not allowed:- during any flight phase in the cockpit<(>,<)>- during critical flight phases (TTOL) in the cabinPrior to installation of this design changeit must be determined thatthe interrelationship between this...	02/06/2015	Active	10053498
10053510	AEROTEC & CONCEPT			AS365 N3	Solid State Voice Cockpit & Flight Data Recorder Installation(MOD AEROTEC CONCEPT N°13114)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS29 amendment 3:29.25, 29.27, 29.251, 29.301, 29.303, 29.305, 29.561, 29.601, 29.603,29.605, 29.607, 29.609, 29.610, 29.625, 29.1301, 29.1309, 29.1351,29.1353, 29.1357, 2...	Rotorcraft Flight Manual Supplement ref. AE13114RFMS, initial issueor later revisions of the above listed documents approved by EASA.MASTER DATA LIST document ref. AE13114MDL Rev.0, dated 20/03/15	Valid for AS365 N3 S/N 6959 onlyPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	02/06/2015	Active	10053510
10053511	AVIONICARE Ltd.		CAA UK RESPONSIBILITY	SEE APPROVED MODEL LIST	Upgrade the CAS 67A TCAS II Systems to Incorporate MOPS Change 7.1functionality	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 Amendment 15 - CS25.1; CS 25.25; CS 25.27; CS 25.1301; CS 25.1302; CS 25.1309; CS25.1322; CS 25.1501; CS 25.1519; CS...	Avionicare Flight Manual Supplement FMS-0020-CAS 67B-001 Revision 1 orlater revisions of the above listed documents approved by EASA.Avionicare Master Document List AVC-MDL-0020 Issue G.	Applicable to aircraft with a previously installed Bendix King CAS 67ATCAS II system.	02/06/2015	Active	10053511
10053512	SOCIETE AIR FRANCE S.A.			A330-343	Thomas Cook - Cabin rearrangement / IFE installationCabin seating re-arrangement (“Acro Y/C” new seats) and new Zodiac “imsRAVE“ IFE system	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:refer to section 12.1 in Certification plan ref CP-A330-14-003The requirements for environmental protection and the associa...	- Change Approval Sheet CAS-A330-14-003 rev 0.- Instructionfor Continued Airworthiness, ref : ICA-A330-14-003 rev 0or later revisions of the above listed documents approved by EASA.	1) This STC is applicable to MSN 349, 356, 357 only.2) The following modifications has to be embodied on the aircraft, asper the requirements of the design of this STC : a. Lufthansa Technik Engineering Bulletin ref. A330-EB33-0391 revision00 for Guide U 1000 series photoluminescent emergency floor...	02/06/2015	Active	10053512
10053514	LUFTHANSA TECHNIK AG	REV. 2		747-800 747-8	VIP Cabin interior completionRevision 1: Replacement of conductive oxygen flex-hoses withnon-conductive onesRevision 2:Modification of the intrusion detection support structure	As per CRI A-101 issue 3 issued for project 0010011013; andCS 25.571amdt 19 for the area affected bySTC R2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approva...	Supplemental Type Definition Document STDD00-12/26M Issue 05 rev 02AFM supplement A-00-12/48-AFM issue 02ICA document A-00-12/48-ICA issue 07 rev. 00Oxygen flex-hoses replacement documents:CPL35-20/09M rev 00or later revisions of the abovelisted document (s) approved/ acceptedunder the EASA system.	- The airplane shall be operated for private use only- As per AFM supplement A-00-12/48-AFM section “Certificate limitations”- As per ICA document A-00-12/48-ICA section 4.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any o...	21/01/2025	Active	10053514

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053520	CONCORDE BATTERY CORPORATION			C-212-DF C-212-DE C-212-CF C-212-CE C-212-CD C-212-CC C-212-CB	Validation of FAA ST04178AT.Replacement of Original Nickel-Cadmium Main and Auxiliary Batteries byConcorde Lead-Acid Batteries.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement No. 5-0493, rev. NC, dated 30 September 2014.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.Master D...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/06/2015	Active	10053520
10053522	VOYAGEUR AVIATION CORP.		TCCA SA09-57 ISSUE 2	DHC-8-314, DHC-8-315. DHC-8-301, DHC-8-311, DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103,	Long Range Fuel System Retrofit	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): E-01 – Fuel Tank Safety.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original prod...	Installation must be in accordance with TCCA approved Voyageur AirwaysLimited Design Change Summary DCS 09-0001, Rev. B.Flight operations must be conducted in accordance with TCCAapprovedVoyageur Airways Limited Flight Manual Supplement AFMS 09-0001, Rev. B.Instructions for Continuing Airworthines...	The installation of EASA STC 10053477 (TCCA STC SA14-58, Issue 2) is aco-requisite.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upo...	03/06/2015	Active	10053522
10053524	HELI-ONE (NORWAY) AS			EC 225 LP	EMS & Rescue Cabin Configurations in accordance with PCD AHSE-67000 rev.A, dated 28.05.2015.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS29 Amdt 3, dated11/12/2012: 29.1, 29.29, 29.307, 29.309, 29.561, 29.783, 29.785, 29.803,29.807, 29.809, 29.813, 29.815,2...	Heli-One Flight Manual Supplement H1No.255, dated 28.05.2015 or laterrevisions of the above listed documents approved by EASA.Product Change Definition AHSE-67000 rev. A, dated 28.05.2015Certification Programme AHSE-67003 rev. C, dated 28.05.2015Declaration of Compliance AHSE-67001 rev. A, dated 28....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/06/2015	Active	10053524
10053534	DASSAULT AIRCRAFT SERVICES (DAS)	REV. 1	FAA ST02972NY	MYSTÈRE-FALCON 900 (MF900)	Validation of FAA STC ST02972NY.Installation of ADS-B Out SystemRevision 1: Installation of ADS-B Out System compliant with DO-260B.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: JAR25.869(a)(4) at Change 14 for the parts modified by this change.The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	- AFM Supplement ref. F9BW-D0025-150 Rev. I/R, dated 14 July 2014(Config. 1 DO-260A);- AFM Supplement ref. F9BW-D0045-150 Rev. I/R, dated 31 August 2016(Config.2 DO-260B);- STC Master Data List ref. F9BW-D0025-005 Rev. E, dated 31 August 2016;- Instructions for Continued Airworthiness ICA F9BW-D0025-...	The installation of the EASA STC 10051493 (validation of FAA STCST02970NY)<(>,<)> for the installation of Honeywell GPSLanding SystemSensor Unit (GLSSU) is a pre-requisite for this design change.Prior to installation of this design changeit must be determined thatthe interrelationship between this...	13/06/2017	Active	10053534
10053536	WHELEN ENGINEERING COMPANY Inc.		FAA SA615EA	SEE APPROVED MODEL LIST	Installation of Anti-Collision Light Systems	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Whelen Engineering Company Inc. “Anti-Collision Light SystemsInstallation and Service Manual”<(>,<)> Document No. 05131Rev. C datedOctober 2014.	Install the following placard Whelen Part No. A421<(>,<)> or other EASAapproved equivalent:WARNING,,TO AVOID OPTICAL ILLUSION AND SEVERE VERTIGO<(>,<)> TURNANTI-COLLISION LIGHTS OFF UPON ENTERING CLOUDS<(>,<)> FOG OR HAZEPrior to installation of this design change it must be determined thatthe inter...	03/06/2015	Active	10053536

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053543	ARMSTRONG AEROSPACE Inc.		FAA STC ST03398CH	A320-232	EASA Validation of FAA STC ST03398CH, originally issued November 24th,2014.Installation of a Panasonic eXWireless In-Flight Entertainment (IFE) System in accordance with Armstrong Aerospace Master Data List, Doc. No.DC104-9501-00, Revision C, dated November 18th 2014 or later approvedrevisions	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Armstrong Aerospace Master Data List, Doc. No. DC104-9501-00, RevisionC, dated November 18th 2014, andAirplane Flight Manual Supplement, Armstrong Aerospace Doc. No.DC303-9501-00,Revisio n -, as originally approved by the FAA onNovember 24th, 2014or later revisions of the above listed documents ap...	1) Compatibility of this design change with previously approvedmodifications must be determined by the installer.2) Modification in accordance with this STC requires prior or concurrentembodiment of FAA STC ST03103CH (validated through EASA airworthinessapproval certificate 10046843), CertificationC...	04/06/2015	Active	10053543
10053544	LUFTHANSA TECHNIK AG			A321-231, A321-232 A321-211, A321-212, A321-213 A321-111, A321-112, A321-131 A320-232, A320-233 A320-215, A320-216, A320-231 A320-211, A320-212, A320-214	TCAS Change 7.1TCAS Change 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Applicant's Declaration of Compliance N. 3564, dated 15/04/2015Supplemental Type Definition Document STDD34-13/19M Issue 1, Rev.0,dated 15/04/2015Compliance Record List CRL34-13/19M Issue 1, Rev.1, dated 15/04/2015Instructions for Continued Airworthiness A-00-15/02-ICA Issue 1, Rev. 0,dated 07/01/20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/06/2015	Active	10053544
10053548	FOKKER SERVICES B.V.			757-200, 757-200PF, 757-300	Boeing 757 TCAS V7.0 upgrade to V7.1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan CP-0235 Issue 3Compliance Record Report CRR-0235 Issue 1or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/06/2015	Active	10053548
10053550	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			A320-232	Introduction of TCAS II Version 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance Check List MODE00120_CCL Rev. 2, dated 08/04/2015Master Data List MODE00120_MDL_APP Rev. 2, dated 02/06/2015Aircraft Flight Manual Supplement MODE00120_AFMS Rev. 4, dated02/06/2015or later revisions of the above listed documentsapproved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/06/2015	Active	10053550
10053558	JET AVIATION AG	REV. 4		A340-642	A340-600 VIP Interior InstallationThis STC installs a complete cabin interior distributed into of threeclasses: a VIP area including forward galleys, storage / dressing,lounge area, bedrooms with bathroom, office room, hallway, VIP lavatory,a first class area including lavatory and dining room, andc...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):D-1302-006: Isolated compartments.D-1310-006: Glass screens of displays / monitors.D-1314-003: Shower installation.- Deviation (s):D-1301-006: Interi...	- Master Data List, ref: JBSL-M-00003CDS-01 Issue 4, dated 6 June 2020;- Aircraft Flight Manual Supplement, ref: JBSL-M-00003AFM-01 Issue 2,dated 25 March 2020;- Instructions for Continued Airworthiness, ref: JBSL-M-00003ICA Issue1, dated 12 May 2015;- Weight and Balance Manual Supplement, ref: AUB-...	Limited to MSN 779: Reason: This STC is a unique VIP interiorinstallationNON-COMMERCIAL OPERATION: The Aircraft is certified for private useonly. It is prohibited to operate the aircraft for hire or offered forcommon carriage. (AFMS, Section 1 – Limitations) Prior to installation of this design change...	23/06/2020	Active	10053558
10053568 (EASA.IM.A.S.0022)	MACHINING PROGRAMMING MANUFACTURIN GInc.			BD-100-1A10 (CHALLENGER 300)	The modification consists in the installation of folding step ladder toprovide access to the tailcone equipment compartment in accordance withMPM Inc. Aft Ladder Installation Drawing LD001 dated 4th September, 2003(or later EASA approved revision).			1. This STC is approved only for the product configuration as defined inapproved design data referred to in the paragraph "Description".2. Compatibility with other aircraft/ engine configurations shall bedetermined by installer.This certificate shall remain valid unless otherwise surrendered orrevok...	09/07/2014	Active	10053568

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053569 (2004-477)	ROCKWELL COLLINS, Inc.	REV. 2	FAA SA00907WI-D	SEE EASA APPROVED MODEL LIST	Modification of a Rockwell Collins Inc, TCAS II System Installation toChange 7.0 or Change 7.1.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 23.1301(a)(b)(c)(d) Am 20FAR 23.1309(a)(b)(e) Am 49FAR 23.1322(a)(b)(c)(d) Am 43FAR 23.1431(a)(b) Am 49FAR23.1501(b) Am 21FAR 23.1581(a) Am 50The requirements for env...	Installation in accordance with Rockwell Collins, Inc. Drawing Index992-4375-001, Rev H, dated September 7, 2011, as listed on the attachedApproved Model List (AML).Operation in accordance with Rockwell Collins Airplane Flight ManualSupplements as listed on the attached Approved Model List (AML).ora...	Approval of this change in type design applies to the aircraft in theattached Approved Model List (AML) only.A copy of this Certificate and the Approved Model List (AML) must bemaintained as part of the permanent records for the modified aircraft.Prior approved installation of a Rockwell Collins, In...	27/10/2015	Active	10053569
10053570 (EASA.IM.R.S.00595)	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA SR00898SE	407 206L, 206L-1, 206L-3, 206L-4	Onboard Cargo Hook system Part Numbers 200-258-00, 200-258-01,200-259-00, 200-259-01, or 200-259-02 in accordance with Onboard MasterDrawing List No. 155-058-00.The purpose of Revision 1 to EASA approval IM.R.S.00595/10053570 is toinclude Part Numbers 200-258-01 and 200-259-02.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement (RFMS) No. 121-003-00, Revision 2,dated 02 August 2007 applicable for P/N 200-258-00, 200-259-00, and200-259-01 cargo hook kits.Rotorcraft Flight Manual Supplement (RFMS) No. 121-003-01, Revision 0,datedJanuary 13, 2012 applicable for the P/N 200-258-01 and 200-2...	This approval applies to helicopters Bell 206L, 206L1, 206L3, 206L4 and407 models equipped with Bell Auxiliary Kit Cargo Hook Provisions partnumbers (P/N) 206-706-341-7/ -9/ -103/-111/ -113/ -117/ -123/ -125 orOnboard Systems Fixed Provision Kit, P/N 200-328-00.Prior to installation of this designt...	22/02/2017	Active	10053570
10053571 (EASA.IM.R.S.00594)	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC SR00895SE	206A, 206B	Onboard Cargo Hook system Part Numbers 200-268-00, 200-268-01,200-269-00, 200-269-02, or 200-269-03 in accordance with Onboard MasterDrawing List No. 155-064-00.The purpose of Revision 1 to EASA approval IM.R.S.00594/10053571 is toinclude Part Numbers 200-268-01 200-269-02, or 200-269-03.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	Onboard Systems Rotorcraft Flight Manual Supplement (RFMS) No. 121-009-00,Revision 2, dated September 27, 2007, for the 200-268-00,200-269-00,200-269-02 cargo hook kits.Onboard Systems Rotorcraft Flight Manual Supplement (RFMS) No. 121-009-01, Revision 0, dated November 30, 201, for the 200-268-01 or2...	This approval applies to helicopters Bell 206A and 206B equipped withBell Cargo Hook Kit Provisions part number 206-706-335-3/ -5/ -105/-109.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design...	22/02/2017	Active	10053571
10053577	ROCKWELL COLLINS, Inc.		FAA STC ST01837LA	737-900 737-800 737-700 737-600	Installation of Rockwell Collins HF Transceivers and Couplers	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 25 Amendment OriginalFAR 25.1301FAR 25.1357FAR25.1541FAR 25.1555FAR 25 Amendment 25-23FAR 25.301FAR 25.303FAR 25 Amendment 25-38FAR 25.1355FAR 25 Amendment 25-41FAR 2...	Rockwell Collins Master Data List 2828-01 Revision D	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/06/2015	Active	10053577
10053580	LUFTHANSA TECHNIK AG	REV. 1		747-8	Patient Transport Compartment / Patient Transport Unit installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-115 installation of a PTC Issue 1.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	STDD 00-13/23m Issue02 rev 00Instructions for Continued Airworthiness:-provisions: A-00-14/11-ICA Issue04 rev 00-installation: A-00-15/28-ICA Issue02 rev 00or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/07/2015	Active	10053580

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053586	ROCKWELL COLLINS, Inc.		FAA STC ST00983LA-D	737-600, 737-700, 737-800	Multi-Mode Receiver Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 25 Amendment Original,FAR 25.561, FAR 25.601, FAR 25.1301, FAR 25.1357, FAR 25.1541, FAR 25Amendment 25-23<(>,<)>FAR 25.301, FAR 25.303, FAR 25.611FAR 25 Amendment 25-...	Rockwell Collins Aircraft Flight Manual Supplement 2508-AFMRevision Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreemen...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/06/2015	Active	10053586
10053593	SCANDINAVIAN AVIONICS DESIGN ApS			737-500 737-300	GPS Antenna Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt 4CS 25.1, CS 25.29, CS 25.301, CS 25.303<(>,<)>CS 25.305, CS 25.307, CS 25.337, CS 25.571<(>,<)>CS 25.581, CS 25.601, CS 25.603, CS 25.605<(>,<)>CS 25.609, CS 2...	Engineering Order & Certification Program, Doc ref: 2094034-EO Issue D1Compliance Record. Doc Ref: 2094034 COR Issue 1Continued Airworthiness, Doc 2094034-CA issue 1Structural Load Analysis Appendix, doc 2094034-SL, issue 1Structural Load Analysis Appendix, doc 2094034-SL APP A, issue 1Technical Ord...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/06/2015	Active	10053593
10053604	SOCIETE AIR FRANCE S.A.	REV. 1		A330-243	ACG - Cabin re-arrangement/IFE installationCabin seating re-arrangement (“Acro" Y/C and “ZIM“ Y/C Premium newseats) andnew Zodiac “ims RAVE 2" IFE system.Revision 1 of this STC removes MSN limitation [see Limitation section,bullet point 1)] which made the original issue of this STC applicable toMSN...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:JAR 25.603 Change 14, JAR 25.613 Change 14, JAR 25.853(a)(b)(c) Change13/14, JAR 25.854 Change 14, JAR 25.X899(a)(b)(c) Cha...	Change Approval Sheet CAS-A330-14-005 rev 0.Instruction forContinued Airworthiness, ref: ICA-A330-14-005-001 rev 0or later revisions of the above listed documents approved by EASA.	1) [Deleted].2) The following modifications have to be embodied on the aircraft, asper the requirements of the design of this STC:a. Lufthansa Technik Engineering Bulletin ref. A330-EB33-0391 revision00 for Guide U 1000 series photoluminescent emergency floor path markingsystem installation (Approve...	31/01/2020	Active	10053604
10053613	Q.C.M. DESIGN GmbH			EC 130 T2	E350-QCM34-001 Installation of an Avidyne TAS605 TASRemoved: - N/AInstalled: - Avidyne TAS 605 Traffic Advisory System (TAS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement: E350-QCM34-001-M1-HFM-R2, dated 20.05.2015or later revisions of the above listed documents approved by EASA.Master Document List: E350-QCM34-001-R1_Section 2, dated 10.06.2015Instructions for continued airworthiness: - E350-QCM34-001-M1-ICA-R0,dated 16.03.2015	Limited to S/N 7989Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	10/06/2015	Active	10053613
10053614	HELIPRODUCTS INDUSTRIES Ltd.		TCCA STC SH13-50	AS 355 E/F/F1/F2/N/NP AS 350 B/B1/B2/B3/BA/D	Installation of AVEO Engineering position and anticollisionLED lights	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List no. RLM-MDL-001 Rev C dated 05 August 2014 (AS 350series)Master Drawing List no. RLM-MDL-002 Rev A dated 04 November 2014 (AS 355series)Installation instructions no. HP350LEDXT-II REV 2 dated 10 January 2014Installationinstructions no. HP350LEDXT-II REV 0 dated 21 October 2014In...	None	10/06/2015	Active	10053614

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053619	HELI-ONE		TCCA STC SH12-26	AS 332 L1 AS 332 L	Installation of Powersonix Loud Hailer	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement CHA332-25-045 FMS Rev. 3, dated 10August 2012or later revisions of the above listed documentsapproved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Master Drawing List CHA332-25-045 MDL Rev. C, dated 23 October 2013Compl...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/06/2015	Active	10053619
10053620	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04283AT-D	GULFSTREAM G280	Installation of a Heads Up Display (HUD) and Enhanced Vision System(EVS)on the Gulfstream Aerospace LP Model GulfstreamG280 airplane.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):CRI F-01 EFVS & HUD for operational credit down to 100 ft.The requirements for environmental protection and the associatedcertified noise and/ or emi...	Certification Plan G250-GER-1054 Revision D, dated 27 of January 2013.Aircraft Flight Manual Supplement G250-GER-9283 Revision B, dated 8 ofApril 2014.Instructions for Continued Airworthiness G250-GER-0145 Revision B, dated14 of May 2013.Instructions for Continued Airworthiness GER-0207 Revision A,o...	None	30/06/2015	Active	10053620
10053621	GARMIN INTERNATIONAL, Inc.	REV. 3	FAA STC SR02120SE	SEE FAA APPROVED MODEL LIST SEE FAA AML	Installation of Garmin GTN 6XX/7XX and GTN Xi Series Navigation SystemRev. 3: Update of new hardware models for obsolete parts.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 005-00533-H0, Revision 1, 29 October 2013or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the TechnicalImplementationProcedures of EU/ USA Bilateral Agreement.TheMaster Drawing List establishes the approved configuration f...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	10/12/2021	Active	10053621
10053659	PMV ENGINEERING	REV. 2		A310-322, A310-304, A310-325 A310-221, A310-222, A310-308 A310-203C, A310-204, A310-324 A300 F4-605R, A300 F4-622R A300 F4-203, A310-203 A300 C4-620 A300 C4-605R VARIANT F A300 B4-620, A300 B4-622 A300 B4-605R, A300 B4-622R A300 B4-601, A300 B4-603 A300 B4-220, A300 C4-203 A300 B4-120, A300 B4-203 A300 B4-102, A300 B4-103 A300 B2-320, A300 B4-2C A300 B2-202, A300 B2-203 A300 B2-1C, A300 B2K-3C A300 B1, A300 B2-1A	TCAS 7.1 upgrade on A300/A310/ A300-600.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List AVI-00720-MDL-R01, dated 8. June 2015Aircraft Flight Manual Supplement AVI-00720-AFMS-R00, dated 4.May 2015Instructions for Continued Airworthiness AVI-00720-ICA-R00, dated 4.May2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/10/2015	Active	10053659

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053663	AERO-DIENST GMBH & CO. KG			31, 31A	TCAS TPU67A to B Upgrade to Version 7.1 (Honeywell)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement, Doc. No. AG991-071, Rev.AInstructions for Continued Airworthiness, Doc. No. AG991-085, Rev. IRdated 15 December 2014or later revisions of the above listed documents approved by EASA	None	12/06/2015	Active	10053663
10053664	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	PA-31T2 (CHEYENNE IIXL)	Installation of Various Aeronautical Antennas	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following CS-23 Amdt 3 paragraphs apply:23.1, 23.23, 23.25, 23.29, 23.141, 23.171, 23.221, 23.301, 23.303,23.305, 23.307, 23.321, 23.333, 23.337, 23.341, 23.351, 23.36...	Installation and Maintenance according to Tatenhill Aviation LtdInstallation Manual (document IM.00115 Revision A).or later revisions of the above listed documents approved by EASA.	- Limited to model PA-31T2 (Cheyenne IIXL)- To be installedonly in conjunction with the Tatenhill Minor ChangeTAL-TAD 009/15- Installed antennas shall be maintained according to the Appendix ASection 3 of the Tatenhill Aviation Ltd Installation Manual (IM. 00115Revision A).Prior to installation of t...	12/06/2015	Active	10053664
10053666	DRF STIFTUNG LUFTRETTUNGG EMEINNUETZIGE AG			MBB-BK 117 C-1 MBB-BK 117 B-2	Installation of GNC 255 and GTN 650 COM/NAV System without LPV/ SBAScapability	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MBB BK117 B-2/C-1 FMS 10-DRF-026 initial issue dated 05.06.2015or later revisions of the above listed documents approved by EASA.Compliance Checklist CC-117-34-60-00006Master Document List MD-117-34-60-00009	GPS/RNAV approaches are prohibitedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	12/06/2015	Active	10053666
10053672	AVIONICARE Ltd.		CAA UK RESPONSIBILITY	BAE 146 SERIES 300 BAE 146 SERIES 200 BAE 146 SERIES 100 AVRO 146-RJ70, AVRO 146-RJ85 AVRO 146-RJ100, AVRO 146-RJ115	Upgrade of TCAS II Systems to incorporate MOPS Change 7.1 Functionality	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 15CS 25.1; CS 25.25; CS 25.27; CS 25.1301; CS 25.1309; CS 25.1322; CS25.1431; CS 25.1501; CS 25.1519; CS 25.1529; CS 25.1581; CS 25.1585The requirements fo...	Avionicare Flight Manual Supplement FMS-0033-BAe146/Avro146-RJ-001Revision 1or later revisions of the above listed documents approved by EASA.Avionicare Master Document List AVC-MDL-0033 Issue E	Applicable to aircraft with a previously installed TCAS II systemincorporating an ACSS RT-950<(>,<)> Rockwell Collins TTR-920 or TTR-921or a Honeywell TPA-81A TCAS processorPrior to installation of this design change it must be determined thatthe interrelationship between this design change and anyp...	15/06/2015	Active	10053672
10053717	ALIDAUNIA S.R.L.			A109 AII	Installation of swinging landing/search light	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFM Supplement FMS/ALI/ 024, Rev. 0or later revisions of theabove listed documents approved by EASA.Bollettino di Modifica 024/ALI/2013, dated 13.12.2013 (ModificationBulletin) (Contains: Master Doc. List, CCL & MOC)Disegni Tecnici di Progetto TD/ALI/ 024, Rev. 0, dated 13.12.2013(Contains: Master Dr...	None	17/06/2015	Active	10053717
10053718	BELL TEXTRON, Inc.	REV. 1	FAA STC SR00780DE	429	Installation of Tail Rotor Pedal Removal KitThis STC installs a kit to allow the rapid removal of the Tail RotorPedals at the left hand pilot position when a non-pilot occupies theseat.Rev. 1: Transfer from "La Paz, LLC. to "Bell Textron, Inc."	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing list – Report Number LT-13205 Revision AInstallation Instructions – Report Number LT-13207 Revision AInstruction for Continued Airworthiness – Report LT-13202	1. FAA accepted Instructions for Continued Airworthiness, Laz-Tec, LLCDocument No. LT-13202, No Revision, dated May 30,2014, FAA accepted June02, 2014, or later FAA accepted revision is required.2. If the STC holder agrees to permit another person to use thiscertificate to alter the product, the hol...	17/03/2025	Active	10053718

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053719	AERODATA AG			737-700, 737-800	Installation of Aerodata "AeroPhone+" Satcom communication system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SII Master Document List MDL-232-00002-000 issue NRücker Aerospace Change Description CD-232-00002-000 issue GAerodata AFM Supplement AFM-142 issue 3SII AMM Supplement AMS-232-00002-000 issue Eor later revisions of the above listed documents approved by EASA.	As per AFM supplement AFM-142Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	17/06/2015	Active	10053719
10053726	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 2	FAA ST01651CH	LEARJET 45	Air Ambulance Conversion	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List 6015DL, Revision 4, dated November 29,2012- Aircraft Flight Manual Supplement FMS 6015, Revision 4 dated Jan 16,2013- Instructions for Continued Airworthiness 6015MM Revision 3, datedOctober 15, 2012- Per installationdrawing 6015, Revision 4 dated October 15, 2012- Per Enginee...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/09/2021	Active	10053726
10053732	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC ST01138CH	560XL	Air Ambulance Conversion	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 6050-XL-DL Revision 4 dtd. December 7, 2014Flight Manual Supplement FMS 6050-XL-FMS Rev. 4 dtd. 19.May 2014Instructions for Continued Airworthiness 6050-XLMM Rev. 3 dtd. April 7,2014or later revisions of the above listed documents approved by EASA ED Decisi...	-Per installation drawing 6050-XL, Revision 4 dated December 7, 2014-Per Engineering Substantiation 6050-XL-B Revision 2, dated August 19,2013-Per Airworthiness limitations in Instructions for ContinuedAirworthiness 6050-XLMM Revision 3, dated April 7, 2014-Per Aircraft Flight Manual Supplement FMS1...	23/04/2019	Active	10053732
10053763	AIRGLAS, Inc.		FAA STC SA02441AK	GA-8, GA-8-TC 320	Installation of 8.50" x 6", 6-ply nose tires utilizing an Airglas, Inc.part number PA32-206LA-GA8 Nose Fork Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Installation in accordance with: Master Data List, PA32-GA8LA, Rev C,dated August 14, 2014.Operation in accordance with: Flight Manual Supplement, PA32-GA8LA-FM,Rev (-), dated August 14, 2014.Instructions for Continued Airworthiness: Instructions for ContinuedAirworthiness including installation, ma...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/06/2015	Active	10053763
10053769	DISCOVERY AIR TECHNICAL SERVICES			G58	Installation – Intelligence, Surveillance and Reconnaissance (ISR)Special Mission System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Installation in accordance with Discovery Air Technical Services MasterDrawing List MDL13004 Revision A, dated 21 March2014.Operation in accordance with Discovery Air Technical Services FlightManual Supplement FMS13004-01 Revision NC, dated 25 April 2014.Instructions for Continued Airworthiness in...	None	22/06/2015	Active	10053769

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053781	DELTA ENGINEERING CORPORATION		FAA STC ST02652NY-D	777-200LR 777-200	Panasonic System 3000i In-Flight Entertainment System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DELTA ENGINEERING MASTER DATA LIST NO. 0143-06768-2215 REVISION J DATED02 JANUARY 2013	Approved configurations are TL10593-01<(>,<)> TL10593-02; TL10593-03 andTL10593-04.This STC includes activation of passenger seat Panasonic in-flightentertainment system (IFE) equipment. The conditions of activating theseat IFE is as follows:The seat IFE equipment as defined on Panasonic drawing IS6...	23/06/2015	Active	10053781
10053782	STIRLING DYNAMICS GMBH	REV. 4	FAA STC ST03682NY	737-400	Complete seat replacement to install Zodiac Dragonfly 31 Series Seats.Rev. 4: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Compliance Records 214210-C-CL-2520-001-02Master Document List 214210-C-DL-2520-001-02or later revisions of the above listed documents approved by EASASystem Description Doc. 214210-C-DE-2520-001-01Drawing Register Doc. 214210-C-DR-2520-001-01	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2022	Active	10053782
10053786	BELL HELICOPTER TEXTRON, Inc.		FAA SR09599RC	407	Radar Altimeter Antenna Mount KitInstallation of a High Frequency Antenna Kit P/N 407-007-001 for BellHelicopter Model 407.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement RFMS Document AA-12013 Rev. NR,Dated July 9th, 2012 or later revisions of the abovelisted documentsapproved by EASA in accordance with EASA EDDecision 2004/04/CF (orsubsequent revisions of this decision) and/ or the TechnicalImplementation Procedures of EU/ USAD...	The antenna is capable of interfacing with many differing types of HFradios; therefore, it is the responsibility of theinstaller to verifycompatibility of an HF radio installation with the 407-007-001 HFAntenna Kit and gain separate approval for the radio installation andEMI evaluation of the radio...	23/06/2015	Active	10053786
10053787	BELL HELICOPTER TEXTRON, Inc.		FAA SR03033NY	412EP	Left Hand Aft Equipment Shelf Kit P/N 412-340-001Installation of a L/H Equipment Shelf, in the left hand aft cargocompartment on Bell Helicopter Textron 412 EP helicopters.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Drawing List Document AA-10019 Rev. NRInstallation Instructions Document AA-10020 Ref. NRInstructions for Continued Airworthiness AIC Document AA-10018 Rev. NR.	The shelf is designed to carry a maximum weight of 100lbs (45.36kg).NOTE: After installation is complete, the aircraft should be weighed inaccordance with the applicable Maintenance Manual instructions andballast adjusted as necessary to return the helicopter empty weightCenter of Gravity to withinP...	23/06/2015	Active	10053787
10053788	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	MBB-BK 117 D-2	Scotland Air Ambulance, NVIS installation in accordance withBOND/MOD/110.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 29 Amdt 3 dated11/12/2012: 29.1, 29.21, 29.251, 29.301, 29.303, 29.305, 29.307, 29.321,29.337, 29.341, 29.351, 29.561,2...	Flight Manual Supplement FMS/110-002 Issue 1, dated 5 June 2015 or laterrevisions of the above listed documents approved by EASA.Design report DR/110-001 Issue 3 dated 22 June 2015Compliance Checklist for CS-29 CCL/110-03 Issue 1 dated 1 June 2015Compliance Checklist for NVIS CCL/110-04 Issue 1 date...	Minor Change Bond/MOD/099 and EASA STC 10052111 Rev. 2 (Aerolite EMSequipment) must be embodied prior to installation of this Design Change.Rotorcraft modified by this STC employsNight Vision Imaging Systemlighting, commonly named NVIS lighting, which has been certified toensure the aircraft is com...	23/06/2015	Active	10053788
10053795	BERINGER AERO	REV. 4		DA 42 NG DA 42 M-NG, DA 42 NG DA 42 M-NG DA 42 M DA 42, DA 42 M DA 42	Installation of RF-006(A) main wheel and RA-014(A) nose wheel withEA-003.7N(A) brake system on Diamond Aircraft DA-42 series.Revision 2: Nose wheel replacement, RA-014(A) supersedes nose wheelRA-002(B).Revision 3: Update with new servicinginstructions within ICA documentand addition of SensAIR devi...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification file: DM-MOD001-STC-013 Rev 00 dated 12 Oct. 2023;Instructions for Continued Airworthiness and Installation Instructionsfor BERINGER wheels and brakeson DA 42 aircraft: ICA-STC-013 Rev 04 dated 09 Aug. 2023or later revisions of the above listed document(s) approved/acceptedunder the EAS...	STC applicable only on Diamond Aircraft DA-42 models with MTOW equal orless than 1900 kg (i.e. not on DA 42 models withMÄM 42-678 and/or MÄM42-659 modifications installed).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyp...	13/10/2023	Active	10053795

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053796	ALPINE AEROTECH LP	REV. 1	TCCA SH96-82 ISSUE 2	212, 412, 412EP	Alpine Aerotech Ltd. Stiffener AssemblyInstallation of stiffeners to the firewall assembly in accordance withAlpine Aerotech , Ltd. Master Document List 191M-96-028-MDL Rev.NI.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Alpine Aerotech Ltd. Master Document List 191M-96-028-MDL Rev.NIAlpine Aerotech Ltd Illustrated Part Breakdown 191M-96-028-IPB ReV. NIAlpine Aerotech Ltd. Installation Instructions Document No. 191M-96-028-II, Rev.BAlpine Aerotech Ltd. Maintenance Manual Document No. 191M-96-028-MMS,Rev.NI.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/06/2017	Active	10053796
10053799	AVIONITEC AG			M20J	Avionics upgradeOut: Bendix/King dual KX 175; KMA 20; KN 72; KN 75; KEA 127; Garmin100AWD; GA 56; Skymap IIIC; Becker BXP 6403; Ameri King AK 451;Flightcom Intercom 403In: Garmin GTN 750; GNC 255A; GTX 330; GA 35; Artex ME 406 ACE; ACK A30; DAC Intern.GDC 31; PS Engineering PMA 8000BT; Garrecht TRXC...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-23 Initial Issue; 23.301, 561<(>,<)> 1301, 1309, 1321, 1325, 1327,1329, 1351<(>,<)> 1357, 1359, 1365<(>,<)>1381, 1431, 1...	AFM Supplement Power Flarm No. 5232-011 of 20.04.2014or later revisions of the above listed documents approved by EASA.Master Document List No. 5232-017 Rev. 0 of 03.04.2015Instructions for Continued Airworthiness No. 5232-015 of 20.04.2015	Limited to S/N 24-0775 HB-DFMPrior to installation of this design change it must be determined thatthe interrelationship between this change and any other previouslyinstalled design change will introduce no adverse effect upon theairworthiness of the product.	24/06/2015	Active	10053799
10053815	SCANDINAVIAN AVIONICS DESIGN ApS			S550 (CITATION S/II) 560XL 560 550 500	Upgrade from TCAS II Version 7.0 to TCAS II Version 7.1 on CessnaCitation Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt 4CS 25.1, CS 25.1301, CS 25.1309, CS 25.1501, CS 25.1529.CS 25.1581The requirements for environmental protection and the associatedcertified noise and/ or emiss...	Engineering Order & Certification Program - Doc ref: 2095388-EO, Issue 1dated 11 June 2015Technical Order - Doc Ref: 2095388-TO, Issue 2 dated 24 June 2015Compliance Record - Doc ref: 2095388-CR, issue 1 dated 29 April 2015Aircraft Flight Manual Supplement - Doc Ref: 2095388-AM A, Issue 2 dated24 Ju...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/06/2015	Active	10053815
10053816	AVIONICS SUPPORT GROUP, Inc.	REV. 1		A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-216/-231/-232/-233 A320-211/-212/-214/-215 A319-115/-131/-132/-133 A319-111/-112/-113/-114	Installation of Dual Astronautics Class 3 Electronic FlightBagsRevision 1 is a correction of the applicable models	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.CS-25 Amendment 16, pertaining to 25.29<(>,<)> 25.301, 25.305(a)(b)(1),25.307(a), 25.561<(>,<)> 25.601, 25.603, 25.605(a), 25.609, 25.611<(>,<)> 25.613, 25.771(a), 25.773(a), 25.777(a)(c)<(>,<)> 25....	-Master Data List, Aviation Support Group document No. 29106-MDL,Revision H<(>,<)> dated 24 October 2014-Instruction for Continued Airworthiness, Aviation Support Groupdocument No. 29106-ICA, Revision E, dated 10 October 2014or later revisions of the above listed documents approved by EASA inaccorda...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/01/2021	Active	10053816
10053827	LEARJET Inc.	REV.2	FAA STC ST02030LA	LEARJET 40/45	Installation of a Honeywell Automatic Dependent Surveillance Broadcast(ADS-B) Out system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02030LA.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Data List BAS45010024, Revision "B", dated 3 March 2014, FAAapproved 3 March 2014, or later FAA approved revision.Airplane Flight Manual Supplement BAS45040108 Revision NC,FAA approved3 March 2014, or later FAA approved Revision isrequired for the -1 & -2configurations.Airplane Flight Manua...	For the -1 Configuration: A prior or concurrent requirementfor thismodification is the installation of an approved Dual Universal AvionicsSystems Corporation (UASC) UNS-1Ew (WAAS) FMS with SCN 1000.5 and aHoneywell Enhanced Surveillance System for aircraft without HFcapability.For the -2 Configurat...	29/07/2021	Active	10053827

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053829	DASSAULT AIRCRAFT SERVICES (DAS)	REV. 5	FAA ST02969NY	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Validation of FAA STC ST02969NY.Installation of triple Honeywell International, Inc. Flight ManagementSystem (FMS) v6.1Upgrade.Revision 1: Correction of pre-requisite FAA STC number.Revision 2: Correction of STC Holder name.Revision 3: Correction of STC Holder address.Revision 4: Installation of du...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02969NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Data List, F9XW-D0004-005, Revision A, dated 3 September 2013,or later FAA approved revision.- Instructions for Continued Airworthiness (ICA) F9XW-D0004-155,Revision B, dated 2 July 2013, or later FAA accepted revision.- Airplane Flight Manual Supplement F9XW-D0004-150, Revision I/R, dated9...	The installation of the EASA STC 10051492 (validation of FAA STCST02967NY) for the installation of Honeywell GPS Landing System SensorUnit (GLSSU) is a pre-requisite for this design change.Prior to installation of this design change it must be determined thatthe interrelationship between this design...	26/02/2020	Active	10053829
10053830	ASI INNOVATION			B200	Retractable mast with relay antenna installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with ASI Innovation Master Drawing List refASI-MDL-0299 Rev 2, dated 02/06/2015 and Service BulletinASI-SB-B200-2300-0299 Revision 1, dated 01/06/2015.Operation in accordance with ASI Innovation Flight Manual Supplement refASI-AFM-0299 Rev 0, dated 11/05/2015.InstructionsI...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/06/2015	Active	10053830
10053831	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			650 (CITATION III, VI, VII)	Certification of P-RNAV capability of aircraft equipped with FlightManagement System Honeywell FMZ-2000	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List, Cessna Düsseldorf document No. 2014-15-16,Revision IR, dated 02 December 2014.- Airplane Flight Manual Supplement, Cessna Düsseldorf document No. 2014-15-8, Revision IR, dated 02 December 2014.or later revisions of theabove listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/06/2015	Active	10053831
10053841	DASSAULT AIRCRAFT SERVICES (DAS)	REV. 1	FAA ST02968NY	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Honeywell FMS CD-830 CTL Display UnitsRevision 1: Removal of existing Honeywell CD-810 or CD-820 ControlDisplay Units(CDUs) and replaced with Honeywell CD-830 CDUs.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List F9XW·D0022-005 Rev C, March 21, 2017Instructions for Continued Airworthiness (ICA) F9XW·D00022-155, Rev B,March 15, 2017Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	18/05/2020	Active	10053841
10053847	EIRTECH AVIATION SERVICES LIMITED	REV. 1		737-800	Approval for PED Operation on Boeing 737 Aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertificated noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MDL/688-099 Issue 05, FMS/688-015 Issue 03, GTR/688-016 Issue 03,MMS/688-020 Issue 01or later revisions of the above listed documents approved by EASA	Limited to B737-800 aircraft MSNs listed in FMS/ 688-015Prior to installation of this modification it must be determinedthatthe interrelationship between this modification and anyother previouslyinstalled modification and/ or repair will introduce no adverse effectupon the airworthiness of the prod...	09/07/2015	Active	10053847

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053848	BOLDER MANUFACTURING L.L.C.		FAA STC ST03471CH	767-300F 767-300	Installation of Galley A4 and F3	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List MDL-BM1410D01M1 rev. NCInstructions for continued airworthiness BM1410R55M1 rev NCWeight and balance supplement BM1410R63M1 rev NCor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2015	Active	10053848
10053856	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR00254AT	212/412/412EP	Quick Mount Kit for the Spectrolab Nightsun SX-16 Searchlight	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement AA-93027 revision Dor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.Drawing list...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2015	Active	10053856
10053859	ROEDER PRAEZISION GMBH	REV. 1		A320-214, A320-216	Activation of PED power system on Recaro 3520D seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Report A320-CR25-03-2015 Rev. 01, dated 26/06/2015Master Documentation List A320-MDL25-03-2015 Rev. 00, dated 26/06/2015;Instructions for Continued Airworthiness A320-ICA25-03-2015 Rev. 01,dated 26/06/2015;Aircraft Flight Manual Supplement A320-AFS25-03-2015 Rev. 00, dated27/05/2015;or...	None	15/06/2018	Active	10053859
10053886	AIR ALLIANCE GmbH			35, 35A	Installation of Iridium SATCOM Antenna to support SituationAwarenessTools	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Air Alliance, Instructions for Continued Airworthiness, 2015_001_LJ35_0507, rev 00, dated 24 June 2015or later revisionsof the above listed documents approved by EASA	None	01/07/2015	Active	10053886
10053887	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04196AT	767-300	Installation of an Interior Reconfiguration in a Boeing 767-300	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	HAECO Americas Cabin Solutions Master Data List 14T061L001 Revision Bdated 28 June 2015	None	01/07/2015	Active	10053887
10053890	AERODATA AG			CL-600-2B16	FMS Upgrade UNS-1B	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 1525.601; 25.771; 25.899; 25.1301;25.1302; 25.1309; 25.1329; 25.1353;25.1431; 25.1501; 25.1529; 25.1581; 25.1585The requirements for environmental protect...	Aerodata Airplane Flight Manual Supplement AFM-149 Rev 0or later revisions of the above listed documents approved by EASA.Aerodata Master Document List MDL-A/ C-870 Rev 2	None	01/07/2015	Active	10053890

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053893	BOGGI S.R.L.			AW139	Installation of Incubator Atom V808 on AW139 helicopter - change139P010-00	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 Amdt. 3 for changed partsThe requirements for environmental protection and the associatedcertified noiseand/ or emissions levels of the original product areunchange...	Flight Manual Supplement - 139P01000-RFMS-01, Issue 1Instructions for Continued Airworthiness - 139P01000-ICA-00 Issue 0or later revisions of the above listed documents approved by EASA.Master Document List 139P01000-Mdl-04, Issue 4Installation Service Bulletin 139P01000-SBT-01, Issue 1Master Drawin...	The installation of the KIT Aerolite P/N 139001-502 in accordance withthe STC 10016742 (short nose), or the KIT Aerolite P/N 139172-501/502 inaccordance with the STC 10017278 (long nose), are consideredprerequisites for the installation ofthe Incubator Change 139P010-00	01/07/2015	Active	10053893
10053896	BOGGI AERONAUTICS S.R.L.	REV. 2		MBB-BK117 D-3 MBB-BK 117 C-2, MBB-BK 117 D-2	Installation of Incubator ATOM V808 on MBB-BK117 C-2 and MBB-BK117 D-2helicopters, change 145P001-00. Variants MBB-BK117 C-2e and MBB-BK117D-2m are not eligible for this STC.Rev. 1 of this STC is including a new structural interface forincubator, P/N 145P001-10 and expand the type of cabin doorsconf...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS29 Amdt. 3 for theaffected areas. For the change 145P001-30(i.e. Rev. 2 of this STC), CS29 Amdt. 4 for the following re...	Initial issue for the change 145P001-00:Flight Manual Supplement 145P00100-RFMS-02, Issue 2.Instruction for Continued Airworthiness 145P00100-ICA-00, Issue 0.Rev. 1 for the change145P001-10:Flight Manual Supplement 145P00110-RFMS-01, Issue 1.Instruction for Continued Airworthiness 145P00110-ICA-00,...	Pre- requisites for the change 145P001-00:Rotorcrafts MBB-BK117 C-2 shall be equipped with kit sliding doorjettisonablein emergency, as ruled by the FMS 9.2-34 rev 2.1 and withKIT Aerolite P/N 145212-501.Rotorcrafts MBB-BK117 D-2 shall beequipped with kit sliding doorjettisonable in emergency, asM...	14/10/2022	Active	10053896
10053897	OGMA, INDUSTRIA AERONAUTICA DEPORTUGAL, S.A.	REV. 1		EMB-145MK, EMB-135LR EMB-145EU, EMB 145LU, EMB-145, EMB-145EP, EMB-145MP, EMB-135ER, EMB-145LR, EMB-135BJ, EMB-145ER	Installation of EFB mounting device. The installation as per this STCcan result in two configurations:A. Installation on the rod assembly of the cockpit LH or RHdirect-vision windows.B. Installation on the frame of the cockpit LH or RH direct-visionwindows.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	AFM Supplement (to Embraer AFM 145/1154, AFM 135/1283 and AFM 135/1541)ref. 13P07MS10210 initial revision, dated 14 October 2014. This AFMSupplement is applicable to the configuration of the EFB mounting deviceinstalled on the rod assemblyof the LH or RH direct-vision windows.AFM Supplement (to Emb...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/07/2015	Active	10053897
10053902	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Installation of TCAS 7.1 on A300-600ST fleet.The modification consists in:-,,Removal of current Collins TCAS TTR-920 standard 7.0 (P/N622-8971-322)<(>,<)>-,,Installation of new Collins TCAS TTR-921 standard 7.1 (P/N822-1293-332).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Transport International, Fiche de Modification, ST34MOD041, issueED01, dated 01 June 2015 or later revisions of the above listeddocuments approved by EASA.	None	02/07/2015	Active	10053902
10053904	LUFTHANSA TECHNIK AG			A380-841, A380-842, A380-861	LHT – A380 Installation of a Patient Transport Compartment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01 Installation of a Patient TransportCompartment (PTC) ; CRI H-01 – ICA on EWISThe requirements for environmental protection and the associate...	Supplemental Type Def.Doc. (STDD25-13/45M Iss.02 Rev.00)Compliance Record List (CRL25-13/45M - Iss.02 Rev.00)Instructions for cont. Airworthiness (A-00-15-24-ICA Rev.1.0)or laterrevisions of the above listed documents approved by EASA.Applicants Decl. of Compliance (ADoC3566 - updated with Rev.02)...	PFW STC 10051181 is a pre-requisite to install this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the...	02/07/2015	Active	10053904

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053922	DAO AVIATION A/S			PA-31, PA-31-300, PA-31-325, PA-31-350	Dual Garmin GNS 430 installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	DAO Aviation NS AFM-supplement DAD-DD-0518-AFMS-01 , signed2014-04-02,Rev IR.or later revisions of the above listed documents approved by EASA.DAO Aviation A/S, Design Order DAO-DO-0518 as defined in Master DatalistDAO-DO-0518-MDL-00, signed 2015-06-16.	None	13/07/2015	Active	10053922
10053925	AVM SOLUTIONS (KELOWNA)INC.		TCCA STC SA15-28	CL-215-6B11 (CL-415 VARIANT)	Universal Avionics System Corp. UNS-1Lw Flight management System.Installation/UNS-1Lw with LPV monitor, approved for en-route, terminaland non-precision approach use.Installation includes: CDU, NCU, LPV monitor, fuel flow converter, radiotuning unit, two GPS antennas and WX controller (FMS map range...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25.1316 Amdt. 14.The requirements for environmental protection and the associatedcertified noise and/ or emissions leve...	AFM Supplement A003-102-001-014.1 (approved data) or later revisions ofthe above listed documents approved by EASA in accordance with theTechnical Implementation Procedures of EU/Canada Bilateral Agreement.Project Description No. 208-50360-00-R00Airworthiness Compliance Plan No. 210-50360-00-R00Air...	See AFM Supplement A003-102-001-014.1 Limitation Section.	03/07/2015	Active	10053925
10053928	365 AEROSPACE DDS LIMITED	REV. 1		CL-600-2B16 CL-600-2A12 CL-600-1A11	SATCOM Antenna InstallationRev. 1: Transfer of STC from 365Aerospace Ltd. to 365 Aerospace DDSLtd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	365 Aerospace Ltd MDL-0024 Revision A dated 02 July 2015	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/08/2019	Active	10053928
10053931	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		SEE EASA APPROVED MODEL LIST	Introduction of the Smartcart Galley CartRev. 2: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS-25 Amdt 15CS 25.20, CS 25.21, CS 25.23, CS 25.25, CS 25.27, CS 25.29, CS 25.301,CS 25.302, CS 25.303, CS 25.305, CS 25.307, CS 25 321, CS 25.331, CS25.333,...	ATL Modification Summary Sheet MOD-12855-00001 Issue 5ATL Master Document List MDL-12855-00001 Issue 6 and all its referenceddocuments.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/11/2021	Active	10053931
10053932	DLR DEUTSCHES ZENTRUM FUERLUFT- UND RAUMFAHRT e.V.			A320-232	Operator seat double	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List ATRA-10108-11-09 Issue M, dated 18/12/2014Compliance Check List CCL-ATRA-MPL-12-02 Issue A, dated 17/12/2014Instructions for Continued Airworthiness ATRA-10108-11-16 Issue E, dated21/08/2014or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/07/2015	Active	10053932
10053948	AIRCRAFT INTERIOR REFURBISHMENT ESPANA S.L.	REV. 2		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Passenger Seating Replacement and In-Seat Power Supply System.Rev. 1 adds some models of the Airbus A319 series and A321 seriesaircraft to EASA STC 10053948.Rev 2: certificate transfer from Tenencia Ltd. to Aire S.L.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Report Modification TEN 774 issue 9;- AFMS TEN 774-47;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The following tests must be successfully carried out on each A319 andA321 Series First of Type installation:TEN 774-05TEN 774-11TEN 774-25.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change a...	13/06/2022	Active	10053948

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053951	FEDERATION FRANCAISE DE VOL A VOILE (FFVV)			SNC 34C	Method to install aileron hinge on Alliance 34 SN 34 C.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Bulletin de Service FFVV 012015 rev1 du 30 Juin 2015 or later revisionsapproved by EASA.	None	06/07/2015	Active	10053951
10053952	HELI AUSTRIA GmbH	REV. 2		412, AB412 412	HAU-D-010, Tarsyn and Heli Pilot relocationThis change moves the Tarsyn and Heli Pilot System including TerminalBlocks,Trim Computer into the nose compartment to reduce the requiredlead weights in the nose. No new equipment or functions implementedRev. 1 extends to all serial numbers of Model 412 a...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List, Doc. No. HAU-D-010-001, Rev. 2, dated01.10.2021Approved Model List, Doc HAU-D-010-AML, Rev. 0, dated 01.10.2021Installation Manual, Doc. No. HAU-D-010-004, Rev. 2, dated 28.09.2021Instructions for Continued Airworthiness, Doc. No. HAU-D-010-006, Rev.2, dated 28.09.2021Or later...	This STC is not applicable to helicopter Model AB412 EP.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the...	16/11/2021	Active	10053952
10053956	STANDARD AERO		FAA ST02911CH-D	G-IV	Installation of an Interior Reconfiguration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25 amdt. 11: 25.853(a)(c)(f).The requirements for environmental protection and the associatedcertified noise and/ or emi...	Master Data List 1019483 rev B dated Feb. 01, 2011AFM Supplement 1019803 rev A dated Feb 04, 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures o...	None	07/07/2015	Active	10053956
10053959	DELTA ENGINEERING CORPORATION		FAA STC ST02983NY	A330-201/-202/-203/-223/-243	Panasonic In-Flight Entertainment eX2 system installation on A330-200This modification installs Panasonic eX2 IFE providing audio, video andin-seat power supply system to the passengers for use in flight.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 at various amendments25.831 (Amdt 2); . 853 (Amdt 13); .869 (Amdt 4); . 981 (Amdt 13); .1307(Amdt 13); . 1351 (Amdt 13); .1353 (Amdt 2); . 1431 (Amdt 13); .1581 (Amdt13)...	Master Data List, ref. 0154-06966-2225 Revision H, dated 27August 2014Instruction for Continued Airworthiness, ref. 0754-06973-2225 RevisionD, dated 27 August 2014Aircraft FlightManual Supplement, ref. 0654-06972-2225, dated 11 May2011orlater revisions of the above listed documents approved by EA...	Depending on the various configurations supported by this STC, thefollowing modifications are prerequisites:1-Configuration TL10600-01 requires Lufthansa Technics STC, ref :STDD00-10/26M (EASA approval 10034892)2-Configuration TL10600-02requires Airbus Modifications 56228, and200867 (approved iaw...	07/07/2015	Active	10053959
10053970	SOMMER, MICHAEL			PA-28-180 (ARCHER)	Installation of DME KN62A and PMABOOOB for IFR operation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 amendment 3: 23.21, 23.773(a), 23.1301, 23.1309, 23.1321,23.1351(a)(d)(e)(f)(g), 23.1357, 23.1359, 23.1365, 23.1367, 23.1381,23.1431, 23.1529.The requirements for en...	Installation in accordance with: Change certification document for Piper28-180, Ref: OWNER- DECLP-01, dated 20/05/2015.Operation in accordance with Aircraft Flight Manual Supplement: 12.3.STC-OWNER-DECLP-01, dated 07/07/2015.or later revisions of the above listed documents approved by EASA.	Limited to serial number: S/N 28-4404	07/07/2015	Active	10053970
10053983	Q.C.M. DESIGN GmbH			CL-600-2B16 (604 VARIANT)	Change in Layout of Passenger Accommodation by relocation of a divan andan entertainment rack	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval .	ICA, Doc. No. B604-QCM25-011-M1-ICA, Initial Issue, dated 16th March2015or later revisions of the above listed documents approved by EASACompliance Report, Doc. No. CR-B604-QCM25-011, Rev. 2 Dated 7th July2015	Only valid for S/N 5602Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	08/07/2015	Active	10053983

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10053993	NORTHERN AVIONICS S.R.L.			AW109SP	Installation of Entertainment System CD/ DVD Player with dual 7" foldabledisplay, Drawing 23-NAV0493-00 SH 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement RFMS NAV0493, Rev. 0 orlaterrevisions approved by EASA.Instructions for ContinuousAirworthiness ICA-NAV0493, Rev. 0Compliance Check List CCL0493-001, Rev. 0Project Description NAV0493/1, Rev. 0Master Document List MDL0493, Rev. 0 (contains the Master Drawing Lis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/07/2015	Active	10053993
10053998	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		A330-300	Economy class seat installation for Cathay Pacific A330-300Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Summary, ref : N0495-D90 rev –Master Drawing List, ref : N0495-D10 rev CInstruction for Continued Airworthiness, ref : N0495-D70 rev Aor later revisions of the abovelisted documents approved by EASA.	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product2) This approval is limited to the following s...	13/07/2015	Active	10053998
10054000	AIRBUS S.A.S.			A319-115	Airbus Corporate Jet Modification CJ1900 VIP Project ”Candy”.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRIA-4301-019 Issue 1 “Certification basis for A319-115 MSN 5792”.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels...	Modification Approval Sheet CJ1900, Issue 1, dated 09/07/2015Airplane Flight Manual – AFM Supplement FM-S MOD CJ1900, dated01/07/2015Maintenance Planning Document – MPD SupplementMPD-S MOD CJ1900, dated01/07/2015or later revisions of the above listed documents approved by EASA.	This approval is limited to MSN 5792.	09/07/2015	Active	10054000
10054006	AVIATION SPECIALTIES UNLIMITED, INC		FAA SR01383SE	206L-1, 206L-3, 206L-4 206A, 206B, 206L	Installation of a supplemental NVIS lighting system .Validation of FAA STC SR01383SE	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	· Aviation Specialties Unlimited, Inc. Master Drawing List (MDL) MDL2060043, Revision CN, dated December 4, 2013· Instructions for Continued Airworthiness ICA2060044, Revision C, datedAugust 8, 2011· Rotorcraft Flight Manual Supplement No. FMS-206004-6 for Bellhelicopter Textron Model 206 Series roto...	- Compliance with EASA_AD_US-2012-12-11_1 is mandatory- It is recommended that first installation is made with support fromSTC holder- EASA must be notified at time of first installation for check ofdifferences of applicable configuration.EASA CRI F-01 on NVIS dated 25feb 2015 refers- Approval of t...	29/07/2015	Active	10054006
10054019	DOA21 LIMITED	REV. 2		A320-214	Introduction of VIP InteriorRev. 2: Transfer of STC holder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):D-02 Isolated CompartmentsD-05 Glass Screens of Displays/MonitorsD-06 ShowerInstallationDeviation (s):D-01 Installation of Interior Doors...	STC Twenty One Aeroplane Flight Manual Supplement S21.FMS-0120 Issue 2STC Twenty One Supplement Manual S21.TEC-0464 Issue 1, AirworthinessLimitations (Appendix A to Comlux Maintenance Planning DocumentSupplement PRM1-0000RM300 Revision IR)or later revisions of the above listed documents approved byS...	Any changes to the WLAN or interior layout approved under this designchange will require a re-examination to determine if the compliancedemonstration and/or the certification basis are still valid.Airworthiness approval of the Airborne Wireless Local Area Network(WLAN) does not constitute operationa...	24/10/2023	Active	10054019

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054037	LUFTHANSA TECHNIK AG			747-400	New Premium Economy Class (B747-400)In the main cabin of the main floor on the aircraft, the change consistof the removal of 10 per cent of the Economy Class Seats between door 2and door 3 and the installation of new developed Premium Economy Seatsinstead. The new seating will have a greater pitch a...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD25-13/40M issue1 rev 0- ICA, ref A-00-15/34-ICA, Issue 2 rev 0- ComplianceRecord List CRL25-13/40M iss 1 rev 0or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with :a) SB AIM B747-25-173 - Introduction of a three part class dividerinstallation(Minor Change ref MM 638-14)b) STC 10014325 (rev3 or later revision), Non Electric Floor PathMarking System, together wi...	14/07/2015	Active	10054037
10054041	LUFTHANSA TECHNIK AG			A330-300	New Premium Economy Class (A330-300)In the main cabin of the main floor on the aircraft, the change consistof the removal of 10 per cent of the Economy Class Seats between door 2and door 3 and the installation of new developed Premium Economy Seatsinstead. The new seating will have a greater pitch a...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD25-13/44M issue1 rev 1- ICA, ref A-00-15/36-ICA, Issue 2 rev 0- ComplianceRecord List CRL25-13/44M iss 1 rev 0or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with :a) SB AIM A330-25-050 - Introduction of a three part class dividerinstallation(Minor Change ref MM637-14)b) STC 10014507 rev2 (or later revision), Non Electric Floor PathMarking System, together wit...	14/07/2015	Active	10054041
10054053	BELL HELICOPTER TEXTRON, Inc.		FAA SR01921AT	212, 412, 412EP	Installation of Forward Mount for the (FSI) FLIR Systems, Inc. SAFIREImaging System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement AA-98161 No Rev or later revisionsof the above listed document approved by EASA in accordance with EASA EDDecision 2004/04/CF (or subsequent revisions of this decision) and/ orthe Technical Implementation Procedures of EU/ USA Bilateral Agreement.Installation inst...	Bell Model 212 rotorcraft is limited to day or night VFR operations.,,Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwort...	15/07/2015	Active	10054053
10054083	ROMTEX ANJOU AERONAUTIQUE S.R.L.			737-700, 737-800	B737NG Cabin Layout ModificationThe old seats have been removed, new BRICE seats have been installedwith increasing or decreasing passenger capacity. New class dividerinstallationon some MSNs. On the remaining MSNs, the existing classdividers have been relocated. PSU channel layouts have been modif...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissionslevels of the original product are unchanged and remain applicable tothis certificate/ approval.	DOA Technical Report: 02-100003-DOATR-001 revision 01(content equal to Certification ProgrammePlan)Master Document List:02-100003-MDL-001 revision 01For ICA §10 of Service Bulletins:02-100003-SB-001 revision 01 ; 02-100003-SB-002 revision 0102-100003-SB-003 revision 01 ; 02-100003-SB-004 revision 010...	STC limited to MSN 28982, 28984, 28985, 28986, 28988, 33062, 28980,28983, 28987, 33057<(>,<)> 28981, 33058, 33059, 33060, 33061, 33063,33064, 33065, 33066, 33067, 37718, 33068, 33069<(>,<)> 33070, 33071,33072, 33073, 33074, 33075, 36822, 36826, 36829, 36828, 36831, 33978,33979.Prior to installationt...	16/07/2015	Active	10054083
10054085	AVIONITEC AG			F260B	Avionics Upgrade1. List of removed units:Manufacturer ,,,,Unit Function ,,,,Unit NameBendix/ King ,,,,DME ,,,,,,KN 62ABendix/ King ,,,,NAV Indicator ,,,,KI 209Aeritalia ,,,,AirspeedIndicator RH ,, 8-133-006Aeritalia ,,,,Vertical Speed md. RH,,8-041-508-1Aeritalia ,,,,Altimeter RH ,,,,NS5F006-2Aerita...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 23 original issue: 23.301, 561, 1301, 1309, 1321, 1325, 1327<(>,<)> 1351, 1357, 1359, 1365,1381, 1431, 1529, 1541, 1581....	AFMS for dual Garmin GNS 530/430 system Doc. No. 1362-011 Rev. 1AFMS for Sandel EHSI SN4500 Doc. No. 2536-012 Rev. 15.12.2014AFMS for Sandel EADI SN4550 Doc. No. 2536-013 Rev. 15.12.2014AFMS for Avidyne TAS 615 Doc. No. 2536-014 Rev. 15.12.2014or later revisions of the above listed documents approve...	Limited to S/N 2-58, HB-KOYPrior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	23/07/2015	Active	10054085

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054089	I.S.E.I INTERNATIONAL SERVICESELECT RONIQUE INFORMATIQUE	REV. 2		S-76C	Installation of Flight Data Monitoring and Transmitting System HELICOMV2 NUM or HELICOM V2+ NUMRevision 1 to STC:Correction of Engine modelRevision 2 to STC:-,,Proposed additionallocations for the main device, GPS/ SAT/ GSMantennas and the Air/Ground sensor-,,Extension of applicability of system fo...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):SC F-01: Lithium Battery InstallationsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	Rotorcraft Flight Manual Supplement N11-S76C+ HV2 HV2+ NUM,Revision 04or later revisions of the above listed documentsapproved by EASA.-,,List of Documents N10-S76C+ HV2 HV2+ NUM, revision 06-,,Master Drawing List N12-S76C+ HV2 HV2+ NUM,Revision 05-,,Installation Instructions N7-S76C+ HV2 HV2+ NU...	For helicopters with engines Arriel 2S1 and with or withoutIIDS RDAUequipment installedPrior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effec...	08/12/2015	Active	10054089
10054105	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	A319-115	Activation of WAP and Media Servers	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Aeroplane Flight Manual Supplement S21.FMS-0118 Issue 1or later revisions of the above listed documents approved by EASA.STC TWENTY ONE MASTER DOCUMENT LIST No. S21.MDL-1216 ISSUE 2	1) The Airworthiness Approval of the wireless system does not constituteOperational approval for the use of transmitting Personal ElectronicDevices (PED's) on board of the aircraft. Operational Approval must beobtained from the responsibledivision of the operational authority ofthe aircraft's count...	17/07/2015	Active	10054105
10054122	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		ATP	Installation of a Five Panel Universal EFI-890R EFIS to BAESystems ATPSerial Number 2033.Major Change relates to extension of Approval Time Limit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 HIRFCRI H-01 Enhanced Airworthiness Programme for Aeroplane Systems (EAPAS)NEW-PAGEInstructions for Continued Airworthiness (ICA) on Electri...	Scandinavian Avionics Design Document 2093719-AM A, Approved AircraftFlight Manual Supplement, Initial, Issue 4 dated 22 June 2016.Scandinavian Avionics Design Document 2093719-AMC, Approved AircraftFlight Manual Supplement, Issue 3 dated22 June 2016or later revisions of the above listed documents...	1. Aircraft serial number 2033 only.2. Any proposed software changes to the EFIS and/or VISION-1 systemsmust be approved by EASA.3. This Approval is only valid until 16 July 2017.Prior to installation of this design change it must be determined thatthe interrelationship between this design change an...	06/07/2016	Active	10054122
10054139	HELIFAB Inc.d/b/a ARROW AVIATION CO. LLC			S-76A, S-76B, S-76C	Installation of a 62 Gallon Auxiliary Fuel Tank in the baggagecompartment in a Sikorsky S-76A, B & C Rotorcraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement, document N° HF-S76-FMS-2800-0004,Revision 0, dated February 06, 2014 or later revisions of the abovelisted documents approved by EASA in accordance with EASA ED Decision2004/04/CF (or subsequent revisions of this decision) and/ or theTechnical Implementation Pr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/07/2015	Active	10054139
10054157	SABENA TECHNICS BGC			EC 155 B, EC 155 B1	ADS-B OUT Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ROTORCRAFT FLIGHT MANUAL SUPPLEMENT N° 2037-01-A-2301-R00orlater revisions of the above listed documents approved by EASA.MASTER DATA LIST N° 2037-01-A-2103-R01COMPLIANCE RECORDS N° 2037-01-A-2104-R02INSTRUCTIONS FOR CONTINUED AIRWORTHINESS N° 2037-01-A-2211-R01	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/07/2015	Active	10054157

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054170	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04031AT-D	GV-SP	Installation of an APU Fire Bottle on GV-SP.This modification installs an active third fire extinguishing bottlededicated to the Auxiliary Power Unit (APU), together with thesupporting structure and plumbing line adaptations.Revision 1: FAA STC reference number corrected and update of thecompliance...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Index List, ref: CE514428002 Revision C, dated 29 September2015FAA Airplane Flight Manual Supplement, ref: CE51 442M001, dated 01October 2015Instructions for Continued Airworthiness, ref: CE51 442A001, dated 15December 2014or later revisions of the above listed documents approved by EASA inaccordan...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/03/2019	Active	10054170
10054173	SCANDINAVIAN AVIONICS DESIGN ApS			35A, 36, 36A, 55, 55B, 55C, 60 25C, 25D, 25F, 31, 31A, 35 24D-A, 24F, 24F-A, 25, 25B 24, 24A, 24B, 24B-A, 24D,	Upgrade from TCAS II Version 7.0 to TCAS II Version 7.1 on Learjet24/25/31/35/36/55/60 Series Aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 amdt 4 - CS 25.1,CS 25.1301, CS 25.1309, CS 25.1501, CS25.1529, CS 25.1581.The requirements for environmental prote...	Engineering Order & Certification Program - Doc ref: 2095389-EO, IssueD1 dated 30 April 2015Technical Order - Doc Ref: 2095389-TO, Issue 1 dated 30 April 2015Compliance Record - Doc ref: 2095389-CR, issue 1 dated 30 April 2015Aircraft Flight Manual Supplement - Doc Ref: 2095389-AM A, Issue 1date...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/07/2015	Active	10054173
10054177	AMAC AEROSPACE SWITZERLAND AG			737-900ER	Interior Re-Configuration / DX01-2500Reconfiguration of theMajlis as described in the Certification Plan,Doc. No. CP-DX01-2500, Rev. C, Dated 06.07.2015	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFMS, Doc. No. AFMS-DX01-2500, Rev. A, dated 03.07.2015 orlaterrevisions of the above listed documents approved by EASA.- Master Data List, Doc. No. MDL-DX01-2500, Rev. C, dated21.07.2015-ICA (without ALS), Doc. No. ICA-DX01-2500, Rev.A, dated 25.06.2015	Approval valid only for MSN 37560 - The installation of the EASA STC10041604 (EASA Project Number 0010008975-001) is aprerequisite for thischange.Prior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed...	23/07/2015	Active	10054177
10054178	LUFTHANSA TECHNIK AG	REV. 2		747-8	747-8 VIP cabin interior completionTwo configurations:- VIPpassengers-MedevacRev. 1: Replacement of conductive oxygenflex-hoses with non-conductiveonesRev. 2: Modification of the intrusion detection support structure	As per CRI A-101 issue 1 issued for project 0010016058; andCS 25.571amdt 19 for the area affected bySTC R2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approva...	- Supplemental Type Definition Document No. STDD00-12/20M, Issue 03 Rev01- Airplane Flight Manual Supplement Doc. No. A-00-12/49-AFM, Issue 03- Instructions for Continued Airworthiness Doc. No. A-00-12/49-ICA,Issue 05 Rev 00or later revisions of the above listed document(s) approved/ acceptedunder th...	- The airplane shall be operated only for private use.- As per AFM Supplement A-00-12/49-AFM section “Certificate Limitations”- As per ICA document A-00-12/49-ICA section 4.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyp...	21/01/2025	Active	10054178
10054184	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A300 B4-203	Airbus A300-203<(>,<)> TCAS Change 7.1 Upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 25 Amdt 2325.1309FAR 25 Amdt 5425.1529The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original productu...	Tenencia Ltd Modification TEN 765 Issue 1 and all its referenceddocuments	Applicable to aircraft serial number 255 onlyPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	23/07/2015	Active	10054184

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054195	ADAC LUFTFAHRT TECHNIK GmbH			MBB-BK 117 D-2	Installation of a Honeywell RDR-2000 Weather RadarNEW-PAGE	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-29,Amdt. 2 (not required by 21A.101)21<(>,<)> 29<(>,<)> 45<(>,<)> 64, 65, 141, 251, 601, 603, 605, 607, 609<(>,<)> 610<(>,<)> 611, 613, 631, 773, 1301, 1309, 1322, 132...	Rotorcraft Flight Manual Supplement EC14S-0410S-02S-MFS-00 Rev. 0 orlater revisions of the above listed documents approved by EASA.Master Document List EC145-04105-002-LMD-00 Rev.0 or later approvedrevisionsInstallation Instructions EC145-04105-004-DIN-01 Rev. 1 or laterapproved revisionsInstructio...	Prior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any other previously installed designchange and/ orrepairwill introduce no adverse effect upon the airworthiness of theproduct.	24/07/2015	Active	10054195
10054221	STEVE'S AIRCRAFT		FAA STC SA01026SE	SEE EASA APPROVED MODEL LIST	Installation of Improved fuel gascolator assembly.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Manufactured in accordance with Steve's Aircraft Master Drawing List 1/4NPT 3/8 line design dated, November 11, 2002 or3/8 NPT 1/2 Line Design,dated November 20, 2002.Installation in accordance with Installation Instructions and MasterDrawing List as defined in Approved Model List (AML)Instructions...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/07/2015	Active	10054221
10054222	STEVE'S AIRCRAFT		FAA STC SA01768SE	SEE EASA APPROVED MODEL LIST	Installation of Oil Cooler System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Installation Instructions and MasterDrawing List as defined in Approved Model List (AML)Instructions for Continued Airworthiness in accordance withICA Document3200-7-1, Rev IR, dated December 12, 2006.or later revisions of the above listed documents approved by EASAa...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/07/2015	Active	10054222
10054224	HELI AUSTRIA GmbH			MD900 (902 CONFIG.)	HAU-D013, Installation of Garmin G500H integrated flight deck into MD 900 series aircraftInstallation of the following equipment: Display (GDU 620), AttitudeHeading and Reference System (GRS 77H AHRS), Magnetometer (GMU44), AirData Computer (GDC 74H), OAT Probe (GTP59), Radio Altimeter (GRA 5500),Si...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS, Annex I to ED Decision 2013/031/RCS ACNS.B.VCS.001, CS ACNS. B.VCS.010, CS ACNS. B.VCS. 020,CS ACNS. B.VCS.025, CS ACNS. B.VCS.030, CS ACNS. B.VCS.040The requireme...	Flight Manual Supplement, Doc. No. HAU-D-013-005, Rev. 0 dated26-05-2015 or later revisions of the above listed documents approved byEASA.Master Document List, Doc. No. HAU-D-013-001, Rev. 0, dated 26-05-2015Compliance report, Doc. No. HAU-D-013-003, Rev. 0, dated 26-05-2015Installation Manual, Doc....	Limited to VFR operation. Installation is not NVIS approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of...	27/07/2015	Active	10054224
10054235	JAMCO AMERICA, INC.		FAA STC ST01891SE-D	777-200	Installation of an interior reconfiguration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 13 pertaining to 25.571(a)(b)(c), 25.853(a)(d)(e)<(>,<)>25.1353(a)(b)(d), 25.1431(a)(c)(d)<(>,<)> 25.1447(a)(c)(1)(4)The requirements for environmental prote...	-Master Drawing List, Jamco America, Inc. document No. MDL1477-1,Revision J<(>,<)> dated 24 May 2011.-Instructions for Continued Airworthiness, Jamco America, Inc. documentNo. ICA1477-1, Revision B, dated 28 February 2010or later revisionsof the above listed documents approved by EASA inaccordancet...	EASA validated FAA STC ST02652NY-D, installation of an in-flightentertainment system, must be installed concurrently with this STCPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and...	28/07/2015	Active	10054235

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054256	TUI AIRLINES BELGIUM N.V.	REV. 1		737-800	Installation of IFE serverRev. 1: Modification of system operational limitation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amendment 12; refer to Certification Plan JAF-DOA-CP-44M-0002 Rev.00 for list of specific paragraphs.The requirements for environmental protection and the associatedc...	Master Data List / JAF-STC-0001-0001 Rev. 01AFM Supplement / AFMS-JAF-DOA-44M-0001 Rev. 01Instructions for Continued Airworthiness / JAF-DOA-ICAR-44M-001 Rev.01or later revisions of the above listed documents approved by EASA	The wIFE system cannot be used during low visibility operationsPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness...	08/07/2016	Active	10054256
10054275	AIRBORNE MAINTENANCE ANDENGINEERING SERVICES, Inc. (AMES)		FAA STC ST03440CH	767-300 767-200	Relocation of the Auxiliary Power Unit (APU) Electronic Control Unit(ECU) from the E6 rack in the Aft Equipment Center (AEC) to the E2 rackin the thermally-controlled Main Equipment Center (MEC)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 47094MDL01 rev A dated March 26, 2015orlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/07/2015	Active	10054275
10054280	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			DHC-8-301/-311/-314/-315 DHC-8-102/-103/-106	Introduction of TCAS II Version 7.1 on DHC-8-100/300 Series	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation must be in accordance with MEDAVIA Service BulletinMODE00142_SB.Operation must be in accordance with MEDAVIA AFM SupplementMODE00142_AFMS.Continued Airworthiness unchanged in accordance with OEM ICA.or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/08/2015	Active	10054280
10054286	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST03171NY	A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-243 A330-201/-202/-203	Installation of a Bruce Aerospace Cabin lighting system.This STC installs new cabin lighting, ceiling and sidewall, with LEDmodules which require less power. These lights are for generalillumination and provide no emergency lighting. They require power andinterface with a new control panel to allowt...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List, ref: 0154-08495-2347 Revision F,dated 30 March 2016Delta engineering Instructions for Continued Airworthiness, ref: 0754-08496-2347 revision C, dated 20 Nov. 2015or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/10/2016	Active	10054286
10054289	AEROCLUBUL ROMANIEI			IS-28B2	Replacement of the lifetime limitation of 35 calendar yearsbyperiodical inspections.Structural soundness with respect to corrosion was addresses by alifetime limitation of 35 years. The limitation is replaced byinspections outlined in SB IS-28B2/EO-26 at short intervals.The lifetime limitation addr...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight and Maintenance Manual issue 2A, replacement of pages2.2.D, 2.3.C, and 26.2D at revision 27, dated Mai 2015;Aircraft Flight and Maintenance Manual issue 3, replacement of pages0.2.4.C, 0.3.Z.1.C, and 6.10.F at revision 41, dated Mai 2015;or later revisions of the above listed documen...	Installation of this modification by third persons is subject to writtenpermission of the approval holder and disposal of the approveddocumentation.	04/08/2015	Active	10054289

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054304	DELTA ENGINEERING CORPORATION			A321-213, A321-231, A321-232 A321-131, A321-211, A321-212 A321-111, A321-112 A320-231, A320-232, A320-233 A320-211, A320-212, A320-214 A319-132, A319-133 A319-114, A319-115, A319-131 A319-111, A319-112, A319-113	Installation of a Bruce Aerospace Cabin lighting system.This STC installs new cabin lighting, ceiling and sidewall, with LEDmodules which require less power. These lights are for generalillumination and provide no emergency lighting. They require power andinterface with a new control panel to allowt...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List, ref : 0164-09071-2372 Revision E,dated 20 April 2015Delta engineering Instructions for Continued Airworthiness, ref :0764-09072-2372 revision C, dated 15 April 2015Bruce Aerospace Weight & Balance reports :- ref : 351-826 Revision B, dated 28 November 2014 – for c...	None	05/08/2015	Active	10054304
10054305	365 AEROSPACE DDS LIMITED	REV. 2		757-200	Installation of a Controller Pilot Data Link Communications(CPDLC)SystemRev. 1: corrects Limitations on this certificateRev. 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 1525.301<(>,<)> 25.303<(>,<)> 25.305<(>,<)> 25.307<(>,<)> 25.365<(>,<)>25.561<(>,<)> 25.571<(>,<)> 25.581<(>,<)> 25.601<(>,<)> 25.603<(>,<) >25.605<(>,<)> 2...	-365 Aerospace Ltd Flight Manual Supplement No. 1, FMS-0006-001 Issue 3to B757 Flight Manual Reference No. D631N005-365Aerospace Ltd Instructions for Continued Airworthiness, paragraph4.2 Airworthiness Limitations, ICA-0006-001 Revision Bdated 27 July2017or later revisions of the above listed docu...	1. Boeing 757-200 aircraft must have skin configuration 143N3121-4 atthe GPS antenna location as defined by Boeing drawing 143N3121.2. Each Boeing 757-200 aircraft, by serial number, must have a specificDeclaration of Design and Performance document calling up the necessaryEmteq documents.Prior to i...	05/08/2019	Active	10054305
10054306	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A340-313 A340-312 A340-311	Cabin Interior Reconfiguration of Lufthansa Airlines Aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0498-D90, Revision -, dated 2 August 2015.- Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0498-D70, Revision A, dated 5 June 2015or later revisions of the above listed documen...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/08/2015	Active	10054306
10054313	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BAE 146-300 BAE 146-200 BAE 146-100 AVRO 146-RJ85 AVRO 146-RJ70 AVRO 146-RJ115 AVRO 146-RJ100	TCAS II Version 7.1 Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Tenencia Ltd Modification TEN 784 Issue 1 and all its referenceddocuments	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/08/2015	Active	10054313
10054319	ACC COLUMBIA Jet Service GmbH	REV. 3		LEARJET 31A	Upgrade TCAS II to ACAS II Change 7.1 for AlliedSignal Bendix King CAS67.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Airplane Flight Manual Supplement, LR31-15003-800-MF-0, Revision 0,dated 17 July 2015.2. Instruction for Continuous Airworthiness, LR31-15003-850-MI-0,Revision 0, dated 17 July2015.3. Master Document List, LR31-15003-050-LP-0, Revision0, dated 30 July2015or later revisions of the above listed d...	Prerequisite is STC ST00346WI (LBA validated as EMZ TA0340).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the pro...	26/01/2022	Active	10054319

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054346	BOMBARDIER Inc.			CL-600-2B16 (604 VARIANT)	Challenger 604 variant – Installation of SAT AFIS Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ACS Ltd Modification Data Summary : E942000 Rev A- Mandatory Maintenance Manual Supplement : DMM-5340-4001-MMMS Rev NC- Instruction for Continued Airworthiness : DC-5340-4001-IFCA Rev NCor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation...	Applicable only For CL604 Aircraft Serial No. 5628 and 5630.Refer to Limitation section of the approved Mandatory Maintenance ManualSupplement (MMMS).	06/08/2015	Active	10054346
10054351	INNOVATIVE SOLUTIONSAND SUPPORT, Inc.	REV. 4	FAA ST00354BO	757-200, 757-300 757-200, 757-200PF, 757-300	Installation of an Innovative Solutions & Support (IS<(>&<)>S)Integrated Standby Unit (ISU), Part Number 9D-80190-7, loaded with toplevel software 7H-80190-33.Rev. 2 clarifies thescope, operational and maintenance conditionsassociated to aeroplanes.Rev. 3 adds the model 757-200PF.Rev. 4 corrects ty...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments:CS 25 Amendment 17 pertaining to 25.1 (b), 25.21(a)(1), 25.29, 25.301(a), 25.303, 25.305(a)(b), 25.307(a), 25.365(a)(b)(c)(d),25.561(a)(b)(3)(c)(d), 2...	- Aircraft Flight Manual Supplement (AFMS) Document ID-12319, Revision3, dated 10 February 2021- IS<(>&<)>S Master Document List (MDL) Document ID-12303, Revision 9,dated 08 February 2021- IS<(>&<)>S Instructions for Continued Airworthiness (ICA) DocumentID-12304, Revision 4, dated 08 February 2021-...	- Refer to FAA Advisory Circular (AC) 20-188 for compatibility of thisdesign change with previously approved modifications.- IS<(>&<)>S ISU, Part Number 9D-80190-7, loaded with top level software7H-80190-33, is defined as: Article Part Number,,,,,,,,Article Description9D-80190-7 w...	23/03/2021	Active	10054351
10054353	JET AVIATION AG			MYSTÈRE-FALCON 900 MYSTÈRE-FALCON 50	ACAS II upgrade to software version 7.1Out: Honeywell TPA-81A P/N 066-50000-2320 or TPA-100A P/ N940-0300/0400-001In: Honeywell TPA-100B P/N 940-0351/0451-010	The Certification Basis (CB) for the original product remains applicableto this cedificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM supplement DOC.No.:JBSL-M-00466AFM-01 Issue 1 of 16.07.2015or later revisions of the above listed documents approved by EASA.MASTER DATA LIST Doc. No.:JBSL-M-00446MDL-01 Issue1 of 06.08.2015Instructions tor Continued Airworthiness Doc. No.:JBSL-M-00446ICA-01Issue 1 of 17.07.2015	MF900 & MF50 aircraft with prerequisite:ACAS II compliant TCAS Honeywell TPA-81A or TPA-100A and EHS and/ orADS-B compliant SSR ATC transponders and Altitude data not providedthrough Gray (Giliham) coding.Prior to installation of this design change it must be determined thatthe interrelationship betw...	07/08/2015	Active	10054353
10054364	PMV ENGINEERING			A340-311/-312/-313	In Flight Entertainment (IFE) system installation and Cabininteriormodification on A340.This modification deals with the installation of the Zodiac InflightInnovations IFE system(Rave) and cabin interior upgrade (rearrangementand modification of B/C seats and replacement of Y/C seats) on A340aircr...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR25 Change 15 (Refer to PMV document. Ref : SCA-00300-CIR-R02 for the detailedaffected requirements)The requirements for environmental protection and the associatedcerti...	PMV Master Document List, ref : SCA-00300 rev 01, dated 06 August 2015PMV Instruction for Continued Airworthiness :- associated to A340 ZII IFE Installation, ref: SCA-00300-ICA, dated 21May 2015-associated to A340 Cabin modification, ref: CAB-00900-ICA, dated 09January 2015-associated to A340 SICMA M...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/08/2015	Active	10054364
10054379	HELIFAB Inc.		FAA STC SR09626RC	S-76A, S-76B, S-76C, S-76D	Installation of an aft cabin area Storage Net in accordancewith HelifabInc., installation drawings document list HF-S76-IDL-2550-0002, RevisionE, dated January22, 2014	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement, Helifab Inc. Document No.HF-S76-MD-2550-0002, Rev. IR, dated September 14, 2012.- Installation drawing and documents list HF-S76-IDL-2550-0002, Rev E,dated January 22, 2014.or later revisions of the above listed documents approved by EASA inaccordance with EASA...	S-76 D through S/N 761036Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	10/08/2015	Active	10054379

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054380	HELI-ONE		TCCA STC SH08-58	S-76A, S-76C	CPI-503 Automatic Deployable ELT InstallationNEW-PAGE	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Heli-One Canada Aircraft Flight Manual Supplement No. CHS76-25-091 FMSRevision - dated 24 July 2015or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Heli-One Approval Control Document No. CHS76...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/08/2015	Active	10054380
10054382	ASI INNOVATION			ERJ 170-100 STD	Embraer 170-100 Cabin Modification (dual class 68 passengers)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Data List ref. ASI-SDL-0267-02, dated 07/08/2015or later revisions of the above listed documents approved by EASA.	Applicability limited to ERJ 170-100 STD model, S/Ns 23 & 27	10/08/2015	Active	10054382
10054393	E A D AEROSPACE AIRWORTHINESS	REV. 6		A321-251N/-253N/-271N/-272N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-251N/-271N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Transmitting Portable Electronic Devices (T-PED) tolerancedemonstration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List, EAD Aerospace document No. 01469-EAS-C-MDL,Revision B, dated 7 March 2018.- Instructions for Continued Airworthiness, EAD Aerospace document No. 01469-EAS-C-ICA-01, Revision A, dated 26 February 2018- Aircraft Flight Manual Supplement, EAD Aerospace document No.01469-EAS-A-AFM-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/03/2018	Active	10054393
10054395	PMV ENGINEERING			A319-115	Venue IFE installation on A319CJ	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-118 "Glass Screens of Displays / Monitors"The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pr...	-Master Document List SCA-00500-MDL-R00 dtd. 10. August 2015-Aircraft Flight Manual Supplement SCA-00500-AFMS-R00 dtd. 13 April 2015-Instructions for Continued Airworthiness SCA-00500-ICA-R00 dtd. 03 June2015-Master Minimum Equipment List Supplement SCA-00500-MMELS-R00 dtd. 28July 2015or later revis...	Limited to MSN 2592EASA STC IM.A.S.01793 (validated FAA STCST10546SC) needs to beinstalled prior to this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will int...	11/08/2015	Active	10054395
10054396	SABENA TECHNICS BGC	REV. 1		ATR 72-212/-212A ATR 72-101/-102/-201/-202/-211 ATR 42-200/-300/-320/-400/-500	TCAS 7.1 system upgrade on ATR 42 & ATR 72The modification consists in the software upgrade from TCAS Version 7.0functionality to Version 7.1 functionality.For aircraft fitted with the Rockwell Collins TCAS TTR-920 model, thephysical replacement of the unit is performed (due to a lack of memoryprovi...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:-Special Condition (s):F-1000-004: HIRF Protection-The following paragraph(s) at a later amendment:CS-25 Amdt 4 (Refer to Aeroconseil Certification Plan, ref:0665-01-A-CP-R...	- Aeroconseil Instruction for Continued Airworthiness, ref :0665-01-A-ICA-R02-Aeroconseil Aircraft Flight Manual Supplement, ref : 0665-01-A-AFMS-R02or later revisions of the above listed documents approved by EASA.- Aeroconseil Weight andBalance Analysis, ref : 0665-01-A-WBA-R01- Aeroconseil Maste...	This STC is not valid for the ATR 42-500 ‘600 Version’ and ATR 72-212A‘600 Version’ (refer to EASA TCDS EASA.A.084)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair wil...	26/06/2017	Active	10054396

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054416	AEROTEC & CONCEPT	REV. 2		A320-200 AND A321-200	Airborne wireless platform activation on A320/A321Rev1: technical documentation updated for ICARev 2: Gate to Gate operability with Wifi activated	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25 at amdt. 15:25.1301, 25.1309, 25.1353, 25.1431, 25.1529,25.1581, 25.1585.The requirements for environmental protecti...	Master Data List AE14263MDL rev 3 dated 23 Mar 2016AircraftFlight Manual Supplement AE14263AFMS issue 3 dated 21 Mar 2016Instructions for Continued Airworthiness AE14263ICA issue2 dated 20 Nov2015or later revisions of the above listed documents approved by EASA.	As per AFMS:- ” WiFi system is prohibited to work and must be switched OFF duringrefueling and Low Visibility Approach Operation, use “WIFI ON/ OFF”pushbutton located on CCP in theFWD face of the first R/H Overhead Bin”and- “TPEDs (including GSM personal devices) are prohibited to work andmust be sw...	21/04/2016	Active	10054416
10054417	HARTZELL PROPELLER LLC	REV. 1	FAA STC SE03232CH	SEE FAA AML SEE EASA APPROVED MODEL LIST	Engine Preheat Kit- EASA Validation of FAA STC SE03232CH Installation ofEngine Preheat Kit, p/n TSP4CYL-2925-115 for 115 volt applicationRev. 1: changes the EASA Design Approval Holder’s name and address fromthat for Tanis Aircraft Products (“Tanis”) to those for Hartzell. Tanispart and drawing numb...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Engine Preheat Kit drawing TA2925-1 Revision F, dated 6 March 2023<(>,<) >Preheat Kit Installation Instruction TNP2925 Revision E, dated 12 April2019<(>,<) >Instructions for Continued Airworthiness (ICA) document TCA 1000Revision D, dated 7 August 2023, and Operating Guide document TPG 1000Revisio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for engine types and models ap...	17/01/2024	Active	10054417
10054420	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINE S.A.R.L.			PA-32-300 (CHEROKEE SIX 300)	4481/14 Rev1 dated 04 May 2015 - installation avionique avec privilegeRNAV-5	CS23 amdt 3 and CS-ACNS initial issue as defined in SEAM 4481 CSP Rev1The requirements for environmental protection andthe associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SEAM 4481 SDL Rev 1 du 04/05/2015SEAM 4481 Supplement Manuel de Vol Rev 1 du 04/05/2015or later revisions of the above listed documents approved by EASA.	Limitation to Piper Aircraft PA32-300 serial number 76-80224	12/08/2015	Active	10054420
10054422	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09606RC	429	Installation of Retractable Hardpoints System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List, Report No. AA-13052, Rev. C, dated September 30,2014Rotorcraft Flight Manual Supplement, Report No. AA-13058, No Revision,dated November 24, 2014Instructions for continued airworthiness, Report No. AA-13056, NoRevision, dated August 28, 2014or later revisions of the above listed...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/08/2015	Active	10054422
10054423	LUFTHANSA TECHNIK AG	REV. 1		MD-11, MD-11F	TCAS Change 7.1Replacement of the TCAS II computer with software version 7.0 currentlyinstalled on Lufthansa German Airlines (DLH) MD11 aircraft by a newgeneration TCAS II computer with software version 7.1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplement Type Definition Document STDD34-14/20M, Issue 1,Revision 0(2015-07-17) Certification Program - CP34-14/20M, issue 1, Revision 1 (2014-12-12) Compliance Record List – CRL34-14/20M, Issue 1, Revision 0 (2015-07-17) Instructions for Continued Airworthiness - A-00-14/55-ICA, Issue 1,Revision 0A...	None	19/08/2015	Active	10054423

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054430	SCANDINAVIAN AVIONICS DESIGN ApS			ATR72-212/212A ATR72-101/201/202/211 ATR42-200/300/320/400/500	ATR aircraft – Installation of provision for portable Electronic FlightBag (EFB) with wireless connectivity and optional surveillance camerasystemThe installation provides, as a baseline, the provision for Portable EFBTablet Displays in the cockpit on both pilot sides, including two windowmounts, on...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-25amendment 4, for all applicable requirements, as an elect to comply. Therequirements for environmental protection and the associated certifiednoise and/ or emissions...	Airplane Flight Manual Supplement for Portable EFB , ScandinavianAvionics document 2084240-AM A issue 2Airplane Flight Manual Supplement for Surveillance Camera System,Scandinavian Avionics document 2084240-AM B issue 1Instructions for Continued Airworthiness for Portable EFB, ScandinavianAvionics d...	1. Only products that meet the Aircraft configuration specified inScandinavian Avionics Engineering Order 2084240-EO (chapter 4) can bemodified with this STC; ATR 42-500 '600 version' and ATR 72-212A '600version', with "New Avionics Suite", are not eligible for thisinstallation. The optional Surveil...	14/08/2015	Active	10054430
10054432	DOA AESGLOBAL LIMITED	REV. 1		757-200, 757-200PF, 757-300	Introduction of ACAS II v7.1 to B757 AircraftRev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-25 Amendment 14 -25.301, 25.303, 25.305, 25.307<(>,<)>25.601, 25.609, 25.611, 25.613, 25.619, 25.625, 25.899, 25.1301,2...	Aerospace Engineering Solutions Airplane Flight Manual Supplements AESAFMS Nr 65 Issue 2andAES AFMS Nr 69 Issue 1or later revisions of the above listed documents approved by EASA.Aerospace Engineering Solutions Master Document ListAES-757-3110 MDL Issue 4.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/04/2021	Active	10054432
10054433	HARTZELL PROPELLER LLC	REV. 1		SEE FAA AML SEE EASA AML	Installation of Engine Preheat Kit, p/n TA2927-1 for 115 voltapplication, in accordance with Engine Preheat Kit drawingTA2927-1,Revision G, dated 6 March 2023, andPreheat Kit Installation Instruction TNP2927, Revision G, dated 12 April2019<(>,<)>Installation of Engine Preheat Kit, p/n TA2927-2 fora...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness (ICA) document TCA1000,Revision C, dated 5 October 2022, andOperating Guide document TPG1000, Revision E, dated 29 October 2020<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Im...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/01/2024	Active	10054433
10054440	AMES - AEROSPACE AND MECHANICALEN GINEERING SERVICES ING. WALTERSTARZACHER GesmbH			A330-243	AZUL - A330 Cabin ReconfigurationThe modification covers seat replacement and redistribution and includescabin upgrade on several Airbus A330-200.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AMES Engineering Order, ref: EO_M24200101_MZI_1509 2014, dated 14 August2015AMES Instruction for Continued Airworthiness, ref:ICA_M24200101_MZI_1 5092014 rev 4, dated 07 August 2015or later revisions of the above listed documents approved byEASA	1. This modification must be installed in conjunction with the followingreferences :a) Airbus Modification 205041D63138.b) EASA STC No. 10014507 rev 2c) EASA approval of Project No. 0010037133 (EASA Validation of FAAProject no. ST14783AT-T).2. Monitors and components of the IFE System, including In-...	17/08/2015	Active	10054440
10054441	ALAMO ENGINEERING GmbH	REV. 2		CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700/701/702) CL-600-2B19 (RJ SERIES 100) CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	TCAS Change 7.1 Upgrade.Rev. 2: transfers the STC from "Deutsche Aircraft GmbH" to "AlamoEngineering GmbH".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	328 Design GmbH Aircraft Flight manual Supplement No.HBKAFMS010C344Z0001 Issue A<(>,<)>or later revisions of the above listed documents approved by EASA.328 Design GmbH Master Document List No. MDL076Z0001 Issue A.	None	18/12/2023	Active	10054441

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054444	SCANDINAVIAN AVIONICS DESIGN ApS			ATP	ATP aircraft - Provision of dual portable Electronic FlightBag (EFB)The installation of the EFB provision comprises of2 window mountsconsisting of a swivel and a tablet holder, 2 EFB control panels, onedata integration centre and 2 C/B'sfor 28VDC to the EFB systems.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:Asan elect to comply, CS-25 amendment 4, for all applicablerequirements, except for 25.341 and 25.561 as documented by JAR...	- Airplane Flight Manual Supplement for Dual Portable Electronic FlightBag (EFB) Provision, Scandinavian Avionics document 2091420-AM A, issue2- Instructions for Continued Airworthiness for Provision for dualportable EFB, Scandinavian Avionics document 2091420-CA, issue 1or later revisions of the ab...	The content of this STC is a full mechanical, electrical and functionalprovision of a dual Portable EFB System. The installation of theportable parts of the EFB System may only beperformed if the operatoris granted an operational approval (as applicable).Prior to installation of this design changet...	17/08/2015	Active	10054444
10054449	AEROTEC & CONCEPT	REV. 1		1900D	P-RNAV & LPV equipment installation in Beech 1900D.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of AEROTEC modification No 15071 in accordancewith AEROTECMaster Drawing List ref AE15071MDL, Rev 4, dated 18/12/2017.Operate in accordance with AEROTEC Flight Manual Supplement refAE15071AFMS, Rev 3, dated 15/11/2017.Instructions for Continued Airworthiness in accordance with AEROTECr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/12/2017	Active	10054449
10054450	DUNCAN AVIATION, INC.		FAA STC SA01760WI	EMB-505	Installation of an Aircell Universal Cabin System (UCS) 5000 withWireless local Area Network (WLAN).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Duncan Aviation, Inc, Master DocumentList, Document No CERTDOC-0000001789, Revision A, dated 01 August 2014.Operate in accordance with Duncan Aviation, Inc, Flight ManualSupplement, Document No EDOC-0000017304, Revision A, dated 01 August2014.or later revisions of the...	This Design Change is only applicable to Embraer EMB-505 aircraft withexisting Aircell Gogo Biz system installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willa...	18/08/2015	Active	10054450
10054451	DUNCAN AVIATION, INC.		FAA STC SA01789WI	EMB-505	Installation of "Quasar II" Cabin Lighting with eConnect and NoiseMitigation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:FAR 23.856 Am 23-62The requirements for environmental protection and the associatedcertified noise and/ or emissions levels...	Installation in accordance with Duncan Aviation Master Document List refEDOC-018233, Rev A, dated 22 June 2015.Maintainin accordance with Duncan Aviation Instructions for ContinuedAirworthiness (ICA) ref EDOC-018321, Rev A. or later revisions of the above listed documents approved by EASA inaccorda...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/08/2015	Active	10054451
10054475	ECMS AVIATION SYSTEMS GMBH	REV. 4		MBB-BK117 D-3, MBB-BK117 D-3M MBB-BK 117 D-2M MBB-BK 117 D-2 MBB-BK117 C-2, MBB-BK117 D-2 MBB-BK 117 C-2E MBB-BK 117 C-2	EAD03 External loads system for NHEC and HEC operationsRevision 2:- Introduction of a shelf-life definition in the AirworthinessLimitation Section of the Instructions for ContinuedAirworthiness (Component maintenance manual).- Minor editorial corrections of the Component maintenance manual.Reason fo...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Initial issue:Flight Manual supplement EAD03_RFMS_EASA, Rev. 0 dated 1 May 2015Airworthiness limitation section as per the Component Maintenance ManualChapter 11, Original Issue dated 6 August 2015Equipment and configuration list EAD03_ECL, Rev. 1 dated 11 August 2015List of certification documents2...	No Personnel Carrying Device System (PCDS) is considered within thisapproval.A separate airworthiness approval for PCDSis needed for HEC operationusing complex PCDS.Installation of the EAD03 external load system to a MBB-BK117 D-3 andD-3musing RIA04 / FIA04 adapters is only possible if D-2 style f...	18/12/2024	Active	10054475

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054487	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		U206F, U206G, 206 U206B, U206C, U206D, U206E TU206E, TU206F, TU206G TU206B, TU206C, TU206D TP206D, TP206E, TU206A TP206A, TP206B, TP206C P206, P206A, P206B, P206C P206D, P206E, U206, U206A	Installation of 3-blade constant speed propeller MTV-9-D/200-58 onTextron Aviation Inc. Models 206, U206, U206A throughG, P206, P206Athrough E, TU206A through G and TP206A through E.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS-36, Amendment 4.FAR 36, Amendment 36-30.This certificate/ approval involves a change to the requirements forenvironmenta...	According to MT-Propeller Master Documentation List No. E-2625, Rev 2;To be operated in accordance with MT-Propeller AFM-S Document No.E-2621, Rev 1;or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instructions Doc. No. E-2622, Rev 1,or later revi...	According limitation section of AFM-S.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	06/02/2018	Active	10054487
10054488	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		208B 208, 208B 208	Installation of 5-blade constant speed propellerMTV-27-1-E-C-F-R(G)/ CFRL270-66 on Cessna 208, 208B equipped withHoneywell TPE331-12JR turbine and optional increased Gross Weight iaw.EASA STC 10033295 (FAA STC SA02291AK) or EASA STC 10033267 (FAA STCSA10841SC)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase...	According to MT-Propeller Master Documentation List No. E-2671, Rev 1To be operated in accordance with MT-Propeller AFM-S Document No.E-2667, Rev 1To be installed i.a.w. Installation Instructions Doc. No. E-2668, Rev 0To be maintained i.a.w. Instruction for continued airworthiness Doc. No.E-2669, Re...	1. According limitation section of AFM-S2. Honeywell TPE331-12JR turbine and optional increased Gross Weightiaw. EASA STC 10033295 (FAA STC SA02291AK) or EASA STC 10033267 (FAA STCSA10841SC)Prior to installation of this change/repair it must be determined thatthe interrelationship between this chang...	03/06/2024	Active	10054488
10054490	MT-PROPELLER ENTWICKLUNG GmbH			114TC 114B 114A 114	Installation of 3-blade constant speed propeller MTV-9-B/198-52 onCommander Aircraft Corp. 114, 114A, 114B and 114TC aircraft models	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.CS 36, Amdt 3 and FAR 36 Amdt 30	According to MT-Propeller Master Document List No. E-2557Tobe operated in accordance with MT-Propeller AFM-S Document No. E-2553 or later revisions of the above listed documents approved by EASA.To be installed iaw. Installation Instructions Doc. No. E-2554, or laterRevisionsTo be maintained i.a.w....	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/08/2015	Active	10054490
10054491	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		112TCA 112TC 112B 112	Installation of 3-blade constant speed propeller MTV-12-B/188-59f onCommander Aircraft Corp. 112 aircraft models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 36, Amdt 3 and FAR 36 Amdt 30This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emission...	According to MT-Propeller Master Document List No. E-3306Tobe operated in accordance with MT-Propeller AFM-S Document No. E-2612To be installed iaw. Installation Instructions Doc. No. E-2613To be maintained i.a.w. MT-Propeller ICA Document No. E-2614or later revisions of the above listed document(s...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	03/05/2018	Active	10054491
10054506	MOTORFLUG BADEN-BADEN GmbH	REV. 1		DORNIER 228-212 DORNIER 228-200/-201/-202 DORNIER 228-100/-101	Approval of Motorflug Modification ref 28145F181335, Exchange oftransponder MST-67A to MST-70B to provide ADS-B capability.	CS-ACNS Initial Issue, Subpart D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Master Document List ref28145F181335-0109, rev 0, dated 10.01.2019;Operation in accordance with Motoflug Aircraft Flight Manual Supplementref 28145F181335-0601, rev 0, dated 13.12.2018;Instructions for Continued airworthiness in accordance with Motoflug ICAdocument re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/01/2019	Active	10054506

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054518	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CL-600-2B16 (601-3A VARIANT)	ADS B System upgrade from DO-260A to DO-260B	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AIEC AG AIRPLANE FLIGHT MANUAL SUPPLEMENT NO. AC5392-071 REVISION IRDATED 14 AUGUST 2015AIEC AG INSTRUCTIONS FOR CONTINUED AIRWORTHINESS NO. AC5392-085REVISION.A DATED 18 AUGUST 2015or later revisions of the above listed documents approvedby EASA.AIEC AG MASTER DATA LIST NO. AC5392-049 REVISION A D...	RESTRICTED TO ASN 5042	24/08/2015	Active	10054518
10054539	TDG AEROSPACE INC		FAA STC ST02502LA	MD-90-30 MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Universal fault interrupter install/Electrical protection device thatinterrupts and electrical source immediately afterdetecting a ground, aline-to-line or an arc fault(s).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:25.981(a)(3) & (d) Amdt. 25-125The requirements for environmental protection and the associatedcertified noise and/ or emis...	UFI MD-80 Installation kit Master Drawing List Doc. 10-3210-0002 Rev. EAFM Supplement 20-3210-0002 dated 4 March 2014Instruction for Continued Airworthiness (ICA) 20-3210-0001 Rev. Aor later revisions of the above listed documents approvedby EASA inaccordance with EASA ED Decision 2004/04/CF (or su...	See doc. 20-3210-0002 dated 4 March 2014 "FAA approved AFM Supplement" ,Sect. 1	25/08/2015	Active	10054539
10054572	PMV ENGINEERING			777F 777-300ER 777-300 777-200LR 777-200	TCAS 7.1 upgrade on B777	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List AVI-00930-MDL-R00, dated 13 Aug 2015- Aircraft Flight Manual Supplement AVI-00930-AFMS-R00, , dated 28 Jul2015- Instructions for Continued Airworthiness AVI-00930-ICA-R00 , dated 28Jul 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/08/2015	Active	10054572
10054574	TELEDYNE UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	A320-231, A320-232, A320-233 A320-231/-232/-233 A320-215, A320-216 A320-211, A320-212, A320-214 A320-211/-212/-214/-215/-216 A319-131, A319-132, A319-133 A319-131/-132/-133 A319-114, A319-115 A319-111, A319-112, A319-113 A319-111/-112/-113/-114/-115	Installation of WGL-Fi System on Airbus A319/A320 Series AircraftRev. 1: Transfer from Teledyne Limited to Teledyne UK Limited.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-02, Network Security.- The following paragraph(s) at a later amendment: . JAR-25 Amdt 16 - 25.29(b), 25.301(a)(c), 25.303, 25.305(a)(b),25...	Teledyne Controls Flight Manual Supplement, MOD-FMS-033 Issue 01 dated05 May 2015Teledyne Controls Master Data List MOD-MDL-033 Issue 02 dated 11 August2015or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/08/2015	Active	10054574
10054581	DEC TECHNOLOGIES, INC.			429	Installation of a locking hinge on the baggage door of the BELL 429rotorcraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement Report N°. DEC13052-RFMSor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.Drawing...	HEICO Rotorcraft Flight Manual Supplement, Document NumberDEC13052-RFMS, Original Issue, dated May 28, 2015, or later FAA approved revisions, is required and must be carried in the aircraft during all flights.HEILO Instructions for Continued Airworthiness (ICA), document NumberHAC14-003, Revision 0,...	27/08/2015	Active	10054581

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054582	SJT AEROSPACE CORPORATION		FAA STC ST09806AC	737-700 IGW	Ancillary Outboard Support Structure	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SJT Aerospace Corporation Instructions for Continued AirworthinessSJT-ICA-B737-1 Revision IR<(>,<)> dated March 21,2013<(>,<)>Airworthiness Limitations SectionSJT Aerospace Corporation Instructions for Continued AirworthinessSJT-ICA-B737-2Revision IR<(>,<)> dated February 25<(>,<)> 2015<(>,<)>Airwo...	It is the responsibility of the organisation designing the interior thatwill be attached to this Ancillary Outboard Support Structure to ensurethat the load and moment limitationsspecified in Nordam (SJT Aerospace) documents NTR 7153 and NTR 7264 have been met for the -001 and - 002configurations re...	27/08/2015	Active	10054582
10054583	AERODATA AG			B300	Installation of AD-AFIS-0255 into B300.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SeeAnnexThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicabl...	Installation, Operation and Maintenance according to the Master DrawingList document number MDL-A/C-874 Rev. 1 dated 10th July 2015or later revisions of the above listed documentsapproved by EASA.	Limited to model B300 with installed Proline21 avionics andnextgeneration interiors only.The document AMM-1156 Rev.0 (dated 1st June 2015) Chapter 04 definesadditional Airworthiness Limitations applicable.Prior to installation of this design change it must be determined thatthe interrelationship be...	27/08/2015	Active	10054583
10054584	Q.C.M. DESIGN GmbH			EC 130 T2	Hook Release ModificationInstallation of a switch to allow the pilot the option of selectingeither the existing upper hook or a lower hook for cargo release.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	E350-QCM25-001-M1-HFM-R1 rev. one. Flight Manual Supplementor later revisions of the above listed documents approved byEASA.CP-E350-QCM25-001 rev. 2. Certification ProgramCR-E350-QCM25-001 rev. 1. Compliance ReportE350-QCM25-001-M1-ICA initial issue. Instruction for ContinuedAirworthinessE350-QCM25...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/08/2015	Active	10054584
10054587	SPECTRUM AEROMED, LLCd/b/a SPECTRUM AEROMED	REV. 1	FAA STC ST02340CH	A320-232 A319-115/A319-133/ A320-214	Air Ambulance ConversionReason for revision 1: Change of ownership from Snaky Creek Enterprises,LLC to Spectrum AeromedLLC d/b/a Spectrum Aeromed	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Spectrum Aeromed, LLC Master Drawing List 6072-5DL Rev. 8, datedSeptember 26, 2012 or later FAA approved revision.- Airplane Flight Manual Supplement 6072-5FMS Rev. 8, dated December 5,2016, or later FAA approved revision.- Instructions for Continued Airworthiness 6072-5MM Rev.13<(>,<)> datedSepte...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/04/2019	Active	10054587
10054589	PRO STAR AVIATION, L.L.C.		FAA STC ST00347BO	SEE EASA APPROVED MODEL LIST	Upgrade of the BendixKing CAS 67A TCAS II Change 7.0 to CAS67B TCAS IIChange 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	INSTALLATION DATA LIST - Document Number 21238-IDL-101, Revision IR.EASA APPROVED AIRPLANE FLIGHT MANUAL SUPPLEMENT - Document Number21238-FMS-102, Revision IR.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions oft...	An existing EASA-approved installation of a BendixKing CAS 67A ACAS II(TCAS II Change 7.0) system with TCAS Processor Unit (TPU) part numbersas identified in System Installation Manual 21238-SIM-101Prior to installation of this design change it must be determined thatthe interrelationship between th...	28/08/2015	Active	10054589

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054591	AIRBUS HELICOPTERS CANADA LIMITED		TCCA SH14-31	EC 130 T2	Installation of Cargo Pods	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List Cargo Pods Installation MDL-13-003 issue Bor later revisions of the above listed documents approvedby EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Instructions for Continued Airworthiness Cargo Pods InstallationICA-AHCA-273 revi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/08/2015	Active	10054591
10054607	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	A330-243	320Y LOPA Configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	Master Configuration Scheme, 3135-MCS-01, Issue 2ComplianceReport, 3135-COM-01, Issue 2or later revisions of the abovelisted documents approved by EASA.	Other: Applicable only for MSN 1498 under STC 10034690Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/or repair willintroduce noadverse effect upon the airworthiness of the pro...	28/08/2015	Active	10054607
10054617	AVIATECH & CONSULTING, SOCIEDADLIMITADA	REV. 2		AT-802 AT-502, AT-802 AT-502	INSTALACION DE COMPUERTAS ANTIINCENDIOS. “Design and installation ofcomputerized gates for firefighting”.Rev. 2: Transfer from TRABAJOS AEREOS ESPEJO S.L. to AVIATECH &CONSULTING SOCIEDAD LIMITADA	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1) Plan de Certificación PC01-12 Rev. 3, Fecha: 03/08/2015.2) Planos, Fotografías y Esquemas PL01-12 Rev. 3, Fecha: 17/07/2015.3) Boletín de Ingeniería – Instrucciones de Instalación yAeronavegabilidad Continuada BI01-12 Rev. 4, Fecha 15/07/2015.4) Suplemento al Manual de Vuelo SMV01-12 R2, Fecha: 0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/02/2022	Active	10054617
10054619	LUMA TECHNOLOGIES LLC	REV. 2	FAA STC SA02133SE	SEE FAA AML	Installation of Luma Technologies LT-4500 Series IntegratedLightEmitting Diode (LED) Display Panel and LT-3500 LED light modules, andLT-2103 series landing gear annunciatorRev. 1: Correction of title and descriptionRev. 2: Correction of title and description	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02133SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Luma Technolgies Master Drawing List (MDL) as listed on theAML, orlater FAA approved revision.Luma Technologies Instructions for Continued Airworthiness (ICA)document as listed on the AML, or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.The STC is valid for aircraft types and models ap...	19/10/2020	Active	10054619
10054649	LUFTHANSA TECHNIK AG			A330-300	New Premium Economy Class (A330-300)In the main cabin of the main floor on the aircraft, the change consistof the removal of 10 per cent of the Economy Class Seats between door 2and door 3 and the installation of new developed Premium Economy Seatswith a Panasonic IFE System instead. The new seating...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD25-13/39M issue1 rev 0- ICA, ref A-00-15/35-ICA, Issue 1 rev 0- ComplianceRecord List CRL25-13/39M iss 1 rev 0 or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with :a) SB AIM A330-25-050 - Introduction of a three part class dividerinstallation(Minor Change ref MM637-14)b) STC 10014507 rev2 (or later revision), Non Electric Floor PathMarking System, together wit...	03/09/2015	Active	10054649
10054670	AIRWOLF AEROSPACE L.L.C.	REV.1	FAA STC SR03465CH	F-28F-R F-28A, F-28C, F-28C-2, F-28F 480, 480B 280, 280C, 280F, 280FX	Title: Installation of Airwolf Tension Torsion StrapsDescription: Installation of Airwolf Tension Torsion Strap AssembliesP/N AA-ECD-084-480 and AA-ECD-084-280 on Enstrom Helicopters by usingInstallation Instructions AA-ECD-084-280/480 Rev. A dated 5th June 2015	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Airworthiness Limitations Section, Chapter 4 of the Instruction forContinued Airworthiness for Airwolf Replacement MainRotor BladeTension-Torsion Strap Assemblies on Enstrom Helicopter CorporationTH-28, 480 & 480B Model Rotorcraft & F-28/280 Model Series Rotorcraft,Airwolf Aerospace LLC Report Numb...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/02/2016	Active	10054670

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054673	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BD-700-1A10	Introduction of Upgraded IFE<(>,<)> Cabin Lighting and Universal Outlets	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):EASA CRI D-01 - Glass screensof monitors and displaysThe requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	STC Twenty One Flight Manual Supplement S21.FMS-0121 Issue 1or later revisions of the above listed documents approved by EASA.STC Twenty One Master Document List S21.MDL-1250 Issue 1	None	07/09/2015	Active	10054673
10054682	MT-PROPELLER ENTWICKLUNG GmbH			F177RG 177RG 177B 177A	Installation of 3-blade constant speed propeller MTV-9-B/198-52 onCessna 177A, 177B, 177RG, F177RG	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.CS-36 Amdt.3 and FAR 36 Amdt.30	According to MT-Propeller Master Document List No. E-2659Tobe operated in accordance with MT-Propeller AFM-S Document No. E-2655or later revisions of the above listed documents approved by EASA.To be installed iaw. Installation Instructions Doc. No. E-2656, or laterRevisionsTo be maintained i.a.w.R...	According limitation section of AFM-S	07/09/2015	Active	10054682
10054688	AEROTEC & CONCEPT			EC120 B	MOD 14250 – Installation of Garmin 500HNEW-PAGE	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	RFM Supplement<(>,<)>Rotorcraft Type Airbus Helicopters EC120 B<(>,<)>Garmin G500 H installation for day VFR useDoc n° AE14250RFMS, Rev 0-G, dated 4 September 2015or later revisions of the above listed documents approved by EASA.Certification Programme G500H installation EASA project n° 0010034034,D...	- Use limited to Day-VFR- No connection with autopilotPriorto installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the pr...	08/09/2015	Active	10054688
10054690	GLOBAL ENGINEERING AND TECHNOLOGY,		FAA STC SA1788WI	T206H	Modification of Cabin Interior and Seating Configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	GETI Airplane Flight Manual Supplement, No. AFMS206-102113,Rev. A, FAAapproved January 28, 2015;GETI Master Drawing List, No. MDL206-102113, Rev. A, dated March 12,2015or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/09/2015	Active	10054690
10054694	THE MONROE COMPANY, LLC	REV. 1	FAA ST02762CH	550, S550	Installation of a Rockwell Collins IDS-3000 integrated cockpit flightdisplays system and other avionics modifications.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Master Drawing List, Great Lakes Aviation Holding document No. AE1008003<(>,<)> Revision H, dated 16 December 2011.Aircraft Flight Manual Supplement, Great Lakes Aviation Holding documentNo. AE0109007, Revision B, dated 21 December 2015.orlater revisions of the above listed documents approved by EA...	For aircraft equipped with Williams FJ44-3AP engines, the engines mustbe installed in accordance with FAA STC ST02661CHvalidated by EASA ifthe IDS-3000 is to be used for engine instrumentation display inaccordance with this STC.Prior to installation of this design change it must be determined thatt...	17/09/2015	Active	10054694
10054696	HELI-ONE		TCCA STC SH11-36	S-76A, S76-B, S-76C	Installation of Composite Utility Interior in accordance with Heli-OneMaster Drawing List CHS76-25-094 MDL	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Master Drawing List CHS76-25-094 MDL, revision AInstallation Manual INSTCHCS76, revision CMaintenance Manual SupplementCHCICAS76, revision B	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/09/2015	Active	10054696

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054711	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	747-400	Installation of LED Wash Lights	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan H4CP0092 issue 1, dated 20 April 2015Certification Summary H4A1764 Issue 1, dated 07 September 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/09/2015	Active	10054711
10054713	GOODRICH LIGHTING SYSTEMS		FAA ST01978AT	727-100, 737-200	Installation of Fixed Wingtip Halogen Navigational LightingSystem.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	BF Goodrich Aerospace Lighting Systems Master Drawing List BFG-R-342-00Revision A dated June 7<(>,<)> 2012.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/09/2015	Active	10054713
10054714	STC TWENTY ONE LIMITED	REV. 5	CAA UK RESPONSIBILITY	A321-272N/-251NX/-252NX A321-271N/-271NX/-272N/-272NX A321-253NX/-271NX/-272NX A321-251NX/-252NX/-253N/-253NX A321-251N/-252N/-253N/-271N A321-213/-231/-232/-251N/-252N A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-271N/-272N/-273N A320-253N/-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233/-251N/-252N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N A319-131/-132/-133/-151N/-153N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	FlightLink System Installation.Rev. 4: To add the A319NEO, A320NEO and A321NX models within theeligibility model list.Rev. 5: transferred from Tenencia Ltd. to STC Twenty One Ltd	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List: TEN 779 Issue 26 dated 04.Feb. 2020- Maintenance Manual Supplement: TEN 779-04 (D3110-004 E) Issue 4dated09.Jan.2019- Flight Manual Supplement: TEN 779/47 (TEN/A320/010) Issue 2 dated06.Jul.2017or later revisions of theabove listed document(s) approved/acceptedunder the EASA sys...	- EMI/EMC Test Procedure reference TEN 779/11 must be performed andsuccessfully completed for First of each Airbus A318, A319, A319N, A320,A320N, A321, A321N and A321NX) where modification TEN 779 is installed.- Aircraft with AMDS installed in accordance with EASA STC 10037808 musthave the system de...	14/11/2022	Active	10054714
10054715	SOCIETE AIR FRANCE S.A.	REV. 1		A321-231	Vietnam Airlines - Cabin rearrangementCabin seating rearrangement (9g “Zodiac“ Y/C new seats)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Change Approval Sheet CAS-A320-15-002 rev 2- Instruction for Continued Airworthiness<(>,<)> ref:ICA-A320-15-005-002 rev 1or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/03/2016	Active	10054715
10054724	ALPINE AEROTECH LP		TCCA STC SH13-36	429	Bear Paw Kit Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Alpine Aerotech Master Data List No. AAL-490-014-001, Revision AAlpine Aerotech Instructions for Continued Airworthiness No.AAL-490-015-701, Revision NIor later revisions of the above listed documents approved by EASA inaccordance with theTechnical Implementation Procedures of EU/ CanadaBilateral A...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/09/2015	Active	10054724

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054735	NORTHWEST AEROSPACE TECHNOLOGIESINC.			747-400	Cabin Interior Reconfiguration and IFE System Installation on BritishAirways Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:JAR-25 Change 10 with regard to 25X1360JAR-25 Change 11 with regard to 25.1529JAR-25 Change 12 with regard to 25.812(a)(1)(...	- Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0497-D90, Revision -, dated 6 September 2015.- Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0497-D70, Revision -,dated 1 July 2015or later revisions of the above listed docu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/09/2015	Active	10054735
10054737	HELI-ONE		TCCA SH08-47	S-76A, S-76C	Installation of Dual GPS Antenna Mount to Tail Rotor Driveshaft Cover(Structural Provisions only) in accordance with Heli-One Master DataList CHS76-53-044 MDL.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List CHS76-53-044 MDL Rev F	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/09/2015	Active	10054737
10054749	AMAC AEROSPACE SWITZERLAND AG			A319-115	Interior Outfitting - DM01-2500See Master Data List MDL-DM01-2500, Rev. F	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-4302 Isolated compartmentsCRI D-4308 Installation of an open cook top in the galleyarea of a VIPinteriorCRI D-4309 Improved Flammability Standa...	Airplane Flight Manual Supplement: AFMS-DM01-2500 revision A dated26.08.2015Instruction for Continued Airworthiness: ICA-DM01-2500 revision A dated21.07.2015Master Minimum Equipment List Supplement MMELS-DM01-2500 revision ACabin Crew Manual CCM-DM revision Aor later revisions of the above listed do...	Limited to S/N 5040Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	14/09/2015	Active	10054749
10054784	DEC TECHNOLOGIES, INC.		FAA STC SR03997AT	429	Installation of Locking Fuel Cap, DEC Technologies, Inc. part number429-001 DEC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing number 429-001DEC, Rev. F, dated 03/05/2013Instructions for Continued Airworthiness, document number TI-HAC12-002,Rev. 0, dated 10/04/2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)"...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.,,	16/09/2015	Active	10054784
10054785	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09607RC	429	Installation of Helicopter Emergency Egress Lighting System(HEELS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List, Report No. AA-10059 Revision A, dated September 23,2014Rotorcraft Flight Manual Supplement, ReportNo. AA-10065, No Revision,dated November 24, 2014Instructions for Continued Airworthiness, Report No. AA-10064, NoRevision, dated August 26, 2014or later revisions of the above lis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.,,	16/09/2015	Active	10054785

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054788	AVIONICARE Ltd.		CAA UK RESPONSIBILITY	CL-600-2B16 (604 VARIANT)	Activation of Cabin WiFi	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avionicare Ltd Aircraft Flight Manual SupplementAVC-AFMS-01007-CL604-001 Issue 1or later revisions of the above listed documents approved by EASA.Avionicare Ltd Master Document List AVC-MDL-01007-15 Issue A	None	16/09/2015	Active	10054788
10054797	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		SEE EASA APPROVED MODEL LIST	TCAS 7.1 (ACAS II) Upgrade of Prior Existing TCAS 7.0 in Part 25Aircraft as per AML STCRevision 1 - Honeywell TCAS computer changed part number from940-0351-001 to 940-0351-005 tocorrect False RA issue	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 2 for the requirements affected bythis change.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels ofu...	-AML Document: 2096998-EO Issue 3-Engineering Order & Certification Program for TCAS 7.1 (ACAS II)Upgrade of Prior Existing TCAS 7.0 in Part 25 Aircraft Document2096998-EO Issue 4or later revisions of the above listed documents approved byEASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/10/2017	Active	10054797
10054800	STANDARD AERO		FAA STC ST01662CH-D	31, 31A, 35, 35A, 36, 36A	Installation of Honeywell Mark VIII Enhanced Ground Proximity WarningSystem, EGPWS with video display of terrain.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement, ES35-300162-100, revision IR, dated23 August 2002, for option 1.Airplane Flight Manual Supplement, ES31-300099-101, revision IR, dated15 April 2003, for option 2.Airplane Flight Manual Supplement, ES35-300162-102, revision A, dated19 October 2003, for option 3Inst...	None	17/09/2015	Active	10054800
10054809	AMTECH AERONAUTICAL LIMITED	REV. 2	TCCA STC SH15-17 ISSUE 2	AB139/ AW139	Installation of Flight Data Acquisition Storage & Transmission System(FAST) on AB139/AW139.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Pratt & Whitney RFM Supplement GN4-T-250-4, Rev. Cor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Pratt & Whitney Data List, Installation Data GN4-T-100-4, Rev. E.Pratt & Whitney FAST Instruc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/07/2017	Active	10054809
10054811	B/E AEROSPACE, Inc.		FAA ST04220AT	A330-341, A330-342, A330-343 A330-321, A330-322, A330-323, A330-321, A330-302, A330-303 A330-223, A330-243 A330-201, A33-202, A330-203	Installation of the B/E Aerospace Tapestry LED Lights in the CabinRemoves and replaces the existing fluorescent tube light assemblies inthe main cabin and lavatories with LED light assemblies. Additionally,all passenger reading lights are replaced with LED light assemblies.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: all the affectedparagraph are considered with CS 25 Amendment 4 (refer to CertificationPlan for details).The requirements...	Certification Plan Reference : 2-152820-900, rev BMDL: 2-152820-001, rev AICA : 2-152820-804, rev AFAA Statement of Compliance, dated on 16 September 2015or later revisions of theabove listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis de...	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2) Pre-requisite : the design requires the in...	18/09/2015	Active	10054811
10054815	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC ST11131SC	ATR 72-212 A ATR 72-212 ATR 42-500	Pratt & Whitney Flight Acquisition, Storage and Transmission system(FAST) installation.This modification installs an on-board communications system having thecapabilities to record data from engine control systems or enginediagnostic and monitoring unit, aircraft and avionics systems, and totransmit...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Data List, Installation Data document, ref GN4-T-100-3 Revision E, dated01 October 2014.Aircraft Flight Manual Supplement, ref : GN4-T-250-3 Revision B, dated01 October 2014.Instruction for Continued Airworthiness, ref : GN4-T-260-4 Revision C,dated 01 October 2014or later revisions of the above lis...	None	21/09/2015	Active	10054815

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054816	E A D AEROSPACE AIRWORTHINESS			B747-8	Activation for GSM and WIFI Installation ,,The Cabin Connectivity System is an end-to-end solution that providesGSM andWiFi services to aircraft passengers only. The system consistsof hardware and software parts for the airborne GSM network to beconnected to ground network via satellite, or any oth...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFMS, Doc. No. 01422-EAS-A-AFM-01, Rev. B, Dated 15. September 2015 (section 2 only)- ICA, Doc. No. 01422-EAS-A-ICA-01, Rev. A, Dated 13. August 2015(section 2 only)or later revisions of the above listed documents approved by EASA.- Master Drawing List, Doc. No. 01422-EAS-A-MDL, Rev. C, Dated 15.Se...	- TPED use is not allowed in cockpit and lavatories.- The CCS must not be used below 3000m AGL (approximately 10 000 ft)	21/09/2015	Active	10054816
10054817	FOKKER SERVICES B.V.			767-400ER 767-300F 767-300BCF 767-300 767-200	Boeing 767 TCAS V7.0 upgrade to V7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan CP-0277 Issue 1Certification Plan CP-0278 Issue 1Compliance Record Report CRR-0277 Issue 1ComplianceRecord Report CRR-0278 Issue 1or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/09/2015	Active	10054817
10054820	TC INTER-INFORMATICS A.S.	REV. 1		A330-243	Virgin Australia Business Class Interior ReconfigurationInstallation of new business class seats and associated furniture – A330Virgin Australia cabin	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI D-4324-001 – Installation of angled seatsJAR 25.603 Change 14JAR 25.853 Change 16JAR 25.869 Change 14JAR 25.1431 Change 14The requirements...	MASTER DRAWING LIST: JD-45AC02-1, rev AICA & EWIS for Continued Airworthiness: JD-45AC04-1, rev 3Certification Summary Report: ref JD-45AC10-1, rev Newor later revisions of the above listed documents approved by EASA.	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2) The following approval is required for the...	08/02/2017	Active	10054820
10054826	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		MYSTÈRE-FALCON 20GF MYSTÈRE-FALCON 20F5 MYSTÈRE-FALCON 20E5 MYSTÈRE-FALCON 20D5 MYSTÈRE-FALCON 20C5 FAN JET FALCON SÉRIES F FAN JET FALCON SÉRIES E FAN JET FALCON SÉRIES D FAN JET FALCON SÉRIES C FAN JET FALCON	CVR/FDR INSTALLATION	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 at amendment 4:25.1 (a)(2) Applicability – 25.23 Load distribution limits – 25.25Weight limits – 25.27 Centre of gra...	-BOURNEMOUTH AVIATION (CONSULTANTS) LTD FLIGHT MANUAL SUPPLEMENT NO.BAC-891-FMS01 ISSUE 1-BOURNEMOUTH AVIATION (CONSULTANTS) LTD MASTER DATA LIST NO.BAC-891MDL01 ISSUE 5.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The approval holder shall fulfill the obligations of Part 21, Point21A.109.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthi...	26/03/2021	Active	10054826
10054871	ASSOCIATED AIR CENTER, L.P.		FAA STC ST10916SC	A330-243	Modification of a VIP Interior installed in Airbus A330-243, MSN 1053.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):Isolated Compartments (CRI D-4302-003)Cabin Crew Rest (CRI D-4304-001)Glass Screen of Display Monitors (CRI D-4310-001)Shower Installation (CRI D-4314...	MDL ref 3007000000 rev BICA ref 3007050090 rev BCertification Plan ref 3007000090, rev FFAA Statement Of Compliance dated on 23th Sept 2015AFM ref 3007021090 rev Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisionst...	This approval is limited to MSN 1053The following STC need to be installed, concurrent to this approval :STC 10032264, “Installation of Cabin Interior Noise Reduction Kit”.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any o...	24/09/2015	Active	10054871
10054873	STANDARD AERO		FAA STC ST01654WI	MF 50, MF 900	Wireless Fidelity (WiFi) Activation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	3S Certification, Aircraft Flight Manual Supplement (AFMS) 032-2325-AO1-00, Revision IR, Dated: 08 December 2011.3S Certification, Aircraft Flight Manual Supplement (AFMS)032-2325-A02-00, Revision IR, Dated: 25 September 2012.or later revisions of the above listed documents approved by EASA inaccord...	Applicability limited to MF50 and MF900 models.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	24/09/2015	Active	10054873

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054878	AEROTEC & CONCEPT			757-200, 757-300	Installation of Dual Iridium/GPS Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, Aerotec document No. AE14265MDL, Revision 0, dated09 July 2015- Instruction for Continued Airworthiness, Aerotec document No.AE14265ICA<(>,<)> Revision 0, dated 09 July 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/09/2015	Active	10054878
10054885	LAKE CENTRAL AIR SERVICES		TCCA SA12-77	208, 208B	Installation of Synthetic Aperture Radar System (AKA SnowSAR).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List LCA01927-MDL, Rev. 1, TCCA approved January 28, 2013Flight Manual Supplement LCA01927-CF, Rev. 2, TCCA approved February 4,2013or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreem...	Cessna 208B (EX) as defined in EASA TCDS IM.A.226, Section 2.2 areexcluded.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the ai...	28/09/2015	Active	10054885
10054891	DELTA ENGINEERING CORPORATION		FAA STC ST03204NY	AIRBUS A321 SERIES	Panasonic In-Flight Entertainment eX1 System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Delta Engineering Airplane Flight Manual Supplement No. 0664-09190-2373Delta Engineering Instructions for Continued Airworthiness Document No.0764-09191-2373or later revisions ofthe above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthi...	For configuration TL10792-01 Turkish Design Approval CG-2528001-DAOI-OO (raceways) is required.	30/09/2015	Active	10054891
10054903	AIRBORNE TECHNOLOGIES GmbH	REV. 1		AP68TP-600 "VIATOR"	Aviator- Aero Data Rack Installation / With this major change No.:STC-AT-090 a mission configuration for the AP68TP-600is certified. Themission configuration includes an operatorworkstation, an aero datarack, 11 antennas and other mission equipment.Revision 1: This revision was issued to add the i...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: The followingparagraphs of CS 23 Amendment 3 are applicable to the change: 23.1;23.3; 23.21; 23.23; 23.29; 23.45; 23.49;2...	The Change is defined with Revision 1 of Airborne Technologies “ChangeApproval” document STC-090-G-ASThe aircraft shallbe operated in accordance with Revision 3 of AirborneTechnologies Airplane Flight Manual Supplement document AFM-STC-AT-090.The aircraft shall be maintained in accordance with Revi...	Limited to Aircraft Serial Number 9010Vulcanair modification MOD.VTR/01 “Aerial Survey Configuration” incombination with VulcanairDRW A-7.9603 shall be incorporated prior to orin conjunction with this change.Prior to installation of this change/repair it must be determined thatthe interrelationshipp...	26/11/2021	Active	10054903
10054910	HELI-ONE		TCCA STC SH03-34	S-76A, S-76C	Installation of EXIS Emergency Exit Lighting System in accordance withHeli-One Approval Control Document CHS76-33-022 ACD	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Flight Manual Supplement EXIS Lighting System FMS CHS76-33-022, RevisionNCor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Proceduresof EU/ Canada Bilateral AgreementApproval Control Document CHS76-33-022 ACD, Revision DMaintenance Manu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/09/2015	Active	10054910

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054913	TRANSPORTES AEREOS PORTUGUESES, S.ATAP MAINTENANCE & ENGINEERING			A321-212, A321-213 A321-111, A321-112, A321-211 A320-211, A320-212, A320-214 A319-114, A319-115 A319-111, A319-112, A319-113	Installation of thrust reverser pivoting door actuator fitting on CFM56-5B.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Report TAP-AC0136-CR-01R02 dated 18/09/2015Compliance Check List TAP-AC0136-CCL-01R03 dated 18/09/2015or later revisions of the above listed documents approved by EASA.	None	30/09/2015	Active	10054913
10054917	BOMBARDIER Inc.	REV. 1	TCCA C-LSA12-147/D	CL-600-2B16 (604 VARIANT)	Installation, Aircraft Completion (Special Mission Provision)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Data Summary, ref. doc. RAZ-605-5896-MDS, Rev. B, dated24th September 2013- Modification Data Summary, ref. doc. RAZ-605-5898-MDS, Rev. B, dated24th September 2013-Airplane Flight Manual Supplement, ref. doc. H478090 (5896),Rev. NC,dated 15th August 2012- Airplane Flight Manual Suppl...	Applicable only For CL604 Aircraft Serial No. 5896 and 5898	01/10/2015	Active	10054917
10054918	FEDEX EXPRESS CORP.		FAA ST03832AT	727-200	Installation of Nose Landing Gear Viewport with relocation of theviewport from aft of cargo bulkhead to forward of thecargo bulkhead.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: JAR25 amdt 18: 25.301,25.303, 25.305, 25.307, 25.561(c), 25.571(b), 25.601, 25.603, 25.605,25.607, 25.611, 25.613, 25.1301...	Federal Express Top Drawing B27-25-136 rev E dated sept 8, 2009AFM Supplement ER 08-121 dated Feb 10, 2010Instructions for continued airworthiness 08-118 dated Aug 6, 2008or laterrevisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent re...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/09/2015	Active	10054918
10054923	FEDEX EXPRESS CORP.	REV. 1	FAA ST01955AT	727-100, 727-200	Installation of a triple Rockwell Collins 618M5 VHF Transceivers and thereplacement of control heads with Gables G7406-04 to meet the 8.33kHzchannel space frequencies.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Federal Express Top Level Drawing B27-23-034 rev B dated May 10, 1999AFM Supplement VHF-001 dated July 20, 1999or laterrevisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementati...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/10/2015	Active	10054923
10054939 (2004-476)	ROCKWELL COLLINS, Inc.	REV. 2	FAA ST00881WI-D	SEE APPROVED MODEL LIST	TCAS II System ModificationModification of a TCAS II SystemInstallation to Change 7.0or Change7.1Revision 2 of this STC includes revision to the AFM and administrativechanges to the drawing index.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Refer to EASA APPROVED MODEL LISTor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures ofEU/ USA Bilateral Agreement.	EASA approved installation of a TCAS II system is a prerequisite to thisSTC. Refer to the Drawing Index for each model in the EASA AML.Airplanes with a maximum operating altitude greater than 51000 feet arenot authorized to upgrade from a TTR-920(CPN 622-8971-522) to a TTR-921or TTR-2100.Prior to in...	01/03/2019	Active	10054939
10054941	BUTLER AVIONICS, INC		FAA STC ST01791WI	60	Installation of a Collins AHC-3000A Series Altitude HeadingComputer	The certification basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable for thiscertificate/approval.	Butler National Corporation Master Drawing List, No. 0280100, Rev. IR,dated July 23.2015 or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	05/11/2015	Active	10054941

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054957	JET AVIATION AG, BASEL			MYSTÈRE-FALCON 900	Cabin Interior (recertification of 94K05 cabin interior)Recertification of historic cabin interior installation (prj. 94KC5)w/13 pax configuration (prj. 99BF2) for non-commercial operation (ref.EC216/2008, EU Air Ops - NCC).The design developed in 1995 with UK-CAA technical oversight receivedapprov...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Falcon 900B Aircraft Maintenance Manual or later revisions of the abovelisted documents approved by EASA.Certification Plan Doc. No. JBSL-M-00441CER-01 Issue 4	This STC (re-certification of 94KC5 Cabin Interior) is limited to thespecific aircraft S/N 145.All modifications that may be introduced at any later date will need tocomply with the current interpretations (CRI Special conditions, etc.).	02/10/2015	Active	10054957
10054960	SABENA TECHNICS BGC			A330-200	CABIN RECONFIGURATION WITH IFE eXlite System on A330.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to associated Certification Plan4802-01-A-CP-R01, section 5 & 6, for de...	Master Data List, ref : 4802-01-A-MDL-R00Instruction for Continued Airworthiness, ref : 4802-01-A-ICA-R00Aircraft Flight Manual Supplement, ref : 4802-01-A-AFMS-R00or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with STC 10014507 rev2 (or later revision), NonElectric Floor Path Marking System.Prior to installation of this design change it must be determined thatthe interrelationship between this design change andp...	02/10/2015	Active	10054960
10054962	SABENA TECHNICS BOD	REV. 1		A340-313	Cabin modificationThis modification is converting a mono-class cabin configuration (342Y/C seats) into a three classesone (8F/C -30B/C -54 Y/C). Themodification includes the removal / deactivation of existing IFE system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): D-2305-004 : Firm HandholdThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product ar...	Modification Approval Sheet, ref : S-25-4018 Issue 4, dated24 September2015Aircraft Flight Manual Supplement, ref : AFMS-F4041-25-017 Issue 1,dated 09 September 2015Instruction for Continued Airworthiness, ref : ICA-F4041-25-004 Issue B,dated 17 September 2015Master Minimum Equipment List Suppleme...	The applicability of this modification is limited to the A340-313 MSN257	06/10/2015	Active	10054962
10054966	DASSAULT AIRCRAFT SERVICES (DAS)		FAA ST03371NY	MYSTÈRE-FALCON 900 FALCON 900EX	Validation of FAA STC.Installation of Honeywell Primus Elite Avionics System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): SC F-9107-001, “HIRF Protection”- The following paragraph(s) at a later amendment: Thecertificationbasis for the parts changed or affected by the2...	AFMS ref. 042413-001 Revision IR, dated 26 February 2014 orlaterrevisions of the above listed documents approved by EASA in accordancewith EASA ED Decision 2004/04/CF (or subsequent revisions of thisdecision) and/ or the Technical Implementation Procedures of EU/ USABilateral Agreement.Master Data...	Applicable to MF900 model with Dassault Aviation modifications M1975 andM2695 embodied (Falcon 900C version).Applicableto F900EX model.Prior to installation of this design changeit must be determined thatthe interrelationshipbetween thisdesign change and any other previously installed designchang...	02/10/2015	Active	10054966
10054973	SCANDINAVIAN AVIONICS DESIGN ApS			EC 135 T2 (CPDS) EC 135 T1 (CPDS) EC 135 T1 (CDS) EC 135 P2+, EC 135 T2+ EC 135 P2 (CPDS) EC 135 P1 (CPDS) EC 135 P1 (CDS)	P-RNAV Upgrade of GNS430	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 Amendment 3: CS27.1/29/301/303/305/307/321/337/561/601/603/605/609/610/611/613/771/773/853/1301/1303/1307/1309/1321/...	- Rotorcraft Flight Manual Supplement 2091141-AM A Issue 4,date09.09.2015 or later revisions of the above listed documents approved byEASA.- Drawing List 2091141-DL Issue 1, dated 06.02.2015- Engineering Order Doc 2091141-EO Issue 1, dated 23.09.2015- Continued Airworthiness Doc 2091141-CA Issue 1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/10/2015	Active	10054973
10054976	AYESA AIR CONTROL INGENIERIAAERO NAUTICA SL			FALCON 10	Installation of Medical Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement ref. AAS111PD20FM01FM0102, dated 27October 2013 ;Airworthiness Limitations contained in the Chapter 4 of MaintenanceManual Supplement ref. AAS111PD20IC01MM0103, dated 19 December 2013 ;or later revisions of the above listed documents approved by EASA.	Applicable to Falcon 10 s/n 209Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	05/10/2015	Active	10054976

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10054978	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	JETSTREAM SERIES 3100	TCAS II Upgrade to Version 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-25 Amendment 1625.130125.130925.152925.1581The requirementsfor environmental protection and the associatedcertified noi...	Cranfield Aerospace Limited Flight Manual Supplement CA/DD/M053 Issue Aor later revisions of the above listed documentsapproved by EASA.Cranfield Aerospace Limited Type Design Definition Document CA/DD/DR0286Issue A	None	05/10/2015	Active	10054978
10054997	ORCON CORPORATION		FAA STC ST01824LA	767-200, 767-300	Blanket Insulation Installation	The Certification Basis (CB) fir the original product remains applicable to this certificate/approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Orcon Index List, Report Number F83006, Revision B,dated August 17, 2005, or later FAA approved revision.	The approval of this modification applies to the above noted airplanemodel series only.If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.Prior to installation of this design change it m...	05/11/2015	Active	10054997
10054999	ORCON CORPORATION		FAA STC ST02497LA	A318/A319/A320/A321 SERIES	Installation of Cabin Doors, Floor Panels and Forward Galley MatInsulation Replacement Blanket	The Certification Basis (CB) fir the original product remains applicable to this certificate/approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	FAA approved Orcon Corporation Index List F83009 Revision "B", datedJanuary 29, 2014 or later FAA approved revision	The approval of this modification applies to the above noted aircraftmodels series only. A copy of this STC must be included in the permanentrecords of the modified aircraft. If the holder agrees to permit anotherperson to use this certificate to alter the product, the holder shallgive the other per...	05/11/2015	Active	10054999
10055010	IAC - INDUSTRIAS AERONAUTICAS DECOIMBRA, Lda.			U206G, TU206G U206D, TU206D, U206E, U206F TU206E, P206E, U206C, TU206C 206H, T206H, F206D, U206E	Static line parachutes supportThis support is manufactured and installed on the floor of the aircraftand fixed to its primary structure (same structure that supports theseat railsand the seat belts), and installed with a reinforcement plateto help the force dissipation to ensure the structural inte...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): SC-O23-div-01 Parachuting Activity.The requirements for environmental protection and theassociatedcertified noise and/or emissions levels of the or...	AFM Supplement for Static Line Operation IAC-C206_Saticline-AFMS ED1 orlater revisions of the above listed documents approved by EASA.Master Document List IAC.C206SL.MDL issue1FORM IAC. 21.MOD.M-120515 Project Dossier issue 1IAC-C206SL-MoC List for IAC. 21.MOD.M-120515 issue 1Installation Instructions...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/10/2015	Active	10055010
10055011	AVIONITEC AG			F260D	Avionics RetrofitOut: Gemelli Audiopanel AG04-1, dual Collins VHF-COM VHF 20B systems,dual VHF-NAV VIR 31A systems, Compass system PN-101, NAV-IndicatorIND-31, ADF 60A system, DME40 system, Transponder TDR 90 system, dualInternational Aerospace ID-90000 RMI, dual AIM P20A InverterIn: Garmin RemoteG...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-23 original issue:CS 23.301, 561, 1301, 1309, 1321, 1325, 1327, 1329, 1351, 1357, 1359<(>,<)> 1365, 1381, 1431, 1529, 1...	AFMS Sandel SN 3500 EHSI No. 2604-011 of 01.10.2014AFMS Avidyne TAS 605 No. 2604-012 of 01.10.2014or later revisions ofthe above listed documents approved by EASA.Master DocumentList No. 2604-017 Rev. 1 of 30.09.2015Instructions for Continued Airworthiness No. 2604-015 of 01.1O. 2014.	Limited to HB-EJO S/N 0567 and VFR operationPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	06/10/2015	Active	10055011
10055012	ADS-B TECHNOLOGIES, L.L.C.		FAA STC SA02442AK	SEE FAA AML	Installation of the L-3 Communications NGT-1000/2000/2500 ADS-B system	The Certification Basis (CB) fir the original product remains applicable to this certificate/approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Master Data List, L3-61-MDL 1, Revision 2, dated April 6,2015.	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.2) If the holder agrees to permit another pers...	11/12/2015	Active	10055012

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055022	HELI-ONE		TCCA SH07-45	S-76A, S-76B, S-76C	Installation of Audio Panel NAT-380 in accordance with Avionics DesignServices Ltd. Master Drawing List MDL07124.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Configuration 1: Pilot and Co-pilot NAT-380 Audio Panel Installation- Master Drawing List MDL07124 Rev B- Maintenance Manual Supplement H1C-S76-23-0055-MMS Rev AConfiguration 2: Third NAT-380 Audio Panel Installation- Master Drawing List MDL07124 Rev B- Maintenance Manual Supplement HCS76230055-730...	Configuration 1 and configuration 2 may be installed independently ortogether.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the...	06/10/2015	Active	10055022
10055024	DELTA ENGINEERING CORPORATION	REV. 1	FAA ST02928NY	777-200LR, 777-300ER	Installation of a Panasonic Avionics Corporation Global CommunicationsSuite (GCS)Revision 1 removes the limitation for T-PED STC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 4: 25.831, 25.853, 25.869, 25.981, 25.1353, 25.1431, 25.1583,25.1585The requirements for environmental protectio...	Delta Engineering Master Data List 0143-08223-2319 RevisionO dated 24June 2017 or later FAA approved revisions to Delta Engineering MasterData List previously listed.The Instructions for Continued Airworthiness and Airplane Flight ManualSupplement as listed on the Master Data List.	Operational approval to use T-PED's must be obtained separately fromthis STC.EASA STC No. 10043555 (Antenna) is required with this STC when installedconfiguration includes eXConnect or eXPhone.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this ch...	09/10/2020	Active	10055024
10055027	ANCRA INTERNATIONAL LLC		FAA STC ST02447LA	DC-9-81/-82/-83, MD-88	Installation of mechanical cargo loading system main deck /Installationof mechanical cargoloading system Pin 85130-1 0<(>,<)>-11 <(>&<)>-12 in accordance with FAAapproved Ancra Int. Controlleddata list OL85130 rev. C.	The Certification Basis for the original product as amendedby thefollowingadditional or alternative airworthiness requirements:14 CFR 26.11 & 26.47The requirements for environmental protection and the associatedcertified noise and/ oremissions levels of the original product are unchanged and remaina...	Project Specific Certification Plan ANCRA report 9674 rev.E;Documentation FAA approved Ancra International LLC Controlled data listDL85130 rev. C.or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision...	None	07/10/2015	Active	10055027
10055029	AERONAUTICAL ENGINEERS Inc.		FAA STC ST02434LA	DC-9-81/-82/-83, MD-88	MD-80 SF/Conversion from passenger to freighter configuration includingClass E Cargo compartment	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Conditions:CRI/SC D-02 Fire protection of Essential system/ equipment within Class Ecargo compartments;CRISC D-03 Courier compartmentDeviation (s):CRI D-01 CourierT...	Project Specific Certification Plan doc. R-2817 Rev. N.Documentation FAA approved AFM supplement doc.R-847 Rev. BAirworthiness Limitation See: Maintenance Planning Document supplement,doc.R-867 IR Sect.9Cargo Door Drawing List for the MD-80 Aircraft doc.R-831 , rev. H withDwg.AE5345 Rev. A (seven vi...	See AFM supplement R-847 Rev. BPrior to installation of this design change it must be determined thattheinterrelationship between this design change and any other previouslyinstalleddesign change and/or repair will introduce no adverse effect upon theairworthinessof the product.	06/10/2015	Active	10055029
10055030	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	A340-642, A340-643	Installation of Gogo 2KU – Structural and Electrical Provisions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 16 –Various.The requirements for environmental protection and the associatedcertified noise and/ or emissi...	STC Twenty One Ltd Instructions for Continued AirworthinessS21.TEC-047 3Issue 2 dated 15 May 2017, Section 3 – Airworthiness Limitations< (>,<)>or later revisions of the above listed documents approved by EASA.STC Twenty One Ltd Master Document List S21.MDL-1236 Issue 10.	Airbus A340-642 and -643 aircraft, modified by this EASA STC, havedoublers and brackets attached to the external crown skin between framesFR 53.4 and FR 53.9, and stringers STR 4 LH and STR 4 RH.EASA AD 2016-0152 (superseding EASA AD 2013-0127 for A340 aircraft) requires accomplishment of the actions...	13/06/2017	Active	10055030

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055031	AERODATA AG	REV. 1		1900D	Installation of AD-AFIS-290 including additional RSBN receiver and theSO-94R Transponder	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-23 Amdt 3: 23.1 ; 23.3(d) ; 23.25(a)(2) ; 23.29 ; 23.251 ; 23.301(a) & (c) ; 23.303 ; 23.305 ; 23.307 ; 23.337(a) & (b) ;...	Installation according to the Master Document List MDL-A/C-865 Rev. 4dated 1st October 2015 and Service Bulletin SB-B1900-RUSFIS-2134 Rev. 0Operation according to Aircraft Flight Manual Supplement documentsAFM-145 Rev. 2Maintenance according to Aircraft Maintenance Manual Supplement documentAMM-1147...	- Limited to model B1900D with installed Rockwell Collins Pro Line IIavionics only.- The document AMM-1147 Rev.4 Chapter 04 defines additionalAirworthiness Limitations applicable.Prior to installation of this design change it must be determined thatthe interrelationship between this design change an...	26/02/2016	Active	10055031
10055039	ADS-B TECHNOLOGIES, L.L.C.	REV. 2	FAA STC SA02444AK	SEE FAA AML REV. 3	Approval of the L-3 Communications NGT 9000/9000R ADS-B system	The Certification Basis (CB) for the original product remains applicable to this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Master Data List, L3-76AK-MDL 1, Revision 1, dated June 2, 2015.	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.2) If the holder agrees to permit another pers...	22/08/2016	Active	10055039
10055044	AEROTEC & CONCEPT			MYSTÈRE-FALCON 900	Upgrade to TCAS Change 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, AE15136MDL, Issue 0- Aircraft Flight Manual Supplement, AE15136AFMS, Issue 0- Instructions For Continued Airworthiness, AE15136ICA, Issue 1or later revisions of the above listed documents approved by EASA.	Per Aircraft Flight Manual Supplement, AE15136AFMS, Issue 0andInstructions For Continued Airworthiness, AE15136ICA, Issue 1Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or r...	08/10/2015	Active	10055044
10055045	AIM AVIATION (JECCO) LIMITED	REV. 1	CAA UK RESPONSIBILITY	737-700	YG140 Interior CompletionRev.1: Approval holder transfer from ALTITUDE AEROSPACE INTERIORS Ltd toAIM AVIATION (JECCO) LIMITED	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-101 Issue 1 issued for project 0010025795Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	- Master Data List: MDL 22001134_F- Summary Report: 21001390_C- Flight Manual Supplement: FMA 63001843_C- Maintenance Planning Document Supplement TM 61001092_Bor later revisions of the above listed documents approved by EASA.	- As per Flight Manual Supplement: FMA 63001843_C / Section1Certificate Limitations- As per Maintenance Planning Document Supplement TM 61001092_B /Section 9 Airworthiness Limitations (AWLs) and Certification MaintenanceRequirements (CMRs)- Only applicable for Serial Number 40119Prior to installati...	24/03/2017	Active	10055045
10055047	SABENA TECHNICS BGC			777-200/-200LR/-300/-300 ER	TCAS 7.1 Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, Aeroconseil document No. 0778-01-A-MDL-R00, Revision0<(>,<)> dated 25 April 2015.-Flight Crew Operating Manual Supplement, Aeroconseil document No.0778-01-AFCOMS<(>,<)> Revision 0, dated 24 May 2015- Instructions for Continued Airworthiness, Aeroconseil document No.0778-01-AICA-R00...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/10/2015	Active	10055047

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055048	SABENA TECHNICS BGC			767-200/-300/-300F/-400ER	TCAS 7.1 Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, Aeroconseil document No. 0732-01-A-MDL-R00, Revision0<(>,<)> dated 6 August 2015.-Aircraft Flight Manual Supplement, Aeroconseil document No. 0732-01-A-AFMS<(>,<)> Revision 0, dated 3 July 2015-Instructions for Continued Airworthiness, Aeroconseil document No. 0732-01-AICA-R00, Revi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/10/2015	Active	10055048
10055057	B/E AEROSPACE, Inc.		FAA STC ST04226AT	737-600/700/800/900/900ER	Installation of the B/E Aerospace LED Lights in the Main Cabin.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amdt. 4 for affected area.The requirements for environmental protection and the associatedcertified noiseand/ or emissions levels of the original product areunchange...	Master Drawing List 2-153358-001 rev B dated Sept 2, 2015Weight and Balance change record 2-1553358-902 rev A dated Aug14, 2015Instructions for Continued Airworthiness 2-1553358-804 rev A dated Aug14, 2015or later revisions of the above listed documents approved by EASA inaccordance with EASA ED De...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/10/2015	Active	10055057
10055068	WHELEN ENGINEERING COMPANY Inc.		FAA STC SA800EA	SEE EASA APPROVED MODEL LIST	EASA validation of FAA STC SA800EA: Installation of WhelenAnti-Collision, Position, or Antidesign change clear) Collision/Position Light System- limited to EASA GA aeroplanes (Approved Model List)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Whelen Anti-Collision Light Systems Installation and Service Manual,Document No. 05131, Rev. D dated May 2015 or later approved revisionor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or th...	Limited to EASA Approved Model List (attached)Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	09/10/2015	Active	10055068
10055075	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04294AT-D	GVI (G650)	Installation of AirCell ATG-4000 High Speed Internet (AHSI)system.This modification provides a high speed two-way dataconnection from theairborne aircraft to the internet via a network of terrestrialtransceiver sites. The systems consists of an Air-To-Ground (ATG) receiver-transmitter, two antennas...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	- Index List, ref :GDL100000014, dated 18 April 2015- Airplane Flight Manual Supplement, ref : GC61302M001, dated 23 April2015- Instruction for Continued Airworthiness, ref : CE61203A001 Revision D,dated 16 March 2015or later revisions of the above listed documents approved by EASA inaccordance with...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/02/2017	Active	10055075
10055077	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST03458CH	A320-214 A319-112/-115	Installation of a Passenger Cabin IFE Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, Document No. DC104-9505-00, Revision B, dated May 22,2015or later FAA approved revisions	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Flight Manual Supplement, Armstrong Aerosp...	09/10/2015	Active	10055077

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055080	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 2		A340-642	Installation of Economy Class Seats and Power Supply Systemfor VirginAtlantic Airways.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0509-D91, Revision -, dated 29 November 2015.- Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0509-D70, Revision A,dated 17September 2015or later revisions of the above listed...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/11/2016	Active	10055080
10055082	JET AVIATION ST. LOUIS, Inc.		FAA ST02910CH-D	BD-700-1A10, BD-700-1A11	Installation of a 3-Place Divan	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01 INJURY CRITERIA FORSIDE FACING DIVANS (SOFAS).The requirements for environmental protection and the associatedcertified noise and/ or emissi...	JET AVIATION ST. LOUIS INC. INDEX LIST No. 35-299G035 REV NC DATED 26MAY 2012.	Jet Aviation St. Louis inc. Installation limitations and follow-onapplicability requirements document no. 35-169e032 Rev A dated 26 May2012 is required.	12/10/2015	Active	10055082
10055084	ESG ELEKTRONIKSYS TEM-UND LOGISTIK-GmbH	REV. 2		EC635 T3 EC635 T1, EC635 T2+, EC635 T3 EC635 P2+, EC635 P3 EC635 P2+, EC135 P3, EC635 P3 EC135 T2+, EC635 T2+, EC135 T3 EC135 T2+, EC135 T3 EC135 T1, EC635 T1, EC135 T2 EC135 T1, EC135 T2 EC135 P2+ EC135 P3 EC135 P1, EC135 P2, EC135 P2+ EC135 P1, EC135 P2	Mission Management System WorkstationInitial IssueInstallation of a Mission Management System (MMS) Workstation to supportsurveillance, utility survey and search<(>&<)>rescue missionsRevision 1Extension of the installation range of Operator Console by removal ofthe forward positioning limitationRevi...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Rotorcraft Flight Manual Supplement 0022-DO-MZ-FMS-00 Issue 02- Master Drawing List 0022-DO-MZ-MDL-00 Issue 20- Meansof Compliance Records 00059-DO-MZ-MOCR-000 Issue 02- Instructions for Continued Airworthiness 0022-DO-MZ-ICA-00 Issue 12or later revisions of the above listed document(s) approved/...	Prior to installation of this change it must be determined that theinterrelationship between this change and any other previously installedchange and/ or repair will introduce no adverse effect upon theairworthiness of the product.	25/05/2022	Active	10055084
10055102	NORTHERN AVIONICS S.R.L.			45	Northern Avionics Waves: wireless in-flight entertainmentsystem/Installation of entertainment system platform with a Wi-Fi router that enables a wireless LAN onboard the aircraft,to which passengers can connect their own personal PEDs	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt.14 for 25.301, 25.305, 25.561, 25.581, 25.601,25.603,25.605,25.609,25.613,25.625, 25 .771, 25.853<(>,<)>25.869,25.899, 25.1301, 25.1309, 25.1322,25.1351, 25.135...	Aircraft Flight Manual Supplement AFMS NAV-0491, Rev. 0 - WavES dated02/09/2015or later revisions of the above listed documents approved by EASA.Northern Avionics doc. MDL0491 Rev. 0 Master Document List, dated 05/10/2015Northern Avionics doc. ICA-NAV0491 - Instructions for ContinuousAirworthiness W...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	13/10/2015	Active	10055102
10055109	HELI-ONE		TCCA STC SH08-27	S-76A, S-76C	Installation of Baro Altitude Display Mode Switch in accordance withAvionics Design Services Ltd. Master Drawing List MDL08043	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Master Drawing List MDL08043, Revision BMaintenance Manual Supplement HCS76340101-730, Revision 2	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/10/2015	Active	10055109

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055111	VAN RIEMSDIJK ROTTERDAM B.V.			747-8F 747-400F 747-400 (BCF)	PZE-0581 Pallet (196”x125”)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Declaration of Design and Performance - DDP150581 Issue 4Compliance Record - CR-150581 Issue 2or later revisions of the above listed documents approved by EASA.	As per:- Section 9 - Limitations / DECLARATION OF DESIGN AND PERFORMANCE - DDP150581 Issue 4Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse ef...	14/10/2015	Active	10055111
10055112	SABENA TECHNICS BGC			ATR 72-212 A ATR 72-211/-212 ATR 72-201/-202 ATR 72-101/-102	Second Mode S installation with ELS/ EHS upgrade – upgrade to TCAS 7.1 onATR (ACAS II 7.0 upgrade)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Applicable regulations at CS 25 Amendment 4 (referto associatedCertification Plan 0762-01-A-CP-R01, section 5& 6, for details)The requirements for environmental protect...	Master Data List, ref: 0762-01-A-MDL-R00Instruction for Continued Airworthiness, ref: 0762-01-A-ICA-R01Aircraft Flight Manual Supplement, ref: 0762-01-A-AFMS-R00or later revisionsof the above listed documents approved by EASA.	As per design of this STC, the following modifications needto beinstalled, and are pre-requisites for the installationof this STCa) STC SA8074SW, Collins TCAS II single Mode Sb)MPC installation (SB ATR72-31-1051) and the HT1000 FMS installation(SB ATR72-34-1036Prior to installation of this design...	14/10/2015	Active	10055112
10055113	AMAC AEROSPACE SWITZERLAND AG			A340-212	Large Monitor Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-01/10037430 Glass Screens Displays / MonitorsThe requirements for environmental protection and the associatedcertified noise and/ or emissions l...	Master Data List MDL-ES01-2500 Rev. B dtd. 13.10.2015or later revisions of the above listed documents approved by EASA.	The installation of this STC is limited to MSN 009.	14/10/2015	Active	10055113
10055115	AERODATA AG			ATR 42-500	EFIS interface for AeroFIS system on an ATR 42-500The scopeof this approval is the operation of the ATR 42-500 with thecapability of display on the flight deck EFIS (Electronic FlightInstrument System) of the navigation information issuedby a FlightInspection System (AeroFIS), for the purpose of c...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:All affected requirements (see Compliance Summary) at amendment 4 of CS25, as an elect to comply.The requirements for envir...	Airplane Flight Manual Supplement, Aerodata reference AFM-138 rev. 0or later revisions of the above listed documents approved by EASA.Compliance Summary, Aerodata reference CS-ATR42-01.01 rev. 0 dated24-Sep-2015.Master Document List, Aerodata reference MDL-A/C-847 rev 3 – dated13-Oct-2015.Declaratio...	1. This approval is limited to ATR 42-500 aircraft MSN 673.2. The aircraft must have the following modifications already embodied(prerequisite configuration):- EASA STC 10047498 rev. 1 (Integration of a Flight Inspection Systeminto an ATR 42-500)- Aerodata minor change MCA-ATR42-01.02 rev. 2 (Provis...	14/10/2015	Active	10055115
10055127	AMAC AEROSPACE SWITZERLAND AG			A340-212	Tailwind 550 SAT TV Antenna Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List MDL-ES01-4420 Rev. B dtd. 14-Oct-2015Airplane Flight Manual Supplement AFMS-ES01-4420 Rev. A dtd. 29-Sep-2015Instructions for Continued Airworthiness ICA-ES01-4420 Rev. A dtd. 01-Okt-2015or later revisions of the above listed documents approved by EASA.	-Per Airplane Flight Manual Supplement AFMS-ES01-4420 and Instructionsfor Continued Airworthiness ICA-ES01-4420-The installation of this STC is limited to MSN 009Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprevio...	15/10/2015	Active	10055127
10055130	SCANDINAVIAN AVIONICS DESIGN ApS			SEE EASA APPROVED MODEL LIST	Replacement of existing TCAS 7.0 by TCAS 7.1 in accordance withScandinavia Avionics Design document 2097492 DOC, at issue 1, datedOctober 9, 2015;	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplements, Scandinavia Avionics Designdocuments-2097492-AM A, at issue 1, dated September 3, 2015, for aircraftequipped with Honeywell TPA-100B TCAS II Processor;-2097492-AM B at issue 2, dated September 17, 2015, for aircraftequipped with ACSS TCAS 2000 RT950/RT-951 Process...	None	15/10/2015	Active	10055130

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055137	STANDARD AERO	REV. 1	FAA ST03158CH-D	EMB-145LR/ EMB-145MP EMB-145EP/ EMB-145ER EMB-135ER/ EMB-135LR/ EMB-145	Installation of a Reconfiguration of a Cabin Floorplan.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. StandardAero Master Data List 1023033 Rev (J), dated 4 February 2019or later FAA approved revision.2. Airplane Flight Manual Supplement document number 1023399 Rev (B),dated 4 November 2015 or later FAA approved revision.3. Airplane Flight Manual Supplement document number 1035666 Rev (A),dated 7...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/03/2019	Active	10055137
10055144	DIAMOND J, Inc.		FAA STC SR2531LA	407	Installation of anyone, or a combination of the eight Diamond J Inc.propulsion system indicators. See continuation in Appendix for indicatorpart numbers	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable for thiscertificate/approval.	Diamond J Inc. top drawing 24070, dated November 10, 2014Rotorcraft Flight Manual Supplements and Instructions for ContinuedAirworthiness as defined in Appendix.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	13/11/2015	Active	10055144
10055161	BLACKHAWK MODIFICATIONS Inc.			208B 208	Replacement of the original Cessna 208 and 208B Starter/Generator withan AMETEK 325 Amp. Starter/Generator (MG94K-2) and associated equipment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:FAR-23Amdt. 34: 23.1Amdt. 42: 23.1163Amdt. 49: 23.1359Amdt. 50: 23.1581Amdt. 51: 23.1041, 23.1043, 23.1045Amdt. 53: 23.901T...	Master Drawing List 201207-000, Rev. IR, dated May 30, 2014Airplane Flight Manual Supplement 201207, IR, dated August 27, 2014, FAAapproved November 6, 2014or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisU...	1. This modification must be installed in conjunction with Blackhawk STCSA02467LA (EASA STC 10047057) for Cessna 208 orBlackhawk STC SA02357LA(EASA STC 10036469) for Cessna 208B.2. This modification and applicable supplements must be accompanied bythe POH and FAA approved AFM D1307-34-13PH or D1352...	16/10/2015	Active	10055161
10055165	AEROTEC & CONCEPT			B200GT	MOD 15005 - Beech 200 GPS antenna array installation for goniometry missionsNEW-PAGE	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Instructions for Continued Airworthiness AE150051CA Rev 0 dated11/09/2015Master data List AE15005MDL Rev 0 dated 13/10/2015or later revisions of the above listed documents approved by EASA	Limitation to B200GT serial number BY-91 .STC EASA 10030456is a prerequisite for this STC.Activation of the system must be approved by a separate approval.	16/10/2015	Active	10055165
10055169	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR01928NY	412EP 412	Installation of Emergency Floatation System on Bell 412, 412EPHelicopters in accordance with Agusta Emergency Floatation System KitP/N 412-4600-04, Rev. DI	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA approved Rotorcraft Flight Manual Supplement for Bell HelicopterTextron model 412 with Agusta Emergency FloatationSystem Kit P/ N412-4600-04, AWPC-ENG-16-011, Rev. 0or later revisions of the above listed documents approved by EASA.Helicopter Bell model 412 Instructions for Continued Airworthine...	None	17/03/2016	Active	10055169
10055175	MECAER AVIATION GROUP S.p.A.	REV. 2		MBB-BK117 D-3 MBB-BK117 D-2 MBB-BK 117 D-2	VIP MB Style Interiors P/N 6EC10000X002001.The change consists of passenger cabin interior VIP customization, seatslayout, separation walls, small cabinets, entertainment system and otherminor items as detailed in the configuration description documents.Revision 1 is to add compatibility with the Je...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:for MBB-BK117 D-2:CS 29 Amdt. 2:CS 29.1, CS 29.27, CS 29.29, CS 29.251, CS 29.301, CS 29.303, CS 29.305,CS 29.307 a), CS 29...	- Rotorcraft Flight Manual Supplement for “H145 VIP MB Interiors P/ N6EC10000X002001”< (>,<)>Supplement Number 6EC1RFM-1-2, Issue 1 Rev. 0;- Owner's Manual (Instructions for Continued Airworthiness), P/ N6EC1WNM-2-2, Issue 2 Rev. 17;Applicable to the original STC:- Configuration Description, Document N...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/10/2020	Active	10055175

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055183	WHELEN AEROSPACE TECHNOLOGIES LLC	REV. 2	FAA STC SA02279AT	SEE FAA AML SEE EASA APPROVED MODEL LIST	Installation of HID Landing and Taxi Lights	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Drawing List Report Number 43, Revision F, dated 15 July 2002or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	The STC is valid for aircraft types and models approved by EASA andlisted on the latest approved FAA Aircraft Model List.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairand any otherpreviously installed change and/ or repair will...	26/03/2021	Active	10055183
10055184	BELL HELICOPTER TEXTRON, Inc.	REV. 1	FAA SR01052AT	BELL 412, BELL 412EP BELL 205A-1, BELL 212 AB412, AB412EP	Replacement High Skid Landing Gear Crosstubes for Bell HelicopterTextron Models 205A-1, 212, 412, 412EP, and LEONARDO S.p.A. ModelsAB412, AB412EP helicopters.Revision 1 of this approval is published to correct a typo of theapproved LEONARDO S.p.A. models.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness Crosstubes AA-01136 Rev. L,dated July 30, 2012;or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/ CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USAD...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/03/2017	Active	10055184
10055190	FEDERATION FRANCAISE DE VOL A VOILE (FFVV)			201 A, 201 B, 201 B1	Polyurethane paint on gliders C201 "Marianne" A, B<(>,<)> B1 series	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levelsremain applicable to this certificate/ approval	BS FFVV 02/2015· edition 1 dated 19/10/2015or later revisions of the above listed documents approved byEASA.	None	23/10/2015	Active	10055190
10055191	SABENA TECHNICS BGC			ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW (195 AR) ERJ 190-100 STD ERJ 190-100 SR ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ (LINEAGE 1000)	Aeroconseil Supplemental Type Certificate STC 0689-01: Mechanical andelectrical installation for personal tablet computer on E190 familyaircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):-H-01 “Enhanced AirworthinessProgramme for Aeroplane Systems - ICA onEWIS”-E-08 “Engine Sustained Imbalance”All applicable paragraphs according to CS...	-Aeroconseil Master Data List ref. 0689-01-A-2103 Rev. 01 dated 20October 2015, and-Aeroconseil AFM Supplement ref. 0689-01-A-2301 Rev. 01 dated 16 October2015, and-Aeroconseil Instruction for Continued Airworthiness (ICA) ref.0689-01-A-2211 Rev. 00 dated 29 July 2015or later revisions of the above...	The limitations as identified in the AFM Supplement are applicable.The mechanical and electrical installation of this STC shall only beused for portable EFBs. It is the operator’sresponsibility to apply forthe operational assessment of EFB at its National Aviation Authorities.The portable EFB shall...	21/10/2015	Active	10055191
10055193	JET AVIATION AG	REV. 3		A320-214	Transfer of STC 10055193 Rev. 2 to new holderVIP Interior Installation A320-214	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-2302-XXX Isolated CompartmentsCRI D-2310-XXX Glass Screens of Displays and MonitorsDeviation(s):CRI D-2324-XXX Single Non-Smoking PlacardCRI D-2...	-JBSC-M-00001AFM-01 Issue 1 Airplane Flight Manual Supplement-JBSC-M-00001ECA-01 Issue 1 EWIS Instruction for Cont. Airworthiness-JBSC-M-00001ICA-01 Issue 1 Instruction for Cont. Airworthiness-The following ICA documents contain Airworthiness Limitations:JBSC-M-00001ICA-08 Issue 1 Iridium antenna in...	Limited to S/N 6285	10/10/2017	Active	10055193
10055196	SABENA TECHNICS BGC	REV. 1		A320-231/-232/-233 A320-211/-212/-214/-215/-216	GEE Broadband System Activation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Applicable regulations at CS 25 Amendment 4 & 8 (refer to associatedCertification Plan 0695-01-A-2101-R02 and0695-01-A-2101-F-01-R00,section 4 & 5<(>,<)> for details)The...	-Master Data List, Aeroconseil document No. 0695-01-A-2103,Revision 2,dated 18 December 2015.-Aircraft Flight Manual Supplement, Aeroconseil document No.0695-01-A-2301, Revision 2, dated 17 December 2015-Instructions for Continued Airworthiness, Aeroconseil document No.0695-01-A-2211, Revision 3, d...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.,,	21/12/2015	Active	10055196

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055197	SABENA TECHNICS BGC	REV. 2		A320-216, -231, -232, -233 A320-211, -212, -214, -215	Ku-band Antenna Provisions Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRIB-0301-001 (Vibration/buffeting compliance criteria for large externalantenna installation).The requirements for environmental protection and the associatedcertified n...	Master Data List, Aeroconseil document No. 0736-01-A-2103, Revision 1,dated 18 February 2016.Instructions for ContinuedAirworthiness, Aeroconseil document No. 0736-01-A-2211, Revision 1, dated 19 October 2015 for airplanes modifiedas per “configuration 1” installation design (as approved by the init...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/03/2016	Active	10055197
10055203	MONARCH AIRCRAFT ENGINEERING LTD		CAA UK RESPONSIBILITY	A321-231	214 PASSENGER RECONFIGURATION	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MONARCH DESIGN SERVICES MASTER DOCUMENT LIST NO. MON/320/25/MDL/ 3474ISSUE C	None	22/10/2015	Active	10055203
10055204	AVIONIK STRAUBING ENTWICKLUNGS GmbH			CABRI G2	Installation of Aspen EFD1000H flight display and Mid-Continent 4300-311attitude indicator, in accordance with Avionik Straubing Entwicklungsmodification file no. ASR-2014-045	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27 amdt. 3, § 307, 561, 603, 605, 607, 609, 610, 611, 613, 619, 671,771, 773, 777, 863, 1301, 1303, 1309, 1321, 1322, 1323, 1325, 1327,1351, 1353, 1357, 1365, 1367, 138...	Flight Manual Supplement No. ASR-2014-045-FMS-05-00 initialissue dated12/09/2014or later revisions of the above listeddocuments approved by EASA.Master Document List No. ASR-2014-045-MDL-01-00 dated 12/09/2014Instructions for Continued Airworthiness No. ASR-2014-045-ICA-11-00dated 12/09/2014Instru...	1) This installation is limited to VFR operations.2) The aircraft must be equipped with airspeed, altitude, attitude andvertical speed indicators independent from the EFD1000H display.3) For night VFR operations the aircraft must be equipped with anelectro-mechanical attitude indicator independent f...	22/10/2015	Active	10055204
10055205	S4A SOLUTIONS FOR AVIATION, S.L			BN2A-21	Installation of Mission Equipment incl. Ballasts on the Empennage inaccordance with S4A Master Drawing List BN003-RPT02.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amdt. 4:23.1, 23.3, 23.21(a), 23.25(a)(b), 23.251, 23.301(a)(b)(c), 23.303,23.305(a)(b), 23.307(a), 23.321(a), 23.337(a)(b)(c), 23.341 (c), 23.471,23.561(a)(b3)(c)(e)...	Flight Manual Supplement BN003-HDK01, issue 1, dated 23 September 2015or later revisions of the above listed documents approved by EASA.Maintenance Manual Supplement BN003-HDK02Wiring Manual Supplement BN003-HDK03IPC Supplement BN003-HDK04	Limited to BN2A-21, S/N: 523 and 531Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	22/10/2015	Active	10055205
10055227	TENENCIA Ltd.		CAA UK RESPONSIBILITY	737-800	Cabin Configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Tenencia Modification TEN 785Boeing 737-800 Cabin Configuration Issue 1 dated 22 October 2015	Restricted to ASN 37750	23/10/2015	Active	10055227
10055228	APTOZ EHF.	REV. 1		757-300 757-200/-300 757-200	Replace existing Audio Selector Panels with Gables Audio Control PanelsP/N G7257-04Rev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Change/Repair Approval, Icelandair document No. CRA-757-2350-10,Revision A, dated 21 October 2015-Continued Airworthiness Instructions, Icelandair document No.CAI-757-2350-10, Revision IR, dated 10 July 2014-Aircraft Flight Manual Supplement, Icelandair document No.AFM-757-2350-10, Revision IR, dat...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10055228

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055233	DASSAULT FALCON JET CORPORATION		FAA STC ST01774WI	MYSTÈRE-FALCON 900	Validation of FAA STC.Upgrade from a Honeywell Traffic Alert and Collision Avoidance SystemCAS-81 (TCAS II), to a Honeywell Traffic Alert and Collision AvoidanceSystem CAS-100 (TCAS II version 7.1).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.1316, CS 25.1317 at Amendment 17 for the areas modified oraffected by this changeThe requirements for environmental protection and the associatedcertified noise and/...	Airplane Flight Manual Supplement ref. EDOC-0000017415 revision A, dated9 February 2015.or later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USAM...	Applicability is limited to MF900 model.The pre-requisite for this approval is the EASA approval ref. 10055239.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will in...	26/10/2015	Active	10055233
10055234	ACC COLUMBIA Jet Service GmbH	REV. 1	LBA EMZ SA 1154	DR 400/180 S DR 400/180 R DR 400/180	GO2015-57 DR 400 Exhaust SystemRev. 1 Transfer to ACC Columbia Jet Service GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels:CS-36 Amdt. 3	According to Gomolzig Master Document List No.MDOCL_2037202_rev0 _20150915To be operated in accordance with Gomolzig AFM-S Document No.SPOH_2037202_DR40 0_180R_rev0_20150915 andSPOH_2037202_DR40 0_180_180S_rev0_201509 15or later revisions of the above listed documents approved by EASATo be installed iaw...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/01/2022	Active	10055234
10055235	L'ATELIER DE LA MONTGOLFIERE			FIREFLY 8	STC ADLM 01-2015Schroeder fire balloon bottom end installation under Firefly 8 enveloppe	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplément manuel de vol F-GZAP selon STC ADLM 01-2015or later revisions of the above listed documents approved by EASA.	Modification limited to Balloon Firefly 8 sn F8-2022	26/10/2015	Active	10055235
10055239	DASSAULT FALCON JET		FAA STC SA7306SW-D	MYSTÈRE-FALCON 900	Installation of Bendix CAS-81 TCAS System on MF900	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement, Report No. 36255-1, Rev. C dated 21August 1995.Airplane Flight Manual Supplement, Report No. 36255-2, Rev. NC dated 24March 2000.Airplane Flight Manual Supplement, Report No. 36255-3, Rev. NC dated 07September 2000or later revisions of the above listed documents app...	Applicability is limited to MF900 model.The EASA approval ref. 10055239 cannot be installed as a finalconfiguration, but only as pre-requisite for the EASA approval ref.10055233.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and...	26/10/2015	Active	10055239
10055241	I.S.E.I INTERNATIONAL SERVICESELECT RONIQUE INFORMATIQUE			172S 172R	Installation of SAFETYPLANE V5 System	CRI F-01 issue 03 Lithium Battery InstallationsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	List of Documents Project 0010039455-001 N10 - Cessna 172R-S-SAFETYPLANEV5 Edit A Revision 02 dated 7 October 2015N11-Cessna 172R-S-SPV5-AEROPLANE FLIGHT MANUAL SUPPLEMENT-E-A-01 Rev.00dated 06 August 2015or later revisions of the above listed documents approved by EASA.	None	26/10/2015	Active	10055241

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055247	S-TEC CORPORATION	REV. 1	FAA STC SA09192AC-D	185E, A185E, A185F 185, 185A, 185B, 185C, 185D	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem., Model ST-650	The Certification Basis (CB) fir the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval...	Bulletin No. 750, Revision 4, dated 4-25-01 and Master Drawing List No. 92963 Revision D, dated 4-25-01 (14 Volt System).	1. Also eligible on the above models (landplane, floatplaneoramphibian) when equipped with STC SA1441WE (Robertson STOL) or STCSA968CE (Horton STOL) and/or STC SA2529WE (internaltip tanks).2. FAA/DAS approved Supplemental Flight Manual, P/N 891314, dated11-06-96 is required for Cessna Models 185,1...	18/12/2015	Active	10055247
10055250	MT-PROPELLER ENTWICKLUNG GmbH			SR20	Installation of 3-blade propeller MTV-12-D/188-59b on Cirrus SR20	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels:CS-36 Amdt. 3 and FAR 36 Amdt. 30	According to MT-Propeller Master Document List No. E-2607Tobe operated in accordance with MT-Propeller AFM-S Document No. E-2603or later revisions of the above listed documents approved by EASA.To be installed iaw. Installation Instructions Doc. No. E-2604, or laterRevisionsTo be maintained i.a.w.R...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	09/11/2015	Active	10055250
10055251	MT-PROPELLER ENTWICKLUNG GmbH			DR 400/RP DR 400/200 R DR 400/180 R DR 400/140 B DR 400/120 D	Installation of 3-blade constant speed propeller MTV-6-A/190-69 onC.E.A.P.R. DR400 series modified with TAE-125-02-114 engine per STC10014219	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels:CS-36 Amdt. 3 and FAR 36 Amdt. 30	According to MT-Propeller Master Document List No. E-2711Tobe operated in accordance with MT-Propeller AFM-S Document No. E-2708or later revisions of the above listed documents approved by EASATo be installed iaw. Installation Instructions Doc. No. E-2709, or laterRevisionsTo be maintained i.a.w. M...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	26/10/2015	Active	10055251
10055257	AVIATION DEFENSE SERVICE			SR22	AVD-MSR22-95-ISR4A Iss01 dated 12/10/2015 - Activation of ISR mission systemNEW-PAGE	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Instructions for Continued Airworthiness ICA-AVD-SR22-ISRissue 01 dated 14 September 2015Master Document List MDL_AVD_ISR4a dated 12 October 2015POH and EASA approved AFM supplement SAFM-AVD-SR22-ISRRevision 01 dated 12 October 2015or later revisions of the above listed documents approved by EASA.	Limitation to Cirrus SR22 G5 from serial number 3026 and subsequentequipped with Perspective avionics.AvDef STC AVD-MSR22-95-ISR3A must be installed on the airframe.	27/10/2015	Active	10055257
10055258	AVIATION DEFENSE SERVICE	REV. 2		SR22	AVD-MSR22-95-ISR3A Issue 01 dated 12/10/2015 - Carriage of ISR missionexternal loads	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/approval	Instruction for continued Airworthiness ICA-AVD-SR22-ISR issue 01 dated14 September 2015Master Document List MDL-AVD-ISR3A dated 12 October 2015POH and EASA approved AFM supplement SAFM-AVD-SR22-ISR Revision 01 dated12 October 2015or laterrevisions of the above listed documents approved by EASA	Limitation to SR22 G3 serial numbers 2334, 2420 and 2438 thru 3914 andSR22 G5 from serial number 3915 and subsequent. Cirrus structureprovisions CM00001365 must be installed on the airframe.	10/11/2015	Active	10055258

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055270	MT-PROPELLER ENTWICKLUNG GmbH		LBA SA1263	F260, F260B, F260C, F260D	Installation of 3-blade constant speed propeller MTV-9-B/188-50 onAlenia Airmacchi F260 series	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels:CS-36 Amdt. 3 and FAR 36 Amdt. 30	According to MT-Propeller Master Document List No. E-2732Tobe operated in accordance with MT-Propeller AFM-S Document No. E-784or later revisions of the above listed documents approved by EASATo be installed iaw. Installation InstructionsDoc. No. E-783, or laterRevisionsTo be maintained i.a.w. MT-...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	27/10/2015	Active	10055270
10055273	HONEYWELL INTERNATIONAL, Inc.	REV. 1	FAA STC SR02461SE	AW139	Installation of a Honeywell ASPIRE 200 Intermediate Gain (IG) SATCOMsystem.	The Certification Basis (CB) fir the original product remains applicable to this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	1. Master Drawing List (MDL) MOD-AW139ASPIRE200-5201, Revision C, dated13 December 2016, or later FAA-approved revision.2. Instructions for Continued Airworthiness (ICA) documents<(>,<)> orlater FAA-accepted revision as applicable:ICA MOD-AW139ASPIRE200-7601, Revision E, dated 9 November 2016;ICA MO...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	06/07/2017	Active	10055273
10055274	NORTHERN AVIONICS S.R.L.			45 (LEARJET 45)	Aerowave 100 (In-Flight Internet/Satcom)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt. 14The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain appl...	CCL No. CCL0500-001 Rev. 0or later revisions of the above listed documents approved by EASA.	None	28/10/2015	Active	10055274
10055280	AEROLITE AG	REV. 1	FOCA 25-20-90	EC135 T3	Installation of EMS Equipment P/N 135490-501 in accordance with MasterDrawing List DWL-211This Major Change to STC applicable to EC135 T3 S/N 0259 only supersedesSTC FOCA-25-20-90.Revision 1: Change of STC holder from "Aerolite Max Bucher AG" to"Aerolite AG"	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement for Airbus Helicopters Model EC135T3 S/N 0259FMS-211 Rev. B, dated 13 October 2015or later revisions of the above listed documents approved by EASA-Airbus Helicopter EC135 S/N 0259 Master Document List MDL-211 Rev. B-Airbus Helicopter EC135 S/N 0259 Master Drawing List DWL-...	EMS Equipment P/N 135490-501 has only been installed into EC135 S/N 0259and no further or new delivery / installation is planned. This STC isapplicable to EC135 S/N 0259 only.The medical devices are considered as payload and their installation isperformed by the operator. The medical portable device...	15/02/2019	Active	10055280
10055282	SABENA TECHNICS BOD	REV. 4		A330-223	A330-223 Egide Safe Protection System (SPS) modification.This modification has been achieved in three phases.The initial phase has prepared the aircraft belly area to receive a podby relocating antennas, drain mast, and provisioning some otherequipment.The second phase has checked the functionalityT...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-4301-001: Vibration & Buffetingcompliance criteria for large external antenna installation.The requirements for environmental protection an...	- Modification Approval Sheet ref: MAS -00-4009 Issue 9, dated 19October 2016- Aircraft Flight Manual Supplement, ref: AFMS-F3042-00-065 issue E,dated 03 November 2016- Instruction for Continued Airworthiness, ref: ICA-F3042-00-003 IssueD,dated 26 October 2016- Weight and Balance Manual Supplement,...	The following modifications are prerequisites to this modificationembodiment:- EASA STC 10032391 rev 2 - P710 VIP CabinCompletion.- EASA STC 10031972 - Humidification System Installation.- EASA STC 10032264 (EASA validation of FAA STC ST02317LA) - Installation of Cabin interior Noise Reduction kit.-...	04/11/2016	Active	10055282
10055294	NATIONAL AIRCRAFT SERVICES, INC.		FAA STC ST01438CH	727-200, 727-200F 727-100, 727-100C	Install National Aircraft Service, Inc. Vent Door in a maincabin window of 727 airplanes, modified with a Cargo Doorper STC SA176SONEW-PAGE	The Certification Basis (CB) fir the original product remains applicable to this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approva...	National Aircraft Service Inc. Drawing List FXV-DL. 14, Rev.A, datedMarch 22, 2001Installation Manual FXV-727-14, No Rev, dated March 4, 2001 or laterFAA-Approved revision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.2. National Aircraft Service, Inc., Airplane F...	05/11/2015	Active	10055294

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055297	KELLY AEROSPACE THERMAL SYSTEMS, L.		FAA STC SA2006CH	SEE FAA AML REV. 7	Installation of air conditioning system	The Certification Basis (CB) for the original product remains applicable to this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Kelly Aerospace Installation Instructions as listed on AML No. SA2006CH.	1. Airplane Flight Manual Supplement as listed on the FAA Approved ModelList (AML) No. SA02006CH, is required on board the modified aircraft.2. Instructions for Continued Airworthiness (ICA) as listed on FAAApproved Model List (AML) No. SA02006CH, should be incorporated into theAircraft Maintenance3...	18/12/2015	Active	10055297
10055299	GYRO-STABILIZED SYSTEMS, LLC	REV. 2	FAA STC SR02447AK	R66	Installation of ZW Aviation LLC Utility Camera Mount in accordance withMaster Drawing List (MDL) R66M-010Revision 1: transfer of EASA STC 10055299 to different legal entityRevision 2: administrative re-issuance due to change of address	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement for the installation ofthe R66M-001Utility Camera Mount, document number R66M-007,revision IR, dated May13, 2015Master Drawing List (MDL) R66M-010, revision 3Instructions for Continued Airworthiness (ICA) R66M-008, revision 0or later revisions of the above liste...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/10/2022	Active	10055299
10055312	HELI-ONE		TCCA STC SH01-17	S-76A, S-76C	Installation of Water Activated Flotation System in accordance withHeli-One Master Drawing List CHS76-32-001 MDL	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS CHS76-32-001, Revision Aor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures ofEU/ CanadaBilateral Agreement.Master Drawing List CHS76-32-001 MDL, Revision BMaintenance Manual Supplement MMS CHS76-32...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/10/2015	Active	10055312
10055322	ALAMO ENGINEERING GmbH	REV. 2		HAWKER 1000	ACSS TCAS Change 7.1 Upgrade.TCAS II Change 7.1 Upgrade with P/N 4066010-914.TCAS 2000 RT-951 Change 7.1 Upgrade with P/N 7517900-55020.Revision 1: Transfer to 328 Support Services GmbHRevision 2: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AFM supplement AFMS022B344Z0002 Issue A released 29 Oct. 2015 for TCASII;AFM supplement AFMS022B344Z0001 Issue A released 18 Sept. 2015 for TCAS2000 Change 7.1;Master Data List MDL079Z001 Issue C from 30 Oct. 2015.Declaration of ComplianceIssue C from 30 Oct. 2015.Compliance Statements CS-22B079Z00...	The approval is limited to TCAS II Change 7.1 Upgrade with computer P/N4066010-914 and TCAS 2000 RT-951 Change 7.1 Upgrade with computer P/ N7517900-55020Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously inst...	05/11/2024	Active	10055322
10055330	BOND HELICOPTERS EUROPE Ltd.		CAA UK RESPONSIBILITY	EC135 T3(CPDS)	NVIS for HIOW Air Ambulance	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS27 Amendment 3: 27.1/27.1321/27.1322/27.1381/27.1383/27.1501/27.1525/27.1529/27.1581/27.1583/ 27.1585Appendix A: A27.1/A...	- Flight Manual Supplement for HIOW FMS/115-002 - Issue 2,dated 21October 2015.or later revisions of the above listeddocuments approved by EASA.- Design Report DR/ 115-001- Issue 1, dated 16 September 2015.- Instructions for Continued Airworthiness: BOND/MOD/ 115, HIOW AirAmbulance, NVIS, EC135 - I...	Any subsequent deviation from the cockpit or cabin configurationspecified in the STC Type Design may affect the compatibility of theNVIS and will require an engineering evaluationto assess the effect ofthe change on NVG compatibility.The engineering evaluation must be approved by the aircraftcertif...	02/11/2015	Active	10055330

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055335	AIR ALLIANCE GmbH			LEARJET 55/55B/55C LEARJET 31/31A/35/35A	Operation of TCAS II Change 7.1Software Upgrade from TCAS II Version 7.0 to 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval	Air Alliance Aeroplane Flight Manual Supplement, doc. No. 2015_014_LJ3X_0506_rev. 01, dated 27 October 2015.or later revisions of the above listed documents approved by EASA.Air Alliance Master Document List, doc. No. 2015_014_LJ3X_Form 2, rev.01, dated 02 November 2015	None	02/11/2015	Active	10055335
10055372	S-TEC CORPORATION		FAA STC SA09342AC-D	H35, J35, K35, M35, N35, P35	Installation of S-TEC System 20/30 Single and Two Axis Automatic FlightGuidance Systems, Model ST-773-20/30.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Bulletin No. 873, dated 2-16-98Master Drawing List No. 921076, dated 2-16-98	1. FAA/DAS approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement P/N 891670, dated 2-20-98 is required for Beech ModelsH35, J35, K35, M35, N35, and P35 for S-TEC System 20.2. FAA/DAS approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement. P/N 891671, datedM...	18/12/2015	Active	10055372
10055381	RHEINLAND AIR SERVICE GmbH	REV. 1		C90, C90A, C90GT, C90GTI	Installation of Dual Garmin G600 System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 323, 29, 301, 303, 305, 307, 561,601, 603, 605, 609, 611, 613, 771, 773,777, 867, 1301, 1303, 1305, 1309, 1311, 1321, 1322, 1323, 1325, 1326,1327, 1329,1...	Flight Manual Supplement G600 RAS-14-01-02-FMS-00 G600, Rev. 0Flight Manual Supplement ESI-2000 RAS-14-01-02-FMS-00 ESI2000, Rev. 0Flight Manual Supplement PS835D RAS-14-01-02-FMS-00 PS-835D, Rev. 0or later revisions of the above listed documents approved by EASA.Instructions for Continued Airworthi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/02/2016	Active	10055381
10055382	ONBOARD SYSTEMS INTERNATIONAL		FAA SR0244SE	R 66	Cargo Hook Kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement Onboard Systems Cargo HookSuspension System for the Robinson R66 121-058-00, Rev. 0, dated 20 July2015 or later revisions of the above listed documents approved by EASAin accordance with EASA ED Decision2004/04/CF (or subsequent revisionsof this decision) and/ or...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/11/2015	Active	10055382
10055385	AERODATA AG			B300	Installation of AD-AFIS-0130 in B300	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 23.1, 23.3(d),23.25 (a)(2), 23.29, 23.251, 23.301(a) and (c), 23.303, 23.305<(>,<) >23.307, 23.337(a) and (b), 23.341(a) and...	Installation, Operation and Maintenance according to the Master DrawingList document number MDL-A/C-872 Rev. 2 dated 2nd November 2015 or laterrevisions of the above listed documents approved by EASA.	- Limited to model B300 with installed Rockwell Collins Proline21avionics and Slick Interior only.- The document AMM-1155 Rev.0 (dated 29th September 2015) Chapter 04defines additional Airworthiness Limitations applicable- The document AFM-150 Rev. 1 Chapter 02 defines the additionalOperational Limi...	05/11/2015	Active	10055385
10055386	HELI-ONE		TCCA STC SH07-30	S-76C	Installation of Flight Data Monitoring System in accordancewithHeli-One Approval Control Document CHS76-31-013 ACD	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Approval Control Document CHS76-31-013 ACD, Revision IMaintenance Manual Supplement MMS CHS76-31-013, Revision A	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/11/2015	Active	10055386

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055388	JET AVIATION ST. LOUIS, Inc.		FAA ST02664CH-D	BD-700-1A11	Installation of a Wireless Local Area Network (WLAN)	The Certification Basis (CB) for the original product remains applicable to this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Master Data List 35-409G003, Revision D, dated January 26, 2009. The FAAapproved AFMS document defined by the Master Data List is required.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	13/11/2015	Active	10055388
10055420	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A340-313	SAS A340-300 Cabin reconfigurationReplacement of Business, Premium Economy and Economy Class seats,galleys, stowages, IFE and ISPSS. Relocation of mid cabin lavatories,rework of cabin crew rest module.Rev.1: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.	Aircraft Flight Manual Supplement S.OAED. 000301-AFM, rev 00Master Document List S.OAED. 000301-MDL, rev 00Instructions for Continued Airworthiness S.OAED.000301-ICA, rev 00	Cabin Attendant Information Panel (AIP) smoke detection alerts for twolavatories are incorrectly identified within the CIDS system, namely,lavatory L35 appears as L37 and L36 appears as L38. OVHD loudspeakers inthe Economy Class do not function properly during video announcementwith the design solut...	20/04/2021	Active	10055420
10055429	KNSI AVIATION ENGINEERING LIMITED		CAA UK RESPONSIBILITY	757-200	Replacement of Business Class and Economy Class Seats	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	KNSI Master Document List No.14K055-MDL-001-5.R Revision 5 dated 01October 2015	Restricted to ASN 23453 and 26246	09/11/2015	Active	10055429
10055440	THALES AVIONICS Inc.		FAA STC ST02151LA	A340-541, A340-642	Installation of Thales Avionics TopSeries i-4000 Inflight EntertainmentSystem.	The Certification Basis (CB) for the original product remains applicable to this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Thales Avionics Index List, Drawing No. 25678, Revision "A", dated June16, 2008Instruction for Continued Airworthiness (ICA), Thales Avionics Inc.Document No. 250868, Rev. N, dated March 15< (>,<)> 2010	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.This modification may not be installed after Augu...	13/11/2015	Active	10055440
10055443	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC ST02530LA	SEE APPROVED MODEL LIST	Installation of T2CAS with TCAS version 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ACSS document 8900044-001 rev -or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/11/2015	Active	10055443
10055445	ONTIC ENGINEERING ANDMANUFACTURING, Inc.		FAA STC SA3468NM	727-200 727-100	Installation of a 2300-07-01 or 2307-02-1 or 237-03-1 digital FuelQuantity gauge System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Smiths Industries Master Drawing 0015-ED rev. V, dated July7, 1995Smiths Industries Airplane Flight Manual Supplement No. 0021-ED RevisionF, dated September 13, 1995or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisio...	Aircraft which incorporate a 2-cell centre tank are not approved underthis STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	10/11/2015	Active	10055445

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055447	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC ST02543LA	767-200/-300/-400ER SERIES	Installation of Dart Aerospace Evacuation Slide/Raft Modification KitPart Number 603.8403.	The Certification Basis (CB) for the original product remains applicable to this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Dart Aerospace Master Document List MD767-1, Revision F, dated August12, 2015	This Dart Aerospace Evacuation Slide/Raft Modification Kit Part Number603.8403 installation is limited to the Goodrich FWD/ AFT evacuationslide/raft Part Number 101651-303.The Instructions for Continued Airworthiness (ICA) Dart AerospaceDocument No. ICA767-1, Revision N/C, dated January 27, 2015 or l...	17/11/2015	Active	10055447
10055463	MARSHALL AVIATION SERVICES LIMITED		CAA UK RESPONSIBILITY	BAE 146 SERIES 300 BAE 146 SERIES 200 BAE 146 SERIES 100	To Introduce Universal UNS-1Fw Flight Management System as an Upgrade tothe Existing UNS-1L Currently Installed on BAe 146 Series Aircraft UnderEASA.A.S.02689	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25 Change 13JAR 25.1322JAR 25.1431JAR 25.1529The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the originalu...	Marshall AFM 5.1 Supplement 1 Issue 1 – Flight Manual Supplement –Universal UNS-1FwFlight Management Systemor later revisions of the above listed documents approved by EASA.The applicable documents and drawings detailed in Marshall Change No.SC0542B Issue 2	Applicable to BAe 146 series aircraft previously modified in accordancewith EASA STC.A.S.02689.The Flight Management System installed by this modification is notapproved for approach operations or vertical navigation. VNAVinformation<(>,<)> when provided on the FMS control unit<(>,<)> isadvisory onl...	11/11/2015	Active	10055463
10055465	AIM AVIATION (JECCO) LIMITED		CAA UK RESPONSIBILITY	747-8	WWHCo - 747-8 Dog Box	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AIM AVIATION (JECCO) LTD MODIFICATION NO. MM621-13 AND COMPLIANCE CHECKLIST NO. 11894 ISSUE C DATED 02 NOVEMBER 2015	None	11/11/2015	Active	10055465
10055472	AIRBORNE TECHNOLOGIES GmbH			MBB-BK 117 C-2	Provisions for surveillance operations / Installation of severalprovisions in order to enable the later installation (separate change)of mission equipment.Further details are shown in the project description Doc. No.:084-PD-STC-AT	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs of CS-29 AMDT 3 are applicable to this change:29.1; 29.21; 29.25; 29.27; 29.29; 29.45; 29.49; 29.51; 29.64; 29.65;29.67; 29.75; 29.79; 29.141; 29....	AFM-STC-AT-084; Flight Manual Supplement, Rev. No. 0, dated03-Jul-2015AMM-STC-AT-084; Maintenance Manual Supplement, Section B, Rev. No. 0,dated 23-Jul.2015or later revisions of the above listed documents approved by EASA.List of compliance documents and manuals in Chapter 7 of the Doc. No.:STC-AT-...	Limited to Rotorcraft Serial Number 9560Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/11/2015	Active	10055472
10055475	AEROTEC & CONCEPT			1900C	KHF 950 antenna provision installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation and Maintenance according to the “Master Data List”document AE15184MDL Rev. 0 dated 11/11/2015 or later revisions of theabove listed documents approved by EASA.	Applicability limited to all MSN UB- and UC- only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produc...	12/11/2015	Active	10055475
10055479	LUFTHANSA TECHNIK AG			737-700	Communication - Activation of CPDLC.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 “Data Link Servicesfor the SingleEuropean Sky” Issue 1.The requirements for environmental protection and the associatedcertified noise and/...	- Supplemental Type Definition Document, Ref. STDD23-13/22M, Issue 1.0,dated August 25, 2015- Airplane Flight Manual Supplement, Ref. A-00-13/52-AFM, Iss./Rev. 02/00, dated July 09, 2015- Instructions for Continued Airworthiness, Ref. A-00-13/52-ICA, Iss. /Rev. 01 / 00, dated Sep 20, 2013.or later re...	As per Airplane Flight Manual Supplement, Ref. A-00-13/52-AFM, Iss./Rev.02/00, dated July 09, 2015.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noad...	12/11/2025	Active	10055479

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055487	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC ST03255CH	BEECH 400/400A	Air Ambulance Conversion	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 6047DL Revision 2 dated 10. March 2014Aircraft Flight Manual Supplement 6047FMS Revision – dated Aug 28, 2013Instructions for Continued Airworthiness 6047MM Revision 1 dated Aug 6,2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Dec...	-Per installation drawing Revision 1 dated March 20, 2013-Per Engineering Substantiation 6047B Revision 1 dated Jul 13,2013-Per Airworthiness limitations in Instructions for ContinuedAirworthiness 6047MM Revision 1 dated Aug 6, 2013-Per Aircraft Flight Manual Supplement 6047FMS Revision – dated Aug...	17/04/2019	Active	10055487
10055493	JET AVIATION AG			747-400	B747-400 Main Deck Reconfiguration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRIA-101 Issue 1 issued for project 0010035841.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pr...	- Master Data List, Ref. JBSL-M-00371MDL-01, Issue 3.- Instructions for Continued Airworthiness, JBSL-M-00371ICA-01, Issue 1and JBSL-M-00371ICA-02, Issue 1.- EWIS ICA, Ref. JBSL-M-00371ECA-01, Issue 1- Aircraft Flight Manual Supplement, Ref. JBSL-M-00371AFM-01, Issue 2or later revisions of the above...	- Only applicable to S/N 25074- As per Aircraft Flight Manual Supplement, Ref. JBSL-M-00371AFM-01,Issue 2, Section 1 “Certificate Limitations“- As per ICA document, Ref. JBSL-M-00371ICA-02, Issue 1,- Minimum number of Cabin Crew is 9 (Maindeck 8 - one per floor levelexit , upper deck 1 at the exit)...	13/11/2015	Active	10055493
10055494	AEROTEC & CONCEPT			1900C, 1900D	MOD 15180 - TCAS Change 7.1 with Honeywell suite	CS23 amdt. 3. Refer to Programme de Certification Ref. AE15180PCDP Rev.0 for list of applicable requirements.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approv...	- Master Data List AE15180MDL Issue 0 dated 12/11/2015- Aircraft Flight Manual Supplement AE15180AFMS Issue 0 dated 24/09/2015- Instruction for Continued Airworthiness AE15180ICA Issue 0 dated24/09/2015or later revisions of the above listed documents approved by EASA.	Limitation to aircraft equipped with Honeywell TPU-67A UnitP/ N066-01146-1111 or -1211.	13/11/2015	Active	10055494
10055495	DASSAULT FALCON JET		FAA SA8233SW-D	FALCON 2000	Installation of the Basic Oxygen System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01011-1, Rev.NC dated 20 November 1995.	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	13/11/2015	Active	10055495
10055497	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 2		PA-46R-350T PA-46-500TP PA-46-350P PA-46-310P	Installation of multiple Antennas	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendt. 4 301, 303, 305, 307, 365, 561, 571, 575, 603, 607, 611,625, 843, 867, 1301, 1306, 1308, 1309, 1327, 1351, 1431, 1529.The requirements for environmental pro...	- Project Description ASR-2015-012-PRD-04-00 Rev. 00 or later approvedrevisions- Instructions for Installation ASR-2015-012-IFI-10-00 Rev. 00 or laterapproved revisions- Instructions for Continued Airworthiness ASR-2015-012-ICA-11-02 (Rev.02) dated 12th July 2017	Final compliance demonstration must be provided in the frame of theinstallation STC for the equipment which is to be served by the hereinstalled antennas.The antenna installationsare independent from each other, not allantennas must be installed concurrently.Prior to installation of this design cha...	30/08/2017	Active	10055497
10055502	DASSAULT FALCON JET		FAA SA8237SW-D	FALCON 2000	Avionics Rack Installations.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01015, Rev.A dated 12 April 1995.	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/11/2015	Active	10055502

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055503	DASSAULT FALCON JET		FAA SA8238SW-D	FALCON 2000	Installation of the Electrical Feedthru – Pressure Vessel.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01020, Rev.NC dated 05 April 1995.	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/11/2015	Active	10055503
10055506	DASSAULT FALCON JET		FAA SA8239SW-D	FALCON 2000	Printed Circuit Board Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01021, Rev.A dated 21 June 1995.	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/11/2015	Active	10055506
10055508	ETIHAD AIRWAYS ENGINEERING L.L.C.			A320-212	LOPA Change from 20J/120Y to 24J/24P/ 78Y	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Etihad Airways Engineering Master Document List No. EA2-1525001—MD01Issue 4 dated 15 November 2015.	RESTRICTED TO MSN 350	16/11/2015	Active	10055508
10055511	DASSAULT FALCON JET	REV. 2	FAA SA8242SW-D	FALCON 2000	Installation of the Air Distribution System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01016, Rev.C dated 20 May 1996	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	09/12/2015	Active	10055511
10055513	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			737-800	Wireless IFE system installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph at CS 25 amdt 16: CS 25.1703, 25.1707, 25.1709,25.1711, 25.1713, 25.1715, 25.1717, 25.1719, 25.1729.The requirements for environmental protection a...	AFM Supplement CE-4421001-FF01 rev 00 dated 12.10.2015 or laterrevisions of the above listed documents approved by EASA.AMM Supplement CE-4421001-AM01 rev 00 dated 11.05.2015MDL CE-4421001-MD01-01 rev 01 dated 15.11.2015	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/11/2015	Active	10055513
10055515	NORTHERN AVIONICS S.R.L.			AB139, AW139	Secondary Cycle counter for Breeze Eastern hoist	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Chapt. 4 ALS included in Rep. ICA-NAV0515, Rev. 0, dated 9.10.2015 orlater revisions of the above listed documents approved by EASA.Compliance Checklist CCL0515, Rev. 0, dated 9.10.2015Master Document List MDL0515, Rev. 0Description NAV0515, Rev. 0, dated 9.10.2015Drawing 25-NAV0515-00, Rev. 0, date...	The installation of this Secondary Cycle counter is limitedto thefollowing aircraft installed Breeze Eastern hoists P/ Ns:BL-20200-421BL-20200-422 BL-20200-431Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously...	17/11/2015	Active	10055515

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055532	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.			757-200	Relocation of existing antennas.	The Certification Basis (CB) fir the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	- Standard Aero Master Data List 1026545, Revision (G), dated October17, 2014.- Instructions for Continued Airworthiness Document 1026568, revision(D) dated July 23, 2014 in addition to the basic airplane maintenancemanuals.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	18/11/2015	Active	10055532
10055533	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.			757-200	Installation of KU Band Satellite System Provisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Standard Aero Master Data List 1024000, Revision (F), datedOctober 25,2014.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	18/11/2015	Active	10055533
10055545	HELI-ONE (NORWAY) AS	REV. 1		AS 332 L, AS 332 L1	Implementation of ES ADS-B OUT capability with transponder TDR-94D (Mod.AHSE-66400).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation from CS-ACNS.D.ADSB.105 as per CRI F-01, Issue 3- The following paragraph(s) at a later amendment:CS 29 Amdt 3 for thefollowing requirements: 29.1, 29.29, 29....	AS 332L/L1 Flight Manual Supplement H1N.239 “1090 ES ADSB-OUT" InitialIssue, 16.11.2015or later revisions of the above listed documents approved by EASA.Product Change DeclarationAHSE-66400, Initial Issue, 30.10.2015Master Drawing AHSE-66407, Rev. A, 10.11.2015Certification Program AHSE-66403 Rev.C...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/11/2015	Active	10055545
10055548	AEROSERVIS, S.R.O.			L 410 UVP-E9 L 410 UVP-E20 L-410 UVP-E	Introduction of SW version 7.1 to aircraft currently equipped withHoneywell CAS-67A TCAS II as per document AE162 001P	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:FAR 23 §,,Amdt.,, 1309,,,,49,,1431,,,,49,,1581,,,,50,, The requirements for environmental protection and the associatedcertif...	- STC AE/162 Master Document List, Doc. No. AE162000X, rev D<(>,<)>dated 06.11.2015- L 410 UVP-E Flight Manual Supplement Doc. No. STC AE/162-DLP1<(>,<)>TCAS II Honeywell CAS 67B (SW ver. 7.1), initial issue, dated September15/15- L 410 UVP-E9 Flight Manual Supplement Doc. No. STC AE/162-DLP2, TCASI...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/11/2015	Active	10055548
10055550	B/E AEROSPACE LIMITED		TCCA SA15-42 ISSUE 1	DHC-8-402	Installation, Provisions for Passenger Life Vest	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with B/E Aerospace Modification Data SummaryJ954001 Rev N/C dated 11 May 2015 or later revisions of the above listeddocuments approved by EASA in accordance with the TechnicalImplementation Procedures of EU/ Canada Bilateral Agreement.J954041 Rev A EASA Cert Basis Complian...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/11/2015	Active	10055550
10055557	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	AVRO 146 SERIES RJ85 AVRO 146 SERIES RJ70 AVRO 146 SERIES RJ115 AVRO 146 SERIES RJ100	Introduction of TCAS Change 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: JAR 25 Change 10 -25.1301; 25.1309; 25.1431; 25.1581; 25.1585.The requirements for environmental protection and the associ...	STC Twenty One Ltd Flight Manual Supplement S21.FMS-0124 Issue 2 orlater revisions of the above listed documents approved by EASA.STC Twenty One Ltd Master Document List S21.MDL-1274 Issue 3.	None	20/11/2015	Active	10055557

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055570	L2 AVIATION SOLUTIONS, LLC		FAA ST11037SC	777-300, 777-300ER 777-200, 777-200LR	Installation of aSAT-2100B satellite communication system and interfaceto aircraft systems	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List, L2 Consulting Services document No. 2315-B61-MDL<(>,<)> Revision N, dated 11 August 2015.- Airplane Flight Manual Supplement, L2 Consulting Services document No. 2315-B61-AFM, Revision IR, dated 14 December 2010.- Instructions for Continued Airworthiness, L2 Consulting Services...	None	20/11/2015	Active	10055570
10055575	SABENA TECHNICS BGC	REV. 1		737-900, 737-900ER 737-600, 737-700, 737-800	TCAS 7.1 upgrade on B737The modification consists in the upgrade of the existing TCAS 7.0 systemto TCAS 7.1 system, only computer unit is modifiedRev 1 : In addition to the initial release of this STC, Revision 1Include the associated Software update for Rockwell-Collins (Post Mod PN822-1293-033). R...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to associated Certification Plan 0685-01-A-CP-R02, section 5 & 6, for d...	Master Data List (MDL), ref: 0685-01-A-MDL-R01Instructions for Continued Airworthiness, ref: 0685-01-A-ICA-R01or later revisions of the above listed documents approved by EASA.	As per design of this STC, the modifications related to TCAS 7.0 need tobe previously installed, and are pre-requisitesfor the installation ofthis STC. Refer to associated Certification Plan 0685-01-A-CP-R02(section 2), and Aircraft System Configuration Checklist ref0685-01-A-ASCC-R02 (or later rev...	26/05/2016	Active	10055575
10055588	S4A SOLUTIONS FOR AVIATION, S.L.			ATR 72-212 A ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102	ACAS II VERSION 7.1 UPGRADE	CS-25 Amdt. 17, IAW Report 72019-CPL01 Ed. 6.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	72019-HDK01 Flight manual supplement Ed4 or later revisionsof the abovelisted documents approved by EASA.72019-SB001 Service Bulletin Ed372019-HDK02 Maintenance Manual SupplementEd1	None	23/11/2015	Active	10055588
10055592	STIRLING DYNAMICS GMBH	REV. 4		CL-600-2C10 (RJ 700, 701, 702) CL-600-2C10	LOPA ChangeRev. 4: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	V-Plane GMBH & Co.KG Master Document List No. 215096-C-DL-2520-001 Issue3 dated 30 October 2015or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2022	Active	10055592
10055599	DASSAULT FALCON JET		FAA SA8246SW-D	FALCON 2000	Installation of the Miscellaneous Structures (General/Mechanical)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01009, Rev.D dated 19 June 1997	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/11/2015	Active	10055599
10055604	DASSAULT FALCON JET		FAA SA8266SW-D	FALCON 2000	Installation of the Battery Temperature System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement, Report No. 36489-1, dated 8 August1996or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or theTechnical Implementation Procedures of EU/USA Bilateral Agre...	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/11/2015	Active	10055604

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055608	AEROTEC & CONCEPT	REV. 1		EC635 P2+, EC635 T1, EC635 T2+ EC135 T1, EC135 T2, EC135 T2+ EC135 P1, EC135 P2, EC135 P2+	Installation of Night Vision Imaging System (NVIS) on EC135withSingle-Sided Cockpit with conventional instruments in accordance withMaster Data List AE14131MDLRevision 1: Introduction of additional Night Vision Goggles (NVG) modelin accordance with Master Data List AE14131MDL.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS.27 Amdt. 3 for27.771, 27.773, .777, 27.1301, 27.1303, 27.1305, 27.1309, 27.1321,27.1322, 27.1351, 27.1381, 27.1383, 27....	Rotorcraft Flight Manual Supplement AE14131RFMS Revision 1Master Data List AE14131MDL Revision 4Instructions for Continued Airworthiness AE14131ICA Revision 6or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	Limited to helicopters with CPDS cockpit variants.The firstinstallation of this kit must be supervised by the STC holder.Rotorcraft modified by this design change employ Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible w...	06/05/2020	Active	10055608
10055615	S4A SOLUTIONS FOR AVIATION, S.L			SAAB SF340A	ACAS II VERSION 7.1 UPGRADE	CS-25 Amdt.17, IAW Certification Plan S3401-CPL01 Ed3The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	S3401-HDK01 Flight Manual Supplement Ed3 or later revisionsof the abovelisted documents approved by EASA.S3401-SB001 Service bulletin Ed2S3401-HDK02 Maintenance manual supplementEd2	None	23/11/2015	Active	10055615
10055631	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	JETSTREAM SERIES 3100	TCAS II Upgrade to Version 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 16 - CS25.1301; CS 25.1309; CS 25.1431; CS 25.1529; CS 25.1581.The requirements for environmental protecti...	Cranfield Aerospace AFM Supplement CA/DD/M043 Issue Aor later revisions of the above listed documents approved by EASA.Cranfield Aerospace Certification Plan CA/DD/ DR0293 Issue B CranfieldAerospace Compliance Matrix CA/DD/ DR0294 Issue BCranfield Aerospace Type Design Definition Addendum CA/ DD/DR0295...	Applicable to aircraft serial number 614 only.Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	24/11/2015	Active	10055631
10055632	WHELEN ENGINEERING COMPANY Inc.		FAA SA00344BO	SEE FAA AML 140212 REV. 4	Installation of Parmetheus Plus LED PAR36 and PAR46 taxi and landinglights.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Whelen STC Manual, Form 14793, dated July 7<(>,<)> 2014.	Maintenance must be in accordance with Whelen STC Manual, Form 14793,dated July 7, 2014.Prior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effec...	21/12/2015	Active	10055632
10055633	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA ST02545LA	747-8, 747-8F	Installation of Cabin Interior Noise Reduction Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aerocon Engineering Company Master Drawing List AC25-NRB747-1000Revision "G" dated 30/08/2015.Aerocon Engineering Company Instructions for Continued AirworthinessDocument Maintenance Manual Supplement MMS-B747-1818 Revision "NC" dated14/01/2014.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/11/2015	Active	10055633
10055637	SABENA TECHNICS BOD			737-700	BBJ Turnkey Taiwan Eagle conversion VIP	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CRIA-101 Issue 2 issued for project 0010029108Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	- Master Data List, Ref. MDL-S-00-2345, Issue A.- Aircraft Flight Manual Supplement, Ref. AFMS-B3031-00-031 Issue B.- Instruction for Continued Airworthiness, Ref. ICA-B3031-00-032 IssueB.or later revisions of the above listed documents approved by EASA.	- Only applicable for MSN 61040- As per Aircraft Flight Manual Supplement, Ref. AFMS-B3031-00-031 IssueB, Section 3 - Limitations.- As per Instruction for Continued Airworthiness,Ref. ICA-B3031-00-032Issue B, Section 4 - Airworthiness Limitations,,,,Prior to installation of this design change it mu...	25/11/2015	Active	10055637

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055655	I.S.E.I INTERNATIONAL SERVICESELECTRONIQUE INFORMATIQUE			SR22, SR22T	Installation of SAFETYPLANE V5 System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition: CRI F-01 issue 03 Lithium Battery Installations.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels...	Aeroplane Flight Manual Supplement N11-CIRRUS SR22-SAFETYPLANE V5 EditA-01 Revision 00 dated 06 August 2015List of Documents Project 0010039458-001 N10-CIRRUS SR22-SAFETYPLANE V5Edit A revision 03 dated 20 November 2015or later revisions of the above listed documents approved by EASA.	None	26/11/2015	Active	10055655
10055664	AEROTEC & CONCEPT			1900C, 1900D	MOD 15181 - TCAS Change 7.1 with Rockwell suite	CS23 amdt. 3 refer to Programme de Certification Ref. AE15181PCDP Rev.0.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels ofthe original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement AE15181AFMS issue 0 dated24/09/2015Instruction for Continued Airworthiness AE15181ICA issue 0 dated24/09/2015Master Data List AE15181MDL issue 0dated 12/11/2015or later revisions of the above listed documents approved by EASA.	Limitation to aircraft equipped with Rockwell TTR921 unit P/ N822-1293-002/003/322 or TTR 4000 unit P/N 822-1294-002.	26/11/2015	Active	10055664
10055683	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	767-200	Introduction of TCAS Change 7.1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Ltd Flight Manual Supplement S21.FMS-0125 Issue 2or later revisions of the above listed documents approved by EASA.STC Twenty One Ltd Master Document List S21.MDL-1276 Issue 2.	None	27/11/2015	Active	10055683
10055694	LUFTHANSA TECHNIK AG			A380-841, A380-842, A380-861	PAC GCS A380 – Installation of Data Broadband System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document Ref. STDD - 44-15/02M Issue 01- Compliance Record List Ref. CRL44-15/02M Issue 01- Airplane Flight Manual Supplement Ref. A-00-15-63-AFM Rev. 1.0- Instruction for Continued Airworthiness Ref. A-00-15-63-ICA Rev.1.0or later revisions of the above listed documen...	None	27/11/2015	Active	10055694
10055698	MECAER AVIATION GROUP S.p.A.	REV. 5		AW189	VIP 023 MCB interiors configurationRevision 1 of the STC 10055698 introduced a new Electro-Chromic Windowsas per MECAERNDC 6A8W-0002Revision 2 of the STC 10055698 introduced two-seat configurations and anew fibre-optic light panel for passenger doors locking visualinspection as per MECAER NDC 6A8W-...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Revision 5:- 6A8W0000N214, AW189 VIP - Windows and Gaskets Instl - CertificationProgramme, Revision C- 6A8WWNM-2-1, Owner's Manual – Chapter 04-00-00 (ALS Section), Revision5- 6SPEC-322-PRC, AW189 Emergency Exit Small Window InstallationProcedure, Revision C- 6SPEC-323-PRC, AW189 Emergency Exit Door...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/03/2025	Active	10055698

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055699	LEAT S.p.A.			CITATION II	TCAS II VERSION 7.1 MODIFICATIONThe Pre mod configuration consists in TCAS II version 7.0 installationprocessor TPU 67APN 066-01146-1211.Post mod configurations consist in TCAS II version 7.1 installationprocessor TPU 67B PN 066-01146-2221.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: theCertification Basis is defined in the documentDRW n. 600-0904-1100-000Rev. IR dated 06/12/2004.The requirements for environmental protection and the associatedcertifie...	Aircraft Flight Manual Supplement n. 34-40-0415-0800 Rev. 0 dated05.11.2015or later revisions of the above listed documents approved by EASAMaster Data List DRW No. 600-0904-000-000 Rev. 07 dated 06.11.2015ICA TCAS II Version 7.1 Modification 34-40-0415-0600 rev. 00 dated05.11.2015	Limited to Aeroplanes serial No. 550-0393 and 550-0081.ThisSTC can be installed provided STC EASA.A.S.00413 has beeninstalled.	27/11/2015	Active	10055699
10055724	WHELEN ENGINEERING COMPANY Inc.		FAA STC SR00359BO	SEE FAA AML-150212 REV --	Installation of Parmetheus Plus PAR36 and PAR46 taxi and landing lights.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See FAA AML - 150212, Revision -- dated 10.09.2015	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.The STC is valid for those aircraft types and mod...	09/12/2015	Active	10055724
10055726	ROSEMOUNT AEROSPACE, Inc.		FAA STC ST01717CH	777-300ER 777-300 777-200	Installation of a Cockpit Door Surveillance System (CDSS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, Rosemount Aerospace document No. D0230682, RevisionAD<(>,<)> dated 14 November 2011.- Airplane Flight Manual Supplement, Rosemount Aerospace document No.D0230717, Revision E, dated 25 February 2004or later revisions of the above listed documents approved by EASA inaccordance with...	None	30/11/2015	Active	10055726
10055735	DASSAULT FALCON SERVICE			MYSTÈRE-FALCON 900	Upgrade TCAS 2000 to Change 7.1 on MF900	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement, DFS Supplement N°36, Original Issuedated 18 November 2015or later revisions of the above listed documents approved by EASA.Statement of Compliance DFS-DE-24-F9-9774 Issue A dated November 30,2015	Applicability is limited to MF900 model,,,,Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducenoadverse effect upon the airworthiness of the product.,,	30/11/2015	Active	10055735
10055739	AERO MEDICAL PRODUCTS MFG. Inc.		FAA STC SA1129GL	B200GT, B200T, B300, B300C B200, B200C, B200CGT, B200CT A100-1, A200, A200C, A200CT 200CT, 200T, 300, 300LW 1900, 1900C, 1900D, 200, 200C	- Install Aero Medical Products Mfg., Inc Air Ambulance Stretcher P/N125 using Installation Kit P/N 805.- The Medical Oxygen System Kit P/N is an FAA approved option.- The Inverter Pump Kit No. 812 may be installed.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	- Installation and Operating Instructions, Form EA 109K datedNovember 28,1988.- Inverter/Pump Installation Instructions, EA Form 170, dated December2, 1991.	1. FAA Approved Aircraft Flight Manual Supplement dated July 2, 2001required.2. Prior to the first flight of each modified aircraft, and after eachchange to any of the Communication, Navigational, or Med Pack equipment,a ground EMI test must be conducted in accordance to EA Form 173, datedNovember 1...	09/12/2015	Active	10055739
10055745	ALAMO ENGINEERING GmbH	REV. 2		DORNIER 228-212 DORNIER 228-202 DORNIER 228-201 DORNIER 228-200 DORNIER 228-101 DORNIER 228-100	Approval of TCAS Change 7.1 software upgrade.Revision 1: Transfer to 328 Support Services GmbHRevision 2: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation in accordance with 328 Design modification DC-12A032Z0001Issue A, dated 25.11.2015 and MDL ref MDL083Z001 Issue A, dated25.11.2015;Operate in accordance with 328 Design Flight Manual Supplement refAFMS012A344Z0001 Rev A, dated21.11.2015;or later revisions of the above listed document(s...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10055745

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055746	LEARJET Inc.	REV. 2	FAA STC ST11032SC	CL-600-2C10 (RJ 700/701/702) CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600) BD-700-1A10, BD-700-1A11 BD-100-1A10	Installation of a wireless cabin telecommunications router	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST11032SC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Future Jet Aerodesign master document list NO. 193-347000-MDL,Revision B, dated 20 September 2010, or later approvedFAA revision.	The installer must verify that the airplane meets the configurationrequirements contained in Future Jet Aerodesign document 193-347000-AMR, "All Models Report, Aircell CTR with Active Wi-Fi", revision IR,20th September 2010, or later FAA approved revision.	15/11/2019	Active	10055746
10055754	POLYTECH AERO SUPPORT INC.	REV. 1	TCCA SA15-88 ISSUE 1	737-600, 737-700, 737-800	Provisions for B737 EFB Mount and Power Connection Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Summary, Ref. MS-15-005, Revision 0, dated October 8, 2015Instructions for Continuous Airworthiness, Ref. ICA-15-005, Revision 0,dated October 8, 2015or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ Canada...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2015	Active	10055754
10055755	SABENA TECHNICS BGC			A330-200	CABIN RECONFIGURATION WITH IFE eXlite System on A330	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to associated Certification Plan4802-02-A-CP-R01<(>,<)> section 5 & 6, f...	Master Data List, ref: 4802-02-A-MDL-R00Instruction for Continued Airworthiness, ref: 4802-02-A-ICA-R01Aircraft Flight Manual Supplement, ref: 4802-02-A-AFMS-R01or later revisionsof the above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with STC 10014507 rev2 (or later revision), NonElectric Floor Path Marking System.Prior to installation of this design change it must be determined thatthe interrelationship between this design change andp...	01/12/2015	Active	10055755
10055770	STANDARD AERO	REV. 1	FAA ST02922CH-D	GIV	Installation of an Aircell Axxess Iridium Phone System witha True NorthExpress WiFi System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List 1019857 Rev D dated Feb 03, 2011AFM Supplement 1019802 rev A dated Feb 04, 2011Instructions for continued airworthiness document 1019912 rev C datedJan 05, 2011Airworthiness limitations document 1019919 rev A dated Jan 05,2011or later revisions of the above listed documents approve...	As per AFMS:A. the wireless LAN are not to be utilized on the flight deckB. this system is intended to provide internetconnection and emailservices to the airplanes cabin using portable electronic devices (PED)C. restriction on usage to passengers accessing cached internet contentand email via PEDs...	04/03/2016	Active	10055770
10055777	P3 ENGINEERING GMBH	REV 1		CL-600-2B16	AIRCELL SBB SATCOM AND WIFI CABIN NETWORK SYSTEM INSTALLATION	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Program / Compliance Summary, ref. doc.P3V-100034-CPR-0001-D, dated 11th November 2015- Master DocumentList, ref. Doc. P3-AAI01-MDL-0001, Issue B, dated 26thSeptember 2018- Airplane Flight Manual Supplement, ref. doc. P3V-100034-FOM-0001-B,dated 27th November 2015- Instruction for C...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/10/2018	Active	10055777

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055789	DASSAULT AVIATION BUSINESSSERVICES SA			FALCON 2000, FALCON 2000EX	TCAS II change 7.1 - Collins flR4100 ImplementationOut: ,,Collins TCAS II change 7.0 Transmitter/Receiver TTR-920 orTTR4000In: ,,Collins TCAS II change 7.1 Transmitter/Receiver TTR4100	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement No. TAG-M058-AFMS Rev. IRdated09.11.2015or later revisions of the above listed documents approved by EASA.Master Compliance Data List No. TAG-M058-MCDL Rev. A dated 01.12.2015Instructions for Continued Airworthiness Outline No. TAG-M058-ICAO Rev.IR dated 04.11.2015...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/12/2015	Active	10055789
10055806	B/E AEROSPACE, Inc.	REV. 1	FAA ST02876CH	SEE FAA AML DATED 05.10.2015	Installation of B/E Aerospace, Inc.<(>,<)> Vacuum Toilet AssemblyRetrofit Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	B/E Aerospace, Inc. Installation Instructions as listed on AML,ST02876CH, dated 05/10/2015.	The STC is valid for those aircraft types and models approved by EASAwithin the FAA AML dated 05/10/2015.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduc...	11/12/2015	Active	10055806
10055839	AEROTEC & CONCEPT			1900C, 1900D	MOD 15182 - TCAS II Change 7.1 with ACSS suite	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 amdt. 3 refer toProgramme de Certification Ref. AE15181PCDP Rev. 0.The requirements for environmental protection and...	Aircraft Flight Manual Supplement AE15182AFMS Issue 0 dated24/09/2015Instructions for Continued Airworthiness AE15182ICA Issue 0 dated24/09/2015Master Data List AE15182MDL Issue 0 dated 12/11/2015or later revisions of the above listed documents approved by EASA.	Limitation to aircraft equipped with ACSS RT-950 or RT-910 unit P/N7517900-100XX or 4066010-0904 or -910.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduc...	04/12/2015	Active	10055839
10055843	AEROCORP AVIONIC SOLUTIONS Inc.	REV. 1	TCCA STC 1576 ISSUE 1	DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300 DHC-6 SERIES 210 DHC-6 SERIES 200 DHC-6 SERIES 110 DHC-6 SERIES 100	Installation of Garmin G950 Integrated Flight Deck System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:FAR 23:Amdt. 23-0: 23.303, 23.307, 23.601, 23.609, 23.1367, 23.1381, 23.1551Amdt. 23-07: 23.625Amdt. 23-14: 23.771Amdt. 23-...	Genesys Top Document List A029400, Iss. K, dated 22 January2019Genesys Flight Manual Supplementsa) For Series 300: Doc. No. A029601, Iss. H, dated 22 January 2019b) For Series 100/200: Doc. No. A029602, Iss. H, dated 22 January 2019Installation Instructions: Genesys Engineering Order A029430, Iss.d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/01/2019	Active	10055843
10055848	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 3		737-800	Interior Reconfiguration of KLM Royal Dutch Airlines B737-800 AircraftRevision 1 covers the interior reconfiguration oftwo Boeing 737-800aircraft from its current, EASA-approved Transavia configuration to thestandard KLM Royal Dutch Airlines 737-800 configuration. The GO-TO,standard KLM 737-800 con...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List: N0517-D10 REV KCertification Summary: N0581-D90 REV - Instruction for continued airworthiness: N0517-D70 REV AWeight and Balance Report: N0581-D60 REV Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/12/2020	Active	10055848

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055850	ALAMO ENGINEERING GmbH	REV. 2		JETSTREAM SERIES 3200 JETSTREAM SERIES 3100	TCAS II Change 7.1 SW Upgrade for British Aerospace (BAe) Jetstream 3100/ 3200 Series.Revision 1: Transfer to 328 Support Services GmbHRevision 2: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AFMS026B34Z0001.CP-26 B084Z0001_A.DC-26B084 Z0001.GTR026B344Z0001 _SN857.MDL084Z001.or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10055850
10055866	AERO-DIENST GMBH & CO. KG			HS.125 SERIES 700B	TCAS TTR-4000 Upgrade to Version 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 25 Amendment 25-0FAR 25.29; FAR 25.1301; FAR 25.1309; FAR25.1331; FAR 25.1351; FAR25.1353; FAR 25.1357; FAR 25.1431; FAR 25.1519; FAR 25.1519; FAR25.1581; FAR 25.1583;...	Aero-Dienst AFM Supplement AG1005-071 Rev. Aor later revisions of the above listed documents approved by EASA.Aero-Dienst Engineering Order 286-HW.056.1 Rev. 2	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/12/2015	Active	10055866
10055876	JET AVIATION ST. LOUIS, Inc.		FAA STC ST04036CH	CL-600-2B16 (604 VARIANT)	Installation of a Window Shade System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Jet Aviation St. Louis, Inc. Master Data List 34-157G001 Rev. A, datedOctober 23, 2015	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product	09/12/2015	Active	10055876
10055877	SIRIUM AEROTECH S.L.			MYSTÈRE-FALCON 900	Change from TCAS 7.0 to TCAS 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MASTER DATA LIST, TCAS 7.1 Upgrade F900, SA15- 37S-MDL, rev. 0FLIGHT MANUAL SUPPLEMENT, TCAS 7.1 Upgrade F900, SA15- 37S-AFMS, rev. 0or later revisions of the above listed documents approved by EASA.	- As per the LIMITATIONS section in the FLIGHT MANUAL SUPPLEMENT, SA15-37S-AFMS, rev. 0Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installeddesign change and/ or repair will introduce noadverse effect...	08/12/2015	Active	10055877
10055883	SABENA TECHNICS BOD			A340-300 (A340-313)	AIR TAHITI NUI - CABIN AND IFE MODIFICATIONCabin configuration change from 6 F/C-24 B/C / 264Y/C to 32 B/C / 264Y/C with new B/C STELIA Evolys II seats and Y/C GEVEN Steezy seats.Installation of new ZODIAC Inflight Innovations RAVE IFE system withAVOD and WIFI. Installation of two galleys.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ICA, ref : ICA-F4040-25-015, Issue AModification approval sheet, ref : MAS-S-25-4000, issue 3AFM ref AFMS-F4040-25-017,Issue ACertification Plan ref CP-F4040-001 issue 1 (Including Master Data Listin Section 4.5.3)or later revisions of the above listed documents approved by EASA.	This STC is applicable for MSN 0668 only.Concurrent installation of EASA STC EASA.IM.A.S.01163 “Installation ofSafTGlo photoluminescent floor proximity escape path marking system(FPEEPMS)” (SafTGlow, Inc).Prior to installation of this design change it must be determined thatthe interrelationship bet...	08/12/2015	Active	10055883
10055885	ASSOCIATED AIR CENTER, L.P.		FAA ST11111SC	747-8	Provisions for the Installation of the Civil Aircraft Missile ProtectionSystem (CAMPS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, Ref. 3129000000, Rev IR.Instructions for Continuous Airworthiness, Ref. 3129050090, Rev IRor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)” and/ or the Technical Implementat...	- Applicable to B747-8 Serial Number 38636 only- This approval does not permit the CAMPS components to be powered- As per Chapter 3 “Airworthiness Limitations” of the InstructionsforContinuous Airworthiness, Ref. 3129050090, Rev IRPrior to installation of this design change it must be determined th...	08/12/2015	Active	10055885

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055904	JET AVIATION ST. LOUIS, Inc.		FAA STC ST03444CH	BD-700-1A10	Modification of an Executive Interior Arrangement IncludingCabin Seats,Divans, Mid Cabin Pocket Door, Removable Mid Cabin Bulkhead, PassengerOxygen System Mods, Emergency Lighting System Mods and EmergencyEquipment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Jet Aviation St. Louis, Inc. Master Data List 35-299G041 Rev. A, datedApril 22, 2015.The FAA approved AFMS document defined by this Master Data List isrequired.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2015	Active	10055904
10055911	JET AVIATION ST. LOUIS, Inc.		FAA STC ST03420CH	BD-700-1A10	One-time Modification of an Executive Interior Arrangement includingCabin Seats, Divans, Mid-Cabin Pocket Door, Removable Mid-CabinBulkhead, Passenger Oxygen System Mods, Emergency Lighting System Modsand Emergency Equipment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Jet Aviation St. Louis, Inc. Master Data List 35-299G040 Rev. A, datedFebruary 7, 2015.The FAA approved AFMS document defined by the Master Data List isrequired.	1) This approval is limited to only the installation made in BombardierInc. model BD-700-1A10 serial number 9133. This STC does not permitmanufacturing of parts for multiple installations.2) Prior to installation of this design change it must be determinedthat the interrelationship between this desi...	11/12/2015	Active	10055911
10055913	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04027AT-D	GVI (G650)	Installation of Satcom Direct Router (SDR) on Gulfstream GVI airplanes.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval wi...	- FAA STC ST04027AT-D Certificate- GDL100000019 Index List Rev H- GCD000020829, Rev –, EASA Validated Configurations List ST04027AT-D- CE61429M001 AFMS Rev B- CE61429A002 ICA Rev Dor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/10/2021	Active	10055913
10055915	CESKA LETECKA SERVISNI A.S.			L-410 UVP - TURBOLET L-410 UVP M - TURBOLET L 410 UVP-LW L 410 UVP-E-LW L 410 UVP-E9, L 410 UVP-E20 L-410 UVP-E	Replacement of the existing TTR-920 TCAS processor by new TTR-921 withTCAS version 7.1 capability in accordance with CLS-15-L410-AC257.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23, Amdt. 3:23.1 (a), 23.29(a)(b), 23.301(a)(b)(c), 23.303, 23.305(a)(b), 23.307(a), 23.337(a), 23.561(b)(3),23.603, 23.609, 23.773(a), 23.867(a)(b), 23.1301(a)-(d), 23.1...	Flight Manual Supplement FMS TCAS II, Doc.-Nr. AC257-2500Flight Manual Supplement FMS TDR-94D Doc.-Nr. AC257-2501Installation Instruction (Technical Order) AC257-2101Master Document List AC257-0001or later revisions of the above listed documents approved by EASA.Instruction For Continued Airworthin...	Limited to L-410 aircraft, initially equipped by the Type CertificateHolder with TTR 920 TCAS processor.	09/12/2015	Active	10055915
10055917	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		525A 525	Installation of Garmin GTS 855 TCAS I with dual antennas Garmin GA58	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 423.301, 303, 305, 307, 365, 561,571, 575, 603, 607, 611, 867, 1301,1306, 1308, 1309, 1327, 1351, 1357, 1365, 1431, 1529, 1581, 1583, 1585The requirement...	Flight Manual Supplement ASR-2015-111-FMS-05-00, Amdt. 00orlater revisions of the above listed documents approved by EASA.- Instructions for Installation ASR-2015-111-IFI-10-00, Amdt. 00-Instructions for Continued Airworthiness ASR-2015-111-ICA-11-01 (Rev.01) dated 1st June 2017	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10055917

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055918	DASSAULT FALCON JET CORPORATION		FAA STC SA8231W-D	FALCON 2000	Installation of the Cockpit Voice Recorder System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Type – A100S: Airplane Flight Manual Supplement Report No. 36361-1 Rev.A, dated 15 December 1995.Type – Allied Signal: Airplane Flight Manual Supplement Report No. 36361-2, dated 10 October 1995.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/...	Applicability is limited to F2000 S/N 025Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	09/12/2015	Active	10055918
10055922	INTELSAT INFLIGHT LLC	REV. 1		747-400	Installation of Gogo 2KU – Structural and Electrical ProvisionsRev 1: transfer of certificate to new holder GoGo LLC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 Amendment 1625.23:25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.365, 25.561,25.571, 25.581, 25.601, 25.603, 25.605, 25.607, 25.609, 25.611, 25.613,25.619, 25.621...	STC Twenty One Ltd Instructions for Continued AirworthinessS21.TEC-048 2Issue 1, Appendix A, Section 3 – Airworthiness LimitationsSTC Twenty One Ltd Master Document List S21.MDL-1245 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Only applicable to the following aircraft serial numbers: 26255< (>,<)>28757<(>,<)> 29406< (>,<)> 30885<(>,<)> 32337< (>,<)> 32338<(>,<)> 32339and 32340Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installe...	23/07/2020	Active	10055922
10055944	HONEYWELL INTERNATIONAL INC.		FAA STC ST01762WI	767-300 757-200 747-400	Installation of the Honeywell TPA-100B TCAS II Processor with Change 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	None	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/12/2015	Active	10055944
10055947	DASSAULT FALCON JET CORPORATION		FAA STC SA8243SW-D	FALCON 2000	Installation of the Centralized Water System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01017, Rev. D dated 18 November 1997	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	10/12/2015	Active	10055947
10055948	AIR AMBULANCE TECHNOLOGY GmbH	REV. 7		MBB-BK117 D-3M MBB-BK117 D-2, MBB-BK117 D-3 MBB-BK 117 D-2	Installation of a modular EMS-SAR/DMK equipment series P/ N117-25-20-100.000-7xx.Rev. 1 - Applicability extended to MBB-BK117 D-2m.Rev. 2 - Added cabin configurations 117-25-20-100.000-6xx and117-25-20-100.000-5xx including medical oxygen systems and electricalprovisions.Rev. 3 - Standalone change to...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Initial Issue:Master Data List, MDL-BK117 D-2-25-20-100.000-700, Rev. 0, dated 05 Oct2015;Certification Program, CP-BK117 D-2 (BK117 D-2-25-20-100.000-700), Rev.1;Compliance Record, CR-BK117 D-2-25-20-100.000-700, Rev. 1;Flight Manual Supplement, FMS AAT68, Part I Rev. 0, Part II Rev. 0,Annex 1 Rev....	This STC is also applicable to the MBB-BK117 D-2m variant.Minor Change 10070398 and 10070395 are prerequisites for theinstallation of Integration of AAT electrical system P/N 100.383-525 onD-2.Minor Change 10070398 and 10077085 are prerequisites for theinstallation of Integration of AAT electrical s...	30/11/2021	Active	10055948
10055954 (EASA.A.S.00631)	RUAG AEROSPACE SERVICES GmbH	REV. 2		525, S/N 0360 AND UP 525A	Upgrade of Honeywell CAS-67A System to S/W-Change 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement 128E-AFMS, Rev. N/Cor later revisions of the above listed documents approved by EASA.128E-CN, Rev. N/C Change Note (Approval for Aircraft Modification) orlater approved revisions128E-EO, Rev. A EngineeringOrder or later approved revisions	This STC does not cover aircraft equipped with Garmin G3000AvionicsSuite.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the air...	16/12/2015	Active	10055954

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10055967	ADAC LUFTFAHRT TECHNIK GmbH			MBB-BK 117 D-2	Night Vision Imaging System (NVIS) follow-on installation. Certificationof additional NVIS configuration as defined in Master Document ListEC145-04106-001-LMD-00.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-29 Amdt. 3. For paragraph29.1; 29.21; 29.141 (a) (b) (c); 29.601 (a)(b); 29.771(a) (b); 29.773 (a); 29.1301 (a) (d); 29.1309 (a) (b,1,2)(d) (c); 29.1321 (a)-(e) (g); 2...	RFMS EC145-04106-025-MFS-00or later revisions of the above listed documents approved by EASAEC145-04106-027-RCS-00EC145-04106-001-LMD-00	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2015	Active	10055967
10055988	TELAIR INTERNATIONAL Inc.		FAA STC ST02540LA	SEE FAA AML	Installation of Telair International LLC light weight P/Ns PMC 100 andPAG100 series cargo pallets.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	Telair International LLC Master Data Lists MDLPMC100 and MDL PAG100 bothat Revision D, dated July 01, 2015.Approved Model List (AML) No. ST02540LA, Revision NC, dated July 30,2015.	1. Only eligible for installation on transport category airplane asmentioned in the Approved Model List (AML) SA02540LAand that have beentype certificated with a cargo restraint system that is compatible withspecification NAS 3610 and themanuals referenced in the typecertificate data sheet include...	17/12/2015	Active	10055988
10055994	EIRTECH AVIATION SERVICES LIMITED			737-800	Design Change ERT/CNG/742 - B737-800 Cabin reconfiguration.Passenger seat configuration change from 8C 154Y to 189Y.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Eirtech Aviation Services Master Document List MDL/742-099 Issue 6,Certification Programme CP/742-003 Issue 7, Design Report DR/ 742-001Issue 6, Declaration of Compliance Issue 1, Change & RepairClassification CRC/ 742-002, Equipment Assessment EA/742-005 Issue 3,Service Bulletin ERT-SB-803 Issue 4, P...	None	14/12/2015	Active	10055994
10056048	DASSAULT FALCON JET CORPORATION		FAA SA8241SW-D	F2000	Installation of the Collins Traffic Alert and Collision Avoidance System(TCAS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01013, Rev.A dated 13 April 1995	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/12/2015	Active	10056048
10056050	DASSAULT FALCON JET CORPORATION		FAA SA8235SW-D	F2000	Installation of the Antenna Installations	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01002, Rev.C dated 01 May 1996	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/12/2015	Active	10056050
10056051	DASSAULT FALCON JET CORPORATION		FAA SA8244SW-D	F2000	Installation of the Basic Interior Furnishings	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01001-M, Rev.M dated 19 June 1996	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/12/2015	Active	10056051

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056055	S4A SOLUTIONS FOR AVIATION, S.L			A300 C4-605 R VARIANT F	TCAS V7.1 Upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25.1CS 25.1301CS 25.1302,,CS 25.1309,,CS 25.1316,,CS 25.1317,,CS 25.1322,,CS 25.1351,,CS 25.1353,,CS 25.1357,,CS 25.1431...	S4A Flight Manual Supplement A3005-HDK01 Issue 3or later revisions of the above listed documents approved by EASA.The compliance documents detailed in S4A STC/ Major Change DeclarationOf Compliance Form A3005-STA01 Issue 1	Applicable only to A300 C4-605R variant F aircraft with ACSS T2CASComputer Unit part number 9000000-11212 previously installedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or...	16/12/2015	Active	10056055
10056059	DASSAULT FALCON JET CORPORATION		FAA SA8240SW-D	F2000	Installation of the Miscellaneous Structural Modifications(Avionics/ Electrical)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report F2M-01006, Rev.H dated 26 April 1996	Applicability is limited to F2000 S/N 025.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/12/2015	Active	10056059
10056082	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09609RC	407	Installation of MD302 Standby Attitude Module Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Rotorcraft Flight Manual Supplement, Report No. AA-14091, No Revision,dated April 27, 2015.Master Drawing List, Report No. AA-14086, Rev. A, dated March 13, 2015.Instructions for Continued Airworthiness, Report No. AA-14088, Rev. A,dated April 27, 2015.	Eligible for installation on S/N 54300 and subsequent.Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the pr...	21/12/2015	Active	10056082
10056085	S4A SOLUTIONS FOR AVIATION, S.L			501	AVIONIC MODIFICATION (Weather RADAR, TCAS, TAWS, FMS, GPS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	50003-CHK0150003-HDK01 AFM-S50003-HDK02 MM-Sor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/12/2015	Active	10056085
10056089	ISOLAIR Inc., ISOLAIR HELICOPTER SY		FAA STC SR03173CH	F-28C, F-28F 280C, 280F, 280FX	Title:Isolair Model 3900-280 Agricultural Spray SystemDescription:Installation of an externally mounted agricultural spray systemconsisting of belly mounted pod, spray booms, spray pump, tank liquidcontents jettison system and pilot controls	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA Rotorcraft Flight Manual Supplement for Enstrom Model 280 Serieswith the Isolair Model 3900-280 Spraying System, RFMS No.3900-280FMS-EASA, Initial Issueor later revisions of the above listed documents approved by EASAMaster Drawing List for Isolair 3900-280 Spray System, MDL No. 3900-280,Revisi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/12/2015	Active	10056089
10056093	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CL-600-2B16 (604 VARIANT)	Installation of an Aviator 300 SwiftBroadband System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 25 Amdt 25-1 thru 25-7825.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.365, 25.561, 25.571,25.581, 25.601, 25.603, 25.605, 25.607, 25.609, 25.611, 25.613, 25.625,25....	STC Twenty One Ltd Flight Manual Supplement S21.FMS-0126 Issue 1STC Twenty One Ltd Instructions for Continued Airworthiness S21.TEC-0487Issue 1< (>,<)> Section 3 – Airworthiness Limitations or later revisionsof the above listed documents approved by EASA.STC Twenty One Ltd Master Document List S21.MD...	1. Applicable to aircraft MSN 5980 and 5983 only.2. This design change is only certified for the aircraft configurationat the time of this document issue. Any changes to the aircraft for thefollowing reasons will require re-evaluation:a) The required systems equipment fit is appreciably different an...	17/12/2015	Active	10056093

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056102	LEARJET Inc.	REV. 1	FAA STC ST01772WI	45	Installation of a seven passenger floor plan (SA-3) on Learjet Model 45aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Learjet Inc. Master Document List M1005681CT, Revision (G), dated 26December 2014, FAA approved 28 December 2014, orlater FAA approvedrevision.2. Instructions for Continued Airworthiness, M100568ICT-ICA-001, dated20 October 2014, FAA accepted December 28, 2014NEW-PAGEand Maintenance Requirements...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Installation of the Galley Solenoid per 45...	14/06/2019	Active	10056102
10056110	SCANDINAVIAN AVIONICS DESIGN ApS			737-600/-700/-800/-900/-900ER	EFB Tablet Display Mount Provision	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement, Refs 2082919-AM B Issue 2 / 2082919-AM C Issue 2Continued Airworthiness, Ref. 2082919-CA, Issue 1.or later revisions of the above listed documents approved by EASA.Engineering Order and Certification Program, Ref. 2082919-EO, Issue 6.	As per AFMS Aircraft Flight Manual Supplement, Refs 2082919-AM B Issue 2/ 2082919-AM C Issue 2Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse...	18/12/2015	Active	10056110
10056115	LUFTHANSA TECHNIK AG	REV. 1		A321-111, A321-212	Installation of Swiss Max cabin reconfigurationRev 1: Approval Extension to include A321-111.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Design Definition STDD25-15/21M Iss.1 – Rev.03, dated15/06/2016Instructions for Continued Airworthiness A-00-15/38-ICA Iss.1 – Rev.02,dated 26/08/2015Statement of Compliance: Applicant Declaration of Compliance (ADoC) –ref 3599, dated 07 Oct 2016.or later revisions of the above lis...	This design approval shall be installed in conjunction withSTC10051689, Rev.1.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	10/10/2016	Active	10056115
10056116	SABENA TECHNICS BOD	REV. 1		F28 MARK 0100	Ventral and Wings Pods - F28 Mark 0100Rev 1: Removal of Limitation to MSN 11290	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25.858 at Amendment 3, Cargo or Baggage compartment smoke or firedetection systemsThe requirements for environmental pro...	AFMS-FK104-00-016 issue CICA-FK104-00-017 issue ADeclaration of Compliance: MAS S-00-2113 issue 8 TRS-S-00-2113 Issue Dor later revisions of the above listed documents approved byEASA	For all configurations:- The aircraft may not be converted back to a pax configuration.- AFMS-FK104-00-016 section 3 Limitations.- The aircraft is not to be used in civil/commercial operations (nopublic transport); maximum number of passengers: 19.- Minimum crew: a qualified operator must be at allO...	29/04/2020	Active	10056116
10056117	VENTURA AEROSPACE, Inc.		FAA STC ST02448LA	MD-88 DC-9-81, DC-9-82, DC-9-83	9G Cargo Barrier - Installation of a cargo barrier on the main deck inthe forward cabin on Boeing DC-9 and MD-88 aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Chapter 12 of Report No. VA-RB-1100 Rev. B "Maintenance andInstructionsfor Continued Airworthiness Manual MD-80 SeriesRigid Cargo BarrierInstallation", Airworthiness LimitationsSectionor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (...	This cargo barrier may only be installed in conjunction withAeronautical Engineers. Inc passenger to freighter conversion EASA STC10055029.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design c...	18/12/2015	Active	10056117

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056118	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04030AT-D	GV	Installation of a Future Air Navigation System (FANS) -1/A+(AFN<(>,<) >CPDLC, ADS-C) functionality with data link capability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Gulfstream Aerospace Corporation Index List CE51 4068001, Revision (B),dated October 6, 2015.The Airplane Flight ManualSupplement, CE 51406M001, Rev.(-), datedOctober 6, 2015, isrequired and must be carried in the aircraft on allflights.The Instructions for Continued Airworthiness, CE51 406A001, R...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	21/12/2015	Active	10056118
10056127	MED-PAC INC.		FAA STC SA01452CH	SEE FAA AML	Installation of an air ambulance conversion kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	Med Pac, Inc. Drawings as listed on AML No. SA01452CH issued May 14,2001.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	21/12/2015	Active	10056127
10056129	AEROLITE AG	REV. 4		AW169	EMS Equipment P/N 169-0040200-501Revision 1 modifies the EMS Equipment P/N 169-0040200-501 to include anexpansion of the cabin configuration (New cabin configurations, Cabincompatibility with NVIS operation).Revision 2 modifies the EMS Equipment P/N 169-0040200-501 to include anexpansion of the cabi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement FMS-169- 0040200-501 D, dated 29-03-2019- Master Document List MDL-14-006 F, dated 07-05-2019- Operations Manual OPM-169-0040200-501F, dated 29-03-2019The above manuals revisions apply to all cabin configurations.or later revisions of the above listed document(s) approve...	Pre-requisites for installation of P/N 169-0040200-501 are given in theOperations Manual OPM-169-0040200-501 revision F, dated 2019-03-15.For any installation onto the Cargo Platform a separate design approvalis needed (not scope of this STC).Prior to installation of this change/repair it must be de...	22/05/2019	Active	10056129
10056134	LUFTHANSA TECHNIK AG			A380-861 A380-842 A380-841	PAC GCS A380 Large Antenna Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document Ref. STDD53-15_19M issue 01- Compliance Record List Ref. CRL53-15_19M issue 01-Instruction for Continued Airworthiness Ref. A-00-15_62-ICA Issue 02- Airplane Flight Manual Supplement A-00-15-62-AFMRev. 1.0or later revisions of the above listed documents app...	None	21/12/2015	Active	10056134
10056137	ROCKWELL COLLINS, Inc.	REV. 1	FAA SA01792WI	C90GTI	Installation of Rockwell Collins, Inc. Pro Line Fusion ® cockpit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): See appendix.- Equivalent Safety Finding(s): See appendix.The requirements for environmental protection and the associatedcertified noise and/ or e...	- Installation of Rockwell Collins, Inc. Pro Line Fusion® in accordancewith Master Drawing List RCA-0465, Revision (-),dated, August 31, 2015.- Operate in accordance with Airplane Flight Manual Supplement RCA-0494,Revision (-), dated, July 31, 2015.- Instructions for Continued Airworthiness RCA-052...	(1),,Approval of this change in type design applies to the above modelaircraft only; (2),,Compatibility of this design change with previously approvedmodifications must be determined by the installer; (3),,A copy of this Certificate must be maintained as part of thepermanent records for the modified a...	10/02/2017	Active	10056137

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056140	AIRBUS S.A.S.			A319-133	Airbus Corporate Jet Centre Modification MOD CJ1930: “Top ModificationAIGLE – Cabin and Systems Upgrade”	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements allincluded in the CRI A-4301-021 Issue 1 “ACJC STC Project CertificationBasis”Special Condition(s): CRI H-01 – ICA on EWISDeviation(s):CRI E-20 – Interior DoorsCRI E-24 –...	Modification Approval Sheet - MAS ref CJ1930, Issue 01, dated 18thDecember 2015Airplane Flight Manual – AFM Supplement ref FM-S MOD CJ1930, dated DEC01/15Maintenance Planning Document – MPD Supplement ref MPD-S MOD CJ1930,dated DEC 01/15orlater revisions of the above listed documents approved by EA...	This STC is limited to MSN 2192	21/12/2015	Active	10056140
10056144	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04033AT-D	GV	Installation of Gogo UCS 5000 Universal Cabin System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Gulfstream Aerospace Corporation Index List CE51428009 Rev "-", datedOctober 15, 2015.The Airplane Flight Manual Supplement, CE51428M013 Revision "-", datedOctober 15, 2015, is required and must be carried in the aircraft on allflights.TheInstructions for Continued Airworthiness CE51428A013, Revisi...	Use of the UCS 5000 Wi-Fi function by the Flight Crew whilein thecockpit during flight is not permitted.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduc...	21/12/2015	Active	10056144
10056146	DASSAULT FALCON JET CORPORATION		FAA SA8247SW-D	FALCON 2000	Flight Data Recorder System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report No. F2M-01024, Revision C.Airplane Flight Manual Supplement, Ref. 36392-1, Revision Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)” and/ or the Technical Implementation Pr...	As per Airplane Flight Manual Supplement, Ref. 36392-1, Revision A.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthin...	21/12/2015	Active	10056146
10056147	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04034AT-D	G-IV	Installation of a UCS 5000 Aircell Universal Cabin System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Gulfstream Aerospace Corporation Index List CE414288002<(>,<)> Revision(-), dated October 26, 2015.The Airplane Flight Manual Supplement CE41428M005, Revision (-), datedOctober 26, 2015, is required and must be carried in the aircraft on allflights.The Instructions for Continued Airworthiness, CE414...	Use of the UCS 5000 Wi-Fi function by the Flight Crew whilein thecockpit during flight is not permitted.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduc...	21/12/2015	Active	10056147
10056150	Q.C.M. DESIGN GmbH			HAWKER 800XP	Upgrade of Dual Honeywell Control Display UnitsExisting two(2) Honeywell Flight Management System Control DisplayUnits(CD-820) are replaced with updated touchscreen technology units (CD-830)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25.1302 amendment 3The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	Design Organization QCM Declaration of Compliance RH80-QCM31-001-M0-DOCrevision 1 from 21 December 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2015	Active	10056150

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056157	SABENA TECHNICS BGC			ERJ 170-200 STD ERJ 170-200 LR ERJ 170-100 STD ERJ 170-100 LR	Aeroconseil Supplemental Type Certificate STC 0662-01: Mechanical &electrical installation for personal tablet computer on E170 Familiy	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:All applicable paragraphs according to CS 25 at Amendment 4 (elect tocomply)The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	-Aeroconseil Master Data List ref. 0662-01-A-2103 Rev. 01 dated 20December 2015-Aeroconseil AFM Supplement ref. 0662-01-A-2301 Rev. 00 dated 21 October2015-Aeroconseil Instructionfor Continued Airworthiness (ICA) ref. 0662-01-A-2211 Rev. 01 dated 17 December 2015or later revisions of the above liste...	The limitations as identified in the AFM Supplement are applicable.The mechanical and electrical installation of this STC shall only beused for portable EFBs. It is the operator'sresponsibility to apply forthe operational assessment of EFB at its National Aviation Authorities.The portable EFB shall...	22/12/2015	Active	10056157
10056161	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04021AT-D	GULFSTREAM 200 / GALAXY	Installation of ADS-B Out SystemReason for Revision 1: Flight Stream 210 Bluetooth option added ,,	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS-ACNS Initial Issue:CS ACNS.D.ADSB.001, CS ACNS.D.ADSB.010, CS ACNS.D.ADSB.020, CSACNS.D.ADSB.025, CS ACNS.D.ADSB.030, CS...	Airplane Flight Manual Supplement Document No. G200-CGER-0014, Rev. C,dated 20 February 2015Index List Doc. No. CEB11268001, Rev. F, dated 20. Feb. 2015Instructions for Continued Airworthiness Doc. No. G200-CGER-0013, Rev.C, dated 19 December 2015or later revisions of the above listed documents appr...	This STC approval is limited to Galaxy / Gulfstream 200 serial number004 and subsequent.For serial numbers 004 through 172, EASA STC 10015449 (ST02883AT-D)Installation of Transponder Flight ID is a required prerequisite forthis STC (see Gulfstream Index List CEB11268001 for details)Prior to installa...	14/03/2016	Active	10056161
10056168	DASSAULT AVIATION BUSINESSSERVICES SA	REV. 1		MF900, F900EX	TCAS II change 7.1 - Collins TTR-4100 ImplementationOut: Collins TCAS II change 7.0 Transmitter/Receiver TTR-920 or TTR4000In: Collins TCAS II change 7.1 Transmitter/Receiver TTR-4100 & DACInternational GDC62 Analog/Digital Converter.	The Certification Basis (CB) tor the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval	Aircraft Flight Manual Supplement (F900C/ 900EX) No. TAG-M059-AFMS Rev.IR dated 26.11.2015Aircraft Flight Manual Supplement 2 (F900) No. TAG-M059-AFMS Rev. IRdated 26.11.2015or later revisions of the above listed documents approved by EASA.Master Compliance Data List No. TAG-059-MCDL Rev. IR dated 17...	The aircraft must be fitted with Rockwell Collins TTR-920 or TTR-4000TCAS II TransceiverPrior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effec...	06/01/2016	Active	10056168
10056169	SCANDINAVIAN AVIONICS DESIGN ApS			SEE EASA APPROVED MODEL LIST	ROCKWELL COLLINS TCAS VERSION 7.1 (ACAS II) UPGRADE OF PRIOR EXISTINGTCAS VERSION 7.0 IN PART 25 AIRCRAFTS as per AML STC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:EASA AMC 20-15 < (>&<)>CS 25 amdt 2CS 25.1, CS 25.29, CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS25.341, CS 25.561, CS 25.581, CS 25.601, CS 25.603, CS 25.605, CS25.609,...	2096998-EM REP A EMI TEST REPORT issue 1 15.10.20152096998-EM REP B EMI TEST REPORT issue 1 16.10.20152096998-GP A REP A GROUND TEST REPORT issue 1 16.10.20152096998-GP B REP A GROUND TEST REPORT issue 1 15.10.20152096998-TO REP A TECHNICAL ORDER REPORT issue 1 15.10.20152096998-TO REP B TECHNICAL O...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/12/2015	Active	10056169
10056170	TAMARACK AEROSPACE GROUP, INC.	REV. 7		525(M2),525A, 525B	Installation of Tamarack ATLAS to Cessna models 525, 525A and 525B withATLAS enhancements.This change incorporates corrective actions to the unsafe conditionreferenced in EASA AD 2019-0086-E and improvements to the ATLAS system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):C525 . CRI A-08 Team Involvement· . CRI B-01 Handling Requirements for CS-23 High PerformanceAeroplanes· . CRI B-02 High Speed Characteristic...	Installation in accordance with:Service Bulletin CA/ DD/SB1375, issue R, dated March 2019 andService Bulletin CAS/SB1480, issue A, dated July 2019Operation in accordance with:AFM Supplement CA/DD/M023, Issue C, dated 29 May 2019S/N: 525-0001 through 525-0359AFM Supplement CA/DD/M037, Issue C, dated 2...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/10/2019	Active	10056170

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056177	SCANDINAVIAN AVIONICS DESIGN ApS			757-300 757-200PF 757-200	Provision For Dual Portable Electronic Flight Bag (EFB) in a Boeing 757Series Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:AMC 20-25 Airworthiness and operational consideration for ElectronicFlight Bags (EFBs).EWIS: Applied i.a.w. (generic) SC/CR...	082919-ST C REP STATIC STRENGTH TEST REPORT issue 1 13.01.20152082919MP001 TABLET HOLDER ASSY issue D 13.01.20152084240-UD A DIC 600 UNIT DATA issue 1 02.06.20152084240MP012 DIC-600 OUTLINE & CG DRAWING P/N 70-12002-00211 issue IR02.12.20142084240MP012-RF.ZIP DIC600 OUTLINE & CG DRAWING REF DOC is...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/12/2015	Active	10056177
10056180	SIKORSKY AIRCRAFT CORPORATION		FAA STC SR02602NY-D	S-76C	Installation of a Honeywell 1239 ZingHUM	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CFR14 FAR Part 29, Amdt. 29-0 through 29-52:29.301, 29.303, 29.305(a), 29.307(a), 29.337, 29.601, 29.603, 29.607,29.613(a)(b)(d), 29.771(a), 29.773(a), 29.1301,29.1309(b)(...	Rotorcraft Flight Manual Supplement, Honeywell 1239 ZINGHUMSFor Sikorsky S-76 C Aircraft (s/n/ 760511 and subsequent) <(>,<)>Doc. FM02296, Rev. -, Original Issue, 30 July 2010or later revisions of the above listed documents approved by EASAinaccordance with EASA ED Decision 2004/04/CF (or subsequent...	Eligible s/n 760511 and upPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effectupon the airworthiness of the product.	23/12/2015	Active	10056180
10056185	S4A SOLUTIONS FOR AVIATION, S.L			CL-600-2B16 (604 VARIANT)	Installation of antenna for ELT (Emergency Locator Transmitter) system	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 AT Amendment 17:25.1<(>,<)> 25.21<(>,<)> 25.23<(>,<)> 25.25<(>,<)> 25.27<(>,<)> 25.251<(>,<)> 25.301<(>,<)> 25.303<(>,<)> 25.305<(>,<)> 25.307<(>,<)> 25.321<(>,<)> 25...	S4A Flight manual supplement no. 60422-HDK01 Edition 1S4A Maintenance manual supplement no. 60422-HDK02 Edition 1or later revisions of the above listed documents approved by EASA.S4A Master Drawing List no. 60422-RPT02 Edition 1	None	04/01/2016	Active	10056185
10056190	CONCORDE BATTERY CORPORATION		FAA STC ST04211AT	CN-235-300 CN-235-200 CN-235-100 CN-235 C-295	Replace original equipment Nickel-Cadmium (NiCd) main batteries withConcorde Lead-Acid, main batteries along with associated hardware onEADS CASA CN-235, CN-235-100, CN-235-200, CN-235-300 and C-295 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Drawing List 5-0502 Revision B, dated March 18, 2015.	FAA Approved Airplane Flight Manual Supplement for the replacement withConcorde Lead-Acid, main batteries, 05-0504, Revision A, dated June 12,2015, is a required part of this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change an...	04/01/2016	Active	10056190
10056191	CONCORDE BATTERY CORPORATION		FAA STC ST04185AT	FALCON 7X	Replacement of the original equipment valve regulated sealed Lead-acidbatteries with Concorde valve regulated sealed Lead-acid batteries withassociated hardware on the Dassault Falcon 7X series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Drawing List 05-0336, Revision A, dated August 12, 2014.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/01/2016	Active	10056191

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056192	TECH-TOOL PLASTICS, Inc.		FAA STC SR09647RC	AS 350 D, AS 350 D1 AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA	Installation of Bubble Windows in left hand or right hand side crewdoors.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approva...	Rotorcraft Flight Manual Supplement (RFMS), Tech Tools Plastics, Inc.Document No. TTP-350-FMS-001, Revision IR, dated September 8, 2014, isrequired.Tech Tools Plastics, Inc., Master Drawing List, Document No.TTP-350-MDL-001, Rev A, dated July 10, 2014.Instructions for Continued Airworthiness (ICA),I...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/01/2016	Active	10056192
10056193	TECH-TOOL PLASTICS, Inc.		FAA STC SR09568RC	R44, R44 II	Installation of Tech Tool Plastics replacement doors with full viewwindows.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Rotorcraft Flight Manual Supplement, Document No. TTP-RFMS-002, Rev.I/R, dated March 26<(>,<)> 2010 is required for this installation.Tech Tool Plastics Master Drawing List MDL-R44/R44II-001, Rev. D, datedMarch 2, 2010.Instructions for Continued Airworthiness, Document No. TTP-ICA-0005,Revision New,...	The following R44-101 Forward Door Configurations are approved:R44-101-1, -2, -3, -4, -5 and -6. Cabin Comfort Forward DoorConfigurations, R44-101-7, -8, -9 and -10 are NOT approved forinstallation. All R44-102 Aft Door configurations are approved.Prior to installation of this design change it mustt...	05/01/2016	Active	10056193
10056194	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		TBM700 N TBM700 C1, TBM700 C2 TBM700 A, TBM700 B	Installation of multiple Antennas	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 4 - 301, 303, 305, 307, 365, 561,571, 575, 603, 607,611, 625, 843, 867, 1301, 1306, 1308, 1309, 1327, 1351, 1431, 1529.The requirements for environmental...	- Project Description ASR-2015-077-PRD-04-00, Amdt. 00- Instructions for Installation ASR-2015-077-IFI-10-00, Amdt. 00- Instructions for Continued Airworthiness ASR-2015-077-ICA-11-02 (Rev.02) dated 31st July 2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10056194
10056195	RHEINLAND AIR SERVICE GmbH			TBM700 N TBM700 C1, TBM700 C2	Installation of Skywatch Sky497	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23, Amendment 4 -23, 29, 301, 601, 603, 611, 613, 771, 773, 867, 1301, 1309, 1351, 1357,1359, 1365, 1381, 1431, 1501, 1...	- Flight Manual Supplement G600 RAS-15-01-02-FMS-00, Rev. 0or later revisions of the above listed documents approved byEASA.- Instructions for Continued Airworthiness RAS-15-01-02-ICA-00, Rev. 0	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/01/2016	Active	10056195
10056201	FOKKER SERVICES B.V.			CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700/701/702) CL-600-2B19 (RJ SERIES 100) CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	CL-600 TCAS V7.0 upgrade to V7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan CP-0285 Issue 3Certification Plan CP-0286 Issue 1Compliance Record Report CRR-0285 Issue 1ComplianceRecord Report CRR-0286 Issue 1or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/01/2016	Active	10056201

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056206	WHELEN ENGINEERING COMPANY Inc.		FAA SA800EA	SEE EASA APPROVED MODEL LIST	Installation of Whelen Anti-Collision, Position, orAnti-Collision/Position Light System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Whelen Anti-Collision light Systems Installation and Service Manual,Document No. 05131, Rev. D dated May2015 or later approved revision.	The installation must be checked in accordance with WhelenAnti-Collision light Systems Installation and Service Manual,DocumentNo. 05131, Rev. D dated May2015 or later approved revision.Install the following placards, Whelen Part N° A421-1, or other approvedequivalent, in view of the pilot:TURN OFF...	06/01/2016	Active	10056206
10056217	MARSHALL AVIATION SERVICES LIMITED		CAA UK RESPONSIBILITY	BD-700-1A10	To introduce role change operation for a Mid Cabin Sliding Doorcurrently installed on Bombardier Global Express (BD-700-1A10) aircraftMSN9081<(>,<)> registration OE-IVG	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Marshall Aviation Services Ltd Aircraft Flight Manual Supplement No. CSP700-1 Supplement 1 Issue 1or later revisions ofthe above listed documents approved by EASA.Marshall Aviation Services Ltd Change Sheet No. SC0547A Issue 2	Restricted to ASN 9081A prerequisite is that EASA minor modification EASA.A.C.08622 isinstalled on the aircraft.	07/01/2016	Active	10056217
10056239	E A D AEROSPACE AIRWORTHINESS			777F 777-300ER 777-300 777-200LR 777-200	TCAS II Change 7.1 installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, EAD Aerospace document No. 01468-EAS-A-MDL, RevisionC, dated 4 November 2015- Airplane Flight Manual Supplement, EAD Aerospace document No.01468-EAS-A-AFM-A, Revision A, dated 14 October 2015or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/01/2016	Active	10056239
10056241	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04217AT	767-300	Interior Reconfiguration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt. 11: 25.1, 25.23(a)(b)2, 25.301, 25.303,25.601, 25.571(a)(b), 25.609, 25.613(a)(b), 25.619, 25.791, 25.793, 25.815,25.851(a)(5)(6)(7)(8), 25.853(a)(c)(d), 25.869...	HAECO Master Data List 14T205L001 rev AHAECO Instructions for continued airworthiness 14T205R009 rev BHAECO Weight And Balance report 14T205R017 rev Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decisi...	STC Aerospace Photoluminescent floor proximity emergency escape pathmarking system (EASA STC 10015434/FAA STC ST02521AT) must be installedprior to or concurrently with this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change andp...	08/01/2016	Active	10056241
10056242	BOND HELICOPTERS EUROPE Ltd.	REV. 1	CAA UK RESPONSIBILITY	EC135 T2+	NPAS Mid – Life Upgrade(Upgrade of the airborne surveillance suite of equipment and systems).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27 Amdt 3CS 27 Amdt 3 Appendix ACS 27 Amdt 3 Appendix BCS 27 Amdt 3 Appendix CCS ACNS Initial Issue:ACNS.B.VCS.001,A...	- Flight Manual Supplement for NPAS Mid-Life Upgrade, EC135 (includingGarmin GTN 650), FMS/104-002 Issue 4, dated 7 January 2016.or later revisions of the above listed documents approved by EASA.- Design Report DR/104-001, Issue 5, dated 7January 2016- Compliance Check List CCL/104-003, Issue 5, da...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/01/2016	Active	10056242
10056256	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09539RC	407	Installation of a Polycarbonate Windshield Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Drawing List, Report No. AA-10052, Revision H, datedDecember 11,2013.Instructions for Continued Airworthiness, Report No. AA-10057, RevisionA, dated January 20, 2014.	Polycarbonate Windshield kit is a replacement for the acrylicwindshields for Bell Helicopter Textron Canada Limited Model 407helicopters. The Polycarbonate Windshield kit has notbeen evaluated forcompatibility with Night Vision Imaging Systems (NVIS).Prior to installation of this design change itt...	13/01/2016	Active	10056256

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056257	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR01600AT	407	Manufacture of Hat Rack Safety Net.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Aeronautical Accessories, Inc. Drawing List Report No. AA-98021, norevision, dated February 5, 1998 and installation per Report No. AA-98020, no revision, dated February 5, 1998 or later approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/01/2016	Active	10056257
10056273	AVIATION SPECIALTIES UNLIMITED, INC	REV. 1	FAA SR01717SE	SA 365 N, SA 365 N1 EC 155 B1 AS 365 N2, AS 365 N3	Installation of a supplemental lighting system - NVIS Lighting System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ASU Flight Manual Supplement FMS-365004-6 Revision H, dated 01/05/2015,approved by FAA on 14/12/2015or later revisionsof the above listed documents approved by EASA inaccordancewith EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedu...	This STC is applicable to the models listed above and only to thespecific S/N listed in the Master Drawing List MDL-365004-3 Revision AA,dated 11/11/2015, or later FAA approved revisions.Rotorcraft modified by this STC employs Night VisionImaging Systemlighting, commonly named NVIS lighting, whiche...	01/03/2016	Active	10056273
10056275	HELIKOPTER AIR TRANSPORT GESELLSCHAm.b.H.	REV. 5		EC135 T2+, EC135 T3 EC135 T1, EC135 T2 EC135 P2+, EC135 P3 EC135 P1, EC135 P2	Installation of Northern Airborne Technology Digital Audio ControlSystem (nat-DACS) in accordance with Helikopter Air Transport GmbHEngineering Order EO 23-012Installation of Northern Airborne Technology Digital Audio ControlSystem (nat-DACS) in accordance with Helikopter Air Transport GmbHEngineeri...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS27 Amdt. 3:27.21, 27.25, 27.27, 27.29, 27.301, 27.303, 27.305, 27.561, 27.603,27.609, 27.610, 27.771, 27.1301, 27.1309,2...	- Aircraft Flight Manual Supplement AFM 23-012 Revision 2- Certification Plan 23-012 Revision 3 (Order EO 23-012 Revision 4)- Compliance Report CR 23-012 Revision 1- Installation Manual IM 23-012 Revision 4- Instructions for Continued Airworthiness ICA 23-012 Revision 4or later revisions of the abov...	Applicable to CDS, CPDS and Helionix cockpit variantsPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	31/07/2020	Active	10056275
10056335	ROCKWELL COLLINS, Inc.	REV. 3	FAA SA01784WI	B300C B300	Installation of Rockwell Collins, Inc. Pro Line Fusion® cockpit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): See EASA approved AnnexEquivalent Safety Finding (s): See EASA approved AnnexThe requirements for environmental protection and the associatedcertified...	Installation of Rockwell Collins, Inc. Pro Line Fusion® in accordancewith Master Drawing List RCA0430, Revision (-), dated May 4, 2015.Operate in accordance with:-Table 1 – Pro-Line Fusion® without the Intergrated Terrain Awareness andWarning System (ITAWS)Airplane Flight Manual Supplement (B300/B30...	(1) Approval of this change in type design applies to the above modelaircraft only.(2) Compatibility of this design change with previously approvedmodifications must be determinedby the installer.(3) A copy of this Certificate must be maintained as part of thepermanent records for the modified airc...	20/08/2018	Active	10056335
10056336	AIR AMBULANCE TECHNOLOGY GmbH	REV. 1		EC 130 T2	Installation of a modular "quick conversion" Air Ambulance Equipment,configurations EC130-25-20-41.000-601 and EC130-25-20-41.000-609, inaccordance with Master Data List MDL-EC130T2-EMS.Configuration EC130-25-20-41.000-601 incorporates a single stretcherinstalled on a structure called basic unit att...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR/CS-27.863 first issue as documented in CRI F-01 "Oxygen fire hazardin rotorcraft with Emergency Medical Service cabin configuration".The requirements for environmental...	- Flight Manual Supplement FMS-AAT65 Rev. 01- AirworthinessLimitations Section as per section 6 of CMM-EC130-AAT85Rev 02or later revisions of the above listed documents approved by EASA.- Instruction for Continued Airworthiness<(>,<)> CMM-EC130-AAT85 Rev 02- EMS Operation Manual, OM-EC130T2-AAT01,-...	"Quick conversion" Air Ambulance Equipment configurationEC130-25-20-41.000-601 incorporates provisions (storage space,attachments and electrical power supply) for medical devices.Installation and operation of those devices are not part of this STC.Prior to installation of this design change it mustt...	17/08/2016	Active	10056336

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056340	ROCKWELL COLLINS, Inc.	REV. 2	FAA SA01769WI	B200GT B200CGT B200C B200	Installation of Rockwell Collins, Inc. Pro Line Fusion® Cockpit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): See EASA approved Annex.- Equivalent Safety Finding(s): See EASA approved Annex.The requirements for environmental protection and the associatedcer...	Installation of Rockwell Collins, Inc. Pro Line Fusion® in accordancewith Master Drawing List RCA-0420, Revision (-), dated December 15,2014.Operation in accordance with:-(1) Airplane Flight Manual Supplement B200GT/ B200CGT, RCA-0422, Revision(-), dated December 15, 2014 or< (>,<)>(2) Airplane Flight...	(1) Approval of this change in type design applies to the above modelaircraft only;(2) Compatibility of this design change with previously approvedmodifications must be determinedby the installer;(3) A copy of this Certificate must be maintained as part of thepermanent records for the modified airc...	20/08/2018	Active	10056340
10056342	AIRGLAS, Inc.		FAA STC SR02429AK	R44 II R44	Installation of Airglas, Inc. LTB2600 Modular Terrain System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Airglas Inc. Descriptive Data List (DDL) LTB2600-R-44, Rev. B, datedOctober 29, 2015.2. FAA Approved Rotorcraft Flight Manual Supplement (RFMS), DocumentAI-LTB2600-R44-FM, Rev. Orig., dated December 14, 2015.3. Instructions for Continued Airworthiness (ICA), refer to Airglas,Inc., Manual Number...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2016	Active	10056342
10056358	GULFSTREAM AEROSPACE CORPORATION		FAA ST10027SC-D	G200/GALAXY	Installation of an Executive Cabin Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement GA 21468M073<(>,<)> dated 11Juli 2003or later revisions of the above listed documents approvedby EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.IndexC...	Limited to G200; S/N 073,,,,Prior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.,,,	20/01/2016	Active	10056358
10056375	STIRLING DYNAMICS GMBH	REV. 4		737-800	Complete LOPA ChangeRev. 4: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List, Ref. 215073-C-DL-2500-001-03, dated 18/01/2016.Drawing Register, Ref. 215073-C-DR-2500-001-03, dated 18/01/2016.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2022	Active	10056375
10056381	HARTZELL PROPELLER LLC		FAA STC SA03466CH	PC-12, PC-12/45 PC-12/47, PC-12/47E	Installation of Hartzell 5-blade composite propeller modelHC-E5A-3A/NC10245B	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 incl. Amdt. 4: 23.907This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionsleve...	-Airplane Flight Manual Supplement, AFMS030314 dated April 1, 2014-Instructions for Installation, INST030314 dated May 20, 2015or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technic...	Propeller Limitations:Diameter: 105 inches, no reductions permitted:Pitch setting at 42 inch radius:Low: 14,7 +/- 0.1 degreesFeather: 80.0 +/- 0.5 degreesReverse: 17.5 +/- 0.5 degreesPrior to installation of this design change it must be determined thatthe interrelationship between this design chang...	21/01/2016	Active	10056381

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056384	LEARJET Inc.	REV. 1	FAA STC ST01773WI	45 (LEARJET 45)	Installation of a 115VAC/60Hz/1200VA outlet in the right hand galley onthe Learjet Model 45 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Learjet Inc. Master Document List M100572ICT, revision (E), datedDecember 17, 2014< (>,<)> FAA Approved December 28, 2014 or later FAAapproved revision.2. The following documents are required for MDL M100572ICT-001configuration of this STC: Instructions for Continued AirworthinessM100572ICT-ICA-00...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Seven passenger floor plan (SA-3), install...	17/02/2016	Active	10056384
10056386	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH	REV. 1		525, 525A	Dual Garmin GTN 750 or GTN750 and GTN650Revision of the STCto enable Iridium phone calls over theoptionalGMA35c audio panel. An Iridium Satphone must be alreadyinstalled in the aircraft and is not included in this change	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Engineering Order Doc.-No. 2015-2, Rev. A;- Installation Procedure Doc.-No. 2015-2-1, Rev. C;- Airplane Flight ManualSupplement Doc.-No. 2015-2-8, Rev. C;- Maintenance Manual Supplement Doc.-No. 2015-2-10, Rev. C;or later revisions of the above listed document(s) approved/ acceptedunder the EASA s...	Vertical GPS/SBAS based approach modes are not covered by this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of...	11/11/2019	Active	10056386
10056394	DASSAULT FALCON SERVICE		DGAC FRANCE 2003-0239	MYSTERE-FALCON 900EX	Interior Modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Fiche d'Approbation de Modification DFS 9405 Original Issue dated 14January 2003or later revisions of the above listeddocuments approved by EASA	Applicability is limited to Falcon 900EX S/N 106Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	22/01/2016	Active	10056394
10056429	S4A SOLUTIONS FOR AVIATION, S.L			737-400	TCAS V7.1 Upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 17CS 25.1<(>,<)> CS 25.251<(>,<)> CS 25.581, CS 25.625<(>,<)> CS 25.899<(>,<)> CS 25.1301, CS 25.1302<(>,<)> CS 25.1309<(>,<)> CS 25.1316, CS 25.1317<(>,<)...	S4A Flight Manual Supplement 737130-HDK01 Issue 2or later revisions of the above listed documents approved by EASA.The compliance documents detailed in S4A STC/ Major Change DeclarationOf Compliance Form 737130-STA01 Issue 3	Applicable only to Boeing 737-400 aircraft with Honeywell TPA 81A TCAScomputer part number 066-50000-2220 previously installedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or...	22/01/2016	Active	10056429
10056456	GENEVA AVIATION Inc.		FAA STC SR02270SE	SEE EASA APPROVED MODEL LIST	Installation of Geneva Aviation Audio System on CS-29/Part 29 CategoryRotorcraft in accordance with the enclosed EASA Approved Model List (AML).This certificate replaces the approval and the provisions of EASA STC10036806 for the CS-29/Part29 rotorcraft identified in the enclosedAML.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ROTORCRAFT FLIGHT MANUALS SEE EASA APPROVED MODEL LISTor later revisions of the above listed documents approved by EASAinaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.MASTER DRAWING...	A copy of this certificate, the Rotorcraft Flight Manual Supplement andthe Instructions for Continued Airworthiness must be maintained as partof the permanent records of the modified rotorcraft as listed in the AMLof this approval.Prior toinstallation of this design change it must be determined tha...	26/01/2016	Active	10056456

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056472	BAE SYSTEMS (OPERATIONS) LIMITED	REV. 1	CAA UK RESPONSIBILITY	A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Introduction of a functioning Wireless In-Flight Entertainment System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt 1525.771, 25.777, 25.831, 25.863, 25.869, 25.981, 25.1301, 25.1302,25.1309, 25.1316, 25.1327, 25.1351, 25.1353, 25.1357, 25.1360, 25.1423,25.1431, 25.1501, 25.1...	BAE Systems Flight Manual Supplement BAES-STM-44-001-80013A-AFM Issue 1dated 22 January 2016or later revisions of the above listed documents approved by EASA.BAE Systems STC Dossier AWR/807/A320 Issue 1 dated 22 January 2016,“Not-Significant Major Change STM80013A, Introduction of a FunctioningWirel...	1. Applicable to aircraft fitted with BAE Systems Minor ChangesSTM80015A, STM80016A and STM80017A2. Application of STC to other individual aircraft not fitted with BAESystems Minor Changes STM80015A, STM80016A and STM80017A must becontrolled by further change action based on criteria established for...	28/01/2016	Active	10056472
10056476	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09604RC	407	Installation of an Expanded Instrument Panel kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/approval.	1. Master Drawing List, Report No.AA-13013, Revision C, dated March 14,2014.2. Instructions for Continued Airworthiness, Report No. AA-13008, NoRevision, dated October 10, 2013.	1. Eligible for installation on S/N 54300-Subsequent.2. TheFAA has not certified the equipment for which these provisionsare intended, additional FAA approval is required for equipmentinstallations.3. Prior to installation of this design change it must be determinedthat the interrelationship betwee...	29/01/2016	Active	10056476
10056478	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09605RC	407	Installation of an L-3 Wescam MX-10 System Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Rotorcraft Flight Manual Supplement, Report No. AA-12010<(>,<)> NoRevision, dated May 9, 2014 or later FAA approved revision2. Master Drawing List, Report No. AA-12004, Revision G, dated May 21,2014.3. Instructions for Continued Airworthiness, Report No. AA-12009, NoRevision, dated October 8, 201...	1. Eligible for installation on S/N 54300-Subsequent.2. High skid landing gear required for installation.3. Wescam MX-10 system GPS electrically disabled and not FAA approved.4. The FAA has not certified the installation of the Wescam MX-10 systemGPS antenna. The FAA must evaluate the Wescam MX-10 s...	29/01/2016	Active	10056478
10056483	HELI-ONE		TCCA STC SH07-24	S-76A, S-76C	Installation of Ryan 9900BX Traffic Advisory System (TAS) in accordancewith Heli-One Master Drawing List CHS76-34-040 MDL.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS CHS76-34-040 Ryan 9900BX Traffic AdvisorySystem, Revision NCor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Master Drawing List CHS76-34-040 MDL, Revision –Mainte...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/01/2016	Active	10056483
10056484	HELI-ONE		TCCA STC SH06-13	S-76A, S-76C	Installation of Garmin GNS-530/ GNS-530W in accordance with Heli-OneMaster Drawing Lists CHS76-34-039 MDL (rotorcraft equipped with EFIS)and CHS76-34-039A MDL (rotorcraft without EFIS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For rotorcraft equipped with EFIS:Flight Manual Supplement FMS CHS76-34-39C, Revision DFor rotorcraft without EFIS:Flight Manual Supplement FMS CHS76-34-39A, Revision Aor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ C...	The GNS-530W must have the WAAS function disabled.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produc...	27/01/2016	Active	10056484

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056491	S4A SOLUTIONS FOR AVIATION, S.L			C-212-DD, C-212-DF	TCAS V7.1 Upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 17 - CS25.1; CS 25.1301; CS 25.1302; CS 25.1309; CS 25.1316; CS 25.1317; CS25.1322; CS 25.1351; CS 25.1353...	S4A Flight Manual Supplement A1205-HDK01 Issue 1or later revisions of the above listed documents approved by EASA.The compliance documents detailed in S4A STC/ Major Change DeclarationOf Compliance Form A1205-STA01 Issue 3.	Applicable only to C-212-DD & C-212-DF aircraft with Honeywell TPU 67ATCAS computer part number 066-01146-1211 previously installedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change an...	28/01/2016	Active	10056491
10056498	ATELIER CHABORD	REV. 3	STC DGAC 45-SF-0001	DR400-180S DR 400/180 S DR 400/180 R DR400-180/ DR400-180 R DR 400/180	Installation of exhaust system according to Chabord modificationSTC-DR480-16-01REV. 3:- Enhanced silent blocks- Alternative anti corrosion surface treatment- Enhanced material on different parts- Additional bracket on double rod tube- Enhanced shape of central structural part in muffler	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 Amdt 3 § 607,611, 783, 807, 867, 1101, 1121, 1123, 1125, 1529The requirements for environmental protection and the a...	Technical Dossier ref. STC-DR480-16-01 Revision D dated 16January 2022Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	31/05/2022	Active	10056498
10056512	INTER-TEC AERO DESIGN AND CERTIFICALIMITED	REV. 3		AB139, AW139	Modification Number ITS-139-25-0313 - Forward Facing Observer Seat.Rev. 1 : Extension of the applicability of the original STC to allAB139/AW139 serial numbers and to introduce compatibility with LeonardoHelicopters floor panel P/N 3G5332A05832.Rev. 2: Transfer of STC holder from INTER-TEC SERVICESA...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Flight Manual Supplement ITS-0313-016 Issue 1- Instructions for Continued Airworthiness ITS-0313-015 Issue 1- Master Data List ITS-0313-011 Issue 3- Drawings ITS-0313-007 Issue 4 Sheets 1 through 4- Compliance Check List ITS-0313-002 Issue 3- Certification Plan ITS-0313-001 Issue 4or later revisio...	This STC is compatible only with Leonardo Helicopters floorpanels P/N3P5332A00331 or P/N 3G5332A05832.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducea...	20/03/2024	Active	10056512
10056519	S-TEC CORPORATION		FAA STC SA6076SW-D	76	Installation of S-TEC System 60 Two Axis Automatic Flight GuidanceSystem, Model ST-106, with Optional Automatic Electric Trim System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. FAA Approved Supplement to Pilot's Operating Handbook and/or FAAApproved Airplane Flight Manual, P/N 89127-1, dated 15.09.1986 and/orlater FAA Approved revision of the above supplement.2. Bulletin No. 209, Revision 2, dated 14.08.1986.3. Master Drawing List No. 92110, Revision A, dated 14.08.1986...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2016	Active	10056519
10056563	SIRIUM AEROTECH S.L.			ATR72-212A	Flap Cam Guides substitution by TCCA PDA	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1) TCCA “COMTEK Advances Structures Ltd.” Part Design Approval No.:PDA13-9 Issue 01, June 06, 2013.2) Conversion Bulletin SA13-03S-CB Rev: 0, Date: 04/12/2013.or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBila...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/02/2016	Active	10056563

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056573	GAMA AVIATION (ENGINEERING) LIMITED	REV. 3	CAA UK RESPONSIBILITY	B200T B200GT B200CT B200CGT B200C B200	Approval of King Air 200/B200 Steep Approach capability up to 5.5degrees.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Change MDL-1455 Issue 4 to Issue 6 dated 06 March 2018-Change AFMS-1455-01 Issue 4 to Issue 6-Instructions for Continued Airworthiness (ICA) in accordance with GamaAviation Document ref. ICA-1455-01 Issue 2 dated 23 May 2016or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/03/2018	Active	10056573
10056574	DART AEROSPACE Ltd.	REV. 1	TCCA SH14-14	EC130 B4, EC130 T2 AS350 B, AS350 B1, AS350 B2 AS350 B3, AS350 BA	Installation of Active Vortex Tube Inlet Filtration system (PA100PUREair System).Rev. 01 of the STC is issued to add EC130 T2 in the eligible modelslist.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA approved, Master Document List MDL-D350-822 Rev. H, dated July 21,2015TCCA approved, Installation Instructions IIN-D350-822 Rev. E dated July20, 2015TCCA approved, Flight Manual Supplement FMS-D350-822 Rev. B, dated July21, 2015TCCA accepted, Instruction for Continued Airworthiness ICA-D350-822...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/02/2017	Active	10056574
10056592	ROCKWELL COLLINS, Inc.		FAA STC SA01806WI	SEE FAA AML RCA-0526 REV. (-)	Modification of Rockwell Collins TCAS II System Installation with DCpowered TCAS Transmitter Receiver Processor.	See Annex.	1. Airplane Flight Manual Supplement RCA-0542, Revision (-), datedNovember 20, 2015; or later approved revisions. 2. FAAApproved Model List (AML) RCA-0526, Revision (-), dated November20, 2015, or later approved revisions.3. Instructions for Continued Airworthiness RCA-0541, Revision (-),dated July...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	09/02/2016	Active	10056592
10056598	SCANDINAVIAN AVIONICS DESIGN ApS			AS 332 L, AS 332 L1 AS 332 L2 AS 332 C, AS 332 C1	Single transponder system upgrade to MODE S ELS/EHS/ADS-B	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): CS 29.1309, CS ACNS.D.ELS.045, CS ACNS.D.ASSB.105 as perCRI F-01 Issue 3- The following paragraph(s) at a later amendment: CS-ACNS InitialIssue, Subpart D....	- Rotorcraft Flight Manual Supplement 2097842-AM Issue 1, dated26.10.2015or later revisions of the above listed documents approved by EASA.- Drawing List 2097842-DL Issue 1, dated12.01.2016- Engineering Order and Certification Program 2097842-EO Issue 2, dated03.02.2016- Compliance Record 2097842-C...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/02/2016	Active	10056598
10056625	HAECO CABIN SOLUTIONS, LLC		FAA STC ST00437AT	747-400	Installation of Collins SAT-906 SATCOM with Canadian-Marconi CMA-2102Antenna System and Ball Airlink Low Gain Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Page Avjet Master Drawing List 94-01, Rev. B, dated 16.06.1994 or TIMCOMaster Data List MDL-01242, Initial Revision, dated 12.02.1998.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/02/2016	Active	10056625

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056626	JET AVIATION ST. LOUIS, Inc.		FAA STC ST01376WI-D	BD-700-1A10, BD-700-1A11	Installation of an Executive Interior Arrangement, including CabinSeats, Jumpseat<(>,<)> Pocket Doors, Divan, PassengerOxygen System,Emergency Equipment, and Emergency Lighting System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Jet Aviation Index List 35-299G009, Rev. N, dated May 29, 2011 orlater FAA approved revision.2. FAA approved Airplane Flight Manual Supplement(s) 35-261M003, Rev.NC, dated March 27, 2006 (Config. 1); 35-261M005, Rev. NC, dated August9, 2006 and(Optional) 35-261M006, Rev. NC, dated August 9, 2006(...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/02/2016	Active	10056626
10056648	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST04024CH	A320-214	Installation of Passenger Cabin Seats and Inflight Entertainment (IFE)Upgrade.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. FAA Approved Flight Manual Supplement, Astronics Armstrong AerospaceDoc. No. DC303-9632-00, Revision -, approved September 04, 2015 or laterFAA approved revision.2. Astronics Armstrong Aerospace Master Data List, Doc. No.DC104-9632-00, Revision A, dated September 02, 2015.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/02/2016	Active	10056648
10056667	I.S.E.I INTERNATIONAL SERVICESELECTRONIQUE INFORMATIQUE			APM 20, APM 30	Installation of SAFETYPLANE V5 system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Aeroplane Flight Manual Supplement N11-APM 20_30-SPV5-AEROPLANE FLIGHTMANUAL SUPPLEMENT Edit A-01 Revision 01 dated 25 Nov 2015.List of Documents Project 0010040815-001 N10-APM 20_30-SPV5-LIST OFDOCUMENTS-Edit A Revision 05 dated 03 Feb 2016or later revisions of the above listed documents approved b...	None.	10/02/2016	Active	10056667
10056671	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04026AT-D	G280	Installation of an Automatic Dependent Surveillance Broadcast (ADS-B) SystemRev. 1 adds the Instructions for Continued Airworthiness.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Gulfstream Index List GA411268000 Rev "-", dated 10 April2015- Flight Manual Supplement G280-CGER-0030, Rev "-", dated 10 April 2015- Instruction of Continued Airworthiness GA41134A001 Revision "-" dated14 November 2019or later revisions of the above listed document(s) approved/acceptedunder the...	Aircraft Avionics Suite 3.6 or later EASA/FAA approved, as noted onIndex List A411268000, is required to be installed concurrently or as aprerequisite for this STC.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherprev...	10/02/2021	Active	10056671
10056719	TRIEB GmbH			F260B	Fuel valve replacement	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EOMD-020 Rev – Dated 14.01.2016 – Engineering order Fuel systemModificationPLMD-020 Rev – Dated 14.01.2016 this is a supplement to Periodicinspection list „Lista Controlli A/M Siai Marchetti F260-F260B – F260C – F260D Rev 1“ referenced in TCDSor later revisions of the above listed documents approved...	Limited to aircraft serial number 112 only	12/02/2016	Active	10056719

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056720	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	AVRO 146 SERIES RJ70	BAE 146-RJ70 ACTIVATION OF WI-FI SYSTEM	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 AMENDMENT 14:25.1301(a)(1), 25.1309(a)(b)(c), 25.1351(a), 25.1353(a),25.1431(a)(b)(c)(d), 25.1529, 25.1541(a)(b), 25.1581 (a)(b)(d),25.1585(a)(b)The requirements forc...	-CRANFIELD AEROSPACE INSTRUCTIONS FOR CONTINUED AIRWORTHINESS SERVICEBULLETIN NO. CA/DD/SB1426 ISSUE A-CRANFIELD AEROSPACE Aircraft Flight Manual Supplement No. CA/DD/ M026Issue A.or later revisions of the above listed documents approved byEASA.CRANFIELD AEROSPACE TYPE DESIGN DEFINITION ADDENDUM NO....	Restricted to ASN E1254Refer to CRANFIELD AEROSPACE TYPE DESIGN DEFINITION ADDENDUM NO.CA/DD/ DR0313 for the list the devices and quantities that may be usedwith this Wi-Fi network. Devices that are not in the list below must notbe connected to the Wi-Fi network provided by the Rockwell CollinsWAP300...	12/02/2016	Active	10056720
10056721	SCANDINAVIAN AVIONICS DESIGN ApS			HAWKER 1000 BAE.125 SERIES 1000B BAE.125 SERIES 1000A	Iridium Antenna Installation on BAe 125-1000A, BAe 125-1000B & Hawker1000	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.1, CS 25.29, CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS25.337, CS 25.365, CS 25.571, CS 25.581, CS 25.601, CS 25.603, CS25.605, CS 25.609, CS 25.611, CS 25.613,T...	2099382-EO ENGINEERING ORDER Issue 1 dated 18.01.20162099382 COR COMPLIANCE RECORD Issue 1 dated 18.01.20162099382-SL STRUCTURAL LOAD ANALYSIS Issue 1 dated 07.12.20152099382-TO TECHNICAL ORDER Issue 1 dated 07.12.20152099382-CA CONTINUED AIRWORTHINESS Issue 1 dated 07.12.2015or later revisions of t...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/02/2016	Active	10056721
10056724 (EASA.IM.A.S.00489)	RAM AIRCRAFT, LP	REV. 2	FAA STC SA2375SW	172I, 172K, 172L, 172M, 172N 172D, 172E, 172F, 172G, 172H	Installation of Lycoming O-320-D2G, O-320-D2J, or O-320-E2D(as modifiedby STC SE3692SW-D) engine rated for 160 h.p. take-off and 150 h.p. METOfor models 172I, 172K, 172L, and 172M; or installation of LycomingO-320-D2G, O-320-D2J, or O-320-E2D (as modified by STC SE3692SW-D)engine rated for 160 h.p....	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	RAM Dwg. RI 720 I Rev. F dated 09.12.1986;RAM Dwg. 17202, Rev. K dated 09.12.1986;RAM Dwg. 17203, Rev. L dated 09.12.1986;For models 172I, 172K, 172L, 172M:Airplane Flight Manual for Land with Lycoming O-320-D2G engine, dated 1November 1976, or, 10 June 1977, or 30 March 1978;Airplane Supplemental F...	For additional limitations see the applicable flight manuallistedabove.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness...	03/12/2024	Active	10056724
10056734	ANCRA INTERNATIONAL LLC		FAA STC ST02552LA	757-200 SERIES	Installation of main deck cargo loading system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	FAA approved Ancra International LLC Controlled Data List DL85300,Revision D, dated February 24, 2015, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.FAA STC ST04242AT must be installed in conjuncti...	15/02/2016	Active	10056734
10056736	ROEDER PRAEZISION GMBH	REV. 1		EMB-505	Installation of Low Gain Satcom Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/or emissions levels ofthe original product are unchanged and remain applicable to thiscertificate/approval.	Master Document List No. LGA·NY-11277 Rev. 00Documentation ICA Instruction for Continued Airworthiness No.LGA-NY-11277-07 Rev. 01or later revisions of the above listed documents approved by EASA.	Airworthiness limitations resulting from this modification accordingDocument:ICA Instruction for Continued Airworthiness No. LGA-NY-11277-07 Rev. 01(Chapter 4.1); (Threshold- and repeat Inspection Interval for aircraftskin and doubler).Prior to installation of this design change must be determined t...	15/11/2017	Active	10056736

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056738	AERODATA AG			1900C	Installation of AD-AFIS-0113 in 1900C	See Annex	Installation, Operation and Maintenance according to the Master DrawingList document number MDL-A/ C-878 Rev. 2 dated 11th February 2016 orlater revisions of the above listed documents approved by EASA.	Limited to model Beechcraft 1900C S/N UC-10 and UC-33 only.The document AMM-1157 Rev.1 (dated 10th February 2016) Chapter 04defines additional Airworthiness Limitations applicable.Prior to installation of this design change it must be determined thatthe interrelationship between this design change a...	15/02/2016	Active	10056738
10056760	DART AEROSPACE Ltd.		TCCA STC SH13-22	117 C-1 117 B-1, 117 B-2 117 A-1, 117 A-3, 117 A-4	D117-837 Basket InstallationHeli-Utility-Basket Installation on either the LH or RH Side of theHelicopter	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dart Aerospace Ltd Flight Manual Supplement FMS-D117-837 Revision A,dated June 11, 2013or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.-Master Document List MDL-D117-837 Revision J, dated Feb...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/02/2016	Active	10056760
10056761	BOGGI AERONAUTICS S.R.L.	REV. 2		AB139, AW139	Introduction of Trakka A800 Searchlight.Rev.1: removal of two limitations; change of STC holder address.Rev. 2: STC transferred to Boggi Aeronautics S.r.l.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-29 Initial Issue29.1; 29.29;29.45; 29.49; 29.51; 29.53; 29.55; 29.59; 29.60; 29.61;29.62; 29.65; 29.67; 29.75; 29.77; 2...	- Phoenix Aerospace Limited Flight Manual Supplement PAL/FMS/ AW139/106Revision Adated 12 February 2016< (>,<)>- Phoenix Aerospace Limited Master Document List, PAL/MDL/1297, RevisionD dated 05 July 2016.- Phoenix Aerospace Limited Change Embodiment & Approval, PAL/CP/1297Revision D dated 05 July 2016...	Applicable to rotorcraft without an ice protection system or limited iceprotection system fitted.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadve...	05/03/2024	Active	10056761
10056768	APTOZ EHF.	REV. 3		757-200	Installation of TCAS 7.1 Antenna Provisions.Description of Type Design Change: installation of an external doublerand antenna adapter plate on the upper fuselage at STA 426.35 andlowerfuselage at STA 446.5 in accordance with Icelandair CRA-757-5310-143Initial Release.Rev. 1: Removal of the 600FC li...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Icelandair CRA-757-5310-143 Revision D.Icelandair's Continued Airworthiness Instructions ref. CAICAI-757-5310-143 Revision Cor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.Icelandair's Engineering Order EO-757-5310-143 IR	- This STC is limited to Boeing 757-200 series aeroplane MSN 24527.- This STC is a pre-requisite to embodiment on MSN24527 of EASA STC10049475 “Navigation - Software Update or Replacement of the ACSS TCAS2000 Computer to Comply with the TCAS Change 7.1 Requirements.Prior to installation of this chan...	27/05/2025	Active	10056768
10056771	DOA AESGLOBAL LIMITED	REV. 1		757-200	Introduction of Alternative Business Class Seats.Rev 1: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 at Amendment 17 - Various.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchang...	AES Master Data List AES-757-3721MDL Issue 1.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/04/2021	Active	10056771
10056785	LUFTHANSA TECHNIK AG	REV. 1		A320-214, A320-271N	Center Ceiling Stowage InstallationThe change related to this STC deals with the installation of a CenterCeiling Stowage (CCS). The CCS is a small compartment unit locatedbetween C63 and C65, in the Ceiling and center area of the aircraft.Itis used by the Cabin Crew, which means that the CCS is not...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD25-15/35M issue1 rev 4- ICA, ref A-00-15-71-ICA, Issue 2 rev 1- ComplianceRecord List CRL25-15/35M iss 1 rev 3or later revisions of the above listed documents approved by EASA.	This STC and the associated documents considered, are approved only forA320-214 < (>&<)> A320-271N Models.The pre-requisites/pre-modification to this STC are :1) Lufthansa DeliveryLayout (DLH A320-214), Airbus Drawing320-25.40292, or2) Eurowings Delivery Layout (EWG A320-214), Airbus Drawing 320-25....	25/11/2016	Active	10056785

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056801	AVIONIK STRAUBING ENTWICKLUNGS GmbH			C90A	LPV upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS-23, Amendment 4 (notrequired by 21A.101), 301, 303, 305, 307, 561, 575, 603, 607, 611, 771,773, 867, 1301, 1306, 1308,1...	Flight Manual Supplement ASR-2015-109-FMS-05-00 Rev. 00or later revisions of the above listed documents approved by EASA.- Instructions for Installation ASR-2015-109-IFI-10-00 Rev. 00or later revisions- Instructions for Continued Airworthiness ASR-2015-109-ICA-11-00 Rev.00or later revisions	A suitable HSI (e.g. Collins EHSI-74) must have been already installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwor...	19/02/2016	Active	10056801
10056809	RAISBECK ENGINEERING Inc.	REV. 1	FAA STC SA02473SE	300, 300LW, B300, B300C	Installation of Raisbeck/Hartzell Swept Blade Turbofan Propellers.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. FAA-approved Airplane Flight Manual Supplement (AFMS) listed inRaisbeck Engineering Document 15-350S-ORL, Revision IR, dated January28, 2016, or later FAA-approved revision.2. Raisbeck Engineering Master Drawing List 15BC-61-000, Revision IR,dated January 28, 2016, or later FAA-approved revision....	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This installation requires the incorporati...	12/07/2018	Active	10056809
10056823	AIRBUS HELICOPTERS CANADA LIMITED		TCCA STC SH12-28	AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	AS350/AS355 Standard Interior modification including floor covering,seat coverings, document holder and panel painting	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CP-0355 REV. H Standard Interior Modification AS350/ AS355 ComplianceProgram.MDL-11-030 REV. H Master Drawing ListICA-ECL-242 REV. 4 Instructions For Continued Airworthiness, seat coversICA-ECL-243 REV. 2 Instructions For Continued Airworthiness, floor coverICA-ECL-244 REV. 2 Instructions For Continu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/02/2016	Active	10056823
10056836	AIRBUS DEFENCE AND SPACE S.A.			A330-202/-203/-243	DCV0232S Modified Electrical Bonding of Cockpit Door	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Defence and Space Declaration of Compliance Ref. TAE-FA-CO-150026dated 16.11.2015Certification Plan Ref. TAE-FA-DT-150033, A330 MRTT/ FSTA ModifiedElectrical Bonding of Cockpit Door (DCV0232S)or later revisions of the above listed documents approved by EASA.	This STC can only be installed, if one of following EASA STC waspreviously installed:-A330 MRTT EASA STC 10029272 or-A330 FSTA STC1 10034690 or-A330 FSTA STC2 10035945	22/02/2016	Active	10056836
10056844	SABENA TECHNICS BGC			777F 777-300, 777-300ER 777-200, 777-200LR	Mechanical & electrical installation for tablet computerThis STC deals with the installation on B777 of provisions bothmechanical (mounting assembly support on lower frame of eachcockpitsliding window) and electrical (DC/DC USB converter)for personal tabletcomputer.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:All affected paragraph at CS25 amdt. 4The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areu...	- Master Data List 0688-01-A-MDL-R00- AFM Supplement 0688-01-A-AFMS-R01- Instructions for continued airworthiness 0688-01-A-ICA-R01or later revisions of the above listed documentsapproved by EASA.	- Only for Electronic Flight Bag use. No other use permitted.- In case of Electro Magnetic Interference when tablet computer isconnected to electrical installation, the power supply cord must bedisconnected from the USB outlet (power supply plugs). It is theoperator's responsibility to determine tha...	23/02/2016	Active	10056844

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056848	RSG PRODUCTS, Inc.		FAA STC SR001115DE	EC130B4, EC130T2 AS350D AS350B, AS350BA AS350B1, AS350B2, AS350B3	Installation of a Video Camera System in accordance with Master DrawingList DL-4Note: This STC is the validation of FAASTC SR001115DE (date reissuedAugust 15, 2014)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Integrated Flight Systems. Inc. Master Drawing List DL-4 Revision FRSG Products Rotorcraft Flight Manual Supplement RFM-350/130-VS-01Revision Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/02/2016	Active	10056848
10056882	SOCIETE AIR FRANCE S.A.			A330-203	AERCAP Cabin rearrangement / PSS installationThe modification consists in cabin rearrangement from 243 passengers(30C +35Y + 178 M) to 326 Economic and Rockwell Collins PAVESTMPassenger Service System (PSS) installation (no IFE).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Change Approval Sheet CAS-A330-15-003 rev 0.Instruction forContinued Airworthiness, ref : ICA-A330-15-003 rev 0.or later revisions of the above listed documents approved by EASA.	This STC is applicable to MSN 811; 819; 834 & 900 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the p...	24/02/2016	Active	10056882
10056904	SCANDINAVIAN AVIONICS DESIGN ApS			650	P-RNAV approval of existing Dual Honeywell GNS-XLS FMS System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Technical Order, doc. No. 2034469-TO, issue 3, dated 11 January 2016-AFM Supplement, doc. No. 2034469-AM, issue 3, dated 16 February 2016or later revisions of the above listed documents approved by EASA	None	26/02/2016	Active	10056904
10056905	B/E AEROSPACE, Inc.		FAA STC ST03899AT	737-600/-700/-800/-900	Installation of a Collins SAT-2000 Satellite Communication System (SATCOM)-configuration 1 (B737-700/800): receiver installation-configuration 2 (B737-600/-700/-800/-900) receiver,antenna, audiopanel installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amdt11: 25.23 (a), 25.251(b) , 25.301(a)(b) , 25.303, 25.305(a)(e) ,25.307(a) , 25.337, 25.365, 25.561(c) , 25.581(a)(b) , 25.601,25.603(a)(b)(c) , 25.605(a) , 25.607,...	Master Drawing List 2-81151-001 rev FAFM Supplement 2-81151-811 rev AInstructions for Continued Airworthiness:-configuration 1 (B737-700/800) 2-81151-804 rev E-configuration 2 (B737-600/-700/-800/-900) 2-132771-806 rev Aor later revisions of the above listed documents approved by EASA inaccordance w...	As per AFMS the SATCOM communication system is not to be used during theapproach, landing and takeoff phases of flight.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair...	26/02/2016	Active	10056905
10056917 (EASA.IM.A.S.00664)	B/E AEROSPACE, Inc.	REV. 1	FAA ST02896AT	MD-90-30 MD-88 DC-9-34F/-41/-51, DC-9-80 DC-9-14/-15/-21/-32/ F/-33F/-34	Installation of a Kannad Model 406-AF Emergency Locator Transmitter (ELT).Revision 1 transferred from EMTEQ Engineering to B/E Aerospace.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 25.23, 25.561, 25.601,25.603, 25.611, 25.863, 25.869, 25.1301, 25.1309, 25.1322, 25.1351,25.1353, 25.1381, 25.1431 and 25....	Instructions for Continued Airworthiness (ICA), EMTEQ EngineeringDocument 2-23982-905, Rev. E, dated May 28, 2010.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10056917
10056930	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST03290CH	767-400ER SERIES 767-300 SERIES 767-200 SERIES	Certification of Compatibility with Cellular and Wireless DataTechnologies.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Armstrong Aerospace Master Data List Doc. No. DC104-9414-00, Revision -,dated December 20, 2013.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Limitations for installation utilizing the...	29/02/2016	Active	10056930

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10056934	SOCIETE AIR FRANCE S.A.			A330-243	Air Europa cabin rearrangementThis modification reconfigures the forward cabin area by mainly replacesBusiness Class seats Galley and In-Flight Entertainment System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approvalThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Change Approval Sheet, ref CAS-A330-14-004, dated 24 February 2016- Instruction for Continued Airworthiness document,ref :ICA-A330-14-004, dated 01 November 2015or later revisions of the above listed documents approved by EASA.	The EASA STC, ref: EASA.A.S.02580 Rev 1 (10014507 Rev. 1), or laterapproved revision, must be concurrently installed with thismodification.	26/02/2016	Active	10056934
10056949	AEROTEC & CONCEPT			E90	MOD 15179 - Glass Cockpit with G600 and MD302.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: FAR 23Amdt 1 thru 23.61.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and...	Airplane Flight Manual Supplement AE15179AFMS Rev. 0 dated 05 October2015Master Data List AE15179MDL Rev. 0 dated 10 December 2015or later revisions of the above listed documents approved by EASA.Instruction for Continued Airworthiness AE15179ICA Rev. 0 dated 05October 2015.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/02/2016	Active	10056949
10056957	DELTA ENGINEERING CORPORATION	REV. 3	FAA STC ST04037NY	A330-343	INSTALLATION OF GOGO 2KU - STRUCTURAL AND ELECTRICAL PROVISIONS.Rev. 2: Transfer to new STC holder Delta Engineering with FAA as PrimaryCertifying AuthorityRev. 3: updates the MDLand ICA	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 25AMENDMENT 1625.23, 25.29 (b), 25.301(a)(b)(c), 25.303, 25.305(a)(b)(c) , 25.307(a)(d), 25.321(a)(b)(c) , 25.365(a)(b)(c)(d) , 25.561(a)(b)(c) , 25.571(a)(b), 25.581(a...	Delta Engineering Master Data List (MDL) 0154-11329-2548 Revision -dated 19 August 2021<(>,<)>Instructions for Continued Airworthiness as listed on the Master DataList<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Impleme...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.No external antenna or radome is included in this desig...	19/12/2023	Active	10056957
10056959	BALLONBAU WOERNER GmbH			FKP-STU/510 FKP-STU/380 FKP-STU/280	Indoor operation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Appendix 4 to Instruction Manual for indoor operations - issue January2016or later revisions of the above listed documents approved by EASA.	The STC is applicable when the tethered balloons are operated inbuildings with a roof. During these operations an additional crew membermust be available to help the ground operator.	01/03/2016	Active	10056959
10057013	SCANDINAVIAN AVIONICS DESIGN ApS			AS 332 L2 AS 332 L1 AS 332 L AS 332 C1 AS 332 C	Universal FMS UNS-1Lw installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-29 Amdt. 3 paragraphs 1, 21, 29, 301, 303, 305, 307, 309, 601, 603,605, 609, 610, 611, 613, 771, 773, 853, 1301, 1309, 1...	- Flight Manual Supplement 2097844-AM Issue 4, dated 16.02.2016or later revisions of the above listed documents approved by EASA.- Engineering Order and Certification Program 2097844-EO Issue 2, dated16.02.2016- List of Certification Documents 2097844-DOC Issue 2, dated 16.02.2016- Compliance Record...	- The aircraft must have other approved navigation equipment installedand operating appropriate for the route of flightas backup for theFMS/ MMMS system.- This FMS/ MMMS installation is not approved for Vertical Navigation,WAAS(LP/LPV) operations, Approach Operations, Oceanic/ RemoteOperations, and c...	02/03/2016	Active	10057013
10057014	RHEINLAND AIR SERVICE GmbH			P.180 AVANTI II P.180 AVANTI	Installation of Skywatch TRC899 including antenna, GTN625 includingantenna, Flightstream210, Iridium antenna and USB charger.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements are thefollowing paragraph(s) at a later amendment:CS-23, Amendment 423, 29, 301, 303, 305, 365, 561, 571, 601, 603, 611, 613, 771, 773, 777,867, 1301, 1309, 1311, 1322, 1...	Flight Manual Supplement G600 RAS-15-02-02-FMS-00-Flightstream, Rev. 0Flight Manual Supplement ESI-2000 RAS-15-02-02-FMS-00-GTN625, Rev. 0Flight Manual Supplement PS835D RAS-15-02-02-FMS 00-TCAS, Rev. 0Instructions for Continued Airworthiness RAS-15-02-02-ICA-00, Rev. 0	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/03/2016	Active	10057014

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057016	SYNODON Inc.		TCCA STC SH12-55	206B	Bell 206B Synodon Camera Mount “Realsens Instrument Installation”.Installation of Synodon “realSens Optical Bench” model V17, modifiedTyler Mount model JR206, and cockpit display computers.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Flight Manual Supplement Bell 206B Realsens Instrument InstallationDocument CF-SYN-002, Revision 2, Dated October 24<(>,<)> 2012or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Compliance Prog...	VFR flight only.Sling operations not permitted.VNE is limited to 108 MPH IAS or as prescribed by the basic rotorcraftflight manual, whichever is less.The baggage compartment must remain empty when the camera installed.The equipment is not approved for installation on rotorcraft equippedwith VEMD ord...	02/03/2016	Active	10057016
10057019	STC HOLDING COMPANY, INC.	REV. 1	FAA STC SA7621SW	DHC-6	Installation of modified passenger door.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. R. W. Martin, Inc. Drawing No. RWM90029<(>,<)> dated June 6, 1989.2. Engineering Order No. 8911-01, Revision A<(>,<)> dated July 3, 1989.3. Engineering Order No. 8911-02<(>,<)>dated July 14, 1989, or laterFAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/09/2021	Active	10057019
10057020	NORTHERN AVIONICS S.R.L.			A119, AW119MKII	First Limit Advisory System (FLAS)The FLAS system is designed to trigger by means of a discrete output theAural WarningGenerator when one or more of the selected parametersexceedthe customer limit value.The warning provided is supplemental and auxiliary to the existingvisual/audio alerts already p...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement RFM NAV-0519 Rev. 0 AgustaWestlandA119/ AW119MKIIor later revisions of the above listed documents approved by EASA.,,,,- ICA-NAV0519 Rev. 0 Instructions for Continuous Airworthiness-II-NAV0519 Rev. 0 Installation Instructions.	The FLAS installation is applicable only on Helicopter installing:1- Electrical Display Unit Installation P/N DPN191-31003 or P/ NDPN191-310042- Northern Avionics FLAS Modification01531NAV0523.Prior to installation of this design change itmust be determined thatthe interrelationship between this de...	02/03/2016	Active	10057020
10057021	AEROTEC & CONCEPT			767-300	Airborne wireless platform activation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements are thefollowing paragraph(s) at a later amendment:CS25 at amdt. 15: 25.1301, 25.1309, 25.1353, 25.1431, 25.1529, 25.1581,25.1585.The requirements for environmental protec...	Master Data List AE14291MDL rev 0 dated 28/02/2016.AircraftFlight Manual Supplement AE14291AFMS rev 0 dated 18/02/2016.Instructions for Continued Airworthiness AE14291ICA rev 1 dated20/11/2015or later revisions of the above listed documents approved by EASA.	As per AFMS:WiFi system is prohibited to work and must be switched OFF duringrefuelling and Low Visibility Approach Operation, use “WIFI ON/ OFF”pushbutton located on CCP on the top part of FWD L/ H Attendant’s Area,above attendant seat.TPEDs (including GSM personal devices) are prohibited to work and...	02/03/2016	Active	10057021
10057027	S-TEC CORPORATION		FAA SR02254LA	R 44, R44 II	Installation of stability augmentation system and autopilotinaccordance with S-TEC Master Data List, HeliSAS-026Note: This STC is the validation of FAA STC SR02254LA (date amendedNovember 12, 2014)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): SC CRI F-01 for project 10035925 - “Installationof HeliSAS AP/SAS - EASA Type Certification Basis requirementsapplicable to Equipment, systems, and...	S-TEC Master Data List, HeliSAS-026, Revision E dated 10-16-14S-TEC Rotorcraft Flight Manual Supplement to the RobinsonHelicopterCompany R44 and R44 II Rotorcraft Flight Manual when aircraft areequipped with the HeliSAS®/Autopilot System,document No.ST-931-RFM-0001, Revision D dated February 1, 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/03/2016	Active	10057027
10057034	FALCON CREST AVIATION SUPPLY, INC.	REV. 1	FAA SR09054RC	206A, 206 B	Replacement of the original NiCad Battery with the ConcordeRG206 valveregulated sealed acid battery.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approvalor later revisionsof the above listed documents approved by EASA inaccordancewith EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/03/2016	Active	10057034

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057046	AVCON INDUSTRIES, Inc.		FAA STC SA03698AT	B300, B300C B200GT, B200CGT 200, 200C, B200, B200C	Installation of a Supplemental DC Power for an Isolated InstrumentalBus.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	1) Aviation Design Services Master Drawing List, ADS R001, Revision B,dated May 22<(>,<)> 2009; or2) Avcon Industries, Inc., Master Data List, ADS R001, Revision C, datedJanuary 18<(>,<)> 2012, or later FAA approved revisions.3) FAA approved Airplane Flight Manual Supplement for Aviation DesignServi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/03/2016	Active	10057046
10057051	AMTECH AERONAUTICAL LIMITED	REV. 1	TCCA STC NO. SH02-40	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Spectrolab & Trakkabeam Searchlight InstallationsThis STC is the validation of Canadian STC No. SH02-40.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of Spectrolab SX-5/SX-16/XP:- Engineering OrderEO342401, Revision 5, dated 17 March 2011- Flight Manual Supplement FMS342401, Revision 4, dated 17 August 2015- Maintenance Manual Supplement MMS342401, Revision 5, dated 8 March2011Installation of Trakkabeam A800/A800 (-1)/A800MKII:-Enginee...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/03/2016	Active	10057051
10057054	AIRBUS HELICOPTERS CANADA LIMITED		TCCA STC SH98-43	AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of Rear Crosstube Maintenance Steps (350-500604).This STC is a validation of Canadian STC no. SH98-43.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Helicopters Canada Limited Master Drawing List MDL-98-002, IssueC, Transport Canada approved 09 December 2014Airbus Helicopters Canada Limited Instructions for continuedAirworthiness ICA-ECL-235, revision 1, Transport Canada accepted 09December, 2014or later revisions of the above listed docu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/03/2016	Active	10057054
10057056 (2004-10115)	ROCKWELL COLLINS, Inc.		FAA STC ST00845SE	737-700,-800,-900,-900ER	Installation of the Head-Up Display Guidance System HGS Model 4000	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-01 Issue 2 “Certification Basis”The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areu...	- FAA Approved Airplane Flight Manual Supplement for the Boeing 737-700,-700C, -900, and -900ER Series Model 4000 Head-Up Guidance system (HGS),Ref. 523-0809596, Rev. 5- FAA Approved Airplane Flight Manual Supplement for the Boeing 737-800Series Model 4000 Head-Up Guidance system (HGS), Ref. 523-080...	As per AFMS Ref. 523-0809596 (Rev. 5), Ref. 523-0809592 (Rev. 5), andRef. 523-0809597 (Rev. 7) as applicable.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will intr...	04/03/2016	Active	10057056
10057058	COMTECH GLOBAL AVIATION SERVICES S.	REV. 1		A320-214 A319-115, A319-112	Introduction of Structural Provisions for Cabin Access Points	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:25.23, Amdt. 1725.25, Amdt. 1725.27, Amdt. 1725.29, Amdt. 1725.301, Amdt. 1725.303, Amdt. 1725.305, Amdt. 1725.307, Amdt. 1...	- CTE-MS0141-320 Modification Summary- CTE-WB0141-01 Weight& Balance Report- CTE-EO0141-01 Engineering Order, A319 aircraft- CTE-EO0141-02 Engineering Order, A320 aircraft- CTE-I0141-01-320 Structural Provision Installationor later revisions of the above listed document(s) approved/ acceptedunder th...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/06/2019	Active	10057058

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057068	VT MOBILE AEROSPACE ENGINEERING, In	REV. 2	FAA STC ST04242AT	757-200	Modification of Passenger Aeroplane to 15-Pallet Cargo ConfigurationRevision 1: Limitation related to winglets revised	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR-25 Change 11: 25.812(a)(b)(2)(d)(e)(f)(2)(g)(h)(i)(j)JAR-25 Change 13: 25.321, 25.331, 25.335, 25.341, 25.345, 25.349,25.351,25.365(d)(e)(f)(g), 25.365(e)(1)(2), 25.37...	-Master Drawing List (MDL), VT Mobile Aerospace Engineeringdocumentnumber 34000000, Revision D, dated 23 November2015.-Aeroplane Flight Manual Supplement, VT Mobile Aerospace Engineeringdocument number 757SF-AFM-01 Revision 5, dated 28 March 2016.-Instructions for Continued Airworthiness, VT Mobile...	It has been demonstrated that this modification is compatible withBoeing Model 757-200 Aeroplanes with winglets installed per AviationPartners Boeing STC ST01518SE<(>,<)> validated by EASA STC 10015659Rev.6. No other winglet installations have been evaluated.This modification must be installed concu...	17/01/2017	Active	10057068
10057076	HELI-ONE (NORWAY) AS			AS 332 L1 AS 332 L	Business Interior Upgrade in accordance with modification H1N332-00065	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CS29.811(d) Photo luminescent exit identifiers recorded in CRI D-01the following paragraph(s) at a later amendment:Elected to comply with CS-2...	- Product Change Declaration H1N332-00065-2201, dated 16.10.2015-Certification Programme H1N332-00065-2301 Rev. A, dated 12.11.2015-Declaration of Compliance H1N332-00065-2701, dated 16.02.2016-Continued Airworthiness Supplement H1N332-00065-1601, dated 27.01.2016	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/03/2016	Active	10057076
10057091	WIPAIRE Inc.		FAA SP03376CH	3GFR34C703	Installation of pitch locks	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Wipaire, Inc. Installation Instruction, Document No. 1005830, RevisionA, dated August 8, 2014.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/03/2016	Active	10057091
10057093	WIPAIRE Inc.		FAA SA03379CH	208B 208	Installation of McCauley Model 3GFR34C703 propeller, modified to includepitch locks per STC SP03376CH.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Wipaire, Inc. Drawing No. 1008230, Revision A, dated August 8, 2014,or later FAA approved revisions.2. FAA Approved Airplane Flight Manual Supplement, Document No.W208PL-25-01,No Revision, dated September 12, 2014, or later FAAapprovedrevisions	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/03/2016	Active	10057093
10057114	BHE & ASSOCIATES, LTD.	REV. 5	FAA STC SA11133SC	B300, B300C B200, B200C, B200GT, B200CGT	Installation of a Rockwell Collins Pro Line 21 update to includeoptional TAWS mode 5 warnings during LPV approaches, optional ADS-B Outand optional synthetic vision system (SVS).Rev. 3 adds serial numbers of Textron Aviation B200 and B300 aircraftand version 10.4 Pro Line 21 displays.Rev. 4 adds anD...	a. The type certification basis for Beechcraft Corporation B200, B200C,B200 GT, B200CGT, B300 and B300C airplane is shown on TCDS A24CE forparts not changed or not affected by thechange.b. The certification basis for parts changed or affected by the changesince the reference date of application, 19...	1. Master Drawing List 543-00-0001, revision K, dated 21 November 20162. Airplane Flight Manual Supplement 543-00-0055,revision B, dated 14November 20163. Instructions for Continued Airworthiness 543-00-0056, revision B,dated 21 November 2016or later revisions of the above listed document(s) approv...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Must have factory installed Pro Line 21 (B...	06/08/2025	Active	10057114
10057145	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 P2+, EC135 T2+	Installation of Trakka A800 Search Light on the forward endof the lefthand landing gear step (AHUK/135/3030) in accordance with Drawing ListAHUK/1353030-001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement Installation of Trakka A800 SearchLightAHUK/135-FMS-101, Issue 0or later revisions of the above listed documents approved by EASA.Drawing List AHUK/1353030-001, Issue BInstructions for Continued Airworthiness ICA-135-3030-3256, Issue A,,	As prerequisite LH Meeker Aviation Step Utility Mount in accordance withEASA STC 10017058 must be installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will intro...	09/03/2016	Active	10057145

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057148	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04025AT-D	G280	Activation of LINK 2000+ software function.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI F-36 Data Link Services for Single European SkyCRI F-37 Flight Recorders including Data Link RecordingThe requirements for environmental protectio...	Airplane Flight Manual Supplement G280-GER-0012, Rev "-", dated 09 April2015.Gulfstream Index List GA411318004 Rev "-",dated 09 April 2015or later revisions of the above listed documents approved by EASA.	- Aircraft Avionics Suite 3.6 or later EASA approve, is required forthis STC.- The following STC is required to be installed for this STC: 10052498,Installation of an Executive Cabin Interior.Prior to installation of this design change it must be determined thatthe interrelationship between this des...	09/03/2016	Active	10057148
10057166	BHE & ASSOCIATES, LTD.	REV. 1	FAA ST02325LA	400A	Installation of Rockwell Collins Flight Management System FMC 5000software Version 4.0.Rev. 1: Change of Address	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. FAA approved Airplane Flight Manual Supplement, Cutter AviationDocument No. CA1004-AFM, revision IR, dated 06 December 2010 or laterFAA approved revision.2. FAA Approved CutterAviation Master Drawing List (MDL) Document No.CA1004-MDL, Revision A, dated 03 December 2010.3. Instructions for Contin...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The pre-modified baseline system must meet...	07/08/2025	Active	10057166
10057199 (EASA.IM.R.S.00552)	ONBOARD SYSTEMS INTERNATIONAL	REV. 4	FAA SR00713SE	3. AB 412, AB 412EP 2. 212, 412, 412EP 1. 204B, 205A-1	Installation of Onboard Systems International Cargo Hook Suspension Kitin accordance with master drawing list 155-048-00Reasons for the revision of the approval:Revision 1 issued to correct the RFM document number.Revision 2 issued to extend the approval to the Bell 412Revision 3 issued to extend th...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement Cargo Hook SuspensionKit DocumentNumber 121-021-00 Revision 4, dated August 1, 2012.- Rotorcraft Flight Manual supplement Cargo Hook Suspension Kit DocumentNumber 121-060-00 Revision 0, dated October 13 2015or later revisions of the above listed documents appro...	Approval of this change in type design is only applicable to the modelslisted in this certificate which were previouslyequipped with BellCargo hook suspension assembly Part Number 204-072-915-25 or Part Number204-072-915-103.The Cargo Hook suspension systems, as installed in accordance with thisapp...	13/01/2017	Active	10057199
10057223	DRF STIFTUNG LUFTRETTUNGGEMEINNUETZIGE AG	REV. 2		EC135 P2/ EC135 P2+	Installation of GNC 255B and GTN 650 COM/NAV System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27 Amdt 3: CS27.1/21/25/27/29/251/303/305/307/561/601/603/605/607/609/610/613/771/773/1301/1309/1321/1322/1351/1357/13...	- Flight Manual Supplement FMS 10-DRF-033, Revision 00,: Supplement forGTN 650 & GNC 255B dated January 14, 2016.or later revisions of the above listed documents approved by EASA.- Master Document List MDL-135-34-60-00001, Revision 00, dated19/02/2016.- Compliance Check List Doc N° CC-135-34-60-0000...	Limited to VFR operation only.Prior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	08/04/2016	Active	10057223
10057244	AVIANOR INC	REV. 1		A330-243	Modification of Recaro Model 6510 passenger seats by changing dresscovers<(>,<)> revising trim and installing Zii RAVE IFE equipment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AVIANOR MASTER DOCUMENT LIST MDL15142901 REV. NC DATED 15 DECEMBER 2015	NOTE THAT THIS APPROVAL IS FOR SEAT MODIFICATIONS ONLY. INSTALLATION OFTHE MODIFIED SEATS ONTO THE AIRCRAFT AND THE RAVE IFE EQUIPMENT IS TO BEIN ACCORDANCE WITH EASA STC REFERRING TO EASA PROJECT NO. 0010041560Restricted to ASNs 261 and 265.	04/04/2016	Active	10057244

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057276	BOMBARDIER Inc.		TCCA C-LSA13-079/D ISSUE 2	BD-700-1A10	Display of EVS (Enhanced Video System) Video on Copilot's MFD	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification in accordance with ACS-NAI Ltd. Modification Data SummaryJ113000 Revision A;Refer to Maintenance Manual Supplement J113071 Revision NCor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreem...	Supplemental Type Certificate limited to serial number aircraft 9264	18/03/2016	Active	10057276
10057280	DUNLOP AIRCRAFT TYRES LIMITED		CAA UK RESPONSIBILITY	DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301	Installation of Dunlop P/N DR 26222T Bias Main Landing GearTyre(s) onthe DHC-8-300 Series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25.105 (a)(c), 25.109, 25.125 (a)(b)(e)(f), 25.233 (a)-(c), 25.235,25.305, 25.471, 25.473, 25.477, 25.479, 25.481, 25.483...	Installation has to be in accordance with DATL - PR11 - MDL.or later revisions of the above listed documents approved by EASA.DATL - PR11 - ICA – Instructions for Continued AirworthinessDATL - PR11 - AMMS – Aircraft Maintenance Manual	None	18/03/2016	Active	10057280
10057292	AMAC AEROSPACE SWITZERLAND AG			737-800	Replacement of Large Monitors,,Replacement of the currentlyinstalled large monitors with new largemonitors of less weight as defined in the Master Data List, Doc. No.MDL-AR10-4420, Rev. B, dated 16.03.2016,,	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-10, Glass Screens ofDisplays / Monitors.The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	Master Data List, Doc. No. MDL-AR10-4420, Rev. B, dated 16.03.2016	Valid for MSN 35792 onlyPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	18/03/2016	Active	10057292
10057319	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 3		767-300ER	Aviation Traders Limited Modification ref. MOD-11930-00001 issueRev. 1: Installation of Crew Rest Module.This Modification installs a pallet-mounted crew rest module of similardimensions as standard A2 Unit Load Device in the A1 cargo containerposition in front of the main cargo deck in accordance w...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI F-110, Cabin Crew Portable OxygenEquipment, CS 25.1443(a)(b)(d)(e), 25.1447 (c)(4), 25.1449.The requirements for environmental protectio...	- ATL MDL ref. MDL-11930-00001 issue 7.- ATL AFM-S ref. 11930-AFM-00001 issue 1.- ATL Modification Summary Sheet MOD-11930-00001 issue 1Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This approval applies to Boeing 767-300 series model aeroplanes that arepassenger-to-freighter converted in accordance with EASA STC 10028430.ATL modification ref. MOD-11390-00002, airframe provisions for crew restmodule is a pre-requisitetothis STC.Aeroplanes modified by this STC must be operateda...	21/08/2023	Active	10057319
10057324	COMTECH GLOBAL AVIATION SERVICES S.	REV. 1		A319-111	Introduction of 144 passenger interior configuration and associatedcabin changes	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 Amendment 17 (various).The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	COMTECH Aviation Services Master Data List No. CTE-MDL0142-319 Rev. –dated 18 March 2016or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	Restricted to MSNs 2240 and 2253.The installation must be accomplished concurrently with the introductionof the Lufthansa Technik AG Self-illuminating Floor Path Marking Systemunder EASA STC 10014013 Rev. 2.This change installs replacementSELCAL code & aircraft registrationplacards to the cockpit.t...	12/06/2019	Active	10057324
10057326	JCB AERO SA			757-200	B757 Cabin Modification B752-24527-03 initial issue.The modification consists in replacing the In-Flight Entertainmentsystems, modifying the lighting systems, installing a new In-Seat PowerSupply System and re-arranging the monuments on-board a VIP configuredBoeing B757-200 in accordance with JCB Ae...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-01 iss.01 & D-02 iss. 01Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	JCB Aero-AFM-S reference B752-24527-03-AFMS-01 initial release-ICA-S reference B752-24527-03-ICA-01 Initial release.or later revisions of the above listed documents approved by EASA.JCB AERO-Master Drawing List reference B752-24527-03-MDL-01 Revision J-Service bulletin B752-24527-03-SB-01 Revision A...	Limited to MSN 24527 onlyAeroplane(s) converted by this STCmust be:(a) operated in accordance with the latest approvedcopy of thefollowing JCB AERO document:- Flight Manual Supplement Document reference B752-24527-03-AFMS-01(b) maintained in accordance with the following JCB AERO document:- Supplem...	22/03/2016	Active	10057326

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057327	JCB AERO SA			757-200	B757 VIP lavatory installation Modification No. B752-24527-07 InitialRelease.The modification consists in replacing thewardrobe with a new VIPlavatory between Door 1 and Fuselage Station 450, in accordance withJCB Aero Master Drawing List reference: B752-24527-07-MDL-01 Revision A.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-JCB AERO ICA-S reference B752-24527-07-ICA-01 Initial Releaseor later revisions of the above listed documents approvedby EASA.-JCB AERO Service Bulletin ref. B752-24527-07-SB-01Revision A.-JCB AERO Master Drawing List ref. B752-24527-07-MDL-01 Revision A.	Limited to MSN 24527 onlyAeroplane(s) converted by this STCmust be:maintained in accordance with the following JCB AERO document:-Supplemental instructions for Continued Airworthiness, DocumentB752-24527-07-ICA-01 Initial Release.JCB AEROModification B752-24527-07 is a concurrent modification toMo...	22/03/2016	Active	10057327
10057328	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	A319-112	Airbus A319 Cabin WiFi System Installation for IFE streaming	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-H4 Aerospace Flight Manual Supplement No. H4AFMS040 Revision Initial-H4 Aerospace Instructions for Continued Airworthiness No. H4ADR972Issue 2or later revisions of the above listed documents approved by EASA.-H4 Aerospace Modification Summary No. H4A1810 Issue 1 dated 18 March2016	Restricted to MSN's 1598 1625Future modifications must consider the Wifi 2.4GHz and 5GHz RFenvironment during the design.	22/03/2016	Active	10057328
10057329	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	JETSTREAM SERIES 3100	Installation of a Flight Navigation System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-25 Amendment 4 -25.603; 25.605; 25.609; 25.611; 25.613; 25.771; 25.773; 25.789; 25.899;25.1301; 25.1302; 25.1309; 25.13...	Cranfield Supplement No. 5 Issue 3 dated July 2014 to Jetstream CAAApproved Flight manual Doc. No. HP. 4.11or later revisions of the above listed documents approved by EASA.Cranfield Aerospace Ltd Type Design Definition Addendum CA/DD/ DR0033Issue E dated 21 March 2016Cranfield Aerospace Ltd Declarati...	Aircraft Serial Number 614 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	22/03/2016	Active	10057329
10057330	TASS-EU Ltd.	REV. 1	CAA UK RESPONSIBILITY	757-200	Installation of GPS Antenna provisions	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amendment 17: 25.301; 25.303; 25.305; 25.307;25.571; 25.601;25.603; 25.605; 25.607; 25.609; 25.611; 25.613; 25.625; 25.1310(a); 25.1529The requirements for environmen...	TASS EU Change Classification and Certification Sheets No.s101046-CCSa-132 Revision 10 dated 21 March 2017 and 101046-CCSb-132Revision 10 dated 21 March 2017	None	21/03/2017	Active	10057330
10057351	VT DRB AVIATION CONSULTANTS, INC.	REV. 2	FAA STC ST11167SC	737-700	VIP Interior Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-02 Isolated CompartmentsCRI D-05 Glass Screens of Displays and MonitorsCRI D-06 Shower InstallationCRI D-08 Injury Criteria for Side Facing Diva...	VT DRB AIRPLANE FLIGHT MANUAL SUPPLEMENT No. 8052CT25-01 Revision A.VT DRB Instructions for Continued Airworthiness No.8052CT25-03 RevisionA.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/...	Restricted to MSN 60406EASA STCs No.s 10053109 "Structural modification necessary for theinstallation an EMS AMT-3800 SATCOM antenna"<(>,<)> EASA.IM.A.S. 03088"Installation of Aft Wing Fairing Acoustic Thermal Installation Kit"<(>,<)> and 10051622 "Installation of an Auxiliary Fuel System" must be in...	14/04/2016	Active	10057351

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057355	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	A319-112	MOD. H4A1804 Issue 1 - Palletised Business Class Seat Configurations onAirbus A319:Initial configuration B: 48 BusinessClass SeatsFinal configuration A: 50 Business Class Seats	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Summary Sheet and Declaration of Compliance Ref.H4A1804Issue 1 dated 22 March 2016- Instructions for continued airworthiness Ref.H4ADR964 Issue 3 dated 16March 2016- Weight and Balance Report (50 B/C Seating Layout) Ref.H4AWB564 Issue 1dated 11 March 2016- Weight and Balance Report (4...	Applicability is limited to A319-112 MSN 1598 and MSN 1625.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of t...	23/03/2016	Active	10057355
10057357	BROMMA AIR MAINTENANCE AB			MBB-BK117 D-2	Installation of auxiliary fuel tank system	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): ESF CRI G-2 FAR/ CS29.1555(c)(1)usablefuel capacity marking.- The following paragraph(s) at a later amendment: CS-29 Amdt. 3. Forparagraph2...	ALS embodied under document BAM ICA-14-01-D-2 chapter 1.6BAM FMS-14-01-D-2 rev.Aor later revisions of the above listed documents approved by EASA.BAM Certification Program CP-14-01 Rev.B dated 16 December 2015BAM ICA-14-01-D-2 Rev.A dated 02 March 2016BAM Compliance Report CR-14-01-D-2 Rev.A dated 1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/03/2016	Active	10057357
10057361	KNSI AVIATION ENGINEERING LIMITED	REV. 8	CAA UK RESPONSIBILITY	DHC-6 SERIES 400 DHC-6 SERIES 300 DHC-6 SERIES 200	Removal of Bleed Air, Cabin Heat and Engine Air Intake Deflector Systemsin accordance with KNSI Change Bulletin Number 15K263-CB-001-8.R(addition of MSN 330, 410, 414, 513).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-23 incl. Amdt. 4:23.23(a)(b), 23.301(a)(b), 23,331(c), 23.347(a), 23.601, 23.603(a)(b),23.605(a), 23.607(a)(b), 23.6092...	Aircraft Flight Manual Supplement 15K263-AFM-003-8.RAircraft Flight Manual Supplement 15K263-AFM-004-1.RMaster DocumentList 15K263-MDL-001-8.RAircraft Maintenance Manual Supplement 15K263-AMM-002-8.RIPC supplement 15K263-IPC-001-8.RIPC supplement 15K263-IPC-002-2.Ror later revisions of the above li...	Limited to:a) DHC-6 Series 200 with Serial Number 045;b) DHC-6 Series 300 with Serial Numbers: 234, 256, 259, 270, 283,288,291, 308, 324, 330, 347, 364, 372, 375, 410, 414, 435, 449, 451, 467,493, 513, 561, 580, 582, 587, 597, 625, 640, 652, 657, 659, 663, 668,687, 691, 700, 701, 722, 751, 753, 754...	09/12/2019	Active	10057361
10057364	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		A320-232	Interior modification on Qatar Airways aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0501-D90, Revision -, dated 22 March 2016.-Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0501-D70, Initial Release,dated 16November 2016or later revisions of the above listed...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/03/2016	Active	10057364
10057368	IAC - INDUSTRIAS AERONAUTICAS DECOIMBRA, Lda.			TR182 182R	Modification for skydiving operationIt includes the modification of the right door to open it upwards, theremoval of the co-pilot control wheel, and the introduction of aninstrument panel protection and a static line parachutes support. Theaircraft allows up to four skydivers after the modification....	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):SC-O23-div-01 Parachuting ActivityThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- IAC-C182RG-AFMS For Parachuting Activities in Cessna Models R182,TR182 ED.1or later revisions of the above listed documents approved by EASA.- IAC-21 .MOD.M-450112 Project Dossier Issue 1- IAC.C182RG.MDL Master Data List Issue 1- IAC-C182RG Annex I Manufacturing Issue 1- IAC-C182RG- I.I. Installat...	Aircraft MSN 6848 , 6910 , 6976 , 7032 , 7114Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	23/03/2016	Active	10057368

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057612	AIRBUS HELICOPTERS CANADA LIMITED		TCCA SH16-11 ISSUE 1	EC 130 T2 EC 130 B4 AS 350 D AS 350 BB AS 350 BA AS 350 B3 AS 350 B2 AS 350 B1 AS 350 B	Provision for ENGINE AIR INTAKE COVER installation, P/N 350-700924.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List MDL-15-006 Issue C, 1st March 2016.Instructions for Continued Airworthiness ICA-AHCA-296 revision 0, 1stMarch 2016.Compliance Program CP-0401 Issue A, 1st March 2016.,,	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/03/2016	Active	10057612
10057630	AEROTEC GROUP S.A.S.transferred to 309218 with 707360			EC135 T2+	Night Vision Goggles (NVG) Compatible Lighting System.This STC adds interior and exterior lighting to the helicoptercompatible with the use of the Night Vision Goggles (NVG).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS27/29 Amendment 3:27.01/27.21/27.29/27.141(c)/ 27.561(b)(3)/ 27.603/27.607/27.609/27.610/27.611/27.771/27.773/27.779/29....	Flight Manual Supplement ATG-MV-ECJIL135-02_01, dated 23/02/16,,or later revisions of the above listed documents approved by EASA.Design Definition File ATG-DD-ECJIL135-02_01, dated 27/11/2015User's Manual ATG-DTU-006-001_R03, dated 27/11/2015Installation Manual ATG-DTI-ECJIL135-02_02, dated 20/01/2...	Applicable to helicopter S/N 0407.This STC applies only to the S/N listed above. This rotorcraft employsNight Vision Imaging System lighting, commonly named NVIS lighting thathas been certified to ensure the aircraft is compatible with nightvision goggles (NVG). For this reason modifications that ad...	31/03/2016	Active	10057630
10057634	AEROTEC & CONCEPT	REV. 1		737-900ER 737-800	Airborne wireless platform activationRev1: list of associated documents corrected	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 at amdt. 15: 25.1301, 25.1309, 25.1353, 25.1431, 25.1529, 25.1581,25.1585The requirements for environmental protection and the associatedcertified noise and/ or emiss...	Master Data List AE14196MDL rev 0 dated 02/03/2016Aircraft Flight Manual Supplement AE14196AFMS rev 0 dated 23/02/2016Instructions for Continued Airworthiness AE14196ICA rev 0 dated02/12/2014or later revisions of the above listed documentsapproved by EASA.	As per AFMS-WiFi system is prohibited to work and must be switched OFF duringrefuelling and Low Visibility Approach Operation, use "WIFI ON/ OFF"pushbutton located on CCP on the top part of P13 FWD Attendant's panel,near to the existing PA announcement panel.-TPEDs (including GSM personal devices) ar...	05/04/2016	Active	10057634
10057644	LUFTHANSA TECHNIK AG			A320-231/-232/-233 A320-211/-212/-214/-215/-216	Introduction of new Cabin Layout,,This cabin modification will increase the cabin layout from 168 M-Classseats in the current cabin layout up to 174 M-Class seats after themodification. This will be accomplished by the removal of lavatories,the installation of new narrower lavatories and one additio...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document, Doc. No. STDD25-15/32M, Rev, 1.0, dated 31.03.2016- ICA, Doc. No. A-00-16/07-ICA, Rev. 01/00, dated 01.02.2016or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/04/2016	Active	10057644
10057646	BLACKHAWK MODIFICATIONS Inc.		FAA STC SA02546LA	208B 208	Installation of P<(>&<)>W PT6A-140 and 3-blade Hartzell PropellerHC-B3TN-3AF (Y)/T10890CN0(K)-2 propeller, also Ametek MG94K-2 325 AmpStarter Generator, Howell Instruments powerplant indicating system, andassociated equipment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):SC-23.0901-01, Issue 2the following paragraph(s) at a later amendment:CS-23, incl. Amdt. 4:23.1, 23.25, 23.29, 23.33, 23.45 , 23.53 , 23.63, 23.65, 23...	- FAA approved Master Drawing List 201321-000, Rev. IR, dated April 6,2015- FAA approved Aircraft Flight Manual Supplement AFMS 201321-208, Rev.IR, dated October 9, 2015- FAA approved Aircraft Flight Manual Supplement AFMS 201321-208B, Rev.IR, dated October 9, 2015or later revisions of the above lis...	This modification is not compatible with Textron (Cessna) Model 208,Serial Number 20800500 and greater or Textron (Cessna) Model 208B SerialNumber 208B1190, 208B1216, and 208B2000and greater (Garmin 1000installations) and aircraft equipped with TKS installation.Prior to installation of this desingnt...	01/04/2016	Active	10057646
10057648	BOND HELICOPTERS EUROPE Ltd.	REV. 1	CAA UK RESPONSIBILITY	EC135 T2+	Norwegian Aircraft Reconfiguration – BOND/MOD/118 - NVIS – EC135Description:This change fits two Meeker steps to carry an MX-15 camera and aNightsun XP searchlight (both relocatedfrom the belly pod), one eachside.Other equipment from the belly pod is relocated inside the aircraft.An existing CRT mo...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS27 Amdt 3, as included in BOND CCL 118-003 Issue 2, including CS 27Amdt 3 Appendix C for Cat A certification.The require...	Flight Manual Supplement for Norwegian Aircraft reconfiguration NVIS,EC135 – Doc FMS/ 118-002 Issue 2or later revisions of the above listed documents approved by EASA.- Design Report Doc DR/118-001 Issue 3, dated 31 March 2016.- Compliance Check List CCL/118-003 Issue 2, dated 5 February 2016- Compli...	- Rotorcraft modified by this STC employs Night Vision Imaging Systemlighting, commonly named NVIS lighting, which has been certified toensure the aircraft is compatible with Night Vision Goggles (NVG). Forthis reason, any deviation from the cockpit or cabin configurationspecified in this STC may af...	18/04/2016	Active	10057648

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057657	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR9600RC	BELL 412EP	Installation of Bell BasiX-Pro Glass Cockpit and Pratt & Whitney CanadaPT6T-9 Twin Power Section Turboshaft engines andassociated systems,designated as the "412EPI", in accordance with Master Drawing List No.AA-11023.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Appendix 1: Certification Basis(1) The type certification basis for Model 412EP helicopter as shown inEASA. IM.R.106 remains valid for 412EP parts not impacted by thischan...	-Rotorcraft Flight Manual Report No. AA-11045 Revision C, dated January21, 2016.- Rotorcraft Flight Manual Supplement for Category A Operations withPT6T-9 Engine Installation Report No. AA-12087 Revision C, dated January21, 2016.or later revisions of the above listed documents approved by EASA inacco...	1) This STC is limited to 412EP aircraft serial number 36248 andsubsequent or those otherwise modified to be equivalentwith regards todual AHRS (LCR-100) wiring and installation.For aircraft serial numbers36248 through 36490, the dual LCR-92 AHRS installation must be replacedwith the dual LCR-1007...	04/04/2016	Active	10057657
10057662	EMBRAER GPX Ltda. (PC 722)		ANAC BRAZIL REF 2013S09-09	EMB-505	Installation of Pilot's new extended seat tracks.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation in accordance with Master Document List ref No ESCCCD043Rev C, dated 20 September 2013- Operation in accordance with ANAC Approved Flight Manual Supplement(AFMS) Document ref No H. 02-4131-0/ANAC/2013 Rev IR, dated 24 September2013- Instructions for Continued Airworthiness in accordanc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/04/2016	Active	10057662
10057665	DAVIS AVIATION SERVICES		FAA STC SA2830SO	U206, U206A THROUGH G 206, P206, P206A THROUGH E	Installation of a Teledyne Continental Motors (TCM) model IO-550F engine along with either a McCauley model D3A34C420/90DFA-10,D3A34C401/90DFA-10, D3A34C401/90DFA-8, D3A34C402I90DFA-10,D3A34C402I90DFA-8 or a Hartzell model HC-C3YF-1RF/F9587C15S,PHC-C3YF-1RF/F8468A-6R, PHC-J3YF-1RF/F8468A-6R, PHCC3YF-...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Bonaire Aviation Company "Instructions Continental IO-550-FInstallation Cessna 206 Series Aircraft", Revision E, dated August 1,1998, or later FAA approvales revision.2. The following Bonaire Aviation Company Supplemental Airplane FlightManuals, and Pilot's Operating Handbook and Airplane FlightS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/04/2016	Active	10057665
10057671	HARTZELL PROPELLER LLC	REV. 1	FAA STC SR03474CH	407	Installation of Heli-Preheat Kit, p/n TA3083-1 for 115 voltapplicationorInstallation of Heli-Preheat Kit, p/n TA3083-2for 230 volt application.Rev. 1: This amendment changes Tanis part and drawing numbers toHartzell part and drawing numbers and changes the EASA Design ApprovalHolder's name and add...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For 115 volt preheater kit:Heli-Preheat Kit drawing TA3083-1, Revision J, dated 17 July 2023, andPreheat-Kit Installation Instruction TNH3083, Revision J, dated 17October 2019<(>,<)>For 230 volt preheater kit:Heli-Preheat Kit drawing TA3083-2, Revision J, dated 17 July 2023, andPreheat Kit Install...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/01/2024	Active	10057671
10057674	HARTZELL PROPELLER LLC	REV. 1	FAA STC SR03168CH	429	Installation of Heli-Preheat Kit, p/n TA2584-1 for 115 voltapplicationand Heli-Preheat Kit, p/n TA2584-2 for 230 volt applicationRev. 1: changes the TCCA Design Approval Holder'sname and address fromthat for Tanis Aircraft Products ("Tanis") to those for Hartzell.Tanis part and drawing numbers are...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. FAA Approved Rotorcraft Flight Manual Supplement, Document TFMS2584,Rev A, dated 25 September 2012<(>,<)>2. Instructions for Continued Airworthiness (ICA)<(>,<)> document TCA1000 Revision D, dated 7 August 2023 and Operating Guide document TPG1000 Revision F, dated 7 August 2023<(>,<)>3. For 1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/04/2024	Active	10057674

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057677	EICHELSDOERFER GmbHFLUGZEUGBAU			DUO DISCUS	Modification of the fuselage for Installation of a jet-engine	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Modification of the fuselage for installation of a jet-engine (Änderungdes Rumpfes zum Einbau eines Jet-Triebwerkes)orlater revisions of the above listed documents approved by EASA.-Project description-List of modification-Load Test-Reinforcement of fuselage and tempering-Pictures of the de-instal...	Flight Operation manual Update for Duo Discus SNo 204Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willintroduce noadverse effect upon the airworthiness of the pro...	05/04/2016	Active	10057677
10057679	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC SA11134SC	C90GTI	Installation of a Rockwell Collins Pro Line 21 update to include TAWSmode 5 warnings during LPV approaches, ADS-B Out and optional syntheticvision system (SVS).Rev. 1: Change of Address	New Certification Basis: Based on 14 CFR §§ 21.115 and 21.101, and theFAA policy for significantchanges in FAA Order 8110.48, the certification basis for the BeechcraftCorporationB300 and B300Cmodified by installing the Rockwell Collins Pro Line 21 update toinclude TAWS mode 5 warnings duringLPV ap...	1. Master Drawing List 544-00-0001, revision E, dated 12/11/2015 orlater approved FAA revision.2. Airplane Flight Manual Supplement 544-00-0055, revision IR, dated12/11/2015 or later FAA revision.3. Instructions for Continued Airworthiness544-00-0056, revision A ,dated November 12, 2015 or later FA...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Must have factory installed Pro Line 21 an...	06/08/2025	Active	10057679
10057682	GYRON SYSTEMS INTERNATIONAL, Ltd.		FAA STC SR02288LA	AS 350 B/ AS 350 B1/ AS 350 B2 AS 350 B3/ AS 350 BA/ AS 350 D	Installation of Nose Window Utility Mount in accordance with FAAapproved Gyron Systems International, LTD Master Drawing List AFNW-010.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirements for environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	- Master Drawing List, AFNW-010, Rev. A, dated June 25, 2014.- Installation Instructions, AFNW-006, dated March 12, 2014.- Rotorcraft Flight Manual Supplement, AFNW-007, dated March 20, 2014.- Instructions for Continued Airworthiness, AFNW-008, dated January 14,2014or later revisions of the above li...	Installation of Nose Window Utility Mount addresses only the Subpart B(Flight) and C (Strength Requirements) of Code 14of Federal AviationRegulations, Part 27.Installation not approved for AS350B3 incorporating Airbus Helicoptersmodification OP-3369 (2370kg weight extension) or Airbus Helicoptersmo...	06/04/2016	Active	10057682
10057686	STG AEROSPACE GERMANY GmbH	REV. 2		DHC-8-402 DHC-8-401/-402 DHC-8-315, DHC-8-401 DHC-8-311, DHC-8-314 DHC-8-301/-311/-314/-315 DHC-8-202, DHC-8-301 DHC-8-106, DHC-8-201 DHC-8-102, DHC-8-103 DHC-8-102/-103/-201/-202	PL AISLE PATH MARKING SYSTEMRevision 01: SuperSeal Ultralight (SSUL) Blue emitting and additionalcolor film inserts andsealants/ adhesives added.Revision 2: Transfer of STC holderfrom STG Aerospace Limited to STGAerospace GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:For AircraftDHC-8-402, DHC-8-401: The Certification Basis (CB)for the originalproduct remains applicable to this certifica...	The change is defined with Revision E of Master Data List DocumentSG-1002-MDL-01. The aircraft shall be operated in accordance withRevision B of Airplane Flight Manual Supplement Document SG-1002-FMS-01.The aircraft shall be maintained in accordance with Rev. B ofInstructions for Continued Airworthi...	Limitations as per Airplane Flight Manual Supplement documentSG-1002-FMS-01 and per Instructions for Continued Airworthiness documentSG-1002-ICA-01.SSUL Green Emitting Photoluminescent insert shall not be mixed with SSULBlue Emitting Photoluminescent insert on the same aircraft installation.Prior to...	12/02/2021	Active	10057686
10057696	CONCORDE BATTERY CORPORATION		FAA STC SA01653LA	P180	Installation of Concorde Battery RG-380E/40L.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Concorde Battery Corp. FAA Approved Airplane Flight ManualSupplement, Supplement No. 5-0239, FAA approved on September 10, 2004,or later FAA approved revisions.2. FAA approved Concorde Battery Corporation Master Drawing List,Drawing No. 5-0127, Revision "B", dated August 20, 2004, or later FAAapp...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/04/2016	Active	10057696

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057702	SCANDINAVIAN AVIONICS DESIGN ApS			BELL 412/412EP	Installation of Sandel Avionics ST3400H HTAWS.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS-29 Amdt 3 paragraphs: CS29.1, CS 29.29, CS 29.301, CS 29.303, CS 29.305, CS 29.307, CS 29.321,CS 29.341, CS 29.601, CS2...	- RFM Supplement Doc. 2085628-AM Issue 5 dated 22.02.2016orlater revisions of the above listed documents approved by EASA.- Engineering Order and Certification Program Doc. 2085628-EO Issue 2dated 25.02.2016;- Compliance Record Doc. 2085628 COR Issue 2 dated 26.01.2015;- Compliance Record to MG 1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/04/2016	Active	10057702
10057703	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A330-203	Economy Class Seat Replacement of EVA Air Aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0484-D90, Revision -, dated 30 March 2016Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0484-D70, Revision A, dated 1March2016or later revisions of the above listed documents ap...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/04/2016	Active	10057703
10057705	STC TWENTY ONE LIMITED	REV. 2	CAA UK RESPONSIBILITY	ATR 72-212A '600 VERSION' ATR 42-500 '600 VERSION'	Introduction of AFIRS 228.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	STC Twenty One Limited Flight Manual Supplement No. S21.FMS-0128 Issue3;STC Twenty One Ltd Master Document List S21.MDL-1259 Issue 1;or later revisions of the above listed documents approved by EASA.	The Satcom voice function of the AFIRS 228 system is not approved forcommunication with Air Traffic Control under this Design Change.The Operator/Installer must conduct ground EMItesting for each aircraftinstallation to mitigate EMI risksdue to build standard differences.Any interference observedp...	02/10/2018	Active	10057705
10057706	SAAB AB	REV. 2		NH-500D 369HM, 369HS 369HE, 369HM, 369HS 369D, 369E, 369H, 369HE 369D, 369E, 369FF, 369H	Original Issue: Increase payload of Data Acquisition Module- Hardware,DAM-H, Vision Mount Module InstallationRevision 1: Transfer of STC from SAAB AB (EASA.21J.108) to SAAB AB(EASA.21J.066)Revision 2: Addition of model 369FF to applicability list and referenceto the latest issues of the associatedt...	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	TDM14-30 Rev. C as defined in TDM14-30-0-LEP, Revision C, dated 08 March2024RFM Supplement TDM14-30-4-RFMS, Rev C, dated 9 February 2016Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Max. payload for Data Acquisition Module Hardware of 86,5 kg and withunchanged physical performance criteria (same form, fit and function) onthe payload as per previous EASA approval No. 364, Major ChangePrior to installation of this change/repair it must be determined thatthe interrelationship betw...	22/11/2024	Active	10057706
10057722	HELIKOPTER AIR TRANSPORT GESELLSCHAm.b.H.	REV. 2		EC135 T2+, EC135 T3 EC135 T1, EC135 T2, EC135 T3 EC135 P3, EC135 T1, EC135 T2, EC135 P2+, EC135 T2+ EC135 P1, EC135 P2, EC135 P3 EC135 P1, EC135 P2, EC135 P2+	EO 23-011: Tactical Radio Installation.Description: Subjectof this modification is a standardized andmodernized Tactical Radio Installation for the ChristophorusFlugrettungsverein AHD EC135 fleet. Therefore, the existing approvalsEASA R.C. 02649, EASA R.C. 02075 and EASA MCA 10047429 are combined a...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27 Amdt. 3: CS27.21, CS 27.25, CS 27.27, CS 27.29, CS 27.251, CS 27.301, CS 27.303, CS27.305, CS 27.561, CS 27.601, CS2...	AFM-Supplement, Tactical Radio Installation, AFMS 23-011 R1, dated05.10.2020;Engineering Order EO 23-011 R2, dated 09.10.2020;Installation Manual EO 23-011, R2, dated 09.10.2020;Instructions for Continued Airworthiness ICA 23-011 R1, dated09.10.2020;System Maintenance Manual SMM 23-011 R2, dated 08....	The approval holder shall fulfill the obligations of Part 21, Point21A.109.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the ai...	19/10/2020	Active	10057722

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057727	HAECO CABIN SOLUTIONS, LLC	REV. 1	FAA STC ST04230AT	A330-200 SERIES	Interior Reconfiguration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. HAECO Americas Cabin Solutions Master Data List (MDL) 14T165L001,Revision A, dated 7 April 2016.2. HAECO Americas Cabin Solutions Instructions for ContinuedAirworthiness (ICA) 14T165R009, Rev. IR, dated 16 October 2015.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Lufthansa Technik STC No. ST02324NY, Insta...	08/04/2016	Active	10057727
10057729	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINE S.A.R.L.			DA20-A1 / DA20-C1	AVIONICS MODIFICATION (installation of G3X).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	To be installed according with SEAM 4146 EI Rev4 and SEAM 4146 IP rev. 4.To be operated according with Flight manual supplement SEAM 4146 AFMSG3x Rev3.To be maintained according with SEAM 4146 ICA rev.0.	Limited to VFR-day. Further limitations are in the AFMS.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the...	08/04/2016	Active	10057729
10057735	N.S.E.			SA227-TT	Modification of radio electrical install iaw. Dossier 48/2008	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	NSE Doc 48/2008 MDL, Rev. 2NSE Doc 48/2008 AFMS GNS 530W TAWS, Rev. 3NSE Doc 48/2008 AFMS GNS 430W, Rev. 3NSE Doc 48/2008 AFMS SN 4500, Rev. 3or later revisions of the above listed documents approved by EASA.	iaw AFMSPrior to installation of this design change it mustbe determined thatthe interrelationship between this designchange and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	11/04/2016	Active	10057735
10057746	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			737-800	Cabin Retrofit by seat and partition panel installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Turkish Technic Master Document List No. CE-2500015-MD01-00revision 00dated 19 February 2016.	Restricted to MSNs 29765 to 29773, 29776, 29780, 29790.	11/04/2016	Active	10057746
10057755	AVIATECH & CONSULTING, SOCIEDADLIMITADA	REV. 2		R172K CESSNA R172K	Modification for skydiving operationThe modification for manual and static line jumping includes a winddeflector, a parachutist's platform fixed to the wheel nut and the rightlanding gear leg, the removal of the co-pilot control wheel, theintroduction of an instrument panel protection, a static line...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): SC-O23- div-01 Parachuting ActivityThe requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	SAFM P01-15 TAE AFMS For Parachuting Activities in Cessna R172K. Rev. For later revisions of the above listed document(s) approved/acceptedunder the EASA system.and-MDL P01-15 TAE "Master data list". Rev 5- PC P01/15 TAE "Certification programme". Rev 5- BC-MC P01-15 TAE "Certification basis/ Means-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/02/2022	Active	10057755
10057764	FLYING COLOURS CORP.	REV. 4	TCCA C-LSA16-004/D	BD-700-1A10	Revision 4 - Installation, Aircraft Interior (Special MissionProvisions) Addition of aircraft S/N 60166.Revision 3 - Installation, Aircraft Interior (Special MissionProvisions) Addition of aircraft S/N 60111 and 60118.Revision 2 - Installation, Aircraft Interior (Special MissionProvisions) AdditionR...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	For aircraft s/n: 9714, 9743, 9787, 60030 and 60043:B/E Aerospace Limited Modification Data Summary K172000 Rev. S, dated 16January 2023;B/E Aerospace Limited Aircraft Flight Manual Supplement K172090 Rev. A,dated 25 March 2020;B/E Aerospace Limited Mandatory Aircraft Maintenance Manual SupplementK1...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limited to aircraft S/N: 9714, 9743, 9787,60030, 60043,...	30/07/2025	Active	10057764

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057766	RUAG AG	REV. 1		P.180 AVANTI II AVANTI	PIAGGIO P180 GARMIN GTS 825/855 TAS/TCAS I Installation.Installation of Garmin GTS 825 TAS system or GTS 855 TCAS I system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 23 Amdt 3:CS23.1, 29, 301, 303, 305, 307, 337, 341, 365, 561, 571, 573, 575, 601,603, 605, 607, 609, 611, 613, 625, 867...	-Airplane Flight Manual FMS-610099 Rev. A, dated 08.04.2016.-Master Data List MDL-8003041 Rev. A, dated 08.04.2016.-Instructions for Continuous Airworthiness ICA-8003025 Rev. A, dated04.04.2016.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prerequisite: single or dual Garmin GTN 6501750 system mustbeinstalled.Limited to Model Avanti only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no advers...	02/02/2021	Active	10057766
10057770	ALPINE AEROTECH LP		TCCA STC SH14-46	AS 350 B, AS 350 B1 AS 350 BA, AS 350 D AS 350 B2, AS 350 B3	Floor Protection Kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See EASA approved Appendix 1or later revisions of the abovelisted documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/04/2016	Active	10057770
10057773	MT-PROPELLER ENTWICKLUNG GmbH			DV 20 DA20-A1	New firewall forward installation of Rotax 912iSc() () andMTV-21-A/170-05 or MTV-21-A/175-05 propeller	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-VLAplusSpecial Condition(s): SC-OVLA-div-03-i02-Night-VFREquivalent Safety Finding(s): CS-VLA.991 Electrical fuel Pumps iaw CRIVLA E-01This certificate/ approval invol...	According to MT-Propeller Master Document List No. E-2693Tobe operated in accordance with MT-Propeller AFM-S Document No.E-2688, Rev 0or later revisions of the above listed documents approved by EASA.To be installed iaw. Installation Instructions Doc. No. E-2686, Rev 0,or later RevisionsTo be maint...	VFR day or NightLimitations iaw AFMS Doc No E-2688 limitation sectionPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworth...	13/04/2016	Active	10057773
10057774	SEMIA SAS			AS350 B, BA, BB, B1, B2, B3	Installation du système d'Analyse Vibratoire Hélicoptère HELIVIB	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplément au Manuel de Maintenance AVH-1000-403, Version A, dated15/03/2016Dossier d'installation AVH-1000-405, Version A, dated 15/03/2016	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/04/2016	Active	10057774
10057780	AEROTEC & CONCEPT			AS 350 B3	Aerotec Concept Modification No. 15119: Installation of Garmin G500Hdual-screen electronic flight instrument system, coupled with autopilotSAGEM PA 85 in heading mode.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS27 Amdt. 3 paragraphs 27.25, 27.251, 27.301, 27.303, 27.305, 27.307,27.337, 27.561, 27.603, 27.607, 27.610, 27.625, 27.771, 27.773, 27.1301,27.1303, 27.1309, 27.1321, 27...	-Rotorcraft Flight Manual Supplement, doc. no. AE15119RFMS Rev. 4-A,dated 08/03/2016or later revisions of the above listed documents approved by EASA.-Master Data List, doc. no. AE15119MDL, Rev. 2-A, dated 12/04/2016-Programme de Certification, doc. no. AE15119PCDP Rev. 8-A, dated12/04/2016-Instruct...	- Equipment for VFR use only-Use of GPS for approaches is not EASA certified- Garmin GPS/SBAS navigation unit GTN650 shall be present-Installation and use of Helicopter Synthetic Vision Technology (HSVT)is not EASA certified.- Standby indicators (Mid Continent MD 302 with battery) providing ADI,AI...	13/04/2016	Active	10057780
10057781	S-TEC CORPORATION		FAA STC SA5217SW-D	210J, T210J 210G, T210G, 210H, T210H	Installation of S-TEC System 60 Two Axis Automatic Flight GuidanceSystem, Model ST-226, with Optional Automatic Electric Trim System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	1. FAA Approved Supplemental Flight Manual, P/N 89327, dated 7 October1983 is required for Cessna Models 210G, T210G, 210H, T210H, 210J andT210J and/or later FAA Approved revisions of the above supplement.2. FAA Approved Supplemental Flight Manual P/N 89327-1, dated 5 August1985 is required for Cess...	1. Also eligible on Cessna Models T210G, T210H and T210J when modifiedin accordance with STC SA2689SW (RAM Modification). 2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or r...	14/04/2016	Active	10057781

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057782	CONSTANT AVIATION, LLC		FAA STC SA03956AT	EMB-505	Installation of Aircell ATG-4000 High Speed Internet System(AHSI) andAircell Axxess II Iridium Satcom or Aircell Aviator 200 SBB Satcom,Aircell ATG - 5000 High Speed Internet System (AHSI) all with WirelessLocal Area Network (WLAN).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. FAA Approved Airplane Flight Manual Supplement, DocumentNumberDB1008006, Revision A, dated April 5, 2013 or later FAA approvedrevisions.2. Constant Aviation LLC, Master Drawing List DB 1008002, Revision H,dated February 6, 2013, or later FAA approved revision.3. Instructions for Continued Airwor...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This system is intended to provide interne...	14/04/2016	Active	10057782
10057794	VIH AEROSPACE Inc.		TCCA STC SH14-43 ISSUE 2	412 (S/N 33001 THRU 33107) 212	Replacement of OEM Master Caution Panel in accordance with Document MDLV212-1311-MDL	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan Report Number V212-1311-CP Revision A,dated June17, 2014.- Compliance Record DAR333 24-CR-01 Rev.1, dated January 8, 2016.- Compliance Record DAR 333 24-CR-02 Rev.1 dated February 8, 2016.- Instruction for Continued Airworthiness Report Number V212-1311-ICARevision B, dated Nov...	The approval is applicable on Bell 212 model and on Bell 412 modellimited to S/N 33001 thru 33107.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadv...	04/05/2016	Active	10057794
10057812	RUAG AG	REV. 2		P.180 AVANTI II AVANTI	Piaggio P180 Avionics UpgradeRemoved:-2x Collins VHF 22C COM transceiver and control head CTL-22C.-2x Collins VIR 32 NAV receiver and control head CTL-32.-1x Universal UNS-1K FMS,processor unit, display/ control unit,annunciators and GPS antenna.-1x Collins RTA852 weather radar incl. control panel a...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 Amdt 3, inparticular 23.1, 23.29, 23.301, 23.303, 23.305, 23.307, 23.337, 23.341,23.365, 23.561, 23.571, 23.573, 23....	-Flight Manual Supplement: Doc. No. FMS-610089 Rev. B-Instructions for Continuous Airworthiness: Doc. No. ICA-8003002 Rev. A-Master Data List: Doc. No. MDL-8003039, Rev. B-Engineering Order: Doc. No. EO-8002993, Rev. F-Declaration of compliance: Doc. No. DOC-8003138, Rev. Bor later revisions of theu...	SBAS based approaches with vertical guidance cannot be coupled to theAP/FD approach mode. Therefore they have to be flown manually with rawdata.The following required EHS Parameters are not transmitted:- Roll Angle- Magnetic Heading- Barometric Pressure SettingThe following EHS Parameters are transm...	02/02/2021	Active	10057812
10057814	EMBRAER ENGINEERING & TECHNOLOGYCENTER USA, INC.	REV. 1	FAA STC SA03003CE	EMB-505	Installation of an Aviator 200 SATCOM System.This STC was originally issued as a validation of Brazilian CST (STC)No. 2014S09-02 (3 September 2014), and transferred to a United Statesbased Design Approval Holder on 17 July 2019.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Embraer Master Document List NoESCCCD045, Rev M, dated 21 June 2017.Operation in accordance with FAA Approved Flight Manual Supplement(AFMS) document number ST00721CE-A, Revision IR, dated 6 March 2015.Instructions for Continued Airworthiness (ICA), Document NumberESC...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/11/2019	Active	10057814
10057819	SOCIETE AIR FRANCE S.A.			A320-232	NILE AIR Cabin rearrangement.The modification consists in cabin rearrangement from 180 passengers (Economic) to 164 (8 Business + 156 Economic).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	- Master Data List : Change Approval Sheet ref : CAS-A320-15-015 Rev 0- Instruction for Continued Airworthiness, ref : ICA-A320-15-015-001 Rev0or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, this modification must beinstalled in conjunction with :STG Aerospace (SafTGlo) Installation instructions ref. SG-A320-SSL320for photoluminescent emergency floor path marking system rearrangement(Approved under existing EASA STC no. 10042956 rev 1).Priort...	18/04/2016	Active	10057819

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057828	TOST GmbH FLUGZEUGGERA ETEBAUMUENCH EN	REV. 1		NIMBUS-4T NIMBUS-4M NIMBUS-4 NIMBUS-3T NIMBUS-3/24,5 NIMBUS-3 NIMBUS-2M NIMBUS-2C NIMBUS-2B NIMBUS-2 DISCUS CS	SM 03-2020 Installation of TOST hydraulic brake system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation of TOST hydraulic brake system in accordance with TOST GmbHdocument SM 03-2020, initial issue, dated December 16, 2020;Instructions for Continued Airworthiness, TOST GmbH document SM03-2020, initial issue, dated December 16, 2020;or later revisions of the above listed document (s) ap...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/12/2020	Active	10057828
10057845	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		P210N, P210R	Installation of TAS Antennas.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23, Amendment 4301, 303, 305, 307, 365, 561, 571, 575, 603, 605, 607, 609, 611, 613,625, 843, 867, 1301, 1306, 1308, 1309, 1327, 1351, 1431, 1529The requirements for en...	Project Description ASR-2016-001-PRD-04-00, Amdt. 00Instructions for Installation ASR-2016-001-IFI-10-00, Amdt. 00Instructions for Continued Airworthiness ASR-2016-001-ICA-11-01 (Rev.01) dated 27th March 2017or later revisions of the abovelisted documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10057845
10057873	BOGGI S.R.L.			AS 365 N3	Stretcher Installation on Airbus AS365N3 - (Change 365P005-00)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement 365P00500-RFMS-01, Issue 1or laterrevisions of the above listed documents approved by EASA.Master Document List 365P00500-Mdl-00, Issue 0,Installation Service Bulletin 365P00500-SBT-00, Issue 0Master Drawing List 365P00500-Mdw-00, Issue 0Compliance Check List 365P00500-CCL-...	None	21/04/2016	Active	10057873
10057883	CERTIFIED TECHNOLOGY, INC		FAA STC SR00532SE	SEE FAA AML	Installation of Certified Technology, Inc. quick release door pins.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	Certified Technology Drawing list CT9801 , Revision New Release, datedJune 3, 1998 .	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This STC is valid for aircraft types and m...	22/04/2016	Active	10057883
10057899	AEROTEC & CONCEPT			EC 120 B	MOD 14285 – Installation of Aspen 1500H (PFD and MFD)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27, Amdt. 3: 27.25,27.251, 27.301, 27.303, 27.305, 27.307,27.337, 27.561, 27.603, 27.607,27.610, 27.771, 27.773, 27.13...	RFM Supplement<(>,<) >Rotorcraft Type Airbus Helicopters EC120 B<(>,<) >Installation ASPEN EVOLUTION 1500H (PFD et MFD)Doc n° AE14285RFMS, Rev 0-E, dated 29 March 2016or later revisions of the above listed documents approved by EASA.- Certification Programme Aspen Evolution 1500H (PFD and MFD)installa...	- Use limited to Day-VFR- No connection with autopilotPriorto installation of this design change it must be determinedthatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the pr...	25/04/2016	Active	10057899

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057921	LUFTHANSA TECHNIK AG			CL-600-2D24 (RJ SERIES 900) CL-600-2C10 (RJ 700/701/702)	Activation of ATN/Mode 2 Data Link for Protected Mode-CPDLC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 Data Link Services for the SingleEuropean Sky.The requirements for environmental protection and the associatedcertified noise and/ or emissi...	Lufthansa Technic Airplane Flight Manual Supplement No. A-00-15/01-AFMRevision 01Lufthansa Technic Instructions for Continued Airworthiness No.A-00-15/01-ICA Revision 1or later revisions of the above listed documents approved by EASA.Lufthansa Technic Supplemental Type Definition Document No.STDD23-...	None	26/04/2016	Active	10057921
10057925	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04024AT-D	G280	Synthetic Vision System (SVS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	- AFM G280-GER-0015, Rev A, Dated 10 of April 2015.- ICA G280-GER-0285, Rev A, Dated 16 of November 2015.- Index List GA413358000, Rev A, Dated 10th August 2015or later revisionsof the above listed documents approved by EASA.	Aircraft Avionics 3.6 or later EASA approved is required tobe installedconcurrently or as a prerequisite for this STC.	26/04/2016	Active	10057925
10057927	AERODATA AG			B300	TCAS Software Upgrade 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amdt 4 applies for the following paragraphs:-23.1-23.3 (d)-23.1301-23.1309(a), (b), and (e)-23.1501(a) and (b)-23.1581(a), (b) and (f)-23.1585(a) and (j)The requireme...	Installation, Operation and Maintenance according to the “MasterDocument List” number MDL-A/C-884 Rev. 2 dated 26th April 2016.or later revisions of the above listed documents approved by EASA.	Aerodata STC EASA.A.S.C. 01017 is a prerequisite.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	26/04/2016	Active	10057927
10057930	STANDARD AERO		FAA STC ST02837CH-D	MF900, F900EX	Installation of Honeywell DU-875 Display.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:SC F9107-003, HIRF Protection.The requirements forenvironmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged...	Airworthiness Limitations Supplement ref. 1019267 revision A, dated 17March 2011.Airplane Flight Manual Supplement ref. 1020135 revision B, dated 16November 2015or later revisionsof the above listed documents approved by EASA inaccordancewith EASA ED Decision 2004/04/CF (or subsequent revisions of...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2016	Active	10057930
10057937	AIR PLAINS SERVICES, CORPORATION		FAA SA00393WI	U206E, U206F, U206G U206B, U206C, U206D TU206G, U206, U206A TU206D, TU206E, TU206F TU206A, TU206B, TU206C TP206D, TP206E TP206A, TP206B, TP206C P206, P206A, P206B P206C, P206D, P206E 206	Installation of McCauley D3A34C401/90DFA -2, -4, -6, -8, and -10propeller.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	C S Industries Installation Instructions No. 206-1, Rev. -,dated March12, 1996 in Annex or later "FAA approved" revisions.	The installation of McCauley D3A34C401/90DFA -2, -4, -6, -8, and -10propeller is limited to:- not over 88 inches and not under 84 inches diameter for float planes- not over 84 inches and not under 78 inches diameter for land planes.Placardis required to indicate the Operating Restrictions forContin...	29/04/2016	Active	10057937
10057951	LUFTHANSA TECHNIK AG			SEE APPROVED MODEL LIST (AML)	Installation of photoluminescent Exit Signs at Bulkhead or Class DividerThis approval is related to the installation ofphotoluminescent exitsigns, manufacturer by Lufthansa Technik for several aircraft types andmodels.The photoluminescentexit sign is self-illuminating sign to be installedon the as...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI D-3999-001: Photo Luminescent ExitIdentifiers.- The following paragraph(s)at a later amendment: CS-25 Amdt.17 for theassociated impact...	- Supplemental Type Definition Document STDD33-12/19M issue1 rev 1- ICA, ref A-33-14/000-ICA, Issue 1 rev 2- Compliance Record List CRL33-12/19M iss 1 rev 1or later revisions of the above listed documents approved by EASA.	The pre-conditions presented in 1.2.1 of Engineering Bulletin refPLM-EB33-0374 rev 2 (or later approved) need to be fulfilled.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or...	29/04/2016	Active	10057951

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10057952	NORTHWEST AEROSPACE TECHNOLOGIESINC.			767-300	Installation of Zodiac NuLook Interior on Icelandair aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	- Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0543-D90, Revision -, dated 22 April 2016.- Instructions for Continued Airworthiness, HeathTecnam document No.HTM1033<(>,<)> Revision -, dated 8 March 2016or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/04/2016	Active	10057952
10057954	APTOZ EHF.	REV. 1		767-300	Equipment/Furnishings - Passenger Compartment - Installation of NewAviointeriors Passenger Seats with Zii RAVE IFE and AES EmPower ISPS.Description of Type Design Change: installation of new seating layoutwith 262 total passengers using AVIO seats with Zii Rave IFE system andAES EmPower ISPS systemR...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Icelandair CRA-767-2520-97 Revision A.- Icelandair's Continued Airworthiness Instructions ref. CAI-767-2520-97 Initial Release- Icelandair AFM Supplement ref. AFM-767-2520-97or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.Icelandair's Engineering Orders re...	Concurrent STCs:- EASA STC IM.A.S.01169, STG Aerospace SafTGlo photo-luminescentemergency escape path.and- EASA STC 10057952, Northwest Aerospace Technologies (NAT) InstallationofZodiac NuLook Interior on Icelandair aircraft.Prior to installation of this change/repair it must be determined thatthep...	27/05/2025	Active	10057954
10057958	SABENA TECHNICS BOD			A310-308	VIP CABIN MODIFICATION S-25-4035 in accordance with Master Data ListMDL-S-25-4035 Iss. A	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Approval Sheet MAS-S-25-4035 Issue 2 Dated 28.04.2016Master Data List MDL-S-25-4035 Issue Aor later revisions of the above listed documents approved by EASA.	Applicable for MSN 667 with STC 10038294 installed	02/05/2016	Active	10057958
10057960	BERINGER AERO	REV. 5		PA-28-181 (ARCHER III) PA-28-181 (ARCHER II) PA-28-180 (CHEROKEE) PA-28-180 (ARCHER) PA-28-161 (WARRIOR III) PA-28-161 (WARRIOR II) PA-28-160 (CHEROKEE) PA-28-151 (CHEROKEE WARRIOR) PA-28-150 (CHEROKEE) PA-28-140 (CHEROKEE CRUISER)	Replacement of Wheel and Brake SystemRevision 4: Addition of PA-28-140 modelRevision 5: Update with new servicing instructions within ICA documentand addition of SensAIR device asan option	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification file: DM-STC-014 rev 07 dated 11 Mar. 2022;Installation and Instructions for Continued Airworthiness: ICA-STC-014rev 07 dated 19 Oct. 2021;or later revisions of the above listed documents approved by EASA.	The approval holder shall fulfill the obligations of Part 21, Paragraph21A.109.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	18/03/2022	Active	10057960
10057976	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 2		206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	Installation of the HELICOM V2/V2+ ANA Flight Data Monitoring SystemRevision 1: Add Bell 407 model.Revision 2: STC holder name change from I.S.E.I International Servicesto SAFRAN ELECTRONICS & DEFENSE BUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 "Lithium Battery Installation" dated18/04/2019.The requirements for environmental protection and the associatedcertified noise and/ or emi...	Initial Issue :Rotorcraft Flight Manual Supplement. Report No. N11-Bell206-HV2_HV2+ ANAE-A-02 Revision 05.Description of the change. Report No. N1-Bell206-HV2_HV2+ ANA E-A-03,dated July 17, 2015.Certification Program. Report No. N2-Bell206-HV2_HV2+ ANA E-A-05, datedApril 15, 2016.Installation Manual...	Crew interaction with the HELICOM V2/V2+ ANA Flight Data MonitoringSystem is not allowed when rotor turning.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no...	27/02/2020	Active	10057976
10057994	Q.C.M. DESIGN GmbH			525	ADS-B Out Upgrade for a Cessna 525,,Removed: Garmin GTX-330D TransponderInstalled: Garmin GTX-330D w/ES TansponderCompliance to CS-ACNS.D.ADSB and AMC 20-24 was shown.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS.D.ADSBThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain appl...	- Airplane Flight Manual Supplement: Doc. No.C525-QCM34-001-M1-AFM, Rev.0- Instructions for continued Airworthiness: Doc. No.C525-QCM34-001-M1-ICA, Rev. 0or later revisions of theabove listed documents approved by EASA- Master Document List: Doc. No. Section 2.1 of C525-QCM34-001, Rev. 0-Declarati...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/05/2016	Active	10057994

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058033	SABENA TECHNICS BGC			A330-223/-224F/-243/-243 F A330-201/-202/-203	Introduction of B/C with IFE and Wireless IFE in whole cabin on A330Retrofit of Airbus A330-200 (design definition MSN 261 & MSN 265) withB/C seats with IFE, and IFE Wireless for all the cabin.Additional information, refer to associated Certification Plan.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Applicable regulations at CS 25 Amendment 4 (referto associatedCertification Plan 4859-01-A-CP-R01, section 5& 6, for details)The requirements for environmental protecti...	Master Data List, ref: 4859-01-A-MDL-R00Instruction for Continued Airworthiness, ref: 4859-01-A-ICA-R01Aircraft Flight Manual Supplement, ref: 4859-01-A-AFMS-R01or later revisionsof the above listed documents approved by EASA.	This STC is limited to Airbus A330-200 MSN 261 and 265.According to design related to this STC, this modification must beinstalled in conjunction with :- STC EASA.IM.A.S. 00543, Installation of Saftglo Inc photoluminescentfloor proximity emergency escape path marking system- STC 10057244 Rev 1, Modif...	06/05/2016	Active	10058033
10058034	GVH AEROSPACE LIMITED		CAA UK RESPONSIBILITY	737-600/-700/-800	Installation of Cobham Aviator 300D INMARSAT SwiftBroadbandSATCOMSystem with IGA-5001 Antenna	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 at Initial Issue for the affected areaThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product...	-Flight Manual Supplement, Cobham Aviator 300D SATCOM SystemInstallation, Ref. GVH-5244-02-FMS-01, Issue 2.-Instructions for Continued Airworthiness, Cobham Aviator 300D SATCOMSystem Installation B737-800, Ref. GVH-5244-02-ICA-01, Issue 2.or later revisions of the above listed documents approved by-...	As per:-Flight Manual Supplement, Cobham Aviator 300D SATCOM SystemInstallation, Ref. GVH-5244-02-FMS-01, Issue 2 (Section 1 – CertificateLimitations).-Instructions for Continued Airworthiness, Cobham Aviator 300D SATCOMSystem InstallationB737-800, Ref. GVH-5244-02-ICA-01, Issue 2 (Section11 – Airw...	06/05/2016	Active	10058034
10058036	HELIFAB Inc.d/b/a ARROW AVIATION CO. LLC	REV. 1	FAA STC SR09522RC	407 206L-4 206L-3 206L-1 206B	Installation of frameless seat cushions in accordance with Helifab Inc.Master Drawing List, Document No. HF-MDL-7-1, Rev. IR, dated 3 September2015 or later FAA approved revision.Rotorcraft Flight ManualSupplement, Helifab Inc. Document No. HF-FM-7-1, Revision 0, approved 7January 2016 or later FAA...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Helifab Inc. Master Drawing List, Document No. HF-MDL-7-1, Rev. IR,dated 3 September 2015 or later FAA approved revision.2. Rotorcraft Flight Manual Supplement, Helifab Inc. Document No.HF-FM-7-1, Revision 0, approved 7 January 2016 or later FAA approvedrevision is required.	1. Instructions for Continued Airworthiness, Helifab Inc. Document No.HF-CA-7-1, Rev. IR, dated 3 September 2015 or later approved FAArevision is required.2. Compatibility of thisdesign change with previously approvedmodifications must bedetermined by the installer.3. If the holder agrees to permi...	18/05/2016	Active	10058036
10058041	AIRBORNE SCIENTIFIC Inc.		FAA STC SA4-662	182 SERIES 180 SERIES 172 SERIES	Installation of camera pod on Cessna series 172, 180 and 182.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	Clifton G. McBride Project 1-CGM Drawings No. 1, 2, 3 and 4 dated20.04.1958 and Drawing E.O. No. 1 & 2; or later FAA approved revisions.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesE...	11/05/2016	Active	10058041
10058044	2 EXCEL DESIGN LIMITED	REV. 3	CAA UK RESPONSIBILITY	727-200F	Introduction of an Oil Dispersant Fluid Storage and Delivery System(TERSUS), projects JN491-005.Rev 1: Addition of Rhodamine B and Kilfrost DF Plus fluids to TERSUSsystem, project2XL061.Rev 2: Kilfrost DF Plus fluid replaced with Monopropylene Glycol,project 2XL061.Rev 3: Removal of existing AFM li...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): HIRF protection (CRI F-01 Issue 2).- The following paragraph (s) at a later amendment: as per CRI-A01 Issue3.The requirements for environmental prot...	- Leading Edge Master Data List Project 2XL065 issue 1- Leading Edge Airplane Flight Manual Supplement JN491-005 LEF71(1),Revision 6- Leading Edge Instructions for Continued Airworthiness SupplementJN491-005 LEF73/ ADC54-25(1), Issue 9or later revisions of the above listed document(s) approved/accep...	- This modification is applicable to aircraft serial numbers 22938 and22929.- limitations as per Airplane Flight ManualSupplement JN491-005LEF71(1)-The AFM Supplement introduces an airspeed limitation of 250KIAS/ 0.75M,an altitude limitation of FL360 and a MTOW reduction from 203,100lbs to195,300lbs...	09/07/2020	Active	10058044
10058047	SAFRAN CABIN INC.		FAA STC ST02003LA	ERJ 190-100 IGW	C<(>&<)>D Zodiac, Inc. Interior Installations and Modifications	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. C<(>&<)>D Zodiac, Inc. Index List No. F251, Revision B, dated 29October 2012, or later FAA approved revisions.2. Instructions for Continued Airworthiness (ICA), C<(>&<)>D ZodiacReport No. CDRF251-78, Revision N/C, dated 5 September 2012.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/05/2016	Active	10058047

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058054	LEARJET Inc.		FAA STC ST00136MC	BD-700-1A10	Installation of an ADS-B Out Inhibit capability on a BombardierBD-700-1A10 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Master Document List BAS67015011, revision (G), dated April 12, 2016,FAA approved April 21, 2016.2. Instructions forContinued Airworthiness, BAS67055001-ICA-1, revision(B), dated April 13, 2016, FAA accepted April 21, 2016.3. FAA approved Airplane Flight Manual Supplement, AFMS BAS7045005,Revisi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/05/2016	Active	10058054
10058067	STG AEROSPACE GERMANY GmbH	REV. 2		757-200, 757-300	B757 – LiTeMood Cabin LED Light V1.1 InstallationRev. 1: Transfer from Aviation Traders Limited (t/a ATL) to AviationTraders Limited Europe SAS.Rev. 2: Transfer from ATL aerospaceEurope to STG Aerospace GmbH.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	ATL Master Document List No. MDL-12982-00001 Issue 7<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Applicable to all Being 757-200/-300 aircraft fitted with Diehl, Bruceor Page ceiling and recessed lights, and Grimes type Sidewallfluorescent lighting as defined in ATL Modification Summary SheetMOD-12982-00001Prior to installation of this change/ repair it must be determined thatthe interrelationsh...	28/09/2021	Active	10058067
10058068	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	JETSTREAM 4100	Replacement of Smoke Detectors.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cranfield Aerospace Ltd Type Design Definition Addendum No.CA/DD/ DR0323b Issue B	None	10/05/2016	Active	10058068
10058069	STC TWENTY ONE LIMITED	REV. 2	CAA UK RESPONSIBILITY	A340-642, A340-643	Installation of Gogo 2KU – System Activation.Rev. 2: Removal of restriction in Flight Manual Supplement.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 25Amendment 16 - 25.23 ALL; 25.29 (b); 25.251 (a)(b)(c)(d)(e); 25.301(a)(b)(c); 25.303 ALL;25.305 (a)(b)(c)(e); 25.307 (a)(d); 25.321 (a);25.331 (a)(b)(c); 25.333 (a)(...	- STC TWENTY ONE LIMITED Aircraft Flight Manual Supplement S21.FMS-0129Issue 2;- STC TWENTY ONE LIMITED Supplement Manual S21.TEC-0497 FORAIRWORTHINESS LIMITATIONS Issue 4;- STC TWENTY ONE LIMITED MASTER DOCUMENT LIST NO. S21.MDL-1238 Issue 8;,,or later revisions of the above listed document(s) appr...	STC TWENTY ONE LIMITED Design change S21.44-69-1009, approved by EASASTC 10055030, must be installed prior to, or concurrently with, thisdesign change.There are Airworthiness Limitations in the form of structuralinspections required for this design change which are documented withinS21.TEC-0497.Thet...	22/11/2018	Active	10058069
10058077	GROWING ENGINEERING PARTNERS GmbH	REV. 1		747-400	Virgin Atlantic Airways B747-400 Cabin ReconfigurationDecrease capacity of Upper Class seats (UCS J) and increase both thePremium Economy (W) and Economy (Y) cabin seating, Changeof seatconfiguration from 44J/62W/261Y to 14J/66W/375Y, Installation of new IFEPanasonic eXK in J-class and W-class seat...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFMS: S.OAEZ.001459-AFMS Rev 00MDL: S.OAEZ.001459-MDL Rev 00ICA: S.OAEZ.001459-ICA rev 00,,or later revisions of the above listed documents approved by EASA.	Prior to installation of this repair it must be determined that theinterrelationship between this repair and any other previously installeddesign change and/ or repair will introduce no adverse effect upon theairworthiness of the product.	21/04/2021	Active	10058077
10058089	SERAM - SOCIETE D'ENTRETIEN ETREPARATION AERONAUTIQUE MACONNAISE			A36	FM416R Revision 2 dated 09 May 2016 - INSTALLATION GPS GNS430/A/W FORBRNAV, PRNAV, RNP APCH operations	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 initial issue aslisted in the FACE FM416R Rev2.The requirements for environmental protection and the associatedcerti...	Supplément au Manuel de Vol Avion Révision 0 du 27 Avril 2016or later revisions of the above listed documents approved by EASA.	None	12/05/2016	Active	10058089

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058091	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC ST11168SC	680A (LATITUDE)	Installation of a Pratt & Whitney Flight Data Acquisition, Storage, andTransmission System (FAST)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. "Data List, Installation Data for Cessna Citation Latitude 680A"document no. GN4-T-100-5, revision A, dated 19 February 2016.2. "Instructions for Continued Airworthiness for Cessna CitationLatitude 680A", document no. GN4-T-260-6, revision A, dated 12 February2016.	Cessna Engineering Change Record 080504, titled "FAST BOX PROVISIONSINSTALLATION - 680A,"revision '-' or later approvedFAA revision, mustbe installed prior to installation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyp...	23/05/2016	Active	10058091
10058095	BELL TEXTRON, Inc.	REV. 1	FAA STC SR00782DE	429	Approval of a seating configuration to allow flight operations with theleft hand pilot seat removed.Rev. 1: Transfer from "Laz-Tec, LLC." to "Bell Textron, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Laz-Tec Drawing List, Report No. LT-14211 , No Revision,datedNovember 26, 2014, FAA approvedDecember 18, 2014.2. Flight Manual Supplement, Laz-Tec, LLC Document No. LT-14214, NoRevision, dated December 12, 2014, or later FAA approved revision.3. Instructions for Continued Airworthiness, Laz-Tec,...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/03/2025	Active	10058095
10058097	SABENA TECHNICS BGC	REV. 1		A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-243F A330-223, A330-223F, A330-243 A330-201, A330-202, A330-203	Assessment of Aircraft Compatibility with TPED's on A330 Aircraft.Revision 01 : Revision of the approval following the use by theapplicant of the EASA CM-ES-003 Issue 1 (Guidance to Certify an Aircraftas PED tolerant), and modification of the associatedlimitation/conditions information, accordingly....	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to associated Certification Plan0805-01-A-CP-03, section 4 & 5, for deta...	Aircraft Flight Manual Supplement, Aeroconseil document No.0805-01-A-AFMS-02, dated 01 March 2018;Instructions for Continued Airworthiness, Aeroconseil document No. 0805-01-A-ICA-R05, dated 26 April 2018;or later revisions of the above listed documents approved by EASA.Master Data List, Aeroconseil d...	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. Even if the airplane is not fitted with anactive in-flight connectivity system;if this system is inautomatic/manual shutdown condition, orm...	27/06/2018	Active	10058097
10058098	BELL TEXTRON, Inc.	REV. 1	FAA STC SR00791DE	429	Installation of the skid-gear mounted step to assist in external hoistoperations.Rev. 1: Transfer from "La-Paz, LLC." to "Bell Textron, Inc."	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Laz-Tec Drawing List, Report No. LT-15202, Revision B, dated July 10,2015, FAA approved September 01, 2015.2. FlightManual Supplement, Laz-Tec, LLC Document No. LT-15205, NoRevision, dated August 28, 2015, or later FAA approved revision.3. Instructions for Continued Airworthiness, Laz-Tec, LLC D...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/03/2025	Active	10058098
10058100	GARMIN INTERNATIONAL, Inc.	REV. 1	FAA SA01456WI-D	C90A, C90GT, C90GTI	Installation of the Garmin G1000 Integrated Avionics Systemand GFC-700Automatic Flight Control System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: seeAppendix dated 27 April 2020.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchan...	For Models C90A, C90GT and C90GTi with system software version 3557.00or later:-Installation in accordance with Garmin Master Drawing List (MDL) 005-00375-30, Revision 18, dated 10/17/2019Operation in accordance with Garmin Airplane Flight Manual Supplement(AFMS) 190-00682-N2, Revision 1, dated 10/17...	(1) Eligible aircraft Serials are S No LJ-1063 and after.(2) Additional Aircraft configuration requirements are definedin thedata shown on the Garmin Master Drawing List (MDL) 005-00375-30.(3) This STC has been shown compatible with Blackhawk Modifications IncSTC SA10341SC and SA10364SC (engine/pro...	27/04/2020	Active	10058100

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058102	DASSAULT AVIATION BUSINESSSERVICES SA			MYSTÈRE-FALCON 50	TCAS II change 7.1 - TTR4100 upgradeOut: Collins TCAS II change 7.0 Transmitter/Receiver TTR-920 or TTR4000In: Collins TCAS II change 7.1 Transmitter/Receiver TTR4100.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement No. TAG-M063-AFMS2 Rev. IR dated14.04.2016or later revisions of the above listed documents approved by EASA.Master Compliance Data List No. TAG-M063-MCDL Rev. IR dated 20.04.2016Instructions tor Continued Airworthiness Outline No. TAG-M063-ICAO Rev.IR dated 14.04.20...	Limited to Falcon 50 EX versions.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverseeffect upon the airworthiness of the product.	12/05/2016	Active	10058102
10058114	SIRIUM AEROTECH S.L.			ATR 72-212 A	LOPA 72 PAX ATR72-212A	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt 17: 25.305, 25.307, 25.601, 25.603, 25.607, 25.611, 25.625,25.791, 25.803, 25.811, 25.813, 25.815, 25.817, 25.853, 25.1301,25.1351, 25.1360, 25.1415, 25.1423, 2...	MASTER DATA LIST SA15-39S-MDL Rev. 2 dtd. 19/Apr/2016or later revisions of the above listed documents approved by EASA.	MSN effectivity as per MASTER DATA LIST SA15-39S-MDLPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the prod...	13/05/2016	Active	10058114
10058130	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA STC ST04022AT-D	GIV G300, G400	Removal of Windshield Wiper System and Application of Windshield SurfaceSeal CoatingThis modification consists in the installation of a windshield surfaceseal as the primary meansof rain repellent and the deactivation/removalof the existing windshield wiper blade system.Rev. 1: Addition of the FAAR...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): D-125 : Pilot compartment view –Hydrophobic coatings in lieu of windshield wipers.The requirements for environmental protection and the assoc...	- Index List, ref: CE41 4688007 Revision A, dated 02 March 2015- Aircraft Flight Manual Supplement, ref: CE41 468M008, dated 02 March2015- Instructions for Continued Airworthiness, ref: CE41 468A032 RevisionA, dated 19 February 2015or later revisions of the above listed documents approved by EASA in...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/01/2025	Active	10058130
10058132	AVIDYNE CORPORATION	REV. 3	FAA STC SA00343BO	SEE EASA APPROVED MODEL LIST	Installation of a single configuration or of a dual configurationAvidyne Corporation Integrated Flight Display, Model IFD5XX and/or ModelIFD4XX, loaded with Release 10.1 software and/or Atlas, loaded withRelease 10.3 software.Revision 3 adds an additional hardware part number	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The certification basis for the Make, Model aircraft is as follows:a. The type certification basis for parts not changed or not affected bythe change is shown on the appli...	Installation in accordance with Avidyne Corporation Master Document List (MDL), Document Number AVIFD-306, Revision 04, dated 27 May 2015;Operation in accordance with the Avidyne Corporation Aircraft FlightManual Supplement (AFMS) Document Number 600-00298-000, Revision 02, FAAapproved on 18 June 201...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/06/2023	Active	10058132
10058140	TRACES AIRCRAFT CERTIFICATIONENGINEERING SERVICES		FAA STC ST04080CH	737-800 SERIES	Installation of FWD LH Overhead Bin and Interior Furnishings.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	TRACES Master Data List, TS1122MDL, Revision B, dated April12, 2016.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/05/2016	Active	10058140

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058141	GAMA AVIATION (ENGINEERING) LIMITED	REV. 1	CAA UK RESPONSIBILITY	206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	Installation of Garmin G500H System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-27 Amendment 3, 27.1, 27.27, 27.29, 27.301, 27.303, 27.305, 27.307,27.309, 27.321, 27.337, 27.561, 27.601, 27.602, 27.603, 27.605, 27.607,27.609, 27.610, 27.611, 27.613...	Gama Aviation (Engineering) Ltd Rotorcraft Flight Manual Supplements:RFMS-1440 Issue 1, Bell 206BRFMS-1440-02 Issue 1, Bell 206ARFMS-1440-03 Issue 1, Bell 206L and 206L-1RFMS-1440-04 Issue 1, Bell 206L-3 and 206 L-4RFMS-1440-05 Issue 1, Bell 407or later revisions of the above listed documents approv...	Rotorcraft equipped with the G500H are limited to VFR operations ONLY.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwort...	17/10/2016	Active	10058141
10058144	SKYTRAC SYSTEMS Ltd.	REV. 1	TCCA SH15-12	AW139	SkyTrac ISAT Airborne Position/Data Communicator Installation.Revision 1 of this STC corrects clerical errors, updates the AssociatedTechnical Documents section and reflects the address change of the STCholder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avionics Design Services Ltd. Master Drawing List MDL14069,Rev. Y dated19.03.2020;Flight Manual Supplement FMS14069-1,Rev. G, dated 09.06.2020;Instructions for Continued Airworthiness ICA14069-1, Rev. N, dated08.06.2020;or later revisions of the above listed document(s) approved/ accepted onbehalfP...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/11/2020	Active	10058144
10058153	CANARD AEROSPACE CORPORATION		FAA STC ST04057CH	ATR 72-211/-212/-212A ATR 72-101/-102/-201/-202 ATR 42-200/-300/-320/-500	Installation of the CMA-6800 AMLCD EFIS Displays.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	1. Canard Aerospace Corporation (CAC) Document Control Drawing 40199Rev. 1, dated February 11, 2016, or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA), Canard AerospaceCorporation Document Number 34-3610-07<(>,<)> Revision C, dated February09, 2016, or later FAA accept...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Airplane Flight Manual Supplement, CanardD...	23/05/2016	Active	10058153
10058171	AMAC AEROSPACE SWITZERLAND AG			BD-700-1A11	Replacement of large monitors.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI D-01/10042177 Glass Screens of Displays / MonitorsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origi...	Master Data List MDL-DT02-4425 Rev. B dtd. 17.05.2016or later revisions of the above listed documents approved by EASA.	The installation of this STC is limited to MSN 9166.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the prod...	20/05/2016	Active	10058171
10058175	AEROTEC & CONCEPT			SEE APPROVED MODEL LIST	Installation of G500 and GTN650 for DR400 aeroplanes in accordance withAerotec Concept Master Data List AE16061MDL, at Rev. 1, dated12.05.2016.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Aerotec Concept Master Data List AE16061MDL, at Rev. 1, dated 12.05.2016or later revisions of the above listed documents approved by EASA.	VFR Day only.	20/05/2016	Active	10058175

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058198	LEARJET Inc.		FAA STC ST01800WI	LEARJET 45	Installation of an Executive Interior, Floor Plan FP45-3B in the Model45, Learjet 70 series.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Learjet Inc. Master Document List M100576ICT, revision (K), datedDecember 14, 2015, FAA approved December 18, 2015.2. MDL M100576ICT-001 configuration:Instructions for Continued Airworthiness, M100576ICT-ICA-001, revision(A), dated December 1, 2015, FAA accepted December 18, 2015.3. MDL M100576IC...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Installation of ModSums 045T023617 and 045...	30/05/2016	Active	10058198
10058209	AERO-DIENST GMBH & CO. KG	REV. 1		55	PRNAV Compliance in accordance with. JAA TGL No. 10	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement, AG1021-071, revision A, dated 26February 2016Instructions for Continued Airworthiness – ICA, AG1021-085, revision IR,dated14 December 2015or later revisions of the above listed documents approved by EASA.	MSN 55-059 only	25/05/2016	Active	10058209
10058213	BELL HELICOPTER TEXTRON, Inc.		FAA SR09603RC	412EP	Installation of a Cockpit Voice / Flight Data Recorder (CV/FDR) andQuick Access Recorder (QAR) for Bell Helicopter Textron 412EP ModelHelicopter in accordance with Master Drawing List AA-12049.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:FAR 29:At Amdt. 29-0: 29.301, 29.303, 29.305(a), 29.307(a),29.561(b) (3),29.601(a), 29.603(b), 29.605, 29.609(a), 29.611, 29.619, 29.625(a), 29.1301At Amdt. 29-30: 29.613 (d...	- Rotorcraft Flight Manual Supplement AA-12051 No Revision,datedDecember 03, 2013.- Instruction for Continued Airworthiness AA-12050 Revision A, datedAugust 27, 2013.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisi...	Prerequisite for the installation of this change CV/FDR andQAR is theInstallation of EASA STC No. 10057657 of Bell BasiX-Pro® Glass Cockpitand Pratt & Whitney Canada PT6T-9 Twin Power Section Turboshaft Enginesand associated systems.Priorto installation of this design change it must be determinedt...	24/05/2016	Active	10058213
10058216	ELDEC LLC		FAA STC ST01689WI	DHC-8-400 SERIES DHC-8-300 SERIES DHC-8-200 SERIES DHC-8-100 SERIES	Installation of Crane Aerospace & Electronics SmartStem Wireless TirePressure Sensing System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Duncan Aviation Inc., Document list No, 111207013, RevisionA, datedJuly 24, 2012.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/05/2016	Active	10058216
10058239	SOCIETE AIR FRANCE S.A.			A330-243	Air Europa – Cabin rearrangementCabin seating rearrangements including a configuration with “STELIA”Business seats and IFE adaptation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List: Change Approval Sheet ref: CAS-A330-15-002 Rev 0- Instruction for Continued Airworthiness, ref: ICA-A330-15-002 Rev 0or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with EASA STC no. 10014507 rev 1 (Installationof Non-electrical floor path marking system guideline).Prior to installation of this design changeit must be determined thatthe interrelationship between this...	25/05/2016	Active	10058239
10058279	MOTORFLUG BADEN-BADEN GmbH			58P	25745F156221 / Relocation of COM antenna on fuselage top. Installationof one Avidyne TAS antenna on fuselage top, Installation of one AvidyneTAS antenna on fuselage bottom.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- 25745F156221-0109 / Master Document List, rev. 0, dated 21.03.2016- 25745F156221-0701 / Instruction for Continued Airworthiness, rev. 0,dated 21.01.2016or later revisions of theabove listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/05/2016	Active	10058279

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058292	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	757-200	Introduction Crew Oxygen Charging Panel	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Limited MASTER DOCUMENT LIST No. S21. MDL-1269 Issue 1.	None	31/05/2016	Active	10058292
10058295	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A340-311, A340-313	Cabin Reconfig. Turkish Airlines A340-300Change of seat configuration 34BC/236EC to 354ECRev 1.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFMS: S.OAEZ.001482-AFM Revision 03ICA: S.OAEZ.001482-ICA Revision 01MDL: S.OAEZ. 001482-MDL Revision 00CCS including DoC: S.OAEZ.001482-CCS Revision 00or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/04/2021	Active	10058295
10058307	KLM ENGINEERING & MAINTENANCE			777-300ER	Cabin reconfiguration of KLM 777-306ER aircraft[Replacementof Business Class seats and Economy Class seats, removalandinstallation of monuments, replacement of In-Flight EntertainmentSystem, replacement of décor laminates, curtains and carpet and relatedchanges to cabin furniture to accommodate ne...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):CRI D-254 (Post TC special condition – a Overhead Crew RestCompartments) closedon 16 April 2003, which adopted special condition FAA 25-230-SC. CRID-2...	Master Data List, KLM document No. MDL-013135, Revision 02,dated 3 June2016Instructions for Continued Airworthiness, KLM document No.ICA-777-013135, Revision ORG, dated 27 May 2016or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/06/2016	Active	10058307
10058319	JAMCO AMERICA, INC.		FAA STC ST02117SE	777-300 SERIES	Installation of 3 to 2 class interior reconfiguration on Boeing Model777-300 series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Jamco America, Inc. Master Drawing list (MDL) MDL2135-1, Revision A,dated March 01, 2016.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Supplemental Instructions for Continued Ai...	09/06/2016	Active	10058319
10058320	TURBINE KINETICS, INC.		FAA STC SR04213AT	429	Installation of a barrier net on the Bell 429 rotorcraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing 429-002-901DEC, Revision F, dated 8 June 2015.2.HEICO Instructions for Continued Airworthiness (ICA), Document NumberHAC14-002, Revision 0, dated 4 March 2015.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/06/2016	Active	10058320
10058321	B/E AEROSPACE, Inc. - FSI		FAA STC ST02446SE	737-800 SERIES	Installation of interior reconfiguration on Boeing Model 737-800 seriesairplanes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	FSI Master Drawing List (MDL) B4FS410-D01, Revision F, dated August 27,2015.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/06/2016	Active	10058321

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058328	DUNCAN AVIATION, INC.		FAA ST01769CH-D	MF50, MF900, F900EX F2000, F2000EX	Validation of FAA ST01769CH-DInstallation of Max-Viz Enhanced Vision System (EVS)Two configurations:- F2000 and F2000EXwith Skyquest Displays; the Skyquest Displays areincluded in the scope of this STC.- F2000, F2000EX, MF50, MF900 and F900EX with CMS Electronics CMA-1100Electronic Flight Bags (EFB...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement ref. 050729009 revision A, dated 24 April 2009 for theconfiguration of F2000 and F2000EX with Skyquest Displays.AFM Supplement ref. 060803020 revision B, dated 24 April 2009 for theconfiguration of F2000, F2000EX, MF50, MF900 and F900EX with CMSElectronics CMA-1100 EFBor later revisio...	May only be used with CMS Electronics CMA-1100 Electronic Flight Bag,when provisions for the CMA-1100 have been certified by EASA andassociated operational approval has been gained.Prior to installation of this design change it must be determined thatthe interrelationship between this design changep...	16/06/2016	Active	10058328
10058333	BROMMA AIR MAINTENANCE AB			650 CITATION VII 650 CITATION VI 650 CITATION III	Cessna 650 Special Mission Aft Pressure Bulkhead Feedthru	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Bromma Air Maintenance AB, Doc No MDL-15-14 as defined in MasterDocument List, Revision B, Dated 1st June 2016	This STC cover data for modifying the Feed trough Plate, Cessna (basic)P/N 6211084-8 (left or right) to allow electrical or electronics wiringto pass through the plate via Amphenol® cylindrical connectors i.a.w.standard MIL-DTL-5015 with P/N MS3454-x. Other means of plugging the newholes is outsideT...	07/06/2016	Active	10058333
10058335	MCFARLANE AVIATION, Inc.		FAA STC SA02113AK	185E, A185E, A185F 185, 185A, 185B, 185C, 185D,	Fabrication and installation of Stabilizer Jack-Screw Actuator.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	North Pacific Welding Drawing Number C-0712500, dated March31, 2000 andCessna Skywagon 180 and 185 Series Service Manual; or McFarlaneAviation, Inc., Drawing 1111-1, revision original, dated June 1, 2010 orlater FAA approved revisions.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This approval is valid only if North Pacif...	09/06/2016	Active	10058335
10058336	MCFARLANE AVIATION, Inc.		FAA STC SA02112AK	180K 180E, 180F, 180G, 180H, 180J 180, 180A, 180B, 180C, 180D	Fabrication and installation of Stabilizer Jack-Screw Actuator.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	North Pacific Welding Drawing Number C-0712500, dated March31, 2000 andCessna Skywagon 180 and 185 Series Service Manual; or McFarlaneAviation, Inc., Drawing 1111-1, revision original, dated June 1, 2010 orlater FAA approved revisions.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This approval is valid only if North Pacif...	09/06/2016	Active	10058336
10058341	AEROTEC & CONCEPT			787-8, 787-9	MEDICAL STRETCHER INSTALLATION ON B787	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List AE16078MDL Rev.0 dated of 06/06/2016- AFM Supplement AE16078AFMS Rev.0 dated of 25/05/2016or later revisions of the above listed documents approved by EASA.	- Per AFM Supplement AE16078AFMS Rev.0 dated of 25/05/2016-Aerotec Change AE16077MAS is a pre-requisite for this STCPrior to installation of this design change it must be determined thatthe interrelationship between this design change andany otherpreviously installed design change and/ or repair w...	08/06/2016	Active	10058341
10058345	MCFARLANE AVIATION, Inc.		FAA STC SA02161AK	182, 182A, 182B, 182C, 182D	Fabrication and installation of Stabilizer Jack-Screw Actuator.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	North Pacific Welding Drawing Number C-0712500, dated March31,2000 andCessna 100 Series 1962 and prior Service Manual,dated February 1, 1962;or McFarlane Aviation, Inc., Drawing1111-1, revision original, datedJune 1, 2010 or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/06/2016	Active	10058345

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058356	GULFSTREAM AEROSPACE CORPORATION		ST04301AT-D	GV	Installation of Honeywell Primus Elite Advanced Features (PEAF) Upgradeto DU-885 Displays.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Gulfstream Aerospace Corporation Index List CE512088003, Rev. A, datedJune 1,2016, or later FAA approved revision.For -501 Configuration:FAA accepted Instructions for Continued Airworthiness CE51208A002,Revision -, dated January 7, 2015.For -503 Configuration:FAA accepted Instructions for ContinuedR...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Gulfstream Aircraft Service Change (ASC) 1...	08/06/2016	Active	10058356
10058357	HELI-ONE (NORWAY) AS	REV. 1		AS 332 L1, AS 332 L AS 332 L1 AS 332 L	EFI-890H EFIS system installationRev. 1: Replacement of Standby Indicator (ref. AHSE 74760)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 29 Amdt. 3, dated11.12.2012 for the followings: 29.1, 29.29, 29.251,29.301, 29.303,29.305, 29.307, 29.309...	Rev 0:-Product Change Declaration H1N332-00103-2201, dated 27.05.2016-Certification Programme H1N332-00103-2301 Rev. A,dated 26.05.2016-Declaration of Compliance H1N332-00103-1001, dated 27.05.2016-Heli One Aircraft Flight Manual Supplement H1N332-00103-1801, dated16.03.2016Rev 1:-Product Change De...	- A copy of EFI-890H Pilot's Handbook must be immediately available tothe flight crew.- The EFIS EFI-890H system is notapproved for Back Course Approaches.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously i...	29/06/2023	Active	10058357
10058371	AVMAX AVIATION SERVICES Inc.	REV. 1	TCCA STC SA14-48	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103	Cabin LED Lighting SystemRevision 1: Addition of an alternate LED vendor	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	The change is defined with Issue AA of Avmax Master Data List documentCE167-900.EMT EQ/Rockwell Collins Airstair Door, Lavatory, Reading Lights, Ceiling& Sidewall Lights:Installation of the Cabin LED Lighting Installation must be inaccordance with Avmax Engineering Order CE167-401 Issue E, dated June...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/08/2025	Active	10058371
10058379	DRF STIFTUNG LUFTRETTUNGG EMEINNUETZIGE AG			MBB-BK 117 C-1 MBB-BK 117 B-2	Installation of ADELT	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS-29 Amdt. 3. forparagraph 29.1; 29.21; 29.25; 29.27; 29.29;29.87; 29.143; 29.173;29.177; 29.181; 29.251; 29.301; 29.303...	- MBB-BK 117B-2/C-1 FMS 10-DRF-032 Rev. 00- ALS section of ICA document CA-117-25-60-00019 Rev. 00or later revisions ofthe above listed documents approved by EASA.- Master Document List MD-117-25-60-00023 Rev. 00- Compliance Checklist CC-117-25-60-00009 Rev. 00	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/06/2016	Active	10058379
10058380	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04264AT	767-300 SERIES	Interior reconfiguration installation on a Boeing 767-300 Seriesaircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. HAECO Cabin Solutions Master Data List 16T009L001, revision IR, datedJune 08, 2016.2. TIMCO Aerosystems Instructionsfor Continued Airworthiness16T009R009, Rev. IR, dated 20 April 2016.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/06/2016	Active	10058380

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058391	AVCON INDUSTRIES, Inc.		FAA STC SA1726CE	SEE FAA AML REV. A	Installation of camera window with sliding door cover and drift sight	1. For Hawker Beechcraft B90, C90, E90 the certification basis foralteration is as follows: Part 3 and FAR 23, plus amendments listed inthe TCDS.2. For Hawker Beechcraft F90 the certification basis for alteration isas follows: FAR 23, plusamendments listed in the TCDS.3. For Hawker Beechcraft C90A,...	1. MDL:- Hawker Beechcraft B90, C90, E90: Avcon Industries Drawing list No.8020, dated 1 March 1982 or later FAA approved revision.- Hawker Beechcraft F90: Avcon Industries Drawing list No. 8020,Revision D, dated 29 June 2004 or later FAA approved revision.- Hawker Beechcraft C90A, C90GT, C90GTi: Av...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This STC is valid for aircraft types and m...	22/06/2016	Active	10058391
10058397	BELL HELICOPTER TEXTRON, Inc.		FAA SR09602RC	412EP	Installation of a Honeywell Mark XXII HTAWS Kit for Bell HelicopterTextron 412EP Model Helicopters.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: FAR 29:At Amdt. 29-0: 29.301, 29.303, 29.305(a), 29.307(a), 29.561(b)(3),29.601(a), 29.603(b), 29.605, 29.609(a), 29.611(a), 29.619, 29.625(a), 29.1301At Amdt. 29-3: 29.773...	- Rotorcraft Flight Manual Supplement AA-12080 No Revision,DatedDecember 3, 2013or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilate...	Installation of Bell BasiX-Pro® Glass Cockpit and Pratt & Whitney CanadaPT6T-9 Twin Power Section Turboshaft Engines and associated systems inaccordance with EASA STC 10057657 is a pre-requisite for the HoneywellMark XXII HTAWS Kit installations.Prior to installation of this design change it must be...	13/06/2016	Active	10058397
10058399	SABENA TECHNICS BOD			F28 MARK 0100	ABE-NG - Scoop and Deflector InstallationAddition of one scoop and one deflector to improve nose pod coolingperformance	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Certification Program_CP-FK104-21-001E-AFMS-FK104-21-004 issue A_AFM Supplement-ICA-FK104-21-005 issue A & CVEDeclaration of Compliance: MAS-S-21-4024 issue 5or later revisions of the above listed documents approved by EASA.	-Only applicable for MSN 11290-The aircraft pre-modification configuration is the ABE-NG configuration(EASA STC No. 10056116)	13/06/2016	Active	10058399
10058421	BOMBARDIER Inc.		Q-LSA15-020/ D ISSUE 2	CL-600-2B16 (604 VARIANT)	Installation, Special Mission Equipment	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- TCCA Statement of Compliance, ref. NAI 5010-12-007, dated7th June2016- L-3 Communications MAS (CANADA) Inc. Master Document List, ref. doc.RAL-411-0004, Revision A, dated 1st March 2016- L-3 Communications MAS (CANADA) Inc. SupplementalAirplane FlightManual, ref. doc. AFMS-411-0001, Revision C,-...	EASA STC 10054917 Rev. 1 is a pre-requisite for this installation.,,Applicable only For CL604 Aircraft Serial No. 5896 and 5898.For Operating Limitations refer to Limitations Section of theSupplemental Airplane Flight Manual ref. doc. AFMS-411-0001, Revision C.The maximum number of occupants is elev...	14/06/2016	Active	10058421
10058425	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC ST11162SC	FALCON 2000EX FALCON 2000	Installation of Rockwell Collins Synthetic Vision System (SVS) andupgrade of Rockwell Collins Pro Line 21 to include TAWS Mode 5 warningsduring LPV ApproachesRev. 1: Change of Address	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List 514-00-0001, revision C, dated 12 November 2014.2. Airplane Flight Manual Supplement 514-00-0055, revision A, dated 19December 2014 or later FAA revision. 3.Instructions for Continued Airworthiness 514-00-0056, revision B,dated 12 November 2014.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. A prerequisite for this installation is th...	08/08/2025	Active	10058425

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058426	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC ST11165SC	MYSTÈRE FALCON 50 (MF50)	Installation of Rockwell Collins Synthetic Vision System (SVS) andupgrade of Rockwell Collins Pro Line 21 to include TAWS Mode 5 warningsduring LPV ApproachesRev. 1: Change of Address	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List 513-00-0001, revision C, dated 22 April 2015.2. Airplane Flight Manual Supplement 513-00-0055, revision IR, dated 22April 2015 or later FAA revision. 3. Instructions for Continued Airworthiness 513-00-0056, revision C,dated 26 March 2015.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. A prerequisite for this installation is th...	08/08/2025	Active	10058426
10058429	PMV ENGINEERING	REV. 2		A321-271N/-271NX/-272N/-272NX A321-253N/-251NX/-252NX/-253NX A321-251N/-253N/--271N/-272N A321-231/-232 A321-213/-231/-232/-251N/-252N A321-211/-212/-213 A321-111/-112/-131/-211/-212 A321-111/-112/-131 A320-253N/-271N/-272N/-273N A320-251N/-271N A320-231/-232/-233/-251N/-252N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-171N A319-131/-132/-133/-151N/-153N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	TPED tolerance on A320 familyRev. 1: - New Neo aircraft models added - ED130A is used instead of ED130 as guidance in accordancewith CM-ES-003 issue 01 - AFMS added as MOC in accordance with EASA CM-ES-003 issue01.Rev. 2 adds new NEO models.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- MASTER DOCUMENT LIST, ref: SCA-00480-MDL-R04 dated 23/08/2017- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: SCA-00480-ICA-R01 dated10/07/2017- AIRCRAFT FLIGHT MANUAL SUPPLEMENT, ref: SCA-00480-AFMS-R00 dated10/07/2017or later revisionsof the above listed documents approved by EASA.	Per Instructions for Continued Airworthiness document SCA-00480-ICA Rev.01 dated 10 July 2017.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse...	08/04/2022	Active	10058429
10058448	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	727-200F	FQIS Wiring Changes on Boeing 727	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Leading Edge Master Data List No. 2XL011 LEF78 Issue 1 dated 13 June2016	None	15/06/2016	Active	10058448
10058454	SABENA TECHNICS BGC			MBB-BK 117 C-2	Installation of Helinuc System mainly consisting of externally mountedpods containing different detectors and Mission equipment inside thecabin.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MBB-BK117 C-2 RFMS, document N° 2034-01-A-2301-Rev. 02ALS section of ICA document N° 2034-01-A-2211-Rev. 00or later revisions of the above listed documents approved by EASA.Certification Plan 2034-01-A-2101-Rev. 01MDL 2034-01-A-2103-R01Compliance Records 2034-01-A-2104-R00	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/06/2016	Active	10058454
10058458	AIR ALLIANCE GmbH			35, 35A, 36, 36A	P-RNAV Operation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeroplane Flight Manual Supplement, document No. 2015_013_LJ35_0506, rev02, dated 15 June 2016Instructions for Continued Airworthiness (ICA), document No. 2015_013_LJ35_0507, rev 00, dated 12 April 2016or later revisions of the above listeddocuments approved by EASA.Master Document List, document No...	This STC is limited to the following Learjet serial numbers:35A-607; 35A-614; 35A-643; 35A-654; 35A-674; 36A-062; 36A-063Prerequisite for this STC is:Universal Avionics Flight Management System UNS1FwDual Directional Gyros or Dual AHRS systemsDual electro-mechanical Navigation Displays (EHSI-74)RNAV...	16/06/2016	Active	10058458

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058463	PMV ENGINEERING	REV. 1		A300 F4-622R A300 F4-605R, A300 F4-622R A300 F4-605R A300 C4-620 A300 C4-605R VARIANT F A300 C4-605 R VARIANT F A300 B4-622R A300 B4-622, A300 B4-622R A300 B4-622 A300 B4-620 A300 B4-605R, A300 B4-620 A300 B4-605R A300 B4-603 A300 B4-601, A300 B4-603 A300 B4-601	Dual FMS CMA-9000 activation on A300-600Rev. 1: updates forintegration of aircraft A300-605R equipped with 2General Electric CF6-80C2A5F engines. In addition MMEL Supplement isincorporated in the STC.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-MASTER DOCUMENT LIST AVI-00650-MDL-S08-R00 dated 03 July 2024-AIRCRAFT FLIGHT MANUAL SUPPLEMENT AVI-00650-AFMS-R05 dated March 2024-INSTRUCTIONS FOR CONTINUED AIRWORTHINESS AVI-00650-ICA-R03 dated 04July 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system....	-As per AIRCRAFT FLIGHT MANUAL SUPPLEMENT and ICA document-Qualification in accordance with RTCA/ DO-229D, Change 1, MinimumOperational Performance Standards for Global PositioningSystem/ Satellite-Based Augmentation System Airborne Equipment datedFebruary 1, 2013 is not part of this STC approval-Mino...	08/07/2024	Active	10058463
10058465	AVIDYNE CORPORATION		FAA STC SA00269BO	SEE FAA AML REV. 9	Installation of Avidyne Corporation TWX 670 Tactical Weather DetectionSystem P/N 850-00026-000-( ) consisting of Avidyne Processor P/N700-00033-000-( ), Sensor Systems Inc. Antenna P/N S72-1715-1 withdoubler plate P/N S72-171530-1, and Avidyne Mounting Tray P/N700-00034-000.	Based on 14 CFR §§ 21.115 and 21.101, and the FAA policy fornon-significant changes in FAA Order 8110.48, the certification basisfor installation of the Tactical Weather DetectionSystem in theaircraft listed on the Approved Model List is as follows:a. The particular aircraft type certification basi...	1. Avidyne Corporation Master Document List, Document No. AVTWX-003,Revision 11, dated October 16, 2008, or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA), Avidyne CorporationDocument AVTWX-004, Revision 07, dated June 10, 2008, or later FAAaccepted revision.	1. The Tactical Weather Detection System integrates with separatelyapproved system installations. Adherence to the limitations in theappropriate Aircraft Flight Manual Supplementsfor those systems ismandatory.2. Prior to installation of this design change it must be determinedthat the interrelation...	22/06/2016	Active	10058465
10058467	E A D AEROSPACE AIRWORTHINESS			A300 F4-622 R A300 C4-620, A300 F4-605R A300 C4-605 VARIANT F A300 B4-622, A300 B4-622 R A300 B4-605 R, A300 B4-620 A300 B4-601, A300 B4-603	Installation of AlliedSignal Mark II ACARS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List, EAD Aerospace document No. 01496-EAS-A-MDL,Revision A, dated 27 April 2016.- Instructions for Continued Airworthiness, EAD Aerospace document No.01496-EAS-A-ICA-01, Revision A, dated 6 April 2016or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/06/2016	Active	10058467
10058474	AVMAX AVIATION SERVICES Inc.			DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-102, DHC-8-103,DHC-8-106	Seat Cushion & Dress Cover Replacement	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation of the Seat Cushion and Dress Cover Replacement must bein accordance with Transport Canada Civil Aviation (TCCA) approved AvmaxMaster Data List CE 236-900 Section 1.1 Issue B, dated December 15,2015.- Maintenance of the SeatCushion and Dress Cover Replacement must be inaccordance wit...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/06/2016	Active	10058474
10058495	GVH AEROSPACE LIMITED		CAA UK RESPONSIBILITY	B300	ACSS TCAS 7.0 Upgrade to TCAS 7.1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	GVH Aerospace Flight Manual Supplement No. GVH-6545-01-FMS-01 Issue 1or later revisions of the above listed documents approved by EASA.GVH Aerospace Master Data List No. GVH-6545-01-MDL-01 Issue 1.	None	20/06/2016	Active	10058495

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058501	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC SA10966SC	C90GTI	Installation of upgraded hardware to the Rockwell Collins Pro Line 21FMS-3000 to provide Localizer Performance with Vertical Guidance (LPV)Rev. 1: Change of Address	The Certification Basis for this installation is per Type CertificateData Sheet 3A20 plus the following:Regulations that meet amendment 23-123.671Regulations that meet amendment 23-1423.771 (a) Regulations that meet amendment 23-2123.1501 (b); 23.1541Regulations that meet amendment 23-3423.1; 23.1523...	1. Master drawing list 335-00-0001, revision A, dated 12 January 2010,or later approved FAA revision.2. Airplane FlightManual Supplement, document 335-00-0014, revision IR,dated 12 January 2010, or later approved FAA revision.	1. This installation is limited to airplane serial numbers listed in BHE& Associates document 335-00-0002, revision IR,dated 24 November 2009,or later FAA approved revision.2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change andp...	06/08/2025	Active	10058501
10058511	LUFTHANSA TECHNIK AG			A340-313	WLAN UpgradeReplacement of approved wireless access points with WLAN IEEE 802.11a/b/g standard by new units with WLAN IEEE 802.11 a/n/ac standard	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD23-15/37M Issue1 Rev 0- ICA, ref A-00-16/52-ICA Issue 2 Rev 0- Compliance Record List CRL23-15/37M Issue 1 Rev 0- AFM A-00-16-52-AFM Issue 02 Rev 0 (Internal Checking)or later revisions of the above listed documents approved by EASA.	As per the Instructions of Continuous Airworthiness, this approval isfor MSN 955Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designchange and/ or repair will introduce noadverse effect upon t...	22/06/2016	Active	10058511
10058529	CMD FLIGHT SOLUTIONS, LLC	REV. 2	FAA STC ST03424CH	SEE FAA AML	Certification of Automatic Dependent Surveillance - Broadcast (ADS-B)Out System with Rockwell Collins TDR-94D Transponders.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:The type certification basis for the aircraft listed on theEASAApproved Model List is shown on TCDS listed on the EASAL...	AIRPLANE FLIGHT MANUAL SUPPLEMENT, REPORT NO DB1409004 REVISION Dor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.DA...	THE TDR-94 transponder is a non-diversity transponder. Installation ofthe TDR-94D transponder is required for operations in accordance withEuropean Air Operations rules. Airplane Flight Manual supplement, ReportNo DB1409004 Revision C or later revision approved by EASA must beattached to the FlightS...	18/07/2018	Active	10058529
10058536	LUFTHANSA TECHNIK AG			A340-313	A340-313 Ka-Band SATCOM System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-2301-001 - Vibration / buffetingcompliance criteria for large external antenna installation.The requirements for environmental protecti...	- Supplemental Type Definition Document, Ref. STDD00-15/23MIssue 01 Rev02- ICA, Ref. A-00-16/51-ICA Issue 4 Rev 00- Compliance Record List, Ref. CRL00-15/23M Issue 01 Rev 00- AFM, Ref. A-00-16/51-AFM Issue 07 Rev 00or later revisions of the above listed documents approved by EASA.	- As per ICA Ref. A-00-16/51-ICA Issue 4 (Section 4) and AFMS Ref.A-00-16-51-AFM Issue 07 (Section 2).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce n...	23/06/2016	Active	10058536
10058540	LUFTHANSA TECHNIK AG	REV. 12		A321-111/-131/-211/-231 A320-211/-214/-216/-232/-251N A319-112/-114/-132	KA-band SATCOM System GX ConnectivityRev. 12: Revision to include additional Weight Variants in the STCeligibility.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-2301-002 "Vibration / buffetingcompliance criteria for large external antenna installation".The requirements for environmental protecti...	- Airplane Flight Manual A-00-16/45-AFM Iss/Rev 08/00-Instructions for Cont. Airworthiness A-00-16/45-ICA Iss/Rev 09/04-Supplemental Type Design Document STDD23-15/28M Iss/Rev 10.0- Flight Crew Data A-00-16/45-FCD Iss/ Rev 01/00or later revisions of the above listed document(s) approved/ acceptedunde...	This STC constitutes an approval for installation only for aircraftmodels that satisfy the configurations and criteria in both EngineeringInstructions AQY01-23-EI-001 Rev 11 and AQY01-53EI-001 Rev 12 and thatare listed in EMI Survey Summary AQY01-23-DR-12 Rev 14 or later approvedrevision.Prior to in...	27/09/2023	Active	10058540
10058553	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	A330-243	A330-200 AirTanker Enhanced Cabin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- SWS Certification Programme Ref. 3130-CEP-01- SWS Declaration of Compliance Ref. SWS/C/ 3130 dated 24.05.2016	X Installation of STC2 (EASA STC 10035945)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	27/06/2016	Active	10058553

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058559	DART AEROSPACE Ltd.		SH16-19 ISSUE 1	EC 130 B4/ EC 130 T2 AS 350 B/ AS 350 B1/ AS 350 B2 AS 350 B3/ AS 350 BA	Installation of D350-1021 Engine Cowling Swivel Prop Rod for groundmaintenance activities on engine bay.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions IIN-D350-1021 Revision A, dated 29 March 2016,or later TCCA approved revision.Instruction forcontinued Airworthiness ICA-D350-1021, Revision 01,dated 22June 2016, or later TCCA approved revision.Master Document Lists MDL-D350-1021, Revision A, dated 04 April 2016 orlater...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2016	Active	10058559
10058566	SWS CERTIFICATION SERVICES Ltd.	REV. 1	CAA UK RESPONSIBILITY	A330-200	AZUL A330-200 Skycouch Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration Scheme No.3146-MCS-01 Issue 1	Skycouch can only be used as a sleeping area or as an accommodationarea, as detailed in SWS Certification Services Ltd Design Report3146-DR-01, during in-flight conditions	22/07/2016	Active	10058566
10058570	KELLY AEROSPACE THERMAL SYSTEMS, L.		FAA STC SA03302CH	T206H 206H	Installation of an Air Conditioning System, Kelly Aerospacekit KATS-13-001	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Installation Instructions as listed on NC-13-027, revision A, dated24 December 2013.2. Drawing list NC-13-023, revision B, dated 24 January 2014, or laterFAA approved revision. 3. FAA approved Airplane Flight Manual Supplement, Doc. No. NC-13-025,Rev. B, approved 11 February 2014, or later FAA app...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/06/2016	Active	10058570
10058585	FALCON CREST AVIATION SUPPLY, INC.		FAA SR09186RC	AS 355 F2, AS 355 N AS 355 E, AS 355 F, AS 355 F1	Installation of concorde valve regulated sealed lead acid battery P/NRG355.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement for American Eurocopter Model Number AS355E, F,F1, F2& N with Concorde RG355, dated 9 December1997.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2016	Active	10058585
10058594	JET AVIATION AG			737-700	Interior Reconfiguration - Exec Lounge.,,Change of the executive lounge as per Section 2 of the CertificationPlan, Doc.No. JBSL-M-00523CER-01, Issue 4, dated 23-06-2016.The reconfiguration will not affect the passenger capacity. The interiorconfiguration shall continue to accommodate 24 passengersP...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	AFMS, Doc. No. JBSL-M-00523AFM-01, Issue 1, dated 23.06.2016or later revisions of the above listed documents approved by EASA.	Valid for MSN 38855.Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designchange and/ or repair will introduce noadverse effect upon the airworthiness of the product.	29/06/2016	Active	10058594
10058601	SABENA TECHNICS BOD			A330-323	A330 SUNLINE cabin installationThis modification installs acabin lay-out, mainly composed of newseats, information signs, carpets, raceways, curtains, lateralpartitions, floor pathmarking and flight attendant seat in Door 1LH, andmodifying / relocalising already installed equipment, as galleys,emer...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Modification Approval Sheet, ref: MAS S-25-4027 Issue 5 dated 29 June2016-Master Data List, ref MDL-S-25-4027, Issue B, dated 29 June 2016-Instruction for Continued Airworthiness, ref: ICA-F3043-25-014, Issue Adated 21 June 2016or later revisions of the above listed documents approved by EASA.	-EASA STC 1014507, Revision 2 (Installation of floor pathmarking) mustbe concurrently embodied with this modification.-The In-Flight Entertainment System server (Kontron) installed by thismodification (between FR26 and FR 26.1) must be deactivated and secured.-The 3G/4G antennae installed by this mo...	30/06/2016	Active	10058601

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058602	BELL HELICOPTER TEXTRON, Inc.		FAA SR01884AT	212, 412, 412EP 205A-1	Retractable Hardpoints system (Fast Rope Kit).Installation in accordance with Aeronautical Accessories Master DrawingList Report No. AA-98166 and Installation Instructions Report No.AA-98167.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeronautical Accessories Rotorcraft Flight Manual Supplement Report No.:AA-15058 N/R, dated 16 May 2016or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisionsofthis decision) and/ or the Technical Implementation Proced...	Certification of the Retractable Hardpoints installation does notconstitute operational approval; operational approval for external loadoperations must be granted by local aviation authorities.Prior to installation of this design change itmust be determined thatthe interrelationship between this de...	30/06/2016	Active	10058602
10058615	B/E AEROSPACE, Inc. - FSI		FAA STC ST02483SE	787-8	Installation of a business class ottoman trim and finish change onBoeing Model 787-8 series airplanes	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	B/E Aerospace, Inc. - FSI (B/E - FSI) Master Drawing List (MDL)B5FS542-D01, Revision A dated 29 June 2016.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The Supplemental Instructions for Continue...	05/07/2016	Active	10058615
10058630	AMAC AEROSPACE SWITZERLAND AG	REV. 1		A320-232	Complete interior outfitting (34 passenger VIP interior & 6cabin crew)as defined in the Certification Plan, Doc. No. CP-EE01-2500, Rev. C,dated 30.06.2016	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): - CRI D-2302-000 Isolated Compartments, - CRID-2310-000 Glass Screens of Displays / Monitors, - CRI D-2311-000Installation of glass panels in the cab...	- AFMS, Doc. No. AFMS-EE01-2500, Rev. A, dated 16.06.2016- ICA, Doc. No. ICA-EE01-2500, Rev. A, dated 01.06.2016or later revisions of the above listed documents approved by EASA.-Master Data List, Doc. No. MDL-EE01-2500, Rev. D, dated 01.07.2016	Applicable for MSN 5182.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	07/07/2016	Active	10058630
10058637	ARNFINN HALLAND INC.		TCCA O-LSA 14-082/D ISS 1	182Q	Integration of installed STC modifications, and additional utilitymodifications including B<(>&<)>C 25 amp standby alternator, CAM1601starter motor and associated electrical changes, Gemolzig Muffler, andC182S Front Seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modify aircraft and install “Item” in accordance with “InstallationReference” identified on Modification Summary List MSL-JBI-01, Rev 0,dated July 07, 2014.Operate Aircraft in accordance with “Operation Reference” identified onModificationSummary List MSL-JBI-01, Rev 0, dated July 07, 2014.Maintain...	Aircraft Serial 18266054 Only.Prior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	04/07/2016	Active	10058637
10058643	EMBRAER ENGINEERING & TECHNOLOGYCE NTER USA, INC.		FAA STC SA04243AT	EMB-505	Installation of Aft lavatory Coat Hanger Support.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Installation in accordance with Embraer Engineering and TechnologyCentre Master Drawing List Report No P300-008-002, Rev B, dated 13October 2015.Instructions for Continued airworthiness in accordance with EmbraerEngineering and Technology Centre Master Drawing List Report NoP300-008-003, Rev A, date...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/07/2016	Active	10058643
10058644	ALAMO ENGINEERING GmbH	REV. 4		EMB-135LR EMB-135BJ, EMB-135ER	Replacement of cockpit displays DU-870 with DU-875 on EMBRAER 135 SeriesAircraftRev. 1: Editorial ChangesRev. 2: Transfer of STC from 328 Support Services GmbH to ALAMOEngineeringGmbHRev. 3: Revised MDLRev. 4: Software upgrade for DU-875 and addition of alternate partnumber.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, Document No. MDL20A26AE-02 Revision C, dated23/MAR/2023< (>,<)>Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/04/2023	Active	10058644

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058645	STG AEROSPACE GERMANY GmbH	REV. 3		SEE EASA APPROVED MODEL LIST	saf-Tglo® PHOTOLUMINESCENT AISLE PATH MARKING SYSTEMS AIRBUS SERIESAIRCRAFT.Revision 2: Transfer of STC holder from STGAerospace Limited to STGAerospace GmbHRevision 3: Additional model included	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STG AEROSPACE LTD AEROPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1005-FMS-01Revision A;STG AEROSPACE LTD INSTRUCTIONS FOR CONTINUED AIRWORTHINESS No.SG-1005-ICA-01 Revision B;STG AEROSPACE LTD Cabin Crew Data Supplement No. SG-1005-CCD-01 RevisionIR STG AEROSPACE LTD MMEL Supplement No. SG-1005-MMEL-01 R...	SSUL Green Emitting Photoluminescent insert shall not be mixed with SSULBlue Emitting Photoluminescent insert on the same aircraft installation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed cha...	22/02/2022	Active	10058645
10058657	AVMAX AVIATION SERVICES Inc.		TCCA STC SA14-50 ISSUE 1	DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Transponder Upgrade for ADS-B Out	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): - CRI F-01 ADS-B Out Extended Squitter installation onDHC-8 100, 200, 300 series.- CS ACNSThe requirements for environmental protection and the associatedcer...	- AVMAX Aviation Services Inc. Flight Manual Supplement CE224-801 IssueB- AVMAX Aviation Services Inc. Maintenance Manual Supplement CE224-701Issue Dor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agre...	None	07/07/2016	Active	10058657
10058659	NSE	REV. 2		MBB-BK117 B-2, MBB-BK117 C-2 MBB-BK 117 B-2	Installation of Brite Saver 2, Usage Monitoring System REC-ARA0-BK117.Rev. 2:Addition of BK117 C2 to the STC applicability list.Evolution of the Brite Saver 2 from amendment 07 to10.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	“Rotorcraft Flight Manual Supplement Airbus Helicopter BK117 B2”RFMS-REC-ARA-BK117, Rev 01.“Rotorcraft Flight Manual Supplement Airbus Helicopter BK117 C2”RFMS-BS2-EC145-EN, Rev 02.“BRITE SAVER 2 BK 117 Maintenance Manual Supplement”MMS-REC-ARA-BK117-EN, Rev 01.“BRITE SAVER 2 BK 117 B2 Mounting Inst...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/11/2022	Active	10058659
10058690	ASI INNOVATION	REV. 1		B200	Radome Installation on Beechcraft B200 in accordance with ASI InnovationModification 0388.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	- Installation in accordance with ASI Innovation Service Bulletin refASI-SB-B200-2500-0388, Issue 0 dated 17.05.2016, and MDL refASI-MDL-0388-00 Rev 0, dated 17.05.2016.- Operate in accordance with ASI Innovation Aircraft Flight ManualSupplement ref ASI-AFM-0388, Issue 00, dated 19 July 2016.- Instr...	Applicable to Aircraft Serials BB-1270 and BB-1399.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produ...	07/09/2016	Active	10058690
10058691	AVMAX AVIATION SERVICES Inc.		C-LSA16-71/D	DHC-8-103	37/39 Passenger Seat Conversion.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Installation of the 37/39 Passenger Seat Conversion Installation is tobe done in accordance with Transport Canada CivilAviation (TCCA) approved Avmax Master Data List CE344-900 Section 1.1 &1.2 Issue A,dated May 31,2016Maintenance of the 37/39 Passenger Seat Conversion Installation is to bedone in a...	Limited to S/N 017.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	07/07/2016	Active	10058691

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058692	E A D AEROSPACE AIRWORTHINESS	REV. 1		AS355N	Installation of a an external container and internal storage provisionsas specified in Master Document List 01338-EAS-A-MDL.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment: CS27 Amdt. 2: 27.25, .27,.29, .31, .45, .49, .51, . 65(b), .67, .71, .75, .141, .143, . 171, .173,.175, .177, .241, .251, . 3...	Rotorcraft Flight Manual Supplement “AS355N: HELINUC SYSTEM”01323-EAS-A-RFM-01 Rev Ior later revisions of the above listed documents approved by EASA.- Instructions for continued airworthiness supplement01338-EAS-A-ICA-01, Rev. C- Compliance Checklist 01338-EAS-A-CCL-01, Rev. C.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/07/2016	Active	10058692
10058703	BOLDER MANUFACTURING L.L.C.		FAA STC ST04103CH	767-300 SERIES	Installation of Galley F4.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Bolder Master Data List, MDL-BM1506D01M1, Revision NC, dated May 27,2016.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/07/2016	Active	10058703
10058719	URBE AERO GmbH			DA 40 D	Synthetic Vision and ChartView / Safe Taxi	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DA 40D AFM Supplement for Integrated Avionics System GarminG 1000Synthetic Vision and ChartView DOC. No. AFM-110-01, Initial Issue: 06-Jul-2016or later revisions of the above listed documents approved by EASA.Engineering Order Doc. DOE/F07 Issue 1 26.4.2016	None	08/07/2016	Active	10058719
10058722	AVMAX AVIATION SERVICES Inc.		TCCA STC SA14-18	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103	Auxiliary Power Unit Removal	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Removal of the Auxiliary Power Unit must be in accordance with TransportCanada Civil Aviation (TCCA) approved Avmax Aviation Services (Avmax)Engineering Order CE095-401 Issue C , dated January 15, 2015.Definition of Type Design Change: Avmax Master Data List CE095-900 IssueC dated January 15, 2015or...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/07/2016	Active	10058722
10058731	SABENA TECHNICS BGC			EMB-145MK, EMB-145MP EMB-145LR, EMB-145LU EMB-145ER, EMB-145EU EMB-145, EMB-145EP EMB-135LR EMB-135BJ, EMB-135ER	Mechanical & electrical installation for tablet computer support incockpit of EMB-145 and EMB-135	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Applicable regulations at CS 25 Amendment 4 (referto associatedCertification Plan 0808-01-A-CP-R01, section 5, for details)The requirements for environmental protection a...	Master Data List, ref: 0808-01-A-MDL-R01Instructions for Continued Airworthiness, ref: 0808-01-A-ICA - R01AFM ref 0808-01-A-AFMS Rev 02or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/07/2016	Active	10058731
10058732	DELTA ENGINEERING CORPORATION	REV. 5	FAA STC ST04362NY	A330-343	INSTALLATION OF GOGO 2KU - SYSTEM ACTIVATIONRev. 4: Transfer to new STC holder Delta Engineering with FAA as PrimaryCertifying Authority"Rev. 5: updates the MDL, ICA and AFMS to Delta Engineering format	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS 25 Amendment 16 Various: 25.23 ALL; 25.29 (b); 25.251(a)(b)(c)(d)(e); 25.301 (a)(b)(c); 25.303 ALL;25.305 (a)(b)(c)(e...	Master Data List (MDL), Doc. No. 0154-11334-2549, Rev. C, dated 11October 2023<(>,<)>Airplane Flight Manual Supplement (AFMS), Doc. No. 0654-11332-2549, Rev.A, dated 17 August 2021<(>,<)>Instructions for Continued Airworthiness (ICA), Doc.No. 0754-11335-2549, Rev. A, dated 19 August 2021<(>,<)>Elect...	Design change S21.44-71-1010, approved by EASA STC 10056957Rev 1, mustbe installed prior to, or concurrently with, this design change.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/e...	08/01/2024	Active	10058732

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058735	DELTA ENGINEERING CORPORATION		FAA STC ST03165NY-D	737-800	Installation of Panasonic Digital Multiplexed EntertainmentSystem (DMPES)This modification installs the Panasonic DMPESoverhead video IFE Systemin the Business and Economy Class cabins. This installation includesPower Supply Units video system with overhead monitors.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List 0106-08346-2324 Revision A dated May 16,2013- Aircraft Flight Manual Supplement, ref : 0606-08343-2324, dated 20 may2013- Instruction for Continued Airworthiness, ref : 0706-08344-2324revision A, dated 19 February 2013or later revisions of the above listed documents approved by E...	None	11/07/2016	Active	10058735
10058763	SABENA TECHNICS BGC	REV. 1		CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700/701/702)	Mechanical & Electrical installations for tablet computer support incockpit of CRJ-700/-1000 and /-900Revision 1: CL-600-2D24 (RJ SERIES 900) is added	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Applicable regulations at CS 25 Amendment 4 (referto associatedCertification Plan 0810-01-A-CP-R02, sections 5 and 6 for details)The requirements for environmental protec...	-Master Data List, ref: 0810-01-A-MDL, Revision 01-Instructions for Continued Airworthiness, ref: 0810-01-A-ICA, Revision01-Aircraft Flight Manual Supplement, ref: 0810-01-A-AFMS,Revision 02or later revisions of the above listed documentsapproved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2016	Active	10058763
10058780	NSE			AS332L1 AS332L AS332C1 AS332C	Installation of DTSV2 Data Tracking System V2.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS29.29/.301/.303/.305/.307/.561/.607/.609/.611/.1301/.1309/.1351/.1357/.1359/.1363/.1501/.1529/.1581 at Amdt. 3 for theT...	- Rotorcraft Flight Manual Supplement RFMS-DTSV2-AS332 Rev.00or later revisions of the above listed documents approvedby EASA.- STC Document List DTSV2 on AS 332 : SDL-DTSV2-AS332 rev 02.,,- Certification Plan: PCERT-DTSV2-AS332 rev. 02.,,- Operating Manual :MUL-DTSV2 rev.02- Kit Definition File...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/07/2016	Active	10058780
10058807	LUFTHANSA TECHNIK AG			A330-343	Cabin Wireless Datalink System UpgradeThis modification activate an Internal Wireless Datalink system for newCabin Wireless Access Points supporting IEEE 802.11ac standard.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD46-16/12M Issue01 Rev 00- ICA, ref A-00-16/09-ICA, Issue 1 rev 2- Compliance Record List CRL46-16/12M Issue 01 Rev.00- AFM: ref A-00-16/09-AFM Issue 1 Rev 04or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, the following STCs andmodifications, must be part of the aircraft pre-required configuration,and must be installed accordingly :a) STC10058097, Aeroconseil, “Assessment of Aircraft Compatibility withTPED’s on A330 aircraft“ (12 May 2016)b) Minor Change M...	15/07/2016	Active	10058807
10058815	AVIATION FABRICATORS, Inc.		FAA STC SA52RM	500/ 550/ 560/ S550	Installation of stretcher or isollette.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Branson Engineering Company, Inc. Drawing list No. 90132, Revision A,dated July 2, 1975.2. Aviation Fabricators, Inc. SIC Drawing List AF-232, Revision A, datedApril 22<(>,<)> 1997.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/07/2016	Active	10058815
10058817	ELECTROAIR ACQUISITION CORPORATION		FAA STC SA02987CH	SEE EASA APPROVED AML	Installation of the Electroair Electronic Ignition System in accordancewith EIS-41000 Installation Manual.	Electronic Ignition System Installation is eligible for these airplanemodels that have converted to Textron Lycoming O-235, O-290, O/IO-320,O/IO-360, or IO/AEIO-390 model series engines by FAA Approved means asapplicable. Electronic Ignition System Installation is eligible forthese airplane modelsA...	- EIS-41000 Installation Manual, Revision 3, dated June 8, 2011- FAA Approved Airplane Flight Manual Supplement dated July 5, 2011- Continued Airworthiness Procedures, Document 1018-EA41000-3,Revision 1, dated June 7, 2011or later revisions of the above listed documents approved by EASA inac...	The EIS-41000 system can only replace one magneto.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produc...	19/07/2016	Active	10058817

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058832	CRANFIELD AEROSPACE SOLUTIONS LIMIT	REV. 1	CAA UK RESPONSIBILITY	AVRO 146 SERIES RJ70	Omnibus Modification – Conversion to Flying Classroom	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-01 Glass Screens of Displays and Monitors- The following paragraph(s) at a lateramendment: CS25 at amendment 13:25.23; 25.29; 25.143; 25.145...	CRANFIELD AEROSPACE INSTRUCTIONS FOR CONTINUED AIRWORTHINESS SERVICEBULLETIN NO. CA/DD/SB1381 ISSUE ECRANFIELD AEROSPACE Aircraft Flight Manual Supplement No. CA/DD/M054Issue Aor later revisions of the above listed documents approved by EASA.CRANFIELD AEROSPACE TYPE DESIGN DEFINITION ADDENDUM NO. CA...	Restricted to ASN E1254.The planning table seats are prohibited for use during Taxi, Take-offand Landing.The cockpit FTI Display Units must not be used as a source of primaryflight data and must not be used for observing aircraft limitations.The cockpit FTI Display Units can only be used during plan...	09/08/2016	Active	10058832
10058836	L-3 COMMUNICATIONS AVIONICSSYSTEMS, INC		FAA STC SA04046CH	SEE FAA AML	Installation of L-3 GENESIS ™ Electronic Standby InstrumentSystem(ESI-500/ MAG-500).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Dan Buzz & Associates Master Data List Document No. DB1502025,Revision B, dated December 2, 2015.2. FAA Approved Airplane Flight Manual Supplement (AFMS) as listed onthe AML number SA04046CH, or later FAA approved revision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for aircraft types and mo...	19/07/2016	Active	10058836
10058849	NORTHERN AVIONICS S.R.L.			767-200, 767-300, 767-400ER	WiFi WAvES installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: See Doc. CCL-NAV0521Rev.9.The requirements for environmental protection and the associatedcertified noise and/ or emission...	MDL-NAV0521 Rev.5 Master Document ListAFMS NAV0521 Rev. 0 AFM SupplementICA-NAV0521 Rev. 0 Instruction for continuous airworthinessor later revisions of the above listed documentsapproved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/07/2016	Active	10058849
10058922	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		3. 441 2. 404 1. 421, 421A, 421B, 421C, 425 1. 404, 411, 411A, 414, 414A 1. 402, 402A, 402B, 402C 1. 401, 401A, 401B	Installation of Garmin GTS 825.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:23.301; 23.303; 23.305(a); 23.305(b); 23.307; 23.365(a); 23.365(b);23.365(d); 23.561(a); 23.561(b); 23.571(a); 23.571(b); 23.575;23.603(a); 23.603(b); 23.605; 23.607; 23.6...	Installation, Operation and Maintenance according to the Master DocumentList ASR-2014-012-MDL-01-03 (Rev. 03) dated 7thJuly 2017.Instructions for Continued Airworthiness ASR-2014-012-ICA-11-03 (Rev.03) dated 7th July 2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10058922
10058923	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 2		3. 441 2. 404 1. 421, 421A, 421B, 421C, 425 1. 404, 411, 411A, 414, 414A 1. 402, 402A, 402B, 402C 1. 401, 401A, 401B	Installation of Garmin GTX 330D.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 23.301; 23.303;23.305(a); 23.305(b); 23.307; 23.365(a); 23.365(b); 23.365(d);23.561(a); 23.561(b); 23.571(a); 23.571(b); 2...	Installation, Operation and Maintenance according to the Master DocumentList ASR-2014-011-MDL-01-03 (Rev. 03) dated 7thJuly 2017.Instructions for Continued Airworthiness ASR-2014-011-ICA-11-03 (Rev.03) dated 7th July 2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2017	Active	10058923
10058937	B/E AEROSPACE, Incd/b/a SMR TECHNOLOGIES, INC		FAA STC SA01843CH	PA-46-500TP, PA-46R-350T PA-46-310P, PA-46-350P	Replacement of certain Goodrich pneumatic de-icer boots.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. SMR Technologies. Inc. Installation Instructions as listed onDrawings SMR5164, Revision 6, dated September 10, 2012 and detail designas listed on MDL-0022, revision H, dated August 21, 2013 for PiperPA-46-310P, PA-46-350P, PA-46R-350T and Drawings SMR5294, Revision 7,dated July 8. 2013 and detail...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Approval of this change in type design ext...	26/07/2016	Active	10058937

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058938	B/E AEROSPACE, Incd/b/a SMR TECHNOLOGIES, INC		FAA STC ST09858AC	DHC-8-400 SERIES DHC-8-300 SERIES DHC-8-200 SERIES DHC-8-100 SERIES	Replacement of certain OEM pneumatic De-Icer boots.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. SMR Technologies, Inc. Pneumatic De-Icer Layout, BombardierDHC-8-100, -200, -300 Series, Document No. SMR5152, Revision 8, datedNovember 23, 2015, and detail design as listed on Master Drawing ListMDL-0070, Revision C, dated March 31, 2016, or later FAA approvedrevisions.2. Pneumatic De-Icer Layo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/07/2016	Active	10058938
10058942	MT-PROPELLER ENTWICKLUNG GmbH	REV. 2		208, 208B	Installation of 4-blade constant speed propellerMTV-16-1-E-C-F-R(P)/ CFR250-55a on Textron/Cessna 208, 208B equipped withPratt & Whitney PT6A-42A Engine and optional increased Gross Weight.Installation of 5-blade constant speed propellerMTV-27-1-E-C-F-R(P)/CFR245-55a and optional maximum propeller sp...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to MT-Propeller Master Documentation List No. E-2823 Rev. 8;To be operated in accordance with MT-Propeller ARM-S Document No. E-2816Rev. 5 when the MTV-16-1-E-C-F-R(P)/CFR250-55a on the PT6A-42A enginehas been installed;To be operated in accordance with MT-Propeller AFM-S Document No.E-289...	According limitation section of MT-Propeller AFM-S.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produ...	01/02/2019	Active	10058942
10058946	B/E AEROSPACE, Incd/b/a SMR TECHNOLOGIES, INC		FAA STC ST03242NY	SAAB SF340A SAAB 340B	Replacement of certain Goodrich pneumatic De-Icer boots.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. SMR Technologies, Inc. Pneumatic De-Icer Layout, SAAB 340, DocumentNo. SMR5141, Revision 6, dated February 1, 2013, and detail design aslisted on MDL-0052, Revision J, dated February 1, 2013.2. The Maintenance Instructions for ContinuedAirworthiness inaccordance with SAAB 340 Aircraft Maintenanc...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This STC does not require revised Electric...	26/07/2016	Active	10058946
10058965	INTERNATIONAL ENGINEERINGAS SISTANCE (IEA)	REV. 1		EC135 T3(CPDS) EC135 T2+	Installation sieges Martin Baker en cabine / Seat installation MartinBaker in cabin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Instructions for Continued Airworthiness, document IEA-117, Issue B,dated 04/07/2106- Supplément n °02 au manuel de vol approuvé de l'hélicoptère EC 135toutes variantes, documentIEA-116, Issue A, dated 04/07/2106or later revisions of theabove listed documents approved by EASA.- Service Bulletin I...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/12/2016	Active	10058965
10058968	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED	REV. 2	CAA UK RESPONSIBILITY	EC135 T1, EC135 T2, EC135 T2+ EC135 P1, EC135 P2, EC135 P2+	NVIS Certification in accordance with BOND/MOD/085Rev. 1: Editorial correction regarding title and associated technicaldocumentation referencesRev. 2: Extension of applicability for further rotorcraft models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS27 Amendment 2 for27.1(a); 27.21(a); 27.251; 27.301(a), (b); 27.303; 27.305(a), (b)(1);27.307(a); 27.321(a); 27.337(a);(...	- Modification Leaflet and Certificate of Design MDL/ 085-014 Issue 5- Compliance Checklist (CS27) CCL/085-003 Issue 2- Compliance Checklist (DO-275) CCL/085-004 Issue 3- Rotorcraft Flight Manual Supplement FMS/ 085-002 Issue 5- Instructionsfor Continued Airworthiness ICA/085-011 Issue 4,,or later re...	The first installation of this kit must be supervised by the STC holder.Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, a...	04/02/2020	Active	10058968

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10058969	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A, 525B	Installation of LPV Converter	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-23, Amendment 4 (not required by 21A.101)29, 251, 303, 305,365, 561, 603, 605, 607, 609, 611, 613, 773, 863,867, 1301,1...	- Flight Manual Supplement,,ASR-2014-032-FMS-05-00 Amdt. 00or later revisions of the above listed documents approved byEASA.- Project Description,,ASR-2014-032-PRD-04-00 Amdt. 00or later approvedrevisions- Instructions for Installation ASR-2014-032-IFI-10-00 Amdt. 00 or laterapproved revisions- In...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/07/2016	Active	10058969
10058970	AVIONIK STRAUBING ENTWICKLUNGS GmbH			501, 551	Replacement of existing primary Attitude Indicator Display by SandelSA4550	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-23, Amendt. 3 (not required by 21A.101)307, 561, 575, 603, 607, 611, 771, 773, 777, 867, 1301, 1309, 1311,1322, 1327, 13...	- Flight Manual Supplement ,,ASR-2015-030-FMS-05-00,,Rev. 00or later revisions of the above listed documents approved by EASA.- Instructions for Installation ASR-2015-030-IFI-10-00 Rev. 00 or laterapproved revisions- Instructions for Continued Airworthiness ASR-2015-030-ICA-11-00 Rev.00or later app...	A suitable attitude source and an independent standby attitude indicatormust have been already installed.This STC is compatible to EASA STC 10045766 designed by AvionikStraubing.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and...	29/07/2016	Active	10058970
10058981	SIMPLEX MANUFACTURING CO.	REV. 2	FAA STC SR02351LA	AB139, AW139	Installation of Model 326 and Model 326 Gil Fire Attack System (FAS)aerial fire fighting tanks and equipmentRevision 2 updates the revisions of the ICA and RFMS documents.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	-ICA Simplex 326 GII FAS document 326-102005-002 Revision K, dated 31July 2024;-Rotorcraft Flight Manual Supplement document 326-102003-002 Revision K,dated 26 July 2024;or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical Implementat...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/03/2025	Active	10058981
10059001	RUAG AG	REV. 2		PC-12, PC-12/45, PC-12/47 PC-12, PC-12/45 PC-12/47, PC-12/47E PC-12/47E	PC-12 Sliding Cabin Seat Installation.This change enhances the applicability of the STC to Pilatus PC-12equipped with Overhead / drop down oxygen masks and removes thecertificate's limitation "This change is only approved for the PilatusPC-12 with Oxygen Mask installed in the side ledge".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Flight Manual Supplement FMS-608835, Rev. D;- Instructions for Continued Airworthiness ICA-8001540, Rev. Gor later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2021	Active	10059001
10059003	HONEYWELL INTERNATIONAL Inc.	REV. 4	FAA ST04040CH	737-900, 737-900ER 737-600, 737-700, 737-800 737-600/-700/-800/-900/-900ER	Activation of RAAS Functions for EGPWSActivation of Smart Runway and Smart Landing (SRSL) Runway AwarenessAdvisory System (RAAS) Functions for Honeywell Mark V and Mark V-A Enhanced Ground Proximity Warning Systems (EGPWS)Rev. 1: Extends applicability to additional modelsRev. 2: Includes additionalR...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt 2 foraffected areas.The requirements for environmental protection and the associatedcertified no...	- Master Data List, Ref. CN15-005MDL-00, Revision 14- Airplane Flight Manual Supplement, Ref. CN15-005AFM-02, Revision 7or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	- Master Data List, Ref. CN15-005MDL-00 Revision 14 (Section 1.4)- Airplane Flight Manual Supplement, Ref. CN15-005AFM-02 Revision 7 (Section II).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed ch...	17/09/2024	Active	10059003

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059025	DART AEROSPACE Ltd.		SH16-24 ISSUE 1	205A-1/ 212	D212-1024 Main Rotor Tie Down Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Document List, MDL-D212-1024 Revision A, dated May 18th 2016 orlater TCCA approved revision.Installation Instruction, IIN-D212-1024 Revision A, dated October 13th2015 or later TCCA approved revision.Instruction for Continued Airworthiness, ICA-D212-1024 Revision 0, datedOctober 23rd 2015 or l...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/08/2016	Active	10059025
10059026	S4A SOLUTIONS FOR AVIATION, S.L			777-200LR	CABIN CONNECTIVITY SYSTEM IN B777.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Flight Manual Supplement S4A 77702-HDK01 Edition 8or later revisions of the above listed documents approved by EASA.Service Bulletin 77702-SB001 Ed14 (22/09/15).Master Drawing List 77702-RPT02 Ed8 (10/12/15).Maintenance Manual Supplement 77702-HDK02 Ed4 (07/04/15).Wiring Diagram Manual Supplement 77...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/08/2016	Active	10059026
10059032	IAC - INDUSTRIAS AERONAUTICAS DECOIMBRA, Lda.			U206G TP206D/ TU206E/ U206E/ U206F TP206A/ TP206B/ TP206C/ U206D P206D/ U206E/ P206E/ TU206D P206B/ U206C/ P206C/ P206A 206/ P206/ U206A/ P206A/ U206B	Modification for skydiving operation.The modification for manual and static line jumping includes a rear doorexterior platform, an optional right landing gear platform and twohandles to assisted parachuting activity.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forSpecial Condition (s):SC-O23-div-01 Parachuting Activity.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	IAC-C206SKY-AFMS Parachuting Modification with Cessna SkydivingComponents Equipment List. Issue 01or later revisions ofthe above listed documents approved by EASA.IAC.C206SKY.MDL Master Document List. Rev. 1.ORM IAC21.001 Project Dossier.Issue 01.IAC-MOC-500115 MoC List. Issue 02.IAC-C206SKY-II In...	This modification only can be used in association with Cessnainstallation of skydiving components.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadv...	04/08/2016	Active	10059032
10059044	MICRO AERODYNAMICS, INC.		FAA STC SA01033SE	177/177A/177B/177RG/ F177RG	Installation of vortex generators on the wings and tail surfaces.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Drawing Package MA2162, Revision IR, dated November 1, 2001, andInstallation Manual MA2163, Revision IR, dated December3<(>,<)> 2001,or later FAA approved revision of either of these documents.	Approval of this change in type design applies to the aboveaircraftonly.Prior to installation of this design change itmust be determined thatthe interrelationship between this design change and any otherpreviously installed design changeand/ or repair will introduce noadverse effect upon the airw...	05/08/2016	Active	10059044
10059045	AVOX SYSTEMS Inc.		FAA STC ST01741WI	737-600/-700/-800/-900/-900ER	Installation of the AVOX LavOx Passenger Lavatory Oxygen System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI F-113 Oxygen FireHazard in Gaseous Oxygen SystemsCRI F-125 Minimum Mass Flowof Supplemental OxygenJAR 25 Change 15 for the affected area...	-Master Data List, Ref. 12-268-3500-L01-00, Rev. IR-Instructions for Continued Airworthiness, Ref. 89544, Rev. Eor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementat...	As per Instructions for Continued Airworthiness, Ref. 89544(Section 11)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	05/08/2016	Active	10059045

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059057	BABCOCK MISSION CRITICAL SERVICES DAND COMPLETIONS LIMITED	REV. 1	CAA UK RESPONSIBILITY	MBB-BK117 D-3M MBB-BK117 D-3 MBB-BK117 D-2	NVIS Certification in accordance with BOND/MOD/126.Reason for Revision 1Applicability of BOND/MOD/126 extended to MBB BK-117 D-3 and MBB BK-117D-3m helicopter models according to CAA UK STC UK.STC.00105.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 29 Amdt 4: 29.1,29.771, 29.773, 29.777, 29.785, 29.803, 29.853, 29.1301, 29.1309,29.1321(a), 29.1321(g), 2...	Babcock MCS Design & Completions Ltd CCL/ 126-021 – Compliance Plan /Compliance Checklist Issue 1Babcock MCS Design & Completions Ltd DR/126-001 - Design Report Issue 10Babcock MCSDesign & Completions Ltd Modification Leaflet & Certificateof Design MDL 126/019 Issue 11Babcock MCS Design & Completion...	MBB-BK117 D-3 and D-3m aircraft shall be equipped with OEM NVIScompatible lighting installed.Rotorcraft modified by this STC employ Night Vision Imaging Systemlighting, commonly named NVIS lighting, which has been certified toensure the aircraft is compatible with Night Vision Goggles (NVG). Forthis...	12/01/2022	Active	10059057
10059063	SOCIETE AIR FRANCE S.A.	REV. 1		A330-203	AIRCRAFT T-PED TOLERANCE.Aircraft compatibility with the use of PEDs with transmitting capabilityfrom within the aircraft cabin.Rev 1: The certification dossier is updated to facilitate aircraft PEDtolerance demonstration and aircraft applicability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Instruction for Continued Airworthiness, ref : ICA-A330-16-005-001 Rev1< (>,<)>or later revisions of the above listed documents approved by EASA.Master Data List : Change Approval Sheet ref : CAS-A330-16-005 Rev 4.	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane installed base station using the cellularand/or wireless technologies is concurr...	20/06/2017	Active	10059063
10059069	HELI-ONE		TCCA STC SH12-8 ISSUE 2	AS 332 L/ AS 332 L1	Installation of Soft Shell Interior Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Manufacturing of the Soft Shell Interior Kit is to be carried out inaccordance with Manufacturing Master Drawing List DWG11019-02, Rev. 0,TCCA approved February 02, 2012.Installation of the Soft Shell Interior Kit is to be carried out inaccordance with Installation Master Drawing List DWG11019-01, R...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/08/2016	Active	10059069
10059071	INTELSAT INFLIGHT LLC	REV. 3	FAA STC ST04232NY	747-400	INSTALLATION OF GOGO 2KU - SYSTEM ACTIVATIONRev 3: transferof certificate to new holder GoGo LLC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 16 Various: 25.23 ALL; 25.29 (b); 25.251(a)(b)(c)(d)(e); 25.301 (a)(b)(c); 25.303 ALL;25.305 (a)(b)(c)(e); 25.307 (a)(d); 25.321 (a); 25.331 (a)(b)(c); 25....	'EASA Approved'STC TWENTY ONE LIMITED Aircraft Flight Manual Supplement S21.FMS-0135Issue 2.REFER TO STC TWENTY ONE LIMITED Supplement Manual S21.TEC-0498 FORAIRWORTHINESS LIMITATIONS.'EASA Accepted'STC TWENTY ONE LIMITED MASTER DOCUMENT LIST NO. S21.MDL-1243 Issue 6.or later revisions of the aboveu...	Design change S21.44-14-1008<(>,<)> approved by EASA STC 10055922<(>,<)>must be installed prior to<(>,<)> or concurrently with<(>,<)> thisdesign change.There are Airworthiness Limitations in the form of structuralinspections required for this design change which are documented withinS21.TEC-0498.ItM...	23/07/2020	Active	10059071
10059084	NSE			AB206 B	Installation of Usage Monitoring System by means of BRITE SAVER 2recorders as defined in DD-0027-92-EN, Rev 17.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement AB206 RFMS-ARA0-AB206-EN, Rev 00or later revisions of the above listed documents approved by EASA.Brite Saver 2 Instruction for Continued Airworthiness ICA-REC-ARA0-206,Rev 00 (no Airworthiness Limitation associated to this STC).Brite Saver 2 Mounting InstructionB...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/08/2016	Active	10059084

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059093	AEARO TECHNOLOGIES LLC		FAA STC ST03464CH	G-1159A/G-IV/GV/GV-SP/ GIV-X	Installation of thermal acoustic insulation packages.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Aearo Technologies Master Data List MDL-1664-050614-001, Revision B,dated 28 May 2015.Aearo Technologies Installation Matrix Drawing EAR1664-000, Revision"-", dated 25 August 2014.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/08/2016	Active	10059093
10059100	APTOZ EHF.	REV. 2		DHC-8-402 DHC-8-401	AFIRS 220 Automated Flight Information Reporting System InstallationRev 1: certificate transferred from Tenencia Ltd tolcelandairRev. 2: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	TEN 798-47, Aeroplane Flight Manual Supplement, issue 1 dated 26/04/2016TEN 798-04-ICE, Aircraft Maintenance Manual Supplement, issue 2 dated04/05/2016 (Section 4<(>&<)>5)or laterrevisions of the above listed documents approved by EASA.TEN 798-04-ICE, Aircraft Maintenance Manual Supplement, issue 2...	This STC does not include the EFB provisions of the SystemPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the produ...	27/05/2025	Active	10059100
10059101	SOCIETE AIR FRANCE S.A.			A330-203	WIFI System InstallationInstallation and Activation of IFE system with wireless features for VODon T-PED	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List: Change Approval Sheet ref: CAS-A330-16-004 Rev 0- Instruction for Continued Airworthiness, ref: ICA-A330-16-004-001 Rev0- AFM, ref: AFMS-A330-16-004-001 Rev0or later revisions of the above listed documents approved by EASA	According to the design related to this STC, the following STC and minorchange, are pre-requisites:- STC Air France, ref 10059063, Aircraft T-PED-Tolerance- Minor Change Air France, ref CAS-A330-16-003 (Rev 0)Prior to installation of this design change it must be determined thatthe interrelationship...	11/08/2016	Active	10059101
10059102	AIRBORNE TECHNOLOGIES GmbH			MBB-BK 117 D-2	Title: Trakka Search Light InstallationDescription: Installation and operation of a Trakka A 800 searchlight ona multifunction step on the right side of the helicopter. The followingmodifications are part of this change:Installation of a CFRP searchlight bracket P/N 084-5210-00-01, theTrakka A 800 s...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement, Document No. AFM-STC-AT-094, Rev.1, dated20-Jul-2016or later revisions of the above listed documents approved by EASA.Change Dossier, Doc. No. STC-AT-094, Revision 2, 04-Aug-2016<(>,<)>Aircraft Maintenance ManualSupplement, Doc. No. AMM-STC-AT-094, Rev. 2,dated 20-Jul-201...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/08/2016	Active	10059102
10059103	SCANDINAVIAN AVIONICS DESIGN ApS			B300, B300C B200CGT, B200GT B200, B200C	Digital FDR and FDAU Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-01 – CS 23, Amdt. 3, FAR 23, Amdt. 34The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product...	-Doc. 2101043 DOC - Certification documents, Issue 1, 5.8.2016-Doc. 2101043 COR – Compliance Record, Issue 1, 7.6.2016-AFM Supplement BEECH Model: B200/B200C/B200GT/ B200CGT, Model:B300/ B300C, L3 Digital Flight Data Recorder and Flight DataAcquisitionUnit, Doc. 2101043-AM, Issue 2, dated 2016.07.04-...	None	11/08/2016	Active	10059103

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059108	XENON GROUPE	REV. 5		DR 400/2+2 DR 400/180 R, DR 400/2+2 DR 400/180 R DR 400/140, DR 400/140 B DR 400/140 B DR 400/140 DR 400/125I DR 400/125, DR 400/125 I DR 400/125 DR 400/120 D DR 400/120 A, DR 400/120 D DR 400/120 A DR 400/120 DR 400/100, DR 400/120 DR 400/100	Installation of a ROTAX 912iS on DR400 according to NOG/STC/LDOC/KB/001.Rev. 1: Change in use of external alternator according toNOG/STC912/DMM02/2018Rev. 2: Noise measurementRev.3: Engine cooling improvement during ground operation.Introduction of a larger water cooler equipped with a larger cooli...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI-110 Electrical Systems andEquipment; CRI-104: Fuel Pumps.- The following paragraph (s) at a later amendment: CS-23 (initial...	Initial issue: Installation in accordance with NOG/STC/LDOC/KB/001Aircraft Flight Manual Supplement NOG/STC/SMDV/GA/001AMM Supplement NOG/STC/SME/GA/001Rev. 1: NOG/STC912/DMM02/2018Aircraft Flight Manual Supplement NOG/STC/SMDV/GA/001AMM Supplement NOG/STC/SME/GA/001Rev. 2: DOSSIER DE MODIFICATION M...	This STC requires concurrent installation of the propeller DUCH-FSH_3-D-R_i_RX_C (TCDS P.038).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	02/08/2024	Active	10059108
10059114	ROW 44, Inc.		FAA STC ST03269CH	767-300 SERIES	Installation and activation of Row 44 Wireless Broadband System inaccordance with Row 44 Master Data Index List (MDIL) RWG100-0001-00Revision L, dated 07 July 2016.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:For Parts changed or affected by this change<(>,<)>Regulationsat the latest amendment 25-0 through 25-113:25.23(b), 25-29(...	- Row 44 AFM Supplement RWG220-0001-00 Rev. IR dated 21 April 2016- Row 44 ICA & EWIS ICA source document in accordancewith Row 44 MasterData List as identified in the Row 44 Master Data Index List (MDIL)RWG100-0001-00 Revision L, dated 07 July 2016.or later revisions of the above listed documentsa...	- Row 44 Broadband Antenna System Provisions installation (EASA STC“please insert here the allocated EASA STC No. to EASA Project10027558“ , FAA STC ST03268CH) is a concurrent requirement to this STC.- In accordance with FAA ACO letter 140S-11-202C, dated 03 Aug. 2011,this STC change is an AMoC wit...	12/08/2016	Active	10059114
10059115	ROW 44, Inc.		FAA STC ST03268CH	BOEING 767-300 SERIES	Row 44 Wireless Broadband System Antenna provisions in accordance withRow 44 Master Data Index List (MDIL) RWG100-0002-00 Revision H, dated 23June 2016.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): IP F-1the following paragraph(s) at a later amendment:For Parts changed or affected by this change, Regulations at the latestamendment 25-0 t...	- Row 44 AFM Supplement in accordance with Row 44 Master Data IndexListing (MDIL) RWG100-0002-00 Revision H, dated 23 June 2016.- Row 44 ICA Source Document, Airworthiness Limitations in accordancewith Row 44 Master Data Listing RWG100-0002-00 Revision H, dated 23 June2016.or later revisions of thea...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/08/2016	Active	10059115
10059141	BOMBARDIER Inc.			CL-600-2B16 (604 VARIANT)	Installation, AVS-470 Tail Camera System.	The Certification Basis (CB) for the original product remains applicableto this certificate/approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Transport Canada Supplemental Type Certificate, SA07-115, Issue 1, dated30th August 2007.TCCA approved Aero Consulting Modification Data Summary, ref. doc.F396000, Revision N/C, dated 15th August 2007.TCCA approved Aero Consulting Compliance Check List, ref. doc. F396065,Revision N/C, dated 15th Aug...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/08/2016	Active	10059141
10059148	RSG PRODUCTS, Inc.			SA 365 N/ SA 365 N1 AS 365 N2/ AS 365 N3	Installation of Freon Air Conditioning System with Belt DrivenCompressorFAA Supplemental Type Certificate SH5832SW)	The Certification Basis (CB) for the original product remains applicableto this certificate/approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/approval.	FAA Approved Rotorcraft Flight Manual Supplement dated May 27, 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)” and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/08/2016	Active	10059148

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059156	ASI INNOVATION			ERJ 170-200 LR	Embraer 175 Cabin Modification.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	ASI Innovation Master Drawing List ref. ASI-MDL-0378-01 Revision 01dated 10 August 2016.ASI Innovation Service Bulletinref. ASI-SB-EMB175-2500-0378 Issue 01dated 9 August 2016or later revisions of the above listed documents approved by EASA.	For completion of the compliance demonstration to JAR 25.785, 25.791 and25.1447 the installer should follow the instructions given in chapter 17on “Cabin Inspection” of document ref. ASI-SB-EMB175-2500-0378 duringthe installation of this modification before the aircraft is returned toservice.	18/08/2016	Active	10059156
10059159	S4A SOLUTIONS FOR AVIATION, S.L	REV. 2		208B	FIREWALL MODIFICATIONThe modification includes new materials and P/N into the original STC.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 23.1, 23.3, 23.21,23.25, 23.251, 23.301, 23.303, 23.305,23.307, 23.321, 23.337, 23.341,23.471, 23.601, 23.603, 23.60...	Service Bulletin No 20832-SB-001, Issue 2, date 16/07/20Master Drawing List No 20832-RPT02, Issue 2, date 16/07/20or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/09/2020	Active	10059159
10059180	TELAIR INTERNATIONAL Inc.		FAA STC FAA ST02438LA	747-8F SERIES	Installation of GSM and GPS Cargo Communication System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Index List, IL193100-8GSM, Rev. N/C, dated October 15 2012-Master Data List, MDL193100-801, Rev. B, dated October 17, 2012or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical I...	The installation must not be incorporated in any aircraft unless EASASTC 10036941 (FAA STC ST02367LA) has been installedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repai...	23/08/2016	Active	10059180
10059187	E A D AEROSPACE AIRWORTHINESS			SA227-PC SA227-BC SA227-AC	01495-EAS-A - TCAS 7.1 Installation on Swearingen SA227 series	CS 23 initial issue for paragraphs identified in the CertificationProgram document.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	01495-EAS-A-AFM-01 Rev A dated 16 Mar 2016 - Airplane Flight ManualSupplement01495-EAS-A-MDL Rev E dated 19 Aug 2016 - Master Document Listor later revisions of the above listed documents approved by EASA	Limitation to aircraft already fitted with EAD Aerospace STCEASA.A.S.01562 revision 1.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect u...	24/08/2016	Active	10059187
10059205	SCANDINAVIAN AVIONICS DESIGN ApS			B300, B300C, B200 B200C, B200CGT, B200GT	Installation of a Rockwell Collins TCAS-4100 Traffic Alert and Collision Avoidance System in accordance withScandinavian Avionics Design document 2100328-STC, at issue 1, datedAugust 24, 2016.NEW-PAGE	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs of CS-23 at Amdt. 3: 29, 301, 303, 305, 307,341, 561, 601, 603, 605, 607, 609, 611, 613, 625, 771, 773, 853, 863,867, 1301, 1309, 1311, 1321, 1322...	Aircraft Flight Manual Supplement Scandinavian Avionics Design document2100328-AM, at issue 3, dated August 24, 2016or later revisions of the above listed documents approved by EASA.Instructions for Continued Airworthiness Scandinavian Avionics Designdocument 2100328-CA, at issue 1, dated February 1...	None.	25/08/2016	Active	10059205
10059220	JJASPP ENGINEERING SERVICES, L.L.C.		FAA STC SR09634RC	MBB-BK 117 C-2 MBB-BK 117 B-2/ MBB-BK 117 C-1 MBB-BK 117 A-4/ MBB-BK 117 B-1 MBB-BK 117 A-1/ MBB-BK 117 A-3	Installation of Balloon Pump Restraint System.This project certifies the restraint system for a medical intra-aorticballoon pump.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Rotorcraft Flight Manual Supplement for Eurocopter Deutschland GmbHModels MBB-BK117 A-1, A-3, A-4, B-1, B-2, C-1, C-2 with JJASP AirMedical Balloon Pump Restraint System, DocumentNo. JJASPP-FMS-12-015,Initial Revision dated and FAA approved 4 April 2013or later revisions of the above listed documen...	None.	26/08/2016	Active	10059220

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059221	SPAES GmbH & Co. KG			SA 365 N/ SA 365 N1 AS 365 N2/ AS 365 N3	Installation of adapter plate for EMS seat.For EMS operation an EMS seat has to be installed and a two seat benchhas tobe removed. Therefore an adapter plate as interface betweentheEMS seat and the ground structure of the passenger compartment has to beinstalled.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Flight Manual Supplement “FMS-SPAES-0044”, Revision 01or later revisions of the above listed documents approved by EASA.Master Document List “MDL-365-044-53-01”, Revision 01, dated 17.08.2016.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/09/2016	Active	10059221
10059224	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)	REV. 1		CL-600-2B16 (601-3A VARIANT)	Triple FMS Software Upgrade (UASC) Initial release of 10059224Upgrade of the existing triple Flight Management System (FMS) UNS-1 Fwsystem software to SCN 1001.X in accordance withUniversal AvionicsSystem Corporation (UASC) Service Bulletin 3XXX.XX.()-34-3633, dated 07.April 2016.Rev. 1 to 10059224U...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Airplane Flight Manual Supplement: Doc. No. AC5338-071, Rev. Cor later revisions of the above listed documents approved by EASA.- Master Document List: Doc. No. AC5338-049, Rev.D- Engineering Order: Doc. No. AC5338-062, Rev. B- Instructions for Continued Airworthiness: Doc. No. AC5338-085, Rev. B...	Limited to HB-IKS, S/N 5042Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installeddesign change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	13/03/2018	Active	10059224
10059232	GVH AEROSPACE LIMITED		CAA UK RESPONSIBILITY	EC635 T1(CPDS) EC635 P2+, EC635 T2+ EC135 T2(CPDS) EC135 T1(CDS), EC135 T1(CPDS) EC135 P2+, EC135 T2+ EC135 P2(CPDS) EC135 P1(CDS), EC135 P1(CPDS)	Installation of Thommen HSL-1600 Searchlight and HCU-1600 Hand ControlUnit in accordance with GVH Aerospace Master DataList (MDL) GVH-5898-02-MDL-01.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement (FMS) – EC-135 Searchlight InstallationGVH-5898-02-FMS-01 Issue 2or later revisions of the above listed documents approved by EASA.Master Data List (MDL) - Airbus EC135 Searchlight InstallationGVH-5898-02-MDL-01 Issue 3Instructions for Continued Airworthiness (ICA) - EC135 S...	The Thommen HSL-1600 searchlight is to be installed on an existing sidestep mounting bracket approved in accordance with AirFilm CameraSystems/ Meeker EASA STC 10017058 (EASA.IM.R.S.01490).The minor design change designated GVH-5898-01-MOD-01 will introduce theunpowered internal equipment and wirings...	29/08/2016	Active	10059232
10059233	AVIONIK STRAUBING ENTWICKLUNGS GmbH			MU-2B-60	Installation of Garmin G600 system with GAD 43e as an option.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	AFM-supplement ASR-2016-063-FMS-05-00, amendment level 0, date16/06/2016or later revisions of the above listed documents approved by EASA.Avionik Straubing Entwicklungs GmbH project ASR-2016-063. All documentsare defined in Master DocumentList ASR-2016-063-MDL-01-00.	None.	29/08/2016	Active	10059233
10059237	AVIONITEC Ltd.			PA-60-700P	Avionics Upgrade.Removed:- Garmin GNS530 (GPS/NAV/COM) withGA 56 Antenna- Garmin GNS430 (GPS/NAV/ COM) with GA 56 Antenna- Garmin MX 20 Multifunction Display- Eventide Argus 7000 Navigation Display- Bendix/King KI 525 HSI- Bendix/King KR 87 ADF with KA44B Antenna- Bendix/King KT 76 C Transponder- RC...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:Compliance to CS-ACNS.D.ELS.010, 015, 020, 025, 030, 040, 045, 050, 055,060, 065.The requirements for environmental prot...	AFMS for dual Garmin GNS 530W/430W: Doc. No. 5846-011, Rev. 30.06.2016.AFMS for Sandel SN 3500 EHSI: Doc. No. 5846-012,Rev. 30.06.2016.AFMS for Honeywell KMH 880 TAS/ TAWS: Doc. No. 5846-013, Rev. 30.06.2016or later revisions of the above listed documents approved by EASA.Master Document List: Doc.I...	S/N 60-8423010 (HB-LUD).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	29/08/2016	Active	10059237

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059242	DV AVIATION, Inc.DBA NORTHPOINT AVIATION	REV. 2	FAA STC SA02748AT	B) TU206G/ U206G A) 206H/ T206H 206H, T206H, TU206G, U206G	Installation of a Wing Mounted Forward Looking Infrared Camera System,Monitor Stand, and Microwave Downlink Antenna System.Rev. 3: Transfer from "Fifty-Ten-Yankee, LLC" to "DV Aviation, Inc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List, Soloy Report No. 916-100, Revision L, dated January22, 2016.Pilot's Operating Handbook Supplement,Soloy Publication No. S2060A,Revision 2, dated September 29, 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or...	Approval of this change in type design applies to the abovemodelaircraft only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	14/06/2023	Active	10059242
10059246	JET AVIATION AG	REV. 1		B-747-SP	SATCOM SBB Antenna (remove 500 FC or one year limitation).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions Requirements levels of the originalproduct are unchanged and remain applicable to this certificate/a...	INSTRUCYIONS FOR CONTINUED AIRWORTHINES Doc. No. JBSL-M-00575ICA-01Issue 4or later revisions of the above listed documents approved by EASA.	None.	21/08/2017	Active	10059246
10059257	AIRBUS HELICOPTERS, Inc.	REV. 1	FAA STC SR09105RC-D	EC135 T2+, EC135 T3 (CPDS) EC135 T1(CPDS), EC135 T2(CPDS) EC135 P3(CPDS), EC135 T1(CDS) EC135 P2(CPDS), EC135 P2+ EC135 P1(CDS), EC135 P1(CPDS)	Installation of a Concorde RG-390E or RG-380E/44 Lead Acid Battery.Revision 1 adds battery installation for T3/P3 models equipped withHelionix.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR09105RC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	Airbus Helicopters, Inc. drawing list 135A82-8022, Rev. F, dated 21 June2016;For RG-390E battery installations on aircraft originally certified withthe TC 25-27 Ah NiCad battery and not equipped with Helionix: RotorcraftFlight Manual Supplement (RFMS) 135FMS-002 Rev. 3 dated 24 June 2016 andInstruct...	The RG-390E is a 28 Ampere-Hour lead acid battery and can be used as areplacement for the TC 25-27 Ah NiCad battery.TheRG-380E/44 is a 42 Ampere-Hour lead acid battery and can beused asa replacement for the TC 25-27Ah NiCad battery or the TC 40Ah NiCadbattery.Airbus Helicopters EC135 with Helionix...	10/01/2022	Active	10059257
10059258	AEROMECH Inc.		FAA STC SA01790SE	B300C B300 B200C B200 300LW 300 200C 200	Group aircraft approval for Reduced Vertical Separation Minimum (RVSM)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data list, document AM0190-DL02-00, Revision -, dated 14January 2016 or later FAA approved revision.2. Class 1 Airframes:- IICA, document AMI-IICA-KAIR-0713, Revision F,dated 1 December 2015or later FAA-accepted revision;- AFMS,document AMI-AFMS-KAIR-0718, Revision A, dated 17 February 2...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/09/2016	Active	10059258
10059262	SABENA TECHNICS BGC	REV. 1		ATR 72-211/-212/-212A ATR 72-201/-202 ATR 72-101/-102 ATR 42-400/-500 ATR 42-200/-300/-320	Mechanical & electrical installation for tablet computer support incockpit of ATR 42 & ATR 72Revision 1: A new size of tablet docking-station of 10.5" is allowed inthe installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to the associated Certification Plan0661-01-A-CP-R02, sections 5 and 6 f...	- Master Data List, ref: 0661-01-A-MDL-R04- Instructions for Continued Airworthiness (Supplement), ref:0661-01-A-ICA-R04- AFM (Supplement) ref 0661-01-A-AFMS-R04or later revisionsof the above listed document(s) approved/ acceptedunder the EASA system.	- Only for Electronic Flight Bag use. No other use permitted.- In case of Electro Magnetic Interference when personal tablet computeris connected to electrical installation, the power supply cord must bedisconnected from the USB outlet. Itis the operator's responsibility todetermine that the operat...	23/08/2018	Active	10059262

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059264	PMV ENGINEERING	REV.2		A330-203	Cabin Reconfiguration and In Flight Entertainment System installation onA330.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	- MASTER DOCUMENT LIST SCA-00650-MDL-R03 / dtd. 1.Sep 2016.- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS CAB-01811-ICA-R00dtd. 14.Jan2016.- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS SCA-00650-ICA-R01 dtd. 29.Aug 2016.- EWIS - INSTRUCTIONS FORCONTINUED AIRWORTHINESS SCA-00650-EWIS-R03dtd. 29.Aug 2016or...	- The modification of the economy class seat through EASA STC 10059287is required.- Aircraft cabin has to be modified in accordance with Airbus ServiceBulletin reference SB25-3622.- OBRMs have to be replaced in accordance with Airbus SB referenceSB23-3229Prior to installation of this design change i...	04/11/2016	Active	10059264
10059265	EICHELSDOERFER GmbHFLUGZEUGBAU			ASW 20 CL/ ASW 20 L ASW 20 B/ ASW 20 BL/ ASW 20 C	Installation of the Draline PSR T01 (EASA.E.108) turbine engine to thesailplane ASW 20 in accordance with EichelsdörferFlugzeugbau documentASW 20 STC PSR DL at revision 0, dated August 31, 2016.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forEquivalent Safety Finding(s): 22.975, 22.977.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pr...	Start of engine based on gas: Aircraft Flight Manual Supplement,Eichelsdörfer Flugzeugbau document ASW20STCPSRFLG, at revision 0, datedFebruary 18, 2016.Start of engine based on ceresin: Aircraft Flight Manual Supplement,Eichelsdörfer Flugzeugbau document ASW20STCPSRFL, at revision 0, datedJuly 15,o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/09/2016	Active	10059265
10059267	BELL HELICOPTER TEXTRON, Inc.		FAA STC SE02170AT	PT6A-27/-28/-34/-34B	Installation of Pc safety Valve Kit, part number 610-850-001/-002.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Report No. AA-99088, Installation Instructions< (>,<)> Pc Safety ValveKit of Pratt and Whitney PT6A-27/28/34 series engines, Rev "A", datedMay 19, 2000, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/09/2016	Active	10059267
10059273	KENN BOREK AIR Ltd.		TCCA SA09-59	DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300 DHC-6 SERIES 210 DHC-6 SERIES 200 DHC-6 SERIES 110 DHC-6 SERIES 100 DHC-6 SERIES 1	Modification “Roof Access Step Installation” in accordance with AeroDesign Ltd. DCL857, IR, dated 13 July 2009	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DCL857, IR, dated 13 July 2009or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/09/2016	Active	10059273
10059276	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A330-343	Interior reconfiguration of Lufthansa aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0541-D90, Revision A, dated 31 August 2016.Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0541-D70, Initial Release, dated 6April 2016.Airplane Flight Manual Supplement, Northwes...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/09/2016	Active	10059276
10059277	SABENA TECHNICS BGC			A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-216/-231/-232/-233 A320-111/-211/-212/-214/-215 A319-131/-132/-133 A319-111/-112/-113/-114/-115	ACMS WEFA system installation on Airbus Single Aisle Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Applicable regulations at CS 25 Amendment 4 (referto associatedCertification Plan 0549-01-A-CP-R02, section 5, for details)The requirements for environmental protection a...	- Master Data List, ref : 0549-01-A-MDL-R00- Instructions for Continued Airworthiness, ref:0549-01-A-ICA-R02or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/09/2016	Active	10059277

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059287	KNSI AVIATION ENGINEERING LIMITED		CAA UK RESPONSIBILITY	A330-203	EQUIPMENT AND FURNISHINGS – A330 TOURIST CLASS SEAT INSTALLATION.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	KNSI Aviation Engineering Limited Master Document List No.16K087-MDL-001-4.R Revision 04 dated 02 September 2016.	Restricted to MSNs 0587 and 0634.This STC is a prerequisitefor EASA STC No. 10059264.	05/09/2016	Active	10059287
10059306	Q.C.M. DESIGN GmbH			BAE.125 SERIES 1000A	P-RNAV Airworthiness Approval,,P-RNAV airworthiness approval based on the existing aircraft avionicsequipment in compliance to JAA TGL 10 rev. 1 was shown.RNAV 1 compliance was shown against ICAO PBN Manual DOC 9613, TableII-B-3-2.,,	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Airplane Flight Manual Supplement: Doc. No RH10-QCM34-001-M1-AFM-R2,dated 30.08.2016,,or later revisions of the abovelisted documents approved by EASA.,,- Master Document List:Doc. No. RH10-QCM34-001 R1 Certification Report,dated 29.08.2016.,,	This installation complies with ICAO PBN RNAV 1 airworthiness criteria;provided at least one FMS is receiving usable information from one GPS.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed desig...	06/09/2016	Active	10059306
10059324	AEROSPACE DESIGN FACILITIES Ltd.		CAA UK RESPONSIBILITY	AS350 D AS350 B, AS 350 B1, AS350 B2 AS350 B3, AS350 BA, AS350 BB	External Utility Pod and Laser Scanner Installation.NEW-PAGE	CS27 Amdt. 3 paragraphs: 27.1, 27.29, 27.31, 27.45, 27.51, 27.65, 27.71,27.75, 27.141, 27.143, 27.173, 27.175, 27.177, 27.241, 27.301, 27.303,27.305, 27.309, 27.321, 27.337, 27.351, 27.601, 27.603, 27.605, 27.607,27.609, 27.610, 27.611, 27.613, 27.619, 27.625, 27.629, 27.771, 27.777,27.863, 27.865,2...	- Rotorcraft Flight Manual Supplement, doc. ref. ADF-RFMS2015-146 Rev.1, dated 24/07/2016or later revisions of the above listed documents approved by EASA.- Project Compliance Planning and Management Document, doc. ref.ADF-PCPMD2015-146, issue 4, dated 25/07/2016- Compliance Report, doc. ref. ADF-CR...	- The structural provisions for the External Cargo Sling must beinstalled- This modification requires the rotorcraft tobe equipped with highlanding gear- This modification is notcompatible with cargo sling mirrors. - ADFMinor Change ADF2015-143 Seat Rack, equipped with Riegl PowerDistribution Boxb...	07/09/2016	Active	10059324
10059337	GVH AEROSPACE LIMITED		CAA UK RESPONSIBILITY	A340-312	Installation of a 100 VIP Passenger LOPA.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	GVH Aerospace Instructions for Continued Airworthiness No.GVH-5957-01-ICA-01 Issue 1or later revisions of the above listed documents approved by EASA.GVH Aerospace Master Data List No. GVH-5957-01-MDL-01 Issue 1.	- Restricted to MSN 0374.- EASA STC 10013964 Rev 3. is a prerequisite for this modification.	08/09/2016	Active	10059337
10059338	SOCIETE DUCt/a DUC HELICES PROPELLERS	REV. 2		DR 400/180 S DR 400/180 R DR 400/180 DR 300/180 R	Revision of STC DR400 / FLR2 – Installation Hélice 5-pales FLAIR-2H-FLR2_5-D-I_CUpdate covering increase in weight, removal of the spacer, modificationof fixing configurations andaddition of instruction manual in English	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Program, Doc No. DH_STC_000_CP, Revision H,Dated 16 May2018;- Master Document List, Doc No. DH_STC_000_MDL, Revision C, Dated 16May 2018;or later revisions of the above listed document (s) approved under theEASA system.	Limitation to aircraft fitted with LYCOMING engine O-360-A3A, A1A orA1P.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ orrepair will introduce no adverseeffect upon the airworthines...	07/06/2018	Surrendered	10059338
10059339	AVMAX AVIATION SERVICES Inc.		TCCA STC SA16-16	DHC-8-315 DHC-8-311/ DHC-8-314 DHC-8-202/ DHC-8-301 DHC-8-106/ DHC-8-201 DCH-8-102/ DHC-8-103	Rockwell Collins TTR-4100 TCAS II V7.1 U.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CE329-801, Issue A, dated 11 JAN 16, Flight Manual Supplement, RockwellCollins TTR-4100 TCAS II V7.1 Upgradeor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.CE329-900 Issue A, dated 15 JAN 16,...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/09/2016	Active	10059339

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059355	HAECO CABIN SOLUTIONS, LLC		FAA ST04199AT	A330-300	Interior Reconfiguration of A330-300.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: Refer to TIMCO Letter refTIM-16-0020, dated on 02nd March, 2016, “RE: EASA Significant StandardsDifferences Evaluation – T...	Master Data list, ref 14T144L001, revision DCertification plan 14T144R006 rev CICA ref 14T144R009, rev AFAA Statement Of Compliance: FAA Letter Ref 120A-15313-05, dated on9/ Nov/15, FAA Letter Ref 120A-16130-06, dated on 09th May 16.	Refer to the associated ICA document related to the Associated TechnicalDocumentation for this approvalPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducea...	09/09/2016	Active	10059355
10059358	ADS-B TECHNOLOGIES, L.L.C.		FAA STC SR02471AK	SEE FAA AML REV. 1	Installation of the L-3 Communications NGT -9000/9000R ADS-B System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	1) Lynx NGT -9000 and CP2500 Rotorcraft Installation Manual, L3-89-IM,Revision 0, dated December 2, 2015, or later FAA approved revision.2) Rotorcraft Flight Manual Supplement or Supplemental Flight Manuals,L3-89-RFMSI, Revision 0, dated February 16, 2016, is required to becarried on the rotorcrafto...	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2) Installation requires prior approved anten...	23/09/2016	Active	10059358
10059359	FOKKER TECHNIEK B.V.	REV. 2		737-800	Boeing 737 VIP CompletionThe aircraft conversion consists of replacing and modifying the standardBoeing base line interior partly byinstalling a new VIP interior in the forward section, installing newmonuments in the aft section and theinstallation and/or modification of several cabin systems.Revisi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFMS: B738-RTAF-AFM-S-001, revision 03.AMMS: B737-RTAF-AMM-S-001, revision 03.ICA: SE-794, issue 07.MDL: B737-RTAF-MDL-0001, issue 01.CRR: B737-RTAF-CRR-0001, issue 02.MMEL: B738-RTAF-MMEL-S-001, revision 06.or later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/12/2019	Active	10059359
10059367	BHE & ASSOCIATES, LTD.	REV. 5	FAA STC ST11169SC	HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 900XP	Installation of a Rockwell Collins Pro Line 21 update to includeoptional Terrain Awareness and Warning System (TAWS) mode 5 warningduring Localizer Performance with Vertical Guidance (LPV) approaches,optional Automatic Dependent Surveillance Broadcast (ADS-8) Out,optional Synthetic Vision System (SV...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:FAR 25.613(a)(b) - Amdt 25-141FAR 25.773(a) - Amdt 25-108FAR 25.981(a)(3)(b) - Amdt 25-102FAR 25.1317(a)(b)(c)...	- Installed according to the Master Drawing List 549-00-0001, RevisionC, dated 21 April 2016;- Operated according to the Airplane Flight Manual Supplement549-00-0055 Initial Revision, dated 21 April 2016;- Maintained according to the Instructions for Continued Airworthiness549-00-0056, Initial Revis...	- Must have factory installed Proline 21- The Database Unit (DBU) must be factory installed DBU-5010E or updatedto a DBU-5010E per EASA STC Approval 10016379 (FAA STC ST01431WI-D)- If the optional LPV TAWS Mode 5 is installed, LPV must be installedform the factory, factory service bulletin or be ins...	08/08/2025	Active	10059367
10059374	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02451SE	737-800 SERIES	Installation of interior components.	The Certification Basis (CB) for the original product as amended by thefollowing/or alternative requirements, the following paragraph at alater amendment FAR 25-85 3(a)(b) amdt. 25-116.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Northwest Aerospace Technologies, Inc. (NAT) Master DrawingList (MDL) N0521-D10 Revision B, dated August 26, 2015.Instructions for Continued Airworthiness (ICA) N0521-D70, Revision -,dated June 17, 2015, or later FAA-approved revision.	Approval of this change in type design applies to the abovemodelaircraft only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	18/01/2017	Active	10059374

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059375	LIFEPORT, LLC		FAA STC SA02235LA	B200GT	Installation of a Patient Loading and Utility System (PLUS)andServiPlex.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	FAA Approved Master Drawing List for the PLUS and ServiPlexinstallationin the Hawker Beechcraft B200GT, MDL-846-00, Revision J, dated 27 March2009.FAA Approved Airplane Flight Manual Supplement No. EGR-846-11, dated May13, 2009, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installer of this STC must ensure that if th...	15/09/2016	Active	10059375
10059378	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	A320-231/-232/-233/-271N A320-211/-212/-214/-215/-216	FREE STANDING BULKHEAD	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	J <(>&<)> C ENGINEERING SERVICES Ltd Modification No. JC/ MOD/M4618 Issue1.1	The bulkhead installation must be in accordance with J <(>&<) >C drawingno. RAC252JC2181 ISS A.Subsequent installations of the divider must be the subject of aseparate design approval	12/09/2016	Active	10059378
10059379	AERO TECHNICS DESIGN LIMITED		CAA UK RESPONSIBILITY	A340-642/ -643 A340-311/ -312/ -313	Introduction of alternative part number seat foams on Contour premiumeconomy seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero Technics Design Limited Certification Plan No. ATDCP0838 Issue 3.	None.	12/09/2016	Active	10059379
10059389	AERO TECHNICS DESIGN LIMITED		CAA UK RESPONSIBILITY	A330-341/ A330-342/ A330-343 A330-321/ A330-322/ A330-323 A330-301/ A330-302/ A330-303	Introduction of alternative part number seat foams on Zodiac Sicmaeconomy seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero Technics Design Limited Certification Plan No. ATDCP0830 Issue 4.	None.	12/09/2016	Active	10059389
10059391	AERO TECHNICS DESIGN LIMITED		CAA UK RESPONSIBILITY	A330-300	Introduction of alternative part number seat foams on Zodiac premiumeconomy seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Aero Technics Design Limited Certification Plan No. ATDCP0837 Issue 4.	None.	15/09/2016	Active	10059391
10059392	DELTA G DESIGN Inc.		FAA ST11122SC	737-900ER	Structural modification necessary for the installation of three cameras,one antenna, and one drainage hole.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 1 forthe affected area as defined in DGD-EASA-STC-02, Rev. IR.The requirements for environmental protectio...	- Master Data List, Ref. DGD-SPC0-MD-01, Revision B.- Instructions for Continuous Airworthiness, Ref. DGD-SPC0-IC-01,Revision A.or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF(or subsequent revisions ofthis decision) and/ or the Techni...	Limitations as per:- Instructions for Continuous Airworthiness, Ref. DGD-SPC0-IC-01,Revision A (Airworthiness Limitations).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or re...	13/09/2016	Active	10059392

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059395	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01804SE	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of the 200-310-00 Load Weigh Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Onboard Systems Master Drawing List No. 155-116-00, Revision 0, datedDecember 13, 2006, or later FAA-approved revision.Onboard Systems Owner's Manual No. 120-126-00, Revision 0, dated June29, 2006, or later FAA-approved revision.Section ATA 5 of Onboard Systems Instruction for ContinuedAirworthiness...	Approval of this change in type design applies only to those AirbusHelicopters AS350 model rotorcraft listed above thatare equipped withthe Airbus Helicopters 1400 kg Cargo SwingSystem as installed perEurocopter Service Bulletin 25.00.62.Prior to installation of this design change it must be deter...	21/09/2016	Active	10059395
10059397	GFD GmbH	REV. 1		35A/ 36A 35A, 36A	Decoy Self Protection System (SPS).Rev. 1: Transfer to GFD GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01, Decoy Self Protection System (SPS).The requirements for environmental protection and the associatedcertified noise and/ or emissions leve...	- Aeroplane Flight Manual Supplement, doc. 5467-071, Rev. A, dated 13June 2016.- Instructions for Continued Airworthiness, doc. 5467-085, Rev. A, dated13 June 2016or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC is only valid for a de-activated system, it does not grant anyairworthiness approval for the intended functionof the Decoy system.The aircraft operator must obtain airworthiness and operational approvalfrom the appropriate authority responsible for the type of operation inwhich the systemP...	23/08/2022	Active	10059397
10059427	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR02290LA	MBB-BK117 C-2, MBB-BK117 D-2	Installation of Apical Industries, Inc. Cable Cutters Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Dart Aerospace Master Document List MD145-2, Revision C, dated 12January 2016 or later FAA approved revision.Instructions for Continued Airworthiness, ICA 145-21, Revision D, dated8 June 2015, or other FAA accepted ICA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/09/2016	Active	10059427
10059428	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC ST02602LA	737-800 SERIES	Installation of Cabin Interior Window Shades.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Aerocon Engineering Company Master Drawing List No. AC25-WSB737-1000,Revision "K", dated 10 August 2016.2. Aerocon Engineering Company Instructions for Continued Airworthiness(ICA) Document Maintenance Manual Supplement CMM-B737WS-1983 Revision"NC" dated 23 June 2016.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/09/2016	Active	10059428
10059450	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	737-800	Installation of Galleys 1 (737GUN01GC00), 2 (737GUNF2GC00), 4B(737GUN4BGC00) and 7 (737GUNW1GC00).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Change record CR 1175 rev3- Final Weight Report STR/FWR/1175 rev Aor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/09/2016	Surrendered	10059450
10059454	S-TEC CORPORATION		FAA STC SR02553LA	R66	Installation of S-TEC HeliSAS Stability Augmentation System/Autopilot(SAS/AP) in accordance with S-TEC Master Data List(MDL)ST-953-MDL-0001.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):FAA SC No. 27-035-SC Installation of HeliSAS Autopilot and StabilizationAugmentation System (AP/SAS)The requirements for environmental protection andc...	- Rotorcraft Flight Manual Supplement ST-953-RFMS-0001 Revision Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.--...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/09/2016	Active	10059454

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059458	GAL AVIATION Inc.		TCCA STC Q-LSA16-001/D ISS. 01	B737-800	B737 Partial VIP Interior in a STD configuration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissionslevels of the original product are unchanged and remain applicable tothis certificate/ approval.	Master Drawing List (MDL): BLX-15-074(FS)-NC, Revision IR; Instructionsfor Continued Airworthiness (ICA): BLX-16-052, Revision 0; AbbreviatedComponent Maintenance Manuals (ACMM): 25-20-05 Revision 0 for BulkheadAssembly, 25-20-10 Revision 0 for Sideledge, 25-20-15 Revision 0 forVVIP Lounge Tables, 2...	Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any other previously installed design change and/or repair will introduceno adverse effect upon the airworthiness of the product.	20/09/2016	Active	10059458
10059468	SOCATA			SA 3180	Installation of blade tip ref. AL II 01-200-01 in accordance with Socatamodification n° STC 57-001-16.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	STC approval sheet n° STC 57-001-16 issue 1 dated 02/08/2016.,,Maintenance Manual Supplement n° STC 57.001.16.050 issueD dated 27August 2016.	None.	20/09/2016	Active	10059468
10059470	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		737-800	737 satLINK InstallationRev. 1: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS25 at Amendment 17(various).The requirements for environmental protection and the associatedcertified noise...	Aviation Traders Ltd. Flight Manual Supplement 13071-AFM-00001 Issue 1Avionica Instruction for Continued Airworthiness No. 26047-ICA RevisionPor later revisions of the above listed document(s) approved/acceptedunder the EASA system.Aviation Traders Ltd. MASTER DOCUMENT LIST MDL-13071-00001 Issue 1....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/11/2021	Active	10059470
10059495	ROSEMOUNT AEROSPACE, Inc.	REV. 6	FAA ST02814CH	A321-271N/-271NX/-272N A321-251N/-253N/-271N/-272N A321-231/-232 A321-213/-231/-232/-251N/-253N A321-211/-212/-213 A321-111/-112/-131/-211/-212 A321-111/-112/-131 A320-251N/-271N A320-232/-233/-251N/-271N A320-231/-232/-233 A320-111/-211/-212/-214/-231 A320-111/-211/-212/-214 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of Rosemount Aerospace Electronic Flight Bag (EFB) Systemand ProvisionsRev. 4 adds new installation configuration V.Rev. 5 adds new installation Configuration W.Rev. 6 corrects the aircraft models list and adds new aircraft model(A321-271NX) and revises Inflight Connectivity (IFC) inter...	The Certification Basis for the original product as amendedby- The following additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS-25 Amdt 3 in case of applicable MDL configuration A for25.301(a)-(c); 25.303; 25.305 (a)-(c); 25.307(a); 25.561(c)-(d);...	- Master Data List, Rosemount Aerospace Inc. Doc No. D06404216, revisionAN, dated 16 February 2024- Airplane Flight Manual Supplement, Rosemount Aerospace document No.D06423824, Revision A,dated 30 June 2016.- Airplane Flight Manual Supplement, Rosemount Aerospace document No.D06428259, Revision C,d...	Limitations as per MDL D06404216- The Rosemount Aerospace Electronic Flight Bag (EFB) System is anapproved Class 3 EFB system for use in hosting Type A and Type Bsoftware applications following the guidance in EASA AMC 20-25(equivalent of FAA AC 120-76C).- Hosting Type C software applications requir...	12/09/2024	Active	10059495
10059502	LUFTHANSA TECHNIK AG			A330-343	DLH A330 2 Class Reconfiguration RAVE.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Supplemental Type Design Definition STDD 00-15/22M Issue 1 – Rev. 1.Instructions for Continued Airworthiness A-00-16-19-ICA Issue 1 – Rev. 00.Aircraft Flight Manual Supplement, A-00-16/65-AFM, Issue 1 Rev 1.Declaration of Compliance: “Applicant’s Declaration Of Compliance“, No3597, Rev. 02or later re...	According to the design related to this STC, this modification must beinstalled in conjunction with:a) STC 10014507, Rev. 2, “Installation of non-electrical Floor PathMarking System”, together with associated LHT post STC minor Changereference MX-5003 / 0 (Installation of seat-mounted PLM FPM Strips...	22/09/2016	Active	10059502

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059504	LITEAIR AVIATION PRODUCTS Inc.	REV. 1	FAA ST02438SE	A321-231/-232 A321-213, A321-232, A318-111 A321-211/-212/-213 A321-131, A321-211, A321-212 A321-111/-112/-131 A320-232, A320-233, A321-112 A320-231/-232/-233 A320-212, A320-214, A320-231 A320-211/-212/-214 A319-132, A319-133, A320-211 A319-131/-132/-133 A319-114, A319-115, A319-131 A319-111, A319-112, A319-113 A319-111/-112/-113/-114/-115 A318-112, A318-121, A318-122 A318-111/-112/-121/-122	Lightweight window plug installation.Rev 1: applicability list corrected	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- LAP1011-D01 Rev. A: Master drawing list- LAP2011 Rev. A: Installation drawing including maintenanceinstructions and ,,airworthiness limitations informationor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/11/2022	Active	10059504
10059509	STG AEROSPACE GERMANY GmbH	REV. 4		737-700/-800/-900/-900ER 737-300/-400/-500/-600	Boeing 737 - STG Aerospace LiTeMood® Version 1.1 LED Cabin LightingRev. 1 added 737-900ER models to the ApplicabilityRev. 2 added 737 Classic models to the ApplicabilityRev. 3: Transfer from Aviation Traders Limited (t/ a ATL) to AviationTraders Limited Europe SAS.Rev. 4: Transfer from ATL aerospace...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS25 Amdt 17: 1, 23, 25, 27, 301(a), 303, 305(a), 561 (a)(b)(c), 581,601, 603, 605, 607 (a), 609(b), 611(a), 613, 789, 812 (...	Master Document List MDL-13078-00001, Issue 4<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/09/2021	Active	10059509
10059514	HELI AUSTRIA GmbH			AS 332 L/ AS 332 L1	Installation of a KANNAD 406 AF-H Emergency Locator Transmitter.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forSpecial Condition (s):CRI F-01<(>,<)> Non-rechargeable Lithium Battery Installations.The requirements for environmental protection and the associatedcertified noise and/...	Flight Manual Supplement (FMS), Doc. No. HAU-D-025-005, Rev. 0, dated12.05.2016or later revisions of the above listed documents approved by EASA.Master Document List (MDL), Doc. No. HAU-D-025-001, Rev. 0, dated12.05.2016.Installation Manual, Doc. No. HAU-D-025-004, Rev. 0, dated 12.05.2016.Instructi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/09/2016	Active	10059514
10059517	AIRBUS S.A.S.			A320-214	Airbus Corporate jet Centre Modification CJ2070 – CABIN COMMUNICATIONSYSTEM UPGRADE	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition: CRI H-01 “Enhanced Airworthiness Programme forAeroplanes Systems – EWIS ICA”The requirements for environmental protection and the associatedcertified no...	- Modification Approval sheet CJ2070 issue 01, dated 23rd September 2016- AFM Supplement FM-S MOD CJ2070 dated SEP 01/16or later revisions of the above listed documents approved by EASA.	This approval is limited to MSN 3199	23/09/2016	Active	10059517
10059536	SCANDINAVIAN AVIONICS DESIGN ApS			SEE APPROVED MODEL LIST	Replacement/upgrade of the existing single or dual transponder toinclude ADS-B functionality according to Minimum Operational PerformanceStandards	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): CRI F-101 ADS-B Out Extended Squitter installation onvarious aircraft – Deviation to CS-ACNS.D.ADSB.105The following CS-23 Amdt 3 paragraphs apply: 23.1,,,,23...	- Doc. no. 2101561-TO A-2 Technical Order for a single / dualtransponder system ADS-B upgrade, Issue 2 dated 21st July 2016;- Doc. no. 2101561-AM A-4 Aircraft Flight Manual Supplement, Issue 4dated 12th Aug. 2016or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/09/2016	Active	10059536

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059542	SABENA TECHNICS BGC			A320-232, A320-233 A320-215, A320-216, A320-231 A320-211, A320-212, A320-214	Ku-Band Antenna Provisions Removal on A320	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to associated Certification Plan0819-01-A-CP-R00, section 5 & 6, for det...	- Master Data List, ref: 0819-01-A-MDL-R00- Instructions for Continued Airworthiness (Supplement), ref:0819-01-A-ICA-R00or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/09/2016	Active	10059542
10059543	JET AVIATION AG	REV. 1		A319-131, A319-132, A319-133 A319-114, A319-115, A319-115 A319-111, A319-112, A319-113	HD Tail, Quad and Zoom Camera Installation.Revision 1 : Transfer of the EASA STC 10059543.	See appendix JBSC-M-00094CCS-01, Issue 2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MDL: JBSC-M-00094MDL-01 Issue 02;CCS: JBSC-M-00094CCS-01 Issue 02;ICA: JBSC-M-00094ICA-01 Issue 02; JBSC-M-00094ICA-02 Issue 02,,,,or later revisions of the above listed documentsapproved by EASA.,,	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/09/2017	Active	10059543
10059545	AVIONIK STRAUBING ENTWICKLUNGS GmbH			MBB-BK117 C-1, MBB-BK117 C-2 MBB-BK117 B-1, MBB-BK117 B-2	Installation of single/dual Garmin GTN650/GTN750.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-29, Amdt 3: CS 29.29(a)(b), CS 29.251, CS 29.303<(>,<)>CS 29.305 (a)(b), CS 29.337, CS 29.561 (a)(b), CS 29.603 (a)(b)(...	- Approved Flight Manual Supplement for COM/NAV/ GS/GPS GarminGTN650/ GTN750 for rotorcraft equipped with Bendix/King EFS40/50,ASR-2014-081-FMS-05.1-00, Revision 0 dated 9 September2016;- Approved Flight Manual Supplement for COM/NAV/ GS/GPSGarminGTN650/ GTN750 for rotorcraft equipped with Thales SMD4...	With this installation the approval status of the helicopter of IFR orVFR persists.LPV, VNAV/LNAV isn't approved.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willa...	27/09/2016	Active	10059545
10059551	JJASPP ENGINEERING SERVICES, L.L.C.		FAA SR09633RC	SEE EASA APPROVED MODEL LIST	Installation of Balloon Pump Restraint System (BPRS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RFM Supplement: see EASA Approved Model Listor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.- Installation Instructi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/09/2016	Active	10059551
10059561	AEROTEC & CONCEPT			B200GT	Antenna installation provision for mission system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Data List, doc. no. AE16140PCDP Rev. 0, dated 26 September 2016or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/09/2016	Active	10059561
10059562	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			525, 525A	Installation provisions of Apple IPAD Air Series (single/Dual).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to Master Document List 2015-8-16, Rev IRTo be operated in accordance with AFM-S Document No. 2015-8-8, Rev Aor later revisions of the above listed documents approved byEASA.To be installed i.a.w. Installation Procedure 2015-8-1, Rev IR, or laterRevisionsTo be maintained i.a.w. MM-S 2015-...	Operational approval to use as EFB class 2 separate needed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of t...	28/09/2016	Active	10059562

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059563	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			525, 525A	Installation of Power FLARM Core.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to Master Document List 2015-10-16, Rev IRTo be operated in accordance with AFM-S Document No. 2015-10-8, RevAor later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Procedure 2015-10-1, Rev IR, orlater RevisionsTo be maintained i.a.w. MM-S 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/09/2016	Active	10059563
10059567	LUFTHANSA TECHNIK AG	REV. 1		737-700	Ka-Band SatCom Antenna Provisions.Rev1: increased ALI intervals.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Doc STDD53-15/20M issue 02- AFM Supplement A-00-16/56-AFM Issue 03- ICA Doc A-00-16/56-ICA Issue 04- MPD Supplement A-00-16/56-MPD Issue 02or later revisions of the above listed documents approved by EASA.	Due to a relocation of the GPS antennae on top of the fuselage, theaircraft has lost its approval for all GNSS Landing System (GLS)functions.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design...	02/02/2017	Active	10059567
10059600	FLYING COLOURS CORP.		TCCA C-LSA14-210/D ISSUE 1	CL-600-2B16	Installation<(>,<)> Cabin Reconfiguration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EMTEQ Canada Ltd. Airplane Flight Manual Supplement No. J946090 Rev NC.Flying Colours Corp. Instructions for Continued Airworthiness No.J946075 Revision NCor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilatera...	Restricted to ASN 5508.	30/09/2016	Active	10059600
10059601	E A D AEROSPACE AIRWORTHINESS			A319-132, A319-133 A319-114, A319-115, A319-131 A319-111, A319-112, A319-113	Installation of KA Band Satcom radome with provisions for LRU antenna.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-0301-002 (Vibration/buffetingcompliance criteria for large external antenna installation).The requirements for environmental protection...	- Master Drawing List, EAD Aerospace document No. 01486-EAS-A-MDL,Revision D, dated 30 September 2016- Instructions forContinued Airworthiness Supplement, EAD Aerospacedocument No. 01486-EAS-A-ICA-01, Revision C, dated 30 September 2016- Aircraft Flight Manual Supplement, EAD Aerospace document No....	This modification applies only to aircraft being fitted with Sarklet.This modification applies only to aircraft fitted with SAT TV tailwindantenna, in accordance with Airbus Service Bulletin SB 53CJ014.Prior to installation of this design change it must be determined thatthe interrelationship betwee...	30/09/2016	Active	10059601
10059612	JET AVIATION AG	REV.3		A319-115	VVIP cabin interior - EASA STC Approval.The VVIP interior has been completed allowing for three convertibleconfigurations, Baseline Configuration and Option A and Option B.Revision 3: Transfer EASA STC 10059612 Rev. 2.	See appendix JBSC-M-00054CCS-01, Issue 04,,The requirementsfor environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFMS: JBSC-M-00054AFR-01-I1, Issue 01;- CCS: JBSC-M-00054CCS-01, Issue 04;- MDL: JBSC-M-00054MDL-01, Issue 07;- ICA: JBSC-M-00054ICA-01, Issue 01; JBSC-M-00054ICA-02, Issue 01;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/09/2017	Active	10059612
10059615	SAFRAN POWER USA, L.L.C.		FAA SR03288CH	AB139, AW139	Installation of starter-generator, Goodrich P/N 23078-029 andQuick-Attach-Detach (QAD) kit P/N 23078-500.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Goodrich drawing 23078-029, revision D, dated July 29, 2013<(>,<) >Goodrich drawing 23078-500, revision A, dated December 12, 2013or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/10/2016	Active	10059615

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059617	EAGLE COPTERS USA, INC.		FAA SR00425SE	SEE EASA APPROVED MODEL LIST	Installation of a satellite phone.	See EASA Approved Model List.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	See EASA Approved Model Listor later revisions of the abovelisted documents approved by EASA inaccordance with EASA EDDecision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/ USABilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/10/2016	Active	10059617
10059622	I.S.E.I INTERNATIONAL SERVICESELECTRONIQUE INFORMATIQUE			DA42, DA42M	Installation of SAFETYPLANE V5 systemInstallation of the Flight Data Monitoring and Transmitting System"SAFETYPLANE V5"system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 (HIRF), CRI F-03 (IEL), CRI F-16 (LiPo).The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	AEROPLANE FLIGHT MANUAL SUPPLEMENT: N11-DA42_SPV5-E-A-01 Rev.0or later revisions of the above listed documents approvedby EASA.,,- LIST OF DOCUMENTS: N10-DA42_SPV5-E-A-03 Rev. 03- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS: N8-DA42_SPV5-E-A-01 Rev. 01- COMPLIANCE DECLARATION: N9-DA42_SPV5-E-A-02 Rev....	For aircraft equipped with "Thielert" engines.Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	04/10/2016	Active	10059622
10059623	AVMAX AVIATION SERVICES Inc.	REV. 1	TCCA SA00-55	DHC-8-315 DHC-8-311, DHC-8-314 DHC-8-202, DHC-8-301 DHC-8-106, DHC-8-201 DHC-8-102, DHC-8-103	GPS/SATCOM Antenna Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Top Document List, Doc. No. 68941-400, Rev. 16- Engineering Order, Doc. No. 68941-401, Rev. 15- Maintenance Program Manual Supplement, Doc. No. 68941-701, Rev. 4or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ Canada...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/10/2016	Active	10059623
10059646	LUFTHANSA TECHNIK AG	REV. 1		737-700	Cabin Interior CompletionRevision 1: Smoke Detector Replacement. The design change introducesduct smoke detector P/N GMC1103-02 as an eligible replacement part forthe currently installed and discontinued P/N GMC1102-02	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-101 Isolated compartments issue; D-118 Glassscreens of displays/monitors issue 1; F-108 Network security issuethe following paragraph(...	Supplemental Type Design Definition STDD00-15/21M Issue 02 Rev. 0Instructions for Continued Airworthiness A-00-16/48-ICA Issue 04 rev 02AFM Supplement A-00-16/48-AFM Issue 04or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/08/2025	Active	10059646
10059649	VECTOR AEROSPACE INTERNATIONAL LIMI		CAA UK RESPONSIBILITY	AS 332 L	Mission System Fit (VAIL Project 160).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Flight Manual Supplement 160-20-02 “Vector Aerospace Modifications”,Release A.Flight Manual Supplement 160-23-08 “FLEXCOMM II V/UHF RadioCommunication System”, Release A,,or laterrevisions of the above listed documents approved by EASA.Master Data List 160RPT128 Release A, dated 07.09.2016.Change L...	This STC is applicable to helicopter AS 332L S/N 2046 only.This STC provides for access to stretcher attachment points in thecabin. These attachment points are for provision only and approval forinstallation of stretchers on these points is not included in this STC.Installation of stretchers or anyp...	05/10/2016	Active	10059649

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059658	PEREGRINE LLC		FAA STC ST00813DE	SEE APPROVED MODEL LIST	Replacement of Honeywell (formerly Sperry) ED-800 cathode ray tube (CRT) display, part number 7003110-90I or 7003110-902, with Esterline CMCElectronics CMA-6800 multi-purpose liquid crystal display (LCD).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	EASA AML Listor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement.E-DI-15-0001 Rev C, CMA-6800 Multi-Purpose Liquid Cryst...	None.	06/10/2016	Active	10059658
10059660	MID-CONTINENT INSTRUMENT Co., Inc.		FAA STC SA02075SE	SEE EASA APPROVED MODEL LIST	Installation of Mid-Continent lithium battery in accordancewith MasterData List AM0229-DL02-00	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):SC-F23.1353-02 (as per CRI F-58)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origin...	MDL AM0229-DL02-00, Rev. A dated 21-Feb-2013AFMS AM0229-FM01-00, Rev. A dated 21-Feb-2013ICA AM0229-IC01-00, Rev. A, dated 10-Jan-2013or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the...	The STC is only applicable to aircraft with an existing EASA-approvedinstallation of anL-3 Communications PS-835( ), PS-850( ), or PS-855( ) emergency powersupply.The MD835-1 replaces a PS-835A/ B/C/D/G on aircraft not wired for an L-3SI-100( ) module (static inverter) or an SC-841( ) module (5V adju...	06/10/2016	Active	10059660
10059663	EMBRAER ENGINEERING & TECHNOLOGYCE NTER USA, INC.	REV. 1	FAA STC ST0321CE-A	EMB-500	Installation of L3 Communication Skywatch HP (TCAS I).This STC was originally issued as a validation of Brazilian CST (STC)No. 2008S12-13 (26 December 2008) and transferred to a United Statesbased Design Approval Holder (DAH) on 22 July 2019.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List Number TR0127, Revision L, dated 17 December2018.- Airplane Flight Manual Supplement (AFMS), Document Number ST0321CE-A,Revision IR, dated 1 June 2009.- Instructions for Continued Airworthiness (ICA), Document NumberICA-002, Revision B, dated 21 September 2017or later revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/11/2019	Active	10059663
10059675	SABENA TECHNICS BGC	REV. 1		ATR 72-212, ATR 72-212A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	GPS/SBAS antennas structural installation on ATR42 and ATR72Rev 1 : include the configuration of the aircraft fitted with secondGNSS antenna.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Applicable regulations at CS 25 Amendment 4 (referto associatedCertification Plan 0826-01-A-CP-R02, section 6& 7, for details)The requirements for environmental protecti...	Master Data List, ref: 0826-01-A-MDL-R01;Instructions for Continued Airworthiness (Supplement), ref:0826-01-A-ICA-R01;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/03/2017	Active	10059675
10059692	J & C ENGINEERING SERVICES Ltd.	REV. 1	CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	Major change to STC 10059692(XCAM Installation on StarboardWing Strut) to permit alternative PortWing Strut XCAM pod installation and extension of applicable 172 typeson which installation of XCAM can be permitted	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements of CS-23Amdt 4:23.25; 23.29; 23.45; 23.49; 23.63; 23.65; 23.69; 23.71; 23.73; 23.75;23.77; 23.141; 23.143; 23.145; 23.147; 23.151; 23.153; 23.157; 23.161;23.177; 23.181; 2...	J<(>&<)>C Engineering Services Ltd., Flight Manual SupplementJC/FMS/4584 Issue 1.1 dated 2005-19 covers both original Starboard wingstrut only installation of XCAM pod and includes updates to addressalternate port strut installation of XCAM Pod plus wider Cessna 172 typeapplicability of this STC;orJ...	Original XCAM installation on starboard wing strut was approved underEASA STC 10059692 – this major change permits alternative installationof XCAM pod on port wing strut in lieu of starboard installation, (notethat dual installation of XCAM on both port and starboard wing strutssimultaneously is not...	14/08/2019	Active	10059692

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059693	AVMAX AVIATION SERVICES Inc.			DHC-8-311/ DHC-8-314/ DHC-8-315 DHC-8-201/ DHC-8-202/ DHC-8-301 DHC-8-102/ DHC-8-103/ DHC-8-106	FLYHT AFIRS 228 Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Flight Manual Supplement CE322-801, Issue B dtd. 02 August 2016or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Maintenance Manual Supplement CE322-701, Issue A dtd. 12 November 2015.Certifica...	This system is not eligible for an operational approval forLong RangeCommunication Systems (LRCS).EASA STC 10059623, Rev. 1 or later must be accomplished together withthis STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change andp...	07/10/2016	Active	10059693
10059694	STG AEROSPACE GERMANY GmbH	REV. 1		ERJ 190-100, ERJ 190-200 ERJ 170-100, ERJ 170-200	SuperSeal UltraLite (SSUL) PHOTOLUMINESCENT AISLE PATH MARKING SYSTEM.EMBRAER SERIES AIRCRAFT.Revision 1: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 AMENDMENT 18:25.1(a); 25.25(a)(b); 25.27; 25.301; 25.303; 25.305; 25.307;25.561(a)(b)(3)(c); 25.581; 25.601; 25.603;2...	- STG AEROSPACE LTD AEROPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1009-FMS-01Revision IR- STG AEROSPACE LTD INSTRUCTIONS FOR CONTINUED AIRWORTHINESS No.SG-1009-ICA-01 Revision IROr later revisions of the above listed document(s) approved/ acceptedunder the EASA system.STG AEROSPACE LTD MASTER DATA LIST N...	SSUL Green Emitting Photoluminescent insert shall not be mixed with SSULBlue Emitting Photoluminescent insert on the same aircraft installation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed cha...	12/02/2021	Active	10059694
10059706	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			B200 SERIES (B200, B200C, B200CGT, B200GT)	Installation of Universal UNS-1D FMS with P-RNAV capability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Cessna Dusseldorf Citation ServiceCentre GmbH Master Document List ref 2016-13-16, Rev IR, dated 21 April2016, and Engineering Order ref 2016-13 Rev IR, dated 21 April 2016.Operate in accordance with Cessna Dusseldorf Citation Service CentreGmbH Aircraft Flight Manual...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/10/2016	Active	10059706
10059728	ROCKY MOUNTAIN AIRCRAFT		TCCA SA15-44	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Fuel Quantity Indicating System Replacement	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:FAR 23, Amdt. 0: 23.29, 23.301, 23.303, 23.305, 23.307, 23.601, 23.603,23.605, 23.611, 23.613, 23.615;FAR 23, Amdt. 20: 23....	- Engineering Data Summary E110300, Rev. A<(>,<)>- Modification Instruction E110310, Rev B.or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.- Maintenance Manual Supplement, E110331, Rev A- Ins...	Installation of EASA STC 10047440 (TCCA STC SA12-13) is required.Prior to installation of this design change it must bedetermined thatthe interrelationship between this design change and any otherpreviously installed design change and/ orrepair will introduce noadverse effect upon the airworthines...	11/10/2016	Active	10059728
10059748	ACORN WELDING Ltd.	REV. 1	TCCA SA02-97	185E, A185E, A185F 185, 185A, 185B, 185C, 185D 182Q, 182R 182K, 182L, 182M, 182N, 182P 182E, 182F, 182G, 182H, 182J 182, 182A, 182B, 182C, 182D 180H, 180J, 180K 180C, 180D, 180E, 180F, 180G	Replacement Engine Mount Installation in accordance with ModificationData Summary MDS323411, revision 02, dated 5 October 2011.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Data Summary MDS323411, revision 02, dated 5 October 2011;or later revisions of the above listed documentsapproved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.MaintenanceManual Supplement: Replacement Engine Mount MMS400, revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2017	Active	10059748

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059751	ASI INNOVATION			DA 42 M-NG	ASI-FAM-0270-01 dated 12 September 2016 - DA42 Radome installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement ASI-AFM-0270 Issue 02 dated September2016or later revisions of the above listed documents approved by EASA.	Limitation to Diamond DA42M-NG serial number 007.	12/10/2016	Active	10059751
10059756	AEROTEC GROUP S.A.S.transferred to 309218 with 707360			MBB-BK 117 C-2	Installation of Removable Protection Kit P/N BLI-145-01 including floorplates and seats shields.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	ATG-MV-BLI-145-01 Rev 01 “BLI-145-01 Flight Manual Supplement”, dated11/10/2016.ALS as defined in Chapter 09 of “User’sManual” ATG-DTU-BLI-145-01 Rev.02, dated 12/10/2016or laterrevisions of the above listed documents approved by EASA.ATG-DCAD-BLI-145-01 Rev. 03 “Declaration of Conformity and Com...	None.	12/10/2016	Active	10059756
10059760	DART AEROSPACE Ltd.		FAA STC SH15-44 ISSUE 1	206L/ 206L-1/206L-3/206L-4/407	Installation of air filter D407-1007-011 PA110 PUREair System at engineintake.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Flight Manual Supplement FMS-D407-1007 Rev. B, dated 05/10/2016or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Installation Instructions IIN-D407-1007 Revision C, dated September 29,2015 or l...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/10/2016	Active	10059760
10059765	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	757-200, 757-300	STC Twenty One Change S21.34-15-1160 - Introduction of ADS-B Out	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement - S21.FMS-0113 Issue 1or later revisions of the above listed documents approved by EASA.Master Document List - S21.MDL-1153 Issue 2.	None	13/10/2016	Active	10059765
10059766	365 AEROSPACE DDS LIMITED	REV. 1		CL-600-1A11/ -2A12/ -2B16	Change for the introduction of Satellite Communications System (SATCOM)and Cabin Local Area Network (WI-FI).Rev. 1: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	365 Aerospace Ltd Flight Manual Supplement No.1 FMS-0074-001 REVISION A.365 Aerospace Ltd Instructions for Continued Airworthiness ICA-0074-001Issue 3or later revisions of the above listed document(s) approved/acceptedunder the EASA system.365 Aerospace Ltd MDL-0074 Revision A dated 12 October 2016....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/08/2019	Active	10059766
10059775	DELTA ENGINEERING CORPORATION		FAA STC ST02908NY	737-700/-800/-900ER	Installation of a Panasonic Global Communication System (GCS)This modification installs the Panasonic GCS with the functionalitieseXConnect (internet access) and Cell Modem (ground maintenanceconnection).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List 0106-07787-2294 Revision O, dated 21 October 2015-Aircraft Flight Manual Supplement, ref: 0606-07792-2294 Revision C,dated 24 September 2015-Instruction for Continued Airworthiness, ref: 0706-07793-2294 RevisionL, dated 30 November 2015or later revisions of the above listed documen...	None	14/10/2016	Active	10059775

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059777	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH	REV. 2		EC635 P2+, EC635 T1, EC635 T2+ EC135 T1, EC135 T2, EC135 T2+ EC135 P1, EC135 P2, EC135 P2+	Installation of HD ELECTO OPTICAL SYSTEM (EOS) on EC135 (H135)Initial Rev.: Introduction of EOS of type FLIR Star SAFIRE 380-HD andFLIR Star SAFIRE 380-HDc on Standard Landing GearRev. 1: Extension to use High Landing Gear for EOS of type FLIR StarSAFIRE 380-HDcRev. 2: Introduction of EOS of type He...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement 00026-DO-MZ-FMS-00, Issue 03- Instruction for Continued Airworthiness 00026-DO-MZ-ICA-00, Issue 03- For Initial Rev.: List of Compliance Documents, 00026-DO-MZ-LCD-00,Issue 01- For Rev. 1: List of Compliance Documents, 00035-DO-MZ-LCD-00, Issue 01- For Rev. 2: L...	- Prerequisite for this STC is the installation of the Utility Step asper EASA STC 10017058 (EASA.IM.R.S.01490)- Class 3B and 4 laser operation is not EASA approved. The laser isdisabled.- Installation of EOS FLIR Star SAFIRE 380-HD and FLIR Star SAFIRE380-HDc applicable to EC135 models equipped wit...	04/06/2019	Active	10059777
10059778	PRECISE FLIGHT, Inc.		FAA STC 00733SE	DHC-8-400 SERIES DHC-8-300 SERIES DHC-8-200 SERIES DHC-8-100 SERIES	Installation of Precise Flight Pulselite System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Precise Flight, Inc. Engineering drawings 251P0000, Revision A, datedMay 25, 2001, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement for deHavilland Dash8-100 Series through -400 series, dated May 31, 2001, or later FAAapproved revision.	Approval of this change in type design applies to the abovemodelaircraft only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	14/10/2016	Active	10059778
10059779	TRUATLANTIC MFG., LLC		FAA STC SA02422AT-D	T210K,T210L,T210M,T210N 210K,210L,210M,210N	Installation of a Stainless Steel Exhaust System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Atlantic Aero, Inc. Master Drawing List 20993001, Rev. E,datedNovember 20, 2006or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilat...	1. The following models are eligible for installation of this STC:a. 210K, L, M, N, Serial Numbers 21059200 through 21064897 with theTeledyne Continental Motors (TCM) IO-520-L engine; or thoseincorporating STC's which install the IO-550-P engine.b. T210K, L, M, N, Serial Numbers 21059200 through 210...	14/10/2016	Active	10059779
10059783	INTELSAT INFLIGHT LLC	REV. 1	FAA STC ST04370NY	747-400	Installation of Gogo 2KU – Structural and Electrical Provisions	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Ltd Aeroplane Flight Manual Supplement S21.FMS-0134 Issue1STC Twenty One Ltd Instructions for Continued Airworthiness S21.TEC-0522Issue 1<(>,<)> Appendix A<(>,<)> Section 3 – Airworthiness Limitationsor later revisions of the above listed documents approved by EASA.STC Twenty One Ltd...	This design change comprises of two installation configurations.Approval is granted for independent installation of these configurationsprovided that: --Configuration A, as defined in S21.MDL-1330 (Configuration A), is fullyinstalled in accordance with Accomplishment Instructions S21.ACC- 0617.-Conf...	28/01/2020	Active	10059783
10059784	AIRBORNE TECHNOLOGIES GmbH	REV. 1		182S, 182T, T182T	STC-AT-068-RevA - ADAM Cessna Pod.This minor change is a revision of the already certified STC-AT-068,10059784.This minor change covers the installation of an additional switch inthecockpit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs of CS-23 Amendment 3 are applicable to thischange: 23.1; 23.3; 23.21; 23.23; 23.29; 23.45; 23.49; 23.51; 23.53;23.63; 23.65; 23.69; 23.71; 23.73;2...	AFM-STC-AT-068, Revision 5, dated 28-FEB-2017, Airplane Flight ManualSupplement<(>,<)>or later revisions of the above listed documents approved by EASA.STC-AT-068, Revision 6, dated 16-Mar-2017, ADAM Cessna Pod, ApplicableDocuments and documents listed in chaptes 7 and 8.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/09/2017	Active	10059784

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059799	STG AEROSPACE GERMANY GmbH	REV. 4		SEE EASA APPROVED MODEL LIST	saf-Tglo® PHOTOLUMINESCENT AISLE PATH MARKING SYSTEMS BOEING SERIESAIRCRAFT.Rev. 3 includes B737-9 (Max) series aircraft.Revision 4: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 AMENDMENT 17Requirements: 25.1(a); 25.25 (a)(b); 25.27; 25.301; 25.303; 25.305;25.307; 25.561(a)(b)(c); 25.581; 25.601...	STG AEROSPACE LTD AEROPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1007-FMS-01Revision D;STG AEROSPACE LTD INSTRUCTIONS FOR CONTINUED AIRWORTHINESS No.SG-1007-ICA-01 Revision E;STG AEROSPACE LTD Cabin Crew Data Supplement No. 1007-CCD-01 RevisionD;STG AEROSPACE LTD MMEL Supplement No. SG-1007-MMEL-01 Revi...	SSUL Green Emitting Photoluminescent insert shall not be mixed with SSULBlue Emitting Photoluminescent insert on the same aircraft installation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed des...	12/02/2021	Active	10059799
10059804	SCANDINAVIAN AVIONICS DESIGN ApS			767-300BCF, 767-400ER 767-200, 767-300, 767-300F	Provision For Dual Portable Electronic Flight Bag (EFB) in a Boeing 767Series Aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:AMC 20-25 Airworthiness and operational consideration for ElectronicFlight Bags (EFBs).EWIS: Applied i.a.w. (generic) SC/CRI H-01 and AC25-27A.CS 25.1, CS 25.29, CS 25.301...	Doc ref: 2099680-EO Engineering Order & Certification ProgramDoc ref: 2099680-AM Flight Manual SupplementDoc ref: 2099680-COR Compliance ChecklistDoc ref: 2099680- CA Continued Airworthinessor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/10/2016	Active	10059804
10059818	BELL HELICOPTER TEXTRON, Inc.		FAA STC SH8477SW	412, 412EP 212	Installation of a four place utility seat configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Premier Aviation, Inc., Master Drawing List 000-13000, Revision E,dated 23 July 1993 or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/10/2016	Active	10059818
10059819	BELL HELICOPTER TEXTRON, Inc.		FAA STC SH8478SW	412, 412EP 212	Installation of a five place utility seat configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Premier Aviation, Inc., Master Drawing List 000-13001, Revision E,dated 23 July 1993 or later FAAapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/10/2016	Active	10059819
10059820	BELL HELICOPTER TEXTRON, Inc.		FAA STC SH8479SW	412, 412EP 212	Installation of side facing utility seat configuration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Premier Aviation, Inc. Master Drawing List 000-13002, Revision E,dated 23 July 1993 or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/10/2016	Active	10059820
10059850	FOKKER SERVICES B.V.			ATR 42-500/ ATR 72-212 A	Introduction of several cabin layout configurations with Lifeportmedevac litter system(s) installed.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forSpecial Condition (s):CRI D-01 / 10038042 “Installation of medevac systems”.The requirements for environmental protection and the associatedcertified noise and/ or emiss...	Compliance Record Report CRR-0269 Issue 1 dated 9/26/2016.AFM Supplement ATR4-STT-AFM-S-001 Revision 1 dated 15/09/2016andATR7-STT-AFM-S-002 Revision 1 dated 15/09/2016.Maintenance Recommendations Supplement per Fokker Report SE-806or later revisions of the above listed documents approved by EASA.I...	Per AFM Supplement ATR4-STT-AFM-S-001 Revision 1 dated 15/09/2016 andATR7-STT-AFM-S-002 Revision 1 dated 15/09/2016.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair wi...	21/10/2016	Active	10059850

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059855	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 1		G00-00-000	Installation of ISEI HELICOM V2+ NUM data recorder.Rev. 1: STC holder name change from I.S.E.I International Services toSAFRAN ELECTRONICS & DEFENSE BUSINESS UNIT - HELICOPTERS DATA MANAGEMENTSOLUTIONS & SERVICES.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Lithium Battery Installations - CRI-F01.The requirements for environmental protection and the associatedcertified noise and/or emissions levels ofu...	RFM supplement ref. N11-CABRI G2 HV2+ NUM-E-A-01-Rev.01 dated 26September 2016<(>,<) >or later revisions of the above listed documents approved by EASA.- STC data list ref. N10-CABRI G2 HV2+ NUM-E-A-02 dated 26 September2016;- Instructions for Continued Airworthiness ref. N8-CABRI G2 HV2+NUM-E-A-01 d...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	27/02/2020	Active	10059855
10059871	SWS CERTIFICATION SERVICES Ltd.	REV. 1	CAA UK RESPONSIBILITY	A350-941	Airbus A350-900 for China Airlines – SkycouchTM Installation Redesign.Rev. 1: Redesign removing need for the CRI ESF CRI D-2338-001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- MASTER CONFIGURATION SCHEME, reference 3167-MCS-01 Issue 1 dated 12September 2017;- CERTIFICATION PROGRAMME, reference 3167-CEP-01 at Issue 1 dated 16August 2017;- COMPLIANCE REPORT, reference 3167-COM-01 at Issue 1 dated 12 September2017;- FLIGHT MANUAL SUPPLEMENT, reference 3144-FMS-01 at IssueA...	The redesign approved by this STC terminates the need for the CRI ESFCRI D-2338-001 which will be cancelled. All aircraft fitted with theoriginal STC 10059871 must be retrofitted to the new design as approvedthrough this certificate. The STC 10059871 will be considered revoked.Prior to installationt...	13/09/2017	Active	10059871
10059875	RUAG AG	REV. 1		F2000/ F2000EX F2000 / F2000EX	F2000 ADS-B Out.Removed: Rockwell Collins TDR-94D (p/n 622-9210-008 or later)A/C/S/EHS/ELS Transponder.Installed: Rockwell Collins TDR-94D (p/n 622-9210-501)A/C/S/EHS/ELS/ADSB Transponder.ADS-B Fail Indicators. ADS-B Inhibit Indicator (Optional).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-ACNS.D.ADSB 001,010, 020, 025, 030, 035, 040, 045, 050, 055, 060, 070, 080, 085, 090,100, 105, 110, 115, 120.The requir...	-Flight Manual Supplement Doc. No. FMS-610696, Rev. A-Master Document List: Doc. No. MDL-8003618, Rev. A-Engineering Order: Doc. No. EO-8002646, Rev. B-Instructions for Continued Airworthiness: Doc. No. ICA-8003623, Rev. A.or later revisions of the above listed document(s) approved/acceptedunder the...	This STC is applicable to Falcon 2000 aircraft with:- Proline 21 Cockpit- Dual GPS-4000s GPS receivers (822-2189-010)- Dual TDR94D Transponders (622-920-008 or later)- ImplementedDassault Service Bulletin No. 312 (ATC with EnhancedSurveillance) Prior to installation of this change/repair it must bet...	02/02/2021	Active	10059875
10059876	AIR PLAINS SERVICES, CORPORATION		FAA STC SA00422WI	210R 210E, F, G, H, K, L, M, N	Installation of McCauley Propeller Model D3A34C402/90DFA -8, -10 andassociated changes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	C S Industries Installation Instructions No. 402A, Rev. - ,dated April19, 1996.	For Models listed above, the installation of McCauley D3A34C40290DFA-( )propeller is limited to not over 82 inches and not under 78 inchesdiameter range with no operating restriction placard for use withIO-520-A, 10-520-J and IO-520-L engines, and for approved IO-550-Lengine on Models 210K, L, M, NP...	26/10/2016	Active	10059876
10059881	GARMIN INTERNATIONAL, Inc.		FAA STC SA02018SE-D	SEE FAA AML	Provisions installation of Garmin GPS/XM Antennas.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. FAA Approved Model List (AML) SA02018SE-D, dated January4, 2011 orlater FAA approved revision.2. FAA Approved GPS/XM Antenna STC Master Drawing List, Document No.: 005-00638-01, Revision "1", approved on January 4, 2011, or later FAAapproved revision.	Aircraft modified by this STC must be maintained in accordance with theInstructions for Continued Airworthiness (ICA) listed in the MDLidentified above.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously insta...	26/10/2016	Active	10059881

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059904	AVMAX AVIATION SERVICES Inc.			CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700/701/702) CL-600-2B19 (RJ SERIES 100)	Transponder Upgrade for ADS-B Out.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:FAR 25 Amendment 25-1 to 25-98.FAR 26.11 and 26.47 Amendment 26-0 CS ACNS subpart D<(>,<)> Appendix J.The requirements f...	Avmax Flight Manual Supplement CE312-801 issue Cor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Avmax Master Data List CE312-900 issue B.	None.	27/10/2016	Active	10059904
10059913	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		LEARJET MODEL 45	Learjet 45 - Honeywell DU-875 or DU-875AF MFD InstallationRev. 2: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	According to ATL Master Document List MDL-13144-00001 Issue10To be operated in accordance with ATL AFM-S 13144-AFM-00001 Issue 3 or13144-AFM-00002 Issue 3 for the DU-875AF installationTo be installed iaw. ATL MOD-13144-0001 Issue 5 or MOD-13144-00002 Issue1To be maintained iaw. ATL AMMS 13144-DAN-0...	DU-875 direct display replacement, no new functionalitiesFor DU-875AF SVS and MFD Video function not includedAny changeor removal of limitation will require a further MC approvalPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair an...	10/11/2021	Active	10059913
10059915	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04268AT	767-300 SERIES	Interior Reconfiguration of a Boeing 767-300 Series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TIMCO Aerosystems, LLC Master Data List 16T018L001, revision IR, dated29 October, 2016, or later FAA approved revisions.TIMCO Aerosystems, LLC Instructions for Continued Airworthiness16T018R009, Rev. IR dated 31 August 2016, or later FAA acceptedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The seat installation for which seat track provi...	31/10/2016	Active	10059915
10059921	AVIONIK STRAUBING ENTWICKLUNGS GmbH			EA 400, EA 400-500	Installation of Antennas for Avidyne TAS System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23, Amdt. 4 - 301,303, 305, 307, 365, 561, 573, 575, 603, 605, 607, 609, 611, 613, 625,843, 867, 1301, 1306, 1308, 1309...	-,,Certification Program and Declaration of ComplianceASR-2016-038-CEP-03-00, Rev. 00-,,Project Description ASR-2016-038-PRD-04-00, Rev. 00-,,Instructions for Installation ASR-2016-038-IFI-10-00, Rev. 00-,,Instructions for Continued Airworthiness ASR-2016-038-ICA-11-00, Rev.00.	Final compliance demonstration must be provided in the frame of theinstallation approval for the equipment which is to be served by thehere installed antennas.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviousl...	02/11/2016	Active	10059921
10059923	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED	REV. 1	CAA UK RESPONSIBILITY	EC135 T3 EC135 T2+ EC135 T2	Dual Garmin GTN750 Installation, EC135Note 1: STC 10059923 Original Issue is applicable to EC135 T2 and EC135T2+ onlyNote 2: STC 10059923 Revision 1 extends applicability to EC 135 T3	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27 Amdt 3CS 27 Amdt 3 Appendix. ACS 27 Amdt 3 Appendix. CCS-ACNS.B.VCS. 020/ ACNS.B.VCS.025/ ACNS.B.VCS.030The requirements for environmental protection and the associat...	Flight Manual Supplement FMS/128-002, Issue 3, dated 27 June 2017or later revisions of the above listed documents approved by EASA.-Design Report DR128-001, Issue 6, dated 12 July2017-Compliance Checklist CCL/128-003 Issue 3, dated 16 March 2017-Compliance Checklist CCL/128-004 Issue 2, dated 3 Aug...	Limited to helicopters with CPDS cockpit variantPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	18/08/2017	Active	10059923

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10059927	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			767-300	B767-300 Tapestry Mood Light integration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Engineering Order, Document Number EO_M154001104_MGR_27072016, Rev. 0.Instructions for Continued Airworthiness, Document NumberICA_M154001104_MGR_27072016, Rev. 1.Crew OperationalManual Supplement, Document NumberCOMS_M154001104_MGR_27072016, Rev. 0or later revisions of the above listed documents a...	EASA STC 10046873 for installation of the NuLook® Cabin interior, EASASTC for installation of the Lufthansa Technik Self-Illuminated FloorPath Marking System EASA STC Number: EASA.A.S.01333 and STC ST15213AT-T (EASA Project Number 300009050) HAECO Cabin Monument configuration andSeat Track installati...	02/11/2016	Active	10059927
10059931	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	REV. 2		MBB-BK117 D-3M MBB-BK117 D-3 MBB-BK117 D-2 MBB-BK 117 D-2	Installation of BAE Multiple-place Utility Troop Seating System P/N119900-(XX).Revision 1 grants approval for the installation of a modifiedThree-Place Aft-Facing Seating configuration and addresses compliancewith CS 29.1 e), where applicable.Revision 2 grants approval for the installation of an add...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI D-04 “Passenger emergency exits”Closed at Issue 9, dated 20.08.2020The requirements for environmental protection and the associatedcertif...	BK117 D-2m (Helionix Step 2) RFM Supplement SK-MAC-172-SUP-R-1192 Rev D;BK117 D-3 / D-3m RFM Supplement SK-MAC-172-SUP-R-2107 Rev A;Customization Manual SK-MAC-172-CM-R-1191 Rev D;Certification Program SK-MAC-172-CP-R-1182-F dated 03.07.2020;Compliance Report SK-MAC-172-CRP-R-1193-D dated 18.09.2020...	Only applicable to MBB-BK117 D-2m variant and MBB-BK117 D-3/D-3mrotorcraft models.The Maximum Passenger Seating Capacity of a rotorcraft modified by thisSTC is increased to eleven. Refer to RFM SupplementSK-MAC-172-SUP-R-1192 Rev D or RFM Supplement SK-MAC-172-SUP-R-2107 RevA, as applicable, or late...	13/10/2020	Active	10059931
10059937	JAMCO AMERICA, INC.		FAA STC ST01110SE	777-200 SERIES	Installation of new business class seats, installation of previouslyapproved video monitors and relocation of emergencyequipment in BoeingModel 777-200 series airplanes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	JAMCO America, Inc. Master Drawing list (MDL) No. IA-076MDL, Revision A,dated July 2, 2002, or later Federal Aviation Administration approvedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/11/2016	Active	10059937
10059941	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA2151NM	551 (CITATION II) 501 (CITATION I)	Rosen Sunvisor System – monorail mounted cockpit sunvisor	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cockpit Sunvisor installation iaw. FAA approved Rosen Drawing List No.R500S-00DLor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bilatera...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/11/2016	Active	10059941
10059944	AVIONITEC Ltd.			414A	Avionics Upgrade:- Installation Audiopanel PS Engineering PMA 8000C- Installation of a NAV/COM 3 System King KX 165A- Replacing Mode S XPDR by a Garmin GTX 330- Replacing Weather Radar System by a GWX 68- Installation L-3 TAS System Sky 497 System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23/0 for:23.301 / 23.561 / 23.1301 / 23.1309 / 23.1321 / 23.1325 / 23.1327 / 23.1351 / 23.1357 / 23.1359 / 23.1365 / 23.1381/ 23.1431 / 23.1529 /23.1541 / 23.1581The req...	- AFMS, Doc. No. 1289-011, Original Issue, dated 19.07.2013or later revisions of the above listed documents approved byEASA.- Master Data List, Doc. No. 1289-017, Revision 0, dated 19.07.2013- ICA, Doc. No. 1289-015, Revision 19.07.2013	STC applicable for MSN 414-0360, HB-LSX onlyPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	04/11/2016	Active	10059944

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060000	EIRTECH AVIATION SERVICES LIMITED	REV. 3		737-800 737-700, 737-800, 737-8	737 Zero Passenger LOPARev. 1: 737-700 Model added to the applicability list.Rev. 2: 737-8 Model added to the applicability list.Rev. 3: Correction of Associated Technical Documentation part.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 Amdt 18:25.1 (a), 25.29(b), 25.601, 25.603(a)(b)(c),25.785(a)(b)(c)(d)(e)(f)(g)(h)(i)(j), 25.787(a)(b)...	- Master Document list referenced MDL/882-099 Issue 34 dated 15Th JAN2024- Flight Manual Supplement referenced FMS/882-016 Issue 2 dated 15th JAN2024 (Applicable to B737-8)- Maintenance Manual Supplement referenced MMS/882-014 dated 24th NOV2023 (Applicable to B737-8)- Flight Manual Supplement refer...	The applicability of this STC is limited to the pre-configurations andaircraft MSNs identified under the documents ref.DR/882-001 (section15) applicable to B737-700/-800 or ref. DR/882-002 (section 15)applicable to B737-8. This STC applicability can be extended to otheraircraft MSN under the minort...	17/01/2024	Active	10060000
10060001	FLIGHTSTAR CORPORATION		FAA STC ST04064CH	LEARJET MODEL 45	Installation of Automatic Dependent Surveillance – Broadcast (ADS-B) Outsystem.	The Certification Basis (CB) for the original product remains applicableto this certificate/approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/approval.	Flightstar Corporation Master Data List Doc. No. 45-001-002, Revision H,dated April 12, 2016, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.1. The aircraft must be maintained in accordance...	10/11/2016	Active	10060001
10060002	BOGGI AERONAUTICS S.R.L.	REV. 1		412, 412EP	Trakkabeam® A800 Searchlight System PAL/CP/1280 as described in PhoenixAerospace Limited Report PAL/CEA/1280.Rev.1: STCtransferred to Boggi Aeronautics S.r.l.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Flight Manual Supplement Document PAL/FMS/B412/102 Rev. C- Master Document List PAL/MDL/1280 Rev. E.- Certification Plan PAL/CPL/1280 Rev. E- Compliance Record PAL/CPR/1280, Rev. C.- Instruction for Continued Airworthiness PAL/ICA/1280/001 Rev. C- Change Embodiment and Approval PAL/CEA/1280 Rev. E...	MAXIMUM AIRSPEED WITH A800 SEARCHLIGHT INSTALLED IS LIMITEDTO 113 KIASOR VNE WHICHEVER IS LESS.OPERATION OF THE A800 SEARCHLIGHT IS PROHIBITED IN IFR CONDITIONS.DO NOT USE THE A800 SEARCHLIGHT BELOW 50FT AGL OR IN FOG OR CLOUDCONDITIONS.DO NOT USE THE A800 SEARCHLIGHT IN CLOUD OR FOG CONDITIONS.DOA...	05/03/2024	Active	10060002
10060007	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST02976NY	BD-100-1A10	Installation of ADS-B Out System in the Bombardier BD-100-1A10 (CH300) aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/approval.	-FAA STC ST02976NY, dated 4th December 2015-Dassault Aircraft Services Master Data List, ref. doc.CH-300-D0030-005, Revision A, dated 4th December 2015-Airplane Flight manual Supplement, AFMS, ref. doc.CH-300-D0030-150,Revision IR, dated 4th December 2015-Certification Plan Document, ref. doc. CH-30...	This alteration requires as a prerequisite, Installation ofGlobalPositioning System (GPS) with Wide Area Augmentation System (WAAS) Capability – GPS-4000S receivers	09/11/2016	Active	10060007
10060033	ASI INNOVATION			EC135 T2+	FLIR system installation on EC135 T2+.Installation of FLIR system with Airfilm arm mount (EASASTC.IM.R.S. 01490) and an operator console.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS 27 Amdt. 3:CS 27.25, CS 27.27, CS 27.45, CS 27.141, CS 27.231, CS 27.251, CS27.301, CS 27.303, CS 27.305, CS 27.307<(...	Supplément Manuel de vol, ASI-AFM-0289, Révision 08 dated 2November2016or later revisions of the above listed documents approved by EASA.Certification Program, ASI-CP-0289, Revision 03 dated 19 October 2016.Compliance Check List, ASI-CCL-0289, Revision 10 dated 2 November 2016.SDL – STC Data List,S...	This STC is only valid for eye-safe LASER installations.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the...	10/11/2016	Active	10060033

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060036	DOA AESGLOBAL LIMITED	REV. 1		A319-111	Introduction of GoGo Vision Wireless System Affecting A319 AircraftRev 1: Transfer from AES Ltd. to new STC holder AESGlobal Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 17 (various)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged a...	Flight Manual Supplement AFMS No.75 Issue 1or later revisions of the above listed documents approved by EASA.Master Data List AES-319-3926MDL Issue 5	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/04/2021	Active	10060036
10060043	VECTOR AEROSPACE HELICOPTERSER VICES INC.		FAA SR02473AK	SEE FAA APPROVED MODEL LIST	Installation of the L-3 Communications NGT-9000R/RD and NGT-9000/D ADS-BIN/OUT system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Note: compliance with CS-ACNS has been demonstrated for this STC.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areu...	Master Drawing List, VAHS-1601-MDL, Rev. N/ C, dated May 11,2016, orlater FAA approved revision.Instructions for Continued Airworthiness< (>,<)> Document NumberVAHS-1601-ICA, Rev. B, dated May 10, 2016, or later FAAapproved/accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.1. Rotorcraft Flight Manual Supplement or Supple...	02/12/2016	Active	10060043
10060045	JET AVIATION AG, BASEL			SEE EASA APPROVED MODEL LIST	Honeywell FMS CDU upgrade to CD-830,,Replacement of dual ortriple Honeywell FMS control display unitRemoved: - Honeywell CD-800 or CD-810 or CD-815 or CD-820 ControlDisplay UnitInstalled: - Honeywell CD-830 Control Display Unit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Compliance to CS 25 Amdt 17 was shown.In particular: CS 25.301, 25.307, 25.601, 25.771, 25.773, 25.777,25.869,25.899, 25.1301, 25.1302, 25.1309, 25.1310, 25.1316, 25.1317...	- Airplane Flight Manual Supplement (Bombardier): JBSL-M-00608AFM-01,Issue 01- Airplane Flight Manual Supplement (Dassault): JBSL-M-00608AFM-02,Issue 01- Airplane Flight Manual Supplement (Embraer): JBSL-M-00608AFM-03, Issue01- Airplane Flight Manual Supplement (Gulfstream): JBSL-M-00608AFM-04,Issue...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/11/2016	Active	10060045
10060048	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-42 (CHEYENNE III) PA-42-720 (CHEYENNE IIIA) PA-42-1000 (CHEYENNE 400LS)	Installation of following antennas:-single Garmin GA 35 GPSAntenna-single Comnat CI 105-6 XPDR/DME Antenna-single Comant CI 105 XPDR/DME Antenna-single Comant CI 490-1 Iridium Antenna-single L-3 Communications NY-164 Skywatch Antenna-single Sensor Systems S72-1750-31L Traffic Antenna-single Sensor...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amdt. 4 paragraphs:23.301; 23.303; 23.305(a); 23.305(b); 23.307; 23.365(a); 23.365(b);23.365(d); 23.561(a); 23.561(b); 23.561(b); 23.571(a); 23.571(b);23.575; 23.603...	-Master Document List Doc. No. ASR-2016-006-MDL-01-00, issued07-NOV-2016-Instructions for Continued Airworthiness Doc. No.ASR-2016-006-ICA-11-00, issued 07-NOV-2016or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/11/2016	Active	10060048
10060052	COLUMBIA AVIONICS INC.	REV. 2	FAA STC ST01691WI	SEE FAA AML	Option 1Installation of Garmin GTN Series GPS/Comm/Nav Systems with optionalGarmin GDL-69/A XM Weather Data Link, GTX-33 Series Transponders andoptional Bendix/King KMR-675 MarkerBeacon Receiver, or:-Option 2Installation of Garmin GTN Series GPS/ Comm/Nav Systems with optionalTAWS A or B and/or opti...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01691WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	See FAA AML No. ST01691WI	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	30/07/2020	Active	10060052
10060053	MT-PROPELLER ENTWICKLUNG GmbH			P210N	MTV-5-1-D-C-F-R(A)/CFR210-56 propeller on Textron P210N modified as perLBA STC 0779/625b (FAA STC SA1003NE).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-36, Amendment 3 -FAR 36, Amendment 36-30.This certificate/approval involves a change to the requirements forenvironmen...	- According to MT-Propeller Master Documentation List No. E-2908, Rev 0- To be operated in accordance with MT-PropellerAFM-S Document No.E-2905, Rev 0or later revisions of the above listed documents approved by EASA.- To be installed i.a.w. Installation Instruction Doc. No. E-2906, Rev0, or later R...	According limitation section of AFM-S.Prerequisite: LBA STC0779/625b or FAA STC SA1003NEPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effe...	11/11/2016	Active	10060053

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060060	FLIGHTSTAR CORPORATION		FAA STC ST04061CH	LEARJET MODEL 45	Installation of Single UNS-1Ew with LPV Monitor Upgrade.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Flightstar Corp. Master Data List Doc. No. 45-001-001 Revision B,dated January 9, 2016, or later FAA approved revision.2. Flight Manual Supplement, Flightstar Corp. Doc. No. 45-818-001,Revision NC, approved February 8, 2016<(>,<)> or later FAA approvedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/11/2016	Active	10060060
10060063	SEGELFLUGGRUPPE ISARTAL e.V.			HK 36 TTC	Increase MTOM from 770kg to 800kg	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	-Ergänzung für das Flughandbuch des Motorseglers HK 36 TTC Serial Nr.36525 Betrieb mit mehr als 770 kg bis maximal 800 kg Fluggewicht IssueDate 10.10.2016or later revisions of theabove listed documents approved by EASA.-Zertifizierungsplan zur Erhöhung des MTOW der HK36 TTC „Dimona“ von 770kg auf 8...	This change is limited to Serial number 36525Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	14/11/2016	Active	10060063
10060067	AERODATA AG			B200GT 200	Suppression of ADS-B OUT	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-23 Amdt 423.1; 23.1322, 23.3(a); 23.1351(a) and (b); 23.25(a)(2); 23.1365;23.305; 23.1367; 23.603; 23.1501;23.773 (a); 23.1529; 23.1301(a)<(>,<)>(c) and (d); 23.1541(a)...	Installation, Operation and Maintenance according to the Master DrawingList document number MDL-A/ C-894 Rev. 2 dated 11th November 2016or later revisions of the above listed documents approved by EASA.	Applicability limited to B200/ B200GT equipped with:RockwellCollins Pro Line 21 avionicsRockwell Collins Dual TDR94/94Dtransponder installation versions withELS (Mode S Elementary Surveillance), EHS (Mode S Enhanced Surveillance)and ADS-B(Automatic Dependent Surveillance - Broadcast) capabilityacc...	14/11/2016	Active	10060067
10060070	PROTOPLANE SPECIAL MISSION AIRCRAFT			AS 350 D AS 350 B/ AS 350 B1/ AS 350 B2 AS 350 B3/ AS 350 BA/AS 350 BB	Installation of Video transmission System on AS350 series rotorcrafts.This includes a cabin rack, a cabin display mountand two antennasholders on landing skids.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	PP-079-AFM-03, Supplement to Aircraft Flight Manual, issue 03, dated14/10/2016or later revisions of the above listed documents approved by EASA.PP-079-ICA-00, Supplement to Instruction for C.A., initial issue dated08/07/2016.No ALS is identified for this change.PP-079-MDL-04, Master Data List, issue...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/11/2016	Active	10060070
10060075	TRUATLANTIC MFG., LLC		FAA STC SA00796AT	206/ 207/ 210	Installation of a dual-isolator forward engine mount system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero Modifications & Consulting, Inc. "21 094021 InstallationInstructions" Rev. C dated June 23<(>,<)> 1995, and "21094050 MasterDrawing List" Rev. C dated June 23, 1995, or later FAA approvedrevision of either document.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/11/2016	Active	10060075
10060078	SCANDINAVIAN AVIONICS DESIGN ApS			BD-100-1A10	Aviator 350 Satellite Communication System With Wireless Local AreaNetwork (WLAN) Including 3G/4G Network Functionalityfor On Ground Only.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:EWIS: Applied i.a.w. (generic) SC/CRI H-01 and AC25-27A.CS 25.1, CS 25.29, CS 25.251, CS 25.301, CS 25.303, CS 25.305, C...	Doc ref: 2087703-EO Engineering Order & Certification Program.Doc ref: 2087703-AM-4 Flight Manual Supplement.Doc ref: 2087703-COR-2 Compliance Checklist.Doc ref: 2087703- CA-2 Continued Airworthinessor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/11/2016	Active	10060078

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060082	SIRIUM AEROTECH S.L.			MYSTÈRE FALCON 900 (MF900)	GPS upgrade for Falcon 900.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 Amdt 17,paragraphs 25.1316 and 25.1317.The requirements for environmental protection and the associatedcertified nois...	MASTER DATA LIST, Ref SA16-54S-MDL, Rev. 1, Oct. 5th 2016orlater revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/11/2016	Active	10060082
10060084	AIRBUS HELICOPTERS, Inc.		FAA SR09497RC-D	EC 130 T2	Installation of Garmin G500H Electronic Flight Instrument System (EFIS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- American Eurocopter Drawing List 130A82-8019, Rev. D, dtd. 14 March2013- Rotorcraft Flight Manual Supplement 130FMS-506, Rev. IR, dtd. 27 March2013- Instructions for Continued Airworthiness 130MMS-020, Rev. IR, dtd. 23February 2013or later revisions of the above listed documents approved by EASA i...	- This G500H EFIS installation approves the Garmin GDU 620 display (leftand right hand PFD versions, GRS 77H AHRS, GMU 44 Magnetometer, GDC 74HADC and GTP 59 OAT only.- This STC only approves the interface of Garmin GNS400W/500W seriesGPS/ NAV/COM, GMA340H audio panel, and GTX330 transponder to the G...	16/11/2016	Active	10060084
10060099	AERODATA AG			1900D	Installation of 230VAC Power Supply.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following CS-23 Amdt 4 paragraphs apply: 23.1;23.3(d); 23.25(a)(2);23.29; 23.251; 23.301(a) and (c); 23.303; 23.305; 23.307; 23.337(a) and(b); 23.341(a) and (c); 23.5...	Installation, Operation and Maintenance according to the Master DrawingList document number MDL-A/ C-888 Rev. 4 dated 11th November 2016or later revisions of the above listed documents approved by EASA.	Applicable to Beechcraft 1900D with installed Rockwell Collins Pro LineII avionics with an AD-AFIS-0290 flight inspection system installed(EASA STC 10055031 Revision 1 (or later EASA approved revisions) is aprerequisite for this installation).Prior to installation of this design change it must be de...	17/11/2016	Active	10060099
10060108	NORTHWEST AEROSPACE TECHNOLOGIESI NC.			A340-300	Interior reconfiguration of Lufthansa aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0545-D90, Revision -, dated 14 November 2016.- Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0545-D70, Initial Release, dated 29April 2016or later revisions of the above liste...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/11/2016	Active	10060108
10060110	SABENA TECHNICS BGC	REV. 1		A340-642, A340-643 A340-541, A340-542 A340-311, A340-312, A340-313 A340-211, A340-212, A340-213	Assessment of A/C Compatibility T-PED on A340 Aircraft.Revision 01 : Revision of the approval following the use by theapplicant of the EASA CM-ES-003 Issue 1 (Guidance to Certify an Aircraftas PED tolerant), and modification of the associatedlimitation/conditions information, accordingly.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to associated Certification Plan0806-01-A-CP-R03, sections 4 & 5, for de...	- Instructions for Continued Airworthiness, Aeroconseil document No.0806-01-A-ICA-R03;- Aircraft Flight Manual Supplement, Aeroconseil document No. 0806-01-A-AFMS-R01;or later revisions of the above listed documents approved by EASA.Master Data List, Aeroconseil document No. 0806-01-A-MDL-R04.	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. Even if the airplane is not fitted with anactive in-flight connectivity system;if this system is inautomatic/manual shutdown condition, orm...	27/06/2018	Active	10060110
10060120	HELIKOPTER AIR TRANSPORT GmbH			EC135 T2+	Miscellaneous changes for CFV operationThis change covers the conversion of the configuration of rotorcraftserial number 0374 from configuration used by the previous operator to“Christophorus Flugrettungsverein” (CFV) delivery configuration ofrotorcraft serial number 0600 to meet CFV fleet communali...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs of CS 27 Amendment 3 are applicable to thechange: 27.1; 27.301; 27.303; 27.305; 27.307; 27.561; 27.603; 27.609;27.610; 27.771; 27.1301; 27.1309; 2...	EO 85-011, Engineering Order, Revision 0, dated 10 Oct 2016, includingreferenced documents.	Limited to rotorcraft serial number 0374.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	21/11/2016	Active	10060120

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060139	TEXTRON AVIATION Inc.	REV. 1	FAA SA09860AC	T206H	Increase the maximum ramp weight to 1726 kg (3,806 pounds) and maximumtakeoff weight to 1718 kg (3,789 pounds).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	- Alamo Aerospace Master Drawing List 2900 Rev. A dated May17, 2016- Alamo Aerospace Flight Manual Supplement number AFMS 55186-5 Rev. IRdated June 13, 2016or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/12/2016	Active	10060139
10060149	328 SUPPORT SERVICES GmbH	REV. 1		DORNIER 328-100	Empty Cabin Layout, Project No. 099.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List MDL099Z001 Iss. B dated 18.11.2016;Declaration of Compliance DC-12B099Z0001 Iss. B dated 18.11.2016;Compliance Statements CS-12B099Z0001 Iss. A dated 25.10.2016;A/C Flight Manual Supplement AFMS012B099Z0001 Iss. B dated 15.11.2016;or later revisions of the above listed documents...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/09/2018	Active	10060149
10060172	SOCIETE AIR FRANCE S.A.			777-200	AZ – Cabin rearrangementThe modification consist in a cabinre-arrangement with 293 passengers,including GEVEN Economicand Premium Economic Class seats installationand STELIA Business class seats modification.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Change Approval Sheet CAS-B777-15-014 rev 0- Instruction for Continued Airworthiness, ref: ICA-B777-15-014-001 rev0.or later revisions of the above listed documents approved by EASA.	Monitors and components of the IFE System, including In-Seat PowerSupply System are treated as pure items of mass underthis approval.Electrical connection to aircraft requires further design approvalincluding full equipment qualificationIt is required the installation of the Self-Illuminating Floor...	23/11/2016	Active	10060172
10060173	BOMBARDIER Inc.			BD-700-1A10	EASA validation of Transport Canada Supplemental Type CertificateSA03-77 at Issue 1:Installation, Vacuum Waste System Vent	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification to be completed in accordance with Aero Consulting ServicesModification Data Summary D584000 Revision N/C.Mandatory Maintenance Manual Supplement BAS67050000 RevisionN/C.or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Pro...	Mandatory aircraft maintenance requirements (airworthiness limitations)and required aircraft equipment as per MandatoryMaintenance ManualSupplement BAS67050000 Revision N/C, or later revisions approved by EASAin accordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreemen...	23/11/2016	Active	10060173
10060188	MICRO AERODYNAMICS, INC.		FAA STC SA00865SE	114A/ 114B/ 114TC 112/ 112TC/ 112TCA/ 114	Installation of vortex generators on the wings, horizontal tail surfacesand vertical fin.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Micro AeroDynamics Drawing Package MA2128, Revision IR, dated November1, 2000, and Installation Manual MA2129, RevisionIR, dated December 7<(>,<)> 2000, or later FAA approved revisions.	If more than five vortex generators are damaged or missing<(>,<)> theaircraft is not airworthy.Prior to installation ofthis design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadvers...	23/11/2016	Active	10060188

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060212	DASSAULT FALCON JET CORPORATION	REV. 1	FAA ST01408WI-D	MF 900	Installation of PRIMUS EPIC Control Display System for Retrofit (CDS/R)in Dassault Aviation Mystere-Falcon 900 Airplanes originally equippedwith SPZ-8000 Digital Automatic Flight Control System. Installationincorporates the Phase 5 update with Localizer Performance with VerticalGuidance (LPV) approa...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01408WI-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Duncan Aviation Inc. Document List, No. 060509005, Revision U, dated14 January 2014;2. Duncan Aviation Inc. FAA Approved Airplane Flight Manual Supplement,No. 060509008, Revision J, dated 14 January 2014;3. Duncan Aviation Inc., FAA Approved Airplane Flight Manual Supplement,No. EDOC-0000016705,o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/02/2020	Active	10060212
10060222	MARSHALL OF CAMBRIDGE AEROSPACELIMITED		CAA UK RESPONSIBILITY	DHC-8-401, DHC-8-402	Auxiliary Fuel Management System Provisions (AFMS)This modification provides the mechanical and electrical systemsprovisions within the existing DHC-8-400 Series fuel system for theinstallation of external auxiliary fuel tanks.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition(s) CRI C-01 (Yawing Manoeuvring Conditions INT/POL/25/8, Is. 1),F-01 (Protection from the effects of HIRF INT/POL/25/2, Is. 1),F-02 (Protection from the Eff...	-Installation must be in accordance with EO N° MU9-00-0002,Issue 9 - Engineering Order for Introduction of the Q400 Auxiliary Fuel ManagementSystem- Continued Airworthiness must bein accordance withICA/Q400(1995)/ 15/0667, Issue 2 and Airplane Maintenance Manual MTM0299Part 1 & MTM0303 Part 2, Rev1-E...	AFMS must not be installed on aircraft with CAT operationsThe aircraft must not operate at a range greater than 1 hour's flyingtime from an adequate aerodrome at the one-engine inoperative cruisespeed, in standard atmospheric conditions and still air.Activation of the AFMS and conditions for operati...	25/11/2016	Active	10060222
10060224	TELEDYNE CONTROLS, LLC		FAA ST01823LA	A340-541, A340-642 A340-311, A340-312, A340-313 A340-211, A340-212, A340-213	Wireless GroundLink®- Quick Access Recorder System installationThis modification installs the Teledyne Controls' Wireless Ground LinkQuick Access Recorder (WQAR), P/N 2243800-xx, together with the enhancedAirborne Data Loader (eADL), P/N 2235300-xx.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): F-1310-001: Security protection of aircraft systemand networks.The requirements for environmental protection and the associatedcertified noise and/ o...	- Master Data List, ref. MDL2243800-A340 Revision D, dated 24September2013- Instructions for Continued Airworthiness, ref. ICA2243800_A4_1, dated19 May 2005or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisU...	None	25/11/2016	Active	10060224
10060225	TRUATLANTIC MFG., LLC		FAA STC SE02525AT	IO_550_N	Installation of Engine Mount Brackets.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Atlantic Aero, Inc. Document No. 22593010, "Instructions for ContinuedAirworthiness", dated April 9, 2002, Revision "IR"or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Imp...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/11/2016	Active	10060225
10060231	APTOZ EHF.	REV. 1		767-300	Communications - Data Transmission & Automatic Calling - DLINK+ ACARSSYSTEM INSTALLATIONRev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS-25 Amendment No. 12 (for areas affected by thechange) and CS-ACNSInitial Issue dated 17 December 2013.Thec...	Icelandair AFM Supplement CRA-767-2320-18 Revision IRIcelandair Continued AirworthinessInstructions CAI-767-2320-18 Revision IRor later revisions of the above listed document(s) approved/acceptedunder the EASA system.Icelandair Change/ Repair Approval CRA-767-2320-18 Revision B dated 25November 2016...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10060231

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060239	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	B300, B300C B200CT, B200GT, B200T B200, B200C, B200CGT 200, 200C, 200CT, 200T	Approval of the Introduction of Standalone GPS Antenna on BeechcraftKing Air 200 and B200 all variants, under Leading Edge Modification ref2XL030, Issue 1, dated, 21 October 2016.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Leading Edge Master DrawingList ref,2XL030 LEF78(1), Issue 1, dated, 21 October 2016 and InstallationInstructions ref, 2XL030 LEF49A(1), Issue 1.There is no AFMS associated to this Change.Instructions for Continued Airworthiness in accordance with documentref, 2XL03...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/11/2016	Active	10060239
10060240	ALTITUDE AEROSPACE INTERIORS Ltd.			787-9	Cabin<(>,<)> A Zone Bar, Perch Cushion Installation.The modification consist in the removal of “No sit” devices from perchesand replacement with fitted cushions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Summary report ref DP_005540_C.ICA: CMM 25-20-17 (61001107)Rev C.MDL ref MDL 22001142_Cor later revisions of the abovelisted documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/11/2016	Active	10060240
10060244	GULFSTREAM AEROSPACE Corp.		FAA ST04270AT-D	G280	Installation of Aerial View System (AVS) Video Tail Camera.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Index List GA5058001, Revision M, dated 30 July 2014.- Aircraft Flight Manual Supplement GA41505M001, Revision A, dated 30July 2014.- Instructions for Continued Airworthiness GA41505A002<(>,<)> RevisionB, dated 14 July 2014or later revisions of the above listed documents approved by EASA.	The following EASA STC is a required part of this STC: 10052498Installation of an Executive Cabin Interior.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introd...	29/11/2016	Active	10060244
10060249	SWS CERTIFICATION SERVICES Ltd.	REV. 1	CAA UK RESPONSIBILITY	777-300ER	Air Austral 777-300ER Skycouch Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration Scheme No.3176-MCS-01 Issue 1or later revisions of the above listeddocument (s) approved/ acceptedunder the EASA system.	Skycouch can only be used as a sleeping area or as an accommodationarea, as detailed in SWS Certification Services Ltd Design Report3176-DR-01, during in-flight conditions.	12/12/2018	Active	10060249
10060254	SABENA TECHNICS BOD			A330-323	Air Caraibes - Ultra High Comfort Attendant Seats (UHCAS) installationThis STC installs 4 UHCAS together with the O2 adaptation and modifiesthe In-Flight Entertainment system already installed.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Approval Sheet, ref: MAS S-25-4055 Issue 3 dated 26November 2016- Master Data List, ref MDL-S-25-4055, Issue C, dated 25 November 2016- Instruction for Continued Airworthiness, ref: ICA-F3048-25-009, IssueA dated 18 November2016or later revisions of the above listed documents approve...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/11/2016	Active	10060254
10060260	AVIONITEC Ltd.			PA-28-181 (ARCHER III)	LPV Approach Certification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- To be operated according to AFM Supplement No.PI11543-011, rev. 2,dated 14 November 2016;- To be maintained according to ICA No. PI11543, dated 22 June 2011.or later revisions ofthe above listed documents approved by EASA.	Limited to the S/N: 2843095Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installeddesign change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	30/11/2016	Active	10060260

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060272	NSE			C/C1/L/L1/	Evolution of the UMS Brite Saver 2 from amendment 7 to 8.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Plan PCERT-01297-92-EN Rev 06Definition File DD-0027-92-EN Rev 18Plan for Software Aspect of Certification PSAC-0028-92-EN Rev 04Software Accomplishment Summary SAS-0029-92-EN Rev 10Software Configuration Index SCI-0030-92-ENRev 10STC Document List SDL-BS2-AS332 Rev 05or later revisio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/11/2016	Active	10060272
10060283	LUFTHANSA TECHNIK AG			A340-313	A340 EDW Business Class Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25.981(a) and CS25.981(d) at Amdt.10The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areu...	- Supplemental Type Definition Document, Ref. STDD00-16/20MIssue 1 Rev0- ICA, Ref. A-00-16/72-ICA Issue 1 Rev 1- Compliance Record List, Ref. CRL00-16/20M Issue 1 Rev 0or later revisions of the above listed documents approved by EASA.	This approval applies to those A340-313 aircraft in which the followingpre-modification configurations have been installed:- Changes in the business class area as defined in Airbus SBA340-25-4363- Installation of GuideU, a non-electrical floor path marking system, byLHT Engineering Bulletin A340-EB3...	01/12/2016	Active	10060283
10060285	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED		CAA UK RESPONSIBILITY	EC135 T3	BABCOCK/MOD/125 EC135Description: New aircraft NVIS-ready being equipped including camera,searchlight, front and rear workstations, MW downlink, PA system plusNVIS approval.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 27 Amendment 3 as perCCL/125-003 Issue 4.The requirements for environmental protection and the associatedcertified nois...	- Flight Manual Supplement FMS/125-002, Issue 3, dated 25 Nov 2016or later revisions of the above listed documents approved by EASA.- Design Report DR/125-001 Issue 5, dated 25 Nov 2016- CCL/125-003 Issue 4, dated 25 Nov 2016- CCL/125-004-Instructions for Continued Airworthiness ICA/125-016, Issue2...	This change is applicable to the helicopter with CPDS cockpit.This is a series change applicable to EC135 T3 aircraft equipped withthe Airbus Helicopters NVIS optional lighting and equipment as definedon drawing BD/125-100.Any deviation from the cockpit or cabin configuration specified in thisSTC Ty...	01/12/2016	Active	10060285
10060296	REB TECHNOLOGIES Inc.d/b/a REBTECH		FAA STC SR09489RC	R44 II R44	Installation of Night Vision Goggle Compatible Lighting System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	REB Technologies, Inc., Master Drawing List 98020044MDL. Rev. P, datedOctober 27, 2012, or later FAA approved revision.Either Rotorcraft Flight Manual Supplement (RFMS) 98020044-RFMS, Rev. A,dated March 30, 2012, or later FAA approved revision; or 98020044-5RFMS,Rev.IR, dated October 31, 2012 or lat...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Installation of Infrared Filtering Cockpit Light...	10/02/2017	Active	10060296
10060308	SABENA TECHNICS BGC			A330-343	Cabin Reconfiguration with IFE/ISPSS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to associated Certification Plan4933-01-A-CP-R03, section 5, for details...	- Master Data List, ref 4933-01-A-MDL-R00- Instructions forContinued Airworthiness, ref 4933-01-A-ICA-R01;- Aircraft Flight Manual Supplement, ref 4933-01-A-AFMS-R02or later revisions of the above listed documents approved by EASA.	It is required the installation of Non-Electrical Floor Path Markingsystem, STC EASA 10014507 Rev 2.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noa...	02/12/2016	Active	10060308

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060315	DART AEROSPACE USA, Inc.	REV. 2	FAA STC SR02508SE	MBB-BK117 D-3 MBB-BK117 D-2	Installation of Bearpaw KitRevision 1 adds the MBB-BK117 D-3 model.Revision 2: Removal of Bearpaw Kit reference	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Installation Instructions IIN-D117-1028, Revision D, dated 25 January2023;2. Master Document List (MDL) MDL-D117-1028, Revision D, dated 25January 2023;3. Instructions for Continued Airworthiness (ICA) ICA-D117-1028,Revision 3, dated 25January 2023;or later revisions of the above listed document...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/03/2025	Active	10060315
10060318	E A D AEROSPACE AIRWORTHINESS	REV. 1		A321-251N/-253N/-271N/-272N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of antenna structural provisions for ACGC System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List, EAD Aerospace document No. 01512-EAS-A-MDL,Revision D, dated 21 September 2017.-Instructions forContinued Airworthiness, EAD Aerospace document No. 01512-EAS-A-ICA-01, Revision D, dated 20 September 2017or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/09/2017	Active	10060318
10060319	AEROTEC & CONCEPT			1900D	Installation of Altitude Select function for B1900D aeroplane inaccordance with Aerotec Concept Master Data List AE16151MDL, Issue 0,dated 20 October 2016.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement, Aerotec Concept document,AE16151AFMS, Issue 0, dated 20 October 2016or later revisions of the above listed documents approved by EASA.Instructions for Continued Airworthiness, Aerotec Concept documentAE16151ICA, at issue 0, dated October 10, 2016.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/12/2016	Active	10060319
10060323	LUFTHANSA TECHNIK AG			A380-800	Installation of Data Broadband Transceiver System - Activation of PACOn-Board Mobile Telephony System (OMTS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance Record List Ref. CRL44-16/02M issue 1 dated 21-NOV-2016.Airplane Flight Manual Supplement Ref. A-00-16/69-AFM issue 1 dated13-SEP-2016.Master Minimum Equipment List Supplement Ref. A-00-16/69-MMEL Rev. 00dated 13-SEP-2016.Instruction for Continued Airworthiness Ref. A-00-16/69-ICA issue 1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/12/2016	Active	10060323
10060369	CESSNA ZURICH CITATION SERVICE CENTGMBH	REV. 1		BAE.125 SERIES 800A	Installation of Dual Universal FMS-1Fw (SBAS) with TAWS Class A for LPVapproach.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-ACNSInitial Issue.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and rem...	- Master Document List, Design Engineering Zurich document No. MDL-116,Revision A, dated 7 December 2016.-Instructionsfor Continued Airworthiness, Design Engineering Zurichdocument No. ICA-116, Revision A, dated 1 December 2016-AircraftFlight Manual Supplement, Design Engineering Zurich document...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/12/2016	Active	10060369

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060371	THALES AVIONICS Inc.	REV. 2	FAA ST03414NY	A321-231, A321-232 A321-213/-231/-232 A321-211, A321-212, A321-213 A321-111, A321-112, A321-131 A321-111/-112/-131/-211/-212	Installation of a Thales In-Flight Entertainment System.Rev. 1: Transfer of the STC from Delta Engineering to Thales Avionics,Inc.Rev. 2: Change of Delta Engineering MDL/ICA to Thales MDL/ ICA.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS25.853 at Amdt 13,CS25.869 at Amdt 4,and CS25.981 at Amdt13.The requirements for environmental protection and the ass...	- Thales Index List 258809 Revision A dated 15 April 2021- Thales Master Drawing List 501550-MDL Revision C dated 15 April 2021- Instructions for Continued Airworthiness, 501550-ICA Revision A dated13 April 2021or later revisions of the above listed documents approved by EASA inaccordance with EASAt...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/07/2021	Active	10060371
10060382	DELTA G DESIGN Inc.		FAA STC ST11120SC	737-900ER	Installation of a Rockwell Collins Tailwind 550 Antenna on a Boeing737-900ER	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta G Design Inc. Airplane Flight Manual Supplement DGD-C550-AFM-01Revision IRDelta G Design Inc. Instructions for Continued Airworthiness No.DGD-C550-IC-01 Rev Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions...	Note that the ICA report DGD-C550-IC-01 Rev A contains additionalmandatory airworthiness inspections.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce no...	07/12/2016	Active	10060382
10060383	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR01186AT	205A-1, 212, 412, 412EP	Installation of replacement fuel cap or locking fuel cap onBellHelicopter Models 205A-1, 212, 412, 412EP.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeronautical Acccessories, Inc. report no. AA96134, "Replacement FuelCap Kit, Locking Fuel Cap Kit, Replacement Fuel Cap InstallationInstructions", N/ C, dated 22 August 1996 or later FAA approved revision.	The approval of this change in type design is restricted tothehelicopters identified above only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadve...	08/12/2016	Active	10060383
10060386	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A330-343	Cabin Reconfiguration (Intrepid Aviation Management)Rev 1.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement: S.OAED. 000454-AFM Rev 02Master Document List: S.OAED. 000454-MDL Rev 01Compliance Check List: S.OAED.000454-CCS Rev 01Instructions for Continued Airworthiness: S.OAED.000454-ICA Rev 00or later revisions ofthe above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/04/2021	Active	10060386
10060396	COMTECH GLOBAL AVIATION SERVICES S.	REV. 1		737-800	Introduction of 174 passenger seating configuration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.23(a)(b)(1), CS 25.25(a)(1), CS 25.27, CS 25.29, CS 25.301(a)(b),CS 25.303, CS 25.305(a)(b), CS 25.307(a), CS 25.365(g), CS 25.601, CS25.603, CS 25.605, CS 25.607,...	-Master Data List, Ref. CTE-MDL0144-737, Rev "-", dated Dec8, 2016- Instructions for Continued Airworthiness, Ref. CTE-TP0144-01, dated Nov17, 2016or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/06/2019	Active	10060396

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060398	BLR AEROSPACE, L.L.C.	REV. 4	FAA STC SR09658RC	AS 350 D AS 350 B, B1, B2, B3 AS 350 BA AS 350 B3, AS 350 D AS 350 B1, AS 350 B2	Installation of BLR FASTFIN® System.Rev. 1: Transfer of STCfrom JJASPP Engineering Services LLC to BLRAerospace LLCRev. 2: Update of STC holder's addressRev.3: Addition of RFMS-350FF-20, to the AML, dealing with compatibilitywith Airbus Helicopters Increased Take-off Power (Mod. 07.5102-RFMSuppleme...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List BLR-AS350-40, Rev. AE, dated 9 May 2023<(>,<) >Rotorcraft Flight Manual Supplements, as applicable:RFMS-350FF-1, Rev. 3, dated 14 June 2024, supplemented byRFMS-350FF-1-EASA, Rev. IR;RFMS-350FF-2, Rev. 2, dated 14 June 2024, supplemented byRFMS-350FF-2-EASA, Rev. IR;RFMS-350FF-3,R...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/12/2024	Active	10060398
10060403	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST03817AT	B717-200 SERIES	Installation of a Thales-KANNAD Emergency Locator Transmitter inB717-200 Series Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	- Avionics Support Group, Inc. Master Data List 29055-MDL, Rev. A, dated26 October 2009, or later FAA approved revision.- FAA approved Airplane Flight Manual Supplement for Avionics SupportGroup 29055-FMS dated 29 October 2009 or later FAAapproved revision.- Instructions for Continued Airworthiness...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/12/2016	Active	10060403
10060425	INTERNATIONAL ENGINEERINGAS SISTANCE (IEA)	REV. 2		EC135 T2+, EC135 T3	TIR/VH station installation in cabin.Rev 2: New cabin layout with Airbus Helicopter passenger seats added.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplément N°3 au manuel de vol IEA127 Issue D<(>,<)>or later revisions of the above listed documents approved by EASA.- Programme de certification IEA-123 Révision G du 15/11/2017.- Master Data List IEA-124 Révision D du 15/11/2017.- Instruction for Continued Airworthiness IEA-128 Revision C du29/1...	Can only be installed with prior installation of EASA STC 10058965.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthin...	15/11/2017	Active	10060425
10060428	PMV ENGINEERING			737-900, 737-900ER 737-600, 737-700, 737-800	TPED tolerance on B737 NG	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List SCA-00740-MDL-R02 dtd. 5. Dec. 2016-Instructions for Continued Airworthiness document SCA-00740-ICA-R00dtd. 29. Sep. 2016or later revisions of the above listed documents approved by EASA.	Per Instructions for Continued Airworthiness document Instructions forContinued Airworthiness document SCA-00740-ICA-R00 dtd. 29. Sep. 2016Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design c...	12/12/2016	Active	10060428
10060430	DELTA ENGINEERING CORPORATION		FAA STC ST02640NY	777-300/ 777-300ER	Installation of Panasonic 3000i IFE System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS25.831 at Amdt 2, CS25.853 at Amdt 13, CS25.869 at Amdt 4, andCS25.981 at Amdt 13, CS25.1353 at Amdt. 2, CS25.1423 atC...	Master Data List, Ref. 0143-06439-2182 Rev. U, dated Feb. 25th 2016.Instructions for Continued Airworthiness, Ref. 0743-06444-2182 Rev. J,dated Feb. 25th 2016.Supplemental Type Certificate Project Results for the Panasonic System3000i In-Flight Entertainment System In a Boeing 777-300 Series, Ref.OD...	The EASA STC covers only the configuration no. 11 of the MDL, Ref.0143-06439-2182 Rev. U.The prior installation of the EASA STC 10058319 is required.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installe...	13/12/2016	Active	10060430

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060437	DELTA ENGINEERING CORPORATION		FAA ST02897NY-D	777-200, 777-200LR	Installation of Panasonic 3000 IFE System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, Ref. 0143-07671-2258 Rev. "-", Nov. 21st 2012.- Instructions for Continued Airworthiness, Ref. 0743-07672-2258 Rev. A,dated Jul. 4, 2012.- Airplane Flight Manual Supplement, Ref. 14886000 Rev. IR, dated July18th 2002.- Compliance Summary Report, Ref. 6643-09978-2258 Rev. A, dated...	This STC includes an AMOC to AD 2008-11-13.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducenoadverse effect upon the airworthiness of the product.	12/12/2016	Active	10060437
10060441	H4 AEROSPACE (UK) Ltd.	REV. 2	UK CAA STC UK.STC.00134	A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	WIRELESS IN-FLIGHT ENTERTAINMENT (W-IFE) SYSTEM.Rev. 2 is atransfer from Tenencia Ltd. to H4 Aerospace (UK) Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TENENCIA LTD. Flight Manual Supplement No. TEN 797-47 Issue1;TENENCIA LTD. MASTER DATA LIST No. TEN 797 Issue 1;or later revisions of the above listed document(s) accepted by EASA inaccordance with the Technical Implementation Procedures of EU/UKBilateral Agreement.	Operational Approval for the use of transmitting PEDs on board of theaircraft must be obtained from the responsible division of theoperational authority of the aircraft's country of registration prior toconducting this kind of operation. It is the operator's responsibilityto ensure he has the necess...	07/01/2025	Active	10060441
10060444	T.P.S. S.P.A.	REV. 1		AW189	Installation of Medical Oxygen System in accordance with Design ChangeTPS189-001-00.Rev. 1: Change of the approval holder name from TPS AEROSPACEENGINEERING S.r.l. to T.P.S. S.P.A.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Rotorcraft Flight Manual Supplement TPS 189-00100-RFMS-00, issue 0,dated 4th June 2016- I.C.A (Airworthiness Limitation Section) TPS 189-00100-ICA-00, issue0, dated 30th August 2016- Master Document List TPS 189-00100-Mdl-08, issue 8 dated 28th.October2016- Installation Service Bulletin TPS 189-00...	Limited to AW 189 S/N 89003 & 89004.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	19/05/2022	Active	10060444
10060445	LUFTHANSA TECHNIK AG			737-700 / 737-800	Fin Top Antenna.-Ku Band TIOS radome installation on B737-700/-700IGW.-Rev. 1: in Feb 2001, one configuration added: KuBand TIOS radomeinstallation on B737-800.-Rev. 2: LBA certificate LBA. 21E2.TA0311 integrated in EASA system. Twoadditional configurations certified:-Ka Band TIOS radome installatio...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Definition document STDD55-00/01M issue/ revision07/00.Description of change ARS02-55 Rev. 3 dated Nov07th, 2016.Configurations-specific data:Ku Band TIOS RadomeB737-700/-700IGW:-AFMS A-55-01/331 Rev. B dated Jun 04th, 2002-AMMS Dimensions / Area A-06-13/09-AMM dated Mar 22nd, 201...	The fin Top Antenna installation does not affect the ETOPS capability upto 180 minutes diversion time of the B737-700/-700IGW and of theB737-800.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed de...	13/12/2016	Active	10060445
10060447	EMBRAER ENGINEERING & TECHNOLOGYCENTER USA, INC.	REV. 1	FAA STC SA03006CE	EMB-505	Installation of Medical Evacuation Configuration (MEDEVAC)This STC was originally issued as a validation of Brazilian CST (STC)No. 2012S02-15 (11 February 2016). STC transferred to United Statesbased Design Approval Holder (DAH) on 13 May 2019.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List Number ESCCC, Revision H, dated 05 May 2017.- Operation must be performed in accordance with ANAC approved AirplaneFlight Manual Supplement (AFMS), DocumentNumber H. 02-3692-0/ANAC/2012,Rev IR dated 28 February 2012.- Instructions for Continued Airworthiness (ICA), Document Nu...	Qualification of carry on medical devices used for sustaining patientsin flight, including incubators, not listed in the installation manualdocument ref, No ESCMSD006, Rev E, dated 05 May 2017, will requireseparate approval.Prior to installation of this design change it must be determined thatthe in...	25/11/2019	Active	10060447

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060483	SKYTRAC SYSTEMS Ltd.		SA 16-22	LEARJET MODEL 45	SkyTrac ISAT Airborne Position / Data Communicator Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SkyTrac Systems, Flight Manual Supplement, FMS14056-1, Rev.N/ C.SkyTrac Systems, Airworthiness Limitations – SKYTRAC ISAT AirbornePosition / Data Communicator, AWL-14056-1, Rev. N/ C.SkyTrac Systems, Instructions for Continued Airworthiness,ICA14056-1, Rev. N/C.SkyTrac Systems, Master Drawing List, MD...	None.	15/12/2016	Active	10060483
10060494	DART AEROSPACE Ltd.	REV. 3	TCCA SH08-16, ISSUE 7	AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 B3, AS 350 BA, AS 350 D AS 350 B1, AS 350 B2	Installation of External Attachment Provisions as detailed below.Configuration A- External Attachment Provisions OnlyInstallation of External Attachment Provisions to be completedinaccordance with TCCA approved, Aero Design Ltd. Document Control List,DCL786-1, Revision 4, dated 17 July 2014, or lat...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Data Pertinent to configurations A to F;Aero Design Ltd. Flight Manual Supplement FMS764.91, Revision 4, dated16 July 2014;Aero Design Ltd. Instructions for Continued Airworthiness ICA764.90,Revision 6, dated 15 July 2014For configuration G - Quick Release Cargo Basket InstallationDart Aerospace Ltd...	Approved type of operation - VFR only.For AS 355, CAT A operations are forbidden.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon...	26/10/2021	Active	10060494
10060495	DART AEROSPACE Ltd.	REV. 4	TCCA SH16-29, ISSUE 03	AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 BA, AS 350 D AS 350 B1, AS 350 B2,AS 350 B3	Configuration 1Installation of Quick Release Bicycle Racks.Installation of Quick Release Bicycle Racks to be completed inaccordance with TCCA approved, Aero Design Ltd. Document Control List,DCL1002-1, Revision 0, dated 12 August 2016, or later approved revision.Installation of External Attachment P...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For configuration 1Aero Design Ltd. Flight Manual Supplement FMS71002.91, Revision 0, dated30 June 2016;Aero Design Ltd. Instructions for Continued Airworthiness ICA1002.90,Revision 0, dated 12 July 2016For configuration 2Dart Aerospace Ltd Installation Instructions IIN-D350-1081 Revision A,dated Ja...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/10/2021	Active	10060495
10060496	DART AEROSPACE Ltd.	REV. 2	TCCA SH09-38 ISSUE 6	AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 B3, AS 350 BA, AS 350 D AS 350 B1, AS 350 B2	Installation of Quick Release Maintenance Step, Installation ofMaintenance Peg Step, Installation of Fixed Cabin Step as detailedbelow.Configuration A- Quick Release Maintenance StepInstallation of External Attachment Provisions in accordance with STCSH08-16 (Configuration A) is required for install...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For Configuration A- Aero Design Ltd. Flight Manual Supplement FMS827.90, Revision 4, dated31 July 2014- Aero Design Ltd. Instructions for Continued Airworthiness ICA827.91,Revision 5, dated 31 July 2014.For Configuration B- Aero Design Ltd. Instructions for Continued Airworthiness ICA827.93,Revisio...	Approved type of operation - VFR only.For AS 355, CAT A operations are forbidden.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the air...	10/11/2021	Active	10060496
10060505	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	737-200	Introduction of Honeywell TCAS 7.1 to Boeing 737This designchange entails the upgrade of the existing TCAS II processorVersion 7.0 to 7.1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Regulations at the amendment level: 14 CFR 25.1529Amdt 25-54.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	Leading Edge Aircraft Flight Manual Supplement, 2XL027 LEF71B (1) Issue3or later revisions of the above listed documents approved by EASA.Leading Edge Master Data List, 2XL027 LEF78(1) Issue 3.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/12/2016	Active	10060505

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060507	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	757-200	Activation of Controller Pilot Data Link Communications (CPDLC).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment: CS-ACNS:CS-ACNS.B.DLS.B1.001, CS-ACNS.B.DLS.B1.005<(>,<)> CS-ACNS.B.DLS.B1.010<(>,<)> CS-ACNS.B.DLS.B1.020<(>,<)>CS-ACN...	Flight Manual Supplement S21.FMS-0114 Issue 1or later revisions of the above listed documents approved by EASA.Master Document List S21.MDL-1071 Issue 1.	None.	16/12/2016	Active	10060507
10060508	ACC COLUMBIA Jet Service GmbH	REV. 6		A340-341, A340-342, A340-343 A340-341/-342/-343 A340-311, A340-312, A340-313 A340-311/-312/-313 A330-341, A330-342, A330-343 A330-323/-341/-342/-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-301/-302/-303/-321/-322 A330-223, A330-243 A330-201, A330-202, A330-203 A330-201/-202/-203/-223/-243	A330, A340 Installation of IAGOS P2 – Package 2dRevision 1 of this STC makes installation of IAGOS P2 – Package 2dapplicable additionally to A330-201, A330-202, A330-203, A330-223andA330-243 aeroplanes, incorporates changes CN_P2d_2043488_rev0_20171107,CN_2051301_rev0_20181010 and improvements defi...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDOCL_P2d_2036301_rev8;Master DocumentList MDOCL_P2d_23-90403_rev0;Master Drawing List MDRWL_P2d_2036301_rev6;Instructions for Continued Airworthiness ICA_P2d_2036301_rev8;or later revisions of the above listed documents approved by EASA.	Pre-condition of the installation of this design change is modificationof an aeroplane to incorporate either EASA STC 10045974 (for A330aeroplanes) or EASA STC 10028070 (for A340 aeroplanes).Prior to installation of this change/repair it must be determined thatthe interrelationship between this chan...	11/05/2023	Active	10060508
10060520	INTELSAT INFLIGHT LLC	REV. 1	FAA STC ST04369NY	747-400	Installation of Gogo 2KU – System Activation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Ltd Aeroplane Flight Manual Supplement S21.FMS-0143 Issue1 Refer to STC Twenty One Ltd Supplement ManualS21.TEC-0539 forAirworthiness Limitations.or later revisions of the above listed documents approved by EASASTC Twenty One Ltd Master Document List S21.MDL-1331 Issue 1	Configuration A and B of Design change S21.44-14-1022, approved by EASASTC 10059783, must be installed prior to, or concurrently with, thisdesign change.The operational approval for the use of 802.11 protocol T-PED devices isthe responsibility of the operator.Any change to essential aircraft LRU's a...	28/01/2020	Active	10060520
10060524	ANUVU	REV. 2		ERJ 190-300 ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 SR ERJ 190-100 LR, ERJ 190-100 SR ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ	Mechanical provision for EFB holder installationNote:,,ThisSTC is revised at Rev. 1 in order to extend the applicability toERJ 190-300.This STC is revised at Rev. 2 in order to record the transfer of STC toNavaero avionics AB.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List No. MDL-16-04 Revision H, dated 8 July 2019- Flight Manual Supplement FMS-16-04 Revision B, dated 22 May 2019- Instructions for Continued Airworthiness ICA-16-04 Revision B, dated22 May 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA syst...	The STC is to be used only with the tablets listed in chapter 0.6.2 ofthe Instructions for Continued Airworthiness ICA-16-04.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repaire...	04/09/2020	Active	10060524
10060527	GARMIN INTERNATIONAL, Inc.	REV. 1	FAA STC SR02124SE	SEE FAA AML	Installation of Garmin transponders: GTX 345/345R with ADS-B Out and Infunctionality; GTX 335/335R with ADS-B Out functionality.Revision 1: Add EC135 P3 and EC135 T3 models to theFAA Approved ModelList.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	(1) Garmin Master Drawing List (MDL), 005-00734-A4, Revision 1, datedNovember 11, 2016; or later FAA-approved revision.(2) Garmin Rotorcraft Flight Manual Supplement (RFMS), 190-00734-22,Revision 1, dated November 11, 2016; or later FAA-approved revision.(3) Gamin GTX 3X5 Part 27 AML Maintenance Man...	Compliance of this installation with CS-ACNS has not been demonstrated.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwor...	27/08/2020	Active	10060527

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060530	SPECIALIST AVIATION SERVICESLIMITED		CAA UK RESPONSIBILITY	AW169	NVIS AW169 (SAS/MOD/881).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS/881-043 issue A, dated 08/11/2016or later revisions of the above listed documents approvedby EASA.Declaration of Compliance for SAS/MOD/ 881, dated 09/11/2016.Maintenance Program Supplement MPS/ 881-040 issue A,dated 08/11/2016.	This STC is applicable only to AW169 Serial Numbers complying with theNVIS configuration described in SAS documents MPS/881-040 issue A andFTR/881-021 issue A.Rotorcraft modified by this STC employs Night Vision Imaging Systemlighting, commonly named NVIS lighting, which has been certified toensuret...	19/12/2016	Active	10060530
10060536	ACC COLUMBIA Jet Service GmbH	REV. 1		208B	Leica ALS Installation on C208B equipped with EASA STC 10015027.Rev. 1 Transfer to ACC Columbia Jet Service GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to GFM Master Document list MDOCL_2040415_rev0_20161020.To be operated in accordance with Gomolzig AFM-S Document No.SPOH_2040415_rev0_20161020or later revisions of the above listed documents approved by EASA.To be installed iaw.Installation Instructions Doc. NoII_2040415_rev0_20161020, or...	According limitation section of AFM-S.Prior to installation: STC EASA 10015027 must be installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadve...	31/01/2022	Active	10060536
10060542	S-TEC CORPORATION		FAA STC SA09219AC-D	M20K M20J	Installation of S-TEC System 20/30 Single and Two Axis Automatic FlightGuidance Systems Model ST-678-20/30.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	- Bulletin No. 778, dated 14 May 1997.- Master Drawing ListNo, 92992, dated 14 May 1997 or later FAA approvedrevisionsof the above data (28 Volt System).- FAA/DAS approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891380, dated 19 May 1997 for Mooney Model M20Jfor S-T...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/12/2016	Active	10060542
10060550	SCANDINAVIAN AVIONICS DESIGN ApS			206L-3, 206L-4 206A, 206B, 206L, 206L-1	Garmin GNS 430W and GTX 330 installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-27 Amdt 0 paragraphs:CS 27.1, CS 27.29, CS 27.301, CS 27.303, CS 27.305, CS 27.307, CS27.309, CS 27.561, CS27.601, CS 27.602,NEW-PAGECS 27.603, CS 27.605, CS 27.607, C...	RFM:- Document 2046476-AM-A, BELL HELICOPTER 206, 206A, 206B ,206L, 206L-1,206L-3, 206L-4 ROTORCRAFT FLIGHT MANUAL SUPPLEMENT single GarminGTX-330 Mode-S Transponder Mode S Elementary Surveillance (ELS) Issue 2dated 29-09-2011- Document2046476-AM-B , BELL HELICOPTER 206L-1 With Flight ManualSupp...	- RFM 2046476-AM-A: applicable for all models (in the STC)- RFM 2046476-AM-B: applicable for IFR operation in Model BELLHelicopter 206L-1 with BHT modification 206-705-001 (IFR ConfigurationInstallation) and associated IFR RFM (BHT-206L 1-FMS-10)- RFM 2046476-AM-C: applicable for VFR only operatio...	20/12/2016	Active	10060550
10060571	AVIATION SUPPORT GmbH			SA 365 N1 SA 365 N AS 365 N3 AS 365 N2	Installation of EMS Equipment SA 365NInstallation of EMS Equipment SA 365N series helicopters. The systemincludes a rear panel for medical equipment and an equipment rack forthe installation of medical oxygen bottles, power converters and adigital tactical radio equipment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 29 Amdt. 3:CS 29.1, CS 29.21, CS 29.25, CS 29.27, CS 29.29, CS 27.31, CS 29.251, CS29.301, CS 29.303, CS 29.305, CS 29.307, CS 29.309, CS 29.321, CS29.341, CS 29.571, C...	- Flight Manual Supplement, FMS-ASE-91315, original releaseor later revisions of the above listed documents approved byEASA.- Liste der gültigen Dokumente, MDL-ASE-91315, original release, dated13/12/2016- Instructions for Continued Airworthiness, ICA-ASE-91315, revision 0-2,dated 8/12/2016	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2016	Active	10060571

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060572	HONEYWELL INTERNATIONAL INC.		FAA STC SA01418WI-D	GA8, GA8-TC 320	Installation of the Bendix/King KFC 225 Automatic Flight Control system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For the GA8 model:Master Drawing List 159-08311-0001, Revision E, dated 12-19-2006 orLater FAA approved revision.For the GA8-TC320 model:Master Drawing List 159-08311-0001, Revision G, dated 1-2-2012 or laterFAA approved revision.Airplane Flight Manual Supplement, Honeywell part number 006-10320-000...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This approval is limited to GA8 aircraft s...	21/12/2016	Active	10060572
10060575	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	RRJ-95B	Introduction of a VIP Interior on Sukhoi RRJ-95B.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-12 for Isolated compartmentsEquivalent Safety Finding(s):F-34 for Quantity of Oxygen DeterminationDeviation (s):D-13 Internal DoorsThe requirements f...	-Flight Manual Supplement S21.FMS-0139, Issue 1.- Master Document List S21.MDL-1266, Issue 2- Introduction of VIP Interior – Supplement Manual S21.TEC-0474, Issue 1	This modification is applicable only to the RRJ Serial Number 95060.	21/12/2016	Active	10060575
10060577	AIRCRAFT SYSTEMS AND MANUFACTURING,INC	REV. 1	FAA STC ST04027CH	CL-600-2B16 (604 VARIANT)	Certification of the aircraft data link system used for communicationsupporting Air Traffic Services (ATS) and installation of the RockwellCollins Communications Management Unit (CMU), with a complementaryIridium Satcom system, or with theintegration of an existing SatcomsystemRev. 1 updates the de...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04027CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Aircraft Systems <(>&<)> Manufacturing, Inc. Master DataList, No.34-334G001, Revision H, dated 4 January 2017, or later FAA approvedrevision.2. Instructions for Continued Airworthiness, Report No. 34-027E361,Airworthiness Limitations section, Basic Issue, dated August 2015, FAAapproved 23 Septem...	1. EASA STC 10016518 or Bombardier Service Bulletin 604-34-057 Revision3 is a prerequisite for this STC to modify the Global Positioning System(GPS).2. EASA STC 10041712 is a prerequisite for this STC to add SBAS LPVcapability to the FMS-6000 Flight Management System.3. Bombardier Service Bulletin 6...	05/09/2018	Active	10060577
10060578	SPAES GmbH & Co. KG	REV. 3		AS 350 B2/ AS 350 B3 AS 350 B2, AS 350 B3	Max Pilot View Kit consisting of a new RH bubble door with a largertransparent area, a new bow shaped floor structure which the doorconforms to, a floor viewing aperture outboard of the RH pilot’s seatand a corresponding transparent section in the underlying fairing.Rev. 1 allows some specific confi...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement, doc. Ref. GVH-6767-01-FMS-01 issue 5, dated 07August 2017<(>,<)>or later revisions of the above listed documents approved by EASA.- Certification Programme GVH-6767-01-CP-01 issue 4, dated 20 December2016 (for initial issue).- Certification Programme GVH-6767-01-CP-02 issue...	This design change is not compatible with the RHS sliding doorinstallation.The panel covering the floor viewing window must be installed whenpassengers are carried.Operation with RHS door open or removed is not allowed with thismodification installed.The use of AFCS with yaw axis control is not comp...	12/10/2022	Active	10060578
10060586	LUFTHANSA TECHNIK AG			A319-111	Hyperion Cabin Modification	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25.301 Amdt.1, CS25.303 Amdt. 0, CS25.305 Amdt 1, CS.25.307 Amdt 1,JAR25.365 Ch14/Ch13, CS25.601 Amdt 0, CS25.603 Amdt 10, CS25.605 Amdt 0,CS25.609 Amdt 0, CS25.611 Amdt...	-Supplemental Type Definition Document, Ref. STDD25-16/37M Issue 1 Rev.0-Instructions for Continuous Airworthiness, Ref. A-00-16/76-ICA Issue 1Rev. 0-Compliance Record List, Ref. CRL25-16/37M Issue 1 Rev. 0or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/12/2016	Active	10060586

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060587	BOMBARDIER Inc.	REV. 1	TCCA STC Q-LSA99-055/D ISSUE 2	CL-600-2B16 (601-3A VARIANT)	Installation of Oxygen System Pressure Discharge Indicator	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-TCCA Serialized Supplemental Type Certificate (SSTC) No. Q-LSA99-055/D,Issue No. 2, dated 11th November 2016-Kmlex Aviation Inc. Master Document List, ref. doc. MDL36118004,Revision A, dated 15th November 2016-Kmlex Aviation Inc. Compliance Plan Document, ref. doc. CP36118-001,Revision A, dated 17t...	Applicable to CL-600-2B16 (601-3A Variant), Aircraft SerialNo. 5125	22/12/2016	Active	10060587
10060588	SCANDINAVIAN AVIONICS DESIGN ApS			JETSTREAM 3200 SERIES JETSTREAM 3100 SERIES	GPS Antenna Installation – Two antenna on upper fuselage (STA 133 onabout BL 7L and BL 3R)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 amendment 2 paragraphs:CS 25.1, CS 25.23 (a),(b), CS 25.29 (a), (b), CS 25.251 (a), (b), (c),(d), CS 25.301 (a), (b), CS 25.303, CS 25.305 (a), (b), (e), CS 25.307(a...	To be installed in accordance with the documents listed in Document ID2104016 STC, issue 1, Dated 20/12/2016;To be maintained in accordance with document ID 2104016-MM issue 2,dated 07/12/2016, with continuing airworthiness limitations as specifiedin document ID 2104016-CA issue 1;or later revisions...	As specified in document ID 2104016-CA issue 1;Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	22/12/2016	Active	10060588
10060590	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04297AT-D	GIV	Installation of Honeywell Primus Elite Advanced Features (PEAF) Upgradeto DU-885 Displays.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Gulfstream Aerospace Corporation Index List CE412088001, Rev. A, datedMarch 30, 2016, or later FAA approved revision.1.For-401 Configuration:FAA accepted Instructions for Continued Airworthiness CE41208A001,Revision B, dated October 23, 2014, or later FAA accepted revision isrequired.2. For-403 Con...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Gulfstream Aircraft Service Change (ASC) 476B an...	22/12/2016	Active	10060590
10060591	AEARO TECHNOLOGIES LLC		FAA STC ST04115CH	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Installation of thermal acoustic insulation packages	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS Part,,,,,,,,,,Amd.,,,,TitleSubpart A - General25.1(a),,,,,,,,,, 25/11,,,,ApplicabilitySubpart B - Flight, General25.29,,,,,,,,,,25/0,,,,Empty Weight and Corresponding Ce...	Aearo Technologies Master Data List MDL-1627-033015-001, Revision A,dated 20 July 2016.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/12/2016	Active	10060591
10060622	DELTA ENGINEERING CORPORATION		FAA STC ST03419NY	A340-300 SERIES	Installation of Bruce Aerospace Cabin Lighting.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Delta Engineering Master Data List 0161-09497-2399 RevisionA dated Nov.28, 2016 or later FAA approved revisions to Delta Engineering MasterData List previously listed. The Instructions for ContinuedAirworthiness as listed on the Master Data List is required with thisinstallation.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/01/2017	Active	10060622

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060624	DART AEROSPACE USA, Inc.		FAA STC SR02517SE	MBB-BK117 D-2 MBB-BK117 C-2	Installation of 651.1501 External Life Raft System (ELRS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Document List (MDL) MD145-3, Revision G, dated 17 November 2016,or later Federal Aviation Administration (FAA) approved revision.Instructions for Continued Airworthiness (ICA) ICA145-3, Revision A,dated 16 November 2016, or later FAA-accepted revision.Rotorcraft Flight Manual Supplement (RFMS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/01/2017	Active	10060624
10060626	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04299AT-D	G150		The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-ACNS Initial Issue:CS ACNS.D.ADSB.001, CS ACNS.D.ADSB.010, CS ACNS.D.ADSB.020, CSACNS.D.ADSB.025, CS ACNS.D.ADSB.030, CS...	Airplane Flight Manual Supplement Document No. G150-CGER-0015, Rev. B,dated 21 October 2015Index List Doc. No. CEC11268001, Rev. B, dated 13.May. 2015Instructions for Continued Airworthiness Doc. No. G150-CGER-0013, Rev.A, dated 16 December 2014or later revisions of the above listed documents approv...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/01/2017	Active	10060626
10060629	BHE & ASSOCIATES, LTD.	REV. 5	FAA SA11136SC	B200, B200C, B300, B300C	Installation of a Rockwell Collins Pro Line Fusion ® embedded displaysystem (EDS) and optional TCAS IIRev. 2 upgrades the existing Collins Aerospace Pro Line 21 system onB300/B300C.Rev. 3 updates the existing Collins Aerospace Pro Line II System to aCollins Aerospace Pro Line 21 backbone in Textrona...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Refer to FAA Approved Model List (AML) STC Number SA11136SCRev. F dated14 February 2023-Software update in accordancewith BHE & ASSOCIATES, LTD ServiceBulletin (SB) ref 522-00-0141 Rev IR, dated, 16 August 2019, for B300and B300C.- Software update in accordance with BHE & ASSOCIATES, LTD ServiceB...	Refer to FAA Approved Model List (AML) STC Number SA11136SCRev. F dated14 February 2023 for applicable serial numbers.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will i...	06/08/2025	Active	10060629
10060630	S-TEC CORPORATION		FAA STC SA8894SW-D	F172M, F172N, F172P	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST- 563.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Bulletin No. 663, Revision 5, dated 1 February 2001 and MasterDrawing List No. 92732, Revision E, dated 1 February 2001 or later FAAapproved revisions of the above data (28 Volt System).2. FAA/DAS approved Supplemental Flight Manual, P/N 891125, dated 30November 1994 for Reims-Cessna models FI72M...	1. Also eligible on the above models when modified by 180 H.P. engineconversion.2. Prior to installation of this designchange it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upo...	04/01/2017	Active	10060630
10060634	AIRBUS HELICOPTERS DEUTSCHLAND GmbH			EC135 T1, EC135 T2 EC135 P2+, EC135 T2+ EC135 P1, EC135 P2	Installation of Garmin Transponder GTX335R with Special MissionConfiguration for Mode-S and ADS-B in accordance with compliance reportSK-MAC-167-CRP-B-1116.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS ACNS.D.ELS. 010, .015, .020, .025, .030, . 040;CSACNS.D.ADSB.010, . 020, .025, .030, .060, .070, .080, . 085, .090,.100, .105, .110, .115, . 120.The requirements for enviro...	Flight Manual Supplement GTX335R Installation SK-MAC-167-SUP-B-1118Revision Aor later revisions of the above listed documents approved by EASA.- Compliance Report GTX335R Transponder InstallationSK-MAC-167-CRP-B-1116 Revision A-Customization Manual Garmin GTX335R Installation SK-MAC-167-CM-B-1117Re...	The helicopter must be already equipped with a suitable GPS.Deactivation of Mode S and ADS-B-OUT ("Incognito-Mode") is not coveredby this approval.Activation of "incognito mode" may be permitted by the state of registryif the helicopter isoperated under VFR as state aircraft (e.g. forpolice) accord...	09/01/2017	Active	10060634

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060640	EMBRAER ENGINEERING & TECHNOLOGYCE NTER USA, INC.	REV. 1	FAA STC SA03005CE	EMB-505	Installation of Aviator 200 SATCOM System in EMB-505 airplanes equippedwith a Garmin G3000 avionics system.This STC wasoriginally issued as a validation of Brazilian CST (STC)No. 2015S01-10 (28 January 2015) and transferred to a United Statesbased Design Approval Holder (DAH) on 18 June 2019.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Master Document List NumberESCCCD055,Rev J, dated 23 May 2017.Operation must be performed in accordance with ANAC approved AirplaneFlight Manual Supplement (AFMS), document number H. 02-4342-0/EASA/2015,Rev A, dated 14 June 2017.Instructions for Continued Airworthines...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/11/2019	Active	10060640
10060645	ASIG, LLC	REV. 1	FAA STC ST09859AC	SEE APPROVED MODEL LIST	Installation of a SkyTender Beverage Trolley in the aircraft galley.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. STC Assembly Data List, ASIG Document No. 1065-5001-00, Rev. IR,dated 5/3/2016, or later FAA approved revisions;2. Installation Requirements Assessment, ASIG Document No. 1065-3005-00,Rev. IR, dated 2/24/2016, or later FAA approved revisions.	1. The SkyTender Beverage Trolley must be installed in accordance withInstallation Requirements Assessment< (>,<)> ASIG Document No. 1065-3005-00, Rev. IR, dated 2/24/2016, or laterFAA approved revisions.2. Maintenance Instruction 1065-2080099, dated February 25 2016, rev Ais a required part of this3...	05/01/2017	Active	10060645
10060646	MT-PROPELLER ENTWICKLUNG GmbH			T303	MTV-14 Propeller on Cessna T303.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-36, Amendment 3 ;FAR 36, Amendment 36-30.This certificate/approval involves a change to the requirements forenvironmen...	According to MT-Propeller Master Documentation List No. E-2802, Rev 0To be operated in accordance with MT-Propeller AFM-S Document No.E-2795, Rev 1or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No. E-2796, Rev 1,or later Revisio...	According limitation section of AFM-S.,,Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	05/01/2017	Active	10060646
10060660	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A319-132	Cabin Retrofit by Seat Replacement and Soft Cabin Items Refurbishment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Turkish Technic Master Document List No. CG-2500008-MD01-00Revision 00dated 05 January 2017.	None	06/01/2017	Active	10060660
10060666	NSE	REV. 1		EC635 T1, EC635 T2+, EC635 T3 EC635 P2+, EC635 P3 EC135 T3 / EC635 T3 EC135 T3 EC135 T2 / EC135 T2+ EC135 T1 / EC635 T1 EC135 T1, EC135 T2, EC135 T2+ EC135 P3 / EC635 P3 EC135 P3 EC135 P2/ EC135 P2+/ EC635 P2+ EC135 P1/ EC635 T2+ EC135 P1, EC135 P2, EC135 P2	Data Transmission System DTSV2Initial:Installation of DTSV2in accordance with STC Data List SDL-DTSV2-EC135Revision 1:Extension of applicability to EC135 T3 with Helionix cockpitvariant(EC135 T3H) in accordance with STC Data List SDL-DTSV2-EC135-T3H	InitialThe Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS-27 Amendment 3 for27.25, 27.27, 27.29, 27.301, 27.303, 27.305, 27.307, 27.337, 27.341,27.351, 27.561, 27.607, 27.609, 27.610, 27.611, 27.619, 27.625...	- STC Data List SDL-DTSV2-EC135-T3H Revision A1- RotorcraftFlight Manual Supplement RFMS-DTSV2-EC135 T3H Revision 01- Instructions for Continued Airworthiness ICA-00053147AA Revision A1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to helicopters with CDS/ CPDS cockpit variantFor EC135 T3 model also applicable to helicopters with Helionix cockpitvariantPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or re...	10/07/2023	Active	10060666

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060667	LUFTHANSA TECHNIK AG			A330-243	Installation of KA-Band SATCOM System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forEquivalent Safety Finding(s):CRI C-102 “Vibration / buffeting compliance criteria for large externalantennainstallation”.The requirements for environmental protectionc...	- Supplemental Type Definition Document, Ref. STDD23-16/21M, Issue 1Rev. 0.- Compliance Record List, Ref. CRL23-16/21M,Issue 1 Rev. 0.- Instructions for Continued Airworthiness, Ref. A-00-16/75-ICA Issue 1Rev. 0.- Airplane Flight Manual Supplement, Ref. A-00-16/75-AFM Issue 1 Rev. 0or later revisio...	Refer to the Instructions for Continued Airworthiness, Ref.A-00-16/75-ICA Issue 1 Rev. 0 (Section 4 Airworthiness LimitationSection).Prior to installation of this design change itmust be determined thatthe interrelationship between this design change and any otherpreviously installed design changea...	09/01/2017	Active	10060667
10060670	MCCAULEY PROPELLER SYSTEMS		FAA STC SA9850AC	208B	Installation of a McCauley Propeller Systems model 4HFR34C778 hub and102BHA-0 blade for a Textron Aviation Inc. model 208B aircraft with a P<(>&<)>WC PT6A-140 turboprop engine.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	Alamo Aerospace Installation Instructions number 2701 Rev. A dated 19August 2015 or later FAA approved revision.FAA approved Alamo Aerospace Flight Manual Supplement number AFMS55181-5 Rev. IR dated 11 December 2015 or later FAA approved revision.Instructions for Continued Airworthiness are containe...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/01/2017	Active	10060670
10060674	MAG AEROSPACE INDUSTRIES, Inc.d/b/a MONOGRAM SYSTEMS		FAA STC ST02585LA	A321-212/-213/-232 SERIES A321-111/-112/-131/-211/-231 A320-233 SERIES A320-211/-212/-214/-231 A319-131/-132/-133 SERIES A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122 SERIES	Installation of Toilet Assembly.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Monogram Master Data List MDL 14330-514 Revision A dated 15March 2016or later FAA approved revisions.Instructions for Continued Airworthiness (ICA), Monogram ICA 14330-514Revision A, dated 27 January 2016, or later FAA accepted revision mustbe made available to the operator at the time of installat...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/01/2017	Active	10060674
10060680	AVIONITEC Ltd.			PA-28R-201T	Avionics RetrofitRemoved: - Bendix King KMA 20 Audio Panel - Sigtronic SPA 400 Intercom - Bendix King KR 85 ADF - Bendix/King KX155 COM/NAV - Garmin GNS 430 GPS/COM/NAV - Trig TT31 XPDR - Narco AR-...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.,,The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Airplane Flight Manual Supplement GNS 430W: Doc. No. 2023-011, Rev. 06.06.2013- Airplane Flight Manual Supplement TAS 600: Doc. No. 2023-012, Rev.02.11.2012 ,,,,or later revisions of the above listed documents approved by EASA.,,- Instruction for continued airworthiness: Doc. No. 2023-015, Issue06....	Limited to S/N 28R7703135.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effectupon the airworthiness of the product.	11/01/2017	Active	10060680
10060686	S4A SOLUTIONS FOR AVIATION, S.L			208B	Structural Modifications in accordance with S4A Master Drawing List20834-RPT02, Issue 1.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 23, Amdt. 4 - 23.1,23.3, 23.21, 23.25, 23.251, 23.301, 23.303, 23.305, 23.307, 23.321,23.337, 23.341, 23.471, 23.561, 2...	Master Drawing List 20834-RPT02, Issue 1, dated 01 December2016or later revisions of the above listed documents approved by EASA.- Maintenance manual supplement 20834-HDK02, Edition 1.- Weight and balance 20834-RPT03, Edition 1.	This STC is limited to the modifications as defined in Master DrawingList 20834-RPT02, Issue 1, but does not cover any installation ofmission equipment.,,,,Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously i...	11/01/2017	Active	10060686

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060688	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH	REV. 1		525/ 525A/ 525B/ 525C	Installation of Garmin GTN 725/ 625.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Cessna Düsseldorf Citation Service Center GmbH, Master Document List,Document No. 2016-29-16, Rev A, dated 24 January 2019.To be installed in accordance with Installation Procedure, Document No.2016-29-1, Rev A, dated 24 January 2019.To beoperated in accordance with AFM-S, Document No. 2016-29-8, R...	- According limitation section of AFM-S- G3000 equipped S/ Nare excludedPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	28/05/2019	Active	10060688
10060691	MT-PROPELLER ENTWICKLUNG GmbH			TR182 T182T T182	MTV-9-B/200-52 propeller on Textron T() 182()	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-36, Amendment 3FAR 36, Amendment 36-30This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise or...	According to MT-Propeller Master Documentation List No. E-2837, Rev 0To be operated in accordance with MT-Propeller AFM-S Document No.E-2833, Rev 0or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No. E-2834, Rev 0,or later Revisio...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	11/01/2017	Active	10060691
10060693	LUFTHANSA TECHNIK AG			A330-243	WLAN Modification and Cabin Integration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document, Ref. STDD23-16/23MIssue 1,Rev. 1- Compliance Record List, Ref. CRL23-16/23M, Issue 1 Rev. 0- Airplane Flight Manual Supplement, Ref. A-00-16/81-AFM, Issue 1 Rev.2- Instructions for Continued Airworthiness, Ref. A-00-16/81-ICA, Issue 1Rev.0or later revisions...	Requires the previous installation of the following modifications:- Airbus Service Bulletins A330-23-3391 and A330-23-3267- EASA STCs 10028128 and 10060667Prior to installation ofthis design change it must be determined thatthe interrelationship between this design change and any otherpreviously in...	11/01/2017	Active	10060693
10060708	BOMBARDIER Inc.		TCCA STC SA16-110	BD-700-1A11 BD-700-1A10	EASA validation of Transport Canada STC SA16-110 at issue 1for:Installation, Conductive Antenna Gaskets.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification to be completed in accordance with B/E Aerospace IncModification Data Summary number L179000 Revision NC<(>,<)>or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.For Instructions fo...	None	13/01/2017	Active	10060708
10060709	ALPINE AEROTECH LP		TCCA SH16-1	407 206L, 206L-1, 206L-3, 206L-4	Bear Paw Auxiliary Skid Pads installation in accordance with AlpineAerotech Master Data List AAL-390-014-001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continuing Airworthiness Document NumberAAL-390-015-701 Revision A, dated 20 November 2015.Installation Instructions Document Number AAL-390-015-001 Revision NI,dated 01 June, 2016.Master Data List Document Number AAL-390-014-001 Revision B, dated 01June 2016.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/01/2017	Active	10060709

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060710	DART AEROSPACE Ltd.		TCCA SH16-30 ISSUE 1	AB139, AW139	D139-1019 Replacement Window Installations.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dart Instructions for Continued Airworthiness ICA-D139-1019, Rev. 0or later revisions of the above listed documents approved by EASA inaccordance with the Technical ImplementationProcedures of EU/ CanadaBilateral Agreement.TCCA SupportingLetter C-16-0737, dated 5 August 2016.Dart Airworthiness Com...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/01/2017	Active	10060710
10060712	DART AEROSPACE Ltd.	REV. 1	TCCA SH12-59 ISSUE 4	407 206L, 206L-1, 206L-3, 206L-4 206A, 206B	Configuration 1Cyclic Stick Control Friction in accordance with Aero Design Ltd.DCL952-1, Revision 2, dated 23 November2016 or later TCCA approvedrevision.Configuration 2Cyclic Stick Control Friction in accordance with Dart Aerospace Ltd.MDL-D407-1086, Revision A, dated 17 May 2020 or later TCCA ap...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Configuration 1Aero Design Flight Manual Supplement FMS952.91, Revision 1, dated 06August 2014.Aero Design Instructionsfor Continued Airworthiness ICA 952.90,Revision 1, dated 09January 2015.Configuration 2Dart Aerospace Ltd InstallationInstructions IIN-D407-1086 Revision A,dated 31 March 2020.Da...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/11/2021	Active	10060712
10060718	GULFSTREAM AEROSPACE Corp.		FAA ST04267AT-D	G280	Installation of an Aircell High Speed Internet System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aircraft Flight Manual Supplement GA41302M001, Revision -, Dated 24 ofOctober 2012.- Gulfstream Aerospace CorporationIndex List GA413028001, Revision P,Dated 12 of November 2012.- Instructions for Continued Airworthiness GA41302A004, Revision C,dated 26 of October 2012.or later revisions of the a...	The following STC is a required part of STC 10052498, Installation of anExecutive Cabin Interior.This system is intended to provide Internet connection and emailservices using portable electronic devices (PEDs). Any other intendedfunction of this equipment will require a re-examination of thecertifi...	16/01/2017	Active	10060718
10060727	JET AVIATION AG	REV. 1		A330-200, A330-300	Quad, Zoom and Tail Camera Installation.Revision 1: Transfer of EASA STC 10060727.	See appendix JBSC-M-00088CCS-01, Issue 03.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Compliance Sheet: JBSC-M-00088CCS-01, Issue03- Master Document List: JBSC-M-00088MDL-01, Issue 02- Instructions for Continued Airworthiness: JBSC-M-00088ICA-01, Issue01; JBSC-M-00088ICA-02, Issue 01or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/09/2017	Active	10060727
10060730	EDGE AERODYNAMIX, INC		FAA STC ST02623LA	737-800/-900/-900ER 737-300/-400/-500/-600/-700	Installation of Conformal Vortex Generators.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	FAA approved Edge Aerodynamix, Inc. Master Drawing ListEA51001-1 Revision D, dated 26 October 2016 or later FAA approvedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/01/2017	Active	10060730

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060733	ALPINE AEROTECH LP		TCCA SH16-36 ISSUE 2	2. 205A-1 1. 212, 412, 412EP	Installation of Baggage Compartment Protection Kit defined with AlpineAerotech Master Data List AAL-221-054-001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Alpine Aerotech Master Data List Document Number AAL-221-054-001Revision D, dated 26 August 2016.- Alpine Aerotech Installation Instructions Document NumberAAL-221-055-005 Revision NI, dated 11 July 2016.- Alpine Aerotech Instructions for Continuing Airworthiness DocumentNumber AAL-221-055-701 R...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/01/2017	Active	10060733
10060742	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR00044AT	206L-4 206L-3 206L-1 206L 206B 206A	Installation of replacement battery door	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeronautical Accessories, Inc. Drawing List Report No. AA-92104, norevision, dated November 16, 1992, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/01/2017	Active	10060742
10060769	KORFF LUFTFAHRT GMBH			G 109	Increase of MTOW up to 850 kg (including new increased wingspan), newpropeller, various improvements reg. instruments.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Description of the STC "G 109 with 850 kg":- Increasing of MTOW up to 850 kg (including new increased wingspan)- New propeller MTV-1-A/ L-165-06- Improvements in the instrumentation (optional: Dynon EFIS D 10A, DynonEMS D10, Transponder, GPS, artificial horizon, new engine tachometer,AVEO Strobe Lich...	Not possible for the S/N: 6001 and 6010 of the model Grob G109.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness...	20/01/2017	Active	10060769
10060774	AIRCRAFT SPECIALTIES SERVICES, Inc.		FAA STC SE09002SC	SEE FAA APPROVED MODEL LIST	Regrind Teledyne Continental crankshafts, to .020” undersize on crankpinand main journals	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Specialties Services, Inc. Drawing No. 1010, Rev. C, dated 01December 2004, or later FAA approved revision.	1. The following bearings are eligible for installation forthismodified crankshaft:Aircraft Specialties Services Inc. Part Numbers:S530058M020 Bearing, Front mainS643233M020 Bearing, Center mainS633398M020 Bearing, Center mainS639640M020 Bearing, Connecting RodAll drawings dated 27 May 1996, or lat...	23/01/2017	Active	10060774
10060790	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST04140CH	MYSTÈRE FALCON 900 (MF900) MYSTÈRE FALCON 50 (MF50) FALCON 900EX (F900EX)	Installation of a Honeywell JetWave System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: 25.301(a, b)(25-86), 25.307(a)(25-72), 25.561(b, c)(25-91), 25.571(a, b)(25-86) 25.613(a, b,d, e)(25-72), 25.1351 (a1)(25-72...	1. StandardAero Master Data List 1030897, Revision (E), dated 18November 2016 or later FAA approved revision.2. FAA Approved Airplane Flight Manual Supplement document number1030932, Rev (B) dated 8 November 2016, or later FAA approved revision.3. StandardAero Instructions for Continued Airworthines...	1. FAA Approved Airplane Flight Manual Supplement document number1030932, Rev (B) dated 8 November 2016, or later FAA approved revisionis a required part of this modification.2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and...	03/02/2017	Active	10060790

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060791	AVIATION FABRICATORS, Inc.		FAA STC SA01825WI	PC-12, PC-12/45, PC-12/47, PC-12/47E	Installation of a stretcher assembly onto a cabin seat track.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Aviation Fabricators STC Drawing List, Document No. AF-596, Rev. B,dated 25 April 2016 or later FAA approved revision.2. Aviation Fabricators Airplane Flight Manual Supplement (AFMS),Document No. AF-624FMS, Rev. IR, dated 19 October 2016<(>,<)> or laterFAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/01/2017	Active	10060791
10060794	JET AVIATION AG	REV. 1		737-900ER	VIP Cabin Interior Completion.Revision: Transfer STC 10060794.	See appendix JBSC-M-00051CCS-01 Issue 04.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aircraft Flight Manual Supplement: JBSC-M-00051AFM-01 ISSUE 4;- Master Document List: JBSC-M-00051MDL-01 Issue 3;- Compliance Check List: JBSC-M-00051CCS-01 Issue 4;- Instructions for Continued Airworthiness: JBSC-M-00051ICA-01 Issue 3;or later revisions of the above listed documents approved b...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/10/2017	Active	10060794
10060803	LUFTHANSA TECHNIK AG			A350-941	Premium Economy Seats in A350	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document, Ref. STDD25-15/36MIssue 1,Rev. 0- Instructions for Continued Airworthiness, Ref. A-00-16/89-ICA Issue 1,Rev.0- Compliance Record List, Ref. CRL25-15/36M Issue 1, Rev. 0or later revisions of the above listed documents approved by EASA.	- This STC requires the pre-installation of the delivery layout DLH 350-25.45610 (certified by Airbus with EASA Major Change with Approval Ref. 10060442)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously insta...	25/01/2017	Active	10060803
10060807	SPECIALIST AVIATION SERVICESLIMITED		CAA UK RESPONSIBILITY	AW169	Nose-mounted Trakka Searchlight AW169 (SAS/MOD/832).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS/832-025 issue A2, dated 22/11/2016or later revisions of the above listed documents approved by EASA.- Declaration of Compliance for SAS/MOD/832, dated25/01/2017.- Maintenance Program Supplement MPS/832-020 issue A2, dated 22/11/2016.	Helicopter operation requiring ditching capability is not allowed withthis modification installed.NVIS operation require separate design approval.This modification is not compatible with the following LeonardoHelicopters systems:- Weather Radar RTA-4112, Kit P/N 6F3441F00111- Windscreen wash System-...	25/01/2017	Active	10060807
10060808	BELL TEXTRON, Inc.	REV. 1	FAA STC SR00801DE	412, 412EP	Installation of Crew Mobility Restraint Kit.Rev. 1: Transfer from "La-Paz, LLC." to "Bell Texron, Inc."	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	1. Laz-Tec Drawing List, Report No. LT-15212, Revision A, dated April26, 2016, FAA approved 13 May 2016, or later FAA approved revisions.2. Flight Manual Supplement, Laz-Tec, LLC Document No. LT-15216, NoRevision, dated 19 January 2016, orlater FAA approved revision.3. Instructions for Continued Ai...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for the following aircraf...	17/03/2025	Active	10060808

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060811	3 POINTS AVIATION Corp.D/ B/A 3 POINTS AVIATION		TCCA STC SA14-36	DHC-8-301/-311/-314/-315 DHC-8-201/-202 DHC-8-102/-103/-106	DHC-8 Spoiler Servo Actuator Housing STCReplacement SpoilerServo Actuator Housing and Assembly (A44700-009-3PMA)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-3PMA-ENG13-255-ICA, Issue 1, Instructions for Continued airworthiness-3PMA-ENG13-254-MDL, Issue 2, Master Data Listor later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Proceduresof EU/ CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/01/2017	Active	10060811
10060813	AMAC AEROSPACE SWITZERLAND AG			737-900ER	WLAN activation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List MDL-EO03-4430 Rev C dated 24.01.2017-Aeroplane Flight Manual Supplement AFMS-EO03-4430 Rev A dated13.01.2017-Instructions for Continued Airworthiness ICA-EO03-4430 Rev A dated05.01.2017<(>,<)>or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/01/2017	Active	10060813
10060824	JET AVIATION AG, BASEL COMPLETIONS	REV. 3		A330-243	VIP Cabin Interior Completions.Rev. 2: Transfer of STCRev. 3: Activation of lift monitors in cabin.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFMS: JBSC-M-00055AFM-01, Issue 01;- MDL: JBSC-M-00055MDL-01, Issue 05;- CCS: JBSC-M-00055CCS-01, Issue 04;- ICA: JBSC-M-00055ICA-01, Issue 01; JBSC-M-00055ICA-02, Issue 01; JBSC-M-00055ICA-03, Issue 02; JBSC-M-00055ICA-04, Issue 01orlater revisions of the above listed documents approved by EA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/11/2017	Active	10060824
10060826	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		690D, 695, 695A, 695B 690, 690A, 690B, 690C	MTV-27() on Twin Commander 690, 695 Series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-36, Amendment 4FAR 36, Amendment 36-30This certificate/ approval involves a change to the requirements forenvironmentall...	According to MT-Propeller Master Documentation List No. E-2962, Rev 0To be operated in accordance with MT-Propeller AFM-S Document No.E-2959, Rev 0or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No. E-2960, Rev 0,or later Revisio...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	18/07/2017	Active	10060826
10060831	PRECISE FLIGHT, Inc.		FAA STC SH3319NM	MBB-BK117 B-2/C-1/C-2/ D-2 MBB-BK117 A-1/A-3/A-4/ B-1 EC135 P2/T2+/P2+/T3/P3 EC130 B4/T2/EC135 T1/ P1/T2 AS350 B/D/B1/B2/BA/B3 AS332C/L/L1/L2/ EC225LP/SA330J	Installation of Precise Flight Pulselite Control Unit in theLanding/Taxi Recognition Visual Control Light System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	Precise Flight Instructions as listed on FAA AML No. SH3319NM, dated 23January 1986, or later FAA approved revision.	The location of the pulselite box has not been evaluated, except if aninstallation drawing manual is provided on AML SH3319NM for theappropriate model aircraft. FAA Approval of structurally substantiatedlocation must be obtained prior to the installation of this STC.Prior to installation of this des...	10/02/2017	Active	10060831

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060846	GARMIN INTERNATIONAL, Inc.	REV. 4	FAA SA01818WI	SEE FAA AML SA01818WI	Installation of Garmin G5 Electronic Flight Instrument.Rev.1 amends the certification basisRev. 2 updates the type data and adds more models to the AMLRev. 3 updates the type data and adds more models to the AMLRev. 4 amends the certification basis	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01818WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Garmin Master Drawing List (MDL) 005-01112-01, Revision 1, dated 22 July2016;Garmin G5 STC Maintenance Manual includingICA190-01112-11, Revision 1,dated 22 July 2016;Garmin G5 Airplane Flight Manual Supplement 190-01112-13, Revision 1,dated 22 July 2016;or later revisions of the above listed docume...	1. This STC is valid for those aircraft types and models approved byEASA and listed on the FAA Approved Model List SA01818WI, dated 10December 2020.2. The installation of the G5 requires the retention of the mechanicalairspeed indicator, altimeter, and vertical speed indicator. Theinstallation of th...	24/05/2023	Active	10060846
10060852	AIRBUS HELICOPTERS	REV. 1		EC 130 B4 AS 350 B3	STC ST.7500 Crash Resistant Fuel System.- Revision 01. Extension to EC130 B4.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 Amdt. 3, dated 11December 2012, 27.561c), 27.863, 27.901b5), 27.952, 27.963e)f)g)h),27.967, 27.973, 27.975b) for the...	350N042807E_TN "ECST7500 Master Document List", issue A, dated 12December 2019Update of AS 350 B3e Rotorcraft Flight Manual Supplements as per FSA ECU16-40 065 2B, dated 01/12/2016:SUP.0 NR 3 (16-40)SUP.99.1 NR0 (16-40)Update of EC 130 B4 Rotorcraft Flight Manual Supplements as per FSA ECU19-48 014S...	Refer to 350N042807E_TN "ECST7500 Master Document List", issue A, dated12 December 2019 for pre-requisite installationsand incompatibilitiesPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change...	27/01/2020	Active	10060852
10060857	DAO AVIATION A/S	REV. 2		JETSTREAM 3200 SERIES JETSTREAM 3100 SERIES	Dual Garmin GTN 650 Installation on the JETSTREAM 3100/3200SERIES.	CS 23 Amendment 4.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- DAO-DO-0567-MDL-00 Master Document List;- DAO-DD-0567-ICA-01,,Instructions for Continued Airworthiness;- DAO-DD-0567-AFMS-03,,Aircraft Flight Manual Supplement;or later revisions of the above listed documents approved by EASA.	None	16/01/2018	Active	10060857
10060862	AERODATA AG	REV. 1		B200GT	Increase of MTOW to 14000 lbs.	See EASA approved Annex 10060862.This certificate/ approvalinvolves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Installation, Operation and Maintenance according to the Master DocumentList number MDL-A/C-883 Rev. 2 dated 25th January 2017.Applicable Noise Record: C12914.or later revisions of the above listed documents approved by EASA.	Limited to aircraft S/N BY-249 with the following modificationsinstalled:- Rockwell Collins ProLine 21 avionics- BLR Aerospace Ultimate Performance Package- BLR Aerospace Winglets- Raisbeck Engineering Ram Air Recovery System- Hartzell Composite Propellers HC-E4N-3A/NC9208K- Large main landing wheel...	06/02/2017	Active	10060862
10060873	GARMIN INTERNATIONAL, Inc.	REV. 3	FAA STC SA01714WI	SEE FAA AML	Installation of a Garmin transponders:(a) GTX 330/330D/33/33D or GTX 335/335R/335D/335DR with ADS-B Outfunctionality;(b) GTX 345/345R/345D/345DR with ADS-B Out and In functionality;(c) GTX 335R/335DR with ADS-B Out functionality in select airplanesinstalled with G950/G1000 systems; or(d) GTX 345R/34...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01714WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Garmin Master Drawing List (MDL) 005-00734-04, Revision 1, dated 1 May2013, or later FAA approved revision.Garmin Airplane Flight Manual Supplement (AFMS), 190-00734-15, Revision1, dated 1 May 2013 or later FAA approved revision.	(1) Aircraft installations involving the Garmin transponder modelswithout an internal GPS require the previous installation of an approvedADS-B position source. Refer to design data specified in the MasterDrawing List (MDL) listed above for specific hardware and softwarerequirements.(2) Aircraft wi...	02/10/2019	Active	10060873

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060874	AMAC AEROSPACE SWITZERLAND AG	REV. 4		737-900ER 737-800 737-8 737-700	Ka-Band Antenna InstallationRevision 1 of this STC is issued to include aircraft Model 737-800.Revision 2 of this STC is issued to include aircraft Model 737-700.Revision 3 of this STC is issued to include a different configurationfor the 737-700 Model (STA727C and 787) including a Dual Iridium Ante...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-01 Vibration / Buffeting compliancecriteria for large external antenna installationsThe requirements for environmental protect...	For 737-700 (Configuration 2)The change is defined with Revision A of Master Data List documentMDL-B7371-2-5300.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplement document AFMS-B7371-2-5300.Theaircraft shall be maintained in accordance with Revision B o...	Airworthiness limitations per Instructions for Continued AirworthinessICA-B7371-5300, ICA-B7371-2-5300, ICA-B7371-3-5300, ICA-B737-4-5300 andICA-B737-5-5300.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	20/12/2022	Active	10060874
10060881	E A D AEROSPACE AIRWORTHINESS			A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-223, A330-243 A330-201, A330-202, A330-203	Satcom KA band – GX Antenna Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-4301-002 (Vibration/buffetingcompliance criteria for large external antenna installation).The requirements for environmental protecti...	· Master Drawing List, EAD Aerospace document No. 01487-EAS-A-MDL,Revision C, dated 1 February 2017.· Instructions for Continued Airworthiness, EAD Aerospace document No. 01487-EAS-A-ICA-01, Revision A, dated 20 January 2017· Aircraft Flight Manual Supplement, EAD Aerospace document No.01487-EAS-A-AF...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2017	Active	10060881
10060883	AIRBUS HELICOPTERS DEUTSCHLAND GmbH			EC 130 T2	Installation of Garmin G500H Electronic Flight Instrument system (EFIS),consisting of a primary and a multifunctional display, an attitude andheading reference system (AHRS), an air data computer (ADC), amagnetometer and an outside air temperature (OAT) probe.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement, doc. ref. SK-MAC-163-SUP-J-992 Revision C,date code 11-16or later revisions of the above listed documents approved by EASA.- Certification Programme, doc. ref. SK-MAC-163-CP-J-985 Revision C,dated 22/06/2016.- Compliance Report, doc. ref. SK-MAC-163-CRP-J-994 Revision D, da...	- Garmin GTN750 equipment shall be installed as a prerequisite for thismodification.- A standby attitude indicator mustbe installed- No new kinds of operation are approved- Neither the Synthetic Vision System (SVS) nor the Helicopter TerrainAwareness and Warning System (HTAWS) functions have been c...	02/02/2017	Active	10060883
10060886	AERODATA AG	REV. 1		HAWKER 850XP/ HAWKER 900XP HAWKER 750/ HAWKER 800XP	Enhancement of TDR94/94D transponders for ADS-B functionality.Upgrade of the TDR94/94D transponders and connection of the transpondersto both GPS receivers for compliance with RTCA DO-260B requirements forADSB-out functionality.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS-25 Amdt 4 for the following paragraph: 25.1301, 25.1309,25.1317,25.1529, 25.1581(a)(2) and (d), 25.1583(a), (b), (c)...	Installation according to AERODATA Service Bulletin referenceSB-H125-TDR-2158 Rev. 1<(>,<)>Operation according to AERODATA Aircraft Flight Manual Supplementreference AFM-158, Rev.-,Maintenance according to AERODATA Aircraft Maintenance ManualSupplement, reference AMM-1165, Rev. -or later revisionsC...	Applicability limited to Aircraft equipped with:- Rockwell Collins ProLine 21 avionics suite<(>,<)>- dual Rockwell Collins GPS4000S installation<(>,<)>- dual Rockwell Collins TDR94/94D (Part number 622-9352-008 or -108 or-308 or -408 or -409) or TDR94D (Part number 622-9210-008 or -108 or-308 or -40...	27/06/2017	Active	10060886
10060926	DART AEROSPACE Ltd.		TCCA SH16-54 ISSUE 1	AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 B, AS350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of Skidtube Wearplate KIT P/ N D350-1023.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA accepted Instructions for Continued Airworthiness ICA-D350-1023 Rev0, dated 10th August 2016 (NOTE: no ALS changeshas been introduced withthis STC) TCCA approved InstallationInstructions IIN-D350-1023 Rev A, dated 10thAugust 2016TCCAapproved Master Document List MDL-D350-1023 Rev A, dated 1st...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/02/2017	Active	10060926

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060936	JET AVIATION AG	REV. 1		GV-SP	Iridium Antenna Replacement.The modification installs a newIridium antenna (replacing another oneat the same location).The Revision 1 updates the limitation section, by removing the lifedesign restriction.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, ref : JBSL-M-00860MDL-01 Issue 2, dated13 September2017;- Instruction for Continued Airworthiness,ref : JBSL-M-00860ICA-10Issue 3, dated 13 September 2017;orlater revisions of the above listed documents approved by EASA.	The installation of this modification is limited to MSN 5093.Prior to installation of this design change it must be determined thatthe interrelationship between this design changeand any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of...	19/01/2018	Active	10060936
10060937	ANJOU AERONAUTIQUE S.R.L.			A340-312/-313	A340-300 SEAT BELTS MODIFICATIONThe design change related to this STC consist in the replacement ofexisting safety belts by new ones manufactured by ANJOU AERONAU. Themodificationis on BC seats type 1404 & EC seats type 9174 and 3509.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan ref 02-610850-CP-001 Rev 04- Master Data List ref 02-610850-MDL-001 Rev 02- ICA: CMMS (Component Maintenance Manual Supplement), ref02-610850-CMMS-003 Rev 1- Modification Approval Sheet, Project 02-610850 Rev 02or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/02/2017	Active	10060937
10060941	AEROTEC & CONCEPT			EC 225 LP	Starting System Adaptation with “Start Bost” Kit (P/N EPA-AE-14121-100)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement «Start Boost» Starting Adaptation,AE16021RFMS Rev. 0 dated 23/02/2016or later revisions of the above listed documents approved by EASA.- Certification Program AE16021PCDP Rev. 3 dated 23/09/2016- Master Data List AE16021MDL Rev. 3 dated 31/01/2016	This design change cannot be installed on H/C with APU or with MOD45“HUMS” lightsPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon...	08/02/2017	Active	10060941
10060944	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 1	FAA STC SA380CH	B300C B300 300	Replace existing nose wheel with Cleveland Nose Wheel P/N 40-204 byinstalling Parker Hannifin Conversion Kit 199-126Revision 1 is an administrative re-issuance following a name change fromParker Hannifin Corporation Aircraft Wheel and Brake Division to KamanCorporation, Aircraft Wheel and Brake, LLC...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Parker Hannifin Conversion Kit 199-126, Revision M, dated31 July 2011or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/06/2023	Active	10060944
10060949	FLYING COLOURS CORPORATION	REV. 2	FAA ST02975NY	CL-600-2B16 (604 VARIANT)	ADS-B Out Installation in the Bombardier CL-600-2B16 (CL-604 Variant).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA STC ST02975NY, dated 2nd October 2015- Dassault Aircraft Services Master Data List, ref. doc. MDL00001S,Revision C, dated 2nd February 2017- Airplane Flight Manual Supplement, AFMS, ref. doc. FMS00001S, RevisionIR, dated 2nd October 2015- Instruction for Continued Airworthiness (ICA) ref. doc....	This alteration requires as a prerequisite<(>,<)> the Bombardier Inc.Service Bulletin 605-34-026 for Model CL-600-2B16;Installation ofGlobal Positioning System (GPS) – Upgrade the Wide Area AugmentationSystem (WAAS) Capability to prevent signal loss during flight.	12/06/2017	Active	10060949
10060955	SABENA TECHNICS BOD			A340-313	IAGOS – RTTU installationThis STC installs an additional module, nammed Real Time TransmissionUnit (RTTU) to the Integration of routine Aircraft measurements into aGlobal Observing System (IAGOS) on A340-313 aircraft model. This modulereceives IAGOS data and transmits them, through SATCOM system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Approval Sheet, ref. : S-23-2354, Issue 3 dated 07February 2017- Instruction for Continued Airworthiness, ref : ICA-F4035-23-007 issueA, dated 22 October 2015or later revisions of the above listed documents approved by EASA.	1- The modification is applicable to the following aircraftSerialNumber:,,,,- MSN 304.2- The following modifications are prerequisites for the implementationof this STC :,,,,- IAGOS installation - EASA approval 10028070 (at any revision),,,,- SATCOM installation - Airbus modifications 40907, 40982,...	09/02/2017	Active	10060955

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10060962	SPAES GmbH & Co. KG			EC135 T2/ EC135 T2+ EC135 P3/ EC135 T3/ EC135 T1 EC135 P1/ EC135 P2/ EC135 P2+	Title: Installation of an automatic deployable ELT.Description: For operation over water an automatic deployable ELT(AD-ELT) has to be installed. The beacon will be installed on the middlecover on the LH side of the lower fuselage shell. The cockpit controlpanel for activation and release will be in...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment: CS 27 Amdt. 2:For models EC135 P1<(>,<)> EC135 P2, EC135 P2+, EC135 T1, EC135 T2,EC135 T2+:CS 27.21, CS 27.25, CS 27.27...	Supplement for Automatic Deployable ELT (AD-ELT), FMS-SPAES-0047,Revision 01 dated 02 February 2017or later revisions of the above listed documents approved by EASA.Installation Manual, INM-135-047-25-01, Ausgabe 00 dated 8 November2016.Instructions for Continued Airworthiness, ICA-135-047-25-01, Au...	Not applicable to Helionix cockpit variants.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	15/02/2017	Active	10060962
10060967	LEARJET Inc.		FAA STC ST00370BO	BD-700-1A11 BD-700-1A10	Installation of a Honeywell Jetwave™ KA Band Satellite DataSystem.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: 25.29, 25.301, 25.303,25.305, 25.365, 25.561, 25.581, 25.601,25.603, 25.605, 25.609<(>,<)>25.619, 25.625, 25.629, 25.777,...	1. Master Document List (MDL), Document number BAS67017022,Revision B<(>,<)> dated 2 August 2016 or later FAA approvedrevision.2. Aircraft Flight Manual Supplement (AFMS) Document Number BAS67047020<(>,<)> revision NC, dated and FAA approved on 4 August 2016, or later FAA approved revisions.	1. Maintenance for the MDL -1 configuration must be in accordance withthe Instructions for Continued Airworthiness (ICA), document numberBAS670 17022-ICA-l, revision: A dated 5 April 2016, or later FAAaccepted revision.2. Maintenance for the MDL -2 configuration must be in accordance withthe Instruc...	13/02/2017	Active	10060967
10060979	HONEYWELL INTERNATIONAL (BENDIXKING)		FAA STC SA09856AC	SEE FAA AML SA09856AC-28/04/16	Installation of BendixKing Aerowave 100 In-flight Data LinkSystem fornon-essential, non-required aircraft Cabin Systems & Equipments	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Document List, Document No. 89800015-21, Rev. -, dated 19April 2016, or later FAA approved revision.2. AFMS, Document No. 89800015-004, Rev. -, approved 16 March 2016, orlater FAA approved revision.3. AML Eligibility Summary Report, Document No. 89800015-031, Rev. -,dated 21 March 2016, or...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This STC is valid for aircraft types and m...	02/03/2017	Active	10060979
10060986	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A340-313	Modification of Economy Class seats installed on VIP aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0600-D90, Initial Issue, dated 2 February 2017.Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0600-D70, Revision A, dated 4 January2017or later revisions of the above listed docu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/02/2017	Active	10060986
10061014	PK FLOATS INC	REV. 1	FAA SA00280BO	A-1, A-1A, A-1B, A-1C-180	Installation of PK 2250A Amphibious Floats in accordance with PK FloatsDrawing List 22DL1100, Initial revision, dated October 24, 2008.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): ACE-08-20.This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise orl...	- PK Floats, Inc. Airplane Flight Manual Supplement for SkyInternational Model A-1 with PK 2250A Amphibious Floats, Initialrevision, dated November 7, 2008- PK Floats, Inc. Airplane Flight Manual Supplement for SkyInternational Model A-1A with PK 2250A Amphibious Floats, Initialrevision, dated Novem...	- This STC does not apply to Engine Options Group Configurations of theModel A-1B- The weight increase to 2250 lbs for the A-1B and A-1C with PK 2250AAmphibious Floats is valid for serial numbers 2285, 2288 and greateronly. The applicable portions of Sky International Service Letter No. 3must be app...	14/02/2017	Active	10061014

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061022	CMD FLIGHT SOLUTIONS, LLC		FAA STC SA04051CH	SEE FAA AML	Certification of Automatic Dependent Surveillance -Broadcast (ADS-B) OutSystem with Rockwell Collins TDR-94/-94D Transponders.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	1) CMD Flight Solutions Master Data List, Document No. DB1506001,Revision IR, dated 19 June 2015, or later FAA approvedrevision. 2) FAA Approved Airplane Flight Manual Supplement (AFMS) as listed onthe FAA AML number SA04051CH, or later FAA approved revision.	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2) Additional Limitations and Conditions areS...	03/05/2017	Active	10061022
10061026	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST04146CH	ERJ 190-100 LR	EASA validation of FAA STC ST04146CH. Installation of a Zodiac RAVE In-Flight Entertainment System in accordance withStandardAero Master Data List DC104-9752A-00, Revision (E) dated 02ndDecember 2016 or later approved revisions.NEW-PAGE	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 impacted requirements at initial issue unless otherwise specified:25.1(a, b); 25.301(a, b)(amdt 1); 25.303; 25.305(a-c))(amdt 1);25.307(a)) (amdt 1); 25.561(a-d); 2...	The STC installation must be performed in accordance with StandardAeroMaster Data List DC104-9752A-00, Revision (E) dated 02nd December 2016,andThe Airplane Flight Manual Supplement document number DC303-9752A-00,Rev (-) dated 19th October2016 is a required part of this modification,andThe aircraft...	See those of original FAA STC ST04146CH and those of the Airplane FlightManual Supplement document number DC303-9752A-00, Rev (-) dated 19thOctober 2016, or later approved revisions.Prior to installation of this design change it must be determined thatthe interrelationship between this design change...	14/02/2017	Active	10061026
10061033	AVIATION FABRICATORS, Inc.	REV. 1	FAA STC SA01672WI	SEE FAA APPROVED MODEL LIST B200CGT B200C/ B200GT/ B200CT/ B200T 200/ 200C/ 200CT/ 200T/ B200	Installation of Window Shade Assembly as the replacement for OEMpolarized window assemblies.Revision 1 adds Beechcraft 90 and 300 series models.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01672WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Aviation Fabricators, Inc., Drawing List, AF-513, Rev. B, dated 10 May2011;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance withthe Technical ImplementationProcedures of EU/ USA BilateralAgreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	04/11/2022	Active	10061033
10061038	B.A.S., INC.		FAA STC SA01643SE	SEE APPROVED MODEL LIST	Installation of BAS, Inc. shoulder harness with inertia reel.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	BAS, Inc. Report 1006< (>,<)> dated October 15, 2005, or later FAAapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	16/02/2017	Active	10061038
10061050	ANJOU AERONAUTIQUE S.R.L.			A330-243	Passenger Economic Seats Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS 25 Amdt. 16 for the affected area – refer to CP ref. 02-100009-CP-001Rev. 0 for details.The requirements for environm...	Certification Program, Ref. 02-100009-CP-001 Rev. 0, dated 04/04/2016.Master Data List, Ref. 02-100009-MDL-001 Rev. 0, dated 04/04/2016or later revisions of the above listed documents approved by EASA.	Applicable to A330-243 MSN 0501 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/02/2017	Active	10061050
10061056	AIRBUS HELICOPTERS	REV. 1		AS 350 B3, EC 130 B4	STC ST.7501 Rupture Resistance Fuel System.Revision 01. Extension to EC 130 B4	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27.561 c) Amendment3 dated 11/12/2012.The requirements forenvironmental protection and the associatedcertified noise a...	350N042802E_TN, “ECST7501 Master Data List”, Issue A, dated12 December2019<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Refer to 350N042802E_TN, “ECST7501 Master Data List”, IssueA, dated 12December 2019 for pre-requisite modifications and incompatibilities.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change a...	24/01/2020	Active	10061056

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061069	CANARD AEROSPACE CORPORATION		FAA STC ST02780CH	DHC-8-401/ DHC-8-402	Installation of ATC Transponders with ADS-B Capability, LPVApproachAdapter, and FMS Upgrade.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS 25 Amendment 4, 27 December 2007, 25.29(b); 25.301(a)(b); 25.303;25.305(a)(b); 25.307(a); 25.321(a)(d); 25.561 (c); 25...	34-3475-06, Revision B, Airplane Flight Manual Supplement.40178, dated 7th of November 2016, Document Control Drawingorlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implem...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/02/2017	Active	10061069
10061072	PROTOPLANE SPECIAL MISSION AIRCRAFT			AS 355 NP AS 355 N AS 355 F2 AS 355 F1 AS 355 F AS 355 E	Installation of a video transmission system on AS355, mod number PP-082.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	PP-082-AFM-02, Supplement to Aircraft Flight Manual, issue 2, dated 01Feb 2017or later revisions of the above listed documents approved by EASA.PP-0082-ICA-00 "Supplement to ICA",issue 0, dated 16 Feb 2017No ALS update identified for thisSTC.PP-082-MDL-03 "Master Data list", issue 03, dated 16 Feb...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/02/2017	Active	10061072
10061082	SOCIETE AIR FRANCE S.A.			777-200	AZ – Cabin rearrangementThe modification consist in a cabinre-arrangement with 293 passengers,including GEVEN Economicand Premium Economic Class seats installationand STELIA Business class seats installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI 0010044498 F-01, Non-rechargeable Lithium Battery InstallationThe requirements for environmental protection and the associatedcertified noise and/...	- Change Approval Sheet CAS-B777-16-007 rev 0-Instruction for Continued Airworthiness, ref: ICA-B777-16-007 rev 0.or later revisions of the above listed documents approved by EASA.	Monitors and components of the IFE System, including In-Seat PowerSupply System are treated as pure items of mass underthis approval.Associated IFE sub-installations and Electrical connection to aircraft< (>,<)> require further design approval including full equipment qualification.It is required th...	21/02/2017	Active	10061082
10061083	AIRBUS S.A.S.			A330-343	MOD CJ2041: "MASTER MOD – VAA UCS"Installation of Upper Class Suite seats and stowages in forward part ofseveral A330-343 cabin, with an additional bar unit. Activation of IFEsystem.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-3312-001 (Issue 2): Single Side Facing SeatsThe requirements for environmental protection and the associatedcertified noise and/ or emissions le...	-Certification Summary ref: ACJC-AJA-15109 Issue 5-Modification Approval Sheet ref: CJ2041 Issue 1-ICA: Maintenance Planning Document Supplement, ref MPD-S MOD CJ 2041Issue Feb 01/17.or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/02/2017	Active	10061083
10061089	AIR ALLIANCE GmbH			35/ 35A/ 36/ 36A	TCAS & XPDR Antenna Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions For Continued Airworthiness (ICA) doc. no.2016_034_LJ35_0507, revision 01, dated 17 February 2017.Master Document list (MDL), doc. no. 2016_034_LJ35_Form 2, revision 00,dated 20 February 2017or later revisions of the above listed documents approved by EASA.	None.	22/02/2017	Active	10061089
10061092	AEROTEC & CONCEPT			757-200/ -300	Airborne wireless platform activation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS25 at amdt. 15: 25.1301, 25.1309, 25.1353, 25.1431, 25.1529, 25.1581,25.1585.The requirements for environmental protec...	Master Data List AE14266MDL Rev. 0 dated 15/02/2017.Aircraft Flight Manual Supplement AE14266AFMS Rev. 0 dated 25/01/2017.Instructions for Continued Airworthiness AE14266ICA Rev. 1 dated25/01/2017or later revisions of the above listed documents approved by EASA.	As per AFMS:- WiFi system is prohibited to work and must beswitched OFF duringrefuelling and Low Visibility Approach Operation, use "WIFI ON/OFF"pushbutton located on CCP on the top part of FWD L/H Attendant's area,above attendant seat.-TPEDs (including GSM personal devices) are prohibited to work...	22/02/2017	Active	10061092

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061095	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR01298LA	412/ 412EP	Installation of Apical Industries, Inc. Emergency Float Assemblies PartNumbers 20714, and 20715, in accordance with Master Document ListMD412-1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness for replacement emergency floatassemblies Bell Helicopter 412 float assembliesP/N 20714 and P/N 20715Report No. ICA412 -1 Rev. N/C dated 28 August 2000.Master Document List MD412-1, Revision N, dated March 04, 2013.Installation Instructions II412-1, Revision...	1) Bell Helicopter Textron Inc., Emergency Float Kit Part Number412-706-004-137, or 412-706-004-143, or 412-706-004-149must beinstalled prior to installation of this STC.2) The intermixed installation configuration between the followingApical Industries Inc. and Bell Helicopter Textron Inc. Emergen...	23/02/2017	Active	10061095
10061103	AMPHENOL CABLE AND INTERCONNECTT ECHNOLOGIES, Inc.	REV. 2	FAA STC ST04107CH	A320-231/-232/-233 A320-211/-212/-214	Installation of ARINC 791 Antenna ProvisionsRev. 2 reflectsthe transfer of the STC from Carlisle InterconnectTechnologies Inc. to Amphenol Cable and Interconnect Technologies, Inc.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):B-2301-001 Issue 1 dated 23/02/2017 - “Vibration / buffeting compliancecriteria for large external antenna installation”CS 25 Initial Issue fo...	Master Data List 900-149445 rev. F, dated January 19, 2017Instructions for Continued Airworthiness 900-149356 rev. D, datedJanuary 19, 2017Airplane Flight Manual Supplement 900-149355 rev. N/C, dated May 26,2016EASA Certification Comparison Report 900-725753 rev. A, January 27, 2017or later revision...	This STC does not certify any system equipment to be installed under theradome. The provisions installed under the present approval are intendedonly for the Honeywell JetWave Ka-Band SATCOM System Fuselage MountedAntenna (FMA) and Ka-Band Radio Frequency Unit (KRFU). Separate FAAapproval will be req...	04/07/2025	Active	10061103
10061104	ARCHEION HOLDINGS, L.L.C.		FAA STC ST04354AT	DHC-8-202 DHC-8-201	Installation of an Avionica, Inc. avWiFi wireless router system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Master Data List 150137-MDL, Revision C, dated 2 February 2017 or laterFAA approved revisions.FAA approved Airplane Flight Manual Supplement for Archeion HoldingsLLC, 150137- AFMS, Revision IR, dated 21 February 2017, or later FAAapproved revisions.Instructions for Continued Airworthiness 150137-ICA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/02/2017	Active	10061104
10061109	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525	Installation of L-3 Communications Stormscope Antenna	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing CS-23 Amdt 4 paragraphs apply: 23.29, 23.301 (a), 23.303,23.305 (a) (b), 23.307 (a), 23.337 (a),23.365 (a) (b) (d), 23.561 (a),23.571, 23.571 (c), 23.573 (b...	Master Documents List ASR-2016-096-MDL-01-00 dated 20/02/2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/02/2017	Active	10061109
10061113	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04300AT-D	GV-SP GIV-X	Installation of Satcom Direct Router (SDR)This modificationinstalls various configurations of single or dualcommunication hub (SDR) together with several data systems (Ku system,SwiftBroadband, GoGo Air To Ground) supporting voice and datacommunications.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Index List, ref CE414298001 Revision C, dated 12 May 2016For the GIV-X aircraft model:- Instructions for Continued Airworthiness, ref: CE41429A005 Revision B,dated 09 May 2016- Airplane Flight Manual Supplements (depending on the SDR configurationinstalled), ref:·CE41429M001 Revision B·CE41429M002 Rev...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/02/2017	Active	10061113

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061115	PMV ENGINEERING	REV. 1		ATR 72-212 A ATR 42-500	TPED tolerance on ATR42/72	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List SCA-00930-MDL-R01 dtd. 17. Feb 2017-Instructions for Continued Airworthiness SCA-00930-ICA-R01 dtd. 17.Feb 2017or later revisions of the above listed documents approved by EASA.	Per Instructions for Continued Airworthiness SCA-00930-ICA-R01 dtd.17.Feb 2017Limited to aircraft having received the New Avionic Suite (NAS) modification 5948	06/03/2017	Active	10061115
10061116	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST01678CH	777-200	EASA validation of FAA STC ST01678CH. Installation of a General Dynamics110 VAC EmPower In-Seat Power Supply System in accordance with ArmstrongAerospace Master Data List, Doc. No. DC104-0491-00, Revision 10, dated29th April 2016 or laterapproved revisions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS 25 impacted requirements at initial issue:25.1; 25.29; 25.301; 25.303; 25.305; 25.307; 25.561; 25.601, 25.603,25.605;...	The STC installation must be performed in accordance with ArmstrongAerospace Master Data List, Doc. No. DC104-0491-00,Revision 10, dated29th April 2016, andThe Airplane Flight Manual Supplement document number ArmstrongAerospace DC303-0491-00, Revision 1 dated 12th March 2004 is a requiredon board...	See those of original FAA STC ST01678CH and those of the Airplane FlightManual Supplement Armstrong Aerospace DC303-0491-00, Revision 1 dated12th March 2004, or later approved revisions.Prior to installation of this design change it must be determined thatthe interrelationship between this design ch...	28/02/2017	Active	10061116
10061119	DART AEROSPACE Ltd.		TCCA STC SH16-17 ISSUE 1	AW139 AB139	D139-1012 Cargo Net Installations	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dart Flight Manual Supplement FMS-D139-1012, Rev. Aor laterrevisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.TCCA Supporting Letter C-16-0433, dated 2 May 2016Dart Instructions for Continued Airworthin...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/02/2017	Active	10061119
10061129	DOA AESGLOBAL LIMITED	REV. 2		767-300	Introduction of Digecor “Glide” IFE System B767Revision 1 removes the MSN limitation.Rev 2: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:The following paragraph(s) at a later amendment: CS 25 Amendment 17: CS25.29; CS 25.301; CS 25.303CS 25.305; CS 25.307;2...	AES Flight Manual Supplement No. 72 issue 1AES PRINCIPAL ICA DOCUMENT – INTRODUCTION OF DIGECOR“GLIDE LITE” IFE SYSTEM B767 No. AES-TR-1786 Issue 2AES Master Data List AES-767-3762MDL issue 11or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/04/2021	Active	10061129
10061143	DELTA ENGINEERING CORPORATION		FAA STC ST03223CH	767-200, 767-300, 767-400ER	Certification of Compatibility with Cellular and/or Wireless DataTechnologies.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.1529 at CS25 Amendment 13The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged a...	- Supplemental Type Certificate Project Results, Ref. ODA-2417-01, Rev.B, dated Jan. 13, 2017- Master Data List, Ref. DC104-9230-00 Rev. L- Aircraft Equipment Compatibility List, Ref. DC370-9230-01 Rev. G- Aircraft Equipment Compatibility List, Ref. DC370-9230-02 Rev. L- EWIS and ICA Assessment, Ref...	- Operational approval to use T-PEDs (Transmitting Portable ElectronicDevices) must be obtained separately from this STC.- This STC does not constitute installation approval of any cellular orwireless radio frequency systems using wireless data technologies.- This STC only to be used concurrently w...	02/03/2017	Active	10061143

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061156	365 AEROSPACE DDS LIMITED	REV. 1		S-76C	Installation of Nginuity DAQ9000 as an alternate Flight Data AcquisitionUnit (FDAU)Rev. 1: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDSLtd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-29 Amdt. 3:29.251, 29.1301, 29.1309, 29.1351, 29.1353, 29.1357, 29.1459, 29.1529,29.1541, A29.1, A29.2, A29.3, A29.4The requirements for environmental protection and th...	Airworthiness Limitations as per Section 4.2. of the Instructions forContinued Airworthiness ICA-0182-001, Rev Aor later revisions of the above listed documents approved by EASA.-Engineering Order EO-0182-001, Rev A- Certification Plan CCP-0182, Rev C- Instructions for Continued Airworthiness ICA-0...	This STC requires as a pre-requisite the installation of Major ChangeEASA.IM.R.C. 01404, dated 13 September 2006.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will i...	05/08/2019	Active	10061156
10061170	365 AEROSPACE DDS LIMITED	REV. 1		737-800 737-700	Change to introduce a 189Y LOPA and recline installation onto Weber C100seatsRev. 1: Transfer of STC from 365 AerospaceLtd. to 365 Aerospace DDS Ltd	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	365 Aerospace Ltd Master Data List No. MDL-0237 Revision A dated 20February 2017	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/08/2019	Active	10061170
10061176	2 EXCEL DESIGN LIMITED	REV. 4	CAA UK RESPONSIBILITY	A321-251N/-271N A321-213/-231/-232/-251N/-271N A321-211/-212/-213/-231/-232 A321-111/-112/-131/-211/-212 A321-111/-112/-131 A320-251N/-271N A320-231/-232/-233/-251N/-271N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Replacement of the Saft Groupe SA NiCad Battery, Type 2758,with theHawker Enersys Type F20/23XLM Battery, P/N 4575126-( )	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 at Amendment 17:CS 25.1CS 25.21CS 25.561CS 25.601CS 25.603CS 25.1301CS 25.1309CS 25.1351(a)(1),(2) and (d)CS 25.1353(c...	2 Excel Design Limited Master Data List No. 2XL135 LEF78(1)Issue 2dated 15 October 2020or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	This approval is limited to those aircraft serial numbers recorded on2Excel Design Limited Statement(s) of Approved Design Data No. 2XL135LEF83 (-)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed c...	21/10/2020	Active	10061176
10061179	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			A330-201/-202/-203/-223/-243	Title: A330 RAVE IFE IntegrationDescription: Installation of the Zodiac Inflight Innovations Rave™ AVODIFE system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Engineering Order, Document Number EO_M14800138_MGR_22072016, Rev 0Instructions for Continued Airworthiness, Document Number ICA_M14800138_MGR_22072016, Rev 2Aircraft Flight Manual Supplement, Document Number AFS_M14800138_MGR_21112016, Rev 0Crew Operational Manual Supplement, Document Number COMS_M...	Airberlin Technik GmbH (EASA. 21J.228) minor change Airberlin projectnumber: 07-2016 and AIRBUS Service Bulletin SB25-3641 or SB25-3642 mustbe installed prior this modificationPrior to installation of this design change it must be determined thatthe interrelationship between this design change and an...	13/03/2017	Active	10061179
10061180	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST03403NY	737-900ER/-9 737-700/-800/-900	Installation of a Intelsat Cabin Connectivity (with demod option) systemRevision 1 expands the installation of the GoGovision system to theBoeing 737-900, 737- 900ER, 737-9.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 amdt 0:CS 25 amdt 18: 25.869, 25.981, 25.1583CS 25 amdt 23: 25.853CS 25 amdt 24: 25.1581, 25.1585The req...	1. Delta Engineering Master Data List 0106-09806-2401, Revision CG dated30 September 2021;2. Instructions for ContinuedAirworthiness 0706-09423-2401, Revision Rdated 13 September2019;3. Electrical Wiring Interconnect System Instructions for ContinuedAirworthiness 0706-11345-2401, Revision A, 25 Au...	Operational approval to use T-PED's must be obtained separately fromthis STC.When installing/activating the system on the aircraft the aircraft mustcomply with the requirements this STC or other existing FAA approvedT-PED tolerance data for aircraft systems compatibility with RF (RadioFrequencies) e...	14/02/2022	Active	10061180

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061181	INTELSAT INFLIGHT LLC	REV. 1	FAA ST04116CH	SEE FAA AML	Installation of 802.11 ac protocol Cabin Wireless Access Points (acWAP)retrofit for existing Cabin Wireless Access Points.Rev. 1: Change company name from "GOGO LLC" to "Intelsat Inflight LLC".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Applicable Regulations at the latest amendment 25-0 through 25-119:25.29(a)(b); 25.30 I (a)(b); 25.303; 25.305(a)(b); 25.307(a); 25.561(c)(d);25.601; 2S.603(a)(b)(c); 25.60...	Installation Instructions as listed on FAA AML Number ST04116CH.Instructions for Continued Airworthiness (ICA) as listed on FAA AMLNumber ST04116CH.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Additional Limitations and Conditions as listed on FAAS...	06/04/2021	Active	10061181
10061190	IKHANA GROUP, LLC	REV. 1	FAA STC SA02627LA	DHC-6 SERIES 400 DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of wing hardpointsRev. 1: Name Change from "Ikhana Group Inc." to "Ikhana Group LLC."	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. IKHANA Aircraft Services Installation Drawing List No. ER218-1220,Revision NC, dated 29 December 2016 or later FAA approved revisions.2. IKHANA Aircraft Services Master Drawing List No. ER218-1221, RevisionNC, dated 29 December 2016 orlater FAA approved revisions.3. IKHANA Aircraft Services Mas...	1. Approval of this modification applies to the above notedmodelairplane series only that have Viking Post-Mod No. 6/1117 wing boxassemblies or wing box assemblies modified per IKHANA Group<(>,<)> Inc.STC No. SA00160LA-A.2. Prior to installation of this design change it must be determinedthat the i...	09/09/2021	Active	10061190
10061210	AVINCIS AVIATION ITALIA S.P.A	REV. 4		CL-215-6B11 (CL-415 VARIANT)	INSTALLATION OF AN INFRARED VISION SYSTEM.Rev. 3: Change ofSTC holder’s name from Babcock Mission CriticalServices Italia S.p.A. Divisione Ala FIssa to Avincis Aviation ItaliaS.p.A., starting from the 1st of March 2023.Rev. 4: Correction of the applicability.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Flight Manual Supplement FMS-34-45-1604-A rev. 00 dated 21/10/2016- Master document list MDL-34-45-1604-A rev. 00 dated 25/02/2017- Compliance Check List CCL-34-45-1604-A rev. 02 dated 25/02/2017or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2023	Active	10061210
10061220	STENE AVIATION, INC.		FAA STC SA2256WE	SEE FAA APPROVED MODEL LIST	Installation of leading edge "CUFF" and aileron gap covers on eachwing.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The master drawing list (MDL) as listed on the AML, or later FAAapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	09/03/2017	Active	10061220
10061221	STENE AVIATION, INC.		FAA STC SA4303WE	T182, T182T, TR182 182Q, 182R, 182S,182T, R182 182K, 182L, 182M, 182N, 182P 182E, 182F, 182G, 182H, 182J 182, 182A, 182B,182C, 182D	Installation of leading edge "CUFF" on each wing.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Stene Aviation Master Drawing List Number SASP-1, Revision A, datedNovember 20, 2015, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/03/2017	Active	10061221
10061236	LANITZ-PRENA FOLIEN FACTORY GmbH	REV. 2		SEE EASA APPROVED MODEL LIST	Application of ORATEX UL600MK3 aircraft covering system withnon-stitched integration.Rev. 2 includes “on-condition” NDTevaluation for the lifetime of thesystem.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 22.1, CS 22.21, CS22.29, CS 22.45, CS 22.63, CS 22.143, CS22.152, CS 22.201, CS 22.203,CS 22.207, CS 22.251, CS 22.301...	- Application of ORATEX covering & coating system, Doc. No.ADxC-51-C0-001, issue M, dated 5th March 2020- ORATEX Application Manual & Airplane Maintenance Manual Supplement,Doc. No. ADxC-51-001-AMM Edition 8.0, dated 6th March 2020or laterrevisions of the above listed document(s) approved/acceptedu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/05/2020	Active	10061236

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061246	S4A SOLUTIONS FOR AVIATION, S.L			C-212-CC/ C-212-DD	Installation of GPS Repeater.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement ref. A1206-HDK01 issue 2, dated 23November2016,,or later revisions of the above listed documents approved by EASA.Certification Plan ref. A1206-CPL01 issue 12, dated 28 February 2017.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/03/2017	Active	10061246
10061248	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A320-232	Cabin Retrofit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. Note: no need torecall the CB when thisbox is tickedThe Certification Basisfor the original product as amended by thefollowing additional or alternative airworthiness requirements:JAR 25 Change 1...	Master Document List CG-2500006-MD01-00 adressing:Compliance Documents in Chapter 2Instructions for Continued Airworthiness in Chapter 3or later revisions of the above listed documents approved by EASA.	Limited to S/N 2395, 2401Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	10/03/2017	Active	10061248
10061270	LEARJET Inc.		FAA STC ST00841DE	CL-600-2B16 (604 VARIANT)	Installation of Automatic Dependent Surveillance - Broadcast (ADS-B) Outfunctionality using the Rockwell Collins TDR-94D Enhanced SurveillanceMode S Transponders paired with the Rockwell Collins GPS-4000S WAAS GPSReceivers, plus installation of the IOC-4000.	The Certification Basis (CB) for the original product remains applicable to this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original productareunchanged and remain applicable to this certificate/ appr...	1. Bombardier Master Data List, Document No. BAS63010136, Rev. D, dated5 October 2016, or later FAA approved revision.2. Airplane Flight Manual Supplement AFMS BAS63040223, Rev. NC, dated 28November 2016 or later FAA approved revision.3. Instructions for Continued Airworthiness document BAS 63050061...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The Input/Output Concentrator installed by...	13/03/2017	Active	10061270
10061274	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			A330-223, A330-243 A330-201, A330-202, A330-203	A330-200 Cabin Reconfiguration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 on Non-rechargeable Lithium BatteryInstallations.- The following paragraph(s) at a later amendment: JAR 25.869, change13, OP 25-93--3.The...	- Engineering Order A330-200 Cabin Upgrade EO_M173001019_MZI_13062016Rev 0.- Instructions for Continued Airworthiness ICA_ M173001019_MZI_13062016Rev 1.- Aircraft Flight Manual Supplement AFS_173001019_DBE_21062016 Rev 0.- Document and drawing tree A330 Cabin Upgrade 17330085 Rev 3;or later revision...	For effective modification prerequisites see Document and Drawing treeA330 Cabin Upgrade 17330085 Rev 3.For effective Concurrent modifications see Document and Drawing treeA330 Cabin Upgrade 17330085 Rev 3.Note: Drawing Tree A330 Cabin Upgrade 17330085 Rev 3 includeseffectivity list of affected airc...	13/03/2017	Active	10061274
10061277	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A320-232/ A321-231 A319-132	Installation of wireless IFE System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:JAR 25.305, 25.571 (b)(2) at Change 14. CS 25.1423, 25.1703,25.1707,25.1709, 25.1711, 25.1713, 25.1715, 25.1717, 25.1719...	Turkish Technic Aircraft Flight Manual Supplement C0002-AFM-00or later revisions of the above listed documents approvedby EASA.Certification Programme C0002-CEP-03.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2017	Active	10061277
10061293	ADS-B TECHNOLOGIES, L.L.C.		FAA STC ST02479AK	SEE FAA AML	Installation of the L-3 Communications Display System EFI-650.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.NEW-PAGEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ appro...	1. Master Data List L3-EFI-650-MDL, Revision 0, dated 20 September 2016,or later FAA approved revision.2. Instructions for Continued Airworthiness L3-EFI-650-ICA, Revision 0,dated16 October 2016, or later FAA accepted revision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesw...	16/05/2017	Active	10061293

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061304	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A321-213/231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	ARINC 791 SYSTEM PROVISIONS.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TENENCIA LTD. Flight Manual Supplement No. TEN-808-47 Issue1.TENENCIA LTD. INSTRUCTIONS FOR CONTINUED AIRWORTHINESS No. TEN- 808-04Issue 1or later revisions of the above listed documents approved by EASA.TENENCIA LTD. MASTER DATA LIST No.TEN-808 Issue 1 dated 10 March 2017.	None.	15/03/2017	Active	10061304
10061309	AEROTEC & CONCEPT			787-8, 787-9	B787 DUAL MEDICAL STRETCHER INSTALLATION.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List AE16230MDL Rev.0 dated 10/03/2017.- AFM Supplement AE16230AFMS Rev.0 dated 06/01/2017.- Instructionsfor Continued Airworthiness AE16230ICA Rev.0 dated14/01/2017;or later revisions of the above listed documents approved by EASA.	- Per AFM Supplement AE16230AFMS.- Aerotec Change AE16077MAS is a pre-requisite for this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse...	16/03/2017	Active	10061309
10061316	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR02289LA	AB412/ AB412EP	Installation of Apical Industries, Inc. Cable Cutters Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. FAA approved Apical Industries, Inc. Master Document List MD412-101,Revision A, dated 23 December 2009, or later FAAapproved revision.2. Apical Industries, Inc.'s Instructionsfor Continued Airworthiness,ICA412-101, Revision N/C, dated5 January 2010, or later FAA acceptedrevision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesa...	22/03/2017	Active	10061316
10061321	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.	REV. 2	FAA ST11112SC	A320-232	Installation of a VIP Interior.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):CRI D-2302-002 (Isolated compartments)CRI D-2306-001 (Application of heat release and smoke densityrequirement to seat material)- Deviation(s):CRI D...	1. Master Document List, Associated Air Center document No. 3264000000,Revision C dated 13 October 2017.2. Instructionsfor Continued Airworthiness, Associated Air Centerdocument No. 3264050090, Revision D dated 18 August 2017.3. Aircraft Flight Manual Supplement, Associated Air Center document No.3...	The Cabin Wireless Local Area Network (WLAN) system is intended toprovide internet connection and e-mail services usingportableelectronic devices (PEDs). Any other intended function of this equipmentwill require a re-examination.Components identified in AAC document “Commercial off the Shelf PMAExc...	13/02/2018	Active	10061321
10061325	AVIDYNE CORPORATION		FAA STC SA00352BO	SEE FAA AML	Installation of an Avidyne Corporation Mode A/C/S Transponder with ADS-BOut capability, ModelAXP340 loaded with Version3.13 software (or later FAA approved version)or Model AXP322 withVersion 2.7 software (or later FAA approved version).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Avidyne Corporation Master Document List (MDL), DocumentNumberAVAXP-005, Revision 03, dated 27 October 2016, or later FAA approvedrevision.2. Avidyne Corporation Aircraft Flight Manual Supplement (AFMS) DocumentNumber 600-00309-000, Revision 01, or later FAA approved revision.3. Instructions for...	1. Model AXP340 can interface only with proven compatible avionicssystems as identified by vendor name and model numberin AvidyneCorporation Installation Manual Section 6.6.4, Document Number600-00308-000, Revision 00, dated 9 January 2015, or later FAA approvedrevision.2. Model AXP340 must have aA...	01/08/2017	Active	10061325

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061341	HELI AUSTRIA GmbH	REV. 1		AS 332 L, AS 332 L1	Installation of GARMIN GTN750 COM/ NAV/GPS System into Airbus HelicoptersAS332L and AS332L1Reason for Revision 1:Extension of the Applicability to two more NAV-Switching Unit types(SSU102F and 699 90 R 2865), Revision of Wiring Diagram, additionalInstallation Manual and Flight Manual for NAV-Switchin...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):STC CRI-F-02 Non-rechargeableLithium BatteryCS-ACNS.B.VCS.001, CS-ACNS.B.VCS.010, CS-ACNS.B.VCS.020,CS-ACNS.B.VCS.025, CS-ACNS.B.VCS.040The requireme...	Flight Manual Supplement, Doc. No. HAU-D-029-005-01, Rev. 1Flight Manual Supplement, Doc. No. HAU-D-029-005-02, Rev. 0or later revisions of the above listed documents approved by EASA.Master Document List, Doc. No. HAU-D-029-001, Rev. 1Installation Manual, Doc. No. HAU-D-029-004-01, Rev. 1Installati...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/06/2017	Active	10061341
10061345	AMAC AEROSPACE SWITZERLAND AG	REV. 2		737-700	Interior Outfitting	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-02 Isolated CompartmentsCRI D-06 Glass Screens of Displays / MonitorsCRI D-09 Shower installationCRI D-20 Installation of Glass Panels in the C...	-Master Data List MDL-FE01-2500, Rev. L dated 27.04.2018-Airplane Flight Manual Supplement AFMS-FE01-2500, Rev. D dated12.04.2018-Instructions for Continued Airworthiness ICA-FE01-2500 Rev. C dated08.03.2017or later revisions of the above listed document(s) approved under theEASA system.	For aircraft operations with Cabin CrewLimited to MSN 62699Per AFMS-FE01-2500Per ICA-FE01-2500Prerequesite Installations:EASA STC 10042295 (FAA STC ST01697SE) Low Cabin AltitudeEASA STC LBA. 21E2.TA0311 (FAA STC ST01340NY) TIOS – Fin Top Antennastructural provisionsEASA Project 0010043505 (FAA Projec...	07/05/2018	Active	10061345
10061347	CORPORATION LOGIC AIR Inc.	REV. 1	TCCA SA15-84	737-300, 737-400, 737-500 737-300 / 737-400	Installation of Second Flight Management Computer (FMC)Revision 1 includes 737-500 model.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Data Summary – Doc Ref: K403000 Rev DInstructions for Continued Airworthiness – Doc Ref: MM-34354-1 Rev 1or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/10/2020	Active	10061347
10061349	BELL HELICOPTER TEXTRON, Inc.		FAA STC SH3884SW	212/ 412/ 412EP	Installation of Radome assembly.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeronautical Accessories, Inc. Drawing 22HP750<(>,<)> Rev. A<(>,<)>dated 26 March 1988.Servo Mount installation in accordance with Aeronautical Accessories,Inc. Drawing List Report AA-92052, dated 27 April 1992 or FAA approvedrevisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/03/2017	Active	10061349
10061350	S-TEC CORPORATION		FAA STC SA09261AC-D	182S	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-586.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Bulletin No. 686, Revision 2, dated 2 February 2001.2. Master Drawing List No. 92779, Revision B, dated 2 February 2001 orlater FAA Approved revisions of the above data (28 Volt System).3. FAA/DAS Approved Pilot's Operating Handbook and/or Airplane FlightManual Supplement, P/N 891461, dated 31 Ju...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. FAA/DAS Approved Pilot's Operating Handboo...	28/03/2017	Active	10061350

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061372	EIRTECH AVIATION SERVICES LIMITED			A321-231, A321-232 A321-211, A321-212, A321-213 A321-111, A321-112, A321-131 A320-251N, A320-271N A320-232, A320-233 A320-215, A320-216, A320-231 A320-211, A320-212, A320-214 A319-131, A319-132, A319-133 A319-113, A319-114, A319-115 A318-122, A319-111, A319-112 A318-111, A318-112, A318-121	A320 SERIES ZERO PASSENGER LOPA.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 18.The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	Eirtech Aviation Services Aircraft Flight Manual SupplementFMS/883-015or later revisions of the above listed documentsapproved by EASA.Master Document List MDL/883-099.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/03/2017	Active	10061372
10061373	CHICAGO JET GROUP, LLC		FAA STC ST03262CH	SEE FAA AML	Installation of a Data Link Communication System supportingAir TrafficServices (ATS) utilizing SATCOM with a compliantCommunicationsManagement Unit.	The Certification Basis (CB) for the original product is amended asdescribed in the FAA AML.NEW-PAGEThe requirements for environmental protection and the associatedcertified noiseand/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Chicago Jet Group LLC, Master Drawing List Document No. DB1201002Revision C, dated 17 February 2015, or later FAA approved revision.2. FAA Approved Airplane Flight Manual Supplement (AFMS) as listed onthe AML number ST03262CH, or later FAA approved revision.3. AML item 1:Instructions for Continue...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesw...	17/05/2017	Active	10061373
10061374	CHICAGO JET GROUP, LLC		FAA STC ST03369CH	SEE FAA AML	Certification of the aircraft data link system used for communicationsupporting Air Traffic Services (ATS) andinstallation of an ICG Iridium Satcom, installation of the UniversalAvionics UniLink® UL-801 CommunicationsManagement Unit, and UNS-1(-)w Flight Management System (s).	The Certification Basis (CB) for the original product is amended asindicated in the FAA AML.The requirements for environmental protection and the associatedcertified noise and/ oremissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Chicago Jet Group Master Drawing List Doc. No. DB1211002Revision D,dated 5 August 2015, or later FAA approved revision.2. FAA approved Airplane Flight Manual Supplement as listed on AMLnumber ST03369CH, or later FAA approved revision.3. AML Item 1:a. The aircraft must be maintained in accordance...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesw...	17/05/2017	Active	10061374
10061389	365 AEROSPACE DDS LIMITED	REV. 2		ATR 72-211/-212/-212A ATR 72-201/-202 ATR 72-101/-102 ATR 42-200/-300/-400/-500	Change to introduce a Zero Pax ConfigurationRev. 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDS Ltd	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 Amendment 18:25.29, 25.301, 25.303, 25.305, 25.307<(>,<)>25.601, 25.785, 25.789,25.791, 25.803<(>,<)> 25.807, 25.811,...	365 Aerospace Instructions for Continued Airworthiness – 'Change tointroduce a Zero Pax Configuration, Configuration 1'ICA-0249-001 Issue A365 Aerospace Instructions for ContinuedAirworthiness – 'Change tointroduce a Zero Pax Configuration, Configuration 2' ICA-0249-002 IssueA365 Aerospace Instruc...	Refer to 365 Aerospace Master Data List No. MDL-0249 for aircraftapplicability.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	05/08/2019	Active	10061389
10061394	FLYING COLOURS CORP.		TCCA C-LSA16-075/D ISSUE 1	BD-700-1A11	Installation<(>,<)> SATCOM Direct SDR Network Router.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	B/E Aerospace Flight Manual Supplement No. K923090 RevisionNC;Flying Colours Corp. Instructions for Continued Airworthiness No.K923075 Revision NC;or later revisions of the abovelisted documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agree...	RESTRICTED TO ASN 9222.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	22/03/2017	Active	10061394

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061401	SABENA TECHNICS BOD	REV. 1		A340-541	Ka Band system installationThe modification consists in theinstallation of new Satcom system,named as JetWave, and operating in the Ka band. Line Replaceable Units(LRU) and a large antenna on top of the fuselage are supporting theconnection of the existing IFE system to the satellite network.The Re...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): B-1301-002: Vibration & Buffetingcompliance criteria for large external antenna installation.The requirements for environmental protectionc...	- Modification Approval Sheet, ref: MAS-S-00-4052 issue 4 dated 20 July2017;- Instruction for Continued Airworthiness, ref: ICA-F4042-00-010 issue Bdated 06 September 2017;- Aircraft Flight Manual Supplement, ref: AFMS-F4042-00-022 revision 3dated 20 March 2017;or later revisions of the above listed...	Modification applicable only to MSN 560.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	06/09/2017	Active	10061401
10061409	LUFTHANSA TECHNIK AG			A340-313	A340 VIP Cabin Modification.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document, Ref. STDD00-16/21MIssue 01 Rev01;- ICA, Ref. A-00-16/78-ICA Issue 01 Rev 00;-Compliance Record List, Ref. CRL00-16/21M Issue 01 Rev 00;-AFM, Ref. A-00-16/78-AFM Issue 01 Rev 00;or later revisionsof the above listed documents approved by EASA.	The following prerequisite approvals must be installed in the aircraft: - LHT EASA STC 10033112 Rev. 0 and MinorChanges with Refs. CRASNo. 3408 and No. MX-4680 and No. MX-5227. - ZNAT EASA STC 10060986 Rev. 0Prior to installation of this design change it must be determined thatthe int...	23/03/2017	Active	10061409
10061410	AIRBUS HELICOPTERS DEUTSCHLAND GmbH	REV. 1		EC135 T3 (CPDS) EC135 T2, EC135 T2 (CPDS) EC135 T2+ EC135 T1, EC135 T1 (CDS) EC135 T1(CPDS) EC135 P3 (CPDS) EC135 P2, EC135 P2 (CPDS) EC135 P2+ EC135 P1, EC135 P1 (CDS) EC135 P1(CPDS)	Floice InstallationRevision 1: Addition of EC135 P3(CPDS) and EC135 T3(CPDS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-For original revision of this STC:Flight Manual SupplementSK-MAC-168-SUP-B-1142, Revision B-For revision 1 of this STC:Flight Manual Supplement, SK-MAC-168-SUP-B-1142, Revision C dated April2018or later revisions of the above listed document(s) approved under theEASA system.For original revision o...	Limited to Visual Metrological Conditions (VMC) / For mission purposesonly.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the ai...	17/05/2018	Active	10061410
10061417	BRISTOW HELICOPTERS Ltd.		CAA UK RESPONSIBILITY	AS 350 BB	Omnibus Modification MOD/350/4935 on AS350BB for DHFS Contract.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instruction for Continued Airworthiness as provided in BHL.350.10380,issue A, dated 13th March 2017. No ALS identified for this modification.BHL. 350.10380 “Certification Review ofModification for EASA STCApplication Purposes”, issue A, dated 13th March 2017.	See the aircraft MSNs list as provided in BHL.350.10380, issue A, dated13th March 2017.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installeddesign change and/ or repair will introduce noadverse effect...	24/03/2017	Active	10061417
10061419	CMD FLIGHT SOLUTIONS, LLC	REV. 1	FAA ST04159CH	SEE FAA AML	Certification of Automatic Dependent Surveillance - Broadcast (ADS-B)Out for installing Honeywell Primus II Communications Units RCZ-8XXTransponders.Revision 1: Amendment of AML with the addition of:- Dornier 328-100/-200.- Textron 680.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- CMD Flight Solutions Master Data List, Document No. DB 1606001,Revision D, dated 24 May 2017;- FAA Approved Airplane Flight Manual Supplement (AFMS) as listed on theAML number ST04159CH, or later FAA approved revision;- Instructions for Continued Airworthiness (ICA) as listed on AML NumberST04159C...	- Successful completion of Ground Test Plan DB1606004, Revison A, dated17 October 2016, or later FAA approved revision must be accomplishedfollowing implementation of this STC.- The STC is valid for those aircraft types and models approvedby EASAwithin the FAA AML ST04159CH amended July 06, 2017.Pr...	28/09/2017	Active	10061419

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061420	AERO TWIN, Inc.		FAA STC SA4651NM	208, 208B	Fabrication and Installation of Aero Twin, Inc. Main Gear GravelDeflector Kit No. GD8-100.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero Twin, Inc. Master Data List No. GD8-100 dated 16 June 1991, orlater FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/05/2017	Active	10061420
10061425	AERO TWIN, Inc.		FAA STC SA2335NM	208, 208B	Installation of rubber Nose Tire Scraper/ Gravel Deflector (P/NATI-208TS) in conjunction with 22x8.0-8 nose tire.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing List No. 208TS, dated 31 January 1986, or later FAA approvedrevision. 2. Aero Twin, Inc. Installation DrawingNo. ATI-0010, dated 28 November1985, or later FAA approved revision.	1. The approval of this change in type design applies to the basicTextron model 208 and 208B airplanes that have been equipped with the22x8.0-8 nose wheel/tire installation.2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and a...	29/05/2017	Active	10061425
10061426	ASI AVIATION			B300 AND B300C	Installation, operation and maintenance of ASI Aviation design change“Installation of VHF marine” in accordance with DL– Data List for FAM518 No. 027 issue 00, dated 28 October 2017.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- DL – Data List for FAM 518 No. 027 issue 00, dated 28 October 2017;- Aircraft Maintenance Manual Supplement MM-350-950000 issue 00, dated21 December 2016;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/03/2017	Active	10061426
10061436	AIRBORNE TECHNOLOGIES GmbH			EC135 P2+	Operator Seat Installation (Fischer Seat 170/260 H160)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:Amendment 2 of CS-27 has been chosen for the following paragraphs: CS27.21, CS27.29, CS27.301, CS27.303, CS27.305, CS27.307...	- Flight Manual Supplement: STC-107-0-AFM, Rev. 1or later revisions of the above listed documents approved by EASA.- Maintenance Manual Supplement: STC-107-0-AMM, Rev. 0- Installation Instruction: STC-107-0-II, Rev. 0	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/03/2017	Active	10061436
10061437	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			DHC-8-315 DHC-8-102	Installation of NNAL527 Airborne Stretcher on DHC-8 Series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-01 MEDEVACthe followingparagraph(s) at a later amendment:JAR 25.853 at Change 13 for DHC-100The requirements for environmental protection and t...	-Master Data List MODM00045_MDL Rev. 3 dtd. 27/03/2017-Aircraft Flight Manual Supplement MODM00045_AFMS Rev. 3 dtd. 06/03/2017- Instructions for Continued Airworthiness MODM00045_ICA Rev. 1 dtd.01/11/2016or later revisions of the above listed documents approved by EASA.	-Per Aircraft Flight Manual Supplement MODM00045_AFMS-Design change MODM00007 – FWD LH Cabin Draft Bulkhead Modification isrequired as prerequisite for DHC-8-100 aircraft.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any ot...	28/03/2017	Active	10061437
10061444	AIRBUS S.A.S.			A330-203	Cabin Removal for MRTT Conversion.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	ACJC AFM Supplement for MSN 0892 and 0898 Ref. FM-S MOD CJ2077 and MODCJ2078 dated 01.02.2017or later revisions of the above listed documents approved by EASA.- A330 MRTT Cabin Removal Certification Plan Ref. ACJC-AJA-16029.- ACJC Modification Approval Sheet Ref. CJ2077 Issue 1 dated 10.03.2017.	1. STC is limited for installation on MSN 0892 and 08982. Zero occupancy and no cargo allowed in the passenger cabin duringTTOL and flight (Ref. FM-S MOD CJ2077 and MOD CJ2078 dated 01.02.2017).Prior to installation of this design change it must be determined thatthe interrelationship between this d...	28/03/2017	Active	10061444

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061445	IKHANA GROUP, LLC	REV. 3	FAA STC SA02267LA	DHC-6-300, DHC-6-400	This STC approves the Viking Air Limited DHC-6-300 and DHC-6-400landplanes to take off and land at a maximum weight of 14,000 pounds andDHC-6-300 and DHC-6-400 floatplanes to takeoff and land at a maximumweight of 13,600 pounds when operated under Restricted Category for thespecial purpose of fores...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. R. W. Martin Master Data List No. ER218-3041, Revision A, dated 12November 2009, or later FAA approved revisions, and if applicable, R. W.Martin Master Data List No. 218-3051, Revision NC, dated 5 July 2010, orlater FAA approved revisions (DHC-6-300 and DHC-6-400 landplane totakeoff at a maximumw...	1. This airplane at takeoff and landing weight above 12,500pounds mustbe operated under Restricted Category.2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will i...	09/09/2021	Active	10061445
10061450	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		DORNIER 228-212	Approval of EFIS installation & Avionics Upgrade.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI B-52 Human Factors CRI F-52 HIRF CRI F-54 Lightning Indirecteffec...	Installation in accordance with Scandinavian Avionics Engineering Orderref 2102491-EO Issue 1 dated 28.03.2017 and Installation Documentsreferenced in report 2102491 STC Issue 1 dated 28.03.2017.Operate in accordance with Scandinavian Avionics Aircraft Flight ManualSupplements:-2102 491-AM-A EFIS & E...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/03/2017	Active	10061450
10061456	AIRBUS S.A.S.			A330-203	CABIN INSTALLATION FOR MRTT CONVERSION.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ACJC Modification Approval Sheet Ref. CJ2078 dated 10.03.2017.- A330MRTT Cabin Installation Certification Plan Ref. ACJC-AJA-16030.	1. STC is limited for installation on MSN 0892 and 0898.2. Installation of this STC is in conjunction with EASA STC 10061444.3. Zero occupancy and no cargo allowed in the passenger cabin duringTTOL and flight.Prior to installation of this design change it must be determinedthatthe interrelationship...	29/03/2017	Active	10061456
10061459	AEROTEC & CONCEPT			767-300	KA BAND Antenna installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-01: Vibration and buffeting.The following paragraph(s) at a later amendment:CS 25 Amdt 15: CS25.23, 25.301, 25.305, 25.365, 25.571, 25....	MASTER DATA LIST Doc N°: AE15239MDL Rev.0 dated 28/03/2017.INSTRUCTIONS FOR CONTINUED AIRWORTHINESS Doc N°:AE15239ICA Rev: 1 dated20/02/2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/03/2017	Active	10061459
10061462	AIRBORNE TECHNOLOGIES GmbH			EC135 P2+	TRAKKA A 800 Searchlight Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following requirements of CS 27 Amendment 2 are applicable to thischange: CS27.21; CS27.29; CS27.45; CS29.45; CS29.53; CS29.64;CS29.67(a); CS29.79; CS27.141; CS27.143;...	-STC-106-0-AFM, Rev. 1, dated 15-March-2017, AFM Supplementor later revisions of the above listed documents approved byEASA.-STC-106-0-AMM, Revision 1, dated 03-03-2017, Maintenance ManualSupplement-STC-106-0-II, Revision 2, dated 15-Mar-2017, Installation Instructions-STC-AT-106, Revision 3, 24-Ma...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/03/2017	Active	10061462

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061463	AMAC AEROSPACE SWITZERLAND AG			737-700	Installation of gaseous passenger oxygen system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Special Condition(s):CRI F-13 Installation of a therapeutic oxygen system formedical use ona Boeing 737-700 AircraftThe requirements forenvironmental protection and the associatedcertified noise a...	-Master Data List MDL-B7371-3500 Rev. Rev B dated 29.03.2017-Airplane Flight Manual Supplement AFMS-B7371-3500 Rev. B dtd.23-Mar-2017-Instructions for Continued Airworthiness ICA-B7371-3500 Rev. C dtd.28-Mar-2017or later revisions of the above listed documents approved by EASA.	Limited to MSN 62699Per AFMS-B7371-3500Per ICA-B7371-3500Prior to installation of this design change it must be determined thatthe interrelationship between this design change andany otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the...	31/03/2017	Active	10061463
10061473	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			525, 525A	ADS-B upgrade of Garmin GTX-330D.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS-ACNS.D.ELS. 001, 010, 015, 020, 025, 030, 040, 045, 050, 055, 060, 065<(>,<) >CS-ACNS.D.EHS.001, 010, 015, 020, 025<(>,<)>...	Airplane Flight Manual Supplement 2017-2-8, Amdt. IRor later revisions of the above listed documents approved by EASA.-Master Documents List 2017-2-16, Amdt. IR.- Engineering Order 2017-2, Amdt. IR.- Maintenance Manual Supplement (incl. Instructions for ContinuedAirworthiness) 2017-2-10, Amdt. IR....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/03/2017	Active	10061473
10061475	MAGELLAN SERVICES COMPANY	REV. 1	FAA STC ST11068SC	737-700/ 737-800/ 737-900/-8	Installation of a dual port heated drain mast assembly.Revision 1: Additional model in the applicability list	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 at amendment 11: 25.613, 25.1360The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areu...	Magellan Services Company Master Document List 1002000000, Rev. E, dated21 September 2012, or later FAA approved revision.Instructions for Continued Airworthiness, Magellan Services CompanyDocument Number 1002050090, Rev. A, dated 21 November 2011, or later FAAaccepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/09/2020	Active	10061475
10061476	MT-PROPELLER ENTWICKLUNG GmbH			A-1B, A-1C-180 A-1, A-1A	MTV-9-B/200-52( ) on Aviat Husky A-1( )	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS-36, Amendment 4, FAR 36,Amendment 36-30This certificate/ approval involves a change to the requirements forenvironmenta...	According to MT-Propeller Master Documentation List No. E-2845, Rev 0To be operated in accordance with MT-Propeller AFM-S Document No.E-2852, Rev 0or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No. E-2853, Rev 0,or later Revisio...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	03/04/2017	Active	10061476
10061477	TELEDYNE CONTROLS, LLC		FAA STC ST02622LA	ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ	Installation of Teledyne Controls Wireless Ground Link - Quick AccessRecorder (WQAR)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Teledyne Controls Master Data List Document No. MDL 2243800-E190,Revision "-", dated 30 August 2016, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/10/2017	Active	10061477

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061480	EMBRAER S.A.	REV. 1	ANAC PROCESS H. 02-4766-0	EMB-500	MEPT CONFIGURATION (MULTI-ENGINE PILOT TRAINING)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	To be installed in accordance with documents listed in Master DocumentList ESCCCD063 rev.E dated 9th Jan 2017To be operated in accordance with AFM Supplement H. 02.4766-0/EASA/ 2017rev.I.R. dated 22nd March 2017To be maintained in accordancewith Instructions for ContinuedAirworthiness ESCMSD031 rev.D...	None	06/04/2017	Active	10061480
10061481	DAO AVIATION A/ S	REV. 1		B200	Installation of Garmin Radar GWX70 interfaced with GTN750	See appendix of TVThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List DAO-DO-0569-MDL-00 dated 21-03-2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/04/2017	Active	10061481
10061484	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		767-300	Installation of Artex C406-2 Fixed ELT.Rev. 1: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): The followingSpecial Condition is applicable tothis change: CRI-F101 Non-Rechargeable Lithium Battery Installation.- The following pa...	- 13065-AFM-00001, Issue 1, Flight Manual Supplement, Installation ofARTEX Model C406-2 Fixed ELT;or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.- ATL/767/013, Issue 4, Change bulletin, Installation of Artex ModelC406-2 Fixed ELT.- MDL-13065-00001, Master D...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/11/2021	Active	10061484
10061493	HARTZELL PROPELLER LLC		FAA STC SA04045CH	PA-46-500TP (MERIDIAN)	Installation of 5-blade Raptor propellerInstallation of Hartzell propeller model 5D3-N338A1/78D01B onPA-46-500TP, S/N 4697001 and up	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23.907, Amendment 3This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	-AFMS_020215, Initial Release (IR)or later revisions of theabove listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures ofEU/USA Bilateral Agreement.-INST_020215, Initial Release (IR...	S/N 4697001 and upPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	04/04/2017	Active	10061493
10061494	AIRCRAFT SYSTEMS AND MANUFACTURIN G,INC		FAA STC ST11144SC	737-500 737-400 737-300	Installation of Extended Squitter Mode S Transponder and GPS PositionSource	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:Regulations at the latest amendment 25-0 through 25-136:14 CFR§ 25.29 b; 25.251; 25.301; 25.303; 25.307; 25.561; 25.581 a,...	1. Aircraft Systems & Manufacturing, Inc. Top Drawing List No. 5704-0001-00, Rev. K, dated 26 September 2016, or later FAA approvedrevision.2. Airplane Flight Manual Supplement No. 5704-2160-00, Rev. A, dated 27January 2016, or later FAA approved revision, or No. 5704-2160-01, dated27 December 2016,...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/04/2017	Active	10061494

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061499	ANCRA INTERNATIONAL LLC		FAA STC ST02620LA	CL-600-2B19 (RJ SERIES 100)	Installation of main deck cargo loading system.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Ancra International LLC Controlled Data List DL85400, Revision D,dated 4 May 2016, or later FAA approved revision. 2.Instructions for Continued Airworthiness Cargo Handling System PartNumbers 85400-10 and 85400-11 installed on CRJ200 (CL-600-2B19) Freighter.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. EASA STC's 10061615 and 10061681 must be i...	07/05/2018	Active	10061499
10061529	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 355 NP	AutoPilot HDG mode-GPS Coupling with GTN650 as per change AHUK/355/3073.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AS355 FMS SUPPLEMENT No: 103, AUTOPILOT GPS COUPLING WITH GTN650,AHUK/355-FMS-103, Rev. C, April 2017or later revisionsof the above listed documents approved by EASA.Instruction for continued airworthiness, ICA/3553073-01, Rev. A, 14thDecember 2016 (No ALS identified for this STC).Design Compliance...	This STC is compatible only with Autopilot Configuration asper OEMAS355 RFM SUP. 16 (AFCS SFIM 85 T 31, 3-axis, with optional coupler) andAHUK SPP. 355-FMS-101 (Installation of GTN650 as primary COM-NAV).Prior to installation of this design change it must be determined thatthe interrelationship bet...	07/04/2017	Active	10061529
10061532	BOMBARDIER Inc.		TCCA SA02-131 ISSUE 3	BD-700-1A10	EASA validation of Transport Canada Supplemental Type CertificateSA02-131 at Issue 3:Upgrade to Honeywell MCS-7000 SATCOM	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification to be completed in accordance with Aero Consulting ServicesModification Data Summary Number D39300 Revision B.Honeywell MC-7000 Satcom to be maintained in accordance withInstructions for Continued Airworthiness Maintenance Manual SupplementD39371 Rev A.or later revisions of the above li...	Installation of Honeywell MCS-6000 Satcom System in accordance withBombardier Service Bulletin SB700-23-001 is a pre-requisite for thismodification.Prior to installation of this design change it must be determined thatthe interrelationshipbetween this design change and any otherpreviously installed...	10/04/2017	Active	10061532
10061533	GULFSTREAM AEROSPACE CORPORATION		FAA ST10760SC-D	GULFSTREAM 200/ GALAXY	Installation of an Aircell Axxess II Airborne Satcom Systemwith anAircell Cabin Telecommunications Router (CTR) --OR--an Aircell CabinTelecommunications Router (CTR) ONLY --OR--an Aircell Air to Ground (ATG) Communications System in combination with either the AircellAxxess II Airborne Satcom System...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Gulfstream Index List GA212038002, Rev Q, dated 15 July 2016Instructions for Continued Airworthiness GA24203A001 Rev. Ddated 2November 2010Flight Manual Supplements:Flight ManualSupplement GA21203MOOI, Rev -, dated 14 August 2009 isrequired for the Aircell Airborne Axxess II Satcom System.Flight M...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/04/2017	Active	10061533
10061534	GULFSTREAM AEROSPACE CORPORATION		FAA ST10761SC-D	GULFSTREAM 200/ GALAXY	Installation of a Thrane and Thrane Aero – SB Lite High Speed DataSystem	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Gulfstream Index List GA213038001, Rev. KAirplane Flight Manual Supplement GA21303M001 Rev. –Instructions for ContinuedAirworthiness GA24303A001 Rev. Aor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis deci...	STC ST10760SC-D is required prior to or concurrently with thisinstallationPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the air...	10/04/2017	Active	10061534

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061535	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		DA 40 D	Installation of Garmin G500 system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS-23, Amendment 423, 251, 301, 303, 305, 307, 337, 561, 603, 605, 607, 609, 611, 613,771, 773, 777, 863, 867, 1301, 130...	Flight Manual Supplement ASR-2015-115-FMS-05-00, Rev. 00or later revisions of the above listed documents approved by EASA.Certification Report (including Declaration of Compliance) ASR-2015-115-CEP-03-00, Rev. 00.Project Description ASR-2015-115-PRD-04-00, Rev. 00.Instructions for Installation ASR-2...	A suitable Garmin GPS System must have been already installed.This STC includes the installation of Garmin´s Synthetic Vision (SVT)Option (Software).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installe...	12/04/2017	Active	10061535
10061536	ASI AVIATION			B300	POLMAR mission equipment installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Aircraft Flight Manual Supplement - Document n°: POH-350-958000 Issue00, dated 09 March 2017Chapter 05 of Aircraft Maintenance Manual Supplement - Document n °:MM-350-958000 Issue 01<(>,<)> dated24 March 2017or later revisions of the above listed documents approved by EASA.	None.	10/04/2017	Active	10061536
10061569	AEROSERVIS, S.R.O.			L 410 UVP-E/ L 410 UVP-E20	Installation of Chelton IDU-450 EFIS.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forSpecial Condition (s):CRI F-01 SC-F23.1308<(>,<)> CRI F-02 SC-F23.1309(e) and SC-F23.867, CRIF-03 SC-F23.1309(e).The requirements for environmental protection and the as...	Certification program AE 118016 P Rev. H.The Flight Manual Supplement:L 410 UVP-E FLIGHT MANUAL SUPPLEMENT, Nov 10/16, STC AE/118-DLP1-9.L 410 UVP-E20 FLIGHT MANUAL SUPPLEMENT, Nov 10/16, STC AE/118-DLP11-19or later revisions of the above listed documents approved by EASA.Master Document list AE1180...	None.	12/04/2017	Active	10061569
10061585	SHADIN AVIONICS		FAA STC SR04158CH	SEE FAA AML	Installation of a fuel flow adapter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Shadin Avionics documents as listed on AML No. SR04158CH, or later FAAapproved revision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This installation requires previous or con...	04/07/2017	Active	10061585
10061588	AEROMECH Inc.		FAA STC ST02509SE	ATR 72-212 ATR 72-202, ATR 72-211, ATR 72-102, ATR 72-201, ATR 42-320, ATR 72-101, ATR 42-200, ATR 42-300,	Installation of dual Garmin GTX 3000 Transponders with ADS-B Out.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List AM0293-DL02-00, Revision A, dated 16 March 2017 orlater FAA-approved revision.2. ATR42-200, ATR42-300, and ATR42-320 AIRPLANES:- Instructions for Continued Airworthiness, AM0293-IC01-01, Revision -,dated 26 February 2017 or later FAA-accepted revision.- FAA-approved Airplane Flig...	1. Aircraft must be modified with dual GTN 72S GPS Navigator System perGarmin EASA STC 10048231.2. Aircraft must be modified with ACSS RCZ 852 Transponders per EASA STC10042297.3.Prior to installation of this design change it must be determinedthat the interrelationship between this design change a...	21/04/2017	Active	10061588

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061589	STAR AVIATION, Inc.		FAA STC ST03729NY	747-400	Installation and modification upgrade of the existing CabinWirelessAccess Point (CWAP), SMART monitor and file server	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:25.869(a)(4), 25.899 (a)(1)(3) and 25.899(b)(1)(2) at CS25 Amdt.0The requirements for environmental protection and the assoc...	- Airplane Flight Manual Supplement, Ref. R44-1439, Rev. G- Instructions for Continued Airworthiness, Ref. R44-1405, Rev. Hor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the TechnicalU...	- The following STCs are pre-requisites to this installation: - EASA STC Ref. EASA.IM.A.S. 00285 - EASA STC Ref. 10041648- Prior to activation of a CWAP, it must be shownthat the aircraft iscompatible with transmittable portable electronic devices (T-PED)- No design changes to required air...	19/04/2017	Active	10061589
10061590	PMV ENGINEERING	REV. 3		777-300, 777-300ER 777-200, 777-200LR	TPED tolerance on B777.The change consists of introducing the updated ED-130A/DO-363 and usingthe EASA CM-ES-003 (PED tolerance) instead of CRI WLAN and TGL29.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 25.1301(a)(b)(c), 25.1309(a)(b)(c), 25.1431(a)(b)(c)(d), 25.1529 at CS 25 Amdt 4.The requirements for environmental protect...	- MASTER DOCUMENT LIST, ref: SCA-00800-MDL-R05, dated 27/02/2018;- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: SCA-00800-ICA-R02,dated 27/02/2018;- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: SCA-00800-ICA-S01-R02,dated 27/02/2018;- AIRCRAF FLIGHT MANUAL SUPPLEMENT, ref: SCA-00800-AFMS-R00, da...	Per applicable AFM Supplement SCA-00800-AFMS.Per applicableInstructions for Continued Airworthiness SCA-00800-ICA.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair wil...	06/03/2018	Active	10061590
10061591	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED	REV. 1	FAA STC SR02666CH	S-92A	Installation of air ambulance conversion.EASA STC 10061591 Rev.1 reflects the transfer of EASA STC 10061591 fromSNAKY CREEK ENTERPRISES, LLC d/b/a/ SPECTRUM AEROMED to SPECTRUMAEROMED, LCC d/b/a SPECTRUM AEROMED.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Spectrum Aeromed Master Drawing List 7009-1DL, Revision 4, dated 10March 2014;2. Flight Manual Supplement, 7009-1FMS, dated 19 November 2008;3. Instructions for Continued Airworthiness, Manual 7009-1MM, norevision, dated 22 September 2008;or later revisions of the above listed document (s) approve...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2019	Active	10061591
10061615	AERONAUTICAL ENGINEERS Inc.			CL-600-2B19	CRJ-200Passenger to Freighter ConversionCRJ-200 Passenger to Freighter Conversion. This modification adds alarge cargo door forward of the wing, 9G barrier per Ventura AerospaceLLC FAA-STC no. ST02607LA, Class E cargo compartment, and cargo handlingsystem by Ancra International LLC FAA-STC no. ST026...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01 Class E Cargo Compartments FireProtection of Essential Systems, CRI D-02 Supernumerary AreaThe requirements for environmental protection and...	-AEI, Master Data List, doc. No. R-891, revision G-AEI, Aircraft Flight Manual Supplement, doc.no. R-926, revision B,dated 13 April 2018.-Weight and Balance Control and Loading Manual Supplement, doc no. R-923rev C-Aircraft Maintenance Manual Supplement, doc. no. R-924, revision B.- Supplemental Stru...	The additional installation of a rigid main deck cargo barrier, per EASASTC 10061681 (FAA STC ST02607LA) and cargo handling system per EASA STC10061499 (FAA STC ST02620LA) which is compatible with this STC isrequired.Prior to installation of this change/repair it must be determined thatthe interrela...	07/05/2018	Active	10061615
10061623	AVCON INDUSTRIES, Inc.		FAA STC ST01783WI	55, 55B, 55C, 60 31, 31A, 35, 35A, 36, 36A, 25, 25A, 25B, 25C, 25D, 25F,	Installation of Internal Wing Hardpoints.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Butler National Corporation Master Data List, No. 02101000,Rev IR,dated 27 April 2015, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/06/2017	Active	10061623

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061628	DOA AESGLOBAL LIMITED	REV. 3		767-300	Introduction of a Twin Class Cabin ConfigurationRevision 1 removes the MSN limitation.Revision 2 corrects the limitations. Revision 3 Transfer from AES Ltd. to new STC holder AESGlobal Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 18:25.29; 25.301; 25.303; 25.305; 25.307; 25.365; 25.601; 25.603; 25.605;25.611; 25.613; 25.619; 25.625; 2...	AES PRINCIPAL ICA DOCUMENT No. AES-TR-1950 Issue 2AES Master Data List No. AES-767-3793MDL issue 3or later revisions ofthe above listed document(s) approved/acceptedunder the EASA system.	The following modifications are prerequisites for this STC:AES-767-3767 - INTRODUCTION OF SINGLE CLASS CABIN CONFIGURATION(MINOR) AES-767-4128 - ACTIVATION OF A TWIN CLASS DIGECOR 'GLIDE' IFESYSTEM-B767 (EASA STC No. 10061629)AES-767-4135 - INTRODUCTION OF A TWIN CLASS DIGECOR 'GLIDE' IFE...	28/04/2021	Active	10061628
10061629	DOA AESGLOBAL LIMITED	REV. 2		767-300	Activation of Twin Class Digecor "Glide" IFE System - B767Revision 1 removes the MSN limitation.Rev 2: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 18 - CS25.29; CS 25.301; CS 25.303CS 25.305; CS 25.307; CS 25.581; CS 25.601; CS 25.603; CS 25.605; CS25.6...	AES Flight Manual Supplement No. 76 Issue 2AES PRINCIPAL DOCUMENT – INSTRUCTIONS FORCONTINUED AIRWORTHINESS – ACTIVATION OF A TWINCLASS DIGECOR 'GLIDE' IFE SYSTEM – B767 No. AES-TR-2007 Issue 3AES Master Data List AES-767-4128MDL issue 5orlater revisions of the above listed document (s) approved/acc...	The following modifications require embodiment prior to or concurrentlywith this Major change: 1. Modification AES-767-3793 [EASA STC 10061628] - Introduction ofTwin Class Cabin Configuration – B767 2. Modification AES-767-4135 - Introduction of Twin Class Digecor'Glide' IFE System ProvisionsD...	28/04/2021	Active	10061629
10061630	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CL-600-2B16 (604 VARIANT)	INTRODUCTION OF CORPORATE VIP INTERIOR	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-01 GLASS SCREENS OF DISPLAYS/MONITORS	STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0145 Issue 1or later revisions of the above listed documents approved by EASA.STC Twenty One Ltd Master Document List No. S21.MDL-1347 Issue 1	The wireless functions are not certified as part of this design changeand are to be certified under separate EASA approved design changeaction (ref EASA STC 10049203 Rev 1)	21/04/2017	Active	10061630
10061636	AVMAX AVIATION SERVICES Inc.		TCCA STC C-LSA13-159/D	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103	Installation of two batteries - Structural Provisions Only	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-CE176-401, Issue D, dated 1st of April, 2016, Engineering Order-CE176-900, Issue F, dated 7th of December 2016, MasterData List,Installation of Dual Batteries Structural Provisionsor later revisions of the above listed documents approvedby EASA inaccordance with the Technical Implementation Proce...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/04/2017	Active	10061636
10061638	AVMAX AVIATION SERVICES Inc.		TCCA STC SA03-45 ISSUE 4	DHC-8-311/DHC-8-314/ DHC-8-315 DHC-8-201/DHC-8-202/ DHC-8-301 DHC-8-102/DHC-8-103/ DHC-8-106	Passenger Briefing System Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Configuration 1 CD Passenger Briefing System- 92023-401, Revision 5, dated 06 October 2008, Engineering Order<(>,<)>- 92023-701 revision 2, dated 06 October 2008, Maintenance ManualSupplement.Configuration 2 DMP-200 MP3 Player Passenger Briefing System- 92023-402, Initial Issue, dated 06 October 200...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2017	Active	10061638
10061639	MED-PAC INC.		FAA STC SA01496CH	SEE FAA AML	Installation of an air ambulance conversion kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Med-Pac, Inc. Drawings as listed on FAA AML SA01496CH issued 26 July2001, or later FAA approved revisions.2. FAA approved Airplane Flight Manual Supplement approved 26 July 2001,or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/04/2017	Active	10061639

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061651	AVIONIK STRAUBING ENTWICKLUNGS GmbH			DA 40 D	Garmin GTN650 Dual Installation	As defined in the TCDS EASA.A. 022, plus CS-ACNS Initial Issue, Subpart BSection 1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation, Operation and Maintenance according to the AvionikStraubing “Master Document List” - ASR-2016-092-MDL-01-00 InitialRelease dated 20/04/2017.or later revisions of the above listed documents approved by EASA.	Limited to DA-40D aircraft with G500 and/or analog HSI/CDI installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworth...	25/04/2017	Active	10061651
10061652	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	MBB-BK117 C-1 MBB-BK117 B-2 MBB-BK117 B-1 MBB-BK117 A-4 MBB-BK117 A-3	HIGH DENSITY (9 PAX) SEATING INSTALLATION ON MBB-BK117 ROTORCRAFT	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	3159-FMS-01 issue 3, dated 16 April 2017, “Flight Manual Supplement”or later revisions of the above listed documents approved by EASA.3159-MMS-01, issue 3, dated 24 April 2017, “Maintenance ManualSupplement” (no ALS identified for this STC) 3159-COM-01, issue 2, dated March 2017, “Compliance Report”3...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/04/2017	Active	10061652
10061653	PMV ENGINEERING			A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	ISPSS installation on A320 familyThe change consists in installing and activating an In-Seat Power SupplySystem (ISPSS)only on FWD and MID cabin areas will be fitted with poweroutlets (36 ISPU and 69 outlets).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-MASTER DOCUMENT LIST, ref: SCA-00970-MDL-R02 dated 24/04/2017-INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: SCA-00970-ICA-R01 dated24/04/2017-AIRCRAFT FLIGHT MANUAL SUPPLEMENT, ref: SCA-00970-AFMS-R00 dated21/03/2017or later revisions ofthe above listed documents approved by EASA.	None	25/04/2017	Active	10061653
10061661	ASI INNOVATION	REV. 1		AS 332 L1	ASI mod 0284: Installation of two Garmin GPS400W and certification ofB-RNAV< (>,<)> P-RNAV, RNP-APCH, and LPV-APCH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	- Rotorcraft Flight Manual Supplement ASI-AFM-0284-00, dated 21.02.2017 or later revisions of the above-listed documents approved by EASA.- Certification Program ASI-CP-0284-06, dated 21.02.2017- Compliance Checklist ASI-CCL-0284-04, dated25.11.2016- Master Drawing List ASI-MDL-0284-04, dated 31.03...	This design change cannot be installed on helicopter with the AHCASsystem (commercial reference AS332L1e). The ASI modification approval n. 20150017 must be embodiedprior to installation of this designchange.Prior to installation of this design change it must be determined thatthe interrelationshipc...	26/04/2017	Active	10061661
10061662	21JAERODESIGN LIMITED	REV. 1	CAA UK RESPONSIBILITY	A321-111/-112/-211/-212/-213 A320-211/-212/-214/-215/-216 A319-111/-112/-113/-114/-115 A318-111/-112	Nacelle - CFM56-5A/5B Engines - Thrust Reverser - Replacement of adapterring outer flange segments – Amendment of modellisting	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25.601, CS 25.603, CS 25.609, CS 25.613, CS 25.1529 at Amdt 18The requirements for environmental protectionand the associatedcertified noise and/ or emissions levels o...	Design Change Document DCD-0001M, Issue 4, dated 19/05/2017or later revisions of the above listed documents approved byEASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/08/2017	Active	10061662

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061663	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST03405NY	737-700, -800, -900ER, -8, -9	Installation/Upgrade/Demod of an Intelsat 2Ku AntennaRevision 1 adds aircraft models Boeing 737-700, 737-900ER, 737-8 and737-9.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:B-01 : Vibration/ buffeting compliance criteria forlarge externalantenna installationThe requirements for environmental protection and the associatedcertified noise and/ o...	- Master Data List (MDL) 0106-09518-2400 Revision CV<(>,<)>dated 30September 2021- Instructions for Continued Airworthiness, ref: 0706-09574-2400Revision AQ, dated 30 September 2021- Electrical Wiring Interconnect System Instructions for ContinuedAirworthiness, ref: 0706-09612-2400 Revision E, date...	This STC includes certain configurations for provisions only whichrequire additional FAA approval to activate. The FAA must evaluate toensure it complies with the applicable airworthiness standards.Reference Delta Engineering Master Data List, which can be found inDescription of Type Design Change f...	31/01/2022	Active	10061663
10061666	AVIATION TECHNICAL SERVICES, Inc.		FAA STC ST02527SE	A319 SERIES	Installation of a reconfiguration of the cabin interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Aviation Technical Services Master Data List (MDL) 721546-MDL-001,Revision G, dated 29 March 2017, or later Federal AviationAdministration (FAA) approved revision.2. Instructions for Continued Airworthiness (ICA) 721546-ICA-001,Revision-, dated 14 November 2016, or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/04/2017	Active	10061666
10061669	FALCON CREST AVIATION SUPPLY, INC.		FAA STC SR09034RC	MBB-BK117 C-1 MBB-BK117 B-2 MBB-BK117 B-1 MBB-BK117 A-4 MBB-BK117 A-3 MBB-BK117 A-1	Installation of a Concorde RG390E valve regulated sealed lead-acidbattery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Rotorcraft Flight Manual Supplement (RFMS), dated 21 August 1995or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/05/2017	Active	10061669
10061675	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC SA11135SC	B300C B300 B200GT B200C B200 300LW 300	Installation of Pratt & Whitney flight data acquisition, storage, andtransmission (FAST) system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Data List, Installation Data, for King Air 200 & 300 Series, documentno. GN4-T-100-6, revision H, dated 14 November 2016 or later FAAapproved revision.2. Airplane Flight ManualSupplement for King Air 200 & 300 Series,document no. GN4-T-250-5, revision B, dated 27 October 2016 or later FAAapprove...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/05/2017	Active	10061675
10061680	BERINGER AERO	REV. 2		LS4, LS4-A, LS4-B LS 4/ LS 4-A/ LS 4-B	Beringer brake system installation on LS 4 series.Rev 1: Update with new servicing instructions within ICA document andaddition of SensAIR device as an option.Rev. 2: Update to account for improved brake assembly EA-006E design. Itnow becomes EA-017E.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification file: CR-MOD001-STC-015 REV 0, dated 30 Nov. 2023;Installation and Instructions for Continued Airworthiness: ICA-STC-015REV 02 dated 23 August 2023.or later revisionsof the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/03/2024	Active	10061680

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061681	VENTURA AEROSPACE, Inc.		FAA STC ST02607LA	CL-600-2B19 (RJ SERIES 100)	Installation of a rigid cargo barrier on the main deck in the forwardcabin.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Data List Bombardier, CL-600-2B19 (CRJ-100/200) Rigid CargoBarrier, Report No. VA-MDL-1000, Revision A, dated13 July 2016 or laterapproved FAA revision.,,2. FAA accepted Bombardier CL-600-2B19 Maintenance Manual Rigid CargoBarrier – CRJ-100/200, including Instructions for ContinuedAirwort...	1. This cargo barrier may only be installed on Bombardier CL-600-2B19aircraft which have a main deck cargo door and a Class E cargocompartment installed per FAA STC ST02606LA and cargo handling systemper FAA STC ST02620LA.2. Prior to installation of this design change it must be determinedthat the i...	07/05/2018	Active	10061681
10061689	JET AVIONICS AVIATION & MARINESERVICE CENTER S.r.l.			AS350 B3	Cabin Console installation.Installation in the cabin of an electronic console for the control of aRadar Surveillance System (Tetherpod multisensor) carried as a load bythe helicopter cargo swing.The Cabin Console consists of a display withits bending arm, a consolebody and a mounting tray. It is in...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS27 Initial issue (ED Decision 2003/15/RM), paragraph CS 27.561CS27 Amdt 3 (ED Decision 2012/021/R) paragraph27.865b) and d)The requirements for environmental protection...	Rotorcraft Flight Manual Supplement, doc. no. BDI 001-13-16issue 5dated 17/02/2017or later revisions of the above listed documents approved by EASA.- Master Drawing List, doc. no. BDI-001-13-01 Rev. 9 dated 23/02/2017- Certification Program, doc. no. BDI-001-13-08 Rev. 2 dated 29/10/2014,,- Complia...	Only applicable to AS350 B3 S/N 3483<(>,<)> embedding:- EASA STC 10016711 “Onboard Systems Cargo Swing”,- Boggi S.r.l. SB 350P008-00 for cable routing openings and- Airbus Helicopters SB 25.00.64 for the “Installation of 450 lb hoistmechanical and electrical fixed parts and a 200 Amp starter-generat...	28/04/2017	Active	10061689
10061695	ANJOU AERONAUTIQUE S.R.L.			CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2B19 (RJ SERIES 100)	BOMBARDIER SEAT BELT MODIFICATION - MOD 02-900114.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, ref. doc. 02-900114-MDL-001, Revision No.03, dated21st April 2017.Modification Approval Sheet (Declaration of Compliance), ref. doc. 02-900114-MAS-001, Revision No. 03, dated 21st April 2017.Dynamic Test Report, ref. doc.02-900114-DTR-001, Revision No. 03,dated 21st April 2017or...	None.	28/04/2017	Active	10061695
10061698	AVIONIK STRAUBING ENTWICKLUNGS GmbH			F172P	Installation of Provisions for Mission Equipment Carriage	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS-23, Amdt. 429, 301, 303, 305, 307, 337, 561, 601, 603, 605, 607, 609, 611, 613,625, 867, 1301, 1306, 1308, 1309, 1327,1...	- Flight Manual Supplement ASR-2016-098-FMS-05-00, Rev. 00or later revisions of the above listed documents approved by EASA.- Certification Program and Declaration of ComplianceASR-2016-098-CEP-03-00, Rev. 00- Project Description ASR-2016-098-PRD-04-00, Rev. 00- Instructions for Installation ASR...	This approval does not cover the installation of any mission/ researchequipment in the 19" rack other than specified Avionik Straubingdocument ASR-2016-098-PRD-04-00. It does also not cover the operation ofany kind of PED.Prior to installation of this design change it must be determined thatthe inter...	28/04/2017	Active	10061698
10061714	TEXTRON AVIATION Inc.	REV. 2	FAA SA01830WI	SEE FAA AML E. T206H E. 206H, D. 182T, T182T C. 172R, 172S B. G58 A. G36	Installation of the G1000 Integrated Avionics System hardware andsoftware updates, including optional Flight stream 510.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation in accordance with Garmin Master Drawing List (MDL) ref005-00620-21, Rev 1, dated 20 December 2016;Operatein accordance with Garmin Aircraft Flight Manual Supplementasdefined in the MDL and EASA AFMS ref 190-02128-06-01, Rev1, dated 03May 2017;Operate in accordance with Garmin Instru...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/06/2021	Active	10061714

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061719	AMAC AEROSPACE SWITZERLAND AG	REV. 6		A340-541/-542/-642/-643 A340-313/-541/-542/-642/-643 A340-311/-312/-313 A340-211/-212/-213/-311/-312 A330-201/-202/-203/-223/-243	JetWave Ka-Band Antenna installation.Reason for Revision 3:extension of STC to additional Airbus A340models, update ofdocumentationReason for Revision 4: extension of STC to Airbus A340-311, A340-312,A340-313 models, revision of ICA and inclusion of WLAN activation forA340-313 MSN 528.Reason for R...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): For Aircraft A340-313 MSN 528: F-108 Securityprotection of Aircraft Systems and Networks.- Equivalent Safety Finding(s): CRI B-01 Vibr...	Applicable for Airbus A340-500:Master Data List MDL-A3401-1-5300, Rev. E dated 22.01.2020Airplane Flight Manual Supplement AFMS-A3401-1-5300 Rev B dated08.08.2017Instructions for Continued Airworthiness ICA-A3401-1-5300 Rev D dated22.01.2020Applicable for Airbus A340-600:Master Data List MDL-A3401-2...	Other:Applicable for Airbus A340-500:Effectivity Substantiation Report ESR-A3401-1-5300Airworthiness limitations per Instructions for Continued AirworthinessICA-A3401-1-5300Applicable for Airbus A330-200:Effectivity Substantiation Report ESR-A3401-3-5300.Airworthiness limitations per Instructions fo...	02/04/2024	Active	10061719
10061729	SOCIETE AIR FRANCE S.A.			A330-243	A330-200 Cabin rearrangementCabin seating rearrangement including "ACRO series 3" Y/C passengers'seats and new lavatoryL53 installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List : Change Approval Sheet ref : CAS-A330-16-010 Rev 0;- Instruction for Continued Airworthiness, ref :ICA-A330-16-010 Rev 0;or later revisions of the above listed documents approved by EASA.	According to the design related to this STC, This modification must beinstalled in conjunction with EASA STC 02580 (Introduction ofself-illuminated Floor Path Marking System „“colored guidelinePL88-900Series, manufactured by Lufthansa Technik AG (LHT)“).Prior to installation of this design change it...	03/05/2017	Active	10061729
10061774	CHIPPEWA AEROSPACE, Inc.		FAA STC ST04281AT	SEE FAA APPROVED MODEL LIST	Installation for the Upgrade of the NZ-2000 FMS computer for softwareversion NZ6.1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval as amended by thefollowing paragraphs:Regulations at the latest amendment 25-0 through 25-14225.111<(>,<)> 25.1301<(>,<)> 25.1307<(>,<)>25.1316<(>,<)> 25.1317<(>,<)> 25.1353<(>,<)> 25.1431, 25.152...	1. Chippewa Aerospace Master Drawing List (MDL) No. CAI-3461-01-0001,Rev. 1, dated 6 December 2016, or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA), Chippewa AerospaceInc. as listed on the AML, or later FAAapproved revision.3. Document No. CAI-3461-01-0002, Rev. IR,...	1. FAA Approved Airplane Flight Manual Supplement (AFMS) aslisted onthe AML or later FAA approved revision are a required part of this STC.2. The STC is valid for those aircraft types and models approved by EASAwithin the FAA AML No. CAI-3461 Rev. IR, dated 6 December 2016.3. Prior to installationt...	15/05/2017	Active	10061774
10061791	LEARJET Inc.		FAA STC ST00427DE-D	LEARJET MODEL 45	Installation of a Universal Avionics Systems Corporation, TerrainAwareness and Warning System (TAWS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Learjet Inc. Master Document List BAS45010007, revision (-), dated 1February 2001, FAA approved 6 February 2001 or later approved revision. 2. Instructions for Continued Airworthiness, BAS-45010007-IFCA, dated 30January 2001, FAA accepted 30 January 2001 or later FAA acceptedrevision.3. FAA approv...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/05/2017	Active	10061791
10061793	LEARJET Inc.		FAA STC ST00437DE-D	LEARJET MODEL 45	Installation of Concorde RG-380E/40L 38 Amp Hour Lead Acid Batteries.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. FAA Approved Learjet Inc. Master Document List BAS45010011, RevisionB, dated 17 January 2001, or later FAA approved revision.2. Instructions for Continued Airworthiness, FAA acceptedBAS-45010011-IFCA, dated 21 December 2000, or later FAA acceptedrevision.3. FAA Approved Airplane Flight Manual Sup...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/05/2017	Active	10061793

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061795	LEARJET Inc.		FAA STC ST01120WI-D	LEARJET MODEL 45	Installation of a Filter in the Cabin Temperature System onLearjetModel 45.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Learjet Master Document List M100385ICT, revision (A), dated 14November 2002, FAA approved 14 November 2002, or later approvedrevision.2. Instructions for Continued Airworthiness, M100385ICT-IFCA, revision(-), dated 14 November 2002, FAA accepted 14 November 2002 or later FAAaccepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/05/2017	Active	10061795
10061796	LEARJET Inc.	REV. 1	FAA STC ST01226WI-D	LEARJET MODEL 45	Installation of Universal Performance database on Learjet Model 45aircraft.Revision 1 updates the AFMS, ICA and the Limitations and Conditionssection of the certificate.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Learjet Master Document List M100446ICT, revision (C), released 6 May2004, FAA approved 18 May 2004, or later approved revision.2. The following document is required for MDL M100446ICT-001 and -002configurations of this STC:FAA approvedAirplane Flight Manual Supplement, W1533, revision NC, FAAap...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Model 45 aircraft serial number range 45-2...	21/09/2021	Active	10061796
10061800	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST04131CH	A321-211/-212/-213/-231/-232 A320-232/-233/-271N/-251N A320-211/-212/-214/-231 A318-111/-112/-121/-122	EASA validation of FAA STC ST04131CH. Installation of a Zodiac RAVEIn-Flight Entertainment System in accordance with StandardAero MasterData List DC104-9739-00, Revision (V) dated28th March 2017 or laterapproved revisions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 impacted requirements at initial issue unless otherwise specified:25.1; 25.301 (a, b)(amdt 1); 25.303; 25.305(a-c) (amdt 1); 25.307(a))(amdt 1); 25.561(a-c); 25.571(a...	The STC installation must be performed in accordance with StandardAeroMaster Data List DC104-9739-00, Revision (V) dated 28th March 2017, andThe Airplane Flight Manual Supplement document number DC303-9739-00, Rev(A) dated 21st December 2016 or later approved revisions is a requiredpart of this modi...	See those of original FAA STC ST04131CH and those of the Airplane FlightManual Supplements and other documents listed above under associatedtechnical documentation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprev...	08/05/2017	Active	10061800
10061804	LEARJET Inc.	REV. 1	FAA STC ST01499WI-D	LEARJET MODEL 45	Installation of an UNS-1Ew Flight Management System on Learjet Model 45.Revision 1 updates the AFMS and ICA.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Learjet Inc. Master Document List M100520ICT, revision (D), dated 21December 2008, FAA approved 22 December 2008, orlater FAA approvedrevision.2. The following document is required for M100520ICT-001 configurationof this STC:Airplane Flight Manual Supplement W1592, Original release, dated 22Dece...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Dual UNS-1Ew Flight Management System with...	21/09/2021	Active	10061804
10061806	LEARJET Inc.	REV. 1	FAA STC ST01719LA-D	LEARJET MODEL 45	Installation of a Universal Avionics Systems Inc. Terrain AwarenessWarning System (TAWS) SCN 11.1 Upgrade, a Class "A" System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. FAA Approved Master Document List BAS45017001, Revision D, dated 28March 2005, or later FAA Approved Revision.2. FAAApproved Airplane Flight Manual Supplement BAS45040106, RevisionNC dated 28 March 2005, or later FAA Approved Revision,is required forthe -1 Configuration.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The approval of this modification appliesm...	17/05/2017	Active	10061806

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061809	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			737-800	Introduction of First Row CVS Seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Programme C0067-CEP-02.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/05/2017	Active	10061809
10061811	LEARJET Inc.		FAA STC ST01734LA-D	LEARJET MODEL 45	Installation of a Cockpit Speaker Mute System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA Approved Master Document List BAS45010020, Revision F, dated 10February 2007 or later FAA Approved Revision. FAA Approved AirplaneFlight Manual Supplement BAS45040107, Revision NC dated 10 February2007, or later FAA Approved Revision<(>,<)> is required for the -1Configuration.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The approval of this modification appliess...	15/05/2017	Active	10061811
10061812	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	B200CT, B200T 200, 200C, 200CT, 200T	Introduction of antennas and pressure hull feed through provisions andinstallations	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	To be installed according to documents in Master data list in 2XL019LEF78(1) Issue 1 dated 26th April 2017;To be maintained according to Instructions for Continued Airworthiness2XL019 LEF73(1) Issue 1 ICA dated 14th December 2016.No AFM Supplement is issued with this STC.or later revisions of the ab...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/05/2017	Active	10061812
10061818	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CL-600-2B16 (604 VARIANT)	Upgrade to Cabin Interior.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-01 GLASS SCREENS OF DISPLAYS/MONITORS.The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0146 Issue 1or later revisions of the above listed documents approved by EASA.STC Twenty One Ltd Master Document List No. S21.MDL-1295 Issue 1.	It is the responsibility of the operator to develop procedures fordeveloping and maintaining a list of authorised PED'sfor use on the aircraft. This condition also requires the operator totest each PED (type) and maintain a list of PED's found acceptable foruse.	10/05/2017	Active	10061818
10061823	AERODATA AG			B200, B200C, B200CGT, B200GT	Enhancement of TDR94/94D by ADS-B Capability.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:- CS 23 Amdt 4 paragraphs 23.1301, 23.1308(c), 23.1309(a), (b)and (c),23.1529, 23.1581(a)(2) and (f).- CS ACNS Initial Iss...	- Installation according to Service Bulletin SB-B200-TDR-2159 Rev.2 ;- Operations according to Airplane Flight Manual Supplement AFM-159Rev. 0;- Maintenance according to Aircraft Maintenance Manual SupplementAMM-1166 Rev.0;or later revisions of the above listed documents approved by EASA.	Limited to aircraft equipped with:- Rockwell Collins Pro Line 21 avionics- Rockwell Collins GPS 4000S (Single)- L-GPS-3ARINC 429 HS Bus-TDR94 (622-9352-xxx) / TDR94D (622-9210-xxx) - xxx = 008 / 108 / 308/ 408 / 409.,,Prior to installation of this design change it must be determined thatthe inte...	10/05/2017	Active	10061823
10061825	FOKKER SERVICES B.V.			737-900, 737-900ER 737-600, 737-700, 737-800 737-300, 737-400, 737-500 737-100, 737-200, 737-200C	Boeing 737 provisions for EFB.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- CP-0324 Issue 1- CRR-0324 Issue 1- Instructions for Continued Airworthiness Supplement SE-804 Issue 1;or later revisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/05/2017	Active	10061825

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061828	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			737-800	Change Interior Arrangement from 166 PAX [12J/154Y] to 176 PAX [8J/168Y]and associated modifications.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25.853, CS25.1701,and CS25.1703 at Amdt 18.The requirementsfor environmental protection and the associatedcertified noi...	Master Data List, Ref. JCAERO/MDL/0162 Issue 1.0;or later revisions of the above listed documents approved by EASA.	- The allowed preconfigurations are defined in the CertificationProgramme Ref. JCAERO/CP/0162 Issue 1.6 and are approved by PaustianAirtex Gmbh Minor Change Ref. MCA-DP048 or J<(>&<)>C Aero Minor ChangeRef. JCAERO/MODC/0175- Only applicable to Boeing 737-800 S/N 28239, 28243, and 30640.Prior to inst...	10/05/2017	Active	10061828
10061829	ROCKWELL COLLINS, Inc.	REV. 4	FAA STC ST01750WI	767-200/ 767-300F	Installation of Rockwell Collins, Inc. Large Display System(LDS)Revision 1 rescinds the 10.02 limitation.Revision 2 adds Approach Mode to the ND Format; corrects Cabin pressurecontrolled by Barometric Correction Settings; LDS dataload enablediscrete moved from parking brake to the left engine fueld...	See EASA approved Annex	Master Drawing List (MDL) RCA-0415, Revision R, dated 29 October 2019,or later approved revision;Table 1 – Boeing 767-300F Series Aftermarket:Instructions for Continued Airworthiness RCA-0432, Revision (-), dated 9May 2014, or later accepted revision; Airplane Flight Manual Supplement3422-B68-AFM, R...	Other:(1) Aeroplanes modified with this STC must have the Engine Indicationand Crew Alerting System (EICAS) computer Operational Program Software(OPS) part number 317B-COL-DE0-08 installed in the Left & Right EICAScomputers.(2) Intermix ofGeneral Electric CF6-80A engines with CF6-80A2 enginesis not...	02/03/2020	Active	10061829
10061847	BLR AEROSPACE, L.L.C.		FAA STC SA00037SE	PA-31	Approval of Installation of vortex generators and operationat increasedgross weights.	The Certification Basis (CB) for the original product remains applicableto this certificate/approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.EASA Noise Record number ref C13036 refers to thism...	Installation of vortex generators, manufactured in accordance withdocument ref AA1161, Revision B, dated November 15, 1993, and installedin accordance with Document ref BL1162, Revision A, dated August 31,1993.Operation in accordance with document ref AFMS-NAV-3, dated November 18,1993or later revis...	Serial Numbers eligible 31-2 and subsequent.All limitationsand Conditions defined on the original FAA STC SA00037SEmust be respected.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change...	12/05/2017	Active	10061847
10061849	AERODATA AG	REV. 1		B200GT B200 GT	Conversion for Maritime Patrol MissionRev. 1: AFM-163 includes the content of Temporary Revision AFMTR-116-4,Correctionof Drop Hatch Operation.	See EASA approved AnnexThis certificate/approval involves achange with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amendedas follows: The environmental protectionrequirements are amended as follows: ICAO Annex 16, Volume I, 6thedition, amendm...	Master Document List MDL-A/C-893 Rev. 7Aircraft Flight Manual AFM-163, Rev. 5Maintenance Manual AMM-1164, Rev. 2or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	- Limited to B200GT aircraft with installed:- Rockwell-Collins Proline 21 Avionics- Aerodata STC 10060862 Rev.1 or later (Increase of MTOW to 14000lbs)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	19/02/2024	Active	10061849
10061854	S4A SOLUTIONS FOR AVIATION, S.L			FALCON 2000	Installation of Antenna for XM Weather System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt 18 for the affected area as detailed in the compliancechecklist, Ref. FAL03-CHK01 Issue 1The requirements for environmental protection and the associatedcertifie...	-Master Drawing List, Ref. FAL03-RPT02 Issue 2.-MaintenanceManual Supplement, Ref. FAL03-HDK02 Issue 4.or later revisions of the above listed documents approved by EASA.	As per Maintenance Manual Supplement, Ref. FAL03-HDK02 Issue 4, Section11 (Airworthiness Limitations)Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce no...	12/05/2017	Active	10061854
10061857	FOKKER TECHNIEK B.V.	REV. 1		A319-115	Installation of a GOGO satellite communication antennaRevision 1: Transfer of STC from Fokker Services B.V. (EASA.21J.059) toFokker Techniek B.V. (EASA.21J.667)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI C-102 Vibration / buffeting compliance criteria for large externalantenna installationThe requirements for environmental protection and th...	-A319-ALE-AFM-S-002, Revision 2-A319-GOGO-ICA-0002, Issue 1or later revisions of the above listed documents approved byEASA.EBA319-0046, Engineering Bulletin, First release-CP-0342, Certification Plan, Issue 2-CRR-0342, Compliance Record Report, Issue 1	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/12/2019	Active	10061857

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061874	TENENCIA Ltd.		CAA UK RESPONSIBILITY	A340-541/-542/-642/-643 A340-311/-312/-313 A340-211/-212/-213	Electronic Flight Bag (EFB) ProvisionsTIM EFB System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TEN 817-47, Aeroplane Flight Manual Supplement, Issue 1or later revisions of the above listed documents approved by EASA.TEN 817, Master Data List, Issue 1	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/05/2017	Active	10061874
10061878	EMBRAER ENGINEERING & TECHNOLOGYCENTER USA, INC.	REV. 2	FAA STC ST116-010NM	EMB-135BJ	Installation of a Forward Lavatory with an Externally Serviced WasteSystem.This STC was originally issued as a validation of Brazilian CTS (STC)No. 2010S08-11 (16 August 2010), and transferred to a United Statesbases Design Approval Holderon 22 July 2019.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Embraer Installation Manual, ESCWWE001, Revision B, dated22 January2016.- Master Document List No. ESCWWD001, Rev. J, dated 9 October 2018.- Instructions for Continued Airworthiness (ICA), Document No. ICA-008,Rev. A, dated 9 October 2018or later revisions of the above listed document(s) approved...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	26/11/2019	Active	10061878
10061893	AVCON INDUSTRIES, Inc.	REV. 1	FAA STC SA2300CE	SEE FAA APPROVED MODEL LIST	Installation of Removable External Baggage Compartment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avcon Maintenance Manual, dated 20 October 1987, or Instructions forContinued Airworthiness, No. 03607200, Rev.IR< (>,<)> dated 15 February2017, or later FAA accepted revision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesa...	19/05/2017	Active	10061893
10061899	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		SAAB SF340A, SAAB 340B SAAB SF340A SAAB 340B	Upgrade of Universal (UNS) Flight Management System, including LPVmonitor & Rockwell Collins Transponder for Mode S ELS/EHS & ADS-B OUT.This STC consists through various optional upgrade in modifying theexisting single Universal UNS-1() FMS system to a Universal UNS-1Lw FMS (option A), eventually cou...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): F-102 : MODE S ELS/EHS and ADS-B out functionalityinstallation.- The following paragraph(s) ata later amendment:CS25 Amdt 2: CS25A.1, .29, .301, .303, .30...	SAD Engineering Order, ref: 2094590-EO Issue 1SAD Aircraft Flight Manual Supplement : - for FMS, ref: 2094590-AM A Issue 1 - for LPV Monitor, ref: 2094590-AM B Issue 3 - for XPDR, ref: 2094590-AM C Issue 1SAD Instruction for Continued Airworthiness : - for FMS, ref: 2094590- CA A Issue 1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/11/2021	Active	10061899
10061912	AIR AMBULANCE TECHNOLOGY GmbH			B300	Installation, Operation and Maintenance of Air Ambulance Technology AATequipment Beech 300 EMS installation P/N B300-25-20-103.000-600 inaccordance with MDL-B300-25-20-103.000-601-603, Initial Issue, dated 16May 2017.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement FMS-Beech300-EMS-000 Air AmbulanceTechnologyP/N B300-25-20-103.000-600 Initial Issue, dated April 24 2017or later revisions of the above listed documentsapproved by EASA.- Instructions for Continued AirworthinessICA-Beech300-EMS-000 AirAmbulance Technology P/N B300-25-20-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/05/2017	Active	10061912

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061913	AVIDYNE CORPORATION		FAA STC SA00382BO	SEE FAA APPROVED MODEL LIST	Installation of Globalstar Antenna and Cradle provisions tosupport aGlobalstar GPS-1700 in non-composite airplanes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Avidyne Corporation Master Document List (MDL)<(>,<)> Document NumberAVIFC-004, Revision 00, dated 8 February 2017, or later FAA approvedrevision.2. Avidyne Corporation Aircraft Flight Manual Supplement (AFMS) DocumentNumber 600-00327-000, Revision 00, FAA approved on 5 April 2017, orlater FAA ap...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesa...	17/05/2017	Active	10061913
10061919	SBC AMERICA LLC	REV. 1	FAA STC SA00787SE	737-900/ -900ER 737-8, 737-9 737-600/ -700/ -800 737-300/ -400/ -500	Installation of a Sliding Carpet Cargo Loading System in the cargocompartment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Telair International Drawing List/Report List STC/003-ÖC, Revision29, dated 17 December 2018, or later FAA approved revision.2. Chapter 16, Airworthiness Limitations, of TelairInternationalSliding Carpet Manuals, Revision 2, dated 15 December 2018, or later FAAaccepted revision.	1. This approval does not include electrical provisions fortheinstallation for the Sliding Carpet Loading System in the Boeing Model737-600/-700/-800/-900/-900ER/-8/-9 cargo compartments. The electricalprovisions for the installations of the Sliding Carpet Loading System inthe Boeing Model 737-600/...	11/03/2019	Active	10061919
10061922	HONEYWELL INTERNATIONAL (BENDIXKING)		FAA STC SA11174SC	SEE AML	Installation of BendixKing by Honeywell KSN 770 and KSN 765WAAS LPVapproach capable nav/comm systems	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Installation Manual 006-10716-0000, Revision 5, dated 11July 2014,or later FAA approved revision. ,,2. Airplane Flight Manual Supplement 900-00024-001, Revision F, dated 25July 2014, or later FAA approved revision.3. ICA 900-00025-001 Revision B dated 7 January 2014 or later FAArevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	17/05/2017	Active	10061922
10061933	AVEO ENGINEERING GROUP S.R.O.	REV. 1		737-900, 737-900ER 737-600, 737-700, 737-800 737-300, 737-400, 737-500	Design Change for Boeing 737 Light replacement.Replacement of existing Navigation-, Logo-, Wing Illumination-, Taxi- orTurn lights with AVEO Engineering LED lights.Revision 1 is the addition of replacement of light bulbs for strobelights, the anti-collision lights and the landing light and replace t...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 AMDT 18: 25.301;25.603; 25.609; 25.773; 25.1301; 25.1309; 25.1351; 25.1385; 25.1387;25.1389; 25.1391; 25.1393; 25.13...	The change is defined with Issue 05 of the Master DocumentsListAVE-MOD-002-MDL<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/11/2018	Active	10061933
10061934	AMAC AEROSPACE SWITZERLAND AG			A340-211	Cabin Refurbishment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): Per CRI A-01.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged an...	Master Data List MDL-FC01-2500, Rev. A dtd. 16.05.2017;or later revisions of the above listed documents approved by EASA.	Limited to MSN 026.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	18/05/2017	Active	10061934
10061936	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE	REV. 2	FAA ST04058CH	737-800/-900/-900ER/-8/-9 737-737-800/-900/-900ER/ -8/-9 737-300/-400/-500/-600/-700	Installation and activation of an Astronics webFB System and/or FlightDeck USB UltraLite Power System (Provisions for Class 2 EFB Systems)Rev. 1 adds the models 737-8 and 737-9 toEASA approved installationeligibility and changes Astronics' address.Rev. 2 corrects some typos.	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements:for 737 Classic and NG models CS 25 impacted requirements at initialissue unless otherwise specified:25.29(a,b); 25.301(a, b)(amdt 1); 25.303; 25.305(a-c) (amdt 1);25.307(a...	Astronics Armstrong Aerospace Document No per Section 6.1. of MasterData List DC104-2017-00, Revision W, dated 22 July 2019, and the FlightManual Supplement Document number DC104-2017-00, Rev W, dated 22 July2019, or later FAA approved revisions.For Astronics Armstrong Aerospace Master Data List, Do...	This STC installation approval does not include the Electronic FlightBag computers. The operational approval of the electronic flight bagcomputers should follow the guidance and requirements laid down in theapplicable operational rules.Prior to installation of this design change it must be determine...	06/05/2022	Active	10061936

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061938	MONOGRAM SYSTEMS		FAA STC ST02624LA	SEE FAA APPROVED MODEL LIST	Installation of Toilet Assembly.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Monogram Master Data List as noted on the FAA Approved Model ListST02624LA.2. Instructions for Continued Airworthiness (ICA), as noted on the FAAApproved Model List ST02624LA.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesa...	19/05/2017	Active	10061938
10061941	CLAY LACY AVIATION, INC.		FAA STC ST03423CH	G-IV	Installation of a Universal Avionics UNS-1Espw flight management systemwith UniLink UL-801 datalink system and CVR- 120A cockpit voice recorderto meet airworthiness requirements for FANS 1/A+ and optional AutomaticDependent Surveillance Broadcast (ADS-B) Out.	The certification basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:14 CFR Part 25:25.29 [Amdt 25-72]; 25.571(a), (b) [Amdt 25-45]; 25.869(a)(4) [Amdt25-11 3]; 25.1307(e) [Amdt 25-72]; 25.1329(c), (i) [Amdt 25-119];25.1351(a) [Amdt 25-72];...	Clay Lacy Aviation Master Data List E13096-2320-L001, Revision E, dated28 February 2017, or later FAA approved revision.2. Flight Manual Supplements, Clay Lacy Aviation Document No.E13096-2320-B001, Revision IR, approved 13 March 2015 andE13096-2320-B002, Revision IR, dated 13 March 2015, or later F...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/05/2017	Active	10061941
10061946	BLACKHAWK AEROSPACE TECHNOLOGIES IN		FAA STC ST01823WI	500/550/S550/560/560XL	Installation of Garmin GTS Traffic Sensor with Garmin GTX 3000 Mode STransponders with ADS-B Out.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Columbia Avionics & Aircraft Services Flight Manual Supplement,Document No. 30142347, Rev. IR, dated 16 September 2016, or Document No.30142269, Rev. IR, dated 16 September 2016; and2. Columbia Avionics & Aircraft Services Master Document List, DocumentNo. 30142251, Rev. IR, dated 19 September 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/05/2017	Active	10061946
10061947	AVENGER AEROSPACE SOLUTIONS, INC.	REV. 1	PMA NO.: PQ05316NM	HS.125 SERIES 600B/ 700A/ 700B HS.125 SERIES 403A/ 403B/ 600A HS.125 SERIES 400B/ 401B HS.125 SERIES 1B/ 3B/ 400A HAWKER 900XP, HAWKER 1000 HAWKER 750/800/800XP/ 850XP DH.125 SERIES 1A/ 3A/ 400A BH.125 SERIES 400A/ 600A BAE.125 SERIES 800A/ 800B BAE.125 SERIES 1000A/ 1000B	Hawker Nose Landing Gear Plunger Tube P/N NP-UN649-1 (replacement forOEM P/N 25UN649).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: JAR 25 Change 13 forthe following paragraphs: 25.301, 25.303,25.305(a) and (b), 25.307(a)and (b), 25.571(a)(3) and (c), 2...	Part in accordance to drawing number NP-UN649 Rev.B;Limitations as per document Airworthiness Limitation Section -AV8-ALS-16-007, Rev. NC, dated 26/04/2016;or later revisions of the above listed documents approved by EASA inaccordance withEASA ED Decision 2004/04/CF (or subsequent revisions ofthisU...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/05/2017	Active	10061947
10061949	TURBINE CONVERSIONS, LTD	REV. 2	FAA SA04034CH	B. 206H, T206H A.U206F, TU206F, U206G, TU206G A. TP206A, U206A, TU206A A.P206E, TP206E, U206E, TU206E A.P206D, TP206D, U206D, TU206D A.P206C, TP206C, U206C, TU206C A.P206B, TP206B, U206B, TU206B A. 206, P206, U206, P206A	Installation of Pratt & Whitney Canada PT6A engines (ref. to LimitationSection) and Hartzell HC-B3TN-3 propeller with T10173-8 blades.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	- Turbine Conversions, Ltd, Master Drawing List Report 206000, Rev E,dated 14 Jan 2015;- Turbine Conversions, Ltd, Airplane Flight Manual Supplement 206004,Rev A, dated 15 March 2017;- Turbine Conversions, Ltd, Installation Manual 206001, Rev. B, dated 14December 2015;or later revisions of the above...	a) The following engines are eligible: PT6A-11, PT6A-20, PT6A-20A,PT6A-20B, PT6A-21, PT6A-6/C20, PT6A-110, and PT6A-112.b) EASA STC 10061220 (FAA STC SA2256WE) “Installation of leading edgecuff and aileron gap covers on each wing” is required.c) If the holder agrees to permit another person to use t...	15/11/2018	Active	10061949

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061952	CLAY LACY AVIATION, INC.		FAA STC ST04014CH	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT)	Installation of dual Universal Avionics UNS-1Fw flight management systems with UniLink UL-801 datalink system andCVR-120A or CVR-120R cockpit voice recorder to meet airworthinessrequirements for FANS 1/A +.NEW-PAGE	The certification basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:14 CFR Part 25:25.869(a)(4) [Amdt 25-113]; 24.1307(c) [Amdt 25-72]; 25.1329 (c), (i)[Amdt 25-119]; 25.1457 (a), (b), (c), (d)(1)(i),(2), (3), (4),(5)(i) (ii)(iii),(6), (e),T...	1. Clay Lacy Aviation Master Data List JRW1330-MDL, Revision A, dated 17August 2015, or later FAA approved revision.2. Flight Manual Supplements, Clay Lacy Aviation Document No.JRW1332-FMS-01, Revision IR, approved 19 August 2015 and JRW1332-FMS-02,Revision IR, approved 19 August 2015, or later FAA...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The modified aircraft must be maintained i...	29/05/2017	Active	10061952
10061954	B/E AEROSPACE, Inc.		FAA STC ST04362AT	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-233/-251N/-271N A320-211/-212/-214/-231/-232 A319-131/132/-133 A319-111/-112/-113/-114/-115	Installation of the Rockwell Collins Automatic Dependent Surveillance - Broadcast (ADS-B) Out System on the Airbus A319/A320/A321 SeriesAircraft.	The certification basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:14 CFR Part 25:25.23(a), 25.301(a)(b), 25.303, 25.305(a), 25.561(c), 25.601,25.603(b)(c), 25.853(a), 25.863(a), 25.1351(a)(1)<(>,<)>25.1431(a)(c), 25.1529, 25.1581.25.307(...	1. Master Drawing List (MDL) 2-177034-001, Rev. A, dated 31March 2017,or later FAA approved revision.2. FAA Approved Airplane Flight Manual Supplement for the RockwellCollins Automatic Dependent Surveillance - Broadcast (ADS-B) Out System,2-177034-805, Rev IR, dated 2 May 2017, or later FAA approve...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/05/2017	Active	10061954
10061960	AVIATION SUPPORT GmbH			SA 365 N1 SA 365 N AS 365 N3 AS 365 N2	EMS Equipment & Stretcher InstallationInstallation of an EMS Equipment installed in the FWD section of thepassenger compartment. The system includes a medical floor with easyaccess provisions for stretcher installation and an equipment panel forthe installation of medical equipment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 29 Amdt. 3:CS 29.1, CS29.21, CS 29.25, CS 29.27, CS 29.29,CS27.31, CS 29.251, CS29.301, CS 29.303, CS 29.305, CS 29.30...	- Flight Manual Supplement, FMS-ASE-91616, original releaseor later revisions of the above listed documents approved byEASA.- Liste der gültigen Dokumente, MDL-ASE-91616, original release, dated15/05/2017-Instructions for Continued Airworthiness, ICA-ASE-91616, originalrelease, dated 15/05/2017	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/05/2017	Active	10061960
10061965	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	767-300	767 Cabin Attendant Crew Rest Seat	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration Scheme No.3153-MCS-01 Issue 1	None	22/05/2017	Active	10061965
10061969	JET AVIATION AG, BASEL			MYSTÈRE FALCON 900 (MF900)	VIP & Medevac cabin reconfiguration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):D-17 - No Smoking Signs and Lavatory Ashtrays D-18 - Width of AisleThe requirements for environmental protection and the associatedcertified noise and...	-Master Data List JBSL-M-00727MDL-01 Issue 2 dtd. 18.05.2017-AFM Supplement No. JBSL-M-00727AFM-01 Issue 2 dtd. 12.05.2017-Instructions For Continued Airworthiness JBSL-M-00727ICA-01 Issue 2dtd. 15-05-2017or later revisions of the above listed documents approved by EASA.	- per AFM Supplement No. JBSL-M-00727AFM-01- per Medevac Provision Definition and Limitations JBSL-M-00727ANA-01for configurations 2 and 3Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design ch...	22/05/2017	Active	10061969

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061971	AEROLITE AG	REV. 1		AW189	EMS Equipment P/N 189-0213100-501 <3 Stretcher Kit> incorporatingmodification ref. DECEASA60079369.The EMS Equipment features three stretchers for patient transport andseveral electrical and medical oxygen outlets for dedicated patienttreatment. It consists of the following installations:- 3 Stretch...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Program CPR-21-008 revision BFlight Manual Supplement: FMS-189-0213100-501 revision AOperation Manual OPM-189-0213100-501 revision AMaster Document List MDL-15-022 revision Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Effectivity:AW189 S/N 49007 and upwards (except S/N 49024)<(>,<)>AW189 SN 89001 and upwards<(>,<) >AW189 SN 91001 and upwards<(>,<)>AW189 SN 92001 and upwards.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously...	10/03/2023	Active	10061971
10061972	AVENGER AEROSPACE SOLUTIONS, INC.	REV. 1	PMA N. PQ05316NM	HAWKER 900XP HAWKER 850XP HAWKER 800XP HAWKER 800 HAWKER 750 BAE.125 SERIES 800B BAE.125 SERIES 800A	Hawker Main Landing Gear Plunger Tube P/N NP-8UM-5 / -6 / -7 / -8(replacement for OEM P/N 25-8UM5 and 25-8UM6)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:JAR 25 Change 13 for the following paragraphs: 25.301, 25.303,25.305(a)and (b), 25.307(a) and (b), 25.571(a)(3) and (c), 2...	Part in accordance to drawing number NP-8UN Rev.BLimitations as per document Airworthiness Limitation Section -AV8-ALS-16-008, Rev. A, dated 13/10/2016or later revisions of the above listed documents approved by EASA inaccordance with EASAED Decision 2004/04/CF (or subsequent revisions ofthis decis...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/05/2017	Active	10061972
10061979	AEROCET, INC.		FAA STC SA02452SE	KODIAK 100	Installation of Aerocet Model 6650 Amphibious Twin Floats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List (MDL) Document 66-12000, Revision J,dated 5August 2015, or later Federal Aviation Administration (FAA) approvedrevision.2. Instructions for Continued Airworthiness (ICA) Document A-10038,Revision 0, dated 11 February 2015, or later FAA-accepted revision.3. Airplane Flight Man...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/05/2017	Active	10061979
10061989	TRUATLANTIC MFG., LLC		FAA STC SA02314AT-D	B) G36 A) S35, V35, V35A, V35B A) 36, A36, E33A, E33C, F33A A) 35-C33A	Installation of a Stainless Steel Exhaust System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Atlantic Aero, Inc. Master Drawing List 19593001, Rev. F,dated March2, 2010or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)” and/ or the Technical Implementation Procedures of EU/USA Bilateral...	None	23/05/2017	Active	10061989
10061994	SBC AMERICA LLC	REV. 2	FAA STC ST00702SE	737-8/-9 SERIES 737-600/-700/-800/-900 SERIES	Installation of electrical wiring provisions for cargo loading system inforward and aft lower cargo compartment.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List B737-1000, Revision H, dated 31 March 2018, orlater FAA approved revision.2. Engineering Change Order (ECO) 737-001, Revision G, dated 10 April2001, or later FAA approved revision.3. For Boeing Model 737-600/-700/-800/-900 cargo compartments andService Bulletin 737-25-38M10300...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This approval does not include the install...	15/11/2018	Active	10061994

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10061995	PAUSTIAN AIRTEX GmbH		LBA TA0712	737-800	Cabin Configuration Change from 186YC to 189YC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, Ref. B7378-25-04-02 Rev. 03 dated 2012-01-09.or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/06/2017	Active	10061995
10061997 (2004-12063 // LBA EMZ SA 1412)	ROEDER PRAEZISION GMBH			M20, M20A, M20B, M20C, M20D M20L, M20SM, M20R, M20S M20E, M20F, M20G, M20J, M20K	Installation of Bendix King Mode S Transponder KT 73	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA STC 2004-12063 from Nayak Aircraft Service GmbH based on:-LBA EMZ SA 1412 Issue 1, dated 10th December 2004.-AFM Supp. Doc. : M20-NY-0706-08, Rev 0or later revisions of the above listed documents approved by EASA.	As listed in the AFMPrior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designchange and/ or repair will introduce noadverse effect upon the airworthiness of the product.	12/10/2017	Active	10061997
10061998 (EASA.A.S.0042)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		F28 MARK 0100	Introduction of Passenger Briefing SystemRev. 1: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:T-100-87 (FA 21 Issue 4)The requirements for environmental protection and the associatedcertifiednoise and/ or emissions levels of the product are unchangeda...	ATL Engineering Order ATL/F100/E004 Issue 1 oror later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	1. Subject to compliance with the provision of Part 21 Subpart E, thisSTC and associated data shall remain valid until surrendered, withdrawnor otherwise terminated.2. If transferof this certificate is requested under Part 21A.116, theSTCwill be reissued.3. This STC is approved only for the produc...	10/11/2021	Active	10061998
10061999 (EASA.A.S.0043)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		F28 MARK 0100	Interior Modification for 60 seat VIP layoutRev. 1: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:T-100-87 (FA 21 Issue 4)The requirements for environmental protection and the associatedcertifiednoise and/ or emissions levels of the product are unchangeda...	FAC Inc Modification Report 190710 initial issueor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	1. Subject to compliance with the provision of Part 21 Subpart E, thisSTC and associated data shall remain valid until surrendered, withdrawnor otherwise terminated.2. If transferof this certificate is requested under Part 21A.116, theSTCwill be reissued.3. This STC is approved only for the produc...	10/11/2021	Active	10061999
10062000	MT-PROPELLER ENTWICKLUNG GmbH		LBA SA1369	PA-60-700P (AEROSTAR 700P) PA-60-601P, PA-60-602P PA-60-600, PA-60-601	Extension of LBA/EASA STC SA1369 and SA1403:Aerostar PA-60-700P ; Installation of MTV-14-B-C/CF(L) 188-30dpropellers: optional installation of MTV-14-B-C/CF(L)188-30g propellers.Aerostar PA-60-600; PA-60-601; PA-60-601P; PA60-602P all modified withFAA-STC SA1658NM Installation of MTV-14-B-C/CF188-30d...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-36, Amendment 4FAR 36, Amendment 36-30This certificate/ approval involves a change to the requirements forenvironmentall...	According to MT-Propeller Master Documentation List No. E-2998, Rev 0Aerostar PA-60-700P with MTV-14-B-C/CF(L)188-30d (counterrotating)propellers to be operated in accordance with MT-Propeller AFM-S DocumentNo. E-996, Rev. 0.Aerostar PA-60-600; PA-60-601; PA-60-601P; PA60-602P all modified withFAA-S...	According AFM-Sprerequisite: modified with STC SE1658NM forPA-60-600, PA-60-601,PA-60-601P, PA-60-602PPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducea...	18/07/2017	Active	10062000
10062006	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	737-800	CLASS 2 FLIGHT ATTENDANT SEAT INSTALLATION ON NEOS 737-800.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration Scheme No.3154-MCS-01 Issue 1.	The cabin attendant seat rest configuration is not to be used during thetaxi, take-off and landing phases of a flight and may only be used oncethe aircraft is in a steady cruise condition.As the leg rest of the cabin attendant seat in fully deployed positionfits into the cart space on each side of t...	24/05/2017	Active	10062006

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062018	AMAC AEROSPACE SWITZERLAND AG	REV. 2		777-300, 777-300ER 777-200, 777-200LR	Wave Ka Band Antenna InstallationRevision 1 adds 777-300 and 777-300ER models and provides showing ofcompliance to ESF CRI B-101.Revision 2 adds the configuration 3 on B777-200LR aircraft types.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-101 Vibration / Buffeting compliancecriteria for large external antenna installationsthe following paragraph(s) at a later...	Initial Issue – Configuration 1 (777-200 / -200LR):- Master Data List MDL-B7771-5300 Revision D, dated 31st of October 2018-Airplane Flight Manual Supplement AFMS-7771-5300 Revision C, dated 27thof April 2017-Instructions for Continued Airworthiness, ICA-B7771-5300 Revision B,dated 30th of October 20...	- For B777-200, B777-200LR: Only applicable to line number 298 andsubsequent. The Airworthiness Limitations per ICA-B7771-5300- For B777-200LR Configuration 3: Only applicable to line number 504 andsubsequent. The Airworthiness Limitationsper ICA-B7771-3-5300- For B777-300, B777-300ER: Only applica...	15/02/2022	Active	10062018
10062025	AEROTEC & CONCEPT			AS 350 B3	G500H EFIS SYSTEM INSTALLATION.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Amdt 4 of CS27 -27.25; 27.27; 27.251; 27.301; 27.303; 27.305;27.307; 27.337; 27.561;27.601; 27.603; 27.607; 27.625; 27.85...	AE17019RFMS, Rotorcraft Flight Manual Supplement, Rev 0, dated 22 May2017;AE17019OSDS, Operational Suitable Data Supplement, Rev 0, dated 09 May2017;or later revisions of the above listed documents approved by EASA.AE17019ICA, Instructionsfor Continued Airworthiness, Rev 0, 07 April2017 (no ALS ide...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/05/2017	Active	10062025
10062027	AIR ALLIANCE GmbH			35, 35A	Installation of Sandel SN4500 EHSI.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aircraft Flight Manual, doc. no. 2015_012_LJ35_0506, revision 02,dated 12 May 2017;- Instructions for Continued Airworthiness, doc. no. 2015_012_LJ35_0507,revision 01, dated 15 May 2017;- Master Document List, doc. no 2015_012_LJ35_Form 2, revision 00, dated22 May 2017;or later revisions of the ab...	None	24/05/2017	Active	10062027
10062034	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		DORNIER 228-212	High North Latitude Operation Modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Modification in accordance with Scandinavian Avionics DesignEngineering Order 2106617-EO Issue 2, dated 07.09.2017.-Operate in accordance with Scandinavian Avionics Design FlightManualSupplement 2106617-AM Issue 3, dated 15.08.2017.-Instructions for Continued Airworthiness in accordance withScandi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/09/2017	Active	10062034
10062041	KELOWNA FLIGHTCRAFT Ltd.	REV. 2	TCCA SA16-86	737-500 737-400 737-300, 737-400, 737-500 737-300	ADS-B OUTRev. 1:- Add CMA-5024 GPS and TRA-100B Transponderpairing- Add CMA-5024 GPS and XS-950 Transponder pairing- Add GPS-4000S GPS and TRA-100B Transponder pairingRev. 2: Administrative revision to add a comment on the approval oflater revisions to the limitation section.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-ACNS, originalissue: CS-ACNS.D.ADSB.001;CS-ACNS.D.ADSB.010; CS-ACNS.D.ADSB.020; CS-ACNS.D.ADSB.025;CS-AC...	ADS-B OUT modifications that do not meet EASA CS.ACNS.D.ADSB (1090 MHzExtended Squitter ADS-B OUT) are to be accomplished in accordance withTable 1 of Kelowna Flightcraft Ltd. Modification Data SummaryK389-102-001-002 Rev. N dated January 6, 2020 and operated in accordancewith Kelowna Flightcraft Lt...	EASA approved Installation of dual GPS systems in accordance with theinstallation prerequisites of Kelowna Flightcraft Ltd. DrawingK389-00001 Rev J dated January 6, 2020 or later revisions of the abovelisted document(s) approved/ accepted on behalf of EASA in accordancewith the Technical Implementati...	13/06/2022	Active	10062041

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062042	QPA S.R.L.	REV. 2		SPORTSTAR RTC	Aircraft Wheel Disc Brake SystemRevision 2 is an administrative re-issuance to update the STC holder'sname from QPA di Pelliconi Iuri & C. S.A.S. to QPA S.R.L.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List QPA-EVEKTOR-32-01/ MDL, Ed. 1, Rev. 0 dated24.04.2016Certification Program QPA-EVEKTOR-32-01/CP, Ed. 1, Rev. 0 dated24.04.2016Compliance Check List QPA-EVEKTOR-32-01/CCL, Ed. 1, Rev. 0 dated24.04.2016Classification of Change QPA-EVEKTOR-32-01/CoC, Ed. 1, Rev. 0 dated24.04.2016Ana...	The STC is applicable to aircraft SportStar RTC conform to TCDS No.EASA.A.592The approval holder shall fulfill the obligations of Part 21, Point21.A.109 or 21.A.451(b) (as applicable).Prior to installation of this design change it must be determined thatthe interrelationship between this design chan...	26/01/2022	Active	10062042
10062049	LANITZ-PRENA FOLIEN FACTORY GmbH	REV. 3		SEE EASA APPROVED MODEL LIST	Application of ORATEX UL600MK3 aircraft covering system, using theaeroplane original stitching pattern	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 22.1, CS 22.29, CS22.251, CS 22.301, CS 22.303<(>,<)>CS 22.305, CS 22.307, CS 22.601, CS 22.603, CS 22.605, CS 22.609...	Application of ORATEX covering & coating system, Doc. No.ADxC-51-C0-001, issue O, dated 13th May 2022ORATEX ApplicationManual & Airplane Maintenance Manual SupplementDoc. No. ADxC-51-001-AMM Edition 8.3, dated 13th September 2022or laterrevisions of the above listed document(s) approved/acceptedu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/09/2022	Active	10062049
10062053	AIRFORMS, LLC	REV. 1	FAA STC SA02469AK	208B 208	Nose gear torque link modification and installation of oversize pins andboltsRevision 1 is an administrative re-issuance following a name change.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Airforms, Inc., Installation Instructions, Report No: 32-604-24-01,Rev/Date: N/C 1 December 2015 or later FAA approved revision.2. Instructions for Continued Airworthiness, refer to Airforms, Inc.,Doc. No. 32-604-24-02, Revision Level: N/C, dated 16 December 2015 orlater FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/11/2022	Active	10062053
10062054	AIRFORMS, LLC	REV. 1	FAA STC SA02410AK	208B 208	Installation of high strength replacement wheel bolt hardwareRevision 1 is an administrative re-issuance following a name change.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Airforms, Inc., Installation Instructions, Report No: 32-601-36-01,Rev. N/C, dated 7 April 2013.2. Instructions for Continued Airworthiness refer to Cessna 208Maintenance Manual, section 32-40-00, revision 25.	The replacement hardware is eligible for installation only on the mainwheels of Cessna models 208 and 208B aircraft with any of the Cessnaapproved tire sizes and 10 inch diameter Cleveland wheel and brakeassembly, P/N 20-244.This Supplemental Type Certificate (STC) is compatible withAeroacoustics, I...	02/11/2022	Active	10062054
10062055	EXTEX ENGINEERED PRODUCTS INC		PMA NO. PQ2203NM SUPPL. 2	500N, 600N 369D, 369E, 369F, 369FF	STC of EXTEX PMA E500N5215 (Transmission Interconnect Shaft-CriticalComponent PMA Replacement Part)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Extex Substantiation Report EE-16-5215.01 Rev IR of 25 Jan 2016,Continued Operation Safety (COS) System dated 21 October 2015.	None	12/06/2017	Active	10062055

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062085	LIBELLULE MONDE INC.	REV. 2	TCCA SA15-95	SEE EASA APPROVED MODEL LIST	Manufacture and installation of interior placards, signs and markings.Manufacture and installation of interior placards, signs and markingsRev. 1: Updates to the certification basis.Rev. 2: Correction of Technical Document reference.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt 11: 25.1,25.601, 25.603, 25.605, 25.853, 25.855(d) , 25.1301, 25.1501, 25.1529.The requirementsc...	Master Drawing List MDL-PA-15-006 rev. MLibellule Instructions for Continued Airworthiness No. ICA-PA-15-006Revision B.or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Installation and servicing instructions as per ICA document.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the pro...	06/02/2024	Active	10062085
10062086	AVIONITEC Ltd.			500N	Installation Garmin Navigator.Removed: Garmin KMA24H Audio Panel; Bendix King KY 196A COM; Bendix KingKLN 90B GPS; Bendix King KX 165 NAV/ COM; Bendix King KRA 405 RadarAltimeter System and Bendix King KN 62A DME.Installed: Garmin GMA35c Audio Panel; Garmin GTN650 (GPS/ COM/NAV);Garmin GTN750 (GPS/ COM...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement Dual GTN Installation: Doc. No. 7015-011, dated 04.04.2017;- Rotorcraft Flight Manual Supplement Traffic Advisory System: Doc. No.7015-012, dated 04.04.2017;or later revisions of the above listed documents approved by EASA.- Master Document List: Doc. No. 7015-01...	- S/N LN076 (HB-ZRM).- GNSS Systems (GTN750/GTN650) limitedto VFR Operation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the...	01/06/2017	Active	10062086
10062093	ADVENT AIRCRAFT SYSTEMS, INC	REV. 3	FAA STC SA03275CH	SEE FAA AML	Installation of an antiskid brake system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation instructions specified on FAA Approved Model List (AML) No.SA03275CH.	1. For EA500 aircraft, installation pf the NG 2.5 avionics suite is aprerequisite and must be installed with this approval.2. For 300/300LW, B200, B200C, B200CT, B200GT, B200CGT and B300/ B300Caircraft, installation of a Collins Pro Line GPS-4000S or Garmin400W/500W series GPS or Garmin G1000 with GI...	22/02/2018	Active	10062093
10062095	2 EXCEL DESIGN LIMITED	REV. 1	CAA UK RESPONSIBILITY	PA-31	Transfer of EASA STC No. 10062095 for Activation of Wi-Fi for SATCOMSystem including Swift Broadband from STC Twenty One Ltd to 2ExcelDesign Ltd.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	STC Twenty One Ltd Flight Manual Supplement S21.FMS-0130 Issue 2 dated 8December 2016or later revisions of the above listed documents approved by EASA.STC Twenty One Ltd Master Document List S21.MDL-1294 Issue 3	Applicable to aircraft serial number 31-7400984 only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and anyotherpreviously installed design change and/ or repair willintroduce noadverse effect upon the airworthiness of the pro...	27/04/2018	Active	10062095
10062099	SPECIALIST AVIATION SERVICESLIMITED		CAA UK RESPONSIBILITY	AW169	AW169 EMS Interior (SAS/MOD/833).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement FMS/833-043 Issue Aor later revisions of the above listed documents approved by EASA.Declaration of Compliance for SAS/MOD/ 833 Issue B, dated 01/06/2017.Maintenance Program Supplement MPS/ 833-040 Issue A, dated 23/05/2017.	This installation must be installed in conjunction with LeonardoHelicopters EMS Machined Floor (UR) Kit P/N 6F5332F00211.Helicopter operation requiring ditching capability is not allowed.NVIS operation requires separate design approval.Prior to installation of this design change it must be determine...	02/06/2017	Active	10062099
10062104	AVIO TECHNOLOGIES SRL			FA150K, FA150L, FA150M F150M, F152, FA152 F150H, F150J, F150K, F150L	Union Aviation Hand Control Installation (Assembly Drawing List 101model C).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement AT-STC-001-AFM, Issue 01r1< (>,<)>or later revisions of the above listed documents approved by EASA.- Declaration of Similarity dated 17.05.2017.- Compliance Checklist AT-STC-001-CS23, Issue 01r1.- Maintenance Manual Supplement AT-STC-001-ICA, Issue 01.- STC Analytical Evaluation AT-ST...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/06/2017	Active	10062104

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062124	JET AVIATION AG	REV. 1		737-700 IGW	VVIP Cabin Interior CompletionRevision 1: Transfer STC 10062124 Revision 0 from Jet Aviation AG, BaselCompletions to Jet Aviation AG	See CRI A-01 EASA Supplemental Type Certification Basis on B737-700 VVIPInterior installationThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Aircraft Flight Manual Supplement: JBSC-M-00048AFM-01, Issue 02;-Certification Compliance Sheet: JBSC-M-00048CCS-01, Issue 05;-Master Data List: JBSC-M-00048MDL-01, Issue 06;Instructions for Continued Airworthiness: JBSC-M-00048ICA-01, Issue 04;Maintenance Planning Document Supplement: MS0004-MPDS,...	Limited to S/N 39095Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designchange and/ or repair will introduce noadverse effect upon the airworthiness of the product.	21/12/2017	Active	10062124
10062139	ROSEMOUNT AEROSPACE, Inc.	REV. 2	FAA ST03360CH	737-900, 737-900ER 737-600, 737-700, 737-800	Provisions for installation of Rosemount Aerospace Electronic Flight bag(EFB) systems.Rev. 1: added configurations P, Rand T.Rev. 2 amends configurations R and T to add capability for LRU dataloading functionality.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1) FAA Approved Flight Manual Supplement as identified in RosemountAerospace Master Data List, Doc No. D06414246, Revision AT, dated December 1, 2022, or later FAAapproved revision.2) For Rosemount Aerospace Master Data List, Doc. No. D06414246,Configuration C (Provisions for Class 2 EFB), FAA A...	1) The equipment (EFB) for which these provisions are intended is notapproved as part of this STC; an operational approval is needed forinstallation and use of the EFB on aircraft.2) For Rosemount Aerospace Master Data List, Doc. No. D06414246,Configurations P, R and T, Incorporation of this designc...	14/03/2023	Active	10062139
10062142	UAB FL TECHNICS			737-500	Passenger Cabin seat reconfiguration and cabin refurbishment on Boeing737-500 aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FL TECHNICS MASTER DATA LIST No. MDL-238-01 Issue A dated 08 June 2017	Restricted to ASN 28923	08/06/2017	Active	10062142
10062144	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)	REV. 1		SEE EASA APPROVED MODEL LIST PER CERTIFICATION PROGRAM C0055-CEP-03	Air Transport StretcherAir Transport StretcherRev. 1: Extension of applicability of the AML STC 10062144 to includethe B737-8/-9 MAX andthe A321NEO models.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.25, CS 25.27, CS 25.305(a)(b), CS 25.307(a), CS 25.321, CS 25.341,CS 25.471, CS 25.561(b)(1)(3)(c)(d)<...	Certification Programme C0306-CEP Rev. 3 dated 17.02.2023Component User Manual C0306-CUM Rev. 1 dated 01.02.2023SEE EASA APPROVED MODEL LISTor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- per Certification Programme C0055-CEP and C0306-CEP- per Component User Manual C0055-CUM and C0306-CUM- only one stretcher per aisle- This STC constitutes an approval for installation only for aircraftserial numbers as stated in Certification Programme C0055-CEP andC0306-CEP. For additional aircra...	09/06/2017	Active	10062144
10062145	HELI AUSTRIA GmbH	REV. 1		B. TO 36999 ONLY) B. 212, 412, 412EP (S/N 36087 A. TO 25669 ONLY) A. AB212, AB412 (S/N 25501	Installation of a KANNAD 406 AF-H or KANNAD 406 AP-H Emergency LocatorTransmitter.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): STC CRI-F-01, Non-rechargeable Lithium Battery.The requirements for environmental protection and the associatedcertified noise and/ or emissions leve...	- Flight Manual Supplement, Doc. No. HAU-D-032-005, Rev. 0;- Instructions for Continued Airworthiness, Doc. No. HAU-D-032-006, Rev.0;or later revisions of the above listed documents approved by EASA.- Master Document List, Doc. No. HAU-D-032-001, Rev. 0.- Certification Plan, Doc. No. HAU-D-032-002,-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/06/2017	Active	10062145

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062156	VECTOR AEROSPACE HELICOPTERSER VICES INC.		FAA STC SR02478AK	SEE FAA APPROVED MODEL LIST	Installation of the L-3 Aviation Products Lynx multilink surveillancesystem model NGT-9000() part number 9029000-20000 or Garmin GTX-345ADS-B transponder part number 011-03302-40.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List (MDL) VAHS-1614-MDL, Revision NC, dated 25November 2016, or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA) for the L-3 AviationProducts Lynx Multilink Surveillance System Model NGT-9000() Part Number9029000-20000 and Garmin GTX-345 ADS-B Transpon...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. This STC is valid for those aircraft types...	09/06/2017	Active	10062156
10062160	E A D AEROSPACE AIRWORTHINESS	REV. 3		777-200/-200LR/-300/-300 ER	KA-Band Satcom installation and activation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-01 (Vibration/ buffeting compliancecriteria for large external antenna installation).The requirements for environmental protection and t...	-Master Drawing List, EAD Aerospace document No. 01523-EAS-A-MDL,Revision I, dated 13 December 2017.- Instructions for Continued Airworthiness Supplement, EAD Aerospacedocument: No. 01523-EAS-A-ICA-01, Revision E, dated 08 December 2017.-Aircraft Flight Manual Supplement, EAD Aerospace document: No.0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/12/2017	Active	10062160
10062162	AIRBUS S.A.S.			A330-203	MOD CJ2073 - TAP CABIN UPGRADE.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Summary ref: ACJC-AJA-16005 Issue 6.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/06/2017	Active	10062162
10062171	AEROTEC & CONCEPT			300LW	Installation of Garmin GTN625 and approval for P-RNAV and LNAVcapabilities.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with AEROTEC Concept modification ref AE16243as defined in Master Data List ref AE16243MDL, Rev 0, dated 01/06/2017and Service Bulletin ref AE16243SB, Iss 4 dated 19/05/2017.Operation in accordance with AEROTEC Concept Flight Manual Supplementref AE16243AFMS, Rev 0, datedI...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/06/2017	Active	10062171
10062175	SPAES GmbH & Co. KG	REV. 1		PA-46-350P	Installation of Directional Antenna NY-164.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Plan (Compliance Checklist) CCL-046-066-53-01, Rev. 00.- Installation Manual INM-046-066-53-01, Rev. 00.- Instructions for Continued Airworthiness ICA-046-066-53-01, Rev. 01.- Master Document List MDL-046-066-53-01, Rev. 01.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2017	Active	10062175
10062183	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		SA226-T, SA226-AT SA226-TC, SA226-TC (SFAR41) SA226-TC, SA226-TC SA226-AT, SA226-T	MTV-27-() on M7 Metro II / Merlin IV equipped with TPE331-() engines	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36, Amendment 4FAR 36, Amendment 36-30.The requirements for environmental protection and the associatedc...	- According to MT-Propeller Master Documentation List No. E-3056, Rev 7- To be operated in accordance with MT-PropellerAFM-S Document No.E-3047, Rev 3- To be installed i.a.w. Installation Instruction Doc. No. E-3048, Rev 0- To be maintained i.a.w. MT-Propeller ICA Document No. E-3049, Rev 0or later...	According limitation section of AFM-S.	14/12/2021	Active	10062183

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062189	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST03314CH	737-800 /737-900S/ 737-900ER 737-500 /737-600/ 737-700	Certification of Compatibility with Cellular and Wireless DataTechnologies.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval as amended by thefollowing additional oralternative airworthiness requirements:14 CFR Part 25 Regulations at the latest amendment 25-0 through 25-11925.1309(a); 25.1529.The requirements for environ...	1. Astronics Armstrong Aerospace Master Data List, Doc. No.DC104-9375-00, Revision B, dated 15 October 2015 or later FAA approvedrevision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Honeywell Display Unit, P/N 4091900-xxx (E...	30/06/2017	Active	10062189
10062193	2 EXCEL DESIGN LIMITED	REV. 4	CAA UK RESPONSIBILITY	B200CT, B200T 200, 200C, 200CT, 200T	Leading Edge Application Pod (LEAP) Series – (LEAP, -R, -R Expandedweight and speed<(>,<)> -M)- Rev4 Alternative Material	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.the following paragraph (s) at a later amendment: CS-23 Amd 1: 23.301,23.303, 23.305, 23.307, 23.573, 23.601, 23.603, 23.605, 23.613, 23.619,23.625.The requirements for environmental protection and t...	For aircraft modified with the Pod “LEAP”:- To be installedaccording to documents in Master data list in 2XL020LEF78(1) Issue 5 dated 16th April 2019;- To be operated according to AFM supplement 2XL020 LEF71B(1) Issue 3,dated 12th April 2019;- To be maintained according to Instructions for Continue...	As indicated in LEF79, Issue 8, dated 24th November 2020.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andany otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the produc...	26/11/2020	Active	10062193
10062194	SABENA TECHNICS BOD	REV. 1		A330-323	A330 Air Caraibes – Ka-band system installation.This modification consists in installing a Ka-band system, supported byInmarsat’s Ka-band Global Xpress network, the associated mechanicalprovisions located above ceiling on center channel for the systemcomponents, and an antenna on top fuselage with i...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-4301-0004 : Vibration / buffetingcompliance criteria for large external antenna installation.The requirements for environmental protectionc...	- Master Data List, ref: MDL-S-00-4039 issue A, dated 06 June 2017;- Instruction for Continued Airworthiness, ref: ICA-F3046-00-010 issueB, dated 30 May 2017;- Aircraft Flight Manual Supplement, ref: AFMS-F3046-00-022 revision. 1,dated 15 May 2017;or later revisions of the above listed documents appr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/03/2019	Active	10062194
10062195	SABENA TECHNICS BOD			A330-323	A330 Air Caraibes cabin and system modification.This modification consists in rearranging the cabin layout by installingadditional passenger seats (from 355 to 378 PAX, economy and premiumeconomy seats) together with new flight attendant seats andreconfiguring cabin partition (galleys, curtains, flo...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, ref: MDL-S-00-4037 issue B, dated 08 June 2017;- Aircraft Flight Manual Supplement, ref: AFMS-F3045-00-031 revision 1,dated 25 May 2017;- Instruction for Continued Airworthiness, ref: ICA-F3045-00-009revision A, dated 26 May 2017;or later revisions of the above listed documents a...	The following modifications must be concurrently embodied with thismodification:- STC 10014507 Revision 2– Floor Pathmarking installation.- MOD-S-23_4087 AAP - Placard modification (Minor change – Approvedunder DOA EASA. 21J.055).- 1095L-25-06 revision 00 - Galley G12 modification (Minor change -Appr...	14/06/2017	Active	10062195
10062198	SELL GmbH	REV. 2		777-200LR, 777-300ER	Relocation of Galleys M1, M2, Pelmet and BC Coat Stowage.Rev.1: Aircraft Serial Numbers extension.Rev.2: Type Definition Document update.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Type Definition Document, SELL GmbH document No. TDD-1041G-25-34<(>,<)>Revision B, dated 14 June 2018<(>,<)>or later revisions of the above listed documents approved by EASA	OSD data must be approved before entry into service with anEuropeanUnion operator.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upo...	15/06/2018	Active	10062198
10062203	DASSAULT FALCON SERVICE			MOD. M3083 FALCON 900EX (F900EX) WITH	FANS 1/A-OCL ENABLE switch installation in cockpit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- DFS AFM Supplement Ref. F900-037 dated 09 June 2017;- MASTER DOCUMENT LIST Rev. DFS-DE-17-F9-9826 Issue A dated 09 June 2017;or later revisions of the above listed documents approved by EASA.	Installation of Iridium Satcom, Inmarsat Satcom and FANS 1/A to beactivated over Iridium are pre-requisite for this deign change.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/...	14/06/2017	Active	10062203

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062211	BOMBARDIER Inc.		TCCA SA17-28 ISSUE 1	BD-100-1A10	EASA validation of Transport Canada Supplemental Type CertificateSA17-28 at Issue 1.Replacement of DCMP Hydraulic FluidLines.Modification to be completed in accordance with B/E Aerospace Inc.Modification Data Summary number K922000 Revision NC or later approvedrevisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification to be completed in accordance with B/E Aerospace Inc.Modification Data Summary number K922000 Revision NC.For Instructions for Continued Airworthiness, refer to K922070 RevisionNC.or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implement...	See those of original Transport Canada approved STC SA17-28.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of...	16/06/2017	Active	10062211
10062222	AMAC AEROSPACE SWITZERLAND AG			777-200LR	Interior Outfitting	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-02,,Isolated CompartmentsD-06,,Glass Screens of Displays / MonitorsD-09,,Shower InstallationD-15,,Crew Rest Compartment and Flight Crew Rest Compart...	-Master Data List MDL-DW01-2500 Rev. D dtd. 16.06.2017-Airplane Flight Manual Supplement AFMS-DW01-2500 Rev. C dtd. 02.06.2017-Instructions for Continued Airworthiness ICA-DW01-2500 Rev. B dtd.14.06.2017or later revisions of the above listed documents approved by EASA.	Per Airplane Flight Manual Supplement AFMS-DW01-2500Per Instructions for Continued Airworthiness ICA-DW01-2500Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will int...	16/06/2017	Active	10062222
10062247	AVIATION TECHNICAL SERVICES, Inc.		FAA STC ST02541SE	A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of a reconfiguration of the cabin interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval except where amended as listed below:Regulation25.571 (a)(b) Amdt. 25-54Regulation 25.869(a)(1)(4) Amdt. 25-113Regulation 25.853(a)(c)(d)(e)(f)(g)(h)Amdt. 25-116Regulation 25.854 Amdt. 5-74Regulat...	1. Aviation Technical Services Master Data List (MDL) 721546-MDL-002,Revision J, dated 26 April 2017, or later Federal AviationAdministration (FAA) approved revision.2. Instructions for Continues Airworthiness (ICA) 721546-ICA-002,RevisionA, dated 24 May 2017, or later FAA-accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/06/2017	Active	10062247
10062249	AVIATION TECHNICAL SERVICES, Inc.		FAA STC ST02525SE	737-800, 737-900 737-600, 737-700	Installation of a Cargo Door Latch	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval except where amended as listed below:14 CFR §21.50 Amdt. 21-9214 CFR §25.611(a) Amdt. 25-12314 CFR §25.783(a)(1)(3)(5)(c)(2)(d)(1)(2)(e)(1)(3)(h) Amdt. 25-11414 CFR §25.899 Amdt. 25-12314 CFR §25....	Aviation Technical Services Master Drawing List (MDL)-718932-MDL-001 ,Revision K, dated 11 January 2017, or later Federal AviationAdministration (FAA) approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/06/2017	Active	10062249
10062277	WIPAIRE Inc.		FAA SA03323CH	182S, 182T	Installation of Lycoming I0-580-B1A engine and HartzellHC-F3YR-1AN/ NG8301-3 Propeller at 3158 lbs Gross Weight on TextronAviation Inc. model 182S and 182T.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	- Wipaire, Inc. Installation Instruction, Document No. 1005680, RevisionF, dated January 1, 2016;- FAA Approved Airplane Flight Manual Supplement, Document No.POHSA03323CH-L-1, NoRevision, dated March 20, 2015;or later revisions of the above listed documents approved by EASA inaccordance with EASAt...	1. This STC is currently valid for landplanes only.2. Engine limitations refer to Installation Instruction, Document No. 1005680	19/06/2017	Active	10062277
10062279	BOGGI S.R.L.			AW169	Incubator Installation on AW169 Helicopter.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 29 amdt. 3: 29.21,29.25, 29.27, 29.29, 29.31, 29.251, 29.301, 29.303, 29.305, 29.307,29.309, 29.321, 29.337, 29.339, 29...	Rotorcraft Flight Manual Supplement 169P00200-RFMS Issue 1<(>,<)>or later revisions of the above listed documents approved by EASA.Master Document List 169P00200-Mdl Issue 2, dated 14/06/2017.Declaration of compliance 169P00200-DoC Issue 0, dated 14/06/2017.	This STC must be installed in conjunction with Aerolite STCNo. 10056129(Kit P/N 169-0040200-501).Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadv...	19/06/2017	Active	10062279

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062280	PMV ENGINEERING	REV. 2		A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	ELT survival installation on A320 family (A318 excluded)Initial approval: the STC consists in installing a TECHTEST LIMITEDEmergency Locator Transmitter Survival ELT(S) Series 500-12 in adedicated overhead bin of the A320 family aircraftRevision 1: a second configuration is added - Cockpit coat clos...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.the following paragraph (s) at a later amendment: CS 25 amdnt 18 for thefollowing requirements: 561 (c)(1)(i)(ii)(iii)(2)(d), 601, 611,787(a)(1)(2)(3), 789 (a), 863(a)(b)(1)(2)(3)(4)(5)(c)(d), 1301(a)...	- MASTER DOCUMENT LIST, ref: AVI-01510-MDL-R06 dated 06/03/2020- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: AVI-01510-ICA-R03 dated14/11/2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/03/2020	Active	10062280
10062281	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			200	HySpex Camera replacement by Trimble AX60 Camera System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-To be installed according to Engineering Order No. CV5465-062, Rev. IR,dated 6 December 2016;-To be operated accordingto AFM Supplement No. CV5465-071, Rev. IR,dated 15 December2016;-To be maintained according to ICA No. CV5465-085, Rev. A, dated 6February 2017.or later revisions of the above lis...	Limited to the S/N: BB353Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	20/06/2017	Active	10062281
10062286	AIRCRAFT SPECIALTIES SERVICES, Inc.		FAA STC SE09846SC	SEE FAA APPROVED MODEL LIST	Installation of S539800M30 and S539800M40 Starter Adapter Springs	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Aircraft Specialties Services, Inc. STC Document List 1101A, Rev. 1dated 3 May 2006, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for engine types and models ap...	21/06/2017	Active	10062286
10062288	AIRBUS HELICOPTERS, Inc.	REV. 1	FAA STC SR09298RC-D	MBB-BK117 D-3 MBB-BK117 D-2 MBB-BK117 C-2	Installation of a Concorde RG-380E/44 lead acid batteryRevision 1 adds battery installation for the D3 model.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR09298RC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	Drawing List 145A82-8009, Revision E, dated 22 August 2012;Model MBB-BK 117 C-2:- Rotorcraft Flight Manual Supplement 117FMS-221, Revision B, dated 8May 2013;- Instructions for Continued Airworthiness 145MMS-001, Revision D, dated12 December 2012;Model MBB-BK 117 D-2/D3:- Rotorcraft Flight Manual Su...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Additional limitations may be detailed in the Ro...	04/01/2022	Active	10062288
10062295	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 1		412, 412EP	Installation of Flight Data Monitoring system HELICOM V2 ANA or HELICOMV2+ ANAInstalled: - Device HELICOM V2 ANA (PN4720F-xx / PN4730F-xx) including lipo battery(PN4002) and Rack HELICOM V2ANA (PN4770-xx). or - Device HELICOM V2+ ANA (PN4720P-xx / PN4730P-xx)ANA (PN4...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 (Lithium Battery Installations).The requirements for environmental protectionand the associatedcertified noise and/ or emissions levels o...	- RFMS: Doc. No. N11-BELL412 HV2 HV2+ ANA-E-A-02 Rev.03, dated20.12.2016<(>,<)>or later revisions of the above listed documents approved by EASA.- Master Document List: Doc. No. N10-BELL412 HV2 HV2+ ANA-E-A-06, dated16.06.2017.- Installation Manual: Doc.No. N7-BELL412 HV2 HV2+ANA-E-A-04,20.12.2016.-...	- This STC is not applicable to Model 412EP helicopters serial numbers37002 thru 37999 with FADEC.- The system does notreplace standard maintenance records and pilotreporting.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and a...	27/02/2020	Active	10062295
10062301	JET AVIATION AG	REV. 2		737-900ER	Live Live TV Antenna Stmctural ProvisionsMajor Change to EASA STC 10062301 to remove the limitation of 500 FC or6 months.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CR1 C-102 Vibration & buffeting compliancecriteria for large external antenna installation.The requirements for environmental protection andc...	JBSL-M-00914 ICA-0l Issue 6 Instruction tor Cont. AirworthinessJBSL-M-00914 MDL-01 Issue 10 Master Data Listor later revisions of the above listed documents approved by EASA.	None	13/12/2017	Active	10062301

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062317	AIRTRONIC SAS			SEE EASA APPROVED MODEL LIST	DR Series A/C Poly-Fiber Fabric Covering	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS-23, Amdt. 3CS23.29 Empty weight and corresponding centerof gravityCS23.305 Strenght and deformation (Tenue mécanique...	Poly-Fiber STC Aircraft Model List for DR Series Aircraft, Issue Date 01March 2017 - Rev. 00 dated 15-03-2017Installation and maintenance instructions “Supplément manuel demaintenance - entoilage Poly-FIBER - avions DR220, DR300-400” Edition 01dated 07-06-2017or later revisions of the above listed d...	None	23/06/2017	Active	10062317
10062336	BOMBARDIER Inc.		TCCA STC SA05-60 ISSUE 1	BD-700-1A11	Complete Custom Aircraft Interior.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-200 EASA Special Condition and Deviation: Side facing divans.Equivalent Safety Finding (s):D-500 Emergency exit signs reduction in size of letteringb...	Aero Consulting Services Ltd. Configuration Definition ListE025000Revision FY (dated 23rd March 2017), andAirplane Flight Manual Supplement G-FM25004501 Revision N/C,or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ Ca...	-) See those of original Transport Canada STC SA05-60 and of the AFMSupplement quoted above in the associated technicaldocumentationparagraph.-) For Instructions for Continued Airworthiness, refer to the followingdocument GCXXXX0000-IFCA or GCXXXX0000-ICA as applicable (where XXXXdenotes the serial...	26/06/2017	Active	10062336
10062337	SOCIETE AIR FRANCE S.A.			747-400	IFE WiFi system installation and activation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25 Change 14 for: 25.853, 25.869, 25.1423The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original produ...	- Instruction for Continued Airworthiness, ref: ICA-B747-16-002-001 Rev0- AFM ref: AFMS-B747-16-002-001or later revisions of the above listed documents approved by EASA.- Master Data List: Change Approval Sheet ref: CAS-B747-16-002 Rev 0	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/06/2017	Active	10062337
10062339	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		PA-28-236 (DAKOTA) PA-28-235 (CHER.PATHFINDER)	Installation of MTV-9-B/198-52( ) Propeller on Piper Aircraft, Inc.PA-28-235 and PA-28-236.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, 14 CFRPart 36 Amdt 36-32This certificate/approval involves a change with an impact on the noise...	According to MT-Propeller Master Documentation List No. E-2878 Rev. 5To be operated in accordance with MT-Propeller AFM-S Document No. E-2885Rev. 5To be installed i.a.w. MT-Propeller Installation Instructions Doc. No.E-2886 Rev. 2To be maintained i.a.w. MT-Propeller ICA Doc. No. E-2887 Rev. 2or late...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/08/2025	Active	10062339
10062340	BS DESIGNS, INC.		FAA STC SA09872AC	208/ 208B	Installation of Hartzell Propeller, Inc. Composite PropellerHC-E4N-5KL/JNC10904(B)<(>,<)> De Ice, or HC-E4N-5KL/JNC10904, Non-DeIce.	The Certification Basis (CB) for the original product remains applicableto this certificate/approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	BS Designs, Master Data List BSD-MDL-208-01, Rev. B1, datedApril 20,2017.Airplane Flight Manual Supplement dated April11, 2017or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF(or subsequent revisions ofthis decision)” and/ or the Techn...	1. The installation of the Honeywell International, Inc.TPE331-12JR-704TT turboprop engine is required, in accordance with EASASTC 10033267 (FAA STC SA10841SC).2. The Hartzell HC-E4N-5KL/JNC10904() propeller diameter limits are279.4 – 277.9 cm (110 to 109,5 inches).3. Honeywell Service Bulletin No.1...	23/08/2017	Active	10062340

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062360	RUAG AG	REV. 1		DORNIER 228-202	Approval of Avionics Upgrade DO228-202 Serial 8112.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Installation in accordance with RUAG Schweiz AG, Master Document Listref MDL-8003966, Revision A, dated 26th June 2017.- Operate in accordance with RUAG Schweiz AG, Flight Manual Supplementref FMS-611234 Revision A, dated 23rd June 2017.- Instructions for continued airworthiness in accordance with RU...	Aircraft Serial 8112 Only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effectupon the airworthiness of the product.	02/02/2021	Active	10062360
10062364	Q.C.M. DESIGN GmbH			CL-600-2B16 (604 VARIANT)	Exterior LED Lights Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	QCM design GmbH Certification Report No. B605-QCM33-001 Initial IssueDated 26th June 2017	Restricted to ASN 5301 to 5699 and ASN 5701 to 5990	27/06/2017	Active	10062364
10062368	STC TWENTY ONE LIMITED	REV. 2	CAA UK RESPONSIBILITY	A319-111, A320-214	Activation of FeiTian System Media Server with Cabin Wi-FiRev. 1: Transfer from STC Twenty One to JAMCO Aero Design & Engineering.Rev. 2: Transfer from JAMCO Aero Design & Engineering to STC Twenty OneLimited.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0133 Issue 1- STC Twenty One Ltd Master Document List No. S21.MDL-1311 Issue 1or later revisions of the above listed documents approved/ accepted underthe EASA system.	The design change only provides approval for aircraft tolerance to2.4GHz, 5GHz and Cellular Rf radiation and the operation of the mediaserver with cabin Wi-Fi, Portable ElectronicDevices (PEDs) must stillbe operated as per the aircraft PED Policy.It is the responsibility of the Aircraft Operator to...	09/07/2019	Active	10062368
10062428	AIRBORNE TECHNOLOGIES GmbH			P2006T	STC-AT-108 Noise Certification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	AFM-STC-AT-108, Rev. 2, date 25.04.2017or later revisions of the above listed documents approved by EASA.	None	29/06/2017	Active	10062428
10062438	AIRBUS HELICOPTERS UK LIMITED	REV. 1	UK.STC.00210 REVISION 01	MBB-BK117 D-2, MBB-BK117 D-3 MBB-BK117 D-2	Revision 0: Full NVIS certificationRevision 1:This Major Change to STC extends the applicability to also include theMBB-BK117 D-3 model. In addition, White Phosphor NVGs AN/ AVS-9 (M949)are added to the approved configuration for the MBB-BK117 D-2 andMBB-BK117 D-3.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Revision 0AUTHORITY CERTIFICATION PLAN ACP/1453050-01 iss.ECHANGE CLASSIFICATION AND DESCRIPTION CCL/ 1453050-01 iss.CDrawing AHUK/1453050-101-01 Iss.CInstruction for Continued Airworthiness ICA/1453050-01 iss.CDESIGN COMPLIANCE REPORT DCR/1453050-01 iss. CDECLARATION OF COMPLIANCE DOC/ 1453050-01 iss...	Rotorcraft modified with this design change employ Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, modifications that add or change systems that emit orreflect light haveN...	03/07/2025	Active	10062438
10062454	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A330-203	A330-203 Cabin Modification.Rev 1.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SR Technics Aircraft Flight Manual Supplement S.OAEZ.001579-AFM Rev. 01or later revisions of the above listed documentsapproved by EASA.Master Document List S.OAEZ.001579-MDL Rev. 00.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/04/2021	Active	10062454

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062462	KUERZI AVIONICS AG			AS 350 B2, AS 350 B3	Installation of EFIS IDU450 and general avionics upgrade ofAS350helicopters.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement, FMS-201518928, original issue, dated 25 April2017< (>,<)>or later revisions of the above listed documents approved by EASA.Instruction for Continued Airworthiness ICA-201518928, rev C, dated 24April 2017.Master Document List, MDL-201518928, original issue, dated 30 June 2017...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/06/2017	Active	10062462
10062477	GFD GmbH	REV. 1		35A	Iridium Satcom Antenna Installation Provision.Rev. 1: Transfer to GFD GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- According to AIEC Master Data List No. EA5522-049, Rev. IR- To be installed i.a.w. AIEC drawing list EA5522-082, Rev IR- To be maintained i.a.w. AIEC ICA Document No. EA5522-085, Rev IROr later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Applicable to SN: 35-654.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	23/08/2022	Active	10062477
10062480	CHIPPEWA AEROSPACE, Inc.		FAA STC ST04367AT	SEE FAA APPROVED MODEL LIST	Removal of the Existing Honeywell DL-900 or DL-950 Data Loader andInstallation of the Honeywell DL-1000 Data Loader.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Chippewa Aerospace Master Drawing List (MDL) No. CAI-3461-03-0001,Rev. IR, Dated 27 December 2016, or later FAA approved revision.2. Document No. CAI-3461-01-0002, Rev. I, Dated 15 May 2017, or laterFAA approved revision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for those aircraft typesa...	03/07/2017	Active	10062480
10062481	FOKKER SERVICES B.V.			DHC-8-201, DHC-8-202	ADS-B out on the Dash 8-200 series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Initialissue of CS ACNS.D.ADSB.001; CS ACNS.D.ADSB.010; CS ACNS.D.ADSB.020; CSACNS.D.ADSB.025; CS ACNS.D.ADSB.30; CS ACNS.D.ADSB.35; CSACNS.D.ADSB.40; CS ACNS.D.ADSB.45;C...	- DHC8-FXI-AFM-S-004, Airplane Flight Manual Supplement, Revision 1dated 20 Jan 2017- DHC8-FXI-MMEL-S-001, Master Minimum Equipment List Supplement,Revision 02 dated 11 April 2017or later revisions of the above listed documents approved byEASA.- DHC8-FXI-AMM-S-005, Supplement Aircraft Maintenance M...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/07/2017	Active	10062481
10062495	DART AEROSPACE Ltd.		TCCA SH17-7 ISSUE 1	R66	Dart Aerospace Ltd. Heli-Utility-Basket Installation for Robinson R66 inaccordance with Master Document List MDL-D066-1016.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement Heli-Utility-Basket Robinson R66 FMS-D066-1016Revision A< (>,<)>or later revisions of the abovelisted documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.- Master Document List Heli-Utility-Basket Robinson R66...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/07/2017	Active	10062495

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062521	AIRBORNE TECHNOLOGIES GmbH			EC135 P2+	Laser illuminator activation – MX 15HDi camera.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS27 Amdt. 2: 27.301, 27.303, 27.305, 27.307, 27.601, 27.603,27.609,27.610, 27.773, 27.1301, 27.1309, 27.1322, 27.1327, 2...	Flight Manual Supplement STC-111-0-AFM for Rotorcraft EC135P2+ "LaserIlluminator Activation", Rev. 4, dated 14 July 2017<(>,<)>or later revisions of the above listed documents approved by EASA.- Certification Program STC-111-0-CP, Rev. 2.- Maintenance Manual Supplement STC-111-0-AMM, Rev. 2.- Appli...	This STC is limited to EC135 s/n 600.Requires as a precondition the installation of:- EASA STC 10042009, Rev. 2.- EASA Minor Change 10059956.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design...	14/07/2017	Active	10062521
10062524	AVIANOR INC	REV. 2	TCCA O-LSA17-028/D ISSUE 4	BD-500-1A11	Design and Installation of Removable Seat Table.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avianor Master Document List No. MDL 16150701 Revision F dated 13 March2019<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ CanadaBilateral Agreement.	Restricted to ASNs 55003,55004,55005,55006,55007, 55008,55009,55016,55034,55038, 55039, 55041, 55042, 55043, 55050, 55051, 55052, 55053, 55054, 55055, 55064, 55071, 55085, 55093.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and...	09/07/2019	Active	10062524
10062526	TASS-EU Ltd.		CAA UK RESPONSIBILITY	767-300	Installation of EROS Full Face Quick Donning Mask RegulatorMF40-40-007& Stowage MXP827.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-25 Amendment 18:CS25.1; CS25.301(a)(b); CS25.303; CS25.305(a); CS25.307(a);CS25.321(a)(b)(c)(d); CS25.341(a)(b)(c); CSC...	TASS-EU Flight Manual Supplement No. 162034-FMS-019 Issue 1<(>,<)>or later revisions of the above listed documents approved by EASA.TASS-EU Master Document List No. 162034-MDL-005Issue 5.	None	05/07/2017	Active	10062526
10062531	FLYING COLOURS CORP.		TCCA C-LSA15-038/D ISSUE 1	CL-600-2B16 (604 VARIANT)	Aircell Aviator 300 Swift Broadband<(>,<)> Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	B/E Aerospace Airplane Flight Manual Supplement No. K179090Rev N/C<(>,<)>or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.B/E Aerospace Modification Data Summary No. K179000 Rev N/C.	Restricted to ASN 5520.	06/07/2017	Active	10062531
10062542	COMMUTER AIR TECHNOLOGY Inc.		FAA STC SA8986SW	B200T, B200GT, B200GT B200, B200C, B200CT A100-1, A200, A200C, A200CT 300, 300LW, B300, B300C 200, 200C, 200CT, 200T	Installation of full turning contoured engine exhaust stacks	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing No. DL93005, Revision 3, or later FAA approved revision.2. Required Instructions for Continued Airworthinessare contained inDrawing No. 78-02-01, 78-02-02, 78-02-03, or 78-02-04.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/07/2017	Active	10062542
10062544	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED	REV. 2	CAA UK RESPONSIBILITY	EC135 T2, EC135 T2+, EC135 T3 EC135 P1, EC135 P2, EC135 P2+	TPED Tolerance Certification on EC135Revision 1: Extension of STC applicability to EC135 P2, EC135 P2+, EC135T2, EC135 T2+.Revision 2: Extension of STC applicability to EC135 P1 (with CDS cockpitvariant).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft manual Supplement FMS/140-002 Issue 4- Instruction for Continued Airworthiness ICA/140-007 Issue 5- DesignReport DR-140-001 Issue 7- Post Installation Actions PIA/140-006 Issue 3- Modification Leaflet& Certificate of Design Issue 4or later revisions of the above listed document(s) appr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/03/2019	Active	10062544

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062545	AERO-DIENST GMBH & CO. KG			55/ 55B/ 55C	Replacement of DFDR F800 by DFDR F1000.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forSpecial Condition (s):CRI F-01 Non-Chargable LiOnBat.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	According to Aero-Dienst Master Document List No. 20299-LJ.DC-101, Rev. 1.To be operated in accordance with Aero-Dienst AFM-S Document No.20299-LJ.DC-106, Rev. 00or later revisionsof the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No.20299-LJ.DC-104,T...	According limitation section of AFM-S.Prior to installationof this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	07/07/2017	Active	10062545
10062561	CARLISLE INTERCONNECT TECHNOLOGIES	REV. 1	FAA STC NO. ST04035CH	757-200PF 757-200	Installation of Ka-Band Satellite Communication (SATCOM) SystemProvisions in accordance with Carlisle Interconnect Technologies (Carlisle IT) Master Data List (MDL) ECS-211102, Revision L, dated 12January 2018, or later approved revision.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:14 CFR Part 25 at the latest amendment through 25-113:25.251(a)(b), 25.305 (a)(b)(e), 25.351(a)(b),25.365(a)(b)(d)(e)(3),25.561(a)-(d), 25.571(a)(b)(e)(1), 25.603(a)-(c),2...	- Carlisle Interconnect Technologies Aeroplane Flight Manual Supplement (AFM-S) Document No. ECS-211106, Revision B<(>,<)> dated 09 January2018.- Carlisle IT Instructions for Continued Airworthiness Document No.ECS-211108 Revision E<(>,<)> dated 07 November 2017.or later revisions of the above listed...	Aeroplanes modified by this STC must be:- operated in accordance with Carlisle Interconnect Technologies AFM-Sdocument No. ECS-211106.- maintained in accordance with Carlisle IT ICA document No. ECS-211108.AMoC to Airworthiness Directive(s):This modification is approved as an Alternative Means of Co...	16/10/2018	Active	10062561
10062562	CARLISLE INTERCONNECT TECHNOLOGIES		FAA STC NO. ST04047CH	757-200PF 757-200	Installation and activation of a Honeywell Ka-Band SatelliteCommunications (SATCOM) System in accordance with Carlisle InterconnectTechnologies (Carlisle IT) Master Data List (MDL) document ECS-211103Revision H, dated 27 January 2017.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:14 CFR Part 25 at the latest amendment through 25-113:25.305 (a)(b), 25.561(a)-(d), 25.571(a)(b), 25.603(a)-(c), 25.605(a),25.613(a)(b), 25.869(a)(4), 25.981(a)(3), 25.141...	-Carlisle Interconnect Technologies Aeroplane Flight ManualSupplement (AFM-S) Document No. ECS-211107 Revision A, dated05 November 2015.- Carlisle IT Instructions for Continued Airworthiness Document No.ECS-211109 Revision D, dated 02 March 2016.-Carlisle IT EWIS ICA document No. ECS-211121 revision...	Prerequisite: EASA STC 10062561 must be installed prior to,orconcurrent with, this modification.Conditions:Aeroplanes modified by this STC must be:- operated in accordance with Carlisle Interconnect Technologies AFM-Sdocument No. ECS-211107.- maintained in accordance with Carlisle IT ICA document N...	10/07/2017	Active	10062562
10062566	S4A SOLUTIONS FOR AVIATION, S.L			P2006T	FMS limitation change	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement P2006T6-HDK01 issue 9or later revisions of the above listed documents approved by EASA.Modification description D 2006T6-DES01 Ed. 4	This change is limited to P2006T Serial Number 085 & 129Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the...	10/07/2017	Active	10062566
10062569	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST04143CH	737-900, 737-900ER 737-700, 737-800	EASA validation of FAA STC ST04143CH. Installation of a TelefonixWireless In-Flight Entertainment (IFE) System in accordance withAstronics Armstrong Aerospace Master Data List, Doc. No. DC104-9734-00,Revision (J) dated 15th May 2017 or later approved revisions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 impacted requirements at initial issue<(>,<)> unless otherwisespecified: 25.29; 25.301(a, b)(amdt 1); 25.303; 25.305(a...	The STC installation must be performed in accordance with AstronicsArmstrong Aerospace Master Data List, Doc. No. DC104-9734-00, Revision (J) dated 15th May 2017, andThe Airplane Flight Manual Supplement, Astronics Armstrong Aerospace Doc. No. DC303-9734-00, Rev (-) approved 07th October 2016 or late...	1) See those of original FAA STC ST04143CH and those of theAirplaneFlight Manual Supplement and other documents listedabove underassociated technical documentation.2) Aircraft modification in accordance with this STC requires prior orconcurrent embodiment of FAA STC ST03314CH, Certification ofComp...	10/07/2017	Active	10062569

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062574	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 1	FAA STC SA781GL	404	Replace existing Main Wheel and Brakes by installing ParkerHannifinConversion Kit 199-78.Rev. 1: Transfer from "ParkerHanifin Aircraft Wheel and Brake Division"to "Kaman Corporation Aircraft Wheel and Brake Divsion".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	Installation Instructions and Installation Drawing 50-54 Rev. C dated 31May 1984 or later FAA-approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/10/2024	Active	10062574
10062577	ALPINE AEROTECH LP	REV. 1	TCCA SH13-13 ISSUE 1	212/ 412/ 412EP	Aft Cabin Wall Protection Kit (TCCA STC SH13-13, Issue 1).Installation of polymer panels on top of the cabin pylon and aft cabincomposite panel walls, to provide protection from damages and wear.Polymer panels are bolted on inserts alreadyinstalled on the nativecomposite panels.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AAL-212-030-701, Revision A, dated 2015-09-29.AFT CABIN BULKHEAD PROTECTOR, KIT INSTRUCTIONS FOR CONTINUINGAIRWORTHINESS or later approved revisions from TCCA.Doc. No. AAL-212-040-701, Revision B, dated 2015-10-26.PYLON PANEL PROTECTOR, KIT INSTRUCTIONS FOR CONTINUING AIRWORTHINESS orlater approved...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/07/2017	Active	10062577
10062579	GOERRES, HARALD	REV. 1		FOURNIER RF 5 B "SPERBER" FOURNIER RF 5	Various Improvements reg. instruments.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Bulletin: Major Change HG-MC-RF5-001or later revisions of the above listed documents approved by EASA.Eränzungen zum Flughandbuch bezüglich der Änderung des InstrumentenPanels/ Supplimental pages to Flight Manual, relating to modification ofthe instrument panel<(>,<)> dated May 2017.Erg...	Valid for Models Fournier RF 5 / RF 5BOpiton 1 (electronical engine Tachometer) only with Rotax enginePrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducea...	19/07/2017	Active	10062579
10062583	21JAERODESIGN LIMITED	REV. 1	CAA UK RESPONSIBILITY	A320-252N/-253N A320-231/-232/-233/-251N A320-211/-212/-214/-215/-216 A319-131/-132/-133/-151N A319-111/-112/-113/-114/-115	Introduction of Zero-passenger Seating ConfigurationRevision 1: Extension of applicability	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs at a later amendment: CS 25 Amendment 18 - CS25.25, CS 25.27, CS 25.601<(>,<)>CS 25.785, CS 25.803, CS 25.813, CS 25.815, CS 25.817, CS 25.853, CS...	21JAerodesign Design Change Document No. DCD-0007M Issue 0221JAerodesign Design Change Document No. DCD-0097M Issue 01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/04/2019	Active	10062583
10062588	AIRBUS S.A.S.			A350-941	MOD CJ2060 Installation of A350 2KU Antenna: installation of outsideaircraft equipment for 2Ku system including large antenna, base plate,adapter and lugs.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forEquivalent Safety Finding(s):CRI B-2301-001: Vibration / buffeting compliance criteria for largeexternal antenna installation.The requirements for environmental protect...	Certification Summary Report ref: ACJC-AJA-16015 Issue 6.Modification Approval Sheet: MAS CJ2060 Issue C.Instructions for Continued Airworthiness (ICA): MPD-S A350 MOD CJ2060Rev 01or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/07/2017	Active	10062588
10062593	HELIFAB Inc.d/b/a ARROW AVIATION CO. LLC		FAA STC SR02597LA	206L-4, 407 206B, 206L, 206L-1, 206L-3	Installation of radar altimeter antenna mounting provisions	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. HELIFAB Inc. Master Document List HF-MDL-7-6, Revision IR, dated 4February 2016, or later FAA approved revision.2. Continued Airworthiness, ICA, HF-CA-7-6, Revision IR, dated 25January 2016, or other FAA accepted ICA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/07/2017	Active	10062593

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062601	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 3	FAA STC ST02609LA	SEE EASA APPROVED MODEL LIST	EASA Validation of FAA approved AML STC ST02609LA for the NXT-700System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	8009629-901 Rev IR EASA Approved Airplane Flight Manual Supplement. 8909629-001 Rev. A Approved Amended MDL. 8909629-600 Rev. A ICA.EASA AML List (attached to EASA STC)or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/07/2017	Active	10062601
10062607	SABENA TECHNICS BGC	REV. 1	FAA STC SH3261SH	F 406	Replacement of GPS for RNAV5, LNAV and LPV capability on CESSNA F406.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS23 Amdt. 3: 23.1,23.21(a)(1), 23.29, 23.301 (a), 23.303, 23.305, 23.307(a), 23.321,23.337, 23.341, 23.561(b) (2), 23.601(a...	AFM Supplement Ref. 0835-01-A-2301-R01 (12-Jul-2017)<(>,<)>or later revisions of the above listed documents approved byEASA.- ICA Ref. 0835-01-A-2211-R00 (11-Jul-2017)<(>,<)>- MDL Ref. 0835-01-A-2103-R00 (12-Jul-2017).	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	18/07/2017	Active	10062607
10062614	S4A SOLUTIONS FOR AVIATION, S.L			60	ISAT SYSTEM AND ANTENNA INSTALLATIONInstallation of SkytracSatCom systems ISAT-100 and ISAT-200A (only oneof them to be installed in the aircraft at the same time) in cockpit andavionics bay, and related GPS/Iridium antenna installation on top offuselage with correspondent modification and reinforc...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI-F-01, Lithium battery installations.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	- S4A Modification Description, ref. doc. L6006-DES01, issue 4, dated8th June 2017;- S4A Master Data List, ref. doc. L6006-RPT02, issue 4, dated 8th June2017;- S4A Certification Plan, ref. doc. L6006-CPL01, issue 5, dated 8th June2017;- S4A Flight Manual Supplement, ref. doc. L6006-HDK01, Issue 3, d...	None	13/07/2017	Active	10062614
10062621	PMV ENGINEERING			A310-304/-308/-322/-324/-325 A310-203/-203 C/-204/-221/-222 A300 F4-622 R A300 C4-620/ F4-203/ F4-605 R A300 C4-203/ C4-605 R VARIANT A300 B4-620/ B4-622/ B4-622 R A300 B4-601/ B4-603/ B4-605 R A300 B4-203/ B4-220/ B4-2C A300 B4-102/ B4-103/ B4-120 A300 B2-203/ B2-320/ B2K-3C A300 B1/ B2-1A/ B2-1C/ B2-202	CVR/FDR upgrade on Airbus Wide Body.The aim of this modification is to replace the existing 30 minutes CVR(tape recorder) by a 120 minutes SSCVR (Solid State Recorder) and toreplace the existing 25 hrs FDR (magnetic tape recorder) by a 25 hrsSSFDR (Solid State Recorder).The change also allows to rep...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MASTER DOCUMENT LIST, ref: AVI-01550-MDL-R01 dated 15/05/2017.MASTER DOCUMENT LIST, ref: AVI-01560-MDL-R01 dated 15/05/2017.INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: AVI-01550-ICA-R00 dated03/05/2017.INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: AVI-01560-ICA-R00 dated05/05/2017or later revis...	None.	14/07/2017	Active	10062621
10062622	IMAGIK INTERNATIONALFAA REPAIR STATION, CORP.	REV. 1	FAA STC ST04365AT	737-700, 737-800	Installation of the IMAGIK QUATRO In-Seat Power Supply System (IPSS).Rev. 1: added the configuration 2 (Recaro seats P/N 3530AY62-31-() and3530AY62-32-()) and configuration 3 (USB-C connection)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs at CS25 Amendment 4:CS25.23(a), CS25.301(a)(b), CS25.303, CS25.305(a)(b), CS25.561(c),CS25.601, CS25.603(a)(b)(c), CS.25.611, CS25.613(a)(b)(c), C...	1. Master Data List (MDL) MD1002-01, Rev. N, dated 2 August2023<(>,<)>2. Instructions for Continued Airworthiness (ICA) document CA1002-01 RevG, dated 30 June 2023, for configuration 3 document CA1221M01 Rev C,dated 31 July 2023<(>,<)>or later revisions of the above listed document(s) approved/acce...	The installation of the configuration 1 of this STC is a prerequisite tothe installation of configuration 2.Applicability of configurations 2 and 3 limited to B737-800 model.Priorto installation of this design change it must be determinedthatthe interrelationship between this design change and any...	16/11/2023	Active	10062622

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062630	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A321-231	Cabin RetrofitThis change covers a Cabin Reconfiguration with Introduction of NewSeats, Monuments and IFE System Installation according to thedescription in the certification program C0018-CEP-06.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	C0018-AMM-01 Aircraft Maintenance Manual Supplementor laterrevisions of the above listed documents approved by EASA.C0018-FCO-00 Flight Crew Operating Manual SupplementC0018-CCO-00 Cabin Crew Operating Manual SupplementSee Master DocumentList (chapter 6 of the Certification ProgramC0018-CEP-06	MSN 3382Prior to installation of this design change it mustbe determined thatthe interrelationship between this designchange and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	17/07/2017	Active	10062630
10062644	DASSAULT FALCON SERVICE			FALCON 2000EX FALCON 2000	Modification DFS D220 Issue A : Baby Sofa installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List DFS-DE-17-FD-D220 Issue A dated 17 July 2017<(>,<) >or later revisions of the above listed documents approved by EASA.	Applicability is limited to FALCON 2000EX S/N 136.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produc...	18/07/2017	Active	10062644
10062655	WORLDWIDE AVIATION L.L.C.		FAA STC SA8919SW	SA227-AC/ SA227-AT/ SA227-BC	Conversion from passenger to cargo only configuration for M7 AerospaceLLC Metro series.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to Certification Drawing List AD940007, Rev. B, dated 15February 2010.To be operated iaw. Worldwide Aviation LLC AFM-S 75-231M003 Rev. A dated11 April 2011or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revision...	According to FAA SA8919SW and listed in AFM-S.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducenoadverse effect upon the airworthiness of the product.	19/07/2017	Active	10062655
10062657	SABENA TECHNICS BGC			ATR 72-212 A ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102 ATR 42-500 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	LPV/SBAS activation on ATR.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-25 Amdt 4 (Refer toAeroconseil Certification Plan, ref: 0828-01-A-CP- R03, paragraph 6 fordetailed affected requirement...	- MMEL : MMEL Suplement ref 0828-01-A-MMELS-R01;- AFM Supplement: 0828-01-A-AFMS-R02;- Instruction for Continued Airworthiness, ref: 0828-01-ICA-R02;or later revisions of the above listed documents approved by EASA.- Master Data List, ref:0828-01-A-MDL-R00.- Certification Plan, ref: 0828-01-A-CP-R0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/07/2017	Active	10062657
10062658	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A340-542	TC-CAN Relocation of Guest Area Seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Programme C0127-CEP-02.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/07/2017	Active	10062658
10062665	AIRBUS HELICOPTERS CANADA LIMITED		TCCA SH16-14 ISSUE 1	EC135 T1, EC135 T2, EC135 T3 EC135 P2+, EC135 T2+ EC135 P1, EC135 P2, EC135 P3	Installation of Removable Pins for Hinged Door in accordance with MasterDrawing List MDL-14-005.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Drawing List MDL-14-005, Issue C.- Instructions for Continued Airworthiness ICA-AHCA-295, Revision 0.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/07/2017	Active	10062665

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062689	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-106 DHC-8-102, DHC-8-103	GPS Installation on DHC-8.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-MODM00050_AFMS_MED, Airplane Flight Manual Supplement, Revision 1,05/05/2017;-MODM00050_ICA1_MED, Instructions for Continued Airworthiness, Revision2, dated 10/07/2017;-MODM00050_SB1_MED, D.O. Service Bulletin, Revision 1, dated05/05/2017;or later revisions of the above listed documents approved...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/07/2017	Active	10062689
10062690	AIR ALLIANCE GmbH			36, 36A 35, 35A	Installation of F1000 SSFDR	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI F-01 Non-Chargable LiOnBatThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original...	According to AirAlliance Master Document List No. 2016_023_LJ35_Form 2,Rev 0To be operated in accordance with AirAlliance AFM-S Document No. 2016_023_LJ35_0506, Rev 00or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No. 2016_023_LJ3...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	21/07/2017	Active	10062690
10062691	AIR ALLIANCE GmbH			35, 35A	Installation of MKVIII EGPWS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to AirAlliance Master Document List No. 2016_020_LJ35_Form 2,Rev 1To be operated in accordance with AirAlliance AFM-S Document No. 2016_020_LJ35_0506, Rev 00or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No. 2016_020_LJ3...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	21/07/2017	Active	10062691
10062694	DRB AVIATION CONSULTANTS		FAA STC ST10933SC	DORNIER 328-300	Installation of an Executive Interior and Reduction in Maximum Zero FuelWeight from 28,814 to 28,279 pounds.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. DRB Aviation Consultants Master Document List Number DL1634M00,Revision D, dated 4 February 2009, or later FAA approved revision.2. Airplane Flight Manual Supplement, Document Number FMS-HL-08-032,Revision Orig., dated 6 February 2009 or later FAA approved revision.3. Instructions for Continued A...	1. This modification is eligible to be installed on aircraft equippedwith the type certified 31 passenger cabin layout with aircraftincorporating MOD 10 Maximum Takeoff Weight (MTOW) increase only.2. Prior to installation of this design change it must be determinedthat the interrelationship betweenp...	25/07/2017	Active	10062694
10062700	AERO TWIN, Inc.		FAA STC SA02126AK-D	208B 208	Fabrication and Installation of Aero Twin, Inc. Brake Disk Spacer KitNo. BS8-100.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aero Twin, Inc. Master Data List No. BS8-100 dated 4 September 1998, orlater FAA/DAS approved revision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Applicable only to airplanes equipped with...	24/07/2017	Active	10062700

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062705	STG AEROSPACE GERMANY GmbH	REV. 1		757-200, 757-300 737-900ER 737-800, 737-900, 737-900ER 737-800, 737-900 737-600, 737-700	LITEMOOD® LED READING LIGHT UPGRADERevision 1: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 at Amendment 18CS 25.1, CS 25.25, CS 25.27, CS 25.301 (a),(c), CS 25.303, CS 25.305 (a),(b),(c), CS 25.307 (a), (d), C...	- MASTER DATA LIST, Doc No: SG-1015-MDL-01, Rev No. IR- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, Doc No: SG-1015-ICA-01, RevNo. IR- SERVICE BULLETIN, Doc No: SG-1015-SB-01, Rev No. IRor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/02/2021	Active	10062705
10062707	BELL HELICOPTER TEXTRON, Inc.		FAA STC SH3261SO	AB412, AB412EP 212, 412, 412EP	Installation of replacement skid tubes.This Certificate is based on "grandfathered" approvals LBA RC1084, UKCAA 26707 and 26708.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeronautical Accessories, Inc. Drawing List, Report No. AA-97002,Revision B, dated 12 June 1992 or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/08/2017	Active	10062707
10062708	BELL HELICOPTER TEXTRON, Inc.		FAA STC SH3712SW	412EP, 214B 204B, 205A-1, 212, 412	Installation of replacement windshield 22HP464 or manufacture ofwindshield.This Certificate includes the "grandfathered" approval LBA 0253/3039.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Replacement of Windshield per Aeronautical Accessories, Inc. DrawingList Report No. AA-92023, no revision, dated 20 February 1998.2. Manufacture of Windshield Aeronautical Accessories, Inc. Drawing ListReport No. AA-92023, no revision, dated 20 February 1998.3. Installations per Report No. AA-920...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/08/2017	Active	10062708
10062709	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR00040AT	212, 412, 412EP	Installation of avionics rainshield.This Certificate is based on the "grandfathered" approvals ENAC99/255/ MAE, UK CAA 26707 and 26708.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeronautical Accessories, Inc. Drawing list, Report No. AA-92062, Rev.D, dated 21 November 2001, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/08/2017	Active	10062709
10062710	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR00446AT	205A-1, 212, 412, 412EP	Manufacture of Flitestep.This Certificate is based on the "grandfathered" approvals LBA RC1134,ENAC 98/5476/ MAE.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeronautical Accessories, Inc. Drawing List Report No. AA-93085, norevision, dated 4 November 1993, and installation per Report No.AA-93086, Revision A, dated 21 February 1994, orReport No. AA-97087, norevision, dated 21 May 1997, or later FAA approved revision.	1. Inspection and Maintenance requirements are listed in AeronauticalAccessories, Inc. Report AA-98049, no revision, dated 23 December 1998,or later FAA accepted revisions.2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and an...	17/08/2017	Active	10062710
10062713	AIRBORNE TECHNOLOGIES GmbH			P.68C	Title: STC-AT-113, Survey Cabin ConfigurationDescription: Installation of a flight guidance display in the cockpit,somecomputing devices, a laser scanner (Class 3B Laser) above theVulcanair Photogrammetric hatch, an operator desk with itsmissionequipment (displays, etc.), a Connector Box, a laserr...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraphs of CS 23, Amendment 3:CS 23.29, CS 23.301, CS 23.303, CS 23.305, CS 23.307, CS 23.337, CS23.561, CS 23.601, CS 23.603, CS 23.605, CS 23.607, CS 23...	-Supplement to the AFM, Doc. No. STC-113-0-AFM, Rev. 1or later revisions of the above listed documents approved by EASA.- Applicable Documents, (List of Compliance documents and manuals), Doc.No. STC-AT-113, Rev. 6-Supplement to the AMM, Doc. No. STC-113-0-AMM, Rev. 1-Installation Instructions, Doc....	Limited to S/N 499Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	24/07/2017	Active	10062713

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062719	LB AIRCRAFT ENGINEERING LLC	REV. 2	FAA STC ST04368AT	737-8/-9 737-600/-700/-800/-900	Installation of a Rockwell Collins CMU-900 ACARS/CPDLC CommunicationManagement Unit P/N 822-1239-151 to provide Data Link communications viaexisting data link capable VHF Mode 2 (VDLM2), HF and/ or SATCOM systemsand host the CPDLC application which support EASA Link 2000+communications.Rev. 1 MMEL Su...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- For 737-600/-700/-800/-900:LB Aircraft Engineering MasterData List LB-CMU. 737-MDL, Rev. E dated 18April 2017<(>,<)>-For 737-8 and 737-9:LB Aircraft Engineering MDL document B38M-MDL-0169, Rev IR, dated 10December 2024,- For 737-600/-700/-800/-900:Flight Manual Supplement, LB Aircraft Engineering...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	14/03/2025	Active	10062719
10062742	STG AEROSPACE GERMANY GmbH	REV. 1		CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700,701,702) CL-600-2B19 (RJ SERIES 100)	saf-Tglo® PHOTOLUMINESCENT AISLE PATH MARKING SYSTEM BOMBARDIER CL-600(CRJ) SERIES AIRCRAFT.Revision 1: Transfer of STCholder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25 AMENDMENT 18-Requirements: 25.1(a) -25.25 (a)(b); 25.27; 25.301; 25.303; 25.305;25.307; 25.561(a)(b)(c); 25.581; 25.60...	STG AEROSPACE LTD AEROPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1004-FMS-01Revision IR;STG AEROSPACE LTD INSTRUCTIONS FOR CONTINUED AIRWORTHINESS No.SG-1004-ICA-01 Revision IR;STG AEROSPACE LTD CABIN CREW DATA SUPPLEMENT No. SG-1004-CCD-01 RevisionIR STG AEROSPACE LTD MASTER MINIMUM EQUIPMENT LIST SUPPL...	SSUL Green Emitting Photoluminescent insert shall not be mixed with SSULBlue Emitting Photoluminescent insert on the same aircraft installation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed cha...	12/02/2021	Active	10062742
10062749	AEROTEC & CONCEPT	REV. 1		A321-253N/-271N/-272N A321-213/-231/-232/-251N A321-111/-112/-131/-211/-212 A320-271N A320-231/-232/-233/-251N A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	MOD AE17026 : KU Band Antenna Internal Mechanical ProvisionsInstallation.Revision 1: add 7 external reinforcement doublers to increase fatigueand damage tolerance figures.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List Ref. AE17026MDL Revision 5 dated 25.05.2018;- Instructions for Continued Airworthiness Ref. AE17026ICA Revision 6dated 25.05.2018;or later revisions of the above listed documents approved by EASA.	None	25/05/2018	Active	10062749
10062757	LEARJET Inc.	REV. 1	FAA ST04060CH	CL-600-2B16 (604 VARIANT)	EASA Validation of FAA ST04060CH.Certification of the aircraft data link system used for communicationsupporting Air Traffic Services (ATS) and installation of the TrueNorthor International Communications Group Iridium Satcom and RockwellCollins CMU-1000 Communications Management Unit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): EASA Special Condition F-01-10050843 “FlightRecorders and Data Link Recording” at Issue 2.- The following paragraph(s) at a later amendment:For STC...	- Supplemental Type Certificate modification to be performed inaccordance with in accordance with Master Data List 34-334G002 Rev N,dated December 20th, 2017, or later approved revision.- The following documents are required for MDL 34-334G002-001configuration of this STC: Instructions for Continued...	1. Supplemental Type Certificate FAA ST01433WI-D which is validatedthrough EASA STC 10016518 (previously EASA.IM.A.S.02889) or BombardierService Bulletin 604-34-057 Revision 3 is a prerequisite for this STC tomodify the Global Positioning System (GPS).2. Supplemental Type Certificate FAA ST01505WI-D...	20/07/2018	Active	10062757
10062773	IPR CONVERSIONS (SWITZERLAND) LTD	REV. 1		ATR 72-212	Stand Alone Large Cargo Door (LCD) Transfer of EASA STC 10062773 from Alenia North America - Canada to IPRConversions Switzerland	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-AFM Supplement “ATR72 Stand Alone LCD” Issue 1 dated Nov. 2011-MPD Supplement “ATR72 Stand Alone LCD” Appendix A Time Limits(Airworthiness Limitations) dated Dec. 2011or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2018	Active	10062773

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062778	ROCKWELL COLLINS, Inc.		FAA STC ST01805WI	SEE FAA AML	Modification of Rockwell Collins TCAS II System Installation with DCpowered TCAS Transmitter Receiver Processor	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	(1) FAA Approved Model List (AML) RCA-0585, Revision (-), dated 23 March2017;(2) Instructions for Continued Airworthiness RCA-9715, Revision (-),dated 17 March 2017;(3) Airplane Flight Manual Supplement RCA-9714, Revision (-), dated 22March 2017or later FAA approved revisions for items (1), (2) and...	(1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.(2) Equipment specific limitations are docum...	31/07/2017	Active	10062778
10062785	MECAER AVIATION GROUP S.p.A.	REV. 2		AW139, AB139 AW139 AB139	AW139 Restyling VIP Interiors P/N 6A3W0000X001001Rev.1 of the STC introduces the existing cabin configuration approved byEASA under STC 10062785 by introducing three new differentcabin lay-outconfigurations featurings electrochromic window installation with newwindows gasket type as well as new fin...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 29 Amdt. 2, forrelevant paragraphs as listed in the Compliance Check List Report6A3W0000N306 quoted below.The requireme...	Rotorcraft Flight Manual Supplement 6A3WRFM-1-1 Issue 2, Revision 12Design Data Set DDS-2022-024 Issue YOwner's Manual 6A3WWNM-2-1 Issue 0 Revision 11Certification Programme Report 6A3W0000N215 Revision C.Configuration Description and Compliance Check List Report 6A3W000N306Revision BOr later revisi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/07/2025	Active	10062785
10062804	ROCKWELL COLLINS, Inc.		FAA STC SA01306WI-D	SEE FAA APPROVED MODEL LIST	Modification of a Collins ALT-50A or ALT-55B Radio Altimeter systeminstallation to a Collins ALT-1000 or ALT-4000 RadioAltimeter systeminstallation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Collins Drawing Index as listed on AML No. SA01306WI-D, Revision-, orlater FAA approved revision.	1. Prior FAA approved installation of a Collins ALT-50A part numbers622-3201-001/-002/-011 or ALT-55B part numbers 622-2855-001/-002/-011/-012 is a prerequisite to this STC.2. Foraircraft installations utilizing two radio altimeters, bothradioaltimeters must be replaced; Intermixing of new radio a...	16/08/2017	Active	10062804
10062813 (EASA.A.S.00625)	AERODISA S.L.	REV. 4		ATR 72-212, ATR 72-212 A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR42 AND ATR72 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Conversion to freighter configuration. Conversion from passenger to allcargo configuration (Class E cargo compartment)Rev. 2: Update of the Supplement to AFM - Update of the Supplement toMMEL and Adding option to remove the electronic cockpit door lockingsystem.Rev. 3: Compliance with regulations 26...	The EASA Certification Basis for the original product as amended by thefollowing additional alternative airworthiness requirements:- The following paragraph(s) at a later amendment:25.1, 25.23, 25.25, 25.27, 25.29, 25.301, 25.303, 25.305, 25.307,25.371, 25.471, 25.477, 25.479, 25.489, 25.491, 25.493...	For ATR 72:Master Data List AED_01_2003_00 ED3/Rev.0 dated 03/02/2023Supplement to MPD AED_01_2003_11-1A ED5/Rev.0 dated 29/08/2022Supplement to MPD AED_01_2003_11-1B ED5/Rev.0 dated 29/08/2022For ATR 42:Master Data List AED_01_2003-ANNEX ED3/Rev.0 dated 03/02/2023Supplement to MPD AED_01_2003_11-1F...	Supplement to AFM AED_01_2003_07Supplements to MPD AED_01_2003_11-1() Limited to aircraft pre ATR MOD 5948 (Glass Cockpit).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wil...	16/02/2023	Active	10062813
10062814	RESURGENT AVIATION SOLUTIONS, LLC		SA04166CH-A	EA500	Removal of icephobic coating from the area surrounding static parts onEA500 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	RAS Implementation Instructions document number E50-I-16-001, Rev. 0,dated 26 July 2016, or later FAA approved revisions.	1. Installation of this approval does not alter the EA500 certificationfor flight into known icing.2. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce n...	03/08/2017	Active	10062814

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062815	AIRBUS HELICOPTERS, Inc.		FAA STC SR09109RC-D	EC 120 B	Installation of a collective activated hourmeter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing List 120A82-8002, Revision A, dated 21 December 1998 or laterFAA approved revisions.2. Instructions for Continued Airworthiness 120MMS-003 dated 10 December1998 or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/08/2017	Active	10062815
10062832	DASSAULT FALCON SERVICE	REV. 1		FALCON 2000, FALCON 2000EX	FANS 1/A - OCL enable switches installation in cockpitRevision 1: applicability extension to Falcon 2000 and F2000EX withoutM1691 nor ProLine 21.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.1302 at amdt. 19.The requirements for environmental protection and the associatedcertified noise and/ or emissions l...	- Master Document List DFS-DE-17-FD-D229 issue C- AFMS DFS F2000-012 dated 03 June 2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Installation of Iridium Satcom FANS 1/A-capable and Inmarsat L BandSatcom are pre-requisite for this design change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intro...	24/07/2019	Active	10062832
10062834	SABENA TECHNICS BGC	REV. 1		737-600/-700/-800/-900/-900ER	USB charging plug into cockpit.Installation in cockpit, on both Captain and F/O sides, of one 28/5VDCconverter dual USBcharging plugs into cockpit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS-25 Amdt 4 (Refer to Aeroconseil Certification Plan, ref:0675-03-A-CP- R03, paragraph 5 for detailed affected requirem...	AFM Supplement, ref: 0675-03-AFMS-R00.Instruction for Continued Airworthiness, ref: 0675-03-ICA-R00.or later revisions of the above listed documents approved by EASA.Master Data List, ref: 0675-03-A-MDL-R01.Certification Plan, ref: 0675-03-A-CP-R03.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/08/2017	Active	10062834
10062838	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T3	Infrared Flood Lamp.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement AHUK/135-FMS-108 Rev. 0or later revisions of the above listed documents approved by EASA.Design Compliance Record DCR/ 1353105-01 Issue B.Master Drawing AHUK/ 135/3105-101-01 Issue A.Supplemental Aircraft MaintenanceManual SAMM-135-MFTS-00 (ATA 33-45),Rev 0.	Limited to Helionix cockpit variant.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	07/08/2017	Active	10062838
10062841	OUTERLINK CORPORATION		FAA STC SR00368BO	EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of an Outerlink SATCOM Communications and Flight DataMonitoring System KIT 135-SAT-100.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS27.610 at Amdt. 4The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	1. Outerlink Corporation's Master Data Drawing Lists (MDL),Documentnumber MDL 135-SAT-100, Revision IR, dated 18 February 2016, or laterFAA approved revisions of these documents.2. Operation must be in accordance with Outerlink Corporation'sRotorcraft Flight Manual Supplement (RFMS) Document Numbe...	1. The RFMS must be carried in the aircraft during all flights.2. The ICA must be made available to the operator at thetime ofinstallation.3. This system does not meet the operational rule requirement of a voiceor flight data recorder system.4. Prior to installation of this design change it must be...	16/10/2017	Active	10062841
10062842	OUTERLINK CORPORATION		FAA STC SR00374BO	MBB-BK117 C-2	Installation of a Satcom and Flight Data Monitoring System KIT145-SAT-100.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS29.610 at Amdt. 4The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	1. Outerlink Corporation's Master Drawing List Document Number MDL145-SAT-100, Revision A, dated 24 October 2016, or later FAA approvedrevision.2. Operation must be in accordance with Outerlink Corporation'sRotorcraft Flight Manual Supplement (RFMS) Document Number FMS145SAT001,Revision IR, dated 27...	1. The RFMS must be carried in the aircraft during all flights.2. The ICA must be made available to the operator at thetime ofinstallation.3. Prior to installation of this designchange it must be determinedthat the interrelationship between this design change and any otherpreviously installed desi...	16/10/2017	Active	10062842

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062857	OUTERLINK CORPORATION		FAA STC SR00362BO	S-92A	Installation of a Satcom Communications and Flight Data MonitoringSystem KIT S92-SAT-100 on Sikorsky Aircraft Corporation S-92AHelicopters	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Outerlink Corporation's Master Drawing List (MDL), Document numberMDLS92-SAT-100, Rev. B, dated 2 November 2015, or later FAA approvedrevision.2. Operation must be in accordance with Outerlink Corporation'sRotorcraft Flight Manual Supplement (RFMS) Document numberFMS92-SAT-001, Rev. A, dated 17 D...	1. The RFMS must be carried in the aircraft during all flights.2. The ICA must be made available to the operator at thetime ofinstallation.3. This system does not meet the operational rule requirement of a voiceor flight data recorder system.4. Prior to installation of this design change it must be...	11/08/2017	Active	10062857
10062858	IPR CONVERSIONS (SWITZERLAND) AG	REV. 1		ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 42-300, ATR 42-320	Installation of an auxiliary battery on ATR 42/72.Reason for Revision: Transfer of STC 10062858 from ASI INNOVATION to IPRCONVERSIONS (SWITZERLAND) AG.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.301, CS 25.303,CS 25.305, CS 25.307, CS 25-321, CS 25.337, CS 25.341, CS 25.471, CS25.571, CS 25.601, CS 25.603, CS2...	Master Drawing List ASI-MDL-0463-02 Rev.02 dtd. 02.08.2017;AFM Supplement AFM-0463 Rev. 01 dtd. 30.06.2017;Maintenance Planning Supplement ASI-MPS-0463-02 Issue 02 dtd. 01.08.2017;or later revisions of the above listed documents approved byEASA.	Per AFM Supplement AFM-0463.Limited to ATR 42 / 72 aircraftwith BFC & LCD STC installed (EASA STC10043128, 10043003, 10043005).Prior to installation of this design change it mustbe determined thatthe interrelationship between this designchange and any otherpreviously installed design change and/a...	16/11/2017	Active	10062858
10062861	AEROTEC & CONCEPT			A321-251N/-253N/-271N A321-231/-232 A321-211/-211/-213 A321-111/-112/-131 A320-251N/-271N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	MOD AE17111 - A319-A320-A321 Generic WIFE Systems Activation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List : AE17111MDL Rev 0 dated 04/08/2017- Aircraft Flight Manual Supplement: AE17111AFMS Rev 0 dated 06/08/2017- Instructions For Continued Airworthiness: AE17111ICARev 0 dated06/08/2017or later revisions of the above listeddocuments approved by EASA.	Modification AE17146 is prerequisite for this STCPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product...	11/08/2017	Active	10062861
10062869	ROCKWELL COLLINS, Inc.	REV. 2	FAA STC ST01305WI-D	SEE FAA AML	Modification of a Collins ALT-50A or ALT-55B Radio Altimeter systeminstallation to a Collins ALT-1000 or ALT-4000 RadioAltimeter systeminstallationRev. 1: implementation of modified Collins ALT-1000 or -4000 radioaltimeters design (new P/N) to allow unrestricted operations inenvironment with 5G C-B...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Collins Drawing Index as listed on AML No. ST01305WI-D RCA-0728,Revision -, dated 8 December 2023< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	1. Previously EASA approved installation of Rockwell Collins radioaltimeter(s) ALT-50A, ALT-55B, ALT-1000 or ALT-4000, is a prerequisiteto this STC (see Installation Instructions document RCA-2190 forapplicable part numbers).2. The radio altimeter part numbers must be installed as a ship-set;intermi...	04/12/2024	Active	10062869
10062870	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST04203CH	757-200	EASA validation of FAA STC ST04203CH. Installation of a Zodiac RAVEIn-Flight Entertainment System in accordance with StandardAero MasterData List, Doc. No. DC104-9752C-00, Revision (B) dated 30th May 2017 orlater approved revisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The STC installation must be performed in accordance with StandardAeroMaster Data List, Doc. No. DC104-9752C-00, Revision (B) dated 30th May2017, andThe Airplane Flight Manual Supplement document number DC303-9752C-00,Rev (A) dated 26th May 2017 is a required part of this modification, andThe aircra...	1) See those of original FAA STC ST04203CH and those of theAirplaneFlight Manual Supplement and other documents listedabove underassociated technical documentation.2) Aircraft modification in accordance with this STC requires prior orconcurrent embodiment of FAA STC ST04153CH, Certification ofComp...	14/08/2017	Active	10062870

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062872	GARMIN INTERNATIONAL, Inc.	REV. 9	FAA STC SA01844WI	SEE FAA APPROVED MODEL LIST SEE FAA AML	Installation of Garmin GFC 600 Automatic Flight Control System.Rev. 7 amends the FAA Approved Model List with PA-31-350and add theMMEL for King Air 200 series.Rev. 8 adds TextronAviation Inc. F90 to the AML.Rev. 9 adds in the Approved Model List:Piper PA-31T (Cheyenne I/II);Textron Aviation Inc. 5...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS MMEL is.3; CS FCDis.2; the additional requirements indicated on FAA STC SA01844WI, asamended on date 15thT...	- Garmin Master Drawing List (MDL) 005-01009-01, Revision 1, dated 14July 2017;- Garmin GFC 600 Automatic Flight Control System Part 23 AML STCMaintenance Manual (includes Instructions for Continued Airworthiness) 190-01938-00, Revision 1, dated 14 July 2017;- EASA MMEL report 190-01937-36_MMEL rev. 1...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	09/10/2025	Active	10062872
10062878	ADAC LUFTFAHRT TECHNIK GmbH			MBB-BK 117 D-2	Installation of a Spectrolab SX-7 Searchlight onto the multifunctionstep of an MBB-BK 117 D-2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement, H145-04109-025-MFS-00,Rev. 0or later revisions of the above listed documents approved by EASA.-Master Document List, H145-04109-001-LMD-00, Rev. 0, dated 22/06/2017-Instructions for Continuing Airworthiness, H145-04109-023-MMS-00, Rev.0, dated 19/06/2017	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/08/2017	Active	10062878
10062883	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04036AT-D	GIV	Installation of FANS -1/A+ functionalityThis modification is installing a Future Air Navigation System(FANS)-1/ A+, including the ATS Facilities Notification (AFN),Controller-PilotData Link Communication (CPDLC), and AutomaticDependent Surveillance (ADS-C) coupled with Data Link capability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Index List, ref : CE41 4068001 revision B, dated 28 March2016- Aircraft Flight Manual, ref : CE41 406M001, dated 28 March 2016- Instruction for Continued Airworthiness, ref : CE41 406A001 RevisionA, dated 11 January 2016or later revisions of the above listed documents approved by EASA inaccordanc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/08/2017	Active	10062883
10062885	ELDEC LLC		FAA STC ST02534SE	ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 SR ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ	Installation and maintenance of a Crane Aerospace & Electronics TirePressure Sensor Assembly.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Crane Aerospace Installation Manual and Instructions forContinuedAirworthiness (ICA) IM83-022-01_EMBRAER, Revision -, dated 7 April 2017,or later Federal Aviation Administration (FAA) approved revision.2. Configuration is defined by Configuration Control ListCCL83-022-01_EMBRAER, Revision -, dat...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/08/2017	Active	10062885
10062886	DOA21 LIMITED	REV. 1		A319-115	Introduction of VIP Cabin ReconfigurationRev. 1: Transfer of STC holder role to DOA21 Ltd.	The Certification Basis The Type and OSD Certification Bases for theoriginal product as amended by the following additional or alternativeairworthiness requirements:Special Condition (s):D-1 Medical EvacuationD-2 Isolated CompartmentsF-02 Security Protection of Aircraft Systems and NetworksDeviation (...	- STC TWENTY ONE FLIGHT MANUAL SUPPLEMENT No. S21.FMS-0148 ISSUE 1or later revisions of the above listed documents approved by EASA.- STC TWENTY ONE MASTER DOCUMENT LIST No. S21.MDL-1361 ISSUE 1	Restricted to ASN 1485.Any changes to the WLAN or interior layout approved under this designchange will require a re-examination to determine if the compliancedemonstration and/ orthe certification basis are still valid.Airworthiness approval of the Airborne Wireless Local Area Network(WLAN) does no...	24/10/2023	Active	10062886

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062887	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T3	Installation of Multi-Sensor Turret and Recorder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the original product are unchanged and remain applicable to thiscertificate/ approval.	- Flight Manual Supplement AHUK/135-FMS-105, Issue 9or later revisions of the above listed documents approved by EASA.- Design Compliance Report DCR/1353088-01 Issue B, dated 8th August2017- Airworthiness Certification Plan ACP/1353088-01 Issue C, dated 9thAugust 2017- Instructions for Continued...	Limited to helicopter with Helionix cockpit variant.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the prod...	15/08/2017	Active	10062887
10062888	AVIANOR INC		TCCA O-LSA17-073/D	A330-343	Reconfigure forward cabin<(>,<)> install seats and approve new layout ofpassenger accommodation (LOPA).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AVIANOR MASTER DOCUMENT LISTS MDL16182001 REV. NC and MDL16182701 Rev.NC.	Restricted to MSN 1098.Aeroconseil minor modification no. MOD 4996-03-A and 365 Aerospace minormodification no. MOD-0305 are prerequisites for this STC.	15/08/2017	Active	10062888
10062890	AMAC AEROSPACE SWITZERLAND AG			A340-642	Cabin Reconfiguration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for:- Equivalent Safety Finding(s): CRI D-08 Side facing Seats.- The following paragraph(s) at a later amendment: 25.603, 25.788,25.1447, Appendix S at CS-25 Amdt 19.The r...	Master Data List MDL-FK03-2500 Rev. B dated 15-Aug-2017.Airplane Flight Manual Supplement AFMS-FK03-2500 Rev. A dated08-Aug-2017.Instructions for Continued Airworthiness ICA-FK03-2500 Rev. A dated28-Jul-2017or later revisions of the above listed documents approved by EASA.	Per Airplane Flight Manual Supplement AFMS-FK03-2500.EASA STC 10042295 Rev 2 “‘Eminence” VIP cabin interior completion’is aprerequisite installation.Prior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously install...	15/08/2017	Active	10062890
10062891	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH			EC635 T3 EC635 P3, EC635 T1, EC635 T2+ EC135 T2+, EC135 T3, EC635 P2+ EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of Tactical Copilot Display	The Certification Basis (CB) of the EC135/635 P3(CPDS)/T3(CPDS) isapplied to all models listed on this certificate. Refer to TCDSEASA.R.009, Issue 11, or later revision.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product ar...	Flight Manual Supplement “Installation of Tactical Copilot Display” forAirbus Helicopters EC135,Doc.-ID 00030-DO-MZ-FMS-00, Issue 2or later revisions of the above listed documentsapproved by EASA.List of Compliance Documents “Installationof Tactical Copilot Display”,Doc.-ID 00030-DO-MZ-LCD-00, Iss...	Not applicable to EC135/EC635 models with Helionix cockpitinstrumentation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the air...	16/08/2017	Active	10062891
10062892	AIRBUS S.A.S.	REV. 1		A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	MOD CJ2087 INSTAL OF A330 2KU ANTENNARevision 1 of the STC 10062892 introduces additional pre-modificationconfigurationcondition for installation of a GoGo 2KU antenna on anaeroplane that requires relocation of Emergency Locator Transmitter(ELT) antenna(s) in accordance with Airbus major modificati...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-4301-003 - Vibration and buffetingon Large AntennaThe requirements for environmental protection and the associatedcertified noise and/u...	Certification Summary Reports ref. ACJC-AJA-16063 Issue 2 (Initial) &AIS-AJA-18076 Issue 4 (Major Change)Modification Approval Sheet ref. MAS CJ2087 Issue 5Maintenance Planning Document ref. MPD-S A330 MOD CJ2087 Revision 03or later revisions of the above listed document(s) approved/ acceptedunder th...	Modification of an aeroplane in accordance with the Revision 1 of STC10062892 is allowed, provided that prior to GoGo antenna installationthe aeroplane is modified in accordance with Airbus SB A330-25-3702(Airbus MOD 207958), or Airbus SB A330-25-3703 (Airbus MOD 207959), asapplicable to aeroplane m...	22/01/2019	Active	10062892

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062897	ALAMO ENGINEERING GmbH	REV. 3		GULFSTREAM 200/ GALAXY	ADS-B OUT on RC Pro Line 4 (G-200).Revision 1: Transfer to 328 Support Services GmbHRevision 3: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): CRI F-01, Continuity Requirements for ADS-B function.- The following paragraph(s) at a later amendment: CS-ACNS, InitialIssue: CS ACNS.D.ADSB. 001, CS ACNS...	- Master Document List (MDL), Document No. MDL113Z001, Rev.A;- AFM Supplement, Document No. AFMS016C345Z0001, Rev. B;-MMEL Supplement, Document No. MMELS016C345Z0001, Rev. A;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system	Limited to S/N 062 and up.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10062897
10062928	AMAC AEROSPACE SWITZERLAND AG			A340-643 A340-642	Tailwind 550 SAT TV antenna installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Equivalent SafetyFinding (s):CRI B-01 Vibration / Buffeting compliance criteria for large externalantenna installationThe requirements for environmental protection and the associatedcertified noiseu...	- Master Data List MDL-A3402-1-5300 Rev. B dtd. 17.08.2017-Airplane Flight Manual Supplement AFMS-A3402-1-5300 Rev. A dtd. 08.08.2017- Instructions for Continued Airworthiness ICA-A3402-1-5300 Rev. C dtd.17.08.2017or later revisions of theabove listed documents approved by EASA.	Per:- Airplane Flight Manual Supplement AFMS-A3402-1-5300- Instructions for Continued Airworthiness ICA-A3402-1-5300Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair wi...	17/08/2017	Active	10062928
10062930	STRAERO S.A. (INSTITUTE FOR TESTING AND CALCULATOF STRUCTURES AERO-ASTRONAUTICS)	REV. 4		BN2A-27	Installation of surveillance and atmospheric measurement equipment incl.cabin refreshment as defined in STRAERO MDL_STR001003, Rev. O, dated 10August 2017.Revision 1:Installation of surveillance and atmospheric measurement equipment incl.cabin refreshment as defined in STRAERO MDL_STR001003, Rev. O,...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23 Amdt.4 23.1,23.29, 23.251, 23.301, 23.303, 23.305, 23.307, 23.321, 23.471, 23.473,23.561, 23.574, 23....	Master Data List MDL_STR001003 Revision 6, dated 01.09.2023Aircraft Flight Manual Supplement AFMS_STR001003, Revision 3, dated10.10.2022Instructions for Continued Airworthiness ICA_STR001003, Revision 3,dated 10.10.2022or later revisions of the above listed document(s) approved/ acceptedunder the EAS...	This STC is limited to BN2A-27, S/N 804, 808 and 824.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	21/09/2023	Active	10062930
10062934	SABENA TECHNICS BOD	REV. 7		A350-941	Seats and floor covering installationThis modification consists in a 411 economy/ premium economy seatsinstallation, including the seat power system and in-FlightEntertainment system connections, and the installations of the textilefloor, seat track, cover, cabin placards, and floor pathmarking. Doo...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Data List, ref: MDL-S-25-4102 issue K, dated 12th October 2022.- Instruction for Continued Airworthiness, ref:ICA-V000I-25-009 IssueE, dated 5th October 2022.- Weight and Balance Manuel Supplement, ref: WBMS-V000I-25-039 Issue A,dated August 2017.- Spare Parts Mechanical Installation, ref:...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/10/2022	Active	10062934
10062949	GOODRICH LIGHTING SYSTEMS GmbH& Co. KG	REV. 2		A321-271NX/-272NX A321-271N/-272N A321-251NX/-252NX/-253 NX A321-251N/-252N/-253N A321-231/-232 A321-213/-231/-232 A321-211/212/-213 A321-111/-112/-131/-211/-212 A321-111/-112/-131/ A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of LED Navigation LightRev. 1: updates the ICAand the installation documentation withadditional existing wing navigation light P/Ns which can be substitutedas part of the STC.Rev. 2: Minor Update of Build Standard of LED WingNavigation Lightbased on editorial changes. Revision of Tech...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): H-01 - ICA on EWISThe following paragraph(s) at a later amendment:CS-25, Amdt. 4: 25.1, 25.29, 25.1301, 25.1309, 25.1351, 25.1353,25.135...	Modification Summary Sheet and Declaration of Compliance for DesignChanges<(>,<)> MSS-456500-01-02, Rev. 03Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This modification is not applicable to A/C which have been previouslymodified with the Airbus Sharklet Modification (A319/A320: MOD 160500;A321: MOD 160023).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	15/03/2024	Active	10062949

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10062960	ALPINE AEROTECH LP	REV. 1	TCCA STC SH00-2	212/ 412/ 412EP	Firewall Web Installation (Alpine Aerotech Ltd. P/ N AAL-061-903-001).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions Document No. 191M-99-003-II, Revision NC,dated November 17, 1998, or later TCCA approved revisions.Master Drawing List Document No. D191M-99-003, Rev. NI, dated February22, 1999, or later TCCA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/09/2017	Active	10062960
10062985	FOKKER SERVICES B.V.			DHC-8-401/ DHC-8-402	ADS-B out on the Dash 8-400 series.Installation of the NXT 700 instead of the MST-67A Transponder.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for:Deviation(s):CRI F-01 Continuity Requirements for ELS and ADS-B function.The following paragraph(s) at a later amendment:Initial issue of CS ACNS.D.AC.001; CS ACNS.D.A...	DHC8-FXI-AFM-S-003, Airplane Flight Manual Supplement, Revision 1 dated19-01-2017.DHC8-FXI-AMM-S-006, Supplement Aircraft Maintenance Manual, originalissue dated Aug 02/17.DHC8-FXI-IPC-S-006, Supplement Illustrated Parts Catalog, original issuedated Apr 08/17.DHC8-FXI-WDM-S-006, Supplemental Wiring0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/08/2017	Active	10062985
10062996	AIRBUS S.A.S.			A330-243	MOD CJ2083 : Installation of Zodiac KA BAND Antenna on A330.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI B-4301-003 - Vibration and buffeting on Large Antenna.The requirements for environmental protection and the associatedcertified noise and/...	Certification Summary Report ref: ACJC-AJA-16034 issue 5.Modification Approval Sheet: MAS CJ2083 issue 1.ICA: MPD-S MODCJ2083 issue Aug 01/17.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/08/2017	Active	10062996
10063006	AIRCRAFT DEVELOPMENT AND SYSTEMSENGINEERING (ADSE) B.V.			737-700	Certification of the Boeing 737-700 as PED tolerant.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS 25 at Amdt. 19: CS 25.1309(a)(1), CS 25.1353(a), CS 25.1431(a), CS25.1529.The requirements for environmental protect...	Design Definition List, Doc. Nr. 17-DO-022, Issue 1.0.AFM Supplement PED Tolerance B737-700, Doc. Nr. 17-DO-025, Rev. 0.2or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/08/2017	Active	10063006
10063008	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC SA03293NY	737-600/-700/-800/-900/-900ER	Upgrade of existing cabin lighting to the STC Aerospace liTeMood® LEDCabin Lighting system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:the following paragraph(s) at a later amendment:CS 25.1353 at CS25 amendment 1.The requirements for environmental protec...	Master Data List LM737-MDL-01 rev B dated July 29th 2015.Configuration Matrix LM737-CM-01 rev A dated July 21st 2015or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Impleme...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/08/2017	Active	10063008
10063015	ALPINE AEROTECH LP	REV. 1	TCCA STC SH05-36	212/ 412/ 412EP	Cowling Baffle Screen Installation in accordance with Master DocumentList (MDL) AAL-232-024-001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List (MDL) Document No. AAL-232-024-001 Revision NI,dated May 27, 2005, or later TCCA approved revision.Cowling Baffle Screen Installation Instructions Document No.AAL-232-025-001, Revision NI, dated May 27, 2005, or later TCCA approvedrevision.Cowling Baffle Screen Maintenance Manua...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/09/2017	Active	10063015

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063016	JET AVIATION AG			MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX) 550/ 560/ 560XL	Display Unit replacement by DU-875.Removed: 1 or up to 5 EFIS and EID CRT Display Units Honeywell DU-870.Installed: 1 or up to 5 EFIS and EID LCD Display UnitsHoneywell/ Esterline DU-875.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:Voluntary Compliance to CS 25, change 18 was shown, in particular:CS25.771, CS25.869, CS25.899, CS25.1301, CS25.1302, CS...	Approved Model List: Doc. No. JBSL-M-00831 AML-01, Issue 01.Instructions for continued airworthiness: Doc. No. JBSL-M-00831 ICA-01,Issue 01or later revisions of the above listed documents approved by EASA.Master Document List: Doc. No. JBSL-M-00831 MDL-01, Issue 02.Declaration of Compliance: Doc. No...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/08/2017	Active	10063016
10063017	ALPINE AEROTECH LP		TCCA STC SH05-30	212/ 412/ 412EP	Oil Cooler Support Bracket, Kit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:FAR 29 up to Amendment 29-47: 29.1, 29.303, 29.305, 29.307,29.601,29.603, 29.605, 29.607, 29.609, 29.613, 29.1121(b), 2...	TCCA Airworthiness Limitations section of Oil cooler support bracket,kit, Maintenance Manual Supplement Document No. AAL-214-015-101, Rev. Bdated October 27, 2011,,or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ Canad...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/09/2017	Active	10063017
10063018	ALPINE AEROTECH LP		TCCA STC SH05-31	212/ 412/ 412EP	Induction Baffle Screen Installation in accordance with Master DocumentList (MDL) No. AAL-253-024-001.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:FAR 29 up to Amendment 29-47: 29.1, 29.601, 29.603, 29.605,29.607,29.609, 29.613, 29.901, 29.1091, 29.1529, Appendix AT...	Master Document List (MDL) Document No. AAL-253-024-001, Rev. NI, datedMay 13, 2005, or later TCCA approved revisions.Installation Instructions Document No. AAL-253-025-001, Rev. NI, datedMay 13, 2005, or later TCCA approved revisions.Maintenance Manual Supplement Document No. AAL-253-025-101, Rev.d...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/09/2017	Active	10063018
10063031	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH	REV. 3		EC635 T3 EC635 P3, EC635 T1, EC635 T2+ EC135 T2+, EC135 T3, EC635 P2+ EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Title: Installation of EuroNav 7 on EC135 helicopters.Description:This modification installs a EuroNav 7 Digital MovingMap System inEC135 helicopter. The system consists mainly of: Digital Map Generator (including customized storage media,FLARM Module, SATCOM Module),Control Panel, SATCOM Antenna,...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement for Installation of EuroNav 7 Digital MovingMap System, 00036-DO-MZ-FMS-00, Issue 01 dated 18 August 2017or later revisions of the above listed documents approved by EASA.List of Compliance Documents, 00036-DO-MZ-LCD-00, Issue 01 dated 21August 2017.Master Drawing List, 0003...	This change is limited to helicopters which are equipped with CPDS andmulti-monitor FCDS.This change excludes helicopters which are equipped with the HELIONIXcockpit.Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpr...	19/09/2017	Active	10063031
10063034	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CL-600-2B16 (601-3A VARIANT)	Unilink UL-801 upgrade to ATN B1The existing Unilink UL-801was upgraded with SCN 31.X to meet theATN-B1 data link requirements.Universal Avionics System Corporation (UASC) Service Bulletin,“Introduction of UniLink® UL-800 (P/N 10800-01) and UL-801 (P/ N10801-01) and SCN 31.0 withAeronautical Telecom...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:For this installation, the amendments considered i.a.w the TCDS and inadditionamendment 25-123 for §25.1310 and 25-54 for §25.1529 are considered.CS-ACNS.B.DLS all paragra...	- AFM Supplement AC5533-071, Rev. IR- Inst. for Cont. Airworthiness: Doc. No. AC5533-085, Rev. IR- Supplemental MMEL: Doc. No. AC5533-074, Rev. IRor later revisions of the above listed documents approved by EASA- Master Data List: Doc. No.AC5533-049, Rev. A- Declaration of Compliance: Doc. No. AC55...	Limited to Reg: HB-IKS, Sn: 5042Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	01/09/2017	Active	10063034

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063040	AEROLITE AG	REV. 1		AW169	AW 169 EMS Equipment 169-0232000-501Revision 1: Modifications to the EMS Equipment P/N 169-0232000-501 toinclude an expansion of the cabin configuration as per theMDL-17-001_Rev_C, dated 26/04/2019.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement FMS-169-0232000-501-A ,dated 29/03/2019- Master Document List MDL-17-001_Rev_C, dated 26/04/2019- Operations Manual OPM-169-0232000-501-A, issue 28/03/2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Pre-requisites for installation of P/N 169-0232000-501 are given inOPM-169-0232000-501 Rev. A (Chapter Configuration page 2).For any installation onto the Cargo Platform a separate design approvalis needed (not scope of this STC).Prior to installation of this change/repair it must be determined that...	09/05/2019	Active	10063040
10063057	RUAG AG	REV. 2		AS 350 B3	FOCA / STSB H125 Avionics UpgradeRemoved: - Garmin GMA 350HAudio Panel and Garmin GTX 33H TransponderInstalled:- Jupiter Avionics JA94 Audio Controller (Qty 1)<(>,<)>- Garmin GTX33H w/ES (ADS-B Transponder) (Qty 1)<(>,<)>- NAT NPX138 VHF-FM Radio (Qty1)<(>,<)>- Avidyne TAS615 Traffic Advisory Syst...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-27 Amdt 3:CS27.1<(>,<)> CS27.21, CS27.27, CS27.29, CS27.251, CS27.301, CS27.303,CS27.305, CS27.307, CS27.321, CS27.337,...	- Rotorcraft Flight Manual Supplement (SYS): Doc. No. FMS-610668, Rev.B;- Rotorcraft Flight Manual Supplement (NVIS): Doc. No. FMS-611608, Rev.A;- Instructions for Continued Airworthiness (SYS): Doc. No. ICA-8003605,Rev. F;- Instructions for Continued Airworthiness (NVIS): Doc. No. ICA-8004286,Rev.-...	Limited to S/N 8343 (HB-ZSN) and S/N 8349 (HB-ZSO).Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with NightVision Goggles (NVG).For this reason, any deviation from the...	18/01/2021	Active	10063057
10063069	GAMA AVIATION (ENGINEERING) LIMITED	REV. 1	CAA UK RESPONSIBILITY	MODELS B200 AND B300	Gama Modification HL/1451 Revision, Honeywell Aspire 200 Satcom SystemInstallation and enabling.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation in accordance with GAMA Document No. MDL-1451, Issue 3,dated 14 December 2017, Master Data List (MDL) for Honeywell Aspire 200SatCom Installation. Beechcraft Corporation King Air B200 / B300 series;- Operate in accordance with GAMA Flight Manual Supplement refAFMS-1451, Issue: 1, date...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/12/2017	Active	10063069
10063071	BELL TEXTRON, Inc.	REV. 1	FAA STC SR00829DE	429	Installation of Baggage Pallet.Rev. 1: Transfer from "Laz-Tec, LLC." to "Bell Textron, Inc."	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Laz-Tec Drawing List, Report No. LT-15223, Revision A, dated 16February 2017, FAA approved 3 March 2017, or later FAA approvedrevisions.2. Flight Manual Supplement, Laz-Tec, LLC Document No. LT- 15228, NoRevision, dated 24 February 2017, or later FAA approved revisions.3. Instructions for Continu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/03/2025	Active	10063071
10063084	AIRBUS DEFENCE AND SPACE S.A.	REV. 6		A330-243	Conversion of A330-200 Series A/C to A330 Multi Role Transport Tanker(MRTT) GOS (Government of Singapore).- Rev 1 of this STC introduces ALS Part 2 Supplements for MRTT STCSbased on A330 ALI Issue19. After the release of these supplements, Airbus has published ALS Part2R01 and Variations 1.1 & 1.2-...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.0562 Initial Issue for affected areas by this STC;CS 25.0853 Initial Issue for affected areas by change DCV1086-E.T...	- “CONVERSION DEFINITION A330 MRTT GOS STC” document Ref.TAE-FG-DT-160003 Issue A.- Airplane Flight Manual Supplement “EASA APPROVED MODEL A-330 MRTT GOSAIRPLANE FLIGHT MANUAL" document Ref. TAE-FG-DT-150011, Issue asreferenced in STC 10069541 AML TEA-FA-AW-190015.- Temporary Revision No. 5, issue 1...	This STC only covers the installation of external aerodynamic devices(two underwing pods, boom, receptacle for refueling, antennas, fairings,in case they are equipped with) with the associated structuralmodifications, the modification of some basic aircraft systems, theinstallation of some inoperati...	17/04/2023	Active	10063084

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063088	PRATT & WHITNEY ENGINE SERVICES, IN	REV. 1	FAA STC SA11220SC	208, 208B	Installation of a Pratt & Whitney flight data acquisition, storage, andtransmission system (FAST).Rev. 1: changes the “Limitations and Conditions” section to align withamended FAASTC No SA11220SC, dated 23 March 2023.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List for Cessna 208 Series document no. GN4-T-100-7,Revision B, dated 1 May 2017<(>,<)>NEW-PAGE2. FAST Instructions for Continued Airworthiness for Cessna 208 SeriesAircraft, document no. GN4-T-260-8, Revision B, dated 20 April 2017<(>,<)>3. Flight Manual Supplement for Cessna 208 Ser...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is applicable to Textron Aviation, Inc2...	26/09/2023	Active	10063088
10063096	LUFTHANSA TECHNIK AG	REV. 1		A321-111/-131/-211/-231 A320-211/-214/-216/-232/-251N A319-112/-114/-132	Removal of Ka-band SatcomRemoval of EASA STC no. 10058540. Extension to A320-251N within the listof the eligible models.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Compliance Checklist: CRL23-17/04M Rev 3 dated 22.Jan.2020- Instructions for Continued Airworthiness: A-00-17/64-ICA Issue 02 Rev0 dated 05.Dec.2019- Supplemental Type Design Document: STDD23-17/04M Issue 02 Rev 0 dated16.Jan.2020or later revisions of the above listed document(s) approved/accepted...	Airworthiness Limitation Section within A-00-17/64-ICA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product....	28/01/2020	Active	10063096
10063143	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T3	EC135T3H NVIS Certification for NVG Operations – AHUK/135/3101.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement AHUK/135-FMS-109 Revision 0: NVISCertification for NVG Operations<(>,<)>or later revisions of the above listed documents approved by EASA.- Design Compliance Report DCR/1353101-01 Issue A, dated 16 August 2017.- Declaration of Compliance DOC/ 1353101-01, Issue A, d...	- Limited to helicopters with Helionix cockpit variant.- Any deviation from the cockpit or cabin configuration specified inthis STC Type Design may affect the compatibility of theNight VisionImagining System (NVIS) and may require a re-evaluation for NVGcompatibility.Once the aircraft is modified w...	14/09/2017	Active	10063143
10063147	AIRBUS S.A.S.	REV. 1		A330-341/-3422/-343 A330-321/-322/-323 A330-301/-302/-303 A330-201/-202/-203/-223/-243	MOD CJ2089 2KU SYSTEM ACTIVATIONRev. 1: Extension of Modelsaircraft applicability	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Refer to section 4.2 of document Certification Programme Report ref:ACJC-AJA-17002 issue 2The requirements forenvironmental protection and the associatedcertified noise a...	- Certification Programme Report ref: ACJC-AJA-17002 issue 2- Modification Approval Sheet: MAS CJ2089 issue 2- Certification Summary Report ref: AIS-AJA-18005 issue 2- Modification Approval Sheet: MAS CJ2089 issue 5or later revisions of the above listed document(s) approved/ acceptedunder the EASA sy...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/07/2018	Active	10063147
10063149	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A	Installation of Standby Instrument L-3 ESI-2000.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23, Amendment 4 -(not required according to 21A.101)29, 301, 303, 305, 307, 337, 561, 601, 603, 605, 607, 609, 611, 613...	Flight Manual Supplement ASR-2017-007-FMS-05-00 Amdt. 00<(>,<)>or later revisions of the above listed documents approved by EASA.- Certification Programme, Compliance Report, Compliance Statement and Declaration of Compliance ASR-2017-007-CEP-03-00, Amdt. 00.- Instructions for Installation ASR-201...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/09/2017	Active	10063149

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063152	ANJOU AERONAUTIQUE S.R.L.			737-800	Replacement of seatbelts on 16G aircraft seat.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	02-100074-MDL-001, Rev. 04 dated 16 August 2017 “Master Data List”<(>,<)>or later revisions of the above listed documents approved by EASA.	The STC approval is limited to Group 1 Polyester belts installed on thefollowing seat models:Recaro 3510 Seats, Recaro 3410 Seats.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and...	14/09/2017	Active	10063152
10063155	S4A SOLUTIONS FOR AVIATION, S.L			CL-600-2B16 (604 VARIANT)	ISAT SYSTEM AND ANTENNA INSTALLATIONInstallation of SkytracSatCom systems ISAT-100 and ISAT-200A (only oneof them to be installed in the aircraft at the same time) in cockpit andavionics bay, and related GPS/Iridium antenna installation on top offuselage	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI F-01 „Lithium battery installations“The requirements for environmental protection andthe associatedcertified noise and/ or emissions levels of th...	-S4A Modification Description, ref. doc. 60434-DES01, Issue1, dated 1stAugust 2016-S4A Certification Plan, ref. doc. 60434-CPL01, Issue 5, dated 31stAugust 2017-S4A Flight ManualSupplement, ref. doc. 60434-HDK01, Issue 1, dated22nd February 2017-S4A Maintenance Manual Supplement, ref. doc. 60434-H...	None	15/09/2017	Active	10063155
10063156	AIRBUS S.A.S.			A319-115	Airbus Interiors Services MOD CJ2158 SECURITY GUARD SYSTEM INSTALLATION	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI H-01 “Enhanced Airworthiness Programme for Aeroplanes Systems – EWISICA”The requirements for environmental protection and the associatedcertifiedu...	-Modification Approval Sheet MAS CJ2158 issue 02, dated 14th September2017-MDP-Supplement ref: MPD-S MOD CJ2158 dated 1st September 2017or later revisions of the above listed documents approved by EASA.	This approval is limited to Airbus A319-115 MSN 1556	15/09/2017	Active	10063156
10063158	MOTORFLUG BADEN-BADEN GmbH			MBB-BK117 C-2	Installation of Dual COM/NAV/GPS GTN750, GTX33 Mode-S Transponder andKR21 Marker as per Mod. 25101F160284-01.This STC is not applicable to MBB BK117 C-2e.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS Initial issue: B.VCS.(all), D.EHS.(all), D.ELS.(all),D.ADSB.(all)CS-29 Amdt 04: 29.1316 and 29.1317Therequirements for environmental protection and the associated...	25101 F160284-01-0601 Rotorcraft Flight Manual Supplement, R1, dated14.09.2017or later revisions of the above listed documents approved by EASA.25101 F160284-01-0701 Instruction for Continued Airworthiness, R1, dated25.08.201725101 F160284-01-0109 “Master Document List”, R2, dated 14.09.2017	Antenna installations except GPS antenna are not covered bythisapproval.S-BAS based approach functions as well as NVISoperation are not coveredby this approval.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprevio...	15/09/2017	Active	10063158
10063161	ALPINE AEROTECH LP		TCCA STC SH05-52	212/ 412/ 412EP	Firewall Cover installation in accordance with MDL AAL-237-014-001.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:FAR 29 up to Amendment 29-47: 29.1, 29.601, 29.603, 29.605,29.607,29.609, 29.613, 29.901, 29.1191, 29.1529, Appendix AT...	Firewall Cover Master Document List, Document No. AAL-237-014-001,Revision A, dated April 17, 2017, or later TCCA approved revisions.Firewall Cover Installation Instructions, Document No. AAL-237-015-001,Revision NI, dated September 30, 2005, or later TCCA approved revisions.Firewall Cover Installat...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/09/2017	Active	10063161

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063169	MILLENNIUM CONCEPTS, INC.		FAA STC SA01761WI	KODIAK 100	Executive Style Interior Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Millennium Concepts Master Drawing List, No. 2038-MDL052, Rev A,dated 10 July 2014.2. Millennium Concepts Airplane Flight Manual Supplement, No.2038-AFMS-S1, Rev IR, dated 19 August 2014, or later FAA approvedrevisions to 1 or 2.	For production, on aircraft serial numbers 100-0069, 100-0081, and100-0084 through 100-0097, STC SA01711WI must be installed prior tomodification.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed d...	18/09/2017	Active	10063169
10063170	ANCRA INTERNATIONAL LLC		FAA STC SA5014NM	747-400F 747-200B/-200C/-200F/-300	Installation of Ancra Cargo System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ancra Drawing List DL 82000, Revision B, dated 17 August 1990<(>,<)> orlater FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/09/2017	Active	10063170
10063178	WIPAIRE Inc.		FAA STC SP04133CH	4HFR34C778	Installation of pitch locks.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Wipaire, Inc. Installation Instruction, Document No. 1008767, RevisionC, dated 17 June 2016, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/09/2017	Active	10063178
10063180	PPG AEROSPACE	REV. 1	FAA STC ST02542LA	HAWKER 900XP HAWKER 850XP HAWKER 800XP HAWKER 800 HAWKER 750 HAWKER 1000	Installation of PPG Aerospace cockpit windshields P/Ns 196600-01 and196600-02	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. PPG Aerospace Master Data List 196600 at Revision B, dated 12 August2015, or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA) Document No. U10-0370,Revision B, dated 11 August 2015 or later FAA accepted revision.	This approval requires the 196600-01 and 196600-02 windshields bemaintained according to the following PPG Aerospace componentmaintenance manual (CMM), 56-10-23, original issue, dated 7 August 2015or other FAA accepted maintenance data.Prior to installation of this design change it must be determine...	21/09/2017	Active	10063180
10063181	B/E AEROSPACE, Inc. - FSI	REV. 1	FAA STC ST02540SE	777-300ER 777-200LR	Interior reconfiguration	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02540SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. B/E Aerospace, Inc. - FSI (B/E -FSI) Master Drawing List(MDL) B4FS445-D01, Revision AG, dated 23 May 2018, or later Federal AviationAdministration (FAA) approved revisions. 2. The Supplemental Instructions for Continued Airworthiness, B/E - FSIDocument B4FS445-D15, Revision J, dated 21 May 2018<(>...	Concurrent installation of the following FAA STCs, validated by EASA, isrequired for all aircraft modified by this STC:- Delta Engineering FAA STC No. ST03178NY- Amsafe, Inc. FAA STC No. ST02152LAConcurrent installation of the following Boeing Service Bulletins isrequired on airplane serial numbersC...	11/06/2018	Active	10063181
10063197	AVIDYNE CORPORATION		FAA STC SA02013CH	SEE FAA APPROVED MODEL LIST	Installation of Avidyne Corporation Traffic Advisory System(TAS) inaccordance with the Master Document List (MDL) referenced on theattached AML, or later FAA approved revisions.System installation consists of:1) Avidyne Model TAS6XX/TAS6XXA Processor/ Receiver, any one of p/n70-2420-8TAS600, p/n 70...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. The applicable Avidyne Corporation Aircraft Flight Manual Supplement(AFMS) as stated in the Master Document List (MDL) referenced on theattached AML, or later FAA approved revisions.2. The applicable Instructions for Continued Airworthiness (ICA) asstated in the Master Document List (MDL) referen...	1. Directional Antenna installation in accordance with InstallationManual (IM) Document No. 600-00282-000 (32-2351), Revision 01, or laterapproved revisions is approved only for non-pressurized metallicstructure certified to 14 CFR Part 23§23.305 Amendment 23-45 or earlierand to §23.613 Amendment 2...	22/09/2017	Active	10063197

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063200	WIPAIRE Inc.		FAA SA04141CH	208, 208B	Installation of modified McCauley Propeller (SP04133CH) on Cessna 208and 208B (SA04141CH) in accordance with Wipaire, Inc. Drawing No.1008768, Revision A, dated 23 February 2016.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Wipair, Inc. Airplane Flight Manual Supplement, Document No.W208PL-25-02, No Revision, dated 22 September 2016<(>,<) >orlater revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Impleme...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/09/2017	Active	10063200
10063209	WORLDWIDE AVIATION L.L.C.		FAA STC ST01836WI	SAAB 2000	Installation of a Reinforced Flight Deck Door.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Worldwide Aircraft Services Master Drawing List, No. 2000-MDL-300,Rev. C, dated 2 December 2016, and2. Worldwide Aircraft Services Airplane Flight Manual Supplement, No.WA2000-FMS-002, Rev. IR, dated 13 March 2017, and3. Worldwide Aircraft Services Instructions for Continued Airworthiness,No. 200...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/09/2017	Active	10063209
10063212	STENE AVIATION, INC.		FAA STC SA02513SE	SEE FAA AML	Installation of wing tips with integrated Light Emitting Diode (LED)landing and taxi lighting	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Stene Aviation Master Drawing List (MDL), Document SA1400_MDL,Revision D, dated 5 October 2016, or later FAA-accepted revision.2. Instructions for Continued Airworthiness (ICA)Document SA1400_IFCA,Revision B, dated 29 August 2016, or later FAA-accepted revision.3. Aircraft Flight Manual Suppleme...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	21/09/2017	Active	10063212
10063214	AIR AMBULANCE TECHNOLOGY GmbH	REV. 5		AW189	“Quick-conversion” Air Ambulance Equipment, installing various EMS cabinlayout configurationsRev. 1 covered minor STC certificate editorial changesRev. 2 covered the addition of Oxygen System (either “Complete system”or “Provisions Only”) to the previously approved EMS configurationsinstalling one o...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For Revisions 1 through 4:For Configuration AW 189-25-20-101.000-601/601-1/601-2 (EMS equipmentfor max. 1 patient):- Master Data List (MDL) AW 189-25-20-101.000-601, Rev. 0- Certification program CP-AW189-25-20-101.000-60X/70x. Rev. 1- Compliance Record CR-AW189-25-20-101.000-601, Rev. 0.For Configu...	Installation of oxygen cylinders and/or pressure regulatorsfor the“Oxygen Provisions Only” configuration -604 requiresfurther approval bythe Competent Authority.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprevi...	17/12/2024	Active	10063214
10063232 (EASA.A.S.00170)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		DORNIER 228-201	Installation of Cabin Emergency Lights in accordance with ATLModification Summary Sheet (ATL/228/M001 Issue 3) dated 06/08/2004 orlater approved revisions. Flight Manual Supplement ATL Supplement No20.Rev. 1: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:LBA TCDS 2031bThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remaint...	None	1. Subject to compliance with the provision of Part 21 Subpart E, thisSTC and associated data shall remain valid until surrendered, withdrawnor otherwise terminated.2. If transferof this certificate is requested under Part 21A.116, theSTCwill be reissued.3. This STC is approved only for the produc...	10/11/2021	Active	10063232

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063233 (EASA.A.S.00419)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		757-200/-300/-200PF 737-8/-100/-200/-300/-400/-500 737-600/-700/-800/-900/-900ER 737-600/-700/-800/-900 737-200C/-700C 737-200C 737-100/-200/-300/-400/-500	Modification ATL/CPT/M138 Issue 1 dated 29/11/2004, Business ClassDouble Seat p/n C2C207555()16()40INRev. 2: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ATL DDP 503 Issue 2 dated 29/11/2004or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	1. Subject to compliance with the provision of Part 21 Subpart E, thisSTC and associated data shall remain valid until surrendered, withdrawnor otherwise terminated.2. If transferof this certificate is requested under Part 21A.116, theSTCwill be reissued.3. This STC is approved only for the produc...	10/11/2021	Active	10063233
10063234 (EASA.A.S.00512)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		757-200/-300/-200PF 737-8/-100/-200/-300/-400/-500 737-600/-700/-800/-900/-900ER 737-600/-700/-800/-900 737-200C/-700C 737-200C 737-100/-200/-300/-400/-500	Conversion of Reynard Business Class Double Seat Series C3C2075()()Rev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification Summary Sheet DD/024/9083, Declaration of Design andPerformance DDP 504 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	1. This STC relates only to the modification of the seat structure. Aseparate modification will be needed for a passenger seat layout usingthese seats and for use of/ compatibilitywith any seat mounted passengerentertainment equipment.2. This STC is approved only for the product configuration as def...	10/11/2021	Active	10063234
10063235	SYLT AIR GmbH	REV. 1	LBA STC 1294	P.68 B "VICTOR", P.68 C P.68B, S/N 47	Bubble Window Installation.Rev. 1: corrects the applicability to P.68B, S/N 47S/N 45 is not applicable for this change following this revision.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Sylt Air Modification Bubble Windows P.68, based on: LBA STC Ref SA-1294for bubble window installation P.68 B dated 13 January 2003 or laterrevisions of the above listed documentsapproved by EASA.	Aircraft Serial Numbers for P.68 B: 47, 170, 212, andP.68 C: 455 only; S/N 45 is not eligible for this change.The approval holder shall fulfil the obligations of Part 21, Paragraph21.A.109 or 21.A.451(b) (as applicable).Prior to installation of this design change it must be determined thatthe interr...	16/08/2024	Active	10063235
10063239 (EASA.A.S.00332)	ROEDER PRAEZISION GMBH	REV. 1		SA227-DC, SA227-TT, SA226-AT SA227-AT, SA226-T(B), SA226-T, SA226-TC, SA227-AC, SA227-BC,	Installation of MST 67 Mode-S Transponder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement SA226/227-NY-0303-08, Rev. 0, or later EASA approvedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	25/09/2017	Active	10063239
10063240 (EASA.A.S.00639)	ROEDER PRAEZISION GMBH	REV. 1		SA227-DC, SA227-TT, SA226-AT SA227-AT, SA226-T(B), SA226-T, SA227-AC, SA227-BC,	Installation of a Garmin GTX 330D Mode S Transponder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement Doc. No. SA226/227-NY-0604-08 orlaterapproved revision.- MM Supplement SA226/227 NY-0604-07or later approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	25/09/2017	Active	10063240
10063257	AVIONITEC Ltd.			172P	Installation Garmin GNS 430W.Removed: Bendix/King KLX 135A COM/GPS and Bendix King KA 92 GPS Antenna.Installed: Garmin GNS 430W COM/NAV/GPS, Garmin GA 35 WAAS Antenna andGarmin GI106B NAV Indicator.Compliance to AMC20-28 and CRI F-10 was show for RNAV approaches down toLNAV, LNAV/VNAV and LPV Level...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:CS23, original issue, in particular: 23.301, 23.561, 23.1301, 23.1309,23.1321, 23.1327, 23.1351, 23.1357, 23.1359, 23.13...	Flight Manual Supplement: Doc. No. 7687-011, dated 17.07.2017or later revisions of the above listed documents approved by EASA.,,Master Document List: Doc. No. 7687-017, dated 17.07.2017.Instructions for continued airworthiness: 7687-015, dated 17.07.2017.Declaration of Compliance: Doc. No. 7687-060...	Limited to S/N 17276640 (HB-CLS).Technical compliance to AMC20-28 and CRI F-10 does not constitute anoperational approval. It is the operator's responsibility to gainoperational approval for RNAV approaches.Prior to installation of this design change it must be determined thatthe interrelationship b...	27/09/2017	Active	10063257

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063260	LIBERTY PARTNERS, INC.	REV. 1	FAA STC ST11071SC	SEE FAA AML	Demonstration of aircraft critical equipment and antenna systemstolerance of radio frequency interference (RFI) from intentional orspurious transmissions from certain Portable Electronic Devices (PEDs)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Based on 14 CFR §§ 21.115 and 21.101(b)(1), and FAA Order 8110.48, thecertification basis is per the AML TCDS plus the following:- Regulations at the latest amendment 25-0...	1. Master Drawing List L60-DL001, revision H, dated 14 March 2017, orlater approved FAA revision.2. One of the following Airplane Flight Manual Supplements (AFMS),document L60-FM001, L60-FM002, revision A, L60-FM003, L60-FM011,L60FM012< (>,<)> or L60-FM013 dated 14 March 2017 or later approved FAArev...	This STC does not constitute installation approval of a wireless radiofrequency system using wireless data technologies. It only provides datathat may partially support its installation or activation.Prior to installation of this design change it must be determined thatthe interrelationship betweenp...	30/01/2018	Active	10063260
10063263	SECURAPLANE TECHNOLOGIES, Inc.		FAA STC ST02530SE	SAAB SF340A, SAAB 340B	Installation of Securaplane Sealed Lead Acid Batteries.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: 14 CFRPart 25 as noted below:Regulations compliedwith through amendment 25-51:25.1301(a), 25.1301(b), 25.1301(c), 25.1301(d), 25.1309 (a),25.1309(b)(1), 25.1309(b)(2), 25...	1. Master Data List, AM0300-DL02-00 Revision A, dated 4 March 2017, orlater FAA approved revision.2. Instructions for Continued Airworthiness AM0300-IC01, Revision - ,dated 21 February 2017, or later FAA accepted revision.3. Airplane Flight Manual Supplement, AM0300-FM01 -00, Revision -, FAAapprove...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/09/2017	Active	10063263
10063264	S4A SOLUTIONS FOR AVIATION, S.L	REV. 1		208B	Video Mast installation in accordance with S4A Service Bulletin20840-SB001.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS23, Amdt. 4:23.1, 23.21, 23.25, 23.29, 23.45, 23.49, 23.51, 23.53, 23.59, 23.63,23.65, 23.73, 23.75, 23.141, 23.143, 23.1...	- Flight manual supplement 20840-HDK01, Rev. 5, dated 20 December 2017< (>,<)>or later revisions of the above listed documents approved by EASA.Maintenance manual supplement 20840-HDK02, Issue 3, dated 20 December2017 or any later Revision released by S4A.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/02/2018	Active	10063264
10063273	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04161AT	A330-342/ 343	Interior Reconfiguration.	The Certification Basis (CB) for the original product as amended by thefollowing additional or alternative airworthiness requirements:Regulations at the latest amendment 25-0 through 25-13725.1, 25.23(b)(2), 25.27(b) <(>,<)> 25.301<(>,<)> 25.303< (>,<)> 25.562<(>,<)> 25.601< (>,<)> 25.603, 25.605(a), 2...	1. TIMCO Aerosystems Master Data List (MDL) 13T442L001, Revision C,dated 14 July 2014, or later FAA approved revisions.2. TIMCO Aerosystems Instructions for Continued Airworthiness (ICA)13T442R009, Rev. IR, dated 23 May 2014, or later FAA accepted revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/10/2017	Active	10063273
10063277	AIRBUS S.A.S.			A318-112	Airbus Interiors Services MOD CJ2154 - AL MAJID A318 MSN1599 CabinCommunication System Upgrade including WLAN	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI F-0304-000 WLAN & Interfacing T-PEDS Issue 1The requirements for environmental protection and the associatedcertified noise and/ or emissions leve...	-Modification Approval Sheet MAS CJ2154 issue 01, dated 29th September2017-AFM – Supplement, ref. doc. FMS MOD CJ2154, dated 1st July 2017or later revisions of the above listed documents approved by EASA.	This approval is limited to Airbus A318-112 MSN 1599.	29/09/2017	Active	10063277
10063283	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	777-300ER	Gogo 2KU - Structural ProvisionsRev.1: Editorial Correction	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- S21.MDL-1384 Issue 03,,	This STC only approves the installation of the structural provisions forthe later installation of the antenna and radome. The installation ofthe antenna and radome and the loads they induce in the structuralprovisions and the aircraft structure are not covered by this STC andwill be the subject ofP...	09/10/2017	Active	10063283

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063291	STG AEROSPACE GERMANY GmbH	REV. 1		757-200/-300 737-800/-900/-900ER 737-300/-400/-500/-600/-700	REPLACEMENT SIDEWALL LIGHT LENSES AND END RETAINERSRevision1: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 at Amendment 18CS 25.1, CS 25.25, CS 25.27, CS 25.301 (a),(c), 25.305 (a),(b),(c), CS25.307 (a),(d), CS 25.561 (a),(b...	MASTER DATA LIST, Doc No: SG-1020-MDL-01, Rev No. IRINSTRUCTIONS FOR CONTINUED AIRWORTHINESS, Doc No: SG-1006-ICA-01, RevNo. A for Boeing 737INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, Doc No: SG-1008-ICA-01, RevNo. IR for Boeing 757SERVICE BULLETIN, Doc No: SG-1006-SB-01, Rev No. A for Boeing 737SERV...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/02/2021	Active	10063291
10063292	DAC INTERNATIONAL INC.		FAA STC SA10236SC	SEE FAA AML REV. 5	Installation of a GDC 31 Roll Steering Converter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List No. 1049-000-XX, Rev. G, dated 23 August 2006, orlater FAA approved revision.2. Airplane Flight Manual 1049-2100-02, Rev. A, dated 7 October 2005, orlater FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	16/10/2017	Active	10063292
10063304	AVIATION SPECIALTIES UNLIMITED, INC		FAA SR02050SE	MD900	NVIS Lighting System installed as per MDL-900004-3 Rev L, dated 13 June2017.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement FMS-900004-6, rev C, dated 13 June2016<(>,<) >or later revisions of the above listeddocuments approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/or the Technical Implementation Procedures of EU/USA Bilater...	This STC applies to the model listed above and only the specific serialnumbers listed on the ASU Master Drawing List MDL-900004-3, Rev L, dated13 June 2017 or later FAA approved revisions. This rotorcraft employsNight Vision Imaging Systemlighting, commonly named NVIS, that has beencertified to ens...	04/10/2017	Active	10063304
10063316	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	A319-131, A319-132, A319-133 A319-114, A319-115 A319-111, A319-112, A319-113	-201 Antenna Doubler InstallationThis revision will includethe -201 WADL antenna doubler installation,which was not considered by STC Twenty One Limited during the initialapproval.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- S21.MDL-1357 issue 3- ICA S.21.TEC-0568 issue 4or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	27/03/2019	Active	10063316
10063340	ALPINE AEROTECH LP			212, 412, 412EP 205A-1	Cargo Mirror & Pulse Light Kit as per Master Data List AAL-290-014-001,Rev B dated 21 Feb 2014 or later TCCA approved revisions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:FAR 29.1529, Amendment 29-20The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	Valid for all the types and models:RFMS AAL-290-015-401, initial issue, dated 21 Feb 2014or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.Installation instructions as applicable to each modelM...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/10/2017	Active	10063340

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063346	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04370AT	A320-214	Cabin Interior Reconfiguration on an Airbus 320 Series aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Regulations at the latest amendment 25-0 through 25-14425.1, 25.23(a)(b)(2), 25.27 (b), 25.301, 25.303, 25.601,25.603,25.605(a), 25.609, 25.789(a), 25.793, 25.812(e), 25.8...	1. TIMCO Aerosystems, LLC Master Data List 17T002L001, Revision A, dated5 October 2017, or later FAA approved revisions.2. TIMCO Aerosystems, LLC Instructions for Continued Airworthiness17T002R009, Revision IR, dated 16 August 2017, or later FAA acceptedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/10/2017	Active	10063346
10063358	AEROTEC & CONCEPT			AS 350 D AS 350 B, AS 350 B1 AS 350 BA, AS 350 BB AS 350 B2, AS 350 B3	MX-10 Mission System Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27 Amdt 3:27.25, 27.27, 27.51, 27.65, 27.71, 27.143, 27.173, 27.251, 27.301,27.303, 27.305, 27.307, 27.337,27. 341, 27.351, 27.561, 27.601, 27.603,27.607, 27.609, 27.6...	Rotorcraft Flight Manual Supplement AE17058RFMS, issue 0, dated 2October 2017.or later revisions of the above listed documents approved by EASA.Instruction for Continuous Airworthiness AE17058ICA, issue 0, dated 13June 2017Certification Plan/ Presentation Dossier AE17058PCDP, issue 3, dated 8Septembe...	RFMS as per STC EASA. IM.R.S.01158 (AirFilm/Meeker down post utilitybracket) & EASA 10049767 (Crosstube Antenna Mount Kit Dart) remain fullyapplicable.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously instal...	10/10/2017	Active	10063358
10063360	MAGNETIC MRO AS	REV. 1		777-300 747-400 737-800	Installation of Stretcher Assembly P/N 1120030-310This modification introduces a single Stretcher Assembly (P/ N1120030-310) into the passenger cabin of three aircraft types:-B737-800 (8 interior layouts)-B747-400 (7 interior layouts)-B777-300 (1 interior layout) Revision: Transfer of Certificate to M...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:JAR 25.25, JAR 25.27, JAR 25.561(d), JAR 25.785 (a), JAR 25.785(h)(2),JAR 25.785 (j), JAR 25.791, JAR 25.803, JAR 25.807, JAR 25.812, JAR25.813, JAR 25.815,JAR 25.1411(f), J...	17MDL090 Master Data List, B737-800 Issue B dtd. 6. Oct 1717MDL091 Master Data List, B747-400 Issue A dtd. 31. Aug 1717MDL092 Master Data List, B777-300 Issue A dtd. 31. Aug 1717ICA069 Instructions for Continued Airworthiness B737-800 Issue A dtd.31. Aug 1717ICA070 Instructions for Continued Airwort...	EASA STC 10027884 is a pre-requisite to this modificationPrior to installation of this design change it must be determined thatthe interrelationship between this design change andany otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the...	19/09/2019	Active	10063360
10063363	S4A SOLUTIONS FOR AVIATION, S.L	REV. 1		T337H, 337G FT337HP, FTB337G FT337E, FT337F, FT337GP F337E, F337F, F337G, F337H	CAMERA SYSTEM INSTALLATIONThe modification consists in the mechanical installation of cameraSWE300 and its supports outside fuselage in Cessna 337 aircraft; andmechanical installation of rack and mission equipment inside aircraftcabin.Rev.1: Addition of aircraft models.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any i...	33701-HDK01 Flight Manual Supplement issue 333701-RPT02 Master Drawing list issue 2Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Approval for FTB337G model is limited to serial numbers 0004, 0013 &0028.Prior to installation of this design change itmust be determined thatthe interrelationship between this design change and any otherpreviously installed design changeand/ or repair will introduce noadverse effect upon the airw...	12/03/2020	Active	10063363
10063370	AEROCORP AVIONIC SOLUTIONS Inc.		TCCA SA17-82, ISSUE 1	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of Emergency Cabin Lighting System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Airplane Flight Manual Supplement A089601, Issue A;- Installation Instructions Genesys Engineering Order A089430, Issue A;or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement.- Maintenance Instr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/10/2017	Active	10063370
10063373	S4A SOLUTIONS FOR AVIATION, S.L			60	Antenna installation provisions in Learjet 60	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to S4A Master Drawing List L6010-RPT02 Ed1or later revisions of the above listed documents approved by EASA.To be installed i.a.w. S4A SB L6010-SB001 Ed1To be maintainedi.a.w. S4A MM-S L6010-HDK02 Ed1 or later Revisions	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/10/2017	Active	10063373

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063383	SOCIETE AIR FRANCE S.A.	REV. 1		A321-111/-212 A320-211/-214 A319-111/-112/-113/-115	A319, A320, A321 - T-PED tolerance.Aircraft compatibility with the use of PEDs with transmitting capabilityfrom within the aircraft cabin.Rev. 1: Correction of model effectivity.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM: references AFMS-A320-17-015-001 & AFMS-A320-17-015-002or later revisions of the above listed documents approved byEASA.Master Data List: Change Approval Sheet ref: CAS-A320-17-015 Rev 0.ICA: ICA-A320-17-015-001 Rev. 1.	1) This STC does not constitute installation approval of aeroplanehardware. It only provides data that may partially support theirinstallations or activations. This STC may only be applied to anaircraft when an airplane installed base station using the cellularand/or wireless technologies is concurr...	16/10/2017	Active	10063383
10063393 (EASA.A.S.00534)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		550	Installation of TCAS II with MST 67A Mode S TranspondersRev. 1: Transfer of STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:FAA TC No A22CEThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain...	Definition Document DD/ 011/9124 Issue 2ATL Flight Manual Supplement 24 Issue 1ATL Flight Manual Supplement 25 Issue 1orlater revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by installer.This certificate shall remain valid unless otherwise surrendered orrevoked.P...	10/11/2021	Active	10063393
10063394 (EASA.R.S.00544)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		412, 412CF, 412EP 212	Polastar Emergency Exit Lighting InstallationRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification Summary Sheet ATL/GEN/M027 Issue 3, dated November 5 2004or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by installer.This certificate shall remain valid unless otherwise surrendered orrevoked.P...	10/11/2021	Active	10063394
10063395 (EASA.A.S.00611)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		737-300	Installation of Enhanced Mode S TranspondersRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Ltd Definition Document DD/ 017/9168 Issue 1, datedOctober 27, 2004or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by installer.This certificate shall remain valid unless otherwise surrendered orrevoked.P...	10/11/2021	Active	10063395
10063397 (EASA.A.S.00648)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		ATP	Elementary and Enhanced Mode S TransponderRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Ltd Definition Document DD/ 006/8827 Issue 4Aviation Traders Ltd AFM Supplement Number 21 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by installer.Prior to installation of this change/ repair it must be determined thatthe in...	10/11/2021	Active	10063397
10063398 (EASA.A.S.00650)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		737-800	Installation of Enhanced Mode S TranspondersRev. 1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Ltd Definition Document DD/ 016/9198 Issue 2Aviation Traders Ltd AFM Supplement Number 27 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by installer.Prior to installation of this change/ repair it must be determined thatthe in...	10/11/2021	Active	10063398

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063399 (EASA.A.S.00651)	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		DC-8-63 DC-8-61, DC-8-63 DC-8-61	Introduction of a Honeywell EGPWS Mk VIIRev. 1: Transfer ofSTC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aviation Traders Ltd Definition Document DD/ 005/9067 Issue 2Aviation Traders Ltd AFM Supplement Number 22 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by installer.Prior to installation of this change/ repair it must be determined thatthe in...	10/11/2021	Active	10063399
10063400 (2004-11566 // LBA EMZ SA 1417)	ROEDER PRAEZISION GMBH			114, 114A, 114B, 114TC 112, 112TC	Installation of Bendix King Mode S Transponder KT 73	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA STC 2004-11566 from Nayak Aircraft Service GmbH based on:-LBA EMZ SA 1417 Issue 1, dated 30th November 2004.-AFM Supp. Doc. : RC 114-NY-0707-08, Rev 0.or later revisions of the above listed documents approved by EASA.	As listed in the AFMPrior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designchange and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/10/2017	Active	10063400
10063401 (2004-12063)	ROEDER PRAEZISION GMBH			M20, M20A, M20B, M20C, M20D, M20L, M20S, M20M, M20R M20E, M20F, M20G, M20J, M20K,	Installation of Bendix King Mode S Transponder KT 73	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Approval as per EASA STC No. 2004-12063The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applic...	EASA STC 2004-12063 from Nayak Aircraft Service GmbH basedon:- LBA EMZ SA 1412 Issue 1, dated 10th December 2004.- AFM Supp. Doc. : M20-NY-0706-08, Rev 0.or later revisions of the above listed documents approved by EASA.	As listed in the AFM.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	15/11/2017	Active	10063401
10063402 (2004-5755)	ROEDER PRAEZISION GMBH			SA227-TT, SA226-AT, SA227-AT SA227-AC, SA227-DC, SA227-BC, SA226-T(B), SA226-T, SA226-TC,	Installation of TCAS II System and Mode-S Transponder as per LBA STC No.SA 1390 Issue 1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Approval as per EASA STC No. 2004-5755The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applica...	EASA STC 2004-5755 from Nayak Aircraft Service GmbH based on:- LBA STC No. SA1390 Issue 1, dated 04th June 2004.- AFM Supp. CAS 67 TCAS System and MST 67A Mode S System for Fairchild,Doc No. SA226/227-NY-1002-08, Rev 0, dated 21st May 2004.or later revisions of the above listed documents approved by...	As listed in the AFM.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	15/11/2017	Active	10063402
10063403 (2004-11566)	ROEDER PRAEZISION GMBH			114TC 114, 114A, 114B, 112, 112TC,	Installation of Bendix King Mode S Transponder KT 73	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Approval as per EASA STC No. 2004-5755The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applica...	EASA STC 2004-11566 from Nayak Aircraft Service GmbH basedon:- LBA EMZ SA 1417 Issue 1, dated 30th November 2004.- AFM Supp. Doc. : RC 114-NY-0707-08, Rev 0.or later revisions of the above listed documents approved by EASA.	As listed in the AFM.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	15/11/2017	Active	10063403
10063405	ATELIER CHABORD	REV. 1	DGAC 38-SF-0001	B. FA150M B. F150M, FA150K, FA150L B. F150J, F150K, F150L B. F150F, F150G, F150H A. A150L, A150M A. 150K, 150L, 150M, A150K A. 150F, 150G, 150H, 150J	Installation of an exhaust with a silencer.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aeroplane Flight Manual Supplement ref. Supmv-cessna150-17-01 Rev. Bdated 14/12/2017<(>,<) >or later revisions of the above listed documents approved by EASA.FAM STCCESSNA150-17-01Rev. D dated 13/12/2017.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2017	Active	10063405

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063406	FARGO MANUFACTURING CO.	REV. 1	FAA SH656GL	369HS, 369HE, 500N 369D, 369E, 369FF, 369H, 369HM	Installation of Auxiliary Fuel System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Fargo Manufacturing Company Drawing and Parts List A-1066-1082, dated25 October 1982.- Fargo Manufacturing Company Installation Manual, dated 5 November1982.- Rotorcraft Flight Manual Supplement, dated 12 November 1982Or later revisions of the above listed document (s) approved/accepted onbehalf of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/06/2020	Active	10063406
10063409 (EASA.A.C.12747)	ROEDER PRAEZISION GMBH			M20/M20A/M20B/M20C/ M20D M20L/M20M/M20R/M20S M20E/M20F/M20G/M20J/ M20K	Installation of GNS 430 WAAS navigation system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List Doc. No. GNS430-NY-05131-EB06.Engineering Order No. GNS430-NY-05131-05.AFM-S Document No. GNS430-NY-05131-08, Rev 0.ICA Document No. GNS430-NY-05131-07, Rev 0or later revisions of the above listed documents approved byEASA.	As stated in limitation section NAYAK AFM-S Document No.GNS430-NY-05131-08, Rev 0.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon...	15/11/2017	Active	10063409
10063410	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	MBB-BK117 D-2	Hoist Controller and Reel In/Out Switch.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft FMS for MBB-BK117 D-2: AHUK /145-FMS-101<(>,<)>or later revisions of the above listed documents approved by EASA.AHUK Declaration of compliance DOC/ 1453096-01 iss. B.AHUK Airworthiness Certification Plan ACP 1453096-01 iss. C.1.AHUK Design Compliance Report DCR 1453096-01 iss. B.1.	Only applicable if OEM hoist system, AH Change Nr. E-2024, is installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	12/10/2017	Active	10063410
10063415	MT-PROPELLER ENTWICKLUNG GmbH			P2010	Installation of MTV-12() propeller on Tecnam P2010.	Installation of MTV-12() propeller on Tecnam P2010The following paragraph(s) at a later amendment: CS-36, Amendment 4, FAR36, Amendment 36-30.This certificate/ approval involves achange to the requirements forenvironmental protection or achange to the certified noise or emissionslevels.	According to MT-Propeller Master Documentation List No. E-2982, Rev 0<(>,<) >To be operated in accordance with MT-Propeller AFM-S Document No.E-2979, Rev.0<(>,<)>or later revisionsof the above listed documents approved by EASA.To be installed i.a.w. Installation Instruction Doc. No. E-2980, Rev 0,or...	According AFM-S.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	12/10/2017	Active	10063415
10063425	NORTHWEST AEROSPACE TECHNOLOGIESINC.			767-300	Cabin Interior Reconfiguration - AUA 767	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-GEN02 PTC (HR and SD for new seat Install.)H-01 Enhanced Airworthiness Programme for Aeroplane systemsThe following paragraph(s) at a later amendmen...	Certification Summary Doc Nr N0594-D90-1, Rev - Master Drawing List Doc Nr.N0594-D10-1, Rev. CInstructions for ContinuedAirworthiness Doc. Nr. N0594-D70-1 Rev -or later revisions of the above listed documents approved by EASA.	Limited to Boeing 767-300, S/N 25273, -26417<(>,<)> -27095<(>,<)> -29867<(>,<)> -30331<(>,<)> -30383LHT SB Revision to EEPL EBS001136347004 and Thomson Aero Seating SBVT04-25-167 shall be concurrently installedPrior to installation of thisdesign change it must be determined thatthe interrelationshi...	16/10/2017	Active	10063425

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063435	BHE & ASSOCIATES, LTD.	REV. 3	FAA STC SA11221SC	390	Installation of Rockwell Collins Pro Line 21 update to include optionalAutomatic Dependent Surveillance Broadcast (ADS-B) out with flight IDand optional Synthetic Vision System (SVS) and optional 3rd VHF datalinkto support Controller PilotDatalink Communication (CPDLC) Revision 2 updates the Data Li...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA11221SC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List 575-00-0001, revision IR, dated 28 August 2017;2. Airplane Flight Manual Supplement 575-00-0055, revision IR<(>,<)>dated 23 August 2017;3. Airplane Flight Manual Supplement 575-00-0088, Revision IR, dated 6March 2018 for optional FMSv4.2;4. Instructions for Continued Airworthines...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Must have factory installed Rockwell Collins Pro...	06/08/2025	Active	10063435
10063451	DASSAULT FALCON SERVICE			FALCON 7X	DFS MOD 7082A : Falcon 7X with M1000 - S/N 405 Cabin seats replacement.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 19 :Appendix S, § S25.30(a) .The requirementsfor environmental protection and the associatedcertified noi...	Instructions for Continued Airworthiness DFS-DE-15-7X-7082-01 Issue Adated 09.October.2017< (>,<)>or later revisions of the above listed documents approved by EASA.Master Document List DFS-DE-17-7X-7082 Issue A dated 13 October 2017.	This STC is applicable to aircraft Falcon 7X post-modification M1000 S/ N405.This design change must be applied concurrently with Dassault Aviationmodification M-OPT0551 (EASA approval 10036130).Prior to installation of this design change it must be determined thatthe interrelationship between this d...	13/10/2017	Active	10063451
10063452	HONEYWELL INTERNATIONAL, Inc.		FAA STC SR02544SE	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of a Honeywell ASPIRE 200 SATCOM system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List (MDL) MOD-AS350ASPIRE200-5201, RevisionB, dated 12July 2017, or later Federal Aviation Administration (FAA) approvedrevision.Rotorcraft must be maintained in accordance with Instructions forContinued Airworthiness (ICA) MOD-AS350ASPIRE200-7601, Revision A, dated23 May 2017 or la...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/10/2017	Active	10063452
10063459	SECURAPLANE TECHNOLOGIES, Inc.	REV. 1	FAA STC ST02552SE	DHC-8-401, DHC-8-402	Installation of Securaplane Sealed Lead Acid Batteries.	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements:Based on 14 CFR §§ 21.101, and the FAA policy for changed aeronauticalproducts in FAA Order 8110.48, the type certification basis for theBombardier DHC-8-400, DHC-8-401, an...	Master Data List AM0301-DL02-00, Revision -, dated 19 July 2017, orlater Federal Aviation Administration (FAA) approvedrevision.The modified aircraft must be maintained in accordance with theInstructions for Continued Airworthiness, AM0301-IC01-00, Revision -,dated 19 May 2017 or later FAA-accepted...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/10/2017	Active	10063459
10063461	SCANDINAVIAN AVIONICS DESIGN ApS			500/ 550/ S550	GTN upgrade for LPV and TAWS A Operation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements thefollowing paragraph(s) at a later amendment:CS-ACNS Initial Issue, dated 19.12.2013.The requirements for environmental protection and the associatedcertified noise and/...	Installation in accordance with Scandinavian Avionics designmodification ref 2108486, Master Document list 2108486-DOC,Iss 1 dated13.10.2017.Operation in accordance with Scandinavian Avionics design AFMSupplement:-. 2108486-AM A, Iss 1 dated 28.08.2017, TAWS A. 2108486-AM B, Iss 2 dated 04.10.2017, L...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/10/2017	Active	10063461

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063463	AIRBUS HELICOPTERS, Inc.		FAA STC SR09504RC	AS 350 B2/ AS 350 B3	Installation of AHI multi-bloc Center Console.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Helicopters, Inc. Master Drawing List (MDL) 350A82-1792, Rev Adated 26 January 2016 or later FAA approved revision.Instructions for Continued Airworthiness (ICA) 350MMS-035, Rev IR dated21 September 2015 or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/10/2017	Active	10063463
10063477	ANCRA INTERNATIONAL LLC		FAA STC ST02656LA	737-700	Installation of main deck cargo loading system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Regulations at Amd't (25-0): 25.601, 25.609<(>,<)>25.621, 25.1541.Amd't (25-23): 25.30l(a)(b), 25.303, 25.471, 25.607, 25.619. Amd't (25-46): 25.603, 25.605, Amd't (25-51)...	Ancra International LLC Controlled Data List DL85450, Revision F, dated24 May 2017.Instructions for Continued Airworthiness (ICA), Ancra International LLCDocument No. 10472, Revision B, dated 24 May 2017, or later FAA acceptedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.STC ST2556SE must be installed in conjunction wi...	11/12/2018	Active	10063477
10063478	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02507SE	777-300ER	First Class Cabin Refresh of Cathay Pacific Aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:25.853 (a)(c)(d) at CS-25 Amendment 1.The requirements for environmental protection and the associatedcertified noise an...	Master Data List, Northwest Aerospace Technologies, Inc. document No.N0551-D10, Revision B, dated 24 July 2017.Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0551-D70, Revision B, dated 2 August2017or later revisions of the above listed documents approv...	The modification approval is limited to aircraft serial numbersdetermined by Northwest Aerospace Technologies, Inc. drawing 551NT000.If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.Pr...	17/10/2017	Active	10063478
10063487	E A D AEROSPACE AIRWORTHINESS	REV. 1		A340-211, A340-212, A340-213	Satcom KA band & Cabin Wifi Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-0301 (Vibration/ buffeting compliancecriteria for large external antenna installation).The requirements for environmental protection and...	- Master Drawing List, EAD Aerospace document No. 01501-EAS-A-MDL,Revision B, dated 17 October 2017;- Instructions for Continued Airworthiness, EAD Aerospace document No. 01501-EAS-A-ICA-01, Revision D, dated 10 October 2017;- Aircraft Flight Manual Supplement, EAD Aerospace document No.01501-EAS-A-A...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/10/2017	Active	10063487
10063489	B/E AEROSPACE LIMITED		TCCA STC C-LSA08-013/D ISSUE 3	CL-600-2B19	Installation<(>,<)> Complete Custom Aircraft Interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Aero Consulting Services Ltd. Mandatory Maintenance Manual SupplementF606070 Revision A.2. Midcoast Aviation Inc. Airplane Flight Manual Supplement for thePassenger Oxygen System, 33-261M002 Rev A.3. Midcoast Aviation Inc. Airplane Flight Manual Supplement for theToilet and Cargo Compartment Smok...	Restricted to ASN 8072.	18/10/2017	Active	10063489

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063536	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED		CAA UK RESPONSIBILITY	EC135 T2+	BABCOCK/MOD/134 - EC135Description: This STC takes an aircraft equipped with the Airbus factoryNVIS options and role equipped for air ambulance work, and re-roleequips it for airborne surveillance work. NVIS certification of the newequipment is carried out as part of this Change in order to maintain...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27 Amdt 3CS 27 Amdt 3 Appendix ACS 27 Amdt 3 Appendix BCS 27 Amdt 3 Appendix CCS-ACNS.B.VCS.020/ ACNS.B.VCS.025/ ACNS.B.VCS.030The requirements for environmental protec...	Flight Manual Supplement FMS/134-002, Issue 2, dated 22 September 2017or later revisions of the above listed documents approved by EASA.-Design Report DR134-001, Issue 3, dated 23 February 2017- Compliance Checklist CCL/134-003 Issue 2, dated 20 July 2017- Compliance Checklist CCL/134-004 Issue 2,-...	1) This is a series Change applicable to all EC135 T2+ aircraft equippedwith the modifications listed below and subjectto compatibility withother existing Changes.OEM Changes:-Airbus Helicopters Emergency Floats System. Ref Code L321M5801105Third Party Changes:-NVG Curtains. Ref Mod No.: MCH/A/135/...	20/10/2017	Active	10063536
10063537	LUFTHANSA TECHNIK AG	REV. 3		A321-253NX/-271N A321-232 A321-231/-232 A321-211 A320-251N/-271N A320-232/-251N A320-232 A320-214 A319-131/-132/-133 A319-131/-132	Provisions for large Ka-Band antenna and systems installationRev. 2 extends the applicability to the A321-253NXRev. 3 extends the applicability to A319-133; A320-214/-271N;A321-211/-231/-271N	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-101 “Vibration/ buffeting compliancecriteria for large external antenna installation”The requirements for environmental protect...	-Supplemental Type Definition Document, Ref. STDD53-16/21M,Issue 03 Rev01-Airplane Flight Manual Supplement, Ref. A-00-16/92-AFM Issue 04 Rev 00-Instructions for Continued Airworthiness, Ref. A-00-16/92-ICA Issue 05Rev 00or later revisions of the above listed document(s) approved/ acceptedunder the...	Installation allowed only on aircraft that satisfy the criteria andconfiguration defined in Description of Change AVA01-23 Rev 26 and STRConfiguration Sheet AVA02-53-EI-004 Rev 6,or later revisions of thesedocuments, as applicablePrior toinstallation of this change/repair it must be determined tha...	03/08/2022	Active	10063537
10063544	ECMS AVIATION SYSTEMS GMBH			EC635 T3 EC635 P3/EC635 T1/ EC635 T2+ EC135 T2+/EC135 T3/ EC635 P2+ EC135 P3/EC135 T1/ EC135 T2 EC135 P1/EC135 P2/ EC135 P2+	External Load Attachment Device EAD03.Left hand, right handand both-sided installation of External LoadAttachment Device on existing hard points to attach up to four loads.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements thefollowing paragraph(s) at a later amendment:CS-27 Amdt. 2:CS 27.1, CS 27.21, CS 27.25, CS 27.27, CS 27.29, CS 27.45, CS 27.65, CS27.141, CS 27.175, CS 27.177, CS 27.241...	Flight Manual Supplement for External Load System, EAD03 onEC135 P1,P2, P2+, P3, T1, T2, T2+, T3, EC635 P2+, P3, T1, T2+, T3, Original Issue (R0).Airworthiness Limitation Section,Chapter 11 of the ComponentMaintenance Manual and Instructions for Continued Airworthiness (CMM/ICA) for External Load Sy...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/10/2017	Active	10063544
10063549	SOCIETE DUCt/a DUC HELICES PROPELLERS	REV. 2		TB 9, TB 200 TB 10, TB 20, TB 21	TBs Spinner/Backplate STC update (Backplate screw change)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DH TB STCMiC 01 A dated 26/06/2019,or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/06/2019	Active	10063549
10063553	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04408AT	737-600/-700/-800/-900	Installation of Rockwell Collins TPR-901 Automatic DependentSurveillance - Broadcast (ADS-B) Out Transponder(s).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Regulations at the latest amendment 25-0 through 25-143:§25.29, §25.771, §25.773, §25.777, §25.1301(a), §25.1307 (c), §25.1309, §25.1322, §25.1351(a), §25.1353(a), §25.1357...	1. Master Data List (MDL) 216307-MDL, Rev. B, dated 17 August 2017, orlater FAA approved revision.2. Instructions for Continued Airworthiness (ICA) Document 216307-ICA,Rev. A, dated 19 May 2017<(>,<)> or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/10/2017	Active	10063553
10063557	INNOVATIVE SOLUTIONSAND SUPPORT, Inc.		FAA STC ST00379BO	757-200	Integrated Global Navigation System Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:As defined in the Appendix D of the Project Specific Certification Plan(PSCP), 1D-12428, Rev. 14, dated 12 October 2017....	Master Data List (MDL), 1D-13248, Rev. 1, dated 12 October 2017.Instructions for Continued Airworthiness (ICA), 1D-12462, Rev. 3, dated12 October 2017.Airplane Flight Manual Supplement (AFMS), 1D-13249, Rev. 1, dated 12October 2017.EWIS ICA, 1D-12446 Rev. 2, dated 25 Jan. 2017,,or later revisions of...	As per:1) Airplane Flight Manual Supplement (AFMS), 1D-13249, Rev. 1, dated 12October 20172) Instructions for ContinuedAirworthiness (ICA), 1D-12462, Rev. 3,dated 12 October 20173) EWIS ICA, 1D-12446 Rev. 2, dated 25 Jan. 2017,,- Applicable to aircraft with the following EASA STCs installed:1) EASA...	23/10/2017	Active	10063557

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063559	LUFTHANSA TECHNIK AG	REV. 2		A321-271N A321-232 A321-211/-231/-232/-253N X A320-232/-251N A320-214/-232/-251N/-271 N A319-131/-132/-133 A319-131/-132	Ka-Band in-flight connectivity system and in-cabin distribution systemactivationRev. 1: extends the applicability of this STC to the A321-253NX modelRev.2: extends the applicability of this STC to the A319-133, A320-214,A320-271N, A321-211,A321-231 and A321-271N models	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Supplemental Type Definition Document, Ref. STDD23-17/03M, Issue 03Rev 00- Airplane Flight Manual Supplement, Ref. A-00-16/93-AFM Issue 01 Rev 02- Instructions for Continued Airworthiness, Ref. A-00-16/93-ICA Issue 05Rev 00- Flight Crew Data, Ref. A-00-16/93-FCD Issue 01 Rev 02or later revisions o...	- Only applicable to aircraft with EASA STC 10063537 installed.- Installation on aircraft models only that satisfy the configurationsand criteria defined in Description of Change AVF01-23 Rev 34 or laterapproved revisions of this document.Prior to installation of this design change it must be determ...	19/08/2022	Active	10063559
10063567	LINDSTRAND TECHNOLOGIES Ltd.		CAA UK RESPONSIBILITY	LBL 77X	Modification L52; STC for Lindstrand Technologies ‘bottom end’components (Vortech double burner on 700 x 700 frame <(>&<)> 1.0 x 1.2basket) on Cameron (ex-Lindstrand) 77X envelope.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-31HB Amdt. 1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels ofu...	LTLHABFM Issue 6.0 ‘Hot Air Balloon Flight Manual’ Supplement 1or later revisions of the above listed documents approved by EASA.Compliance Checklist: LTLHAB STC for Cameron Balloon Envelopes CCL Issue1 Design Definitions: (700 x 700) Burner frame; BA-100-A-002<(>,<)> 1.0x 1.2 Basket: BA-001-A-001.I...	None	24/10/2017	Active	10063567
10063572	SABENA TECHNICS BGC			A330-203	Cabin reconfiguration with IFE eXlite System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:Applicable regulations at CS 25 Amendment 4 (for details refertoassociated Certification Plan ref 4802-03-A-CP-R02, sectio...	- AFM ref 4802-02-A-AFMS rev 01or later revisions of the above listed documents approved by EASA.- Master Data List ref4802-03-A-MDL-R00- ICA: ref 4802-03-A-ICA-R00	Refer to the concurrent requirements of the Certification Plan ref4802-03-A-CP-R02, section 2.5.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadver...	25/10/2017	Active	10063572
10063579	AEROSPACE LOGIC INC.		TCCA STC SA09-96	SEE "200 SERIES ELIGIBILITY LIST".	Aerospace Logic Aircraft Instruments 200 Series as per Document S200-CPL Rev 1.0 dated 02.12.2009 or later Transport Canada approvedrevisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation as primary or secondary, new or replacement must be inaccordance with Aerospace Logic Certified Installation List – Document S200-CIL, Rev. 1.0 dated 02/12/2009 (approved Transport Canada on14/12/2009)- Operation of instruments utilizing and intensity control module mustbe done in ac...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/10/2017	Active	10063579
10063582	FEDERATION FRANCAISE DE VOL A VOILE (FFVV)			101D/ 101 P 101/101 A/ 101 AP/ 101B/ 101BC	Rear wheel on C101 Pegase Glider.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	BS 03-2015-FFVV edition 1 du 25/10/2015.	None.	25/10/2017	Active	10063582
10063595	RAISBECK ENGINEERING Inc.	REV. 1	FAA STC SA02559SE	300, 300LW, B300, B300C	Installation of Raisbeck/Hartzell Five-Blade Swept TurbofanPropellersHC-E5P-3 Hubs with NC10320K Blades.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Installation in accordance with Raisbeck Engineering MasterDrawing List(MDL) 14BC-61-000, Revision A, dated August 28,2017, This installationrequires the prerequisite installation of STC SA5151NM (LBA STC SA1011)which installs Raisbeck Dual Aft Body Strakes.Aircraft must be operated in accordanceA...	1) This STC is only approved for installation on the above modelaircraft when the aircraft is operated in the commuter category underthe provision of Type Certificate Data Sheet EASA.IM.A.277.2) This STC is not approved for installation onthe above model aircraftwhen the aircraft is operated in the...	12/07/2018	Active	10063595

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063613	AEARO TECHNOLOGIES LLC		FAA STC ST04252CH	BD-700-1A10, BD-700-1A11	Install thermal acoustic insulation system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Regulations at the latest amendment 25-0 through 25-144:14 CFR §§ 25.307(a), 25.611, 25.613, 25.853(a)<(>,<)> 25.856(a)<(>,<)>25.1301(a), 25.1309(a)(b)(d)The requirementsc...	1. Aearo Technologies Master Data List MDL-1747-001, Revision A, dated19 December 2017, or later FAA approved revisions.2. FAA accepted Instructions for Continued Airworthiness ManualICA-1747-001, Revision IR, dated 30 May 2017, or later FAA acceptedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/11/2017	Active	10063613
10063614	MOTORFLUG BADEN-BADEN GmbH			MBB-BK117 C-2	Installation of EOS camera Star Safire 380HDc and cabin workstation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight manual Supplement AFMS 25101F160285-01-0601 initial revisiondated 07 June 2017or later revisions of the above listed documents approved by EASA.Instruction for Continued Airworthiness ICA 25101F160285-01-0701 initialrevision dated 03 February 2017Master Document List MDL 25101F160285-01-0109,...	Camera System Star Safire 380HDc shall be mounted on the existingmounting arm certified by AHD for the Star Safire 380HD (ref AHD RFMS9.2-70).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed desig...	02/11/2017	Active	10063614
10063622	SII DEUTSCHLAND GMBH			A330-223	LDMCR (Lower Deck Mobile Crew Rest) Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, Ref. MDL-257-00004-000A, dated 30/10/2017- Aircraft Flight Manual Supplement, Ref. AFS-257-00004-000B, dated24/10/2017or later revisions of the above listed documents approved by EASA.	- Only applicable to A330 MSN 290 and 300.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	02/11/2017	Active	10063622
10063633	SABENA TECHNICS BGC			747SP 747-8F 747-8 747-400F 747-400 BCF 747-400 747-300 747-200F 747-200C 747-200B 747-100	USB charging plugs into cockpitInstallation in cockpit, on both Captain and F/O sides, of one 28/5VDCconverter dual USBcharging plugs.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS-25 Amdt 4 (Refer to Aeroconseil Certification Plan, ref:0801-03-A-CP-R00, paragraph 5 & 6 for detailed requirements,acco...	- Instructions for Continued Airworthiness, Aeroconseil document No.0801-03-A-ICA, R00 (initial release)- Airplane Flight Manual Supplement, Aeroconseil document No.0801-03-A-AFMS, R00 (initial release) or later revisions of the above listed documents approved by EASA.- Master Data List, Aeroconseil-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/11/2017	Active	10063633
10063637	AVOX SYSTEMS Inc.		FAA STC ST01780WI	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of the AVOX LavOx Passenger Lavatory Oxygen System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forEquivalent Safety Finding(s):CRI F-02 Oxygen Fire Hazard in Gaseous Oxygen Systems.The requirements for environmental protection and the associatedcertified noise and/u...	AVOX Systems Inc. Instructions for Continued Airworthiness (ICA) No. 89561, Revision Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision) and/ or the Technical Implementation Procedures of EU/USA Bil...	None.	06/11/2017	Active	10063637

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063638	LUFTHANSA TECHNIK AG			A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	ADS-B Out Activation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS Initial Issue: ELS.010, ELS.015, ELS.020, ELS.025, ELS.030,ELS.040, ELS.045, ELS.050, ELS.055, ELS.060, ELS.065, EHS.010, EHS.015,EHS.020, EHS.025, ADSB.001, ADSB....	- Supplemental Type Definition Document, Ref. STDD34-17/04MIssue 1,Rev. 0- Compliance Record List, Ref. CRL34-17/04M, Issue 1 Rev. 1- Master Minimum Equipment List Supplement<(>,<)> Ref. A-00-17/77-MMELRev.0- Airplane Flight Manual Supplement, Ref. A-00-17/77-AFM, Issue 1 Rev.0- Instructions for Co...	- The pre-change configuration and prerequisites are defined in theDescription of Change AVU01-34 Chapter 2.1- Limitations as per: AFMS Section 2 “Limitations”, Ref.A-00-17/77-AFM, Issue 1 Rev.0Prior to installation of this design change it must be determined thatthe interrelationship between thisp...	06/11/2017	Active	10063638
10063641	AVIONITEC AG			340A	Avionics renewal.Removed:- Bendix/King KI 525A Analog HSI with KA51B Slaving Accessory- Aerosonic EA-801A Encoding Altimeter- L-3 WX-950 Stromscope with NY 163 AntennaInstalled:- Sandel SN 3500 EHSI- Avidyne TAS 615 Traffic Advisory Systemwith Top/Bottom Antenna- TCI SDD 120 Altitude Serializer- Sa...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFMS for Sandel SN 3500 EHSI: Doc. No. 7203-011, Rev. 25.11.16.- AFMS for Avidyne TAS 615: Doc. No. 7203-012, Rev. 25.11.16.- AFMS for Garmin Flight Stream FS-210: Doc. No. 7203-013, Rev. 22.05.17,,or later revisions of the above listed documents approved by EASA.- Master Document List: Doc. No. 7...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/11/2017	Active	10063641
10063645	NORTHWEST AEROSPACE TECHNOLOGIESINC.			777-200	Cabin Interior Reconfiguration - AUA 777.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):D-GEN02 PTC (HR and SD for new seat Install.).D-GEN01 PTC (Fire Resistance Thermal Insulation material).H-01 Enhanced Airworthiness Programme for Aero...	Certification Summary Doc Nr N0594-D90-2, Rev- ;Master Drawing List Doc Nr.N0594-D10-2, Rev.E;Instructions for Continued Airworthiness Doc. Nr. N0594-D70-2 Rev- ;or later revisions of the above listed documents approved by EASA.	Limited to Boeing 777-200, S/N 27607, -28698,-28699,-29313,-35960.LHT SB Revision to EEPL EBS00113595/005, Thomson AeroSeating SBVT04-25-175 and Austrian Engineering Bulletin EB-777-25-0028-00 shall beconcurrently installed.Prior to installation of this design change it must be determined thatthe i...	07/11/2017	Active	10063645
10063684	PHOENIX AEROSPACE LIMITED	REV. 1	CAA UK RESPONSIBILITY	S-61N	Introduction of Sandel ST3400H HTAWS and SG102/D AHRSRev.1:Addition of S-61N serial number 61809	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: FAR 29, initial issue: 29.1, 29.25, 29.27, 29.29, 29.251, 29.301, 29.303, 29.305, 29.307,29.337, 29.561, 29.571, 29.601, 29...	Initial issue:- Flight Manual Supplement ST3400H HeliTAWS System<(>,<)>S-61N,Supplement 118, Doc No PAL-FMS-S61-118, Revision C;Following Rev. 1:- Certification Plan, Doc No PAL-CPL-1307, Revision C;- Compliance Report, PAL-CPR-1307, Revision C;- Master Document List, Doc No PAL-MDL-1307, Revision D...	Limited to serial numbers 61269, 61270 and 61809.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	15/10/2019	Active	10063684

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063705	SABENA TECHNICS BGC	REV. 1		A321-272NX A321-271NX, A321-272N A321-253NX, A321-271N A321-252NX, A321-253N A321-251NX, A321-252N A321-231, A321-232, A321-251N A321-211, A321-212, A321-213 A321-111, A321-112, A321-131 A320-271N, A320-272N A320-233, A320-251N, A320-252N A320-216, A320-231, A320-232 A320-212, A320-214, A320-215 A319-132, A319-133, A320-211 A319-114, A319-115, A319-131 A319-111, A319-112, A319-113	Mechanical and electrical installations for Thales EFB solutionmountings in cockpit of A319/A320/A321This change to STCdefines an additional electrical configuration (GroupII), aquick release cable to cut-off the power (replacing a dedicatedswitch), and addition of the A321 NX Models.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 amdt 4 or later (refer to associated Certification Plan0803-01-A-CP-R04 section 6).The requ...	- Master Data List: 0803-01-A-MDL-R02- Instruction for Continued Airworthiness: 0803-01-A-ICA-R03- Aircraft Flight Manual Supplement: 0803-01-A-AFMS-R01or later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/02/2019	Active	10063705
10063717	ALOFT AEROARCHITECTS			737-900ER 737-900 737-800 737-700C 737-700 737-600	Installation of Automatic Dependent Surveillance – Broadcast Out (ADS-BOut) system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. ALOFT AeroArchitects: Installation Master Drawing List, document No. 7753-0001-MDL, revision D, dated 11 May 2017, orlater FAA-approvedrevision.2. ADS-B Out Configuration Matrix, document No. 7753-34-CFGM-001,revision B, dated 29 March 2017, or later FAA-approved revisions.3. FAA-accepted Instruc...	Prerequisite installations to this STC include the following:a. Rockwell Collins transponder (TPR-901), P/N 822-1338-003,822-1338-004, or 822-1338-005.b. Rockwell Collins multi-mode receiver (GLU-920), P/N 822-1152-001,822-1152-002, 822-1152-003, 822-1152-004, or 822-1152-005.This ADS-B OUT system m...	15/11/2017	Active	10063717
10063741	MT-PROPELLER ENTWICKLUNG GmbH			BN2, BN2A, BN2A-2, BN2A-6 BN2B-27 BN2B-20, BN2B-21, BN2B-26 BN2A-8, BN2A-9, BN2A-20 BN2A-21, BN2A-26, BN2A-27	Installation of MTV-14-() on Model BN2, BN2A and BN2B series.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS-36, Amendment 4, FAR 36, Amendment 36-30.This certificate/ approval involves a change to the requirements forenvironment...	- According to MT-Propeller Master Documentation List No. E-3013, Rev 3;- To be operated in accordance with MT-Propeller AFM-S Document No.E-3010, Rev. 0;or later revisions of the above listed documents approved by EASA.- To be installed i.a.w. Installation Instruction Doc. No. E-3011, Rev0, or later...	According AFM-S.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	14/11/2017	Active	10063741
10063764	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-46R-350T (MATRIX) PA-46-500TP (MERIDIAN) PA-46-350P (MIRAGE) PA-46-310P	Installation of following antennas:- single Bendix/King KA131 radar altimeter antenna- single L-3 Communications NY-164antenna	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Elect toComply by applicant:CS-23 Amdt. 4 paragraphs:23.29; 23.301(a); 23.303; 23.305(a); 23.305(b); 23.307(a); 23.337(a)(1); 23.365 (a); 23.365(b); 23.365(d); 23.561 (a);2...	Master Document List-Doc. No. ASR-2016-071-MDL-01-01, issued 02-NOV-2017Instructions for Continued Airworthiness-Doc.No. ASR-2016-071-ICA-11-01, issued 02-NOV-2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/11/2017	Active	10063764
10063767	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09612RC	505	Installation of a Cowling Access Door Kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List, Report No. AA-16075, Revision B<(>,<)> dated 20April 2017, or later FAA approved revision.2. Instructions for Continued Airworthiness, Report No. AA-15073<(>,<)>Revision A, dated 28 April 2017, or later FAA acceptedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/12/2017	Active	10063767

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063770	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09613RC	505	Installation of an Automatic Door Opener Kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List, Report No. AA-16060, Revision A<(>,<)> dated 11April 2017, or later FAA approved revision.2. Instructions for Continued Airworthiness, Report No. AA-15071<(>,<)>Revision B dated 30 March 2017, or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/12/2017	Active	10063770
10063774	SAAB AB	REV. 2		B200GT	Installation of SATCOM using Iridium satellites model: Flightcell DZMx.Rev. 1: Transfer to SAAB AKTIEBOLAG.Rev. 2: Correction of DOA reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Installation Data TDM17-24-3-ID Revision A.- Instructionsfor Continued Airworthiness TDM17-24-4-ICA Revision A.- Certification Program TDM17-24-1-CP Issue A.- Design AssessmentTDM17-24-1-DA Issue A.- Ground Test TDM16-35-1-GT Revision A.- Generic Interference Test TDM16-35-1-GIT().- First Articl...	This change is only applicable to Beech 200GT with Fusion avionics. Aprerequisite is that no HF is installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will intr...	07/12/2023	Active	10063774
10063786	JET AVIATION ST. LOUIS, Inc.	REV. 1	FAA STC ST03161CH-D	CL-600-1A11/-2A12/-2B16 BD-700-1A10/ BD-700-1A11	Use of Portable Electronic Devices (PEDs) to Control installed AircraftSystems.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	JET AVIATION ST. LOUIS INC. INDEX LIST No. 35-406G003 REV CDATED 01December 2014.	The Wi-Fi and Cabin Management Systems on which the PEDs will functionrequire EASA approval by means other than this STC.	27/11/2017	Active	10063786
10063787	AIRBUS HELICOPTERS DEUTSCHLAND GmbH			EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of a Cockpit Voice Flight Data Recorder (CVFDR) System inaccordance with Compliance Report SK-MAC-117-CRP-B-1385.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement CVFDR Upgrade SK-MAC-177-SUP-B-1376, Issue A,,or later revisions of the above listed documentsapproved by EASA.Compliance Report SK-MAC-177-CRP-B-1385, Issue D.Customisation Manual SK-MAC-177-CM-B-1375, Issue C,,.	Applicable to variants with CPDS installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducenoadverse effect upon the airworthiness of the product.	20/11/2017	Active	10063787
10063795	ELBE FLUGZEUGWERKE GmbH	REV. 4		A330-342, A330-343 A330-322, A330-323, A330-341 A330-302, A330-303, A330-321 A330-223, A330-243, A330-301 A330-201, A330-202, A330-203	Lavatory A installation in A330 passenger to Freighter convertedaircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Top Engineering Order EFW-EO-0047-001 Revision B dated 20-11-2017;- Type Investigation EFW-TIP-0047-001 Revision C dated 20-11-2017;- Instructions for Continued Airworthiness EFW-E-ED-00277 Revision Bdated 05-07-2018;- Master Minimum Equipment List A330-P2F-MMEL-S-CLC-ENV Revision 01dated 01-05-20...	This modification must be installed together with the following relatedchange:- EFW - A330 Passenger to Freighter. Approval number 10063798.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changee...	30/01/2019	Active	10063795
10063796	ELBE FLUGZEUGWERKE GmbH	REV. 5.1		A330-342, A330-343 A330-323/-341/-342/-343 A330-322, A330-323, A330-341 A330-302, A330-303, A330-321 A330-301/-302/-303/-321/-322 A330-223, A330-243, A330-301 A330-201, A330-202, A330-203 A330-201/-202/-203/-223/-243	Installation of Courier Module in the A330 Passenger to Freighter.This STC covers 2 options of the Courier Module:- Courier Stowage-Flight Crew Rest CompartmentRev. 4: Limitation for un-occupied Courier Area needed for storage ofpersonal belongings	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): F4313-001 Installation of Flight CrewRest Module on A330 Passenger to Freighter.The requirements for environmental protection and the assoc...	- Top Engineering Order EFW-EO-0046-001 Revision H- Master Minimum Equipment List A330P2F-MMEL-CLC-ENV Revision 01- Aircraft Flight Manual Supplement A330P2F-AFM-CLC-ENV Revision 02- Instructions for Continued Airworthiness EFW-E-ED-00277 Rev B- Documents valid only for courier stowage: - Typ...	This modification must be installed together with the following relatedchange:- EFW - A330 Passenger to Freighter. Approval number 10063798.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changee...	07/02/2023	Active	10063796

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063797	ELBE FLUGZEUGWERKE GmbH	REV. 3		A330-342, A330-343 A330-323/-341/-342/-343 A330-322, A330-323, A330-341 A330-302, A330-303, A330-321 A330-301/-302/-303/-321/-322 A330-223, A330-243, A330-301 A330-201, A330-202, A330-203 A330-201/-202/-203/-223/-243	Powered Cargo Loading System Installation in A330 Passengerto FreighterThis approval covers the installations of powered cargo loading systemsin A330-200 and A330-300 Passenger to Freighter models.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Top Engineering Order EFW-EO-0048-001 Revision D- Type Investigation EFW-TIP-0048-001 Revision E- Instructions for Continued Airworthiness EFW-E-ED-00277 Revision BPost P2F Modification certified with EFW-EO-0198-001 Rev. A andEFW-TIP-0198-001 Rev. B:- EFW-SB-25-0096 R00 - Modification of Cargo Lo...	This modification must be installed together with the following relatedchanges:- EFW - A330 Passenger to Freighter. Approval number 10063798.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change...	22/02/2023	Active	10063797
10063798	ELBE FLUGZEUGWERKE GmbH	REV. 40		A330-341/-342/-343 A330-323/-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303/-321/-322 A330-301/-302/-303 A330-223/-243 A330-201/-202/-203/-223/-243 A330-201/-202/-203	Airbus A330 Passenger to Freighter conversion.Rev. 16 for editorial changes and update of AMOC list.Rev. 17: Introduction of A330P2F Smoke Curtain Design Improvement.Rev. 18: implementation (Adaptation Engineering) of Major Change F<(>&<)>DT Analysis for MSN 0610.Rev. 19: MSN 0709 EA Life Limit Rela...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):As per STCDS 10063798 at revision 9 with following special conditions:D-02 Courier Compartment.D-03 Fire Protection of Essential systems/...	- Certification Summary A330-200 398/QAD/066 Revision C<(>,<)>- Certification Summary A330-300 398/QAD/057 Revision A<(>,<)>- Major Structural Deviations of MSN 127 Certification Plan 398/QAD/058Rev. B<(>,<)>- Major Structural Deviations of MSN 709 Certification Plan 398/QAD/075Rev. A<(>,<)>- MajorR...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This modification must be installed with the followingc...	04/11/2025	Active	10063798
10063799	S-TEC CORPORATION	REV. 1	FAA SR11230SC	EC 120 B	Installation of HeliSAS Stability Augmentation System and Autopilot(SAS/AP).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI CS 27.1309 (FAA Special Condition 27-040-SC).The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	Rotorcraft Flight Manual Supplement to the Airbus Helicopters EC120 BRotorcraft Flight Manualwhen equipped with the HeliSAS/Autopilot System, Supplement n °ST-995-RFMS-0001, Rev A<(>,<)>or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/11/2017	Active	10063799
10063802	CARSON HELICOPTERS, INC.		FAA STC SR02507NY	SEE FAA AML	Installation of Goodrich AC rescue hoist system P/N 44311-10-2NEW-PAGE	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Rotorcraft Flight Manual Supplements required with this installation(see AML N° SR02507NY)or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of E...	1. This approval is limited to the model helicopters listedin AML No.SR02507NY with the following aircraft configuration:a. CT58-140-1 or·-2 enginesb. Main Gearbox P/N S6135-20600-039 and subsequentc. Ribbed pocket tail rotor blades P/N S6117-30101-043 and subsequentd. Bifilar assembly P/N 56112-23...	13/03/2018	Active	10063802
10063824	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 3	FAA ST02632LA	SEE FAA AML	Modification to replace the existing Mode S Transponder system with ACSSNXT-700 Mode S Transponder with ADS-B Out and optionally install theACSS NXG-900 GPS as a position source for ADS-B Out.Rev. 3 includes an additional NXT-700 transponder part number,additional approved aircraft models and addit...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved AML STC Master Data List (MDL) as defined, along with itsassociated FAA approved Airplane Flight Manual Supplement andInstructions for Continued Airworthiness in the AML No. ST02632LA, dated09 June 2017, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	03/09/2018	Active	10063824

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063836	JET AVIATION ST. LOUIS, Inc.	REV. 1	FAA ST02620CH-D	BD-700-1A10	Installation of a Pocket Door.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements forDeviation(s):CRI D-01 Installation of a Pocket Door.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	JET AVIATION ST. LOUIS INC. Index List No. 35-174G002 Rev. B Dated 17November 2016.	1. Restricted to ASN 9300.2. Door finish requirements and installation environment must adhere tothe applicable frangibility and/or decompression requirements. Refer toIndex Listfor requirements definition.3. Maximum installed door weight must not exceed the requirementsdefined by the correspondin...	10/01/2018	Active	10063836
10063837	JET AVIATION ST. LOUIS, Inc.		FAA STC ST04157CH	BD-700-1A10	Modification of an Executive Interior Arrangement.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	JET AVIATION ST. LOUIS INC. Airplane Flight Manual Supplement No. 35-299M005 Rev. NC.JET AVIATION ST. LOUIS INC. Instructions for Continued Airworthiness No. 35-027E512 Rev. Bor later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequentt...	1. Restricted to ASN 9300.2. EASA STC No. 10044180 Rev 1 isa prerequisite for this STC. 3. EASA STC No. TBD (EASA PN 0010049549 refers) is a prerequisite forthis STC.	23/11/2017	Active	10063837
10063838	POLYTECH AERO SUPPORT INC.		TCCA STC SA17-37	A330-243	A330 CABIN LAYOUT RECONFIGURATION.This modification reconfigures the passenger cabin of Airbus A330aircraft type, certified under Canadian Type Certificate A-205 asapplicable.The reconfigured cabin includes: new J/C seats (12) and Y/C seats (333);interior placards, emergency equipment (rearranged fo...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TCCA SUPPLEMENTAL TYPE CERTIFICATE, Number: STC SA17-37.CERTIFICATION PLAN A330 CABIN LAYOUT RECONFIGURATION CP-17-001 REV. 0JUN 20/2017.PERMISSION GRANTED UST PGL-17-001, REV. 0 APR 6/2017.MODIFICATION SUMMARY MS-17-001 REV. 0 APR 6/2017.SEATS DECLARATION OF DESIGN AND PERFORMANCE.ENGINE ERING BULLE...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product. The aircraftshould be weighed upon modification...	23/11/2017	Active	10063838
10063839	MAP AIRCRAFT PART 21 AS			AS 365 N3	AXNES PNG Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-29 Amendment 3:29.1, 29.301, 29.303, 29.305, 29.307, 29.561, 29.601, 29.603, 29.605,29.609, 29.610, 29.613, 29.629, 29....	Flight Manual Supplement MAP084FMS Issue C, dated 01/11/2017<(>,<)>or later revisions of the above listed documents approved by EASA.- Master Drawing List MAP084A101 Issue C dated17/11/2017.- Certification Compliance Report MAP084D101 Issue B, dated 17/11/2017.	Compatibility with Night Vision Goggles (NVG) has not been demonstrated.Therefore NVIS operation is not allowed with this STC installed.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design chan...	23/11/2017	Active	10063839
10063854	HELIKOPTER AIR TRANSPORT GESELLSCHAm.b.H.	REV. 5		EC135 T3 EC135 T2+, EC135 T3 EC135 T2+ EC135 T2 EC135 T1 EC135 P3, EC135 T1, EC135 T2 EC135 P3 EC135 P2+ EC135 P2 EC135 P1, EC135 P2, EC135 P2+ EC135 P1	Inst. of multipurpose interior lining (Configuration 25-001).Rev. 1 included the Medical Attachment Structure configuration 25-002Rev. 2 required changes in the forward airframe roof section/ attachmentstructure due to added applicability to new introduced EC135 T3H/P3HHelionix helicoptersRev. 3 ens...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:For Configuration 25-001R2:CS 27, Amdt 4: CS 27.301 (a)(b)(c),CS 27.303, CS 27.305 (a)(b), CS27.561 (a)(b), CS 27.573 (a)(...	For Configuration 25-001 Rev 3:• AFM Supplement Doc AFMS 25-001, Rev 2• Engineering Order Doc EO 25-001, Rev 3• Instructions for Continued Airworthiness Doc ICA 25-001, Rev 1• Installation Manual Doc IM 25-001, Rev 3• Installation Manual Helionix Doc IM 25-001, Rev 2• System Maintenance Manual Doc S...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/04/2022	Active	10063854

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063857	E A D AEROSPACE AIRWORTHINESS	REV. 5		A321-272N/-272NX A321-271N/-271NX A321-253N/-253NX A321-252N/-252NX A321-251N/-251NX A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Activation of the Airborne Complementary Ground Component (ACGC) System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, EAD Aerospace document No. 01538-EAS-A-MDL,Revision F, dated 29 March 2019.Airplane Flight ManualSupplement, EAD Aerospace document No. 01538-EAS-A-AFM-01, Revision B, dated 17 July 2018.Instructions for Continued Airworthiness, EAD Aerospace document No.01538-EAS-A-ICA-01, Rev...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/04/2019	Active	10063857
10063896	LUFTHANSA TECHNIK AG			A330-343	A330 DLH 2 Class Configuration - PAC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document, Ref. STDD00-16/27M, Issue 1Rev. 0- Compliance Record List, Ref. CRL00-16/27M, Issue 1 Rev. 0- Airplane Flight Manual Supplement, Ref. A-00-17/20-AFM Issue 1 Rev. 0- Instructions for Continued Airworthiness, Ref. A-00-17/20-ICA Issue 3Rev. 0or later revisions...	The following pre-requisite installations apply:- Installation of 1000-series photo luminescent emergency path markingsystem certified by EASA STC 10014507 & Minor Change ApprovalCRASMX-5526.- Installation of ZNAT Interior Reconfigurationcertified by EASA STC10059276 and Minor Change Approval N054...	29/11/2017	Active	10063896
10063914	LITEAIR AVIATION PRODUCTS Inc.		FAA STC ST02528SE	ATR 72-212 A ATR 72-211/ ATR 72-212 ATR 72-201/ ATR 72-202 ATR 72-101/ ATR 72-102 ATR 42-320/ ATR 42-500 ATR 42-200/ ATR 42-300	Installation of lightweight window plugs.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	LiteAir Document LAP2012, Revision IR, dated 11 January 2017 or laterFAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/11/2017	Active	10063914
10063917	B/E AEROSPACE, Inc. - FSI		FAA STC ST02538SE	A330-203/ A330-303	Installation of monuments and structural provisions on Airbus ModelA330-200/-300 series airplanes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	B/E Aerospace, Inc. - FSI (B/E - FSI) Master Drawing List (MDL)B6FS638-D01, Revision E, dated 24 November 2017 or laterFAA approvedrevision.The Supplemental Instructions for Continued Airworthiness, B/E - FSIDocument B6FS638-D15, RevisionIR, dated 21 November 2017, or later FAAaccepted revision.	This STC certifies structural provisions for the installation of aninterior reconfiguration as defined in B/E - FSI DocumentB6FS638-D41, Rev. C, Dated 24 October 2017 or later FAAapprovedrevision. The FAA must evaluate and provide additional approval for theinstallation of the interior to ensure it...	30/11/2017	Active	10063917
10063936	THEO SCHROEDER FIRE BALLOONS GmbH			SEE EASA APPROVED MODEL LIST	Installation of ADR compliant equipment for Worthington cylinders inaccordance with Schroeder Fire Balloons Document List TM60, Issue 1,dated 30 November 2017	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Schroeder Fire Balloons Document List TM60, Issue 1, dated30 November2017-Schroeder Fire Balloons AFM supplement “STCzu Worthington GasbehälternAnhang”, Ausgabe 1, Änderung 2, dated October 2017or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/12/2017	Active	10063936

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063941	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03161AT-D	GIV-X	Installation of a Custom Interior	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Gulfstream Aerospace Corporation Index List GC420008092, Revision C,dated 10 November 2005, or later FAA approved revision.	Descriptive data pertaining to this design change are consideredinadequate for duplication in other products.This approval is limited to only the installation made in GulfstreamGIV-X, Serial Number 4024.This STC does not permit manufacturing of parts for multipleinstallations.The following STCs areE...	04/12/2017	Active	10063941
10063950	SABENA TECHNICS BOD			A330-323	A330 Air Caraibes cabin and system modificationThis modification consists in rearranging the cabin layout by installingnew passenger seats (for economy and premium economy sections),refurbishing already installed ones (business section) and reconfiguringcabin partition (galleys, curtains, floor path...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, ref: MDL-S-00-4126 issue A, dated 28 November 2017;- Aircraft Flight Manual Supplement, ref: AFMS-F3058-00-031 revision 1,dated 27 October 2017;- Instructions for Continued Airworthiness, ref : ICA-F3058-00-009 issueA, dated 17 November 2017;- Airworthiness Limitation Supplement,...	The following modification must be concurrently embodied with thismodification:- STC 10014507 Revision 2– Floor Pathmarking installation (or later EASAapproved revision).	01/12/2017	Active	10063950
10063956	HAECO CABIN SOLUTIONS, LLC		FAA STC ST00431AT	767 SERIES	Installation of Collins SAT-906 SATCOM System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TIMCO Master Data List Number MDL-01186, Revision D, dated 25 May 1997or Page Avjet Master Drawing List 94-04, RevisionB, dated 25 February1994, or later FAA approved revisions.Page Avjet Report No. PR-94-108, dated 16 March 1994<(>,<)>"Continual Maintenance Inspection Requirements".	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/12/2017	Active	10063956
10063969	B/E AEROSPACE, Inc.		FAA STC ST03663AT	CL-600-2D24 (RJ SERIES 900) CL-600-2C10 (RJ 700,701,702) CL-600-2B19 (RJ SERIES 100)	Installation of an Artex C406-2 Emergency Locator Transmitter (ELT) intoa Bombardier Regional Jet100, 200, 440, 700, 701, 702, 705 and 900 Series Aircraft and associatedhardware.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Regulations at the latest amendment 25-0 through 25-12425.23, 25.561, 25.571, 25.601, 25.603, 25.611, 25.899, 25.1301, 25.1309,25.1351, 25.1353, 25.1357, 25.1431, 25.1529A...	- Master Drawing List 2-46336-001<(>,<)> Revision D<(>,<)> dated 2 June2010 or later FAA approved drawing revisions.- Instructions for Continued Airworthiness (ICA), EMTEQ EngineeringDocument No. 2-46336-905, Rev. B, dated 21 June 2010<(>,<)> or later FAAaccepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/12/2017	Active	10063969
10063971	BUTLER NATIONAL CORPORATION		FAA STC ST02230SE	SEE FAA AML	The installation of dual Garmin GTX-33ES Mode-S transponders and singleor dual Garmin GTN 650/750 panel mounted navigation and globalpositioning system (GPS) units,or dual Garmin GTX-335R and/or GTX-345R Mode-S transponders and singleor dual Garmin GTN 650/750/625/725 panel mounted navigation and GP...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installed in accordance with Butler National Corporation's master datalist (MDL) as specified on AML ST02230SE; operated in accordance withButler National Corporation's airplane flight manual supplement (AFMS)as specified on AML ST02230SE;and maintained in accordance withInstructions for ContinuedS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	05/12/2017	Active	10063971

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10063974	BUTLER NATIONAL CORPORATION		FAA STC ST02455SE	SEE FAA AML	Installation of Dual Garmin GTX-3000 Transponders. GDL-88 AutomaticDependent Surveillance-Broadcast (ADS-B(In) with Wide Area AugmentationSystem (WAAS) Global Positioning System (GPS) sensor and Flight Stream210 Bluetooth Connectivity installed for ADS-S(Out) Compliance.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Butler National Corporation's Master Data List (MDL) as specified on AMLST02455SE. Maintained in accordance with ButlerNational Corporation'sInstructions for Continued Airworthiness (ICA) as specified on AMLST02455SE. Operated In accordance with Butler National Corporation'sAirplane Flight Manual S...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	05/12/2017	Active	10063974
10063978	AIRWORK & HELISEILEREI GmbH	REV. 2		EC635 T3 EC635 P2+, EC635 P3, EC135 T3 EC135 T2, EC135 T2+, EC635 T2+ EC135 P3, EC135 T1, EC635 T1 EC135 P1, EC135 P2, EC135 P2+	Y-rope for double load hook on a EC135 Human External CargoRev. 2: Transfer of STC to AirWork & Heliseilerei GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 Amendment 3:27.27; 27.301; 27.303; 27.305; 27.321; 27.337; 27.571; 27.603; 27.605;27.609; 27.610; 27.613; 27.625; 27...	- MDL-201212573 Rev NC, dated 15/08/2017.- Declaration of Compliance DOC-201212573 Rev NC, dated 01/12/2017.- ICA-201212573 Rev NC, dated 29/06/2017.	Applicable to EC135 helicopters with Dual External Cargo Hook as perEASA Approval Number R.C.01667, and related FMS 9.2-47.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or re...	19/03/2019	Active	10063978
10063983	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04229AT	737-800/-900 737-300/-400/-500/-600/-700	Installation of an International Communications Group (ICG) IRIDIUMSatellite Communications System on B737-300/-400/-500/-600/-700/-800/-900 series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 214184-MDL, Revision C, dated 6 October2015 orlater FAA approved Revision.FAA approved Airplane Flight Manual Supplement for Avionics SupportGroup 214184-FMS dated 13 October 2015 or later approved revision.Instructions for Continued Airworthiness Document 214184-ICA Revision B,...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/12/2017	Active	10063983
10063991	BOMBARDIER Inc.	REV. 1	TCCA STC SA17-80	CL-600-2B19 CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	EASA validation of Transport Canada STC SA17-80 at Issue 2.Modification to Water Line Heater Wiring.Modification to be completed in accordance with B/E Aerospace Ltd.Modification Data Summary Number L404000 Revision A or later approvedrevision.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification to be completed in accordance with B/E Aerospace Ltd.Modification Data Summary Number L404000 Revision A.For Instructions for Continued Airworthiness, refer to Bombardierdocument BAS63058024 Revision 1.or later revisions of the above listed documents approved by EASA inaccordance with t...	See those of original Transport Canada STC SA17-80.The Issue 1 of Transport Canada STC SA17-80 was originally validatedthrough EASA approval 10063991 (initial revision) on 07th December 2017.Prior to installation of this design change it must be determined thatthe interrelationship between this desi...	15/02/2018	Active	10063991
10063999	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	777-200	Gogo 2KU - Structural Provisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AMOC to FAA Airworthiness Directive 2012-07-06<(>,<)>or later revisions of the above listed documents approved by EASA.S21.MDL-1387 issue 1.	This STC only approves the installation of the structural provisions forthe later installation of the antenna and radome. The installation ofthe antenna and radome and the loads they induce in the structuralprovisions and the aircraft structure are not covered by this STC andwill be the subject ofP...	08/12/2017	Active	10063999

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064000	ROCKWELL COLLINS, Inc.	REV. 3	FAA STC SA01848WI	SEE FAA AML DATED 03.07.2024 SEE FAA AML	Modification of a Rockwell Collins Global Positioning System (GPS)installationRev. 1: Update of GPS-4000S to resolve software issues.Rev. 2: Correction of “Limitations/Conditions”section.Rev. 3: The software embedded in the GPS-4000S has been updated toaddress several OPRs and COS-40 resulting in t...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	(1) AML RCA-0392, Revision B, dated 3 July 2024;(2) Instructions for Continued Airworthiness (ICA) RCA-0394, Revision Bas specified by AML RCA-0392, Revision B;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedu...	(1) Prior FAA approved installation of a Rockwell Collins GPS-4000S,P/N: 822-2189-001/-002/-003/-004/-005/-006/-007/-010/-011/-100/-101, isa prerequisite to this STC; (2) The STC is valid for aircraft types and models approved by EASA andlisted on the FAA AML No. RCA-0392, Revision B, dated 3 July 20...	21/11/2024	Active	10064000
10064001	ROCKWELL COLLINS, Inc.	REV. 3	FAA STC ST01833WI	SEE FAA AML	Modification of a Rockwell Collins Global Positioning System (GPS) installationRevision 1 updates the GPS-4000SRevision 2: The software embedded in the GPS-4000S has been updated toaddress several OPRs and COS-40 resulting in the top-level part numberchange to 822-2189-102. There are no hardware chan...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	(1) AML RCA-0324, Revision B, dated 2 July 2024<(>,<)>(2) Instructions for Continued Airworthiness (ICA) RCA-0319, Revision Bas specified by AML RCA-0324, Revision B<(>,<)>(3) Modification Instructions RCA-2703, Revision B, dated 22 February2024<(>,<)>(4) Drawing Index RCA-325, Revision D, dated 20o...	(1) Prior FAA approved installation of a Rockwell Collins GPS-4000S,P/N: 822-2189-001/-002/-003/-004/-005/-006/-007/-010/-011/-100/-101, isa prerequisite to this STC. (2) The STC is valid for aircraft types and models approved by EASA andlisted on the FAA AML No. RCA-0324, Revision B, dated 2 July 20...	12/12/2024	Active	10064001
10064008	PMV ENGINEERING			A321-253N/-271N/-272N A321-213/-231/-232/-251N A321-111/-112/-131/-211/-212 A320-231/-232/-233/-251N/-271N A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	ADSB-OUT installation on A320 family.The change consists ofa transponder replacement or upgrade for DO-260Bcompliance,the installation of a dedicated ADS-B fail annunciator, awiring between the GNSS receiver and the Transponder, and a wiringbetween the Transponder and the Annunciator.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List AVI-01430-MDL-R01, dated 11 Dec. 2017.Aircraft Flight Manual Supplement AVI-01430-AFMS-R00, dated 04 Aug. 2017.Instructions for Continued Airworthiness AVI-01430-ICA-R01, dated 06Oct. 2017or later revisions of the abovelisted documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2017	Active	10064008
10064009	AIRBORNE TECHNOLOGIES GmbH			P.68R "VICTOR"	STC-AT-115 Additional NPAS ModificationsDetails of the installed mission equipment can be found in the AFMS Doc.No STC-115-0-AFM	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI F-01, Lithium battery installations (rechargeable)The following paragraphs of CS 23, Amendment 4:CS 23.29, CS 23.301, CS 23.303, CS 23.305, CS 23....	Change Dossier, Doc. No. STC-AT-115, Rev. 2Aircraft Flight Manual, Doc. No. STC-115-0-AFM, Rev. 1Aircraft Maintenance Manual, Doc. No. STC-115-0-AMM, Rev. 2Installation Instruction, Doc. No. STC-115-0-II, Rev. 1or later revisions of the above listed documents approved by EASA.	The following changes must be accomplished on the affected aircraftprior to the incorporation of STC-AT-115.EO-AT-095 Aircraft Preparation – Airborne Technologies GmbHEASA Approval No.: 10055442Step BEO-AT-098 NPAS Mission Equipment Installation – Airborne TechnologiesGmbHEASA Approval No.: 10063960...	12/12/2017	Active	10064009
10064010	KLM ENGINEERING & MAINTENANCE			A330-303	Cabin Reconfiguration of KLM A330-303Replacement of Business Class seats, installation of monuments,modification of In-Flight Entertainment System, replacement of décorlaminates, curtains and carpet and related changes to cabin furniture toaccommodate new Business Class cabin layout.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, KLM Report MDL-013437, Revision 02, dated 7-Dec-2017.-Instructions for Continued Airworthiness, KLM Report ICA-333-13437,Revision ORG, dated 23-Oct-2017	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/12/2017	Active	10064010

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064011	S4A SOLUTIONS FOR AVIATION, S.L	REV. 3		CL-600-2B16 (604 VARIANT)	SATCOM Aviator 350 installation and mechanical installationof flGA-5001 antenna	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Rev. 1:- 60436-HDK01 Flight Manual Supplement Edition 2or later revisions of the above listed document (s) approved by EASAsystem.- 60436-SB001 Service Bulletin Edition 2- 60436-RPT02 Master Drawing List Edition 2- 60436-HDK02 Maintenance Manual Supplement Edition 2.Rev. 2:Installed in accordance wit...	Rev. 1: CL-600-2B16(604 Variant) Aircraft MSN 5416 & 5552.Rev. 2: This design change is limited to the mechanical installation ofthe IGA-5001 antenna.Prior to installation of thischange/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously install...	10/03/2022	Active	10064011
10064016	JET AVIATION AG			GIV-X, GV-SP FALCON 900EX (F900EX) FALCON 7X FALCON 2000EX	Wireless Data Loader Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:,,- Special Condition (s): CRI F-31 Security Protection of Aircraft andNetworks.- The following paragraph(s) ata later amendment: CS-25.301, 307, 561,789, 831, 869, 899, 1...	Master Data List: JBSL-M-00888MDL-01 Issue 02;CertificationCompliance Sheet: JBSL-M-00888CCS-02 Issue 02;Aeroplane Flight Manual Supplement: JBSL-M-00888AFM-01 Issue 01,JBSL-M-00888AFM-02 Issue 01;Instructions for Continued Airworthiness:JBSL-M-00888ICA-01 Issue 01;or later revisions of the above...	This STC is limited to the models - versions/ variants:Dassault Aviation F900EX EASy, F900DX, F900LX, F2000EX EASy, F2000DX,F2000LX, F2000LXS, F2000S, F7X;Gulfstream GIV-X, GV-SPPrior to installation of this design change it must be determined thatthe interrelationship between this design change andp...	12/12/2017	Active	10064016
10064033	DELTA ENGINEERING CORPORATION	REV. 4	FAA STC ST03432NY	777-300ER 777-200LR 777-200	Installation of an Intelsat 2Ku Cabin Connectivity SystemRev.1: Added 777-200/-200LR modelsRev.2: Amendment to the installation of a Gogo 2Ku Cabin System on theBoeing 777-200/-200LR/-300ERRev.3: Amendment updates the 2Ku system from the utility Bus to the Main115AC busRev. 4: addresses a major chan...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-102 Non-rechargeable Lithium BatteryInstallationsThe following paragraph(s) at a later amendment: CS 25.853 and CS 25.869at Amendment 4The requ...	- Master Data List 0143-10303-2435<(>,<)> Revision AK<(>,<)> dated 23July 2024<(>,<)>- Airplane Flight Manual Supplement Ref. 0643-10304-2435 Rev. “-”, dated9 October 2017<(>,<) >-Instructions for Continued Airworthiness Ref. 0743-10305-2435, Rev D,or later revisions of the above listed document(s) b...	Operational approval to use T-PED’s must be obtained separately fromthis STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwort...	10/09/2025	Active	10064033
10064045	TELEDYNE BATTERY PRODUCTS		FAA STC SR00831DE	407	Installation of Teledyne Battery Products Gill LT Valve-Regulated LeadAcid (L T-VRLA), P/N 7407-28, battery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Teledyne Battery Products Document No. TD34-8-20, Master Data List,Installation of Teledyne Battery Products P/N 7407-28, Revision IR dated26 October 2016, FAA approved 1 December2016 or later FAA approvedrevision.Instructions for Continued Airworthiness (ICA), Document No. TD34-8-03,Revision NC da...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Installation is for the Bell 407, except serials...	14/12/2017	Active	10064045
10064046	TELEDYNE BATTERY PRODUCTS		FAA STC SA00797DE	525, 525A, 525B, 525C 525	Installation of Teledyne Battery Products PIN 7638-44T Lead-Acid Battery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Document No. TD34-4-02, Master Drawing List, Revision IR dated 16 May2016 or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Document No. TD34-8-01,Revision A dated 7 December 2015, FAA accepted 7 December 2015<(>,<)> orlater FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/12/2017	Active	10064046

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064048	TELEDYNE BATTERY PRODUCTS		FAA STC SA00867DE	PC-12/47E PC-12/47 PC-12/45 PC-12	Installation of Teledyne Battery Products Valve-Regulated Lead-Acid(VRLA), P/N 7638-44, battery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Teledyne Battery Products Document No. TD74-1-01, Master Drawing List,Pilatus PC-12 Teledyne Battery installation, Revision IR dated 24 June2017, FAA approved 30 June 2017 or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Document No. TD 74-8-02,Revision IR dated 22 June...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/12/2017	Active	10064048
10064056	IKHANA GROUP, LLC	REV. 2	FAA STC SA02649LA	DHC-6 SERIES 400 DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100 DHC-6-100/-200/-300/-400	Installation of Max-Viz 2300 Enhanced Vision SystemRev. 1: Name Change from "Ikhana Group Inc." to "Ikhana Group LLC."	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	IKHANA Aircraft Services Installation Drawing List ER218- 1209, RevisionNC, dated 15 May 2017, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement, Document No. EV-6-1-A,Revision "IR", dated 21 August 2017, or later FAA approved revision.The Instructions for Continued Airwo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/06/2021	Active	10064056
10064057	AEROCLUBUL ROMANIEI			IS-28B2	IS 28B2 TBO increase.Increasing TBO from 1200 flight hours / 7500 landings to 1400 flighthours / 8400 landings in accordance with Aeroclubul Romaniei documentSB-IS-28B2-AR-03, at Revision 2, dated 25 October 2017.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight and Maintenance Manual edition 2A / 1977, pages atamendmentno. 30: 0.2.2, 0.2.3, 26, 26.1, 36, 37;- Flight and Maintenance Manual edition 3 / 1978, pages at amendment no.44: 0.2.4, 0.3.Z.1, 6.9, 6.9.1, 6.10, 6.14, 6.15;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/12/2017	Active	10064057
10064059	DIAGNOSTIC SOLUTIONS INTERNATIONAL,		FAA STC SR02630LA	AS 350 B2 AS 350 B1	Installation of Honeywell Model 15175VXP Health Monitoring System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Diagnostic Solutions International Master Drawing List, Document Number25715, Rev. "A", dated 15 December 2016, or later FAA approved revision.Instructions for Continued Airworthiness (ICA) 860-25711, Rev. "A",dated 30 January 2017, or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/12/2017	Active	10064059
10064060	TELEDYNE BATTERY PRODUCTS		FAA BASIC STC ST00796DE	SEE FAA APPROVED MODEL LIST	Installation of Teledyne Battery Products P/N 7638-44T Lead-AcidBattery.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Document No. TD34-4-01, Master Drawing List, Revision IR dated 04 March2016 or later FAA approved revision.Instructionsfor Continued Airworthiness (ICA) are required to be madeavailable at installation, refer to AML ST00796DE for model specific ICAdocument.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	14/12/2017	Active	10064060
10064070	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-31T (CHEYENNE/ CHEYENNE II) PA-31T2 (CHEYENNE IIXL) PA-31T1 (CHEY. I/ CHEYENNE IA) PA-31P (PRESSURIZED NAVAJO) PA-31P-350 (MOJAVE)	Installation of one or more of the following antennas:- Single Garmin GA35 GPS antenna.- Single L-3 Communications NY-164 antenna.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 23.29; 23.301(a); 23.303; 23.305(a); 23.305(b); 23.307(a); 23.337 (a)(1); 23.365 (a);23.365(b); 23.365(d); 23.561 (a); 23.571...	- Master Documents List ASR-2017-055-MDL-01-00, dated 22/11/17;- Instructions for Installation ASR-2017-055-IFI-10-00, dated 20/11/17;or later revisions of the above listed documents approved by EASA.Instructions for continued Airworthiness ASR-2017-055-ICA-11-00, dated22/11/17.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/12/2017	Active	10064070

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064073	airplus engineering GmbH	REV. 2		PA-46-350P	Installation of Diversity Antenna.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-ACNS.D.ELS. 060,CS-ACNS.D.ELS.065.The requirements for environmental protection and the associatedcertified noise and/...	- Master Document List MD-2099-000000, Issue 3.- Description of Modification DE-2099-000000, Issue 2.- Means of Compliance List MO-2099-000000, Issue 2.- Maintenance Manual Supplement MM-2099-000000, Issue 3or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This modification is only applicable to aircraft, which have beenmodified with the DLX Jetprop conversion STC (EASA STCNo. 10016000).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change...	10/02/2021	Active	10064073
10064078	DRF STIFTUNG LUFTRETTUNGG EMEINNUETZIGE AG			EC135 T2+, EC135 P2+	Installation of two GTN 650 COM/NAV.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27, Amendment 3:CS 27.1, CS 27.21, CS 27.25, CS 27.27, CS 27.29, CS 27.251, CS 27.303,CS 27.305, CS 27.307, CS 27.561,2...	- Flight Manual Supplement for GTN 650 and MD41 System SPIFR/DPIFR – SBAS, FMS 10-DRF-036, Revision 8 dated 28 November 2017<(>,<)>or later revisions of the above listed documents approved by EASA.- Certification Program, CP-135-34-60-00001, Ausgabe 7.- Master Document List, MD-135-34-60-00002, Ausga...	- SMD 45 Modification / Retrofit to P/N C19267YA02 (NVG WAAS compatiblenew generation) has to be installed prior to this change.- This change does not include the check/approval of NVIS capability.- Suitable NAV and COMM antennas must havebeen previously installed.Prior to installation of this desi...	15/12/2017	Active	10064078
10064080	DIAGNOSTIC SOLUTIONS INTERNATIONAL,		FAA STC SR02535LA	MBB-BK 117 C-2 MBB-BK 117 C-1	Installation of Honeywell Model 15175 VXP Health MonitoringSystem onAirbus Helicopters Deutschland, Model MBB-BK 117 C-1 and MBB-BK 117 C-2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved Master Drawing List, Document Number 25698, Revision "NC"dated 20 March 2015, orlater FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/12/2017	Active	10064080
10064081	TELEDYNE BATTERY PRODUCTS	REV. 1	FAA STC SR00842DE	EC135 T1, EC135 T2, EC135 T2+ EC135 P1, EC135 P2, EC135 P2+,	Installation of Teledyne Battery Products Gill LT Valve-RegulatedLead-Acid (LT-VRLA), P/N 7638-44, battery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Teledyne Battery Products Document No. TD70-8-03, Master Drawing List,Installation of Teledyne Battery Products P/N 7638-44, Revision IR dated4 March 2017 , FAA approved 7 March 2017 or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Document No. TD 70-8-02,Revision NC da...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/12/2017	Active	10064081
10064109	P3 ENGINEERING GMBH			767-300	767-300 First Class Reconfiguration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Declaration of Compliance of P3 Engineering GmbH Ref. P3-AAB01-DCO-0001Issue A- Certification Programme Compliance Summary Ref. P3-AAB01-CPR-0001 IssueC dated 14 December 2017-Master Document List Ref. P3-AAB01-MDL-0001 Issue A Dated 15 December2017or later revisions of the above listed documents ap...	None	18/12/2017	Active	10064109
10064110	SABENA TECHNICS BOD			A330-323	French Blue – G12 Ultra High Comfort Attendant Seats (UHCAS)installationThis modification installs 1 new UHCAS on the galley G12, andre-arranges the aft area by re-routing curtainrails, adding placards,and relocating emergency equipment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, ref MDL-S-25-4128, Issue A, dated 17 November 2017- Instruction for Continued Airworthiness, ref: ICA-F3043-25-042, Issue Adated 06 November 2017or later revisions of the above listed documents approved by EASA.	None	18/12/2017	Active	10064110

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064114	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			A320-231,-232,-233 A320-211,-212,-214,-215,-216	Title: A320 ELT InstallationDescription: Installation of a fixed ELT system type Kannad 406AFcomposed of an ELT antenna, an ELT remote control panel inside theflight deck and the ELT unit itself	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):CRI F-01, Non-rechargeable Lithium BatteryThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels ofu...	Engineering Order (MDL), Doc. No. EO_M390001001_IMA_01 082017, Rev. 0Aircraft Flight Manual Supplement, A32F Kannad 406AF ELT Installation,Doc No. AFS_M390001001_IMA_08 082017, Rev.0Instructions for Continued Airworthiness, A320 ELT Installation, Doc.No. ICA_M390001001_IMA_01 082017, Rev. 1or later re...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/12/2017	Active	10064114
10064118	GOODRICH CARGO SYSTEMS (UNITED TECHNOLOGIES AEROSPACE SYST		FAA STC ST02546CH	747-400F 747-200F, 747-300, 747-400, 747-100, 747-200B, 747-200C,	For all models except 747-400F:Install Power Drive Unit forMain Deck Cargo Handling SystemsFor 747-400F:Install Goodrich Freighter Common Turntables (FCT) for Main Deck CargoHandling Systems	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For all models except 747-400F:Drawing List Report Number MD2510, Revision C, dated 12 March 2008, orlater FAA approvedrevisions.For 747-400F:Master Data List MD2896, Revision A,dated 13 December 2013, or laterFAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.An FAA approved cargo interior, compatible withb...	18/12/2017	Active	10064118
10064120	AIRBUS S.A.S.	REV. 1		A340-642, A340-643	MOD CJ2153 INSTAL OF A340 2KU ANTENNARevision 1 introduces additional pre-modification configurationcondition for installation of a GoGo 2KU antenna on an aeroplane thatrequires relocation of Emergency Locator Transmitter (ELT) antenna(s) inaccordance with Airbus major modification MOD 208045.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-1301-004-Vibration and buffetingon Large Antenna.The requirements for environmental protection and the associatedcertified noise and...	- Certification Summary Reports ref. AIS-AJA-17073 Issue 4 (Initial) &AIS-AJA-18077 Issue 4 (Major Change);- Modification Approval Sheet ref. MAS CJ2153 Issue 3;- Maintenance Planning Document ref. MPD-S MOD CJ2091, dated 01 December2017;or later revisions of the above listed documents approved by E...	This approval is valid only for the following A340-642 and A340-643 MSN:0601, 0960, 0993, 1017, 1079, 1122.Modificationof an aeroplane in accordance with the Revision 1 of STC10064120 is allowed, provided that prior to GoGo antenna installationthe aeroplane is modified in accordance with Airbus SB(...	23/01/2019	Active	10064120
10064129	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 2		EC135 T2+, EC135 T3 EC135 T1, EC135 T2 EC135 P2+, EC135 P3 EC135 P1, EC135 P2	INSTALLATION OF FLIGHTCELL DZMX WITH OPTION FOR WiFi	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM Supplement 2109331-AM, Issue 1<(>,<) >Engineering Order & Certification Program 2109331-EO, Issue 1.Certification Documents 2109331 DOC, Issue 1.or later revisions of the abovelisted documents approved/accepted underthe EASA system	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/07/2020	Active	10064129
10064134	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		DORNIER 228-212 DORNIER 228-202 DORNIER 228-201 DORNIER 228-200 DORNIER 228-101 DORNIER 228-100	AeroStretcher® System Installation for Dornier 228 Series Aircraft, inaccordance with GVH Aerospace modification ref GVH-7528-01-MOD-01 Issue1 dated 13.12.2017.Rev 1: Transfer of STC from GVH Aerospace Ltd - United Kingdom, to GVHAerospace(Ireland) Limited	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with GVH Aerospace modification refGVH-7528-01-MOD-01 and Master Document List GVH-7528-01-MDL-01, Issue 1,dated 12.12.2017;Operation in accordance withGVH Aerospace Pilot’s Operating HandbookSupplement ref GVH-7528-01-FMS-01, Issue 2, dated 15.11.2017;Instructions for Co...	This modification is limited to the AeroStretcher® system installationand use only, the installation and use of other medical equipment orinstallations will require separate approvals.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repa...	26/01/2021	Active	10064134

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064136	ASI INNOVATION			EC135 T2+	Installation of multipurpose container POD on EC135 multi-function armmount.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplément Manuel de Vol“Installation d’un POD SC02 sur bras multifonction EC135 T2+& T2e”,document ASI-AFM-0405, Rev 1<(>,<)>or later revisions of the above listed documents approved by EASA.- Certification Programme ASI-CP-0405-01, Rev 1.- SD-STC Data List ASI-SDL-0405-01, Rev 4.- Master Drawing-...	This STC approves the installation of the multipurpose container only.Any further installation in- or outside of the container requiresfurther approval.The installation is limitedto rotorcraft with ‘Standard’ landing gear.Prior to installation of this design change it must be determined thatthe int...	19/12/2017	Active	10064136
10064143	ARCHEION HOLDINGS, L.L.C.	REV. 3	FAA STC ST04215AT	737-800/-900/-8/-9 737-300/-400/-500/-600/-700	Installation of Avionica sat.LINK MAX with optional Personality Module(avPM) in the Cabin Compartment overhead, and optional avRDC MAX QAR inthe EE Bay.Existing aircraft systems optional interface/integration include theFlight Deck Audio System (i.e. Pilot Crew Headsets), MCDUs [or IDUs],ACARS CMU &...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List 142335-MDL, Revision N, dated 19 September2018 orlater FAA approved revisions, to provide 2 Iridium SATCOM ATS Voicechannels, 1 Iridium SATCOM ATS Datalink FANS 1/A+ Data channel for nightDeck use (CPDLC at RCP240 & ADS-Cat RSP 180) & 1 optional AOC Voicechannel for cabin crew use....	This approval should not be extended to other aircraft of this model onwhich previously approved modifications are incorporated.Prior to installation of this design change it mustbe determined thatthe interrelationship between this designchange and any otherpreviously installed design change and/a...	15/02/2019	Active	10064143
10064146	SABENA TECHNICS BGC	REV. 2		A321-271N/-271NX/-272N/-272NX A321-253N,-272N A321-253N/-251NX/-252NX/-253NX A321-213,-231,-232,-271N,-251N A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A321-111,-112,-131,-211,-212 A320-253N/-271N/-272N/-273N A320-231,-232,-233,-271N,-251N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A320-211,-212,-214,-215,-216 A319-171N A319-131/-132/-133/-151N/-153N A319-131,-132,-133 A319-111/-112/-113/-114/-115 A319-111,-112,-113,-114,-115 A318-111/-112/-121/122 A318-111,-112,-121,-122	CABIN AIR RECIRCULATION FILTER CARTRIDGE REPLACEMENT ON AIRBUS SINGLEAISLERev.1: Applicability list extended.Rev. 2: Correction of Applicability list.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Instructions for Continued Airworthiness, AEROCONSEIL document No.0784-01-A-ICA Rev 03- Master Data List, AEROCONSEILdocument No. 0784-01-A-MDL, Rev 05,dated 15 November 2022orlater revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2022	Active	10064146
10064158	DASSAULT FALCON JET CORPORATION		FAA ST01785WI	MYSTÈRE-FALCON 900	Validation of FAA STC ST01785WI.Installation of a Data LinkCommunication System supporting Future AirNavigation System(FANS 1/A+).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-9122-001: Flight Recorders and Data LinkRecording.- The following paragraph(s) at a later amendment: CS25 Amendment 18 ofCS 25.1301, CS 25.14...	- Master Document List No. EDOC-018246, Revision B, dated 24 September2015<(>,<)>- Airplane Flight Manual Supplement Document No EDOC-018239, Revision B,dated 24 September 2015<(>,<)>- Instructions for Continued Airworthiness Document No.:EDOC-018238Revision: B, dated 24 September 2015<(>,<)>or lat...	- This STC is applicable to Dassault Aviation Mystère-Falcon 900aeroplanes S/N 001 through 178.- Installation of this STC requires installation of EASA STC 10060212and approved Satellite Communication system that meets the requirementsof AC 20-140B.Prior to installation of this design change it must...	20/12/2017	Active	10064158

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064192	AIRBUS DEFENCE AND SPACE S.A.	REV. 12		A330-243	Conversion of A330-200 Series A/C to A330 Multi Role Transport Tanker(MRTT) FAF (French Air Force).Revision 1 of this approval add the ETOPS capability of the basicaircraft to theMRTT FAF aircraft.Revision 2 of this approval introduces ALS Part 2 Supplements for MRTTSTCS based on A330 ALI Issue19.A...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-3999-002: Partial Empty Cabin, in interest ofGovernmental Service; D-4318-002: Air Medical Servicethe following paragraph(s) at a late...	- “CONVERSION DEFINITION A330 MRTT FAF STC” document Ref.TAE-FF-DT-170082 Issue A.Airplane Flight Manual and Weight andBalance Manual:- Airplane Flight Manual Supplement “EASA APPROVED MODEL A-330 MRTT FAFAIRPLANE FLIGHT MANUAL" document Ref. TAE-FF-DT-150059.- “Limitations of Weight and Balance Ma...	Approval of this STC is limited to compliance to selected CertificationStandards as defined in A330 MRTT FAF CRI A-01.A330 MRTT RAAF CRI G-01 defines in particular restrictions relating toMaintenance Tasks and Airworthiness Limitations, Ref. JAR 25.571a(3) and25.1529.Therefore, the following limitat...	25/03/2025	Active	10064192
10064196	SCANDINAVIAN AVIONICS DESIGN ApS			GV, GV-SP	Civil Aircraft Missile Protection System (CAMPS) Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Refer to CRI F-01.- The following paragraph(s) at a later amendment: CS 25 Amendment 2forthe requirements affected by this change.The requirements...	- Aircraft Flight Manual, Doc Ref: 2105396-AM-2;- ContinuedAirworthiness for CAMPS Installation, Doc Ref: 2105396-CA;or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2017	Active	10064196
10064207	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			737-800	Cabin Reconfiguration with Introduction of New G1, G2, G4B Galleys andGalley Inserts	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	C0020-CEP-04 Certification Programme, dated 21/12/2017	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2017	Active	10064207
10064210	DELTA ENGINEERING CORPORATION	REV. 6	FAA STC ST03431NY	777-200/-200LR/-300ER	Installation of a gogo 2Ku Radome (with Demod option)Rev.1:Added model 777-200Rev.2: Update of Master Data ListRev.3: Amendment to the installation that includes a structural repairmanual update and resolution to an FAA airworthiness directiveRev.4: Update of Master Data List revision and Structura...	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements:Equivalent Safety Finding(s): CRI B-101 "Vibration / buffetingcompliance criteria for large external antennainstallation"The following paragraph(s) at a later amendment: CS...	Master Data List Ref. 0143-10287-2434 Rev. AV, dated 23 July 2024<(>,<) >Airplane Flight Manual Supplement Ref. 0643-10290-2434 Rev B, dated 20April 2018<(>,<) >Instructions for Continued Airworthiness Ref. 0743-10288-2434 Rev. Q< (>,<)>EWIS Instructions for Continued Airworthiness Ref. 0743-10289-2434...	This STC includes the validation of the Alternative Method of Compliance(FAA Ref. 782-17-2796 or782-18-862) to AD 2012-07-06.AD 2013-07-11 must be accomplished prior to installation.For additional limitations refer to the ICA Ref. 0743-10288-2434 andEWIS ICA Ref. 0743-10289-2434Prior to installation...	10/09/2025	Active	10064210
10064224	S4A SOLUTIONS FOR AVIATION, S.L			P2006T	P2006T10 Aerial Photography CameraInstallation of the mission system Leica City Mapper (Sensor Unit andits respective server, cockpit display and operator stand and display)in Tecnam P2006T aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-P2006T10-HDK01 Issue 4 FMS MISSION EQUIPMENT IN P2006Tor later revisions of the above listed documents approved by EASA.-P2006T10-CPL01 Certification Plan Issue 4-P2006T10-CHK01 Compliance Check List Issue 2-P2006T10-SB001 Service Bulletin Issue 5-P2006T10-HDK02 Maintenance Manual Issue 3-P2006T10-...	The following OEM modification must be implemented in the aircraft priorto carry out this design change.a) MOD2006/204 Installation of converter boxb) MOD2006/307 Enlarged hatch for Leica installationc) MOD2006/310 Removal of baggage compartment windowsd) MOD2006/309 Alternative combination of seats...	22/12/2017	Active	10064224
10064226	SCANDINAVIAN AVIONICS DESIGN ApS			SEE EASA APPROVED MODEL LIST	DUAL TRANSPONDER SYSTEM ADS-B UPGRADE IN PART 25 AIRCRAFT (VARIOUS)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amendment 2 for the affected requirementsTherequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	-Aircraft Flight Manual, Doc Ref: 2105994-AM A-Aircraft Flight Manual, Doc Ref: 2105994-AM B-Continued Airworthiness, Doc Ref: 2105994-CA Aor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/12/2017	Active	10064226

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064251	B/E AEROSPACE, Inc. - FSI		FAA STC ST02550SE	787-9	First class seat upgrade on Boeing Model 787-9 series airplanes.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. B/E Aerospace, Inc. - FSI (B/E - FSI) Master Drawing List (MDL) B7FS707-D01, Revision B, dated 15 November2017 or later Federal AviationAdministration (FAA) approved revisions. 2. The Supplemental Instructions for Continued Airworthiness,B/E - FSIDocument B7FS707-D15, Revision B, dated 14 November...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/01/2018	Active	10064251
10064253	KNSI AVIATION ENGINEERING LIMITED		CAA UK RESPONSIBILITY	A330-343	Flush doubler installation for Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	KNSI Instructions for continued airworthiness 17K204-ICA-001-3.RRevision 03 dated 13 December 2017<(>,<)>or later revisions of the above listed documents approved by EASA.KNSI Master Document List 17K204-MDL-001-5.R Revision 05 dated 13December 2017.	This modification de-modifies GOGO 2KU antenna systems installed inaccordance with EASA STC 10058732.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce no...	08/01/2018	Active	10064253
10064257	AEROCET, INC.		FAA STC SA01257SE	SEE FAA AML	Installation of Aerocet Model 3400 floats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aerocet Drawing List listed on FAA AML SA01257SE, dated 28 August 2003,or later FAA approved revision.Aerocet, Inc. Service Manual and Instructions for ContinuedAirworthiness, Document Number A-10031, Revision 0, dated 12 August 2003 or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for those aircraft types and m...	08/01/2018	Active	10064257
10064258	ANDERSON, THOMAS RICHARD		FAA STC SA01087SE	185D, 185E, A185E, A185F 185, 185A, 185B, 185C 180H, 180J, 180K 180D, 180E, 180F, 180G 180, 180A, 180B, 180C	Installation of titanium main landing gear assembly	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA approved Master Drawing List XP010101MDL, Revision D,dated 14August 2014	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/01/2018	Active	10064258
10064259	AVIATION TECHNICAL SERVICES, Inc.		FAA STC ST02577SE	A321-253N, A321-271N, A321-272 A321-231, A321-232, A321-251N A321-211, A321-212, A321-213 A321-111, A321-112, A321-131 A320-271N A320-232, A320-233, A320-251N A320-215, A320-216, A320-231 A320-211, A320-212, A320-214 A319-132, A319-133 A319-114, A319-115, A319-131 A319-111, A319-112, A319-113	Installation of vortex generators	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Aviation Technical Services Master Data List (MDL) 780001-MDL-001,Revision A, dated 12 October 2017, or later Federal AviationAdministration (FAA) approved revision.2. Instructions for Continued Airworthiness (ICA) 780001-ICA-001,Revision A, dated 7 November 2017, or later FAA-accepted revision....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/01/2018	Active	10064259

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064260	KNSI AVIATION ENGINEERING LIMITED		CAA UK RESPONSIBILITY	A340-642	Flush doubler installation for Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. ,,The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval....	KNSI Instructions for Continued Airworthiness 17K205-ICA-001-3.RRevision 03 dated 13 December 2017< (>,<)>or later revisions of the above listed documents approved by EASA.KNSI Master Document List 17K205-MDL-001-4.R Revision 04 dated 13December 2017.	This modification de-modifies GOGO 2KU antenna systems installed inaccordance with EASA STC 10058069.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce no...	08/01/2018	Active	10064260
10064261	FTI ENGINEERING NETWORK GmbH			525, 525A, 525B	ADS-B Out for Citation Jet.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23 Amdt 0: 23.1,23.21, 23.29, 23.601, 23.603, 23.605, 23.607, 23.771, 23.1301, 23.1309,23.1322, 23.1351, 23.1357, 23.13...	- Installation according to the document “Installation Instructions forADS-B Out for Cessna 525, 525A and 525B” – F23-001-EO17-1589 Issue 02,dated 29/11/2017;- Operation accordingto the document “Aircraft Flight Manual Supplementfor ADS-BOut for Cessna 525, 525A and 525B” – F20-EO17-1589 Issue 02,...	Limited to the aircraft serial numbers:- Model 525: SN: 0600 to 0701- Model 525A: SN: 0300 to 0524- Model 525B: SN: 0001 to 0056, 0058 to 0415.Prior to installation of this designchange it must be determined thatthe interrelationship between this design change and any otherpreviously installed desi...	09/01/2018	Active	10064261
10064263	ARCHEION HOLDINGS, L.L.C.		FAA STC ST03967AT	SEE FAA AML REV. C	Installation of an Avionica, Inc. avWiFi wireless router systemThe system provides 3 modes of operation installations: Secure device todevice Wi-Fi Wireless connectivity in the aircraft cabin during allphases of flight (CWLU Mode), or WiFiconnectivity to the Gate TerminalWiFi Router on the ground v...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List 120890-MDL, Revision Q, dated 3 October2017 orlater FAA approved revisions.2. FAA approved Airplane Flight Manual Supplement for Archeion HoldingsLLC, 120890-AFMS-1, -3 and -4, Revision A, dated 20 October 2016, or120890-AFMS-5, Revision IR, dated 22 June 2017, or 120890-AFMS-2,...	The avWiFi system must be deactivated via the flight deck WiFi switchduring Autoland landing on the B777.Refer to limitations in Airworthiness Directive AD 2014-20-06 and PolicyStatement PS-ANM-25-13; this WiFi installation is not compatible withB777 and B737NG aircraft equipped with Honeywell Phase...	09/01/2018	Active	10064263
10064268	SCANDINAVIAN AVIONICS DESIGN ApS			525	GA35 GPS ANTENNA INSTALLATION in accordance with Scandinavian AvionicsEngineering Order 2106348-EO, Issue 3, dated 17 November 2017.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Scandinavian Avionics Engineering Order 2106348-EO, Issue 3, dated 17November 2017< (>,<)>or later revisions of the above listed documents approved by EASA.Scandinavian Avionics Maintenance Manual Supplement 2106348-MM, Issue 2,dated 15 November 2017.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/01/2018	Active	10064268
10064269	FOKKER SERVICES B.V.			A321-253N, A321-271N A321-231, A321-232, A321-251N A321-211, A321-212, A321-213 A321-111, A321-112, A321-131 A320-251N, A320-271N A320-231, A320-232, A320-233 A320-215, A320-216 A320-211, A320-212, A320-214 A319-131, A319-132, A319-133 A319-114, A319-115 A319-111, A319-112, A319-113 A318-121, A318-122 A318-111, A318-112	Introduction of ADS-B OUT capabilities by addition of DO-260B capableATC transponder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance Record Report CRR-0353 Issue 1, dated 21/12/2017;Aircraft Flight Manual Supplement A320FAM-XXX-AFM-S-001 Rev.2, dated08/12/2017;MMEL Supplement A320FAM-XXXMMEL-S-001 Rev.2, dated 08/12/2017;FCD Supplement A320FAM-XXXFCD-S-001 Rev. 2, dated 08/12/2017;or later revisions of the above listed...	Prior to installation of this repair it must be determined that theinterrelationship between this repair and any other previously installeddesign change and/ or repair will introduce no adverse effect upon theairworthiness of the product.	09/01/2018	Active	10064269

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064282	AVIDYNE CORPORATION	REV. 1	FAA STC SR00387BO	R66 R44, R44 II R22, R22 ALPHA R22 BETA, R22 MARINER	Installation of Avidyne 700-00182-XXX IFD5XX and 700-00179-XXX IFD4XXSeries Integrated Flight Displays (IFD)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The CertificationBasis for the original product as amended by thefollowing additional or alternative airworthiness requirements:Regulations at the latest amendment 23-0 through 27-4727.1(a)(b), 27....	1. Avidyne Corporation Master Document List (MDL), DocumentNumberAVIFD-495, Revision 02, dated 6 December 2017, or later FAA approvedrevision.2. Avidyne Corporation Rotorcraft Flight Manual Supplement (RFMS) Document Number 600-00324-000, Revision 01, FAA approved on 12 December2017, or later FAA ap...	This STC only covers the installation of the IFDs, the IFD trays, andassociated wiring. It does not cover the installation of antennas,annunciators, or switches that may be required to make a fullyfunctional system.Prior to installation ofthis design change it must be determined thatthe interrelati...	17/01/2018	Active	10064282
10064296	CERT WORKS, LLC	REV. 1	FAA STC SR00812DE	SEE FAA AML	Installation of Honeywell Sky Connect Tracker III system.Rev 1: Addition of Bell 429 to the FAA Approved Model List (AML) andupdate of document numbers.	The certification basis for parts changed or affected by the changesince the reference date of application<(>,<)>March 16, 2016, is based upon 14 CFR Part 27, Amendment 27-1 through27-47:14 CFR Sections: 27.301 Amdt. - ; 27.303 Amdt. -; 27.305(a) Amdt. -; 27.307(a) Amdt. 27-26; 27.337(a) Amdt. 27-26;...	Document No. CW0603-1006, Master Installation Drawing List,Part 27 AMLSky Connect Tracker III Installation, Revision Adated 29 August 2016 orlater FAA approved revisions.Parts manufactured in accordance with Document No. CW0604-1004,Master Installation Drawing List, Document No. CW0603-1006, PartS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	29/11/2019	Active	10064296
10064297	BOMBARDIER Inc.		TCCA SA17-93	CL-600-2B19 (SPE. ED. SE ONLY) CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	EASA Validation of Transport Canada STC SA17-93 at issue 1:PortableOxygen Bottle Bracket Replacement.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification to be completed in accordance with B/E Aerospace Ltd.Modification Data Summary Number L585000 Revision NC,dated September22nd, 2017 or later approved revisions;Maintenance to be completed in accordance with Bombardier Instructionsfor Continued Airworthiness BAS63058026, Basic Issue, da...	See those of original Transport Canada STC SA17-93.Prior toinstallation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produ...	11/01/2018	Active	10064297
10064301	STARLING AEROSPACE LIMITED		CAA UK RESPONSIBILITY	737-500	New Cabin Configuration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 Amendment 18: CS-25.23; CS-25.25; CS-25.27; CS-25.29; CS-25.301;CS-25.302; CS-25.303; CS-25.305; CS-25.307; CS-25.561;...	Starling Aerospace Limited Master Document List No. B737-MDL-0022 Issue4.	Restricted to MSN 24919.	11/01/2018	Active	10064301
10064303	WIPAIRE Inc.		FAA STC SA04053CH	T206H 185E, A185E, A185F 185, 185A, 185B, 185C, 185D	Installation of Hartzell "Trailblazer" Composite Propeller in accordancewith Wipaire, Inc. Installation Drawing as listed on AML No. SA04053CH,issued November 23, 2016, or later FAA approved	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	-Wipaire, Inc. Installation Drawing 1008738, Revision B, issued 12/1/15-Wipaire, Inc. Installation Drawing 1009159, Revision A, issued 10/17/16-Wipaire, Inc. POHSA04053CH-1, Revision IR, issued 12/23/15-Wipaire, Inc. POHSA04053CH-3, Revision IR, issued 11/21/16or later revisions of the above listeda...	The installation for models 185/ A/B/C/D/E, A185E/F is limited toconfigurations with floats only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadver...	11/01/2018	Active	10064303

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064307	HOVERFLY DIVISIONE SAM S.R.L			AS 350 B3	FreeFlight RA-4000 Radar Alt. Install.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-27 Amendment 4 dated30.11.2016:§27.21, 25, 27, 29, 45.§27.301, 303, 305, 321, 337, 351, 561, 571.§27.601, 603, 605, 609...	RFM Supplement FMS/ HDS/001/00 dated 30.11.2017<(>,<)>or later revisions of the above listed documents approved by EASA.- Programma Di Certificazione Cod.: CP/ HDS/001/00.- Technical Compliance Cod.: TR/HDS/ 001/00.- Limiti Operativi di Peso e Foglio di Carico e Centraggio Cod.:WB/HDS/ 001/00.- Istruzio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/01/2018	Active	10064307
10064315	BOMBARDIER Inc.		STC SA17-83	BD-700-1A11 BD-700-1A10	Installation, Underwater Locator Device	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):F-10052103-1 at Issue 1 – NonRechargeable Lithium Battery InstallationsThe requirements for environmental protection and the associatedcertified nois...	Installation to be completed in accordance with B/E Aerospace Inc.Modification Data Summary L552000 Revision NC, andForInstructions for Continued Airworthiness, refer to BAS67058056Revision Basic Issueor later revisions of the above listed documents approved by EASA inaccordance with the TechnicalB...	See those of original Transport Canada STC SA17-83Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the produc...	12/01/2018	Active	10064315
10064325	TYLER CAMERA SYSTEMS		FAA BASIC STC SR01449LA	SEE FAA APPROVED MODEL LIST	Installation of cargo rack.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA Approved Tyler Camera Systems Master Drawing List No. ASCR-001,Revision N/C, dated 20 January 2003.FAA Approved Rotorcraft Flight Manual Supplement No, CR-RFM-001,Reissued 6 August 2004, or later FAA Approved Revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	15/01/2018	Active	10064325
10064359	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED	REV. 3	UK.STC.00076 REV. 2	MBB-BK117 D-3 MBB-BK117 D-2	Wales Air Ambulance mission configuration including NVIS, ref.BD/ 133-100-01.Revision 1 is to introduce a NVIS-certifiedright-hand configurationoption for the A800 Trakka searchlight and additional LED Landing Lightsmounted on fore and aftskid cross tubes (validation on CAA UK STCUK.STC.00076 Rev.R...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:For the original STC:CS 29 Amendment 3:CS 29.1 (a), CS 29.21 (a), CS 29.29 (a) (b), CS 29.49 (a) (1) (3), CS29.51 (a) (1) (...	MDL/133-025, Issue 10;DL/ 133-099 Drawing List, Issue 07;FMS/133-002 Flight Manual Supplement, Issue 06;FMS/133-026 Flight Manual Supplement for RH Trakka & Additional LandingLights, Issue 01;ICA/133-016 Instructions for Continued Airworthiness, Issue 07;ICA/133-027 Instructions for Continued Airwort...	This STC is not applicable to the MBB-BK117 D-2m variant.Rotorcraft modified by this design change employs Night VisionImagingSystem lighting, commonly named NVIS lighting, whichhas been certifiedto ensure the aircraft is compatible withNight Vision Goggles (NVG).For this reason, any deviation fr...	09/09/2024	Active	10064359
10064374	MAGELLAN SERVICES COMPANY		FAA STC ST10952SC	737-700	Installation of an active ventilation system for lavatories, galleys,and non-essential equipment throughout the aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:Part 25 of the Federal Aviation Regulations as amended by Amendments25-1 through 25-77 with the exceptions listed below (Am...	1. Single fan:- Master Documents List (MDL) 08101002 Revision A dated 9 September2009, or later FAA approved revisions.- Instructions for Continued Airworthiness (ICA), 08101003, Rev. A,dated 30 September 2009, or later FAAaccepted revision.2. Dual fan:- Master Documents List (MDL) 09101002 Revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/02/2018	Active	10064374

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064378	DASSAULT AIRCRAFT SERVICES (DAS)			MYSTÈRE-FALCON 900 FALCON 900EX	Validation of FAA STC ST02974NY.Installation of Data Link Communications System with Honeywell Primus2000 Avionics System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-9122-001: Flight Recorders and Data LinkRecording.the following paragraph(s) at a later amendment: CS25 Amendment 18 of CS25.1301, CS 25.1457 a...	- Master Data List No. F9XW-D0048-005, Revision C, dated 17August 2015<(>,<)>- Airplane Flight Manual Supplement Document No F9XW-D0048-150, RevisionIR, dated 21 July 2015<(>,<)>- Instructions for Continued Airworthiness Document No.: F9XW-D0048-155Revision A, dated 03 August 2015< (>,<)>or later re...	- This STC requires as prerequisite, the installation of anapprovedSatellite Communication System that meets the requirements of AC20-140B.Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designa...	18/01/2018	Active	10064378
10064402	SEBALD LUFTFAHRTTECH NISCHER BETRIEB(LTB)			NIMBUS-4M	TM-S01 „Lenkbares Spornrad N4M“ / SB-S01 „Steerable tail wheel N4M“Lenkbares Spornrad für NIMBUS-4M / steerable tailwheel for NIMBUS-4M	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Technische Mitteilung (TM S01) “Lenkbares Spornrad N4M“-Service Bulletin (SB-S01) „Steerable tail wheel N4M“-Ergänzung zum Flug- und Wartungshandbuch Nimbus-4Mor later revisions of the above listed documents approved by EASA.-Zeichnungsliste TM-S01 – lenkbares Spornrad Nimbus-4M, Ausgabe10.01.201...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/01/2018	Active	10064402
10064409	VOYAGEUR AEROTECH, Inc.		TCCA STC SA17-51 ISSUE 1	DHC-8-102/ DHC-8-103/ DHC-8-106	DHC-8 Package Freighter.The installation reconfigures the aircraft interior from a passengercabin to a Class E Cargo Compartment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DCS 15-2700 Rev NC, “DHC-8-100 Package Freighter”, dated 2 May 2017.AFMS 15-2700 Rev B “Airplane Flight Manual Supplement”, dated 10 May2017.MMS 15-27100, Rev A “Maintenance Manual Supplement”, dated 24 April2017, including airworthiness limitation tasks in Chapter 4-00-00or later revisions of the a...	The aircraft is limited to cargo operations.Prior to installation of this repair it must be determined that theinterrelationship between this repair and any other previously installeddesign change and/ or repair will introduce no adverse effect upon theairworthiness of the product.	19/01/2018	Active	10064409
10064418	365 AEROSPACE DDS LIMITED	REV. 1		737-300	New Cabin ConfigurationRev. 1: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDS Ltd	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amendment 18:25.1529<(>,<)> 25.1701<(>,<) > 25.1703<(>,<)> 25.1705<(>,<)> 25.1707<(>,<)>25.1709<(>,<)> 25.1711<(>,<)> 25.1713<(>,<)> 25.1715<(>,<)> 25.1717<(>,<) >25.17...	365 Aerospace Flight Manual Supplement No. FMS-0277-001 Revision A365 Aerospace Instructions for Continued Airworthiness No. ICA-0277-001Revision Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.365 Aerospace Limited Master Data List No. MDL-0277 Revision A...	Restricted to MSN 25402Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/08/2019	Active	10064418
10064419	AIRBUS S.A.S.	REV. 2		A321-231 A321-211 A320-214 A319-112	MOD CJ2096 - VIASAT KA BAND Antenna Installation on Single AisleThis STC covers the installation of structural provisions for theinstallation of the VIASAT KABAND antenna, betweenFr58 and Fr63,between Str4 and Str4’.The STC also covers the installation of the radome, the antenna, theadapter plate w...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-AIS-AJA-18001 Issue 3 - STC 10064419 Major change Certification SummaryReport, dated 24/01/2018.-MAS CJ20 96 Issue 2,dated 24/01/2018	None	02/03/2018	Active	10064419

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064446	JET AVIATION AG	REV. 2		747-300, 747-400	KA Band Antenna Installation.The installation is composed of 3 configurations:CONF1: KA Band Structural ProvisionCONF2:KA Band Antenna Systems InstallationCONF3: KA Band Antenna Installation (CONF1 and CONF2 combined)Revision 1 to extend the applicability to the 747-300 with a differentradome insta...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI C-102-005 Vibration / buffeting.The requirements for environmental protection and the associatedcertified noise and/ or emissions levelsa...	- JBSL-M-00507MDL-01 Issue 05- JBSL-M-00507MDL-02 Issue 06- JBSL-M-00508MDL-01 Issue 06- JBSL-M-00507AFM-01 Issue 01- JBSL-M-00507ICA-01 Issue 02- JBSL-M-00508ICA-01 Issue 05or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/04/2020	Active	10064446
10064449	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	AW139 AB139	Removal of RFM Limitations for HF	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement S21.FMS-0127, Issue 1or later revisions of the above listed documents approved by EASA.-Certification Programme No. S21.PROG-1277, Issue 2, dated 19.11.2016-Compliance Record No. S21.COMP-1277, Issue 2, dated 19.11.2016	Applicability is limited to AW139 Serial Numbers: 31203, 31208 and 31209	23/01/2018	Active	10064449
10064455	Q.C.M. DESIGN GmbH			HAWKER 800XP	Delta Certification of a GPS/WAAS Sensor & Antenna Installation for thesupport of the Approved EASA STC 10058529.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation and Maintenance in accordance with Master Document ListRH80-QCM34-001-M0-MDL, Initial Issue, dated 27th November 2017<(>,<)>or later revisions of the above listed documents approved by EASA.	- Limited to aircraft serial number 258536.- The EASA STC 10058529 is a prerequisite for the installation of thisSTC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change andany otherpreviously installed design change and/ or repair w...	23/01/2018	Active	10064455
10064456	LUFTHANSA TECHNIK AG			A340-541	RTAF Cabin Retrofit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI C-102 “Vibration/ buffetingcompliance criteria for large external antenna installation”.The requirements for environmental protection an...	- Supplemental Type Definition Document, Ref. STDD25-17/20MIssue 01Rev. 01;- Compliance Record List, Ref. CRL25-17/20MIssue 01 Rev. 00;- Instructions for Continuous Airworthiness, Ref. A-00-17/72-ICA, Issue01 Rev. 00;- Airplane Flight Manual, Ref. A-00-17/72-AFM Issue 01, Rev. 00;or later revision...	- Applicable only to A340 MSN 698.- Requires the installation of the non-electrical Floor Path MarkingSystem (EASA STC 10013964).- Refer to AFM, Ref. A-00-17/72-AFM Issue 01, Rev. 00, Section 2“Limitations” and ICA, Ref. A-00-17/72-ICA, Issue 01 Rev. 00, Section 4“Airworthiness Limitation Section”.P...	23/01/2018	Active	10064456
10064457	AERO SEATS AND SYSTEMS, INC		FAA STC SR09343RC	412	Installation of Aero Seats and Systems, Inc., Life Raft DeploymentSystem (LRDS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval	1. Aero Seats and Systems, Inc., LRDS Manufacturing DrawingListASI-800, Rev D, dated 26 May 2005 or later FAA approvedrevision. 2. Aero Seats and Systems, Inc. Installation Manual, ASI-800 LRDS BHTI412 Helicopter, ASI-800-101, Rev E, dated 26 May 2005 or later FAAapproved revision.3. Instructions f...	Single or Dual LRDS installation is determined by the installer, basedupon the approved passenger seating configurationof the helicopter, toprovide a rated life raft capacity which accommodates all personnel.Prior to installation of this design change it must be determined thatthe interrelationship...	26/01/2018	Active	10064457

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064470	ALAMO ENGINEERING GmbH	REV. 2		FALCON 900EX (F900EX)	CMS/IFE, SatCom & LED Cabin Lighting.This STC installs the following cabin system: Rockwell Collins “Venue”CMS/IFE System, True North “Optelity Pro” Iridium Phone System,Mid-Continent universal AC Cabin Outlets with dual USB Charger, B/EAerospace cabin Up-wash and Downwash LED Lighting and B/E Aeros...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Document List No. MDL118Z001, Revision B, dated 24th January2018;- Airplane Flight Manual Supplement Document No AFMS020E043Z0001,Revision A, dated 15th January 2018;- Instructions for Continued Airworthiness Document No.:AMMS020E043Z0001 Revision: A, dated 18th January 2018;or later revisi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10064470
10064473	GARMIN DEUTSCHLAND GmbH	REV. 1		SEE EASA APPROVED MODEL LIST	Installation of Garmin G5 Electronic Flight Instrument.Rev.1 changes the STC holder from Garmin (Europe) Limited to GarminDeutschland GmbH.	a. The certification basis for parts not changed or not affected by thischange remains unchanged from the original approval.b. The certification basis for parts changed or affected by this changeis FAR Part 23:23.301(a), 23.303, 23.305(a)(b), 23.307(a), 23.337(a)(b),23.561(a)(b)(3), 23.561(e), 23.60...	Installation in accordance with Garmin Master Drawing List (MDL) 005-01112-01, Revision 8, dated October 18, 2017.Instructions for Continued Airworthiness (ICA) as listed in above MDL.Operate in accordance with Garmin G5 Airplane Flight Manual Supplementas listed in above MDL.For EASA STC 10064473 Ap...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/02/2019	Active	10064473
10064475	AIRBUS HELICOPTERS, Inc.	REV. 2	FAA SR09509RC	AS 350 B3	Installation of Garmin GRA 5500 Radar Altimeter System.Rev.1: adds configuration 350A82-1656-02Rev. 2: Correction of typos	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Helicopters, Inc. Drawing List 350A82-1797 Rev. IR dated 8November 2017;Instructions for Continued Airworthiness (ICA) 350MMS-041 Rev. IR dated22 September 2017;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revis...	For configuration 350A82-1656-01, this STC is applicable toAS350B3aircraft in the Post Mod AMS 07.4723 only.For configuration 350A82-1656-02, this STC is applicable to AS350B3aircraft in the Post Mod ECP 07.4961 only.Prior to installationof this design change it must be determined thatthe interrel...	19/09/2023	Active	10064475
10064476	RAMM AEROSPACE INC.		TCCA SH16-38	R44, R44 II	Installation of Replacement Floor Covering.Replacement floor covering kits consisting of carpet, utility flooringand floor trays.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MDL-RH044-1009 Master Document List Revision F dated December 06, 2017or later accepted revision.ICA-RH044-1009 INSTRUCTIONS FOR CONTINUED AIRWORTHINESS Revision 4<(>,<)> dated June 27, 2017 or later accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/01/2018	Active	10064476
10064478	RAMM AEROSPACE INC.		TCCA SH17-1	R44, R44 II	Replacement Seat Cushion/Backrest Installation & Interior Accessories.Installation of replacement seat cushion for pilot/co-pilot/pax, as wellas interior accessories.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MDL-RH044-1011 MASTER DOCUMENT LIST Revision D, dated November 14, 2017or later accepted revision.ICA-RH044-1011 INSTRUCTIONS FOR CONTINUED AIRWORTHINESS Revision 3,dated November13, 2017 or later accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/01/2018	Active	10064478
10064482	RAMM AEROSPACE INC.		TCCA STC SH16-48	R44, R44 II	Installation of Replacement Headliner and Bulkhead Covering.Replacement Headliner and Bulkhead covering kits.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MDL-RH044-1010 Master Document List Revision C, dated November 08, 2017or later accepted revision.ICA-RH044-1010 INSTRUCTIONS FOR CONTINUED AIRWORTHINESS Revision 1,dated March 28, 2017 or later accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/01/2018	Active	10064482

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064487	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	737-900, 737-900ER 737-600, 737-700, 737-800	Honeywell ADS-B Transponder Upgrade from TRA67A to TRA100B.Revision 1: including the interface with Rockwell Collins GLU920 andGLU925 MMR's as additional approved GPS position sources for ADS-Bcompliance. In addition, the ICA were amended.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): F-129: ADS-B Out Extended SquitterInstallation, issue1.The requirements for environmental protection and the associatedcertified noise and/ or emissions l...	- AFMS H4AFMS047 rev 2- ICA H4AICA003 issue 3- ModificationSummary Sheet H4A1875 issue 5or later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/06/2019	Active	10064487
10064494	KNSI AVIATION ENGINEERING LIMITED		CAA UK RESPONSIBILITY	A330-243	A330 – CABIN RECONFIGURATION.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List reference 16K303-MDL-001-16.R (Revision 16).	None.	26/01/2018	Active	10064494
10064495	DASSAULT AIRCRAFT SERVICES (DAS)		FAA ST03586NY	FALCON 2000EX FALCON 2000	Validation of FAA STC ST03586NY.Installation of a Data LinkCommunication System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-2122-001: Flight Recorders and Data LinkRecording.The following paragraph(s) at a later amendment: CS25 Amendment 18 of CS25.1301, CS 25.1457 a...	- Master Data List No. F2MW-D0036-005, Revision A, dated 03June 2016<(>,<)>- Airplane Flight Manual Supplement Document No F2MW-D0036-150, RevisionIR, dated 03 June 2016<(>,<)>- Instructions for Continued Airworthiness Document No.: F2XW-D0036-155Revision IR, dated 09 May 2016<(>,<)>or later revisi...	This STC requires as prerequisite, the installation of EASASTC 10048395Rev.1 and the installation of an approved Satellite Communication Systemthat meets the requirements of AC 20-140B.Prior to installation of this design change it must be determined thatthe interrelationship between this design ch...	26/01/2018	Active	10064495
10064496	LUFTHANSA TECHNIK AG	REV. 4		737-800 737-700 737-700, 737-800	Provisions for large KA band antenna and systems installation.Rev. 1: Removal of DTA-related limitationsRev. 2: Correction of models listRev. 3: Improvement of design; ICA: updateof inspection program afternew F<(>&<)>DT analysisRev. 4: Correction and clarification of ICA.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): B-101"Vibration / buffeting compliancecriteria for large external antenna".The requirements for environmental protection andc...	- Supplemental Type Definition Document STDD53-16/20M issue04 rev 00- Airplane Flight Manual Supplement A-00-16/94-AFMIssue 01 rev 03- Instructions for continued airworthiness A-00-16/94-ICA Issue 05 rev00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Installation on aircraft models only that satisfy the configurationsand criteria defined in document AUZ01-23 and AUZ02-53-EI-003.- This change constitutes Alternative Method OfCompliance for EASAadopted FAA AD 2013-08-15, 2013-08-16 and 2013-19-23 for the areasaffected by this modificationPriort...	01/03/2024	Active	10064496
10064499	DASSAULT FALCON JET CORPORATION		FAA STC ST04044CH	MYSTÈRE FALCON 50 (MF50)	Validation of FAA STC ST04044CH.Installation of a FANS 1/A +CPDLC System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI F-5122-001: Flight Recorders and Data Link RecordingCS25 Amendment 18 of CS 25.1301, CS 25.1457 and CS 25.1459The requirements for environmental p...	-StandardAero Master Data List No. 1029262, Revision D, dated 22 March2016<(>,<)>-Airplane Flight Manual Supplement Document No 1029700, Revision D,dated 22 March 2016<(>,<)>-Instructions for Continued Airworthiness Document No.: 1029735,Revision B, dated 25 January 2016<(>,<)>or later revisions ofa...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/01/2018	Active	10064499
10064501	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST03420NY	EMB-145LR/ EMB-145MP EMB-145/ EMB-145EP/ EMB-145ER EMB-135BJ/ EMB-135ER/ EMB-135LR	Installation of a Business Class Commuter Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03420NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Delta Engineering Master Data List 0166-10046-2411 RevisionF dated 18June 2019 or later FAA approved revisions to Delta Engineering MasterData List previously listed.The Instructions for Continued Airworthiness<(>,<)> Electrical WiringInterconnect System Instructions for Continued Airworthiness and...	For Configuration 2 and 3 of the Master Data List EASA STC 10055137 isrequired.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon th...	11/07/2019	Active	10064501

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064504	GAMA AVIATION (ENGINEERING) LIMITED	REV. 1	CAA UK RESPONSIBILITY	R66	Aspen EFD1000H.This change removes the current analogue Attitude Indicator (AI) andDirectional Gyro (DG) and replaces them with the Aspen EFD1000H.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement (RFMS), Aspen EFD1000H,GAEL-1501RFMS-01, Issue 3 dated 22 January 2018or later revisions of the above listed documents approved by EASA.Certification Plan (CP) – including project description, GAEL-1501CP-01,Issue 1 dated 10 January 2018.Master Data List (MDL), GA...	Signal coupling to autopilot (if installed) is not covered by this STC.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwor...	31/01/2018	Active	10064504
10064506	ADAC LUFTFAHRT TECHNIK GmbH			EC135 T1/ EC135 T2/ EC135 T2+ EC135 P1/ EC135 P2/ EC135 P2+	Installation of a Dual GTN650/750 System into the EC135 helicopter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement EC135-07530-025-MFS, Revision 0or later revisions of the above listed documents approved by EASA.Master Document List, EC135-07530-001-LMD-00, Revision 0.Instructions for Continued Airworthiness, EC135-07530-023-MMS-00,Revision 0.Compliance Summary EC135-07530-027-RCS-00, R...	This certificate does not include NVIS, SBAS (including LPV) and P-RNAV.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	29/01/2018	Active	10064506
10064512	LUFTHANSA TECHNIK AG			737-700, 737-800	Activation of Ka-band in-flight connectivity system and in-cabindistribution system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document STDD23-17/02M Issue/Rev 1/0;- Airplane Flight Manual – Supplement A-00-16/95-AFM Issue/Rev 1/0;- Instructions for Continued Airworthiness Issue/Rev 4/0;or later revisions of the above listed documents approved by EASA.	- Only for activation of provisions certified by EASA STC 10064496.- Installation on aircraft models only that satisfy the configurationsand criteria defined in Description of Change AVE01-23 Rev. 5 or laterapproved revisions.Prior to installation of this design change it must be determined thatthep...	30/01/2018	Active	10064512
10064516	OUTERLINK CORPORATION		FAA STC SR00384BO	AW139 AB139	Installation of a Satcom and Flight Data Monitoring System KIT139-SAT-100.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:29-0 through 29-5529.29, 29.251, 29.301, 29.303, 29.305(a), 29.307(a), 29.337,29.561(b)(3)(c), 29.601(a) <(>,<)>29.603(b)(c), 29.605(a), 29.607, 29.609, 29.613, 29.619, 29....	Outerlink Corporation Master Document List (MCL), Document numberMDL139-SAT-100, Revision -, dated 8 November 2016 or later FAA approvedrevision.Operation must be in accordance with Outerlink Rotorcraft Flight ManualSupplement (RFMS), Document number FMS 139SAT001, Revision IR, FAAapproved on 27 Apr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/01/2018	Active	10064516
10064523	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		A320-214, A320-216	Airbus A320 - Installation of 180 Passenger Configuration.Rev 1: Transfer of STC from GVH Aerospace Ltd - United Kingdom, to GVHAerospace (Ireland) Limited	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): SC D-0306 Heat release and smoke densityrequirements to seat material.The requirements for environmental protection and the associatedcertified noise...	Major change summary and declaration of compliance GVH-6167-01-MOD-01.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/01/2021	Active	10064523

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064539	EXTEX ENGINEERED PRODUCTS INC		FAA PMA NO. PQ2203NM SUPP NO:4	369HM/ 369HS/ 500N/ 600N 369D/ 369E/ 369FF/ 369H/ 369HE	STC of EXTEX PMA E369D25501-9< (>,<)> (Coupling Tail Rotor Driveshaft – MD369 series).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA LAACO letter 140L-17-137 of May 19, 2017 enclosing EXTEX datapackage "EASA STC of an FAA PMA Critical Part per FAA-EASA TIP 5Revision 5 Reference E369D25501-9".	None.	31/01/2018	Active	10064539
10064542	BALLOONACY, LLC		FAA STC SB04407AT	SEE FAA AML REV. A	Installation of the DBI-III Omega	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List 5001, Revision B, dated 6 September 2017, orlater FAA approved revision.2. FAA Approved AirplaneFlight Manual Supplement, Drawing Number 5007,Revision IR, dated 6 September 2017, or later approved revision. 3. Instructions for Continued Airworthiness Document (ICA), DrawingNum...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	02/02/2018	Active	10064542
10064557	AIRBUS HELICOPTERS, Inc.		FAA STC SR09312RC-D	AS 350 B3 AS 350 B2	Installation of an Avidyne 610 or 615 Traffic Advisory System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing List 350A82-1780, Rev. H, dated 25 November 2015or later ODAapproved revision.2. For Avidyne 610- Rotorcraft Flight Manual Supplement 350FMS-177 dated 16 February 2009or later ODA approved revision.- Instructions for Continued Airworthiness 350MMS-020, revision - dated02 February 2009 or...	This STC is only applicable for post AMS 07-3274 helicopters.Prior to installation of this design change it must be determined thatthe interrelationship between this design changeand any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of...	02/02/2018	Active	10064557
10064558	AIRBUS HELICOPTERS, Inc.	REV. 1	FAA SR09508RC	AS 350 B3	Installation of a Garmin GTS 800 Traffic Advisory SystemRev. 1 adds the configuration 35 A82-1657-02.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:27.610 (a)(b)(c)(d) Amdt 27-46; 27.773 Amdt 27-50; 27.1309 (a)(c) Amdt27-46 and 27.1329 (f) Amdt 27.35.The requirements f...	- Airbus Helicopters, Inc. Master Drawing List (MDL) 350A82-1796 Rev. IRdated 06 December 2017.For the configuration 350A82-1657-01- Rotorcraft Flight Manual Supplement (RFMS) 350FMS-546, Rev IR dated 12January 2018- Instructions for Continued Airworthiness (ICA) 350MMS-040 Rev. IR,dated 01 December...	For the configuration 350A82-1657-01:- Aircraft must be AS 350 B3 post AMS07-4723 (TC G500H Installation).For the configuration 350A82-1657-02:- Aircraft must be AS 350 B3 Post ECP OP-4962.- Aircraft must include previous installation approval of the GTX 345(R) Transponder.Prior to installation of t...	25/01/2021	Active	10064558
10064559	AAR AIRCRAFT SERVICES		FAA STC ST04190CH	A330-243	Installation of Forward Left Hand, Right Hand, and Center Monuments.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AMR Master Data List, 31725CR003, Revision B, dated 5 March2017, orlater FAA approved revision.	AAR STC 10064797 must be concurrently installed.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	27/02/2018	Active	10064559

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064583	AIRBUS HELICOPTERS, Inc.		FAA STC SH7011SW-D	AS 350 B/ AS 350 B1/ AS 350 B2 AS 350 B3/ AS 350 BA/ AS 350 D	Installation of a Nightsun or Starburst Searchlight.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing List 355A82-1743, Revision BJ. 2. For Nightsun pre-AMS 07-3450 or Starburst, Rotorcraft Flight ManualSupplement 350FMS-026, revision 5 dated 21 May 1999 or later ODAapproved revision.3. For Nightsun post AMS 07-3450 Rotorcraft Flight Manual Supplement350FMS-535, revision A dated 23 June 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/02/2018	Active	10064583
10064584	AIRBUS HELICOPTERS, Inc.		FAA STC SR09311RC-D	AS 350 B2/ AS 350 B3	Installation of a BMS Video Downlink System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing List 350A82-1781, Rev. J, dated 24 November 2016or later ODAapproved revision.2. Rotorcraft Flight Manual Supplement 350FMS-529, Rev A, dated 16 June2016 or later ODA approved revision.3. Instructions for Continued Airworthiness 350MMS-031, Rev. -, dated 5January 2016 or later FTW AEG ac...	This STC is only applicable for post AMS 07-4280, AMS-07-3439, and AMS07-4654 helicopters.Prior to installation of thisdesign change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse eff...	05/02/2018	Active	10064584
10064585	AIRBUS HELICOPTERS, Inc.		FAA STC SR09495RC-D	MBB-BK117 C-2	Installation of IFR Single or Dual Pilot WAAS GPS Upgrade.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing List 145A82-8018, Rev. M dated 12 September 2013or later ODAapproved revision.2. For configuration 145A73-0054-01, Rotorcraft Flight Manual Supplement(RFMS) 117FMS-237Rev. B dated 20 September 2013 or later ODA approvedrevision.3. Instructions for Continued Airworthiness 145MMS-020, Rev...	Prior to or concurrently with installation of this STC, theTypeCertified Dual Pilot/ Single Pilot or Single Pilot Dual Garmin GNS 430Winstallation and Type Certificated MEGHAS part number C19267ZG-12 orC19267YA02 SMD-45 displays must be installed. This installation is notcompatible with Helicopter T...	06/02/2018	Active	10064585
10064586	AIRBUS HELICOPTERS, Inc.	REV. 1	FAA SR09498RC-D	EC 155 B1	Activation of Airbus Helicopters (formerly Eurocopter France) Provisionsof GPS with WAAS Vertical Guidance.Rev.1 of this STC is made to add the configuration 155A73-0021-02.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Drawing List 155A82-8010, Rev. B dated 29 July 2013- For 155A73-0021-01 configuration (dual Garmin GPS with 400W system): . Rotorcraft Flight Manual Supplement 155FMS-013, Rev. IR, dated19 Aug. 2013 . Instructions for ContinuedAirworthiness 155MMS-021, Rev. IRdated 16 May 2013- For 155A...	- For 155A73-0021-01 configuration (dual Garmin GPS with 400W system)<(>,<) > . this STC is limited to helicopters equipped with thefollowing:(a) Type Certified Dual Pilot/Single Pilot or Single Pilot, Dual GarminGPS-400WGPS/400W installation EC catalogue option 08-43056-00-C1:(b) Ty...	21/01/2021	Active	10064586
10064600	AIRBUS DEFENCE AND SPACE S.A.	REV. 5		A330-243	A330 MRTT ROKAF STCConversion of A330-200 Series A/C to A330 Multi Role Transport Tanker(MRTT) RoKAF (Republic of KoreaAir Force)Rev. 1 adds the ETOPS capability of the basic aircraft to MRTT RoKAFaircraft.Rev. 2 introduces ALS Part 2 Supplements for MRTT STCS based on A330 ALIIssue19.After the rel...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.0562 Initial Issue for affected areas by this STC;CS 25.0853 Initial Issue for affected areas by chang...	- “CONVERSION DEFINITION A330 MRTT RKAF STC” document Ref.TEA-FR-DT-180094 Issue A.- Airplane Flight Manual Supplement “EASA-APPROVED MODEL A330 MRTT ROKAFAIRPLANE FLIGHT MANUAL” document Ref. TEA-FR-DT-180020, Issue asreferenced in STC 10069541 AML TEA-FA-AW-190015.- ALS Part 1 Supplement “A330 MRT...	This STC only covers the installation of external aerodynamic devices(two underwing pods, boom, receptacle for refuelling, antennas,fairings, in case they are equipped with) with the associated structuralmodifications, the modification of some basic aircraft systems, theinstallation of some inoperat...	18/04/2023	Active	10064600

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064604	ALAMO ENGINEERING GmbH	REV. 1		GULFSTREAM G150	ADS-B OUT - Rockwell Collins Pro Line 21 Avionics on GULFSTREAM 150.Revision 1: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): CRI F-01, Continuity Requirements for ADS-B function.- The following paragraph(s) at a later amendment: CS-ACNS, InitialIssue:CS ACNS.D.ADSB. 001, CS ACNS.D...	Master Document List (MDL), Document No. MDL128Z001, Rev. B;AFM Supplement, Document No. AFMS016B345Z0001, Rev. B;MMEL Supplement, Document No. MMELS016B345Z0001, Rev. B;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10064604
10064609	SCANDINAVIAN AVIONICS DESIGN ApS			206L-1	Garmin single GTN 650 or dual GTN650/750 installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Subpart B Communication (COM) Section 1 of CS-ACNSInitial Issue, dated19.12.2013.The requirements for environmental protection and the associatedcertified noise and/ or e...	Operation in accordance with Scandinavian Avionics design AFMSupplement:- 2107136-AM A, Dual Garmin GTN 750/GTN 650 Initial Issue 6 dated07.Feb. 2018;- 2107136-AM B, Single Garmin GTN 650, Initial Issue 2 dated07.Feb. 2018;or later revisionsof the above listed documents approved by EASA.- Instruction...	Installation of this STC requires prior embodiment of the IFRconfiguration 206-705-001.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installeddesign change and/ or repair will introduce noadverse effect...	09/02/2017	Active	10064609
10064614	AIRBUS HELICOPTERS, Inc.		FAA STC SR09494RC-D	EC135 T2/ EC135 T2+ EC135 P2/ EC135 P2+	Installation of IFR Single or Dual Pilot WAAS GPS upgrade.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Drawing List 135A82-8024, Rev. P dated 31 March 2016 or later ODAapproved revision.2. Rotorcraft Flight Manual Supplement (RFMS) 135FMS-034 Rev. E dated 18May 2016, for Garmin GNS-430(A)W installations, or RFMS 135FMS-035 Rev.C dated 18May 2016, for Garmin GNS-530(A)W installations or later ODAa...	Prior to or concurrently with the installation of this STC,the TypeCertified Dual Pilot/Single Pilot or Single Pilot Dual Garmin GNS 430Winstallation, or FAA approved GNS 530W substitution(s) for the TypeCertified GNS 430W(s); and Type Certified MEGHAS part number C19267ZG-12SMD-45 display (s) mustT...	09/02/2018	Active	10064614
10064624	AIRBUS S.A.S.			A320-216 A320-214	MOD AI0009 - IBE A320 - ISPSS Activation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Approval Sheet, ref. doc. MAS n° AI0009, Issue1, dated24th January 2018.or later revisions of the above listed documents approved by EASA.Certification Summary Report ref. AIS-AJA-17109, Issue 2, dated24/01/2018.	None	13/02/2018	Active	10064624
10064630	IKHANA GROUP, LLC	REV. 3	FAA STC SA02642LA	DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of Pratt & Whitney Canada PT6A-27 engines rated at 620 SHP,Hartzell HC-B3TN-3D(Y)/T10282H (B)+0 propellers.Rev. 1: Name Change from "Ikhana Group Inc." to "Ikhana Group LLC".Rev. 2: Typo Correction	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. IKHANA Aircraft Services Drawing List ER218-2027, Revision B< (>,<)>dated 30 May 2017, or later FAA approved revision.2. IKHANA Aircraft Services Master Data List ER218-2016, Revision NC< (>,<)> dated 21 June 2017, or later FAA approved revision.	Installation of this STC does not allow increase in Max Gross Weight.This modification has been substantiated to be a non-acoustic change per14 CFR part 21.93 (b).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherprevi...	09/09/2021	Active	10064630
10064631	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		V35B (TC), G36, A36TC, B36TC F33C, S35, V35 (TC), V35A (TC) F33A 35-C33A, 36, A36, E33A, E33C	Installation of 3-blade constant speed propeller MTV-9-D/200-58 onTextron Aviation Inc. Bonanza Models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-36, Amendment 4FAR 36, Amendment 36-30This certificate/ approval involves a change to the requirements forenvironmental protection or a change to the certified noise or...	According to MT-Propeller Master Documentation List No. E-2934, Rev 0To be operated in accordance with MT-Propeller AFM-S Document No.E-2931, Rev 0or later revisions of the above listed documents approved by EASA.To be installed i.a.w. Installation Instructions Doc. No. E-2932, Rev 0,or later revisi...	According limitation section of AFM-SPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviouslyinstalled design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	16/02/2018	Active	10064631

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064641	B/E AEROSPACE, Inc.	REV. 1	FAA ST04358AT	767-200/ 767-300/ 767-300F 767-200, 767-300, 767-300F	Installation of the Rockwell Collins Automatic Dependent Surveillance – Broadcast (ADS-B) Out System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04358AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Drawing List (MDL) 2-171676-001, Rev. F dated 25 September 2018or later FAA approved revision.- Airplane Flight Manual Supplement for the Rockwell Collins AutomaticDependent Surveillance – Broadcast (ADS-B) Out System, 2-171676-805, RevIR dated 27 March 2017, or later FAA approved revision....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/07/2021	Active	10064641
10064656	GAMA AVIATION (ENGINEERING) LIMITED		CAA UK RESPONSIBILITY	B300, B300C, B200 B200GT, B200T B200C, B200CGT, B200CT	Gama Modification GAEL-1548 - Installation of two Garmin GPS AntennasGA-36 and GA-37.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23, Amendment 4 forthe areas affected by the change (for details see the CertificationPlan, GAEL-1548CP-01, issue 1).Th...	- To be installed according to GAMA Document GAEL-1548MDL-01<(>,<) >issue A, dated 26 January 2018;- To be maintained according to Instructions for Continued Airworthiness (ICA), GAMA Document GAEL-1548ICA-01<(>,<)> issue 1, dated 26 January2018;or later revisions of the above listed documents approve...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/02/2018	Active	10064656
10064675	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09615RC	505	Installation of Cargo Mirror Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List, Report No. AA-16083, Revision A, dated 9November 2017, or later FAA approved revision.2. Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-16081, No Revision, dated 25 July 2017, or later FAAaccepted revision.3. Aeronautical Accessories Rotorcraf...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/02/2018	Active	10064675
10064676	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09614RC	407	Installation of a 407 Imaging System Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List, Report No. AA-16063, Revision D, dated 21 July2017, or later FAA approved revision.2. Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-16068, No Revision, dated 17 May 2017, or later FAAaccepted revision.3. Aeronautical Accessories Rotorcraft Fl...	High skid landing gear required for installation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product...	15/02/2018	Active	10064676
10064678	FLYHT AEROSPACE SOLUTIONS Ltd.		TCCA SA13-02 REV. 03	737-700, 737-800 737-300, 737-400, 737-500	AFIRS 228 Automated Flight Information Reporting System Installation, inaccordance with FLYHT MDL 121-0075 Rev. F (for 737-300, 737-400,737-500) and FLYHT MDL 121-0065 Rev. AC (for 737-700, 737-800).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: FAR 25.1322 Amdt 25-38,FAR 25.1529 Amdt 25-54 (for 737-300, 737-400 and 737-500).The requirements for environmental protec...	737-300, 737-400, 737-500 - FLYHT AFMS 155-0016 rev C -FLYHT ICA 153-0068 rev D - FLYHT EWIS ICA 157-0016737-700, 737-800 - FLYHT AFMS 155-0013 rev E - FLYHT ICA 153-0055 rev L - FLYHT EWIS ICA 157-0007 rev Bor later revisionsof the above listed documents approved by EASA inaccordanceB...	- The aeroplane modified by this STC must be: - operated in accordance with the AFMS - maintained in accordance with the ICA- The scope of this STC modification does not approve the installationor connection to any type of Electronic Flight Bags (EFB) or PersonalElectronic Devise (PED), function...	15/02/2018	Active	10064678

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064679	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR01295AT-D	407	External Hoist Kits and Hoist Retrofit Kit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Aeronautical Accessories, Inc. Drawing List, Report No. AA-97005,Rev. H, dated 17 May 20062. For External Hoist Kit,Installation Instructions Report No.AA-97006, Rev. K, dated22 March 20043. For Hoist Retrofit Kit 407-998-001, Installation Instructions ReportAA-06055, No Revision, dated 16 May4...	For Hoist Retrofit Kit 407-998-001, installation of External Hoist Kitwith Hoist Assembly BL-16600-170 is required.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair wil...	15/02/2018	Active	10064679
10064681	MORSON PROJECTS LIMITED		CAA UK RESPONSIBILITY	HS.125 SERIES 700B HS.125 SERIES 700A HAWKER 900XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE.125 SERIES 800B BAE.125 SERIES 800A	Introduction of ADS-B Out functionality.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:FAR 25.1529 Amdt 54.FAR 25.1581 (a) & (b) Amdt 72.CS-ACNS Initial Issue (Subpart D Section 4).The requirements for environm...	Installation, Operation and Maintenance according to MorsonProjectsLimited Change Report MP0001A Issue 1, dated January 2018<(>,<)>or later revisions of the above listed documents approved by EASA.	Limited to aircraft equipped with Rockwell-Collins Pro Line21 or ProLine 2 avionics suites with the following equipment installed:1) Dual Rockwell Collins TDR-94D transponders (part number 622-9210-501or later)2) Wiring between the TDR-94D transponders, wiring for a cockpitannunciator, installation...	16/02/2018	Active	10064681
10064685	AIR AMBULANCE TECHNOLOGY GmbH	REV. 3		EC 175 B	EC175 EMS equipment installation.The change consists of different layouts (one or two patientconfigurations) and can include the following components: Medicalequipment carrier (MEC), Oxygen station, Stretcher (including footrest),Locker system.Reason for Revision 1: the following manuals/ documents h...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, Doc. No.: MDL-EC175-25-20-104.000-601 to 636 REV BFlight Manual Supplement, Doc. No.: FMS-EC175-EMS-000, Rev. 2Instructions for Continued Airworthiness, Doc. No.: ICA-EC175-EMS-000,Rev. 1Installation Manual, Doc. No.: IM-EC175-EMS-000Weight and Balance Manual, Doc. No.: WBM-EC175-E...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/12/2019	Active	10064685
10064698	365 AEROSPACE DDS LIMITED	REV. 3		A320-214 A319-133 737-9, 737-900, 737-900ER 737-8, 737-800, 737-8200 737-600, 737-700	Introduction of Donica Wi-Fi 6000 System.-Revision 1: Transfer of STC to DONICA Intl.-Revision 2: Transfer of STC to 365 AEROSPACE DDS LIMITED.-Revision 3: applicability list extended to models: 737-700/-8/-800/-8200/-9/-900/-900ER/-600	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:- CS25 at amdt. 20: 25.29, 25.301, 25.303, 25.305, 25.307, 25.321,25.561, 25.571, 25.601, 25.603, 25.605, 25....	Defined within Approved Model List (AML) document, Ref. AML-2076 IssueC dated 25 June 2024or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The system is not approved for CAT II/III approach flight phases.This design change does not approve the use of passenger portableelectronic devices. This remains the responsibility of the aeroplaneoperator.Prior to installation of this change/repair it must be determined thatthe interrelationship b...	23/07/2024	Active	10064698
10064703	STANDARDAERO ATLANTIC USA, INC.		FAA STC SR02492AK	EC 130 B4 AS 350 D AS 350 BA AS 350 B3 AS 350 B2 AS 350 B1 AS 350 B	Installation of a Crash Resistant Fuel System (CRFS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02492AK.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Document List (MDL) AS350-1420-MDL, Revision A, dated 30November 2017, or later FAA approved revision.2. Vector Aerospace "Instructions for Continued Airworthiness, for theCrash Resistant Fuel System (CRFS)", Document Number HM-019- 150G-ICA,Revision D, dated 3 November 2017, or later FAA3...	This installation has been shown compliant with the requirements for aCRFS when concurrently installed with the rotorcraft manufacturer'scargo swing. Compliance when any other external cargo swing is installedmust be determined by the installer.This installation is not compatible with the rotorcraft...	20/06/2018	Active	10064703
10064716	NORTHERN AVIONICS S.R.L.			767-400ER 767-300 767-200	USB Power on B767	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:Rif. CCL-NAV0573 Rev.2The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	AFMS – doc.AFM-NAV0573 Rev.1ICA – doc. ICA-NAV0573 Rev.0,,or later revisions of the above listed documents approved by EASA.Certification Program doc. P-2 NAV0573/2 Rev. 2CCL – doc. CCL-NAV0573 Rev.2	None	20/02/2018	Active	10064716

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064718	AIRBORNE TECHNOLOGIES GmbH	REV. 2		AW109SP	AW109-Mission Configuration including Trakka A800 searchlight, cameralift system with MX-15 HDI and a cabin workstation(ref STC-AT-102).Revision 1: Removal of STC incompatibilitywith TCH approved Snow skisKIT (ref STC-AT-102B).Revision 2: Transfer from ADOA to DOA	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Special Conditionfor Lithium-IonBattery Installation- The following paragraph(s) at a later amendment: CS27.49 Amdt 1.The requirements fo...	Rotorcraft Flight Manual Supplement STC-102-0-AFM rev 08, dated 18October 2018;CERTIFICATION MAINTENANCE REQUIREMENTS as per paragraph 4.3 ofSTC-102-0-AMM at rev 03 dated 08 January 2018;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.Certification ProgramM...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/01/2021	Active	10064718
10064719	BOMBARDIER Inc.		TCCA STC SA17-19 AT ISSUE 1	CL-600-2B16 (604 VARIANT)	EASA Validation of Transport Canada STC SA17-19 at Issue 1Installation of SATCOM Datalink Interface	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification to be completed in accordance with B/E Aerospace Ltd.Modification Data Summary Number L261000 Revision NC.For Instructions for Continued Airworthiness, refer to B/E AerospaceLtd. document L261070 Revision N/Cor later revisionsof the above listed documents approved by EASA inaccordanceB...	See those of original TCCA STC SA17-19.Previous to or concurrently with the implementation of the designchanges coveredby this STC, the aircraft must be fitted a CobhamAviator 700D satellite communications system with the followinginstallation characteristics:a. Type F DLNA.b. An ARINC 741 or 781 c...	20/02/2018	Active	10064719
10064720	SECURAPLANE TECHNOLOGIES, Inc.	REV. 1	FAA STC ST04243CH	GV-SP GIV-X	Installation of Securaplane Technologies High Definition External CameraSystem (CMX-HD) to replace existing standard definition camera system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Pentastar Aviation, Master Data List. Document No. A-16099-001, RevA, dated 5 September 2017 or later FAA approved revision.2. FAA Approved Airplane Flight Manual Supplement< (>,<)> PentastarAviation Supplement No. A-16099-204, Rev IR, approved 14 September 2017,or later FAA approved revision.3. I...	EASA STC 10015697 (FAA STC ST02980AT-D) for GIV-X Series aircraft mustbe installed prior to or in conjunction with thisSTC.EASA validation of the FAA STC ST02715AT-D is a prerequisite on GV-SPSeries aircraft for the installation of this STC design change.Prior to installation of this design changet...	02/03/2018	Active	10064720
10064726	B/E AEROSPACE LIMITED		TCCA STC C-LSA14-035/D	BD-700-1A10	EASA validation of Transport Canada STC C-LSA14-035/D at issue 2.Installation, Complete Custom Aircraft Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): EASA CRI D-300 at Issue 3 “Deviation – PassengerInformation Signs”the following paragraph(s) ata later amendment:The MSN 9517 aircraft is equipped with Glo...	Modification to be completed in accordance with Modification DataSummary J122000 Revision B, andMandatory Maintenance Manual Supplement L476070 Revision NC, andRefer to Instructions for Continued Airworthiness 35-027E372 Revision NC,,or later revisions of the above listed documents approved by EASAa...	A) See those of original TCCA STC C-LSA14-035/D.B) This Supplemental Type Certificate is limited to aircraft serialnumber 9517.C) The aircraft configuration approved by this STC represents provisionsfor special mission operation. As a result the following items normallyassociated with an interior ca...	20/02/2018	Active	10064726
10064732	B/E AEROSPACE LIMITED		TCCA STC C-LSA14-090/D ISSUE 2	BD-700-1A10	EASA validation of Transport Canada STC C-LSA14-090/D at issue 2.Installation, Complete Custom Aircraft Interior.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s):EASA CRI D-300 at Issue 3 “Deviation – Passenger Information Signs”.for the following paragraph(s) at a later amendment:The MSN 9494 aircraft is equipped with...	Modification to be completed in accordance with Modification DataSummary J314000 Revision B, andMandatory Maintenance Manual Supplement L476070 Revision NC, andRefer to Instructions for Continued Airworthiness 35-027E402 Revision NC,,or later revisions of the above listed documents approved by EASAa...	A) See those of original TCCA STC C-LSA14-090/D.B) This Supplemental Type Certificate is limited to aircraft serialnumber 9494.C) The aircraft configuration approved by this STC represents provisionsfor special mission operation. As a result the following items normallyassociated with an interior ca...	20/02/2018	Active	10064732

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064733	SCANDINAVIAN AVIONICS DESIGN ApS			550, 560, S550, 500	VHF/GPS Antenna Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 Amendment 2. Requirements as listed in Compliance Record, DocumentRef: 211373 COR, Issue 1.The requirements for envir...	- Engineering Order & Certification Program, Doc Ref: 2111373-EO, Issue1- Compliance Record, Doc Ref: 211373 COR, Issue1or later revisions of the above listed documents approved by EASA.- Continued Airworthiness for VHF Antenna Installation, Doc Ref:2111373-CA A- Continued Airworthiness for GPS Ant...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/02/2018	Active	10064733
10064734	FLYHT AEROSPACE SOLUTIONS Ltd.		TCCA SA12-67 ISSUE 3	767-300F 767-300 767-200	AFIRS 228 Automated Flight Information Reporting System InstallationIn accordance with FLYHT Master Document List 121-0068 Rev. M dated 5January 2018	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:Aircraft TCDS with the addition of FAR 25.869(a) at Amendment 25-72, FAR25.981 at Amendment 25-102 and 14 CFR 26 at Amendme...	- FLYHT ICA Document ref. 153-0059 Rev. E, dated February 2017- FLYHT EWIS ICA Document Ref. 157-0015 Rev. B, 26 March 2015- FLYHT AFM Supplement, AFIRS 228 Installation, Boeing 767-200/300; Ref.155-0011 Rev. B dated 5 January 2018or laterrevisions of the above listed documents approved by EASA ina...	Condition(s):- The aeroplanes modified by this STC must be:- operated in accordance with FLYHT AFM-S Ref. 155-0011 Rev.B or laterapproved revisions- maintained in accordance withFLYHT ICA 153-0059 Rev. E and FLYHT EWISICA Ref. 157-0015 Rev. B, or later approved revisionsNotes:- This STC does not a...	21/02/2018	Active	10064734
10064735	SAFRAN CABIN GERMANY GmbH	REV. 1		SEE FAA APPROVED MODEL LIST	Installation of Monogram Systems' In-Flight Trash Compactor.Revision 1: Transfer of STC holder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Monogram Systems' Master Data List TR40800, Revision C, dated 9September 20112. Instructions for Continued Airworthiness, ICA No. 112, Revision B,dated 7 October 2011or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	25/05/2021	Active	10064735
10064772	AMAC AEROSPACE SWITZERLAND AG			737-800	Tailwind Sat TV Antenna installationJRG Design FAA STC ST01850NY (not EASA validated), installed on upperfuselage between STA 500C and STA 540, certifying against EASAcertification basis.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s):CRI B-01 Vibration / Buffeting Criteria for large external antennainstallations.The requirements for environmental protection and the associat...	- Master Data List MDL-GE01-5300, Revision A, Dated 20.02.2018-Airplane Flight Manual Supplement AFMS-GE01-5300, Revision A, Dated9.11.2017- Instructions for Continued Airworthiness ICA-GE01-5300 Revision B,Dated 19.01.2018or later revisions of the above listed documents approved by EASA.	Per: Airworthiness Limitations Section of Instructions for ContinuedAirworthiness ICA-GE01-5300Prior to installation ofthis design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadvers...	23/02/2018	Active	10064772
10064774	AIRBORNE TECHNOLOGIES GmbH	REV. 1		P.68R “VICTOR” P.68R "VICTOR"	TCAS IIThis change approves the upgrade of a Garmin GTS Processor, TrafficAdvisory System (TAS) (GTS 825) to a Traffic Collision Avoidance System (TCASII) (GTS 8000) together with the installation of GTX3000transponder and GA58 antenna to facilitate TCAS II capabilityChanges of this STC:STC-AT-104A i...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23 Amdt 3: 23.301;23.303; 23.305; 23.307; 23.337; 23.625(a); 23.771(a); 23.867(a)(b);23.1301; 23.1309; 2...	STC-104-0-AFM, Airplane Flight Manual Supplement, Revision 4, dated20.12.2022STC-104-0-AMM, Maintenance Manual Supplement, Revision 6, dated20.12.2022STC-104-0-DWG, List of Drawings, Revision 2, dated 23.07.2019STC-104-0-II, Installation Instructions, Revision 5, dated 20.12.2022Or later revisions o...	The aircraft must have been fitted with the TC holder’s Garmin GTS825option prior to the upgrade of the system under this approval.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change an...	10/03/2023	Active	10064774

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064791	B/E AEROSPACE, Inc. - FSI	REV. 5	FAA ST02551SE	777-200	British Airways Boeing model 777-200 series interior reconfigurationRevision 5 updates the Limitations/Conditions section.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.613 at amdt. 1,,,,JAR 25.785(a) at change 14 ,,JAR 25.785(b) atchange 14JAR 25.785(c) at change 14,,JAR 25.785(d) at...	Master Drawing List ref. B6FS657-D01 rev. AM dated 10/09/2020Supplement to Instructions for Continued Airworthiness ref. B6FS657-D15rev. G dated 23/07/2020AFMS ref. TP18-865AFM initial revision dated 03/09/2020or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in a...	“Prior or concurrent installation of the following modification(s) arerequired with this STC (aircraft applicability isidentified within thefollowing documentation):- British Airways Service Bulletin BA-777-25-0078, Rev. 00, datedSeptember 12, 2018 and Concession Engineering DesignInstruction/Appro...	28/09/2020	Active	10064791
10064792	ROCKWELL COLLINS, Inc.		FAA STC ST01794WI	SEE FAA AML, REV. A	Modification of Rockwell Collins TCAS II System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Airplane Flight Manual Supplement as specified by FAA Approved Modellist (AML) RCA-0551, Revision (-);2. Instructions for Continued Airworthiness as specified by FAA ApprovedModel List (AML) RCA-0551, Revision (-);or later FAA approved revisions.	Prior EASA approved installation of a Rockwell Collins TCASII system isa prerequisite to this STC.Model specific limitations are documented within AML RCA-0551, Revision (-), or later approved revisions.Prior to installation of this designchange it must be determined thatthe interrelationship betwe...	02/03/2018	Active	10064792
10064794	GARMIN INTERNATIONAL, Inc.	REV. 8	FAA STC SA02571SE	STC 10064794 SEE FAA AML TO STC SA02571SE SEE FAA AML COMPLEMENTED WITH EASA AML TO	Installation of Garmin G500/G600 TXi Integrated Avionics System (PrimaryFlight Display, Multi-Function Display, and Engine Indicating SystemDisplay).Revision 1 amends the Master Drawing List, Equipment List, AFMS, ICA andInstall Manual.Revision 2 is a correction of a typographical error.Revision 3 a...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: as indicated on FAA STCSA02571SE dated January 25, 2023.The requirements for environmental protection and the...	For Aircraft in FAA AML to FAA STC SA02571SE1. Garmin Master Drawing List (MDL) 005-00795-C2 Revision 1, dated 17November 20172. Garmin Airplane Flight Manual Supplement (AFMS) 190-01717-B2 Revision1, dated 17 November 20173. Additional Garmin AFMS for the Socata TBM 700/850 (to address RVSMaspects)...	This EASA STC is valid for aircraft types and models approved by EASAand listed on the FAA AML to FAA STC SA02571SE dated 15 March 2023 andfor aircraft types and models listed in EASA AML to EASA STC 10064794attached to this approval (which are only approved in EASA System: “EASAonly models”)Prior t...	21/07/2023	Active	10064794
10064797	AAR AIRCRAFT SERVICES		FAA STC ST04092CH	A330-243	Installation of 278 (18BC/68PY/192EY) Passenger Seating Arrangement.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AAR Master Data List, 31725CR002. Revision C< (>,<)> dated 24 May 2016< (>,<)> or later FAA approved revision.	Lufthansa Technik AG STC 10014373 must be concurrently installed.Prior to installation of this design change it must bedetermined thatthe interrelationship between this design change and any otherpreviously installed design change and/ orrepair will introduce noadverse effect upon the airworthines...	27/02/2018	Active	10064797
10064798	P.P.G. INDUSTRIES, Inc.		PQ1019CE SUPPLEMENT NO. 122	CL-600-2D24 (RJ SERIES 900) CL-600-2C10 (RJ 700,701,702) CL-600-2B19 (RJ SERIES 100)	CL-600 Main and Side WindshieldPPG Windshield PMA - CL-600	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA – Parts Manufacturer Approval, letter PMA No. PQ1019CE, dated 22August 2014- FAA – PQ1019CE, Supplement 122, dated 26 June 2014or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)” and/ or theU...	None	27/02/2018	Active	10064798

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064803	AMAC AEROSPACE SWITZERLAND AG			737-700	Certification for Commercial Operation / The modification consists ofremoving the existing limitations for private use to allow commercialoperation of the aircraft. For this purpose, physical modifications ofthe aircraft have been performed and substantiated through AMAC Minormodification AY07-2520....	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:Appendix S of CS 25 Amendment 19: S25.1(a); S25.10; S25.20;S25.30;S25.40(a)(b); S25.50.The requirements for environment...	AFMS-AY07-2500, Airplane Flight Manual Supplement, Rev. Aorlater revisions of the above listed documents approved by EASA.MDL-AY07-2500, Master Data List, Rev. AAMMS-AY, AircraftMaintenance Manual Supplement, Rev. A	AMAC Aerospace Minor Change AY07-2520 must be accomplished prior to orconcurrently with this modification.Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpreviously installed design change and/ or repair will introdu...	27/02/2018	Active	10064803
10064804	Q.C.M. DESIGN GmbH	REV. 1		HAWKER 800XP HAWKER 800 HAWKER 1000 BAE.125 SERIES 800B BAE.125 SERIES 800A BAE.125 SERIES 1000B BAE.125 SERIES 1000A	ADS-B Out Upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-ACNS Initial Issue(Subpart D Section 4)The requirements for environmental protection and the associatedcertified noisea...	Installation, Operation and Maintenance in accordance with ComplianceReport CR-RH10-QCM23-001, issue R1 dated 3rd June 2020or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to:-BAe.125 Series 1000A and 10008 Serial Numbers 258151, 258159, 259004through 259042-Hawker 1000 Serial Numbers 259003, 259043 through 259052When equipped with Honeywell SPZ-8000 avionics given the followingconfiguration:-Honeywell Dual Integrated Communication Unit - RCZ-8XX, (PN:751070...	10/06/2020	Active	10064804
10064806	ELECTRONICS INTERNATIONAL, Inc.		FAA STC SA02135SE	SEE FAA APPROVED MODEL LIST	Installation of Electronics International Inc. Glass Panel EngineMonitor (with In-Flight Data) MVP-50T	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Installation Instructions, Document No. II 1211061, Revision D, dated15 June 2011 or later FAA approved revision.2. Airplane Flight Manual Supplement (AFMS) Document Number AFM06271101,Revision IR, dated 27 June 2011, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	01/03/2018	Active	10064806
10064808	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		A321-231	Cabin Densification of British Airways A321-231 Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Summary, Northwest Aerospace Technologies, Inc. documentN0604-090, Revision -, dated 27 February 2018;-Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document N0604-070, Revision -<(>,<)> dated 3 January2018;or later revisions of the above listed doc...	The following Minor Change Approved Service Bulletins shallbeconcurrently installed: British Airways SB A321-25-0025; Airbus SBsA320-53-1368, SB25-1 BGV; AIM Aviation SBs 321 BMI2AGAOO-25-1710,A321-25-016 and A321-25-018; ZSFR SB 160-25-174; H4A SB H4AA12400.Prior to installation of this design cha...	06/04/2018	Active	10064808
10064809	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03585NY	FALCON 2000EX FALCON 2000	Validation of FAA STC ST03585NY.Installation of Meggitt Avionics Integrated Secondary Flight Display(iSFD).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List No. F2MW-D0057-005, Revision B, dated 31 October 2016.Airplane Flight Manual Supplement Document No F2MW-D0057-150, RevisionIR, dated 02 June 2016.Instructions for Continued Airworthiness Document No.: F2MW-D0057-155,Revision A, dated 21 Oct 2016or later revisions of the above liste...	This STC requires as prerequisite, the installation of Dassault AviationModification M3152: Meggitt Digital Standby unit (Meggitt MKII).Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design chan...	28/02/2018	Active	10064809

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064811	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03587NY	MYSTÈRE FALCON 50 (MF50)	Validation of FAA STC ST03587NY.Installation of Meggitt Avionics Integrated Secondary Flight Display(iSFD).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List No. F50XW-D0043-005, Revision A, dated 31 October 2016.Airplane Flight Manual Supplement Document No F5XW-D0043-150, RevisionIR, dated 08 June 2016.Instructions for Continued Airworthiness Document No.: F50XW-D0043-155,Revision A, dated 21 Oct 2016or later revisions of the above lis...	This STC requires as prerequisite, the installation of Dassault AviationModification M3124: Meggitt Digital Standby unit (Meggitt MKII).Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design chan...	28/02/2018	Active	10064811
10064815	DASSAULT FALCON JET CORPORATION		FAA STC SA7084SW-D	MYSTÈRE FALCON 900 (MF900)	Validation of FAA STC SA7084SW-D.Antenna Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List Report No. F90-01005, Revision AD, dated 13 July 1995or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)" and/ or the Technical Implementation Procedures of EU/USA Bilateral Agreement....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/03/2018	Active	10064815
10064817	PEREGRINE LLC		FAA STC SA00756DE	SEE FAA APPROVED MODEL LIST	Installation of Automatic Dependent Surveillance – Broadcast (ADS-B) OutEquipment using a Trig Avionics TT22 Transponder and an approved GlobalPositioning System (GPS) Position Sensor.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Peregrine Master Drawing List, referenced on the attached AML No.SA00756DE.2. Instructions for Continued Airworthiness document< (>,<)> as listed onthe attached AML No. SA00756DE.3. Airplane Flight Manual Supplement as listed on the attached AML No.SA00756DE.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	01/03/2018	Active	10064817
10064818	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED		CAA UK RESPONSIBILITY	EC135 T3 EC135 T2+ EC135 T2	CVR/FDR Installation/NVIS on EC135	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 27 Amendment 3: 27.301/303/305/321/337/341/351/561/601/603/605/609/610/611/613/853/1301/1307/1309/1322/1351/1357/1365/1367/1381/1457/1459/1525/1529/1541/1581/1585CS 27C...	-Flight Manual Supplement FMS/143-002, Issue 2or later revisions of the above listed documents approved by EASA.-ICA/143-014, Issue 1 dated 2 February 2018-Design Report Doc DR/143-001 Issue 5, dated 20 February 2018-Modification Leaflet &Certificate of Design, BABCOCK/MOD/143 Issue 2dated 22 Febru...	Applicability of this STC is limited to CPDS cockpit versionsPrior to installation of this design change it must be determined thatthe interrelationship between this design changeand any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of...	01/03/2018	Active	10064818
10064823	AEROTEC & CONCEPT			A330-342, -343 A330-322, -323, -341, A330-302, -303, -321, A330-223, -243, -301, A330-201, -202, -203,	A330 Stretcher InstallationThis modification deals with theinstallation of medical stretchers (LHand RH) on AIRBUS A330 AFT passenger cabin.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List AE17186MDL Rev.0 dated 01/03/2018- AFM Supplement AE17186AFMS Rev.0 dated 22/11/2017-Instructions for Continued Airworthiness AE17186ICA Rev.0 dated22/11/2017orlater revisions of the above listed documents approved by EASA.	-Per AFM Supplement AE17186AFMS-Per Instructions for Continued Airworthiness AE17186ICA-Pre-requisite: Aerotec Change AE16077 MASPrior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/...	01/03/2018	Active	10064823
10064829	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A330-223	IFE UpgradeRev 1.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement S.OAEZ. 001878-AFM Rev 00.or later revisions of the above listed documents approved byEASA.Master Document List S.OAEZ.001878-MDL R01	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/04/2021	Active	10064829

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064848	FLYHT AEROSPACE SOLUTIONS Ltd.		TCCA STC NO. SA14-39 ISSUE 2	757-200	AFIRS 228 Automated Flight Information Reporting System Installation inaccordance with FlyHTMaster Document List 121-0076 Revision G.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Aircraft TCDS with the addition of FAR 25.869(a) at Amendment 25-72, FAR25.981 at Amendment 25-102 and 14 CFR 26 at Amendment 26-6The requirements for environmental protec...	-FLYHT ICA Document ref. 153-0070 Rev. B, dated 3 October 2016-FLYHT EWIS ICA Document AFIRS 228 Installation, Boeing 757-200, Ref. 157-0018 Rev. A, dated 12 February 2015-FLYHT AFM Supplement, AFIRS 228 Installation, Boeing 757-200; Ref.155-0017 Rev. C dated 23 January 2018or later revisions of thea...	The aeroplanes modified by this STC must be:- operated in accordance with FLYHT AFM-S Ref. 155-0017 Rev. C or laterapproved revisions- maintained in accordance with FLYHT ICA 153-0070 Rev. B and FLYHT EWISICA Ref. 157-0018 Rev. A, or laterapproved revisionsNotes:- The scope of this STC modification...	05/03/2018	Active	10064848
10064869	ANJOU AERONAUTIQUE S.R.L.			737-800	Replacement of seatbelts on 16G aircraft seat	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	02-900428-MDL-001, Rev. 05 dated 05 March 2018 “Master DataList”or later revisions of the above listed documents approved by EASA.	The STC approval is limited to Polyester seat belts 34911 installed onB/E seat models Pinnacle P/N 1032422Prior to installation of this design change it must be determined thattheinterrelationship between this design change and any otherpreviously installed design change and/ or repair will introdu...	06/03/2018	Active	10064869
10064887	AVIATION FABRICATORS, Inc.		FAA STC SA126RM	501/551	Installation of stretcher.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Branson Engineering Company, Inc. Drawing List No. 90132, Revision C,dated 13 March 1978 or subsequent FAA approved revision;or according to Aviation Fabricators STC Drawing List AF-215, RevisionB, dated 25 March 2003 or later FAA approved revision.2. Airplane Flight Manual Supplement dated 19 De...	Interchange provisions apply only to model 551.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product....	07/03/2018	Active	10064887
10064889	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		B100	MTV-27-() on Beech B100.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-36, Amdt 4, FAR 36Amdt 36-30.This certificate/ approval involves a change to the requirements forenvironmental protecti...	According to MT-Propeller Master Documentation List No. E-3224, Rev 3To be operated in accordance with MT-Propeller AFM-S Document No.E-3226, Rev 2To be installed i.a.w. Installation Instructions Doc. No. E-3227, Rev 2To be maintained i.a.w. Instruction for continued airworthiness Doc. No.E-3228, Re...	According limitation section of AFM-S.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	14/11/2019	Active	10064889
10064891	AIRFILM CAMERA SYSTEMS, INC		FAA STC SR02660LA	SEE FAA AML	Installation of Nose Utility Mount.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved Airfilm Camera Systems documentation listed onAML No.SR02660LA, dated 30 November 2017,and Master Document List AF-R44NM-010, Revision B, dated 20 November2017. Rotorcraft Flight Manual Supplement, dated 21 November 2017 orlater FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	07/03/2018	Active	10064891

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064895	CERT WORKS, LLC	REV. 2	FAA STC SR00826DE	SEE FAA APPROVED MODEL LIST	Installation of Honeywell Sky Connect Tracker III system.Rev. 1:Revised to add Leonardo S.p.A. AW189.Rev. 2:Revised to add Airbus Helicopters SA365N, SA365N1, AS365N2, AS365N3,EC155B, EC155B1.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00826DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Document No. CW0602-1006, Master Data List (MDL), Part 29 AML SkyConnect Tracker III Installation, Revision IR dated 1 December 2016 orlater FAA approved revisions.FAA approved Rotorcraft Flight Manual Supplement (RFMS). Refer toAML-SR00826DE for model specific RFMS document.Instructions for Continu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	14/02/2020	Active	10064895
10064898	AMAC AEROSPACE SWITZERLAND AG	REV. 8		A321-231/-232 A321-211/-212/-213/-231/-232 A321-211/-212/-213 A320-271N/-272N/-273N A320-253N/-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233/-251N/-252N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of the Honeywell JetWave Ka-Band Antenna.Revision 1:Extension of EASA STC 10064898 to include the A320-211, A320-212,A320-214, A320-215, A320-216, A320-231, A320-232,A320-233 AircraftModels.Revision 2:Extension of EASA STC 10064898, Rev. 1 to include the A320-251N,A320-252N, A320-253N,...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-01 Vibration/buffeting compliancecriteria for large external antenna installation.- The following paragraph(s) at a late...	For Configuration 1- The change is defined through AMAC Master Data List MDL-A3201-1-5300,Revision E.- The Aircraft shall be modified in accordance with AMAC EngineeringOrder EO-A3201-1-5300, Revision C and associated documents.- The aircraft shall be operated in accordance with AMAC Airplane Flight...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/09/2024	Active	10064898
10064899	E A D AEROSPACE AIRWORTHINESS			777-300, 777-300ER 777-200, 777-200LR	Transmitting Portable Electronic Devices (T-PED) tolerance demonstration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Drawing List, EAD Aerospace document no. 01554-EAS-A-MDL,Revision C, dated 6 March 2018-Instructions for Continued Airworthiness, EAD Aerospace document no.01554-EAS-A-ICA-01, Revision B, dated 27 February 2018-Aircraft Flight manual Supplement, EAD Aerospace document no.01554-EAS-A-AFM-01,o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	09/03/2018	Active	10064899
10064901	RAMSEIER, DANIEL			CTLS-ELA	Hand-Controls installation on CTLS-ELA	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-To be installed according to Installation Document IN_10050162, issue2, dated 25 August 2017.-To be operated accordingto POH, Document PO_10050162, issue 1, dated26 August 2017.-To be maintained according to Supplement to Aircraft MaintenanceManual, Document AM_10050162, issue 2, dated 25 August 2...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/03/2018	Active	10064901
10064912	AIRBUS HELICOPTERS, Inc.		FAA STC SH4016SW-D	AS 350 B, B1, B2, B3, BA	Installation of Hourmeter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List 350A82-1154, Revision U, dated 25 February 1998, or later FAA approved revision.NEW-PAGE	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/03/2018	Active	10064912

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064913	KLM ENGINEERING & MAINTENANCE			A330-203	Cabin Reconfiguration of KLM A330-203Replacement of Business Class seats, Economy Class seats and VideoControl Centre, installation of monuments, installation of In-FlightEntertainment System, replacement of décor laminates, curtains andcarpet and related changes to cabin furniture to accommodate ne...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, KLM Report MDL-013435 Revision 02, dated19-Feb-2018.-Instructions for Continued Airworthiness, KLM Report ICA-332-13435,Revision ORG, dated 05-Jan-2018or laterrevisions of the above listed documents approved by EASA	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/03/2018	Active	10064913
10064914	AEROMECH Inc.		FAA ST01531SE	35, 35A, 36, 36A	Reduced Vertical Separation Minimum (RVSM).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AeroMech Document No. AMI-QD-LJ-0146 Rev. A, dated May 18, 2006 orlatest FAA approved revision.- Instructions for Initial and Continued Airworthiness, documentAMI-IICA-LJ-0428, Rev. A, dated May 18, 2006 or latest FAA approvedrevision.- Airplane Fight Manual Supplement (AFMS) for the Learjet Model...	- Instructions for Initial and Continued Airworthiness,AMI-IICA-LJ-0428, Rev. A, dated May 18, 2006 or latest FAA approvedrevision, is a required part of this STC.- AFMS for the Learjet Model 35/35A/36/36A aircraft, AMI-AFMS-LJ-0507,Rev. Original, FAA approved April 21, 2005, or latest FAA approvedr...	09/03/2018	Active	10064914
10064929	FLIR SYSTEMS AB	REV. 2	SWEDISH STC M 31/01	AS 350 BB, AS 350 D AS 350 BB, AS 350 C, AS 350 D AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA AS 350 B3 AS 350 BA	Installation of External Camera (Flir System AB sensor).Original Issue. Transfer of STC to different legal entity (fromSwedishSTC M31/01)Rev. 1: Added installation of camera P/N 275CF.Rev. 2: Compliance document revised.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For original issue:PolyTech AB Flight Manual Supplements FMS AS350 No AS350-101, LFV No.S41/01.For Rev. 1:Master Document List E200109-841 Rev C, dated 13 June 2021Flight Manual Supplement AS350-101, Rev 07, dated 16 May 2021Instructions for Continued Airworthiness E200109-839, Rev B, dated 11June 2...	The approval holder shall fulfill the obligations of Part 21, Point21A.109.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthi...	17/08/2023	Active	10064929
10064930	FLIR SYSTEMS AB		SWEDISH STC M 23D/94	AB206 A, AB206 B 206L-1, 206L-3, 206L-4 206A, 206B, 206L	Transfer of the certificate No. M 23D/94 Rev. 1 - Installation of PolyTech AB “Stable Eye 350 Type C”, belly or nose mounted.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	PolyTech AB Flight Manual Supplements: LFV No. S 16/96 Rev.3 (Bell206)and No. S11/01 (AB206).or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/07/2018	Active	10064930
10064931	FLIR SYSTEMS AB		SWEDISH STC M 24A/94	500N 369HE, 369HM, 369HS 369D, 369E, 369FF, 369H	Transfer of the certificate No. M 24A/94 Rev. 1 - Installation of PolyTech AB “ARGUS 350 Sensor System” previously named “Stable Eye 350 TypeC”, belly or nose mounted.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	PolyTech AB Flight Manual Supplements: LFV No. S 9/98 bellymounted andNo S 21/98 nose mountedor later revisions of theabove listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/07/2018	Active	10064931
10064932 (LBA SA 1237)	RAISBECK ENGINEERING Inc.		FAA STC SA2905NM	B200CT, B200T A200C, A200CT, B200, B200C, 200, 200C, 200CT, 200T, A200,	Installation of Butterfield Industries Flow Through Anti-Ice Kit P/N BI1001-1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Data Package BI 1003, Revision F, dated8 November 2006, and Drawing list BI 1002, Revision G, dated 4 November2013 or later FAA approved revisions.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.	06/08/2018	Active	10064932

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064933	ACC COLUMBIA Jet Service GmbH	REV. 2	LBA 0533/657	RALLYE 235 E, RALLYE 235 E-D MS 894 A, MS 894 E	Exhaust System MS 235-606500 to Rallye 235 and MS 894 variants.Extension of the existing approval to following variants:Rallye 235 C, Rallye 235 E, Rallye 235 F, MS 894 C.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to GFM Master Document list MDOCL_2043745_rev0_20180201;To be operated in accordance with Gomolzig AFM-S Document No.SPOH_2043745_rev0_20180201;or later revisions of theabove listed documents approved by EASA.To be installed iaw. Installation Instructions Doc. NoII_2043745_rev0_20180201,T...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	31/01/2022	Active	10064933
10064936	U.S. TECHNICAL CONSULTANTS, INC.		FAA STC ST02655LA	ATR 72-211/-212/-212A ATR 72-101/-201/-102/-202 ATR 42-200/-300/-320/-400/-500 09032018	Installation of two True Blue Power Model TA102 Changing Ports in thecockpit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	U. S. Technical Master Data List (MDL), Document No.7642-24-000,Revision "L", dated 2 October 2017, or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Document No.U10-0430,Revision C, dated 29 September 2017.Airplane Flight Manual Supplement (AFMS), Document No. U10-0459,...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/03/2018	Active	10064936
10064937	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 350 B3	Installation of L3 Trilogy ESI-2000 Standby Instrument, changeAHUK/ 350/3135.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s):CRI F-01 Lithium Battery InstallationThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	AS 350 B3e AFM SUPPLEMENT No: 106AHUK/350-FMS-106, initial issue, dated07 March 2018or later revisions of the above listed documents approved by EASA.Certification Plan ACP/3503135-01 issue C, dated 5 March 2018Instructions for Continued Airworthiness ICA/3503135-01, issue A, dated15 February 2018	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/03/2018	Active	10064937
10064941	AIR COMM CORPORATION L.L.C		FAA STC SR00601DE	MBB-BK117 C-2 MBB-BK117 C-1	Installation of Cabin Air Conditioning System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Air Comm Corporation Master Drawing List - EC 145 Cabin AirConditioning System, Report No. DL-EC145, Revision C, dated 10 April2006 and FAA approved 17 April 2006 or later FAA approved revision.2. Instructions for Continued Airworthiness, Air Comm Corporation ReportEC 145-200M-1, Revision 0, date...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/03/2018	Active	10064941
10064955	GARMIN INTERNATIONAL, Inc.	REV. 1	FAA ST01821WI	400A	Installation of the G5000 Integrated Flight Deck, includingprimaryflight displays, automatic flight control system, NAV/ COM/FMS and engineinstrument systems.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-03 (Flight GuidanceSystem) - CRI F-04 (Human Factors)SC 25-ANM-32 (High Altitude Operation at 45,000 feet) - 25-634-SC(Airplane Electronic-S...	- Master Drawing List, Garmin International, Inc. document No. 005-00756-00, Revision 1, dated 29 August 2016;- AirplaneFlight Manual Supplement, Garmin International, Inc. documentNo. 190-01508-03, Revision 1, dated 29 August 2016;- G5000System Maintenance Manual, Garmin International, Inc. docume...	1),,Eligible aircraft serial numbers RK-001 through RK-604.Additionalaircraft configuration requirements are defined in the data shown onMaster Drawing List (MDL) 005-00756-00.2),,Aircraft modified by this STC must be operated in accordance withthe Airplane Flight Manual Supplement (AFMS) identifie...	16/03/2018	Active	10064955

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064977	B/E AEROSPACE, Inc. - FSI	REV 1	FAA STC ST02579SE	A330-243/-243F/-343 A330-201/-202/-203/-223/-223F,	Interior Reconfiguration on Airbus A330-200 series and A330-300 seriesairplanes.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02579SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. B/E Aerospace, Inc. - FSI (B/E -FSI) Master Drawing List(MDL) B6FS643-D01, Revision L, dated 20 November 2018, or later FederalAviation Administration (FAA) approved revision.2. The Supplemental Instructions for Continued Airworthiness,B/E - FSIDocument B6FS643-D15, Revision B, dated 5 October 2...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/11/2018	Active	10064977
10064982	AEROTEC & CONCEPT			737-800	AEROTEC CONCEPT Mod No. 17189 : B737-800 Cabin Reconfiguration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 Amendment 17:§25.785(h).The requirements for environmental protection and the associatedcertified noise and/ or emiss...	- Instructions for Continued Airworthiness Doc N°: AE17189ICA Revision 0dated 12.03. 2018;- Master Data List Doc N°: AE17189MDL Revision 0 dated: 13.03.2018;or later revisions of the above listed documents approved by EASA.	This STC is applicable to B737-800 MSN 61353.This STC requires as prerequisite, installation of a class dividerpartitions as per AMES Change approval reference M403001001.13092017.Prior to installation of this design change it must be determined thatthe interrelationship between this design change a...	14/03/2018	Active	10064982
10064984	ZEE SYSTEMS, Inc.		FAA STC SA4034SW	500/ 501	Installation of Zee Systems Air Conditioner.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawings DA-79-1801, Revision B dated 1 November 1979, DA-79-1802,Revision B dated 1 November 1979, and 978180, Revision B dated 14January 1980, or later FAA approved revision.FAAApproved Airplane Flight Manual Supplement dated 10 March 1980.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/03/2018	Active	10064984
10064985	AEROLITE AG	REV. 5		EC135 P3, EC135 T3	Emergency Medical Services (EMS) EquipmentInitial STC:This STC covers the installation of EMS Equipment P/N 135-0238317-501.The equipment includes several cabin configurations consisting of seats,stretchers, patient retaining system and stowage provisions which areinstalled in a modular way. An inte...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-27 at Amendment 2for 27.309(a), (e), (g); 27.321(a); 27.337(a); 27.339; 27.341;27.351(a); 27.471; 27.619;2...	For all EMS Equipment configurations:- Master Document List, MDL-17-005, Rev. RFor EMS Equipment P/N 135-0238317-501:- Flight Manual Supplement FMS-135-0238317-501 Revision F- Master Minimum Equipment List Supplement MMEL-S-135-0238317-501Revisio n 0- Operations Manual OPM-135-0238317-501 Revision F-...	Limited to Helicopters with Helionix cockpit variantEMS Equipment P/N 135-0238317-502 (STC 10064985 Revision 5) is limitedto EC135 T3 with Helionix cockpit variantPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	11/07/2024	Active	10064985
10064986	AIRBUS S.A.S.			A340-643 A340-642	AIS MOD CJ2093 - A340 GOGO 2KU SYSTEM ACTIVATIONActivation of an Outside Aircraft Equipment (large antenna + radome+skirt) located on A340-600 upper fuselage.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Approval Sheet - MAS CJ2093 Issue 3, dated 16th March 2018or later revisions of the above listed documentsapproved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/03/2018	Active	10064986
10064987	SOCIETE AIR FRANCE S.A.			A340-313	"JOON" cabin reconfiguration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.807, 25.811, 25.853, 25.854, 25-1423 at JAR25 Change 14The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	-Société Air France Change Approval Sheet CAS-A340-17-005 original issuedated 13 March 2018-Société Air France Instructions for Continued AirworthinessICA-A340-17-005 original issue dated 13 February 2018	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/03/2018	Active	10064987

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064988	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03591NY	FALCON 7X	Validation of FAA STC ST03591NY.Installation of Honeywell JetWave System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List F7XW-D0042-005 Revision B, dated 23 September 2016-Instructions for Continued Airworthiness F7XW-D0042-155 Revision IR,dated 21 September 2016-Aircraft Flight Manual Supplement F7XW-D0042-150 Revision IR, dated 23September 2016or later revisions of the above listed documents approv...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/03/2018	Active	10064988
10064994	AIRBUS HELICOPTERS, Inc.	REV. 1	FAA SR09510RC	AS 350 B3	Installation of AEM 600W Loud Hailer SystemRev. 1 introduces a correction in the Certification Basis and a newlimitation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:27.773 Amendment27-50.The requirements for environmental protection and the associatedcertified noise and/ or emissionsu...	- Master Drawing List 350A82-1794 Rev. A dated 16 November 2017-Rotorcraft Flight Manual Supplement 350FMS-548 Rev. IRdated 16February 2018- Instruction for Continued Airworthiness 350MMS-039 Rev. IR dated 10January 2018or later revisions of the above listed document(s) approved/accepted onbehalfP...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/04/2021	Active	10064994
10064995	HAMILTON SUNDSTRAND CORPORATION	REV. 1	FAA STC ST00386BO	787-8, 787-9	Installation of Hamilton Sundstrand Supplemental Cooling Unit (SCU) P/ N7011015H02EX (service life escalation).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Hamilton Sundstrand Master Document List (MDL) HSER37062, Revision -,dated 30 November 2017, or later FAA approved revision.Maintenance must be in accordance with Instructions forContinuedAirworthiness (ICA), Hamilton Sundstrand ComponentMaintenance Manual(CMM) 21-54-88, Revision 0, dated 30 Novem...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.There is no impact to The Boeing Company 787-8,e...	20/03/2018	Active	10064995
10064996	3S CERTIFICATION, LLC		FAA STC SA01865WI	PC-12/47 PC-12/45	Installation of Generator 2 RCCB Upgrade and/or Dual Battery CockpitLabeling	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. 3S Certification, Master Data List (MDL) 3S17-005-1001, Revision IR,dated 17 January 2018 or later FAA approved revision.2. 3S Certification, Airplane Flight Manual Supplement (AFMS) 3S17-005-7101, Revision IR, dated 17 January 2018 or later FAA approvedrevision.3. 3S Certification, Instructions f...	EASA validation of FAA STC SA02266LA is a pre-requisite on PC-12/45,PC-12/47 for the installation of this STC design change.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or r...	28/03/2018	Active	10064996
10064997	DUNCAN AVIATION, INC.	REV. 1	FAA STC ST01856WI	EMB-135BJ	Upgrade Honeywell FMZ-2000 FMS to FMZ-2010 for LPV & VNAVRev. 1: Amended to update the datalink timer to support RCP/RSPcompliance and other datalink related improvements for commonalty acrossplatforms.	The Certification Basis (CB) for the original product as amended by thefollowing additional or alternative airworthiness requirements:CS25 amdt 17: 25.1317The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and...	1. STC Master Document List, Duncan Aviation, Inc. Doc. No.CERTDOC-003015, Rev A, dated 8 November 2017 or later FAA approvedrevisions.2. Airplane Flight Manual Supplement, DuncanAviation, Inc. Doc. No.CERTDOC-005289, Rev A, dated 8 November 2017, or later FAA approvedrevisions.3. Duncan Aviation,N...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/08/2021	Active	10064997

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10064998	LATITUDE TECHNOLOGIES CORPORATION		TCCA STC SA11-84, ISSUE 3	DHC-8-401/DHC-8-402 DHC-8-311/DHC-8-314/ DHC-8-315 DHC-8-201/DHC-8-202/ DHC-8-301 DHC-8-102/DHC-8-103/ DHC-8-106	Latitude Technology S200 Satcom and associated accessories.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation must be in accordance with Latitude Technologies MasterDrawing List, 1120-MDL-001, Rev. E, dated 20th ofOctober 2014.- Maintenance must be in accordance with Latitude TechnologiesInstructions for Continued Airworthiness 1120-400-005, Rev. 05.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/03/2018	Active	10064998
10064999	DUNCAN AVIATION, INC.	REV. 1	FAA STC ST01858WI	EMB-135BJ	Installation of a Data Link Communication System supportingFuture AirNavigation FANS 1/A+Rev. 1: Limitation updated	The Certification Basis (CB) for the original product as amended by thefollowing additional or alternative airworthiness requirements:CS25 amdt 17: 25.1316, 25.1317CS25 amdt 26: 25.1460(a)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. STC Master Document List, Duncan Aviation, Inc. Doc. No.CERTDOC-005598, Rev A, dated 15 November 2017 or later FAA approvedrevisions.2. Airplane Flight Manual Supplement, Duncan Aviation, Inc. Doc. No.CERTDOC-005307, Rev B, dated 23 June 2021 or later FAA approvedrevisions.3. Duncan Aviation, Inc...	This STC requires that the Honeywell FMZ-2000 Flight Management System(FMS) be equipped with software version NZ 6.1.1-03046 (NZ-2010).Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design chang...	13/08/2021	Active	10064999
10065001	DUNCAN AVIATION, INC.	REV. 2	FAA STC ST01861WI	EMB-135BJ	Upgrade of Honeywell Electronic Display System with option for SyntheticVision Capability and Primus Elite Advanced FeaturesRev. 2: updates technical data.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Master Document List, Duncan Aviation, Inc. Doc. No. CERTDOC-002787,Rev G dated 30 August 2023<(>,<)>Airplane Flight Manual Supplement, Duncan Aviation, Inc. Doc. No.CERTDOC-002760, Rev D, dated 30 August 2023<(>,<)>Duncan Aviation, Inc. Instructions for Continued Airworthiness, Doc. No.CERTDOC-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/12/2023	Active	10065001
10065008	DART AEROSPACE USA, Inc.		FAA STC SR02578SE	MBB-BK117 C-2/ MBB-BK117 D-2	Installation of a Heli-Utility-Basket.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions IIN-D117-1044, Revision B, dated 27 October2017, or later FAA approved revision.Master Drawing List (MDL) MDL-D117-1044, Revision C, dated 11 December2017.Instructions for Continued Airworthiness (ICA) ICA-0117-1044, Revision0, dated 11 October 2017, or later FAA accepted r...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/03/2018	Active	10065008
10065014	EMBRAER ENGINEERING & TECHNOLOGYCE NTER USA, INC.		FAA STC SA04278AT	EMB-505	Installation of a cabin In-Flight Entertainment & PassengerAudio System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Embraer Master Drawing List 16006-001, Revision B, dated7 September2016, or later FAA approved revision.2. Instructions for Continued Airworthiness Document (ICA), EmbraerEngineering & Technology Center (EETC – USA) Document Number 16006-030,Revision A, dated 4 August 2016, or later approved rev...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/03/2018	Active	10065014

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065018	SOCIETE AIR FRANCE S.A.			A340-313	A340 aircraft -T-PED (Transmitting Personal Electronic Device) tolerance	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Airplane Flight Manual Supplement: AFMS-A340-17-009-001 original issue- Instructions for Continued Airworthiness: ICA-A340-17-009-001 originalissueor later revisions of the above listed documents approved by EASA. - Change Approval SheetCAS-A340-17-009 original issue	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/03/2018	Active	10065018
10065022	AVIATION SPECIALTIES UNLIMITED, INC		FAA STC SR02592SE	R66	NVIS Lighting System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement for Robinson Model: R66Night Vision Imaging System (NVIS) Doc. No: FMS-R66004-6 Revision B, dated 5 April 2018or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision)"U...	Installation limited to standard instrument panel configuration asdefined by drawings:- R66-0561-012, Rev C- R66-0561-013, Rev C- R66-0561-014, Rev C- and Master Drawing List, MDL-R66004-3The first installation of this kit must be supervised by the STC holder.Rotorcraft modified by this STC employ N...	30/04/2018	Active	10065022
10065039	AEROSPACE TURBINE ROTABLES, INC d/bKELLY AEROSPACE TURBINE ROTABLES, IAVCELLS, INC, AERO ELECTRIC, INC			SEE EASA APPROVED MODEL LIST	TR-245824 Burst Disk (Large Aeroplanes)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt 11: 25.601, 25.603(a)(b)(c), 25.613 (a),25.1195(b),25J1195(b), 25.1201(a)(b), 25J1201(a)(b), 25.1207, 25J1207,25.1301(a)(1) (2)(3), 25.1309(a)(1)The requirements...	-Drawing TR245824 Rev. A, dated 30 October 2014- TR-245824-ICA revision C, dated 29 January 2015- EASA-TR-245824-CERT, IR, dated 13 February 2018-TR-245824-COMP, rev N/A, dated 15 April 2015	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/03/2018	Active	10065039
10065049	DART AEROSPACE Ltd.			505	Installation of Bearpaws Auxiliary Skid Pad in accordance with MasterDocument List MDL-D505-1049.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Rotorcraft Flight Manual Supplement FMS-D505-1049 Revision A< (>,<)>or later revisions of the above listed documents approved by EASA inaccordance with the Technical ImplementationProcedures of EU/ CanadaBilateral Agreement.- Master Document List MDL-D505-1049 Revision A.- Installation Instructions-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/03/2018	Active	10065049
10065053	TELEDYNE BATTERY PRODUCTS		FAA STC SR00843DE	MBB-BK117 C-2	Installation of Teledyne Battery Products Gill LT Valve-RegulatedLead-Acid (LT-VRLA), P/N 7638-44, battery.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Teledyne Battery Products Document No. TD71-1-01, Master Drawing List,Installation of Teledyne Battery Products P/ N7638-44, Revision IR, dated19 March 2017, FAA approved 5 April 2017 or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Document No. TD 71-8-02,Revision NC, d...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/03/2018	Active	10065053
10065057	AEROSPACE TURBINE ROTABLES, INC d/bKELLY AEROSPACE TURBINE ROTABLES, IAVCELLS, INC, AERO ELECTRIC, INC			441 425	TR-245824 Burst Disk (General Aviation)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23 Amdt 4: 25.601, 25.603(a)(1)(2)(3)(b), 25.613(a),25.1195(a)(2)(b), 25.1201(a)(b), 25.1301(a)(b)(c)(d) Therequirements for environmental protection and the associated...	-Drawing TR245824 Rev. A, dated 30 October 2014- TR-245824-ICA revision C, dated 29 January 2015- EASA-TR-245824-CERT, IR, dated 13 February 2018-TR-245824-COMP, rev N/A, dated 15 April 2015	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/03/2018	Active	10065057

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065061	SCANDINAVIAN AVIONICS DESIGN ApS			AB412 EP	NVG compatible cockpit lighting and NVG friendly exterior lightingmodification, ref. 2103601.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	2103601-AM A, FLIGHT MANUAL SUPPLEMENT, Issue 2, dated 06 February 2018<(>,<)>or later revisions of the above listed document(s) approved under theEASA system.	This rotorcraft employs Night Vision Imaging System lighting, commonlynamed NVIS that has been certified to ensure the aircraft is compatiblewith Night Vision Googles (NVG). For this reason, interior and exteriormodification that add or change systems that emit or reflect light havethe potential to....	23/03/2018	Active	10065061
10065066	FLYING COLOURS CORP.		TCCA C-LSA17-119/D	CL-600-2B16 (604 VARIANT)	Interior Completion with Provisions For Air Ambulance Equipment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): CRI D-01 Width of Aisle.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areu...	- Modification Data Summary K604000 REV B dtd. 15 Mar 2018;- Airplane Flight Manual Supplement K604090 Rev. A dtd. 13.Mar 2018;- Mandatory Maintenance Manual Supplement K604075 Rev. A dtd. 9 Mar2018;or later revisions of the above listed document(s) approved on behalf ofEASA in accordance with the T...	- Airplane Flight Manual Supplement K604090.- Mandatory Maintenance Manual Supplement K604075.- Limited to serial No. 6092, 6105, 6114.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/e...	23/03/2018	Active	10065066
10065073	AIRBUS HELICOPTERS, Inc.		FAA STC SH4343SW-D	AS 350 B/ AS 350 B1/ AS 350 B2 AS 350 B3/ AS 350 BA/ AS 350 D	Installation of strobe anti-collision light installation and/orsupplemental strobe light.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List 350A82-1176, Revision Y, dated 25 April 1998, or later FAAapproved revision.Drawing List 350A82-1176, Revision AP, dated 9 June 2015<(>,<)> or laterODA approved revision.Instructions for Continued Airworthiness (ICA) 350MMS-030, Revision IR<(>,<)> dated 25 June 2015<(>,<)> or later FTW...	Installation of LED strobe anti-collision light for AS-350B2 andAS-350B3 models only.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect u...	26/03/2018	Active	10065073
10065076	MAGELLAN AEROSPACE		TCCA STC SH17-21 ISSUE 1	505	Installation of Wire Strike Protection System in accordancewithModification Data Summary EM107462.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Data Summary EM107462 Issue B- Instructions for Continued Airworthiness and Illustrated Parts ListPM-965-094 Issue C	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/03/2018	Active	10065076
10065078	HELI AUSTRIA GmbH	REV. 1		AS 332 L/ AS 332 L1 AS 332 L, AS 332 L1	Installation of GARMIN GTX Transponder SystemThis change covers the installation of a GARMIN GTX33DH/ GTX345DRTransponder, controlled by a Garmin GTN750.The installation of the GTN750 is not part of this installation.Rev. 1: Transponder Model deleted from title and description, CS ACNSissue 3 instead...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS ACNS issue 3:CS ACNS.D.ELS.001, CS ACNS.D.ELS.010, CS ACNS.D.ELS.015<(>,<)> CSACNS.D.ELS.020, CS ACNS.D.ELS.025,CS ACN...	Flight Manual Supplement, Doc. No. HAU-D-038-005, Rev. 1Master Document List, Doc. No. HAU-D-038-001, Rev. 1Installation Manual, Doc. No. HAU-D-038-004, Rev. 1Instructions for Continued Airworthiness, HAU-D-038-006, Rev. 1Or later revisions of the above listed document(s) approved/ acceptedunder the...	Required prerequisite for this change is the STC HAU-D-029 or a similarinstallation introducing a GTN650(Xi) or GTN750(Xi).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wi...	22/03/2022	Active	10065078
10065084	AEROLITE AG			CL-600-2B16 (604 VARIANT)	EMS interior P/N 650-0212923-501	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-01 Medical EvacuationDeviation(s):CRI D-02 Width of AisleThe requirements for environmental protection and the associatedcertified noise and/ or...	-Master Document List MDL-15-017 Rev. N/C dtd. 2018.03.26-Flight Manual Supplement FMS-650-0212923-501 Rev. 0 dtd. Mar 22/2018-Operations Manual OPM-650-0212923-501 Rev. 0 dtd. Mar 13/2018or later revisions of the above listed document(s) approved under theEASA system.	-Flight Manual Supplement FMS-650-0212923-501-Operations Manual OPM-650-0212923-501-Pre-requisite: EASA STC 10065066 (validated TCCA STC C-LSA17-119 D)“Interior Completion with Provisions for Air Ambulance Equipment”-Limited to serial No. 6092, 6105, 6114Prior to installation of this change/repair i...	27/03/2018	Active	10065084

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065089	JAMCO AMERICA, INC.		FAA STC ST02555SE	777-300ER	Installation of an interior reconfiguration on Boeing model777-300ERseries aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Jamco America, Inc. Master Drawing List (MDL) MDL2290-1, Revision B,dated 21 February 2018, or later Federal Aviation Administration (FAA) approved revision.Supplemental Instructions for Continued Airworthiness (ICA) ICA2290-1,Revision 1, dated 18 January 2018 and Supplemental Electrical WiringInterc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.STC ST03846NY, Installation of SuperSeal UltraLi...	28/03/2018	Active	10065089
10065094	JAMCO AMERICA, INC.		FAA STC ST01881SE-D	777-300ER	Installation of an interior reconfiguration on Boeing model777-300ERseries aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Jamco America, Inc. Master Drawing List MDL1268-1, Revision C, dated19 January 2010, or later Federal Aviation Administration (FAA) approvedrevision.- Instructions for ContinuedAirworthiness (ICA), Document NumberICA1268-1, Revision B, dated 8 January 2010, or later FAA approvedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This modification may not be installed after 7 J...	04/07/2018	Active	10065094
10065095	JAMCO AMERICA, INC.		FAA STC ST02116SE	777-300ER	Installation of Door 1 and Door 2 interior modification on Boeing Model777-300ER series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Jamco America, Inc. Master Drawing List (MDL) MDL1847-1, Revision A,dated 7 December 2015, or later Federal Aviation Administration (FAA) approved revision.Supplemental Instructions for Continued Airworthiness (ICA) DocumentNumber ICA1847-1, Revision 0, dated 13 November 2015 and SupplementalElectric...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The Supplemental Type Certificate (STC) installs...	27/03/2018	Active	10065095
10065104	LEARJET Inc.	REV. 2	FAA ST01842WI	LEARJET MODEL 45	Installation of Honeywell DU-875 Primus Elite cockpit display units inthe Learjet Model 40/45.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to LEARJET Inc. Master Document List BAS45017005,revision (c) dated July 14, 2017 FAA approved July 18, 2017;To be operated in accordance with LEARJET Inc. AFM-S Document No.current approved manual;To be installed i.a.w. Master Document List BAS45017005, revision (c) dated July 14, 2017 FAA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/04/2018	Active	10065104
10065107	LUFTHANSA TECHNIK AG			A340-313	VIP Conversion "Silence" Project	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-101 “Certification Basis”The requirements for environmental protection and the associatedcertified noiseand/ or emissions levels of the original product areunchange...	- Supplemental Type Definition Document, Ref. STDD00-16/23MIssue 01 Rev00- ICA, Ref. A-00-17/13-ICA Issue 01 Rev 00 (Section 4)- AFM, Ref. A-00-17/13-AFM Issue 01 Rev 00or later revisions of the above listed document(s) approved under theEASA system.- Compliance Record List, Ref. CRL00-16/23M issue...	As defined in the Airplane Flight Manual Supplement, Ref. A-00-17/13-AFM(Section 2), and the Instructions for ContinuedAirworthiness, Ref.A-00-17/13-ICA (Section 4).Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpr...	28/03/2018	Active	10065107

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065108	DIAMOND AIRCRAFT INDUSTRIES GmbH	REV. 9		DA 62	DA 62 MPP Basic OptionsRevision "n" of STC 62-001 certifiesthe BR-700 Pod – Module M180Revision "q" of STC 62-001 certifies an additional exhaust option.Revision "ab" certifies Maximum Take-Off Mass 2360 kg with PPC 185.Revision "aa" certifies Maximum Take-Off Mass 2360 kgRevision “ag” certifies La...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase and/or emission levels.	Installation per Supplemental AMMs:Doc. No. 7.02.25-M00 Rev. 0Doc. No. 7.02.25-M20 Rev. 0Doc. No. 7.02.25-M30 Rev. 2Doc. No. 7.02.25-M50 Rev. 0Doc. No. 7.02.25-M70 Rev. 0Doc. No. 7.02.25-M80 Rev. 0Doc. No. 7.02.25-M90 Rev. 0Doc. No. 7.02.25-M130 Rev. 0Doc. No. 7.02.25-M180 Rev. 0Operation accordingS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/05/2025	Active	10065108
10065111	LUFTHANSA TECHNIK AG			A321-231, A321-232 A321-211, A321-212, A321-213 A321-111, A321-112, A321-131 A320-251N, A320-271N A320-232, A320-233 A320-215, A320-216, A320-231 A320-211, A320-212, A320-214 A319-132, A319-133 A319-114, A319-115, A319-131 A319-111, A319-112, A319-113	Increase of seating capacity.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:As defined in the CRI A-01 “Certification Basis”.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original p...	- Supplemental Type Design Document STDD25-16/31M Issue 01,Revision 00<(>,<)>or later revisions of the above listed document(s) approved under theEASA system.	The following conditions must be met by any dependent cabinmodification:- An unobstructed door opening of at least 32inch x 73inch for the overperforming exit configuration.- A TSO C69-c qualified evacuation device installed on each overperforming exit configuration.- A passageway width of at leastt...	28/03/2018	Active	10065111
10065112	BERINGER AERO	REV. 5		PA-46R-350T, PA-46-350P PA-46R-350T PA-46-600TP PA-46-500TP PA-46-350P PA-46-310P, PA-46-500TP PA-46-310P	Servicing instruction & SensAIR optionRevision 2 of this STC introduces an adapter for the tow bar.Revision 3 is an administrative change and addition of SensAIR optionKitweight correction.Revision 4 accounts for modificatio...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List, document MDL-STC-017 Rev. 5 dated 08 October 2024;Installation and Instructions for Continued Airworthiness, documentICA-STC-017 Rev. 6 dated 03 October 2024.or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/10/2024	Active	10065112
10065115	AIRBORNE TECHNOLOGIES GmbH			P.68R "VICTOR"	Flight into known icing	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-01The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable...	Flight Manual Supplement STC-103-0-AFM Rev. o Issue 8.3.2018or later revisions of the above listed document(s) approvedunder theEASA system.STC-AT-103-G-ASInstallation Instruction STC-103-0-II Rev. 3 initial issue 9.3.2018Maintenance Manual Supplement STC-103-0-AMM Rev. 1 initial issue8.3.2018	None	28/03/2018	Active	10065115
10065118	ALAMO ENGINEERING GmbH	REV. 2		750	Installation of modifications for introduce ADS-B Out capability onCessna Citation X aircraft equipped with Primus II Radio Suites.Revision 2: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-ACNS, Initial Issue,dated 19.12.2013.The requirements for environmental protection and the associatedcertified noise an...	Installation in accordance with 328 Design Master Document List ref MDL139Z001 Rev B dated 03 May 2018.Operate in accordance with 328 Design Airplane Flight Manual Supplementref AFMS024K345Z001 Rev B dated 03 May 2018.or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10065118

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065119	LUFTHANSA TECHNIK AG			A319-131, A319-132	SAS LOPA Change.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Refer to the CRI A-01 for EASA STC 10065111.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original produc...	- Supplemental Type Design Document STDD25-17/08M Issue 01 / Revision01;- Instructions for Continuous Airworthiness, Ref. A-00-18/03-ICA Issue01 Revision 03 (Chapter 4 / Airworthiness Limitation Section);or later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/03/2018	Active	10065119
10065133	NSE	REV. 1		BN2T, BN2T-2, BN2T-2R BN2T-4S BN2T-4R, BN2T-4S BN2T-2, BN2T-2R, BN2T-4R BN2, BN2A, BN2A-2, BN2A-3 BN2B-26, BN2B-27, BN2T BN2B-26, BN2B-27 BN2B-20, BN2B-21 BN2A-6, BN2A-8, BN2A-9 BN2A-27, BN2B-20, BN2B-21 BN2A-27 BN2A-20, BN2A-21, BN2A-26	Installation of a tracking system DTS V2, transmitting the aircraftposition over the Iridium satellites.Rev. 1: New DTSV2 amendment and modification of the supporting bracket.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Doc. No. 00022011AA “STC Document List For DTSV2 on BN2T”, Issue A2,dated 25/03/2024or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Embodiment of STC 10065133 is pre-requisite for this change.The approval holder shall fulfill the obligations of Part 21, Point21A.109.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/e...	27/03/2024	Active	10065133
10065134	AIRBUS S.A.S.			A380-841, A380-842, A380-861	A380 - STC ACJC -INSTALLATION OF A380 2KU ANTENNA.Installation of a large antenna on top aft part of A380 fuselage, forconnectivity capacity (Wifi) in the passenger cabin. This modificationcovers only the definition and installation of "Outside AircraftEquipment (OAE)" and associated wiring. Systems...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI C-02 Vibration and BuffetingAerolastic Stability Requirements Compliance Criteria.The requirements for environmental protection and the a...	- MAS CJ2148 issue 01.- MPD- Supplement ref: MPD-S A380 MODCJ2148 Rev 00.	None	05/04/2018	Active	10065134
10065135	AVIONIK STRAUBING ENTWICKLUNGS GmbH			C90GTI C90GT C90A	Installation of Garmin GA35 and/or L-3 Communications NY-164 antenna(s)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Avionik Straubing modification referenceASR-2017-002 as defined in MDL ref ASR-2017-002-MDL-01-00 dated01.03.2018 and Instructions for Installationref ASR-2017-002-IFI-10-00dated 23.02.18.Instructions for Continued Airworthiness (ICA) in accordance withAvionik Straub...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/04/2018	Active	10065135
10065145	BLACKHAWK MODIFICATIONS Inc.	REV.1	FAA STC SA02658LA	B300/ B300C, 300, 300LW B300, B300C, 300, 300LW	Replacement of the original Pratt and Whitney PT6A-60A engines andpropellers with Pratt and Whitney PT6A-67A engines and MT PropellerMTV-27-1-N-C-F-R(P)/ CFR260-65b propellers or Hartzell HC-E5A-3A/NC10245Bpropellers	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02658LA.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Drawing List 200914-00, Rev. A dated 23 May 2017, orlater FAAapproved revisions.Pilot’s Operating Handbook and Airplane Flight Manual Supplement AFMS200914-20, Rev. IR dated 14 August 2017, or later FAA approved revisionis required.The following Pilot's Operating Handbook and FAA approved Fl...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Dual aft body strakes installed per LBA approved...	03/11/2020	Active	10065145

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065149	AEROSPACE TURBINE ROTABLES, INC d/bKELLY AEROSPACE TURBINE ROTABLES, IAVCELLS, INC, AERO ELECTRIC, INC			S-76A, S-76B, S-76C 212, 412, 412EP	TR-245824 Burst Disk - CS-29.STC approval of FAA-PMA approved critical PMA part.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Drawing TR245824 Rev. A, dated 30 October 2014.- TR-245824-ICA revision C, dated 29 January 2015.- EASA-TR-245824-CERT, IR, dated 13 February 2018.- TR-245824-COMP, rev N/A, dated 15 April 2015.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/04/2018	Active	10065149
10065167	VENTURA AEROSPACE, Inc.		FAA STC ST02667LA	737-800	Installation of 9g Rigid Cargo Barrier.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Ventura Aerospace, Inc. Master Data List VA-MDL-1006, Revision A,dated 13 March 2018 or later FAA approved revision.2. 737-800 Boeing Converted Freighter (BCF) (Boeing Top Drawing number800A0003, Revision C, dated 27 March 2018, or later FAA approvedrevision).3. Instructions for Continued Airwort...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The 9g Rigid Cargo Barrier Installation maximum,...	09/04/2018	Active	10065167
10065171	ANCRA INTERNATIONAL LLC		FAA STC ST02666LA	737-800	Installation of main deck cargo loading system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ancra International LLC Controlled Data List DL85600, Revision C, dated4 December 2017, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.737-800 Boeing Converted Freighter (BCF) (Boeing...	09/04/2018	Active	10065171
10065174	ANDERSON, THOMAS RICHARD		FAA STC SA00800SE	SEE FAA APPROVED MODEL LIST	Installation of Steel Main Landing Gear.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved Master Drawing List as specified on AML SA00800SE.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	10/04/2018	Active	10065174
10065175	ANDERSON, THOMAS RICHARD		FAA STC SA2359NM	SEE FAA APPROVED MODEL LIST	Installation of tail wheel assembly.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved Master Drawing List as specified on AML SA2359NM.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	10/04/2018	Active	10065175
10065179	FINNOFF AVIATION PRODUCTS, LLC		FAA SA02266LA	PC-12/45, PC-12/47	Installation of a Pratt and Whitney PT6A-67P Engine upgradewithoptional 2nd Battery installation and optional Generator2 ExhaustDucting installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Master Drawing List (MDL) No.0201-00100, Revision A, dated 11th November 2011;Operate in accordance with AFM Supplement FTA-FIN-001022, Revision A,9th March 2012 and maintain in accordance with ICAs, FTA-FIN-001014,Revision A dated 18th February 2012;or later revision...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/04/2018	Active	10065179

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065186	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA ST03221CH	ERJ 190-100 STD ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ	EASA validation of FAA STC ST03221CH.Certification of compatibility with cellular and wireless datatechnologies in accordance with Armstrong Aerospace Master Data List,Doc. No. DC104-9212-00, Revision E, dated September 26th, 2016 or laterapproved revisions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: EASA CS 25.1309(a) andCS 25.1529, at initial issue.The requirements for environmental protection and the associatedcertifi...	Armstrong Aerospace Master Data List, Doc. No. DC104-9212-00, RevisionE, dated September 26th, 2016< (>,<)>or later revisions of the above listed document (s) approved on behalf ofEASA in accordance with the Technical Implementation Procedures of EU/USA Bilateral Agreement.	See those of original FAA STC ST03221CH, particularly concerningapplicable limitations for installations utilizing Cellularcompatibility aspects, or Wireless Data Technologies compatibilityaspects or both Cellular and Wireless Data Technologies compatibilityaspects of this Supplemental Type Certific...	10/04/2018	Active	10065186
10065200	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	757-200PF 757-200	Introduction Of An Underwater Locator Beacon (ULB).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Non-rechargeable Lithium BatteryInstallations.- The following paragraph(s) ata later amendment: CS 25 Amendment 20:CS25.601; CS25.603; CS...	STC TWENTY ONE MASTER DOCUMENT LIST No. S21. MDL-1383 ISSUE1.	None	10/04/2018	Active	10065200
10065214	WILLIBALD LANG			LS 3-A	Bau und Anbringung von Winglets.Die Maßnahme umfasst den Bau von Winglets in Formen, sowie dasAnbringender Winglets an den Flächenenden der LS3-a.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:JAR 22.375 Winglets.The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	Zeichnung: Winglet (LS3, a) Li / Re Nr.: LS3-1311 Li/ -1312ReCompliance Checklist LS3-a vom 13.03.2018Ergänzungen zum Flughandbuch vom 01.02.1995or later revisions of the above listed document(s) approved under theEASA system.	Only for Sailplane LS3-a, Werk-Nr.: 3183.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/04/2018	Active	10065214
10065220	AIRBUS HELICOPTERS, Inc.	REV. 3	FAA STC SR09500RC-D	EC 130 B4, EC 130 T2 AS 350 B2, AS 350 B3	Installation of L-3 Trilogy ESI-2000 or ESI-500 Electronic StandbyIndicator.Rev. 3: adds an optional configuration witha new ICA.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Helicopter, Inc. drawing list 350A82-1791 Revision B, dated 7February 2014;Configuration -01: AS 350 B2/ AS 350 B3 models:- Rotorcraft Flight Manual Supplement (RFMS) 350FMS-528 Revision IR,dated 6 March 2014;- Instructions for Continued Airworthiness (ICA) 350MMS-028 Revision IR,dated 12 Feb...	Rotorcraft modified under this STC are required to have an approvedprimary flight instrument system installed on the rotorcraft because theL-3 Trilogy ESI-2000 or ESI-500 does notreplace the required VFRrotorcraft instruments.Prior to installation of this design change it must be determined thatthe...	21/01/2022	Active	10065220
10065222	PMV ENGINEERING	REV. 1		737-800/-900/-900ER 737-300/-400/-500/-600/-700	The STC consists on the installation of the ADSB-OUT function on B737 NGRev 0: - Initial STC for the B737 /-600 /-700 /-800 / -900 /-900ER models - Limitation to Transponder Rockwell Collins TPR-901822-1338-205 and MMR Rockwell Collins GLU-920 822-1152-004.Rev 1: - Extension to the...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): SC H-01 - EWIS.- the following paragraph(s) at a later amendment: CS25 amdt 4:25.1301(a)(b)(c), 25.1302(b), 25.1309(a)(b)(c), 25.1322(a)(b)(c)(d),2...	- Master Document List AVI-01670-MDL-R10, dated 20 JUN 2019- Aircraft Flight Manual Supplement AVI-01670-AFMS-R02, dated 17 MAY2019- Instructions for Continued Airworthiness AVI-01670-ICA-S01-R02, dated17 MAY 2019- Instructions for Continued Airworthiness AVI-01670-ICA-S02-R02, dated17 MAY 2019- Ins...	STC limitations and configurations are defined in the applicableAircraft Flight Manual Supplement ref. AVI-01670-AFMS.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will in...	28/06/2019	Active	10065222
10065226	COMTECH GLOBAL AVIATION SERVICES S.	REV. 1		A321-231, A321-232 A321-211, A321-212, A321-213	Introduction of Centre Fuel Tank Ignition Mitigation ReticulatedPolyurethane Foam.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 25.29; 25.301(a)(b); 25.303; 25.307(a); 25.321(a); 25.333; 25.343(a); 25.601; 25.603;25.605(a); 25.609; 25.611; 25.901 [a(1...	- Certification Report CTE-CR0181-01, dated 11/03/2018- Aircraft Flight Manual Supplement CTE-AFM0181-01, dated 19/10/2017- Instruction for Continued Airworthiness CTE-TP0181-01 Rev B, dated11/03/2018or later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/04/2019	Active	10065226

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065227	APTOZ EHF.	REV. 3		737-8, 737-9	New seating layout with160 total passengers using AVIO seats with ZiiRave IFE and ISPS systems.Rev. 2: Transfer of STC from Icelandair EHF to Aptoz EHF.Rev. 3: Typo correction.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 Amdt 18: 1,29 (a)(b), 301(a), 302, 303, 307(a), 365(g), 561(b)(c)(d), 562 (a)(b)(c), 571, 601, 603(a)(b...	- Change/repair Approval CRA-737-2520-087 Revision A- Aircraft Flight Manual Supplement AFM-737-2520-087 Revision A;or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/06/2025	Active	10065227
10065229	CORPORATION LOGIC AIR Inc.	REV. 1		737-500 737-400 737-300	Structural Provisions for Dual GPSInstallation of structural provisions for dual GPS antennas onB737-300/-400/-500 aircraft.This STC is approved as AMOC to FAA ADs: 2008-09-13 and2013-18-08.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-K388-102-001-002 Rev. B “Modification Data Summary”- K388-102-001-012 Rev. B “Mandatory Maintenance Manual Supplement”or later revisions of the above listed document(s) approved on behalf ofEASA in accordance with the Technical Implementation Procedures of EU/Canada Bilateral Agreement.	After embodiment of this STC, the aeroplane must be maintained inaccordance with the applicable instructions for continued airworthiness,report K388-102-001-012Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevious...	30/04/2018	Active	10065229
10065231	NSE	REV. 2		R44, R44 II	Installation of Usage Monitoring System Brite SAVER 2 (BS2)P/NsKIT-PE0-53-00 and KITR-ARA0-53-00 in accordance with Conformitystatement and Document Architecture 00021778AA_A2 dated 26/03/2018.Rev. 1: Installation of Usage Monitoring System Brite SAVER 2 (BS2) P/NsKIT-ARA0-53-00 and KIT-ARA1-53-00s...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Initial Issue:- Rotorcraft Flight Manual Supplement for Brite Saver 2 Usage MonitoringSystem 00020430AA-A1,dated 23/02/2018.- Instruction for Continued Airworthiness Brite Saver 2Usage MonitoringSystem 00020435AA-A1,dated 09/01/2018- Conformity Statement and Documentary Architecture 00021778AA-A2,2...	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the a...	08/09/2022	Active	10065231
10065237	E A D AEROSPACE AIRWORTHINESS	REV. 2		A321-253N/-272N A321-213/-231/-232/-271N/-251N A321-111/-112/-131/-211/-212 A320-231/-232/-233/-251N/-271N A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	KA-BAND Installation on Airbus SAThe present Major Change to STC 10065237 Rev 1 (issued 26 Nov 2019)consists in adding a new design change configuration by installing theKA-BAND Satcom antenna on existing SBB antenna doubler. This designchange requires small adaptation of the installation, and revis...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-0301-002 (Vibration/buffetingcompliance criteria for large external antenna installation)The requirements for environmental protectionc...	- Master Document List, EAD Aerospace document No. 01535-EAS-B-MDL,Revision H, dated 25 June 2020.- Airplane Flight Manual Supplement, EAD Aerospace document No. 01535-EAS-B-AFM-01, Revision C.- Design Similarity Statement 01535-EAS-B-DSS-02 rev C, dated 25 June2020.- Instructions for Continued Airwo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/06/2020	Active	10065237
10065246	CONCORDE BATTERY CORPORATION		FAA STC SA02653LA	510	Replacement of original equipment main battery with Concorde RG-390E/30Valve Regulated Lead-Acid battery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List 5-0598, Revision A, dated 22 March 2017, or laterFAA Approved Revisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/04/2018	Active	10065246
10065278	JET AVIATION AG			767-300	WIRELESS LAN (W-LAN) ACTIVATION.This STC demonstrates immunity to IEEE 802.11 a/b/g/n/ac passengers' PEDtransmissions on the B767-300 series. The installation of Wireless-LAN(WLAN) system is not part of this STC, however the system specificationshave been included in Engineering Order as pre-requisi...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-25 Amendment 20:25.789, 25.831, 25.869, 25.1301, 25.1309, 25.1351, 25.1353, 25.1357,25.1360, 25.1431, 25.1529, 25.1581T...	- Airplane Flight Manual Supplement, Doc. No. JBSL-M-01012AFM-01, Issue01;- Master Data List, Doc. No. JBSL-M-01012MDL-01, Issue 01;- Certification Compliance Sheet, JBSL-M-01012CCS-01, Issue 01or later revisions of the above listed documents approved by EASA.	: This change is applicable to Boeing B767-300 series previously fittedwith certified:- Wireless Access Point(s) capable to transmit only onIEE802.11a/b/g/n/ac protocols, or a subset of these protocols, with notmore than 1000 mW transmitted power capacity;- The WAP power supply must be supplied thro...	18/04/2018	Active	10065278

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065284	DASSAULT FALCON JET		FAA STC ST10256SC-D	FALCON 2000EX	Aircraft Compliance for Falcon 2000EX S/N 54	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Data List Report No. F2EX-07001-D054, Revision A dated 28 April 2005,or later FAA approved revision.2. FAA Approved AFM Supplement, Report 37159-F2EX-D054 dated 29 April2005.3.Supplemental Maintenance Manual, Report SMM F2000EX-S/N 054dated APR2005.	Descriptive data pertaining to this design change are consideredinadequate for duplication on other products.This approval is limited to only the installation made in DassaultAviation Model Falcon 2000EX S/N 54.This STC does not permit manufacturing of parts for multipleinstallations.Prior to instal...	19/04/2018	Active	10065284
10065285	DASSAULT FALCON JET CORPORATION		FAA STC ST10574SC-D	FALCON 2000EX	Aircraft Compliance for Falcon 2000EX S/N 115	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Data List Report No. F2EX-07001-D109<(>,<)> Revision NC dated 7 May2007, or later FAA approved revision.2. FAA Approved AFM Supplement, Report 37159-F2EX-D109 dated 8 May 2007or later FAA approved revision.3. Supplemental Maintenance Manual, Report SMM F2000EX SN115 dated April2007 or later FAA a...	You cannot use descriptive data about this design change toduplicateother products.This approval is limited to only the installation made in DassaultAviation Model Falcon 2000EX Serial No. 115.This STC does not permit manufacturing of parts for multipleinstallations.Prior to installation of this ch...	19/04/2018	Active	10065285
10065287	DASSAULT FALCON JET CORPORATION		FAA STC ST10522SC-D	FALCON 2000EX	Aircraft Compliance for Falcon 2000EX S/N 91	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Data List Report No. F2EX-07001-D091, Revision A dated 14 December2006, or later FAA approved revision.2. FAA Approved AFM Supplement, Report 37159-F2EX-D091 dated 15 December2006 or later FAA approved revision.3. Supplemental Maintenance Manual, Report SMM F2000EX-SN 091, RevisionC dated Decembe...	You cannot use descriptive data about this design change toduplicateother products.This approval is limited to only the installation made in DassaultAviation Model Falcon 2000EX S/N 91.This STC does not permit manufacturing of parts for multipleinstallations.Prior to installation of this change/rep...	19/04/2018	Active	10065287
10065288	DASSAULT FALCON JET CORPORATION		FAA STC ST10521SC-D	FALCON 2000EX	Installation of ST3100 Satellite Telephone System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Data List Report No. F2EX-01017, Revision NC dated 8 December 2006,or later FAA approved revision.2. FAA Approved AFM Supplement, Report 37786-1 dated 15 December 2006,or laterFAA approved revision. 3. Maintenance Manual Supplement, Report 37549, Revision D dated 8December 2006 or later FAA appro...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/04/2018	Active	10065288
10065292	DASSAULT FALCON JET CORPORATION		FAA STC ST10265SC-D	FALCON 2000EX	Installation of Service and Indirect Lighting System for Falcon 2000EX	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Data List Report No. F2EX-01001 Revision B dated 20 June2005, orlater FAA approved revision.2. Maintenance Manual Supplement Report No. 37409 dated 17 May 2005 orlater approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/04/2018	Active	10065292

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065294	LUFTHANSA TECHNIK AG	REV. 1		A340-313	Intrusion Detection System InstallationRevision 1: This modification enlarges a cut-out in the fuselage toimprove maintenance accessibility when replacing the aft quad-cam.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Design Document, Ref. STDD31-17/01M, Issue 2, Rev.0, dated 08 July 2019;- Airplane Flight Manual Supplement, Ref. A-00-17/80-AFM, Issue 1,Rev.1, dated 21 March2019;- Instruction for Continued Airworthiness, Ref. A-00-17/80-ICA, Issue 3,Rev. 0, dated 26 June 2019or later revision...	- The EASA STC 10033112 (VIP Cabin Conversion) must be installed- As per ICA, Ref. A-00-17/80-ICA, Section 4Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no...	29/10/2019	Active	10065294
10065295	DASSAULT FALCON JET CORPORATION		FAA STC ST10412SC-D	FALCON 2000EX	Aircraft Compliance for Falcon 2000EX S/N 59	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Data List Report No. F2EX-07001-D059<(>,<)> Revision NC dated 27 July2005, or later FAA approved revision.2. FAA Approved AFM Supplement, Report 37159-F2EX-D059 dated 2 August2005.3. Supplemental Maintenance Manual, Report SMM F2000EX-SN 059 dated July2005.	Descriptive data pertaining to this design change are consideredinadequate for duplication on other products.This approval is limited to only the installation made in DassaultAviation Model Falcon 2000EX S/N 59.This STC does not permit manufacturing of parts for multipleinstallations.Prior to instal...	19/04/2018	Active	10065295
10065296	DASSAULT FALCON JET CORPORATION		FAA STC ST10507SC-D	FALCON 2000EX	Aircraft Compliance for Falcon 2000EX S/N 86	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Data List Report No. F2EX-07001-D086<(>,<)> Revision C dated 21August 2006, or later FAA approved revision.2. FAA Approved AFM Supplement, Report 37159-F2EX-D086 dated 22 August2006, or later FAA approved revision.3. Supplemental Maintenance Manual, Report F2000EX-SN 086 dated August2006, or late...	You cannot use descriptive data about this design change toduplicateother products.This approval is limited to only the installation made in DassaultAviation Model Falcon 2000EX S/N 86.This STC does not permit manufacturing of parts for multipleinstallations.Prior to installation of this change/rep...	19/04/2018	Active	10065296
10065303	APTOZ EHF.	REV. 1		767-300 SERIES 767-300	Installation of Thales Integrated Electronic Stand-by Instrument (IESI,V2 Family 2) P/N C16786AAA02.Rev. 1: change of Holder, FAA Original STC number removed.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. Master Document List (MDL) Document number CRA-767-3420-012, RevisionD, dated 27 March 20182. Aircraft Flight ManualSupplement (AFMS) Document numberAFM-767-3420-012, RevisionA approved on 7 March 20183. Instructions for Continued Airworthiness (ICA) Document numberCAI-767-3420-012, Revision A,...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/10/2025	Active	10065303
10065308	ALAMO ENGINEERING GmbH	REV. 1		HAWKER 900XP HAWKER 850XP HAWKER 800XP, HAWKER 850XP, HAWKER 800XP	Swift Broadband SBB Satcom with WiFi.Revision 1: Transfer to ALAMO Engineering GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 14CFR Part 25,Amendment 25-1 through 25-97The requirements for environmental protection and the associatedcertified noiseu...	-Installation according to Master Document List MDL138Z001 Issue B,dated 19/04/2018-Operation according to Aircraft Flight Manual SupplementAFMS022A231 Z0001 Issue A, dated 04/04/2018-Maintenance according to Aircraft Maintenance Manual SupplementAMMS022A231 Z0001 Issue A, dated 04/04/2018or later rev...	Limited to aircraft with Rockwell Collins Proline 21 avionics suiteinstalled.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwort...	05/11/2024	Active	10065308

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065309	WEST STAR AVIATION, L.L.C.		FAA STC ST04120CH	MYSTÈRE FALCON 900 (MF900)	Installation of a Datalink Communications System supportingAir TrafficServices (ATS) using Honeywell MK-III Communications Management Unit (CMU), Honeywell TR-865B VHF Datalink radio, Aircell Axxess IridiumSatcom, and a GoGo Iridium Data Interface Unit (DIU).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. West Star Aviation, Master Data List Document No. DB1504002 RevisionB, dated 11 July 2016, or later FAA approved revision.2. Airplane Flight Manual Supplement (AFMS) DB1504005 Revision IR dated16 August 2016, or later FAA approved revision.	The aircraft CVR must be capable of supporting CPDLC data linkrecording.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airwo...	25/04/2018	Active	10065309
10065314	GFD GmbH	REV. 1		35A	Iridium Satcom Antenna Installation ProvisionRev. 1: Transfer to GFD GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to AIEC Master Data List No. EA5562-049, Rev. IRTo be installed i.a.w. AIEC drawing list EA5562-082, Rev IRTobe maintained i.a.w. AIEC ICA Document No. EA5562-085, Rev IRor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10065314
10065315	LUFTHANSA TECHNIK AG	REV. 1		A321-271NX/-272NX A321 – 271N, A321 – 272N A321-271N/-272N A321 – 252N, A321 – 253N, A321-251NX/-252NX/-253 NX A321-251N/-252N/-253N A321 – 232, A321 – 251N, A321-231/-232 A321 – 213, A321 – 231, A321 – 211, A321 – 212, A321-211/-212/-213	Zonal Drying System InstallationRevision 1: extended applicability	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: EASA CS 25.0029,25.0301, 25.0303, 25.0305, 25.0307, 25.0365, 25.0571, 25.0581, 25.0601,25.0603, 25.0609, 25.0...	Supplemental Type Design Definition STDD21-17/01M issue 3 rev. 0Instructions for Cont. Airworthiness A-00-18/32-ICA Issue 5 rev 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	As defined in section 4 of the ICA document, Ref. A-00-18/32-ICAPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the...	12/01/2023	Active	10065315
10065316	DASSAULT FALCON JET CORPORATION	REV. 3	FAA STC ST01615WI-D	MYSTÈRE FALCON 900 (MF900)	Upgrade Honeywell FMZ-2000 Flight Management System (FMS) to SoftwareVersion NZ 6.1.1 (Nav Computer Part No. 7018879-03046 (NZ-2010)) andreplace or upgrade Honeywell Global Positioning System (GPS) NavigationSystem Sensor Unit (GNSSU) to enable Wide Area AugmentationSystem/Localizer Performance with...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01615WI-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Duncan Aviation Inc., Master Document List No. 101029004, Revision A,dated 17 December 2010;2. FAA Approved AirplaneFlight Manual Supplement, Duncan Aviation Inc.,Document No., 081120040, Revision A, dated 17 December 2010, or laterFAAApproved Revisions to (1) or (2).	Applicable only to airplanes equipped with Honeywell SPZ-8000 FlightControl System (FCS) and EDZ-820 Electronic Flight Instrument System(EFIS) Displays with dual or triple NZ-2000Flight Management System.Until such time that the TAWS Mode-5 protection is available, theapproval will be limited to ap...	30/03/2020	Active	10065316
10065350	INTER-TEC AERO DESIGN AND CERTIFICALIMITED	REV. 2		A321-231, A321-232. A321-213/-231/-232 A321-212, A321-213, A321-131, A321-211, A321-111, A321-112, A321-111/-112/-131/-211/-212 A320-232, A320-233, A320-231/-232/-233 A320-216, A320-231, A320-214, A320-215, A320-211, A320-212, A320-211/-212/-214/-215/-216 A319-132, A319-133, A319-131/-132/-133 A319-115, A319-131, A319-113, A319-114, A319-111, A319-112, A319-111/-112/-113/-114/-115	Installation of pitch aircraft seating system models PF3200and PF3300seatsRev. 2: Transfer of STC holder from INTER-TEC SERVICES Ltd to INTER-TECAERO DESIGN AND CERTIFICATION LIMITED.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Tenencia Ltd. Master Data List No. 745 issue 1?or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/12/2021	Active	10065350

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065355	S4A SOLUTIONS FOR AVIATION, S.L			EMB-135BJ	CABIN MANAGEMENT SYSTEM & WLAN IN EMB-135BJ (MSN 14501094)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- 14505-HDK01 Flight Manual Supplement Edition 2or later revisions of the above listed documents approved by EASA.- 14505-SB001 Service Bulletin Edition 1- 14505-HDK02 MaintenanceManual Supplement Edition 2	Airworthiness Approval Limited to Airplane EMB-135BJ MSN 14501094.	25/04/2018	Active	10065355
10065358	FLINT AERO, INC.		FAA STC SA2676WE	207/ 207A/ T207/ T207A	Installation of larger fuel containing wing tips.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	FAA sealed Flint Aero Data List No. DL FA200, Revision A orsubsequentFAA sealed revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The limitations and conditions of Data Sheet A16...	29/05/2018	Active	10065358
10065359	DASSAULT FALCON JET CORPORATION			FALCON 900EX	Validation of FAA STC ST10982SCAvionics and Interior Installations	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Data List Report No. F9EX-01087 Revision B dated17-July-2012- Aircraft Flight Manual Supplement Report No.37159-F9EX-D466 dated 17July 2012-Supplemental Maintenance Manual Report SMM F900EX-SN 250, RevisionOriginal, dated 13-July-2012or later revisions of the above listed document(s...	This approval is limited to Falcon 900EX Serial Number 250.Prior to installation of this change it must be determined that theinterrelationship between this change and any other previously installedchange will introduce no adverse effect upon the airworthiness of theproduct.	25/04/2018	Active	10065359
10065360	AIRBUS DEFENCE AND SPACE S.A.			A330-243	DCV0536S. FSTA EFB Fitting Device Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Defence and Space, doc. no. TEA-FU-DT-180008, issue B, dated 23March 2018or later revisions of the above listed document(s) approved under theEASA system.	This STC can only be installed if one of the following EASASTC ispreviously installed:• A330 FSTA STC1 10034690 or• A330 FSTA STC2 10035945Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changee...	25/04/2018	Active	10065360
10065369	airplus engineering GmbH	REV. 1		DHC-6 SERIES 400	Installation of AMT-1800 IG Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MD-2124-000000, Iss. 1- Master Drawing List DL-2124-000010, Iss. 1- Maintenance Manual Supplement MM-2124-000000, Iss. 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/02/2021	Active	10065369
10065371	AIRBORNE TECHNOLOGIES GmbH	REV. 1		P.68 "VICTOR", P.68R "VICTOR" P.68TC "OBSERVER" P.68 "OBSERVER 2" P.68 "OBSERVER" P.68C, P.68C-TC	SBAS enable / This design change approves the navigation using GPS andSBAS with the installed Garmin G950Revision 1: Transfer from ADOA to DOA	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- STC-114-G-DOC, Document List, Revision 1, 20th of April 2018- STC-114-0-AFM, Aircraft Flight Manual Supplement, Revision 2, 20th ofApril 2018or later revisions of the above listed document(s) approved under theEASA system.	The following modifications must be incorporated prior to thecompletions of this change: P68/240; P68/86; P68/127; P68/311.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wi...	25/01/2021	Active	10065371

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065373	HAECO CABIN SOLUTIONS, LLC		FAA STC ST03940AT	A330-243F A330-243 A330-223F A330-223 A330-203 A330-202 A330-201	Installation of TIMCO Aerosystems lavatories in an Airbus A330-200Series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TIMCO Aerosystems Master Data List (MDL) 10T176L001, Revision IR, dated14 April 2012, or later FAA approved revisions.TIMCO Aerosystems Instructions for Continued Airworthiness 10T176R009,Rev. B, dated 6 April 2012, or later FAA accepted revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2018	Active	10065373
10065374	HAECO CABIN SOLUTIONS, LLC		FAA STC ST03939AT	A330-343 A330-342 A330-341 A330-323 A330-322 A330-321 A330-303 A330-302 A330-301	Installation of TIMCO Aerosystems lavatories in an Airbus A330-300Series aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TIMCO Aerosystems Master Data List (MDL) 10T176L501, Revision IR, dated29 November 2012, or later FAA approved revisions.TIMCO Aerosystems Instructions for Continued Airworthiness10T176R509, Rev. A, dated 20 November 2012, or later FAA accepted revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2018	Active	10065374
10065375	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04223AT	777-300ER	Interior reconfiguration installation for Boeing 777 -300ERSeriesaircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- TIMCO Aerosystems, LLC Master Data List 14T039L001, Revision J, dated02 April 2018, or later FAA approved revisions.- TIMCO Aerosystems<(>,<) > LLC Instructions for Continued Airworthiness14T039R009, Revision D, dated 6 February 2018 and 14T039R509 Revision Edated 3 March 2018, or later FAA accepte...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2018	Active	10065375
10065394	B/E AEROSPACE, Inc.		FAA STC ST04421AT	737-900/-900ER 737-600/-700/-700C/-800	Installation of the Honeywell MK II Aircraft Communication,Addressing,and Reporting System (ACARS) with Data Link Communication Function inthe B737-NG Series Aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List (MDL) 2-153882-001, Rev. A, Dated 20November2017, or later FAA approved revision.2. Airplane Flight Manual Supplement for the Honeywell MK II AircraftCommunication, Addressing<(>,<)> and Reporting System (ACARS) with DataLink Communication Function< (>,<)> 2-153882-807, Rev IR...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/04/2018	Active	10065394
10065403	AEROSERVIS, S.R.O.			L 410 UVP-E20, L 410 UVP-E9, L-410 UVP-E	Replacement of the original electric fuel booster pump by BP-DCA-06 pump	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Elect toComply requirements: CS-23 Amdt. 423.29, 23.301 (a), (b), (c), 23.305, 23.603, 23.607, 23.609, 23.611,23.613 (b)(1), (b)(2), 23.863, 23.901 (b), 23.943, 23.951, 2...	- Master Document List doc. No. AE164000X, revision G, dated 12.03.2018- L410 UVP-E, -E9 and -E20 Maintenance Manual (Do-L410-1232.2) Supplement doc. No. STC AE/164-DTP1, issued November 2017- L410 UVP-E, -E9 and -E20 Wiring Manual (Do-L410-1242.2) Supplementdoc. No. STC AE/164-DAE1, issued August 20...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/05/2018	Active	10065403

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065406	NORTHWEST AEROSPACE TECHNOLOGIESINC.			777-200	Cabin Reconfiguration of Austrian Boeing 777-200 Aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: for Special Condition(s):CRI D-01 Installation ofinflatable Seat BeltsCRI F-01 Non-rechargeable Lithium Battery Installationsfor the following paragraph(s) at a later am...	Certification Summary Doc Nr N0587-D90, Rev-Master Drawing List Doc Nr.N0587-D10, Rev. AInstructions for Continued Airworthiness Doc. Nr. N0587-D70 Rev. Aor later revisions of theabove listed documents approved by EASA.	Limited to Boeing 777-200, S/N 28692.The following ApprovedService Bulletins shall be concurrentlyinstalled: Boeing SB777-25-0711; GE SBs 4234ELM1-24-486,5287ELM1-24-487, 6278ELM1-21-1049, 6278ELM1-21-1050, 6278ELM1-24-488,7220ELM1-25-060; Austrian Engineering EB-777-25-0028-00 and LHT SBs777-EB33...	02/05/2018	Active	10065406
10065407	DOA AESGLOBAL LIMITED	REV. 1		777F 777-300ER 777-300 777-200LR 777-200	T-PED Tolerance CompatibilityRev 1: Transfer from AES Ltd.to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25.1, 25.1309(a) 1,25.1353(a), 25.1431(a), 25,1529, 25.1581(a)3 at Amdt 20The requirements for environmental protectionc...	-,,Master Data List, Ref. AES-777-4653MDL, Issue 1-,,Airplane Flight Manual Supplement, AES Supplement No. 77, Issue 1or later revisions of the above listed document(s) approved under theEASA system.	- This modification provides the aircraft configuration management andtesting requirements to facilitate demonstration of aircraftcompatibility with PED emissions operating in the2.4GHz and 5GHzFrequency range, within the flight deck, cabin and cargo area. Refer toMaster Data List AES-777-4653MDL.-...	28/04/2021	Active	10065407
10065422	AERSALE, Inc.	REV. 3	FAA ST04009NY	737-600, 737-700, 737-800 737-300, 737-400, 737-500	ADS-B Out.Automatic Dependent Surveillance-Broadcast (ADS-B) Out System includinginstallation of High-integrity GPS position source, dual GPS antennas,dual ACSS transponders and associated annunciators.Rev. 2. to add 737-300/-400/-500 aircraft .	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amdt 20 and CSACNS Subpart D, Issue 2.The requirements for environmental protection and the associatedcertified nois...	1. Instructions for Continued Airworthiness, Doc Ref: B737-ICA-0019 RevB2. Flight Manual Supplement, Doc Ref: B737-0017Rev Cor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement....	None	20/04/2020	Active	10065422
10065426	CRANFIELD AEROSPACE SOLUTIONS LIMIT			525A	OSD for STC Number 10056170Initial issue of the MMEL Supplement for C525A.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CAS/MMEL1452, Master Minimum Equipment List (MMEL) Supplement,Installation of Tamarack ATLAS Winglets, Issue A, dated January 2018or later revisions of the above listed documents approved by EASA.	Applicable to Cessna 525A aircraft fitted with EASA STC 10056170 issue5.Must be used in conjunction with MMEL 525MMELEUfrom TCH.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/...	04/05/2018	Active	10065426
10065432	QUIET TECHNOLOGY AEROSPACE, Inc.		FAA STC ST04233AT	60	Replacement of the inner aluminum barrel of the engine inlet cowl, withan inlet barrel of carbon graphite sandwich construction, to provide asolution for in-service corrosion.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	QTA Assembly Procedure, Report QTA 6004, Revision A, dated 24 June2005.QTA Master Drawing List, Report QTA-6001, RevA, dated 24 June 2015.Instructions for Continued Airworthiness, Report QTA- 6005, Rev IR,dated 31 December 2014.Structural Repair Manual Report QTA-6006, Rev IR dated 16 January...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/05/2018	Active	10065432
10065435	JET AVIATION AG			777-300ER	VVIP Cabin Interior Completion	As per CRI A-01The requirements for environmental protection and the associatedcertified noise and/ or emissions levelsof the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, Doc. No. JBSC-M-00056MDL-01 Issue 03-Certification Compliance Sheet, Doc. No. JBSC-M-00056CCS-01 Issue 03-Aircraft Flight Manual Supplement, Doc. No. JBSC-M-00056AFM-01 Issue 05-Airworthiness Limitation Section (ALS) of the ICA, Doc. No.JBSC-M-00056AMT-01 Issue 01.or later revisio...	None	04/05/2018	Active	10065435

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065438	B/E AEROSPACE, Inc.	REV. 1	FAA STC ST02967AT	737-900 737-800 737-700 737-600 737-500 737-400 737-300	Installation of an Avtech NA138-714B/C Selective Calling (SELCAL) System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. EMTEQ Engineering Master Drawing List (MDL) 2-27097-001,Rev. C,dated 12 June 2006, or later FAA approved revision.2. FAA Approved Flight Manual Supplements (AFMS) for an AvtechNA138714B/C SELCAL System on Boeing 737 Series Aircraft, EMTEQ DocumentNo. 2-27097-838, Rev. IR, dated 30 March 2010, or...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/06/2018	Active	10065438
10065448	365 AEROSPACE DDS LIMITED	REV. 1		PA-31T (CHEYENNE/ CHEYENNE II) PA-31T3 PA-31T2 (CHEYENNE IIXL) PA-31T1 (CHEY. I/ CHEYENNE IA)	Installation of Weather Modification EquipmentRev. 1: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDS Ltd	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	-365 Aerospace Ltd. Master Data List MDL-0234, Rev. C, issued 2 May 2018-365 Aerospace Ltd. Flight Manual Supplement FMS-0234-001, Rev. A-365 Aerospace Ltd. Instructions for Continued AirworthinessICA-0234-001 , Rev. A, issued 16 Feb. 2018or later revisions of the above listed document(s) approved un...	The installation of STC FAA SA1593GL is a precondition for installingthe weather modification equipment.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adv...	05/08/2019	Active	10065448
10065451	POLYTECH AERO SUPPORT INC.	REV. 1	TCCA SA17-52 ISSUE 1	A330-343 A330-342 A330-243	A330 Audio and Video Entertainment System InstallationThe modification removes the currently installed IFE and replacesitwith the new audio and video entertainment system. Refer to M5-17-002REV 2, Modification Summary.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: In addition to theoriginal Certification Basis, the followingsections of CS-25 Amdt, 19has been included 25.1701, 25.1703...	P.A.S. Modification Summary MS-17-002 R2, July 28, 2018or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	None	31/08/2018	Active	10065451
10065452	POLYTECH AERO SUPPORT INC.	REV. 1	TCCA SA17-53 ISSUE 1	A330-243, 330-342, A330-343	A330 Mood Lighting Installation.To replace existing passenger cabin fluorescent lighting with BR3000 orBR3100, as applicable, Mood Lighting System (MLS) that uses LEDtechnology onAirbus A330 aircraft type.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: In addition to theoriginal Certification Basis, the followingsections of CS-25 Amdt. 19have been included 25.1701, 25.170...	POLYTECH AERO SUPPORT INC. DOC. NO. MS-17-003 REVISION 1 (JUN 7/2018)<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/10/2018	Active	10065452
10065453	NORTH AMERICAN SURVEILLANCE SYSTEMSInc.		FAA STC SA02917NY-D	208B	Installation of Camera Ports.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Delta Engineering Master Data List 0160-08107-2321 Revision- dated 5September 2012 or later FAA approved revisions to Delta EngineeringMaster Data List previously listed.The Instructions for Continued Airworthiness and Airplane Flight ManualSupplement as listed on the Master Data List.	This STC can only be installed on aircraft that have the activated TKSIce Protection System. The TKS system is not approved by this STC.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design chan...	07/05/2018	Active	10065453
10065460	PALL AEROPOWER CORPORATION		FAA ST04414AT	A321-271N/-272N A321-251N/-252N/-253N A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-251N/-252N/271N A320-216/-231/-232/-233 A320-211/-212/-214/-215 A319-115/-131/-132/-133 A319-111/-112/-113/-114 A318-111/-112/-121/-122	Installation of Pall Aeropower Corporation FTIS pre-filter kit partnumber A290957STC.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Pall Aeropower Drawing No. A290957STC, Rev. A, dated June 1, 2017 orlater FAA approved revisions.	The installation applies to the referenced aircraft models equipped withParker IGGS pallet part number 2070066-102 or 2070066-103 installed.Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designa...	07/05/2018	Active	10065460

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065469	AIRBUS S.A.S.			A380-841, A380-842, A380-861	A380 - STC ACJC - Mod CJ2150 2KU ANTENNA System Activation.Cabin Connectivity System Activation including Wireless LAN.Definition and installation of "Outside Aircraft Equipment (OAE)" andassociated wiring was dealt with separate EASA Approval 10065134 (Project 10048573).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- MAS CJ2150 issue 01.- ACJC-AJA-17027 Certification Summary Report issue 3.	None	08/05/2018	Active	10065469
10065492	VT DRB AVIATION CONSULTANTS	REV. 1	FAA ST11212SC	777-200	Installation of a VIP Interior.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01 (Glass screens of displays/monitors), CRID-02 (Isolated Compartments), CRI D-04(Shower Installation), CRI F-05(Non-rechargeable Lithium Bat...	- Data List, Compliance Data, Aeria, P8050, Polaris 777, ODA STC, VT DRBAviation document DL1935M00, Revision AH, dated09 May 2017;- Instructions for Continued Airworthiness, VT DRB Aviation document8050CT25-03, Revision A, dated 04 May 2017;- Airplane Flight Manual Supplement, VT DRB Aviation docu...	The approval is limited to MSN 30867.If the holder agrees to permit another person to use this certificate toalter a product, the holder must give the other person written evidenceof that permission.The applicant's assessment showing that this modification does notimpact the existing electrical wiri...	23/05/2018	Active	10065492
10065501	T.P.S. S.P.A.	REV. 1		AS 332 L, AS 332 L1 AS 332 L1 AS 332 L	Installation of new sponson on main landing gear in accordance withchange TPS332-00100-00Rev. 1: Change of the approvalholder name from TPS AEROSPACEENGINEERING S.r.l. to T.P.S. S.P.A.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- RFM Supplement TPS332-00100-RFMS-00 Issue 0 dated 07.05.2018- Master Drawing List TPS332-00100-Mdw-00 Issue 0 dated 28.08.2017- General Description Report TPS332-00100- Gdr-01 Issue 1 dated07.05.2018- Certification Program TPS332-00100-Cpr-03 Issue 3 dated 07.05.2018- Compliance Checklist TPS332-0...	This STC is not compatible with the ski installation or with theemergency floatation gears. This STC cannot be installed on AS 332 L1modified with AHCAS (commercial reference AS 332 L1e).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/r...	19/05/2022	Active	10065501
10065503	SABENA TECHNICS BOD			F28 MARK 0100	Kit Aero Large Band (KALB) project – Mechanical provision for antennainstallation.This modification installs structuralprovisions on top skin fuselage,where the flush doublers, the longitudinal webs and associated junctionbrackets will remain permanently, modifies the cabin ventilation ductsand ada...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, ref : MDL-S-00-4113 Issue 4, dated 27 April 2018- Airworthiness for Continued Airworthiness, ref : ICA-FK109-00-004Issue A, dated 27 April 2018.or later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/05/2018	Active	10065503
10065511	ALAMO ENGINEERING GmbH	REV. 1		BD-700-1A11 BD-700-1A10, BD-700-1A11 BD-700-1A10	Replacement of Honeywell DU-870 display units with DU-875 Elite withbasic functions.This supplemental type certificate (STC) installation consists ofreplacement of the existing Honeywell cockpit display units DU-870 (CRTmodel) with DU-875 (Part Number K9321060A13-03 and Software variantV01.10.01) on...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1316 and 25.1317at amendment level 21.The requirements for environmental protection and the associatedc...	328 Support Services GmbH's Master Document List MDL 109Z001 Issue A,dated 07th May 2018or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system	This supplemental type certificate (STC) installation consists ofreplacement of the existing Honeywell cockpit display units DU-870 (CRTmodel) with DU-875 (Part Number K9321060A13-03 and Software variantV01.10.01) on Bombardier BD-700 series aircrafts equipped with HoneywellPrimus 2000XP avionics su...	18/12/2023	Active	10065511
10065512	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR09616RC	505	Installation of Floor Protectors	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List, Report No. AA-17066, Revision A, dated17 January2018, or later FAA approved revision.AeronauticalAccessories Instructions for Continued Airworthiness,ReportNo. AA-16012, No Revision, dated 4 January 2018, or later FAAaccepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/05/2018	Active	10065512

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065514	QUIET TECHNOLOGY AEROSPACE, Inc.		FAA STC ST04413AT	FALCON 2000EX	Replacement or the inner aluminum barrel of the engine inlet cowl<(>,<)>with an inlet barrel of carbon graphite sandwich construction<(>,<)> toprovide a solution for in-service corrosion.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. QTA Nose Cowl Assy - Falcon F2000, Drawing F20-NC-2000, Rev. NC,dated 29 September 2017.2. Assemble Procedure, Report QTA-2005, Rev. IR, dated 16 August 2017.3. Instructions for Continued Airworthiness, Report QTA-2006, Rev. IR.dated 13 September 2017.4. Structural Repair Manual, Report QTA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/05/2018	Active	10065514
10065518	QUIET TECHNOLOGY AEROSPACE, Inc.		FAA STC ST04417AT	BD-100-1A10	Replacement of the inner aluminum barrel of the engine inlet cowl with aQuiet Technology Aerospace inlet barrel of carbon graphite sandwichconstruction.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Quiet Technology Aerospace document “Challenger 300/350 Series InletCowl Inner Barrel Replacement Master Drawing List,” Report No. QTA 6301,Rev. IR, dated 1 December 20172. “Bombardier Challenger 300/350 Inlet Cowl Inner Barrel ReplacementAssemble Procedure,” Report No. QTA 6305, Rev. IR, dated 1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/05/2018	Active	10065518
10065521	HELI AUSTRIA GmbH	REV. 1		AB412 412EP 412 212, 412, 412EP 212	Tactical Radios and Centre Pedestal Extension for Bell 212 / 412 / AB412HelicoptersReason for Revision 1: Extends STC to Agusta Bell 412 (AB412) model	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List, Doc No. HAU-D-033-001, Rev. 1-FlightManual Supplement, Doc. No. HAU-D-033-005, Rev. 1-Instructions for Continued Airworthiness, Doc. No. HAU-D-033-006, Rev.1-Installation Manual, Doc No. HAU-D-033-004, Rev. 1-Approved Model List, Doc No. HAU-D-033-AML, Rev. 0or later revisio...	This STC is not applicable to helicopter Model AB412 EPBell412EP limited to serial number up to S/N 36999Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no a...	09/12/2021	Active	10065521
10065532	APTOZ EHF.	REV. 1		757-200 SERIES 757-200	Demonstrating the 120-minutes ETOPS capability per AMC-20-6revision 2for RB211-535E4-powered Boeing 757-200 series aeroplanes in accordancewith Icelandair CRA-757-0000-23, Initial Release dated 23 February 2018.With this STC Icelandair demonstrates that with three reliable andindependent electrical...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25.1309(b) Amendment18 and AMC-20-6, revision2.The requirements for environmental protection and the asso...	- Icelandair’s Change Repair Approval ref. CRA-757-0000-23,InitialRel ease dated 23 February 2018;- Icelandair’s Continuing Airworthiness Instructions CAI-757-0000-23Revision A;orlater revisions of the above listed document(s) approved/acceptedunder the EASA system.	1) This approval does not constitute an operational approval. Theoperator must seek operational ETOPS approval from their nationalauthority.(2) The Operator’s Minimum Equipment List must incorporate the contentof the Icelandair’s MMEL-S asper CAI-757-0000-23 Revision A or laterapproved revision.(3...	27/05/2025	Active	10065532
10065538	AMAC AEROSPACE SWITZERLAND AG	REV. 1		A319-133	Alternate Cabin reconfiguration with reduced passenger capacityRevision 1 : The alternate configuration option to allowflexibleremoval/re-installation of the seats S6B and S9B iscancelled. The seatsare permanently removed.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.1, CS 25.853, CS25.1301, CS 25.1519, CS 25.1581, CS S25.1, CS S25.20, CS S25.30, CSS25.40, CS S25.50.The requirement...	- The change is defined with Revision A of MDL-GF04-2520 amendingRevision B of MDL-GF02-2500- The Aircraft shall be operated in accordance with Revision B ofAFMS-GF02-2500or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	STC 10038393 shall be completed prior to or in conjunction with thismodification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the air...	25/07/2019	Active	10065538

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065543	DELTA ENGINEERING CORPORATION		FAA STC ST02650NY	777-300ER 777-300 777-200	Upgrade of Panasonic Avionics Corporation System Monitors	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02650NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Delta Engineering Master Data List 0100-06700-2211 Revision B dated17 April 2018 or later FAA approved revisions.2. Instructions for Continued Airworthiness as listed on the Master DataList.	This STC is for replacement of existing Panasonic RD-AA7204-01 monitorsonly.Prior to installation of this design changeit must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the a...	17/05/2018	Active	10065543
10065549	AIRBORNE TECHNOLOGIES GmbH			P.68R "VICTOR"	STC-AT-118 Holding Power Setting.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flight Manual Supplement Doc. No. STC-118-G-AFM Rev. 1, Date 5.5.2018< (>,<)>or later revisions of the above listed documents approved by EASA.Aircraft Maintenance Manual Supplement Doc. No. STC-118-G-AMM Rev. 0,Date 23.3.2018.Installation Instruction Doc. No. STC-118-G-II, Rev. 0, Date 23.3.2018.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/05/2018	Active	10065549
10065550	E A D AEROSPACE AIRWORTHINESS	REV. 2		A340-313 A340-211/-212/-213/-311/-312 A330-343 A330-321/-322/-323/-341/-342 A330-243/-243F/-301/-302/-303 A330-201/-202/-203/-223/-223F	KA-Band SATCOM radome with provisions for LRU (antenna) installation ontop on the aircraft fuselage.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List, EAD Aerospace document No. 01555-EAS-A-MDL,Revision E, dated 3 May 2019.- Airplane Flight Manual Supplement, EAD Aerospace document No. 01555-EAS-A-AFM-01, Revision A, dated 26 April 2018.- Airplane Flight Manual Supplement, EAD Aerospace document No. 01555-EAS-A-AFM-02, Revisi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/05/2019	Active	10065550
10065567	PMV ENGINEERING	REV. 4		A321-271N/-271NX/-272N/-272NX A321-253N/-253NX A321-251N/-251NX/-252N/-252NX A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-251N/-252N/-271N/-272N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	S-band Satcom on A320 familyThis modification installs mechanical / electrical provisions for theinstallation of a S-band Satcom system.The Revision 1 corrected some editorial errors on Master Document Listand Instructions for Continued Airworthiness documents.The Revision 2 consisted in activatingT...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: :CS25 amdt 18:25.301(a)(b), 25.303, 25.305 (a)(b), 25.307(a),25.561(c)(d), 25.571(a),(b),(c),(d), 25.601, 25.603, 25.611(...	- Master Document List SCA-01070-MDL-R08, dated 07 NOV 2018- Instructions for Continued Airworthiness SCA-01071-ICA-R01, dated 11AVR 2018- Instructions for Continued AirworthinessSCA-01071-ICA-S01 R00, dated20 SEP 2018- Instructions for Continued Airworthiness SCA-01071-ICA-S90 R00, dated07 NOV 201...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/11/2018	Active	10065567
10065568	BROMMA AIR MAINTENANCE AB	REV. 2		B300	Bromma Air Maintenance AB Modification 16-10 for installation of MSS7000 Airborne Maritime Special Mission System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Bromma Master Document Listref.MDL-16-10 Revision A, dated 18 May 2018;Operate in accordance with Bromma Aircraft Flight Manual Supplement(AFMS) ref. FMS-16-10 Revision C, dated 24 July 2018;Instructions for Continued Airworthiness (ICA) in accordance with BrommaDocu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/01/2019	Active	10065568

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065570	TELEDYNE BATTERY PRODUCTS		FAA STC SR00866DE	AB139/AW139	Installation of Teledyne Battery Products Valve-Regulated Lead-Acid(VRLA), P/N 7638-44 main battery andP/N 7407-28 auxiliary battery.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Teledyne Battery Products Document No. TD72-1-01, Master Drawing List,AB139/AW139 Teledyne Battery Installation, Revision IR, dated 3 November2017, FAA approved 30 November 2017.- Instructions for Continued Airworthiness (ICA), Document No.TD-72-8-02, Revision IR, dated 3 November 2017, FAA accept...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/05/2018	Active	10065570
10065571	AIRBUS DEFENCE AND SPACE S.A.	REV. 1		A330-243	OSD A330 MRTT FAF version Flight Crew Data.Ref STC 10064192.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airbus Operational Suitability Data – Flight Crew, OSD-FC Final ReportA330 MRTT FAF STC, TAS-FF-RP-17-0004, version B, dated 25 January 2018<(>,<)>or later revisions of the above listed document(s) approved under theEASA system.	None	28/06/2018	Active	10065571
10065575	SABENA TECHNICS BOD			A310-304	A310 Cabin modification with new 55'' screen.This modification consists in replacing an aft facing TV monitor in thelounge area by a new 55'' screen.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.788(b) amendment19.The requirements for environmental protection and the associatedcertified noise and/ or emissions...	Master Data List, ref. MDL-S-23-4127 Revision A, dated 14 May 2018<(>,<) >or later revisions of the above listed document(s) approved under theEASA system.	This modification needs the concurrent embodiments of the followingdesign changes as prerequisites:- EASA STC 10043347<(>,<)> dated on 22 January 2013 (Tenanciamodification N°. 687)- PMV Minor Change, ref CAB-02440-MCA (supporting PMV Service Bulletinref : CAB-02440-SB-S01-R01).Prior to installation...	22/05/2018	Active	10065575
10065576	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE		TCCA SH17-30, ISSUE 1	SA 365 N, SA 365 N1 EC 155 B, EC 155 B1 AS 365 N2, AS 365 N3	NiCd to Lead-Acid Battery Replacement.Replace Saft P/N 40208-2 Nickel-Cadmium battery with Concorde P/ N RG-365Lead Acidbattery.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Concorde Battery Co. Modification Summary 5-0620, Revision B, TCCAapproved August 18, 2017<(>,<)>or later revisions of the above listed document(s) approved on behalf ofEASA in accordance with the Technical Implementation Procedures of EU/Canada Bilateral Agreement.Concorde Battery Co. InstructionsR...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/05/2018	Active	10065576
10065631	SABENA TECHNICS BGC			A320-214	Rave IFE System Installation on A320	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): F-01 (PN 10051441), Securityprotection ofAircraft systems and networks;the following paragraph(s) at a later amendment: Applicable regulationsat CS4...	- AFM Supplement 40166-01-A-AFMS-R00or later revisions of the above listed document(s) approved under theEASA system.- Instructions for continued airworthiness 40166-01-A-ICA-R00;- Master Data List 40166-01-A-MDL-R00.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2018	Active	10065631
10065632	JANZAIR CONSULTING SERVICES, INC.		FAA STC ST02904AT	737-200/-300/-400/-500	Installation of a Dual Collins HF Communication System witha LeadingEdge Antenna into a Boeing 737-200/ -300/ -400/ -500 aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	JanzAir Master Drawing No. 731-2311-101 Revision B, dated 15 July 2005,or later FAA approved revision.Airplane Flight Manual Supplement, dated 21 September 2005, or later FAAapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/05/2018	Active	10065632

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065642	AIR ALLIANCE GmbH			35, 35A, 36, 36A	Replacement of GPS/WAAS Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to Air Alliance GmbH Master Document List2017_018_LJ35_Form_ 2, Rev 00;To be installed i.a.w. Air Alliance GmbH 2017_018_LJ35_0500, Rev 00;To be maintained i.a.w. Air Alliance GmbH 2017_018_LJ35_0507, Rev 00;or later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.,,,,	25/05/2018	Active	10065642
10065652	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 1		777-300	Economy Class Reconfiguration and provisions for future approval ofoptional stretcher installation.,,	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 25.561, 25.791,25.813(a)(b)(d)(e), 25.815, 25.1447 are at CS-25 Amendment 12 and 25.785is at CS-25 Amendment 13.The requir...	- Certification Summary, Northwest Aerospace Technologies, Inc. documentN0592-D90, Revision B, dated 28 May 2018;- Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document N0592-D70, Revision B, dated 7 May 2018;or later revisions of the above listed document (s) appro...	The following Approved B/E Aerospace Service Bulletins shall beconcurrently installed on MSN aircraft 27504-27510: SB 25-30-1022, SB25-30-1028, SB 25-30-1024, SB 25-30-1029 and SB25-30-1030. Thefollowing Approved ZPG Service Bulletins shall be concurrently installedon MSN aircraft 33702-33704, 342...	04/06/2018	Active	10065652
10065656	ELECTRONICS INTERNATIONAL, Inc.		FAA STC SA02283SE	SEE FAA AML	Installation of Electronics International Inc. Glass Panel EngineMonitor (with Flight Data) CGR-30P	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Installation Instructions, Document No. II 02151301, Revision B,dated 21 June 2013, or later FAA approved revision.2. Electronics International, Inc. Instructions for ContinuedAirworthiness, Document No. 06211301, Revision B, or later FAA acceptedrevision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. Only one of the parameters displayed on th...	29/05/2018	Active	10065656
10065657	ELECTRONICS INTERNATIONAL, Inc.		FAA STC SA02402SE	SEE FAA AML	Installation of Electronics International Inc. Glass Panel EngineMonitor (with In-Flight Data) CGR-30C.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1) Master drawing list as specified on AML SA02402SE, or later FAAapproved revision.2) Electronics International, Inc. Instructions for ContinuedAirworthiness, Document No. 06211301, Revision E, dated 28 March 2014,or later FAA accepted revision.	1) Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2) The STC is valid for aircraft types and mo...	29/05/2018	Active	10065657
10065670	NORTHERN AVIONICS S.R.L.	REV. 1		767-200, 767-300, 767-400ER	Cabin monitor Installation on B767.	EASA CS-25 Amdt 20.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- AFM Supplement doc. NAV 0572 dated 01/03/2018;- MDL0572 Rev.5 (Master Document List);- ICA-NAV0572 Rev.0 (Instructions for Continuous Airworthiness);or later revisions of the above listed document approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/06/2018	Active	10065670
10065672	DELTA ENGINEERING CORPORATION	REV. 1	FAA ST03199NY	BD-700-1A10/ BD-700-1A11 BD-700-1A10, BD-700-1A11	Installation of ABC Completions Electronic Flight Bag Display Mounts andDAC International GDC-64:- Configuration 1: EFB- Configuration 2: EFB with mount support installationRev. 1: Update of Master Data List. EASA Certification basis corrected.Removal of dependency to prerequisite “Quick cha...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt. 0: 25.853, 25.1583, 25.1585CS 25 amdt.5: 25.981.The requirements for environmental protection andthe associatedcertified noise and/ or emissions levels of th...	- Master Data List 0162-09033-2379, Rev. T, dated 02 February 2023- Instructions for Continued Airworthiness No. 0762-09039-2379, Rev. B,dated 31 January 2023- Airplane Flight Manual Supplement No. 0662-09038-2379, Rev. A, dated01 February2023or later revisions of the above listed document(s) appro...	1. Prior to installation of this change/repair it must be determinedthat the interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of theproduct.2. This STC is for provisions of Electronic Flight B...	31/03/2023	Active	10065672

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065675	AIRBUS HELICOPTERS CANADA LIMITED	REV. 1	TCCA SH 17-47 ISS.1	MBB-BK117 D-3 MBB-BK117 D-2 MBB-BK117 C-2, MBB-BK117 D-2 MBB-BK117 C-2	Installation of Removable Pins for Hinged DoorRev. 1: Applicability extended to MBB BK-117 D-3 helicopter model.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- must be in accordance with Airbus Helicopters Canada Limited MasterDrawing List MDL-17-001, Issue B, Transport Canada approved 24thSeptember 2021.- Maintenance must be performed in accordance with Airbus HelicoptersCanada Limited Instructions for Continued Airworthiness ICA-AHCA-298,revision 1, T...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/01/2022	Active	10065675
10065679	AIRBUS HELICOPTERS UK LIMITED	REV. 5	CAA UK RESPONSIBILITY	EC135 T3	Powerline Mission Equipment and Load Carrying Components – ConfigurationAHUK/135/3000 or AHUK/135/3010This STC includes, Anti-Spin Release System, External Cargo InformationSystem, External Mirrors, Mission Radio and Load Carrying Components(LCC) including Workstation BasketsInitial Issue:LCC up top...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-27 at Amendment 2for CS-27 CS27.605; 27.619; 27.625; 27.1585 / CS-27 at Amendment 3 for27.865The requirements for envir...	Initial Issue:Design Compliance Reports:- DCR/1353000-01 Issue A. Aircraft configuration for Power LineOperations- DCR/1353001-01 Issue A. Anti-Spin System- DCR/1353002-01 Issue A. Workstation Baskets & Load Carrying Components- DCR/1353004-01 Issue B. Load Carrying Components- DCR/1353005-01 Issue-...	Limited to helicopters with CPDS cockpit variantPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	08/12/2020	Active	10065679
10065686	SCANDINAVIAN AVIONICS DESIGN ApS			SEE EASA APPROVED MODEL LIST	ULB UPGRADE TO DK120/90The change consists of replacing thebattery, in the existing (30 days)ULB, with a new Li Ion battery to support 90 days ULB operation. Thereis one ULB attached to the cockpit voice recorder and one ULB attachedto the flight data recorder.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): See CRI F-01 Issue 3CS 25 Amdt 2 for the affected requirementsThe requirements for environmental protection and the associatedcertified noise and/ or...	-Continued Airworthiness – Doc Ref: 211913-CAor later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/06/2018	Active	10065686
10065691	SABENA TECHNICS BOD			A330-341/-242/-243 A330-321/-322/-323 A330-301/-302/-303 A330-201/-202/-203/-223/-243	A330 landscape camera installationThis modification consists in mechanical and wiring routing provisionsfor the installation of a LATECOERE landscape camera, on lower fuselagebetween frames (FR) 2 and FR 3, together with a plug (the plug isremoved once the final installation of the camera).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, ref: MDL-00-4138 Issue A, dated 10 May 2018-Aircraft Flight Manual Supplement, ref: AFMS-F3059-00-011 Issue 1,dated 08 March 2018-Instruction for Continued Airworthiness, ref: ICA-F3059-00-009 Issue A,dated 23 April 2018or later revisions of the above listed document(s) approved u...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/06/2018	Active	10065691
10065695	SABENA TECHNICS BOD			A330-323	A330-323 cabin and systems modification, and Ultra High ComfortAttendant Seat installationThis modification reconfigures the cabin layout of the MSN 758 byinstalling new passengerseats, UHCAS, IFE and cabin features (curtains,lining, floor pathmarking, carpet …).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List, ref: MDL-S-00-4129 Issue A, dated 01 June 2018-Airworthiness Limitation Supplement, ref: ALS-F3058-00-141 Issue A,dated 30 May 2018-Instruction for Continued Airworthiness, ref: ICA-F3058-00-109 Issue A,dated 31 May 2018or later revisions of the above listed document(s) approved u...	The following modifications must be concurrently embodied with thismodification:- EASA STC 10014507 Revision 2 (or later EASA approved revision) : Floorpathmarking installation- EASA STC 10065691 (or later EASA approved revision) : A330 landscapecamera installationPrior to installation of this change...	01/06/2018	Active	10065695

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065722	PEREGRINE LLC		FAA STC SA00744DE	SEE FAA APPROVED MODEL LIST	Installation of the Automatic Dependent Surveillance – Broadcast (ADS-B)Out Equipment using a Trig Avionics TT31 Transponder and an approvedposition sensor.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Peregrine Master Drawing List, referenced on the attached AML No.SA00744DE.2. Instructions for Continued Airworthiness document, as listed on theattached AML No. SA00744DE.3. Airplane Flight Manual Supplement, as listed on the attached AML No.SA00744DE.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	04/06/2018	Active	10065722
10065740	BELL HELICOPTER TEXTRON, Inc.	REV. 1	FAA SR09617RC	412EP	Installation of Enhanced Hover Hold.Rev. 1: expands the applicability to include Model 412EP serial numbers38001-38999 and 39101-39999.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval	- Master Drawing List, Report No. AA-16038 Revision C, dated 19 November2021<(>,<)>- Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-16045, Revision B, dated 8 September 2021<(>,<)>- Aeronautical AccessoriesRotorcraft Flight Manual Supplement, ReportNo. AA-16046, Rev...	Eligible for installation on S/N 37002-37999, 38001-38999, and39101-39999 or aircraft modified in accordance with STC No. SR09600RCInstallation of Bell BasiX-Pro Glass Cockpit andPratt & Whitney CanadaPT6T-9 Twin Power Section Turboshaft Engines and associated systems.Prior to installation of thist...	01/08/2025	Active	10065740
10065747	ALPINE AEROTECH LP		TCCA STC SH-18-1 ISSUE 1	505	Installation of Alpine Aerotech LP Bear Paw Kit in accordance withMaster Data List AAL-390-024-001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Bear Paw Kit Flight Manual Supplement AAL-390-025-401 Revision NI<(>,<)>or later revisions of the above listed document(s) approved on behalf ofEASA in accordance with the Technical Implementation Procedures of EU/Canada Bilateral Agreement.- Airworthiness Requirements Compliance Program Bell 505 Be...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/06/2018	Active	10065747
10065748	STANDARD AERO		FAA ST04236CH	GV, GV-SP	GV<(>&<)>GV-SP – Installation of a Honeywell Jetwave satcomwithassociated Ka-Band Radome.This modification removes theexisting Ku-Band radome and installs a newKa-Band radome onthe aircraft tail. It also installs the HoneywellJetWave SATCOM System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): ESF B-101: Vibration/ buffetingcompliance criteria for large external antenna installation.The requirements for environmental protection and...	- Master Data List, ref. 1032256 issue E dated 06 JUN 2018;- Airplane Flight Manual Supplements, ref. 1032713 Rev A dated22NOV2017;- Instructions for Continued Airworthiness, ref.1032712 Rev A dated27NOV2017;or later revisions of the above listed document(s) approved on behalf ofEASA in accordanceU...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/06/2018	Active	10065748
10065749	AVIONIK STRAUBING ENTWICKLUNGS GmbH			F172P	Installation of a special Antenna and Signal/Data processing Equipmentfor Mission Purposes.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment: CS-23, Amdt. 429, 141, 143, 149, 153, 171, 301, 303, 305, 307, 337, 561, 601, 603,605, 607, 609, 611, 613, 625, 867, 13...	- Project Description ASR-2017-085-PRD-04-00, Rev. 00- Instructions for Installation ASR-2017-085-IFI-10-00, Rev. 00- Instructions for Continued Airworthiness ASR-2017-085-ICA-11-00, Rev.00	All provisions according to EASA STC 10061698 must have been alreadyinstalled.This approval does not cover the installation of any mission/ researchequipment in the 19” rack other than specified Avionik Straubingdocument ASR-2017-085-PRD-04-00. It does also not cover the operation ofany kind of PED.P...	06/06/2018	Active	10065749

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065753	STG AEROSPACE GERMANY GmbH	REV. 2		SEE EASA APPROVED MODEL LIST SEE APPROVED MODEL LIST	saf-Tsign® PHOTOLUMINESCENT EXIT SIGNs.Revision 1: Transferof STC holder from STG Aerospace Limited to STGAerospace GmbHRevision 2: Extension of aircraft model applicability in the EASAapproved model list. Update of the EASA approved model list form andeditorial changes.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): D-01thefollowing paragraph(s) at a later amendment: CS25, Amdt 20:25.1 (a),25.25(a)(b), 25.27, 25.301, 25.303, 25.305(a)(b), 25...	Master Data List Doc No SG-1012-MDL-01 Rev. U;AFM supplement Doc Nr SG-1012-FMS-01 Rev. D;Service Bulletin Doc No SG-1012-SB-01 Rev. E;Instructions for Continued Airworthiness DocNo SG-1012-ICA-01 Rev. D;Cabin Crew Data Supplement Doc Nr SG-1012-CCD-01 Rev. D;or later revisions of the above listedu...	For all aircraft with required cabin crew Cabin Crew Data Supplement DocNr SG-1012-CCD-01 has to be applied.For all other limitations refer to Service Bulletin Doc NoSG-1012-SB-01, Instructions for Continued Airworthiness Doc NoSG-1012-ICA-01 and AFM Supplement Doc No SG-1012-FMS-01Prior to installa...	05/07/2024	Active	10065753
10065755	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.	REV. 1		S-76C	Activation of AIS Transponder SystemRev. 1: Transfer of STC	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-536SB-1 Service Bulletin Issue 2-536A Installation Design (Drawings) Issue 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/02/2019	Active	10065755
10065756	HELIFAB Inc.d/b/a ARROW AVIATION CO. LLC		FAA STC SR09870AC	407 206L-4 206L-3 206L-1 206L 206B	Installation of floor protectors	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Helifab Master Drawing List HF·MDL-7-3, Revision IR, dated 15 June2016, or later FAA approved revision.2. Instructions for Continued Airworthiness, Helifab Report No.HF-CA-7-3,Revision IR, dated 15 June 15 2016, or later FAA acceptedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/06/2018	Active	10065756
10065772	JETTECH, L.L.C.		FAA STC ST02427LA	500, 550, S550, 560, 560XL	Installation of Dual Garmin GTN 6XX/7XX Series Global Navigation Systemwith Structural Antenna and WAAS approval; Garmin GMA 35 Audio Panel;and Dual Garmin GTX33 Mode S Transponders, Weather Radar, and ADS-BLink.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. FAA Approved JETTECH, LLC Master Document List, Drawing No.JTECH-WAAS-0001, Revision A<(>,<)>dated 19 July 2012, or later FAA approved revision; and2. FAA Approved Airplane Flight Manual Supplements, Document No. JTECH-WAAS-0002 Revision IR<(>,<)>dated 20 July 2012, or JTECH-WAAS-0202 Revision IR...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Display of StormScope® is not approved under thi...	11/06/2018	Active	10065772
10065773	SECURAPLANE TECHNOLOGIES, Inc.		FAA STC SA02566SE	PC-12, PC-12/45, PC-12/47, PC-12/47E	Installation of Securaplane SLA Batteries	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, AM0303-DL02-00, Revision -, dated 13 September 2017 orlater FAA approved revision.The modified aircraft must be maintained in accordance with inaccordance with the Instructions for Continued Airworthiness,AM0303-IC01-00, Revision A, dated 23 August 2017, or later FAA acceptedrevisi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/06/2018	Active	10065773
10065783	AMAC AEROSPACE SWITZERLAND AG			GVI (G650)	Installation of J-Music SystemInstallation of J-Music self defence system with optical sensors,jamming turret, and electrical equipment.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-AFMS-G6501-1-5300, Revision A, Airplane Flight Manual Supplement-ICA-G6501-1-5300, Revision B, Instructions for Continued Airworthiness-MDL-G6501-1-5300, Revision C, Master Data Listor later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/06/2018	Active	10065783

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065785	SABENA TECHNICS BGC	REV. 1		A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-243, A330-243F A330-223, A330-223F A330-201, A330-202, A330-203	Mechanical and electrical installations provisions for Thales EFBsolutions in cockpit of A330.This STC deals with the installation in the A330 cockpit on the LH andRH sliding windows of a mounting device and the electrical supply forThalesEFB solutionsRev 01: The option GROUP II (No equipped switch...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Refer to sections 5 & 6in the certification plan (CS-25 Amendment 4)The requirements for environmental protection and thec...	Instructions for Continued Airworthiness, Aeroconseil document ref.0866-01-A-ICA-R02Airplane Flight Manual Supplement, Aeroconseil document ref. 0866-01-A-AFMS-R03Master Data List,Aeroconseil document ref. 0866-01-A-MDL-R02Certification Plan, Aeroconseil document ref. 0866-01-A-CP-R02or later revisi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2018	Active	10065785
10065809	DELTA ENGINEERING CORPORATION		FAA STC ST02646NY-D	777-300ER	Installation of a Panasonic Avionics Corporation System 3000i	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02646NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Delta Engineering Master Data List 0143-06318-2176 Revision E dated15 June 2011 or later FAA approved revisions.2. Instructions for Continued Airworthiness as listed on the Master DataList.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/06/2018	Active	10065809
10065823	AVIATION SPECIALTIES UNLIMITED, INC		FAA SR02104SE	AB139, AW139	Night Vision Imaging System (NVIS) Lighting.Supplemental NVIS Lightning System manufactured and installed byAviation Specialties Unlimted Inc for the helicopter models AB139 andAW139 in accordance with Master Drawing List document MDL-139004-3Revision AD or later FAA approved revisions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement FMS-139004-6 Revision C dated 16May 2018;- Master Drawing List MDL-139004-3 Revision AD dated 16 May 2018;or later revisions of the above listed document(s) approved on behalf ofEASA in accordance with the Technical Implementation Procedures of EU/USA Bilateral Agreement....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/06/2018	Active	10065823
10065825	PATRIA AVIATION OY	REV. 1		AB412 EP	FMS and EHSI Installation.Reason for Revision 1: limit the AFCS bank angle authority in GNSS-basedNAV.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List No. D-412-08-DL-09, Rev. B, dated 19.09.2019RFMS No. D-412-08-RFM-02 FMS installation, Rev. 2 dated 4th June 2018Certification Programme No. D-412-08-CP-02, Issue 3, dated 18.03.2019Design Approval No. D-412-08-DA-06, Rev. -, dated 16.09.2019Declaration of Compliance No. D-412-08-DOC-06...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/10/2019	Active	10065825
10065827	SPAES GmbH & Co. KG			204B, 205A-1	Installation of electrical Power / Control System.Installation of an Power and Control Box for use of several externalloads (e.g. long line, bambi bucket) including change of pushbuttonfunctions on the cyclic stick to operate the externalload.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment: FAR 29 including Amdt. 1through 6 and CS 29 Amdt. 4: FAR 29.21, FAR 29.25, FAR 29.27, FAR 29.29,FAR 29.251, FAR 29.301, FA...	FMS-SPAES-0072, Supplement for control box power and control system,Revision 00 dated 3 May 2018<(>,<)>or later revisions of the above listed document(s) approved under theEASA system.- Installation Manual, INM-205-072-25-01, Revision 00 dated 3 May 2018.- Instructions for Continued Airworthiness, I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/06/2018	Active	10065827

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065832	SPAES GmbH & Co. KG			AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 BB, AS 350 D AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA	Installation of automatic deployable ELT system series 503,manufacturedby HR-Smith consisting of emergency locator transmitter, beacon releaseunit, locator beacon, control unit, water switch and system interfaceunit.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Part List PAL-355-098-25-01, rev 00, issued on 9 April 2018;- Aircraft Flight Manual Supplement FMS-SPAES-098 rev 00,dated 13 June2018;or later revisions of the above listed document(s) approved under theEASA system.Instruction for Continued Airworthiness ICA-355-098-25-01, rev 00, dated9 April 2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/06/2018	Active	10065832
10065834	BOMBARDIER Inc.		TCCA SA18-25 AT ISSUE 1	BD-100-1A10	Installation, Lavatory Glass Mirror.EASA Validation of Transport Canada STC SA18-25 at Issue 1.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): EASA Special Condition D-10053642-1 at Issue 1“Installation of Large Glass Items in the cabin”.The requirements for environmental protection and thec...	Modification Data Summary L844000 Revision NC, dated 29th May 2018<(>,<) >or later revisions of the above listed document(s) approved on behalf ofEASA in accordance with the Technical Implementation Procedures of EU/Canada Bilateral Agreement.	Modification must be completed in accordance with Modification DataSummary L844000 Revision NC, dated 29th May 2018, orlater approvedrevisions.Maintenance must be in accordance with Instructions for ContinuedAirworthiness document BAS68058009 Basic Issue, dated 02nd May 2018 orlater accepted revisi...	14/06/2018	Active	10065834
10065841	QUIET TECHNOLOGY AEROSPACE, Inc.		FAA STC ST04261AT	GULFSTREAM 200/ GALAXY	Replacement of the inner aluminum barrel of the engine inlet cowl, withan inlet barrel of carbon graphite sandwich construction, to provide asolution for in-service corrosion.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	QTA Nose Cowl Assy - Gulfstream G200, Drawing G20-NC-6200, Rev. A, dated14 March 2017;Assemble Procedure, Report QTA-6204, Rev. A, dated 23 February 2017;Instructions for Continued Airworthiness, Report QTA-6205, Rev. A.dated 23 February 2017;Structural Repair Manual, Report QTA-6206, Rev. A,2...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2018	Active	10065841
10065871	PATRIA AVIATION OY	REV. 1		AB412EP AB412 EP 412EP	EO/IR Camera & Downlink / This STC consists in the installation of anElectro Optical / Infrared (EO/IR) camera turret type model L3HarrisWescam MX-10 on the AB412EP and Bell 412EPhelicopter together with orprovision for Hand Controller for the turret - GPS Antenna for theturret - Operator’s console...	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	AB412EP.-Rotorcraft Flight Manual Supplement D-412-08-RFM-05 Issue 2 Revision 0dated 8 June 2023.-Instructions for Continued Airworthiness D-412-08-ICA-01 Issue 2 dated21 May 2018Bell 412EP.-Rotorcraft Flight Manual Supplement D-412-08-RFM-14 Issue 1 Revision 0dated 8 June 2023.-Instructions for Con...	-For all models: Available capacity for additional electrical load of 28VDC / 11 A.-For model AB412 EP: Kit P/N 412-7718-29 FLIR-Multirole Turret System-For model B412EP: Patria minor change D-412-08-DA-12 – Provision forEO/IRPrior to installation of this change/repair it must be determined thatthep...	11/07/2023	Active	10065871
10065890	GROB AIRCRAFT SE			208B	C 208B Operator Consoles and Interfaces according to OCN C208-01	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-23, Amdt. 5:23.2000, 23.2010, 23.2100, 23.2170, 23.2230, 23.2235, 23.2240, 23.2250,23.2255, 23.2265, 23.2270, 23.2315,2...	Flight Manual Supplement Doc. No. G-C208-01-1-S1, Issue 1orlater revisions of the above listed document (s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/06/2018	Active	10065890

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065891	HELI AUSTRIA GmbH	REV. 2		EC 130 T2 AS 350 B3, EC 130 T2 AS 350 B3	Digital Backup Attitude Indicator and Digital Clock / USB Charger.Reason for Revision 1: Effectivity extended to EC 130T2 and addition ofa second Digital Clock / USB ChargerP/N.Reason for Revision 2:-Option for replacing only the Clock inAS350 B3 helicopters post ModNo. OP4962-Option for installat...	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	The change is defined with Revision 2 of the Master Document ListHAU-D-042-001.Installation shall be performed in accordance with Revision 2 ofInstallation Manual HAU-D-042-004.The aircraft shall be operated in accordance with Revision 2 ofRotorcraft Flight Manual HAU-D-042-005.Maintenance shall bel...	This change is only applicable to AS350 B3, equipped with the GarminG500H cockpit, Mod No. 074723 and EC130 T2 helicopters, equipped withthe Garmin G500H cockpit, Mod No. 074529.For installation/ replacement of the Digital Clock/USB Chargeronly:AS350 B3 helicopters (all)Prior to installation of this...	22/10/2024	Active	10065891
10065900	GFD GmbH	REV. 2		36A 35A, 36A 35A	GPS Antenna Installation ProvisionsRev. 2: Transfer to GFD GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to AIEC Master Data List No. 5565-049, Rev. A;To be installed i.a.w. AIEC drawing List 5565-082, Rev A;To be maintained i.a.w. AIEC ICA document no. 5565-085, Rev IR;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10065900
10065926	E A D AEROSPACE AIRWORTHINESS			A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-223, A330-243 A330-201, A330-202, A330-203	Transmitting Portable Electronic Devices (T-PED) tolerance demonstration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	· Master Drawing List, EAD Aerospace document No. 01553-EAS-A-MDL,Revision A, dated 12 June 2018;· Instructions for Continued Airworthiness, EAD Aerospace document No.01553-EAS-A-ICA-01, Revision A, dated 12 June 2018;· Aircraft Flight Manual Supplement, EAD Aerospace document No. 01553-EAS-A-AFM-01,...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/06/2018	Active	10065926
10065929	SIRIUM AEROTECH S.L.	REV. 1		747-400	SIRIUM AEROTECH S.L. Modification SA18-03S revision 01, PEDToleranceCompliance demonstration in accordance with SIRIUMAEROTECH S.L. MasterData List SA18-03S-MDL revision 01.Thisdesign change contains no physical change to the aeroplane(s) butconsists in showing that the aeroplanes are found toler...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SIRIUM AEROTECH S.L Master Data List - PED Tolerance Compliance – SA18-03S-MDL, Revision 1 – 8 May 2018or later revisions of the above listed document(s) approved under theEASA system.	- This STC is limited to Boeing 747-400 series aeroplanes MSN(Manufacturer Serial Number): 25703, 26549, 27178, 28427, 28435 and26910.-Wireless communication must be limited to amaximum of 100mWEquivalent Isotropic Radiated Power (EIRP) (for instance Wifi emissionis limited to the 2.4 GHz ISM band...	14/08/2018	Active	10065929
10065930	BIGORRE AEROSPACE CORPORATION	REV. 1	FAA ST04062CH	FALCON 2000, FALCON 2000EX	Installation of Cabin LED Lighting System.Rev. 1: Transfer from GDS AERO LLC. to BIGORRE AEROSPACE CORPORATION.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Instructions for Continued Airworthiness ref. doc. GDSLED-ICA, Rev. A,dated 2nd April 2015-Electrical Load Analysis ref. doc. GDSLED-ELA, Rev. A, dated 22nd May2015-Master Data List ref. doc. GDSLED-MDL, Rev. C, dated 12th January 2016or later revisions of the above listed document(s) approved/a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/06/2021	Active	10065930
10065946	ATI ENGINEERING SERVICES, LLC		FAA STC SA00363BO	300/ 300LW/ B300/ B300C	Installation of LED Position Lights.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Installation / Manufacturing Drawing List IDL-141211, Revision -, dated25 September 2015, or later FAA approved revision.Instructions for Continued Airworthiness (ICA) ICA-141211,Revision -,dated 15 October 2015, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/06/2018	Active	10065946

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10065950	SCANDINAVIAN AVIONICS DESIGN ApS			SEE AML DOC. 2112821-EO-APP-2	Underwater Locator Beacon (ULB) UPGRADE TO DK120/90.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 “Non-RechargeableLi-Ion Battery”,Issue 3 dated 18/06/2018.- The following paragraph(s) at a later amendment: CS 29 Amdt 2 for thefollowin...	- Engineering Order, Doc Ref: 2112821-EO dated 18/06/2018.-Engineering Order, Doc Ref: 2112821-EO APP-2 dated 08/06/2018.- Compliance Record, Doc Ref: 2112821 COR-2 dated 15/06/2018.- Continued Airworthiness, Doc Ref: 2112821-CA dated 24/04/2018.	The ULB installation must be compliant with the following conditions:- At least 2” separated from any Fuel, hydraulic or oxygen carrying partsuch as tank, line or hose.- At least 2” separated from wires.- At least 2” separated from other equipment.- At least 2” separated from structure.NOTE: If ones...	22/06/2018	Active	10065950
10065971	ALOFT AEROARCHITECTS		FAA STC ST03747NY	A330-201/-202/-203/-223/-243	Viasat KA SATCOM Antenna System Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Data List (MDL) 1266004, revision 005, dated 23 May 2018, orlater FAA approved revision, for Activated, Demodified and Deactivatedconfigurations. 2. Instructions for Continued Airworthiness (ICA) listed below.Supplements to the Aircraft Maintenance Manual, Illustrated PartsCatalog and Wirea...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is in compliance with 14CFR 36.7, Acous...	25/06/2018	Active	10065971
10065972	AIRBUS S.A.S.	REV. 1		A321-211, A321-231 A319-112, A320-214	MOD CJ2097 - VIASAT KA BAND ACTIVATION.This STC covers the activation of the VIASAT KA BAND antenna.Rev. 1 extends the applicability to A319-112, A320-214 models and someA321-211 MSNs equipped with ADF2.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Summary Report ref. AIS-AJA-17064 Issue 4 (initial) &AIS-AJA-18056 Issue 3 (STC Major Change).- Modification Approval Sheet ref. MAS CJ2097 Issue 2.	None	20/09/2018	Active	10065972
10065986	BOGGI AERONAUTICS S.R.L.	REV. 2		AW169	AW169 EMS interiorsRevision 0 (initial STC) approved EMS cabin interiors P/N 169P001-00Revision 1 incorporated minor change 169P001-41 (belts to restraingeneric equipment and items on a cabin monument already approved underinitial STC, replacing previously approved medical equipment mounts).Revision...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Revision 0:- Rotorcraft Flight Manual Supplement 169P00100-FMS-03- Master Document List 169P00100-Mdl-05 dated 19/06/2018Revision 1:- Rotorcraft Flight Manual Supplement 169P00100-FMS-05- Instructions for Continued Airworthiness 169P00100-ICA-01- Master Document List 169P00100-Mdl-05 dated 19/06/201...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/11/2024	Active	10065986
10065987	BOGGI S.R.L.			AW139 AB139	AW139 EMS interiors.AW139 EMS interior in passenger cabin, including change in seatconfiguration installation, stretchers and supports for medicalequipment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Doc. No. 139P01500-Mdl-01 Issue 1, dated 22.06.2018 “MasterDocumentList”;Doc. No. 139P01500-Mdw-02 Issue2, dated 13.06.2018 “Master DrawingList”;Doc. No. 139P01500-FMS-00 Issue 1“Change 139P015-00 AW139 HelicopterEMS Interior Flight Manual Supplement”;Doc No. 139P01500-ICA-00 Issue 0 “Change 139P0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/06/2018	Active	10065987
10065995	SABENA TECHNICS BGC	REV. 2		A330-203, A330-223, A330-243	Seat Rails provisions for 9-abreast seat.Rev 01 : This revision is to add two new models (A330-203 and A330-223)to the original STC approval.Rev 02 : Editorial corrections.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to associated Certification Plan40112-03-A-CP-R06, sections 5 and 6 forT...	- ICA : 40112-03-A-ICA-R02- Master Data List : 40112-03-A-MDL-R02or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2018	Active	10065995

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066006	AEROTEC & CONCEPT			A350-941, A350-1041	Dual Medical stretcher installation on A350.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 25.23, 25.301, 25.303,25.305, 25.307, 25.321, 25.331, 25.337,25.341, 25.561, 25.613, 25.625,25.785, 25.789, 25.791, 25.80...	- Master Data List AE17185MDL Rev.1 dated 27/06/2018;- AFM Supplement AE17185AFMS Rev.0 dated 27/06/2018;- Instructions for Continued Airworthiness AE17185ICA Rev.0 dated27/06/2018;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- Per AFM Supplement AE17185AFMS.- Per Instructions for Continued Airworthiness AE17185ICA.- Pre-requisite: Aerotec Change AE16077MAS.- This STC constitutes an approval for installation only for aircraftserial numbers as stated in drawing STR-16077-001-000. For additionalaircraft serial numbers thed...	28/06/2018	Active	10066006
10066008	AVIO DESIGN GROUP INC.d/b/a AVIO DG		TCCA SH18-22	AW119MKII A109S, AW109SP, A119 A109A, A109AII, A109C, A109E	Installation of Enhanced Vision System (EVS) Max-Viz Model 1500 and2300.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: FAR 27 Amdt. 27-40 forthe affected requirements and FAR 27 Amdt 27-42 for 27.1317 requirement.The requirements for environ...	- Flight Manual Supplement 321404 Revision 2, dated October10, 2012 forMAX-VIZ 1500 Enhanced Vision System (EVS);- Flight Manual Supplement 1740-FM-001 Rev --, dated February 15,2018for MAX-VIZ 2300 Enhanced Vision System (EVS);- Flight Manual Supplement 1740-FM-002 Rev --, dated February 15, 2018...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/06/2018	Active	10066008
10066011	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 2		A330-202 A330-201/-202/-203	Interior Reconfiguration QANTAS A330-200.Rev 1: Crew Rest Compartment design update.Rev. 2: adds the SB reference to the list of technical documentation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-4304-002 Crew Rest Compartment.CRI D-3327-002 Incorporation of ILD in Dynamic SeatsThe requirements for environmental protection and the associ...	-Certification Summary: N0610-D90, Revision B, dated 14 February 2019.- Certification Summary: N0610-D91, Revision W, dated 27 September 2024.- Instructions for Continued Airworthiness: N0610-D70, Revision F, dated19 February 2020.or later revisions of the above listed document(s) approved/ accepted on...	This STC shall be installed in conjunction with EASA STC 10052319.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of t...	09/07/2025	Active	10066011
10066021	SECURAPLANE TECHNOLOGIES, Inc.	REV. 1	FAA STC ST02580SE	ERJ 190-100 STD ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ	Installation of two Securaplane Model 9750W0360-12 24 VDC/28 Ah sealedlead acid batteries	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List AM0311-DL02-00 Revision A, dated 18 May 2018 or laterFAA-approved revision.- The altered aircraft must be maintained in accordance with theInstructions for Continued Airworthiness (ICA) document AM0311-IC01-00,Revision A, dated 24 April 2018 or later FAA-accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/07/2018	Active	10066021
10066025	SABENA TECHNICS BOD			A330-223	A330-223 cabin and systems modification, and Ultra High ComfortAttendant Seat installation.This modification reconfigures the cabin layout of the MSN 253 byinstalling new passenger seats, UHCAS, IFE and cabin features (curtains,lining, floor path marking, carpet …).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, ref : MDL-S-00-4136 Issue A, dated 29 June 2018;- Airworthiness Limitation Supplement, ref : ALS-F3059-00-125 Issue B,dated 01 June 2018;- Instruction for Continued Airworthiness, ref : ICA-F3059-00-109 IssueA, dated 30May 2018;- Aircraft Flight Manual Supplement, ref : AFMS-F30...	The following modifications must be concurrently embodied with thismodification :- EASA STC 10014507 Revision 2 (or later EASA approved revision) : Floorpath marking installation.- EASA STC 10065691 (or later EASA approved revision) : A330landscapecamera installation.Prior to installation of this c...	29/06/2018	Active	10066025

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066026	SABENA TECHNICS BGC			737-800	CABIN RECONFIGURATION WITH ISPSS INSTALLATION	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:Applicable regulations at CS 25 Amendment 4 (refer to associatedCertification Plan 40090-01-A-CP-R01, sections 5 and 6 forT...	- Instructions for Continued Airworthiness, AEROCONSEIL Document ref.40090-01-A-ICA-R00- Master Data List, AEROCONSEIL Document ref. 40090-01-A-MDL-R00- Certification Plan, AEROCONSEIL Document ref. 40090-01-A-CP-R01or later revisions of the above listed document(s) approved/acceptedunder the EASA s...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/06/2018	Active	10066026
10066031	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC SH4904NM	AS 332 L, AS 332 L1, SA 330 J AS 332 C, AS 332 C1	Installation of Onboard Systems International Load Weigh Kits	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List (MDL) No. 155-002-00, Revision 19, dated 9 October2017, or later Federal Aviation Administration (FAA) approved revision.Owner's Manual 120-008-00, Revision 11, dated 9 October 2017, or laterFAA accepted revision.Rotorcraft Flight Manual Supplement (RFMS) 121-067-00, Revision 0,1...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Approval of this change in type design applies t...	04/07/2018	Active	10066031
10066032	STC TWENTY ONE LIMITED	REV. 2	CAA UK RESPONSIBILITY	737-400 737-300	Introduction of structural provisions for GNSS antennas.REV. 2: editorial correction	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC TWENTY ONE MASTER DOCUMENT LIST No. S21. MDL-1429 issue2	To remain compliant with FAA AD 2017-22-04 perform inspections perService Bulletin 737-53A1349 in the area of the installation prior tocommencing the installation.This design change (S21.53-13-1053) is an alternative means ofcompliance (AMOC) to FAA Airworthiness Directives 2012-26-02 in theregion o...	18/07/2018	Active	10066032
10066036	AEROTEC & CONCEPT			DR 400 NGL, DR 400 RP DR 400/2+2, DR 400/500 DR 400/200 I, DR 400/200 R DR 400/180 S DR 400/180, DR 400/180 R DR 400/160, DR 400/160 D DR 400/140, DR 400/140 B DR 400/125, DR 400/125I DR 400/120 A, DR 400/120 D DR 400/100, DR 400/120 DR 315, DR 340, DR 360, DR 380 DR 300/180 R DR 300/125, DR 300/140 DR 300/108, DR 300/120 DR 253, DR 253 B DR 250, DR 250 B DR 250 B-160, DR 250-160 DR 221, DR 221 B DR 220, DR 220 A, DR 220 AB DR 220 B DR 200	ASPEN EFD1000 primary flight display	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MASTER DATA LIST ref. AE18010MDL Rev. 1 dated 29.06.2018AIRCRAFT FLIGHT MANUAL SUPPLEMENT ref. AE18010AFMS Rev. 0 dated14.06.2018or later revisions of the above listed document(s)approved/ acceptedunder the EASA system.	None	02/07/2018	Active	10066036

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066037	S4A SOLUTIONS FOR AVIATION, S.L			BN2A-21		The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 23 Amdt. 4paragraphs: 23.1, 23.21, 23.25, 23.29, 23.45, 23.49, 23.51, 23.53,23.59, 23.63, 23.65, 23.73, 23.75, 23.141,2...	Flight Manual Supplement BN005-HDK01, issue 1, dated 27/09/17or later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/07/2018	Active	10066037
10066039	SOCIETE AIR FRANCE S.A.			A340-313	A340 JOON "SOFA" seat installationBed convertible passengerseats installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Société Air France Change Approval Sheet CAS-A340-17-013 Revision 0dated 15 June 2018- Société Air France Cabin Crew Operating Manual Supplement CCOMS-A340-17-013-001 Revision 0dated 13 June 2018or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/07/2018	Active	10066039
10066054	BOGGI S.R.L.	REV. 1		AB139, AW139	Installation of external Camera System on AW139 external supportInstallation of an external camera P/N TC-1542HD using the structuralprovisions P/N 139P014-1000-0000-00 or 139P014-1100-0000-00 designed byBoggi S.r.L previously approved at initial issue of this STC on 03 July2018.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List 139P01410-MDL-03;Flight Manual Supplement 139P01410-FMS-02;or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system	It is prohibited to operate the camera during any phase of flight and onground.Pre-requisite for the installation of this STC is that the helicopterhas embodied the following Leonardo S.p.A changes :P/N 3G3340A01352P/ N 3G3340A01452.Prior to installation of this change/repair it must be determined th...	18/01/2019	Active	10066054
10066058	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE		TCCA O-LSA18-009/D	DHC-8-201, DHC-8-202	Cargo Abrasion Protection System for Combi Configurations.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation is to be in accordance with DECA Aviation Engineering Ltd.Modification Summary MS18011, Revision 1, dated February 20, 2018< (>,<)>or later revisions of the above listed documents approved by EASA inaccordance with the Technical Implementation Procedures of EU/ CanadaBilateral Agreement....	The mixed passenger-cargo configuration defined in TCDS EASA.IM.A.191shall be incorporated prior to or in conjunction with this modification.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design...	05/07/2018	Active	10066058
10066088	AVIATION FABRICATORS, Inc.		FAA STC SA01809WI	SEE FAA AML	Installation of an Operator Seat onto an existing Cabin Seat Track.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	In accordance with FAA Approved Model List SA01809WI.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/07/2018	Active	10066088
10066090	BOGGI AERONAUTICS S.R.L.	REV. 1		AS 365 N3 AS 365 N2, AS 365 N3 AS 365 N2	Installation of Trakkabeam A800 High Intensity Searchlight System.Rev.1: STC transferred to Boggi Aeronautics S.r.l.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Doc. No. PAL-CPR-1303 “Compliance Report”, Rev. A dated June 27, 2018Doc. No. PAL-MDL-1303 “Master Document List”Doc. No. PAL-FMS-AS365-112 “Flight Manual Supplement Trakkabeam® A800Searchlight System”, Revision ADoc. No. PAL-ICA-1303-001 “Instructions for Continued AirworthinessTrakkabeam® A800 Sea...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/03/2024	Active	10066090

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066091	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	777-300ER	SkyCouch Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS26.1, CS26.50(d)(2), and CS26.120(a)(2)(i) at Amdt. 1The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	Master Configuration Scheme, Ref. 3168-MCS-01 Issue 2or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Skycouch can only be used as a sleeping or an accommodationarea duringin-flight conditions, as detailed in SWS Certification Services LtdDesign Report 3168-DR-01.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	04/07/2018	Active	10066091
10066096	EIRTECH AVIATION SERVICES LIMITED			737-8/-800/-900/-900ER 737-400/-500/-600/-700 737-100/-200/-200C/-300	737 Family ADS-B Out - Honeywell	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS Initial IssueThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and rema...	Master document List MDL/ 1014-001 Issue 8or later revisionsof the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/07/2018	Active	10066096
10066109	DELTA G DESIGN Inc.	REV. 1	FAA STC ST09852AC	737-900/-900ER 737-400/-500/-600/-700/-800	Installation of Securaplane and Otonomy camerasInstallationof Securaplane and Otonomy Cameras (structural provisionsonly) on the tailfin and belly of the fuselage on Boeing 737 seriesaircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:- EASA CS 25 Amdt 0: 25.23, 25.251, 25.303, 25.365, 25.571, 25.581,25.601, 25.603, 25.605, 25.609, 25.611, 25.613, 25.625,2...	- Master Data List, DGD-SOCM01-MD-01, rev. IR, dated 17 December 2015- Instructions for Continued Airworthiness, DGD-SOCM01-IC-01, Rev. IR,dated 15 December 2015or later revisionsof the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProced...	Functional installation of cameras and associated equipmentis notapproved as part of this STC.Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffec...	11/07/2018	Active	10066109
10066114	OUTERLINK CORPORATION		FAA STC SR00376BO	EC 130 B4 AS 350 B3	The STC installs a SATCOM and Flight Data Monitoring System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval, except where amended by additional orlater amendments if indicated on FAA STC SR00376BO.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	Model AS 350 B31. Outerlink Corporation Master Drawing Listdocument numberMDL350-SAT-100, revision C, dated 10 February 2017, or later FAAapproved revision.2. Outerlink Corporation Rotorcraft Flight Manual Supplement (RFMS) document numberFMS350SAT001, revision IR, dated 27 October 2016, orlater FA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/07/2018	Active	10066114
10066117	JET AVIATION AG	REV. 1		747-400F, 747-747SP 747-200F, 747-300, 747-400 747-100, 747-200B, 747-200C	Rev. 0The ADS-B Out installation consists of:- replacement/upgrade of dual ATC SSR transponders by ADS-B models(RTCA/DO260B)- replacement of dual GNSS receivers by SBAS receivers or reuse ofexisting SA-Aware GPS receivers- replacement of dual GPS antennas by SBAS models when GPS receivers arereplac...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:For this change, JBSL elected to comply with EASA CS25 Amdt. 20except 25.1322 (reverted back to JAR 25 ch 10), andexcept Su...	- Aircraft Flight Manual Supplement, JBSL-M-1086 AFM-01, Issue 3- Instructions for Continued Airworthiness, JBSL-M-1086ICA-01, Issue 3- Engineering Order, JBSL-M-01086ENO-01, Issue 3- Master Data List: JBSL-M-01086MDL-01, Issue 5,,or later revisions of the above listed documents approved by EASA.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/04/2019	Active	10066117

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066126	DELTA ENGINEERING CORPORATION		FAA STC ST03436NY	787-8, 787-9	Installation of a Panasonic Avionics Corporation Global CommunicationSuite (GCS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List 0165-10375-2433 Revision- dated 8February 2018 or later FAA approved revisions to Delta EngineeringMaster Data List previously listed. The Instructions for ContinuedAirworthiness as listed on the Master Data List is required with thisinstallation.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/07/2018	Active	10066126
10066131	ALAMO ENGINEERING GmbH	REV. 2		MYSTÈRE FALCON 50 (MF50)	Aviator 300 SBB SATCOM with WLAN.Revision 2: Transfer to ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	328 Support Services GmbH Airplane Flight Manual SupplementNo.AFMS020C 231Z0001 Rev. B<(>,<) >328 Support Services GmbH MASTER DOCUMENT LIST No. MDL129Z001 Rev. B.or later revisions of the above listed document(s) approved/acceptedunder theEASA system	Restricted to ASN 345.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10066131
10066134	JET AVIATION AG	REV. 1		SEE EASA APPROVED MODEL LIST	WIRELESS LAN (WLAN) ActivationRev. 0:This STC demonstrates immunity to IEE 802.11 a/b/g/n/ac passengers' PEDtransmissions on model Dassault Falcon 7X. The installation of the WLANAccess Point (WAP) is not part of this STC, however, the systemspecifications have been included in the Engineering Order...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Rev 0 and 1: CS25 Amdt21; 25.789, 25.831, 25.869, 25.1301, 25.1309, 25.1351, 25.1353, 25.1357,25.1360, 25.1431, 25.1529, 2...	Rev 0:AFMS JBSL-M-01123AFM-01 Issue 1 "WIRELESS LAN (WLAN) ACTIVATION"Rev 1:AFMS JBSL-M-01123AFM-01 Issue 2 "FOR A/C: DassaultF900EX/F2000/ F2000EX/F7X Series; WIRELESS LAN (WLAN) ACTIVATION"AFMS JBSL-M-01123AFM-02 Issue 1 "FOR A/C: Bombardier BD-100-1A10,BD-700-1A10/-1A11/-2A12 Series; WIRELESS LA...	For Ref 0 and 1:This change is applicable to airplanes previously fitted with properlycertified:- Wireless Access Point(s) capable to transmit only onIEE802.11a/b/g/n/ac protocols, or a subset of these protocols, with notmore than 1000 mW transmitted power capacity- The WAP power supply must be supp...	03/11/2020	Active	10066134
10066135	JET AVIATION AG	REV. 1		747-400 747-300	WIRELESS LAN (WLAN) Activation1. Certification of Compatibility with Wireless Data technologies shallbe in accordance with Jet Aviation AG Master Data ListJBSL-M-01097MDL-01 Issue2, dated Aug 21, 2018 or later EASA approvedrevision. This STC demonstrate only the immunity to IEEE 802.11a/b/g/n/ ac pa...	NEW-PAGEThe Certification Basis for the original product asamended by thefollowing additional or alternative airworthiness requirements:CS25 Amdt 21, CS 25.789, 25.831, 25.869, 25.1301, 25.1309, 25.1351, 25.1353, 25.1357, 25.1360, 25.1431, 25.1529,25.1581, 25.1707The requirements for environmentalc...	AFMS JBSL-M-01097AFM-01_I2 WIRELESS LAN (WLAN) ACTIVATIONorlater revisions of the above listed documents approved by EASA	1. This STC does not constitute installation approval of a wirelessradio frequency system using wireless data technologies. It onlyprovides data that may partially support their installations oractivations with a separate approval. These data are provided in theEngineering Order JBSL-M-01097ENO-01 i...	24/08/2018	Active	10066135
10066144	PRECISE FLIGHT, Inc.		FAA STC SA00560SE	407	Installation of the Precise Flight Pulselite Controls System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The system is to be manufactured in accordance with PreciseFlightEngineering Drawing lists 002P0000< (>,<)> Revision J; 015P0000, RevisionK; 025P0000, Revision H, or later FAA approved revisions. It is to beinstalled in accordance with appropriate Precise Flight Drawing List141P0000 Revision B, or l...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/07/2018	Active	10066144

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066145	JET AVIATION AG			MYSTÈRE FALCON 900 (MF900) MYSTÈRE FALCON 50 (MF50) FALCON 900EX (F900EX)	JBSL F900 Medevac Units Installation.Installation of Medevac units, medical equipment and medical cabinet.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 25.23, 25.25, 25.27,25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.341, 25.365, 25.561,25.562, 25.571, 25.601, 25.603,(...	- Master Data List JBSL-M-00999MDL-01 Issue 1 dtd. 9 July 2018;- AFM Supplement No. JBSL-M-00999AFM-01 Issue 2 dtd. 9 July 2018;- Instructions for Continued Airworthiness JBSL-M-00999ICA-01 Issue 2dtd. 27 April 2018;or later revisions of the above listed document(s) approved under theEASA system.	- Per AFM Supplement No. JBSL-M-00999AFM-01.- Provisions for Medevac unit installation per EASA STC 10061969.- Oxygen components are not certified for use with pressurized oxygen.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair an...	10/07/2018	Active	10066145
10066148	FOKKER SERVICES B.V.	REV. 1		737-900, 737-900ER 737-600, 737-700, 737-800 737-600/-700/-800/-900/-900ER	ADS-B out on the Boeing 737 NG seriesThis change introducesADS-B capability on the Boeing 737 NG seriesaircraft.Revision 1 introduces the use of dual standalone GPS/SBAS receivers asGNSS source to enable ADS-B out V2 capabilities.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Compliance Record Report CRR-0343 Issue 1 dated 27 June 2018- Aircraft Flight Manual Supplement B737-ADSB-AFM-S-001 Issue 2 dated 26April 2018- FCD Supplement B737-ADSB-FCD-S-001 Issue 1 dated 06 March 2018- MMEL Supplement B737-ADSB-MMEL-S-001 Issue 1 dated 12 March 2018For Revision 1 of STC- Cer...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/09/2020	Active	10066148
10066150	Q.C.M. DESIGN GmbH			BD-700-1A10	Passenger Seating Refurbishment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Report, BBD7-QCM25-016, Rev. 1;Instructions for Continued Airworthiness, BBD7-QCM25-016-M1-ICA, InitialIssue;or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Effictivity: S/N 9043.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	11/07/2018	Active	10066150
10066156	APTOZ EHF.	REV. 1		757-200, 757-300	Icelandair Modification CRA-757-4620 issue 01, Enabling EFBServerConnectivity via GEE SMU (Ku).This change enables theconnectivity of existing Electronic Flight Bag(EFB) system via the existing Global Eagle Entertainment (GEE) Wifisystem. It permits the DIC-600 (EFB Server) to communicate to groun...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC/IM CRI F-01, on Security protection ofAircraft systems and networks from internal and external SecurityThreats.- The following para...	Icelandair Instructions for Continuing Airworthiness Document ref.CAI-757-4620-009 Initial Release, dated 05 July 2018<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior or concurrent modification (s):The EFB System is to beinstalled in accordance with ScandinavianAvionics Design (SA)EASA STC 10056177.The GEE Wifi System (previously known asRow44) is to be installed perEASA VSTC 10044038).IcelandairDOA approved Minor changes EO-757-4620-05 andEO-757-4620-007...	27/05/2025	Active	10066156
10066160	N2 DEVELOPMENT, Inc.		FAA STC ST02518LA	A321-272NX A321-271N, -271NX, -272N A321-252NX, -253N, -253NX A321-251N, -251NX, -252N A321-212, -213, -231, -232 A321-111, -112, -131, -211 A319-115, -131, -132, -133 A319-111, -112, -113, -114	1. N2 Development, Inc. Certification Data List N2101-CDL, Revision "J",dated 20 January 2017<(>,<)> or later FAA approved revision.2. N2 Development, Inc. Maintenance Manual Supplement N21010301, Issue"002", dated 30 January 2014 or laterFAA approved revision.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02518LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.		12/07/2018	Active	10066160

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066161	OUTERLINK CORPORATION		FAA STC SR00365BO	407 206L-4 206L-3 206L-1 206L	Helicopters modified with an Installation of an Outerlink SATCOMCommunications and Flight Data Monitoring System KIT B206-SAT-100 or KITB407-SAT-100.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00365BO.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Outerlink Corporation's Master Drawing Lists (MDL), Document numberMDLB206-SAT-100, revision C, dated 9 March 2016 or MDLB407-SAT-100revision C dated 15 March 2016, or later FAA approved revision.2. Outerlink Corporation's Rotorcraft Flight Manual Supplements (RFMS) Document number FMSB206SAT001,R...	This system does not meet the operational rule requirement of a voice orflight data recorder system.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverse...	12/07/2018	Active	10066161
10066162	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	200	Approval for the relocation of ADF Antenna on KingAir 200 in accordancewith 2 Excel Design Limited Modification 2XL051.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with 2 Excel Design Master Data List ref2XL051 LEF78, Issue 2, dated, 06.07.2018;There is noFlight Manual Supplement associated to this change;Instructions for Continued Airworthiness (ICA) in accordance with 2Excel Design Document ref 2XL051 LEF73(1), Issue 1;or later re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/07/2018	Active	10066162
10066166	FTI ENGINEERING NETWORK GmbH			B. B200GT, B300, B300C B. B200, B200C, B200CGT A. C90GTI	Installation of ADS-B Out for King Air 90/200/300 and Premier 1/1Aaircraft in accordance with FTI Engineering Network GmbH modificationref 18-1632.	CS-ACNS Issue 1.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicableto this certificate/ approval.	Installation in accordance with FTI Engineering Network GmbHmodification ref 18-1632 Master Document List F18-EO18-1632, Issue 01,dated 09.07.2018 and Installation Instructions ref F23-001-EO18-1632Issue 2, dated 06.07.2018;Operation in accordance with FTI Engineering Network GmbH AircraftFlight Man...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/07/2018	Active	10066166
10066194	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		EC635 T3 EC635 T1, EC635 T2+, EC635 T3 EC635 P2+, EC635 P3 EC135 T3, EC635 T1, EC635 T2+ EC135 T3 EC135 T1, EC135 T2, EC135 T2+ EC135 P3, EC635 P2+, EC635 P3 EC135 P3 EC135 P1, EC135 P2, EC135 P2+	Installation of AeroStretcher Mk IV Modular EMS System in accordancewith Master Data List GVH-6463-02-MDL-01Rev. 1: Transfer of STC to GVH Aerospace (Ireland) Ltd., Pembroke Place10, DO2 ED86 Dublin Eire	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 amendment 2 forthe following paragraphs: 27.625/27.783(a)/27.807(a)(1)/ 27.1413The requirements for environmental pro...	Rotorcraft Flight Manual Supplement GVH-6463-02-FMS-01 Issue 1Instructions for Continued Airworthiness GVH-6463-02-ICA-01 Issue 2Master Data List GVH-6463-02-MDL-01 Issue 2or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/12/2020	Active	10066194
10066206	SPECIALIST AVIATION SERVICESLIMITED		CAA UK RESPONSIBILITY	AW169	AW169 Paediatric Intensive Care Interior (SAS/MOD/935).ThisSTC includes the installation of optional TCAA Litter Bridge (SAS/MOD/934).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Declaration of Compliance for SAS/MOD/935 Issue A, dated 11/07/2018Rotorcraft Flight Manual Supplement FMS/935-043 Issue ARotorcraft Flight Manual Supplement FMS/934-043 Issue AMaintenance Program Supplement MPS/935-040 Issue AMaintenance Program Supplement MPS/934-040 Issue Aor later revisions of t...	NVIS operation requires separate design approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	16/07/2018	Active	10066206

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066209	BOMBARDIER Inc.		TCCA SA17-121	BD-100-1A10	Bleed Air Leak Detection System Loop Element Shell and Insert AssemblyReplacement.EASA Validation of Transport Canada STC SA17-121 at Issue 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DECA Aviation Engineering Ltd. Master Data List MDL17099, Revision 1,dated December 19th, 2017 (approved), andDECA Aviation Engineering Ltd. Instructions for Continued AirworthinessICA17099, Revision 1, dated December 19th, 2017 (accepted)or later revisions of the above listed document(s) approved/a...	See those of original Transport Canada STC ST17-121.Installation is to be in accordance with DECA Aviation Engineering Ltd.Master Data List MDL17099, Revision 1, dated December 19th, 2017, orlater approved revisions.Maintenance is to be inaccordance with DECA Aviation Engineering Ltd.Instructions f...	16/07/2018	Active	10066209
10066218	SOCIETE AIR FRANCE S.A.			A330-202	Air Mauritius cabin rearrangement.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-4312-001 Non-rechargeable lithium batteryinstallations.The requirements for environmental protection and the associatedcertified noise and/ oru...	Société Air France Change Approval Sheet CAS-A330-17-003 Revision 0 forAir Mauritius Cabin Rearrangement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/07/2018	Active	10066218
10066225	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED	REV. 2	CAA UK RESPONSIBILITY	EC135 T2, EC135 T2+ EC135 P2, EC135 P2+	External Payload Category A OperationsInitial:Approval for Category A operations with payloads embodied on aircraftwithlow skidsRevision 1:Correction of typo in the limitations/conditions section of the approvalcertificateRevision 2:Approval for Category A operations with Payloads embodied on aircr...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 amendment 4:27.1/27.51(a)/ 27.71/27.141/27.143(a),(b)/ 27.171/27.1501/27.1525/27.1581/ 27.1583(e)/27.1585(a)/27.1587 (a)...	Rotorcraft Flight Manual Supplement FMS/155-003 Issue 3Design Report DR/ 155-002 Issue 3Modification Leaflet & Certificate of Design, MDL/ 155-010 Issue 4or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to Helicopters having EASA STC 10017058 installed (StarboardMeeker Utility Step with Fore C10 Mounting Arm for FLIR 380HD/HDcpayloads and Aft A11 Mounting Arm for Trakka A800 payload)Prior to installation of this change/repair it must be determined thatthe interrelationship between this chan...	17/12/2020	Active	10066225
10066231	MECAER AVIATION GROUP S.p.A.			505	Bell 505 VIP Interiors P/N 6B5J0000X001001 in accordance with DesignData Set DDS-18-001 Rev. C.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	NDC 6B5JX-0001/III, Issue B, dated 10.07.2018;Rotorcraft Flight Manual Supplement 6B5JRFM-1-1, Issue 0, Revision 0;Master Minimum Equipment List (MMEL) Supplement 6B5JMML-3-1, Issue 0,Revision 0;Design Data Set DDS-18-001 Issue C;Owner's Manual for B505 VIP Interiors 6B5JWNM-2-1, Issue 0, Revision 0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/07/2018	Active	10066231
10066237	AMAC AEROSPACE SWITZERLAND AG			A319-133	Cabin RefurbishmentWith this change several items of the cabin equipment/ furnishing arereplaced or removed, refurbishedand re-installed again.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01, Security protection of aircraft systemsand networks;The following paragraph (s)at a later amendment: CS 25 Amendment 19CS25.603; CS25.788;T...	The Change is defined through AMAC Master Data List MDL-BK09-2500,Revision D;The aircraft shall be operated in accordance with AMAC Airplane FligthManual Supplement AFMS-BK09-2500, Revision A;Maintenance shall be performed in accordance with AMAC Instructions forContinued Airworthiness ICA-BK09-2500...	STC 10014023 (Cabin VIP master modification, including conversionprivate to public) STC 10014234 (Live TV antenna installation), STC10037123 (Monitor replacement Plasma to LCD), STC 10014644 (Installationof additional water Tank), STC 10015206 (WLAN activation) must beaccomplished prior to or in con...	18/07/2018	Active	10066237

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066238	LUFTHANSA TECHNIK AG	REV. 1		A320-232	A6-SHJ Cooktop InstallationThe change consists of the installation and operation of an InductionCooking Platform (IPC) into the Aft Galley G5 previously modified.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.813, 25.1365,25.853 at Amdt 20.The requirements for environmental protection and the associatedcertified noise and...	- Supplemental Type Design Document STDD25-17/34M Iss/ Rev02/00- Airplane Flight Manual AFM A-00-18/54-AFM Iss/Rev 01/00- Instruction for Continued Airworthiness ICA A-00-18/54-ICA Iss/ Rev04/00- Cabin Crew Data A-00-18/54-CCD Iss 04or later revisions of the above listed document(s) approved/accept...	STC 10061321 for cabin completion needs to be installed before thisdesign change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the air...	27/06/2019	Active	10066238
10066248	GVH AEROSPACE (IRELAND) LIMITED	REV. 4		A319-131, A320-232, A321-231	Installation of In-flight Canada USB, AES AC Power Systems and In-flightCanada Provisions KitsRev. 1 extends the applicability by adding Airbus A319-131 aeroplanes.Rev. 2 extends the applicability by adding Airbus A320-232 aeroplanes.Rev. 3 updates the section of Description Design Change.Rev. 4 tra...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	GVH Aerospace Master Data List GVH-8141-01-MDL-O1 issue 10<(>,<) >GVH Aerospace Flight Attendant Manual Supplement GVH-814101-FAS-01 issue1<(>,<)>GVH Aerospace Instructions for Continued AirworthinessGVH-8141-01 -ICA-0l issue 4or later revisions of the above listed document(s) approved/ acceptedunder t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/03/2021	Active	10066248
10066260	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC ST04219AT	A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	Version 7.1 Software upgrade of the Aviation Communication &Surveillance Systems (ACSS) TCAS II Model TCAS 2000, P/N 7517900-10020(Configuration 1) or Model T2CAS, P/N 9000000-11414 (Configuration 2).This upgrade allows for the installation of Configuration I TCAS II. Theinstallation also includes a...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List A330-150105-010, Revision B, dated 15 July2015 orlater FAA approved revisions and upgrade to P/N 7517800-10403, inaccordance with Master Data List 8900062-001, Revision -, dated 19 June2018 or later FAA approved revisions.FAA approved Airplane Flight Manual Supplement (AFMS) SCR En...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/07/2018	Active	10066260
10066262	LIFEPORT, Inc.		FAA STC SA00183WI	SEE FAA AML	Installation of Overhead Console Cabinets	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	LifePort, Inc., Master Drawing List 600-1132, Revision O, dated 25 June1997, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	20/07/2018	Active	10066262
10066265	AIRBUS S.A.S.			A321-231 A321-212 A321-211	MOD AI0010 ADDITIONAL WATER TANK INSTALLInstallation of an additional water tank (capacity 160l) in lower partof cabin between Fr35.8 and Fr 36.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- MAS AI0010 issue 01, dated 19/07/2018;- AIS-AJA-17132 issue 04 - Certification Summary Report, dated19/07/2018.	None	20/07/2018	Active	10066265

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066272	AVIONIK STRAUBING ENTWICKLUNGS GmbH			TBM700 N TBM700 C1, TBM700 C2 TBM700 A, TBM700 B	Installation of Comant CI 490-490.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment: EASA CS23, Amd. 04, dated15.07.2015: 23.29; 23.301; 23.303; 23.305(a); 23.305 (b); 23.307(a);23.337 (a)(1); 23.365(a); 23....	Master document list ASR-2017-006-MDL-01-00 Rev. 00 dated 13.07.2018;Airworthiness Limitation Section (§3) of ASR-2017-006-11-ICA-00 Rev. 00dated 19.03.2018;or later revisions of the above listed document(s) approved/ acceptedunder the EASAsystem.	This STC covers the mechanical installation of the Comant CI 490-490antenna only. Functional aspects must comply with the documentation ofthe connected devices.	23/07/2018	Active	10066272
10066273	AVCON INDUSTRIES, Inc.		FAA STC ST01881WI	35, 35A, 36, 36A	Installation of the Garmin GTS 8000 TCAS II System and DualGTX 3000Transponders for ADS-B Out Compliance and Interfaceof factory installedFC-530 Autopilot System to Single/Dual GTN 7XX/6XX Navigators.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List, Document No. 04701000, Rev. IR, dated 5 July 2018,or later FAA Approved revision; and2. Airplane Flight Manual Supplement, Document No. 04707100, Rev. 0,dated5 July 2018, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/07/2018	Active	10066273
10066318	BIGORRE AEROSPACE CORPORATION	REV. 1	FAA ST04265CH	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Installation of a Cabin LED Lighting System.Rev. 1: Transfer from GDS AERO LLC. to BIGORRE AEROSPACE CORPORATION.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- GDS Master Data List (MDL)), GDS-F900-002, Revision I/R, dated 26November 2016- Instructions for Continued Airworthiness, GDS-F900-030, Revision I/ R,dated 22 November 2016or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implemen...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2021	Active	10066318
10066327	PRATT & WHITNEY ENGINE SERVICES, IN	REV. 2	FAA STC SA00393BO	PC-12/ PC-12/45/ PC-12/47 PC-12/47E	Installation of the Pratt <(>&<)> Whitney Engine Services FAST System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Pratt & Whitney Engine Services Master Data List (MDL), Document numberGN4-T-100-9, Revision G, dated 28 August 2019, or later FAA approvedrevision.Pratt < (>&<)> Whitney Engine Services Aircraft Flight Manual (AFMS)Document number GN4-T-250-8, Revision C, FAA approved on 27 September2019< (>,<)> or l...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/05/2020	Active	10066327
10066333	CHIPPEWA AEROSPACE, Inc.		FAA STC ST04411AT	550/ 560/ 560XL	Installation of Upgraded IC-615 with NZ-2000 FMS Software Version 6.1.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Chippewa Aerospace Master Drawing List (MDL) No. 560-3461-01-0001,Rev. IR, dated 26 December 2016, or later FAA approved revision.2. Airplane Flight Manual Supplement (AFMS) tothe Model 550 (Bravo),560 (Encore), 560XL (Excel), 560XL (XLS) for Upgrade for the IC-615 withNZ-2000 FMS Software Versi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/08/2018	Active	10066333

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066351	B/E AEROSPACE, Inc.		FAA ST04427AT	737-900, 737-900ER 737-600, 737-700, 737-800	Installation of Rockwell Collins Automatic Dependent Surveillance –Broadcast (ADS-B) Out System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instructions for Continued Airworthiness (ICA) Document 2-193114-804;Airplane Flight Manual Supplement (AFM) Document 2-193114-805;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with theTechnical ImplementationProcedures of EU/ USA Bilateral Agre...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/11/2018	Active	10066351
10066352	ALOFT AEROARCHITECTS		FAA STC ST03746NY	A330-201/-202/-203/-223/-243	Viasat KA Cabin Distribution System Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments as indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Data List (MDL) 1266000, revision 005, dated 23 May 2018, orlater FAA approved revision for Activated, Provisions and Deactivatedconfigurations. 2. Instructions for Continued Airworthiness (ICA) 1265316, revision 001,dated 05 January 2018, FAA accepted 24 May 2018 or later FAA acceptedrevis...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The following alterations are prerequisite...	09/08/2018	Active	10066352
10066355	CARLISLE INTERCONNECT TECHNOLOGIES	REV. 1	FAA STC ST04292CH	A321-251N/-253N/-271N/-272N A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-251N/-271N A320-231/-232/-233 A320-211/-212/-214/-215/-216	Installation of ARINC 791 Antenna ProvisionsNew VSTC for installation of ARINC 791 Antenna Provisions with thefollowingconfigurations:1. ARINC 791 SATCOM Antenna System Provisions Installation.2. Installation of Emergency Locator Transmitter (ELT) Antenna InternalStructural Support.3. ARINC 791 SAT...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CS 25.251(b) CRI B-0301-005 Vibration andbuffeting compliance criteria for largeexternal dated 04 july 2018The requirements for environmenta...	-Master Data List (MDL) 900-102886 Rev. C dated Jun 6, 2018-Airplane Flight Manual Supplement (AFMS) Document N. 900-102890Revision A-Instruction for Continued Airworthiness (ICA), Section 4, AirworthinessLimitations< (>,<)> Document N. 900-102891 Revision Bor later revisions of the above listed docu...	1) The equipment for which these provisions are intended has not beenverified. Additional approval is required for the installation of thisequipment and must be evaluated to assure satisfactory compliance withthe applicable airworthiness standards.2) If the holder agrees to permit another person tot...	06/08/2018	Active	10066355
10066362	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A340-542	TC-CAN Meeting Room Modification	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.785 (b)(c)(d)(f)(h)(j)(k) (Amdt 21), 25.853 (a)(c)(d) (Amdt 21),S25.20 (Amdt 21), S25.30 (Amdt 21), S25.50 (Amdt 21)The requirements for environmental protection and th...	C0169-CEP-04, C0169-ODT-01, C0169-CCO01-01or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/08/2018	Active	10066362
10066363	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A340-542	TC-CAN Monument Introduction	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:25.853 (a)(d)(e) (Amdt 21), 25.1729 (Amdt 20)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original produ...	C0174-CEP-04or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/08/2018	Active	10066363
10066364 (EASA.IM.R.S.00292)	AKV, Inc.	REV. 1	FAA STC SR01452LA	AS 350 B, - B1, -B2, -BA	Installation of an AKV, Inc (formerly AKV Partners) Ng cycle counter,p/n 350NGTEC.Rev. 1 updates the STC holder's address	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List No NCC-001, Rev. B, dated 10 January 2004, or laterFAA-approved revisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The Ng cycle counter can only be installed on day/ night...	13/09/2018	Active	10066364

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066365 (LBA 0368/539)	ACC COLUMBIA Jet Service GmbH	REV. 4		F172L, F172M, F172N, F172P 172Q, 172RG, 172 R, 172S 172K, 172L, 172M, 172N, 172P	GO2018-68_C172-606500 ExhaustInstallation of an externally mounted exhaust silencer systemC172-606500 resp. C172RG-606500	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	iaw. Master Document List MDOCL_2051129_rev0_20190208to be operated iaw. AFM Supplement SPOH_2051129_rev0_20190208to beinstalled iaw. Installation Instruction II_2051129_rev0_20190208to be maintained iaw Maintenance Manual SupplementMMS_2051129_rev0_20190208or later revisions of the above listed do...	Condition:Documents issued with modification kits deliveredbefore June 2019remain valid and applicable unless expressively noted on later approvedrevisions.Limitation:iaw. Limitation section of AFM-SThe installation of this modification by third person is subject towritten confirmation by the appro...	26/01/2022	Active	10066365
10066387	365 AEROSPACE DDS LIMITED	REV. 2		B300, B300C B200, B200C, B200GT, B200CGT	Change to install a CVDR on Beechcraft.Rev. 1: to include similar aircraft types.Rev. 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDS Ltd	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installed, Maintained and Operated in accordance with the documentscontrolled by Master Data List: Document No. Master Data List, MDL-0588Rev B, Dated 03 August 2018<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Applicable to aircraft equipped with Rockwell Collins Avionics Suite,see Document ICA-0588-001, Section 4.2.-Electrical Loads Analysis must be performed, see DocumentICA-0588-001, Section 3.2.Prior to installation of this change/repair it must be determined thatthe interrelationship between thisp...	05/08/2019	Active	10066387
10066395	MORSON PROJECTS LIMITED		CAA UK RESPONSIBILITY	B200GT B200CGT	Installation of two LITEF LCR-100N Attitude and Heading Reference Units (AHRU) on the B200GT/B200CGT equipped with Rockwell Collins Fusion (Change MP0004A).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-To be installed documents listed in Master Data List MP0004A ChangeReport Issue 1 dated 1st Aug 2018-To be operated according to AFM Supplement 3 – LITEF LCR-100N AHRS,issue 1;-To be maintained according to ICA MPL-C-02-AW0027 Issue 1 dated 31stJuly 2018;or later revisions of the above listed docum...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/08/2018	Active	10066395
10066398	ALOFT AEROARCHITECTS	REV. 1	FAA ST03742NY	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Viasat KA Cabin Distribution System Installation.Revision 1adds the A319 and A320 models.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 amdt. 11: 25.869(a)(3), 25.899The requirements for environmental protection and the associatedcertifieda...	1. Master Data Index List (MDIL) 1284835, revision 039, dated 16September 2024<(>,<)>2. ICAa. Viasat Document No. 1277469, Revision 012, dated 15 January 2024<(>,<)>b. Viasat Document No. 1325036, Revision 006, dated 15 January 2024<(>,<)>c. Viasat Document No. 1377420, Revision 007, dated 11 Januar...	The following alterations are prerequisites to this installation: EASASTC 10069607 Installation of a Viasat KA SATCOM Antenna System.Prior to activation of a Wireless Cabin Distribution System, it must beshown that the aircraft is compatible with transmitting portableelectronic devices (T-PED).Opera...	23/06/2025	Active	10066398
10066419	S4A SOLUTIONS FOR AVIATION, S.L			FALCON 10	INSTALLATION OF FLIGHT DATA RECORDER L3·SSFDR MODEL F1000	The Certification Basis for the original product remains applicable tothis certificate/ approval.Special Condition(s): CRI F-01 Non-rechargeable Lithium BatteryInstallationsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original produc...	-FAL102-SB001 Service bulletin Edition 10-FAL102-HDK01 Flight Manual Supplement Edition 3-FAL102-HDK02 Maintenance Manual Supplement Edition 6or later revisions of the above listed document(s) approved under theEASA system.-FAL102-CPL01 Certification Plan Edition 11-FAL102-STA01 STC Declaration Edit...	None	09/08/2018	Active	10066419

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066428	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 2		777-300	Interior Reconfiguration of Cathay 777-300 Aircraft with OptionalInstallation of Bucher Stretcher.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 (Non-rechargeableLithium BatteryInstallations); CRI-D-01 (Inflatable Restraint Systems).- The following paragraph(s) at a later amendment...	- Certification Summary, Northwest Aerospace Technologies, Inc. documentN0593-D90, Revision G, dated 17 May 2019;- Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document N0593-D70, Revision C, dated 8 August 2018;or later revisions of the above listed document (s) ap...	: The following Approved B/E Aerospace Service Bulletins shall beconcurrently installed: B/E Aerospace Service Bulletins 25-30-1019 and25-30-1021 for airplane MSN 28687, 29396, 32697, 32699 and 32702installation of a steam oven for the G2 galley and 25-30-1020 and25-30-1022 for airplane MSN 28687, 2...	22/05/2019	Active	10066428
10066443	WEST STAR AVIATION, LLCd/ b/a WEST STAR AVIATION	REV. 1	FAA STC ST00818DE	SEE EASA APPROVED MODEL LIST SEE APPROVED MODEL LIST	Installation of Honeywell Control Display Unit (CDU) model CD-830 toreplace the following CDU's: CD-810, CD-815 and CD-820Revision 1: Addition of Textron Cessna 560 XL	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.29, 25.771(a)(e), 25.773 (a)(2), 25.777 (a)(b)(c), 25.1301 (a)(1)(2)(3), 25.1309(a)(b)(c)(d), 25.1322, (...	-0040312-001 – Master Data List CD-830 FMS Control Display Unit Rev. E-16312P-321 – Installation Instructions for Honeywell CD-830 FMS ControlDisplay Unit Rev A-16312M-1182 – AFMSBeechcraft Corporation Rev. A-16312M-1181 – AFMS Bombardier, Inc (CL-600, CL-601) Rev. A-16312M-817 – AFMS Bombardier, I...	The aircraft must be previously modified with an approved HoneywellFlight Management System (FMS) with a Honeywell FMS model CD-810, CD-815or CD-820 CDUPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously insta...	22/02/2023	Active	10066443
10066444	AMETEK AMERON, LLC D/ B/A/ MASS SYST	REV. 1		SEE EASA APPROVED MODEL LIST	EASA Approval of FAA-PMA (Part Manufacturing Approval) approved,Reservoir Assembly – Door Emergency Power P/N 40400-2.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA PMA No. PQ1432NM Supplement No. 1, dated 27 July 2010and amendedon 26 December 2012;- Technical documentation asper the Approved Model List (AML) for theEASA STC 10066444;or later revisions of the above listed document(s) approved on behalf ofEASA in accordance with the Technical Implementat...	Additional Limitations and Conditions may be listed on AML for the EASASTC 10066444.	11/09/2018	Active	10066444
10066445	STG AEROSPACE GERMANY GmbH	REV. 1		A321-231, A321-232 A321-211, A321-212, A321-213 A321-211/-212/-213/-231/-232 A321-111, A321-112, A321-131 A321-111/-112/-131 A320-231, A320-232, A320-233 A320-231/-232/-233 A320-214, A320-215, A320-216 A320-211, A320-212 A320-211/-212/-214/-215/-216 A319-131, A319-132, A319-133 A319-131/-132/-133 A319-113, A319-114, A319-115 A319-111, A319-112 A319-111/-112/-113/-114/-115 A318-121, A318-122 A318-111, A318-112 A318-111/-112/-121/-122	AIRBUS LITEMOOD® CABIN LIGHTING UPGRADEReplacement of the Airbus Single Aisle fluorescent ceiling, window,entry and lavatory lighting with new STG Aerospace Airbus LiTeMood® LEDLighting.Revision 1: Transfer of STC holder from STG AerospaceLimited to STGAerospace GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List SG-1024-MDL-01 Rev. IR, dated 24 Jul 2018- Airworthiness Limitation Section of ICA SG-1024-ICA-01 Rev. IR dated24 Jul 2018- Cabin Crew Data Supplement SG-1024-CCD-01 Rev. IR, dated 24 July 2018or later revisions of the above listed document(s) approved/ acceptedunder the EASA syste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/02/2021	Active	10066445

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066465	SWS CERTIFICATION SERVICES Ltd.	REV.1	CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	SkyCouch Additional Occupancy	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 Amdt.5 for the affected area and CS26.1, CS26.50(d)(2), andCS26.120(a)(2)(i) at Amdt. 1The requirements for environmental protection and the associatedcertified noise...	Master Configuration Scheme, Ref. 3166-MCS-01 Issue 2or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	- Skycouch can only be used as a sleeping or an accommodation areaduring in-flight conditions, as detailed in SWS Certification ServicesLtd Design Report 3166-DR-01.- The following STCs are considered prerequisites for some of theinstallations: STC 10049763 (for 787-9 Code 1 LOPA installation), STC1...	20/08/2018	Active	10066465
10066467	LEE AEROSPACE, INC.		FAA STC ST01862WI	DHC-8-301/-311/-315/-401/-402 DHC-8-102/-103/-106/-201/-202	DHC-8 Window Assembly Side Canopy (RH) Replacement Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master data List Doc. No. LAI-MDL-102, Rev C, dated 19 January 2018or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/11/2019	Active	10066467
10066469	BHE & ASSOCIATES, LTD.	REV. 2	FAA STC ST11216DS	SEE FAA APPROVED MODEL LIST SEE FAA AML	Installation of automatic dependent surveillance-broadcast (ADS-B) outon Part 25 aircraft.Rev. 2: Change of Address	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Data List 584-00-0001, Revision IR, dated 29 June 2018 or laterFAA approved revision.	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is only valid for those aircraft w...	08/08/2025	Active	10066469
10066473	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	737-400	Palletized Aerial Dispensing of Liquids Tanker Conversion Program	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:Compliance has been demonstrated to CS-25 at Amendment 14 except for:- Electrical Wiring Interconnection System complies wi...	EASA Approved:WPA Airplane Flight Manual Supplement ref. WPA-5300-AFMS-14 Revision C,dated 15 August 2018WPA Instructions for Continued Airworthiness ref. WPA-5300-ICA-14Revision D, dated 12 May 2018EASA Accepted:WPA Master Data List WPA-5300-MDL-14 Revision A, dated 12 May 2018or later revisions of...	This STC can only be installed on a Boeing 737-400 series airplanemodified in accordance with AeronauticalEngineers, Inc. FAA STC ST01827LA (validated by EASA under STC ref.10015732 Rev 4 or later revision), andVentura Aerospace Inc. cargobarrier FAA STC ST01806 (validated by EASAunder STC ref. EAS...	20/12/2019	Active	10066473
10066482	LUFTHANSA TECHNIK AG			A319-131, A319-132, A319-133 A319-114, A319-115 A319-111, A319-112, A319-113	A319 Cargo Access HatchInstallation of new maintenance access hatch at C61-C62 from cabin toaft bulk cargo compartment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- SC H-01 Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS;- the following paragraph(s) at a later amendment: CS 25.869 Amdt. 4.The requirements for env...	- Master Document List P3-AA-E01-MDL-0001 issue A dated 16/08/2018;- Instruction for Continued Airworthiness (ICA) ALS P3-AAE01-ICA-0001issue A dated 16/08/2018;or later revisionsof the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/08/2018	Active	10066482
10066512	JET AVIATION AG	REV. 1		767-300	KA Band Antenna Installation,,Three different configurations are intended to be covered by thisapproval:- Configuration1: KA Band Structural ProvisionsConfiguration 1 consists ofthe installation of the structuralprovisions which are the dorsal radome, radome fairing and antennamounting plate pluss...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:,,CRI C-101: Structural Certification Criteria forLarge AntennaInstallationsCRI C-102: Vibration/ buffeting compliance criteria for large externalantenna installation,,Th...	For configuration 1:JBSL-M-00775AFM-01 issue 1JBSL-M-00775ICA-01 issue 1For configuration 2:JBSL-M-00776AFM-01 issue 1JBSL-M-00776ICA-01 issue 1For configuration 3: documents fromconfiguration 1 and 2.,,or later revisions of the above listed documents approved by EASA.,,	Configuration 2 may be installed with the structural provisions definedin Configuration 1 or any other EASA approved structural provision (seeJBSL-M-00776ANA-01 issue 1) ,,Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any o...	28/08/2018	Active	10066512

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066515	JORMAC AEROSPACE, INC.		FAA STC ST02445AT	777-200 737-700/-800/-900/-900ER	Installation of External Door, Access Panel and Window Security Locks	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Jormac Aerospace Master Drawing List JMER-843, Revision AC, dated 16July 2015 or later FAA approved revision.2. Airplane Flight Manual Supplement, JMER-847, Revision L, dated 19February 2016, or later FAA approved revision.3. Instructions for Continued Airworthiness, JMER-885, Revision J, dated19...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/08/2018	Active	10066515
10066565	P3 ENGINEERING GMBH			A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-223, A330-243 A330-202, A330-203	P3 Engineering GmbH EON 100050, Rockwell Collins Tailwind TW560 TVSystem RemovalThis modification de-installs the system components and thefuselage-mounted radome and antenna located in between frames C37 andC37.4.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	P3 Engineering GmbH Instructions for Continuing Airworthiness ref. ICAP3-AAN01-ICA-0001 (Issue A) documentor later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Aeroplanes modified by this STC must be maintained in accordance with P3Engineering GmbH Instructions for Continuing Airworthiness ref. ICAP3-AAN01-ICA-0001 document.	24/08/2018	Active	10066565
10066571	LUFTHANSA TECHNIK AG			A321-231	VIP Cabin Completion	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25.603, 25.788 (b),S25.1(b), S25.10(a)(c), S25.30 (a)(b), S25.50(a) at Amendment 19The requirements for environmental pro...	-Supplemental Type Definition Document (STDD) Ref. STDD00-17/01M Issue01 Revision 00-Compliance Checklist (CCL) Ref. CRL00-17/01M Issue 1 Revision 00 andCRL00-18/01M Issue 01 Revision 00-Airplane Flight Manual Supplement (AFM-S) Ref. A-00-17/22-AFM Issue 04Revision 00-Instructions for Continued Airw...	- The aircraft is certified for "private operation" only.- In the cabin configurations “empty space for one or for two patienttransport unit(s)” the opposite seats (left hand sideof cabin) of theempty space must not be occupied.- As defined in Section 4 (ALS) of the Instructions for ContinuedAirwor...	24/08/2018	Active	10066571
10066631	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	767-300	INTRODUCTION OF IRIDIUM SATCOM	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MASTER DOCUMENT LIST: S21.MDL-1297 ISSUE 2;AIRCRAFT FLIGHT MANUAL SUPPLEMENT: S21.FMS-0144 ISSUE 1;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The SATCOM system must not be used during take-off/landing or approach.The SATCOM system is approved for non-essential voice communicationsonly. It is not approved for Future Air Navigation System (FANS) or forLong Range Voice Communication with ATC.Prior to installation of this change/ repair it mus...	28/08/2018	Active	10066631
10066646	AVIANOR INC			A330-343	Cabin reconfiguration, seat installation and layout of passengeraccommodation (LOPA) approval	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Avianor Master Document list MDL16182002 Rev. B dated 1 March 2018;- Avianor Master Document list MDL16182702 Rev. NC dated 18 February2018;- Avianor Supplemental Instructionsfor Continued AirworthinessICA16182002 Rev. A dated 1 March2018;or later revisions of the above listed documents approv...	Limited to s/n 1098Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	29/08/2018	Active	10066646

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066657	AMAC AEROSPACE SWITZERLAND AG	REV. 1		747-8	JetWave KA-Band Antenna Installation / Installation of Honeywell KA-bandantenna mounted top fuselage. The installation includes the Ka FrequencyUnit (KRFU) installed on the antenna mounting plateRevision 1 of this STC: Correction of inspection Methods described inthe Instructions for Continued Airwo...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI C-105,Vibration/buffeting compliance criteria for large externalantenna installation.The requirements for environmental protection and the associatedcertified noise an...	For Configuration 1: · The change is defined with MasterData List MDL-B7472-1-5300,Revision D. · The aircraft shall be operated in accordance with Airplane FligthManual Supplement AFMS-B7472-1-5300, Revision A. · The aircraft shallbe maintained in accordance with Instructionsfor Continued A...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/04/2019	Active	10066657
10066675	SIRIUM AEROTECH S.L.			MYSTÈRE FALCON 900 (MF900)	F900 Transponder Upgrade for ADS-B activation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS Subpart D, Section 4The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged a...	Conversion Bulletin SA18-02S-CB Revision 2Test Plan SA18-02S-TP Revision 2AMM Supplement SA18-02S-AMMS Revision 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The EASA Approval is only applicable Airplanes FALCON 900B MSN 38, 73,74, 77 and 90.Before accomplishment of this modification transponder MST70B must beinstalled with ADS-B-NRA capabilities as per modification SIRIUMAEROTECH SA17-61M.	30/08/2018	Active	10066675
10066680	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T3	Additional Hoist Controller – Change AHUK/135/3090.This Change provides role equipment in the form of an additional hoistcontroller for use by an instructor during hoist operations training.The equipment consists of a control pendant with coiled cable andelectrical connector, which interfaces with t...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27.865 (b)(3) atamendment 4.The requirements for environmental protection and the associatedcertified noise and/ or emi...	- AFM Supplement AHUK/ 135-FMS-102, Initial Issue-Master Record Design Definition Document MRI/ 1353090-01, Issue Aor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	- EASA Major Change 10065363 Rev. 1 embodiment is a pre-condition.- Limited to helicopters with Helionix cockpit version.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairand any otherpreviously installed change and/ or repair will...	30/08/2018	Active	10066680
10066697	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST03539AT	757-200/ -300	Installation of a Thales Integrated Standby Flight Display inB757-200/-300 Series Aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Avionics Support Group, Inc. Master Data List 27252-MDL,Rev. IR,dated 14 November 2007, or later FAA approved revision.2. Airplane Flight Manual Supplement for Avionics Support Group27252-FMS dated 26 February<(>,<)> or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/08/2018	Active	10066697
10066717	ACC COLUMBIA Jet Service GmbH	REV. 3	EMZ 0112/669	MX-7-180, MX-7-235 M-6-235, M-7-235, MT-7-235	Installation of the GOMOLZIG Silencer System 606500 in the Mauleaircraft models M-6-235, M-7-235, MT-7-235, MX-7-180 and MX-7-235.This EASA STC is a major change to former STC (EMZ) No 0112/669, issuedby Luftfahrt-Bundesamt (Germany) on 14.09.1993.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: FAR 23 amendment 7 forall paragraphs listed in the certification plan.This certificate/ approval involves a change to thee...	- Master Drawing List MDRWL_2044124_rev0_20180515, dated 24.07.2018;- Master Document List MDOCL_2044124_rev0_20180515,dated 02.08.2018;- Installation Instruction II_2044124_rev0_20180515, Edition 24.07.2018;- Flight Manual Supplement SPOH_2044124_rev0_20180515, Edition24.07.2018;For modification k...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/01/2022	Active	10066717
10066725	LATITUDE TECHNOLOGIES CORPORATION			DHC-8-401/-402 DHC-8-301/-311/-314/-315 DHC-8-201/-202/ DHC-8-102/-103/-106	Latitude Antenna Installation (Structural Provisions)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The Change is defined with DECA Aviation Modification Summary MS11121,Revision 4Maintenance must be in accordance with DECA Aviation instruction forContinued Airworthiness ICA11121, Revision 4or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the...	This Supplemental Type Certificate covers only the structuralinstallation of the Antenna. Spearate aprpoval is requiredfor theelectrical and functional aspects of the Latitude Equipment installationPrior to installation of this change/repair it must be determined thatthe interrelationship between t...	03/09/2018	Active	10066725

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066726	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		DORNIER 228-212 DORNIER 228-202 DORNIER 228-201 DORNIER 228-200 DORNIER 228-101 DORNIER 228-100	Approval of Single / Dual Honeywell MST 70B Transponder system, EHS &ADS-B upgrade and approval of Single / Dual Rockwell Collins TDR-94DTransponder system, EHS & ADS-B upgrade, in accordance with ScandinavianAvionics modification 2111499-EO, Issue 2	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): CS-ACNS 2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged an...	- Modification in accordance with Scandinavian Avionics DesignEngineering Order 2111499-EO Issue 2, dated 24.06.2019- Operate in accordance with Scandinavian Avionics Design Flight ManualSupplement 2111499-AM A Issue 2< (>,<)> dated 08.05.2019 and 2111499-AM CIssue 4, dated 17.06.2019- Instructions f...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/06/2019	Active	10066726
10066729	LUFTHANSA TECHNIK AG	REV. 1	FAA STC ST09878AC	737-800	Installation of headliner hanger and panel system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST09878AC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. BizJet data list 1446000001 revision AR dated 1 June 2017 or laterFAA approved revision. 2. BizJet Instructions for Continued Airworthiness (ICA) R1182S0601 RevIR dated 19 September 2016 or later FAA accepted revision.	1. It must be demonstrated by test or combination of test and analysisthat all occupants can be evacuated from the airplane in a time periodnot exceeding 45 seconds under the conditions specified in appendix J ofpart 25 amendment 25-72.2. Operations involving the carriage of person or property forco...	04/04/2019	Active	10066729
10066731	S-TEC CORPORATION	REV. 2	FAA STC SA09745DS	T210R, P210N, P210R T210M, 210N, T210N, 210R T210K, 210L, T210L, 210M 210H, T210H, 210J, T210J, 210K 210E, 210F, T210F, 210G, T210G 210, 210A, 210B, 210C, 210D	Installation of an S-TEC 01326 Digital Flight Control System (DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Data List No. ST-962-MDL-0001, Revision E, dated 31 October 2018or later FAA approved revision.Airplane Flight Manual Supplement, ST-962-AFMS-0001, Rev. A, dated 1November 2018 or later FAA approved revision.Instructions for Continued Airworthiness, ST-962-ICA-0001, Revision A,dated 31 Octobe...	Also eligible on models 210L, T210L, 210M, T210M, 210N, T210N, P210Nwhen modified with LBA STC 0779/625b (FAA STC SA1003NE); and model P210Nwhen modified with EASA STC 10060053.Prior to installation of this design change it must be determined thatthe interrelationship between this design change andp...	14/12/2018	Active	10066731
10066732	S-TEC CORPORATION	REV. 1	FAA STC SA09744DS	N35/ P35/ S35/H35/ J35/ K35 M35/ V35/ V35A/ V35B 36/ A36/ A36TC/ B36TC	Installation of an S-TEC 01326 Digital Flight Control System (DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Data List No. ST-959-MDL-0001, Revision A, dated 06 April 2018or later FAA approved revision.2. Airplane Flight Manual Supplement, ST-959-AFMS-0001, Revision-, dated10 April 2018 or later FAA approved revision.3. Instructions forContinued Airworthiness, ST-959-ICA-0001, Revision-,dated 29...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/09/2018	Active	10066732
10066734	SOCIETE AIR FRANCE S.A.	REV. 1		737-800	Boeing 737-800 T-PED (Transmitting Personal Electronic Device) tolerancedemonstration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Société Air France Airplane Flight Manual SupplementAFMS-B737-18-001-001 original issue;Société Air France Instructionsfor Continued Airworthiness of AircraftT-PED Tolerance ICA-B737-18-001-001 original issue;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system....	The modification consists in demonstrating that B737-800 aircraft isT-PED tolerant to mobile phone and Wi-Fi frequencies. Transmitting PEDscan be used in passenger cabin in transmitting mode during all phases offlight but restricted to connections as per cellular and/or wirelesstechnologies. The use...	05/09/2018	Active	10066734

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066758	LUFTHANSA TECHNIK AG			MD-11F	GNSSU Replacement on MD-11.The modification is the replacement of the existing Global PositioningSystem (GPS) by a GPS using Satellite-based Augmentation (GPS/SBAS).TheGlobal Navigation Satellite Sensor Units (GNSSUs) and the passive GPSantennae are replaced by GNSSUs with Satellite-based Augmentati...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Design Document STDD34-18/03M Issue/ Rev 1/0;- Compliance Check List CCL34-18/03M Issue/Rev 2/0;or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/09/2018	Active	10066758
10066792	SIDDHIS AERONAUTICAL DESIGNSCORPORATION	REV. 2	TCCA SA98-92 ISSUE 7	CL-600-2B19 (RJ SERIES 440) CL-600-2B19 (RJ SERIES 100) CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Installation of fin-mounted radome and SatCom / DBS antenna (Structuralprovisions only).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The change installation must be performed in accordance with DECAAviation Engineering Limited modification summary document numberMS16046, Revision 7, dated 15 January 2019.Operation must be performed in accordance with DECA Aviation EngineeringLimited flight manual supplement number FMS16046, Revi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/10/2019	Active	10066792
10066800	JETTECH, L.L.C.		FAA STC ST02432LA	501/551	Installation of Dual Garmin GTN 6XX/7XX Series Global Navigation Systemwith Structural Antenna and WAAS approval; Garmin GNA 35 Audio Panel;Dual Garmin GTX 33 Mode S Transponders;Garmin GWX 70 Weather Radar; andGarmin GDL-88 ADS-B Transceiver on airplane models with a SPZ-500AFCS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	JETTECH LLC Master Document List, Drawing No. JETTECH-WAAS-0001,Revision "B", dated 30 August 2012, or later FAA approved revision.Airplane Flight Manual Supplement, Document No. JETTECH-WAAS-0102,Revision "B", dated 10 August 2012, or later FAA approved revision.The Instructions for Continued Airwo...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Display of StormScopc® is not approved under thi...	07/09/2018	Active	10066800
10066802	JETTECH, L.L.C.		FAA STC SA01755WI	525, 525A, 525B	Installation of GPS LEFT/RIGHT Deviation Converter with a single or dualGTN 6XX/7XX GPS WAAS receiver to allow the installed AFCS to be WAAS LPVcapable.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	. JETTECH Master Document List No, JET-WAAS-001, Revision IR, dated 21April 2014 or No. JET-WAAS-0001, Revision A, dated 17 November 2017, orlater FAA approved revision; and2. JETTECH Airplane Flight Manual Supplement, No. JET-WAAS-0002,Revision IR, dated 20 June 2014, or No. JET-WAAS-0102, Revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/09/2018	Active	10066802
10066827	PPG AEROSPACE		FAA STC ST02598LA	400/ 400A	Installation of PPG Aerospace main cockpit windshields P/N's 196700-01and 196700-02.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. PPG Aerospace Transparencies Master Drawing List 196700,Rev. N/C,dated 2 May 2016 or later FAA approved revision.2.PPG Aerospace Instructions for Continued Airworthiness, PPGdocumentNo. ER 14-094, Revision N/C, dated 15 February 2016, or other FAAaccepted maintenance data.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/09/2018	Active	10066827

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066828	FLINT AERO, INC.		FAA STC SA8036NM	185E/ A185E/ A185F 185/ 185A/ 185B/ 185C/ 185D	Installation of wing tip fuel tank 28/30 U.S. gallon; increase wing spanapproximate four feet and area to 185 square feet and increase grossweight to 3,600 lbs. for landplanes.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Flint Master Drawing List (MDL) FA 185, Revision L, dated 6September1995, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The Limitations and conditions of aircraft speci...	10/09/2018	Active	10066828
10066845	EIRTECH AVIATION SERVICES LIMITED			737-900/-900ER 737-8/-800 737-600/-700	B737 PM-CPDLC ACARS CMU II UPGRADEInstallation of HoneywellACARS Mark II CMU+ and associated wiringchanges. The targetaircraft for this STC are currently provisioned forACARSCMU's and will be upgraded to modify the wiring configuration toenable installation of the Mark II Honeywell 965-0758-006 AC...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-04 Flight Recorders and Data Link Recordingthe following paragraph(s) at a later amendment: CS-ACNS Initial IssueThe requirements for environme...	MASTER DOCUMENT LIST, MDL/1175-001 ISSUE 4or later revisions of the above listed document (s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/09/2018	Active	10066845
10066848	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Introduction of ARINC 791 SATCOM System.Introduction of theSATCOM components of an ARINC 791 satellitecommunications system in an existing external adapter plate and radome.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master document list S21.MDL-1401<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	A radome and VSAT adapter provisions must be installed prior to orcurrently with this design change. The provisions must be compatible andhave been previously substantiated to embody a VSAT Antenna with thefollowing characteristics:a. Weight - 60Kgb. Swept Diameter - 980mmc. Height – 280mmPrior to i...	12/09/2018	Active	10066848
10066864	EIRTECH AVIATION SERVICES LIMITED			777-300	B777 Removal of Economy Class Seats.This Change removes allexisting Economy Class passenger seats in themain cabin of the aircraft without replacement to achieve a First ClassandBusiness Class only configuration for limited ferry flights. Allother elements in the passenger cabin will remain as is....	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 21 isthe Certification Basis for this project.The requirements for environmental protection and the associ...	Master Document List MDL/1214-001 Issue 3;Flight Manual Supplement FMS/1214-001 Issue 2;or later revisions of the abovelisted document (s) approved/ acceptedunder the EASA system.	Operation of the aircraft is restricted to non-revenue ferry flightswith flight crew and supernumerary crew only. The carriage ofpassengers is not permitted.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	13/09/2018	Active	10066864
10066867	S4A SOLUTIONS FOR AVIATION, S.L			PC-12/45	HF radio installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Operation in accordance with document: No. PC1201-HDK01, SuplementoManual Vuelo, Ed 2, dated 04/09/2018-Installed and maintenance in accordance with document: No.PC1201-HDK-02 Suplemento Manual Manenimiento, Ed 6, dated 11/06/2018or laterrevisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/09/2018	Active	10066867
10066894	ADVANCED AEROSPACE DEVELOPMENTS GMB			AS 350 D AS 350 B, AS 350 B1 AS 350 BA, AS 350 BB AS 350 B2, AS 350 B3	External Mirror System (EMS) consisting of two mirrors withelectricalcontrol and de-fog.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27 Amdt 4 for theaffected parts.The requirements for environmental protection and the associatedcertified noise and/ or...	Master Document List AAD-MDL-01EMS-001 Rev 04, dated 10 September 2018;Aircraft Flight Manual Supplement AAD-FMS-01EMS-001 Rev 01, Dated 19June 2018;Installation Manual and Instruction for Continued AirworthinessAAD-ICA-01EMS Rev 01, dated27 June 2018;or later revisions of the above listed document...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/09/2018	Active	10066894

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066912	SOCIETE AIR FRANCE S.A.			A319-115(CJ)	CPDLC (Controller Pilot Data Link Communications) System Activation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.23, 25.561,25.581, 25.1301<(>,<)> 25.1307(b), 25.1309, 25.1322<(>,<)> 25.1351(a),25.1353(a) and (b), 25.1357, 25X136...	Societe Air France S.A. Airplane Flight Manual SupplementAFMS-A320-15-009-001;Societe Air France S.A. Flight Crew Manual SupplementFCOMS-A320-15-009-001;Societe Air France S.A. AFSB-A320-15-009-46-001 (CPDLC systemactivation)<(>,<)> AFSB-A320-15-008-46-001 (minor change including CPDLCprovisioning)c...	This STC does not, by itself, constitute an operational approval wheresuch an approval is required.The following functions are not certified: - Pushback clearance request<(>,<)>- Oceanic clearance request<(>,<)> - Taxi clearance request<(>,<)> - TWIP (Terminal Weather Information for Pilots) cl...	18/09/2018	Active	10066912
10066922	AMAC AEROSPACE SWITZERLAND AG			A319-133	Certification for Commercial Operation / This changes includesinstructions to alter the aircraft to allow operation in Commercial AirTransport. If desired, this change also includes instructions to alterthe aircraft back to its initial configuration for sole private use.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Appendix S to CS-25Amendment 19.The requirements for environmental protection and the associatedcertified noise and/ or em...	- The change is defined in MDL-CF11-2500, Master Data List,Revision B;- The aircraft shall be operated in accordance with AFMS-CF11-2500,Airplane Flight Manual Supplement, Revision A;- Additional instructions for continued airworthiness are defined inAMMS-CF, Chapter 5 Time Limits and Maintenance C...	FOCA approved STC Z25-20-72 and STC 10039943 has to be installed priorto or in conjunction with the modifications of this STC.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair...	19/09/2018	Active	10066922
10066948	NEXTANT AEROSPACE, L.L.C.		FAA ST04282CH	EMB-145LR, EMB-145MP EMB-145EP, EMB-145ER EMB-135LR, EMB-145 EMB-135BJ, EMB-135ER	Honeywell CD-830 FMS CDU Replacement.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 Initial Issue andCS 25.1301 Amdt 2, CS 25.1309Amdt 3, CS25.1371 Amdt 17.The requirements for environmental protectio...	- Master Data List Doc. No. AS0012-MDL0-0100 Rev. A dated 15 January2018;- Airplane Flight Manual Supplement Doc. No. AS0012-AFMS-0100 Rev. IRdated 9 February 2018;- Instructionsfor Continued Airworthiness Doc. No. AS0012-ICA-0100Rev.B dated 9 January 2018;or later revisions of the above listed do...	- FAA approved Airplane Flight Manual Supplement, Nextant Aerospace, LLCDoc. No. AS0012-AFMS-0100, Revision IR, approved February 9, 2018, orlater FAA approved revision, is required on board the modified aircraft- This STC is applicable only to aircraft with Honeywell FMZ-200navigation system previo...	21/09/2018	Active	10066948
10066950	Q.C.M. DESIGN GmbH			560	Installation of ADS-B Out and FMS Upgrade with LPV Approachcapability.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-ACNSInitial Issue 19.12.2013.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchan...	Installation in accordance with QCM Design Organisation modification refC560-QCM34-001 and Engineering Bulletin EB-C560-QCM34-001, Rev 0, dated15.07.2018;Operation in accordance with QCM Design Organisation Aircraft FlightManual Supplements:-C560-QCM34-001-M1-AFM – FMS SBAS, Rev 0, dated 23-Jul-2018...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/09/2018	Active	10066950
10066960	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED		CAA UK RESPONSIBILITY	MBB-BK117 C-2, MBB-BK117 D-2	Investigation to demonstrate that MBB-BK117 D-2 and MBB BK-117 C-2 arePED's and T-PED's tolerant.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-29 amdt.4; §§ 29.1,29.1309, 29.1501, 29.1525, 19.1581, 29.1583, 29.1585, A29.1, A29.2,A29.3, A29.4.The requirements for...	Babcock FMS 161-003 iss. 2 for MBB-BK117 C-2 and MBB-BK117 D-2Babcock Design Report 161-002 iss. 3Babcock Compliance Checklist 161-004 iss.2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	05/10/2018	Active	10066960

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10066962	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	212	Installation of a Garmin GTN650H.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-ACNS Initial issuefor the affected requirements.The requirements for environmental protection and the associatedcertifi...	Doc. No PAL-FMS-B212-139 FLIGHT MANUAL SUPPLEMENT Revision A<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/09/2018	Active	10066962
10066978	BOEING IRELAND LIMITED	REV. 2		777-300ER	777-300ER End of Lease Zero-PAX Cabin Reconfiguration.Rev. 1: ICA documentation provided, limitation removed.Rev. 2: Transfer to new certificate holder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Continental DataGraphics Ltd Aircraft Flight Manual Supplement No.B10253-00AFM Revision 1<(>,<)>- Continental DataGraphics Ltd Certification Programme No. B10253-00CPRevision 2< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/11/2020	Active	10066978
10066987	VT DRB AVIATION CONSULTANTS	REV. 1	FAA ST11214DS	SEE EASA APPROVED MODEL LIST	Installation of Dukane underwater acoustic beacon.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 Non-rechargeable Lithium BatteryInstallations.The requirements for environmental protection and the associatedcertified noise and/ or emissi...	FAA Approved Model List for Installation of a DK180 Dukane SEACOMunderwater acoustic beacon on Part 25 aircraft Revision D dated 03December 2018<(>,<) >or later revisions of the above listed documents approved by EASA inaccordance with EASAED Decision 2004/04/CF (or subsequent revisions ofthis decis...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/04/2019	Active	10066987
10067004	JAMCO AMERICA, INC.		FAA STC ST01880SE	777-300	Installation of an interior reconfiguration on Boeing Model777-300series aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	- Jamco America, Inc. Master Drawing List (MDL) 1343-1, Revision J,dated 25 October 2013, or later Federal Aviation Administration (FAA) approved revision.- Supplemental Instructions for Continued Airworthiness (ICA) DocumentNumber ICA1343-1, Revision K, dated 10 February 2012, or later FAAapproved r...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.EASA STC 10060430, Installation of an inflight e...	26/09/2018	Active	10067004
10067014	DELTA ENGINEERING CORPORATION		FAA ST03177NY	EMB-145MP, EMB-135ER EMB-145EP, EMB-145LR EMB-145, EMB-145ER EMB-135LR, EMB-135BJ	Installation of ADS-B with FreeFlight GPS.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.831, 25.853,25.869, 25.981, 25.1353, 25.1431, 25.1583, 25.1585 at Amdt 4 plus CSACNS.D.ADSB.001, ACNS.D.ADSB.010, AC...	- Instructions for Continued Airworthiness ref. doc. 0766-08754-2360,Rev. C, dated 17th January 2018;- Master Data Listref. doc. 0166-08681-2360, Rev. E, dated 23rd July2018;- Airplane Flight Manual Supplement ref. doc. 0666-08682-2360, Rev. C,dated 6th July 2018;- Electrical Wiring Interconnection...	- For configuration 1: Not covered by EASA validation- For configuration 2: Honeywell Service Bulletins 7013270-34-0020,7510700-23-32, 7510700-23-0053, 7510784-23-0016 and 7517400-23-0024 arerequired with this STC.- For configuration 3: configuration 2 is required and previouslyinstalled Universal A...	27/09/2018	Active	10067014

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067038	ROCKWELL COLLINS, Inc.	REV. 1	FAA ST02522SE	737-900ER 737-900 737-800 737-700	HGS 6000 on Boeing 737-NGInstallation of HGS Model 6000 on Boeing 737-NG series of aircraft. HGS6000 is a re-host of the HGS Model 4000 approved for installation on theBoeing 737-NG aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: EASA CS 25 Amdt 12,paragraphs 25.303; 25.305 (a)(b)(c); 25.307 (a)(d); 25.561 (b)(c)(d);25.562 (a); 25.581 (a)(b)(c); 25.6...	- Master Drawing List 946-0EU4-001 Rev. -, dated 26 September 2016- Instruction for Continued Airworthiness 946-0EU5-001, Rev. -, dated 02February 2017- Airplane Flight Manual Supplement 9701-1306 Rev. A, dated 24 January2017- Airplane Flight Manual Supplement 9701-1307 Rev. A, dated 24 January2017o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/10/2018	Active	10067038
10067048	CHIPPEWA AEROSPACE, Inc.		FAA STC ST04190AT	EMB-145LR, EMB-145M EMB-145ER, EMB-145EU EMB-145, EMB-145EP EMB-135LR EMB-135BJ, EMB-135ER	Installation of ADS-B Out	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04190AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Chippewa Aerospace Master Drawing List (MDL) No. 145-3452-01-0001,Rev. 2, dated 1 May 2016, or later FAA approved revision.2. Airplane Flight Manual Supplement for ADS-B Out inthe EmbraerEMB-135() and EMB-145() Series Aircraft, Chippewa Aerospace Document No. 145-3452-01-1012, Rev. IR, dated 6 Ja...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/10/2018	Active	10067048
10067052	DART AEROSPACE USA, Inc.		FAA STC SR02609SE	EC 130 T2 EC 130 B4	Installation of Cable Cutters	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Installation Instructions IIN-D130-1046, Revision B, dated 26 June2018, or later FAA approved revision<(>,<)>2. Master Document List MDL-D130-1046, Revision B, dated 6 July 2018, orlater FAA-approved revision<(>,<)>3. Instructions for Continued Airworthiness (ICA) ICA-D130-1046,Revision 0, dated...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/10/2018	Active	10067052
10067056	Q.C.M. DESIGN GmbH			BD-700-1A10	Honeywell CNX-900 WiFi Installation.The Honeywell CNX-900 router will be installed within the pressurizedcabin area andinterfaced with both the Ku band system and Satcomsystem.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01, SECURITY PROTECTION OF AIRCRAFT SYSTEMSAND NETWORKS.The requirements for environmental protection and the associatedcertified noise and/ or...	Change Definition: Chapter 3.4 of Certification Program, Doc. No.CP-BBD7-QCM23-004;Airplane Flight Manual Supplement, Doc. No. BBD7-QCM23-004-M1-AFM,Initial Issue;Instructions forContinued Airworthiness, Doc. No.BBD7-QCM23-004-M1-ICA, Initial Issue;Maintenance Manual Supplement, Doc. No. BBD7-QCM23...	Aircraft Equipped with the Global Vision Flight Deck (GVFD)are excludedfrom this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon th...	02/10/2018	Active	10067056
10067059	PMV ENGINEERING			A321-272NX A321-253N/-271N/-272N/-251NX A321-252NX/-253NX/-271NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-252N/-271N A320-231/-232/-233/-251N A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	CVR/FDR ULB 90 days on A320 family.The aim of this modification is to replace the existing 30 daysUnderwater Locator Beacon (ULB) installed on Cockpit Voice Recorder(CVR) and Flight Data Recorder (FDR) by new 90 days ULB.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Special Condition F-0318-002 – Non-rechargeableLithium Batteries installation.- The following paragraph(s) at a later amendment: CS25 amdt 18: 25.6...	- Master Document List AVI-01410-MDL-R02, dated 19 SEP 2018;- Instructions for Continued Airworthiness AVI-01410-ICA-R01, dated 19SEP 2018;- Instructions for Continued Airworthiness AVI-01420-ICA-R01, dated 24SEP 2018;or later revisions ofthe above listed documents approved/ acceptedunder the EASA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/10/2018	Active	10067059

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067064	GAMA AVIATION (ENGINEERING) LIMITED		CAA UK RESPONSIBILITY	C90A, C90GT, C90GTI	Antenna Provision for Microwave D/L System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	GAEL-1563MDL-01, Issue 1, Dated 20th September 2018<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/10/2018	Active	10067064
10067065	AVIONITEC AG			PA-46-350P	Installation GPS WAAS Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installed and Maintained in accordance with the documents listed inMaster Document List titled: Master Document List 8934-017, Revision 0,Dated 13th September 2018.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/10/2018	Active	10067065
10067072	AIRBUS HELICOPTERS, Inc.		FAA STC SR09130RC-D	AS 350 B3 AS 350 B2	Installation of a Lead Acid Battery RG350 at the Aircraft StandardBattery Location	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing List 350A82-1753, initial release, dated 18 October2000 orlater FAA approved revision(s).	The modification ref. AMS 07-2769 is a pre-requisite for the embodimentof this Supplemental Type Certificate (STC) on AS 350 B2.Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repa...	15/01/2019	Active	10067072
10067076	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03602NY	FALCON 900EX (F900EX)	Installation of a Meggitt iSFD Functional Upgrade (DisplaysILS andMagnetic Heading) in Dassault Aviation Falcon 900EX Aircraft with EASyAvionics installed	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03602NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Dassault Aircraft Services Master Data List F9XW-D0083-005 Rev IR,dated 31 May 2018, or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA) F9XW-D0083-155, RevIR, dated 16 May 2018<(>,<)> or later FAA accepted revision.3. Airplane Flight Manual Supplement (AFMS) F9XW-D00...	This alteration requires the following prerequisites:TI-F900EX-M5776-M5920-M or equivalent mod, MKB Part Number 7028560-921and MRC Part Number 7517959-904.Prior to installation ofthis change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously in...	05/10/2018	Active	10067076
10067083	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03595NY	SEE FAA APPROVED MODEL LIST	Installation of Honeywell Laseref IV Upgrade	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03595NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Dassault Aircraft Services Master Data List, AML25-D0074-005,Revision A, dated 1 September 2017 or later FAA approved revisions.2. Dassault Aircraft Services Instructions for Continued Airworthiness,AML25-D0074-155, Revision IR<(>,<)> dated 28 July 2017 or later FAAapproved revisions.	Prior EASA Approved installation of Honeywell Laseref II, III and/or IVIRS as specified by AML No. AML25-D0074-002 General Note 3 is aprerequisite to this STC.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviousl...	05/10/2018	Active	10067083
10067084	AIRLIFT A/S			AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1	The mod DO-355-25-101 introduces the “Removable External Mount” on AS355 series helicopters.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	CCPL-355-25-101 Configuration Control Part List, rev 0, dated 01 June2018;FMS-355-25-101-01 Flight Manual Supplement, rev 04, dated October 2018;ICA-355-25-101-01 Instructions forContinued Airworthiness, rev 0, dated01 November 2016;or later revisions of the above listed document(s) approved/accept...	The external load installation and the task specialist restraint systemare not part of this STC and must be subject of separate approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and...	05/10/2018	Active	10067084

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067100	L2 AVIATION SOLUTIONS, LLC		FAA STC ST00750DE	777-200/777-300/777-300 ER	Installation of an Iridium Communication System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List 2315-B70-MDL, REV K, dated 11 April 2017 or laterFAA approved revision. 2. Flight Manual Supplement (AFMS) 2315-B70-AFM, REV IR, dated 31January 2017, or later FAA approved revisions.3. Instructions for Continued Airworthiness (ICA) 2315-B70-ICA, REV H,dated 31 March 2017, or l...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/10/2018	Active	10067100
10067113	W-MOTOR SERVICE, s.r.o.	REV. 1		M 337, M 337A, M 337AK M 332, M 332A, M 137A, M 137AZ M 332, M 332A M 137A, M 137AZ	M137, M332, M337 Engines Overhaul.The alternative procedurefor M137, M332 and M337 piston enginesovehauls is defined with the WMS-OS –F1-13 procedure (Definitiondocument).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI E-01.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product...	M137/M337/M332 Piston Engine OH instruction No.WMS-OS-F1-13, dated March01, 2013<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	26/09/2024	Active	10067113
10067114	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A, 525B	Installation of dual Garmin GA35 GPS/ WAAS antennas.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with: Instructions for installation,ASR-2018-033-10-IFI-03;Instructions for continued airworthiness: ASR-2018-033-11-ICA-03;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/10/2018	Active	10067114
10067117	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 350 B3	The change AHUK/350/3143 introduces an Air Data Boom to be used asindependent source of air data for special training need.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MRI/3503143-01 (issue B) Master Record Design definitionAHUK/350-FMS-101 (issue 0) Flight Manual SupplementICA/ 3503143-01 (issue B) Maintenance / Continued AirworthinessInstructionsor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Pre-requisite for this STC is the external mount EASA STC 10016801subject to AFSP-005 Flight Manual Supplement, dated 13th July 2016.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or...	12/10/2018	Active	10067117
10067132	BELL HELICOPTER TEXTRON, Inc.		FAA SR11237DS	505	Installation of Tinted Windows.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11237DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Drawing List, Report No. AA-17099, Revision A, dated26 June2018, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/10/2018	Active	10067132
10067133	BELL HELICOPTER TEXTRON, Inc.		FAA SR09618RC	505	Installation of Headliner.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR09618RC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Drawing List, Report No. AA-17116, Revision D, dated31 July2018, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/10/2018	Active	10067133

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067159	LUFTHANSA TECHNIK AG	REV. 1		MD-11F	Activation of ADS-B and ELS/EHS upgrade.The change consistsin activating Automatic Dependent Surveillance – Broadcast Out (ADS-B Out) and to upgrade the Mode S ElementarySurveillance (ELS) and Enhanced Surveillance (EHS) System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Design Document: Doc. no. STDD34-18/05M Issue/Rev 1/2;Manuals: - Instruction for Continued Airworthiness: Doc. no. A-00-18/61-ICAIssue/Rev 1/0; - Flight CrewInformation: Doc. no. A-00-18/61-FCI Issue/Rev 0/1; - Master Minimum Equipment List: Doc. no. A-00-18/61-MMEL Issue/ Re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/10/2018	Active	10067159
10067160	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		G 120TP-A	J7689 – Flight Test Instrumentation Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation, Operation and Maintenance in accordance with documentscontrolled by Master Document Lists: Document No. Master Data List,GVH-7689-01-MDL-01<(>,<)> Issue 4, Dated 01 October 2018<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The approval holder shall fulfill the obligations of Part 21, Point21A.109.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthi...	26/03/2021	Active	10067160
10067166	NORTHWEST AEROSPACE TECHNOLOGIESI NC.			747-400	Cabin Interior Reconfiguration and IFE System Installation on BritishAirways Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0622-D90, Revision -, dated 08 October 2018.Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0622-D70, Revision A, dated 10September 2018.or later revisions of the above listed doc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/10/2018	Active	10067166
10067171	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 1		A320-232	Cabin Densification of British Airways Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Summary, Northwest Aerospace Technologies, Inc. documentNo. N0603-D90, Revision A, dated 10 January 2019;Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document No. N0603-D70, Revision -, dated 27 July2018;or later revisions of the above listed document...	The following Minor Change Approved Service Bulletins shallbeconcurrently installed: British Airways SB A320-25-0059; Airbus SBA320-53-1368, Airbus SB A320-25-1BGW, Airbus SB A320-53-1369 and AirbusSB A320-25-1BH3.Prior to installation ofthis change/repair it must be determined thatthe interrelati...	11/01/2019	Active	10067171
10067190	LEE AEROSPACE, INC.		FAA STC SA01867WI	SEE FAA AML	CoolView Compartment Side and Storm Windows Installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	See attached AML No. SA01867WI for required data.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.King Air Models B200GT, B200GT and, and 300 seri...	12/10/2018	Active	10067190

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067192	AMAC AEROSPACE SWITZERLAND AG			737-700	Remove Limitation for required cabin crew	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The Change is defined through AMAC Master Data List MDL-FE08-2500, Rev.BThe aircraft shall be operated in accordance with AMAC Airplane FlightManual Supplement AFMS-FE08-2500, Revision Aor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Initial Issue of EASA Supplemental Type Certificate 10061345 or laterapproved revision must be accomplished prior to orin conjunciton withthis modification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	12/10/2018	Active	10067192
10067200	VORTEX CONTROL TECHNOLOGIES LLC		FAA STC ST03744NY	737-700	Installation of Vortex Control Technologies Finlets on Boeing 737-700aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03744NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. ALOFT AeroArchitects Configuration Listing No. 7874-53-CFGM-001,revision C, dated 13 July 2018, or later FAA approved revisions.2. Master Data List No. 7874-0001-MDL<(>,<)> Revision IR, dated 11 May2018, or later FAA approved revisions.3. Instructions for Continued Airworthiness (ICA), No. TM-787...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/10/2018	Active	10067200
10067204	LUFTHANSA TECHNIK AG			A321-272N/-272NX A321-271N/-271NX A321-253N/-253NX A321-252N/-252NX A321-251N/-251NX A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-251N/-252N/-271N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of LF-ULDInstallation of Low Frequency Underwater Locating Device (LF-ULD)required by CAT.IDE.A.285(f). LF-ULD contains non-rechargeable LithiumBattery.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): F-0318-003 Non-rechargeable Lithium BatteryInstallationsThe requirements for environmental protection and the associatedcertified noise and/or emissi...	Supplemental Type Design Document - STDD25-18/20M Issue 1.0dated02.OCT. 2018Compliance Check List - CCL25-18/20M Issue 1 dated 10.OCT.2018or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/10/2018	Active	10067204
10067206	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 350 B3	Mod ref. AHUK/350/3128 consisting of installation and adaptation of AHIegacy SAGEM 85T31 Three Axis Autopilot (ref. AMSOP 1776) to enable I/Fwith Garmin 500H avionics.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MRI/3503128-01 “Master Record Design definition”, issue B, dated 8thOctober 2018;AHUK/350-FMS-107 “Flight Manual Supplement”, initial issue, datedOctober 2018;ICA/ 3503128-01 “Maintenance / Continued Airworthiness Instructions”,issue C, dated 11th October 2018;or later revisions of the above listed d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/10/2018	Active	10067206
10067211	SABENA TECHNICS BGC	REV. 3		A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112	GEE Global AirConnect System Activation on Airbus A318/A319/A320/ A321Revision 1 : Removal of the Limitation associated with HF communicationsystemRevision 2 : introduces the A318Revision 3 : introduces the A320 fitted with ARINC 791 provisions forinstallation of a dorsal Satellite Communication ante...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS amendment 4paragraphs : 1, 601, 777, 1301, 1307, 1309, 1322, 1351, 1353, 1360,1381, 1431, 1529, 1541, 1581, 1583, 1585....	- Master Data List, ref 0878-01-A-MDL-R04- Instructions forContinued Airworthiness (Supplement), ref :0878-01-A-ICA-R05- AFM (Supplement) 0878-01-A-AFMS-R04or later revisions of the above listed document(s) approved/ acceptedunder the EASAsystem.	The change related to this STC requires as a pre-requisite:Aeroconseil STC 10067212 or Aeroconseil STC 10071558 and AeroconseilMinor Change 0877-01-A-MCA-R06 or Minor Change 0877-02-A-MCA-R00 orMinor Change 0880-01-A-MCA-R00, or later approval revisions.The installation of the GEE Global AirConnecta...	08/11/2019	Active	10067211

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067212	SABENA TECHNICS BGC	REV. 2		A321-211/-121/-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112	GEE ARINC 791 Ku-Band Satellite Communication Antenna ProvisionsInstallationRevision 1 introduces the A318 models.Revision 2 introduces new specific design for A321-111 MSN 544	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: o,,CS-25 at amendment 4paragraphs: 1, 23, 29, 121, 251, 301, 303, 305, 307, 321, 337, 341, 365,561, 571, 581,...	- Master Data List, Ref. 0874-01-A-MDL-R04 (17/12/2021)- Instructions for continued airworthiness, Ref:,,0874-01-A-ICA-R04 (for A319/A320/A321, including specific MSN 544 ALI),,0874-01-A-ICA-F03-R01 (for A318)- Airplane Flight Manual Supplement, ref : 0874-01-A-AFMS-R00or later revisions of the abo...	This modification is compatible with Extended Service Goal,as describedin section 3.2 of Instructions for Continued Airworthiness (Supplement),ref: 0874-01-A-ICA-R04 & 0874-01-A-ICA-F03-R01.Models already fitted with ARINC 791 provisions for the installation ofa dorsal large Satellite Communication...	22/12/2021	Active	10067212
10067222	AERO ENGINEERING DESIGN LIMITED		CAA UK RESPONSIBILITY	737-500 737-400 737-300	Introduction of SSR Mode S Enhanced Surveillance Transponder System		-Aero Engineering Design Modification Certificate 34-13-200Issue 1dated January 08 2005 orlater approved revision-AeroEngineering Design Flight Manual Supplement AED/B737/001 Issue 1or later approvedrevision	1. This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraph "Description". Compatibility withother aircraft/ engineconfigurations shall be determined by theinstaller.	23/03/2005	Active	10067222
10067225	DART AEROSPACE Ltd.			429	DART D429-1056 Wearplate Kits.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS27.1 Amdt.4, CS27.21Amdt.4 , CS27.25 Amdt. 4, CS27.27 Amdt.4, CS27.29 Amdt.4, CS27.45 Amdt. 4,CS27.141 Amdt.4, CS27.241 A...	MDL-D429-1056 Rev. A Master Document List, dated July 31st 2018ICA-D429-1056 Rev. 0 Instruction for Continued Airworthiness, datedApril 30th 2018IIN-D429-1056 Rev. A Installation Instruction, dated April 30th 2018or later revisions of the above listed document(s) approved/accepted onbehalf of EASA i...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/10/2018	Active	10067225
10067226	SABENA TECHNICS BGC	REV. 1		A330-343	Cabin Reconfiguration from 38BC+262YC to 367YC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Applicable regulationsat CS 25 Amendment 4 (refer to the associated Certification Plan,indicated in the Master Data List)T...	- Master Data List, ref: 40264-01-A-MDL-R00-Instructions for Continued Airworthiness (Supplement), ref: 40264-01-A-ICA-R00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/10/2018	Active	10067226
10067230	LUFTHANSA TECHNIK AG	REV. 1		A330-203	Change to LHT STC 10067230 “A330-200 Executive Cabin Installation”Update to Instructions for Continued Airworthiness-AirworthinessLimitation-Section (CMR)<(>,<)>Update to AirplaneFlight Manual Supplement	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	LHT Certification Plan Ref. CPL-25-16/30M Rev 07 dated 25.02.2019Airplane Flight Manual Supplement Ref A-00-17/23-AFM Issue 07 dated21.12.2018Instructions for Continued Airworthiness Ref A-00-17/23-ICA Rev 04 dated22.02.2019LHT Declarationof Compliance Ref ADC 3661 Rev 0 dated 22.03.2019or later re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/03/2019	Active	10067230
10067244	AIRBUS HELICOPTERS, Inc.		FAA STC SR09499RC	EC 130 T2	Installation of a Lead Acid Battery in the tailboom.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Drawing List 130A82-8020, Installation, Lead Acid Battery EC130T2,Revision E dated 11 July 2014 or later ODA approved revision(s).2. Rotorcraft Flight Manual Supplement 130FMS-505, Rev. IR dated 31 July2014 or later ODA approved manual.3. Instruction for Continued Airworthiness 130MMS-022, Rev. I...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/10/2018	Active	10067244

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067248	airplus engineering GmbH	REV. 1		DR 400 RP, DR 400-120 DR 400-200R, DR 400/500 DR 400-180S, DR 400-2+2 DR 400-180, DR 400-180R DR 400-160, DR 400-160D DR 400-140, DR 400-140B DR 400-125, DR 400-125I DR 400-120A, DR 400-120D DR 400-100, DR 400 NGL DR 315, DR 340, DR 360, DR 380 DR 300-140, DR 300-180R DR 300-120, DR 300-125 DR 253, DR 253 B, DR 300-108 DR 250 B, DR 200 B-160 DR 220 AB, DR 221, DR 221 B DR 200, DR 250, DR 250-160 2. DR 253, DR 253 B 2. DR 250 B, DR 250 B-160 2. DR 220, DR 220 A, DR 220 B 2. DR 220 AB, DR 221, DR 221 B 2. DR 200, DR 250, DR 250-160 1. DR 400 RP 1. DR 400/500, DR 400 NGL 1. DR 400-2+2, DR 400-200R 1. DR 400-180R, DR 400-180S 1. DR 400-160D, DR 400-180 1. DR 400-140B, DR 400-160 1. DR 400-125I, DR 400-140 1. DR 400-120, DR 400-120A 1. DR 400-120D, DR 400-125 1. DR 360, DR 380, DR 400-100 1. DR 300-180R, DR 315, DR 340 1. DR 300-125, DR 300-140 1. DR 300-108, DR 300-120	Installation of Avidyne IFD5XX/4XX.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23, Amdt. 4 -23.1, 29, 301, 305, 307, 603, 605, 609, 611, 771, 773, 853, 1301, 1306,1308, 1309, 1321, 1327, 1329, 135...	- Description of Modification DE-2053-000000, Issue 2;- Aircraft Flight Manual Supplement PO-2053-000000, Issue 0-1;- Maintenance Manual Supplement MM-2053-000000, Issue 1;- Engineering Work Order EW-2053-000000, Issue 1;or later revisionsof the above listed document(s) approved/acceptedunder the E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/02/2021	Active	10067248
10067249	AMAC AEROSPACE SWITZERLAND AG			BD-700-1A10, BD-700-1A11	WLAN Activation.Activation of Wireless Local Area Network (WLAN) afterphysicalinstallation of router including the cockpit WLANON/OFFswitchwith Project AMAC Aerospace Minor Modification EY02-4430.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The change is defined with Revision A of Master Data List DocumentNumber MDL-BD701-4430;The aircraft shall be operated in accordance with the initial issue ofAirplane Flight Manual Supplement Document AFMS-BD701-4430;or later revisions of the above listed document(s) approved/ acceptedunder the EASA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.,,,,	17/10/2018	Active	10067249

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067255	FOKKER TECHNIEK B.V.	REV. 1		737-800	737-800 from Private use to Commercial.Change from Private to both Private and Commercial Role for Boeing737-800 with EASA STC 10047657 incorporated.Revision 1: Transfer of STC from Fokker Services B.V. (EASA.21J.059) toFokker Techniek B.V. (EASA.21J.667)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Airplane Flight Manual Supplement (AFMS) B738-ACM-AFM-S-001 Revision1;- Compliance Record Report CRR-0297 Issue 1;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The installation of EASA STC 10047657 is a prerequisite to install thisSTC.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthi...	05/12/2019	Active	10067255
10067266	JET AVIATION AG	REV. 1		FALCON 7X, FALCON 8X (VARIANT)	This STC allows the installation of cargo bags on Dassault Falcon 7X/8X3-place divans. The cargo bags are designed for carrying passengerluggage such as sports equipment. The transport of dangerous goods isexcluded.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-01 Cargo Seat Bag Installation.- The following paragraph(s) at a later amendment: CS-25 Amdt. 20 forthe paragraphs 25.1, 25.23, 25.301, 25.3...	- Airplane Flight Manual Supplement JSBL-M-01014AFM-01, Issue 02- Airworthiness Limitations Section in chapter 4 of JBSL-M-01014ICA-01,Issue 01- Master Data List JBSL-M-01014MDL-01, Issue 02or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/06/2019	Active	10067266
10067267	DELTA ENGINEERING CORPORATION	REV 1	FAA STC ST03437NY	737-9 737-8	Installation of Panasonic TAMDAR.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Delta Engineering Master Data List 0106-10357-2451 Revision A dated 7October 2018 or later FAA approved revision.2. The Instructions for Continued Airworthiness as listed on the MasterData List.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.EASA STC 10064143 is required with this STC.	16/11/2018	Active	10067267
10067268	DRABPOL SP. JAWNA P. DRABCZYNSKII WSPOLNIK			177 RG	Complete avionic refurbishment as defined in Z-034-014 document.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Elect to Comply paragraph(s) by applicant: FAR 23.867 Amdt. 7, FAR23.1309 Amdt. 62The requirements for environmental protection and the associatedcertified noise and/ oru...	Note: All below stated documents are valid for S/N 177RG0522 only.-Change Dossier Doc. No. Z-034-014, issue 1, dated 04/10/2018-Cessna 177RG Flight Manual Supplement Doc. No. DP-014-12<(>,<) >Bendix/King KN 62A DME, revision 0, dated 10/05/2018-Cessna 177RG Flight Manual Supplement Doc. No. DP-014-13...	Valid for S/N 177RG0522 only.The use of Garmin GNS 430W system is not permitted for instrumentapproaches using GPS guidance, in accordance with the limitationsspecified in AFM-S DP-014-23 Rev 0.The indications provided by G4 engine monitorsystem are not aircraftprimary engine parameters indications...	19/10/2018	Active	10067268
10067270	E A D AEROSPACE AIRWORTHINESS	REV. 1		747-400	KA-BAND SATCOM InstallationThe modification consists in:- The installation of the Antenna andRadome on the top of the aircraft having already received the structuralreinforcement approved under initial EASA STC approved revision.- Thecurrent EASA revised STC approval is covering in addition the SATC...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-101: “Vibration/ buffeting compliancecriteria for large external antenna installation” at issue 1The requirements for environmental prot...	Master Document List, EAD Aerospace document No. 01536-EAS-A-MDL,Revision D, dated 1st February 2019, andAirplane Flight Manual Supplement 01536-EAS-A-AFM-01 at revision B,dated 14th December 2018, andInstructions for Continued Airworthiness, EAD Aerospace document No.01536-EAS-A-ICA-01, Revision D,...	See those of Airplane Flight Manual Supplement 01536-EAS-A-AFM-01 atrevision B, dated 14th December 2018 or later EASA approved revisions,andThe previous original EASA STC Approval 10067270 was issued on 19thOctober 2018, when the STC configuration definition covered at that timeonly structural prov...	06/02/2019	Active	10067270
10067271	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST03438NY	SEE FAA APPROVED MODEL LIST	Installation of Adams Rite infrared Faucet and components.Revision 1 adds B737-8 and B737-9 to the applicability list.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	1. Delta Engineering Approved Model List 0198-10338-2437 Revision Ddated 27 May 2022;2. The Instructions for Continued Airworthiness as listed on theApproved Model List;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Implementati...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	04/05/2023	Active	10067271

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067272	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03596NY	FALCON 2000EX	Installation of a Meggitt iSFD Functional Upgrade (DisplaysILS andMagnetic Heading) in Dassault Aviation Falcon 2000EXAircraft with EASyAvionics installed.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Data List F2XW-D0078-005 Rev IR, dated 30 November 2017, orlater FAA approved revision.2. Instructions for Continued Airworthiness (ICA) F2XW-D0078-155, RevIR, dated 28 November 2017, or later FAA accepted revision. The ICA andits contents must be incorporated into the operator's maintenan...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.1. This alteration requires the following prereq...	22/10/2018	Active	10067272
10067286	JET AVIATION AG			A330-243	VVIP Cabin Interior Completion	As per CRI A-4301The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement: JBSC-M-00114AFM-01, Issue 02Certification Compliance Sheet: JBSC-M-00114CCS-01, Issue 05Master Data List: JBSC-M-00114MDL-01, Issue 03Instructions for Continued Airworthiness: JBSC-M-00114ICA-01, Issue 01EWIS Instructions for Continued Airworthiness: JBSC-M-00114EC...	Limited to S/N 1751Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	22/10/2018	Active	10067286
10067288	CHIPPEWA AEROSPACE, Inc.		FAA STC ST04361AT	ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ ERJ 170-200LR, ERJ 170-200 STD ERJ 170-100 LR,ERJ 170-100 STD	Installation of an ADS-B Out	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Drawing List (MDL) No. 170-3452-01-0001, Revision IR, dated 15January 2016, or later FAA approved revisions.Airplane Flight Manual Supplement (AFMS) to the Model EmbraerERJ-170-100 (ERJ170-200 (ERJ-175), ERJ-190-100 (ERJ-190), ERJ-190-200(ERJ-195) Series for Installation of ADS-B Out Capabili...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/10/2018	Active	10067288
10067325	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03598NY	FALCON 900EX (F900EX)	Installation of a GoGo AVANCE L5 system in Dassault Aviation Falcon900EX Aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03598NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Dassault Aircraft Services Master Data List F9XW-D0080-005 Rev IR,dated 18 December 2017, or later FAA approved revision.2. Dassault Aircraft Services Instructions for Continued Airworthiness(ICA) F9XW-D0080-155, Rev IR, dated 13 December 2017, or later FAAaccepted revision.3. Dassault Aircraft S...	The ICA and its contents must be incorporated into the operator'smaintenance program.Prior to activation of a Wireless Cabin Distribution System, it must beshown that the aircraftis compatible with transmitting portableelectronic devices (T-PED) per FAA policy statement PS-ANM-25-13.Operational app...	23/10/2018	Active	10067325
10067328	S-TEC CORPORATION		FAA STC SA09746DS	F182P, F182Q, FR182 182S, 182T, T182T 182Q, 182R, R182, T182, TR182 182K, 182L, 182M, 182N, 182P 182E, 182F, 182G, 182H, 182J 182, 182A, 182B, 182C, 182D	Installation of an S-TEC 01326 Digital Flight Control System (DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09746DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List No. ST-960-MDL-0001, Revision A, dated 19 April 2018or later approved revision.2. Airplane Flight Manual Supplement, ST-960-AFM-0001, Rev. -, dated 20April 2018, or later FAA approved revision.3. Instructions for Continued Airworthiness, ST-960-ICA-0001, Revision-, dated 20 April...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/10/2018	Active	10067328

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067334	S-TEC CORPORATION		FAA STC SA09747DS	F177RG 177RG 177B 177A 177	Installation of an S-TEC 01326 Digital Flight Control System (DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09747DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List No. ST-963-MDL-0001, Revision A, dated 30 May 2018or later approved FAA revision.2. Airplane FlightManual Supplement, ST-963-AFMS-0001, Rev.-, dated 30May 2018 or later FAA approved revision.3. Instructions for Continued Airworthiness, ST-963-ICA-0001, Revision-, dated 21 May 20...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	23/10/2018	Active	10067334
10067343	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR11238DS	505	Installation of Nightscanner	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	- Master Drawing List, Report No. AA-17095, Revision A, dated 19 July2018, or later FAA approved revision.- Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-17088, No Revision, dated 22 January 2018, or laterFAAaccepted revision.- Aeronautical Accessories Rotorcraft F...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/10/2018	Active	10067343
10067345	H4 AEROSPACE (UK) Ltd.	REV. 2	CAA UK RESPONSIBILITY	777-300ER/ 777F 777-200/ 777-200LR/ 777-300	ADS-B Upgrade using alternate GPS.The Major Change is required to approve an additional GPS positionsource for the ADS-B Out transponders. The new GPS position source datais provided by the CMC CMA-5024.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFM supplement ref. H4AFMS049 Rev. 6Modification summary sheet and declaration of compliance ref. H4A1883Issue 6or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/08/2019	Active	10067345
10067355	S4A SOLUTIONS FOR AVIATION, S.L			A330-343 A330-321/-322/-323/-341/-342 A330-243/-243F/-301/-302/-303 A330-201/-202/-203/-223/-223F	Seat Track and Floor Panels Installation in A330Seat tracksand floor panels will be installed on passenger cabin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SERVICE BULLETIN S4A 330173-SB001 Edition 1, 18/09/2018or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None.	26/10/2018	Active	10067355
10067361	ALAMO ENGINEERING GmbH	REV. 1		EMB-135BJ	Installation of IGA SatCom AntennaRev. 1: transfers he STC from "Deutsche Aircraft GmbH" to "AlamoEngineering GmbH".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	328 Support Services GmbH Master Document List ref. MDL147Z001 Issue Adated 25 October 2018or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	18/12/2023	Active	10067361
10067363	CHIPPEWA AEROSPACE, Inc.	REV. 1	FAA STC ST04015AT	EMB-145EU/EMB-145LR/ EMB-145MP EMB-145/EMB-145EP/ EMB145ER EMB-135BJ/EMB-135ER/ EMB-135LR	Installation of the Honeywell NZ-2000 FMS/GPS with or without WAAS/LPV	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Chippewa Aerospace Master Drawing List (MDL) No. 145-3461-01-0001, Rev.8, dated 19 December 2016, or later FAA approvedrevision.For aircraft installing the NZ-2000 FMS/GPS without WAAS/LPV refer toChippewa Aerospace MDL No. 145-3461-01-0001, Rev. 8, dated 19 December2016, or later FAA approved revi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/12/2018	Active	10067363

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067383	AEROTEC & CONCEPT			737-900/-900ER 737-500/-600/-700/-800/-8 737-100/-200/-300/-400	Medical stretcher installation on B737	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Data List AE18101MDL Rev. 0 dated 29/10/2018-AFM Supplement AE18101AFMS Rev. 0 dated 25/07/2018-Instructions for Continued Airworthiness AE18101ICA Rev. 0 dated25/7/2018orlater revisions of the above listed document(s) approved/ acceptedunder the EASA system.	-Per AFM Supplement AE18101AFMS-Per Instructions for Continued Airworthiness AE18101ICA-Pre-requisite: Aerotec Change AE16077MAS-This STC constitutes an approval for installation only for aircraftserial numbers as stated in drawing STR-16077-001-000. For additionalaircraft serial numbers the require...	30/10/2018	Active	10067383
10067398	ETIHAD AIRWAYS ENGINEERING L.L.C.			A380-861	EQUIPMENT AND FURNISHINGS - A380 CABIN RECONFIGURATION FROM11F / 70J /415 Y TO 11F / 70J / 68 Y+ / 337 Y	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Etihad Airways Engineering Master Document List Ref. EA8-18250687-DL01Issue 3 dated 25 October 2018or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This design change is applicable only to MSN 166, 170, 176,180, 191,195, 198, 199, 233 and 237Prior to installation ofthis change it must be determined that theinterrelationshipbetween this change and any other previously installedchange and/ or repair will introduce no adverse effect upon theair...	31/10/2018	Active	10067398
10067414	AEROTEC & CONCEPT			737-700	MOD AE17150 : G2 Galley Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- MASTER DATA LIST Doc N°: AE17150MDL Rev: 0 dated 29 October 2018-Instructions for Continued Airworthiness Doc N°: AE17150ICA Rev. 0dated 31 October 2018or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This design change is applicable only to MSN 29370	02/11/2018	Active	10067414
10067419	B/E AEROSPACE, Inc.		FAA STC ST02994AT	A300 F4-622 R A300 C4-620/A300 F4-605 R A300 C4-605 R VARIANT F A300 B4-622/A300 B4-622 R A300 B4-605 R/A300 B4-620 A300 B4-601/ A300 B4-603	Installation of a Honeywell Mark V Enhanced Ground Proximity WarningSystem (EGPWS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. EMTEQ Engineering Master Drawing List (MDL) 2-18476001, Rev. B, dated30 October 2004, or laterFAA approved revision. 2. Flight Manual Supplements (AFMS) for Airbus A300B4/F4600 SeriesAircraft, EMTEQDocument No. 2-18476-908, Rev. JR, dated 01 December 2004, or later FAAapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/11/2018	Active	10067419
10067420	MAXCRAFT AVIONICS Ltd.		TCCA STC P-LSH18-004/D ISSUE 1	MBB-BK117 C-2	Approval of Existing Installed AvionicsDual GNS430W GPS / NAV / COM, DVCS-6100 Audio System, KRA-405B RadarAltimeter, GTX330 Mode S Transponder, DFS-43A ADF Receiver, KR-21 MarkerBeacon	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment: Transport Canada AWM 529change 529-3: AWM 529.1301-1The requirements for environmental protection and the associatedcertif...	- Flight Manual Supplement, Garmin GNS430W GPS/NAV/COM (Dual),FMS-05-70-00-091, Revision A dated 26 August 2017- Chapter 04 - Airworthiness Limitations of Instructions for ContinuedAirworthiness, ICA-05-70-00-091, Revision B dated 9 August2018- Project Description, PD-05-70-00-091, Revision A dated...	Approval is limited to S/N 9158 and S/N 9209.Approval does not cover NVIS/NVG operation as well as SBAS basedapproaches.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wille...	02/11/2018	Active	10067420

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067422	DART AEROSPACE Ltd.		TCCA STC SH18-9	505	Installation of Dart Aerospace Ltd. Emergency Flotation System inaccordance with Master Document List MD505-1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MD505-1 Revision A- Installation Instructions II505-1 Revision A- Rotorcraft Flight Manual Supplement RFMS505-1 Revision A- Instructions for Continued Airworthiness ICA505-1 Revision 0or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in acco...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/11/2018	Active	10067422
10067437	GARMIN INTERNATIONAL, Inc.	REV 1	FAA STC SA02121SE	SEE FAA APPROVED MODEL LIST	Installation of Garmin GTS 800 (TAS), GTS 825 (TAS) or GTS 855 (TCAS I) Traffic System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 23Amendment 4.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain...	1. Master Drawing List, GTS 8X5 Part 23 AML STC, 005-00738-01, Rev 1,dated 2 May 2014, or later FAA-approved revision.2. Instructions for Continued Airworthiness (ICA) are provided in theMaintenance Manual 190-01279-01, Rev 1, dated 1 May 2014, or laterFAA-approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	19/12/2018	Active	10067437
10067443	MORSON PROJECTS LIMITED		CAA UK RESPONSIBILITY	B200GT, B200CGT	Approval of Category II ILS Approach functionality on BeechKing AirB200GT and B200CGT in accordance with Morson Projects Modification refMP0005A.	As per TCDS EASA.IM.A.277 Issue 13, plus CS-AWO Initial Issue dated17.10.2003.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Morson Projects Modification refMP0005A, and Service bulletin ref SB.MP34-007 latest revision;Operate in accordance with Morson Projects Aircraft Flight ManualSupplement No 4 Issue 1, dated November 2018;Instructions for Continued airworthiness in accordance with Mors...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/11/2018	Active	10067443
10067445	ETIHAD AIRWAYS ENGINEERING L.L.C.			787-9	REPLACEMENT OF ELECTRICAL GALLEY INSERT.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List ref EB8-1625279-DL01 Iss5< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2018	Active	10067445
10067448	ALOFT AEROARCHITECTS	REV. 3	FAA STC ST04052NY	737-8, 737-9 737-8	ViaSat KA Cabin Distribution System InstallationRev. 2: Applicability list extended to B737-9Rev. 3: Amendment to add aconfiguration 3 onto Boeing 737-8 aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data Index List (MDIL) 1292351, revision 013, dated 27 June2023;2. ICA. Comply with FAA-accepted Instructionsfor ContinuedAirworthiness (ICA) listed below. Supplements to the AircraftMaintenance Manual, Illustrated Parts Catalogand Wire Diagram Manualare cited within;a. Configuration 1,2...	The following alterations are prerequisites to this installation: EASASTC 10068725 Installation of a ViaSat KA SATCOM Antenna System.Prior to activation of a Wireless Cabin Distribution System, it must beshown that the aircraft is compatible with transmitting portableelectronic devices (T-PED) per F...	26/10/2023	Active	10067448
10067464	C&D ZODIAC, Inc.		FAA STC ST02391LA	ERJ 190-100 LR	C<(>&<)>D Zodiac, Inc. Interior Installations and Modifications.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	C<(>&<)>D Zodiac, Inc., Index List No. G811, Revision A, dated 10November 2014, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC approves provisions for the installatio...	07/11/2018	Active	10067464

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067471	ARCHEION HOLDINGS, L.L.C.		FAA ST03386AT	737-700, 737-800 737-300, 737-400	Installation of an Avionica, Inc satLINK System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Archeion Holdings, L.L.C. Airplane Flight Manual SupplementNo.26048-AFMS Revision C;Archeion Holdings, L.L.C. Instructions for Continued Airworthiness No.26047-ICA Revision R;or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subseque...	None	07/11/2018	Active	10067471
10067483	AEROLITE AG	REV. 4		PC-24	EMS Equipment P/N 024-0229582-501 and P/N 024-0314000-501.Rev. 1 changes the following limitations defined in the FMS: - Limitations for EMS operation - Satcom limitation - Removal of the temperature limitations for vacuum pump and240VAC outletsRev. 2 introduces EMS Equipment P/...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:For the installation of stretcher / stretcher trolley: CS-23Amdt. 05§23.2270(a).The requirements for environmental prote...	- General:Installation according to Aerolite Master Document List MDL-16-005, Rev.M- For EMS Equipment PC-24 P/N 024-0229582-501:Aerolite Flight Manual Supplement FMS-024-0229582-501, Rev. EAvionic Straubing Flight Manual Supplement ASR-2016-070-FMS-05-01, Rev.01Aerolite Instructions for Continued A...	Pilatus Factory Option Stretcher Loading Device P/N 5002024307 isprerequired for installation of Aerolite Stretcher Loading Device Inst.P/N 024-0312000-501.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously i...	12/05/2023	Active	10067483
10067487	STG AEROSPACE GERMANY GmbH	REV. 1		EMB-145MK, EMB-145MP EMB-145LR, EMB-145LU EMB-145ER, EMB-145EU EMB-145, EMB-145EP EMB-135LR EMB-135BJ, EMB-135ER	saf-Tglo Photoluminescent Aisle Path Marking Systems EMBRAER 135/ E145Series AircraftRevision 1: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- STG Aerospace LTD Master Data List Doc. No. SG-1027-MDL-01 Rev. Adated 2 November 2018- STG Aerospace LTD Flight Manual Supplement Doc. No. SG-1027-FMS-01Rev. A dated 7 November2018- STG Aerospace LTD Ground Test Schedule Doc. No. SG-1027-GTS-01 Rev. Adated 2 November 2018- STG Aerospace LTD Inst...	For each individual aircraft cabin configuration the STC Holder shallupdate the Appendix 1 of the Flight Manual Supplement Doc. No.SG-1027-FMS-01 and the Appendix 1 of the Cabin Crew Data Supplement Doc.No. SG 1027-CCD-01 to include the appropriate cabin interior lightingconfiguration and “Charginge...	12/02/2021	Active	10067487
10067500	GAL AVIATION Inc.		TCCA STC Q-LSA18-012/D	DHC-8-402	Fabrication and Installation of New Overhead Bins	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- The modification and installation must be carried out in accordancewith Can-AM Aerospace Master Drawing List 25-17-08-005, Revision NC,dated 7th of March 2018- The maintenance must be carried out in accordance with Can-AmAerospace Instructions for Continued Airworthiness (ICA) 25-17-08-004Revision...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/11/2018	Active	10067500
10067510	B/E AEROSPACE, Incd/b/a SMR TECHNOLOGIES, INC		FAA STC ST03242NY	SAAB SF340A, SAAB 340B	Replacement of certain Goodrich pneumatic de-icer boots	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	SMR Technologies, Inc. Pneumatic De-icer Layout SAAB 340, Document No.SMR5141, Revision 8, dated 6 October 2017 and detail design as listed onMDL-0052, Revision N, dated 18 May 2018 or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The Maintenance Instructions for Continued Airwo...	14/11/2018	Active	10067510
10067515	AERODATA AG			B300	OSD elements MMEL and FCD for B300 aircraft equipped with AD-AFIS.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MMEL: OSD-MMEL-1000 Rev. 1, dated 2 November 2018;FCD: OSD-FCD-1000 Rev. 0, dated 25 September 2018;or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The approval holder shall fulfill the obligations of Part 21, Point21A.109.	14/11/2018	Active	10067515

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067516	CORPORATION LOGIC AIR Inc.		TCCA Q-LSA18-036/D ISSUE 2	A330-243	Removal of the LDMCR and Installation of Lavatories at Locations L35 andL61/62.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	'EASA Approved'Kmlex Aviation Inc. Instructions for Continued Airworthiness No.ICA38152-003 Revision NC dated 15 August2018;'EASA Accepted' Kmlex Aviation Inc. Master Document List No. MDL38152002 Revision Adated 15 October 2018;or later revisions of the above listed document(s) approved/ accepted o...	Restricted to MSNs 0728 and 0732.	14/11/2018	Active	10067516
10067518	AERODATA AG			B300	Installation of AD-AFIS-1013 into B300 in accordance with MasterAssembly Drawing B30 0-37.01_AFIS and defined in Aerodata ModificationIdent B300-37.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement AFM-166 Rev. 1 dated 26-Oct-2018;Aircraft Maintenance Manual Supplement AMM-1168;Master Document List MDL-A/ C-916;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Limited to B300 aircraft equipped with Rockwell-Collins Proline FusionAvionics.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	14/11/2018	Active	10067518
10067589	LORD CORPORATION		FAA STC SR04913CH	206L-4 206L-3 206L-1 206L 206B 206A	Installation of LORD Tension-Torsion Strap Assemblies (P/ NLORD206-310-004101 and LORD206-310-004103) on the main rotor	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:14CFR Part 27 as provided below27.301 (27-0) Loads27.303 (27-0) Safety27.305 (27-0) Strength and Deformation27.547 (27-3)2...	Airworthiness Limitation Section of ICA ECCN 9E, Rev C, dated 28 October2018Project Specific Certification Plan APA15-0105, Rev C, dated 27 August2018Master Drawing List LORD-MDL-206-310-004101/0041 03 initial revision,dated 15 March 2017orlater revisions of the above listed document(s) approved/ acc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/11/2018	Active	10067589
10067592	AIRBUS S.A.S.			A319-114, A319-115 A319-111, A319-112, A319-113	A319 VOLOTEA 150 TO 156 PAX TYPE 1Change to the existing cabin arrangement to increase overall seatingcapacity from 150PAX to 156 PAX.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Summary Report ref. AIS-AJA-18072 Issue 5, dated 20thNov 2018.- Modification Approval Sheet ref. MAS AI0074 Issue 2, dated 20th Nov2018.	None	21/11/2018	Active	10067592
10067626	SPECIALIST AVIATION SERVICESLIMITED		CAA UK RESPONSIBILITY	AW169	Fischer 230/305 Seat (SAS/MOD/894) This Change installs a translating and swivelling Fischer Medical Seat230/305 replacing the fixed Fischer 1021-series seat in the port-aftposition within a seating configuration already certified by SAS aspartof STC 10062099.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Declaration of Compliance for SAS/MOD/894 dated 22/11/2018- Rotorcraft Flight Manual Supplement FMS/894-043 Issue A-Maintenance Program Supplement MPS/894-040 Issue Aor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This Supplemental Type Certificate must be installed in conjunction withSAS/MOD/833 (STC 10062099).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adversee...	26/11/2018	Active	10067626

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067627	AERO-DIENST GMBH			60	GPS WAAS Sensor System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- According to Aero-Dienst Master Document List No. 20308-LJ.DC-101, Rev. 0- To be operated iaw. with Aero-Dienst AFM-SDocument No.20308-LJ.DC-106, Rev 00- To be maintained iaw. Aero-Dienst ICA Document No. 20308-LJ.DC-105,Rev 00or later revisions of the above listed document(s) approved/acceptedun...	According limitation section of AFM-S applicability: LJ60, LJ60XrexcludedPrior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthine...	27/11/2018	Active	10067627
10067644	GROWING ENGINEERING PARTNERS GmbH	REV. 2		A330-223	A330-200 Cabin Reconfiguration.Reconfigure aircraft from 19 BC / 0 PEC / 268 EC to: 19 BC / 35 PEC/212 EC (MSNs 0403, 0432 and 0476); and 19 BC / 36 PEC / 212 EC (MSN0322), including new BC and PEC seats.Rev 2.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	S.OAED.000609-ICA;CCD Supplement - S.OAED. 000609-OSD;or later revisions of the above listed document(s) approved under theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/04/2021	Active	10067644
10067645	SAFRAN ELECTRONICS & DEFENSEBUSINESS UNIT - HELICOPTERS DATAMANAGEMENT SOLUTIONS & SERVICES	REV. 2		AB206 A, AB206 B	Installation of the HELICOM HV2+ ANA flight data monitoringsystem.Rev. 2: STC holder name change from I.S.E.I International Services toSAFRAN ELECTRONICS & DEFENSE BUSINESS UNIT - HELICOPTERS DATA MANAGEMENTSOLUTIONS & SERVICES.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 issue 3 dated 12 November 2018 - AB206Lithium Battery Installations.The requirements for environmental protection and the associatedcertif...	Rotorcraft flight manual supplement N11-AB206 HV2+ ANA-E-A-03 dated 22November 2018;List of documents N10-AB206 HV2+ ANA-E-A-03 dated 22 November 2018;Instructions for continued airworthiness N8-AB206 HV2+ ANA-E-A-03 dated22 November 2018;Installation manual N7-AB206 HV2+ ANA-E-A-03 dated 22 Novembe...	Crew interaction with the HELICOM HV2+ ANA flight data monitoring systemis not allowed when rotor turning.Prior to installation of this change/ repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no a...	27/02/2020	Active	10067645
10067647	APTOZ EHF.	REV. 1		FALCON 2000	Installation of a Free Flight 1203C WAAS GPS Sensor and Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. STC documents list in CRA341019 revision B, dated 21 December 20182. Certification Programme CP341019 revision C, dated 21 December 20183. Airworthiness Limitations in ICA341019 revision A, dated 21 December2018or later revisions of theabove listed document(s) approved under theEASA system.	This approval covers the physical installation of the parts, asdescribed in the Certification Programme CP341019 revision C, dated 21December 2018. The activation of the function is not covered by thisapproval.Prior to installation of thischange/repair it must be determined thatthe interrelationshi...	18/02/2019	Active	10067647
10067665	B/E AEROSPACE, Inc.		FAA STC ST03283AT	737-600/-700/-800/-900	Installation of a Matsushita Model RDAX7360 Pre-Recorded Announcementand Boarding Music Reproducer (PRAM)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	EMTEQ Engineering Master Drawing List (MOL) 2-36870-002, Rev. A, dated12 June 2016, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/11/2018	Active	10067665
10067669	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC ST02126LA	767-300	Installation of ACSS SafeRoute™ System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Index of Master Data Lists, Document No. 8900056, Revision "C", dated 5June 2008, or later FAA approved revision.Instructions for Continued Airworthiness (ICA) and FAA approved AirplaneFlight Manual Supplement (AFMS) are called out in their correspondingFAA approved Master Data List (MDL) of the con...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Applicable "Limitations" are described in the co...	29/11/2018	Active	10067669

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067682	TENENCIA Ltd.		CAA UK RESPONSIBILITY	737-800	Kontron Cab-n-Connect Wireless IFE System.This modificationinstalls the Kontron Cab-n-Connect Wireless IFE Systemon the Boeing 737-800 aircraft. The Cabin Wireless IFE system provideswireless access to audio-visual info- entertainment content topassengers via carry-on PED's.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): SC H-01 ICA on EWIS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original productu...	- Master data List Report TEN 840 issue 1;- Airplane flightManual Supplement Report TEN 840-47 issue 1;- Instructions for Continued Airworthiness Report TEN 840-04 issue 2;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/11/2018	Active	10067682
10067685	DASSAULT FALCON JET CORPORATION	REV. 1	FAA STC ST01824WI	MYSTÈRE FALCON 900 (MF900)	Installation of a Data Link Communication System supportingFuture AirNavigation (FANS I/A+) Capability.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): EASA CRI F9122-002, EASA CRIF-9122-003.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	EDOC-020049 Rev C Master Document List - March 24, 2017EDOC-020085 Rev C AFMS - March 24, 2017or later revisions of theabove listed document(s) approved/accepted onbehalf of EASAin accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	None.	20/12/2018	Active	10067685
10067699	LUFTHANSA TECHNIK AG	REV. 3		A330-343 A330-341 A330-243 A330-202, A330-341, A330-343 A330-202	Large KA-band antenna and systems installation – A330 Family GXconnectivityRev. 1: Extension of STC applicability to A330-341 model; Designoptimization affecting Structural & F<(>&<)>DT AnalysisRev. 2: Update of inspection program by improved F<(>&<) >DT Analysis forall modelsRev. 3: Extension of STC...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-101 "Vibration/ buffeting compliancecriteria for large antennainstallation"The requirements for environmental protection a...	- Supplemental Type Design Document STDD23-17/11M Issue 4 Rev 2- Flight Crew DATA A-00-18/06-FCD Issue 02 Rev 00- Airplane Flight Manual Supplement A-00-18/06-AFM Iss. 05 Rev. 00-Instruction for Continued Airworthiness A-00-18/06-ICA Iss.05 Rev. 00or later revisions of the above listed document(s)...	Installation allowed only on models that satisfy, respectively, thecriteria and configuration defined in the configuration sheetsAWX01-23-EI-001 Rev. 5 and AWX01-53-EI-002 Rev. 7,or later revisions ofthese documentsPrior to installation of this change/repair it must be determined thatthe interrelat...	28/10/2024	Active	10067699
10067717	S4A SOLUTIONS FOR AVIATION, S.L			MYSTÈRE-FALCON 20GF MYSTÈRE-FALCON 20F5 MYSTÈRE-FALCON 20E5 MYSTÈRE-FALCON 20D5 MYSTÈRE-FALCON 20C5	Installation of FDR L3 Model F1000 in in FALCON 20 Airplanes	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- F2003-SB001 Service bulletin Ed6- F2003-HDK01 Flight Manual Supplement Ed4- F2003-HDK02 Maintenance Manual SupplementEd4or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/12/2018	Active	10067717
10067723	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR04230NY	AW119MKII	Installation of a TRAKKA A800 Searchlight	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. AgustaWestland Philadelphia Corporation Master Data ListNo.AWPC-ENG-17-061, Revision -, dated 20 June 2018 or laterFAA approvedrevisions.2. Maintenance must be in accordance with AgustaWestland PhiladelphiaCorporation, Instructions for Continued Airworthiness, for the TRAKKAA800 searchlight Doc...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/12/2018	Active	10067723

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067746	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 2	FAA STC ST02638LA	747-400, 747-400F	Upgrade of the Aviation Communication & Surveillance Systems (ACSS)XS-950 Mode S/ADS-B Out Transponder or Installation of the ACSS NXT-800Mode S/ ADS-B Out Transponder including ADS-B Out functionality. Rev 2includes use of Standalone GPS source to provide Navigation Data to theACSS XS-950 or ACSS NX...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 Amdt 12 (except for CS 25.869(a)(4) & CS 25.1322(b) which are atAmdt 4). CS ACNS.D.ELS, CS ACNS.D.EHS & CS ACNS.ADSBT...	ACSS Index of Master Data List, Drawing No. 8917474, Revision "-" dated28 September 2018, or later FAA approved revision.Instructions for Continued Airworthiness (ICA) and FAA approved AirplaneFlight Manual Supplement (AFMS), called out inthe corresponding FAAApproved Master Data List (MDL), listed...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/08/2019	Active	10067746
10067754	S-TEC CORPORATION	REV. 1	FAA STC SA09749DS	320E, 320F, 335, 340, 340A 310R, T310R, 320B, 320C, 320D 310N, 310P, T310P, 310Q, T310Q 310I, 310J, E310J, 310K, 310L 310D, 310E, 310F, 310G, 310H	Installation of an S-TEC 01326 Digital Flight Control System (DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Data List No. ST-965-MDL-0001, Revision A, dated 29 August 2018or later FAA approved revision.Airplane Flight Manual Supplement, ST-965-AFMS-0001, Revision -, dated 5September 2018 or later FAA approved revision.Instructions for Continued Airworthiness, ST-965-ICA-0001, Revision -,dated 16 Au...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/12/2018	Active	10067754
10067773	SWISS AIR-AMBULANCE Ltd.			AW109SP	Replacement of existing incandescent lamps with LED-type lamps forLanding-, taxiing- and cabin searchlight (ref. modification RE.10344)for NVIS certified AW109SP helicopter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List RE.10344.DWL issue 1, dated 20 September 2018.ICA Supplement, RE.10344.ICS, issue 02, dated 07 November 2018.Service Bulletin RE.10344.SB01, issue 03, dated 06November 2018.Certification report, RE.10344.CR, issue 01, dated 06 September 2018.	Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the configuration specified in thisdesign change may a...	04/12/2018	Active	10067773
10067805	AVCON INDUSTRIES, Inc.	REV. 5	FAA SA2429CE	SEE FAA APPROVED AML SA2429CE	Provisions for the Installation of Tandem Cameras, with Optional DropHatch.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA2429CE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Avcon Drawing List No. 1043, dated 1 November 1988, or later FAAapproved revisions.See FAA Approved Model List (AML) No. SA2429CE for Pilot's OperatingHandbook and FAA Approved Airplane Flight Manual Supplements.	These airplanes are in a Restricted Category when this modification isinstalled.Prior to installation of this design change it must be determined thatthe interrelationship betweenthis design change and any otherpreviously installed designchange and/ or repair will introduce noadverse effect upon t...	12/02/2020	Active	10067805
10067813	WENDLING, TOBIAS			ASW 20, ASW 20 L	Installation of winglets ‘Maughmer’ kind of instead of winglets‘Lindner’ kind of.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dimension of winglets defined in Tobias Wendling document ‘AbmaßeWinglets’, at revision 1.1, dated November 18, 2018;Installation in accordance with Tobias Wendling document,‘Beschreibung’, at revision 1.1, dated November 13, 2018;AircraftFlight- and Maintenance Manual Supplement, Tobias Wendlingdo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.,,,,	05/12/2018	Active	10067813

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067829	S-TEC CORPORATION		FAA STC SA09748DS	PA-32RT-300T (TURBO LANCE II) PA-32RT-300 (LANCE II) PA-32R-301T (TURBO SARATOGASP) PA-32R-301T (SARATOGA II TC) PA-32R-301 (SARATOGA SP) PA-32R-301 (SARATOGA II HP) PA-32R-300 (LANCE) PA-32-301XTC (PIPER 6XT) PA-32-301T (TURBO SARATOGA) PA-32-301 (SARATOGA) PA-32-301FT (PIPER 6X) PA-32-300 (CHEROKEE SIX 300) PA-32-260 (CHEROKEE SIX 260)	Installation of a S-TEC 01326 Digital Flight Control System(DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Data List No. ST-957-MDL-0001, Revision A, dated 2 July 2018 orlater FAA approved revision.Airplane Flight Manual Supplement, ST-957-AFMS-0001, Revision -, dated 3July 2018or later FAA approved revision.Instructions for Continued Airworthiness, ST 957-ICA-0001, Revision -,dated 19 June 2018,...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	05/12/2018	Active	10067829
10067840	SOCIETE AIR FRANCE S.A.			A330-243	Crew rest installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: JAR 25.807, JAR 25.811,JAR 25.853 and JAR 25.1423 at Change 14.The requirements for environmental protection and the assoc...	Air France Service Bulletin (Service Bulletin issued by AirFrance DOA) AFSBA3301701025-001;Air France DOA Change Approval Sheet CAS-A330-17-010;or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/12/2018	Active	10067840
10067844	GLOBAL AEROSPACE DESIGNCORPORATION		FAA STC ST04321CH	737-800	Install passenger cabin upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Global Aerospace Design Corp Master Drawing List GR0362-MDL, Revision A,dated 4 May 2018, or later FAA approved revisions.	Limited to Serial Numbers 35632, 35286 and 35637.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	06/12/2018	Active	10067844
10067863	FTI ENGINEERING NETWORK GmbH	REV. 1		EMB-145MP EMB-145LU, EMB-145MK EMB-145EU, EMB-145LR EMB-145EP, EMB-145ER EMB-135LR, EMB-145 EMB-135BJ, EMB-135ER	ADS-B Out for EMB-145 SeriesNote: This STC has been updatedat Rev. 1 for the definition of analternate GPS Antenna Position.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): F-01 Issue 1 dated 18 October 2018.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original p...	- FTI Master Document List document ref. F18-EO18-1634 Issue 4 dated 10December 2019- FTI AFM Supplement documents ref.F20-001-EO18-1634 Issue 4 dated 22October 2019 and F20002-EO18-1634 Issue 3 dated 11 December 2018- FTI Instructions for Continued Airworthiness document ref.F33-EO18-1634 Issue 5...	The Airworthiness Limitations as defined in chapter 2 of FTI ICAdocument ref. F33EO18-1634 are applicable to this STC installation.	12/12/2019	Active	10067863
10067869	ROCKWELL COLLINS, Inc.		FAA STC ST02218AT-D	767-200, 767-400	Installation of Collins HF Data Link System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	TIMCO Master Data List 98TI26L059, Revision G, dated 30 June 2001, orlater FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/12/2018	Active	10067869

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067871	AEROSPACE DESIGN & COMPLIANCE LLC		FAA STC ST04010NY	A321-271N/ -272N A321-251N/ -252N/ -253N A321-212/ -213/ -231/ -232 A321-111/ -112/ -131/ -211 A319-115/ -131/ -132/ -133 A319-111/ -112/ -113/ -114 A319	Installation of Reticulated Polyurethane Foam (RPF) for Center Fuel TankIgnition Mitigation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04010NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Aerospace Design & Compliance, LLC. Master Data List A321-MDL-0004,Rev IR, dated 23 April 2018, or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA)A321-ICA-0004, Rev IR,dated 16 March 2018, or later FAA accepted revision.3. Aircraft Flight Manual Supplement (AFMS) A3...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/12/2018	Active	10067871
10067872	S4A SOLUTIONS FOR AVIATION, S.L			DC-9-83 (MD-83) DC-9-82 (MD-82)	Installation of a New SSFDR L3 Model FA2100, and ULB DUKANE DK-120/90.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MD813-SB001 Service Bulletin Edition 3;MD813-HDK01 Flight Manual Supplement Edition 1;MD813-HDK02 Maintenance Manual Supplement Edition 1;MD813-RPT02 Master Drawing List Edition 2;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Boeing MD-82 MSN 49902, Boeing MD-83 MSN 49936.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce noadverseeffect upon the airworthiness of the product.	07/12/2018	Active	10067872
10067876	DASSAULT FALCON JET CORPORATION		FAA ST01786WI	MYSTÈRE FALCON 900 (MF900)	Installation of a Cobham Aviator 7000 Satellite Communication System (SATCOM).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EDOC-018681 Rev B MDL Master Data List - Sept. 24, 2015;EDOC-018698 Rev B Instructions for Continued Airworthiness - Sept. 24,2015;EDOC-018700 Rev A Airplane Flight Manual Supplement - June 03, 2015;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance w...	Applicable to MF900, A and B models.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	07/12/2018	Active	10067876
10067947	DUNCAN AVIATION, INC.		FAA ST01811WI	HAWKER 800, HAWKER 800XP	Honeywell Primus II ADS-B OutThe Honeywell Primus II Systemis upgraded to provide ADS-B Outcapability. This includes upgrading the existing Honeywell IntegratedControl Units andRadio Management Units and installing a new HoneywellKGS 200 GNSSU as position source.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: FAR 25.571 (a)(b) Amdt45, FAR 25.853(a) Amdt 51, FAR 25.869(a)(4) Amdt 113, FAR 25.581(a)(b)Amdt 141, FAR 25.1316(b) AmdtT...	Installation in accordance with Duncan Aviation Inc. MasterDocumentList EDOC-019840, Rev. B, dated 6th October 2016;Operation in accordance with Duncan Aviation Inc. Airplane Flight ManualSupplement EDOC-019836, Rev. A, dated 4th April 2016;Maintenance in accordance with Duncan Aviation Inc. Instru...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/12/2018	Active	10067947
10067948	LEARJET Inc.		FAA STC ST00385BO	CL-600-2B16 (604 VARIANT)	The STC installs a Honeywell Jetwave™ KA Band Satellite Data System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00385BO.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Bombardier Master Document List (MDL), Document number BAS63017019,Revision C, dated 1 May 2017, or later FAA approved revision.2. Learjet Inc.'s Aircraft Flight Manual Supplement (AFMS) DocumentNumber BAS63047020, revision NC, dated and FAA approved on 3 May 2017,or later FAA approved revisions....	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The aircraft must have the fin top radome M38-10...	18/12/2018	Active	10067948

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10067952	CARLISLE INTERCONNECT TECHNOLOGIES		FAA STC ST04234CH	777-300, 777-300ER	Installation of the Outside Antenna Equipment Provisions for theARINC791 SATCOM System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-101 “Vibration/ buffeting compliancecriteria for large external”The requirements for environmental protection and the associatedcertifie...	- Master Data List (MDL), Ref. 900-429653 Rev. E- Airplane Flight Manual Supplement (AFMS), Ref. 900-431727 Rev. N/C- Instructions for Continued Airworthiness (ICA), Ref. 900-349451 Rev. Bor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Tec...	Per Section 4 of the Instructions for Continued Airworthiness (ICA),Ref. 900-349451 Rev. BPrior to installation of thischange/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upo...	11/12/2018	Active	10067952
10067962	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE	REV. 2	FAA ST01918CH	A330-941 A330-341/-342/-343 A330-321/-322/-323 A330-301/-321/-322/-323 A330-301/-302/-303 A330-243/-243F A330-223/-223F A330-202/-223/-243 A330-201/-202/-203	Installation of Honeywell RESCU 406AF/ AFN/AFN2 ELT on Airbus A330.Reason for Revision 1: extended model applicability.Reason for Revision 2: typos corrected	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): SC F-11 Non-rechargeable Lithium BatteryInstallationsthe following paragraph(s) at a later amendment:CS 25.29(a,b) amdt. 15CS 25.301(a,b) amdt.15CS 25...	MDL DC104-1002-00 Rev. R dated March 11 2020AFMS DC303-1002-00 Rev. B dated October 20 2009ICA DC113-1002-00 Rev. F dated August 28 2009DC113-1009-00 Revision A, dated February 10 2004DC113-9807A6-00 Revision E, dated March 10 2020or later revisions of the above listed document(s) approved/accepted...	As per AFMS DC303-1002-00 Revision B. In particular: The ELT does notneed to be manually activated for test purposes. Manual activation, ifdesired, is limited to the first five minutes of the hour and is to beof very short duration (5-10 seconds).	31/08/2020	Active	10067962
10067971	LUFTHANSA TECHNIK AG	REV. 1		A320-214	Ka-band Satcom System Installation.Revision 1: ICA/ ALS structural inspection intervals change.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-101 “Vibration/ buffeting compliancecriteria for large external”.The following paragraph(s) at a later amendment: CS-FCD Initial Issue.T...	Supplemental Type Design Document, Ref. STDD53-18/06M Issue02 Revision00Airplane Flight Manual Supplement, Ref. A-00-18/68-AFM Issue 01 Revision00Flight Crew Data, Ref. A-00-18/68-FCD Issue 02 Revision 00Instructions for Continued Airworthiness, Ref. A-00-18/68-ICA Issue 03Revision 00or later revis...	As per:- Airplane Flight Manual Supplement, Ref. A-00-18/68-AFM- Instructions for Continued Airworthiness, Ref. A-00-18/68-ICAPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair...	17/07/2019	Active	10067971
10067992	EMS TECHNOLOGIES CANADA, Ltd.	REV. 1	TCCA SH17-37	429	Aspire 200 IG SATCOM with Cabin Wi-Fi System Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avionics Design Services Ltd. Master Drawing List MDL17032,RevisionN/C, Transport Canada approved September 29, 2017;EMS Technologies Flight Manual Supplement FMS17032-1 RevisionN/ C,Transport Canada approved September 29, 2017;EMS Technologies Instructions for Continued Airworthiness ICA17032-1,Re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/12/2018	Active	10067992
10067995	WEST STAR AVIATION, LLCd/ b/a WEST STAR AVIATION		FAA STC ST00914DE	MYSTÈRE FALCON 900 (MF900)	Installation of an Iridium Satellite Communication Data Link Unit.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00914DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List 18311L-745, Revision B, dated 8 October2018, orlater approved FAA revision.2. Airplane Flight Manual Supplement, West Star Aviation, Doc. No. 18311M-1120, Revision I/ R, dated 31 July 2018, FAA approved 8 October2018 or later FAA approved revisions.3. Instructions for Continued Ai...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/12/2018	Active	10067995

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068000	EIRTECH AVIATION SERVICES LIMITED			737-8	B737-8 MAX, 189Y ACRO Series 6 Installation.This Change will install ACRO Series 6 seats in a 189Y passengerconfiguration into 6 x Boeing B737-8 MAX aircraft being delivered in aZERO pax configuration from the TC holder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MASTER DOCUMENT LIST MDL_1087-001_4 dated 13 December 2018SERVICE BULLETIN ERT-SB-1703_2 dated 13 December 2018ICA AMS_1087-001_1 dated 17 October 2018or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/12/2018	Active	10068000
10068010	DUNCAN AVIATION, INC.		FAA ST01810WI	560 AND 560XL	Upgrade of Honeywell Primus II System for ADS-B Out with existingUniversal UNS-1Espw Position Source or installation ofstand-aloneHoneywell KGS-200 position source.	CS 25.869(a)(4) at Am 0 and CS 25.1316(b), 25.1317(b)(c) atAm 15.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Duncan Aviation, Inc. , Master DocumentList EDOC-019623, Rev. A, dated December 21, 2015;Operate in accordance with Duncan Aviation, Inc., FAA Approved AirplaneFlight Manual Supplement, CERTDOC-002510, Rev. A, dated December 21,2015;Maintain in accordance with Instruc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/12/2018	Active	10068010
10068013	COMTECH GLOBAL AVIATION SERVICES S.	REV. 1		A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Introduction of Centre Fuel Tank Ignition Mitigation ReticulatedPolyurethane Foam.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 25.29; 25.301(a)(b); 25.303; 25.307(a); 25.321(a); 25.333; 25.343(a); 25.601; 25.603;25.605(a); 25.609; 25.611; 25.901 [a(1...	-Modification Summary CTE-MS0180-320 Rev A, dated 21/11/2018For the A319 models:-Aircraft Flight Manual Supplement CTE-AFM0180-02 Rev -, dated18/08/2018-Instructions for ContinuedAirworthiness CTE-TP0180-03 Rev -, dated25/06/2018For the A320 models-Aircraft Flight Manual Supplement CTE-AFM0180-01 R...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/04/2019	Active	10068013
10068020	DASSAULT FALCON JET			MYSTÈRE FALCON 900 (MF900)	Battery Installation (36 or 40 hour) in accordance with Drawing ListReport No. F90-01053, Revision G, dated 18 October 2001, or later FAAapproved revision.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA7232SW-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	1) When the -501 installation is utilized:FAA approved Airplane Flight Manual Supplement, Report No. 36071-1,dated 24 May 1988, or later FAAapproved revision is required.2) When the -503 installation is utilized:a) FAA approved Airplane Flight Manual Supplement, Report No. 36071-2,dated 27 September...	1) The F90-01053-501 Installation is valid only in the Mystère Falcon900 Model Aircraft.2) The F90-01053-503 Installation is valid only in the Mystère Falcon900 Model Aircraft.3) The F90-01053-505 Installation is valid only in the Falcon 900CDefinition Aircraft. 4) The F90-01053-507 Installation is v...	17/12/2018	Active	10068020
10068025	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST04293CH	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Installation of a Honeywell JetWave System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04293CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	StandardAero Master Data List 1035510, Revision (D), dated 22 October2018< (>,<)> or later FAA approved revision.FAA approved Airplane Flight Manual Supplement document number 1034227,Revision (A)<(>,<) > dated 9 September 2018, or later FAAapprovedrevision is a required part of this installation.Inb...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/12/2025	Active	10068025

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068074	TENENCIA Ltd.	REV. 1	CAA UK RESPONSIBILITY	737-9, 737-900, 737-900ER 737-700, 737-800, 737-8	TEN 845Installation of an auxiliary rack E8-1V that provides provisions forLRUs to be installed in the Electronics and Engineering Bay. The E8-1Vis located between FS 312 - FS 328and LBL 3.75 - LBL 27.4 at WL200. Itis weight limited to hold up to 50 lbs of equipment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List TEN 845 issue 1ICA TEN 845-04 issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This modification is not applicable to Lower Cabin Altitude(LCA)modified aircraft (EASA STC 10042295).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adve...	07/01/2019	Active	10068074
10068090	LUFTHANSA TECHNIK AG	REV. 1		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-231/-232/-233/-251N A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Wireless (WiFi) Infotainment SystemThis modification activates a Wireless (WiFi) Infotainment (CabinDistribution) System.The revision allows for the eligibility of the A320-251N (A320neo) tothe existing STC 10068090.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Compliance Check List – CCL44-18/06M Rev 4 dated 19.MAR.2019 CCL44-19/02M Rev 1 dated24.Jun.2019- Aeroplane Flight Manual – A-00-18/103-AFM Issue 01 Rev 01 dated03.MAY.2019- Instruction of Continued Airworthiness – A-00-18/103-ICA Issue 02 Rev01 dated-...	The following design changes (pre-modifications) need to beapproved andinstalled on the aircraft prior to the installation of the subjectdesign change: Structural and electrical provisions for the Wireless (WiFi) Infotainment System according to Supplemental Type DefinitionDocument STDD44-18/04; Sof...	27/06/2019	Active	10068090
10068097	DART AEROSPACE Ltd.		TCCA STC SH18-49	EC135 T2+ EC135 T2 EC135 T1 EC135 P2+ EC135 P2 EC135 P1	Installation of Dart Aerospace Ltd. crosstubes in accordance with MasterDocument List MDL-D135-1027 with reference to TCCA STC SH18-49.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 Amendment 4 forthe following paragraphs: 27.1; 27.2; 27.21; 27.25; 27.27; 27.29; 27.75;27.231; 27.241; 27.251; 27.30...	- Airworthiness Compliance Report ACR-D135-1027-1 Revision A- Master Document List MDL-D135-1027 Revision B- Installation Instructions IIN-D135-1027 Revision C- Instructions for Continued Airworthiness ICA-D135-1027 Revision 0or later revisions of the above listed document(s) approved/accepted onbeh...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/12/2018	Active	10068097
10068104	STG AEROSPACE GERMANY GmbH	REV. 1		757-200/-300 737-600/-700/-800/-900/-900ER 737-100/-200/-300/-400/-500	REPLACEMENT PSU LENS ASSEMBLYRevision 1: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STG AEROSPACE LTD AEROPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1016-FMS-01Revision IRSTG AEROSPACE LTD INSTRUCTIONS FOR CONTINUED AIRWORTHINESS No.SG-1016-ICA-01 Revision IRSTG AEROSPACE LTD MASTER DATA LIST No. SG-1016-MDL-01 Revision IROr later revisions of the above listed document(s) approved/accep...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/02/2021	Active	10068104
10068135	CENTERVOL MAINTENANCE SL			SEE EASA APPROVED MODEL LIST	Installation of MDU001-03 recording unit for operational purposes.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 Amdt 4 for theaffected partsThe requirements for environmental protection and the associatedcertified noise and/ oru...	For applicability of the following documents refer to EASA approved AMLMDWL-2012 “Master Drawing List", Rev 01, dated 21 November 2018FMS-2012-1 “Flight Manual Supplement”, Issue 01 Rev 00, 10 July 2018ICA-2012-1 “Instructions for Continued Airworthiness”, Issue 01 Rev 00,dated 07 June 2018ICA-2012-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/12/2018	Active	10068135

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068155	STC TWENTY ONE LIMITED	REV. 2	CAA UK RESPONSIBILITY	SEE EASA APPROVED MODEL LIST	Introduction of ADS-B Out as per CS-ACNSThis AML STC introduces ADS-B Out functionality at the aircraft leveland demonstrates compliance to CS-ACNS for the European 2020 Mandate.This revision (at revision 2) introduces a new avionics equipmentconfiguration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 20 and CS ACNS Subpart D (Section 2<(>,<)> 3 & 4)The requirements for environmental protectionand the associatedcertified noise and/ or emissions levels o...	Aircraft Maintenance Manual Supplement, Doc Ref: S21.AMMS-0015 issue 5Aircraft Flight Manual Supplement, Doc Ref: S21.FMS-0152, Issue 2Approved Model List, Doc Ref: S21.AML-002, Issue 1Master Document List (MDL), Doc Ref: S21.MDL-1415, Issue 5or later revisions of the above listed document(s) approv...	None	13/02/2020	Active	10068155
10068156	AEROTEC & CONCEPT	REV. 1		A321-252N/-253N/-271N/-272N A321-213/-231/-232/-251N A321-111/-112/-131/-211/-212 A320-271N/-272N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216	MOD AE17144 : AEROSAT F-310 External Antenna (KU BAND) and SystemInstallationsRevision 1: Correction of pre-requisite modification AE17026 instead ofAE17126.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-0301-006: Vibration and buffetingcompliance criteria for large radome or antenna fairing on the fuselage.The requirements for environm...	- Master Data List document N° AE17144MDL Revision 0 dated 17 December2018;- Instructions for Continued Airworthiness document N° AE17144ICARevision 0 dated 07 December 2018;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Aerotec Concept MOD AE17026 (EASA STC 10062749 REV. 1) and MOD AE17143(Minor Change) are pre-requisite for this design change.	08/01/2019	Active	10068156
10068157	ADAC LUFTFAHRT TECHNIK GmbH			EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of ADS-B IN/OUT System in accordance with Master DocumentList EC135-08679-001-LMD	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): Continuity Requirements for Elementary Surveillance (ELS)and ADS-B functions CS ACNS.D.ELS.045,CS ACNS.D.ADSB.105.The following paragraph(s) at a later ame...	- Rotorcraft Flight Manual Supplement EC135-08769-025-MFS Revision 0;- Master Document List EC135-08679-001-LMD Revision 0;- Compliance Summary EC135-08769-027-RCS Revision 2;- Maintenance Manual Supplement/ICA EC135-08769-023-MMS Revision0;or later revisions of the above listed document(s) approve...	Applicable to CDS/CPDS cockpit variants only.A fully functional and approved dual installation of Garmin GTN650/750,as well as a suitable XPDR-antenna must have been already installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repa...	20/12/2018	Active	10068157
10068179	CONCORDE BATTERY CORPORATION		FAA STC ST01520WI	EMB-145ER, EMB-145LR EMB-135LR, EMB-145, EMB-145EP EMB-135BJ, EMB-135ER	Installation of the Concorde RG-442 VRSLA Battery and Temperature Sensorin place of the original Nickel-Cadmium Battery	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01520WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Drawing List, Drawing No. 5-0276, Revision NC, dated4 June 2008,or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2018	Active	10068179
10068183	ROCKWELL COLLINS, Inc.		FAA STC ST01185WI-D	SEE FAA AML	Modification of an existing FAA approved Collins HF Communication Systemwith HFS-900D Receiver/Transmitter, CPN 822-0990-002/-003, and CPL-920DHF Antenna Coupler, CPN 822-0987-002/-003, to a Collins HF CommunicationSystem with a HFS-900D Receiver/Transmitter, CPN 822-0990-004, andCPL-920D HF Antenna...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01185WI-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	Collins Drawing Index as listed on AML No. ST0I185WI-D, Revision -, orlater FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	21/12/2018	Active	10068183
10068184	ROCKWELL COLLINS, Inc.		FAA STC ST02217AT-D	767-200	Installation of Collins IDC-900.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02217AT-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	TIMCO Master Drawing List 98T0126L084, Revision E, dated 14August 2001,or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/12/2018	Active	10068184

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068185	SCANDINAVIAN AVIONICS DESIGN ApS			SEE EASA APPROVED MODEL LIST	MST-70B ADS-B UpgradeThis AML STC consists of replacement of existing dual MST-67A XPDR unitby dual MST-70B XPDR (compliant to European 2020 Mandate) andinstallation of an ADS-B 1FAIL/ADS-B 2 FAIL Annunciator or,alternatively, the Gables G7534 Control panel may be used for ADS-B Failindication. An...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amendment 2 and CS ACNS Subpart DThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product are...	Aircraft Flight Manual Supplement, Doc Ref: 2111293-AM AInstructions for Continued Airworthiness, Doc Ref: 2111293-CAorlater revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	21/12/2018	Active	10068185
10068192	MORSON PROJECTS LIMITED	REV. 1	CAA UK RESPONSIBILITY	B200GT B200CGT	Approval of Morson Projects Limited Change MP0014A for the introductionand relocation of various antennas to support the later installation ofa SATCOM System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Morson Project Limited Modificationreference MP0014A.Instructions for Continued airworthiness (ICA) in accordance with Morsondocument ref MPL-C-02-AW0106 Issue 1 dated November 2018.There is no Flight ManualChange associated with this modification.OSD data is unaffec...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/01/2019	Active	10068192
10068216	FOKKER SERVICES B.V.			757-300 757-200PF 757-200	ADS-B OUT on the Boeing 757 / This change introduces ADS-B capability onthe Boeing 757 aircraft. The ATC transponders will be changed and theywill interface with a suitable position sensor.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment:Initial Issue of CS-ACNS: CS-ACNS.D.AC.10; CS-ACNS.D.AC.015;CS-ACNS.D.AC.020; CS-ACNS.D.AC.025; CS-ACNS.D.AC.030;CS-ACNS.D....	- The change is defined with Issue 1 of the Master DocumentListB757-ADSB-OUT-MDL-0001- The aircraft shall be operated in accordance with Revision 1 ofAirplane Flight Manual Supplement B757-ADSB-AFM-S-001or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/01/2019	Active	10068216
10068217	FOKKER SERVICES B.V.	REV. 1		747-400/ 747-400F	ADS-B OUT on the Boeing 747 / This change introduces ADS-B capability onthe Boeing 747 aircraft. The ATC transponders will be changed and theywill interface with a suitable position sensor.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Initial Issue ofCS-ACNS: CS-ACNS.D.AC.10; CS-ACNS.D.AC.015; CS-ACNS.D.AC.020;CS-ACNS.D.AC.025; CS-ACNS.D.AC.030;CS-ACNS.D....	The change is defined with Issue 1 of the Master Document ListB747-ADSB-OUT-MDL-0001;The aircraft shall be operated in accordance with Revision 1 of AirplaneFlight Manual Supplement B747-ADSB-AFM-S-001or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/01/2019	Active	10068217
10068267	AERODESIGN AND MANUFACTURINGTECHNOLOGY S.L.			ATR 72-212 A	LOPA CONFIGURATION CHANGE FROM 70 TO 72 PAX ATR72.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List (MOBT-1721-MDL, Rev03);- Weight and Balance Manual Supplement (MOBT-1721-WBMS01, Rev00);- Illustrated Parts Catalog Supplement (MOBT-1721-IPCS01, Rev00);or later revisions of the above listed documents approved by EASA.	Limited to MSN 982.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of the product.	09/01/2019	Active	10068267

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068273	TUI AIRLINES BELGIUM N.V.			737-8	Wireless IFE system installation on B737MAXThe modificationconsists in the installation of a server and CWAPS. Thesystem is operated by means of a control panel in the cabin.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instruction for Continued Airworthiness: Doc no. JAF-DOA-ICAR-44M-0003REV 00;Airplane Flight Manual Supplement: Doc no.AFMS-JAF-DOA-44M-0003 REV 00;Master Data List: Doc no. JAF-STC-0002-0001 REV00 – JAF-DOA-CJR-44M-0003REV00;or later revisions of the above listed document(s) approved/acceptedunder...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/01/2019	Active	10068273
10068296	ODA AVIATION GROUP, LLC		FAA STC ST09876AC	737-800	Installation of an equipment rack structure in the forward cargocompartment on Boeing 737-800 aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	ODA Aviation Group, LLC Master Drawing List No. R1136S0301,"EquipmentRack Installation (Equipment Provisions}", Revision A, dated 1 May 2017,or later FAA approved revision.Required instructions for continued airworthiness are contained inDocument No. R1136S0601, Revision IR, dated 24 October 2016 o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/01/2019	Active	10068296
10068301	MARSHALL OF CAMBRIDGE AEROSPACELIMITED			A318-112	Master Minimum Equipment List amendments for the Airbus A318 “Elite”Auxiliary Centre Tank System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-MMELInitial Issue.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and rem...	Certification Summary CS/A318(2424)/17/0061 Rev.2, dated 08/10/2018;MMEL Supplement MMEL/A318 (1778)/10/0968 Rev.1, dated 30/06/2017;or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	EASA STC 10035677 Rev.4 shall be embodied on the aircraft.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the produ...	11/01/2019	Active	10068301
10068320	ETIHAD AIRWAYS ENGINEERING L.L.C.			SEE EASA APPROVED MODEL LIST	Low Frequency ULD InstallationReferring to EASA mandate Commission Regulation (EU) 2015/2338 dated 11Dec 2015, on underwater beacon installation prior 01-Jan-2019. Themodificationinvolves the installation of Dukane Seacom DK180 LowFrequency Underwater Locating Devices (90 days, 8.8 KHz, one unit pe...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-0318-004 Issue 1 Non-rechargeable LithiumBattery Installations.- CS 25 at Amdt.21 for the affected area.The requirements for environmental pr...	- Master data list E00-18250531-DL01 Issue 8 dated 13 Jan 2019;- MMEL Supplement E00-18250531-PA11 Issue 3 dated 09 Jan2019;- MMEL Supplement E00-18250531-PA04 Issue 3 dated 09 Jan 2019;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/01/2019	Active	10068320
10068342	FOKKER SERVICES B.V.	REV. 1		747-400F	Non-activated GNSS Installation on 747Introduction of a Dual Non-Activated GNSS Unit and Antenna Installationon Boeing 747-400FRev. 1 (CPR/ CRR-0441) introduces corrections to the ALS supplement.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25, initial issue: 25.301(a); 25.303; 25.307(a); 25.321(a)(b)(c); 25.471 (a).The requirements for environmental protect...	The change is defined through Issue 1 of Fokker Services Master DataList document B747-GNSS-MDL-0001The aircraft shall be maintained in accordance with Issue 5 of theInstructions for Continued Airworthiness document B747-GNSS-ICA-S-001(Note: the ICA document issue index has been updated in relationc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product	08/03/2021	Active	10068342

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068365	AIRBORNE TECHNOLOGIES GmbH	REV. 1		T206H 206H, T206H 206H	STC-AT-130, Cessna 206 – Survey ConfigurationModification of the cabin layout to a survey cabin configuration. Thenew survey cabin configuration consists of three different surveyequipment configurations (called as Configuration 1, 2, and 3) which areinstalled above the hatch, in the baggage compart...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Approval Sheet (MDL), Doc. No.: STC-130-0-AS, Rev. 3Flight Manual Supplement, Doc. No.: STC-130-G-AFM, Rev. 3Maintenance Manual Supplement, Doc. No.: STC-130-G-AMM, Rev. 2Installation Instructions, Doc No.: STC-130-G-II, Rev. 3Or later revisions of the above listed document (s) approved/ acceptedunder...	The following change must be accomplished prior to the incorporation ofSTC-AT-130: CAA.21NE2.00081 – Straight Flight, Modification of aircraftfloor to create a 20 inch camera holePrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair an...	06/11/2020	Active	10068365
10068390	FACC OPERATIONS GmbH			A321-213/-231/-232/-233 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-112/-121/-122	Passenger Luggage Space Upgrade for A3SA Classic OHSCThis change replaces the overhead stowage compartments doors with newdoors with a different shape to increase the overall volume of theoverhead stowage compartment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 Amendment 20: CS25.1; CS25.301; CS25.303; CS25.305; CS25.307;CS25.341; CS25.365; CS25.561; CS25.601; CS25.603; CS25.6...	The change is defined with initial issue of FACC Master Data ListCDO_1_0007_19-0068_Rev_NCor later revisions of the above listed documents approved by EASA.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/01/2019	Active	10068390
10068413	AIRBUS S.A.S.	REV. 2		A321-271NX A321-253NX A321-252NX A321-251NX	VIASAT KA BAND OAE INSTALLATIONThis modification covers thedefinition and installation of "OutsideAircraft Equipment (OAE)" and associated wirings (from the OAE to theskin feed through connectors) Activation of the Wifi in cabin will bedealt later on under Minor Modification process.Revision 1: Adm...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Certification Summary Report ref. AIS-AJA-18037 Issue 3, dated 10thJan 2019- Modification Approval Sheet ref. MAS AI0050 issue 1, dated 10th Jan2019- Airplane Flight Manual Supplement: AFM-S MOD AI0050 Rev.00, dated 1stSep 2018- Maintenance Planning Document Supplement MPD-S: MPD-S MOD AI0050Rev.0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/11/2021	Active	10068413
10068416	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 1	FAA ST02635LA	SEE EASA APPROVED MODEL LIST	Installation of ACSS NXT-600 Mode S Transponder for ADS-B Out withOptional ACSS NXG-900 GPSThis AML STC installs the ACSS NXT-600 Mode-S Transponder with ADS-B Outfunctionality and optionally installs the ACSS NXG-900 GPS as a positionsource for ADS-B Out.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-ACNS Subpart D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels...	- Airplane Flight Manual (AFM), Doc Ref: 8001154-900, Rev A;- Instructions for Continued Airworthiness, Doc Ref: 8001154-600, Rev Afor the NXT-600 and 8001154-610 Rev – for the NXG-900;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Techni...	None	23/01/2019	Active	10068416
10068417	RHEINLAND AIR SERVICE GmbH	REV. 2		PA-46R-350T (MATRIX) PA-46R-350T PA-46-500TP, PA-46-600TP PA-46-500TP (MERIDIAN) PA-46-350P (MIRAGE) PA-46-310P, PA-46-350P PA-46-310P	Installation of electrical Cabin Floor Heating Panels in accordance withEngineering Work Order EW-1999-000000.Revision to account for the transfer from airplus engineering GmbH toRheinland Air Service GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23, Amdt. 4 -23.1, 23.29, 23.303, 23.305, 23.307, 23.337, 23.561, 23.601, 23.603,23.605, 23.613, 23.853, 23.863, 23.8...	Airplane Flight Manual Supplement PO-1999-000000, Issue 2-0, dated 21January 2019<(>,<)>or later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product	23/07/2025	Active	10068417

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068437	SPAES GmbH & Co. KG			PA-46-350P	Iridium Antenna Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List Doc. No. MDL-046-147-53-01, Issue 00, Date30.11.2018Instructions for Continued Airworthiness Doc. No. ICA-046-147-53-01,Issue 00, Date 30.11.2018or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	S/N 4636011 only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	23/01/2019	Active	10068437
10068480	NORTHERN AVIONICS S.R.L.			LEARJET MODEL 45	KA 96 WAAS GPS ANTENNA INSTALLATION	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Iaw. Northern Avionics MDL NAV0610, Rev. 0To be maintained iaw. Northern Avionics ICA-NAV0610, Rev. 0To be installed iaw. II-NAV0610, Rev 0or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	None	25/01/2019	Active	10068480
10068482	ETIHAD AIRWAYS ENGINEERING L.L.C.	REV. 1		777-300ER	BOEING 777-300ER CABIN RECONFIGURATIONREV 0 : Certifies CONFIGURATION 1REV 1 : Certifies CONFIGURATION 2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List, Ref. EB7-18250500-DL02 Issue 3;or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Installation of this STC on an aircraft under EASA jurisdiction requiresan EASA approved Cabin Configuration.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce n...	06/05/2019	Active	10068482
10068485	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	A321-211	44 B/C<(>,<)> 106/100 Y/C<(>,<)> Passenger Seat Reconfiguration	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA Approved: H4 Aerospace Instructions For Continued Airworthiness No.H4AICA022 Issue 1EASA Accepted: H4 Aerospace Modification Summary No. H4A1896 Issue 2or later revisions of the above listed document (s) approved/ acceptedunder the EASAsystem.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/01/2019	Active	10068485
10068513	365 AEROSPACE DDS LIMITED	REV. 2		ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 LR, ERJ 190-100 SR ERJ 190-100 IGW ERJ 190-100 ECJ ERJ 170-200 STD ERJ 170-100 STD ERJ 170-100 LR, ERJ 170-200 LR	Change to introduce New Cabin Interior ComponentsRev. 2: Transfer of STC from 365 Aerospace Ltd. to 365 Aerospace DDS Ltd	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 at Amendment 21:25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.341, 25.471, 25.561,25.601, 25.603, 25.605, 25.607...	- 365 Aerospace Instructions for Continued Airworthiness – ‘Change toIntroduce New Cabin Interior Components, Configuration 1’ ICA-0629-001Issue A;- 365 Aerospace Instructions forContinued Airworthiness – ‘Change toIntroduce New Cabin Interior Components, Configuration 2` ICA-0629-002Issue A;- 365o...	Refer to 365 Aerospace Master Data List No. MDL-0629 for configurationstandards that are a pre-requisite for this modification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	05/08/2019	Active	10068513
10068520	LUFTHANSA TECHNIK AG			SEE EASA APPROVED MODEL LIST	Installation of Media Trolley for:- ground charging configuration- in-flight charging configuration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition: D-127 “PED charging trolley”.- The following paragraph(s) at a later amendment: CS25 amdt12 for25.853(a), CS25 amdt 5 for 25.1301 (a)(1), CS 25 amdtT...	Description of Change ASK01-44 rev 3Master Data List: see AML table in annexOperational Requirements document C-ACE815-OR rev 0User Guide document C-ACF461-UG-001 rev 0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- This approval is limited to installations in ATLAS galleys- This approval is limited to a maximum of three (3) Media Trolleyscarried simultaneously per galley- The PED types approved for use in the Media Trolleys are limited tothose described in document ASK01-44Prior to installation of this chang...	30/01/2019	Active	10068520

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068528	RUAG AG	REV. 2		PC-12, PC-12/45, PC-12/47 PC-12, PC-12/45 PC-12/47, PC-12/47E	Installation of Dual Garmin GNS-530 COM/NAV/GPS System Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Engineering Order TSA PC12-34.60.02EO, Revision Aor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approval design data referred to in the paragraph description.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/e...	01/02/2021	Active	10068528
10068537	SOCIETE AIR FRANCE S.A.	REV. 2		A330-223F/-243/-243F A330-201/-202/-203/-223	A330-200 BEST – Cabin rearrangement and installation of an in-flightentertainment system.Rev. 2 updates the "AssociatedTechnical Documentation" Sectionincluding CAS rev 13 covering Minor Change dated 16 Oct 2024.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-4312-002 Non-rechargeable lithium batteryinstallations.The requirements for environmental protection and the associatedcertified noise and/ oru...	Air France Change Approval Sheet CAS-A330-16-006 Revision 13 dated 16October 2024Air France Certification Program CP-A330-16-006 Revision 2 dated 30January 2019Air France Cabin Crew Operating Manual Supplement CCOMS-A330-16-006-001Revision2 dated 16 October 2024Air France Master Minimum Equipment L...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.,,,,	20/11/2024	Active	10068537
10068540	AERO-DIENST GMBH	REV. 1		BD-100-1A10	Installation of a SDR Gateway Router including WIFI activation.The existing ICS-200 / ICS-220 Iridium Satcom Transceiver is replaced bythe Satcom Direct Gateway Router (SDR). The SDR Gateway includes a dualchannel Iridium transceiver and a3G / 4G module for high speed interneton ground. A interface...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- MDL - 20300-CL.DC-101 rev 00- ICA - 20300-CL.DC-105 rev 00- AFMS - 20300-CL.DC-106 rev 00or later revisions of the above listed document(s) approved under theEASA system.	Limited to the following aircraft: 20124, 20125, 20128, 20134, 20139,20143, 20146, 20148 and all subsequent serial numbers.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wi...	29/03/2019	Active	10068540
10068542	AERSALE, Inc.	REV. 1	FAA STC ST02980NY	737-600, 737-700, 737-800	Reticulated Polyurethane Foam in B737NGInstallation of an inherently electrostatically conductive ReticulatedPolyurethane Foam as an aircraft Ignition Mitigation Mean, in the centerwing tank of Boeing 737-600, 737-700 and 737-800 model aircraft.Revision 1: Transfer of STC from Dassault Aircraft Serv...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: EASA CS 25 Amdt 10,25.29, 25.301(a)(b), 25.303, 25.307(a), 25.321(a), 25.333, 25.343(a),25.561(a). 25.601, 25.603, 25.605(...	-Master Data List B737NG-D0032-005, Revision IR, dated 03 March 2016-Instructions for Continued Airworthiness B737NG-D0032-155, revision B,dated 17 March 2018-Airplane Flight Manual Supplement B737NG-D0032-150, Revision IR, dated03 March 2016or later revisions of the above listed document(s) approve...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/09/2019	Active	10068542
10068551	AEROTEC & CONCEPT			B300, B300C	Antennae relocation, ballast and cabin arrangement for subsequentinstallation of mission system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, AE17120MDL, Rev. 0Airworthiness LimitationSection (ALS) of the ICA AE17120ICA, Rev. 2or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	None	01/02/2019	Active	10068551
10068553	HONEYWELL INTERNATIONAL INC.	REV. 1	FAA ST02664LA	757-200/ 757-200PF/ 757-300	Installation of Honeywell RMA-55B Multi-Mode Receiver.Rev 1: “Installation of Honeywell Multi-Mode Receivers (MMR).”Configuration 1: installation of 3 RMA-55B MMR part number (P/N) 066-50029-1201 & OPS P/N HNR58-2601-0801 and 2 GNSS antennas P/NAT575-343H/ 071-50029-5510Configuration 2: installation o...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except whereamended by additional or later amendments:CS 25 at amdt 00 for 25.303, 25.337(a)(b)(c)(1)(2), 25.561(b)(3),25.601, 25.1307(e), 25.1431(a)(c)CS 25 at amdt 01 for 25.305 (a)(b)(1)(2)(3), 25.30...	1. Honeywell Master Drawing List 756-0265-001, revision B or later FAAapproved revision.2. Honeywell Instructions for Continued Airworthiness (ICA) documentnumber 756-0265-800, revision - or later or later FAA approved revision.3. Honeywell Instructions for Continued Airworthiness (ICA) documentnumb...	Configuration 1: The airplane must be previously equipped withInstrument Landing System in accordance with Boeing Service Bulletin757-34-0458 or equivalentConfiguration 2: The airplane must be previously equipped with:• Installation of triple MMR (Honeywell RMA-55B MMR, 24-Channel, partnumber 066-50...	18/03/2020	Active	10068553

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068575	CONCORDE BATTERY CORPORATION	REV. 1	FAA STC SR02588LA	AS 332 L1/ AS 332 L2/EC 225 LP AS 332 C/ AS 332 C1/ AS 332 L	Replacement of existing SAFT main Battery models 40208-1, 40208-5,40308-1 or 40308-5 with Concorde Battery Corporation Valve RegulatedLead Acid (VRLA) Battery models RG-332-1 or RG-332-2.Rev. 1 corrects typographical errors in the description of the STC.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Data List, 5-0512, Revision C, dated 1 March 2016, or laterrevisions of the above listed document (s) approved/accepted on behalf ofEASA in accordance with the Technical Implementation Procedures of EU/USA Bilateral Agreement.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/06/2021	Active	10068575
10068585	HONEYWELL INTERNATIONAL INC.		FAA STC ST02665LA	757-200PF 757-200	Installation of Honeywell TRA-100B Mode S Transponders withADS-B Out	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02665LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Honeywell Master Drawing List 756-0263-001, revision -, dated 24January 2018 or later FAA approved revision.2. Honeywell Airplane Flight Manual Supplement (AFMS) document number756-0263-810, revision -, dated 21 November 2017, or later FAA approvedrevision, OR Honeywell AFMS document number 756-0...	The installation of Honeywell EASA STC 10068553 must be incorporated onthe aircraft prior to or at the time of this STCinstallation.	05/02/2019	Active	10068585
10068606	BOGGI S.R.L.			AS 350 BB, AS 350 D AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA	External Mirrors System (Mod N. 350P025)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	350P02500-Mdw-01 “Master Drawing List”, dated 04th February2019350P02500-Mdl-02 “Master Document List”, dated 04th February 2019350P02500-FMS-02 “FMS Mirror Installation on AS350Helicopter”, dated04th February 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA s...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/02/2019	Active	10068606
10068611	S-TEC CORPORATION		FAA STC SA09750DS	PA-46-500TP/ PA-46R-350T PA-46-310P/ PA-46-350P	Installation of an S-TEC 01326 Digital Flight Control System (DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Data List No. ST-967-MDL-0001, Revision A, dated 18 September2018<(>,<)> or later FAA approved revision.2. Airplane Flight Manual Supplement, ST-967-AFMS-0001, Revision -,dated 20 September 2018 or later FAA approved revision.3. Instructions for Continued Airworthiness, ST-967-ICA-0001, Re...	1. Also eligible on models PA-46-310P and PA-46-350P when modified perSTC EASA.IM.A.S.02158.2. Prior to installation ofthis design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadvers...	05/02/2019	Active	10068611
10068636	PRO STAR AVIATION, L.L.C.		FAA STC ST00391BO	SEE FAA 05649-AML-101, REV. B	Installation of a Honeywell CNX-900 Cabin Network Accelerator andcertification for portable electronic device (PED) tolerance.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Pro Star Aviation Installation Data List 05649-IDL-101, Revision IR,dated 17 December 2018, or later FAA approved revision.2. Airplane Flight Manual Supplement (AFMS) listed inFAA Approved ModelList 05649-AML-101, Revision B, dated 30 November 2018, or later FAAapproved revisions.3. Pro Star Avi...	1. Prior to installation of this design change it must be determinedthat the interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthinessof the product.2. The STC is valid for aircraft types and mo...	06/02/2019	Active	10068636

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068642	LUFTHANSA TECHNIK ENGINE SERVICES,INC.		FAA STC ST11057SC	737-700	Installation of an Executive Style Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Compliance Data List DL1855M00, Revision F, dated 1 July2013 orlater FAA approved revision.2. Airplane Flight manual Supplement 1330021090, Revision 13, dated 24June 2013 or later FAA approved revision.3. Instructions for Continued Airworthiness 1330050090, Revision C,dated 20 June 2013 or later...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/02/2019	Active	10068642
10068680	AVIONIK STRAUBING ENTWICKLUNGS GmbH			C90A, C90GT, C90GTI	Installation of Antenna Comant CI 401-490	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23, Amendment 4 -29, 251, 301, 303, 305, 307, 337, 365, 561, 571, 573, 575, 601, 603,605, 607, 609, 611, 613, 625, 843,...	- Instructions for Installation ASR-2018-019-IFI-10-00, Rev. 00- Instructions for Continued Airworthiness ASR-2018-019-ICA-11-00, Rev.00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Final compliance demonstration must be provided in the frame of theinstallation approval for the equipment to be servedby the antennabeing subject of this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevious...	08/02/2019	Active	10068680
10068682	FOKKER TECHNIEK B.V.	REV. 1		737-800	VIP Refurbishment RTAF2Revision 1: Transfer of STC from Fokker Services B.V. (EASA.21J.059) toFokker Techniek B.V. (EASA.21J.667)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement: B738-RTAF-AFM-S-001, Revision 6;Instructions for Continued Airworthiness Supplement:SE-794, Revision 9;Compliance Record Report: B737-RTAF2-CRR-0001, Rev. 1;Master Minimum Equipment List: B738-RTAF-MMEL-S-001, Revision 6;or later revisions of the above listed docu...	MSN 62445.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthinessof the product.	05/12/2019	Active	10068682
10068683	GULFSTREAM AEROSPACE Ltd.	REV. 1	CAA UK RESPONSIBILITY	GIV-X	JetWave KA Band SATCOM System Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- GULFSTREAM AEROSPACE Ltd. Instructions for Continued Airworthiness No.GAeL 18-29-ICA-501 Rev - (JetWave KA HSD Systemand Fin Cap Radome)- GULFSTREAM AEROSPACE Ltd. Instructionsfor Continued Airworthiness No.GAeL 18-29-ICA-503 Rev - (Fin Cap Radome)- GULFSTREAM AEROSPACE Ltd. Aircraft Flight Manu...	None	13/02/2019	Active	10068683
10068688	ALAMO ENGINEERING GmbH	REV. 1		EMB-505	Approval of the installation of Honeywell Aspire 200 SATCOMsystem andthe Honeywell “GoDirect”™ Router, including relocation of existingIridium Satcom Antenna.Revision 1: Transferto ALAMO Engineering GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	To be installed according to document listed in Master Document ListMDL131Z001 issue A Dated 07th February 2019;To be operated according to EASA approved AFM supplementAFMS014N231 Z0001 issue A dated 10th January 2019;To be maintained according to AMM Supplement AMMS014N231Z0001 issue Adated 15th Jan...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2024	Active	10068688

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068692	BRITISH AIRWAYS PLC		CAA UK RESPONSIBILITY	A320-232, A321-231 A318-112, A319-131	Installation of Low Frequency Underwater Locator Beacon	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 Non-rechargeable Lithium BatteryInstallations.The requirements for environmental protection and the associatedcertified noise and/ or emissi...	British Airways Master Data List No. BA-320-23-0011-MDL Revision 00<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/02/2019	Active	10068692
10068702	GULFSTREAM AEROSPACE Ltd.	REV. 2	CAA UK RESPONSIBILITY	GIV-X, GV-SP	Latitude Technologies Satellite Data System Installation (FANS 1/A overIridium)The revision 1 corrected typographical error in AssociatedDocumentation.The revision 2 corrects typographical error of the Revision 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- GULFSTREAM AEROSPACE Ltd. Instructions for Continued Airworthiness:GAeL18-15-ICA-04 Rev - (GIV-X, FANS over Iridium SATCOM)- GULFSTREAM AEROSPACE Ltd. Instructions for ContinuedAirworthiness:GAeL18-15-ICA-05 Rev - (GV-SP, FANS over Iridium SATCOM).- GULFSTREAM AEROSPACE Ltd. Aircraft Flight Manua...	Refer to applicable GULFSTREAM AEROSPACE Ltd. Design ChangeRecord forprerequisite modifications.	16/04/2019	Active	10068702
10068718	CONCORDE BATTERY CORPORATION		FAA STC ST04366AT	680 (SOVEREIGN)	This STC is a replacement of the original equipment nickel cadmium mainbatteries manufactured by Saft or Marathon with Concorde valve regulatedlead acid main batteries.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04366AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Concorde Master Drawing List No. 5-0576, Revision B, dated 20 March2017, or later FAA approved revisions.2. Instructions for Continued Airworthiness Document (ICA), ConcordeBattery Corporation No. 5-0577, No Revisions, dated 5 February 2016, orlater FAA accepted revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/02/2019	Active	10068718
10068719	CONCORDE BATTERY CORPORATION		FAA STC ST04273AT	SEE FAA APPROVED MODEL LIST	Replace Original Main Battery Connector with Concorde Connector, PartNumber 4000.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04273AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Concorde MDL 5-0569, Revision B, Dated 26 April 2016, orlater FAAapproved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	12/02/2019	Active	10068719
10068724	HELI AUSTRIA GmbH	REV. 1		AS 332 L, AS 332 L1 AS 332 L1 AS 332 L AS 332 C, AS 332 C1 AS 332 C1 AS 332 C	Installation of Garmin GTN 650 NAV1 / COM1 / GPS System into AirbusHelicopters AS332 L / L1 / C / C1Reason for Rev. 1: installation of the new version of the GTN650, theGTN650 Xi	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS ACNS initial issue:CS ACNS.B.VCS.001, CS ACNS.B.VCS.010, CS ACNS.B.VCS.020, CSACNS.B.VCS.025, CS ACNS.B.V...	Master Document List, Doc. No. HAU-D-046-001, Rev. 1Rotorcraft Flight Manual Supplement, Doc. No. HAU-D-046-005, Rev. 1Installation Manual, Doc. No. HAU-D-046-004, Rev. 1Instructions for Continued Airworthiness, Doc. No. HAU-D-046-006, Rev. 1Or later revisions of the above listed document(s) approve...	This change is limited to VFR day and night operation.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product....	16/09/2022	Active	10068724
10068725	ALOFT AEROARCHITECTS	REV. 3	FAA ST04051NY	737-8, 737-9 737-8	Ka SATCOM Antenna System InstallationRev. 1 adds the 737-9 model to the aircraft applicability.Rev. 2 adds a new 737-8 configuration to the STC.Rev. 3 corrects typo in Technical Associated Documentation section.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): B-3301-001 Vibration and buffetingcompliance criteria for large external antenna installation.The requirements for environment...	Master Data Index List (MDIL) 1292339<(>,<)> rev 022, datedSeptember21, 2023ICA ViaSat Document No. 1291340, rev 006, dated January 1, 2022 forconfiguration 1, 2 andICA ViaSat Document No. 1432579, rev 001, dated March 17, 2023 forconfiguration 3EWIS ICA ViaSat Document No. 1291344, rev 002, datedc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/04/2024	Active	10068725

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068727	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 350 B3	Installation of TRAKKA A800 Searchlight (Design DefinitionAHUK/3503185-101)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement AHUK/350-FMS-122 “Incompatibilities of usebetween AHUK Optional Equipment Items “Issue 1;- Flight Manual Supplement AHUK/350-FMS-113,” Introduction of TRAKKAA800 Searchlight”, issue 0;- Instruction of Continued Airworthiness ICA/3503185-01, Issue A, dated30/10/2018;or late...	Refer to AHUK/350-FMS-122 for identified incompatibilities.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the prod...	12/02/2019	Active	10068727
10068730	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04247AT	A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303 A330-243, A330-243F A330-223, A330-223F A330-201, A330-202, A330-203	Installation of an Avionics Support Group Constant FrictionMount(cfMount) and Cradle with an Integrated Power Supply (IPS) on AirbusA330 Series Aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04247AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Avionics Support Group, Inc. Master Data List 214255-MDL, Rev. H,dated 29 November 2016, or later FAA approved revision.2. Instructions for Continued Airworthiness Document 214255-ICA dated 21November 2016 Rev. F or later approved revision. 3. Airplane Flight Manual Supplement 215289-FMS is a requ...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/02/2019	Active	10068730
10068744	BOOST HUMAN EXTERNAL CARGO SYSTEMS		TCCA SH18-34 ISSUE 2	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Human External Cargo System – Provision Only	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions, INSTALL-B1805-DHS, Rev. A, dated11 February2019Instructions for continued Airworthiness, ICA-B1805-DHS, Rev. A, dated11 February 2019Flight Manual Supplement, FMS-B1805-DHS, Rev. A, dated 11 February 2019or later revisions of the above listed document(s) approved/ accepted...	NHEC operations are enabled by removal of secondary hook. All HECrelated controls shall be INOP.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffe...	13/02/2019	Active	10068744
10068757	PIEDMONT PROPULSION SYSTEMS, L.L.C.			14SF-5, 14SF-7, 14SF-11 14SF-11E, 14SF-15, 14SF-23	FAA PMA PQ04267CE Supplement No. 4: 14SF - Propeller Blade Sheaths – Introduction of Blade Sheath Part Numbers (P/N) PPS-1007556-2 for14SF-5, 14SF-7 and PPS-1007556-3 for 14SF-11, 14SF-11E, 14SF-15, 14SF-23in Replacement of Original Equipment Manufacturer (OEM) P/N 1007556-2and 1007556-3.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Federal Aviation Administration – Parts Manufacturer Approval PMA No.PQ04267CE, Supplement No.: 4, Date: August 4, 2018Part Specific Certification Plan DOCUMENT NO: PPS-1007556-2-PartSCP,REVISION: E, Release Date: 07/19/18Part Specific Certification Plan DOCUMENT NO: PPS-1007556-3-PartSCP,REVISION:...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/02/2019	Active	10068757
10068768	RECAERO			A320-251N A320-214	Cabin reconfigurationRearrangement of seats from 150 YC to 162 YC - Installation of forwardwindscreens and aft doghouses - Relocation of 1 exit sign and emergencyequipment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master data list RCP005MDL001 issue 1- Aircraft manual Supplement RCP005AMS001 issue 3or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/02/2019	Active	10068768

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068771	AERSALE, Inc.	REV. 1	FAA STC ST04011NY	757-200PF 757-200	ACSS ADS-B OUT SYSTEMInstallation of the ACSS Automatic Dependent Surveillance – Broadcast(ADS-B) Out System in accordance with Aerospace Design & Compliance,LLC. Master Data Listreference B753-MDL-0022 Revision A.Revision 1: Transfer of EASA STC 10068771 - originally issued toAEROSPACE DESIGN & CO...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aerospace Design & Compliance, LLC- AFM SUPPLEMENT ref. B753-AFMS-0022 Rev. IR- ICA Document ref. B753-ICA-0022 Rev. IRor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	- As a prerequisite, the existing Transponder System must be incompliance with Mode S, Mode S ELS, and Mode S EHS. Transponder ControlPanel must provide an ATC/XPDR Failure Indication. (AC 20-165B refers).- Aeroplanes modified with this STC must be:Operated in accordance with the AFM SUPPLEMENT ref....	19/06/2020	Active	10068771
10068773	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 1	FAA STC SA04348CH	AVANTI, AVANTI II	Installation of Parker Hanifin Corporation Aircraft Wheel &BrakeDivision, Wheel and Brake Conversion Kit, Part Number 199-283.Rev. 1: Transfer from "Parker Hanifin Corporation,. Aircraft Wheel &Brake Division" to "Kaman Corporation, Aircraft Wheel and Brake, LLC"	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Document Number IM199-283, Kit Installation Publication: Main Wheel &Brake Conversion Kit Parker Hanifin Part No. 199-283, Revision A, dated16 October 2018, or later FAA approved revision and drawing number50-166, Installation, Wheel & Brake Revision A, dated 30 November 2017,or later FAA approved r...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	28/10/2024	Active	10068773
10068808	HONEYWELL INTERNATIONAL INC.	REV. 3	FAA STC ST01685AT	SEE FAA AML	Installation of Honeywell VHF Voice and/ or Data Communications System.NEW-PAGE	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements for thefollowing paragraph(s) at a later amendment:for MDL configuration 1 CS25.1529 at amdt. 0.	Honeywell Master Drawing List 159-08203-0001, Rev. R, dated10 January2019, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.This STC is valid for aircraft types and models a...	03/12/2019	Active	10068808
10068835	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			DC-9-82 (MD-82)	Introduction of a fuselage ULBInstallation of a fuselage Underwater Locator Beacon on MD-82	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition: CRI F-01 Non rechargeable Lithium BatteryInstallations.The requirements for environmental protection and the associatedcertified noise and/ or emissions...	- Master Data List - MODE00240_MDL Initial issue- Instruction for Continued Airworthiness - MODE00240_ICA1 Initial issueor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	None	19/02/2019	Active	10068835
10068836	HELI AUSTRIA GmbH			EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of Tactical Radios into Airbus Helicopters Deutschland GmbHEC 135 helicopter	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment for models EC135 P1,EC135 P2, EC135 P2+, EC135 T1, EC135 T2, EC135 T2+:. CS 27 at Amendment 2: CS 27.021, CS 27.029, CS 27....	- Master Document List (MDL), Doc. No HAU-D-031-001, Rev. 0- Installation Manual for Installation of Tact. Radios into EC135helicopter, Doc. No. HAU-D-031-004, Rev. 0- Rotorcraft Flight Manual Supplement for Installation of Tact. Radiosinto EC135 helicopter, Doc. No. HAU-D-031-005, Rev. 0- ICA manua...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/02/2019	Active	10068836

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068849	VOYAGEUR AEROTECH, Inc.		TCCA SA18-99	DHC-8-402 DHC-8-315, DHC-8-401 DHC-8-311, DHC-8-314 DHC-8-202, DHC-8-301 DHC-8-106, DHC-8-201 DHC-8-102, DHC-8-103	TS60 Emergency Battery Power Supply Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition: CR F-101 Lithium battery installations.- The following paragraph(s) at a later amendment:CS 25 AMDT 17:CS25.1309(b); CS25.1351(c); CS25.1351(d).The r...	- TS60 Emergency Battery Power Supply Installation must be in accordancewith True Blue Power Design Change Summary DCS 17-3225 Revision NC- Operation of the aircraft must be in accordance with True Blue AFMS17-3225 Rev NC- Maintenance mustbe in accordance with True Blue Maintenance ManualSupplement...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/02/2019	Active	10068849
10068894	LUFTHANSA TECHNIK AG	REV. 2		A321-211/-231 A320-214/-232/-233	Direct View Camera SystemThe design change is about the installation of a Direct View CameraSystem (DVCS), which is designed as an additional system to improve theoverall direct view of cabin attendants in the AFT cabin on A320 familyaircraft as replacement to the direct view cabin attendant seat.Re...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Definition Document: STDD25-18-06M issue 01 Rev. 05dated 09.Dec.2019- Compliance Checklist: CCL25-19/22 Revision 1 dated 09.Dec.2019- Instructions for Continued Airworthiness: A-00-18-102-ICA Issue 1 Rev3 dated 15.Oct.2019or later revisions of the above listed document(s) approve...	This approval does not constitute an authorization for the installationof the modification "A320 Direct View Camera System" unless theindividual cabin layout<(>,<)> on which such modification is installed,is demonstrated to be compliant toJAR25.785(h)(1) at Change 11.Furthermore, the embodiment ofS...	10/12/2019	Active	10068894
10068940	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC SA11225DS	390	Installation of a Rockwell Collins Integrated Flight Information System (IFIS-5000) into a Rockwell Collins Pro Line 21 systemRev. 1: Change of Address	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	"Master Data List - Premier 1 IFIS - Premier 1 IFIS and XM"<(>,<)>Document 620-00-0001, Revision IR, dated 28 November 2018 or later FAAapproved revision.Instructions for Continued Airworthiness, Document 620-00-0026 RevisionA, dated 19 November 2018 or later FAA accepted revision.Airplane Flight Ma...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Must have factory installed Pro Line 21 and EASA...	07/08/2025	Active	10068940
10068941	JET AVIATION AG			MYSTÈRE-FALCON 20 - F5 MYSTÈRE-FALCON 20 - E5 MYSTÈRE-FALCON 20 - D5 MYSTÈRE-FALCON 20 - C5	FMS ReplacementReplacement of a single Honeywell GNS-XLS bya single Universal UNS-1Lwincorporating a SBAS GPS receiver.Removed:- Honeywell GNS-XLS- GPS AntennaInstalled:- Universal Avionics UNS-1Lw FMS- Universal Avionics SBAS GPS Antenna- Universal Avionics Solid State Transfer Unit (SSDTU)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:JBSL has elected to comply with later requirements of EASA CS25amendment 21 for paragraphs as follows: 301, 303, 305, 307,5...	- Master Document List: JBSL-M-01186MDL-01, Issue 1<(>,<)>-Airplane Flight Manual Supplement: JBSL-M-01186AFM-01, Issue 2<(>,<)>- Instructions for continued airworthiness: JBSL-M-01186ICA-01, Issue 2or later revisions of the above listed documents approved by EASA.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/02/2019	Active	10068941
10068943	BHE & ASSOCIATES, LTD.	REV. 5	FAA STC SA11219SC	525B 525, 525A, 525B	Rockwell Collins Pro Line Fusion installation.Rev. 1 introduces software version that resolves the ACAS Fly-To Cueindication issue addressed byEASA AD 2019-0179.Rev. 3 adds 525 and 525A model into the scope of this change and addsCPDLC functionality for 525 and 525A model.Rev. 4: Change of AddressRe...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):For 525, 525A, 525B: CRI F-89 Weather DisplaysFor 525, 525A, 525B: SC-F23.1457-01 Flight Recorders including Data LinkRecordingthe follow...	Master Data List, 560-00-0001, revision AZ, dated 07 November 2024.For model 525:Installed according to:Design Data List, 598-01-0002, Revision N, dated 24 October 2024.Operated according to:Airplane Flight Manual Supplement, 598-01-0102, Revision G, dated 09January 2024.Maintained according to:Inst...	Mobile Enablement System is automatically inhibited in flight for EASAregistered aeroplanes.This EASA approval does notcover or authorize participation in the FAAPrivacy ICAO Address (PIA) program.Prior to installation of this change/repair it must be determined thatthe interrelationship between th...	12/09/2025	Active	10068943

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10068944	HONEYWELL INTERNATIONAL INC.		FAA STC ST01552AT	A300 F4-622 R A300 F4-605 R A300 C4-605 R VARIANT F A300 B4-622 R A300 B4-622 A300 B4-620 A300 B4-605 R A300 B4-603 A300 B4-601	Installation of an AlliedSignal Mark II ACARS	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Drawing List No. 159-08175-0001, Revision D, dated 7April 2000,or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/02/2019	Active	10068944
10068945	AEROSERVIS, S.R.O.			L 410 UVP-E20, L-410 UVP-E L 410 UVP-E20 CARGO	Installation of the Garmin GTN 725 with enabled TAWS A option, and anavigational information source to comply with PBN (RNAV1 and LPVApproach)	CS-ACNS Initial Issue.The requirements for environmental protection and the associatedcertified noise and/ or emissionslevels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Aeroservis Aircraft MaintenanceModification ref AE/177 and Master Document List ref AE 177000X_RA ,dated, 2. 10. 2018.Operate in accordance with Aeroservis Aircraft Flight Manual Supplementsref LET 410 UVP-E, GTN 725 with TAWS-A, or L 410 UVP-E20, GTN 725 withTAWS-A,I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/02/2019	Active	10068945
10069003	DASSAULT FALCON SERVICE			MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Modification DFS 9872 Issue A: Portable Emergency Locator Transmitter(ELT) Installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: SpecialCondition (s): F-9128-001: Non-rechargeableLithium BatteryInstallations.The requirements for environmental protection and the associatedcertified noise and/ or emi...	MASTER DOCUMENT LIST Document Ref. DFS-DE-17-F9-9872 Issue A dated 26February 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/03/2019	Active	10069003
10069004	SOCIETE AIR FRANCE S.A.	REV. 1		747-400	Automatic Dependent Surveillance – Broadcast (ADS-B) OUT (DO-260B) activation on B747-400 aeroplanes. Revision 1 of thisSTC expands theapproved design change configuration by allowing installation ofadditional Multi-mode Receiver and Air Traffic Control (ATC) TransponderPart Numbers as defined in Ai...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Air France Service Bulletin AFSB-B747-18-001-34-001 original issueAir France Service Bulletin AFSB-B747-18-001-34-002 original issueAir France Airplane Flight Manual Supplement AFMS-B747-18-001-001Revision 1Air France Change Approval SheetCAS-B747-18-001 Revision 2or later revisions of the above li...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2019	Active	10069004
10069005	BHE & ASSOCIATES, LTD.	REV. 3	FAA STC SA11222DS	SEE FAA AML	Installation of automatic dependent surveillance-broadcast (ADS-B) Outon Part 23 aircraft.Rev. 1 adds aircrafts to the AML.Rev. 2 adds Collins GPS-4000S-101 and updates applicableavionics/modelcombinations for Textron 525, 525A and 525B with the Collins Pro LineFusion.Rev. 3: Change of Address	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA11222DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Data List 583-00-0001, Revision IR, dated 23 January 2018, orlater FAA approved revision.- For Instructions for Continued Airworthiness and Airplane FlightManual Supplement reference the AML.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	07/08/2025	Active	10069005

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069007	AIRBORNE TECHNOLOGIES GmbH	REV. 1		BO 105 S	Pankl Load Arm for Side Step of BO105.Modification of a load arm on an BO105 left hand side step includingforward and rearward camera position.Rev. 1: Transfer from Pankl Aerospace Systems Europe GmbH to AirborneTechnologies GmbH.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	CER_17040_03082017 Certification ProgramDOC_17-40_0308 2017 Declaration of ComplianceICA_17-040_03 082017 Instructions for continued AirworthinessAFM_17-040_ 08112017 Flight Manual Supplementor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	EASA STC 10046138 needs to be installed prior to installation of thisSTC.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthine...	20/01/2021	Active	10069007
10069009	DART AEROSPACE Ltd.		TCCA STC SH18-50 ISSUE 1	EC 130 B4/ EC 130 T2	Emergency Float System Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List MD130-4 Revision A, dated 15 November 2018Installation Instructions II130-4 Revision B, dated 21 October 2018Instructions for Continued Airworthiness ICA130-4Revision 0, dated 12June 2018Flight Manual Supplement RFMS130-2 Revision A, dated 11 October 2018or later revisions of t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/03/2019	Active	10069009
10069010	LIFEPORT, Inc.		FAA STC SA02234LA	B300C	Installation of a ServiPlex.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List for the ServiPlex installation in the HawkerBeechcraft B300C, MDL-848-00, RevisionL, dated 29 March 2009, or later FAA approved revision.2. Airplane Flight Manual Supplement No. EGR-848-11, dated 13 May 2009,or laterFAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	01/03/2019	Active	10069010
10069011	Q.C.M. DESIGN GmbH			BD-700-1A10	Change of aircraft LOPA and installation of SATCOM system	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): F-01 Security Protection of Aircraft Systems andNetworksDeviation(s): D-01, Doors between Passenger CompartmentsThe following paragraph(s) at a later...	The change is defined with the initial issue of Q.C.M. CertificationReport BBD7-QCM25-015;The aircraft shall be operated in accordance with Aircraft Flight ManualSupplement BBD7-QCM25-015-M1-AFM. This AFMS consists of two parts:1. BBD7-QCM25-015-M1-AFM titled LOPA Change, Revision 022. BBD7-QCM25-01...	The Luftfahrt Bundesamt Joint Aviation Authorities Supplemental TypeCertificate LBA.21NE2.TA0575, installation of complete custom aircraftinterior shall be incorporated prior to or in conjunction with this STC.Prior to installation of thischange/ repair it must be determined thatthe interrelationshi...	01/03/2019	Active	10069011
10069012	DELTA ENGINEERING CORPORATION	REV. 4	FAA ST03417NY	A321-272NX A321-253NX/-271N/-271NX/-272N A321-251NX/-252N/-252NX/-253N A321-213/-231/-232/-251N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-232/-233/251N/-252N/-272N A320-232/-233/-251N/-252N A320-211/-212/-214/-216/-231 A319-131/-132/-133/ A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation with demod option of Intelsat Cabin Connectivity SystemconfigurationsRev 1: Typos correction.Rev 2: New configuration added. This approval constitutes an AMOC withEASA AD 2022-0085 (FAA AD 2020-20-05).Rev. 3: Correction of Description of Design Change.Rev. 4: New configurations added as...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 amdt 4: 25.853,25.869, 25.1581, 25.1583, 25.1585.The requirements for environmental protection and the associatedc...	Master Data List 0164-09676-2406 Revision CI dated 6 June 2025.The Instructions for Continued Airworthiness, ElectricalWiringInterconnect System Instructions for Continued Airworthiness andAirplane Flight Manual Supplement as listed on the Master Data List isrequired with this installationor laterb...	As per MDL 0164-09676-2406, in particular:Operational approval to use T-PED's must be obtained with this STC.Installation of EASA STC 10070123 (FAA STC ST03416NY) is required whenproviding internet connectivity.Prior to installation of this change/repair it must be determined thatthe interrelationsh...	28/10/2025	Active	10069012

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069040	SWISS AVIATIONSUPPORT GMBH			2180	Increase of limited mass for sailplaneWith this change the maximum allowed sailplane mass which can be towedis increased from 580kg to 800kg.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Special Condition(s): CRI O-09 Glider towingThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain a...	AFM supplement Aerotow Varga 2180 rev 0 dated 23 March 2018Maintenance Manual supplement Doc. No. E-17GTSMM rev 0 dated23 March2018Installation Instructions Doc. No. E-17GTSII rev 0 dated 23 March 2018or later revisions of the above listed documents approved by EASA.	Limited to S/N VAC 158-80 and VAC 180-82Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/03/2019	Active	10069040
10069041	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Lithium Ion Powered Devices & EquipmentTo approve the carriage of Non Rechargeable Lithium Ion battery powereddevices &emergency equipment on board the aircraft type.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 Non- rechargeable Lithium BatteryInstallationsThe requirements for environmental protection and the associatedcertified noise and/ or emissi...	-Master Data List - MODE00257_MDL Rev. 1 Initial Issue-Instruction for Continued Airworthiness - MODE00257_ICA1 Rev. 1 Initialissueor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	05/03/2019	Active	10069041
10069042	IKHANA GROUP, LLC	REV. 1	FAA STC SA03245NY	DHC-6 SERIES 400	Installation of R. W. Martin Air Conditioning SystemRev. 1:Name Change from "Ikhana Group Inc." to Ikhana Group LLC".	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	*R. W. Martin Inc. Drawing List, Report ER218-2502V, Revision C, dated 7September 2010, FAA approved 9 September 2010 or later FAA approvedrevision.For Instructions for Continued Airworthiness refer to *R. W. MartinInstructions for Continued Airworthiness, Document No. AC-64-11,Revision IR, dated 4O...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	18/06/2021	Active	10069042
10069048	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 1	FAA STC ST02608LA	777-200/-200LR/-300/-300ER/-F	Modification to the existing Mode S Transponder system to add NEXTGENADS-B Out and optionally install the ACSS NXG-900 GPS as an ADS-B Outposition source.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	FAA approved Index of Master Data Lists, Document No. 8900077, Revision"-", dated 17 August 2016, or later FAA approvedrevision.	The installation of the optional ACSS NXG-900 GPS as an ADS-B Outposition source, is not permitted.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noad...	07/03/2019	Active	10069048
10069103	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			525A 525	Upgrade GNS-430/530(A) to GNS430/530A(W)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, Report 2018-21-16, Revision B, dated 5 March 2019.Installed according to:Installation Procedure, Report 2018-21-1, Revision A, dated 15 August2018.Operated according to:Airplane Flight Manual Supplement, Report 2018-21-8, Revision IR, dated21 August 2018.Maintained according to...	Limited to the following S/N: 525-0001 through 525-0599525A-0001 through 525A-0299Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the air...	07/03/2019	Active	10069103
10069118	LUFTHANSA TECHNIK AG	REV. 3		A321-211/-231 A320-214/-232/-233	Alternative aluminium material at frame C70Alternative aluminium material for the drag struts and angles at frameC70 isadopted. Additionally, the material thickness has been increasedfrom 2.5mm to 2.6mm and all bend radii have been increased from 4mm to6mm ±1mm.Revision 2: extension of the applicabi...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: as per CCLL00120-ACC-0011 Rev. D.The requirements for environmental protection and the associatedcertified noise and/ or e...	L00120-MDL-0010 rev. G< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	1) This change exclude the installation of the new floor panels fromEuro Composite.2) On the aircraft affected by this change a yearly inspection shall beperformed throughout the life of the aircraft in accordance MPDSupplement L00120-MPD-0002. The inspection regime on the affectedaircraft cannot be...	04/11/2019	Active	10069118

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069122	E A D AEROSPACE AIRWORTHINESS			DHC-6 SERIES 300	Installation of SATCOM ANTENNA AMT3800	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, EAD Aerospace drawing reference 01409-EAS-A-MDL,revision C, dated 28 February 2019Instructions for Continued Airworthiness, EAD Aerospace documentreference 01409-EAS-A-ICA-01, revision E, dated 28 February 2019or later revisions of the above listed document(s) approved/acceptedunde...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/03/2019	Active	10069122
10069126	SCANDINAVIAN AVIONICS DESIGN ApS			B200	TCAS I ANTENNA PROVISIONThe modification consists of the mechanical/ aerodynamic relatedinstallation of: 1. Garmin GA58 TCAS Antenna on the upper fuselage. 2.DM Antenna Technologies DM NI50 series L-Band antenna on the lowerfuselage.NOTE: This installation covers the full mechanical provision only.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-23 Amendment 3 andFAR 23.341 Amdt. 23-0 and FAR 23.561 Amdt. 23-7.The requirements for environmental protection and the...	Installation in accordance with Scandinavian Avionics Design MasterDocument List, document 2116368, at issue 1, dated March 6, 2019;Instructions for Continued Airworthiness in accordance with ScandinavianAvionics Design documents: 2116368-CA A, at issue 2, dated March 1, 2019; 2116368-CA B, at issu...	This installation covers the mechanical provisions only. System relatedanalysis (e.g. Functional hazard analysis, HIRF and indirect effects ofLightning) must is part of a related other change documentation.Prior to installation of this change/repair it must be determined thatthe interrelationship be...	08/03/2019	Active	10069126
10069134	LUFTHANSA TECHNIK AG	REV. 2		A320-233 A320-232 A320-214	Latam A320 Cabin ModificationThe modification of the A/C isinitiated by installation of new economyclass seats with one or two additional seat rows and the installationand activation of a new In-Seat Power Supply System (ISPSS). The newseat arrangement consists 180ea economy seats.Revision 1: Added...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-2318-001 Non-rechargeable Lithium BatteryInstallationsthe following paragraph(s) at a later amendment: CS 25.562 Arndt. 0except 25.562 (c)(5) a...	- Compliance Checklist: CCL25-18/08M issue 5 dated 21.Oct.2019- Supplemental Type Design Document: STDD25-18/08M Issue 01 Revision 04dated 21.Oct. 2019- Instructions for Continued Airworthiness: ICA M01001092RSP 23082018LA869 Revision 05 dated 09.Aug.2019or later revisions of the above listed documen...	- Lufthansa Technik EASA STC 10069118 for the installation of Skypaxgalley/lavatory monument at door 4 has to be performed before or inparallel.- Lufthansa Technik EASA STC 10068894 for the implementation of thedirectview camera system at door 4 has to be performed before or in parallel.- Aircraft e...	22/10/2019	Active	10069134
10069146	ELLIOTT AVIATION		FAA STC ST04272CH	560XL	Installation of ADS-B Out System with Shad in Avionics AMC	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04272CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Elliott Aviation Master Data List, Document No. MDL-3832-560,Revision D, dated 1 October 2018, or later FAA approvedrevision. 2. FAA Approved Flight Manual Supplement, Elliott Aviation Document No.FMS-3832-560, Revision A, approved 1 November 2018, or later FAAapproved revision.3. Airworthiness L...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/03/2019	Active	10069146
10069154	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC ST00252BO	560XL	Installation of Pratt & Whitney Engine Services, Inc. Digital AircraftData Acquisition System ADASd	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Installation Manual DAAS-G-010-4, Revision B, dated 26 April 2007, orlater FAA approved revision.Instructions for Continued Airworthiness (ICA)DAAS-G-260-4, dated 5March 2007, or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2019	Active	10069154
10069155	FTI ENGINEERING NETWORK GmbH			C90, C90A, C90GT, C90GTI	Additional Antenna InstallationMechanical Installation of 7additional antennas - further details aregiven in "System Description" Doc. No. F30-EO17-1593	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-F30-EO17-1593 Issue 02 System description-F14-EO17-1593 Issue 01 Master Drawing List-F09-EO17-1593 issue 01 Parts Listor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	11/03/2019	Active	10069155

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069157	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC ST00253BO	560XL	Installation of Pratt & Whitney Engine Services, Inc. Data TransmissionUnit (DTU)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Installation Manual DTU-G-010-4, Revision B, dated 26 April2007, orlater FAA approved revisions.Instructions for Continued Airworthiness (ICA) DTU-G-260-4, Revision A,dated 5 March 2007, or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2019	Active	10069157
10069165	AEROTEC & CONCEPT			B200GT	EGPWS Inhibition of alert during mission operation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with AEROTEC Concept Modification ref 18098as defined in Master Document List (MDL) ref, AE18098MDL Rev 0, dated, 04.03.2019.Operation in accordance withAEROTEC Flight Manual Supplement (AFMS)ref, AE18098AFMS, Initial Issue, dated March 2019.Instructions for Continued Airw...	Aircraft equipped with Flight Inspection System, installed through EASASTC N°10030456 only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect up...	12/03/2019	Active	10069165
10069189	SAFRAN SEATS			747-400	LGW Aircraft. Zone A and Zone B reconfiguration	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Heath Tecna Definition Document R652 Rev. 1, dated 22 October 2004, orlater approved revision.Instructions for Continued Airworthiness HTM911, Initial Release, dated19 August 2004, or later approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2019	Active	10069189
10069190	SAFRAN SEATS			737-500	Introduction of a new 108 Y class configuration along with galley andwardrobe as defined in Heath Tecna Drawing 8-04156and associated DDPR660.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Heath Tecna Modification Document C944 and associated DDP, dated 24March 2005, or later approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/03/2019	Active	10069190
10069191	DELTA ENGINEERING CORPORATION		FAA STC ST03435NY	777-200LR 777-200	Installation of a Bruce Aerospace Lighting	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03435NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Delta Engineering Master Data List 0143-10360-2423 RevisionF dated 16May 2018 or later FAA approved revisions to DeltaEngineering MasterData List previously listed.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Configuration 2 of the Master Data List 0143-103...	12/03/2019	Active	10069191
10069211	STANDARD AERO		FAA STC ST04283CH	GV-SP GV GIV-X GIV GIII (G-1159A) GII (G-1159) GIIB (G-1159B)	Activation of a WiFi System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04283CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. StandardAero Master Data List 1033889, Revision (A), dated 3 May 2018<(>,<)> or later FAA approved revision.2. FAA Approved Airplane Flight Manual Suppement document number 1034562Rev (A)<(>,<)> dated 2 May 2018, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2019	Active	10069211

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069212	STANDARD AERO		FAA STC ST03274CH	BD-700-1A11 BD-700-1A10	Activation of an 802.11 a/b/g/n/ac WiFi System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03274CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Standard Aero Master Data List 1025506<(>,<)> Revision (C), dated 4December 2017<(>,<)> or later FAA approved revision.2. FAA Approved Airplane Flight Manual Supplement document number1025493, Revision (B) dated 10 October 2017<(>,<)> or later FAA approvedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/03/2019	Active	10069212
10069214	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	727-200F	Installation of Low Frequency Underwater Locating Device onto Boeing 727	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01 Non-rechargeable Lithium BatteryInstallations.- The following paragraph(s) ata later amendment: CS 25 at Amendment12: 25.1<(>,<)> 25.21<(...	- 2Excel Design Limited Instructions for Continued Airworthiness No.2XL136 LEF73(1) Issue 2;- 2Excel Design Limited Master Data List No. 2XL136 LEF78(1) Issue 3;or later revisionsof the above listed document (s) approved/ acceptedunder the EASA system.	This approval is limited to those aircraft serial numbers recorded on2Excel Design Limited Statement(s) of Approved Design Data No. 2XL136LEF83 (-).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installe...	13/03/2019	Active	10069214
10069215	AEROTEC & CONCEPT	REV. 1		B300, B300C 300, 300C	Installation of External Electro-Optical-Infrared (EO/IR) sensor, Searchand Rescue antenna (SAR-DFF) and Radome for Intelligence, Surveillanceand Rescue application (mission system).Revision 1 accounts for modifications to external installations toimprove operational reliability of the Maritime Stra...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List, document AE24072MDWL, Issue 0, dated 09 Jun 2025Aircraft Flight Manual Supplement, document AE24072AFMS, Issue 0, dated10 Apr. 2025Instructions for continued airworthiness, document AE24072AICA, Issue 0,dated 10 Apr. 2025or later revisions of the above listed document(s) approve...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The following MODs are pre-requisites of MOD 24072:- MO...	11/06/2025	Active	10069215
10069222	DELTA ENGINEERING CORPORATION		FAA STC ST03434NY	777-200	Installation of a Cabin Interior Reconfiguration.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03434NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Delta Engineering Master Data List 0143-10295-2428 Revision D dated24 April 2018 or later FAA approved revisions to Delta EngineeringMaster Data List previously listed.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.For this configuration EASA STC 10043267 is requ...	13/03/2019	Active	10069222
10069231	AMAC AEROSPACE SWITZERLAND AG			A340-541, A340-542	Installation of C-Music System. The change includes the PodStructuralAssembly, (PSA) housing the main components of the system. The PSA isfuselage-mounted at the lower section ofthe fuselage.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-101 Vibration/ buffeting compliancecriteria for large external antenna installations.The requirements for environmental protection and the a...	The change is defined with Revision B of Master Data List DocumentMDL-A3403-1-5300The aircraft shall be operated in accordance with Revision B of AirplaneFlight Manual Supplement AFMS-A3403-1-5300The Aircraft shall be maintained in accordance with Revision B ofInstructions for Continued Airworthines...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/03/2019	Active	10069231

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069246	ADAC LUFTFAHRT TECHNIK GmbH			EC135 P3, EC135 T3	Night Vision Imaging Systems (NVIS) Certification of Mission Equipmentin accordance with Master Document List EC135-08368-001-LMD	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 27 Amendment 4 forthe following paragraphs: 27.1; 27.141(c); 27.601; 27.771(a), (b); 27.773; 27.1301(a),(d); 27.1309 (a)-...	- Rotorcraft Flight Manual Supplement EC135-08368-025-MFS Revision 0- Master Document List EC135-08368-001-LMD Revision0- Installation Instructions EC135-08368-004-DIN Revision 1- Maintenance Manual Supplement EC135-08360-023-MMS Revision0or later revisions of the above listed document(s) approved...	Limited to Helionix cockpit variants only.The approval of this STC is based on the following prerequisites:- Airbus Helicopters Deutschland GmbH “Night Vision Imaging System (NVIS)First-Time Installation on EC135 models equipped with avionicssuite HELIONIX (EC135 P3H/T3H)”, EASA Approval 10064200- A...	14/03/2019	Active	10069246
10069248	BROMMA AIR MAINTENANCE AB			DORNIER 228-212 DORNIER 228-202 DORNIER 228-201 DORNIER 228-200 DORNIER 228-101 DORNIER 228-100	Mechanical installation of a belly pod to Dornier 228 series asprovision for special mission equipment, Modification No17-27.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Bromma Air Maintenance AB modification17-27 and Bromma Master Data List ref MDL-17-27, Rev A, dated08.03.2019.Operation in accordance with Bromma Air Maintenance AB, Flight ManualSupplement ref FMS-17-27, Rev A, dated 04.12.2018.Maintain in accordance with Bromma AirC...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/03/2019	Active	10069248
10069253	ANCRA INTERNATIONAL LLC		FAA STC ST01553LA	747-200B/-200C/-200F/-300/-400	Installation of Lower Deck Ball Mats	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	FAA approved Ancra International LLC Controlled Drawing List DL82900,dated 15 October 2003, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/03/2019	Active	10069253
10069255	BEONE HAMBURG GmbH			C90A, C90GT, C90GTI	Installation of L-Band AntennaInstallation of two L-Band Communication Antennas	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation of L-Band Antenna in accordance with BeOne MasterDocument List, 617-1005-MDL-0001, at revision A, datedMarch 2019.- Instructions for Continued Airworthiness, BeOne document 617-1005-ICA-0001, at revision A, dated March 2019or later revisions of the above listed document(s) approved/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/03/2019	Active	10069255
10069256	AIRBUS DEFENCE AND SPACE S.A.	REV. 9		A330-243	Conversion of A330-200 Series Aircraft to A330 Multi Role TransportTanker MMF (Multi National MRTT Fleet)- Rev. 1 introduces MEDEVAC Configuration via change DCV0846-E- Rev. 2 updates the change reference- Rev. 3 updates the AFM reference-Rev. 4 introduces change DCV0949A-E, AFM Limitation for Stre...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): D-4318-002, Air Medical Service.- The following paragraph (s) at a later amendment:CS 25.0562 Initial Issue for affected areas by this STC;CS 25.085...	- "CONVERSION DEFINITION A330 MMF STC" document ref. TAE-FM-DT-170056Issue A- Airplane Flight Manual Supplement "EASA APPROVED MODEL A-330 MRTT MMFAIRPLANE FLIGHT MANUAL" documentRef. TEA-FM-DT-170052, including Weightand Balance limitations reference TAS-FM-TD-19-0001 Limitations ofWeight and Bala...	Approval of this STC is limited to compliance to selected CertificationStandards as defined in A330 MRTT MMF CRI A-01.A330 MRTT RAAF CRI G-01 defines in particular restrictions relating toMaintenance Tasks and Airworthiness Limitations, Ref. JAR 25.571a(3) and25.1529.Therefore, the following limitat...	17/04/2023	Active	10069256

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069257	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-31T (CHEYENNE/ CHEYENNE II) PA-31T2 (CHEYENNE IIXL) PA-31T1 (CHEY. I/ CHEYENNE IA) PA-31P (PRESSURIZED NAVAJO) PA-31P-350 (MOJAVE)	Garmin GA58 and/or Comant CI105-6Installation of Garmin GA58 TAS antenna on top fuselage and/or ComantCI105-6 XPDR diversity antenna on top fuselage.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 23.29; 23.251;23.301(a) (b); 23.303; 23.305(a); 23.305(b); 23.307(a); 23.337 (a)(1);23.365(a); 23.365 (b); 23.365(d); 23.5...	Installation defined in Master Document List, reference Doc.-N °ASR-2018-070-MDL-01-01, dated 11/03/19Instructions for installation, reference Doc.-N° ASR-2018-070-IFI-10-00,dated 17/12/18Instructions for continued airworthiness, reference Doc.-N °ASR-2018-070-ICA-11-00, dated 18/12/18or later revisio...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/03/2019	Active	10069257
10069260	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC SA02677LA	SEE FAA AML	Modification to upgrade the existing Mode S Transponder system byinstalling the ACSS NXT-700 Transponder with ADS-B Outand optionallyinstall the ACSS NXG-900 GPS as the position source for ADS-B Out.	See Annex 1.	FAA approved AML STC Master Data List (MDL) as defined in the AML No.SA02677LA, dated 15 January 2019, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement and Instructions forContinued Airworthiness are defined inthe AML No. SA02677LA, dated 15January 2019, or later FAA ap...	Eligible airplane models must be listed on the FAA ApprovedModel List(AML) for this STC to be applied.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducea...	12/04/2019	Active	10069260
10069291	BELL TEXTRON, Inc.	REV. 1	FAA STC SR04047NY	407	Installation of a GPMS Foresight MX Condition Monitoring System (CMS) Revision 1 adds Bell 407 Analog aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	- FAA Approved Model List (AML) No. SR04047NY-AML as amended on 6December 2022;- Instructions for Continued Airworthiness (ICA) as specified in theSR04047NY-AML;- Master List as specified in the SR04047NY-AML;- Rotorcraft Flight Manual Supplement (RFMS) as specified in theSR04047NY-AML;or later revi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/06/2024	Active	10069291
10069292	BUTLER NATIONAL CORPORATION		FAA STC ST02416SE	36, 36A, 55, 55B 25C, 25D, 25F, 31, 35, 35A 24D-A, 24F, 24F-A, 25, 25B 24, 24A, 24B, 24B-A, 24D	Installation of the replacement rate gyro, Butler National Part Number501-1169-01 MOD A or 501-1169-02 MOD A	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02416SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List (MDL) 02401000, Revision IR< (>,<)> dated 13 August2014, or later FAA-approved revision.2. Instructions for Continued Airworthiness (ICA) 02407011, Revision IR,dated 6 August 2014 or later FAA-accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/03/2019	Active	10069292
10069305	L2 AVIATION SOLUTIONS, LLC		FAA STC ST10938SC	757-200, 757-200PF, 757-300	Installation of an Iridium Communication System (ICS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Drawing List 2325-B47-MDL, Revision U, dated 8 December 2018, orlater FAA approved revision.Airplane Flight Manual Supplement 2325-B47-AFM, Revision D, dated 18December 2018.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/03/2019	Active	10069305

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069307	LUFTHANSA TECHNIK AG			A321-253N/-271N/-272N A321-213/-231/-232/-251N /-252N A321-111/-112/-131/-211/-212 A320-271N A320-231/-232/-233/-251N /-252N A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Auxiliary Equipment RackThe design change consists of the installation of an Auxiliary EquipmentRack and Provisions to integrate avionic and electrical equipment intothe aircraft forward lower cabin compartment area.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Design Document STDD53-18/02M iss 1.0<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	20/03/2019	Active	10069307
10069344	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	ERJ 170-200 STD ERJ 170-200 LR ERJ 170-100 STD ERJ 170-100 LR	Installation of two Securaplane 24 VDC/ 28 Ah sealed Lead Acid Batteries	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-STC Twenty One Limited Master Document List ref. S21.MDL-1312 Issue 1- STC Twenty One Limited Compliance Record ref. S21.COMP-1312 InitialIssue dated 11 March 2019-STC Twenty One Limited Instructions for Continued AirworthinessSupplement Manual ref. S21.TEC-0526 Issue 1 dated 18 March 2019or later r...	None	21/03/2019	Active	10069344
10069347	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A340-313	Cabin Interior Reconfiguration of Lufthansa aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Certification Summary, Northwest Aerospace Technologies, Inc. documentN0635-D90, Revision A, dated 20 March 2019;- Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document N0635-D70, Revision IR, dated 4 January2019;or later revisions of the above listed document(s)...	None	21/03/2019	Active	10069347
10069355	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	737-300/-400	Introduction of Structural Provisions For A No.3 VHF CommunicationsAntenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STC Twenty One Ltd Master Document List No. S21. MDL-1438 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This design change (S21.53-13-1055) is an Alternative Method ofCompliance (AMOC) to Airworthiness Directive AD 2013-04-05 in the regionon the installation.The airworthiness limitation inspections<(>,<)> mandated inS21.AMMS-0037<(>,<)> are required in order to maintain continuedairworthiness in the r...	21/03/2019	Active	10069355
10069367	JET AVIATION AG			GVI (G650)	This STC introduces several changes to the existing GVI (G650) cabinlayout, which has been approved under FAA STC ST04252AT-D and EASA STC10045299.The modifications include, amongst others, the replacement of the LHthree seats divan by twosingle seats, the relocation/installation offolding tables,c...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs at a later amendment: CS-25, Amdt. 21 for25.27, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.341, 25.561,25.562, 25.581, 25.601, 25.603, 25.6...	- Master Data List JBSL-M-01164MDL-01, Issue 01-ALS in Chapter 4 of JBSL-M-01164ICA-01, Issue 01or later revisions of the above listed documents approved/ accepted underthe EASA system.	- The embodiment of this STC is limited to MSN 6115 only.- GVI (G650) Airplane Interior approved under FAA STC ST04252AT-D / EASASTC 10045229 is a prerequisite for installation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andp...	22/03/2019	Active	10069367

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069369	LUFTHANSA TECHNIK AG	REV. 4		737-700, 737-800	Removal of Viasat Antenna System, as installed per STC 10064496 (up toRev 4 inclusive) and 10064512 (initial issue) – Option 1 and Option 2Rev. 1: Updated ICA (including updated inspection intervals); AMOC to ADUS-2013-19-23.Rev. 2: STC description update (including reference to STC 10064496 Rev3).R...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Definition Document STDD53-18/05M Issue 04 rev 00Instructions for continued airworthiness A-00-18/88-ICA Issue 05 rev 00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This change constitutes Alternative Means of Compliance forADUS-2013-08-15, US-2013-08-16 and US-2013-19-23 for the areas affected bythis modification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously insta...	21/06/2024	Active	10069369
10069380	CRANFIELD AEROSPACE SOLUTIONS LIMIT	REV. 1	CAA UK RESPONSIBILITY	A109E	Installation of QinetiQ FTI SystemInstallation of flight test instrumentation system to provide thepossibility to monitor aircraft systems and gather independent datawithout control or feedback from the FTI system into any aircraftsystem. The system includes monitoring, processing, storage and trans...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-27 Amdt. 2:CS 27.1 (a)(c), CS 27.21 (a), CS 27.29 (a)(b), CS 27.31, CS 27.45 (a)(b)<(>,<)>CS 27.29 (a)(b), CS 27.51 (a)...	Original STC Issue:- Aircraft Flight Manual Supplement, CAS/ AFM0009, Issue D dated March2019- Airworthiness LimitationsSection of Airworthiness Information Report,CAS/M0125, Issue C dated March 2019- Airworthiness Information Report, CAS/M0125, Issue Cdated March 2019- Certification Plan, CAS/ CP147...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/06/2019	Active	10069380
10069399	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A330-223	IFE installation in Y-ClassAir Greenland has awarded SR Technics to provide an IFE upgrade(installation of new IFE equipment) on existing business class (30) andeconomy class (248) seats. The business class seats were upgraded withnew IFE with STC 10064829. This STC application is to upgrade theecon...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplement S.OAEZ. 001907-AFM Rev 00Master Document List S.OAEZ. 001907-MDL Rev 00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/04/2021	Active	10069399
10069404	AEROTEC & CONCEPT	REV. 1		DR 400 RP, DR 400/100 DR 400/2+2, DR 400/200 I DR 400/200 R, DR 400/500 DR 400/180 R, DR 400/180 S DR 400/160 D, DR 400/180 DR 400/140 B, DR 400/160 DR 400/125I, DR 400/140 DR 400/125, DR 400/120 DR 400/120 D, DR 400/120 A DR 360, DR 380, DR 400 NGL DR 300/180 R, DR 315, DR 340 DR 300/125, DR 300/140 DR 300/108, DR 300/120	G500Txi and GTN650 installation (without VFR Night limitation)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List Ref. AE18047MDL_Rev.1 dated 25/07/2019;-Aircraft Flight Manual Supplement ref. AE18047AFMS Revision1 dated22/07/2019;- Section 9 “Airworthiness Limitations” of Instructions for ContinuedAirworthiness Ref. AE18047ICA Revision 1 dated 16/05/2019;or later revisions of the above lis...	None	04/10/2019	Active	10069404
10069409	ROCKWELL COLLINS, Inc.		FAA SA01857WI	C90GTI B200GT, B200CGT, B300, B300C	Modification of Rockwell Collins, Inc. Pro Line Fusion® software andhardware.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: see Appendix.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	Installation in accordance with Rockwell Collins AML RCA-0569, Revision(-), issued November 13, 2017.Operate in accordance with appropriate Rockwell Collins Flight ManualSupplement ref :- Airplane Flight Manual Supplement B200GT/ B200CGTRCA-0578, Revision(-), dated February 28, 2017; Airplaned...	For model specific limitations, see AML RCA-0569, Rev. (-).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the prod...	26/03/2019	Active	10069409

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069414	BOMBARDIER Inc.	REV. 1		BD-700-2A12	Installation of Mounts for Tablet from Factor Portable Electronic FlightBag (EFB) Devices.Rev. 1: Update of the STC holder address.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Data Summary, Bombardier Inc. document No. RAZ-BM700-167,Revision--,date d 23 November 2018Instructions forContinued Airworthiness, Bombardier Inc. document No.EFB251600-ICA, Revision Basic,dated 4 December 2018Supplemental Airplane Flight Manual, Bombardier Inc. document No.GCA-460002d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/04/2023	Active	10069414
10069416	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA ST04319AT-D	SEE FAA AML GVI (G650)	Installation of Satcom Direct Router - Gateway(SDR-G) SystemRevision 1: Minor edits on the referenced documentsRevision2: Adds GVII-G550 and GVII-650 to the AML.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- GVII-G600 and GVII-G500 Certification Plan GC73422C001 Revision B-Summary Compliance Report GC72422C001 Revision A for GVII-G500-Summary Compliance Report GC73422C002 RevisionB for GVII-G600-EASA Validation Summary Compliance Report GC73422C005 Revision (-) forGVII-G600 and GVII-G500- Index Li...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/08/2022	Active	10069416
10069421 (LBA SA 0094)	ACC COLUMBIA Jet Service GmbH	REV. 3		208, 208B	208, 208B Parachute KitRevision 1: Transfer from Atlas Air Service AG to Gomolzig AircraftServices GmbH.Revision 2: Transfer from Gomolzig Aircraft Services GmbH to ACCColumbia Jet Service GmbHRevision 3: Typo in company name	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List MDOCL_2050230_rev0_20180615Model 208 - MDRWL_C208_2050230_rev0_20180615 - SPOH_C208_2050230_rev0_20180615 - II_C208_2050230_rev0_20180615Model 208B - MDRWL_C208B_2050230_rev0_20180615 - SPOH_C208B_2050230_rev0_20180615 - II_C208B_2050230_rev0_20180615Main...	The installation of this modification by third person is subject towritten permission of the approval holder and holding and disposal ofthe approved documentation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	26/01/2022	Active	10069421
10069423	ELBE FLUGZEUGWERKE GmbH			A319-133	Structural Modification for Antenna and Window Plug Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Top Engineering Order, Ref. EFW-EO-0101-001, Rev. A- Airworthiness Limitation Section (ALS) / Part 2 AirworthinessLimitation Items, Ref. A319-ALI-PEGASUS<(>,<)>Rev. 01-AircraftFlight Manual Supplement, Ref. A319-AFM-PEGASUS<(>,<)> Rev.00- Master Minimum Equipment List, Ref. A319-MMEL-PEGASUS, Re...	- Installation of STC 10069424 (corresponding to EASA project0010049528)- As defined in the AFMS, Ref A319-AFM-PEGASUS (Limitations Section)- As defined in the Airworthiness Limitation Section (ALS) / Part 2Airworthiness Limitation Items, Ref. A319-ALI-PEGASUS (Section 3).Prior to installation of th...	27/03/2019	Active	10069423
10069424	LUFTHANSA TECHNIK AG	REV. 1		A319-133	A319 Special Mission and Cabin ModificationRevision 1: Reduction of minimum cabin crew.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25.788(b), CS25S25.1(b), CS25 S25.10(d)(e), CS25 S25.30(a)(b), CS25 S25.50(a), all atAmdt 19, plus CS-MMEL,...	-Supplemental Type Design Document, Ref. STDD00-17/06M, Issue 02Revision 00-Instruction for Continued Airworthiness, Ref. A-00-17/82-ICA, Issue 03Revision 04-Airplane Flight Manual Supplement, Ref. A-00-17/82-AFM, Issue 01Revision 01-Flight Crew Data, Ref. A-00-17/82-FCD, Issue 01 Revision 00-Master...	- Non-commercial operations only.-Installation of STC 10068423 (corresponding to EASA project0010049529).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no ad...	15/05/2024	Active	10069424

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069436	LUFTHANSA TECHNIK AG			A319-133	Replacement of Window Plugs by Mission Windows	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Top Engineering Order, Ref. EFW-EO-0111-001, Rev. A- Master Minimum Equipment List, Ref. A319-MMEL-PEGASUS2, Rev. 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Installation of STCs 10069423 and 10069424.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/03/2019	Active	10069436
10069439	GARMIN INTERNATIONAL, Inc.	REV. 9	FAA STC SA01866WI	SEE FAA AML	Installation of Garmin GFC 500 Autopilot with Electronic Stability andProtection.Revision 1 adds new Part 23 aircraft models.Revision 2 adds new models to the AML.Revision 3 adds new models to the AML.Revision 4 adds new models to the AML and updates the Master Data List(MDL), which stands at Revisi...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01866WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Garmin Master Drawing List (MDL) 005-01264-00, Revision 1, dated 21December 2017;2. Garmin GFC 500 Automatic Flight Control System Part 23 AML STCMaintenance Manual (includes Instructions for Continued Airworthiness) 190-02291-01, Revision 1, dated 21 December 2017;or later revisions of the aboveb...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List FAA STC SA01866WI dated 20 July2022.Aircraft modified by this STC must beoperated in accordance with theAirplane Flight Manual Supplement (AFMS) identified on the ApprovedModel List.Aircraft mo...	27/08/2025	Active	10069439
10069446	AIRBUS HELICOPTERS, Inc.		FAA STC SR09506RC	EC 130 T2	Installation of AEM 600W PA Speaker System on EC 130 T2.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	- Master Drawing List 130A82-8023 Rev. B, "Installation 600W LoudspeakerSystem", dated 21 December 2015.- Rotorcraft Flight Manual Supplement 130FMS-516 Rev. IR, dated 2 March2016.- Instructions for Continued Airworthiness 130MMS-025 Rev. IR, dated 23December 2015or later revisions of the above list...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/05/2019	Active	10069446
10069456	BRITISH AIRWAYS PLC		CAA UK RESPONSIBILITY	747-400	Installation of Low Frequency Underwater Locator Beacon	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 Non-rechargeable Lithium BatteryInstallations.The requirements for environmental protection and the associatedcertified noise and/ or emissi...	British Airways Master Data List No. BA-747-23-0022-MDL Issue 01<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/03/2019	Active	10069456
10069470	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR11239DS	505	Installation of High Skid Landing Gear and Crew Steps in accordance withMaster Drawing List AA-17071 in relation to FAASTC SR11239DS.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement AA-17096 No Revision,datedSeptember 18, 2018- Master Drawing List AA-17071 Revision C- Instructions for Continued Airworthiness AA-17062 No Revision, datedAugust 30, 2018- Instructions for Continued Airworthiness AA-18017 No Revision, datedAugust 30, 2018- Inst...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/04/2019	Active	10069470

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069514	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED		CAA UK RESPONSIBILITY	EC135 P1	Single Pilot VFR Conversion.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-27 Amendment 3 forthe following paragraphs: 27.1 (a); 27.301(a), (b); 27.303; 27.305 (a);27.307(a); 27.321(a); 27.337 (a);...	Rotorcraft Flight Manual Supplement FMS/160-002 Issue 3Instructions for Continued Airworthiness ICA/160-012 Issue 1Modification Leaflet & Certificate of Design Babcock/MOD/160 Issue 1Design Report DR/ 160-001 Issue 4or later revisions of the above listed document(s) approved/ acceptedunder the EASA sy...	This STC covers only EC135 P1(CDS) DPIFR helicopters equipped withanalogue instrumentation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect up...	03/04/2019	Active	10069514
10069522	COMMUTER AIR TECHNOLOGY Inc.		FAA SA03342CH	B300, B300C	Operating Weight Increase.Operating Weight Increase, increase gross weight to 7.484 kg (16,500 lb)MTOM.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: as per FAA STCSA03342CH.This certificate/ approval involves achange to the requirements forenvironmental protection or al...	- Operating Weight Increase in accordance with VJETS MasterData List1025750, at Revision N, dated January 23, 2017;- For the configuration 01, Airplane Flight Manual Supplement forOperating Weight Increase Beechcraft King Air Model B300 and B300C,Commuter Air Technology document 300V7001, at revisi...	If the older agrees to permit another entity to use this approval tomodify the product, the holder must give the other entity writtenevidence of that permission.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviou...	04/04/2019	Active	10069522
10069523	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		A319-112	AFMS MTOW ReductionRev 1: Transfer of STC from GVH Aerospace Ltd - United Kingdom, to GVHAerospace (Ireland) Limited	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	GVH Aerospace Airplane Flight Manual Supplement No. GVH-6286-03-FMS-01Issue 3;GVH Aerospace Airplane Master Data List No. GVH-6286-03-MDL-01 Issue 1;or later revisions of the above listed documents approved/accepted underthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/01/2021	Active	10069523
10069527	AIR COMM CORPORATION L.L.C		FAA STC SH5778SW	S-76A, S76B, S-76C	Addition of Electrically Driven Vapor Cycle, Freon or RefrigerantR-134a, Air Conditioning System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SH5778SW.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Drawing List DL-85-02-100, Revision AC, dated 19 April 2012, or laterFAA approved revision.FAA approved Rotorcraft Flight Manual Supplement, Document No. CR-S76-9,Rev. A, dated 4 March 1997, or later FAA approved revision.Instructions for Continued Airworthiness are contained in theMaintenance Manua...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/04/2019	Active	10069527
10069534	POLYTECH AERO SUPPORT INC.		TCCA SA19-12	A340-642 A340-312, A340-313, A340-541 A340-211, A340-212, A340-311	A340 Improved Air Filter Element - IDPRefer to MS-17-006 Modification Summary	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- MS-17-006 A340 Improved Air Filter Element Substitute ModificationSummary Rev 1;- EB 21-17-006-1 Engineering BulletinRev 0;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreem...	None	05/04/2019	Active	10069534

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069535	MICRO AERODYNAMICS, INC.		FAA STC SA00170SE	SEE FAA AML	Installation of vortex generators on the wings and tail surfaces	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00170SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Micro AeroDynamics, Inc. drawings and installation instructionsspecified on the attached FAA AML No. SA00170SE, dated 11 August 2006,or later FAA approved revision.NOTE: If more than five vortex generators are damaged or missing, theaircraft is not airworthy.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	10/04/2019	Active	10069535
10069537	SABENA TECHNICS BGC	REV. 1		A319-133 A319-132 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111 A318-112 A318-111	Aircraft structure reinforcement for ARINC 791 Large Antennainstallation on Airbus A318Revision 1 consisted of extension of STC applicability to the A319series aircraft (CEO models).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-25 at amendment 4paragraphs: 25.1, 25.23, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321,25.337, 25.341, 25.365, 25.561,...	- Master Data List, Aeroconseil document No. 0887-01-A-MDL-R01, Rev. 1dated 23 March 2020;- Instructions for Continued Airworthiness (for A318), Aeroconseil document No. 0887-01-A-ICA-R00, first issue dated 28 March 2019;- Instructions forContinued Airworthiness (for A319), Aeroconseil document No....	Limitations as per §3 (NDT inspections) of Instructions forContinuedAirworthiness documents referenced above.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introducee...	25/03/2020	Active	10069537
10069538	SABENA TECHNICS BGC	REV. 3		A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112	ARINC 791 Outside Antenna Equipment (OAE) installation and Ka-bandSystem Activation on Airbus A318Rev. 1 consisted of extension of STC applicability to the A319 seriesaircraft (CEO models).Rev. 2 consisted of validation of the installationwith the “StructureReinforcement Common Design” introduced b...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): - CRI C-0303-003 “Structural CertificationCriteria for Large Antenna Installations”, currently closed at issue 2,as far as applicableB...	Master Data List, Ref. 0910-01-A-MDL-R02 dated 30th September 2022Instructions for Continued Airworthiness, Ref. 0910-01-A-ICA-R02 dated15th September 2022Airplane Flight Manual Supplement, Ref. 0910-01-A-AFMS-R02, Rev. 2 dated08th November 2019or later revisions of the above listed document(s) appr...	Accomplishment of this STC requires the previous or concurrentembodiment of the following modifications, all designed by AEC:1. EASA STC 10069537 rev 1 (AEC ref. 0887-01) “Structure reinforcementfor A791 Large Antenna installation on Airbus A318/A319”OREASA STC 10080048 (AEC ref. 0887-03) “Structure...	07/10/2022	Active	10069538
10069541	AIRBUS DEFENCE AND SPACE S.A.	REV. 18		A330-202, A330-203, A330-243 A330-202/-203/-243	A330 MRTT STC – Approved Model List (AML)A specific A330 MRTT version is defined through the specific STC and theAML document which contains the associated technical documentationforthat specific version.-10029272 (A330 MRTT RAAF/ RSAF/UAETranche 1)-10063084 (A330 MRTT GOS)-10064192 (A330 MRTT FAF)...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows:ICAO Annex 16, vo...	A330 MRTT Approved Model List, ref. TEA-FA-AW-190015, issueW, dated 05June 2025<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/06/2025	Active	10069541
10069542	SABENA TECHNICS BOD	REV. 4		B300	ALSR Special Missions Aircraft – B300 (King Air 350 ER) - Rev 4Rev 4: Correction noise database entry as 14040.Rev 3: Removes msn limitation to allow reuse of ALSR 1 and 2 approveddesign to further applicable aircraft.Rev 2: Revised noise limitations.Rev 1: Revised AFMs limitations.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-23 Amd 0: 23.49,23.201, 23.203 and 23.207.Therequirements for environmental protection are unchanged butc...	- Installed in accordance with Certification Program Document Number:MCP-BC001-00-005, Issue 4,dated 27 February 2024 and Master Data Lists Document Number:MDL-S-00-4066, RevisionE,Dated 14 October 2024 and Document Number: MDL-S-99-4124,Revision B,Dated 12 February 2020.- Operated in accordance w...	Configuration: Aircraft build standard is a Beechcraft KingAir 300,with Pratt & Witney Canada PT6A-60A Engines and Hartzell HC-B4MP-3CPropellers with the following pre-requisite EASA Major Changesinstalled:- 10053290 - Replacement of 300 Amp Generator with 400 Amp.- 10059488 - Increased Gross Weigh...	02/12/2024	Active	10069542

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069544	SABENA TECHNICS BGC	REV. 2		A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112	WiFi/LTE Cabin Network activation on Airbus A318.Rev. 1: Extension of STC applicability to the A319 series aircraft (CEOmodels).Rev. 2: Update of the applicant's name and address.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4 paragraphs: 25.1, 25.23, 25.29, 25.601, 25.1301,25.1307, 25.1309, 25.1351, 25.1353, 25.1360, 25.143...	- Master Data List, Aeroconseil document No. 0908-01-A-MDL-R01, dated 03April 2020;- Instructions for Continued Airworthiness, Aeroconseil document No.0908-01-A-ICA-R01, Rev. 1issue dated 19 November 2019;- Airplane Flight Manual Supplement, Aeroconseil document No.0908-01-A-AFMS-R01, Rev. 1 dated 2...	- Limitations as per §3 of Airplane Flight Manual Supplement documentreferenced above.Accomplishment of this STC requires the previous accomplishment of thefollowing modification:- Mechanical & Electrical provisions, Minor Change Approval0897-02-A-MCA-R01, Rev. 1 or later approved revisions.Prior to...	09/01/2025	Active	10069544
10069551 (2004-2872)	SABENA TECHNICS BGC	REV. 2		ATR 72-212, ATE 72-212A ATR 72-212 A ATR 72-212 ATR 72-211 ATR 72-202 ATR 72-201, ATR 72-202 ATR 72-201 ATR 72-102 ATR 72-101, ATR 72-102 ATR 72-101 ATR 42-500 ATR 42-400 ATR 42-320 ATR 42-300 ATR 42-200, ATR 42-300 ATR 42-200	Conversion from a passenger-cargo “combi” configuration to a “Class ECargo” ConversionInitial issue: STC referenced EASA N°2004-2872 covering DGAC Franceapproval STC 176-SF-0163 rev 3Rev 0: STC Number changed to 10069551. Decompression Panel Installationfor Bulk Freighter Conversion on ATR 42 & ATRR...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25 at amdt. 4: 25.1, 25.301, 25.303, 25.305, 25.307, 25.331, 25.561,25.601, 25.603, 25.605, 25.607, 25.609...	Instructions for Continued Airworthiness:Rev 0: 0110-25-A-ICARev 01Rev 1: 0110-50-A-ICA Rev 00Rev 2: 0110-90-A-ICA Rev 00 dated 5 December 2023Master Data Lists:Initial issue: 0110-01-2103 Rev 4, 0110-05-A-2103 Rev 2 and0110-09-A-2103 rev 3, 0110-11-A-2103 Rev 1Rev 0: 0110-25-A-MDL Rev 02Rev 1: 0110...	As per AFMS, WBMS and ICA documents.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	14/12/2023	Active	10069551
10069553	B/E AEROSPACE, Inc. - FSI		FAA STC ST02582SE	737-700/-8/-800/-9/-900/-900ER	Lavatory modifications on Boeing 737-700/-800/-900/-900ER/-8/-9 seriesairplanes	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02582SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	B/E Aerospace, Inc. - FSI (B/E - FSI) Master Drawing List (MDL)B7FS755-D01, Revision B, dated 4 February 2019 or later Federal AviationAdministration (FAA) approved revision.Supplemental Instructions for Continued Airworthiness, B/E - FSIDocument B7FS755-D15-CL, Revision A, dated 15 February 2019, o...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/04/2019	Active	10069553
10069555	AVOX SYSTEMS Inc.		FAA ST03568NY	A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-223F/-243/-243F A330-201/-202/-203	AVOX LavOx A330 STCInstallation of AVOX LavOx Passenger Lavatory Oxygen System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): FAA Equivalent Levelof Safety (ELOS)-014CFR 25.1441(c) & 25.1443(c)the following paragraph(s) at a later amendment:Certification Specificati...	Installation Data List (IDL) Document No. 89574, Revision F, dated 30March 2015Instructions of Continued Airworthiness Document No. 89576 Revision A,dated 15 July 2015or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implementation...	Mandatory replacement times and/or inspection intervals defined inAirworthiness Limitation section of AVOX Systems Instructions forContinued Airworthiness Document No 89576 Revision A, dated 15 July2015.	08/04/2019	Active	10069555
10069558	AEROSPACE DESIGN & COMPLIANCE LLC		FAA ST04012NY	SAAB 340B/ SAAB SF340A	Installation of the Garmin GTX-3000 Automatic Dependent Surveillance - Broadcast (ADS-B) Out System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Aerospace Design & Compliance, LLC. Master Data List SF34-MDL-0016, RevA, dated 25 October 2018, or later FAA approved revision.Instructions for Continued Airworthiness (ICA) SF34-ICA-0016, Rev IR,dated 9 October 2018, or later FAA accepted revision.Aircraft Flight Manual Supplement (AFMS) SF34-AFMS...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC provides installation approval only for...	17/05/2019	Active	10069558

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069586	S-TEC CORPORATION		FAA STC SA09751DS	425 421, 421A, 421B, 421C 414, 414A	Installation of an S-TEC 01326 Digital Flight Control System (DFCS).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23:23.1306 Amdt 223.1308 Amdt 423.1309 Amdt 223.2540 Amdt 5The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	1. Master Data List No. ST-966-MDL-0001, Revision A, dated 24 September2018 or later FAA approved revision.2. Airplane Flight Manual Supplement, ST-966-AFMS-0001, Rev.-, dated 26September 2018, or later FAA approved revision.3. Instructions for Continued Airworthiness, ST-966-ICA-0001, Revision-,dat...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/04/2019	Active	10069586
10069594	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST04377CH	737-600/-700/-800/-900/-900ER	Installation of a Ballard webCS system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04377CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Astronics Armstrong Aerospace Master Data List, Document No.DC104-9841-00, Revision B, dated 11 February 2019, or laterFAA approvedrevision.FAA Approved Flight Manual Supplement,as identified in AstronicsArmstrong Aerospace Master Data List, Document No. DC104-9841-00,Revision B, dated 11 February...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/04/2019	Active	10069594
10069604	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			525, 525A, 525B, 525C	ADS-B OUT GNSS source modification for transponder 2.Replacement of Rockwell Collins GPS-4000S by Garmin GTN-7XX or GTN-6XXfor connection to transponder 2 (Rockwell Collins TDR-94).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification in accordance with MDL 2019-1-16 Revision IRand morespecifically Engineering Order 2019-1 Revision IR- Installation in accordance with Installation Procedure 2019-1-1Revision IR-Operation in accordance with Airplane FlightManual Supplement AFMS2019-1-8 Revision IR- Maintenance andw...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/04/2019	Active	10069604
10069607	ALOFT AEROARCHITECTS	REV. 2	FAA STC ST03741NY	A321-272NX A321-271N/-253N/-272N/-252 A321-252NX/-253NX/-271NX A321-231/-232/-/-251N/-251NX A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-232 A320-211/-212/-214/-216/-231 A319-131/-132/-133 A319-111/-112/-113/-114/-115	KA SATCOM Antenna System Installation. The STC consists in theinstallation of both external radome and antenna along with the internalantenna power supply unit and satellite modem.Rev. 1: Installation A319 Series Aircraft is added. In addition,installation on A321-111-112-131-211-212-213-231-232 air...	The Certification Basis for the original product as amendedby the following additional or alternative airworthinessrequirements:Equivalent Safety Finding(s): CRI B-4301-007 – Vibration and buffetingcompliance criteria for large external antenna installationthe following paragraph (s) at a later amen...	- MDL ViaSat document No. 1272199 Revision 045 and 1455658 revision 01and 1455659 revision 1- ICA ViaSat document No. 1277470 Revision 003- EWIS ICA ViaSat document No. 1277468 Revision 002 and 1459599 revision01 and 1459601 revision 01- AFMS ViaSat document No. 1277466 Revision 001- AFMS (A319) Via...	Limitations as per MDL 1455658 and per AFM supplements.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product....	11/02/2025	Active	10069607
10069610	CONCORDE BATTERY CORPORATION		FAA STC SR00917DE	S-92A	Installation of Concorde VRLA Battery	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00917DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Document No. 5-0365, Master Drawing List, Sikorsky S-92A BatteryReplacement, Revision N/C, dated 19 September 2018, FAAapproved 2November 2018, or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Document No. 5-0604,Revision IR, dated 19 September 2018, FAA accepted 2 Nov...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/04/2019	Active	10069610

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069611	PMV ENGINEERING			A350-941, A350-1041	Installation of a portable EFB arm mount on A350	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 at amdt 13:25.301, 25.303, 25.305, 25.307, 25.561, 25.601, 25.611, 25.625, 25.789,25.803, 25.853, 25.1301, 25.1519, 2...	- Master Document List ref. AVI-01340-MDL-R00 dated 19 MAR 2019- AFM Supplement ref. AVI-01340-AFMS-S01-R01 dated 20 JULY 2017- Instructions for Continued Airworthiness ref. AVI-01340-ICA-S01-R02dated 01 MAR 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA syste...	- Per AFM supplement ref. AVI-01340-AFMS.- Per ICA ref. AVI-01340-ICA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness...	12/04/2019	Active	10069611
10069614	IKHANA GROUP, LLC	REV. 3	FAA STC SA02682LA	DHC-6 SERIES 300	DHC-6-300 Max Take-off Weight Increase up to 6350 kg (14,000 lbs),Increase of Landing Weight up to 6260 kg (13,800 lbs), Installation ofPT6A-34 engines rated at 750 SHP and Hartzell HC-D4N-3A / D9515 4-bladedpropellers as defined in IKHANAAircraft Services Installation DrawingList ER218-3000, Rev.R...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-23, incl. Amdt. 4:23.1, 23.3, 23.21, 23.23, 23.25, 23.29, 23.33, 23.45, 23.49, 23.51,23.53, 23.55, 23.57, 23.59, 23.61,...	Airplane Flight Manual Supplement (AFMS) HGLD-63-1A, Rev. IRMaintenance Manual Supplement (MMS) HGLD-63-2, Rev. IRor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Landplane only	03/11/2021	Active	10069614
10069616	GVH AEROSPACE LIMITED		CAA UK RESPONSIBILITY	GVI (G650)	Introduction of Underwater Locator Device	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition; CRI F-01 Non-rechargeable Lithium batteryInstallations.The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	- GVH Aerospace Instructions for Continued Airworthiness No.GVH-9865-01-ICA-01 Issue 1- GVH Aerospace Master Data List No. GVH-9865-01-MDL-01 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/04/2019	Active	10069616
10069617	CHIPPEWA AEROSPACE, Inc.		FAA STC ST04443AT	ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102 ATR 42-320, ATR 42-500 ATR 42-200, ATR 42-300	Replacement of the HT1000 MCDU (Multi-Function Control Display Unit)with the HT9100 MCDU	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04443AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Chippewa Aerospace Master Drawing List (MDL) No. 42-3461-02-0001, Rev.IR, dated 26 August 2018, or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Chippewa Document No.42-3461-02-0002, Rev. IR, dated 26 August 2018, or later FAA acceptedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	15/04/2019	Active	10069617
10069619	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST04081NY	SEE FAA AML	Installation of Aviation Technical Services CargoTekTM.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04081NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Delta Engineering Approved Model List 0164-10671-2501 Revision C dated26 April 2019.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	03/06/2019	Active	10069619

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069621	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04314AT-D	GIV, GV	Installation of Honeywell Laseref IV IRU	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04314AT-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	Gulfstream Aerospace Corporation Index List CE511138001, Revision A,dated 3 October 2018, or later FAA approved revision.FAA accepted Instructions for Continued Airworthiness:- GVModel: CE51113A001, Revision A, dated 26 July 2018, or later FAAapproved revision.- G-IV Model: CE41113A001, dated 28 Au...	For Gulfstream GV aircraft, the STC is limited to serial numbers 501 -584 without Gulfstream ASC 82.For Gulfstream G-IVaircraft:- Application of the -01 Configuration is only approved to replaceLASERREF II or III and is not approved for an AHRS replacement.- Application of the -03 Configuration isn...	27/08/2019	Active	10069621
10069622	BOMBARDIER Inc.	REV. 1	TCCA SA18-132 ISSUE 1	BD-700-2A12	Installation, Aircraft Completion ModificationRev. 1: Update of the STC holder address.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-25 Amendment 19The requirements for environmental protection and the associatedcertified noise and/ or emissions levels...	Configuration Definition Record, Bombardier Inc. document No.RAZ-BM700-164 Revision D,dated 10 April 2019Supplemental Airplane Flight Manual, Bombardier Inc. document No.GCA-7500-001 Revision Basic,dated 9 November 2018Instructions for Continued Airworthiness, Bombardier Inc. document No.GCXXXXX7500...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/04/2023	Active	10069622
10069624	DELTA ENGINEERING CORPORATION		FAA ST04072NY	777-300ER	Installation of a Cabin Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Delta Engineering Master Data List 0143-10482-2455 RevisionA dated 8January 2019 or later FAA approved revisions.Instructions for Continued Airworthiness as listed on the Master DataList.	For Master Data List Configuration 1 STC 10014897 (ST02530NY) isrequired.For Master Data List Configuration 1 Air France Industries ServiceBulletin AFSB-B777-18-004-25-002 and SRTService BulletinC.OAEZ-001858-CCS are required prior to installing this STC.For Master Data List Configuration 1 Air Fra...	15/04/2019	Active	10069624
10069627	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		KODIAK 100	Installation of MTV-27-() propeller on the Quest Kodiak 100.This modification removes the existing reversing and full featheringHartzell propeller with the appropriate spinner andreplaces it with thefive blade MTV-27-1-E-C-F-R(P)/ CFR240-55() propeller and spinner.The existing governor and engine co...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): ESF-D23.855-01.- The following paragraph(s) at a later amendment: CS23 Amdt 3 for thefollowing paragraphs: 23.45, 23.49, 23.51, 23.53, 23.6...	According to MT-Propeller Master Documentation List No. E-3113 Rev. 5dated 03/02/2021- To be operated in accordance with MT-Propeller AFM-S Document No.E-3115 Rev. 0 dated 04/04/2019- To be installed i.a.w. Installation Instruction Doc. No. E-3116 Rev. 3dated 06/02/2020- To be maintained i.a.w. MT-P...	Note: This STC is compatible with the EASA STC 10061979 from Aerocet,Inc.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthin...	04/02/2021	Active	10069627
10069642	STC TWENTY ONE LIMITED	REV. 1	CAA UK RESPONSIBILITY	737-400	Carriage of Horses and Other Animals.Revision 1: “Limitations/ Conditions” updated to remove reference EASASTC 10015780.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01 “Fire protection ofessentialsystems/equipment within class E cargo compartment”; CRI D-02“Installation of Seats on a B737-400 converted fre...	-Flight Manual Supplement S21.FMS-0154 Issue 3- Master Document List S21.MDL-1416 Issue 3or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	The Following EASA STCs must have been previously embodied or embodiedconcurrently with this design change: EASA STC 10015732(EASA.IM.A.S.01754) and EASA STC 10033161.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherp...	24/05/2019	Active	10069642

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069670	AERO-DIENST GMBH			55, 55B, 55C	GPS WAAS Antenna InstallationInstallation of a GPS WAAS antenna for an ADS-B transponderinstallation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- According to Aero-Dienst Master Document List No. 20310-LJ.DC-101, Rev00- To be maintained iaw. Aero-Dienst ICA Document No. 20310-LJ.DC-105,Rev 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC may only be installed in conjunction with ACSS NXG-900 GPSReceiver installation i.a.w. EASA STC No. 10063824 /FAA STC No.ST02632LA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change...	17/04/2019	Active	10069670
10069683	MORSON PROJECTS LIMITED	REV. 2	CAA UK RESPONSIBILITY	680A (LATITUDE)	Approval of Antenna Structural Provision under Morson Projects LtdModification ref MP0030A.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation in accordance with Morson Projects Ltd Modification refMP0030A and Service Bulletin ref SB.MP51-036.- Instructions for continued airworthiness in accordance with MorsonProjects Ltd ICA ref MPL-C-04-AW0141 Iss 2, dated April 2019.- There is no Flight Manual change associated with this-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/04/2019	Active	10069683
10069691	ALTITUDE AEROSPACE INC.		TCCA SA19-35 ISSUE 1	CL-600-2B19 (RJ SERIES 100)	Replacement of the Passenger Door Piano Hinge	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Altitude Aerospace Inc. Instructions for Continued Airworthiness No.ICA-AA601R-008 Revision A- Altitude Aerospace Inc. Master Document List No. MDL-AA601R-008Revision Aor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implementat...	This approval is subject to the limitations specified in TCCA ADCF-2012-13 in accordance with TCCA Alternative Means ofCompliance(AMOC) Alleviation No. AARDG 2019/ A13.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any other...	23/04/2019	Active	10069691
10069695	ROCKWELL COLLINS, Inc.		FAA STC ST02173LA	400A	Modification and replacement of existing Rockwell Collins dual AttitudeHeading Reference System (AHRS) AHS-85E with Rockwell Collins dual(AHRS) AHS-3000A.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02173LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Cutter Aviation Master Data List Document No. 60308-00, Revision "A",dated 4 November 2008, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/04/2019	Active	10069695
10069697	EICHELSDOERFER GmbHFLUGZEUGBAU	REV. 1		SEE EASA APPROVED MODEL LIST	Covering and recovering of sailplanes and powered sailplanes with“Ceconite” polyester cover.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Covering and recovering with “ceconite” polyester fabric inaccordancewith Eichelsdörfer Technische Mitteilung Nr. 005-18, at Revision 3,dated January 7, 2020.or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/01/2020	Active	10069697
10069698	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR02484LA	R66	Installation of Emergency Float System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Master Document List MD66-1 Rev. D dated 14 June 2017-Rotorcraft Flight Manual Supplement FM66-1 Rev. A dated 13 March2015-Instruction for Continued Airworthiness ICA66-1 Rev. Edated 14 July2017or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance wit...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/04/2019	Active	10069698

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069700	CHIPPEWA AEROSPACE, Inc.		FAA STC ST04437AT	ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102 ATR 42-500 ATR 42-300, ATR 42-320 ATR 42-200	Replacement/Upgrade of HT1000 NRP (Nav Processor Unit) and the HT9100NRP.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04437AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Chippewa Aerospace Master Drawing List (MDL) No. 42-3461-01-0001, RevIR, Dated 26 August 2018, or later FAA approvedrevision.2. Instructions for Continued Airworthiness (ICA),Chippewa Aerospaceinc. Document No. 42-3461-01-0002, Rev IR, Dated 2 August 2018, or laterFAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/06/2019	Active	10069700
10069710	AERO-DIENST GMBH			55C 55B 55	Replacement of the GA100 CVR by the L3 FA2100 CVR	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Non-rechargeable Lithium Battery InstallationsThe requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	- According to Aero-Dienst Master Document List No. 20311-LJ.DC-101, Rev00;- To be operated iaw. with Aero-Dienst AFM-SDocument No.20311-LJ.DC-106, Rev 00;- To be maintained iaw.Aero-Dienst ICA Document No. 20311-LJ.DC-105,Rev 00;or later revisions of the above listed document(s) approved/ accepted...	None	24/04/2019	Active	10069710
10069712	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST00912DE	GULFSTREAM 200/ GALAXY	Installation of Future Air Navigation System (FANS) 1IA+, Remote OceanicController Pilot Data Link Communications (CPDLC), Automatic DependentSurveillance - Contract (ADS-C), and CPDLC Departure Clearance (CPDLC-DCL) applications through replacement of the existing HoneywellAirborne Flight Informatio...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except when amended by additional or lateramendments if indicated on FAA STC ST00912DE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	1. Master Drawing List E-TM-17-0002, Rev. 8, accepted 13 February 2019,or later FAA accepted revision.2. Instructions for Continued Airworthiness E-TM-17-0008, Rev. IR, dated31 January 2019, FAA approved 20 February 2019, or later FAA approvedrevision.3. Airplane Flight Manual Supplement E-TM-17-000...	A prerequisite to this STC is the update of the existing Pro Line 4Flight Management Computers (FMC) software to version 4.0 or laterapproved versions.This STC does not provide the necessary "Operational Approval" for theuse of the FANS 1/A+ functions.This STC is specific to the following aircraft s...	07/12/2021	Active	10069712
10069713	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04309AT-D	GVI (G650)	Installation of Iridium SATCOM System (FANS-1/A+ Over Iridium).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04309AT-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Gulfstream Aerospace Corporation Index List GDL100000028, Revision (-), dated 23 July 2018, or later FAA approved revision.2. Airplane Flight Manual Supplement, CE61 203M001, Revision (-), dated23 July 2018, or later FAA approved revision.3. Airplane Flight Manual Supplement, CE61 203M002, Revisio...	1. Iridium SATCOM System requires FANS-1/A+ to operate; therefore,FANS-1/A+ must be installed prior to or concurrently with this STC.2. This STC DOES NOT approve the installation of Iridium SATCOM System(FANS-1/A+ Over Iridium) on an aircraft that already equipped with anInmasat data link system, th...	24/04/2019	Active	10069713
10069725	URBE AERO GmbH			200	TDR94D transponder upgrade ADS-B OUT for CS-ACNS complianceFor BeechKing Air 200 aircraft serial number BB1569Upgrade from a Collins TDR94D P/N 622-9210-007 Transponder to aP/ N622-9210-501 for ADS-B out compliance with CS-ACNS.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation in accordance with Engineering Order doc: DOE / F 01,Project No. 147, Issue 01-Operation in accordance with Supplement to the Airplane Flight Manual,Doc. No. AFM-147-01, Date of Issue 29-Mar-2019-Maintenance and Instructions for Continued Airworthiness in accordancewith Doc. No. AMM...	Installation limited to Beech King Air 200 aircraft with serial numberBB1569Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	25/04/2019	Active	10069725

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069731	SABENA TECHNICS BGC	REV. 3		A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303	Cabin Reconfiguration to 295 PAX with iFE Rave System on A330-300.Revision 1 consisted of a full cabin reconfiguration to reach 295 pax(30B/C, 21PY/C, 244Y/C) and a newly installation of the ZII Rave IFEsystem.Revision 2 with extension to pre-mod configuration as recorded in MasterData List.Revision...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): - CRI D-3327-001 (PN 10054095) “Incorporation ofinertia device in dynamic seats”,- CRI F-01 (PN 10054095) “ Securityprotection of aircraft systems an...	- Instructions for continued airworthiness 40121-02-A-ICA-R00- OSD Change Document 40121-02-A-OSDCD-R00- Master Data List 40121-02-A-MDL-R01- Aircraft Flight Manual Supplement re.: 40121-02-A-AFMS R00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCfor all configurations requires the simultaneous accomplishment of thefollowing modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik A G,STC No. 10014507 Rev. 02Prior to installation of this change/ repa...	14/02/2020	Active	10069731
10069736	AIRBUS S.A.S.	REV. 1		A319-131/-132/-133 A319-112 A319-111/-112/-113/-114/-115	SEATS AND EMER. EQUIPMENT MODIFICATIONChange to the existing cabin arrangement to increase overall seatingcapacity from"Zero Occupancy" Airbus Mod to 156 PAX forA319 VOLOTEAaircraft.Revision 1: Integration of the models: A319-111 / A319-113 / A319-114 /A319-115 /A319-131 / A319-132 / A319-133 in a...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MAS AI0077 issue 01AIS-AJA-18101 issue 03 Certification Summary Report MOD AI0077AIS-AJA-18104 issue A - Cabin Safety Inspection MOD AI0077MAS AI0077 issue 02AIS-AJA-20053 Issue 5Certification Summary Report STC Major Changeor later revisions of the above listed document (s) approved/ acceptedunder t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/12/2020	Active	10069736
10069737	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.	REV. 1		A321-271N/-271NX/-272N/-272NX A321-253N/-253NX A321-252N/-252NX A321-251N/-251NX A321-211/-212/-213/-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-114/-115	Placards & markings MMEL SupplementThis Standalone MMEL supplement is used for the management of missing orunreadable placards and markings. Rev 1: applicability list extended toother models	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Stand-alone Master Minimum Equipment List JCAERO/MMEL/0230-1 Rev. 3.0Placards categorisation for Stand-alone Master Minimum Equipment ListInterior and Exterior as listed in JCAERO/MDL/0230 Rev. 2.1:-SDM110JCAERO0847 REV D-SDM110JCAERO0848 REV C-SDM110JCAERO0897 REV D-SDM110JCAERO0898 REV C-NVD110JCA...	The Stand-Alone MMEL must be used with J<(>&<)>C Aero EEU Ltd. Minorchanges No. JCAERO/MODC/0092, JCAERO/MODC/0110, JCAERO/MODC/ 0113,JCAERO/MODC/0114, JCAERO/MODC/0326 and JCAERO/MODC/0368 installed. ThisMMEL Supplement shall be used together with the Interior and ExteriorPlacards catalogues referen...	24/06/2020	Active	10069737
10069751	PRATT & WHITNEY			A321-231, -232 A321-211, -212, -213 A321-111, -112, -131	Installation of a Pratt & Whitney enhanced Flight Data AcquisitionStorage and Transmission (eFAST) system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST11213DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. "Data List, Compliance Data, Pratt & Whitney eFASTtm, A321, ODA STC,"document DL2009M00, revision E, dated 8 January2018, or later FAAapproved revision. 2. "Instructions for Continued Airworthiness for eFAST Health ManagementComputer," document PWA-11557, revision C, dated 3 November 2017 orlater...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/04/2019	Active	10069751
10069756	ETIHAD AIRWAYS ENGINEERING L.L.C.	REV. 2		A321-231 A320-232	PASSENGER CABIN RECONFIGURATIONApplicability to the A320-232 with the introduction of several cabinmodification including (the list is not exhaustive): Removal of C1 andC2 stowages and installation of windscreen partitions instead. Removalof 2 rows of B/C seats and re-pitching as per post-mod LOPA (...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-0306-000 Application of heat release and smokedensity requirements to seat materialsthe following paragraph(s) at a later amendment: CS 25.785(b) a...	Master Document List EA2-18250657-DL01 issue 3or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	This revision is applicable to the A320-232 only.	15/07/2019	Active	10069756

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069757	DOA21 LIMITED	REV. 1		A330-243	Introduction of a Cabin VIP InteriorRev. 1: Transfer of STCholder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):CRI D-01 Injury Criteria for Side Facing Divans (Sofas)CRI F-01 Lithium Battery Installationsthe following paragraph(s) at a later amendm...	- STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0132 Issue 1- STC Twenty One Ltd Maintenance Manual / AWL Supplement No.S21.AMMS-0036 Issue 1- STC Twenty One Ltd Master Document List No. S21. MDL-1287 Issue 1or later revisions ofthe above listed document(s) approved/acceptedunder the EASA...	Restricted to MSN 0451Airworthiness approval of this designchange does not constituteoperational approval of transmitting portable electronic devices (T-PEDs). The operator should seek, as required, operational approval of TPEDs with the National Aviation Authorityresponsible for the registry of th...	24/10/2023	Active	10069757
10069769	ACC AIRCRAFT CABIN COMPONENTS GmbH			PA-28-180 (ARCHER)	Modification of Piper PA-28-180 S/N 28-7305200 rear seats to accommodate3 children	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ACC Master Document List MDL1022, dated 30.04.2019- ACC Flight Manual Supplement MAS1022-01, Issue A, dated 08.04.2019- ACC Instructions for Continuous Airworthiness, Issue A, dated08.04.2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Installation applicable to S/N 28-7505200 only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce noadverseeffect upon the airworthiness of the product.	02/05/2019	Active	10069769
10069770	ROSEN SUNVISOR SYSTEMS L.L.C.	REV. 1	FAA STC SR00840DE	SEE FAA APPROVED MODEL LIST	Installation of the Rosen Sunvisor System into the RobinsonR22, R44 andR66	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00840DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Rosen MDL 2091000-DL (Doc 9050-2091-001), Revision C, dated 7October 2016 or later FAA approved revision.2. Instructions for Continued Airworthiness Document: "ProductMaintenance Manual with Illustrated Parts List and Instructions forContinued Airworthiness", 9100-2091-000, Revision B, dated 13...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	22/07/2019	Active	10069770
10069779	FOKKER SERVICES B.V.	REV. 3		747-400F 747-400	Activated GNSS Stand-Alone provisions for ADS-B Out.This STC activates the provisions introduced with EASA STC 10068342on747-400F and introduces activated provisions on 747-400.(Revision 1, Revision 2 and Revision 3 were issued to correctinformation on the certificate)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Initial issue ofCS-ACNS, CS ACNS.D.ADSB.090, CS ACNS.D.ADSB.100The requirements for environmental protection and the assoc...	The change is defined through issue 1 of Fokker Master DataListdocument B747-GNSS-MDL-0002The aircraft shall be operated in accordance with Revision 1 of AirplaneFlight Manual Supplement document B747-ADSB-AFM-S-001.The aircraft shall be maintained in accordance with Issue 2 theInstructions for con...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/06/2019	Active	10069779
10069780	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges	REV. 1		SEE EASA APPROVED MODEL LIST	AML STC for ELT InstallationEASA AML STC for installation of portable and survival type ELT's onvarious aircraft types.The following equipment are approved with thisSTC: KANNAD/ OROLIA P/N S1820502-(), S1823502-(), S1850501-(),S1863501-(),TECHTEST P/N 500-32-2Y-G(), 500-32-2Y-H(), EXAIL P/N12N67880...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI F-01, Non-rechargeable Lithium BatteryInstallations, Issue 2.- The following paragraph(s) at a later amendment: CS 25.29, CS 25.56...	Engineering Order, Doc No. EO_M990001055_DBE_04032019, Rev 2Instructions for Continued Airworthiness, Doc No.ICA_M990001055_DBE_04032019, Rev 2Aircraft Manual Supplement, Doc No. AMS_M990001055_DBE_27032019, Rev 2or later revisions of the above listed document(s) approved/ acceptedunder the EASA syst...	The automatic function of the automatic portable ELTs is not covered bythis STC, it can be used as portable ELT only. Each individualinstallation requires an approved installationposition and attachment.Prior to installation of this change/repair it must be determined thatthe interrelationship betw...	24/08/2023	Active	10069780

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069783	APTOZ EHF.	REV. 1		767-300	Icelandair Change ref. CRA-767-3450-014 Revision B, Navigation -Dependent Position Determining - DO-260B Transponder upgrade to meet theEASA/FAA 2020 Mandate.This change consists in accordance with Icelandair CRA-767-3450-014Revision B document of installation of either a DO-260B Mode-Stransponder w...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The certification basis for changed areas by this change is CS-25Amendment No. 21 and CS-ACNS initial issue. Those areas of the aircraftthat remain unchangedc...	Icelandair ICA document reference CAI-767-3450-014 RevisionAIcelandair AFM-S document reference AFM-767-3450-014, Rev Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplanes modified with this STC must be:- Operated in accordance with Icelandair AFM-S document referenceAFM-767-3450-014, Rev A.- Maintained in accordance with Icelandair ICA document referenceCAI-767-3450-014 Revision APrior to installation of this change/repair it must be determined thatthe int...	27/05/2025	Active	10069783
10069788	BELL HELICOPTER TEXTRON, Inc.	REV. 1	FAA STC SR11240DS	505	Installation of Tail Rotor Gearbox Cover	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11240DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List, Report No. AA-17122, No Revision, dated 15January 2019, or later FAA approved revision.2. Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-17118, No Revision, dated 14 August 2018, or later FAAaccepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/05/2019	Active	10069788
10069792	ALPINE AEROTECH LP		TCCA STC NO. SH19-6	429	Deep Snow Kit Installation, composed of two Bear Paws at the aft end ofthe skid, two “yeti paws” at the forward end of the skis and a tractionpad running between the paws, along with the associated clamps andhardware.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	-Installation Instruction AAL-490-015-002, Rev. NI dated October 19,2018-Instructions for Continued Airworthiness AAL-490-015-702, Rev. NI datedOctober 19, 2018-Master Data List AAL-490-014-002, Rev. NI dated October 19, 2018or later revisions of the above listed document(s) approved/accepted onbeha...	Deep Snow Kit Installation is not compatible with the Wheeled LandingGearPrior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthine...	07/05/2019	Active	10069792
10069795	BOMBARDIER Inc.	REV. 2	TCCA SA19-13	CL-600-2B16 (604 VARIANT) BD-700-2A12 BD-700-1A11 BD-700-1A10 BD-100-1A10	EASA Validation of Transport Canada Supplemental Type Certificate (STC) SA19-13Installation, Fire Extinguishers with Halocarbon Clean ExtinguishingAgentsModification must be in accordance with the following B/E Aerospace Ltd.Documents:For BD-100-1A10 aircraft model: Modification Data Summary M293001N...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: EASA CS 25.851(a) and(c) at amendment 12; for BD-700-1A10 andBD-700-1A11, EASA CS 25.851(a)and (c) at amendment 13.The re...	Modification must be in accordance with the following B/E Aerospace Ltd.Documents:-For BD-100-1A10 aircraft model: Modification Data Summary M293001 RevNC, 13th March 2019 or later approved revisions, and-For CL-600-2B16 aircraft model: Modification Data Summary M293000 RevNC, 13th March 2019 or lat...	See those of original TCCA STC SA19-13. This EASA STC airworthinessapproval is limited to the following Fire Extinguisher Suppliers - component part numbers (P/N’s):Kidde – Component P/N: 476288, andTyco/Ansul – Component P/N: ASF429599, andP3 Hafex TM – Component P/N: P3APP003010D, andTyco Fire Prot...	02/08/2019	Active	10069795
10069824	SAAB AB	REV. 2		B200GT	SATCOM system Flightcell DZMx with Cabin Intercom / Attendant CallThis change installs the following modifications:- SATCOM capability via Iridium satellites.- Intercom and Attendant Call.The system consists of dual control heads giving the capability for useboth from the cockpit and from the cabin....	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 23.301, 23.303, 23.305,23.307, 23.561, 23.571, 23.603, 23.609, 23.613, 23.771, 23.773, 23.777,23.853, 23.1301, 23.1309, 23...	- Change definition according to the Scope of Work, TDM19-05-SoW,Revision A, dated 2019-03-13 and to the Master Data List TDM19-05-0-LEPRevision B, dated 2019-05-06-Installation according to Installation Data, TDM19-05-3-ID, RevisionA, dated 2019-03-01 and Manufacturing data, TDM19-05-2-MD, Revisio...	This change is only applicable to Beech 200GT with Fusion avionics.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of...	07/12/2023	Active	10069824

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069829	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BAE 146 SERIES 100	Approval of P-RNAV and LNAV RNP Approach	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0157 Issue 1- STC Twenty One Ltd Maintenance Manual / AWL Supplement No.S21.AMMS-0038 Issue 1- STC Twenty One Ltd Master Minimum Equipment List SupplementNo. S21.MMEL-0023 Issue 1,,- STC Twenty One Ltd Master Document List No. S21. MDL-1485Is...	Restricted to MSN E1144.STC Twenty One Limited Design Change S21.34-25-1194 must be embodiedprior to embodiment of thisDesign Change.This Design Change is limited to non-EFIS equipped aircraft only.Unless the alleviation conditions listedwithin Master Minimum EquipmentList Supplement S21.MMEL-0023...	09/05/2019	Active	10069829
10069831 (EASA.IM.A.S.00253)	SAFRAN CABIN INC.	REV. 1	FAA ST01408LA	CL-600-2B19	Installation of Reinforced Cockpit Doors with Flight Deck Access System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	C & D Interiors Controlled Drawing List, 4631000, Revision B, dated 9December 2002, or later FAA approved revision.	Equipment Functional Check Intervals as defined in FAA approved C & DInteriors Report CDR4635-69, Revision A, dated 8 November 2002,“Certification Maintenance Requirements”, or any later FAA approvedrevision, shall not be extended. Later revisions to C & D AerospaceReport CDR4635-69 may be used onl...	09/05/2019	Active	10069831
10069838	HONEYWELL INTERNATIONAL Inc.	REV. 1	FAA ST04269CH	737-800, 737-900ER 737-500, 737-700	Retrofit installation of Honeywell TRA-100B Automatic DependentSurveillance - Broadcast (ADS-B) Out ATC Transponder System.Rev. 1: Transfer from "CertifyNation, LLC." to "Honeywell International,Inc.".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 Initial issue: 25.29(a)(b); 25.301(a)(b); 25.303; 25.305(a)(b); 25.307(a);25.561(c)(d); 25.601; 25.611; 25.777(a); 25....	- Airplane Flight Manual Supplement CN17-023AFM-01, Revision 0- Master Data List CN17-023MDL-00, Revision 3or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.,,,,	17/09/2024	Active	10069838
10069859	E A D AEROSPACE AIRWORTHINESS			B200	ASPIRE 200 SATCOM INSTALLATION ON B200The STC installs:- Honeywell AMT-3800 HGA (High Gain Antenna) on top on aircraftfuselage.- LRU (ASPIRE 200 suite & SCOTTY SCP video server) inside the aircraftfor antenna and communication management.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:23.143, 23.145, 23.153, 23.161, 23.173 from FAR 23 at amendment 14;23.573 from FAR 23 at amendment 45<(>,<)>23.1301 from FA...	- Change according to Master Document List, 01562-EAS-A-MDL, Rev. C,dated 4 JUN 2019 as described in Supplemental Type Design,01562-EAS-A-STD-01, Revision C, dated JUN 2019- Airworthiness Limitations and maintenance in accordance withInstructions for continued airworthiness supplement, 01562-EAS-A-I...	This STC shall be installed concurrently with or after EASASTC 10069860. This STC also requires prior installation of EASA STC 10033158 rev. 5 or later as applicable.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any other...	18/06/2019	Active	10069859
10069860	SABENA TECHNICS BOD	REV. 3		B200 SUPER KING AIR B200	King Air B200 Monitoring System - Configurations 1, 2, 3 - with revisednoise levels	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase and/or emission levels.	- Installed in accordance with Certification Program, Document NumberMCP-BC003-00-001, Issue 17,Dated 10 June 2022 and Master Data List Document Number MDL-S-00-4161,Issue D, Dated 22 June 2022.- Operated in accordance with Aircraft FlightManual Supplement (AFMS)<(>,<)>Document Number: AFMS-BC003-0...	- Configuration: Aircraft build standard is a Beechcraft King Air B200,modified with the following Engine and Propellerpre-requisite STCs:STC 10040181 (FAA STC SA02715CH-D) - Pratt & Whitney Canada PT6A-52engines.STC 10031275 (FAA STC SA2698NM-S) - Quiet Turbofan Propellers HartzellHC-D4N-3A propel...	24/06/2022	Active	10069860

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069861	UNICAL AERO INC.		FAA STC ST02670LA	737-900ER 737-900 737-800 737-700 737-600 737-500 737-400 737-300 737-200 737-100	Installation of Unical Aero USB-PED Charging System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02670LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List Document No. MDL16-008, Revision B, dated 8 December2017, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	13/05/2019	Active	10069861
10069872	APTOZ EHF.	REV. 2		757-300 757-200PF 757-200, 757-200PF, 757-300 757-200	Icelandair Change ref. CRA-757-3450-046 Rev.G, Navigation - DependentPosition Determining DO-260B Transponder upgrade to meet the EASA/ FAA2020 Mandate.Rev. 1: This change consistsin accordance with IcelandairCRA-757-3450-046 Rev.G document of installation of either a DO-260BMode-S transponder with1...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) were considered at CS-25 Amendment 21 for theB757-200 series, B757-200PF series and 757-300 series:CS 25.1, 25.29(a)(b), 25.301(a),...	- Icelandair AFM-S document reference AFM-757-3450-046 Rev B.- Icelandair ICA document reference CAI-757-3450-046 Rev.D- Icelandair Change Repair Approval Document reference CRA-757-3450-046Revisio n Gor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplanes modified with this STC must be:- Operated in accordance with Icelandair AFM-S document referenceAFM-757-3450-046 Rev B.- Maintained in accordance with Icelandair ICA document referenceCAI-757-3450-046 Rev D.Prior to installationof this change/repair it must be determined thatthe interrel...	27/05/2025	Active	10069872
10069884	GARMIN INTERNATIONAL, Inc.	REV. 1	FAA STC SR02622SE	SEE FAA APPROVED MODEL LIST	Installation of Garmin G500H TXi Display System (Primary Flight Display(PFD), Multi-Function Display (MFD))	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02622SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	-Garmin Master Drawing List (MDL) 005-01297-00 Rev.1, dated16 November2018 or later FAA approved revision.- Garmin Rotorcraft Flight Manual Supplement (RFMS) 190-02401-02 Rev. 1,dated 16 November 2018 or later FAA approved revision.-Garmin Maintenance Manual (includes Instructions for ContinuedAirwor...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List FAA STC SR02622SE dated 5 August2020.A Garmin GPS Navigator source must be available to support the G500H TXiAvionics Display System.Rotorcraft that are modified per this STC are limited to VFRP...	11/11/2020	Active	10069884
10069903	B/E AEROSPACE, Inc.		FAA STC ST04446AT	747-400/-400F/-8/-8F	Installation of the Rockwell Collins Automatic Dependent Surveillance-Broadcast (ADS-B) Out System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04446AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Drawing List (MDL) 2-203317-001, Revision B, dated20 March2019, or later FAA approved revision.- Airplane Flight Manual Supplement 2-203317-805, Revision IR, dated 15April 2019, or later FAA approved revision.- Instructions for Continued Airworthiness (ICA) Document 2-203317-804,Revision B...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/05/2019	Active	10069903
10069906	AIRCRAFT SYSTEMS AND MANUFACTURIN G,Inc.	REV. 5	FAA STC ST03885AT	SEE FAA AML SEE EASA APPROVED MODEL LIST	Installation of an Avionica, Inc. avCM Cellular ModuleThe Cellular Module mount directly on the following Avionica QuickAccess Recorders installed by other STC's: MK-III mini QAR,avRDC QAR,or avRDC MAX QAR. The avCM is intended to provideQAR data transfer overthe cellular network when the aircraft...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 amdt 25: 25.1,25.21(a)(1), 25.301, 25.1301 (a)(1) (a)(2) (a)(3) (a)(4), 25.1309 (a) (b)(c) (d) (e) (f), 25...	- Configuration 1 3G avCM with battery, Instructions for ContinuedAirworthiness 100600-504, Revision D, dated 10 April 2015, or later FAAaccepted revisions.- Configuration 2 4G avCM installed in accordance with section 5.0 ofMaster Data List 100600-001, Instructions for Continued Airworthiness170795...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	05/05/2025	Active	10069906

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069922	SMR ACQUISITION LLCdba SMR TECHNOLOGIES, INC		FAA STC SA00332BO	PA-32R-301T (SARATOGA II TC) PA-32R-301 (SARATOGA SP) PA-32R-301 (SARATOGA II HP) PA-32-301XTC (PIPER 6XT) PA-32-301T (TURBO SARATOGA) PA-32-301 (SARATOGA) PA-32-301FT (PIPER 6X)	Installation of non-hazard ice protection system kits SMR9065-11,SMR9065-12, SMR9065-14, SMR9065-1 5, SMR9065-16<(>,<) >SMR9065-17,SMR9065-24, SMR9065-25, SMR9065-30, SMR9065-31, SMR9065-40, SMR9065-60,SMR9065-61<(>,<)> SMR9065-62, SMR9065-63, SMR9065-64, SMR9065-65,SMR9065-66, SMR9065-67, SMR9065-6...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00332BO.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Installation Instructions as listed on MDL-0065, Revision H, dated 12September 2014, or later FAA approved revisions.2. The following Airplane Flight Manual Supplement (s) (AFMS), or laterFAA approved revisions must be carried on the airplane when thefollowing kits are installed:a. The following A...	14 Volt System aircraft must upgrade to a National AirPartsInc. P/NP312RN, 120 Amp Alternator. This can be installed via its PMA, but aseparate logbook entry must be made if thisalternator is installed.14 Volt System PA-32R-301 and PA-32R-30lT aircraft must have an Oildynehydraulic pump, Piper P/N...	16/05/2019	Active	10069922
10069925	AIRCRAFT WHEEL AND BRAKE, LLC	REV. 2	FAA STC SA1065GL	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100 DHC-6 SERIES 1	Install Aircraft Wheel and Brake Conversion Kit 199-92, NC,dated 31March 1986.Revision 1 is a correction of a typographical errorRevision 2 is an administrative re-issuance following a name change fromParker Hannifin Corporation Aircraft Wheel and Brake Division to KamanCorporation, Aircraft Wheel...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA1065GL.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Cleveland Wheels and Brakes Installation Instructions Drawing 050-10100,Revision A, dated 24 September 1986, andCleveland Wheels and Brakes Conversion Kit Installation Manual for KitNumber 199-92, Revision A, dated 24 September 1986, or other FAAapproved revisions of kits 199-92 and installation dra...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/04/2023	Active	10069925
10069926	AIRCRAFT SYSTEMS AND MANUFACTURING,Inc.	REV. 4	FAA STC ST02472AT	SEE FAA AML	Installation of an Avionica LLC mini-Quick Access Recorder (miniQAR)model MKI, MKII, or MKIIIRevision 1: Wiring documentation for 747-400F updated. Models 737-8/9,767-2C, A300-941, BD-700-2A12, ERJ190-400, 787-10, A350-941/-1041,EMB-545/-550, GVI (G650), BAE Jetstream 4101 added to the AML. Majorcha...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 amdt 25: 25.1, 25.21(a)(1), 25.301, 25.303,25.305(a)(b)<(>,<)>25.307 (a), 25.561(c)(1)(d), 25.601, 25.60...	Archeion Holdings, LLC Master Drawing List 21149-MDL, Revision AB, dated9 May 2023;Installation of an Avionica, LLC Quick Access Recorder (QAR) modelavRDC, or avRDC MAX in accordance with Archeion Holdings, LLC MasterData List 130070-MDL, Revision AH, dated 9 May 2023;Optional Installation of an Avi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	05/05/2025	Active	10069926
10069938	LUFTHANSA TECHNIK AG			A319-133	Ka-band SatCom, Wi-fi and Intrusion Detection System.Installation of Ka-band SatCom antenna as well as cabin wi-fi Systemsand upgrade of existing intrusion detection system in aircraft havingEASA STC no. 10028830 (VIP cabin) installed.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-4301-003 Vibration/buffetingcompliance criteria for large antenna installation.The requirements for environmental protection and thec...	- Supplemental Type Definition Document STDD23-18/16M Iss.01 Rev. 01- ICA A-00-19/19-ICA Iss. 03 Rev. 00- AFM A-00-19/19-AFM Iss. 03 Rev. 00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is applicable only on aircraft where the EASA STC 10028830 isembodied.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	17/05/2019	Active	10069938
10069949	ONTIC ENGINEERING ANDMANUFACTURING, Inc.		FAA STC ST00511LA	737-300	Installation of a smoke detection and fire suppression system in thelower cargo compartments	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00511LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Hollingsead International, Inc. Master Index List No. 20493, Revision D,dated 19 November 1998, or later FAA approved revision.Hollingsead International, Inc. Airplane Flight Manual SupplementDocument No. 290-0008-01, Revision N/C, dated 19 November 1998, or laterFAA approved revision.	Securaplane Technologies, LLC smoke detector unit (SDU) must not beinstalled closer than four feet from the central control unit (CCU).Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design chang...	20/05/2019	Active	10069949
10069951	ROCKWELL COLLINS, Inc.		FAA STC ST02781AT	737-600/-700/-800/-900	Installation of Rockwell Collins CMU-900 Communications Management UnitVHF-920 VDL Mode 2 Radio and the APM-900 Airplane Personality Module toprovide ACARS over Aeronautical (AOA)VHF Link Control functionality.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02781AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Hollingsead International Master Data List 2755-01, Revision NC, dated18 December 2003, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	20/05/2019	Active	10069951

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10069964	URBE AERO GmbH			525	Change 183, L3 Lynx NGT-9000D +Installation of a L3 NGT-9000D Mode S Transponder and approval for ADS-BOUT according to CS-ACNS. The Transponder is installed in addition tothe existing Garmin GTX330D.	CFR Part 23, effective February 1, 1965, as amended by Amendments 23-1through 23-38, and 23-40; CS-ACNS, initial issue.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the originalproduct areunchanged and remain applicable to this certifica...	- Equipment upgrade according to design change proposal, Doc DOE/ F01,Project No. 183, Issue 01- Installation in accordance with Engineering Oder doc: DOE / F 07,Project No. 183, Issue 01- Operation in accordance with Supplement to the Airplane Flight Manual,Doc. No. AFM-183-01- Maintenance and Instr...	This STC only applies to installations originally fitted with 2 GarminGTX330 transponders where all required antenna are already available.The NGT-9000D+ is installed on the location of the Garmin GTX330D. TheSTC does not cover antenna installations or relocations.Prior to installation of this chang...	21/05/2019	Active	10069964
10069967	FIELD AVIATION COMPANY Inc.		TCCA O-LSA18-029/D	DHC-8-103	EGPWS Modification (SN-593)Relocation of EGPWS Terrain Selection, Terrain Warning, Terrain Inhibit,and add steep approach Annunciators/Switches.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- The change is defined with FAEL Master Drawing and Data listdesignated 26330000, Rev. IR.- Maintenance must be performed in accordance with FAEL MaintenanceManual Supplement designated 26333100, Rev. IRor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accorda...	This STC is limited to Aircraft S/ N 593.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	22/05/2019	Active	10069967
10069978	LUFTHANSA TECHNIK AG	REV. 1		777-200, 777-300ER, 777F	NAVIGATION - Replacement of existing Multi-Mode Receivers with HoneywellIntegrated Multi-Mode Receivers introducing SBAS capability.Rev 1: removal of one limitation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Description Document STDD34-18/06M Issue 2.0Description of Change AZA01-34 Rev 3Airplane Flight Manual Supplement A-00-18/104-AFM Issue/ Rev 01/03Instructions forContinued Airworthiness A-00-18/104-ICA Issue/Rev 2/0or later revisions of the above listed document(s) approved/accepte...	Please check the detailed prerequisites for the operation of theHoneywell Integrated Multi-Mode Receiver (IMMR) during CAT II and CATIII ILS approach and landing in the AFMS.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any...	24/06/2019	Active	10069978
10069980	SPAES GmbH & Co. KG			EC 155 B, EC 155 B1	Installation of Automatic Deployable ELT.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Certification Program CPR-155-201-25-01, Rev. 00Compliance Check List CCL-155-201-25-01, Rev. 00Master Document List MDL-155-201-25-01, Rev. 00Flight Manual Supplement FMS-SPAES-0201. Rev. 00Declaration of Compliance Change DCC-155-201-25-01, Rev. 00or later revisions of the above listed document(s)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.,,,,	22/05/2019	Active	10069980
10070031	S4A SOLUTIONS FOR AVIATION, S.L			A321-271NX/-272NX A321-271N/-272N A321-251NX/-252NX/-253 NX A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of FliteByte WiFi in AIRBUS A318/A319/A320/A321	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	320223-HDK01 Flight Manual Supplement Edition 5320223-SB001Service Bulletin Edition 4320223-SB002 Manufacturing Instructions Edition 24320223-RPT02 Master Drawing List Edition 3or later revisions of the above listed documents approved by EASA.	None	27/05/2019	Active	10070031

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070044	AIR ALLIANCE GmbH			35, 35A	Installation of dual Sandel SA4550A dual Sandel SA4550 primary attitude display shall be installed as areplacement of the former obsolete ADI.The SandelSA4550 EADI is an advanced microprocessor controlled airborneelectronic display which is EASA and FAA approved under technicalstandard orders TSO C1...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Air Alliance, Airplane Flight Manual Supplement, doc. No. 2015_003_LJ35_0506, revision 05.- Air Alliance, Master Document List, Doc. No. 2015_003_LJ35_Form_02,revision 01- Air Alliance, Instructions for Continued Airworthiness, 20115_003_LJ35_0507, revision 03or later revisions of the above listed d...	None	28/05/2019	Active	10070044
10070051	CAVOK			B300	Forward Pressure Bulkhead Connector installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of Forward Pressure Bulkhead Connector in accordance withCAVOK drawing number 350-053-000-00 issue A and InstallationInstructions, document number 350-053-SB-006 Issue B, 20/05/2019.NEW-PAGEInstructions for Continued Airworthiness in accordance with CAVOKInstallation Instructions, docum...	Applicable to Beechcraft B300 aircraft S/N(s): FL-31, FL-241, FL-389,FL-479.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	28/05/2019	Active	10070051
10070054	S4A SOLUTIONS FOR AVIATION, S.L			R44, R44 II	TRACKING DEVICE INSTALLATION	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- C-R4408-HDK01 Flight manual supplement Ed2 dated 22 November 2018- C-R4408-HDK02 Maintenance manual supplement Ed 3 dated 28 May 2019- R4408-RPT02 Master drawing list Ed2 dated 13 May 2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/05/2019	Active	10070054
10070067	FOKKER TECHNIEK B.V.	REV. 3		737-700	VIP conversionThis modification consists in adapting a Boeing 737-700 for VIP useRevision 1: Transfer of STC from Fokker Services B.V. (EASA.21J.059) toFokker Techniek B.V. (EASA.21J. 667).Revision 2: Table TTOL-Reconfiguration.Revision 3: Adding data for Life raft replacement.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:- JAR 25 change 14: 25.853, 25.854, 25.869, 25.1423- CS 25 Amdt. 19: 25.603 (a), 25.788(a) , 25.788(b) , 25.812...	- 737-PHGOV-CRR-0001 rev. 1- Compliance Record Report- 737-PHGOV-CRR-0009 rev. 3- Compliance Record Report- 737-PHGOV-CRR-0012 rev. 1- Compliance Record Report- 737-PHGOV-AFM-S-001 rev. 3 - Airplane Flight Manual Supplement (AFM-S)for the VIP completion of 737-700 for The Netherlands Government- 737...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Stowage 5 oxygen bottle must not be present in the airc...	02/06/2025	Active	10070067
10070084	STG AEROSPACE GERMANY GmbH	REV. 1		A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-243 A330-201/-202/-203	AIRBUS LITEMOOD® CABIN LIGHTING UPGRADERevision 1: Transferof STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA Approved:STG AEROSPACE LTD INSTRUCTIONS FOR CONTINUED AIRWORTHINESS No. SG-1025-ICA-01 Revision IRSTG AEROSPACE LTD Cabin Crew Data Supplement No. SG-1025-CCD-01 RevisionIREASA Accepted:STG AEROSPACE LTD MASTER DATA LIST No. SG-1025-MDL-01 Revision IRor later revisions of the above listed docum...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/02/2021	Active	10070084

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070087	DELTA ENGINEERING CORPORATION		FAA STC ST04078NY	787-9 787-8 787-10	Update of gogo 2Ku	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04078NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Delta Engineering Master Data List 0165-10663-2498 Revision A dated18 April 2019 or later FAA approved revisions.2. Delta Engineering Instructions for Continued Airworthiness0765-10664-2 498 Revision A dated 26 February 2019 or later FAAapprovedrevisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/06/2019	Active	10070087
10070090	MT-PROPELLER ENTWICKLUNG GmbH			1900, 1900C, 1900D	MTV-27-() on Beech 1900Installation of MTV-27-() propeller on the Beech 1900, 1900C & 1900Daircraft models.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	- According to MT-Propeller Master Documentation List No. E-3384 Rev. 0- To be operated in accordance with MT-PropellerAFM-S Document No.E-3386 Rev. 0- To be installed i.a.w. Installation Instruction Doc. No. E-3387 Rev. 0- To be maintained i.a.w. MT-Propeller ICA Document No. E-3388 Rev. 0or later...	According limitation section of MT-Propeller AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduceno adverseeffect upon the airworthiness of the product.	03/06/2019	Active	10070090
10070091	365 AEROSPACE DDS LIMITED	REV. 2	FAA STC NO. ST04395NY	ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 SR ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ ERJ 170-200 STD ERJ 170-200 LR ERJ 170-100 STD ERJ 170-100 LR	Change to introduce a modification to Zodiac Standard 'Elite' Doubleseats.Rev. 2: Transfer of STC to new legal entity.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 Amendment 21:25.2525.2725.30125.30325.30 525.30725.56125.56225.60125.60 325.60525.60925.61325.61925.62 525.78525.78925....	- 365 Aerospace Master Data List No. MDL-0631 Revision A;-365 Aerospace Instructions for Continued Airworthiness ICA-0631-001 – ‘Change to introduce a modification to Zodiac Standard 'Elite'Double seats<(>,<)> Configuration 1’ Issue A-365 Aerospace Instructions for Continued Airworthiness ICA-0631-0...	Refer to 365 Aerospace Master Data List No. MDL-0631 for configurationstandards that are a pre-requisite for this modification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	24/10/2019	Active	10070091
10070096	MT-PROPELLER ENTWICKLUNG GmbH			T67M-MKII FIREFLY T67M FIREFLY	MTV-12-( ) Propeller on Slingsby T67M( ) Installation of MTV-12-( ) Propeller on Slingsby T67M FireflyandT67M-MkII Firefly Aircraft Models.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	- According to MT-Propeller Master Documentation List No. E-3395 Rev. 0- To be operated in accordance with MT-PropellerAFM-S Document No.E-3397 Rev. 0- To be installed i.a.w. Installation Instruction Doc. No. E-3398 Rev. 0- To be maintained i.a.w. MT-Propeller ICA Document No. E-3399 Rev. 0or later...	According limitation section of MT-Propeller AFM-S.Prior toinstallation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	04/06/2019	Active	10070096
10070100	GDC TECHNICS, LLC.	REV. 1	FAA STC ST03190NY	A330-243 A330-223 A330-203 A330-202 A330-201	Installation of Executive interior in an Airbus A330-200 SeriesThis modification consists in the installation of an executive interiorwhich provides ninety eight (98) Taxi/Take-Off/Landing (TTL) passengerseats and eleven (11) TTL cabin attendant seats and includes a PanasoniceX2 and Global Communica...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-4302-004 Isolated Compartments; D-4310-002 GlassScreens of Displays / Monitors; D-4314-004 Shower InstallationDeviation(s): D-4301-004 Installatio...	Master Data List, ref: 08873 Rev B dated 13 August 2014Aircraft Flight Manual Supplement, ref: 579-TP-49 Revision A dated 11November 2014Instruction for Continued Airworthiness, ref: 0754-08876-2370 Revision Adated 22 August 2014or later revisions of the above listed document(s) approved/accepted on...	The following modifications shall be installed concurrently:- EASA STC 10037167 (equivalent to FAA STC ST02884NY) : PanasonicKu-band installation- EASA STC 10043936 (equivalent toFAA STC ST03109CH) : T-PED tolerance- EASA STC 10032264 (equivalent to FAA STC ST02317LA) : Installation ofCabin interio...	11/02/2021	Active	10070100
10070115	SOCIETE AIR FRANCE S.A.			777-200, 777-300ER	Boeing 777-200 and 777-300ER aeroplanes – tolerance to theelectromagnetic emissions of TPEDs (Transmitting Personal ElectronicDevices).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Airplane Flight Manual Supplement: AFMS-B777-18-005-001 originalissue, dated 11 December 2018- Instructions for Continued Airworthiness: ICA-B777-18-005-001 Revision2, dated 16 May 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/06/2019	Active	10070115

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070116	CONCORDE BATTERY CORPORATION		FAA STC SR00864DE	369D/ 369E/ 500N/ 600N	Installation of Concorde Battery Corporation 24 Ah VRLA Main Battery.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00864DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Document No. 5-0607, Master Drawing List, MD Helicopters369/500/600Battery Upgrade, Revision NC dated 1 June 2017, FAA approved 4 September2017 or later FAA approved revision;2. Instructions for Continued Airworthiness (ICA), Document No. 5-0610,Revision A dated 31 May 2017, FAA accepted 31 Augu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/07/2019	Active	10070116
10070122	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		S-76C	Sikorsky S-76 - SSQAR Installation.This Design Change introduces a Flight Data Vision 200-E10-2100SolidState Quick Access Recorder (SSQAR) on the subject SikorskyS-76CModel with two Turbomeca Arriel 2S2 engines with dual FADEC. The SSQARwill be installed in the aft electronics compartment on a new f...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 29 Revision 4: CS29.1, CS 29.301, CS 29.303, CS 29.305, CS 29.307, CS 29.309, CS 29.337,CS 29.561, CS 29.6...	- Master Document List, MDL-13218-00001, Issue 1 dated 3 June 2019- Instructions for Continued Airworthiness, 13218-ICA-0001, Issue 1dated 6 December 2018- Change Bulletin, MOD-13218-00001, Issue 1 dated 6 December 2018or later revisions of the above listed document(s) approved/acceptedunder the EAS...	Approval limited to S-76 C helicopters equipped with two TurbomecaArriel 2S2 engines with dual FADEC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no advers...	10/11/2021	Active	10070122
10070123	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST03416NY	A321-271NX/-272NX A321-271N/-272N A321-251NX/-252NX/-253NX A321-251N/-252N/-253N A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-271N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of a gogo 2Ku radome/ antenna with demod option:Configuration 1: A319 ODA-2407-01Configuration 2: A319-21502 ODA-2407-01Configuration 3: Demod of 2KuConfiguration 3a: Demod of ATG Antenna'sConfiguration 3b: Demod of LiveTV A319Configuration 3c: Demod of Panasonic DBS (iDTV) System A320 O...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-0301-007 Vibration and buffetingcompliance criteria for large external antenna installationThe requirements for environmental protectio...	Master Data List, ref: 0164-09685-2407 Revision CB dated 9 June 2025<(>,<)>For configurations 1, 2, 4, 5:Aircraft Flight Manual Supplement, ref: 0664-09891-2407 Revision C<(>,<)>For configurations 1, 2, 3, 3b, 3c, 3d, 3e, 3f, 3g, 4, 5:Instruction for Continued Airworthiness, ref: 0764-09813-2407 Rev...	As per MDL 0164-09685-2407 and ICA document 0764-09813-2407, inparticular:- Additional airworthiness approval is necessary for the configurationsnot explicitly covering the activation of the 2KU antenna;-Configuration 3b requires existing LiveTV radome, fittings, antenna andadapter plate previouslyP...	15/09/2025	Active	10070123
10070124	STAR WORK SKY S.A.S.	REV. 1		AS 350 B, AS 350 B1 AS 350 BA, AS 350 BB AS 350 B2, AS 350 B3	Cabinet Helibox Sniper Technology SWS-P031Rev.1: Scope of this minor change is the correction of typing errors inthe original installation service bulletin SB SWS31/2018 and tointroduce an alternative rear/front cross-link configuration tosecurethe cabinet to the helicopter floor.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement SWS-031 Revision 1 dated 9 March2022- Master Drawing List MDL-P031 Revision 1- Master Compliance Document List MCDL-SWS-P031 Revision 1- Instructions for Continued Airworthiness SWS-031 Revision 1- Installation Service Bulletin SWS-031 Revision 1- Certification Program PD...	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	29/03/2022	Active	10070124
10070128	ANCRA INTERNATIONAL LLC		FAA STC ST02605LA	SEE FAA AML	Installation of Passenger Window Plugs	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02605LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Controlled Data List as listed on AML No. ST02605LA, or later FAAapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	06/06/2019	Active	10070128

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070149	STG AEROSPACE GERMANY GmbH	REV. 3		SEE EASA APPROVED MODEL LIST	saf-Tglo® SSUL23 PHOTOLUMINESCENT AISLE PATH MARKING SYSTEMReason for Rev. 2: Adding of Associated Technical DocumentationRevision 3: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 at Amendment 22:25.1(a); 25.25(a)(b); 25.27;25.301; 25.303; 25.305; 25.307;25.561(a)(b)(c); 25.581; 25.601; 25.603; 25.605(a); 25.609; 25.611;25.613; 25.789(a); 25....	EASA accepted:STG AEROSPACE LTD AIRPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1026-FMS-01Revision IR (AIRBUS)STG AEROSPACE LTD AIRPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1026-FMS-02Revision IR (ATR) STG AEROSPACE LTD AIRPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1026-FMS-03Revision IR (CRJ) STG AEROSPACE LTD AIRP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/02/2021	Active	10070149
10070152	DASSAULT FALCON SERVICE	REV. 2		MYSTÈRE FALCON 900 (MF900) MYSTÈRE FALCON 50 (MF50) FALCON 900EX (F900EX) FALCON 2000EX, FALCON 7X	TrueNorth DLU satcom ActivationRev 1: extension applicability to the Falcon 900EX, MF50, MF900Rev 2: extension applicability to the Falcon 7X	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-0127-001: SECURITY PROTECTION OF AIRCRAFTSYSTEMS AND NETWORKS.The requirements for environmental protection and the associatedcertified nois...	Master Data List DFS-DE-17-AML-P001 issue C<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The minor modification DFS D260A (or later approved issue) on Falcon2000EX Post-mod (M1691, MI 745 and M1504) and the modification DFS 9871Aon F900EX EASy post-mod (M3083) and DFS7117 A (or later issue) onFalcon 7X are a pre-requisite forthis design change.If aircraft with FANS 1/A activated, theP...	07/07/2020	Active	10070152
10070153	AEROSERVIS, S.R.O.			L-410 UVP-E	STC AE/187Increase of MTOW to 6600kgs	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 23, Amdt 4 (23.45, 23.51, 23.53, 23.65, 23.143,23.145, 23.147,23.149, 23.161, 23.175, 23.177, 23.181, 23.203, 23.305, 23.331, 23.391,23.393, 23.399, 23.423, 23.441, 23...	-FLIGHT MANUAL SUPPLEMENT<(>,<)> Supplement xxxx<(>,<)> STCAE/187-DLP1,Apr 15/19.-MASTER DOCUMENT LIST, AE187000X__RD,Date 24.05.2019.-Definition Document, AE187001P_RC, Date 11.04.2019.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/06/2019	Active	10070153
10070164	airplus engineering GmbH	REV. 1		DHC-6 SERIES 400	Installation of Honeywell Go Direct Router.This modification enables WIFI functionality within the aircraft cabin.The equipment will be interfaced with the Aspire 200system and AMT-1800IG SatCom Antenna.See Description of Modification, doc. no. DE-2231-000000 Iss. 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Document List MD-2231-000000, Issue 2-Descriptionof Modification DE-2231-000000, Issue 3-Aircraft Flight Manual Supplement PO-2231-000000, Issue 0-1- Maintenance Manual Supplement MM-2231-000000, Issue 1-Engineering Work OrderEW-2231-000000, Issue 2or later revisions of the above liste...	This modification is only applicable to aircraft with Honeywell Aspire200 System (Airplus Minor Change 2122) and Honeywell AMT-1800Intermediate Gain Antenna (EASA STC 10065369) installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/r...	10/02/2021	Active	10070164
10070175	AEROLEDS HOLDINGS, LLC		FAA STC SA02386AK	SEE FAA APPROVED MODEL LIST	Replacement of existing landing and/or taxi light reflectorand bulbswith Light Emitting Diode lighting systems	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. AeroLEDs Master Drawing List (MDL) document as listed onAMLSA02386AK and later FAA approved revisions.2. Instructions for Continued Airworthiness (ICA) document as listed onAML SA02386AK and later FAA approved revisions.	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List SA02386AK dated 11 March 2015 orlater approved revisions.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	13/06/2019	Active	10070175

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070178	ELDEC AEROSPACE CORPORATION		FAA STC ST02421SE	SEE FAA APPROVED MODEL LIST	Installation of a Crane Aerospace & Electronics Tire SensorAssembly	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Crane Aerospace Master Document List (MDL) as listed on AMLST02421SE,or later FAA-approved revision.	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List ST02421SE dated 14 January 2015 orlater approved revisions.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpre...	13/06/2019	Active	10070178
10070182	JETTECH, L.L.C.		FAA STC ST01897WI	500, 550, 560, S550	Installation of the RVSM capable Garmin G70D with GDU-106D Touch ScreenPrimary Flight Display (PFD).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01897WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. JETIECH Master Document list, No. MDl2704-34251, Rev IR,dated 12February 12, 2019, and2. JETIECH Airplane Flight Manual Supplement, No. FMS2704-34251-1 RevIR, or No. FMS2704-34251-2 Rev IR, both dated 12 February 2019, or laterFAA Approved revision to 1 or 2.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2019	Active	10070182
10070184	JETTECH, L.L.C.		FAA STC ST01898WI	501, 551	Installation of the RVSM capable Garmin G600 with GDU-I 060Touch ScreenPrimary Flight Display (PFD).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01898WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. JETIECH Master Document List, No. MDL2704-34251, Rev IR,dated 12February 2019, and2. JETIECH Airplane Flight ManualSupplement, No. FMS2704-34252-1 RevIR, or No. FMS2704-34252-2 Rev IR, both dated 12 February 2019, or laterFAA Approvedrevision to 1 or 2.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/06/2019	Active	10070184
10070192	AIRCRAFT RESTORATION CORP.		FAA SA00555DE	SEE FAA APPROVED AML SA00555DE	Replacement of the inboard main landing gear door with an aerodynamicfairing.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00555DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Aircraft Restoration Corporation Master Drawing List No.MDL-85280-01, Revision A, dated 4 June 2004<(>,<)> or later FAA approved revision.2. Instructions for Continued Airworthiness, Aircraft RestorationCorporation Report No. ICA-85280-01 dated 13 February 2004< (>,<)> orlater FAA accepted revisio...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	13/06/2019	Active	10070192
10070201	FLYING COLOURS CORP.			BD-700-1A10	Cabin ReconfigurationInstallation to be completed in accordance with Modification DataSummary L688000 Revision NC or later approved revision.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation to be completed in accordance with Modification DataSummary L688000 Revision NC.Refer to Instructions for Continued Airworthiness L688070 Revision NC.or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProc...	As per original Transport Canada STC C-LSA18—40/D, this cabinreconfiguration is limited to BD-700-1A10 aircraft serial number 9189.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or r...	14/06/2019	Active	10070201

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070206	ALPINE AVIATION, INC.		FAA SA00905DE	1900D	Installation of a Cargo Interior.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00905DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List Document No. MDL-2015-01, Revision B, dated 15October 2018, or later FAA approved revision.2. Aircraft Flight Manual Supplement Document No. AFMS-2015, NoRevision, dated 24 September 2018, or later FAA approved revision.3. Instructions for Continued Airworthiness Document No.R...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC approval is limited to Model 1900D airc...	14/06/2019	Active	10070206
10070207	AVIANOR INC		TCCA O-LSA11-199, ISSUE 3	737-800	B/E Aerospace Spectrum Seat ModificationDescription: Replacement of seat dress covers, life preservers, seatrestraints,IFE components and modification of headrest cushionassembly.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Transport Canada STC O-LSA11-199, Issue 3- Avianor MasterDocument List, ref. MDL11143001, Rev. B, dated 7thSeptember2012- Avianor Components Maintenance Manual Supplements, ref. 25-20-278,Rev. NC, dated 11th Nov. 2011; ref. 25-20-284, Rev. A, dated 13th August2012; ref. 25-20-285, Rev. NC, dated...	This approval is for seat modifications only. Seat installation isauthorized separately.STC approval applicability: MSN29642, 34704, 36552, 33029, 30292,29647, 33018	14/06/2019	Active	10070207
10070212	AMAC AEROSPACE SWITZERLAND AG			A320-232	Certification for commercial operation. / This change includesinstructions to alter the aircraft to support approval ofoperation forcommercial air transport. If desired, this change also includesinstructions to alter the aircraft back to its initial configuration forsole private use.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Appendix S to CS-25Amendment 21.The requirements for environmental protection and the associatedcertified noise and/ or em...	- The change is defined with Revision A of Master Data ListDocumentMDL-ED03-2500- The aircraft shall be operated in accordance with Revision A ofAirplane Flight Manual SupplementAFMS-ED03-2500or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/06/2019	Active	10070212
10070213	SAFRAN SEATS	REV. 1		777-300ER & 787-9	Upper Class Suite (UCS) Refresh ProgrammeRev. 1: Transfer from Safran Seats GB Limited to Safran Seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- SAFRAN Seats GB Instructions for Continued Airworthiness No. C1343ICARevision 0- SAFRAN Seats GB Master Data List No.C1343MDL Revision 0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	1. The existing approved cabin layouts were approved by theFAA atoriginal time of aircraft integration (refer to Master Data List No.C1343MDL). Should these configurations be introduced in the EU, thebaseline cabin configuration(s) will need to be approved by the Agency.The approval of this changec...	09/07/2019	Active	10070213
10070222	AIRBUS HELICOPTERS, Inc.		FAA SR11189DS	AS 350 B3	Installation of provisions to install Garmin G500H GDU 1060Display, L3ESI-500 Electronic Standby Indicator and TA202 USB Charging Port.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11189DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Airbus Helicopters Inc. Master Drawing List (MDL) 350A82-1904 Rev. Adated 23 January 2019 or later ODA approved revision.2. Configuration -01: Rotorcraft Flight Manual Supplement (RFMS) 350FMS-556 Rev. IR dated 31 January 2019 or later ODA approved revision.3. Instructions for Continued Airworthin...	1. This STC is limited to Airbus Helicopters AS350 B3 Post Mod 07-4723or Post ECP 07-4961 aircraft only.2. Installationof Garmin G500H TXi Display System (Primary FlightDisplay (PDF), Multi-Function Display (MFD)) AML STC 10069884 is aprerequisite for installing this STC.3. Rotorcraft modified unde...	17/06/2019	Active	10070222

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070239	APTOZ EHF.	REV. 1		747-400F 747-300, 747-400 747-200C, 747-200F 747-100, 747-200B	Installation of GPS/SBAS sensors/ antennaInstallation of two(TSO-145c) CMC Esterline CMA-3024 GPS/SBAS sensors,(TSO-C190) antennas, and associated wiring. The installed equipment andwiring will be inactive, activation is via separate STC.Reason for Rev. 1: Addition of 747-100, -200 and -300 models	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): H-01The following paragraph (s) at a later amendment: CS-25 amdentment 4: CS25.29, CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS 25.337, CS 25.341,CS...	- Master Data List, document No: MDL341017, Rev. IR, issued3 Feb. 2021- Instructions for Continued Airworthiness documents No: ICA341017-n“n” corresponds to the customised version related to the specificapplicable type, refer to respective table at the MDLor later revisions of the above listed docu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/03/2021	Active	10070239
10070247	FALCON CREST AVIATION SUPPLY, INC.		FAA STC SR09069RC	206L-4 206L-3 206L-1	Installation approval of a Concorde RG222 Valve Regulated Sealed LeadAcid Battery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Falcon Crest Master Drawing List, FC-003, Revision IR, dated 29February 1996, or later FAA approved revisions.2. Flight Manual Supplement (RFMS), dated 6 May 1996, or later RFMS.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/06/2019	Active	10070247
10070255	AEROTEC & CONCEPT			A321-271N/-271NX/-272N /-272NX A321-251NX/-252NX/-253 N/-253NX A321-213/-231/-232/-251N /-252N A321-111/-112/-131/-211/-212 A320-271N A320-231/-232/-233/-251N /-252N A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	MOD AEROTEC CONCEPT AE18084: Rain Repellent Dry Coat Application on theOutside Surface of SAINT GOBAIN SULLY (SGS) Windshield.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Instructions for Continued Airworthiness Doc N° AE18084ICA Rev 0 dated11/06/2018.- MASTER DATA LIST Doc N° AE18084MDLRev.1 dated 18/06/2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/06/2019	Active	10070255
10070260	ALPHA AVIATION, INC.		FAA STC SA02211CH	SEE FAA AML	Installation of a Three Point Torso Restraint System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Alpha Aviation Inc. Installation and Maintenance Manual as listed onAML SA02211CH, reissued 20 December 2016, or later FAA Approvedrevisions.	The Three Point Torso Restraint System installation is to be inspectedand maintained in accordance with Alpha Aviation Inc. Installation andMaintenance Manual as listed on AML SA02211 CH, reissued 20 December2016, or later FAA Approved revisions.This STC is valid for aircraft types and models approv...	21/06/2019	Active	10070260
10070267	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST04316CH	EMB-145LR, EMB-145MP EMB-145EP, EMB-145ER EMB-135ER, EMB-135LR, EMB-145	Installation of a Smartsky System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04316CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- StandardAero Master Data List 1034570, Revision (C), dated 23 March2019, or later FAA approved revision.- Airplane Flight Manual Supplement Document Number 1035750, Revision (B),dated 20 March 2019, or later FAA approved revision.- Instructions for Continued Airworthiness, Document Number 1035747,...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/06/2019	Active	10070267

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070273	HELI-ONE (NORWAY) AS			AS 332 L1 AS 332 L	Becker Avionics BXT6513 series Transponder with Mode S ElementarySurveillance and Automatic Dependent Surveillance – Broadcast (ADS-B)Out capabilities (ref. modification AHSE-70870).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): Deviation from CS ACNS.D.ELS. 045 and CS ACNS.D.ADSB. 105as per CRI F-01 issue 3 dated 08/05/2019.the following paragraph(s) at a later amendment:CS 29 Amdt 4...	Certification Programme (CP) ref. AHSE-70873 Revision B, dated09/05/2019.CS-ACNS Compliance Plan ref. AHSE-70881 Initial Issue, dated 09/05/2019.AS 332 L/L1 Flight Manual Supplement (FMS) ref. H1No.302 Revision dated20/06/2019.Product Change Declaration ref. AHSE-70870 Revision A, dated 21/06/2019.D...	“ADS-B / MODE S OFF” function is outside of the scope of this STC andnot part of the EASA approved configurationPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	24/06/2019	Active	10070273
10070274	HONEYWELL INTERNATIONAL INC.	REV. 2	FAA STC ST01618WI-D	777-200/-200LR/-300/-300 ER/-F	Installation of a Honeywell Enhanced Ground Proximity Warning Computer (EGPWC) and Activation of the Smart Runway/Smart Landing Features inaccordance with Honeywell Master Drawing List 756-0251-002EASA validation of FAA STC ST01618WI-D Configuration 2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Honeywell Master Drawing List 756-0251-002 Revision A dated25. February2019Airplane Flight Manual Supplement 756-0251-811 Revision - dated 5.September 2014Airplane Flight Manual Supplement 756-0251-812 Revision A dated 25.February 2019Refer to Master Drawing List 756-0251-002 for the required Instr...	-EGPWC 965-0976-003-XXX-XXX MK V with software version -212-212 or laterinstalled is a pre-requisite to this modification-Limitations per Airplane Flight Manual Supplement 756-0251-811 andAirplane Flight Manual Supplement 756-0251-812Priorto installation of this change/repair it must be determinedt...	16/10/2019	Active	10070274
10070279	JET AVIATION AG	REV. 2		737-900ER, 737-8 737-900ER 737-900 737-9 737-800 737-8 737-700, 737-800, 737-900 737-700	Installation of KA Band Satcom Systemon the rear fuselage crown area. Three configurations are included onthis change:Configuration 1:Structural Provisions only: dorsal radome, mounting plate, and fuselagefairing, supported by 7 external fittings following ARINC 791 standard.Configuration 2:KA BandC...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): the following paragraph(s) at a lateramendment:CS 25 amdt. 24: 25.629CS 25 amdt. 27: 25.603, 25.605CS 25 amdt. 28: 25.111, 25.11...	-,,MDL: JBSL-M-01190MDL-01_9-,,ICA: JBSL-M-01190ICA-10_6-,,ICA: JBSL-M-01190ICA-30_5-,,AFM: JBSL-M-01190AFM-1_3-,,STC: 10070279-EASA STC-20190624or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/10/2025	Active	10070279
10070281	LEARJET Inc.	REV. 1	FAA STC ST01920WI	BD-700-1A10, BD-700-1A11	Installation of software Batch 3.4 to the Honeywell Integrated AvionicsComputer (IAC) model IC-810 on a Model BD-700-1A10 and BD-700-1A11	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01920WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Document List (MDL) BAS67015021, Revision (F), dated10 May 2019,FAA approved 10 May 2019, or later FAA approvedrevision.Instructio ns for Continued Airworthiness, BAS67015021-ICA-1, Revision(NC), dated 21 February 2019, FAA accepted 10 May 2019, or later FAAaccepted revision.Airplane FlightM...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The aircraft must be equipped with Honeywell Int...	01/07/2019	Active	10070281
10070292	AEROFEM GmbH			EC 130 B4, EC 130 T2	Installation of a bubble window on the LH small hinged cockpit door ofthe EC 130 B4/T2 rotorcraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Rotorcraft Flight Manual Supplement AEF-0181-FMS-0001, Issue 05- Instructions for Continued Airworthiness AEF-0181-ICA-0001, Issue 02- Master Document List in Appendix C of AeroFEM-PCP-0002, Issue 09or later revisions of the above listeddocument (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/06/2019	Active	10070292

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070298	GULFSTREAM AEROSPACE CORPORATION		FAA ST01674LA-D	GV-SP	Installation of a 14-Passenger cabin interior.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-110 (Installation ofnon-rechargeablelithium battery).The requirements for environmental protection and the associatedcertified noise and/ or...	- Index List, Gulfstream Aerospace document No. GC520008442, Revision K,dated 13 May 2019.- Airplane Flight Manual Supplement, Gulfstream Aerospace document No.GC51605M010, Revision A, dated 13 May 2019.- Instructions for Continued Airworthiness, Gulfstream Aerospacedocument No. GC52801A336, Revisio...	This STC is limited to serial number 5050 only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce noadverseeffect upon the airworthiness of the product.	26/06/2019	Active	10070298
10070304	DOA AESGLOBAL LIMITED	REV. 1		SEE EASA APPROVED MODEL LIST	Introduction of ADS-B Out FunctionRev 1: Transfer from AESLtd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 at Amendment21: CS 25.1, CS 25.601, CS 25.869, CS 25.899, CS 25.1301, CS 25.1302, CS25.1307, CS 25.1309, CS 25.132...	AES Limited Flight Manual Supplement No. 78 Issue 1AES Limited Instructions for Continued Airworthiness: Boeing 737NG Series Aircraft: AES-TP-0270 Issue 1 - Boeing 757 Series Aircraft: AES-TP-0268 Issue 1 - Boeing 767 Series Aircraft: AES-TP-0269 Issue 1AES Limited Master Data List No. AES-0...	The following pre-requisite provisioning modifications are required tobe embodied prior to or concurrently with this modification (consultapplicable modification for issue status)- Boeing 737NG Series Aircraft: AES-737-5362- Boeing 757 series Aircraft: AES-757-4838- Boeing 767 Series Aircraft: AES-7...	28/04/2021	Active	10070304
10070313	LUFTHANSA TECHNIK AG			A330-343	SWISS-Ultra High Comf. CAS InstallationInstallation of a TSO approved UTAS seat track mounted Ultra HighComfort Cabin Attendant Seat (UHC-CAS) in SWISS Airbus A330-300aircrafts, by replacing the installed High Comfort CAS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type definition Document STDD25-07/07 Iss/Rev 01.00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	None	27/06/2019	Active	10070313
10070355	T.P.S. S.P.A.	REV. 1		AW169	Installation of medical rack and retainers (ref. change TPS169-03-00).Rev. 1: Change of the approval holder name from TPS AEROSPACEENGINEERING S.r.l. to T.P.S. S.P.A.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program (CP) ref. TPS169-0300-Cpr-03 Issue 3 dated10/06/2019Compliance Check List (CCL) ref. TPS169-0300-CCL-03 Issue 3 dated23/04/2019Rotorcraft Flight Manual Supplement (RFMS) ref. TPS169-0300-RFMS-00Issue 0 dated 10/06/2019Master Document List ref. TPS169-0300-Mdl-00 Issue 0 dated 1...	This STC requires as pre-requisite the embodiment of at least one of thefollowing passenger cabin layouts defined in the Leonardo HelicoptersAW169 RFM Supplement 40 (“Stretcher installation layout”): forward (FWD)single stretcher with FWD facing seats (P/N 6F2560F02211 or P/ N6F2560F02611); or MIDDLE...	19/05/2022	Active	10070355
10070370	JORMAC AEROSPACE, INC.	REV. 1	FAA ST04079NY	787-8/ 787-9/ 787-10 787-8, 787-9, 787-10	Installation of Jormac Aerospace Door Locks.Revision 1: Transfer of STC holders from Delta Engineering to JormacAerospace: amend validation STC accordingly	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04079NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Delta Engineering Master Data List 0165-10673-2497 Revision A dated 8May 2018 or later FAA approved revisions.2. TheInstructions for Continued Airworthiness and Airplane Flightannual Supplement as listed on the Master Data List.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/02/2021	Active	10070370
10070402	LUFTHANSA TECHNIK AG			777-300ER	LATAM B777 Business Class Cabin Upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-129 “Incorporation of Inertia Locking Device indynamic seats”The requirements for environmental protection and the associatedcertified noise and/ o...	Supplemental Type Definition Document STDD00-17-12M Rev01.00Instructions for Continued Airworthiness document A-00-19-51-ICARev02-01or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/07/2019	Active	10070402

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070420	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC SR04390CH	AW109SP, AW119MKII A109E, A109K2, A109S, A119 A109, A109A, A109AII, A109C	Installation of an Electronic Flight Instrument System (EFIS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR04390CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- StandardAero Master Data List 10036824, Revision (B), dated 5 June2019, or later FAA approved revision.- Rotorcraft Flight Manual Supplement document number 1036499, Rev. (D),dated 30 May 2019, or later FAA approved revision.- RotorcraftFlight Manual Supplement document number 10036500, Rev.(C),...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/07/2019	Active	10070420
10070442	HEIKO NICKEL			SF 25 A	Einbau Zusatzpumpe SF25A, Anbau von Rädern an den Flügelspitzen,Änderung Kraftstoffhahn und Kraftstoffanzeige.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	· Änderungsblatt „Einbau einer Anlaßerkraftstoffeinspritzanlage für dieVergaser des Motors Hirth F10 A2c“· Beschreibungder Einspritzanlage für den Flugmotor Hirth F10 A undSolo 560 A/B· Zeichnung „Anlasskraftstoffeinspritzung Einbauschema“ 28.01.2019· Änderungsblatt „Anbau von Rädchen an den Schlei...	Limited to SN 4520.	10/07/2019	Active	10070442
10070454	AERO DYNAMIX, Inc.		FAA SR09888AC	480B	Installation of Night Vision Goggle (NVG) Complatible Lighting System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA Approved Rotorcraft Flight Manual Supplement (RFMS), NVGCompatible Lighting System, RFMS 480B-01, Revision IR dated 16 May 2018- EASA Approved Rotorcraft Flight Manual Supplement Appendix, NVIS/ NVGCompatible Lighting System, RFMSA 480B-01-EASA-01, Revision IR dated 20May 2019- Instructions for...	Installation of NVG compatible interior lighting system does not includeor imply approval for flight operations with NVGs. The operator mustreceive a determination from their civilaviation authority if anapproval to operate with NVGs is required.Rotorcraft modified by this design change employs Nigh...	10/07/2019	Active	10070454
10070456	LUFTHANSA TECHNIK AG	REV. 1		A321-253NX/-271N A321-232 A321-211/-231/-232 A320-251N/-271N A320-251N A320-232 A320-214/-232 A319-132 A319-131/-132/-133 A319-131	Removal of ka-band antenna and systemsThe modification is to remove the system components and structuralprovisions of the Ka-band antenna system, including the in-cabindistribution system, that have been previously installed per EASA STC10063537 and 10063559.Revision 1: Extension of validity	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Supplemental Type Design Definition STDD53-18/04M Issue 02Rev. 00- Instructions for Continued Airworthiness A-00-19/23-ICA Issue 02 Rev.00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	With this modification, EASA STC 10063537 and 10063559 are removed. Therelated AFM-S become obsolete, the ICAs are superseded by the ICAdocument A-00-19/23-ICA referenced abovePrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and a...	07/07/2023	Active	10070456
10070462	AVCON INDUSTRIES, Inc.	REV. 1	FAA SA01902WI	B200T/ B300/ B300C B200C/ B200CGT/ B200CT/ B200GT A200/ A200C/ A200CT/ B200 200/ 200C/ 200CT/ 200T/ 300	Installation of Fuselage Underside Rail Mounting Provisionsfor carriageof external payload.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01902WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List, Document No. 04501000, Rev.IR, dated 22 February2019 or later FAA Approved revision;2. Airplane Flight Manual Supplement, Document No. 04507100, Rev. 0,dated 21 February 2019 or later FAA Approved revision.	Carriage of payload will require separate approval unless installed onKing Air Model B300 with concurrent installation of STC 10061893.Prior to installation of this design change it must be determined thatthe interrelationship between thisdesign change and any otherpreviously installed design chang...	15/07/2019	Active	10070462
10070472	DIEHL AVIATION LAUPHEIM GmbH		LBA TA0294	CL-600-2B19 (RJ SERIES 100)	Installation of Wardrobe P/N 104119 and P/N 104119S	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	None	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/07/2019	Active	10070472

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070473	DIEHL AVIATION LAUPHEIM GmbH		LBA TA0295	DHC-8-315 DHC-8-312, DHC-8-314 DHC-8-301, DHC-8-311	Installation of Galley P/N 106049C and P/N 106049D	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	None	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/07/2019	Active	10070473
10070475	QUIET TECHNOLOGY AEROSPACE, Inc.		FAA STC ST04444AT	GULFSTREAM G280	Replacement of the inner aluminum barrel of the engine inlet cowl with aQuiet Technology Aerospace inlet barrel of carbon graphite sandwichconstruction	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04444AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Quiet Technology Aerospace document "Bombardier Challenger 300/350and Gulfstream G280 Inlet Cowl Inner Barrel Replacement Master DrawingList," Report No. QTA 6301, Rev. A, dated 4 January 2019 or later FAAapproved revisions;2. "Bombardier Challenger 300/350 and Gulfstream G280 Inlet Cowl InnerBar...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/07/2019	Active	10070475
10070478	AIRBUS DEFENCE AND SPACE S.A.	REV. 1		A330-243	A330 MRTT FAF OSD-FCref STC 10064192Revision 1 corrects theSTC reference.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Operational Suitability Data – Flight Crew, OSD-FC Final ReportA330 MRTT FAF STC, document number TAS-FF-RP-17-0004, issue C, dated 11October 2018or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	16/07/2019	Active	10070478
10070512	PEREGRINE AVIONICS LLC		FAA ST00882DE	SEE FAA APPROVED MODEL LIST	Installation of Becker Avionics BXT6553 transponder.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00882DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List E-FF-17-0002 Rev. C FAA, Approved 29May 2019 orlater FAA approved revision.2. Instructions for Continued Airworthiness E-FF-17-0008 Rev. IR dated 8February2019 or later FAA approved revision.3. Airplane Flight Manual Supplement E-FF-17-0009 Rev. IR dated 10 May2019 or later...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	15/07/2019	Active	10070512
10070525	ETIHAD AIRWAYS ENGINEERING L.L.C.	REV. 3		A320-232	Overwater & Non-Overwater modificationRemoval and exchange of some components like emergency equipment andslide rafts/escape slides based on the a/c effectivity table included inthe document EA2-19251035-PC01Revision 1: this revision is issued to add further configurations toEA2-19251035-PC01 and to...	The Type and OSD Certification Bases for the original product as amendedby the following additional oralternative airworthiness requirements:Special Condition (s): F-2318-002 Non-rechargeable Lithium BatteryInstallationsthe following paragraph(s) at a later amendment: JAR 25.305 and JAR25.365 (e) atT...	Master Data List EA2-19251035-DL01 Issue 12or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is applicable only to the following MSN: 1944, 2167, 3676,3693, 3713, 4066, 4077, 5714, 5882, 5924<(>,<)> 6134, 6226, 6527Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or r...	19/10/2022	Active	10070525
10070534	AMAC AEROSPACE SWITZERLAND AG			737-700	Replacement of Satcom Antenna HGA-7000Replacement of the existing Satcom High Gain Antenna HGA-7000 with thenew HGA-7001 mounted on the top fuselage (above the ceiling STA480-500)and removal of the existing Beam Steering Unit.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):B-01 Vibration / buffeting compliance criteria for large externalantenna installationE-01Security protection of Aircraft systems and networksThe requ...	The change is defined with Revision A of the Master Data List documentMDL-BZ09-5300.The aircraft shall be maintained inaccordance with Revision A ofInstructions for Continued Airworthiness document ICA-BZ09-5300.or later revisions of the above listed document(s) approved/ acceptedunder the EASA syst...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/07/2019	Active	10070534

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070543	SABENA TECHNICS BGC			757-200, 757-200PF, 757-300	ADSB-OUT System Installation on B757This STC addresses the installation of a 1090MHz Extended SquitterAutomatic Dependent Surveillance – B out (ADS-B out) system. Compliantwith DO-260B on the B757. The system enables to support ADS-B innon-radar and radar area applications (NRA and RAD).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: :Applicableregulations at CS 25 Amendment 4 (refer to the associated CertificationPlan 0390-01-A-CP-R00, section 5 & 6 fo...	- Master Data List, ref : 0390-01-A-MDL-R00- Instructions for Continued Airworthiness (Supplement), ref :0390-01-A-ICA-R00- AFM (Supplement) : 0390-01-A-AFMS-R00or later revisionsof the above listed document(s) approved/ acceptedunder the EASA system.	The MMEL 0390-01-A-MMELS-R00 (or related later approval) isassociatedto this change.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	18/07/2019	Active	10070543
10070554	LB AIRCRAFT ENGINEERING LLC		FAA STC ST04449AT	737-500 737-400 737-300 737-200	Replacement of the dual Honeywell or Collins enhanced Mode Stransponders with a dual ACSS XS-950 Automatic Dependent Surveillance -Broadcast (ADS-B) Out System.Installation of Gables G7490-() control panel to provide Flight I.D.data and Transponder Fail annunciation.Installation of ADS-B Function FA...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04449AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. LB Aircraft Engineering LLC. Master Data List LB-XS950.737-MDLRevision E, dated 25 March 2019, or later FAA approvedrevisions;2. FAA Approved Flight Manual Supplement, LB Aircraft Engineeringdocument LB-XS950.737-AFM, Rev IR, dated 10 May 2019, or later FAAapproved revisions;3. LB Aircraft Engin...	The aircraft must be equipped with Dual Universal Avionics UNS-1FWFlight Management System with WAAS/GNSS sensors to provide High-Integrity GPS position Source.Prerequisite to this installation, the existing transponders must bewired to provide Mode S ELS and Mode S EHS functions.Prior to installati...	19/07/2019	Active	10070554
10070561	AEROCLUBUL ROMANIEI			IS-28B2	Installation of provisions for smoke generators and pyrotechnics on thewing tips.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation of provisions for smoke generators and pyrotechnics on thewing tips in accordance with Aeroclubul Romaniei, document MDL02.MDrL. 002 at Revision 2, dated 05 July, 2017;Aircraft Flight and Maintenance Supplement, Aeroclubul Romaniei,document AR. 02.F03.1012, dated April 2018;or later revis...	Use of pyrotechnics only if permitted by the competent authority of theterritory over which the operation takes place.	22/07/2019	Active	10070561
10070566	SKANDIA, INC.		FAA STC SA04304CH	PC-12, PC-12/45, PC-12/47 PC-12/47E	Installation of Thermal/Acoustic Kits	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04304CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Skandia Master Data List, Report No. Document Number 7803040MDL001,Revision E, dated 25 April 2018, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/07/2019	Active	10070566
10070588	AIR ALLIANCE GmbH			55, 55B 31, 31A, 35, 35A, 36, 36A	GTX 3000 Dual Transponder Installation including ADS-B out	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to Air Alliance Master Document List No. 2017_006_LJ35_55_Form_02, Rev 01To be operated in accordance with AirAlliance AFM-S Document No. 2017_006_LJ35_55_0506, Rev 00To be installed i.a.w. Air Alliance Installation Instruction Doc. No. 2017_006_LJ35_55_0500, Rev 00To be maintained i.a.w. Ai...	- Antenna installation is excluded and needs further approval- Compliance to Mode-S Enhanced Surveillance (EHS) dependson particularaircraft configurationPrior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously in...	24/07/2019	Active	10070588
10070589	AIR ALLIANCE GmbH	REV. 1		35, 35A, 36, 36A	Installation of GA36 GPS Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	According to Air Alliance Master Document List No. 2019-006-MDL, Rev 03To be installed i.a.w. Air Alliance InstallationInstruction Doc. No.2019-006-IM, Initial IssueTo be maintained i.a.w. Air Alliance ICA Document No. 2019-006-ICA,Initial Issueor later revisions of the above listed document(s) app...	- max altitude 45000 ft- not compatible with ECR 1446, 1559, 2675B, 9005 or AAK88-3B- structural installation only, additional approval needed totechnically connect the GPS antenna to the onboard Avionics.Prior to installation of this change/repair it must be determined thatthe interrelationship bet...	24/01/2020	Active	10070589

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070590	ST ENGINEERING AEROSPACE LTD.			A320-231/-232/-233 A320-211/-212/-214/-215/-216	Passenger cabin reconfiguration with STAAS Model 268 seriesEconomyClass seats	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.853(a)(b)(c), CS25.1529 at Amdt 20.The requirements forenvironmental protection and the associatedcertified noise a...	- Aircraft Compliance Summary Report: 366/ QAD/003 Rev B, dated23.July.2019- Master Document List: 366_AED_001 Rev C MDLBassaka Air, dated22.July.2019- Instruction for Continued Airworthiness: ICA-0374-001 Rev C, dated09.July.2019or later revisions of the above listed document(s) approved/ acceptedun...	EASA STC 10058645 shall be installed concurrently with thisapproval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness o...	24/07/2019	Active	10070590
10070591	MAGNETIC MRO AS	REV. 1		737-800/747-400/777-300	Installation of Stretcher Assembly P/N 1123000-050This modification introduces a single Stretcher Assembly (P/ N1123000-050) into the passenger cabin of three aircraft types:- B737-800 (17 aircraft, 8 interior layouts)- B747-400 (9 aircraft, 7 interior layouts)- B777-300 (10 aircraft, 3 interior layo...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 25.29, 25.301, 25.303,25.305, 25.307, 25.321, 25.337, 25.341,25.561(a)(b)(d), 25.601, 25.619,25.625, 25.785(a)(b)(h)(2),(...	18MDL107 Master Data List Issue D dtd. 23 July 201918ICA074Instructions for Continued Airworthiness B737-800 Issue A dtd.07 Mar 1918ICA075 Instructions for Continued Airworthiness B747-400 Issue A dtd.07 Mar 1918ICA076 Instructions for Continued Airworthiness B777-300 Issue A dtd.07 Mar 19or lateru...	EASA STC 10031757 is a pre-requisite to this modification.	19/09/2019	Active	10070591
10070592	NORTHERN AVIONICS S.R.L.			AVANTI II	Installation of Automatic Dependent Surveillance - Broadcast Out (ADS-BOut) system on Piaggio P.180 Avanti II accordingto CS-ACNS subpart D.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:accepted deviation CS-ACNS 1 (certification of an ADS-B Out ExtendedSquitter & ELS installation (Major Change) and its compliance toCS-ACNS).The requirements for environme...	Project specification in accordance with Master Document List, MDL0615Rev. 2Installation in accordance with installation instructions, II-NAV0615Rev. 0Maintenance in accordance with instructions for continued airworthiness,ICA-NAV0615 Rev.0Operation in accordance with Aircraft Flight Manual Supplem...	None.	24/07/2019	Active	10070592
10070599	AEROSCIENCE GmbH			DG-300 ELAN	Winglets for a DG-300 ELAN SailplaneWinglets of new Design for a DG300 ELAN	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Zeichnung Winglet-Nr.: D-300/10 vom 02.06.2016- Compliance Checklist vom 15.03.2019- Ergänzungen zum Flughandbuch vomJuni 2019or later revisions of the above listed document(s)approved/ acceptedunder the EASA system.	None.	25/07/2019	Active	10070599
10070605	SOCIETE AIR FRANCE S.A.			A340-313	A340 Air Mauritius cabin reconfiguration according to SOCIETE AIR FRANCES.A.design change A34017002.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.Special Condition(s): CRI F-001 Non-rechargeable Lithium BatteryInstallationsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the originalu...	SOCIETE AIR FRANCE S.A. Aircraft Maintenance Manual SupplementAMMSA34017002001SOCIETE AIR FRANCE S.A. Flight Crew Operations Manual SupplementFCOMSA34017002-001SOCIETE AIR FRANCE S.A. Cabin Crew Operating Manual SupplementCCOMSA34017002-001 and CCOMS-A340-17-002-002SOCIETE AIR FRANCE S.A. Instructio...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/07/2019	Active	10070605

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070610	SHOCK TRAUMA AIR RESCUE SERVICE			AW139	Installation of Technisonic TDFM-9100 Multiband P25 Airborne TransceiverSystem	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification Data Summary ADC2018-18/MDS Initial Issue dated 25 April2018Rotorcraft Flight Manual Supplement ADC2018-18/FMS16 Initial Issue dated25 March 2018Instructions for Continued Airworthiness ADC2018-18-/ICA16 Initial Issuedated 25 April 2018or later revisions of the above listed document(s)b...	Installation of this STC is limited to the following AB/AW139 ModelS/N's: 41314312774132 3Prior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	26/07/2019	Active	10070610
10070613	B/E AEROSPACE, Inc.	REV. 1	FAA ST04436AT	777-200/-200LR/-300/-300ER/-F 767-200/-300/-300F/-400ER 757-200/-200PF/-300 757-200/-200PF/-200CB/-300 737-900ER 737-600/-700/-800/-900/-900ER 737-600/-700/-700C/-800/-900	Installation of Rockwell Collins Multi Mode Receivers (MMR)on Various14 CFR Part 25 AircraftThe STC consists of the following: - Installation of Dual Rockwell Collins Multi-Mode Receivers (MMR)GLU-2100 in replacement of the existing MMRs located in the Main Equipment Center<(>,<)> - I...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:25.23(a),25.301(a) (b), 25.303, 25.305(a), 25.307(a), 25.561(c), 25.601,25.603(b)(c), 25.611,25.853(a), 25.863(a), 25.130...	- Approved Model List (AML), ref. 2-197183-002 rev. C datedMAR 18,2019.- Project Specific Validation Report, ref. 2-197183-999 rev. D datedJuly 12, 2019.- Master Drawing List (MDL), ref. 2-197183-001_F (Boeing 737-NG).- Master Drawing List (MDL), ref. 2-197183-001_F (Boeing 757).- Master Drawing Li...	As part of this modification, no new functionalities shall be activated.All existing functionalities shall be retained.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will i...	20/12/2024	Active	10070613
10070622	BELL HELICOPTER TEXTRON, Inc.		FAA SR11242DS	505	Installation of Avionics Rain Shield.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11242DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Drawing List, Report No. AA-19021, Revision A, dated2 May 2019,or later approved revision.Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-19023, No Revision, dated 30 April 2019, or later approvedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/07/2019	Active	10070622
10070628	STG AEROSPACE GERMANY GmbH	REV. 1		F28 MARK 0100 F28 MARK 0070 F27 MK0604 F27 MK0502 F27 MK050	saf-Tglo® PHOTOLUMINESCENT AISLE PATH MARKING SYSTEM FOKKERSERIESAIRCRAFTRevision 1: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA Approved:-STG AEROSPACE LTD AIRPLANE FLIGHT MANUAL SUPPLEMENT No. SG-1018-FMS-01Revision IR-STG AEROSPACE LTD INSTRUCTIONS FOR CONTINUED AIRWORTHINESS No.SG-1018-ICA-01 Revision IR-STG AEROSPACE LTD MMEL SUPPLEMENT No. SG-1018-MMEL-01Revision IR-STG AEROSPACE LTD CABIN CREW DATA SUPPLEMENT No....	SSUL Green Emitting PL insert shall not be mixed with SSUL Blue EmittingPL insert on the same aircraft installation.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intr...	12/02/2021	Active	10070628
10070634	NEXTANT AEROSPACE, L.L.C.	REV. 2	FAA ST04357CH	CL-600-2B16 (604 VARIANT)	Installation of the Safe Flight Instrument Corporation AutoPower®Automatic Throttle Control System (ATS)Rev. 1 involvesthe upgrade of the Rockwell Collins Pro Line Fusion FMSsoftware to FMS v2.1.Rev. 2 corrects typos.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.1301(a), CS25.1309(a) [amendment 3], Software aspects only.The requirements for environmental protection and the ass...	Master Data List NT0017-MDL0-100, Revision E, dated 14 May 2021.Airplane Flight Manual Supplement, Document No. NT0017-AFMS-0100,Revision C, approved June 28, 2021, is required onboard a modifiedaircraft configured with the Rockwell Collins Pro Line Fusion®integrated avionics and operating with FMS...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/02/2022	Active	10070634

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070636	ROW 44, Inc.	REV. 1	FAA ST03304NY	737-700/-800/-900ER 737-700/ 37-800	Installation and activation of a new Row 44 Wireless Broadband AntennaSystem.Rev. 1 adds the model 737-900ER.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03304NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Data Index List (MDIL) RWC100-0004-00, Revision E,dated 28December 2020- Instructions for Continued Airworthiness (ICA) a. Comply with FAA accepted Instructions for ContinuedAirworthiness (ICA), revision that is called out bythe Master Data List (MDL) for a given model found in the ab...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.- In order to access satellite broadband, the R...	06/04/2021	Active	10070636
10070639	ANCRA INTERNATIONAL LLC		FAA STC ST02135LA	757-200	Installation of main deck cargo loading system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02135LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Ancra International LLC Controlled Data List DL 84880, Revision "A",dated 17 March 2008, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.EASA STC 10038822 (FAA STC ST03952AT) must be in...	02/08/2019	Active	10070639
10070642	LUFTHANSA TECHNIK AG			767-300	LATAM Business Class Cabin Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	STDD 00-17/11M Iss./ Rev.: 1 / 0Instructions for continued Airworthiness A-00-18/72-ICA Iss./ Rev.: 1 /0Compliance Checklist CCL00-17/11M Rev. 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/07/2019	Active	10070642
10070651	SPAES GmbH & Co. KG			EC 155 B, EC 155 B1	Installation of Medical Equipment Retainer P/N SDG-155-208-25-01.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance Check List doc. No. CCL-155-208-25-01, Issue 00,dated16.05.2019Master Document List Doc. No. MDL-155-208-25-01, Issue 00, dated16.05.2019Rotorcraft Flight Manual Supplement Doc. No. FMS-SPAES-0208, Issue 00Declaration of Compliance Change Doc. No. DCC-155-208-25-01, Issue 00,dated 09.07....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/07/2019	Active	10070651
10070655	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST04077NY	A330-941 A330-341, -342, -343 A330-321, -322, -323 A330-301, -302, -303 A330-223, -223F, -243, -243F A330-201, -202, -203 A330	Installation of a gogo 2Ku Cabin Connectivity SystemRev. 1:approves alternate location for the Ka radio frequency unit(KRFU).	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List 0154-10627-2466 RevisionW dated 21August 2023<(>,<)>Airplane Flight Manual Supplement 0654-10628-2466 Rev. Adated 8 June 2019<(>,<) >Instructions for Continued Airworthiness 0754-10629-2466 Rev. E dated 8October 2020<(>,<) >Weight and Balances Report D12716-21704, R...	Operational approval to use T-PED's must be obtained separately fromthis STC.EASA STC 10076932 (FAA STC ST04076NY) is apre-requisite for theinstallation of this STC design changeunless configuration installed isonly for gogo Vision.Priorto installation of this change/repair it must be determinedt...	28/02/2024	Active	10070655

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070657	DELTA ENGINEERING CORPORATION	REV. 6	FAA ST03422NY	SEE FAA AML	Update of Connectivity ComponentsRev 1: New types/models added (737-8, 737-9, 787, A220, A330, A340, A350and A380), software update and radome SRM changes.Rev 2: Correction of Associated Technical Document reference.Rev 3: Amendment to theinstallation of a Gogo 2Ku components on all themakes and mo...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 amdt 4:25.571 (e)(1), 25.853, 25.869, 25.1581< (>,<)> 25.1583, 25.1585 and25.1587.The requirements for environmental p...	Delta Engineering Approved Model List 0198-10082-2419, Revision BG,dated 26 September 2024;Instructions for Continued Airworthiness 0798-10078-2419 Revision Ddated 24 September 2024;Master Data List 0198-11707-2419 Revision W dated 18 November 2024;or later revisions of the above listed document (s)b...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for aircraft types and models a...	31/01/2025	Active	10070657
10070667	PEREGRINE AVIONICS LLC		FAA STC SR00925DE	SEE FAA APPROVED MODEL LIST	Installation of Garmin GTX 335/335R and GTX345/345R transponders toprovide ADS-B Out and In functionality	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00925DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List, Peregrine Document Number E-AM-17-0002, RevisionE<(>,<)> dated 16 November 2018, or later FAA approved revision;2. Peregrine Rotorcraft Flight Manual Supplement (RFMS) E-AM-17-0009,Revision IR< (>,<)> dated 18 May 2018, or later FAA approved revision;3. Peregrine InstructionsE...	See Specific Limitations § 2.2. of FAA Approved Model List.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness of t...	06/08/2019	Active	10070667
10070669	ELDEC LLC		FAA STC ST02408SE	SEE FAA AML.	Installation of a Crane Aerospace & Electronics Tire SensorAssembly	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02408SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Crane Aerospace Master Document List (MDL) as listed on AMLST02408SE,or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	09/08/2019	Active	10070669
10070670	JET AVIATION ST. LOUIS, Inc.		FAA STC ST03311CH	BD-700-1A10, BD-700-1A11	Wireless Fidelity (Wi-Fi) Activation of a Previously Installed (IEEE802.11 b, g only) Router and Transmitting Portable Electronic Device(T-PED) Aircraft Tolerance Testing.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Jet Aviation St. Louis, Inc. Master Data List 35-409G009, Revision E,dated 29 June 2014, or later FAA approved revision.The FAA approved AFMS document, defined by the Master Data List, isrequired.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/08/2019	Active	10070670
10070673	AIRBUS HELICOPTERS CANADA LIMITED		TCCA STC SH18-56 ISSUE 1	AS 350 B3, EC 130 T2	Installation of Mid-Continent MD15-322 altimeter to replaceAerosonicaltimeter P/ N 15025-0175.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing Lists MDL-18-004 issue A, TCCA approved, October 2, 2018Instructions for Continued Airworthiness ICA-AHCA-303 Revision 0, TCCAaccepted, dated August 27<(>,<)> 2018or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Imp...	Installation of Garmin 500H is a pre-requisite. Refer to the MOD listedbelow:MOD 074731 (AS 350 B3)MOD 074529 (EC 130 T2)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairand any otherpreviously installed change and/ or repair will...	06/08/2019	Active	10070673

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070677	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	MBB-BK117 D-2	Dual Cargo Hook Control Pendant.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Record Index MRI/ 1453214-01 Revision A dated 01/08/2019 forfixed provisions and role fit;- BK117 D-2 Approved RFM Supplement AHUK/145-FMS-109 Revision 0;- Instructions for Continued Airworthiness ICA/ 1453214-01 Revision Bdated 17/07/2019;- Airworthiness Certification Plan for System Interfa...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/08/2019	Active	10070677
10070687	S-TEC CORPORATION		FAA STC SA8892SW-D	172M, 172N, 172P, 172Q	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-563	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA8892SW-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	1. Bulletin No. 663, Revision 5, dated 1 February 2001 and MasterDrawing List No. 92732, Revision E, dated 1 February 2001, or later FAAapproved revisions of the above data (28 Volt System).2. Also eligible on Textron models 172M, 172N and172P, when modified by180 H.P. engine conversion.3. FAA/DASN...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/08/2019	Active	10070687
10070697	SEBALD LUFTFAHRTTECHNISCHER BETRIEB(LTB)	REV. 2		SEE EASA APPROVED MODEL LIST SEE APPROVED MODEL LIST	Airbrake spring elementOptional installation of a spring element in the airbrake push rodsystem for constant locking force and possibility of visual inspectionof the locking force.Rev. 1 makes several drawings changes or corrections, to preventmistakes due to missing information in manufacturing. Al...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Technical drawings:- 1801B10E001.1- 1801B10E001.2- 1801B10E001- 1801B10E002.3- 1801B10E002.4- 1801B10E002- 1801B10E003-1801B10Z001- 1801B11E002- 1801B11Z001or later revisions of the above listed document(s) approved/ acceptedunder the EASAsystem.	None	14/12/2020	Active	10070697
10070698	BOMBARDIER Inc.		TCCA STC SA19-10	BD-100-1A10, CL-600-2B16	Installation, Galley with Compartment for Commercial Appliances orEquipment.EASA Validation of Transport Canada (TCCA) STC SA19-10 at Issue 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Modification must be in accordance with the following approveddocuments:a) For aircraft BD-100-1A10: B/E Aerospace Ltd.Modification DataSummary L711001 Rev NC, 27 June 2019, andb) For aircraft CL-600-2B16: B/E Aerospace Ltd. Modification DataSummary L711000 Rev NC, 27 June 2019.Instructions for Con...	The following STC's must be embodied as pre-requisite installation:a) TCCA STC SA04-112 (validated through EASA STC 10016423 Rev. 38 orlater revisions) for BD-100-1A10 aircraft, andb) TCCA STC SA06-90 (validated through EASA STC 10016019 Rev. 63 orlater revisions) for CL-600-2B16 aircraft.Prior to i...	12/08/2019	Active	10070698
10070716	AVCON INDUSTRIES, Inc.	REV. 1	FAA STC SA01924WI	B200C B200 A200 200C 200, 200C, A200, B200, B200C 200	Installation of an External Pod and Retractable EO/IR Sensor LiftMechanismRev. 1: adds a new configuration to the B200/B200C models.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List, Document No. 04601001, Rev. IR, dated 3 June 2019<(>,<)>2. Airplane Flight Manual Supplement, Document No. 04607101, or No.04607102, or No. 04607103, all at Rev. 0, all dated 28 May 2019<(>,<)>3. Airplane Flight ManualSupplement, Document No. 04607104 or No.04607105, both at Re...	Installation of the Sensor Lift Mechanism requires prior orconcurrentinstallation of EASA STC 10070462 (FAA STC SA01902WI).Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or r...	19/10/2022	Active	10070716

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070718	SII DEUTSCHLAND GMBH	REV. 1		EC135 T2, EC135 T2+ EC135 T2+ EC135 P2, EC135 P2+, EC135 T2 EC135 P2, EC135 P2+	VABENE 4K-Mission SystemReal-time airborne monitoring system consisting of external sensor podinstallation to the multifunction step, and installation of theprocessing unit in thecargo area.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-27 Amd. 2.The requirements for environmental protection and the associatedcertified noise and/ or emissi...	Compliance Program CP-239-00014-000, Issue ECompliance Report CR-239-00014-000, Issue CMaster Document List MDL-239-00014-000, Issue AFlight Manual Supplement FMS-239-00014-000, Issue Dor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Operation under Instrument Flight Rules (IFR) and Category A operationare not allowed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon th...	27/08/2019	Active	10070718
10070736	AVCON INDUSTRIES, Inc.		FAA STC SA01893WI	B300C B300	Installation of a Retractable EO/IR Sensor Mechanism.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01893WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Butler National Corporation Master Data List, No. 04601000, Rev. IR,dated 21 November 2018;2. Avcon Industries Airplane Flight Manual Supplement, No. 0467100, Rev.IR, dated 24 October 2018;or later FAA approved revisions to 1 or 2.	Prior to, or concurrent, installation of fuselage undersiderailmounting provisions.Prior to, or concurrent, installation of an external fuselage undersideradar pod in accordance with EASA STC 10061893 (FAA SA2300CE).Prior to installation of this design change it must be determined thatthe interrela...	16/08/2019	Active	10070736
10070737	SCANDINAVIAN AVIONICS DESIGN ApS			SAAB SF340A, SAAB 340B	MODE S & ADS-B UPGRADEThe change consists of replacing the existing single/dual Transpondersystem with a Transponder system capable of MODE S ELS/EHS and ADS-B OUTfunctionality according Minimum Operational Performance Standards (ADS-BVersion 2 as per DO-260B including Corrigendum 1 MOPS).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): See CRI F-102The following paragraph(s) at a later amendment:CS 25 Amendment 2 CS 25.1, CS 25.29, CS 25.301, CS 25.303, CS 25.305, CS25.307, CS 25.341, CS 25...	1. Approved Aircraft Flight Manual Supplement, Document Ref: 2120322-AMA, Issue 1, dated 29.07.19.2. Continued Airworthiness, Document Ref: 2120322-CA A, Issue 1, dated28.07.19or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None.	16/08/2019	Active	10070737
10070744	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			737-700	Maximum Take Off Mass Change in accordance with EASA recordA121336.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual Supplement MODE00281_AFMS1 rev 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Applicable to Boeing 737-700 aeroplanes, equipped with winglets andCFM56-7B22 engines, AFM option code <97224W>.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	19/08/2019	Active	10070744
10070755	S-TEC CORPORATION		FAA STC SA09134AC-D	F172N F172M	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-612	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09134AC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Bulletin No. 712, Revision 2, dated 28 February 2001 andMasterDrawing List No. 92827, Revision B, dated 28 February2001 or later FAAapproved revisions of the above data;2. FAA/DAS Approved Supplemental Flight Manual, P/N 891221, dated4December 1995 is required for Reims Aviation S.A. Cessna Mo...	Also eligible on Models F172M and F172N when modified by 180 H.P. EngineConversation.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect u...	20/08/2019	Active	10070755
10070756	S-TEC CORPORATION	REV. 1	FAA STC SA09754DS	T303	Installation of a S-TEC 01326 Digital Flight Control System(DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09754DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Data List No. ST-971-MDL-0001, Revision A, dated 3April 2019,or later FAA approved revision.- Airplane FlightManual Supplement, ST-971-AFMS-0001, Revision -, dated3 April 2019, or later FAA approved revision.- Instructions for Continued Airworthiness, ST-971-ICA-0001, Revision -,dated 14...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/08/2019	Active	10070756

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070757	S-TEC CORPORATION	REV. 1	FAA STC SA09753DS	1900, 1900C	Installation of a S-TEC 01326 Digital Flight Control System(DFCS).	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09753DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Data List No. ST-970-MDL-0001, Revision A, dated 3April 2019,or later FAA approved revision.- Airplane FlightManual Supplement, ST-970-AFMS-0001, Rev. -, dated 3April 2019, or later FAA approved revision.- Instructions for Continued Airworthiness, ST-970-ICA-0001, Revision -,dated 6 March...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/08/2019	Active	10070757
10070774	GROB AIRCRAFT SE			T207A T207 207A 207	Approval of GROB Aircraft SE modification ref OCN C207-01 to installDual Garmin G5 Instruments.	CS 23 Amendment 4The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation in accordance with GROB Aircraft SE modification ref OCNC207-01 to install Dual Garmin G5 Instruments and Garmin STC 10060846;- Operation in accordance with Garmin approved Flight Manual Supplementsas defined in EASA STC 10060846 and GROB Aircraft Flight ManualSupplement A1 Doc No G-C...	After modification the aircraft is restricted to a maximum total of six(6) occupants including the Pilot(s).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no...	21/08/2019	Active	10070774
10070776	SIKORSKY AIRCRAFT CORPORATION		FAA STC SR02421NY-D	S-92A	Installation of Center Console Four Inch Extension.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02421NY-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	- Keystone Helicopter Installation Drawing List IDL01260, Rev. A, dated26 June 2007, or later FAA approved revision.- Keystone Helicopter Instructions for Continued Airworthiness,CenterConsole Extension Installation in Sikorsky S-92A Aircraft, Report No.IC01260, Rev. -, dated 3 May 2007, or later F...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/08/2019	Active	10070776
10070777	SPAES GmbH & Co. KG			MBB-BK117 B-2/ MBB-BK117 C-1 MBB-BK117 A-4/ MBB-BK117 B-1 MBB-BK117 A-1/ MBB-BK117 A-3	Installation of Nightscanner in lower forward fairing of MBB-BK117helicopters as mission equipment for searching and landing.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 29 Amdt.4 CS29.1316, CS 291317.The requirements for environmental protection and the associatedcertified noise and/ oru...	EASA approved documents:- Flight Manual Supplement, FMS-SPAES-0207, Revision 00 dated 10 July2019;- Airworthiness Limitations Section, Section 8 of Instructions forContinued Airworthiness, ICA-117-207-33-01, Ausgabe 01 dated 15 August2019.EASA accepted documents:- Master Document List, MDL-117-207-3...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/08/2019	Active	10070777
10070785	RSG PRODUCTS, Inc.D/B/A INTEGRATED FLIGHT SYSTEMS, IN		FAA STC SR02445NY-D	S-76C	Installation of a Canadian Marconi (CMC) CMA-2012C in placeof a RACAL91 Doppler	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Keytech Installation Drawing List 1DL01769 Rev. C, dated21 April2008 or later FAA accepted revision.2. Keystone Helicopter Instructions for Continued Airworthiness, CMCCMA-2012C Doppler Sensor Installed in a Sikorsky S-76C Aircraft, ReportNo. IC01769 Rev. -, dated 15 March 2008 or later FAA acce...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/08/2019	Active	10070785

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070786	ALAMO ENGINEERING GmbH	REV. 1		CL-600-2B19 (RJ SERIES 100) CL-600-2B19	Satcom Upgrade to SBB Aviator 700E including GSM and WLAN via SDR-G.The project consists in upgrading the existing Inmarsat AERO H+ SATCOMsystem to SBB “Aviator 700E” along with the installation of the SDR-Ggateway (Satcom Direct) including Wi-Fi and 3G/4G functionality.Rev. 1: transfers the STC fro...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List: MDL160Z001, Issue A, dated 21 August 2019.- Airplane Flight Manual Supplement: AFMS010D231Z0001, Issue A, dated 23July 2019.- Aircraft Maintenance Manual Supplement: AMMS010D231Z0001, Issue A,dated 9 July 2019< (>,<)>or later revisions of the above listed document (s) approved/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/12/2023	Active	10070786
10070793	HELICOPTER FILMWORKS INC.	REV. 1	TCCA SH16-6	AS 355 F2/ AS 355 N/ AS 355 NP AS 355 E/ AS 355 F/ AS 355 F1 AS 350 B/ AS 350 B1/ AS 350 B2 AS 350 B3/ AS 350 BA/ AS 350 D	Installation of single and double mounts external cameras.Rev.1: correction of certificate.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Eligibility List CE-HFW-001, Rev 04 of April 27, 20172. Installation Instructions: a. CI-HFW-001-1, Rev 3 dated March 26, 2017 (Single mount) b. CI-HFW-001-2, Rev 3 dated March 26, 2017 (Dual mount)3. Instructions for Continued Airworthiness: a. CC-HFW-001-1, Rev 3 dated March 26, 2017 (Single...	Day & Night VFR only.No CAT A operations permitted (for AS 355).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the...	29/11/2019	Active	10070793
10070797	FREIBALLONSPORT-VEREIN MUENSTERUND MUENSTERLAND e.V.			NL-STU/1000	Leichtbaukorb Völker K-01	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS-31GB initial issue.The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	- Zulassungsprogramm EASA Projekt 0010061295 Völker K-01, dated 22 Aug. 2019, initial issue;- Flughandbuch Anhang VölkerK-01, dated 22 Aug. 2019, initial issue;or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Other: Leichtbaukorb Völker K-01 kann nur mit Hülle Ballonbau WörnerNL-STU/1000 SN 1098 betrieben werden.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no ad...	23/08/2019	Active	10070797
10070799	DART AEROSPACE Ltd.			EC 130 T2 EC 130 B4	D130-1048 Landing Gear Kits	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions IIN-D130-1048 Rev B, dated February 13, 2019Instructions for Continued Airworthiness ICA-D130-1048 Revision 0, datedDecember 20, 2018Master Document ListMDL-D130-1048 Rev A, dated February 14, 2019or later revisions of the above listed document(s) approved/accepted onbehal...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2019	Active	10070799
10070801	LUFTHANSA TECHNIK AG	REV. 1		A320-271N	Cabin conversion 188 to 180 paxRevision 1: Qualification ofexisting Cabin Attendant Seat at door 4L in16g environment	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): ESF D-2340-001 “Dynamic seatqualification – Vertical test.The requirements forenvironmental protection and the associatedcertified noise a...	- Compliance Check List CCL25-19/34M Revision 2 dated 28.May.2020- Compliance Check List CCL_25-19/10M Issue 7 dated 20.Aug.2019- Supplemental Type Design Document STDD25-19/10M Issue 02 Revision 0dated 25.May.2020- Supplemental Type Design Document STDD25-19/10M Issue 01 Rev 00 dated21.Aug.2019- In...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/05/2020	Active	10070801

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070805	FOKKER SERVICES B.V.			767-200/-300/-300F/-400ER	ADS-B on the Boeing 767This change introduces ADS-B out capability on the Boeing 767. The ATCTransponders will be changed and they will interface with the GNSSposition sensor.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Initial issue of CSACNS.D.AC.010, CS ACNS.D.AC.015, CS ACNS.D.AC.020, CS ACNS.D.AC.025, CSACNS.D.AC.030, CS ACNS.D.AC.035,...	- The change is defined with issue 1 of Master Document List DocumentB767-ADSB-OUT-MDL-0001.- Aircraft operation shall be accomplished in accordance with issue 1 ofAirplane FlightManual Supplement Document B767-ADSB-AFM-S-001.- Training shall be accomplished in accordance with issue 1 of FlightCrew...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2019	Active	10070805
10070818	AEROMECANIC			DR 400/140 B	Installation of a KI-204 and approval of GNS 430 for Night VFRnavigation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment:CS23 Amendment 4 (16/07/2015): 23.1301 – 23.1309 – 23.1321 –23.1351 –23.1357 – 23.1431.The requirements for environmenta...	Modification sheet EMA/17/002/DR400/GNS430 Revision 3 dated03.06.2019;Aeroplane Flight Manual Supplement Edition 1 Revision 0 dated27.02.2018;or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Installation of this change is limited to aeroplane DR 400/140 B SerialNumber 2378, registered F-GSRS	28/08/2019	Active	10070818
10070819	SIRIUM AEROTECH S.L.	REV. 1		737-300/-400/-500 737-100/-200/-200C	ADS-B System Upgrade for B737Revision 1: added reference tominor change SA20-32M for MMEL-S	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplement to AFM SA19-02S-AFMS Revision 2;- Supplement to Aircraft Maintenance Manual SA19-02S-AMMS Revison 1- Master Document List SA19-02S-MDL Revision 4- MMEL supplement SA19-02S-MMELS rev 0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/09/2020	Active	10070819
10070821	SABENA TECHNICS BOD			A330-223	A330-223 P710 : Egide GPS antenna relocation.This modification supports the relocation of a GPS antenna, component ofthe Egide Safe Protection System (SPS) modification. The GPS antenna isalso renewed due to obsolescence matter.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List ref : MDL- S-23-4203 Issue A, dated 20 August 2019- Instruction for Continued Airworthiness, ref : ICA-F3042-00-003 IssueE, dated 20 August 2019- Instruction for Continued Airworthiness, ref : ICA-F3065-23-008 IssueA, dated 13 August 2019or later revisions of the above listed docu...	The following modifications are prerequisites to this modificationembodiment:- EASA STC 10032391 rev 2 - P710 VIP CabinCompletion- EASA STC 10055282 rev 4 - Egide Safe ProtectionSystem (SPS)modification.Prior to installation of this change/repair it must be determined thatthe interrelationship bet...	29/08/2019	Active	10070821
10070898	DART AEROSPACE Ltd.		TCCA SH19-31 ISSUE 1	505	Dart D505-1057 Skid tube Installations	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS27.1, 27.21, 27.25,27.27, 27.29, 27.45, 27.141, 27.241, 27.251, 27.301, 27.303, 27.305,27.307, 27.309, 27.337(a), 27.471...	- Installation Instruction IIN-D505-1057 Rev. A dated 31 May 2019- Instruction for Continued Airworthiness ICA-D505-1057 Rev. 0 date 29April 2019- Master Document List MDL-D505-1057 Rev. A dated 03 June 2019or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in acco...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/09/2019	Active	10070898

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070901	MT-PROPELLER ENTWICKLUNG GmbH			441	Installation of MTV-27-1-E-C-F-R(G)/CFR () on Cessna 441	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- According to MT-Propeller Master Documentation List No. E-3416 Rev. 0- To be operated in accordance with MT-PropellerAFM-S Document No.E-3418 Rev. 0- To be installed i.a.w. Installation Instruction Doc. No. E-3419 Rev. 0- To be maintained i.a.w. MT-Propeller ICA Document No. E-3420 Rev. 0or later...	According limitation section of AFM-S.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/09/2019	Active	10070901
10070903	APUS - AERONAUTICAL ENGINEERING Gmb	REV. 1		F182P, F182Q 182S, 182T, T182T 182Q, 182R, 182P, 182N	Skydive Operation on C182 with 5 parachutists.The change isbased on existing modifications for operation with 4parachutists.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with APUS List of Design DefinitionDocuments, No P70-A18131 at issue 00, dated 29 May 2019;Operation in accordance with APUS Aircraft Flight Manual Supplement, NoP41-900182 at revision 01, dated 03 May 2019;or later revisions of the above listed document(s) approved/accept...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/09/2019	Active	10070903
10070911	FOKKER TECHNIEK B.V.	REV. 1		ATR 72-212 A	Introduction of Inmarsat and Iridium SATCOM system incl. WLAN system onATR 72-212A "600 version"Revision 1: Transfer ofSTC from Fokker Services B.V. (EASA.21J.059) toFokker Techniek B.V. (EASA.21J.667)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Compliance Record Report ref. CRR-0252 issue 1 dated 04 Sept. 2019AFM Supplement ref. 19-DO-014 issue 1 dated 12 July 2019 (ATR7STT-AFM-S-001 dated 11 July 2019)ICA Supplement ref. SE-790 issue 2 dated 18 July 2019or later revisions of theabove listed document (s) approved/ acceptedunder the EASA sys...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/12/2019	Active	10070911
10070914	HONEYWELL INTERNATIONAL Inc.	REV. 1	FAA STC ST02704LA	SEE FAA AML	Installation of the Honeywell Fuselage Anti-Collision Light(FACL)SystemRev. 1 is a change of the certificate holder's address and an additionof Boeing 757, 767 and 777 series models.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Honeywell Master Drawing List identified on the AML.The Instructions for Continued Airworthiness (ICA) identified on theAML.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	28/01/2021	Active	10070914
10070921	UMLAUT ENGINEERING GMBH	REV. 1		A321-272N/-272NX A321-253N/-253NX/-271N /-271NX A321-252N/-252NX A321-251N/-251NX A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of Low Frequency Underwater Locator Device LF-ULDAn ARINC 677 type Low Frequency Underwater Locator Device(LF-ULD),manufactured by Novega (model SID88), will be installed in theunpressurized Section 19 of the aircraft.Revision 1: Change of Design Organisation's name to "umlaut engineer...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 Amdt 18Special Conditions:SC CRI F-01 Non-rechargeable Lithium Battery InstallationsThe requirements forenvironmental protection and the associatedcertified noise a...	Master Data List, document No: P3-AAR01-MDL-0001, Issue A.Instructions for Continued Airworthiness, document No: ICAP3-AAR01-ICA-0001, Issue A.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/11/2019	Active	10070921

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070938	SCANDINAVIAN AVIONICS DESIGN ApS			500, 550, 560, S550	UNS-1()w UPGRADE FOR CPDLC and LPVThe purpose of this STC is to upgrade of an existing Universal FMSsystem for the following options: 1. CPDLC communication installation<(>&<) > 2.LPV installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 2 - CS25.1, CS 25.29, CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS 25.341,CS 25.561, CS 25.581, CS 25.6...	Instructions for Continued Airworthiness for CPLDC, Doc: 2111211-CA A ,Issue 1Instructions for Continued Airworthiness LPV, Doc: 2111211-CA B, Issue 1Aircraft Flight Manual Supplement for CPDLC, Doc: 2111211-AM A, Issue 1Aircraft Flight Manual Supplement for LPV, Doc: 2111211-AM B, Issue 3or later r...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/09/2019	Active	10070938
10070943	GARMIN INTERNATIONAL, Inc.	REV. 2	FAA STC SA01896WI	510	Approval of installation of Garmin G1000 NXi Integrated Avionics SystemHardware and Software Updates, including Optional Flight Stream 510.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Based on Regulation 748/2012 Annex I (Part 21), and the EASA policy forsignificant changes, the certification basis for this change is asfollows:a. The certification basis...	Installation in accordance with Garmin Master Document List(MDL) Number005-01328-00 revision 1<(>,<)>dated 4 February 2019.Operate in accordance with Garmin Airplane Flight Manual Supplement Dwg.Number 190-02450-02revision 1, dated 4 February 2019 and<(>,<)>EASA approved Flight Manual Supplement Ga...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/07/2021	Active	10070943
10070952	AYESA AIR CONTROL INGENIERIAAERO NAUTICA SL			FALCON 10	REPLACEMENT OF CVR IN FALCON 10	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AAC118127YCP01MD0101 MASTER CERTIFICATION DOCUMENT LIST ISSUE 1AAC118127YIC01MM0101 MAINTENANCE MANUAL SUPPLEMENT ISSUE1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/09/2019	Active	10070952
10070963	SABENA TECHNICS BGC			737-800	RAVE IFE System Installation on B737-800	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: the followingparagraph(s) at a later amendment: CS-25 amendment 4 paragraphs: 1, 29,301, 303, 305, 307, 321, 337, 341, 365...	- Master Data List, ref : 40166-02-A-MDL-R00- Instructions for Continued Airworthiness (Supplement), ref : 40166-02-A-ICA-R00- AFM (Supplement) 40166-02-A-AFMS-R00or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/09/2019	Active	10070963
10070965	BOMBARDIER Inc.		TCCA Q-LSA19-031/D	BD-700-1A10	Cabin Refurbishment and CMS Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, Kmlex Aviation Inc. document No. MDL39123002,Revision NC, dated 10 June 2019Instructions for Continued Airworthiness, Bombardier Inc. document No.BAS67010215-ICA-1, Revision NC, dated 14 May 2019or later revisions of the above listed document(s) approved/accepted onbehalf of EA...	Limited to aircraft serial number 9287.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/09/2019	Active	10070965

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10070969	AERODATA AG			B300	Installation of an Aerodata automatic flight inspection system(AD-AFIS-220NG).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Master Document List, documentMDL-A/C-927 Rev. 0 dated 13 September 2019;Operation in accordance with Aircraft Flight Manual Supplement, documentAFM-171 Rev. 3 dated 11.9.2019;Instructions for Continued Airworthiness in accordance with AircraftMaintenance Manual Suppl...	Limited to B300 aircraft with installed Rockwell-Collins Proline FusionAvionics.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changeand/ or repair will introduce no adverseeffect upon the airw...	13/09/2019	Active	10070969
10070970	INGENIEURBUERO CALSBACH UG	REV. 2		LS6-B LS6-A LS6 LS 4-A, LS 6, LS 6-A, LS 6-B LS4-A LS4 LS 1-C, LS 1-D, LS 1-F, LS 4	Connector replacement - Service Bulletin SB STC 10070970-1	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Service Bulletin SB STC 10070970-1	Applicable only for STC 1007	20/10/2022	Active	10070970
10070980	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CL-600-2B16 (601-3A VARIANT)	Replacement of Laseref I by Laseref IV,,Removed: Triple Honeywell Laseref I (2 x HG1075AB04 and 1x HG1075GB05) Installed: Triple Honeywell Laseref IV (HG2001G40) - Triple Shadin D/ AConverter (834510-00) ,,	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List: AC5574-049, Rev. A-Instructions for Continued Airworthiness: AC5574-085, Rev. A-Airplane Flight Manual Supplement: AC5574-071, Rev. Aor later revisions of the above listed documents approved by EASA.	S/N 5042 (HB-IKS)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	17/09/2019	Active	10070980
10070986	DOA AESGLOBAL LIMITED	REV. 2		757-200/-200PF/-300 737-900ER, 737-8, 737-900 737-500/-600/-700/-800/-900 737-100/-200/-200C/-300/-400	INTRODUCTION OF ZERO PASSENGER CONFIGURATIONRevision 1 extends the applicability.Rev 2: Transfer from AES Ltd. to new STC holder AES Global Ltd.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 at Amendment 23:25.1; 25.29; 25.601; 25.603; 25.785; 25.787; 25.791; 25.795; 25.803;25.812; 25.813; 25.815; 25.817; 2...	AES Limited Master Data List No. AES-000-5726MDL Issue 1AESLimited Flight Manual Supplements:AFM Supplement No 89 Issue 1 FLIGHT MANUAL SUPPLEMENT - Introduction ofZero PassengerConfiguration (757) Applicable to Configuration 1AFM Supplement No 90 Issue 1 FLIGHT MANUAL SUPPLEMENT - Introduction of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/04/2021	Active	10070986
10071002	LUFTHANSA TECHNIK AG			767-300F, 767-400ER 767-200, 767-300	Replacement of existing Multi-Mode Receivers with HoneywellIntegratedMulti-Mode Receivers introducing SBAS capability	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Design Document STDD34-19/04M Issue 1.0Instructions for Continued Airworthiness A-00-19/73-ICA Issue/Rev 01/02Airplaine Flight Manual supplement A-00-19/70-AFM Issue/Rev 01/00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/09/2019	Active	10071002
10071037	SABENA TECHNICS BGC			A330-243 A330-203, A330-223 A330-201, A330-202	Privacy door installation between the L11 lavatory and the crew rest.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 amendment 4: 1,25, 27, 29, 301, 303, 305, 307, 321, 337, 341, 365, 561, 601, 603, 605,607, 609, 611, 613, 625, 772,8...	- Master Data List, ref 40338-01-A-MDL-R00-Instructions for Continued Airworthiness, ref : 40338-01-A-ICA-R01-Master Minimum Equipment List supplement, ref: 40338-01-A-MMELS-R00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The Change related to this STC has to be embodied on aircraft with theminor MOD 40416-01 - A330-200 – Electrical provision installation forthe privacy door installation along the cockpit aisle.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this ch...	20/09/2019	Active	10071037

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071041	AMAC AEROSPACE SWITZERLAND AG			747-8	Installation of J-Music SystemThis change includes the required modifications to the aircraftincluding installation of all system components for a fully functioningsystem.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25.1301 Amdt 2;CS25.1309 Amdt 2; CS25.1316 Amdt 20; CS25.1317 Amdt 20;The requirements for environmental protection andc...	The change is defined with Revision C of Master Data List DocumentMDL-B7471-1-5300The aircraft shall be operated in accordance with Revision B of AirplaneFlight Manual Supplement document AFMS-B7471-1-5300.The aircraft shall be maintained in accordance with Revision G ofInstructions for Continued Ai...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/09/2019	Active	10071041
10071050	RUAG AG	REV. 1		DORNIER 228-212 DORNIER 228-202 DORNIER 228-201 DORNIER 228-200 DORNIER 228-101 DORNIER 228-100	Installation of equipment for Implementation of full Mode SELS, EHS,and ADS-B Out capability on Dornier Do-228 aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-ACNS Initial Issue.The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	-Installation in accordance with RUAG Master Document List (MDL) refMDL-8005085 Rev B, dated, 18.09.2019.-Operation in accordance with RUAG Flight Manual Supplement refFMS-612741 Rev B, dated, 16.09.2019.-Instructions for continued airworthiness (ICA) in accordance with RUAGdocument ref ICA-8005083o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/02/2021	Active	10071050
10071055	LANITZ-PRENA FOLIEN FACTORY GmbH	REV. 3		SEE EASA APPROVED MODEL LIST	Application of ORATEX covering and coating system installedwithoutstitching.Rev. 1 includes “on-condition” NDT evaluation for the lifetime of thesystem.Rev. 2 extends the applicability.Rev. 3 includes the ORATEX WET covering system as additional option	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 23.1, CS 23.3, CS23.21, CS 23.29, CS 23.45, CS 23.63, CS 23.143, CS 23.201, CS 23.203, CS23.207, CS 23.251...	- ORATEX System with unstitched integration on DR-series, Doc. No.ADxC-51-C0-002 Issue B dated 14th June 2019-Application of ORATEX covering & coating system, Doc. No.ADxC-51-C0-001, issue M, dated 5th March 2020- ORATEX Application Manual & Airplane Maintenance Manual Supplement,Doc. No. ADxC-51-0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2025	Active	10071055
10071060	JET AVIATION AG			747-300	Interior reconfiguration of the nose area on the main deck of Boeing747-300, S/N 23070, originally approved under FAA STC No. SA3572SW,subsequently modified with GACA STC No. RAE-052.The reconfiguration includes the installation of two newsingle seats (approved for TTOL), a desk with an extension ta...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): D-02 Isolated Compartments.-Deviation(s): D-05 Firm Handhold.The requirements for environmental protection and the associatedcertified noise and/u...	- Master Data List JBSL-M-01180MDL-01, Issue 02-Aircraft Flight Manual Supplement JBSL-M-01180AFM-01, Issue 04or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	Applicable for S/N 23070 only.Prior to installation of thischange/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	26/09/2019	Active	10071060
10071065	GROWING ENGINEERING PARTNERS GmbH	REV. 1		747-400	B747-400 – WIFI IFE Streaming InstallationInstallation and Activation of a WIFI based IFE streaming solutionconsisting of a Head End Server Unit, Wireless Access Points and a CrewControl Panel.Rev 1.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List S.OAEZ.001926-MDL, Rev. 02- Instructions for Continued Airworthiness Supplement S.OAEZ. 001926-ICA,Rev. 00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	SR Technics Minor Modification “IFE streaming provisioning modification”C.OAEZ.001924 and FAA STC No. ST03047CH / EASA STC No. 10040513“Certification of Compatibility with Cellular and/ or Wireless DataTechnologies” is a prerequisite for this installation.Prior to installation of this change/repair i...	21/04/2021	Active	10071065

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071066	AEROMETALS INC.	REV. 1	FAA SR02629LA	S-92A	Installation of Engine Inlet Barrier Filter SystemRevision 1 to correct the STC holder name.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 14CFR Part 29: 29.1316 (b) Amdt 27-5329.1317 (c) Amdt 27-49The requirements for environmental protection and the associate...	Master Drawing List 1092-MDL-1, Rev. “F”, dated September 17, 2018Instructions for Continued Airworthiness 1092-ICA-1, Rev. “B”, datedJune 15, 2018Rotorcraft Flight Manual Supplement 1092-RFMS-3, Rev. “NC”, datedSeptember, 2019or later revisions of the above listed document(s) approved/accepted onbe...	Flight in icing conditions with the IBF system installed isprohibited.Operation of the IBF bypass doors in icing conditions is prohibited.Flight in falling and/or blowing snow with the IBF system installed isprohibited.Prior to installation of this change/repair it must be determined thatthe interr...	01/10/2019	Active	10071066
10071068	GLOBAL AEROSPACE DESIGNCORPORATION	REV. 1	FAA STC ST04298CH	SEE FAA AML 767-300	Certification of Automatic Dependent Surveillance - Broadcast (ADS-B)OUT System utilizing upgraded Rockwell Collins TPR-901 Mode-STransponders paired with the aircraft’s existing GPS Source listed onAML number ST04298CH.Revision 1 adds Boeing 737-800 to the applicability list.	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements:- The following paragraph(s) at a later amendment:CS25 amdt 1: 25.1583(e)CS25 amdt 5: 25.1301, 25.1353(a)(b)CS25 amdt 6: 25.1309(a)(b)(c)(d)CS25 amdt 13: 25.1501(b)CS-ACNST...	Global Aerospace Design Corp. Master Drawing List, No. GR0232-MDL,Revision C, dated May 16, 2018, or later FAA approvedrevision.Airplane Flight Manual Supplement (AFMS) listed onAML number ST04298CH.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The existing Rockwell Collins TPR-901 Transponde...	21/01/2021	Active	10071068
10071070	airplus engineering GmbH	REV. 1		525A	Upgrade of Avionic Systems to WAAS.Upgrade of existing Garmin GPS400 / GNS530A to GPS 400W / GNS530(A)W.This modification enables the WAAS functionality.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval and is complemented by CS-ACNS Amendment 2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable t...	- Modification in accordance with Engineering Work Order,EW-2277-340000, Issue 2 and Description of Modification Issue 3- Installation in accordance with Engineering Work Order, EW-2277-340000Issue 2 and Master Drawing List, DL-2277-340000Issue 1.- Instructions for continued airworthiness in accord...	This STC is valid with a Garmin compatible WAAS GPS antennaand for anyof the variants specified in the Engineering Work Order section 2.1. TheADS-B OUT transponder certification (Garmin GTX 330D ES) is not part ofthis STC. This STC certifies installation and usage of listed units asWAAS GPS sourceG...	10/02/2021	Active	10071070
10071071	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		A330-343/-941 A330-321/-322/-323/-341/-342 A330-243/-243F/-301/-302/-303 A330-201/-202/-203/-223/-223F	Installation of 90-Day Underwater Locator BeaconRev 1: Transfer of STC from GVH Aerospace Ltd - United Kingdom, to GVHAerospace (Ireland) Limited	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 at amendment 23:25.1, 25.29, 25.301, 25.305, 25.307, 25.321, 25.337, 25.341, 25.601,25.607, 25.611, 25.863, 25.1301,...	- GVH Aerospace Instructions for Continued Airworthiness (ICA);GVH-10367-01-ICA-01 Issue 1- GVH Aerospace Master Data List No. GVH-10367-01-MDL-01 Issue 1or later revisions of theabove listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/01/2021	Active	10071071
10071097	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)			SEE EASA APPROVED MODEL LIST	EASA Validation of FAA Approved AML Supplemental Type Certificate (STC)No. ST02636LA that installs RTCA DO 260B Version2 ADS-B Out (ACSS ModeS transponder XS-950). This STC optionally installs the ACSS NXG-900 GPSas the ADS-B Out positionsource and a Fail indicator or ATC/TCAScontrol panel as the...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: See EASA Approved ModelListThe requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	- Master DataList (MDL), ACSS Doc Number: 8909949-001 Rev –, dated 07December 2018.- Aircraft Flight Manual Supplement (AFMS), ACSS Doc Number 8009949-900Rev -, dated 07 December 2018.- Instructions for Continued Airworthiness (System Maintenance Manual)for XS-950, ACSS Doc Number: 8009949-600 Rev –...	None	09/10/2019	Active	10071097

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071101	SEBALD LUFTFAHRTTECHNISCHER BETRIEB(LTB)			SEE EASA APPROVED MODEL LIST	Optional surface protectionOptional surface protection and/or increase of visibility. Optionallythe existing surface protection may be covered by additionalself-adhesive foil.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- TM-S02 Oberflächenschutz mittels Folien- TM-S02 Oberflächenschutz mittels Folien Allgemeines- TM-S02-AW01 Arbeitsanweisung- TM-S02 Wartungshandbuch- TM-S02 MZ-Listeor later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	The color of the foil must correspond to the specificationsof the TCDS.	30/09/2019	Active	10071101
10071112	AVIONIK STRAUBING ENTWICKLUNGS GmbH			31A	Installation of dual Universal Avionics UNS-1Ew.Optional installation of Universal Avionics UL-801 and UniversalAvionics CVR-120A.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): F-01 Data Link CVR/ FDR.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original prod...	- According to Avionik Straubing GmbH Master Documents ListNo.ASR-2018-051-MDL-01-00 Rev. 00- To be operated in accordance with Avionik Straubing AFM-S Document No.ASR-2018-051-FMS-05.1-00, ASR-2018-051-FMS-05.2-00,ASR-2018-051-FMS-05.3-00,- To be installed i.a.w. Avionik Straubing Instructions for...	According limitation section AFM-S.Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	01/10/2019	Active	10071112
10071113	P3 ENGINEERING GMBH			A321-271N/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-131/-132/-133-151N/-153N A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Wireless Cabin Distribution ActivationThis change consists in the activation of Wireless Cabin DistributionSystem and in the change of related AFM procedures	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25.601 at Amdt. 18CS 25.1301(a) at Amdt. 18CS 25.1309(a)(b)at Amdt. 18CS 25.1351(a) at Amdt. 18CS 25.1353(a)(b) at Amdt...	AFMS: P3-ABA01-FMS-0001, Issue A, dated 24 September 2019MDL: P3-ABA01-MDL-0001, Issue A, dated 27 September 2019ICA: P3-ABA01-ICA-0001, Issue A, dated 25 September 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/10/2019	Active	10071113
10071122	ROCKWELL COLLINS, Inc.	REV. 1	FAA SA01922WI	REFER TO AML IN TECH. DOC.	Pro Line Fusion FDSA and ICITModification of Rockwell Collins, Inc. Pro Line Fusion® Flight DisplaySystem Application (FDSA) and IMA Configuration Index Table (ICIT)software installation. This software version resolves the ACAS Fly-ToCue indication issue addressed by EASA AD 2019-0179.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 14 CFR Part 23 – 1301(a)(b)(c)(d) Amend. 20, 1309 (a)(1)(3)(4)(b)(e) Amend. 49, 1322 (a)(b)(c)(d) Amend. 43, 1529 Amend. 26...	Instructions for Continued Airworthiness, Rockwell Collins,Inc.,document RCA-0645, Revision (-), dated May 20, 2019Rockwell Collins Approved Model List (AML) Pro Line Fusion® SoftwareUpgrade STC No. SA01922WIor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in ac...	This STC is valid for those aircraft types and models approved by EASAas defined on EASA Product Lists, which are contained in the FAAApproved Model List RCA-0646, Revision (-), or later approved revisions.Prior to installation of this change/repair it must be determined thatthe interrelationship be...	30/10/2019	Active	10071122
10071123	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04038AT-D	GIV, GV	Installation of Iridium SATCOM System (FANS-1/A+ Over Iridium)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Gulfstream Aerospace Corporation Index List CE512038009,Revision(-), dated 5 July 2016, or later FAA approved revision.2. Airplane Flight Manual Supplement, CE41203M008, Rev (-), dated 6 July2016 or later FAA approved revision or CE41203MOO9. Rev (-), dated 6July 2016 or later FAA approved revis...	EASA STC 10056118 Installation of a Future Air Navigation System(FANS-1/A+) (AFN, CPDLC, ADS-C) functionality with datalink capabilityis required to be installed prior to or concurrent with this STC onGulfstream Model GV.EASA STC 10062883Installation of a Future Air Navigation System (FANS-1/A+) (A...	02/10/2019	Active	10071123

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071127	GDC ENGINEERING GmbH	REV. 1		747-400F	B747-400F Upper Deck Seats ReplacementRevision 1: B747-400FUpper Deck Alternative Seat In (minor change) tointroduce Weber 840638-401/-402in lieu of Sicma 5009211.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Certification Documents List CCN-B744B Issue 01Instructions for Continued Airworthiness B744B-ICA-00 issue 00Master Certification Documents List CCN-B744D Issue 01Instructions for Continued Airworthiness B744D-ICA-00 issue 00or later revisions of the above listed document(s) approved/accepted...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/03/2020	Active	10071127
10071137	MICRO AERODYNAMICS, INC.		FAA STC SA01299SE	PA-24-260 PA-24-250 PA-24	Installation of vortex generators on the wings and tail surface	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01299SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Micro AeroDynamics, Inc. Drawing Package Document MA2191, RevisionIR, dated 17 September 2003, or later FAA approvedrevision.2. Installation Manual MA2192, Revision IR, dated 27 October 2003, orlater FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/10/2019	Active	10071137
10071141	COMTECH GLOBAL AVIATION SERVICES S.			A320-214	Introduction of Overhead Video IFE SystemThis modification introduces the CETCA iWO-1000 Wireless Overhead VideoIn-Flight Entertainment (IFE) System to the subject aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Paragraph CS 25.603 at amendment 19Paragraphs: CS 25.301, 25.581, 25.609, 25.787, 25.831, 25.863, 25.869 atamendment 18Paragraphs: CS 25.611, 25.1301, 25.1411, 25.1701, 25...	-Master Data List CTG-MDL5004-320 revision B dated 07 Oct. 2019-AFM Supplement CTG-AFM5004-01 Rev. Aor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/10/2019	Active	10071141
10071146	SCANDINAVIAN AVIONICS DESIGN ApS			REFER TO AML 2117844-EO	Approval of Single/Dual Transponder System ADS-B Upgrade onPart 23aircraft, in accordance with Scandinavian Avionics Modification ref211784.	CS-23 at amendment 3.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Scandinavian Avionics Master DocumentList (MDL) ref 2117844 DOC, Rev 1, dated 04.10.2019, and EngineeringOrder ref 2117844-EO, Rev 1, dated 03.10.2019.Operation in accordance with Scandinavian Avionics Aircraft FlightManual Supplement (AFMS) ref 2117844-AM A, Rev 1, d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/10/2019	Active	10071146
10071149	AERO-DIENST GMBH	REV. 1		35, 35A, 36, 36A	Installation of GPS / SBAS Sensor System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 25.581, 25.869, 25.899and 25.1529 from CS-25 initial issue.The requirements for environmental protection and the associat...	- Aero-Dienst Master Document List 20320-LJ.DC-101, Rev. 00- Aero-Dienst Airplane Flight Manual Supplement 20320-LJ.DC-106, Rev. 00- Aero-Dienst Instructions for Continued Airworthiness 20320-LJ.DC-105,Rev. 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system....	This modification must be installed concurrently with the EASA AML STC10058529.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	07/10/2019	Active	10071149
10071150	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	777-200	8F/49J/40W/138M Passenger Seating Configuration on B777-200	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):CRI D-01 Installation of mini-suite type seating.CRI D-02 Installation of oblique seats.The requirements for environmental protection and the associ...	H4 Aerospace Instructions for Continued Airworthiness No. H4AICA017Issue 1H4 Aerospace Cabin Crew Data Supplement No. H4ACCDS001 Issue 1H4 Aerospace Modification Summary No. H4A1881 Issue 1H4 Aerospace Master Drawing List No. H4ADR1186 Issue 7or later revisions of the above listed document(s) approv...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/10/2019	Active	10071150

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071157	SIRIUM AEROTECH S.L.	REV. 4		ATR 72-212 A ATR 72-212/-212 A ATR 72-201/-202/-211/-212 ATR 72-201/-202/-211 ATR 42-200/-300/-320/-500 ATR 42-200/-300/-320	ADS-B Out upgrade for ATR 42/72Rev. 1: addition of an alternate GPS antenna installation optionRev. 2 added reference to minor change SA-2033M for MMEL-SRev.3: Correction to include missing references to approved supplementsin AFM.Rev. 4 adds model ATR 42-500.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	SA19-04S-MDL Revision 07SA19-04S-AFMS-42 Revision 01SA19-04S-AFMS-72 Revision 01SA19-04S-AMMS Revision 03or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/09/2023	Active	10071157
10071161	LUFTHANSA TECHNIK AG			A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	Activation of the Wireless IFEThis modification activates aWireless (WiFi) Infotainment (CabinDistribution) System on Airbus A330 aircraft. The full provision isinstalled in a separated modification. This Wireless IFE system is fedwith the data connection via a Satcom system, which is installed thr...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Supplemental Type Design Document:,,STDD44-18/05 M Issue 01 Rev 0 dated08.Oct.2019.,Flight Crew Data:,,,,,,A-00-19/58-FCD Issue 01 Rev 00 dated 18.Jun.2019,,Cabin Crew Data:,,,,,,A-00-19/58-CCD Issue 00 Rev 00 dated 18.Jun.2019 ,,Instruction for Continued Airworthiness: A-00-19/32-ICA Issue 01 Rev 00...	The following design changes (pre-modifications) need to beapproved andinstalled on the aircraft prior to the installation of the subjectdesign change: Structural and electrical provisions for the Wireless (WiFi) Infotainment System Cabin Distribution according to SupplementalType Definition Documen...	09/10/2019	Active	10071161
10071176	LEARJET Inc.		FAA ST00360BO	CL-600-2B16 (604 VARIANT)	Installation of a cockpit speaker mute switch.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Data List BAS63017018, Revision C, dated 17 November 2015 orlater FAA approved revision.2. The Airplane Flight Manual Supplement, Bombardier documentBAS63047018 RevisionNC, or later FAA approved revision.3. Bombardier documents BAS63017018-ICA-1 Revision NC, dated 17 July2015 or BAS630170...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/10/2019	Active	10071176
10071191	SABENA TECHNICS BGC			A319-132	Re-Installation of Linefit Cargo Loading SystemThis STC re-installs the linefit Cargo Loading System configuration (replacing the interim, bulk cargo, configuration).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List, ref: 7162-01-A-MDL-R00-Instructions for Continued Airworthiness (Supplement), ref:7162-01-A-ICA-R00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	In accordance with 21A.115(d)2 this supplemental type-certificate isissued on the basis of an arrangement between the supplementaltype-certificate holder the type-certificate holder such that thedischarge of obligations for continued airworthiness are held betweenboth parties (AeroConseil responsibi...	17/10/2019	Active	10071191
10071193	STANDARD AERO		FAA STC ST02452CH-D	HAWKER 850XP HAWKER 800XP	Installation of a Collins IFIS-5000 Integrated Flight Information System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02452CH-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Landmark Aviation Master Data List 1013021, Revision "A", dated 11July 20017.2. Flight Manual Supplement, Landmark Aviation document 1013447, Rev.(A), dated 13 July 2007, or later FAA approved revision for Option 1.3. Flight Manual Supplement, Landmark Aviation document number 1013521,Rev. (A), d...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	14/10/2019	Active	10071193

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071226	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA ST04310AT-D	GVII-G500 G500	GVII-G500 Airplane Interior Installation:Cabinetry, Seating, Associated Electrical and Mechanical Systems andExterior Markings	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	GC87099C999 Revision (-) Summary Compliance Report – Brimstone BagInstallation, dated 12 December, 2024GDL300008507 Revision (-) G500 BRIMSTONE BAG, dated 21 November, 2024GDL100000007 Revision (EP) Index List, dated 12 December, 2024GC71468M001 Revision (H) Airplane Flight Manual Supplement forGulf...	The “EASA Validated Configuration Lists ST04310AT-D” GCD000009923 liststhe EASA Aircraft Configurations and the compatible aircraft exportoptions.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed c...	21/01/2025	Active	10071226
10071227	S4A SOLUTIONS FOR AVIATION, S.L			BN2A-20	Antennas installation in BN2 aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS23 Initial Issueparagraphs: 23.1, 23.3, 23.21, 23.23, 23.25, 23.45, 23.49, 23.51, 23.53,23.63, 23.65, 23.66, 23.67, 23.7...	Modification Description, doc. No. BN006-DES01, Issue 1 dated 4thOctober 2018Flight Manual Supplement, doc. No. BN006-HDK01 Issue 2 dated 7th October2019or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/10/2019	Active	10071227
10071229	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04312AT-D	GVII-G500	GVII-G500 Ka Band JetWave System Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- FAA Statement of Compliance G_ODA-19-0091, dated 11 October 2019- FAA Certification Statement ref. 7A0-19-11808, dated 11 October 2019- FAA Approval ST04312AT-D, Date of Issuance 21 September 2018- EASA Validation Summary Compliance Report ref. GC72204C057 Revision A,dated 22 August 2019- Airplane...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/10/2019	Active	10071229
10071261	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH	REV. 1		B200GT, B200T, B300, B300C B200, B200C, B200CGT, B200CT 300LW, A200, A200C, A200CT 200, 200C, 200CT, 200T, 300 1900, 1900C, 1900D	Replacement of existing UNS-1D/K/L with UNS-1LwThis STC includes the replacement of the NCU, of the ConfigurationModuleand CDU of the Universal FMS, as well as the replacement oftheGPS antennas by SBAS GPS antennas.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Upgrade in accordance with MDL 2018-37-16 Revision C and morespecifically with Engineering Order 2018-37 Revision BInstallation in accordance with Installation Procedure 2018-37-1Revision BOperation in accordance with Airplane Flight Manual Supplement 2018-37-8Revision BMaintenance and Instructionsw...	See conditions in Engineering Order 2018-37.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	24/03/2020	Active	10071261
10071262	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			B300C B300 B200T B200CT B200CGT B200C B200 A200CT A200C A200 300LW 300 200T 200CT 200C 200	Upgrade of Rockwell Collins TDR-94D Transponder on Textron AviationBeech Model B200 & B300 aircraft. Addition of ADS-B out capability incompliance to CS-ACNS.D.ADSB Initial Issue and AMC 20-24.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval and is complemented by CertificationSpecifications and Acceptable Means of Compliance for AirborneCommunications Navigation and Surveillance(CS-ACNS) at Initial Issue.The requirements for environmen...	Upgrade in accordance with MDL 2018-29-16 Revision A and morespecifically with Engineering Order 2018-29 Revision AInstallation in accordance with Installation Procedure 2018-29-1Revision AOperation in accordance with Airplane Flight Manual Supplement AFMS2018-29-8 Revision AMaintenance and Instruct...	For conditions, refer to section 1 in Engineering Order 2018-29Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the...	16/10/2019	Active	10071262

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071270	AIRFILM CAMERA SYSTEMS, INC		FAA SR02695LA	130 B4/ 130 T2	Installation of Airfilm Utility Mount	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Airfilm Camera Systems documentation listed on AML No. SR02695LA,dated 11 April 2019, or later FAA approver revisions.2. Instructions for Continued Airworthiness, which are found withinAirfilm Camera Systems Report No. AFM-130-208, Rev.A, dated 19 February2019, or later FAA accepted revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/10/2019	Active	10071270
10071280	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	777-200, 777-300ER	RE-PITCH OF OUTBOARD ECONOMY CLASS SEATS	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration Scheme No.3199-MCS-01 Issue 1or later revisions of the above listeddocument (s) approved/ acceptedunder the EASA system.	Operational Limitation - Skycouch can only be used as a sleeping or anaccommodation area during in-flight conditions, as detailed in SWSCertification Services Ltd Design Report 3199-DR-01.Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/...	18/10/2019	Active	10071280
10071324	GVH AEROSPACE (IRELAND) LIMITED	REV. 2		AW139 AB139, AW139 AB139	Installation of AeroStretcher Mk IV Modular EMS System in accordancewith Master Data List GVH-8386-01-MDL-01Initial:Installation of AeroStretcher Mk IV Modular EMS System limited to S/N31031, 31458, 31103, 31156, 31146Rev. 1: Removal of the S/N related Limitation for the original STC andextend appli...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Flight Manual Supplement GVH-8386-01-FMS-01 Issue 5Master Data List GVH-8386-01-MDL-01 Issue 4Instruction for ContinuedAirworthiness GVH-8386-01-ICA-01 Issue 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/12/2020	Active	10071324
10071326	JET AVIATION AG	REV. 2		SEE EASA APPROVED MODEL LIST	WLAN ActivationDemonstration of aircraft immunity to IEEE 802.11a/b/g/n/ actransmissions from PEDs based on EASA CM-ES-003.Activation of existingcabin Wireless LAN System provisions for all Airbus A320-familyaircraft.Revision 1:WLAN ActivationDemonstration of aircraft immunity to IEEE 802.11a/b/g/n/a...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 Amdt 23: 789, 831, 869<(>,<)> 1301, 1309, 1351, 1353, 1357, 1360,1431, 1501, 1529, 1581, 1585, 1707.The requirement...	Revision 2:Cert Plan: JBSL-M-01351CER-03, Issue AAML: JBSL-M-01351AML-01, Issue 2MDL: JBSL-M-01351MDL-01, Issue 4AFMS A330-200/-300: JBSL-M-01351AFM-02, Issue 2AFMS A340-200/-300/-500/-600: JBSL-M-01351AFM-03, Issue 2AFMS B777-200/-200LR/-300/-300ER: JBSL-M-01351AFM-05, Issue 2AFMS B787-8/-9/-10: JB...	As per AFM JBSL-M-01351AFM:Only Wireless-LAN transceivers conform to IEEE 802.11a/b/g/n/ac approvedWLAN System and all PEDs Wireless LAN transmissions must be OFF during- Low Visibility Approach-Abnormal or Emergency conditions- During usage of life sustaining devices (pacemakers, auto insulininjec...	31/08/2022	Active	10071326
10071381	BLACKHAWK AEROSPACE TECHNOLOGIES IN		FAA STC ST01929WI	500/550/560/S550	Installation of Garmin G700 TXi EFIS System and GWX 75 Weather Radar	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01929WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. FAA approved Airplane Flight Manual Supplement, DocumentNo.30142601, Revision IR or No. 30142601-01, Revision IR, both dated 16August 2019; and2. FAA approved Master Document List, No. 30142590, Revision IR, dated21 August 2019, or later FAA approved revision to 1. or 2.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	25/10/2019	Active	10071381

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071407	URBE AERO GmbH			DA 42	Garmin GFC700 Autopilot endorsementEASA STC 10048730 approves the Installation of Technify Centurion 2.0SDiesel Engineson the Diamond DA 42. Compared to the OEM approvedTechnify Engine Versions, the 2.0S provides more engine power and in thecourse of STC 10048730, just the KAP140 Autopilot System h...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The Change is defined with issue 01 of Engineering Order documentDOE/F07 for project No.: 211.The aircraft shall be operated in accordance with initial issue ofAirplane Flight Manual Supplement document AFM-211-01.Maintenance shall be accomplished in accordance with initial issue ofAirplane Maintena...	The following changes must be incorporated as prerequisitesto theinstallation of this STC:- EASA STC 10048730and- OÄM-42-102 or equivalent TC Holder change to install the GFC-700Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair an...	25/10/2019	Active	10071407
10071421	SCANDINAVIAN AVIONICS DESIGN ApS			650	Installation of GPS antenna and WAAS GPS receiver	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 Amendment 2 - CS25.1, CS 25.29, CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS 25.337,CS 25.341, CS 25.365, CS 25.56...	Continued Airworthiness for Installation of GPS/WAAS Receiver Doc Ref:2120697-CA, Issue 1 dated 20 September 2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/10/2019	Active	10071421
10071441	ACC AIRCRAFT CABIN COMPONENTS GmbH			ERJ 190-100 LR	Change to EMBRAER 190-100LRCabin Refurbishment, Replacementof Seat Cover of Aft Exit Row ZODIACSeats	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- ACC Master Documents List ref. MDL1041 Issue A dated 19 September 2019- ACC Instructions for Continued Airworthiness ref. ICA1041-01 Issue Bdated 16 September 2019- ACC Maintenance Manual Supplement ref. MAS1041-01 Issue A dated 8August 2019or later revisions of the above listed document(s) approv...	As defined in ACC Maintenance Manual Supplement ref. MAS1041-01 Issue A,this Major Change Approval (MCA) is limited to an operation time of 1 (one) year. After that period the MCA shall be removed and the aircraftshall be returned into its previously approved configuration.	29/10/2019	Active	10071441
10071442	ANCRA INTERNATIONAL LLC		FAA STC ST02683LA	A321-272N/-272NX A321-271N/-271NX A321-253N/-253NX A321-252N/-252NX A321-251N/-251NX A321-231/-232 A321-211/-212/-213 A321-131 A321-111/-112 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-231/-232 A320-216 A320-211/-212/-214	Installation of windows plugs	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02683LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Ancra International LLC Controlled Data List DL87050, Revision C,dated 29 May 2018 or later FAA approved revision. 2.Instructions for Continued Airworthiness, report number 10630,Revision C, or other FAA accepted document.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	22/11/2019	Active	10071442
10071445	JET AVIATION AG	REV. 3		A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-131/-132/-133/-151N/-153N A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	KA Band Satcom System InstallationThis project is installing a Honeywell Jet Wave MCS-8200 KA-Band Satcomsystem on the rear fuselage.Rev. 1: inclusion of new installation locationfor the A319 and A320series and inclusion of A318 installationRev. 2: Typo and editorial changeRev. 3: Correction of app...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-4301-005 Issue2 “Vibration andbuffeting compliance criteria for large external antenna installation”.The requirements for environmenta...	CERTIFICATION PLAN - JBSL-M-01326CER-02 Issue 3CERTIFICATION COMPLIANCE SHEET - JBSL-M-01326CCS-01 Issue 3DECLARATION OF COMPLIANCE - JBSL-M-01326DOC-02 Issue 1INSTRUCTIONS FOR CONTINUED AIRWORTHINESS - JBSL-M-01326ICA-10 Issue 3INSTRUCTIONS FOR CONTINUED AIRWORTHINESS - JBSL-M-01326ICA-30 Issue 1I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/03/2021	Active	10071445

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071447	ALOFT AEROARCHITECTS		FAA ST01738NY	737-900ER	PATS installation of VIP Aircraft Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- CRI A-101 Issue 1, issued for project 0010022543The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the originalu...	- PATS Aircraft, LLC Master Drawing List 6950-0001-MDL, revision F dated12 February 2015.- Airworthiness Limitations Section (approval date 29 June 2013) locatedin section 4 of the Maintenance Planning Document Supplement (MPDS)Report No. TM-6950-MPDS.- PATS Aircraft, LLC Airplane Flight Manual Supp...	- As per PATS Aircraft, LLC Airplane Flight Manual Supplement No. 137- As per AIRWORTHINESS LIMITATIONS SECTION (section 4 of the MPDS ReportNo. TM-6950-MPDS)The installation of the following STC is required or this modification:- EASA STC10045954 (FAA ST02466LA) Cabin Interior Noise ReductionSyste...	30/10/2019	Active	10071447
10071509	AIRBUS TRANSPORT INTERNATIONAL SNC	REV. 1		A300F4-608ST	A300-600 ST Beluga - EFB arm mountThe change consists of the installation of hardware and power supply onsliding windows for the installation of Panasonic CF-20 ElectronicFlight Bag (tablet). This change installs the adaptation supports, theIPS, the ASG sliding cf Mount and associated cradle on CAPT...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Change approval sheet ref. ST46MOD009_CAS at issue 1 dated 30 October2019AFM supplement ref. ST46MOD009_ADD Issue 1 dated 13 August 2019OSD/MMEL proposal ref. ST46MEL009 Issue 2 dated 21 August 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/11/2019	Active	10071509
10071512	EMBRAER ENGINEERING & TECHNOLOGYCENTER USA, INC.		FAA STC SA03007CE	EMB-500	Installation of Rockwell Collins Automatic Direction FinderThis STC was originally issued as a validation of Brazilian CTS (STC)no. 2009S05-07 (31 May 2009) and transferred to a United States basedDesign Approval Holder (DAH) on 17 July 2019.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List Number TR0083, Revision N, dated 21 September 2017.This STC was originally issued as a validation of Brazilian CST (STC)No. 2009S05-07 (21 May 2009), and transferred to a United States basedDesign Approval holder (DAH)on 17 July 2019.Operation must be performed in accordance wi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/or repair will introduce noadverse effect upon the airworthiness of the product.	25/11/2019	Active	10071512
10071527	SABENA TECHNICS BGC	REV. 3		ATR 72-212 A ATR 72-212 ATR 72-211, ATR 72-212 ATR 72-211 ATR 72-202 ATR 72-201, ATR 72-202 ATR 72-201 ATR 72-102 ATR 72-101, ATR 72-102 ATR 72-101 ATR 42-500	ADSB OUT System Installation on ATR42/72:Replacement of theRCI transponders TDR94D (-007, 008 or 108) by TDR94D(-502) in order to obtain the capability ADSB-Out.Rev. 0: Certification of Group II “Dual GPS SBAS “CMA 5024” Source”.Rev. 1: Certification of configuration 1 “XPDR without BA-540 AAU A429...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4 paragraphs: 1, 29, 301, 303, 305, 307, 337, 341,561, 581, 601, 603, 605, 607, 609, 611,...	- Master Data List, ref: 0724-02-A-MDL-R04- Instructions for Continued Airworthiness (Supplement), ref:0724-02-A-ICA-R03- AFM (Supplement): 0724-02-A-AFMS-R03- Master Minimum Equipment List (Supplement): 0724-02-A-MMELS-R00or later revisions of the above listed document(s) approved/ acceptedunder the...	Applicability does not include ATR 42-500 '600 version', ATR 72-212A'600 version'.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the ai...	25/04/2022	Active	10071527
10071538	S4A SOLUTIONS FOR AVIATION, S.L		FAA US A10CE	60	GTX 3000 Dual Transponder Installation including ADS-B out Out inLearjet 60	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	According to S4A Master Drawing List No. L6012-RPT-02 Ed3Tobe operated in accordance with S4A AFM-S Document No. L6012-HDK01 Ed3To be installed i.a.w. S4A SB L6012-SB001 Ed3To bemaintained i.a.w. S4A ICA Document L6012-HDK02 Ed2or later revisions of the above listed document(s) approved/ acceptedun...	None	05/11/2019	Active	10071538

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071539	DC AEROSPACE SOLUTIONS, LLC		FAA STC ST02582LA	A321-272NX A321-253NX/-271N/-271NX/-272N A321-251NX/-252N/-252NX/-253N A321-213/-231/-232/-251N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-216 A319-131/-132/-133/-151N A319-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of Flight Deck Thermal Acoustic Insulation Blanket	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02582LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Frontera Solutions, Inc. Master Drawing List, Document NumberMDL-A3201, Revision B, dated 18 February 2016, or later FAA approvedrevision.- Frontera Solutions, Inc. "Instructions for Continued Airworthiness,Thermal/ Acoustic Insulation Installation", Document Number ICA-A3201,Revision A, dated 24 N...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	07/11/2019	Active	10071539
10071554	B/E AEROSPACE, Inc.		FAA ST04459AT	757-300 757-200PF 757-200	Installation of the Rockwell Collins Automatic Dependent Surveillance - Broadcast (ADS-B) Out System on the Boeing 757-200/-300 Series Aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except for the following requirements at alater amendment (CS 25 at amendment 4):25.23(a), 25.301(a)(b) , 25.303, 25.305(a) , 25.307(a) , 25.561(c) ,25.601, 25.603(b)(c) , 25.611, 25.853(a) , 25.863(a) ,...	1. Master Drawing List (MDL) 2-194190-001, Rev. B, dated 19August 2019,or later FAA approved revision.2. Airplane Flight Manual Supplement for the Rockwell Collins AutomaticDependent Surveillance - Broadcast (ADS-B) Out System, 2-194190-805, RevIR, dated 17 September 2019 or later FAA approved revi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2019	Active	10071554
10071558	SABENA TECHNICS BGC			A320-233 A320-232 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211	GEE ARINC 791 Ku-Band Satellite Communication Antenna (PartNumberRWA11-0008-00) Provisions Installation on Airbus A320 Aircraft modelsalready equipped with the ARINC 791 provisions for the installation of adorsal large Satellite Communication antenna between frames FR58 andFR63	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-0301-001 “Vibration/buffetingcompliance criteria for large external antenna installation”the following paragraph(s) at a later amendmen...	-Master Data List, ref 0874-02-A-MDL-R00-Instructions for Continued Airworthiness, ref : 0874-02-A-ICA-R00-Airplane Flight Manual Supplement, ref : 0874-02-A-AFMS-R00	This modification is compatible with Extended Service Goal,as describedin section 3.2 of Instructions for Continued Airworthiness (Supplement),ref 0874-02-A-ICA-R00.Models not already fitted with ARINC 791 provisions for the installationof a dorsal large Satellite Communication Antenna between fram...	07/11/2019	Active	10071558
10071569	ALPHA AVIATION, INC.			SEE FAA AML	Installation of a Three Point Restraint System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02015CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Alpha Aviation, Inc. Installation and Maintenance Manual aslisted onAML SA02015, reissued 20 December 2016, or later FAA approved revisions.The Three Point Torso Restraint Systeminstallation is to be inspectedand maintained in accordancewith Alpha Aviation, Inc. Installation andMaintenance Manual...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	07/11/2019	Active	10071569
10071580	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			737-800	Alternative Maximum Takeoff WeightReduction of the certified maximum take-off weight of the aircraft to71990kg in accordance with EASA record A121701.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Airplane Flight Manual Supplement MODE00267_AFMS1 rev 3or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Applicable to Boeing 737-800 aeroplanes, equipped with winglets andCFM56-7B26E engines, AFM option code <986WS1>Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	07/11/2019	Active	10071580

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071581	ALPHA AVIATION, INC.		FAA SA01880CH	SEE FAA AML SA01880CH	Installation of a Three Point Torso Restraint System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01880CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Alpha Aviation Inc. Installation and Maintenance Manual as listed onAML SA01880CH, reissued 20 December 2016, or later FAA Approvedrevisions.2. Approved Model List (AML) No. SA01880CH, reissued 20 December 2016,or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	07/11/2019	Active	10071581
10071587	MORSON PROJECTS LIMITED		CAA UK RESPONSIBILITY	525, 525A, 525B, 525C	Introduction of ADS-B Out functionality.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:- CS-23 Initial Issue: 23.301; 303; 305; 307; 333; 337; 471; 561; 601;603; 605; 607; 609; 613; 771; 1301; 1309; 1322; 1351;...	Installation, Operation and Maintenance according to MorsonProjectsLimited Change Report MP0039A<(>,<)>Issue 1, dated 23 October 2019<(>,<)>or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Limited to the following serial numbers of aircraft that are fitted withRockwell Collins Proline 21 Avionics with dual Rockwell Collins TDR-94Dtransponders compliant with RTCA DO-260B and Rockwell Collins GPS-4000SGNSS position sensor qualified to EASA ETSO-C145 (and associated SBASqualified GNSS an...	08/11/2019	Active	10071587
10071603	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	T182, T182T, TR182, R182 F182P, F182Q, FR182 182R, 182S, 182T 182L, 182M, 182N, 182P, 182Q 182E, 182F, 182G, 182H, 182K 182, 182A, 182B, 182C, 182D	Xcam pod installation on port or starboard wing strut	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS23 Amendment 4.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain a...	Aircraft Flight Manual Supplement JC/FMS/5329 (issue 1.0)<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	08/11/2019	Active	10071603
10071611	LIFEPORT, LLC		FAA ST04367CH	680A (LATITUDE)	Installation of a Medical Interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with LifePort Master Drawing List (MDL) EGR-887-000-001, Revision (B), dated April 18, 2019, or LifePort MasterDrawing List (MDL) MDL-887-00, Revision (D), dated April 11, 2019.Operate in accordance with FAA Approved Airplane Flight ManualSupplement document number EGR-887-...	This STC requires prior embodiment by Textron of the modificationslisted in the Medical Interior Collector document number 7490007, Rev(-).If the holder agrees to permit another person to use this certificate toalter the product, the holder must give the other person writtenevidence of that permissi...	08/11/2019	Active	10071611
10071622	AIRBUS S.A.S.			A330-743L	Airbus Interiors Services (AIS) MOD CJ1970 Courier Area Installation onAirbus A330-743L Beluga XL.This Courier Are MOD1970 provides a module integrated in the A330-743LBeluga XL aircraft, between the cockpit and the aft pressurizedbulkhead. This module provides transportation provisions up to fouroc...	The Certification Basis (CB) for the original product as amended by thefollowing additional or alternative airworthiness requirements:- Special Condition (s): D-02-700L Courier Area: Allowed Occupants;D-03-700L Emergency Evacuation; D-50-700L-AIS Courier Area airworthinessrequirements for low occupan...	Airbus Interiors Services':- Modification Approval Sheet ref. MAS CJ1970 issue 01- Certification Summary Report ref. ACJC-AJA-15050 issue 09- MRD (Maintenance Requirements Supplement) Supplement ref. MRD-S NOV01/19- MMEL (Master Minimum Equipment List) Supplement ref. MMEL-S issue OCT01/19or later r...	This STC MOD CJ1970 is associated to the initial configurationdefinition of the A330-743L Beluga XL aircraft, as defined in AirbusA330-743L Type Design Definition (TDD) 00G000A0743/C00 at issue 4 andtherefore needs to be installed on aircraft concurrently with thisaircraft configuration (or later EA...	11/11/2019	Active	10071622
10071632	MT-PROPELLER ENTWICKLUNG GmbH	REV. 2		DA 42-NG, DA 42 M-NG DA 42-NG DA 42M-NG DA 42 M DA 42, DA 42 M DA 42	Installation of MTV-6-()-C-F/CF190-69() on DA42 series.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase...	According to MT-Propeller Master Documentation List No. E-3468, Rev 6To be operated in accordance with MT-Propeller AFM-S Document No.E-3470, Rev 4 for DA 42, DA 42(M)To be operated in accordance with MT-Propeller AFM-S Document No.E-3473,Rev 3 for DA 42-NG, DA 42(M)-NGTo be installed i.a.w. Instal...	According limitation section of AFM-S.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/04/2023	Active	10071632

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071634	AERODATA AG	REV. 1		B300	Installation of an Aerodata automatic flight inspection system(AD-AFIS-1013DF).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: Elected to comply withCS-23 Amdt. 4 except for 23.561 and 23.785 at FAR-23 Amdt. 34.The requirements for environmental pro...	Installation in accordance with Master Document List, documentMDL-A/C-925 Rev. 0 dated 01 October 2019Operation in accordance with Aircraft Flight Manual Supplement, documentAFM-170 Rev. 0 dated 16.9.2019Instructions for Continued Airworthiness in accordance with AircraftMaintenance Manual Supplemen...	For model B300 with installed Pro Line Fusion® avionics andSlickInterior only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	14/11/2019	Active	10071634
10071643	ROCKWELL COLLINS, Inc.		FAA ST00526WI-D	SEE EASA AML	Modification of Rockwell Collins VHF COMM receiver installation.Rev: the original approved configurations (by Italian ENAC and IcelandicCAA) were complemented by additions of the Boeing models 737-300F,737-600, 737-800, 737-900, 747-400, 747-400D, 747-400F, 777-200,777-300, 777-200LR, 777-300ER, DC-...	Requirements at a later amendment:JAR 25 amdt 15:25.60125.609(a)25.613(a)(b) 25.625(a)25.1301(a)(b)(c)(d) 25.1353(a)25.1357(a)(c)25.1519	Rockwell Collins Drawing Index 992-4285-001, Rev. T, dated 27 January2012, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/02/2020	Active	10071643
10071645	SPAES GmbH & Co. KG			SA 365 N1 SA 365 N AS 365 N3 AS 365 N2	Installation of automatic deployable ELT	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Document List MDL-365-245-25-01, Issue 00- Instructions for Continued Airworthiness ICA-365-245-25-01, Issue 00- Flight Manual Supplement FMS-SPAES-0245, Issue 00or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/11/2019	Active	10071645
10071650 (FM02-01 (GRANDFATHERED))	JLC AERONAUTICAL LLC		FAA STC SA4622SW	2. DHC-6 SERIES 400 1. DHC-6 SERIES 300 1. DHC-6 SERIES 200 1. DHC-6 SERIES 100	Installation of JLC Aeronautical Vapor Cycle Air ConditionerThis is a revision to the French STC FM02-01 dated 15 February 2001.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List MA-001, Rev 4 dated 6 December 2012 or later FAAapproved revision.2. FAA approved Airplane Flight Manual Supplement (AFMS), dated 9 March2013 or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/11/2019	Active	10071650
10071654	EMBRAER ENGINEERING & TECHNOLOGYCE NTER USA, INC.		FAA STC SA04453AT	EMB-505	Installation of a Tire Pressure Sensing Kit.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04453AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List (MDL) 17008-001, Rev. --, dated 21 November 2018, orlater FAA approved revision.2. Instructions forContinued Airworthiness (ICA) document ICA17008-030, Rev. --, dated 21 November 2018 or later FAA acceptedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/11/2019	Active	10071654
10071663	CAVOK			B300	Installation of forward pressure bulkhead cable feedthrough.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Installation Instructions documentnumber 350-084-SB-004, Issue B, date 25/09/2019.Maintenance in accordance with “Supplement to Super King Air B300Maintenance Manual” document number 350-084-HBK-008, Issue C, date08/11/2019.or later revisions of the above listed docum...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/11/2019	Active	10071663

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071669	ROCKY MOUNTAIN AIRCRAFT		TCCA SA16-45 ISSUE 1	B. DHC-6 SERIES 400 A. DHC-6 SERIES 320 A. DHC-6 SERIES 310 A. DHC-6 SERIES 300 A. DHC-6 SERIES 210 A. DHC-6 SERIES 200 A. DHC-6 SERIES 110 A. DHC-6 SERIES 100	Installation of Replacement Fuel Manifold Tubes	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation in accordance with Transport Canada Civil Aviation (TCCA)approved Rocky Mountain Aircraft (RMA) Modification Instruction E108610,Revision B, dated March 11 2016.or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Impleme...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/11/2019	Active	10071669
10071677	BOEING IRELAND LIMITED			737-800	Zero Passenger LOPA for B737This Change removes all existing passenger seats from the passengercabin of the aircraft. Operation of the aircraft is restricted toflights with flightand supernumerary crew only (no passengers areallowed).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Change / Repair Approval BIL-00107-APP Revision 00, dated 14th Nov 2019Aircraft Flight Manual Supplement BIL-00107-AFM01 Revision 01Manual Supplement BIL-00107-MS01 Revision 00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/11/2019	Active	10071677
10071683	AMAC AEROSPACE SWITZERLAND AG			737-700	Activation of Wireless Local Area Network (WLAN) for the purpose ofpassenger connectivity.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): F-108 Security Protection ofAircraft Systems andNetworksthe following paragraph(s) at alater amendment: The followingparagraphs of CS-25 as of Amen...	The change is defined with Revision A of the Master Data List documentMDL-B7371-1-4430.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual document AFMS-B7371-1-4430.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/11/2019	Active	10071683
10071684	AMAC AEROSPACE SWITZERLAND AG			737-700	Iridium Satcom System InstallationInstallation of an Iridium antenna mounted on upper part of the fuselage(between STA 460 and STA 480) and a Data Link Unit (DLU).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): F-108, Security Protection of Aircraft Systems andNetworksThe requirements for environmental protection and the associatedcertified noise and/ or emi...	The change is defined with Revision A of Master Data List documentMDL-B7371-1-2300.The aircraft shall be maintained in accordance with Revision A ofInstructions for Continued Airworthiness document ICA-B7371-1-2300.or later revisions of the above listed document(s) approved/ acceptedunder the EASA sy...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/11/2019	Active	10071684
10071712	CANARD AEROSPACE CORPORATION	REV. 1	FAA STC ST04406CH	737-600/-700/-800/-900/-900ER	Installation of ADS-B Qualified Transponders and new IntegratedMulti-Mod Receivers (IMMRs) on Boeing 737 aircraftRev. 1adds Collins transponders.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt. 4: 25.29(b); 25.301(a),(b); 25.303; 25.305(a),(b);25.307(a); 25.321 (a),(d); 25.333(a); 25.561(c); 25.571(a),(b); 25.601;25.603; 25.605; 25.207; 25.609; 25.611;...	- Canard Aerospace Corporation (CAC) Document Drawing 40218, Revision N,dated 8 March 2021, or later FAA approved revision.- Airplane Flight Manual Supplement, Canard Aerospace Document Number34-3626-06, Revision N/C, FAA approved 8 July 2019, or later FAAapproved revision.- Instructions for Continu...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2021	Active	10071712

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071713	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST00680LA-D	GIV, S/N 1353 ONLY	Installation of passenger cabin interior	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00680LA-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	Gulfstream Aerospace Corporation Index List IL 11011555, Revision E,dated 17 July 1999, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	21/11/2019	Active	10071713
10071716	LUFTHANSA TECHNIK AG			A340-541/-542/-642/-643 A340-311/-312/-313 A340-211/-212/-213 A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-223F/-243/-243 F A330-201/-202/-203	ADS-B OUT on A330 and A340The change consists in the activation of the Automatic DependentSurveillance – Broadcast Out (ADS-B Out) in accordance with RTCADO-260B. Simultaneously the changed Elementary- and EnhancedSurveillance requirementswill be implemented.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25.029(a);25.029 (b);25.301(b); 25.303; 25.561(c); 25.601; 25.899(a);25899(b); 25.1301(a)(01); 25.1301(a)(02); 25.1301(a)...	-Master Data List STDD34-18/09M Issue.Revision 1.0-AircraftFlight Manual A-00-19/04-AFM Issue.Revision 00/00-Aircraft Flight Manual A-00-19/01-AFM Issue.Revision 00/00-Instruction for continued Airworthiness A-00-19/01-ICA Issue.Revison01/00or later revisions of the above listed document(s) approve...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/11/2019	Active	10071716
10071721	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04387AT	A320-271N, -272N, -273N A320-251N, -252N, -253N A320-231, -232, -233 A320-214, -215, -216 A320-111, -211, -212	Class Divider Installation in an Airbus A320 Series aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04387AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. HAECO Cabin Solutions, LLC Master Data List 19T011L001, Revision IR,dated 8 November 2019, or later FAA approved revisions.2. HAECO Cabin Solutions Instructions for Continued Airworthiness19T011R009, Revision 00, dated 17 October 2019, or later FAA acceptedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2019	Active	10071721
10071724	LEARJET Inc.		FAA STC ST02027LA-D	31A	Installation of the Universal Avionics Systems Corporation Dual UNS-1EwFlight Management System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02027LA-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	- Learjet Master Data List BAS31010042, Revision "C", dated24 June2011, or later FAA-Approved revision.The following documents are required for MDL BAS31010042, -1Configuration of this STC:- Airplane Flight Manual Supplement BAS31040208, Revision NC,FAA-Approved on 24 June 2011, or later FAA-Approv...	The installation of the Universal Avionics Systems Corporation DualUNS-1Ew Flight Management System is applicable only to Learjet 31A modelaircraft that are configured with a Bendix/King EFS 50 Electronic FlightInstrument System.Prior to installation of this change/ repair it must be determined thatt...	20/11/2019	Active	10071724
10071725	WEST STAR AVIATION, LLCd/ b/a WEST STAR AVIATION			MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Installation of Universal CVR-120AInstallation of a Universal CVR-120A Cockpit Voice Recorder.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-9122-003 Flight Recorders and Data LinkRecording;CRI F9128-003 Non-Rechargeable Lithium battery Installation.EASA Certification Basis (Contin...	- MDL 18336L-1736 Revision B- AFM 18336M-1740 Revision I/R-ICA 18336P-1760 Revision I/Ror later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/11/2019	Active	10071725
10071727	DELTA ENGINEERING CORPORATION		FAA STC ST02645NY	777-300ER 777-300	Installation of a Panasonic In-Flight Entertainment System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS.25 at Amdt. 4:§25.831, §25.853, §25.869, §25.869, §25.981,§25.981, §25.1353, §25.1431The requirements for environmenta...	Delta Engineering Master Data List 0143-06432-2177, Revision E, dated 27August 2019.The Instructions for Continued Airworthiness as listed on the MasterData List are required withthis installation.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Configuration TL10552 requires installation of E...	03/03/2019	Active	10071727

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071729	LORD CORPORATION			212 205B 205A-1 205A 204B	Part Manufacturer Approval (PMA) LORD Tension Torsion StrapNo. PQ0466NEsupplement No.135 for installation of LORD Tension Torsion StrapAssembly (P/N LORD204-310-101101) on the Main Rotor.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 14 CFR Part 29.301 {29-0}; 29.303 {29-0}; 29.305 {29-0}; 29.547 {29-40}; 29.571 {29-55};29.601 {29-0}; 29.602 {29-45}; 29.6...	Instructions for Continued Airworthiness for LORD P/ NLORD204-310-101101, dated 29 May 2019Project Specific Certification Plan APA15-0112, Rev B, dated 06September 2019or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Implementation...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/11/2019	Active	10071729
10071731	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			737-800	Alternative Maximum Takeoff WeightReduction of the certified maximum take-off weight of the aircraft to66990 kg, and maximum landing weight to 65317 kg.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	Airplane Flight Manual Supplement MODE00268_AFMS1 rev 1<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Applicable to Boeing 737-800 aeroplanes, equipped with winglets andCFM56-7B26E engines, AFM option code <986WS1>.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introdu...	19/11/2019	Active	10071731
10071732	AERO-DIENST GMBH			55	RNP-1 i.a.w. CS-ACNS Issue 02, Subpart C	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:25.1529 from CS-25initial issue.- CS-ACNS-Issue 2.The requirements for environmental protection and the associatedcertif...	Airplane Flight Manual Supplement 20319-LJ.DC-106, Rev. 00<(>,<) >or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The aircraft must be equipped with Collins HSI-85 (ex-factory) as wellas with a Universal FMS UNS-1L according to Aero-Dienst's STCEASA.A.S. 02659.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed c...	19/11/2019	Active	10071732
10071737	LUFTHANSA TECHNIK AG			A319-115	A319 - Cabin ModificationThe existing VIP cabin interior, which has been installed by Airbus,shall be modified to install one new compartment and to modify severalareas within thecabin. In addition some systems shall be modified and acomplete new In-Flight Entertainment system will be installed. Pa...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-4301-002 - Vibration and buffetingcompliance criteria for large external antenna installationthe following paragraph (s) at a later amendmen...	- Airplane Flight Manual: A-00-19/40-AFM Issue 01 Revision00 dated 10.Sep. 2019- Master Minimum Equipment List: A-00-19/40-MMEL Revision 00 dated24.Sep.2019- Supplemental Type Design Document: STDD00-18/04M Issue 01 Revision 00dated 18.Nov. 2019- Instruction for Continued Airworthiness: A-00-19/40-...	1) As no compliance demonstration with the certification basis for OSDconstituents CCD and FCD has been performed, the aircraft is not allowedto be registered in any EASA member state without demonstration ofcompliance to CCD and FCD OSD requirements.2) The changed aircraft is intended to operate wi...	20/11/2019	Active	10071737
10071738	SIRIUM AEROTECH S.L.	REV. 1		737-500, 757-200/-200PF/-300 737-100/-200/-200C/-300/-400	ADS-B System Upgrade for B737 and B757Revision 1: added reference to minor change SA20-40M for MMEL-S	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	MASTER DATA LIST SA19-03S-MDL Rev 02B737 AFM SUPPLEMENT SA19-03S-AFMS-737 Rev 01B757 AFM SUPPLEMENT SA19-03S-AFMS-757 Rev 01MMEL supplement SA19-03S-MMELS rev 0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/09/2020	Active	10071738
10071752	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			737-800 737-700 737-600	Survival ELT InstallationSurvival Emergency Locator Transmitter (ELT) ELTA ATD406S Series P/N01N65920 installation in cabin interior in enclosed overhead bin.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List doc JCAERO/MDL/0447 issue 1.0or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/11/2019	Active	10071752

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071756	GARMIN INTERNATIONAL, Inc.	REV. 1	FAA STC SA02636SE	SEE FAA AML SA02636SE SEE FAA AML	Installation of Garmin GPS 175 Navigation System, GNX 375 NavigationSystem with ADS-B In/Out Transponder, and GNC 355 Navigation System withVHF COM Radio.Rev. 1: Addition of F150,FA 150, FA152, FRA150, PA-16, PA16S and PC-7to the ApprovedModel List (AML).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: The certification basisfor parts changed or affected by this change is CS-23 at Amendment 0through Amendment 5, as detaile...	Installation in accordance with Garmin Master Drawing List (MDL) 005-01206-A1 Revision 1, dated March 22, 2019.Operate in accordance with Garmin Airplane Flight Manual Supplement(AFMS) 190-02207-A3 Revision 1, dated March 22, 2019; and EASAAirplaneFlight Manual Supplement 190-02207-A6 Revision 1, da...	For the GPS 175, a GPS/SBAS antenna must be previously or concurrentlyinstalled.For the GNX 375, a GPS/SBAS antenna anda transponder antenna must bepreviously or concurrently installed.For the GNC 355, a GPS/SBAS antenna and a VHF COM antenna must bepreviously or concurrently installed. For IFR ins...	01/09/2023	Active	10071756
10071757	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04388AT	787-8	Class Divider Installation in a Boeing 787-8 aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04388AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. HAECO Cabin Solutions, LLC Master Data List 19T011L501, Revision IR,dated 20 November 2019, or later FAA approved revisions.2. HAECO Cabin Solutions Instructions for Continued Airworthiness19T011R509, Revision 00, dated 19 September 2019, or later FAA acceptedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/11/2019	Active	10071757
10071764	LUFTHANSA TECHNIK AG	REV. 1		A321-111/-131/-211/-231 A320-211/-214/-216/-271N	CGC System - ActivationThe modification activates the new Complementary Ground Component (CGC)System as a part of the European Aviation Network (EAN).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Compliance Checklist: CCL23-19/07M Rev 1 dated 17.Jan.2020- Instructions for Continued Airworthiness: A-00-19/87-ICA Issue 01Revision 0 dated 24.Oct.2019- Supplemental Type Design Document: STDD23-18/01M Issue 2 Revision 0dated 18.Jan. 2020- Cabin Crew Data: A-00-19/103-CCD Revision 0 dated 06.Dec....	Installation only on models that satisfy the criteria defined inconfiguration sheet AWF01-53-EI-001, AWF-DR-01 and AWF02-23-MC5-02, Rev.0 or later revision of these documents.Prerequisite EASA STC: 10069307 and 10049524.Airworthiness Limitation Section mentioned within A-00-19/87-ICA.	23/01/2020	Active	10071764
10071765	LUFTHANSA TECHNIK AG			A321-111/-131/-211/-231 A320-211/-214/-216/-271N	MSS Satcom system installationThe modification installs theinstalls the full provisions for newMobile Satellite Services (MSS) System as a part of the EuropeanAviation Network (EAN), including electrical and structural parts andcomponents. Although all components are installed, the system is notac...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Supplemental Type Design Document: STDD23-18/03M Issue 01 Rev 0 dated22.Nov.2019- Instruction for Continued Airworthiness: A-00-19/85-ICA Issue 01 Rev00 dated 24.Oct.2019- Compliance Checklist: CCL23-18/03M Revision 2 dated 20.Nov. 2019,,or later revisions of the above listed document (s) approved/...	The installation can be performed only on models that satisfy thecriteria defined in configuration sheet AXU01-53-EI-002 Rev. 1 or laterrevision of this document.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevio...	22/11/2019	Active	10071765
10071779	AIRBASE CERTIFICATION ENTERPRISESERVICES (ACES) INC.		TCCA STC SA17-114, ISSUE 2	737-8	Seat Table Inset InstallationSeat Table Inset Installation in the middle seat of Triple PassengerSeat Assembly – forward facing – on Boeing model 737-8.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Modification Data Summary MDS 70015 Rev C, dated 30 May 2018;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/11/2019	Active	10071779

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071808	LUFTHANSA TECHNIK AG	REV. 1		747-400	Riblets Film on Lower FuselageApplication of self-adhesive film on lower fuselage aft of STA 440. Amicrostructure pattern is applied to the film in order to influence theboundary layer and reduce dragRevision 1: Improved Riblets film material T1TF2.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Supplemental Type Definition Document STDD11-18/01M Issue02 rev 00- Airplane Flight Manual Supplement – A-00-19/42-AFM Issue 02 rev 00- Instructions for Continued AirworthinessA-00-19/42-ICA Issue 01 rev04or later revisions of the above listed document(s) approved/ acceptedunder the EASA system....	Riblets foils P/Ns R()-T1TF1-(xxxxx)P only applicable to B747 MSN 29871.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ orrepair will introduce no adverseeffect upon the airworthines...	16/06/2020	Active	10071808
10071814	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1	EASA.A.S. 00748	PA-32RT-300 PA-32R-300/-301 PA-32-301 (SARATOGA) PA-32-300 (CHEROKEE SIX 300) PA-32-260 (CHEROKEE SIX 260)	Installation of MTV-9-B/198-52() on Piper PA-32	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-36, Amendment 4, FAR36, Amdt 36-30This certificate/ approval involves a change to the requirements forenvironmental pro...	According to MT-Propeller Master Documentation List No. E-3504, Rev 1To be operated in accordance with MT-Propeller AFM-S Document No.E-3506, Rev 1To be operated in accordance with MT-Propeller AFM-S Document No.E-3525, Rev 1 with NR Kit MTP 198-52-PA32®To be installed i.a.w. Installation Instructio...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	26/11/2019	Active	10071814
10071815	AEROTEC & CONCEPT	REV. 2		SEE EASA APPROVED MODEL LIST	Aerotec UCS AML StretcherRevision of AML STC 10071815 to address additional aircraft types:Boeing 737/ Boeing 787/ ATR 42/ATR72 / DHC-8 / EMB-145	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25.301, 25.303,25.305, 25.307, 25.321, 25.331, 25.337, 25.341, 25.561, 25.613, 25.625,25.785, 25.789, 25.791, 25.803,2...	Master Data List/ MDL: SEE EASA APPROVED MODEL LISTAFM Supplement / AFMS: SEE EASA APPROVED MODEL LISTInstructions for Continued Airworthiness / ICA: SEE EASA APPROVED MODELLISTorlater revisions of the above listed document(s) approved/ acceptedunder the EASA system.	- Per AFM supplement: SEE EASA APPROVED MODEL LIST- Per ICAsupplement: SEE EASA APPROVED MODEL LIST- Installation is limited to configurations as per drawing ref.025-18113-101 or025-180113-102 or 025-18113-103 or 025-180113-105 or025-180113-106 without Medical or Oxygen Equipment.Prior to installa...	27/04/2021	Active	10071815
10071832	AIRBORNE TECHNOLOGIES GmbH	REV. 1		AS 350 B3 AS 350 B2	STC-AT-140 Survey Configuration.In the exterior of the helicopter, this STC combines the installation ofa Riegl VP-1 eye-safe laser scanner on the forward RH side of thehelicopter(according to unmodified STC EASA.IM.IR.S.01158, validatingFAA SR01784LA), a SWE400 EOIR Camera on the forward LH side (...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS-27 initial issue: 27.1, 27.25, 27.27, 27.29, 27.45, 27.51, 27.65,27.67, 27.71, 27.73, 27.75, 27.79, 27.141, 27.143, 27.1...	Change Approval Sheet, doc. ref. STC-140-G-AS Rev. 0Flight Manual Supplement, doc. no. STC-140-G-AFM Rev. 1Maintenance Manual Supplement, doc. no. STC-140-G-AMM Rev. 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The following changes must be embedded prior to the installation of thisSTC:(A) Airfilm Camera System STC ref. EASA.IM.R.S.01158 (Validating FAA STCSR01784LA)(B) Airfilm Camera System STC ref. EASA 10016801 (Validating FAA STCSR01785LA)(C) Amtech Aeronautical STC ref. EASA 10057051 (Validating TCCAS...	29/11/2019	Active	10071832
10071833	MT-PROPELLER ENTWICKLUNG GmbH			PA-28RT-201 (ARROW IV) PA-28R-201 (ARROW III) PA-28R-200 (ARROW II) PA-28R-200 (ARROW) PA-28R-180 (ARROW)	MTV-12-B/188-59( ) on PA-28R(T)-Series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 36, Amdt 4, FAR 36,Amdt 36-30This certificate/ approval involves a change to the requirements forenvironmental protecti...	According to MT-Propeller Master Documentation List No. E-3492, Rev 0To be operated in accordance with MT-Propeller AFM-S Document No.E-3494, Rev 0To be installed i.a.w. Installation Instructions Doc. No. E-3495, Rev 0To be maintained i.a.w. Instruction for continued airworthiness Doc. No.E-3496, Re...	According to limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/11/2019	Active	10071833

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071834	BOEING IRELAND LIMITED	REV. 1	CAA UK RESPONSIBILITY	787-8	United Airlines Cabin Reconfiguration – Installation of Business Class,Premium Economy and Economy Class Seating on 787-8 aircraftRev. 1: Transfer to new certificate holder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Boeing Technical Services UK Ltd Instructions for ContinuedAirworthiness (ICA) B21792-ICA00 Revision 1Boeing Technical Services UK Ltd Master Data List No. B21792-MDL00Revision 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The following are prerequisites for this STC (and will require EASAapproval if aircraft with this STC installed are to be added to an EUregister):FAA STC No. ST09723ACBoeing Master Change No. 2500MK8110Prior to installation of this change/repair it must be determined thatthe interrelationship betwee...	16/11/2020	Active	10071834
10071889	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST04075NY	A380-861 A380-842 A380-841	Installation of a Panasonic Avionics In-Flight Entertainment (IFE) SystemRevision 1 replaces the eX2 Integrated Passenger System Controller (IPSC) in F/C and B/C with a newer version.	The Certification Bases for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 amdt 4 25.853The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	1. Delta Engineering Master Data List 0157-10832-2463 Revision B dated20 May 2022;2. Instructions for Continued Airworthiness 0757-10833-2463 Revision B;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is applicable to all serial numbers lis...	11/08/2022	Active	10071889
10071905	GUENTERT + KOHLMETZ GMBH			LS 3-A LS 3-17 LS 3	LS-3 Nachrüstung von WingletsNachrüstung der Tragflächen aller LS 3 Baureihen mit Winglets für die15m Flügelenden.	The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Technische Mitteilung/ technical note GK-LS-01Drawings for LS3-WL: 3WL_1401, 3WL_1411, 3WL_1421, issue 22.11.2019Anhang (Ergänzung) zum Flughandbuch der LS-3, Ausgebe November 2019Supplement to the flight manual of LS3, issue November 2019or later revisions of the above listed document(s) approved/a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/12/2019	Active	10071905
10071909	JET AVIATION AG			747-400, 747-400F	EGPWS UpgradeRemoved: Honeywell EGPWS MKVInstalled: Honeywell EGPWS MKV-A	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: The change complieswith the applicable sections of EASA CS-25Amdt.22 and CS-ACNS.E.TAWSIssue 2.The requirements for envir...	- Master Data List: Doc. No. JBSL-M-01343MDL-01, Issue 1<(>,<)>- Instructions for continued Airworthiness: Doc. No. JBSL-M-01343ICA-01,Issue 1<(>,<)>- Aircraft Flight Manual Supplement: Doc. No. JBSL-M-01343AFM-01, Issue1or later revisionsof the above listed document (s) approved/ acceptedunder the E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/12/2019	Active	10071909
10071911	SABENA TECHNICS BOD	REV. 2		A310-304	A310 ADS-B Out installationRev 1: The revised STC consists to add a specific configuration.Rev 2: Correction of a typo (reference of the Modification CertificationPlan)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-ACNS Issue2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of...	Modification Certification Programme ref. MCP-A1080-34-001 issue 9 dated24/01/2020Master Data List ref. MDL-S-34-4213-431 Issue A dated 27/11/2019Master Data List ref. MDL-S-34-4213-422 Issue A dated 27/01/2020Aircraft Flight Manual Supplement ref. AFMS-A1080-34-010 issue C dated20/11/2019Aircraft F...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/02/2020	Active	10071911

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071912	HELI-ONE (NORWAY) AS	REV. 1		AS 332 L, AS 332 L1	Argos II HD FLIR installation (ref. modification AHSE-70900)Revision 1 introduces an alternative prerequisite for the embodiment ofthe STC.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 29 Amdt 4 for the following requirements: 29.1, 29.21, 29.29, 29.45,29.49, 29.51, 29.53, 29.55, 29.59, 29...	Certification Programme (CP) ref. AHSE-70901 Revision C, dated 01November 2023AS 332 L/L1 Flight Manual Supplement (FMS) ref. H1 No.316 Revision dated13 September 2019Product Change Declaration ref. AHSE-70900 Revision G, dated 29 January2024Declaration of Compliance ref. AHSE-70905 Revision D, date...	The installation of Heli-One STC ref. 10036393 or Heli-One Minor Changeref. SDD AHSE56152 is a pre-requisite for the embodiment of this STC.Laser pointer (laser class 3B) and laser illuminator (laser class 4)shall be disabled because they are outside of the scope of this STC andnot part of the EASAP...	02/02/2024	Active	10071912
10071914	JET AVIATION AG	REV. 1		CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT)	WLAN ActivationDemonstration of immunity to IEEE 802.11 a/b/g/n/ac passenger PEDtransmission on Bombardier CL-600-2B16 (601-3A, 601-3R, 604 Variants),for all flight phases except low visibility APP based on EASA CM-ES-003.The WLAN Access Point (WAP) installation is not part of this STC.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 as of Amdt 22:789, 831, 869, 1301<(>,<)> 1309<(>,<)> 1351, 1353, 1357, 1360, 1431,1501, 1529, 1581, 1585, 1707.The r...	-MDL JBSL-M-01244MDL-01-AFMS JBSL-M-01244AFM-01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This change is applicable to Bombadier CL600 (CL-600-2B16 model)previously fitted with properly certified WLAN Access Point system withWLAN functionality tested and deactivated (system provisions).Limitations as stated in the AFMS JBSL-M-01244AFM-01.Prior to installation of this change/repair it mus...	11/12/2019	Active	10071914
10071915	LEE AEROSPACE, INC.		FAA STC ST01900WI	DHC-8-301/-311/-315/-401 /-402 DHC-8-102/-103/-106/-201 /-202	Heated (LH) Side Canopy Window Assembly Replacement Installation	The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the productare unchangedand remain applicable to this certificate/approval without any impact onthe noise database.The Certification Basis for the original product as amended by thefollowingt...	Master Data List No. LAI-MDL-108, Revision A, dated 13 September 2019,or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe DHC-8-101 and DHC-8-400 are excluded...	05/12/2019	Active	10071915
10071921	FOKKER SERVICES B.V.			757-300 757-200PF 757-200	Introduction of Dual Activated Stand-Alone GNSS Interface to ATCtransponder on B757 to meet ADS-B Out V2 RequirementsThis STC introduces the installation of a dual stand-alone Freeflight1203C GPS/SBAS receiver as a compliant GNSS source toenable ADS-B outV2 capabilities on the B757, for those aircr...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Issue 2 of CSACNS.D.AC.015, CS ACNS.D.AC.025, CS ACNS.D.AC.030, CS ACNS.D.AC.035, CSACNS.D.AC.040, CS ACNS.D.AC.040, CS AC...	- Compliance Record Report CRR-0399 issue 2-B757-ADSB-AFM-S-002 issue 1- B757-ADSB-FCD-S-002 issue 1or later revisionsof the above listed document(s) approved/ acceptedunder the EASA system.	Prerequisite for the application of the present STC is to havepreviously performed EASA STC 10068216 and Fokker Services minor mod refCP/CRR-0409	09/12/2019	Active	10071921
10071934	WEATHER MODIFICATION LLC	REV. 1	FAA SA02855CH	C90A, C90GT, C90GTI	STV-23: installation of weather modification equipment for modifyingweather conditions.Revision 1 corrects the company name.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change to the requirements forenvironmental protection or a change to the certified noise or emissionslevels.	To be installed in accordance with Installation drawing List219-004-IDL_C90 revision B datedOctober 16th 2019;To be operated in accordance with Aircraft Flight Manual Supplements219-025-AFMS_C-90A, Revision IR (for model C90) and 219-026-AFMS_C90GT & GTi Revision IR (for modelsC90GT & GTi);To be main...	When modified with this STC the aircraft can still be operated in thenormal category.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	09/12/2019	Active	10071934

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10071935	APTOZ EHF.	REV. 2		737-900, 737-900ER 737-600, 737-700, 737-800 737-300, 737-400, 737-500	DO260B GPS and Transponder Upgrade in accordance with Aptozdesignchange No. CRA341044 Revision A or later. The change covered by theoriginal STC complies with the mandated requirement for the performanceand the interoperability of surveillance for the single European sky asdirected by Commission Re...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-25 Amendment No.4,paragraphs 1, 29a-b, 301a, 302, 303, 305a-f, 307a, 337, 341, 365 a-b,561 b3, 571a-b, 581a-b, 601, 60...	- MDL341044 revision A or later- ICA341044-n initial revision or later (*)- AFM341044-n initial revision or later (*)(*) “-n” corresponds to the customised version related to the specificapplicable type, since this STC covers several types: B737-300 B737-400B737-500 B737-600 B737-700 B737-800 B737-9...	As per ICA341044-1 Revision B or other ICA341044-n Revisions (“-n”corresponds to the customised version related to the specific applicabletype, since this STC covers several types: B737-300 B737-400 B737-500B737-600 B737-700 B737-800 B737-900 B737-900ER).Prior to installation of this change/repair i...	02/02/2021	Active	10071935
10071939	SAAB DEFENSE AND SECURITY USA LLC		FAA STC ST01254AT	SAAB 340B	Enlarge Class "C" cargo compartment of SAAB 340B by relocating cargo bybulkhead forward to F.S.594.1	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01254AT.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- FFV Aerotech's Master Drawing List, Document No. B22-2, Revision E,dated 10 February 1998, or later FAA approved revision.- FFV Aerotech's Airplane Flight Manual Supplement No. B22-9, dated 30January 1997, or later FAA approved revision.	The modification requires that SAAB 340-25-163, SAAB 340-25-184, andSAAB 340-26-005 have been complied with previously,or must be compliedwith simultaneously with the installation of this STC.Prior to installation of this design change itmust be determined thatthe interrelationship between this de...	09/12/2019	Active	10071939
10071970	AIRBUS HELICOPTERS, Inc.		FAA SH2917SW-D	AS 350 B/ AS 350 B1 AS 350 BA/ AS 350 D AS 350 B2/ AS 350 B3	Installation of Electric Attitude and/or Directional Gyro instruments.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Drawing List 350A82-1153, Revision S<(>,<)> dated 25 January 1991, orlater FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2019	Active	10071970
10071971	TELEDYNE UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	A380-861 A380-842 A380-841, A380-842, A380-861 A380-841	Installation of GroundLink AID+ SystemThe approval covers the installation of a Wireless Access Point (WAP)with an integral antenna and wiring between the WAP and the WirelessQuick Access Recorder (WQAR).The approval does not include the (T-)PEDs (installation, testing andoperation).Rev. 1: Transfer...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Security Protection - SC F-66 issue 1 dated 28August 2019.The requirements for environmental protection and the associatedcertified noise and/ or e...	Master Data List ref. MOD-MDL-037 issue 2 dated 27 November2019Aircraft Flight Manual Supplement ref. MOD-FMS-037 issue 1 dated 9August 2019Instructions for continued Airworthiness ref. MOD-ICA-037 issue 1 dated1 July 2019or later revisions of the above listed document(s) approved/ acceptedunder the...	This STC does not allow WIFI connection between the installed system and(T-)PED devices which shall stay in flight mode.For WIFI connection, any operator shall therefore demonstrate (as partof an additional certification activity) (T-)PED tolerance of theaircraft before enabling WIFI transmission fr...	26/11/2020	Active	10071971
10071973	AIRBUS HELICOPTERS, Inc.		FAA SH4636SW-D	AS 350 B/ AS 350 B1 AS 350 BA/ AS 350 D AS 350 B2/ AS 350 B3	Installation of tail rotor guard.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Drawing List 350A82-1181, Revision F, dated 20 October 1998or later FAAapproved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2019	Active	10071973
10071994	ELBE FLUGZEUGWERKE GmbH	REV. 33		A321-211, A321-231 A320-214, A320-232	Passenger to Freighter (P2F) ConversionRev. 1: Removal of limitations.Rev. 2: A321P2F Frame Shell Structure improvements and optionalConfigurations: - RFD Option A Redefined Flight Deck (new monument, additionalseat) - to allow supernumerary access to the Class E Main Deck CargoCompa...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:D-0341-001 Redefined Flight Deck;D-0307-001 Access to Class E Cargo Compartment in flight;F-0307-002 Non-rechargeable Lithium Battery Installation.This certif...	- DOA/2018/005 Initial Issue dated on 20 FEB 2020- DOA/2019/053 Initial Issue (A321P2F with Optional Configurations) dated on 10 AUG 2020- 349/QAD/010-1 Rev A Statement of Compliance Summary Report for A321P2F- 349/QAD/011-1 Rev B Certification Summary Report for A321P2F 14 PalletConfiguration- 349/ Q...	Limitations as per ALS supplement.The technical documentation defined for each individual STC revisionretains its validity for the configurations covered by the associatedrevision.This modification must be installed with the following associatedchanges:a) Airbus Cockpit Computer Modifications:i. EIS...	02/10/2025	Active	10071994

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072001	AIRBUS HELICOPTERS, Inc.		FAA SH7693SW-D	AS 350 D AS 350 B/ AS 350 B1 AS 350 B2/ AS 350 B3	Installation of six heavy duty tiedown rings in the aft cabin floor.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Sealed Drawing List 350A82-1714, Revision A, dated 13 July 1990, orlater FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2019	Active	10072001
10072004	AIRBUS HELICOPTERS, Inc.		FAA SH8154SW-D	AS 350 B/ AS 350 B1 AS 350 BA/ AS 350 D AS 350 B2/ AS 350 B3	Installation of a Steerable Landing Light installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Drawing List 350A82-1724 Revision W, dated 26 November 2012or later FAAapproved revisions.Rotorcraft Flight Manual Supplement 350FMS-515 Rev IR, dated 10 December2012, or later FAA approved revisions.Instructions for Continued Airworthiness 350MMS-025 Rev IR, dated 9 May2012, or later FAA accepted...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2019	Active	10072004
10072006	AIRBUS HELICOPTERS, Inc.		FAA SR09279RC-D	AS 350 B3	Installation of a full width or half panel replacement instrument panel.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Drawing List 350A82-1759 revision G dated 26 June 2004 or later FAAapproved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	11/12/2019	Active	10072006
10072015	APTOZ EHF.	REV. 1		767-300	EFB Server Connectivity via GEE SMU (Ku) in accordance withCP-767-4620-007 Revision A.This change introduces connectivity of existing Electronic Flight Bag(EFB) system via existing Global Eagle Entertainment (GEE) Wifi system.This change enables the DIC-600 (EFB Server) to communicate to groundnetwo...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC F-01 - Security protection of Aircraftsystems and networks from internal and external Security Threats.- The following paragraph (s)...	Icelandair Continued Airworthiness Instructions, document referenceCAI-767-4620-00 7 revision IR<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	Prior or concurrent modification (s):The EFB System is to beinstalled in accordance with ScandinavianAvionics Design (SA)EASA STC 10059804.The GEE Wifi System (previously known asRow44) is to be installed perEASA VSTC 10059114).IcelandairDOA approved Minor changes EO-767-4620-004 andEO-767-4620-00...	27/05/2025	Active	10072015
10072022	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)			SEE APPROVED MODEL LIST	EASA Validation of FAA Approved AML Supplemental Type Certificate (STC)No. STC ST02639LA. This AML STC installs an RTCADO 260B Version 2 ADS-BOut compliant ACSS Mode S transponder (NXT-800)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: See EASA Approved ModelListThe requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	Doc Ref: 8010071-600 Rev – NXT-800 System Maintenance Manual (ICA) Doc Ref: 8010071-900 Rev – Flight Manual Supplement (AFMS)Doc Ref: 8910071-001 Rev – NXT-800 ADS-B Out AML STC Master Data ListDoc Ref: 8010071-100 Rev B, NXT-800 AML STC Installation Manualor later revisions of the above listed docum...	None	12/12/2019	Active	10072022

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072023	JAMCO AMERICA, INC.		FAA STC ST01882SE-D	777-300ER	Interior reconfiguration of Boeing Model 777-300ER	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS.25 at Amdt. 4:§25.856(a), §25.1353(a)(b)(d), §25.1431(a)(c)The requirements for environmental protection and the associa...	Jamco America, Inc. Master Drawing List (MDL) No. MDL 1269-1, RevisionL, dated 14 December 2010, or later Federal Aviation Administration(FAA) approved revision.Instructions for Continued Airworthiness, document number ICA1269-1,Rev. L, dated 16 December 2010, or later FAA approved revision.Instruct...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.EASA STC 10071727 (FAA STC ST02645NY-D), Install...	03/03/2020	Active	10072023
10072025	2 EXCEL DESIGN LIMITED	REV. 1	CAA UK RESPONSIBILITY	B200T B200CT 200T 200CT 200C 200	Cabin Reconfiguration for Special Missions - King Air 200	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at amendment CS-23 Amd 1: 23.1, 23.3(d),23.21, 23.23, 23.25(a), 23.301, 23.303, 23.305, 23,307, 23.321, 23.333,23.335, 23.337, 23.341, 23.471, 2...	- Installed in accordance with document Installation Instructions 2XL155 LEF49A(1) Issue 1 listed in document: Master Data List LEF 78, Issue1 Dated 9th December 2019.- Operated in accordance with document: Flight Manual Supplement 2XL 152LEF71B(1), Revision 1, Dated 20th November 2019.- MaintainedA...	- Configuration: Aircraft build standard is a Beechcraft King Air 200with following pre-requisite STC installed:- STC 10048797 Revision 2 – Centrex Aerospace HALO 250 STC Option 2installed.- Maximum number of passengers four (4).Prior to installation of this change/repair it must be determined thatt...	16/12/2019	Active	10072025
10072026	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	B200CT, B200T 200C, 200CT, 200T	Antenna and Disconnect Installations - King Air 200	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at amendment CS-23 Amd 1: 23.1, 23.3(d),23.21, 23.23, 23.25(a), 23.45, 23.49(a)(b),23.51(c), 23.53(c), 23.57,23.59, 23.61, 23.63(a)(d), 23.67(c...	- Installed in accordance with documents: Installation Instructions -Master 2XL152 LEF49A(1) Issue 5, Installation Instructions - U1, U4, L62XL152 LEF49A (2) Issue 1,Installation Instructions - U2 L2 L3 L9 L13 2XL152 LEF49A(3) Issue 1,Installation Instructions - L5 & L7 2XL152 LEF49A(4) Issue 1,Insta...	: Configuration: Aircraft build standard is a Beechcraft King Air 200with Pratt & Whitney Canada PT6A-41 engines with standard three bladedHartzell HC-B3TN-3G propellers with following pre-requisite STCs:STC 10048797 Rev 2 - Centex Aerospace HALO 250 STC Option 2STC 10016599 Rev1 – Installation ofT...	15/01/2020	Active	10072026
10072027	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	B200T B200CT 200T 200C 200	Installation of a Drop Tube - King Air 200	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at amendment CS-23 Amd 1:23.1, 23.3(d), 23.21, 23.23, 23.25(a), 23.45, 23.49(a)(b),23.63(a)(d),23.69, 23.73(c), 23.75, 23.77(c), 23.141, 23.143...	- Installed in accordance with document Installation Instructions 2XL158 LEF49A(1) Issue 1 and Installation Instructions 2XL 158 LEF 54I(4)Issue 2 listed in document: Master Data List LEF 78, Issue 3 Dated 11thDecember 2019.- Operated inaccordance with document: Flight Manual Supplement 2XL 158LE...	Configuration: Aircraft build standard is a Beechcraft KingAir 200 withPratt & Whitney Canada PT6A-41 engines with standard three bladedHartzell HC-B3TN-3G propellers with following pre-requisite STCs:STC 10048797 Rev 2 - Centex AerospaceHALO 250 STC Option 2STC 10016599 Rev 1 – Installation of Du...	16/12/2019	Active	10072027
10072031	AMAC AEROSPACE SWITZERLAND AG	REV. 2		A320-251N	Interior OutfittingThis change provides instructions to install a VIP cabin layout into anew aircraft.Rev. 1 adds a crew rest compartment to the configuration.Rev. 2 adds the possibility to stow a limited amount of luggage in theCrew Rest Compartment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s):F-108 Security Protection of Aircraft Systems and NetworksD-129 Installation of Crew Rest Compartment- The following paragraph(s) at a later amendme...	The change is defined with Revision O of Master Data List documentMDL-GL01-2500The Aircraft shall be operated in accordance with Revision H of AirplaneFlight Manual Supplement document AFMS-GL01-2500.The Aircraft shall be maintained in accordance with Revision D ofInstructions for Continued Airworth...	Limitations as per Airplane Flight Manual Supplement documentAFMS-GL01-2500 and per Instructions for Continued Airworthiness documentICA-GL01-2500.AMAC Minor Change GL03-2500 shall be installed as prerequisite for thisinstallation.Aeroplanes modified per this STC are considered to be a “new type” fo...	16/09/2022	Active	10072031

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072048	LUFTHANSA TECHNIK AG			737-8	Installation of a TIOS (Two-In-One-Solution) Ka-Band Radomeon top ofvertical stabilizer of a Boeing 737-8	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airplane Flight Manual A-00-19/06-AFM Iss.Rev 01/00Instruction for Continued Airworthiness A-00-19/06-ICA Iss.Rev 02/01Supplemental Type Design Document STDD55-18/01M Iss.Rev 01.00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/12/2019	Active	10072048
10072052	AVIONITEC AG			340A	Installation TAS antennas in the pressurized fuselageOn thetop a GPS antenna (GARMIN GA-35) is replaced by a TAS doubleblade antenna and on the bottom a COM rod antenna (ARC A-15) is replacedby a TAS single blade antenna.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Instruction for Continued Airworthiness 11028-015 dated 31.10.2019or later revisions of the above listed document(s) approved under theEASA system.	Applicable to S/N 340A-0242Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installedchange and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	16/12/2019	Active	10072052
10072057	GLOBAL AEROSPACE DESIGNCORPORATION	REV. 1	FAA STC ST04417CH	767-300F 767-300	Data Link ACARS and CPDLCProvisional installation of the Envoy Data Link with Iridium system forAircraft CommunicationsAddressing and Reporting System (ACARS) andController PilotData Link Communication (CPDLC).Revision 1: Fully functional installation of the Data Link with IridiumSystem for Aircra...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-ACNS issue 2 forACNS.B.DLS.B1.001/005/010/015/020/025/030/035/040/050/055/060070/075/080/085090/095/100/105/110/115/120...	- Global Aerospace Design Corp document “EASA CertificationSummary”ref. 18GR164-ECS-2 Rev. C- Global Aerospace Design Corp document “Master Drawing List”ref.18GR164-MDL-2 Rev: L-Global Aerospace Design Corp document “Airplane Flight ManualSupplement” ref. 18GR164-AFM-2 Rev. A- Global Aerospace Des...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/08/2020	Active	10072057
10072060	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			A330-343	Cabin Reconfiguration introducing 21PAX new Premium Economyseats in theFwd Economy area and a cabin divider to split the FWD economy from thePremium economy and the introduction of an additional row of seats inthe Aft economy section. Introduction of PSU, cabin lights modification,new carpets and c...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List MODE00289_MDL REV 1Instructions for Continued Airworthiness MODE00289_ICA1_BEL Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	As per MODE00289_ICA1_BEL.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	17/12/2019	Active	10072060
10072091	SIRIUM AEROTECH S.L.	REV. 1		EMB-120, EMB-120ER, EMB-120RT	ADS-B Upgrade for EMB120This project aims showing compliance with CS-ACNS for the approval ofADS-B use in Radar Areas. For this purpose, ADS-B parameters will beconfigured in transponder, New WAAS/SBAS GPS installed and interfacedwith transponder and ADS-B Fail Annunciator installed.Rev. 1: added re...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List SA19-06S-MDL Revision 07AFM Supplement SA19-06S-AFMS Revision 03AMM Supplement SA19-06S-AMMS Revision 04 (ICA)MMEL supplement SA19-06S-MMELS rev 0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/09/2020	Active	10072091
10072098	LUFTHANSA TECHNIK AG	REV. 2		A321-231, A321-211 A321-231 A321-211	LATAM A321 Cabin conversionRev. 1: Change in the Limitations/Conditions section and AssociatedTechnical Documents sectionRev. 2: Change in the Associated Technical Documentation (added ref. toSTDD).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS25 at amdt. 00: CS25.562 except 25.562 (c)(5) and (c)(6), 25.1529 CS 25 at amdt. 5:25.1301(a) CS 25 at am...	Supplemental Type Definition Document STDD25-18/31MCompliance Checklist: CCL25-18/13M Revision 01 dated 11.Dec. 2019Instructions for Continued Airworthiness ICA_M010001103_RSP_10072018 rev3or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	: Following STC have to be performed in advance or in parallel:- Lufthansa STC 10069118 for the installation of Skypax galley/ lavatorymonument at door 4,- Lufthansa Technik STC 10068894 for the implementation of the directview camera system at door 4,- Lufthansa Technik STC 10065111 for the exchange...	09/02/2022	Active	10072098

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072100	HAVACILIK MUHENDISLIK VE SERTIFIKASHIZM ETLERI SANAYI VE TICARET ANONIMSIRKETI	REV. 1		A320-232	Installation of a 180 passengers interior arrangementRevision 1: administrative re-issuance, technical documentationreferences corrected.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 amdt. 14: 25.561,25.791, 25.853 CS25 amdt. 11: 25.29, 25.301, 25.303, 25.305, 25.307,25.321, 25.365, 25.571, 25.581,...	Master Drawing List MDL-TS1160 Issue IRInstructions for continued airworthiness TS1160R20 Issue Bor later revisions of the above listed document (s) approved/ acceptedunder the EASAsystem.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/01/2020	Active	10072100
10072102	APTOZ EHF.	REV. 1		757-200	Installation of 82C/11Y Passenger configurationThis change introduces a cabin reconfiguration with 82C/11Y passengerseating configuration and in-seat passenger systems to accommodate VIPoperation.Rev. 1: Transfer of STC from Icelandair EHFto Aptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: following CS 25paragraphs are at amdt 22: 25.15(a)/29/301(a)/302/303/365 (g)/601/603/605(a)/607/611/613 (a)/619...	-Top Collector Drawing ref. TCD-757-2520-527, Revision IR-Aircraft Flight Manual Supplement ref. AFM-757-2520-527, Revision IRor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10072102
10072108	SABENA TECHNICS BOD	REV. 2		A350-941 A350-1041	Economy seats installationThis modification installs Y/C seats in mid and aft passenger areas,together with in-seat IFEsystem, and life vest in their tamper proofseal pouchRevision 1: MSN limitation removedRevision 2: seats replacement due to material obsolescence of backrestand kick panel	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Data List, ref: MDL-S-25-4262 Issue C, dated 08 June 2021- Instruction for Continued Airworthiness, ref: ICA-V0003-25-009 IssueB, dated 08 June 2021- Minimum Master Equipment List Supplement, ref: MMELS-V0003-25-020Issue B, dated 31 May 2021or later revisions of the above listed document(s)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/06/2021	Active	10072108
10072110	ANUVU			737-900ER 737-900 737-9 737-800 737-8 737-700 737-600	EFB Hardware Power AID installationInstallation of provision for hardware to host tablet EFB with power anddata connectivity	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-31 PTCthe following paragraph(s) at a later amendment:25.25 Weight Limits25.27 Center of gravity25.305(a)(b)(c) Strength and deformation25.307(...	Navaero, Aircraft Flight Manual Supplement, doc. No. 0118-AFMS-B7373,revision A, dated 04 April 2019Navaero, Instructions for Continued Airworthiness, doc. No. 0118-ICA-B737, revision A, dated 04 April 2019Navaero, Master Data List, doc. No. 0118-MDL-B737, revision A, dated 17December 2019or later re...	None	19/12/2019	Active	10072110
10072132	AVIONIK STRAUBING ENTWICKLUNGS GmbH			EMB-500	Exchange of existing Garmin GTX33D and/or GTX33 for Garmin GTX33D w/ ESand/or GTX33 w/ES using existing Transponder antennas	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): CRI F-101 ADSB-out Systemthe following paragraph(s) at a later amendment:CS-23 Amendment 4:23.29; 301; 303; 305; 307; 337; 561; 603; 607; 611; 613; 625; 867...	Installation, Operation and Maintenance according to Avionic StraubingMaster Documents List ASR-2019-056-MDL-01-00, revision 00, dated 25November 2019.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to Embraer EMB-500 aeroplanes which are factory equipped withdual Garmin GTX33(D) and a Garmin G1000 Flight Deck. The Garmin G1000Flight Deck must be configured with G1000Load 63.7 avionics software ora higher version.Prior to installation of this change/repair it must be determined thatthe...	19/12/2019	Active	10072132
10072133	H4 AEROSPACE (UK) Ltd.	REV. 1	CAA UK RESPONSIBILITY	717-200	Honeywell ADS-B Transponder Upgrade on Boeing 717 Aircraft for HoneywellSystemsR1 introduces an H4A MMEL supplement as an addition to the H4 AerospaceEASA STC.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-ACNS initial issueThe requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	-Master Minimum Equipment List ref. H4AMMEL001, Issue 2 dated 27/10/2020-H4 Aerospace Instructions for Continued Airworthiness No. H4AICA027Issue 2-H4 Aerospace Airplane Flight Manual Supplement H4AFMS052 Revision 1-H4 Aerospace Modification Summary No. H4A1931 Issue 2or later revisions of the above...	H4 Aerospace minor modifications H4A1928 and H4A1929 will installprovisions for the new TRA-100B Transponders and a newTSO-145ccompliant GPS system respectively and both must be embodied prior to thestart of this modification.Prior to installation of this change/repair it must be determined thatthe...	03/12/2020	Active	10072133

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072134	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			A330-343	A330 Monument Integration.Integration of Diehl Aviation monuments in Air Canada A330-300 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Technical Interface Document TID_M320001015_MHU_05112018 Revision 0- Master Data List, ref: EO_M320001015_MHU_12022019 Revision: 0- Instructions for Continued Airworthiness (Supplement), ref: ICA_M320001015_MHU_12022019 Revision 1or later revisions of the above listed document(s) approved/ accepte...	Adaption of the passenger cabin and installation of aircraft structuraland system provisions necessary for the monuments of this STC, asdefined in TID_M320001015_MHU_05112018 (as referenced), must beaccomplished concurrently with this STC prior to release to service.Prior to installation of this cha...	19/12/2019	Active	10072134
10072149	GULFSTREAM AEROSPACE Ltd.	REV. 1	CAA UK RESPONSIBILITY	GV-SP GV GIV-X GIV	Installation of Astronics T-310 KU SATCOM HSD System which suppliespassenger information and entertainment services.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Index List, Gulfstream Aerospace Ltd document No. GAeL19-13-MIL,Revision B, dated 28 November 2019Aircraft Flight Manual Supplement, Gulfstream Aerospace Ltd document No.GAeL19-13-AFMS-GIV, Revision -, dated 1 November 2019Aircraft Flight Manual Supplement, Gulfstream Aerospace Ltd document N...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/12/2019	Active	10072149
10072155	AEROLITE AG			PC-24	EMS Floor KitThis Major Change to Type Design covers the introduction of the FreightFloor Inst. P/N 024-0280001-501 andthe Aft Freight Floor Inst. P/N024-0234993-501.The Aft Freight Floor installation can be installed as alternative totheFreight Floor installation.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For Freight Floor Installation :-Instruction for ContinuousAirworthiness: OPM-024-0280001-501, initialissue-Weight andBalance Manual: WBM-024-0280001-501, initial issueFor Aft Freight Floor Installation:-Instruction for Continuous Airworthiness: OPM-024-0234993-501, initialissue-Weight and Balance...	This approval covers the floor installation for a cabin with a volumeinstalled equal or not greater than the one of theTC holder interiorconfiguration EX-8S-1.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevious...	23/12/2019	Active	10072155
10072159	NORTHERN AVIONICS S.R.L.	REV. 1		737-900ER 737-900 737-800 737-700 737-600 737-500 737-400 737-300 737-200 737-100	Wi-Fi WAvES installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.the following paragraph (s) at a later amendment: EASA CS-25 Amendment 2325.301, 303, 305, 307, 321, 337, 365, 561, 601, 603, 605, 609, 611, 613,619, 625, 771, 899, 1301, 1309, 1353, 1357, 1501, 1519...	- AFM Supplement doc. NAV 0598 Rev. 1- ICA NAV0598 R2 dated28/11/2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limitation as per document AFMS NAV0598 R1Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	30/01/2020	Active	10072159
10072161	SPECTRUM AEROMED, LLCd/ b/a SPECTRUM AEROMED		FAA STC SA04403CH	PC-6/B2-H4	EMS conversion	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Spectrum Aeromed Master Drawing List 6056DL, Revision 1,dated 14March 2019, or later FAA approved revisions.2. FAA Approved Aircraft Flight Manual Supplement, 6056FMS, dated 14June 2019, or later FAA approved revision.3. FAA Accepted Instructions for Continued Airworthiness, Manual 6056MM,Revisi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/01/2020	Active	10072161

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072168	CONCORDE BATTERY CORPORATION	REV. 1	FAA STC SA00959DE	EMB-505 (PHENOM 300)	Installation of Concorde valve regulated Lead-Acid batteries inreplacement of aircraft main batteries	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00959DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Document No. 5-0676, Master Drawing List, Embraer 505 BatteryUpgrade, Revision NC dated 21 March 2019, FAA approved 30 April 2019 orlater FAA approved revision.2. Instructions for Continued Airworthiness (ICA), Document No. 5-0678,Revision NC dated 21 March 2019, FAA Accepted 29 April 2019, or la...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/01/2020	Active	10072168
10072169	GAMA AVIATION (ENGINEERING) LIMITED		CAA UK RESPONSIBILITY	B300C B300 B200T B200GT B200CT B200CGT B200C B200	Installation of a Pressure Bulkhead Union Fitting.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Master Data List (MDL), document numberGAEL-1646MDL-01 Issue 1, dated 07/01/2020.Instructions for Continued Airworthiness in accordance with DesignStatement (DS), document number GAEL-1646DS-01 Issue 2, dated17/12/2019.or later revisions of the above listed document(s...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/01/2020	Active	10072169
10072177	CRANFIELD AEROSPACE SOLUTIONS LIMIT		CAA UK RESPONSIBILITY	SAAB 2000	Installation of Standalone ADS-B (Out) into Saab 2000 aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS Initial Issue.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain appli...	Cranfield Aerospace Solutions Ltd Instructions for ContinuedAirworthiness No. CAS/AMM1482 Issue 2Cranfield Aerospace Solutions Ltd Airplane Flight Manual SupplementCAS/AFM0013 Issue ACranfield Aerospace Solutions Ltd Type Design DefinitionAddendum No.CAS/TDDA1482 Issue Bor later revisions of the ab...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/01/2020	Active	10072177
10072182	FR AVIATION Ltd.		CAA UK RESPONSIBILITY	FAN JET FALCON SÉRIES E FAN JET FALCON SÉRIES D FAN JET FALCON	ADS-B OutChange to installed equipment to comply with ADS-BOut requirements.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Document List DC-0321 issue 1- AFM Supplement FRAH/FM/100 Issue 15or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is applicable to the Dassault FJF embodied with EASA.A.S.00510and EASA.A.S.02710.Prior to installation of thischange/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upo...	10/01/2020	Active	10072182
10072183	TEXTRON AVIATION Inc.	REV. 1	FAA SA11228DS	B200GT B200CGT B200C B200, B200C, B200GT, B200CGT B200	Installation of a Fuel Temperature Indication System on TextronAviation, Inc.Rev. 1: Transfer from Aerospace Systems International, LLC to TextronAviation Inc.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA11228DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Data list, document no. 607-00-0001<(>,<)> revision JR, dated 8November 2019Airplane Flight Manual Supplement, document no. 607-00-0027<(>,<)>revision C, dated 6 November 2019Instructions for Continued Airworthiness, document no. 607-00-0028<(>,<)> revision B, dated 02 October 2019or later re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/10/2023	Active	10072183

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072189	SOCIETE AIR FRANCE S.A.			777-300ER	Caraïbes -Océan Indien (COI) 14J Cabin reconfiguration modification777-17-007.Commercial cabin reconfiguration for AIR FRANCE Boeing 777 COI fleetincluding Business (J), Premium Economy (W) and Economy (J) classes seatreplacement, rearrangement and monuments replacement. Installation ofnew in-flight...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):CRI D-001 Installation of inflatable restraint systems (JAR 25.562 andJAR 25.785 at Change 14)The requirements for environmental protection and the as...	Societe Air France S.A. Change Approval Sheet CAS-B777-17-007 Revision0, paragraph 15.1 Master Definition Listor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/01/2020	Active	10072189
10072190	AEROTEC & CONCEPT	REV. 1		ATR 72-211 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Dual FMS UNS-1Lw installation in ATR 42/72 Airplanes for ADS-B OutImplementation and compliance with PBN Specificationsfor RNAV/RNP.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The applicable Sections of CS-ACNS Issue 2 for newSurveillance andNavigation Functions.The requirements for environmental protection and the associatedcertified noise and...	Master Data List AE19086MDL Rev: 2AFM Supplement AE19086AFMS Rev: 1Instructions for Continuous Airworthiness AE190861CARev: 0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	ICA document AE190861CARev:0, AFM supplement AE19086AFMS Rev:1.	20/10/2020	Active	10072190
10072193	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	A330-202	A330 Seat refurbishmentThis modification supports the refurbishment of existing seat (mainlyinstalling the elements of a new IFE system – the IFE system itselfbeing installed witha concurrent STC) together with the installation ofnew seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Configuration Scheme, ref. 3181-MCS-01 Issue 1, dated January2020- Instruction for Continued Airworthiness, ref. . 3181-MMS-01 Issue 1, dated December 2019 . 3181-MMS-02 Issue 1, dated December 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA sy...	1- This modification is limited to the MSN 4412- This modification must be implemented concurrently with SabenaTechnicsModification ref. S-00-4188Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installede...	14/01/2020	Active	10072193
10072230	ROCKY MOUNTAIN AIRCRAFT		TCCA SA02-1 ISSUE 6	DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300 DHC-6 SERIES 210 DHC-6 SERIES 200 DHC-6 SERIES 110 DHC-6 SERIES 100	Installation of substitute passenger cabin and cargo baggage compartmentfloor panels.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation of substitute passenger cabin floor panels in accordancewith Transport Canada Civil Aviation (TCCA) approved Rocky MountainAircraft (RMA) Modification Instruction E105310 revision -, dated March16, 2012.Installation of substitute cargo baggage floor panels in accordance withTransport Ca...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/01/2020	Active	10072230
10072233	BLACKHAWK AEROSPACE TECHNOLOGIES IN	REV. 1	FAA ST01853WI	650	Installation of Garmin GTS Traffic Sensor with Garmin GTX 3000 Mode STransponders and ADS-B Out.Rev. 1 corrects the Original STC Number.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List, Document No. 30142503, Rev. IR, datedAugust 24,2017Airplane Flight Manual Supplement, Document No. 30142510, Rev. IR, orDocument No. 30142511, Rev. IR, bothdated September 19, 2017;or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accord...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/03/2022	Active	10072233
10072235	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A320-214	Re-activation of ISPS and associated seat change.This Change is to re-activate and adapt the In-Seat Power Supply (ISPS)System on Airbus A320-214 aircraft post modification of currentlyinstalled B/E Aerospace Pinnacle 1019010 Series passenger seats inaccordance with OEM Service Bulletin (SB) Collins...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.831, 25.853,25.869, 25.1431, 25.1529 atAmendment 22.Therequirements for environmental protection and the associated...	Master Data List: JCAERO/MDL/0403 Issue 1.3<(>,<)>or laterrevisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/01/2020	Active	10072235

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072236	SABENA TECHNICS BOD	REV. 1		A330-202	A330 Air Lingus cabin modificationThis modification supports the modification of a cabin layout, mainlyinstalling new passenger seatsand new IFE.Revision 1 corrects references of the technical associateddocumentation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Data List, ref : MDL-S-00-4188 Issue B, dated 15 January 2020.- Instruction for Continued Airworthiness, ref :ICA-F3063-00-004 IssueB, dated 15 January 2020or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	1- This modification is limited to MSN 441.2- This modification must be implemented concurrently with the EASAapproval N°10072193 (EASA STC : A330 Seat refurbishment).3- The following modifications are prerequisites to the installation ofthis modification :- EASA approval N°10043586 (Validation of F...	16/01/2020	Active	10072236
10072240	BOEING IRELAND LIMITED	REV. 1		787-9	United Airlines Cabin Reconfiguration – Installation of Business Class,Premium Economy and Economy Class Seating on 787-9 aircraft.Rev. 1: Transfer to new certificate holder.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Boeing Technical Services UK Ltd Instructions for ContinuedAirworthiness (ICA) B10878-ICA00 Revision 2Boeing Technical Services UK Ltd Master Data List No. B10878-MDL00Revision 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The following are prerequisites for this STC:Boeing Technical Services UK Ltd Minor Modification No. 25013Boeing MasterChange No. 2500MK8105 will require EASA approval ifaircraftwith this STC installed are to be added to an EU registerThe following Boeing Technical Services UK Ltd documents define...	16/11/2020	Active	10072240
10072244	ALPINE AEROTECH LP		TCCA SH19-47 ISSUE 1	212	Basic Digital Flight Instrument Kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA Rotorcraft Flight Manual Supplement AAL-280-045-402_NIdated 13January 2020Instruction for Continuing Airworthiness AAL-280-045-701_NI dated 21October 2019Master Data List AAL-280-044-001_Ni dated 21 October 2019or later revisions of the above listed document(s) approved/ accepted onbehalf of EA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/01/2020	Active	10072244
10072245	TRAKKA USA, LLC		FAA SR02657LA	206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	Installation of a Trakkabeam A800 Searchlight on the Aero PacificAP407UMOI Aft Utility Mount (STC 10072247) of the affected helicopters.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Meeker Aviation Services, Ltd, Master Drawing List TRK-110,Revision C,dated 22 November 2017 or later FAA approved revisions.Rotorcraft Flight Manual Supplement TRK-107, Revision IR, dated 27October 2017, or later FAA approved revisions.Instructions for Continued Airworthiness TRK-108, Revision 0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This determination should include considerationi...	17/01/2020	Active	10072245
10072247	MEEKER SPECIAL OPS, INCORPORATION d/b/a MEEKER AVIATION		FAA SR00891LA	206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	Installation of aft utility mount.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Master Data List, Aero Pacific Document Number 407UM01-30, Revision"NEW" dated 1 October 2001, or later FAA approved revisions.Flight Manual Supplement Document Number 407UM01-10 dated 20 December1999 or later FAA approved revisions is required for this installation.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	17/01/2020	Active	10072247
10072250	MICRO AERODYNAMICS, INC.		FAA SA01912SE	58/ 58A/ G58	Installation of vortex generators on the wings, engine nacelle<(>,<)>horizontal tail surfaces, and leading edge of the rudder of the abovemodel aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	Drawing Package, MA2226, Rev. IR, dated 17 September 2008, andInstaliation Manual, MA2227<(>,<)> Rev. IR, dated 2 October 2008, orlater FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.If more than five vortex generators are damagedi...	21/01/2020	Active	10072250

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072257	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)	REV. 1		737-700	New Maximum Take-Off WeightReduction of the certified maximum take-off weight of the aircraft to56472 kg, and maximum landing weight to 55338 kg.Rev. 1: Added a/c configuration with CFM56-7B22E engines	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase and/or emission levels.	Airplane Flight Manual Supplement MODE00292_AFMS1 rev 2<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Applicable to Boeing 737-700 aeroplanes, equipped with winglets andCFM56-7B22 / CFM56-7B22E engines (including intermix engineconfiguration).- Aeroplane must be operated as per AFMS MODE00292_AFMS1 rev 2 or later.Prior to installation ofthis change/repair it must be determined thatthe interrelati...	20/11/2020	Active	10072257
10072259	COMTECH GLOBAL AVIATION SERVICES S.			777F 777-300, 777-300ER 777-200, 777-200LR	Introduction of PAX. E/C Seat CushionsThis modification introduces new cushions to the standard economy class(E/C) seats keeping existing dress cover fabric materials.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	CTG-MS5040-777 MODIFICATION SUMMARY<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder theEASA system	Comtech bottom seat cushions P/N: 864984-401CTG are not approved forinstallation in front row seats. Original seat manufacturer installationlimitations remain applicable after installing the Comtech bottom seatcushion P/ N:864984-401CTG.	23/01/2020	Active	10072259
10072260	SAFRAN CABIN INC.	REV. 1		CL-600-2D15, CL-600-2D24 CL-600-2C10, CL-600-2E25	Flight Deck Access System (FDAS) InstallationRev. 5 introducing MMELRev. 6 Correction of type designations.Original FAANumber: FAA STC ST01415LA	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	MDL 9391000, Revision W, dated 26 October 2010For Model CL-600-2C10 Airplane Flight Manual Supplement No.939-1-AFMS-001dated 5 December 2002 or later FAA approved revision.Model CL-600-2D24 is added with Revision 1, dated 13 March 2003.For Models CL-600-2C10, CL-600-2D24 Airplane Flight Manual Supp...	Equipment Functional Check Intervals as defined in FAA approved C & DInteriors Report CDR9397-69, Revision A, dated November 8, 2002,"Certification Maintenance Requirements", or any later FAA approvedrevision, shall not be extended. Later revisions to C & D AerospaceReport CDR9397-69 may be used onl...	28/01/2020	Active	10072260
10072261	SAFRAN CABIN INC.			CL-600-2B19	Installation of Reinforced Cockpit Doors with Flight Deck Access System.Rev 2. Introducing MMELOriginal STC Number: FAAST01408LA	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	C & D Interiors Controlled Drawing List, 4631000, Revision B, dated 9December 2002, or later FAA approved revision.Safran, MMEL Supplement to CL-600-2B19/-2C10/-2D15/ -2D24/-2E25 with EASASTC 10069831, Rev 1 Installed, dated 09 January 2020or later revisions of the above listed document(s) approved/a...	Equipment Functional Check Intervals as defined in FAA approved C & DInteriors Report CDR4635-69, Revision A, dated 8 November 2002,“Certification Maintenance Requirements”, or any later FAA approvedrevision, shall not be extended. Later revisions to C & D AerospaceReport CDR4635-69 may be used only...	21/01/2020	Active	10072261
10072263	BELL HELICOPTER TEXTRON, Inc.		FAA SR11243DS	505	Installation of Expanded Avionics Shelf.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List, Report No. AA-16074. Revision A, dated 8November 2019, or later FAA approved revision.2. Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-16003, No Revision, dated 18 November 2019, orlater FAAaccepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	04/02/2020	Active	10072263

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072264	E A D AEROSPACE AIRWORTHINESS			A321-271N/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-131/-132/-133/-151N/-153N A319-111/-112/-113/-114/-115	MSS ANTENNA INSTALLATION ON AIRBUS SAThis modification consists in the installation, as provision on AirbusSingle Aisleseries aircraft, of Compact S-band Mobile Satellite Service (CSM) Antenna, from Inmarsat Aviation. It is implemented as follows :• Installation of the CSM antenna: an omni-direction...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-25.23/ 29/ 301/ 303/305/ 307/ 321/ 337/ 341/ 365/ 561/ 571/ 581/ 601/ 603/ 605/ 607/ 609/611/ 613/ 619/ 625/ 629/ 631/1...	- Master Document List ref. 01517-EAS-A-MDL, Rev C- Instructions for Continued Airworthiness Supplement ref.01517-EAS-A-ICA-01, Rev Aor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	As per ICA Supplement document ref. 01517-EAS-A-ICA-01, RevA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the p...	22/01/2020	Active	10072264
10072265	AVINCIS AVIATION ITALIA S.P.A	REV. 2		CL-215-6B11 (CL-415 VARIANT)	CL-415 ADS-B OUT CAPABILITYIntroduction of the Automatic Dependent Surveillance – Broadcast Outcapability (ADS-B Out).Rev. 1: Change of STC holder's name from Babcock Mission CriticalServices Italia S.p.A. Divisione Ala FIssa to Avincis Aviation ItaliaS.p.A., starting from the 1st of March 2023.Rev....	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-ACNS, subpart D,initial issue, 17 December 2013.The requirements for environmental protection and the associatedcertifi...	- Engineering Order, EOR-34-59-1810-A, rev 00, dated 16 December 2019- Flight Manual Supplement, FMS-34-59-1810-A, rev 00, dated 17 June 2019- Instructions for Continued Airworthiness, ICA-34-59-1810-A, dated 16December 2019- Master Document List, MDL-34-59-1810-A, rev 00, dated 16 December 2019or l...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2023	Active	10072265
10072277	ZLIN-AVION SERVICE S.R.O			V 503, V 503A, V 503AP, V 503P	Alternative Maintenance Programme	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Certification Program V 503 series propellers – AlternativeMaintenance Programme<(>,<)> doc. No. AW-01-V503, Rev. A, dated 13November 2019<(>,<)>- Supplement to the V 503 seriespropeller maintenance manual, doc. No.AMMS-01-V503-CZ, dated 13 November 2019Or later revisions of the above listed docu...	None	24/01/2020	Active	10072277
10072279	FOKKER SERVICES B.V.	REV. 1		737-400, 737-300 737-300, 737-400	B737 - Antenna Structural Provisions (Fokker Services Project CP/CRR-0407) Introduction of GPS antennastructural provisions (only).Revision 1 (CP/CRR-0420) extends the Limit of Validity (LOV) from 2000FC (initial approval) to 25800 FC, as per the new ICA supplement.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: amdt 23 of CS 25.561(a) and (b).The requirements for environmental protection and the associatedcertified noise and/ or...	- Certification Record Report CRR-0407 issue 1.Revision 1- Compliance Record Report CRR-0420 issue 1- Instructions for Continued Airworthiness supplement refB737-GNSS-ICA-S-003 issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- As per the ICA Supplement B737-GNSS-ICA-S-003 this STC has a Limit ofValidity of 25800 FC. Operation beyond such value is not allowed withoutprior EASA approval of an updated ICA Supplement.Prior to installation of this change/repair it must be determined thatthe interrelationship between this cha...	03/12/2020	Active	10072279
10072283	3S CERTIFICATION, LLC		FAA STC SA01860WI	B200	BendixKing AeroVue Avionics Systems Upgrade - B200	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):SC-CS23.Div-01 - Human FactorsSC-F23.1309-02 - HIRFSC-F23.1309-03 - Lightening IndirectFurther details for applicable CS paragraphs see Annex.	- Installed in accordance with document: Installation Data List No. 3S14-197-5001, Revision 3, Dated 20th April 2018.- Operated in accordance with document: Flight Manual SupplementDocument No. 3S14-197-7101, Revision 3, Dated 3rd June 2019.- Maintained in accordance with document Instructions for Co...	Other:The eligible aircraft serial numbers, as reflected inTCDS EASA.IM.277 /A24CE are:- BB-734, BB-793, BB-829- BB-854 through BB-870- BB-874 through BB-891- BB-894- BB-896 through BB-911- BB-913 through BB-990- BB-992 through BB-1833 (excluding BB-1114, BB-1204 and BB-1205,BB-1385 through BB-1388...	27/01/2020	Active	10072283

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072288	APTOZ EHF.			737-400	Iridium Antenna Installation - Structural installation of Sensor SystemIridium antenna Part Number S67-1575-365.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 Amdt 4, 25.1,25.29 (a)(b), 25.301(a)(b), 25.303, 25.305, 25.307(a), 25.337,25.365(a)(b), 25.571(a)(b), 25.581(a)(b),...	- Instructions for Continued Airworthiness ICA231058-1 Revision A- Change / repair approval, CRA231058 Revision Aor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	- This STC covers only the structural installation of the antenna.Functional and EMC aspects and equipment qualification are not coveredby this STC.- Inspections must be accomplished in accordance with the instructionsof ICA231058-1 Revision A, or later.Prior to installation of this change/repair it...	28/01/2020	Active	10072288
10072295	B/E AEROSPACE, Inc.		FAA ST04419AT	A330-343/A330-743L/ A330-941 A330-323/A330-341/ A330-342 A330-303/A330-321/ A330-322 A330-243F/A330-301/ A330-302 A330-223/A330-223F/ A330-243 A330-201/A330-202/ A330-203	Installation of the Rockwell Collins Automatic Dependent Surveillance - Broadcast (ADS-B) Out System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 25amendment 425.23 (a), 25.301 (a)(b)<(>,<)> 25.303, 25.305 (a), 25.307 (a), 25.561(c), 25.601, 25.603 (b)(c), 25.611, 25.853 (a), 25.863 (a), 25.869(a)(4), 25.1301 (a...	1. Master Drawing List (MDL) 2-186235-001, Rev. A, dated 8 December2017, or later FAA approved revision.2. Airplane Flight Manual Supplement for the Rockwell Collins AutomaticDependent Surveillance - Broadcast (ADS-B) Out System, 2-186235-805, RevIR, dated 30 January 2018, or later FAA approved revi...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/02/2020	Active	10072295
10072313	PMV ENGINEERING			A310/-324/-325 A310/-222/-304/-308/-322 A310/-203/-203 C/-204/-221 A300/-F4-203/-F4-605R/-F4-622R A300 C4-605 R VARIANT F A300/-C4-203/-C4-620 A300/-B4-620/-B4-622/-B-622R A300/-B4-601/-B4-603/-B4-605R A300/-B4-203/-B4-220/-B4-2C A300/-B4-102/-B4-103/-B4-120 A300/-B2-203/-B2-320/-B2K-3C A300/-B1/-B2-1A/-B2-1C/-B2-202	A300, A300-600 and 310 ADS-B Out installationThe modification consists to give the A300 product with the ADS-B outcapability	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-ACNS issue 2.The requirements for environmental protectionand the associatedcertified noise and/ or emissions levels o...	Certification Plan ref. AVI-01830-CIR-R02 dated 28 Oct. 2019Master Document List ref. AVI-1830-MDL-R02 dated 28 Oct. 2019Instructions for Continued Airworthiness ref. AVI-01830-ICA-S01-R02dated 28 Oct. 2019Instructions for Continued Airworthiness ref. AVI-01830-ICA-S02-R00dated 28 Oct. 2019Aircraft...	This approval has considered the configuration described intheCertification Plan ref. AVI-01830-CIR-R02 dated 28 Oct. 2019; alternateconfiguration can be managed as a minor change of the STC provided that:• The ATC transponders are compliant with ETSO C-166B and C-112D andmanufacturer is unchanged<...	28/01/2020	Active	10072313
10072320	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)	REV. 1		737-700	New Maximum Takeoff WeightReduction of the certified maximum take-off weight of the aircraft to61999 kgRev. 1: Added a/c configuration with CFM56-7B22E engines	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase and/or emission levels.	Airplane Flight manual Supplement MODE00291_AFMS1 rev 3<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- - Applicable to Boeing 737-700 aeroplanes equipped with winglets andCFM56-7B22 / CFM56-7B22E engines (including intermix engineconfiguration).- Aeroplane must be operated as perAFMS MODE00291_AFMS1 rev 3 or later.Prior to installation of this change/repair it must be determined thatthe interrelat...	20/11/2020	Active	10072320
10072321	Q.C.M. DESIGN GmbH			FALCON 7X	Removal of A/C Cabin & Lav AshtraysAs smoking is not permitted on the aircraft, all the ashtrays currentlyinstalled on the passenger cabin and lavatory are removed.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-25 25.1; 25.21;25.23; 25.25; 25.27; 25.29; 25.791; 25.853;25.854; 25.1529; 25.1541;25.1581; CS 25 Appendix H H25.1; H2...	- AFM DF8X-QCM25-001-M1-AFM Rev. 00- MDL DF8X-QCM25-001 Rev. 00- ICA DF8X-QCM25-001-M1-ICAor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/01/2020	Active	10072321

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072325	MAP AIRCRAFT PART 21 AS			737-800	Stanchion Litter System & Oxygen Module Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-01/10053133 Medical Evacuation.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the prod...	Master Drawing MAP120A101 Issue E dated 15.01.2020Flight Manual Supplement MAP120FMS Issue E dated 20.11.2019Instructions for Continued Airworthiness MAP120E201 Issue B dated10.01.2019or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	- Per Flight Manual Supplement MAP120FMS- Per Instructions for Continued Airworthiness MAP120E201- Minor Change MAP 119is a pre-requisite for this STCPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	31/01/2020	Active	10072325
10072326	UNICAL AERO INC.		FAA ST02710LA	A321-272NX A321-253N/-271N/-272N/-251NX A321-252NX/-253NX/-271NX A321-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-271N/-272N/-273N A320-233/-251N/-252N/-253N A320-211/-212/-214/-216/-232 A319-131/-132/-133/-151N/-171N A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122/-231	Installation of Unical Aero USB-PED Charging System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List referenced on the Approved Model List (AML) No.ST02710LA dated 24 September 2019ICA 18-002 Rev IR dated 04 March 2019or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral A...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/01/2020	Active	10072326
10072329	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	MBB-BK117 D-2	Title: Additional external landing lightsDescription: Four additional LED Landing Lights are introduced to theundersideof the helicopter; one on the forward landing gear and threeon the rear landing gear. These are to afford a larger poolof light forlandings at the request of the operator and area...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	EASA approved documents:-Flight Manual Supplement, DocumentNumber AHUK/ 145-FMS-112-Airworthiness Limitations Section, Section 2.0 of Instructions forContinued Airworthiness, Document Number ICA/1453255-01, Issue/RevisionC dated 29 January2020EASA accepted documents:-Instructions for Continued Airw...	The additional landing lights introduced by this Change areonlycertified as optional/ additional lights to the minimum required andcertified landing lights.The additional landing lights introduced by this Change will requireassessment prior to NVIS approval/operations.The additional landing lights i...	31/01/2020	Active	10072329
10072331	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		A340-642	A340-600 LOPA InstallationRev 1: Transfer of STC from GVH Aerospace Ltd - United Kingdom, to GVHAerospace (Ireland) Limited	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- GVH Aerospace Instructions for Continued Airworthiness No.GVH-10621-01-ICA-01 Issue 1- GVH Aerospace Master Data ListNo. GVH-10621-01-MDL-01 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	EASA STC 10055080 is a pre-requisite for this modification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the prod...	26/01/2021	Active	10072331
10072343	AIRBUS HELICOPTERS, Inc.		FAA STC SR09511DS	EC 130 T2 EC 130 B4 AS 350 B3 AS 350 B2	Installation of LED Taxi and Landing Lights with Optional Pulse	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR09511DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	For AS350B2 and B3 models:- Instructions for Continued Airworthiness 350MMS-044 Rev. A dated 12December 2019, or later ODA or AEG accepted revision;- Rotorcraft Flight Manual Supplement 350FMS-550 Rev. IR dated 12December 2019, or later ODA approved revision.For EC 130T2 and B4 models:- Instructions...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/02/2020	Active	10072343

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072345	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA ST02621LA	737-600/-700/-800/-900/-900ER	Modification to the existing Mode S Transponder system and optionalreplacement of ATC/TCAS Control Panel to add NEXTGENADS-B Out.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Aviation Communication & Surveillance Systems Index of Master DataLists, Drawing No. 8916737, Revision '-' dated 2 November 2016, or laterFAA approved revision. ,,2. Instructions for Continued Airworthiness (ICA) and Airplane FlightManual Supplement (AFMS) are called out in the corresponding FAAA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/02/2020	Active	10072345
10072363	NORTHWEST AEROSPACE TECHNOLOGIESINC.			787-8	Replacement of in-seat IFE components.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Summary, Northwest Aerospace Technologies, Inc. documentN0650-D90, Revision -Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. documentN0650-D70, Revision -or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	The pre-mod cabin layout is not EASA approved, the interfaces aredefined in the document N0650-D01. Additional EASA review of the entirecabin and approval is required to register the aircraft in the EU.This approval is limited to the approval of seat modifications definedin the NAT N0650-D10 MasterI...	04/02/2020	Active	10072363
10072378	S-TEC CORPORATION		FAA SA09756DS	100, A100, A100A, B100	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List No. ST-968-MDL-0001, Revision A, dated 12.11.2019Airplane Flight Manual Supplement, ST-968-AFMS-0001, Revision -, dated18.11.2019Instruction for Continued Airworthiness, ST-968-ICA-0001, Revision -,dated 06.03.2019or laterrevisions of the above listed document(s) approved/ acceptedb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/02/2020	Active	10072378
10072379	S-TEC CORPORATION	REV. 1	FAA SA09755DS	B95A, D55, D55A, D95A, E55 95-B55B, 95-C55, 95-C55A 95-B55A, B95, E55A, E95 95-55, 95-A55, 95-B55 58P, 58PA, 58TC, 58TCA 56TC, A56TC, 58, 58A, 95	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)Revision 1 corrects a model designation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List No. ST-964-MDL-0001, Revision A, dated 04.09.2019Airplane Flight Manual Supplement, ST-964-AFMS-0001, Revision -, dated11.09.2019Instruction for Continued Airworthiness, ST-964-ICA-0001, Revision -,dated 21.08.2019or laterrevisions of the above listed document(s) approved/ acceptedb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/02/2020	Active	10072379
10072466	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		DORNIER 328-300 DORNIER 328-100	ADS-B UPGRADEUpgrade of existing dual MODE-S Transponder system with ADS-Bfunctionality in order to comply with operational requirements inCOMMISSION REGULATION (EU) No 1207/2011 amended by COMMISSION REGULATION(EU) No 1028/2014.Rev. 1: Alternative location for GPS antenna feed thru connector.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25 Amdt 2. CS 25.1,CS 25.29, CS 25.251, CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS25.337, CS 25.341, C...	Engineering Order, Ref. 2118360-EO, Is. 6, Date: 14.11.2024andCertification Documents, Ref. 2118360 DOC, Is. 6, Date: 18.11.2024.AFM Supplement, Ref. 2118360-AM, Is. 4, Date: 14.08.2023.ICA document, Ref. 2118360-CA, Is. 5, Date: 02.07.2024.MMEL Supplement, Ref. 2118360-ME, Is. 1, Date: 09.01.2020....	Prior to installation of this change, aircraft configuration must complywith the configuration defined in section 4 of Engineering Order2118360-EO.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installede...	19/11/2024	Active	10072466

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072469	LUFTHANSA TECHNIK AG	REV. 1		A330-203	Eurowings A330 - Business Class InstallationThe modification of the Aircraft A330-200 is initiated by theinstallation of a new business class. The installation leads to a newlayout with 3 classes and the modification takes place mainly betweendoor 1 and door 3. The layout aft of door 3 remains uncha...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Supplemental Type Design Document: STDD25-19/26M Issue 1 Rev 0 dated06.Feb.2020- Instruction for Continued Airworthiness: A-00-20/10-ICA Issue 1 Rev 1dated 27.Jan.2020- Compliance Checklist: CCL25-19/26M Rev 2 dated 06.Feb.2020or later revisions of the above listed document(s) approved/acceptedund...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/02/2020	Active	10072469
10072539	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.			BD-700-1A11 BD-700-1A10	Installation of a Honeywell JetWave Satcom System with associatedKa-Band Radome	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-01 Vibration/ buffeting compliancecriteria for large external antenna installationThe requirements for environmental protection and the...	Approved:StandardAero Airplane Flight Manual Supplement No.1033377 Revision (C)dated 27 November 2019StandardAero Instructions for Continued Airworthiness No. 1033376,Revision (C) Airworthiness Limitations dated 11 June 2018Accepted:StandardAero Master Data List No. 1033284, Revision (D) dated 10De...	This STC requires prior embodiment of a T-PED STC, Service Bulletin orembodiment of EASA STC no. 10069212.Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no a...	14/02/2020	Active	10072539
10072545	AIRBUS S.A.S.			A330-243	Cabin Reconfiguration for WAMOS A330-200Changing the cabin configuration from 24B/C + 242Y/C seats to new layout20B/C +260Y/C seats. Modification and adaptation of the relatedmonuments and Aircraft passenger systems.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Summary Report AIS-AJA-19026 issue 04 dated12th Feb2020 <(>&<)>MAS AI0136 issue 01 dated 12th Feb 2020or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/02/2020	Active	10072545
10072552	ASI AVIATION			B300	SURPOLMAR MCA	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Master Data List ref. DL n° 047 Rev. 02 dated 29.01.2020Operation in accordance with Aircraft Flight Manual Supplement Ref.POH-350-959000 Rev. 02 dated 29.01.2020Maintain in accordance with Beechcraft Corporation approved ICA documentRef. 130-590031-539, Original Issue, dated 01.05.2015 for increase...	Changes to the individual aircraft Airworthiness Limitations will needto be EASA Approved.Aircraft with Increased MTOW of 17,500 lb are eligible only for aRestricted Category Certificate of Airworthiness.	17/02/2020	Active	10072552
10072563	URBE AERO GmbH			525C 525B 525A 525	Garmin GTX3000 TransponderInstallation of 2 Garmin GTX3000 Mode S Transponders as a replacementfor the original Transponders and approval for 1090MHz Extended SquitterADS-B per CS-ACNS Issue 2.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 23.29, 23.301, 23.305,23.1301, 23.1306, 23.1308, 23.1309, 23.1322, 23.1327, 23.1351, 23.1357,23.1365, 23.1431, 23.1529, 23...	- Installation in accordance with Engineering Order doc: DOE / F 07,Project No. 219, Issue 01- Operation in accordance with Supplement to the Airplane Flight Manual,Doc. No.AFM-219-01, Date of Issue 03-Feb-2020- Maintenance and Instructions for Continued Airworthiness in accordancewithDoc. No. AMM-2...	The approval holder shall fulfill the obligations of Part 21, Point21A.109.	19/02/2020	Active	10072563

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072564	RAISBECK ENGINEERING Inc.		FAA STC SA01454CH	C90GTI C90GT C90A	Installation of Butterfield Industries Oil Residue Collection System,kit Part Number BI 8030-1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Installation Data Package BI 8020<(>,<)> Revision D, dated 1 March2011, or later Federal Aviation Administration (FAA) approved revisions. 2. Drawing List BI 8015, Revision E, dated 4 November 2013, or laterFederal Aviation Administration (FAA) approved revisions.3. The Instructions for ContinuedR...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/02/2020	Active	10072564
10072571	ZIMEX AVIATION Ltd.	REV. 1	FOCA Z 27-50-03	DHC-6 SERIES 400 DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300 DHC-6 SERIES 210 DHC-6 SERIES 200 DHC-6 SERIES 110 DHC-6 SERIES 100 DHC-6 SERIES 1	DHC 6 Flap rollersThis installation reduces the erosion of the flaps rods by reducing thevibration of these rods in their supports. Improvement is due to the useof a new support roller material and a change of the installationprocedure (reduced gap control).Rev. 1: Minor Changes to FOCA STC No. Z 27...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CAR Part 3, dated May1956, including amendments 3-1 to 3-8Therequirements for environmental protection and the associated...	in accordance with Zimex drawing N° ZIM 1015-98Applicable design drawings: in accordance with Zimex drawing N° ZIM1015-98Required Manuals: Installation handbook Zimex Doc. N° 60202Rev. 1: Zimex Wing Flap System Drawing No. ZIM1015-98, Rev.1<(>,<)>- Installation Instruction Handbook for STC No Z 27-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/02/2020	Active	10072571
10072573	RHEINLAND AIR SERVICE GmbH	REV. 3		K-1200	Installation of Garmin G500H TXi and GTN650H SystemThis installation combines the installation of Garmin G500H TXi, GTN650Hand several supporting equipment such as GNC225A, GMA350H and GTX345.This installation is for use in VFR day and night operation.Rev. 1: Revision of the certification basis - ad...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): ADS-B Out Extended Squitter & ELS Installation (MajorChange) and its compliance to CS-ACNS.- The following paragraph(s) at a later amendment:CS-27 Amdt. 4A...	EASA approved documents:- Rotorcraft Flight Manual Supplement PO-2157-000000, Issue 1-1, dated14 February 2020- Airworthiness Limitations Section, Chapter 2 of Maintenance ManualSupplement, MM-2157-000000, Issue 4, dated 14 February 2020EASA accepted documents:- Description of Modification, DE-2157-...	Prior to the installation of this change/repair it must be determinedthat the interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverse uponthe airworthiness of the product.	23/07/2025	Active	10072573
10072578	MAMMOTH FREIGHTERS, LLC.	REV. 1	FAA ST03592NY	737-800, 737-900 737-600, 737-700	Installation of a Strut Data Collection System (SDCS)Rev. 1: Transfer from "Delta Engineering Corporation" to "MammothFreighters, LLC."	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25.981 at amdt. 4.The requirements for environmental protection and the associatedcertified noise and/ or emissions leve...	AviX Aero Master Data List 0106-10706-2449 Revision A dated25/06/2019Instruction for Continued Airworthiness 0706-10713-2449 Revision A dated25/06/2019or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.,,	18/07/2024	Active	10072578
10072588	DELTA ENGINEERING CORPORATION		FAA STC ST04082NY	SEE FAA AML -600/700/800/900/900ER/-8/-9	Installation of Aircraft Tracking Solutions Autonomous Distress Tracking(ADT) System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments. The requirements for environmental protection and theassociated certified noise and/ oremissions levels of the originalproduct are unchanged and re...	Delta Engineering Approved Model List 0198-10598-2495, Revision B, dated14 October 2019 or later FAA approved revisionsto Delta EngineeringApproved Model List previously listed. The Instructions for ContinuedAirworthiness as listed on theApproved Model List are required.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	26/02/2020	Active	10072588

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072589	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01459WI-D	SEE FAA APPROVED MODEL LIST	Rockwell Collins DLM-900 ACARS CORE Software UpgradeRevision 1 is a correction of typographical errors.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Collins Drawing Index as listed on AML No. ST01459WI-D, revised 26August 2014, or later FAA approved amendment.	Prior installation and approval of a Collins DLM-900 ACARS is required.This STC is valid for aircraft types and models approved by EASA andlisted on the FAA Approved Model List ST01459WI-D, Revision A revised 26August 2014 or later approved revisions.A copy of this Certificate and FAA Approved Model...	06/03/2020	Active	10072589
10072590	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE			A321-271N/-271NX/-272N /-272NX A321-252NX/ -253N/ -253NX A321-251N/ -251NX/-252N/ A321-212/ -213/ -231/ -232 A321-111/ -112/ -131/ -211 A320-271N/ -272N/ -273N A320-251N/ -252N/ -253N A320-216/ -231/ -232/ -233 A320-211/ -212/ -214/ -215 A319-151N/ -153N/ -171N A319-115/ -131/ -132/ -133 A319-111/ -112/ -113/ -114 A318-111/ -112/ -121/ -122	Installation of a Wireless In-Flight Entertainment (IFE) System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Armstrong Aerospace Master Data List, Doc. No. DC104-8098-00,Revision C, dated 29 May 2018, or later FAA approved revision.2. FAA Approved Airplane Flight Manual Supplement, Armstrong AerospaceDoc. No. DC303-8098-00, Revision A, approved 8 June 2018< (>,<)> or laterFAA approved revision.	Modification in accordance with this STC requires that the aircraft beshown to be electromagnetically compatible with transmitting portableelectronic devices that utilize wirelessdata technologies.This system is intended to provide internet connection and emailservices using portable electronic dev...	26/02/2020	Active	10072590
10072596	EICHELSDOERFER GmbHFLUGZEUGBAU			ASW 27	ASW 27 – installation of a turbojet engineInstallation of the Draline PSR T01 (EASA.E.108) turbojet engine to thesailplane ASW 27 in accordance with Eichelsdörfer Flugzeugbau documentASW 27 STC PSR DL, at revision 7, dated July 21, 2019;CS-34.1 Fuel Venting has been demonstrated as part of EASA.E.10...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): 22.975, 22.977The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unc...	Operation in accordance with Aircraft Flight Manual Supplement,Eichelsdörfer Flugzeugbau document ASW 27 STC PSR FL, atrevision 4,dated September 09, 2018;Airworthiness Limitations as per Instruction for ContinuingAirworthiness SupplementChapter 4, Eichelsdörfer Flugzeugbau documentASW 27 STC PSRo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/02/2020	Active	10072596
10072601	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1		AT-802, AT-802A AT-802A AT-802	MTV-27-( ) on AT-802 Series	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- According to MT-Propeller Master Documentation List No. E-3519, Rev 4- To be operated in accordance with MT-PropellerAFM-S Document No.E-3521, Rev 3- To be installed i.a.w. Installation Instructions Doc. No. E-3522, Rev0- To be maintained i.a.w. Instruction for continued airworthiness Doc.No. E-3...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	26/07/2021	Active	10072601
10072602	FOKKER SERVICES B.V.			737-500 737-400 737-300	ADS-B Out on the Boeing 737 classicThis change introduces ADS-B out capability on the 737 classic. The ATCTransponders will be changed and they will interface with the GNSSposition source. The sensor may be a stand-alone sensor that is notcoupled to the FMS.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.the following paragraph (s) at a later amendment: Initial issue of CSACNS.D.AC.010, CS ACNS.D.AC.015, CS ACNS.D.AC.020, CS ACNS.D.AC.025, CSACNS.D.AC.030, CS ACNS.D.AC.035, CS ACNS.D.AC.040, CS ACNS....	The change is defined through issue 1 of MDL documentB737-ADSB-OUT-MDL-0002.The aircraft shall be operated in accordance with issue 1 of AirplaneFlight Manual Supplement document B737-ADSB-AFM-S-002.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/02/2020	Active	10072602

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072642	SIRIUM AEROTECH S.L.			A310-325 A310-324 A310-322 A310-308 A310-304 A310-222 A310-221 A310-204 A310-203 C A310-203 A300 F4-622 R A300 F4-605 R A300 F4-203 A300 C4-620 A300 C4-605 R VARIANT F A300 C4-203 A300 B4-622 R A300 B4-622 A300 B4-620 A300 B4-605 R A300 B4-603 A300 B4-601 A300 B4-2C A300 B4-220 A300 B4-203 A300 B4-120 A300 B4-103 A300 B4-102 A300 B2K-3C A300 B2-320 A300 B2-203 A300 B2-202 A300 B2-1C A300 B2-1A A300 B1	New Supplement to AFM for ADS-B Upgrade in Airbus A300/310 Airplanes	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Section 4 of CS-ACNS Subpart D Issue 2 for ADS-B OUT ApprovalsThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	-Master Data List SA19-69S-MDL Rev02-AFM Supplement SA19-69S-AFMS Rev02- Instructions for Continuous Airworthiness SA19-69S-AMMS Rev 00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limitations as per:- AFM Supplement SA19-69S-AFMS Rev02- Instructions for Continuous Airworthiness SA19-69S-AMMS Rev00Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will in...	03/03/2020	Active	10072642
10072643	S4A SOLUTIONS FOR AVIATION, S.L			550 500	ADS-B OUT INSTALLATION (according to CS ACNS Issue 2)	Certification basis for this design change are the originalcertification basis, as defined by the type certificate<(>,<)>-amended by the following CS25 Amendment 23 paragraphs:25.1, 25.21, 25.23, 25.25, 25.27, 25.251, 25.301, 25.303, 25.305,25.307, 25.321, 25.337, 25.561, 25.571, 25.581, 25.601, 25....	Modification in accordance with Master Document List, 50010-RPT02 Ed 2Operation in accordance with Flight Manual Supplement, 50010-HDK01 Ed 2Instructions for continued airworthiness in accordance with MaintenanceManual Supplement, 50010-HDK02 Ed 1or later revisions of the above listed document(s) ap...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/03/2020	Active	10072643
10072649	AVIONIK STRAUBING ENTWICKLUNGS GmbH			C90A, C90GT, C90GTI	Installation of either single or dual Garmin GA58 antennas.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Avionik Straubing GmbH Instructions forInstallation Doc. No: ASR-2019-074-IFI-10-00, Revision 00, date19/11/19.Instructions for Continued Airworthiness in accordance with AvionikStraubing GmbH Doc No: ASR-2019-074-ICA-11-00 Revision 00, date 31/01/20or later revisions...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/03/2020	Active	10072649

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072650	BOMBARDIER Inc.	REV. 1		BD-700-2A12	Installation of Emergency Vision Assurance System (EVAS)Rev. 1: Update of the STC holder address.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Modification Data Summary, Bombardier Inc. document No. RAZ-BM700-168,Revision NC,dated 29 November 2019Instructions for Continued Airworthiness, Bombardier Inc. document No.EVS256800-ICA, Revision 2,dated 22 November 2019Aircraft Flight Manual Supplement, Bombardier Inc. document No.GCA-250002 Revi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/04/2023	Active	10072650
10072655	TUI AIRLINES BELGIUM N.V.			767-300	Installation of a wireless IFE system on B767-300 (Change NumberJAF-STC-0003-0001 R00)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs at a later amendment: CS 25 at amdt. 12 for25.29, 25.301(a)(b) , 25.303, 25.305(a)(b), 25.307(a), 25.321, 25.341,25.365(a)(b) (d)(g), 25.471(a),2...	- Certification Plan ref. JAF-DOA-CP-44M-0004 R07, dated 25/11/2019- AFM Supplement ref. AFMS-JAF-DOA-44M-0004 R00, dated 16/09/2019- ICA Report JAF-DOA-ICAR-44M-0004 R00, dated 10/12/2019- MDL ref. JAF-STC -0003-0001 R00or later revisions of the above listed document(s) approved/acceptedunder the...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/03/2020	Active	10072655
10072663	SEBALD LUFTFAHRTTECHNISCHER BETRIEB(LTB)			SEE EASA APPROVED MODEL LIST	TM S04 Dynamic balancingDynamic balancing of a retractable propulsion system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	TM-S04 Auswuchten von Klapptriebwerken, Ausgabe 02.07.2019<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	04/03/2020	Active	10072663
10072666	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED		CAA UK RESPONSIBILITY	AB139, AW139	Martin Baker Rotating Seat InstallationThis STC installs a Martin Baker Rotating and Traversing CrashworthySeat (P/N MBCS6930) into the cabin of the AB/AW139 helicopter models.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Compliance Plan/ Checklist CCL/163-003 Issue 2- Flight Manual Supplement FMS/163-007 Issue 3- Master Data List MDL/163-011 Issue 3- Drawing List DL/163-099 Issue 3- Instructions for Continued Airworthiness ICA/163-004 Issue 2- Role ChangeInstructions RCI/ 163-010 Issue 2or later revisions of the ab...	The Leonardo Helicopters Removable Floor Panel P/N 3P5332A00112 is aprerequisite for the installation of this STC.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introd...	04/03/2020	Active	10072666
10072679	AVIATECH & CONSULTING, SOCIEDADLIMITADA	REV. 1		S2R-T660	Installation of Computerized FiregatesInstallation of computerized firegates, used and approved already onAirTractor 502 and 802 Series under STC EASA 10054617, with an adapterforthe hopper of the S2R-T660Rev. 1: Transfer from TRABAJOS AEREOS ESPEJO S.L. to AVIATECH &CONSULTING SOCIEDAD LIMITADA	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1) Master Drawing List MDL01-18 Rev. 0, Fecha: 30/09/2019.2) Boletín de Ingeniería – Instrucciones de Instalación yAeronavegabilidad Continuada BI01-18 Rev. 1, Fecha: 30/09/2019.3) Suplemento al Manual de Vuelo SMV01-18 R1, Fecha: 30/09/2019.or later revisions of the above listed document(s) approve...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/02/2022	Active	10072679

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072690	AEROMECH Inc.	REV. 1		1900D	Installation of Garmin G950 Integrated Avionics and DisplaySystemRev. 1 corrects a typo in AFM supplement reference.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:FAR 23 amdt. 34: 23.1, 23.207(b), 23.251, 23.301, 23.303, 23.305,23.307, 23.333, 23.337, 23.341, 23.365(a)(b)(c)(d), 23.5...	Installation in accordance with Master Document List (MDL),documentAM0203-DL02-00 Revision G,dated 6 August 2018.Maintenance in accordance with Instructions for Continued Airworthiness(ICA), document AM0203-IC01-00 Revision G, dated 20 December 2017.Operation in accordance with Airplane Flight Manu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/03/2023	Active	10072690
10072708	DIAMOND AIRCRAFT INDUSTRIES Inc.		TCCA SA06-52	DA 40	Installation of MTV-12-B/183-59b Propeller	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase and/or emission levels.	Installation in accordance with Diamond Aircraft IndustriesInc. Drawing C41-RDC-001, Rev A dated 09 August 2006 and C41-MDL-001, Rev A dated09 August 2006.Operation in accordance with Diamond Air Industries Inc. AFMS6.01.01-CS0601 (E), Rev IR approved 10 August 2006.Maintenance in accordance with4...	FAA STC SA03281AT must be installed with this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduceno adverseeffect upon the airworthiness of the product.	09/03/2020	Active	10072708
10072732	AAR AIRCRAFT SERVICES		FAA STC ST03096CH	737-800	Installation of Center Overhead Life Raft Stowage Compartments	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmental protectionand the associated certified noise and/ or emissions levels of theoriginal product are unchanged and remain applicable to thiscertificate/ approval.	AAR Aircraft Services Master Data List 1001802R02, RevisionD, dated 25April 2012.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/03/2020	Active	10072732
10072739	COMTECH GLOBAL AVIATION SERVICES S.			A330-342,A330-343 A330-322,A330-323,A330-341 A330-302,A330-303,A330-321 A330-223,A330-243,A330-301 A330-201,A330-202,A330-203	Introduction of PAX. E/C Seat CushionsThis modification replaces the bottom cushions of Weber Seats Model 5750series with bottom cushion P/N 864984-401CTG, maintaining the existingdress cover fabric materials.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	CTG-MS5045-330 MODIFICATION SUMMARY Initial Release 21/02/2020Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Comtech bottom seat cushions P/N: 864984-401CTG are not approved forinstallation in front row seats. Original seat manufacturer installationlimitations remain applicable after installing the Comtech bottom seatcushion P/N: 864984- 401CTG.	12/03/2020	Active	10072739
10072740	COMTECH GLOBAL AVIATION SERVICES S.			A380-861 A380-842 A380-841	Introduction of PAX. E/C Seat CushionsThis modification replaces the bottom cushions of Weber Seats Model 5750series with bottom cushion P/N 864984-401CTG, maintaining the existingdress cover fabric materials.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	CTG-MS5046-380 MODIFICATION SUMMARY Initial Release 21/02/2020Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Comtech bottom seat cushions P/N: 864984-401CTG are not approved forinstallation in front row seats. Original seat manufacturer installationlimitations remain applicable after installing the Comtech bottom seatcushion P/N: 864984-401CTG.	12/03/2020	Active	10072740
10072752 (03/1981/SVTO (ENAC))	SMART ELICOTTERI S.P.A.	REV. 2		PA-31T (CHEYENNE/ CHEYENNE II)	KIT CGA-04 for PA-31T S/N 31T-7620005Revision 2: Transfer of STC to SMART Elicotteri	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Drawing List Kit Doc. P00500-MDL-01-00 dated 23/04/2019- Master Document List Doc. P00500-MDocL-01-00 dated 25/06/2019- AFMS Doc. P00500-AFM-01-00 dated 12/2/2020Or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	Applicable to PA-31T S/N 31T-7620005 only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	02/07/2020	Active	10072752

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072765	AERODISA S.L.			B300	AFM SBAS procedures for the B300 series.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The applicable Sections of CS-ACNS Issue 2, Subpart C, for RNAV/ RNPApprovals.Including LPV Approaches.The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	-Master Data List AED2016-40M-MDL Rev, A0-AFM Supplement AED2016-40M-AFMS Rev A0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limitations as per:- This EASA Design Approval must be limited to the Airplane Model B300<(>,<)> MSN FL-255Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce noe...	12/03/2020	Active	10072765
10072771	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 2		680A (LATITUDE)	Approval of UNIFIS 3000 System Installation in accordance withScandinavian Avionics Modification 2110369.Revision.2 of this STC Includes VHF COMM Extended Frequency Range.Configuration enablement of extended frequency range on VHF COMMsystems, equipment prior installed.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Modification in accordance with Scandinavian Avionics Engineering Orderref 2110369-EO Issue 2, dated 12.11.2020 and Master Document List ref2110369 DOC Issue 2 dated 12.11.2020.Operate in accordance with Scandinavian Avionics Flight ManualSupplements ref 2110369-AM (), as defined in Master document2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/11/2020	Active	10072771
10072772	SCANDINAVIAN AVIONICS DESIGN ApS			680A (LATITUDE)	Approval of Aircraft Audio System Modification in accordance withScandinavian Avionics Modification 2113232.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 Amendment 2,except following:Paras 25.29, . 301, .303, .305(a)(b)(c)(e), .307, . 321, 335,.337, .341,.365, .571, . 581,...	Installation in accordance with Scandinavian Avionics Engineering Orderref 2113232-EO Iss 1, dated 06.03.2020 and Master Document List ref2113232 DOC Iss 1 dated 06.03.2020.Operate in accordance with Scandinavian Avionics Flight ManualSupplement ref 2113232-AM A Iss 2, dated 11.12.2019.Instructionsi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/03/2020	Active	10072772
10072820	EMBRAER ENGINEERING & TECHNOLOGYCE NTER USA, INC.		FAA STC SA04471AT	EMB-500	Installation of a Tire Pressure Sensing Kit.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04471AT.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- Master Data List (MDL) 17007-001, Rev. -, dated 21 November 2018.- Instructions for Continued Airworthiness (ICA), Document ICA17007-030, Rev. -, dated 21 November 2018.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/03/2020	Active	10072820
10072821	IKHANA GROUP, LLC	REV. 2	FAA STC SA02556LA	DHC-6 SERIES 400 DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300 DHC-6 SERIES 210 DHC-6 SERIES 200 DHC-6 SERIES 110 DHC-6 SERIES 100 DHC-6-100/-200/-300/-400	Installation of Passenger Utility SeatsRev. 1: Name Change from "Ikhana Group Inc." to "Ikhana Group LLC."	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02556LA.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- IKHANA Aircraft Services Utility Seat Installation Drawing No.SU00-0011, Revision A, dated 2 December 2015.- Design Approval of Passenger Utility Seats per IKHANA AircraftServices Master Drawing List, Document No. ER354-1090, Revision A,dated3 December 2015.- IKHANA Aircraft Services Instructions...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	09/09/2021	Active	10072821
10072822	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		EMB-505	ADS-B approval. Exchange of existing single/dual ACSS RCS-852 forsingle/dual Garmin GTX3000 using existing transponder antennas.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS-23 Amendment 4:23.29; 251; 301; 303; 305; 307; 337; 561; 601; 603; 605; 607; 609; 611;613; 619; 625; 771; 773; 863; 867;...	Installation, Operation and Maintenance according to Avionic StraubingMaster Documents List ASR-2019-073-MDL-01-00, revision 00, dated 27February 2020.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to Embraer EMB-505 aeroplanes which are factory equipped withsingle/dual ACSS RCZ-852 and a Garmin G1000 or Garmin G3000 Flight Deck.The Garmin G1000 Flight Deck must be configured with G1000 Load 83.25 ora higher version.The Garmin G3000 Flight Deck must be configured with G3000 Load 13.25a...	24/03/2020	Active	10072822

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072824	SIRIUM AEROTECH S.L.			S550 560XL 560 550 500	New Supplement to the EASA AFM for RNAV 1 Approval	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The applicable Sections of CS-ACNS Issue 2 for RNAV 1 ApprovalThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	-Master Data List SA19-83S-MDL Rev 00-AFM Supplement SA19-83S-AFMS Rev 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limitations as per:- AFM Supplement SA19-83S-AFMS Rev 00Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product...	16/03/2020	Active	10072824
10072827	E A D AEROSPACE AIRWORTHINESS			SEE EASA APPROVED MODEL LIST	KA-BAND SATCOM-Skirt - Instructions for Continued AirworthinessInstructions developed after composite material test results performed.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Certification Program ref. 01599-EAS-A-CPM-01, Rev B (13 March 2020)-MDL ref. 01599-EAS-A-MDL, rev B (13 March 2020)- ICA Supplement for A340 ref.01501-EAS-A-ICA-01, rev H (13 March 2020)- ICA Supplement for 777 ref. 01523-EAS-A-ICA-01,rev M (13 March 2020)- ICA Supplement for 747 ref. 01536-EAS...	The ICA generated in the frame of this approval supersede the onesgenerated for STCs 10067270 rev 1 (on B747), 10062160Rev 3 (on B777), 10063487 rev 1 (on A340), and 10065550 Rev 2 (on A330/ A340) approvals.Prior to installation of this change/repair it must be determined thatthe interrelationship be...	17/03/2020	Active	10072827
10072830	S-TEC CORPORATION	REV. 1	FAA STC SA09757DS	B200, B200C, B200CT, B200T A100-1, A200, A200CT, A200C 200, 200C, 200CT, 200T	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09757DS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Data List No. ST-976-MDL-0001, Revision A, dated 22 January 2020.Flight Manual Supplement, ST-976-AFMS-0001, Revision -, dated 23 January2020.Instructions for Continued Airworthiness, ST-976-ICA-0001, Revision -,dated 21 January 2020.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	19/03/2020	Active	10072830
10072831	ALAMO ENGINEERING GmbH	REV. 2		EMB-135BJ	PM-CPDLC with MKII+ CMU and VDR UpgradeModification of FANS1/A+ equipped aircraft to add PM-CPDLC (ATNB1)capability.Rev. 2: transfers the STC from "Deutsche Aircraft GmbH" to "AlamoEngineering GmbH".	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI-F01 Flight Recorders and Data Link Recordingat Issue 3.- CS-ACNS, Issue 2.The requirements for environmental protection and the associatedcerti...	Master Document List MDL168Z001, Issue AAirplane OperationsManual Supplement AOMS014M232Z0001, Rev. AAirplane Maintenance Manual Supplement AMMS014M232Z0001, Issue Bor later revisions of the above listed document (s) approved/ acceptedunderthe EASA system.	328SSG Minor OSD Change Approval DC-14M168Z0002 is a required elementfor this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the ai...	18/12/2023	Active	10072831
10072832	ACC COLUMBIA Jet Service GmbH	REV. 3		690C	RC 690C Camera Lift InstallationRev. 0: Installation and operation of a gimbal camera lift withinaircraft cabin.Rev. 1:Transfer to ACC Columbia Jet Service GmbHRev. 2: Typo in company nameRev. 3: RC690 Camera Lift Installation [Revised Operational Limitations]– Installation and operation of gimbalO...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: - FAR-23 Amd 0: 23.21,23.303, 23.305, 23.307, 23.321, 23.365, 23.601, 23.627, 23.843, 23.1367,23.1431; - FAR-...	-Installed in accordance with installation instruction document numberII_2051502_rev6, Revision 6, Dated 19th July 2022.-Operated in accordance with flight manual supplement document numberSPOH_2051502_rev4, Revision 4 Dated 19th July 2022.Maintained in accordance with Maintenance Manual Supplementi...	- Aircraft build standard is Twin Commander RC690 C as described in FAATCDS 2A4.- Maximum altitude with camera lift deployed is FL 100<(>,<)>- Maximum occupants 4 (four) persons [Pilot, Co-pilot plus two personsor Pilot plus three persons]<(>,<)>- Maximum camera mass, 50 kg.The following pre-requisi...	03/08/2022	Active	10072832

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072845	AEROSERVIS, S.R.O.			L 410 UVP-E, L 410 UVP-E9, L 410 UVP-E20 L 410 UVP-E	STC-23: Inst. of PWC PT6A-42 EngineInstallation of PWC PT6A-42 engine, AV-725 propeller and relatedaccessories	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-01The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to thist...	-Master Document List, AE130000X, Rev. P, dated 13.2.2020-Compliance Checklist, AE130016P, Rev. K, dated 20.1.2020-Definiční document, AE130001P, Rev. N, 30.1.2020or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	18/03/2020	Active	10072845
10072849	BOGGI AERONAUTICS S.R.L.			P92-JS P92-J	Smartbay installation on aircraft P92	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	- Certification Program doc. n. P92P00100-Cpr-05, issue 5, dated03.03.2020;- Compliance Check List doc. n.P92P00100-CCL-03, issue 3 dated03.03.2020;- Master Drawing List doc. n. P92P00100-Mdl-01, issue 1 dated27.01.2020;- Flight Manual Supplement doc. n. P92P00100-FMS-02 issue 2;- ICA doc. n.P92P001...	The STC is applicable only on P92-JS model.	19/03/2020	Active	10072849
10072867	BELL TEXTRON, Inc.		FAA STC SH1385SO	206L-1, 206L-3, 206L-4 206A, 206B, 206L	Installation of a cargo viewing mirror	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SH1385SO.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	Aeronautical Accessories< (>,<)> Inc., Report KR-198, Rev. A, dated 6July 1982, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/03/2020	Active	10072867
10072884	HELI AUSTRIA GmbH			AS 355 F2 AS 355 F1	Title: Installation of a G500H flight DeckDescription: Purpose of this change is to replace the originalanalog-type flight and navigation instruments by a digital Garmin G500HPFD/MFD (Primary Flight Display / Multi Function Display) systemand toreplace the existing NAV1 receiver and COM 1transceive...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F01, Lithium battery installationsThe following paragraph(s) at a later amendment: CS-ACNS Initial Issue:CS ACNS.A.GEN.010, CS ACNS.B.VCS.001, CS...	Master Document List (MDL), HAU-D-049-001, Rev. 0Installation Manual, HAU-D-049-004, Rev. 0Flight Manual Supplement, HAU-D-049-005, Rev. 0Instructions for Continued Airworthiness,HAU-D-049-006, Rev. 0Or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Operation limited to VFR day and night. No IFR.Compatibility of the present STC with a flight director or an autopilotsystem requires further approval.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	27/03/2020	Active	10072884
10072889	FOKKER SERVICES B.V.			A321-231, A321-232 A321-212, A321-213 A321-131, A321-211 A321-111, A321-112 A320-232, A320-233 A320-216, A320-231 A320-214, A320-215 A320-211, A320-212 A319-132, A319-133 A319-115, A319-131 A319-113, A319-114 A319-111, A319-112	A320 Dual non-activated Stand-alone GNSSIntroduction of dual non-activated stand-alone GNSS antenna and receiverinstallation for Airbus A319/A320/ A321.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Certification Plan CP-0405 issue 4- Compliance Record Report CRR-0405 issue 1- Instructions for Continued Airworthiness supplement refA320-GNSS-ICA-001 issue 1or later revisionsof the above listed document (s) approved/ acceptedunder the EASA system.	As per the ICA Supplement this STC has an initial Limit of Validity of1200 FC or 2400 FH, whichever occurs first.Prior to embodiment of this STC on an aircraft it has to be ensuredthat:•,,The aircraft fuselage skin panels between Frames 25-26 and Stringers1-2 have nominal thickness of 1.2mm, and•,,T...	25/03/2020	Active	10072889
10072891	SKANDIA, INC		FAA STC SA04221CH	B300, B300C B200GT, B200T B200, B200C, B200CGT, B200CT A100-1, A200, A200C, A200CT 300, 300LW 200, 200C, 200CT, 200T	Installation of Thermal Acoustic Kit	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04221CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Skandia, Inc. Master Data List Document Number 7806034MDL001,Revision B, dated 9 May 2017, or later FAA approved revision.2. Instructions for Continued Airworthiness, Manual 7806034ICA001,Revision B, dated 10 July 2015, or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/03/2020	Active	10072891

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072893	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			737-800	Alternative Maximum Takeoff WeightModification of airplane maximum take-off weight to 78990 kg and ofmaximum landing weight to 66360 kg.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase and/or emission levels.	Certification Program MODE00269_CP Issue 5, dated 27 January 2020< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Applicable to Boeing 737-800 aeroplanes, equipped with winglets andCFM56-7B26E engines, AFM option code <986WS1>, having EASA STC 10071580or EASA STC 10071731 embodied- The aeroplane must be operated as per basic AFM D631A001.Prior to installation of this change/ repair it must be determined thatth...	26/03/2020	Active	10072893
10072895	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 2		A320-231/-232/-233 A320-211/-212/-214/-215/-216 A320-211	Airbus A320 – Introduction of GLU-925 MMRsRev. 1: Transfer of STCRev. 2: Applicability list extended to additional A320models	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ATL AFM Supplement: 13405-AFM-00001 Issue 5ATL ICA supplement: 13405-ICA-00001 Issue 1ATL MDL: MDL-13405-00001 Issue 5or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	GPS installation is not approved for navigation. This limitation is alsoextended to the broadcast of any of those data not demonstrated tofunction properly in a dynamic environment.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairp...	02/11/2022	Active	10072895
10072897	AEROSPACE DESIGN & COMPLIANCE LLC			SEE FAA AML	Installation of the KFC 230 Aerocruze Automatic Flight Control System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	(1) Aerospace Design & Compliance, LLC. Master Data List (MDL) 89800019-057, Rev IR, dated 10 July 2019, or later FAA approvedrevision.(2) Aerospace Design & Compliance, LLC. Instructions for ContinuedAirworthiness (ICA) 89800019-024, Rev IR, dated 5 July 2019, or laterFAA accepted revision. (3) Aeros...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	30/03/2020	Active	10072897
10072904	GULFSTREAM AEROSPACE CORPORATION		FAA ST03774AT-D	GULFSTREAM G150	Installation of a Rockwell Collins FMS-6100 Version 4.0 Upgrade inaccordance with Gulfstream AerospaceSTC No. ST03774AT-D.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Index List CEC11188001, Revision AFlight Manual Supplement CEC1118M002, Revision - Instructions for Continued Airworthiness, CEC1118A001, Revision Aor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ US...	Rockwell Collins GPS-4000S installation by STC ST01433WI-D (EASA10016518) is required.Rockwell Collins DBU-5000 installed by STC ST10327SC-D(EASA.IM.A.S. 02547) is required for serial numbers 201 thru 234, (DBU-5000 is existing in serial numbers 235 and subsequent by TypeCertificate).Prior to installa...	27/03/2020	Active	10072904

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072905	JETAIRE AEROSPACE, LLC			A321-232 A321-231/-232 A321-231 A321-213 A321-212 A321-211/-212/-213 A321-211 A321-131 A321-112 A321-111/-112/-131 A321-111 A320-233 A320-232 A320-231/-232/-233 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211/-212/-214/-215/-216 A320-211 A319-133 A319-132 A319-131/-132/-133 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111/-112/-113/-114/-115 A319-111	Invicta-Flammability Reduction System (FRS), installation of ignitionmitigation means in the Center Wing Tank.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 amdt. 15:25.307(a), 25.963(d)(e), 25.981(b), 25.1305(a), 25.1309 (b), 25.1501(c)The requirements for environmental pr...	Master Data List 13023C0012 Rev AAFM Supplement 13023S0001 Rev AInstructions for Continued Airworthiness 13023S0004 revAor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the TechnicalImplementationProcedures of EU/ USA Bilateral Agreement.	As per AFM Supplement, Flight Crew shall take into account the followingfor calculation of the airplane maximum range: fuel retention and fueldisplacement characteristics of Invicta reduce the usable fuel capacityof the Center Wing Tank byup to 42.9 US Gallons (or 287 lb or 130 kg,approximately 2%P...	27/03/2020	Active	10072905
10072906	GULFSTREAM AEROSPACE CORPORATION		FAA ST04208AT-D	GULFSTREAM 200/ GALAXY	Installation of a Rockwell Collins FMS-6100 Version 4.1 Upgrade inaccordance with Gulfstream AerospaceSTC No. ST04208AT-D.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Index List CEB11188003, Revision CFlight Manual Supplement CEB1118M005, Revision - Instructions for Continued Airworthiness, CEB1118A002, Revision IRor later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ U...	This STC is only applicable for SNs 052 & subsequent (Rockwell Collinsavionics equipped aircraft).Prior or concurrent installation of the Rockwell Collins GPS-4000SGlobal Positioning System by STC ST01433WI-D (EASA 10016518) isrequired.Upgrade of the DBU-4100 Data Base Unit to DBU-5000 status per Ro...	27/03/2020	Active	10072906
10072907	HONEYWELL INTERNATIONAL, Inc.		FAA STC SR02667SE	S-76A, S-76B, S-76C, S-76CD	Installation of a Honeywell ASPIRE 200 Intermediate Gain (IG) SATCOMSystem	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02667SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- Master Drawing List (MDL) MOD-S76ASPIRE200-5201, Revision-, dated 25September 2019, or later FAA approved revision.- Instructions for Continued Airworthiness (ICA) MODS76ASPIRE200-7601, Revision A, dated 24 July 2019, or later FAA accepted revision.- Rotorcraft Flight Manual Supplement (RFMS) MOD-...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/03/2020	Active	10072907
10072908	DART AEROSPACE USA, Inc.		FAA STC SR02676SE	MBB-BK117 D-2 MBB-BK117 C-2	Installation of Heavy Duty Wearplates	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02676SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- Installation Instructions IIN-D-145-1069, Revision A, dated 23 August2019, or later FAA approved revision.- Master Document List MDL-D145-1069, Revision B, dated 19 December2019, or later FAA approved revision.- Instructions for Continued Airworthiness ICA-D145-1069, Revision 0,dated 26 August 201...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	30/03/2020	Active	10072908

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072909	JAMCO AMERICA, INC.		FAA STC ST02643SE	A320-273N A320-271N, A320-272N A320-252N, A320-253N A320-232, A320-233, A320-251N, A320-215, A320-216, A320-231 A320-211, A320-212, A320-214, A320	Installation of FTS Cabin WiFi System on Airbus A320 Series	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS-25 Amdt. 4: 25.869(a)(1)(4)CS-25 Amdt. 23: 25.853(a), 25.899(a)(b), 25.1353 (a)The requirements for environmental protect...	Jamco America, Inc. Master Data List (MDL) 2618-2, RevisionA, dated 8January 2020, or later FAA approved revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.EASA STC 10072983 (FAA STC ST02642SE), Installat...	29/04/2020	Active	10072909
10072911	SCANDINAVIAN AVIONICS DESIGN ApS			L-410 UVP - TURBOLET L 410 UVP-LW L 410 UVP-E-LW L 410 UVP-E9 L 410 UVP-E20 CARGO L 410 UVP-E20 L-410 UVP-E	Approval of ADS-B & LPV Upgrades in accordance with ScandinavianAvionics Modification Ref 2121024.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Scandinavian Avionics Engineering Orderref 2121024-EO Iss 1, and Master Document List ref 2121024 DOC Iss 1dated 16.03.2020.Operate in accordance with Scandinavian Avionics Flight ManualSupplements ref 2121024-AM ( ), as defined in Master document List2121024 DOC Issl...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/03/2020	Active	10072911
10072928	3S CERTIFICATION, LLC	REV. 2	FAA ST01917WI	767-200, 767-300 767-200/-300/-300F 757-200, 757-300 757-200/-200PF/-300 737-300/-400/-500	LCD Display RetrofitThis STC installs the Thomas Global Systems (TGS) TFD-7066 (EADI)andTFD-7076 (EHSI/ EICAS) LCD displays as direct form, fit, and functionreplaceable units for the originally installed Rockwell CollinsInternational (RCI) EDU-766C/D (EADI) and EDU-776C/D (EHSI/EICAS) cathode ray tube...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 -§25.29(b); §25.333; §25.341; §25.561 (a)(b)(3)(c); §25.603; §25.605 (a);§25.613 ; §25.625(a)(b)(c); §25.853(a); §25....	- MDL Ref. 3S18-021-1001 Rev 9.0, dated 25 May 2022.- Certification Plan (PSCP) Ref. 3S18-021-1101 Rev 3.0< (>,<)>dated 4 March 2022.- Instructions for Continued Airworthiness Ref. 3S18-021-6101 Rev 3.0,dated 25 May 2022.- AML Ref. 3S18-021-1801 Rev. 5.0, dated 25 May 2022.or later revisions of the a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/10/2022	Active	10072928
10072943	DART AEROSPACE USA, Inc.		FAA SR02677SE	EC135 T2+/ EC135 P3 EC135 T1/ EC135 T2/ EC135 T3 EC135 P1/ EC135 P2/ EC135 P2+	Installation of Heavy Duty Wearplates.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Installation Instructions IIN-D135-1070 Revision A, dated 26September 2019< (>,<)> or later FAA approved revision.2. Master Document List MDL-D135-1070 Revision B, dated 19 December 2019< (>,<)> or later FAA approved revision.3. Instructions for Continued Airworthiness (ICA) ICA-D135-1070 Revision0...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/04/2020	Active	10072943
10072944	AV8 PMA, LLC	REV. 1		HS.125 SERIES 700A/ 700B HS.125 SERIES 600A/ 600B HS.125 SERIES 403B HS.125 SERIES 403A(C) HS.125 SERIES 401B HS.125 SERIES 400A/ 400B HS.125 SERIES 1B/3B HAWKER 850XP, HAWKER 900XP HAWKER 800, HAWKER 800XP HAWKER 750, HAWKER 1000 DH.125 SERIES 1A/3A/ 400A BH.125 SERIES 400A/ 600A BAE.125 SERIES 800A/ 800B BAE.125 SERIES 1000A/ 1000B	EASA Validation of FAA Parts Manufacturer Approval (PMA) PQ03885SWSupplement No. 3 date 07/22/2019, for Article NP-UN649-1 Nose LandingGear Plunger Tube as approved replacement for Article Number 25UN649 inTextron Hawker Series listed above.Rev. 1 corrects the model list (Hawker 850XP was missing)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Av8PMA, LLC. Drawing Number NP-UN649 Rev E, date 12-19-2019Document No. AV8-ALS-18-101, Airworthiness Limitations Supplement RevNo. B, date 5-04-2019or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:“Produced by the holder of the EASA STCnumber 10072944".Prior to installation of this change/repair it must be determined thatthe interrelationship between thi...	03/04/2020	Active	10072944

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072961	AIRBUS TRANSPORT INTERNATIONAL SNC			EASA.A.004 (IN PROGRESS) A330-743L	ATI Modification XL46MOD001: Portable Electronic Flight Bag(EFB) armmount and power supply activation.This design change which is implemented through a Supplemental TypeCertificate (STC) consists in the replacement of original Airbusinstallation (Identified through Mod 206449) of the EFB mounting d...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Airbus Transport International´s (ATI):- Change Approval Sheet (CAS) Doc. Ref. XL46MOD001_CAS Issue 1, dated02nd April 2020, and-AFM Supplement XL46MOD001_ADD (Approved Documentation Dossier) Issue 1,dated 18th March 2020: “Portable EFB armmount and power supplyActivation on A330-700L (Beluga XL)”.o...	See those of XL46MOD001_CAS Issue 1, and AFM Supplement XL46MOD001_ADDIssue 1, or later EASA approved revisionsPrior toinstallation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce...	03/04/2020	Active	10072961
10072970	HARTZELL PROPELLER LLC			SR22T	Hartzell Propeller Inc. STC for Cirrus Design Corporation Model SR22TaircraftInstallation of Hartzell Propeller Model 4C1- F650A1/76C04-0.6 or Model4C1-F650A1/76C04B-0.6	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.This certificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: CS-36 Amd 5	- Installed in accordance with documents: Instructions for Installationof Hartzell 4C1-F650A1/76C04(B)-0.6 Propeller onCirrus SR22T AircraftSTC SA04440CH - Document number INST-032519, Initial Revision, Dated16th December 2019.- Operated in accordance with document: Airplane Flight ManualSupplement...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/04/2020	Active	10072970
10072974	HAECO CABIN SOLUTIONS, LLC	REV. 1	FAA STC ST04389AT	737-800	Interior reconfiguration installation for Boeing 737-800	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS25 amdt 24: 25.571(a)(b), 25.853 (a)(c)(d), 25.899(a)(b), 25.981(d)The requirements for environmental protection and the associatedcertified noise and/ or emissions leve...	Haeco Cabin Solution, LLC. Master Data List 19T125L001, Revision B,dated 20 March 2020, or later FAA approved revision.Haeco Cabin Solution, LLC. Instructions for Continued Airworthiness19T125R009, Revision 00, dated 23 January 2020, or later FAA acceptedrevision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	06/05/2020	Active	10072974
10072976	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)	REV. 1		737-700	Alternative Maximum Takeoff WeightModification of airplane maximum take-off weight to 68946 kg and ofmaximum landing weight to 58059 kgRev. 1: Added a/c configuration with CFM56-7B22E engines	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase and/or emission levels.	Certification Program MODE00293_CP Issue 2< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Applicable to Boeing 737-700 aeroplanes, equipped with winglets andCFM56-7B22 / CFM56-7B22E engines (including intermix engineconfiguration), having EASA STC 10072320 or EASA STC 10072257 embodied.- The aeroplane must be operated as per basic AFM D631A001.7C9.Prior to installation of this change/r...	20/11/2020	Active	10072976
10072983	JAMCO AMERICA, INC.		FAA STC ST02642SE	A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216	Installation of FTS SATCOM System on Airbus Model A320 Series aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS-25 Amdt. 23: 25.853(a), 25.899(a)(b), 25.1353 (a), 25.1431(a)(c)(d)CS-25 Amdt. 4: 25.869(a)(1)(4)The requirements for env...	Jamco America, Inc. Master Drawing List (MDL) MDL2618-1, Revision A,dated 8 January 2020, or later Federal Aviation Administration (FAA) approved revision.Supplemental Principal Instructions for Continued Airworthiness (ICA)ICA2618-1, Revision 0, dated 30 December 2019 and SupplementalElectrical Wiri...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.EASA STC 10066355 (FAA STC ST04292CH), Installat...	20/05/2020	Active	10072983

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10072997	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE		FAA ST04318CH	777-300/ 777-300ER 777-200/ 777-200LR	Installation of an Astronics Flight Deck Outlet w/ USB Power System.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments:CS25 at amdt 0:25.29, 25.303, 25.561(c) , 25.571(a)(b) , 25.601, 25.605(a) , 25.609(a),25.611, 25.613(a) , 25.619, 25.625(a) , 25.771(a) , 25.777(a...	1. Astronics Armstrong Aerospace Master Data List, DocumentNo. DC104-9760D-00, Revision C, dated 15 June 2018<(>,<)> or later FAAapproved revision.2. Flight Manual Supplement<(>,<)> Astronics Armstrong AerospaceDocument No. DC303-9760D-00, Revision -<(>,<)> approved 26 June 2018<(>,<)> or later FAA...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	27/04/2020	Active	10072997
10073000	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	787-9	CHINA EASTERN 787-9 VANTAGE XL VT34 BUSINESS CLASS SUITE DOOR ACTIVATIONThis design change certifies the re-activation and use of the suitedoors in the closed position during flight conditions only.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	SWS Certification Services Ltd Master Configuration Scheme No.3209-MCS-01 Issue 3 dated 23 April 2020<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Boeing Master Change No. 2525MP8365 will require EASA approval ifaircraft with this STC installed are to be added to anEU register.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ ore...	24/04/2020	Active	10073000
10073006	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04328AT-D	GV, GV-SP	Installation of KuKa Fin Cap Radome in accordance with GulfstreamAerospace Corporation Index List CE525128001 Revision (-), dated August29, 2019Revision 1 adds the FAA STC reference.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Instructions for Continued Airworthiness, CE52512A001 Revision (-),dated July 30, 2019<(>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures ofEU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/04/2020	Active	10073006
10073008	AEROSPACE DESIGN & COMPLIANCE LLC			SEE FAA APPROVED MODEL LIST	Installation of Bendix King KA 310 Autopilot Adapter.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Aerospace Design & Compliance, LLC. Master Data List AML23-MDL-0048,Rev A, dated 18 July 2019, or later FAA approvedrevision.2. Aerospace Design & Compliance, LLC. Instructions for ContinuedAirworthiness (ICA) AML23-ICA-0048, Rev IR, dated 16 July 2019, or laterFAA approved revision.3. Aerospace...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The STC is valid for those aircraft types and mo...	15/04/2020	Active	10073008
10073021	JETAIRE AEROSPACE, LLC		FAA ST03450NY	737-900ER 737-700, 737-800, 737-900 737-400, 737-500, 737-600 737-200, 737-200C, 737-300	Installation of Invicta Mitigation/ Flammability Reduction Technology inthe Boeing 737 Center Wing Tank	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: 737-200/-200C/-600/-700/-800/-900/-900ER aeroplanes:CS25.1, 25.301, 25.303, 25.305, 25.307 (a), 25.561(c)(1)(ii), 25.571(b),...	Jetaire Aerospace Master Data List. Report No. 13022C0012, revision date03 December 2018 Revision G or later FAA approved revision.Jetaire Aerospace Supplement to Instructions forContinued AirworthinessReport No. 13022S0004 revision date 07 September 2018 Revision IR orlater FAA accepted revision.a...	The aircraft must be operated in accordance with the "AirworthinessLimitations Requirements" section of Jetaire Aerospace Supplement toInstructions for Continued Airworthiness Report No. 13022S0004 revisiondate 07 September 2018 Revision IR or later FAA accepted revision. (737·200 / -200C / -300 / -T...	24/04/2020	Active	10073021
10073051	FALCON CREST AVIATION SUPPLY, INC.		FAA STC SR09016RC	BO105 S BO105 C	Installation of a Concorde RG390E valve regulated sealed lead-acidbattery	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Falcon Crest Ref. drawing number 1, Rev. 1, dated 19 June 1995, orlater FAA approved revisions.2. Rotorcraft Flight Manual Supplement (RFMS), dated 19 June 1995, orlater RFMS.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/04/2020	Active	10073051

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073059	J.G.A	REV. 2		PC-12/47E PC-12/47 PC-12/45, PC-12/47 PC-12/45 PC-12	Seat Slides JGInstallation of so-called Seat Slides JG intothe cabin of the PilatusPC-12. This optional feature aims at improving passenger comfort inflight by enabling a longitudinal translation of the seat.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation Seat Slides in accordance with J.G. Aviation documents JG001-B Master Drawing List, at Edition 4, dated August 02, 2021;Aircraft Flight Manual Supplement, JG001 Flight Manual Supplement, Rev.0, dated April 01, 2020;Maintenance Manual Supplement, JG001 Maintenance Manual Supplement(incl...	The Seat Slides JG are applicable to all Pilatus PC12 equipped withGoodrich Executive Seat Model 4006 andthe following cabin configurations: EX-6S-2, EX-8S, EX-4S-3B,EX-6S-STD-2S, EX4S-STD-4S.The STC cannot be installed with the cabin configuration STD-9S.The Seat Slides are not eligible for instal...	11/10/2021	Active	10073059
10073061	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST04376CH	A330-323/ -341/ -342/ -343 A330-302/ -303/ -321/ -322 A330-223F/ -243/ -243F/ -301 A330-201/ -202/ -203/ -223	Installation of an Astronics Flight Deck Outlet w/ USB Power System	EASA TCDS level amended by the following requirements:CS 25amdt 0: 25.29, 25.303, 25.561 (c) , 25.571(b) , 25.601, 25.605 (a) ,25.609(a) , 25.611, 25.613 (a) , 25.619(a)(b)(c) , 25.625(a) , 25.771(a), 25.789(a) , 25.869(a) (4) , 25.981(a) , 25.1301(a)(b)(c) (d) ,25.1307(c) , 25.1309(a)(b)(d) (g) , 25.135...	1. Astronics Armstrong Aerospace Master Data List, DocumentNo.DC104-9847 B-00, Revision E, dated 3 May 2019, or later FAA approvedrevision.2. Flight Manual Supplement, Astronics Armstrong Aerospace Document No.DC303-9847B-00, Revision-, approved 6 May 2019 or later FAA approvedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/05/2020	Active	10073061
10073071 (DGAC 163-SI-2085)	HONEYWELL INTERNATIONAL INC.	REV. 1		MYSTÈRE FALCON 900 (MF900)	Installation of Honeywell N1 Digital Electronic Engine Control (DEEC).Revision 1: Transfer from Dassault Aviation to Honeywell InternationalInc.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Drawing List, Garrett Aviation Services document No. 72-0027-001,Revision -, dated 28 August 2001Airplane Flight ManualSupplement, Garrett Aviation Services documentNo. 72-8027-001, Revision -,dated 31 August 2001or later revisions of theabove listed document (s) approved/accepted onbehalf of EASAP...	If the holder agrees to permit another person to use this certificate toalter the product, the holder shall give the other person writtenevidence of that permission.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpre...	20/04/2020	Active	10073071
10073072	WINGLET TECHNOLOGY, LLC		FAA ST01840WI	680 (SOVEREIGN)	Installation of Transitional Winglets, wing structural reinforcement,and related systems changes.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The EASA Certification Basis for the addition of Transitional Winglets,for wing structural reinforcement, winglet attachment structure, LEDposition and anti-collision ligh...	Installation in accordance with Winglet Technology Master Drawing List(MDL) ref Document No D60-2000, Rev A, dated May 19, 2017.Operation in accordance with Winglet Technology Airplane Flight ManualSupplement (AFMS) ref:Document No 68FM-S1WT-00, Rev Original, dated May 5, 2017, orDocument No 68FM-S2...	1) It has been determined that the installation of this STCand does notaffect the hold function of the autopilot and does not affect the RVSMqualification of the Cessna Model 680aircraft.2) The limitations and conditions of TCDS EASA.IM.A.033 (FAA T00012WI)apply except as noted in this STC. Eligib...	20/04/2020	Active	10073072

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073073	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A321-272NX A321-272N A321-271NX A321-271N A321-253NX A321-253N A321-252NX A321-252N A321-251NX A321-251N A321-232 A321-231 A321-213/-231/-232 A321-213 A321-212 A321-211 A321-131 A321-112 A321-111/-112/-131/-211/-212 A321-111 A320-273N A320-272N A320-271N A320-253N A320-252N A320-251N A320-233 A320-232 A320-231/-232/-233 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211/-212/-214/-215/-216 A320-211 A319-153N A319-151N A319-133 A319-132 A319-131/-132/-133 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111/-112/-113/-114/-115 A319-111 A318-122 A318-121 A318-112 A318-111	Introduction of cargo seat bags for transportation of cargoin A319,A320 and A321 series passenger cabinThis Change is to introduce Cargo Seat Bags for transportation of cargo/ mail in the passenger cabin to comply with operator's requirement toperform mail flights.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI D-01, Issue 08, dated 08/04/2020.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of thea...	Master Data List JCAERO/MDL/0512, Issue 1.0Aircraft Flight Manual Supplement JCAERO/AFMS/0512-1, Issue 1.1or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/04/2020	Active	10073073
10073080	MTN. VIEW AVIATION, LLC	REV. 1	FAA SA01120SE	SEE FAA AML	Installation of Door StewardThis revision caters for the change in ownership, from AP Enterprises,LLC to Mtn. View Aviation, LLC.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval except where amended byadditional or later amendments if indicated on the FAA STC SA01120SE.The requirements for environmental protection and the associatedcertified noise and/ or emiss...	Drawings listed on FAA Approved Model List SA01120SE, dated2 September2002<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA AML SA01120SE, dated 6 November 2019, or later FAAapproved revision.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously ins...	29/04/2022	Active	10073080

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073110	AEROSPACE COMPOSITES GmbH	REV. 1		KODIAK 100	Cartography Aircraft.Installation of a camera system and control console for cartographicalobservation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation according to the document PDL-KOD100-9503-01 Rev.01 (31stMarch 2020).Operations according to the AFM Supplement AFMS-KOD100-9503-01 Rev.0-1Maintenance according to the AMM Supplement MMS-KOD100-9503-01 Rev. 0-2or later revisions of the above listed document(s) approved/acceptedunder the...	- Flight into known icing conditions is prohibited<(>,<)>- Maximum operating altitude with the cartography system operating is16 000 feet<(>,<)>- Minimum flight crew when cartography camera in operation: One pilot inthe left cockpit seat and one operator in the cabin (Operator Seat)<(>,<) >- Maximumc...	08/10/2025	Active	10073110
10073112	BEECHCRAFT BERLIN AVIATION GmbH			GVI (G650)	Installation of a new divan on GVI (G650) in accordance with MasterDocuments List E/O N° D11-B18-01,Issue 01	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Documents List E/O N° D11-B18-01, Issue 01Maintenance Manual Supplement D31-B18-01, Issue 03, dated 20 Apr 2020Aircraft Flight Manual Supplement D-30-B18-01, Issue 03, dated 16 Apr2020or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Installation is limited to serial 6132.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	23/04/2020	Active	10073112
10073116	PARAVION TECHNOLOGY, INC.		FAA SR00516DE	206L-4 206L-3 206L-1 206L 206B 206A	Installation of mounting hardware and approval for the aircraft to beoperated by a single pilot from the left crew seat.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Master Drawing List DL-206LS-100, Revision N/ C, dated 7 March 2003 orlater FAA approved revision.2. Flight Manual Supplement PR206LS-100, dated 19 June 2003 or later FAAapproved revision.3. Instructions for Continue Airworthiness, Report PR-206LS-120M, Rev.0, dated 14 March 2003 or later FAA appr...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.For left seat operation of equipment originallyb...	24/04/2020	Active	10073116
10073126	EIRTECH AVIATION SERVICES LIMITED	REV. 1	FAA STC ST04054NY	A330-341/-342/-343 A330-321/-322/-323 A330-243/-243F/-301/-302 /-303 A330-201/-202/-203/-223/-223F	Automatic Dependent Surveillance Broadcast (ADS-B) Out InstallationRevision 1: Transfer of STC holder from ALOFT AEROARCHITECTS to EIRTECHAVIATION SERVICES LIMITED	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 amdt. 0: 25.1585The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	Master Data List (MDL) 8154-0001-MDL, Revision D, dated 5 February 2020,or later FAA approved revision.ALOFT AeroArchitects Document No. TM-8154-ICAW, Revision A, dated 4February 2020, FAA accepted 13 February 2020, or later FAA acceptedrevision.ALOFT AeroArchitects Document No. AFMS-ST04054NY-A, Re...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	24/02/2021	Active	10073126
10073150	AV8 PMA, LLC			HAWKER 900XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE.125 SERIES 800B BAE.125 SERIES 800A	EASA Validation of FAA Parts Manufacturer Approval (PMA) PQ3885SWSupplement No. 6 date 10/01/2019 for MLG Plunger Tube Articles NP-8UM-5,NP-8UM-6, NP-8UM-7, NP-8UM-8 as replacement for Articles 25-8UM5 and25-8UM6 in Textron Hawker Series listed above.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Av8 PMA, LLC. PMA No. PQ3885SW, Supplement 6, date 10/01/2019Av8 PMA, LLC. Drawing Number NP-8UM, Main Landing Gear Plunger Tube, RevC, date 7/02/19Airworthiness Limitations Supplement for Main Landing Gear Plunger TubePart No. NP-8UM-5, -6, -7, -8, Document No. AV8-ALS-16-008, Rev B, dateJuly 2, 20...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:“Produced by the holder of the EASA STCnumber 10073150".Prior to installation of this change/repair it must be determined thatthe interrelationship between thi...	28/04/2020	Active	10073150

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073151	AV8 PMA, LLC			HS.125 SERIES 700A/ 700B HS.125 SERIES 403B/ 600A/600B HS.125 SERIES 401B/ 403A(C) HS.125 SERIES 1B/3B/ 400A/400B HAWKER 900XP, HAWKER 1000 HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 DH.125 SERIES 1A/3A/ 400A BH.125 SERIES 400A/ 600A BAE.125 SERIES 800A/ 800B BAE.125 SERIES 1000A/ 1000B	EASA Validation of FAA Parts Manufacturer Approval (PMA) PQ03885SWSupplement No. 8 date 11/01/2019, for Article NPFA-UM423-1 Distance Pin(Retracting Jack) as approved replacement for Article Number 25UM423 inTextron Hawker Series listed above.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Av8 PMA, LLC. PMA No. PQ3885SW, Supplement 8, date 11/01/2019Av8 PMA, LLC. Drawing Number NPFA-UM423, Distance Pin (Retracting Jack),Rev C, date 1/14/20Airworthiness Limitations Supplement for MLG Side Stay Retracting JackDistance Pin PartNo. NPFA-UM423-1, Document No. AV8-ALS-18-102, Rev A,date Au...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:“Produced by the holder of the EASA STCnumber 10073151".Prior to installation of this change/repair it must be determined thatthe interrelationship between thi...	28/04/2020	Active	10073151
10073157	AIRCRAFT DESIGN CERTIFICATION GmbH			EA 300/LC EA 300/L	Extra 300 single pilot control	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Doc.,,,,,,issue,,date,,,titleADxC-44-003-MDL,,A,, 21.02.2020,,Master document listADxC-44-003-TS ,,B ,,20.07.2018 ,,Single pilot control DescriptionADxC-44-003-AFM ,,A ,, 25.02.2020 ,,Airplane flight manual supplementADxC-44-003-AMM ,,A ,, 25.02.2020 ,,Airplane maintenance manualsupplementor later rev...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/04/2020	Active	10073157
10073161	SAFRAN ENGINEERING SERVICES GmbH			CL-600-2D24 (RJ SERIES 900)	Installation of a Communications Management Unit UL-801 PIN10801-01from Universal Avionics, to support Air Traffic Services (ATS) data linkover ATN B1	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:JAR 25 Chg 14 and CS ACNS Issue 2: CS ACNS.A.GEN.010, CSACNS.A.GEN.015, CS ACNS.A.GEN.020, CS ACNS.B.DLS.B1.001, CSACNS.B....	System Description Document MOD-CR9001-SDD issue 2AFM supplement MOD-CR9001-AFMS Issue 1MMEL supplement MOD-CR9001-MMELS Issue 1.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/04/2020	Active	10073161
10073169	TELAIR INTERNATIONAL AB			ERJ 190-300	Sliding Carpet System in the forward and aft Cargo Holds ofEMBRAERE-Jets 190-E2	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Telair Master Document List ref. T-D293 Rev IR-Telair Sliding Carpet Manuals for E190E2 Rev –, dated 10 December 2019or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/04/2020	Active	10073169
10073170	AERODATA AG			B300	Enhancement of ADS-B of TDR94/94D	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: -CS 23 Amdt 4paragraphs 23.1301, 23.1308(c), 23.1309(a), (b)and (c), 23.1529,23.1581(a)(2) and (f).-CS ACNS Initial Iss...	- Installation according to Service Bulletin SB-B300-TDR-2152 Rev. 2- Operations according to Aircraft Flight Manual Supplement AFM-157 Rev. 1- Maintenance according to Aircraft Maintenance Manual SupplementAMM-1180 Rev. 0or later revisionsof the above listed document (s) approved/ acceptedunder the E...	Limited to aircraft equipped with:- Rockwell Collins ProLine 21 avionics- Rockwell Collins GPS 4000S (Single)- Provisions for IRS (L-GPS-3, ARINC 429 HS Bus) in rear avionicscompartment. (Alternatively: use existing spare wire to rear avionicscompartment and connect to L-GPS-3)- TDR94 (622-9352-xxx)...	04/05/2020	Active	10073170

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073186	WAYPOINT AEROTEC LIMITED		CAA UK RESPONSIBILITY	EMB-505	Replacement of Passenger Seat Cushion Covers and Foams.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Waypoint Aerotec modification refWAL-078 and Master Data List (MDL) ref WAL-MDL-078 Iss1, dated16.03.2020.Instructions for Continued Airworthiness(ICA) in accordance withWaypoint Aerotec document ref WAL-CSP-078-02 Iss 1or later revisions of the above listed documen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/05/2020	Active	10073186
10073189	DIAMOND AIRCRAFT INDUSTRIES GmbH	REV. 1		DA 62	T/O and LDG with RACC OFFAmended procedures for Take-Off and Landing mandate switching off theair conditioning system before take-off and landing. As a result thereis no performance reduction during Take-Off compared to airplaneswithout air conditioning system. Thus same noise level as the airplanes...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection are unchanged but this certificate/ approval involves achange with an impact on the noise database and/ or emission levels.	STC 62-003AFM Supplement STC 62-003 to Doc. No. 7.01.25-Eorlater revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/05/2020	Active	10073189
10073190	SCANDINAVIAN AVIONICS DESIGN ApS			B200, B200C	FMS INDICATION ON RH EHSIThe purpose of this modification is to design and certify an approveddocumentation for the presentation of the prior installed FMS withP-RNAV, LNAV/VNAV, LPV approval onto the prior installed right handSN3500 Primary Navigation Display (EHSI)	The Certification Basis for the original product complemented by thefollowing additional airworthiness requirement JAA TGL No. 10, AMC20-4A, AMC 20-27A and AMC 20-28.The requirements for environmental protection and the associatedcertifiednoise and/ or emissions levels of the product are unchangeda...	Definition in accordance with Engineering Order Doc. 2123900-EO, Issue 1Instructions for continued airworthiness in accordance with 2123900-CA,Issue 1Operation in accordance with AFMS Doc. 2123900-AM, Issue 2or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	See aircraft configuration in section 4 of Engineering Order Doc.2123900-EO, Issue 1	05/05/2020	Active	10073190
10073215	HONEYWELL INTERNATIONAL Inc.	REV. 2	FAA ST01797CH	A321-253NX/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-271N A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-271N/-272N/-273N A320-231/-232/-233/-251N/-253N A320-211/-212/-214/-215/-216 A319-153N/-171N A319-131/-132/-133/-151N A319-111/-112/-113/-114/-115	Installation of Honeywell RESCU 406AF/ AFN/AFN2 ELT on AirbusA319/A320/ A321 Series AircraftRevision 1 corrects the modellist and the Description of Design Change.Revision 2 is issued following a transfer from Armstrong Aerospace Inc.to Honeywell International Inc	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	MDL= Armstrong Aerospace Master Data List, DC104-1020-00 REV. R datedJanuary 07, 2020CL=Armstrong Aerospace Compliance Listing, DC108-9807J-00 REV. – datedDecember 12, 2019AFMS = Armstrong Airplane Flight Manual Supplement, DC303-1020-00 REV. Bdated October 01, 2009ICAs = Armstrong Instructions forA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/07/2024	Active	10073215
10073220	GOODRICH CORPORATION DE-ICING &SPECIALTY SYSTEMS		FAA STC ST04311CH	DHC-8-402 DHC-8-401	Installation of Goodrich de-icer boots on the engine inlet	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmental protectionand the associated certified noise and/ or emissions levels of theoriginal product are unchanged and remain applicable to thiscertificate/ approval.	Goodrich Corporation Drawing 5D5277, Revision B, dated 22 January 2018,or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.Approval of this change in type design is for th...	25/05/2020	Active	10073220

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073230	ONBOARD SYSTEMS INTERNATIONAL			SA 315 B	Fabrication of Onboard Systems Model 200-036-00, 200-036-01<(>,<) >200-038-00 and 200-038-01 Load Weigh Kits.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Onboard Systems Master Drawing List No. 155-015-00, Revision 13,dated 29 November 2006, or later FAA approved revision.2. Onboard Systems Manual No. 120-018-00, Revision 6, dated 28 November2006, or later FAA approved revision.3. Onboard Systems Rotorcraft Flight Manual Supplement (RFMS) 121-038-0...	Approval of this change in type design applies to only those modelslisted above, which are equipped with Siren Cargo Hook Suspension System315A73-10-120 utilizing a 12581-1 universal joint, or 3160S73-06-517gimbal joint and A90B100 hook, respectively.Prior to installation of this design change it mu...	08/06/2020	Active	10073230
10073235	TROTTER CONTROLS, INC.			AT-802/ AT-802A	Fabrication of Fire Retardant Dispersal System, GEN III.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC.Therequirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original pro...	1. Trotter Controls, Inc. Master Data List ER0322, Rev B, dated 19 March2020, or later FAA approved revision.2. TrotterControls, Inc. Installation Manual 9001-0056, Rev C, dated 13March 2020, or later FAA approved revision.3. Trotter Controls, Inc. Instructions for Continued AirworthinessManual 900...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	12/05/2020	Active	10073235
10073236	AIRBORNE TECHNOLOGIES GmbH			P.68 "OBSERVER 2"	STC-AT-148, Rear hatch LASER scanner activation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: The followingparagraphs of CS-23 Amendment 3 apply to this change:23.301, 23.303, 23.305, 23.307, 23.321, 23.337, 23.561,2...	Document List (MDL) STC-148-G-DOC, Rev. 0AFM Supplement STC-148-G-AFM, Rev. 0AMM Supplement STC-148-G-AMM, Rev. 0Installation Instruction STC-148-G-II, Rev. 0,,Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The following change is precondition for the incorporation of thisSTC-AT-148:Airborne Technologies EO-AT-147 Gispro Cabin Survey ConfigurationPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed chang...	12/05/2020	Active	10073236
10073294	LUFTHANSA TECHNIK ENGINE SERVICES,INC.		FAA ST09891AC	737-800	Installation of an Executive Style Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): EASA CRI F-101 “Flammability for Mahjongtable”the following paragraph(s) at a later amendment: CS 25 amdt 19: 25.788;Appendix SThe requiremen...	- Master data list 201690010 revision IR dated 20 June 2018- AFM Supplement 201691103 Rev. D dated 23 March 2018- ICA 201691107 Rev. G dated 16 May 2018or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of E...	- EASA STC 10066729 (FAA ST09878AC) “Installation of a cabin headlinersystem (Support Structure)” and EASA STC 10068296(FAA ST09876AC)“Equipment rack installation (Equipment Provisions) for Boeing (BBJ) 737Series Aircraft” must be installed prior or concurrently.- Limited to B737-800 serial no. 425...	18/05/2020	Active	10073294
10073298	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	727-200F 727-200	ACTIVATION OF RNP-APCH TO LNAV MINIMAThis Change is raised to provide airworthiness approval of an existingdual Global Navigation Satellite System (GNSS) for the followingoperational functionality:-RNP approach operations (RNP-APCH), to LNAV minima in accordance withAMC 20-27A.-Precision RNAV operat...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 Amdt. 21:CS 25.1302(b)(c)(d)CS 25.1309(a)(b)(c)(d)(e)CS 25.1316(b)CS 25.1317(c)CS 25.1321(a)(e)CS 25.1353(a)CS 25.152...	EASA Approved:STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0162 Issue 1EASA Accepted:STC Twenty One Ltd Master Document List No. S21. MDL-1459 Issue 1or later revisionsof the above listed document(s) approved/ acceptedunder the EASA system.	The following Minor Changes must be embodied prior to, or concurrentlywith this Change:a. STC Twenty One Limited ChangeS21.20-12-1047 - Introduction of WiringProvision for Mid-Life Upgrade,b. STC Twenty One Limited Change S21.34-12-1191 -Rework to Existing FMSAnnunciators and Provisions for Additi...	20/05/2020	Active	10073298

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073323	JET AVIATION AG			CL-600-2B19 (RJ SERIES 100)	Master Minimum Equipment List (MMEL) Supplement for Challenger 850:JBSL-S-03527MEL-001This MMEL Supplement introduces appropriate updates to aircraft dispatchconditions of the EASA MMEL for CL-600-2B19 concerning ATA 52 cabininterior door indication system.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: EASA CS-MMEL: MMEL.050;MMEL.100; MMEL.105; MMEL.107; MMEL.110; MMEL.115; MMEL.120; MMEL.125;MMEL.130; MMEL.135; MMEL.140;I...	Jet Aviation AG MMEL Supplement for Challenger 850 JBSL-S-03527MEL-001Issue Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The MMEL Supplement for Challenger 850 JBSL-S-03527MEL-001 Issue A orlater EASA approved revision is applicable on those BombardierCL-600-2B19 aircraft (Challenger 850 marketing designation):1) Which have been previously modified in accordance with any of thefollowing STCs: EASA 10032098 “Introducti...	22/05/2020	Active	10073323
10073324	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH			EC635 T2+, EC635 T3 EC635 P2+, EC635 P3, EC635 T1 EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+,	Installation of a cabin WiFi hotspot with 3G/4G cellular modem andoutside antennas in accordance with List of Compliance Documents00049-DO-MZ-LCD-000	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Rotorcraft Flight Manual Supplement 00049-DO-MZ-FMS-000 Issue 02- Instructions for Continued Airworthiness 00049-DO-MZ-ICA-000 Issue 02- List of Compliance Documents 00049-DO-MZ-LCD-000 Issue 02or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Limited to Helicopters with CPDS cockpit variant.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	22/05/2020	Active	10073324
10073325	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		TCCA STC Q-LSA06-043/D ISSUE 3	BD-700-1A10	Miscellaneous Interior Modifications, including1) Minor Galley Modification (addition of removable shelf Slide LockModification)<(>,<)>2) Two additional UL/CSA 115 VAC 60 Hz electrical outlets installed -Galley, RHS<(>,<)>3) Tow Bar Bracket Relocation<(>,<)>4) Lockable Compartment Instl-AFT Wardrobe...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the product are unchanged andremain applicable to thiscertificate/approval without any im...	Master Data List, Kmlex Aviation Inc. document No. MDL26140002, RevisionB, dated 10 September 2019Instructions for Continued Airworthiness, Kmlex Aviation Inc. documentNo. ICA26140-003, Revision NC, dated 10 September 2019or later revisions of the above listed document(s) approved/accepted onbehalfP...	This modification approval is limited to Aircraft Serial Number 9157.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness o...	02/06/2020	Active	10073325
10073338	AVIONITEC AG			340A	Avionics Upgrade: Installation of dual Garmin GNS Transceivers 530W/430Wincl. PBN/LPV capability, L-3 WX-500 StormscopeSystem, Avidyne TAS 600System, Garmin Flight Stream FS 210 and related antennas.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: EASA AMC 20-28,effective 24/09/2012 for Airworthiness Approval and Operational Criteriarelated to Area Navigation for Glob...	Installation Manual Garmin GNS 530AW, Document Number 190-00357-02,Revision M;Installation Manual Garmin GNS 430W, Document Number 190-00356-02,Revision M;Installation Manual Mid Continent TA 102, Document Number 9017942,Revision J;Installation Manual Avidyne TAS 600, Document Number 600282-000,Revi...	Applicable to Cessna 340A S/N 340A-1248Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	26/05/2020	Active	10073338

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073343	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		A321-272N,-272NX A321-271N,-271NX A321-253N,-253NX A321-251NX,-252N,-252NX A321-213,-231,-232,-251N A321-111,-112,-131,-211,-212 A320-271N,-272N,-273N A320-251N,-252N,-253N A320-231,-232,-233 A320-211,-212,-214,-215,-216 A319-151N,-153N,-171N A319-131,-132,-133 A319-111,-112,-113,-114,-115 A318-111,-112,-121,-122 737-9,-900,-900ER 737-500,-600,-700,-8,-800 737-100,-200,-200C,-300,-400	Zero Pax LOPAIntroduction of a ZERO PAX LOPA on Boeing 737 & AirbusA318-A319-A320-A321 aircraft.Rev 1: Transfer of STC from GVH Aerospace Ltd - United Kingdom, to GVHAerospace (Ireland) Limited	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-25 Amendment 18:CS25.1(a), CS25.23(a)(b)(2), CS25.25(a)(2)(b)(2), CS25.27(b),CS25.29(a)(b), CS25.31, CS25.301(a), CS25....	EASA Approved:GVH Aerospace Flight Manual Supplements:For Boeing 737 series aircraft, AFM Supplement GVH-10886-01-FMS-01 Issue2.For Airbus A318-A319-A320-A321 series aircraft, AFMSupplement:GVH-10886-01-FMS- 02 Issue 2.GVH Aerospace Instructions for Continued Airworthiness:For Boeing 737 series air...	A. LIMITATIONS (operational):- No passengers on board- No supernumerary crew on board- No cargo in passenger cabinB. LIMITATION (for Operational Suitability Data Cabin Crew Data (OSDCCD)):- Approved OSD CCD (as referenced in each EASA TCDSof the STCapplicability) are invalid with theinstallation of...	26/01/2021	Active	10073343
10073348	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04326AT-D	GVII-G600 (IN PROGRESS) GVII-G600	Installation of Ka-Band Jetwave High Speed Data (HSD) System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval. The requirementsfor environmentalprotection and the associated certified noise and/ or emissions levelsof the product are unchanged andremain applicable to thiscertificate/approval without any im...	Instructions for Continued Airworthiness Ka-Band Broadband Multi-link –High Speed Data System, GC000008396 Rev –Ka BandHigh Speed Data – EWIS Instructions for Continued Airworthiness,GCD000008395 Rev CAirplane Flight Manual Supplement, GC71468M012 Rev –or later revisions of the above listed documen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2020	Active	10073348
10073350	AEROTEC & CONCEPT			ATR 72-212 A ATR 42-500	WiFi Activation in Airplanes ATR 72 and ATR 42-500 «600 version»	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) of CS 25 Amdt 5: CS-25.1301, CS-25.1309, CS25.1353, CS 25.1357, CS 25.1360, CS 25.1431, CS-25.1501, CS-25.1529,CS-25.1581.The requirements for e...	Master Data Lis AE18110MDL Issue 0, Date: 20/05/2020AFM Supplement AE18110AFMS Rev.0, Date: 28/10/2019Instructions for Continued Airworthiness AE18110ICA Rev.0, Date: 20/01/2020Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This approval is valid only for ATR 42/72 “600 version” aircraft.	05/06/2020	Active	10073350
10073351	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA ST04324AT-D	GVII-G600	GVII-G600 Airplane Interior Installation:Cabinetry, Seating, Associated Electrical and Mechanical Systems andExterior Markings	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	GC87099C999 Revision (-) Summary Compliance Report – Brimstone BagInstallation, dated 12 December, 2024GDL300008558 Revision (-) G600 BRIMSTONE BAG, dated 21 November, 2024GDL100000018 Revision (DW) Index List, dated 12 December, 2024GC71468M009 Revision (K) Airplane Flight Manual Supplement ref., d...	The “G600 EASA Validated Configuration List” GCD000012772 lists the EASAAircraft Configurations and the compatible aircraft export options.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change a...	21/01/2025	Active	10073351

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073356	S4A SOLUTIONS FOR AVIATION, S.L			DV 20, DV 20 E	TRACKING DEVICE INSTALLATION	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-VLA paragraphs 1, 3,21, 25, 301, 303, 305, 307, 321, 337, 341, 471, 561, 572, 601, 603, 605,607, 609, 611, 613, 615, 61...	Modification description and installation in accordance with ServiceBulletin,DV201-SB001 Issue 1Operation in accordancewith Flight manual supplement, DV201-HDK01 Issue1Instructions for continued airworthiness in accordance with Maintenancemanual supplement, DV201-HDK02 Issue 2or later revisions ofu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/05/2020	Active	10073356
10073358	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA STC SA18-14 ISSUE 2	BD-700-1A10	KA Band System Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	DECA Aviation Engineering Limited Flight Manual Supplement No.FMS17052-2 Revision 3 dated 29 January 2020DECA Aviation Engineering Limited Instructions for ContinuedAirworthiness No. ICA17052-2 Revision 5 dated 31 March 2020or later revisions of the above listed document(s) approved/accepted onbehal...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/05/2020	Active	10073358
10073359	BOEING IRELAND LIMITED	REV. 1		787-8, 787-9, 787-10 777-200/-200LR/-300/-300ER 767-200/-300/-300ER 757-200/-300 737-8, 737-9 737-600/-700/-800/-900/-900ER	Zero Occupancy in Passenger CabinRevision 1 adds Boeing 737-8 and 737-9 aeroplane models into theApplicability.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:Original issue of STC 10073359: The paragraphs for CS 25 Amd13 (Electto Comply) are specified in the Annex of the origin...	Original issue of STC 10073359:Certification Program Ref. BIL-00149-CP Rev. 02 dated 22.05.2020Declaration of Compliance Ref. BIL-00149-APP Rev. 00 dated 22.05.2020Airplane FlightManual Supplements:BIL-00149-AFM37 – AFM Supplement to D631A001.8D6BIL-00149-AFM57 – AFM Supplement to D631N005.22LBIL-0...	Original issue of STC 10073359A.,,LIMITATIONS (operational):- No passenger on board- No supernumerary crew on board- Nocargo in passenger cabinB.,,LIMITATION (for Operational Suitability Data Cabin Crew Data (OSDCCD)):-,,Approved OSD CCD (as referenced in each EASA TCDS of the STCapplicability) ar...	11/12/2020	Active	10073359
10073363	S4A SOLUTIONS FOR AVIATION, S.L			CL-600-2B19 (RJ SERIES 100)	REAR PRESSURE BULKHEAD FEED THRUMechanical installation of several electrical connectors and areinforcement at rear pressure bulkhead on Bombardier Challenger CL850	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	60486-RPT02 Master Document List Issue 260486-HDK02 Maintenance Manual Supplement Issue 3Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/06/2020	Active	10073363
10073367	DASSAULT AIRCRAFT SERVICES (DAS)		FAA ST03590NY	MYSTÈRE FALCON 900 (MF900)	Honeywell FMS CD-830 Displays UpgradeRemoval of existing Honeywell CD-810 or CD-820 Control Display Units (CDUs) and replaced with Honeywell CD-830 CDUs	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List F9BW-D0051-005_IR, 26 Aug 2016Instructionsfor Continued Airworthiness (ICA) F9BW-D0051-155 IR, 26 Aug2016or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	29/05/2020	Active	10073367

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073370	LUFTHANSA TECHNIK AG			A321-272N/-272NX A321-271N/-271NX/-272N/-272NX A321-253NX/-271N/-271NX A321-253N/-251NX/-252NX/-253NX A321-253N/-251NX/-252NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-171N A319-131/-132/-133/-151N/-153N A319-111/-112/-113/-114/-115	Installation of Stretcher NG on A320 Family	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplemental Type Definition Document STDD25-19/25M Iss./Rev. 01/00,dated 16 Apr 2020Airplane Flight Manual Supplement A-00-20/12-AFM Iss./Rev. 01/00, datedJan 22/20or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/05/2020	Active	10073370
10073373	AVIADECO GmbH			A320-214	Cabin Re-ConfigurationThis modification consists of a cabinreconfiguration to the maximumallowablepassenger seat reconfiguration of Y180 for A320 aircrafts.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	The change is defined with Revision 1 of Master Document List documentMDL-00518The Aircraft shall be operated in accordance with Revision 0 of AirplaneFlight Manual Supplement document AFM-00518.The Aircraft shall be maintained in accordance with Revision 1 ofInstructions for Continued Airworthiness...	This change is limited to Weight Variants 001 through 007.FL Technics UAB Minor Modifications CRB-312-01, issue A, Introduction ofnew FWD partitions arrangement on A320 aircraft, CRB-345-01, Issue A,Introduction of new emergency equipment layout on Airbus A320 Aircraft,and CRB-346-01, issue A, Parti...	10/06/2020	Active	10073373
10073385	AEROMECH Inc.	REV. 1	FAA STC SA02654SE	PA-46-600TP PA-46-500TP	Group Reduced Vertical Separation Minimum (RVSM) airworthiness approval	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02654SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Data List AM0325-DL02-00, Revision"-", dated 20 September 2019(or later FAA-approved revision).Class 1 airframesmust be maintained in accordance with the Instructionsfor Initial and Continued Airworthiness document AM0325-IC01-01, Rev.-,dated 20 September 2019 (or later FAA accepted revision...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	02/07/2020	Active	10073385
10073396	KAISERAIR, INC.		FAA STC ST03422CH	GV GIV	Installation of an Universal Avionics UNS-1Espw flight management systemwith UniLinK UL-801 datalink system and CVR-120A Cockpit voice recorderto meet airworthiness requirements for FANS 1-A + and optional AutomaticDependent Surveillance -Broadcast (ADS-B) Out	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03422CH.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	KaiserAir, Inc. Master Data List JRW1279-MDL, Revision J, dated 30October 2018, or later FAA approved revision.FAA approved Flight Manual Supplements, KaiserAir, Inc. Document No.JRW1280-FMS-01, Revision A, approved 25 May 2015, JRW1280-FMS-02,Revision B, approved 6 October 2015, JRW1280-FMS-03, Rev...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	03/06/2020	Active	10073396

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073398	AMAC AEROSPACE SWITZERLAND AG			A340-311/-312/-313 A340-211/-212/-213	WLAN ActivationActivation of Wireless Local Area Network (WLAN).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): F-108 Security Protection of Aircraft Systemsand Networks.The requirements for environmental protection and the associatedcertified noise and/ or e...	The change is defined with Revision D of Master Document List documentMDL-A3401-1-4430.The Aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplement document AFMS-A3401-1-4430.Or later revisions of the above listed document(s) approved/acceptedunder the EASA system...	AMAC Aerospace change DF07-2300 or equivalent modification shall beinstalled prior to the accomplishment of this change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wille...	05/06/2020	Active	10073398
10073399	AV8 PMA, LLC			HAWKER 900XP, HAWKER 1000 HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE.125 SERIES 800B BAE.125 SERIES 800A BAE.125 SERIES 1000B BAE.125 SERIES 1000A	EASA Validation of FAA Parts Manufacturer Approval (PMA) PQ03885SWSupplement No. 10 date 03/17/2020 for Article NP-UM153A-1 “BoltAssembly” as approved replacement for Article Number 25UM153A andNP-UM153A-3 “Bolt” as approved replacement for Article Number 25UM153-1in Textron Hawker Series listed abo...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Av8 PMA, LLC. PMA No.: PQ03885SW Supplement 10, date 03/17/2020Av8 PMA, LLC. Drawing No. NP-UM153A Bolt (Jack to pivot), Revision A,Dated 4-29-2020Av8 PMA, LLC. Document No. AV8-ALS200001, Airworthiness LimitationsSupplement Rev. No. A, date 2-6-2020.or later revisions of the above listed document(s...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:“Produced by the holder of the EASA STCnumber 10073399.Prior to installation of this change/repairit must be determined thatthe interrelationship between this...	03/06/2020	Active	10073399
10073400	LUFTHANSA TECHNIK AG			A330-343	Removal of Ka-Band Satcom System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Compliance Checklist CCL53-19/04M revision 1 dated 03.June.2020- Instructions for Continued Airworthiness A-00-20/08-ICA Issue 01Revision 00 dated 14.May.2020- Supplemental TypeDesign Documents STDD53-19/04M Issue 1 Revision 0dated 03.June. 2020or later revisions of the above listed document(s) ap...	With the application of this STC the technical documentationA-00-18/06-FCD, A-00-18/06-AFM and A-00-18/06-ICA become obsolete.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair...	03/06/2020	Active	10073400
10073403	WATTUM, JOEL WILLIAM AND ORO HARE-WATTUM BARBARA JEANNE		FAA STC SA02400AK	SEE FAA AML	Installation of Aerocet 2200 floats	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02400AK.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Installation Drawing as indicated on Approved Model List, SA02400AK,Revision B, dated 6 May 2020, or later FAA approvedrevision.Instructions for Continued Airworthiness, DocumentNo. FW-JWA517-13,Revision C, dated 14 December 2018, or later FAA accepted revision.A FAA approved Flight Manual Supplem...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC is valid for aircraft types and modelsl...	05/06/2020	Active	10073403
10073407	SWIFT AIRCRAFT Ltd.	REV. 1	CAA UK RESPONSIBILITY	G 115E	Conspicuity Wrapping 2The UK MoD requires a Conspicuity Assessment of the Grob Tutor G115EAircraft that they currently use for AEF (Air Experience Flights) andUAS (University Air Squadrons). Under a previous EASA STC 10073407,Swift Aircraft obtained permission for wrapping with a certainmanufacturer...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Flight Manual Supplement SWSTC0003-FMS01, Issue 03- Instructions for Continued Airworthiness SWSTC0003-ICA01, Issue 04- Instruction Procedure SWSTC0003-INST01, Issue 03or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/11/2020	Active	10073407

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073445	MAGELLAN AEROSPACE		TCCA SH17-39 ISSUE 1	R66	Installation of Wire Strike Protection System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Modification Data Summary EM107275 Issue CFlight Manual Supplement PM-965-098 Issue AInstructions for Continuing Airworthiness PM-965-096 Issue Aor later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Cana...	Robinson R66 Part number C599-1 Airspeed Indicator (130 KIAS VNE) andPart Number F654-28 Cockpit Placard (Flight Limitation – 130 KIAS VNE) must be installed in conjunction with this modification.Prior to installation of this change/repair it must be determined thatthe interrelationship between thisp...	09/06/2020	Active	10073445
10073460	CONCORDE BATTERY CORPORATION		FAA STC ST04469AT	GULFSTREAM G280	Installation of the Concorde Lead Acid Battery RG-380E to replace theOEM Main Lead Acid Battery	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04469AT.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Drawing List, 5-0661, Revision C, dated 16 August 2019, or laterFAA approved revision.Instructions for ContinuedAirworthiness (ICA) document 5-0663, Rev. NC,dated 20 November 2018<(>,<)> or later FAA accepted revision.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	29/06/2020	Active	10073460
10073469	T.P.S. S.P.A.	REV. 1		A109E	Right pole with RIEGL VP-1 kit p/n TPS109-03-00This kit (STC) consists in a pole, installed at the front right side ofthe helicopter, with attached a pod (RIEGL VP-1) that contains theVUX-SYS for Airborne Laser Scanning comprising the LiDAR Sensor, theIMU/GNSS unit and a digital camera for airbornes...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Airworthiness Limitation Section: TPS109-0300-ALS-00Rotorcraft Flight Manual Supplement: TPS109-0300-RFMS-00Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This approval is limited to the helicopter A109E s/n 11825 I-TEBA ** due to the certification process conducted in accordance with the NOHAZARD criteria for the impossibility to full comply with FAR 27.1301 a& d part of the CB.	19/05/2022	Active	10073469
10073482	S4A SOLUTIONS FOR AVIATION, S.L			412	EFIS INSTALLATION IN B412FIVE-TUBE BENDIX/KING MODEL EFS 50ELECTRONIC FLIGHT INSTRUMENTATIONSYSTEM	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Master Document List 41240-RPT02 EDIC./ISS. 2Flight Manual Suplement 41240-HDK01 EDIC./ISS. 3Maintenance Manual Supplement 41240-HDK02 EIC,/ISS. 2Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This Approval is limited to Helicopter Bell 412 S/N 36022Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andany otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the produc...	15/06/2020	Active	10073482
10073485	S4A SOLUTIONS FOR AVIATION, S.L			551	AMBULANCE MODULE INSTALLATION IN CESSNA 551This modification consists of the installation of one Ambulance moduleP/N 2200-016 in passenger compartment.The passenger cabin has beenreconfigured, passenger seat number 7 anddivan (passenger seats nº 4, 5 & 6) have been removed in order to allowthe inst...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	55102-RPT02 Master document list Ed655102-HDK01 Flight manual supplement Ed3Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2020	Active	10073485
10073494	DIAMOND AIRCRAFT INDUSTRIES GmbH	REV. 2		DA 62	The aim of this project is to provide an alternative seatingconfiguration for the DA 62 with more comfort in the 1st passenger row.The 3-seat 1st passenger row is replaced by a LHand a RH interfaceshell as provision for 2 seats with an increased distance to the pilotrow.	The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the productare unchangedand remain applicable to this certificate/approval without any impact onthe noise database.	STC 62-002AFM Supplement STC 62-002 to Doc. No. 7.01.25-E and Doc. No. 11.01.05-Eor later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/07/2020	Active	10073494

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073498	AIRWOLF FILTER CORP		FAA FAA STC SA00024NY	SEE FAA AML SA00024NY	Installation of Airwolf remote mounted engine oil filter kit AFC-K007 onsingle or multi-engine fixed wing light aircraft incorporating Lycomingreciprocating engines of 450 horsepower or less.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Airwolf Instructions for Continued Airworthiness, AFC-K000-ICA,revision IR, dated 5 July 2012 or later FAA accepted revision.	Engine compartment firewall for mounting oil filter shall be of 0.021inch minimum thickness ASTM A527galvanized steel or equivalent Ref. CAR 3.624(b), FAR 23 .1191(h).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherp...	16/06/2020	Active	10073498
10073499	WIPAIRE Inc.		FAA FAA STC SA04388CH	208B 208	Installation of extended baggage assembly	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Wipaire, Inc. Drawing 1008423, Revision B, dated 16 May 2019, orlater FAA approved revision.2. Airplane Flight Manual Supplement POHSA04388CH, Revision B, dated 17June 2019, orlater FAA approved revision.3. Instructions for Continued Airworthiness 1008957, Revision NC, dated2 April 2019, or late...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/06/2020	Active	10073499
10073508	HONEYWELL INTERNATIONAL Inc.	REV. 1	FAA STC ST04441CH	A380-861 A380-842 A380-841	Installation of ELT System UpgradeInstallation of HoneywellRESCU 406AFN2 Emergency Locator Transmitter (ELT) System Upgrade.Rev. 1: Transfer from "CertifyNation, LLC." to "Honeywell International,Inc.".	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- CertifyNation Master Data List doc. no. CN19-044MDL-00 rev 0, datedMatch 04 2020- CertifyNation Instructions for Continued Airworthiness (ICA) doc. no.CN19-044ICA-01 rev 0or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implemen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/09/2024	Active	10073508
10073509	SAAB AB	REV. 1		35A	Installation of ADS-B out capability In Learjet 35A.Rev. 1:Transfer from SAAB AKTIEBOLAG (DOA 21J.108) to SAAB AB (DOA21J.066).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI F-01.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchang...	Saab AB project TDM20-02 including documents as listed in TDM20-02-LEP,Rec C.AFM-supplement TDM20-02-4-AFMS, Rev Bor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Serial numbers 075 and 195.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installedchange and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	06/12/2023	Active	10073509
10073516	S4A SOLUTIONS FOR AVIATION, S.L			390	WIFI ACTIVATION IN B390This design change activates the WIFI system on board Beechcraft 390aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS23 paragraphs 23.1,23.3, 23.21, 23.23, 23.251, 23.611, 23.771, 23.773, 23.853, 23.1301,23.1306, 23.1309, 23.1351, 23.135...	Modification and installation in accordance with Master Document List,B39002-12-13, Edition 2Instructions for ContinuedAirworthiness in accordance withB39002-12-30, Edition 1Usage in accordance with Flight Manual Supplement, B39002-12-28,Edition2or later revisions of the above listed document(s) a...	Conditions: See applicability in section 5 from Master Document List,B39002-12-13, Edition 2.	17/06/2020	Active	10073516
10073520	AIR ALLIANCE GmbH			31A 31	Installation of GPS/SBAS Antenna	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: FAR 25.899 (a) and (b)amendment 25-123; FAR 25.1316 (a) amendment 25-134; FAR 25.1529amendment 25-54The requirements forc...	Installation and Maintenance in accordance with Master Drawing list ref2020-001-MDL initial issue dated 15/06/2020, Installation Manual ref. 2020-001-IM initial issue dated 15/06/2020 and Instructions forContinuous Airworthiness ref 2020-001-ICA initial issue dated12/05/2020.or later revisions of the...	Installation of GARMIN GA36 GPS/SBAS antenna as provision only.Connection to aircraft equipment requires additional approvalPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair w...	17/06/2020	Active	10073520

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073526	PMV ENGINEERING	REV. 1		737-8, 737-9 737-600/-700/-800/-900/-900ER	Tablet cradle installation on B737The modification consistson the installation of 2 arm mounts on theexisting sliding windows (both sides, Captain and First Officer) and theinstallation of tablet cradles on those arm mounts.Rev 1: introduces configuration for the installation of the 11 inchestablet...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 amdt 12 for thefollowing requirements: 301 (a)(b)(c), 303, 305(a)(b)(c)(e)(f), 307(a)(d), 561(a)(b)(c)(d),...	8 inches tablet cradle configuration:- MASTER DOCUMENT LIST, ref: AVI-02020-MDL-R04 dated 28/05/2020- INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, ref: AVI-02020-ICA-S01-R03dated 28/05/2020- AIRCRAFT FLIGHT MANUAL SUPPLEMENT, ref: AVI-02020-AFMS-S01-R02 dated20/02/2020- MMEL Supplement AVI-02020-MMELS-...	Limitations are defined in the ICA documentPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/09/2023	Active	10073526
10073527	REB TECHNOLOGIES Inc.d/b/a REBTECH	REV. 1	FAA SR09561RC	369E, 369FF, 500N	Installation of NVG Infrared Filter SystemThis project installs an NVG Infrared Filter System for use with NightVision Goggles (NVGs) in MD Helicopters inc. (MDHI), Models 369E, 369FF,500N to reduce or eliminate infrared emissions detrimental to NVGflight.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: FAA – 14 CFR Part 2727.1(a)(b), amdt. 27-0; 27.301 (a), amdt.27-0; 27.303, amdt. 27-0;27.305(a), amdt. 27-0; 27.307(a),am...	EASA approved documents:- Rotorcraft Flight Manual Supplement, Document Number: 98020500-ERFMS,Rev. IR dated 21 April 2020EASA accepted documents:- Master Drawing List, Document Number: 98020500MDL, Rev. AE< (>,<)>dated 27 January 2020- Configuration Control List, Document Number: 98020500-ECCL, Rev....	Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the cockpit or cabin configurationspecified in this de...	19/06/2020	Active	10073527
10073531	HELICOPTER TECHNOLOGY COMPANY		FAA STC SR02492LA, 07.10.2020	204B, 205A-1	Installation, operation, and maintenance of Helicopter TechnologyCompany main rotor blade assembly	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02492LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Document List, MDL-204-2100-01, Rev. C, dated 24 January 2018- Instructions for Continued Airworthiness of Maintenance ManualHTCM-006, Rev. D, dated 03 January 2020, withits AirworthinessLimitation Section at Rev. D dated 13 April 2020or later revisions of the above listed document(s) appr...	Installation of HTC Main Rotor Blade with Part Number 204P2100-101 isnot approved under this STC certificate.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce n...	06/11/2020	Active	10073531
10073534	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		SC7 SERIES 3	Installation, operation and maintenance of Electronics InternationalMVP-50T Glass Panel Monitor System in SC-7 “Skyvan”in accordance withMaster Document List ASR-2017-024-MDL-01-00, dated 5 June 2020	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 amdt 4.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	Master Document List ASR-2017-024-MDL-01-00, dated 5 June 2020Instructions for continued Airworthiness ASR-2017-024-ICA-11-00, dated 5June 2020Flight Manual Supplement ASR-2017-024-FMS-05-00, dated 8 August 2017or later revisions of the above listed document(s) approved/ acceptedunder the EASA system...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/06/2020	Active	10073534
10073535	QUIET TECHNOLOGY AEROSPACE, Inc.		FAA STC ST04265AT	BAE.125 SERIES 1000B BAE.125 SERIES 1000A	Replacement of the inner aluminum barrel of the engine inlet cowl with aQuiet Technology Aerospace inlet barrel of carbon graphite sandwichconstruction	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04265AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Quiet Technology Aerospace document "Hawker 1000 Inlet Cowl InnerBarrel Replacement Master Drawing List," Report No.QTA 6101, Rev. A,dated 16 October 2019, or later FAA approved revisions.2. '"Hawker 1000 Inlet Cowl Inner Barrel Replacement Assemble Procedure," Report No. QTA 6107, Rev. A, dated...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/06/2020	Active	10073535

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073537	SABENA TECHNICS BGC			A330-343	A330-300 - Cabin Reconfiguration & IFE Modification from 3 classes to375 PAX YC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: The followingparagraph(s) at a later amendment: CS-25 at amendment 4, 25.1, 25.29,25.301, 25.303, 25.305, 25.307, 25.321,...	- Instructions for continued airworthiness 40533-01-A-ICA-R00- Airplane Flight Manual Supplement 40533-01-A-AFMS-R00- Master Data List 40533-01-A-MDL-R00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik EASA STC No. 10014507 Rev.02Prior to installation of this change/repair it must be determin...	18/06/2020	Active	10073537
10073552	BREEZE EASTERN, LLC.	REV. 1	FAA SR09911AC	SEE FAA APPROVED MODEL LIST	Installation of alternate hoist cableRev. 1: Changed STC Holder.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. JJASPP Master Drawing List Number BL-19725 revision IR, dated 28November 2018, or later FAA approved revision.2. Instructions for Continued Airworthiness Refer to FAA AMLfor relevant document as applicable to TypeCertificate Holder and helicopter Type and Model.Original STC Number: FAAo...	Refer to FAA AML for relevant limitations as applicable to TypeCertificate Holder and helicopter Type and Model.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	18/08/2023	Active	10073552
10073563	THALES AVIONICS Inc.	REV. 1	FAA ST02610LA	A321-251N, A321-271N A320-251N, A320-271N	INSTALLATION OF SATELLITE TELEVISION SYSTEM THALES STV+ ON AIRBUS A320AIRPLANESThe THALES STV+ system provides cabin live television and stored contentto each seatback display. Inaddition, the system also integratesindependent on-ground data link capability for airline operations andmaintenance.Rev...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s):EASA CRI C-01 LargeAntenna InstallationEASA CRI C-02 Vibration & Buffeting- The following paragraph(s) at a later amendment:JAR 25.562 Chan...	Master Data List 320M8001-MDL, Revision F, dated October 9,2017Airplane Flight Manual Supplement 320M8001-AFM, Revision IR, datedOctober 9, 2017<(>,<)>Instructions for Continued Airworthiness 320M8001-NCA, Revision B, datedSeptember 29, 2017, and EWIS Instructions for Continued Airworthiness320L800...	- See Inspections in Report 320M8001-NCA Rev B SupplementalInstructionsfor Continuous Airworthiness, and- EWIS Instructions for Continued Airworthiness 320L8001-EWI, RevisionC, dated May 4, 2017- The following Airbus Modifications must beinstalled prior to orconcurrently with the EASA STC: Mod.w...	15/07/2020	Active	10073563
10073566	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	757-200	Zero Passenger Layout.This Modification is raised to reconfigure the subject aircraft from a52 F/C & 9 Y/C Layout to a Zero Passenger Layout.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	EASA Approved:H4 Aerospace Flight Manual Supplement-Zero Passenger Layout No.H4AFMS053 Issue 1H4 Aerospace Instructionsfor Continued Airworthiness-Zero PassengerLayout No. H4AICA038 Issue 2EASA Accepted:H4 Aerospace Modification Summary No. H4A1940 Issue 1or later revisions of the above listed doc...	A. LIMITATIONS (operational):- No passengers on board- No supernumerary crew on board- No cargo in passenger cabinB. LIMITATION (for Operational Suitability Data Cabin Crew Data (OSDCCD)):- OSD CCD is not applicable to this aircraft type.Prior to installation of this change/repair it must be determi...	22/06/2020	Active	10073566
10073571	SBARS, LLC		FAA STC SA0688LA	DA 40	Installation of a Supercharged Lycoming IO-360-M1A engine	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	1. Master Drawing List No. MDL-DA40-1, Rev. D, dated 8 August 2018, orlater FAA approved revisions.2. Instructions for Continued Airworthiness, Document No. 20040-30, Rev.IR, dated 13 June 2017, or later FAA revisions.3. Airplane Flight Manual Supplement No. AFMS20040, Rev. IR, dated 29November 2018...	The supercharged IO-360-M1A engine installation is limited to 30 inHgMAP and 2700 RPM.This Supplemental Type Certificate cannot be used unless EASA STC10073577 has been applied tothe IO-360-M1A engine.Prior to installation of this change/repair it must be determined thatthe interrelationship betwee...	26/06/2020	Active	10073571

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073576	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		A321-271N/-271NX/-272N /-272NX A321-253N/-253NX A321-252N/-252NX A321-251N/-251NX A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of 90-Day Underwater Location BeaconRev 1: Transfer of STC from GVH Aerospace Ltd - United Kingdom, to GVHAerospace (Ireland) Limited	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 Amendment 24:25.1, 25.29, 25.301, 25.305, 25.307, 25.321, 25.337, 25.341, 25.601,25.607, 25.611, 25.863, 25.1301, 25....	EASA Approved:GVH Aerospace Instructions for Continued Airworthiness No.GVH-10367-02-ICA-01 Issue 1.EASA Accepted:GVH Aerospace Master Data List No. GVH-10367-02-MDL-01 Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/01/2021	Active	10073576
10073577	SBARS, LLC		FAA STC SE02689LA	IO-360-M1A	Installation of SBARS Supercharger system on Lycoming IO-360-M1A engine	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Master Drawing List No. MDL-DA40-1-E, Rev. A, dated 18 August 2018,or later FAA approved revisions.2. Instructions for Continued Airworthiness, Document No. 20040-31, Rev.IR, dated 13 June 2017, or later FAA approved revisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/06/2020	Active	10073577
10073585	INGENIO AEROSPACE INC.	REV. 1	TCCA SA16-9 ISSUE 5	BD-700-1A10, BD-700-1A11	Installation of Pilot's and Co-Pilot's Ingenio Aerospace Tripod TabletHolder MountsRevision 1: INGENIO Cockpit Tripod Electronic Flight Bag (EFB) MountInstallation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.305, CS 25.561<(>,<)> CS.25.853 at amdt 1The requirements for environmental protection and the associat...	Initial issue: Modification must be performed in accordancewith thefollowing:1) Kmlex Aviation Inc. Master Document List – Installation of INGENIOCockpit Tripod-Mount System onBombardier Global Express Series Aircraft, Number MDL35149002,RevisionG dated 18 June 2020.2) Ingenio Aerospace Installati...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Initial issue:1) This STC is for the installation of Pi...	23/04/2025	Active	10073585
10073588	GAMA AVIATION (ENGINEERING) LIMITED		CAA UK RESPONSIBILITY	B200GT B200CGT	Installation of provisions for and subsequent installation of GarminG1000 NXi Integrated Avionics System and GFC 700 Automatic FlightControl System.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS-23 Amendment 4:23.1; 21; 25; 29; 301; 303; 305; 321; 337; 341; 561; 601; 603; 605; 607;609; 611; 613; 671; 771; 773; 777...	Gama Aviation Master Data List, document GAEL-1641MDL-01, Issue 2, dated29 June 2020.Part A - GAMA Aviation Drawing GAEL-1641-001 – General Arrangement.Part B - Garmin Drawing 005-00421-N3 – General Arrangement.To be operated according to:Gama Aviation Aircraft Flight ManualSupplement, document GAE...	This STC is only applicable to aircraft ex-factory (or equivalent)equipped with Collins Pro Line Fusion avionics.The following STCs must be installed concurrently, respectively inimmediate sequence: EASA STC 10072169, Rev. 0 or later Rev.,Holder:GAMA Aviation (Engineering) Ltd.;EASA STC 10033158, R...	29/06/2020	Active	10073588
10073595	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04422AT	A321-271N/-272N A321-251N/-252N/-253N A321-212/-213/-231/-232 A321-111/-112/-131/-211 A320-251N/-252N/-271N A320-216/-231/-232/-233 A320-111/-211/-212/-214 A319-151N/-153N/-171N A319-115/-131/-132/-133 A319-111/-112/-113/-114 A318-111/-112/-121/-122	Installation of Gables Engineering Audio Control Panels	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt 11: 25.1357CS25 amdt 16: 25.29, 25.611, 25.625, 25.1301, 25.1309, 25.1353, 25.1431,25.1581CS25 amdt 18: 25.1529,T...	1. Master Data List (MDL) 217232-MDL, Rev.IR, dated 9 January 2018, orlater FAA approved revision.2. Instructions for Continued Airworthiness (ICA) document 217232-ICA,Rev. IR, dated 24 October 2017 or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/09/2020	Active	10073595

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073599	LUFTHANSA TECHNIK AG			A310-304	ADS-B Out Activation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS ACNS Subpart A & DIssue 2.The requirements for environmental protection and the associatedcertified noise and/ or emi...	- Compliance Checklist CCL34-19/07M Rev 2 dated 23.June.2020- Supplemental Type Definition Document STDD34-19/07M Issue1 Rev 0dated 22.June.2020- Aircraft Flight Manual A-00-19/78-AFM Issue 02 Rev 00 dated 08 Oct2019- Instructions for Continued Airworthiness A-00-19/78-ICA Issue 01 Rev01 dated 05 J...	This approval is only valid for aircraft which have undergone an EMI GRDtest according to the procedure BAQ-GESP-01.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intr...	25/06/2020	Active	10073599
10073610	AIRWOLF FILTER CORP		FAA STC SA00013NY	A-1	Installation of Airwolf Filter Model AFC-500 Full Flow Engine Oil FilterP/N AFC-500	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Airwolf Installation Drawing List AFC-A001 dated 30 March 1993.2. Installation Instructions No. AFC-K005-II dated 30March 1993.3. Airwolf Maintenance Instructions AFC-K005-MI dated 30 March 1993.	Installation is limited to AVIAT A-1 airplane with Lycomingengine modelO-360-CIG and O-360-AIP.Fire wall must be minimum 0.021 inch ASTM A527 galvanized steel orequivalent.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyp...	26/06/2020	Active	10073610
10073617	SABENA TECHNICS BGC	REV. 1		ATR 72-212 A ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102 ATR 42-500 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Cargo seat bag installation on ATR-42/-72 aircraftRev. 1 extends the time limitation to 31 July 2022, as prescribed byEASA deviation DEV-D25.855-01 issue 3.1.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI D-130-60073262 - Transportation of cargo inpassenger compartments.- The followingparagraph(s) at a later amendment: CS-25 at amendment 4:25.1...	- Master Data List, Ref. 40681-01-A-MDL-R01 dated 20 Dec 2021- Airplane Flight Manual Supplement, Ref. 40681-01-A-AFMS-R07 dated 20Dec 2021- Instructions for continued airworthiness, Ref. 40681-01-A-ICA-R02dated 20 Dec 2021or later revisions of the above listed document(s) approved/ acceptedunder the...	Limitations as per §3 of Instructions for Continued Airworthinessdocument and §3 of Airplane Flight Manual Supplement document referencedabove.After 1 year or 2 000 FH threshold after STC embodiment, whichever comesfirst, but no later than31 July 2022 (iaw. DEV-D25.855-01 issue 3.1):No cargo is all...	10/01/2022	Active	10073617
10073636	ROW 44, Inc.		FAA STC ST04462CH	A321-231/-232 A321-111/-112/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of Row 44 Broadband Antenna System Provisions	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04462CH.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Row 44 Master Data Index Listing, Document No. RWO100-0001-00, RevisionIR, dated 4 May 4, 2020 or later FAA approved revision.FAA Approved Airplane Flight Manual Supplement, Row 44 Document No. aslisted, is required on board the modified aircraft:a. A319 models: RWO220-0007-00, Revision -, approvedl...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	10/07/2020	Active	10073636
10073652	AIRWOLF FILTER CORP		FAA STC SE95WE	O-470-U O-470-R, O-470-S,O-470-T O-470-M-CI, O-470-N, O-470-P O-470-L-CI, O-470-M O-470-K-CI, O-470-L O-470-H, O-470-J, O-470-K O-470-E, O-470-G, O-470-G-CI O-470-A, O-470-B, O-470-B-CI IO-470-A, IO-470-C	Installation of oil fitting (AN-832-5D) in rocker box cover	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SE95WE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origin...	Walker Engineering Company Drawing List No. DL W2031, Revision A, dated8 May 1978, or later FAA approved revisions.	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.This STC has to be used in conjunction with EASA...	09/07/2020	Active	10073652

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073655	AEROSPACE SYSTEMS INTERNATIONAL LLC		FAA STC SA11227DS	B300, B300C B200CT, B200GT, B200T B200, B200C, B200CGT	Installation of a remote heading select panel into the pedestal to beused in conjunction with the existing Collins Flight Guidance System(FGS-3000) in a Textron Aviation Inc. 8200, 8200C, B200C (C-12F), B200C(UC-12M), B200C (C-12R), B200C (UC-12F), B200CT, B200T, B200GT, B200CGT,B300, B300C, B300C (...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA11227DS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	"Master Data List", Document No. 632-00-0001, Revision IR, dated 13November 2019, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement, Document No. 632-00-0017, Revision IR, dated 29 August 2018, or later FAA approvedrevision.Instructions for Continued Airworthiness, Documen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This installation requires the installation of Pro Line...	30/06/2020	Active	10073655
10073666	AEROTEC & CONCEPT			ATR 72-212 A ATR 72-212 ATR 72-211/-212/-212 A ATR 72-211 ATR 72-202 ATR 72-201 ATR 72-102 ATR 72-101/-102/-201/202 ATR 72-101 ATR 42-500 ATR 42-400/-500 ATR 42-400 ATR 42-320 ATR 42-300 ATR 42-200/-300/-320 ATR 42-200	ATR 42/72 Stretcher Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Data List AE19140MDL Rev.0 dated 9/06/2020- AFM Supplement AE19140AFMS Rev.0 dated 09/06/2020- Instructions for Continued Airworthiness AE19140ICA Rev.0 dated09/06/2020orlater revisions of the above listed document(s) approved/ acceptedunder the EASA system.	-Per AFM Supplement AE19140AFMS-Per Instructions for Continued Airworthiness AE19140ICA-Pre-requisite: Aerotec Change AE16077MAS-Installation is limited to configurations as per drawing ref.STR-16077-001-000 without Medical or Oxygen EquipmentPrior to installation of this change/repair it must be d...	01/07/2020	Active	10073666
10073668	AERODATA AG	REV. 1		680 (SOVEREIGN)	Installation of AD-AFIS-1310.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List, document MDL-A/C-932, Revision 1, dated 29 June2020.To be operated according to: Airplane Flight Manual Supplement, documentAFM-173, Revision 2, dated 20 May2020.To be maintained according to: Aircraft Maintenance Manual Supplement,document AMM-1176, Revision 0, dated 18 May 2...	Limited to S/N 680-0501 and on.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.At time of approval of t...	24/07/2020	Active	10073668
10073676	AIRWOLF FILTER CORP		FAA SE92WE	L/IO-470-A IO-470-U, IO-470-V, IO-470-VO IO-470-R, IO-470-S, IO-470-T IO-470-LO, IO-470-N, IO-470-P IO-470-G, IO-470-H, IO-470-L IO-470-D, IO-470-E, IO-470-F	Installation of oil fitting (AN-823-(D) in rocker box cover.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Walker Engineering Company Drawing List No. DLW-2031, Revision "A" dated08 May 1978<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This STC has to be used in conjunction with EASA STC 10016590.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the p...	09/07/2020	Active	10073676
10073677	AIRWOLF FILTER CORP		FAA SE93WE	TSIO-470-D TSIO-470-C TSIO-470-B	Installation of oil fitting (AN-823-(D) in rocker box cover.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Walker Engineering Company Drawing List No. DLW-2031, Revision "A" dated08 May 1978<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This STC has to be used in conjunction with EASA STC 10016590.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the p...	09/07/2020	Active	10073677

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073678	AIRWOLF FILTER CORP		FAA SE94WE	IO-520-L, IO-520-M IO-520-F, IO-520-J, IO-520-K IO-520-C, IO-520-D, IO-520-E IO-520-A, IO-520-B, IO-520-BA	Installation of oil fitting (AN-823-(D) in rocker box cover.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Walker Engineering Company Drawing List No. DLW-2031, Revision "A" dated08 May 1978<(>,<) >or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This STC has to be used in conjunction with EASA STC 10016590.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the p...	09/07/2020	Active	10073678
10073691	AIRWOLF FILTER CORP		FAA SE96WE	TSIO-520-R TSIO-520-N, TSIO-520-P TSIO-520-L, TSIO-520-M TSIO-520-J, TSIO-520-K TSIO-520-G, TSIO-520-H TSIO-520-E, TSIO-520-F TSIO-520-C, TSIO-520-D TSIO-520-A, TSIO-520-B	Installation of oil fitting (AN-823-5D) in rocker box	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Walker Engineering Company Drawing List No. DLW-2031, Revision "A",dated 08 May 1978< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA inaccordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This STC has to be used in conjunction with EASA STC 10016590.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the p...	09/07/2020	Active	10073691
10073692	DASSAULT FALCON SERVICE			MYSTÈRE FALCON 50 (MF50)	FANS 1A+ installationInstallation of UniLink UL-801 connected to MCS 7120. Exchange of theCVR and installation of 3 newswitches.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Flight Recorders and Data Link Recording CRIF-5122-001; Non-rechargeable Lithium Battery Installations CRIF-5128-001.- The following paragraph(s) a...	- Master Document List DFS-DE-17-F5-5737 issue A- Airplane Flight manual Supplement F50-068- MMEL Supplement DFS-DE-06-F5-A1 issue Originalor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/07/2020	Active	10073692
10073693	DASSAULT FALCON SERVICE			MYSTÈRE FALCON 50 (MF50)	Honeywell Satcom MCS 7120 InstallationThe existing MCS 6000Satcom and PABX Magnastar C750 are removed and theMCS7120 satcom system is installed.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Security protection of Aircraft systems andnetworks CRI F-5123-001.- The following paragraph(s) at a later amendment: JAR 25.869 Change 14;JAR 25.8...	- Master Document List DFS-DE-17-F5-5738 issue A- MMEL Supplement DFS-DE-06-F5-A1 issue Originalor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/07/2020	Active	10073693
10073694	DASSAULT FALCON SERVICE			MYSTÈRE FALCON 50 (MF50)	ADS-B out (DO-260B) installationTransponders are upgraded. Three annunciator switches added oninstrument panel and two BA-440 and associated relays installed inbaggage compartmentto provide ADS-B out	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: JAR 25.869 Change 14;JAR 25.899 and 25.1360 change 13; FAR 251302 (b)(c)(d) amdt. 137; CS25.1309(b)(3) amdt. 23; CS 25.13...	- Master Document List DFS-DE-17-F5-5736-A issue A- Airplane Flight manual Supplement F50-069- MMEL Supplement DFS-DE-06-F5-A1 issue Originalor later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/07/2020	Active	10073694
10073698	AIRWOLF FILTER CORP		FAA STC SH1065NE	269C 269B 269A	Installation of Airwolf Model AFC-500 Full Flow Engine Oil Filter P/NAFC-500	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SH1065NE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	Installation Drawing List AFC-H001, dated 5 December 1992 andInstallation Instructions No. AFC-K004-II, dated 5 December 1992.	Installation is limited to Schweizer 269A, B, C HelicopterswithLycoming engine models O-360-B1A, HO-360-B1B, HIO-360-A1A, HIO-360-B1A,HIO-360-B1B, HIO-360-D1A, O-360-C2D.Prior toinstallation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any ot...	03/07/2020	Active	10073698

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073699	FOKKER TECHNIEK B.V.	REV. 1		A319-153N	A319NEO Corporate Jet VIP-conversion – Project ARCTIC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 Amendment 21 forall project impacted paragraphs (see A319-ARCTIC-CRR-0001 Issue 1)except 25.853 (f), 25.1441(c), 25.13...	A319-ARCTIC-CRR-0001 Issue 1 dated 2 July 2020A319-ARCTIC-MMEL-S-0001 Issue 2 dated 23 June 2020A319-ARCTIC-AFM-S-0001 Issue 2 dated 5 June 2020A319-ARCTIC-CCOM-S-0001 Issue 2 dated 5 June 2020or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product	06/07/2020	Active	10073699
10073700	FOKKER TECHNIEK B.V.			A319-153N	Installation of a large antenna for GOGO 2KU satellite communicationsystem	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-4301-006 Vibration and buffetingcompliance criteria for large external antenna installations.- Refer to the Appendix.The requirements...	A319-ARCTIC-CRR-0002 Issue 1 dated 02 July 2020A319-GOGOFT-ICA-0001 Issue 1 dated 30 March 2020A319-ARCTIC-AFM-S-0002 Issue 1 dated 26 March 2020or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/07/2020	Active	10073700
10073703	AIRWOLF FILTER CORP		FAA STC SR00568NY	F-28F, 280F, 280FX F-28A, 280, F-28C, 280C	Installation of remote mounted engine oil filter, model AFC-500 orAFC-600, and kit AFC K014	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00568NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Airwolf Installation Instructions No. AFC-K014-A-II, dated 30 April1996.Airwolf Maintenance Instructions AFC-K014-MI, dated 30 April 1996.	This installation applies to the above Enstrom helicopters equipped withLycoming HI0-360 series engines as listed on EASA type certificate datasheet EASA.IM.R.122.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	06/07/2020	Active	10073703
10073713	AVIONIK STRAUBING ENTWICKLUNGS GmbH			650	Installation of dual Garmin Transponder GTX 3000 with Position SourceGPS 3000	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS-25 Amendment 4: 1301, 1309, 1353 CS-25Amendment1...	- Flight Manual Supplement ASR-2020-004-FMS-05-00, Am 00-Instructions for Continued Airworthiness ASR-2020-004-ICA-11-00, Am 00- Instructions for Installation ASR-2020-004-IFI-10-00, Am 00Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC is only applicable to aircraft pre-configured as described inchapter 2 of Avionik Straubing document ASR-2020-004-IFI-10.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or re...	06/07/2020	Active	10073713
10073714	AIRWOLF FILTER CORP		SH1052NE, DATED 20.12.17.	R22	Installation of Airwolf Model AFC-500 or AFC-600 full flow engine oilfilter and, Kit No. AFC-K003	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SH01052NE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Installation Drawing List Report AFC-R001<(>,<)> dated 27 October 1992and Installation Instruction AFC-K003-II, dated 5October 1992.	Installation is valid for R22 Helicopters with Lycoming Engine ModelsO-320-A2B, or O-320-A2C, or O-320-B2C.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce noe...	22/07/2020	Active	10073714
10073718	AIRWOLF FILTER CORP		FAA STC SR00342NY	R44	Installation of Airwolf remote mounted engine oil filter kit AFC-K011	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR00342NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Installation Drawing List AFC-R003, dated 24 May 1995 and InstallationInstruction AFC-K011-II, dated 24 May 1995.	Installation is limited to R44 helicopters with Lycoming Engine ModelO-540-F1B5.Prior to installation of this change/ repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changeand/ or repair will introduce no adverseeffect upon the airw...	07/07/2020	Active	10073718

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073723	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC SA976GL-D	MYSTÈRE-FALCON 20 - F5 MYSTÈRE-FALCON 20 - E5 MYSTÈRE-FALCON 20 - D5 MYSTÈRE-FALCON 20 - C5	Relocation and installation of a wing/ nacelle mounted HF antenna	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA976GL-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Garrett General Aviation Services Division drawing no. 5518004, dated 10November 1989<(>,<)> no revision or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/07/2020	Active	10073723
10073728	JAMCO AMERICA, INC.		FAA STC ST02675SE	787-9 787-10	Installation of Jamco America "Venture" B/C Seat Furniture ModificationService Bulletin on Boeing Model 787-9 and 787-10 aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02675SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Jamco America, Inc. Master Drawing List (MDL) 2499-1, Revision D, dated20 May 2020, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/07/2020	Active	10073728
10073733	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02533SE	777-300ER	Economy Class Cabin refresh to include revising the seatingconfiguration from 9 to 10 abreast seats, rework of the passengerservice units, installation of newin-flight entertainment, refresh of all partitions,monument/partition/stowage refresh and installation ofc...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02533SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Northwest Aerospace Technologies, Inc. (NAT) Master Data List (MDL) N0583-D10 Revision D, dated 2 April 2018, or later Federal AviationAdministration (FAA) approved revision.Instructions for Continued Airworthiness (ICA) N0583-D70, RevisionA,dated 6 April 2018, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The FAA has approved accomplishing the tasks specifiedR...	07/07/2020	Active	10073733
10073737	DASSAULT FALCON SERVICE			FALCON 7X	WIFI activationTo activate WIFI network on Falcon 7X	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25.1302 amdt. 24The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	- DFS-DE-17-7X-7152 issue Aor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/07/2020	Active	10073737
10073747	KELLY AEROSPACE THERMAL SYSTEMS, L.		FAA STC SA04037CH	SR22T SR22 SR20	Installation of an Air Conditioning System, Kelly Aerospacekit KATS-14-003.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04037CH.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Installation Instructions as listed on NC-14-022, Revision D, dated 19November 2015, and Drawing List NC-14-021, Revision D, dated 24September 2015, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement, Doc. No. NC-14-023,Revision A, approved 3 December 2015<(>,<)> or laterr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/07/2020	Active	10073747
10073751	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	B200	Antenna Installations, Relocation & Removals – King Air B200	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Installed in accordance with documents: Installation Instructionsdocument number 2XL168 LEF49A (1),Issue 1, dated 18thJune 2020<(>,<)>- Maintained in accordance with documents: Instructions for ContinuedAirworthiness document number 2XL168 LEF73A(1), Issue 1, dated 18th June2020<(>,<)>- Master Dat...	Aircraft build standard is a Beechcraft King Air 200 with Pratt &Whitney Canada PT6A-42 engines with following four pre-requisite STCs:EASA STC 10037574 – Installation of Garmin GTN 6XX/7XX and GTNXi SeriesNavigation SystemEASA STC 10059881 – Provisions installation of Garmin GPS/XM AntennasEASA STC...	09/07/2020	Active	10073751

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073760	BOGGI AERONAUTICS S.R.L.			AW119MKII AW109SP A119 A109S A109N A109LUH A109K2 A109E A109C A109AII A109A A109	External Heated Mirror Installation (ref 109P00600).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document list, 109P00600-Mdl-01, issue 1, dated 07 July 2020.Rotorcraft Flight Manual Supplement, 109P00600-FMS-01, issue 01, dated07 July 2020.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/07/2020	Active	10073760
10073765	SCANDINAVIAN AVIONICS DESIGN ApS			AS 355 NP AS 355 N AS 355 F2 AS 355 F1 AS 355 F AS 355 E	Installation of Garmin GTN650H (Option A/IFR) and GNS430W (OptionB/VFR).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Document List 2112809 DOC, issue 01, dated 10 July 2020.Rotorcraft Flight Manual Supplement for GTN650, 2112809-AMA, issue 5,dated 10 July 2020Rotorcraft Flight Manual Supplement for GNS430, 2112809-AMB, issue 1,dated 02 July 2020OSD compliance 2112809-OS, issue 3, dated 14 January 2019.Refer to:APP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/07/2020	Active	10073765
10073770	SABENA TECHNICS BGC			A340-643 A340-642	OAE installation and Ka-band & Wifi systems activation on AirbusA340-600CJ	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-01-10060641 Vibration/buffetingcompliance criteria for large external antenna installationthe following paragraph (s) at a later amendme...	- Master Data List, Aeroconseil document No. 0850-01-A-MDL-R00, dated 10July 2020;- Instructions for Continued Airworthiness, Aeroconseil document No.0850-01-A-ICA-R01, dated 01 July 2020;- Airplane Flight Manual Supplement, Aeroconseil document No. 0850-01-A-AFMS-R00< (>,<)> dated 03 June 2020or late...	Limitations as per §3 of Instructions for Continued Airworthinessdocuments and §3 of Airplane Flight Manual Supplement documentreferenced above.Accomplishment of this STC requiresthe previous or simultaneousaccomplishment of the followingmodifications:- Mechanical and Electrical provisions installa...	13/07/2020	Active	10073770
10073778	DUNCAN AVIATION, INC.		FAA STC ST01759WI	BD-100-1A10	Installation of a R/H FWD Cabin Pocket Door	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01759WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Duncan Aviation, Inc. STC Master Document List, Document No.EDOC-0000017465, Revision A, dated 5 September 2014, or later FAAapproved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/07/2020	Active	10073778
10073783	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST545CH-D	MYSTÈRE-FALCON 20 - F5 MYSTÈRE-FALCON 20 - E5 MYSTÈRE-FALCON 20 - D5 MYSTÈRE-FALCON 20 - C5 MYSTÈRE-FALCON 200 FAN JET FALCON SÉRIES F FAN JET FALCON SÉRIES E FAN JET FALCON SÉRIES D FAN JET FALCON SÉRIES C	Installation of an AlliedSignal Avionics, Dual GNS-XLS Flight ManagementSystem, with GPS as a primary means of navigation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST545CH-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Garrett Aviation Services, Drawing List DL545, dated 16 October 1996, norevision, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/07/2020	Active	10073783

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073786	AIRWOLF FILTER CORP		FAA STC SE100WE	E185-1/-3/-8/-9/-11	Installation of Oil Filter Adapter and Oil Filter	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SE100WE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origi...	FAA sealed Lew Gage Company Drawing List Report No. 1, dated 5 May 1983,or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/07/2020	Active	10073786
10073798	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST93CH-D	MYSTÈRE-FALCON 20 - F5 MYSTÈRE-FALCON 20 - E5 MYSTÈRE-FALCON 20 - D5 MYSTÈRE-FALCON 20 - C5	Modification of the landing gear warning system on aircraftmodifiedwith Garrett TFE731 engines and equipped with Collins ADC-85 Air DataComputers, to inhibit landing gear warnings above 160 knots.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST93CH-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	AlliedSignal Services drawing M453005, dated 1 July 1993, no revisions,or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/07/2020	Active	10073798
10073816	GARMIN INTERNATIONAL, Inc.	REV. 5	FAA STC SA01899WI	SEE FAA AML AG-5B AA-5B AA-5A AA-5 AA-1C AA-1B AA-1A AA-1	Installation of Garmin G3X Touch Electronic Flight Instrument SystemRev. 3:- Adds 14 CFR 23.1309(d) Amdt 23-62, adds 14CFR 23.2000, 23.2005,23.2010 Amdt. 23-64 to the certificate.- Adds Cessna 305A/B/C/D/E/F, AS 202/15 “Bravo”, AS 202/18A“Bravo”,AS202/18A4 “Bravo”, FS2002 PA-14, Stinson V-77, Text...	See Appendix of STC dated 20 February 2024.	Installation in accordance with Garmin Master Drawing List (MDL) 005-01320-00, Revision 1,dated March 15, 2019.Operate in accordance with Garmin G3X Airplane Flight Manual Supplement190-01754-01, Revision 1,dated March 15, 2019, and EASA Flight Manual Supplement ref 190-01754-02Rev 1, dated July 2020...	Installation of the version of the GMA 245R with P/N 011-03784-11(010-01471-12) is not approved as part of this STC. Previous P/N of theGMA 245R are still authorized.Prior to installation of this change/ repair it must be determined thattheinterrelationship between this change/repair and any otherpr...	11/03/2025	Active	10073816
10073820	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR11245DS	407	Installation of G1000NXi Glass Cockpit Upgrade	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11245DS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Drawing List, Report No. AA-17049, Revision D, dated29 October2019, or later FAA approved revision.AeronauticalAccessories Instructions for Continued Airworthiness,ReportNo. AA-17057, Revision A, dated 19 March 2019, or later FAAaccepted revision.Aeronautical Accessories Rotorcraft FlightA...	Eligible for installation on S/N 53000 to 53138, 53140 to 53279, 53281to 53470, 53472 to 53900, 53911 to 54299.Prior toinstallation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce...	16/07/2020	Active	10073820
10073830	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD	REV. 1		BD-700-1A11 BD-700-1A10	Bullet fairing replacementReplacement of the existing Bombardier OEM top-mid fairing of the bulletfairing with a new top-mid fairingP/N 90402560-01.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List, DECA Aviation Engineering Ltd. document MDL18005,Revision 1, dated 17 May 2019Instructions for Continued Airworthiness, DECA Aviation Engineering Ltd.document ICA18005, Revision 1, dated 14 May 2019or later revisions of the above listed document(s) approved/accepted onbehalf of EAS...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/04/2021	Active	10073830

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073840	AMAC AEROSPACE SWITZERLAND AG			A319-133	Cabin ReconfigurationThis Interior Outfitting Project includes a reconfiguration of thepreviously installed forward VIPcabin to install a bedroom and lavatoryas well as the refurbishment of the Business Class area by replacing theseats and installing new monuments including a standard lavatory.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: The followingparagraphs of CS-25 Amendment 23 are applicable to the change: CS25.603; CS 25.788; CS 25.811; CS 25.812; CSC...	The change is defined with Revision C of Master Data List documentMDL-CF12-2500.The Aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplement document AFMS-CF12-2500.The Aircraft shall be maintained in accordance with Revision A ofInstructions for Continued Airwort...	EASA STC Nr 10039943 must be embodied on the aircraft priorto theinstallation of this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect up...	21/07/2020	Active	10073840
10073842	LUFTHANSA TECHNIK AG	REV. 2		SEE EASA APPROVED MODEL LIST	Installation of Thermo PadsThe Thermo Pad is a layer compound that is installed under the NonTextile Floor (NTF) to provide electrical heating. The Pad warms up theFloor Panel, when connected to electrical power.Revision 1: Editorial correctionsRevision 2: Extended applicability (Airbus A320-253N, A...	See associated AML.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact onthe noise database.	See associated AML<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	28/06/2023	Active	10073842
10073843 (ENAC REF. 02/171146/SPA)	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC SA972GL-D	MYSTÈRE-FALCON 20 - F5 MYSTÈRE-FALCON 20 - E5 MYSTÈRE-FALCON 20 - D5 MYSTÈRE-FALCON 20 - C5	Relocation of three computer emergency batteries (two optionalinstallations)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	AlliedSignal Aerospace Company, Garrett General Aviation ServicesDivision drawing list DL972, no revision, or later FAAapprovedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/07/2020	Active	10073843
10073844 (ENAC REF. 02/171142/SPA)	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC SA974GL-D	2. MYSTÈRE-FALCON 20 - F5 2. MYSTÈRE-FALCON 20 - E5 2. MYSTÈRE-FALCON 20 - D5 2. MYSTÈRE-FALCON 20 - C5 1. FAN JET FALCON SÉRIES G 1. FAN JET FALCON SÉRIES F 1. FAN JET FALCON SÉRIES E 1. FAN JET FALCON SÉRIES D 1. FAN JET FALCON SÉRIES C	Installation of cabin interior panels consisting of the headliner,window panels and sidewalls	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Garrett General Aviation Services Division drawing list DL974, norevision, dated 22 August 1989, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/07/2020	Active	10073844
10073845 (ENAC REF. 02/171144/SPA)	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC SA980GL-D	3. MYSTÈRE-FALCON 20 - F5 3. MYSTÈRE-FALCON 20 - E5 3. MYSTÈRE-FALCON 20 - D5 3. MYSTÈRE-FALCON 20 - C5 2. MYSTÈRE-FALCON 200 1. FAN JET FALCON SÉRIES G 1. FAN JET FALCON SÉRIES F 1. FAN JET FALCON SÉRIES E 1. FAN JET FALCON SÉRIES D 1. FAN JET FALCON SÉRIES C 1. FAN JET FALCON	Installation of a Master Caution/Warning Panel	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Garrett Aviation Services drawing list number 70-9000-001<(>,<)>norevision<(>,<)> dated 21 November 2000, or later FAAapproved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/07/2020	Active	10073845

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073846 (ENAC REF. 02/171141/SPA)	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST94CH-D	MYSTÈRE-FALCON 20 - F5 MYSTÈRE-FALCON 20 - E5 MYSTÈRE-FALCON 20 - D5 MYSTÈRE-FALCON 20 - C5	Installation of a Collins TCAS-94 Traffic and Collision Avoidance SystemTCAS II with dual Collins TDR-94D Mode "S" Transponders	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Garrett Aviation Services drawing list DL438002, dated 14 April 1993,revised 16 July 1993, no revision, or later FAAapproved revision.2. Airplane Flight Manual Supplement dated 29 July 1993, no revision, orlater FAA approved revision.3. Aircraft with configuration -02 as identified in DL438002 m...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/07/2020	Active	10073846
10073847	AIRBORNE TECHNOLOGIES GmbH			DHC-6 SERIES 400	STC-AT-141, DHC-6 ISR ConfigurationThe aircraft is modifiedwithin this change as Intelligence,Surveillance, and Reconnaissance Demonstrator (ISR). The SCAR Pod[141-5400-00-01] installed on Pylon under RH wing.This change certifies the installation of following systems and parts onthe aircraft:the P...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:- following paragraphs at CS 23, Amdt 1: CS 23.21, SC 23.29, CS 23.45,CS 23.49, CS 23.51, CS 23.53, CS 23.63, CS 23.65, CS2...	Flight Manual Supplement for DHC-6 Series 400, ISR CONFIGURATION,Document Number STC-141-G-AFM, Rev. 0Maintenance Manual Supplement for DHC-6 Series 400, STC-AT-141, ISRCONFIGURATION, Document Number STC-141-G-AMM, Rev. 0Installation Instruction STC-AT-141 DHC-6 ISR CONFIGURATION, DocumentNumber STC...	IKHANA DHC-6 Wing Payload Hard Points must be installed (EASA STC No. 10061190).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	21/07/2020	Active	10073847
10073853	SOCIETE AIR FRANCE S.A.	REV. 2		SEE EASA APPROVED MODEL LIST	Portable Halon-free Fire ExtinguishersReplacement of portable Halon fire extinguishers by Halon-free fireextinguishers (UMLAUT HAFEX) on Air France fleetRevision 1 of this STC adds Boeing 777-200, 777-300ER and 777Faeroplanes to the Approved Model List Applicability.Revision 2 adds Air Tanker A330-2...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment : See EASA ApprovedModel ListThe requirements for environmental protection and the associatedcertified noise and/ or emissi...	Societe Air France S.A. Change Approval Sheet CAS-ACFT-20-001 Revision 1Societe Air France S.A. Service Bulletin ACFT 20 001 26-001 (A320Family) Societe Air France S.A. Service Bulletin ACFT 20 001 26-002 (A330-203) Societe Air France S.A. Service Bulletin ACFT 20-001-26-003 (Boeing 777)Societe Air Fr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/03/2023	Active	10073853
10073864	AIRWOLF FILTER CORP		FAA STC SE4493NM	O-435-A2 O-435-A GO-435-C2E GO-435-C2B2 GO-435-C2B1 GO-435-C2B GO-435-C2	Installation of oil filter adapter and oil filter	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SE4493NM.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	FAA sealed Sunrise Filters, Inc. Master Drawing List, Drawing No. 2000,dated 1 September 1984, Revision N/C, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/07/2020	Active	10073864
10073868	AIRWOLF FILTER CORP		FAA STC SA00079NY	SEE FAA AML	Installation of Airwolf remote mounted engine oil filter Kit AFC-K008 onsingle or multi engine fixed wing light aircraft incorporating TeledyneContinental reciprocating engines of450 horsepower or less.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00079NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Airwolf Instructions for Continued Airwotthiness, AFC-K000-ICA, RevisionIR, dated 5 July 2012, or later FAAaccepted revision.	Engine compartment firewall for mounting oil filter shall be of 0.021inch minimum thickness ASTM A527 galvanized steel or equivalent (Ref.CAR 3.624(b), FAR 23.1191 (h)).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any othe...	23/07/2020	Active	10073868

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073874	AIRWOLF FILTER CORP		FAA STC SE4494NM	GO-480-G2F6 GO-480-G1J6, GO-480-G2D6 GO-480-G1D6, GO-480-G1H6 GO-480-F4A6, GO-480-F6 GO-480-F1A6, GO-480-F2A6 GO-480-C2C6,GO-480-C2D6 GO-480-B, GO-480-B1A6, GO-480-B1D, GO-480-C1D6 GO-480-B1B, GO-480-B1C	Installation of oil filter adapter and oil filter	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SE4494NM.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	FAA scaled Sunrise Filters, Inc. Master Drawing List, Drawing No. 2000,dated 1 September 1984, Revision N/C, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/07/2020	Active	10073874
10073881	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST02313CH	A320-214 A319-112, A319-114, A319-115	Installation of Satellite TV System Provisions	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 at amdt. 0: 25.23 (a)(b), 25.29(a)(b), 25.251 (a)(b)(c)(d)(e),25.301(a)(b)(c), 25.303, 25.305(a)(b), 25.307(a), 25.36...	Armstrong Aerospace Master Data List, Doc. No. DC104-3101-00, RevisionY, dated 26 May 2015, or later FAA approved revision.Armstrong Aerospace Instructions for Continued Airworthiness Doc. No. DC113-3101-00, Revision E, dated 26 May 2015, and FAA approved 29 May2015, or later FAA approved revisions....	The Satellite TV system equipment for which these provisions areintended is not covered by this approval: an additionalapproval isrequired for the installation of this equipment.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair an...	15/01/2021	Active	10073881
10073889	LIBELLULE MONDE INC.	REV. 1	TCCA SA18-22	SEE EASA APPROVED MODEL LIST SEE ATTACHED AML	Installation of exterior placards, graphics, labels and signsThis STC installs exterior placards, graphics, labels and signs. Thesemarkings include printed polymer, self-adhesive graphics on the exteriorof the aircraft that may be information placards, identification labelsor custom signs for operat...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 amdt 11: 25.1, 25.601, 25.603, 25.605, 25.609, 25.611,25.1301,25.1309, 25.1501, 25.1529.The requirements for envir...	Master Drawing List MDL-PA-15-006 Rev MLibellule Instructions for Continued Airworthiness No. ICA-PA-17-025Revision Corlater revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Installation and servicing instructions as per ICA document.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the pro...	14/08/2023	Active	10073889
10073891	AVIATION FABRICATORS, Inc.			F90 C90, C90A, E90, H90 B200C, B200CT, B200T 200, 200C, 200CT, 200T, B200	Part Fabrication and Installation of Arm Ledge System and Table Assemblyfor aircraft cabin interior.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Aviation Fabricators, Inc., Master Drawing List, AF-268MDL,Rev (B),dated 16 June 2011,Or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/07/2020	Active	10073891
10073893	ANCRA INTERNATIONAL LLC	REV. 2	FAA STC ST02727LA	A321-231/-232 A321-211/-212/-213	Installation of cargo loading systemRevision 1: Adding of models A321-211/-212/-213/-232 to theapplicability list.Revision 2: Adding of models A321-231 back to the applicability list	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 at amdt 16: 25.29(a)(b), 25.625(a)(b), 25.1557 (a), 25.305(a)(b),25.561, 25.613 (a)(b), 25.853, 25.855, 25.1301(a)(1)(2)...	FAA approved Ancra International LLC Controlled Data List DL85550,Revision G, dated 3 February 2020, or later FAA approved revision.Instructions for Continued Airworthiness, Report Number 10551, RevisionB, or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.EASA STC 10071994 (FAA STC ST04493NY) must be installed...	03/11/2022	Active	10073893

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073895	AIRWOLF FILTER CORP		FAA STC SA01406NY	SEE FAA AML	Installation of Airwolf remote mounted engine oil filter kit AFC-K017 onsingle and multiengine fixed light aircraft androtary wing aircraftincorporating Curtiss-Wright, Jacobs, Kinner<(>,<)> Ranger, Warner andWSK PZL Kalisz reciprocating engines.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01406NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Airwolf Instructions for Continued Airworthiness, AFC-K000-ICA, RevisionIR, dated 5 July 2012, or later FAA accepted revision.	Airwolf Oil Filter AFC-600 (Champion) is included as part ofInstallation Kit AFC-K017.Engine Compartment Firewall for mounting oil filter shall be of 0.002linch minimum thickness ASTM A527 galvanized steel or equivalent [Ref.CAR 3.624(b), 14 CFR Part 23.119(h)].Prior to installation of this change/r...	28/07/2020	Active	10073895
10073896	LUFTHANSA TECHNIK AG			CL-600-2B19 (RJ SERIES 100)	“Challenger” Replacement of gaseous passenger oxygen system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplemental Type Design Document STDD35-19/01Mv Iss/Rev 01/00Instruction for Continued Airworthiness A-00-05/9876 Iss/Rev 01/00Airplane Flight Manual A-00-06/461-AFM Iss/Rev 01/04or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/07/2020	Active	10073896
10073900	AIRWOLF FILTER CORP		FAA STC ST01282NY	SEE FAA AML	Installation of Airwolf remote mounted engine oil filter kit AFC-KO 15on aircraft powered by Pratt & Whitney radial reciprocating engineSeries R-985, R-1340 and R-1830.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01282NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Airwolf Instructions for Continued Airworthiness, AFC-K000-ICA, revisionIR, dated 5 July 2012, or later FAA accepted revision.	1. Airwolf Oil Filter Model AFC-600 (Champion) is eligible only withR-985 series engines. 2. Airwolf Oil Filter Model AFC-700 (Fram) is eligible on R-985, R-1340and R-1830 series engines.3. Engine compartment firewall for mounting oil filter shall be of 0.021inch minimum thickness ASTM A527 galvanize...	29/07/2020	Active	10073900
10073903	SEATON ENGINEERING CORPORATION		FAA STC SA01861SE	SEE FAA AML	Installation of Landing Light Controler	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01861SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Seaton Engineering Corporation Master Drawing List as listed on AMLSA01861SE.Instructio ns for Continued Airworthiness (ICA), Document Number9150-008, Revision D, dated 25 June 2013, or later FAA acceptedrevision.FAA approved Aircraft Flight Manual Supplement as listed on AMLSA01861SE.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	29/07/2020	Active	10073903
10073934	BOGGI AERONAUTICS S.R.L.			EC635 T3 EC635 T2+ EC635 T1 EC635 P3 EC635 P2+ EC135 T3 EC135 T2+ EC135 T2 EC135 T1 EC135 P3 EC135 P2+ EC135 P2 EC135 P1	Cabin control console and electrical system installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: :CS 27 Amdt. 4 for27.1, 27.21, 27.25, 27.27, 27.29, 27.301, 27.303, 27.305, 27.307,27.309, 27.321, 27.337, 27.339, 27.341...	- 135P00100-FMS-01 Flight Manual Supplement, Issue 1- 135P00100-Mdl-05 Master Document List, Issue 5or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Installation of STC EASA.IM.R.S.01490 Air Film Camera System is aprerequisite.- Safety issues constituted by lasers classified 3B or 4 according tolaser class table of EASA CM-AS-006 are not in the scope of thisapproval.Prior to installation of this change/repair it must be determined thatthe inte...	31/07/2020	Active	10073934
10073941	SIRIUM AEROTECH S.L.			MYSTÈRE FALCON 900 (MF900)	EFIS, FMS and Datalink Upgrades for Falcon 900 AirplanesUpgrading Falcon 900B avionics by replacing existing FMS by UNS-1Fw andexisting EFIS by UASC Electronic Flight Displays EFI-890R. AdditionallyCPDLC, FANS 1/A+ and ADS-C Datalink capabilities will be added byinstalling new UL-801 Communication M...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): ASA CRI F-04 HIRF ProtectionElectronic EquipmentIssue 3The requirements for environmental protection and the associatedcertified noise and/ or emiss...	MASTAER DATA LIST SA19-01S-MDL Rev. 01SA19-01S-AFMS-EFIS Rev. 00SA19-01S-AFMS-VIS Rev. 00SA19-01S-AFMS-FMS Rev. 00SA19-01S-AMMS Rev. 00SA19-01S-MMELS Rev. 00Or later revisions of the above listed document(s) approved/acceptedunder the EASAsystem.	SA19-01S-AFMS-EFIS REv.00, SA19-01S-AFMS-VIS Rev. 00, SA19-01S-AFMS-FMSRev. 00Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwor...	03/08/2020	Active	10073941

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073943	NORTHWEST AEROSPACE TECHNOLOGIESINC.			A320-251N, A321-251NX	Head Injury Criterion compliance modifications	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25 amdt. 15:25.562(c)(5)(6)The requirements for environmental protection and the associatedcertified noise and/ or emiss...	Master Drawing List N0683-D10 rev – Instructions for Continued Airworthiness N0683-D70 rev –or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The installation of one of the cabin layouts defined by thefollowingdocuments is a prerequisite:-A320 Airbus document 320-25.47770 rev A-A321 Airbus document 321-25.50938 rev APrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andp...	05/08/2020	Active	10073943
10073948	HELI AUSTRIA GmbH			212	Installation of a dual GTN 750 COM/NAV/ GPS including a GTX 345transponder and a GRA5500 Radar Altimeter	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The CertificationBasis for the original product as amended by thefollowing additional or alternative airworthiness requirements:Special Condition (s): Non-rechargeable Lithium Battery Installations(...	- Rotorcraft Flight Manual Supplement, HAU-D-048-005, Rev. 0- Master Document List, HAU-D-048- 001, Rev 0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This change is only applicable to helicopters:without the following:- TARSYN System-Helipilot and Flight Director System.with the following:- Dart D212-722 Avionic Console, covered by EASA STC EASA.IM.R.S.01181- EAGLE Vertical Reference Door LBA EMZ RC1137- Installation of Mid Continent 4300-311 At...	04/08/2020	Active	10073948
10073951	SAFRAN CABIN GERMANY GmbH	REV. 1	FAA ST10930SC	737-900ER, 737-8/-9 737-500/-600/-700/-800/-900 737-100/-200/-200C/-300/-400	Installation of a TIA Air Coffee MK-1 coffee maker (model 400-2153-01) Revision 1: Transfer of certificate to Safran Cabin Germany GmbH	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmental protectionand the associated certified noise and/ or emissions levels of theoriginal product are unchanged and remain applicable to thiscertificate/ approval.	Master Drawing List OT-CB-0113 rev BICA document OT-CB-097 rev AElectrical Loads and weight OT-CB-096 rev AAir Coffee MK1 assembly Interface 400-2153 rev C	The coffee maker is only interchangeable with “ATLAS” coffee makers.Overall envelope, clearances are found in drawing 400-2153.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	07/12/2020	Active	10073951
10073953	SAFRAN CABIN GERMANY GmbH	REV. 1	FAA ST03239NY	CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700, 701, 702) CL-600-2B19 (RJ SERIES 100)	Replacement of existing coffee makers and mounting rails with TIAAirCoffee PX coffeemakers and mounting railsRevision 1: Transfer of certificate to Safran Cabin Germany GmbH.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- TCDS amended by following requirements at CS-25 Amendment 10: 25.29,25.301, 25.303, 25.305, 25.601, 25.603, 25.605, 25.609, 25.611, 25.613,25.625, 25.789, 25.869, 25.130...	Master Drawing List ST-CB-018 rev 1ICA document ST-CB-025 rev 1Electrical Loads Statement ST-CB-024 rev 1Weight and ArmStatement ST-CB-023 rev 1Specification Control drawing Air Coffee PX/Rail 400-2197 rev A	The coffee maker is only interchangeable with “ATLAS” coffee makers.Overall envelope, clearances are found in drawing 400-2197.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	07/12/2020	Active	10073953
10073966	SAFRAN CABIN GERMANY GmbH	REV. 1	FAA ST03493NY	767-300F	Installation of Zodiac Executive Aircraft Inserts Model AirCoffee Makerand RailsRevision 1: Transfer of certificate toSafran Cabin Germany GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- TCDS amended by following requirements at CS-25 Amendment 16: 25.301,25.303, 25.305, 25.307, 25.561, 25.601,25.603, 25.605, 25.609, 25.611,25.613, 25.625, 25.789, 25.85...	Master Drawing List ST-CB-041 rev 2ICA document ST-CB-049 rev 1Electrical Loads Statement ST-CB-046 rev 1Weight and ArmStatement ST-CB-053 rev 1Specification Control drawing Air Coffee PX/Rail 400-2197 rev A	The coffee maker is only interchangeable with “ATLAS” coffee makers.Overall envelope, clearances are found in drawing 400-2197.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	07/12/2020	Active	10073966
10073968	AIR PROJET	REV. 1		CAP10B CAP10	Installation of Ruder Hand controlREV 1: Modification of the braking system	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	-Master Document List APMDL-0030 Revision 05 dated 11 October 2022-Compliance Document APMOD-0030 Revision 05 dated 21 September 2022Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/10/2022	Active	10073968

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073970	DRF STIFTUNG LUFTRETTUNGG EMEINNUETZIGE AG			MBB-BK117 D-2 MBB-BK117 C-2	Installation of Multifunction EMS Groundplate.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-29 Amdt. 4:29.1, 29.21, 29.25, 29.27, 29.29, 29.251, 29.303, 29.305, 29.307,29.337, 29.561, 29.601, 29.603, 29.605, 29....	Certification Program, Document No. CP-117-25-50-00001 Rev. 01;Master Document List, Document No. MD-117-25-50-00049 Rev. 03;Installation manual, Document No. IM-117-25-50-00019 Rev. 00;Instructions for Continued Airworthiness, Document No.CA-117-25-50-00050 Rev. 00;Flight Manual Supplement, Documen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/08/2020	Active	10073970
10073971	AIRWOLF FILTER CORP		FAA STC SA00433NY	SEE FAA AML	Installation of Airwolf remote mounted engine oil filter AFC-K010 onsingle and multi-engine fixed wing light aircraft and rotary wingaircraft incorporating Franklin reciprocating engines of 450 horsepoweror less. Oil filter kit and installation instructions are specified inthe attached Approved Mode...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00433NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Airwolf Instructions for Continued Airworthiness, AFC-K000-ICA, RevisionIR, dated 5 July 2012, or later FAA accepted revision.	Engine compartment firewall for mounting oil filter shall be of .021inch minimum thickness ASTM A527 galvanized steel or equivalent (Ref.CAR 3.624(b), 14 CFR PART 23.1191(h)).Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and an...	05/08/2020	Active	10073971
10073973	JET AVIATION AG			GIV-X	Oxygen Overboard Discharge IndicatorThis STC covers the installation of a medical oxygen overboard dischargeindicator installed on the fuselage between FS 193 and 257.5 and betweenstringers S19 and S20 LHS.There are no oxygen lines or equipment installed as part of this STC.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	AFM Supplement: JBSL-M-01435AFM-01 Issue 01Instructions forContinued Airworthiness: JBSL-M-01435ICA-01 Issue 4Or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/08/2020	Active	10073973
10073974	JET AVIATION AG			GIII (G-1159A)	GPS Antenna Structural Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: the followingparagraphs of CS 25 at amendment 24: CS 25.23, CS 25.25, CS 25.251, CS25.301, CS 25.303, CS 25.305, CS 25.30...	Master Data List, JBSL-M-03533MDL-001, Issue BDrawing List (Mechanical), JBSL-M-03533DLM-001, Issue AEngineering Order,JBSL-M-03533ENO-001, Issue AInstructions for Continued Airworthiness, JBSL-M-03533ICA-001, Issue AOr later revisions ofthe above listed document(s) approved/acceptedunder the EASA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/08/2020	Active	10073974
10073980	AEROSPACE DESIGN & COMPLIANCE LLC		FAA STC ST04187NY	400, 400A	Installation of Encode Engine Data Acquisition Unit & Ionode DigitalData Recorder on Textron Aviation Aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04187NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Aerospace Design & Compliance(1) Master Data List BE40-MDL-0399, Revision IR, dated 12 March 2019, orlater FAA approvedrevision.(2) Instructions for Continued Airworthiness (ICA)BE40-ICA-0039,Revision IR, dated 20 November 2019, or laterFAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/08/2020	Active	10073980
10073983	SAFRAN CABIN GERMANY GmbH	REV. 1	FAA ST09858SC	EMB-145LR, EMB-145MP EMB-145EP, EMB-145ER EMB-135ER, EMB-135LR	Installation of Cabin Automatic Coffee Brewing SystemRevision 1: Transfer of certificate to Safran Cabin Germany GmbH	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	TIA Master Drawing List 300-1751, Rev. L, dated 18 August 2005.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/12/2020	Active	10073983

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10073985	ST ENGINEERING AEROSPACE LTD.	REV. 1		A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-243F A330-243 A330-223F A330-223/-243 A330-202 A330-201/-202/-203 A330-201	Additive Manufacturing Replacement PartsThis project is to replace existing Housing Assembly (PartNumberF252R4155-202-00) on A330P2F with a part designed and manufactured using Additive Manufacturing techniquesRevision 01: Scope extension for a part designed and manufactured usingFLM technique.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Certification Plan for Major Change to A330P2F STC for Housing Assembly Ref.: AM/QAD/001 Rev. A. dated 10 June 2020-STATEMENT OF COMPLIANCE Ref.: DOA/ 2020/027 dated 08 July 2020-Certification Program for the addition of another alternative AM partmade using FLM technique for a Housing Assembly Ref....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/08/2021	Active	10073985
10074002	PMV ENGINEERING	REV. 2		ATR 72-212 A ATR 42-500	Medical Evacuation Operation for Air TahitiRev. 1: Typo CorrectionRev. 2: Typo Correction	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-01/60073802 Medical evacuation configurationThe requirements for environmental protection and the associatedcertified noise and/ or emissions level...	- Master Document List CAB-03920-MDL-R03 dated 11 August 2020-AFM Supplement CAB-03920-AFMS-R00 dated 20 July 2020or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Installation of stretcher carrier per EASA STC EASA.IM.A.S. 0139 andService Bulletin CAB-03920-SB on ATR-72 aircraft arepre-requisites forthis installation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously i...	04/06/2021	Active	10074002
10074003	WAYPOINT AEROTEC LIMITED		CAA UK RESPONSIBILITY	737-400	Suppression of the EGPWS Aural WarningThis change involves a modification to achieve temporary suppression ofthe EGPWS aural warning on aircraft fitted with an Oil Dispersant SpraySystem (ODSS) in accordance with EASA STC 10066473 (FAA STCST02676LA).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25.29(b), 25.601,25.603, 25.831, 25.853, 25.863, 25.1301,25.1302, 25.1309, 25.1351,25.1357, 25.1360, 25.1529, 25.158...	WAL-MDL-066 issue 1 – Master Data ListWAL-AFMS-066 Issue 2 – Airplane Flight Manual Supplementor later revisions of theabove listed document(s) approved/ acceptedunder the EASA system.	- In accordance with AFM Supplement- EASA STC 10066473 (FAASTC ST02676LA) “Palletized Aerial Dispensing ofLiquids Tanker Conversion Program” and EASA STC 10015921 (FAA STCST00389SE) “Installation of the Honeywell Enhanced Ground proximityWarning System (EGPWS) and Runway Awareness & Advisory System...	11/08/2020	Active	10074003
10074015	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA STC ST04039AT-D	GV	Installation of Honeywell CD-830 Control Display Units (CDU) onGulfstream Model GV aircraft in accordance with Gulfstream AerospaceCorporation Index List CE51 1188002, Revision D,dated July 19, 2016.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25.1302 amdt 13The requirements for environmental protection and the associatedcertified noise and/ or emissions levelsa...	The Airplane Flight Manual Supplement, CE51 118M002, Revision (-), datedJuly 15, 2016.The Instructions for Continued Airworthiness, CE51 118A004, Revision(-), dated February 17, 2016.or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technica...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/08/2020	Active	10074015
10074016	SAFRAN CABIN GERMANY GmbH	REV. 1	FAA ST02856NY	767-300F, 767-400ER 767-200, 767-300	Installation of a TIA Model 1547 Convection Oven, part number400-2286-01Revision 1: Transfer of certificate to Safran Cabin Germany GmbH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:- JAR25 Change 13: 25.29, 25.307, 25.613, 25.1316, 25.1351- JAR25 Change 14: 25.305, 25.561<(>,<)>- CS25 Amdt 4: 25.603, 2...	- Master Drawing List ST-OV-007, Revision B- ICA document ST-OV-013 rev IR- Electrical Loads Statement ST-OV-012 rev A-Weight and Arm Statement ST-OV-015 rev A- Installation & Checkout Procedures ST-OV-11 rev B	Overall envelope, clearances as per document ST-OV-11.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product....	07/12/2020	Active	10074016
10074017	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04037AT-D	GIV	Installation of Honeywell CD-830 Control Display Units (CDU) onGulfstream Model G-IV aircraft in accordance with Gulfstream AerospaceCorporation Index List CE41 1188008, Revision A, dated March 31, 2016.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25.1302 amdt 13 andFAR25.1453(b) amdt 25-72The requirementsfor environmental protection and the associatedcertified noi...	The Airplane Flight Manual Supplement, CE41 118M006, Revision (-), datedMarch 31, 2016.The Instructions for Continued Airworthiness, CE41 118A004, Revision B,dated January 07, 2016.or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the TechnicalP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/08/2020	Active	10074017

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074019	SABENA TECHNICS BGC	REV. 1		A319-131/-132/-133 A319-111/-112/-113/-114/-115	Structure reinforcement for Ka-band antenna installation onFrame 53 onAirbus A319Rev. 1: - Extend the STC to cover a various smaller sizes of antennainstalled in pre-mod in FR58 - Remove the limitation attached to the existing“SBB”antenna installed in FR58.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.1 amdt.4 - CS 25.23 amdt.4 - CS 25.29 amdt.4 - CS 25.301 amdt.4 -CS 25.303 amdt.4 - CS 25.305 amdt.4CS...	- MDL 0887-02-A-MDL-R01 dated 04 February 2022- ICA 0887-02-A-ICA-R01, dated 03 August 2020or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limitation as per §3 of Instructions for Continued Airworthinessdocument referenced above.This STC, supplemented by present major change, is limited to either ofthe two configurations mentioned in paragraph 2.5 of the CP0887-02-A-CP-F01-R00 of 08 October 2021.Prior to installation of this change/rep...	10/02/2022	Active	10074019
10074020	AERO TWIN, Inc.		FAA STC SA02391AK	KODIAK 100	Installation of a Nose Gear Gravel Deflector, P/N NGDQ-100	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02391AK.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Aero Twin, Inc. Installation Instructions, Document No. NGDQ-IM,Original Issue, dated 10 October 2011, or later FAA approved revision.Instructions for Continued Airworthiness, Aero Twin, Inc. NGDQ-ICA,Original Issue, dated 10 October 2011,or later FAA approved revision.	The size must be 22 x 8.00-8.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	13/08/2020	Active	10074020
10074021	AIRBUS S.A.S.			A320-214	STANDALONE V/UHF SYSTEM INSTALLATIONMOD AI0095: Installation and activation of a V/UHF System on ACJ320ceo.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-4301-004The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unc...	-MAS AI0095 Issue 1-AIS-AJA-18088 issue 04 Certification Summaryor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/08/2020	Active	10074021
10074023	SABENA TECHNICS BGC	REV. 1		A319-131/-132/-133 A319-111/-112/-113/-114/-115	OAE installation on Frame 53 and Ka-band System Activation on AirbusA319Rev. 1: Cover a various smaller sizes of L-Band(SBB) antenna installedin pre-mod in FR58 - Remove the limitation associated to the existing“SBB” antenna installed in FR58.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-01-10057880 “Vibration/ buffetingcompliance criteria for large external antenna installation” issue 1.- The following par...	- MDL 0910-02-A-MDL-R01, dated 02 February 2022- AFMS 0910-02-A-AFMS-R01, dated 16 July 2020- ICA 0910-02-A-ICA-R02, dated 31 January 2022or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limitations as per §3 of Airplane Flight Manual Supplement documentreferenced above.Accomplishment of this STC requiresthe previous accomplishment of thefollowing modifications:-Mechanical and Electrical Provisions, Minor Change Approval0909-01-A-MCA-R03 or later approved revisions.- Aircraft stru...	10/02/2022	Active	10074023
10074025	AERO TWIN, Inc.		FAA STC SA02339AK	KODIAK 100	Installation of main gear gravel deflectors, P/N GDQ-100, on the mainlanding gear of the Quest Kodiak 100	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02339AK.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Data List, GDQ-100, Original Issue, dated 14 February 2009, orlater FAA approved revisions.Aero Twin, Inc.'s Instructions for Continued Airworthiness, DocumentNumber GDQ-100-ICA, Original Issue, dated 14 February 2009, or later FAAaccepted revisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Instructions for Continued Airworthiness, Aero Twin, In...	13/08/2020	Active	10074025
10074027	PRO STAR AVIATION, L.L.C.		FAA STC ST00395BO	BD-100-1A10	Installation of a Honeywell GoDirect Router	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00395BO.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Pro Star Aviation Installation Data List 05673-IDL-101, Revision B,dated 31 July 2020, or later FAA approved revision.Pro Star Aviation Airplane Flight Manual Supplement 05673-FMS-101,Revision B, dated 15 July 2020, or later FAA approved revision.Pro Star Aviation Instructions for Continued Airworth...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/08/2020	Active	10074027

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074041	GULFSTREAM AEROSPACE CORPORATION		ST04028AT-D	GVI (G650)	Installation of a TrueNorth Iridium Telephone/WLAN System in accordancewith Gulfstream Aerospace Corporation Index ListGDL100000015, Revision"-", dated July 14, 2015	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Airplane Flight Manual Supplement, CE61104M001, Revision "-", dated July14, 2015< (>,<)>Instructions for Continued Airworthiness GCD000002043, Revision A, datedJune 17, 2015or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implement...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/08/2020	Active	10074041
10074043	AMAC AEROSPACE SWITZERLAND AG			A320-273N A320-272N A320-271N/-272N/-273N A320-271N A320-253N A320-252N A320-251N/-252N/-253N A320-251N A320-233 A320-232 A320-231/-232/-233 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211/-212/-214/-215/-216 A320-211 A319-153N A319-151N/-153N A319-151N A319-133 A319-132 A319-131/-132/-133 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111/-112/-113/-114/-115 A319-111 A318-122 A318-121 A318-112 A318-111/-112/-121/-122 A318-111	Underwater Locator Beacon Battery ReplacementReplacement ofUnderwater Locator Beacon (ULB) battery of the CockpitVoiceRecorder / Flight Data Recorder. The new Lithium Type Battery hasimproved performance (P/N DK120/90) for 90 days duration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: The followingparagraphs of CS 25 Amendment 21CS 25.1, CS 25.601, CS 25.611, CS25.863, CS 25.869, CS 25.899, CS 25.1301, CS...	The change is defined through Revision A of Master Data List documentMDL-A3201-3130.Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This modification is applicable for “DK Series” (Dukane Corporation)Underwater Acoustic Beacon P/N DK100, DK100/90 or DK120 installations onthe Flight Data Recorder or/and CockpitVoice Recorder with mountingkits P/N N30A26 or N30A21A. This modification doesn’t cover theinstallation of mounting kits...	17/08/2020	Active	10074043
10074045	AMERICAN AVIATION Inc.		FAA STC SA02651SE	PC-12, PC-12/45, PC-12/47 PC-12/47E	Installation of ram air cowling	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02651SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	American Aviation, Inc.< (>,<)> Drawing List 012 TDL, dated 29 May 2019,or later FAA approved revision.American AviationRam Air Cowling Instructions for ContinuedAirworthiness Report 12-006, Revision N/ C, dated 24 June 2019, or laterFAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/08/2020	Active	10074045
10074046	AERO TWIN, Inc.		FAA STC SA02344AK	KODIAK 100	Manufacture and installation of nose gear tire scraper, P/NTSQ-100, onthe nose landing gear of the Quest Kodiak 100	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02344AK.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Data List, TSQ-100, Original Issue, dated 17 March 2009, or laterFAA approved revisions.Instructions for Continued Airworthiness, Aero Twin, Inc. DocumentNumber TSQ-100-ICA, Original Issue, dated 17 March 2009, or later FAAaccepted revisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/08/2020	Active	10074046

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074070	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT, LLC		FAA STC ST04214CH	400A	Installation of Automatic Dependent Surveillance - Broadcast (ADS-B) Outtransponder	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. Elliott Aviation Master Data List Doc. No. MDL-3671-560 Revision C< (>,<)> dated 18 May 2017, or later FAA approved revision.2. Flight Manual Supplement<(>,<)> Elliot Aviation Doc. No.FMS-3671-560, Revision IR, approved 19 May 2017<(>,<)> or later FAAapproved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/09/2020	Active	10074070
10074074	CORPORATION LOGIC AIR Inc.		TCCA SA19-31 ISSUE 2	737-800 737-700 737-600	Installation of GNSS with LPV Approach / ADS-B Systems	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-ACNS initial issue,Subpart D, Section 4The requirements for environmental protection and the associatedcertified noisea...	L782000 Rev. A – Modification Data SummaryL782091 Rev. NC –Aircraft Flight Manual SupplementL782092 Rev. NC – AircraftFlight Manual Supplementor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canad...	As required by Aircraft Flight Manual Supplement L782091 and/or L782092,as applicable to aircraft configurationPrior toinstallation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce...	20/08/2020	Active	10074074
10074090	GLOBAL AEROSPACE DESIGNCORPORATION		FAA STC ST04417CH	767-300	Data Link ACARS and CPDLCFully functional installation of the Data Link with Iridium System forAircraft Communications Addressing and Reporting System (ACARS) andController Pilot Data Link Communications (CPDLC).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-ACNS issue 2 forACNS.B.DLS.B1.001/005/010/015/020/025/030/035/040/050/055/060070/075/080/085/090/095/100/105/110/115/120/125The requirements for environmental protectio...	- Global Aerospace Design Corp document “EASA CertificationSummary”ref. 18GR164-ECS-2 Rev: C- Global Aerospace Design Corp document “Master Drawing List” ref.18GR164-MDL-2 Rev: L- Global Aerospace Design Corp document “Airplane Flight ManualSupplement” ref. 18GR164-AFM-2 Rev A- Global Aerospace Des...	Requires prior installation of STC 10072057 “Provisional installation ofthe Envoy Data Link with Iridium system for Aircraft CommunicationsAddressing and Reporting System (ACARS) and Controller Pilot Data LinkCommunication (CPDLC)”.Prior to installation of this change/repair it must be determined th...	24/08/2020	Active	10074090
10074092	PILATUS BUSINESS AIRCRAFT, Ltd.		FAA STC SA01003DE	PC-24	Avance L3 system installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01003DE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Document List for Avance L3 in a PC-24, 24-1806-01-0000, RevisionA, dated 22 June 2020, or later FAA approved revisions.Flight Manual Supplement for installation of the Avance L3 System,Document No. 24-1806-65-0000, Revision IR, dated 17 June 2020, or laterFAA approved revision.Instructions f...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/08/2020	Active	10074092
10074094	JET AVIATION AG	REV. 3		A319-153N	VVIP Cabin Interior CompletionThis modification installs a VVIP Cabin Interior into a green AirbusA319-153N.The aircraft will be outfitted to accommodate 2 Cabin Crew and 19Passengers and can be operated non-commercial (private) as well ascommercial. Two aircraft configurations are possible to be in...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI F-4306 Security Protection of AircraftSystems and Networks.- The following paragraph(s) at a later amendment:CS 25 amendment 22: 2...	JBSC-M-00180MDL-01 ISSUE L MASTER DATA LISTBASELINE CONFIGURATION:JBSC-M-00180AFM-01 ISSUE E AIRPLANE FLIGHT MANUAL SUPPLEMENTJBSC-M-00180ICA-01 ISSUE A INSTRUCTIONS FOR CONTINUEDAIRWORTHINESSJBSC-M-00180MEL-01 ISSUE B MASTER MINIMUM EQUIPMENT LIST SUPPLEMENTJBSC-M-00180CCS-01 ISSUE E CERTIFICATION...	Non-Smoking Aircraft. Applicable to Baseline Configuration only: As nocompliance demonstration with the certification basis for OSDconstituents CCD and FCD has been performed, theaircraft is not allowedto be registered in any EASA member state without demonstration ofcompliance to OSD CCD and FCD r...	10/03/2023	Active	10074094

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074112	DOA21 LIMITED	REV. 1		A320-251N	Introduction of a VIP Cabin InteriorRev. 1: Transfer of STCholder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:CS 25 Amendment 24:25.78825.85625.1365Appendix S:S25-1, S25-10, S25-20, S25-30, S25-40, S25-50The requirement...	EASA Approved:STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0164 Issue 1STC Twenty One Ltd Maintenance Manual/AWL Supplement No. S21.AMMS-0072Issue 1STC Twenty One Ltd Cabin Crew Data Manual No. S21.CCD-0001 Issue 2EASA Accepted:STC Twenty One Ltd Master Document List No. S21. MDL-1501 Is...	This design change (S21.25-03-1683) installs external doublers on thefuselage belly skin between frames C28-C29 and C33-C34 which obscure theGVI required by task 532165-01-1 of Airbus ALS Part 2 Revision 08, asmandated by EASA AD 2020-0036R1. The inspections contained in theAirworthiness Limitations...	24/10/2023	Active	10074112
10074113	ANCRA INTERNATIONAL LLC		FAA STC ST02733LA	A321-231/-232 A321-211/-212/-213	Installation of lower cargo deck loading system	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ancra International LLC Controlled Data List DL87620, Revision M, dated20 August 2020, or later FAA approved revision.Airplane Flight Manual Supplement 11240, Revision A, dated 20August2020, or later FAA approved revision.Instructions forContinued Airworthiness, Ancra International LLC,Document No...	This STC is not compatible with airplanes where an auxiliary fuel tankis located in the lower cargo compartment.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	26/08/2020	Active	10074113
10074114	VT DRB AVIATION CONSULTANTS		FAA STC ST11279DS	A330-343/-743L/-841/-941 A330-321/-322/-323/-341/-342 A330-243/-243F/-301/-302/-303 A330-201/-202/-203/-223/223F	Interior reconfiguration increasing passenger count from 292 to 297passengers	Certification Basis as per TCDS amended by: CS25 amdt 25: 25.772(b)(c),25.791(a)(b)(c)(d)(e), 25.795(a), 25.801(a), 25.803(a), 25.807(a)(7)(viii)(d), 25.853(a)(d)(f)(g), 25.854(a)(b), 25.869(a)(4), 25.981(a)(3)(d)(e), 25.1307(c), 25.1411(a)(b)(d)(e), 25.1415(a)(b)(c)(d),25.1423(c)(g), 25.1557(a)(c) The req...	"Data List, Installation Data, A330 ACA Interior Reconfiguration<(>,<)>"Document No. DL2076N00, Revision B<(>,<)> dated19 May 2020, or laterFAA approved revision."Instructions for Continued Airworthiness," Document No. 2076CT25-04,Revision S, dated 21 February 2020<(>,<)> or later FAA acceptedrevis...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This modification does not impact the existing electric...	08/12/2020	Active	10074114
10074118	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE	REV. 1	FAA STC ST02445CH-D	A320-214 A319-115 A319-112	Installation of an Aircraft Cabin Interiors Modification	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:-CS 25 amdt. 0: 25.29(a)(b), 25.303, 25.305(a)(b), 25.307(a),25.561(b)(c)(d), 25.562(a)(b)(c), 25.601, 25.603(a)(b)(c), 25....	Armstrong Aerospace Master Data List, Doc. No. DC104-4025-00, RevisionW, dated 14 May 2012, or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Virgin America Doc. No.ICA05253, Revision 5, dated 21 December 2011,or Virgin America Doc. No.ICA05271, Revision 4, dated 26 Apr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/10/2020	Active	10074118
10074119	VT DRB AVIATION CONSULTANTS		FAA STC ST11280DS	A330-743L, -841, -941 A330-323, -341, -342, -343 A330-302, -303, -321, -322 A330-223F, -243, -243F, -301 A330-201, -202, -203, -223	Interior reconfiguration increasing passenger count from 292 to 297passengers	Certification basis as per TCDS amended by: CS25 amdt 25:25.772(b)(c), 25.801(a), 25.803(a), 25.807(d), 813(a)(b)(d)(e), 25.853(a)(d)(f)(g), 25.854(a)(b), 25.869(a)(4), 25.981(a)(3)(d)<(>,<)>25.1307(c), 25.1411(a)(b)(d)(e)(f), 25.1415(a)(b)(c)(d), 25.1423(c)(g),25.1557(a)(c).The requirements for envi...	1. "Data List, Installation Data<(>,<)> A330 ACA InteriorReconfiguration" document no. DL2070N00, revision-, dated 4 August 2020or later FAA approved revision.2. "Instructions forContinued Airworthiness" document no. 2070CT25-04,revision-, dated 23 March 2020 or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This modification does not impact the existing electric...	08/12/2020	Active	10074119

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074129	Q.C.M. DESIGN GmbH			BD-700-1A11 BD-700-1A10	Installation of Ku Band Satellite System with a Gimbal Antenna and WiFiHotspots	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment: CS-25 Amendment 11, 21, 23, 25, 27, 29, 301, 303, 305, 307, 561, 571, 581, 601, 603, 605,607, 609, 611, 613, 619, 625, 77...	- Aircraft Flight Manual Supplement BBD7-QCM23-007-M1-AFM, Rev. 2- Instructions for Continued Airworthiness BBD7-QCM23-007-M1-ICA, Rev. 0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/08/2020	Active	10074129
10074139	LUFTHANSA TECHNIK AG	REV. 1		A319-133, A321-200	Uninterruptable Power Supply (UPS).REV.1 extends the applicability of this STC to A319-133.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): F-112 “Supercapacitors systems and installation”issue 2.The requirements for environmental protection and the associatedcertified noise and/ or emi...	- Supplemental Type Definition Document STDD24-20/01M Issue/Rev 02/00,dated 2 Feb 2021- For A321-200: Instructions for Continued Airworthiness A-00-20/20-ICAIssue/Rev 03/00, dated20 Aug 2020- For A319-133: Instructions for Continued Airworthiness A-00-21/01-ICAIssue/Rev 01/00, dated 11 Jan 2021or l...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/02/2021	Active	10074139
10074157	AIRLIFT A/S			AW169	Installation of external LED lights kit P/N EN-169-33-101-01	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Design Order DO-169-33-101 Rev. 1 dated 28.01.2019Certification Plan CP-169-33-101 Rev. 4 dated 18.12.2019Compliance Checklist CCL-169-33-101 Rev. 0 dated 11.08.2020Flight Manual Supplement AW169 with Led lights FMS-169-33-101-01 Rev. 1Instruction for Continued Airworthiness ICA-169-33-101-01 Rev. 1...	Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the cockpit or cabin configurationspecified in this de...	01/09/2020	Active	10074157
10074182	AV8 PMA, LLC			HAWKER 900XP, HAWKER 1000 HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE.125 SERIES 800B BAE.125 SERIES 800A BAE.125 SERIES 1000B BAE.125 SERIES 1000A	EASA validation of FAA Parts Manufacturer Approval (PMA) NoPQ3885SWSupplement No 12 Revision 1, date July 13 2020, for the following FAAPMA life limited critical parts (NLG assemblies and parts): NP-8UN441-1ATorque Link Pick-Up Sleeve Assembly, NPR-8UN101-1 Torque Link Pick-UpSleeve, NP-8UN439-1AS...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	AV8 PMA, LLC. PMA No: PQ3885SW, Supplement No 12, Revision 1, date July13, 2020;AV8 MRO LLC. Parts Manufacturer Approval Drawing List Document No.:AV8-DL19115Revision A, date 10.15.2019;AV8 MRO, LLC. Airworthiness Limitations Supplements documents:AV8-ALS1911501 for the NP-8UN439-1A Steering SleeveA...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:“Produced by the holder of the EASA STCnumber 10074182.Prior to installation of this change/repairit must be determined thatthe interrelationship between this...	04/09/2020	Active	10074182
10074187	AVIONIK STRAUBING ENTWICKLUNGS GmbH			F172P	Installation of Single/Dual Research Equipment Carrier(s)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Avionic Straubing Master Document Listref ASR-2019-066-MDL-01-00 dated 31.07.2020 and Instructions forinstallation ref ASR-2019-066-IFI-10-00 dated28.07.2020.Operate in accordance with Avionic Straubing Aircraft Flight ManualSupplement ref ASR-2019-066-FMS-05-00 date...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/09/2020	Active	10074187

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074189	AIRBORNE MAINTENANCE ANDENGINEERING SERVICES, Inc. (AMES)		FAA ST04319CH	767-200, 767-300 757-200	Installation of Automatic Dependent Surveillance – Broadcast (ADS-B) Oututilizing Aviation Communication and Surveillance Systems (ACSS) NXT-800Mode-S Transponders paired with Esterline/CMC Electronics CMA-5024 GPSSensors listed on AML number ST04319CH. The validated STC (ST04319CH) isfully complian...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- CS ACNS Subpart D, Section 4.The requirements for environmental protection and the associatedcertified noiseand/ or emissions levels of the product are unchangedand rem...	EASA MDL for ADS-B OUT on B757, Doc Ref: 47228MDL04 Rev IREASA MDL for ADS-B OUT on B767, Doc Ref: 47228MDL03 Rev IREASA AFM Supplement for B757-200 Series Aircraft, Doc Ref: 47228AFM04Rev IREASA AFM Supplement for B767-200/300 Series Aircraft, Doc Ref: 47228AFM03 Rev IRInstructions for Continued Air...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product	04/09/2020	Active	10074189
10074190	S4A SOLUTIONS FOR AVIATION, S.L	REV. 1		CL-600-2B19 (RJ SERIES 100) CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Installation and activation of WiFi system to provide passengers withthe means to access WLAN services on their personal devices (PEDs).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:25.1, 25.1301,25.1309, 25.1501, 25.1529, 25.1581, 25.23.1585 at Amendment 24 of CS-25.The requirements for environmental...	Master Document List, S4A document No. 604102-12-13, Edition 4, dated 9September 2020Flight Manual Supplement, S4A document No. 604102-12-28, Edition 2,dated 4 August 2020or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	WiFi may only be activated and operated during non-criticalflightphases.	10/09/2020	Active	10074190
10074210	ELBIT SYSTEMS - ELECTRO-OPTICS-ELOP			757-300	757 SPS (Self-Protection System) FootprintThe STC consists of structural reinforcements and components remainingin the aircraft after removal of the equipment installed on the aircraftduring a previous modification approved by the Civil Aviation Authorityof Israel (CAAI SA313), which we designate as...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: The amendment of allthe following CS-25 requirements is CS-25Amdt. 11: CS-25.1 (b),CS-25.23 (a) (b), CS-25.25 (a1) (a2) (...	- B757 SPS Footprint Compliance Check List, ref. doc 3759-0000-00GC,20th March 2018- B757-SPS Footprint Compliance Plan, ref. doc. 3759-0000-00CN, 20thMarch 2018- B757-SPS Footprint Instruction for Continued Airworthiness (MPDSupplement),ref. doc. 3759-4000-00ZT Rev. B--B757 SPS Footprint Airplan...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/09/2020	Active	10074210
10074211	SWISS AIR-AMBULANCE Ltd.	REV. 1		MBB-BK117 D-3 MBB-BK117 D-2	Introduction of the White Phosphor NVG P/N FENN NG 800Rev. 1 extends the scope of this STC to the model MBB-BK117 D-3	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	For initial issue:Design Effectivity List R980-00142 Rev. Bdated 06.04.2020Certification Programme R980-00144 Rev. B dated 06.04.2020Compliance Summary List R980-00143 Rev. B dated 02.09.2020Declaration of Compliance R980-00145 Rev. B dated 02.09.2020Flight Manual Supplement R980-00181 Rev. C dated...	Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the cockpit or cabin configurationspecified in this de...	25/03/2021	Active	10074211
10074212	SWISS AIR-AMBULANCE Ltd.			AW109SP	Introduction of the White Phosphor NVG P/N FENN NG 800	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Design Effectivty List R980-00130 Rev. B dated 03.04.2020Certification Programme R980-00131 Rev. B dated 06.04.2020Compliance Summary List R980-00132 Rev. B dated 02.09.2020Declaration of Compliance R980-00137 Rev. B dated 02.09.2020FlightManual Supplement R980-00180 Rev. C dated 02.09.2020Instruct...	Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the cockpit or cabin configurationspecified in this de...	08/09/2020	Active	10074212

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074213	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT, LLC			560XL	Installation of Mid-Continent Instruments MD-302 Standby Instrument onTextron Aviation Inc. 560XL aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Elliott Aviation Master Data List MDL-4207-466, Revision E,dated 8 June2020, or later FAA approved revision.Airplane Flight Manual Supplement, Elliott Aviation Document No.FMS-4207-466, Revision A, FAA Approved 1 July 2020, or later FAAapproved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/09/2020	Active	10074213
10074217	ROCKY MOUNTAIN AIRCRAFT			DHC-6 SERIES 400 DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300 DHC-6 SERIES 210 DHC-6 SERIES 200 DHC-6 SERIES 110 DHC-6 SERIES 100	Installation of Replacement Cabin Roof Escape Hatch, PN:RMA-C6FS2413-11.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Rocky Mountain Aircraft (RMA)Modification Instruction E117110, Revision -, dated 05 June 2020.Maintenance in accordance with RMA Maintenance ManualSupplementE117131, Revision -, dated May 22, 2020.or later revisions of the above listed document(s) approved/ accepted o...	Aircraft roof assembly must be pre-mod Viking Aircraft Ltd.ModificationNo. 6/1256 or equipped with EO68397.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no...	08/09/2020	Active	10074217
10074223	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			B300, B300C B200GT, B200T B200, B200C, B200CGT, B200CT A100-1, A200, A200C, A200CT 300, 300LW 200, 200C, 200CT, 200T 1900, 1900C, 1900D	RCZ-852 transponder replacement with NXT-600 transponder for ADS-B Outcompliance in the above Textron Aviation Beechcraft Models (NON ProLine21 aircraft).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-ACNS Initial IssueSection 2- Mode-S Elementary Surveillance; Section 3- Mode-S EnhancedSurveillance; Section 4- 1090MHz...	Installation Procedure, Report 2020-22-1 Revision A, date 20 August 2020Aeroplane Flight Manual Supplement, Report 2020-22-8, Revision IR, date29 June 2020Maintenance Manual Supplement Report 2020-22-10, Revision A, date 20August 2020or later revisions of the above listed document(s) approved/ accept...	Before the modification of the aircraft, it must be checkedthat theSBAS receiver is listed in the Table 1 of the Installation InstructionsReport 2020-22-1 Section 1 including thecorrect software version.Prior to installation of this change/repair it must be determined thatthe interrelationship bet...	09/09/2020	Active	10074223
10074225	AVIONITEC AG			340A	Avionics upgrade:Installation of a TAS Top Antenna Garmin GA 58 in pressurized Area<(>,<)>Installation of a L-3 WX-500 Stormscope System with new Antenna in non-pressurized area. Stormscope Informations displayed and controlled bythe Garmin GTN DisplaysExchange of the existing WX Radar System by a G...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: §23.867, 23.1306 and23.1308 of CS 23 Amdt 4The requirementsfor environmental protection and the associatedcertified noi...	- Master Document List: Doc. No. 9469-017, Dated 31.08.2020- Airplane Flight Manual Supplement: Doc. No. 9469-011, Dated31.08.2020- Instructions for continued airworthiness Doc. No. 9469-015, Dated29.03.2019Or later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	Limited to Serial Number 340A-0948 (HB-LMN)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	09/09/2020	Active	10074225
10074232	ANCRA INTERNATIONAL LLC		FAA STC ST02705LA	767-300	Installation of window plugs	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt 00: 25.29, 25.303, 25.561, 25.601, 25.605, 25.607, 25.619,25.625(a)(b), 25.843(a), 25.899(a)(b), 25.1529CS 25 am...	Ancra International LLC Controlled Data List DL87040, Revision D, dated28 June 2019, or later FAA approved revision.Instructions for Continued Airworthiness, Report Number 10932, RevisionB, or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/01/2021	Active	10074232

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074234	AMAC AEROSPACE SWITZERLAND AG			BD-700-1A10	Alternate Cabin ConfigurationThis modification changes the area modified by EASA STC 10042314 byrearranging the aft cabin to facilitate the installation of a singlebed.,,	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25 at Amendment 25-1CS 25.1, CS25.301, CS25.303, CS25.305,CS25.307, CS25.365, CS25.561,CS25.562, CS25.571, CS25.601, C...	The Change is defined with revision A of AMAC Aerospace Master Data ListDocument MDL-JT01-2500.The aircraft shall be operated in accordance with revision A of AMACAerospace Airplane Flight Manual Supplement Document AFMS-JT01-2500.Maintenance shall be conducted in accordance with revision A of AMACA...	EASA STC 10042314 must be incorporated prior to the installation of thisChange. This change must be incorporated concurrent with AMAC Aerospacechange ALLAC01-2620.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	11/09/2020	Active	10074234
10074237	STG AEROSPACE GERMANY GmbH	REV. 5		SEE EASA APPROVED MODEL LIST	saf-Tglo® SuperSeal UltraLite-X (SSUL-X) Photoluminescent FloorProximity Emergency Escape Path Marking SystemsRev. 1: Transfer of STC holder from STG Aerospace Limited to STGAerospace GmbHRev. 2 incorporates the installation of a new SSUL-X variant of the STGAerospace saf-Tglo® Floor Path Marking Sy...	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 at Amendment 25- CS 25.1; CS 25.25; CS 25.27;CS 25.301; CS 25.303; CS 25.305; CS 25.307; CS 25.561; CS 25.581; CS25...	- SG-1029-MDL-01 MASTER DATA LIST Revision E- STG AEROSPACEGmbH AIRPLANE FLIGHT MANUAL SUPPLEMENT No.SG-1029-FMS-01 Revision C (Single Aisle Aircraft)- STG AEROSPACE GmbH AIRPLANE FLIGHT MANUAL SUPPLEMENT No.SG-1029-FMS-03 Revision C (Twin Aisle Aircraft)- STG AEROSPACE GmbH AIRPLANE FLIGHT MANUALS...	SSUL-X Green Emitting PL insert shall not be mixed with SSUL-X BlueEmitting PL insert on the same aircraft installation.SSUL-X systems shall not be mixed within the aircraft cabinarea (i.e. amix of SSUL-X11 and SSUL-X18 within the cabin area).SSUL-X36 shall not be used in Non-Textile Flooring areas...	02/06/2023	Active	10074237
10074240	Q.C.M. DESIGN GmbH			31A	FMS Upgrade with UNS-1Lw covering SBAS and RNP-1 Capability	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	According to QCM Design GmbH Document CR-L31X-QCM34-001, Rev. 1To be operated in accordance with QCM Design GmbH AFM-S Document No.L31X-QCM34-001-M1-AFM, Rev. 2To be installed i.a.w. QCM Design GmbH Document Engineering BulletinEB-L31X-QCM34-001, Initial IssueTo be maintained i.a.w. QCM Design GmbH Do...	This change is only for aircraft equipped as defined in chapter 1.1 ofQCM Engineering Bulletin EB-L31X-QCM34-001, Rev. 1.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairand any otherpreviously installed change and/ or repair will...	11/09/2020	Active	10074240
10074241	AMAC AEROSPACE SWITZERLAND AG	REV. 1		SEE EASA APPROVED MODEL LIST	Replacement of Halon agent with alternate Halon-free Portable FireExtinguisher agentThis certificate covers the replacement of the existing Portable FireExtinguisher agent with Halon-free Portable Fire Extinguisher agent(Halotron BrX).Rev.1: Remove limitation for “Low Occupancy” aircraft and additi...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 at Amendment25: CS 25.1, CS 25.561, CS 25.601,CS 25.789, CS 25.851, CS 25.1411, CS 25.1501, CS 25.1529, CS 25.1561...	The Change is defined with revision B of AMAC Aerospace Master Data ListDocument MDL-ALLAC01-2620.The Installation has to be accomplished in accordance with revision B ofAMAC Engineering Order Document EO-ALLAC01-2620Or later revisions of the above listed document(s) approved/ acceptedunder the EASA...	Physical installation of the fire extinguisher is not covered by thismodification and requires a concurrent approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andany otherpreviously installed change and/ or repair will int...	14/01/2022	Active	10074241
10074267	S-TEC CORPORATION		FAA STC SA09759DS	PA-31T (CHEYENNE/ CHEYENNE II) PA-31T2 (CHEYENNE IIXL) PA-31T1 (CHEY. I/ CHEYENNE IA) PA-31P (PRESSURIZED NAVAJO) PA-31P-350 (MOJAVE) PA-31-350 (CHIEFTAIN) PA-31-300, PA-31-325 PA-31	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09759DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List No. ST-975-MDL-0001, Revision A, dated 23 June 2020or later FAA approved revision.2. Airplane Flight Manual Supplement, ST-975-AFMS-0001, Rev. -, dated 23June 2020 or later FAA approved revision.3. Instructions for Continued Airworthiness, ST-975-ICA-0001, Revision-, dated 17 Jun...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/09/2020	Active	10074267

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074272	INTELSAT INFLIGHT LLC	REV. 3	FAA STC ST02541CH	SEE FAA APPROVED MODEL LIST	Installation of an Aircell Broadband Services (ABS) SystemRev1: Typo and Certification Basis correctedRev2: Certification Basis correctedRev3: Company Name changed from "Gogo LLC"to "Instelsat Inflight, LLC.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 amdt 2: 25.29 (a)(b),25.301(a)(b), 25.303, 25.305(a)(b),25.307(a), 25.365(a)(b)(c)(d),25.561(c)(d), 25.571(a)(b), 25...	1. Installation instructions as listed on FAA AML Number ST02541CH.2. Airplane Flight Manual Supplement (AFMS) as listed on FAA AML NumberST02541CH.3. Instructions for Continued Airworthiness (ICA) as listed on FAA AMLNumber ST02541CH.	Additional Limitations and Conditions are listed on FAA AMLNumberST02541CH.This modification may not be installed after 30 August 2010 unless (1)previously approved electrical wiring interconnection system (EWIS)instructions for continuedairworthiness (ICA) have been evaluated anddetermined to beh...	25/03/2021	Active	10074272
10074276	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST02886CH-D	FALCON 2000EX FALCON 2000	Installation of an Interior Floorplan Reconfiguration	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02886CH-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. StandardAero Master Data List 1019035, Revision (K), dated 13 August2020 or later FAA approved revision.2. Airplane Flight Manual Supplement document number 1019205, Rev (A) dated 11 October 2010, or later FAA approved revision.3. Airplane Flight Manual Supplement document number 1019556, Rev (A)d...	Equivalent Safety Findings have been made for the followingregulation:25.813(c)(2) “Emergency Exit Access” (documentedin TAD ELOS MemoSP00843IB-T-C-1).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously inst...	16/09/2020	Active	10074276
10074283	AIM ALTITUDE UK LIMITED		CAA UK RESPONSIBILITY	787-9 787-8	Installation of El Al Feature Panels C78ELAAGA000-01	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Plan and Compliance Checklist 13688 Issue Borlater revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/09/2020	Active	10074283
10074292	STC HOLDING COMPANY, INC.		FAA STC SA7738SW	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of a Freon Air Conditioning System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	1. R. W. Martin Drawing List No. 890612, dated 18 September1990, orlater FAA approved data.2. Flight Manual Supplementdated 13 March 1990, or later FAA approved.	The Model 100 must have de Havilland Modification Bulletin No. 6/1075,"To Extend Rear Baggage Compartment," installed for installation of thisSTC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed c...	18/09/2020	Active	10074292
10074295	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA ST04396CH	BD-700-1A11 BD-700-1A10, BD-700-1A11 BD-700-1A10	Installation of Viasat Ku and Ka SATCOM Terminal Systems and associatedKuKa Radome.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): Pertaining 25.251 ELOS MemorandumST099933CH-T-F-1 (Vibration and buffeting).- The following paragraph(s) at a later amendment: CS 25.869(a)...	Master Data List, StandardAero document No. 1035835, Revision B, dated21 August 2019Airplane Flight Manual Supplement (Configuration 01 and 02),StandardAero document No. 1036021,Revision B, dated 21 August 2019Airplane Flight Manual Supplement (Configuration 01 and 03),StandardAero document No. 1036...	This STC requires prior or concurrent embodiment of a TPED STC, ServiceBulleting or embodiment of FAA STC ST03274CH validated by EASA STC10069212For Configuration 01 and 02 Airplane Flight Manual Supplement 1036021 isa required part of themodification.For Configuration 01 and 03 Airplane Flight Man...	18/09/2020	Active	10074295
10074298	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		SA227-CC, SA227-DC, SA227-PC SA226-TC, SA227-AC, SA227-BC	MODE S EHS UpgradeRevision 1 corrects the Associated Technical Documentation references.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23 Amd 3: 23.1,23.1301, 23.1309, 23.1359, 23.1365, 23.1501, 23.1529, 23.1581, andCS-ACNS .The requirements for enviro...	Installed in accordance with document: Engineering Order Document Number2125253-EO, Issue 1,Dated 14th September 2020.Operated in accordance with document: Aircraft Flight Manual Supplement,Document Number 2125253-AM A, Issue 3, dated 14thSeptember 2020<(>,<)>Maintained in accordance with document:...	The prerequisite aircraft configuration must adhere to:- Existing single or dual MST-67A (EHS capable) or MST-70B XPDR Systemmust be found installed and approved at least for ModeS ELS.- The existing Air Data Computer holding TSO C106 or C08 with A429output available.- The XPDR System must be conne...	29/09/2020	Active	10074298

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074305	LB AIRCRAFT ENGINEERING LLC	REV. 1	FAA STC ST04473AT	737-500 737-400 737-300	Replacement of the dual Honeywell or Collins Mode S transponders with adual Honeywell TRA-100B Automatic Dependent Surveillance – Broadcast (ADS-B) Out System.Installation of Gables Engineering G7490-() control panel to provideFlight ID input and Transponder Fail annunciation.Installation of ADS-B Fu...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 amdt 0: 25.23 (a),25.561(c), 25.601, 25.771(a), 25.1381(a)(b), 25.1431(a)(c), 25.1529,25.1581(a)(2)(d)CS 25 amdt 5: 2...	1. LB Aircraft Engineering LLC. Master Data List LB-TRA.737-MDL RevisionB, dated 10 January 2020, or later FAA approvedrevisions.2. FAA Approved Flight Manual Supplement, LB Aircraft Engineeringdocument LB-TRA.737-AFMS, Rev IR, dated 12 March 2020, or later FAAapproved revisions.3. LB Aircraft Engi...	The aircraft must be equipped with Dual Esterline CMC ElectronicsCMA-6024 GNSS Landing System with SBAS/ GNSS sensors toprovideHigh-Integrity GPS position source, and the existingtransponders mustbe wired to provide Mode S ELS and Mode S EHS functions.Prior to installation of this change/repair itt...	23/02/2021	Active	10074305
10074308	LB AIRCRAFT ENGINEERING LLC	REV. 1	FAA STC ST04474AT	737-500 737-400 737-300	Installation of Esterline CMC Electronics dual CMA-6024 GPS/SBAS LandingSystem Sensor Units (GLSSU), dual CMA-5025 GPS Landing System (GLS)Control Panels, dual low profile high-speed WAAS GPS/SBAS/GNSSU antennas(CMC Electronics 201-990309-187 or Aero Antenna TechnologyAT575-234W-TNCF-000-RG-29.5-NM...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt 0: 25.23 (a), 25.303, 25.365(a)(b)(d), 25.561(b)(3),25.571(a)(b), 25.601, 25.605(a), 25.771(a)(c), 25.789 (a), 25....	1. LB Aircraft Engineering LLC. Master Data List LB-GLS.737-MDL RevisionG, dated 6 March 2020, or later FAA approved revisions.2. FAA Approved Flight Manual Supplement, LB Aircraft Engineeringdocument LB-GLS.737-AFMS, Rev IR, dated 3 April2020, or later FAAapproved revisions.3. LB Aircraft Engineer...	Both FMCs must be loaded with operator specific Boeing provided OPCsoftware with GPS update recognition.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adv...	28/01/2021	Active	10074308
10074311	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	A330-941	AZUL AIRBUS A330NEO RECARO CL3710 SKYCOUCH ECONOMY SEAT ACTIVATION	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	SWS Certification Services Ltd Master Configuration Scheme No.3183-MCS-01 Issue 1<(>,<)>Or later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	Operational Limitation - The use of the Skycouch seats by occupants withthe Skycouch restraints and extended legrest deployment are notpermitted during taxi, take-off or landing.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and...	21/09/2020	Active	10074311
10074314	SAFRAN CABIN INC.		FAA STC ST01928LA	A320-214, A321-253N A319-112, A319-115	Installation of Forward LH/RH Windscreen, Mid LH/RH Class Divider, AftLH/RH Windscreen, Upper Attach Provision and Interior Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: list CS25 amdt. 0:25.307(a)(d) , 25.365(e)-(g), 25.561(a)-(d), 25.625(a)-(c), 25.785(b)(d)(2)(h)(2)(4)(k) , 25.791(a)(b)(e...	FAA approved Index List No. C31, Revision P, dated 1 May 2017, or laterFAA approved revision.Instructions for ContinuedAirworthiness (ICA), Report No. CDRC315-78,Revision C, dated 7 March 2017, or later FAA accepted revision.EWIS Instructions for continued airworthiness CDRC-315-84 Rev A	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC approves provisions for the installation of eq...	09/11/2020	Active	10074314
10074326	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH	REV. 1		EC 155 B, EC 155 B1 EC 155 B1 EC 155 B	Installation of a mission management system (MMS) workstation and acamera system HD EOSRevision 1 corrects references in Associated Technical Documentation andclarifies the Limitations/Conditions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Flight Manual Supplement, Doc. No. 00044-DO-MZ-FMS-00, Issue 01 dated4th August 2020- System Description, Doc. No. 00044-DO-MZ-SD-00, Issue 03 dated 20thMay 2020- List of Compliance Documents, Doc. No. 00044-DO-MZ-LCD-00, Issue 01dated 13rd August 2020- Instructions for Continued Airworthiness, Do...	The activation of non-eye safe laser (Class 3, 3B and 4) isnot EASAapproved.These lasers are disabled.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adve...	28/09/2020	Active	10074326

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074336	W&S CONSULTANTS, INC.d/b/a TELAIR INTERNATIONAL	REV. 3	FAA STC ST02735LA	SEE FAA AML	Installation of modular lower deck Cargo Loading System (CLS)Rev. 1: Typos correctedRev. 2: A321 aircraft family includedRev. 3: Technical documentation wording clarified	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 amdt 0: 25.23 (a)(b), 25.303, 25.601, 25.605(a) (b),25.625(a)(b)(c), 25.1307(c), 25.1529, 25.1541(a)(b)CS 25 amdt 1: 25...	APPROVED MODEL LIST (AML), ST02735LA, REV. NC DATED 23 JULY2021For A320:- FAA approved Telair International Index ListIL909100 Revision A,dated 28 August 2020- FAA approved Airplane Flight Manual Supplement 909100AFMS-3200,Revision Original, dated 31 July 2020, Weight & Balance Control andLoadingt...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is limited to: 1) Aircraft which were original...	19/12/2024	Active	10074336
10074362	ROCKWELL COLLINS, Inc.		FAA STC ST01542WI-D	SEE FAA AML	Modification of a Rockwell Collins. Inc. AFD-3010 and AFD-3010E AdaptiveFlight Display Installation in Part 25 Aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01542WI-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	Rockwell Collins<(>,<)> Inc. Master Drawing List as listed on AML No.ST01542WI-D, Revision -, or later FAA approved revisions.	Prior installation and approval of a Rockwell Collins<(>,<)> Inc.AFD-3010 and AFD-3010E Adaptive Flight Display is a prerequisite to thisSTC. Reference Table 1 (AFD-3010) or Table2 (AFD-3010E) of RockwellCollins<(>,<)> Inc. Installation Instructions, Document Number RCA-2578,Revision -, dated 25 Ma...	25/09/2020	Active	10074362
10074366	GROWING ENGINEERING PARTNERS GmbH	REV. 1		777-300ER	Cabin ReconfigurationRev 1.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List S.OAEZ.001918-MDL, Rev. 00Aircraft Flight Manual Supplement S.OAEZ. 001918-AFM, Rev. 01Instructionsfor Continued Airworthiness S.OAEZ. 001918-ICA, Rev. 00Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The installation of STC 10065375 as pre-configuration is apre-requisite.Compliance with the OSD Certification Basis of the product with this STCinstalled has not been shown. The product with this STC installed istherefore not eligible for registration in any EASA member state unlesscompliance with t...	21/04/2021	Active	10074366
10074402	TEXAS AIR SERVICES, Inc.		FAA STC SA10407SC	DHC-6 SERIES 400 DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of a replacement electrically driven by hydraulic pumpassembly	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA10407SC.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Texas Air Services, Inc. Master Drawing List No. AAT-001, Revision F,dated 4 October 2016, or later FAA approved revision.Installation Instruction with Instructions for Continued Airworthiness,Document No. AAT-600-6, Revision A, dated 4 October 2016, or later FAAaccepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/09/2020	Active	10074402
10074403	AVMAX AVIATION SERVICES Inc.		TCCA C-LSA20-047/D	1900D	GTS 8000 TCAS II V7.1 and GTX 3000 ADS-B Out UpgradeThis modification installs a Garmin GTS 8000 TCAS II V7.1 system and aGTX 3000 transponder system with ADS-B Out capability, includingcombined TCAS/vertical speed indicators and structural provisions forTCAS and transponder antennas.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS ACNS Subpart DSection 4 at Issue 2The requirements for environmental protection and the associatedcertified noise and/a...	Change defined in Master Data List CE480-900 Issue C, or later TCAAapproved revisionInstallation in accordance with Engineering Order CE480-401 Issue B, orlater TCAA approved revisionMaintenance in accordance with Maintenance Manual Supplement CE480-701Issue C, or later TCAA approved revisionOperati...	This STC is only applicable to aircraft serial number UE-398.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairand any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the pr...	28/09/2020	Active	10074403

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074404	FOKKER SERVICES B.V.			737-900ER 737-900 737-800 737-700	Activation of standalone GNSS sensor system on Boeing 737-NG AircraftThe present STC concerns the activation of the dual standalone GNSSsensor system installed by means of minor mod ref ECR016676(CP/CRR-0424). The standalone GNSS sensor system has no connection toany other aircraft system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	· Certification Program ref CPR-0425 issue 3· Compliance Record Report ref CRR-0425 issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This present STC can be installed on aircraft only providedthat:- Fokker Services' minor mod ECR016676 (CP/CRR-0424) has been previouslyinstalled, and- no SATCOM installation is presentPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/re...	30/09/2020	Active	10074404
10074408	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			SEE EASA APPROVED MODEL LIST	Replacement of Portable Fire Extinguishers using Halon agent withalternate Halon-free agent.This certificate covers thereplacement of the existing Portable FireExtinguisher agentwith Halon-free Portable Fire Extinguishers agent(Halotron BrX).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25.1, CS25.29,CS25.301, CS25.303, CS25.305, CS25.307, CS25.561, CS25.601, CS25.603,CS25.605, CS25.607, CS25.609, CS25.61...	The Change is defined with revision 1 of AMES Engineering Order DocumentEO_M990001057_MTH_20022020.The Installation hasto be accomplished in accordance with revision 1 ofAMES Instructions for Continuous Airworthiness DocumentICA_M990001057_MTH_20022020Or later revisions of the above listed document...	Physical installation of the fire extinguisher is not covered by thismodification and requires a concurrent approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andany otherpreviously installed change and/ or repair will int...	28/09/2020	Active	10074408
10074409	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST02435CH	A319-112/-115/-214	Installation of an In-Flight Entertainment (IFE) System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:- CS 25 amdt. 0: 25.29(a)(b), 25.303, 25.305(a)(b), 25.307(a),25.365(e)(f)(g), 25.561 (c), 25.571(a)(b)(c)(d)(e), 25.601,25....	Armstrong Aerospace Master Data List, Doc. No. DC104-3102-00, RevisionAB, dated 26 April 2012, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement, Inflight Canada Doc. No.FMS05254, Revision 1, approved 1 June 2007, or Doc. No. FMS05270,Revision 1, approved 21 February 2008...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- STC 10073881 (FAA STC ST02313CH), installation of anB...	16/10/2020	Active	10074409
10074412	MECAER AVIATION GROUP S.p.A.	REV. 5		H160-B (IN PROGRESS) H160-B	"STYLENCE" cabin interior configurations family P/N 6A6H0000X001001 asspecified in doc. ref. 6A6H0000N064 and 6A6H0000N088.Each configuration incorporates installation of seats, cabinets (whereapplicable), carpet in passenger compartment together with existing trimpanel modifications (i.e. painting,...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	H160 Stylence Interior - Configuration Description, doc. ref.6A6H0000N064 issue DH160 Stylence – Front Partition Major Change Configuration Description,doc. ref. 6A6H0000N088 Revision BRotorcraft Flight Manual Supplement (RFMS) No 6A6HRFM-1-1, Part I,revision 1 (paper format only)Airworthiness Limit...	Limitations/ Conditions:Compatibility of the RFMS 6A6HRFM-1-1, revision 1, approved by this STCin paper format, with theH160-B eRFM of the Type Certificate Holder hasnot been demonstrated.The electronic version of the RFMS and of the MMEL S are approved as ofrevision 3 of the STC.Prior to installati...	08/02/2024	Active	10074412
10074417	ROCKWELL COLLINS, Inc.		FAA STC SA01544WI-D	SEE FAA AML	Modification of a Rockwell Collins. Inc. AFD-3010 and AFD-3010E AdaptiveFlight Display Installation in Part 23 Aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01544WI-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	Rockwell Collins, Inc. Master Drawing List as listed on theAML No.SA01544WI-D, Revision -, or later FAA approved revisions.	Prior installation and approval of a Rockwell Collins, Inc.AFD-3010 andAFD-3010E Adaptive Flight Display is a prerequisite to this STC.Reference Table 1 (AFD-3010) or Table 2 (AFD-3010E) of Rockwell Collins,Inc. Installation Instructions,Document N° RCA-2549, Revision -, dated25 March 2009, or lat...	29/09/2020	Active	10074417

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074446	LUFTHANSA TECHNIK AG	REV. 1		A350-941	Cabin IntegrationCabin conversion from a previously configured standard airline cabin toa governmental use cabinRev 1:Instructions for Continued Airworthiness updated and associatedlimitation removed. OSD CCD documentation updated for a minor change.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-47 'Personal injury criteria of dynamic testingof side facing sofas'the following paragraph(s) at a later amendment: the followingparagraph(s) at a...	- Certification Plan CPL00-19/04M Issue 5- Description of Change BBG10-24 Revision 2- Supplemental Type Definition Document STDD00-19/04M Issue 1 Rev 3- Compliance Checklist CCL00-19/04M Issue 7- Instruction for Continued Airworthiness A-00-19/81-ICA Issue 6 Rev 0- Airplane Flight Manual A-00-19/81-...	1) The aircraft with the STC installed is certified for non-commercialuse only;2) Extended overwater flight is not permitted;Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair...	15/12/2020	Active	10074446
10074450	PMV ENGINEERING			A340-313/-541/-542/-642/-643 A340-211/-212/-213/-311/-312	The STC consists on the installation of the ADSB-OUT function on AirbusA340Approved configurations are defined in the applicable Aircraft FlightManual Supplement ref. AVI-02230-AFMS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:- CS25 amdt 4: 25.1301(a)(b)(c), 25.1302(a)(b), 25.1316(c),25.1309(a)(b)(c), 25.1322(a)(b)(c)(d), 25.1351(a)<(>,<)> 25....	- Master Document List AVI-02230-MDL-S01-R01, dated 20 JUL 2020- Aircraft Flight Manual Supplement AVI-02230-AFMS-S01-R00, dated 23 MAR2020- Instructions for Continued Airworthiness AVI-02230-ICA-S01-R01, dated06 APR 2020- MMEL Supplement AVI-02230-MMELS-R00 rev R00, dated 23 MAR 2020or later revisi...	STC limitations and approved configurations are defined in theapplicable Aircraft Flight Manual Supplement ref. AVI-02230-AFMS.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	02/10/2020	Active	10074450
10074454	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		FAN JET FALCON SÉRIES F FAN JET FALCON SÉRIES E FAN JET FALCON SÉRIES D FAN JET FALCON SÉRIES C FAN JET FALCON	Installation of 90-Day Underwater Locator Beacon.The existing 30-day CVR and FDR ULB's are replaced with 90-day versions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): F-1128 Non-rechargeable lithium batteries andbattery installations- The following paragraph(s) at a later amendment: CS 25 amdt 4 - CS25.1 (a), CS(...	Installation of 90-Day ULB doc. No. GVH-10367-03-MOD-01 Issue 1 datedSept. 29th 2020<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The approval holder shall fulfill the obligations of Part 21, Point21A.109.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthi...	26/03/2021	Active	10074454
10074455	AV8 PMA, LLC			HAWKER 900XP, HAWKER 1000 HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE.125 SERIES 800B BAE.125 SERIES 800A BAE.125 SERIES 1000B BAE.125 SERIES 1000A	EASA validation of FAA Parts Manufacturer Approval (PMA) NoPQ3885SWSupplement No 14, Rev 1,date July 24, 2020, for theFAA PMA life limited critical partsinstalled on the Main Landing Gear Assemblies: Lower Arm (Side Stay)Assembly, P/N NP-UM1944-1 and NP-UM1944-2 eligible on the BAe.125 Series800A...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	AV8 PMA, LLC. PMA No: PQ3885SW, Supplement No 14, Revision 1, date 24July 2020;AV8 MRO LLC. Parts Manufacturer ApprovalDrawing No. NP-UM1944, LowerArm (Side Stay) Assembly, Revision E, date 5/22/20;AV8 MRO, LLC. Airworthiness Limitations Supplements Document NoAV8-ALS19119, Revision NC,date January...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:"Produced by the holder of the EASA STCnumber 10074455".Prior to installation of this change/repair it must be determined thatthe interrelationship between thi...	02/10/2020	Active	10074455
10074461	S-TEC CORPORATION		FAA STC SA09760DS	F90, 65_90, 65_A90, 65_A90_1 C90GT, E90, F90, H90 65_A90_4, B90, C90, C90A	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09760DS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Data List No. ST-973-MDL-0001, Revision A, dated 30 June 2020, orlater FAA approved revision.Airplane Flight Manual Supplement, ST-973-AFMS-000I, Rev. -, dated 30June 2020,or later FAA approved revision.Instructions for Continued Airworthiness, ST-973-ICA-000I, Revision -,dated 4 June 2019,a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/10/2020	Active	10074461

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074474	AMAC AEROSPACE SWITZERLAND AG			MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81) DC-9-51 DC-9-41 DC-9-34F DC-9-34 DC-9-33F DC-9-32 DC-9-21 DC-9-15 DC-9-14	Underwater Locator Beacon Battery ReplacementReplacement ofUnderwater Locator Beacon (ULB) battery of the CockpitVoiceRecorder / Flight Data Recorder. The new Lithium Type Battery hasimproved performance (L-3AR battery) for 90 days duration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): F-GEN11 PTC Non-rechargeableLithium BatteryInstallationThe requirements for environmental protection and the associatedcertified noise and/ or emiss...	The change is defined with revision A of AMAC Aerospace Switzerland AGMaster Data List Document MDL-MD801-1-3130Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This modification is applicable for "L3 30 Day ULB" Underwater LocatorBeacon installed on the Flight Data Recorder or/and Cockpit VoiceRecorder. This modification does not cover the installation of othermounting kits. In case different existing Underwater Locator Beaconand/or mounting kit is install...	07/10/2020	Active	10074474
10074488	EIRTECH AVIATION SERVICES LIMITED			737-400	Reduction of Minimum Take Off Weight.Reduced Maximum Take-off Weight for B737-400F to 61,234 Kg.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Master Data List MDL-1394-001, Issue 4Aircraft Flight Manual Supplement FMS-1394-001, Issue 4Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This modification is effective only to aircraft which have incorporatedEASA STC 10033161 / FAA STC ST01827LA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce n...	07/10/2020	Active	10074488
10074499	S4A SOLUTIONS FOR AVIATION, S.L			A340-643 A340-642/-643 A340-642 A340-542 A340-541/-542 A340-541 A340-313 A340-312 A340-311/-312/-313 A340-311 A340-213 A340-212 A340-211/-212/-213 A340-211	Installation of the FliteByte Wi-Fi System on board AirbusA340Airplanes	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	34026-RPT02 Master Document List Issue334026-HBK01 Flight Manual Supplement Issue134026-HDB02 Maintenance Manual Supplement Issue1Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	34026-HDB01 Flight Manual Supplement Issue1Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	07/10/2020	Active	10074499
10074500	SKYWAY GROUP Inc.		FAA STC SA04176NY	501	Installation of Cabin Entry Step Assembly on Textron Aviation, Inc.,Models 501 and 551 aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04176NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Aerospace Design & Compliance. LLC. Master Data List C551-MDL-0041.Rev IR<(>,<)> dated 16 April 2019, or later FAA approved revision.2. Instructions for Continued Airworthiness(ICA) C551-ICA-0041, Rev IR.dated 10 April 2019, or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/10/2020	Active	10074500
10074501	WAYPOINT AEROTEC LIMITED		CAA UK RESPONSIBILITY	A320-214	Vueling A320 WiFi Connectivity System De-Modification of Aircraft withEASA STC No. 10052356 Installed.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	EASA Approved:Waypoint Aerotec Limited Instructions for Continued Airworthiness No.WAL-ICA-104-01 Issue 1EASA Accepted:Waypoint Aerotec Limited Master Data List No. WAL-MDL-104-01Issue 2Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Installation of EASA STC No. 10052356 is a prerequisite forthis STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness o...	07/10/2020	Active	10074501

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074503	T.P.S. S.P.A.	REV. 1		AW139 AB139, AW139 AB139	Installation of medical interior EMS Kit P/N TPS139-0300-0000-00This EMS Kit installs inside the main cabin of the Leonardo helicopterAW/AB139 a rack assyP/N TPS139-0300-100-00-0 together with one stretcher P/ NTPS139-0300-3000-00-0.Rev. 1:Change of the approval holder name from TPS AEROSPACEENGINEE...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Flight Manual Supplement TPS139-0300-RFMS-00- Master Document List TPS139-0300-Mdl-00- Master Drawing List TPS139-0300-Mdw-01- Instructions for Continued Airworthiness TPS139-0300-ICA-00- Installation Service Bulletin TPS139-0300-SBT-00Or later revisions of the above listed document(s) approved/ac...	Operations with EMS kit installation P/N TPS139-0300-0000-00 are allowedon AW139/AB139 helicopters only if equipped with :- Leonardo Helicopters Service Bulletin No 139-290 12Pax<(>,<)>configuration P/N 4G2520F05911 or ;12 Passengers seats, configuration P/N 3G2520F00111- and installing at least one...	19/05/2022	Active	10074503
10074520	AIRBUS S.A.S.			A320-214	STANDALONE V/UHF SYSTEM ACTIVATIONMOD AI0165: activation ofa V/UHF System on ACJ320ceo.	Demands STC 10074021.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact onthe noise database.	- MAS AI0165 Issue 1- AIS-AJA-20016 issue 02 CertificationSummaryor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/10/2020	Active	10074520
10074523	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A321-211	Cabin ReconfigurationReconfiguration of the passenger cabinof Airbus A321-211 in accordancewith SR Technics doc. no. S.OAEZ.001939-PD.Rev 1.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Master Document List S.OAEZ.001939-MDL, Rev. 00Instructionsfor Continued Airworthiness S.OAEZ. 001939-ICA, Rev. 01Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Airbus S.A.S. MOD No. 151369 “Equipment / Furnishing Pax CompartmentAdapt Cabin Layout for AFL05 Version” is a pre-requisite forinstallation.Lufthansa Technik EASA STC 10014013 Photoluminescent Emergency FloorPath Marking is a pre-requisite for installation.Prior to installation of this change/ repai...	21/04/2021	Active	10074523
10074577	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			737-800 737-8	Introduction Of Front Row MonumentThe design change installs Front Row Monuments in the passenger cabinbetween STA381 and STA404.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	MEDAVIA D.O. Master Data List MODE00294 (MDL)MEDAVIA D.O. Instructions for Continued Airworthiness MODE00294or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The installer of the passenger cabin seats shall ensure a minimumdistance of 35 inches between the aft face of the front row monument andthe seat reference point of the front row seats.The passenger cabin seating configuration is not part of this designchange.Prior to installation of this change/rep...	16/10/2020	Active	10074577
10074588	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	ATR 72-212 A ATR 72-212 ATR 72-211, ATR 72-212 ATR 72-211 ATR 72-202 ATR 72-201, ATR 72-202 ATR 72-201 ATR 72-102 ATR 72-101, ATR 72-102 ATR 72-101 ATR 42-500 ATR 42-400 ATR 42-320, ATR 42-400 ATR 42-320 ATR 42-300 ATR 42-200, ATR 42-300 ATR 42-200	INSTALLATION OF TWO HAWKER 24 VDC SEALED LEAD ACID (SLA) BATTERIES	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	MASTER DOCUMENT LIST Issue 1 dtd. 14th October 2020.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/10/2020	Active	10074588

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074589	AMAC AEROSPACE SWITZERLAND AG			747-8	GSM System ActivationThis change describes the activation of a “Global System for MobileCommunication (GSM)” Function of a pre-installed GSMConneX system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	The change is defined with Revision A of AMAC Aerospace SwitzerlandMaster Data List document MDL-B7471-1-3300.The aircraft shall be operated in accordance with Revision A of AMACAerospace Switzerland Airplane Flight Manual Supplement documentAFMS-B7472-1-5300.Or later revisions of the above listed d...	The equipment components required must be installed prior to theincorporation of this change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	16/10/2020	Active	10074589
10074596	AV8 PMA, LLC			HS.125 SERIES 700B HS.125 SERIES 700A HS.125 SERIES 600B HS.125 SERIES 600A HS.125 SERIES 403B HS.125 SERIES 403A(C) HS.125 SERIES 401B HS.125 SERIES 400B HS.125 SERIES 400A HS.125 SERIES 3B HS.125 SERIES 1B HAWKER 900XP HAWKER 850XP HAWKER 800XP HAWKER 800 HAWKER 750 HAWKER 1000 DH.125 SERIES 400A DH.125 SERIES 3A DH.125 SERIES 1A BH.125 SERIES 600A BAE.125 SERIES 800B BAE.125 SERIES 800A BAE.125 SERIES 1000B BAE.125 SERIES 1000A	EASA validation of FAA Parts Manufacturer Approval (PMA) NoPQ3885SWSupplement No 7, date August 4, 2020, for the following FAA PMA lifelimited critical parts (NLG assemblies and parts): NP-UN597-1 LowerPivot Pin-Retraction Jack, NP-UM787-1 Pin-Retraction Lever andNP-UN605-1 Pin-Steering Sleeve, asp...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	AV8 PMA, LLC. PMA No: PQ3885SW, Supplement No 7, date August 4, 2020;Drawing No. NP-UN597 (Rev B) Lower Pivot Pin - Retraction Jack;Drawing No. NP-UM787 (Rev A) Pin - Retraction Lever;Drawing No. NP-UN605 (Rev B) Pin - Steering Sleeve;AV8 MRO, LLC. Airworthiness Limitations Supplements documents:AV8...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:“Produced by the holder of the EASA STCnumber 10074596.Prior to installation of this change/repairit must be determined thatthe interrelationship between this...	19/10/2020	Active	10074596
10074597	LUFTHANSA TECHNIK AG			787-8	787-8 VIP Cabin Completion "Silkroad"	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements asdefined in CRI A-101 “Certification Basis” Issue2:Equivalent Safety Finding (s): F-113 “Crew Determination of Quantity ofOxygen in Passenger Oxygen System” Issue 2, F-12...	Supplemental Type Design Document STDD00-17/09M Issue 1 rev00Instruction for Continued Airworthiness A-00-19/50-ICA Issue 3 rev 01Airplane Flight Manual supplement A-00-19/50-AFMIssue 1 rev 00Master Minimum Equipment List supplement A-00-19/50-MMEL Issue 03OSD Cabin Crew Data A-00-19/50-CCD IssueO...	Aircraft is certified for "private use not for hire" only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the produ...	19/10/2020	Active	10074597
10074602	SKYWAY GROUP Inc.		FAA STC ST04016NY	500/550/S550/560	Installation of Cabin Entry Step Assembly on Textron Aviation, Inc.Models 500, 550, S550 and 560	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04016NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Aerospace Design & Compliance, LLC. (1) Master Data List C560-MDL-0037,Rev. IR, dated 12 April 2019, or later FAA approved revision. (2) Instructions for Continued Airworthiness (ICA) C560-ICA-0037, Rev. IR,dated 3 April 2019, or later FAA approved revision.	The ICA and its contents must be incorporated into the operator'smaintenance program.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	19/10/2020	Active	10074602

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074604	ALAMO ENGINEERING GmbH			CL-600-2B16 (601-3R VARIANT)	FMS TO PBN SPECIFICATION (RNP 1)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-ACNS, Issue 2,dated 26th April 2019.The requirements forenvironmental protection and the associatedcertified noise a...	Operated in accordance with Flight Manual Supplement ref: FMS20A03AE-01Rev A dated 15.10.2020<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to aircraft equipped with FMS system Honeywell FMZ-2000 withsoftware release NZ6.1 according to EASA STC 10061774.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wil...	19/10/2020	Active	10074604
10074619	AERODATA AG			B200	Installation of Aerodata Flight Inspection System AD-AFIS-1013 inBeechcraft King Air B200.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List MDL-A/C-937, Rev 1Airplane Flight Manual Supplement AFM-175, Rev 1Aircraft Maintenance Manual Supplement AMM-1179, Rev 2or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	This design is limited to aircraft Beechcraft King Air B200, S/ NBB-1923, with installed Proline21 avionics and with thefollowing STCs:ADS-B Upgrade (STC EASA 10069005 Rev. 1)DataBase Unit DBU-5010E Upgrade (STC EASA 10016397 Rev. 1) Winglets and associated wings and aileron changes (STC EASA 100159...	21/10/2020	Active	10074619
10074623	SKYWAY GROUP Inc.		FAA STC SA04015NY	525, 525A, 525B	Installation of Cabin Entry Step Assembly on Textron Aviation, Inc.,Models 525, 525A, and 525B aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04015NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Aerospace Design & Compliance, LLC. (1) Master Data List C25B-MDL-0038,Rev IR, dated 4 April 2019, or later FAA approved revision. (2) Instructions for Continued Airworthiness (ICA) C25B-ICA-0038, Rev. IR,dated 1 April 2019<(>,<)> or later FAA accepted revision.	The ICA and its contents must be incorporated in the operator'smaintenance program.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the a...	22/10/2020	Active	10074623
10074630	MOTORFLUG BADEN-BADEN GmbH	REV. 1		MBB-BK117 D-2, MBB-BK117 D-3 MBB-BK117 D-2	Installation of Direction Finder AntennaRev. 1: Extension to model BK117 D-3.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	25107F211421-0101 Compliance Program at Revision 1, dated 10.03.202225107F211421-0102 Compliance Report at Revision 0, dated 10.03.202225107F191328-0601 Rotorcraft Flight Manual Supplement at Revision 4,dated 18.01.2022or later revisions of the above listed document(s) approved/ acceptedunder the EAS...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/05/2022	Active	10074630
10074631	AIRWORTHINESS RESOURCES CORPORATION	REV. 1		U206, U206A, U206B, U206C U206D, U206E, U206F, U206G TU206D, TU206E, TU206F, TU206G 206, TU206A, TU206B, TU206C 206H, T206H	Installation of a Split Forward Cargo Door Window in accordance withTransport Canada Civil Aviation (TCCA) STC SA20-34.Rev. 1: Introduction of a basic installation configuration	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Operation in accordance with TCCA approved ARC Flight Manual SupplementFMS-2061-02 issue 1 dated 9 of April 2024Installation in accordance with TCCA approved Airworthiness ResourcesCorporation (ARC) Installation Instructions, Report No. P0220-08,Revision 2, dated 24 May, 2024;Maintenance in accordan...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/11/2024	Active	10074631
10074633	CASCADE AEROSPACE Inc.		TCCA SA03-75 ISSUE 4	737-300, 737-400, 737-500	Speed Brake Warning ModificationThe modification involves the installation of a supplementary speedbrake caution system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Flight Manual Supplement FMS 3182 Revision 3- Master Drawing List MDL 3182 Revision IRor later revisions of the abovelisted document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/10/2020	Active	10074633

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074637	CONCORDE BATTERY CORPORATION		FAA STC SA01050DE	PA-46-600TP PA-46-500TP	Installation of aircraft main battery replacement with Concorde valveregulated Lead-Acid battery	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01050DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Document No. 5-0691, Master Drawing List, Piper M500 & M600 BatteryUpgrade, Revision NC dated 11 June 2020, FAA approved 3 July 2020 orlater FAA approved revision.2. Instructions for Continued Airworthiness (ICA), Document No. 5-0693,Revision NC dated 11 June 2020, FAA Accepted 3 July 2020, or la...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/10/2020	Active	10074637
10074639	KELOWNA FLIGHTCRAFT Ltd.		TCCA SA17-17 ISSUE 1	737-300, 737-400, 737-500	EFB Installation ProvisionsThis modification provides provisions for the installation of twoElectronic Flight Bags (EFBs) on B737-300/-400/-500 aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Modification Data Summary K399-102-001-002 Rev NC- AFM Supplement K399-102-001-014.1 Rev Basicor later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	As per AFM Supplement K399-102-001-014.1.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	23/10/2020	Active	10074639
10074643	SABENA TECHNICS BGC			A321-271N/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-171N A319-131/-132/-133/-151N/-153N A319-111/-112/-113/-114/-115	Deactivation of Broadband Satcom System & ARINC 791 AntennaRemoval onAirbus A319 / A320 / A321.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4paragraphs: 29, 777, 787, 843, 853, 1301, 1351, 1357, 1525, 1541, 1581,and 1587. CS-25 at amendment6...	- Master Data List, Ref. 0970-01-A-MDL-R00, dated 21 October 2020- Instructions for Continued Airworthiness, Ref. 0970-01-A-ICA-R00,dated 19 October 2020- Airplane Flight Manual Supplement, Ref. 0970-01-A-AFMS-R00, dated 13October 2020or later revisions of the above listed document(s) approved/accep...	This STC is limited to aircraft fitted with primary structurereinforcement for installation of ARINC 791 KU/ KA Band antenna as perAirbus MOD 158144.Limitations as per §3 of Instructions for Continued Airworthiness(Inspections) document and§3 of Airplane Flight Manual Supplement (Performance) documen...	23/10/2020	Active	10074643
10074655	AO AVIATION LLC	REV. 2	FAA STC SA01871WI	KODIAK 100	Installation of a Single Point Pressure Refueling System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01871WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	1. AO Aviation Master Data List, No. G-1002-00, Rev B dated21 March2018, and2. AO Aviation Aircraft Flight Manual Supplement, No. L-1002-03, Rev. -,dated 21 March 2018, or later FAA approved revision to 1. or 2.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/10/2020	Active	10074655
10074661	STERLING CORPORATIOND/ B/A STERLING HELICOPTER	REV. 1	FAA STC SR04481AT	AB139, AW139	Installation of LED steerable searchlight/ landing light assembly inreplacement to the legacy steerable searchlight/landing light assemblyon the Leonardo S.p.a. AB139 and AW139 rotorcraftRevision 1: Transfer from "Luminator Holding L.P." to"SterlingCorporation".	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Master Drawing List (MDL) No. MDL ST-2019-048-02, Revision H, dated 2February 2024;Instructions for Continued Airworthiness (ICA), Luminator AerospaceDocument No. ST-2019-048-04, Revision C, 2 February 2024;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in acco...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.This STC is approved for NVIS operations for AW139 helic...	17/07/2024	Active	10074661

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074684	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303	INTRODUCTION OF AIRBORNE 4G AIT FEMTO SITE PROVISIONSThis Design Change will introduce electrically deactivated provisions tothe aircraft to allow for the future activation of theairborne FemtoSites under a separate Design Change.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	STC Twenty One Ltd Master Document List No. S21. MDL-1542 Issue 1Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/10/2020	Active	10074684
10074697	AEROTEC & CONCEPT			MBB-BK117 D-2	Night Vision Imaging System (NVIS) installation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 29 Amdt. 2:CS 29.601, CS 29.771, CS 29.773, CS 29.777, CS 29.811, CS 29.812, CS29.853, CS 29.1301, CS 29.1303, CS 29.13...	Master Data List, Doc. No. AE19133MDL Rev. 0 dated 02.10.2020;Instructions for Continued Airworthiness, Doc. No. AE19133ICA Rev. 0dated 04.06.2020;Rotorcraft Flight Manual Supplement, Doc. No. AE19133RFMS Rev. 2 dated15.10.2020;Certification Program, Doc. No. AE19133PCDP Rev. 1 dated 05.06.2020or la...	MBB-BK117 D-2m is excluded.Installation of NVIS/ NVG compatible lighting does not include or implyapproval for flight operations with Night Vision Goggles (NVG). Theoperator must receive approval from the Civil Aviation operationalauthorityto operate with NVG.Rotorcraft modified by this design chang...	30/10/2020	Active	10074697
10074708	AVIADECO GmbH			737-700	ADS-B Out ModificationThis XPDR modification makes the aircraft fully compatible with EuropeanSPI Rule (EU Regulation 1207/2011 including all amendments published sofar) concerning ADSB-out.For this purpose the two previously installed Rockwell Collins XPDRshave been exchanged to their successors TP...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS-ACNS,Issue 2The requirements for environmentalprotection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicableo...	- Instructions for Continued Airworthiness ICA-03919, Rev.00- AFM Supplement AFM-03919, Rev. 00- Engineering Order (includes Installation Instructions) EO-03919, Rev.00Or laterrevisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is only applicable to aircraft pre-configured as described inchapter 1.5 of AVIADECO document SCOM-03919, Rev.01Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wil...	02/11/2020	Active	10074708
10074718	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A321-271N/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-171N A319-131/-131/-133/-151N/-153N A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	SURVIVAL ELT INSTALLATION IN CABINSurvival Emergency Locator Transmitter (ELT) Honeywell RESCU 406SGSeries P/N 51090368-1 installation in cabin interior in enclosedoverhead bin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List JCAERO/ MDL/0638 issue 1<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/11/2020	Active	10074718
10074725	E A D AEROSPACE AIRWORTHINESS			A330-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-201/-202/-203/-223/-243	TAIL MUTE WIRE REMOVAL ON GX SYSTEMSWith this STC, the GX JetWave Ka-Band Broad Band Satellite System (fromHoneywell) “Tail Mute” hardware protection is removed, and the Tail Mutefunction is now managed via software functionality only.The Tail Sector Mute function is mainly designed to protect other...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Master Drawing List ref. 01558-EAS-B-MDL, rev D dated 02 Nov. 2020- Airplane Flight Manual Supplement: 01558-EAS-B-AFM-01 rev B dated 28Oct. 2020. or later revisions of the above listed document (s)approved/accepted under the EASA system.	Applicable to aircraft modified per EAD Aerospace STC 10065550 "JETWAVESYSTEM INSTALLATION ON AIRBUS LONG RANGE AIRCRAFT" and EAD Minormodification 01556-EAS-CPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviousl...	03/11/2020	Active	10074725

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074761	LUFTHANSA TECHNIK AG	REV. 3		A320-233 A320-214	RTAF 2: VIP cabin completionRev. 1: typo correction in model validityRev. 2: CCD and ICA limitations removedRev. 3: ELTupgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): D-2341-001 Placards and Signs issue 01.- The following paragraph(s) at a later amendment:CS 25.App.S25.01(b) at amdt 19; CS 25.App.S25.40(a) at amd...	- Airplane Flight Manual A-00-19/89-AFM Issue 01 rev 00- Flight Crew Data A-00-19/89-FCD Issue 01 rev 00- Cabin Crew Data A-00-19/89-CCD rev 05- Instruction for Continued Airworthiness A-00-19/89-ICA Issue 02 rev 02- Master Minimum Equipment List A-00-19/89-MMEL rev. 00- Supplemental Type Design Doc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/05/2022	Active	10074761
10074764	AEROSPACE COMPOSITES GmbH	REV. 1		KODIAK 100	Battery InstallationThis installation is considered as an EASA approved design changealternative to the installation ofthe Daher (former Quest) AircraftDesign LLC. Field Service Instruction FSI-148, Standby Battery System”.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Installation according to the Project Document List document –PDL-KOD100-2430-01 Rev. --,dated 16/10/2020- Operationsaccording to the Aircraft Flight Manual SupplementAFMS-KOD100-2430-01 Issue 0-0,dated 09/10/2020- Maintenance accordingto the Aircraft Maintenance Manual SupplementMMS-KOD100-2430...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/10/2025	Active	10074764
10074771	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			525B 525	Provisions for wireless connection of a PED/EFB to Garmin G3000 avionicsvia Garmin FS-510.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:Only for model 525 (SN 525-0685; 0800 and on): CS-23 Initial Issue:23.1; 771; 773; 1301; 1309; 1321; 1431; 1501; 1519; 1529...	Cessna Düsseldorf Citation Service Center GmbH, Master Document List,Document No. 2020-24-16, Rev IR, dated 22 October 2020.To be installed in accordance with Installation Procedure, Document No.2020-24-1, Rev IR, dated 18 September 2020.To be operated in accordance with AFM-S, Document No. 2020-24-...	Limited to the following serial numbers:525: 525-0685; 0800-on525B: 525B-0057; 0451-onPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon th...	06/11/2020	Active	10074771
10074772	AMAC AEROSPACE SWITZERLAND AG			747-8	Installation of C-Music System self defence system.The change includes the Pod Structural Assembly, (PSA) housing the maincomponents of the system. The PSA is fuselage-mounted at the lowersection of the fuselage.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): B-101, Vibration / buffetingcompliance criteriafor large external antenna installationsThe requirements for environmental protection and the associa...	The change is defined with Revision D of Master Data List DocumentMDL-B7473-1-5300.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual SupplementAFMS-B7473-1-5300.The Aircraft shall be maintained in accordance with Revision B ofInstructions for Continued Airworthin...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2020	Active	10074772
10074779	GROWING ENGINEERING PARTNERS GmbH	REV. 1		A330-202	CLA A330-200 Cabin ReconfigurationRev 1.: Transfer of STC from SR Technics Switzerland to groWINGEngineering Partners GmbH	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Master Document List S.OAEZ.001935-MDL, Rev. 01Instructionsfor Continued Airworthiness S.OAEZ. 001935-ICA, Rev. 00Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Cabin Layout STC 10048558 is a pre-requisite for installation.Lufthansa Technik EASA STC 10014507 Rev.01 “Installation ofnon-electrical Floor Path Marking System” is a pre-requisite forinstallation.Prior to installation of this change/ repair it must be determined thatthe interrelationship between th...	21/04/2021	Active	10074779

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074808	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	A350-941	A350 SKYCOUCH SEAT DEACTIVATIONThis STC deactivates 12-off Safran Seat US (SSUS) Z300 Skycouch serieseconomy class triple seats (10-off standard and 2-off transition seats),previously installed under SWS EASA STC 10059871.To accomplish this, Skycouch leg rests & occupant restraint (CuddleStrap) are(...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	MASTER CONFIGURATION SCHEME doc. Ref. 3213-MCS-01, issue 3 dated29/10/2020<(>,<)>or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Applicable to A350-941 modified per SWS EASA STC 10059871.,,Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the pro...	11/11/2020	Active	10074808
10074814	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04203AT	737-8 737-700/-800/-900/-900ER 737-300/-400/-500/-600	Installation of a Constant Friction Mount, Cradle, and Integrated PowerSupply on Boeing B737 Series Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment:CS25 amdt 0: 25.29, 25.303, 25.561, 25.601, 25.625, 25.789, 25.1307,25.1431, 25.1529, 25.1541, 25.1581CS25 amdt 1: 25.305,C...	1. Avionics Support Group, Inc. Master Data List 213135-MDL, Rev. W,dated 12 April 2018, or later FAA approved revision.2. Instructions for Continued Airworthiness Document 213135-ICA, Rev. C,dated 29 November 2017, or later approved revision.3. Airplane Flight Manual Supplement 213135-FMS dated 13l...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/12/2020	Active	10074814
10074828	KELOWNA FLIGHTCRAFT Ltd.		TCCA STC SA17-123	737-500 737-400 737-300	B737 Cabin Altitude WarningThis modification provides redundancy to the cabin altitude warningsystem on B737-300/-400/-500 aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-101, HIRF; Protection from the indirecteffects of Lightning strikeThe requirementsfor environmental protection and the associatedcertified noi...	K407-102-001-002 Rev H - Modification Data SummaryK407-102-001-014.1 Rev 1 – AFMSK407-102-001-012 Rev. 2 – Chapter 5 – Time Limits / Maintenance Checkor later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/...	- As per Flight Manual Supplement K407-102-001-014.1- As per Airplane Maintenance Manual Supplement - Chapter 5 – TimeLimits / Maintenance Check - K407-102-001-012- Only applicable to aircraft having Boeing SB 737-31A1325 installed- This STC constitutes an Alternative Method of Compliance (AMOC) toE...	13/11/2020	Active	10074828
10074835	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02497SE	A319, A320	Installation of interior components	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment:CS25 amdt 0: 25.853.The requirements for environmental protection and the associatedcertified noise and/ or emissions level...	Northwest Aerospace Technologies, Inc. (NAT) Master DrawingList (MDL) N0560-D10, Revision D, dated 24 January 2017, or later Federal AviationAdministration (FAA) approved revision.Instructions for Continued Airworthiness (ICA) N0560-D70, Revision A,dated 18 January 2017, or later FAA approved revisi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.EASA STC 10056648 (FAA STC ST04024CH) must be installed...	21/01/2021	Active	10074835
10074836	AMAC AEROSPACE SWITZERLAND AG			767-400ER	2Ku-Band Antanna Installation.This change describes the installation of a 2Ku Band (GoGo) antenna onthe top of the fuselage.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-101 Vibration / buffeting compliancecriteria for large external antenna installationThe requirements for environmental protection and the a...	The change is defined with Revision C of Master Data List DocumentMDL-B7671-1-5300.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplementdocument AFMS-B7671-1-5300.The Aircraft shall be maintainedin accordance with Revision A ofInstructions for Continued A...	AMAC Aerospace Switzerland AG Minor Change IB03-2300 "Ku-Band SATCOMSystem installation" shall be accomplished togetherwith thisSupplemental Type CertificatePrior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	17/11/2020	Active	10074836

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074885	GULFSTREAM AEROSPACE CORPORATION			GV GIV	Installation of a SATCOM Direct Router on Gulfstream Models: G-IV and GV	Per FAA STC ST04032AT-DThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact onthe noise database.	Supplemental Type Certificate (STC), ST04032AT-D, Installation SatcomDirect Router (SDR), Date Amended August 25, 2016.Index List ref. CE514298002 Revision B, dated November 5, 2019.Model G-IV:• Instructions for Continued Airworthiness CE41429A009, Revision -,dated August 3, 2016.• Airplane Flight M...	This system is intended to provide Internet connection and email serviceto the airplane's cabin using portable electronic devices (PEDs). Anyother intended function of this equipment will require a re-examinationof the certification basis.Prior to installation of this change/repair it must be determ...	18/11/2020	Active	10074885
10074890	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	777-300ER, 777F 777-200, 777-200LR, 777-300	BOEING 777 SKYCOUCH SEAT DEACTIVATIONThis STC deactivates 10-off Safran Seats US (SSUS) 5751 Series Sky Couchseats previously installed under SWS EASA STC 10050705. To accomplishthis, SkyCouch legrests & occupant restraint (Cuddle Strap) are beingremoved and new armrests and life vest containers (in...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.795(c)(3)(iii)at amendment 9.The requirements for environmental protection and the associatedcertified noise and/ a...	Master Configuration Scheme ref. 3214-MCS-01 issue 01 dated14/08/2020< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Applicable to BOEING 777 modified per SWS EASA STC 10050705.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the pro...	18/11/2020	Active	10074890
10074893	JAMCO AMERICA, INC.		FAA ST01455SE	747-400	Upper deck stowage bin and closet modification in accordance with JamcoAmerica Inc. Master Drawing List IA-104 MDL, revision B dated 09/09/04or later FAA approved revision.				29/11/2004	Active	10074893
10074896	LUFTHANSA TECHNIK AG		LBA STC TA0352	777-200	VIP cabin completionRevision: Replacement of conductive oxygen flex-hoses withnon-conductive ones. Original LBA certificate number TA0352 modified.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): D-03 “Side facing divans” issue 1Deviation(s): D-01 "Direct view” Issue 1, D-02“Doors between passengercompartments” issue 1, D-04 “Firm ha...	Generic documents:STDD 25-99/29M issue 01 rev 01Cabin completion installation:Master Drawing List VP-BRH/HAM TE/Lsy rev03AFM Supplement A-25-00/303 rev IRAFM Supplement A-25-00/304 rev IRAFM Supplement A-00-00/305 rev IRAFM Supplement A-00-00/306 rev IRAMM Supplement A-00-00/262-AMM rev 00Oxygens h...	As per AFM supplements A-25-00/303, A-25-00/304, A-00-00/305 rev IR andA-00-00/306Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the ai...	19/11/2020	Active	10074896
10074897	AEROTEC & CONCEPT			EC 155 B, EC 155 B1 EC 155 B1 EC 155 B	New CVFDR Installation in accordance with Aerotec Change N°19136This STC consists in the installation of a combined voice & data flightrecorder CVFDR Curtiss Wright « Multi-Purpose Flight Recorder » (MPFR)and its associated peripheral devices: CVFDR Curtiss MPFR, Flight DataAcquisition Unit (FDAU),S...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 29 Amdt 7: 29.1316, 29.1317, 29.1457, 29.1459FAR 29 Amdt 16: 29.561.The requirements for environmental protection andc...	Certification Programme AE19136PCDP Rev 1Master Data List AE19136MDL Rev 0Instruction for Continued Airworthiness AE19136ICA Rev 0Rotorcraft Flight Manual AE19136RFMS Rev 0or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/11/2020	Active	10074897
10074910	SOCIETE AIR FRANCE S.A.			A330-203	Connecting the inflight entertainment system (Zodiac inflight innovationRAVE) to air traffic service / communication management unit in order toprovide connecting gate messages topassengers and free textcapabilities to cabin crew via aircraft communications addressing andreporting system (ACARS).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Societe Air France S.A Change Approval Sheet CAS-A330-19-005Societe Air France S.A. AFSB-A330-19-005-23-001 (IFE-ACARS ConnectingGate Message Activation)Societe Air France S.A. Instructions for Continued AirworthinessICA-A330-19-005-001or later revisions of the above listed document(s) approved/ acce...	In case of Air Traffic Service Unit Part Number evolution (hardwareand/or software), the operator shall inform Societe Air France S.A tocheck the need for a new or amended cybersecurity analysis.	20/11/2020	Active	10074910

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074911	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		A321-272NX A321-272N A321-271NX A321-271N/-271NX/-272N/-272NX A321-271N A321-253NX A321-253N A321-252NX A321-252N A321-251NX/-252NX/-253N/-253NX A321-251NX A321-251N A321-232 A321-231 A321-213/-231/-232/-251N/-252N A321-213 A321-212 A321-211 A321-131 A321-112 A321-111/-112/-131/-211/-212 A321-111 A320-273N A320-272N A320-271N/-272N A320-271N A320-253N A320-252N A320-251N A320-233 A320-232 A320-231/-232/-233/-251N/-252N A320-231 A320-216 A320-215 A320-214 A320-212 A320-211/-212/-214/-215/-216 A320-211 A319-153N A319-151N A319-133 A319-132 A319-131/-132/-133/-151N A319-131 A319-115 A319-114 A319-113 A319-112 A319-111/-112/-113/-114/-115 A319-111 A318-122 A318-121 A318-112 A318-111/-112/-121/-122 A318-111	Airbus A320 Series - ADS-B OUT v2 InstallationThis STC replaces the existing ATC transponders with new RockwellCollins TPR-901 transponders that are compliant with ADS-B Out DO-260Bfunctions and configures them for ADS-B Out operation.Rev.1: Transfer of STC	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ATL AFM Supplement No. 13651-AFM-00001 Issue 1ATL Instructions for Continued Airworthiness No. 13651-ICA-00001 Issue 1ATL MMEL No. MMELS-13651-00001 Issue 1ATL Master Document List No. MDL-13651-00001 Issue 1or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/11/2021	Active	10074911

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074937	NORTHERN AVIONICS S.R.L.			A330-343 A330-342 A330-341 A330-323,341,-342,-343 A330-323 A330-322 A330-321 A330-303 A330-302 A330-301,-302,-303,-321,-322 A330-301 A330-243 A330-223 A330-203 A330-202 A330-201,-202,-203,-223,-243 A330-201	Wi-Fi WAvES Installation./Installation of Wi-Fi system intothe cabin ofthe A330 family for passenger usage	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	AFMS NAV0621 R1ICA NAV0621 R1Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limitation as per document AFMS NAV0621 R1Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	24/11/2020	Active	10074937
10074939	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04461AT	737-900ER 737-900 737-800 737-700 737-600 737-500 737-400 737-300	Installation of the Honeywell Solid State Cockpit Voice Recorder (SSCVR)with ACARS message recording capability	The certification basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraphs at a later amendment:CS 25 amdt. 5: 25.1301, 25.1529CS 25 amdt. 23: 25.1457The requirements for environmental protection and the associatedcerti...	1. Master Drawing List, 218194-MDL, Revision A, dated 28 March 2019, orlater FAA approved revision.2. Instructions for Continued Airworthiness (ICA) document 218194-ICA,Rev. IR, dated 14 August 2018 or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/12/2020	Active	10074939
10074945	AMS HELI DESIGN, LLC	REV. 1	FAA STC SR09917AC	AW109SP A109S	Installation of an Advanced Life Support System (ALSS) airborne EMS airambulance interiorRevision 1 is a correction of the FAA STC reference	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR09917AC.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	AMS Master Drawing List Document No. 1835950301, Revision F, dated 26October 2020, or later FAA approved revision.Rotorcraft Flight Manual Supplement Document No. 1835912001, Revision A,dated 29 September 2020, or later FAA approved revision, is required forthe A109S and Rotorcraft Flight Manual Sup...	This approval includes Model A109S helicopters equipped with LeonardoS.p.A. Trekker Kit Part Number 109G0000F01.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	10/08/2021	Active	10074945
10074953	BELL HELICOPTER TEXTRON, Inc.		FAA STC SR11244DS	505	Installation of Expanded Instrument Panel	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR011244DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Drawing List, Report No. AA-17015, Revision A, dated7 November2019, or later FAA approved revision.AeronauticalAccessories Instructions for Continued Airworthiness,ReportNo. AA-17013, No Revision, dated 17 July 2018<(>,<)> or later FAAaccepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/11/2020	Active	10074953
10074954	SPAES GmbH & Co. KG			EC 155 B, EC 155 B1	Tactical Radios antennas installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Program CPL-155-396-23-01, rev 1.0Compliance Check List CCL-155-396-23-01, rev 1.0Declaration of Compliance DOC-155-396-23-01, rev 1.0Master Document List MDL-155-396-23-01, rev 1.0Installation Manual INM-155-396-23-01, rev 1.0Instructions for Continued Airworthiness, ICA-155-396-23-01...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/11/2020	Active	10074954

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10074957	BEONE HAMBURG GmbH			B300C B300 B200GT B200CGT 200C 200	Installation of GPS AntennaInstallation of one GPS Antenna with antenna doubler and coaxial cable.	The original certification basis is complemented by CS 23 at initialissue as documented in certification plan 617-10017-CPL-0001 Rev. C.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this c...	Installation in accordance with Master Document List, 617-10017-MDL-0001at revision A.Instructions for Continued Airworthiness, document 617-10017-ICA-0001at revision A with detailed instructions in document 617-10017-AMM-0001at revision B.or later revisions of the above listed document(s) approved...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/11/2020	Active	10074957
10074959	BOEING IRELAND LIMITED			737-800	SatLINK antenna removal.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Change/Repair approval document BIL-00175-APP rev 00Instructions for continued airworthiness BIL-00175-ICA01 rev 00Airworthiness limitations manual supplement BIL-00175-MS03 rev0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- the installation of an antenna as per STC 10064143 is a prerequisite-the minor change BIL-00174 for deactivation and removal of ArcheionSatLINK system is a prerequisite-limitations as per AWL manual supplement BIL-00175-MS03Prior to installation of this change/repair it must be determined thatthep...	25/11/2020	Active	10074959
10074962	S4A SOLUTIONS FOR AVIATION, S.L			C-212-VA C-212-DE, C-212-DF, C-212-EE C-212-CE, C-212-CF, C-212-DD C-212-CB, C-212-CC, C-212-CD	DS-B Out and PBN Avionics Systems Upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	A1219-RPT02 Master Document List Edition 3A1219-HDK01-A Flight manual supplement Edition 2A1219-HDK01-B Flight manual supplement Edition 2A1219-HDK01-C Flight manual supplement Edition2A1219-HDK02 Maintenance Manual Supplement Edition 2Or later revisions of the above listed document(s) approved/acce...	Se A1219-HDK01-A Flight manual supplement Ed2, A1219-HDK01-B Flightmanual supplement Edi2, A1219-HDK01-C Flight manual supplement Ed2.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ o...	25/11/2020	Active	10074962
10074963	LUFTHANSA TECHNIK AG		LBA TA0745	747-400	Installation of a VIP cabin interior “El Meymoon”, modifiedwithstairway from passenger deck to lower lobe cargo compartment.Revision: replacement of conductive oxygen flex-hoses withnon-conductive ones	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-1 “Certification basis” Issue 2The requirements for environmental protection and the associatedcertifiednoise and/ or emissions levels of the product are unchangeda...	Generic documents:Supplemental type design document STDD 25-02/13M issue 01 rev 02Original installation documents:AFM supplement A-00-03/017-AFM rev IRAMM supplement A-00-03/017-AMM rev IROxygen flex hoses replacement documents:CPL-35-20/05M rev 0or later revisions of the above listed document(s) ap...	As per AFM supplement A-00-03/017-AFMPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	25/11/2020	Active	10074963
10074980 (EASA.A.S.00474)	TELEDYNE UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	757-200	Installation of Teledyne Controls Wireless Ground Quick Access Recorder(WQAR) P/N 2243800.Rev. 1: Transfer from Teledyne Limited to Teledyne UK Limited.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Teledyne Limited Modification FDC.M.011 (Master Data List/ DefinitionDocument STC-MDL-011-03)dated 15/12/2004<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/11/2020	Active	10074980

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075005	LEARJET Inc.	REV. 1	FAA STC ST04455CH	BD-100-1A10	Installation of a Viasat Ka RadomeRev. 1: Transfer of STC 10075005	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	StandardAero Master Data List 10038145, Revision (E), dated13 November2020Instructions for Continued Airworthiness, Document 1038100, Revision(A), dated 13 November 2020or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implementat...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/08/2021	Active	10075005
10075034	SPECIALIST AVIATION SERVICESLIMITED		CAA UK RESPONSIBILITY	429	ESN T-PED Approval in accordance with SAS/MOD/1018	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 27 Amdt. 1: 27.1309,27.1501, 27.1529, 27.1581, 27.1585, Appendix B: B27.7, B27.8, B27.9The requirements for environment...	Flight Manual Supplement FMS/1018-043 Issue AT-PED Compatibility Report (ICA) DR/1018-004 Issue BService Bulletin SB 23-119 Issue BDeclaration of Compliance of Issue B of SAS/MOD/1018or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft T-PED Compatibility is demonstrated for the list ofequipment provided in the Appendix A of theT-PED Compatibility Report DR/ 1018-004 Issue B. Any deviation to thislist leads to the reassessment of theT-PED Compatibility of theaircraft.	04/12/2020	Active	10075034
10075044	IKHANA AIRCRAFT CANADA, Inc.			DHC-6 SERIES 400 DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300 DHC-6 SERIES 210 DHC-6 SERIES 200 DHC-6 SERIES 110 DHC-6 SERIES 100	Enhanced Air Conditioning System Installation in accordancewithTransport Canada Civil Aviation (TCCA) STC SA16-33.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Title 14 CFR Part 23Amendment 23-0 23.303, 23.307, 23.601, 23.609, 23.1367Amendment 23-7 23.619, 23.625Amendment 2...	Ikhana Aircraft Services Manufacturing Drawing List ER218-2516, RevisionA, dated February 26, 2019;Ikhana Aircraft Services Installation Drawing List ER218-2517, RevisionA, dated February 19, 2019;Ikhana Aircraft Services Instruction of Continued Airworthiness DocumentNo. AC-6-11, Revision B, datedI...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/12/2020	Active	10075044
10075050 (FOCA 25-20-95 (GRANDFATHERED))	AEROLITE AG			MBB-BK117 C-2	Installation of EMS Equipment P/N 145060-501The aeromedicalconcept of the EMS-Equipment which is installed insidethe cabin is based on a modular principle with fixed provisions andvarious detachable components.The EMS-Equipment contains aspecific cabin floor layer designed for theinstallation of v...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Aerolite Max Bucher AG Master Drawing List DWL-301- Rotorcraft Flight Manual Supplement FMS-301- Operation and Maintenance Manual OPM-301or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/12/2020	Active	10075050
10075068	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	B200T B200CT, B200T B200CT 200T 200CT 200C 200, 200C, 200CT, 200T 200	Introduction of Osprey 50 in LEAP-RThis design change introduces an Osprey 50 Radar system and interconnectharnesses into the Leading Edge Application Pod-Radar (LEAP-R) approvedunder design change 2XL020 (STC 10062193).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:23-1 through 23-9,Amendment 23-11, FAR Paragraphs 23.175 and associated FARs 23.143(a), 23.145(d), 23.153, 23.161(c)(3) a...	- Installation of Osprey 50 in LEAP-R in accordance with Leading Edge,2Excel Aviation Master DocumentList 2XL049, at issue 2, May 14, 2020;- Operation in accordance with Aircraft Flight Manual Supplement,Leading Edge, 2Excel Aviationdocument 2XL049 LEF71B(1), at Revision 1, dated December 20, 201...	The following Leading Edge, 2Excel Aviation changes constitute apre-requisite for the installation: 2XL019, 2XL020, 2XL021, 2XL030,2XL051, 2XL059, 2XL044, 2XL040 without role fit equipment.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change...	03/12/2020	Active	10075068
10075077	ATELIER CHABORD	REV. 1		TB 20	TB20 EXHAUST MUFFLERRev. 1 corrects the Associated Technical Documentation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS23 Initial Issueparagraphs:23.21, 23.23, 23.25, 23.29, 23.45, 23. 53, 23.63, 23.65, 23.69, 23.71,23.77, 23.201, 23.203...	- Master Document list MDL-TB20-16-01H dated 19.11.2020- Aeroplane Flight Manual Supplement / Supplément au Manuel de Vol Ref.SUPMV-TB20-16-01A<(>,<)>dated 11.02.2020Or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/11/2021	Active	10075077

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075078	DASSAULT FALCON JET CORPORATION		FAA ST04217CH	FALCON 2000EX FALCON 2000	EGPWSEnhanced Ground Proximity Warning System upgrade (238-238) with aSmartRunway SmartLandingoption (RAAS)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- MDL 1032092 rev C- AFMS 1032805 rev B- ICA 1032651 Rev D-MMEL Supplement DFJ-MMELS-F2000-00-I1 issue 1-MMEL Supplement DFJ-MMELS-F2000EX-00-I1 issue 1or later revisions of theabove listed document (s) approved/accepted onbehalf of EASAin accordance with the Technical ImplementationProcedures of...	The “Reloadable Customer Definitions (RCD)” part number that is loadedin the Enhanced Ground Proximity Computer shall be: 718-1601-203 (Configuration 1 “Low Volume”).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpre...	04/12/2020	Active	10075078
10075079	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		MBB-BK117 D-3 MBB-BK117 D-2	Installation of Flightcell DZMx with optional activation ofintegratedWireless Functions (WiFi / Bluetooth).Revision 1Extension of applicability to MBB-BK117 D-3 and addition of analternative GSM Antenna location andintroduction of latest DZMX HW/FW.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Revision 0RFMS for Flightcell DZMx, Doc. 2117706-AM A Issue3 dated 24.11.2020;Addendum to RFMS for Flightcell DZMx, Doc. 2117706-AM B Issue 2 dated24.09.2020;MMEL Supplement, Doc. 2117706-ME Issue 1 dated 21.01.2020;Instructions for Continued Airworthiness, Doc. 2117706-CA Issue 1 dated26.05.2020;A...	MBB-BK117 D-2m is excluded.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installedchange and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	03/06/2024	Active	10075079
10075096	GDC ENGINEERING GmbH			A320-251N	A320-251N cabin modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Certification Document List CCN-MCDL-A320B Issue 01 dated 4 Dec2020ICA & Operator Manual Supplement A320B-ICA-A Rev 01 dated 3 Dec 2020or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/12/2020	Active	10075096
10075105	AEARO TECHNOLOGIES LLC		FAA STC ST04387CH	FALCON 2000, FALCON 2000EX	Install thermal/acoustic insulation system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04387CH.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Aearo Technologies Master Data List MDL-1764-002. Revision A. dated 15January 2019, or later FAA approved revisions.FAAAccepted Instructions for Continued Airworthiness, ManualICA-1764-001, Revision IR, dated 17 January 2019, or later FAAacceptedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/12/2020	Active	10075105
10075109	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01892WI	747-400, 747-400F, 747-8F	Modification of an existing Rockwell Collins Global LandingUnit (GLU)Multi-Mode Receiver (MMR), Sensor Systems Inc. GPS Antenna and ACSSTransponderRev. 1: adds the 747-8F airplane to the applicability list.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments:CS25 at amendment 12: 25.301(a), 25.303, 25.305(a)(b)(c) , 25.307 (a),25.365(a)(b)(d) , 25.561(b)(3)(c) , 25.581(a)(b)(1)(2) , 25.601,25.603(a)(b) , 2...	1. Master Drawing List RCA-0637, Revision C, dated 7 November 2024.2. Instructions for Continued Airworthiness RCA-0624, Revision C, dated15 May 2024, or later FAA approved/accepted revision for item 1 and 2.	Prior installation and approval of a Rockwell Collins, Inc.GLU_920/925and ACSS XS-950 Transponder systems installations are a prerequisite forthe 747-400 and 747-400F aircraft.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andp...	10/03/2025	Active	10075109
10075110	LEE AEROSPACE, INC.		FAA STC ST01228WI	SEE FAA AML	Replacement of OEM window pane assemblies with Lee Aerospace laminatedwindow assembly and termination of OEM dry air system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01228WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Lee Aerospace Master Drawing List, LAI-001-MDL, Revision D,dated 13February 2004, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	08/12/2020	Active	10075110

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075112	LEE AEROSPACE, INC.		FAA STC ST01935WI	MU-300 400A 400	Installation of Windshields	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC01935WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the origi...	- For model MU-300, Master Data List, No. 17-003-SC4301 Rev0*, dated 4December 2019.- For models 400, 400A, Master Data List, No. 17-003-SC4301 Rev 0*,dated 4 December 2019.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/12/2020	Active	10075112
10075118	LEARJET Inc.	REV. 1	FAA ST04490CH	BD-100-1A10	Installation of a Viasat Business Aviation Router (VBR) P/N1371388	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List 1039044, Revision (B), dated 13 November 2020Airplane Flight Manual Supplement, Document number 1038992 Rev (A),dated 12 November 2020or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA inaccordance with the Technical ImplementationProcedures of EU...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/12/2022	Active	10075118
10075120	LEARJET Inc.	REV. 1	FAA STC ST04457CH	BD-100-1A10	Installation of a Viasat Ka TerminalRev. 1: Transfer of STC10075120	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-StandardAero Master Data List 1038079, Revision (B), dated14 November2020,- Airplane Flight Manual Supplement, Document Number 1038445, Rev (B),dated 13 November 2020,-Instructions for Continued Airworthiness, Document 1038099, Revision(A), dated 12 November 2020, in addition to the basic airplanem...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC requires prior or concurrent embodiment of EAS...	30/08/2021	Active	10075120
10075124	SPECIALIST AVIATION SERVICESLIMITED		CAA UK RESPONSIBILITY	AW169	ESN T-PED Approval in accordance with SAS/MOD/1016	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Rotorcraft Flight Manual Supplement FMS/1016-043 Issue ADeclaration of Compliance for SAS/MOD/ 1016 Issue BT-PED Compatibility Report DR/ 1016-004 Issue AService Bulletin SB 23-120 Issue A	The aircraft T-PED Compatibility is demonstrated for the list ofequipment provided in the T-PED Compatibility Report DR/1016-004 IssueA. Any deviation to this list leads to the reassessment of the T-PEDCompatibility of the aircraft.	09/12/2020	Active	10075124
10075142	GARMIN INTERNATIONAL, Inc.	REV. 7	FAA SA02658SE	SEE FAA AND EASA AML	Installation of Garmin GI 275 Multi-Function Display SystemNew STC Validation for Garmin GI 275 Multiple Function Electronic FltDisplayRev. 2: Added the B-N BN2T-4S, Cessna 305A/ B/C/D/E/F, De HavillandBeagle B.121 to the AML. Updated B-N TC info and a model name.Rev. 3: Added PA-46-600TP to the AMLR...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:See Annex dated 25/03/2024.The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements...	For Aircraft in FAA AML to FAA STC SA02658SEGarmin Master Drawing List (MDL) 005-01208-41, Revision 24, dated 16 May2024<(>,<) >Airplane Flight Manual Supplement (AFMS) 190-02246-12 Revision 4, andEASA Flight Manual Supplement190-02246-15, Revision 1, dated 15 December 2020<(>,<) >Instructions for Con...	The aircraft's magnetic wet compass must be retained for all GI 275installations.The STC is valid for aircraft types and models approved by EASA andlisted on the FAA AML SA02658SE, dated 16 May 2024 and for aircrafttypes and models listed in EASA AML to EASA STC 10075142 attached tothis approval (wh...	17/07/2024	Active	10075142
10075151	JET AVIATION AG	REV. 1		A320-214	Cabin ReconfigurationThe previous VIP interior was modifiedby re-configuring the fwdlounge area. The existing lounge area cabinetry, monuments, seats andtables were removed and new seating arrangement installed. Thereconfiguration reducesthe number of TTOL passenger seats in theforward area from 1...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraphs are at later amendment:CS25 Amendment 2425.25, 25.27, 25.29, 25.301, 25.302, 25.303,25.305, 25.307, 25.321,25.321, 25.365, 25.561, 25.571, 25.60...	- MASTER DATA LIST: Doc No. JBSL-M-03542MDL-001, ISSUE C- AIRPLANE FLIGHT MANUAL SUPPLEMENT : Doc. No. JBSL-M-03542AFM-001,ISSUE BOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Private Operation (Not-for-Hire, Non-Commercial)<(>,<)>STC 21, EASA STC 10035344, Cusom Interior A320 Jubilee, is apre-requisite for installation.STC 21, EASA STC 10052458, Reworks STC 10035344, is a pre-requisite forinstallation.Prior to installation of this change/repair it must be determined that...	18/01/2021	Active	10075151

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075154	SABENA TECHNICS BGC			A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112	Removal of GEE Ku/A791 Satellite Antenna and Structural Provisions onAirbus A318/A319/A320/A321	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-25 at amendment 4paragraphs: 1, 29, 611, 843, 1301, 1351, 1357, 1525, 1529, 1541, 1581,and 1587. CS-25 at amendment 8 p...	- Master Data List, Ref. 0898-01-A-MDL-R00, dated 11 Dec 2020;- Instructions for Continued Airworthiness:Ref. 0898-01-A-ICA-R00, dated 10 Dec 2020, for A319, A320 and A321models,Ref. 0898-01-A-ICA-F01-R00, dated 10 Dec 2020, for A318 model;- Airplane Flight Manual Supplement, Ref. 0898-01-A-AFMS-R00...	This STC is limited to aircraft fitted with Aeroconseil STC0874-01(EASA Ref. 10067212) “GEE Ku/A791 Satellite Antenna ProvisionsInstallation on Airbus A318/A319/A320/ A321”Limitations as per §3 of Instructions for Continued Airworthiness(Inspections) document and §3 of Airplane Flight Manual Supplem...	14/12/2020	Active	10075154
10075160	FTI ENGINEERING NETWORK GmbH	REV. 1		DORNIER 228-202 DORNIER 228-201 DORNIER 228-200 DORNIER 228-101 DORNIER 228-100	Dornier 228 Flight Deck Upgrade, comprising integration of two FMS (dualGarmin GTN) with LNAV (LPV), implementation of ADS-B Out capabletransponders, implementation of one trafficreceiver (Flarm and ADS-B),replacement of VHF COM3, integration of one digital standby instrumentwith backup battery.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 Li batteries.CS-ACNS Iss 2The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the pr...	Installation in accordance with FTI Engineering Network GmbH MasterDocument List ref F18-EO20-0004 Iss 1 dated 08.12.2020.Operate in accordance with FTI Engineering Network GmbH Flight ManualSupplements as defined in Master Document List ref F18-EO20-0004 Iss 1dated 08.12.2020.Instructions for Conti...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/02/2021	Active	10075160
10075163 (EASA.IM.A.S.02778)	CHIPPEWA AEROSPACE, Inc.	REV. 1	FAA ST03336AT	CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700, 701, 702) CL-600-2B19 (RJ SERIES 100)	Installation of LRU Avionics Protective CoversRev. 1 extends the applicability to model CL-600-2E25.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 amdt 0: 25.303, 25.561, 25.601, 25.603, 25.605, 25.607, CS 25.625CS 25 amdt 1: 25.301, 25.613CS 25 amdt 2: 25.305,T...	- Chippewa Aerospace Master Drawing List (MDL) No. 601-2451-01-0001,Rev. 9, dated 21 October 2019;- Instructions for Continued Airworthiness (ICA), Chippewa Aerospace,Inc. Document No. 601-2451-01-0002, Rev. 6, dated 08 April 2019;or later revisions of the above listed document(s) approved/ accepte...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/02/2021	Active	10075163
10075164	DUNCAN AVIATION, INC.		FAA STC ST01949WI	BD-700-1A11 BD-700-1A10	Installation of Aviation Clean Air Bi-Polar Ionization System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01949WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Duncan Aviation, Inc. STC Master Document List Doc. No. CERTDOC-011232,Rev. A, dated 12 August 2020, or later FAA approved revisions.Duncan Aviation, Inc. Instructions for Continued Airworthiness, Doc. No.CERTDOC-011323, Rev. B, dated 12 August 2020, or later FAA acceptedrevisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/12/2020	Active	10075164

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075171	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	A330-941 A330-343 A330-342 A330-341/-342/-343 A330-341 A330-323 A330-322 A330-321/-32/-323 A330-321 A330-303 A330-302 A330-301/-302/-303 A330-301 A330-243F A330-243 A330-223F A330-223/-223F/-243/-243F A330-223 A330-203 A330-202 A330-201/-202/-203 A330-201	Introduction of ARINC 791 SATCOM System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	EASA Approved:STC Twenty One Limited Aircraft Maintenance Manual Supplement andInstructions for Continued AirworthinessNo. S21.AMMS-0043 at latestissue.EASA Accepted:STC Twenty One Ltd Master Document List No. S21. MDL-1468 Issue 1Or later revisions of the above listed document(s) approved/accepted...	A radome and VSAT adapter provisions must be installed prior to orcurrently with this design change. The provisions must be compatible andhave been previously substantiated to embody a VSAT Antenna with thefollowing characteristics:a. Weight - 60Kgb. Swept Diameter - 980mmc. Height – 280mm	14/12/2020	Active	10075171
10075198	GAMA AVIATION (ENGINEERING) LIMITED		CAA UK RESPONSIBILITY	35A	FMS Upgrade with Universal Avionics UNS-1Lw	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	According to Gama Aviation (Engineering) Ltd MDL DocumentGAEL-1670MDL-01 Issue1To be operated in accordance with Gama Aviation (Engineering) Ltd AFMSDocument No. GAEL-1670AFMS-01 Issue 3To be installed i.a.w. Gama Aviation (Engineering) Ltd DocumentGAEL-1670DS-01 Issue 1To be maintained i.a.w. GamaG...	Conditions:This change is only for aircraft equipped as defined in Chapter 3 ofGAMA Design Statement GAEL1670DS-01 Issue (or later approved)Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changee...	15/12/2020	Active	10075198
10075201	AIRPLUS MAINTENANCE GmbH	REV. 1		SEE EASA APPROVED MODEL LIST DR 400/RP DR 400/NGL DR 400/500 DR 400/2+2 DR 400/200 R DR 400/180 S DR 400/180 R DR 400/180 DR 400/160 D DR 400/160 DR 400/140 B DR 400/140 DR 400/125 I DR 400/125 DR 400/120 D DR 400/120 A DR 400/120 DR 400/100 DR 380 DR 360 DR 340 DR 315 DR 300/180 R DR 300/140 DR 300/125 DR 300/120 DR 300/108	Installation of Aspen EFD1000 Primary Flight Display System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-23, Amendment 41, 29, 301, 303, 305, 307, 561, 603, 605, 1301, 1306, 1308, 1309, 1321,1329, 1335, 1351, 1365, 1431, 152...	- Aircraft Flight Manual Supplement PO-1868-000000, Issue 01- Maintenance Manual Supplement MM-1868-000000, Issue 01Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/12/2020	Active	10075201

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075216	LUFTHANSA TECHNIK AG		LBA STC TA0560	737-800	VIP Cabin Completion (EAGLE)Rev 1: Replacement of conductive oxygen flex-hoses with non-conductiveones. Renumbering certificate from German LBA STC TA0560.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-1.1 Cabin Conversion (BBJ) for Boeing 737-800isolated compartment (EAGLE)Deviation (s): JAR 25.785(j) Firm Handhold, JAR 25.807(d)(7) EmergencyExi...	Generic documents:STDD-00-02/02 M Issue 03 rev 01Original installation documents:Airplane Flight Manual Supplement-,,Doc. No A-52-03/046-AFM, Rev. IR (July 04/03): Passenger CabinInternal Doors indication-,,Doc. No A-26-03/047-AFM, Rev. IR (Nov 17/03): Passenger Cabin SmokeDetection System-,,Doc. NoE...	- Limitations as per AFM supplements A-52-03/046-AFM, A-26-03/047-AFM,A-00-03/045-AFM and A-00-03/027-AFM-Possible electromagnetic or other interferences between the Head-UpGuidance System and this STC installation have not been checked. Priorto future activation of the Head-Up Guidance System, ita...	16/12/2020	Active	10075216
10075218	LUFTHANSA TECHNIK AG	REV. 1	LBA STC TA0585	747-400	VIP – Interior and Systems InstallationRev 1: Replacement of conductive oxygen flex-hoses with non-conductiveones. Renumbering certificate from German LBA STC TA0585.Rev 2: typo corrected	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): JAR 25.785(h)(1), JAR 25.813(e), JAR 25.785(d) and JAR25.853(a)(1) The requirements for environmental protection and the associatedcertified noise and/ or em...	Generic documents:STDD-00-01/02 M issue 04 rev 02Original installation documents:Lufthansa Technik Specification Doc. NoS-25-00/081 dated Dec. 31, 2000or later revisionSupplementsto AFM D6U10002-4F6 as follows-,,Doc. No A-23-01/136-AFM (IFE Cut Off Switch), dated March 23, 2002 orlater revision-,,D...	- Limitations as per AFM supplements A-23-01/136-AFM, A-00-02/140-AFM,A-26-02/149-AFM, A-00-02/150-AFM and A-00-02/153-AFMPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wil...	21/01/2021	Active	10075218
10075220 (EASA.A.S.00221)	LUFTHANSA TECHNIK AG	REV. 1		737-800	VIP Cabin Completion (MIDROC)Rev. 1: Replacement of conductive oxygen flex-hoses with non-conductiveones. Renumbering certificate from EASA.A.S. 00221.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-1.1 Cabin Conversion (BBJ) for Boeing 737-800isolated compartment (MIDROC)Deviation (s): JAR 25.785(h)(1) seats, berths, safety belts andharnesses,...	Generic documents:STDD-00-03/10 M issue 02 rev 02Original installation documents:Airplane Flight Manual Supplement Doc. No A-00-04/106-AFM, Rev IR, (Jul01/04)Dispatch Deviations Guide Supplement Doc. No A-00-04/106-DDG, Rev 01, (Aug 26/04)Oxygen flex hoses replacement documents:CPL35-20-02M rev 0or la...	- As per Airplane Flight Manual Supplement Doc. No A-00-04/106-AFM, RevIR.-Maximum Passenger seating capacity: 25.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intro...	16/12/2020	Active	10075220
10075222	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	727-200F 727-200	ACTIVATION OF CPDLC (ATN B1 AND FANS 1/A+) AND ESSENTIAL SATVOICE FORATSThis Change is raised to comply with the 2020 mandates for CPDLC (ATNB1) and FANS 1/A+. It also facilitatesthe approval of a Long-RangeVoice Communications System (LRVC) for Air Traffic Services (ATS) Voice.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 Amdt. 21:CS25.773 (a)CS25.777(a) CS25.1301 (a)(1)CS25.1302 (a) CS25.1302 (b)CS25.1309 (a) CS25.1309 (b)CS25.1309 (c) CS25...	EEASA Approved:STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0163 Issue 2STC Twenty One Ltd Maintenance Manual /AWL Supplement No. S21.AMMS-0083at latest issueEASA Accepted:STC Twenty One Ltd Master Document List No. S21. MDL-1458 Issue 1Or later revisions of the above listed document(s) a...	The following STC Twenty One Ltd Minor Changes must be embodied priorto, or concurrently with, the embodiment of this Change:-S21.20-12-1047 - Introduction of Wiring Provision forMid-Life Upgrade-S21.23-12-1185 - Introduction of SATCOM Provisions for Essential Voice& Data-S21.31-12-1081 - Introduct...	17/12/2020	Active	10075222
10075224 (LBA STC TA0501)	LUFTHANSA TECHNIK AG	REV. 1		737-800	Installation of Lowa VIP Cabin ConversionRevision 0: Replacement of conductive oxygen flex-hoses withnon-conductive ones. Certificate renumbering from German LBA STC TA0501.Revision 1: limitations in AFM Supplements updated.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The requirements for environmental protection and the associatedcertified noise and/ or emissionslevels of the product are unchangedand remain applicable tot...	Generic documents: STDD-00-01/05M issue 04 revision 00Original installation documents:Airplane Flight Manual SupplementDoc. No A-23-02/228-AFM Rev IRAirplane Flight Manual Supplement Doc. No A-25-02/230-AFM Issue 02/ Rev00Airplane Flight Manual Supplement Doc. No A-26-02/225-AFM Rev IRAirplane Flig...	Limitations as per AFM supplements A-23-02/228-AFM, A-25-02/230-AFM,A-26-02/225-AFM and A-52-02/226-AFMPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adve...	06/01/2022	Active	10075224

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075225	VENTURA AEROSPACE, Inc.		FAA ST02691LA	737-800	Installation of 9g Rigid Cargo Barrier	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments:CS25 amdt. 1: 25.305CS25 amdt. 5: 25.611, 25.613.The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	Ventura Aerospace, Inc. Master Data List VA-MDL-1002, Revision B, dated11 December 2018Instructions for Continued Airworthiness, VA-AMM-1 001, Revision A,dated 11 December 2018Airworthiness Limitations and Certification Maintenance Requirements,Document VA-AMM-1001, Revision A, dated 11 December 201...	EASA STC 10076409 (FAA STC ST02690LA - B737-800 Passenger to FreighterConversion) must be concurrently installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introdu...	07/05/2021	Active	10075225
10075233	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE	REV. 1	FAA ST04414CH	A320-214 A319-112	Cabin Interior ReconfigurationRev. 1 adds model A319-112 and includes a new installation dataconfiguration "MDL Group 6".	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments: CS 25 amt. 0: 25.29(a)(b), 25.301 (a)(b) , 25.303,25.305(a)(b) , 25.307, 25.561, 25.571(a)(b) , 25.601, 25.603(a)(b)(c) ,25.605 (a) , 25.607(a)(b)(c)2...	- Astronics Connectivity Systems & Certification Master Data List, Doc.No. DC104-9901-00, Rev. N, dated 17 May 2023;- FAA approved Airplane Flight Manual Supplement as defined in AstronicsArmstrong Master Data List, Doc. No. DC104-9901-00;- Instructions for Continued Airworthiness - Airworthiness Li...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/07/2023	Active	10075233
10075235	SPECIALIST AVIATION SERVICESLIMITED		CAA UK RESPONSIBILITY	MD900	ESN T-PED Approval in accordance with SAS/MOD/1017	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Flight Manual Supplement FMS/1017-043 Issue AT-PED Compatibility Report (ICA) DR/1017-004 Issue AService Bulletin SB 23-121 Issue ADeclaration of Compliance Issue A of SAS/MOD/1017or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft T-PED Compatibility is demonstrated for the list ofequipment provided in the Appendix A of the T-PED Compatibility ReportDR/ 1017-004 Issue A. Any deviation to this list leads to thereassessment of the T-PED Compatibility of the aircraftPrior to installation of this change/ repair it must...	17/12/2020	Active	10075235
10075251	ALPINE AEROTECH LP	REV. 1	TCCA STC SH99-220	2. 205A-1 1. 212, 412, 412EP	Installation of Shoulder Harness Kit - SH99-220Revision 1: Models Bell 412 and 412EP added, EASA Certification Basisupdated	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:for Model 412EP: FAR 29.2 Amdt. 29-32for Model 205A-1, FAR 29,Amdts. 29-1, 29-2: 29.1, 29.301, 29. 303,29.305, 29.307, 29...	-Compliance Program, Report 191M-99-001, Revision NI-Supplement to Compliance Program 191M-00-001 Rev. NI, dated 29 March2023- Master Data List No. 191M-99-001-MDL, Revision J-for 212, 412, 412EP: Maintenance Manual Supplement No. 191M-99-001-MMS,Revision C-for 205A-1: Maintenance Manual Supplement N...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Applicability note: Shoulder Harness Kit - SH99-220 ist...	22/05/2023	Active	10075251
10075254	ALPINE AEROTECH LP		TCCA SH09-52	C. 212, 412, 412EP B. 214B, 214B-1 A. 205A-1	Bell Medium Bear Paw Kit - SH09-52	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:For 205A-1 and 212,412 and 412EP, FAR 29 Amdts. 29-1 through 29-9: Amdt. 29-0 - 29.29, 29.251, 29.301, 29.303, 29.305, 2...	- Compliance Checklist, 1072-CMP-01, Issue 1- Master Data List No. AAL-290-044-001, Revision N- 'Instructions for Continuing Airworthiness No. AAL-290-045-701,Revision E'or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implementat...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/12/2020	Active	10075254

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075257	GLOBAL AEROSPACE DESIGNCORPORATION		FAA ST04434CH	777-300	Install First Class Seat Upgrade	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Global Aerospace Design Corp. Master Drawing List 18GR146-MDL, dated16 October 2019, or later FAA approved revision.- Instructions for Continued Airworthiness 18GR146-ICA, Revision B,dated 11 December 2019, or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/01/2021	Active	10075257
10075259	CARLISLE INTERCONNECT TECHNOLOGIES	REV. 1	FAA ST04334CH	A321-253N A321-231 A321-211/-231/-253N A321-211 A320-233 A320-214/-233 A320-214 A319-132 A319-115/-132 A319-115	Installation & Activation of the ARINC 791 Ka-Band SATCOM SystemRev. 1 corrects the Technical Documentation and Limitations/Conditions.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:,,- Equivalent Safety Finding(s): EASA 0010064140-001 CRI C-02 VIBRATIONBUFFETING.The requirements for environmental protection and the associatedcertified noise and/ or e...	Master Data List, Document No. 900-102529 Revision HAFM Supplement 900-102531 Revision BInstructions for Continued Airworthiness for Configurations 1-5 DocumentNo 900-102532 Revision EInstructions for Continued Airworthiness for Configurations 6-10Document No 900-106369 Revision AEWIS ICA Source Doc...	Airplane Flight Manual Supplement, Document No. 900-102531 Revision BInstructions for Continued Airworthiness (ICA) forConfigurations 1-5,Document No. 900-102532 Revision EInstructions for Continued Airworthiness (ICA) for Configurations 6-10,Document No. 900-106369 Revision A.Prior to installation...	11/01/2021	Active	10075259
10075260	MOTORSEGLER-CLUB BERLIN e.V.			SF 25 C	SF 25 C-UM "Rennfalke"	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:Additional JAR-22.375Winglets.This certificate/ approval involves a change to the requirements forenvironmental protecti...	- STC SF 25C-UM „Rennfalke“- Lärmvermerk 20701-T334/EASA.A.098, Ausgabe 1 vom 28.10.2020- Zeichnungsliste SF 25 C-UM “Rennfalke”, Ausgabe 27.10.2020- Ergänzungen zum Flughandbuch zum Betrieb des SF 25 C-UM “Rennfalke”Rev. 2- Ergänzungen zum Betriebshandbuch des SF 25 C-UM „Rennfalke“, Rev. 1or lateru...	Only for SF 25 C Falke , D-KDDK, S/N 44136.Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introducenoadverse effect upon the airworthiness of the product.	18/12/2020	Active	10075260
10075263	ALAMO ENGINEERING GmbH	REV. 2		BD-700-1A10, BD-700-1A11	Installation of Iridium Satcom AntennaRev. 1: Mirrored Location of the 1ch Iridium Antenna Installation (FS767 and 781)in the skin panel from A/C CL (STR0) RHS to the LHS.Extension of approved Model BD-700-1A10 to include BD-700-1A11.Rev.2 adds two alternative and additional location for the insta...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.571 Amdt. 25.The requirements for environmental protection and the associatedcertified noise and/ ora...	Master Document List (MDL20A15AE-01) with Rev. D dated 24.10.2024Instructions for Continued Airworthiness ICA20A15AE-01with Rev. D dated15.10.2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The STC only covers the structural integration of the Iridium antenna.Any function and operation of the antenna will besubject to anotherengineering approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviousl...	29/10/2024	Active	10075263
10075267	LUFTHANSA TECHNIK AG	REV. 1		A321-271N/-272N A321-251N/-252N/-253N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-113/-114/-115	Exchange of emergency exits slides.Rev. 1: Correction of models	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Description of Change BDF01-25 Revision 5Supplemental Type Design Document STDD25-20/03M Issue 0 Rev 0Operational Requirements Document BDF01-25-OR-001 rev 0Instructions for Continued Airworthiness A-00-20/47-ICA Issue 1 rev 0or later revisions of the above listed document(s) approved/ acceptedunder...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/05/2021	Active	10075267

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075268	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	A321-272NX A321-272N/-272NX A321-272N A321-271NX A321-271N/-271NX A321-271N A321-253NX A321-253N A321-252NX A321-252N A321-251NX A321-251N A321-232 A321-231 A321-213 A321-212 A321-211/-212/-213/-231 A321-211 A321-131 A321-112 A321-111/-112/-131 A321-111 A320-273N A320-272N A320-271N/-272N/-273N A320-271N A320-253N A320-252N A320-251N A320-233 A320-232 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211 A319-153N A319-151N A319-133 A319-132 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111 A318-122 A318-121 A318-112 A318-111/-112/-121/-122 A318-111	Introduction of ARINC 791 SATCOM System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 Amendment 1125.1307 (c)CS 25 Amendment 1525.251 (d)(e) 25.60125.60325.605 (a) 25.60725.609 (a)25.613 (a) 25.1360 (a)(b)C...	EASA Approved:STC Twenty One Limited Aircraft Maintenance Manual Supplement andInstructions for Continued AirworthinessNo. S21.AMMS-0062 (A320) andS21.AMMS-0063 (A321) at latest issue.EASA Accepted:STC Twenty One Ltd Master Document List No. S21. MDL-1519 Issue 2Or later revisions of the above list...	A radome and VSAT adapter provisions must be installed prior to orcurrently with this design change. The provisions must be compatible andhave been previously substantiated to embody a VSAT Antenna with thefollowing characteristics:a. Weight - 60Kgb. Swept Diameter - 980mmc. Height – 280mmPrior to i...	18/12/2020	Active	10075268
10075269	Q.C.M. DESIGN GmbH	REV. 1		EMB-135BJ, EMB-550	Seat Belt RefurbishmentRev. 1 is issued to include EMB-550 model.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Certification Report, Seat Belt Refurbishment ref. J135-QCM25-018,Revision Eight, dated 09 December 2022.- Engineering Bulletin ref. EB- J135-QCM25-018, Revision Eight, dated 09December 2022.- Instructions for Continued Airworthiness ref. J135-QCM25-018-M1-ICA,Revision Eight,dated 09 December 2022...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/02/2023	Active	10075269

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075271	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			200	Installation of TCAS II and ADS-B Out	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23 initial issue;CS-23.1306 and CS-23.1308 at Amendment 4; CS-ACNS Issue 2.The requirements for environmental protect...	Installed and maintained in accordance with Medavia Master Document ListRef: MODE00310_MDL Revision 1 dated 18/12/2020,operated in accordancewith Medavia Flight Manual SupplementRef: MODE00310_AFMS1 Revision 1dated 02/09/2020or later revisions of the above listed document(s) approved/ acceptedunder...	Due to the single IVSI TA/RA indicator installation on the left-handside, the operation of the TCAS 7.1 system as certified under thisdesign change, is restricted to single pilot operations ONLY.Prior to installation of this change/repair it must be determined thatthe interrelationship between thisp...	18/12/2020	Active	10075271
10075272	GROB AIRCRAFT SE	REV. 1		208B	Installation of the wing hard points to be used for mounting an externalequipment.Revision accounts for the STC transfer from GDG Engineering GmbH to GrobAircraft SE	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:-The following paragraph(s) at a later amendment: Paragraphs affected bythis change as per Certification Program CP-570-C208A-02 issue 2:FAR23 regulation as a...	Master Certification Document List, CCN-C208A, issue 2, dated 26 October2020.To be installed according to:Master Document List, C208A-MDR-570000, issue B, dated 26 October 2020.Tobe maintained according to:Aircraft Maintenance Manual Supplement, C208A-AMM-A-01, dated 21 October2020.To be operated a...	External equipment to be mounted on the wing hard points isnot approvedby this STC approval.Limited to S/N: 208B5405.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will in...	24/04/2024	Active	10075272
10075283	JET AVIATION AG	REV. 1		A320-251N	VVIP Cabin Interior CompletionThis modification installs a VVIP Cabin Interior into a green AirbusA320-251N. The aircraft will be outfitted to accommodate 2 Cabin Crewand 22 Passengers.Revision 1: compliance to Operational Suitability Data- Cabin Crew(OSD-CC) added	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS25 amendment 21:25.23, 25.25, 25.27, 25.29, 25.251, 25.301,25.302, 25.305, 25.307,25.321, 25.337, 25.341, 25.365, 25.56...	JBSC-M-00179MDL-01 ISSUE 05 MASTER DATA LISTJBSC-M-00179AFM-01 ISSUE 02 AIRPLANE FLIGHT MANUAL SUPPLEMENTJBSC-M-00179ICA-01 ISSUE 01 INSTRUCTIONS FOR CONTINUED AIRWORTHINESSJBSL-M-01299ICA-01 ISSUE 02 INSTRUCTIONS FOR CONTINUED AIRWORTHINESSJBSC-M-00179CCS-01 ISSUE 06 CERTIFICATION COMPLIANCE SHEETJ...	Private Operation (Not-for-Hire, Non-Commercial)Non-SmokingaircraftPrior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of...	01/03/2021	Active	10075283
10075287	PARC AVIATION ENGINEERING SERVICESLIMITED			A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-171N A319-131/-132/-133/-151N/-153N A319-111/-112/-113/-114/-115	Airbus A319/ A320/ A321 Zero Passenger configurationEASA Approved Model List (AML) STC for the reconfiguration of aircraftin the Airbus A320 family to zero passenger seat LOPA's. The AML STCincludes A319, A320 and A321 aircraft types.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): E-4105: Type III Overwing Emergency Exit Access(Group 1) & E-2105: Type III Overwing Emergency Exit Access (Group 2).- The following paragraph(s) a...	Master Document List 320-25317-MDL, rev 00 dated 22.10.2020Aircraft Flight Manual: . 320-25317-AFM-01 rev 00 (A319) . 320-25317-AFM-02 rev 00 (A320) . 320-25317-AFM-03rev 00 (A321)Illustrated Parts Catalogue : . 320-25317-IPC-01 rev 00 (A319) . 320-25317-IPC-02 rev 00 (A320)Airc...	As stated in AFM Supplement.Prior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect uponthe airworthiness of the product.	21/12/2020	Active	10075287
10075293	AEROSPACE DESIGN & COMPLIANCE LLC		FAA SA04199NY	AVANTI II	Installation of Becker Avionics DVCS6500 digital voice communicationsystem.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Aerospace Design & Compliance LLC MasterData List (MDL) ref P180-MDL-0056, Rev IR, dated September 23, 2020.Operate in accordance with Aerospace Design & Compliance LLC AeroplaneFlight Manual Supplement (AFMS) ref P180-AFMS-0056, Rev IR, datedSeptember 23, 2020.Instru...	This STC is applicable to all serial numbers P180 models designated asAvanti II or Avanti EVO with Baker Electronics B1045 audio panels;Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/...	21/12/2020	Active	10075293

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075304	APTOZ EHF.	REV. 1		767-200, 767-300	Transportation of cargo on the floor in passenger compartmentRev. 1 extends the calendar limitation to 31 July 2022.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): DEV D-60073416 “Transportation ofcargo in passengercompartments”- The following paragraph(s)at a later amendment:JAR 25.793 at change 8;JAR 25.858 at ch...	- Master Data List MDL251156 Rev O, dated 7 Oct 2021- Aircraft Flight Manual Supplement AFM251156-1 Rev E, dated 7 Oct 2021- Instructions for Continued Airworthiness ICA251156-1 Rev D, dated 7Oct 2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The allowance to transport cargo in passenger compartment is limited to2 000 FH following installation of the change orto 31 July 2022,whatever occurs first.Prior to installationof this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	19/11/2021	Active	10075304
10075306	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED		CAA UK RESPONSIBILITY	EC135 T3 EC135 T2+ EC135 T2	Upgrade of Garmin GTN750 installation enabling Satellite BasedAugmentation System (SBAS) Performance Based Navigation (PBN) inaccordance with Modification Leaflet and Certificate of designMDL/175-003	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-27 Amendment 6 for27.1/ 27.21(a)/27.301(a),(b)/ 27.303/27.305/27.307(a)/ 27.321/27.337/27.561(a), (b)(3)/ 27.601(a)/27.603...	- Rotorcraft Flight Manual Supplement FMS/175-012 Issue 1- Instructions for Continued Airworthiness ICA/175-011 Issue 1- Modification Leaflet and Certificate of design MDL/ 175-003Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to helicopters with CPDS cockpit variantDual GarminGTN750 installation as per EASA STC 10059923 Rev. 1(BABCOCK/MOD/128) and TPED tolerance certification as per EASA STC10062544 Rev. 2 (BABCOCK/MOD/140) are prerequisitePrior to installation of this change/repair it must be determined thatthe...	23/12/2020	Active	10075306
10075315	BABCOCK MISSION CRITICAL SERVICESDESIGN AND COMPLETIONS LIMITED		CAA UK RESPONSIBILITY	EC135 T3 EC135 T2+ EC135 T2	Upgrade of Garmin GTN750 installation enabling Helicopter TerrainAwareness Warning System (HTAWS) functionality in accordance withModification Leaflet and Certificate of design MDL/188-014	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-27 Amendment 6 for27.1/27.21(a)/27.29(a), (b)/ 27.301(a),(b)/ 27.303/27.305/27.307(a)/ 27.321/27.337/27.561(a),(b)(3)/ 27.6...	- Rotorcraft Flight Manual Supplement FMS/188-012 Issue 3- Instructions for Continued Airworthiness ICA/188-010 Issue 2- Modification Leaflet and Certificate of design MDL/ 188-014Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to helicopters with CPDS cockpit variantDual GarminGTN750 installation as per EASA STC 10059923 Rev. 1(BABCOCK/MOD/128) is prerequisitePrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed cha...	23/12/2020	Active	10075315
10075326	AIRBUS S.A.S.			A350-941	A350 DAL C++ Cabin ReconfigurationThis modification covers the cabin reconfiguration of seatingconfiguration between door 2 and 3, including seat change and seatrelocation, to match with future DAL linefit configuration. S	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Plan Ref AIS-AJA-20003 - Issue 3MAS AI0164 Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/01/2021	Active	10075326
10075339	ACORN WELDING Ltd.		TCCA SA20-28	DHC-6 SERIES 400 DHC-6 SERIES 300, 310 AND 320 DHC-6 SERIES 200 AND 210 DHC-6 SERIES 100 AND 110	Installation of Acorn Welding C6SC1107-NG Exhaust Stacks inaccordancewith Transport Canada Civil Aviation (TCCA) STC SA20-28.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Acorn Welding Engineering Order EO-08.01, Rev 0, March 18, 2020;Acorn Welding Drawing C6SC339-08-01, Rev 0, March 3, 2020;Acorn Welding Instructions for Continued Airworthiness, ICA-08-01, Rev0, June 22, 2018or later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in acc...	Only applicable for DHC-6 Series with PT6A-27 and PT6A-34 enginesinstalled. This STC is not compatible with PT6A-20 engines.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair w...	19/01/2022	Active	10075339
10075340	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			737-800	C0248-B737-CABIN REFURBISHMENTReplacement of all Weber tourist class seats with TSI ELASA-S economyclass seats, rearrangement of PSU, LVP modification and renewal ofcurtains and carpets.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Programme document No C0248-CEP rev. 6 (whichincludesMaster Document List)<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC constitutes an Alternative Method of Compliance (AMOC) to theLife Vest Panel (LVP) modification requirement ofEASA adopted FAA AD2019-03-26. All provisions of FAA AD 2019-03-26 that are not referencedabove remain fully applicableand must be complied with accordingly.Prior to installationt...	07/01/2021	Active	10075340

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075345	BLACKHAWK MODIFICATIONS Inc.		FAA STC SA02726LA	B300C B300	Replacement of the original Pratt and Whitney PT6A-60A engines andpropellers with Pratt and Whitney PT6A-67A engines and MT PropellerMTV-27-1-N-C-F-R(P)/ CFR260-65b propellers, installation of CentexAerospace extended range fuel tanks and Raisbeck Engineering landinggear doors	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02726LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Installation Instructions 201806-001, Rev.IR, dated 9 January 2020,or later FAA approved revision.2. Airplane FlightManual Supplement AFMS 201806-07, Rev. IR, dated 5June 2020, or later FAA Approved revision.3. Instructions for Continued Airworthiness, Document Number ICA201806-30, Rev. IR, date...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/01/2021	Active	10075345
10075346	BELL TEXTRON, Inc.		FAA SR11247DS	429	Installation of Connected Aircraft Interface Residing On-board (CAIRO) System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11247DS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Drawing List, Report No. AA-19072, Revision D, dated23 September2020, or later FAA approved revision.Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-19079, NoRevision, dated 14 January 2020, or laterFAA accepted revision.	This STC is applicable to all serial numbers for the Bell Textron CanadaLimited 429.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	11/01/2021	Active	10075346
10075350	FLAIR AIRLINES, Ltd.		TCCA C-LSA11-115/D ISSUE 4	737-400	Installation of Skytrac ISAT-200 Satcom SystemInstallation of a low-profile dual GPS/Iridium antenna on the topfuselageRH of the centreline with an aluminium doubler reinforcement,an ISAT-200 transceiver installed in the avionics rack, and two controlpanels (CDP-300 and DVI-300).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Modification Data Summary, ACS-NAI Report No H176000 rev. EMandatory Maintenance Manual Supplement, ACS-NAI Report No H176070 rev.Bor later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with theTechnical ImplementationProcedures of EU/ Canada Bilateral A...	As per Mandatory Maintenance Manual Supplement, ACS-NAI Report NoH176070.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthine...	07/01/2021	Active	10075350
10075369	GLOBAL AEROSPACE DESIGNCORPORATION		FAA ST04299CH	737-800	Certification of Automatic dependent Surveillance - Broadcast (ADS-B)OUT System utilizing upgraded Aviation Communication & SurveillanceSystems (ACSS) XS-950 Mode-S Transponders paired with the aircraft'sexisting GPS Source or newly installed ADS-B dedicated GPS sourceRockwell Collins GLU-920 and Ro...	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements: The following paragraph(s) at a lateramendment:CS25 amdt 1: 25.1583(e)CS25 amdt 5: 25.1301, 25.1353(a)(b)CS25 amdt 6: 25.1309(a)(b)(c)(d)CS25 amdt 13: 25.1501(b)CS-ACNS In...	Global Aerospace Design Corp. Master Drawing List, No. GR0252-MDL Rev.C, dated 16 May 2018Airplane Flight Manual Supplement (AFMS) No.GR0264-AFM Rev. IR, dated 30May 2018 for GPS source Rockwell Collins GLU-920Airplane Flight Manual Supplement (AFMS) No.GR0264-AFM Rev. A, dated 04May 2018 for GPS so...	ACSS XS-950 Transponder installation must be previously approved.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repairwill introduce no adverseeffect upon the airworthiness of th...	25/02/2021	Active	10075369
10075387	DUNCAN AVIATION, INC.		FAA STC ST04271CH	BD-100-1A10	Installation of an AVANCE L5 System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04271CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Approved Flight Manual Supplement, Duncan Aviation, Inc.Doc. No.CERTDOC-004721, Revision A, approved 1 February 2018 or later FAAapproved revision.2. Instructions for Continued Airworthiness - Airworthiness Limitations,Section 15.0 of Duncan Aviation, Inc. Doc. No. CERTDOC-004720, RevisionD, app...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/01/2021	Active	10075387

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075392	FOKKER TECHNIEK B.V.			737-400	VHF Antenna Structural ProvisionsThis project certifies thestructural provisions for the installation ofa VHF antenna on top of the fuselage. Activation of the system is notcovered by this STC.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Instructions for Continued Airworthiness no. B737-HSHRH-ICA-S-0001 Issue1 dated December 21st 2020Compliance Record Report no. B737-HSHRH-CRR-0001 Issue 1 dated January11 2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/01/2021	Active	10075392
10075402	DART AEROSPACE Ltd.	REV. 2	TCCA SH20-13	MBB-BK117 C-2, MBB-BK117 D-2	Certification for ditching when equipped with Emergency Flotation Kitsper FAA STC SR02244LA(EASA STC 10028171).Revision1: Demonstration of compliance of the Emergency FloatationSystem P/N 651.3400 to EASA CS-26 requirements CS 26.410 Issue 4, CS26.420(a) Issue 4 and CS 26.425 Issue 4.Revision 2: D...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:Revision 1:CS 29.1555(d)(2) Amdt.5 , CS 29.1587(c) Amdt. 5Revision 2:CS 29.1 Amdt.2, CS 29.1529 Amdt.2, CS 2...	Master Document List MD145-4 Rev. A dated April 1st, 2020;Airworthiness Compliance Report ACR145-2 Rev. A dated March 26th, 2020;Flight Manual Supplement RFMS145-4 Rev. A dated March 25th, 2020Revision 1:Master Document List MD145-4 Revision B dated 22nd December 2023;Rotorcraft Flight Manual Supple...	The Dart Emergency Flotation system is approved as a ditching provisionaccording to FAR 29.801 Amdt.40. In order for the helicopter to be fullyapproved for ditching, additional equipment is required as follows:1) If the operator has Emergency Floats with integrated Liferaftsinstalled per FAA STC SR0...	23/07/2024	Active	10075402
10075425	AEROSPACE DESIGN & COMPLIANCE LLC		FAA STC ST04198NY	FAA APPROVED ML AML25-AML-0073	Installation of Becker Avionics DVCS6500 Digital Voice CommunicationSystem	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25, Amdt 25:CS 25.301(a)(b), CS 25.303, CS 25.305(a)(b), CS 25.307(a), CS 25.341, CS25.561(a)(b)(c), CS 25.601, CS 25.6...	Master Data List, AML25-MDL-0073, Rev. IRApproved Model List, AML25-AML-0073, Rev. IRAirplane Flight Manual Supplement,AML25-AFMS-0073, Rev. IRInstructions for Continued Airworthiness, AML25-ICA-0073, Rev. IROr later revisions of the above listed document(s) approved/accepted onbehalf of EASA in ac...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/01/2021	Active	10075425
10075430	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		400A 400	Installation of dual Garmin GTX 3000 with single Garmin GPS3000 andGarmin GA 36 GPS Antenna	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25.29; CS 25.581; CS 25.843; CS 25.899; CS 25.1301; CS 25.1302; CS25.1309; CS 25.1310; CS 25.1316; CS 25.1317; CS 25.13...	Installed in accordance with ASR-2020-016-IFI-10-00 dated 14/10/2020;maintained in accordance with ASR-2020-016-ICA-11-00 dated 07/01/2021and operated in accordance with ASR-2020-016-FMS-05.1-00 dated03/11/2020 (MODEL 400), ASR-2020-016-FMS-05.2-00 dated 03/11/2020 (MODEL400A) or later revisions of t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/01/2021	Active	10075430
10075433	ECMS AVIATION SYSTEMS GMBH			AS 350 D AS 350 BB AS 350 B, AS 350 B1 AS 350 BA, AS 350 BB AS 350 BA AS 350 B3 AS 350 B2, AS 350 B3 AS 350 B2 AS 350 B1 AS 350 B	STP01 - SKYTEK PodThe SKYTEK Pod is an external box which is located below the helicopterfuselage and which is attachedto the original cargo hook attachmentpoints. It is equippedwith specific sensing and measuring equipment.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: . For AS 350 B, AS 350 B2, AS 350 BA, AS 350 BB, AS 350 D:CS 27 initial issue: CS 27.1, CS 27.21, CS 27.25, CS 27...	- Flight Manual Supplement, Initial Issue R0 dated 11th December 2020- Airworthiness Limitations Section, Section 11 ofComponent MaintenanceManual, Maintenance Manual for STP01 on AS 350, Revision R0 dated 12thJanuary 2021- Master Document List, STP01_MDL_EASA, Revision R1 dated 13th January2021- C...	The installation of the STP01 is only approved in combination with thehigh skid landing gear.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	20/01/2021	Active	10075433

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075443	BABCOCK MISSION CRITICAL SERVICES FMANAGEMENT S.A.U.			412EP	Linkage of existing GTN 725Xi/750Xi installation to Flight Director andHorizontal Situation Indicator	The Certification Basis for the original product as amendedby thefollowing:- additional airworthiness requirements: FAR Part 29: 29.610, Amdt. 53;29.1529, Appendices A.1, A.2, A.3, A.4 (all Amdt. 20);- and, paragraphs at a later amendment: FAR Part 29: 29.1309, Amdt. 53;29.1329 Amdt. 42.The require...	- Flight Manual Supplement approved section 598B, Issue 3- Service Bulletin 598SB-2, Issue 1- Certification Plan 598CP,Issue 6- Airworthiness declaration and approval 598AW(D), Issue 2or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Limited to s/n 36183 and 36376- No IFR operation with GTNposition source input to Flight Director.- Autopilot coupling limited to lateral GPS coupling.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously ins...	22/01/2021	Active	10075443
10075450	AEROTEC & CONCEPT			737-800	B737 Refurbishment of Flight Attendant SeatsThis modification consists in the refurbishment of the three FlightAttendant seats (Flight Attendant Aft Facing DBL Seat), P/N 2110-324AE,P/N 2110-325AE and P/N 2110-326AE, including the replacement of seatcushions.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Drawings 8805670 Rev.A, 8805671 Rev.NC, 8805672 Rev.NC, 8805673 Rev.NC, 8805674 Rev.NC, 8805675 Rev.NC, 8805676 Rev.NC< (>,<)>Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/01/2021	Active	10075450
10075452	GULFSTREAM AEROSPACE CORPORATION		FAA ST04272AT-D	GULFSTREAM G280	Installation of an XM Satellite Weather Receiver and Antenna.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Gulfstream Aerospace Corporation Index List GA423258001, Revision J,dated 03 November 2012.- Airplane Flight Manual Supplement, GA41325M001, Revision "-", dated 24October 2012.- Instruction for Continued Airworthiness GA41325A002, Revision B, dated26 October 2012or later revisions of the above lis...	The EASA STC 10052498 (FAA STC ST04266AT-D - Installation of anExecutive Cabin Interior) is a required part of this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wille...	22/01/2021	Active	10075452
10075453	MT-PROPELLER ENTWICKLUNG GmbH			F 406	Installation of MTV-27-1-E-C-F-R(P)/ CFR220-55( ) on ASI Aviation (Reims) F406 aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 36 Amdt 5, FAR 36-31This certificate/approval involves a change with an impact on the noisedatabase and/or emission lev...	According to MT-Propeller Master Documentation List No. E-3586 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-3588Rev. 0To be installed i.a.w. Installation Instruction Doc. No. E-3589 Rev. 0To be maintained i.a.w. MT-Propeller ICA Document No. E-3590 Rev. 0or later revisio...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	16/02/2021	Active	10075453
10075462	WESTERN JET AVIATION, Inc.	REV. 1	FAA STC ST04478CH	GIV-X	Installation of a Collins KuSAT-2000 Tail Mounted SATCOM SystemRev. 1: Transfer of STC	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04478CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. StandardAero Master Data List 1038905, Revision (A)<(>,<)> dated 27October 2020 or later FAA approved revision.2. FAA Approved Airplane Flight Manual Supplement< (>,<)> documentnumber1038906< (>,<)> Rev (A) dated 17 September 2020<(>,<)>or later FAAapproved revision. 3. Instructions for Continued1...	This STC requires prior or concurrent embodiment of a TPED STC, ServiceBulletin or embodiment of EASA STC 10069211.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intro...	03/08/2022	Active	10075462

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075463	S-TEC CORPORATION		FAA STC SA09761DS	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09761DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List No. ST-979-MDL-0001, Revision A<(>,<)> dated 1October 2020<(>,<)> or later FAA approved revision.2.Airplane Flight Manual Supplement ST-979-AFMS-0001, Rev. -,dated 5October 2020, or later FAA approved revision.3. Instructions for Continued Airworthiness, ST-979-ICA-0001, Rev. -...	This STC is applicable to all serial numbers for Viking AirLimitedmodels DHC-6-100, DHC-6-200 and DHC-6-300.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce n...	27/01/2021	Active	10075463
10075464	S-TEC CORPORATION		FAA STC SA09541AC-D	SR22	Installation of S-TEC System 55X Automatic Flight Guidance System RollServo Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09541AC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Master Data List No. ST-924-L-0001, Revision H, dated 30March 2011or later FAA Approved revisions.2. FAA/DAS Approved Pilot's Operating Handbook and /or Airplane FlightManual Supplement No. ST-924-M-0001, Revision -, dated 23 October 2006or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/01/2021	Active	10075464
10075465	GDC ENGINEERING GmbH			ATR 72-212 A	ATR72 Cabin Modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Certification Document List CCN-AT72B-MCDL Issue 01,dated 22 Jan2021ICA & Operator Manual Supplement AT72B-ICA-A Rev 01, dated 4 Jan 2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/01/2021	Active	10075465
10075466	LEE AEROSPACE, INC.		FAA STC ST04202NY	HAWKER 900XP HAWKER 850XP HAWKER 800XP HAWKER 800 HAWKER 750 HAWKER 1000 BAE.125 SERIES 800B BAE.125 SERIES 800A BAE.125 SERIES 1000B BAE.125 SERIES 1000A	Installation of LAI Window Panel B	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04202NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List, LAI-MDL-118, Revision IR, dated 18 December 2020,or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA) LAI-ICA-118, RevisionIR, dated 10 December 2020, or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/01/2021	Active	10075466
10075477	DUNCAN AVIATION, INC.		FAA STC ST01739WI	BD-700-1A10	Installation of a cabin interior alteration and cabin entertainmentsystem upgrade.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01739WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Duncan Aviation Inc., Master Document List No. CERTDOC-0000001356,Revision A, dated 21 March 2014 or later FAA Approved Revisions.2. Airplane Flight Manual Supplement, Duncan Aviation Inc., Document No.EDOC-0000016709, Revision A, dated21 March 2014, or later FAA ApprovedRevisions.	You cannot use descriptive data about this design change toduplicateother products. This approval is limited to only the installation madein Bombardier, Inc., BD-700-1A10, SerialNo. 9092. This STC does notpermit manufacturing of parts for multiple installations.Prior to installation of this change...	26/01/2021	Active	10075477
10075498	FORCED AEROMOTIVE TECHNOLOGIES	REV. 1	FAA STC SR00958DE	206L-4 206L-3 206L-1 206L 206B	Installation of Airborne LIDAR Pipeline Inspection Service (ALPIS).Rev. 1: Correction of address	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: Paragraph 27.51(a) Amdt.44; 27.65(b)2 Amdt.33, 27.75(a) Amdt.44, 27.141 (a)(b)2 Amdt.21,27.143 (a)(b)(c) Amdt.21, 27.171 A...	Master Drawing List (MDL) MDL-206-1-A dated 02 October 2018;Instruction for Continued Airworthiness (ICA) ALPIS-STC-ICA-001 Rev. IRv2 dated 12 June 2018;EASA Rotorcraft Flight Manual Supplement ALPIS-STC-RFMS-001 Rev.0 dated25 January 2021;or later revisions of the above listed document (s) approved/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/02/2021	Active	10075498

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075499	DUNCAN AVIATION, INC.		FAA STC ST01854WI	GIV-X GIV	Installation of Gogo Biz AVANCE L5 Broadband System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01854WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Duncan Aviation Master Document List, Doc. No. CERTDOC-004745<(>,<) >Rev. A, dated 6 October 2017, or later FAA approved revision.2. Duncan Aviation Airplane Flight Manual Supplement, Doc. No.CERTDOC-004743, Rev. A, dated 6 October 2017,or later FAA approvedrevision.3. Instructions for ContinuedN...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/01/2021	Active	10075499
10075510	S4A SOLUTIONS FOR AVIATION, S.L			737-300, 737-400, 737-500	CMA-525 SLS Control Panels Replacement	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:EASA CS-25 Amdt. 24, Paragraphs; 25.1, 25.21, 25.25, 25.301, 25.303,25.305, 25.307, 25.321, 25.337, 25.341, 25.471, 25.561,...	737424-RPT02 Master document list Edition 5,737424-HDK01 Flight Manual Supplement Edition 3,737424-HDK02 Maintenance manual supplement Edition 5,737424-12-33 MMEL Supplement Edition 5Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The new approved design changes are only applicable to airplanespreviously modified according EASA STC 10043626, dated in 13/02/2013.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or...	22/06/2021	Active	10075510
10075511	S4A SOLUTIONS FOR AVIATION, S.L			412, 412EP, 212	External Cargo Basket Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS29.1(a),CS29.21 (a), CS29.25(a)(b), CS29.27(a)(b)(c), CS29.45(a)(b)(c)(d),CS29.51 (a)(b), CS29.65(a), CS29.71, CS29.75(a...	MASTER DOCUMENT LIST : 41244-RPT02 Issue 6 dated 27 January2021FLIGHT MANUAL SUPPLEMENT : 41244-HDK01 Issue 5 dated 27January 2021MAINTENANCE MANUAL SUPPLEMENT : 41244-HDK02 Issue 4 dated 06 January2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/01/2021	Active	10075511
10075520	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		ATR 72-212A ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102 ATR 42-500 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	ADS-B UpgradeThe change consists of a replacement of the existing Rockwell CollinsTDR-94D transponder system with Garmin GTX 3000 transponders to includeADS-B out functionality according to Minimum Operational PerformanceStandards (ADS-B Version 2 as per DO-260B including Corrigendum 1 MOPS).This ch...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): CS-ACNS 1 (Deviation to CS ACNS requirements for ELSand ADS-B continuity) & CS-ACNS 2 (Deviation to CS ACNS requirements forProvision of Pressure Altitude...	Aircraft Flight Manual Supplement – Doc Ref: 2123010-AM Issue 3Instructions for Continued Airworthiness – Doc Ref: 2123010-CA Issue 2or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2021	Active	10075520
10075530	SABENA TECHNICS BGC			A321-231	A321-200 - CABIN RECONFIGURATION FROM 16B/C + 153Y/C TO 214Y/C	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4:25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341,25.365, 25.561, 25.601, 25.603,...	- Master Data List, Aeroconseil document No. 40557-01-A-MDL-R00, firstissue dated 29 January 2021;- Instructions for continued airworthiness, Aeroconseil document No. 40557-01-A-ICA-R00 dated 28 January 2021;or later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/01/2021	Active	10075530

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075538	URBE AERO GmbH			HK 36 TTC	MTOM Increase from 770kg to 800kg	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed in accordance with Engineering Order ref: DOE/F07rev 1 dated28/01/2021Operated in accordance with Flight Manual Supplement ref: AFM-245-01 rev0 dated 21/01/2021or laterrevisions of the above listed document(s) approved/ acceptedunder the EASA system.	Tail skit (Metal Tube Type 2, P/N 820-3721-00-025) must be installed;limited to S/N 36.541, 36.610 and 36.804Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce n...	29/01/2021	Active	10075538
10075546	ALAMO ENGINEERING GmbH			EMB-135BJ	INSTALLATION AND ACTIVATION OF IRIDIUM SATELLITE SYSTEM FORFANS 1/A	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 Amdt 25. CS25.29, CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS 25.561, CS 25.601,CS 25.603, CS 25.605, CS 25.607,2...	Flight Manual Supplement – Doc Ref: FMS20A11AE-01 Revision BInstructions for Continued Airworthiness – Doc Ref: ICA20A11AE-01Revision Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/02/2021	Active	10075546
10075547	JET AVIATION AG	REV. 3		A320-214	VVIP CABIN INTERIOR COMPLETIONThis modification installs a VVIP Cabin Interior into an AirbusA320-214. The aircraft will be outfitted to accommodate 4 Cabin Crew and35 Passengers.Rev. 1: Compliance to Operational Suitability Data - Cabin Crew (OSD-CC)addedRev. 2: List of Prerequisite STC's updatedRe...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s):- SC H-01 Enhanced Airworthiness Programme for Aeroplane Systems - ICAon EWIS- CRI F-4306Security Protection of Aircraft Systems and NetworksThe foll...	- MASTER DATA LIST: Doc No. JBSC-M-03507MDL-001, Issue N-AIRPLANE FLIGHT MANUAL SUPPLEMENT: Doc. No. JBSC-M-03507AFM-001, IssueC-INSTRUCTIONS FOR CONTINUED AIRWORTHNESS: Doc. No. JBSC-M-03507ICA-001,Issue D-OSD CABIN CREW DATA: Doc. No.JBSC-M-03507CCD-001, Issue COr later revisions of the aboveu...	Limitation:Private Operation (Not-for-Hire, Non-Commercial), Non Smoking AircraftPre-Requisites:The following EASA STC's are a pre-requisite for this installation:-WLAN ActivationEASA STC 10071326-Self-illuminated exit signs on bulkhead STC EASA 10065753 (applicablefor configuration 1 only)Prior to...	28/11/2022	Active	10075547
10075551	SAFRAN CABIN GERMANY GmbH	REV. 1		747-300/-400/-400F 747-200B/-200C/-200F	Installation of Trash Compactors.Revision 1: Transfer of STC holder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List TR40066, Revision N, dated 02 October 2020<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075551
10075552	SAFRAN CABIN GERMANY GmbH	REV. 1		747-300/-400/-400F 747-200B/-200C/-200F	Installation of Trash Compactors within C. F. Taylor Galleypart NumbersM3296A1, M3276A1, M4424A1 and M4556A1Revision 1: Transfer of STC holder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List TR40011, Revision. R dated 02 October 2020<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075552
10075558	GULFSTREAM AEROSPACE CORPORATION		FAA ST04334AT-D	GVI (G650)	Installation of a Viasat Ka-Broadband High Speed Data (HSD)System onGulfstream Model GVI aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplemental Type Certificate (STC), ST04334AT-D, Installation of aViasat Ka-Broadband High Speed Data (HSD) System, date amended July 16,2020Index List ref. GDL100000032 Revision (-), dated July 16, 2020Airplane Flight Manual Supplement, CE61 303M001, Revision (-), datedJuly 16, 2020Airplane Flight...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/02/2021	Active	10075558

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075574	AIRBUS HELICOPTERS, Inc.		FAA SR09512DS	AS 350 B2, AS 350 B3	Installation of extended pilot and copilot seat rails.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR09512DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the pr...	Airbus Helicopters, Inc. Master Drawing List (MDL) 350A82-1798 Rev. 14July 2020Rotorcraft Flight Manual supplement 350FMS-574 Rev. IR dated 24 July2020Instructions for Continued Airworthiness (ICA) 350MMS-043 Rev. A dated24 June 2020;or later revisions of the above listed document(s) approved/ accept...	This STC is applicable to all serial numbers.When passengers are seated in either the left or right aft seats, theassociated Pax Seat Rail Stop must be installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevio...	15/02/2021	Active	10075574
10075581	DUNCAN AVIATION, INC.		FAA STC ST01863WI	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT)	Installation of GoGo Business Aviation AVANCE L5 Broadband System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01863WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Document List, Duncan Aviation, Inc. Doc. No. CERTDOC-004902,Rev A, dated 21 December 2017, or later FAA Approved revisions.2. Airplane Flight Manual Supplement, Duncan Aviation, Inc. Doc. No.CERTDOC-004900, Rev A, dated 21 December 2017, or later FAA Approvedrevisions.3. Instructions forN...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/02/2021	Active	10075581
10075584	DUNCAN AVIATION, INC.		FAA STC ST01955WI	BD-100-1A10	Installation of Aviation Clean Air Bi-Polar Ionization System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01955WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Duncan Aviation, Inc., STC Master Document List Doc. No.CERTDOC-011389, Rev. A, dated 30 October 2020, or later FAA approvedRevisions.2. Duncan Aviation, Inc. Instructions for Continued Airworthiness, Doc.No.CERTDOC-011437 , Rev A, dated30 October 2020, or later FAA acceptedrevisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/02/2021	Active	10075584
10075588	365 AEROSPACE DDS LIMITED			ATR 72-212 A ATR 72-212 ATR 72-211, ATR 72-212 ATR 72-211 ATR 72-202 ATR 72-201, ATR 72-202 ATR 72-201 ATR 72-102 ATR 72-101, ATR 72-102 ATR 72-101 ATR 42-500 ATR 42-400 ATR 42-320, ATR 42-400 ATR 42-320 ATR 42-300 ATR 42-200, ATR 42-300 ATR 42-200	Change to introduce an Automatic Dependent Surveillance – Broadcast (ADS-B) Out System and Single UNS-1Lw Flight Management System includingLocalizer Performance with Vertical Guidance (LPV) Monitor	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-ACNS Issue 2.CS.ACNS.C.PBN. 101,.201,.205,.210,.215,.220,.225, .230,.235,.240,.245,.250,.255,.260 ,.265,.270,.275,.280,....	Master Data List, MDL-1002 Revision A.Flight Manual Supplement No 1, FMS-1002-001 Revision B.Flight Manual Supplement No 2, FMS-1002-002 Revision H.Instructions for Continued Airworthiness, ICA-1002-001 Revision DSection 4.2.Instructions for Continued Airworthiness, ICA-1002-002 Revision CSection 4....	For Airworthiness Limitations refer to Instructions for ContinuedAirworthiness document ICA-1002-001 and document ICA-1002-002.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	05/02/2021	Active	10075588
10075589	SABENA TECHNICS BGC			A330-203	A330-200 - CABIN & IFE Modification from 326YC to 24BC & 265YC	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4paragraphs: 1, 29, 301, 303, 305, 307, 321, 337, 341, 365, 561, 562,601, 603, 605, 607, 609, 611, 61...	Master Data List, Ref. 40664-01-A-MDL-R00 dated 01 Feb 2021<(>,<) >Airplane Flight Manual Supplement, Ref. 40664-01-A-AFMS-R00 dated 11 Jan2021<(>,<) >Instructions for continued airworthiness, Ref. 40664-01-A-ICA-R00 dated29 Jan 2021.or later revisions of the above listed document(s) approved/ accepte...	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik EASASTC No. 10014507 Rev.02.Prior to installation of this change/repair it must be determin...	05/02/2021	Active	10075589

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075592	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03606NY	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Installation of Mid-Continent Instruments and Avionics MD302 StandbyAttitude Module	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03606NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Dassault Aircraft Services1.Master Data List, F9XW-D0095-005, Revision IR, dated 11 September 2020or later FAA approvedrevision.2. Instructions for Continued Airworthiness (ICA) F9XW-D0095-155,Revision IR, dated 3 September 2020, or laterFAA accepted revision.3. Airplane Flight Manual Supplement F...	This STC is applicable to Mystere-Falcon 900 (basic model definition)serial numbers 001 through 168 and serial numbers 170 through 178,Mystere-Falcon 900 (Falcon 900C definition) serial number 169 and serialnumbers 179 through 202, and Falcon 900EX (non EASy definition) serialnumbers 001 through 096...	08/02/2021	Active	10075592
10075604	MISSION SYSTEMS DAVENPORT INC.	REV. 2		A321-272NX A321-272N A321-271NX/-272NX A321-271NX A321-271N A321-253NX A321-253N/-272N/-252N A321-253N A321-252NX A321-252N A321-251NX/-252NX/-253 NX A321-251NX A321-251N A321-232 A321-231 A321-213/-231/-232/-251N /-271N A321-213 A321-212 A321-211 A321-131 A321-112 A321-111/-112/-131/-211/-212 A321-111 A320-273N A320-272N A320-271N A320-253N A320-252N/-272N/-253N/-273N A320-252N A320-251N A320-233 A320-232 A320-231/-232/-233/-251N /-271N A320-231 A320-216 A320-215 A320-214 A320-212 A320-211/-212/-214/-215/-216 A320-211 A319-153N A319-151N/-153N/-171N A319-151N A319-133 A319-132 A319-131/-132/-133 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111/-112/-113/-114/-115 A319-111 A318-111/-112/-121/-122	Cobham A320 series Air Separation ModuleEASA STC validationof the FAA PMA - Cobham A320 Air Separation Module(ASM) Part Number 3261217-0101Rev. 1: Name change from Cobham MissionSystems Davenport LSS Inc. toMission Systems Davenport Inc.Rev. 2: as per PMA approval PQ04284CE Supplement No.02 rev 1,...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.301 – amdt 16, CS 25.303 – amdt 16, CS 25.305 – amdt 18, CS 25.307– amdt 18, CS 25.561 – amdt 16,CS 25.601 – amdt 1...	- Pub. No. 25180A, European Aviation Safety Agency (EASA), SupplementalType Certificate (STC), Master Document List (MDL) for PN 3261217-0101for Airbus A318-100, A319-100, A320-200, A321-100/200- Pub. No. 25152, Instructions for continued airworthiness (ICA) for theAir Separation Module (ASM) P/N 32...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/10/2023	Active	10075604

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075606	GARMIN INTERNATIONAL, Inc.		FAA STC SA01947WI	PA-46-500TP	Hardware and software updates for the G1000 Integrated Avionics System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01947WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Garmin Master Drawing List (MDL) 005-01423-00, Revision 1, dated 12August 2020.2. Airplane Flight Manual Supplement (AFMS) 190-01423-03, Revision 1,dated 12 August 2020.3. System Maintenance Manual (includes ICA) 190-01423-02, Revision 1,dated 12 August 2020.Later FAA-approved revisions to the dat...	Limited to serial numbers 4697002, 4697340, 4697399 to 4697581, except4697549 and 4697569.Prior to installation of thischange/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upo...	12/02/2021	Active	10075606
10075624	SABENA TECHNICS BGC	REV. 4		A330-941 A330-323/-341/-342/-343/-841 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	A330 – Cabin Reconfiguration for the transportation of cargo inpassenger compartmentsRev. 1 corrects the applicability.Rev. 2 allows capability to install PEC seats Zodiac series 5810 in thecabin occupants area.Rev. 3 updates the TechnicalDocumentation and extends the timelimitation.Rev. 4: New cus...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4 paragraphs: 1, 561, 562, 601, 603, 607,613, 785,787, 789, 803, 811, 812, 813, 815, 851, 853, 869, 1...	- Master Data List, Ref. 40696-01-A-MDL-R20 dated 03 Mar 2022- Airplane Flight Manual Supplement, Ref. 40696-01-A-AFMS Rev 02- Instructions for continued airworthiness, Ref. 40696-01-A-ICA Rev 04- OSD Change Document, Ref. 40696-01-A-OSDCDRev 02or later revisions of the above listed document(s) app...	Limitations as per §3 of Instructions for Continued Airworthinessdocument and §3 of Airplane Flight ManualSupplement document referenced above.The allowance to transport cargo in the passenger cabin compartment islimited to 2 000 FH followinginstallation of the change or to 31 July 2022, whatever oc...	07/03/2022	Active	10075624
10075630	GULFSTREAM AEROSPACE CORPORATION		FAA ST04321AT-D	GULFSTREAM G280	Installation of Viasat GAT-5510 Ka-Band High Speed Data (HSD) System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Gulfstream Aerospace Corporation Index List GA41308002, Revision "-"dated 28 March 2019Flight Manual Supplement GA41303M001, Revision "-" dated 28 March 2019Instruction of Continued Airworthiness GA41303A003, Revision "-" dated15 November 2018or later revisions of the above listed document(s) approv...	The EASA STC 100052498 (FAA ST04266AT-D, Installation of anExecutivePassenger Cabin Interior), is required as part of this STCPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	12/02/2021	Active	10075630
10075631	SAFRAN CABIN GERMANY GmbH	REV. 2		777-200	Installation of Monogram Systems Chiller P/N 7000-2Revision1: Transfer of STC holder from Safran Cabin Galleys US Inc.toSafran Cabin Germany GmbHRevision 2: Correction of MasterData List	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Monogram Systems Master Data List MDL7000-2, Revision G, dated 10 August2020<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/06/2021	Active	10075631
10075632	SAFRAN CABIN GERMANY GmbH	REV. 1		747-400	Installation of Trash CompactorRevision 1: Transfer of STC holder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Monogram Systems Top Drawing List Report Number TR40369, Revision G,dated 10 August 2020<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075632
10075633	SAFRAN CABIN GERMANY GmbH	REV. 1		A330-343	Installation of Trash Compactor AssemblyRevision 1: Transfer of STC holder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Monogram Systems Top Drawing List Report Number TR40572, Revision G,dated 10 August 2020<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075633

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075634	SAFRAN CABIN GERMANY GmbH	REV. 1		SEE FAA ST01331LA AML	Installation of Trash CompactorRevision 1: Transfer of STC holder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Top drawing List TR40580, Revision J, dated 10 August 2020<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075634
10075635	SAFRAN CABIN GERMANY GmbH	REV. 1		747-400, 777-200	Installation of Trash Compactor AssemblyRevision 1: Transfer of STC holder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Top Drawing List TDL40389, Revision H, dated 10 August 2020< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075635
10075636	SAFRAN CABIN GERMANY GmbH	REV. 1		747-200C, 747-200F 747-100, 747-200B	Installation of Aero-Design Technology trash Compactors in C. F. TaylorGalleys M4948-A1 and M4893-A1Revision 1: Transfer of STC holder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Aero-Design Technology Master Drawing List TR40021, Revision J, dated 10August 2020<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075636
10075637	SAFRAN CABIN GERMANY GmbH	REV. 1		767-300	Installation of Trash CompactorsRevision 1: Transfer of STCholder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Aero-Design Technology Incorporated Top Drawing List TR40068, RevisionJ, dated 10 August 2020< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075637
10075638	SAFRAN CABIN GERMANY GmbH	REV. 1		757-200	Installation of Trash CompactorsRevision 1: Transfer of STCholder from Safran Cabin Galleys US Inc. toSafran Cabin Germany GmbH	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Aero-Design Technology, Incorporated Top Drawing List TDL40106, RevisionF, dated 10 August 2020< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/05/2021	Active	10075638
10075641	HELI AUSTRIA GmbH	REV. 1		AB412 412	HAU-D-022 Installation of GARMIN GTN750 COM/NAV/GPS System and MasterCaution Panel RelocationReason for Rev. 1: addition of AB412 model, option to replace the No.2GTN750 by a GNC255 COM/NAV unit, the installation of an additionalSSD120 altitude encoder model. Further a new P/N of the GTN750 isintrod...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 Non rechargeable Lithium batteriesThe following paragraph(s) at a later amendment:the following paragraphs of CS-ACNS, Issue 3:CS ACNS.A.GE...	Master Document List, Doc. No. HAU-D-022-001, Rev. 1Installtion Instructions:Installation Manual - Dual GTN Configuration, Doc. No. HAU-D-022-004-01,Rev. 1Installation Manual - GTN +GNC Configuration, Doc. No. HAU-D-022-004-02,Rev. 0Flight Manual Supplements:Flight Manual Supplement - Dual GTN Config...	For the Bell Model 412 is the change limited to serial numbers33001–36086<(>,<) >The Helicopters have to be equipped with Dart D212-722 Avionic Console,STC EASA.IM.R.S.01181, or similar modification to allow the installationof the avionic units.Limited to VFR DAY and NIGHTPrior to installation of thi...	25/04/2022	Active	10075641

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075646	BELL TEXTRON, Inc.		FAA STC SR11249DS	505	Installation of Flitestep	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11249DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List, Report No. AA-20035, Revision IR, dated 11August 2020;2. Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-20034, Revision IR, dated 3 June 2020;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance w...	This STC is applicable to all serial numbers for the Bell Textron CanadaLimited 505.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	16/02/2021	Active	10075646
10075649	AEROTEC & CONCEPT			EMB-135LR	EMB-135 Cabin ReconfigurationThis modification consists in switching the cabin dual class versionVIP-passengers of Embraer EMB-135LR into passengers-stretchersconfiguration. Two medical stretchers with P/N: KIT-AE-18113-117,manufactured byUUDS, are installed in the FWD RH cabin section.Stretchers c...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	- AE20111AFMS AFMS “EMBRAER 135 SERIES MOD AEROTEC CONCEPT Nº 20111” Rev0.- AE20111MDL EMB-135 CABIN RECONFIGURATION MASTER DATA LIST Rev 0Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to model previously modified with EASA STC 10041778.	19/02/2021	Active	10075649
10075659	BELL TEXTRON, Inc.		FAA SR11248DS	407	Installation of Connected Aircraft Interface Residing On-board (CAIRO) System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11248DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Drawing List, Report No. AA-20023, Revision B, dated03 September2020Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-20022, No Revision<(>,<)>dated 24 February 2020or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordan...	Applicable to serial numbers 53000 to 54299 with STC EASA 10073820 (FAASR11245DS - 407 G1000NXi Glass Cockpit Upgrade) and to serial numbers54805 and subsequent.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviou...	17/02/2021	Active	10075659
10075660	S-TEC CORPORATION	REV. 1	FAA SA09762DS	PA-24, PA-24-250 PA-24-260, PA-24-400	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)Rev. 1 corrects the AFM reference.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA9762DS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Data List ST-978-MDL-0001, Revision A, dated 07 December 2020Airplane Flight Manual Supplement ST-978-AFMS-0001,Rev. -, dated 09December 2020Instructions for Continued Airworthiness ST-978-ICA-0001, Rev. -, dated07 December 2020or later revisions of the above listed document(s) approved/acce...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2021	Active	10075660
10075661	B.A.S., INC.		FAA SA00855SE	T210M, T210N, T210R P210N, P210R, T210K, T210L 210K, 210L, 210M, 210R	Installation of BAS, Inc. duel belt shoulder harness with inertia reel	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	BAS Report 1002, dated 01 April 2000<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/02/2021	Active	10075661

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075664	FTI ENGINEERING NETWORK GmbH			CL-600-2B19 (RJ SERIES 100)	Introduction of ADSB-out capability	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 initial Issue:1, 21, 29, 251, 301, 303, 305, 307, 321,333, 337, 341, 365, 471, 561,571, 581, 601, 603, 605, 607, 6...	- System Description F30-EO19-0060, Issue 02- Instructionsfor Continued Airworthiness F33-EO19-0060, Issue 02- Maintenance Manual Supplement F21-001-EO19-0060, Issue 02- Airplane Flight Manual Supplement F20-EO19-0060, Issue 02- MMEL Supplement F25-EO19-0060, Issue 02- Installation Instructions F2...	This STC is only for aircraft which have Collins Proline 4 avionicsalready installed ex-factory.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffe...	18/02/2021	Active	10075664
10075667	LUFTHANSA TECHNIK AG	REV. 1		A350-941 A350-1041	Installation of non-electrical Floor Path Marking SystemRev. 1: typos corrected	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplemental Type Definition Document STDD33-19/06M Issue 1rev 1Airplane Flight Manual Supplement A-00-19/69-AFM Issue2 rev 0Instructions for Continued Airworthiness A-00-19/69-ICA Issue 1 rev 0Master Minimum Equipment List Supplement A-00-19/69-MMEL rev 2or later revisions of the above listed doc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/03/2021	Active	10075667
10075706	URBE AERO GmbH	REV. 2		HK 36 TTC HK 36 TC	MTOM increaseThis STC allows the increase of the Maximum Take-Off Mass of theapplicable aircraft up to 800kg.Revision 1adds Model HK 36 TC to the certificateRevision 2 corrects typos (HK 36 TC vs. H 36 TC, and “TTC vs” TCC”) andan issue with the issue date of the HK 36 TTC AFMS	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.This certificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: CS-36 Amdt 3	For Model HK 36 TTCThe change is defined with Revision 1 ofUrbe Aero GmbH EngineeringOrder DOE/F07 Change 240 dated 18.02.2021.The aircraft shall be operated in accordance with initial issue of UrbeAero GmbH Airplane Flight Manual Supplement document AFM-240-01 dated09.12.2020For Model HK 36 TCTheO...	1. Metal Tube Type 2 with Part Number 820-3721-00-02 must be installedprior to increase of the MTOM. Check of the aircraft by Urbe Aero inaccordance with Doc No. DOE/F07 Change 240 for suitability is aprerequisite for the MTOM increase.Prior to installation of this change/repair it must be determine...	16/12/2022	Active	10075706
10075709	BROMMA AIR MAINTENANCE AB			FALCON 7X	Stretcher installation on Falcon 7X	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:CS 25.25; 25.301-303;25.305-307; 25.337; 25.341; 25.561; 25.571; 25.601; 25.603; 25.605;25.609; 25.611; 25.613; 25.619;2...	- MDL-20-04 Rev. D- FMS-20-04 Rev. D- ICA-20-04 Rev. Cor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Patient transport is limited to only using Lifeport Aerosled TS<(>,<)>P/N: AS1-001-01 together with FB2-007 mattress and utility arch P/N: 100-4049.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installede...	23/02/2021	Active	10075709
10075710	BOEING IRELAND LIMITED	REV. 3		737-800	Removal of the Row 44 Wi-Fi antenna installation, associated fuselagereinforcement members installed by the Row 44 modification (EASA STC10033185, FAA STC ST02829CH) and installation of local crown skinreplacement between STA727D+13.4 and STA727J+10Rev. 1 corrects model applicability.Rev. 2 introduc...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List provided in Change/Repair Approval Document, Doc:BIL-00177-APP Rev. 07Instructions for Continued Airworthiness, Doc: BIL-00177-ICA01 Rev. 01Instructions for Continued Airworthiness, Doc: BIL-00177-ICA02 Rev. 01Instructionsfor Continued Airworthiness, Doc: BIL-00177-ICA03 Rev. 01Ins...	A pre-requisite to this change is that the Row 44 broadbandsystem (EASASTC 10033186(FAA STC ST02836CH-D) is deactivated and removed.Aeroplanes modified by this STC must be maintained in accordance with:Instructions for Continued Airworthiness, Doc: BIL-00177-ICA01 Rev. 01and Airworthiness Limitatio...	10/05/2024	Active	10075710

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075718	S-TEC CORPORATION	REV. 1	FAA SA09763DS	690B, 690C, 690D, 695, 695A 680W, 681, 685, 690, 690A 560F, 680E, 680F, 680T, 680V 560A, 560E 500, 500A, 500B, 500S, 500U	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)Rev. 1 corrects the applicability.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09763DS dated 22 December 2020.The requirements for environmental protection and the associatedcertified noise and/ or emi...	- Master Data List ST-983-MDL-0001, Revision A, dated 21 December 2020-Airplane Flight Manual Supplement ST-983-AFMS-0001, Rev. -, dated 22December 2020-Instruction for Continued Airworthiness ST-983-ICA-0001, Rev. -, dated17 December 2020or later revisions of the above listed document(s) approved...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/02/2021	Active	10075718
10075723	COLUMBIA AVIONICS INC.d/ b/a COLUMBIA AVIONICS & AIRCRAFTSERVICES, INC.		FAA STC SA01958WI	SEE FAA APPROVED MODEL LIST	Installation of Garmin Avionics Modernization Package	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01958WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Refer to FAA Approved Model List (AML) SA01958WI	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List SA01958WI dated 23 December 2020.Installation and use of FS510 is not approved on EASA registeredaircraft.Prior to installation of this change/ repair it must be determined thatthe interrelations...	25/02/2021	Active	10075723
10075724	WESTERN JET AVIATION, Inc.	REV. 1	FAA ST04480CH	GV, GV-SP	Installation of a Collins KuSAT-2000 Tail-Mounted SATCOM systemRev. 1: Transfer of STC	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04480CH dated 15 January 2021.The requirements for environmental protection and the associatedcertified noise and/ or emis...	Western Master Data List 1469900 Revision (B), dated 13 January 2021Airplane Flight Manual Supplement document number 1469900-400 Rev (B)dated 11 January 2021or later revisions ofthe above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedure...	This STC requires prior or concurrent embodiment of EASA STC 10065748(FAA STC ST04236CH) for the radome installation.This STC requires prior or concurrent embodiment of a TPED STCorService Bulletin.Prior to installation of this change/repair it must be determined thatthe interrelationship between t...	03/08/2022	Active	10075724
10075726	NORTHERN AVIONICS S.R.L.			525, 525A	WAAS GPS ANTENNA INSTALLATON	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed and maintained in accordance with Master DocumentList refMDL0634 R0 dated 24/01/2021.	This design change only covers the mechanical provisions ofthe antennainstallation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	25/02/2021	Active	10075726
10075728	3S CERTIFICATION, LLC		FAA STC SA01855WI	SEE FAA APPROVED MODEL LIST	Installation of the Send Solutions Airtext Router	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01855WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. 3S Certification, Master Data List (MDL) 3S17-003-1001, Revision 3.0,dated 13 January 2020 or later FAA approved revisions.2. 3S Certification, Airplane Flight Manual Supplement (AFMS)3S17-003-7101, Revision IR, dated 13 October 2017 orlater FAA approvedrevisions.3. 3S Certification, Instruction...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List SA01855WI dated 13 January 2020.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change an...	25/02/2021	Active	10075728
10075729	SAFRAN CABIN GALLEYS US, INC.		FAA STC ST01919LA	A320-233 A320-232 A320-231 A320-214 A320-212 A320-211	Installation of an Aft Stowage Unit P/N 501231-1	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Driessen Aircraft Interior Systems Master Data List MDL-501231, RevisionNC, dated 5 May 2006, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2021	Active	10075729

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075739	GULFSTREAM AEROSPACE CORPORATION		FAA ST02697AT-D	GV-SP	Installation of Interior Emergency Lights	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Gulfstream Aerospace Corporation Index List GC514868002, Revision "B",dated 06 August 2003Instructions for Continued Airworthiness, GC51486A002, Revision "B",dated 13 February 2008or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/02/2021	Active	10075739
10075740	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE		FAA ST04465CH	A320-231/-232/-233 A320-211/-212/-214/-216	Removal of a 2Ku In-flight Entertainment and Connectivity (IFEC) System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments:CS25 amdt 0: 25.29(a)(b), 25.303, 25.305(a)(b) , 25.307, 25.365(a)(b)(d), 25.561, 25.571(a)(b) , 25.601, 25.603(a)(b) , 25.605(a) , 25.609(a)(b), 25...	Astronics Connectivity Systems & Certification (CSC) MasterData List,Doc. No. DC104-9932-00 Revision A, dated 18 February 2021Instructions for Continued Airworthiness - Airworthiness Limitations,Section 2 of Astronics CSC Doc. No. DC113-9932-00, Revision -, dated 19February 2021or later revisions o...	Airplane Flight Manual Supplements, Doc. No. 0664-09891-2407 and Doc.No. 0664-09906-2406 are not applicable to the aircraft modified by thisSTC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed cha...	04/03/2021	Active	10075740
10075742	S4A SOLUTIONS FOR AVIATION, S.L			421B	DUAL GPS AND RADAR ALTIMETER INSTALLATION	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	42104-RPT40 Master Document List Edic142104-HDK01 Flight Manual Supplement Edic.142104-HDK02 Maintenance Manual Supplement Edic. 1Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Cessna 421B Airplane with MSN: 421B0485Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	01/03/2021	Active	10075742
10075748	AMAC AEROSPACE SWITZERLAND AG			GIV	Cabin ModificationThe change consists of cabin modifications such asreplacement/ removal/installation of galley equipment and monumentsitems, including also the replacement of a 3-places divan by two (2)single seats.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AFMS-JA02-2500 Rev B-Airplane Flight Manual Supplement, dated 26thFebruary 2021ICA-JA02-2500- Rev A - Instructions forContinued Airworthiness, dated15th February 2021or later revisions of the above listed documents approved by EASA.CP-JA02-2500-rev DJA02L250008-B-LOPA OLD-NEW - MODIFICATION-INTERF...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	16/03/2021	Active	10075748
10075749	AIRBUS S.A.S.			A321-253NX A321-252NX A321-251NX	Airbus Interiors Services MOD AI0112 Cabin Conversion for TITAN/ FOURSEASONS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph at JAR25 ch11:25.785, 25.787, 25.789, 25.791, 25.815, 25.817, 25.1351, 25.1357,25.1359, 25.1415, 25.1441, 25.1443, 25.1447, 25.1450- The followin...	- Modification Approval Sheets ref MAS AI0112 issue 01 _ MAR 01/21- Certification Summary Report ref: AIS-AJA-19003 issue 07 _ MAR 01/21- Flight Manual Supplement ref FM-S MOD AI0112 issue _ FEB 01/21- Flight Crew Operating Manual ref FCOM-S MOD AI0112 issue 01 _ DEC 20- Cabin Crew Operating Manual_...	This STC presents the specificity to enable several cabinconfigurations. Any subsequent modification to the aeroplane is allowed, provided that the interrelation between this subsequent design change and each cabin configuration permitted by thepresent STC is evaluated and found to meet the requirem...	02/03/2021	Active	10075749

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075763	AV8 PMA, LLC			HAWKER 900XP HAWKER 850XP HAWKER 800XP HAWKER 800 HAWKER 750 HAWKER 1000 BAE.125 SERIES 800B BAE.125 SERIES 800A BAE.125 SERIES 1000B BAE.125 SERIES 1000A	EASA Validation of FAA Parts Manufacturer Approval (PMA) PQ03885SWSupplement No. 15, date December 15 2020, for the Nose Landing GearBarrel Assembly NP-8UN257-1 as replacement forarticles 25-UN-385A/B, 25-8UN257-1A and 25-8UN257-27A BarrelAssemblies in Textron HawkerSeries listed above.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Av8 MRO Axle Barrel Assembly Drawing Number NP-8UN257 Revision A, date6/15/2020;Airworthines s Limitations Supplement for NP-8UN257-1 Barrel Assembly<(>,<)> Document No.AV8-ALS-17-GS001 Rev. B December 9, 2020, FAA approved 2020.12.11.or later revisions of the above listed document(s) approved/ accept...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:“Produced by the holder of the EASA STC10075763.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change...	02/03/2021	Active	10075763
10075764	DASSAULT FALCON JET CORPORATION			MYSTÈRE FALCON 50 (MF50)	Upgrade of a Honeywell MK V EGPWS with Optional Runway Safety Package	The Certification Basis for the original product remains applicable tothis certificate/ approval.Special Condition(s): CRI F-5109-001 Upgrade of a Mark V EGPWS Computerwith Optional Runway Safety PackageThe requirements for environmental protection and the associatedcertified noise and/ or emissions...	Master Data List 1032087 Revision (A), AFM Supplement 1034042 Revision(A)<(>,<)>AFM Supplement 1034065 Revision (A), Instructions for ContinuousAirworthiness 1033949 Revision (B),MMEL Supplement DFJ-MMELS-F50-00-I1Issue 1Or later revisions of the above listed document(s) approved/ accepted onbehalfP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/03/2021	Active	10075764
10075766	TEXTRON AVIATION Inc.		FAA SA2841CE	1900D	Installation of a Privacy Partition and a non-belted toiletin the cabin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Drawings and data called out on United Beechcraft, Inc. TopDrawing No.UB1901006, dated 23 July 1992<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2021	Active	10075766
10075767	TEXTRON AVIATION Inc.		FAA SA2842CE	1900D	Installation of a mid-baggage cargo net, option 1, or an aft bulkheadpartition, option 2, in the aft cabin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Drawings and data called out on Raytheon Aircraft Services Top DrawingNo. UB1901005, dated 23 July 1992<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2021	Active	10075767
10075768	GULFSTREAM AEROSPACE CORPORATION		FAA ST02715AT-D	GV-SP	Installation of an External Camera System (Securaplane)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Gulfstream Aerospace Corporation Index List GC515058016, Revision "D",dated 07 October 2003Airplane Flight Manual Supplement GC5150M006, Revision "NC", dated 07October 2003Instructions for Continued Airworthiness, GC51505A005, Revision "B",dated 03 September 2004or later revisions of the above liste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2021	Active	10075768

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075771	ANCRA INTERNATIONAL LLC		FAA ST02725LA	737-800	Installation of a cargo loading system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments:CS 25 amdt 0: 25.23(a) , 25.29(a)(b), 25.303, 25.471, 25.561, 25.601,25.605, 25.607, 25.609, 25.619, 25.625, 25.1529, 25.1541, 25.1557(a)CS 25 amdtC...	1. Ancra International LLC Controlled Data List DL85700, Revision E,dated 28 October 2019, or later FAA approved revision.2. Instructions for Continued Airworthiness, report number 10725,Revision A, or later FAA accepted revision.	Installation of IAI's 737-800 "BDSF" Pax to Special Freighter STC (FAAref ST02682SE) is a pre-requisite for the installation of this STC. EASAvalidation of this FAA STC is necessary for aircraft to be accepted onthe register of a European country.Prior to installation of this change/repair it must b...	06/07/2021	Active	10075771
10075776	SKANDIA, INC		FAA ST04475CH	BD-700-1A10, BD-700-1A11	Installation of Thermal/Acoustic kits	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Skandia Master Data List, Document Number 7803-053MDL, Revision A, dated15 July 2020Instructions for Continued Airworthiness - Skandia Document No. 7803-0531ICA, No Revision, dated10 January 2020or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance withP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/03/2021	Active	10075776
10075779	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03605NY	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	EASA Validation of FAA STC ST03605NYCMU Mk II+ upgrade in Dassault Aviation Mystere-Falcon 900 and Falcon900EX with CMUMk III.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation in accordance with Master Data List F9XW-D0093-005,Revision AInstructions for Continued Airworthiness (ICA) F9XW-D0093-155, RevisionCOperation in accordance with Airplane Flight Manual SupplementF9XW-D0093-150, Revision IROr later revisions of the above listed document(s) approved/accep...	1. This STC is applicable to Mystere-Falcon 900 (Basic Model Definition)serial numbers 001 through 168 and serial numbers 170 through 178,Mystere-Falcon 900 (C Definition) serial number 169 and serial numbers179 through 202, and Falcon 900EX serial numbers 001 through 096 andserial numbers 098 throu...	04/03/2021	Active	10075779
10075790	DAHER AEROSPACEt/a DAHER			P.68 "OBSERVER 2"	STC 00-001-19 Installation of flight parameters measuring devices	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplemental Type Certificate n° STC 00-001-19 Issue 1 dated 22.11.2019Aircraft Flight Manual Supplement n° SUP1_AFM_DHR_P68ISAE_R0 dated08.12.2020Aircraft Flight Manual Supplement n° SUP2_AFM_DHR_P68ISAE_R0 dated08.12.2020Or later revisions of the above listed document(s) approved/acceptedunder the...	Installation of this STC is limited to VULCANAIR P.68 "OBSERVER 2" s/n473.	12/03/2021	Active	10075790
10075792	DASSAULT FALCON JET CORPORATION		FAA ST04218CH	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Upgrade of a Honeywell MK V EGPWS with Optional Runway Safety Package	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List 1032081 Revision (E)AFM Supplement 1033982Revision (B) Instructions for Continuous Airworthiness 1033329 Revision (B)MMEL Supplements DFJ-MMELS-F900-00-I1 Issue1 and DFJ-MMELS-F900EX-00-I1Issue1Or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA inP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/03/2021	Active	10075792

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075802	JET AVIATION AG	REV. 1		787-9 787-8, 787-9 787-8 787-10	Seat Mounting Intercostal - Provisions OnlyThis STC introduces metallic intercostals which may be embedded insidethe B787-8/-9 floorboards to allow the installation of seats and cabinfurnishing. The STC provides an envelope identifying theallowedconfigurations in terms of Intercostal span, number o...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 Amdt. 21 of25.301, 25.305, 25.307, 25.321, 25.561, 25.562, 25.571, 25.601, 25.603,25.605, 25.609, 25.611, 25.613,T...	Master Data List JBSC-M-00184MDL-01, Issue 02B787 Intercostal-Airworthiness Requirements JBSC-M-00184ANA-02, Issue 01 Airworthinessor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limitations and conditions i.a.w. B787 Intercostal - AirworthinessRequirements JBSC-M-00184ANA-02,Issue 01.This STC does not include the actual installation of the intercostalsinto B787-8/-9, which is covered via a separate cabin modification STC.	27/09/2021	Active	10075802
10075807	BELL TEXTRON, Inc.		FAA SR11250DS	206L, 206L-1, 206L-3, 206L-4	Installation of Lithium Main Battery	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11250DS dated 26 February 2021.The requirements for environmental protection and the associatedcertified noise and/ or emi...	Master Drawing List, Report No. AA-20001, Revision C, dated11 September2020Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-20006, Revision A,dated04 August 2020Aeronautical Accessories Rotorcraft Flight Manual Supplement, Report No.AA-20007, Revision IR,dated 25 Aug...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/03/2021	Active	10075807
10075825	SAFRAN ENGINEERING SERVICES GmbH			A350-941	A350-900 CARIBIC Lab installationRev 0 consists in a fuselage cut out provision, closed by a cover.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List MOD-A35001-MDL Issue 1, dated 10 Mar 2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/03/2021	Active	10075825
10075833	INTERNATIONAL WATER-GUARDINDUSTRIES Inc.			737-800 737-700 737-600	Installation of the Potable Water Quantity Pre-select system	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS25 amdt. 0: 25.29,25.301, 25.303, 25.305(a)(b)(c), 25.307, 25.561, 25.571(a)(b) , 25.581,25.601, 25.603, 25.605, 25.609,...	Master Data Summary 1094-MDS-01 Issue 4Instructions for Continued Airworthiness MM-017371-101 Issue 3MMEL supplement MEL-017371-101 Issue 0or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bil...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/03/2021	Active	10075833
10075840	PATRIA AVIATION OY			AW119MKII	Installation of G500H EFIS, GTN650COMM/NAV and GTX335 TRANSPONDER	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Program D-119-11-CP-01, Revision 8, dated 01.03.2021Configuration Statement D-119-11-CS-01, Revision ARotorcraft Flight Manual Supplement D-119-11-RFM-01Instructionsfor Continued Airworthiness D-119-11-ICA-01Master Minimum Equipment List D-119-11-MMEL-01Design Approval/Declaration ofR...	Configuration pre-requisites:Rotorcraft configuration is asper TCDS and valid EASA approvedmaintenance program.Batteryin baggage compartment kit P/N 109G2406R01Equipped with King Serial tuned DMEDual VHF COM antennasNAV antenna (separateVLOC and GS antenna)Analogue flight instruments (no EFIS).Pr...	11/03/2021	Active	10075840

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075843	PATRIA AVIATION OY			AW119MKII	Mission system upgrade	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Program D-119-11-CP-02, Initial Revision, dated 29.01.2021Configuration Statement D-119-11-CS-02, InitialRevisionRotorcraft Flight Manual Supplement D-119-11-RFM-02Instructions for Continued Airworthiness D-119-11-ICA-01 andAppendix 2Maintenance Manual Supplement for Mission System u...	Configuration pre-requisites:Rotorcraft configuration is asper TCDS and valid EASA approvedmaintenance program.Batteryin baggage compartment kit P/N 109G2406R01EASA STC 10031277Installation of a Border Guard ConfigurationEASA STC 10075840 Installation of G500H EFIS, GTN650COMM/NAV and GTX335Trans...	12/03/2021	Active	10075843
10075845	SABENA TECHNICS BGC			EMB-145MP EMB-145LU, EMB-145MK EMB-145EU, EMB-145LR EMB-145EP, EMB-145ER EMB-135LR, EMB-145 EMB-135BJ, EMB-135ER	Mounting device and power supply connection for "PIVOT" EFBsolutions incockpit of E135/E145	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4paragraphs: 1, 29, 301, 303, 305, 307, 321, 337, 341, 561, 571, 601,603, 605, 607, 609, 613, 625, 77...	Master Data List, Ref. 10006-01-A-MDL-R00 dated 25 Feb 2021 - Airplane Flight Manual Supplement, Ref. 10006-01-A-AFMS-R01dated 23 Feb 2021 - Instructions for continued airworthiness, Ref. 10006-01-A-ICA-R00 dated 18 Jan 2021- Master Minimum Equipment List Supplement Document, Ref.100...	Limitations as per §3 of Airplane Flight Manual Supplement document.Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of...	12/03/2021	Active	10075845
10075846	FLYHT AEROSPACE SOLUTIONS Ltd.	REV. 1	TCCA SA12-34 ISSUE 2	CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700, 701, 702) CL-600-2B19 (RJ SERIES 100)	EASA validation of Transport Canada Supplemental Type Certificate (STC) SA12-34 at Issue 2AFIRS 228 Automated Flight Information Reporting System InstallationRev. 1 corrects editorial typos.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	For STC installation on aircraft models CL-600-2C10, CL-600-2D15 andCL-600-2D24: · STC Type design Change definition as per FLYHT AerospaceSolutions Ltd., Master Document List121-0070, Rev. W, and · STC Installation must be in accordance with FLYHT AerospaceSolutions Ltd., Installation Inst...	See those of the approved documentation as quoted under EASA associatedtechnical documentation.-) For STC installation on aircraft models CL-600-2C10, CL-600-2D15 andCL-600-2D24: Maintenance must be performed in accordance with FLYHTAerospace Solutions Ltd., Instructions for Continued Airworthiness1...	16/03/2021	Active	10075846
10075850	PMV ENGINEERING			747-400, 747-400F	The STC consists on the installation of the ADSB-OUT function on BoeingB747-400 and B747-400FApproved configurations are defined in the applicable Aircraft FlightManual Supplementref. AVI-01460-AFMS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: - CS25 amdt 4: 25.1301(a)(b)(c), 25.1302(a)(b), 25.1316(c),25.1309(a)(b)(c), 25.1322(a)(b)(c)(d), 25.1351(a)<(>,<)>25....	- Master Document List AVI-01460-MDL-S01-R01, dated 29 SEP 2020- Aircraft Flight Manual Supplement AVI-01460-AFMS-S01-R00, dated 16 APR2020- Instructions for Continued Airworthiness AVI-1460-ICA-S01-R00, dated16 APR 2020or later revisions of the above listed document(s) approved/ acceptedunder the EA...	STC limitations and approved configurations are defined in theapplicable Aircraft Flight Manual Supplement ref. AVI-01460-AFMS.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	12/03/2021	Active	10075850
10075855	B/E AEROSPACE, Inc. - FSI		FAA ST02702SE	737-800	LED Lighting installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments:JAR25 amdt. 14: 25.869(a)(1)(4), 25.1353(a)(b)(d)CS25 amdt. 0: 25.853(a), 25.1585CS25 amdt. 6: Appendix F Part I.The requirements for environmentalc...	B/E Aerospace , Inc. - FSI (B/E - FSI) Master Drawing List (MDL)B9FS982-D01, Revision D, dated 07 March 2021Supplemental Instructions for Continued Airworthiness, B/E - FSIDocument B9FS982-D15, Revision IR,dated 12 February 2021or later revisions of the above listed document(s) approved/ accepted onb...	Prior or concurrent incorporation of Boeing Service Bulletin 737-25-1837Rev. 00 dated 10 July 2020<(>,<)> approved/accepted on behalf of EASA inaccordance with the Technical Implementation Procedures of EU/ USABilateral Agreement.Prior to installation of this change/repair it must be determined that...	17/03/2021	Active	10075855

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075856	UAVIONIX CORPORATION	REV. 1	FAA STC SA00410BO	SEE AML FAA STC SA00410BO	Validation of STC SA00410BO, AV-30-CThe AV-30-C is an instrument designed to serve as a primary attitude ordirection indicator, in addition to other functions and installationapprovals.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 23.601, 23.603, 23.671,23.771, 23.867, 23.1301, 23.1303, 23.1306, 23.1308, 23.1309, 23.1311,23.1321, 23.1322, 23.1323, 23....	Installation in accordance with Master Drawing List (MDL) uAvionixdocumentUAV-1004236-001, Revision COperate in accordance with the Airplane Flight Manual Supplement (AFMS)uAvionix document UAV-1004044-001, Revision CMaintenance in accordance with Instructions for Continued Airworthiness(ICA) uAvion...	Installation may not be performed as part of an integrated autopilotsystem, including heading bug interface, attitude source or flightdirector display.Installation may not be performed as a replacement of a HorizontalSituational Awareness Indicator (HSI).In installations where the primary attitude i...	18/05/2021	Active	10075856
10075862	AVIO DESIGN GROUP INC.d/b/a AVIO DG	REV. 1		EC 130 B4, EC 130 T2 AS 350 B, AS 350 B1 AS 350 BA, AS 350 BB, AS 350 D AS 350 B2, AS 350 B3	Astronics Max-Viz 1200 or 1400 Sensor InstallationRevision 1: added Astronics Max-Viz 2300 Sensor Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Definition of Type Design Change: TCCA approved Avio dg Master Data List2002-MD-001 Revision E, dated April 14, 2023.For AS 350 models (1200 or 1400 EVS):Modification Instruction 2002-MI-001, Revision B, dated January 15,2021- TCCA approved.Instructions for Continued Airworthiness 2002-CA-001 Revisi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/06/2023	Active	10075862
10075882 (DE SA1273 ISSUE 1)	airplus engineering GmbH			T206H	Installation of Skydive Kit	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installation description DE-0001-000000, Rev 3, Installation of SkydiveKit Cessna T 206HEquipment List EQ-0001-000000, Rev 0Drawing Set ZG-0001-000000, Rev 0Amendment to operator's manual model Cessna T 206H "Disembarkation of 6sky divers", Document No. PO-0001-000001, Rev.4, LBA approved 04 July200...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/03/2021	Active	10075882
10075883 (DE SA1402)	airplus engineering GmbH			B60	Installation of Garmin VHF Communication Transceiver / VOR/ILS Receiver/ GPS Receiver GNS 530, GNS 430 and GTX 330 ModeS Transponder	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Document DE-0008-340000Flight Manual Supplement Garmin GNS 530, PO-0008-000530, dated 24th ofJune, 2004Flight Manual Supplement Garmin GNS 430, PO-0008-000430, dated 24th ofJune, 2004Flight Manual Supplement Garmin GTX 330, PO-0008-000330,dated 24th ofJune, 2004or later revisions of the above liste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/03/2021	Active	10075883
10075884 (DE SA1483)	airplus engineering GmbH			DO 228-101	Instrumentation for DLR "FusionProp" Project	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:Additional FAR 23,Amdt.34.The requirements for environmental protection and the associatedcertified noise and/ or emissi...	Flight Manual Supplement PO-2225-000000, issue 0-3Maintenance Manual Supplement MM-2225-000000, issue 2Master Document List MD-2225-000000, issue 6Description of Modification DE-2225-000000, issue 3Engineering Work Order EW-2225-000000, issue 3or later revisions of the above listed document(s) appro...	This STC is only applicable to research-aircraft registeredin Germany.The limited timeframe iaw. Airplus Doc. No MM-2225-000000, 4.2 areapplicable.The DLR Mod No BS-228-86-03.1 "Elektrische Versorgung derVersuchsausrüstung, Upgrade vom 02.01.2006" needs to be installed.Prior to installation of this...	17/03/2021	Active	10075884

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10075885 (DE TA0735)	airplus engineering GmbH			500	Modification of NAC/COM – Equipment in accordance with airplusdocumentation DE 0002-340000, revision 1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Airplus document DE 0002 – 340000, revision 1, dated 2nd ofMay, 2003LBA approved Airplane Flight Manual Supplement Garmin GNS 530 VHFCommunications Transceiver/VOR/ILS/GPS Receiver for Cessna 500-0081or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Applicable only for Cessna 500 S/N 500-081.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	17/03/2021	Active	10075885
10075911	GULFSTREAM AEROSPACE CORPORATION		ST04316AT-D	GULFSTREAM G280	Installation of Garmin ADS-B In System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Index list CED12268001, Rev. EFlight Manual Supplement CED1226M001, Rev. AInstruction for continued airworthiness CED1226A001, Rev. DOr later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Ag...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/03/2021	Active	10075911
10075923	STERLING CORPORATIOND/ B/A STERLING HELICOPTER		FAA STC SR04585NY	AW139 AB139	Replacement of Vertical and Horizontal Stabilizer Lights with LEDPosition/Anti-collision Lights	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR04585NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Sterling Helicopter Master Drawing List, Document No. ST-19-500-003,Rev. A, dated January 18, 2021.Sterling Helicopter Instructions for Continued Airworthiness, DocumentNo. ST-19-500-008, Rev. IR, dated January 7, 2021.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/03/2021	Active	10075923
10075937	BERINGER AERO	REV. 1		DA 62	DA-62 Wheels & Brakes replacement.Replacement of Main Wheel, Nose wheel, brake assembly, axle, mastercylinder and brakelines.Revision 1: Update with new servicing instructions within ICA documentand addition of SensAIR device as an option	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Data List MDL-STC-021 Rev. 04, dated 11 July 2024;- Instructions for Continued Airworthiness ICA-STC-021 Rev. 02 dated 11July 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/08/2024	Active	10075937
10075972 (LBA EMZ (STC) SA 1217)	SPESSART AIR SERVICE GmbH	REV. 1		F152	Installation of Engine Lycoming O-235-L2CThis EASA STC is arevision of former LBA STC (EMZ SA 1217) dated16.07.2001. The purpose of this revision is only extension of serialnumber applicability.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on the noisedatabase and/or emission levels.	Flight Manual: "Flughandbuch Reims/ Cessna F152, Ausgabe 2001", LBAapproved 16.07.2001<(>,<)>Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The effectivity of this STC shall be limited to aircraft serial numbersF15201941 and F15201961.Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffec...	29/03/2021	Active	10075972
10075981	AIRFILM CAMERA SYSTEMS, INC		FAA SA02734LA	SEE AML SA02734LA - 30.09.2020	Installation of Airfilm Wing Strut Utility Mount	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Airfilm Camera Systems documentation listed on AML No. SA02734LA, dated30 September 2020Instructions for Continued Airworthiness Airfilm Camera Systems ReportNo. AFWM-1-008, Revision A,dated 09 April 2020or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accorda...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List SA02734LA dated 30 September 2020or later approved revisions.This STC covers provisions for installation only, the equipment forwhichthese provisions are intended has not been EASA certified. A...	30/03/2021	Active	10075981

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076109	ROCKWELL COLLINS, Inc.		FAA STC SA2157CE	MYSTÈRE-FALCON 20 - F5	Electronic Flight Instrumentation System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): Docket No. NM-129; Special Conditions No.25-ANM-119 Dated Aug 6, 1996The requirements for environmental protection and the associatedcertified noisea...	Collins Drawing Index and AFMS as listed in FAA STC SA2157CE dated Aug.8th 1997 and as applicable to the configuration of the Falcon 20-F5 MSN382	Limited to MSN 382	31/03/2021	Active	10076109
10076122	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-46R-350T PA-46-600TP PA-46-500TP PA-46-350P PA-46-310P	Installation of dual Radar Altimeter Antennas Sensor Systems S67-2002	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed in accordance with 'instructions for installation' ref:ASR-2020-064-10-IFI-00 Amendment 0 dated 29/03/2021, maintained inaccordance with 'Instruction for continued airworthiness' ref:ASR-2020-064-11-ICA-00 Amendment 0 dated 22/02/2021or later revisions of the above listed document(s) appro...	This change only covers the mechanical installation of the antennas.Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of...	06/04/2021	Active	10076122
10076123	AIRBUS HELICOPTERS, Inc.		FAA SR11323DS	AS 350 B3	Installation of RT-7000 RMR Tactical Radio	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:27.773 Amendment27-50.The requirements for environmental protection and the associatedcertified noise and/ or emissionsu...	- Airbus Helicopters, Inc. Master Drawing List (MDL): 350A82-1918 Rev. A dated 02 July 2020 (350A82-1675-01configuration)<(>,<)> 350A82-1918 Rev. B dated 23 December 2020 (350A82-1675-02configuration)- Instructions for Continued Airworthiness (ICA) 350MMS-066 Rev. IRdated 15 July 2020- For t...	This STC is limited to Airbus Helicopters AS 350 B3 Post AMS 07-4654aircraft. 350A82-1675-01 is limited to receive-only.350A82-1675-02 enables transmit function.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherprevious...	23/06/2021	Active	10076123
10076124	AIRBUS HELICOPTERS, Inc.		FAA SR11338DS	AS 350 B3	Installation of an Avalex DVR AVR-8345 digital video recorder	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:27.773 Amendment27-50.The requirements for environmental protection and the associatedcertified noise and/ or emissionsu...	Master Drawling list (MDL) 350A82-1916 Rev. A dated 12 March 2021Instructions for Continued Airworthiness 350MMS-064 Rev. IR dated 17March 2021or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bi...	The STC EASA 10076336 (FAA SR1135DS<(>,<)> Aft Console/ CollectiveBarrier) is a prerequisite installation for this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will in...	13/09/2021	Active	10076124
10076127	EIRTECH AVIATION SERVICES LIMITED	REV. 1		737-8200	Installation of Fixed ELT structure provision and Fixed ELTExternalAntennaThis STC consists in the installation of structural provisions for anELT installation and installation of an ELT external antenna on Section46 Crown Fuselage, aft of Frame 787, between Stringers 1 and 2R inaccordance with Ei...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	ALS/1524-001 Issue 3 (Airworthiness Limitations Supplement)AMS/1524-001 Issue 3 (Aircraft Manual Supplement)MDL/1524-001 Issue 3 (Master Document list)or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplanes modified by this STC must be maintained in accordance with:ALS/1524-001_Iss03_ALS supplementAMS/1524-001_Iss03_AMM supplementPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and...	14/06/2021	Active	10076127
10076133	AIRBUS HELICOPTERS, Inc.		FAA SR11330DS	AS 350 B3	Installation of a Jupiter Audio System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:27.773 Amendment27-50.The requirements for environmental protection and the associatedcertified noise and/ or emissionsu...	Master Drawing List (MDL) 350A82-1923 Rev. B dated 17 June 2020Instructions for Continued Airworthiness (ICA) 350MMS-073 Rev. IR dated29 June 2020or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA...	This STC shall be installed in the frame of SR11336DS "Ukraine BorderGuard Configuration"Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	13/09/2021	Active	10076133

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076134	AIRBUS HELICOPTERS, Inc.		FAA SR09496RC-D	AS 350 B2, AS 350 B3	Installation of Trakka Corporation A800 or A800MKII Searchlight	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR09496RC-D dated 01 August 2020.The requirements for environmental protection and the associatedcertified noise and/ or emi...	- Drawling List 350A82-1786 Rev. 1 dated 06 December 2013- For configuration 350A82-1638-04:Rotorcraft Flight Manual Supplement 350FMS-551 Rev. A dated 01 August2020Instructions for Continued Airworthiness 350MMS-052 Rev. IR dated 01July 2020- For configurations 350A82-1638-01, 350A82-1638-02 and 35...	This STC is applicable to all serial numbers except the A800 MKIIsearchlight installation is limited to AS 350 B3 modelonly.Installation of infrared light filters in the A800 or A800 MKIIsearchlight is not authorised.The installation of A800 searchlight removable provisions (350A73-1870)under thisC...	07/04/2021	Active	10076134
10076155	KLM ENGINEERING & MAINTENANCE			737-800	Cabin reconfiguration of KLM Boeing 737-800 aeroplanes	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	KLM Engineering & Maintenance Master Data List MDL-013931 Revision 06KLM Engineering & Maintenance Aircraft MaintenanceManual SupplementAMM737013931-00 original issueKLM Engineering & Maintenance 737 CMU - Instructions for ContinuedAirworthiness ICA737-013931 original issueKLM Engineering & Mainten...	Concurrent installation of EASA STC 10075855 (Installation of LED MoodLighting System) is required.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adversee...	09/04/2021	Active	10076155
10076166	AEROLEDS HOLDINGS, LLC	REV. 1	FAA STC SR02704SE	SEE FAA AML	Installation and maintenance of the Sunspot 36 and 46 series lightsRev. 1 updates the holder name following a change ofownership fromAEROLEDS, LLC TO AERLEDS HOLDINGS, LLC.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02704SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Instructions for Continued Airworthiness (ICA) as listed onthe AMLSR02704SEor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is only valid for CS-27 aircraft types and mode...	17/06/2025	Active	10076166
10076217	PATS AIRCRAFT L.L.C.	REV. 1	FAA ST01384NY	737-800	1. Configuration 1-A: Installation of a Three Cell Auxiliary Fuel Systemin the forward and aft cargo compartments in accordance with PATS, Inc.Kit Installation Drawing BBJ2-101200as listed on Master Drawing ListBBJ2-0001, Rev. C dated 8/23/01, or later FAA approved revision isrequired.2. Configurat...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aircraft Flight Manual Supplements applicable to Configurations 1-A,1-B, 1-C, 1-D, 1-E, 1-F, 1-G, 1-H1. PATS, Inc. Airplane Flight Manual Supplement No. 101 For A Three -Cell Auxiliary Fuel System FAA approved August 30, 2001, is required forConfiguration 1-A.2. PATS, Inc. Airplane Flight Manual Sup...	- Configuration 1-A through 1-H are limited to one year from date ofissue. Incorporation of PATS, Inc. Service BulletinNumber BBJ2-28-08A,Revision A. dated June 5, 2002, removes this limitation on affectedaircraft.- Configuration 1-A through 1-H are limited to the Aircraft SerialNumber 32438, 32450...	13/04/2021	Active	10076217
10076224	BLACKHAWK MODIFICATIONS Inc.		FAA STC SA04303CH	B300C B300 300LW 300	Installation of a Lithium-ion main ship battery in accordance with FAASTC SA04303CH	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): FAA Special Condition 23-288-SCThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the produc...	Blackhawk Modifications, Inc. Master Drawing List 601-002-MDL, revision6, dated March 18, 2020;Blackhawk Modifications,Inc. Flight Manual Supplement, Document No.601-023-AFMS, Revision IR, FAA approved May 8, 2020;Blackhawk Modifications,Inc. Instructions for Continued Airworthiness,Document No. 6...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/04/2021	Active	10076224

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076225	AEROTEC & CONCEPT			FALCON 10	Installation of a SATCOM system and antenna and integrationof a WIFIsystem	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 25.581, 25.771,25.773, 25.899, 25.1301, 25.1309, 25.1316, 25.1321, 25.1351, 25.1353,25.1357, 25.1360, 25.1431, 25.1529, 2...	Master Data List no. AE19151MDL rev. 0 dated 12th April 2021Aircraft Flight Manual Supplement no. AE19151AFMS rev. 1 dated 23rdMarch 2021Instruction for Continued Airworthiness no. AE19151ICA rev. 2 dated 23rdMarch 2021or later revisions of the above listed document(s) approved/acceptedunder the EAS...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/04/2021	Active	10076225
10076232	ELBE FLUGZEUGWERKE GmbH	REV. 1		A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-201/-202/-203/-223/-243	Installation of an Additional Stowage in Courier Area of A330P2Fconverted aircraft	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	EFW-EO-0154-001 Rev. A - ENGINEERING ORDER - A330P2F FCRC add. StowageCabinetor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Current STC shall be only applied to aircraft that have thefollowingSTC embodied:EASA STC 10063798 (STC for A330 P2F) Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will in...	03/09/2024	Active	10076232
10076238	AEROTEC & CONCEPT			FALCON 10	ADS-B OUT and LPVImplementation of ADS-B function and LPV capability	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25.581; 25.771;25.773; 25.899; 25.1301; 25.1302; 25.1309; 25.1310; 25.1316; 25.1321;25.1322; 25.1329; 25.1351; 25.1353;...	-AFM Supplement AE19150AFMS Rev. 1-MMEL Supplement AE19150MMELS Rev. 0-ICA AE19150ICA Rev. 1-MDL AE19150MDL Rev. 0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	For Falcon 10 aircraft without CAT II capability if Satcom system isinstalled, GNSS antennas must be installed forward of FR 11 and SATCOMantenna must be located aft of FR 22.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and an...	16/04/2021	Active	10076238
10076244	AEROLITE AG	REV. 1		PC-24	EMS Interior P/N 024-0284000-501:This Major Change to Type Design covers the introduction EMS interiors(12 different configurations) into a PC-24 aircraft.Rev. 01: Amendment of the limitations and procedure sections of FlightManual Supplement FMS-024-0284000-501. Extension of the scope of the EMSoxy...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): D-104 Emergency evacuationfor Air MedicalServices installations.The requirements for environmental protection and the associatedcertified noise an...	To be installed i.a.w. Master Document List Doc. No. MDL-19-011, Rev. ETo be operated in accordance with Aerolite FMS Doc. No.FMS-024-0284000-501 Rev. BTo be maintained i.a.w. Aerolite ICA Doc. No. OPM-024-0284000-501, Rev.EOr later revisions of the above listed document (s) approved/ acceptedunder th...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/11/2021	Active	10076244
10076245	SABENA TECHNICS BGC			A330-243	Cabin and IFE modification from 34B/C & 207Y/C to 21B/C & 236Y/C	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4:25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341,25.365, 25.561, 25.562, 25.601,...	- Master Data List, Aeroconseil document No. 40752-01-A-MDL-R00, dated15 April 2021-Instructions for continued airworthiness, Aeroconseil document No. 40752-01-A-ICA-R00,dated 09April 2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limitations as per §3 of Instructions for Continued AirworthinessAs a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik EASASTC No. 10014507 Rev. 0...	16/04/2021	Active	10076245

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076248	SABENA TECHNICS BGC			A330-343/-841/-941 A330-321/-322/-323/-341/-342 A330-243/-243F/-301/-302/-303 A330-201/-202/-203/-223/-223F	Mounting device and power supply connection for portable EFB with PIVOTcases in cockpit of Airbus A330.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 at Amendment 15paragraphs: 29, 301, 303, 305, 307, 321, 337, 341, 561, 571, 619, 625,773, 1581. CS 25 at Amendment...	Master Data List, Ref. 10001-01-A-MDL-R00 dated 16 April 2021-Airplane Flight Manual Supplement, Ref. 10001-01-A-AFMS-R00 dated 16April 2021-Instructions for continued airworthiness, Ref. 10001-01-A-ICA-F01-R00-installation dated 16 April2021,Ref. 10001-01-A-ICA-F02-R00-removal dated 16 April 2021...	Limitations as per §3 of Airplane Flight Manual Supplement document.Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of...	16/04/2021	Active	10076248
10076249	AVIONITEC Ltd.			PA-46-350P	Installation of TAS Antennas:Installation of one double blade top TAS antenna and on single bladebottom TAS antenna in pressurized section. These antennas are requiredfor the installation of Garmin TAS system 800 subject to a separate EASAapproval (STC 10067437 Rev.1).	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	To be maintained i.a.w. Instruction for Continued AirworthinessNo.11223-015 issued 16.04.2021 (date on the ICA 31.08.2020)<(>,<)>Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/04/2021	Active	10076249
10076250	GVH AEROSPACE (IRELAND) LIMITED	REV. 3		A340-642, A340-643	A340-600 Cargo Carriage in Passenger CompartmentRev. 1 corrects the STC holder address.Rev. 2: Extension of the calendar limitation to July 31, 2022 as perupdated EASA Deviation D-130 Issue 3.Rev. 3: 'Yellow' and 'Red+' configuration layout updated	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Deviation(s): D-130/60073586the following paragraph(s) at a later amendment: CS-CCD Issue 2 / CS-MMEL Issue 2The requirements for environmental protection and...	Master Data List GVH-11008-01-MDL-01 Issue 14 dtd. 16-Dec-2021Flight Manual Supplement GVH-11008-01-FMS-01 Issue 9 dtd.16-Dec-2021Master Minimum Equipment List Supplement GVH-11008-01-MMEL-01 Issue 6dtd. 26-Nov-2021Cabin Crew Data Supplement GVH-11008-01-CCD-01 Issue 10 dtd. 16-Dec-2021Instructionsd...	As per Deviation D-130/60073586 EASA has established an operatinglimitation. The allowance to transport cargo in passenger compartment islimited to 2000 FH following installation of the change or until July31, 2022, whichever occurs first – see also Airworthiness LimitationsSection of Document GVH-1...	20/12/2021	Active	10076250
10076254	AEROTEC & CONCEPT	REV. 1		B300	B300 External Installations for ISR missionsRev. 1 extends the approval to Textron Aviation B300 aircraft withPT6-67A engine and with Proline Fusion avionics (B350 ER Super KingAir).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aerotec Concept Master Data List, document AE19105MDL Rev 1Aerotec Concept Aircraft Flight Manual Supplement, document AE19105AFMSRev 0, dated 13 APR 2021 for Textron Aviation B300 aircraft withPT6A-60A engine and with Proline21 avionics (B350 ER Super King Air)Aerotec Concept Aircraft Flight Manual...	In conjunction with STC 10076255 (B300 Internal Cabin Modification forISR Mission Control)And the following prerequisites: - Textron Aviation B300 aircraft with Extended Fuel capabilities,with Proline21, with PT6A-60A engine, and equipped with Dual Aft StrakesKit (Beechcraft Super King Air B300,F...	22/02/2024	Active	10076254
10076255	AEROTEC & CONCEPT			B300	B300 Internal Cabin Modification for ISR Mission Control	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Aerotec Concept Master Data List, document AE19106MDL Rev 0, date 9April 2021Aerotec Concept Aircraft Flight Manual Supplement, document AE19105AFMSRev 0, date 13 April 2021Aerotec Concept Instructions For Continued Airworthiness, documentAE19106ICA Rev 0, date 19 October 2020or later revisions of t...	MOD AE19105: External modificationPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	19/04/2021	Active	10076255

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076267	B/E AEROSPACE, Inc. - FSI		FAA STC ST02706SE	737-800	Interior reconfiguration on Boeing 737-800 series airplanes	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:JAR25 chg. 14: 25.869(a)(1)(4), 25.1353(a)(b)(d) CS25 amdt. 0: 25.853(a)(c)(d)(e) The requirements for environmental protecti...	B/E Aerospace Inc. - FSI (B/E - FSI) Master Drawing List (MDL)C0FS035-D01 Revision D, dated 8 April 2021 or later Federal AviationAdministration (FAA) approved revisions.Instructions for Continued Airworthiness, B/E - FSI DocumentC0FS035-D15, Revision A, dated 29 March 2021, or later FAA acceptedrev...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/04/2021	Active	10076267
10076270	AEROSERVIS, S.R.O.			VIPER SD-4 RTC VIPER SD-4 NIGHT-VFR	STC AE/215 - Bearings replacement in primary control system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed, maintained, and operated in accordance with documents listedin: Master Document List, Doc. No. AE215000X_IR,Dated 9th March 2021.or later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/04/2021	Active	10076270
10076294	airplus engineering GmbH	REV. 1		31A	Provision for GPS / WAAS Antenna(s)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- According to AirPlus Engineering GmbH Master Document List No.MDO-2328-340000 Rev 4- To be installed iaw. AirPlus Engineering GmbH Work Order ref:EWO-2439-340000 Rev 2- To be operated iaw. AirPlus Engineering GmbH Flight Manual Supplementref: POH-2439-340000 Rev 1- To be maintained iaw. AirPlus En...	With the installation of this design change THE AIRCRAFTS THAT HAVECONFIGURATION 4 Option 1 INSTALLED ARE LIMITED TO 35,000 FT. MAXIMUMALTITUDE.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any other previously installed ch...	02/09/2021	Active	10076294
10076300	DOA AESGLOBAL LIMITED			BD-700-1A10	INTRODUCTION OF GO-DIRECT WIFI ROUTER	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed and maintained in accordance with AES-700-6315MDLissue 1dated April 2021, operated in accordance with AFM Supplement No 93 issue1 dated April 2021or later revisions of the above listed document(s) approved/ acceptedunder the EASAsystem.	Embodiment of approved EASA STC No. 10063260 Rev 1 (or later approvedrevision) is a pre-requisite to the installation of this design changePrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change a...	26/04/2021	Active	10076300
10076309	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE	REV. 1	FAA STC ST03107CH	737-900ER 737-900 737-800 737-700 737-600	Certification of Compatibility with Cellular and/or Wireless DataTechnologies- Group 1: installations utilizing both Cellular and Wireless DataTechnologies- Group 2: installationsutilizing the Wireless Data Technologies only- Group 3: installations utilizing the Cellular Technologies onlyRev. 1: Ty...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 0: 25.1309(a), 25.1529The requirements for environmental protection and the associatedcertified noise and/ or e...	Armstrong Aerospace Master Data List, Doc. No. DC104-9208-00, RevisionB, dated 2 April 2012, or later FAA approved revision.	Following equipment is not compatible with the design covered by thisapproval:Honeywell Display Unit, PIN 4091900-xxx (Example PINs 4091900-931,4091900-932, 4091900-933 and 4091900-934), has exhibited susceptibilityduring 4 watt EIRP Personal Electronic Devices (PEDs) wireless dataradio frequency co...	10/06/2021	Active	10076309

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076336	AIRBUS HELICOPTERS, Inc.		FAA STC SR11335DS	AS 350 B3	Installation of an Aft Console / Collective Barrier	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11335DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List 350A82-1926 Rev. IR dated 22 December 2020;2. Instructions for Continued Airworthiness 350MMS-077 Rev. IR dated 12March 2021;or later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ U...	This STC is applicable to all serial numbers for this Make-Model.This STC does not certify the installation of any equipment in the aftconsole/ collective barrier.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	28/04/2021	Active	10076336
10076346	AIRBUS HELICOPTERS, Inc.		FAA STC SR11333DS	AS 350 B3	Installation of a FLIR UltraForce 350-HD Surveillance System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11333DS.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Drawing List 350A82-1914 Rev. A dated 15 March 2021Rotorcraft Flight Manual Supplement 350FMS-562 Rev. A dated 15 April2021Instructions for Continued Airworthiness 350MMS-061 Rev. IR dated 26March 2021or later revisions of the abovelisted document(s) approved/ accepted onbehalf of EASA in acc...	This STC is limited to Airbus Helicopters AS350 B3 Post AMS07-3439 withhigh skid gear.Refer to approved RFMS for the applicable airspeed limitation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installe...	16/09/2021	Active	10076346
10076357	GVH AEROSPACE (IRELAND) LIMITED			A320-216 A320-214	MTOW ReductionReduction of MTOW by introduction of AFM Supplement with revised weightlimitations.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.1, 25.25,25.1519, 25.1529, 25.1581 & 25.1583 at amdt 23.The requirements for environmental protection are unchangedc...	GVH-11970-01-MOD-01 issue 3GVH-11970-01-FMS-01 issue 3Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/05/2021	Active	10076357
10076365	MIDDLE FORK MODS LLC		FAA STC SA01869WI	SEE FAA APPROVED MODEL LIST	Installation of tail tie down assembly	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01869WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. FAA Approved Master Drawing List as listed on AML SA01869WI, amended23 July 2019, or later FAA Approved revision.2. Instructions for Continued Airworthiness (ICA) as listed on AMLSA01869WI, amended 23 July 2019, or later FAA Approved revision.	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List SA01869WI dated 25 July 2019.Prior to installation of this change/repair it must be determined thatthe interrelationship between thischange/repair and any otherpreviously installed change and/e...	30/04/2021	Active	10076365
10076367	DASSAULT AIRCRAFT SERVICES (DAS)		FAA ST03594NY	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	EASA Validation of STC ST03594NYHoneywell Primus Elite SVS Upgrade in Dassault Aviation Mystere-Falcon900 and Falcon 900 with Honeywell Primus Elite Avionics and HoneywellFMS 6.1.1 or later.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	AFM Supplement F9XW-D0099-150-1 Rev. IRAFM Supplement F9XW-D0099-150-2 Rev. IRMDL Supplement F9XW-D0073-005 Rev. Eor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Applicable to Falcon 900 and 900EX with EASA STC 10054966 (FAA STCST03371NY) and 10053829 (FAA STC ST02969NY) installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wille...	30/04/2021	Active	10076367

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076375	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE		FAA ST02915NY-D	737-700, 737-800	Installation of a Lufthansa Systems BoardConnect System	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements: the following paragraphs at a lateramendment:- CS25 amdt 0: 25.831, 25.853, 25.869, 25.981, 25.1309, 25.1353,25.1423, 25.1431, 25.1583, 25.1585.The requirements for enviro...	Armstrong Aerospace Master Data List DC104-9100-00 RevisionN dated 02May 2013Instruction for Continued Airworthiness and Airplane Flight ManualSupplement as listed on the Master Data List above mentionedor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accorda...	The FAA STC ST03107CH is a prerequisite installation to ensure TPEDtolerance.Operational approval to use T-PED's must be obtained separately fromthis STC.The Lufthansa BoardConnect must interface with the following listedrequired existing systems/components, which must be installed. The belowlistedS...	19/05/2021	Active	10076375
10076385	JET AVIATION AG	REV. 1		747-400	Installation of an adapter plate between the A/C fuselage skin and theVHF antenna, located at the forward fuselage, upper lobe between STA 900to STA 920, including new inspection intervals.Rev.1 : Typo correction / editorial correction.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Engineering Order VHF Adapter Plate Modification JBSL-M-03609ENO-001Instructions for Continued Airworthiness VHF Adapter Plate ModificationJBSL-M-03609ICA-001 Iss.BMaster Data List JBSL-M-03609MDL- 001 Iss.Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/05/2021	Active	10076385
10076388	PROTOPLANE SPECIAL MISSION AIRCRAFT			MBB-BK117 D-3M MBB-BK117 D-2, MBB-BK117 D-3 MBB-BK117 D-2 MBB-BK117 C-2 MBB-BK117 C-1, MBB-BK117 C-2 MBB-BK117 C-1 MBB-BK117 B-2 MBB-BK117 B-1, MBB-BK117 B-2 MBB-BK117 B-1	Installation of provisions for the EVS2300 system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Declaration of compliance Document No. PP-112-DC-04 issue 4dated 3rdMay 2021Master data list No. PP-112-MDL issue 5 dated 3rd May 2021Rotorcraft Flight Manual Supplement No. PP-112-AFM issue 1 dated 22ndDecember 2020or later revisions of the above listed document(s) approved/acceptedunder the EASA...	This approval is a design provision only. The activation ofthe EVS2300and the side displays will be addressed in a separate approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ o...	05/05/2021	Active	10076388
10076400	AERODATA AG	REV. 1		B300	Installation of Automatic Flight Inspection System AD-AFIS-112	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List, Document Number MDL-A/C-940 Rev. 2, date28-Apr-2021Master Assembly Drawing, Document Number B300-40_01_AFIS Rev 0, date09-Dec-2020Installation Manual, Document Number HB-A/C-1101 Rev 3, date 17-Mar-2021Airplane FlightManual Supplement, Document Number AFM-176 Rev 0, date02-Feb...	This Installation is limited to B300, Serial Number FL-630.Operational Limitations according to AFM-176, Rev. 0 or later must beobserved.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and...	06/05/2021	Active	10076400
10076403	TEXTRON AVIATION Inc.		FAA SA00748DE	1900D	Installation of the Rockwell Collins IDS-3000 system with new PrimaryFlight Displays, Multi-Function Display, Display Control Panels, AudioPanels and Engine Instrumentation. The installation also includesIntegrated File Server System capability XM Satellite Graphical Weather,Turbulence Weather Radar...	Certification basis as defined on the original FAA STC ref SA00748DE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact onthe noise database.	Installation in accordance with:-Hawker Beechcraft ServicesMaster Data List (MDL) 014-3110-L01-00,Revision 4.0, dated 09/17/2012.Operate in accordance with:-Hawker Beechcraft Services Aircraft Flight Manual Supplement (AFMS) ref014-3110-A01-00, revision 3.0, dated 09/17/2012.Hawker Beechcraft Servi...	Installation of Rockwell Collins APS-65 Autopilot system must have beenpreviously accomplished.Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffec...	05/05/2021	Active	10076403

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076407	W&S CONSULTANTS, INC.d/b/a TELAIR INTERNATIONAL		FAA STC ST02741LA	A321-272N A321-251N/-252N/-253N/-271N A321-211/-212/-213/-231/-232	Installation of Main Deck Cargo Loading System (MDCLS)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 0: 25.23 (a)(b), 25.303, 25.601, 25.605(a) (b),25.625(a)(b)(c), 25.1529, 25.1541(a)(b)CS25 amdt. 1: 25.307(a), 25....	FAA approved Telair International Index List IL904100 revision B, dated24 February 2021, and FAA approved Airplane Flight Manual SupplementAFMS904100 revision Original, dated 18 March 2021 or later FAA approvedrevisions.FAA Accepted TelairInstructions for Continued Airworthiness (ICA),Report No. IC...	The following STC are prerequisites for this installation:1) Precision Conversions, LLC Airbus A321 STC ST02716SE,2) Telair International Cargo Floor STC ST02742LAPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	20/05/2021	Active	10076407
10076408	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04305AT-D	GV-SP GIV-X	Installation of Iridium SATCOM System (FANS-1/A+ Over Iridium)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04305AT-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Gulfstream Aerospace Corporation Index List CE41 2038008, Revision(-), dated 30 January 2018, or later FAA approved revision.2. Airplane Flight Manual Supplement, CE41 203M010,Revision (-), dated30 January 2018, or later FAA approved revision.3. Airplane Flight Manual Supplement, CE41 203M011, R...	FANS-I / A+ must be installed prior to or concurrently withthis STC onGulfstream GIV-X and GV-SP.FANS Over Iridium (Iridium data safety services) have not been approvedto operatesimultaneously with an operating Inmarsat SATCOM System. Foraircraft equipped with an Inmarsat SATCOM that is interfaced...	06/05/2021	Active	10076408
10076409	AERONAUTICAL ENGINEERS Inc.	REV. 2	FAA ST02690LA	737-800	B737-800 Passenger to Freighter ConversionThis modificationadds a main deck cargo door and main deck Class Ecargo compartmentRevision 1: Added reference to EASA MMEL Supplement and ETOPS CMPRevision 2: EASA MMEL supplement updated	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s):CRI D-01 Courier compartment Issue 1CRI D-02 Protection of essential systems Issue 1CRI D-03 Access to Class E compartment Issue 1-The...	- Master Data List, R-951 Rev. H- Airplane Flight Manual Supplement (AFMS), R-1000 Rev. D- Airworthiness Limitations and Certification Maintenance Requirements (AWL and CMR), R-1025-CMR Rev. D- MMEL/DDG EASA R-1092 Rev. D-ETOPS Configuration, Maintenance & Procedures (CMP) Supplement, R-1074Rev. Aor...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.EASA STC 10075225 (FAA ST02691LA - Installation of 9g R...	01/10/2025	Active	10076409
10076410	ANCRA INTERNATIONAL LLC		FAA ST02692LA	737-800	Installation of cargo loading system	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 Amdt 0: 25.561CS 25 Amdt 1: 25.305(a)(b), 25.307(a), 25.613(a)(b)CS 25 Amdt 5: 25.1301(a)(1)(2)(3)(4)CS 25 Amdt 13: 2...	Ancra International LLC Controlled Data List DL85360, Revision E, dated20 November 2018Instructions for Continued Airworthiness 10614 rev Bor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordancewith the Technical ImplementationProcedures of EU/ USA Bilat...	EASA STC 10076409 (FAA STC ST02690LA - B737-800 Passenger to FreighterConversion) must be concurrently installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introdu...	18/05/2021	Active	10076410
10076411	ALPINE AEROTECH LP		TCCA SH21-11 ISSUE 1	429	Floor Protection Kit Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	CONFIG.,,INSTALLATION INSTRUCTION,,INSTRUCTION FOR CONTINUED,, MASTERDATA LIST,,,,,,,,,, AIRWORTHINESSFWD,,,, AAL-412-025-001,,,,AAL-412-025-701,,,,Revision NI,,,,,Revision NI,,,December 18, 2020,,,December 18, 2020AFT,,,,AAL-412-025-002,,,,AAL-412-025-702,,,, AAL-412-024-001,,,...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product	06/05/2021	Active	10076411

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076413	W&S CONSULTANTS, INC.d/b/a TELAIR INTERNATIONAL		FAA STC ST02742LA	A321-272N, -272NX A321-271N, -271NX A321-253N, -253NX A321-252N, -252NX A321-251N, -251NX A321-231, -232 A321-211, -212, -213 A321-111, -112, -131	Installation of Main Deck Cargo Floor Panel System (CFPS)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: Thefollowing paragraph(s) at a later amendment:CS25 amdt. 0: 25.23 (a)(b), 25.303, 25.601, 25.605(a)(b), 25.625(a)(b)(c)CS25 amdt. 1: 25.307(a), 25.613(a)(b)(c)(e)CS25 amd...	1. Telair International Index List IL604100 revision A, dated 24February 2021 or later FAA approved revisions.2. FAA Accepted Telair Instructions for Continued Airworthiness (ICA),Report No. ICA604100, Rev. C, 15 dated April 2021.3. Operation and System Maintenance Manual (O<(>&<)>SMM), Report No. 50...	The above CFPS may only be installed on Airbus A321-200 Series passengeraircraft that have previously been modified in accordance with PrecisionConversions, LLC Airbus A321 STC ST02716SE. EASA validation of FAA STCST02716SE is a pre-requisite on EASA STC 10076413 for the installationof this STC desi...	20/05/2021	Active	10076413
10076414 (EASA.A.S.00310)	SABENA TECHNICS BGC	REV. 1		ATR 72-212, ATR 72-212 A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Installation of a Honeywell Mark VIII Enhanced Proximity Warning System (EGPWS)Rev. 1: Addition of a MMEL Supplement	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-MMEL issue 2: 050, 100, 110, 120, 125, 130, 135, 140, 145, 150.The requirements for environmental protection and the a...	Master Data List N °0120-01-A-2103-R20 dated 07 October 2004AFM Supplement 0120-01-A-2301-R03ICA detailed in Airworthiness Data Sheet Supplement N°0120-01-A-2203-R16Master Minimum Equipment List Supplement - N°0120-01-A-MMELS-R01or later revisions of the above listed document(s) approved/ acceptedunde...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.,,,,	07/05/2021	Active	10076414
10076419	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			767-300	B767 Cabin Modification for Cargo TransportModification of the cabin and removal of existing seats to allowtransportation of cargo on the passenger compartment floor.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): CRI D-130.- The following paragraph (s) at a later amendment: CS 25.561 (c) (2)Amdt 24.The requirements for environmental protection and the associatedcerti...	The change is defined with revision 1 of AMES Engineering Order DocumentEO_M154001148_RSP_15042020The installation has to be accomplished in accordance with revision 18of AMES Instructions for Continuous Airworthiness DocumentICA_M154001148_RSP_23042020The aircraft shall be operated in accordance wi...	The allowance to transport cargo in the passenger compartment is limitedto 2000 FH following installation of the changeor to 31 December 2021,whatever occurs first.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpre...	07/05/2021	Active	10076419
10076440	AV8 PMA, LLC			HAWKER 900XP/1000 HAWKER 750/800/-800XP/850XP BAE.125 SERIES 800A/ 800B BAE.125 SERIES 1000A/ 1000B	Approval of FAA PMA parts for use on Bae 125 and Hawker Series Aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Approval of FAA PMA Parts under AV8 PMA, ref No PQ03885SW Supplement 13dated April 30, 2020, and Approved Drawing List,ref AV8-DL19116 Rev B,dated 10.27.2020.Instructions for Continued Airworthiness (ICA) in accordance with AV8PMA, LLC documents ref :-AV8-ALS1911601, rev NC, dated 12.09.2019.AV8-AL...	In accordance with FAA-EASA TIP rev 6, Article 7.11.3, the followingstatement should be written in the remarks block ofthe FAA Form 8130-3:“Produced by the holder of the EASA STCnumber 10076440".Prior to installation of this change/repair it must be determined thatthe interrelationship between thi...	19/05/2021	Active	10076440
10076472	BELL TEXTRON, Inc.		FAA STC SR11246DS	505	Installation of Accessories Package	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR11246DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List, Report No. AA-18078, Revision D, dated 1 June2020;2. Aeronautical Accessories Instructions for Continued Airworthiness,Report No. AA-18083, No Revision, dated 19 June 2019;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with...	This STC is applicable to all serial numbers for the Bell Textron CanadaLimited 505.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	11/05/2021	Active	10076472

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076473	HELI AUSTRIA GmbH			AS 355 F2 AS 355 F1, AS 355 F2 AS 355 F1	Installation of a GTX345 Transponder	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:CS 27.610 Amdt 4;CS-ACSN Issue 2 Subpart A and D.The requirements for environmental protection and the associatedcertifi...	Master Document List MDL HAU-D-050-001, Revision 2, dated 10.05.2021Rotorcraft Flight Manual Supplement, HAU-D-050-005,Revision 0, dated16.12.2019Installation Manual, HAU-D-050-004, Revision 0, dated 16.12.2019Instructions for Continued Airworthiness, HAU-D-050-006 , Revision 0,dated 16.12.2019or l...	Type of Operation: VFR only.Prior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect uponthe airworthiness of the product.	11/05/2021	Active	10076473
10076474	HELI AUSTRIA GmbH			AS 355 F2 AS 355 F1, AS 355 F2 AS 355 F1	Installation of a GTN650 COM/NAV/GPS as NAV2/COM2.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:CS 27.610 Amdt 4;CS-ACSN Issue 2 Subpart A, B, C.The requirements for environmental protection and the associatedcertifi...	Master Document List MDL HAU-D-051-001, Revision 2, dated 10.05.2021Flight Manual Supplement HAU-D-051-005, Revision 0,dated 20.10.2020Instructions for Continued Airworthiness HAU-D-051-006, Revision 0,dated 28.11.2019Installation Manual HAU-D-051-004, Revision 0, dated 28.11.2019or later revisions...	Type of Operation: VFR only.Prior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect uponthe airworthiness of the product.	11/05/2021	Active	10076474
10076475	BOEING IRELAND LIMITED			737-800	Avionic provisions for a “Poland Head of State” configuration.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:CS 25 amdt. 22:25.1302 and CS ACNS Initial issue.The requirements for environmental protection and the associatedcertifi...	Certification Programme BIL-00189-CP rev 01Aircraft Flight Manual Supplement BIL-00189-AFM01 rev 0Instructions for Continued Airworthiness BIL-00189-ICA01 rev0Limitations report BIL-00189-DR01 Rev 0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	-- the activation of the provisions installed as per documentBIL-00189-DR01 tables 2 and 3 is not covered by this certificate.- the enabling of military features of the active equipment as perdocument BIL-00189-DR01 table 5 is not covered by this certificate.-in particular: only the ATC Mode 3/A, Co...	11/05/2021	Active	10076475
10076479	HELI AUSTRIA GmbH			AS 332 L1 AS 332 L AS 332 C, AS 332 L AS 332 C1, AS 332 L1	HAU-D-030 - Remote pump power supply	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Master Document List, Doc. No. HAU-D-030-001, Rev. 0Installation Manual, Doc. No. HAU-D-030-004, Rev. 0Flight Manual Supplement, Doc. No. HAU-D-030-005, Rev. 0Instructions for Continuing Airworthiness, Doc. No. HAU-D-030-006, Rev. 0Supplemental Master Minimum Equipment List, Doc. No. HAU-D-030-511, R...	The following are prerequisites to the installation of thisSTC:1. the helicopter must not be equipped with the “6th fuel-tank”.2. the helicopter must be equipped with a cargo hook pole and provisionsfor the 4.5-ton cargo hook.3. the helicopter must embody installation of HAU-D-026, EASA MiCApproval...	12/05/2021	Active	10076479
10076487	365 AEROSPACE DDS LIMITED			BAE 146 SERIES 300 BAE 146 SERIES 200 BAE 146 SERIES 100 AVRO 146-RJ85 AVRO 146-RJ70 AVRO 146-RJ115 AVRO 146-RJ100	Conversion of Flying Services Seats/To meet QinetiQ's requirement for aircraft operator (crew mission) seatsfor the modification to their Avro RJ100 aircraft (Aircraft TechnologyDemonstrator) (ATD) "Project Mansfield", standard 'Flying Services'F3304 Triple and F2306 series passenger seats will be...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Change / Repair Certification Plan, CCP-1136 Rev. G- Instructions for Continued Airworthiness, ICA-1136-001 Rev. C- Master Data List, MDL-1136 Rev. E- Service Bulletin, SB-1136-25-001 Rev. D- Flight Manual Supplement No.1, FMS-1136-001 Rev. A- Drawing FLYING SERVICES SEAT INSTALLATION - 365-25-117...	None	17/05/2021	Active	10076487

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076493	PARC AVIATION ENGINEERING SERVICESLIMITED			SEE EASA APPROVED MODEL LIST	AML-25001Installation of emergency equipment.	The following Certification Basis applies to all the modelsincluded inthe AML List:-CS 25 Amendment 12.Affected paragraphs:25.2925.301 (a) 25.30325.305 (a)25.307 (a)25.561 (b) (c)(d)25.60125.60325.611 (a) 25.787 (a) (b)25.789 (a)25.853 (a) 25.86325.869 (a)25.130125.1309 (a) (b)25.1353 (a) (b) (c)25.1...	-Master Document List AML-25001-MDL Rev 02-Instructions forContinued Airworthiness AML-25001-ICA-01 Rev 00-OperationalSuitability Data – Cabin Crew Data SupplementAML-25001-CCD-01 Rev 00-Operational Suitability Data – Boeing 737 Max Master Minimum EquipmentList Supplement AML-25001-MMEL-01 Rev 00-...	As a result of this Change it is not permitted to install additionalequipment or cabin baggage in the same compartment as the newlyinstalled portable ELT or AED. It is also not permitted to install anyfurther pressurised equipment in the same stowage compartment.Prior to installation of this change/...	17/05/2021	Active	10076493
10076495	DASSAULT FALCON JET CORPORATION		ST10650SC-D	FALCON 900EX (F900EX)	Installation of Mid Cabin Cabinet Structural Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST10650SC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Data List Report No. F9EX-01066, Revision J, dated 16 April 2008, orlater FAA approved revision.2. For Mid Cabin Cabinet F900 Installation Requirements use Report38311, Revision NC dated 4-8-08.F9EX-OI066-501 Installation approved for Falcon 900EX EASy Definitionand Falcon 900DX Definition requir...	The EASy designation for Falcon 900EX does not correspond to a modeldesignation. This is only a commercial designation for airplanes onwhich a Major modification number M3083 has been embodied.The 900DX designation for Falcon 900EX does not correspond to a modeldesignation. This is only a commercial...	19/05/2021	Active	10076495
10076500	AIRBUS DEFENCE AND SPACE S.A.			A330-243	A330-200 Emergency MEDEVAC SOLUTION (DCV0993S-E)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Design Change Definition DCV0993S-E Issue A dated 26/03/2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	STC EASA.IM.A.S.0134 is pre-requisite for this installation. Oxygeninstallation provisions only. Not certified for use with pressurizedOxygen.No medical equipment is part of this installation. The stretcher carrieris not covered by this STC.This STC constitutes an approval for installation only fors...	18/05/2021	Active	10076500
10076501	LUMINATOR HOLDING L.P.d/b/a Luminator Aerospace		FAA STC SR09919AC	SEE FAA AML	Installation of a Luminator search light LS-400, LS-400M, or LS-400T	The Certification Basis for the original product remains applicable tothis certificate/ approval. The requirements for environmental protectionand the associated certified noise and/ or emissions levels of theoriginal product are unchanged and remain applicable to thiscertificate/ approval.	Installation Instructions and Instructions for Continued Airworthinessper the attached Approved Model List Initial Release dated 06/01/2021.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC requires that Luminator or Aeronautical Access...	23/06/2021	Active	10076501
10076506	SABENA TECHNICS BGC			737-900/-900ER/-8/-9 737-600/-700/-800/-800BCF	Mounting device and power supply connection for portable EFB with PIVOTcases in cockpit of BOEING 737	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment: CS-25 at amendment12 paragraphs: 1, 29, 301, 303, 305, 307, 321, 337, 341, 561, 562, 571,601, 603, 605, 609, 613, 619,8...	- Master Data List, Ref. 10003-01-A-MDL-R00 dated 17 May 2021-Airplane Flight Manual Supplement, Ref. 10003-01-A-AFMS-F01-R00 dated11 May 2021,Ref. 10003-01-A-AFMS-F02-R00 dated 11 May 2021- Instructions for continued airworthiness, Ref.10003-01-A-ICA-F01-R00-Installation dated 12 May 2021,Ref. 100...	Limitations as per Section 1 of Airplane Flight Manual Supplementsdocument referenced above.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect u...	19/05/2021	Active	10076506

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076509	PILATUS BUSINESS AIRCRAFT, Ltd.		FAA STC SA00931DE	PC-12/47E	Airtext/Airtext + system installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00931DE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Drawing List for Airtext in a Pilatus PC-12/47E, 2E-1802-01-0000,Revision C, dated 18 December 2018 or later Federal AviationAdministration approved revisions.Instructions for Continued Airworthiness, Airtext, 2E-1802-64-0000,Revision A, dated 12 October 2018NEW-PAGEor later FAA accepted revi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/05/2021	Active	10076509
10076513	WORTHINGTON AVIATION, LLC		FAA SA04497CH	208B 208	Installation of cabin utility seats	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Worthington Aviation Inc. Drawing List 22-0208-IDL, Revision 0, dated 05June 2020Airplane Flight Manual Supplement, 22-0208-IFMS, Revision 0, dated 24November 2020Instructions forContinued Airworthiness, Manual 22-0208-IM, Revision 0,dated 05 June 2020or later revisions of the above listed document...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/05/2021	Active	10076513
10076516	ARCHEION HOLDINGS, L.L.C.	REV. 1	FAA STC ST04164AT	777F 777-300, -300ER 777-200, -200LR	Installation of Avionica satLINK MAX with optional Personality Module(avPM) in the Cabin Compartment overhead, and optional avRDC MAX QAR inthe EE Bay to provide 2 Iridium SATCOM ATS Voice channels, 1 IridiumSATCOM ATS Datalink FANS 1/A+ Data channel for Flight Deck use (CPDLC atRCP240 & ADS-C at RS...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS25 amdt 26: 25.21 (a)(1),25.301, 25.303, 25.305(a)(b), 25.307(a), 25.561(c)(d), 25.571(a)(b),25.581, 25.601, 25.603, 25.6...	1. FAA approved Airplane Flight Manual Supplement for Archeion HoldingsLLC, 130710-AFMS, Revision A, dated 19 November 2018, or later FAAapproved revisions.2. For maintenance and inspections, apply the following ArcheionHoldings Instructions for Continued Airworthiness, or later FAA approvedrevision...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/07/2021	Active	10076516
10076527	PILATUS BUSINESS AIRCRAFT, Ltd.		FAA STC SA01036DE	PC-12/47E	Avance L3 system installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01036DE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Document List for Avance L3 in a PC-12/47E, 2E-1803-01-0000,Revision B, dated 13 July 2020, or later FAA approved revisions.Flight Manual Supplement, for the Installation of the Avance L3 Systemfor the PC-12/47E, Document No. 2E-1803-65-0000, Rev -, dated 16 July2020, or later FAA approved re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/05/2021	Active	10076527
10076528	JET AVIATION AG	REV. 2		737-8	VVIP Cabin Interior CompletionInitial: Introduction of a new VVIP cabin interior as a so-calledbaseline configuration for private operation.Rev. 1: Introduction of a derivate VVIPcabin interior configuration (variant 2) for private and commercial operation. Removal of three (3)ottomans from the fami...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:CS-25 Amdt. 21 with reversions/exceptions as noted:25.23, 25.25, 25.27, 25.29, 25.251, 25.301, 25.302, 25.303,...	VIP Cabin Interior – Baseline Configuration:Aircraft FlightManual Supplement JBSC-M-00156AFM-01, Issue 04Instructions for Continued Airworthiness JBSC-M-00156ICA-01, Issue 04Airworthiness Maintenance Tasks (ALS) JBSC-M-00156AMT-01, Issue 02Master Minimum Equipment List Supplement JBSC-M-00156MEL-01...	VIP Cabin Interior – Baseline Configuration:Private Operation (Not-for-Hire, Non-Commercial).Non-smoking aircraft.An approved exterior paint livery matching the exit configurationof thecabin considering the deactivated exits must be applied. Changes to theexterior exit marking must be approved.VVIP...	16/07/2025	Active	10076528

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076533	S-TEC CORPORATION		FAA SA09764DS	PA-60-602P (AEROSTAR 602P) PA-60-601P (AEROSTAR 601P) PA-60-601 (AEROSTAR 601) PA-60-600 (AEROSTAR 600)	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09764DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Data List ST-984-MDL-0001, Revision A, dated 30 March 2021Airplane Flight Manual Supplement ST-984-AFMS-0001, Rev. -, dated 31March 2021Instructions for Continued Airworthiness ST-984-ICA-0001, Rev. -, dated09 March 2021or later revisions of the above listed document(s) approved/ accepted onbe...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/05/2021	Active	10076533
10076534	DASSAULT FALCON JET CORPORATION		FAA STC ST10640SC-D	SEE FAA APPROVED MODEL LIST	Installation of Aux Galley/Entertainment Center Structural Installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST10640SC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Data List Report No. F00-01009 Revision AF dated 19 January 2011, orlater FAA approved revision.2. For Aux Galley/ Entertainment Center Structural Installation F2000EXand F900EXRequirements use Report 38165, Revision NC, dated 28 November2007.3. Maintenance Manual Supplement, Report 37912, revisi...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List ST10640SC-D, Report No. 40686,Rev. NC<(>,<)> dated 19 January 2011.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyp...	25/05/2021	Active	10076534
10076538	LEARJET Inc.		FAA STC ST00428DE-D	CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT)	Installation of a Honeywell TCZ-9 10 TCAS II processor withchange 7software	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00428DE-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	Learjet Inc. Master Document List BAS63010073, Revision (-), dated 31August 2000, FAA approved 31 August 2000, or laterapproved revision.Any Instructions for Continued Airworthiness documented in STC SA1677GLremains a requirement for modification by MDL BAS630 10073-1configuration of this STC.Any I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The FAA STCs SA1677GL, SA985NE, SA6014NM and ST00069WIv...	10/06/2021	Active	10076538
10076539	SABENA TECHNICS BGC	REV. 1		A321-271NY A321-271NX/-272NX A321-271N/-272N A321-253NY A321-251NX/-252NX/-253NX A321-251N/-252N/-253N A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N/-171N/-173N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	“FLEX” Pivot Tablet Support Provision & Power supply installationRev 1: applicability list extended to new Model ModelsA321-253NY/A321-271NY (A321XLR) and to Variant A319-173N. Certification basis includes now Special Condition M-TS-0000419.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): M-TS-0000419 issue 02 "Mitigation of flight deckfires originating from lithium batteries that are not part of theaircraft design"the fol...	Master Data List, Ref. 10000-01-A-MDL-R05 dated 16 May 2025Aircraft Flight Manual Supplement – EFB Mechanical Support, Ref.10000-01-A-AFMS-F01-R01 dated 03 March 2025Aircraft Flight Manual Supplement – USB Power Supply, Ref.10000-01-A-AFMS-F02-R03 dated 03 March 2025Instructions for Continued Airwor...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/05/2025	Active	10076539

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076556	AVIATION TECH ASSOCIATES LLC		FAA STC SR02601LA	EC 130 B4, EC 130 T2	Installation of Landing Gear Sleeve	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List ATA-130-110, Revision "C", dated 5 August 2016Aviation Tech Associates Instructions for Continued Airworthiness (ICA)document ATA-109, Revision 2, dated 30 July 2016or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Techni...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/08/2021	Active	10076556
10076562	LEARJET Inc.		FAA SA8061NM-D	CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT)	Installation of a MagnaStar C2000 Digital Airborne Telephone system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	DAS Approved Master Document List No. CA-1067-TUC, Revision(B), dated26 October 1995< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/05/2021	Active	10076562
10076571	MT-PROPELLER ENTWICKLUNG GmbH			PA-E23-250 PA-23-250 PA-23-235, PA-23-250 PA-23-235	Installation of MTV-12-( ) propeller on Piper PA-23-235, PA-23-250andPA-E23-250 aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 36 Amdt 5, FAR36-31.This certificate/ approval involves achange with an impact on the noisedatabase and/ or emission l...	- According to MT-Propeller Master Documentation List No. E-3317 Rev. 0- To be operated in accordance with MT-PropellerAFM-S Document No.E-3314 Rev. 0- To be installed i.a.w. Installation Instruction Doc. No. E-3315 Rev. 0- To be maintained i.a.w. MT-Propeller ICA Document No. E-3316 Rev. 0or later...	According limitation section of AFM-S.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product	28/05/2021	Active	10076571
10076572	MT-PROPELLER ENTWICKLUNG GmbH			PA-34-200 (SENECA)	Installation of MTV-12-B-C-F/CF(L) 183-59( ) Propeller onPA-34-200(Seneca)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 36 Amdt 5; FAR36-31.This certificate/ approval involves achange with an impact on the noisedatabase and/ or emission l...	- According to MT-Propeller Master Documentation List No. E-3549 Rev. 0- To be operated in accordance with MT-PropellerAFM-S Document No.E-3551 Rev. 0- To be installed i.a.w. Installation Instruction Doc. No. E-3552 Rev. 0- To be maintained i.a.w. MT-Propeller ICA Document No. E-3553 Rev. 0or later...	According limitation section of AFM-S.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/05/2021	Active	10076572
10076577	ENGINEERING CONCEPTION MAINTENANCEd/ b/a E.C.M			747-400	Stowage quick change B747-400Removal of passenger seat frommain deck (zones C, D and E), andinstallation of central and lateral under bin stowages	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): D-01 “Underbin Stowage Installation”.The requirements for environmental protection andthe associatedcertified noise and/ or emissions levels of th...	Master Drawing List Report B191-MDL001 Revision AMaster Data List Report B191-MDAL01 Revision CAFM Supplement Report B191-AFMS01 Revision CFAM Supplement Report B191-FAMS01 Revision BUBS Content Checklist Report B191-CKLIST Revision Bor later revisions of the above listed document(s) approved/ accept...	Limited to B747-400 MSN 25629, Tail number CN-RGAAs per applicable AFM Supplement.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the ai...	28/05/2021	Active	10076577

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076603	GARMIN INTERNATIONAL, Inc.		FAA SA01933WI	EMB-505 EMB-500	Installation of Garmin G1000 NXi Integrated Avionics SystemHardware andSoftware Updates, excludingFlight Stream 510.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	EMB-500Installation in accordance with Garmin Master Drawing List (MDL) Number005-01385-00, Revision 1,dated 10/29/2019Operate in accordance with Garmin Airplane Flight Manual Supplement190-02545-01, Rev 1,dated 10/29/2019Maintain in accordance with Garmin Instructions for ContinuedAirworthiness 190...	Installation and use of Garmin Flight Stream 510 is not covered by thisapproval.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changeand/ or repair will introduce no adverseeffect upon the airw...	02/06/2021	Active	10076603
10076604	AEROLITE AG			CL-600-2B16 (604 VARIANT)	EMS EquipmentInstallation of several air ambulance medical equipment provisions	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- According to Aerolite Master Document List No. MDL-21-004Rev. NC- To be operated in accordance with Aerolite AFM-S Document No.FMS-650-0212923-502 Rev. 0- To be installed i.a.w. Aerolite Installation Instruction Doc. No.IM-21-001 Rev. 0- To be maintained i.a.w. Aerolite ICA Document No. OPM-650-0...	Limited to MSN 5518.Limitations iaw. section 2 of FMS-650-0212923-502.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness...	02/06/2021	Active	10076604
10076614	S4A SOLUTIONS FOR AVIATION, S.L			CL-600-2B16 (604 VARIANT)	Provisions for Antenna Installation in CL604	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed in accordance with Service Bulletin ref: 604118-12-19 edition1 dated 12-03-2021, maintained in accordance with Maintenance ManualSupplement ref: 604118-12-30 edition 3 dated 26-05-2021.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This design change only covers the mechanical provisions for theinstallation of the antennaPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect up...	06/06/2021	Active	10076614
10076616	ST ENGINEERING AEROSPACE LTD.	REV. 2		A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216	CS-CCD complianceCargo-Lite Solution for A320-200 AircraftCabin reconfiguration to transport cargo in the passenger cabinRev. 1: Replacement of existing 4 portable oxygen cylinder/ maskassembly with portable oxygen bottle and full face smoke mask & removalof the 3 months limitation.Rev. 2: Complianc...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): CRI D-130 Transportation of cargo in passengercompartmentsThe requirements for environmental protection and the associatedcertified noise and/ or emissions...	- 376/QAD/003 Rev B : Certification Programme for Carriage of Cargo inPassenger Cabin for A320 Aircraft.- 376/AED/ FR001Rev: B : Fire Risk Assessment for Transportation ofCargo inpassenger compartments.- 376/AED/ ICA001 Rev B: Instructionsfor Continued Airworthiness (ICA) &Master Minimum EquipmentC...	In accordance with the Deviation D-130 and due to the type of portableoxygen equipment masks, this STC is limited to 2 000 FH followinginstallation of the change or to July 31st 2022, whichever occurs first.Prior to installation of this change/repair it must be determined thatthe interrelationship b...	02/09/2021	Active	10076616
10076617	AEROSERVIS, S.R.O.			L 410 UVP-E20 CARGO L 410 UVP-E20 L-410 UVP-E	ADS-B Out ImplementationADS-B Out Implementation for L-410 aircraft currently equipped withHoneywell MST-67A transponder.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CRI A-01, Issue 1, Rev.2, dated 10-MAY-2021The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product...	- Master Document List, Doc. AE 184 000 X, Rev. E, dated 25.5.2021- Certification Program, Doc. AE 184 016P, Rev. I, dated 21.5.2021- Definition document, Doc. AE 184 001P, Rev. H, dated 02.06.2020- L-410 UVP-E Flight Manual Supplement, Doc. STC AE/184-DLP1, August18/20- L-410 UVP-E20 Flight Manual1...	This STC is not applicable to the aircraft equipped with anautopilot.	06/06/2021	Active	10076617

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076625	EXPERT GEOPHYSICS LTD		TCCA SH18-39	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Geophysics Equipment (Rad-alt and GPS antenna) Installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Drawing List MDL18011, Revision B, dated October 24,20218Instructions for Continued Airworthiness ICA18011-1, Revision A, datedSeptember 21, 2018.Flight Manual Supplement FMS18011-1, Revision A, dated October 24, 2018or later revisions of the above listed document (s) approved/accepted onbehal...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/06/2021	Active	10076625
10076627	LEARJET Inc.		FAA STC ST00099WI	CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT)	Installation of Entertainment Cabinet	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00099WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Precision Pattern Drawing Number CA-1035-TUC stamped "FAA approved" witha date of 29 December 1993, or later.	This approval is for installation of structural provisions only. Theinstallation of electrical, plumbing and ECS components must beseparately approved.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	08/06/2021	Active	10076627
10076628	LEARJET Inc.		FAA STC ST00050WI	CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT)	Installation of a bulkhead across fuselage station 542 witha hingedswinging door, a lavatory with a sinkand a toilet on the right hand side.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00050WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Precision Pattern Drawing Number CA-1012-TUC stamped "FAA Approved" witha date of 15 March 1993, or later.	This approval is for installation of structural provisions only.The installation of the electrical, plumbing and ECS components must beseparately approved.Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously in...	08/06/2021	Active	10076628
10076629	AERO DYNAMIX, Inc.		FAA SR09350RC	407	Installation of Night Vision Imaging System (NVIS) / Night Vision Goggle (NVG) compatible lighting system.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Instruction for Continued Airworthiness (ICA) Doc ICA B407-01 Rev. BNdated 10 January 2014Master Drawing List MDL 2441-01 Rev. FU dated 22 July 2020EASA Flight manual Supplement RFMSA B407-03-EASA-03 Rev.IR dated 10 May2021or later revisions of the above listed document(s) approved/ accepted onbehalf...	Minimum crew is dual pilot for NVIS flights on unimproved lightingsites.Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, a...	08/06/2021	Active	10076629
10076630	LEARJET Inc.		FAA STC ST00047WI	CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT)	Installation of a bulkhead across fuselage station 353 witha hingedswinging door and magazine racks.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00047WI.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Precision Pattern Drawing Number CA-1021-TUC stamped "FAA Approved" witha date of 15 March 1993<(>,<)>or later.	This approval is for installation of structural provisions only.The installation of the electrical, plumbing and ECS components must beseparately approved.Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously in...	08/06/2021	Active	10076630
10076631	LEARJET Inc.		FAA STC ST00568AT	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT)	Installation Corporate Interior Cabinets	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00568AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Learjet Top Drawing "Arrangement Interior Cabinets", Dwg No. TM313173,Revision B, dated 5 August 1994, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/06/2021	Active	10076631

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076635	BOEING IRELAND LIMITED			737-8	B737-8 Zero Pax to 189Y ReconfigurationThree new aircraft delivered with Zero PAX occupancy. Modificationconsists of installation of Y-class Recaro seats to create a 189Ypassengerseating layout, removal of the “Zero Occupancy” placard,reconfiguration of the existing PSUs and rework of no smoking PS...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Change / Repair Approval, ‘737-8 Zero Pax to 189Y Reconfiguration’,BIL-00130 -APP, Revision 01,dated 2nd June 2021<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/06/2021	Active	10076635
10076636	AMAC AEROSPACE SWITZERLAND AG	REV. 1		737-900ER 737-900 737-9 737-800 737-8 737-700	WLAN ActivationThis Modification activates the Wireless Local Area Network (WLAN)Function of a preinstalled WLAN system(Router interfaced with WAPs inthe cabin emitting in 2.4GHzand/or 5GHz Frequency Band and a cockpitWLAN ON/OFF switch).Revision 1 of this STC is issued to include the Configuratio...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: For the 737-700,737-800, 737-900, 737-900ER, 737-8 the following paragraphs of CS-25Amendment 12 are applicab...	Configuration 1:The Change is defined with Revision B of Master Data List documentMDL-B7372-1-4430.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplement document AFMS-B7372-1-4430.Configuratio n 2:The Change is defined with Revision A of Master Data List doc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/05/2023	Active	10076636
10076638	LEARJET Inc.		FAA STC ST00100WI	CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT)	Installation of bulkhead	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00100WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Precision Pattern Drawing Number CA-1036-TUC stamped "FAA Approved" witha date of 29 September 1993, or later.	This approval is for installation of structural provisions only. Theinstallation of electrical, plumbing and ECS components must beseparately approved.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	09/06/2021	Active	10076638
10076639	LEARJET Inc.		FAA STC ST00101WI	CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT)	Installation of galley assembly	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST00101WI.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Precision Pattern Drawing Number CA-1037-TUC stamped "FAA Approved" witha date of 29 September 1993, or later.	This approval is for installation of structural provisions only. Theinstallation of electrical, plumbing and ECS components must beseparately approved.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	10/06/2021	Active	10076639
10076666	S4A SOLUTIONS FOR AVIATION, S.L			P2006T	Additional gear alert system installation to inform the pilot aboutlanding gear deployment.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List, S4A Solutions for Aviation document No.P2006T12-18-02, Edition--, dated 11 June 2021Flight ManualSupplement, S4A Solutions for Aviation document No.P2006T12-12-28, Edition 01, dated 21 August 2020Maintenance Manual Supplement, S4A Solutions for Aviation document No.P2006T12-12...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/06/2021	Active	10076666
10076697	NORTHWEST AEROSPACE TECHNOLOGIESI NC.	REV. 1		A330-302 A330-202	Reconfiguration of the passenger cabin for transporting cargo on IberiaA330 aircraft.Rev 1: MMEL supplement updated. Calendar limitation updated as follows:‘Aircraft modified under this STC Project can be operated in thecargo-in-cabin configuration for a maximum of 2000 flight hours or until31-July-...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): D-130 Cargo transport in passenger cabinThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the prod...	Certification Summary, N0689-D90, Revision A, dated 26 July2021AFM Supplement, N0689-D85, Revision C, dated 27 May 2021ICA, N0689-D70, Revision B, dated 17 May 2021MMEL Supplement, N0689-D86, Revision F, dated 22 July 2021or later revisions of the above listed document(s) approved/ acceptedunder the...	Aircraft modified under this STC Project can be operated inthecargo-in-cabin configuration for a maximum of 2000 flight hours or until31-July-2022, whatever occurs first.Prior toinstallation of this change/repair it must be determined thatthe interrelationship between this change/repair and any ot...	30/07/2021	Active	10076697

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076718	SABENA TECHNICS BGC	REV. 1		ATR 72-212, ATR 72-212 A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Mounting device and power supply connection for PIVOT portable EFBsolutions in cockpit of ATR42/ ATR72.Rev. 1 adds missing requirements in the Certification Basis (missingrequirements) and updates the MDL issue number.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4 paragraphs: 1, 29, 301, 303, 305, 307, 321, 337,341, 561, 571, 601, 603, 605, 607, 609, 611, 613, 62...	- Master Data List, Ref. 10002-01-A-MDL-R01, dated 18 June 2021;- Instructions for Continued Airworthiness, Ref. 10002-01-A-ICA-R00,dated 10 June 2021;- Airplane Flight Manual Supplement, Ref. 10002-01-A-AFMS-R01, dated 11June 2021;- Master Minimum Equipment List Supplement, Ref. 10002-01-A-MMELS-R0...	Limitations as per §3 of Airplane Flight Manual Supplement documentreferenced above.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	22/06/2021	Active	10076718
10076728	BOEING IRELAND LIMITED			787-9	Installation of Business Class Mini-Suites	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Programme ref. BIL-00103-CP Revision 04Declaration of Compliance ref. BIL-00103-APP Revision 00 dated18.06.2021Aircraft Flight Manual Supplement ref. BIL-00103-AFM01Revision 02Instructions for Continued Airworthiness ref. BIL-00103-ICA01 Revision00or later revisions of the above liste...	At time of approval of this change to type certificate, theapproval ofaffected parts of Operational Suitability Data (OSD) were still pendingfor the following OSD constituents:Cabin Crew DataThe corresponding changes to OSD need to be provided before the OSD mustactually be used.	21/06/2021	Active	10076728
10076730	EIRTECH AVIATION SERVICES LIMITED			737-900ER 737-900 737-9 737-8200 737-800 737-8	Installation of ELT's on B737Installation of a Survival andAutomatic Fixed ELT within the passengercabin.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 Amendment 22,CS-MMEL Initial IssueThe requirements for environmental protection and the associatedcertified noise an...	Flight Manual Supplement FMS/1329-001 Issue 2Master Document List MDL/1329-001 Issue 3Master Minimum List Supplement MMELS/ 1329-001 Issue 1OSD Flight Crew Data Supplement FCDS-1329-001 Issue 3or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	STC 10076127 Installation of Fixed ELT structure provisionsand FixedELT External Antenna is a concurrent requirement for this STC on Model737-8200.Prior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed...	22/06/2021	Active	10076730
10076735	APTOZ EHF.	REV. 1		777-300, 777-300ER 777-200, 777-200LR	Conversion of main cabin to cargo AreaThis change converts the main passenger cabin to cargo area afterremoval of cabinarrangements.REV. 1 of this STC approval extends the calendar limitation to July 31st2022The referenced documents have been updated accordingly	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): CRI D-01 “Transportation of cargo in passengercompartments”The requirements for environmental protection and the associatedcertified noise and/ or emissions...	Airplane Flight Manual Supplement document number: AFM251171-1 at issueG dated October 4th, 2021Master Data List document number: MDL251171 at issue K dated October4th, 2021Instruction for Continued Airworthiness document number: ICA251171-1 atissue F dated October 4th, 2021Declaration of Compliance...	Operations with this STC installed are limited to 2 000 FH (followingissuance of the STC) or to July 31st 2022, whatever occurs first.Cabin Crew: Aeroplanes modified per this STC are considered to be a“variant” to the B777-200/-200LR/-300/-300ER passenger configurations.Cabin crew operating aeroplan...	26/10/2021	Active	10076735
10076741	CAVOK			208B 208	Provisions for Cessna 208 cabin layouts for special missions	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Dossier de Certification document 208-061-CTF-005 Issue E, dated22.06.2021Master Drawing 208-061-000-00 Issue B, dated February 24, 2021Supplement to Pilot Operations Handbook 208-061-HBK-003 Issue E, dated16.06.2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA s...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/06/2021	Active	10076741

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076742	ZIM AIRCRAFT SEATING GMBH			A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	STC for EC1 A330 Air CaraibesNew plastic materials for backrest shells and kick panels. The designchange covers spare parts to ensure continued airworthiness of thedelivered seats.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:EASA CertificationSpecification paragraphs 25.23, 25.25, 25.27, 25.561, 25.562, 25.625,25.785, 25.789, 25.853, 25.1301 a...	ZIM Aircraft Seating Master Document List 505705-MDL-001<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Pre-requisite for embodiment of this design change is a cabinconfiguration approved by EASA STC 10062195 or STC 10063950 or STC10063950 or STC 10065695 or STC 10066025.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any other...	23/06/2021	Active	10076742
10076748	GULFSTREAM AEROSPACE CORPORATION		FAA ST03117AT-D	GIV-X	Installation of Iridium Satellite Telephone System	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	GC41203K013, Rev. A, dated April 28, 2021EASA Validation SummaryCompliance Report – GIV-X Iridium Satellite Telephone SystemGC412038001 Index ListGC41203M000 (Rev -), dated September 23 2005, Airplane Flight ManualSupplementGC4120 3A001 (Rev -), dated September 23 2005, Instructions for ContinuedAirw...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/06/2021	Active	10076748
10076750	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA ST02047SE	777-300ER	Installation of a new seats and In Flight Entertainment system.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Northwest Aerospace Technologies, Inc. (NAT) Master DrawingList (MDL) N0339-D10, Rev D, dated 22 January 2010 or later Federal AviationAdministration (FAA) approved revisions.	Concurrent installation of Lufthansa Technik STC 10014897 (formerlyEASA.A.S. 03127), photo luminescent Emergency Escape Path Lighting (EEPL)system installation, is required for theinstallation of this STC.This modification may not be installed after 30 August 2010 unless:1. Previously approved Elect...	06/07/2021	Active	10076750
10076757	PILATUS BUSINESS AIRCRAFT, Ltd.	REV. 1	FAA SA03469AT	PC-12, PC-12/45, PC-12/47 PC-12/47E	Installation of an Equipment Console, Model AEC 1100, in the passengercabin interiorRev. 1 corrects the FAA STC number.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Drawing List No. BR-96002, Revision C, dated 24 July2018Instructions for Continued Airworthiness, No. BR-96003,dated 10September 2018or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bil...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/07/2021	Active	10076757
10076760	AVIATION SPECIALTIES UNLIMITED, INC	REV. 2	FAA SR02512SE	EC 225 LP AS 332 L, AS 332 L1	EASA validation of the Night Vision Imaging Systems (NVIS) FAASupplemental Type Certificate (STC) ref. SR02512SE date amended February12, 2024Initial revision: STC applicable to EC 225 LP modelRevision 1: AS 332 L model incorporatedRevision 2: AS 332 L1 model incorporated, document dates corrected,a...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Initial Revision: - Project Specific Certification Plan (PSCP) ref. ASU-PSCP-225-2716Revision C, dated May 04, 2021 - Rotorcraft Flight Manual (RFM) Supplement ref. FMS-332004-6Revision B, dated May 17, 2021 and approved by the FAA on June 21, 2021 - Instructions for Continued Airworthiness...	Initial Revision: Design change applicability limited to EC225 LPhelicopters with a configuration described in the ICA-332004-4Appendices for S/N 2716, Revision B, dated June 14, 2021, supplementingthe ICA document ref. ICA-332004-4 Revision A, dated March 24, 2017.Revision 1: Design change applicab...	22/05/2025	Active	10076760

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076761	LIBERTY PARTNERS, INC.		FAA STC SR09921AC	SEE FAA APPROVED MODEL LIST	Demonstration of aircraft critical equipment and antenna systemstolerance of radio frequency interference (RFI) from intentional orspurious transmissions from certain Portable Electronic Devices (PEDs)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR09921AC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data list LP2923-DL001, revision IR, dated 15 January 2021;2. One of the following Rotorcraft Flight Manual Supplements (RFMS) isrequired as defined in the master data list:- LP2923-FM001 Revision IR, dated 1 February 2021;- LP2923-FM002 Revision IR, dated 1 February 2021;- LP2923-FM003 Re...	This STC does not constitute installation approval of a wireless radiofrequency system using wireless data technologies. It only provides datathat may partially support its installation or its activation.This STC is valid for aircraft types and models approved by EASA andlisted on the FAA Approved M...	06/08/2021	Active	10076761
10076768	LIBERTY PARTNERS, INC.		FAA STC SA11158SC	SEE FAA APPROVED MODEL LIST	Demonstration of aircraft critical equipment and antenna systemstolerance of Radio Frequency Interference (RFI) from intentional orspurious transmission from certain Portable Electronic Devices (PEDs)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA11158SC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List LP23-DL001, Revision B, dated 19 May2017, orlater approved FAA Revision.2. Airplane Flight Manual Supplements<(>,<)> documents- LP23-FM001 Revision B;- LP23-FM002 Revision IR;- LP23-FM003 Revision IR;- LP23-FM011 Revision IR;- LP23-FM012 Revision IR;- LP23-FM013 Revision IR;d...	This STC does not constitute installation approval of a wireless RadioFrequency System using wireless data technologies. It only provides datathat may partially support its installation or its activation.This STC is valid for aircraft types and models approved by EASA andlisted on the FAA Approved M...	29/06/2021	Active	10076768
10076770	S4A SOLUTIONS FOR AVIATION, S.L			BD-700-1A10	CREW REST SEAT LIMITATIONS CHANGE BD700The STC consists in cabin and Aircraft Flight Manual changes required toallow passengers to occupy the crew rest seat.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:25.1, 25.301, 25.303,25.305, 25.307, 25.321, 25.337, 25.471, 25.561, 25.562, 25.601, 25.603,25.605, 25.609, 25.611, 25.6...	GEX55-RPT02 Master document list Ed4GEX55-HDK01 Flight manual supplement Ed03or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	29/06/2021	Active	10076770
10076776	UAB "FL TECHNICS"	REV. 1		737-800	Cargo on passenger cabin floorThis change introduces capability for carrying additional cargo inpassenger cabin on Boeing 737 aircraft, removing passenger seats.Rev. 1: Limitations updated to allow operation until 2000 FH afterinstallationof the STC, or 31 July 2022, whichever occurs first	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): D-101, Issue 2 – Transportation of cargo in passengercompartments.- The following paragraph(s) at a later amendment: CS 25.1443 (a)(b)(e) amdt 26.The requi...	MDL-527-01 Issue K – Master Data ListPA-527-03 issue H – Aircraft Flight Manual SupplementPA-527-04 issue G – Flight Attendant Manual SupplementCRB-527-01 Issue G – Change/Repair Bulletinor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Operations with this STC installed are limited to 2 000 Flight Hoursfollowing installation of this STC, or to 31 July2022, whatever occursfirst.- Aeroplanes modified per this STC are considered to be a “variant” tothe B737-800 passengerconfiguration. Cabin crew operating aeroplanesmodified per t...	07/12/2021	Active	10076776
10076786	SIRIUM AEROTECH S.L.			GV-SP GV GIV-X GIV	Activation ADS-B OUT Functions for Gulfstream GIV/GV	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: EASA CS-ACNS Subpart D,Section 4The requirements for environmental protection and the associatedcertified noise and/ or em...	SA20-63S-MDL Rev 02, SA20-63S-AFMS Rev01, SA20-63S-AMMS Rev01,SA20-63S-MMELS Rev01Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Aircraft must be equipped with TDR-94D Transponders P/N 622-9210-501,GPS Freeflight 1203C P/N 84327-50-XXXX and provisions for ADS-Binstalled as per previous Sirium Aerotech Mod ADSB-GIV-01 or ModADSB-GV-01	30/06/2021	Active	10076786

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076797	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02602SE	A320-214	Installation of seats, monuments and ISPS.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:JAR 25 change 13: 25.561, 25.562(a)(b)(c)CS 25 amdt. 0: 25.853(a)(c)(d)(e)(f), 25.869(a)(1)(4)The requirements for environm...	Master Drawing List (MDL) N0618-D10, Revision MInstructionsfor Continued Airworthiness N0618-D70, Revision Cor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	- installations 618NT000-1 through -45 require prior or concurrentinstallation of the STC 10058645 (FAA STC ST03848NY)and STC 10054304(FAA STC ST03198NY) - installation of 618NT001-1 requires concurrent installation of STC10075233 (FAA STC ST04414CH)Prior to installation of this change/repair it m...	01/07/2021	Active	10076797
10076800	SIRIUM AEROTECH S.L.			A310-304/-308/-322/-324/-325 A310-203/-203 C/-204/-221/-222 A300 F4-203/-605 R/-622 R A300 C4-605 R VARIANT F A300 C4-203/-620 A300 B4-605 R/-620/-622/-622 R A300 B4-220/-2C/-601/-603 A300 B4-102/-103/-120/-203 A300 B2K-3C A300 B2-202/-203/-320 A300 B2-1A, A300 B2-1C	Installation of Iridium DLU system and interface with existing Datalinkequipment for FANS 1/A+	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	SA21-26S-MDL Rev 01, SA21-26S-AFMS Rev 01, SA21-26S-AMMS Rev 01,SA21-26S-MMELS Rev 00<(>,<)>Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The STC TCCA SA13-75 must be validated by EASA in order to allow theaircraft with the installation covered by this STC to be registered inthe EU.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed ch...	01/07/2021	Active	10076800
10076801	DOA AESGLOBAL LIMITED	REV. 2		A321-271N/-272N/-271NX/-272NX A321-251NX/-252NX/-253NX A321-251N/-252N/-253N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-273N A320-272N A320-271N/-272N/-273N A320-271N A320-253N A320-252N A320-251N/-252N/-253N A320-251N A320-233 A320-232 A320-231/-232/-233 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211/-212/-214/-215/-216 A320-211 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-112	ACTIVATION OF BLUEBOX WIFI SYSTEM.Rev. 1: applicability list extended toA319-111/-113/-114/-115/-131/-132/-133/-151N/-153N/-171N.Rev. 2: applicability list extended to A321-111/-112/-131/-211/-212/-213/-231/-232/-251N/-251NX/-252N/-252NX/-253N/-253NX/-271N/-271NX/-272N/-272NX.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-25 Amdt. 23,Sections 25.1, 25.561, 25.601, 25.603, 25.605, 25.611, 25.787, 25.789,25.831, 25.853, 25.869,2...	For models A320-211/-212/-214/-215/-216/-231/-232/-233/-251N/-252N/-253N/-271N/-272N/-273N:AES-320-5778MDL Issue 12, AFM Supplement No. 91 Issue 3, AES-TR-2724(ICA) Issue 4, OSD Supplement No. 44 Issue 1, CCOM Supplement No. 45Issue 3.For modelsA319-111/-112/-113/-114/-115/-131/-132/-133/-151N/-153N...	Prior to installation of this change aircraft configurationmust complywith concurrent requirements defined in section 5.1 of Master Data ListAES-320-5778MDL.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	02/09/2024	Active	10076801

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076808	AMAC AEROSPACE SWITZERLAND AG	REV. 1		A320-251N	Interior OutfittingThe change consists of a complete cabin interior outfitting of theA320-251N with 34 passengers VIP and 5 cabin crew seats for private useonlyRev. 1 adds a Configuration 2 with 22 passengers and 5 cabin crew seatfor private use only.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraphs of CS-25 at Amendment 21 are applicable tothis change: CS25.1, CS25.20, CS25.21, CS25.23, CS25.25, CS25.27,CS25.29, CS25.301, CS25.303, CS25.305...	Configuration 1:The change is defined with Revision B of Master Data List documentMDL-JE01-2500.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplement document AFMS-JE01-2500.The aircraft shall be maintained in accordance with Revision A ofInstructions for C...	Private use only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	15/06/2023	Active	10076808
10076810	ETIHAD AIRWAYS ENGINEERING L.L.C.	REV. 1		A330-343	CABIN RECONFIGURATION FROM 249 TO 335PAXInstallation of additional economy class seats in zones between doors 1and 3 toincrease passenger seating capacity to have 335 economy PAXconfiguration (post-mod configuration “Aircraft A”).Revision1 of this STC introduces a design change to increase passeng...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Etihad Airways Engineering L.L.C. Master Document List EA3-21251420-DL01issue 2Etihad Airways Engineering L.L.C. MasterDocument List EA3-21251420-DL02issue 2.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/02/2022	Active	10076810
10076815	AIRBUS S.A.S.			A321-253NX A321-252NX A321-251NX/-252NX/-253 NX A321-251NX	Airbus Interiors Services MOD AI0104 Cabin Conversion for TITAN/TCS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): ESF CRI D-1101 issue 01.- The following paragraph at JAR25 ch11:25.785, 25.787, 25.789, 25.791, 25.815, 25.817, 25.1351, 25.1357,25.1359, 25.1415,-...	- Modification Approval Sheet ref.: MAS AI0104 issue 01 dated 28 JUN 21- Certification Summary Report ref.: AIS-AJA-19014 issue 03 dated 28 JUN21- Flight Manual Supplement ref.: FM-S MOD AI0104 dated 01 MAY 21- Flight Crew Operating Manualref.: FCOM-S MOD AI0104 dated 29 APR 21- Cabin Crew Operatin...	This STC covers 3 possible configurations: - Titan-TCS 195 PAX - TCS 76 PAX - TCS 64 PAXThis has to be taken into account by subsequent/ concurrent installationson the same aircraft.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairp...	05/07/2021	Active	10076815
10076816	DASSAULT FALCON JET CORPORATION			FALCON 900EX (F900EX)	Avionics and Interior InstallationsAvionics and Interior Installations in accordance with Data List ReportNo. F9EX-07001-D223 Revision C dated September 14, 2009, or later FAAapproved revision	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 25.611 (b); 25.855 (e);25.899(a) (b); 25.1301(a)1,2; 25.1309(e); 25.1310(a),(b); 25.1353(a);25.1357(d),(f); 25.1360(a),(b);...	-MDL F9EX-07001-D223 REV C-AFM Supplement 37159-F9EX-D233 REV Aor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This approval is limited to only the installation made in DassaultAviation Model 900EX Serial No. 223.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adver...	02/07/2021	Active	10076816
10076826	AEROSPACE COMPOSITES GmbH	REV. 1		KODIAK 100	Maritime Patrol Aircraft	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: ICAO Annex 16, V...	Installation according to document “Project Document List”PDL-KOD100-9501-01 Rev.1 dated 21/06/2021Operations accordingto document “Aircraft Flight Manual” (Supplement) AFMS-KOD100-9501-01 Issue 0-1 dated 17/05/2021Maintenance according todocument “Maintenance Manual Supplement”MMS-KOD100-9501-01 I...	- Flight into known icing conditions is prohibited.- Minimum flight crew: when mission system is in operation one pilotrequired in the left cockpit seat and one operator required in thecabin.- Maximum occupant seating limit: 3 (ref. to AFMS-KOD100-9501-01 fordetails).Prior to installation of this ch...	08/10/2025	Active	10076826

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076863	PATRIA AVIATION OY			429	Distance Measuring Equipment (DME) retrofit installation.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Flight Manual Supplement D-429-19-RFM-01 dated 2 July 2021MMEL Document D-429-19-MEL-01 dated 21 June 2021Instructions for Continued Airworthiness D-429-19-ICA-01 dated 18 June2021Configuration Statement D-429-19-CS-02 dated 09 June 2021orlater revisions of the above listed document(s) approved/ acc...	- Patria Minor Change D-429-19-DA-02 Provision for DME Installation isaccomplished.- Two VHF NAV receivers with King-Serial DME tuning interface (GarminGTN 750/650 or equivalent)-ICS system having an available audio input for DME audio (Eagle AudioP139-HD Router or equivalent).- Bell 429 integrated...	06/07/2021	Active	10076863
10076888	HONEYWELL INTERNATIONAL Inc.	REV. 2	FAA STC ST02715SE	SEE FAA APPROVED MODEL LIST	Installation of the Honeywell RDR-7000 Volumetric Buffer Weather RadarSystemRevision 1 is a transfer of certificate from the previous holderAerospace Testing Engineering & Certification Inc. d/b/a Aerotec, Inc.to Honeywell International Inc.Revision 2 adds models Mystère Falcon 900 (MF900) and BD-70...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02715SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Data List;Instructions for Continued Airworthiness (ICA);Aircraft Flight Manual Supplement (AFMS);as listed on the FAA Approved Model List dated 12 April 2022.	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List dated 12 April 2022.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair...	17/05/2022	Active	10076888
10076890	AIRCRAFT SYSTEMS AND MANUFACTURING,Inc.		FAA ST11382DS	A321-213/-231/-232 A321-111/-112/-131/-211/-212	Installation of an Iridium Communication System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25.1, 25.21, 25.23, 25.25, 25.27, 25.29(b), 25.251, 25.301(a)(b),25.303, 25.305(a)(b), 25.307(a),25.356(a)(b), 25.561(a)(b), 25.571(a)(b), 25.581, 25.601, 25.603,25.605...	Master Data List 5753-0000-00, Rev. IR<(>,<)> dated 17 February 2021AFMS Document No. 5753-8007-00, Rev. IR, dated 27 January 2021Instructions for Continued Airworthiness (ICA) Document No. 5753-8006-00, Rev. B, dated 04 November 2020or later revisions of the above listed document(s) approved/accepte...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/07/2021	Active	10076890
10076898	NORTHWEST AEROSPACE TECHNOLOGIESINC.			777-300ER	Cabin reconfiguration of British Airways 777-300ER	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Drawing List, Northwest Aerospace Technologies, Inc.documentN0636-D10, Revision D, dated 28 June 2021Instructions for Continued Airworthiness, Northwest AerospaceTechnologies, Inc. document N0636-D70, Revision -, dated 25 February2021or later revisions of the above listed document(s) approve...	The following approved Service Bulletins shall be concurrentlyinstalled:- Jamco Service Bulletin BA0R7-25-3870 for the modification of Jamcolavatory modules 3F-LC, 3F-RC, 4F-1L, 4F-LC and 4F-RC- Jamco Service Bulletin BAE77-25-3763 for themodification of Jamcogalley system BAE77-11- British Airways...	09/07/2021	Active	10076898
10076899	ROCKWELL COLLINS, Inc.		FAA STC ST01943WI	SEE FAA AML	Modification of Rockwell Collins, Inc. Multi-Mode Receiver (MMR) GlobalLanding System (GLU-2100) Software installation	The Certification Basis (CB) for the original product as amended by thefollowing additional or alternative airworthiness requirements:CS25 amdt 0: 25.1309, 25.1529The requirementsfor environmental protection and the associatedcertified noise and/ or emissions levels of the original product areuncha...	(1) Approved Model List, RCA-0663, Revision(-), issued 17 April 2020(2) Instructions for Continued Airworthiness, RCA-0655, Revision -,dated 2 March 2020 or later FAA approved/accepted revision for items (1)and (2)	(1) Prior installation and approval of Rockwell Collins, Inc. GLU-2100,part number 822-2532-100 is a prerequisite. (2) Approval of this change in type design applies to only the aircraftmodels listed on AML document No. RCA-0663<(>,<)> Rev.(-) or later FAAapproved revisions.(3) Prior to installation...	16/08/2021	Active	10076899
10076900	Q.C.M. DESIGN GmbH			BD-700-1A10	Rockwell Collins Venue RetrofitExisting CES system components performing audio/video signal selectionand distribution, bulkhead displays, Galley Touchscreen display, DVDplayers, audio speakers and amplifiers will be removed and replaced withnew units from Venue system performing same function.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	-Certification Report BBD7-QCM23-014-M Initial issue-ICA BBD7-QCM23-014-M1-ICA Initial issueor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/07/2025	Active	10076900

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076901	GULFSTREAM AEROSPACE CORPORATION	REV. 1		GV-SP GV	Installation of a KA Broadband High Speed Data System, installed onGulfstream model GV & GV-SP (G550) Rev.1: correct typo	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	FAA STC ST04329AT-DGDL100000031 Index List Rev AGDL300001782 Config List Rev BGCD000019368 Rev –, EASA Validated Configuration List - ST04329AT-DCE51303C025 Cert Plan Rev ACE513033041 Summary Compliance Report Rev – CE51303M041 AFMS Rev –CE51303A141 ICA Rev Bor later revisions of the above listed doc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/08/2021	Active	10076901
10076908	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			737-800	737 – Cabin Refurbishment Phase 2This project includes the installation of a windscreen, curtain rail,literature pockets, baby bassinet and a megaphone.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Certification Programme C0256-CEP-02, dated 18th June 2021,section 6,table 20.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/07/2021	Active	10076908
10076911	AVIDYNE CORPORATION		FAA STC SA00401BO	SEE FAA AML	Installation of a SkyTrax 100B/200 ADS-B Receiver 700-00190-100	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00401BO.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Master Document List (MDL) AVMLB-002, Revision 04, dated 21May 2021Instructions for Continued Airworthiness (ICA), Document NumberAVMLB-004, Revision 01, dated 22 April 2021 , orlater FAA acceptedrevision.	This approval is for the installation of the SkyTrax100B/ 200 receiverand associated antenna only. Separate approval of a proven compatiblecockpit display system is necessary in order to use the receivedinformation. There is no AFMS associated with this STC.This approval does not cover the installati...	12/07/2021	Active	10076911
10076913	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA STC ST04339AT-D	SEE FAA AML	Installation of Air Ionizer System on Gulfstream Models: G28O, G-IV,GIV-X, GV, GV-SP and GVI	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04339AT-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	Gulfstream Aerospace FAA Approved Model List (AML) - Air IonizationSystem Installation, SGER-665, Revision (-), dated 19 March 2021 orlater FAA approved revisions.For Gulfstream Aerospace Model G280, Instructions for ContinuedAirworthiness, CED1468A002, Revision (-), dated 10 March 2021 or laterFAAF...	This STC applies to aircraft with smoke detection systems that utilizesphotoelectric method of smokedetection. Additional compliance findings for §§ 25.858(a) are requiredfor aircraft configured with smokedetection systems utilizing any other method of detection exceptphotoelectric method.Prior to i...	15/07/2021	Active	10076913
10076917	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02680SE	A320	ECOS Enlarged Shelf Bin Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25.561 Amdt. 1, CS 25.791 (a)(b)(e) Amdt. 1<(>,<) >CS 25.812(a)(1)(c)(e)(i)(j)(1)(1) (2) Amdt. 3, CS 25.853(a)(d)(e) Amdt....	Northwest Aerospace Technologies, Inc. Master Drawing List N0667-D10Revision D, dated 28 June 2021, or later Federal Aviation Administration (FAA) approved revision.Instructions for Continued Airworthiness (ICA) N0667-D70, Revision A,dated 27 April 2021, or later FAA approved revision.The FAA has app...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/07/2021	Active	10076917

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076922	CESSNA ZURICH CITATION SERVICE CENTGMBH			510	Cargo Trans Platform / passenger cabin	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed in accordance with installation instruction ref: IIS-224 Rev.A, maintained in accordance with Instruction forContinuousAirworthiness ref: ICA-224 Rev. IR, Operated in accordance with AircraftFlight Manual (supplement) ref: FMS-224 Rev. IR.or later revisions of the above listed document (s)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/07/2021	Active	10076922
10076924	KNSI AVIATION ENGINEERING LIMITED	REV. 1	CAA UK RESPONSIBILITY	A330-223	Cabin reconfiguration from a current LOPA of 24 B/C seats and 259 E/Cseats to a post modification configuration of 361 E/C seats.Revision 1 includes the UK STC reference.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	KNSI Master Document List No.19K665-MDL-001 Revision 02KNSIAircraft Maintenance Manual Supplement No. 19K665-AMM001 Revision00KNSI Cabin Crew Data No. 19K665-CCD-001 Revision 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/07/2021	Active	10076924
10076925	LUFTHANSA TECHNIK AG	REV. 2		A330-302 A330-201/-202/-203/-223/-243	Provisional Cargo Compartment.REV. 1: Calendar limitation extended to 31 July 2022REV. 2: Model applicability extended to A330-201/-202/-203/-223/-243with a second configuration	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): DEV D-60076546 'Transportation ofcargo in passengercompartments'.The requirements for environmental protection and the associatedcertified noise and/ ora...	- Supplemental Type Definition Document, Ref. STDD25-20/21M, Issue 03Rev 01 dated 17 Dec 2021For A330-300:- Airplane Flight Manual Supplement, Ref. A-00-21/03-AFM Issue 08 Rev 00dated 24 Nov 2021- Instructions for Continued Airworthiness, Ref. A-00-21/03-ICA Issue 03Rev 00 dated 26 Nov 2021- Cabin C...	The allowance to transport cargo in passenger compartment is limited to2 000 FH following installation of the change orto 31 July 2022,whichever occurs first.Aeroplanes modified per this STC are considered to be a 'variant' to theA330-200/-300 passenger configuration. Cabin crew operating aeroplane...	17/12/2021	Active	10076925
10076932	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST04076NY	A330-941 A330-343 A330-342 A330-341,-342,-343,-941 A330-341 A330-323 A330-322 A330-321,-322,-323 A330-321 A330-303 A330-302 A330-301,-302,-303 A330-301 A330-243F A330-243 A330-223F A330-223,-223F,-243,-243F A330-223 A330-203 A330-202 A330-201,-202,-203 A330-201	Installation of a gogo 2Ku radome/ antenna (with Demod option)Rev. 1: changes the Maximum Take-off Weight (MTOW) for theA330-941weight variants.Rev. 2: This Amended STC certifies the installation or demod forConnectivity Antenna on Airbus A330-200, -300, and -900 model aircraft.The amendment takes i...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-4301-005 "Vibration and buffetingcompliance criteria for large external antenna installation" Issue 2The requirements for envi...	Delta Engineering Master Data List 0154-10622-2465 RevisionQ, dated 18September 2024<(>,<)>Instructions for Continued Airworthiness 0754-10623-2465 Revision I,dated 13 September 2024<(>,<)>Airplane Flight Manual Supplement 0654-10624-2465Revision C<(>,<)>dated 28 April 2021<(>,<)>or later revision...	The activation of the gogo 2Ku antenna is not covered by this approval.This STC cannot be installed on Airbus A330-900 weight variants 920, 921and 922.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	11/11/2024	Active	10076932

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076944	ALITALIA SOCIETA AEREA ITALIANA S.p	REV. 2		777-200, 777-300	Reconfiguration for transport of cargo in the cabinThis project removes cabin seats to allow transportation of cargopallets on passenger floor.REV. 2 of this STC approval extends the calendar limitation to July31st, 2022.The referenced documents have been updated accordingly.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): CRI D-01 “Transportation of cargo in passengercompartments”The requirements for environmental protection and the associatedcertified noise and/ or emissions...	Airplane Flight Manual Supplement, document number: AFMS-DOA-2021-0001 at issue 2 dated December 14th, 2021Master DataList, document number: MDL-DOA-2021-0001 at issue 01 datedDecember 14th 2021Instruction for Continued Airworthiness, document number: 2021-0001-CD-ICA-01 at issue 01 dated DecemberD...	Operations with this STC installed are limited to 2 000 FH (followingissuance of the STC) or to July 31st 2022, whatever occurs first.Cabin Crew: Aeroplanes modified per this STC are considered to be a“variant” to the B777-200/-200LR/-300/-300ER passenger configurations.Cabin crew operating aeroplan...	17/12/2021	Active	10076944
10076950	AEROSPACE DESIGN & COMPLIANCE LLC		FAA ST04206NY	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT)	Installation of Viasat VMT-1500 VR-12C KU Band SATCOM System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04206NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Data List, CL60-MDL-0081, Revision IR, dated 10 March 2021Instructions for Continued Airworthiness (ICA), CL60-ICA-0081, RevisionIR, dated 08 March 2021Airplane Flight Manual Supplement (AFMS), CL60-AFMS-0081, Revision IR,dated 10 March 2021or later revisions of the above listed document(s) a...	This STC requires installation of FAA STC ST00929NY Fin-Mounted Radome.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness...	19/07/2021	Active	10076950
10076951	SABENA TECHNICS BGC	REV. 1		A340-311/-312/-313 A340-211/-212/-213	A340 – Cabin Reconfiguration for the transportation of cargo inpassenger compartmentsRev. 1 updates the Technical Documentation and extends the timelimitation.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): CRI D-130-60076141 Transportationof cargo in passengercompartments- The following paragraph(s) at a later amendment: CS-25 at amendment 4paragraphs: 1, 2...	- Master Data List, Ref. 40696-03-A-MDL-R03 dated 05 Oct 2021- Airplane Flight Manual Supplement, Ref. 40696-03-A-AFMS-R01 dated 05Oct 2021- Instructions for continued airworthiness, Ref. 40696-03-A-ICA-R01dated 05 Oct 2021- OSD Change Document, Ref. 40696-03-A-OSDCD-R00 dated 12 Jul 2021or later re...	Limitations as per §3 of Instructions for Continued Airworthinessdocument and §3 of Airplane Flight Manual Supplement document referencedabove.The allowance to transport cargo inthe passenger cabin compartment islimited to 2 000 FH following installation of the change or to 31 July2022, whatever o...	11/10/2021	Active	10076951
10076952	SABENA TECHNICS BOD			737-800	CHOPIN VIP Cabin	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certific...	Master Document List MDL S-00-4147 issue BMMEL Supplement MMELS-B3038-00-125 issue DAFM Supplement AFMS-B3038-99-509 issue FInstructions for Continued Airworthiness ICA-B3038-00-032 Issue Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- For the design covered by this approval, the following limitationapplies:<< Oxygen Discharge Provisions only. Not certified for use with pressurized Oxygen. >>The installation of the associated placard is done under ModificationMOD-S-00-4321 CHOP 1 MINOR MODIFICATIONThe EASA validation of FAA STCa...	19/07/2021	Active	10076952
10076953	SABENA TECHNICS BOD	REV. 2		737-800	Chopin - C-Music Pod self-protection system:-Configuration 1: pod installed-Configuration 2: pod removedRev 1: update to remove ALS limitations related to fatigueRev 2: ICA document update	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:As defined in CRI A-101 “Certification basis” Issue 5The requirements for environmental protection and the associatedcertified noise and/ or emissions levelsa...	Master Document List MDL S-99-4181 issue DAFM Supplement AFMS-B3038-99-509 issue FInstructions for Continued Airworthiness ICA-B3038-99-304 Issue EAirworthiness Limitations Section document ALS-B3038-99-305 Issue DMMEL Supplement MMELS-B3038-99-316 issue Bor later revisions of the above listed docum...	When the C-MUSIC pod is not installed:- A cancellation plate must be installed in lieu of the pod- The C-MUSIC CDU, C-MUSIC master control panel and the two FPILannunciators must be marked INOPWhen the C-MUSIC pod is installed:- The C-MUSIC must be powered in TTOL, in order to have correct DIPfuncti...	27/10/2022	Active	10076953

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076954	SABENA TECHNICS BOD	REV. 1		737-800	CHOPIN – Self Defence SystemRev 1: update to remove ALS limitations related to fatigue	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:As defined in the CRI A-101 “Certification Basis” Issue 5The requirements for environmental protection and the associatedcertified noise and/ or emissions lev...	Master Document List MDL S-99-4182 issue BAFM Supplement AFMS-B3038-99-509 issue FInstructions for Continued Airworthiness ICA-B3038-99-510 Issue DAirworthiness Limitations Section document ALS-B3038-99-535 Issue GMMEL Supplement MMELS-B3038-99-524 Rev Bor later revisions of the above listed documen...	- The Basic EW system must remain OFF: REDCOM/SPS CMDS PWR switch mustremain with OFF/R position lit - Chaff and flaresloading (and dispensing) is prohibitedPrior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	25/05/2022	Active	10076954
10076956	GULFSTREAM AEROSPACE SERVICES CORP.d/b/a GULFSTREAM AEROSPACE CORPORATd/b/a GULFSTREAM		FAA ST00853CH	CL-600-2B16 (604 VARIANT)	Installation of Interior Furnishings and Passenger Accommodations	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Airplane serial numbers 5354 and 5356: Drawing List 600-061, RevisionC, dated 09 April 1998-Airplane serial number 5360: Drawing List 600-062, Revision A, dated21 May 1998-Airplane serial number 5362: Drawing List 600-063, Revision A, dated21 October 1998-Airplane serial numbers 5374, 5401 andR...	Applicable to airplane serial numbers 5354, 5356, 5360, 5362, 5374, 5401and 5412.Changes to the weight limitations and the center of gravity rangeapproved for this airplane are not authorised.Prior to installation of this change/repair it must be determined thatthe interrelationship between this cha...	19/07/2021	Active	10076956
10076967	T.P.S. S.P.A.			AB139, AW139	New neonatal transport system for AB/ AW139 P/N TPS139-07-00This change introduces the installation of an incubator equipped withmedical devices and oxygen cylinders.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Flight Manual Supplement TPS139-0700-RFMS-00-Master Document List TPS139-0700-Mdl-00-Master Drawing List TPS139-0700-Mdw-00-Instructions for Continued Airworthiness TPS139-0700-ICA-00-Installation Service Bulletin TPS139-0700-SBT-00Or later revisions of the above listed document(s) approved/ac...	This STC is valid only for AB139 and AW139 helicopters whenequipped ormodified with:-Aerolite EMS Equipment Kit P/ N 139172-501/502 in “EMS Configuration 1”with the Multimission FloorP/N 007841-501 of this kit installed (see EASA STC 10017278 Rev. 3)- and, at least one of the following approved Leo...	22/07/2021	Active	10076967
10076972	ALAMO ENGINEERING GmbH	REV. 2		AW169	OSD-SIM Data for AW169 Full Flight SimulatorsRevision 1:Transfer of STC from 328 Support Services GmbH, Postfach 1252, 82231Wessling, GermanyRevision 2:Scope of approval extensionto incorporate OSD-SIM Data for FFS and/orFTD devices simulating the AW169 aircraft configured with Core AvionicsSW Phas...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS SIMD initial issueof 02 December 2014.The requirements for environmental protection and the associatedce...	For STC at Rev. 1:Master Drawing List MDL-134Z002 issue B dated 20 July 2021Validation Data Roadmap: Validation Data Roadmap Leonardo AW169,SR-028C000Z0001 issue E dated 28 May 2021Flight Test Data Report: Flight Test Report Leonardo AW169FTR028C000Z0001 issue D dated 28 May 2021Compliance Statement...	The usage of the validation data of this STC is limited to thevalidation of FFS and/or FTD devices simulating the AW169aircraft onthe basis of the AW169 in the following configuration:- AW169 configured with Core Avionics SW Phase 3.0 andfixed landinggear (i.e. AW169 Rotorcraft Flight Manual Suppl...	15/04/2025	Active	10076972
10076981	KILROY AVIATION LLC		FAA STC ST04649NY	GVI (G650)	Installation of Avionic Instruments' Frequency Converters in aGulfstream Model GVI (G650/G650ER)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04649NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Kilroy Aviation, LLC, Master Data List - Installation, documentJ538-0030-001, revision E, dated 7 May 2021, or laterFAA-approvedrevision.2. Kilroy Aviation, LLC, Instructions for Continued Airworthiness (ICA),document J538-ICA, revision A, dated 1 May 2021, or later FAA-acceptedrevisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.There are no airworthiness limitations for this certifi...	23/07/2021	Active	10076981

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10076986	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC ST01143LA	737-400, 737-700, 737-800	Installation of Aerocon Engineering company (AEC) Airstair	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST01143LA.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	AEC Master Drawing List (MDL) 1423-3700, Revision C, dated 30 January2001, or later FAA approved revisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/08/2021	Active	10076986
10076990	DASSAULT AIRCRAFT SERVICES (DAS)		FAA ST03604NY	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	EASA Validation of STC ST03604NYInstallation of a HoneywellMCS8000 KA Band SATCOM in Dassault AviationMystere-Falcon 900 and Falcon 900EX	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: JAR 25.305(a)(b); 25.321(a); 25.341; 25.365(a)(b)(c)(d)(e); 25.561(a)(b)(c); 25.571(a)(b)at change 15; CS 25.855(b)(f)(g);2...	-Master Data List F9XW-D0087-005 Rev. B-AFM Supplement F9XW-D0087-150 Rev. IR-ICA F9XW-D0087-155 Rev. Bor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This STC is applicable to DA MF-900 and 900EX with radome installed perDassault Aviation MOD 5044 and DA 900EX with radome installed perDassault Aviation MOD 6067 or Service Bulletin 554Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/re...	23/07/2021	Active	10076990
10077003	JAMMONS, INC.		FAA STC ST01894AT	737-700	Relocation of High Frequency Transceiver 1 and 2 (HF1 and HF2), CockpitVoice Recorder (CVR), Flight Data Recorder (FDR), and Auxiliary PowerUnit Electronic Control Unit (APUECU), and Removal of the E6 ElectronicsRack	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List No. 98-F0131 Rev. C dated 27 April 1999, for S/N 29200 (registration no. N742PB) only, and for all other installations Rev. F,dated 29 July 1999 or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/08/2021	Active	10077003
10077005	GULFSTREAM AEROSPACE Corp.		FAA ST09374SC	CL-600-2B16 (604 VARIANT)	Installation of Passenger Oxygen Distribution for the Bombardier modelCL-600-2B16 (604 Variant)	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- ST09374SC, Canadair CL-600-2B16, Installation of a Passenger OxygenDistribution System Certificate- Instructions for Continued Airworthiness for Passenger Oxygen system,MMP10-005 dated August 20, 1997 (revisions on Apr 20/98 and Dec 18/00)- Airplane Flight Manual Supplement For Canadair Challenger...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/07/2021	Active	10077005
10077006	GULFSTREAM AEROSPACE Corp.		FAA ST00643CH	CL-600-2B16 (604 VARIANT)	Traffic Alert and Collision Avoidance System (TCAS) Modification -Installation of Lower Directional Antenna and Relocation of LowerTransponder Antenna	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Drawling List No. 604-5305-1, Rev. F, dated 02 March 1999Installation of Lower Antenna, Maintenance Manual Supplement KCA-MMS-02<(>,<)> dated 03 April 1997or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures o...	Collins TCAS-94 must have been previously installed or to be installedconcurrently with this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeff...	26/07/2021	Active	10077006
10077009	SABENA TECHNICS BOD			A330-243	Forward cabin modification “S0005 Martine”.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Document List MDL S-25-4304 rev AAFM Supplement AFMS-S0005-25-009 rev CInstruction for Continued Airworthiness ICA-S0005-25-007 rev AMMEL Supplement MMELS-S0005-25-010 rev Cor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limitations as per AFM Supplement AFMS-S0005-25-009;Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	26/07/2021	Active	10077009

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077012	AERSALE, Inc.		FAA STC ST04184NY	777-200LR 777-200	Installation of ACSS DO-260B ADS-B Out Qualified Transponder AutomaticDependent Surveillance-Broadcast (ADS-B) Out SystemThe validated STC (ST0418NY) is fully compliant to EASA CSACNS SubpartD, Section 2 (Mode S Elementary Surveillance), Section 3 (Mode SEnhanced Surveillance) and Section 4 (1090MH...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS ACNS Subpart D, Section 2,3 & 4The requirementsfor environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedandt...	Master Data List, Doc Ref: B772-MDL-0051 Rev BAirplane Flight Manual Supplement, Doc Ref: B772-AFMS-0051 Revision AInstructions for Continued Airworthiness, Doc Ref: B772-ICA-0051Rev IRor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Techn...	None	26/07/2021	Active	10077012
10077017	ANUVU OPERATIONS LLC		FAA ST04528CH	A321-213/-231/-232 A321-111/-112/-131/-211/-212	Installation of a broadband wireless internet system	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04528CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Data Listing Document No. RWO100-0003-00, Revision IR, dated 26May 2021Project Specific Certification Plan (PSCP) RWO105-0002-00 Rev. C, datedMay 25, 2021EWIS ICA Source Document RWO270-0009-00, Revision. IR, dated 30 November2020Airplane Flight Manual Supplement (AFMS) RWC220-0011, Revision0...	The EASA STC 10073636 Rev. 0 (FAA ST04462CH - Installation of Row 44Broadband Antenna System Provisions) is prerequisite to this STC.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or...	28/07/2021	Active	10077017
10077018	CONCORDE BATTERY CORPORATION		FAA STC SA00944DE	525C	Installation of Concorde VRLA battery	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00944DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Document No. 5-0654, Master Drawing List, Cessna 525C (CJ4) BatteryReplacement, Revision NC dated 19 February 2019, FAA approved 12 March2019 or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA), Document No. 5-0655,Revision NC dated 19 February 2019, FAA accepted 12 M...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/07/2021	Active	10077018
10077019	CONCORDE BATTERY CORPORATION		FAA STC SA01076DE	SR22T	Installation of main battery replacement with Concorde Valve RegulatedLead Acid battery	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01076DE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Document No. 5-0712, Master Drawing List, Cirrus S22T Battery Upgrade,Revision NC, dated 20 October 2020, FAA approved 2 November 2020, orlater FAA approved revision.Instructions for Continued Airworthiness (ICA), Document No. 05-0714,Revision NC, dated 20 October 2020, FAA accepted 3 November 2020,...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/07/2021	Active	10077019
10077020	PILATUS BUSINESS AIRCRAFT, Ltd.		FAA STC SA00634DE	PC-12/47E PC-12/47 PC-12/45 PC-12	Installation of a SPECTRE Lift Platform System and ventral camera turretprovisions	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00634DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Drawing List, Document No. PBA. 600.103-MDL, Revision J, dated21 October 2015, FAA approved 27 October 2015 orlater FAA approvedrevision.2. Airplane Flight Manual SupplementFor the modified Model PC-12/45 and PC-12/47 aircraft: DocumentPBA.600.103-FMS, Revision A, dated 21 April 2015, or l...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/07/2021	Active	10077020

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077027	CONCORDE BATTERY CORPORATION		FAA STC SR01067DE	480B 480	Installation of main battery replacement with Concorde Lead-Acid battery	The Certification Basis for the original product remains applicable tothis certificate/ approval except where amended byadditional or lateramendments if indicated on FAA STC SR01067DE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	Document No. 5-702, Master Drawing List Enstrom 408 & 408B BatteryReplacement, Rev. NC, dated 14 August 2020, FAA approved 8 October 2020,or later FAA approved revision.Instructions for Continued Airworthiness (ICA), Document No. 5-704, Rev.NC, dated 14 August 2020, FAA accepted 8 October 2020, or l...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/07/2021	Active	10077027
10077043	INNOVIATOR, LLC.		FAA STC SA04459CH	B200GT, B200T, B300, B300C B200, B200C, B200CGT, B200CT A200, A200C, A200CT 300, 300LW 200, 200C, 200CT, 200T	Installation of a modified horizontal stabilizer cover assembly andantenna provisions	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04459CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Innoviator, LLC Installation Data List IN41-IDL-25908 rev. IR dated15 April 2020, or later FAA-Approved Revision. 2.General Arrangement Drawing IN41-5510-001 rev. IR dated 2 April2020, or later FAA-Approved Revision.3. Instructions forContinued Airworthiness, IN41-ICA-25704 rev. IRdated 2 April...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/08/2021	Active	10077043
10077044	S4A SOLUTIONS FOR AVIATION, S.L			CL-600-2B19 (RJ SERIES 100)	PASSENGER OXYGEN CONTROL PANEL REPLACEMENT	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: EASA CS-25 Amdt. 24,Sections; 25.1, 25.21, 25.23, 25.27, 25.301, 25.303, 25.321, 25.337,25.341, 25.471, 25.561, 25.601, 25...	604101-12-13 Master Document List Edition 03604101-12-28 Flight manual supplement Edition 03604101-12-30 Maintenance Manual Supplement Edition 02604101-12-32 Wiring manual supplement Edition 01	Bombardier CL-600-2B19 aircraft MSN: 8048, 8054, 8073, 8076, 8082<(>,<)>8086, 8101, 8107 (19 passengers or less) Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	02/08/2021	Active	10077044
10077054	BOEING IRELAND LIMITED			737-800	Change of the Electrical Power System to Provide 60 Minutesof StandbyPower for the Airplane Standby Loads in Lieu of 30 Minutes and ChangeCaptain’s Pitot Heat power source to theStandby Bus.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 amdt 12 for thefollowing paragraphs: 232527301(a)(b)303305(a)(b)307(a)3213313333373413 65(e)471(a)(b)561(a)(b)(c)58160...	Change/Repair Approval document BIL-00114-APP Rev 00, dated9 July 2021Instructions for Continued Airworthiness BIL-00114-ICA01 rev 00, dated20 May 2021Aircraft Flight Manual Supplement BIL-00114-AFM01 Rev 00, dated 10 March2021Flight CrewOperations Manual Supplement BIL-00114-MS12 Rev 00, dated 6A...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/08/2021	Active	10077054
10077075	MAXCRAFT AVIONICS Ltd.		TCCA SH09-20 ISSUE 2	AS 355 N AS 355 F2 AS 355 F1 AS 355 F AS 355 E	DC Electrical Panel Rework.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List MDL-05-70-00-031 Rev. E dated Sep 21, 2020;ICA-05-70-00-031 Rev. C dated Mar 6, 2013;For AS 355 E, F, F1, F2:FMS-05-70-00-031(-E1) Rev. A dated Aug 13, 2020;For AS 355 N:FMS-05-70-00-031(-E2) Rev. A dated Aug 13, 2020.or later revisions of the above listed document (s) approved/accep...	Approved for Day VFR operations only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	10/08/2021	Active	10077075

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077081	IKHANA GROUP, LLC			DHC-6 SERIES 400 DHC-6 SERIES 300 DHC-6 SERIES 200	Installation of High-Flow 250 Amp Starter-Generators	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02730LA.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	IKHANA Aircraft Services Master Drawing List ER218-3081, Revision NC,dated 9 July 2020, or later FAA approved revision.FAA Approved Flight Manual Supplement, Document No. SG-62-1-250,Revision IR, dated 3 August 2020, or later FAA approved revision isrequired for the DHC-6-200 airplane model.FAA Appr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC approval is limited to DHC-6-200 and DHC-6-300...	11/08/2021	Active	10077081
10077086	ONBOARD SYSTEMS INTERNATIONAL		FAA SR02719SE	AS 350 B3	Onboard System Cargo Swing Suspension System for AS 350 B3 fitted withCrash Resistant Fuel Tank System (CRFS) as per TCH mod 0720034.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Drawings List No. 155-216-00, Rev 2, dated 30 March 2021Instructions For continued Airworthiness No. 123-051-00,Rev 00, dated 4March 2021Rotorcraft Fight Manual SupplementNo. 121-071-00, Rev 00, dated 27April 2021or later revisions of the above listed document(s) approved/ accepted onbehalfP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/08/2021	Active	10077086
10077095	SCANDINAVIAN AVIONICS DESIGN ApS			GULFSTREAM G150	Dual CVFDR installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01, Non-rechargeable Lithium BatteryInstallationThe following paragraph(s) at a later amendment: following paragraphs atCS 25 Amendment 2:CS 25...	Certification documents (MDL), Doc. No. 2128299 DOC, Issue 1AFMS, Doc. No. 2128299-AM, Issue 2 and Doc No.2128299-AM B,Issue 1CONTINUED AIRWORTHINESS, Doc. No. 2128299-CA, Issue 1MAINTENANCE MANUAL SUPPLEMENT, Doc. No. 2128299-MM, Issue 1MMEL SUPPLEMENT, Doc. No. 2128299-ME, Issue 1TECHNICAL ORDER,...	Limited to serial number 0283Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	16/08/2021	Active	10077095
10077099	AIRCRAFT COMPLETION ENGINEERING	REV. 3		SEE EASA APPROVED MODEL LIST	ACE STC001 - Oxygen medical bottleReason for revision 1: addition of Alternative support for ACE medicaloxygen, EASA approval 10080368Reason for revision 2: Editorial corrections / clarifications of ServiceBulletinReason for revision 3 – Addition of alternative parts for Medical oxygenkit ACE1801-00...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): F-02/60072263 Maximum Oxygen WorkingPressure and Pressure Limiting Performancethe following paragraph(s) at a later amendment: CS 25.1, 25.60...	Master Document List MDL 1801-2-001 Issue 11 dated 24/04/2024Flight Manual Supplement ACE_STC 001_AFM Supplement Rev 0 dated12.08.2021	EASA Minor Changes 10072988, 10080368 or 10084565 are pre-requisite forthis installation. This installation is limited to configurations as perService Bulletin ACE1801-2-001 OXYGEN MEDICAL KIT REV 8 or ServiceBulletin ACE1801-3-001 Alternative support for ACE medical oxygen kit Ed6Prior to installat...	10/06/2024	Active	10077099
10077101	AMAC AEROSPACE SWITZERLAND AG			747-8	Installation of Self Protection System - CAMPSThe change consists of the installation and activation of a SelfProtection System (CAMPS)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 Missile Protection System Installationthe following paragraph(s) at a later amendment: The followingparagraphs of CS-25 at Amendment 2 are a...	The change is defined with Revision B of Master Data List documentMDL-B7471-1-4300.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplementdocument AFMS-B7471-1-4300.The aircraft shall be maintainedin accordance with Revision A ofInstructions for Continued A...	The STC grants no operational approval, the aircraft operator will needto obtain operational approval from the Agency or Authority responsiblefrom the State of registry and the State in who's airspace it is to beoperated.Prior to installation of this change/repair it must be determined thatthe inter...	18/08/2021	Active	10077101

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077113	S4A SOLUTIONS FOR AVIATION, S.L			CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	EPISHUTTLE INSTALLATION IN CL-600	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-01 Medical Evacuation Configurationthe following paragraph(s) at a later amendment: CS25.1; CS25.21;CS25.23; CS25.25; CS25.27; CS25.301; CS25.303;C...	Installed in accordance with Service Bulletin ref 60492-12-19 edition 2dated 17/8/2021, maintained in accordance with Maintenance ManualSupplement ref 60492-12-30 edition 1 dated 27/10/2020, operated inaccordance with Flight Manual Supplement ref 60492-12-28 edition 2 dated24/02/2021 and Operationsd...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/08/2021	Active	10077113
10077114	LEARJET Inc.	REV. 5	FAA ST01970WI	SEE FAA AML	Installation of an Aircraft Health Management System (AHMS)Revision 1 consists of addition of Challenger 604, 605, 650,Global5000/6000 Global Vision Flight Deck and Special Condition for SystemSecurity (25-794-SC) for Challenger models and activation of RS-422 onChallenger 300, 350 installs.Revisio...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition: FAA Special Condition No. 25-794-SC, ElectronicSystem Security Protection from UA External Access.The requirements for environmental prot...	Refer to FAA Approved Model List.In addition, for Bombardier models BD-700-1A10 (Global 6500configuration) and BD-700-1A11 (Global 5500 configuration)- EASA MMELsupplement 46-35-01 Rev. 0 dated 04 November 2024or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	30/04/2025	Active	10077114
10077124	GVH AEROSPACE (IRELAND) LIMITED	REV. 1		737-800	189 Passenger ConfigurationThis change reconfigures cabin interior of Boeing 737-800 aircraft asfollows:-Removal of allexisting economy class seats.-Installation of new Acro seats.-Re-pitching of existing PSUs to suit new LOPA.-Installation of new portable ELT.-Installation of emergency & safety eq...	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Master Data List ref. GVH-10495-01-MDL-01 at Issue 1 dated 20 Aug 2021Instructions for Continued Airworthiness ref. GVH-10495-01-ICA-01 atIssue 1 dated 29 Apr 2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/09/2021	Active	10077124
10077144	ANCRA INTERNATIONAL LLC		FAA STC ST02757LA	ATR 72-212 A	Installation of main deck cargo loading system	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 amdt. 0: 25.23 (a)(b),25.29(a)(b), 25.303, 25.471, 25.561, 25.301, 25.605, 25.607, 25.619,25.625, 25.1529, 25.1541CSC...	1. FAA approved Ancra International LLC Controlled Data List DL85440,Revision C, dated 14 June 2021, or later FAA approved revision;2. Airplane Flight Manual Supplement for ATR72-212A, report number11300, Revision IR, dated 20 July 2021, or later FAA approved revision.3. Instructions for Continued A...	ATR Major modifications 5948, 6521, and 5977 must be installed inconjunction with this installation on model ATR 72-212A ("600 version"full Cargo defined by TCDS EASA.A.084).Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any...	27/08/2021	Active	10077144
10077147	AEROMETALS INC.		FAA STC SR02680LA	EC 130 T2	Installation of Engine Inlet Barrier Filter SystemValidation of FAA STC SR02680LA	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Equivalent Safety Finding(s): P-1 (FAA) with JAR 27.45(c)(f)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the...	Aerometals Master Drawing List, doc. no. 2130-MDL-1, Rev. B, dated June22, 2017Instructions for Continued AirworthinessEngine Inlet Barrier SystemAirbus Helicopters EC130T2, doc.no. 2130-ICA-1, Rev. B, dated July 18,2018EASA Approved Rotorcraft Manual Supplement (RFMS), doc. no. 2130-RFMS-2,datedo...	The limitations specified in the basic Rotorcraft Flight Manual aremodified by the following:- Flight in falling and/orblowing snow with IBF bypass doors closed ispermitted;- Maximum operating altitude in flight: 16 000 ft pressure altitude ordensity altitude, whichever is lower;- Engine Health Che...	27/08/2021	Active	10077147

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077148	GULFSTREAM AEROSPACE CORPORATION	REV. 1		GV-SP GV	Installation of JetWave Ka HSD System with Mid Fin Cap Radome for GV-SPand Installation of Mid Fin Cap Radome only for GV aircraft.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Supplemental Type Certificate ST04323AT-D, reissued May 26,2020Index List GDL100000034, Revision (-), dated May 02, 2019CE51303M040 Revision (-), dated May 02, 2019 “FAA ApprovedAirplaneFlight Manual Supplement for Gulfstream Model GV-SP”CE51 303A138 Revision (-), “Instructions for Continued Airwo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/09/2021	Active	10077148
10077171	SKY SERVICE F.B.O. INC.		TCCA SA18-94	LEARJET MODEL 45	UASC UL-801 UNILINK Airborne Data Link	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:FAR 25.1457 atAmendment 25-124.The requirements for environmental protection and the associatedcertified noise and/ or e...	Installation must be in accordance with Avionics Design Ltd. MasterDrawing List MDL18006 Revision N/C, approved September 11, 2018;Operations must be in accordance with Sky Service F.B.O Inc FlightManual Supplement FMS18006-1 Review N/C approved September 10, 2018;Maintenance must be in accordance w...	Installation of FAA STC ST01499WI-D/EASA 10061804 is a prerequisite forthis approvalCompliance with chapter 4.0, “Airworthiness limitations” of Instructionsfor Continued Airworthiness ICA18006-1 is mandatory.Prior to installation of this change/ repair it must be determined thatthe interrelationshipp...	31/08/2021	Active	10077171
10077174	APTOZ EHF.			SEE EASA APPROVED MODEL LIST	Installation of Techtest Limited Portable ELT 500-32	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- As per Approved Model List.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remai...	Approved Model List AML231147 rev AMaster Data List MDL231147 rev Cor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/08/2021	Active	10077174
10077176	2 EXCEL DESIGN LIMITED	REV. 2	CAA UK RESPONSIBILITY	B200	Introduction of Flight Inspection Antennas to King Air B200Rev. 1 and Rev. 2 issued for editorial corrections.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed in accordance with 2Excel Aviation Limited InstallationInstructions No. 2XL178 LEF49A(1) Issue 3, 2Excel Aviation LimitedMaster Data List No. 2XL178 Issue 3Maintained in accordance with 2Excel Aviation Limited Instructions forContinued Airworthiness No. 2XL178 LEF73(1) Issue 5or later rev...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/09/2021	Active	10077176
10077188	HONEYWELL INTERNATIONAL Inc.	REV. 3	FAA ST04473CH	SEE FAA AML	Installation of a Honeywell RDR-7000 Weather Radar SystemRev. 3: Add Embraer S.A. EMB-135BJ listed from FAA AML Item 2.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Instructions for Continued Airworthiness (ICA) as listed onthe FAA AMLST04473CH.Airplane Flight Manual Supplement as listed on the FAA AML.or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordancewith the Technical ImplementationProcedures of EU/ USA Bilat...	AML Item 1The STC is applicable to the following serial numbers for thisMake-Model: MSN 550-0801 and on, MSN 560-0260 to 560-0538AML Item 2This STC is applicable to the following serial numbers for this MakeModel: MSN 145412, 145462 and subsequent (Legacy 600), MSN 145115 andsubsequent (Legacy 650) P...	09/06/2022	Active	10077188
10077189	APTOZ EHF.	REV. 1		757-200	Structural provisions of removed SATCOMStructural provisions for the High Gain Antenna & Low NoiseAmplifier-Diplexer unit and for the equipment rack in the forward cargohold.Rev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Certification Plan CP-757-5310-209 Rev A-Instructions for Continued Airworthiness (Limitations section) ICA-757-5310-209-01 Rev I/Rsigned 11. Aug.2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10077189

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077190	HONEYWELL INTERNATIONAL Inc.	REV. 1	FAA ST04470CH	MYSTÈRE FALCON 900 (MF900) MYSTÈRE FALCON 50 (MF50) FALCON 900EX (F900EX)	Install RDR-7000 Weather Radar on MF900Installation of the Honeywell RDR-7000 Weather Radar System on DassaultAviation Mystere-Falcon 900.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: 25.869(a)(4) amdt.25-113; 25.981(a)(3) amdt. 25-102.The requirements for environmental protection and the ass...	- ATEC-077-241-1000 STC Master Data List Rev. G- ATEC-20372Airplane Flight Manual Supplement rev. 1- ATEC-20373 Airplane Flight Manual Supplement rev. 1- ATEC-21046 Airplane Flight Manual Supplement rev. 1- ATEC-21161 Airplane Flight Manual Supplement rev. 1- ATEC-20205 Instructions for Continued A...	This STC is applicable to the following serial numbers for thisMake-Model: MSN 174 through 178.Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffec...	16/05/2022	Active	10077190
10077192	HONEYWELL INTERNATIONAL Inc.	REV. 2	FAA ST04477CH	680 (SOVEREIGN)	Installation of Honeywell RDR-7000 RadarSTC for the installation of the Honeywell RDR-7000 Weather Radar Systemon Textron Aviation Cessna 680 (Sovereign).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ATEC-077-241-1200 STC Master Data List Rev. FATEC-20512 Airplane Flight Manual Supplement rev 1ATEC-20513 Airplane Flight Manual Supplement rev 1ATEC-21159 Airplane Flight Manual Supplement rev 1or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance withP...	This STC is applicable to the following serial numbers for thisMake-Model: MSN 680-0001 to 680-0500.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverse...	25/04/2022	Active	10077192
10077193	DELTA ENGINEERING CORPORATION	REV. 3	FAA STC ST04241CH	777-300ER 777-300	Installation of a Gogo Cabin Distribution System with 2Ku SatelliteConnectivityRevision 1: Mention of the Alternative Method of Compliance (AMOC) toAirworthiness Directive (AD) 2014-11-01Revision 2: Transfer of the STC from INTELSAT INFLIGHT LLC to DeltaEngineering Corporation and editorial updates....	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 amdt. 1:25.981(a)(3); CS25 amdt. 4: 25.853(a), 25.869(a)(4).The requirements for environmental protectio...	1. Delta Engineering Master Data List (MDL) D12525-21620 Revision AHdated 1 August 2023;2. Instructions for Continued Airworthiness, Electrical WiringInterconnect System Instructions for Continued Airworthiness, Doc. No.D12454-21620, Revision V, dated 19 July 2023;3. FAA Approved Airplane Flight Man...	Reference the Master Data List for additional limitations and conditionsas well as applicable serial numbers.Operational approval to use T-PED's must be obtained separately fromthis STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/re...	27/10/2023	Active	10077193
10077194	DASSAULT FALCON JET		FAA STC ST09731SC-D	FALCON 2000, FALCON 2000EX	Installation of the Ordinance Signs	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST09731 SC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	Drawing List Report No. F2M-01054, Revision NC, dated 24 January 2002,or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/09/2021	Active	10077194
10077196	ALAMO ENGINEERING GmbH			EMB-145MP EMB-145MK EMB-145LU EMB-145LR EMB-145EU EMB-145ER EMB-145EP EMB-145 EMB-135LR EMB-135ER EMB-135BJ	ADS-B Out Upgrade on Mode-S Enhanced Surveillance HoneywellPrimus IIInstallations	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.1319, Amdt. 26Other: CS-ACNS, Issue 2The requirements for environmental protection and the associatedcertified nois...	-Master Document List, MDL21A16AE-01, Rev. A- Aircraft Flight Manual Supplement, FMS21A16AE-01, Rev. A- Instructions for Continued Airworthiness, ICA21A16AE-01, Rev. AOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/09/2021	Active	10077196
10077197	INNOVATIVE SOLUTIONSAND SUPPORT, Inc.		FAA SA00400BO	B300, B300C B200, B200C, B200CGT, B200GT	Validation of FAA STC SA00400BO for the following configurations:STC Configuration 2: Innovative Solutions & Support, Inc. (IS<(>&<)>S)Integrated Standby Unit (ISU) with ATS, DualEngine, installed in 2A:B200, B200C, B200GT, B200CGT or 2B:B200, B200C, B200GT, B200CGT, B300,B300C. All original produ...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): EASA SC-F23.1329-01 Auto-Throttle for CS-23Aircraft.The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	1. To be installed according to:- STC Configuration 2:ISU Part Number 9K-88130-1, loaded with top level software 7H-13683-09(or later FAA approved top level software), in accordance with IS<(>&<)>S Master Data List (MDL): 2.A: 1D-13860, Revision 1, dated 12 November 2019. ATS, Dual Engine,provid...	Configuration 1 of FAA STC SA00400BO is not included in this approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness...	06/09/2021	Active	10077197

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077205	BROMMA AIR MAINTENANCE AB			LEARJET MODEL 45	Learjet 45 Medevac Rack Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed in accordance with TO-20-03 Revision A; maintained inaccordance with ICA 20-03 Revision B; operated in accordance withFMS-20-03 Revision Aor later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/09/2021	Active	10077205
10077207	DASSAULT AIRCRAFT SERVICES (DAS)			FALCON 7X	Installation of a GoGo AVANCE L5 system in Dassault Aviation Falcon 7Xaircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03600NY.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Dassault Aircraft Services (1) Master Data List F7XW-D0084-005, Rev. IR, dated 16 February 2018, orlater FAA approved revision.(2) Instructions for Continued Airworthiness (ICA) F7XW-D0084-155, Rev.IR, dated 16 February 2018, or later FAA accepted revision. The ICA andits contents must be incorporate...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/09/2021	Active	10077207
10077247	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04485AT	A321-271NX,-272N,-272NX A321-253N,-253NX,-271N A321-251NX,-252N,-252NX A321-213,-231,-232, 251N A321-111,-112,-131,-211,-212 A320-253N,-271N,-272N,-273N A320-232,-233,-251N,-252N A320-211,-212,-214,-216,-231 A319-151N,-153N,-171N A319-115,-131,-132,-133 A319-111,-112,-113,-114 A318-111,-112,-121,-122	Installation of the Avionics Support Group Constant Friction Mount(cfMount), Cradle and Integrated Power Supply (IPS) on Airbus A318,A319, A320 and A321 Series Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS25 amdt. 1: 25.613CS25 amdt. 5: 25.611, 25.1301CS25 amdt. 18: 25.773, 25.1353, 25.1357, 25.1360CS25 amdt. 19: 25.571Thec...	1. Master Drawing List, 217368-MDL<(>,<)> Revision D, dated13 October2020, or later FAA approved revision.2. Instructions for Continued Airworthiness (ICA) document 217368-ICA,Rev. IR, or later FAA accepted revision.3. Airplane Flight Manual Supplement (AFMS) document 217368-FMS, Rev IR,or later FA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/09/2021	Active	10077247
10077254	3 POINTS AVIATION CORP.		TCCA SA12-42	DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Replacement of worn upper caps of cockpit seat tracks with stainlesssteel track.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	The change is defined with issue 2 of 3 Points Machining & Aerospacedocument 3PMA-ENG12-094-MDL.or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/09/2021	Active	10077254
10077275	BOMBARDIER Inc.	REV. 1	TCCA SA20-92	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Emergency Equipment Modification	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	According to B/E Aerospace Limited Modification Data Summary N100000,Rev NCTo be maintained iaw. TCCA accepted Bombardier Inc. Instructions forContinued Airworthiness document BAS63058100-ICA-XXX (Where XXX is a unique identifier for each configuration defined inModification Data Summary N100000<(>,<...	See those of TCCA STC SA20-92.The EASA approved configurations are identified in the Modification DataSummary N100000, Rev NC or later TCCA accepted revision.Prior to installationof this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	17/09/2021	Active	10077275

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077279	B/E AEROSPACE, INC.		FAA STC ST04520AT	SEE FAA AML	Installation of Rockwell Collins GLU-2100 Multi Mode Receivers (MMR)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 amdt. 4: 25.23 (a), 25.301(a)(b), 25.303, 25.305 (a), 25.307(a),25.561(c), 25.601, 25.603(b)(c), 25.611, 25.853(a), 25....	FAA Approved Model List (AML) 2-197186-002, Revision IR, dated 21 June2021 or later FAA accepted revisions.Instructionsfor Continued Airworthiness (ICA) as listed in the FAAApproved Model List (AML) document and the Airplane Flight ManualSupplement (AFMS) as listed in the FAA Approved Model List (A...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Configuration 1 (installation on A330 aircraft models):...	21/09/2021	Active	10077279
10077284	AIRBUS HELICOPTERS, Inc.		FAA STC SR11334DS	AS 350 B3	Installation of a Flightcell DZMx Satellite/ Cellular/Tracking System.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval except where amended by additional orlater amendments if indicated on FAA STCSR11334DS.The requirements for environmental protection andthe associatedcertified noise and/ or emissions levels of th...	Master Drawing List 350A82-1917, rev IR, dated 07 January 2021Rotorcraft Flight Manual Supplement 350FMS-565, rev A, dated 18 August2021Instructions for Continued Airworthiness 350MMs-065, rev IR, dated 23March 2021or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA...	1. This STC is limited to Airbus Helicopters AS 350 B3 postmod 07-34392. AHI STC SR11335DS, Installation of AFT console/collective barrier isa pre-requisitePrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	15/09/2021	Active	10077284
10077291	AIRBUS HELICOPTERS, Inc.		FAA STC SR11336DS	AS 350 B3	Installation of the Ukraine Border Guard (UBG) collection of systems andequipment specific to the UBG aircraft configuration.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval except where amended by additional orlater amendments if indicated on FAA STCSR11336DS.The requirements for environmental protection andthe associatedcertified noise and/ or emissions levels of th...	Master Drawing List 350A82-1927, rev D, dated 12 April 2021Rotorcraft Flight Manual Supplement 350FMS-577, rev C, dated19 August2021Instructions for Continued Airworthiness 350MMS-078, rev IR, dated 31March 2021or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in...	1. This STC is limited to Airbus Helicopters AS 350 B3 postECP OP-49622. Refer to approved RFMS for the applicable airspeed limitation3. Prerequisite installation limitations must be complied with: thefollowing are prerequisite installations for this STC:AHI STC SR11333DS, FLIR UltraForce 350-HDAHI...	16/09/2021	Active	10077291
10077294	DASSAULT AVIATION BUSINESSSERVICES SA			FALCON 900EX (F900EX)	TAG-M317 – VARNISH REWORKRework of cabin interior wood items finished with varnish	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	TAG-M317-MCDL Rev. B dated Sept. 13th 2021or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	This STC constitutes an Alternative Method of Compliance (AMOC) to theaction required by EASA AD 2014-0082, sect. “Required Action(s) andCompliance Time (s)”, paragraph (1).The STCapproval and AMOC is limited to aircraft serial number 623.Prior to installation of this change/repair it must be determ...	16/09/2021	Active	10077294
10077306	SAFRAN CABIN INC.		FAA STC ST02565LA	ERJ 190-100 IGW	Interior Installations and Modifications	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 15: 25.853(a)(d)The requirements for environmental protection and the associatedcertified noise and/ or emission...	Index List No. J601, Revision A, dated 16 April 2021, or later FAAapproved revisions.Instructions for Continued Airworthiness (ICA), Report No. CDRJ601-78,Revision A< (>,<)> dated 16 April 2021, or later FAA accepted revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC approves provisions for the installation of eq...	01/10/2021	Active	10077306

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077319	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			777-300ER	B777 Cabin Modification for Cargo TransportModification of the cabin and removal of existing seats to allowtransportation of cargo on the passenger compartment floor.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): CRI D-130The following paragraph(s) at a later amendment: CS 25.561 (c) (2) Amdt24The requirements for environmental protection and the associatedcertified n...	The change is defined with revision 1 of AMES Engineering Order DocumentEO_M158001021_MZI_04112020The installation has to be accomplished in accordance with revision 6 ofAMES Instructions for Continuous Airworthiness DocumentICA_M158001021_MZI_04112020The aircraft shall be operated in accordance wit...	The allowance to transport cargo in passenger compartment is limited to2 000 FH following installation of the change orto 31 July 2022,whatever occurs first.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	21/09/2021	Active	10077319
10077347	EMBRAER GPX Ltda. (PC 722)			EMB-135BJ	Satcom Aviator 300 Installation	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	- Master Documents List ref. ESC-MDO-0002 Rev. H dated 6 August 2021- Aircraft Flight Manual Supplement ref. AFMS-H. 02-5239/ANAC/2019 Rev. / dated 7 November 2019- Instructions forContinued Airworthiness ref. ESC-ICA-0012 Rev. /dated 6 August 2021or later revisions of the above listed document(s) ap...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/09/2021	Active	10077347
10077348	UAB "FL TECHNICS"			A320-214	Passenger seating arrangement change.This change introducesnew passenger seating configuration from currentlayout (8B/C and Y/C150 (dual passenger class layout) or Y/C 150PAX (single passenger economy class layout)) to 180 Y/C PAX layout(single passenger economy class layout) on A320 aircraft.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS25.562 Initialissue; JAR 25.812 Change 13.The requirements for environmental protection and the associatedcertified no...	MDL-581-01 Issue CAMM Supplement: PA-581-01 initial issue (MSN 3044); PA-581-02 initialissue (MSN 3601); PA-581-03 initial issue (MSN 3605)or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This change must be performed concurrently with AMES Minor change(Partition installation as per EO_M230001014_JTU_23032021 (AMES,EASA.21J. 299)).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed cha...	27/09/2021	Active	10077348
10077352	GDC ENGINEERING GmbH			A321-271NX/–272NX A321–251NX/–252NX/–253NX A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/–212/–214/–215/–216	Pax to Cargo Modification - LEVIS	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Deviation(s): D-0340-002 'Transportation of cargoin passengercompartments'the following paragraph(s) at a later amendment: The followingparagraphs at Amdt 26:25.21(a)(1)...	For A320:A320E-AFM-A Rev 04, dated 13 Sep 2021A320E-MMEL-A Rev 02, dated 14 Sep 2021A320E-CCD-A Rev 03, dated 11 Aug 2021A320E-ICA-A Rev 01, dated 13 Sep 2021For A321:A321D-AFM-A Rev 01, dated 17 Sep 2021A321D-MMEL-A Rev 00, dated 10 Sep 2021A321D-CCD-A Rev 01, dated 17 Sep 2021A321D-ICA-A Rev 00, d...	The allowance to transport cargo in passenger compartment is limited to2 000 FH following installation of the change orto 31 July 2022,whatever occurs first.Aeroplanes modified per this STC are considered to be a “variant” to theA320/ A321passenger configurations. Cabin crew operating aeroplanesmod...	27/09/2021	Active	10077352
10077353	AVIATION TRADERS LIMITEDEUROPE S.A.S.			747-200F, 747-300 747-200F 747-200C 747-200B 747-100, 747-200B, 747-200C	Installation of ADS-B Out functionality.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Deviation(s): DEV F-01 ‘ADS-B Out Extended Squitter & ELS installationwith TPR-901 transponderon Boeing 747'.- The following paragraph(s) at a later amendment: CS ACNS I...	Aircraft Flight Manual Supplement 13659-AFM-00001, Issue 1 dated 11March 2020Aircraft Flight Manual Supplement 13659-AFM-00002, Issue 2 dated 17 May2021Master Minimum Equipment List MMEL-13659-00001, Issue 1Instructions for Continued Airworthiness 13659-ICA-00001, Issue 1 dated13 September 2021Maste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/10/2021	Active	10077353

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077356	AKV, Inc.		FAA STC SR02758LA	AS 350 B3	Installation of an AKV, Inc. Data Collector System, Kit P/NDCS1100	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List No. DCS1100-MDL Rev A, dated 3 April 2021Instructions for Continued Airworthiness, document number DCS1100-ICA,Rev. NC< (>,<)> dated 11 June 2021or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationPro...	FADEC equipped AS350 B3 helicopters with the Arriel 2B, 2B1and 2Dengines.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthin...	29/09/2021	Active	10077356
10077362	S4A SOLUTIONS FOR AVIATION, S.L			60	Mechanical installation of an Iridium antenna on the top fuselage of aLearjet 60	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Installed in accordance with Service Bulletin Ref: L60_028-12-19 Edition1 dated 21/7/2021; maintained in accordance with Maintenance ManualSupplement Ref: L60_028-12-30 Edition 2 dated 21/9/2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This design change only covers the mechanical installation of theantennaPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ orrepair will introduce no adverseeffect upon the airworthines...	29/09/2021	Active	10077362
10077400	S4A SOLUTIONS FOR AVIATION, S.L	REV. 1		CL-600-2B19	MMEL Update in CL850This modification comprises the MMEL update concerning the itemsinstalled for the SATCOM system(STC10074190).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-MMEL issue 2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels...	MASTER MINIMUM EQUIPMENT LIST SUPPLEMENT 604104-12-33 edition 02< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	None	18/10/2021	Active	10077400
10077413 (2004-12060)	MT-PROPELLER ENTWICKLUNG GmbH	REV. 1	LBA SA1415	SC-7 SERIES 3	Installation of MTV-37-() Propellers on Short Skyvan SC-7.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: CS-36 Amdt 5, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase and/or emiss...	According to MT-Propeller Master Documentation List No. E-3702 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-3704Rev. 0To be installed i.a.w. Installation Instruction Doc. No. E-3705 Rev. 0To be maintained i.a.w. MT-Propeller ICA Document No. E-3706 Rev. 0or later revisio...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	15/11/2021	Active	10077413
10077419	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.	REV. 1		SEE EASA APPROVED MODEL LIST	Portable ELT Honeywell RESCU 406SG installation in CabinRevision 1: Introduction of 767-300	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 Amdt 22, Sections25.601, 25.863, 25.869, 25.1301, 25.1309, 25.1353(c), 25.1360(b),25.1529sThe requirements for enviro...	MASTER DATA LIST JCAERO/MDL/0768 Issue 1.1Or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	The approval of this design changes do not allow the installation of anELT in open spaces in the cabin.	08/04/2022	Active	10077419

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077422	JET AVIATION AG			747-400	Cabin Reconfiguration.Modification of the existing VIP interior by - reconfiguring the lower lobe crew rest area into 5 Passengerrestrooms mini suites - reconfiguring the Main Deck Medical Room	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:The followingrequirements at CS 25 Amendment 24: CS25.25, CS25.29, CS25.301,CS25.303, CS25.305, CS25.307, CS25.321, CS25...	The change is defined with Revision B of the Master Data ListJBSL-M-03528MDL-001The aircraft shall be operated in accordance with Revision A of theAircraft Flight Manual SupplementJBSL-M-03528AFM-001or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	- FAA STC ST03018NY shall be installed prior to or concurrent with thisSTC.- before embodiment of this STC on an aircraft under the oversight ofEASA Member State, the FAA STC ST03018NY requires appropriate EASAapproval.Prior to installation of this change/ repair it must be determined thatthe interre...	06/10/2021	Active	10077422
10077432	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			767-300	B767 Zero Passenger ConfigurationThe modification reconfigures the Passenger Cabin into a Zero PassengerConfiguration by removing the seats and other cabin installations fromthe cabin and by implementing specific operational limitations.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision 0 of the Engineering Order documentEO_M154001156_JTU_24062021The aircraft shall be operated in accordance with Revision 1 of theAircraft FlightManual Supplement document AFS_M154001156_JTU_24062021The aircraft shall be maintained in accordance with Revision 1 ofl...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/10/2021	Active	10077432
10077436	DART AEROSPACE Ltd.	REV. 2	TCCA SH21-24	MBB-BK117 D-3	Emergency Floatation System Installation with (optional) IntegratedLiferafts.Revision 1: demonstration of compliance ofthe 'Emergency FloatationSystem P/N 654.6700 SeriesMBB-BK117 D-3 (H145)' to EASA CS-26 requirements CS 26.410 Issue 4, CS26.420(a) Issue 4 and CS 26.425 Issue 4.Revision 2: Demons...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:Revision 1:CS 29.1555(d)(2) Amdt.5, CS 29.1587(c) Amdt. 5Revision 2:CS 29.1529 Amdt.2, CS 29.1541 Amdt.2, CS...	Installation Instructions II145-6 Rev. A dated Jul 22nd, 2021;Airworthiness Compliance Report ACR145-3 Rev. B dated Jul22nd, 2021Revision 1:Master Document List MD145-5 Revision B dated 21st July 2023;Rotorcraft Flight Manual Supplement RFMS145-5 Revision B dated 5th July2023;Instructions for Conti...	The Dart Emergency Flotation system is approved as a ditching provisionaccording to CS 29.801 Amdt. 2. In order for the helicopter to be fullyapproved for ditching, additional equipment is required as follows:1) If the operator has Emergency Floats with integrated Liferaftsinstalled, then the follo...	23/07/2024	Active	10077436
10077483	ROCKY MOUNTAIN AIRCRAFT		TCCA SA21-6	DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300	Installation of 27" x 36" Fuselage Cut-out with FS 281 - 321 InternalCabin Access - Structures Provision Only as per TCCA STC SA21-6	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of the 27" X 36" Fuselage Cut-Out with FS 281 – 321Internal Cabin Access must be in accordance with Transport Canada CivilAviation (TCCA) approved Rocky Mountain Aircraft (RMA) ModificationInstruction E122110 Revision C, datedJanuary 20, 2021.Maintenance of the 27" X 36" Fuselage Cut-O...	"Flight with cover plate installed only"Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	19/10/2021	Active	10077483
10077485	S4A SOLUTIONS FOR AVIATION, S.L			EMB-145MP EMB-145LU, EMB-145MK EMB-145EU, EMB-145LR EMB-145, EMB-145EP, EMB-145ER EMB-135LR EMB-135BJ, EMB-135ER	INSTALLATION OF INTEGRATED COMMUNICATION UNIT HONEYWELL RCZ-833K & PCPOWER SYSTEM	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS25 Amendment 26,Sections 25.21, 25.26, 25.27, 25.301, 25.303, 25.305, 25.307, 25.321,25.337. 25.471, 25.561, 25.601, 25....	14517-18-02 Master Document List Rev 13/10/21, 14517-12-28 Flight manualsupplement Edition 03, 14517-12-30 Maintenance Manual Supplement Edition04Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	PC Power System must not be turned on below 10.000 ft(See AFM Suplement 14517-12-28 Edition 03)Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffec...	19/10/2021	Active	10077485

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077509	ARCHEION HOLDINGS, L.L.C.		FAA STC ST04375AT	747-8/-8F/SP 747-300/-300/-400/-400F 747-100/-200B/-200C/-200 F	Installation of Avionica satLINK MAX with optional Personality Module(avPM) in the Cabin Compartment overhead, and optional avRDC MAX QAR inthe EE Bay to provide 2 Iridium SATCOM ATS Voice channels, 1 IridiumSATCOM ATS Datalink FANS 1/A+ Data channel for Flight Deck use (CPDLC atRCP240 & ADS-C at RS...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 at amdt. 26: 25.1, 25.21(a)(1), 25.301, 25.303, 25.305(a)(b),25.307(a), 25.561(c)(d), 25.571(a)(b), 25.581, 25.601, 2...	Master Data List 160910-MDL Revision C, dated 7 June 2019 or later FAAapproved revision.FAA approved Airplane Flight Manual Supplement for Archeion Holdings,LLC160910-AFMS Revision A, dated 19 July 2019, or later FAA approvedrevisions.For maintenance and inspections, apply the following Archeion Hol...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/10/2021	Active	10077509
10077518	S-TEC CORPORATION		FAA STC SA09765DS	PC-6/C-H2 PC-6/B-H2 PC-6/B2-H4 PC-6/B2-H2 PC-6/B1-H2	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List ST-982-MDL-0001, Revision A, dated 5-03-21<(>,<)> orlater FAA approved revision.Airplane Flight ManualSupplement ST-982-AFMS-0001, Rev. -, dated5-05-21, or laterFAA approved revision.Instructions for Continued Airworthiness ST-982-ICA-0001, Rev. -, dated4-01-21, or later FAA appro...	This STC is applicable to all serial numbers for Pilatus Aircraft, Ltd.Models PC-6/B-H2, PC-6/B1-H2<(>,<)>PC-6/B2-H2, PC-6/B2-H4, and PC-6/C-H2.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed cha...	22/10/2021	Active	10077518
10077548	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03608NY	FALCON 2000EX FALCON 2000	Installation of Satcom Direct (SD) HUB 2.0 WiFi Hub and Wi-Fi antennas	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03608NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Dassault Aircraft Services Master Data List, F2XW-D0104-005 RevisionIR dated 14 July 2021, or later FAA Approved revision.2. Airplane Flight Manual Supplement (AFMS) F2XW-D0104-150, Revision IR,dated 14 July 2021 or later FAA approved revision supplements theAircraft Flight Manual.3. Instructions...	This STC is applicable to Dassault Aviation Model Falcon 2000EXairplanes except serial numbers 001 through 005 and 007 through 027.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or r...	25/10/2021	Active	10077548
10077551	UMLAUT ENGINEERING GMBH			757-200	BOEING 757-200 KA-BAND SYSTEM INSTALLATION AND CABIN WIFI NETWORKACTIVATIONThis STC installs a Honeywell Jetwave Ka-Band broadband satcom system(including ARINC 791 radome & adapter-plate).The structural modifications include:-Installationof internal structural reinforcements-Installation of extern...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): Enhanced Airworthiness Programme for AeroplaneSystems – ICA on EWIS (CRI SCH-01)Equivalent Safety Finding(s): ESF to CS 25.251(b) (CRI“...	-Master Document List ref. UM-AAW01-MDL-0001 Issue A-Certification Programme ref. P3-AAW01-CPR-0001 Issue D-Compliance CheckList ref. UM-AAW01-CRL-0001 Issue A-Flight Manual Supplement ref. UM-AAW01-FMS-0001 Issue A-Instructions for Continued Airworthiness ref. UM-AAW01-ICA-0001 Issue Aor later revi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/10/2021	Active	10077551
10077564	URBE AERO GmbH	REV. 1		B300	Flight Data Recorder (FDR) upgrade to Universal Avionics FDR-25, P/N1607-00-00Extension of Applicability to B300 S/N FL-279	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Urbeaero Engineering Order “FDR Upgrade”, document UA-DOE/F07, Project262, Rev. 02, dated 10.10.2022.Universal AvionicsCockpit Voice Recorder/Flight Data RecorderInstallation Manual, document 23-70-08, Rev. 4, dated 30 September 2019.or later revisions of the above listed document(s) approved/ accep...	Applicable only to Beechcraft B300 S/N FL-246 and S/N FL-279 equippedwith Garmin G1000NXi avionics suitePrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adv...	27/10/2022	Active	10077564

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077565	BOEING IRELAND LIMITED			787-8, 787-9, 787-10	Cabin Conversion for On-Seat Cargo	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Deviation(s): EASA CRI D-134 Deviation/Interpretative Material “CabinConversion for On-Seat Cargo” Issue 5, dated 20 Sept 2021.- The Type and OSD Certifica...	Change Approval Document Ref. BIL-00184-APP Rev 00 dated 20Oct 2021Certification Programme Ref. BIL-00184 Rev 03AFM Supplement Ref. BIL-00184-AFM02 Rev 02AFM Supplement Ref. BIL-00184-AFM03 Rev 02AFM Supplement Ref. BIL-00184-AFM04 Rev 02AFM Supplement Ref. BIL-00184-AFM05 Rev 02MMEL Supplement Ref...	The aircraft are limited to the carriage of cargo in the passenger cabinon economy class passenger seats. Occupancy of the passenger cabin isrestricted as defined in the Airplane Flight Manual Supplements,Section 4.1. Cabin crew operating aeroplanes modified by this STC mustcomplete airplane differe...	27/10/2021	Active	10077565
10077569	SIERRA INDUSTRIES Ltd.		FAA STC SA215RM	501	Installation of Extended Width Cabin Door	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Branson Aircraft Corporation List of Drawings and Documents, ExtendedDoor, Number 91500, Rev. F, dated 30 July 1981, orlater FAA approvedrevision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/10/2021	Active	10077569
10077571	ARCHEION HOLDINGS, L.L.C.		FAA STC ST04526AT	A330-343 A330-342 A330-341 A330-323 A330-322 A330-321 A330-303 A330-302 A330-301 A330-243 A330-223 A330-203 A330-202 A330-201	Installation of Avionica satLINK MAX with optional Personality Module(avPM) in the Cabin Compartment overhead, and optional avRDC MAX QAR inthe EE Bay. Existing aircraft systems optional interface/integrationinclude the Flight Deck Audio System (i.e. Pilot Crew Headsets), MCDUs[or IDUs], ATSU ACARS,...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 24: 25.1 (b), 25.29 (b), 25.301, 25.303, 25.305 (a)(b),25.307 (a), 25.561 (c)(d), 25.571 (a)(b), 25.581, 25.601...	Master Data List 181640-MDL Rev. D, dated 30 July 2021 or later FAAapproved revisions, to provide 2 Iridium SATCOM ATS Voice channels, 1Iridium SATCOM ATS Datalink FANS 1/A+ Data channel for Flight Deck use(CPDLC at RCP240 & ADS-C at RSP180), & 1 optional AOC Voice channel forcabin crew use.For main...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/11/2021	Active	10077571
10077573	S4A SOLUTIONS FOR AVIATION, S.L			60	Mechanical installation of a GPS/WAAS antenna on top of fuselage andinstallation of SBAS/GNSS sensor unit on a floor panel beneath cockpit.Electrical connection between the antenna and the sensor unit.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with Service Bulletin Ref. L60_029-12-19 edition02 dated 18/10/2021, maintained in accordance with Maintenance ManualSupplement Ref. L60_029-12-30 edition 03 dated 18/10/2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This design change only covers the installation of the GPS / WAASantenna, the SBAS/ GNSS unit and the electrical connection between them,any other electrical connection is out of scope.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repai...	28/10/2021	Active	10077573
10077574	GENESYS AEROSYSTEMS, INC.		FAA SR02230AK	SEE APPROVED MODEL LIST	Installation of Genesys Aerosystems, Inc. FlightLogic Electronic FlightInstrument System (EFIS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR02230AK.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the pr...	- Master Data List (MDL) Document Number 17-000025, Revision M, dated 16April 2021- Flight Manual Supplement Document ref. 17-230FMS-0450 (IDU-450 with9.0A), Revision A<(>,<) > dated 13 July 2021- Flight Manual Supplement Document ref. 17-230FMS-0680 (IDU-680 with9.0A), Revision A<(>,<) > dated 13 Jul...	- Installation is not permitted in Instrument Flight Rules (IFR) certified rotorcraft.- Installation is limited to having Primary Flight Display (PFD) locatedabove multi-Function Display (MFD).- Activation of Fuel Flow functions required installation of separatelyapproved fuel flow transducers.- Opti...	28/10/2021	Active	10077574

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077577	BERINGER AERO	REV. 2		F182P, F182Q, FR182 182R, 182S, 182T, R182, T182 182L, 182M, 182N, 182P, 182Q 182F, 182G, 182H, 182J, 182K 182A, 182B, 182C, 182D, 182E 180K, 182, T182T, TR182 180E, 180F, 180G, 180H, 180J 180, 180A, 180B, 180C, 180D	Installation of Beringer Wheels, axles, brake and master-cylinders.Rev 1: Improvement to the Master cylinder connectingparts with thepedals.Rev 2: Addition of RA-016.1 (6") frontwheel configuration for Cessna182 models with Airglas nose fork and 6" nose wheel installed per FAASTC SA02069AK/EASA 10...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed and maintained in accordance with ICA-STC-022 Rev. 4 dated 8November 2024 and BOM-STC-022 Rev. 3 dated 5 August 2024<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	For RA-016.1 (6") front wheel installation prerequisite installation ofFAA STC SA02069AK/EASA STC 10047367.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce noe...	29/01/2025	Active	10077577
10077594	STG AEROSPACE GERMANY GmbH	REV. 1		SEE EASA APPROVED MODEL LIST	Installation of Photoluminescent Safety Systems in CS-23 Aircraft types.Revision 1 accounts for the addition of TextronAviation Inc. Models1900, 1900C and 1900D to the AML.	CS-23 Am 5, CS-CCD Am 0 and CS-MMEL Am 0.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact onthe noise database.	Installation in accordance with STG Aerospace GmbH, Master Data List (MDL) ref. SGEU-1051-MDL-01, Rev C, dated 29 September 2023, and theService Bulletins referenced therein.Operation in accordance with STG Aerospace GmbH, Flight ManualSupplements (FMS) ref. SGEU-1051-FMS-01 Rev B and SGEU-1051-FMS-0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/10/2023	Active	10077594
10077595	AEROTEC & CONCEPT			777-300ER	Cargo in Cabin Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Deviation(s): D-LR-10 'Transportation of cargo in passengercompartments'The requirements for environmental protection and the associatedcertified noise and/a...	- AFMS AE20065AFMS Rev. 9, dated 2 Nov 2021-MMELS AE20065ST02 Rev. 2, dated 28 Oct 2021-CCOMS AE20065ST01 Rev. 8, dated 2 Nov 2021-ICA AE20065ICA Rev. 10, dated 2 Nov 2021-MDLAE20065MDL Rev. 1, dated 2 Nov 2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA sy...	The allowance to transport cargo in passenger compartment is limited to2 000 FH following installation of the change orto 31 July 2022,whatever occurs first.Aeroplanes modified per this STC are considered to be a "variant" to theB777-300ER passenger configurations. Cabin crew operating aeroplanesmo...	03/11/2021	Active	10077595
10077605	QUIET TECHNOLOGY AEROSPACE, Inc.			GIV-X G450, GIV-X G350	Replacement of the nose cowl assembly with a Quiet Technology Aerospacenose cowl assembly. The Quiet Technology Aerospace nose cowl assemblyconsists of a replacement of the OEM aluminum inner inlet barrel with aninner inlet carbon graphitesandwich construction barrel mated to areused aluminum OEM o...	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04522AT.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	Quiet Technology Aerospace document "Gulfstream G450 SeriesInlet CowlInner Barrel Replacement Master Drawing List," Report No. QTA 6401, Rev.B, dated February 11, 2021, and "G450Replacement Upgraded Inlet Cowlwith Composite Inner Barrel Assemble Procedure," Report No. QTA 6405,Rev. B, dated May 26...	This modification has been substantiated as a no acoustic change inaccordance with 14 CFR <(>&<)>21-93(b).Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no a...	04/11/2021	Active	10077605
10077612	QUIET TECHNOLOGY AEROSPACE, Inc.		FAA STC ST04464AT	EMB-550 EMB-545	Replacement of the inner aluminum barrel of the engine inlet cowl with aQuiet Technology Aerospace inlet barrel of carbon graphite sandwichconstruction	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04464AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Quiet Technology Aerospace document "Bombardier Challenger 300/350,Gulfstream G280 and Embraer Legacy 450-500 Inlet Cowl Inner BarrelReplacement Master Drawing List," Report No. QTA6301, Rev. B, dated 18 September 2019.2. "Bombardier Challenger 300/350, Gulfstream G280 and Embraer Legacy450/500 I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2021	Active	10077612

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077615	GDS AERO LLC		FAA ST02397CH	FALCON 2000, FALCON 2000EX	Installation of GDS Aero Tail Cone APU Firewall Assembly, P/N GF2APU-FW1	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any im...	Drawing List GF2APU-FW1-DL, Revision 4, dated January 16, 2007or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2021	Active	10077615
10077620	DOA AESGLOBAL LIMITED			737-800	Introduction of Full Economy Layout	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:The following pargraphs of CS 25 Amdt 4: CS 25.1301(a), CS25.1309(a)(b), CS 25.1351(a), CS 25.1353(a), CS 25.1431(a)The fol...	Master Data List, Doc. No. AES-737-6502MDL, issue 2Instructions for Continued Airworthiness, Doc. No. AES-TR-3084, issue 1and AES-TP-0374, issue 1CCOM Supplement No. 52, issue 1OSD CCD supplement, AES-OSD SUPPLEMENT 55, issue 1Or later revisions of the above listed document(s) approved/acceptedunder...	The following installations are not covered by this certificate and needto be concurrently embodied:• Introduction of cabin emergency floor path lighting and carpet• Installation of emergency equipment• Installation of interior cabin placardsPrior to installation of this change/repair it must be det...	08/11/2021	Active	10077620
10077665	DELTA ENGINEERING CORPORATION	REV. 3	FAA ST04240CH	777-300ER 777-300	2Ku Antenna InstallationThis project installs an Intelsat 2Ku Antenna. The Intelsat 2KuRadome/Antenna System includes structural provisions and installation ofthe transmit and receive antennas, an adapter plate and a radome.Revision 1: Transfer of the STC from INTELSAT INFLIGHT LLC to DeltaEngineeri...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): 14 CFR 25.251(b) – Vibration and BuffetingCompliance Criteria (Ref Transport Directorate ELOS Memo ENV15092-F-1).The requirement...	1. Delta Engineering Master Data List (MDL) D12525-21720 Revision AMdated 8 September 2023;2. Instructions for Continued Airworthiness, Electrical WiringInterconnect System Instructions, Doc. No. D12454-21720 Rev AC dated 21July 2023;3. FAA Approved Airplane Flight Manual Supplement Doc. No. D12443-...	Reference the Master Data List for additional limitations and conditionsas well as applicable serial numbers.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce n...	06/12/2023	Active	10077665
10077669	SEATON ENGINEERING CORPORATION		FAA STC SA01800SE	SEE FAA AML	Fabrication and installation of new or replacement of existinginstrument panel lights dimmer control.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Seaton Engineering Corp. FAA approved Master Drawing document 9750-002,dated May 10, 2007, or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	11/11/2021	Active	10077669
10077695	GVH AEROSPACE (IRELAND) LIMITED			EC135 T3 EC135 T2+ EC135 T2 EC135 T1 EC135 P3 EC135 P2+ EC135 P2 EC135 P1	Installation of Electro Optical System (EOS) EuroFLIR 410 in accordancewith Master Data List GVH-11968-01-MDL-01	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Rotorcraft Flight Manual Supplement GVH-11968-01-FMS-01 Issue 4Master Data List GVH-11968-01-MDL-01 Issue 3Major ChangeSummary and Declaration of Compliance GVH-11968-01-MOD-01Issue 2or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to helicopters with CDS/ CPDS cockpit variantsCAT A and NVIS operations are prohibitedInstallation of AirFilm Camera Systems, LLC Utility Step Mount (EASA STC10017058) is prerequisitePrior to installation of this change/repair it must be determined thatthe interrelationship between this chang...	16/11/2021	Active	10077695

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077712	C&L STC HOLDINGS LLC		FAA STC ST04177NY	EMB-145XR EMB-145MR EMB-145MP EMB-145LR EMB-145ER EMB-145EP EMB-135LR EMB-135KL EMB-135KE EMB-135ER EMB-135BJ	Installation of ALI LED Cabin Lighting, Cabin and Crew AC Power Outlets,LH Fwd Closet and Misc Cabin Modification on Embraer 135/145 passengeraircrafts.This STC consists in the Installation of ALI LED Cabin Lighting, Cabinand Crew AC PowerOutlets, LH Fwd Closet and Misc Cabin Modification onEmbraer...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI D-01 “Emergency Exit Marker aboveaisle – ESF”The requirements for environmental protection and the associatedcertified noise...	-Master Data List (MDL) E135-MDL-0026, Revision A-Aircraft Flight Manual Supplement (AFMS) Document E135-AFMS-0026,Revision IR-Instructions for Continued Airworthiness (ICA) Document E135-ICA-0026,Revision IRor later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in acc...	- Aeroplanes modified by this STC must be maintained in accordance with:Aerospace Design & Compliance, LLC Instructionsfor ContinuedAirworthiness (ICA) Document E135-ICA-0026, Revision IR or laterrevision-Aeroplanes modified by this STC must be operated in accordance with:Aerospace Design & Compli...	17/11/2021	Active	10077712
10077713	APTOZ EHF.			A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-243 A330-201/-202/-203	Conversion of Main Cabin to Cargo Area	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Deviation(s): D-60078394 ‘Transportation of cargo in passengercompartments’the following paragraph(s) at a later amendment:CS-MMEL at Issue 2 for the followi...	Instructions for Continued Airworthiness ICA251192-1 Rev C,dated 3 Nov2021AFM Supplement AFM251192-1 Rev D, dated 3 Nov 2021Master Data List MDL251192 Rev B, dated 3 Nov 2021CCOMICA251192-1-FAMS Rev C, dated 3 Nov 2021MMEL Supplement ICA251192-1-MMEL Rev IR, dated 27 Jul 2021or later revisions ofu...	The allowance to transport cargo in passenger compartment is limited to2 000 FH following installation of the change orto 31 July 2022,whatever occurs first.Aeroplanes modified per this STC are considered to be a “variant” to theA330-200/-300 passenger configurations. Cabin crew operating aeroplane...	17/11/2021	Active	10077713
10077720	SABENA TECHNICS BGC			A330-243	A330-200 CABIN Reconfiguration from 330 PAX (42B/C, 288 Y/C) to 269 PAX (18 B/C, 251 Y/C) with IFE Rave System Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25 at amendment 4:25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341,25.365, 25.561, 25.5...	-Master Data List, Aeroconseil document No. 40563-01-A-MDL-R00 dated 15November 2021-Instructions for continued airworthiness, Aeroconseil document No. 40563-01-A-ICA-R00 dated 22October 2021-Aircraft Flight Manual Supplement, Aeroconseildocument No. 40563-01-A-AFMS-R00, dated 15 November 2021or la...	Limitations as per §3 of Instructions for Continued AirworthinessAs a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik EASASTC No. 10014507 Rev. 0...	18/11/2021	Active	10077720
10077726	S4A SOLUTIONS FOR AVIATION, S.L			747-400F	LOPA Modification in B747 This design change consists in the replacementof the upper deck seats from aircraft by new ones with similarproperties and the same function.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	MDL LOPA Modification 747_112-18-02 Issue 3 of 06/11/2021<(>,<)>Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/11/2021	Active	10077726
10077730	AIRBUS HELICOPTERS CANADA LIMITED		TCCA SH20-49 ISSUE 2	MBB-BK117 D-3 MBB-BK117 D-2	Cabin Heat Outlets Control.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List MDL-20-003 Issue C, TCCA approved Jun 11th, 2021;Flight Manual Supplement FMS-AHCA-181 Rev. 1, TCCAapproved Jun 11th, 2021;Instructions for Continued Airworthiness ICA-AHCA-315 Rev. 1, TCCAaccepted Jun 11th, 2021;Certification Program CP-0416 Issue B, TCCA accepted Jun 11th, 2021...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2021	Active	10077730

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077745	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT, LLC		FAA STC SA03120CH	B300, B300C B200, B200C 200, 300	Installation of Fuel Flow and Engine Torque DC Transducers	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA03120CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Elliott Aviation Master Data List (MDL) Document No. MDL-3203-569,revision G dated 11 February 2020, or later FAA approved version.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/11/2021	Active	10077745
10077746	AVCON INDUSTRIES, Inc.		FAA STC SA04476CH	B300C B300	Installation of External Belly Radar POD and Upper SATCOM Radome	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avcon Industries, Inc. Master Data List 06201000, Revision (B), dated 27September 2021, or later FAA approved revision.Airplane Flight Manual Supplement 06207100, Revision (IR), dated 4October 2021, or later FAA approved revision.Instructions for Continued Airworthiness 06207200, Issue (0), dated 13...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/11/2021	Active	10077746
10077749	AEROTEC & CONCEPT			EMB-145	EMB-145 EVASAN STRETCHERS INSTALLATION (MEDEVAC)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-01 Medical Evacuation Configurationthe following paragraph(s) at a later amendment: CS25.301, 25.303,25.305, 25.307, 25.321, 25.331, 25.337, 25.34...	Master Data List AE21075MDL Rev.: 2 dtd. 15/11/2021AircraftFlight Manual Supplement AE21075AFMS Rev.: 2 dtd. 25/10/2021Instructions for Continued Airworthiness AE21075ICA Rev.: 2dtd. 25/10/2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	-Per AFM supplement AE21075AFMS-Per ICA supplement AE21075ICA - Installation is limited to layout configurations 21075C000-0001 and21075C000-0002 without Medical or Oxygen EquipmentPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair a...	23/11/2021	Active	10077749
10077750	AEROTEC & CONCEPT			DHC-8-402	DHC-8 EVASAN STRETCHERS INSTALLATION (MEDEVAC)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): D-01 Medical Evacuation Configurationthe following paragraph(s) at a later amendment: CS25.301, 25.303,25.305, 25.307, 25.321, 25.331, 25.337, 25.34...	Master Data List AE21076MDL Rev.: 2 dtd. 15/11/2021AircraftFlight Manual Supplement AE21076AFMS Rev.: 2 dtd. 25/10/2021Instructions for Continued Airworthiness AE21076ICA Rev.: 2dtd. 25/10/2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	-Per AFM supplement AE21076AFMS-Per ICA supplement AE21076ICA - Installation is limited to layout configuration 21076C00-0001 withoutMedical or Oxygen EquipmentPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviousl...	23/11/2021	Active	10077750
10077751	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST04508CH	BD-100-1A10	Installation of a Collins KuSAT-2000 Tail-Mounted SATCOM System and aKuKa Radome	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List (MDL), 1039410, Revision (F), dated 5 November 2021, orlater FAA approved revision.Airplane Flight Manual Supplement, 1040118, Revision (A), dated 30August 2021<(>,<) > or later FAA approved revision is a required part ofConfiguration 01 installation.Airplane Flight Manual Supplement...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/11/2021	Active	10077751
10077757	SCANDINAVIAN AVIONICS DESIGN ApS			A320-214 A319-133 A319-132, A319-133 A319-132	DLINK+ w/CPDLC installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: . CS 25 amdt 2 for the following paragraphs: CS 25.29; CS 25.301; CS25.303; CS 25.305; CS 25.307; CS 25.341; CS 25.561;...	AFM Supplement 2120617-AM Issue 4, dated 15 Nov 2021MMEL Supplement 2120617-ME Issue 1, dated 17 Jan 2020ICA Supplement2120617-CA Issue 1, dated 5 May 2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/11/2021	Active	10077757

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077817	L-3 COMMUNICATIONS INTEGRATED SYSTEL.P.		FAA STC ST9752SC-D	737-700	Installation of an executive interior:This STC consists in the installation of an executive interior withcustom rooms, seating, galleys, lavatories, entertainment systems andassociated equipment and systems in accordance with L-3 CommunicationsMaster Data List (MDL) 99010004-000 Rev AM	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: Appendix S of CS25Amendment 19 (paragraph S25.10 (a) & S25.50).The requirements for environmental protection...	- Master Data List (MDL) 99010004-000 Rev AM- Instructions for Continued Airworthiness (ICA) Document:1. “ST9752SC-D__MM-V2 Revision 12“2. „ST9752SC-D__MPSD Revision 12“- AircraftFlight Manual Supplement (AFMS) Document referenced STCST6752SC-D AFMS Revision 02or later revisions of the above listed...	- Aeroplanes modified by this STC must be maintained in accordance with:L-3 Communications Instructions for Continued Airworthiness (ICA)1. “ST9752SC-D__MM-V2 Revision 12“2. „ST9752SC-D__MPSD Revision 12or later revision.- Aeroplanes modified by this STC must be operated in accordance with:L-3 Commu...	02/12/2021	Active	10077817
10077827	UMLAUT ENGINEERING GMBH			747-8	747-8 Cargo Access HatchInstallation of a new access hatch and ladder from Main Deck Cabin toFWD Cargo Compartment	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Master Document List UM-ABI01-MDL-0001 issue A-Instructions for Cont. AW UM-ABI01-ICA-0001 Issue Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/12/2021	Active	10077827
10077828	LUFTHANSA TECHNIK AG			747-8	B747-8 - Cabin CompletionInstallation of an executive interior including several systems, roomsand interior components on the main deck. Upper deck is modified interms of installing telephones and power outlets into the existinginterior. The modification covers two configurations for the PrivateRoom...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): D-101 –VIP Interiorthe following paragraph(s) at a later amendment: EASA CS 25.1301,25.1309 and 25.1310 at amdt 2 for affectedT...	-Supplemental Type Design Document STDD00-20/10M Issue 01 Rev 00-AFM Supplement A-00-20/64-AFM Issue 02 Rev 00-Instructions for Cont AW A-00-20/64-ICA Issue 02 Rev 00-MMEL Supplement A-00-20/64-MMEL Issue 01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- The aircraft with this STC installed is certified for non-commercialuse only- EASA STC 10077827 “747-8 cargo access hatch” and Boeing ServiceBulletin 747-44-2031 “Installation of Radome and Structural Provisionsfor the Panasonic eXconnect Antenna System” must be installed prior orconcurrently.- UH...	02/12/2021	Active	10077828
10077830	LUFTHANSA TECHNIK AG			747-8	B747-8 - SDS InstallationInstallation of ELBIT Self DefenseSystem (SDS) “C-MUSIC”.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: EASA CS 25.1301,25.1309 and 25.1310 at amdt 2 for affected systems and equipmentThe requirements for environm...	-Supplemental Type Design Document STDD00-20/09M Issue 02 Rev 00-AFM Supplement A-00-21/08-AFM Issue 04 Rev 00-Instructions for Cont AW A-00-21/08-ICA Issue 03 Rev 00-MMEL Supplement A-00-21/08-MMEL Issue 01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	02/12/2021	Active	10077830
10077832	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		SA227-CC, SA227-DC	Installation of Garmin GA 35 GPS AntennaCase 1 – replacing an existing Trimble GPS antennaCase 2 – new antenna is installed	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with ASR-2021-041-IFI-10-00 Rev 00;Maintainedin accordance with ASR-2021-041-ICA-11-00 Rev 00<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This design change only covers the mechanical installation of theantenna.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthine...	14/12/2021	Active	10077832
10077833	DELTA ENGINEERING CORPORATION		FAA STC ST03195NY	757-200PF 757-200	Installation of Dual Rockwell-Collins GPS-4000S, ADS-B (Out),Transponder and Control Panel update	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 25 atamdt. 13: 25.571, 25.853, 25.981, 25.1529, 25.1581, 25.1583, 25.1585The requirements for environmental protection and the associatedcertified noise and/ or emissi...	Delta Engineering Master Data List 0145-08946-2377 RevisionI dated 11September 2017 or later FAA approved revisions toDelta EngineeringMaster Data List previously listed. The Instructions for ContinuedAirworthiness and Airplane Flight Manual Supplement as listed on theMaster Data List.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.EASA has not certified the interface of the GPS-4000S t...	20/12/2021	Active	10077833

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077834	S-TEC CORPORATION		FAA STC SA09741AC-D	YMF F5C	Installation of S-TEC System 55X Two Axis Automatic Flight ControlSystem	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09741AC-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Master Data List No. ST-945-MDL-0001, dated 10-03-12 or later FAAApproved revisions of the above data (28 Volt System).2. ODA Approved Airplane Flight Manual Supplement, ST-940-AFMS-0001,Revision -, dated 10-04-12 is required for YMF (WACO F5C) for S-TEC 55XTwo Axis Automatic Flight Control Syste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/12/2021	Active	10077834
10077840	AIRCRAFT SYSTEMS AND MANUFACTURING,Inc.		FAA STC ST11381DS	A321-231, -232 A321-211, -212, -213 A321-111, -112, -131	Installation of an Avionica WiFi System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: list CS 25 at amdt 4:25.869(a)(1)(4)CS 25 at amdt 26: 25.1, 25.21, 25.23, 25.25, 25.27, 25.301(a)(b), 25.303,2...	1. Aircraft Systems and Manufacturing, Inc. Master Data List5754-0000-00, Rev IR, dated 22 October 2021, or later ODA approvedrevision.2. Airplane Flight Manual Supplement Document No. 5754-2160-00, Rev IR,dated 7 September 2021, or later FAA approved revision.3. Instructions for Continued Airworthi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Prior or concurrent installation of STC 10076890 (FAA S...	15/12/2021	Active	10077840
10077845	JET AVIATION AG			787-8	VVIP Cabin Interior CompletionThis modification installs a VVIP cabin interior into a green Boeing787-8. The aircraft will be outfitted to accommodate 4 Flight Crew, 1Cabin Crew and 27 passengers. The cabin will comprise of severalcompartments typical of a VVIP cabin.	The Type and OSD Certification Basesfor the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s):D-1101 Injury Criteria for Side-Facing SeatsF-06 Security Protection of Aircraft Systems and NetworksF-0503 Non-rechargeable Lithium Bat...	JBSC-M-00189MDL-01 ISSUE 08 MASTER DATA LISTJBSC-M-00189AFM-01 ISSUE 03 AIRPLANE FLIGHT MANUAL SUPPLEMENTJBSC-M-00189ICA-01 ISSUE 01 INSTRUCTIONS FOR CONTINUED AIRWORTHINESSJBSC-M-00189CCS-01 ISSUE 09 CERTIFICATION COMPLIANCE SHEETor laterrevisions of the above listed document(s) approved/acceptedu...	Private Operation (Not-for-Hire, Non-Commercial)Non-SmokingAircraftMax occupancy: 27 Pax, 4 Flight crew, 1 Cabin CrewExterior Exit Marking - an approved exterior paint livery matching theexit configuration of the cabin considering the deactivated exits mustbe applied. Changes to the exterior exit m...	06/12/2021	Active	10077845
10077853	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special transportation of Airbus Helicopter H225 in NPA configuration (Nippon National Police Agency)Issue 1 of ATI modification ST25MOD020 (applicant’s reference) wasdeveloped, reviewed, tested and found compliant with the CertificationBasis to deal with non-Airbus sub-assemblies transport.On case-b...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Change Approval Sheet (CAS) ST25MOD020Ed53 Issue 1 dated 18 November2021- Change Certification Plan (CCP) ST25MOD020Ed53 Issue 6 – H225-NPAHelicopter Transport dated 15 November2021- Approved Document Dossier (ADD) ST25MOD020 Ed53_ADD Issue 3 includingAFM and WBM supplements as enclosed in Indepe...	The dangerous goods installed in the payloads have to comply with theIATA Dangerous Goods Regulation (or any relevant Aviation Authorityregulation).This approval covers the transportation of H225 helicopter in NPAconfiguration as describedin Airbus Helicopter Technical Note332N050019 issue B and co...	07/12/2021	Active	10077853
10077859	ROCKWELL COLLINS, Inc.		FAA STC ST01891AT-D	737-400 737-300	Installation of Collins VHF-700B/900B Transceiver and Collins CMU-900ACARS	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Collins Master Data List 99T014L002, Revision AG, dated 1 June 2005, orlater FAA approved revision.Airplane Flight Manual Supplement AFM-01029, dated 23 November 2000, orlater FAAapproved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Autoland operations below CAT I have not been demonstra...	08/12/2021	Active	10077859

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077861	SABENA TECHNICS BOD	REV. 2		A330-223	Cabin modification:Reconfiguration of the cabin area (S-25-4245) and communication center“Com Gouv NG3” (S-23-4242).Rev. 1: typos correctedRev. 2: removal of OSD limitation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Deviation(s): CRI D-132 “Exits with non-adjacent Cabin Attendant Seat”issue 3the following paragraph(s) at a later amendment: JAR 25 at change 14:25.1423Thec...	Master Document List MDL-S-23-4242 Issue AInstructions for Continued Airworthiness ICA-F3073-00-806 Issue CMaster Document List MDL-S-23-4245 Issue BInstructions for Continued Airworthiness ICA-F3073-05-003 Issue CAFM Supplement AFMS-F3073-00-004 Issue DMMEL Supplement MMELS-F3073-00-068 Issue Coru...	- The pre modification for this configuration is covered byEASA STC10032391- Aeroplanes modified per this configuration are determined to be anaircraft “variant” to the previous changes. Nevertheless, for Cabin Crewwho have not undergone training satisfying the approval of previousSTCs, the overall...	19/10/2022	Active	10077861
10077918	BOMBARDIER Inc.	REV. 2	TCCA STC SA21-48,ISSUE 1	BD-700-1A11 BD-700-1A10	Demonstration of T-PED ToleranceRev. 0This modification provides data to support operational approval oftransmitting portable electronic devices (TPED). The data can also beused in part support the installation / activation approval of awireless access point or other radiofrequency system using wire...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aircraft Flight Manual Supplement M869091 Revision NCAircraft Flight Manual Supplement M869093 Revision NCAircraft Flight Manual Supplement M869095 Revision NCAirplane Flight Manual Supplement R034097 Rev NCModification Data Summary M869000 Revision Aor later revisions of the above listed document(s...	This STC does not constitute an operational approval for the use ofportable electronic devices (PED) on board. Operational approval must beobtained by the responsible airworthiness authority.This STC does not constitute installation approval of a wireless radiofrequency system using wireless data te...	01/04/2025	Active	10077918
10077920	SABENA TECHNICS BGC			A330-343	A330-300 CABIN Reconfiguration from 285 PAX (30 B/C, 255 Y/C) to 367 PAX (367 Y/C)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25 at amendment 4:25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341,25.365, 25.561, 25.5...	- Master Data List, Aeroconseil document No. 40211-01-A-MDL-R00- Instructions for continued airworthiness, Aeroconseil document No. 40211-01-A-ICA-R00or later revisions of theabove listed document (s) approved/ acceptedunder the EASA system.	Limitations as per §3 of Instructions for Continued AirworthinessAs a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik EASASTC No. 10014507 Rev. 0...	13/12/2021	Active	10077920
10077926	GENESYS AEROSYSTEMS, INC.		FAA SR01673SE	EC 120 B	Installation of Genesis Aerosystems Electronic Flight Instrument System (EFIS) and associated equipment	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SR01673SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	- Master Data List (MDL) 651-045049, Revision G, dated 21 April 2021- Rotorcraft Flight Manual Supplements (RFMS) 17-673FMS-0450 and17-673FMS-0680, Reision A,dated 04 August 2021Rotorcraft Instructions for Continued Airworthiness (RICA) 17-120004,Revision A, dated 02 April 2021 and 17-120005, Revisi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/12/2021	Active	10077926
10077930	LUFTHANSA TECHNIK AG			A319-133	LAIRCM GPS Antenna Provisions	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Design Document STDD53-21/05M Issue 02, Revision 00,dated 6 Dec 2021Instructions for Continued Airworthiness A-00-21/64-ICA Issue 01,Revision 00, dated 3 Dec 2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/12/2021	Active	10077930

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077931	GARMIN INTERNATIONAL, Inc.	REV. 1	FAA SR02647SE	AS 350 BA AS 350 B2, AS 350 B3	Installation of Garmin GFC 600H Flight Control SystemRev. 1: Approval reference for OSD-FCD and removal of associatedlimitation on EASA certificate.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): adopted FAA 27-043-SC (System Safety).- The following paragraph(s) at a later amendment: In addition to theSTC Certification Basis rep...	Master Drawing List, 005-01095-00 Rev. 1Rotorcraft Flight Manual Supplement, 190-02081-02 Rev. 3Instructions for Continued Airworthiness, 190-02081-03 Rev.1Master Minimum EquipmentList, 190-02081-E0 Rev. 1005-01095-E3, “EASA CS-FCD CERTIFICATION PLAN GARMIN GFC 600H IN AIRBUSHELICOPTERS AS 350 BA/B2/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/05/2022	Active	10077931
10077943	T.P.S. S.P.A.			AS 350 B3 AS 350 B1, AS 350 B2	Baskets installation on AS350 series	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List TPS350-1200-Mdl-00Rotorcraft Flight Manual Supplement TPS350-1200-RFMS-00Instructions for Continued Airworthiness TPS350-1200-ICA-00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/12/2021	Active	10077943
10077945	S4A SOLUTIONS FOR AVIATION, S.L			A330-243	Passenger Seats RearrangementPassenger seats rearrangement in the AFT cabin. It includes thereplacement of five Y/C passenger seats by three double passenger seatsmodel 6810 by Safran, to be used as Crew Rest Area when required.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- MDL Passenger Seats Rearrangement in Airbus A330 Ref. 330_251-18-02Issue 3 of 15/12/2021- FMS Passenger Seats Rearrangement in Airbus A330 Ref. 330_251-12-28Issue 1 of 15-12-2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/12/2021	Active	10077945
10077950	ELBE FLUGZEUGWERKE GmbH	REV. 1		A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	A330P2F Removal of Panasonic GCS Antenna in the non-affected area of P2FSTC, including the necessary structural modification.A330P2F – Removal of Panasonic GCS Antenna Rev.1Rev. 1introduces a new Configuration (Configuration 3) for thestructural modification on the fuselage (G534R1000-that is requi...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Initial IssueCertification Report - Ref. EFW-TIP-0171-001 Rev. B<(>,<)>Engineering Order - Ref. EFW-EO-0171-001 Rev. A<(>,<)>ALS Part 2 Supplement - Ref. A330P2F-ALS-ALI-CLC-ENV R00<(>,<)>ICA Manuals Applicability Substantiation Report - Ref. EFW-E-JAD-00039Rev. A.Rev. 1Engineering Order – Ref. EFW-...	Current STC shall be only applied to aircraft that have thefollowingSTCs embodied:EASA STC10037167 Rev.1 - STC for Panasonic GCS STC InstallationEASA STC10050808 - STC for Panasonic Global Communication Suite SystemCurrent STC shall be applied in conjunction with:EASA STC 10063798 (STC for A330 P2F...	06/06/2024	Active	10077950
10077952	AIRBUS HELICOPTERS	REV. 1		AS 365 N3	Design change no 4006, installing an operator mission console ADUANASSTD2 in the forward area of the cabin.Rev 1: Changed STC Holder	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Document no. 365H043024 “Certification Plan for Civil Modification No:4006 Title: ADUANAS OPERATOR CONSOLE STD2”, IssueB, dated 10.09.2021.Master Document List no. DL 365H000003 “Master Document List for ADUANASAS365N3+ H/C mission console ST2”, Issue D, dated 09.12.2021.Flight Manual Supplement no...	Modification 2015M-AS365N3 shall be installed before the implementationof this design change.	24/03/2022	Active	10077952

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10077983	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04306AT-D	SEE FAA AML	Installation of Tailwind 500 Satellite TV System in accordance withGulfstream Aerospace Corporation Index List as referenced on FAAApproved Model List (AML) GC73507C003.Rev. 1 corrects typos.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA Approved Model List (AML) GC73507C003, Revision A, dated 08 December2021.Refer to the AML for additional limitations and conditions asapplicable.FAA / ODA accepted Instructions for Continued AirworthinessFAA / EAR approved EWIS Instructions for Continued AirworthinessFAA / ODA approved AirplaneO...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA AML GC73507C003 Revision A, dated08 December 2021.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and...	21/12/2021	Active	10077983
10077984	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH			429	Installation of Mission Management System Workstation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Approved by EASA:- Flight Manual Supplement, 00054-DO-MZ-FMS-000, Issue 01 dated 1stDecember 2021Accepted by EASA:- Installation Instruction Index, 00054-DO-MZ-INI-000, Issue 01 dated25th November 2021- Instructions for Continued Airworthiness, 00054-DO-MZ-ICA-000, Issue01 dated 25th November 2021-I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/12/2021	Active	10077984
10077989	ETIHAD AIRWAYS ENGINEERING L.L.C.			777-300ER	CARRIAGE OF CARGO IN PASSENGER CABIN	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Deviation(s): D-130 “Transportation of cargo in passengercompartments” Issue 3.The requirements for environmental protection and the associatedcertified no...	Master Document List EB7-20251261-DL01 Issue 4AFM Supplement EB7-20251261-PA06 Issue 6MRBR Supplement EB7-20251261-PA04Issue 5OSD CCD Supplement EB7-20251261-TR03 Issue 7or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	: - The allowance to transport cargo in passenger compartment is limitedto 2000 FH following installation of the changeor to July 31st 2022,whatever occurs first.- Aeroplanes modified per this STC are considered to be a “variant” tothe B777-300ER passenger configurations. Cabin crew operating aerop...	16/12/2021	Active	10077989
10077991	EIRTECH AVIATION SERVICES LIMITED			ATR 72-212 A	Fuselage Protection for Unpaved Runway for Belly Fuselage Skin Panels.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDL-1579-001 issue 2Instructions for continued airworthiness AMS-1579-001 Issue 2or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/12/2021	Active	10077991
10077994	L3 AVIATION PRODUCTS, INC	REV.1	FAA STC ST02718LA	SEE FAA AML	Modification to replace the existing standby instrument with L3HarrisEFD-750 Electronic Flight DisplayStandby Instrument System with optional Air Data Computer ADC-4000 andoptional Magnetometer MAG-500	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA approved AML STC Master Data List (MDL) as defined in the AML No.ST02718LA<(>,<) >dated 14 May 2021, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement (AFMS) and Instructionsfor Continued Airworthiness(ICA) are defined in the AML No. ST02718LA, dated 14 May 2021, or la...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	17/12/2021	Active	10077994

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078005	APTOZ EHF.			747-400	Conversion of Main Cabin to Cargo Area	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Deviation(s): D-130 'Transportation of cargo in passengercompartments'- The following paragraph(s) at a later amendment: . JAR 25 at change 11 for theJ...	Instructions for Continued Airworthiness ICA251218-1 Rev A,dated 16 Dec2021AFM Supplement AFM251218-1 Rev A, dated 9 Dec 2021Master Data List MDL251218 Rev IR, dated 16 Dec 2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The allowance to transport cargo in passenger compartment is limited to2 000 FH following installation of the change orto 31 July 2022,whatever occurs first.Prior to installationof this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	17/12/2021	Active	10078005
10078006	AIR ALLIANCE GmbH	REV. 1		PC-12, PC-12/45 PC-12/47, PC-12/47E	Transponder AntennaInstallation This design change covers the installation of two SensorSystems S65-5366-7L transponderantennas to a Pilatus PC 12 Series. Oneantenna is installedon the top and one at the bottom of the aircraft inthe areaof the pressurized cabin.Revision 1 adds an additional optio...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:Amdt 4:CS 23.301, CS 23.305, CS 23.561, CS 23.571, CS 23.573, CS 23.575, CS23.613, CS 23.627, CS 23.1306.The requirement...	Master document list: 2021-010-MDL, Revision 01Installationinstructions: 2021-010-IM, Revision 01Instructions for continued airworthiness: 2021-010-ICA, Revision 02Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The in installation of the new L-Band transponder antenna is performedas a provision only. Connection to existing aircraft equipment is notcovered by this design change and requires separate approval.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenp...	23/03/2023	Active	10078006
10078015	ALPINE AEROTECH LP		TCCA SH20-40 ISSUE 1	212, 412, 412EP 205A-1	Installation of Garmin GTX 3x5 ADS-B Transponder	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Data List, AAL-280-084-001 Rev. B, TCCA-approved 25 November2021;- Rotorcraft Flight Manual Supplement, AAL-280-085-401 Rev. A,TCCA-approved 25 November 2021;- Instructions for Continuing Airworthiness, AAL-280-085-701 Rev. A,dated 29 October 2020or later revisions of the above listed docum...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/12/2021	Active	10078015
10078016	BOGGI AERONAUTICS S.R.L.			AS 350 B, AS 350 BB AS 350 B3, AS 350 BA, AS 350 D AS 350 B1, AS 350 B2	External Mirror System 350P025 installed on RHS and/or LHS as describedin the Configuration Control Document 350P02520-CCD.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Configuration Control Document 350P02520-CCD-01, Issue 1Master Document List 350P02520-Mdl-00, issue 0RHS and/or LHS heated and movable mirror, RHS and/or LHS not electrifiedmirrorRotorcraft Flight Manual Supplement 350P02520-FMS-10, issue0Instructions for Continued Airworthiness 350P02520-ICA-10,R...	This STC includes the external mirror configuration previously approvedwith EASA STC 10068606.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	17/12/2021	Active	10078016
10078017	HAVACILIK MUHENDISLIK VE SERTIFIKASHIZM ETLERI SANAYI VE TICARET ANONIMSIRKETI			A340-542	Installation of VIP interior furnishingsFour interior doorsare installed in an existing meeting room.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25 Amdt 25_25.813(a)(d)(e)(f), 25.1729.The requirements for environmental protection and the associatedc...	Master Document List, MDL-TS1150, Issue D, dated 15th December 2021Airplane Flight Manual Supplement, TS1150R50, Issue IR, dated 14thDecember 2021or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/12/2021	Active	10078017
10078020	SPAES GmbH & Co. KG			429	Ascom, Tetra, GPS Antenna Installation	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS27.1316 Amdt.8 andCS27.1317 Amdt. 8.The requirements for environmental protection and the associatedcertified noise an...	Instruction for Continued Airworthiness ICA-429-461-29-01 Rev.1.1 dated03/11/2021Rotorcraft Flight Manual Supplement FMS-429-461-23-01 Rev. 1.0 dated17/09/2021Master Document List MDL-429-461-23-01 Rev. 1.7 dated 17/12/2021or later revisionsof the above listed document(s) approved/acceptedunder the E...	SPAES GmbH & Co. KG Minor Change No. 0459 "Installationof Tactical Radios" is a prerequisite for this installation.The electromagnetic compatibility of the new installation with theoptional HF, ADF1 & ADF2, DME, CVR and FDR systems was nottested andnot accounted for.Prior to installation of this ch...	20/12/2021	Active	10078020

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078021	BOEING IRELAND LIMITED	REV. 3		737-800	Deactivation and removal of GoGo ABS Ku-Band Antenna (FAA STCST03191NY), including removal of all structural provisions, filling theredundant fastener holes in the frame, reinforcement of stringers(limited aircraft effectivity) and a localcrown skin replacement inSection 46Rev. 1 corrects the Limit...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List provided in Change/Repair Approval Document, Doc:BIL-00204-APP Rev. 07Instructions for Continued Airworthiness, Doc: BIL-00204-ICA00 Rev. 01or later revisions of the above listed document (s) approved/ acceptedunder the EASAsystem.	Aircraft are to be maintained in accordance with Boeing Ireland Limitedinstructions as detailed below:Aeroplanes modified by this STC must be maintained in accordance with:Instructions for Continued Airworthiness, Doc: Doc: BIL-00204-ICA00.Prior to installation of this change/repair it must be deter...	23/05/2025	Active	10078021
10078027	LUFTFAHRTTECHNIK MICHAEL ENDER	REV. 1		TAIFUN 17E	Retrofit of Rotax 914F3 Engine with MTV-21-A-C-F/CF175-05 PropellerLTME-STC-299-1/2018	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flughandbuch für den Motorsegler Taifun 17 E nach nachLTME-STC-299-1/2018<(>,<)>Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/02/2022	Active	10078027
10078032	SWISS HELICOPTER ENGINEERING AG			KA-32A11BC	Installation of an additional bubble window on the right-hand side.Installation of a bubble window with enhanced curvature for the rightdoor of a Kamov KA-32A11BC, which is already equipped with a smallerradius bubble window as original installed part.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- To be installed i.a.w. Master Document List No. 10_SHE_MDL_2019011_rev0<(>,<)> andInstallation Bulletin No 6.2 SHE Installation Bulletin 2019011 rev0<(>,<)>- To be operated i.a.w. SHE AFMS Doc. 11.1.1_SHE_AFMSUPPL_2019011_rev1<(>,<)>- To be maintained i.a.w. SHE AMMS Doc. 11.1.2_SHE_AMMSUPPL_201901...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/12/2021	Active	10078032
10078041	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		AW139	RDR-7000 Weather Radar installationThe RDR-7000 Weather Radar installation is a replacement of the existingPrimus 70x and Primus 660 weather radars installed on the AW139helicopters Long Nose configuration.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	-,,Flight Manual Supplement 3000035-AM A, Issue 3-,,FlightManual Supplement 3000035-AM B, Issue 1-,,Certification Documents List 3000035 DOC, Issue 3-,,Drawing List 3000035-DL , Issue 3-,,Instructions for Continued Airworthiness 3000035-CA A, issue 2-,,Instructions for Continued Airworthiness 3...	The Installation of the RDR-7000 weather radar is limited only to thefollowing AW139 helicopter S/N's (Long Nose Configuration) :31201 and higher41201 and higherPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevio...	02/05/2022	Active	10078041
10078052	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			ERJ 190-100 ECJ	Certification of Alternative Life Raft on Lineage 1000	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): Non-rechargeable Lithium Battery Installations.The requirements for environmental protection and the associatedcertified noise and/ or emissions l...	- MODE00381_MDL rev. 1 Master data List-MODE00381_ICA1AXY rev. 2 Instruction for Continued AirworthinessOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/01/2022	Active	10078052
10078055	S4A SOLUTIONS FOR AVIATION, S.L	REV. 1		EMB-135LR, EMB-145LR	IRIDIUM ANTENNA INSTALLATIONRev 1: Maintenance interval inspections update	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25 Amdt. 26 Sections25.1, 25.21, 25.23, 25.25, 25.27, 25.29, 25.251, 25.301, 25.303, 25.305,25.307, 25.321...	145_522-18-02 Master document list (02/08/2022) 145_522-12-30 Maintenance Manual Supplement Modification, Edition 02or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	See ALS in Maintenance Manual Supplement 145_522-12-30 Edition 02.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of t...	04/08/2022	Active	10078055

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078064	LUMA TECHNOLOGIES LLC		FAA STC ST02722SE	DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Installation of LT-4098 series Integrated LED Display Paneland/orassociated LT-2201 series LED Pushbutton Switches	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02722SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List (MDL) MDL-4098-001, Revision A, dated 20 October2020, or later FAA-approved revision.2. Instructions for Continued Airworthiness (ICA) ICA-4098-001, RevisionIR, dated 29 July 2019, and/or ICA-2201-001<(>,<)> Revision IR, dated 29July 2019, as applicable, or later FAA-accepted rev...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/01/2022	Active	10078064
10078067	LEARJET Inc.		FAA STC SA8193NM-D	BD-700-1A10	Installation of wiring provisions and structural provisionsfor a WingCollision Avoidance System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA8193NM-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the o...	Master Drawing List GC31005001, revision B dated 10/03/01 or later FAAapproved revision.	The equipment for which these provisions are intended, havenot beencertified. Additional EASA approval is required forthe installation ofthese equipment and must be evaluated toassure satisfactory compliancewith the applicable airworthiness standards.Prior to installation of this change/repair it...	05/01/2022	Active	10078067
10078070	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC SA01964WI	SEE FAA APPROVED MODEL LIST	Modification of Rockwell Collins Radio Interface Unit (RIU), SXMReceiver and Pro Line Fusion Display System SoftwareRev. 1: provides minor software updates to the Flight Display SoftwareApplication (FDSA), Engine Indication Crew, AwarenessSoftware (EICAS),IMA Configuration Index Table (ICIT)<(>,<)>...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	(1). FAA Approved Model List (AML) RCA-0671, Revision (-), dated 7December 2021;(2). Instructions for Continued Airworthiness RCA-0673, Revision (-),dated 13 August 2021 or later FAA approved/accepted revision for items(1) and (2).(3). Airplane Flight Manual Supplement C90GTi RCA-066S, Revision (-),...	Aircraft affected by Airworthiness Directive 2021-05-17 must be equippedwith software specified in Rockwell Collins Service Information LetterFDSA-6500-19-1 prior to installation of this type design change.For model specific limitations, see AML RCA-0671, Rev. (-), or laterapproved revisions.This ST...	26/09/2024	Active	10078070
10078131	ASI INNOVATION			MBB-BK117 C-2	Installation of multipurpose “POD SC2” on the LH multifunction arm mountP/N R853-001.12100-00.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Programme ASI-CP-0567-04;STC Data List ASI-SDL-0567-01;Master Drawing List ASI-MDL-0567-02;RFM SupplementASI-AFM-0567-00;Maintenance Planning Supplement ASI-MPS-0567-00:Installation Instructions per ASI-SB-EC145-2500-0567-01or later revisions of the above listed document(s) approved/a...	The multipurpose POD SC2 installation is certified as a provision for ageneric payload only. Any further installation inside or outside the podwill require a specific airworthiness approval.The multipurpose POD SC2 installation is only certified for Category Band day/ night VFR operations.Prior to in...	13/01/2022	Active	10078131
10078133	NORTHERN AVIONICS S.R.L.			757-200, 757-300	Wi-Fi WAvES installationInstallation of Wifi LAN for IFE ondemand content distribution toPortable Electronic Devices.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 Initial Issue,paragraphs 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.561,25.601, 25.603, 25.605, 25.609, 25...	- Project Description NAV0635/1 Rev. 2- AFM Supplement AFMS-NAV0635 Rev. 1- Instructions for Continued Airworthiness ICA-NAV0635 Rev. 0- Master Document List MDL0635 R3or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	As per the AFM Supplement AFMS-NAV0635 Rev. 1, demonstratedcomplianceof of the WAvES with the airworthiness requirements related to thewireless system does not constitute approval for the use of the T-PED onboard.Prior to installation of this change/repair it must be determined thatthe interrelatio...	13/01/2022	Active	10078133

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078142	TEAM J.A.S., Inc.dba PMA DESIGN AND MANUFACTURING		FAA SA04458AT	DHC-6 SERIES 400 DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of a PMA Design and Manufacturing nose landinggear (NLG) shock strut assembly, PDM71-300-STC, as a direct replacement for theoriginal equipment manufacturer (OEM) NLGshock strut assembly.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except when amended by additional or lateramendments if indicated on FAA STC SA04458AT.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- Master Document List, PDM-MDL100, Revision C, dated 15 April 2019- Instructions for Continued Airworthiness (ICA), PMA Design andManufacturing Document Number,PDM-ICA107, Revision B, dated 15 April 2019or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accorda...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/01/2022	Active	10078142
10078145	HELI-ONE (NORWAY) AS	REV. 1		AS 365 N3	Design change AHSE-72010, installing a CMA-9000 FMS and dual CMA-5024GNSSU GPS receivers and relevant antennas on AS 365 N3 helicopters,allowing the following: LNAV capability: RNP2 for enroute continental,RNP1 for arrival (STAR) and departure (SID), RNP0,3 for enroutecontinental, arrival (STAR) and...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: Elect to comply toCS-ACNS ACNS.C.PBN.101 to ACNS.C.PBN.2150, Issue 2.The requirements for environmental pro...	Dwg AHSE-72011 “CMA-9000 FMS Installation Master Drawing”Document no. AHSE-72015 “Certification Programme”, Revision B,dated07.12.2021Rotorcraft Flight Manual Supplement no. SUP.H1No.I.331 “Aircraft FlightManual Supplement CMA-9000 FMS Installation Project 72010”Document no. AHSE-72035 “Instruction...	OEM installation of Rockwell Collins MFD255 EFIS is a pre-requisite forthe implementation of this design change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduc...	19/01/2022	Active	10078145
10078158	ACC COLUMBIA JET SERVICE GMBH	REV. 5		A340-311/-312/-313 A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	Installation of In-Service Aircraft for a Global Observing System(IAGOS) P2 in A330 and A340 aeroplanes – Package P2bRev. 1 documentation updated as per minor change approvalMCA_P2b_22-91267_rev0Rev. 2 documentation updated as per minor change approvalMCA_P2b_23-90402_rev0Rev. 3 is a correction of a...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDOCL_P2b_21-9001_rev 6;Master DocumentList MDOCL P2b_24-90259 rev0;Master Document List MDOCL_P2b_24-90259 rev0Master Drawing List MDRWL_P2b_21-9001_rev 3;Instructions for Continued Airworthiness ICA_P2b_21-9001_rev4;or later revisions of the above listed document(s) approved/ac...	Pre-condition of the installation of this design change is modificationof an aeroplane to incorporate either EASA STC 10045974 (IAGOS Package 1for A330 aeroplanes) or EASA STC 10028070 (IAGOS Package 1 for A340aeroplanes) and EASA STC 10051908 (for both, A330 and A340, aeroplanes).Prior to installat...	17/04/2024	Active	10078158
10078169	AIRBUS HELICOPTERS UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	EC135 T3	Powerline Mission Equipment and Load Carrying ComponentsInitial Issue:Addition of Type 4b and 4c Workstation Basket forstatic powerlineoperations (basket deposited on powerline) to the STC 10065679 Revision5 previously approved under EASAregimeRevision 1:Introduction of revised Fatigue Life Limita...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-27 at Amendment 2for 27.605(a), (b); 27.619(a), (b); 27.625(a), (b), (c), (d) and27.1585(a) / CS-27 at A...	Initial Issue:Design Compliance Reports:- Certification Programme DCP/1353004-02 Issue DDesign Definition:- Master Record Index MRI/ 1353060-02 Issue A. Type 4b-400 Basket- Master Record Index MRI/ 1353061-02 Issue A. Type 4b-600 Basket- Master Record Index MRI/ 1353062-02 Issue B. Type 4c BasketOperat...	Limited to helicopters with CPDS cockpit variant.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/09/2022	Active	10078169
10078181	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA ST04333AT-D	GIV, GIV-X, GV, GV-SP	Installation of Satcom Direct Gateway and WiFi Hub System on GulfstreamG-IV, GV, GIV-X and GV-SP model aircraft.Rev. 1 corrects Technical Documentation references.Rev. 2 corrects Technical Documentation reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	• Supplemental Type Certificate (STC), ST04333AT-D, Installation ofSatcom Direct Gateway and WiFi Hub System, Date Amended October 12,2020.• Index List ref. CE512038015 Revision A, dated October 12, 2020.• Airplane Flight Manual SupplementCE41203M012, Revision (-), datedJune 8, 2020 for GulfstreamM...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/02/2022	Active	10078181

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078182	AIRBORNE TECHNOLOGIES GmbH			DHC-6 SERIES 400	STC-AT-150 DHC-6 MX-25 IntegrationA L3 Wescam MX-25 camera is installed in the nose of the aircraft. Theassociated supporting equipment as commander Workstation is installed inthepassenger cabin.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Master Data List, Change Approval STC-AT-150, Document NumberSTC-150-G-AS, Rev. 0Flight Manual Supplement for DHC-6 Series 400, MX25 Integration,Document Number STC-150-G-AFM, Rev. 1Maintenance Manual Supplement for DHC-6 Series 400, STC-AT-150 DHC-6MX25 Integration, Document Number STC-150-G-AMM, R...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/01/2022	Active	10078182
10078190	AVIATION SPECIALTIES UNLIMITED, INC		FAA SR01634SE	AB412, AB412 EP 212, 412, 412EP	EASA Validation of the Night Vision Imaging Systems (NVIS) SupplementalType Certificate (STC) SR01634SE	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Project Specific Certification Plan (PSCP) ref. ASU-PSCP-AB412-25808Revision IR, dated 01/06/21.Rotorcraft Flight Manual (RFM) Supplement ref. FMS-412004-6 Revision J,dated 23/06/2021 and approved by the FAA on 22/01/2022.Instructions for Continued Airworthiness (ICA) document ref.ICA-412004-4 Revis...	Design change limited toRotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonlynamed NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the cockpit or cabin configura...	26/01/2022	Active	10078190
10078191	3S CERTIFICATION, LLC		FAA STC SA00028MC	PC-12/47E	Installation of non-essential antenna and radome.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00028MC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Sierra Nevada Corporation (SNC), Master Data List (MDL) 0126-00-9357Rev A, dated 08 July 2020 or later FAA approved revision.2. For configurations 01260000-01 through -04 defined in design datalist MDL-01260001, the following manuals apply: Airplane Flight ManualSupplement (AFMS), SNC document nu...	The approval is limited to aircraft serial numbers 1186 and1263.Configurations 01260000-01 is approved for safe carriage of equipmentonly. You must get additional FAA approval tomake the equipmentoperational. The FAA must functionally evaluate these configurations toensure they comply with the app...	26/01/2022	Active	10078191
10078215	SIERRA NEVADA CORPORATION		FAA STC SA00030MC	PC-12/47E	Installation of non-essential radio rack, communications equipment andantennas	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00030MC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Sierra Nevada Corporation (SNC) Master Drawing List, Document NumberMDL-03030001, Revision E, dated 18 April 2012, FAA approved 11 July 2012or later FAA approved revision.2. Instructions for Continued Airworthiness, Document 03039305, Rev B,dated 3 July 2012, FAA approved 11 July 2012 or later FA...	The approval is limited to aircraft serial numbers 1186 and1263.This STC is intended for Military, Public, or Government Use AircraftOnly. Installation of this system on aircraftfor commercial use isprohibited.Prior to installation of this change/repair it must be determined thatthe interrelations...	01/02/2022	Active	10078215
10078217	SIERRA NEVADA CORPORATION		FAA STC SA00097MC	PC-12/47E	Installation of antennas and provisions to mount antennas	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00097MC.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Sierra Nevada Corporation (SNC) Master Drawing List<(>,<)> DocumentNumber MDL-0198-00-9316<(>,<)> Revision D, dated 14 January 2014<(>,<)>FAA approved 21 February 2014<(>,<)> or later FAA approved revision.2. Instructions for Continued Airworthiness, Document No. 0198-00-9303,Rev C, dated 13 Janu...	The approval is limited to aircraft serial numbers 1186 and1263.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repairwill introduce no adverseeffect upon the airworthiness of th...	01/02/2022	Active	10078217

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078220	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			737-900 737-600, 737-700, 737-800 737-300, 737-400, 737-500	Integration of cargo seat bags for transportation of cargo in Boeing 737“CLASSIC” AND “NEXT GENERATION” aeroplanes.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Deviation(s): CRI D-01” Transportation of cargo in passengercompartments”.The requirements for environmental protection and the associatedcertified noise an...	J & C Aerospace Master Data List JCAERO/MDL/ 0689J & C Aerospace Aircraft Flight Manual Supplement JCAERO/AFM/ 0689-1J & C Aerospace Aircraft Maintenance Manual JCAERO/AMM/ 0689-1.	The allowance of transport cargo in passenger compartment is limited to2 000 flight hours following installation of thechange or to 31 July2022, whatever occurs first.	02/02/2022	Active	10078220
10078259	INNOVATIVE SOLUTIONSAND SUPPORT, Inc.		FAA STC ST00399BO	767-300F 767-300 767-200	Installation of an Innovative Solutions & Support, Inc. (IS<(>&<)>S)Integrated Standby Unit (ISU), Part Number 9D-80190-7, loaded with toplevel software 7H-80190-9 as defined in section Limitations/Conditions(or later approved top level software)	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:- CS 25 amdt 0: 25.29, 25.307(a), 25.365(a)(b)(c)(d),25.561(a)(b)(3)(c)(d), 25.1529, 25.1543(b)- CS 25 amdt 1: 25.307(a)- C...	IS<(>&<)>S Master Data List (MDL) 1D-12292, Revision 1, dated 16 March2019<(>,<)>IS<(>&<)>S Aircraft Flight Manual Supplement (AFMS) 1D-12385, RevisionIR, FAA approved on 21 March2019IS<(>&<)>S Instructions for Continued Airworthiness (ICA) 1D-12370,Revision 1, dated 2 September 2015IS<(>&<)>S Elec...	IS<(>&<)>S ISU, Part Number 9D-80190-7, loaded with top level software7H-80190-9, is defined as:Article Part Number Article Description9D-80190-7 withSoftware Part Number SoftwareDescription7H-09848-1 Boot Software7H-10227-9 OFP Software Integrated Standby Unit7H-10228-7 Service Software10H-10041-1...	21/02/2022	Active	10078259
10078270	NORTHWEST AEROSPACE TECHNOLOGIESINC.			777-200	IFE Monitor Replacement	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS-25 Amdt 1: 25.853(a)(d)(e) , 25.1431(a)(c) CS-25 Amdt 4: 25.869(a)(1)(4) , 25.1357(a)(b)(c)The requirementsc...	Master Drawing List N0674-D10 Rev IRICA supplement N0674-D70 Rev ACertification summary N0674-D90 Rev IROr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/02/2022	Active	10078270
10078312	AEROSPACE COMPOSITES GmbH	REV. 1		KODIAK 100	Kodiak 100 Series - Border Patrol Aircraft	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: The environmenta...	Installation according to document “Project Document List”PDL-KOD100-9502-01 Rev.--dated 19/01/2022Operations according to document “Aircraft Flight Manual” (Supplement) AFMS-KOD100-9502-01 Issue 0-1 dated 13/09/2021Maintenance according to document “Maintenance Manual Supplement”MMS-KOD100-9501-01o...	- Flight into known icing conditions is prohibited.- Minimum flight crew: when mission system is in operation one pilotrequired in the leftcockpit seat and one operator required in the cabin.- Maximum occupant seating limit: 3 (ref. to AFMS-KOD100-9502-01 fordetails).Prior to installation of this ch...	08/10/2025	Active	10078312
10078321	TEAM J.A.S., Inc.dba PMA DESIGN AND MANUFACTURING		FAA STC SA00282NY	DHC-6 SERIES 400 DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Replacement Cargo Door latching mechanism on the Viking AirDHC-6 Series aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Document Control List, PDM-MDL0013, Rev B, dated 19 October2021, orlater FAA approved revisions.Instructions for Continued Airworthiness (ICA), PDM-ICA0013, Rev A,dated 22 July 2021 or later FAA approved revisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/02/2022	Active	10078321

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078613	AERODATA AG	REV. 2		560XL	Installation of Aerodata AG Flight Inspection System AD-AFIS-1200.Revision to account for AFM change to remove the flight into known icingconditions limitation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List Installation of AD-AFIS-1200, documentMDL-A/C- 930Rev 5Airplane Flight Manual Supplement Installation of AD-AFIS-1200 forCessna 560XL, document AFM-172 Rev 2Aircraft Maintenance Manual Supplement Cessna 560ML, document AMM-1173Rev 4or later revisions of the above listed documen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	05/07/2023	Active	10078613
10078614	NEW-SENSE GEOPHYSICS LIMITED	REV. 1	TCCA SH07-44	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Fibrotec stinger installation on AS 350Rev. 1 corrects a typo in Associated Technical Documentation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List ATS-0814-MDL-1000, Revision NC, dated 28 April 2008Installation Instructions ISI-AS350-FIB-1000, Revision NC, dated 17September 2007Maintenance Manual ATS-0814-MML-1000 Revision NC, dated 28 April 2008Rotorcraft Flight Manual Supplement AAC-RFMS-AS350-FIB-1001, Issue 01,dated 28C...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/02/2023	Active	10078614
10078618	SAAB AB	REV. 1		A109LUH, A109N A109C, A109E, A109K2 A109A, A109AII	Inflation System for A109 Emergency Flotation System - Certification ofa new inflation system as an alternative to the existing Moog´sinflation system.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-27 initial issueThe requirements for environmental protection and the associatedcertified noise and/ or em...	-Master data list. TDM21-04-MDL issue A dated 11 February 2022-Instructions for Continued Airworthiness. TDM21-04-4-ICAIssue A dated10 February 2022Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/10/2023	Active	10078618
10078637	ALAMO ENGINEERING GmbH			BD-700-1A11 BD-700-1A10	Install. of Collins AID & TIM for EFBInstallation of Collins single Aircraft Interface Device (AID) with dualTablet Interface Modules (TIM) providing aircraft data in peer-to-peercommunication and electrical power to Portable Electronic Flight Bag(EFB).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.29; 25.301;25.303; 25.305; 25.307; 25.561;25.581; 25.601; 25.603; 25.605; 25.607;25.609; 25.611; 25.61...	- AFM Supplement FMS21A07AE-01 Rev. A-MDL21A07AE-01 Rev. A-ICA21A07AE-01 Rev. Aor later revisions of the above listeddocument(s) approved/acceptedunder the EASA system.	None	17/02/2022	Active	10078637
10078639	EIRTECH AVIATION SERVICES LIMITED	REV. 1		737-900ER 737-900 737-9 737-8200 737-800 737-8 737-700 737-600	Auxiliary Battery SystemThis Change alters the configuration from a single battery configurationto a dual battery configuration to increase the standby power time from30 minutes to a minimum of 60 minutes standby power.Revision 1: additionof Models 737-900, 737-900ER, 737-8, 737-8200,737-9.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 Amendment 17;25.1/.29/ . 301/.303/.305/307/.365/.561/.581/. 601/.603/.609/.611/.789/.831/.853. /863/.869/....	Master Document List MDL/1586-001 Issue 7, Aircraft Flight Manualsupplement FMS/ 1586-001 Issue 1, FMS/ 1586-002 Issue 1,FMS/ 1586-003Issue 1, FMS/ 1586-004 Issue 1or later revisionsof the above listed document(s) approved/ acceptedunder the EASA system.	This change may only be performed on aircraft with the Captain’s PitotHeat powered from the 115V AC Standby BusPrior toinstallation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce...	16/08/2022	Active	10078639

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078646	TELAIR US LLC		FAA STC ST04532AT	ATR 72-212 A	Installation of a Bulk Cargo Loading System, P/N 72150-101,or a BulkCargo Loading System Foldout Section, P/N 72729-102	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 amdt. 0: 25.23, 25.321, 25.601, 25.607, 25.609, 25.619, 25.621,25.623, 25.625, 25.1529CS 25 amdt. 1: 25....	1. U.S. Cargo Systems Master Drawing List (MDL) for ATR72-600F FedExBulk Load System, RPT-3988, Issue 4.0, dated 17 December 2021, or laterFAA-approved revision.2. Illustrated Parts Catalog & Component Maintenance Manual, U.S. CargoSystemsPublication No. 50-20-45, Rev. 2.0, dated 10 December 2021,I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/03/2022	Active	10078646
10078650	AIRBORNE TECHNOLOGIES GmbH			DHC-6 SERIES 400	STC-AT-151 DHC-6 IR Suppression SystemThe standard exhaustsare replaced with two modified exhaust tubes whichare additionally shielded for IR suppression.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List, Change Dossier STC-AT-151, Document Number STC-AT-151,Rev. 0Aircraft Flight Manual Supplement for DHC-6 Series 400, IRSSInstallation, Document Number AFM -STC-AT-151, Rev. 1Maintenance Manual Supplement for DHC-6 Series 400, STC-AT-151 DHC-6IRSS Integration, Document Number AMM-STC...	The installation of this change is only allowed in aircraftwhere theLetter of Authorization Doc. 151-LOA-STC-AT has been issued by AirborneTechnologies;Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously inst...	18/02/2022	Active	10078650
10078663	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR04601NY	AW119 MKII	Installation of crash resistant fuel tanks and other fuel systemmodifications.This fuel system modification includes also the installation of anoptional Closed Circuit Refueling Receiver (CCRR), to allow hotrefueling during ground operations with the engine running and rotorsturning.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:Special Condition (s): E-1 for the optional closedcircuit refuelingreceiver (CCRR)The following paragraph (s) at a later amendment: CS27.952(a)(1)(2)(3)(5)(6) (c)(3) (f),...	- Master data list. AWPC-ENG-19-064 Rev A dated April 6, 2021- Instructions for Continued Airworthiness. AWPC-ENG-20-094 Rev - datedMarch 8, 2021,,Or later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ U...	The present STC is issued to validate the fuel tank installation againstthe paragraphs identified in the 49 U.S.C. § 44737 (2018). In particularcompliance have been demonstrated with the following paragraphs: CS27.952(a)(1)(2)(3)(5)(6)(c)(3) (f); CS 27.963(g); CS 27.975(b) all atAmendment 6.Prior tot...	22/02/2022	Active	10078663
10078671	MT-PROPELLER ENTWICKLUNG GmbH	REV. 4		R172H, R172J, R172K R172E, R172F, R172G FR172H, FR172J, FR172K FR172E, FR172F, FR172G	Installation of MTV-12-D/180-17( ) or MTV-12-D/188-59( ) Propeller onCessna FR172( ) Series and installation of MTV-12-D/188-59( ) Propelleron Cessna R172( ) Series.Rev. 1: Revision of STC LBA EMZ 0195-739, Issued 1996-01-17.Rev. 2: Editorial change.Rev. 3 extends the model list.Rev. 4 corrects the...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31.This certificate/ approval involves a change with an impact on the noisedatab...	Applicable to all aircraft and engine models:According to MT-Propeller Master Documentation List No. E-3725 Rev. 2To bemaintained i.a.w. MT-Propeller ICA Doc. No. E-3834 Rev. 2Applicable to MTV-12-D/180-17( ) Propeller:To be operated in accordance with MT-Propeller AFM-S Document No. E-299ERev. 0To...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	02/03/2023	Active	10078671
10078672	MT-PROPELLER ENTWICKLUNG GmbH			U206E, U206F, U206G U206A, U206B, U206C, U206D TU206E, TU206F, TU206G, U206 TU206B, TU206C, TU206D TP206D, TP206E, TU206A TP206A, TP206B, TP206C P206C, P206D, P206E, T206H 206, 206H, P206, P206A, P206B	Installation of MTV-5-1-E-C-F-R(P)/ CFR220-54( ) Propeller on Cessna 206Series with PT6A engine conversion.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31.This certificate/ approval involves a change with an impact on the noisedatab...	According to MT-Propeller Master Documentation List No. E-3573 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3577 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-3575Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-3576 Rev. 0or later...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	24/02/2022	Active	10078672

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078673	LUFTHANSA TECHNIK AG			A330-343	E/CL INSTALLATIONPassenger cabin modification, including installation of Premium EconomyClass seats.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25.791(b) amdt 00;CS25.853 (a)(c)(d) amdt 23The requirements for environmental protection and the associate...	Supplemental Type Design Document STDD25-21/18M Issue 01/00Instructions for Continued Airworthiness A-00-22/08-ICA Issue 02/00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/02/2022	Active	10078673
10078677	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Implementation of ADS-B OUT RAD capability on A300-600STST34MOD052 (applicant's reference) modification aims at implementing theADS-B OUT RAD application (Automatic Dependant Surveillance – Broadcastin Radar Airspaces) on the Beluga ST. The ADS-B OUT application providescontrollers with improved sit...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS ACNS Issue 3.The requirements for environmental protection and the associatedcertified noise and/ or emi...	- Change Approval Sheet (CAS) ST34MOD052 Issue 1 dated 25 February 2022- Change Certification Plan (CCP) ST34MOD052 Issue 6 – Implementation ofADS-B OUT RAD capability on A300-600ST dated 25 February 2022- Approved Document Dossier (ADD) ST34MOD052_ADD Issue 2 including AFMand MMEL supplements as en...	The Mode S / ADS-B OUR RAD system does not transmit the barometricpressure setting parameter entered on the barometric altimeter.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or rep...	28/02/2022	Active	10078677
10078679	AVMAX AVIATION SERVICES Inc.		C-LSA09-113/ D ISSUE 1	DHC-8-102	Retrofit Installation – Separation of Warning & Caution Annunciators	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined and has to be accomplished with Western AvionicsEngineering Order 116888-451,Initial Issue< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/02/2022	Active	10078679
10078680	LUFTHANSA TECHNIK AG	REV. 2		777-300ER	Installation of Premium EcoInstallation of new Premium Economy Class seats between door 3 and 4 ofBoeing 777-300ER.Revision 1: new front row seat with an improved in-arm-video system(IVS)Revision 2: technical documentation list corrected	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25.785(h)(2)(3)(j)(k), CS 25.811(c), CS 25.812(e) and CS 25.813(d) amdt19; CS 25.791(a)(b) and CS 25.853 (a...	Supplemental Type Design Document STDD25-19/30M Issue 02/00Instructions for Continued Airworthiness A-00-21/11-ICA Issue 01/00Instructions for Continued Airworthiness A-00-22/01-ICA Issue 01/01Cabin Crew Information LHT A-00-22/12-CCI, Rev. 01or later revisions of the above listed document(s) approv...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/06/2022	Active	10078680
10078681	HONEYWELL INTERNATIONAL Inc.		FAA STC ST02759LA	SEE FAA APPROVED MODEL LIST	Installation of the Honeywell RDR-4000 Weather Radar System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. Master Drawing List (MDL), 756-0279-001, Revision B, dated 9 November2021;2. Aircraft Flight Manual Supplement (AFMS), 756-0279-820, Revision -,dated 12 November 2021;3. Instructions for Continued Airworthiness (ICA), 756-0279-800,Revision -< (>,<)> dated 8 October 2021;or later revisions of the a...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List for ST02759LA, 756-0279-003, dated12 November 2021.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	01/03/2022	Active	10078681

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078688	INTERCONTINENTAL JET SERVICECORPORATION	REV. 1	FAA SA01877WI	AVANTI II	Installation of ADS-B OutRev. 1 corrects typo in AFM reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. Avionics Integration Master Data List, No. 31-318L001, Rev. D dated16 May 20182. Avionics Integration Aircraft Flight Manual Supplement, No.31-348B001, Rev. IR dated 16 May 2018or later revisions to 1 or 2 above listed document approved/ accepted onbehalf of EASA in accordance with the Technical I...	Limited to S/N 1105 and On (equipped with Rockwell Collins Proline 21Avionics).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	22/03/2022	Active	10078688
10078695	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			767-300	B767-300 Cabin Layout ModificationSeating Layout Change to increase the Premium Economy Class (E/C)capacity in a 3 class seating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision 0 of AMES Engineering Order DocumentEO_M070001082_MTH_04082021The installation shall be accomplished in accordance with revision 2 ofAMES Instructions for Continuous Airworthiness DocumentICA_M070001082_MTH_04082021or later revisions of the above listed document(s...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2022	Active	10078695
10078696	PMV ENGINEERING			A330-343 A330-321/-322/-323/-341/-342 A330-243/-243F/-301/-302/-303 A330-201/-202/-203/-223/-223F	ELT Survival installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment: CS 25 at Amdt. 4:25.601, 25.611, 25.863, 25.1301, 25.1309, 25.1353(c)< (>,<)> 25.1411(a).The requirements fo...	Master Document List AVI-02500-MDL-S01 issue 1Instructions for Continued Airworthiness AVI-02500-ICA-R00 Rev 0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2022	Active	10078696
10078697	AVMAX AVIATION SERVICES Inc.		SA14-35, ISSUE NO.: 1	DHC-8-314/-315 DHC-8-301/-311 DHC-8-201/-202 DHC-8-102/-103/-106	Weather Radar UpgradeThis modification replaces an existingWeather Radar system with aRockwell Collins TWR-850 System.The existing Weather Radarreceiver/transmitter and antenna are removed and replaced with a newcombined receiver/transmitter antenna	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Definition of the Type Design Change in accordance with Avmax MasterData List CE229-900, Issue A.Installation of the Rockwell Collins TWR-850 Weather Radar system to bedone in accordance with Avmax Engineering Order CE229-401, Issue AMaintenance of the Rockwell Collins TWR-850 Weather Radar system t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2022	Active	10078697
10078700	AVIATION TRADERS LIMITEDEUROPE S.A.S.			737-800	BOEING 737-800 INSTALLATION OF MADELEC AERO LED CABIN LIGHTING	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): CRI H-01 EWIS ICAThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product...	MDL-13452-00001 Issue 413452-ICA-00001 Issue 2or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	None	03/03/2022	Active	10078700

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078701	PILATUS BUSINESS AIRCRAFT, Ltd.		FAA STC SA01082DE	PC-24	Installation of Cabin Power Outlets	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01082DE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Doc No. 24-2011-01-0000, Master Drawing List, PC-24 Cabin UtilityPower, Issue C dated 22 June 2021, FAA approved 1 July 2021 or later FAAapproved revisions.2. Doc No. 24-2011-64-0000, Instructions for Continued Airworthiness(ICA), Issue"-" dated 21 May 2021, FAA accepted 1 July 2021 or laterFAA3...	This STC is applicable to all serial numbers for the Pilatus AircraftLtd. PC-24.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changeand/ or repair will introduce no adverseeffect upon the airw...	03/03/2022	Active	10078701
10078702	ROCKWELL COLLINS, INC.D/ B/A ROCKWELL COLLINS, INC.,PORTLAND SERVICE CENTER		FAA ST02691SE	BD-100-1A10	Installation of Head-up Display System (HUD) Model 6650 andEnhanceVision System (EVS) Model 3600 on the Bombardier Model BD-100-1A10 (Challenger 350) aircraft.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	FAA STC ST02691SEMaster Drawing List (MDL) 946-1KJ2-001, Revision B, dated Feb 17, 2021Instructions for Continued Airworthiness (ICA) 946-24U8-001, Revision -,dated March 23, 2020Airplane Flight Manual Supplement (AFMS) 9701-1310, Revision-, datedJune 12, 2020or later revisions of the above listedb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/03/2022	Active	10078702
10078713	AVMAX AVIATION SERVICES Inc.		TCCA SA17-122	B300C, B200CGT, B200GT	Medivac Audio System Installation as per TCCA STC SA17-122	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of the Medivac Audio System must be in accordance withTransport Canada (TCCA) approved Avmax Engineering Order CE403-401,Issue B, dated December 18, 2017Maintenance of the Medivac Audio System must be in accordance with TCCAaccepted Avmax Maintenance Manual Supplement CE403-701, Issue A...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/03/2022	Active	10078713
10078716	AEROSERVIS, S.R.O.			L-410 UVP-E, L-410 UVP-E-LW L-410 UVP-E20, L-410 UVP-E9 L-410 UVP-E20 CARGO, L-420	STC AE/219 [L-410 MLG rear hinge]The scope of the project is approval of rear main landing gear hingechange. New designconsiders the change of production technology processand the design improvements to achieve an increased reliability duringoperation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Applicable to following models: L 410 UVP-E20; L 410 UVP-E20 CARGO;L-420.The Type and OSD Certification Bases for the original product as amendedby the following additional or alternati...	- STC Master Document List; Doc. No. AE219000X, rev. A; dated 25.02.2022- Maintenance Schedule supplements, Doc No. STCAE/219-DPU-1, Issue 1;12 January 2022or later revisions of the above listed document(s) approved/ acceptedunder the EASAsystem.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/03/2022	Active	10078716
10078748	WEST STAR AVIATION, L.L.C.		FAA STC ST04518CH	750	Installation of a Honeywell Flight Management System Software Update toversion NZ 6.2.1	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	West Star Aviation Master Data List, Doc. No. A21312L-652, Rev. I/ R,dated 4 October 2021, or later FAA approved revision.West Star Aviation Airplane Flight Manual Supplement, Doc.No.A21312M-657, Rev. I/R, dated 5 November 2021, or later FAA approvedrevision.	This STC is applicable to the following serial numbers: MSN750-0001through 750-0500.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	07/03/2022	Active	10078748

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078750	SABENA TECHNICS BGC			777F 777-300ER 777-300 777-200LR 777-200	Mounting device and power supply connection for “PIVOT” EFBsolutions.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 at amdt 4: 25.1,25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341, 25.561,25.571, 25.601, 2...	Master Documents List 10004-01-A-MDL Rev 0AFM Supplement 10004-01-A-AFMS-R02 Revision 2Instructions for Continued Airworthiness 10004-01-A-ICA Rev 0MMEL Supplement 10004-01-A-MMELRev 0or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	As per AFM supplementPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	08/03/2022	Active	10078750
10078751	UUDS AERO CONCEPT	REV. 1		SEE EASA APPROVED MODEL LIST	UNIVERSAL CONVERTIBLE STRETCHER INSTALLATIONExtension of STC 10078751 to an AML STC for the installation of medicalstretcher on-board	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 Amdt 26:25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.331, 25.337,25.341, 25.561, 25.601, 25....	SEE EASA APPROVED MODEL LISTor later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	-per AFM supplement as identified in the EASA APPROVED MODEL LIST-Installation is limited to configurations as per below InstallationInstructions and Limitations Drawings: UAC21M001-101, UAC21M001-M0002,UAC21M001-M0003, UAC21M001-M0004, UAC21M001-M0005, UAC21M001-M0006,UAC21M001-M0007, UAC21M001-M00...	04/09/2023	Active	10078751
10078753	ETIHAD AIRWAYS ENGINEERING L.L.C.			A321-272N,-272NX A321-271N,-271NX A321-253N,-253NX A321-252N,-252NX A321-251N,-251NX A321-213,-231,-232 A321-111,-112,-131,-211,-212 A320-271N,-272N,-273N A320-251N,-252N,-253N A320-231,-232,-233 A320-211,-212,-214,-215,-216	CARRIAGE OF CARGO IN PASSENGER CABIN	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Deviation(s): CRI D-130 “Transportation of cargo in passengercompartments” issue 3The requirements for environmental protection and the associatedcertified n...	Master Document List EA2-20251298-DL01 Issue 3AFM Supplement EA2-20251298-PA06 Issue 5Airworthiness Limitations SectionSupplement EA2-20251298-PA10 Issue 1OSD CCD Supplement EA2-20251298-TR03 Issue 3OSD MMEL Supplement EA2-20251298-PA11 Issue 4or later revisions of the above listed document(s) appr...	- The allowance to transport cargo in passenger compartmentis limitedto 2000 FH following installation of the change or to July 31st 2022,whatever occurs first.-Aeroplanes modified per this STC are considered to be a “variant” tothe B777-300ER passenger configurations. Cabin crew operating aeropla...	08/03/2022	Active	10078753
10078795	VIH AEROSPACE Inc.	REV. 1	TCCA SH19-52 ISSUE 3	AS 332 L, AS 332 L1 AS 332 L2, EC 225 LP AS 332 L1 AS 332 L	EASA validation of cockpit door bubble windows installationRev. 1: Addition of AS332 L2.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Project Compliance Plan, ref. VIH 23/01-001, Rev A, dated 14/05/2022Rotorcraft Flight Manual (RFM) Supplement, ref. V332-1715-FMS, Rev C,dated 29/03/2022Instructions for ContinuedAirworthiness (ICA), ref. V332-1715-ICA, RevB, dated 19/05/2022Master Document List (MDL), ref V332-1715-MDL, Rev B, dat...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/12/2022	Active	10078795
10078797	AVIONIK STRAUBING ENTWICKLUNGS GmbH			P210R P210N	Installation of dual Garmin GA 58 TAS/ TCAS antennas	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation in accordance with Avionik Straubing GmbH Instructions forInstallation Doc. No: ASR-2021-050-IFI-10-00, date 01/02/22.Instructions for Continued Airworthiness in accordance with AvionikStraubing GmbH Doc No: ASR-2021-050-ICA-11-00, date 31/01/22.or later revisions of the above listed do...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/03/2022	Active	10078797

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078806	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR01344NY	AW119MKII A119	Installation of a Spectrolab SX-5 searchlight on a side mount or centerof nose	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Agusta Aerospace Corporation Master Data List, Report No.ACC-ENG-00-036, Rev. B, dated 28 April 2001 for configuration 1 (A119Only).Agusta Aerospace Corporation Instructions for Continued Airworthiness,Report No. AAC-ENG-00-035, Rev. - dated 2 March 2001 for configuration 1(A119 Only).Agusta Aerospa...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/03/2022	Active	10078806
10078809	ALAMO ENGINEERING GmbH			DORNIER 328-100	Certify Dornier 328-100 as PED tolerantCertification of theinstallation of a wireless communication system tobe used in all flight phases except low visibility approach operationlimited to a maximum of 100 mW EIRP (for example Bluetooth or Wi-Fi inthe 2.4 GHz ISM band).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.1319, Amdt. 27.The requirements for environmental protection and the associatedcertified noise and/ or emissions l...	Master Document List, MDL21A47AE-03, Rev. AAircraft Flight Manual Supplement, FMS21A47AE-01, Rev. AInstructions for Continued Airworthiness, ICA21A47AE-03, Rev. AOr later revisions of the above listed document(s) approved/acceptedunder theEASA system.	The following related design changes are prerequisite for thisinstallation:• STC EASA.A.S.01024 - Aerodata: Installation of Maritime SurveillanceSystem on Dornier 328-100 including SAR Radar, FLIR, and optional IR/ UVScanner• Minor Change Approval DC-12B161Z0001 Deutsche Aircraft GmbH:Installation of...	29/06/2022	Active	10078809
10078814	EIRTECH AVIATION SERVICES LIMITED			737-600, 737-700, 737-800	Captains Pitot Heater Power SupplyThis change allows the Captains Pitot Heater to remain powered in theevent of a main and essential electric power failure. Post this change,during normal operation the Captains Pitot Heater is powered fromthe115V AC Transfer Bus but automatically switches to the 11...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25 Change 14;25.1/.29/ 601/.603/.853/.1301/.1309/.1322/. 1326/.1351/.1353/.1355/.1357/ X1360/.1419/.1431/...	Master Document List MDL/1580-001 Issue 5< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This change may only be performed on aircraft equipped withdual (two)standby batteries providing a minimum of 60 minutes of standbyelectrical power.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installe...	11/03/2022	Active	10078814
10078816	SKANDIA, INC		FAA STC ST04555CH	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Installation of Thermal/Acoustic kits	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Skandia Master Data List, Document Number 7803-060MDL, Revision IR,dated August 4, 2021 or later FAA approved revisions.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/03/2022	Active	10078816
10078823	CHIPPEWA AEROSPACE, Inc.		FAA STC ST02695AT	DHC-8-401/-402 DHC-8-301/-311/-314/-315 DHC-8-201/-202 DHC-8-102/-103/-106	Installation of a FA2100CVR Cockpit Voice Recorder (CVR)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Chippewa Aerospace Master Drawing List (MDL) D8-2371-0001, Rev. IR,dated 12March or later FAA approved revision.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/03/2022	Active	10078823
10078824	U.S. TECHNICAL CONSULTANTS, INC.	REV. 1	FAA STC ST04527CH	EMB-145LR, EMB-145MP EMB-145EP, EMB-145ER, EMB-135ER, EMB-135LR,	Cabin installations:-installation of a 16 passengers configuration-installation of a 22 passengers configurationRev. 1:22 passengers configuration added and applicability listextended to EMB-135ER, EMB-145EP, EMB-145ER, EMB-145LR, EMB-145MP	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 Initial issue: 25.305(a)(b) , 25.561(a)(b)(c)(d) , 25.613(a)(b)(d)(e), 25.785(a)(b)(c)(f)(1)(3)(j)(k) , 25.813(c)(1)(2...	16 Passengers configuration only:- Technical Master Documents and Drawing List (MDL), 9469-25-000,Revision E, dated 17 November 2021- Airplane Flight Manual Supplement, U10-0633, Revision A, dated 19 July2021- Instructions for Continued Airworthiness, U10-0632, Revision NC, dated13 July 202122 Passe...	- 16 Passengers configuration installation limited to EMB-135ER,EMB-135LR- 22 Passengers configuration installation limited to EMB-145EP,EMB-145ER, EMB-145LR, EMB-145MP- This STC requires prior or concurrent embodiment of EASA STC 10077712 (ST04177NY) for the installation of ALI LED Cabin Lighting, C...	01/09/2023	Active	10078824

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078831	RHEINLAND AIR SERVICE GmbH	REV. 1		DORNIER 228-212 DORNIER 228-202 DORNIER 228-201 DORNIER 228-200 DORNIER 228-101 DORNIER 228-100	Installation of Garmin G700TXi Suite, including certification of LPVapproaches, integration of a Garmin GWX75 Weather Radar, GTN750Xi TAWS-Aand a Becker DVCS6100 IntercomRev. 1: Revision to account for the transfer from airplus engineeringGmbH to Rheinland Air Service GmbH	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23.1, 23.3, 23.25,23.29, 23.251, 23.601, 23.603, 23.605, 23.607, 23.609, 23.611, 23.613,23.619, 23.623,2...	Change description DOM-2449-340000-3Master Drawing List MDL-2449-340000-1Master Document List MDO-2449-340000-2AirplaneFlight Manual Supplement – G700TXi POH-2449-340001-4Airplane Flight Manual Supplement – DVCS6100 POH-2449-340002-2Airplane Flight Manual Supplement – GWX75 POH-2449-340003-3Airplan...	None	23/07/2025	Active	10078831
10078850	GULFSTREAM AEROSPACE CORPORATION		FAA ST04307AT-D	GIV, GIV-X	Installation of GoGo Business Aviation Avance L5 System on theGulfstream G-IV and GIV-X model aircraft(FAA STC ST04307AT-D)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): F-110 Installation of non-rechargeable lithiumbattery.The requirements for environmental protection and the associatedcertified noisea...	1. Index List CE413028010 Rev -, dated March 08 20182. Instructions for Continued Airworthiness – GIV-X Gogo Biz AVANCEL5System Installation CE41302A016Rev C, dated Feb 22 20183.Instructions for Continued Airworthiness – G-IV Gogo Biz AVANCE L5System Installation CE41302A017Rev C, dated Feb 22 201...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/03/2022	Active	10078850
10078853	GULFSTREAM AEROSPACE CORPORATION		FAA ST03118AT-D	GIV-X	Installation of Custom Interior on GIV-X aircraft (FAA STC ST03118AT-D).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): F-110 Installation of non-rechargeable Lithiumbattery.The requirements for environmental protection and the associatedcertified noisea...	Index List GC420008046, Rev E, dated Feb 18 2022Instructions for Continued Airworthiness GC42801A241<(>,<)> Rev-–, datedAug 19 2005Instructions for Continued Airworthiness CE42856A057 Rev A, dated Feb 172022or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in acco...	The following STCs are a required part of this Custom Interior STC:ST02948AT-D Cabin Window Shades (EASA.IM.A.S.01687) ST02979AT-D Passenger Oxygen System (EASA.IM.A.S.01686)ST02987AT-D Interior Emergency Lights (EASA.IM.A.S.01684).Prior toinstallation of this change/ repair it must be determined tha...	17/03/2022	Active	10078853
10078866	JET AVIATION AG			777-200LR	B777 Iridium Antenna STCStructural provisions installation for a Dual Iridium Antenna on theB777 fuselage upper lobe.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	JBSL-M-01277DOC-001 Issue A - Declaration of ComplianceJBSL-M-01277ICA-001 Issue A - Instruction for Continued AirworthinessJBSL-M-01277CCS-001 Issue A – Certification Compliance Sheetor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/03/2022	Active	10078866
10078880	SABENA TECHNICS BGC			A340-313	Cabin Reconfiguration to 353 YC PAX	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25 at amendment 4paragraphs: 1, 29, 301, 303,305, 307, 365, 561, 562, 571, 601, 603,605, 607, 609, 611, 6...	- Master Data List, Ref. 40930-01-A-MDL-R00 (18 Mar 2022)- Instructions for continued airworthiness, Ref. 40930-01-A-ICA-R00 (19Nov 2021)or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik EASASTC No. 10013964 Rev.03.Prior to installation of this change/repair it must be determin...	21/03/2022	Active	10078880

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078884	INTER-TEC AERO DESIGN AND CERTIFICALIMITE D	REV. 1		EC135 P2, EC135 P2+ EC135 P2	Initial approvalIntroduction of Mid-Continent Standby Attitude Module (SAM) MD302 Seriesin accordance with Master Data List ITS-0594-007Revision 1Extension of applicability to EC135 P2+ in accordance with Master DataList ITS-0594-007	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): Lithium Battery Installations F-01.The requirements for environmental protection and the associatedcertified noise and/ or emissions l...	For initial approval- Master Data List ITS-0594-007 Issue 1- Rotorcraft Flight Manual Supplement ITS-0594-006 Issue 1- Master Minimum Equipment List Supplement ITS-0594-016 Issue 1- Instructions for Continued Airworthiness ITS-0594-005 Issue 1For Revision 1- Master Data List ITS-0594-007 Issue 3- Ro...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/06/2025	Active	10078884
10078890	AVIADECO GmbH			35A	Removal of the Raisbeck Aft Fuselage Stowage Locker, previouslyinstalled by the FAA STC ST00179SE	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Removal installation in accordance with Engineering Order EO-02421-1 rev00 andEO-02421-2 rev 00; maintained in accordance with ICA-02421 rev 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/03/2022	Active	10078890
10078893	GVH AEROSPACE (IRELAND) LIMITED			AW169	SATCOM Installation with Skytrac ISAT-200A flight following/ satellitecommunication system and DAL-200 Dynamic Air link (wireless networkdevice)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Programme GVH-11967-01-CP-01 Issue 3Instructions for Continued Airworthiness ICA20043-1Flight Manual Supplement FMS20043-1 Issue CAntenna Install MD21009 Issue AEquipment Install MD21010 Issue A.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/03/2022	Active	10078893
10078895	FIELD AVIATION EAST, LTD.		TCCA O-LSA14-013/D ISSUE 2	DHC-8-102, DHC-8-201	Honeywell Primus 660 Weather Radar SystemReplacement of existing weather radar system and display with a newHoneywell Primus 660 and Universal MFD-640 Multifunction Display.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- For Model DHC-8-102:Installation shall be performed in accordance with Field AviationCompany inc. Master Drawing and Data list designated 25920000, initialRevisionMaintenance shall be performed in accordance with Field Aviation Companyinc. Maintenance Manual Supplement designated 25923100, initial...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product	22/03/2022	Active	10078895
10078900	HELI-ONE (NORWAY) AS			AS 332 L, AS 332 L1 AS 332 L1 AS 332 L	Nose mounted FLIR installation (ref. modification AHSE-72102).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:CS 29 Amdt 7 for the following requirements: 29.351, 29.610, 29.853,29.1309, 29.1316, 29.1317 and 29.1359.Th...	Certification Programme (CP) ref. AHSE-72105 Revision F, dated21/03/2022.Flight Manual Supplement (FMS) for nose mounted FLIR installation ref.H1No.I.332 Revision dated 24/02/2022.Product Change Declaration (PCD) ref. AHSE-72102 Revision B, dated21/03/2022.Instructio n for Continued Airworthiness (IC...	The following modifications are a pre-requisite for the embodiment ofthis STC:- Heli-One (Norway) AS ref. AHSE-73030 and AHSE-73045 - Mission panelmodifications;- Airbus Helicopters ref. 0725624 - Provisions for installation of FLIRsystem.Laser pointer (laser class 3B) and laser illuminator (laser c...	23/03/2022	Active	10078900

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078904	WIPAIRE Inc.		FAA STC SA227CH	PC-6/B2-H4	Installation of Wipaire Model 6100 Amphibious/Seaplane Floats	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA227CH.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	1. Wipaire Drawing No. 8C1-5001, Revision B, dated 6 July 1994, or laterFAA approved revisions.2. FAA Approved AirplaneFlight Manual Supplement for AmphibiousOperation of the Pilatus PC·6/B2·H4, dated 14 July 1994 or a laterapproved revision.3. FAA Approved Airplane Flight Manual Supplement for Sea...	This float installation is compatible with aircraft incorporatingPilatus underwing fuel tanks, part numbers 959.17.11.103 (2 x 49 USgallons), 115.55.06.225 (2 x 63 US gallons), or115.55.06.305 (2 x 64 USgallons). The fuel tank installations are approved on Type CertificateData Sheet 7A15.Prior to i...	24/03/2022	Active	10078904
10078913	MT-PROPELLER ENTWICKLUNG GmbH			MU-2B-60 MU-2B-40 MU-2B-36A MU-2B-26A	Installation of MTV-37-1-E-C-F-R(G)/ CFRL228-352( ) Propeller onMitsubishi MU-2B-( ) aircraft models.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase...	According to MT-Propeller Master Documentation List No. E-3868 Rev. 1To be operated in accordance with MT-Propeller AFM-S Document No. E-3870Rev. 1To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-3871 Rev. 1To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3872 Rev. 1or later...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/03/2022	Active	10078913
10078922	AERODATA AG			B300	Installation of L-Band Antenna	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Service Bulletin, Installation of additional L-Band antenna, documentSB-B300-ANT-2243 Rev. 0Aircraft Maintenance ManualSupplement, document AMM-816 Rev. 0, date 31Oct. 2006or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/03/2022	Active	10078922
10078925	AVIONIK STRAUBING ENTWICKLUNGS GmbH			SA26-T SA26-AT SA227-TT SA227-PC SA227-DC SA227-CC SA227-BC SA227-AT SA227-AC SA226-TC SA226-T(B) SA226-T SA226-AT	Garmin GTN 6XX (Xi) / or GTN 7XX (Xi) Installation of singleGarmin GTN 6XX (Xi) / or GTN 7XX (Xi) withoptional Garmin GA 35 GPS antenna using existing antenna footprint.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-23 Amd 4: 23.29,23.301, 23.303, 23.305, 23.307, 23.337(a), 23.365, 23.561 (b), 23.571(c),23.601, 23.603(a) (...	Installed, operated and maintained in accordance with applicabledocuments as listed in:Master Documents List, Document number: ASR-2021-055-MDL-01-00, Revision0, Dated 24th March 2022.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Other: No structural modifications are approved; any antennainstallation in accordance with this STC must use existing antennafootprints; failing this an additional approval covering the structuralmodification must be sought.Furthermore, this approval covers three particular cases with theapplicable...	29/03/2022	Active	10078925
10078929	LUFTHANSA TECHNIK AG	REV. 1		A340-213, A340-541	Large Antenna Provisions InstallationInstallation of structural provisions for a Ka-band SatelliteCommunication System (Satcom).Rev. 1: Extended applicability to A340-541.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): B-60077131-001 – Vibration and buffetingcompliance criteria for large external antenna installation.The requirements for envir...	Supplemental Type Design Definition STDD53-21/02M Issue 3 Rev 00Airplane Flight Manual Supplement A-00-21/28-AFM Issue 3 Rev 00Airplane Flight Manual Supplement A-00-24/29-AFM Issue 3 Rev 00Instructions for Continued Airworthiness A-00-21/28-ICA Issue 1 Rev 00Instructions for Continued Airworthiness...	At time of approval of this STC, the approval of OSD-FCD for A340-213was still pending.The corresponding change to OSD-FCD for A340-213 need to be providedbefore it must actually be used.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/r...	09/12/2024	Active	10078929

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10078946	JET AVIATION AG			BD-700-1A10	Cabin LOPA changeThe LOPA change consists of replacing the aft bed L/H with a 3-placedivan. The divan installation willbe covered with STC EASA10055082 /FAA ST02910CH-D. The new LH divan and existing R/H divan will beupholstered with new foams and covers in addition to other cabinrefurbishing.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- MDL JBSL-M-03701MDL-001 Issue C-Aircraft Flight Manual Supplement JBSL-M-03701AFM-001 Issue Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Installation of the 3-places divan must be in accordance with EASA STC1005082 configuration 1;The AFMS No: 35-169M-001,Rev A of this STC remains applicable inconjunction with AFMS JBSL-M-03701AFM-001.	01/04/2022	Active	10078946
10078948	COMTECH GLOBAL AVIATION SERVICES,SOCIEDAD LIMITADA			757-200, 757-200PF, 757-300	Installation of Reticulated Polyurethane Foam (RPF) for Center Fuel TankIgnition Mitigation in the Boeing 757-200 & 757-300 Series AircraftThis STC installs a Fully Packed Reticulated Polyurethane Foam (RFP) asa Fuel Tank Ignition Mitigation Means (IMM) in the Center Fuel Tank ofBoeing 757-200/ 300...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.29 Amdt.25/ Initial; CS 25.301 (a)(b) Amdt. 25/18;CS 25.303 Amdt. 25/1; CS 25.305 (a)(b) Amdt. 25/1; C...	- Project Specific Certification Plan ref. CTG-PSCP5062-757, rev. Cdated JAN 14, 2022-Aircraft Flight Manual, Supplement ref. CTG-AFM5062-01, rev. B datedMAR 30, 2022-Instructions For Continued Airworthiness, Supplement ref.CTG-ICA5062-01, Rev. D dated MAR 31, 2022or later revisions of the above l...	1- This modification is applicable only to airplanes which incorporatecenter tank fuel scavenge system under the delivery configuration.2- acceptable Fuel and fuel additives as specified in AFM supplementref. CTG-AFM5062-01 and ICA supplement ref. CTG-ICA5062-01 must beobserved. 3- ALS/ CDCCL as det...	01/04/2022	Active	10078948
10078957	ALAMO ENGINEERING GmbH			BD-700-1A11 BD-700-1A10	Installation of Ku-Band Satcom with TMAThe installation covers the upgrade of the existing satellitecommunication system by a Satcom Direct Plane Simple Ku-Band SatcomSystem consisting of: a Satcom Direct Modem Unit (SMU) in the aftequipment bay and an Advanced Tail Mounted Antenna (ATMA) on existin...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1319 at amdt 26The requirements for environmental protection and the associatedcertified noise and/ ora...	- Master Document List MDL21A33AE-01 Rev. A-Instructions for Continued Airworthiness ICA21A33AE-01 Rev. B-Flight Manual Supplement FMS21A33AE-01 Rev. Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- The aircraft must be equipped / installed with Satcom Direct Gateway(SDRG) or Satcom Direct Router (SDR) or can be modified concurrentlywith ALAMO Engineering, “Minor Change Approval project Upgrade”, projectno 20A13/ 21A41.-AMT-50 Antenna Assembly (P/N 0476-A-00377) with ACU (P/N 0811-A-0001)and...	04/04/2022	Active	10078957
10078962	AERSALE, Inc.		FAA ST04203NY	777-300, 777-300ER 777-200, 777-200LR	Installation of Reticulated Polyurethane Foam (RPF) for Center Fuel TankIgnition Mitigation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS25 amdt 1: 25.307 (a), 25.561, 25.901(a)(1)(3)(b)(2)(3)(4)(c)CS25 amdt 5: 25.611CS25 amdt 6: 25.981.The req...	Master Data List, AES-MDL0078-777, Revision IR, dated 22 December 2020Instructions for Continued Airworthiness (ICA), AES-ICA0078-01, Revision-, dated 14 December 2020Aircraft Flight Manual Supplement (AFMS), AES-AFMS0078-01, Revision IR,dated 22 December 2020or later revisions of the above listed d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/05/2022	Active	10078962
10078974	FIELD AVIATION COMPANY Inc.		C-LSA03-146/D	DHC-8-102	PBS-400 Passenger Briefing System InstallationThis STC approves the installation of a Heads Up Technologies, PBS-400Passenger Briefing System.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision A of Field Aviation Company Inc.Engineering Data Summary document 191100.Installation of Heads Up Technologies PBS-400 Passenger Briefing Systemto be performed in accordance with Field Aviation Company Inc.Modification Instruction 191110, original issue.Maintenanc...	Limited to Aircraft Serial Numbers 013 and 038Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	06/04/2022	Active	10078974

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079001	S4A SOLUTIONS FOR AVIATION, S.L			BD-700-1A10	GEX05 CES INSTALLATIONInstallation of a new cabin configuration and associated equipment.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with GEX05-SB001 Service Bulletin Ed3,maintained in accordance with GEX05-HDK02 Maintenance manual supplementEd5, operated in accordance with GEX05-HDK01 Flight manual supplementEd6.GEX05-RPT02 Master drawing list Ed7or later revisions of the above listed document(s) approved...	Limited to aircraft Bombardier Global Express B700-1A10, MSN 9013Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repairwill introduce no adverseeffect upon the airworthiness of th...	06/04/2022	Active	10079001
10079002	AEROSPACE COMPOSITES GmbH	REV. 1		KODIAK 100	External Intelligence, Surveillance and Reconnaissance (ISR) Provisions	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation according to document “Project Document List”PDL-KOD100-9505-01 Rev.--dated 30/03/2022Operations according to document “Aircraft Flight Manual” (Supplement) AFMS-KOD100-9505-01 Issue 0-0 dated 24/03/2022Maintenance according to document “Maintenance Manual Supplement”MMS-KOD100-9505-01o...	Flight into known icing conditions is prohibited.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	08/10/2025	Active	10079002
10079012	LEE AEROSPACE, INC.	REV. 1	FAA ST04210NY	HAWKER 850XP/ 900XP/ 1000 HAWKER 750/ 800/ 800XP BAE.125 SERIES 800A/ 800B BAE.125 SERIES 1000A/ 1000B	Installation of LAI Windshield Panel ARev. 1 corrects the applicability.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List LAI-MDL-119, Revision IR, dated 02 September 2021Instructions of Continued Airworthiness (ICA) LAI-ICA-119, Revision IR,dated 01 June 2021or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/04/2022	Active	10079012
10079023	SABENA TECHNICS BGC			A321-213/-231/-232 A321-111/-112/-131/-211/-212	A321-Cabin Reconfiguration from 169PAX to 220PAX	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: - JAR25 at change 11 paragraphs: 811, 1441 - CS-25 at amendment 4 paragraphs: 1, 29, 301, 303, 30...	- Master Data List, Ref. 40850-01-A-MDL-R00 dated 15th July2022- Instructions for continued airworthiness, Ref. 40850-01-A-ICA-R00dated 15th July 2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:Installation of a photo-luminescent EFPM as per Lufthansa TechnikEngineering Bulletin ref A320-EB33-0384 approved through EASA STC No. 10014013.Prior to install...	15/07/2022	Active	10079023
10079033	S4A SOLUTIONS FOR AVIATION, S.L			EMB-135LR	Passenger Seats RearrangementAircraft with initial LOPA (37Y) changed due to new seats part numbers.Seat locations remain unchanged from the pre-mod LOPA, only the partnumbers areaffected. New seats PROTEUS and REGIONAL AIRLINES Seriescomply with TSO-C72c and TSO-C127a.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	MDL LOPA Modification in EMB-135 Ref. 145_520-18-02 of 31/03/2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/04/2022	Active	10079033

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079035	AMAC AEROSPACE SWITZERLAND AG			A319-153N	Interior OutfittingThe change consists of a cabin interior outfitting of a A319-153N with21 passengers VIP interior forPrivate use only.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI D-135 Installation of stowage or chargingstations for personal electronic devices (PED) in an aircraft cabin.- The following parag...	The Change is defined with revision C of AMAC Aerospace Master Data ListDocument MDL-KC01-2500.The aircraft shall be operated in accordance with revision B of AMACAerospace Airplane Flight Manual Supplement Document AFMS-KC01-2500.Maintenance shall be conducted in accordance with revision A of AMACA...	The following TC holder specific MOD's are defined as pre-requisite tothis change: MOD160500, MOD161004, MOD162337, MOD163214, MOD163216,MOD23398, MOD162193, MOD162338.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any other...	11/04/2022	Active	10079035
10079040	LUFTHANSA TECHNIK AG			A350-941	DLH A350 Cabin Interior AdaptionCabin modification and re-branding to Deutsche Lufthansa (DLH) standard.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Design Document STDD25-21/22M Issue 1.0Instruction for Continued Airworthiness A-00-22/02-ICA Issue 01/00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/04/2022	Active	10079040
10079044	SABENA TECHNICS BOD	REV. 1		737-800	CHOPIN 3 cabin modificationRev 1: Typo corrected in the technical documentation list	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): D-101 Isolated compartments Issue 2.- Deviation(s): D-104 Installation of interior doors Issue 2, D-106Firm handhold Issue 2.The requ...	Master Document List MDL S-00-4303 issue AMMEL Supplement MMELS-S0002-00-125 issue BAFM Supplement AFMS-S0002-00-031 issue BInstructions for Continued Airworthiness ICA-S0002-00-032 Issue Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The STC 10060445 KA Band TIOS Radome installation shall be installedconcurrently to the configuration covered by this STC.The aircraft modified per this STC is not compliant with OSD-CCD (perRegulation (EU) 69/2014).Since operation cannot be performed with professional Cabin Crew (CC) members (i.e. h...	13/04/2022	Active	10079044
10079045	HONEYWELL INTERNATIONAL Inc.	REV. 1	FAA SR04472CH	AW139	Honeywell RDR-7000 Weather Radar System installationThe RDR-7000 Weather Radar installation is a replacement of the existingPrimus 70X weather radar installed on the AB139/ AW139 helicopters ShortNose configuration.Rev. 1: Transfer from Aerospace Testing Engineering & Certification,Inc. d/b/a Aerote...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Rotorcraft Flight Manual Supplement ATEC-20358, Rev.3- Master Data List ATEC-077-241-1300, Rev. H- Instructions for Continued Airworthiness ATEC-20203, Rev. F- Installation Instructions ATEC-077-241-1305, Revision H- Weight and Balance Report ATEC-20286, Rev. AOr later revisions of the above liste...	The Installation of the RDR-7000 weather radar system is limited only tothe following AW139 helicopter S/ N's (Short Nose Configuration): 31001 to 3115741001 to 41023.As a prerequisite for the RDR-7000 weather radar installation, theweather radar Primus 70X must be already installed on the helicopter....	07/06/2022	Active	10079045
10079050	AMTECH AERONAUTICAL LIMITED		TCCA SA19-109 ISSUE 2	S2R-T34, S2R-T660	Installation of a Pratt and Whitney Engine Services, Inc. Flight DataAcquisition Storage and Transmission System (FAST)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	MDL469701 GN4-T-100-10, Revision 1Aircraft Flight Manual Supplement GN4-T-250-9, Revision AInstructions for Continued Airworthiness Manual Number GN4-T-260-11,Revision Aor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Implementati...	The installation of EASA STC 10064806 is a prerequisite forinstallationof the STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the a...	13/04/2022	Active	10079050

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079062	AVIO DESIGN GROUP INC.d/b/a AVIO DG		SH21-41 ISSUE 1	412EP 412	TV Broadcast Equipment Mounting	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	- Master data list. 2137MD-001 Rev B dated April 14, 2022- Rotorcraft Flight Manual Supplement – 2137-FM-001 October 20, 2021TCCA Approved December 09, 2021- Instructions for Continued Airworthiness. 2137-CA-001 Rev - datedOctober 19, 2021Or later revisions of the above listed document(s) approved/a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/04/2022	Active	10079062
10079073	BEONE HAMBURG GmbH			B300	Installation of ADF Antenna with Antenna Adapter Plate	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List, Document No. 617-10023-MDL-0001 Rev. AAircraft Maintenance Manual Supplement, Document 617-10023-AMM-0001 Rev.BInstructions for Continued Airworthiness, Document 617-10023-ICA-0001Rev. BManufacturing Instructions, Document 617-10023-MIN-0001 Rev. Aor later revisions of the abov...	Only applicable to Beech B300 S/N FL-630 RA-02812Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	20/04/2022	Active	10079073
10079077	JET AVIATION AG			SEE EASA APPROVED MODEL LIST MYSTÈRE FALCON 900 (MF900) MYSTÈRE FALCON 50 (MF50) MYSTÈRE-FALCON 20 GF MYSTÈRE-FALCON 20 - F5 MYSTÈRE-FALCON 20 - E5 MYSTÈRE-FALCON 20 - D5 MYSTÈRE-FALCON 20 - C5 MYSTÈRE-FALCON 200 GV-SP GVI (G650) GV GIV-X GIV GIII (G-1159A) GII (G-1159) GIIB (G-1159B) G-159 FAN JET FALCON SÉRIES G FAN JET FALCON SÉRIES F FAN JET FALCON SÉRIES E FAN JET FALCON SÉRIES D FAN JET FALCON SÉRIES C FAN JET FALCON FALCON 900EX (F900EX) FALCON 7X FALCON 2000EX FALCON 2000 DHC-8-402 DHC-8-401 DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202	Real Glass Window Shade LensThis design change replaces allthermoplastic transparent protectiveinner windowpanes in the passenger cabin with a laminated glass product.In additionto the lens replacement, structural change may be applied tothe window shades. The attachments to the A/C structure will...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.29, 25.301,25.305, 25.307, 25.321, 25.561,25.601, 25.603, 25.605, 25.609, 25.613,25.775, 25.785, 25.78...	Jet Aviation Approved Model List ref. JBSL-M-01140AML-01 issue 03 dated22.02.2022Master Data List ref. JBSL-M-01140MDL-01 issue 03 dated 31.03.2022Declaration of compliance ref. JBSL-M-01140DOC-01 issue 04 dated31.03.2022or later revisionsof the above listed document(s) approved/ acceptedunder the E...	This STC applies to the aircraft types and models listed inthe EASA AMLreported in annex to this certificate. However,the designconfigurations approved for installation are limited to those listed inJet Aviation Approved Model List JBSL-M-01140AML-01 Appendix A at issue3 (or subsequent revisions)....	21/04/2022	Active	10079077

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
				DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102 CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700,701,702) CL-600-2B19 (RJ SERIES 100) CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600) BD-700-1A11 BD-700-1A10 BD-100-1A10 A380-861 A380-842 A380-841 A350-941 A350-1041 A340-643 A340-642 A340-542 A340-541 A340-313 A340-312 A340-311 A340-213 A340-212 A340-211 A330-343 A330-342 A330-341 A330-323 A330-322 A330-321 A330-303 A330-302 A330-301 A330-243F A330-243 A330-223F A330-223 A330-203 A330-202 A330-201 A321-272NX A321-272N A321-271NX A321-271N A321-253NX A321-253N A321-252NX A321-252N A321-251NX A321-251N A321-232 A321-231 A321-213 A321-212 A321-211 A321-131 A321-112 A321-111 A320-271N A320-252N						

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
				A320-251N A320-233 A320-232 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211 A319-133 A319-132 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111 A318-122 A318-121 A318-112 A318-111 A310-325 A310-324 A310-322 A310-308 A310-304 A310-222 A310-221 A310-204 A310-203 C A310-203 A300 F4-622 R A300 F4-605 R A300 F4-203 A300 C4-620 A300 C4-605 R VARIANT F A300 C4-203 A300 B4-622 R A300 B4-622 A300 B4-620 A300 B4-605 R A300 B4-603 A300 B4-601 A300 B4-2C A300 B4-220 A300 B4-203 A300 B4-120 A300 B4-103 A300 B4-102 A300 B2K-3C A300 B2-320 A300 B2-203 A300 B2-202 A300 B2-1C A300 B2-1A A300 B1 787-9 787-8 787-10 777F 777-300ER 777-300 777-200LR 777-200 767-400ER 767-300F 767-300 767-200 757-300 757-200PF 757-200 747SP 747-8F 747-8 747-400F 747-400 747-300							

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
				747-200F 747-200C 747-200B 747-100 737-900ER 737-900 737-800 737-8 737-700 737-600 737-500 737-400 737-300 737-200C 737-200 737-100 727C 727-200F 727-200 727-100C 727-100 727 720B 720 707-400 707-300C 707-300B 707-300 707-200 707-100 LONG BODY 707-100B SHORT BODY 707-100B LONG BODY						
10079083	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			A320-216 A320-214	Cabin ModificationSeating layout change to change the installed seat models and toincrease the seating capacity	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision 0 of AMES Engineering Order DocumentEO_M276001015_RSP_02112021The installation shall be accomplished in accordance with revision 0 ofAMES Instructions for Continuous Airworthiness DocumentICA_M276001015_RSP_27122021or later revisions of the above listed document(s...	The modification is only applicable to the basic aircraft model withoutany MOD as listed on the EASA TCDS is installedPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will in...	22/04/2022	Active	10079083
10079092	L2 CONSULTING SERVICES Inc.		FAA STC ST09865AC	737-700/-800/-900/-900ER	Installation of Panasonic FlightLink	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 Amdt. 0: 25.29, 25.101, 25.103, 25.105, 25.119, 25.121, 25.125,25.251, 25.301, 25.303, 25.305, 25.307, 25.365, 25.561...	Master Drawing List 3170-B107-MDL, Revision A, dated 2 November 2016<(>,<)> or later FAA approved revision.Airplane Flight Manual Supplement, Document 3170-B107-AFM, Revision B.dated 10 January 2017, or later FAA approved revision.Instructions for Continued Airworthiness, Document 3170-B107-ICA,Revi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/05/2022	Active	10079092
10079095	ANCRA INTERNATIONAL LLC	REV. 2	FAA STC ST2762LA	A320-233 A320-232 A320-231 A320-216 A320-214 A320-212 A320-211	Installation of main deck cargo loading systemRev. 1: adds two additional manufacturer serial numbers (MSN), 2164 and2288, to the Limitations and Conditions section.Rev. 2: installs Ancra Cargo Loading System P/N 85551-10 & 11 on themain deck of converted Airbus A320-200 aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Ancra International LLC Control Data List DL85551, RevisionB, dated 27December 2021,Airplane Flight Manual Supplement for Airbus A320, report number 11342,Revision IR, dated 28 January 2022<(>,<)>Instructions for Continued Airworthiness (ICA), Ancra International LLCDocument No. 11229, Rev. A, date...	The installation is for serial numbers MSN 2737, 2724, 2164and 2288, orserial numbers that have been modified in accordance with FAA STCST04493NY.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installede...	24/07/2024	Active	10079095

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079113	GULFSTREAM AEROSPACE CORPORATION			GVI (G650)	Installation of GoGo Business Avance L5 System on Gulfstream GVIaircraft	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- FAA STC ST04317AT-D- Index List, GDL100000030, Revision D, dated 15 April 2022- EASA Validated Configurations List ST04317AT-D, GCD000023158, Rev –,dated 15 April 2022.- Airplane Flight Manual Supplement, CE61302M001, Revision A, dated 11October 2018- Instructions for Continued Airworthiness, CE61...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/04/2022	Active	10079113
10079132	JET AVIATION AG			777-200LR	B777 Installation of a Tail mounted Camera on the VTP Tip and a Quad andZoom camera on the fwd lower lobe.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Certification Plan, ref.: JBSL-M-01278CER-001 Issue A, dated23/03/2022.- Instructions for Continued Airworthiness, ref.: JBSL-M-01278ICA-001Issue A, dated 28/03/2022.- Declaration of Compliance, JBSL-M-01278DOC-001, dated 27/04/2022.or later revisions of the above listed document(s) approved/ accep...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/05/2022	Active	10079132
10079142	T.P.S. S.P.A.			AW169	New neonatal transport system for AW169 P/N TPS169-11-00This change introduces the installation of a transport system equippedwith an incubator and oxygen cylinders on the AW169 helicopter	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Documents Internal Approval TP169-1100-DIA-04- Flight Manual Supplement TPS169-1100-RFMS-00- Master Document List TPS169-1100-Mdl-00- Master Drawing List TPS169-1100-Mdw-00- Instructions for Continued Airworthiness TPS169-1100-ICA-00- Installation Service Bulletin TPS169-1100-SBT-00Or later revisi...	For the operation of the Neonatal transport system p/n TPS169-11-00, theLeonardo AW169 helicopter has to be equipped with: - KIT EMS POWER SOCKET, p/n 6F2460F00411; and - EMS Machined floor, p/n 6F5332F00311, and - 8 Foldable Seats Internal Arrangement p/n 6F2520F01111 oralternately 7 Fo...	29/04/2022	Active	10079142
10079159	RECAERO	REV. 1		A320-214	RCP019 - Cabin reconfiguration / Seats and foward closets modification	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 25.853 Amdt 0The requirements for environmental protectionand the associatedcertified noise and/ or emissions levels o...	- Aircraft Manual Supplement RCP019AMS001, Issue 01- Master Data List RCP019MDL001, Issue 02- Design Service Bulletin RCP019DSB001, Issue 03Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to MSN 2011, 2325, 2390Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	24/05/2022	Active	10079159
10079180	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01978WI	737-700/-8/-800/-9/900/-900ER	Installation of a forward pressure bulkhead Kinetic Energy ProtectionDevice (KEPR)Rev. 1: Typo corrected.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt 14: 25.301(a)(b)(c), 25.303, 25.305(a)(b)(c), 25.307(a),25.365(a)(b)(d), 25.561(a)(b)(c)(d), 25.571(a)(b), 25.58...	Master Drawing List RCA-0700, Revision (-), dated 2 December 2021.Instructions for Continued Airworthiness RCA-0701, Revision (-), dated 1November 2021or later FAA approved/ accepted revision for items (1) and (2).	Installation of Boeing EVS provisions must be installed prior to, or inconcurrence with, the installation of the KEPR in accordance with thisSTC.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed ch...	20/06/2022	Active	10079180

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079182	SABENA TECHNICS BGC	REV. 1		ATR 72-212 A	Cabin Reconfiguration with Galley InstallationRev. 1: Typo corrected	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS25 at amendment 4,CS 25.1, CS 25.29, CS 25.301,CS 25.303, CS 25.305, CS 25.307, CS 25.321, CS 25.337, CS2...	Master Data list 40936-01-A-MDL-R00 dated 04 May 2022Instructions for Continued Airworthiness 40936-01-A-ICA-R00 dated 04 May2022Cabin Interior Specification 40936-01-A-CIS-R02 dated 27 April 2022or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/05/2022	Active	10079182
10079185	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			A330-243	A330 Comfort Seat InstallationThe modification changes the cabin seating layout to provide optionalseating positions for the crew on rotation based on operational needswithout imposing any further limitations to these seats.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision 0 of AMES Engineering Order DocumentEO_M154001160_KRU_15112021Maintenance shall be accomplished in accordance with revision 0 of AMESInstructions for Continuous Airworthiness DocumentICA_M154001160_KRU_15112021or later revisions of the above listed document(s) app...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/05/2022	Active	10079185
10079194	AIRBUS S.A.S.			A320-214, A320-216	Installation of a 180 pax seat layout	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Summary Report ref: SRSA-21-044 Issue 4Modification Approval Sheet ref. MASAI0229 Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/05/2022	Active	10079194
10079199	365 AEROSPACE DDS LIMITED	REV. 1		737-900, 737-900ER 737-600, 737-700, 737-800	Introduction of FANS 2 Data Link Capabilities (Dual Stack)Rev.1 corrects reference of Technical Documentation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	MDL-1502 Master Data List Revision DFMS-1502-001 Introduction of FANS 2 (Dual Stack) Revision CICA-1502-001 Instructions for Continued Airworthiness Revision Dor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This approval is only applicable to aircraft that have previously beenequipped with a CPDLC (ATN-B1) System installed by STC 10048649 Revision2 (or later approved revision) or by the aircraft Type Certificateholder using Collins Aerospace CMU-900.In addition, a SATCOM System installed by STC 1004903...	09/05/2022	Active	10079199

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079203	CARLISLE INTERCONNECT TECHNOLOGIES	REV. 1	FAA STC ST04288CH	A321-232 A321-231 A321-213,-231,-232 A321-213 A321-212 A321-211 A321-131 A321-112 A321-111,-112,-131,-211,-212 A321-111 A320-233 A320-232 A320-231,-232,-233 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211,-212,-214,-216 A320-211 A319-153N A319-151N,-153N A319-151N A319-133 A319-132 A319-131,-132,-133 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111,-112,-113,-114,-115 A319-111	Installation of an Automatic Dependent Surveillance – Broadcast Out(ADS-B Out) Transponder System withHoneywell Integrated Multi-Mode Receiver (IMMR), Model Number IMMR 20.1installed with TSO-C190 compliant GPS AntennaRev. 1: includes an update to the IMMR software version under existingConfiguratio...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS-ACNS, Book 1, Subpart C (Subsections 1, 2, 3, & 5), Navigation (NAV)CS-ACNS, Book 1, Subpart D(Section 4), Surveillance (SUR)The requirements for environm...	Master Data List, Document No. 900-102500 Revision W, dated30 September2022;Airplane Flight Manual Supplement, Document No. 900-102911 Revision E,with Configuration 1 and/or 2 installed;Airplane Flight Manual Supplement (AFMS)<(>,<)> Document 900-104704,Revision A, with Configuration 3 installed;In...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/12/2022	Active	10079203
10079227	HELI AUSTRIA GmbH			AS 332 L1 AS 332 C1 AS 332 C	Installation of a GARMIN GTN650 & GTN750 NAV / COM / GPS System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: the followingparagraphs of CS ACNS Issue 3:CS ACNS.A.GEN.010, CS ACNS.A.GEN.015, CS ACNS.B.VCS.001, CSACNS.B....	Master Document List, Doc. No. HAU-D-056-001, Rev. 0Installation Manual, Doc. No. HAU-D-056-004, Rev. 0Flight Manual Supplement, Doc. No. HAU-D-056-005, Rev. 0Instructions for Continued Airworthiness, Doc. No. HAU-D-056-006, Rev. 0Or laterrevisions of the above listed document(s) approved/acceptedu...	Limited to serial number 2082, 2123 and 2468Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/05/2022	Active	10079227
10079229	AMAC AEROSPACE SWITZERLAND AG			747-8	Cabin Reconfiguration 747-8Reconfiguration and Refurbishment of the previously installed PrivateLounge, Main Lounge andUpper Deck Cinema Area. Upgrade of the existingIFE System from eX2 to eX3 (Panasonic) and installation of a new FlightInformation System.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1557 atAmendment 12; CS 25.603, CS 25.788,CS 25.851, CS 25 Appendix S S25.1, S25.10, S25.20, S25.30,S...	The change is defined with Revision B of Master Data List documentMDL-IO04-2500.The aircraft shall be operated in accordance with Revision C of AirplaneFlight Manual Supplement document AFMS-IO04-2500.The aircraft shall be maintained in accordance with Revision A ofInstructions for Continued Airwort...	EASA STC 10053514 must be installed prior to or in conjunction with thischange.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	12/05/2022	Active	10079229
10079248	HELI-ONE (NORWAY) AS			AS 332 L, AS 332 L1 AS 332 L1 AS 332 L	TrakkaBeam Searchlight installation (ref. modification AHSE-72238).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 29 Amdt 6 for the following requirement: 29.351. CS 29 Amdt 7 for thefollowing requirement: 29.853.The re...	Certification Programme (CP) ref. AHSE-72244 Revision D dated08/02/2022.Flight Manual Supplement (FMS) for TrakkaBeam Searchlight installationref. H1No.I.327 Revisiondated 20/04/2022.Product Change Declaration (PCD) ref. AHSE-72238 Revision E dated01/04/2022.Instruction for Continued Airworthiness (...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/05/2022	Active	10079248

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079251	UMLAUT ENGINEERING GMBH	REV. 2		SEE APPROVED MODEL LIST (AML) MD-11F MD-11 ERJ 190-400 ERJ 190-300 ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 SR ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ ERJ 170-200 STD ERJ 170-200 LR ERJ 170-100 STD ERJ 170-100 LR EMB-550 EMB-545 EMB-145MP EMB-145MK EMB-145LU EMB-145LR EMB-145EU EMB-145ER EMB-145EP EMB-145 EMB-135LR EMB-135ER EMB-135BJ DHC-8-402 DHC-8-401 DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102 DC-10-30F DC-10-30 DC-10-10 CL-600-2E25 (RJ SERIES 1000) CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700,701,702) CL-600-2B19 (RJ SERIES 100) CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600) BD-700-2A12 BD-700-1A11 BD-700-1A10 BD-500-1A11 (A220-300) BD-500-1A10 (A220-100) BD-100-1A10 ATR 72-212 A ATR 72-212 ATR 72-211 ATR 72-202 ATR 72-201 ATR 72-102 ATR 72-101 ATR 42-500	Integration of Halon-free Portable Fire Extinguisher HAFEXRev. 1: 777F model added to the applicability list as per minor changeEON100072 UM-ABD01-MCA-0001Issue A.Rev. 2: Correction of the Approved Model List (AML).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt. 27:25.29(a)(b), 25.301(a)(b)(c) , 25.303, 25.305(a)(b) , 25.307(a) , 25.561(a)(b)(e) , 25.571(a)...	Master Data List UM-ABD01-MDL-0001 Issue CInstructions for Continued Airworthiness UM-ABD01-ICA-0001 Issue Cor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/01/2025	Active	10079251

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
				ATR 42-400 ATR 42-320 ATR 42-300 ATR 42-200 A380-861 A380-842 A380-841 A350-941 A350-1041 A340-643 A340-642 A340-542 A340-541 A340-313 A340-312 A340-311 A340-213 A340-212 A340-211 A330-941 A330-743L A330-343 A330-342 A330-341 A330-323 A330-322 A330-321 A330-303 A330-302 A330-301 A330-243F A330-243 A330-223F A330-223 A330-203 A330-202 A330-201						
				A321-272NX A321-272N A321-271NX A321-271N A321-253NX A321-253N A321-252NX A321-252N A321-251NX A321-251N A321-232 A321-231 A321-213 A321-212 A321-211 A321-131 A321-112 A321-111 A320-273N A320-272N A320-271N A320-253N A320-252N A320-251N A320-233 A320-232 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211 A319-153N A319-151N A319-133 A319-132 A319-131 A319-115 A319-114 A319-113 A319-112						

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
				A319-112 A319-111 A318-122 A318-121 A318-112 A318-111 A310-325 A310-324 A310-322 A310-308 A310-304 A310-222 A310-221 A310-204 A310-203 C A310-203 A300 F4-622 R A300 F4-605 R A300 F4-203 A300 C4-620 A300 C4-605 R VARIANT F A300 C4-203 A300 B4-622 R A300 B4-622 A300 B4-620 A300 B4-605 R A300 B4-603 A300 B4-601 A300 B4-2C A300 B4-220 A300 B4-203 A300 B4-120 A300 B4-103 A300 B4-102 A300 B2K-3C A300 B2-320 A300 B2-203 A300 B2-202 A300 B2-1C A300 B2-1A A300 B1 787-9 787-8 787-10 777F 777-300ER 777-300 777-200LR 777-200 767-400ER 767-300F 767-300 767-200 757-300 757-200PF 757-200 747SP 747-8F 747-8 747-400F 747-400 747-300 747-200F 747-200C 747-200B 747-100 737-900ER 737-900 737-9 737-800 737-8 737-700 737-600 737-500 737-400 737-300 737-200C						

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
				737-200 737-100 727C 727-200F 727-200 727-100C 727-100 727							
10079252	SOCIETE AIR FRANCE S.A.			A330-243	A330 Cabin RearrangementCabin Layout Change introducing a full Economy Seating Layout	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision 0 of Air France Change ApprovalSheet document CAS-A330-22-001.The installation shall be accomplished in accordance with revision 0 ofAir FranceService Bulletin document AFSB-A330-22-001-25-001The aircraft shall be maintained in accordance with revision 0 of AirFr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/05/2022	Active	10079252
10079262	NEPTUNE AVIATION SERVICES, INC.		FAA STC ST02699SE	AVRO 146-RJ100	Installation of Honeywell Flight Data Acquisition Management System (FDAMS) with Flight Control Input Position Sensors	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, NEP-MDL-P254701, Revision A, dated 27June 2020 orlater FAA approved revision.Instructions for Continued Airworthiness (ICA) for Installation ofHoneywell Flight Data Acquisition Management System (FDAMS) with FlightControl Input Position Sensors, IFCA-P254707, Revision NC, date...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/05/2022	Active	10079262
10079265	AEROSPACE DESIGN & COMPLIANCE LLC		FAA STC SA04204NY	B300, B300C B200CGT, B200GT B200, B200C 200, 200C, A200	Installation of Upper SATCOM Radome	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA04204NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Aerospace Design & Compliance, LLC., Master Data List, B350-MDL-0029,Revision IR, dated 25 January 2021, or later FAA approved revisions;2. Aerospace Design & Compliance, LLC.,Instructions for ContinuedAirworthiness (ICA), Document 264-80, Revision 0, dated 11 January 2021,or later FAA acceptedD...	This STC is applicable to all serial numbers for the Make: TextronAviation Inc. Models: B300 & B300C aircraft with 15,000 lbs MTOW andPT6A-60 Engines and Models: 200, 200C, A200, B200/B200C &B200GT/B200CGT.This approval is limited to only the installation of the Radome forSatCom Antenna provisions.f...	17/05/2022	Active	10079265
10079268	THIELE, THOMAS			PIK-20 E	PIK 20 - Inst of winglets	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS-22 at Amdt. 2,22.143 through 22.223, 22.375, 22.629, and 22.1581 through 22.1589The requirements for environmental prot...	Manufacturing drawings: TT-PIK-20E WL-57-200, sheets 1 - 2;Installation instructions: TT-PIK-20E WL-01, Rev. 2 dated 16May 2022;Supplement Flight Manual PIK-20E Operation with winglets, Issue 1, Rev.0, dated March 2022or later revisions of the above listed documents) approved/ acceptedunder the EASA...	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.	17/05/2022	Active	10079268
10079302	AERODATA AG			B300	Activation of the FLARM system	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Design Definition Document MDL-A/C-110, rev. 5Airplane Flight Manual Supplement AFM-182, Rev. 2Instructions for Continued Airworthiness AMM-816, Rev. 2or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/05/2022	Active	10079302

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079311	RECAERO			DHC-6 SERIES 300	Ladder relocation from aft door LH to aft door RH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Design Service Bulletin document RCP026DSB001 Issue 3FlightManual Supplement document RCP026FMS001 Issue 2Aircraft Manual Supplement document RCP026AMS001 Issue 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Applicable to MSN 292, 298, 300, 730, 745.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	19/05/2022	Active	10079311
10079328	NOVA SYSTEMS & ENGINEERING LIMITED			737-700	62 PAX LOPAThis modification introduces a cabin layout using 31 business classdouble seats generating a 62 passenger seating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision 0 of GVH Aerospace Master Data Listdocument GVH-13103-01-MDL-01Iss 1The aircraft shall be maintained in accordance with Issue 1 of GVHAerospaceInstructions for Continued Airworthiness documentGVH-13103-01-ICA-01 Iss 1or later revisions of the above listed documen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/05/2022	Active	10079328
10079331	BOEING IRELAND LIMITED			737-8	16J/126Y to 189Y Interior ReconfigurationReconfiguration ofpassenger cabin to remove business class seating andadjust to 189 PAX full economy class configuration. Includes removal ofstowage at Door 1L and installation of windscreen.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, '737-8: 16J/162Y to 189Y & 16J/126Y to 186YInterior Reconfiguration', BIL-00229-APP, Revision00, dated 20th May2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/05/2022	Active	10079331
10079341	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			737-800	Cabin with 189 PAX seating arrangementAdaptation of the passenger cabin to 189 PAX to fulfill operationalrequirements, by replacement of existing ETSO-C127a seats with new GevenEssenza.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS 26.150(b) from Additional Airworthiness Specifications for OperationsCS 26 Issue 2.The requirements for environmental protection and the associatedcertifie...	Master Data List: JCAERO/ MDL/0809 revision 1.0AMM Supplement: JCAERI/AMM/ 0809-1 revision 1.0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Aeroplanes modified by this STC must be maintained in accordance with:- JCAERO/ AMM/0809-1_Iss01 AMM supplement.Prior toinstallation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce...	24/05/2022	Active	10079341
10079366	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			737-800	SSUC0307 B737 Cabin RefurbishmentReplacement of all 145/165PAX Dual Class B/E Spectrum Model Seats withTSI ELESA-S Economy Class Seats, installation/rearrangement of PSUs,Panasonic MPES IFE system removal, Emergency Equipmentintroduction/replacement and renewal of curtains, carpets and NTFs.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- C0307-DWG01-01 LOPA Drawing- C0307-DWG02-01 PSU Installation Drawing- C0307-DWG04-02 Emergency Equipment Layout Drawingor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/05/2022	Active	10079366
10079369	PMV ENGINEERING	REV. 3		SEE EASA APPROVED MODEL LIST	Installation of Automated External Defibrillator (AED).Rev.1 added the BD-500 (A220) as an applicable Aircraft Type.Rev. 2 added an additional AED installation location for Aircraft TypeBD-500 (A220).Rev. 3 Amended some minor typos.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI F-132 "Non-rechargeable Lithium batteries"issue 2.- The following paragraph(s) at a later amendment: CS 25 amdt. 27:25.863, 25.130...	SEE EASA APPOVED MODEL LIST dated 24 November 2022<(>,<) >orlater revisions of the above listed document(s) approved/acceptedunder the EASA system.	-This approval is limited to the model serial numbers specified withinthe AML.- One overhead bin (OVHB) is dedicated tothe AED on aircraft typesA319, A320, A350 and BD-500. Additionally, one stowage compartment onaircraft type BD-500.- The OVHB or stowage container in which AED is installed shall n...	24/11/2022	Active	10079369

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079375	AEROLITE AG			AW189	EMS Equipment P/N 189-0307260-501 installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Flight Manual Supplement FMS-189-0307260-501 Rev 0 dated 30-03-2022-Master Document List MDL-21-001-A, dated 23-05-2022-Operations Manual OPM-189-0307260-501-Rev 0, dated 06-04-2022-Declaration of compliance-DEC-EASA 60077399 dated 30-05-2022or later revisions of the above listed document(s) approv...	Pre-requisites for installation of P/N 189-0307260-501 are given in theOperations Manual OPM-189-0307260-501-Rev 0, dated 06-04-2022.The mission Console Seat as part of the pre-requisite Kit P/N8G2520F09811 should not be installed in combination with the EMSEquipment.Prior to installation of this ch...	31/05/2022	Active	10079375
10079380	JET AVIATION AG			737-700	Introduction of several cabin upgrades to the existing office and mainlounge area.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 Amdt. 26 of 25.29, 25.301, 25.302, 25.303, 25.305, 25.307(a),25.321(a), 25.561,25.562(a)(b)(c)(1)(2)(3)(4)(7)(8), 2...	Master Data List JBSL-M-03649MDL-001, Issue CAircraft Flight Manual Supplement JBSL-M-03649AFM-001, Issue AOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	FAA STC No. ST10000SC is prerequired for installation.This approval is limited only to the installation on model 737-79U, S/N29441.Model 737-79U, S/N 29441 with this EASA STC installed cannot beregistered and operated under EU regulations as long as the interfacingFAA STC No. ST10000SC is not EASA a...	31/05/2022	Active	10079380
10079381	NOVA SYSTEMS & ENGINEERING LIMITED			737-800	GVH-13130-01-MOD-01 - 186Y PAX LOPAThis modification introduces a cabin layout using 62 economy classtriple seats generating a 186 passengers seating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Issue 1 of GVH Aerospace Master Data Listdocument GVH-13130-01-MDL-01, dated 25/MAY/2022The aircraft shall be maintained in accordance with Issue 1 of GVHAerospace Instructions for Continued Airworthiness documentGVH-13130-01-ICA-01, dated 25/MAY/2022or later revisions ofu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/05/2022	Active	10079381
10079382	SMR ACQUISITION LLCdba SMR TECHNOLOGIES, INC		FAA SA01873CH	1900, 1900C, 1900D	Replacement of certain Goodrich pneumatic de-icer boots	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Pneumatic De-icers Beech 1900 Series, SMR5137, Rev. 6, dated 28September 2021Master Drawing List for Beech 1900, 1900C, 1900D, MDL-0024, Rev. G,dated 13 September 2021Master Drawing List for Beech 1900D, MDL-0031, Rev. J, dated 17September2021or later revisions of the above listed document(s) appro...	Approval of this change in type design extends to the applicable modelswith previously approved de-icer boots.Intermix of these de-icer boots with previously approved de-icer bootsis permitted.Prior to installation of this change/ repair itmust be determined thatthe interrelationship between this ch...	31/05/2022	Active	10079382
10079395	UAVIONIX CORPORATION		FAA STC SA04568CH	SEE FAA AML	Installation of the uAvionix tailBeaconX, a tail mounted position lightwith integrated Automatic Dependent Surveillance-Broadcast (ADS-B) Outand 1090MHz Mode-S transponder functionality	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation instructions as listed on AML No. SA04568CH.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The uAvionix AV-30-C Multi-Mode Indicator is required t...	02/06/2022	Active	10079395
10079396	CAVOK			208B	Cessna 208B Cabin layout 4 Passengers	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Dossier de Certification, document 208-089-CTF-003 Issue C,dated 01June 2022Supplement to Pilot Operations Handbook, document 208-089-HBK-002 IssueA, dated 28 April 2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/06/2022	Active	10079396

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079401	NOVA SYSTEMS & ENGINEERING LIMITED			A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216	Airbus A320 - 180 PAX LOPA Installation.This design change installs new economy class seats to accommodate a 180passengers' layout on Airbus A320. The seats to be installed areeconomy-type seats and do not contain any electrical equipment orwiring, therefore no seat, seat-to-seat or cabin wiring ism...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.812(e) atChange 13.The requirements forenvironmental protection and the associatedcertified noise a...	- Master Data List ref. GVH-11907-01-MDL-01, issue1 dated 26 APR 2022- Certification Programme ref. GVH-11907-01-CP-01 Issue 3 dated 06 JAN2022- Instructions for Continued Airworthiness ref. GVH-11907-01-ICA-01,issue 1 dated 26 APR 2022or later revisions of the above listed document(s) approved/ acce...	Following changes must be installed concurrently:- GVH-9999-17-MOD-01: 'Installation of Interior Placards'- GVH-10802-02-MOD-01: 'Installation of Emergency & Safety Equipment'- EASA STC 10014013: 'Lufthansa Technik AG - Installation ofnon-electrical Floor Path marking system.'Prior to installation o...	03/06/2022	Active	10079401
10079404	TRANSPORTES AEREOS PORTUGUESES, S.A			A330-941 A321-251NX	TAP-AC300: ATA 25 - Bucher stretcher installation on TAP fleet	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment: 25.561(d),25.785(a)(b)(h)(2)(j), 25.791(a)(b), 25.803, 25.807, 25.812(e), 25.813,25.815, 25.1353(a)(b), 25.1360(a), 25.141...	Certification Report TAP-AC0300-CR-01R1 dtd. 5/ Apr/2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	As per Certification Report TAP-AC0300-CR-01EASA STC 10031757 at Revision 18 or later is a pre-requisite for thisinstallationPrior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repaire...	03/06/2022	Active	10079404
10079433	AKADEMISCHE FLIEGERGRUPPE BERLIN	REV. 1		GROB G 103 "TWIN II"	Installation of a wing-mounted sleeve with closed cross-section to carrymeasurement-equipment for inflight measurements.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Anhang zum Flughandbuch - Grob G103 Twin II - Für den Betrieb mitMesshandschuh [Revision 02] 25.05.2022Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	09/06/2022	Active	10079433
10079450	FOKKER SERVICES B.V.	REV. 1		737-900, 737-900ER 737-700, 737-800	B737-NG SBAS Landing SystemIntroduction of dual independentSBAS Landing System on aircraft with aCMA-5024 p/n 100-601967-150 GLSSU sensor installed per Fokker ServicesCPR/CRR-0425 (EASA STC 10074404).Rev. 1: corrected reference to the FCDdocument listed in the"Associated Technical Documentation" s...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:. Issue 2 of the following CS ACNS requirements:CS ACNS.C.PBN.275, CS ACNS.C.PBN.280, CS ACNS.C.PBN.305, CSACNS.C.PBN.310...	- Certification Program ref. CPR-0435 issue 7- Compliance Record Report ref. CRR-0435 issue 2- AFM Supplement ref. B737-SLS-AFM-S-001 issue 3- MMEL Supplement ref. B737-SLS-MMEL-S-001 revision 4- FCD Supplement ref. B737-SLS-FCD-S-001 issue 4or later revisions of the above listed document(s) approve...	This STC is to be applied on aircraft in conjunction with EASA STC10074404 "Activation of standalone GNSS sensor systemon Boeing 737-NGAircraft", ref CPR/ CRR-0425, installing a CMA-5024 GPS Landing SystemSensor Unit (GLSSU).Prior to installation of this change/repair it must be determined thatthe i...	18/07/2022	Active	10079450
10079471	FIELD AVIATION COMPANY Inc.		TCCA O-LSA02-635/D, ISSUE 01	DHC-8-102	Interior Reconfiguration DHC-8-102The change describes an aircraft re-configuration to restore the civilconfiguration on the DHC-8-102, S/N 038 aircraft after operation byDepartment of National Defense (DND).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Interior reconfiguration is defined with FAEL DDL-1094 Rev.B<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	This change is limited to aircraft Serial Number 038.An EASA approved change for re-arrangement of the lightning instead ofSA97-047 is required to be incorporated together with this change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change...	14/06/2022	Active	10079471
10079474	ATELIER CHABORD			F260E, F260F	F260 exhaust mufflerIntallation of a tuned exhaust and muffler	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection are unchanged but thiscertificate/ approval involves a change with an impact on thenoisedatabase and/or emission levels.	Master Document list MDL-F260-21-01F edition 5 dated 10.06.2022Aircraft flight manual supplement SUPMV-F260-21-01C dated 10.06.2022Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/06/2022	Active	10079474

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079478	PANKL AEROSPACE SYSTEMS EUROPE GMBH			A320-214	174 PAX LOPAThis modification introduces a cabin layout using 58 economy classtriple seats generating a 174 passengers seating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision 1 of Pankl Certification ProgramDocument CER_22J004_04032022The installation shall be accomplished in accordance with revision 0 ofPankl Instructions for Continuous Airworthiness DocumentICA_22J004_07042022or later revisions of the above listed document (s) approve...	The modification is only applicable to the basic aircraft model withoutany MOD defined by EASA TCDS EASA.A.064 incorporated.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair w...	15/06/2022	Active	10079478
10079482	JET AVIATION AG			777-200LR	B777 KA Band Antenna STCInstallation of KA Band Satcom System upper fuselage provisions based onArinc 791 standard and System.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-60077044-001 Issue 2 onVibration-Buffeting.The requirementsfor environmental protection and the associatedcertified noi...	JBSL-M-01275DOC-001 Issue A - Declaration of ComplianceJBSL-M-01275CCS-001 Issue B – Certification Compliance SheetJBSL-M-01275ICA-030 Issue A - Instructions for Continued Airworthiness -KA Band Antenna STC - Satcom SystemJBSL-M-01275ICA-10 Issue 1 - Instructions for Continued Airworthiness -KA Band...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2022	Active	10079482
10079510	JET AVIATION AG	REV. 2		777-200LR	B777 Installation of the structural provisions for a Live TV antennaSystem.Rev. 1 and Rev. 2 for administrative issue.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-60075907-001 Issue 2 onVibration-Buffeting.The requirementsfor environmental protection and the associatedcertified noi...	JBSL-M-01276DOC-001 Issue A - Declaration of ComplianceJBSL-M-01276CCS-01 Issue 3 – Certification Compliance SheetJBSL-M-01276MDL-001 Issue B - Master Data ListJBSL-M-01276ICA-01 Issue 1 - Instructions for Continued Airworthiness -B777 Live TV antenna STCor later revisions of the above listed docume...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/08/2022	Active	10079510
10079514	ARCHEION HOLDINGS, L.L.C.	REV. 1	FAA ST04518AT	737-9 737-800 737-8 737-700 737-400 737-300	Installation of an Avionica, avWiFi wireless system with Cyber SecurityCompliance and Hosted Application Functionality,on B737-300/-400/-700/-800/-8/-9	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List, 200450-MDL, Rev C, Dated May 5, 2021Airplane Flight Manual Supplement 200450-AFMS, Rev IR, Dated November 3,2020Instructions for Continued Airworthiness 200450-ICA, Rev B, DatedJanuary 13, 2021or later revisions of the above listed document(s) approved/accepted onbehalf of EASA inP...	FAA approved Airplane Flight Manual Supplement for ARCHEIONHoldingsLLC, 200450-AFMS, Revision IRPrior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeff...	21/06/2022	Active	10079514
10079530	FOKKER TECHNIEK B.V.			737-800	VVIP Cabin Refurbishment	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): D-101 “Isolated compartment” Issue 2< (>,<)> D-108 “Installation of glasspanels into the cabin” Issue 2.- Deviation(s): D-102 “Heat<...	Master Data List B737-HSMVS-MDL-0001 issue 2AFM Supplement B737-HSMVS-AFM-S-001 Issue 3Instructions for continued Airworthiness B737-HSMVS-ICA-S-002 Issue 2MMEL Supplement B737-HSMVS-MMEL-S-001 Issue 2or later revisions of the above listeddocument (s) approved/ acceptedunder the EASA system.	Limitations as per B737-HSMVS-AFM-S-001 and B737-HSMVS-ICA-S-002.The following certificates cover installations that need to be installedconcurrently:- STC 10053109: SATCOM installation- STC10061825: Electronic Flight Bag installation- STCEASA.IM.AS.03076 (10016636): Cabin interior noise reductionP...	21/06/2022	Active	10079530

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079537	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04332AT-D	GV-SP GV GIV-X GIV	Installation of Personal Electronic Device (PED) Interface on aGulfstream G-IV, GV, GIV-X and GV-SP aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): FAA Special Conditions 25-450-SC and 25-451-SCapplicable to Gulfstream Model GIV-X and GV-SPThe requirements for environmental protectio...	FAA STC ST04332AT-D, Personal Elec Device, (PED)Index List (IL) CE515718008 Rev –, Dated March 03, 2020Instructions forContinued Airworthiness (ICA) CE51571A007 Rev A, DatedFebruary 10, 2020or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with theP...	The instructions contained in the Installation Interface and Limitationsfor PEDS STC Compatibility with Follow-On Aircrafts CE515718012,Revision (-), dated February 25, 2020 or later approved revision must befollowed for subsequent installations of this STC.Prior to installation of this change/ repai...	21/06/2022	Active	10079537
10079539	LUFTHANSA TECHNIK AG			A321-251NX	Pluto Cabin ModificationThe modification installs a new cabin layout	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-3343-001 “Installation of high wall suite typeseating compartment”The requirements for environmental protection and the associatedcert...	Supplemental Type Design Document: STDD00-20/11M Issue 1.00Airplane Flight Manual: A-00-20/65-AFM Issue 03/00Cabin CrewData: A-00-20/65-CCD Issue: 02/00Flight Crew Data: A-00-20/65-FCD Issue: 02/00Flight Crew Information: A-00-20/65-FCI Issue: 04Instructions for Continued Airworthiness A-00-20/65-I...	Aeroplanes modified per this STC are considered to be a “new type” tothe A321-200 commercial configurations. Cabin crewoperating aeroplanesmodified per this STC must complete aircraft type specific training inaccordance with ORO.CC. 125, which must include the approved OSD-CabinCrew Data (CCD).Prior...	21/06/2022	Active	10079539
10079549	JET AVIATION AG			777-200LR	Head of State Cabin CompletionInstallation of a Head of State cabin interior into a green BOEING777-200LR	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s):CRI F-6 Security Protection of Aircraft Systems and Networks- The following paragraph(s) at a later amendment:CS25 amdt. 24:25.25,25.27...	JBSC-M-03505MDL-001 ISSUE G MASTER DATA LISTJBSC-M-03505AFM-001 ISSUE C AIRPLANE FLIGHT MANUAL SUPPLEMENTJBSC-M-03505ICA-001 ISSUE A INSTRUCTIONS FOR CONTINUED AIRWORTHINESSJBSC-M-03505CCS-001 ISSUE G CERTIFICATION COMPLIANCE SHEETJBSC-M-03505MEL-001 ISSUE B MASTER MINIMUM EQUIPMENT LIST SUPPLEMENTJ...	- Private Operation (Not-for-Hire, Non-Commercial)- Non-Smoking Aircraft- Max occupancy: 98 Pax, 4 Flight crew, 11 Cabin Crew- The aircraft must be fitted with Boeing Delivery Interior ArrangementDiagram - Zero Occupancy Certification, drawing reference LOPA 772-226Rev D.- Exterior Exit Marking - an...	24/06/2022	Active	10079549
10079555	AEROSPACE DESIGN & COMPLIANCE LLC		FAA ST04212NY	EMB-145LR, EMB-145MP EMB-145EP, EMB-145ER EMB-135KL, EMB-145XR EMB-135ER, EMB-135LR	Installation of Universal UNS-1Lw FMSThis alteration upgrades existing single or dual Universal UNS-1K FlightManagementSystems to new Universal UNS-1Lw SBAS Flight ManagementSystems.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AFM supplement: E145-AFMS-0091 Rev IR dated November 23, 2021ICA supplement: ICA E145-ICA-0091 Rev IR dated November 17, 2021Master Data List: E145-MDL-0091 Rev A dated November 23, 2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplanes modified by this STC must be maintained in accordance with:ICA E145-ICA-0091 Rev IR_ICA supplementand operated in accordance with:E145-AFMS-0091 Rev IR _AFM supplement.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair an...	23/06/2022	Active	10079555
10079560	JET AVIATION AG	REV. 2		A319-153N	VIP Cabin Interior CompletionThe modification installs a full VIP interior to a green ACJ A319-153Naircraft. The aircraft will be completed to accommodate a maximum of 19Passengers and 2 Cabin Crew. The flight deck occupation remainsunchanged from the OEM configuration, with 3 occupants.Rev 1: edito...	The Certification Basis for the original product (commercial designationACJ319Neo) as amended by the following additional or alternativeairworthiness requirements:CS 25 amendment 25:25.23, 25.25, 25.27, 25.29, 25.301, 25.302, 25.303, 25.305, 25.307,25.321, 25.337, 25.341, 25.561, 25.571, 25.581, 25....	JBSC-M-03549 MDL-001 issue G dated 27 Oct 2022.JBSC-M-03549CER-001 issue F dated 27 10 2022.JBSC-M-03549 AFM- 001 issue B - Aircraft Flight Manual Supplement dated21 June 2022.JBSC-M-03549 CCD-001 issue A - Cabin Crew Data dated 31 May 2022.JBSC-M-03549 ICA-001 issue B - Instructions for Continue...	- Private Operation (Not-for-Hire, Non-Commercial)- Non-smoking aircraft- All limitations listed in the AFM- OSD-CCD: Aeroplanes modified per this STC are considered to be a“variant” to the A319 commercial configurations. Cabin crew operatingaeroplanes modified per this STC must complete aircraft di...	31/10/2022	Active	10079560

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079561	S-TEC CORPORATION		FAA STC SR09758DS	505	S-TEC HeliSAS Stability Augmentation System installation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): 27-048-SC Visual Flight Rules Autopilot andStability Augmentation Systemthefollowing paragraph(s) at a later amendment: FAR27.1 (a)(b)2...	Master Data List No. ST-974-MDL-0001, Rev. A, dated 30 January 2020Rotorcraft Flight Manual Supplement ST-974-RFMS-0001Rev. F dated 23June 2022Instruction for Continued Airworthiness ST-974-ICA-0001 Rev. C dated 05October 2021Flight Crew Data ST-974-FCDS-0001 Rev. C dated 13 June 2022or later revis...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/06/2022	Active	10079561
10079570	AEROTEC & CONCEPT			A321-271NX/-272NX A321-271N/-272N A321-251NX/-252NX/-253 NX A321-251N/-252N/-253N A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216	IRIDIUM ANTENNA INSTALLATION - MECHANICAL PROVISIONS	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	MDL Doc, AE22001MDL Rev.: 0 (20/06/22)ICA Doc. AE22001ICA Rev.: 0 (04/01/2022)or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	ICA Doc. AE22001ICA Rev: 0 (04/01/2022)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	27/06/2022	Active	10079570
10079576	ISRAEL AEROSPACE INDUSTRIES, LTD.IAI	REV. 7	CAAI NO. SA300	737-800	Conversion of a Boeing 737-800 PAX airplane configuration into a SpecialFreighter (SF).This conversion to a special freighter configuration among otherfeatures includes a main deck Class E cargo compartment and associatedsmoke detection system; installation of a main deck cargo door withsurroundingb...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-01 “Courier compartment” issue 2; D-02 “Class Ecargo compartments fire protection of essential systems” issue 2; D-03“Access to classt...	The following IAI’s documents:-365-00-00-M4560 Master Document List MDL revision AJ, and-365-00-00-M4565 Airplane Flight Manual Supplement (EASA) revision 3 (C),and-365-00-00-M4556Structural Repair Manual Supplement revision 7, and-365-00-00-M4554 Maintenance Planning Document (MPD) Supplement toBoe...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Serial Number B737-800 aircraft converted into this IAI...	27/10/2025	Active	10079576
10079580	NSE			EC 130 T2 EC 130 B4 AS 350 D AS 350 B, AS 350 B1 AS 350 BA, AS 350 BB AS 350 B2, AS 350 B3	Installation of BCT (Communication and Tracking Box)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 27 Amdt. 7: 27.21,27.301, 27.303, 27.305, 27.561, 27.601, 27.603, 27.607, 27.609, 27.610,27.611, 27.613, 2...	-Mounting Instruction MD-00040028AA A2-Rotorcraft Flight Manual Supplement RFMS-BCT-Ecureuil-EN 01-Instruction for Continued Airworthiness ICA-00040028AA A2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/06/2022	Active	10079580
10079582	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04343AT-D	GVII-G600 GVII-G500	Installation of an Air Ionization System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04343AT-D.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of theu...	1. Gulfstream Aerospace Corporation Index List GDL 100000059 Rev (-),dated 8 March 2022;2. FAA accepted Instructions for Continued Airworthiness - AirIonization System (GVII-G500/GVII-G600), GC73728A001 Revision (-), dated9 February 2022;3. FAA approved Air Ionization System - EWIS - Instructions fo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/06/2022	Active	10079582

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079595	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-201/-202/-203/-223/-243	Transportation of Cargo in the CabinThis change covers passenger cabin conversion for transportation ofcargo to comply with the operator's requirement to perform cargo flightson cabin floor without cargo pallets using cargo nets and restraintstraps.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Deviation(s): CRI D-01 (Transportation of cargo in passengercompartments)The requirements for environmental protection and the associatedcertified noise and/...	AFM Supplement: JCAERO/AFM/0714-1 Issue 1.2Cabin and Cargo Handling limitations manual: JCAERO/SUPP/0714-1 Issue1.2AMM Supplement: JCAERO_AMM_0714-1 Issue 1Master Data List: JCAERO_MDL_0714_ISS 1.0MPD supplement: Page 7 and 8 JCAERO_MCDC_074 Issue 1or later revisions of the above listed document (s)...	Aeroplanes modified by this STC must be maintained in accordance with:-,,JCAERO/AMM/0714-1 and Page 7 and 8 JCAERO_MCDC_074 Issue 1and must be operated in accordance with:- JCAERO/AFM/0714-1 Issue 1.2 and JCAERO/SUPP/0714-2The allowance oftransport cargo in passenger compartment is limited to2000 F...	29/06/2022	Active	10079595
10079597	SIRIUM AEROTECH S.L.			A340-311,-312,-313 A330-223,-243,-223F,-243F A330-201,-203,-203	ADS-B Upgrade for A330 and A340 Airplanes	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	SA20-23S-MDL Rev. 05SA20-23S-AFMS Rev. 01SA20-23S-AMMS Rev. 02or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	SA20-23S-AMMS Rev.02, ALS SectionTransponder installation on affected aircraft must be compatible withADS-B DO-260B andthe provisions must be installed per SIRIUM MODADSB-A330-002 or MOD ADSB-A340-002Prior to installation of this change/repair it must be determined thatthe interrelationship between...	30/06/2022	Active	10079597
10079604	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1	FAA ST02730SE	787-9	Installation of a VIP interior in accordance with GreenpointTechnologies, Inc., Drawing List G14561003-DL-01.Revision 1: - Transfer of the STC 10079604 from Greenpoint Technologies, Inc. toNorthwest Aerospace Technologies, Inc - Editorial correction of EASA Certification Basis.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:,,-Special Condition(s):1) CRI D-02 Side facing seats, issue 2 dated 28 June 20212) CRI F-01 Information security protection of aircraft systems andnetworks,...	Greenpoint Technologies, Inc. Master Drawing List G14561003-DL-01Revision FGreenpoint Technologies, Inc. Airplane Flight Manual SupplementG14561003-FM-02 Revision IRGreenpoint Technologies, Inc. Master Minimum Equipment List SupplementG14561003-MEL-01 Revision BGreenpoint Technologies, Inc Supplemen...	Aeroplanes modified in accordance with this STC are a "variant" to theB787-9 commercial configurations. Cabin crew operating the aeroplanemodified per this STC must complete an aircraft difference training inaccordance with EU OPS ORO.CC.130 which must include the approved EASACabin Crew Data – Supp...	08/12/2022	Active	10079604
10079609	SIERRA INDUSTRIES Ltd.		FAA STC SA5737SW	T210M, P210N 210K, 210L, 210M, T210K, T210L	Remove main landing gear doors and associated hydraulic system, andcover the wheel wells with a fairing.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions dated September 12, 1984or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/07/2022	Active	10079609
10079613	S4A SOLUTIONS FOR AVIATION, S.L			A330-243	330_262: Cabin ModificationLateral (FWD) stowage replacement and installation of new ones	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	330_262-18-02 Master document list (30/06/2022) 330_262-12-30 Maintenance Manual Supplement, Edition 1or later revisionsof the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/07/2022	Active	10079613
10079622	PMV ENGINEERING	REV. 1		ATR 72-212 A ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202	P2F-00040 Window plugs ATR72REV. 1: removing the windows inspection ICA task	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR25 Chg. 15:25.301, 25.303, 25.305, 25.307, 25.365, 25.561, 25.571, 25.581, 25.601,25.603, 25.609, 25.613...	Master Document List P2F-00040-MDL-S00 Rev 01Instructions for continued airworthiness P2F-00040-ICA Rev 01or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/01/2023	Active	10079622

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079645	CAVOK			B300	Skytrack Antenna installation/removal	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Service Bulletin, document 350-116-SB-007, Issue D, dated 29 November2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/07/2022	Active	10079645
10079646	SABENA TECHNICS BGC			A321-271N/-272N A321-251N/-252N/-253N A321-231/-232 A321-211/-212/-213 A321-111/-112/-131	Cabin Reconfiguration from 195PAX (12B/C + 183 Y/C) to 220PAX (220 Y/C)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: JAR25 at change 11:25.1441,CS-25 at amdt. 4: 25.1, 25.29, 25.561, 25.562, 25.785, 25.787, 25.789,25.791, 25....	Master Data List, Ref. 41006-01-A-MDL-R00 dated July 04th 2022Instructions for continued airworthiness, Ref. 41006-01-A-ICA-R00 datedJuly 04th 2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:Installation of a photo-luminescent EFPM as per Lufthansa Technik'sEngineering Bulletin A320-EB33-0384, approved by EASA STC No. 10014013Prior to installationt...	05/07/2022	Active	10079646
10079656	NOVA SYSTEMS & ENGINEERING LIMITED	REV. 1		A330-223, A330-243 A330-201, A330-202, A330-203	Passenger Service System & In-seat USB Power Installation.Installation of Inflight Canada(IFC) passenger service systemwithIn-seat USB power system (PSS+P). This change includes the installationof the PSS+P equipment, electrical harnesses and connection to aircraftpower.Installation of the seat moun...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 Initial Issue; 25.1/.23/.25/.27/.29/.301/.303/.307/.337/.341/.365/.561/.562/.571/.601/.603/.605/.607/.609/.613/.625...	Master Data List GVH-8292-04-MDL-01 Issue 3<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/02/2024	Active	10079656
10079658	LEE AEROSPACE, INC.		FAA ST04208NY	55, 55B, 55C, 60	Installation of LAI Windshields	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04208NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Data List, LAI-MDL-121, Revision IR, dated 10 May 2021Instructions for Continued Airworthiness (ICA) LAI-ICA-121, Revision IR,dated 12 February 2021or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/07/2022	Active	10079658
10079659	ADVANCED AEROSPACE DEVELOPMENTS GMB			MBB-BK117 C-2	Installation of "07EOS" Hensoldt ARGOS-II HD Electro-Optical System(EOS).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program, Document No. AAD-CP-07EOS-001 Issue 03 dated24.06.2022;Master Drawing List, Document No. AAD-DWL-07EOS-001 Issue 07 dated13.06.2022;Master Documents List, Document No. AAD-MDL-07EOS-001 Issue 01 dated30.06.2022;Flight Manual Supplement, Document No. AAD-FMS-07EOS-001 Issue 022...	This STC is not approved for MBB-BK117 C-2e.The installation of the "07EOS" Hensoldt ARGOS-II HD Electro-OpticalSystem is not equipped with a video device and requires priorinstallation of the utility step mount from AIRFILM CAMERA SYSTEMS, INC.(STC No. SR02137LA).It is the operator's responsibility...	07/07/2022	Active	10079659

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079660	BELL TEXTRON, Inc.		FAA SR03336NY	206B	Installation of interior blankets in passenger compartment	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation Drawing List Report No. AA-13021 Revision D, dated 19September 2013Lawson Aerospace LLC Instructions for Continued Airworthiness Report No.AA-12055 Revision C,dated 30 May 2013or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Te...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/07/2022	Active	10079660
10079682	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A340-311/-312/-313 A340-211/-212/-213	Transportation of Cargo in the CabinThis change covers passenger cabin conversion for transportation ofcargo to comply with the operator's requirement to perform cargo flightson cabin floor without cargo pallets using cargo nets and restraintstraps	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Deviation(s): CRI D-01 (Transportation of cargo in passengercompartments).The requirements forenvironmental protection and the associatedcertified noise a...	AFM Supplement: JCAERO/AFM/0773-1 Issue 1.0Cabin and Cargo Handling limitations manual: JCAERO/SUPP/0773-2 Issue1.1AMM Supplement: JCAERO_AMM_0773-1 Issue 1.0Master Data List: JCAERO_MDL_0773_ISS 1.0MPD supplement: Page 7 and 8 JCAERO_MCDC_0773 Issue 1.0or later revisions of the above listed docum...	Aeroplanes modified by this STC must be maintained in accordance with:- JCAERO/AMM/0773-1 and Page 7 and 8 JCAERO_MCDC_0773 Issue 1.0and must be operated in accordance with:- JCAERO/AFM/0773-1 Issue 1.0 and JCAERO/SUPP/0773-2 Issue 1.1The allowance of transport cargo in passenger compartment is limi...	08/07/2022	Active	10079682
10079689	THALES AVIONICS Inc.		FAA STC ST02449LA	A321-272N, -272NX A321-271N, 271NX A321-253N, -253NX A321-252N, -252NX A321-251N, -251NX A321-231, -232 A321-211, -212, -213 A320-271N, -272N, -273N A320-251N, -252N, -253N A320-216, -231, -232, -233 A320-211, -212, -214, -215	Modification of existing Thales Avionics TopSeries In-flightEntertainment (IFE) System	The Certification Bases for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS.25 Amd 025.305 (a),(b),(c) 25.30725.56125.61325.62525.853 (a)25.869(a)(4)25.1351(a)(1)The requirements for environmental p...	- FAA Approved Thales Avionics Index List, Drawing No. 255274, Revision"A", dated 15 January 2013;- The Instructions for Continued Airworthiness is called out in itsassociated Master Drawing Lists (MDL) defined in the above referencedIndexList;or later revisions of the above listed document(s) appr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/07/2022	Active	10079689
10079691	LUFTHANSA TECHNIK AG			A340-213	Antenna Sys. Installation & Activation of WLAN-Function	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Design Definition STDD53-20/09M Issue 02 Rev 00Airplane Flight Manual Supplement A-00-21/26-AFM Issue01 Rev 00Instructions for Continued Airworthiness A-00-21/26-ICA Issue 01 Rev 00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	EASA STC 10078929 must be installed prior or concurrently.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the produ...	11/07/2022	Active	10079691
10079698	ATLANTIC AVIATION GROUP LIMITED			737-800	Avolon B737-800 (MSN 35646) LOPA ReconfigurationThe proposed change is a cabin reconfiguration from 183 to the maximumof 189 passenger layout. The following modifications will be performed:- Removal of existing (183 Pax) shipset of Recaro seats, Installation ofnew (189 Pax) shipset of Recaro 3530	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: 25.1703(a)(b)(e),25.1707(a)(b), 25.1709, 25.1711, 25.1713(a)(c), 25.1715, 25.1717,25.1719 and 25/1729 at CS-2...	Master Data List AAG-22-C004-MDL, Revision 3, dated 9th July 2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/07/2022	Active	10079698

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079703	MT-PROPELLER ENTWICKLUNG GmbH			E33, F33, H35, J35, K35, M35 35-B33, 35-C33 35-33, 35-A33	Installation of MTV-9-D/200-52( ) Propeller on Beechcraft ()33, ( )35and 35-( )33 aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase...	According to MT-Propeller Master Documentation List No. E-3776 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-3778Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-3779 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3780 Rev. 0or later...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/07/2022	Active	10079703
10079705	MT-PROPELLER ENTWICKLUNG GmbH		LBA STC SA 1318	414	Extension of the existing LBA STC SA 1318:Installation of MTV-14-D-C-F/ CF188-30( ) Propeller on Cessna 414.Installationof MTV-14-D-C-F/ CF188-30( ) Propeller on Cessna 414modifiedby FAA STC SA4379SW (RAM 4).Installation of MTV-14-D-C-F/ CF188-30( ) Propeller on Textron AviationInc. 414 modified byST...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase...	According to MT-Propeller Master Documentation List No. E-3964 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-881Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-882 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3968 Rev. 0or later r...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/07/2022	Active	10079705
10079715	SAFRAN AEROSYSTEMS			EC 130 T2 EC 130 B4	Quick Removal System for Airbus Helicopters (AH) Emergency FloatationSystem (EFS)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List DT-0017426 issue 01Aircraft MaintenanceManual Supplement ILS-000235 issue 03Certification Program DT-00017181 rev 03or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC can be applied to AH EFS configuration (P/N 704A42690054 forLHS and P/N 704A42690053 for RHS)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adver...	13/07/2022	Active	10079715
10079719	GUENTERT + KOHLMETZ GMBH			DG-800 S DG-600/18 DG-600 DG-300 ELAN ACRO DG-300 ELAN DG-300, DG-300 ELAN DG-300 CLUB ELAN ACRO DG-300 CLUB ELAN DG-300	Installation of the turbine PSR T-01 into DG-300.	The type certification bases for the original product remainsapplicable. Due to the installation of the turbine, the followingparagraphs are additionally affected:JAR 22.901 - JAR22.902 - JAR 22.903 - JAR 22.955 - JAR 22.959 - JAR 22963 -JAR 22.965 - JAR 22.967JAR 22.969 - JAR 22.971 - JAR 22 9732...	- Ergänzendes Flughandbuch, Ausgabe Dezember 2021- Ergänzendes Wartungshandbuch, Ausgabe Dezember 2021Or later revisions of the above listed document (s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/07/2022	Active	10079719
10079720	ROCKWELL COLLINS, Inc.		FAA STC ST01836LA	747-400	Installation of Rockwell Collins, Inc. Aircraft CommunicationsAddressing and Reporting System (ACARS)	The Certification Bases for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS25 Amd 1225.301 (a),(b),(c)25.30325.305(a)(b) 25.307(a)25.341(a)(b)25.561(a)(b)(c)25.581(b)(1)(c)(2)25.60125.603 (a)(b)(c)2...	1. Master Data List 2847-01, Revision L, dated 19 May 2014;2. Instructions for Continued Airworthiness 2847-14, Revision NC, dated2 September 2005;3. Instructions for Continued Airworthiness 1510-14, Revision B, dated19 May 2014;4. Airplane Flight Manual Supplement RCA-0471, Revision NC, dated 27Jan...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/07/2022	Active	10079720
10079731	ROEDER PRAEZISION GMBH			B300, B300C	Infrared Suppressing Systems (IRSS)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation Instructions, document A1915-001, Rev 1DrawingList, document 21-06276DL Rev BAircraft Flight Manual Supplement, document 21-06276FM Rev CInstructions for Continued Airworthiness, document 21-06276CA Rev Bor later revisions ofthe above listed document(s) approved/acceptedunder the EASA...	Applicable to King Air B300/300C aircraft with PT6A-67A engine, MTV-275-bladed propeller and up to 8000kg (17.637 lb.) MTOW.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair w...	18/07/2022	Active	10079731

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079734	HELI-ONE (NORWAY) AS			AS 332 L1	Night Vision Imaging System (NVIS) re-evaluation (ref. modificationAHSE-72950).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 29 Amdt 2 for the following requirements: 29.1, 29.141, 29.1383,29.1501, 29.1529, 29.1581, 29.1583, 29.15...	Certification Programme (CP) ref. AHSE-72952 Revision B, dated26/01/2022.Flight Manual Supplement (FMS) for NVIS re-evaluation ref. H1No.I.361Revision dated 14/07/2022.Product Change Declaration (PCD) ref. AHSE-72950 Revision A, dated01/02/2022.Instructions for Continued Airworthiness (ICA) ref. AHS...	This design change is limited to the AS 332 L1 Serial Numbers (S/Ns)3042, 3043, 3045 and 3047 with configuration described in the ProjectDescription document ref. AHSE-72956 Revision A dated 26/01/2022 and ICAdocument ref. AHSE-72958 Revision C dated 13/06/2022.Rotorcraft modified by this design cha...	18/07/2022	Active	10079734
10079735	SABENA TECHNICS BGC	REV. 2		ERJ 190-300, ERJ 190-400 ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW ERJ 190-100 STD ERJ 190-100 LR, ERJ 190-100 SR ERJ 190-100 IGW ERJ 190-100 ECJ	Mounting device and power supply connection for PIVOT EFB solutions onE190Rev 1: new configuration (named CONF 2) of the mechanical configurationcompatible with “PIVOT” cases without sliding rail and integration of anew location FWD for the USB power.Rev 2: Amended inspections interval on supplement...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:- CS-25 at amendment 4 paragraphs: 25.899, 25.1301, 25.1309, 25.1351,25.1353, 25.1357, 25.1360, 25.1431- CS-...	- Master Data List, Ref. 10008-01-A-MDL-R04 dated 30 Apr 2024- Airplane Flight Manual Supplement, Ref. 10008-01-A-AFMS-R05 dated 19Jul 2023- Instructions for continued airworthiness, Ref. 10008-01-A-ICA-R02dated 04 Mar 2024- Master MinimumEquipment List Supplement Document, Ref.10008-01-A-MMELS-R00...	- Limitations as per §3 of Airplane Flight Manual Supplement documentreferenced above.- The Installation of the USB power connection option is limited to theERJ 190-100/-200.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any...	03/05/2024	Active	10079735
10079744	GDC ENGINEERING GmbH			A330-202	Provisional cargo compartment : A330 LEVISThe proposed design change will convert the passenger compartment into acargocompartment.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Deviation(s): Deviation D-4328-001 Issue 1 ‘Transportation of cargo inpassenger compartments’the following paragraph(s) at a later amendment: CS25 at Amdt 26§...	- Master certification document list (MCDL) CCN-A332J Issue01 signed on18.July.2022- Aircraft Flight Manual supplementA332J-AFM-36V Revision 2 signed on08.Jun.2022- Instructionsfor Continued Airworthiness supplement A332J-ICA-36VRevision 00 signed on 04.Feb.2022- Weight & balance manual supplemen...	- The allowance to transport cargo in passenger compartmentis limitedto 2 000 FH following installation of the change or to 31 July 2022,whatever occurs first.- Aeroplanes modified per this STC are a “variant” to the A330-200 passenger configurations. Cabin crew operating aeroplanes modified perthi...	19/07/2022	Active	10079744
10079749	ROSEMOUNT AEROSPACE, Inc.	REV. 1	FAA STC ST04520CH	A321-253N/-271N/-272N/-271NX A321-213/-231/-232/-251N A321-111/-112/-131/-211/-212 A320-233/-251N/-271N A320-211/-212/-214/-231/-232 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of Rosemount Aerospace Aircraft Interface Device (AID) DataLoader ProvisionsRev. 1: adds A321-271NX aircraft to the applicability list andincorporates minor design changes for alternate aircraft connectorcontacts to accommodate varying incoming aircraft configurations.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval except the following paragraphsat CS 25 Amendment 3:25.869(a)(4), 25.981(a)The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the pro...	Rosemount Aerospace Inc. Master Data List, Doc. No. D000022110, RevisionD, dated 13 December 2024<(>,<)>Instructions for Continued Airworthiness, Document No. D000027450Revision C, dated 19 November 2024or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordan...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Previous or concurrent installation of Rosemount Aerosp...	24/03/2025	Active	10079749
10079788	NOVA SYSTEMS & ENGINEERING LIMITED	REV. 1		A340-642, A340-643	Airbus A340 Zero Pax LOPARev. 1: A new pre mod A340 LOPA configuration was added, identified asOrange Configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): D-1/60085475 - Transportation of specialcategories of occupants on aeroplanes subject to a no pax/ no cargo limitation in the cabin.-...	NSI-13525-01-MDL-01 Master Data List Issue 3 dtd. 24-Mar-2023NSI-13525-01-FMS-01 Flight Manual Supplement Issue 3 dtd. 06-Mar-2023NSI-13525-01-ICA-01 Instructions for Continued Airworthiness Issue 2dtd. 21-Mar-2023NSI-13525-01-MMEL-01 MMELSupplement Issue 3 dtd. 21-Mar-2023or later revisions of the...	- Per NSI-13525-01-FMS-01 Flight Manual Supplement- EASA STC 10076250 embodied prior to 31 July 2022 is a prerequisite forthe YELLOW and RED+ Configuration.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously i...	27/03/2023	Active	10079788

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079801	SABENA TECHNICS BGC	REV. 1		A320-251N	Cabin reconfiguration with 186 Y/C seatsRevision 1 of the certificate aimed to review of the certificationbasis.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 amdt. 4: 25.1,25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341, 25.365,25.561, 25.562, 25....	Certification plan reference 41052-01-A-CP-R03 dated 26 July 2022Master Data List 41052-01-A-MDL-R02 dated 26 July 2022Instructions for Continued Airworthiness 41052-01-A-ICA-R00 dated 19July 2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik EASASTC No. 10014013 Rev 02.Prior to installation of this change/repair it must be determine...	27/07/2022	Active	10079801
10079835	TELEDYNE CONTROLS, LLC		FAA STC ST05726LA	A321-271N/-271NX/-272N /-272NX A321-252N/-252NX/-253N /-253NX A321-213/-231/-232/251N/ -251NX A321-111/-112/-131/-211/-212 A320-253N/-271N/272N/ 273N A320-231/-232/-233/-251N /-252N A320-211/-212/-214/-215/-216 A319-131/-132/-133/-151N /-153N A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Installation of Teledyne Aircraft Cabin Environmental Sensor (ACES)System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	FAA Approved Master Data List (MDL) MDL2252300-A320, Rev. “-“, dated 20May 2021The Instructions for Continued Airworthiness are called out in theMaster Drawing List (MDL) MDL2252300-A320, Rev. “-“, dated 20 May 2021Weight and Balance Manual WB2252300-A320, dated 7 February 2022or later revisions ofb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/07/2022	Active	10079835
10079870	SKANDIA, INC		FAA STC ST04526CH	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Installation of Thermal/Acoustic kits	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, Document Number 7803-051MDL, Revision A, dated 5January 2021or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of he product.	08/08/2022	Active	10079870
10079875	JET AVIATION AG			737-800	Passenger Oxygen System Replacement	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment:CS-25 Amdt. 26 of 25.29, 25.301, 25.302, 25.305, 25.307(a), 25.321(a),25.561, 25.601, 25.603, 25.605(a), 25.609, 25.611, 25...	Master Data List JBSL-M-03736MDL-001, Issue CInstructions for Continued Airworthiness JBSL-M-03736ICA-001, Issue AOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Lufthansa Technik STC LBA. 21E2.TA0547 is prerequired for installation.Non Smoking Aircraft.	04/08/2022	Active	10079875
10079876	AKADEMISCHE FLIEGERGRUPPE BRAUNSCHWEIG e.V.			SEE EASA APPROVED MODEL LIST	Installation of a sensor box for gliders and powered gliders with aT-tail.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:As type certification bases, CS-22 Amendment 3 was chosen instead ofJAR-22 (miscellaneous Changes). Following paragraphs were taken intoaccount:-CS 22.23-CS 2...	-Anhang zum Flughandbuch - Duo Discus (T) für den Betrieb mitMASB-Messbox, Revision 01, 2022-07-22-Anhang zum Flughandbuch - Discus-2c für den Betrieb mit MASB-Messbox,Revision 01, 2022-07-22-Änderungsübersicht - Duo Discus (T) Change Definition Document, issue04, 2022-07-29-Änderungsübersicht - Dis...	None	05/08/2022	Active	10079876

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079878	FIELD AVIATION COMPANY Inc.		TCCA STC O-LSA02-634/D	DHC-8-102	Relocation, Removal and Modification of Avionics and Electrical Systems	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation, Removal and Modification must be in accordance with FieldAviation Master Drawing and Data List designatedDDL1091 Rev IRMaintenance must be performed in accordance with Field AviationMaintenance Manual Supplements designated MMS20063 Rev IR and MMS20064Rev IROr later revisions of the a...	Limited to aircraft serial number 38Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/08/2022	Active	10079878
10079886	AEROTEC & CONCEPT			DR 400 NGL, DR 400 RP DR 400/500 DR 400/200 R, DR 400/2+2 DR 400/200 I, DR 400/180 S DR 400/180, DR 400/180 R DR 400/160, DR 400/160 D DR 400/140, DR 400/140 B DR 400/125, DR 400/125I DR 400/120 A, DR 400/120 D DR 400/100, DR 400/120	DR 400 IFR & LPV Certification	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List Doc AE20005MDL dated 03 August 2022Aircraft Flight Manual Supplement (AFMS) Doc AE20005AFMS dated 03 August2022Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	08/08/2022	Active	10079886
10079889	HAECO CABIN SOLUTIONS, LLC		FAA STC ST04167AT	737-800	Interior Reconfiguration of a Boeing 737-800 aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 at amdt. 27: 25.571(a)(b), 25.853(a)(b), 25.981 (d)The requirements for environmental protection and the associatedcer...	TIMCO Master Data List 13T309L001, Revision L, dated 5 July2016,TIMCO Aerosystems Instructions for Continued Airworthiness 13T309R009,Revision D, dated 15 December 2016< (>,<)>TIMCO Aerosystems Airplane Flight Manual Supplement TIM-AFM-01049, RevIR dated 26 November 2014<(>,<) >or later revisions ofb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/08/2022	Active	10079889
10079891	Q.C.M. DESIGN GmbH			60	P-RNAV (RNP-1) airworthiness approval based on existing aircraftavionics systems	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Maintained in accordance with L60X-QCM34-003-M1-ICA Instructions forContinued Airworthiness rev 0; operated in accordance withL60X-QCM34-003-M1-AFM Aircraft Flight Manual rev 0Duncan Aviation Master Document List 120726002 Rev A and associated FAAForm 8100-9or later revisions of the above listed doc...	Limited to aircraft Learjet 60 s/n 186.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	09/08/2022	Active	10079891
10079892	FIELD AVIATION COMPANY Inc.		TCCA O-LSA06-281/D, ISSUE 1	DHC-8-102	Retrofit Installation of Rockwell Collins TCAS/ACAS II SW 7.0, DualMode-S Transponders and VHF-1 Comm.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of retrofit modification must be performed in accordancewith FAEL Master Drawing and Data List designated DDL-1017, Rev. BBTCAS/ACAS II operation must be conducted inaccordance with FieldAviation Company Inc. Flight Manual Supplement designated FMS 20111 RevIRMaintenance must be conduc...	Limited to Aircraft Serial Number 28.Bombardier TCAS II andMode-S structural provisions are a requiredprerequisite to the Collins TCAS/ACAS II and Mode-S system retrofit. Ifnot already fitted with the appropriate structural provisions,Bombardier Structural Provisions Service Bulletin designated SBa...	09/08/2022	Active	10079892

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079893	ENVOY AEROSPACE, LLC	REV. 1	FAA ST04402CH	737-900, 737-900ER 737-700, 737-800	Halotron BrX Fire Extinguisher ReplacementReplacement of existing Halon 1211 portable fire extinguishers withHalotron BrX portable fire extinguishers.Rev. 1: adds additional configurations on Boeing 737-700 and -800Series aircraft, where new Kidde brackets may need to be installed<(>,<)> and the fi...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.29, 25.301(a)(b), 25.303, 25.305 (a)(b),25.307 (a), 25.561 (c)(d), 25.601,25.603, 25.605 (a), 25.611...	The installation is defined with Revision D of the Envoy AerospaceMaster Data List document E18047-2620-L001, dated 1 October 2024Maintenance shall be accomplished in accordance with Revision D of theEnvoy Aerospace Instructions for Continued Airworthiness DocumentE18047-2620-B001or later revisionsb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/11/2024	Active	10079893
10079894	AVIONIK STRAUBING ENTWICKLUNGS GmbH			400, 400A	Installation of single Garmin GA 36 GPS/ WAAS Antenna on topfuselage.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with ASR-2022-010-IFI-10-00 Rev 00,Maintainedin accordance with ASR-2022-010-ICA-11-00 Rev 00<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This installation is limited to the mechanical installation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the pro...	09/08/2022	Active	10079894
10079897	FLUGSPORTVERIN BAD TOELZ e. V.			HK 36 TTC	Increase MTOM from 770kg to 800kg	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed and operated in accordance with Flughandbuch Ergänzung FSV-BadTölz rev 8 and ZertifizierungsplanFSV Bad Tölz dated 5/2/2021<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to aircraft S/N 36600; airspeed limitation shall beclearlydisplayed in the cockpit.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect u...	10/08/2022	Active	10079897
10079898	AIR PROJET			RF 4 RF 3 FOURNIER RF 4 D FOURNIER RF 3	BERINGER Wheel and Brake upgrade for Fournier RF 3<(>&<)>4 (Roue etfrein BERINGER Fournier RF 3<(>&<)>4)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-22 Amd 3 paragraphs:22.473, 22.721, 22.725, 22.731, 22.883The requirements for environmental protection an...	Installed in accordance with Document Number: APFC-0102, Revision 4,Dated 4th August 2022;Operated in accordance with Document Number: APAFM-0102, Revision 3,Dated 2nd February 2022;Maintained in accordance with Document Number: APSMM-0102, Revision 3,Dated 12th May 2022<(>,<)>And documents listed i...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/08/2022	Active	10079898
10079899	GFD GmbH			36A 35A	Mechanical provision for the installation of an antenna, located betweenframe 13D and frame 13C along BL 0<(>,<)>	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed and maintained in accordance with Engineering Order ref21-015-EO-01 rev 00 and Master Data List ref 21-015-MDL-01 rev 0.4or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to the installation of the antenna doubler plates and respectivecover platePrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the a...	10/08/2022	Active	10079899

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079922	DOA AESGLOBAL LIMITED			737-800	INSTALLATION OF FORWARD CABIN CLOSETSThis modification installs seat track mounted underbin coat stowages tothe forwardleft and righthand cabin area of the aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.561 (a)-(d),25.601, 25.603 (a)-(c), 25.605 (a)(b), 25.609 (a)(b), 25.613 (a) – (c),25.619 (a) – (c), 25...	The change is defined with Issue 2 of AES Master Data List DocumentAES-737-6530M DLThe installation shall be maintained in accordance with Issue 1 of AESInstructions for ContinuousAirworthiness Document AES-TR-3170or later revisions of theabove listed document(s) approved/acceptedunder the EASA sys...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/08/2022	Active	10079922
10079923	FLYING COLOURS CORP.			BD-700-2A12	Installation of a Satellite TV SystemInstallation of equipment to support satellite TV display on cabin IFE.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-B/E Aerospace Limited Modification Data Summary N547000, Revision NC,dated February 08, 2022-Flying Colours Corp. Instructions for Continued Airworthiness, N547070Revision A, dated May 13th, 2022or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/08/2022	Active	10079923
10079925	FIELD AVIATION COMPANY Inc.		TCCA O-LSA02-632/D, ISSUE 1	DHC-8-102	Bendix King KDM-706A DME / KFS-564A NAV 1 Frequency Control Retrofit	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation, Removal and Modification must be in accordance with FieldAviation Master Drawing and Data List designatedDDL-1086 Rev IRMaintenance must be performed in accordance with Field AviationMaintenance Manual Supplements designatedMMS20053 Rev IROr later revisions of the above listed docume...	Limited to aircraft serial number 38.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	12/08/2022	Active	10079925
10079926	FIELD AVIATION COMPANY Inc.		TCCA C-LSA02-222/D, ISSUE 1	DHC-8-102	Installation of Replacement Seat Cushion/Cover Assemblies	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of Replacement Seat Cushion/Cover Assemblies to beperformed in accordance with Field Aviaiton Company Inc Drawings:-) Mode 920 Seats: DWG 18322501, initial issue-) Model 910 Seats: DWG 18322502, initial issue-) Attendants Seats: DWG 18322503, initial issueor later revisions of the above...	Limited to Aircraft S/N 038.Prior to installation of this change/ repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect uponthe airworthiness of the product	12/08/2022	Active	10079926
10079931	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC SA11299DS	SEE FAA AML	An update to the existing Collins Aerospace Integrated FlightInformation System (IFIS) FSU-5010 and upgrade the existing XMWR-1000 toa XMWR-1000S (Sirius XM) in Part 23 aircraft.Rev. 1: Change of Address	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List 657-00-0001, Revision IR, dated 27 June 2022Instructions for Continued Airworthiness as referenced in the attachedAMLor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral A...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/08/2025	Active	10079931

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079962	EIRTECH AVIATION SERVICES LIMITED			767-300	CABIN MODIFICATION 767-300This modification covers the removal of Passenger Seats achieving a 6B/C (Group 1) or a 12 B/C (Group 2) configuration for supernumeraryoccupants.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The Change is defined with Issue 2 of Eirtech Aviation Services MasterDocument List Document MDL/ 1635-001The aircraft shall be operated in accordance with Issue 2 of EirtechAviation Services Flight Manual Supplement Document FMS/ 1635-001.Maintenance shall be conducted in accordance with Issue 2 of E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/08/2022	Active	10079962
10079963	AVIADECO GmbH			ATR72-212A	Defibrillator Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 “Non-rechargeable Lithium BatteryInstallations”The following paragraph(s) at a later amendment: CS-25 paragraph 25.853Amdt 27Th...	Master Documentation List (MDL-02022) with Rev. 00 dated 26.07.2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/08/2022	Active	10079963
10079967	AVMAX AVIATION SERVICES Inc.		TCCA C-LSA09-077/D, ISSUE 2	DHC-8-102	Avionics & Equipment Installations	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Definition of the Type Design Change in accordance with Avmax TopDocuments List 116888-400, Rev. 15.Installation of theAvionics & Equipment is to be done in accordancewith Western Avionics Engineering Order 11688-401, Revision 1.Maintenance is to be performed in accordance with Western AvionicsMain...	Limited to aircraft Serial Number 028.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	19/08/2022	Active	10079967
10079968	BOEING IRELAND LIMITED			787-10	Introduction of PEC Cabin for KLMIntroduction of a premium economy cabin in the forward section of zone Bthrough introduction of four rows of TSO-C127b seats. Reconfiguration ofeconomy comfort and economy ETSO-C127a seats in the aft section of zoneB. Seat reconfiguration includes associated changesc...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, ‘KLM 787-10 Introduction of Premium EconomyCabin’, BIL-00196-APP, Revision 00, dated 17th August 2022<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/08/2022	Active	10079968
10079971	APTOZ EHF.			777-300, 777-300ER 777-200, 777-200LR	Zero pax LOPACabin, with no passenger seats installed.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-MMEL Issue 02.The requirements for environmental protection and the associatedcertified noise and/ or em...	AFM supplement Ref: AFM251315-1 Rev: IRICA supplement Ref: ICA251315-1 Rev:AMMEL supplement Ref: MMEL251315-1 Rev:IRMaster Data List: MDL251315 Rev: Aor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft must be operated in accordance with AFM supplement Ref:AFM251315-1 Rev: IR<(>,<)>WBM supplement Ref: ICA251315-1-WBM Rev: IR andMMEL supplement Ref: MMEL251315-1 Rev:IR.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repai...	22/08/2022	Active	10079971
10079973	AVIADECO GmbH			CL-600-2D24 (RJ SERIES 900)	Defibrillator Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): CRI F-01 “Non-rechargeable Lithium BatteryInstallations”The following paragraph(s) at a later amendment: CS-25 paragraph 25.853Amdt 27Th...	Master Documentation List (MDL-02122) with Rev. 01 dated 27.07.2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/08/2022	Active	10079973

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079988	ISRAEL AEROSPACE INDUSTRIES, LTD.IAI		CAAI SA299	737-700	Conversion of a Boeing 737-700 PAX airplane configuration into a SpecialFreighter (SF)This conversion to a special freighter configuration among otherfeatures includes a main deckClass E cargo compartment and associatedsmoke detection system; installation of a main deck cargo door withsurrounding s...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): D-01 “Couriercompartment” issue 2; D-02 “ClassE cargo compartments fire protection of essential systems” issue 2; D-03“Access to clas...	The following IAI’s documents:· 365-00-00-M4510 Master Document List MDL revision M· 365-00-00-M4525 Airplane Flight Manual Supplement (EASA) revision New· 365-00-00-M4515 Structural Repair Manual Supplement revision D· 365-00-00-M4504 Maintenance Planning Document (MPD) Supplement toBoeing Document...	B737-700 aircraft converted into this IAI’s Special Freighter (SF) configuration STC are re-delivered without ETOPS airworthiness approval.B737-700 aircraft converted into this IAI’s Special Freighter (SF)configuration STC are re-delivered without Reduced Vertical SeparationMinimum (RVSM) airworthine...	23/08/2022	Active	10079988
10079990	DELTA ENGINEERING CORPORATION		FAA STC ST04107NY	A350-941	Installation of a Panasonic Avionics In-Flight Entertainment System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List 0173-11438-2551, Revision A, dated 9March 2022or later revisions of the above listeddocument(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.The Instructions for Continued Airworthiness...	This STC is applicable to all serial numbers listed in the Master DataList under Description of Type Design Change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intro...	23/08/2022	Active	10079990
10079991	SCANDINAVIAN AVIONICS DESIGN ApS			GVI (G650)	Cabin Interior ModificationModification of the Cabin to generate a 12 Passenger SeatingConfiguration including an upgrade of the In-Flight-EntertainmentSystem.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.788 atAmendment 19, CS 25 Appendix S at Amendment 26.The requirements for environmental protection an...	The Change is defined with Scandinavian Avionics Design CertificationDocuments List 3000055 DOC, issue 1.The installation is defined with the Scandinavian Avionics DesignTechnicalOrder 3000055-TO, issue 1.The aircraft shall be operated inaccordance with Scandinavian AvionicsDesign Airplane Flighta...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10079991
10079992	DELTA AIR LINES, INC.d/b/a DELTA TECHOPS AND/ OR DTO		FAA STC ST02014AT	767-300	Installation of forward and aft cargo compartment floor panels	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST02014AT.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Delta Engineering Order 1-74138-3, Revision B< (>,<)> dated 23 September1999<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10079992
10079994	DELTA AIR LINES, INC.d/b/a DELTA TECHOPS AND/ OR DTO		FAA STC ST01357AT	767-300	Installation of Allied Signal/Bendix Weather Radar System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Air Lines Engineering Report Number 1-71855-20, IR, dated 15 April1997<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/08/2022	Active	10079994

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10079998	AMAC AEROSPACE SWITZERLAND AG			SEE EASA APPROVED MODEL LIST	Certification Wireless Charging StationThis modification covers the activation of Wireless Charging Systems forPortableElectronic Devices (PED) comprising one or more WirelessCharging Stations installed in the Cabin.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1, CS 25.601,CS 25.869, CS 25.899, CS 25.1301, CS 25.1309, CS 25.1322, CS 25.1351, CS25.1353, CS 25.1...	The Change is defined with Revision A of AMAC Aerospace Master DocumentList Document MDL-ALLAC01-2470.Maintenance shallbe conducted in accordance with Revision A of AMACAerospaceInstructions for Continued Airworthiness documentICA-ALLAC01-2470or later revisions of the above listed document(s) appr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/08/2022	Active	10079998
10080000	BROMMA AIR MAINTENANCE AB			AW139	Internet connection of EFBs with WiFi.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 29 Amdt 9, 29.25,29.301, 29.303, 29.305, 29.307, 29.341, 29.561, 29.571, 29.601, 29.603,29.605, 29.607,2...	- AF-16-16-01 Rev B MCA-Approval Form (Mechanical & electrical install)- ICA-16-16 Rev C Instruction for Continued Airworthiness- FMS-16-16 Rev B Flight Manual Supplementor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/08/2022	Active	10080000
10080014	CHIPPEWA AEROSPACE, Inc.		FAA STC ST04012AT	A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-223/-223F/-243/-243F A330-201/-202/-203 A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-216/-231/-232/-233 A320-211/-212/-214 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of a Portable Data Loader (PDL)	The Certification Bases for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt 0: 25.561, 25.601, 25.605, 25.607, 25.789, 25.899, 25.1307,25.1431, 25.1525, 25.1529, 25.1541CS 25 amdt 1: 25.301, 25.303, 25.305, 25.307, 25.609, 25.613CS 25 a...	Chippewa Aerospace Master Drawing List (MDL) No. PDL-3170-01-0001, Rev.IR, dated 30 April 2013<(>,<)>Instructions for Continued Airworthiness (ICA), Chippewa Aerospace Inc.Document No. PDL-3170-01-0002, Rev. IR, dated 30 April 2013<(>,<)>or later revisions of the above listed document(s) approved/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/09/2022	Active	10080014
10080015	HAECO CABIN SOLUTIONS, LLC		FAA STC ST02826AT-D	767-300	Installation of a Honeywell Mode S Enhanced Surveillance Transponder andActivation of an ADS-B Out System for Hudson Bay Area Operations	The Certification Bases for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 amdt. 27: 25.1,25.601, 25.981(d), 25.1529.The requirements for environmental protection and the associatedcertifieda...	1. TIMCO Master Data List 03T092L001, Revision C, dated 3 July 2014;2. TIMCO Instructions for Continued Airworthiness 03T092R007, RevisionA, dated 6 December 2004;3. TIMCO Instructions for Continued Airworthiness 13T302R009, Revision Adated 15 October 2014;4. Approved Airplane Flight Manual Suppleme...	No evidence of compliance with CS-ACNS provided for the ADS-B Out systeminstallation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	17/04/2023	Active	10080015
10080018	DOA AESGLOBAL LIMITED	REV. 1		737-800	REPLACEMENT of G1 AND G2 GALLEYSTHIS CHANGE INTRODUCES A REPLACEMENT GALLEY IN THE G1 AND G2 POSITIONSON THE AIRCRAFT.Rev. 1 enables removal of all installation limitations.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 Amdt 4: CS25.899, 25.1301, 25.1309, 25.1351, 25.1353, 25.1357,25.1431 CS-25 Amdt 27: CS 25.1, 25.561,2...	Master Data List: AES-737-6690MDL Issue 02 dated Sept 23ICAsupplement: AES-TR-3273 Issue 01AMM, IPC and WDM Supplements: AES-TP-0400 Initial Issueor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft must be maintained in accordance with ICA supplementreferenced AES-TR-3273 Issue 01.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeff...	17/05/2024	Active	10080018

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080020	DELTA AIR LINES, INC.d/b/a DELTA TECHOPS AND/ OR DTO		FAA STC SA2964SO	767-300 767-200	Installation of AlliedSignal TCAS II	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impactt...	MDL 34-1074<(>,<)> IR, dated 5 April 2000<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	For the purpose of compliance with IR1207/2011, concurrent installationof EASA STC 10067669 (FAA STC ST02126LA) is required.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair w...	26/09/2022	Active	10080020
10080029	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			SEE EASA APPROVED MODEL LIST A340-313 A340-311 A330-343 A330-303 A330-302 A330-223 A330-203 A321-232 A321-231 A320-232 A319-132 777-300ER 737-900ER 737-800 737-8 737-700	NEW VERSION AIR TRANSPORT STRETCHER	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:25.1(a), 25.25(a)(b), 25.27(all), 25.305(a)(b), 25.307 (a), 25.321, 25.341(all), 25.471,25.561(a)(b)(1)(b)(3) (c)(1) (c)(2)...	- Certification Programme C0177-CEP-07 dtd. 25.08.2022- Component User Manual C0177-CUM-01 dtd. 04.07.2022or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	- per Certification Programme C0177-CEP-07- per Component User Manual C0177-CUM-01- This STC constitutes an approval for installation only for aircraftserial numbers as stated in the Certification Program C0177-CEP. Foradditional aircraft serial numbers, the requirements for full compliancehave to b...	29/08/2022	Active	10080029
10080030	DELTA AIR LINES, INC.d/b/a DELTA TECHOPS AND/ OR DTO		FAA STC ST01757AT	767-300 767-200	Installation of an Enhanced Ground Proximity Warning System(EGPWS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Engineering Order 1-71327-3, Revision A, dated 7 January1998;2. Airplane Flight Manual Supplement, dated 13 November 1998;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/08/2022	Active	10080030
10080043	MAGELLAN AEROSPACE		TCCA SH93-12 ISSUE 7	412, 412EP	Installation of a Wire Strike Protection System.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Configuration 1 - Installation P/N 364-83300-5 (for Standard Skid GearHelicopters) or P/ N 364-83300-7 (for High Skid Gear Helicopters):·,,Drawing List, Document No. EM105301 Issue F;·,,Installation Instructions, Document No. ER100374, Issue D;·,,Maintenance Manual Supplement and Illustrated Parts L...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/09/2022	Active	10080043
10080048	SABENA TECHNICS BGC	REV. 1		A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112	Structure Reinforcement Common Design for ARINC 791 Large AntennaInstallation on Airbus Single AisleRev. 1 – Revised fatigue calculation due to changed loads. Revisedapplicabilityto add A320 NEO models.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 at Amendment 4 Paragraphs: 25.1, 25.29, 25.561, 25.611, 25.843,25. 853, 25.1301, 25.1309, 25.1525CS 25 a...	Master Data List - 0887-03-A-MDL rev 04Instructions for continued airworthiness - 0887-03-A-ICA rev 02or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/11/2024	Active	10080048

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080059	SABENA TECHNICS BGC			A320-251N	A320-Neo Cabin Reconfiguration with 186 Pax	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR-25 at Change 11:25.1441, CS-25 at amendment 4: 25.1, 25.29, 25.561, 25.562, 25.785,25.787, 25.789, 25.7...	Master Data List, Ref. 41048-01-A-MDL-R00, dated 31st August 2022;Instructions for continued airworthiness, Ref. 41048-01-A-ICA-R00 ,dated 31st August 2022or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:- Installation of a photo-luminescent EFPM as per Lufthansa Technik EASASTC No. 10014013 Rev 02.Prior to installation of this change/repair it must be determi...	02/09/2022	Active	10080059
10080065	GDC ENGINEERING GmbH	REV. 2		A330-343 A330-202	Airbus A330 PAX to Freighter: MEDIUSConversion from a passenger aircraft configuration to an “AvensisMEDIUS” freighter,an intermediate Class E freighter type with noinstallation of main deck cargo door and no installation of a cargoloading system.Revision1: adds model A330-343 to the applicabilityR...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):- E-124: Couriercompartment dated 06th June 2008<(>,<)>- E-125: Class E cargo compartment fire protection of essential systemsdated 27th...	A330-202 model:- Master Certification Document List: CCN-A332H-MCDL Issue 02<(>,<)>- Airworthiness Limitations SectionsSupplement: A332H-ALS-A Issue 07< (>,<)>- Airplane Flight Manual Supplement: A332H-AFM-A Issue 07< (>,<)>- Weight & Balance Manual Supplement: A332H-WBM-A Issue 02< (>,<)>- Flight Cre...	Aeroplanes modified per this STC must not be previously equipped with astandalone/non-integrated alerting system.Aeroplanes should not have subsequent cockpit modifications embodiedwithout application to EASA and consultation to the STC holder.Prior to installation of this change/repair it must be d...	24/04/2025	Active	10080065
10080125	HONEYWELL INTERNATIONAL Inc.		FAA ST02737LA	777-300, 777-300ER, 777F 777-200, 777-200LR	Installation of Honeywell LED Modules in the Forward Position	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): IssuePaper SE-1 (ProjectNo.STC-Redmond1-0280).The requirements for environmental protection and the associatedcertified noise...	- Honeywell Master Drawing List 756-0280-001, revision - dated12/11/2020- Honeywell Instructions for Continued Airworthiness document number756-0280-800, revision -, dated 10/28/2020<(>,<)>Or later revisions of the above listed document(s)approved/ accepted onbehalf of EASA in accordance with the Te...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/09/2022	Active	10080125
10080130	L2 CONSULTING SERVICES Inc.		FAA ST09927AC	737-900, 737-900ER, 737-9 737-700, 737-800, 737-8	Installation of a Gables Audio Management System:K01 configuration: Audio Management SystemK02 configuration: SATVOICE Panel	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Master Data List 2351-B130-MDL, Revision B, dated 10 March 2022Configuration K01:- Airplane Flight Manual Supplement 2351-B130-AFMS-01, Revision IR,dated 30 March 2022- Instructions for Continued Airworthiness (ICA), L2 ConsultingServices, Inc. Document 2351-B130-ICA-01Rev. IR, dated 04 March 2022...	Configurations K01 and K02 can be installed independently or bothconfigurations can be installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeff...	19/09/2022	Active	10080130
10080133	AIR PROJET			FOURNIER RF 4 D	Wingtip Display Pod RF4Wingtip pod that carrys pyrotechnic cartridges and lights for aerobaticdisplays.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of wingtip pods in accordance with Air Projet document APPC-0114, at revision 4,dated August 26, 2022;Aircraft Flight Manual Supplement, Air Projet document APAFM-0114, atrevision 0, dated August 30, 2022;Aircraft MaintenanceManual Supplement, Air Projet document APSMM-0114,at revisi...	Applicability limited to MSN 4014 and 4030.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	13/09/2022	Active	10080133

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080135	LUFTHANSA TECHNIK AG			787-8, 787-9, 787-10	Inst. of non-electrical FPM SystemInstallation of non-electrical Floor Path Marking System: The systemconsists of a continuous photoluminescent strip down both sides of thecabin aisle. The photoluminescent strip will be charged by the cabinlighting and will then glow greenish at total darkness.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Definition Document: STDD33-22/02M Issue: 1/0Airplane Flight Manual Supplement: A-00-22/11-AFM Issue:1/0Instructions for Continued Airworthiness: A-00-22/11-ICAIssue 2/0Master Minimum Equipment List Supplement: A-00-22/11-MMEL Issue -/0or later revisions of the above listed docum...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/09/2022	Active	10080135
10080138	AEROTEC & CONCEPT			H160-B	Cabin Configurations (Modification 21080)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): ESF -d29.807-01_ Use of flight crewemergency exits for passenger evacuation with the rotorcraft on its sidedated 27th OCT. 2...	- Master data list (mdl)- ref. ae21080MDL issue 0 dated 14/09/2022.- Rotorcraft flight manual supplement ref.ae21080RFMS issue 0 dated14/09/2022.- Instruction for continued airworthiness ref. ae21080ICA issue 0 dated14/09/2022.or later revisions of the above listed document(s) approved/ acceptedunder...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/09/2022	Active	10080138
10080178	AVCON INDUSTRIES, Inc.		FAA STC SA2428CE	B300 200, 200CT, 200T, B200, B200C,	Installation of provisions for a scanner, with optional drop hatch.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1. Avcon Drawing List No. 1044, dated November 1, 1988<(>,<)>2. Airplane Flight Manual Supplement, Revision OR, dated October 31,1988, for Model 200 series, dated November 22, 1994 for a scanner<(>,<)>3. Airplane Flight Manual Supplement, No. 00607102, Revision IR, datedMay 26, 2022, for Models B200...	1. These airplanes are in a Restricted Category when this modificationis installed.2. Prior to installation of this change/ repair it must be determinedthat the interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon th...	22/09/2022	Active	10080178
10080184	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST02775CH	A319-112	Installation of a Aircraft Passenger Cabin Modifications	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 0: 25.23 (a), 25.29(a)(b) , 25.303, 25.305 (a)(b) ,25.561(a)(b)(c) , 25.562(a) (b)(c) , 25.601, 25.603(a)(b)(c) , 2...	Armstrong Aerospace Master Data List, Doc. No. DC104-7008-00, RevisionB, dated October 28, 2009<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalfof EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This modification requires the previous or concurrent m...	31/01/2023	Active	10080184
10080191	BELL TEXTRON, Inc.		FAA STC SR01092DE	3. 429 2. 206L-4, 407 2. 206L, 206L-1, 206L-3 2. 206A, 206B 1. 505	Installation of QuantiFLY Data Acquisition System	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	1. Doc No. AA-21072, Master Drawing List, Bell QuantiFly Part 27 AML,Revision IR dated 6 May 2022, FAA approved 26 May 2022;2. Doc No. AA-21073, Instructions for Continued Airworthiness, RevisionIR dated 3 May 2022, FAA accepted 26 May 2022;or later revisions of the above listed document(s) approved...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/02/2023	Active	10080191

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080201 (2004-3216 / CAA.21NE2.00081)	STRAIGHT FLIGHT, LLC	REV. 1	FAA STC SA00515DE	206H, T206H	Modification of aircraft floor to create 20 inch camera holeRevision 1 is an administrative re-issuance of EASA approval number2004-3216 dated 30 March 2004.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. FAA STC SA00515DE and Straight Flight Master Drawing List 0001-2328,Revision A, dated 27 August 2003, FAA approved 9September 2003;2. AFM Supplement to Cessna 206H/T206H Airplane Flight Manual, STCSA00515DE, Revision A, dated 9 September 2003;or later revisions of the above listed document (s) ap...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/09/2022	Active	10080201
10080232	NORTHWEST AEROSPACE TECHNOLOGIESINC.		FAA STC ST02489SE	777-300ER	Interior refresh and installation of interior components	The Type and OSD Certification Bases for the original product as amendedby the following additional oralternative airworthiness requirements:the following paragraph(s) at a later amendment: CS 25 amdt. 6:25.856(a), 25.869(a)(4), 25.899 (a)(1)(3)(b)(1)The requirements for environmental protection andc...	Northwest Aerospace Technologies, Inc. (NAT) Master DrawingList (MDL) N0548-D10, Revision D, dated 21 March 2017<(>,<) >Instructions for Continued Airworthiness (ICA) N0548-D70, Revision -,dated 24 October 2016<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EAS...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The configuration covered by STC 10046995 (FAA STC ST03...	19/10/2022	Active	10080232
10080234	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04131AT	747-400F 747-400	Installation of an AD Aerospace CARGOVu Camera System in Boeing 747-400aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements: the following paragraph(s) at a lateramendment:CS 25 at amdt. 0: 25.29, 25.303, 25.561, 25.601, 25.771, 25.789,25.1431, 25.1529, 25.1541, 25.1581CS 25 at amdt. 1: 25.305,C...	Master Drawing List 212093-MDL, Revision C, dated 24 September 2013< (>,<)>Airplane Flight Manual Supplement for the AD Aerospace CARGOVu CameraSystem, 212093-FMS, revision IR, dated 25 September 2013<(>,<) >Instructions for Continued Airworthiness (ICA), Avionics Support GroupDocument 212093-ICA , Re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2022	Active	10080234
10080235	ALAMO ENGINEERING GmbH			DORNIER 328-100	STRUCTURAL INTEGRATION OF FLIR SYSTEM REPLACEMENT	The Certification Basis for the original product remains applicable tothis certificate/ approval.The Certification Basis for the original product as amended by thefollowing additional or alternative airworthiness requirements:The followingparagraph(s) at a later amendment:JAR 25, Change 12, Amendme...	INSTRUCTIONS FOR CONTINUED AIRWORTHINESSICA22A11AE-01 Rev. A 2022/09/23Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Functional aspects of the FLIR System are not included in this approval.	28/09/2022	Active	10080235
10080241	LUFTHANSA TECHNIK AG			A350-941	A350 – Cabin CompletionInstallation of cabin interior, electrical and mechanical systems andstructural attachments throughout the cabin.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): SC D-300 Is. 01‘Personal injury criteria ofdynamic testing of side facing seats’The requirements for environmental protection and the a...	Supplemental Type Design Document STDD00-20/02M Issue 01 Revision 01Airplane Flight Manual Supplement A-00-20/34-AFM Issue 05 Revision 00Instructions for Continued Airworthiness A-00-20/34-ICA Issue 01Revision 00Master Minimum Equipment List Supplement A-00-20/34-MMEL Issue 02Flight Crew Data Supple...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/09/2022	Active	10080241

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080242	MAGNETIC MRO AS			A320-214	A320 cabin reconfigurationThis STC covers the reconfiguration of the Airbus A320 Series aircraftfrom dual class 132 PAXLOPA to a single class 180 PAX all economy LOPAas part of aircraft redelivery programme along with other cabinrefurbishment works.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Programme ref MMRO-C-0105-CP-01 issue 4Level Of Involvement assessment ref MMRO-C-0105-LOI-01 issue 3or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is applicable to A320-214 MSN 4273 only.This STC can be applied on aircraft only provided that Airbus SB320-52-1162 (Type III Over Wing Exit activation) is also concurrentlyapplied, and that is it checked prior to release to service that theexternal passenger emergency exit markings are pre...	29/09/2022	Active	10080242
10080246	STERLING CORPORATIOND/ B/A STERLING HELICOPTER	REV. 1	FAA SR04713NY	212, 412, 412EP	Installation of LS400NR-T/LS400T LED steerable searchlight assembly.Rev. 1 corrects the company name.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- CS 29 Amendment 8 for parts changed or affected by the change.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of...	- MDL Document Number 910109, Rev. A, dated February 25, 2022.- ICA Document Number 910110, Rev. C, dated February 25, 2022.- Rotorcraft Flight Manual Supplement, Document No. 910145, Rev.IR, FAAapproved March 10, 2022Or later revisions ofthe above listed document(s) approved/ accepted onbehalf of E...	The Bell 212 or 412 series helicopter must be OEM equipped with a PAR46searchlight at the approximate OEM location on the belly of therotorcraft.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed ch...	28/11/2022	Active	10080246
10080250	BHE & ASSOCIATES, LTD.	REV. 1	FAA ST11285DS	SEE FAA APPROVED MODEL LIST	An update to the existing Collins Aerospace Integrated FlightInformation System (IFIS) FSU-5010 and upgrade the existing XMWR-1000 toa XMWR-1 000S (Sirius XM) in Part 25 aircraftRev. 1: Change of Address	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST11285DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List, 665-00-0001 Revision A, dated 22 June 2022;2. Instructions for Continued Airworthiness<(>,<)> 665-00-0014, Rev. A,dated 21 June 2022;or later revisions of theabove listed document(s) approved/ accepted onbehalf of EASAin accordance with the Technical ImplementationProcedures of...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List ST11285DS dated 24 June 2022.See FAA Approved Model List for additional limitations and conditions.Prior to installation of this change/repair it must be determined thatthe interrelationship bet...	08/08/2025	Active	10080250
10080256	SABENA TECHNICS BGC			A321-232 A321-231 A321-213 A321-212 A321-211	Cabin Reconfiguration from 195 PAX (195 Y/C) to 220 PAX (220 Y/C)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25 at amendment 4paragraphs: 25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337,25.341, 25.365, 2...	Master Data List, Ref. 40955-01-A-MDL-R00 dated 30th September 2022Instructions for Continued Airworthiness, Ref. 40955-01-A-ICA-R00 dated30th September 2022or later revisions ofthe above listed document(s) approved/acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:Installation of a photo-luminescent EFPM as per Lufthansa Technik'sEngineering Bulletin, approved by EASA STC 10014013 Rev. 2. The EFPM STCref. EASA 10014013 R...	04/10/2022	Active	10080256
10080265	ETIHAD AIRWAYS ENGINEERING L.L.C.			A320-251N	PASSENGER CABIN RECONFIGURATION 174 PAX	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:JAR 25 at change 13: 25.365(f)(g), 25.812(b)(1)(c)(e)(k) ,25.853(a)(b)(2)(b)(3)(c)(d)(e)(f)JAR 25 change 14:...	Master Document List EA2-22251656-DL01 rev 1AMM Supplement EA2-22251656-PA02 rev 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/10/2022	Active	10080265
10080268	AIRCRAFT SYSTEMS AND MANUFACTURIN G,Inc.	REV. 1	FAA STC SA09887AC	SEE FAA AML	Installation of an Avionica MK-III mini Quick Access Recorder (QAR) andoptional 4G or LTE Avionica Cellular Module (avCM)Rev. 1 is a transfer of STC from ARCHEION HOLDINGS, L.L.C.to AIRCRAFTSYSTEMS AND MANUFACTURING, Inc.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Master Drawing List 221250-MDL, Revision F, dated 4 August 2022<(>,<)>Archeion Holdings Instructions for Continued Airworthiness, 221250-ICA,Revision IR, dated 7 June 2022<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Imp...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	05/05/2025	Active	10080268

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080273	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special transportation of non-active satelliteIssue 1 of ATI modification ST25MOD020 (applicant's reference) wasdeveloped, reviewed, tested and found compliant with the CertificationBasis to deal with non-Airbus sub-assemblies transport.Oncase-by-case basis, this modification is up-issued to covert...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Change Approval Sheet (CAS) ST25MOD020Ed57 Issue 1 dated 05 October2022- Change Certification Plan (CCP) ST25MOD020Ed57 Issue 1 – Non activesatellite in CTH04 container + HeaterTransport dated 22 September 2022- Approved Document Dossier (ADD) ST25MOD020 Ed57_ADD Issue 2 includingAFM, WBM and MME...	The transported satellite is expected to contain active systems whichhave not been assessed as part of this change. Theintended flights aretherefore expected to be subject to an airworthiness exemption grantedby the competent authority.Prior to installation of this change/repair it must be determin...	05/10/2022	Active	10080273
10080277	LEARJET Inc.		FAA STC ST00793WI	60	Installation of Dual Rockwell Collins RTU-4220 Radio TuningUnits (RTU) System.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	(1) Learjet Master Document List M100264ICT, Revision D, dated 9 June1999<(>,<)> (2) Learjet, Inc. Document No. WI471, Airplane Flight Manual Supplement,dated 17 June 1999<(>,<)>orlater revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Impl...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/10/2022	Active	10080277
10080318	L2 CONSULTING SERVICES Inc.		FAA STC ST11152SC	767-200/-300/-300F	Installation of the Iridium Communications System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt. 0: 25.29(a), 25.365(a)(b)(c)(d), 25.561(c) , 25.571(a)(b) ,25.603 , 25.625(a) , 25.789(a) , 25.869(a)(1) , 25.981(a)(3)(d) ,25.1351(a) , 25.1355(a) , 25.1381,2...	Master Drawing List 2325-B78-MDL<(>,<)> Revision A, dated 19 July 2013<(>,<)>Airplane Flight Manual Supplement 2325-B78-AFM, Revision IR, dated 13November 2013<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/11/2022	Active	10080318
10080319	DELTA AIR LINES, INC.d/b/a DELTA TECHOPS AND/ OR DTO		FAA STC SA3305SO	767-300 767-200	Installation of a Delta modified forward trunnion bearing housing and aDelta manufactured bearing retainer bolt to allow forced lubrication ofthe respective joints	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta E.O. 1-65641-3, dated 8 August 1992or later revisionsof the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/10/2022	Active	10080319
10080326	DELTA ENGINEERING CORPORATION		FAA STC ST03412NY	A321-213/-231/-232/-233 A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-215/-216	Installation of a ViaSat Radome/Antenna and relocation of VHF 3 antenna(as required) as per following configurations:- Configuration 1: Mantarray- Configuration 2: Demod- Configuration 3: Thales to KuKarray- Configuration 4: Mantarray to KuKarray- Configuration 5: Thales to Mantarray- Configuration...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B-101 "Vibration/ buffeting compliancecriteria for large external antenna installation" Rev. 2the following paragraph(s) at a lat...	Master Data List 0164-09569-2405 Revision R Configurations 1, 3, 4, 5, 6:AFM Supplement 0664-09847-2405 Rev AInstructions for Continued Airworthiness 0764-09568-2405 Rev FConfiguration 2:Instructions for Continued Airworthiness 0764-09568-2405 Rev For later revisions of the above listed document(s)b...	- No antennas of any size may be installed within 36" FWD or AFT of theradome without additional flight testing for vibration and buffeting. - Configuration 3 and 5 of the Master Data List requires priorinstallation and validation by EASA of FAA STC ST03251CH.Prior to installation of this change/rep...	10/10/2022	Active	10080326

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080329	TELAIR US LLC		FAA STC ST04460AT	767-300	Installation of the Main Deck Cargo Loading System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS 25 amdt. 0: 25.23, 25.27, 25.601, 25.607, 25.609, 25.619, 25.621,25.623, 25.625, 25.1529CS 25 amdt. 1: 25.301, 25.303, 25.305(a)(b)(c) , 25.307CS 25 amdt. 5: 25.1301CSC...	B767-300 BCF Master Drawing List for 69000-Series Cargo Handling System,U.S. Cargo Systems Report Number RPT-3890, Revision 3.0, dated 10 July2019<(>,<) >B767-300 BCF PIN 69000-Series MDCLS Weight & Balance Manual Supplement,U.S. Cargo Systems Report Number RPT-3919, Revision 1.0, dated 16September 2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/10/2022	Active	10080329
10080349	DIAMOND AIRCRAFT INDUSTRIES GmbH			DA 62	Business Seating Configuration 1st Passenger RowThis STC provides an alternative configuration for the DA 62 with morecomfort in the 1st passenger row. The 1st passenger row is limited to 2passengers with installation of an armrest on the middle seat. The DA 621st passenger row 2/3 backrest is repla...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	STC 62-004AFM Supplement STC 62-004 to Doc. No. 7.01.25-E and Doc. No. 11.01.05-ESupplemental AMM Doc. No. 7.02.25-STC 62-004or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/10/2022	Active	10080349
10080361	DOA AESGLOBAL LIMITED			ERJ 190-100 STD ERJ 190-100 SR ERJ 190-100 LR ERJ 190-100 IGW ERJ 190-100 ECJ	ACTIVATION OF BLUEBOX WIFI SYSTEM	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: EASA CS 25 Amdt 4Sections 25.869, 25.1301. 25.1309, 25.1353, 25.1431, 25.1529 and EASA CS25 Amdt 27; Sectio...	Master Document List AES-190-6546 MDL Issue 1AFMS No 99 AFMSupplement Issue 1CCOMS No 67 Cabin Crew Operating Operation Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/10/2022	Active	10080361
10080396	SPAES GmbH & Co. KG	REV. 1		AS 365 N2, AS 365 N3	Installation of Tactical Radio Antenna (STC 0508)Rev. 1 corrects the Technical Documentation reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program: CFP-365-508-23-01, Revision 0.3, dated 17/10/2022Compliance Checklist: CCL-365-508-23-01, Revision 0.1, dated 29/09/2022Declaration of Compliance: DOC-365-508-23-01, Revision 1.0, dated14/10/2022or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/12/2022	Active	10080396
10080436	TECCON CONSULTING & ENGINEERINGGmbH			CL-600-2B16 (604 VARIANT)	Repositioning of water panel and filler port	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with Installation instruction document ref.617-10030-IIN-0001 rev. A;Maintained in accordance with ICA Supplement document ref. 617-10030-ICA-0001 rev. B;orlater revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to aircraft s/n 5322Prior to installation of this change/ repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect uponthe airworthiness of the product.	24/10/2022	Active	10080436
10080447	MONTE-CARLO HELICOPTERE SERVICE(MHS)	REV. 1		AS 350 B3	Installation of transponder Garmin GTX345R with ADS-B In enabledRev. 1: Moving of the alert acknowledgement buttons.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation Manual, IM6321, rev C, dated 02/12/2022Instructions for Continued Airworthiness, ICA6321, rev C, dated29/11/2022Rotorcraft Flight Manual Supplement, RFMS6321, rev C, dated 28/11/2022Certification Program MHS6321, rev C, dated 28/11/2022or later revisions of the above listed document(s)u...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/01/2023	Active	10080447

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080448	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04330AT-D	GULFSTREAM G150	Installation of a Future Air Navigation System (FANS) 1/A+ with datalinkrecording system	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): FAA SC No. 25-661-SC, “Non-rechargeable LithiumBattery Installations”.The requirements for environmental protection and the associate...	Index List CEC14068001 Revision “-“, dated October 14, 2019Flight Manual Supplement CEC1406M001 Revision “-“, dated October 14,2019Instructions for Continued Airworthiness CEC1406A001 Revision “-“, datedJune 14, 2019Or later revisions of the above listed document(s) approved/ accepted onbehalf of EAS...	The following STCs are required as part of this STC:STC ST03774AT-D: Installation of Rockwell Collins Flight ManagementSystem (FMS) Upgrade providing Wide Area Augmentation System (WAAS) withLocalizer Precision with Vertical Guidance (LPV) capabilitiesSTC ST10312SC-D: Installation of a VHF COMM 3 An...	14/11/2022	Active	10080448
10080451	OGMA, INDUSTRIA AERONAUTICA DEPORTUGAL, S.A.	REV. 1		EMB-135BJ	EMB-145 upgrade with the Automatic Dependent Surveillance-Broadcast(ADS-B) OUT capability.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-ACNS: D.ELS.001;D.ELS.010; D.ELS.015; D.ELS.020; D.ELS.025; D.ELS.030; D.ELS.040;D.ELS.045; D.ELS.050; D.E...	AFM supplement ref: 18P12MS00003 initial Issue dated 24th October 2022ICA supplement ref: 18P12MS00001 / 18P12MS00004 Initial Issue dated 24thOctober 2022FCD supplement: 18P12MS00002 Initial Issue dated 05th August 2022MDL: §4 of Change Dossier Ref:18 P12CD 00001Initial Issue dated 24thOctober 2022o...	Aeroplanes modified by this STC must be operated in accordance with AFMsupplement ref: 18P12MS00003, and maintained in accordance with ICAsupplement ref: 18P12MS00001 / 18P12MS00004Pre-requisite: EASA STC No. 10046826 Rev. 1 and minor change 12P13-C02related to the DUAL FMS installation and DME MODEb...	26/10/2022	Active	10080451
10080452	AVMAX AVIATION SERVICES Inc.			DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Universal Avionics EFI-890R MFD Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Definition of the Type Design Change: Avmax Master Data List CE324-902,Issue A dated June 06, 2017Installation of the Universal Avionics EFI-890R MFD is to be done inaccordance with Avmax Engineering Order CE324-403, issue B dated March26,2017Maintenance of the Universal Avionics EFI-890R MFD is to...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/10/2022	Active	10080452
10080460	AGUSTAWESTLAND PHILADELPHIACORPORATION		FAA STC SR04231NY	AW119MKII	Installation of the Utility Installations, ID No. AWPC-ENG-17-037-G5"Exterior Cabin Boarding Lights" and G24.6 "Auxiliary Provisions /Relocations: Circuit Breaker Terminal Block Rail".	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	AWPC-ENG-17-033 Rev –, AW119 MKII Certification Plan for Law Enforcement/ Utility Helicopters;AWPC-ENG-20-052 Rev A, AW119MKII Certification Plan for Amendment 1 toAWPC STC SR04231NY;AWPC Installation Master Data List Report No. AWPC-ENG-17-037 Rev E,dated 16 April 2021;AWPC-ENG-17-040 Rev B, dated...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is applicable for AW119MKII helicopters with s...	26/10/2022	Active	10080460
10080470	AVIATION TRADERS LIMITEDEUROPE S.A.S.	REV. 1		A300 F4-622 R A300 C4-620, A300 F4-605 R A300 C4-605 R VARIANT F A300 C4-203, A300 F4-203 A300 B4-622, A300 B4-622 R A300 B4-605 R, A300 B4-620 A300 B4-601, A300 B4-603 A300 B4-2C, A300 B4-102 A300 B4-203, A300 B4-220 A300 B4-203 A300 B4-103, A300 B4-120	A300 / A300-600 - Installation of ADS-B Out FunctionalityThis change aims at installing an ADS-B Out capability on Airbus A300models.REV. 1 aims at extending the applicability to all A300-600 Models	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:For A300 models:CS 25.571 at Initial Issue, CS25.1529 at Initial Issue, CS-ACNS SubpartD at Issue 2For A300-60...	For A300 models:- Master Document List MDL-13685-00001 Issue 4 dated 14/10/2022- Aircraft Flight Manual Supplement - 13685-AFM-00001 Issue 2 dated24/08/2021 as enclosed in Supplement Approval Note 13685-SAN-00001 Issue2- OSD-MMEL Supplement - MMELS-13685-00001 Issue 1 dated 06/04/2020 asenclosed in-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/12/2024	Active	10080470

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080482	NOVA SYSTEMS & ENGINEERING LIMITED			737-800	GVH-12528-01-MOD-01 - 189Y PAX LOPAThis modification introduces a cabin layout using 63 economy classtriple seats generating a 189 passengers seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: JAR 25.562 (c) (5) and(c)(6) at JAR 25 Change 13The requirements for environmental protection and the associat...	The change is defined with Issue 1 of GVH Aerospace Master Data Listdocument GVH-12528-01-MDL-01The aircraft shall be maintained in accordance with Issue 1 of GVHAerospace Instructions for Continued Airworthiness documentGVH-12528-01-ICA-01or later revisions of the above listed document (s) approved/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/10/2022	Active	10080482
10080486	MICRO AERODYNAMICS, INC.		FAA STC SA5789NM	E55, E55A D55, D55A 95-C55, 95-C55A 95-B55, 95-B55A, 95-B55B 95-55, 95-A55	Installation of vortex generators on the wing and vertical tail andstrakes on the engine nacelles	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA5789NM.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	1. Drawing List MA2005, Revision B;2. Installation Instructions MA2004, Revision C, both dated November 30,1992;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/11/2022	Active	10080486
10080502	NOVA SYSTEMS & ENGINEERING LIMITED			A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216	Airbus A320 180 Pax LOPA InstallationNew passenger seats (Recaro 3530A Seats) are installed to accommodate a180 passengers seat layout in a single-class configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25 Change 13:25.562 (a) (b) (c) 25.812 (e); 25.853 (b) (c) CS26 issue 03 paragraphs: 26.50 (b); 26.60 (a...	ICA supplement: GVH-13104-02-ICA-01 Issue 01 dated 05 Sept 2022MDL: GVH-13104-02-MDL-01 Issue 01 dated 18 Oct 2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft must be maintained in accordance with ICA supplementreferenced GVH-13104-02-ICA-01 Issue 01.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no ad...	03/11/2022	Active	10080502
10080508	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS			737-900ER 737-900 737-8, 737-800 737-800 737-8 737-700	KA-BAND SATCOM structural installation ON B737The modification consists in the installation of the aircraft structuralreinforcement for receiving the installation of base plateantenna/ Antenna/Skrit/Radome on the top of the aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): B-101“Vibration/Buffeting compliancecriteria for large antenna installation”.- The following paragraph(s) at a later amendmen...	Master Drawing list: 01577-EAS-A-MDL Rev.C dated 14 October2022ICA supplement: 01577-EAS-A-ICA-01 Rev.A dated 22 July 2022or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aircrafts modified by this STC must be maintained in accordance with ICAsupplement referenced 01577-EAS-A-ICA-01.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introdu...	03/11/2022	Active	10080508
10080546	PMV ENGINEERING			737-8	CAB-04760 - 189 Y/C seats installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List CAB-04760-MDL Rev 00Instructions for continued airworthiness CAB-04760-ICA Rev 00or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/11/2022	Active	10080546
10080554	M&D FLUGZEUGBAU GmbH & Co. KG			LS 4, LS 4- A, LS 4-B	LS 4 Jet engine installationretrofitting of the pure gliderLS-Sailplanes LS 4 to a self-sustainingpowered sailplane	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 22 Amndt 2, SeeCertification Programm.The requirements for environmental protection and the associatedc...	- LS 4 Jet Sustainer Flight Manual Supplement, Issue: 02, Dated10.07.2022- LS 4 Jet Sustainer Maintenance Manual, Issue: 02, Dated 31.08.2022- Master Document List, Rev. 01, Dated 22.08.2022Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	08/11/2022	Active	10080554

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080555	DOA21 LIMITED			A320-251N	Introduction of a VIP Cabin Interior	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): F-115 “Oxygenequipment qualification above40.000ft” Issue 2.The requirements for environmental protection and the associatedcertified...	Certification Programme SYM1-0000RC000 rev AAFM Supplement SYM1-0000RM500 rev AMMEL Supplement SYM1-0000RM19 initial issueOSD CCD Aircraft difference table SYM1-0000RC004 rev Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplane cabin configurations changed per this STC are considered to bea “variant” to the A320-200 baseline configuration. Cabin crew operatingaeroplane cabin configurations changed per this STC must completeaircraft difference training in accordance with ORO.CC.130, which mustinclude the approvedP...	08/11/2022	Active	10080555
10080564	AVIONITEC Ltd.			340	Installation Sky 497 TAS System including TAS Antenna, Exchange WX Radarby a Garmin GWX 75, Exchange of the L-3 Stormscope System WX-1000 by anExtant WX-500 System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with Master Document List No 13161-17 dated16/8/2022, maintained in accordance with Instructionfor ContinuedAirworthiness 13161-015 dated 16/8/2022 and Static Report IFB _HB-LSR60083152 dated 25/8/2022; operated inaccordance with AIRCRAFT FLIGHTMANUAL SUPPLEMENTNo. 13161-01...	Limited to aircraft S/N 340-0180.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffectupon the airworthiness of the product.	09/11/2022	Active	10080564
10080565	GARMIN INTERNATIONAL, Inc.		FAA ST01918WI	560XL	Installation of Garmin G5000 Integrated Flight Deck	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s):25-736-SC (Airplane Electronic System Security Protection fromUnauthorizedInternal Access) 25-737-SC (Airplane Electronic System Securi...	Master Drawing List (MDL), Garmin International, Inc. document N.005-01202-00, Revision 20<(>,<)>dated 15th September 2022.Airplane Flight Manual Supplement, Garmin International,Inc. documentNo. 190-02313-03, Revision 8<(>,<)>dated 15th September 2022EASA OSD-FC Supplement N. 005-01202-U4, Revisio...	Eligible aircraft are serial numbers 560-5001 through 560-5500 (Excel)and serial numbers 560-5501 through 560-6000 (XLS).FS510 EASA-Certified Configuration’ must be loaded to the G5000 avionicsIAW PICP 190-02313-00 Section 2.8.13.	30/11/2022	Active	10080565
10080607	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA SA3597NM	60, A60, B60	Cockpit Sun Visor installation	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA3597NM.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	MDL 9050-0116-001, Rev. U, Number RBB-00DL, dated 21 September 2022ICA Manual 9100-1160-001 and -002, Number RBB-300-2 Rev. A dated 21September 2022or later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ U...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/11/2022	Active	10080607
10080616	AERO SEKUR S.P.A	REV. 1		AW169, AW189 AB139, AW139	The scope of this change is to introduce a new pyrotechnical actuatorassembly kit P/N 318783A as a replacement for the SMA actuator installedon the AB139/ AW139, AW169 and AW189 helicopters modelsRev. 1: Correction of EASA Certification Basis	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: CS 29amdt 8The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to t...	Master Drawing List Document MDW 318783A Rev.BMaster Document List MDL 318783A Rev.FInstruction for Continued Airworthiness ICA01 318783A Initial IssueAssembly Instructions AI01 318783A Initial IssueDocument EO01 318783A “INSTALLATION OF ACTUATOR ASSEMBLY REPLACEMENT KITFOR (AW169) FLOATS INFLATIOND...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/08/2024	Active	10080616

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080626	AEROTEC & CONCEPT			SEE EASA APPROVED MODEL LIST	MEDICAL OXYGEN BOTTLE INSTALLATION	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): F-02/60079498 Maximum Oxygen WorkingPressure and Pressure Limiting Performancethe following paragraph(s) at a later amendment: C...	SEE EASA APPROVED MODEL LISTor later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	AEROTEC CONCEPT modification dossier n°AE20156 is a pre-requisite forthis installationInstallation is limited to configurations as per Assessment Drawingsref. 21073C01-0000; 21073C02-0000; 21073C04-0000; 21073C07-0000;21073C08-0000; 21073C09-0000; 21073C10-0000; 21073C11-0000;21073C14-0000. Subseque...	16/11/2022	Active	10080626
10080636	DOA21 LIMITED	REV. 1		A320-251N	Introduction of Cabin VIP InteriorRev. 1: Transfer of STC holder role to DOA21 Ltd.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 Amendment 25:25.788, 25.810 (d)(4), 25.812 (a)(b)(c)(d)(e)(i)(j)(l), 25.854 (a), 25.856 (a), 25.1360 an...	STC Twenty One Ltd Flight Manual Supplement No. S21.FMS-0168 Issue 1dated 04 November 2021STC Twenty One Ltd Maintenance Manual/AWL Supplement No. S21.AMMS-0097Issue 1dated 04 November 2021STC Twenty One Ltd Cabin Crew Data No. S21.CCD-0003 Issue 3 dated 24June 2022STC Twenty One Ltd Master Document...	Aeroplanes modified in accordance with this STC are considered to be a“variant” to the A320 passenger configurations. Cabin crew operatingaeroplanes modified in accordance with this STC must complete aircraftdifference training in accordance with ORO.CC.130, which must includethe approved OSD-CabinP...	24/10/2023	Active	10080636
10080682	SABENA TECHNICS BOD	REV. 1		BD-700-2A12	MISSILE AVOIDANCE SYSTEM MIYSISMECHANICAL AND ELECTRICAL PROVISIONS FOR MISSILE AVOIDANCE SYSTEM MIYSISINSTALLATION ON BOMBARDIER G7500Rev. 1 is an administrative re-issuance to update the associatedtechnical documentation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master data List MDL-S-99-4344 issue C- AFM Supplement AFMS-S0013-99-003 issue D-MMELS-S0013-99-026 issue B- A/C in configuration 1 (DL-S-99-4344-01): ICA-S0013-99-002 issue A-A/C in configuration 2 or 3 (DL-S-99-4344-02 or DL-S-99-4344-03):ICA-S0013-99-036 issue Aor later revisions of the above...	Operations with Lasers ON are not approved by EASA. Lasers must bepermanently disabled when operating under EASA rules.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will i...	08/10/2025	Active	10080682
10080707	SKY SERVICE F.B.O. INC.	REV. 1	TCCA SA22-59 ISSUE 1	BD-700-1A10, BD-700-1A11	Plane Simple Ku Band SatcomSatcom Ku Band standalone installation providing high speed Ethernet andWi-Fi.Rev.1 adds theTCCA STC reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Drawing List MDL21018 Revision B-AFM Supplement FMS21018-1 Revision A-Instructions for Continued Airworthiness ICA21018-1 Revision Bor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/11/2022	Active	10080707
10080708	S4A SOLUTIONS FOR AVIATION, S.L			DORNIER 228-200	ADS-B OUT on DORNIER 228	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS23.1, CS23.21,CS23.23, CS23.25, CS23.29, CS23.301, CS23.303, CS23.305, CS, 23.307,CS23.321, CS23.337, CS2...	Modification Description, doc no. 228096-12-17 issue 2 dated Oct. 19th2020AFM Supplement, doc. No. 22806-12-28 issue 2 dated Feb. 18th 2021or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/11/2022	Active	10080708

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080718	ADAC HELISERVICE GMBH			EC135 T3 EC135 P3	Installation of retractable LED search & landing light Luminator LS400M(L/H and R/H) in replacement of pre-installed Collins retractable LEDsearch & landing light, as well as associated Night Vision ImagingSystem (NVIS) approval	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-27 Amendment 9 forthe following paragraphs: 27.29; 27.251; 27.301; 27.305; 27.307(a);27.321; 27.603; 27.60...	- Rotorcraft Flight Manual Supplement EC135-11951-025-MFS Revision 1- Master Document List EC135-11951-001-LMD Revision1- Maintenance Manual Supplement EC135-11951-023-MMS Revision 1- Compliance Summary EC135-11951-044-RCS Revision 0or later revisions of the above listed document(s) approved/ accept...	Limited to helicopters with Helionix cockpit variant.As prerequisite (pre-modification configuration) the Rotorcraft must beequipped with one or two of the following retractable search and landing(S/L) lights:- Collins LED S/L light P/N 2LA456436-80 (i.a.w. Airbus IPC 33-43-03-05– R/H side)- Collins...	24/11/2022	Active	10080718
10080731	STERLING CORPORATIOND/ B/A STERLING HELICOPTER	REV. 1	FAA SR04711NY	429	Installation of Luminator Aerospace LS400GR / LS400NR-GR LED steerablesearchlight assembly replacement.Rev. 1 corrects the company name.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-27 specifications at Amendment 1:27.251, 27.301, 27.303, 27.305(a)(b)(1), 27.307 (a), 27.337(a), 27.341,27...	Master Drawing List, Document No. 910106, Rev. A, dated January 10,2022;Instructions for Continued Airworthiness, Document No. 910107, Rev. C,dated February 25, 2022;Rotorcraft Flight Manual Supplement, Document No. 910146, Rev. IR, FAAapproved dated March 10, 2022or later revisions of the above lis...	The Bell 429 helicopter must be OEM equipped with a PAR 46 searchlightat the approximate OEM location on the belly of the rotorcraft.The Bell 429 helicopter must have the OEM dustcover installed.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this...	28/11/2022	Active	10080731
10080735	POLYTECH AERO SUPPORT INC.		TCCA Q-LSA14-010/D	737-800	Cabin Layout Reconfiguration changeReplacing seats: - Configuration 1: B/E Aerospace Spectrum model 1005679 seatsreplaced with ZIM EC15059E seats<(>,<)> - Configuration 2:Webber Model 5500 seats replaced with ZIMEC15059E seats.Thenumber of passengers is not affected and remains with 189.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.562 at Change14.The requirements for environmental protection and the associatedcertified noise and/...	Installation shall be performed in accordance with PolytechAero SupportInc. Modification Summary MS-14-002, Revision 10Maintenance shall be performed in accordance with Polytech Aero SupportInc. Instructions for Continued Airworthiness ICA-14-002, Revision 9or later revisions of the above listed do...	This STC is limited to the following MSN:- Configuration 1:29368, 29369, 30696, 30701- Configuration 2: 30631.Prior toinstallation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce...	25/11/2022	Active	10080735
10080737	RECAERO			A330-202	Recaero project RCP024: Cabin adaptationChange of the seating capacity, from 314 seats to 288 seats, with 19 B/CSeats and 269 Y/C Seats, installation of several equipment's.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.853 & CS 25.854at amendment 0, CS 25.856at amendment 6 and CS 25.571 at amendment 19.The requirement...	- Master Data List RCP024MDL001 Issue 1 signed on 24.Nov.2022- Compliance Summary RCP024COS001 Issue 1 signed on 24.Nov.2022or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/11/2022	Active	10080737
10080739	SIRIUM AEROTECH S.L.			S550 560 550 500	Cessna Citation ADS-B UpgradeActivation of ADS-B DO-260B capabilities with existing UNS-1Lw FMS asGNSS source.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	MASTER DATA LIST SA19-24S-MDL Rev 01,AFM SUPPLEMENT SA19-24S-AFMS Rev 01MMEL SUPPLEMENT SA19-24S-MMELS Rev 00	Aircraft must be equipped with Transponder MST-70B (P/N: 9007000-55001or 9007000-57001) and FMS UNS-1Lw (P/N: 3116-32-1116) with SCN1001.1/1101.1 or higher or SCN 1000.0/1100.0 orhigher with ADS-B Failannunciator provisions installedPriorto installation of this change/repair it must be determinedt...	25/11/2022	Active	10080739

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080749	UMLAUT ENGINEERING GMBH			EMB-505	Reconfiguration of executive cabin into a cabin dedicated for EmergencyMedical Services (EMS),	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with Cabin Re-Configuration Manual Ref:UM-ABE01-CCM-0001 Rev A; maintained in accordance with Instructions forContinued Airworthiness Ref: UM-ABE01-ICA-0001 Rev A; operated inaccordance with Flight Manual SupplementRef: UM-ABE01-FMS-0001 Rev Aand Cabin Crew Information Manua...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/11/2022	Active	10080749
10080751	LIFEPORT, LLC		FAA STC SR01082LA	212, 412, 412EP	Installation of a medical berth/litter system	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List (MDL) EGR-595-02, Revision AB, dated April 24, 2014<(>,<) >Rotorcraft Flight Manual Supplement (RFMS) Number EGR-655-11, RevisionA, dated October 10, 2007<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/11/2022	Active	10080751
10080753	LIFEPORT, LLC		FAA STC SR00871LA	212, 412, 412EP	Installation of the Modular Seating System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List for the Modular Seating System Installation,EGR-606-00, Revision E, dated November 5, 1999<(>,<) >For installation, EGR-606-00, Revision S, dated August 8, 2007<(>,<) >Rotorcraft Flight Manual Supplement No. EGR-606-11, Revision IR, datedOctober 10, 2007< (>,<)>or later revisions of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/11/2022	Active	10080753
10080765	SABENA TECHNICS BGC			A321-271NX	Cabin Reconfiguration to 239 PAX	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS25 at Amendment 15 for:§25.1, §25.301, §25.303, §25.305, §25.307, §25.321, §25.337, §25.341,§25.471, §25.5...	Certification Plan - 41057-01-A-CP-R02Master Data List (MDL) [A01] ref. 41057-01-A-MDLInstructions for Continued Airworthiness (ICA) C41057-01-A-ICA-R00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	As a concurrent requirement of this change, the installation of thephoto-luminescent FPM is needed. Some drawings may be defined to easethe installation which shall be done according to Engineering Bulletinissued by Lufthansa Technik ref A320-EB33-0384 Rev5 and covered throughSTC ref 10014013 Rev 02...	13/12/2022	Active	10080765
10080787	AEROSERVIS, S.R.O.			VIPER SD-4 RTC VIPER SD-4 NIGHT-VFR	Installation of FLASH-R propeller on Viper SD-4 RTC and Viper SD-4 NightVFR exhaust modification.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amd 6, Chapter10 of ICAO Annex 16, Volume I.The requirements for environmental protection are unchang...	Installed in accordance with document number: Installation of DUCHélices FLASH-R propeller, SB_SD4-01-2022, Revision Initial, Dated 28thApril 2022Operated in accordance with document number: Aircraft Flight Manual, TOM-TC-01-(FSH_R)-AFM, Revision Initial, Dated21st March 2022Maintained in accordance...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/12/2022	Active	10080787

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080797	DRABPOL SP. JAWNA P. DRABCZYNSKII WSPOLNIK			GA8-TC 320	Installation of vaccine deployment system	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed and maintained in accordance with the MaintenanceManualSupplement DP-019-06 revision 0;Operated in accordance with the Flight Manual Supplement DP-019-05revision 0;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/12/2022	Active	10080797
10080803	UMLAUT ENGINEERING GMBH	REV. 1		A321-271N/-271NX/-272N A321-253N/-251NX/-252NX/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-171N A319-131/-132/-133/-151N/-153N A319-111/-112/-113/-114/-115	CCS+ Center Ceiling Stowage IntegrationInstallation of an additional overhead stowage in the center aisle ofthe A320 familyRev. 1 corrects the model list.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-25 Amdt. 27 andCS-26 Amdt. 3 for25.29(a)(b), 25.301(a)(b)(c), 25.303, 25.305(a)(b), 25.307(a),25.561(a)(b)...	- Master Document List (UM-AAQ01-MDL-0001) with Issue B dated 06.12.2022- Instructions for Continued Airworthiness (UM-AAQ01-ICA-0001) withIssue A dated 01.12.2022Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/12/2022	Active	10080803
10080809	MECAER AVIATION GROUP S.p.A.	REV. 2		H160-B	VIP INTERIORRev. 1 introduces new cabin layouts with modular 4-seater benches,including configutations 6A6H0000F104011005, 6A6H0000F104023007,6A6H0000F104021002 and 6A6H0000F104019006.Rev. 2 introduces new cabin layouts with forward-facingarmchairs,including configurations 6A6H0000F103001003 and 6A...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification programme No 6A6H0000N177 'H160 VIP - STC MAJOR Change -4+2 Conf Introduct - Certification Programme' Revision 4 of 18 June2024, referring to description 6A6H0000N174Compliance checklist No NDC 6A6HX-0016 'H160-B - VIP STC - MCB - layout4+2 - declaration of compliance' issue A of 21 Ju...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/06/2024	Active	10080809
10080837	ALAMO ENGINEERING GmbH	REV. 1		CL-600-2B16 (604 VARIANT)	Bombardier CL-600-2B16 as PED TolerantThis design change covers the approval for aircraft PED tolerance to useTransmitting Portable Electronic Devices (T-PEDs) during all phases offlight expect low visibility approach operation (ILS CAT II) on aBombardier CL-600-2B16 (604 Variant). The installationW...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): SC 94-2 (HIRF) as mentioned in the TCDS.- The following paragraph(s) at a later amendment: CS-25 Amdt. 27 for1309,1319, 1353, 1360, 1431, 1529.Thec...	Flight Manual Supplement, FMS22A14AE-02, Rev. DInstructionsfor Continued Airworthiness, ICA22A14AE-02, Rev. DMaster Document List, MDL22A14AE-01, Rev. COr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This approval is only applicable to S/N 5301-5699 and S/N 5701-5990.Concerning T-PEDs it covers the 2.4 GHz frequency band, only.AFMS Limitation: During low visibility approaches (ILS CAT II) the WLANSystem has to be deactivated and all PEDs have to be set to"Flight-Mode" or turned off.ImplementingW...	07/10/2024	Active	10080837
10080840	AEROTEC & CONCEPT			MYSTÈRE FALCON 900 (MF900) MYSTÈRE FALCON 50 (MF50) FALCON 900EX (F900EX)	F900 EVASAN Stretchers InstallationInstallation of four (4)Universal Convertible Stretchers, four (4)Oxygen Racks (without oxygen bottles) and relative cabin adaptation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI D-01 Medical Evacuation Configuration.The requirements for environmental protection and the associatedcertified noise and/ or emis...	- Master Data List AE21044MDL Rev. 0- AFM Supplement AE21044AFMS Rev. 4- ICA AE21044ICA Rev. 2or later revisions of theabove listed document(s) approved/ acceptedunder the EASA system.	Oxygen Rack installation covered by this STC does not include theinstallation of Oxygen Cylinders. No Oxygen bottle installation isincluded in this STC.Fare-Paying passengers are not allowed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this chan...	07/12/2022	Active	10080840

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080845	LUFTHANSA TECHNIK AG	REV. 2		777F 777-300ER 777-200	Riblets film on fuselageApplication of self-adhesive film on the fuselage. A microstructurepattern is applied to the film in order to influence the boundary layerand reduce drag.Revision 1: Removal of certain limitations (FWD CG) and update of ICARevision 2: Extended applicability to 777-200 model	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Supplemental Type Definition Document STDD11-21/01M Issue 04 rev 00-Airplane Flight Manual Supplement – A-00-22/26-AFMIssue 12 rev 00-Instructions for Continued Airworthiness A-00-22/26-ICA Issue 15 rev 00-Flight Crew Data Supplement A-00-22/26-FCD Issue 04 rev 00or later revisions of the above li...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2024	Active	10080845
10080855	ELBE FLUGZEUGWERK E GmbH			A300 B4-622, A300 B4-622 R A300 B4-605 R, A300 B4-620 A300 B4-601, A300 B4-603	Exchange of Emergency Locator Transmitter (ELT) on A300B4-600 P2FThis modification allows the exchange of the existing fixed/portable ELTby another fixed/portable ELT. The proposed installation substantiatesthat the requested ELT and the containing non-rechargeable Lithiumbatteries ensures functiona...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI_F-0301-002_Non rechargeable Lithiumbatteries installations -SC.The requirements for environmental protection and the associatedcer...	- Certification Plan ref. EFW-TIP-0146-001 Rev. C-Engineering Order ref. EFW-EO-0146-001 Rev. A-Justification Report for ELT Installation Ref. EFW-E-ED-00897 Rev. Aor later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/12/2022	Active	10080855
10080862	AEROTEC & CONCEPT			1900D	Installation of TCAS II system and replacement of mode-S transponder	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List, document AE22010MDL Issue 0, dated 7 December 2022;Aircraft Flight Manual Supplement, document AE22010AFMS Issue 0, dated 7December 2022;Instructions for Continued Airworthiness, document AE22010ICA Issue 0,dated 24 August 2022;or later revisions of the above listed document (s) app...	The installed TCAS II system (Version 7.0) must be obligatory upgradedto the TCAS II Version 7.1 functionality through the Aerotec Concept STC10055494.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	12/12/2022	Active	10080862
10080863	AIR TEAM SERVICE, S.R.O.			208B 208	Installation of research equipment for atmospheric analysisin theaircraft cabin. The equipment consists of an VOC analyzer IoniconPTR-TOF 6000X2 with CHARON extension module, vacuum generation unitACP15 with sound enclosure kit SEK15, DC 28V to AC 230V converter, andmounting racks.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation Instructions, document ATS-006-INS, Rev 0, dated 15.11.2022Aircraft Flight Manual Supplement, document ATS-006-AFMS, Rev 0, dated15.11.2022Instructions for ContinuingAirworthiness, document ATS-006-ICA, Rev 0,dated 1.09.2022or later revisions of the above listed document(s) approved/ac...	Applicable only to Cessna 208B S/N 208B2435 with installed STCEASA.A.S.03334 Installation of Camera Kit.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adv...	12/12/2022	Active	10080863
10080864	GDC ENGINEERING GmbH	REV. 1		A321-251N	8BC/200EY Cabin ReconfigurationRev 1: Aircraft model applicability corrected.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Certification Document List ref. CCN-A321A-MCDL Issue 01, issuedDecember 07th, 2022Description Report & LOI Issue B ref. A321A-1DE-250000, issued November14th, 2022Instructions for Continued Airworthiness Supplement: A321A-ICA-BAV Issue01, issued November 15th, 2022Cabin Crew Operating Manual...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/12/2022	Active	10080864

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080865	GVH AEROSPACE (IRELAND) LIMITED			A340-643 A340-642	A340-600 Main Cabin Cargo ConversionThis design change is to permanently convert the current passenger cabinto a Class F cargo compartment. The pre-mod configuration has a standardpassenger cabin above the floor, and conventional cargo compartmentsbelow the floor. The post-mod configuration will hav...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): SC H-01 Enhanced Airworthiness Programme forAeroplane Systems - ICA on EWISthe following paragraph(s) at a later amendment:CS 25 at Amen...	Certification Program: GVH-12430-01-CP-01 ,,Flight Manual Supplement: GVH-12430-01-FMS-01Master Data List: GVH-12430-01-MDL-01Master Minimum Equipment List: GVH-12430-01-MMEL-01Instructions for Continued Airworthiness: GVH-12430-01-ICA-01or later revisions of the above listed document(s) approved/ac...	None.	14/12/2022	Active	10080865
10080867	BOGGI AERONAUTICS S.R.L.			429	Mission UHF, HF Radios and antennas Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document list 429P00100-MDL-00 Issue 0Flight Manual Supplement 429P00100-FMS-11 Issue 1Instruction for continuedAirworthiness 429P00100-ICA-10 Issue 0or later revisions ofthe above listed document(s) approved/acceptedunder the EASA system.	Boggi Minor change 429P002-00 and EASA Minor Change approval 10073888are pre-requisites for this installation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introducee...	13/12/2022	Active	10080867
10080895	PMV ENGINEERING			A340-542 A340-541	A340-500 cabin reconfiguration for GLOBAL	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List CAB-03110-MDL rev 02Instructions for Continued Airworthiness CAB-03110-ICA rev 01or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/12/2022	Active	10080895
10080900	THALES AVIONICS Inc.		FAA STC ST02798LA	777F 777-300. 777-300ER 777-200, 777-200LR	Installation of the upgraded Thales Radio Altimeter Transceiver Units,ERT5	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 amdt. 5: 25.611 (a)CS 25 amdt. 17: 25.1317(a)(1) (2)The requirements for environmental protection and the associatedcer...	Thales Avionics, Inc. Index List Drawing No. 259119, Revision A, datedNovember 08, 2022< (>,<)>or later revisions of theabove listed document (s) approved/accepted onbehalf of EASAin accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.The applicable Instructions for...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/12/2022	Active	10080900
10080902	ALAMO ENGINEERING GmbH			DORNIER 328-100	Landing Gear Warning InhibitCertification of the installation of a guarded audio inhibit switch onthe cockpit instrument panel that allows the pilot to mute the low-levelaural warnings provided by the landing gear system and audio calloutsofthe previously installed EGPWS systems. The original TAWSi...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- Special Condition (s): CRI H-1 - ICA for EWIS as mentioned in the TCDS.- The following paragraph(s) at a later amendment: CS-25, Amdt. 27 for CS 25.729 (e).- CS-ACNS, Is...	Master Document List, MDL22A21AE-01, Rev. CAircraft Flight Manual Supplement, FMS22A21AE-01, Rev. AInstructions for Continued Airworthiness, ICA22A21AE-01, Rev. AOr later revisions of the above listed document(s) approved/acceptedunder theEASA system.	The following related design changes are prerequisite for thisinstallation:• Aerodata EASA STC No. 10013993: Installation of Maritime SurveillanceSystem on Dornier 328-100 including SAR Radar, FLIR, and optional IR/UVScannerLimitations/ Conditions:• As per AFM Supplement, FMS22A21AE-01, Rev. A;Priort...	15/12/2022	Active	10080902

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080916	AEROLITE AG	REV. 3		MBB-BK117 D-3M MBB-BK117 D-2, MBB-BK117 D-3	Introduction of the Emergency Medical Service (EMS) equipment PartNumber (P/N) 145-0332030-501 (also referred as “CabinLayoutConfiguration A”) installed in the helicopter cabin (Aerolite referenceP13165).Revision 1Introduction of a changeto Part Number (P/N) 145-0332030-501 CabinLayout Configurati...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program CPR-22-038 Rev. B dated 15/12/2022<(>,<)>Flight Manual Supplement FMS-145-0332030-501 Rev. 0 dated 22/11/2022<(>,<)>Operations Manual, including Instructionsfor Continued Airworthiness,OPM-145-03 32030-501 Rev. 0dated22/11/2022<(>,<)>Master Document List MDL-22-004 Rev. N/C da...	The following are pre-requisite installations for the embodiment of thisdesign change:- Airbus Helicopters Deutschland (AHD) floor (*) and FWD RH and LHaft-facing AHD seats (**) for the floor protection installation P/N145-0047223-505.- Floor protection installation P/N 145-0047223-505 for the platf...	25/06/2025	Active	10080916
10080919	DOA AESGLOBAL LIMITED			737-800	INTRODUCTION OF REPLACEMENT G4 GALLEYTHIS CHANGE INTRODUCESA REPLACEMENT GALLEY IN THE G4 POSITION ON THEAIRCRAFT	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment:CS 25 Amdt 4: CS25.869, 25.899, 25.1301, 25.1309, 25.1351, 25.1353,25.1357, 25.1431CS-25 Amdt 27 : CS 25.1,2...	Master Data List: AES-737-7057MDL Issue 02ICA supplement: AES-TR-3456 Issue 01AMM, IPC and WDM Supplements: AES-TP-0421Issue 01or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft must be maintained in accordance with ICA supplementreferenced AES-TR-0421 Issue 01.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeff...	16/12/2022	Active	10080919
10080937	THE NORDAM GROUP LLC	REV. 1	FAA STC ST09928AC	737-900ER 737-900 737-9 737-800 737-8 737-700	EFVS Nose Radome AssemblyInstallation of an Enhanced FlightVision System (EFVS) Nose RadomeAssembly supporting installation of a Rockwell Collins (CollinsAerospace) EVS-3600 sensor (infrared camera) Revision 1: Added reference to FAA STC	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI C-101 ‘Vibration and Buffeting'The requirements for environmental protection and the associatedcertified noise and/ or emiss...	Master Data List ND002-MDL01 rev. B dated 08 April 2022or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	EASA STC 10079180 (validation of FAA STC ST01978WI) must beembodiedprior or concurrentlyPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	13/01/2023	Active	10080937
10080942	DRF STIFTUNG LUFTRETTUNGG EMEINNUETZIGE AG			MBB-BK117 D-3 MBB-BK117 C-2, MBB-BK117 D-2	Powered Stretcher System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master document List ref-MD-117-25-50-00083 - Master Document List - N °1508 issue 3Declaration of compliance Ref-DC-117-25-50-00023, issue 0Installation Manual - IM-117-25-50-00023issue 1Instructions for continued Airworthiness N° CA-117-25-50-00084 issue 1Flight Manual supplement FMS 10-DRF-062 iss...	For installation of the Power stretcher system, the cabin floor must becleared. A separate approval is required for anyadditional installationin the cabin..Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	21/12/2022	Active	10080942
10080957	SABENA TECHNICS BGC	REV. 1		AS 332 L, AS 332 L1 AS 332 C, AS 332 C1	Lifeseeker InstallationRev. 1 corrects the Technical Documentation List.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: FAR 29 Amdt 20 for29.1529.The requirements forenvironmental protection and the associatedcertified noise a...	Certification Program 214301ACP, Revision 04, dated 24/11/2022System Technical Specification 2143-01-A-STS, Revision 01, dated19/07/2022Master Data List 2143-01-A-MDL, Revision 01, dated 16/12/2022Rotorcraft Flight Manual Supplement 2143-01-A-RFMS, Revision 02, dated24/11/2022Instructions for Contin...	- STC is limited to the installation variant 2 as defined in document2143-01-A-STS, Revision 01.- The modification MOD 2143-02 is a pre-requisite for the embodiment ofthis design change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/re...	21/12/2022	Active	10080957

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080959	SAFRAN ENGINEERING SERVICES GmbH			EC 225 LP	Night Vision Imaging System (NVIS) capability on EC 225 LP (Ref.MOD-H22001)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-29 Initial Issue.The requirements for environmental protection and the associatedcertified noise and/ or...	Certification Program MOD-H22001-CP, Issue 4, dated 22/08/2022System Description Document MOD-H22001-SDD, Issue 4, dated 20/09/2022Rotorcraft Flight Manual Supplement MOD-H22001-RFMS, Revision 1, dated19/12/2022Instructions for Continued Airworthiness MOD-H22001-ICA Issue 1, dated14/12/2022Master Do...	This design change is limited to the EC 225 LP Serial Numbers (S/Ns)2827, 2851 with configuration described in the Project Descriptiondocument ref. MOD-H22001-SDD Issue 4, dated 20/09/2022 and ICA documentref. MOD-H22001-ICA Issue 1, dated14/12/2022.The following modification is a pre-requisite for...	20/12/2022	Active	10080959
10080972	AEROMECH Inc.		FAA ST02723SE	737-800	RVSM Group Approval for Boeing 737-800 BDSF Aircraft	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: EASA CS-ACNS SubpartE, Section 2 (RVSM) Issue 3.The requirements for environmental protection and the assoc...	MASTER DATA LIST AM0375-DL02-00, 21 October 2022AFM SUPPLEMENT AM0375-FM01-00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The validity of this RVSM Approval is only applicable for Boeing 737-800aircraft previously converted to Special Freighter (SF) according toEASA STC 10079576, and the altitude alert system must be configured toalert deviations from the selected altitude by a value of ±60 m (±200ft) or greater.	21/12/2022	Active	10080972
10080977	AMAC AEROSPACE SWITZERLAND AG			A321-271NX/-272NX A321-271N/-272N A321-251NX/-25212NX/-253NX A321-251N/-2512N/-253N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Activation of an Air Cleaning System (ionization)This change includes the activation of an installed air cleaning systemworking on the ionization principle.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: The followingparagraphs of CS 25 AMDT 27 are applicable to this change: 25.601;25.831; 25.832; 25.853; 25.858...	The change is defined with Revision A of Master Data List documentMDL-ALLAC01-2100.The aircraft shall be maintained in accordance with Revision A ofInstructions for Continued Airworthiness document ICA-ALLAC01-2100Or later revisions of theabove listed document(s) approved/ acceptedunder the EASA sys...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/01/2023	Active	10080977
10080981	AMTECH AERONAUTICAL LIMITED		TCCA SA17-124 ISSUE 1	SEE EASA APPROVED MODEL LIST	Installation of Pratt and Whitney Engine Services, Inc. Flight DataAcquisition Storage and Transmission System (FAST).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List MDL466301, Revision 3, 30 October 2019Approved AFMS GN4-T-250-7 Revision B, 18-05-22or later revisionsof the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/01/2023	Active	10080981
10080984	DELTA ENGINEERING CORPORATION		FAA ST03439NY	737-800	Installation of a Cabin Interior	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements:- The following paragraph(s) at a later amendment: CS25 amdt. 4: 25.820,25.853, 25.869, 25.981.The requirementsfor environmental protection and the associatedcertified noi...	Delta Engineering Master Data List 0106-10378-2429, Revision T, dated 8November 2022< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA inaccordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.The Instructions for Continued Air...	Limitations as per Delta Engineering Master Data List.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product	06/02/2023	Active	10080984

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10080988	CEA DESIGN GmbH	REV. 1		SEE EASA APPROVED MODEL LIST	Provisions for ISR operationsInstallation of provisions forISR operations is consisting of thefollowing parts:STEP1: Fixed provisions:-Stage A – 15A Aux bus installation-Stage B – 25A Aux bus installation-Stage C – GPS Antenna fuselage mountedSTEP2: Provisions for ISR operations:-Stage A - LH Strut...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	As listed in the related AML documentor later revisions of the above listed document(s) approved/ acceptedunder the EASAsystem.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/02/2023	Active	10080988
10080989	EIRTECH AVIATION SERVICES LIMITED			ATR 72-212 A ATR 72-211, ATR 72-212 ATR 72-201, ATR 72-202 ATR 72-101, ATR 72-102 ATR 42-500 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	ATR Cargo Compartment Doublers InstallThis change installs aluminium doublers as abrasion panels in the FWDand AFT cargo compartment.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.1, 25.29 (b), 25.301 (a) – (b), 25.303, 25.305 (a) – (b), 25.307 (a), 25.561 (b), 25.571 (a), 25.601,2...	The Change is defined with Issue 2 of Eirtech Aviation Services MasterDocument List Document MDL-1636-001Maintenanc e shall be conducted in accordance with Issue 1 of EirtechAviation Services Aircraft Manual Supplement document AMS-1636-001or later revisions of the above listed document(s) approved/a...	Not applicable to ATR 72-212A with MOD 7900 installed.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product....	04/01/2023	Active	10080989
10080990	NORTH WEST HELI-STRUCTURES INCORPOR		FAA STC SR02640SE	412EP 412 212	Installation of a Service Deck	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions DM1518-5, Revision A, dated February 26, 2019<(>,<)>Master Drawing List DM1518-3, Revision A,dated February 26, 2019<(>,<)>Instructions for Continued Airworthiness (ICA) DM1518-7, Revision A,dated February 26, 2019<(>,<)>or later revisions of the above listed document(s) a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/01/2023	Active	10080990
10080995	ROCKWELL COLLINS, Inc.		FAA STC ST02002WI	SEE FAA APPROVED MODEL LIST	Replacement of Rockwell Collins LRA-900 Low Range Radio Altimeters withupgraded LRA-900 units for improved RF immunity to 5G cellular datainterference	The Certification Bases for the original products as amended by thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 amdt 14: 25.301,25.303, 25.305(a)(b)(c), 25.581(a)(b)(1)(2), 25.1301(a), 25.1309(a)(b)(c)(d)(e), 25.1310(a)(1)(2)(3)...	FAA Approved Model List (AML) RCA-0696, Revision (-), dated16 December2022;Instructions for Continued Airworthiness asspecified by FAA ApprovedModel List (AML) RCA-0696, Revision (-);or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Techni...	Prior to installation of this change it must be determined that theinterrelationship between this change and any other previously installedchange and/ or repair will introduce no adverse effect upon theairworthiness of the product.EASA approved installation of LRA-900 Low Range Radio Altimeter ships...	11/01/2023	Active	10080995
10080999	DASSAULT FALCON JET CORPORATION	REV. 2	FAA STC ST03611NY	FALCON 7X	MMEL SUPPLEMENTInstallation of Garmin GI 275 Standby FlightDisplay System (SFDS) inDassault Aviation model Falcon 7X aircraftRevision 1 approves new software on the installation of garmin GI 275Standby Flight Display System on Dassault Falcon 7X model aircraft.Revision 2 approves EASA MMEL SUPPLEME...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	- Dassault Falcon Jet MMEL Supplement DFJ-MMELS-F7X-01-I1 issue 1 dated02-May-2024- Dassault Falcon Jet Corp Master Data List F7XW-D0107-005, Rev B, dated24 March 2025;- Dassault Falcon Jet Corp Instructions for Continued Airworthiness(ICA) F7XW-D0107-155 Rev A<(>,<)>dated 24 March 2025;- Dassault F...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Applicable to Dassault Aviation Falcon 7X aircraft seri...	25/08/2025	Active	10080999

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081009	AVIATION ENGINEERING AS			680A (LATITUDE)	Installation of EpiShuttle incubator for transportation of patients withhighly contagious virus or bacterial infections.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI D-01 Medical Evacuation.The requirements for environmental protectionand the associatedcertified noise and/ or emissions levels o...	Aviation Engineering Master Drawing List No. 2524-05-324, Installationof EpiShuttle in Cessna C680A Latitude, revision 0, dated 09 January2023.To be installed according to Aviation Engineering Service InstructionNo. 2524-05-356, revision 0,dated 13 June 2022.To be operated according to Aviation Engi...	EASA STC Approval 10071611 is a prerequisite for this Approval.This design change is approved by EASA in accordance with Regulation (EU) No 748/2012 and attests compliance with theapplicableairworthiness requirements only. The approval does not cover the medicalsafety and performance, including itso...	09/01/2023	Active	10081009
10081019	DASSAULT FALCON JET CORPORATION	REV. 1	FAA STC ST01972WI	FALCON 2000, FALCON 2000EX	Installation of Aviation Clean Air Ionization SystemRev. 1:Transfer from "Duncan Aviation, Inc." to "Dassault Falcon JetCorporation".	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The applicant has voluntarily complied with the following 14 CFRPart 25regulations, effective Feb 1, 1965,as amended by theamendments stated: 25.613(a)(b)(c)(f) [Amdt. 25-112].The req...	MDL Doc. No. CERTDOC-011633, Rev. A, dated September 10, 2021ICA Doc. No. CERTDOC-0111676 Rev. A, dated September 10, 2021or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This design change may not be implemented on aircraft with ionizationsmoke detector systems.	08/04/2025	Active	10081019
10081020	MED-PAC INC.		FAA STC SR04355CH	505	Installation of Med-Pac 505 EMS-Lite RC505 Medical Unit	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List (MDL), Report No. RC505-MDL, Revision IR, dated 1 June2018<(>,<)>Rotorcraft Flight Manual Supplement (RFMS), Report No. RFMS 505,Revision IR, dated 1 June 2018<(>,<) >Instructions for Continued Airworthiness (ICA), Report No. ICAS 505,Revision IR, dated 1 June 2018<(>,<) >Medical Tran...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/02/2023	Active	10081020
10081026	LUFTHANSA TECHNIK AG			A340-313	Swiss A340 - Installation of PEY ClassInstallation of new Premium Economy Class seats between door 2 and 3 ofAirbus A340-300	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS25.785(h)(2)(j)(k), CS 25.811(c), CS 25.812(e) and CS 25.813(d) amdt 19;CS 25.791 (a)(b) and CS 25.853 (a)...	Supplemental Type Design Document STDD25-19/31M Issue 01/00Instructions for Continued Airworthiness A-00-22/80-ICA Issue 02/00Instructions for Continued Airworthiness A-00-21/17-ICA Issue 01/00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/01/2023	Active	10081026
10081036	MT-PROPELLER ENTWICKLUNG GmbH			T67M260 FIREFLY	Installation of MTV-9-B-C/C180-50( ) Propeller on Slingsby T67M260series.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31.This certificate/ approval involves a change with an impact on the noisedatab...	To be operated in accordance with MT-Propeller AFM-S Document No. E-4094Rev. 0According to MT-Propeller Master Documentation List No. E-4066 Rev. 1To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-3911 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4095 Rev. 0or later...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	11/01/2023	Active	10081036

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081042	SAFRAN CABIN INC.		FAA STC ST00484SE	SEE FAA AML	Installation of interior retrofit kit	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:CS-25 initial issue: 25.307, 25.613, 25.625, 25.791, 25.853, 25.869,25.981, 25.1351The requirements for environmental protection and the associatedcertified noise and/ oru...	Heath Tecna, Inc. Drawing List HPD-DL-55, Revision AU, dated 28 October2002<(>,<)>Heath Tecna, Inc. Instructions for Continued Airworthiness, HTM852,Revision F, dated 29 August 2001<(>,<) >PMA Supplement 302, dated 9 November 2022< (>,<)>Heath Tecna Master Data List (MDL) HPD-DL-00<(>,<)> Rev BH, date...	Limitations as per FAA AML FAA AML No. ST00484SE.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.The ST...	03/04/2023	Active	10081042
10081043	SAFRAN CABIN INC.		FAA STC ST00773SE	SEE FAA AML	Installation of Upper Deck Overhead Stowage Bin Interior Retrofit	The Type and OSD Certification Bases for the original product as amendedby the following additional oralternative airworthiness requirements:the following paragraph(s) at a later amendment:CS 25 initial issue: 25.25, 25.307, 25.613, 25.791, 25.625, 25.981,25.853, 25.869, 25.1351The requirements forc...	Heath Tecna, Inc. Drawing List HPD-DL-71, Revision T, dated9 March 2004< (>,<)>Master Data List (MDL) HPD-DL-71<(>,<)> Revision T, dated 9 March 2004<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures. ..	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	05/05/2023	Active	10081043
10081045	SOCIETE AIR FRANCE S.A.	REV. 1		777-300ER	48J Cabin ReconfigurationNew IFE Zodiac “RAVE Centric” System InstallationREV. 1 adds reference to Change Approval Sheet which includes list ofdefinition and substantiation data.This revision also adds reference to accomplishment Service Bulletin ofthe modification.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change Approval Sheet CAS-B777-19-003 Rev. 0Service Bulletin AFSB-B777-19-003-25-001 Rev. 0Certification Program CP-B777-19-003 Rev 5MMEL Supplement MMELS-B777-19-003-001 Rev. 0Instructions of Continued Airworthiness ICA-B777-19-003 rev 0or later revisions of the above listed document(s) approved/ac...	- Aeroplanes modified per this STC are considered to be a “variant” tothe B777-300ER baseline configuration. Cabin crewoperating aeroplanesmodified per this STC must complete aircraft difference training inaccordance with ORO.CC.130, which must include the approved OSD-CabinCrew Data (CCD).- Boeing...	18/01/2023	Active	10081045
10081048	BOEING IRELAND LIMITED			787-9	355 Passenger Interior ReconfigurationThis modification introduces a cabin layout using 28 premium economyclass seats and 327 tourist class seats generating a 355 passengerseatingconfiguration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision 00 of Boeing Ireland Change/ RepairApproval document BIL-00235-APPThe aircraft shallbe maintained in accordance with Revision 00 ofBoeing Ireland Limited Instructions for Continued Airworthiness documentBIL-00235-ICA01or later revisions of the above listed documen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/01/2023	Active	10081048
10081050	GDC ENGINEERING GmbH			A320-214	CCN-A320G - A320-200 CEO Cabin ReconfigurationThis modification enables the replacement of economy class seats with 2rows of business class seats on three A320-200 CEO aircraft. The layoutchanges from a single class (180EY) to a two-class configuration(8BC & 156EY).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Description Report & LOI (Certification Plan) A320G-1DE-250000 Issue Ddated 08 December 2022Master Certification Document List CCN-A320G-MCDL Issue 01 dated 13January 2023ICA & Operator Manual Supplement A320G-ICA-KME Rev 00 dated 12 December2022or later revisions of the above listed document(s) app...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/01/2023	Active	10081050

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081075	HONEYWELL INTERNATIONAL Inc.	REV. 2	FAA ST02795LA	767-300F, 767-400ER 767-200, 767-300	Upgrade of Radio Altimeter System to install Honeywell ALA-52B SystemRev. 1: Editorial change.Rev. 2 corrects a typo inthe Description of Design Change.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS25 amdt 17:25.1317(a)(b)(c), 25.1529.The requirements forenvironmental protection and the associatedcertified noise a...	Certify Nation Master Data List, document number CN22-024MDL-00,Revision 0, dated 17 October 2022<(>,<)>Instructions for Continued Airworthiness, Certify Nation document numberCN22-024ICA-01, Revision 0, dated 14 October 2022<(>,<)>or later revisions of the above listed document(s) approved/accepted...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/02/2023	Active	10081075
10081077	DOA AESGLOBAL LIMITED	REV. 1		737-800	INTRODUCTION OF REPLACEMENT G7 GALLEYTHIS CHANGE INTRODUCESA REPLACEMENT GALLEY IN THE G7 POSITION ON THEAIRCRAFT	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 Amdt 4: CS25.869,25.899, 25.1301, 25.1309,25.1351, 25.1353, 25.1357, 25.1431CS-25 Amdt 27 : CS 25.1, 2...	Master Data List: AES-737-6937MDL Issue 01ICA supplement: AES-TR-3410 Issue 01AMM, IPC and WDM Supplements: AES-TP-0415Issue 01or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft must be maintained in accordance with ICA supplementreferenced AES-TR-3410- This STC must be performed concurrently with approved Minormodifications AES-737-6502; AES-737-6939; AES-737-6936; AES-737-6938;AES-737-6969Prior to installation of this change/repair it must be determined thatt...	20/01/2023	Active	10081077
10081079	AIRBUS S.A.S.			A330-743L	MOD AI0210 - MODIFY EMERGENCY EQUIPMENT ARRANGEMENT FOR OVERWATEROPERATIONS	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:- The following paragraph at JAR25 ch11: ,, 25.1301, 25.1309, 25.1353,25.1529- The following paragraph at CS252...	- Modification Approval Sheets ref: MAS AI0210 issue 01- Certification Summary Report ref: SRSA-22-006 issue 04or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/01/2023	Active	10081079
10081080	MT-PROPELLER ENTWICKLUNG GmbH			AT-602	Installation of MTV-27-1-E-C-F-R(P)-J/ CFR300-82( ) Propeller on AirTractor AT-602.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	To be operated in accordance with MT-Propeller AFM-S Document No. E-3988Rev. 0According to MT-Propeller Master Documentation List No. E-3986 Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-3989 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3990 Rev. 0or later...	According to limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	19/01/2023	Active	10081080
10081086	ADAC HELISERVICE GMBH			MBB-BK117 D-3 MBB-BK117 D-2	Installation of retractable LED search & landing light Luminator LS400M(L/H and R/H) in replacement of pre-installed Zodiac Aero Electricretractable search & landing light, as well as associated Night VisionImaging System (NVIS) approval	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-29 Amendment 10 forthe following paragraphs: 29.29; 29.45 (a)-(c); 29.65 (a); 29.67(a);29.141; 29.143; 29....	- Rotorcraft Flight Manual Supplement H145-11949-025-MFS Revision 0- Master Document List H145-11949-001-LMD Revision 2- Maintenance Manual Supplement H145-11949-023-MMS Revision 1- Compliance Summary H145-11949-044-RCS Revision 1or later revisions of the above listed document(s) approved/ acceptedun...	Limited to helicopters with Helionix cockpit variant.As prerequisite (pre-modification configuration) the Rotorcraft must beequipped with the following retractable search and landing (S/L) lights:- Zodiac Aero Electric S/L light P/N 4361646 / AHD P/N D334M3042101(i.a.w. Airbus IPC 33-43-03-01A – R/H...	20/01/2023	Active	10081086

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081088	HAECO CABIN SOLUTIONS, LLC	REV. 1	FAA ST04397AT	737-800	Interior Reconfiguration installation in a Boeing 737-800 SeriesaircraftRev. 1 adds the FAA STC number.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 amdt. 27: 25.853 (a)(c)(d)(e), 25.981 (d)The requirements for environmental protection and the associatedcertifiedu...	HAECO Cabin Solutions Master Data List 21T066L001, RevisionIR, dated 28Dec 2022<(>,<) >HAECO Cabin Solutions Instructions for Continued Airworthiness21T066R009, Revision 00, dated11 Aug 2022<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance wi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/02/2023	Active	10081088
10081097	STANDARDAERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST04547CH	GIV-X	Installation of a Viasat Ka SATCOM	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04547CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List 1040246, Revision (D), dated 16 NOV 2022;2. Airplane Flight Manual Supplement, 1040917, Revision (0), dated 07NOV 2022;3. Instructions for Continued Airworthiness, Report No. 1040287,Revision (A), dated 26 OCT 2022;or later revisions of the above listed document(s) approved/ accep...	This STC is applicable to all serial numbers for these Make-Models.EASA validation of FAA STC ST04543CH is a pre-requisite on EASA STC10081097 for the installation of a Viasat Ku Ka Radome Assembly.Prior to installation of this change/repair it must be determined thatthe interrelationship between th...	23/01/2023	Active	10081097
10081099	STANDARDAERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA STC ST04544CH	SEE FAA APPROVDED MODEL LIST	Installation of a Viasat Business Aviation Router (VBR) P/N1371388	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04544CH.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List 1040259, Revision (E), dated 15 NOV 2022;2. Airplane Flight Manual Supplement, for each Make-Model as listed onthe FAA AML number ST04544CH;3. Instructions forContinued Airworthiness, for each Make-Model aslisted on the FAA AML number ST04544CH;or later revisions of the above li...	This STC is valid for aircraft types and models approved byEASA andlisted on the FAA Approved Model List ST04544CH dated 16 November 2022.This STC is applicable to all serial numbers for these Make-Models.This STC requires prior or concurrent embodiment of a TPED STC orService Bulletin to ensure t...	23/01/2023	Active	10081099
10081114	AVIATION DEVICES & ELECTRONICCOMPONENTS LLC (Av-DEC)	REV. 1	FAA STC ST02532LA	SEE FAA AML	Modification of the wing fuel tank access covers by replacing theexisting rubstrip and seal with a new encapsulated wire mesh gasket andseal, or replacement of the existing seal with a new encapsulated wiremesh gasketRev. 1: adds Boeing 737-8200, listed in Revision H of the AML.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Data List, K3176-MDL, Revision C, dated 17 November 2017<(>,<) >Installation Instructions, Document Number IS_FG_010, revision E, dated1 August 2017<(>,<) >AWL document as specified in AML-STC No. ST02532LA<(>,<)>or later revisions ofthe above listed document(s) approved/ accepted onbehalf of E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	22/07/2025	Active	10081114
10081120	AVIATION BUSINESS CONSULTANTSINTERNATIONAL S.R.L.			A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216	LOPA modification on A320 A/CThis design change is aimed toperform passenger layout re-configurationon the A320 A/C type by replacing the existing passenger seats with the“Essenza” D3 seats model.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- SB-CNG00022-DF-020-03-E, Rev. 0<(>,<) > Service Bulletin Installation-529-00022-1000, Rev. 0<(>,<)> CABIN SEAT LAYOUTLOPA modification- MMS-CNG00022-DF-020-03-C, Rev. 0<(>,<)> Maintenance Manual Supplement- ADL-CNG00022-DF-030-01-E, Rev. 0<(>,<)> Approved Drawing Listor later revisions of the abo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/01/2023	Active	10081120

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081140	AVIATION SPECIALTIES UNLIMITED, INC	REV. 1	FAA SR01611SE	MBB-BK117 D-2, MBB-BK117 D-3 MBB-BK117 C-1, MBB-BK117 C-2 MBB-BK117 B-1, MBB-BK117 B-2 MBB-BK117 A-3, MBB-BK117 A-4	EASA validation of the Night Vision Imaging Systems (NVIS) FAASupplemental Type Certificate (STC) ref. SR01611SE.Revision 1: administrative update of the “Limitations/ Conditions”section of the STC approval to clarify that the STC is also applicableto the MBB-BK117 C2e variant.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Project Specific Certification Plan (PSCP) ref. ASU-PSCP-BK117D3-21125Revision C, dated 23/09/2022.Rotorcraft Flight Manual (RFM) Supplement ref. FMS-117004-6 Revision R,dated 26/10/2022 and approved by the FAA on 02/11/2022.Instructions for Continued Airworthiness (ICA) document ref.ICA-117004-4 Re...	This design change is limited to MBB-BK117A-3/A-4/B-1/B-2/ C-1/C-2/D-2/D-3 helicopters with a configurationdescribed in the ICA-117004-4 Appendices Revision IR, dated 15/09/2022,supplementing the ICA document ref. ICA-117004-4 Revision H, dated06/05/2022.Rotorcraft modified by this design change empl...	13/11/2024	Active	10081140
10081145	Deutsche Aircraft GmbH			DORNIER 328-100	IFOD - In-Flight Operable DoorThis change replaces the original Cargo Door by an In-Flight OperableDoor.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI D-1.1 IFOD – In-Flight Operable Door Issue3.- The following paragraph (s) at a later amendment: CS 25.783 Amdt. 27.The requirements...	Master Document List, Doc.-No. MDL 179Z0001, Issue A, Date 26.01.2023Aircraft Flight Manual Supplement, Doc.-No. AFMS12B179Z0001, Issue A,Date 19.01.2023Airplane Maintenance Manual Supplement, Doc.-No. AMMS12B179Z0001, IssueA, Date 24.11.2022 (containing an Airworthiness Limitation Section)or lateru...	The scope of this STC is limited to the installation of thedoor in theaircraft and the operation of the door in flight(open – close).Additional operations like the dropping of stores from the aircraft areout of the scope of this STC. Therefore, a separate operational approvalmay be required from t...	27/01/2023	Active	10081145
10081148	BOEING IRELAND LIMITED			787-9	Boeing 787-9 – Premium Economy IntroductionThe aircraft arereconfigured in Zones B and C in order to introduce aPremium Economy Cabin at the FWD of Zone B. The outgoing configurationis a 275 PAX 30BC / 21PEC / 48EC+ / 176EC configuration.The following changes are also included: . Class dividers...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, ‘Boeing 787-9 – Premium Economy Introduction’,BIL-00195-APP, Revision 00, dated 24th January 2023<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/01/2023	Active	10081148
10081151	SCANDINAVIAN AVIONICS DESIGN ApS			SEE EASA APPROVED MODEL LIST	INSTALLATION OF PALLET COUPLERS TO CONNECT TWO (E)TSO-C90 authorisedcargo pallets, NAS3610/ AS36100 size code A or M, installed inlongitudinal direction to double the length.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25 Amdt. 2Sections 25.1, 25.23, 25.25, 25.27, 25.29, 25.301, 25.303, 25.305,25.307, 25.337, 25.341, 25.5...	Certification Documents, Ref. 3000095 DOC, Is. 1, Date: 25.01.2023Installation Documents, Ref. 3000095 STC, Is. 1, Date: 25.01.2023Engineering Order, Ref. 3000095-EO, Is. 1, Date: 23.01.2023Component Maintenance Manual, Ref. 3000095-CMM, Rev. 0, Date: 30.11.2022W<(>&<)>B Manual Supplement, Ref. 3000...	Installation shall be done within the limitations identified for thespecific aircraft type in the related Weight & Balance and OperationManual(s). See Component Maintenance Manual, Ref. 3000095-CMM.Prior to installation of this change/repair it must be determined thatthe interrelationship between th...	30/01/2023	Active	10081151
10081171	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			A320-272N	180 Passenger Seating LayoutThis modification introduces a cabin layout using 60 economy classtriple seats generating a180 passenger seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1, CS 25.29, CS25.301 (a)-(b), CS 25.303<(>,<)>CS 25.305 (a)-(b), CS 25.307 (a), CS 25.321, CS 25.337...	The change is defined with revision 1 of AMES Engineering Order DocumentEO_M389001060_JTU_23092022Maintenance shall be accomplished in accordance with revision 1 of AMESInstructions for Continuous Airworthiness DocumentICA_M389001060_JTU_23092022or later revisions of the above listed document(s) a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/02/2023	Active	10081171

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081180	KAMATICS CORPORATION		FAA SR00413BO	212, 412	Installation of KAflex Main Rotor Driveshaft P/N SKCP3587-1in the BellTextron Inc.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 29.1529 atAmendment 8.The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	- MDL Document Number KAM-3587-MDL-001 at Revision C, datedJuly 27,2022.- Installation instructions SI Document NumberSIN3587 at Revision B,dated July 11, 2022- ICA Document Number KAM-3587-ICA-001 at Revision B, dated July 11,2022.- Airworthiness Limitations Section (ALS) of ICA Document NumberKA...	- All original product models, as a prerequisite to this STC, must bemodified by Bell Textron Inc. Service Instruction (SI) BHT-212-SI-99Rev. 0 (Original), Dated 07/15/2021, Titled “BELL 212 SERVICEINSTRUCTION FOR KAFLEX DRIVE SHAFT FIREWALL MODIFICATION KIT”. This Slinstalls Bell Firewall Tunnel Mo...	02/02/2023	Active	10081180
10081184	AVIONIK STRAUBING ENTWICKLUNGS GmbH			650	Installation of Garmin GA 36 GPS/WAAS antenna and Bendix/King AeroWaveLGA antenna.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: FAR 25.571, Amdt. 25-54 for the areas affected by this change.The requirements for environmental protectionc...	Master Document List, ASR-2022-026-MDL-01-00, revision 00, dated 01February 2023.To be installed according to Instructions for Installation,ASR-2022-026-IFI-10-00, revision 00,dated 07 November 2022.To be maintained according to Instructions for continued Airworthiness,ASR-2022-026-ICA-11-00, revisi...	Only structural aspect of the installation of antennas is approved. Thefunctional aspect and the interface with aircraft systems is notapproved by this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously i...	03/02/2023	Active	10081184
10081186	ENAC	REV. 2		TB 10	New Ignition system for TB10 O-360 engineReplacement of theexisting D4LN3000 dual magneto by the combination ofa single Slick 4373 magneto and an electronic ignition systemmanufactured by Electroair.Rev. 1: Proposing a new ENAC designed Trigger Wheel and a more secureENAC designed command panel.Rev...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impact...	Certification program specific to minor n°2 change to STC10081086Version: 1.3 Dated: 12 September 2024Or later revisions of the above listed document (s) approved/ acceptedunder theEASA system.	The approval holder shall fulfill the obligations of Part 21, Point21.A.109.Prior to installation of this change/ repairit must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworth...	05/11/2024	Active	10081186
10081191	ECMS AVIATION SYSTEMS GMBH			AW169	Installation of external load system EAD04	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Compliance Program EAD04_MOC_EASA_ Rev. R0 dated 31stJanuary 2023- Declaration of compliance EAD04_DoC_EASA_ Rev. 0 dated 31st January2023- Installation Instructions EAD04_INST_AW169_EASA_R0 dated 29th April2021- Flight Manual supplementEAD04_RFMS_EASA, Rev. 0 dated 23 August 2022- Component Main...	EAD04 extendable boom installation is certified on the RH of thehelicopter with a SPONSON-EXTENSION installed as a prerequisite.Prior to installation of this change/ repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repa...	07/02/2023	Active	10081191
10081210	NORTHWEST AEROSPACE TECHNOLOGIESINC.	REV. 1		777-200	Cabin Reconfiguration 330 passengers for Austrian Airlines.Rev 1: Approval of amended AFM Supplement for ELMS Load Shedding-relatedprocedure.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 at amdt. 1: 25.853(a)(d)(e), 25.1431(a)(c)CS 25 at amdt. 4: 25.869(a)(1)(4), 25.1357(a)(b)(c).The requ...	Certification Summary N0707-D90 Rev DMaster Drawing List N0707-D10 Rev FICA Principle Manual N0707-D70 Rev AAFM Supplement N0707-D80 Rev Aor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	The installations of the configuration covered by this STC havefollowing prerequisite installations:- STC 10043471 (FAAref. ST02257SE) or- STC 10063645 + STC 10078270 or- STC 10065406 + STC 10078270.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenp...	07/02/2024	Active	10081210

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081211	PEREGRINE AVIONICS LLC		FAA STC SA01988WI	390	Installation to replace the existing DeVore wingtip and tail positionanti-collision lights with Whelan AerospaceTechnologies Light Emitting Diodes (LED)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List, Document No. EW-21-0002, Revision B, signed 26 May2022<(>,<) >or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/02/2023	Active	10081211
10081231	INFINION CERTIFICATION ENGINEERING		TCCA SA22-16, ISSUE 1	DHC-8-401, DHC-8-402 DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-103, DHC-8-106 DHC-8-101, DHC-8-102	Flight Compartment Stowage BoxA stowage box is fabricated and installed in the aircraft, under thefloor. This box is used for miscellaneous storage and is accessible fromthe flight compartment during flight.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:. For DHC-8-100, DHC-8-200 and DHC-8-300 models: FAR 25.1, 25.601,25.609, 25.1541 at Amdt 25-0, FAR 25.771 a...	Installation shall be performed in accordance with InfinionCertification Engineering Inc. Installation Instruction EO-1001-02,Issue 1Maintenance shall be performed in accordance with Infinion CertificationEngineering Inc. Maintenance Manual Supplement and Instructions forContinued Airworthiness MMS-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/02/2023	Active	10081231
10081240	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA STC ST04344AT-D	GIV, GIV-X, GV, GV-SP	Installation of Satcom Direct Plane Simple System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Gulfstream Aerospace Corporation Index List GDL 100000064, Revision (B),dated 16 December 2024<(>,<)>Airplane Flight Manual Supplement,·CE41303M01 7, Revision A, dated 16December 2024 for G-IV model<(>,<)>Airplane Flight Manual Supplement, CE41303M018, Revision A, dated 16December 2024 for GIV-X mode...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/05/2025	Active	10081240
10081241	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST03833AT	767-300F 767-300 767-200	Installation of an Iridium Communications System in B767-200/-300/-300FSeries Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendmentCS 25 amdt. 0: 25.29, 25.303, 25.561, 25.601, 25.605, 25.1307, 25.1431,25.1529, 25.1541CS 25 amdt. 1: 25.305, 25.307, 25.613...	Avionics Support Group, Inc. Master Data List 29126-MDL, Rev. S, dated26 September 2022<(>,<)>Airplane Flight Manual Supplement for Avionics Support Group 29126-AFMSRevision B<(>,<)> dated 27 December 2022<(>,<)>Instructions for Continued Airworthiness 29126-ICA, Rev. D, dated 26September 2022<(>,<)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Installations of the Spectrolux ACARS unit and the ICG(...	08/05/2023	Active	10081241
10081245	GULFSTREAM AEROSPACE CORPORATION			GV	Installation of L3 Harris GH-3900.2 Secondary Flight Display onGulfstream GV model aircraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval withoutan...	FAA Supplemental Type Certificate (STC), ST04338AT-D<(>,<) >Installationof L3 Harris GH-3900.2 Secondary Flight Displayissued 7 July 2021<(>,<)>Index List GDL100000057, Revision (-), dated 7 July 2021<(>,<) >Airplane Flight Manual Supplement, CE51331M004, Revision (-), dated 7July 2021<(>,<) >Instruc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/04/2023	Active	10081245

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081283	DECA AVIATION ENGINEERING LIMITEDd/b/a PAL AEROSPACE		TCCA STC SH11-7 ISSUE 03	AS 355 N, AS 355 NP AS 355 F1, AS 355 F2 AS 355 E, AS 355 F AS 350 B2, AS 350 B3	Structural provisions and equipment installation of CGG-AGGSurveySystem	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification Summary MS10096, Rev 10Flight Manual Supplement FMS10096, Rev 6Instructions for Continued Airworthiness ICA10096, Rev 6or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral...	- For AS 355NP, CAT A operations are not approved with the installationof this STC- This STC covers only the installation of equipment as items of mass.Separate approval is required for the operational, electrical, andfunctional aspects ofthe ACG Survey System installation and itsinterconnection wi...	15/02/2023	Active	10081283
10081288	HELI-ONE (NORWAY) AS			AS 332 L1 AS 332 L	Required Navigation Performance (RNP) approach capability certification(ref. modification AHSE-72850).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 29 Amdt 2 for thefollowing requirement: 29.610.The requirements for environmental protection and the ass...	Certification Programme (CP) ref. AHSE-72852 Revision F, dated28/11/2022.Flight Manual Supplement (FMS) for RNP approach capability ref. SUP.H1No.I. 340 Revision dated 23/01/2023.Product Change Declaration (PCD) ref. AHSE-72850 Revision F, dated15/02/2023.Instructions for Continued Airworthiness (ICA...	This approval is only applicable to AS 332 L1 helicopter models equippedwith AHCAS (i.e. AS332 L1e).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverse...	15/02/2023	Active	10081288
10081291	ALAMO ENGINEERING GmbH	REV. 1		DORNIER 328-100	Mission Cabin ConfigurationRevision 1: This revision adds asecond cabin layout configuration with6 occupant seats to the already approved 9 occupant seat layout	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.853 Amdt 27The requirements for environmental protection and the associatedcertified noise and/ or emis...	Master Document List (MDL22A25AE-01) with Rev. C dated 11.07.2024Operator Manual (OM-B) with version 1.2 dated 10.07.2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to A/C with EASA STC 10013993 (former STC EASA.A.S.01024) embodied.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthin...	11/07/2024	Active	10081291
10081295	SABENA TECHNICS BGC			A321-272N A321-251N/-252N/-253N/-271N A321-211/-212/-213/-231/-232 A321-111/-112/-131	A321 Cabin Reconfiguration from 192PAX (192Y/C) to 214PAX (214Y/C)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amdt. 4: 25.1, 25.29, 25.561, 25.775, 25.785, 25.787, 25.789,25.791, 25.803, 25.811, 25.812, 25.815...	Master Data List, Ref. 40916-01-A-MDL-R00 dated February 15th 2023Instructions for continued airworthiness, Ref. 40916-01-A-ICA-R00 datedFebruary 14th 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:Installation of a photo-luminescent EFPM as per Lufthansa Technik'sEngineering Bulletin A320-EB33-0384, approved by EASA STC No. 10014013.Prior to installation...	16/02/2023	Active	10081295
10081304	BOOST HUMAN EXTERNAL CARGO SYSTEMS		TCCA SH15-39, ISSUE 8	AS355E/F/F1/F2/N/NP AS350B/B1/B2/B3/BA/D AS 350 B3	Dual Hook System (ref. B1310-DHS) for Human External Cargo.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 27.865 Amdt 6.The requirements for environmental protection and the associatedcertified noise and/ or em...	Master Document List, MDL-B1310-DHS, Rev. NC, dated January26, 2023Certification Plan CP1517, Rev. D, dated December 19, 2022Flight Manual Supplement FMS-B1310-EASA, Rev. NC, dated January 26, 2023Installation Instructions, INSTALL-B1310,Rev. E, December 19, 2022Instructions for Continued Airworth...	- Pre-requisite: AS 350 B3 Swing equipped with Onboard hookintroducedby the MOD OP3218- PCDS not included in scope of the STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repai...	21/02/2023	Active	10081304

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081315	JET AVIATION AG			GVI (G650)	Installation of new Cabin Layout 'WOLF' for Gulfstream GVI (G650)aircraft, in accordance with Jet Aviation Master Data ListJBSL-M-03824MDL-001.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Jet Aviation Master Data List JBSL-M-03824MDL-001, Issue B,dated 17 Feb2023<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- The following modification is a prerequisite for this installation: JBSL-M-03823MMA-001, Cabin Modification Minor Mod- Private Operation (not-for-hire, non-commercial)- Non-Smoking AircraftPrior to installation of this change/repair it must be determined thatthe interrelationship between this chan...	22/02/2023	Active	10081315
10081345	NSE			MBB-BK117 D-3 MBB-BK117 C-2	Installation of the BCT communication and tracking unit EC145-H45 P/ N00037647AA.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Plan No. PCERT-00048968AA, Rev A1Roorcraft Flight Manual Supplement No. RFMS-BCT-EC145-EN, rev 01Conformity Statement and Documentary architecture No. CONFAD-00048968AA,Rev A1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/02/2023	Active	10081345
10081347	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A321-231	C0359 A321 High Density Cabin ModReplacement of all 194 Weber 5700 Model seats with 215 Safran Z85B-Dragonfly seats, installation/ rearrangement of PSUs, EmergencyEquipment relocation and installation, carpet, NTFs and life vestreplacement and a windscreen installation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- C0359-DWG01-00 LOPA Drawing- C0359-DWG02-00 PSU Layout- C0359-DWG03-00 Emergency Equipment Layoutor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/02/2023	Active	10081347
10081348	MICRO AERODYNAMICS, INC.		FAA STC SA00795SE	8KCAB 7GCBC (180HP) 7GCBC (160HP) 7GCAA 7ECA	Installation of vortex generators on the wings and tail surfaces of theabove model aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA00795SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Drawing Package MA2131, Revision A, dated 22 April 2001;2. Installation Manual MA2132, Revision A, dated 22 April 2001;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	If more than five vortex generators are damaged or missing,the aircraftis not airworthy.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	27/02/2023	Active	10081348
10081355	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			737-800	189 Passenger Seating LayoutThis modification introduces a cabin layout using 63 economy classtriple seats generating a189 passenger seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1, CS 25.29, CS25.301 (a)-(c), CS 25.303, CS 25.305 (a)-(b), CS 25.307 (a), CS 25.321(a), CS 25.337,2...	The change is defined with revision 0 of AMES Engineering Order DocumentEO_M389001075_MTH_08112022Maintenance shall beaccomplished in accordance with revision 1 of AMESInstructions for Continuous Airworthiness DocumentICA_M389001075_MTH_25102022or later revisions of the above listed document(s) ap...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/02/2023	Active	10081355

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081358	PME ENTERPRISES INC.		FAA SA02606CH	JETSTREAM 3100 SERIES	Air Ambulance Conversion on Jetstream 3100/3200 series	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement dated July 21st 2008Maintenance Manual Supplement dated July 25th 2008Master Data List: Report006-I dated September 28th 1992or later revisions of the above listed document(s) approved/accepted onbehalf of EASA inaccordance with the Technical ImplementationProcedures of EU...	No carriage of oxygen onboard and oxygen system of the Air Ambulanceconversion to be made inoperative.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adver...	01/03/2023	Active	10081358
10081367	SKYTEC AEROSPACE GmbH			737-8, 737-800	64C / 24Y Passenger Seating LayoutThis modification introduces a cabin layout using 8 economy class tripleseats and 32 business class double seats generating a 88 passengerseatingconfiguration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: For Boeing 737-800model: CS 25.1, CS 25.23, CS25.25<(>,<)>CS 25.27 (b)-(c), CS 25.29, CS 25.301, CS 25.303...	The change is defined with revision B of Skytec Master Document ListDocument MDL-B738C111-0001The aircraft shall be operated in accordance with revision A of SkytecAircraft FlightManual SupplementAFMS-B738C111-0001Maintenance shall be accomplished in accordance with revision A ofSkytec Instructions...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/03/2023	Active	10081367
10081374	EICHELSDOERFER GmbHFLUGZEUGBAU			LS6-C, LS6-C18, LS6-18W LS 6	Installation of a turbine engine for self-sustaining propulsion	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of the turbine engine EASA.E.108 in accordancewithEichelsdörfer GmbH Flugzeugbau (EGF) document LS6 STCPSR DL, atrevision 3, dated February 27, 2023;Aircraft Flight Manual Supplement, EGF document LS6 STC PSR FL, atrevision 0, dated November 28, 2022;Aircraft Maintenance Manual Su...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/03/2023	Active	10081374
10081375	AEROLITE AG	REV. 1		PC-24	Installation of EMS Equipment P/N 024-0303000-501	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of EMS Equipment P/N 024-0303000-501 in accordance withAerolite Master Data List - MDL-22-009 rev. N/C dated 28 February 2023;Aircraft Flight Manual Supplement Aerolite document FMS-024-0303000-501 rev. 0 dated 01 February 2023;Instructions for Continued Airworthiness: Operations Manual...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/03/2023	Active	10081375
10081396	RUAG AG			AS 350 B3	Night Vision Imaging System for AS 350 B3 S/N 4913 including:-Night Vision Goggles NVGs, White Phosphor FENN NG800-GI 205 Radar Altimeter Indicator-Modification to cockpit lighting system	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: Amdt 4 of CS 27: 27.1(a) (b) (c); 27.610 (a)(b)(c)(d); 27.1309 (a) (c); 27.1316; 27.1317(a)Amdt 5 of CS 27: 2...	Master Data List, MDL-8007429 rev AInstructions for Continued Airworthiness, ICA-8007349 Rev AFlight Manual Supplement,FMS-615658 Rev BMaster Minimum Equipment List Supplement, MEL-8007353 Rev A, Item 33-12and 34-15 added/modified.or later revisions of the above listed document(s) approved/accepted...	Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the cockpit or cabin configurationspecified in this de...	06/03/2023	Active	10081396

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081405	AVCON INDUSTRIES, Inc.		FAA STC SA01965WI	B300C B300 B200GT B200CGT B200C B200 A200C A200 300 200C 200	Installation of Wing Tip Hard Point Provisions	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Data List, No. 05601000, Rev. IR, signed 5 May 2021<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/03/2023	Active	10081405
10081406	AVCON INDUSTRIES, Inc.		FAA STC SA04178NY	B300C B300 B200GT B200CGT B200C B200 A200CT A200 300LW 300 200CT 200C 200	Installation of Underwing Hard Points	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aerospace Design & Compliance:(1) Master Data List B350-MDL-0035, Revision IR<(>,<)> dated 17 May 2019<(>,<)>(2) Instructions for Continued Airworthiness 248-811, Revision IR, dated15 May 2019<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance w...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/03/2023	Active	10081406
10081408	AVCON INDUSTRIES, Inc.		FAA STC SA04209NY	B300C B300	Increasing the Maximum Zero Fuel Weight (MZFW) from 13,000 to 13,400pounds	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	1) Aerospace Design & Compliance, LLC., Master Data List, B350-MDL-0090,Revision IR, dated 10 June 2021<(>,<)> (2) AVCONIndustries, Inc., Aircraft Flight Manual Supplement (AFMS)<(>,<)> B350-AFMS-0090, Rev IR, dated 10 June 2021<(>,<) >or later revisions of the above listed document(s) approved/accep...	This STC is applicable to all serial numbers for the Make: TextronAviation Inc. Models: B300 & B300C aircraft.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introducee...	07/03/2023	Active	10081408
10081410	THALES AVIONICS Inc.		FAA STC ST02803LA	747-400F 747-400	Installation of the upgraded Thales Radio Altimeter Transceiver Units,ERT550R	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 amdt 5: 25.611 (a)The requirements for environmental protection and the associatedcertified noise and/ or emissions le...	Thales Avionics, Inc. Index List Drawing No. 259239, Revision A, dated10 February 2023,or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.The applicable FAA Approved Instructio...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/03/2023	Active	10081410
10081415	PMV ENGINEERING	REV. 1		A319-153N, A320-251N	Cabin humidification and dryer system installationRev1: A320-251N added to the applicability list.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 amt. 18: 25.301,25.303, 25.305(a)(b)(f), 25.307(a), 25.365(e), 25.561, 25.601, 25.603,25.605, 25.611, 2...	Top Master Document List ECS-00120-TMDL Rev 2Instructions for Continued Airworthiness ECS-00120-ICA-S01 Rev02Instructions for Continued Airworthiness ECS-00120-ICA-S02 Rev01or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- The applicability of this certificate is limited to the S/N listidentified in the ECS-00120-TMDL document- As per ICAdocumentation: “Calibration and changes to the humidifierssettings are only allowed inaccordance with CCS ConfigurationChart. Any application for an updateof the CCS Configuration...	13/06/2023	Active	10081415
10081425	AVIATION BUSINESS CONSULTANTSIN TERNATIONAL S.R.L.			P.68 "VICTOR", P.68B "VICTOR" P.68TC "OBSERVER" P.68R "VICTOR" P.68 "OBSERVER 2" P.68 "OBSERVER" P.68C, P.68C-TC	INSTALLATION OF REMOTE SENSING SYSTEM ON P68Installation ofremote sensing system: Laser (class 3B), Camera, andRemote Sensing Equipment.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment: CS-23 Amd 4:23.21 (a)(b), 23.23(a)(b), 23.25(a)(b), 23.29(a)(b), 23.301(a)(c), 23.303, 23.305(a)(b), 23.307(a...	Installed in accordance with Service Bulletin document number:SB-CNG01320-DF-020-03-E, Revision 1, dated 13 Jul 2022.operated in accordance with Aircraft Flight Manual Supplement documentnumber: AFMS-CNG01320-DF-030-02-A, Revision 2, dated21 Feb 2022.maintained in accordance with Maintenance Manual...	Pre-requisite installation of one of the following to providephotogrammetric hatch: 1. Partenavia Service Bulletin No. 01– Aerophotogrammetric hatch2. Vulcanair Aircraft Service Bulletin No. 112 – Installation ofphotogrammetric hatch3. P68 AFM Supplement A - Installation of photogrammetric hatch4. EA...	08/03/2023	Active	10081425

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081450	APTOZ EHF.	REV. 2		737-8	New seating layout with 160 total passengers using AVIO seats with ZiiRave IFE and ISPS systemsRev. 1: Editorial change.Rev. 2: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 Amdt 18: 1,29 (a)(b), 301(a), 302, 303, 307(a), 365(g), 561(b)(c)(d), 571, 601,603 (a)(b)(c), 605(a), 6...	- Major Change/Repair MCR-737-2520-115 initial release- Aircraft Flight Manual Supplement AFM-737-2520-115 initial revisionor later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10081450
10081454	AVCON INDUSTRIES, Inc.	REV. 1	FAA SA11298DS	B300, B300C	Installation of two 400-AMP starter generators in place of 300-AMPstarter generatorsRev. 1: Transfer from Aerospace Systems International, LLC to AvconIndustries, Inc.	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA11298DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Master Data List, document number 646-00-0001 revision IR, dated 10August 2021Airplane Flight Manual Supplement, document number 646-00-0037 revisionG, dated 20 July 2021Instructions for Continued Airworthiness, document number 646-00-0031revision D, dated 19 July 2021or later revisions of the above...	- This installation requires the installation of Pratt and WhitneyPT6A-67A engines per STC SA02658LA or previously installed Pratt andWhitney PT6A-60A engines with previously installed HC-B4MP-3C hubs andM10476NK blades.- The installed weight of the engine, propeller and generator will belimited to-...	12/10/2023	Active	10081454
10081491	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525B	Mechanical Installation of Garmin GA35 GPS Antenna	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with ASR-2023-001-IFI-10-00 dated 16/02/2023;Maintained in accordance with ASR-2023-001-ICA-11-00 dated 27/02/2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/03/2023	Active	10081491
10081498	SABENA TECHNICS BGC			A330-223/-243 A330-201/-202/-203	Cabin Reconfiguration 296PAX (2 classes)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS-25 at amdt. 4: 25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321,25.337, 25.341, 25.365, 25.471, 25.561,2...	Master Data List, Ref. 40957-01-A-MDL-R00 dated March 15th 2023Instructions for continued airworthiness, Ref. 40957-01-A-ICA-R00 datedMarch 15th 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	As a concurrent requirement of this change, accomplishment of this STCrequires the simultaneous accomplishment of the following modification:“Installation of a non-electrical floor path marking system” as perLufthansa Technik’s EASA STC No. 10014507 Rev.02 (originallyEASA.A.S.02580) Prior to installa...	16/03/2023	Active	10081498
10081502	EIMERS, BENJAMIN HEINRICH			S-71A, S-77A S-57A, S-57S, S-60A, S-66A S-49A, S-52A, S-53A, S-55A RX-6, RX-7, RX-8, RX-9, RXS-8 CELL, W100LB	Modification of propan hose coupling from CGA-555 to Rego (ACME 1 ¼”)coupling for Aerostar burners.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS31HB.33, 45, 46, 81,82 amdt. 1	Certification Program Eimers_Ballooning STC_No.1, dated 01 March 2023Eimers Ballooning STC_No. 1 AFM Appendix 1or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is limited to the modification of Aerostar burnersinstalled inELA1 balloons.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon th...	16/03/2023	Active	10081502
10081564	AEROTEC & CONCEPT			737-800 737-8 737-700	Iridium antenna installation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-25 Amdt. 11 Sections25.23, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341, 25.365,25.581, 25.601,2...	Master Data List, Ref. AE23010MDL, Is. 0, Date: 10.03.2023Instructions for Continued Airworthiness, Ref. AE23010ICA, Is. 0, Date:10.02.2023Service Bulletin, Ref. AE23010SB, Is. 0,Date: 10.02.2023Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Only external installation: activation and internal mechanicalprovisions are not covered by this modification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introducee...	24/03/2023	Active	10081564

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081567	airplus engineering GmbH			DORNIER 228-202/ -212 DORNIER 228-200/ -201 DORNIER 228-100/ -101	Installation of a special mission radome	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed and maintained in accordance with MMS-2470-500000rev 1;operated in accordance with POH-2470-500000 rev 1<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	As defined in the associated technical documents.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	24/03/2023	Active	10081567
10081568	STENE AVIATION, INC.		FAA STC SA4302WE	150M/152/A150M/A152 150F/150G/150H/150J/ 150K/150L	Installation of leading edge "CUFF" on each wing	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Stene Aviation Master Drawing List Number SASP-1, Revision A, dated 20November 2015<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/03/2023	Active	10081568
10081574	HELI-ONE (NORWAY) AS	REV. 4		AS 365 N3	Electronic Flight Information System EFI-890H Installation (ref.modification AHSE-74000)Rev. 1: Installation of 3rd pitot tube used for standby instrument.Rev. 2: EFI-890H Installation - Software Upgrade in EFI-890H to SCN1017.1.15Heli-OneModification Number: AHSE-74000Rev. 3: Introduce Limitations...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:CS 29 Amendment 4 for the following requirements:29.1316 and 29.1317,and CS 29 Amendment 8 for the following<...	- Certification Program ref. AHSE-74001 Revision E, dated 10/02/2023- Product Change Declaration ref. AHSE-74000 Revision E, dated25/04/2024- Declaration of Compliance ref. AHSE-74004 Revision E dated 26 June2024.- Rotorcraft Flight ManualSupplement: SUP. H1No.I.374 dated 18 June2024- Certification...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	11/03/2025	Active	10081574
10081597	ELISEN & ASSOCIES INC.ELISEN & ASSOCIATES INC.		TCCA A-LSA19-171/D	FALCON 7X	Falcon 7X MSN 113 Interior ReconfigurationReconfiguration of the cabin with removal and replacement of components(divan, bulkhead, door). Installation of additional AC and USB outlets.Life rafts changed to address increase in number of occupants.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI D-27 (Table Obstruction to Type IIIEmergency Exits.The requirements for environmental protection and the associatedcertifi...	- Modification Data Summary MDS-3039 Revision A- Duncan Aviation AFM Supplement CERTDOC-010306 Revision A- Duncan Aviation ICA CERTDOC-010142 Revision A- Elisen MMEL Supplement MEL-3039 Revision Aor later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with...	Applicable to F7X MSN 113.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	29/03/2023	Active	10081597
10081604	LEE AEROSPACE, INC.		FAA STC ST04221NY	35A 31A 31	Installation of LAI Heated Windshields	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST04221NY.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List, LAI-MDL-135, Revision A, dated 12 January 2023;2. Instructions for Continued Airworthiness (ICA) LAI-ICA-135, RevisionB, dated 12 January 2023;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationPro...	This STC is applicable to all serial numbers for the Make: Learjet Inc.Models: 31, 31A & 35A.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	29/03/2023	Active	10081604

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081605	AVIDYNE CORPORATION		FAA STC SA00331BO	V35/V35A/V35B H35/J35/K35/M35/N35/ P35/S35 E33C/F33/F33A/F33C/ G33/G36 36/A36/A36TC/B36TC/ E33/E33A 35-33/-A33/-B33/-C33/-C33A	Installa1ion of Avidyne Corporation Autopilot:Model DFC90, p/n 700-00170-025 (28-volt electrical system) or p/n700-0170-026 (14-volt electrical system), loaded with Release-0 softwareas a replacement for the S-TEC autopilot.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Avidyne Corporation Master Document List AVDEC 157, Rev. 00, dated 2 May2013<(>,<) >Avidyne Corporation Airplane Flight Manual Supplement (AFMS) Document600-297000, dated 10 May 2013<(>,<) >Instructions for Continued Airworthiness (ICA), AVDEC 163, Revision 00,dated 25 March 2013< (>,<)>or later revisi...	Aircraft must be configured with an existing S-TEC Manual Electric Trian(MET System) and with a S-TEC autopilot as follows in order toaccomplish this STC:Existing S-TEC Autopilot:System 20 with 30 ALTS-TEC Part Number: 01260 (), 01261()Existing S-TEC Autopilot: System 30S-TEC Part Number: 1260(), 12...	29/03/2023	Active	10081605
10081613	AERODISA S.L.			A321-271NX/-272NX A321-251NX/-252NX/-253 NX	236 Passenger Seating LayoutThis modification modifies a 236 passenger seating configuration byre-pitching of the seat rows 1 through 4.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision A5 of Aerodisa Master Data ListAED2023-01M-MDMThe modification is defined with revision A3 of Aerodisa ServiceBulletin Document AED2023-01M-DIor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/03/2023	Active	10081613
10081614	JANZAIR CONSULTING SERVICES, INC.		FAA ST04431AT	747-300/-400/-400F 747-200B/-200C/-200F	Installation of the Rockwell Collins TPR-901 Mode S transponders andFree Flight SBAS sensor for ADS-B Out capability	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- the following paragraph(s) at a later amendment: CS-ACNS Rev 4: ACNS.D.ADSB. 010/020/025/030/035/040/045/050 /055/060/070/080/085/090/100/10 5/110/115/120.Thec...	Master Data List 747-3699-1601 Rev C.Instructions for Continued Airworthiness 747-3699-1604 Rev. IRAirplane Flight Manual Supplement 747-3699-1610 Rev. Aor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of...	As per ICA document.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changeand/ or repair will introduce no adverseeffect upon the airworthiness of the product.	30/03/2023	Active	10081614
10081618	EIRTECH AVIATION SERVICES LIMITED			A320-251N	Installation of Slide-Raft on A320This change installs emergency slide-rafts instead of the emergencyslides on the passenger/crew doors. The forward (FWD) and aft (AFT)slides are changed on both the left and right sides of the aircraft.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- CCOM supplement referenced CCOMS/ 1676-001 issue 03 dated 24th March2023- CCD supplement referenced CCDS-1676-001 issue 02 dated 01st March 2023- AMM supplement referenced AMS/1676-001 Issue 02 dated 24Th March 2023- MDL referenced MDL/1676-001 Issue 01 dated 30th March 2023or later revisions of th...	Aeroplanes modified per this STC (i.e. with slide-rafts at D1< (>&<)>D4)are considered to be a “variant” to the A320 without the modification(i.e. with slides at D1<(>&<)>D4). Cabin crew operating aeroplanesmodified per this STC must complete aircraft difference training inaccordance with ORO.CC. 130,...	30/03/2023	Active	10081618
10081627	DASSAULT FALCON JET CORPORATION	REV. 3	FAA STC ST03613NY	FALCON 2000EX	Installation of Garmin GI 275 (Standby Flight Display System) inDassault Aviation Falcon 2000EX aircraftRev. 1 upgradesthe software to Version 3.20, revises mechanicalinstallation, and revises the system configuration for the installationof Garmin GI 275 Standby Flight Display System (SFDS) on Dass...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Dassault Aircraft Services (1) Master Data List F2XW-D0110-005, Rev.(B), dated 6 June 2024<(>,<) >Instructions for Continued Airworthiness (ICA) F2XW-D0110-155, Rev. (B),dated 24 June 2024<(>,<) >Airplane Flight Manual Supplement (AFMS) F2XW-D0110-150 Rev. (B), dated24 June 2024<(>,<) >Master Minimum E...	This alteration is applicable to Falcon 2000EX airplanes serial numbers6, 28 and subsequent.GI-275 and GDC-72B hardware, software and configuration must conform toHardware & Software Configuration matrix F2XW-D0110-250 Revision(A),dated 21May 2024<(>,<)>Prior to installation of this change/repair i...	28/05/2025	Active	10081627

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081634	AIRBUS HELICOPTERS DEUTSCHLAND GmbH			EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of upgraded transponder Garmin GTX 330 ES (ExtendedSquitter) in accordance with Compliance Report SK-MAC-255-CRP-B-2318	For the Major Design Change regarding the installation of the upgradedtransponder Garmin GTX 330 ES (Extended Squitter) subject to thisapproval, the Certification Basis (CB) for the original product remainsapplicable. In addition, the applicant has shown compliance with CS-ACNSIssue 4, as applicable...	- Rotorcraft Flight Manual Supplement SK-MAC-255-SUP-B-2317Issue A-Compliance Report SK-MAC-255-CRP-B-2318 Issue ATheassociated Instructions for Continued Airworthiness (ICA) areprovided with Customization Manual SK-MAC-255-CM-B-2316 Issue Aor later revisions of the above listed document(s) appro...	Limited to helicopters with CPDS cockpit variant where a Garmin GTX 330system is already installed in combination with Garmin GNS 430W/ 530W.This design change is only applicable to helicopters without installedTCAS system.Prior to installation of this change/repair it must be determined thatthe inte...	03/04/2023	Active	10081634
10081635	AIR PROJET			DR 400 NGL, DR 400 RP DR 400/2+2, DR 400/500 DR 400/200 I, DR 400/200 R DR 400/180 S DR 400/180, DR 400/180 R DR 400/160, DR 400/160 D DR 400/140, DR 400/140 B DR 400/125, DR 400/125I DR 400/120 A, DR 400/120 D DR 400/100, DR 400/120 DR 315, DR 340, DR 360, DR 380 DR 300/180 R DR 300/125, DR 300/140 DR 300/108, DR 300/120 DR 253, DR 253 B DR 250, DR 250 B DR 250 B-160, DR 250-160 DR 221, DR 221 B DR 220 AB, DR 220 B DR 200, DR 220, DR 220 A	Engine monitoring parameters CGR-30P &/or Fuel level Indicator FL20XD&/or CEIS Fuel level Sender	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:The following paragraph(s) at a later amendment: CS 23 Amdt 4 §§ 23.603<(>,<)> 23.773, 23.867, 23.901, 23.954,23.955, 23.993, 23.1121, 23.1163, 23.1183<(>,<)> 23.1301, 23...	Master Data List Doc APMDL-0118 dated 31 March 2023AircraftFlight Manual Supplement (AFMS) Doc APAFM-0118 dated 2 March2023Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	03/04/2023	Active	10081635
10081645	SECURAPLANE TECHNOLOGIES, Inc.		FAA STC ST04383CH	A321-271N/-271NX/-272N/-272NX A321-252NX/-253NX/-253N A321-232/-251N/-251NX/-252N A321-112/-131/-211/-212/-213 A320-251N/-271N/-111/-112 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Replacement of Main Ship Battery	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Standard Aero Master Data List 1035677, Rev. A, dated 7 November 2019<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/05/2023	Active	10081645
10081651	HELI-ONE (NORWAY) AS			AS 365 N3	Euronav 7 and MFD Installation (ref. modification AHSE-74250)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program ref. AHSE-74253 Revision B, dated 30/03/2023Product Change Declaration ref. AHSE-74250 Revision A, dated 31/03/2023Declaration of Compliance ref. AHSE-74254 Revision A, dated 31/03/2023Flight Manual Supplement ref. H1No.I.368 dated 30/03/2023or later revisions of the above list...	The following modifications are a pre-requisite for the embodiment ofthis design change:AHSE-74980 “CMA-9000 FMS Provision Installation”AHSE-74000 “EFI-890H EFIS Installation”AHSE-74290 “DF-938 Direction Finder Installation”.Prior to installation of this change/repair it must be determined thatthe i...	05/04/2023	Active	10081651

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081653	FOKKER SERVICES B.V.			737-8, 737-9	Introduction of ULD on B737 Max (-8/-9) The change introduces an Underwater Locator Device.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Certification Program CPR-0467 issue 2- Certification Record Report CRR-0467 issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/04/2023	Active	10081653
10081656	BOEING IRELAND LIMITED			737-8	189 Passenger Cabin ReconfigurationChange from a two class, 174 passenger, to a full economy 189 passengercabin interior configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, '737-8: Two to One Class 189PAX',BIL-00221-APP, Revision 00, dated 5th April 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/04/2023	Active	10081656
10081658	AMAC AEROSPACE SWITZERLAND AG			SEE EASA APPROVED MODEL LIST	Certification of Alternative Floor PanelsThis modification certifies alternate cabin floor panels as areplacement on various Boeing aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1, 25.301,25.303, 25.305, 25.307, 25.365, 25.561, 25.601, 25.603, 25.605, 25.609,25.611, 25.613, 25.853...	The change is defined with Revision A of Master Data List documentMDL-ALLAC01-5300.The aircraft shall be maintained in accordance with Revision B ofInstallation Manual document IM-ALLAC01-5300.or later revisions of theabove listed document(s) approved/ accepted under the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/04/2023	Active	10081658
10081678	GFD GmbH			36A 35A	Mechanical Provisions for the installation of an antenna inthe upperfuselage	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25.571 Amendment 27The requirements for environmental protection and the associatedcertified noise and/ ora...	GFD, Master Data List, 22-052-MDL-01, Rev. 0.1, 06.04.2023GFD, Engineering Order, 22-052-EO-01, Rev. 0.0, 13.12.2022or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/04/2023	Active	10081678
10081686	ZIM AIRCRAFT SEATING GMBH			A350-941, A350-1041	BC1 Seats intalled in A350 Air Caraibes Aircrafts modification due toMaterial Obsolescence:A. Plastic raw material change. Obsolete material XHR6206 needs to bereplaced for spares:- Kydex FST (equal to XHR6006) for backrest.- Kydex 6565HI for kick panel and center console decorative parts.B. For bon...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-25 Amdt. 27 for: CS25.23, 25.25, 25.27, 25.561, 25.562, 25.625, 25.785, 25.789, 25.853,25.1301 paragraphsT...	Master Document List, 505706-MDL-001, Revision 0Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is limited to the following aircraft S/N:- A350-941: MSN 005; 193; 325 and 433- A350-1041: MSN 065; 482 and 533Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wille...	12/04/2023	Active	10081686
10081692	AIRBUS HELICOPTERS CANADA LIMITED	REV. 1	TCCA STC SH21-25 ISSUE 2	AS 350 B3	Airframe-Mounted Fuel Filter Installation, compatible with existingaircraft's crash resistant fuel system.Revision 1 isan administrative re-issuance to correct the address	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Compliance Program, CP-0402, issue B.Master Drawing List, MDL-21-001, Issue B.Flight Manual Supplement, FMS-AHCA-172, Rev 1.Instructions for Continued Airworthiness, ICA-AHCA-297,Rev 1<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the...	The following are pre-requisite mods for the subject installation:• Arriel 2D Engine (OP-4305)• Crashworthy Fuel Tank (OP-4605) OR• Fuel System Crash Resistance compatible with Cargo Swing Installation(07.20034)Prior to installation of this change/repair it must be determined thatthe interrelationsh...	09/04/2024	Active	10081692

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081735	SWISS AIR-AMBULANCE Ltd.			AS 350 B3	NVIS Configuration R980-000665.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List R180-00063.MDL Revision BCertificationProgramme R980-00619 Revision BFlight Manual Supplement R980-00634 Revision CService Bulletin R980-00638 Revision CICA Supplement R980-00635 Revision Bor later revisions of the above listed document(s) approved/ acceptedunder the EASA system...	Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the cockpit or cabin configurationspecified in this de...	19/04/2023	Active	10081735
10081752	DOA21 LIMITED			BD-500-1A10	Cabin air exhaust mufflerInstallation of a “muffler” to reduce this noise to a more comfortablelevel by installing a valve cap and sound damping system.	The Type and OSD original product Certification Bases plus CS 25.571 atAmdt 19.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval without any impacton the noise datab...	D21.MDL- 0003 Issue P3 Master Document ListD21.AMMS-0005 Issue 2 Airworthiness Limitation Section od ICA SupplementOr later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Airbus Service Bulletin BD500-215006 – Environmental Control – Cooling –Introduction of a Water-Activated Check Valve with a Housing needs to beinstalled prior to the installationof this Muffler STC.	21/04/2023	Active	10081752
10081756	AAXICO TECHNICAL SERVICES INC.		FAA STC ST04352AT	SEE FAA APPROVED MODEL LIST	Installation of Talon Aerospace LED Replacement Navigation / PositionLights	The Certification Bases for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt 0: 25.1385, 25.1387, 25.1389, 25.1391, 25.1393, 25.1395,25.1397, 25.1529CS 25 amdt. 5: 25.1301CS 25 amdt. 13: 25...	Talon Aerospace Master Data List MDL-028-01or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	08/05/2023	Active	10081756
10081772	AIRBUS S.A.S.			A320-214	OverWing Exits Reactivation – MOD AI0242	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Summary Report SRSA-23001 Issue CAFM Supplement MOD AI0242 issue March 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/04/2023	Active	10081772
10081798	DOA21 LIMITED	REV. 4		BD-500-1A10	Introduction of a cabin Interior.Rev. 1: Typo corrected in the documentation list.Rev. 2: configuration ATT3 added to original configuration ATT1 –Limitation for OSD FCD training removed.Rev. 3: configuration ATT4 addedRev. 4: The ATT4 CAMO noted a typo error in the A220 STC 10081798. TheAFMS refere...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- As per CRI A-101 “Certification basis” issue 2.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of t...	Master Document List (ATT1) D21.MDL-0002 Issue 1Master Document List (ATT3) D21.MDL-0014 Issue 1Master Document List (ATT4) D21.MDL-0015 Issue 1Maintenance Planning Document (ATT1) D21.MPDS-0002 Issue 1Maintenance Planning Document (ATT3) D21.MPDS-0007 Issue 1Maintenance Planning Document (ATT4) D21...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Airworthiness limitations as per AFM Supplement- Airw...	29/08/2025	Active	10081798
10081801	Q.C.M. DESIGN GmbH			CL-600-2B16 (604 VARIANT)	Installation of photoluminescent floor proximity emergency escape pathmarking systemThis modification installs a photoluminescent floor path marking systemin the cabin to assist occupants in identifying the next exit in case ofdense smoke condition.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision 0 of Q.C.M. Design CertificationReport B605-QCM33-002The aircraft must be operated in accordance with revision 0 of Q.C.M.Design Aircraft Flight Manual Supplement B605-QCM33-002The aircraft must be maintained in accordance with revision 0 of Q.C.M.Design Instructi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/04/2023	Active	10081801

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081804	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT, LLC		FAA STC ST03292CH	SEE FAA AML	Activation of an 802.11 a/b/g/n WiFi System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC ST03292CH.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the ori...	- Elliott Aviation activation instructions listed on AML No. ST03292CH<(>,<)>- Master Data List, Report No. MDL-3766-111 Revision H<(>,<)>- Airplane Flight Manual Supplement, Report No. FMS-3766-111 Revision A<(>,<)>- Instructions for Continued Airworthiness, Report No. ICA-3766-111Revision A<(>,<)>...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	02/05/2023	Active	10081804
10081809	SELKIRK AVIATION Inc.		FAA STC SA01007SE	SEE FAA AML	Manufacture and Installation of Interior Fiber Glass Panels	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA1007SE.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the orig...	Selkirk Aviation Master Drawing List SA-5800, Rev. B, dated8 December2004<(>,<)>or later revisions of the above listeddocument (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	02/05/2023	Active	10081809
10081824	INFLIGHT CANADA Inc.		TCCA SA22-90 ISSUE 1	737-8	USB Power System InstallationThe modification installs an USB Power System which is a in-seat powersystem providing theUSB power to the occupants of Rows L1 thru' L32plus R2 thru' R32 Y/C passenger seats (3 x 3 arrangement) and to theflight crew in flight deck.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation shall be performed in accordance with InflightCanada /DECA Aviation Master Data List MDL21014, Revision 3The aircraft shall be operated in accordance with Inflight Canada / DECAAviation Flight Manual Supplement FMS21014, Revision 1Maintenance shall be performed in accordance with Infli...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/05/2023	Active	10081824
10081831	PT21 SOLUTIONS SAS	REV. 1		A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216	Cabin installation: 180 YC seats in cabin plus associated monumentremovals and OHB.OHSC changesRev 1: removal of 180YC Recaro 3510A Seats Installation of 180YC Recaro3530A Seats.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List 22003/MDL/001 Issue 1Master Data List 23012/MDL/001 Issue 1Instructions for Continued Airworthiness 22003/ICA/001 Issue 2Instructions for Continued Airworthiness 23012/ICA/001 Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Configuration covered by Revision 1 of this certificate: applicabilityas per 23012/MDL/001.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect up...	29/01/2024	Active	10081831
10081843	AIRBUS S.A.S.			A350-941	Airbus STC Solutions MOD AI0253 - INSTALL FITTING AND VIASAT OAEInstall fitting and VIASAT OAE.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): ESF B-302 - Vibration/ buffetingcompliance criteria for large external antenna installation.The requirements for environmentalc...	Certification Summary Report reference SRSA-2208 issue G dated 02 May2023.Modification Approval Sheet MAS n° AI0253 issue 1 dated 02 May 2023.Instructions for Continued Airworthiness reference ICA MOD AI0253 rev Bdated 27 January 2023or later revisions of the above listed document(s) approved/accept...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/05/2023	Active	10081843

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081857	AIRBUS HELICOPTERS JAPAN CO., LTD.			H160-B	Partial Modification of the Anti-collision Light including a modifiedanticollision light switch enabling the selection of “BOTH” red andwhite alternating lights in addition to theexisting "WHITE" , "RED" and“OFF” positions.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification record document No CP-SA-491 ‘Certification Record“Partial modification of the ANTICOLLISION LIGHT” ‘Revision 0 of 30November 2022Certification record document No CP-SA-483 ‘Certification Record“Partial modification of the ANTICOLLISION LIGHT” ‘Revision 2 of 30 May2022RFM supplement ‘S...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/05/2023	Active	10081857
10081861	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST04335AT-D	GIV, GV	Installation of Honeywell Display Unit Software Upgrade with SXM Weatheron the Gulfstream G-IV, GV aircraft.Rev. 1 corrects the Associated Technical Documentation section.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- CE51 2088006, Revision F titled “INDEX LIST – Honeywell DU-885Software Upgrade with Optional SXM Weather”- CE41 208A003 Rev A titled “Instructions for Continued Airworthiness – Honeywell DU-885 v1.13/ v2.03 Software Upgrade w/ optional SXM Weather(G-IV)”- CE51 208A005 Rev B titled “Instructions for C...	For G-IV/GV aircraft previously equipped with an XM weatherreceiver mfgp/n 4092743-901, the XM weather receiver must be upgraded to mfg p/n4092743-903 or upgrade to an SXM weather receiver prior to orconcurrently with DU-885/DU-885AF software upgrade.Prior to installation of this change/repair it m...	06/06/2023	Active	10081861
10081895	VIH AEROSPACE Inc.			S-92A	Search And Rescue (SAR) Grab Handles Installation.The SAR grab handles installation allows for the installation of an aftgrab handle, a top grab handle and an outside grab handle in anycombination to aid SAR crew while performing rescues.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List VS92-1719-MDL Rev. B dated Aug 18, 2022;Flight Manual Supplement VS92-1719-FMS Rev. B dated Oct 12, 2022;Instructions for Continued Airworthiness VS92-1719-ICA Rev. A dated Aug18, 2022;Operations Manual VS92-1719-OM Rev. N/R dated Apr 28, 2020;Certification Plan CP20028 Rev. 2 d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/05/2023	Active	10081895
10081915	PARC AVIATION ENGINEERING SERVICESLIMITED			737-800	189 Passenger Seating LayoutThis modification introduces a cabin layout using 63 economy classtriple seats generating a189 passenger seating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision 0 of Parc Aviation EngineeringServices Master DocumentList 737-25185-MDLMaintenanceshall be accomplished in accordance with revision 0 of ParcAviation Engineering Services Instructions for Continuous AirworthinessDocument 737-25185-ICA-01or later revisions of the...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/05/2023	Active	10081915
10081919	DOA AESGLOBAL LIMITED			A321-232 A321-231 A321-213 A321-212 A321-211	215 Passenger Seating LayoutThis modification introduces a cabin layout using economy class seatsgenerating a 215 passenger seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.869 (a), 25.1301(a)-(c), 25.1309 (a)(b), 25.1351 (a), 25.1353 (a)(b)(d)(e), 25.1431 (a)at Amendment 4;(...	The change is defined with issue 1 of AESGLOBAL Master DataListAES-321-7246.Maintenance shall be accomplished in accordance with issue 1 ofAESGLOBAL Instructions for Continuous Airworthiness Document AES-TR-3606or later revisions of the above listed document(s) approved/ acceptedunder the EASA syste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/05/2023	Active	10081919

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081921	AIRBUS S.A.S.			A350-941	Airbus STC Solutions MOD AI0252 - REMOVE GOGO OAE AND INSTALL VIASAT OAERemove GoGo Antenna and Install Viasat OAE.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): ESF B-302 - Vibration/ buffeting compliancecriteria for large external antenna installationThe requirements for environmental pro...	Certification Summary Report reference SRSA-2209 issue G dated 05 May2023.Modification Approval Sheet MAS n° AI0252 issue 1 dated 03 May.Instructions for Continued Airworthiness reference ICA MOD AI0252 rev Bdated 14 April 2023.or later revisions of the above listed document(s) approved/acceptedunde...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/05/2023	Active	10081921
10081927	AEROSPACE DESIGN & COMPLIANCE LLC		FAA SA04190NY	B300, B300C B200, B200C, B200CGT, B200GT 200, 200C, 300, 300LW	Installation of Becker Avionics DVCS-6100 Digital Audio ManagementSystem	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:23.1351 (a)(1)(2)(i) amdt 23-49; - 23.1353(h) amdt 23-49;23.1359(c) amdt 23-49; - 23.1431(a)(b) amdt 23-43;...	Master Data List B350-MDL-0050, Rev IR, dated 14 Feb 2020Aircraft Flight Manual Supplement (AFMS) B350-AFMS-0050, Rev A, dated 17Apr 2020Instructions for Continued Airworthiness (ICA) B350-ICA-0050, Rev IR,dated 06 Feb 2020or later revisions of the above listed document(s) approved/accepted onbehalf...	Prerequisite for this installation is the Garmin G1000 Avionics Suite,installed via STC SA01535WI-D.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverse...	12/05/2023	Active	10081927
10081942	AERODATA AG			B300, B300C	Installation of AD-AFIS-1210. Main items:- Integration of an electrical load shed for FIS-power supply- Installation of16 antennas mainly on the pressurized fuselage- Integrationof one operator console and one equipment console in thecabin- Integration of additional annunciator/switches	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDL-A/C-956, Rev 2Aircraft Flight Manual Supplement AFM-184, Rev 0Aircraft Maintenance Manual Supplement AMM-1191, Rev 0Master Minimum Equipment List MMEL-1015, Rev 0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Only applicable to Textron B300 aircraft S/N FL-1287The functions and performance of Mission System AD-AFIS-1210 have notbeen assessed by EASA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed chan...	16/05/2023	Active	10081942
10081943	MAGNETIC MRO AS			ERJ 190-200 STD	122 Passenger Seating LayoutThis modification introduces a cabin layout generating a 122 passengerseating configurationincluding the installation of a In-Seat PowerSupply System.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Issue 2 of Magnetic MRO Master Data ListMMRO-C-0207-MDL-01Maintenance shall be accomplished in accordance with Issue 1 of MagneticMRO AMM Supplement Document MMRO-C-0207-AMM-01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/05/2023	Active	10081943
10081947	ST ENGINEERING AEROSPACE LTD.	REV. 1		A321-271N/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216	Installation of Lavatory for passengers with reduced mobility (PRMLavatory) in A320/A321 aircraftRev. 1: Administrativeissue.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Declaration of Compliance DOA/2020/042 Rev. B- Certification Programme CP-DOA/2020/042 Rev. Cor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/05/2023	Active	10081947

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10081951	HELI-ONE (NORWAY) AS			AS 332 L1 AS 332 L	Wall Mounted Seats (mod ref. AHSE-72700)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program ref. AHSE-72702 Revision E, dated 31/03/2023Product Change Declaration ref. AHSE-72700 Revision C, dated 31/03/2023Declaration of Compliance ref. AHSE-72701 Revision C, dated 31/03/2023Flight Manual Supplement ref. H1No.I.383 dated 30/03/2023Instructions for continued airworthi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/05/2023	Active	10081951
10082016	AVIATION SPECIALTIES UNLIMITED, INC	REV. 1	FAA SR02600SE	429	Installation of a NVG Compatible Lighting and Filtration System.Revision 1 is to remove the original limitations and update the STC withall applicable references.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List (MDL), MDL-429004-3, Revision E, dated Sept 21,2023;Instructions for Continued Airworthiness, ICA-429004-4, Revision IR,dated January 1, 2016, including Aircraft Specific ICA Appendices forS/N 57037 dated May 5, 2023;RFM Supplement, FMS-429004-6, Revision A, FAA-approved on 20 Se...	1. This supplemental type certificate applies to the modelslisted aboveand only to the specific serial numbers as listed on the ASU MDL.2. Rotorcraft modified by this design change employs Night VisionImaging System lighting, commonly named NVIS lighting, which has beencertified to ensure the aircr...	25/09/2023	Active	10082016
10082017	LUFTHANSA TECHNIK AG			A321-231	EWG A321 Cabin modificationIncrease of passenger seating capacity from 200 to 226 passenger seats	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Supplemental Type Design Document STDD25-22/10M Issue 00 Rev. 00- Instructions for Continued Airworthiness A-00-23/08-ICA Issue 01 Rev.00or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	EASA STC 10065111 must be previously or concurrently installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the...	31/05/2023	Active	10082017
10082018	B/E AEROSPACE, Inc. - FSI	REV. 1	FAA STC ST02740SE	777-300ER, 777-200	Interior ReconfigurationRev. 1: adds Boeing 777-200 to the applicability list.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 issue 1: 25.613, 25.621, 25.791(a)(b)(e), 25.853(a)(c)(d)(e)CS 25 issue 6: Appendix F Part IThe requirements for envir...	1. B/E Aerospace, Inc. - FSI (B/E -FSI) Master Drawing List(MDL) C0FS054-D01, Rev. M, dated 12 May 2024;2. SupplementalInstructions for Continued Airworthiness, B/E - FSIDocument C0FS054-D15 Rev. B, dated 9 April 2024;or later revisions ofthe above listed document(s) approved/accepted onbehalf of E...	Concurrent installation of Delta Engineering EASA STC 10046995Installation of a Panasonic In-Flight Entertainment System is requiredfor all aircraft modified by this STC.See B/E -FSI MDL C0FS054-D01, Revision M, dated 12 May 2024 or later FAAapproved revisions for eligible airplane serial numbers.Pr...	04/07/2024	Active	10082018
10082020	UUDS AERO CONCEPT			SEE EASA APPROVED MODEL LIST	Oxygen Bottle Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): F02/60083304 Maximum Oxygen WorkingPressure and Pressure LimitingPerformance issue 2.- The following paragraph(s) at a later2...	See EASA Approved Model List<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	UUDS MOD UAC22M004 is a pre-requisite for this installationInstallation is limited to configurations as per below InstallationInstructions and Limitations Drawings:UAC22M004-M0002, UAC22M004-M0003, UAC22M004-M0004, UAC22M004-M0005,UAC22M004-M0006, UAC22M004-M0007, UAC22M004-M0008, UAC22M004-M0009,UA...	31/05/2023	Active	10082020

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082027	AERODATA AG			B300	Installation of Aerodata Flight Inspection System (FIS) AD-AFIS-113Main items: - Integration of an electrical load shedfor FIS - Power supply- Installation of new antennas for FIS operation- Relocation of one GPS-antenna- Integration of one operator console and one equipment rack in thecabin	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDL-A/C-949, Rev. 2Aircraft Flight Manual Supplement AFM-180, Rev. 2Aircraft Maintenance Manual Supplement AMM-1187, Rev. 2Master Minimum Equipment List MMEL-1013, Rev. IRFlight Crew Data FCD-1009, Rev. IRor later revisions of the above listed document(s) approved/acceptedunder...	Applicable to Textron Aviation B300 aircraft, S/N FL-1158The performance of Aerodata Flight Inspection System AD-AFIS-113 has notbeen assessed by EASA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously instal...	01/06/2023	Active	10082027
10082029	N AIR AVIATION INC.			PA-31	Sliding door, step, hand holds and restraint installation for sportparachuting activities. This modification kit installs the followingelements: - a sliding door; - an external hand holds; - an external jumpstep; - a restraint system for each parachutist.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): SC-O 23-div-01,is3The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the produ...	Master Data List AvSo-2205-MDL-1000 (Rev A) dated JANUARY 21, 2023AFM Supplement AvSo-2205-AFMS-PA31-1000 Rev A dated January 21, 2023In addition, ICA supplement ATS-1101-ICA-1000Rev NC dated April 11,2011 has been issued for this STCor later revisions of the above listed document(s) approved/accep...	Serial Number 31-393The aircraft must be equipped with FAA STCs SA00037SE and SA970SOPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	01/06/2023	Active	10082029
10082037	RHEINLAND AIR SERVICE GmbH	REV. 1		C90A C90GT C90GTI B300, B300C B200, B200C, B200GT, B200CGT	Installation of Hensoldt Light-Weight Crash Recorder LCR 100Rev. 1: Revision to account for the transfer from airplus engineeringGmbH to Rheinland Air Service GmbH	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List ref. MDL-2436-310000 rev 2; EngineeringWork OrderRef. EWO-2436-310000 Rev 1; Maintenance Manual Supplement Ref.MMS-2436-310000 Rev 1; Flight Manual SupplementRef. POH-2436-310000Rev. 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	23/07/2025	Active	10082037
10082053	SOCIETE AIR FRANCE S.A.			777-200	B777-200 “28J” Cabin reconfiguration and IFE Panasonic “eX2” Systemrearrangement	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s):- CRI D-001 “Installation of inflatable restraint systems” issue 4.- CRI F-GEN-11 ” Non-rechargeable Lithium Battery Installations” iss...	CAS-B777-21-002 “Change Approval Sheet” Rev 0< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	- Aeroplanes modified per this STC (i.e. with New IFE F/A Control Panel)are considered to be the same aircraft as the B777-200 with existing IFEPanasonic “eX2” system (EASA STC 10046995, FAA STC ST03178NY). Cabincrew operating aeroplanes modified per this STC must complete aircraftdifference trainin...	05/06/2023	Active	10082053
10082080	MT-PROPELLER ENTWICKLUNG GmbH			PA-28RT-201T (TURBO ARROW IV) PA-28R-201T (TURBO ARROW III)	Installation of MTV-12-D/188-53( ) Propeller on Piper PA-28R-201T seriesand PA-28RT-201T series.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31.This certificate/ approval involves a change with an impact on the noisedatab...	To be operated in accordance with MT-Propeller AFM-S Document No. E-4020Rev. 0According to MT-Propeller Master Documentation List No. E-4018 Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-4021 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4022 Rev. 0or later...	According limitation section of AFM-S.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/06/2023	Active	10082080

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082085	APTOZ EHF.			SEE EASA APPROVED MODEL LIST	Navigation – New THALES ERT550R Radio Altimeter Installation	In addition to the original Certification Basis, the followingcertification specifications has been included:CS 25.1317Amdt 25/17, CS 25.1701 Amdt 25/05, CS-ACNS Issue 4,E.TAWS.010, E.TAWS.060.The requirements for environmental protectionand the associatedcertified noise and/ or emissions levels o...	Master Data List MDL341431 IRInstruction for Continuous Airworthiness ICA341431-1 Rev. Aor later revisions of the abovelisted document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/06/2023	Active	10082085
10082089	BOEING IRELAND LIMITED	REV. 1		787-9	LATAM 787-9 Cabin ReconfigurationRevision 1 revises LATAM 787-9 Cabin Crew Seating Locations	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Data List included in document “Change / Repair Approval”, Doc.ID: BIL-00213-APP Rev.: 00- Aircraft Flight Manual Supplement, Doc. ID: BIL-00213-AFM01 Rev.: 00- Master Data List included in document “Change / Repair Approval”,Doc.ID: BIL-00261-APP Rev.: 00- Aircraft Flight Manual Supplement...	Boeing Global Service (BGS) TC Service Bulletins B787-81205-SB250283-00and B787-81205-SB250286-00, to modify the door 3from a Type ‘A’ to aType ‘C’ exit, must be implemented prior to the work carried out by BILunder this change.Boeing Global Service (BGS) TC Service Bulletins B787-81205-SB440251-00...	15/02/2024	Active	10082089
10082101	METAL INNOVATIONS INCORPORATED		FAA STC SA02763SE	208B	Installation of Metal Innovations Inc. C-208B Cargo Pod Alteration	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA02763SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. MIIDoc00307, Rev B, dated 21 November 2022;2. Master Drawing List MIIDoc00305, Rev C, dated 3 February 2023;3. Instructions for Continued Airworthiness (ICA)<(>,<)> MIIDoc00308,Rev B, dated 1 August 2022;4. Aircraft Flight Manual Supplement (AFMS) MIIDoc00385, Rev A<(>,<)>Dated 13 May 2022;or lat...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/06/2023	Active	10082101
10082103	CHICAGO JET GROUP		FAA ST04186NY	GULFSTREAM 200/ GALAXY	Installation of the Prolink/Universal UNS1-Fw FMS, CVR, Unilink andLatitude DL-150 Iridium Transceiver to include LPV, FANS-1A, ATN-81 onGulfstream Aerospace LP, Galaxy & Gulfstream 200 Aircraft	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Chicago Jet Group Master Data List C2001MDL00, Rev 1, dated06/10/2021,or later FAA approved revision.Instructions for Continued Airworthiness (ICA) GALX-ICA-0066, Rev AAirplane Flight Manual Supplements:Document No. DB2303001 Rev IR, DualUNS-1Fw Flight Management SystemDocument No. CJG NGPL 052020...	LPV not part of this approval, refer to AFMS Doc. No. DB2303001.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the...	09/06/2023	Active	10082103
10082113	ENVOY AEROSPACE, LLC		FAA STC ST04256CH	757-300 757-200PF 757-200	Retrofit Installation of Honeywell ALA-52B Radio Altimeter System	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments:CS 25 initial issue: 25.29(a)(b), 25.301(a)(b), 25.307(a) , 25.(601) ,25.603(a)(b)(c) ,25.605(a) , 25.609(a) , 25.613(a)(b) , 25.619(a)(b)(c), 25.6...	Retrofit Installation of Honeywell ALA-52B Radio Altimeter System inaccordance with CertifyNation Master Data List, Doc. No. CNI7-008MDL-00, Revision 5, dated 7 April 2023<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Imp...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/07/2023	Active	10082113

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082127	AEROMETALS INC.	REV. 1		369HS 369HM 369HE	Extended Landing Gear Skid AssemblyInstallation of FAA PMA Part Number 369XH92114 Extended Landing GearSkid Assembly replacement article.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Aerometals Instructions for Continued Airworthiness, 369XH92114 ExtendedLanding Gear Skid Assembly, AMI-15, Rev -, 1st September 1999Aerometals Report No. 061699, Revision -, 16thJune 1999, includingRevision A, 25th April 2000Or later revisions of the above listed document(s) approved/ accepted onbe...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/06/2023	Active	10082127
10082128	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT, LLC		FAA STC SA03316CH	SEE FAA AML	Activation of an 802.11 a/b/g/11/ac WiFi System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Elliott Aviation activation instructions listed on AML No. SA03316CH<(>,<)>Master Data List MDL-3830-111 Rev C, dated 22 April 2019<(>,<)>Flight Manual Supplement FMS-3830-111 RevIRInstructions for Continued Airworthiness ICA-3830-111 RevA, dated 7February 2017<(>,<)>or later revisions of the abov...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	14/06/2023	Active	10082128
10082130	BOGGI AERONAUTICS S.R.L.			427	Installation of External Payload Mount System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List 427P00100-MDL-1 Issue 1Flight Manual Supplement 427P00100-FMS-1 Issue 1Instruction for Continued Airworthiness 427P00100-ICA-10 Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/06/2023	Active	10082130
10082147	SABENA TECHNICS BGC			A321-271NX, A321-272NX A321-251NX, A321-252NX	Cabin Reconf to 12 B/C & 190 Y/CThis modification deals with a cabin reconfiguration from 240 PAX fullY/C to 202 PAX (190 Y/C & 12 B/C) onboard two A321-253NX.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amendment 4Except the following requirements: - JAR25 at Change 11 for 25.1439 and 25.144125.57...	Certification plan Ref. 41072-01-A-CP at Rev. 01Master DataList Ref. 41072-01-A-MDL at Rev 00Instructions for Continued Airworthiness Ref. 41072-01-A- ICA at Rev 00.	As a pre-requisite requirement of this change, accomplishment of thisSTC requires the completed accomplishment of the following modification:- Refurbishment of Stowage S1 & S2 andLH 8” Doghouse, as per SABENATECHNICS BGC’s Service Bulletin ref.41072-01-A-SB-F01.As a concurrent requirement of this c...	23/06/2023	Active	10082147
10082156	AIRBUS DEFENCE AND SPACE S.A.	REV. 2		A330-243	A330 Multi Role Transport Tanker (MRTT) UAE T2 (United ArabEmiratesTranche 2)(DCV0944-E and DCV0945-E)Rev. 1: Introduce the design change DCV1439-E, enabling the use of theFlightCrew Rest Compartment (FCRC).Rev. 2: Introduce the design change DCV1175-E related to MEDEVAC cabinlayouts and operation...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC D-4318-002“Air Medical Service”.- The following paragraph(s) at a later amendment: CS 25.562 InitialIssue for affected areas by th...	“Conversion Definition A330 MRTT UAE T2 STC” TE-FE-DT-220159 Issue Adated 22-MAR-2024Airplane Flight Manual and Weight and Balance Manual: - Airplane Flight Manual Supplement “EASA-Approved Model A330 MRTTUAE Tranche 2 Airplane Flight Manual" TE-FE-DT-220096 - “Limitations of Weight and Balanc...	- This STC only covers the installation of of cabin layoutsand externalaerodynamic devices (two underwing pods, boom, receptacle for refueling,antennas, fairings, in case they are equipped with) with the associatedstructural modifications, the modification of some basic aircraftsystems, the install...	10/09/2024	Active	10082156

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082167	Q.C.M. DESIGN GmbH			60	DUAL FMS UNS-1Ew Upgrade	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification report ref: L60X-QCM34-005 initial issue dated 14/6/2023;Flight Manual Supplement ref: L60X-QCM34-005-M1-AFM-ADSB Rev 0 dated23/5/2023,L60X-QCM34-005-M1-AFM-FMS Rev 0 dated 23/5/2023;Instructions for Continuous Airworthiness Ref: L60X-QCM34-005-M1-ICA Rev0 dated 9/6/2023or later revisi...	None	19/06/2023	Active	10082167
10082172	AIRWORK & HELISEILEREI GmbH			429	Y-rope for double load hook - Human External Cargo	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AEF-0562-FMS-0003 Issue 2 - Flight Manual SupplementAEF-0562-ICA-0003- Issue 1 - Instruction for continued AirworthinessAEF-0562-PCP-0004 Appendix A - Issue 4 - Master Document Listor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Pre-requisite for this installation:- Dual External Cargo Hook Kit P/N 429-706-081 (supplier: BELL Textron).- External mirror installation Kit P/N BHP 256 000 (supplier: BELLTextron).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repai...	19/06/2023	Active	10082172
10082188	AVIATION SPECIALTIES UNLIMITED, INC		FAA SR01390SE	EC 130 B4, EC 130 T2 AS 350 B, AS 350 B2, AS 350 B3 AS 350 BA	Installation of a Supplemental Lighting system for NVIS operations.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List, MDL-350004-3, revision JJInstruction for Continued Airworthiness, ICA-350004-4, revision JRotorcraft Flight Manual Supplement, RFMS-350004-6, revision Vor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implemen...	Rotorcraft modified by this design change employs Night Vision ImagingSystem lighting, commonly named NVIS lighting, which has been certifiedto ensure the aircraft is compatible with Night Vision Goggles (NVG).For this reason, any deviation from the cockpit or cabin configurationspecified in this de...	20/06/2023	Active	10082188
10082199	KENN BOREK AIR LTD.		TCCA SA02-58, ISSUE 3	DHC-6 SERIES 320 DHC-6 SERIES 300/ SERIES 310 DHC-6 SERIES 200/ SERIES 210 DHC-6 SERIES 100/ SERIES 110 DHC-6 SERIES 1	Removal of Beta Backup System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Infinion Certification Engineering Installation InstructionEO-1793-01, Issue 1 dated May 02, 2016.- Infinion Flight Manual Supplement FMS-1793-01, Issue 1 dated May 02,2016.- Infinion Maintenance Manual Supplement and Instructions for ContinuedAirworthiness MMS-1793-01,Issue 1 dated May 02, 2016or...	Applicable to Viking Air Limited DHC-6 SERIES 100, SERIES 200, andSERIES 300 equipped with PT6A-27 or PT6A-34 Engines.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will in...	21/06/2023	Active	10082199
10082203	AEROTEC & CONCEPT	REV. 2		H160-B	Installation of SAFRAN ED 410 EOS turret mobile parts with hand controlunits in cockpit and cabin.Rev. 1 introduces revised performance information in the RFM supplement.The restrictions associated with post-STC action item CAI 00-04 arelifted following the completion of the action items.Rev. 2 corr...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Programme No AE21081PCDP-01 'MOD 21081 H160 -MSN ALL FORBABCOCK INSTALLATION OF MOBILE ELECTRO-OPTICAL SYSTEM (EOS) ON H160HELICOPTER - CERTIFICATION PROGRAM / PRESENTATION DOSSIER' Rev 0 of 28Aug 2023RFM Supplement as per sections 1 to 5-1 of document No AE21081RFMS 'MOD21081 H160 FO...	Helicopters with this STC installed are restricted to category B.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repairwill introduce no adverseeffect upon the airworthiness of th...	23/02/2024	Active	10082203

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082206	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		SA26-AT, SA26-T SA227-TT SA227-DC, SA227-PC SA227-BC, SA227-CC SA227-AC, SA227-AT SA226-T(B), SA226-TC SA226-AT, SA226-T	Installation of Single/Dual Garmin GTX 3000Installation of either single or dual Garmin GTX 3000 transponder(s) replacing the existing transponder(s) and using existing XPDR antennasand XPDR antenna cables. After the exchange the GTX 3000 installationfulfill the European Airspace requirements for ADS...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-23, Amdt. 4: 23, 29,251, 301, 303, 305, 307, 337, 561, 601, 603, 605, 607, 609, 611, 613,619, 625, 771, 77...	Master Documents List, ASR-2023-002-MDL-01-00, Rev. 0FlightManual Supplement (Single Garmin GTX 3000),ASR-2023-002-FMS-05.1-00, Rev. 0Flight Manual Supplement (Dual Garmin GTX 3000),ASR-2023-002-FMS-05.2-00, Rev. 0Instructions for Continued Airworthiness (ICA), ASR-2023-002-ICA-11-00,Rev. 0Instruct...	Some enhanced surveillance airborne parameters are not available in adigital format and cannot be provided on request.Refer to AFMS (Single Garmin GTX 3000), ASR-2023-002-FMS-05.1-00, Rev. 0or AFMS (Dual Garmin GTX 3000), ASR-2023-002-FMS-05.2-00, Rev. 0Prior to installation of this change/repair it...	07/09/2023	Active	10082206
10082207	EIRTECH AVIATION SERVICES LIMITED	REV. 1		777-200, 777-300ER	Modification to business class suitesThis modification is raised to activate privacy doors, previously lockedopen, on the Jamco Venture Business Class seating in the passengercabin.Rev. 1 adds model 777-200.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.785(b)(f), 25.791, 25.803(c), 25.853(a)all at Change 14.The requirements for environmental protection...	Master Document List, 'MODIFICATION TO BUSINESS CLASS SUITES,MDL/1633-001, Issue 7,dated 4th September 2024<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	B/E AEROSPACE, Inc. - FSI EASA STC 10082018 'Interior Reconfiguration'must be installed prior to or concurrent with this STC.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repaire...	11/09/2024	Active	10082207
10082250	AEROTEC & CONCEPT			737-800	B737NG Cabin Full Pax ConfigurationCabin reconfiguration from 186Y to 189Y PAX	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	MASTER DATA LIST Doc. AE23011MDL Rev. 0Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Premod configuration according to Boeing LOPA DWG LOPA-378-2387Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the...	26/06/2023	Active	10082250
10082267	AMAC AEROSPACE SWITZERLAND AG			737-8	Interior OutfittingThe change consists of a complete cabin interior outfitting of theBoeing 737-8 with maximum 19 passengers VIP and 2 cabin crew for privateand commercial use	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: The followingparagraphs of CS-25 at Amendment 26are applicable to this change:CS25.603, CS25.788, CS25.807,C...	The change is defined with Revision C of Master Data List documentMDL-LB01-2500The aircraft shall be operated in accordance with Revision B of AirplaneFlight Manual Supplement document AFMS-LB01-2500.The aircraft shall be maintained in accordance with Revision B ofInstructions for Continued Airworth...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/06/2023	Active	10082267
10082268	DOA AESGLOBAL LIMITED			737-800	186Y Passenger Seating LayoutThis modification introduces acabin layout using 62 triple economyclass seats generating a 186 passenger seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1, 25.29 (a)(b,25.561, 25.601, 25.603 (a)-(c), 25.605 (a)(b), 25.609 (a)(b), 25.613(a)-(c), 25.619 (a)-...	The change is defined with issue 1 of AESGLOBAL Master DataListAES-737-7415MDL .Maintenance shall be accomplished in accordance with issue 1 ofAESGLOBAL Instructions for Continuous Airworthiness Document AES-TR-3707or later revisions of the above listed document(s) approved/ acceptedunder the EASA sy...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/06/2023	Active	10082268

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082291	LETECKE OPRAVOVNE TRENCIN, a.s.			L 410 UVP-E20	Installation of ADS-B OUT	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List No. 21-LOTN-895-21/MDL Rev 5; AFM Supplement No.1-EHS and ADS-B OUTMST-70B Rev 2;AFM Supplement No.2- XPDR 2 GTX 330D-ES Rev 2; AFM Supplement No.3-GTN650Xi NAV/COM/ GPSSYSTEM Rev 1;AFM Supplement No.4- Arinc ConverterLUN1794 Initial issue;AFM Supplement No. 5- TCAS II Processor...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/06/2023	Active	10082291
10082302	AKADEMISCHE FLIEGERGRUPPE BERLIN			GROB G 103 "TWIN II" GROB G 103 C "TWIN III ACRO" GROB G 103 A "TWIN II ACRO"	Twin II/III nose boom	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.	ANHANG ZUM FLUGHANDBUCH - GROB G103 -FÜR DEN BETRIEB MIT NASENMAST,REVISION 04, 05.05.2023Technische Mitteilung AFB-A.250-02 vom 21.06.2023Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Only applicable, if sailplane is prepared for installation of canardsaccording to SB 315-52/2.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	04/07/2023	Active	10082302
10082304	DASSAULT AVIATION BUSINESSSERVICES SA			FALCON 900EX (F900EX)	TAG-M372 - Varnish reworkRework of cabin interior wood items finished with varnish	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	TAG-M372-MCDL Rev. A dated 19 June 2023<(>,<) >or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	This STC constitutes an Alternative Method of Compliance (AMOC) to theaction required by EASA AD 2014-0082, sect. “Required Action(s) andCompliance Time (s)”, paragraph (1). The STC approval and AMOC is limitedto aircraft serial number 34.Prior to installation of this change/ repair it must be determi...	04/07/2023	Active	10082304
10082321	TRIEB GmbH			EB29DR EB 28 EDITION	Winglet Upgrade EB28/ EB29DR	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Trieb GmbH Drawing Number 0027-5731-00-00 - Revsion A dated 22.06.2023or later revisions of the above listed document(s)approved/ acceptedunder the EASA system.	None.	06/07/2023	Active	10082321
10082341	DOA AESGLOBAL LIMITED			737-800	186Y Passenger Seating LayoutThis modification introduces acabin layout using 62 triple economyclass seats generating a 186 passenger seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: 25.1301 (a), 25.1309(a)(b), 25.1351 (a), 25.1353(a), CS 25.1431 (a) at Amendment 4, CS25.1, 25.29 (a)(b, 25....	The change is defined with issue 2 of AESGLOBAL Master DataListAES-737-7416MDL .Maintenance shall be accomplished in accordance with issue 1 ofAESGLOBAL Instructions for Continuous Airworthiness Document AES-TR-3708or later revisions of the above listed document(s) approved/ acceptedunder the EASA sy...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/07/2023	Active	10082341
10082342	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		A321-231 A320-232	MAIN BATTERIES REPLACEMENT WITH ALTERNATE TYPE	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:EASA CS25 Amdt 2; CS 25.1, CS 25.29, CS 25.301, CS 25.302, CS 25.303, CS25.305, CS 25.307, CS 25.341, CS 25.561, CS 25.581, CS 25.601, CS25.603, CS 25.605, CS...	Engineering Order 3000097-EO Issue 1List of Certification Documents 3000097 DOC, Issue 1Continued Airworthiness 3000097-CA Issue 1AMM Supplement 3000097-MM Issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/07/2023	Active	10082342

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082346	JET AVIATION AG			A340-313	Passenger Layout Reconfiguration / The modification is verysimilar toprevious modifications completed on sister ships which had alsotransferred from Swiss to Edelweiss. These aircraft were modified underan Airbus approved SB. The intention is that this modification willfollow a similar scope, desig...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25 Amdt 27 / 25.23,25.25<(>,<)> 25.27, 25.29,25.301, 25.302, 25.303, 25.305, 25.307,25.321, 25.337, 25.34...	- Master Data List JBSL-M-03881MDL-001 Issue D- Instructionfor Continued Airworthiness JBSL-M-03881ICA-001 Issue AOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Commercial operation / Non-smoking aircraftPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	07/07/2023	Active	10082346
10082372	NOVA SYSTEMS & ENGINEERING LIMITED	REV. 1		737-800	Cabin Interior ReconfigurationThis change removes the existing two class cabin (8 B/C & 150 Y/C) to asingle class (189 Y/C) configuration.Rev. 1: correction of applicant's address	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: JAR 25.562 (c)(5) and(c)(6) at Change 13The requirements for environmental protection and the associatedcerti...	NSI-13655-01-MDL-01 Master Data List, Issue 1Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC is applicable to B-737-800 aircraft with LOPA configurationLOPA-378-3358 Rev BPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installedchange and/ or repair will introduce no adverseeffect upon t...	12/07/2023	Active	10082372
10082375	PATRIA AVIATION OY			AB412 EP AB412 AB212 412EP 412 212	Flightcell DZMx Connection/Installation of an Flightcell DZMx cellularvoice and data solution available in 3G/4G/LTE/450 MHz cellularnetworks.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	-Drawing List D-412-08-CS-07 revision D dated 27 June 2023-Installation document D-412-08-EO-25 revision D dated 27 June 2023-Instructions for Continued Airworthiness D-412-08-ICA-02 Issue 2 dated20 June 2023.- Rotorcraft Flight Manual Supplement D-412-08-RFM-15 Issue 1 Revision 0dated 26 April 2023O...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/07/2023	Active	10082375
10082376	GDC ENGINEERING GmbH			A320-232	Cabin Reconfiguration from (8BC/156EY) to 180EYThe change includes:- Installation of 180 Recaro SL3710 series EY seats-Adjustment of the PSU layout to match the new seating arrangement- Adjustment of the emergency equipment to the new cabin configuration- Installation of new Door 1 LH and RH partit...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25.562 Amdt. 27The requirements for environmental protection and the associatedcertified noise and/ or emi...	- Description Report & LOI: A320F-1DE-250000 Issue C- Master Certification Document List: CCN-A320F-MCDL Issue 01- Instructions for Continued Airworthiness Supplement: A320F-ICA-CPAIssue 02- Master Document Register: A320F-MDR-250000 IssueE- Airplane Flight Manual Supplement: 43160AR006 IROr lateru...	This STC is limited to aircraft MSN 2229, 2238 and 2428.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product...	11/07/2023	Active	10082376
10082381	NSE	REV. 1		A109S	A109S Trekker – BCT Installation.The Box of Communication and Tracking (BCT) unit is a communication andtracking equipment collecting, transmitting and storing tracking andusage data.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Plan, Document No. CP-NAF2500026-02 Issue A2 dated28/03/2025;STC Data List, Document No. SDL-00043160AA Issue B1 dated 15/04/2025;Installation Instructions, DocumentNo. MD-00043160AA Issue C2 dated15/01/2025;Rotorcraft Flight Manual Supplement, Document No. RFMS-BCT-Trekker-ENIssue 01...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/04/2025	Active	10082381

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082382	NSE	REV. 1		A109S	A109S Trekker – BS2 InstallationThe Brite Saver 2 (BS2) equipment is a Usage Monitoring System acquiringaircraft data for post-flight processing activities on the groundstation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Plan for MiC, Document No. CP-NAF2500026-01 Issue A2 dated28/03/2025;STC Data List, Document No. SDL-00044870AA Issue B1 dated 29/04/2025;Installation Instructions, Document No. MD-00044870AA Issue C2 dated28/04/2025;Rotorcraft Flight Manual Supplement, Document No. RFMS-BS2-Trekker-EN...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The approval holder shall fulfill the obligations of Pa...	07/05/2025	Active	10082382
10082384	L2 CONSULTING SERVICES Inc.			BD-700-1A11 BD-700-1A10	Aspire 400 SATCOM SystemInstallation of Aspire 400 SATCOM System on a Bombardier Globalaircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25 Amdt. 1: 25.29(a); 25.301; 25.303; 25.305 (a), (b); 25.307(a); 25.561 (a), (b), (c);25.601; 25.603; 25....	2315-BM10-AFM Rev IR2315-BM10-ICA Rev IR2315-BM10-MDL Rev Bor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/07/2023	Active	10082384
10082388	PARC AVIATION ENGINEERING SERVICESLIMITED			A320-232	180 Passenger Seating LayoutThis modification introduces a cabin layout by installing 60 economyclass triple seats generating a 180-passenger seating configurationincluding monument changes in the AFT cabin section by removing theLavatory H and Galley GA2 and installing a Lavatory E with subsequenta...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision 2 of Parc Aviation EngineeringServices Master Document List 320-25444-MDL.Maintenance shall be accomplished in accordance with Revision 0 of ParcAviation Engineering Services Instructions for Continued AirworthinessDocument 320-25444-ICA-01.or later revisions of t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/07/2023	Active	10082388
10082393	ALAMO ENGINEERING GmbH			FALCON 2000	Installation of AIRTEXT Iridium-Airtext short burst IridiumSatcom including the installation of anIridium patch antenna top of fuselage. -Passenger (T)PED connectivityvia Bluetooth. -(T)PED 5VDC Charger installed in the cabin.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.23(a)(b); CS25.301(a)(b); CS 25.303; CS 25.305(a)(b); CS 25.307(a); CS25.321(a)(b)(c)(d); CS 25.337 (c)...	MDL22A41AE-01 Master Document List Rev AICA22A41AE-01 Instructions for Continued Airworthiness Rev AFMS22A41AE-01 Flight Manual Supplement Rev Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/07/2023	Active	10082393
10082408	AERODATA AG			B300C B300	Installation of AD-AFIS-1210. Main items:- Integration of an electrical load shed for FIS-power supply- Installation of16 antennas mainly on the pressurized fuselage- Integrationof one operator console and one equipment console in thecabin- Integration of additional annunciator/switches	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDL-A/C-973, Rev 0Aircraft Flight Manual Supplement AFM-192, Rev 0Aircraft Maintenance Manual Supplement AMM-1198, Rev 0Master Minimum Equipment List MMEL-1017, Rev 0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Only applicable to Textron B300 aircraft S/N FL-1296The functions and performance of Mission System AD-AFIS-1210 have notbeen assessed by EASA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed chan...	19/07/2023	Active	10082408

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082409	AIRBUS HELICOPTERS ESPANA, S.A.			EC135 T3 EC135 P3	Installation of an equipped Operator Mission Console in accordance withCompliance Record Document 2237M-EC135P3T3	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Rotorcraft Flight Manual Supplement SFLM-H135P3H-2023-01 NormalRevision 01-Rotorcraft Flight Manual Supplement SFLM-H135T3H-2023-01 NormalRevision 01-Compliance Record Document 2237M-EC135P3T3 Revision A-Instructions for Continued Airworthiness are given in CustomisationManual CM H135 OCM EN 864003...	Limited to helicopters with Helionix cockpit variantPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	19/07/2023	Active	10082409
10082415	AMAC AEROSPACE SWITZERLAND AG			A318-112	Replacement of Large MonitorsThe change covers the mechanical replacement of 6 large monitorsinstalled in the passengercabin with new monitors.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: The following paragraphof CS-25 at Amendment 27 is applicable to this change: CS25.788The requirements for en...	The change is defined with Revision B of AMAC Master Data List documentMDL-IV03-4420.The installation must be accomplished in accordance with Revision A ofAMAC Engineering Order document EO-IV03-4420.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/07/2023	Active	10082415
10082430	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS			747-400F	Upgrade of Honeywell MCS-6000 SATCOM to MCS-7000 by replacing theSatellite Data Unit (SDU).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: At Amdt 4: 25.23;25.29; 25.305; 25.1301; 25.1307(d); 25.1309; 25.1333 (c); 25.1351 (a);25.1353 (a); 25.13532...	Master document list 01634-EAS-A-MDL Revision F dated July 19th<(>,<)>2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to MCS SATCOM system connected to high gain antennaonly asreferred in paragraph 2.2 of Supplemental Type Design 01634-EAS-A-STD-01rev E dated July 19th, 2023Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpr...	20/07/2023	Active	10082430
10082436	TEAM J.A.S., Inc.dba PMA DESIGN AND MANUFACTURING		FAA STC SA04550AT	DHC-6 SERIES 400 DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Main Wheel and Brake Assembly for the Viking Air DHC-6 Series aircraft	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, PDM-MDL0330, dated 24 August 2022<(>,<)>Instructions for Continued Airworthiness (ICA), PDM-ICA109, Rev A, dated26 July 2022<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is applicable to all serial numbers for the Vi...	27/07/2023	Active	10082436
10082453	AIRFILM CAMERA SYSTEMS, INC		FAA STC SR02840LA	505	Installation of Airfilm Utility Mount	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List AFM-505-210, Revision B, dated 12 May 2022<(>,<)>Payload limitations, Sections 2.0 and 4.0 of Installation InstructionsAFM-505-206, Revision B, dated 12 May 2022<(>,<)>Airfilm Rotorcraft Flight Manual Supplement AFM-505-205, Revision N/C,dated 6 March 2023<(>,<)>Instructions for2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/07/2023	Active	10082453

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082454	GDC ENGINEERING GmbH			A320-232	Cabin reconfiguration 8BC/162EY	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master certification document list CCN-A320J-01-MCDL Issue 2Master document register A320J-MDR-250000 Issue AMaster document register – AAR 44542_Doc_Master Issue IRICA & Operator Manual Supplement A320J-ICA-BAV issue 00or later revisions of the above listed document(s) approved/acceptedunder the...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/07/2023	Active	10082454
10082458	DRF STIFTUNG LUFTRETTUNGG EMEINNUETZIGE AG			EC135 P3, EC135 T3	Installation of lightweight flight recorder Hensoldt Lightweight CrashRecorder SferiRec LCR100 in accordance with Master Document ListMD-135-31-32-00001	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-27 Amendment 10for 27.1; 27.21; 27.25; 27.27; 27.29; 27.251; 27.301; 27.303; 27.305;27.307; 27.561; 27.6...	- Master Document List MD-135-31-32-00001 Revision 01- Compliance Checklist CC-135-31-32-00001 Revision 00- Flight Manual Supplement FMS 10-DRF-068 Revision 01- Instructions for Continued Airworthiness CA-135-31-32-00001 Revision01or laterrevisions of the above listed document(s) approved/ acceptedu...	Limited to helicopters with Helionix cockpit variantNVIS compatibility is ensured because any LED on the SferiRec LCR100 isswitched off by means of a configuration file. The additionallyinstalled status indicator is NVIS approved.This STC supports the showing of compliance to Commission Regulation(E...	26/07/2023	Active	10082458
10082466	LIFEPORT, LLC		FAA STC SA00272LA	PC-12/47 PC-12/45 PC-12	Installation of a Patient Loading Utility System (PLUS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Drawing List (MDL) 520-1200, Revision DE, dated 20 July 2020<(>,<) >Instructions for Continued Airworthiness (ICA), DocumentEGR-505-12, Revision F<(>,<)> dated 26 August 2020<(>,<) >Airplane Flight Manual Supplement No. EGR-505-11, Revision F, dated 15September 2020< (>,<)>or later revisions ofb...	For installations in accordance with LifePort, Inc. DrawingNo. 0000-0113-01-01 orCF1-282, as listed on the MDL.Prior toinstallation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce...	27/07/2023	Active	10082466
10082469	LEARJET Inc.	REV. 2	FAA ST02015WI	BD-700-1A10, BD-700-1A11	Installation of replacement Control Display Units and PM-CPDLC upgradeRev. 1 – Include CVR datalink recording capabilitiesRev. 2 - add the -004 MDL configurations	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: 25.1457, 25.1459 and25.1460 at CS-25 Amendment26 and CS-ACNS rev 5.The requirements for environmental prot...	Master Document List BAS67015046, Revision (C), dated 10 May 2023;For MDL BAS67015046-001 and -002 configurations:Airplane Flight Manual Supplement BAS67045020, Revision (NC), dated 26May 2023;Instructions for Continued Airworthiness, BAS67015046-ICA-1, Revision(--), dated 7 April 2023;For the MDL B...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/05/2025	Active	10082469
10082475	AIRBORNE TECHNOLOGIES GmbH			CN-235-300	STC-AT-182, CASA CN235 iSAR ProvisionThe aircraft is prepared for the installation of the iSAR mission systemwith Structural reinforcement for camera and antenna installation,installation of iSAR mission equipment including exchange of existingmission display, mission equipment power distribution an...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplement to AMM, Doc. No. STC-182-G-AMM, Rev. 1Installation Instructions, Doc. No. STC-182-G-II, Rev. 0Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	OEM Major Change CN235-300 SM01 Version – Installation of FLIR, Radar,SLAR and other miscellaneous equipment has to be installed prior thisSTC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed chan...	28/07/2023	Active	10082475

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082476	SABENA TECHNICS BGC	REV. 3		ERJ 170-200 STD ERJ 170-100 STD ERJ 170-100 LR, ERJ 170-200 LR	Mounting device and power supply connection for PIVOT EFB solutions onE170- Configuration 1: installation with sliding rail- Configuration 2: installation without sliding railRev 1: Technical Documentation list amended.Rev 2: CertificationBasis amended.Rev 3: Amended inspections interval on supplem...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): D-137 “Mitigation of flight deck firesoriginating from lithium batteries that are not part of the aircraftdesign” issue 4.- The follow...	- Master Data List, Ref. 10007-01-A-MDL-R02 dated 30 Apr 2024- Airplane Flight Manual Supplement, Ref. 10007-01-A-AFMS-R01 dated 19Jul 2023- Instructions for continued airworthiness, Ref. 10007-01-A-ICA-R02dated 29 Feb 2024- Master MinimumEquipment List Supplement Document, Ref.10007-01-A-MMELS-R00...	Limitations as per §3 of Airplane Flight Manual Supplement documentreferenced above.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	03/05/2024	Active	10082476
10082477	NOVA SYSTEMS & ENGINEERING LIMITED			A330-243 A330-223 A330-203 A330-202 A330-201	Cabin Reconfiguration to 18 B/C & 247 Y/C seats.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List ref NSI-14160-01-MDL-01 issue 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/07/2023	Active	10082477
10082482	PARC AVIATION ENGINEERING SERVICESLIMITED			737-8	189 Passenger Seating LayoutThis modification introduces a cabin layout by installing 63 economyclass triple seats generating a 189-passenger seating configurationincluding associated changes in the cabin to adapt to the new layout.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.562 (c)(5) and(c)(6), 25.785 (h)(1) and (h)(2) at Amendment 11The requirements for environmental protec...	The change is defined with Revision 0 of Parc Aviation EngineeringServices Master Document List 737-25186-MDL.Maintenance shall be accomplished in accordance with Revision 0 of ParcAviation Engineering Services Instructions for Continued AirworthinessDocument 737-25186-ICA-01.or later revisions of t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/07/2023	Active	10082482
10082483	AVIATION SUPPORT GmbH			MD900/MD902 MD900	Installation of CHARM II Gas Detection System (Generation II)	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	-Projektbeschreibung, ASE-91408, CHARM 2 - Gas Detection System, MD900,Doc. No. PB-ASE-91408, Rev. 1-4 dated 28.04.2023-Liste der gültigen Dokumente, ASE-91408, CHARM 2 – Gas DetectionSystem, MD900, Doc. No. MDL-ASE-91408, Rev. 0-1 dated 18.07.2023-Flight Manual Supplement, Installation of CHARM IIS...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/07/2023	Active	10082483
10082501	MT-PROPELLER ENTWICKLUNG GmbH			695 690D 690C 690B 690A 690	Installation of MTV-37-1-E-C-F-R(G)/ CFRL228-352( ) Propeller on TwinCommander Aircraft Models 690( ) and 695( ).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase...	According to MT-Propeller Master Documentation List No. E-3883 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-3885Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-3886 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3887 Rev. 0or later...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	31/07/2023	Active	10082501

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082502	DOA AESGLOBAL LIMITED			F28 MARK 0100	ACTIVATION OF BLUEBOX WIFI SYSTEM	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25.869(a), 25.1301(a)-(c), 25.1309(a)(b), 25.1353 (a)-(e), 25.1431(a)(c)(d) atAmendment 4; CS 25.1, 25.601,...	Master Data List AES-100-6609MDL issue 2Instructions for Continued Airworthiness Report AES-TR-3559 Issue 1AES FLIGHT MANUAL SUPPLEMENT No. 104 ISSUE 01or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The Airplanes must be modified previously according to Minor ChangeAES-100-6608Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	31/07/2023	Active	10082502
10082523	MECAER AVIATION GROUP S.p.A.			AW139	AW139 EMS MAG INTERIORS P/N 6A3M0000X001001This change consists in the modification of the helicopter main cabin toallow use of the helicopter as EMS platform in four differentconfigurations.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Rotorcraft Flight Manual Supplement 6A3MRFM-1-1 Issue 0, Rev. 0- Instructions for Continuing Airworthiness Document 6A3MWNM-2-1 Issue 0Rev. 0- MMEL Supplement 6A3MMML-3-1 First Issue- Certification Programme Report 6A3M0000N003 revision E- Configuration Description Report 6A3M0000N001 Revision G--...	The AW139 EMS MAG INTERIORS P/N 6A3M0000X001001 is compatible with theAW139 Long Nose configuration only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no ad...	02/08/2023	Active	10082523
10082525	HARTZELL ENGINE TECHNOLOGIES, LLC.		FAA STC SA11137SC	SEE FAA AML	Installation of Plane-Power ALT-FLX alternator in small aeroplanes.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions, Drawing No. 17-1001, dated 24 November 2011<(>,<)>Aircraft Engine Alternator Parts List, Drawing No. 17-0000, dated 24November 2011<(>,<)>Instructions for Continued Airworthiness are contained in Drawing No.17-1001<(>,<)>FAA Approved Model List (AML) No. SA11137SC, dated 4...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is only valid for small aeroplane types and mo...	02/08/2023	Active	10082525
10082526	HARTZELL ENGINE TECHNOLOGIES, LLC.		FAA STC SA11137SC	SEE FAA AML	Installation of Plane-Power ALT-FLX alternator in rotorcraft.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Installation Instructions, Drawing No. 17-1001, dated 24 November 2011.Aircraft Engine Alternator Parts List, Drawing No. 17-0000, dated 24November 2011<(>,<)>Instructions for Continued Airworthiness contained in Drawing No. 17-1001<(>,<)>FAA Approved Model List (AML) No. SA11137SC, dated 4 April 202...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is only valid for rotorcraft types and modelsa...	02/08/2023	Active	10082526
10082540	SABENA TECHNICS BGC	REV. 1		A321-253N/-271N/-272N A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212	The modification consists in the reconfiguration of the cabin from 220PAX to 212 PAX (4BC + 208 YC)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25 at Amendment 4:CS 25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341,25.365, 25.471,...	Certification Plan 41135-01-A-CP-R01Master Data List 41135-01-A-MDL-R00Instructions for Continued Airworthiness 41135-01-A-ICA-R00	As a prerequisite of this change, the installation of SABENA TECHNICSBLAGNAC (SNT-BGC) SB 41006-01-A-SB (A321-Cabin Reconfiguration from 195PAX (12 B/C+183 Y/C) to 220 PAX (220 Y/C)) is needed.The technical content of the SB is approved under the authority ofDesign Organisation Approval No. EASA.21J...	04/08/2023	Active	10082540

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082544	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A, 525B	Installation of S/W 6.72 Update for Single Garmin GTN 725 /GTN 750 oralternatively installation of Single Garmin GTN 725(Xi) / GTN 750(Xi)unit and optional Garmin Flight Stream FS 510	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23, Amdt. 4: 23, 29, 251, 301, 303, 305, 307, 337, 365, 561, 571,601, 603, 605, 607, 609, 611, 613, 625...	- Master Documents List, ASR-2022-037-MDL-01-00, Amdt.00, 13.06.2023- AFMS (Honeywell SPZ-5000), ASR-2022-037-FMS-05.1-00, Amdt. 00,12.06.2023- AFMS (Collins Pro Line 21), ASR-2022-037-FMS-05.2-00, Amdt. 00,12.06.2023- Instructions for Continued Airworthiness, ASR-2022-037-ICA-11-00,Amdt.00, 12.06.202...	Design data and documents already EASA approved with STC 10042753, Rev.0 remain valid if legacy Garmin GTN 725 / GTN 750 units are installed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change...	04/08/2023	Active	10082544
10082546	MT-PROPELLER ENTWICKLUNG GmbH			210M, 210N, 210R 210H, 210J, 210K, 210L 210D, 210E, 210F, 210G	Installation of MTV-9-D/200-58( ) Propeller on Textron Aviation Inc.210( ) Series.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS-36 Amdt 6; FAR 36 Amdt 36-31This certificate/approval involves a change with an impact on the noisedatabase...	According to MT-Propeller Master Documentation List No. E-3943 Rev. 1To be operated in accordance with MT-Propeller AFM-S Document No. E-3945Rev. 1To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-3946 Rev. 1To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3947 Rev. 0or later...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	04/08/2023	Active	10082546
10082548	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS	REV. 1		737-8	KA-BAND SATCOM Installation on B737-8MAXKA-BAND SATCOM installation is composed of large antenna installationand LRUs in Cabin. The modification consists in the installation with noactivation of installed equipment.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-01: Vibration/Buffeting compliancecriteria for Large external Antenna installation.The requirements for environmental pr...	- AFM supplement Ref: 01577-EAS-D-AFM-01 issue B dated 31 July 2023- Master Data List Ref: 01577-EAS-D-MDL issue B dated 03 August 2023- ICA supplement: 01577-EAS-D-ICA-01 issue Bdated 28 July 2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aeroplane must be operated in accordance with AFM supplement01577-EAS-D-AFM-01 issue B, and maintained in accordance with ICAsupplement: 01577-EAS-D-ICA-01 issue B.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any other...	08/08/2023	Active	10082548
10082558	AIRFORCE TURBINE SERVICE Ltd.dba AIRFORCE TURBINE SERVICE	REV. 1	FAA STC SE7677SW	PT6A-15AG, PT6A-27, PT6A-28	Modification of the Pratt & Whitney Canada PT6A-27, PT6A-28or PT6A-15AGto the PT6A-34 configurationRev. 1: Correction of FAA STC Number	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Airforce Turbine Service Report No.001, Revision G, dated 28 December1989<(>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordancewith the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/02/2025	Active	10082558
10082583	AIRCRAFT SYSTEMS AND MANUFACTURING,Inc.	REV. 1	FAA STC SA04548AT	SEE FAA AML	Installation of an Avionica, LLC Quick Access Recorder/DataConcentratormodel avRDC MAX (QAR) P/N804-1250-32 and optional Avionica, LLC Cellular Module LTE (avCM LTE)P/N 650-0100-05Rev. 1 is a transfer of STC from ARCHEION HOLDINGS, L.L.C.to AIRCRAFTSYSTEMS AND MANUFACTURING, Inc.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Master Data List 221590-MDL, Revision A, dated 16 September2022<(>,<)>Archeion Holdings Instructions for Continued Airworthiness 221590-ICA<(>,<)>Revision IR, dated 28 June2022<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASAin accordance with the Technica...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is valid for aircraft types and models approve...	05/05/2025	Active	10082583

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082584	AVIATION SPECIALTIES UNLIMITED, INC	REV. 1	FAA SR01476SE	A109S	NVG Supplemental Lighting and Filtration System.Revision 1 is to remove the original limitations and update the STC withall applicable references.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List (MDL), MDL-119004-3, Revision CD, dated29 May 2024;Instructions for Continued Airworthiness, ICA-119004-4, Revision H,dated 09 July 2020, including Aircraft Specific ICA Appendices for S/ N22719 dated 26 July 2023;RFM Supplement, EASA-FMS-119004-6, Revision IR, dated 16 Apr 2024;...	1. This supplemental type certificate applies to the A109S helicoptermodel equipped with Trekker kit and only to the specific serial numbersas listed on the ASU MDL.2. Rotorcraft modified by this design change employs Night VisionImaging System lighting, commonly named NVIS lighting, which has beenc...	03/06/2024	Active	10082584
10082585	ENFLITE, LLCd/b/ a ENFLITE		FAA STC ST10505SC	BD-700-2A12 BD-700-1A11 BD-700-1A10	Installation of an Enflite Model 42100 Pocket Door between the forwardgalley and the passenger compartment, without theelectric door optioninstalled	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Enflite, Inc., Master Document List Number MDL42100-1, Revision A, dated24 February 2006<(>,<)>Midcoast drawing 58MC0001 listed in Enflite Inc., Drawing NBR42100-I,Revision A, dated 28 October 2005<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accorda...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Door finish requirements are determined by the installe...	08/08/2023	Active	10082585
10082589	THALES AVIONICS Inc.		FAA STC ST02809LA	737-900ER 737-900 737-800 737-8 737-700 737-600	Installation of the upgraded Thales Radio Altimeter Transceiver Units,ERT5	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt 17: 25.1317(a)(1)(2)The requirements for environmental protection and the associatedcertified noise and/ or emiss...	1. Thales Avionics, Inc. Index List Drawing Number 259263, Revision A,dated 22 June 2023;2. Master Drawing List 737 Radio Altimeter Transceiver 188409-MDL Rev C;or later revisionsof the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProced...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/08/2023	Active	10082589
10082590	GULFSTREAM AEROSPACE CORPORATION		FAA ST04331AT-D	GULFSTREAM 200/ GALAXY	Installation of a Dual Universal Avionics System Corporation UNS-1EwFlight Management System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): -,,FAA Special Condition (SC) 25-667-SC,Gulfstream Aerospace LP, Model Gulfstream 200 Airplane; Non-RechargeableLithium Battery Insta...	Gulfstream Index List CEB11188005, Revision “A“Airplane Flight Manual Supplement CEB1118M004, Revision AInstructions for Continued Airworthiness, CEB1118A005, Revision COr later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implementati...	This STC is limited to Serial Numbers 004 through 051 of GulfstreamAerospace LP, Galaxy/Gulfstream 200 aircraft.CEB11188010 Configuration List is not applicable for installation onEASA registered aircraft.Prior to installation of this change/ repair it must be determined thatthe interrelationship bet...	09/08/2023	Active	10082590
10082593	AEROSPACE DESIGN & COMPLIANCE LLC		FAA STC ST04201NY	S550 560 550	Installation of ENode Engine Data Acquisition Unit and IONode DigitalData Recorder	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Aerospace Design & Compliance, LLC.<(>,<)> (1) Master Data List<(>,<)> C560-MDL-0071, Revision IR<(>,<)>dated 25 November 2020<(>,<)>(2) Instructions for Continued Airworthiness (ICA),C560-ICA-0071, Revision IR, dated 13 November 2020<(>,<)>or later revisions of the above listed document (s) approved/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is applicable to all serial numbers 550 (Citat...	10/08/2023	Active	10082593

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082598	PROTOPLANE SPECIAL MISSION AIRCRAFT			1900D	Attendant seat installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Drawing List, document PP-145-DL-01Supplement to Aircraft Flight Manual, document PP-145-AFM-01Instructions for Continued Airworthiness, document PP-145-ICA-02or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to Textron Beechcraft aircraft 1900D S/Ns UE.The aircraft must be equipped with:- the chest P/N 94-001-04- the oxygen mask P/N 129-384005-3, its cover P/N 129-384018-49 and itssurrounding part P/N 129-384018-73- the oxygen tubes P/N 101-380049-13Prior to installation of this change/ repair it...	10/08/2023	Active	10082598
10082599	TÄBY AIRMAINTENANCE AKTIEBOLAG			SAAB 2000	GPS Landing System and ADS-B out informationThis modification provides precision approach (LPV) ILS Look alikeguidance on the SAAB 2000 together with GPS information to existingTransponder System for ADS-B out information	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 Amdt 2: 25.1;25.21; 25.29; 25.301; 25.303; 25.305; 25.307; 25.321; 25.333; 25.337;25.341; 25.561; 25.601...	-AFM supplement: 321006-C-AM-3461-002-07 Issue 07 dated 31st May 2023-MDL ref: 321006-C-DL-3461-001-02 dated 08th August 2023-ICA supplement: 321006-C-CA-3461-001-01 Issue 01 dated 22nd April 2022-MMEL supplement: 321006-C-ME-3461-001-01 Issue 01 dated 22nd February2023or later revisions of the abov...	The aeroplane must be operated in accordance with AFM supplement ref: :321006-C-AM-3461-002-07 Issue 07 and maintained in accordance with ICAsupplement ref: 321006-C-CA-3461-001-01 Issue 01 dated 22nd April 2022Prior to installation of this change/repair it must be determined thatthe interrelationsh...	10/08/2023	Active	10082599
10082600	CAVOK			B300	GPS antenna installation/removal	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Service Bulletin, document 350-115-SB-007 Issue B, dated August 8, 2023<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/08/2023	Active	10082600
10082603	SCANDINAVIAN AVIONICS DESIGN ApS			S-92A	Honeywell RDR-7000 Weather Radar installation as replacement of theexisting Primus-70XA weather radar.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-29 Amdt 2paragraphs:CS 29.1, CS 29.21, CS 29.29, CS 29.251, CS 29.301, CS 29.303, CS 29.305,CS 29.307, CSC...	Drawing List, Document No. 3000104-DL Issue 1 dated 27.09.2022;Engineering Order and Certification Program, Document No. 3000104-EOIssue 1 dated 08.08.2023;Compliance Record, Document No. 3000104 COR Issue 1 dated 27.07.2023;RFM Supplement, Document No. 3000104-AM A Issue 1 dated 10.07.2023;Instruct...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/08/2023	Active	10082603
10082608	BOEING IRELAND LIMITED			737-8	737-8: Two to one class 189 passenger USB powered seatsChange from a two class, 174 passenger cabin, to a full economy 189passenger cabin.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, '737-8: Two to One Class 189PAX USB PoweredSeats', BIL-00241-APP, Revision 01, dated 15th August 2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/08/2023	Active	10082608

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082610	ALPINE AEROTECH LP		TCCA SH22-40	AS 355 F2, AS 355 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1 AS 350 BB AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Bear Paw Kit Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Alpine Aerotech LP (AAL) Master Data List AAL-390-034-001, Rev B dated22March 2023, TCCA approved.AAL Installation Instruction AAL-390-035-001, Rev A dated 02 February2023, TCCA approved.AAL Flight Manual Supplement AAL-390-035-401, Rev NIdated 22 March 2023 (AS350 Series) or AAL-390-035-402, Rev NI...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/08/2023	Active	10082610
10082618	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A319-115	New IFE installation & CMS upgradeReplacement of obsolete equipment of the CMS/IFE with updated Astronicsequipment and installation of electrical provision for the cabinsecurity system.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS25 Amdt 27:25.1319; 25.788(b).The requirements for environmental protection and the associatedcertified n...	MDL referenced JCAERO/ MDL/0920 issue 01 dated 14 AUG 2023<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- The installation of the configuration covered by the STC ST10898SC-Dis a prerequisite- The STC ST10898SC-D must be validated by EASA before entry intoservice in the register of an EASA member state.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenp...	18/08/2023	Active	10082618
10082619	FOKKER SERVICES B.V.			737-900ER 737-900 737-800 737-700 737-600	Activation of SBAS system on B737NGWith MCP/CPR/CRR-0472 a de-activated SBAS system was introduced with:-the installation of structural provisions for two GNSS receivers-the installation of two GNSS receivers-the installation of two GNSS splitters/power dividers (includingstructural provisions)-thee...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS ACNS.C.PBN.205, CSACNS.C.PBN.210, CS ACNS.C.PBN.215, CS ACNS.C.PBN.2130, CSACNS.C.PBN.2140, CS ACNS.C.PBN....	-Certification Plan Report CPR-0473 issue 3-Compliance Record Report CRR-0473 issue 1-C<(>&<)>A Sheet for AFM B737-SBAS-AFM-S-001 issue 3-C<(>&<)>A Sheet for MMEL B737-SBAS-MMEL-S-001 issue 3or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC must be installed in conjunction with Fokker Servicesmodification ref CPR/ CRR-0472.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect u...	18/08/2023	Active	10082619
10082620	S-TEC CORPORATION		FAA STC SA09766DS	PA-39 PA-30	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09766DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List ST-988-MDL-0001, Revision -, dated 24 May 2023;2. Airplane Flight Manual Supplement ST-988-AFMS-0001, Rev.-, dated 25May 2023;3. Instructions for Continued Airworthiness ST-988-ICA-0001, Rev. -,dated 13 April 2023;or later revisions of the above listed document(s) approved/accept...	This STC is applicable to all serial numbers for Piper Aircraft, Inc.models PA-30 and PA-39.Also eligible on the above models when modified per STC SA727SW (tiptanks) and for which EASA validation is required.Prior to installation of this change/repair it must be determined thatthe interrelationship...	21/08/2023	Active	10082620
10082622	LEARJET Inc.		FAA STC ST01134WI	BD-700-1A10	Installation of metallic window blanks for direct replacement of factoryinstalled windowpane assemblies	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Millennium Concepts Master Data List (MDL) No. 3321-MDL015,Rev. A,dated 21 December 2002<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The window plug installation kit is not eligible for in...	01/09/2023	Active	10082622

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082623	PILATUS BUSINESS AIRCRAFT, Ltd.		FAA STC SA01104DE	PC-12/47E	Installation of a Send Solutions in Flight Entertainment System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List, Doc No. 2E-2203-01-0001, Rev "-", dated 22 May2023<(>,<)>Instructions for Continued Airworthiness (ICA), Document No. 2E-2203-64-0000, Revision "-"<(>,<)>dated 3 March 2023<(>,<)>Doc. No. 2E-2203-65-0000, Flight ManualSupplement, revision "-", dated4 April 2023<(>,<)>or later r...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/08/2023	Active	10082623
10082626	S-TEC CORPORATION		FAA STC SA09767DS	BN2T BN2B-20, BN2B-26 BN2A-2, BN2A-20 BN2A-26, BN2A-6, BN2A-8	Installation of an S-TEC 01326 Digital Flight Control System (DFCS)	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA09767DS.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	1. Master Data List ST-989-MDL-0001, Revision -, dated 18 May 2023;2. Airplane Flight Manual Supplement ST-989-AFMS-0001, Rev.-, dated 18May 2023;3. Instructions for Continued Airworthiness ST-989-ICA-0001, Rev.-,dated 13 April 2023;or later revisions of the above listed document (s) approved/accepte...	This STC is applicable to all serial numbers for Britten-Norman AircraftLtd. models BN-2A-2, BN-2A-6, BN-2A-8, BN-2A-20, BN-2A-26, BN-2B-20,BN-2B-26, and BN-2T.Eligible on Britten-Norman Aircraft Ltd. model BN-2A-6 only whenmodifications NB/M/430 and NB/M/631 are installed.Prior to installation of t...	21/08/2023	Active	10082626
10082654	CAVOK			AVANTI II	P180 ADS-B OUT Installation with GTX 3000	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: 23.25; 23.29; 23.251;23.301 a) b) c); 23.303; 23.305 a) b); 23.307 a); 23.321 a); 23.341 a)c); 23.365 a) d)...	DCMR no.180-003-CTF-002, Issue B;AFMS no. 180-003-HBK-012, issue C;AMMS no. 180-003-HBK-010, Issue Bor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This modification is not compatible with aircraft equipped withTSO-C119a TCAS units.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the...	22/08/2023	Active	10082654
10082658	DIGISKY S.R.L.			P2006T	Installation of LIDAR system	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List Doc. TPS2006-0100-Mdl-01 issue 1, dated 31July 2023Aircraft Flight Manual Supplement Doc. TPS2006-0100-AFMS-01 issue 1dated 31 July 2023or later revisions of theabove listed document (s) approved/ acceptedunder the EASA system.	As a prerequisite for the installation of the Lidar system,the TecnamP2006T a/c must be equipped with: Big cabin hatch(mod 2006/207),Converter Box (mod 2006/204), Supporter frame (mod 2006/297) and TrimbleAV39 GNSS Antenna installed i.a.w Construzioni Aeronautiche TecnamSB339-CS.Prior to installat...	24/08/2023	Active	10082658
10082664	SABENA TECHNICS BGC			SA 319 B, SE 3160 SA 315 B, SA 316 B, SA 316 C	STICK SWITCH GUARD INSTALLATION	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: Orignal certificationbasis for the original product + FAR 27.1501 (Amdt Init), 27.1529 (AmdtInit), 27.1581T...	CERTIFICATION PLAN 2139-01-A-CP Rev3 issued 18/07/23MASTER DATA LIST 2139-01-A-MDL Rev 0 issued 21/07/23ROTORCRAFT FLIGHT MANUAL SUPPLEMENT N° 2139-01-A-RFMS-F01 Rev3 issued21/07/23SUPPLÉMENT AU MANUEL DE VOL N° 2139-01-A-RFMS-F00 Rev2 issued 21/07/23.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/08/2023	Active	10082664

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082665	PAL AEROSPACE LTD.	REV. 1	TCCA A-LSA22-119/D	DHC-8-106 DHC-8-102	Cabin Observer Window InstallationRevision 1: Addition of model DHC-8-106 with SN 275, 314 and ofconfiguration 002-2004121-003/-004 for SN 38	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1529 at InitialIssueThe requirements for environmental protection and the associatedcertified noise and...	Installation shall be performed in accordance with DECA AviationEngineering Limited Master Data List MDL20061-56, Revision 2Maintenance shall be performed in accordance with DECA AviationEngineering Limited Instructions for Continued AirworthinessICA20061-56, Revision 2Compliance with Airworthinessm...	Limited to Serial Number 028, 038, 275 and 314Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	16/02/2024	Active	10082665
10082666	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04276AT	757-300 757-200	Installation of an IRIDIUM Satellite Communications System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 0: 25. 29, 25.303, 25.561, 25.601, 25.603, 25.771,25.773,25.1431, 25.1529, 25.1541CS 25 amdt. 1: 25.305, 25.30...	Master Drawing List 215125-MDL, Revision G, dated 1 August 2023<(>,<) >Airplane Flight Manual Supplement for the Rockwell Collins IRT-2110/2120IRIDIUM Communication System, 215125-FMS, revision IR, dated 30September 2016< (>,<)>Instructions for Continued Airworthiness (ICA), Avionics Support GroupDocu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/09/2023	Active	10082666
10082678	AVIONITEC AG			340A	Installation of a TAS Top Antenna Garmin GA 58;Exchange of the existing WX Radar System by a Garmin GWX 75 WX RadarAntenna/Receiver Unit.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: § 23.867, 23.1306 and23.1308 of CS 23 Amdt 4.The requirements for environmental protection and the associat...	Certification Program: Doc. No. 14304, dated 22.08.2023Master Document List: Doc. No. 14304-017, Dated 23.08.2023Airplane Flight Manual Supplement: Doc. No. 14304-017, Dated 10.05.2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This change is limited to Serial Number 340A-0921This change requires the installation of:- Garmin Integrated Electronic Flight Display System G500 TXI installedaccording to EASA STC 10064794;- Garmin TAS System GTS 800 installed accordingto EASA STC 10067437.Prior to installation of this change/re...	29/08/2023	Active	10082678
10082682	PATRIA AVIATION OY			412EP	NVIS Approval	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Drawing List D-412-08-CS-03 revision E dated 13 July 2023.- Installation document D-412-08-EO-21 revision E dated 13 July 2023.- Instructions for Continued Airworthiness D-412-08-ICA-03 Revision 1dated 2 June 2023.- Rotorcraft Flight Manual Supplement D-412-08-RFM-11 Issue 1 Revision 0dated 2 June...	- The Installation of this modification by third persons issubject towritten permission of the approval holder and disposal of the approvedappropriate documentation.- Category A operations are prohibited when using NVG.Prior to installation of this change/repair it must be determined thatthe interr...	30/08/2023	Active	10082682
10082683	PATRIA AVIATION OY			412, 412EP	Medical Kit Installation / Provisions for the installation of the oxygenbottle, life raft and stretcher.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Drawing List D-412-08-CS-04 revision L dated 13 July 2023- Installation dcument D-412-08-EO-22 revision L dated 13 July 2023- Instructions for Continued Airworthiness D-412-08-ICA-02 Issue 2 dated12 April 2023 - Appendix 4.- RotorcraftFlight Manual Supplement D-412-08-RFM-12 Issue 1 Revision 0d...	- The Installation of this modification by third persons issubject towritten permission of the approval holder and disposal of the approvedappropriate documentation.- The Air Ambulance Technology STC 10037201 “Installation of AirAmbulanceEquipment”, Rev. 3 must be installed.- Additional electrical...	30/08/2023	Active	10082683

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082690	QINETIQ GmbH	REV. 1		PC-12/47E	MX-15 CAMERA INSTALLATION - Installation of a gyro-stabilized camerawith increased diameter of up to 16.6 inches to an existing lift system	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	10025 – Standard Configuration:- Installed in accordance with document: Installation Instruction, 10025-IIN-0001, Revision G, dated 6th September 2023- Operated in accordance with document: Aircraft Flight ManualSupplement, 10025-AFM-0001, Revision E, dated 29th June 2023- Maintained in accordance wi...	1) STC Prerequisite: PC-12/47E aircraft equipped with hydraulic landinggear, four bladed Hartzell Propeller HC-E4A-3D/ E10477SK and installedSPECTRE LIFT PLATFORM in accordance with EASA STC 10077020 (Validationof FAA STC SA00634DE).2) Installation of 10038 configuration is limited to MSN 1263 only3)...	03/11/2023	Active	10082690
10082691	BOMBARDIER Inc.		TCCA SA23-58	BD-700-1A10	Installation SATCOM SystemThis STC will consist in the installation of a SATCOM system to provideCPDLC and cockpit voice channels for airplanes in a green configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Modification Data Summary RAZ-BM700-295 Revision NC, dated 28 June2023;- Airplane Flight Manual Supplement G-FM23004001 Revision BASIC, dated28 June 2023;- Instructions for Continued Airworthiness BAS67058090-ICA RevisionBasic Issueor later revisions of the above listed document(s) approved/ accept...	None	30/08/2023	Active	10082691
10082695	MICRO AERODYNAMICS, INC.		FAA STC SA02304SE	GA8-TC 320 GA8	Installation of vortex generators on the wings and tail surfaces	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Drawing Package MA2253, Revision IR, dated November 18, 2013, andInstallation Manual MA2254, Revision IR, dated 14 February 2014<(>,<)>Micro AeroDynamics Instructions for Continued Airworthiness MA0666,Revision B<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf ofP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.If more than five vortex generators are damaged or miss...	31/08/2023	Active	10082695
10082696	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04035AT-D	GULFSTREAM 200/ GALAXY	Installation of Micro Quick Access Recorder (µQAR)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Gulfstream Aerospace Corporation Index List CEB14208001 Revision"-",dated 27 January 2016<(>,<)>Instructions for Continued Airworthiness CEB I 420A00 1 Rev B<(>,<)>dated 7 January2016<(>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with theP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	31/08/2023	Active	10082696
10082703	ROCKWELL COLLINS, Inc.		FAA STC ST02091AT-D	767-300	Install a Collins CMU-900 Communications System	The Certification Basis for the original product as amendedby thefollowing additional or alternativeairworthiness requirements: the following paragraph(s) at a lateramendment:CS25 amdt. 12: 25.301, 25.303, 25.305, 25.307, 25.601, 25.603, 25.605,25.609, 25.1301(a)(b)(c)(d) , 25.1307(d) , 25.1309(a)(...	TIMCO Master Data List 99T080L001 Rev. H, dated 14 March 2001<(>,<)>Airplane Flight Manual Supplement, AFM-01028, dated19 December 2000<(>,<)>TIMCO Configuration Document, Rev. H, dated 14 March 2001<(>,<)>TIMCO Maintenance Manual, dated 2 October 2000<(>,<)>or later revisions of the above listed d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/09/2023	Active	10082703

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082750 (EASA.A.S.00480)	SAAB AB	REV. 2		C-212	Installation of ACAS II and dual mode-S transpondersRev. 1:Transfer of STC.Rev. 2 corrects the STC holder name.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Saab Nyge Aero AB, TDM 04-14, Issue 3, dated 2004-07-28 - AFM-supplementS08/04or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatth...	12/09/2023	Active	10082750
10082751 (EASA.A.S.00694)	SAAB AB	REV. 3		C-212	Installation of ACAS II and a single SSR Mode-S transponderRev. 1: Transfer of STC.Rev. 2 corrects the STC holder name.Rev. 3: Correction of Associated Technical Documentation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Saab Nyge Aero AB, TDM 04-18, Issue C, dated 2005-04-11AFM Supplement, AFMS 16, Rev. 4, 11-04-2005or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.Prior to installation of this change/repair it must be determined thatth...	09/04/2024	Active	10082751
10082756	AERODISA S.L.			AT-802A AT-802	Installation of sensors for development	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	AED2022-17M_MDL Rev. A2AED2022-17M_AFMS Rev. A0AED2022-17M_ICA Rev. A1Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/09/2023	Active	10082756
10082765	ARCHEION HOLDINGS, L.L.C.		FAA STC ST04189AT	767-400ER 767-300F 767-300 767-200	Installation of Avionica satLINK MAX with optional Personality Module(avPM) in the Cabin Compartment overhead, and optional avRDC MAX QAR inthe EE Bay, to provide 2 Iridium SATCOMATS Voice channels, 1 IridiumSATCOM ATS Datalink FANS 1/A+ Data channel for Flight Deck use (CPDLC atRCP240 & ADS-C at R...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 27:25.21 (a)(1), 25.301, 25.303, 25.305, 25.307 (a), 25.561 (c)(d), 25.571,25.581, 25.601, 25.603, 25.605, 25.6...	Master Data List 130720-MDL, Revision B, dated 10 December 2014<(>,<) >Airplane Flight Manual Supplement for Archeion Holdings LLC, 130720-AFMSRevision IR, dated 23 December 2014<(>,<) >Instructions for Continued Airworthiness 130720-ICA, Revision B, dated 9December 2014<(>,<)>or later revisions of th...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/09/2023	Active	10082765
10082766	DASSAULT FALCON JET CORPORATION	REV. 1	FAA STC ST01974WI	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Installation of Aviation Clean Air Ionization SystemRev. 1:Transfer from "Duncan Aviation, Inc." to "Dassault Falcon JetCorporation".	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Duncan Aviation, Inc. STC Master Document List, Doc. No. CERTDOC-012909,Rev. A, dated 29 September 2021<(>,<)>Duncan Aviation, Inc. Instructions for Continued Airworthiness, Doc. No.CERTDOC-013215, Rev. A, dated 21 September 2021<(>,<)>or later revisions of the above listed document(s) approved/acce...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This design change may not be implemented on aircraft w...	08/04/2025	Active	10082766

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082767	DASSAULT FALCON JET CORPORATION	REV. 1	FAA STC ST01973WI	FALCON 7X	Installation of Aviation Clean Air Ionization SystemRev. 1:Transfer from "Duncan Aviation, Inc." to "Dassault Falcon JetCorporation."	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Duncan Aviation STC Master Document List, Doc. No. CERTDOC-011636, Rev.A dated 7 September 2021<(>,<)>Duncan Aviation, Inc. Instructions for Continued Airworthiness, Doc. No.CERTDOC-013274 Rev. A, dated 7 September 2021<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbeh...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This design change may not be implemented on aircraft w...	08/04/2025	Active	10082767
10082769	NSE			S2R-T34	DTS V2 for Thrush S2RThe DTSV2 is a tracking system transmitting GPS information through theIridium network.The Installation kit contains all the elements associated to theequipment DTSV2 such as antenna, coaxial cable, harnesses, circuitbreaker, support etc.	The certification basis for the intended modification is the CS 23amendment 00 dated November 14, 2003.The requirementsfor environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedandremain applicable to this certificate/ approval without anyo...	SDL-00055181AA Version A1, STC Data List documentAFMS-00055181 AA Version A01, Aircraft Flight Manual SupplementOr laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/09/2023	Active	10082769
10082771	SKYTEC AEROSPACE GmbH			737-800, 737-8	18C / 150Y Passenger Seating LayoutThis modification introduces a cabin layout using 50 economy classtriple seats and 9business class double seats generating a168-passenger seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: For Boeing 737-800model: CS 25.1, CS 25.23, CS25.25,CS 25.27 (b)-(c), CS 25.29, CS 25.301, CS 25.303, CS 2...	The change is defined with revision A of Skytec Master Document ListDocument MDL-B738C111-0002The aircraft shall be operated in accordance with revision A of SkytecAircraft FlightManual Supplement AFMS-B738C111-0002Maintenance shall be accomplished in accordance with revision A ofSkytec Instruction...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/09/2023	Active	10082771
10082773	AEROTEC & CONCEPT			737-800	G2 GALLEY REPLACEMENTReplacement of Galley G2 slim into galley G2 large. The replacement ofthis galley does not introduce new functionality and new galley is onlyused for storage and oven.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	AE22083MDL Issue 1, Master Drawing ListAE22083ICA Issue 0, Instruction for Continued Airworthinessor later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	The cabin configuration before modification is defined per modificationJC/MOD/5854 approved per J<(>&<)>C Engineering Services Ltd.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or r...	08/03/2024	Active	10082773
10082786	ALAMO ENGINEERING GmbH			FALCON 2000	Interior Refurbishment with LOPA changeInterior refurbishment with Settee modification - Installation of cabinLED lights and Air Show 500 - Replacement of AI CMS with Alto Cadenceincluding Speaker - Galley Espresso machine removal with an installationof AC Outlet	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.23; 25.301;25.303; 25.305; 25.307; 25.321; 25.561; 25.601; 25.603; 25.605; 25.607;25.609; 25.611; 25....	- MDL22A26AE-01 Master Document List Rev. B- ICA22A26AE-01 Instructions for Continued Airworthiness Rev. Aor later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	None	13/09/2023	Active	10082786
10082790	QUIET TECHNOLOGY AEROSPACE, Inc.		FAA STC ST04560AT	SEE FAA AML	Replacement of the existing Honeywell HTF7000 engine upper and lowerthrust reverser door assemblies with Quiet Technology Aerospace modifiedupper and lower thrust reverser door assemblies. The Quiet TechnologyAerospace thrust reverser doorassemblies consist of new titanium innerdoor exhaust impinge...	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Quiet Technology Aerospace document “HTF 7000 Thrust Reverser UpgradeMaster Drawing List,” Report No. QTA 7001, Rev. A,dated 26 October2022, and “HTF 7000 Thrust Reverser UpgradeAssemble Instructions Report,” Report No. QTA 7007, Rev. A,dated 20 February 2023,“HTF 7000 Thrust Reverser Upgrade for...	This modification has been determined to be a no acoustic change inaccordance with 14 CFR §21.93(b).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverse...	13/09/2023	Active	10082790

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082808	STC HOLDING COMPANY, INC.		FAA STC SA1841NM	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of larger windows and the lowering of the seats	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Consulting Aerospace Engineers, Inc. MDL Number GRC-1-1007<(>,<) >Revision H, dated 14 February 1983<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/09/2023	Active	10082808
10082809	STC HOLDING COMPANY, INC.		FAA STC SA3954NM	DHC-6 SERIES 300 DHC-6 SERIES 200 DHC-6 SERIES 100	Installation of larger windows and the lowering of the seats	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Consulting Aerospace Engineers, Inc. MDL Number GRC-1-1007<(>,<) >Revision K, 22 August 1988<(>,<)>or later revisions ofthe above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/09/2023	Active	10082809
10082810	UUDS AERO CONCEPT			A319-171N A319-151N/-153N A319-131/-132/-133 A319-111/-112/-113/-114/-115	A319 MEDEVAC CONFIGURATION	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-01 Medical Evacuation Configurationthe following paragraph(s) at a later amendment: see belowCS 25.1; 25.29; 25.301; 25.303; 25.305; 2...	Master Data List UAC22M002-MDL01 Rev.0 dtd. 06 Sep 2023Aircraft Flight Manual Supplement UAC22M002-AFMS01 Rev. 2 dtd. 28Jul2023Instructions for Continuous Airworthiness UAC22M002-ICA01 Rev. 0 dtd. 20Mar 2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	-Per AFM supplement UAC22M002-AFMS01-Installation is limited to layout configuration UAC22M002-L0001 withoutMedical EquipmentPrior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repaire...	18/09/2023	Active	10082810
10082811	ALAMO ENGINEERING GmbH			35	Replacement of the existing CVR with UASC CVR-120A	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): Special Condition Doc. No. SC-F25.1353-01.the following paragraph(s) at a later amendment: CS 25.23, CS 25.301, CS25.303, CS 25.305, CS....	Master Data List Doc. No. MDL22A43AE-01 Revision A, dated 13 September2023Aircraft Flight Manual Supplement FMS22A43AE-01 Revision A, dated 15March 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/09/2023	Active	10082811
10082812	ASI INNOVATION			AS 355 N	Laser and antenna activation on AS355N equipped with modification ASIFAM-1782 No. 20230001.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Rotorcraft Flight Manual, ASI-RFM-1799-01, Rev 1, dated 06.09.2023Certification Program, ASI-CP-1799-02, Rev 02, dated 12.09.2023Service Bulletin, ASI-SB-AS355-2500-1799-00, issue00, dated 08.09.2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/09/2023	Active	10082812

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082814	PATRIA AVIATION OY			412EP	FMS and EADI_EHSI Installation on B412	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Drawing List D-412-08-CS-02 revision W dated 13 September2023.- Installation Instruction D-412-08-EO-20 revision W dated 13 September2023.- Instructions for Continued Airworthiness D-412-08-ICA-02 Issue 3 dated13 September 2023.- Rotorcraft Flight Manual Supplement D-412-08-RFM-01 Issue 1 Revisio...	- The Installation of this modification by third persons issubject towritten permission of the approval holder and disposal of the approvedappropriate documentation.- Rotorcraft configuration prerequisites as per D-412-08-DA-01 dated 13September 2023 or later approved revision under the EASA system...	19/09/2023	Active	10082814
10082823	JET AVIATION AG			777-200LR	Replacement of installed CMA-2102 SBB antenna with HGA-7001antenna.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): CRI B-101 Issue 3 “Vibration / Buffetingfor Large Antenna Installations”the following paragraph(s) at a later amendment:CS25 Amd...	Master Data List JBSL-M-03868MDL-001 issue B.Instructions for Continued Airworthiness JBSL-M-03868ICA-010 issue A.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This certificate covers only the structural provisions for this antennainstallation; internal looming and installation of any electronichardware need to be covered by a separate airworthiness approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between...	21/09/2023	Active	10082823
10082824	PATRIA AVIATION OY			AB412 EP AB412 AB212 412EP 412 212	Rotorcraft Modular Equipment Rack – RoMER / Installation of the modularfixation device, which allows flexible fixations of multiple differentloads and cargo in cabin.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	-Drawing List D-412-15-CS-01 revision C dated 1 September 2023- Installation document D-412-15-EO-01 revision C dated 1 September2023- Instructions for Continued Airworthiness D-412-15-ICA-01 Revision 1dated 1 September 2023.- Rotorcraft Flight Manual Supplement D-412-15-RFM-01 Issue 1 Revision 0date...	The Installation of this modification by third persons is subject towritten permission of the approval holder and disposal of the approvedappropriate documentation.Patria minor change D-412-15-DA-02 Provision for Rotorcraft ModularEquipment Rack is accomplished.Prior to installation of this change/r...	21/09/2023	Active	10082824
10082852	AERODISA S.L.			A350-941	New Waste Compartment Door on A350-900Installation of a newdoor in the cabinet mounted in lavatories inA350-900 aircraft	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Airworthiness Compliance Program - AED2022-16M_PCA - Installation of acabinet’s door on A350 aircraftRev A0, dated 12 September 2023Master data List - AED2022-16M_MDL - Installation of a cabinet’s door onA350 aircraft Rev A0,dated 21 September 2023or later revisions of the above listed document(s) a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/09/2023	Active	10082852
10082855	ALAMO ENGINEERING GmbH			35	FMS Upgrade UNS-1L to UNS-1Lw including RNP1	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Instructions for Continued Airworthiness ref ICA22A42AE-01 dated11/4/2023;Flight Manual Supplement ref FMS22A42AE-01 dated 7/9/2023;MASTER DOCUMENT LIST (MDL) ref MDL22A42AE-01 dated 8/9/2023.	Limited to aircraft S/N 265.Prior to installation of this change/ repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect uponthe airworthiness of the product.	26/09/2023	Active	10082855

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082918	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03220AT-D	GV-SP	Installation of Pocket Door Lockout Mechanism	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Gulfstream Aerospace Corporation Index List GC51 5188000, Revision C,dated 2 May 2006<(>,<) >Airplane Flight Manual Supplement, GC51 518M001<(>,<)> Revision NC,dated 4 May 2006< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/09/2023	Active	10082918
10082926	AERODATA AG			EMB-550	Installation of Aerodata AG Flight Inspection System AD-AFIS-1350.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List Installation of AD-AFIS-1350, documentMDL-A/C-948Rev 0, dated 19 September 2023.Airplane Flight Manual Supplement Installation of AD-AFIS-1350 forEMB550, document AFM-179 Rev 3,dated 12 April 2023.Aircraft MaintenanceManual Supplement EMB550, document AMM-1185 Rev 0,dated 07 S...	Limited to model EMB-550 equipped with DCA 0550-000-00026-2016 (Praetor600).The performance of Aerodata Flight Inspection System AD-AFIS-1350 hasnot been assessed by EASA.Prior toinstallation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any ot...	28/09/2023	Active	10082926
10082933	AEROSPACE COMPOSITES GmbH	REV. 1		KODIAK 100	Single Hatch Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with EO-KOD100-9506-01 dated 30/8/2023;maintained in accordance with MMS-KOD100-9506-01 dated 18/9/2023;operated in accordance with AFMS-KOD100-9506-01 dated 22/9/2023<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Applicable to Aircraft Serial Numbers: up to and incl. 100-0274.Not compatible with the optional External Cargo Compartment (ECC)Not compatible with the optional TKS Ice Protection System.	08/10/2025	Active	10082933
10082937	HONEYWELL INTERNATIONAL Inc.		FAA SA04195NY	SEE APPROVED MODEL LIST (AML) NO. 89900019-110 - 15/07/2020	Installation of the KFC 230 Aerocruze Automatic Flight Control System(FCS) upgraded from KFC 200 FCS.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aerospace Design & Compliance, LLC Master Data List (MDL) 89800019-112,Rev. IR, dated 13 July 2020Aerospace Design & Compliance, LLC Instructions for ContinuedAirworthiness (ICA) 89800019-111, Rev. A, dated 13 July 2020Aerospace Design & Compliance, LLC Airplane Flight Manual Supplement (AFMS) 890000...	Approved installation of a KFC 200 Flight Control System asspecified bythe AML No. 89900019-110 is a prerequisite to this STC.The ICA and its contents must be incorporated into the operator'smaintenance program.Prior to installation of this change/repair it must be determined thatthe interrelations...	16/10/2023	Active	10082937
10082968	BOEING IRELAND LIMITED	REV. 2		787-9	Boeing 787-9 – QTR 30J Business Class Suites InstallationIntroduction of a 30J/ 281Y passenger seating layout through theinstallation of 30 Business Class (B/C) seats and associated mini-suitefurniture and front row monuments in the forwardpassenger seating zonebetween Doors 1 and 2.Rev. 1 revises e...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-101 Installation of Mini-Suite Type Seating,Issue 1The requirements for environmental protection and the associatedcertified noise and...	- Airplane Flight Manual Supplement (AFM-S), Doc: BIL-00180-AFM01 Rev.05 dd. 15-Jan-2025- Instructions for Continued Airworthiness, Doc: BIL-00180-ICA01 Rev.05, dd. 27-Aug-2025- Change / Repair Approval, Doc.: BIL-00180-APP Rev. 16 dd. 03-Nov-2025or later revisions of the above listed document(s) ap...	At time of approval of this change to type certificate, theapproval ofaffected parts of Operational Suitability Data (OSD) were still pendingfor the following OSD constituents: Cabin Crew Data- As per BIL-00180-AFM01, §1.1.- Implementation of STC 10082968 Rev 1 or later approved revisionconstitutes...	05/11/2025	Active	10082968

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10082976	PMV ENGINEERING			737-9	CAB-04740 – 213 Y/C seats installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List CAB-04740-MDL Rev 01Instructions for continued airworthiness CAB-04740-ICA Rev 00or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/10/2023	Active	10082976
10082977	SKYTEC AEROSPACE GmbH			737-8	12C / 156Y Passenger Seating LayoutThis modification introduces a cabin layout using 52 economy classtriple seats and 6business class double seats generating a 168passenger seating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision A of Skytec Master Document ListDocument MDL-B738C121-0003The aircraft shall be operated in accordance with revision B of SkytecAircraft FlightManual SupplementAFMS-B738C121-0001Maintenance shall be accomplished in accordance with revision A ofSkytec Instructions...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/10/2023	Active	10082977
10082982	JET AVIATION AG			737-8	Iridium Antenna InstallationThis modification consists of the structural installation of a DualIridium/LTE Antenna on the forward fuselage upper lobe, between STA 480and STA 500, stringer S-1 to stringer S-2R	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.23, 25.25, 25.27,25.29, 25.251 (b), 25.301, 25.302, 25.303, 25.305, 25.307, 25.321,25.337, 25.365, 25.5...	The change is defined with revision B of Jet Aviation Master Data ListDocument JBSL-M-03862MDL-001Maintenance shall be accomplished in accordance with revision A of JetAviation Instructions for Continuous Airworthiness DocumentJBSL-M-03862ICA-001or later revisions of the above listed document(s) app...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/10/2023	Active	10082982
10082984	AVMAX AVIATION SERVICES Inc.		TCCA SA13-49	SEE EASA APPROVED MODEL LIST	Cockpit Stowage Box InstallationThe modification covers themanufacture and installation of a stowagebox installed in the main access panel (floor panel) of the flight deckcenter console. The existing main access panel is modified toaccommodate the stowage box.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.29, 25.301,25.303, 25.305, 25.307, 25.365 (e),(g), 25.561, 25.601, 25.603, 25.605,25.607, 25.609, 25...	The change is defined with Avmax Aviation Services Inc. Master Data ListCE80-900, Issue HInstallation shall be performed in accordance with Avmax AviationServices Inc. EngineeringOrder CE80-401, Issue BMaintenance shall be performed in accordance with Avmax AviationServices Inc. Maintenance Manual...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/10/2023	Active	10082984
10082995	NEXTANT AEROSPACE, L.L.C.		FAA STC ST3603CH	GVI (G650)	Installation of a SpaceX Starlink Aviation System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Nextant Aerospace Master Data List, Doc. No. NT0077-MDL0-0100, RevisionA, dated 11 August 2023<(>,<)>Airplane Flight Manual Supplement, Nextant Aerospace Doc. No.NT0077-AFMS-0I00<(>,<)> Revision IR, dated 14 August 2023<(>,<)>Instructions for Continued Airworthiness - Airworthiness Limitations,Chapte...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This modification requires that the aircraft be shown t...	11/10/2023	Active	10082995

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083025	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC SA01094DE	1900D 1900C	Installation of Pratt & Whitney Engine Services FAST System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	GN4-T-100-11, Master Data List, Installation Data, Rev. A<(>,<)> dated18 May 2022<(>,<)>GN4-T-102-11, Data List - Design Data, Rev. A<(>,<)> dated 18 May 2022<(>,<) >Instructions for Continued Airworthiness, GN4-T-260-12, Rev. A, dated 11April 2022<(>,<)>Flight Manual Supplement, GN4-T-250-10, Rev. A...	This STC is applicable to all serial numbers of the TextronAviation Inc1900C and 1900D.Prior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect uponT...	16/10/2023	Active	10083025
10083029	SCANDINAVIAN AVIONICS DESIGN ApS			737-300, 737-400, 737-500	GPS Antenna installationThe modification consists of the full mechanical/ aerodynamic provisionfor an antenna installation as follows:A GPS Antenna on the upper fuselage of the applicable model at - STA 320 between stringer 1 and 2Lor - STA 323 between stringer 1 and 2L	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Compliance Record: 3000115-COR Issue 2Engineering Order: 3000115-EO Issue 1Maintenance Manual Supplement: 3000115-MM Issue 1Instructions for Continued Airworthiness: 3000115-CA Issue 1or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/10/2023	Active	10083029
10083031	BOEING IRELAND LIMITED			777-300ER	Saudi Arabian Airlines, 777-300ER Cabin ReconfigurationThe aircraft configuration is changed from a production 30J (BusinessClass) + 383Y (Economy Class) passenger seat layout to a 12J (BusinessClass) + 433Y (Economy Class) passenger seat layout.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, 'Saudi Arabian Airlines, 777-300ER CabinReconfiguration', BIL-00198-APP, Revision 01, dated 17th October 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/10/2023	Active	10083031
10083051	NOVA SYSTEMS & ENGINEERING LIMITED			737-800	B737-800-Cabin Reconfiguration (186Y/ C)This Change reconfigures the existing two-class cabin configuration (12B/C and 156 Y/C), into a single-class cabin configuration (186 Y/C).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List (MDS) Doc Nr.: NSI-14166-01-MDL-01 Issue (Rev) 2Instructions for Continued Airworthiness (ICA) Doc Nr.:NSI-14166-01-ICA-01 Issue (Rev) 1Cabin Crew Data (CCD) Supplement Doc Nr.: NSI-14166-01-CCD-01 Issue(Rev) 1or later revisions of the above listed document(s) approved/acceptedunder...	Aeroplane cabin configurations changed per this STC (i.e.B737-800 with186Y/C seating reconfiguration) are considered tobe the "same aircraft"as the B737-800 baseline configurations. Cabin crew operating aeroplaneschanged per this STC mustcomplete aircraft difference training inaccordance with ORO....	18/10/2023	Active	10083051
10083061	HELIKOPTER AIR TRANSPORT GESELLSCHAm.b.H.			SEE EASA APPROVED MODEL LIST	Complex Personnel Carrying Device System EO 85-014	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 27.27, CS 27.301, CS27.303, CS 27.305, CS 27.307, CS 27.321, CS 27.337, CS 27.571 (a), CS27.571 (b), CS 27...	Master Drawing List, MDL 85-014, Revision 0List of Simple PCDS, Simple PCDS 85-014, Revision 0Certification Plan, CP 85-014, Revision 3Instructions for Continued Airworthiness (including ALS), ICA 85-014,Revision 0For other approved technical documentation see Appendixor later revisions of the above...	Manufacturing and Assembly Processes of various components of EO 85-014as described in PS 85-014 Revision 0, must be followed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair...	19/10/2023	Active	10083061

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083064	AERODATA AG			B300	Installation of AD-AFIS-2100Main Items:- Integration of an electrical load shed for FIS power supply- Integration of 19antennae on pressurized and non-pressurizedcompartment- Integration of one operator and one equipment console in the cabin ->decrease of passenger seats- Integration of additional...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDL-A/C-969, Rev 1Aircraft Flight Manual Supplement AFM-189, Rev 1Aircraft Maintenance Manual Supplement AMM-1195, Rev IRMaster Minimum Equipment List MMEL-1019, Rev IRor later revisions of the above listed document(s)approved/ acceptedunder the EASA system.	Only applicable to Textron Aviation Inc. B300 aircraft S/N FL-1315The functions and performance of Mission System AD-AFIS-2100 have notbeen assessed by EASA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	19/10/2023	Active	10083064
10083067	BELL TEXTRON, Inc.		FAA STC SH5500NM	206B 206A	Installation of skid shoe assembly kit, Brackett Aircraft P/NBSS-206-00. Skid shoe kit assembly and installation	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Brackett Aircraft Co.<(>,<)> Inc. Drawing List BSS-206, Revision A,dated 29 June 1993<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/07/2024	Active	10083067
10083072	ALAMO ENGINEERING GmbH			DORNIER 228-212	Installation of Skytrac Iridium Certus Satcom	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: FAR §23.1309 at Amdt41, FAR §23.1359 and §23.1431 at Amdt 49, FAR §23.1581 at Amdt 50, CS§23.573 (b)<(>,<)> §...	Master Document List MDL23A20AE-01 rev. AFlight Manual Supplement FMS23A20AE-01 rev. Cor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Applicable to S/N 8232 and 8233Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	20/10/2023	Active	10083072
10083134	SABENA TECHNICS BOD			737-800	Relocation of a Low Frequency Underwater Locating Device (LF-ULD)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDL-S-00-4419 Issue AInstruction for Continued Airworthiness ICA-S0036-00-002 issue Bor later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/10/2023	Active	10083134
10083139	TELEDYNE UK LIMITED			A300 F4-622R A300 F4-605R A300 B4-622R A300 B4-620 A300 B4-605R A300 B4-603 A300 B4-601	Installation of Wireless GroundLinkUpgrade of existing Wireless Quick Access Recorder (WQAR) unit tosupport continued network operation as legacy mobile phone networks areshut down.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25.899 Amdt 27The requirements for environmental protection and the associatedcertified noise and/ or emiss...	-Teledyne Instructions for Continued Airworthiness, Doc Ref:MOD-ICA-043, Rev 01, Dated 18 January 2023-Teledyne Master Drawing List, Doc Ref: MOD-MDL-043, Rev 01, Dated 23June 2023or later revisions of the above listed document(s) acceptedby EASA inaccordance with the Technical Implementation Proce...	EASA STC 10033914 (which is a validation of FAA STC ST01778LA forinstallation of Wireless GroundLink) is a pre-requisite beforeinstalling this STCPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed c...	27/10/2023	Active	10083139
10083196	CONCORDE BATTERY CORPORATION		FAA STC SA01304WI	SR22T SR22 SR20	Installation of the Concorde CB24-11M or CB24-11MXC Lead Acid Battery<(>,<)> or RG24-11M or RG24-15M VRSLA Battery.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Concorde Master Drawing List, Dwg. No. 5-0244, dated 17 June 2004, orDwg. No. 5-0244 Rev A, dated 7 September 2011<(>,<)>Concorde Instructions for Continued Airworthiness, Dwg. No. 5-0144,Revision F, dated 11 March 2011<(>,<)> for the RG series batteries<(>,<)>or later revisions of the above listedb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/11/2025	Active	10083196

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083197	BOEING IRELAND LIMITED			737-8	737-8 Class 2 Crew Rest SeatInstallation of new design single cabin attendant seat capable ofmeeting Class 2 crew rest specifications.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, '737-8 Class 2 Crew Rest Seat', BIL-00206-APP,Revision 00, dated 1st November 2023.Master Minimum Equipment List Supplement, 'NEOS 737-8 Class 2 Crew RestSeat', BIL-00206-MMEL01 R01, dated 8th September 2023.Flight Attendant Manual (FAM) Supplement, 'NEOS 737-8 Class 2 Crew...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/11/2023	Active	10083197
10083201	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.	REV. 1		737-800	Cabin reconfiguration with new Safran Model Z100 Series economy classPassenger seats equipped with ISPS.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-MDL referenced JCAERO_MDL_0879_ISS 1.1 dated May 24th 2024-AMM Supplement referenced JCAERO_AMM_0879-1_ISS 1.0 dated June 1st 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	-Change only applicable to MSNs listed in the CertificationPlanreferenced JCAERO/CP/0879Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	06/06/2024	Active	10083201
10083204	DUNCAN AVIATION, Inc.		FAA STC SA01176WI	1900D 1900C	Installation of Collins TCAS-4000 Traffic Alert and Collision AvoidanceSystem (TCAS-II)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	(1) Duncan Aviation Document List 10059100<(>,<)> Revision A<(>,<)>dated 5 June 2003<(>,<)> (2) Flight Manual Supplement40028800<(>,<)> Revision 0, dated 20 June2003<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Implement...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/11/2023	Active	10083204
10083205	STERLING CORPORATIOND/ B/A STERLING HELICOPTER		FAA STC ST04787NY	GVI (G650) GIV-X, GV-SP	Installation of True Blue Power TFC4000 AC-to-AC Converter	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Sterling Helicopter Master Drawing List, Document No. ST-22-505-02, Rev.A, dated 23 November 2022<(>,<)>Sterling Helicopter Instructions for Continued Airworthiness, DocumentNo. ST-22-505-04, Rev. -, dated 9 September 2022<(>,<)>or later revisions of the above listed document (s) approved/accepted on...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC replaces existing GE Aviation Systems LLC. con...	06/11/2023	Active	10083205
10083206	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT, LLC		FAA STC ST02217CH	650	Installation of a Honeywell CAS 67A Traffic Alert and CollisionAvoidance System (TCAS II)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Elliott Aviation Master Data List, Report No. MDL-2515-000,Revision A,dated 23 November 2005<(>,<)>Airplane Flight Manual Supplement, Elliott Aviation Report No.FMS-2515-000, Revision IR, approved 30 November 2005<(>,<)>Instructions for Continued Airworthiness, Elliott Aviation Report No.ICA-2515-0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2023	Active	10083206

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083207	S4A SOLUTIONS FOR AVIATION, S.L			CL-600-2D24 (RJ SERIES 900)	Low Frequency ULB Installation on CRJ900	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): EASA CRI F-01SC Non rechargeable Lithiumbatteries.- The following paragraph(s) at a later amendment: CS-25 Amdt 27,Sections 25.1, 25...	604_166-18-02 Master Document List 20-10-2023604_166-12-30 Maintenance Manual Supplement (ICA) Edition 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2023	Active	10083207
10083209	AIRBUS S.A.S.			A321-271NX	Airbus STC Solutions MOD AI0257 - INSTALL CUSTOMIZED MCDThis modification describes the removal of the linefit MoveableClassDivider (MCD) and its replacement by a customized lateral MCD. Theinstallation of this new MCD is located behind the last business class(B/C) seat row on the right-hand side (...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Summary Report reference SRS-23014 issue E dated 02November 2023.Modification Approval Sheet MAS n° AI0257 issue 2 dated 02 November2023.Instructions for Continued Airworthiness reference ICA MOD AI0257 rev Adated 21 August 2023or later revisions of the above listed document(s) approve...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2023	Active	10083209
10083212	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT, LLC		FAA STC ST02218CH	650	Installation of a Universal Avionics EFI-890R Electronic FlightInstrument System (EFIS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Elliott Aviation Master Data List, Report No. MDL-2489-000,Revision A,dated 23 November 2005<(>,<)>Airplane Flight Manual Supplement, Elliott Aviation Report No.FMS-2489-000, Revision IR, approved 30 November 2005<(>,<) >Instructions for Continued Airworthiness, Elliott Aviation Report No.ICA-2489-0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2023	Active	10083212
10083213	SKY SERVICE F.B.O. INC.		TCCA SA22-30 ISSUE 1	CL-600-2B16 (604 VARIANT)	Challenger Ku Band Satcom SystemThis modification covers a Ku Band Satcom Installation.This system is a standalone providing Wi-Fi in the cabin.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation shall be performed in accordance with AvionicsDesignServices Ltd Master Drawing List MDL21033, Revision N/CThe aircraft shall be operated in accordance with Skyservice F.B.O.Flight Manual Supplement FMS21033-1 Revision N/CMaintenance shall be performed in accordance with Skyservice F.B...	EASA STC 10066792 shall be installed as prerequisite.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	06/11/2023	Active	10083213
10083223	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT, LLC		FAA STC ST02216CH	650	Installation of a Universal Avionics Terrain Awareness and WarningSystem (TAWS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Elliott Aviation Master Data List, Report No. MDL-2516-000,Revision A,dated 23 November 2005<(>,<)>Airplane Flight Manual Supplement, Elliott Aviation Report No.FMS-2516-000, Revision IR, approved 30 November 2005<(>,<)>or later revisionsof the above listed document(s) approved/accepted onbehalf o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2023	Active	10083223

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083256	3S CERTIFICATION, LLC		FAA STC SA02017WI	SEE FAA AML	Installation of the Parker-Meggitt iPRESS™ System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	3S Certification, Master Data List (MDL) 3S18-036-1001, Revision IR,dated 1 August 2023< (>,<)>3S Certification, Instructions for Continued Airworthiness (ICA) 3S18-036-6101, Revision IR, dated 18 July 2023< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA inP...	Approval of this change in type design applies only to the aircraftlisted on Approved Model List 3S18-036-1801.Prior toinstallation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce...	09/11/2023	Active	10083256
10083262	GDC ENGINEERING GmbH			A319-111	44 B/C – 6 Y/C Cabin ReconfigurationThis modification introduces 22 Business Class Double Seats and 2Economy Class Triple Seats resulting in a 50 Passenger SeatingConfiguration Layout.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.807 (g) at Amdt15 and CS-CCD at Issue 2.The requirements for environmental protection and the associa...	The modification is defined in accordance with GDC Engineering MasterDocument Register A319K-MDR-25000, Issue BThe aircraft shall be maintained in accordance with GDC EngineeringInstructions for Continued Airworthiness & Operator Manual Supplementdocument A319K-ICA-BYD, Revision 0.The OSD-Cabin Crew...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/11/2023	Active	10083262
10083263	GARMIN AT, INC.		FAA STC SA01695SE	SEE FAA APPROVED MODEL LIST	Installation of antenna models identified in the Master Data List	The Certification Basis for the original product remains applicable tothis certificate/ approval, except where amended by additional or lateramendments if indicated on FAA STC SA01695SE.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the or...	Garmin Supplemental Type Certificate Master Data List, P/N 005-C0373-00,Revision D, dated 21 August 2006or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This STC is for physical installation only.For operational Airworthiness approval refer to data for the interfacedreceiving equipment.This STC is valid for aircraft types and models approved by EASA andlisted on the FAA Approved Model ListSA01695SE dated 1 September 2006.Prior to installation of th...	14/11/2023	Active	10083263
10083273	AIRBUS DEFENCE AND SPACE S.A.			A330-202	A330 MRTT-EAE (Multi Role Transport Tanker - Ejército del Aire Español) conversion from Airbus A330-202 model.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC D-4318-002"Air Medical Service".- The following paragraph(s) at a later amendment: CS 25.562 InitialIssue.This certificate/ approva...	- "Conversion Definition A330 MRTT EAE STC", Ref. TE-FE-DT-240001 issueA dated 13 November 2024.- "Limitations of Weight and Balance Manual (WBM) for A330 MRTT", Ref.TAS-F0-TD-21-0004 Issue Adated 18 October 2024- "EASA-Approved Model A330MRTT EAE Airplane Flight Manual", Ref.TE-FD-DT-220023 issue-...	Configuration of the product upon which the change is to bemade: - Major change to TC, 10029273 (G-MRTT-01) - Major change to TC, 10029276 (G-MRTT-02) - Major change to TC, 10063725 (G-MRTT-04) - Major change to TC, 10060569 (G-MRTT-06) - Major change to TC, 10069946 (FWC M...	14/11/2024	Active	10083273
10083274	SABENA TECHNICS BGC			A320-251N	PORTABLE ELT INSTALLATION	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt. 4: 25.1,25.301, 25.303, 25.337, 25.561, 25.601, 25.603, 25.605, 25.607, 25.609,25.611, 25.613,2...	Master Data List 41151-01-A-MDL Rev00Instructions for Continued Airworthiness 41151-01-A-ICA Rev00or later revisions ofthe above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/11/2023	Active	10083274

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083281	L3 HARRIS AVIATION PRODUCTS, Inc.		FAA ST02721LA	CL-600-2D24 (RJ SERIES 900) CL-600-2B19 (RJ SERIES 100)	Installation of SRVIVR25 Cockpit Voice Recorder (CVR) with IntegratedRecorder Independent Power Supply (RIPS)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): EASA CRI F-01Non Rechargeable LithiumBatteries.- The following paragraph(s) at a later amendment: JAR 25 Change 14, Rules: 25.21(a)(d...	Master Data List 8900106-001 Rev , 30 March 2023Instructions for Continued Airworthiness 8210686-600 Rev BAFM Supplement 8210686-900 Revor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/11/2023	Active	10083281
10083293	ALAMO ENGINEERING GmbH			CL-600-2B16 (604 VARIANT)	ADS-B Out Collins TDR-94D / WAAS GPSADS-B Out upgrade in compliance with the latest RTCA DO-260B withinRockwell CollinsProline 4 Avionic suite.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1322 at Amdt 5,CS 25.1319 at Amdt 27.CS-ACNS.D.ADSB.001, ACNS.D.ADSB.010, ACNS.D.ADSB.020, ACNS.D.ADS...	The modification is defined in accordance with Alamo Engineering MasterDocument List MDL23A37AE-01, Revision AThe aircraft shall be maintained in accordance with Alamo EngineeringInstructions for Continued Airworthiness document ICA23A37AE-01-A,Revision A.The aircraft shall be operated in accordance...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/11/2023	Active	10083293
10083295	AIRCRAFT DEVELOPMENT AND SYSTEMSENGINEERING (ADSE) B.V.			737-800	Certification of the Boeing 737-800 as PED tolerant	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1309 (a)(1), 25.1353 (a), 25.1431 (a), 25.1529 and 25.1581 (a)(2) at Amendment 27.The requirements for...	The change is defined with Issue 2.0 of ADSE Design Definition List23-DO-037.The aircraft shall be operated in accordance with Issue 0 of ADSEAirplane Flight Manual Supplement documents 23-DO-038or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/11/2023	Active	10083295
10083311	EICHELSDOERFER GmbHFLUGZEUGBAU			SEE EASA APPROVED MODEL LIST	Covering and recovering of on ELA-1 aeroplanes with polyester cover	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 23.603/ CS 23.605/ CS 23.609 of CS 23 (initial issue).Therequirements for environmental protection and the associated...	Technische Mitteilung Nr. 010-23 Rev.00 Issue dated 14/06/2023<(>,<)>Or later revisions of the above listed document(s)approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/11/2023	Active	10083311
10083329	Q.C.M. DESIGN GmbH			LEARJET MODEL 45	Installation of FDR and SSCVR Upgrade	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	L45X-QCM23-001-M1-AFM Rev 0 dated 8/11/2023; L45X-QCM23-001-M1-ICA REV 1dated 5/12/2022<(>,<)>or later revisions of theabove listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2023	Active	10083329
10083336	AVMAX AVIATION SERVICES Inc.	REV. 1	TCCA SA15-46 ISSUE 2	DHC-8-315 DHC-8-311, DHC-8-314 DHC-8-202, DHC-8-301 DHC-8-106, DHC-8-201 DHC-8-102, DHC-8-103	TB44 / TB40 Lithium Battery System InstallationThis modification replaces the existing aircraft rechargeableNickel-Cadmium batteries with the Mid-Continent Instrument TB44 / TB40rechargeable Lithium-ion battery.Revision 1: TB40 Lithium Battery Configuration added.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition: SCA 2015-02, Rechargeable Lithium Batteries andBattery Systems.- The following paragraph(s) at a later amendment: TB44 Lithium Batteryins...	The change is defined with Avmax Aviation Services Inc. Master Data ListCE273-900, Issue ZTB44 Lithium Ion Battery System Installation:Installation shall be performed in accordance with Avmax AviationServices Inc. Engineering Order CE273-401, Issue TMaintenance shall be performed in accordance withS...	TB40 Lithium Ion Battery Installation: The Battery Access Kit per EASASTC 10086387 is required for the TB40 Lithium IonBattery SystemInstallation.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installede...	30/05/2025	Active	10083336

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083348	Q.C.M. DESIGN GmbH			560XL	Update of ICA for CAT II Operation removing bench check requirement.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 Amendment 27: 25.601; 25.899; 25.1301; 25.1302; 25.1309; 25.1316;25.1317; 25.1319; 25.1323; 25.1333; 2...	QCM Compliance Report, CR-C560-QCM34-001, Revision 1, dated20 November2023.QCM Instructions for Continued Airworthiness, C560-QCM34-003-M1-ICA,Revision 0,dated 03 November 2023.or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	As a prerequisite to this change, the aircraft must be equipped with TCholder option for CAT II operations.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce noe...	24/11/2023	Active	10083348
10083381	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04346AT-D	GVII-G600 GVII-G500	Installation of Satcom Direct Router (SDR) Databus Wire Harness	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Gulfstream Aerospace Corporation Index List GDL100000069, Revision A,dated 4 May 2023<(>,<) >or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Satcom Direct Router is required for this installation....	30/11/2023	Active	10083381
10083382	AMAC AEROSPACE SWITZERLAND AG			A321-271NX/-272NX A321-271N/-272N A321-251NX/-252NX/-253 NX A321-251N/-252N/-253N A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-151N/-153N/-171N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	WLAN ActivationThis Modification activates the Wireless Local Area Network (WLAN)Function of a preinstalled WLAN system(Router interfaced with WAPs inthe cabin emitting in 2.4GHzand/or 5GHz Frequency Band and a cockpitWLAN ON/OFF switch).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1, CS 25.869, CS25.1301, CS 25.1309, CS 25.1351, CS 25.1353, CS 25.1360, CS 25.1431, CS25.1501, CS 25.1...	Configuration 1:The Change is defined with Revision A of Master Data List documentMDL-A3201-1-4430.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplement document AFMS-A3201-1-4430.Maintenance shall be done in accordance with Revision A of Instructionsfor Co...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/11/2023	Active	10083382
10083383	GULFSTREAM AEROSPACE CORPORATION	REV. 2	FAA STC ST04347AT-D	SEE FAA AML	Installation of Satcom Direct Plane Simple SystemRevision 1consists of adding configurations for Satcom Direct (SD)Plane Simple Ka and Ku/Ka System installations in the GVI aircraftmodel.Revision 2 consists of adding GVII-G500 and GVII-G600 to AML.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	For Gulfstream Aerospace Model GVI, Airplane Flight Manual Supplement,CE613030001 Revision A, dated 28 March 2024For Gulfstream Aerospace Model GVI, Airplane Flight Manual Supplement,CE613030002 Revision (-), dated 06 May 2024For Gulfstream Aerospace Model GVI, Airplane Flight Manual Supplement,CE61...	For Gulfstream Aerospace Model GVII-G500 and GVII-G600, theinstructionscontained within the Guidance for Follow-on Installation, GVII-G600Satcom Direct (SD) Plane Simple Ku, GCD000036550, Revision (-), dated 12September 2024, or later revision and GVII-G500 Satcom Direct (SD) PlaneSimple Ku, GCD000...	18/11/2024	Active	10083383
10083387	MAGNETIC MRO AS			ERJ 190-200 STD ERJ 190-200 LR ERJ 190-200 IGW	Cabin ReconfigurationThis reconfiguration modifies the cabin by installing a Galley G2,relocating the FWD RH Stowage and accomplishing related interiorchanges.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Issue 2 of Magnetic MRO Master Data ListMMRO-C-0215Maintenance shall be accomplished in accordance with Issue 2 of MagneticMRO AMM Supplement Document MMRO-C-0215-AMM-01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/11/2023	Active	10083387

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083388	KITCHENER AERO AVIONICS LIMITEDdba MID CANADA MOD CENTER		TCCA O-LSA20-117/D	560XL	UASC TAWS Software Upgrade (from SCN 10.4 to SCN 10.8).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Avionics Design Services Ltd. Certification Plan, CP20039-1, Issue 1,dated 13 October 2020;Installation in accordance with Avionics Design Services Ltd. MasterDrawing List, MDL20039, Issue 1,dated 29 October 2020or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in...	Limited only to S/N 560-5101.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	30/11/2023	Active	10083388
10083392	AMAC AEROSPACE SWITZERLAND AG			A320-232	Cabin Reconfiguration with Commercial OperationThis reconfiguration modifies the aircraft equipped with EASA STC10050094 allowing private and commercial operation including increasingthe maximum passenger seating capacity to 31 for privateconfigurationand limiting the passenger seating capacity too...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.365 inAmendment 14, CS 25.803, CS 25.807,CS 25.809, CS 25.810, CS 25.811, CS 25.812, CS 25.813, CS 25...	The Change is defined with Revision A of Master Data List documentMDL-HP03-2500The aircraft shall be operated in accordance with Revision C of AirplaneFlight Manual Supplement document AFMS-HP03-2500.Maintenance shall be done in accordancewith Revision A of Instructionsfor Continued Airworthiness d...	EASA STC 10050094 Rev 1 is a pre-requisite to this change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the produ...	01/12/2023	Active	10083392
10083396	AIRBORNE TECHNOLOGIES GmbH			407	Bell 407 - PNP Survey Cabin Configuration.This certificate grants approval for the installation of a TacticalWorkstation in the standard passenger cabin in lieu of the LH aft facingseat.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Document List, Document No. STC-186-G-DOC Rev. 0;Drawings List, Document No. STC-186-G-DWG Rev. 0 dated 28.11.2023;Certification Program, Document No. STC-186-G-CP Rev. 2 dated31.10.2023;RFM Supplement, Document No. STC-186-G-AFM Rev. 0 dated 27.10.2023;Maintenance Manual Supplement, Document No. ST...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/12/2023	Active	10083396
10083402	FOKKER TECHNIEK B.V.	REV. 3		GV-SP	STC_Fokker_AFM-S update G550-JCG	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/approval.This certificate/approval involves a change with an impact on thenoisedatabase. The environmentalprotection requirements areamended as follows: ICAO Annex 16 Volume Iat Edition 8, Amen...	- Compliance Record Report G550-JCG-CRR-0002, issue 1- Compliance Record Report G550-JCG-CRR-0001, issue 2- Master DataList G550-JCG-MDL-0001, issue 1- AFM Supplement G550-JCG-AFM-S-0001, Issue 6- Instructions for continued Airworthiness G550-JCG-ICA-S-0001, Issue 2- MMEL Supplement G550-JCG-MMEL-S...	1. Installation of Fokker Techniek EBG550-0001 and EBG550-0002 islimited to GV-SP MSN5616.2. The use of the Mission Equipment is not permitted when operating theaircraft under Regulation (EU)No 2018/1139, as the mission equipment is designed for coastguardmissions.	15/04/2024	Active	10083402
10083410 (EASA.A.S.00255)	SAAB AB	REV. 1		35A	Installation of ACAS II (Collins TCAS 4000) and dual SSR Mode-Stransponders (Collins IDR 94)Rev. 1: Transfer from Saab Nyge Aero AB to SAAB AB.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	AFM-supplement S31/03Master Drawing List, Instructions, etcin accordance with Saab Nyge AeroIDM 03-17, issue 5, 15/09/2004.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/12/2023	Active	10083410

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083426	MT-PROPELLER ENTWICKLUNG GmbH			182P, 182Q, F182P, F182Q 182H, 182J, 182K, 182L, 182M	Installation of MTV-9-D/200-58( ) propeller on Cessna (F)182 seriesequipped with Teledyne Continental IO-550-D engine.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31.The requirements for environmental protection and the associatedcertified no...	Design according to MT-Propeller Master Documentation List No. E-2861Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-2857Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-2858 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-2859 Rev. 0or...	According limitation section of AFM-S.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/12/2023	Active	10083426
10083442	STERLING CORPORATIOND/ B/A STERLING HELICOPTER	REV. 1	FAA STC SR04785NY	SEE FAA AML	Installation of Outerlink Corporation Air IP systemRev. 1: extends the certification of the installation of OuterlinkCorporation Air IP system to Sikorsky model S-76A, S-76B, S-76C, andS-76D model aircraft.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/...	Sterling Helicopter Master Drawing List, Document ST-22-504-02, Rev. G,dated 10 September 2024<(>,<)>Sterling Helicopter Instructions for Continued Airworthiness, DocumentNo. ST-22-504-03, Rev. A, dated 1 February 2023<(>,<)>or later revisions of the above listed document (s) approved/accepted onbeha...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This installation excludes aircraft configurations appr...	16/10/2025	Active	10083442
10083466	VIH AEROSPACE Inc.		TCCA SH23-29	S-92A	Hatch Close Out Panel Installation.The hatch close out panel installation covers the exposed emergency exitassembly mechanism when equipped with a bubble window installation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List, Document No. VS92-2318-MDL Rev. N/R, dated Sep 2,2023;VIH Instructions for Continued Airworthiness, Document No. VS92-2318-ICARev. N/R, dated Aug 17, 2023or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical Imple...	Prior installation of EASA STC No. EASA.IM.R.S.01282 (Bubble WindowInstallation) is required.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	11/12/2023	Active	10083466
10083469	L3 AVIATION PRODUCTS, INC		FAA ST04560CH	DHC-8-402 DHC-8-400, DHC-8-401	Installation of L3Harris Aviation Products SRVIVR25 Model 7100 CockpitVoice Recorder (CVR)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): 25-660-SC, Non-Rechargeable Lithium BatteryInstallation.- The following paragraph(s) at a later amendment: CS 25.981 (a)(3) atAmdt 1,C...	Installation of L3Harris Aviation Products SRVIVR25 Model 7100 CVRSystem in accordance with L3Harris Aviation Products Index of MasterData List, Doc. No. 8900079, Revision -The aircraft shall be operated in accordance with L3Harris AviationAirplane Flight Manual Supplement,Doc. No. 8210693-900, Revi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/12/2023	Active	10083469
10083487	WEST STAR AVIATION, L.L.C.		FAA ST04519CH	750	Installation of Honeywell FANS-1/A+ Datalink Communication System.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s):SC-F25.1353-01Non-rechargeable Lithium Battery InstallationsSC F-34 Flight Recorders and Data Link Recording.- The following paragraph...	West Star Aviation Master Document<(>,<)> List, A21311L-658, Revision A,dated 03 November 2021<(>,<)>or later revisionsof the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Applicable to S/N: 750-0001 through 750-0500.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	18/12/2023	Active	10083487

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083528	GDC ENGINEERING GmbH			A321-231	Airbus A321 Cabin Reconfiguration – 230EY & Cockpit Power SupplyInstallation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.562 & CS 25.854Amdt. 27.The requirementsfor environmental protection and the associatedcertified noi...	- Description, Certification Plan & LOI: A321E-1DE-250000 Issue D- Master Certification Document List: CCN-A321E-MCDL Issue 2- Instructions for Continued Airworthiness Supplement:A321E-ICA-CPAIssue 1- Master Document Register: A321E-MDR-250000 Issue C- Airplane Flight Manual Supplement: 43857AR006o...	MSN limitation according to document A321E-ICA-CPA (ICA & OperatorManual Supplement) applies.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	14/12/2023	Active	10083528
10083541	AERODATA AG	REV. 1		680A (LATITUDE)	Installation of Aerodata AG Flight Inspection System AD-AFIS-1320.Aerodata Modification Ident: C680A-01Revision 1 of this Approval corrects the information about OSD FC inlimitations section.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25, Amdt 25: 25.1319CS-MMEL, Issue 3The requirements for environmental protection and the associatedcerti...	Master Document List Installation of AD-AFIS-1320 in C680A,documentMDL-A/C-957 Rev 2,dated 11 December 2023.Airplane Flight Manual Supplement Installation of AD-AFIS-1320 in C680A,document AFM-185 Rev 2,dated 03 November 2023.Aircraft Maintenance Manual Supplement Installation of AD-AFIS-1320 inC68...	The performance of Aerodata Flight Inspection System AD-AFIS-1320 hasnot been assessed by EASA.This STC cannot apply toaircraft configurations where any flight crewalerts have been installed in addition to the ones implemented in theoriginal TC design and are not integrated with the original TC Cre...	10/04/2024	Active	10083541
10083547	DOA AESGLOBAL LIMITED			737-800	189Y Passenger Seating LayoutThis modification introduces acabin layout using 63 triple economyclass seats generating a 189 passenger seating configuration withconcurrent removalof foreign FAA STC ST02410SE for aircraft with thisFAA STC as pre-mod configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: 25.1301 (a), 25.1309 (a)(b), 25.1351 (a), 25.1353 (a),CS 25.1431 (a) at Amendment 4, CS 25.1, 25.29 (a)(b, 2...	The change is defined with issue 3 of AESGLOBAL Master DataListAES-737-7282MDL .Maintenance shall be accomplished in accordance with issue 1 ofAESGLOBAL Instructions for Continuous Airworthiness Document AES-TR-3692The OSD-Cabin Crew Data (CCD) approved per the CS-CCD issue 2, iscontained by AESGLOB...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/12/2023	Active	10083547
10083549	SKYTEC AEROSPACE GmbH			A321-271N/-271NX/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216 A319-171N A319-131/-132/-133/-151N/-153N A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Skytec Moveable Class Divider InstallationThis modificationintroduces a Moveable Class Divider for installationin an A320 Family aircraft cabin.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): E-114Photo-luminescent EXIT sign forMovable Class Divider.- The following paragraph(s) at a later amendment: CS 25.1, CS 25.2...	- The change is defined with revision A of Skytec Master Document ListDocument MDL-A32FC005-0016-Maintenance shall be accomplished in accordance with revision A ofSkytec Instructions for Continuous Airworthiness DocumentICAS-A32FC005-0014or later revisions of the above listed document(s) approved/a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/12/2023	Active	10083549
10083557	ALAMO ENGINEERING GmbH			BD-700-1A10, BD-700-1A11	FANS-1A+ over Iridium SatcomInstallation of a Satcom Iridium Datalink Unit with FANS 1/A+ capabilityand removal of the installed Inmarsat Swift 64 satcom system.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.29; CS 25.301;CS 25.303; CS 25.305; CS 25.307;CS 25.561; CS 25.601; CS 25.603; CS 25.605; CS 25.607;2...	- Master Document List MDL20A14AE-02 Rev. A-Instructions for Continued Airworthiness ICA20A14AE-02 Rev. A-Flight Manual Supplement FMS20A14AE-02 Rev. Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/12/2023	Active	10083557

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083560	R&R CONSULTING			ATR 72-212 A	Zero Pax Cabin on ATR72-212ARemoval of all seats for Zero Pax Cabin configuration in preparation ofMaintenance activities.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 Amdt 27: 25.25;25.27; 25.29; 25.31; 25.301; 25.303; 25.305 (a) (c); 25.307 (a); 25.561(a) (b); 25.601...	AFM supplement: RRC_FOR101_01_AAL001_04 dated 19th June 2023ICA supplement: RRC_FOR110_01_AAL001_02 dated 27Th November2023Master Data List: RRC_FOR75_01_AAL001_00 dated 18th December 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The aeroplane must be maintained in accordance with ICA supplement:RRC_FOR110_01_AAL001_02 and operated in accordance with AFM supplementref: RRC_FOR101_01_AAL001_04. Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpr...	19/12/2023	Active	10083560
10083567	STANDARDAERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA ST04543CH	GIV, GIV-X	Installation of a Viasat KuKa Radome Assembly	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): C-130Vibration / Buffeting ComplianceCriteria for Large ExternalAntenna Installation.- The following paragraph(s) at a later...	Installation of Viasat KuKa Radome Assembly in accordance withStandardAero Master Data List 1040248 Revision CThe aircraft must be maintained in accordance with StandardAeroInstructions for Continued Airworthiness 1040293 Revision Cor later revisions of the above listed document(s) approved/ accepted...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/12/2023	Active	10083567
10083570	CENTEX AEROSPACE, INC.		FAA ST09934AC	B300, B300C	Halo 350 Conversion:Increase of the maximum take-off weightlimit to 15,950 pounds (7235kg), installation of a take-offtrim out-of-range warning system and anice mode stall warning system.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:Regulations at the latest amendment 23-0 through 23-6223.1; 23.1; 23.21, 23.23, 23.25(a), 23.45, 23.49(a)(b)...	Master Drawing List (MDL) No. 051-0000 Rev A, dated 10 August 2022,Airplane Flight Manual Supplement (AFMS), Document 051-1 Rev IR, datedApril 2023< (>,<)>Instructions for Continued Airworthiness (ICA), Document 051-30, Rev IR,dated January2023or later revisions of the above listed document(s) appro...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/12/2023	Active	10083570
10083576	NSE			EC135 T3	Installation of a Lightweight Flight Recorder (LWFR) for data recordingand transmission in accordance with STC Data List SDL-00057920AA	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-27 Amendment 10for 27.1; 27.21; 27.25; 27.27; 27.29; 27.251; 27.301; 27.303; 27.305;27.307; 27.561; 27.6...	- Rotorcraft Flight Manual Supplement RFMS-LWFR-EC135 T3H Revision 01- STC Data List SDL-00057920AA Revision A1- Instructions for Continued Airworthiness ICA-00057920AA Revision A2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to helicopters with Helionix cockpit variantThe installation of the Iridium Antenna P/N S67-1575-109 according toAirbus Helicopters (AH) Illustrated Parts Catalog IPC 23-15-02-03 andthe service connection to enable data acquisition(ARINC429) accordingto AH SB EC135H-31-002 are prerequisite....	19/12/2023	Active	10083576
10083580	AVIADECO GmbH			A321-231	12B/C – 184Y/C Passenger Seating LayoutThis modification introduces a cabin layout generating a 196-passengerseating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.853 (a), (c),CS 25.1529<(>,<)> CS 25.1729 at Amendment 27. CS-CCD at Issue 2.The requirements for env...	The change is defined with Revision 1 of AviaDeCo Master Data ListMDL-01923.Maintenance shall be accomplished in accordance with Revision 1 ofAviaDeCo Instructions for Continuous Airworthiness Document ICA-01923.The OSD-Cabin Crew Data (CCD) approved per the CS-CCD issue 2, iscontained by AviaDeCo C...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/12/2023	Active	10083580

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083604	INFINION CERTIFICATION ENGINEERING		TCCA C-LSA23-059/D, ISSUE 1	BD-100-1A10	Interior Refurbishment	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1, CS 25.29, CS25.301, CS 25.561, CS 25.562, CS 25.601, CS 25.603, CS 25.605, CS25.785, CS 25.793, CS 2...	The modification is defined in accordance with Infinion CertificationEngineering Inc. Master Data List MDL-2278-01, Issue 1Installation shall be performed in accordance with InfinionCertification Engineering Inc. Installation Instruction EO-2278-01,Issue 1or later revisions of the above listed docum...	This STC is limited to Serial Number 20136Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	20/12/2023	Active	10083604
10083617	S4A SOLUTIONS FOR AVIATION, S.L			BD-700-1A10	Installation of Dual Iridium antenna	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The requirements for environmental protection and the associatedcertified noise and/ or emissionslevels of the product are unchangedand remain applicable tot...	Certification Plan Ref: GEX_121-12-39, Edition 1 dated 1-Sept-2023Maintenance Manual Supplement Ref: GEX_121-12-30, Edition 1 dated3-Nov-2023or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	BD-700-1A10 Global Express	22/12/2023	Active	10083617
10083618	SABENA TECHNICS BGC	REV. 1		A330-243	Dual cabin reconfiguration with IFE installationRevision 0:20B/C + 268Y/C including IFE installation.Revision 1: New incoming configuration for an a/c fitted with a centralgaseous system.This revision introduces the consequent changes to the approved designto accommodate the different incoming conf...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: - CS-25 at amdt. 4:25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341,25.365, 25.471, 25.561...	Master Data List, Ref. 41092-01-A-MDL Rev01 dated 02 August2024.Instructions for continued airworthiness, Ref. 41092-01-A-ICA Rev01dated 02 August 2024.Aircraft Flight Manual Supplement, Ref. 41092-01-A-AFMS issue 0 dated 13December 2023or later revisions of the above listed document(s) approved/ac...	- As a concurrent requirement of this change, accomplishment of this STCrequires the - simultaneous accomplishment of the following modification:“Installation of a non-electrical floor path marking system” as perLufthansa Technik’s EASA STCNo. 10014507 (originally EASA.A.S. 02580).- SIM card shall be...	05/08/2024	Active	10083618
10083627	DELTA ENGINEERING CORPORATION		FAA STC ST04792NY	BD-500-1A11 BD-500-1A10	Update of Intelsat 2Ku	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Delta Engineering Master Data List (MDL), Doc.No. 0175-11703-2516,Revision A, dated 27 Oct 2023<(>,<) >Instructions for Continued Airworthiness (ICA), Doc. No.0775-11932-2516, Revision A, dated 12 October 2023<(>,<) >Weight Report, Doc. No. D12716-20025, Rev. C, dated 28 September 2023< (>,<)>Reference...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/01/2024	Active	10083627
10083629	321 PRECISION CONVERSIONS LLC	REV. 3	FAA STC ST02716SE	A321-232 A321-231 A321-213 A321-212 A321-211/-212/-213/-231/-232 A321-211	Airbus A321 Passenger to Freighter ConversionConversion of an Airbus A321-200 series from an all-passengerconfigurationto an all-freighterconfiguration (including main deck cargodoor, Class E cargocompartment, 9g barrier reinforcement ofthecabin floor, accommodations for supernumeraries, and asso...	See Appendix A - Certification Basis - Initial Issue dated 04/01/2024.See Appendix B - Special Condition / Equivalent Safety Finding - InitialIssue dated 04/01/2024.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedan...	- Project-Specific Certification Plan (PSCP) and Compliancechecklistfor Airbus A321-200 series Freighter conversion ref. PD-A321-028 rev. G-Airplane Flight Manual Supplement forAirbus Model A321-200 with 321Precision Conversions Freighter Conversion A321-200PCF ref. AFMSPD-A321-046 Rev D-Airplan...	Approval of this change in type design applies to Airbus ModelsA321-200, Variant 000, with CFMI Model CFM56 or IAE V2500 Seriesengines.A maximum of four (4) supernumeraries are allowed when this STC isinstalled.The Airbus Model A321-200 series airplane passenger to freighterconversion has not been e...	27/01/2025	Active	10083629

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083630	DELTA ENGINEERING CORPORATION		FAA STC ST04791NY	737-800	Main deck cargo smoke detection system update.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS 25 amdt. 27: 25.305,25.571, 25.611, 25.613, 25.857, 25.858, 25.869, 25.1301, 25.1310,25.1353, 25.1357, 25.1431, 25.1585...	- Delta Engineering Master Data List (MDL) 0106-11849-2577 Revision Adated 19 October 2023;- Instructions for ContinuedAirworthiness 0706-11910-2577 Revision Adated 15 October 2023;- Airplane Flight Manual Supplement 0606-11926-2577 Revision A dated 6October 2023;or later revisions of the above lis...	Reference Delta Engineering Master Data List for additionallimitationsand conditions and applicable serial numbers.Installation of the configuration covered by STC 10076409 (FAA STCST0690LA) is a prerequisite.Prior to installation of thischange/repair it must be determined thatthe interrelationshi...	05/02/2024	Active	10083630
10083639	GARMIN INTERNATIONAL, Inc.		FAA SR01961WI - 16 JUL. 2021	505	Installation of a Garmin GFC 600H Flight Control System (HFCS) in a Bell505 helicopter.	The Type and OSD Certification Bases for the original pro-duct asamended by the following additional or alternative airworthinessrequirements:- Special Condition(s): FAA Special Condition No. 27– 052– SC, replacing14 CFR 27.1309 (b) and (c) requirements, Amdt. 27-46.- The following paragraph(s) at a...	Master Drawing List, Document No. 005-01095-40, Rev. 9;ODA Certification Plan, Document No. 005-01095-42, Rev. 6;EASA CS-FCD Certification Plan, Document No. 005-01095-EC, Rev. 1;Maintenance Manual with Instructions for Continued Airworthiness,Document No. 190-02081-08, Rev. 4;Rotorcraft Flight Manu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/02/2024	Active	10083639
10083665	PEREGRINE AVIONICS LLC		FAA STC ST01108DE	GULFSTREAM 200/ GALAXY	Installation of Curtiss Wright GSD1000 Digital Flight Data AcquisitionUnit	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Master Drawing List E-CW-22-0002, Rev. B, dated 10 July 2023<(>,<) >Instructions for Continued Airworthiness, Document Number EC-CW-22-0008,Rev. A, dated 7 September 2023<(>,<) >or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Imple...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/01/2024	Active	10083665
10083666	JAMCO AMERICA, INC.		FAA ST02478SE	777-300ER	Installation of an interior reconfigurationInstallation of this STC replaces the low-pressure oxygen flex hoseswith newnon-conductive low-pressure oxygen flex hoses in specificlocations and constitutes an approved Alternate Means of Compliance (AMOC) to paragraph (g) of adopted Airworthiness Directi...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- adopted Special Condition(s): FAA SC25-187A-SC; FAA SC 367-SC; FAASC-611-SC-adopted Equivalent Safety Finding(s): ESF to 25.791 as documented inFAA Memorand...	-Project Specific Certification Plan for Interior Reconfiguration ofVirgin Australia Airlines (VOZ) 777-300ER, CP1977-1, Rev. D, dated July8, 2015-Project Specific Certification Plan ST02478SE MDL Update VirginAustralia Airlines (VOZ) 777-300ER, CP1977-2, Rev. A, dated May 23, 2016-Project SpecificR...	STC ST03415NY “installation of a Panasonic Avionics In-Flight System”must be installed concurrently with this modificationPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair wil...	08/04/2024	Active	10083666
10083681	AERODATA AG			300	Installation of Aerodata AD-MS-1100 Mission System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List MDL-A/C-954, Rev.3Master Assembly Drawing B300-42.01_MSA, Rev. IRAircraft Flight Manual Supplement AFM-181, Rev. 2Maintenance Manual Supplement AMM-1188, Rev. IRMaster Minimum Equipment List MMEL-1012, Rev. IRor later revisions of the above listed document(s) approved/acceptedund...	The function and performance of the Mission System AD-MS-1100 have notbeen assessed by EASA.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect u...	11/01/2024	Active	10083681

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083682	ALOFT AEROARCHITECTS	REV. 2	FAA STC ST04254NY	SEE FAA AML	Installation of Viasat Satcom SoftwareRev. 1 adds Airbus A321-252NX to the AML.Rev. 2 expands the AML to include the 737-800 model.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Data List (MDL), Viasat Document No. 1468130, Rev. 001, dated 9December 2024<(>,<)>Master Data Index List (MDIL), Viasat Document No. 1434333, Rev. 008,dated 10 January 2025<(>,<)>Viasat Instructions for Continued Airworthiness (ICAW) and AircraftMaintenance Supplement, Document No. 1434854,2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approvedl...	02/05/2025	Active	10083682
10083686	AERO INSPECTION PART 21 Ltd.			737-800	Installation of Portable ELTThis change provides instructions to install a Portable ELT in FWD lefthand stowage compartment near Door 1L of the aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS.ACNS.E.LAD. 001;CS.ACNS.E.LAD.010; CS.ACNS.E.LAD.020; CS.ACNS.E.LAD. 110;CS.ACNS.E.LAD.120; CS.ACNS.E.LAD.13...	-MDL B737-25-0110 Revision 01 (Master Document List)-MS B737-25-0110 Revision 01 (Aircraft Manual Supplement)or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Aeroplanes modified by this STC must be maintained in accordance with:-MS B737-25-0110 (AMM supplement)Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adve...	15/01/2024	Active	10083686
10083700	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			680 (SOVEREIGN)	Side Facing Seat Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List ref 2023-21-16 Rev A; Work Instructions ref2023-21-1 IR<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to aircraft SN 0001 to 0500.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	16/01/2024	Active	10083700
10083713	LEE AEROSPACE, INC.		FAA STC ST04723CH	SEE FAA AML	Installation of LAI Windshields	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Installation Instructions, Doc. LAI-INSTL-126, Revision B, dated 8August 2023<(>,<)>Master Data List, Doc. LAI-MDL-126,Rev IR, dated 11 August 2023<(>,<)>Instructions for Continued Airworthiness (ICA), Doc. LAI-ICA-126, Rev Bdated 23 May 2023<(>,<)>or later revisions of the above listed document(s)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	18/01/2024	Active	10083713
10083748	AVIONIK STRAUBING ENTWICKLUNGS GmbH			R 90-230RG	Installation of a Garmin G500 TXi Avionics Suite and associated SystemsThis change includes the installation of a Garmin G500 TXi PFD Systemwith two displays with the related sensors and antennas. Furthermore, aGarmin GI 275 standby indicator and two GPS/COMM/NAV systems Garmin GTN6/750Xi with new a...	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:_ The following paragraph(s) at a later amendment:CS-23 Amendment 4:23, 29, 251, 301, 303, 305, 307, 337, 561, 601, 603, 605, 607, 609, 611,613, 625, 671, 771, 773, 777,1...	Project Description ASR-2022-017-PRD-04-00Flight Manual Supplements ASR-2022-017-FMS-05.1-00/05.2-00Instructions for Continued AirworthinessASR-2022-017-ICA-11.1-00/11.2-00Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/01/2024	Active	10083748

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083756	CANARD AEROSPACE CORPORATION	REV. 1	FAA STC ST04174CH	767-400ER 767-300F 767-300 767-200	Upgrade of Collins GLU-920 MMRs and Collins Mode S Transponders toprovide ADS-B Out FunctionalityRev. 1: adds FAA STC reference.	The Certification Basis for the original product as amendedbythe following additional or alternative airworthiness requirements:CS 25 amt. 4: 25.1301(a)(b)(c), 25.1307 (e) , 25.1309(a)(b)(c) , 25.1315,25.1322, 25.1353(a)(b) (d) , 25.1431(a)(c)(d) , 25.1529, 25.1581(a) ,H25.1, H25.2,H25.3, H25.4CS ACN...	Canard Aerospace Corporation (CAC) Document Control Drawing40202, Rev.B, dated 12 March 2018<(>,<) >Airplane Flight Manual Supplement, Canard Aerospace Document No. 34-3615-06, Rev. NC, dated 31 January 2017< (>,<)>Instructions for ContinuedAirworthiness 34-3615-07 , Rev. A, dated 12March 2018<(>,<)>...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/02/2024	Active	10083756
10083762	PMV ENGINEERING			A330-343 A330-321/-322/-323/-341/-342 A330-243/-243F/-301/-302/-303 A330-201/-202/-203/-223/-223F	ADS-B Out Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 at amdt. 4: 25.1301, 25.1302, 25.1309, 25.1316, 25.1322, 25.1351, 25.1353, 25.1357,25.1431, 25.1529,C...	Master Document List AVI-02380-MDL-S01 R00Instructions for continued airworthiness AVI-02380-ICA R00AFM Supplement AVI-02380-AFMS-S01 R00MMEL Supplement AVI-02380-MMELS R01or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/01/2024	Active	10083762
10083772	JET AVIATION AG			GIV	WLAN ActivationDemonstration of aircraft immunity to IEEE 802.11a/b/g/n/ actransmissions from PEDs for all flight phasesexcept low visibilityapproach operation based on EASA CM-ES-003. Activation of existing cabinWireless LAN System provision.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 Amdt 27 / CS25.869, 25.899, 25.1301(a)(1), (3), 25.1309, 25.1319, 25.1351, 25.1353,25.1357, 25.1360, 2...	- Master Data List JBSL-M-03926MDL-001 ISSUE A- Aircraft Flight Manual Supplement JBSL-M-03926AFM-001 ISSUE AOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This change is applicable to aircraft previously fitted with properlyqualified and certified Wireless Access Point(s) meeting thecertification basis of the aircraft. Furthermore, the Wireless AccessPoint(s) installation must: - be capable to transmit only on IEE802.11a/b/g/n/ac protocols, ora su...	02/02/2024	Active	10083772
10083783	SIRIUM AEROTECH S.L.			ATR 42-500 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	ADS-B Upgrade for ATR 42.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR-25 Change 14Sections 25.29, 25.251, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337,25.341, 25.365, 25.5...	MASTER DATA LIST SA23-64S-MDL Rev 02, December 5, 2023AFM SUPPLEMENT SA23-64S-AFMS Rev 01, November 24, 2023AMM SUPPLEMENT SA23-64S-AMMS Rev 01, November 24, 2023MASTER MEL SUPPLEMENT SA23-64S-MMELS Rev 00, November 20, 2023CONVERSION BULLETIN SA23-64S-CB Rev 02, December 5, 2023Or later revisions o...	Prior to installation of this change aircraft configurationmust complywith concurrent requirements defined in section 1.B. of ConversionBulletin SA23-64S-CB.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	25/01/2024	Active	10083783
10083794	3S CERTIFICATION, LLC		FAA STC ST02016WI	SEE FAA AML	Installation of the Meggitt Wireless Tire Pressure Sensor	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	3S Certification, Master Data List (MDL) 3S18-037-1001, Revision IR,dated 16 November 2023<(>,<)>3S Certification, Instructions for Continued Airworthiness (ICA)3S18-037-6101, Revision 1.0, dated 8 November 2023<(>,<)>or later revisions ofthe above listed document(s) approved/accepted onbehalf of E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	29/01/2024	Active	10083794

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083795	SABENA TECHNICS BGC	REV. 1		AS 332 L, AS 332 L1 AS 332 C, AS 332 C1	TCAS II Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program, ref. 2113-01-A-CP, revision 5, dated15/11/2023Declaration of Compliance, ref. 2113-01-MDL, revision 0, dated 26/01/2024Rotorcraft Flight Manual Supplement, ref. 2113-01-A-RFMS-F00, revision3, dated 18/01/2024Instructions for Continued Airworthiness, ref. 2113-01-A-ICA, revisio...	The modifications MOD 2113-02 is a pre-requisite for the embodiment ofthis design change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	30/01/2024	Active	10083795
10083796	JADE ENGINEERING PTE. LTD.			A320-251N	Full Economy Class Interior ModificationThis design change includes a full-economy-class-configuration of ETSOC127a Economy Class seats from Recaro.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 at amendment 11paragraphs: 25.365(e)(2), 25.561(a)(d), 25.787 (a)(b), 25.789(a),25.791(a)(b)(c) (d)(e), 25...	Compliance Document List, JD-41BC03-1 Revision A, 5th Dec 2023Master Drawing List, JD-41BC02-1 Revision A, 4th Dec 2023Supplemental ICA and EWIS ICA Source Document, JD-41BC01-1 Revision 0,5th Dec 2023Aircraft Maintenance Manual Supplement, AMM-AIC41B-1, 29th Nov 2023or later revisions of the aboveu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/01/2024	Active	10083796
10083800	Q.C.M. DESIGN GmbH			60	DUAL FMS UNS-1Lw Upgrade	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	L60X-QCM34-004-M1-ICA Instructions of Continuous Airworthiness Initialissue;L60X-QCM34-004-M1-AFM Aircraft Flight Manual Supplement Initial issue;L60X-QCM34-004-M1-MMS MaintenanceManual Supplement Initial issue;L60X-QCM34-004 Certification Report Revision 2or later revisions of the above listed doc...	Applicable to aircraft with the following configuration:• Dual Universal UNS-1B(+) Flight Management System• Dual Collins Proline 4 Flight Display System.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously ins...	30/01/2024	Active	10083800
10083806	PEREGRINE LLC		FAA STC ST02004WI	SEE FAA AML DATED 2 DEC. 2022	Installation of the Garmin GI-275 Instantaneous Vertical SpeedIndicators (IVSI) as a replacement for the existing Honeywell IVA-81Instantaneous Vertical Speed Indicators.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25.301, CS 25.303, CS 25.305(a)(b), CS 25.307(a), CS 25.321, CS25.471, CS 25.561(c), CS 25.601, CS 25.603<(>,<)>CS 25.60...	1. Master Drawing List, Document No. E-SE-21-0022, Rev. B, dated 1December 2022;2. AFMS, Document No. E-SE-21-0019, Rev. IR, dated 30 November 2022;or later revisions of the abovelisted document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ U...	This STC does not allow for any other Input/Output (I/O) ports to beused except those defined within this document.ThisSTC does not approve the installation of the GI-275 IVSI with abackup battery.Prior to installation of this change/repair it must be determined thatthe interrelationship between th...	21/05/2024	Active	10083806
10083815	PEREGRINE LLC		FAA STC ST01985WI	SEE FAA AML DATED 23 OCT 2023	Installation of the Garmin GI-275 I Electronic Standby Instrument (ESI)as a replacement for the existing 3ATI Standby Attitude DirectionIndicator (ADI) or for the existing 3-inch Standby Altimeter (Cessna 650model only).	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25.301, CS 25.303, CS 25.305(a)(b), CS 25.307(a), CS 25.321, CS25.471, CS 25.561(b)(3), CS 25.601<(>,<)>CS 25.603, CS 25...	1. Master Drawing List, Document No. E-SE-21-0042, Rev. B, dated 12December 2022;2. AFMS, Document No. E-SE-21-0049, Rev. IR and E-SE-21-0059, Rev. IR,dated 8 December 2022;or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical Implemen...	This STC does not allow for any other Input/Output (I/O) ports to beused except those defined within this document.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intro...	29/04/2024	Active	10083815

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083826	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03614NY	FALCON 900EX (F900EX)	Installation of the Viasat Global Aero Terminal GAT-5510 Ka-BandSatellite Communications System	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	(1} Master Data List F9XW-D0108-005 Rev. IR dated 26 September 2023<(>,<)> (2) Instructions for Continued Airworthiness F9XW-D0108-155 Rev. IRdated 25 September 2023<(>,<)>(3) Airplane Flight Manual Supplement F9XW-D0108-150 Rev. IR dated 26September 2023< (>,<)>or later revisions of the above listedb...	Applicable to Dassault Aviation Falcon 900 EX aircraft withKA Radomeinstalled per Dassault Aviation M-Opt 415, or Mod 6067, or ServiceBulletin 554.Prior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed...	02/02/2024	Active	10083826
10083836	BOEING IRELAND LIMITED			787-8	Boeing 787-8 - Avianca Cabin Reconfiguration - 250 to 291 PAXReconfigure 13 QTY 787-8 aircraft from 250 PAX (28 BC / 222EC) to 291PAX (20 BC / 271 EC)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, 'Boeing 787-8 – Avianca CabinReconfiguration', BIL-00238-APP, Revision 00,dated 1st February 2024<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/02/2024	Active	10083836
10083840	AEROTEC & CONCEPT			SEE APPROVED MODEL LIST (AML)	LTE TRANSCEIVER INSTALLATION	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Plan AE22101PCDP, issue 02, 17 January 2024For other associated documents refer to the Annex dated 05 February 2024or later revisions of the above listed document(s)approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/02/2024	Active	10083840
10083873	DUKE AVIATION CO. LLC		FAA SA00153DE	60, A60, B60	Installation of 130 Ampere alternator retrofit system to replaceexisting generator system	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23.1365(e)(1) & (2).The requirements for environmental protection and the associatedcertified noise and/a...	Firewall Forward Installation Data Package, Revision B, dated March 14,1995Flight Manual Supplement, document FWF-FLMS,Rev. no (-), dated April12, 1995or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/02/2024	Active	10083873
10083883	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special transport – 2* Airbus Helicopter H160 on MPP5This approval covers Issue 59 of ATI modification ST25MOD020 for thetransport of two Airbus Helicopter H160 in the Beluga ST Main Deck CargoCompartmentIssue 1 of ATI modification ST25MOD020 (applicant's reference) wasdeveloped, reviewed, tested a...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Change Approval Sheet (CAS) ST25MOD020Ed59 Issue 2 dated 09 February2024- Change Certification Plan (CCP) ST25MOD020Ed59 Issue 4 dated 12January 2024- Approved Document Dossier (ADD) ST25MOD020 Ed59_ADD Issue 3 includingAFM, WBM and MMELsupplements as enclosed in Independent Check SheetICS02 Issu...	- The dangerous goods installed in the payloads have to comply with theIATA Dangerous Goods Regulation (or any relevantAviation Authorityregulation).- This approval covers H160 helicopter as described in Airbus HelicopterTechnical Note U075A0099E01 issue B and complemented by preparationinstruction...	09/02/2024	Active	10083883
10083887	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			A321-231	220Y/C Passenger Seating LayoutThis modification introducesa cabin layout generating a 220-passengerseating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision 5 of Turk Hava Yollari TeknikCertification Programme C0399-CEP-05<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/02/2024	Active	10083887

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083889	ALAMO ENGINEERING GmbH			737-700, 737-800	Installation of Ku-SAT SD Plane SimpleBasing on existing EASA approvals for a tail-fin radome and an aircraftinternal data<(>&<)>voice communication network (including wireless andL-Band Satcom) a Ku-Band Satcom antenna system has been installed here.The antenna and microwave unit were mounted in th...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS25 Amdt.27 for 25.1319.The requirements for environmental protection and the associatedcertified noise and...	Instructions for Continued Airworthiness ICA21A50AE-01 Rev A;Flight Manual Supplement FMS21A50AE-01 Rev A;Master Document List (MDL) MDL21A50AE-01 Rev A<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	EASA STC No. 10060445, Lufthansa Technik Two-In-One-solution (TIOS) mustbe previously or concurrently embodied for the aim of the presentmodification.Prior to installation of thischange/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously install...	13/02/2024	Active	10083889
10083907	COMPANIA ESPANOLA DE TECNICAAERONAUTICA, S.A.			1900D	Installation of Dual GTX3000 Transponder for ADS-B Out capability	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: Refer to Appendixdated 15/02/2024.The requirements for environmental protection and the associatedcertifie...	Master Document and Drawing List, document D2305-0001, Ed 02Aircraft Flight Manual Supplement, document D2305-0017, Ed 01Maintenance Manual Supplement, document D2305-0016, Ed 01or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Applicable to Textron Beechcraft aircraft Model 1900D S/N: UE-197,UE-69, UE-301, UE-367, UE-248, UE-103, UE-196 with the following pre-modconfiguration as detailed in ModificationDescription ref. D2305-0003Ed03.Prior to installation of this change/repair it must be determined thatthe interrelations...	15/02/2024	Active	10083907
10083908	TEXTRON AVIATION Inc.		FAA STC SA00486WI	1900D	Installation of Cabin Ordinance (Fasten Seat Belt / No Smoking) Signs inBeech Model 1900D Airplanes.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Raytheon Aircraft Services Master Drawing List 16-000309-MDL, Revision (--), dated 21 November 1996, or later revisions of the above listeddocument (s) approved/accepted on behalf of EASA in accordance with theTechnical Implementation Procedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/02/2024	Active	10083908
10083910	BELL TEXTRON, Inc.		FAA STC SR11252DS	412EP	Installation of Additional Hoist Cable Cut Switches	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	1. Master Drawing List, Report No. AA-22025, Revision B, dated 13 April2023;2. Aeronautical Accessories Rotorcraft Flight Manual Supplement, ReportNo. AA-22033<(>,<)> No Revision,dated 7 August 2023;3. Aeronautical Accessories Instructions for Continued Airworthiness<(>,<)> Report No. AA-22034, Noo...	This STC is applicable to all serial numbers for Bell Textron Inc. Model412EP. Installation of FAA STC SH3189SO (External Non-HEC Hoist) is apre-requisite on EASA STC 10083910 forthe installation of this STCdesign change. With the validation of FAA STC SH3189SO prior to theexistence of EASA, this S...	27/06/2024	Active	10083910
10083914	NEXTANT AEROSPACE, L.L.C.	REV. 3	FAA ST04612CH	BD-700-2A12 BD-700-1A11 BD-700-1A10	Installation of a SpaceX Starlink Aviation SystemRev. 1: Addition of the a/c model BD-700-2A12 and correction of theCertification Basis for a/c the model BD-700-1A10.Rev.2: Correction of typos of the a/c model.Rev. 3: Addition of the Bombardier BD-700-1A11 aircraft model	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): ESF-B25.251-01 Issue 2 on 'Vibration andBuffeting'The requirements for environmental protection and the associatedcertified nois...	Nextant Aerospace Master Data List. Doc. No. NT0079-MDL0-0100 Rev. J,dated 13 February 2025 andFor BD-700-1A10 model:Airplane Flight Manual Supplement, Nextant Aerospace Doc. No.NT0079-AFMS-0100, Revision IR, dated 2 February 2024, Instructions for Continued Airworthiness Nextant Aerospace Doc. No.N...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This modification requires that the aircraft be shown t...	24/09/2025	Active	10083914

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083918	WIPAIRE Inc.	REV. 1	FAA STC SA02031WI	AT-802A AT-802 AT-602	Installation of a True Blue Power TB60 Lithium ION Battery to replacethe existing lead-acid batteryRev. 1: Transfer from "Peregrine, LLC." to "Wipaire, Inc."	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Drawing List (MDL), No. E-WP-22-0002, Rev. IR, dated24 January2024<(>,<)>Airplane Flight Manual Supplement (AFMS), No. E-WP-22-0009, Rev. IR,dated 24 January 2024<(>,<)>orlater revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Impl...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/11/2024	Active	10083918
10083919	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04349AT-D	GV-SP GIV-X	Laseref V to Laseref VI Upgrade	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	1. Gulfstream Aerospace Corporation Index List GDL 100000077, Revision(-), dated 2 November 2023;2. FAA accepted Instructions for Continued Airworthiness CE41113A002,Revision (-),dated 11 October 2023 for Gulfstream Model GIV-X;3. FAA accepted Instructions for Continued Airworthiness CE51113A002,Re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/02/2024	Active	10083919
10083933	MAGELLAN AEROSPACE	REV. 1	TCCA SH93-41	212	Installation of Wire Strike Protection System.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Configuration 1 - Installation P/N 364-83300-1 (Standard Skid Gear) orP/N 364-83300-3 (High Skid Gear).• Drawing List EM105301 Issue F TCCA Approved 30 June 2011.• Instructions for Continued Airworthiness PM-965-041 Issue C – 17 April2007.Configuration 2 - Installation P/N 364-83100-11.• Drawing L...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/02/2024	Active	10083933
10083940	AEROTEC & CONCEPT			A320-232	180 Y/C Passenger Seating LayoutThis modification introduces a cabin layout generating a 180-passengerseating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.562 (a) through (c)(4), (c)(7) through (c)(8) at Initial Issue.The requirements for environmental prot...	The change is defined with Revision 0 of Aerotec & Concept Master DataList AE23112MDL.Maintenance shall be accomplishedin accordance with Revision 0 ofAerotec & Concept Instructions for Continuous Airworthiness DocumentAE23112ICAor later revisions of the above listed document(s) approved/acceptedun...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/02/2024	Active	10083940
10083963	SKY SERVICE F.B.O. INC.		TCCA SA15-5	GULFSTREAM 200/ GALAXY	Dual UASC UNS-1Ew FMS with FANS-1/ A+ Data Link Option	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement, Document No. FMS14060-1, Rev. BFlight Manual Supplement Document No. FMS14060-2, Rev. N/ CInstructions for continued airworthiness, Document No. ICA14060-1, Rev.CMaster Drawing List, Document No. MDL14060, Rev. GOrlater revisions of the above listed document (s) approved/acc...	STC ST09625SC (EASA.IM.A.S.01490) and ST03358AT-D (EASA.IM.A.S. 02338)are prerequisites to this approvalLPV approach procedure using the UNS-1Ew FMS are prohibited.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevi...	23/02/2024	Active	10083963

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10083965	STELLAR BLU SOLUTIONS GmbH			A319-153N/-171N A319-131/-132/-133/-151N A319-111/-112/-113/-114/-115	CABANNER Infotainment System InstallationInstallation of a WiFi system and LCD screen on passenger seats.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	. Master Document Register: A319J-MDR-233000 Issue A. Instructions for Continued Airworthiness: A319J-ICA-BRX Rev 01. OSD CCD Supplement: A319J-CCD-BRX Rev 00or later revisions ofthe above listed document(s) approved/ acceptedunder the EASA system.	Installation on aircraft models only that satisfy the configurations andcriteria defined in document FCS-233-A319J Iss.01, or later revisionapproved under the EASA system.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any o...	23/02/2024	Active	10083965
10083987	APTOZ EHF.	REV. 1		767-300	Structural provisions for SATCOM systemThis modification introduces structural provisions for a SATCOM systemfor 767-300 BCF aircraftRev. 1: Transfer of STC from Icelandair EHF toAptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1, CS 25.29, CS25.301, CS 25.303, CS 25.305 (a)-(b), CS 25.307 (a), CS 25.337, CS25.341, CS 25.571 (a...	The change is defined with Revision A of Icelandair EHF documentMCR-767-5310-028.The aircraft shall be maintained in accordance with Revision IR ofIcelandair EHF Instructions for Continued Airworthiness documentICA-767-5310-028or later revisions of the above listed document(s) approved/acceptedunder...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10083987
10083990	DIAMOND AIRCRAFT INDUSTRIES GmbH			DA 62	MTOM 2360 kgTo increase the operational range/endurance of the DA 62 the MaximumTake-Off Mass will be increased to 2360kg. The Maximum Landing Mass andthe Maximum Zero Fuel Mass will not be changed. Re-investigations inflight characteristics and flight structure.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows:CS-36 Amendment 6...	Installation per STC 62-005Operation according to AFM Supplement STC-62-005 Rev. 0 to Doc. No.7.01.25-E / 11.01.05-E and AFM Supplement STC-62-005-S03 Rev. 0 to Doc.No. 7.01.25-E / 11.01.05-Eor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/02/2024	Active	10083990
10083995	JET AVIATION AG			737-900ER 737-8200, 737-9, 737-900 737-700, 737-8, 737-800	Seat to floor interfaceBOEING 737 Series – isotropic intercostals for installation of seats anddivans.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 at amdt. 27: 25.301, 25.303, 25.305, 25.307, 25.321, 25.561,25.562, 25.571, 25.601, 25.603, 25.605, 25...	Master Data List, Ref. JBSL-M-03796MDL-001 issue B dated 24November2023<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/02/2024	Active	10083995
10084002	AIRCRAFT INTERIOR REFURBISHMENT ESPANA S.L.			A330-343	Rearrangement and installation of passenger seats: 386 PAX (12 B/C + 374Y/C)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master data list, Ref. A330C166-MDL001 Issue 2 dated 30 January 2024Instructions for continued airworthiness, Ref. A330C166-MMS001 issue 1dated 25 October 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/02/2024	Active	10084002
10084007	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04348AT-D	SEE FAA AML	Installation of Honeywell AIS-2000 High Definition (HD) Upgrade onGulfstream Models: G-IV, GIV-X, GV, GV-SP and GVI	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	For Gulfstream Aerospace Model G-IV<(>,<)> Instructions forContinuedAirworthiness, CE41507A009, Revision A, dated 17 October 2023<(>,<)> ForGulfstream Aerospace Model GIV-X, Instructions for ContinuedAirworthiness, CE41507A010, Revision A, dated 17 October 2023<(>,<)>For Gulfstream Aerospace ModelA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	04/03/2024	Active	10084007

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084015	CENTRI-LUBE TECHNOLOGIES, LLC			B60 A60 60	Engine baffle access panel installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Firewall Forward Drawing No. FFT-PRTB60-BFLACC-001, Rev. -,dated 7/9/04or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/02/2024	Active	10084015
10084024	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A330-243	Introduction of single class economy cabincabin re-configuration from multi-class cabin to single class byreplacement of existing ETSO c127 with new ETSO c127a Geven PIUMA AQModel	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List ref: JCAERO/MDL/1178 issue 1.1 dated Feb 21st 2024AMM supplement ref: JCAERO/AMM/1178-1 issue 1.0 dated 14th July 2023or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplanes operating with this STC must be maintained in accordance withAMM supplement referenced JCAERO/AMM/1178-1.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will intr...	01/03/2024	Active	10084024
10084031	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04150AT	A321-271N, 272N A321-251N, -253N A321-212, -213, -231, -232 A321-111, -112, -131, -211 A320-232, -233, -251N, -271N A320-211, -212, -214, -231 A319-115, -131, -132, -133 A319-111, -112, -113, -114	Installation of an Aviator 300 (D) Communications System, WirelessAccess Point, and Shadin Adapter (forantenna steering) on Airbus A319/ A320/ A321 series aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 0: 25.29, 25.773, 25.1307, 25.1431, 25.1529, 25.1541,25.1581CS 25 amdt. 5: 25.1301CS 25 amdt. 8: 25.1581CS 25 a...	1. Master Drawing List 212096-MDL, Revision X, dated 20 June 2019;2. Instructions for Continued Airworthiness (ICA) document 212096 - ICA,Rev. E, dated 13 September 2017;3. Airplane Flight Manual Supplement 214174-FMS, Rev A, dated 4 December2017;or later revisions of the above listed document(s) app...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/03/2024	Active	10084031
10084032	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04483AT	BD-500-1A11 BD-500-1A10	Installation of the Avionics Support Group Constant Friction Mount(cfMount) with Cradle	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt. 0: 25.29, 25.303, 25.561, 25.601, 25.625, 25.773, 25.789,25.1529, 25.1541CS 25 amdt. 1: 25.305, 25.307, 25.613C...	1. Master Drawing List, 219223-MDL, Revision A, dated 14 January 2020;2. Instructions for Continued Airworthiness (ICA) document 219223-ICA,Rev. IR, dated 31 October 2019;or laterrevisions of the above listed document(s) approved/acceptedonbehalf of EASA in accordance with the Technical Implementa...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/04/2024	Active	10084032
10084056	MICRO AERODYNAMICS, INC.		FAA STC SA00403SE	AT-501, -502, -502A, -502B AT-401B, -402,-402B AT-400, -400A, -401, -401A AT-300/-301/-302 AT-200, -300, -400	Installation of Vortex Generators on the wings	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protectionand the associated certified noise and/ or emissions levels of theproduct are unchanged and remainapplicable to thiscertificate/approval.	Micro AeroDynamics Drawing Package MA2073, Revision C,dated19 March 2013, for Type Certificate (TC) A9SW airplanes;Micro AeroDynamics Drawing Package MA2074, Revision C,dated 19 March 2013, for TC A17SW airplanes; andInstallation Manual MA2075, Revision D, dated 19 March 2013,or later revisions ofb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.If more than five vortex generators are damaged or miss...	05/03/2024	Active	10084056
10084057	LUFTHANSA TECHNIK AG			A320-214	A320 AERQ IFE IntegrationIntegration of a seat-centric IFE system and seats replacement	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Design Document STDD23-22/12M Issue 1 Rev. 0Airplane Flight manual Supplement A-00-23/33-AFM Issue 1 Rev. 0Instruction for Continued Airworthiness A-00-23/33-ICAIssue 2 Rev. 0Cabin Crew Data A-00-23/33-CCD Issue 2 Rev. 0Flight Crew Data A-00-23/33-FCD Issue 2 Rev. 0or later revisi...	Only applicable to aeroplanes not required to comply with JAR/CS 25.562(c)(5) and (c)(6).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	06/03/2024	Active	10084057

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084071	ANUVU OPERATIONS LLC	REV. 1	FAA STC ST04380AT	737-8	Installation of Row 44 Broadband Antenna provisions on Boeing 737-8aircraftRev. 1 adds an alternate installation configuration: ARINC 791 compliantprovisions installation, featuring an antenna mounting plate, sevensmall doublers, and a radome/ring.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS25 amdt. 13: 25.1, 25.21, 25.23, 25.27, 25.111,25.113, 25.119,25.121, 25.13, 25.177, 25.181, 25.251, 25.301...	Master Data Index List Document No. RWC100-0007-00, Revision D, dated 16April 2025;Approved Airplane Flight Manual Supplement in accordance with MasterData Index List Document No.RWC100-0007-00, Revision D, dated April 16,2025;FAA Accepted Instructions for Continued Airworthiness as identified inMa...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/06/2025	Active	10084071
10084081	RECAERO			A330-202	Cabin reconfiguration	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List (MDS) Doc Nr.: RCP036MDL001 Issue (Rev.) 3Aircraft Manual Supplement Doc Nr.: RCP036AMS001 Issue (Rev.) 1Operating Manual Supplement Doc Nr.: RCP036OMS001 Issue (Rev.) 1or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Aeroplane configurations changed per this STC (i.e. with Recaero premiumeconomy seats installed) are considered to be the same aircraft as theA330-200 baseline configurations (i.e. without Recaero premium seatsinstalled). Cabin crew operating aeroplanes changed per this STC mustcomplete aircraft dif...	11/03/2024	Active	10084081
10084086	SPAES GmbH & Co. KG			EC135 T2+ EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of an external VHF Antenna in accordance with MasterDocument List MDL-135-660-23-01	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-27 Amendment 10for 27.1316.The requirementsfor environmental protection and the associatedcertified noi...	- Rotorcraft Flight Manual Supplement FMS-135-660-23-01 Revision 1.0- Master Document List MDL-135-660-23-01 Revision 5- Instructions for Continued Airworthiness ICA-135-660-23-01Revisio n 2or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Limited to helicopters with CPDS cockpit variantRetrofit ofthe emergency floatation system as per Airbus HelicoptersService Bulletin (SB) EC135-32-011 is prerequisite.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any other...	12/03/2024	Active	10084086
10084109	HELI AUSTRIA GmbH			MD900	Installation of Garmin G500H TXi Flight Deck into MD Helicopters MD 902	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): CRI F-01, Lithium Battery installationThe following paragraph(s) at a lateramendment: CS-ACNS, issue 4CS ACNS.B.VCS.001, CS ACNS. B.VC...	Master Document List, Doc No. HAU-D-065-001, Rev. 0Installation Manual, Doc No. HAU-D-065-004, Rev. 0Flight Manual Supplement, Doc No. HAU-D-065-005, Rev. 0Instructions for Continued Airworthiness, Doc No. HAU-D-065-006, Rev. 0Or later revisions of the above listed document(s) approved/acceptedunder...	Limited to VFR operation. Installation is not NVIS approvedPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the prod...	14/03/2024	Active	10084109
10084111	KNSI AVIATION ENGINEERING LIMITED	REV. 1	UK.STC.00270 REVISION 00	A321-251NX	Cabin reconfiguration of A321-251NX aircraft: Installation of ACROseries 9 Economy Class Seats (232 pax)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 Amdt 26: 25.25,25.27, 25.301, 25 303, 25.305, 25.307, 25.337, 25.341, 25.561, 25.562,25.601, 25.603,2...	23U076-MDL-001 Rev 01 – Master Document List23U076-CCD-001 Rev 01 – Cabin Crew Data Supplementor later revisions of theabove listed document(s) accepted by EASA inaccordance withthe Technical Implementation Procedures of EU/ UKBilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/03/2024	Active	10084111

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084122	VAN RIEMSDIJK ROTTERDAM B.V.	REV. 1		747-400, 747-400F, 747-8F	RZY Container, P/N 1304-30-0100 and P/N 1304-30-0101 for transportationin the main cargo compartment.Rev. 1: typos corrected.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt 27:25.301(a), 25.303, 25.305(a) , 25.305(b) , 25.307(a) , 25.365(e) , 25.603, 25.605(a)(b), 25.60...	Weight & Balance Manual supplement RRM648-1 issue 2Weight &Balance Manual supplement RRM648-2 issue 2Weight & Balance Manual supplement RRM648-3 issue 3Component Maintenance Manual RRM647 Issue 3Component Maintenance Manual RRM647-1 Issue2Certification program RR353 Issue 4or later revisions of th...	Applicability to Model 747-400 limited to cargo configuration as perBoeing Service Bulletin 747-00-2004 "747-400BCF" or"747-400SF".	05/04/2024	Active	10084122
10084123	SIA "AEROKNOW"			SEE EASA APPROVED MODEL LIST	installation of a Low-Frequency Underwater Locator Beacon (LF-ULB).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR-25 Change 15Sections 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341,25.561, 25.571, 25.6...	Master Document List, Ref. PR00311-MDL-001, Rev. 2, Date: 01.03.2024Instructions for Continued Airworthiness Supplement, Ref.PR00311-ICAW-001, Rev. 5, Date: 01.03.2024ModificationBulletin, Ref. PR00311-ACC-001, Rev. 2, Date: 01.03.2024Or later revisions of the above listed document(s) approved/ acce...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/03/2024	Active	10084123
10084125	ICARIUS AEROTECHNICS			PC-6/B2-H2, PC-6/B2-H4	STC ICARIUS 006 - PC-6 Reinforced FlapThe change consists of the installation of two additional ribs in theinboard partof the RH flap and a 0.6mm protective plate on the lowersurface.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Programme: ICARIUS006_ Certification Programme_Edition 4dated 15 December 2023<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/03/2024	Active	10084125
10084128	AIRBORNE TECHNOLOGIES GmbH			CN-235-300	STC-AT-180, CASA CN235 Survey Configurationinstallation of a surveillance gimbal, the Satcom Antenna and theactivation of the whole mission equipment	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement, Doc. No. STC-180-G-AFM, Rev. 0Maintenance Manual Supplement<(>,<)> Doc. No. STC-180-G-AMM, Rev. 0Installation Instructions, Doc. No. STC-180-G-II, Rev. 0Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	OEM Major Change CN235-300 SM01 Version – Installation of FLIR, Radar,SLAR and other miscellaneous equipment and Airborne TechnologiesSTC-AT-182 (EASA STC 10082475) have to be installed prior this STCPrior to installation of this change/repair it must be determined thatthe interrelationship betweenp...	18/03/2024	Active	10084128
10084129	DUNCAN AVIATION, Inc.		FAA STC SA01775WI	525C	Installation of Norwegian Special Mission UNIFIS 3000 Flight InspectionSystem	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	(1) Duncan Aviation, Inc., STC Master Document List CERTDOC-0000001863,Rev.B dated 17 June 2015<(>,<)>(2) Duncan Aviation, Inc., Airplane Flight Manual SupplementCERTDOC-001950, Rev.A, dated 17 June 2015<(>,<)>Duncan Aviation, Inc., Instructions for Continued AirworthinessCERTDOC-OOI952, Rev. B, dat...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/03/2024	Active	10084129

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084132	HANSJOERG STREIFENEDER GLASFASER-FLUGZEUG-SERVICE GmbH			ASH 25, ASH 25 E, ASH 25 M	Hand rudder control for ASH 25	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC-D22-D01.- The following paragraph(s) at a later amendment: CS 22 Amdt.3; CS22.143, 147, 151, 152, 161, 655, 671, 675, 685 and 689...	- Flight manual supplement: Anhang A Flughandbuch SeitenruderHandsteuerung, Ausgabe 01,Stand 03.05.2023- Maintenance manual supplement: Anhang B Wartungshandbuch ZusätzlicheHandbremse am vorderen Steuerknüppel, Ausgabe 01, Stand 03.05.2023- Flight manual supplement: Anhang A Flughandbuch Seitenruder...	Self-launch with hand rudder control is not permitted.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product....	27/03/2024	Active	10084132
10084162	LEARJET Inc.		FAA STC ST00202BO	BD-700-1A11 BD-700-1A10	Installation of Environmental Control System Ice Pellet Filter	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Bombardier Aerospace Master Document List BAS67017014<(>,<)> Rev. B,dated 6 April 2005<(>,<) >Instructions for ContinuedAirworthiness BAS67017014-IFCA-1, Rev. A,dated 7 April 2005< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Techn...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/03/2024	Active	10084162
10084187	MT-PROPELLER ENTWICKLUNG GmbH			PA-46-500TP	Installation of Pratt & Whitney PT6A-135A engine in PA-46-500TP aircraftseries.Pre-requisites for the Installation of the PT6A-135A engine are: 1. MT-Propeller STC EASA 10047226 / FAA SA03446NY (Installation of5-Blade MT-Propeller Model MTV-27-1-E-C-F-R(P)/ CFR203-58d) 2. Garmin STC 1006...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: CS-36 Amdt 6, FA...	According to MT-Propeller Master Documentation List No. E-3930 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-3932Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-3933 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-3934 Rev. 0or later...	1. According limitation section of AFM-S2. Prerequisites for the Installation of the PT6A-135A engine are: - MT-Propeller STC EASA 10047226 / FAA SA03446NY (Installation of5-Blade MT-Propeller Model MTV-27-1-E-C-F-R(P)/CFR203-58d) - Garmin STC 10064794 / FAA SA02571SE (Installation ofG...	25/03/2024	Active	10084187
10084189	PMV ENGINEERING	REV. 1		BD-500-1A10	CABIN HUMIDIFICATION SYSTEM: “STEP 1” PROVISIONSRev. 1: “STEP2” ACTIVATION added	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List “Provisions” ECS-00130-MDL-S01 Rev 02Master Data List “Activation” ECS-00130-MDL-S02 Rev 01ICA supplement ECS-00130-ICA Rev 02or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/07/2024	Active	10084189
10084198	DOA21 LIMITED	REV. 1		BD-500-1A10	Introduction of cabin Interior “ATT2”Rev. 1: Typo correctedin limitations section.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- As per CRI PCRI-A-101-60086627 “Certification Basis” Issue 3.The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	Master Document List D21.MDL-0007 Issue 1AFM Supplement D21.FMS-0002 Issue 2Maintenance Planning Document D21.MPDS-0004Issue 1OSD FCD crew training D21.FCDTRN-0002 issue 2OSD CCDAircraft Difference Table D21.ADT-0002 issue 2OSD MMEL Supplement D21_MMEL-0003 Issue 3or later revisions of the above l...	- Airworthiness limitations as per Maintenance Planning Document.- Aeroplane configurations changed per this STC are considered to be a“variant” to the A220 (BD500-100/-300) commercial configurations. Cabincrew operating aeroplanes changedper this STC must complete aircraftdifference training in ac...	03/04/2024	Active	10084198

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084223	HONEYWELL INTERNATIONAL Inc.		FAA ST02765LA	BD-100-1A10	Installation of Honeywell EDG-100 Connected Engine Data Access System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): 25-792-SC Electronic System Security ProtectionFrom Unauthorized ExternalAccess, 25-793-SC Electronic System SecurityProtection From-...	Installation of the Honeywell EDG-100 Connected Engine DataAccessSystem in accordance with Honeywell Master Drawing List 756-0275-001,Revision A.Honeywell Instructions for Continued Airworthiness document number756-0275-800, Revision A must be made available to the operatoror later revisions of the...	The installer must determine that the AS907-2-1A Light MaintenanceManual, 72-05-22 supports the use of the EDG-100 Connected Engine DataAccess System prior to incorporating this modification on a Challenger350 The installer must determine that the AS907-1-1A Light MaintenanceManual, 72-05-12 support...	02/04/2024	Active	10084223
10084242	DASSAULT AIRCRAFT SERVICES (DAS)		FAA ST03607NY	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	EASA Validation of ST03607NYInstallation of Honeywell RDR 7000 Weather Radar in Dassault AviationMystere-Falcon 900 andFalcon 900EX.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1317(b) atamdt. 3.The requirements for environmental protection and the associatedcertified noise and...	- MDL F9XW-D0103-005 Rev. D- AFMS F9XW-D0103-150 Rev. A- ICA F9XW-D0103-155 Rev. Bor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	This STC is applicable to Mystere-Falcon 900 airplane serialnumbers 001 through 202 and Falcon 900EX airplaneserial numbers 001 through 096 and 098 through 119.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherprevious...	05/04/2024	Active	10084242
10084243	NOVA SYSTEMS & ENGINEERING LIMITED			737-800	Boeing 737-800 - Cabin Reconfiguration (189 Y/C)This Project installs a G2 galley at the forward RH area andreconfigures the current 189 Y/C LOPA,into a new 189 Y/C LOPA.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List, 'Boeing 737-800 Cabin Reconfiguration (189 Y/C),NSI-200670-01-MDL-01, Issue 2,dated 5th April 2024<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/04/2024	Active	10084243
10084244	SABENA TECHNICS BGC	REV. 1		A330-203	A330-200 incomplete cabin (MSN 655): Removal of all seats except one rowof 8 seats and CAS at Door 1 and Door 2, all monuments except the GalleyG1 and Lavatories L11 & L73.Rev. 1 corrects typo Technical Documentation section.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:- CS25 at amdt. 4: 25.1, 25.29, 25.301, 25.303,25.305, 25.307, 25.321,25.337, 25.341, 25.365, 25.561, 25.57...	Master Data List, Ref. 41312-01-A-MDL issue 00 dated 4 April 2024Instructions for continued airworthiness, Ref. 41312-01-A-ICA issue 00dated 4 March 2024Aircraft Flight Manual Supplement, Ref. 41312-01-A-AFMS-F02 issue 00dated 21 March 2024or later revisions of the above listed document(s) approved/...	- No occupant in the entire cabin.- No cargo in the entire cabin.- front-door coupling not performed.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no advers...	05/04/2024	Active	10084244
10084245	COMPANIA ESPANOLA DE TECNICAAERONA UTICA, S.A.			EC135 T2+, EC135 T3 EC135 P3, EC135 T1, EC135 T2 EC135 P1, EC135 P2, EC135 P2+	Installation of the airborne mission system for Search and Rescue (SAR) Lifeseeker SAR XL S10 in accordance with Master Document and DrawingList D2318-0001	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-27 Amendment 2 for27.321; 27.337; 27.341; 27.471; 27.571; 27.619; 27.625; 27.783; 27.787;27.805; 27.807;...	Master Document and Drawing List D2318-0001 Edition 03Rotorcraft Flight Manual Supplement D2318-0014 Edition 04Maintenance Manual Supplement D2318-0013 Edition 04or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	Operation of the system is limited to VFR.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	05/04/2024	Active	10084245
10084246	LUFTHANSA TECHNIK AG			A320-232	A320 - Door Lock InstallationExternal and internal door locking devices.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Design Document STDD52-23/01M issue 01 Rev. 00Airplane Flight Manual Supplement A-00-24/08-AFM Issue 01 Rev. 00or later revisions of the above listed document (s)approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/04/2024	Active	10084246

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084249	FLYHT AEROSPACE SOLUTIONS Ltd.		TCCA SA15-63 ISSUE 2	DHC-8-401, DHC-8-402	Installation of the AFIRS 228 System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The modification is defined with FLYHT Aerospace Solutions Ltd MasterDocument List 121-0079, Revision PInstallation shall be performed in accordance with FLYHT AerospaceSolutions Ltd Installation Instructions 151-0068, Revision PThe aircraft shall be operated in accordance with FLYHT AerospaceSoluti...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/04/2024	Active	10084249
10084257	NOVA SYSTEMS & ENGINEERING LIMITED			A321-231, A321-232 A321-211, A321-212, A321-213	Airbus A321-200 – Cabin Interior ReconfigurationThis Project removes the existing two-class 16 B/C & 168 Y/C LOPA andinstalls a single class 220 Y/C LOPA on the aircraft. Various interiorfurnishings, such as the cabin attendant seats, forward monuments,sidewall panels and overhead bins are removed /...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-CCD Issue 2.The requirements for environmental protection and the associatedcertified noise and/ or emis...	Master Data List, 'Airbus A321-200 - Cabin Interior Reconfiguration',NSI-20061 0-01-MDL-01, Issue 1,dated 8th April 2024< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	This STC is not applicable to A321-211, A321-212, A321-213,A321-231 andA321-232 if they have any of the following Airbus modificationsembodied:MOD 157272 Max PaxMOD 159536 Max PaxMOD 160139 Passenger information signs and placards.Prior to installation of this change/repair it must be determined th...	09/04/2024	Active	10084257
10084272	AERODATA AG			680A (LATITUDE)	Installation of Aerodata AG Flight Inspection System AD-AFIS-1320.Aerodata Modification Ident: C680A-02	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25, Amdt 25: 25.1319CS-MMEL, Issue 3.The requirements for environmental protection and the associatedcert...	Master Document List Installation of AD-AFIS-1320 in C680A,documentMDL-A/ C-971 Rev 0,dated 27 March 2024.Airplane Flight Manual Supplement Installation of AD-AFIS-1320 in C680A,document AFM-191 Rev 0,dated 16 January 2024.Aircraft Maintenance Manual Supplement Installation of AD-AFIS-1320 inC680A,M...	The performance of Aerodata Flight Inspection System AD-AFIS-1320 hasnot been assessed by EASA.This STC cannot apply toaircraft configurations where any flight crewalerts have been installed in addition to the ones implemented in theoriginal TC design and are not integrated with the original TC Cre...	11/04/2024	Active	10084272
10084276	Q.C.M. DESIGN GmbH	REV. 1		525	Collins Iridium Certus Satcom InstallationRev.1 corrects a typo in the Technical Documentation part.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Engineering Bulletin ref EB-C525-QCM23-001 Rev 0;Instructions for Continuous Airworthiness Ref C525-QCM23-001-M1-ICA Rev0;Flight Manual Supplement Ref C525-QCM23-001-M1-AFM Rev 0;Certification Report Ref C525-QCM23-001 Rev 0or later revisions of the above listed document(s) approved/acceptedunder th...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/07/2024	Active	10084276
10084286	AEROTEC & CONCEPT			A320-232	Cabin reconfiguration to 180 pax	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List AE23098MDL Issue 0Instructions For Continued Airworthiness AE23098ICA Issue 0or later revisions of theabove listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/04/2024	Active	10084286

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084291	COMPANIA ESPANOLA DE TECNICAAERONAUTICA, S.A.			550	Installation of UASC LPV Monitor for PBN	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:FAR 25 Amendment 25-136: 25.29; 25.251; 25.301;25.303; 25.305; 25.307;25.337; 25.341; 25.365; 25.561; 25.57...	CETA Master Document and Drawing List, D2101-0001, revision7, dated 16November 2023;CETA Airplane Flight Manual Supplement, D2101-0017, revision 5;CETA Maintenance Manual Supplement, D2101-0016, revision 5, dated 16November 2023or later revisions of the above listed document(s) approved/acceptedund...	RNP Approaches are only certified down to LNAV minima.RNP Approaches down to LNAV/VNAV or LPV are forbidden.Limited only to SN 550-0156.Aerlyper (EASA 21J.091) minor modification nº 00112 Ed.00, associatedwith Service Bulletin ref. 101980,is a prerequisite for this Approval.Prior to installation of...	19/04/2024	Active	10084291
10084293	SKYTEC AEROSPACE GmbH			737-800	186Y Passenger Seating LayoutThis modification introduces agenerating a 186-passenger seatingconfiguration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision A of Skytec Master Document ListDocument MDL-B738C111-0003Maintenance shall be accomplished in accordance with revision A ofSkytec Instructionsfor Continuous Airworthiness DocumentICAS-B738C111-0003or later revisions of the above listed document(s) approved/ accep...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/04/2024	Active	10084293
10084306	KNSI AVIATION ENGINEERING EUROPE Lt	REV. 1		A320-214	Equipment & Furnishings - Cabin Reconfiguration (180 Y/C)Installation of ACRO series 9 recline economy class seats. Cabinre-configuration of A320 aircraft to install ACRO series 9reclineeconomy seats for 180 passengers.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25 Change 13 for25.562(a)(b)(c) - JAR 25.562 (c)(5) and (c)(6) are excluded, as thesubject aircraft isc...	Master Document List, ‘Equipment & Furnishings - Cabin Reconfiguration, 23E116-MDL-001, Revision 02, dated 17th April 2024<(>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/04/2024	Active	10084306
10084313	GFD GmbH			35A, 36A	CMDL FWD Antenna Provision (Variant)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: AMDT 19 - CS25.571.The requirements for environmental protection and the associatedcertified noise and/ ora...	Installed in accordance with Engineering Order, 23-072-EO-01, Rev. 0.1,20.02.2024;Master Data List, 23-072-MDL-01, Rev.0.1, 15.02.2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	23/04/2024	Active	10084313
10084325	SCANDINAVIAN AVIONICS DESIGN ApS			ATR 72-212, ATR 72-212 A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Mode S ELS/EHS & ADS-B Upgrade with MOD A or MOD B configurations.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25 Amendment 2Sections 25.1, 25.29, 25.251,25.301, 25.303, 25.305, 25.307, 25.337,25.341, 25.365, 25.56...	Engineering Order, Ref. 3000171-EO, Is. 1, Date: 22.04.2024andCertification Documents, Ref. 3000171 DOC, Is. 1, Date: 22.04.2024.AFM Supplements, Ref. 3000171-AM A, Is. 2, Date: 12.04.2024 and Ref. 3000171-AM B, Is. 1, Date: 10.04.2024.ICAdocuments, Ref. 3000171-CA A, Is. 1, Date: 15.12.2023 and Re...	11. Prior to installation of this change aircraft configuration mustcomply with the configuration defined in section 4 of Engineering Order3000171-EO.2. Configuration MOD B is only applicable to ATR 72-201 s/n 227.3. This modification is not applicable to aircraft models ATR 42-500 andATR 72-212A wi...	23/04/2024	Active	10084325

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084330	AIRBUS S.A.S.			A330-243	Airbus STC Solutions MOD AI0278This modification describes the preparation of cabin for MRTT conversionon A330-243 MSN 1608.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Summary Report reference SRSA-23017 Issue F dated 10 April2024Modification Approval Sheet MAS n° AI0278 issue 1.Airplane Flight Manual supplement for MSN 01608 referenceAFM-S_MOD_AI0278 isue 00dated 01 October 2023or later revisions of the above listed document(s) approved/acceptedunde...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/04/2024	Active	10084330
10084331	SABENA TECHNICS BGC			A320-251N	186 PAX Seats with ISPSS InstallationThis modification consists in changing cabin seats - from 186 PAX fullY/C to 186 PAX full Y/C onboard A320-251N. RECARO Y/C 3510SL seriesequipped with KID ISPSS, will be installed. The ISPSS will be activated.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: : CS25 Amdt 4:paragraphs 1, 29, 301, 303, 305,307, 321, 337, 341, 365, 471, 561, 562,571, 601, 603, 605, 6...	Instructions for Continued Airworthiness (ICA) N° 41198-01-A-ICA-R00Master Data List (MDL) N° 41198-01-A-MDL-R00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The embodiment of this change requires the following A/C configuration,as pre-requisite: installation of SNT-BGC Service Bulletin SB ref.41052-01-A-SB (A320N_Cabin reconfigurationto 186 pax (full Y/C))approved through STC 41052-01/EASA 10079801_REV1.Prior to installation of this change/repair it mu...	24/04/2024	Active	10084331
10084366	BLUE SKY ADVENTURES			U206G U206C, U206D, U206E, U206F TU206G, U206, U206A, U206B TU206C, TU206D, TU206E, TU206F TP206D, TP206E, TU206A, TU206B T207A, TP206A, TP206B, TP206C P206, P206A, P206B, P206C P206D, P206E, T206H, T207 206, 206H, 207, 207A	Installation of transparent sliding door	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Flight Manual Supplement Ref. ADxC-91-001-AFM A 04.04.2024;Maintenance Manual Supplement Ref. ADxC-91-001-AMM A 23.3.2024;Installation instructions Ref. ADxC-91-EO-004 A 18.03.2024;Master Document List Ref ADxC-91-001-MDL A 04/04/2024or later revisions of the above listed document(s) approved/ accept...	This design change is limited to the installation and operation of thesliding door.	25/04/2024	Active	10084366
10084369	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA5137NM	SEE FAA AML	Installation of sun visor	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	ROSEN Product Development, Inc. Drawing List No. RCS-300 /400-00 DL,Revision 8, dated 14 February 2005<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/04/2024	Active	10084369
10084379	JET AVIATION AG	REV. 1		737-8	VVIP Cabin Interior CompletionThe modification installs a full VIP interior in green Boeing 737-8aircraft. The aircraftis completed to accommodate a maximum of 32Passengers and 4Cabin CrewRev. 1 corrects typo.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): D-50-60083515Installation of Oblique Seats.- Equivalent Safety Finding(s): D-90-60083515 Obstruction of Type IIIEmergency Exit.- TheC...	- Master Data List JBSC-M-03783MDL-001 ISSUE E.- Aircraft Flight Manual Supplement JBSC-M-03783AFM-001 ISSUE C.- Instructions for Continued Airworthiness JBSC-M-03783ICA-001 ISSUEA.- Cabin Crew Data JBSC-M-03783CCD-001 ISSUE C.- Master Minimum Equipment List JBSC-M-03783MEL-001 ISSUE Cor later revi...	Private Operation (Not-for-Hire, Non-Commercial)Non-SmokingAircraftMax occupancy: 32 Pax, 4 Flight crew, 4 Cabin CrewPrerequisites:- Exterior Exit Marking - an approved exterior paint livery matching theexit configuration of the cabin considering the deactivated exits mustbe applied. Changes to the...	16/05/2024	Active	10084379

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084383	COMPANIA ESPANOLA DE TECNICAAERONAUTICA, S.A.			EC135 P2, EC135 P2+	Installation of a Video Transmission System in accordance with MasterDocument and Drawing List D2306-0001	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-27 Amendment 2 for27.1; 27.2; 27.21; 27.25;27.27; 27.29; 27.45; 27.141; 27.251; 27.301;27.303; 27.305;2...	- Rotorcraft Flight Manual Supplement D2306-0014 Edition 03- Master Document and Drawing List D2306-0001 Edition 03- Maintenance Manual Supplement D2306-0013 Edition 03or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The usage of the Video Transmission System is limited to VFR operations.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ orrepair will introduce no adverseeffect upon the airworthines...	29/04/2024	Active	10084383
10084386	ZIM AIRCRAFT CABIN SOLUTIONS, LLC		FAA STC ST04495AT	A330-743L, -841, -941 A330-323, -341, -342, -343 A330-302, -303, -321, -322 A330-223F, -243, -243F, -301 A330-201, -202, -203, -223	Interior Reconfiguration of an Airbus A330-300 Aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: CS25 amdt. 28:25.853(a)(c)(d)(e), 25.869(a)(1), 25.899(a)(b) , 25.981(d) , 25.1353(a)(b)(c) , 25.1360, 25.1423(c).The requi...	1. ZIM Aircraft Cabin Solutions Master Data List 22T032L001, RevisionIR, dated 24 April 2024;2. HAECO Cabin Solutions Instructions for Continued Airworthiness22T032R009, Revision 00, dated 23 January 2024;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accord...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/04/2024	Active	10084386
10084407	KITCHENER AERO AVIONICS LIMITEDdba MID CANADA MOD CENTER		TCCA O-LSA23-088D	560XL	Export Configuration - CVR and SSDTU as per TCCA STC O-LSA23-088/D- upgrade of an existing CVR to a L3 Harris SRVIVR 25 SSCVR with InternalRecorder Independent Power Supply (RIPS).- replacement of an existing Universal Avionics Data Transfer Unit (DTU)with a Solid State Data Transfer Unit (SSDTU).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1457(d)(6) atAmdt. 28.The requirements for environmental protection and the associatedcertified noise...	Avionics Design Services Ltd. Master Drawing List MDL23043 Revision N/ CMid-Canada Mod Center Instructions for ContinuedAirworthinessICA 23043-1 Revision N/C dated July 10, 2023or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Imple...	Applicable to Textron Aviation 560XL S/N 5605101.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	08/05/2024	Active	10084407
10084408	AIRBORNE TECHNOLOGIES GmbH			AW139	STC-AT-181 AW139 Survey ConfigurationScope of this change is the mechanical installation of the Wescam MX-10on the AW139 helicopter.Activation and operation of the camera system is no part of this STC.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Manual Supplement STC-181-G-AFM revision 1- Maintenance Manual Supplement STC-181-G-AMM revision 0Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system	This STC is applicable to the following AW139 helicopter configuration :Long Nose configuration (Report n° 139G0000P005/03) ;Dual Hoist Leonardo Helicopters kit p/n 4G2591F00111;Directional Finder Antenna installed within Leonardo Helicopters kit p/ n4G3450F00511;The SX-5 with Flir Camera Leonardo He...	30/04/2024	Active	10084408
10084411	EIRTECH AVIATION SERVICES LIMITED			737-8	B737-8 MAX, Installation of ACRO Series 6 ‘X’ passenger seatsInstallation of ACRO Series 6 ‘X’ passenger seats in 189Y seatingconfiguration on a B737-8 MAX aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.562(c)(5) andCS 25.562(c)(6) at amendment 11.The requirements for environmental protection and the as...	Master Document List, ‘B737-8 MAX, Installation of ACRO Series 6 ‘X’passenger seats’, MDL/ 1820-001, Issue 4, dated 29thApril 2024<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/04/2024	Active	10084411

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084417	AEROSERVIS, S.R.O.	REV. 2		L-410 UVP - TURBOLET L 410 UVP-E-LW, L-410 UVP-E L 410 UVP-E20 CARGO L 410 UVP-E20	Initial issue: Installation of EFIS - Garmin 700 TXi suite on L410aircraftRev. 1: Includes the Operational Suitability Data (OSD) – Flight CrewData (FCD) for Garmin 700 TXi suite.Rev. 2: Integration of KFC 325 automatic flight system (AFCS) with G700TXi.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-23.1301; 23.1306; 23.1308; 23.1309; 23.1322;23.1431 at amendment 5;CS-FCD: 050; 100; 200; 300; 400; 405;...	Initial issue:Master Document List No. AE231C00X_B dated 29.04.2024 Aircraft Flight Manual Supplement AE231W01H Rev. IR-9 dated 16.04.2024Instruction for Continued airworthiness AE231C05X rev IR , 18/2/2023Aircraft Maintenance Manual Supplements, AE231W02X rev. IR, dated20/1/2023Maintenance Schedule...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/10/2024	Active	10084417
10084422	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			737-800	Seat Bottom Cushion Replacement for CS 25.562 (a), (c)(2) and CS 25.785(a) compliance	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 Amendment 23for §25.562(a), §25.562(c-2), §25.853(a) and §25.853(c).The requirements for environmenta...	Master Data List, JCAERO/MDL/0475, Issue 1.1, 03.04.2024<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/05/2024	Active	10084422
10084423	AVIATION BUSINESS CONSULTANTSINTERNATIONAL S.R.L.			A330-343	Modification of the FWD area (DR1-DR2) passenger seats layout currentlyinstalled in B/C configuration to obtain a 347 Y/C layout using the sametype of seats installed in the rest of the cabin. The modification isnot going to involve any IFE equipment and related provisioninstallation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Doc. No ADL-CNG06323-DF-030-01-E, ADL06323 Approved Drawings List, Cabin Reconfiguration on A330, rev.2;- Doc. No SB-CNG06323-DF-020-03-F, SB-CNG06323 Service Bulletin, Cabinreconfiguration on A330, rev-1;- Doc. No MMS-CNG06323-DF-020-03-C, MMS06323, Aircraft MaintenanceSupplement, Cabin recon...	The Change is applicable on aircraft A330-343, MSN 1060 and1090, withSTC Lufththansa Technik No 10034322 embodied.Priorto installation of this change/repair it must be determinedthatthe interrelationshipbetween this change/repair and anyother previously installed changeand/ or repair willintroduc...	10/05/2024	Active	10084423
10084453	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			737-8	Galley G7 InstallationThis modification replaces installed Galley G7 units with new AMESGalley G7 units on Boeing 737-8aircraft.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision 0 of Engineering Order,Doc No.EO_M612001003_JTU_05062023The aircraft shall be maintained in accordance with Revision 2 ofInstructions for Continued Airworthiness, Doc No.ICA_M612001003_JTU_05062023or later revisions of the above listed document(s) approved/ accept...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/05/2024	Active	10084453
10084454	BOEING IRELAND LIMITED			737-800	Removal of the Row 44 Wi-Fi antenna installation and associated fuselagereinforcement members installed by the Row 44 modification (EASA STC10033185, FAA STC ST02829CH), and localcrown skin replacement betweenSTA727D+13.4 and STA727J +10	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List provided in Change Approval Document, Doc:BIL-00260-APP Rev. 00Instructions for Continued Airworthiness, Doc: BIL-00260-ICA01 Rev. 00Airworthiness Limitations (AWL) Supplement, Doc: BIL-00260-AWL01 Rev. 00or later revisions of the above listed document(s) approved/acceptedunder the...	A pre-requisite to this change is that the Row 44 broadbandsystem (EASASTC 10033186(FAA STC ST02836CH-D) is deactivated and removed.Aeroplanes modified by this STC must be maintained in accordance with:Instructions for Continued Airworthiness, Doc: BIL-00260-ICA01 Rev. 00and Airworthiness Limitatio...	10/05/2024	Active	10084454

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084455	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	ST34MOD053 - FMCDU CMA-9000 installationThis STC covers thereplacement of the current Flight ManagementComputers (FMC)and Control Display Units (CDU) by the Flight ManagementComputer Display Units (FMCDU) CMA-9000.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Chance Certification Plan (CCP) ST34MOD053 Issue 5 dated 26-APR-24- Airplane Flight Manual Supplement (AFMS) Dual FMSCMA-9000 (SW61B) ST34MOD053 dated 10-APR-24,as enclosed in certification cover sheet ST34MOD053_ICS09 Issue 3or later revisions of the above listed document (s) approved/ acceptedunde...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/05/2024	Active	10084455
10084456	PROTOPLANE SPECIAL MISSION AIRCRAFT			P2006T	Lidar installation in a Tecnam P2006T	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List, Doc. No. PP-156-MDL-01Supplement to Aircraft Flight Manual, Doc. No. PP-156-AFM-01Installation manual, Doc. No. PP-156-IM-01Instruction for continuing airworthiness, Doc. No. PP-156-ICA-00Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	STC-AT-003-Rev2 (EASA number STC 10034631, Rev.2) must be installedprior this modification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect up...	10/05/2024	Active	10084456
10084495	RMCI CANADA, Inc.		TCCA SH23-13 ISSUE 2	369FF 369E 369D	Installation of Integrated Health and Usage Monitoring System (HUMS)	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	MD 369 Master Data List, RMCI-000088, Revision 6 dated 19 April 2024MD 369 XRDS Instructions for Continued Airworthiness, RMCI-000090,Revision 4 dated 19 April 2024Or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationPro...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/05/2024	Active	10084495
10084496	BOEING IRELAND LIMITED	REV. 1		787-9	Cabin layout configuration from 338 Passenger (56 Premium Economy (PY) / 282 Tourist Class (Y)) to 320 passenger (56 Premium Economy (PY) & 264Tourist Class (Y))Rev. 1 introduces the Maintenance Planning Document (MPD) Supplement forC-Checkinspection of all wet zone floor panels for corrosion or dam...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-CCD Issue 2.The requirements for environmental protection and the associatedcertified noise and/ or emis...	- Change/Repair Approval Document, Doc: BIL-00249-APP Rev. 02 dd. 30-Jun-2025- Instructions for Continued Airworthiness,Doc: BIL-00249-ICA01 Rev. 03dd. 27-Jun-2025- Cabin Crew Manual Supplement, Doc: BIL-00249-CCM01 Rev. 00 dd.25-Apr-2024or later revisions of the above listed document(s) approved/ac...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Aeroplane configurations changed per this STC are consi...	07/07/2025	Active	10084496
10084497	DELTA ENGINEERING CORPORATION		FAA ST03192NY	777-200	Installation of a Panasonic Avionics Corporation In-Flight EntertainmentSystem:- Configuration1: TL10648-01 only for eXLite system installation- Configuration 2: TL10974-01 eXLitesystem installation and eXW systeminstallation (wireless audio/video streaming)	The Type and OSD Certification Bases for the original product as amendedby the following additional oralternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS25 amdt 4: 25.853,25.869, 25.981, 25.1353, 25.1423, 25.1431, 25.1583, 25.1585The requirements for environm...	Master Data List 0143-08961-2358 rev E dated 05 Apr 2018AFMSupplement 0600-08616-2358 Rev A dated 27 March 2018Instructions for Continued Airworthiness 0700-08617-2358 Rev C dated 03April 2018or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with th...	This certificate includes activation of existing installed In-FlightEntertainment equipment installed in a configuration presented in DeltaEngineering Master Data List 0143-08961-2358. Reference the type designfor location and part numbersof the In-Flight Entertainment equipmentactivated by this ST...	12/06/2024	Active	10084497

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084503	CONCORDE BATTERY CORPORATION		FAA STC ST01097DE	GV-SP GV	Installation to Replace Nickel Cadmium Original Equipment Batteries withValve Regulated Lead-Acid Batteries	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment: 25.1529 Amdt. 25-54;25.301 Amdt. 25-23; 25.303 Amdt. 25-23; 25.305(a,b) Amdt. 25-86;25.307(a) Amdt. 25-72; 25.337 Amdt. 25-...	1. Doc No. 5-0726, Master Drawing List, Gulfstream, GV-SP Battery,Revision NC dated 2 August 2022, FAA Approved 18 November 2022;2. Instructions for Continued Airworthiness, Doc. No. 5-0728, Rev. NC,dated 2 August 2022, FAA accepted 18 November 2022;or later revisions of the above listed document (s)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/07/2024	Active	10084503
10084510	FREIBALLONSPORT-VEREIN MUENSTERUND MUENSTERLAND e.V.			NL-STU/1000	Introduction of Load Ring LO-01 Völker	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program LO-01 Völker dated 07.05.2024Flight Manual Supplement LO-01 Völker dated 07.05.2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to competition and training flights, no flights with passengers.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ orrepair will introduce no adverseeffect upon the airworthines...	16/05/2024	Active	10084510
10084511	BALLONS CHAIZE			FIRE BALLOONS G	Compatibility of Schroeder Fire Balloons Sky Heart with Ballon ChaizeA201 basket and Cameron MK4S burner	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Ballon Chaize HABFM-Supplement Sky balloon A201 MK4S, Version 01-00<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/05/2024	Active	10084511
10084520	AIRBUS S.A.S.			A350-941	MOD AI0287 – Modify cabin configuration for ITA Airways.Themodification project is a conversion of Airbus A350 aimed foroperation by ITA Airlines.It consists in changing the cabin layout between doors 2 and doors 3 asdetailed here after.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Summary reference SRSA-23018 issue F dated 17May 2024.Modification Approval Sheet ref. MAS AI0287 Issue 1Manuals & Instructions for Continued Airworthiness referenceV25D24004730 issue A dated 03 April 2024or later revisions of the above listed document(s) approved/acceptedunder the EA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/05/2024	Active	10084520
10084525	AIR PROJET	REV. 2		S-2S, S-2B, S-2C S-1S, S-1T, S-2A	BERINGER PITTSAPPRO-0040 upgrades the original wheel and brake system for all Pittsaircraft models with BERINGER wheel and brake system.Rev 1: S-1T Model added following EASA acceptance of CAA-UK AAN 19455 (Dated 14th May 1986)Rev 2: Correction of approved data per Master Document List	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with document number: APFC-0040, Installationand control manual, Revision 2, Dated 4th November2025.Operated in accordance with document number: APAFM-0040, Flight manualsupplement, Revision 2, Dated 21st October 2025.Maintained in accordance with document number: APSMM-0040...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/11/2025	Active	10084525

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084538	JADE ENGINEERING PTE. LTD.	REV. 1		A320-251N	Three Class Interior ModificationThis design change includes an 8BC/18PEY/ 138EY interior modificationwith ETSO C127b seats from Collins Aerospace, onboard fourteen (14)Airbus 320-251N aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 at amendment 11paragraphs: 25.23 (a)(b), 25.25(a)(b), 25.27(a)(b)(c), 25.303,25.365(e)(2), 25.561(a)(b)(c...	Compliance Document List, JD-34BC03-1 Revision B, 20th May 2024Master Drawing List, JD-34BC02-1 Revision A, 6th March 2024Supplement Instructions for Continued Airworthiness and EWIS ICADocument, JD-34BC04-1 Revision 0, 6th March 2024Aircraft Maintenance Manual Supplement, AMM-AIC34B-1 Revision 0, 1...	IN-SEAT POWER SUPPLY SYSTEM (ISPSS): The ISPSS for PEDs carried by thepassengers must be turned off during take-off andlanding. Theairworthiness approval of the ISPSS for PEDs does not constitute anoperational approval to connect a PED tothe system. Note: Suchauthorization must be obtained by thea...	28/05/2024	Active	10084538
10084548	LEARJET Inc.	REV. 3	FAA STC ST02022WI	SEE FAA AML	Installation of a Bombardier Smart RouterRev. 1: adds CL-600-2B16 (604 Variant) to the approved model list.Rev. 2: addsBD-100-1A10 (Challenger 300 and 350 configurations)to the approved model list. Rev. 3:corrects a typo.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:The Certification Basis for the original product remains applicable tothis certificate/approval as modified wi...	Master Document List (MDL), Document Number BAS00015002, Rev. B, dated11 March 2024<(>,<)>Master Document List (MDL), Document Number BAS67015038, Rev. B, dated12 March 2024<(>,<)>Instructions for Continued Airworthiness (ICA), Document NumberBAS67015038-ICA-3, Rev. -<(>,<)>dated 12 February 2024<(>...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	03/11/2025	Active	10084548
10084550	SABENA TECHNICS BGC			A330-223	A330-223 cabin reconfiguration from 312 Y/C to 345 Y/C seats.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:- CS25 at amdt. 4: 25.1, 25.29 , 25.301 , 25.303 , 25.305 , 25.307 ,25.321 , 25.337 , 25.341 , 25.365 , 25.4...	Master data list, Ref. 41025-01-A-MDL-F01 issue R00 dated 16 May 2024Instructions for continued airworthiness, Ref. 41025-01-A-ICA issue R00dated 15 May 2024or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Non-electrical floor path marking system (EASA STC 10014507) shall beinstalled.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airwo...	24/05/2024	Active	10084550
10084553	PMV ENGINEERING			A330-243	KA-BAND PASSENGER CONNECTIVITY SYSTEM:Installation of an In-Flight Connectivity System (IFCS), including aKa-band antenna interfaced with Satcom Direct WiFi router and hubs.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): PCRI-251-0060088638 “Vibration/ buffetingcompliance criteria for large external antenna installation” Issue 2.- The following p...	Master Data List SCA-01580-MDL-S01 R02Instructions for continued Airworthiness SCA-01580-ICA R01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior embodiment of the Airbus line fit MOD 204370 “FUSELAGE - REARFUSELAGE - INSTALL STRUCTURAL REINFORCEMENTS FOR ARINC791 ANTENNA INSECTION 17 ON A330-200” is a pre-requisite to this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this chang...	24/05/2024	Active	10084553
10084555	HELIKOPTER AIR TRANSPORT GESELLSCHAm.b. H.			EC135 T3 EC135 T2+ EC135 T2 EC135 T1 EC135 P3 EC135 P2+ EC135 P2 EC135 P1	Installation of Hensoldt Avionics EB1 Multipurpose AirborneComputer(MPAC), external LTE/4G antenna and internal Wireless Local Area Network(WLAN) antenna in accordance with Engineering Order 34-006	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-27 Amendment 9 for27.1; 27.21; 27.21; 27.25(a), (b); 27.27; 27.29; 27.251; 27.301(a);27.303; 27.305; 27.56...	- Aircraft Flight Manual Supplement AFMS 34-006 Revision 0-Engineering Order EO 34-006 Revision 0- Instructions for Continued Airworthiness ICA 34-006 Revision 0or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/05/2024	Active	10084555

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084563	SABENA TECHNICS BGC			A330-343	Cabin Reconfiguration to 391 PAX (6B/C 385 Y/C).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 amdt. 3: 25.811,25.812CS 25 amdt. 4: 25.1 (a), 25.29(a)(b), 25.301(a), 25.303, 25.305(a)(b),25.307(a), 2...	Master Data List 41029-01-A-MDL R00Instructions for Continued Airworthiness 41029-01-A-ICA R00Aircraft Flight Manual Supplement 41029-01-A-AFMS R00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prerequisite: concurrent installation of the photo-luminescent floorpath marking approved under EASA STC reference EASA.A.S. 02580,respectively 10014507 Rev.02Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	27/05/2024	Active	10084563
10084564	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Special transport – 2* Boeing AH-64 Apache on MPP7 in Beluga STIssue 1 of ATI modification ST25MOD020 (applicant's reference) wasdeveloped, reviewed, tested and found compliant with the CertificationBasis to deal with non-Airbus sub-assemblies transport.On case-by-case basis, this modification is up...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Change Approval Sheet (CAS) ST25MOD020Ed58 Issue 1 dated 23 May 2024- Change Certification Plan (CCP) ST25MOD020Ed58 Issue 3 dated 15 May2024- Approved Document Dossier (ADD) ST25MOD020 Ed58_ADD Issue 3 includingAFM, WBM and MMEL supplements as enclosed in Independent Check SheetICS02 Issue 2 sign...	- This approval does not preclude the Operator to comply with theapplicable operational regulations, such as the provisions of ICAO Annex18 for the "The Safe Transport of Dangerous Goods by Air".- This approval covers Boeing AH-64 Apache helicopter as described inBoeing Technical Note TRSP-APACHE-BE...	27/05/2024	Active	10084564
10084567	HAVACILIK MUHENDISLIK VE SERTIFIKASHIZM ETLERI SANAYI VE TICARET ANONIMSIRKETI	REV. 1		737-800	189 Pax Interior Arrangement	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 at amendment 27paragraphs: 25.853(a)(c), 25.1729The requirements for environmental protection and the as...	Master Document List, MDL-TS1190 issue IR, 30th Mar 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prerequisite Installation: the STG Aerospace saf-Tglo® SuperSealUltraLite-X (SSULPhotoluminescent (PL) Floor Path Emergency Exit PathMarking Systems (FPEEPMS). Ref. EASA STC No. 10074237 shall be installedconcurrently to this STC configuration.Prior to installation of this change/repair it must be d...	29/10/2024	Active	10084567
10084572	AMAC AEROSPACE SWITZERLAND AG			A320-232	Certification for Commercial OperationThis STC accomplish and certify a configuration allowing commercialoperation of the aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 Appendix S S25.1,S25.10 S25.20, S25.30, S25.40, S25.50 and S25.60 at Amendment 26CS-CCD Issue 2The requ...	The Change is defined with Revision A of Master Data List documentMDL-AB05-2500.The conversion to allow commercial operation shall be accomplished inaccordance with Revision A of AMAC Aircraft Cabin Conversion DocumentACC-AB.The aircraft shall be operated in accordance with Revision A of AirplaneFli...	EASA STC EASA.IM.A.S.01724 is a pre-requisite to this change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repairand any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the pr...	30/05/2024	Active	10084572
10084588	DELTA ENGINEERING CORPORATION			767-300 767-200	Installation of 2Ku Radome and Antenna as per:-Configuration 1 (767-300): installation in area STA 1197+44 to 1307 STRS8-R to S8-L-Configuration 2 (767-300) and 2a (767-300BCF): demodification of theantenna/radome-Configuration 3 (767-200): installation in area STA 1197 to 1307 STRS8-R to S8-L	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): adoptedFAA Equivalent Level of Safety(ELOS) Finding for Vibration/Buffeting Compliance CriteriaODA-2335-01-F-1the following par...	Master Data List 0144-10306-2446 Rev. LConfiguration 1:AFM Supplement 0644-10307-2446 rev AInstructions for Continued Airworthiness 0744-10308-2446 rev Ex²W<(>&<)>B Manual D12716-21701 rev EConfiguration 2:AFM Supplement 0644-10307-2446 rev AInstructions for Continued Airworthiness 0744-10308-2446 r...	-This certificate covers only the physical installations asdescribed inthe associated documentation ("provisions only"). This certificate doesNOT cover the 2KU antenna activation.-This certificate covers configurations compatible with B767 aircraftmodified as per Boeing Service Bulletin 767-00-0039...	31/05/2024	Active	10084588

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084601	DASSAULT AVIATION BUSINESSSERVICES SA			FALCON 900EX (F900EX)	TAG-M416-Cabin Partial Refurbishment	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	TAG-M416-MCDL Rev. IR dated 28 May 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to aircraft serial number 51.This STC constitutes an Alternative Method of Compliance (AMOC) to theaction required by EASA AD 2014-0082, sect. “Required Action(s) andCompliance Time (s)”, paragraph (1).Prior to installation of this change/repair it must be determined thatthe interrelationship...	03/06/2024	Active	10084601
10084620	RECOIL AEROSPACE, INC.		FAA STC SR02584AK	EC 225 LP AS 332 L2 AS 332 L1 AS 332 L	Installation of Recoil Model T1000-E / T650-E Fire Suppression TankSystem (This STC is the validation of FAA STC SR02584AK)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Recoil ROTORCRAFT FLIGHT MANUAL SUPPLEMENT for Recoil ModelT1000-E /T650-E Tsunami Wildfire Suppression Tank System, Airbus HelicoptersModel AS332L, AS332L1, AS332L2, and EC225LP, document ref. RDPU0015Revision D dated 10 October 2025Recoil Maintenance Manual for the Recoil T1000-E & T650-E Tsunami...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/11/2025	Active	10084620
10084621	DOA AESGLOBAL LIMITED			A330-243	24BC / 250YC Dual Class Passenger Seating LayoutThis modification introduces a cabin layout using 24 Business Classseats and 250 Economcy Class seats generating a 274 Passenger seatingconfiguration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25.1, 25.29, 25.303,25.305 (a) – (c), 25.307 (a), 25.321, 25.337, 25.365 (e) – (g), 25.561,25.601, 25.603,...	The Change is defined with Issue 4 of AESGLOBAL Master DataListAES-0385-07-MDL.Maintenance shall be accomplished in accordance with Issue 0 ofAESGLOBAL Instructions for Continuous Airworthiness DocumentAES-0385-07-01 or later revisions of the above listed document(s) approved/acceptedunder the EASA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/06/2024	Active	10084621
10084623	AMAC AEROSPACE SWITZERLAND AG			737-900ER	Cabin ReconfigurationThis STC modifies the aft section of an FAA STC approved VIP Interior(ST02254SE) reducing the seating capacity from 40 to 36 TTOL seats	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.853, CS 25Appendix S S25.1, S25.10 S25.20, S25.30, S25.40, S25.50 and S25.60 atAmendment 19.The requi...	- The Change is defined with Revision B of AMAC Master DataListdocument MDL-EO09-2500.- The aircraft shall be maintained in accordance with Revision A of AMACInstructions for Continued Airworthiness document ICA-EO09-2500- The aircraft shall be operated in accordance with Revision B of AMACAirplane...	An Aircraft with this EASA STC installed can only be registered withinan EU Member State when the pre-requisite configurations are EASAapproved / validated.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously i...	04/06/2024	Active	10084623
10084629	STERLING CORPORATIOND/ B/A STERLING HELICOPTER			PC-12/47E PC-12/47 PC-12/45 PC-12	Installation of replacement LED recognition lights, LED wingtip lights,LED beacon lights, LED taxi lights, and LED landing lights	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Sterling Helicopter Master Drawing List (MDL), Document No.ST-9791-02,Rev. -, dated 23 January 2024< (>,<)>Maintenance to be performed in accordance with Sterling HelicopterInstructions for Continued Airworthiness (ICA) Document NumberST-9791-03, Rev. -, dated 5 February 2024< (>,<)>or later revision...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is applicable to all serial numbers for Pilatu...	19/06/2024	Active	10084629

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084636	STERLING CORPORATIOND/ B/A STERLING HELICOPTER		FAA STC ST04839NY	CL-600-2B19 CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Installation of LED Position/Anti-Collision Lights on the BombardierInc., Challenger (CL) 600 series (600/601/601-3A/601-3R/ 604) and MHIRJAviation ULC models (100/440/550/700/701/702/705/900/1000) jets	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Sterling Helicopter Master Drawing List, Document No. ST-9624-02, Rev.C, dated 7 March 2024<(>,<) >Sterling Helicopter Instructions for Continued Airworthiness, DocumentNo. ST-9624-03, Rev. -, dated 11 December 2023<(>,<)>or later revisionsof the above listed document(s) approved/ accepted onbehalf o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC replaces existing OEM Position/Anti-Collisionw...	04/12/2024	Active	10084636
10084645	365 AEROSPACE DDS LIMITED			ERJ 190-100 STD ERJ 190-100 LR ERJ 190-100 IGW	Change to introduce a cabin reconfiguration to a 106EC passenger layoutwith Geven SeatsThe existing passenger seats shall be removed, and a new 106EC passengerlayout shall be installed using Geven Essenza seats. The passengerservice unit layout will be amended as required to suit the newpassenger la...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List, 'Change to introduce a cabin reconfiguration to a106EC passenger layout with Geven Seats', MDL-2219, Revision A, dated6th June 2024<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to the embodiment of this Change, the effective aircraft must be-100LR variants or -100SR variants with Embraer Service BulletinSB190-00-0043 embodied.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslye...	07/06/2024	Active	10084645
10084653	EIRTECH AVIATION SERVICES LIMITED			737-900, 737-900ER 737-800, 737-8200, 737-9 737-600, 737-700, 737-8	Portable EFB Mount on B737 SeriesThis change installs a mount for a portable Electronic Flight Bag (EFB)unit carried onby the flight crew.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC-25.1585-01- Mitigation of flight deck firesoriginating from lithium batteries that are not part of the aircraftdesign.- The follow...	Master Document List – MDL/1836-001 Issue 2, dated 6th June2024Flight Manual Supplement FMS/ 1836-001 Issue 2, dated 14May 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Flight limitations associated with the Portable EFB Mount are detailedin the Flight Manual Supplement FMS/1836-001. Prior to installation ofthis change/repair it must be determined that the interrelationshipbetween this change/repair and any other previously installed changeand/ or repair will intro...	07/06/2024	Active	10084653
10084659	SAFRAN CABIN INC.		FAA STC ST02571LA	ERJ 190-200 IGW	Interior Installation and Modifications	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Index List No. K151, Rev. A, dated 15 May 2024< (>,<)>Instructions for Continued Airworthiness (ICA), Report No. CDRK151-78,Rev. N/C< (>,<)> dated 28 March 2024<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationPr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Embraer Document Number ETD2023-190-018180 must be inst...	10/06/2024	Active	10084659
10084711	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04264AT-D	GV-SP	Installation of an Aircell ATG 4000 High Speed Internet	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Gulfstream Aerospace Corporation Index List CE513038018, Revision E,dated 9 May 2024<(>,<) >Airplane Flight Manual Supplement CE51303M013, Rev A, dated 22 February2013< (>,<)>Instructions for Continued Airworthiness, Document CE51303A026, RevisionA, dated 31 July 2012<(>,<)>or later revisions of the a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The following STC is a required part of this STC: EASAS...	13/06/2024	Active	10084711
10084714	AEROTEC & CONCEPT			A320-214	A320 Cabin Reconfiguration to 180 Pax	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List AE 23136MDL, rev.0, dated 12 June 2024Instructions for Continued Airworthiness AE23136ICA, rev. 0, dated 24May 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/06/2024	Active	10084714

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084754	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC SA11300DS	SEE FAA AML	An upgrade to previously installed Collins Aerospace radio altimeters onseveral Part 23 aircraft.Rev. 1: Change of Address	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Master Data List 690-00-0001, Revision IR<(>,<)> dated 28 February 2024<(>,<)>For the Instructions of Continued Airworthiness reference in theattached AML<(>,<)>or later revisionsof the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProced...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/08/2025	Active	10084754
10084768	TRIEB GmbH			HK 36 TTC HK 36 TC	MTOW increase from 770 kg to 800 kgThis design change covers the increase of the MTOW from 770kg to 800kgand an increase of the weight limit for non-lifting parts from 610kg to640kg.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: CS 36 Amendment...	For HK36 TC:The change is defined with Engineering Order Doc. EOMD28/F07 Revision 1dated 20.06.2024Aircraft Flight Manual Supplement doc. AFM-EOMD028-02 Issue 0, dated15.04.2024For HK36 TTC:The change is defined with Engineering Order Doc.EOMD28/F07 Revision 1dated 20.06.2024Aircraft Flight Manual1...	Applicable to a/c s/n 36.518 and subsequent except s/n 36.713, 36.717,36.719, 36.725, 36.729 and 36.735;Metal Tube Type2 with Part Number 820-3721-00-02 must be installedprior toincrease of the MTOM.Prior to installation of this change/repair it must be determined thatthe interrelationship between...	21/06/2024	Active	10084768
10084773	SABENA TECHNICS BGC			A321-211	Cabin Reconfiguration to 220 Pax Y/C with ISPSS integration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:. JAR 25 Chg. 1325.365, 25.831. CS-25 Amdt. 425.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25...	- Master Data List, Ref. 41308-01-A-MDL Rev00 dated 18 June2024- Instructions for continued airworthiness, Ref. 41308-01-A-ICA Rev00dated 18 June 2024or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Pre-requisite installation required for this change:- Installation of Doghouse as per AERODISA (EASA DOA 21J. 259)Engineering Bulletin (AED2021-07m_DIM) approved by Minor Change ApprovalNumber AED2021-07m_AMMEN.Concu rrent installations required for this change:- The installation of the photo-luminesc...	21/06/2024	Active	10084773
10084819	ALAMO ENGINEERING GmbH			FALCON 900EX (F900EX)	FANS-1A+ over Iridium SatcomThe installation of a Satcom Iridium Datalink Unit with FANS 1/A+capability as the communication carrier replacing the installed InmarsatSwift 64 satcom system.Additionally, the structural installation of an Iridium Antenna.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List MDL24A14AE-01 Rev A.AFM Supplement FMS24A14AE-01 Rev A.Instructions for Continued Airworthiness ICA24A14AE-01 Rev A.or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/06/2024	Active	10084819
10084829	COMTECH GLOBAL AVIATION SERVICES,SOCIEDAD LIMITADA			A330-223	Interior Reconfiguration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 Amendment 23:25.853(a)(c)(d)(e), CS 25 Amendment 2: 25.1365(a), 25.1423(c), JAR 25Change 14: 25.869(a)(...	CTG-MS5116-330 MODIFICATION SUMMARY Revision A 25 June 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Installations as per EASA STC 10045998 and STC 10072739 must beperformed concurrently/ as a prerequisite.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adv...	28/06/2024	Active	10084829
10084832	AVINCIS AVIATION ITALIA S.P.A			CL-215-6B11 (CL-415 VARIANT)	Change No 34-50-2307-A: CL-415 Flight Management System InstallationInstallation of a Flight Management System (FMS) with PBN capabilities	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-ACNS Issue 4The requirements for environmental protection and the associatedcertified noise and/ or emissi...	Flight Manual Supplement FMS-34-50-2307-A Rev. 00Instructions for Continued Airworthiness ICA-34-50-2307-A Rev. 00Certification Programme CTP-34-50-2307-A Rev. 04Master Document ListMDL-34-50-2307-A Rev.00Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/07/2024	Active	10084832

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084842	QINETIQ GmbH			PC-12/47E	PC-12 Multi Mission AircraftInstallation of mission equipment including a belly radome with anintegrated radar sensor and installation of a gyro-stabilized camerawith increased diameter up to 16,6 inches to an existing lift system	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Master Document List 10014-MDL-0001 rev. M, dated 1st July 2024Aircraft Flight Manual Supplement 10014-AFM-0001 rev. K dated 23rd May2024Aircraft Maintenance Manual Supplement 10014-AMM-0001 rev. B dated 6thJune 2024Installation Instruction 10013-IIN-0001 rev. D dated 17th April 2024Installation Ins...	1) STC Prerequisite: PC-12/47E aircraft equipped with hydraulic landinggear, four bladed Hartzell Propeller HCE4A-3D/ E10477SK and installedSPECTRE LIFT PLATFORM in accordance withEASA STC 10077020 (Validationof FAA STC SA00634DE).2) Embodiment of this STC to an EASA member state registered aircraft...	02/07/2024	Active	10084842
10084845	GULFSTREAM AEROSPACE CORPORATION			GVIII-G700	Installation of Air ionization SystemInstallation of an AirIonization System for the purpose of airpurification.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of an Air Ionization System in accordance withGulfstreamAerospace Corporation Index List GDL100000066, Revision NC, dated March29, 2024, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement GC87006M006, Revision NC,dated March 29, 2024,FAA accepted InstructionR...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/07/2024	Active	10084845
10084849	ZIM AIRCRAFT SEATING GMBH			A330-323 A330-223	Seat parts modifications, including-spare parts replacementdue to material obsolescence and-literature pocket replacement and- center console life vest covers replacement	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List ref. 505706-MDL-004 Rev 0AApproved Model List 505706-CAR-008 Rev 0ADesign Change Proposal 505706-DCP-002 Rev 0Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prerequisite installations identified in Approved Model List505706-CAR-008Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthin...	02/07/2024	Active	10084849
10084850	DELTA ENGINEERING CORPORATION		FAA STC ST02893NY-D	A330-343 A330-342 A330-341 A330-323 A330-322 A330-321 A330-303 A330-302 A330-301	Activation of passenger seat IFE for a Panasonic eX2 In-FlightEntertainment System	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 amdt 4: 25.1307, 25.1351, 25.1353, 25.1423, 25.1431The requirements for environmental protection and the associatedce...	Delta Engineering Master Data List, Document Number 0154-07503-2289,Revision -, dated 2 December 2011<(>,<)>Instructions for Continued Airworthiness (ICA), Document Number0754-07507-2289, Revision A, dated 22 November 2011<(>,<)>or later revisions of the above listed document(s) approved/accepted on...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The installation of the Panasonic eX2 IFE system config...	29/08/2024	Active	10084850
10084859	STG AEROSPACE GERMANY GmbH			SEE EASA APPROVED MODEL LIST	SAF-TGLO ECO PHOTOLUMINESCENT AISLE PATH MARKING SYSTEMSThis STC certify the installation of the saf-Tglo Eco PhotoluminescentFloor Proximity Emergency Escape Path Marking Systemsas an ApprovedModel List (AML) for the aircraft identified.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1, CS 25.25, CS25.27, CS 25.301, CS 25.303, CS 25.305, CS 25.307, CS 25.561, CS 25.581,CS 25.601, CS 25...	See EASA approved model listor later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	Green Emitting PL insert shall not be mixed with Blue Emitting PL inserton the same aircraft installation.Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no a...	04/07/2024	Active	10084859

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084864	AERODATA AG	REV. 1		GV	Installation of Aerodata Mission System AD-MS-1300 in Gulfstream V forJapan Coast Guard in accordance with MDL-A/C-944 Rev. 3.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: ICAO Annex 16, V...	Applicable Requirements defined in: CP-GV-01.01. Rev. 3Compliance Record Document: CS.GV.01.01, Rev.1Design Definition Document: MDL-A/C-944, Rev. 3Instructions for Operation: AFM.177, Rev. 2Instructions for Continued Airworthiness: AMM-1183, Rev, 2Operational Suitability Data: MMEL-1020, Rev. 1or I...	The installation is limited to SN 683 and SN 689.Prerequisite for this modification:1. The STC ST02932AT for a Surveillance Mission System (SMS), must beinstalled in accordance with Engineering Report FS-N492 into theaircraft, designed by Fokker Services B.V.This installation follows FAR25 Amdt. 25-...	15/08/2024	Active	10084864
10084900	APTOZ EHF.	REV. 1		757-200	VIP LOPA for 91 PAX (80BC/2CR/9EC) This modification introduces a 80BC/2CR/9EC seating configurationRev. 1: Transfer of STC from Icelandair EHF to Aptoz EHF	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1, CS 25.29, CS25.301, CS 25.303, CS 25.305 (a)-(b), CS 25.307 (a), CS 25.337, CS25.341, CS 25.571 (a)-...	The change is defined with Revision IR of Icelandair EHF documentMCR-757-2520-593.The aircraft shall be operated in accordance with Revision C ofIcelandair EHF Aircraft Flight Manual Supplement AFM-757-2520-593.The aircraft shall be maintained in accordance with Revision A ofIcelandair EHF Instructi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10084900
10084902	SCANDINAVIAN AVIONICS DESIGN ApS			B300C B300 B200GT B200CGT B200C B200	Aft Pressure Bulkhead Feedthrough/ Connectors	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS23 Amendment 3:23.1(a)(1), (a)(2); 23.29(a)(1), (a)(2), (a)(3)(i), (a)(3)(ii), (b);23.301(a); 23.303; CS23....	Engineering Order, document 3000187-EO, Issue 1Technical Order, document 3000187-TO, Issue 2Misc. Feedthrough Connectors Installations, Drawings 3000187MF001,Revision IRAircraft Maintenance Manual Supplement, document 3000187-MM Issue 2Instructions for Continued Airworthiness, document 3000187-CA, I...	In accordance with Section 4 of the Engineering Order, document3000187-EO Issue 1Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the air...	09/07/2024	Active	10084902
10084904	PT21 SOLUTIONS SAS			737-800	Galley G2 InstallationThis modification introduces a G2 Galley and adapts the seating layoutmaintaining a 189YC configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision 4 of PT21 Solutions SASMaster DataList 23061-MDL-001The aircraft shall be maintained in accordance with Revision 1 of PT21Solutions SAS Instructions for Continued Airworthiness document23061-ICA-001or later revisions of the above listed document(s) approved/accep...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/07/2024	Active	10084904
10084907	VIH AEROSPACE Inc.		TCCA STC SH24-12 ISSUE 2	MBB-BK117 D-3 MBB-BK117 D-2	The VIHA crew bubble window installation modifies the rotorcraft byinstalling crew bubble window(s) in place of the original equipmentmanufacturer crew windows. The crew bubble window installation allowsfor increased visibility during operations.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:FAR 29.773(a) at Amendment 29-57.The requirementsfor environmental protection and the associatedcertified noi...	Master Document List V145-2219-MDL Rev. N/R dated 26 January 2024Instructions for Continued Airworthiness Report No: V145-2219-ICA, Rev.N/R dated 6 February 2024Rotorcraft Flight Manual Supplement Document No: V145-2219-FMS, Rev. Adated 12June 2024Certification Plan V145-2219-CP, Rev. A dated 21 Ma...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/07/2024	Active	10084907

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084911	H4 AEROSPACE (UK) Ltd.			A321-251NX	Cabin Configuration: 8 Club 36 J/C 36 Y/ C Passenger Seating.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 amdt. 15:25.29(a), 25.365(g), CS 25.561 (c)(5) and (c)(6) (except row 2), 25.785(seats only), 25.787(a)...	H4A2017 Modification Summary Sheet and Declaration of Compliance, Issue2, dated 24 October 2023H4AFMS0060 Airplane Flight Manual Supplement, Rev IR, dated 28 September2023H4AICA00 81 Instructions for Continued Airworthiness, Issue 2, dated 19October 2023H4ACCDS004 Cabin Crew Data Supplement, Issue 2,...	-See H4AICA0081 Instructions for Continued Airworthiness forairworthiness limitations.- Applicable to MSN 8830 onlyPriorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introd...	11/07/2024	Active	10084911
10084913	PT21 SOLUTIONS SAS			A330-203	244 Passenger Configuration (32CCL/ 17ECL/195YC)This modification introduces a 32CCL/17ECL/195YC seating configuration	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision 1 of PT21 Solutions SASMaster DataList 23063-MDL-001.The aircraft shall be maintained in accordance with Revision 1 of PT21Solutions SAS Instructions for Continued Airworthiness document23063-ICA-001or later revisions of the above listed document(s) approved/acce...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/07/2024	Active	10084913
10084924	NOVATEM INC.		TCCA STC SH07-10 ISSUE 3	AS 350 D AS 350 BA AS 350 B3 AS 350 B2 AS 350 B1 AS 350 B 206B	Installation of Novatem Magnetic Survey Stinger.This modification consists in the installation of a 27 feet compositeboom forward of the aircraft cabin for geo-survey operations.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List, Document No. MDL-NOV-STG-1000, Rev. D, dated July4, 2024;Compliance Plan, Document No. CPL-NOV-STG-1000, Rev. A, dated October 2,2007;For the AS350 Series:Installation Instructions, Document No. ISI-AS350-NOV-1000, Rev. C,dated June 19, 2024;Rotorcraft Flight Manual Supplement,...	This STC covers manufacturing and installation of mechanical stingeronly and does not Include the installation of any survey equipment oraffiliated wiring.Prior to installation ofthis change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously in...	16/07/2024	Active	10084924
10084931	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04585AT	737-900ER 737-900 737-9 737-800 737-8 737-700	Installation of a Cobham AVIATOR 200S Inmarsat / Swift BroadbandSatellite Communications System onB737-700 /-800 / -900/-900ER / -8 / -9 aircraft	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:the following paragraph(s) at a later amendment:CS25 amdt. 0: 25.29, 25.303, 25.561, 25.605, 25.711, 25.773, 25.777,25.1307, 25.1431, 25.1529, 25.1541, 25.1581CS 25 amdt....	Master Drawing List 223047-MDL, Revision D, dated 29 April 2024<(>,<) >Airplane Flight Manual Supplement, 223047-FMS, Rev IR, dated 22 May 2024<(>,<)>Instructions for Continued Airworthiness, 223047-ICA, Rev B, dated 3June 2024<(>,<)>or later revisions of the above listed document(s) approved/ accepte...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/08/2024	Active	10084931
10084936	GULFSTREAM AEROSPACE CORPORATION			GV-SP GIV-X	Installation of Satcom Direct Router	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	1. Gulfstream Aerospace Corporation Index List GDL100000035, Revision A,dated February 20, 2020.2. Airplane Flight Manual Supplement CE41429M012, Rev (-), dated April26, 2019.3. Airplane Flight Manual Supplement CE41429M013, Rev (-), datedApril26, 2019.4. Airplane Flight Manual Supplement CE51429M0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/07/2024	Active	10084936

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10084939	JET AVIATION AG	REV. 1		737-9, 737-900, 737-900ER 737-700, 737-8, 737-800	SBB Satcom System InstallationInstallation of a Honeywell Aspire 400 SBB Satcom with an AMT-3800 highgain antenna to provide access to SBB Satcom services for cabin andcockpit.This STC covers the following 3 installation configurations:- Configuration 1 – AMT-3800 antenna provisionPartial installati...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): B737-8: CRI0000492-0060092830Vibration/buffeting compliance criteria for large externalantenna installation; B737-9: CRI B-03...	- Master Data List JBSL-M-03878MDL-001 issue F- Aircraft Flight Manual Supplement JBSL-M-03878AFM-020 issue A- Instruction for Continued Airworthiness JBSL-M-03878ICA-010 issue B- Instruction for Continued Airworthiness JBSL-M-03878ICA-020issue AOr later revisions of the above listed document(s) ap...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The Option 1 and option 3 are only valid if no antennas...	04/07/2025	Active	10084939
10084941	SABENA TECHNICS BGC			737-8	B737-8 - Cabin Reconfiguration from 36 P/C + 153 T/C to 189Y/C	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Data List, Ref. 41321-01-A-MDL Rev. 00 dated 17 July 2024- Instructions for continued airworthiness, Ref. 41321-01-A-ICA Rev. 00signed 05 July 2024or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Pre-requisite installation required for this change - The installation of the ELT Adapter plate as per ERT-SB-3664approved under Eirtech Design Change Number ERT/CNG/710Concurrent installations required for this change - The installation of the photo-luminescent FPM approved under EASASTC 10...	18/07/2024	Active	10084941
10084946	HARTZELL PROPELLER LLC		FAA SA04549CH	DA 40 NG	Installation of Hartzell Propeller model 3A1-QP460A1/75A01-2	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23.907 Amendment1.This certificate/ approval involves a change with an impact on the noisedatabase and/o...	Installation Instructions, document INST-030821 Initial Revision, dated12/16/2021Airplane Flight Manual Supplement, document AFMS-030821 Initial Revision<(>,<)> dated 12/16/2021Instructions for Continued Airworthiness, document ICA-030821 InitialRevision, dated 12/16/2021or later revisions of the ab...	1. This STC is applicable only to the Models listed with the followingserial numbers:D4.111D4.36540.N00 1 and subsequent(except 40.N183 through 40.N187, 40.N189 through40.N211, 40.N213 through 40.N223, 40.N228 through 40.N234, and 40.N340through 40.N344) 40.NS001 and subsequent40.NC001 and subsequent...	18/07/2024	Active	10084946
10084960	KNSI AVIATION ENGINEERING EUROPE LT			A330-243	Zero Passenger Cabin ConfigurationThis modification introduces a zero passenger cabin configuration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.791 (a) – (e), CS25.854 (a) – (b), CS 25.1365 (a) at Initial Issue, CS 25.811 (a) – (b),(d) – (g), (i),...	The change is defined with Revision 0 of KNSI Engineering Master DataList 24E028-MDL-001.The aircraft shall be operatedin accordance with Revision 01 of KNSIEngineering Aircraft Flight Manual Supplement 24E028-AFM-001The aircraft shall bemaintained in accordance with Revision 0 of KNSIEngineering2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/07/2024	Active	10084960
10084963	FIELDTECH AVIONICS AND INSTRUMENTS,		FAA SA09923AC	B200CGT, B300, B300C B200, B200C, B200GT 200, 200C, 300, 300LW	Installation of an L-3 Digital Flight Data Recorder, impactswitch, andassociated accelerometer.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:CS23 Amdt. 0: 23.29; 23.301 a,b; 23.303; 23.305 a, b; 23.307 a; 23.321 a,b; 23.341;23.561 a,b,e; 23.601; 23.603 a, b; 23.605 a; 23.607; 23.609 a, b;23.611; 23...	Master Data List 1001-MDL-1400, Revision IR, dated March 17, 2021Airplane Flight Manual Supplement (AFMS) 1001-FMS-1000<(>,<)> RevisionIR<(>,<)> dated October 16<(>,<)> 2020.Instructions for Continued Airworthiness (ICA) 1001-ICA-1000, RevisionC, dated February 6, 2021.or later revisions of the abov...	Prerequisite: Garmin Avionics STC SA01535WI-D for the Installation ofthe Garmin G1000 Integrated Avionics System and GFC 700 Automatic FlightControl System and optional ElectronicStability and Protection (ESP).Prior to installation of this change/repair it must be determined thatthe interrelationsh...	24/07/2024	Active	10084963

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085001	ALOFT AEROARCHITECTS		FAA STC ST04255NY	737-8	Windscreen Installation Aspects	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Installation Master Drawing List No. 8402-0001-MDL revisionIR, dated 3April 2023<(>,<)>ICAW - Document No. TM-8402-ICAW, Instructions for ContinuedAirworthiness<(>,<)> Revision IR<(>,<)> dated 14 March 2023<(>,<)>or later revisions of theabove listed document(s) approved/accepted onbehalf of EASAP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC does not require a revised Electrical Wiring I...	25/07/2024	Active	10085001
10085007	JET AVIATION AG			FALCON 900EX (F900EX)	External installationsIFF blade Antenna installation upper fuselage pressurized area FrameStation 13-14<(>,<)>IFF bladeAntenna installation lower belly panel non pressurized areaFrame Station 13-14<(>,<)>V/UHF blade antenna installation aft lower fuselage non pressurized areaFrame Station 32-33<(>,...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Operation in accordance to Aircraft Flight Manual JBSL-M-03889AFM-001,Issue A, Issue date 2024-06-17.Maintenance in accordance to Aircraft Maintenance ManualJBSL-M-03889ICA-001, Issue A, Issue date 2024-07-10or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	All installations implemented by this change are provisionsand will bedelivered as inoperative. STC Limitations / Conditions:• Antenna installation inoperative / Provisions only•Overboard Discharge Indicator inoperative / Provisions only.Prior to installation of this change/repair it must be deter...	25/07/2024	Active	10085007
10085018	SAFRAN ELECTRONICS & DEFENSE SAS			AS 332 L1 AS 332 C1	Installation of Flight Data Monitoring and Transmitting System HELICOMV2+	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Programme ref. N2-AS332 HV2+, Version E, EditA, Rev. 04dated 14/05/2024Compliance Declaration ref. N9-AS332 HV2+, Version E, Edit A, Rev. 01dated 11/07/2023Rotorcraft Flight Manual Supplement ref. N11-AS332 HV2+, Version E, EditB, Rev. 01Instructions for Continued Airworthiness ref. N...	This modification is only applicable to helicopter models AS 332 C1 andAS 332 L1 equipped with AHCASNo lithium rechargeable battery is approved to be part of the HELICOMV2+ installed under this modificationPrior to installation of this change/repair it must be determined thatthe interrelationship be...	06/08/2024	Active	10085018
10085019	PAL AEROSPACE LTD.	REV. 1	TCCA A-LSA22-004/D ISSUE 1	DHC-8-102	Installation of modified overhead ductingRev. 1: Editorial change.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Fabrication and Installation shall be performed in accordance with ClarkAero Master Data ListCAS-ENG21-004-MDL, Issue 1Maintenance shall be performed in accordance with Clark AeroInstructions for Continued AirworthinessCAS-ENG21-003-ICA, Issue 1or later revisions of the above listed document(s) appr...	- Limited to Serial Number 028 and 038- Aircraft equipped with this STC can only be registered in an EU MemberState when TCCA STC A-LSA22-093/D is concurrently installed and EASAvalidated.Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/...	23/09/2024	Active	10085019
10085053	SOCIETE AIR FRANCE S.A.			777-200	28J 32W 268Y Cabin ConfigurationThis cabin configuration change modifies the cabin achieving a 328Passenger Seating Layout.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.807 (d) (7), 25.853 (a) – (c), (e)-(f), 25.1423 (c) at Change 14.The requirements for environmental p...	The change is defined with Revision 0 of Air France Change ApprovalSheet CAS-B777-23-004.The aircraft shall be maintained in accordance with Revision 0 of AirFrance Instructions for Continuous Airworthiness DocumentICA-B777-23-004or later revisions of the above listed document(s) approved/ acceptedun...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/08/2024	Active	10085053

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085096	H4 AEROSPACE (UK) Ltd.		UK.STC. 00234, REV. 00	A340-313	Tablet Interface Module and Aircraft Interface Device Installation.Installation of Tablet Interface Module and AircraftInterface Devicefor interfacing with an Electronic Flight Bag.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Programme and Master Data List H4ACP0137 Issue 5, dated 11June 2024.Aeroplane Flight Manual Supplement H4AFMS0058 Issue A, dated 4 March2024.Instructions for Continued Airworthiness H4AICA0084 Issue 3, dated 17May 2024or later revisions of the above listed document(s) accepted by EASAa...	1. EFB and EFB mechanical mount are excluded from this STC and must besubject to separate approval.2. The Operator mustassess any Portable Electronic Devices used inconjunction with this modification in accordance with AMC1CAT.GEN.MPA.140.3. This STC is applicable to Airbus A340-313 MSN 0546 only.P...	09/08/2024	Active	10085096
10085098	AEROLEDS HOLDINGS, LLC		FAA STC SA04837NY	SEE FAA AML DATED 15 NOV 2023	Installation of AeroLEDs LLC. position lights, navigation lights, strobelights and beacon lights	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	AeroLEDs Master Drawing List, Document No. 0031-0003, Rev. IR, dated 21August 21;AeroLEDs Instructions for Continued Airworthiness, Document No.0031-0001, Rev. IR, dated 31 October 2023;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Techn...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.Structural modifications may be required for certain mak...	09/08/2024	Active	10085098
10085103	AIR CRUISERS COMPANY		FAA STC ST00792NY	737-900ER 737-900 737-9 737-8200 737-800 737-8 737-700 737-600 737-500 737-400 737-300	Installation of evacuation slides and compartments assemblies	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Air Cruisers Company Installation Data List EDR-07-1282, Rev. G, datedAugust 3, 2023 including installation procedures No. P-12130, RevisionG, dated 13 July 2023<(>,<)>Air Cruisers Company Component Maintenance Manuals (CMM) 25-66-17 rev.15, 25-65-30 rev. 13, and Folding Procedure P-12128<(>,<)> rev...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/02/2025	Active	10085103
10085107	KILROY AVIATION LLC		FAA STC SE04840NY	SEE FAA AML	Installation of HarcoSemco Exhaust Gas Temperature {EGT) ElectricalHarnesses in CFM56-7 engine.	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Instructions for Continued Airworthiness (ICA) document(s) listed on AMLNo. SE04840NY<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.See AML No. SE04840NY for the applicable serial numbers...	13/08/2024	Active	10085107
10085121	JET AVIATION AG			737-9	VVIP Cabin Interior CompletionInstallation of a VVIP cabin interior into a green Boeing 737-9	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirethe following paragraph(s) at a later amendment: 25.23, 25.25, 25.27,25.29, 25.251, 25.301, 25.302, 25.303, 25.305, 25.307, 25.321(a),25.337, 25.365, 25.561, 25.562...	JBSC-M-03805MDL-001 ISSUE F MASTER DATA LISTJBSC-M-03805AFM-001 ISSUE D AIRPLANE FLIGHT MANUAL SUPPLEMENTJBSC-M-03805ICA-001 ISSUE B INSTRUCTIONS FOR CONTINUED AIRWORTHINESSJBSC-M-03805MEL-001 ISSUE A MASTER MINIMUM EQUIPMENT LIST SUPPLEMENTJBSC-M-03805CCD- 001 ISSUE D CABIN CREW DATAor later revisi...	Non Smoking AircraftMax occupancy: 19 Pax, 4 Flight crew, 2Cabin CrewTwo Cabin Crew are mandatedThe following EASA STC's are a prerequisite for this installation:- B737 Series "Seat to Floor Interface" EASA STC 10083995.- WLAN activation STC – EASA STC 10071326.- Exterior Exit Marking - an approv...	13/08/2024	Active	10085121

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085133	MCCAULEY PROPELLER SYSTEMS		FAA STC SA04601CH	B300, B300C	Installation of a McCauley Propeller Systems 4HFR34C780/105STA-0 to -2model propeller	The Certification Basis for the original product remains applicable tothis certificate/ approval.This certificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows: Chapter 10 of ICAO Annex 16, Volume...	LRL Aviation, LLC Installation Instructions, Document No.LRL-2105-INST-01, Rev. -, dated 18 January 2023<(>,<)> or Document No.LRL-2105-INST-02, Rev. -, dated 18 January 2023<(>,<)>LRL Aviation, LLC Airplane Flight Manual Supplement, Document No.LRL-2105-AFMS, Rev. -<(>,<) >Instructions for Continued...	The STC is limited to an MTOM of 15,000lbs.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	04/09/2024	Active	10085133
10085134	BOMBARDIER Inc.		TCCA SA24-8 ISSUE 1	BD-700-1A10	Fuel Recirculation System Modification	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- RAZ-BM700-307 - Modification Data Summary, Rev –, dated 24-May-2024- Maintenance according to Instructions for continued airworthinessBAS67055031-ICA-1, Rev NC,dated 26-May-2024or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Im...	None	14/08/2024	Active	10085134
10085135	EIRTECH AVIATION SERVICES LIMITED			747-400F	Collins EFB B747-400F Data loader updateActivation of the Collins Aircraft Interface Device in a new software toenable new data load functionality	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1319 Amdt 27.The requirements for environmental protection and the associatedcertified noise and/ ora...	Master Data List: MDL-1768-001_1 Issue 01 dated 12 AUG 2024AMM Supplement: AMS/ 1768-001 Issue 01 dated 07 MAY 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	The aircraft affected by this change has to be maintained in accordancewith AMS/1768-001 document.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseef...	14/08/2024	Active	10085135
10085137	GULFSTREAM AEROSPACE CORPORATION	REV. 1	FAA ST03765AT-D	GV-SP	Installation of a 16-passenger cabin interior with one additional crewseatRev. 1 corrects the FAA STC reference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Index List GC520008688, Revision F, dated April 01, 2010.Airplane Flight Manual Supplement GC52000M120, Rev (-), dated April 01,2010.Airplane Flight Manual Supplement GC52000M126,Rev (-), dated April 01,2010.Instructions for Continued Airworthiness GC52801A609, Revision (-),dated February 12, 2010o...	This approval is limited to only the installation made in GulfstreamModel GV-SP Serial No. 5259.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffe...	20/08/2024	Active	10085137
10085138	GULFSTREAM AEROSPACE CORPORATION	REV. 6	FAA ST04350AT-D	GVIII-G700 GVIII-2 (IN PROGRESS)	Installation of an Airplane Interior in the Gulfstream model GVIII-G700.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-16 Issue 5 Installation of Flight Crew SleepingFacilityEquivalent Safety Finding(s): 1. FAA ELOS TC8700AT-T-C-1 Revision 2“Emergency E...	GC87060C002 Revision (-), dated September 23, 2025, EASA ValidationSummary Compliance Report – Non-Baseline Airplane Interior – FGC (87060) GDL300007323 Revision (D) CONFIGURATION LIST - G700 AIRCRAFT INTERIORFGCGDL100000044 Revision (DF) Index List, dated September 29, 2025GC87006M001 Revision (C) A...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The “G700 EASA Validated Configuration List” GCD0000215...	30/10/2025	Active	10085138

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085146	LIFEPORT, LLC		FAA STC SA03476CH	PC-12/47E PC-12/47	Installation of Patient Loading and Utility System (PLUS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Standard Aero Master Data List (MDL) EGR-955-00, Rev. E, dated 10November 2016 and LifePort, LLC, MDL-855-01, Revision AW, dated 24 July2024<(>,<) >Airplane Flight Manual Supplement (AFMS), Document NumberEGT-855-11-001, Revision G, dated 2February 2024<(>,<) >Instructions for Continued Airworthiness...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/08/2024	Active	10085146
10085149	SPACE EXPLORATION TECHNOLOGIES CORPd/b/a Starlink Aviation	REV. 1	FAA ST09939AC	A321-272N/-272NX A321-253N/-253NX/-271N /-271NX A321-251N/-251NX/-252N /-252NX A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-216	Installation of Starlink Aviation System on Airbus A321neo seriesaircraftThe Starlink Aviation System provides non-essential in-flight internetfor passengers using the Starlink satellite constellation.Rev. 1: adds the A320 models to the applicability list.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): ESF 25.251(b) on Vibration and Buffetingby adoption of FAA Issue Paper F-1 Stage 4 signed 14-SEP-2023.- The following paragrap...	- Master Data List SPX-00003982, Version 15.0, dated 2 April 2025< (>,<)>- For A320: Airplane Flight Manual SPX-00005274, Version 2.0., dated 21May 2025< (>,<)>- For A321: Aircraft Flight Manual Supplement SPX-00003758, Version 4.0,dated 21 May 2025< (>,<)>- Instructions for Continued Airworthiness (IC...	The SpaceX Starlink Aviation System must not interface withany aircraftsystem other than prescribed power and ground connections.The Starlink Wireless Local Area Network (WLAN) is intended to provideinternet services to the airplanes cabin crew and passengers with accessvia PEDs. Any other use of t...	16/07/2025	Active	10085149
10085153	DOA AESGLOBAL LIMITED			A321-231	68 Passenger Seating ConfigurationThis modification introduces a cabin layout using 34 business classseats generating a68-passenger seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1, 25.29,25.301, 25.303, 25.305 (a) – (c), 25.307 (a), 25.365 (e), 25.601,25.603, 25.605, 25.609, 25....	The Change is defined with Issue 2 of AESGLOBAL Master DataListAES-0243-01-MDL.The aircraft shall be operated in accordance with Issue 0 of AESGLOBALAircraft Flight Manual Supplement AES-0243-10-AFMS-01The aircraft shall be maintained in accordance with Issue 0 of AESGLOBALInstructions for Continuo...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/08/2024	Active	10085153
10085159	ATI ENGINEERING SERVICES, LLC		FAA STC SA00345BO	DHC-6 SERIES 400	Installation of an NVIS / NVG Compatible Lighting System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:Amdt2: CS 23.1, CS 23.25, CS 23.771(a) CS 23.773(a)(2)CS 23.853(a) CS 23.867(a) CS 23.1301 CS 23.1309(a)CS 23....	Installation Drawing List IDL-131023, Revision I, dated 27 August 2014< (>,<)>Airplane Flight Manual Supplement FMS-131023, Revision -, dated 21 July2014<(>,<) >Instructions for Continued Airworthiness (ICA) ICA-131023<(>,<) >Revision -, dated 22 July 2014<(>,<)>or later revisions of the above listed d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/05/2025	Active	10085159
10085161	MT-PROPELLER ENTWICKLUNG GmbH			B300, B300C 300, 300LW	Installation of MTV-47-1-( )-C-F-R(P)/ CFR260-361( ) Propeller onBeechcraft King Air 300, 300LW, B300, B300C Series Aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, FAR 36Amdt 36-31.This certificate/ approval involves a change with an impact on the noisedatab...	According to MT-Propeller Master Documentation List No. E-4220 Rev. 2To be operated in accordance with MT-Propeller AFM-S Document No. E-4222Rev. 1To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-4223 Rev. 1To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4224 Rev. 0or later...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	22/08/2024	Active	10085161

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085171	WEST STAR AVIATION, LLCd/ b/a WEST STAR AVIATION		FAA STC ST00468DE	550	Installation of Bendix/King KGP-560 Enhanced Ground Proximity WarningSystem (EGPWS)	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Top Level Drawing 01-63079-000, Revision B, dated 7 March 2002<(>,<) >Airplane Flight Manual Supplement, 01-63079-AFMS-MFD, Revision IR, dated18 March 2002, for those installationswith a MFD installed<(>,<) >Airplane Flight Manual Supplement, 01-63079-AFMS, Revision IR, dated 18March 2002, for thoseI...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/08/2024	Active	10085171
10085183	B/E AEROSPACE LIMITED			BD-700-1A10	Upgrade of INMARSAT and installation of Iridium Satcom withcabintelephone system and 802.11b/g/n wireless network	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Modification Data Summary K574000 REV B dated 02-Feb-2024-Airplane Flight Manual Supplement K574090 Rev NC dated 22-jan-2016-Instructions for Continued Airworthiness BAS67056009 Rev B 23-Jan-2024or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with...	Serial Number 9023	27/08/2024	Active	10085183
10085188	BELL TEXTRON, Inc.		FAA STC SR11253DS	505	Installation of Auxiliary Fuel System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List, Report No. AA-21001, Revision D, datedOctober 25,2023;Aeronautical Accessories Installation Instructions, Report No. AA-21092,Revision A, dated February 28, 2023;Aeronautical Accessories Rotorcraft Flight Manual Supplement, Report No.AA-21017, No Revision, dated February 15, 20...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/05/2025	Active	10085188
10085191	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC ST02280LA	A330-200, A330-300	Installation of Aerocon Engineering Company (AEC) On-Board Airstairs	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	AEC Master Drawing List (MDL) AC25-A330-1000, Rev. C, dated3 December2009<(>,<)>or later revisions of the above listeddocument(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/10/2024	Active	10085191
10085192	MT-PROPELLER ENTWICKLUNG GmbH			DV 20 DA 20-A1	Installation of MTV-21-A/170-05( ) Propeller on Diamond Aircraft DV 20series and DA 20-A1 series.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, FAR 36Amdt 36-31This certificate/ approval involves a change with an impact on the noisedatabase...	According to MT-Propeller Master Documentation List No. E-4108 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-4110Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-4111 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4112 Rev. 0or later...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	29/08/2024	Active	10085192

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085195	LEE AEROSPACE, INC.		FAA STC ST04735NY	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Installation of LAI Windshields on Bombardier Inc., Challenger 600Series Airplanes	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25.613(a)(b)(c) at amdt.1CS 25.853(a) at amdt. 23Appendix F, Part I, para (a)(1)(iv) at amdt. 17The requirements for env...	Lee Aerospace, Inc., Master Data List, LAI-MDL-123, Rev. IR, dated 2July 2024<(>,<)>Instructions for Continued Airworthiness (ICA) LAI-ICA-123, Rev B, dated16 April 2024<(>,<)>Installation Instructions LAI-INSTL-12, Rev C, dated 15 May 2024<(>,<)>or later revisions of the above listed document(s) ap...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is applicable to all serial numbers for the Ma...	12/09/2024	Active	10085195
10085203	EIRTECH AVIATION SERVICES LIMITED			ATR 72-211/-212/-212 A ATR 72-201/-202 ATR 72-101/-102 ATR 42-400/-500 ATR 42-200/-300/-320	ERT/CNG/1853 - Portable Electronic Flight Bag (EFB) Mount InstallationThis Change installs a mounting device for a portable EFB on each sideof the cockpit.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): SC-G25.1585-01 “Mitigation of flight deck firesoriginating from lithium batteries that are not part of the aircraftdesign”the following-...	-Master Document List MDL/1853-001 Issue 2 signed 30-AUG-2024-Flight Manual Supplement FMS/1853-001 Issue 4 dated 29-AUG-2024or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- This change does NOT cover the portable EFB. It only deals with theinstallation of the mounting device.- It is the operator’s responsibility to apply for the operationalapprovalof EFB installation and use to its Competent Authority.- This Change can only be embodied on ATR aircraft type that hase...	30/08/2024	Active	10085203
10085213	SKYTRAC SYSTEMS Ltd.		TCCA STC SA19-125, ISSUE 1	767-200	SkyTrac ISAT Airborne Position/Data Communicator Installation.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Installation must be in accordance with Avionics Design Services Ltd.Master Drawing List MDL18083 Revision D Issue 1.Operation must be in accordance with SkyTrac Systems Ltd. FMS18083-1Revision N/C.Maintenance must be in accordance with Transport Canada accepted SkyTracSystems Ltd. Instructions forR...	This modification has not demonstrated compliance with PartCAT,CAT.GEN.MPA.205 for aircraft tracking systems.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introducee...	02/09/2024	Active	10085213
10085215	AVIATION FABRICATORS, Inc.		FAA STC SA2893SW	GV, GV-SP GIV, GIV-X GIII (G-1159A) GII (G-1159) GIIB (G-1159B) G-159	Installation of one, two or three-place side facing seat attached toseat tracks	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.		This STC approves only the installation of the parts contained in theabove section "Description of Type Design Change."The requirements forthe aisle width, passenger oxygen system, seats and safety belts, andupholstery coverings will require a separate FAA approval to verifycompatibility with insta...	02/09/2024	Active	10085215
10085219	AMAC AEROSPACE SWITZERLAND AG	REV. 1		A318-122 A318-121 A318-112 A318-111	Iridium Antenna InstallationThis modification installs an Iridium Antenna on the upper fuselage.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The Change is defined with Revision A of Master Data List documentMDL-A3202-1-5300.Maintenance shall be done in accordance with Revision A of Instructionsfor Continued Airworthiness document ICA-A3202-1-5300.or later revisions of the abovelisted document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/09/2024	Active	10085219

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085262	SPAES GmbH & Co. KG			EC 155 B1 EC 155 B	Design change project no. 0499, introducing the installation of amedical cabin interior, including three or four seats (TSO /TCH-certified), one stretcher (four variants), one stowage rack (cabinetstyle) in the cargo tunnel and a ceiling unit with cabin and patientlight.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program CFP-155-499-25-01 Rev. 0.6 dated 03.07.2024.Master Document List MDL-155-499-25-01 Rev. 0.3 dated0Flight Manual Supplement FMS-155-499-25-01 “Flight Manual Supplement forMedical Cabin P/N P0452-25-00-00-00”, Revision0.45, dated 04.09.2024.Instructions for Continued Airworthin...	The following Type Certificate configuration is a pre-requisite forinstallation of this design change:Central cabin floor X1947-X3205 P/N 365A21-8192-02, -0251, -0252, -0253,-03, -0501, -0551, 365P21-1017-00 or -01, IPC 53-71-10-04Aft cabin floor X3205 X4630 P/N 365V82-0016-00 IPC 53-71-10-05Lateral...	06/09/2024	Active	10085262
10085276	NSE			MBB-BK117 C-2	Installation of an Aircraft Data Recorder System (ADRS).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:the following CS-29 requirements at Amdt. 8:CS 29.21, CS 29.29, CS 29.251, CS 29.301, CS 29.303, CS 29.305,2...	Master Data List, Document No. CONFAD-00036639AA Issue A4 dated11/07/2024;Certification Plan, Document No. 00042453AA Issue A4 dated 18/03/2024;Installation Instructions, DocumentNo. MD-00036639AA Issue D5 dated11/07/2024;Rotorcraft Flight Manual Supplement, Document No. RFMS-ADRS-EC145-ENIssue 06I...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/09/2024	Active	10085276
10085277	HELI-ONE (NORWAY) AS	REV. 1		AS 365 N3	Initial Revision: CMA-9000 FMS INSTALLATION Heli-One ModificationNumber: AHSE-74170Revision 1: OSD MMEL modification for CMA-9000 FMS Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): FAR29.1333 Amd. 24 – Instrument systems.- The following paragraph(s) at alater amendment:CS 29.1316 Amd. 4 - Electrical and electroni...	Initial Revision: - Certification Program (CP): AHSE-74175 Revision C dated 23 May2024. - Rotorcraft Flight Manual Supplement: SUP. H1No.I. 371 dated 02September 2024. - Declaration of Compliance: AHSE-74176 Original Issue dated 18July2024.Revision 1: OSD MMEL modification for CMA-9000 FMS0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	11/03/2025	Active	10085277
10085279	CORPORATION LOGIC AIR Inc.	REV. 1	TCCA C-LSA19-036/D ISSUE 1	A330-243	Cabin OHSC Reconfiguration, Cabinet and Partition Installation, GalleyModifications and Seat Track Installation betweenXL2302 andXL2955Rev. 1 corrects the TCCA STC number.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification Data Summary M356000 Rev NC<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/09/2024	Active	10085279
10085282	ALOFT AEROARCHITECTS		FAA ST04256NY	737-800	Aerodynamic Drag ReductionInstallation of aerodynamic drag reduction kit, including fuselagefairings, flap tracks fairings, tail area vortex generators.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): PCRI-0000251-0060090636 “Vibration andbuffeting compliance criteria“.The requirements for environmental protection and the ass...	- AFM Supplement AFMS-ST04256NY-ADL Revision B- Instructions for Continued Airworthiness TM-8324-ICAW Revision B (including Appendix C “ALS & CMR”)- EWIS Instructions for ContinuedAirworthiness TM-8324-EWIS Originalissueor later revisions of the above listed document(s) approved/ accepted onbehalf of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/09/2024	Active	10085282

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085334	BOGGI AERONAUTICS S.R.L.			A109E	Door Off Operations.Design change consisting in the removalof the pilot's door to improvedownward visibility during external hoist and cargo hook operations.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List, Doc. ID 109P01100-MDL-0 Issue 2 dated12 Sep 2024;Certification Program, Doc ID 109P01100-Cpr-0 Issue 0 dated 2 Oct 2023;Rotorcraft Flight Manual Supplement,Doc. ID 109P01100-FMS-1 Issue 2dated 11 Sep 2024;Installation Instructions, Doc. ID 109P01100-Sbt-1 Issue 1 dated 11 Sep...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/09/2024	Active	10085334
10085354	T.P.S. S.P.A.	REV. 1		AS 332 L, AS 332 L1 AS 332 C, AS 332 C1	Main and Emergency Battery replacement	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI F-01.- The following paragraph(s) at a later amendment: FARs 29.610 Amdt 24,29.1309 Amdt 24, 29.1316 Amdt 53, 29.1317 Amdt 49.Thec...	- ICA TPS332-0400-ICA-00 dated on 20/09/2024- Service Bulletin TPS332-0400-SBT-00 dated on 20/09/2024- RFMS TPS332-0400-RFMS-00 dated on 20/09/2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/09/2024	Active	10085354
10085368	SIA "AEROKNOW"			A310-325 A310-222/-304/-308/-322/-324 A310-203/-203 C/-204/-221 A300 F4-622R A300 F4-203, A300 F4-605R A300 C4-605R VARIANT F A300 C4-203, A300 C4-620 A300 B4-622, A300 B4-622R A300 B4-605R, A300 B4-620 A300 B4-601, A300 B4-603 A300 B4-220, A300 B4-2C A300 B4-120, A300 B4-203 A300 B4-102, A300 B4-103	installation of aircraft tracking system.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR-25 Change 14Sections 25.21, 25.23, 25.29, 25.251, 25.301, 25.303, 25.305, 25.307,25.321, 25.337, 25.341...	Master Document List, Ref. PR00308-MDL-001, Rev. 1, Date: 19/09/2024.Aircraft Flight Manual Supplement, Ref. PR00308-AFMS-001, Rev. 1, Date: 25/06/2024.Instructions for Continued Airworthiness, Ref. PR00308-ICAW-001, Rev.I/R, Date: 05/09/2024.Master Minimum Equipment List Supplement, Ref. PR00308-MME...	This modification complies with Part-CAT, CAT.GEN.MPA.205 for AircraftTracking Systems - Aeroplanes.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverse...	24/09/2024	Active	10085368
10085369	KORFF LUFTFAHRT GMBH			L 2400 EB	STC-E-084-KOLU-SB-09-23-08-2022: Use of alternative cylinder heads andcylindersUse of alternative cylinder heads and cylinders for engine LIMBACH L2400EB. To improve cooling, the alternative use of cylinder head P/N 09 000201 and cylindersP/N 09 200 136 from SAUER Flugmotoren GmbH on enginesof the...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Korff Luftfahrt Taifun 17E Service Bulletin No. 9Betriebs- und Wartungshandbuch Limbach L 2400 EB/ EESTC-E-084-KOLU-SB-09-23-08-2022 S/N 1032 Ausgabe 20.08.2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to L 2400 EB engine S/N 1032.	24/09/2024	Active	10085369
10085374	SIRIUM AEROTECH S.L.			ATR 72-212 A	Cabin interior rearrangement for new interior configurationaccording toSirium LOPA Drawing SA24-01S-DWG01.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25 Initial IssueSections 25.301, 25.303, 25.305, 25.307, 25.561, 25.601, 25.603, 25.611,25.625, 25.785,2...	MASTER DATA LIST SA24-01S-MDL, Rev. 04, September 11, 2024.ICA SUPPLEMENT SA24-01S-ICAS, Rev. 01, September 11, 2024.CONVERSION BULLETIN SA24-01S-CB, Rev. 02, September 11, 2024Orlater revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change aircraft configurationmust complywith concurrent requirements defined in section 1.B. of ConversionBulletin SA24-01S-CB.Prior to installationof this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously...	25/09/2024	Active	10085374

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085398	B/E AEROSPACE LIMITED			CL-600-2B19 (RJ SERIES 100)	Installation, Replacement Cabin EquipmentThis modification replaces the oxygen control panel in the cockpit dueto part obsolescence.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): F-01 Installation of a therapeutic oxygen systemThe requirements for environmental protection and the associatedcertified noise and/ ora...	Installation must be in accordance in accordance with B/E AerospaceLimited Modification Data Summary M835000, Revision AAircraft operation must be in accordance with Transport Canada approvedB/E Aerospace Limited Airplane Flight Manual Supplement M835090 RevisionNC dated June 21, 2022.Maintenance mu...	The EASA STC is limited to -1 Configuration – Oxygen Control PanelReplacement only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the a...	30/09/2024	Active	10085398
10085418	AIRCRAFT INTERIOR REFURBISHMENT ESPANA S.L.			A330-203	Passenger seats rearrangement:-292 PAX (24 B/C + 268 Y/C PAX) configuration	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Master data list, Ref. A330C232-MDL001 Issue 1 dated 11/09/2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/10/2024	Active	10085418
10085420	AEROLITE AG			MBB-BK117 D-3	This STC covers the installation of Emergency Medical Service (EMS) equipment P/N 145-0340390-501 into the cabin of the MBB-BK117 D-3rotorcraft (Aerolite reference P13221).The EMS installation consists of a Fluid barrier, Centre Cabinet withoutauxiliary heating, Oxygen System including Cylinder Rackb...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program CPR-23-018 Rev. B dated 26/07/2024;Flight Manual Supplement FMS-145-0340390-501 Rev. 0 dated 01/08/2024;Operations Manual OPM-145-0340390-501 Rev. A dated 11/04/2024;Master Document List MDL-23-018 Rev. N/C dated 26/07/2024;Declaration of Compliance DEC-EASA-60087003 original i...	The following are pre-requisite installations for the embodiment of thisdesign change:D2465-600-00 Two power sockets (28 VDC, 50 A) at aft avionic bayD5231-100-00 Clam-shell doors hinges, reinforcedD3314-000-00 Discrete signal interface for EMS illumination ORAerolite Service Bulletin SB-2014163...	01/10/2024	Active	10085420
10085421	AERODATA AG			680A (LATITUDE)	Installation of a GPS 1 Antenna Switch for Selection of an Anti-JammingCRPA Antenna	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List Installation of AD-AFIS-1320 in C680A,documentMDL-A/C-957 Rev 6,dated 23 September 2024.Airplane Flight Manual Supplement Installation of AD-AFIS-1320 in C680A,document AFM-185 Rev 5,dated 19 September 2024.Aircraft Maintenance Manual Supplement Installation of AD-AFIS-1320 inC...	Installation of EASA STC 10083541 revision 1 is a prerequisite for thisapproval.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenthis change/repair and any otherpreviously installed changeand/ or repair will introduce no adverseeffect upon the airw...	01/10/2024	Active	10085421
10085423	BOEING IRELAND LIMITED			737-800	737-800 Antenna RemovalThis change deactivates and removes a Global Communications Suite (GCS)system installed by EASA STC 10059775 (FAA STC ST02908NY).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change / Repair Approval, ‘737-800 Antenna Removal’, BIL-00243-APP,Revision 00Instructions for continued airworthiness,BIL-00243-ICA01 Revision 02Airworthiness Limitation Items, BIL-00243-AWL01 Revision 01Maintenance Planning Document (MPD) Supplements BIL-00243-MPD01 Revision00or later revisions o...	Special detailed structural inspections are established forthis change,refer to Maintenance Planning Document (MPD) Supplements BIL-00243-ICA01and BIL-00243-MPD01 for further information.Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/...	04/10/2024	Active	10085423

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085426	AEROTEC & CONCEPT			A320-214	168 Y/C Passenger Seating LayoutThis modification introduces a cabin layout generating a 168-passengerseating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Revision 0 of Aerotec & Concept Master DataList AE24012MDL.Maintenance shall be accomplishedin accordance with Revision 0 ofAerotec & Concept Instructions for Continuous Airworthiness DocumentAE24012ICA.or laterrevisions of the above listed document(s) approved/acceptedu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/10/2024	Active	10085426
10085427	SCANDINAVIAN AVIONICS DESIGN ApS			CL-600-2D24 (RJ SERIES 900) CL-600-2D15 (RJ SERIES 705) CL-600-2C10 (RJ 700, 701, 702) CL-600-2B19 (RJ SERIES 100)	ELT Antenna installationThe modification consists of the full mechanical/ aerodynamic provisionfor an antenna installation as follows:An ELT Blade Antenna on the upper fuselage of the applicable model at:- STA 1170 (for CRJ 700/701/702/705/900 Series), or- STA 745,5 (for CRJ 100/200/440/850 Series)....	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Engineering Order: 3000116-EO-1-MAINTENANCE MANUAL SUPPLEMENT: 3000116-MM-3-ICA: 3000116-CA-2or later revisions of theabove listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/10/2024	Active	10085427
10085438	PMV ENGINEERING			ATR 42-500, ATR 72-212 A	CAB-04770 - EXPLISEAT Seats on ATRReplacement of existing Tiseat E1 Model seats with Expliseat seatsTiseat E2 NT15B Model.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List CAB-04770-MDL-R01 dated July 12th 2024Instructions for Continued Airworthiness CAB-04770-ICA-R00 datedAugust26th 2024or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/10/2024	Active	10085438
10085466	SABENA TECHNICS BGC			A330-202	ARINC791 Connectivity & WIFI Onboard	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:- CS25 Amdt 4: 25.1, 25.23 , 25.29 , 25.121 , 25.251 , 25.301 , 25.305 ,25.307 , 25.321 , 25.337 , 25.341 , 25...	- Aircraft Fight Manual Supplement, Ref. 10090-01-A-AFMS Issue R01 dated14 June 2024- Instructions for continued airworthiness, Ref. 10090-01-A-ICA IssueR00 dated 12 April 2024- Master data list, Ref. 10090-01-A-MDL Issue R00 dated 19 September2024- Operational suitability data change document, Ref....	Accomplishment of this STC requires the previous or simultaneousaccomplishment of the following modifications:- Fuselage – rear fuselage – define KU/KA-band antenna installation inS.17 (EASA.A.004 Major Change 10052330). Note: Airbus MajorMOD 204533- Mechanical and Electrical Provisions Installatio...	07/10/2024	Active	10085466
10085515	HELIFAB EAST, LLC		FAA STC SR04557AT, 20/03/2023	AW119MKII AW109SP A119 A109S A109K2 A109E A109C A109AII A109A A109	Cabin and crew floor protector installations	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Helifab East, LLC Master Drawing & Document List HFE-MDL-26-1, RevisionA, dated 28 December 2022;Helifab East, LLC Instructions for Continued Airworthiness,HFE-CA-26-1EASA<(>,<)> Revision IR, dated 31 March 2025;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/05/2025	Active	10085515

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085516	TECH-TOOL PLASTICS, Inc.		FAA STC SR09102RC-D	EC135 T3 EC135 T2+ EC135 T2 EC135 T1 EC135 P3 EC135 P2+ EC135 P2 EC135 P1	Installation of windows in crew, cabin, and cargo doors in accordancewith Master Drawing List 135A82-8012	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	Master Drawing List 135A82-8012 Revision G< (>,<)>Instructions for Continued Airworthiness TTPICA-EC135-001 Revision D forReverse Slide Camera Window P/N EC135-1006<(>,<) >Window Installation 135A73-0027 Revision D< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf ofP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/09/2025	Active	10085516
10085519	SWIFT FUELS, LLC		FAA STC SE04651CH	IO-360-L2A	To allow use of 100R grade aviation fuel	The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	- Swift Fuel, LLC specification SPEC-100R-22, Rev. 22, dated 07 July2022;- Installation Instructions Drawing No. 33-100R-INST, Rev. A, dated 07August 2024;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.Aircraft installation of an engine modified by this STCF...	10/10/2024	Active	10085519
10085520	SWIFT FUELS, LLC		FAA STC SA04652CH	172S 172R		The Certification Basis for the original product remains applicable tothis certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remainapplicable to this certificate/approval.	- Swift Fuel, LLC specification SPEC-100R-22, Rev. 22, dated 07 July,2022;- Installation Instructions Drawing No. 23-100R-INST, Rev. A, dated 07August 2024;- FAA Approved AirplaneFlight Manual Supplement, Document No. 100R-FMS,Revision IR, dated 22 August 2024;or later revisions of the above listed...	Only to be used with engine approved by EASA STC 10085519.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the produc...	10/10/2024	Active	10085520
10085525	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC ST02053LA	757-200	Installation of ACSS SafeRoute™ ADS-B In System and/or ACSSADS-B OutSystem	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 amdt 4: 25.1353CS25 amdt 12: 25.869, 25.1501CS25 amdt 27:25.23, 25.25, 25.301, 25.601, 25.603, 25.1301<(>,<)>25.1309,...	1. FAA approved Aviation Communications & Surveillance Systems Index ofMaster Data Lists Drawing No. 8900055<(>,<) > Revision A, dated 03 July2010;2. Instructions for Continued Airworthiness (ICA), document no. 8000757-601, Revision D, dated25 May 2017;3. FAA-Approved Airplane Flight Manual Supplemen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	03/12/2024	Active	10085525
10085531	AEROTEC & CONCEPT			H160-B	Installation of SAFRAN ED 410 EOS turret fixed and mobile parts withhand control units in cockpit and cabin and tablet holder.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master data list No AE23129MDL 'H160 - EOS COMPLETE SOLUTION MASTERDATA LIST' revision 1of 11 October 2024- Certification Programme – presentation dossier (PCDP) No - AE23129PCDP'H160 - EOS MOBILE PARTS FOR COMPLETE SOLUTION - CERTIFICATION PROGRAM / PRESENTATION DOSSIER' Rev 2 issued 09 October 20...	Helicopters with this STC installed are restricted to category B.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repairwill introduce no adverseeffect upon the airworthiness of th...	11/10/2024	Active	10085531

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085536	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA SA23-95 ISSUE 1	BD-700-1A10	Installation of interior modifications	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	B/E Aerospace Limited Modification Data Summary P197000 Revision A,dated 24 September 2024Instructions for Continued Airworthiness P197070 Revision NC, dated 09November 2023or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implemen...	Configuration 1 is applicable to a/c s/n 9247 and 9426; Configurations 2,3 and 4 are applicable to all s/n between 9159to 9429 (a/c model BD-700-1A10 under marketing designation GlobalExpress XRS).Prior to installation of this change/repair it must be determined thatthe interrelationship between th...	14/10/2024	Active	10085536
10085539	NORTHERN AVIONICS S.R.L.			A330-323/-341/-342/-343 A330-301/-302/-303/-321/-322 A330-201/-202/-203/-223/-243	Project No. 02444NAV0677 Cabin Monitors Installation on A330Installation of Monitors in A330-series aeroplane cabin on the partitionand on the aisle ceiling to interface an IFE (In-Flight Entertainment)System, or a generic Audio/Video Source, for audio video distributionover the cabin.	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements:- CS 25 at Amdt. 25 for the following requirements: CS 25.788)(b),25.1319, 25.1701 through 25.1729.The requirements for environmental protection and the associatedcertifie...	Certification Programme Document NAV0677/2 Rev. 3Aircraft Flight Manual Supplement AFMS NAV0677 Rev. 0Instructions for Continuous Airworthiness ICA-NAV0677 Rev.0Master Document List MDL0677 Rev. 1Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/10/2024	Active	10085539
10085545	AEROMECH Inc.		FAA ST02752SE	B300, B300C B200GT, 300, 300LW B200, B200C, B200CT, B200T 200, A200, 200C, A200C, A200CT	Installation of Starlink Aviation System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 23 Amdt. 023.251;23.1419(b) (for Models B300, B300C)23.1401(b); 23.629; 23.341(a); 23.571(c); 23.65; 23.6...	Master Data List (MDL) AM0376-DL02-00<(>,<)> Revision-<(>,<)> dated 7March 2024Airplane Flight Manual Supplement (AFMS)AM0376-FM01-00<(>,<)> RevisionA, dated 31 January 2024Instructions for Continued Airworthiness AM0376-IC01-00<(>,<)> RevisionA, dated 5 March 2024or later revisions of the above li...	Operation approval to permit use of Portable Electronic Devices (PED) isnot part of this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect...	15/10/2024	Active	10085545
10085581	SABENA TECHNICS BOD	REV. 2		F28 MARK 0100	ABE-NG2 Modification:Configurations 0-5, 1-4, 2-3, 4-0<(>,<)> 4-0VB, 4-1, 4-1VB, 4-3, 4-3VB,5-0, 5-1<(>,<)> ,6-0, 6-0VB, 6-1<(>,<)> 6-1VBRev 1: Typo correctedRev 2: Removal of configurations limitations	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Deviation(s): C-106 “Installation of two observation windows“ Issue 4.- The following paragraph(s) at a later amendment: JAR 25 chg. 13:25.812.The requireme...	Master Data List MDL-S-00-4277 Rev BInstructions for Continued Airworthiness ICA-S0001-00-111 Rev CAFM Supplement AFMS-S0001-00-112 Rev DMMEL Supplement MMELS-S0001-00-101 rev Aorlater revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Installation of STC 10056116 Rev. 1 “ABE-NG1” is a prer...	02/04/2025	Active	10085581
10085582	HARTZELL PROPELLER LLC	REV. 3	FAA SA04589CH ISS 27/11/2024	KODIAK 100	Installation of Hartzell Propeller Model 5D3-NK366A1(Y)( )/91D17(B)Rev. 2: Transfer from "Hartzell Propeller, Inc." to Hartzell Propeller,LLC".Rev. 3: Update of "Limitations and Conditions" section.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: 14 CFR 23.907Amendment 23-59; ICAO Annex 16 amendment 8/13 chapter 10 (10.4b).This certificate/ approval inv...	Instructions for Continuous Airworthiness<(>,<)> Ref ICA-030822<(>,<)>Rev A<(>,<)> dated 22/11/2024<(>,<)>Installation Instructions<(>,<)> Ref INST-030822, Rev IR<(>,<)> dated15/03/2023<(>,<)>Airplane Flight Manual Supplement<(>,<)> Ref AFMS-030822<(>,<)> Rev IR<(>,<)> dated 22/02/2023<(>,<)>or late...	Propeller RPM tachometer update using Garmin Ltd. Software loader cardP/N 006-B2633-56 is required.Revised Type Certificate Data Sheet information:Propeller and Propeller Limits:Propeller Manufacturer: Hartzell Propeller Inc.Number of Propellers: One (1)Propeller TC Number: P00015CHPropeller Model D...	07/03/2025	Active	10085582

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085585	NSE			MBB-BK117 D-3	Installation of a NVIS Lighting System that provides a cockpit lightingallowing the flight crew to fly at night in VFR with the aid of NightVision Goggles.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program NVIS modification for MBB BK117 D3 S/N 21108 ref.CP-NAF2400065 rev. A4dated 24/09/2024;RotorcraftFlight Manual Supplement (RFMS) NVIS MODIFICATION AIRBUSMBB-BK117 D3ref. RFMS-NAF2400065-01 rev.00 dated 06/01/2025;STCData List (Master Document List) NVIS BK117-D3 ref.SDL-NAF24...	This design change is limited to the MBB-BK117 D-3 Serial Number (S/N)21108 with the configuration described in the System Description forNVIS MODIFICATION AIRBUS MBB-BK117 D3 ref. SD-NAF2400065-01 rev. A2dated 22/08/2024.Rotorcraft modified by this design change employs Night Vision ImagingSystem I...	29/04/2025	Active	10085585
10085589	AERODATA AG			680A (LATITUDE)	Installation of a GPS 1 Antenna Switch for Selection of an Anti-JammingCRPA Antenna. Modification C680A-02.02.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List Installation of AD-AFIS-1320 in C680A,documentMDL-A/C-971 Rev 1,dated 16 October 2024.Airplane Flight Manual Supplement Installation of AD-AFIS-1320 in C680A,document AFM-191 Rev 1,dated 08 October 2024.Aircraft Maintenance Manual Supplement Installation of AD-AFIS-1320 inC680A...	Installation of EASA STC 10084272 is a prerequisite for this approval.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness...	18/10/2024	Active	10085589
10085591	SIRIUM AEROTECH S.L.			MYSTÈRE FALCON 900 (MF900) MYSTÈRE FALCON 50 (MF50) FALCON 900EX (F900EX)	Installation of FDR with FDAU and CVR for aircraft with andwithoutprovisions	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List SA19-72S-MDL rev. 02, dated Oct. 15, 2024<(>,<) >or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/10/2024	Active	10085591
10085593	DOA21 LIMITED			EMB-145MP EMB-145MK EMB-145LU EMB-145LR EMB-145EU EMB-145ER EMB-145EP EMB-145	Introduction of WVSS-II Air Sampling SystemPhase I: Provisions	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List D21.MDL-0013 Issue 1Instructions for Continued Airworthiness AMM D21.AMMS-0013 Issue 1 andD21.MPDS-0008 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This certificate does not cover the activation of the system and doesnot cover the installation of the air probe.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introdu...	21/10/2024	Active	10085593
10085594	Q.C.M. DESIGN GmbH			B300C B300 B200T B200GT B200CT B200CGT B200C B200	COLLINS IRIDIUM CERTUS SATCOM INSTALLATION	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:FAR Part 23, effective February 1, 1965, as amended by 23-1 through23-34 *) FAR Paragraphs 25.929 and 25.1419D...	Instructions for continuous airworthiness Ref RB20-QCM23-001-M1-ICA Rev0 dated 26/06/2024Engineering Bulletin Ref EB-RB20-QCM23-001 Rev o dated 20/06/2024Flight Manual Supplement Ref RB20-QCM23-001-M1-AFM Rev 0 dated 3/07/2024CertificationReport Ref RB20-QCM23-001 Rev 0 dated 14/10/2024or later rev...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/10/2024	Active	10085594

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085637	AIRWOLF AEROSPACE L.L.C.	REV. 1	FAA SR04644CH	AS 355 N AS 355 F, AS 355 F1 AS 355 F2 AS 350 D, AS 355 E AS 350 B3, AS 350 BA AS 350 B1, AS 350 B2 AS 350 B	Replacement of Ni-Cd main battery with a Li-Ion battery (20Ah) andassociated battery system annunciator.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): FAA Issue PaperS-1 “Installed RechargeableLithium Batteries” adopted by EASAThe requirements for environmental protection and the assoc...	See AML for applicable Flight Manual Supplement and Master Data List perproduct.For all products:Instructions for Continued Airworthiness Document No. ICA-STC-AA20-110Rev. IR, dated November 26<(>,<)> 2024or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accord...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/01/2025	Active	10085637
10085641	AIRWOLF AEROSPACE L.L.C.	REV. 1	FAA SR04637CH	SEE EASA APPROVED MODEL LIST	Replacement of Ni-Cd main battery with a Li-Ion battery (17Ah) andassociated LED annunciator.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): FAA Issue PaperS-1 “Installed RechargeableLithium Batteries” adopted by EASAThe requirements for environmental protection and the assoc...	See AML for applicable Flight Manual Supplement and Master Data List perproduct.For all products:Instructions for Continued Airworthiness Document No. ICA-STC-AA17-810Rev. IR, dated November 26<(>,<)> 2024or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accord...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/01/2025	Active	10085641
10085648	SABENA TECHNICS BGC			A330-243 A330-223 A330-203 A330-202 A330-201	Cabin modification and galley installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS25 Amdt. 4: 25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321,25.337, 25.341, 25.471, 25.561, 25.562, 25.5...	Instructions for continued airworthiness, Ref. 7232-01-A-ICA Issue R00dated 17 March 2025Master data list, Ref. 7232-01-A-MDL Issue R00 dated 17 March 2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Accomplishment of this STC requires the previous or s...	21/03/2025	Active	10085648
10085653	AEROLEDS HOLDINGS, LLC		FAA STC ST01936WI	SEE FAA AML	Installation of LED Lights	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	See FAA Approved Model List (AML) ST01936WI, dated 16 December 2021<(>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	23/10/2024	Active	10085653
10085662	PAL AEROSPACE LTD.		A-LSA22-005/ D ISSUE 1	DHC-8-102	Reinforcement of NLG Bay Cross Beam at Station X97	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Fabrication and installation of required parts must be in accordancewith Clark Aero Master Drawing List CAS-ENG21-018-MDL, Issue 2, dated 19April, 2022-Clark Aero Instructions for Continued Airworthiness No.CAS-ENG21-019-ICA, Issue 2, dated 19 April, 2022or later revisions of the above listed docum...	Limited to Serial Number 028 and 038Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	24/10/2024	Active	10085662

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085667	MOTORFLUG BADEN-BADEN GmbH			EC 120 B	Avionic Upgrade – Installation of Garmin PFD/ND G500H Txi, GarminCOM/NAV/ GPS GTN650H Xi, Garmin Transponder GTX345R), Garmin standbyInstrument GI275, Garmin COM/NAV GNC255B, Garmin Audio control GarminGMA350Hc and new instrument panel.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document list 25101F221128-0109 at Revision 2, dated18.10.2024.Rotorcraft Flight Manual Supplement 25101F221128-0601 at Revision 4,dated 17.10.2024.Instructions for Continued Airworthiness 25101F221128-0701 at originalissue, dated 20.10.2023.Compliance Program 25101F221128-0101 at Revision 3...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/10/2024	Active	10085667
10085676	PAL AEROSPACE LTD.		A-LSA22-006/ D ISSUE 1	DHC-8-102	Modification of Outer Flap at Track 5 Carriage	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Fabrication and installation of required parts must be in accordancewith Clark Aero Master Drawing List CAS-ENG21-029-MDL, Issue 1, dated 22February, 2022Clark Aero Instructions for Continued Airworthiness No.CAS-ENG21-033-ICA, Issue 1, dated 18 January, 2022or later revisions of the above listed do...	Limited to Serial Number 028 and 038Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	25/10/2024	Active	10085676
10085677	PAL AEROSPACE LTD.		A-LSA22-007/ D ISSUE 2	DHC-8-102	Installation of Reinforcing Straps on Fuselage Frames	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Fabrication and installation of required parts must be in accordancewith Clark Aero Master Drawing List CAS-ENG21-202-MDL, Issue 2, dated 19April, 2022Clark Aero Instructions for Continued Airworthiness No.CAS-ENG21-202-ICA, Issue 3, dated19 April, 2022or later revisions of the above listed documen...	Limited to Serial Number 028 and 038Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	25/10/2024	Active	10085677
10085683	BOEING IRELAND LIMITED			787-9	787-9 Cabin Reconfiguration (from 344 PAX (35 PEC/309 EC) to 338 PAX (56PEC/282 EC) Configuration)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-CCD Issue 2The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	-Change/Repair Approval Document, Doc: BIL-00259-APP Rev. 00-Instructions for Continued Airworthiness, Doc: BIL-00259-ICA01 Rev. 00-Cabin Crew Data Supplement, Doc: BIL-00259-CCD01 Rev. 01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplane configuration changed per this STC is considered to be thesame aircraft as the B787-9 baseline configuration for cabin crew. Cabincrew operating aeroplanes changed per this STC must complete aircraftdifference training in accordance with ORO.CC.130, which must includethe approved OSD-Cabin...	28/10/2024	Active	10085683
10085696	FLIGHT DATA TECHNOLOGIES Inc.		TCCA SA23-16, ISSUE 4	SEE EASA APPROVED MODEL LIST	Universal Quick Access Recorder (uQAR) Installation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-25 Amendment 17Sections 25.1, 25.301, 25.303,25.305, 25.307, 25.561, 25.601, 25.603,25.605, 25.607, 25.60...	Installation must be in accordance with Avionics Design Services Ltd.Master Drawing List MDL22005 Revision C Issue 1.Maintenance must be in accordance with Transport Canada acceptedAvionics Design Services Ltd. Instructions for Continued AirworthinessICA22005-1 Revision D, dated May 17, 2024Or later...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/10/2024	Active	10085696

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085732	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS			787-8, 787-9, 787-10	Structural Installation of a Viasat large antenna on B787Installation of a Viasat large antenna radome on existing Boeingbaseplate replacing Honeywell radome	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List: 02002-EAS-A-MDL-01 issue 01ICA supplement: 02002-EAS-A-ICA-01 issue A 02or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	The aeroplane must be maintained in accordance with ICA supplementreferenced: 02002-EAS-A-ICA-01.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeff...	04/11/2024	Active	10085732
10085745	J & C AEROSPACE DESIGN ANDCERTIFICATI ON SERVICES EEU Ltd.			737-800	Change of cabin configuration changing existing dual cabin configurationby single cabin configuration using 189Y Recaro3510A Type 357 Series	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List referenced JCAERO/MDL/ 1324 issue 01AMMsupplement referenced JCAERO/AMM/ 1324-1 issue 01or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/11/2024	Active	10085745
10085748	DOA21 LIMITED			A321-231, A330-243 A319-115, A320-214/-251N 737-700, 757-200					06/11/2024	Active	10085748
10085776	SABENA TECHNICS BGC			A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303	Cabin Reconfiguration from 293 PAX to 367 Y/C PAX	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:- CS25 Amdt. 4: 25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.337,25.341, 25.561, 25.562, 25.571, 25.601, 25...	Instructions for continued airworthiness, Ref. 41094-01-A-ICA Issue R00dated 07 November 2024Master data list, Ref. 41094-01-A-MDL Issue R01 dated 12 November 2024or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Non-electrical floor path marking system (EASA STC 10014507) shall beinstalled concurrently to this configuration.Priorto installation of this change/repair it must be determinedthatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introd...	12/11/2024	Active	10085776
10085781	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04540AT	GVI	Installation of SpaceX Starlink Aviation System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Gulfstream Aerospace Corporation Index List GDL100000074, Revision (-),dated 11 September 2024;FAA Approved Airplane Flight Manual Supplement, CE61303M003, Revision(-), dated 12 September 2024;FAA accepted Instructions for Continued Airworthiness CE61303A003,Revision A, dated 28 August 2024;or later...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	13/11/2024	Active	10085781
10085787	AIRBUS HELICOPTERS CANADA LIMITED		TCCA SH24-19	EC 120 B	Installation of Skid Shoes	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List, C320I0190505, Issue A, dated May 13, 2024Flight Manual Supplement, C320I0190670, Revision 0, datedJune 06, 2024Instructions for Continued Airworthiness C320I0190680, Revision 0, datedJune 06, 2024or later revisions ofthe above listed document(s) approved/ accepted onbehalf of E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/11/2024	Active	10085787

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085831	ADS-B TECHNOLOGIES, L.L.C.		FAA STC ST02586AK	SEE FAA AML	Approval of the Thomas Global Systems TFD-4000/4100 Active Matrix LiquidCrystal Display	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Data List, Document No. TFD-4000/4100-MDL, Rev 0, dated 14 June2024< (>,<)>Instructions for Continued Airworthiness, TFD-4000/4100-ICA, Rev 0,dated 14 June 2024< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical Implemen...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approvedl...	15/11/2024	Active	10085831
10085832	WOVEN ELECTRONICS, LLC		FAA STC ST04577AT	SEE FAA AML DATED 08.12.2023	Installation of the ARTEX 4000 Emergency Locator Transmitter (ELT) System on Various 14 CFR Part 25 Aircraft	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Approved Model List (AML) 2-246360-002, Rev IR, dated 8 December 2023;Instructions for Continued Airworthiness (ICA) 2-246360-80, at revisionspecified in the FAA Approved Model List (AML), dated 8 December 2023;Master Drawing List (MDL) 2-246360-001, Rev. A, dated 8 December 2023;or later revisionsb...	The STC is valid for aircraft types and models approved by EASA andlisted on the FAA AML No. ST04577AT dated 8 December2023. The EASA TCDSnumbers corresponding to the FAA TCDS apply.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repai...	15/11/2024	Active	10085832
10085843	RESURGENT AVIATION SOLUTIONS, LLC		FAA STC SA04260CH	EA500	Installation of PPG Windshields	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Resurgent Aviation Solutions<(>,<)> LLC Installation Instructions,Document Number E50-1-30.16-022, Revision A, dated 20October 2017<(>,<) >Resurgent Aviation Solutions<(>,<)> LLC Aircraft Flight Manual. DocumentNumber E50-AFM-30.17-022, Revision 1, dated 17 October 2017< (>,<)>Resurgent Aviation Solu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	19/11/2024	Active	10085843
10085847	TELAIR US LLC		FAA STC ST04592AT	ERJ 190-100 IGW	Installation of Cargo Loading System, P/N 72670-101 or 72670-102	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 initial issue: 25.23, 25.27, 25.601, 25.607, 25.609, 25.619,25.621, 25.623, 25.625, 25.1529CS 25 amdt 1: 25.301, 25.30...	1. U.S. Cargo Systems Master Drawing List (MDL), RPT-4083, Issue 4,dated 29 May 2024;2. Instructions for Continued Airworthiness for Embraer E-Jets 72670Series Cargo Loading System<(>,<)> RPT-4084, Issue 4, dated 23 July2024;3. Weight and Balance Manual Supplement for Embraer E-Jets 72670 SeriesCarg...	This Cargo Loading System, P/N's 72670-101/102, may only beinstalled onTCDS A57NM Embraer ERJ 190-100 IGW aircraft modified by Embraer servicebulletin SB190-25-0270 converted freighter configuration.Prior to installation of this change/repair it must be determined thatthe interrelationship betweenp...	19/12/2024	Active	10085847
10085852	AVCON INDUSTRIES, Inc.		FAA STC SA04660CH	B300C B300	Installation of a Large Diameter Nose Belly Radar Pod with RetractableEO/IR Sensor Mechanism and Optional SATCOM Radome	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	1. Avcon Master Document List, Document Number 06001000 Revision A<(>,<) > dated 09 September 2024;2. FAA Approved Aircraft Flight Manual Supplement (AFMS), documentnumber 06007100Revision (IR), dated 01 August 2024;3. FAA/ODA Approved Instructions for Continued Airworthiness, documentnumber 0600720...	This STC is applicable to all serial numbers for the Textron AviationInc. B300 and B300C models.The following items areeither concurrent or prerequisite embodimentrequirements for the installation of this STC: Fuselage underside railmounting provisions per EASA STC 10070462 (or Avcon drawing 180960...	21/11/2024	Active	10085852

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085859	XCALIBUR AVIATION (CANADA) LIMITED		TCCA SH12-18	AS 350 D AS 350 BA AS 350 B3 AS 350 B2 AS 350 B1 AS 350 B	Fugro Gradiometer Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation DECA Aviation Modification Summary MS12016, Rev. 5, datedDecember 11, 2023DECA Aviation Instructions for Continued Airworthiness ICA12016, Rev. 3,dated December 11, 2023DECA Aviation Flight Manual Supplement FMS12016, Rev. 2, dated December02, 2019.DECA Aviation Flight Manual Supplement...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/11/2024	Active	10085859
10085870	BELL TEXTRON, Inc.	REV. 1	FAA STC SH3189SO	412EP 412 212	Installation of an external hoistRev. 1: STC transferred toBell Textron, Inc.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Aeronautical Accessories, Inc. Report No. AA-91064, no revision, dated 3January 1992Rotorcraft Flight Manual Supplements:AA-95033, Revision D dated 20 October 2016 for External Hoist Kit PartNo. 412-140-XXX<(>,<)>AA-95034, Revision J dated2o October 2016 for External Hoist Kit PartNo. 412-140-XXX<(...	Hoist operation in 4-axis hover coupled mode is approved for the BellModel 412EP; hoist operation in 4-axis hover coupled mode is notapproved for Bell Models 212, 412 and LeonardoModels AB412, andAB412EP.Prior to installation of this change/repair it must be determined thatthe interrelationship bet...	25/11/2024	Active	10085870
10085871	SKYTRAC SYSTEMS Ltd.		SA24-28	DHC-6 SERIES 400 DHC-6 SERIES 300	SkyTrac SDL-350 Broadband Aircraft Satcom Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS.23 Amendment 6:23.2500 (b)The requirements for environmental protection and the associatedcertified noisea...	Installation must be in accordance with Avionics Design Services Ltd.Master Drawing List MDL22019, Revision N/C, Transport Canada approvedApril 08, 2024.Operation must be in accordance with SkyTrac Systems Ltd. Flight ManualSupplement FMS22019-1 Revision N/C, Transport Canada approved April 08,2024....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/11/2024	Active	10085871
10085873	KNSI AVIATION ENGINEERING EUROPE LT			A320-214 A319-112	Zero Passenger Cabin ConfigurationThis modification introduces a zero passenger cabin configuration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.23(a)(b), CS25.25(a)(b), CS 25.27(a)(b)(c), CS 25.29 (a)(b), CS 25.601, CS25.603(a)(b), CS 25.785(b)(c)...	The change is defined with Revision 0 of KNSI Engineering Master DataList 24E228-MDL-001.The aircraft shall be operatedin accordance with Revision 0 of KNSIEngineering Aircraft Flight Manual Supplement 24E228-AFM-001The aircraft shall be maintained in accordance with Revision 0 of KNSIEngineering I...	Zero occupancy, no stowage and no cargo allowed in the PassengerCompartment during TTOL and any phases of flight. Follow limitations asoutlined in AFM Supplement 24E228-AFM-001Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and a...	25/11/2024	Active	10085873
10085874	PARC AVIATION ENGINEERING SERVICESLIMITED			SEE EASA APPROVED MODEL LIST	Halon Free Portable Fire ExtinguisherThis AML STC will approve Halon-free portable fire extinguishers toreplace certainexisting Halon portable fire extinguishers installed inthe effective aircraft with certain Halon-free alternatives.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.29, CS 25.301(a), CS 25.303, CS 25.305 (b), CS 25.307 (a), CS 25.321, CS 25.341, CS25.561 (b) – (c), CS...	SEE EASA APPROVED MODEL LISTor later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	Physical installation of the fire extinguisher is not covered withinthis AML-STC and requires a concurrent approval considering Part 2 –Design Package of CAE Parc Classification and Certification FormPrior to installation of this change/repair it must be determined thatthe interrelationship betweenp...	25/11/2024	Active	10085874

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085875	SELKIRK AVIATION Inc.		FAA STC SA00679SE	5. 185D, 185E, A185E, A185F 5. 185, 185A, 185B, 185C, 4. 182, 182A, 182B, 182C, 182D 3. 180J, 180K 3. 180E, 180F, 180G, 180H 3. 180, 180A, 180B, 180C, 180D 2. 175, 175A, 175B, 175C 1. 172, 172A, 172B, 172C	Fabrication and installation of interior fiberglass trim panels	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....		The STC is valid for aircraft types and models approved by EASA andlisted on the FAA AML SA00679SE dated 31 March 2015.The EASA TCDSnumbers corresponding to the FAA TCDS apply.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair andp...	25/11/2024	Active	10085875
10085893	AIRWORK & HELISEILEREI GmbH			AS 350 B3	Complex PCDS for dual hook HEC system.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 27.865 Amdt 10The requirements for environmental protection and the associatedcertified noise and/ or emis...	Rotorcraft Flight Manual Supplement, AEF-0819-FMS-005-01, dated 18 Nov2024Instructions for continued airworthiness, AEF-0819-ICA-007, dated 04 Nov2024Certification Program, AEF-0819-PCP-0023-05, dated 20 Nov 2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA syste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/11/2024	Active	10085893
10085911	DASSAULT AIRCRAFT SERVICES (DAS)		FAA STC ST03597NY	FALCON 2000EX FALCON 2000	Installation of a GoGo AVANCE LS system in Dassault Aviation Falcon2000EX (EASy), Falcon 2000EX (non-EASy), and Falcon 2000 aircraft	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	(1) Master Data List F2XW-D0079-005 Rev E, dated 31 January2022, (2) Instructions for Continued Airworthiness (JCA) F2XW-D0079-I 55, Rev C,dated 7 January 2022,(3) Airplane FlightManual Supplement (AFMS) F2XW-D0079-I 50, Rev A,dated 6 February 2018, or later revisions of the above listeddocument (s)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	10/12/2024	Active	10085911
10085917	AIRBUS HELICOPTERS, Inc.		FAA STC SR11342DS	EC135 T3 EC135 P3	Installation of Auxiliary External Lighting System in accordance withMaster Drawing List L330U0152500	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Drawing List L330U 0152 500, Rev. A, dated 24 September 2024<(>,<) >Rotorcraft Flight Manual Supplement L150U 0152 670, Rev. A, dated 18October 2024<(>,<) >Instructions for Continued Airworthiness L330U 0152 680, Rev. B<(>,<)>dated 18October 2024<(>,<)>or later revisions of the above listed do...	This STC is limited to EC135P3/T3 models equipped with avionicsconfiguration Helionix (Mod E-2698).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseef...	01/04/2025	Active	10085917
10085920	AIRBUS HELICOPTERS, Inc.		FAA STC SR11344DS	EC135 T3 EC135 P3	Installation of Medevac Options	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements forenvironmental protection and the associated certified noise and/ oremissions levels of the product are unchanged and remain applicable tothis certificate/approval.	Airbus Helicopters, Inc. Master Drawing List L000U 0156 500, Rev. B,dated 10 October 2024<(>,<) >Rotorcraft Flight Manual Supplement L150U 0156 670, Rev. B, dated 21October 2024<(>,<) >Instructions for Continued Airworthiness L850U 0156 680,Rev. B<(>,<)>dated 21 October 2024<(>,<)>or later revisionsb...	This STC is installed to EC135P3/T3 models equipped with avionicconfigurations Helionix (Mod E-2698).Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverse...	28/11/2024	Active	10085920

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085921	ARMSTRONG AEROSPACE Inc.d/b/a ASTRONICS ARMSTRONG AEROSPACE		FAA STC ST04551CH	737-9 737-8	Installation of an Astronics CSC Edge IFE System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Astronics Armstrong Aerospace Master Data List, Doc. No. DC104-2030-00,Revision A, dated 1 February 2022<(>,<)>AirplaneFlight Manual Supplement, Astronics Armstrong Aerospace Doc.No. DC303-2030-00, Revision -, approved 27 April 2022<(>,<)>Instructions for Continued Airworthiness, Astronics Armstron...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	28/11/2024	Active	10085921
10085924	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS	REV. 4		A321-271N/-271NX/-272N/-272NX A321-251NX/-252NX/-253N/-253NX A321-213/-231/-232/-251N/-252N A321-111/-112/-131/-211/-212 A320-253N/-271N/-272N/-273N A320-231/-232/-233/-251N/-252N A320-211/-212/-214/-215/-216	THINKOM SATCOM ANTENNA INSTALLATIONThe change consists in the installation and activation of a largeantenna on A320 andA321 top rear fuselagesection, with either the already designed and approved EAD aircraftreinforcement, the Airbus Fuselagereinforcement or on existing Taqnia antenna installation....	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): CRI B-01 “vibration buffeting for largeexternal antenna”.- The following paragraph(s) at a later amendment: CS 25 Amdt 4: 25.2...	- Master Data List: 02009-EAS-A-MDL-01 Version: E- AFM supplement: 02009-EAS-A-AFM-01 Version: F- ICA supplement: 02009-EAS-A-ICA-01 Version Dor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplane modified with this STC must be operated in accordance with AFMsupplement 02009-EAS-A-AFM-01 and maintained inaccordance with ICAsupplement 02009-EAS-A-ICA-01 - Aircraft must be TPED immunePrior to installation of this change/repair it must be determined thatthe interrelationship betwe...	28/05/2025	Active	10085924
10085925	SABENA TECHNICS BGC			A330-343	Forward Cabin Arrangement	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt. 4: 25.1,25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337, 25.341, 25.471,25.561, 25.562, 2...	Master Data List 41339-01-A-MDL Rev 00Instructions for Continued Airworthiness 41339-01-A-ICA Rev00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/11/2024	Active	10085925
10085939	AIRBUS S.A.S.			A380-861 A380-842 A380-841, A380-842, A380-861 A380-841	A380 QATAR 2 KU ANTENNA ACTIVATIONThe activation of the 2KUantenna consists in activating the 2KU Bandconnectivity system which is made of:- Activating the 2KU SATCOM System by enabling power on each SSPC.- Loading all field loadable software required for GoGo connectivitysystem operation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Summary Report Ref : ACJC-AJA-19068, Issue: 03<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This STC demands prior installation of STC 10065134 “A380 – STC ACJC – Installation of A3802KU antenna”.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adv...	03/12/2024	Active	10085939
10085943	PROTOPLANE SPECIAL MISSION AIRCRAFT			P.68C	LIDAR installation in a P68The purpose of the STC is the installation of a RAMMS to collect lidarbathymetry data.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	PP-176-AFM-03 (Aircrfat Flight Manual)PP-176-IM-03 (Installation Manual) PP-176-ICA-00 (Instructions for Continued Airworthiness)PP-176-MDL-04 (Master Data List) PP-176-DL-01 (Drawing List)Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	a) STC applicable to P.68C s/n 335 onlyb) Aircraft must be equipped with photo hatch, RAI 2214552/T“Installation of Photogrammetric Hatch”.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change a...	03/12/2024	Active	10085943
10085946	AERO ENGINEERING SERVICES			A320-214	A320 MSN 4175 CABIN SEATS CHANGEAircraft with cabin LOPA ERT-817-201 modification to a 174 PAX RECARO3530BL (3530AY03- 3()-()()4) seats installation without IFEconfiguration according to cabin LOPA P03010-DWG-001.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval except the following paragraphsat CS 25 Amendment 4:25.29, 25.301, 25.303, 25.305, 25.307, 25.333, 25.341, 25.561(b)&(d),25.601, 25.603, 25.605, 25.625(a), 25.785, 25.789(a), 25.791, 25.803,...	P03010-MDL-001 Master Data List Rev. 2<(>,<)>Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	- LUFTHANSA TECHNIK PL88 floor path marking is approved through astandalone STC EASA.A.S.01056 REV. 3- Aero EngineeringServices P03821 Minor change.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installe...	04/12/2024	Active	10085946

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10085951	LUFTHANSA TECHNIK AG			A321-251N, A321-251NX	A321-200NX MedEvac Configuration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): D-01/0060081557 Medical EvacuationConfiguration.The requirements for environmental protection and the associatedcertified noise and/ o...	Supplemental Type Design Document: STDD25-21/25M Rev. 01.00, dated 03Dec 2024Airplane Flight Manual Supplement: A-00-23/07-AFM Iss./Rev. 02/00, datedSep 18/24Cabin Crew Data: A-00-23/07-CCD Iss./ Rev. 06/00, dated Nov 12/24Flight Crew Data:A-00-23/07-FCD Iss./ Rev. 04/00, dated Sep 18/24Master Minimu...	- Per AFM Supplement-Installation is limited to layout configurations per STDD25-21/25Mwithout Medical Equipment- EASASTC 10079539 is a pre-requisite for this MEDEVAC installation.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair...	04/12/2024	Active	10085951
10085955	HELICOPTEROS DO BRASIL S/ ADBA HELIBRAS		ANAC CST N° 2019S10-05	MBB-BK117 D-2, MBB-BK117 D-3	This STC permits the installation of a Luggage Net in the rear cabinarea as defined and described by Master Document List N° 145B04 0016Issue F, or later approved revisions.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List BK117 D-2 / D-3 N° 145B04 0016 Issue Fdated28/08/2023Instructions for Continued Airworthiness STC-HB-138-ICA Rev. 2 dated23/08/2023Certification Plan BK117D-2 / D-3 N° 145B04 9007 Issue C dated29/07/2022Or later revisions of the above listed document(s) approved/ accepted onb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/12/2024	Active	10085955
10085968	DASSAULT AVIATION BUSINESSSERVICES SA			FALCON 2000EX	Fabric ReplacementCrew Closet & LH/ Ent Cabinet's interior and Baggage Compartment FabricReplacement	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List TAG-M429-MCDL Rev. B<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	05/12/2024	Active	10085968
10085985	NOVA SYSTEMS & ENGINEERING LIMITED			A319-131/-132/-133 A319-111/-112/-113/-114/-115	Airbus A319-100 Cabin Interior Reconfiguration.The configuration after the design change maintains a 144Y LOPA on theA319-100 aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CCD.050, CCD.100, CCD.105, CCD.110, CCD.200, CCD.205, CCD.215, CCD. 305,CCD.310 – all at CS-CCD issue 2.The r...	Major Change Summary and Declaration of Compliance,NSI-201070-01-MOD-01, Issue 1<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	This design change is not applicable to aircraft that have had thefollowing modifications embodied:MOD 157777 “Max Pax”for aircraft equipped with wing tip fence, MOD159533 Iss 1 “Max Pax” for aircraft equipped with MOD 160500“Sharklets”, MOD 159535 “Max Pax” for aircraft equipped with wing tipfence...	06/12/2024	Active	10085985
10086002	SKY SERVICE F.B.O. INC.	REV. 1	TCCA SA20-58 ISSUE 1	SEE APPROVED MODEL LIST (AML)	Installation of Aviation Clean Air Ionization UnitRev. 1 corrects typo.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Refer to Approved Model List dated 09/12/2024<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/12/2024	Active	10086002

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086007	UNIVERSAL AVIONICS SYSTEMSCORPORATION		FAA STC ST02654LA	650 CITATION VII	Installation of InSight® Display System, EIU, TAWS Class A,and UNS-IFwSBAS FMS (with ADS-B Out function)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25.571 (a)(b)(5) (see special conditions 25-102-NM-7), CS25.773(a)(2), CS 25.777(a)(b)(c), CS 25.1303 (a)(1)...	Universal Avionics Systems Corporation Master Drawing ListMDL-2014-1001, Revision 28<(>,<)>(DM 5288), dated 16 October 2023<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/USA Bilateral Agreem...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	31/07/2025	Active	10086007
10086020	MT-PROPELLER ENTWICKLUNG GmbH			AT-502, AT-502B, AT-503A AT-402, AT-402A, AT-402B	Installation of 3-blade Propeller V508H/108/A on Air Tractor Inc.AT-402, -402A, -402B, -502, -502B, -503A	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	According to MT-Propeller Master Documentation List No. E-4385 Rev. 1To be operated in accordance with MT-Propeller AFM-S Document No. E-4387Rev. 1To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-4388 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4389 Rev. 1or later...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	09/12/2024	Active	10086020
10086026	AIRHAWKE AEROSPATIAL Inc.	REV. 1	TCCA Q-LSA24-018/D ISSUE 2	A320-214	Addition of one row of RECARO 3530AYAddition of one row of PAX RECARO 3530AY and PSU to existing 174 PAXRECARO 3530AY LOPA, re-pitching existing seats and PSUs as needed.Rev 1: typo corrected	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Can-Am Aerospace Master Drawing List 25-24-08-003, Revision 1, DatedOctober 24, 2024- Can-Am Aerospace Instructions for Continued Airworthiness25-24-08-004, Revision NC<(>,<)>Dated May 21, 2024Or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance withP...	This certificate covers installation limited to Aircraft Serial No.:4175.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthine...	12/12/2024	Active	10086026
10086029	AERO DYNAMIX, Inc.		FAA SR09652RC	412EP	Installation of Night Vision Goggle (NVG) Compatible lighting System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Drawing list (MDL) - 7692-01, Revision No. Y, Dated August 28,2023- Rotorcraft Flight Manual Supplement (RFMS)- Document No. RFMS412EPI-01, Revision No. IR,Dated November 5, 2015 - EASA RFMS Appendix Document No. RFMSA412EPX-01-EASA-08, Revision No. IR,Dated December 6, 2024 Or .- Instruct...	This STC is only eligible for installation on helicopters that meet oneof the following criteria: (1) STC SR09600RCis installed<(>,<)> (2) The serial number of the helicopter is included in the range of37002 through 37999, Or (3) The serial number of the helicopter is included in the ra...	10/12/2024	Active	10086029
10086034	LEE AEROSPACE, INC.		FAA STC ST04740NY	SEE FAA AML	Installation of LAI Windshields.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Lee Aerospace, Inc. Installation Instructions, Document Number:LAI-INSTL-14, Revision IR, dated28 June 2024<(>,<)>Lee Aerospace, Inc. Instructions for Continued Airworthiness, DocumentNumber LAI-ICA-140, Revision IR, dated 28 June 2024<(>,<)>Lee Aerospace, Inc. Master Data List, Document Number LAI-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approvedl...	10/12/2024	Active	10086034

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086036	BOGGI AERONAUTICS S.R.L.			PA-34-220T (SENECA III)	Trap door on the cabin floor and installation provisions ofa GNSSAntenna and a downwelling irradiance sensor	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Doc. No. P34P00100-CPR-03 “Certification Program”, Issue 3,dated29/07/2024Doc No. P34P00100-MDL-00 “Master Document List”, Issue 0, dated10/12/2024Doc. No. P34P00100-FMS-10 “Flight Manual Supplement”, Issue 0,08/07/2024or later revisions of the above listed document(s) approved/ acceptedunder the EA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/12/2024	Active	10086036
10086038	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			B300 300	TCAS II and EHS Upgrade on B300	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-ACNS issue 5;CS-23.1306 and CS-23.1308 at Amendment 4The requirements for environmental protection and the...	Instructions for Continued Airworthiness Ref MODE00499_ICA1_2XL rev 1dated 22/07/2024; Airplane Flight Manual Supplement Ref MODE00499_AFMS1rev 1 dated 02/05/2024 and MODE00499_AFMS2 rev 2 dated 05/12/2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	This design Change does not cover the TCAS antennas installation.Prior to installation of this change/repair it must bedetermined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repairwill introduce no adverseeffect upon the airworthiness of th...	11/12/2024	Active	10086038
10086043	ALAMO ENGINEERING GmbH			CL-600-2B19 (RJ SERIES 100)	Certify CL-600-2B19 / RJ 100 as PED tolerant / WIFI ActivationThis STC is for certifying the aircraft type as being T-PED tolerant(with limitations) and to activate a previously installed deactivatedWLAN router. There is no connection to the aircraft’s avionics.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25, Amdt. 28 for1309, 1319, 1353, 1360, 1431, 1529, 1707.The requirements for environmental protection a...	Master Document List, MDL23A65AE-02, Rev. AFlight Manual Supplement, FMS23A65AE-02, Rev. BInstructions for Continued Airworthiness, ICA23A65AE-02, Rev. Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	AFMS Limitation: During low visibility approaches (ILS CAT II/III) theWLAN System has to be deactivated and all PEDs have to be set to“Flight-Mode” or turned off.Implementing thischange requires to have an IEEE 802.11() compliantWLAN router installed. The installation of the deactivated on-board WL...	11/12/2024	Active	10086043
10086044	B/E AEROSPACE, Inc. - FSI		FAA STC ST02410SE	737-800	Installation of an interior reconfiguration on Boeing Model737-800	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 initial issue: 25.853<(>,<)>Jar 25 Chg 14: 25.869<(>,<)>CS 25 amdt 6: App. F Part IThe requirements for environmental...	B/E Aerospace Inc. - FSI (B/E - FSI) Master Drawing List (MDL)B2FS222-D01, Revision C, dated 16 September 2014<(>,<)>Instructions for Continued Airworthiness, B/E - FSI DocumentB2FS222-D15, Revision A, dated 14 August 2014<(>,<)>or later revisions of the above listed document(s) approved/ accepted on...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	12/12/2024	Active	10086044
10086045	SPACE EXPLORATION TECHNOLOGIES CORPd/b/a Starlink Aviation		FAA STC ST04739NY	777-300ER 777-200LR	Installation of Dual SpaceX Starlink Aviation System	The Type and OSD Certification Basis for the original product as amendedby the following additional or alternative airworthiness requirements:CS25 amdt. 4: CS25.613(a)(b)(c), CS25.869(a)(1)(4), CS25.1353(a)(d),CS.25.1431(c)The requirementsfor environmental protection and the associatedcertified noi...	Master Data List (MDL) SPX-00006088, ver 2.0, dated 10 October 2024<(>,<)>Instructions for Continued Airworthiness (ICA) SPX-00006435, ver 2.0,dated 6 September 2024<(>,<)>Aircraft Flight Manual Supplement (AFMS) SPX-00006363, Rev IR, dated 10October 2024<(>,<)>or later revisions of the above listed...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.This approval does not cover the SpaceX Starlink Antenna...	21/01/2025	Active	10086045

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086057	DE HAVILLAND AIRCRAFT OF CANADALIMITED		TCCA SA19-108 ISSUE 2	DHC-6 SERIES 400	Aft Lavatory installation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23 Amdt. 0: CS23.853(d)(1).The requirementsfor environmental protection and the associatedcertified noi...	- Elisen & associés inc. Modification Data Summary MDS-3027Revision A,dated November 29, 2019- Elisen & associés inc. Airplane Flight Manual Supplement FMS-3027Revision A, dated November 29, 2019- Elisen & associés inc. Instructions for Continued AirworthinessICA-3027 Revision A, dated November 29,...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	17/12/2024	Active	10086057
10086061	JET AVIATION AG			A320-251N	VVIP Cabin Interior CompletionInstallation of a VVIP cabin interior into a green Airbus A320-251N (ACJ320neo).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:. 25.23, 25.25, 25.27, 25.29, 25.251, 25.301, 25.302, 25.303, 25.305,25.307, 25.321, 25.337, 25.341, 25.561(...	JBSC-M-03910CER-001, Rev D Certification ProgramBSC-M-03910MDL-001 ISSUE A MASTER DATA LISTJBSC-M-03910AFM-001 ISSUE A AIRPLANE FLIGHT MANUAL SUPPLEMENTJBSC-M-03910ICA-001 ISSUE BINSTRUCTIONS FOR CONTINUED AIRWORTHINESSJBSC-M-03910CCD-001ISSUE B CABIN CREW DATAor later revisions of the above liste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/12/2024	Active	10086061
10086066	ALAMO ENGINEERING GmbH			EMB-135LR, EMB-145 EMB-135BJ, EMB-135ER	Activation of WLAN and interfacing PED ProductsThis STC is for certifying the aircraft type as being T-PED tolerant(with limitations) and to activate a previously installed deactivatedWLAN router. There is no connection to the aircraft's avionics.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25, Amdt. 27 for25.1309, 25.1319, 25.1353, 25.1360, 25.1431, 25.1529.The requirements for environmentalc...	Flight Manual Supplement, FMS23A18AE-01, Rev. BInstructionsfor Continued Airworthiness, ICA23A18AE-01, Rev. AMaster Document List, MDL23A18AE-01, Rev. Bor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	AFMS Limitation: During low visibility approaches (ILS CAT II/III) theWLAN System has to be deactivated and all PEDs have to be set to"Flight-Mode" or turned off.Implementing thischange requires to have an IEEE 802.11() compliantWLAN router installed. The installation of the deactivated on-board WL...	16/12/2024	Active	10086066
10086067	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST04593AT	777F 777-300ER 777-300 777-200LR 777-200	Installation of a Collins Aerospace SAT-2200 Inmarsat SATCOMCommunications System upgrade	The Certification Basis for the original product as amendedby thefollowing additional or alternative airworthiness requirements: thefollowing paragraph(s) at a later amendment:CS25 initial issue: 25.29, 25.601, 25.1307, 25.1431, 25.1529,25.1541,25.1583CS 25 amdt 1: 25.305CS 25 amdt 5: 25.1301CS 2...	- ASG Master Data List 223304-MDL, Revision A, dated 07 May2024;- Instructions for Continued Airworthiness (ICA) document 223304-ICA,Rev IR, dated 25 March 2024;or later revisions of the above listed document(s) approved/accepted onbehalfof EASA in accordance with the Technical ImplementationProce...	Aircraft must be equipped with an existing Inmarsat SATCOM system orprovisions.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airwor...	16/12/2024	Active	10086067
10086069	PMV ENGINEERING	REV. 1		ATR 72-212 A	STARLINK SATCOM INSTALLATIONInstallation on ATR72 models with commercial designations ATR 72-500 andATR 72-600Revision 1 updates the associated technical documentation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): PCRI-0000251-60090581"Vibration/buffeting compliance criteria forlarge external antennainstallation" Issue 2.- The following2...	Master Document List SCA-01760-MDL-S01 Rev02 (applicable tocertification prototype aircraft only)Master Document List SCA-01760-MDL-S02 Rev02Instructions for Continued Airworthiness SCA-01760-ICA Rev01AFM Supplement SCA-01760-AFMS rev02or later revisions of the above listed document(s) approved/acce...	Inspections as per ICA document SCA-01760-ICA.Prior to installation of this change/ repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	06/05/2025	Active	10086069

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086078	Q.C.M. DESIGN GmbH			FALCON 7X	Halon-free Fire Extinguisher InstallationHalon-free portable fire extinguisher P/N, ETSO approved article,replacement.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	DF7X-QCM26-001-M1-ICA Rev. 1 dated 24 Jul 2024< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	None	17/12/2024	Active	10086078
10086080	RECAERO			A320-271N	RCP048 - A320 Cabin reconfigurationComplete PAX seat replacement (same PAX qty) with new ISPSS system & ELTreplacement	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	RCP048MDL001 Master Data List Issue 1RCP048AMS001 Aircraft Manual Supplement Issue 1RCP048OMS001 Operating Manual Supplement Issue 1Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Innovint SB IMOD0014, approved as a Minor Change by InnovintEASA.21J.770.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthine...	17/12/2024	Active	10086080
10086089	SIRIUM AEROTECH S.L.			737-800	Installation of Portable EFB HolderInstallation of two EFB holders suitable for portable EFBs containinglithium batteries, in the flight deck compartment.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC-G25.1585-01 Issue 02.- The following paragraph(s) at a later amendment: CS MMEL Issue 03: CSMMEL.110; MMEL.115; MMEL.120; MMEL.125;...	Master Data List: ref: SA24-15S-MDL Rev. 03AFM Supplement: ref: SA24-15S-AFMS Rev. 02MMEL Supplement: ref: SA24-15S-MMELSRev. 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Aeroplanes modified with this STC must be operated in accordance withAFM supplement SA24-15S-AFMS and MMEL Supplement SA24-15S-MMELS.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or...	18/12/2024	Active	10086089
10086108	AERONAUTICS SOLUTIONS EUROPE S.L.			AT-802, AT-802A	SUBSTITUTION OF basic instrumentation by an Electronic display PFD/MFDGARMIN GDU 1060 (G600 Txi).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List, Ref. ASE-019MDL, Issue 1, Date: 05/12/2024.Flight Manual Supplement, Ref. ASE-019FMS, Issue 1, Date: 05/12/2024.Instructions for Continued Airworthiness, Ref. ASE-019ICA, Issue 1,Date: 05/12/2024Or later revisions of the above listed document(s) approved/ acceptedunder the EASA...	Prior to installation of this change, aircraft configuration must complywith concurrent requirements defined in section2.2 of applicableService Bulletin.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously ins...	20/12/2024	Active	10086108
10086111	T.P.S. S.P.A.			A109S	HEMS interior on A109S Trekker / Installation of a HEMS kitcomposed bya fixed and a removable parts.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- TPS109-1700-Mdw-0 Master Drawing list Issue 0 dated 18 March 2024.- TPS109-1700-ICA-0 Instructions for Continued Airworthiness Issue 0dated 18 December 2024.- TPS109-1700-RFMS-0Rotorcraft Flight Manual Supplement Issue 0Or later revisions of the above listed document(s) approved/acceptedunder the...	- Installation of the HEMS interior kit p/n TPS109-17-00, requires thehelicopter to be equipped with the following, namely A109S Trekker: - Trekker Kit Leonardo P/N 109G0000F01-101; - Interior Utility (3+3 passengers configuration) Leonardo P/ N109G2520F33-103- Installation of the HEMS interior...	20/12/2024	Active	10086111

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086113	JET AVIATION AG			GVI (G650)	VVIP Interior Completion	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC-F25.1445-01 - Installation of a therapeuticoxygen system.- The following paragraph(s) at a later amendment: 25.23, 25.23, 25.25,25...	JBSC-M-03966MDL-001 ISSUE B MASTER DATA LISTJBSC-M-03966AFM-001 ISSUE F AIRPLANE FLIGHT MANUAL SUPPLEMENTJBSC-M-03966ICA-001 ISSUE A INSTRUCTIONS FOR CONTINUED AIRWORTHINESSor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/12/2024	Active	10086113
10086114	AMAC AEROSPACE SWITZERLAND AG			A319-153N	Interior OutfittingThe change consists of a complete cabin interior outfitting of theA319-153N with 19 passengers VIP and 2 cabin crew seats for private useonly	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: The followingparagraphs of CS-25 at Amendment 21 are applicable to this change:CS25.1, CS25.20, CS25.21, CS...	The change is defined with Revision C of Master Data List documentMDL-MT01-2500.The aircraft shall be operated in accordance with Revision C of AirplaneFlight Manual Supplement document AFMS-MT01-2500.The aircraft shall be maintained in accordance with Revision B ofInstructions for Continued Airwort...	Private use only.Follow Limitations as outlined in AFM Supplement AFMS-MT01-2500.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the air...	20/12/2024	Active	10086114
10086118	Q.C.M. DESIGN GmbH			560XL	COLLINS IRIDIUM CERTUS SATCOM INSTALLATION	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1 ; CS 25.21 ;CS 25.23 ; CS 25.25 ; CS25.27 ;CS 25.29 ; CS 25.251; CS 25.301 CS 25.303 ; CS 25.30...	C560-QCM23-001-M1-ICA Instructions for Continued Airworthiness <(>,<)>rev 0 dated 10/12/2024C560-QCM23-001-M1-AFM Aircraft Flight Manual Supplement<(>,<)> rev 0dated 11/6/2024C560-QCM23-001-M1-MMS Maintenance Manual Supplement<(>,<)> rev 0dated12/9/2024C560-QCM23-001-01 Certification Report rev 0 d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/12/2024	Active	10086118
10086122	PAL AEROSPACE LTD.	REV. 1	TCCA A-LSA19-031/D ISSUE 4	DHC-8-106	Observer Window Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1529 at InitialIssue.The requirements for environmental protection and the associatedcertified noisea...	Installation shall be performed in accordance with DECA AviationEngineering Limited Master Data List MDL16062-09, Revision 4Maintenance shall be performed in accordance with DECA AviationEngineering Limited Instructions for Continued AirworthinessICA16062-09, Revision 1Compliance with Airworthinessm...	Limited to Serial Number 275, 314, 317 and 390.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce noadverseeffect upon the airworthiness of the product.	16/01/2025	Active	10086122
10086135	AVCON INDUSTRIES, Inc.		FAA STC SA04744NY	208B	Installation of New External Radar Pod with Retractable EO/IR SensorLift Mechanism	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	1. Master Data List (MDL) C208B-MDL-0154, rev IR, dated 10 December2024;2. Instructions for Continued Airworthiness (ICA) 08207200, rev A, dated27 November 2024;3. Aircraft FlightManual Supplement (AFMS) 08207100, Rev IR, dated 11December2024;or later revisions of the above listed document(s) appr...	Aircraft Applicability, Model 208B1. S/N 208B0001 through 208B0178 and 208B0180 through 208B0229, and asmodified by SK208-84 with PW PT6A-114 engine or with PW PT6A-114A enginewhen operated to PT6A-114 operating limitations and without theoptionalTKS ice protection system.2. S/N 208B0179, 208B0230P...	06/01/2025	Active	10086135

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086141	HONEYWELL INTERNATIONAL Inc.		FAA STC ST02820LA	SEE FAA AML	Installation of the Honeywell MKV-A EGPWC	The Type and OSD Certification Bases for the original product as amendedby the following additional oralternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25 Amdt. 0: 25.1431, 25.1529CS-25 Amdt. 5: 25.1301, 25.CS-25 Amdt. 18: 25.1351CS-25 Amdt. 24: 25.1309The r...	See AML 276-0287-003 Revision A, dated 14 August 2024 for model specificMaster Drawing List (MDL), Instructions for Continued Airworthiness (ICA) and Airplane Flight Manual Supplement (AFMS)<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approvedl...	11/03/2025	Active	10086141
10086181	Q.C.M. DESIGN GmbH			BD-700-2A12 BD-700-1A10, BD-700-1A11	LOPA Change – Credenza Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt. 28Appendix S.The requirements for environmental protection and the associatedcertified noise and...	Certification Report BBD7-QCM25-105, Rev. 0, dated 08.06.2024Aircraft Flight Manual Supplement BBD7-QCM25-105-M1-AFM, Rev. 0, dated22.03.2024or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to a/c s/n 9252.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon theairworthiness of the product.	10/01/2025	Active	10086181
10086182	GULFSTREAM AEROSPACE CORPORATION		FAA ST04304AT-D	GV, GV-SP	Installation of GoGo Business Aviation Avance L5 System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Index List CE513028003, Revision G, dated April 7, 2022.Airplane Flight Manual Supplement CE51302M007, Rev (-), dated December6, 2017.Airplane Flight Manual Supplement CE51302M008, Rev (-), dated December6, 2017.Instructions for Continued Airworthiness CE51302A015, Revision A, datedDecember 17, 2019...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/01/2025	Active	10086182
10086202	RSG PRODUCTS, Inc.D/B/A INTEGRATED FLIGHT SYSTEMS, IN		FAA STC SH3886SW	412EP 412 212	Installation of Rappell System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	- Helidyne Drawing HD-412-00-0005, Rev. H dated 9 February 1995.Assembly and detail part on HD-412-62-3001 Rev. G dated19 September1988;- Rotorcraft Flight Manual Supplement, HDD-87-34, IR, dated 16 December1987;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA i...	Heli-Dyne Rappel System with left/right egress capabilitiesshall not beinstalled in conjunction with Heli-Dyne fixed steps.Prior to installation of this change/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair wi...	15/01/2025	Active	10086202
10086209	TELAIR INTERNATIONAL GMBH			A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-243 A330-201/-202/-203	Telair Door Sill Latch SystemInstallation of Door Sill Latch System on Forward and Aft Lower DeckCargo CompartmentPart Number: 930100-1 (A330-200)Part Number: 930100-3 (A330-300)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:CS 25.301 a,b,c @ amdt 18CS 25.303 @ amdt 00CS 25.305 a,b,c @ amdt 01CS 25.307a @ amdt 01CS 25.601 @ amdt 00CS...	-Configuration Index Document, CID930100-1, initial issue, dated03.12.2024- Instructions for Continued Airworthiness, ICA930100-1, initial issue,dated 26.11.2024Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Precondition for the installation of the Door Sill Latch System (P/N930100-1, P/N 930100-3): 1. existence of all necessary attachment points.2. existence of electrical cable with connectors in the aircraft.Preconditions 1. and 2. are fulfilled if ALL the following equipmentpart numbers are or were in...	17/01/2025	Active	10086209

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086215	AVIATION SUPPORT GmbH			AS 332 L1	Ballistic Protection Kit for AS332 L1 and L1e cockpitInstallation of a ballistic protection for pilot and copilot within thecockpit.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	ICA-ASE-920004 revision 1-5 – Instructions for continued airworthinessFM-ASE-920004 revision 0-4 – Flight Manual SupplementCR-ASE-92004 revision 0-1 – Compliance reportNP-ASE-92004 revision 1-5 – Compliance checklistASE-FORM-02-92004 original revision - Declaration of Complianceor later revisions of...	Rotorcraft should be pre-equipped with the following modification forthis STC to be installed:First, the installation of the floor protection panels can be performed:- either on existing attachment provisions for the OEM ballisticprotection kit accordingto MDF 46-00-05 (or equivalent)- or on the at...	20/01/2025	Active	10086215
10086234	LEE AEROSPACE, INC.	REV. 1	FAA STC ST04217NY	35A/36/36A 24F-A/25/25B/25C/25D/ 25F/31/35 24/24A/24B/24B-A/24D/ 24D-A/24F	Installation of LAI WindshieldsRev. 1: Correction of typos	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:NEW-PAGEthe following paragraph(s) ata later amendment:25.305(a)(b) Amdt. 1,25.307(a)(d) Amdt. 0<(>,<)> 25.603(a)(b)(c) Amdt. 27<(>,<)>25.605(a) Amdt. 0<(>,<...	Master Data List, LAI-MDL-134, Revision IR, dated 8 June 2022<(>,<)>Instructions for Continued Airworthiness (ICA) LAI-ICA-134, Revision IR,dated 23 May 2022<(>,<)>Installation Instructions, LAI-INSTL-134, Revision B, dated 23 May 2022<(>,<)>or later revisions of the above listed document(s) approve...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.This STC is applicable to all serial numbers for the Mak...	17/02/2025	Active	10086234
10086242	AIRBORNE TECHNOLOGIES GmbH			DHC-6 SERIES 300	DHC6-300 Survey ConfigurationWith this change the aircraft is equipped with an EO/IR camera in thenose together with a Visual Radar System (Vidar). The system control isprovided from Operator Workstation located on the RH side of thepassenger cabin in front of the emergency exit.Beside the Operatora...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:§ 23.21, 23.29, 23.45, 23.49, 23.51, 23.65, 23.67, 23.75 23.77, 23.141,23.143, 23.145, 23.147, 23.149, 23.16...	Change Protocol STC-190-G-CHPR, Revision 0, dated 17.01.2025Aircraft Flight Manual Supplement STC-190-G-AFM, Revision 0, dated07.01.2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/01/2025	Active	10086242
10086254	AIRBUS S.A.S.			A330-243	Airbus STC Solutions MOD AI0329 - Prepare cabin FOR MRTT conversion.This modification describes the preparation of cabin for MRTT conversionon A330-243 MSN 1657.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Summary Report reference SRSA-24003 Issue D dated 14January 2025Modification Approval Sheet MAS n° AI0329issue 1 referring to MDLAI0329 issue B.Airplane Flight Manual supplement for MSN 01657 referenceAFM-S_MOD_AI0329 rev 00dated 01 October 2024.or later revisions of the above listed...	Zero occupancy and no Cargo in the passenger cabin during TTOL andFlight.Prior to installation of this change/repair itmust be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthine...	24/01/2025	Active	10086254
10086259	AEROLITE AG			AW169	EMS Equipment P/N 169-0341300-501 consisting of two Equipment Racksinstalled in the rear of the cabin, in two alternative configurations.(Aerolite AG reference P13233)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program ref. CPR-23-027 Rev. D, release date 23.01.2025Master Document List ref. MDL-23-005 Rev. N/C, issue 1-0 dated21.01.2025Flight Manual Supplement ref. FMS-169-0341300-501 Rev. B, issue date15.01.2025Operations Manual ref. OPM-169-0341300-501 Rev. A, issue date 16.12.2024or lateru...	This modification only applies to helicopters with Kit SkidLanding GearSystem installedPrior to installation of this change/repair it must be determined thatthe interrelationshipbetween this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon...	27/01/2025	Active	10086259

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086263	MUNZ, BENEDICT			NL-STU/840, NL-STU/ 1000 NL-STU/510, NL-STU/640	Introduction of a Lightweight 4 Person Basket for Gasballoons.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-31GB InitialIssue.	Certification Programme BPK Revision 01, dated 07.01.2025Handbuchanhang BPK Issue 01, dated 07.01.2025Technische Mitteilung BPK Issue 01, dated 07.01.2025or later revisions of theabove listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/01/2025	Active	10086263
10086270	HELICOPTEROS DO BRASIL S/ ADBA HELIBRAS		ANAC STC 2023S04-07	EC135 P3, EC135 T3	Installation of Open Doors Warning System in accordance with MasterDocument List 135B04 0007	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Master Document List 135B04 0007 Issue F- Rotorcraft Flight Manual Supplement H.02-5863-0/ ANAC/2024 Revision 0- Instructions for Continued Airworthiness STC-HB-206-ICA Revision 1or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical I...	Limited to helicopters with Helionix cockpit variant.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and anyotherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product	27/01/2025	Active	10086270
10086271	BAUERMEISTER AIRCRAFT INTERIOR GMBH			737-800	P028 - B737-800 Cabin Reconfiguration Y186 to Y189.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS25 Amdt. 27: 25.853 (a) (c) (d), 25.1529, 25.1729.The requirements for environmental protection and the as...	Instructions for continued airworthiness, Ref. BAI-P028-ICA Issue 02dated 21 January 2025.Master data list, Ref. BAI-P028-DOC Issue 00 dated 21 January 2025or later revisions of the above listed document(s) approved/acceptedunder the EASAsystem.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/01/2025	Active	10086271
10086338	BOEING IRELAND LIMITED			787-8	271 Passenger Interior Reconfiguration including mini suiteinstallationThis modification introduces a cabin layout using 20 mini suite businessclass seats, 48 economy plus seats and 203 economy class seatsgenerating a 271 passenger seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-10 Installation of mini-suite type seatingThe requirements for environmental protection and the associatedcertified noise and/ or emis...	The change is defined with Revision 0 of Boeing Ireland Change/ RepairApproval document BIL-00232-APPThe aircraft shall be operated in accordance with Revision 4 of BoeingIreland Aircraft Flight Manual Supplement BIL-00232-AFM01The aircraftshall be maintained in accordance with Revision 0 of BoeingI...	Follow limitations defined in BIL-00232-AFM01Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	03/02/2025	Active	10086338
10086351	ALOFT AEROARCHITECTS		FAA STC ST03741NY	A321-272N/-272NX A321-253NX/-253NX/-271N/-271NX A321-251NX/-252N/-252NX/-253N A321-213/-231/-232/-251N A321-111/-112/-131/-211/-212 A320-231/-232/-233 A320-211/-212/-214/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Viasat KA SATCOM Antenna System Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	ICAa.,,Viasat Document No. 1277470, revision 012, dated 15 January 2024,b.,,Viasat Document No. 1325037, revision 006, dated 15 January 2024<(>,<)>c.,,Viasat Document No. 1377410,revision 008, dated 15 January 2024<(>,<)>d.,,Viasat Document No. 1403366, revision 004, dated 15 January 2024<(>,<)>e.,...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.The STC is in compliance with 14CFR 36.7, Acoustical Cha...	05/02/2025	Active	10086351

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086369	LEARJET Inc.	REV. 2	FAA ST02035WI	2. BD-100-1A10 1. CL-600-2B16 (604 VARIANT)	Installation of IRT-4400 Iridium CertusRev. 1 corrects the FAA STC reference.Rev. 2 adds the BD-100-1A model and updates the associated technicaldocumentation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: 14 CFR 25.981(a)(3) Amdt 25-102, 14 CFR 25.853(a) Amdt 25-83, and 14 CFR 25.1419 (a) Amdt 25-72.Equivalent Saf...	CL-600-2B16 (604 Variant):Master Document List BAS00015003,Revision (A), dated September 17,2024;Instructions for Continuous Airworthiness BAS63015427-ICA-1, Revision(--), dated July 9, 2024BD-100-1A10:Master Document List BAS00015003, Revision (B), dated 8 April 2025;Instructions for Continuous Ai...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The STC is valid for aircraft types and models approved...	16/06/2025	Active	10086369
10086373	MT-PROPELLER ENTWICKLUNG GmbH			C24R B24R	Installation of MTV-12-B/188-59( ) Propeller on Beechcraft B24R andC24R.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-36 Amdt 6, 14 CFRPart 36 Amdt 36-32This certificate/approval involves a change with an impact on the noise...	According to MT-Propeller Master Documentation List No. E-4281 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-4283Rev. 0To be installed i.a.w. MT-Propeller Installation Instruction Doc. No.E-4284 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4285 Rev. 0or later...	According limitation section of AFM-SPrior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviouslyinstalled change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	06/02/2025	Active	10086373
10086376	ALAMO ENGINEERING GmbH			737-800 737-700	Aircraft T-PED Tolerance CertificationThis STC is for certifying the aircraft type as being T-PED tolerant(with limitations) and to activate a previously installed deactivatedWLANrouter. There is no connection to the aircraft's avionics.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25, Amdt. 28 for1309, 1319, 1353, 1360, 1431,1529The requirements for environmental protection and the as...	Master Document List, MDL24A41AE-01, Rev. AFlight Manual Supplement, FMS24A41AE-01, Rev. BInstructions for Continued Airworthiness, ICA24A41AE-01, Rev. Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	AFMS Limitation: During low visibility approaches (ILS CAT II/III) theWLAN System has to be deactivated and all PEDs have to be set to"Flight-Mode" or turned off.Implementing thischange requires to have an IEEE 802.11() compliantWLAN router installed. The installation of the deactivated on-board WL...	06/02/2025	Active	10086376
10086378	LEE AEROSPACE, INC.		FAA STC ST04745NY	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	Installation of LAI Cockpit Side Windows on Bombardier Inc., Challenger600	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25.613(a)(b)(c) at amdt 1CS 25.853(a) at amdt 23Appendix F, Part I, para (a)(1)(iv) at amdt 17The requireme...	Master Data List (MDL) LAI-MDL-139, Rev. IR, dated 27 November 2024<(>,<)>Instructions for Continued Airworthiness (ICA) LAI-ICA-139, Rev. B,dated 22 August 2024<(>,<)>or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implementatio...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.This STC is applicable to all serial numbers for: Bombar...	17/03/2025	Active	10086378
10086384	PMV ENGINEERING			BD-500-1A11	Starlink Satcom activation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): "Vibration and buffeting on largeantenna" PCRI-0000251-0060090547Issue 3.The requirements for environmental protection and th...	Master Document List SCA-1700-MDL-S01 Rev02AFM Supplement SCA-01700-AFMS Rev00Instructions for continued Airworthiness SCA-01700-ICA-S01 Rev00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Limitations as per ICA documents- The prerequisite in...	07/02/2025	Active	10086384

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086387	AVMAX AVIATION SERVICES Inc.		TCCA SA24-3	DHC-8-315 DHC-8-314 DHC-8-311 DHC-8-301 DHC-8-202 DHC-8-201 DHC-8-106 DHC-8-103 DHC-8-102	Battery Access Kit	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: JAR 25.29, 25.301,25.303, 25.305, 25.307, 25.601, 25.603, 25.605, 25.607, 25.609, 25.611,25.613, 25.619, 25.6...	Installation of the Battery Access Kit must be done in accordance withAvmax Aviation Services Inc. Engineering Order CE524-400-01, Issue B.Maintenance of the Battery Access Kit must be done in accordance withAvmax Aviation Services Inc. Maintenance Manual Supplement CE524-700-01,Issue B.or later rev...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/02/2025	Active	10086387
10086388	ETIHAD AIRWAYS ENGINEERING L.L.C.			SEE EASA APPROVED MODEL LIST	HALON-free fire extinguishers installation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25 amdt 28:25.29(a), 25.301, 25.303, 25.305(a) , 25.307(a)(d) , 25.561 (a)(b)(c) ,25.601, 25.603, 25.609...	See EASA Approved Model List<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limitations as per AMM supplement.	10/02/2025	Active	10086388
10086390	SABENA TECHNICS BGC			A320-214	Cabin Reconfiguration from 133 PAX (16 B/C + 117 Y/C) to 180 PAX (180Y/C)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 at amendment 4 for paragraphs: 25.1, 25.29, 25.301, 25.303,25.305, 25.307, 25.321, 25.337, 25.341, 25....	Master Data List Ref. 41364-01-A-MDL-R00 dated 07 Feb 2025Instructions for Continued Airworthiness Ref. 41364-01-A–ICA Rev. 00Cabin Crew Data Ref. 41364-01-A–OSDCD Rev. 00or laterrevisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The following changes shall be installed concurrently t...	10/02/2025	Active	10086390
10086394	NEXTANT AEROSPACE, L.L.C.		FAA ST04611CH	GV, GV-SP, GIV-X	Installation of a SpaceX Starlink Aviation System on Gulfstream GIV-X,GV-SP and GV aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): list Equivalent Safety Finding(s)1. FAA ELOS Memo [No.] ENV22044-F-1, Vibration and BuffetingRequirements for Ku Band AntennaG...	1.Master Data List, Document No. NT0078-MDL0-0100 Revision CFAA2. Airplane Flight Manual Supplement, Document No. NT0078-AFMS-0100Revision IR3. Airplane Flight Manual Supplement, Document No. NT0078-AFMS-0200Revision IR4. Instructions for Continued Airworthiness, Document No.NT0078-ICA0-0100 Revisio...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	11/02/2025	Active	10086394
10086396	AIRBUS S.A.S.			A321-253N	MOD AI0325 - Install monuments & emergency equipmentThe project is the installation of a Galley and a Stowage withassociated Emergency Equipment on Airbus A321-253N.The project iscertified together with Airbus MOD 174545.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Certificate Solution Certification Summary ReferenceSRSA-24005 issue Edated 27 January 2025.MAS AI0325 issue 1 referring to MDL AI0325 issue B.Instruction for Continued Airworthiness as per document referenceE25D24029778 RevA dated 22 Jan 2025or later revisions of the above listedu...	This project is to be installed concurrently with Airbus MOD 174545.Prior to installation of this change/repair it mustbe determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of...	11/02/2025	Active	10086396

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086412	AERODESIGN AND MANUFACTURINGTECHNOLOGY S.L.			ATR 72-212 A	Change affecting emergency exit signsChange of emergency exit signs from red lettering to green running man	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.811 (e)(4), CS 25.811 (g), CS 25.812 (b)(1), CS 25.812 (e)(2), CS25.853 (a), CS 25.853 (d), CS 25.1309...	MOBT-2410-MDL Rev 01 “Master Data List"<(>,<)>Or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/02/2025	Active	10086412
10086416	SABENA TECHNICS BGC	REV. 1		EC 120 B	Installation of halon free Umlaut fire extinguisher P/N P3APP003010Dwith extinguishing agent 2-BTP (Halotron® BrX).Revision 1: Introduction of a pre-requisite for certain helicopters.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data list and Declaration of Compliance 2152-01-A-MDL, Revision01 dated 31 January 2025.Rotorcraft Flight ManualSupplement 2152-01-A-RFMS, Revision 01 dated 10June 2024.Instructions for Continued Airworthiness 2152-01-A-ICA, Revision 01dated 31 January 2025or later revisions of the above lis...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Pre-requisite installation of Eurocopter Service Bullet...	18/06/2025	Active	10086416
10086418	APTOZ EHF.			SEE EASA APPROVED MODEL LIST	Installation of KANNAD ULTIMA-S portable ELT	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): See EASA Approved Model List.- The following paragraph(s) at a later amendment: See EASA ApprovedModel List.The requirements for envir...	See EASA Approved Model List<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Flight Deck installation is not allowed in specific A/C...	12/02/2025	Active	10086418
10086426	SKYTEC AEROSPACE GmbH			560XL	Installation of an Inverter and 2ea 230VAC universal power outlets inthe LH forward refreshment center.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 26.150 at Issue 4.The requirements for environmental protection and the associatedcertified noise and/ o...	Master Data List MDL-C560C129-0005 rev. A dated 11.02.2025Instructions for Continued Airworthiness ICAS-C560C129-0004 rev. C dated11.02.2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Removal of the Microwave and Hot LiquidContainer via Sk...	13/02/2025	Active	10086426
10086435	AVCON INDUSTRIES, Inc.		FAA STC ST01926WI	36A 36 35A 35	Interface of factory installed FC-530/ FC-535 Autopilot System toSingle/Dual GTN or GTN Xi 750/650 Navigators	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	1. Master Drawing List, Document No. 02007010, Rev. A, dated 14 June2019, and2. Airplane Flight Manual Supplement, Document No. 02007136, Rev. 0,dated 11 May 2019 or Document No. 02007165, Rev. 0, dated 20 August 2020<(>,<)>3. Instructionsfor Continued Airworthiness, Document No. 04707201, Rev.1, d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	14/02/2025	Active	10086435
10086469	DASSAULT FALCON JET CORPORATION		FAA STC ST03615NY	MYSTÈRE FALCON 900 (MF900) FALCON 900EX (F900EX)	Installation of Honeywell CC-701 Cursor Control Device	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Dassault Falcon Jet Corp. Master Data List, F9XW-D0114-005,Revision IR,dated 16 August 2024<(>,<)>Airplane Flight Manual Supplement (AFMS)<(>,<)> F9XW-D0114-150, RevisionIR, dated 16 August 2024<(>,<)>Instructions for Continued Airworthiness (ICA)<(>,<)> F9XW-D0114-155,Revision IR, dated 9 August 2...	This STC is applicable to Mystere-Falcon 900 serial numbers169, 179through 202 and Falcon 900EX serial numbers 001 through 096 and serialnumbers 098 through 119 with Honeywell Primus Elite 11, DU 875 displaysinstalled by STC ST03371NY.Prior to installation of this change/repair it must be determine...	18/02/2025	Active	10086469

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086471	DASSAULT FALCON JET CORPORATION	REV. 1	FAA STC ST03612NY	FALCON 900EX (F900EX)	Installation of Garmin (Standby Flight Display System)Rev. 1: Addition of MMEL Supplement.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	(1) Master Data List (MDL) F9XW-D0109-005, Rev. C, dated 11December2024<(>,<)>(2) Instructions for Continued Airworthiness (ICA), F9XW-D0109-155, Rev.B, dated 20 November 2024<(>,<)>(3) Airplane Flight Manual Supplement (AFMS), F9XW-D0 109-150, Rev. C,dated 11 December 2024<(>,<)>(4) Master Minimum...	(1) This alteration is applicable to Falcon 900EX airplaneswith thefollowing commercial designations: Falcon 900EX EASy, serial numbers097, 120 through 242; Falcon 900LX, serial numbers 243 through 350:Falcon 900DX, serial numbers 601 through 624.(2) GI-275 and GDC-72B hardware, software and configu...	24/02/2025	Active	10086471
10086481	JADE ENGINEERING PTE. LTD.			A320-251N	Three Class Interior ReconfigurationThis modification introduces a cabin layout using 8 BC Seats, 24 PEYSeats and 132 EY Seats resulting in a 164 Passenger Seating Layout.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.561, CS 25.562,CS 25.785 (a)(b)(c)(f)(1)(3)(h)(2)(i)(j)(k), CS 25.787, CS 25.789 (a),CS 25.791, CS 25...	The change is defined with Revision C of Jade Engineering PTE.LTD.document JD-40BC02-1The aircraft shall be maintained in accordance with Revision 2 of JadeEngineering PTE.LTD. Airbus A320-200 Supplemental Instructions forContinued Airworthiness and EWIS ICS Source Document JD-40BC04-1or later revis...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/02/2025	Active	10086481
10086484	GAMA AVIATION (ENGINEERING) LIMITED		UK.STC. 00344, REVISION 0	MD900	MD902 Mission UpgradeThis Change equips an MD900 (902 Configuration) helicopter with a newairborne mission suite, consisting of a Flightcell SATCOM System, a NATVHF System with Maritime Band Capability, a Shine Micro AutomaticIdentification System (AIS) and a FLIR 380HD Camera System.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Certification Plan, GAEL-1818CP-01, Issue 2- Instructionsfor Continued Airworthiness (ICA), GAEL-1818ICA-01, Issue01- Master Data List (MDL), GAEL-1818MDL-01, Issue 01- Rotorcraft Flight Maunal Supplement (RFMS), GAEL-1818RFMS-01, Issue01or later revisions of the above listed document (s) accepte...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is only applicable to MD900 helicopters in the...	19/02/2025	Active	10086484
10086488	JET AVIATION AG			MYSTÈRE FALCON 50 (MF50)	FMS upgrade dual UNS-1Ew FMS/MMMs	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-ACNS issue 4 for thenavigation system requirementsThe requirements for environmental protection and the as...	Aircraft Flight Manual Supplement Ref JBSL-M-04054AFM-001 issue CInstructions for Continued Airworthiness Ref JBSL-M-04054ICA-001 Issue Aor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/02/2025	Active	10086488
10086489	EIRTECH AVIATION SERVICES LIMITED			A320-251N	A320 Cabin Reconfiguration to Dual ClassRemoval of the cabin economy class passenger seating configuration andinstallation of a dual-class seating configuration (180Y to 4J/168Y)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Aircraft maintenance Supplement ref: AMS/ 1707-001 issue 03dated 21 JAN2025-Master Document list ref: MDL/1707-001 Issue 05 dated 07 FEB 2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Aeroplane with this installation must be maintained inA...	20/02/2025	Active	10086489

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086529	AVIADECO GmbH	REV. 1		35A	GPS Antenna Provisions on Fuselage FR17	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document list Ref. MDL-06124 Rev 02Instructions for Continuous Airworthiness Ref. ICA-06124 Rev 02or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This design change is applicable to S/N 35A-346 and S/N...	06/08/2025	Active	10086529
10086530	AVIADECO GmbH			A350-941	A350-900 Change to OSD-CCDModifications of Cabin Zone Definitions and Cabin Functions to meetEdelweiss Cabin Standard and update associated Cabin crew data.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	CCD supplement ref CCD-03324 Rev.03 dated 19 Feb 2025MDL: MDL-03324 rev.02or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Minor Mod referenced ADC-M03124 and SCOM-03324 and EASA...	27/02/2025	Active	10086530
10086534	ACC COLUMBIA Jet Service GmbH			35A	LJ35A Secondary ADI Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List ref MDRWL_24-91015 rev 0 dated 20/03/2025Service Bulletin ref ACJ_SB_2025-03 rev 0 dated 25/03/2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limited to aircraft S/N 35A-075	26/03/2025	Active	10086534
10086536	SIRIUM AEROTECH S.L.			ATR 72-212 ATR 72-211 ATR 72-202 ATR 72-201 ATR 42-500 ATR 42-400 ATR 42-320 ATR 42-300	Halon Hand-held Fire extinguisher replacement by Umlaut halon freeequivalent, covering configurations C-001, P-002 and P-003.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 amdt. 12: 25.851The requirements for environmental protection and the associatedcertified noise and/ or...	Master Data List SA23-74S-MDL rev 02AMM Supplement SA23-74S-AMMS rev 01or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/02/2025	Active	10086536
10086547	TRIEB GmbH			DA 40 D	Increase of the MTOW (Normal Category) from 1150kg to 1200kg.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The environmental protectionrequirements are amended as follows:CS 36 Amendment 6...	The change is defined with Engineering Order Doc. EOMD29/F07 Revision 1,dated 20.02.2025Flight Manual Supplement AFM-EOMD029-01, Rev 2, dated 20 Feb 2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Applicable to DA40D s/n 40.080, 40.084 and D4.001 throu...	27/02/2025	Active	10086547
10086551	BELL TEXTRON PRAGUE, a.s.			429	BHP 326 Mirror System Installation.The external mirror system installation consists of heated steerablesling load mirrors and fixed cargo hook mirrors.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program, Document No. BHP 326 CP Rev. B, dated 24 Feb2025;Rotorcraft Flight Manual Supplement No. BHP 326FMS Rev. A, dated 24 Feb2025;Maintenance Manual Supplement No. BHP 326 MMS Rev. A, dated 24 Feb 2025;Installation Instructions as per Engineering Bulletin No. BHP 326 EBRev. A, dat...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/02/2025	Active	10086551

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086566	AVIONIK STRAUBING ENTWICKLUNGS GmbH			414	Installation of single/dual Garmin GA 35S GPS Antenna(s) ontop fuselageand/or dual Sensor Systems S67-2002 Radar Altimeter Antennas on bottomfuselage	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation instructions ASR-2024-037-IFI-10-00 Rev 0Instructions for Continuous Airworthiness ASR-2024-037-ICA-11-00 Rev 0or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/02/2025	Active	10086566
10086567	AEROLITE AG			MBB-BK117 D-3	This STC approval is for new Emergency Medical Services (EMS) equipmentP/N 145-0334455-501 installed in the cabin of the MBB-BK17 D-3helicopter. P/N 145-0334455-501 consists of patient and medical crewaccommodation, stowage and equipment racks for medical equipment in thecabin and a related electric...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Certification Program (CP) CPR-23-043 Rev. D dated 14/02/2025;- Flight Manual Supplement FMS-145-0334455-501 Rev. B dated 26/02/2025;- Operations Manual, including Instructions for Continued Airworthiness,OPM-145-03 34455-501 Rev. 0 dated 07/02/2025;- Master Document List MDL-23-043 Rev. N/C date...	The following are pre-requisite installations for the embodiment of thisdesign change: - L852-001-00 DC Recept in Overhead Console<(>,<)> - Airbus Helicopters Deutschland (AHD) B533K8112-051 Standard cabinfloor<(>,<)> - AHD D5221-000-00 Jettisonable cockpit doors<(>,<)> - AHD D8521-000-00 EMS Fixed<...	28/02/2025	Active	10086567
10086579	VIPE 21 AS			AW169	Installation of Modular Stretcher Base (MSB)(V21 project ref. V21.D00002)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Programme, doc. V21.D00002.CPR1 issue 4.0 dated 08 August2024Master Document List, doc. V21.D00002.MDL1 issue 2.0 dated 04 March 2025Service Bulletin, doc. V21.D00002.SB1 issue 1.0 dated 18 July 2024Flight Manual Supplement, doc. V21.D00002.FMS1 Issue 6.1 dated 22November 2024Instructi...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC modification can only be installed on helicopt...	05/03/2025	Active	10086579
10086581	JET AVIATION AG			FALCON 900EX (F900EX)	VIP<(>&<)>Medevac configurationsThe cabin will be convertedto provide 3 configurations for operation.Config 1 VIP, Config 2 with one medevac module, Config 3 with twoMedEvac modules. - Config 1: VIP, 14 seating positions; - Config 2MedEvac 1: 1 MedEvac module installed on the L/H sidewith me...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): SC-D25.803-01Special Condition for MedicalEvacuation configuration Issue01.The requirements for environmental protection and the ass...	Installation in accordance with JBSL-M-03887SB-001, Issue A, Issued date2025-01-15.Operation in accordance with JBSL-M-03887AFM-001, Issue C, Issued date2025-02-28.Maintenance in accordance with JBSL-M-03887ICA-001, Issue B, Issued date2025-02-17or later revisions of the above listed document(s) app...	None	05/03/2025	Active	10086581
10086583	AIRBUS DEFENCE AND SPACE S.A.			A330-243	Government of Canada Aircraft (GOCA) conversion from AirbusA330-243model.Initial revision: 198 seats (13 F/C, 30 B/C, 155 Y/C). Cargo loadingsystem (CLS), crew rest compartment (CRC), cargo access hatch,self-protection system (SPS) and electronic flight bag (EFB) provisions. (MOD DCV1404-E, DCV1405...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.Thiscertificate/approval involves a change with an impact on the noisedatabase and/or emission levels.The environmental protection requirements are amended as follows:- ICAO Annex 16,-...	- Conversion Definition GOCA STC, Ref. TE-FC-DT-240227 issue A dated 18July 2025.- Aircraft flight manual supplement, Ref. TE-FC-DT-240128 Issue A dated23 May 2025- Limitations ofWeight and Balance Manual, Ref. TAS-F0-TD-21-0004 dated06 June 2025- GOCA ALS part 2 supplement, Ref. TE-FC-DT-250002 Is...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.. Configuration of the product upon which the change is...	25/07/2025	Active	10086583

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086609	ENGINEERING CONCEPTION MAINTENANCEd/ b/a E.C.M			777-300ER	Modification of the pitch between the three economic zones'seats inorder to create ECO+ class areas with a larger pitch and recline infront of each zone.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25 Amdt. 28Sections 25.23, 25.27, 25.29, 25.301, 25.303, 25.305, 25.307, 25.561,25.562, 25.601, 25.603,2...	MASTER DATA LIST C878-MDAL01, Rev. C, 25.02.2025.MASTER DRAWING LIST C878-MDL001, Rev. A, 14.11.2024.COMPONENT MAINTENANCE MANUAL SUPPLEMENT C878-CMMS01, Rev. A, 12.11.2024.SERVICE BULLETIN C878-SBN001, Rev. A, 28.10.2024Or later revisionsof the above listed document(s) approved/ acceptedunder the E...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Configuration approved under EASA STC 10072189 is requi...	06/03/2025	Active	10086609
10086611	BUTLER NATIONAL CORPORATION		FAA STC ST02036WI	36A 36 35A 35	Installation of an additional Garmin G700 TXi Primary Flight Display orMultifunction Display on Learjet aircraft with FC-530 or FC-535autopilots.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	FAA Approved Airplane Flight Manual Supplement (AFMS), No. 05707100,Rev. IR, signed 7 August 2024;FAA Approved Master Data List (MDL), No. 05701000, Rev. A, signed 8August 2024;orlater revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Impl...	The Avcon Industries STC, EASA STC 10086435, must be installed for thismodification.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the a...	06/03/2025	Active	10086611
10086621	AVIONIK STRAUBING ENTWICKLUNGS GmbH			414	Installation of Sensor Systems S72-1750-31L and Comant CI 490-490 on topfuselage and Sensor Systems S72-1750-32L on bottom fuselage	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23 amdt 4The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	Installation instruction Ref ASR-2024-039-IFI-10-00 Rev 0Instructions for Continuous Airworthiness Ref ASR-2024-039-ICA-11-00 Rev0or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This change is applicable for the following Textron Avi...	07/03/2025	Active	10086621
10086632	FTI ENGINEERING NETWORK GmbH			EMB-505	Mechanical provisions for the installation of a GOGO HDX antenna	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Instructions for continuous airworthiness Ref F33-E023-0073Rev 03 dated06/03/2025Master Document List Ref F18-E023-0073 Rev 02 dated 06/03/2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/03/2025	Active	10086632
10086648	SAFRAN CABIN INC.		FAA STC ST02383LA	CL-600-2D24 (RJ SERIES 900)	Interior Installations and Modifications	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS25 amdt 0: 25.561(a)-(d), 25.853(a)(c)(d) CS25 amdt 6: 25.856(a)The requirements for environmental protection...	Index List No. G371, Revision E, dated 28 August 2014;Interior Installations G371001-101,-103,-105:Instructions for Continued Airworthiness (ICA) Report No. CDRG371-78,Revision N/C, dated 12 September 2013;Interior Installations G371001-107, -109:Instructions for Continued Airworthiness (ICA) Report...	This STC approves provisions for the installation of equipment intostowage units: this STC does not cover the activation of such equipment.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change a...	28/03/2025	Active	10086648

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086674	MAMMOTH FREIGHTERS, LLC.		FAA STC ST11366DS	777-300ER 777-300 777-200	Installation of a Landing Gear Strut Data Collection System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: list CS [insert CSnumber] paragraphs + amdtThe requirements for environmental protection and the associatedce...	GDC Technics Master Data List AT-1020-MDL, Revision (P), dated 14January 2021<(>,<) >Instructions for Continued Airworthiness, Document AT-1020-TP-05,Revision (003), dated 15 December 2020<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	02/04/2025	Active	10086674
10086676	STANDARDAERO ATLANTIC USA, INC.		FAA STC SR02590AK	412EP 412 212	Installation of Bell Lightweight Tailboom Modification	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Installation Instructions, Document No. 412-2101-INST, Revision NC,dated 11 December 2024<(>,<) >StandardAero Master Document List (MDL), Document No. 412-2101-MDL, Rev.NC, dated 6January 2025<(>,<) >Rotorcraft Flight Manual Supplement for Bell Model 212, 412, 412EPequipped with Lightweight Tailboom4...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	13/03/2025	Active	10086676
10086678	AEROTEC & CONCEPT			A319-153N	Mechanical Installation of OneWeb AntennaThis modification covers the mechanical installation of a SATCOM antennawith associated provisions (interface plate, fairings, doubler,reinforcements).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): Equivalent Safety Finding (s):PCRI-0000492-0060090496 Vibration-Buffeting for Large External AntennaIssue 3.- The following par...	The change is defined with Revision 0 of Aerotec & Concept Master DataList AE24006MDL.The aircraft shall be operated inaccordance with Revision 0 of Aerotec& Concept Aircraft Flight Manual SupplementMaintenance shall be accomplished in accordance with Revision 0 ofAerotec & Concept Instructions for...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	13/03/2025	Active	10086678
10086694	ASTRONICS CONNECTIVITY SYSTEMS& CERTIFICATION CORP.		FAA STC ST04633CH	A320-233 A320-232 A320-231 A320-216 A320-214 A320-212 A320-211	Installation of Safran RA VE Wireless In-Flight Entertainment (JFE)System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 amdt. 0: 25.303,25.561(a)(b)(c) , 25.571(a)(b) , 25.601, 25.603(a)(b)(c) , 25.605(a) ,25.607(a)(b)(c) ,...	Astronics Connectivity Systems and Certification Corp. Master Data List,Doc. No. DC104-142002-00, Revision A, dated 17 December 2024;FAA Approved Airplane Flight Manual Supplement, Astronics ConnectivitySystems and Certification Corp. Doc.No. DC303-142002-00, Revision -,approved 20 December 2024;or...	This STC is applicable to all serial numbers for this Make-Model.This modification requires that the aircraft be shown to beelectromagnetically compatible with transmitting portable electronicdevices that utilize wireless data technologies.Prior to installation of this change/repair it must be deter...	28/04/2025	Active	10086694
10086714	Q.C.M. DESIGN GmbH			A321-272N/-272NX A321-271N/-271NX A321-253N/-253NX/-253NY A321-252N/-252NX A321-251N/-251NX A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-171N/-173N A319-151N/-153N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	Halon-Free Handheld Fire Extinguisher Installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:CS-25, Amdt. 17 for 25.851CS-25, Amdt. 23 for 25.1, 25.23, 25.25, 25.27, 25.601, 25.603, 25.1529,App HThe requ...	Certification Report A3SX-QCM26-001, Rev. 0, 08-Jan-2025Instructions for Continued Airworthiness: A3SX-QCM26-001-M1-ICA, Rev. 1,05-Mar-2025Operations Manual Supplement A3SX-QCM26-001-M1-OPS, Rev. 0, 08-Jan-2025Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The physical installation of the fire extinguisher is n...	18/03/2025	Active	10086714

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086718	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS	REV. 1		787-9	VIASAT satcom system activationActivation of Viasat system following Satcom Antenna InstallationRev. 1: Editorial correction.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document list: 02002-EAS-B-MDL-01 Rev.A dated 5th June 2025<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.STC 10085732 must be installed as a pre-requisite of th...	10/06/2025	Active	10086718
10086722	AERO ENGINEERING SERVICES			ATR 72-212 A	ATR72-212A CABIN LOPA CHANGELOPA change from 70 to 72 PAX. Replacement of the AFT LH and RH overheadbins and galleys, with water provision installation for the AFT RHgalley	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval except the following paragraphsat CS 25 Amendment 4:25.29, 25.301, 25.303, 25.305, 25.307, 25.333, 25,337, 25.341, 25.365,25.561(b) &(d), 25.601, 25.603, 25.605, 25.609, 25.611, 25.613, 25.61...	- P03719-MDL-001 Master Data List Rev. 1- P03719-ICA-001 Instructions for Continued Airworthiness Rev. 00Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Concurrent requirements:-AES Mod package P03930 Minor C...	19/03/2025	Active	10086722
10086723	JANZAIR CONSULTING SERVICES, INC.		FAA ST04470AT	737-800 737-700 737-600 737-500 737-400 737-300	Installation of the Honeywell TPA-100B Mode S Transponders and FreeFlight SBAS Sensor for ADS-B Out Capability.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS-25 Amdt. 18 Sections25.21, 25.301, 25.303, 25.305, 25.307, 25.365, 25.571, 25.601, 25.603,25.605, 25.607,2...	Master Data List (MDL) No. 737-3499-1901, Rev. C, dated April 01, 2021.Airplane Flight Manual Supplement (AFMS) No. 737-3499-1910, Rev. IR,dated January 10, 2020.Instructions for Continued Airworthiness (ICA) No. 737-3499-1904, Rev.A, dated December 30, 2019.Or later revisions of the above listed do...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/03/2025	Active	10086723
10086729	JET AVIATION AG			GVIII-G700	Cabin Interior G700 SN50Installation of a VVIP cabin interior into a green Gulfstream GVIII-G7	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approThe requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	JBSL-M-04131MDL-001 ISSUE D MASTER DATA LISTJBSL-M-04131AFM-001 ISSUE A AIRPLANE FLIGHT MANUAL SUPPLEMENTGC87006M001 ISSUE A AIRPLANE FLIGHT MANUAL SUPPLEMENTJBSL-M-04131ICA-001 ISSUE A INSTRUCTIONS FOR CONTINUED AIRWORTHINESSJBSL-M-04131ECA-001 ISSUE C EWIS INSTRUCTIONS FOR CONTINUEDAIRWORTHINESSor...	The aircraft is not configured to support Flight Crew Sleeping Facilityoperational approval because Flight Crew Sleeping Facility door ismodified to keep the door always open.Flight Crew Sleeping Facility / Forward Crew Compartment is limited to amaximum 1 crew member at all times, including duringP...	20/03/2025	Active	10086729
10086731	SIRIUM AEROTECH S.L.			A320-214	180 Passenger Cabin ReconfigurationThis modification introduces a cabin layout using 60 Economy Classtriple seats resulting in a 180 Passenger Seating Layout.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.23, 25.25,25.27, 25.29, 25.301, 25.303,25.305 (a)(b), 25.307 (a), 25.321 (a)(b),25.341 (a)(b), 25.5...	The change is defined with Revision 9 of Sirium Aerotech Master DataList document SA23-30S-MDLThe aircraft shall be maintained in accordance with Revision 2 of SiriumAerotech Conversion Bulletin SA23-30S-CB, Section 1.I. Instructions forcontinued Airworthiness (ICA)or later revisions of the above li...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/03/2025	Active	10086731

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086733	JAMCO AERO DESIGN & ENGINEERINGPRIVATE LTD.			777-300ER	JAMCO Installation of Lavatories & GalleysRemoval, installation and relocation of several lavatories and galleys.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Declaration of Compliance ref. 29B-DOC-1 Rev A dated 29 March 2025Boeing 777-300ER Supplemental Instructions for continued airworthinessand EWIS ICA Source Document,ref. JD-29BC04-1 Rev 0 dated 18 March 2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Configuration of the product upon which the change is t...	01/04/2025	Active	10086733
10086734	SOCIETE AIR FRANCE S.A.			777-300ER	4P-60J CABIN RECONFIGURATION IFE SAFRAN “RAVE” Installation/ Rearrangement	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): F-101 “Rechargeable Lithium Battery Installations” issue 3 dated 3rdFebruary 2025.- The following paragraph(s) at a later amendment:CS...	Change Approval Sheet, Ref. CAS-B777-21-005 Issue 0 dated 27 Mar 2025Aircraft Fight Manual Supplement, Ref. AFMS-B777-21-005-001 Issue 5dated 27 March 2025Instructions for continued airworthiness, Ref. ICA-B777-21-005-001 Issue0 dated 18 March 2025Operational suitability data, Ref. CCDS-B777-21-005-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Configuration of the product upon which the change is...	01/04/2025	Active	10086734
10086739	FTI ENGINEERING NETWORK GmbH			EMB-505	GOGO HDX antenna system integration	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Aircraft Flight Manual Supplement Ref F20-001-E024-0047 issue 1 dated10.02.2025Instructions for Continued AirworthinessRef F33-E024-0047 Issue 2 dated06.03.2025Master Documents List Ref F18-E024-0047 Issue 2 dated 19.03.2025or later revisions of the above listed document(s) approved/ acceptedunder t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	20/03/2025	Active	10086739
10086757	AERODATA AG	REV. 1		700	Installation of AD-AFIS-1320 Flight Inspection Guidance System incombination with CRPA GPS antenna in C700.This STC modifies the baseline C700 with equipment for flight inspectionservices and includes an additional antenna used to enhance GPS signalusability in a GPS jamming environment.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1319 Amdt. 25(Cybersecurity), and CS-MMEL,Issue 3.The requirements for environmental protection and t...	Installed in accordance with applicable documents from Master DocumentList for AFIS, Document Number MDL-AC-962, Revision 0 dated 19th March2025.Operated in accordance with Airplane Flight Manual SupplementInstallation of AD-AFIS-1320 in C700, Document Number AFM-186, Revision0, Dated 25th September...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	28/03/2025	Active	10086757
10086758	LUFTHANSA TECHNIK AG			A350-941	A350-MedEvac-Configuration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): 0000240-0060081563 Medical EvacuationConfiguration.- The following paragraph(s) at a later amendmentCCD.200(a)(b); CCD. 205(a), CCD.205...	Supplemental Type Design Document: STDD25-21/23M Rev. 01.00, dated19.Mar 2025Airplane Flight Manual Supplement: A-00-24/16-AFM Iss./Rev. 02/00, datedJan 14/25Cabin Crew Data: A-00-24-16-CCD Iss./ Rev. 02/00, dated Feb 07/25Flight Crew Data:A-00-24/16-FCD Iss./ Rev. 01/00, dated Oct 11/24Master Minimu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Per AFM Supplement-Installation is limited to layout...	25/03/2025	Active	10086758

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086763	ELBE FLUGZEUGWERKE GmbH			A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303	Airbus A330 Passenger to Freighter - Installation of optional ballastunder AFT Container	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-ENGINEERING ORDER (EO), Doc No.: EFW-EO-0227-001, Rev. A dated: 14 Feb2025-Type Investigation Report (TIR), Doc No.: EFW-TIP-0227-001, Rev. C,dated 13 Feb 2025-Instructions for Continued Airworthiness as listed in Section 2.3.6 ofEO (Doc No.: EFW-EO-0227-001, Rev. A, dated: 14 Feb 2025), Table 11or...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The installation of EASA STC 10063798 having considered...	25/03/2025	Active	10086763
10086769	EIRTECH AVIATION SERVICES LIMITED			A319-112, A320-214	Acro Series 9 Passenger Seat InstallationInstallation of Acro Series 9 passenger seats onto Airbus A319 and A320Series Aircraft.A319 is fitted with 150 YC passengers seating layout in two differentconfigurations, one of them compliant with25.562 and other onecompliant with 25.562 except (c)(5)& (6)A...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at CS25 Amendment 15:25.1, 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.365, 25.337,25.341, 25.561, 25.562*, 25.601, 25.603,...	MDL/1970-001 Master Document List, Issue 3ERT/1970-100 General Arrangement Drawing, Issue 1AMS/1970-001 Aircraft ManualSupplement, Issue 2Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Concurrent modifications:- Minor Change TCC-50512 Airli...	26/03/2025	Active	10086769
10086770	SKYTEC AEROSPACE GmbH			737-8	8C-168Y Passenger Seating LayoutThis modification introduces a cabin layout using 56 economy classtriple seats and 4 business class double seats generating a 176passenger seating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with revision C of Skytec Master Document ListDocument MDL-B738C111-0004Maintenance shall be accomplished in accordance with revision A ofSkytec Instructionsfor Continuous Airworthiness DocumentICAS-B738C111-0004or later revisions of the above listed document(s) approved/ accep...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	26/03/2025	Active	10086770
10086773	ALPINE AEROTECH LP		SH11-23	412EP 412 212	Relocation of Engine Oil Pressure Transducer.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval withou...	-Master Data List AAL-214-034-001 Rev. NI dated 2011-04-01.-Installation Instruction in accordance with ICA documentAAL-214-035-701 Rev. NI dated 2011-05-04.-Instructions for Continued Airworthiness AAL-214-035-701 Rev. NI dated2011-05-04.Or later revisions of the above listed document(s) approved/a...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/03/2025	Active	10086773
10086784	STIRLING DYNAMICS GMBH			737-800	424047 - Safair B737-800 Fleet HarmonizationHarmonisation of five 189 PAX economy class configurations into one 189PAX post-mod LOPA configuration through the STC application.The Zodiac 3135 series seats remain installed in the cabin and the samenumber of passenger life vests will be retained. The e...	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	424047-C-DL-2520-001-02 Document List for Safair B737-800 FleetHarmonizationOr later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/03/2025	Active	10086784

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086785	T.P.S. S.P.A.			AS 350 B3	Dual Hooks System for Human External Cargo.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 27.865 Amdt 8The requirements for environmental protection and the associatedcertified noise and/ or emiss...	Master Drawing List, TPS350-3100-Mdw-0Rotorcraft Flight Manual Supplement, TPS350-3100-RFMS-0Instruction for Continued Airworthiness, TPS350-3100-ICA-0Installation Instruction, TPS350-3100-SBT-0Certification Program, TPS350-3100-Cpr-07or later revisions of the above listed document (s) approved/accep...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/03/2025	Active	10086785
10086787	AIRHAWKE AEROSPATIAL Inc.		TCCA Q-LSA24-032/D ISSUE 2	A320-214	Installation of 174 RECARO 3530AS without IFERemoval of original Y/C 3530A977 & B/C 4400B420 RECARO seats and classseparation partitions, and installation of 174 RECARO 3530AS withoutIFE, PSU channel re-arrangement and CAM reprogramming.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Can-Am Aerospace Master Drawing List 25-24-13-003, Revision NC, DatedJuly 18, 2024-Can-Am Aerospace Instrctions for Continued Airworthiness 25-24-13-004,Revision NC, Dated July18, 2024Or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Tec...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This certificate covers installation limited to Aircraf...	28/03/2025	Active	10086787
10086790	METRO AVIATION, Inc.		FAA STC SR09354RC	EC135 T3 EC135 T2+ EC135 T2 EC135 T1 EC135 P3 EC135 P2+ EC135 P2 EC135 P1	Installation of Optional Equipment	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Drawing List DL135M-OPT Revision J, dated April 23, 2020;Rotorcraft Flight Manual Supplement FMS135OPT001 Revision C, datedOctober 01, 2020;Instructions for Continued Airworthiness OPT135M-1 Revision K, datedJune 18, 2029or later revisions of the above listed document(s) approved/ accepted onb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.Installation of Emergency Medical System EMS135M-100 asS...	11/09/2025	Active	10086790
10086791	METRO AVIATION, Inc.		FAA STC SR09164RC	EC135 T3 EC135 T2+ EC135 T2 EC135 T1 EC135 P3 EC135 P2+ EC135 P2 EC135 P1	Installation of an Airborne Emergency Medical System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Drawing List<(>,<)> DL135M-100 Revision R, dated June 8, 2020;Rotorcraft Flight Manual Supplement<(>,<)> FMS135M-7 Revision K, datedNovember 01, 2019;Instructions for Continued Airworthiness<(>,<)> EMS135M-1 Revision M,dated June 18, 2019or later revisions of the above listed document(s) appr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.Installation of filled oxygen bottles and the operations...	11/09/2025	Active	10086791
10086796	LUFTHANSA TECHNIK AG			747-8	747-8 Head of State VIP cabin completionInstallation of an executive interior to convert a green aircraft into aHead ofState VIP aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s):-CRI D-101 ‘Personal injury criteria of dynamic testing of side facingseats’, Issue 1, Dated: 05-May-2023The requirements for environment...	-Supplemental Type Definition Document (STDD), Doc. Nr.: STDD00-21/02M,Issue/ Rev.: 02.00, Dated: 13-Mar-2025-ComplianceChecklist (CCL), Doc. Nr.: CCL00-21/02M, Issue/ Rev.: 08,Dated: 13-Mar-2025-Airplane Flight Manual – Supplement (AFM-S), Doc. Nr.: A-00-22/101-AFM,Issue/ Rev.: 03.00, Dated: 13-Mar...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	31/03/2025	Active	10086796

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086810	MAGNETIC MRO AS			737-8	Cabin ReconfigurationThis modification introduces a cabin layout using 63 economy classtriple seats generating a 189-passenger seating configuration.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The change is defined with Issue 4 of Magnetic MRO Master Data ListMMRO-C-0224-MDL-01<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/04/2025	Active	10086810
10086815	BLACKHAWK AEROSPACE TECHNOLOGIES LL		FAA STC ST02029WI	560XL 560	Installation of Garmin GI 275 Standby Instrument and GSB 15USB Port	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Document List, Document No. 3014945, Rev. IR, dated 13 September2023<(>,<)>Airplane Flight Manual Supplement, Document No. 3014943, Rev. IR, signed17 November 2023<(>,<)>Instructions for Continued Airworthiness, Document No. 30142938, Rev. 1,dated 11 October 2022<(>,<)>or later revisions of t...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	02/04/2025	Active	10086815
10086851	AIRCRAFT COMPLETION ENGINEERING			EMB-145MK, EMB-145MP EMB-145LR, EMB-145LU EMB-145ER, EMB-145EU EMB-145, EMB-145EP EMB-135LR EMB-135BJ, EMB-135ER	New cabin layout for EMB-145 aircraftThis modification partially replaces economy cabin seat rows by a firstclass layout.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Declaration of compliance dossier ACE 2103 New Cabin Layoutfor EMB-145,ref. ACE2103_Declaration of Compliance dated 3 April 2025.Master Document List ACE2103-001 ERJ145 VIP revision 1 dated 28 March2025Aircraft Flight Manual Supplement New Cabin Layout for EMB-145, ref.ACE2103_AFM Supplement_Editio...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is applicable to any EMB-145 series equipped w...	03/04/2025	Active	10086851
10086855	INGENIO AEROSPACE INC.		TCCA SA16-10 ISSUE 4	CL-600-2B16 (604 VARIANT) CL-600-2B16 (601-3R VARIANT) CL-600-2B16 (601-3A VARIANT) CL-600-2A12 (601 VARIANT) CL-600-1A11 (600)	INGENIO Tripod Electronic Flight Bag (EFB) Mount Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List Master Data List MDL 24-08-001, Rev. B, dated January6, 2025Aircraft Flight Manual Supplement FMS 82-5001C, Rev A, dated 19 December2024or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.1) The maximum weight permitted for any Portable Electr...	04/04/2025	Active	10086855
10086856	VOCUS GMBH			ARCUS M	Installation of an alternative exhaust muffler coupling.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation of an alternative exhaust muffler coupling i.a.w. VocusGmbH document V-78-CP-001 at revision 4, dated April 1, 2025;Document List V-78-DL-000 at revision 1, dated April 1, 2025;Aircraft Maintenance Supplement document V-78-AMMS-007 at revision 0,dated March 31, 2025;or later revision...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/04/2025	Active	10086856

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086862	ROCKWELL COLLINS, Inc.		FAA STC ST00756LA-D	737-800 737-700	Installation of Rockwell Collins, Inc. Aircraft CommunicationsAddressing and Reporting System (ACARS)	The Type and OSD Certification Bases for the original product as amendedby the following additional oralternative airworthiness requirements: the following paragraph(s) at alater amendment:for B737-800 models:CS 25 amdt. 6: 25.869(a), 25.899, 25.1301(a)(b), 25.1309(a) to (f),25.1316(b)(c), 25.1353(a...	Master Data List R2473-01, Revision P, dated 15 Juni 2013<(>,<)>Aircraft Maintenance Manual Supplement AMM 2473-01, Revision B, dated 30April 2012<(>,<)>Aircraft Maintenance Manual Supplement 2699-AMM, Revision NC, dated 15October 2002<(>,<) >Aircraft Airplane Flight Manual Supplement AFM247301<(>,<)...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	28/04/2025	Active	10086862
10086864	MT-PROPELLER ENTWICKLUNG GmbH			B23, C23	Installation of MTV-18-B/183-59( ) Propeller on Beechcraft B23 and C23.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, 14 CFRPart 36 Amdt 36-32.This certificate/approval involves a change with an impact on the no...	According to MT-Propeller Master Documentation List No. E-4334 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-4336Rev. 0To be installed i.a.w. MT-Propeller Installation Instructions Doc. No.E-4337 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4338 Rev. 0or late...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	07/04/2025	Active	10086864
10086871	DE HAVILLAND AIRCRAFT OF CANADALIMITED		TCCA SA25-2	DHC-6 SERIES 400 DHC-6 SERIES 300	Cabin Interior Upgrade	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation must be in accordance with De Havilland Aircraft of CanadaLimited Master Data List, MDL23010-1 Revision 1,TCCA approved 17January 2025.Operation must be in accordance with De Havilland Aircraft of CanadaLimited Flight Manual Supplement, AFMS23010-1 Revision 1, TCCA approved17 January 2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The hand-held fire extinguisher must be non-Halon and a...	08/04/2025	Active	10086871
10086873	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC SA11302DS	B300C B300 B200GT B200CGT	Installation of the Pro Line Fusion embedded display system(EDS) latestversion 3.7 software upgrade and additional factory optionsRev. 1: Change of Address	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 23.23 (b) at amdt 4CS 23.573 (b) at amdt 4The requirements for environmental protection and the associatedc...	Master Data List 692-00-0001, Revision IR<(>,<)> dated 5 February 2025<(>,<)>Instructions for Continued Airworthiness 692-01-0125 (B200GT & B200CGT),Revision IR, dated 6 January 2025 or Instructions for ContinuedAirworthiness 692-02-0125 (B300 & B300C), Revision IR, dated 6 January2025<(>,<) >Airplan...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.The aircraft shall be equipped from the factory with Pro...	07/08/2025	Active	10086873
10086888	ADAC HELISERVICE GMBH			EC135 T3 EC135 P3	Introduction of the white phosphor Fenn NG800 Night Vision Goggle (NVG)into the current serial number specific approvedNight Vision ImagingSystem (NVIS) configuration for the ADAC EC135 fleet in accordance withMaster Document List EC135-12042-001-LMD	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-27 at Amendment 6for 27.771; 27.773 (a); 27.777; 27.807(b), (c); 27.1301(a), (d);27.1309(a), (b); 27.1321(a...	Rotorcraft Flight Manual Supplement EC135-12042-025-MFS Revision 1Compliance Summary EC135-12042-044-RCS Revision 1Master Document List EC135-12042-001-LMD Revision 0Maintenance Manual Supplement EC135-12042-023-MMS Revision 2or later revisions of the above listed document(s) approved/ acceptedunder...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limited to helicopters with Helionix cockpit variant.Ro...	10/04/2025	Active	10086888

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086889	ADAC HELISERVICE GMBH			MBB-BK117 D-3 MBB-BK117 D-2	Introduction of the white phosphor Fenn NG800 Night Vision Goggle (NVG)into the current serial number specific approvedNight Vision ImagingSystem (NVIS) configuration for the ADAC MBB-BK117 D-2/MBB-BK117 D-3fleet in accordance with MasterDocument List H145-12041-001-LMD	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-29 at Amendment 6for 29.771; 29.773 (a); 29.777; 29.803(a), (b); 29.1301(a), (d);29.1309(a), (b); 29.1321(a...	Rotorcraft Flight Manual Supplement H145-12041-025-MFS Revision 1Compliance Summary H145-12041-044-RCS Revision 1MasterDocument List H145-12041-001-LMD Revision 0Maintenance Manual Supplement H145-12041-023-MMS Revision 2or later revisions of the above listed document(s) approved/ acceptedunder the...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limited to helicopters with Helionix cockpit variant.Ro...	10/04/2025	Active	10086889
10086900	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS			747-8	KA-BAND SATCOM system installationKA-BAND SATCOM antenna installation with installation provisions incabin	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding(s): B-01 (Vibration/Buffeting compliancecriteria for large external antenna installation).EASA Certification Basis (Continuation):...	Master data List: 01628-EAS-A-MDL rev.B dated April 4th 2025AFM supplement: 01628-EAS-A-AFM-01 rev.C dated April 7th 2025ICA supplement: 01628-EAS-A-ICA-01 Rev.C dated April 4th 2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Installation of Live TV antenna (FAA STC ST11979CH) and...	11/04/2025	Active	10086900
10086911	ACC COLUMBIA Jet Service GmbH			208B	C208B LiDAR Mission ConfigurationInstallation of non-essential mission equipment for aerial surveymissions into the A/Ccabin and a GNSS antenna installation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 23.773, 23.853(e),23.901 (a)(b1)(b2), 23.955 (a 1-4), (b)(f1-3), 23.959 (a)(b),23.1183(a), 23.1203 (a)-(d)...	Master Data List MDOCL_23-91096 REV.3 dated 04.11.2025Aircraft Flight Manual Supplement SPOH_23-91096 REV.1 dated 26.08.2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Pre-requisites for this change are EASA STC 10015027, m...	04/11/2025	Active	10086911
10086912	ACC COLUMBIA Jet Service GmbH			208B	C208B ARES-IS Mission Configuration IICompletion of the ARES-IS Mission Configuration by adding the RIEGLVQ-1560II-S airborne mapping system and additional equipment requiredfor the LiDAR operation. Six new cabin configurations are introduced.GNSS antennas are introduced for the connection to the GN...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 23.773, 23.853(e),23.901(a)(b1)(b2), 23.955(a 1-4)(b)(f1-3), 23.959(a)(b), 23.1183(a),23.1203(a)-(d), 23....	Master Data List Doc. No. MDOCL_24-90390 Rev.0 dated 26.05.2025Aircraft Flight Manual Supplement SPOH_24-90390 Rev. 1 dated 12.05.2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This is applicable to a/c s/n 208B5183;As pre-requisite...	27/05/2025	Active	10086912
10086914	AEROTEC & CONCEPT			EC 155 B1	LPV and ADS-B OUT AVIONIC UPGRADE (EC 155 B1) AEROTEC & CONCEPTModification Reference : 19097	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: - CS-29 Amendment 4 for the following requirements : 29.1316 &29.1317 - FAR-29 Amendment 16 for th...	- Certification Program / Presentation Dossier (PCDP) : AE19097PCDP,Revision 7 dated 28 March 2025- Master Data List (MDL) : 19097, Revision 2 dated 14 April 2025Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	None	14/04/2025	Active	10086914
10086915	DOA AESGLOBAL LIMITED			A321-232 A321-231 A321-213 A321-212 A321-211	INTRODUCTION OF 220Y CABIN CONFIGURATIONThe aircraft cabin seating layout is reconfigured to provide a new 220Ydual class seating layout using Recaro 3520 sea	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:CS 25.1, 29, 301, 303, 305, 307, 365, 601, 603, 605, 609, 613, 619, 625,791, 793, 803, 807, 809. 810, 811, 812...	− AES-1067-01-MDL Master Data List, Rev.1− AES-1067-01-ICA-01 Instructions for Continued Airworthiness, Rev. 0− AES-1067-01-CCOMS-01 Cabin Crew Manual Supplement, Rev. 0Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/04/2025	Active	10086915

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086920	PT21 SOLUTIONS Ltd.	REV. 1		777-300ER	B777 Cabin – Interior reconfiguration to 7BC/514ECRemove existing 6FC/53BC/ 259YC configuration including sometoilets/galleys and converting the aircraft cabin to a 7BC/ 514YCconfiguration.Rev.1: Small typo corrections in STC holder name andprojectdescription.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List, ref. 21008/MDL/001, Issue 2 dated 07 April 2025Instructions for Continued Airworthiness, ref. 21008/ICA/001, Issue 4dated 17 March 2025Airplane Flight Manual Supplement, ref. 21008/ AFM/001, Issue 6 dated 20February 2025orlater revisions of the above listed document(s) approved/ acc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	16/04/2025	Active	10086920
10086945	DOA21 LIMITED			BD-700-1A10	Introduction of Halon Free Fire Extinguishers	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.851 (a)(1)-(8), (c) at Amdt. 27, CS 25.853 at Amdt. 12, CS 26.170 (b),(c),(d) at Amdt.4The requirement...	Master Data List Document ref. D21.MDL-0018, Issue 2, dated15 April2025<(>,<) >or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This change is applicable to a/c s/n 9535 and 9656;EASA...	16/04/2025	Active	10086945
10086957	GPMS INTERNATIONAL, INC.		FAA SR01033DE	AS 350 B2, AS 350 B3	Installation of the Green Power Monitoring Systems (GPMS) Foresight MXCondition Monitoring System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Document No. AS350-3130MDL001, Master Drawing List, Revision G, dated 8November 2024<(>,<) >Instructions for Continued Airworthiness (ICA), Document No.AS350-3130ICA001, Revision D,dated 31 October 2022<(>,<)>or later revisions of the abovelisted document(s) approved/accepted onbehalf of EASA in acc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.This system is not certified for Operational or Maintena...	11/07/2025	Active	10086957
10086958	BHE & ASSOCIATES, LTD.	REV. 1	FAA STC SA11301DS	C90GTI B300C B300 B200GT B200CGT B200C B200 525B 525A 525	The installation of an AirSync flight data monitoring systemRev. 1: Change of Address	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	For models 525, 525A, 525B:Master Data List 691-00-0001, Rev. IR, dated 06 November 2024;Airplane Flight Manual Supplement; 691-02-0028, Rev. IR, dated 17 July2024;Instructions for Continued Airworthiness, 691-02-0029, Rev. A, dated 28October 2024;For models B200, B200C, B200GT, B200CGT, B300, B300C...	The STC is valid for aircraft types and models approved by EASA andlisted on the FAA AML No. SA 113010S rev. A dated 8 January 2025. TheEASA TCDS numbers corresponding to the FAA TCDS apply.Prior to installation of this change/repair it must be determined thatthe interrelationship between this chang...	07/08/2025	Active	10086958
10086961	DUNCAN AVIATION, INC.		FAA STC ST01886WI	FALCON 7X	3-Place 16G Divan Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval. Therequirements forenvironmental protection and the associatedcertified noise and/ oremissions levels of the product are unchanged and remain applicable tothis certificate/ approval....	Master Document List, Duncan Aviation Doc. Number CERTDOC-007827,Revisio n A, dated 19 September 2018<(>,<)>Airplane Flight Manual Supplement, Duncan Aviation Doc. NumberCERTDOC-007901 , Revision A, dated 19 September 2018<(>,<) >Instructionsfor Continued Airworthiness, Duncan Aviation, Inc. Doc. No.C...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	22/04/2025	Active	10086961

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10086994	APTOZ EHF.			SEE EASA APPROVED MODEL LIST	Installation of Kidde Halotron BrX Handheld Fire Extinguishers	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-25 Amendment No.28: 25.1, 25.29(a)(b) , 25.301 (a) , 25.303, 25.305(b)(c)(e) , 25.307(a), 25.561(b) , 25...	Master Data List MDL251830 rev IRInstructions for ContinuedAirworthiness ICA251830-1 rev IROr later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/04/2025	Active	10086994
10087006	SABENA TECHNICS BGC			S-92A	Lifeseeker SR20 Installation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-MMEL at issue 2.The requirements for environmental protection and the associatedcertified noise and/ or e...	Master Data List, Doc. 2193-01-A-MDL-R00 dated 28 Apr 2025;Certification Plan, Doc. 2193-01-A-CP-R02 dated 03 Mar 2025;RFM Supplement, Doc. 2193-01-A-RFMS-F00-R01 (PART 1) dated 15 Apr 2025;RFM Supplement, Doc. 2193-01-A-RFMS-F00-R01 (PART2) dated 8 Apr 2025;MMEL Supplement, Doc. 2193-01-A-MMELS-R0...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The modification MOD 2193-02 is a pre-requisite for the...	02/05/2025	Active	10087006
10087009	ADVANCED AEROSPACE DEVELOPMENTS GMB			MBB-BK117 C-2	Installation of an external antenna array mounted to the RHskid stepand installation of LIFESEEKER equipment in the aft cabin compartment.In addition, as part of the installationa separate single antenna isinstalled in the underbelly area.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Certification Program, Document No. AAD-CP-07LSR-001 Issue 4 dated18/03/2025;Master Documents List, Document No. AAD-MDL-07LSR-001 Issue 01 dated31/03/2025;Master Drawing List, Document No. AAD-DWL-07LSR-001 Issue 01 dated21/03/2025;FlightManual Supplement, Document No. AAD-FMS-07LSR-001 Issue 02 d...	The installation of minor change 07LSM is a pre-requisite for theinstallation of this STC.Prior to installation of thischange/ repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upo...	02/05/2025	Active	10087009
10087017	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS			A350-941 A350-1041	Starlink System antenna installation on Airbus A350Large antenna installation for Starlink system connection andactivation.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): PCRI-0000251-0060092383the following paragraph(s) at a later amendment: CS25 at Amdt 13: 25.23;25.29; 25.101; 25.111; 25.113; 2...	Master Data List: ref: 02010-EAS-A-MDL-01 Rev.A dated 05 May 2025Aircraft Flight Manual supplement: 02010-EAS-A-AFM-01 Rev.A dated 30thApril 2025Instruction for Continued airworthiness supplement: 02010-EAS-A-ICA-01Rev.A dated 12th March 2025or later revisions of the above listed document(s) approve...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Aeroplane with this change installed must be operated i...	05/05/2025	Active	10087017
10087041	AVIATION ENGINEERING AS			300	Installation of L3Harris Wescam MX-15 camera and Antenna Provisions	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23 at Amdt. 2:23.1(a)(2), 23.29, 23.251, 23.301(a) to (c), 23.303, 23.305, 23.307(a),23.321(a), 23.335(b...	Aircraft Flight Manual Supplement doc. nr. 2592-01-353, Rev. 0Instructions for Continued Airworthiness doc. nr. 2592-01-354, Rev. 0Modification Procedures doc. nr. 2592-01-356 (Service Instructions),Rev. 0Master Minimum Equipment List Supplement doc. nr. 2592-01-357, Rev. 0or later revisions of theu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Only applicable to Textron King Air Model B300 s/n FL-7...	06/05/2025	Active	10087041

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087044	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			SEE EASA APPROVED MODEL LIST	Replacement of the Halon Type 1211 portable fire extinguisher withHalotron BrX portable fire extinguisher	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Refer to the EASA Approved Model List dated 06/05/2025<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/05/2025	Active	10087044
10087052	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			SEE EASA APPROVED MODEL LIST	Replacement of the Halon Type 1211 portable fire extinguisher withHalotron BrX portable fire extinguisher	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Refer to the EASA Approved Model List dated 07/05/2025<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/05/2025	Active	10087052
10087060	AEROTEC & CONCEPT			A319-153N	Gogo Galileo System Provisions InstallationThis modifications covers the mechanical installation of a SATCOMantenna with associated provisions (interface plate, fairings, doubler,reinforcements).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): PCRI-0000492-0060093654Vibration-Buffeting for Large External Antenna Issue 3the following paragraph(s) at a later amendment: CS...	The change is defined with Revision 0 of Aerotec & Concept Master DataList AE25008MDL.The aircraft shall be operated inaccordance with Revision 0 of Aerotec& Concept Aircraft Flight Manual Supplement AE25008AFMSMaintenance shall be accomplished in accordance with Revision 0 ofAerotec & Concept Inst...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/05/2025	Active	10087060
10087061	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A321-272N/-272NX A321-271N/-271NX A321-253N/-253NX/-253NY A321-252N/-252NX A321-251N/-251NX A321-231/-232 A321-211/-212/-213 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-171N/-173N A319-151N/-153N A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318-111/-112/-121/-122	INTERGRATION OF UNDERBIN CLOSETSInstallation of new L/H and/or R/H Underbin Closet in AFT cabin area,including associated reconfiguration of the passenger cabin post seatremoval.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 Amdt 17: 25.305(b); 25.321 (a) (b) (c); 25.365 (e); 25.803 (a); 25.807 (c); 25.1541;25.1557 (a) – CS25 A...	Master Document List: JCAERO_MDL_1450 issue 1.0 dated May 7th 2025AMM supplement: JCAERO/AMM/1450 issue 1.0 dated May 7th 2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Aeroplane with this change installed must be maintained...	08/05/2025	Active	10087061
10087090	AIRHAWKE AEROSPATIAL Inc.		TCCA Q-LSA24-015/D	A320-214	Addition of one row of PAX RECARO 3530BL seats and PSUs to existing 174PAX RECARO 3530BL LOPA, re-pitching existing seats and PSUs as needed	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	- Can-Am Aerospace Master Drawing List 25-24-07-003, Revision NC, DatedApril 26, 2024.- Can-Am Aerospace Instructions for Continued Airworthiness25-24-07-004, Revision NC, Dated April 26, 2024Or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This certificate covers installation limited to Aircraf...	13/05/2025	Active	10087090

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087117	AIRCRAFT SYSTEMS AND MANUFACTURING,Inc.		FAA STC ST09656SC	CL-600-2B19 (RJ SERIES 100)	Installation of a Teledyne Telelink Data Link System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	ASM Top Drawing List 5549-0001-00. Revision H<(>,<)> dated 15 September2000;FAA approved Airplane Flight Manual Supplement Revision A, dated 31October, 2000;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures. ..	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	15/05/2025	Active	10087117
10087119	APTOZ EHF.			737-8	Galley G7 Unit ReplacementThis modification replaces an existing Galley G7 unit with a new G7 fullheight unit.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.1, CS 25.29 (b),CS 25.301 (a), CS 25.302, CS 25.303, CS 25.305, CS 25.341 (a)(1), CS25.465 (g), CS 25.4...	The change is defined with revision IR of Aptoz Master DataListDocument MDL251605Maintenance shall be accomplished in accordance with revision A of AptozInstructions for Continuous Airworthiness Document ICA251605-1Aor later revisions of the above listed document(s) approved/acceptedunder the EASA...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/05/2025	Active	10087119
10087126	ALPINE AEROTECH LP		TCCA SH21-26	412EP 412 212	Center Pedestal Riser / The Center Pedestal Riser increasesthe heightof the pedestal at the aft end while the height at the forward end isunchanged.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	-Alpine Aerotech Lp Master Data List AAL-280-094-001 Rev. Edated2023-12-01.-Infinion Master Data List MDL-2104-01 Issue 1 dated 9 April 2021.-Installation Instruction AAL-280-095-701, Revision NI dated March 5,2021.-Instructions for Continued Airworthiness AAL-214-035-701 Rev. B dated2023-12-01.Orb...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/05/2025	Active	10087126
10087133	WIPAIRE Inc.		FAA STC SA04646CH	208, 208B	Installation of Hartzell Model HC-E4N-3KTV()/GC11114()-2 propeller	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Wipaire, Inc. Drawing No. 1012329, Revision A, dated November 15, 2023;Instructions for Continued Airworthiness are contained in WipaireDocument No. 1012499, Revision A, dated 15 January, 2024;FAA Approved Airplane Flight Manual Supplements (AFMS):POHSA04646CH-A-2 A, 15 May 2024, 208 PT6A-114A Float...	Aircraft equipped with amphibian/seaplane floats require Wipline®8000/8750 floats installed by EASA STC 10041960.Installation limited to aircraft with 1) Pratt & Whitney Canada Corp.Model PT6A-114A installed via separate approval or as original equipmentOR 2) Pratt & Whitney Canada Corp. Model PT6A-...	19/05/2025	Active	10087133
10087136	AERODISA S.L.			A321-211/-212/-213/-231/-232 A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-131/-132/-133 A319-111/-112/-113/-114/-115	Installation of halon free Fire Extinguishers.Replacement of hand-held fire extinguishers with halon free fireextinguishers P/N P3APP003010D	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25.851(a) at CS 25amdt. 12The requirements for environmental protection and the associatedcertified noisea...	AED2025-09M_MDL Master Data List Rev A0Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.AERODISA Minor Change AED2025-10m is a pre-requisite fo...	20/05/2025	Active	10087136

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087137	AMPHENOL CABLE AND INTERCONNECTT ECHNOLOGIES, Inc.		FAA STC ST11979CH	747-8	Installation of Tailwind 550 SATCOM System provisions on Boeing 747-8(FAA STC ST11979CH)	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): ESF 25.251(b) on Vibration and Buffetingby adoption of FAA ELOS Memo ST10746CH-T-F-1 dated 30-NOV-2022The requirements for envir...	- Master Data List, 900-108680, Rev F, dated March 12, 2025, FAAapproved March 25, 2025- Airplane Flight Manual Supplement (AFMS), 900-111199, Revision NC, FAAapproved March 21, 2025- Instructions for Continued Airworthiness, Section 4, AirworthinessLimitations, 900-108687, Revision E, dated March 7...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/05/2025	Active	10087137
10087159	PMV ENGINEERING			ATR 72-212, ATR 72-212 A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Halon-free extinguishers installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25 change 15:25.305 (a)(b), 25.307 (a), 25.561 (a)(b)(c), 25.601, 25.603 (a)(b), 25.613 (a)(b), 25.789,2...	ATR 72 Master Document List CAB-04790-MDL-S01 Rev00ATR 42 Master Document List CAB-04790-MDL-S02 Rev00Instructions for continued aiworthiness CAB-04790-ICA Rev01Cabin Crew Data Supplement CAB-04790-CCDS Rev01or later revisions of the abovelisted document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Prerequisite installation: ATR MOD 06355 (Service bul...	21/05/2025	Active	10087159
10087160	SABENA TECHNICS BGC			ATR 72-212, ATR 72-212 A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Halon-Free Fire Extinguisher installation according to configurationsF01, F02 and F03.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25 change13:25.1(a), 25.29(a)(b), 25.301, 25.303, 25.305(a)(b), 25.307(a),25.321(a), 25.471(a), 25.561(...	Master Data List 41423-01-A-MDL Rev 00Instructions for Continued Airworthiness 41423-01-A-ICA Rev 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/05/2025	Active	10087160
10087161	SKYTEC AEROSPACE GmbH			A330-243	Business Class Seat ReplacementThis modification replaces the installed Business Class Seats withassociated modification in the cabin.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.29, 25.305,25.307, 25.321, 25.341 and 25.851 at Change 14, OSD-CCD in Issue 2.The requirements for e...	The change is defined with revision B of Skytec Master Document ListDocument MDL-A330C102-0004Maintenance shall be accomplished in accordance with revision A ofSkytec Instructionsfor Continuous Airworthiness DocumentICAS-A330C102-0004The OSD-Cabin Crew Data (CCD) is contained by the documents: - Sk...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/05/2025	Active	10087161
10087163	DOA AESGLOBAL LIMITED			A330-343 A330-342 A330-341 A330-323 A330-322 A330-321 A330-303 A330-302 A330-301	INTRODUCTION OF AN ALL ECONOMY CABIN CONFIGURATION, A330-300The aircraft cabin seating layout is reconfigured to introduce a 352all-economy class passenger seating configuration comprised of Zodiac3530 series YC seats.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:CS 25.1, 29, 301, 303, 305, 307, 321, 337, 365, 561, 601, 603, 605, 609,613, 619, 625, 789, 791, 793, 803, 807...	− AES-0982-01-MDL Master Data List, Rev.3− AES-0982-01-ICA-01 Instructions for Continued Airworthiness, Rev. 0− AES-0982-01-CCOMS-01 Cabin Crew Manual Supplement, Rev. 0Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This modification must be installed in conjunction with...	21/05/2025	Active	10087163

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087167	AIRCRAFT COMPLETION ENGINEERING			A319-112	60 Passenger Cabin LayoutThis modification introduces 30 Business Class Seats generating a 60Passenger Seating Configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.807 and 25.853(a)(b) at Change 13.The requirements for environmental protection and the associatedce...	The Change is defined with Revision 2 of Aircraft Completion EngineeringMaster Document List document MDL ACE2210-001.The aircraft shall be operated in accordance with Revision 7 of AircraftCompletion Engineering Airplane Flight Manual Supplement documentACE2210_Flight Manual SupplementMaintenances...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/05/2025	Active	10087167
10087170	GROB AIRCRAFT SE			250-B17F, 250-B17F/1 250-B17F/2	Torque LimiterInstallation of a hydro-mechanical torque limiter on the RR 250-B17Fturbine in order to prevent turbine over torque.For more detail, refer to the Certification Programme CP-M250-000001-R3.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: FAR 33.64 Amdt. 27;FAR 33.75 Amdt. 24; FAR 33.91 Amdt.27The requirements for environmental protection and t...	Declaration of compliance of GROB AIRCRAFT SE related to EASA projectNo. 0060093819 – Ref “DoC_OCN M250-001” dated 21stof May 2025< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/07/2025	Active	10087170
10087171	AVIATION SPECIALTIES UNLIMITED, INC		FAA SR02547SE	S-92A	NVG Supplemental Lighting and Filtration System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Drawing List (MDL), MDL-S92A004-3, Revision E, dated06 May 2025;Instructions for Continued Airworthiness, ICA-S92A004-4, Revision IR,dated 09 May 2017;RFM Supplement, EASA-FMS-S92A004-6, Revision IR, dated 28 Feb 2025;or later revisions of the above listed document(s) approved/ accepted onbeh...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.1. This supplemental type certificate applies to the mo...	22/05/2025	Active	10087171
10087172	AMAC AEROSPACE SWITZERLAND AG			A330-841/-941 A330-743L A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-223F/-243/-243F A330-201/-202/-203	WLAN ActivationActivation of a Wireless Local Area Network (WLAN) concurrently to aphysical installation of a WLAN System	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25.1, CS 25.869, CS25.1301, CS 25.1309, CS 25.1351, CS 25.1353, CS 25.1360, CS 25.1431, CS25.1501, CS 25.1...	Configuration 1:The Change is defined with Revision B of Master Data List documentMDL-A3301-1-4430.The aircraft shall be operated in accordance with Revision A of AirplaneFlight Manual Supplement document AFMS-A3301-1-4430.Maintenance shall be done in accordance with Revision B of Instructionsfor Co...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.-WLAN System Configuration 1 allows the activation of t...	26/05/2025	Active	10087172
10087175	VIPE 21 AS			S-92A	Installation of heavy-duty seat rails allowing for two sliding seatconfigurations in otherwise empty cabin layout.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Documents List, Document No. V21.D00086.MDL1 Issue 1.0 dated23.05.2025;Certification Programme, Document No. V21.D00086.CPR1 Issue 2.0 dated23.05.2025;RFM Supplement, Document No. V21.D00086.FMS1 Issue 1.0 dated 21.05.2025;Instructions for Continued Airworthiness, Document No. V21.D00086.ICA1...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/05/2025	Active	10087175

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087187	PMV ENGINEERING			ERJ 190-100 STD ERJ 190-100 LR, ERJ 190-100 SR ERJ 190-100 IGW ERJ 190-100 ECJ	Starlink Satcom antenna installation and system activation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding: PCRI-0000492-0060091938 issue 4 “Vibrationbuffeting compliance criteria for large external antenna installation”.- The following2...	Master Document List: SCA-01900-MDL-S01 Rev01 dated 22 May 2025AFM Supplement SCA-01900-AFMS Rev 01 dated 21 May 2025Instructions for Continued Airworthiness SCA-01900-ICA Rev 01 dated 26Mar 2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.As per documents SCA-01900-ICA and SCA-01900-AFMS.	26/05/2025	Active	10087187
10087191	PEREGRINE LLC		FAA STC SA02019WI	SEE FAA AML	Installation of the Trig Avionics TX56, TX56A, TX57, or TX57A VHFNav-Com Radio	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Installation Instructions, Document Number E-TA-22-0014, Rev IR, dated15 June 2023<(>,<) >Airplane Flight Manual Supplement (AFMS), Document Number E-TA-22-0009,Rev IR, dated 25 July 2023<(>,<) >Instructions for Continued Airworthiness (ICA), Document NumberE-TA-22-00088, dated 12 June 2023<(>,<)>or l...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.This STC replaces an existing VHF Radio. A VHF COM anten...	26/05/2025	Active	10087191
10087192	AIRBUS HELICOPTERS, Inc.		FAA STC SR11353DS	AS 350 B3	Installation of electrical provisions to integrate pre ECP 07.20207 AHISTC options on post ECP 07.20207 helicopters	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Drawing List H250U 0269 500 Rev. B dated 8 April 2025;Instructions for Continued Airworthiness H250U 0269 680 Rev. A dated 16April 2025;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/USA Bil...	This STC is applicable to post ECP 07.20207 AS350B3 helicopters only.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of...	26/05/2025	Active	10087192
10087217	AMAC AEROSPACE SWITZERLAND AG			747-8	Installation of Large MonitorThe change covers the replacement of an artwork installed in a privatelounge area with a new 55” large monitor.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.365 (a)-(d),(e)(2)-(g) at Amendment 12, CS 25.788 at Amendment 27.The requirements for environmentalc...	- The change is defined with Revision B of AMAC Master DataListdocument MDL-IO10-4420- The installation must be accomplished in accordance with Revision A ofAMAC Engineering Order document EO-IO10-4420Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	28/05/2025	Active	10087217
10087219	NOVA SYSTEMS & ENGINEERING LIMITED			737-800	Boeing 737-800 – 189Y LOPA ChangeThis project reconfigures the current 2 class LOPA into a new 189 alleconomy layout using Acro Series 6 seats (P/N 1315-6G0X-3-XXX).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	NSI-201387-01-MDL-01 Master Data List Issue 1NSI-201387-01-ICA-01 Instructions for Continued Airworthiness Issue 2Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This modification must be installed together with Lufth...	30/05/2025	Active	10087219

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087225	GULFSTREAM AEROSPACE CORPORATION		FAA ST04570AT	GVIII-G700 GVII-G500, GVII-G600	Installation of SpaceX Starlink Aviation System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	GVIII-G700 ICA: GCD000036973, Rev A, dated 2/18/2025GVII-G600 ICA: GCD000036978, Rev (-), dated 2/21/2025GVIII-G700 EWIS ICA: GCD000036975, Rev (-), dated 2/11/2025GVII-G600 EWIS ICA: GCD000036979, Rev (-), dated 3/01/2025FAA Approved GVIII-G700 AFMS: GC800000011, Rev Basic Issue, dated2/18/2025FAA3...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The Guidance for Follow-on Installation for each airpla...	02/06/2025	Active	10087225
10087237	COMPANIA ESPANOLA DE TECNICAAERONAUTICA, S.A.			1900D	Installation of Garmin Dual GTX 3000 Transponders to enableADS-B Outcapability	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	D2404-0001 Master Documents and Drawing List Ed 04 dated 02/06/2025D2404-0016 Aircraft Maintenance Manual Supplement Ed01 dated 13/12/2024D2404-0017 Aircraft Manual Supplement for S/N UE-350 and UE-338 Ed 01dated 05/12/2024D2404-0020 Aircraft Manual Supplement for S/N UE-374 Ed 01 dated05/12/2024or...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Only applicable to Textron Beechcraft B1900D aircraft S...	03/06/2025	Active	10087237
10087238	AIRCRAFT INTERIOR REFURBISHMENT ESPANA S.L.			A321-251NX	Passenger seats rearrangement and In-Seat Power Supply (ISPS)integration-Initial Issue: 232PAX, Y/C configuration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:- JAR 25 chg. 12: 25.853(c).- CS25 Init. issue: 25.562(c5)(c6).- CS25 Amdt. 2: 25.21.- CS25 Amdt. 11: 25.27,...	Aircraft Fight Manual Supplement, Ref. A320C162-AFM001 Issue 3 dated 23May 2025.Instructions for continued airworthiness, Ref. A320C162-MMS001 Issue 1dated 23 May 2023.Master datalist, Ref. A320C162-MDL001 Issue 3 dated 23 May 2025or later revisions of the above listed document(s) approved/ accepted...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/06/2025	Active	10087238
10087248	STIRLING DYNAMICS GMBH			737-800	Replacement of all existing Zodiac seats with B/E Aerospaceseats.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Document List 423160-C-DL-2520-001-04 Issue 04or later revisions of the above listed document(s) approved/ acceptedunderthe EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	04/06/2025	Active	10087248
10087253	SKYTRAC SYSTEMS Ltd.		TCCA SH20-1 ISSUE 1	S-92A	SkyTrac ISAT Data Communicator Installation.The ISAT-200A is an aircraft tracking system that transmits aircraftposition/status to a ground base station via the Iridium satellitenetwork.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installation per Master Drawing List, Document No. MDL18053Revision E;Flight Manual Supplement, Document No. FMS18053-1 Revision B;Instructions for Continued Airworthiness, Document No. ICA18053-1Revision Eor later revisions of the above listed document(s) approved/accepted onbehalf of EASA in acco...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/06/2025	Active	10087253

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087330	SPAES GmbH & Co. KG			EC 155 B1 EC 155 B	Installation of additional handle for life raft [Project N°: 0749]	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: . CS-26 at Issue 5 . CS-29.1555(d)(2) and CS-29.1561(a),(c) at Amendment 5.The requirements for env...	- Certification Program : CFP-155-749-25-01 Revision 1 dated 28/02/2025.- Declaration of Compliance : DOC-155-749-25-01Revisi on 1 dated05/06/2025Or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	None	12/06/2025	Active	10087330
10087343	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST04571AT	GV-SP GIV-X	Installation of Halotron BrX and water fire extinguishers	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Gulfstream Aerospace Corporation Index List GDL100000088 Rev A, dated 21March 2025<(>,<) >Instructions for Continued Airworthiness GCD000035942 Rev NC, dated 9December 2024, for the following configurations:- GDL300007776- GDL300007777- GDL300008421- GDL300008422- GDL300008423- GDL300008424- GDL30000...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.With the execution of this STC, all existing handheld Ha...	16/06/2025	Active	10087343
10087345	SCHULZ, ALEXANDER			SEE EASA APPROVED MODEL LIST	Installation of electronic flight instruments to sailplanesand poweredsailplanes	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Installation of electronic flight instruments i.a.w. Alexander Schulzdocument 311956-001, at issue C< (>,<)>dated April 7, 2025;- Operation and ICA i.a.w. Aircraft Flight ManualSupplement, AlexanderSchulz document Electronic Airspeed indicator + Altimeter LXIRISAll-In-One, dated February 10, 202...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/06/2025	Active	10087345
10087356	LUFTHANSA TECHNIK AG			A330-243	Activation of a WiFi Cabin Data CommSys	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Supplemental Type Design Definition STDD44-24/04M Issue 1 Rev 0Airplane Flight Manual Supplement A-00-25/08-AFM Issue 2Rev 0Instructions for Continued Airworthiness A-00-25/08-ICA Issue 2 Rev 0Flight Crew Data Supplement A-00-25/08-FCD Issue 1 Rev 0Cabin Crew Data Supplement A-00-25/08-CCD Issue 1o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Structural and non-operational electrical provisions fo...	17/06/2025	Active	10087356
10087364	ZLIN-AVION SERVICE S.R.O			Z 526 M Z 526 L, Z 526 M, Z 726 Z 526 L Z 526 F Z 526 Z 326, Z 326 M, Z 526, Z 526 F Z 326 M Z 326 Z 226 T Z 226 M, Z 226 MS Z 226 MS Z 226 M Z 226 B Z 126 T, Z 226 B, Z 226 T Z 126	New alternative powerplant installation.STC is the approvalof new models based on existing individualmodifications (Z 226 SL and Z 526 ML) and reflecting the operatinglimitationsof the current Z 26 series. The purpose of this STC is toprovide alternative powerplant installation with no appreciable...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): CRI_N-01_0010054708.This certificate/approval involves a change with an impact on the noisedatabase and/or emission levels. The envir...	S-01-226.526 Certifikační program Rev. V 31.01.2025S-226.L235 Technické specifikace Z 226/Z526 L series Rev. D 31.01.2025S-226.L260 Technické specifikace Z 226/Z526 L series Rev. C 31.01.2025S-526.L235 Technické specifikace Z 226/Z526 L series Rev. C 31.01.2025S-526.L260 Technické specifikace Z 226/...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/06/2025	Active	10087364

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087366	EXTEX ENGINEERED PRODUCTS INC		FAA PMA NO. PQ2203M, SUPPL. 54	206L-3, 206L-4 206A, 206B, 206L, 206L-1	Validation of EXTEX PMA for Strap Assy P/N 2E6-310-004-101 and P/ N2E6-310-004-103.Strap Assembly P/N 2E6-310-004-101 isa replacement for the OEM P/N206-310-004-101 on Bell Helicopter Models 206A and 206B; Strap AssemblyP/N 2E6-310-004-103is a replacement for theOEM P/N 206-310-004-103 on Bell Heli...	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Part Specific Certification Plan, Document No. 310004-PSCP Rev. A datedOct 15, 2018;Instructions For Continued Airworthiness, Document No. T-712-EASA Rev.IR dated May 14, 2025or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical Implem...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	18/06/2025	Active	10087366
10087416	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			A319-112, A319-132	144 Economy Class Cabin ConfigurationThis modification introduces a 144 full economy seating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.601, 25.831,25.863, 25.869, 25.899, 25.1301, 25.1309, 25.1351, 25.1353, 25.1357,25.1360, 25.1431, 25....	The change is defined with Revision 0 of AMES Engineering Order documentEO_M469001007_RSP_01082024.The aircraft shall be operated in accordance with Revision 0 of AMESAircraft Flight Manual Supplement document AFMS_M469001007_DBE_20032025The aircraft shall be maintained in accordance with Revision 4...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/06/2025	Active	10087416
10087424	PROTOPLANE SPECIAL MISSION AIRCRAFT			P.68 "OBSERVER 2"	Title: “Lidar installation on the P68 OBS2 s/n 427”Description: The purpose of this STC is to replace the system (Ultracamcamera + Somag GSM3000) by the system (Riegl VQ1460 Lidar+ SomagGSM4000).	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval withou...	PP-183-AFM-01 (Aircraft Flight Manual)PP-183-IM-04 (Installation Manual) PP-183-ICA-00 (Instructions for Continued Airworthiness)Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	a) STC applicable to P.68 Observer 2 s/n 427b) Minor changeCNG-016-20 “Installation of Camera system on P.68”approved under the authority of DOA EASA.21J.529 is a prerequisite forthe installation of this STC.Prior to installation of this change/repair it must be determined thatthe interrelationship...	27/05/2025	Active	10087424
10087455	SABENA TECHNICS BGC			A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216	Installation of JetWave Ka-Band connectivity and Rave WLAN on A320models	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 Amd. 4 for 25.1, 25.23, 25.29, 25.121, 25.301, 25.321, 25.337,25.341, 25.561, 25.581, 25.611, 25.629, 25...	Master Data List - 10095-01-A-MDL-R00 Initial release dated27 June 2025Aircraft Flight Manual Supplement - 10095-01-A-AFMS-R00 dated 03 March2025OSD Change Document (Flight Crew Data and Cabin Crew Data supplement) -10095-01-A-OSDCD-R00 Initial Release dated 28.03.2025Instructions for Continued Air...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/07/2025	Active	10087455
10087457	MEDITERRANEAN AVIATION COMPANY Ltd. (MEDAVIA)			FALCON 10	Clearance for RVSM operations on Falcon 10 equipped with EASA STC No.EASA.IM.A.S.01713	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- CS-ACNS at issue 4- CS-MMEL initialissue.The requirements for environmental protection and theassociatedcertified noise and/ or emissions levels of the pr...	CP and Mod Description doc. no. MODE00462_CP rev. 2AirplaneFlight Manual Supplement doc. no. MODE00462_AFMS1_HMJ rev. 1MMEL Supplement doc. No. MODE00462_MMELS1_HMJ rev. 3or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limited to aircraft MSN 225	01/07/2025	Active	10087457

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087459	LUFTHANSA TECHNIK AG			A319-153N	ACJ319Neo - Cabin CompletionInstallation of a VIP cabin interior into an Airbus ACJ319Neo	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.561, CS25.571, CS25.603 (for large glass panels), CS 25.788 (a)(b), 25.812 and CS 25.1365(b) at amdt 19...	Supplemental Type Design Document STDD00-23/09M Issue 1 Revision 0Airplane Flight Manual Supplement A-00-24/43-AFM Issue 2 Revision 0Cabin Crew Data Supplement A-00-24/43-CCD Issue 3 Revision 0Flight Crew Data Supplement A-00-24/43-FCD Issue 2 Revision 0Master Minimum Equipment List Supplement A-00-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The aircraft is limited to non commercial operations o...	29/10/2025	Active	10087459
10087460	UMLAUT ENGINEERING GMBH			A319-153N	Pressure Reservoir RelocationThis modification relocates the overwing exit slide pressure reservoirbottles (LH/RH).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.29 (a)(b), 25.301 (a)-(c), 25.303, 25.305(a)(b), 25.307 (a), 25.321 (a), 25.341 (a), 25.561 (a)-(c), 2...	The change is defined with Issue A of Umlaut Engineering GmbH MasterDocument List documentUM-ACG01-MDL-0001.The aircraft shall be maintained in accordance with Issue A of UmlautEngineering GmbH Instructions for Continuous Airworthiness documentUM-ACG01-ICA-0001Or later revisions of the above listedu...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The installation of EASA STC 10087459 is required to be...	22/07/2025	Active	10087460
10087481	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC ST12041LA	A350-941	Installation of Aerocon Engineering Company (AEC) On-Board Airstairs	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	FAA Approved AEC Master Drawing List (MDL) ASA350-8900, Revision A,dated 20 February 2025;Instructions for Continued Airworthiness (ICA), Aerocon EngineeringCompany Maintenance Manual Supplement Document No. MMS-ASA350-2159,Revision NC, dated 25 July 2022;or later revisions of the above listed docum...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	02/07/2025	Active	10087481
10087485	LEE AEROSPACE, INC.		FAA STC SA04188NY	PA-46R-350T PA-46-701TP PA-46-600TP PA-46-500TP PA-46-350P PA-46-310P	Installation of LAI CoolView Windshields and Windows	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:14 CFR 23.301 (a)(b) Amdt 23-4814 CFR 23.611 Amdt 23-4814 CFR 23.775(a)(b)(d)(e) Amdt 23-4914 CFR 23.867 Amdt 2...	Master Data List P46T-MDL-0067, Rev IR, dated 18 December 2019;Instructions for Continued Airworthiness (ICA) P46T-ICA-0067, Rev IR,dated 17 December 2019;or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures o...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	03/07/2025	Active	10087485
10087487	ALAMO ENGINEERING GmbH			680 (SOVEREIGN) 680A (LATITUDE)	Installation of Gogo Galileo including HDX Antenna.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): ESF-B25.251-01the following paragraph(s) at a later amendment: CS 26.302 amdt 4; CS26.303 Amdt 4; CS 25.177amdt 28; CS 25.251 Am...	Instructions for continuous airworthiness Ref ICA24A39AE-01rev A dated1/7/2025Master Document List Ref MDL24A39AE-01 Rev A 2/7/2025or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	03/07/2025	Active	10087487

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087488	LUFTHANSA TECHNIK AG			A350-941	A350 Transition Row IntegrationReplacement of row 19 economy class seats with seats equipped withairbag seat belts.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25.562, 25.791 and25.853 amdt 28The requirements for environmental protection and the associatedcertifieda...	Supplemental Type Design Definition STDD25-24/02M Issue 0 Rev 0Instructions for Continued Airworthiness A-00-25/06-ICA Issue 1 Rev 0or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.ZIM SB 503113-SB-002 re. 0A, or later revision approved...	03/07/2025	Active	10087488
10087519	ALAMO ENGINEERING GmbH	REV. 1		BD-100-1A10	Installation of Gogo Galileo HDX AntennaInstallation of theHDX antenna on top of fuselage aft section.Rev. 1 correct the MDL reference.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Equivalent Safety Finding PCRI-0000492 -0060091956:Vibration/buffeting compliance criteria for large external antennainstallation Issue 4.- The following pa...	Master Document List MDL24A43AE-01 with Rev. A dated 07.07.2025Instructions for Continued Airworthiness ICA24A43AE-01 with Rev. A dated09.06.2025Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/08/2025	Active	10087519
10087533	MT-PROPELLER ENTWICKLUNG GmbH			404	Installation of MTV-16-1-E-C-F/CF225-37 ( ) Propeller on Textron AviationInc. Model 404.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS-36 Amdt 6, 14 CFRPart 36 Amdt 36-32.This certificate/approval involves a change with an impact on the no...	According to MT-Propeller Master Documentation List No. E-4140 Rev. 0To be operated in accordance with MT-Propeller AFM-S Document No. E-4142Rev. 0To be installed i.a.w. MT-Propeller Installation Instructions Doc. No.E-4143 Rev. 0To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4144 Rev. 0or late...	According to limitation section of AFM-S.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	08/07/2025	Active	10087533
10087534	2 EXCEL DESIGN LIMITED		UK.STC.00345 REV 0	B200T B200CGT, B200CT, B200GT A200C, A200CT, B200, B200C 200, 200C, 200CT, 200T, A200	Installation and Removal of Antennas on King Air 200Removaland installation of various antennas for aircraft to operate ina search and rescue role. The change is fully described in CertificationProgramme 2XL236 LEF31.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: 14 CFR Part 23 Amdt 1through 57: 23.1, 23.3(d), 23.21, 23.23, 23.25(a), 23.45, 23.49(a)(b),23.51(c), 23.53(...	2Excel Aviation, Master Data List 2XL236 LEF78 Issue 3, dated 15 October2024.2Excel Aviation, Instructions for Continued Airworthiness 2XL236 LEF73Issue 4, dated 10 October 2024orlater revisions of the above listed document(s) accepted byEASA inaccordance with the Technical Implementation Procedur...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This approval is limited to aircraft serial numbers BB-...	08/07/2025	Active	10087534
10087538	JAMCO AMERICA, INC.		FAA STC ST02729SE	737-800	Installation of one (1) LH and one (1) RH hanging type softclassdivider	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 amdt. 0: 25.561, 25.853, 25.1583The requirements for environmental protection and the associatedcertifie...	Jamco America, Inc. Master Drawing List (MDL) MDL2938-1, Revision A,dated 29 June 2022;or later revisions of the above listed document(s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.EASA STC 10080984 must be installed concurrently with th...	09/07/2025	Active	10087538

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087539	LUFTHANSA TECHNIK AG			777-300ER	Sleeping area installationInstallation of 2 single beds with privacy curtains on the aisle side,replacing 8 business class seats	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	-Supplemental Type Definition Document, Doc Nr.: STDD25-25/02 Issue 01Rev 00 dd. 04-July-2025-Instructions for Continued Airworthiness, Doc. Nr.: A-00-25/30-ICAIssue 01 Rev 01 dd. 13-June-2025-Airplane Flight Manual Supplement, Doc. Nr.: A-00-25/30-AFM Issue 01Rev 00 dd. 22-May-2025-Cabin Crew Data...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Installation of this STC on an aircraft under EASA ju...	09/07/2025	Active	10087539
10087540	AERO DESIGN SERVICES Inc.		FAA STC ST04209AT	A320-273N A320-272N A320-271N A320-253N A320-252N A320-251N A320-233 A320-232 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211	Installation of a passenger interior configuration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 initial issue: 25.1415(a)(b)(c)(d)CS 25 amdt.1: 25.305(a)(b)CS 25 amdt. 4: 25.1439CS 25 amdt. 5: 25.1729...	Master Drawing List AA15-2936, Revision P dated May 23, 2025;Instructions for Continued Airworthiness (ICA): Aero Design Services,Inc document IC-0241-01, Rev. D, dated April 22, 2025;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Techn...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.Passenger interior configurations of 180 passengers or m...	24/09/2025	Active	10087540
10087546	DOA21 LIMITED	REV. 1		A321-272N/-272NX A321-271N/-271NX A321-251NX/-252NX/-253NX A321-251N/-252N/-253N A321-211/-212/-213/-231/-232 A321-111/-112/-131 A320-271N/-272N/-273N A320-251N/-252N/-253N A320-231/-232/-233 A320-211/-212/-214/-215/-216 A319-171N/-173N A319-151N/-153N A319-131/-132/-133 A319-111/-112/-113/-114/-115	Introduction of AFIRS Edge+ Wireless Quick Access Recorder (WQAR).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List D21.MDL-0025 Issue 1Maintenance Manual/AWL Supplement D21.AMMS-0021 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASAsystem.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.FLYHT AFIRS Edge+ P/N 507-1002-21 with Mod Level 4 must...	11/07/2025	Active	10087546
10087555	Q.C.M. DESIGN GmbH			CL-600-2B16 (604 VARIANT)	Installation of Halon-free Fire Extinguisher	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	CP-B604-QCM26-002 rev 1 dated 16 June 2025or later revisions of the above listed document(s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/07/2025	Active	10087555
10087557	BERINGER AERO			V35A, V35B F33A, F33C, G33, G36 36, A36, A36TC, B36TC, F33	Replacement of Main Wheels, Nose wheel, brake assembly, master cylinderand brake lines.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Associated Documentation as listed in MDL-STC-025 Rev 01<(>,<)>or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/07/2025	Active	10087557

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087571	ALAMO ENGINEERING GmbH			757-200	Iridium Certus Satellite System InstallationInstallation ofCollins Aerospace IRT4400 NX Iridium Certus for cabinuse only. Consists of High Gain Antenna, Satcom Data Unit. Interface toexisting WLAN system. No change to A/C PED Tolerance approval requiredas no new WiFi capabilities introduced.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment:CS-25, Amdt. 28 for CS 25.899, 25.1319, 25.1360Other: Part 26 compliance information:CS-26, Issue 4 for CS 26....	- Master Document List: MDL25A09AE-01 Rev. A- Aircraft Flight Manual Supplement: FMS25A09AE-01, Rev. A- Instructions for Continued Airworthiness: ICA25A09AE-01, Rev. AOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Installation of equipment shelf in equipment rack in FW...	11/07/2025	Active	10087571
10087579	UUDS AERO CONCEPT			737-8	KA-Band and Cabin WLAN Activation.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Master Data List (MDL), Ref. UAC24C009-MDL01 Revision 01 dated 11 July2025.Airplane Flight Manual Supplement (AFMS), Ref. UAC24C009-AFMS01 Revision00 datedInstructions for Continued Airworthiness (ICA), Ref. UAC24C009-ICA01Revision 03 dated 10 July 2025.Master Minimum List Equipment Supplement (MMEL...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The pre-modification configuration requires the install...	14/07/2025	Active	10087579
10087588	AERODATA AG			B200GT B200	Installation of antennas as provision for an optional installation ofthe ARTEMIS Mobile Phone Detection and Locator System (MPDLS).	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List Aircraft, MDL-A/C-982, Provision for ARTEMISInstallation, Rev 2Service Bulletin, SB-B200-ARTEMIS-PROVISION-2285, Provision for ARTEMIS,Rev 2Airplane Flight Manual Supplement, AFM-163, Rev. 5 and AFMTR-163-2, Rev.0Airplane Flight Manual Supplement, AFM-116, Rev. 8 and AFMTR-116-5...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Only applicable to aircraft B200GT S/N BY-249 and B200S...	19/08/2025	Active	10087588
10087596	GULFSTREAM AEROSPACE CORPORATION		FAA ST04543AT	GV-SP GV GIV-X GIV	Honeywell RT-300 Radio Altimeter Bandpass Filter Installation (FAA AD2023-10-02 Terminating Action)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Gulfstream Aerospace Corporation Index List GDL100000078, Revision (-),dated December 11, 2024.Instructions for Continued Airworthiness, CE41149A002, Revision A, datedNovember 15,2024, for G-IV model.Instructions for Continued Airworthiness, CE51149A002, Revision A, datedNovember 15, 2024, for GV m...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/07/2025	Active	10087596
10087597	GULFSTREAM AEROSPACE CORPORATION		FAA ST04542AT	GV-SP GIV-X	Honeywell KRA-405B Radio Altimeter Bandpass Filter Installation (FAA AD2023-10-02 Terminating Action)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Gulfstream Aerospace Corporation Index List GDL100000079, Revision (-),dated November 21, 2024.Instructions for Continued Airworthiness, CE41149A003, Revision B, datedNovember 15,2024, for GIV-X model.Instructions for Continued Airworthiness, CE51149A003, Revision B, datedNovember 15, 2024, for GV-...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/07/2025	Active	10087597

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087601	PMV ENGINEERING			ATR 72-212 A	Replacement of the Right Hand side cabin emergency exit door by areinforced structural plug.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25 change 15:25.29, 25.301(a)(b), 25.303, 25.305(a)(b), 25.307, 25.341,25.365(a)(b)(d)(e), 25.561 (a)(b)...	Certification Investigation Report P2F-00560-CIR Rev 03Instructions for continued airworthiness P2F-00560-ICA-S01 Rev 00or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Limitations as per Instructions for continued airwort...	17/07/2025	Active	10087601
10087605	STANDARD AERO BUSINESS AVIATIONSERVICES, L.L.C.		FAA SR04509CH	AS 332 L1 AS 332 L	Installation of a Helitak FT4250 Super Puma Fire Tank Liquid DispensingSystem	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: FAR 29.1 Amdt. 29-39,FAR 29.177 Amdt. 29-24, FAR29.865 Amdt. 29-43The requirements for environmental protect...	Certification Plan, ref. 1043984, Revision A, dated 09/06/2025Compliance Checklist, ref. 1039325, Revision D, dated 09/06/2025Rotorcraft Flight Manual Supplement, ref. 104-FT4250-AS332L1, RevisionC, dated 27/06/2025Instructions for Continued Airworthiness, ref. U10-0370, Revision C,dated 15/04/2025M...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/07/2025	Active	10087605
10087608	FTI ENGINEERING NETWORK GmbH			525C 525B 525A 525	Installation of a complete GOGO HDX antenna and SCS system	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: Certification basisapplicable to all models is CS-23 initial issue with the addition of CS23.1529 at amendmen...	Instructions for continuous Airworthiness ref F33-EO24-0048issue 1;Flight Manual Supplement Ref F20-001-EO24-0048 issue 1; Master Documentlist Ref IF18-E024-0048 issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/07/2025	Active	10087608
10087619	EIRTECH AVIATION SERVICES LIMITED			ATR 72-212, ATR 72-212 A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Installation of Lower Fuselage ProtectionThis Change installs 3M 8641 Protective Tape to provide protection tothe LowerFuselage Skin Panels onATR 42 and ATR 72 aircraft.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- MDL-1899-001_1 Issue 1-AMS-1899-001_1 Issue 1-AMS-1899-002_1 Issue 1-MPS-1899-001_1 Issue 1or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Airworthiness Limitations as per MPS-1899-001_1 Issue 1...	21/07/2025	Active	10087619
10087623	SPACE EXPLORATION TECHNOLOGIES CORPd/b/a Starlink Aviation	REV. 1	FAA ST04738NY	777-300ER 777-200LR	Installation of Dual SpaceX Starlink Aero TerminalsRevision1 adds model 777-200LR.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): PCRI-0000492-0060093363, Issue 6 –Vibration / Buffeting Compliance Criteria for Large Antenna InstallationThe following paragrap...	The change is defined with Version 3.0 of Space ExplorationTechnologiesMaster Data List document SPX-00006092, dated 9October 2024;The aircraft shall be maintained in accordancewith Version 3.0 SpaceExploration Technologies Instructionsfor Continued Airworthinessdocument SPX-00005963, dated 4 Se...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This approval is limited to the installation of the Dua...	22/08/2025	Active	10087623

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087635	ZIM AIRCRAFT CABIN SOLUTIONS, LLC		FAA STC ST04497AT	A330-202	Interior Reconfiguration on an Airbus A330-200 Series aircraft	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 amdt. 28: 25.853 (a)(c)(d)(e), 25.869 (a)(4), 25.899 (a)(b),25.981 (d), 25.1353 (a)(c), 25.1360 (a)(b),T...	ZIM Aircraft Cabin Solutions, LLC MDL 23T059L001, Rev B, dated 09 Jul2025;ZIM Aircraft Cabin Solutions, LLC Instructions for ContinuedAirworthiness 23T059R009 Rev 00, dated 21 Apr2025;or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Techni...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	13/08/2025	Active	10087635
10087636	EIRTECH AVIATION SERVICES LIMITED			737-800	16 B/C & 144 Y/C Cabin ReconfigurationThis Change removes the existing passenger seats and installs B/ EAerospace MiQ & Meridian seats in a split class configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: JAR 25.365, 25.571,25,607(a), 25.785(a), 25.1309 all at Change 13 (reversions not used).The requirements fo...	Master Document List, '16 B/C & 144 Y/C Cabin Reconfiguration,MDL/ 1846-001, Issue 3, dated 18th July 2025<(>,<)>or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/07/2025	Active	10087636
10087637	PILATUS BUSINESS AIRCRAFT, Ltd.		FAA STC SA01072DE	PC-24	Airtext system installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Installation Master Document List, Airtext for the PC-24<(>,<) >24-2001-01-0000, Revision A, dated 7 February 2022<(>,<) >Instructions for Continued Airworthiness (ICA), Airtext Installation, 24-2001-64-0000, Revision A, dated 21 September 2021<(>,<)>Airplane Flight Manual Supplement, 24-2001-65-0000,d...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	22/07/2025	Active	10087637
10087644	AEROLITE AG			PC-12/47G	PC-12 Sealed FloorWith this change, the original fourteen (14) OEM floor panels arereplaced by Aerolite designed heavy duty, lightweight sealed floorpanels.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	- MDL-25-003 Master Document List, Revision N/ C- FMS-230-0335400-501 Flight Manual Supplement, Revision 0- OPM-230-0335400-501 Operations Manual, Revision 0Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/07/2025	Active	10087644
10087652	BOMBARDIER Inc.		TCCA SA24-69 ISSUE 2	BD-700-1A10, BD-700-1A11	Installation, Aircraft Completion FAL Provisions	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.301, 25.303,25.305(a)-(c), 25.307(a), 25.601, 25.603, 25.605(a), 25.609, 25.611,25.853(a), 25.869 (a)(...	Bombardier Inc. Modification Data Summary RAZ-BM700-306 Revision A,dated November 6, 2024<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ Canada Bilateral Agreement.	None	23/07/2025	Active	10087652

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087655	AEROSPACE DESIGN & COMPLIANCE LLC		FAA STC ST04736NY	S550 700 680 (SOVEREIGN) 680A (LATITUDE) 560 550 500	True Blue TS28 Emergency Battery Power Supply Replacement	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 Amendment 15:§§25.601, 25.605 (a), 25.611(a), 25.812(i), 25.812 (j), 25.812(k),25.831(c), 25.869(a) (1)(2),...	Master Data List AML25-MDL-0171, Rev. IR, dated 9 September2024<(>,<) >Instructions for Continued Airworthiness AML25-ICA-0171, Revision IR,dated 23 July 2024< (>,<)>or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance with the Technical ImplementationPr...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	01/08/2025	Active	10087655
10087660	FOKKER TECHNIEK B.V.			A330-343	Fokker project: VIP cabin completion A330-343Completion of a VIP cabin layout configured for dual-role operation,i.e. private and commercial use, non-smoking.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): D-3313-001: Side Facing Seats and InflatablePassenger Restraints; M-TS-000090: Installation of Rechargeable Lithiumbatterythe followingf...	-Fokker Compliance Record Report A330-AXEO-CRR-0001 Iss 1 signed on25.JUL.2025-Fokker Master Data List A330-AXEO-MDL-0001 Issue 1 signed no23.JUL. 2025-Fokker AFM Supplement A330-AXEO-AFM-S-001 Issue 6 signed on 24.JUL.2025-Fokker Instructions for Continued Airworthiness A330-AXEO-ICA-S-0001Issue 3 s...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is limited to MSN 1907 only.Commercial use ist...	25/07/2025	Active	10087660
10087666	PMV ENGINEERING			A300 F4-622R A300 C4-620, A300 F4-605R A300 C4-605R VARIANT F A300 B4-622, A300 B4-622R A300 B4-605R, A300 B4-620 A300 B4-601, A300 B4-603	Tablet cradle & Power supply installation on A300-600	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- Special Condition(s): D-137 “Flightdeck fire mitigation” issue 3.- The following paragraph(s) at a later amendment: JAR 25 change 14:25.1529, CS-MMEL Issue...	Master Document List AVI-02352-MDL-S01 Rev 4MMEL SupplementAVI-02352-MMELS Rev 0Instructions for Continued Airworthiness AVI-02352-ICA Rev 1Aircraft Flight Manual Supplement AVI-02352-AFMS Rev 2or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Limitations as per document AVI-02352-ICA Rev.1.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no adverseeffect upon the airworthiness of the product.	28/07/2025	Active	10087666
10087686	SABENA TECHNICS BGC			A330-343	Cabin reconfiguration from Zero PAX to 358 Y/C	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS 25 Amdt. 4 for 25.1, 25.29, 25.305, 25.307, 25.321, 25.337, 25.341,25.471, 25.561, 25.562, 25.601, 25.603,2...	Master Data List - 41461-01-A-MDL Rev. 00 dated 28 July 2025Aircraft Flight Manual Supplement - 41461-01-A-AFMS Rev. 00dated 28 May2025OSD Change Description (Cabin Crew Data) - 41461-01-A-OSDCD Rev. 00Instructions for Continued Airworthiness - 41461-01-A-ICA Rev. 00 dated18 July 2025or later revis...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	29/07/2025	Active	10087686
10087715	Q.C.M. DESIGN GmbH			60	Halon-free Fire Extinguisher Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Instructions for Continuous Airworthiness Ref L60X-QCM26-001-M1-ICA Rev0 date 25/3/2025;Operations Manual Supplement Ref L60X-QCM26-001-M1-OPS Rev 0 dated25/3/2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/08/2025	Active	10087715

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087719	PMV ENGINEERING			ATR 72-212 A	SIDE RAILS EXTENSION FROM FRAME 35 TO FRAME 36 ON ATR 72 CARGO	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25 Amdt 20: 25.29, 25.301, 25.303, 25.305, 25.307, 25.321, 25.337,25.341, 25.365 (a)(d), 25.561, 25.571,2...	Master Data List, ref. P2F-00550-MDL-S01-R01 dated 31 July 2025Instructions for continued Airworthiness P2F-00550-ICA R00 dated 21 May2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The installation of the passengers to freighter convers...	04/08/2025	Active	10087719
10087730	AERSALE, Inc.		FAA STC ST03599NY	767-300 767-200	Installation of Center Fuel Tank Ignition Mitigation ReticulatedPolyurethane Foam	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment:CS25.901(a)(1)(3)(b)(2)(3)(4)(c) and CS25.981(a)(c) at Amdt 5The requirements for environmental protection and...	Dassault Aircraft Services or AerSale (1) Master Data List,B767-D0063-005, Revision D, dated 20 November 2024<(>,<)>Airplane Flight Manual Supplement, B767-D0063-150, Revision IR<(>,<)>dated 23 January 2018<(>,<)>Instructions for ContinuedAirworthiness (ICA) B767-D0063-155<(>,<)>Revision B, dated 2...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	05/08/2025	Active	10087730
10087734	SEBALD LUFTFAHRTTECHNISCHER BETRIEB(LTB)			SEE EASA APPROVED MODEL LIST	Modified wing airfoilFor the sailplanes and powered sailplanes named in the AML to this STCthe airfoil of the wing is modifiged.The maximum take-off weight without waterballast isincreased.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	- Technische Mitteilung TMS05, Rev.2, 16.03.2025 (TN)- Arbeitsanweisung TMS05-AW01, Rev. 2, 16.03.2025 (WI)- Ergänzung zum Flughandbuch Ventus 2c, Rev.0, 17.11.2024 (Sup. AFM)- Ergänzung zum Flughandbuch Ventus 2cM, Rev.0, 17.11.2024 (Sup.AFM)- Ergänzung zum Flughandbuch Ventus 2cT, Rev.0, 17.11.20...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.S/N limitation see AML.As well as S/Ns that were in the...	05/08/2025	Active	10087734
10087738	ALAMO ENGINEERING GmbH			CL-600-2B16 (604 VARIANT)	REPLACEMENT OF COLLINS CES WITH LHT NICEThis modification covers the removal of every single unit and switchpanel of the Collins CES-605 system and installation of thecorresponding units and switch panels of the Lufthansa NICE HD system asreplacement on a Bombardier CL-600-2B16 (604 Variant).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25.601<(>,<)> CS25.869<(>,<)> CS 25.1301, CS 25.1309<(>,<)> CS 25.1322<(>,<)> CS25.1351, CS 25.1353<(>,<)>...	The change is defined with Revision A of Alamo Engineering MasterDocument List MDL23A72AE-01The aircraft shall be operated in accordance with Revision A of AlamoEngineering Aircraft Flight Manual Supplement FMS23A72AE-01.The aircraft shallbe maintained in accordance with Revision A of AlamoEngineer...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/08/2025	Active	10087738
10087742	ROEDER PRAEZISION GMBH			182R, F182P, F182Q 182M, 182N, 182P, 182Q	Installation of Digital Engine Indication System in Cessna 182 aircraftequipped with SMA SR305 Engine	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 23. 1, 23.29,23.307, 23.603, 23.607, 23.611, 23.773, 23.863, 23.1301, 23.1305 (a)(b),23.1306, 23.1308, 2...	Master Data List Doc. No.: 24-01778MDL-01 Rev.02 dated 05 August 2025Aircraft Flight Manual Supplement Doc No: 24-01778FM-01 Rev. 01 dated05 August 2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.EASA STC 10013975 is a pre-requisite for this STC.	06/08/2025	Active	10087742

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087749	BUTLER NATIONAL CORPORATION		FAA STC ST00235MC	60 55C 55B 55 36A 36 35A 35 31A 31 25 24	Installation of Clock/Clock with USB Port	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Butler National Corporation Master Data List No. 08501000, Revision IR,dated 24 May 2024<(>,<)>Instructions for Continued Airworthiness, No. 08507011, Rev IR<(>,<)>dated 23 January 2024<(>,<)>Aircraft Flight Manual Supplement, No. 08507015, Rev IR, dated 5 June2024<(>,<)>or later revisions of the ab...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	14/08/2025	Active	10087749
10087753	PROTOPLANE SPECIAL MISSION AIRCRAFT			P.68 "OBSERVER 2"	Title: Lidar installation in the P68 Obs2 S/N338-25Description: The purpose of this STC is to replace the system Ultracamcamera + Somag GSM3000 by the system Riegl VQ1460 Lidar + Somag GSM4000.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	PP-184-AFM-04 (Aircraft Flight Manual)PP-184-IM-01 (Installation Manual) PP-184-ICA-00 (Instructions for Continued Airworthiness)Or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	a) STC applicable to P.68 Observer 2 s/n 338-25 onlyb) Minor change CNG-029-24 “Installation of Camera system on P.68”approved under the authority of DOA EASA.21J.529 as prerequisite.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repai...	07/08/2025	Active	10087753
10087763	FOKKER SERVICES B.V.			A320-232	Partial VIP cabin re-configurationPartial VIP cabin re-configuration of Airbus A320-232 with EASA STC10034242 incorporated	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS 25.23, 25.27, 25.301(a), 25.303, 25.305(a)(b), 25.307(a),25.321(a)(b), 25.471(a), 25.561, 25.571, 25.601,...	- Compliance Record Report, Doc. Ref.: A320-AKG-CRR-0001, Issue 1,Dated: 08/08/2025- AFM supplement for a partial VIP cabin re-configuration, Doc. Ref.:A320-AKG-AFM-S-0001, Issue 2,Dated: 31/07/2025- Operational Suitability Data - Cabin Crew Data - A320-232, MSN-1868,Doc. Ref.: A320-AKG-CCD-001, Iss...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.A pre-requisite to this change is that the following de...	08/08/2025	Active	10087763
10087780	FLYHT AEROSPACE SOLUTIONS Ltd.		SA22-70 ISSUE 2	A321-272N/-272NX A321-271N/-271NX A321-111/-211 A320-231/-232 A320-211/-212/-214 A319-111/-112/-113/-114	Installation of the AFIRS Edge System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	The modification is defined with FLYHT Aerospace Solutions Ltd MasterDocument List 121-0092, Revision BInstallation shall be performed in accordance with FLYHT AerospaceSolutions Ltd Installation Instructions 151-0073, Revision BThe aircraft shall be operated in accordance with FLYHT AerospaceSoluti...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	12/08/2025	Active	10087780
10087790	CABIN MANAGEMENT SOLUTIONS, LLC.		FAA STC ST11282DS	SEE FAA AML	Installation of a wireless cabin management system	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Data List 648-00-0001, Revision IR dated 5 April 2021<(>,<)>Airplane Flight Manual Supplement for Gulfstream GV-SP (G550)<(>,<)>Document Number 648-00-0089, Revision IR, dated 17 February 2025<(>,<)>For applicable Instructions for Continued Airworthiness please see AMLST11282DS, Rev. B, dated...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	14/08/2025	Active	10087790

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087792	PEREGRINE AVIONICS LLC		FAA ST01109DE	GV-SP GV GIV-X GIV	Gulfstream MB13 AntennaInstallation of Gogo MB13 Antennas on Gulfstream G-IV/GIV-X and GV/GV-SPseries aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): ELOS memo ST07784DE-T-25.251(b)-1as listed in FAA STC ST01109DEThe requirements for environmental protection and the associatedc...	- Master Drawing List, E-GS-23-1002, Rev. B-Instructions for Continued Airworthiness, E-GS-23-1008, Rev. BOr later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreement.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limitation/Condition as listed in FAA STC ST01109DE	14/08/2025	Active	10087792
10087794	STELLAR BLU SOLUTIONS GmbH			747-8	B747 SBS Diamondback InstallationInstallation of LEO/GEO satellite antenna "diamondback" system.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): PCRI-0000492-0060092266 - Vibration/buffeting compliance criteria for large external antennainstallationThe requirements for envi...	-AFM Supplement, document B747SA-AFM-A (Issue A)-CCD Supplement, document B747SA-CCD-A (Issue A)-Maintenance Planning Document Supplement, document B747SA-MPD-A (IssueA)-Master Document Register, document B747SA-MDR-231500 (Issue A)or later revisions of the above listed document(s) approved/ accepted...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/08/2025	Active	10087794
10087795	SABENA TECHNICS BGC			ERJ 190-100 STD ERJ 190-100 LR	Cabin Reconfiguration to 110 passengers with ISPSS.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: JAR 25 change 15:25.365, 25.831, 25.1439, 25.1441, 25.1443, 25.1447, 25.1450, 25.1453CS 25 amdt. 4: 25.1, 25....	Master Data List 41273-01-A-MDL Rev 00Instructions for Continued Airworthiness 41273-01-A-ICA Rev 00OSD Change Document41273-01-A-OSDCD Rev 00Aircraft Flight Manual Supplement 41273-01-A-AFMS rev 00or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	14/08/2025	Active	10087795
10087798	BUTLER NATIONAL CORPORATION		FAA STC ST01138DE	SEE FAA AML DATED 2 JULY 2024	Installation of MidContinent MD23 standby altimeter and/or attitudeindicators	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	FAA approved Master Drawing List, 07101000, Revision IR dated 17 May2024;FAA approved Aircraft Flight Manual Supplement, 07107015, 07107115,07107016, 07107116, for the MD23 Standby Altimeter, Revision IR dated 29May 2024;FAA accepted Installation Instructions and Instructions for ContinuedAirworthin...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.This approval allows the installation of the standby alt...	15/08/2025	Active	10087798
10087853	EIRTECH AVIATION SERVICES LIMITED			ATR 72-212, ATR 72-212 A ATR 72-202, ATR 72-211 ATR 72-102, ATR 72-201 ATR 42-500, ATR 72-101 ATR 42-320, ATR 42-400 ATR 42-200, ATR 42-300	Halon-Free Portable Fire Extinguisher Installation on ATRThis change replaces the existing halon portable fire extinguishers onATR 42 and ATR 72 aircraft with halon-free portable fire extinguishers.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: All requirements at alater amendment – CS 25 Amendment 28. The original certification basisfor each require...	Master Document List, ‘Halon-Free Portable Fire ExtinguisherInstallation on ATR, MDL/1928-001, Issue 1, dated 13th August 2025< (>,<)>or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	It is not permitted to mix halon and halon-free extinguishers in thecabin. All halon portable fire extinguishers must be removed from theaircraft before installing halon-free extinguishers.The cabin length must be equal to or greater than 337.3’’ (8.57m) toensure that, in the event of discharge, the...	19/09/2025	Active	10087853

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087854	TURK HAVA YOLLARI TEKNIK A.S.(TURKISH TECHNIC Inc.)			737-8	189E/C Passenger Seating LayoutThis modification introducesa cabin layout generating a 189-passengerseating configuration.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: JAR 25.1301, JAR25.1453, JAR 25.1441 (a)(c) at JAR 25 Change 13JAR 25.1309, JAR 25.1353 at JAR 25 Change 13 O...	The change is defined with Revision 8 of Turk Hava Yollari TeknikCertification Program Document C0392-CEP-08Or later revisions of the above listed document (s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	27/08/2025	Active	10087854
10087857	Q.C.M. DESIGN GmbH			BD-700-1A10, BD-700-1A11	GOGO GALILEO SATCOM SYSTEM INSTALLATION	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment: CS 25.1319 Amdt. 25.The requirements for environmental protection and the associatedcertified noise and/ or...	Flight Manual Supplement Ref BBD5-QCM23-003-M1-AFM Rev 0 dated 9 July2025Instructions for Continuous Airworthiness Ref BBD5-QCM23-003-M1-ICA RevDated 3/9/2024Master Document List Ref BBD5-QCM23-003 Rev 0 dated 19/8/2025or later revisions of the above listed document(s) approved/acceptedunder the EAS...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	22/08/2025	Active	10087857
10087868	ALAMO ENGINEERING GmbH	REV. 1		757-200	Installation of AFIRS Iridium Satcom System for FANS-1/A and SafetyVoiceInstallation of new FLYHT AFIRS 228S TSO on Boeing 757-200 Seriesaircraft. This system is for FANS-1/A Iridium and Safety Voice andreplaces an existing Inmarsat Aero Satcom. The change covers:• Removal of MCS-7200 SATCOM system•...	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:- The following paragraph(s) at a later amendment:CS-25, Amdt. 28 for CS 25.899, 25.1319, 25.1360, 25.1457, 25.1460.The requirements for environmental protect...	- Master Document List, MDL25A08AE-01<(>,,<)> Rev. C- Aircraft Flight Manual Supplement, FMS25A08AE-01, Rev. B- Instructions for Continued Airworthines s, ICA25A08AE-01, Rev. AOr later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Pre-Requisites:This change requires a suitable Flight M...	26/08/2025	Active	10087868
10087869	TRIEB GmbH			DA40	Operation on unleaded fuel	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Airplane Flight Manual Supplement, document AFM-EOMD030-01,date 06 Aug2025Drawing Auxiliary pump Installation, document EOMD030-2824-01-00, date05 July 2025Engineering Order, document EOMD030/F07, dated 15.08.2025or later revisions of theabove listed document(s) approved/ acceptedunder the EASA sys...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	25/08/2025	Active	10087869
10087877	KILROY AVIATION LLC			737-900ER 737-800 737-700	Vortex Control Technologies Finlets installation	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s): adoptedESF SA09849NY-T—F-1 dated 31 Aug2022 (737-800) and ST09730-NY-T-F1 dated 15 Jul 2022 (737-900/900ER) andESF SA100767NY-T...	Master Data Index List J523-0020-001 Rev HInstructions for continued Airworthiness J625-ICA Rev IRAFM Supplement J625-AFMS Rev -or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProcedures of EU/ USA Bilateral Agreeme...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.-Limitations as per documents J625-ICA and J625-AFMS-Fo...	26/08/2025	Active	10087877

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087878	STANDARD AERO		FAA ST11110SC	747-8	Installation of an Executive Interior	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): - MCRI-0000411-0060089724, Issue 4 – PersonalInjury Criteria of Dynamic Testing of Side Facing SeatsThe following paragraph(s) at a late...	Installation of an Executive Interior in accordance with StandardAero“Master Document List” Document Number 3057000000,Revision LThe aircraft has to be operated in accordance with StandardAeroAirplance Flight Manual Supplement (AFMS), Document Number 3057021090,Revision DThe aircraft has to be main...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.At time of approval of this change to type certificate,...	26/08/2025	Active	10087878
10087886	AIRBORNE TECHNOLOGIES GmbH			208B	Exhaust Gas Bypass Tube InstallationWithin this STC an exhaust gas bypass tube is installed on the Cessna208B (Caravan)to direct the gases to the back of the aircraft.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 23.21 (a)-(b), CS23.45<(>,<)> CS 23.49 (a),(c), (d), CS 23.51 (a)-(b), CS 23.53 (a)-(b),CS 23.63 (a),(c), C...	The change is defined with Revision 0 of AIRBORNE TECHNOLOGIES ChangeApproval Sheet STC-188-G-ASThe aircraft shall be operated in accordance with Revision 0 of AIRBORNETECHNOLOGIES Aircraft Flight Manual Supplement STC-188-G-AFM.The aircraft shall be maintained in accordance with Revision 0 ofAIRBOR...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The EASA STC is limited to Serial Numbers 208B5000 upwa...	27/08/2025	Active	10087886
10087891	AEROTEC & CONCEPT			EC 225 LP	Cabin Floor Protection Tray Installation MOD 24058	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List (including Declaration of Compliance) doc.N°:AE24058MDL Rev. 0 dated 04 August 2025Rotorcraft Flight Manual Supplement (RFMS) for Floor Protection TrayInstallation on EC225LP doc. N°: AE24058RFMS Rev. 4 (Issue 0 as per MDL)dated 26 June 2025Instructions for Continued AirworthinessI...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is approved for installation on EC225LP helico...	27/08/2025	Active	10087891
10087892	THALES AVIONICS Inc.		FAA STC ST02745LA	A321-231	Installation of the Thales Digital Server Unit	The Type and OSD Certification Bases (CB) for the original product asamended by the following additional or alternativeairworthinessrequirements: The following paragraph(s) at a later amendment:CS 25 amdt. 0: 25.869(a)(4)The requirements for environmental protection and the associatedcertified nois...	Thales Avionics, Inc. Index List Document No. 259903 revision A, dated22 July 2025;Supplemental Instructions for Continued Airworthiness (ICA) Document No.189201-ICA revision A, dated 16 July 2025;or later revisions of the above listed document (s) approved/accepted onbehalf of EASA in accordance wit...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	27/08/2025	Active	10087892
10087901	UMLAUT ENGINEERING GMBH			747-8	Ka-Band System Structural Provisions	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Equivalent Safety Finding(s):Vibration/buffeting compliance criteria for large external antennainstallationMCRI-0000492, (B-01) Issue 3the following paragraph...	UM-ABW01-FMS-0001 – Issue A - Aircraft Flight Manual SupplementUM-ABW01-ICA-0001 – Issue A - Instructions for ContinuedAirworthiness (ICA)UM-ABW01-MDL-0001 - Issue A - Master Document Listor later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	01/09/2025	Active	10087901

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10087973	AIRBUS TRANSPORT INTERNATIONAL SNC			A330-743L A300F4-608ST	On-Board Cargo Loader OBCL STI (ref. BL00MOD001)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Change Approval Sheet - ref. BL00MOD001_CAS Issue 1W<(>&<)>B Supplement included in Approved Manual Supplements - ref.BL00MOD001_AMS Issue 2 dated 15 July 2025MMEL supplement included in Approved Manual Supplements - ref.BL00MOD001_AMS Issue 2 dated 15 July 2025STI Limitations and Instructions Manua...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This change is limited to the following MSN:-MSN 002; 0...	05/09/2025	Active	10087973
10087999	BOEING IRELAND LIMITED			737-8	Boeing 737-8 Reconfiguration (to 189Y PAX)Aircraft reconfiguration from a zero-passenger occupancy layout to189PAX economy class seats layout.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-CCD Issue 2The requirements for environmentalprotection and the associatedcertified noise and/ or emissio...	-Change Approval, Doc. Ref.: BIL-00296-APP, Revision: 00, Dated: 10/09/2025-Certification Programme, Doc. Ref.: BIL-00296-CP, Revision: 01, Dated:05/09/2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/09/2025	Active	10087999
10088052	J & C ENGINEERING SERVICES Ltd.			U206F/U206G/U206 U206A/U206B/U206C/ U206D/U206E TU206E/TU206F/TU206G/ U206 TU206A/TU206B/TU206C/ TU206D TP206B/TP206C/TP206D/ TP206E P206D/P206E/T206H/ TP206A 206H/P206/P206A/P206B/ P206C	XCAM POD INSTALLATION ON PORT AND STARBOVALIDATION OF UK STC 000372 REV 2	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 23 Amendment 4 :23.25; 23.29 ; 23.45; 23.49; 23.63; 23.65; 23.69; 23.71; 23.73 23.75;23.77; 23.141 ; 23.1432...	Engineering Report JC/ER/ 6125 (Issue 1.1 dated 18/07/25) Aircraft Flight Manual Supplement JC/ FMS/6125 (Issue 1.1 dated30/06/25), X-CAM Installation General Arrangement Drawing XCA570JC3219 (Issue Adated 30/09/24) Technical Report – XCAM Pod Installation on Port or Starboard WingStrut JC/ TR/60 (Issu...	1. The installer must determine whether this change to the typecertificate is compatible with previously approved configurations.2. This certificate and associated data shall remain valid untilsurrendered, withdrawn, or otherwise terminated.3. If transfer of this approval is requested this certifica...	15/09/2025	Active	10088052
10088053	INTERNATIONAL WATER-GUARDINDUSTRIES Inc.		TCCA STC SA21-47 ISSUE 2	737-8	Boeing 737 Max Pre-Select InstallationSystem to automatically control the amount of water that goes into thepotable water tank during ground servicing	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	JB Aero Engineering Master Data Summary 1188-MDS-01 Issue 3, dated March4, 2022;Instructions for Continued Airworthiness MM-017371-201 Rev. 0, dated May31, 2021;or later revisionsof the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical ImplementationProced...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	15/09/2025	Active	10088053
10088066	ALAMO ENGINEERING GmbH			GV-SP	Iridium Satcom Antenna Relocation on Gulfstream GV-SP series aircraft.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.Part-26 compliance information: CS-26, Issue 5 for CS 26.300(a), 26.301,26.303, 26.304, 26.305The requirements for environmental protection and the associatedcertified noise and/ or emission...	- Master Document List: MDL25A23AE-01, Rev. A;- Instructions for Continued Airworthiness: ICA25A23AE-01, Rev. A;or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/09/2025	Active	10088066

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10088070	AIRBUS HELICOPTERS, Inc.		FAA STC SH4343SW-D	A350B, BA, B1, B2, B3, D	Installation of strobe anti-collision light installation and/orsupplemental strobe light	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Drawing List 350A82-1176, Revision AP, dated 9 June 2015<(>,<)>Instructions for Continued Airworthiness (ICA) 350MMS-030, Revision IR,dated 25 June 2015<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf ofEASA in accordance with the Technical ImplementationProcedur...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.For AS350B3 post ECP 07.20207 aircraft EASA STC 10087192...	16/09/2025	Active	10088070
10088071	J & C AEROSPACE DESIGN ANDCERTIFICATION SERVICES EEU Ltd.			A321-272N/-272NX A321-253NY/-271N/-271NX A321-252/-252NX/-253N/-253NX A321-213/-231/-232-251N/-251NX A321-111/-112/-131/-211/212 A320-253N/-271N/-272N/-273N A320-232/-233/-251N/-252N A320-212/-214/-215/-216/-231 A319-231/-232/-233 A320-211 A319-171N/-173N A319-131/-132/-133/-151N/-153N A319-111/112/-113/-114/-115 A318-111/-112/-121/-122	Customized Movable Class Divider, Windscreen and ETSO c127aAn operator has requested to introduce adaptation of the passenger cabinfrom dual class layout - 158 PAX (8J/150Y) to single class layout - 180PAX (180Y) including customized Movable class divider and Windscreens.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25.321; 25.1541 atAmdt 17; CS25.601; 25.603; 25.605; 25.609; 25.611; 25.613; 25.619;25.625 at Amdt 11The re...	Master Document list: JCAERO_MDL_1509 Issue 1 dated Sept 11th 2025AMM Supplement: JCAERO/AMM/1509 Issue 1 dated Sept 11th 2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	16/09/2025	Active	10088071
10088109	BUTLER NATIONAL CORPORATION		FAA STC ST04538CH	36A 36 35A 35	Installation of a Class A Terrain Awareness Warning System (TAWS)	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Butler National Corporation Master Data List 07201000, Revision C<(>,<)>dated 28 May 2025;FAA Approved Aircraft Flight Manual Supplement (AFMS), document number07207100, Revision IR, dated 5 May 2025;FAA approved Instructions for ContinuedAirworthiness, document number07207200, Revision A, dated 28...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	18/09/2025	Active	10088109
10088116	SOCIETE AIR FRANCE S.A.			A350-941 A350-1041	Personal tablet (“EFB”) mount mechanical provision installation on A350	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): M-TS-0000419 Issue 2The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the prod...	Change Approval Sheet, Doc. Ref.: CAS-A350-24-001, Rev.: 01, Dated: 18/09/2025;Certification Programme, Doc. Ref.: CP-A350-24-001, Rev.: 03, Dated:05/08/2025;Airplane Flight ManualSupplement, Doc. Ref.: AFMS-A350-24-001-002,Rev.: 1, Dated:22/07/2025;or later revisions of the above listed document(s...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Limited to the casing and computer tablet configuration...	19/09/2025	Active	10088116
10088118	EIRTECH AVIATION SERVICES LIMITED			A320-271N/-272N/-273N A320-251N/-252N/-253N A320-216/-231/-232/-233 A320-211/-212/-213/-214/-215	A320 Mirus Seat InstallationThis Change removes the existing passenger seats and installs Mirus MH08series seats in a full economy class configuration	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	MDL/1766-001 issue 01 dated 18th September 2025AMM supplement: AMS/1766-001 issue 03 dated 01st August 2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Aeroplane modified by this change must be maintained in...	23/09/2025	Active	10088118

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10088126	HAVACILIK MUHENDISLIK VE SERTIFIKASHIZM ETLERI SANAYI VE TICARET A.S.t/ a TRACES AEROSPACE			737-8	Passenger interior arrangement to 189 pax-Initial issue: new seats, IFE deactivation, PSU and monumentadaptation.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master data list, Ref. MDL-TS1210 Issue D dated 20 September 2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/09/2025	Active	10088126
10088128	MT-PROPELLER ENTWICKLUNG GmbH			SR20	Installation of MTV-9-B/188-50( ) Propeller on Cirrus Design CorporationSR20.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: ICAO Annex 16, VolumeI, Amendment 14, Chapter 10This certificate/approval involves a change with an impact on...	According to MT-Propeller Master Documentation List No. E-4462 Rev. 1To be operated in accordance with MT-Propeller AFMS Document No. E-4464Rev. 0To be installed i.a.w. MT-Propeller Installation Instructions Doc. No.E-4465 Rev. 1To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4466 Rev. 0.or late...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/09/2025	Active	10088128
10088138	MT-PROPELLER ENTWICKLUNG GmbH			SR22	Installation of MTV-9-D/198-52( ) Propeller on Cirrus Design CorporationSR22.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: ICAO Annex 16, VolumeI, Amendment 14, Chapter 10This certificate/approval involves a change with an impact on...	According to MT-Propeller Master Documentation List No. E-4549 Rev. 1To be operated in accordance with MT-Propeller AFMS Document No. E-4551Rev. 1To be installed i.a.w. MT-Propeller Installation Instructions Doc. No.E-4552 Rev. 1To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4553 Rev. 0.or late...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	24/09/2025	Active	10088138
10088139	MT-PROPELLER ENTWICKLUNG GmbH			SR22T	Installation of MTV-9-D/198-52( ) and MTV-9-D/198-58( ) Propeller onCirrus Design Corporation SR22T.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: ICAO Annex 16, VolumeI, Amendment 14, Chapter 10This certificate/approval involves a change with an impact on...	According to MT-Propeller Master Documentation List No. E-4474 Rev. 1To be operated in accordance with MT-Propeller AFM-S Document No. E-4476Rev. 0To be installed i.a.w. MT-Propeller Installation Instructions Doc. No.E-4477 Rev. 1To be maintained i.a.w. MT-Propeller ICA Doc. No. E-4478 Rev. 0or late...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.According limitation section of AFM-S	24/09/2025	Active	10088139
10088140	NORTHERN AVIONICS S.R.L.			AW169	Restoration of NVIS capability following change of approvedbasic NVISconfigurationNorthern Avionics project No. 02505NAV0683	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-29 Amendment 12: CS29.1 (a), (b), (e); CS 29.773 (a); CS 29.1301; CS 29.1309 (a), (b); CS29.1383; CS 29.15...	Project Description - doc. ref. NAV0683/1 Rev. 3Certification Programme – doc. ref. NAV0683/2 Rev. 4Compliance Check List – doc. ref. CCL0683 Rev. 1Project Approval (incorporatingDeclaration of Compliance) – doc. ref.NAV0683/3 Rev. 3AW169NVG Compatibility Reference Handbook Supplement – doc. ref.N...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.This STC is applicable to AW169 helicopters fitted with...	24/09/2025	Active	10088140

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10088147	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS			A330-341/-342/-343 A330-321/-322/-323 A330-301/-302/-303 A330-223/-243 A330-201/-202/-203	Thinkom Antenna installation (without activation) on A330Installation of a Thinkom satcom antenna on Airbus A330 withoutactivation of the system	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 at Amdt 4: 25.23;25.29; 25.101; 25.111; 25.113; 25.115; 25.117; 25.119; 25.121; 25.123;25.125; 25.145; 2...	Master Document List: 02009-EAS-B-MDL-01 Issue B dated 23rdSept 2025AFM supplement: 02009-EAS-B-AFM-01 Issue C dated 23rd Sept 2025ICA supplement: 02009-EAS-B-ICA-01 Issue A dated 27th Aug 2025or later revisions of the above listed document(s) approved/acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.- Aeroplane modified by this change must be operated in...	25/09/2025	Active	10088147
10088150	E A D AEROSPACE AIRWORTHINESS T/AECLIPSE TECHNICS			A350-941 A350-1041	Starlink System activation to IFE on Airbus A350Connection of the Starlink System installed by EAD modification STC10087017 to the IFE of the Aircraft	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS25 Amdt 28: CS25.1319The requirements for environmental protection and the associatedcertified noise and/ o...	Master Document List: 02012-EAS-A-MDL-01 Issue A dated 24thSept 2025PISRA: 02012-EAS-A-PISRA-01 Issue B dated 28th Aug2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.STC 10087017 is a prerequisite on the installation of t...	25/09/2025	Active	10088150
10088164	HELIBRAS - HELICOPTEROS DO BRASIL S	REV. 1	ANAC STC 2025S08-01	AS 350 B2	Oil Pressure Sensor replacement Rev. 1: Correction of ANAC STCreference.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Document List No. 350B04 0095, Rev. C, dated 29 July2025<(>,<) >Helibras Instructions forContinued Airworthiness (ICA), Document No.STC-HB-247-ICA, Rev. 0, dated 22 July 2025,or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	31/10/2025	Active	10088164
10088202	DASSAULT FALCON JET CORPORATION		FAA STC ST03616NY	FALCON 7X	Installation of SpaceX Starlink Aviation System in DassaultAviationmodel Falcon 7X series aircraft	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Dassault Falcon Jet Corp (1) Master Data List F7XW-D0117-005Rev. (-) dated 09 July, 2025;(2) Instructions for ContinuedAirworthiness (ICA) F7XW-D0117-155 Rev.(-) dated 25 June 2025;(3) Airplane Flight Manual Supplement F7XW-D0117-150 Rev.(-) dated 09July, 2025;or later revisions of the above liste...	Applicable to Dassault Aviation Falcon 7X aircraft serial numbers 001through 400 and Falcon 7X airplanes on which modification M1000 andM1254 are installed at production (Falcon 8X Definition), aircraftserial numbers 0401 and subsequent with Dassault Aviation ModificationOption M-OPT1238 Starlink An...	30/09/2025	Active	10088202
10088231	Q.C.M. DESIGN GmbH			60	UHF SYSTEM INSTALLATION AND AUDIO SYSTEM	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	L60X-QCM23-001-M1-AFM-02 - Airplane Flight Manual Supplement - R<(>&<)>SM3AR MR6000R UHF System Rev 0 DATED 1/5/2025L60X-QCM23-001-M1-AFM-01 - Airplane Flight Manual Supplement - BeckerAvionics – DVCS 6100 Audio System Rev 0 DATED 1/5/2025L60X-QCM23-001-M1-ICA - Instructions for Continued Airworthin...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	02/10/2025	Active	10088231

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10088235	AIRCRAFT INTERIOR REFURBISHMENT ESPANA S.L.			777-200	Passenger Cabin Reconfiguration. Interior reconfiguration consisting ofreplacement of premium economy and economy seats; modification ofbusiness class seats, modification of Door 2 Bar unit, removal ofexisting IFE and structural and electrical provisions for a new IFEsystem.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Master Document List, Ref. B777C019-MDL001, Issue 4, dated 22/09/2025,and Drawing List, Ref. B777C019-DL001, Issue 1, dated 15/09/2025.Maintenance Manual Supplement, Ref. B777C019-MMS001, Issue 1, dated15/09/2025, and Wiring Manual Supplement, Ref. B777C019-WMS001, Issue 1,dated 15/09/2025.Or lateru...	Prior to installation of this change it must be determined that theaircraft conforms with the required pre-modificationconfiguration asdefined in section 1.7 of document Change Description Report, Ref.B777C019-CDR001, Issue 5.Structural and electrical provisions for new IFE system installedconcurre...	02/10/2025	Active	10088235
10088240	GLOBAL AEROSPACE DESIGNCORPORATION		FAA STC ST12089CH	A320-251N	Premium Economy Class Seat Relocation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval....	Master Drawing List 24GR136-MDL Revision B dated 24 June 2025<(>,<)>Instructions for Continued Airworthiness Document Number 24GR136-ICARevision B dated 16 July 2025<(>,<)>or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordance with the Technical Implement...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.	02/10/2025	Active	10088240
10088249	AEROTEC & CONCEPT			A319-133 A319-132 A319-131 A319-115 A319-114 A319-113 A319-112 A319-111	Gogo Galileo System Provisions InstallationThis modifications covers the mechanical installation of a SATCOMantenna with associated provisions (interface plate, fairings, doubler,reinforcements).	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: CS 25.21, 25.23, 25.25,25.27, 25.29, 25.101, 25.103, 25.105, 25.117, 25.123, 25.125, 25.143,25.145, 25.147, 2...	Master Data List, Ref. AE25009MDL, Rev. 0, dated 26/09/2025.Aircraft Flight Manual Supplement, Ref. AE25009AFMS, Rev. 1, dated26/05/2025.Instructions for Continued Airworthiness, Ref. AE25009ICA, Rev. 3, dated05/09/2025.Service Bulletin, Ref. AE25009SB, Rev. 1, dated 06/06/2025.Or later revisions of...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	07/10/2025	Active	10088249
10088253	AEROTEC & CONCEPT			A320-214	A320 Cabin ReconfigurationA320 Cabin Reconfiguration from 150 Y/C to 180 Y/C. Removal of 50 Y/CSAFRAN 5750 series seatsand Installation of 60 Y/C SAFRAN Z100 seats	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	- AE25063MDL MASTER DATA LIST (MDL) Rev. 0Or later revisions of the above listed document(s) approved/acceptedunder theEASA system.	Concurrent modification: EASA STC ref. EASA.A.S.01056 Installation ofnon-electrical floor path marking system.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introducee...	07/10/2025	Active	10088253
10088256	B/E AEROSPACE LIMITED		TCCA C-LSA08-195/DAT ISSUE 2	BD-700-1A10	Installation, In-flight Entertainment System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Modification Data Summary F844000 Rev. B dated 13 May 2025Aircraft Flight Manual Supplement F844091, Rev. N/C, dated 11July 2008Instructions for Continued Airworthiness 9240-ICA,Rev A dated 07 May2025or later revisions of the above listed document(s) approved/ accepted onbehalf of EASA in accordanc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Applicable to a/c s/n 9240	07/10/2025	Active	10088256

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10088287	MAGA AVIATION MANUTENCAO DE AERONAVLTDA		ANAC STC NO 2025S03-17	LEARJET MODEL 45	Installation of the Honeywell RDR 7000 Weather Radar System	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Document List (MDL), Doc. No. 001MDL001-2023, Rev. F, dated 02February 2025Instructions for Continued Airworthiness, Doc. No. 014ICA001-2023, Rev.A, dated 26 December 2024Aircraft Flight Manual Supplement, Doc. No. H. 02-5939-0/ANAC/2023, Rev.IR, dated 24 March 2025or later revisions of the ab...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	08/10/2025	Active	10088287
10088311	Q.C.M. DESIGN GmbH			BD-100-1A10	Halon-Free Fire Extinguisher Installation	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	BBD1-QCM26-001-M1-ICA Instructions for Continued Airworthiness Rev 0Dated 10/8/2025BBD1-QCM26-001-M1-OPS Operations Manual Supplement Rev 0 Dated 10/8/2025or later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	09/10/2025	Active	10088311
10088312	APTOZ EHF.			737-800	Installation of 162 passenger LOPACabin reconfiguration from 144 to 162 passenger dual class LOPA,removing the previously fitted seats and installing 12 Geven Comoda B/Cseats and 150 Geven Essenza E/C seats.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at CS-25 amendment 28:25.1, 25.29, 25.301,25.303, 25.305, 25.307,25.341, 25.365, 25.561,25.562 except (c)(5), 25.571, 25.601,25.603...	MDL251905 Master Data ListAFM251905-1 Aircraft Flight Manual SupplementICA251905-1 Instructions for Continued AirworthinessOr later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Concurrent modification: STG SaftGlo emergency floor path marking systemis installed per EASA STC 10074237Prior to installation of this change/repair it must be determined thattheinterrelationship between this change/repair and any otherpreviously installed change and/ or repair will introduce no a...	13/10/2025	Active	10088312
10088358	SWISS HELICOPTER ENGINEERING AG			AS 350 B3	Installation of a cockpit floor window P/N 350-000087-A.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Compliance Checklist CCL-350-000087 issue 00, released on 15 October2025.Change Declaration of Compliance CDC-SHE-2024004, dated 15 October 2025.Flight Manual Supplement FMS-350-000087-01 issue 00.Instructions for Continued Airworthiness ICA-350-000087, issue 00.or later revisions of the above liste...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.For pre-requisite modifications and compatibility, refe...	16/10/2025	Active	10088358
10088359	KAELIN AIRCRAFTSTRUCTURE GmbH			AS 350 B3	Installation of a cockpit floor window P/N 53001002750.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Declaration of Compliance AEF-0694-DEC-0005, issue 01 dated14 October2025.Flight Manual Supplement AEF-0694-FMS-0004, issue 02 dated 15 October2025.Instructions for Continued Airworthiness AEF-0694-ICA-0006, issue 02dated 13 October 2025.Service Bulletin AEF-0694-SBU-0006, issue 02 dated 13 October...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.For pre-requisite modifications and compatibility, refe...	16/10/2025	Active	10088359

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10088382	DOA21 LIMITED			A320-251N	Introduction of VIP Cabin Interior “PRM2” with the followingconfigurations:-“commercial operations” configuration-“private operations” configuration	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): PCRI-0000165-0060087251 Oxygen EquipmentQualification above 40.000ft Issue 3the following paragraph(s) at a later amendment: CS 25 amdt2...	Master Document List D21.MDL-0005 Issue 1Flight Manual Supplement D21.FMS-0003 Issue 1OSD Cabin Crew Data D21.CCD-0004 Issue 6MMEL Supplement D21.MMEL-0002 Issue 2Aircraft Maintenance Manual Supplement D21.AMMS-0008 Issue 1Aircraft Maintenance Manual Supplement (EWIS tasks) D21.AMMS-0009 Issue1or la...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.As per D21.FMS-0003, in particular the “private operati...	21/10/2025	Active	10088382
10088387	PMV ENGINEERING			787-8 777-300ER	Replacement of hand-held cabin and crew compartments portable halonextinguishers with halon free extinguishers.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS 25 amdt. 27: 25.601,25.603, 25.789, 25.851, 25.1301, 25.1411, 25.1529, 25.1561The requirements for environ...	For B777-300ER:Master Data List CAB-04840-MDL-S01 Rev03Instructions for Continued Airworthiness CAB-04840-ICA-S01 Rev 01For B787-8:Master Data List CAB-04840-MDL-S02-Rev 03Instructions for Continued Airworthiness CAB-04840-ICA-S02 Rev 01orlater revisions of the above listed document(s) approved/acc...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	21/10/2025	Active	10088387
10088491	JET AVIATION AG			SEE EASA APPROVED MODEL LIST	Halon Free Portable Fire ExtinguisherIntegration of non-Halon handheld fire extinguishers as replacement forcurrently installed Halon type or new installation for use in cockpit,passenger cabin and class B cargo/baggage compartment.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: 25.601, 25,831 (a),25.853, 25.855(h)(i), 25.857(b)(1)(2), 25.1301, 25.1529, 25.1561 (a),25.1581 at CS-25 Amdt.T...	Master Data List JBSL-M-04242MDL-001, Issue AApproved ModelList JBSL-M-04242AML-001, Issue AInstructions for ContinuedAirworthiness JBSL-M-04242ICA-001, Issue AOr later revisions of the above listed document (s) approved/ acceptedunder theEASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The physical installation of the fire extinguisher is n...	31/10/2025	Active	10088491
10088494	AIRCRAFT INTERIOR REFURBISHMENT ESPANA S.L.			A320-233 A320-232 A320-231 A320-216 A320-215 A320-214 A320-212 A320-211	LOPA & ISPS INSTALLATIONThe modification involves replacingall passenger seats to achieve a180-passenger, all-economy configuration (Y/C), removing the IFE(In-Flight Entertainment) equipment, and installing an ISPS (In-SeatPower Supply) system.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:The following paragraph(s) at a lateramendment: 25.23, 25.25, 25.301,25.303, 25.305, 25.307, 25.321, 25.333, 25.337, 25.341, 25.365(a),25.601, 25.603, 25.613...	A320C313-DL001 Drawing List, Issue 3A320C313-MDL001 Master Document List, Issue 4A320C313-AFM001 Flight Manual Supplement, Issue 1A320C313-CCD01 CCD Supplement, Issue 1A320C313-MMS001 Maintenance Manual Supplement, Issue 1Or later revisions of the above listed document(s) approved/acceptedunder the...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	30/10/2025	Active	10088494
10088534	SABENA TECHNICS BOD			B300	FIRE EXTINGUISHERS INSTALLATIONSNT Replacement of Fire-Extinguishers for B300 with Halon Free	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Installed in accordance with Document: Master Data List DocumentMDL-S-26-4466, Revision A, Dated 21 October 2025Operated in accordance with Aircraft Flight Manual Supplement (AFMS):Document AFMS-S0007-26-004 Issue B, Dated 12 September 2025Maintained in accordance with Instructions for Continued Air...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The following modifications must be concurrently embodi...	03/11/2025	Active	10088534

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10088537	TELAIR US LLC		FAA STC ST12067AT	ATR 72-212 A ATR 72-212 ATR 72-211 ATR 72-202 ATR 72-201	Installation of USCS Door Sill Protectors P/N 70042-101 and70042-102	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CS-25 Amendment 27:25.301, 25.303, 25.305, 25.561, 25.601, 25.603, 25.605, 25.607, 25.609,25.613(a)(b), 25.61...	Master Drawing List for ATR72 Door Sill Protectors, U.S. Cargo SystemsReport Number RPT-04209, Revision 1.0, dated 15 May 2025;Instructions for Continued Airworthiness for ATR72 Door Sill Protectors,U.S. Cargo Systems Report Number RPT-04208, Revision 2.0, dated 20 June2025;Weight and Balance Manuel...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/or repair will introduce no adverseeffect upon the airworthiness of the product.This Door Sill Protectors, P/N 70042-101 and 70042-102 m...	04/11/2025	Active	10088537
10088540	RMCI CANADA, Inc.		TCCA STC SH17-26 ISSUE 3	MBB-BK117 C-2 MBB-BK117 B-2	This STC is for the installation of an integrated Health and UsageMonitoring System (HUMS) with the marketing name of 'ExpandableRotorcraft Diagnostic System (XRDS)'.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	CERTIFICATION PLAN - INSTALLATION, INTEGRATED HEALTH AND USAGEMONITORING SYSTEM AIRBUS HELICOPTERS BK117 B-2 & C-2, ref. UA405-CPrevision I, dated 1st July 2022;BK117 XRDS Master Data List, ref. RMCI-000042 Revision 9, dated 02ndNovember 2022;BK117 XRDS Instructions for Continued Airworthiness, ref....	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.No maintenance credit is granted for the installation o...	04/11/2025	Active	10088540
10088541	SABENA TECHNICS BOD			A350-1041	Cabin reconfiguration S0060<(>,<) >increasing passenger seats from 360 to 480 and modifying the cabin froma three-class to a two-class layout.	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	Master Data List MDL-S-00-4463 Rev AInstructions for Continued Airworthiness ICA-S0060-00-002 rev Aor later revisions of the above listed document(s) approved/ acceptedunder the EASA system.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.Following Airbus changes are preconditions to the insta...	04/11/2025	Active	10088541
10088545	RMCI CANADA, Inc.		TCCA STC SH22-20	412EP 412 212	Installation of Integrated Health and Usage Monitoring System (HUMS)	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval withou...	Bell 212-Installation Instruction – Engineering Change Order RMCI-000228 Rev 0dated 17 March 2022.-Master Data List - RMCI-000224 Revision 1, dated 1 August 2022.-Instructions forContinued Airworthiness - RMCI-000225 Revision 0,dated January 18, 2022.Bell 412 series-Installation Instruction – Engin...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.The installation of the Integrated Health and Usage Mon...	05/11/2025	Active	10088545
10088549	HELI AUSTRIA GmbH			AS 332 L2 AS 332 L1 AS 332 L AS 332 C1 AS 332 C	Installation of an Integra AF-H ELTWith this change, the Emergency Locator Transmitter (ELT) INTEGRA AF-Hcan be installed in Airbus Helicopters AS 332 C, AS 332 L, AS 332 C1, AS332 L1, AS 332 L2.	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:Special Condition (s): M-TS-0000103 Non-rechargeable Lithium BatteryInstallationsThe requirements for environmental protection and the associatedcertified nois...	The change is defined with Revision 2 of HELI AUSTRIA Master DocumentList HAU-D-093-001.The aircraft shall be operated in accordance with Revision 0 of HELIAUSTRIA RFMS HAU-D-093-005.The aircraft shall be maintained in accordance with Revision 0 of HELIAUSTRIA ICA HAU-D-093-006, including the respec...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	05/11/2025	Active	10088549

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
10088558	SKYTRAC SYSTEMS Ltd.		TCCA SA19-75	737-800 737-500 737-400	SkyTrac ISAT Airborne Position / Data Communicator Installation.	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Installation must be in accordance with Avionics Design Services Ltd.Master Drawing List MDL18079 Revision J Issue 1.Operation must be in accordance with SkyTrac Systems Ltd. FMS18079-1Revision C.Maintenance must be in accordance with SkyTrac Systems Ltd. Instructionsfor Continued Airworthiness ICA1...	This modification has not demonstrated compliance with PartCAT,CAT.GEN.MPA.205 for aircraft tracking systems.Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair will introducee...	05/11/2025	Active	10088558
10088570	AIRBUS S.A.S.	REV. 1		A350-941	Airbus STC solutions MOD AI0321 - Modify cabin configuration from DAL01to DAL02This MOD AI0321 modifies DAL01 layout toget DAL02 layout, where AirbusMOD 117660 installs DAL02 layout starting from green A/C.Rev. 1 to correct the issue of the MAS and to consider up issue of thecertification summary	The Type and OSD Certification Bases (CB) for the original productremains applicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval w...	STC Solutions certification summary reference: SRSA-24011 issue I dated07 November 2025.Modification Approval Sheet MASn° AI0321 issue 2Instructions for Continued Airworthiness as referenced in D25024578issue Bor later revisions of the above listed document(s) approved/ acceptedunder the EASA system...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	10/11/2025	Active	10088570
10088573	SCHULZ, ALEXANDER			SEE EASA APPROVED MODEL LIST	Installation of electronic basic flight instrument on gliders andMotorgliders	The Type and OSD Certification Bases for the original product remainsapplicable to this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the product are unchangedand remain applicable to this certificate/ approval witho...	Supplemental type certificate (STC): Installation of a LXNAV ADI 2 tosubstitute Altimeter and Airspeed indicator and OAT ind. InstallationInstruction, Issue 1, dated 19.10.2025Airplane Flight Manual supplement: Electronic Airspeed indicator +Altimeter LXNAV ADI2, Issue 1, dated 19.10.2025Or later re...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2025	Active	10088573
10088574	UNITY AVIATION CANADA Ltd.		TCCA STC SA07-122 ISSUE 2	DHC-6 SERIES 320 DHC-6 SERIES 310 DHC-6 SERIES 300 DHC-6 SERIES 210 DHC-6 SERIES 200 DHC-6 SERIES 110 DHC-6 SERIES 100	Installation of Wing and Outboard Fore Flap Trailing Edge Assemblies	The Type and OSD Certification Bases for the original product as amendedby the following additional or alternative airworthiness requirements:the following paragraph(s) at a lateramendment: CAR Part 3 dated May15, 1956, including Amendments 3-1 through 3-8, plus CAR 523.1529 atAmendment 523-8The re...	Installation of Wing and Outboard Fore Flap Trailing Edge Assembliesmust be in accordance with, Unity Aviation Canada Ltd. Modification DataSummary 050405-MDS-01, Revision 1 datedJune 10, 2013.Existing maintenance instructions for the DHC-6 are applicable to thisinstallationor later revisions of th...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	06/11/2025	Active	10088574
2003-428	GOODRICH CORPORATION		FAA ST00983SE-D	737-600/-700/-800/-900	Cockpit door surveillance system	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/or emissions levels of the product are unchanged andremain applicable to this certificate/ approval without any imp...	-Master Data List, D2003-073, Revision B, dated 22 October 2003-AFMS, D2003-148, Revision New, dated 4 September 2002-Instructions for Continued Airworthiness (ICAW), D2003-149, RevisionNew, dated 17 September 2003or later revisions of theabove listed document (s) approved/accepted onbehalf of EASAP...	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	23/10/2003	Active	10073156
2004-4159	ANCRA INTERNATIONAL LLC		FAA STC ST01536LA	737-300	Installation of Ancra's Cargo Handling System on Channel ExpressB737-300SF aircraft		ANCRA Drawing No. DL83734, dated 19 August 2003 Ref: JAA/04/50/27	None.	23/04/2004	Active	10043157

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
AAN NO. 26626	SENSENICH PROPELLER MANUFACTURIN GCOMPANY, Inc.		FAA STC SA616NE	F150L A150M A150L 150M 150L	The modification comprises a Sensenich 69CKS12, or M69CKS12propellerhaving adiameter in the range 67 to 69 inches, andpitch between 48 and 52inches. Themodification kit includesspinner assembly C-2326, and documentsincludinginstallationinstructions, and drawing no. A-1076.				07/08/1998	Active	10071760
EASA.A.S.00175	DASSAULT FALCON SERVICE			FALCON 20 EQUIPPED WITH COLLIN	Installation of modified cockpit controls, lods and panels iaw DFSChange Approval Sheet2385 Issue A dtd 15 July 05		-see Change approval sheet DFS 2385 Issue AAMM Supplement DF SIDE/5B F2 - Part 76-10-00 and associated list ofaffected technicaldocuments	I. This STC is applicable to Falcon 20 equipped with Collins Proline IVAvionics only2 .. This STC is approved only fOI the configUlation as defined in ModSheet DFS 2385 Issue A3. This S TC is approved only for the product configuration as definedin the approved designdata refelled to in the paragrap...	17/08/2005	Active	10043153
EASA.A.S.00182	DASSAULT FALCON SERVICE			FALCON 20 EQUIPPED WITH COLLIN	Deviation to STC EASA.IM.A.S.00237 (Rockwell Collins Proline IV DFSInstallation) iawChange approval sheet DFS2524 issueA dtd 15 July 05		-see Change approvalsheetDFS 2524 issue AAMM chapterS DFSIDE/5F2 AX and associated list of affected technicaldocuments	1. This STC is applicable to Falcon 20 equipped with Collins Proline IVAvionics only2. This STC is approved only for the configuration as defined in ModSheet DFS 2524 Issue A3. This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraph "...	17/08/2005	Active	10043152
EASA.A.S.00186	CRANFIELD AEROSPACE SOLUTIONS LIMIT		CAA UK RESPONSIBIL ITY	JETSTREAM 4100	Enabling of Traffic Collision Avoidance System II (TCAS II)inaccordance with Cranfield Aerospace Ltd. Document CA/ DD/R2122, issue Bdated June 2004 or later EASA approved revision. Flight ManualSupplement Cranfield Supplement No 1 to CAA approved Flight ManualDocument No. J41-01.			1. Subject to compliance with the provisions of Part 21 Subpart E, thisSTC and associated data shall remain valid untilsurrendered, withdrawnor otherwise terminated.2. If transfer of this certificate is requested under Part 21A.116, theSTC will be reissued.3. This STC is approved only for the produ...	07/10/2004	Active	10053567
EASA.A.S.00196	AIRBUS S.A.S.	REV. 1		A319-112	Cabin reconfiguration into an executive 44 pax, in accordance with the Modification Approval Sheet (MAS) Ref. SOG-00-830, issue 4, dated September 20, 2004			The Document Ref.: DIT/N/ 2004/1726/OS Revision B must be incorporated as a supplement to the Airplane Flight Manual (AFM)	02/07/2008	Active	10013925
EASA.A.S.00198	SOCIETE AIR FRANCE S.A.	REV. 1		BOEING 747-400	Air France B747-400 "ULYSSE" cabin reconfiguration. This isa revision to STC Ref EASA.A.S.00198, to extend the applicability to the aircraft B747-400 F-GITH MSN 32868, F-GITI MSN32869 and F-GEXA MSN 24154. The general description is included in the Air France Letter BL.NI 10 002/EB and in the AEO...			1.The approval of this modification is limited to the Boeing B747-400 MAS 24969, 24990, 25344, 25600, 25601, 25602, 32868, 32869, 32871, 25238, 25302, 25559, 25628, 25630, 24154, 24155. The limitations and conditions defined in the EASA Datasheet are applicable.2. A copy of this STC and of the CAS m...	19/10/2005	Active	10013926
EASA.A.S.00216	AERODATA AG		EASA.A.S. 00216	500, 550, 560	Installation of an AeroPhone Iridium Satcom System in accordance withMaster Drawing List Doc. No.: MDL-A/C-062 and Drawing List Doc. No.DL-A/ C-09, Rev. 0 (or later EASA approved revision).			1. Operations Instruction: Aero Data Flight Manual Supplement AFM-058,Rev. 02. Instruction for Continued Airworthiness Doc. No. HB-A/C-708, Rev. 023. Installation Instruction: Install and Testing Instruct. Doc. No.REP-A/C-1018, Rev. 014. This STC is approved only for the product configuration as def...	06/10/2004	Active	10077521

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00217	AERODATA AG			560	Installation of a TCAS 2000 in accordance with Master Drawing List Doc.No. MDL-A/C-081<(>,<)> Rev. 01 (or later EASA approved revision).			1- Operation Instruction: Aero Data Flight Manual Supplement AFM-071,Rev 02- Instruction for Continuous Airworthiness Doc. No AMM-758, Rev.03- Installation Instruction: Modification Order Doc. No. HB-A/C-7594- This STC is approved only forthe product configuration as defined inthe approved design d...	06/10/2004	Active	10043031
EASA.A.S.00218	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 560, 550 AND S550	Installation of ACAS 11 CAS 67A and Mode S XPDR MST67A as defined in JetAviation Engineering Order C550, -S550, -C560, report 2004-9 Rev A (orlater EASA approved revision).		Installation of ACAS 11 CAS 67A and Mode S XPDR MST67A as defined in JetAviation Engineering Order C550, -S550, -C560, report 2004-9 Rev A (orlater EASA approved revision).	Limitations and Conditions: 1,,Airplane Flight Manual Supplement Report 2004-9-8, Rev. A .2,,Instruction for Continuous Airworthiness Doc : Maintenance ManualSupplement Report 2004-9-10, Rev A.3,, Installation Instruction: Installation Procedure Report 2004-9-1,Rev A4 This STC is approved...	04/10/2004	Active	10051159
EASA.A.S.00220	MOTORFLUG BADEN-BADEN GmbH			F27 MK500	Installation of Trimble LNL 2101 I/O Approach Plus GPS in accordancewith E/O No. 114112 of the Fa. Aero Technic		AFM Supplement Document No. E/O 114112	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	20/10/2004	Active	10057636
EASA.A.S.00225	SOCIETE AIR FRANCE S.A.	REV. 2		BOEING 747-400	ISPSS Installation on B747-400 in accordance with MA.PM 263/03 rev 5 dated 22/09/2005		AMM Supplement MAPM 482/03PD rev 01 dated 28/01/05AFM Supplement to D6U10002-428 dated 01/09/04 and AFM Supplement D6U10002-4B3 dated 01/09/04	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph “Description”. Compatibility with other aircraft/ engineconfigurations shall be determined by installer.	20/02/2006	Active	10013927
EASA.A.S.00235	E A D AEROSPACE AIRWORTHINESS	REV. 1		A330-342, A330-343 A330-322, A330-323, A330-341 A330-302, A330-303, A330-321 A330-223, A330-243,A330-301 A330-201, A330-202, A330-203	This STC deals with the installation of Balise Emergency LocaterTransmitter (ELT) on A330. All documents related to this STC are listedin the Master Drawing List No. 00848-JAA-MDLRev. B dated 23/09/2004 orlater EASA approved revision.				05/04/2005	Active	10053574
EASA.A.S.00239	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		BEECH 400A	Installation of a EGPWS Mk. VIII system in accordance with the Engineering Order Doc.: 2017016-EO-02 Issue 2 or later EASA approvedrevision.			1. AFM Supplement Document No. 2017016-AM-02 Issue 2 orlater EASA approved revisions.2. Maintenance Requirements and Instruction for Continuous Airworthiness Doc. 2017016-CA-02.	15/02/2008	Active	10013928
EASA.A.S.00240	SCANDINAVIAN AVIONICS DESIGN ApS			BEECHJET 400A	Installation of an Artex ELT 406 in accordance with Engineering OrderDoc.: 20176016-EO-01 Issue 2 or later EASA approved revision.			1. AFM Supplement Document No. 2017016-AM-01 Issue 2 or later EASAapproved revisions. 2. Maintenance Requirements and Instruction for Continuous AirworthinessDoc. 20117016-CA-013. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragrap...	14/10/2004	Active	10053180

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00241	SCANDINAVIAN AVIONICS DESIGN ApS			BEECHJET 400A	Installation of a Rockwell Collins TCAS-4000incl. Dual Collins Mode-STransponder TDR-94 D in accordance with Engineering Order Doc.:2017016-EO-13, issue 2 or later EASA approved Revisions.			1. AFM Supplement Document No. 2017016-MM-03 Issue 2 or later EASAapproved revisions. 2. Maintenance Manual Supplement 2017016-MM-03/1 (ACAS).3. Maintenance Manual Supplement 2017016-MM-03/2 (XPDR)4. Instructions for Continuous Airworthiness Doc. 20117016-CA-03.5. This STC is approved only for the pr...	14/10/2004	Active	10053181
EASA.A.S.00243	LUFTHANSA TECHNIK AG			A340-600	Installation of a Patient Transport Compartment (PTC), having asCertification Basis JAR-25 Change 15 as defined in JAA TCDSJAA/25/92-0004 issue 33			This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	07/10/2004	Active	10070941
EASA.A.S.00265	E A D AEROSPACE AIRWORTHINESS	REV. 1		BOEING 737-500 BOEING 737-300, 737-400,	Installation of Honeywell EGPWS Mark V		EAD Master Drawing List ref. 00772-JAA-A-MDL revision GEAD AFM Supplement ref. DC113-0772-00 revision HEAD MPD Supplement ref. DC114-0772-00 revision Aor later EASA approved revisions of those documents	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	02/02/2009	Active	10013929
EASA.A.S.00278	AERODATA AG	REV. 2		B300	Flight Data Recorder (FDR) integration into Hawker Beechcraft King Air B300		Existing STC ref EASA.A.S. 00278 covers FDR and CVR (CockpitVoice Recorder) , this change to the STC covers integrationof the FDR only, (partial installation of STC EASA.A.S.00278) Installation, Operation and Continued airworthiness in accordance with:-Master Document List MDL-A/ C-080 Rev 1AFM supp...		19/10/2007	Active	10013931
EASA.A.S.00294	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		JETSTREAM 3100 & 3200 SERIES	Danish STC 27/2004 Rev. 1. Installation of 406 MHz Emergency LocatorTransmitter (ELT) in accordance with Scandinavian Avionics A/S TechnicalOrder No 021035, Rev. B, dated 23/09/04or later EASA approvedrevisions.			This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	31/01/2006	Active	10053182
EASA.A.S.00295	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		JETSTREAM 3100 & 3200 SERIES	Danish STC 28/2004 Rev.1. Installation of Class A Terrain AwarenessWarning System (TAWS) in accordance with Scandinavian Avionics A/STechnical Order No. 021033, Rev. B dated 23/09/04 or later EASA approvedrevision.			1. This Danish STC 28/2004 Rev. 1 is valid for installationof HoneywellEGPWS Mk. VIII system with internal GPS card P/N: 965-1186-0062. This STC is approved only for the product configuration as defined inthe approved design data referredto in the paragraph "Description".Compatibility with other a...	31/01/2006	Active	10053183
EASA.A.S.00305	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE	REV. 1		CITATION 550	- Installation of Digital Data Recorder SSUFDR Allied Signal (TSO-C124) in accordance with Master Data List No. UAE.011.02 Issue0 dated 16 August 2004, or later EASA approved Revision.- Installation of a Digital Flight Data Recorder.Note: Revision 1 of STC EASA.A.S.00305.		UAE 011 02 ED 3 Rev 7	1. AFM Supplement UAE No. 46 Revision 0 dated 16 August 2004 or later EASA approved revision is a required part of this STC.2. This STC is approved only for the product configuration as defined in the approved design data referred toin the paragraph "Description". Compatibility with other air...	06/02/2009	Active	10013932

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00318	MADELEC AERO S.A.S.	REV 2		FOKKER F.28 MARK 0070	Installation of photoluminescent Floor Proximity Emergency Escape Path Marking system		AFM Supplement FMS-9802Maintenance information provided in MPS-9802Dispatch deviation procedure provided in MES-9802	1. Photoluminescent system charge time: 10 minutes.2. Photoluminescent Tape life time: 8 years.3. MSN 11290-11296-11323-113294. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraf...	08/03/2006	Active	10013933
EASA.A.S.00334	CESSNA CITATION EUROPEAN SERVICECENTER (CCESC)	REV. 1		CESSNA 525	Installation of a Skywatch HP SKY899A TCAS I coupled to a Honeywell KMD-850 MFD, in accordance with Cessna Citation European Service Center FAM Ref.: 111, Rev NC. Dated 14 August 2007 and FAM ref 82, Rev 01, dated 22 October 2004 or later approved revision.Note: This revision is issued to indicate t...		The Airplane Flight Manual Supplements (AFMS) Ref. FM90598 Rev A and CCESC FM 82 Rev A, dated 27th August 2007 or laterEASA approved revisions, are required on board for operating the aircraft.The Instructions for Continued Airworthiness Ref CMR-525-117 Rev. A, dated 7th August 2007 or later EASA a...	1. Applicability: Cessna 525 MSN 525-001 to 359 includedequipped with Honeywell WX RS-811A and FMS GNS-XLS.	30/08/2007	Active	10013934
EASA.A.S.00339	EAD AEROSPACE	REV. 3		737	Installation of an elementary surveillance / enhanced surveillance ATCtransponder system. This STC supersedes the STC EASA.A.S.00339 Revision2		-EAD Master Drawing List reference 00845-JAA-A-MDL revisionD (or laterEASA approved revision)-AFM Supplement, EAD document reference DC107-0845-00 revision B (orlater EASA approved revision)	1. This STC is only limited to configurations 1, 2 and 4 (as describedin the EAD Supplemental Type Design Definition document reference DC102-00845-00 revision C § 3.32. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Descri...	03/11/2005	Active	10056723
EASA.A.S.0034	SOGERMA SERVICES	REV. 1		AIRBUS A310-304	Aircraft modification for 8.33 kHz spacing on VHF system inaccordance with Modification Approval Sheet SOG 23-878 Issue 1 dated 01July 2004 or later EASA-approved revision.Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.				07/01/2008	Active	10013935
EASA.A.S.00347	AIRBUS S.A.S.	REV. 1		A330-203	VIP Cabin Installation		All documents related to this STC are listed in the Master Data List Drawing No MDL-01-502 Issue A (or later EASA-approved revision).	1. The approval of this modification is limited to the Airbus A330-203 MSN 487 which is used as a private aircraft. The limitations and conditions defined in the EASA Datasheetare applicable. A copy of this STC and of the MDL, AFM mustbe enclosed in the fileof the modified aircraft. Any alterat...	04/07/2008	Active	10013936
EASA.A.S.00348	AIRBUS S.A.S.	REV. 1		A330-203	Installation of a SATCOM Live TV system.		All documents related to this STC are listed in the Master Data List Drawing No. MDL-01-580 Issue A. (or later EASA-approved revision).	1. The approval of this modification is limited to the AIRBUS A330-203 MSN 487. The limitations and conditions defined in the EASA Datasheet are applicable. A copy of this STC and of the MDL, AFM must be enclosed in the file of the modified aircraft. Any alteration of the STC definition must be m...	04/07/2008	Active	10013937
EASA.A.S.00352	SEFA	REV. 1		BEECH B200	- Installation of calibration workbench ref. STNA "Margouillat1" according to the 02-1104-DIR document.- Installation of calibration workbench ref. STNA "Margouillat1".Revision 1: Extension of STC EASA.A.S.00352 with a minor change to another aircraft (F-GJFE s/n BB1399).		- Aircraft Flight Manual Supplement ref 02-1104-DIR dated November 2002 or later approved revisions.- 02-1104-DIRREV 1	1. Applicable only for F-GJFA s/n BB-1270, F-GJFC s/n BB-1347 and F-GJFE s/n BB1399 aircraft.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse...	16/02/2009	Active	10013938

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00357	AERO ENGINEERING DESIGN Ltd		CAA UK RESPONSIBILITY	172	Introduction of Dual Image Capture System AED Design ModificationCertificate 25-79-419Issue I dated October 12, 2004 orlater EASA-approved revision			1. Subject to compliance with the provisions of Part 21 Subpart E, thisSTC and associated data shall remain valid untilsurrendered, withdrawnor otherwise terminated.2. If transfer of this Certificate is requested under Part 21A.116, theSTc will be reissued.3. This STC is approved only for the produ...	07/12/2004	Active	10048032
EASA.A.S.00375	SOCIETE AIR FRANCE S.A.	REV. 1		AIRBUS A319-115	A319 CJ CASTA II Cabin Reconfiguration		Change Approval Sheet CAS-A320-04-002 rev 01 dated February1, 2005Air France Industries Airplane Flight Manual Supplement (AFM-S) ref.: "Government of France, F-RBFA / F-RBFB", Revision 02, dated February 1, 2005, or later EASA-approved revision	1. This STC is limited to the A319-115 CJ MSN's 1485 and15562. This STC is approved only for the product configuration as defined in the approved design data referred to inthe paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installe...	18/10/2005	Active	10013939
EASA.A.S.00376	EADS SOGERMA	REV 1		AIRBUS A310-304	Royal Jordanian ATC Mode S Enhanced Surveillance installation according to EADS Sogerma Modification Approval Sheet SOG-34-974 issue 3 dated 29 November 2004.Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.			1. The Aircraft Flight Manual Supplement No AFM-34-974 issue B dated 29 November 2004, or later EASA-approved revision, is a required part of this STC.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other p...	07/01/2008	Active	10013940
EASA.A.S.00377	EADS SOGERMA	REV 1		AIRBUS 310-325	Cabin Modification from 18F/C-180Y/C to 18B/C-188Y/C according to the modification approval sheet MAS No SOG-25-957 issue 1 dated 6October 2004 or later EASA-approved revision.Note: This revision reflects the transfer of this STC from EADSSogerma Services to Sogerma Services.			Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	07/01/2008	Active	10013941
EASA.A.S.00378	ELECTRONIQUE MAINTENANCE AVIATION	REV. 1		FAIRCHILD SWEARINGEN SA 226-T(	- Installation of VHF 8.33 KHz/VOR/ILS/ GPS/STORMSCOPE/VHF 150 MHz/ UHF/ICS Passengers according to E.M.A. Modification Approval Sheet (FAM) No EMA/03/002/SA226Serie/ VHF.GPSBRNAV.STORM.UHF dated 22 December 2003.- Installation of GARMIN GNS 530A, STORMSCOPE WX500 and UHF TRT TRA-AP-137 to replac...		- 03/002/ SA226Serie/...R1- Flight Manual Supplement- Air flight test by CEV ISTRES	1. This modification is applicable only to SA 226 T(B) s/n T298 F-GLPT.2. EASA Approved Airplane Flight Manual Supplements "Supplément au manuel de vol GPS BRNAV" are required.3. This STC is approved only for the product configuration as defined in the approved design data referred to in th...	05/02/2009	Active	10013942
EASA.A.S.00382	LUFTHANSA TECHNIK AG	REV 1		AIRBUS A340-300	Installation of Antenna and Receiver Transmit System and Network Services (acc.: STDD 00-03/11M issue 02)		AFM Supplement: A-00-04/072-AFMICA: R-00-04/023	1. "The IEEE 802.11 a, b, g (as customized) Wireless Local Area Network (WLAN) introduced by this modification, may be activated onboard Airbus A340-600 Aircraft for operation with commercial IEEE 802.11a, b, g & h compliant WLAN enabled portable electronic devices only, as supported by Lufthansa Te...	15/11/2005	Active	10013943
EASA.A.S.00384	SCANDINAVIAN AVIONICS DESIGN ApS			BAE 125 SERIES 800B	Installation of an Universal CVR-30B Cockpit Voice Recorderin accordance with the Engineering Order Doc: 2022468-EO-01, Issue 1 orlater EASA-approved Revisions. AFM Supplement Document No 2022468-AM-01 Issue 1 or later EASA-approved Revisions. Maintenance Requirements and Instruction for Continuous...			1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	07/12/2004	Active	10013944

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00386	LUFTHANSA TECHNIK AG			A330-300	Installation of a Passenger Transport Compartment (PTC)		STDD 25-04/23 M issue 00CRL 25-04/23 M	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	07/12/2004	Active	10070939
EASA.A.S.00388	LUFTHANSA TECHNIK AG	REV. 1		A330-300	Installation of Antenna and Receive Transmit System and Network Services		- Supplemental Type Definition Document: STDD00-04/14M, Issue 03- Compliance Record List: CRL00-04/ 14, Issue 2- Airplane Flight Manual Supplement: A-00-04/5856-AFM- Instructions for Continued Airworthiness: R-00-04/4829 related toAirbus Doc: AI/SE-M4/95A.0089/97 Supplement	1. The IEEE 802.11 a,b,g (as customized) Wireless Local Area Network(WLAN) introduced by this modification, may be activated on board AirbusA330-300 Aircraft for operation with commercial IEEE 802.11 a,b,g & hcompliant WLAN enabled portable electronic devices only<(>,<)> assupported by Lufthansa Tec...	01/03/2005	Active	10063407
EASA.A.S.00405	SOCIETE AIR FRANCE S.A.	REV 1		BOEING 777-200-228-300	RAAS (Runway Awareness and Advisory System) activation. AirFrance AEO 77-34-0051 rev. 2 dated November 24, 2004CAS-B777-05-19 rev 0 dated 29 June 2006 (or later approved issue)RAAS Activation on B777-200/-300 Air France aircraftNote: Thismodification extends the existing approval under EASA STC EA...		D631W001 Rev 01 for B777-200D631W002 Rev 01 for B777-300	1. See AFM limitations for options to be used.2. Applicable to a/c serial numbers listed in Air France CAS-B777-05-0192. This STC is approved only for the product configuration as defined in the approved design data referred to inthe paragraph "Description". Compatibility with other aircra...	13/07/2006	Active	10013947
EASA.A.S.00411	VITROCISET S.p.A.	REV. 2		500, 550 SERIES	Installation of Honeywell EGPWS. Revision of EASA.A.S.00411due toextension applicability.Note: This STC supersedes EASA.A.S.00411 Revision 1.		Master Drawing List DRW No 700-1004-000-000 Rev. 1, dated 23December2004.	none	07/01/2009	Active	10043091
EASA.A.S.00412	VITROCISET S.p.A.	REV. 2		500, 550 SERIES	Honeywell ART 2000/2100 Radar System Installation. RevisionofEASA.A.S.00412 due to extension of applicability.Note: This STC supersedes EASA.A.S.00412 Revision 1.		Master Drawing List DRW No 400-0804-000-000 Rev. 1 dated 23/12/2004 andsubsequent approved revision.	none	07/01/2009	Active	10043092
EASA.A.S.00413	VITROCISET S.p.A.	REV. 2		500, 550 SERIES	Traffic Collision Avoidance System (TCAS II) Installation. Revision ofEASA.A.S.00413 due to extension of applicability.Note: This STC supersedes EASA.A.S.00413 Revision 1.		Master Drawing List DRW No 600-0904-000-000 rev. 1 dated 23/12/2004 andsubsequent approved revision.	none	07/01/2009	Active	10043093
EASA.A.S.00419	AVIATION TRADERS LIMITED	REV. 1	CAA UK RESPONSIBILITY		Modification ATL/CPT/M138 Issue 1 dated 29/11/2004, Business ClassDouble Seat p/n C2C207555()16()40IN		ATL DDP 503 Issue 2 dated 29/11/2004 or later EASA approvedrevision	1. Subject to compliance with the provisions of Part 21 Subpart E, thisSTC and associated data shall remain valid untilsurrendered, withdrawnor otherwise terminated.2. If transfer of this Certificate is requested under Part 21A.116, theSTC will be reissued. This modification does not include approv...	05/01/2005	Active	10063404
EASA.A.S.00421	GRAFAIR AB	REV. 1		CESSNA S550 CESSNA 550	Installation of an Allied Signal Corporation CAS-67A Traffic Alert and Collision Avoidance System (TCAS II). Technical Documentation Associated: - FAA STC ST00116BO. - Pro Star Aviation, Master Document List No 0100-MDL-02, Revision A, dated February 1, 2001, or later FAA-approved revision.			1. Pro Star Aviation Aircraft Flight Manual Supplement No 0100-FMS-02 for the Cessna Aircraft Company, Models 550, S550and 560, Revision A, FAA-approved March 8, 2001, or later FAA-approved revision, is required with this modification. 2. This approval is valid for Cessna 550, S/N 0302 and Cessna S5...	03/11/2005	Active	10013948

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00426	MADELEC AERO S.A.S.	REV 3		AIRBUS A319-320-321	Replacement of the powered floor proximity emergency escapepath marking system by a FPEEPM photoluminescent system		Certification Document List (CDL) ref.-9908, Issue of February 20, 2006Airplane Flight Manual Supplement, ref. FMS-9908, Issue 4, dated February 27, 2006Master Mimimum Equipment List Supplement, ref. MES-9908, Issue 3, dated February 27, 2006	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	31/03/2006	Active	10013949
EASA.A.S.00428	LUFTHANSA TECHNIK AG			A340-600	Installation of a system for measurement of atmospheric components		-Certification basis as defined in Type Certification Data SheetJAA/25/92-0004, Issue 30.-Supplemental Type Definition Document STD00-03/01M, Issue 01, Rev. 00,30 November 2004-Supplemental Maintenance Requirements as referenced in document"Instructions for Continued Airworthiness" Doc. NO. CS53-015...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	20/12/2004	Active	10070942
EASA.A.S.00432	EADS SOGERMA	REV 1		AIRBUS 310-325	Modification of ATLAS/KSSU galleys into full ATLAS standardin accordance with Modification Approval Sheet reference SOG-25-958 Issue 01 dated 14 October 2004. All documents related to this STC are listed in the Master Drawing List reference MDL-25-958 Issue B orlaterNote: This revision reflects the...			Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	07/01/2008	Active	10013950
EASA.A.S.00438	SCANDINAVIAN AVIONICS DESIGN GMBH	REV. 1		222	Installation of ELT type Kannad 406 AF / AF-H. Reuse or exchange ofantenna		-System Description 2019313-DE-01 issue 4, 11/03/2004-Technical Order 1019313-TO01 rev. B, 06/02/2003-Drawing List 2019313-DI-01 issue 2, 11/03/2004or later EASA approved revision	1. This STC assumes that an existing antenna can be reused,or that anexchange of the antenna may be done without exchanging the doubler. 2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".compatibility with othe...	31/01/2006	Active	10053184
EASA.A.S.00439	E.I.S.A.	REV 1		CESSNA 551	Installation of two Rockwell / Collins TDR 94D instead of two TDR 90 according to FDM EISA 05FDM F055 rev. 4 dated November 2004 and associated documents.New transponder location			1. Compatibility of this modification with other previouslyapproved modifications must be determined by the installer.2. Applicability Cessna 551 S/N 551-0133 and S/N CE551-0174.3. EASA approved Airplane Flight Manual Supplement, dated 23November 2004 is required. 4. This STC is approved only for t...	30/10/2006	Orphaned	10013951
EASA.A.S.00451	ATS INTERNATIONAL	REV 1		DC-9-80 (MD-80) SERIES	Mk VII EGPWS System Installation		Master Data List, ref. 0197-01-A-2103 revision 08, dated January 25, 2006 or later EASA approved revision.Airplane Flight Manual Supplement, ref. 0197-01-A-2301 revision 03, datedMay 16, 2005 or later EASA approved revision.Airplane Flight Manual Supplement, ref. 0197-01-B-2301 revision 00, dated A...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	21/03/2006	Active	10013952

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00456	SCANDINAVIAN AVIONICS DESIGN GMBH	REV. 1		DHC-7-110/-111 DHC-7-100/-101/-102/-103	Installation of VDL Mode 4 Transponder		Engineering Order 2015555-EO-02 Issue 3 dated 29/10/04 or laterrevisions of the above listed documents approved by EASA.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevoke...	31/01/2006	Active	10053185
EASA.A.S.00463	AIR AMBULANCE TECHNOLOGY GmbH	REV. 1		DORNIER 328-300 DORNIER 328-100	Installation of Air Ambulance Equipment, VIP interior		AR 11199I.Component-, Installation-, Operation-Manual, illustrated Part CatalogAir AmbulanceEquipment "quick conversion" PIN 10.000 Dornier 328:Non intensive Care Station RH and LH/S CMM-D0328-AAT6Non Intensive Care Station LH CMM-D0328"AAT9Intensive Care Station CMM-D0328-AAT7Oxygen-lAir Station C...	1. Subject to compliance with the provisions ofEC 1702/2003PART 21Subpart E, thisCertificate and associated data shallremain valid until surrendered,withdrawn or otherterminated.2. This STC is approved only for the product configuration as defined inthe approved designdata referred to in the parag...	21/04/2005	Active	10042957
EASA.A.S.00466	AIR AMBULANCE TECHNOLOGY GmbH	REV. 1		JETSTREAM 3200 SERIES JETSTREAM 3100 SERIES	Installation of Air Ambulance Equipment		AR 15/011. Component-, Installation~, Operation-Manual, illustrated PartCatalogAir Ambulance Equipment JETSRTEAM 31/32"quick conversion" PINJ31-25-24-23.000CMM-J31-AAT352. Airplane Flight Manual JETSTREAM 31/32 Supplemental Air AmbulanceEquipment PINJ31-25-24-23.000, AFM-AAT 23	1. Compatibility of this installation with previous installed equipmentmust be determined by the installer.2. Subject to compliance with the provisions of EC 170212003 PART 21Subpart E, thisCertificate and associated data shall remain valid until surrendered,withdrawn or otherterminated.3. This STCt...	21/04/2005	Active	10042958
EASA.A.S.00473	MOTORFLUG BADEN-BADEN GmbH			F27 MK500	Installation of Honeywell EGPWS Mk VI/ Mk VII		-AFM Supplement: F27-122105-0601-Installation Manual: F27-122105-1001-Instructions for Continued Airworthiness: F27-122105-0701	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	05/01/2005	Active	10057637
EASA.A.S.00493	TROYES AVIATION S.A.R.L.	REV. 2		CESSNA F177-RG	Installation of sliding panel on the front left and right door windows amd rear right window.Addition of new S/N 087 F-BURU on STC EASA.A.S.00493.		Minor Change No. 52.Major Change No. 42 approved under EASASTC EASA.A.S.00493 Revision 1.Flight Manual Supplement No. 42, Revision 2, 5 January 2008.Compliance Statement dated 5January 2008.	Limited to F177RG S/N 0112, 0065 and S/N 087 F-BURU.	28/02/2008	Active	10013953
EASA.A.S.00495	VITROCISET S.p.A.	REV. 1		F27	"Radar System Replacement with bendix ART 2000 System" No 03/03.Note: This STC supersedes EASA.A.S.00495.		- Doc No 400-0303-000-000 Master Drawing List rev. 3 dated 10.11.2004.- AFM Supplement No 400-0303-800-000 Rev. 3 dated18.10.2004.	none	07/01/2009	Active	10043094
EASA.A.S.00496	VITROCISET S.p.A.	REV. 1		F27	"MK II GPWS replacement with MK VIII EGPWS" No 04-03.Note: This STC supersedes EASA.A.S.00496.		- Doc. No 700-0403-000-000 Master Drawing list rev. 3 dated10.11.2004.- AFM Supplement No 700-0403-800-000 rev. 3 dated 18.10.2004.	none	07/01/2009	Active	10043095

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00502	ATS INTERNATIONAL	REV. 1		737-300, 737-400, 737-500	Installation of Honeywell EGPWS Mark VThis STC supersedes and replaces the DGAC STC No F-CIM135-SF-0708		-ATS International Master Data List No 0124-01-2103-R13-Configuration 1 (EGPWS with internal GPS): ATS International AFMSupplement No 0124-01-A-2301-R03-Configuration 2 (EGPWS with FMS): ATS International AFM Supplement No0124-01-R-2301-R02-Airworthiness Limitations as described in the ATS Internati...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	24/01/2005	Active	10042995
EASA.A.S.00505	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (CL-601 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Upgrade Dual Honeywell FMS NZ-2000-PRNAV.		- Master Document List 100A-MDL, Airplane Flight Manual Supplement 100A-AFMS, Continued Airworthiness Plan 100-CAWP	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	12/01/2005	Active	10013955
EASA.A.S.00506	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (CL-601 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Mode-S Transmitter Collins TDR 94D upgrade - ELS/EHS; Associated Technical Documentation: Master Document List 100C-MDL, Airplane Flight Manual Supplement 100C-AFMS, Continued Airworthiness Plan 100C-CAWP		- Master Document List 100C-MDL, Airplane Flight Manual Supplement 100C-AFMS, Continued Airworthiness Plan 100C-CAWP	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	12/01/2005	Active	10013956
EASA.A.S.00510	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK	REV. 2	CAA UK RESPONSIBILITY	FALCON 20 SERIES D,E AND BASIC	Installation of ProLine IV Integrated Avionics Suite		Master Document List MDL 1001FRAH/FM/0100 to DTM918, or later approved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	23/02/2006	Active	10043096
EASA.A.S.00516	ACC COLUMBIA Jet Service GmbH	REV. 2		CL-600-2B16 (604 VARIANT)	Installation of an Artex ELT C406-1.	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	Master Document List CL604-40163-000-S-LP.	Prior to installation of this change/repair it must be determined thatthe interrelationship between this change/repair and any otherpreviously installed change and/ or repair willintroduce no adverseeffect upon the airworthiness of the product.	19/01/2005	Active	10013958
EASA.A.S.00517	SCANDINAVIAN AVIONICS DESIGN GMBH			JETSTREAM SERIES 3200 JETSTREAM SERIES 3100	Installation of Honeywell CAS 67A ACAS with dual MST 67A Mode STransponder		- Engineering Order 2017230-EO-01 Issue 3-Airplane Flight Manual Doc. 2017230-AM-01 (ACAS System),Issue 2- Airplane Flight Manual Doc. 2017230-AM-02 (Mode S),Issue 2- Instruction for Continuous Airworthiness Doc.2017230-CA-01, Issue 1 orlater approved revisions	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	19/01/2005	Active	10053572
EASA.A.S.00545	MOTORFLUG BADEN-BADEN GmbH			550	Installation of Honeywell (Bendix/King) RDR 2000 Color Weather RadarSystem in exchange with a previously installed Weather Radar System.		Document No. C550-05. Operating Instruction Doc. No. C550-05-601, datedSeptember 29, 2004 or later EASA approved revision.Instructions for Continued Airworthiness Doc. C550-05-0701	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	27/01/2005	Active	10057638

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00555	LUFTHANSA TECHNIK AG			A340-300	Cabin refurbishment with installation of New Business-ClassSeats		STDD 00-0417M iss. 01CRL 00-04/17M	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	25/01/2005	Active	10070940
EASA.A.S.00576	SCANDINAVIAN AVIONICS DESIGN GMBH	REV. 2		S/N 260 AND ONWARDS CESSNA 500, 550, S550, 550 BRAVO, 560, AND 560	Installation of Honeywell CAS 67A ACAS System including Dual MST 67AMode-S Transponders		- EASA SIC EAS.A.S. 0576RI- Approved Aircraft Flight Manual Supplement for Honeywell CAS 67A ACASII System<(>,<)>Doc. 2019992-AM-04, Issue 2, dated Sept. 2005- Approved Aircraft Flight Manual Supplement for Honeywell MST 67A ModeS Transponderwith PS 578A Control, Doc. 201 9992-AM-02, Issue, dated Sep...	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	24/01/2006	Active	10053187
EASA.A.S.00577	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			LEARJET 35A	Installation of Honeywell ACAS II CAS 67A and Mode-S XPDR MST 67A		Installation of Honeywell ACAS II CAS 67A and Mode-S XPDR MST 67A	Associated Technical Documentation:-Engineering Order Report 2004-6, Rev. B, 03 December 2004<(>,<)>- AFMS Report 2004-6-8 rev. A, 18 October 2004Limitations and Conditions:1. Certification basis refer to FAA TCDS A10CE plus JAA TGL No. 8 andJAA TGL No. 132. This STC is approved only for the producttt...	09/02/2005	Active	10051158
EASA.A.S.00578	MT-PROPELLER ENTWICKLUNG GmbH			152, A152, F152, FA152	Installation of Propeller MT 183 R115-2C or, Sensenich 72CKS6-0-56 or,Sensenich 72CKS6-0-54 in combination with silencer system LieseR74x8x100.		-Instructions for Continued Airworthiness and Installation InstructionsNo. E-1124-Airplane Flight Manual Supplement No.E-1123	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	09/02/2005	Active	10068197
EASA.A.S.00589	MOTORFLUG BADEN-BADEN GmbH			550, 560	Installation of Honeywell CAS-67A ACAS II and Dual MST 67A Mode STransponder by addition		-Document defing modification: E/O C550-02-0101-Airplane Flight Manual Supplement for Cessna 550/550 Bravo / 560 SeriesDoc. No. C550-02-601, Rev. 2, or later EASA approved revisions-Instructions for Continued Airworthiness: Doc. No. C550-02-701, Rev. 1or later approved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	18/07/2005	Active	10057639
EASA.A.S.00599	SCANDINAVIAN AVIONICS DESIGN GMBH			P210N	Installation of Stormscope WX-500		EASA approved Airplane Flight Manual Supplement, Doc. No. 2016188-AM-01,issue 2 or later EASA approved issue.	This STC is approved only for the product configuration as defined inthe approved design data referred to the paragraph"Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	02/03/2005	Active	10053188
EASA.A.S.00609	SCANDINAVIAN AVIONICS DESIGN GMBH			DORNIER 228-100/-200 SERIES	Installation of Honeywell EGPWS Mk VI, KMD 850 Multifunction Display andRDR2000 Weather Radar.		AFM Supplement 2021714-AM-01 Issue 2 or later approved revisionAFM Supplement 2021714-AM-02 Issue 3 or later approved revisionContinued Airworthiness Instructions 2021714-CA-01	This STC is approved only for the product configuration as defined inthe approved design data referred to the paragraph"Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	01/03/2005	Active	10053189

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.0061	VITROCISET S.p.A.	REV. 1		F27	STC No. 02/04; Electronic flight Instrument System (EFI 550) andVertical Gyros Installation.Note: This STC supersedes EASA.A.S.0061.		none	1.,,Instruction for Continued Airworthiness 400-0204-600-000 Rev.IRdated 30.04.2004Aircraft Flight Manual Supplement No. 400-0204-800-000 Rev. IR dated30.04.20042.,,This STC is approved only for the product configuration as definedin the approved design data referred to in the paragraph “Description”...	07/01/2009	Active	10043097
EASA.A.S.00610	MOTORFLUG BADEN-BADEN GmbH			SOCATA TB 20	Installation of Transponder Garmin GTX 330 - Mode S		-AFM Supplement TB 20-01-0601 AFM Supplemnet TB 20-01-0602-Instructions for Continued Airworthiness TB 20-01-0701	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	01/03/2005	Active	10013959
EASA.A.S.00645	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			LEARJET 55	Installation of Honeywell ACAS II CAS 67A and Mode S XPDR MST 67A		-Engineering Order Report 2004-5, Rev B, dated 3 December 2004-AFMS Report 2004-5-8, Rev A dated 20 October 2004	1. FAA TCDS A10CE plus JAA TGL No 8 and JAA TGL No 13 apply2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	17/05/2005	Active	10013961
EASA.A.S.00646	AVIONIK STRAUBING ENTWICKLUNGS GmbH	REV. 1		B. 501, 551 A. 500, 550	Installation of single/dual Garmin GTX330D.		1. Installation in accordance with ASR-2007-079-IFI-10-00 and STC MDL ASR-2007-079-MDL-01-02, or later approved Revisions;2. To be operated in accordance with Avionik Straubing Airplane Flight Manual Supplement Doc-No. ASR-2007-079-FMS-05.1.00 ASR-2007-079-FMS-05.2.00 or ASR-2007-079-FMS-05.3....	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.The installation of this modification by third persons i...	17/06/2008	Active	10013962
EASA.A.S.00659	ZOREX S.A	REV. 1		FAIRCHILD SWEARINGEN SA 226-TC	COMM/NAV/GPS Garmin GNS430 Installation, for B-RNAV Operation, and COMM Bendix King KY196A Installation, both for 8.33 kHz standard.		- Doc "Programa de Certificatión. Instalación Equipo COMM/NAV/GPS Garmin GNS430, e instalación Equipo Comunicaciones KY196A", Edición 1.Installation Instructions in accordance with:- Anexo 3 al programa de certificación "Descripción delMontaje", Edición inicial.- Garmin Installation Manual 1...	1. The aircraft is approved for dual pilot B-RNAV operation, subjected to the conditions, limitations and procedurescontained in: . Anexo 8 al Programa de Certificación "Aircraft Flight Manual Supplement", Ed. inicial.2. This STC isapproved only for the product configuration as defined in th...	25/04/2006	Active	10013965
EASA.A.S.00675	AERO ENGINEERING DESIGN LIMITED		CAA UK RESPONSIBIL ITY	757-200	Introduction of Enhanced Mode S Transponder System		Design Modification Certificate 34-15-199, Issue New, 06 October 2004 orlater EASA approved Revision. AFM Supplement AED/B757/003, issue 1, orlater EASA approved Revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	07/04/2005	Active	10070928

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00685	AIRBUS S.A.S.	REV. 1		A321-231	VIP cabin modification in accordance with Modification Approval Sheet (MAS) ref. SOG-792 issue 1, dated March 31st, 2005		Airplane Flight Manual Supplemet (AFM-S) ref. DIT/BC/1202/397/03 issue 1, dated January 18, 2005.Master Minimum Equipment List Supplement (MMEL-S) ref. "01-26 P5", "01-26 P5A", "02-26 P1", "01-33 P5", "01-33 P6", "01-35 P3", "01-52 P7", "02-52 P1".	This STC is limited to A321-231 MSN 1202	04/06/2008	Active	10013966
EASA.A.S.0069	SCANDINAVIAN AVIONICS DESIGN GMBH	REV. 1		HAWKER 800XP BAE 125-800B	Installation of an L3 digital FDR F-1000 in accordance withtheEngineering Order Doc.:2021094-EO-01, Issue 2 or later EASA approved Revisions.AFM Supplement Document No 2021094-AM-02 Issue 2 or later EASA approvedRevisions.Maintenance Requirements and Instructions for Continuous AirworthinessDoc. 20...			This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	07/12/2004	Active	10053193
EASA.A.S.00717	DASSAULT FALCON SERVICE			MF 20GF S/N 397	Installation of a 2nd Air Data System		-see Change approval sheet DFS 2474:AFM supplement MF 20 GFN 35 to DIM 30010 and associated list ofaffected technicaldocuments	1 Applicable only to MF 20 SIN 3972. This STC is approved only for the configuration as defined in ModSheet DFS 24741 This STC is approved only for the product configuration as defined inthe approved designdata refeHed to in the paragraph "Description" Compatibility with otheraitcraft/engineconfigur...	17/08/2005	Active	10043156
EASA.A.S.00731	AIR AMBULANCE TECHNOLOGY GmbH			55 / 60	Installation of Air Ambulance Equipment		AR 17/001. Component, installation, operation manual, illustrated part catalogAir Ambulance Equipment Learjet 60 "quickconversion" P/ NLJ60-25-20-20.000, CMM-L60-AAT28, CMM-LJ60_AAT29.2. Airplane Flight Manual Learjet 60 Supplement, Air Ambulance EquipmentP/N LJ60-25-20-20.000, AFM-AT17	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	17/05/2005	Active	10042959
EASA.A.S.00734	AIR AMBULANCE TECHNOLOGY GmbH			550, 560	Installation of Air Ambulance Equipment		AR 12/991. Component, Installation, Operation Manual, illustrated Part CatalogAir Ambulance Equipment CITATION BRAVO "quick conversion" P/N550-25-24-19.000, CMM-CIT-AAT36 CITATIONV and ultra "quick conversion"P/N 560-25-24-16.000, CMM-CIT-AAT172. Airplane Flight Manual CITATION BRAVO Supplement Air...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevok...	31/05/2005	Active	10042961
EASA.A.S.00735	AIR AMBULANCE TECHNOLOGY GmbH			1900D			AR 11/991. Component, Installation, Operation Manual, illustrated Part CatalogAir Ambulance Equipment "quick conversion" P/N 10.000 Beech 1900D AirAmbulance Equipment P/N 1900D-25-20-10.000-601, CMM-BEECH-AAT432. Airplane Flight Manual Beech 1900D Supplement Air Ambulance "quickconversion" P/N 1900D...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevok...	31/05/2005	Active	10042962

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00738	ELECTRONIQUE MAINTENANCE AVIATION	REV. 1		FAIRCHILD SWEARINGEN SA 226-T(	Installation of GPS BRNAV, EGPWS, TAS, Stormscope, Radar, MFD- Garmin GNS 530 VHF.NAV.GPS, Honeywell RDR 2000 Radar, BFGoodrich WX 500 Stormscope and Avidyne EX 500 MDF installation- BF Goodrich Sky 899 TAS and Honeywell KGP 560 EGPWS provision		AFM Supplement:“Supplément au Manuel de Vol GPS BRNAV EMA/05/002/ SA226/ GPS.BRNAV.EGPWS.TAS. STORM.RDR.MFD Rev. 1Avion No. T312, F-GRNT“	1. This STC is limited to MSN T312 F-GRNT2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	20/02/2006	Active	10013968
EASA.A.S.0074	SCANDINAVIAN AVIONICS DESIGN GMBH	REV. 1		HAWKER 800 XP BAE 125-800B	Installation of a Kannad 406 AF ELT in accordance with the EngineeringOrder Doc.: 2021390-EO-01, Issue 2 or later EASA approved revisionsAFM Supplement Document No. 2021390-AM-02,Issue 2 or later EASAapproved revisionsMaintenance Requirements and Instructions for Airworthiness Doc.: 2021390-CA-01			This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	07/12/2004	Active	10053196
EASA.A.S.00747	SCANDINAVIAN AVIONICS DESIGN GMBH			MU 2B-40	Installation of Avionics Alteration in Mitsubishi MU 2B-40		EASA approved Flight Manual Supplements2019747-AM-01, Issue32019747-AM-02, Issue 32019747-AM-03, Issue 32019747-AM-04,Issue 32019747-AM-05, Issue 22019747-AM-06, Issue 32019747-AM-07, Issue 32019747-AM-09, Issue 22019747-AM-10, Issue 22019747-AM-11, Issue 2or later EASA approved issues-Maintenance...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	31/05/2005	Active	10053195
EASA.A.S.00760	VITROCISET S.p.A.			F27 MK 500	Traffic Collision Avoidance Systems (TCAS II) installation.Note: This STC supersedes EASA.A.S.00761.		Master Drawing List No 600-2004-000-000 Rev. IR dated 30 March 2005.	1. Airplane Flight Manual Supplement No 600-2004-800-000 Rev. IR dated25 January 2005.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibilitywith other aircraft/engine configurations shall bedetermined...	07/01/2009	Active	10043098
EASA.A.S.00761	VITROCISET S.p.A.	REV. 1		F27 MK 500	Traffic Collision Avoidance Systems (TCAS II) installation.Note: This STC supersedes EASA.A.S.00761.		Master Drawing List No 600-2004-000-000 Rev. IR dated 30 March 2005.	1. Airplane Flight Manual Supplement No 600-2004-800-000 Rev. IR dated25 January 2005.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibilitywith other aircraft/engine configurations shall bedetermined...	07/01/2009	Active	10043099
EASA.A.S.00762	VITROCISET S.p.A.			F27 MK 500	Radar System Replacement with Bendix king ART 2000 System.Note: This STC supersedes EASA.A.S.00762.		Master Drawing List No 400-0303-000-000 Rev. IR dated 29 July 2003 orlater approved revisions.	1. Airplane Flight Manual Supplement No 400-0303-800-000 Rev. IR dated 4June 2003.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by...	07/01/2009	Active	10043100

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.00764	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 525 & CESSNA 525A	Installation of a Honeywell KMD 850 System and installationof a TCAS ISky.		- Flight Manual Supplement 2016515-AM-01, Issue 3, or laterEASAapproved Revisions.- Flight Manual Supplement 2016516-AM-01, Issue 3, or later EASAapproved Revisions.	1. This STC is approved only for the product configurationas definedin the approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	13/06/2005	Active	10043101
EASA.A.S.00766	SCANDINAVIAN AVIONICS DESIGN ApS			SAAB SF340A	Installation of an ADF 2 Bendix King KDF 806 System.		SAD "Description of System and Installation" Ref.: 2020789-DE-02, Issue 3, dated 22.10.2004.SAD "SAAB SF 340A approved Aircraft Flight Manual Supplement for ADF 2 Bendix/King KDF 806" ref.: 2020789-AM-01, Issue 4, dated May2005	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	08/06/2005	Active	10013971
EASA.A.S.00767	AIRBUS S.A.S.	REV. 1		A320-214	LIVE TV Installation		Modification Approval Sheet (MAS) Ref.: SOG-00-91, Issue 1 dated May 27, 2005. MPD Section 9-2 Supplement Ref.: MPD-S MOD-SOG-00-901, dated May 27, 2005	This STC is limited to A320-213 MSN 2165	04/07/2008	Active	10013972
EASA.A.S.00769	AIRBUS S.A.S.	REV. 1		A320-214	Avionic Rack 9100 VU Installation		Modification Approval Sheet (MAS) Ref. SOG-00-902 Issue 1 dated May 27, 2005.AFM Supplement Ref. FM-S MOD-SOG-00-902 dated May 10, 2005.MMEL Supplement Ref. : MMEL-S MOD-SOG-00-902 dated May 1, 2005	This STC is limited to A320-214 MSN 2165	04/07/2008	Active	10013973
EASA.A.S.00772	AIRBUS S.A.S.	REV. 1		A320-214	NAS VIP Cabin Modification		Modification Approval Sheet (MAS) Ref.: SOG-00-900 Issue 1 dated June 1, 2005.AFM Supplement Ref.: FM-S MOD-SOG-00-900 Revision 3 dated May 27, 2005MPD Section 9-2 Supplement Ref.: MDP-S MOD-SOG-00-900 dated May 27, 2005.MMEL Supplement Ref.: MMEL-S MOD-SOG-00-900 Revision 00 dated May 1, 2005.	This STC is limited to A320-214 MSN 2165	04/07/2008	Active	10013974
EASA.A.S.00773	SCANDINAVIAN AVIONICS DESIGN GMBH			BEECH 200/B200/300, B300	Installation of a Garmin GNS 430A/530A COMM/NAV/GPS System.		AFM Supplement "Garmin GNS-430A/530A VHF Communications Transceiver /VOR/ILS GPS Receiver" Document No. 2026288AM-02A, Issue 3 or later EASAapproved revisions. AFM Supplement "Allied Signal KMR 675 Marker BeaconReceiver" Doc. No. 2026288-AM-02B, Issue 1 or later EASA approvedrevisions.	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	29/06/2005	Active	10053192
EASA.A.S.0082	MOTORFLUG BADEN-BADEN GmbH			SA227-AT SA227-AC	Installation of Artificial Horizon AIM 520-1b and EmergencyPower SupplyPS-835D.			This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	06/08/2004	Active	10057635

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.0088	AERO ENGINEERING DESIGN LIMITED		CAA UK RESPONSIBILITY	757-200	Installation of T2CAS Combined ACAS and Terrain Awareness Warning Systemin accordance with AED Design Modification Certificate 34-15-190 dated16/07/2004 or later EASA-approved revision, Flight Manual Supplement:AED/B757/002			1. Subject to compliance with the provisions of Part 21 Subpart E, thisSTC and associated data shall remain valid untilsurrendered, withdrawnor otherwise terminated.2. If transfer of this Certificate is requested under Part 21A.116, theSTC will be reissued.3. This STC is approved only for the produ...	06/08/2004	Active	10051157
EASA.A.S.01000	LUFTHANSA TECHNIK AG			BOEING 767-300	Installation of an Optical Quick Access Recorder (OQAR) according to LHT Engineering Bulletin No. 767-EB31-0203, dated 09.09.04 or later approved Revision for FOQA Purpose			This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other Aircraft configurations shall be determined by the installer.	17/08/2005	Active	10013977
EASA.A.S.01001	LUFTHANSA TECHNIK AG			BOEING 737-300	Installation of an Optial Quick Access Recorder (OQAR) according to LHT Engineering Bulletin No.737-EB31- 0202, dated 29.09.04 or later approved Revision for FOQA Purpose.			This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other Aircraft configurations shall be determined by the installer.	17/08/2005	Active	10013978
EASA.A.S.01004	ATS INTERNATIONAL			BOEING 737-200-200C	installation of a Class A Terrain Awareness Warning System (TAWS), based on an Honeywell EGPWS MK VII System, aboard Boeing 737-200aircraft equipped with external GPS source.		MDL (Master Data List) : 0200-01-A-2103-R01.	AFMS : 0200-01-A-2301-R00.ADSS (Airworthiness Data Sheet Supplement) including ICA (Instructions for Continued Airworthiness): 0200-01-A-2203-R00.This STC is limited to Terrain display configuration 1 : Honeywell PPI-4B or Collins WXI 701/711.	26/07/2005	Active	10013979
EASA.A.S.01008	RUAG AEROSPACE SERVICES GmbH			CESSNA 525A CESSNA 525	Installation of Honeywell EGPWS MK V with RAAS		Doc. No. 128B-MDL, 128B-EOEASA approved RUAG AFM-S Doc. No.128B-AFMS, Original Issue, or later approved RevisionRUAG Continued AW procedures. Doc. No. 128B-CAWP, Original issue, or later approved Revision		10/04/2007	Active	10013980
EASA.A.S.01012	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (CL-601 BOMBARDIER CL-600-2B16	Installation of Honeywell EGPWS MK V.		- Master Document List 100B-MDL, rev. N/C dated 06.04.2005 or later EASA-approved Revisions.- Airplane Flight Manual Supplement 100B-AFMS, rev. N/C dated 06.04.2005 or laterEASA-approved Revisions.- Continued Airworthiness Plan AMM.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	12/04/2005	Active	10013981
EASA.A.S.01014	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	A320-200	Reconfiguration of Passenger Cabin to 180 Economy Class Passengers		-BBJ394 Issue 1 or later approved revision		17/01/2005	Active	10013982
EASA.A.S.01015	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 501-551	Installation of a Honeywell KTA 870 and ART2000		Flight Manual Supplement 2003-2-8 Revision A, or later EASAapproved revisions.		15/06/2005	Active	10013983
EASA.A.S.01016	AEROTEC & CONCEPT			C90 A	Installation of Garmin GNS 430 (VHF NAV ILS GPS/BRNAV), Allied Signal ART 2000 (weather radar), Allied Signal KMD 850 (MFD), MD 41 (panel annunciator) and GMA 340 (markers)		-Dossier de modification Aerotec No 4104	1. Modification limited to s/n LJ 10982. EASA Supplemental Airplane Flight Manual GNS 430 must be used with this modification. 3. EASA Supplemental Airplane Flight Manual KMD 850must be used with this modification.	19/01/2005	Active	10013984

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01017	BBJ DESIGN SERVICES LIMITED	REV. 1	CAA UK RESPONSIBILITY	737-700, 737-800	Installation of 44 Passenger Seats, seats power supply and in seat power supply system on Boeing-BBJ128 Reynard J2000 double seats,safety equipment, carpet and new wardrobes. Installation of General Dynamics In Seat Power System.		Modification Document BBJ385 Issue 4 or later approved revision		24/10/2005	Active	10013985
EASA.A.S.01018	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	767-300	Floor Structure rework.		BBJ Design Services Ltd Modification Summary Sheet BBJ365 dated May 18, 2005 or later EASA approved revisions.	1. This STC is restricted to Boeing 767-3Z9 Registration G-VKNG, Serial Number 23765.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determin...	08/06/2005	Active	10013986
EASA.A.S.01020	AERODATA AG			BEECH B200T B200 / B200T	Installation of TCAS 2000 with RCZ 852 Mode S Transponders		-AFM 075 Rev 0 or later EASA approved revision-AMM-772 Rev 0	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	11/02/2005	Active	10013988
EASA.A.S.01021	AERODATA AG			B200, B300 / B200T	Installation of UNS 1-F Flight Management System		-AFM 076 Rev 1 or later EASA approved revision-AMM-774 Rev 0		11/02/2005	Active	10013989
EASA.A.S.01022	DASSAULT FALCON SERVICE			MYSTERE FALCON 20-5	Installation of Collins TCAS-4000 and of 2 ATC TDR 94D capable of elementary surveillance.		- Change Approval Sheet DFS 533 issue original dated 7 April 2005.- AFM Supplement DFS No 31 issue original dated7 January 2005.		28/04/2005	Active	10013990
EASA.A.S.01023	AERODATA AG			DORNIER D328-300 DORNIER 328-100	AeroPhone IRIDIUM SATCOM Installation		Master Document List, Ref MDL-A/C-062, Revision 3 dated 8 September 2005Airplane Flight Manual Supplemetn, Ref AFM-058,Revision 1, dated 13 August 2005Airplane Maintenance ManualSupplement, Ref HB-A/C-708, Revision 3		14/09/2005	Active	10013991
EASA.A.S.01028	SCANDINAVIAN AVIONICS DESIGN ApS			LEARJET 55	Installation of a Rockwell Collins ACAS (TCASII) 4000 with dual Mode S Transponders		-Engineering Order 2019360-EO-01, Issue 3-Certification Documents List, 24.1.2005-AFMS Issue 2, January 2005	1. Certification Basis for this STC is CS 25 plus JAA TGL No 8 and JAA TGL No 13	31/01/2005	Active	10013994
EASA.A.S.01029	SCANDINAVIAN AVIONICS DESIGN ApS			LEARJET 55	Installation of a L3 Digital Flight Data Recorder		-Engineering Order 2019360-EO-02, Issue 1-Certification Documents List, 30.12.2004-AFMS Issue 1, October 2004	Certification Basis for this STC is CS 25	31/01/2005	Active	10013995
EASA.A.S.01030	SOCIETE AIR FRANCE S.A.	REV 1		AIRBUS A321-211	Cabin reconfigurationChange Approval Sheet ref. CAS-A320-04-015 revision 2, dated October 21, 2005		Change Approval Sheet ref. CAS-A320-04-015 revision 0, dated October 21, 2005	This STC is limited to the A321 MSN 1017	08/09/2006	Active	10013996
EASA.A.S.01032	SCANDINAVIAN AVIONICS DESIGN ApS			LEARJET 55	Installation of a Honeywell EGPWS mark VIII (TAWS)		-Engineering Order 2019360-EO-03, Rev. 2-Certification Documents List, 24.01.2005-AFMS Issue 1, November 2004	Certification Basis for this STC is CS 25 plus JAA TGL No 12 "TAWS"	31/01/2005	Active	10013997
EASA.A.S.01034	AERO ENGINEERING DESIGN LIMITED		CAA UK RESPONSIBILITY	A330	Introduction of FLIGHTVU Camera Surveillance System		-25-71-426 Rev 1 dated 25 February 2005	1.This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/ engineconfigurations shall bedetermined by the installer.	04/03/2005	Active	10043102

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01035	E A D AEROSPACE AIRWORTHINESS			BEECH 1900D BEECH 1900C, AIRLINER	ELS/EHS mode S installation on B1900 series.		-Top Master Drawing List 00886-JAA-MDL rev. D or later approved revision.- Maintenance planning document supplement DC112-0886-00A or later approved revision.- Minimum Equipment List Supplement DC109-0886-00A or later approved revision.-Airplane Flight Manual Supplement DC107-0886-00B or later approve...	The Airplane Flight Manual Supplement DC107-0886-00B or later approved revisions must be used with this modification.	12/04/2005	Active	10013998
EASA.A.S.01036	E A D AEROSPACE AIRWORTHINESS			BOEING 737	Installation of a Honeywell EGPWS Mark V.		EAD MasterDrawing List Reference 01024-EAS-A-MDL revision E.AFM Supplement Reference 01024-EAS-AFM-01 Revision D.		14/06/2005	Active	10013999
EASA.A.S.01037	E A D AEROSPACE AIRWORTHINESS			BEECH 1900	Installation of a Traffic Alert and Collision Avoidance System, model Hoenywell CAS-67A TCASII installation on B1900 Series.		EAD Master Drawing List Document No. 00887-JAA-MDL, Revision F dated 25 May 2005, or later EASA approved revisions.Maintenance Planning Document Supplement DC112-0887-00A or laterRevisions.	All wiring required for TCAS II activation must be installed.ATC Mode S Transponders must be installed.	18/07/2005	Active	10014000
EASA.A.S.0104	ATS INTERNATIONAL	REV. 1		B737-700/-800/-900 B737-300/-400/-500/-600	Installation of the enhanced Mode S surveillance in accordance withMaster Data List reference 0159-01-A-2103-R03 or later EASA-approvedrevision.			1. The AFM Supplement reference No 0159-01-A-2301-R01 is a required partof this STC.2. Installation of the enhanced Mode S surveillance in accordance withMaster Data List reference 0159-01-A-2103-R02 or later EASA-approvedrevision.3. This STC is approved only for the product configuration as defined...	16/12/2004	Active	10043026
EASA.A.S.01041	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE			BEECH C90A	Installation of a Concorde RG-380E Sealed Lead Acid Battery.		-FAA STC n° SA00257AT.- United Beechcraft Master Drawing List MDL-UBF93101 (15/06/1993). FAA Form 337 No ML2R009L.	1. Supplemental Airplane Fight Manual No UAE/52 (French language) must be used with this modification.2. Modification limited to Beechcraft C90A s/n LJ-1361.3. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". C...	11/04/2005	Active	10014004
EASA.A.S.01042	EADS SOGERMA	REV 1		AIRBUS A340-300	Installation of an upper class with side facing Britax Malcom seats with inflatable restraints, monument, bar and chandelier, and modification of the premium and economy class by repitching.Note: This revision reflects the transfer of thisSTC from EADS Sogerma Services to Sogerma Services.		MAS SOG-00-1000 Issue 1 dated 1/08/2005.Master Data List Drawing No. MDL-00-1000 Issue No. A, or later EASA approved revision.Flight Manual Supplement page 1.02.00 p01 dated 01/07/2005 .Technical repercussion sheet Ref. 00-1000A.	1. This STC is limited to Airbus A340-300 MSN 214, 002, 003, 164 and 225.2. A copy of this STC and of the MAS/MDLmust be enclosed in the files of each modified aircraft.	07/01/2008	Active	10014005

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01043	AERODISA S.L.			EMBRAER EMB-120	Installation TCAS IIHoneywell TCAS II TPU 67A Processor andConfiguration Module with lower and upper ANT 67A Antennas,dual IVA-81D TA/RA/VSI System Displays, one MST67A Mode S Transponder (OPTION 1) or two MST67A Mode S Transponder (OPTION 2) with lower and upper KA60 Omnidirectional Antennas and...		- Doc No. AED2004-01M_MDL " Master Data List", Ed 0, dated 20 April 2006- Doc No. AED2004-01M_PCA "Plan de Comprobaciónde Aeronavegabilidad", ED 0Installation instructions in accordance with:- Doc No. AED2004_01M_D01 "Installation Manual"Edicion 00- Honeywell Installation Manual 006-05340-0006 CAS...	Subject th the conditions, limitations and procedures contained in Doc No. AED2004_01M_D03_OP1 "Flight Manual Supplement for 1 transponder installation", Rev 0 or AED2004_01M_D03_OP2 " Flight Manual Supplement for 2 transponders installation", Rev. 0	31/07/2006	Active	10014006
EASA.A.S.01049	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK	REV. 1	CAA UK RESPONSIBILITY	228-202K	Introduction of ACAS and Mode S		- Design Change Definition Document -DC-0020 Issue B or later approvedrevision- AFM supplement-FRAH/FM/0105 Rev 0 or later approved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	27/09/2006	Active	10043010
EASA.A.S.01051	HAWKER BEECHCRAFT Ltd.	REV. 1	CAA UK RESPONSIBILITY	HAWKER HS 125-700B	Increase Maximum Zero Fuel Weight		Instructions for Continued Airworthiness ACS-R-007-711422.Weight Statement CSWE/L/800.		22/02/2005	Active	10014008
EASA.A.S.01052	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 525- 525A	Installation of a Dual MST 67A Mode S Transponder System.		Airplane Flight Manual Supplement, Report 2004-17-8, Revision A or later EASA approved Revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	13/06/2005	Active	10014009
EASA.A.S.01053	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 525A 525	Installation of Dual Garmin GTX 330D Mode SAFM Supplement 2004-16-8 Revision A or later EASA approved RevisionMM Supplement 2005-16-10 Revision A or later EASA approved Revision				17/11/2005	Active	10014010
EASA.A.S.01057	AEROTEC & CONCEPT			PA-28RT-201T (TURBO ARROW IV)	Installation of GARMIN GNS 430 (VJF/NAV/ILS/GPS) and MD 41 (panel annunciator)Removal of VHF KY 97A, GPS 150XL, NAV VIR351 and Glide GLS 350. Installation of GNS 430 and MD 41 panel annunciator, auto-pilot coupled.		AFMS "Supplement au manuel de vol du PA 28 RT 201 T immatricule F-GJRR pour une utilisation GNS 430 en moyen supplementaire de navigation IFR et B-RNAV" dated 05 September 2005	The approval is limited to MSN 28R7931294 F-GJRR	25/10/2005	Active	10014014
EASA.A.S.01058	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		AMD/BA FALCON 10	Installation of Rockwell Collins TCAS-4000 incl. Dual Mode S Transponder TDR-94D in accordance with the Engineering Order Doc 2022256-EO-01 Issue 2 or later EASA approved revisions		AFM Supplement ACAS Document No 2022256-AM-01A issue 2 or later EASA approved revisionsAFM Supplement Mode S Document No 2022256-AM-01B Issue 2 or later EASA approved revisionsInstructions for Continued Airworthiness Doc 2022256-CA-01		30/05/2005	Active	10014015
EASA.A.S.01059	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		AMD/BA FALCON 10	Installation of a Kannad 406 ELT in accordance with Engineering Order Doc 2022256-EO-03, Issue 1 or later EASA approvedrevisions		AFM Supplement Document No 2022256-AM-03 Issue 2 or later EASA aproved revision Instructions for Continued Airworthiness Doc 2022256-CA-03		14/05/2005	Active	10014016

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01060	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 2		AMD/BA FALCON 10	Installation of a Multi Function Radar Display (MFRD) and EGPWS MK VIII in accordance with the Engineering Order Doc 2022874-EO-01,Issue 2 or later EASA approved revisions		AFM Supplement MFRD Document No 2022874-AM-01A Issue 2 or later EASA approved revisionsAFM Supplement EGPWS MK VIII Document No 2022874-AM-01B Issue 3 or later EASA approved revisionsInstructions for Continued Airworthiness Doc 2022874-CA-01		09/08/2007	Active	10014017
EASA.A.S.01065	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	Installation of a Honeywell Mark V EGPWS soft 217-217 withterrain display in the Collins EFIS 86-C14		-Change Approval Sheet DFS 5601 issue A dated January 19th 2005-AFM Supplement DFS No 49 issue original dated December 29th 2004	1. Applicable to Mystère Falcon 50 equipped with Collins EFIS 86-C14 only2. This STC is approved only for the product configuration as defined in the approved design data referredto in the paragraph "Description". Compatibility with otheraircraft/ engine configurations shall be determined by the in...	03/02/2005	Active	10014018
EASA.A.S.01073	BUSINESS AND COMMUTER AIRCRAFT			CESSNA 550 CITATION II	Installation of TCAS II system in accordance with MDL BCA 70-00 rev. 3 dated 18/03/05		-AFM supplement SMVBCA70 rev. 0 dated 18/01/05	This STC is applicable to s/n 550-0622	04/04/2005	Active	10014019
EASA.A.S.01075	RUAG AEROSPACE SERVICES GmbH			CESSNA 560	Installation of an ACAS II (TCAS 2000, CH 7) with Dual ModeS Transponders ACSS RCZ-852-ELS/EHS.		- Design Modification Document Doc. No. 039A-MDL.- Operating Instructions Doc. No. 039A-AFMS.- Instructions for Continued Airworthiness Doc. No. 039A-CAWP.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	27/01/2005	Active	10014020
EASA.A.S.01076	RUAG AEROSPACE SERVICES GmbH			CESSNA 501	Installation of Dual Mode S Transponders ACSS RCZ-852-EHS		-Airplane Flight Manual Supplement Doc.-No.: 096B-AFMS, Rev. N/Cor later EASA approved revision		01/03/2005	Active	10014021
EASA.A.S.01077	EADS SOGERMA	REV 1		AIRBUS A330-203	Qatar Airways - Cabin Modification. Modification number: SOG-25-886 issue 1Note: This revision reflects the transfer ofthis STC from EADS Sogerma Services to Sogerma Services.Model: Airbus A330-203 MSN 463 and 504		-AFM Supplement ref.: AFM-25-886 Iss. A	1. The approval of this modification is limited to the identified aircraft. The limitations and conditions defined in the EASA Datasheet are also applicable. A copy of the STC approval and the MDL must be enclosed in the files of each modified aircraft.2. Maintenace and Continued airworthiness...	07/01/2008	Active	10014022
EASA.A.S.01079	BUSINESS AND COMMUTER AIRCRAFT			BEECH 1900D	Emergency Transmitter Kannad 406 MHz installation on Beechcraft 1900 D.		- BCA No. 61 Modification File.- BCA/RDO/140404 Drawing (Merely ELT installation).- BCA/RDO/ 030904 Drawing (ELT and Programming Unit).	1. This STC is limited to Beechcraft 1900 s/n UE-1 and up.2. Required Pre-Modification: any existing EASA approved ELT doubler Airplane Flight Manual Supplement No. BCA/61must be used with this modification.	20/01/2005	Active	10014024
EASA.A.S.01091	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B200C BEECH B200 BEECH 200C BEECH 200	Installation of a Universal TAWS system and related components.		- EASA approved AFM Supplement Doc. 2021128-AM-01, issue 5,or later EASA approved issue-Description of Change 2021128-DE, Issue 3		04/01/2007	Active	10014025
EASA.A.S.01092	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B200 BEECH 200	Installation of GPS TNL-2101 I/O APPR+		-AFM Supplement 2021128-AM-02 Issue 1 or later EASA approved revision-Continued Airworthiness Instructions 2021128-CA-02		11/02/2005	Active	10014026

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01093	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		BEECH B300C BEECH B300 BEECH B200C BEECH 300LW BEECH 300 BEECH 200C BEECH 1900	1. Installation of Dual Mode S Transponder MST-67A System with ELS capabilities (installation prior to 31-Jan-2007)2. Installation of Dual Mode S Transponder MST-67A System with ELS and EHS capabilities (installation on or after 31-Jan-2007)		1. For installations prior to 31-Jan-2007:- AFM Supplement 2021128-AM-03, Issue 1 or later EASA approved revision,- Continued Airworthiness Instructions 2021128-CA-03.2. For installations on or after 31-Jan-2007:- Engineering Order, Doc. No. 2021128-EO-03, Issue 5, dated 31-Jan-2007,-...	For installations on or after 31-Jan-2007, this change is limited to the configuration of aircraft / equipment type as listed underItem 4. in Engineering Order, Doc. No. 2021128-EO-03, Issue 5, or later approved issue:	05/02/2007	Active	10014027
EASA.A.S.01094	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B200 BEECH 200	Installation of Multifunction Display MFD-640 & RP 1008		-AFM Supplement 2021128-AM-04 Issue 2 or later EASA approved revision-Continued Airworthiness Instructions 2021128-CA-04		11/02/2005	Active	10014028
EASA.A.S.01095	AERO-DIENST GMBH & CO. KG			60	Installation of a Cabin Entertainment System with Airshow 4X0.		Aerodienst engineering Order N0 203-LR, Rev. IR, or later EASA-approved revisions.	For certification basis refer to FAA TCDS A10CE plus FAR 25.1309 at Amdt. 25-41 and FAR 25.1529 at Amdt. 25-54 and plusJAA TGL No.17, IFE Systems.	28/04/2005	Active	10014029
EASA.A.S.01096	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	Installation of a Honeywell Mark VII EGPWS soft 217-217 with terrain display in the MFD		-Change Approval Sheet DFS 5603 issue original dated February 8th 2005-AFM Supplement DFS No. 50 issue original dated February 8th 2005-if the aircraft has steep approach capability AFM Supplement DFS No. 51 issue original dated February 8th 2005	This STC is only valid for Falcon 50 equipped with a Universal FMS UNS-1B with GPS-1000, or UNS-1C/1C+/1D/ 1E/1F/1K/1K+/1L and with Collins EFIS-86C(x)/weather radar WXR-350	15/02/2005	Active	10014030
EASA.A.S.01097	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-31	Installations of Avidyne FM850, 2x Garmin GTX330D Mode S Transponder and Garmin GMA340 Marker/Audio		EASA approved AFM Supplements:Avidyne FM850 Flight Display LBA2004-024-01 Rev AGarmin GTX330D Mode S Transponder LBA2004-024-00 Rev AGarmin GMA340 Marker/ Audio LBA2004-024-02 Rev A or later EASA approved issues	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	26/10/2005	Active	10014031
EASA.A.S.01098	AVIONIK STRAUBING ENTWICKLUNGS GmbH			300LW	Installation of Mode S Transponder TDR94D with new Top Antenna.		AFM Supplement 'Mode S Transponder Collins TDR 94 D'. Doc. No.: ACG 2004-014-00Rev. A, Engineering Order ACG2004-014-00		22/06/2005	Active	10014032
EASA.A.S.01103	ATS INTERNATIONAL			737-300, 737-400, 737-500	Installation of an Artex Emergency Locator Transmitter		- ATS International Master Data List No 0233-01-A-2103 revision 2- Airworthiness Limitations as specified in ATS-Airworthiness Data Sheet Supplement No 0233-01-A-2203 revision 0§2.6.5		18/03/2005	Active	10014033
EASA.A.S.01108	RUAG AEROSPACE SERVICES GmbH			CESSNA 550 BRAVO	Upgrade of GPWS to EGPWS		- AFM Supplement 5387/04/1-06		10/02/2005	Active	10014035
EASA.A.S.01109	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 525	Installation of Honeywell KMH 980 Multi-Hazard Awareness System including TCAS I and EGPWS (Class B).		EASA-approved Flight Manual Supplement 2019974-AM-01, issue2, or later EASA-approved issue.		11/04/2005	Active	10014036
EASA.A.S.01110	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 525	Installation of WX-500 Stormscope System		EASA-approved Flight Manual Supplement 2019974-AM-02, issue2, or later EASA-approved revision.		11/04/2005	Active	10014037

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01111	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 525	Installation of Bendix/King KLN 94 GPS System.		EASA-approved Flight Manual Supplement 2019974-AM-03, issue2, or later EASA-approved issue.		11/04/2005	Active	10014038
EASA.A.S.01112	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 2		CESSNA 525A CESSNA 525	Installation of dual GTX 330D Mode S Transponder systems.Installation of dual GTX 330D Mode S Transponder systems.		- EASA approved Engineering Order, Doc. No. 2019974-EO-05, Issue 4, or later approved Issue- for ELS-mode operation of XPDR system:EASA approved Airplane Flight Manual Supplement, Doc. No. 2019974-AM-05A, Issue 1, or later approved Issue- in addition for EHS-mode operation of XPDR system:Ap...	1. According to Engineering Order 2019974-EO-05, Issue 41. According to Engineering Order 2019974-EO-05, Issue 4	25/02/2008	Active	10014039
EASA.A.S.01116	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			PA-42 SERIES	Installation of Artex ELT 406.		EASA approved Airplane Flight Mnaual Supplement, Report: 2004-20-8, revision A, or later EASA approved revision.		23/06/2005	Active	10014041
EASA.A.S.01120	GULFSTREAM AEROSPACE Ltd.		CAA UK RESPONSIBILITY	GULFSTREAM IV	Installation of Artex C406N Emergency Locator Transmitter		Definition Document GAeL/0138/001 Issue 3 dated 25 January 2005 or later approved revision		15/02/2005	Active	10014042
EASA.A.S.01121	LUFTHANSA TECHNIK AG			AIRBUS A330-200	A330-200 Air Algerie Quick Change VIP Kit OnePlus.		-Supplemental Type Definition Document: STDD00-04/20M, Issue 1.-Compliance Record List: CRL00-04/20M, Issue 1.-AirplaneFlight Manual Supplement acc.: A-00-05/084-AFM Rev. 03.-Instructions for Continued Airworthiness.-Master Minimum Equipment List (MMEL) A-00-05/084-MMEL.		31/03/2005	Active	10014043
EASA.A.S.01122	RUAG AEROSPACE SERVICES GmbH			CESSNA 560	Installation of ACAS II CAS 67A with Dual Mode S Transponder RCZ-833 J-ELS		-System Description Doc No 085F-MDL-Airplane Fligth Manual suppleent Doc No 085-AFMS-Instructions for Continued Airworthiness Doc No 085F.CAWP		17/03/2005	Active	10014044
EASA.A.S.01123	AERO ENGINEERING DESIGN LIMITED		CAA UK RESPONSIBILITY	737-200	Introduction of Honeywell Mk VII EGPWS		-Design modification certificate 34-13-224 Issue 1 dated February 23,2005 or later EASA approved revision-Aero Engineering Design Flight Manual Supplement AED/B737/003 Issue 2February 2005 or later EASA approved revision	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	09/03/2005	Active	10043011
EASA.A.S.01124	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CAP 232	Introduction of Rudder, Throttle and Brake Controls for Hand Operationby Paraplegic Pilot with upper Body Strength only		Master Document List S21.MDL-0557 Issue 3 dated 02/10/2008	1.,,Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and anyother previously installed modification willintroduce no adverse effectupon the airworthiness of the product.2.,,Serial Number 11 only.	16/03/2009	Active	10043012
EASA.A.S.01125	AERO ENGINEERING DESIGN LIMITED		CAA UK RESPONSIBILITY	B737-700 & B737-800	Introduction of SSR Mode S Enhanced Surveillance		-AED Certification Plan Doc ref. AED/B737/348-Flight ManualSupplement ref AED/B737/02		01/03/2005	Active	10041902

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01126	MT-PROPELLER ENTWICKLUNG GmbH	REV 1		REVO LAKE 250	Installation of propeller- MTV-9-B/ LD193-109 or- MTV-9-B-C-R(M)/ CRLD193-109		- Anhang zum Flugbuch Nr. E-1198- Airplane Flight Manual Supplement No. E-1199- Umruest- und Wartungsanweisung E-1194- Instructions for Continued Airworthiness and Installation Instructions E-1197- Anhang Flughandbuch Nr. E-1200- Airplane Flight Manual Supplement No. E-1201- Umruest- und Wartungsanw...		02/12/2005	Active	10014045
EASA.A.S.01129	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	757-200	Enhanced Mode S Surveillance System completion and activation		-Modification Summery Document BBJ342 Issue 1 21/09/04 or later EASA approved revision -AFM Supplement BBJFMS012 Revision IR or later EASA approved revision		01/04/2005	Active	10014047
EASA.A.S.01130	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	767-300	Enhanced Mode S Surveillance System completion and activation		-Modification Summery Document BBJ343 Issue 1 21/09/05 or later EASA approved revision -AFM Supplement BBJFMS013 Revision IR or later EASA approved revision		01/04/2005	Active	10014048
EASA.A.S.01132	SCANDINAVIAN AVIONICS DESIGN ApS			LEARJET 35A LEARJET 35	Installation of Honywell CAS 67A ACAS/ TCAS II with dual MST-67A Mode S Transponder		-Certification Documents List 2020220-02, 19.04.2005-AFMS 2020220-AM-02A, Issue 2, or later EASA approved issues-AFMS 2020220-AM-02B, Issue 2, or later EASA approved issues	Certification Basis: applicable requirements of CS25 plus JAA TGLs No 8 and 13 1.	31/05/2005	Active	10014050
EASA.A.S.01133	AERODISA S.L.			SA227-AC, SA227-BC, SA227-PC	TCAS II installation on Fairchild SA 227Honeywell TCAS II TPU 67A Processor and Configuration Module with lower and upper ANT 67A Antennas, dual IVA-81D TA/RA/VSI System Displays,two MST67A Mode S Transponders with lower and uppar KA60 Omnidirectional Antennas, PS-55 ATC, TCAS Control Unit, IDC Sec...		- Doc N° AED2004-02M_PCA "Plan de Comprobacion de Aeronavegabilidad", Ed 0 Installation Instructions in accordance with : - Doc N° AED2004-02M_D01 " Installation Manual" Edicion 00 - Honeywell Installation Manual Manual 006-05340-0006 CAS67A TCAS II System, Rev. 6 - Honeywell Installation Manual M...	Subjected to the conditions, limitations and pocedures contained in Doc N° AED2004_02M_D03 "Flight Manual Supplement", Rev 0	04/09/2006	Active	10014051
EASA.A.S.01134	DASSAULT FALCON SERVICE			FALCON 10	DFS 1261 dtd 13.Oct 2005: Installation of a TAWS Honeywell Mark VIII EGPWS soft 011		see Change approval sheet DFS 1261-AFM Supp F10 DFS 29 toDTM 721(A) with DFS 1261 incorp "TAWS Honeywell Mark VIII Soft 011"-AFM Supp F10 DFS 31 to DTM 721 (A) with DFS 1261 incorp "EGPWS Steep Approach Function"-Wiring Diagram DFS 10 600 31-56-01 XXand associated list of affected technical docu...	1. This STC is approved only for the configuration as defined in Mod Sheet DFS 1261.2. Compatibility with other aircraft/ engine configurations shall be determined by the installer	02/05/2006	Active	10014052

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01135	ATS INTERNATIONAL			ATR 72-101-102-201-202-211-212 AEROSPATIALE ATR 72-212 AEROSPATIALE ATR 72-211 AEROSPATIALE ATR 72-202 AEROSPATIALE ATR 72-201 AEROSPATIALE ATR 42-300 42-320-300	121.5/243/406 MHz Emergency Locator Transmitter Installation.		ATS International Master Data List No. 0220-01-A-2103 Revision 1.		24/03/2005	Active	10014053
EASA.A.S.01136	ATS INTERNATIONAL			767-200,-300	MK V EGPWS system installation.		Airplane Flight Manual Supplement (AFMS) ref. 0203-01-A-2301 revision 0;dated June 13, 2005 or later approved revision.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	23/10/2007	Active	10043013
EASA.A.S.01137	SOCIETE AIR FRANCE S.A.			BOEING 767-200-300	Installation of Elementary Surveillance Dual ATC Mode S on B767-300The ATC Mode S computers TPR 720 are replaced by a TPR 901 which is compliant with ATC Mode S Elementary surveillance requirements.ATC Mode S Elementary surveillance implementation is described in Air France Service Bulletin No. AF S...		Air France Change Approval Sheet No. CAS-B767-04-001 dated December 1, 2004.Air France Service Bulletin No. AF SB B767-04-001-34-001 “EATC Installation on B767-300”		22/08/2005	Active	10014054
EASA.A.S.01138	SOCIETE AIR FRANCE S.A.			BOEING 767-200-300	Installation of Elementary Surveillance Dual ATC Mode S on B767-300The ATC Mode S computers TPR 720 are replaced by a TPR 901 which is compliant with ATC Mode S Elementary surveillance requirements.ATC Mode S Elementary surveillance implementation is described in Air France Service Bulletin No. AF S...		Air France Change Approval Sheet No. CAS-B767-04-001 dated December 1, 2004.Air France Service Bulletin No. AF SB B767-04-001-34-001 “EATC Installation on B767-300”		07/04/2005	Active	10014055
EASA.A.S.01139	SOCIETE AIR FRANCE S.A.			BOEING 747-200-300	Installation of EGPWS.This STC supersedes and cancels DGAC STC IM29-SF-0282.		Group 1 (Air France Fleet): AEO 47-34-0715.Group 2 (Customer Fleet): CAS B747-04-010.AFM Supplements D6-33747-228, D6-33747-2B3 and D6-33747-3B3 are applicable to Air France B747-200/-300 aircraft.AFM Supplement No. MA.PM0006/05 is applicable to Pullmantur Air aircraft.		18/05/2005	Active	10014056
EASA.A.S.01140	SOCIETE AIR FRANCE S.A.			BOEING 747-300	Elementary surveillance dual ATC Mode S installation.		Change Approval Sheet ref. CAS B747-04-009 Revision 0, dated February 10, 2005 or later approved revision.	This STC is limited to the B747 MSN 24106.	15/03/2007	Active	10014057
EASA.A.S.01142	SELL GmbH			BOEING 767-300	Replacement of galley G3A P/N10160F23-00000with a new galley P/N 10160F23A00000 designed by Sell GmbHaccording to Sell Engineering Order Doc. No. EO WA 151043, Issue May 7 2004		-Model Drawing 10160F23A00000-Galley Installation Drawing 10160F23A00-Instructions for Continued Airworthiness: Component Maintenance Manual Doc. No. CMM No. 25-01-42		11/02/2005	Active	10014058

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01144	RUAG AEROSPACE SERVICES GmbH			CESSNA 560 (CITATION V)	Installation of ACAS II (ACSS TCAS 2000, CH7) with Dual Mode S Transponders RCZ-833J ELS		-Master Document List, Dok Nr. 093C-MDL, Rev N/C dated 03.03.04-AFM Supplement, Dok Nr. 093C-AFMS, Rev N/C dated 03.03.04-Continued Aitworthiness Plan (Maintenance Manual Supplement), Dok Nr. 093C-CAWP, Rev N/C dated 03.03.04		10/03/2005	Active	10014060
EASA.A.S.01147	AEROTEC & CONCEPT			PA-31T	Installation of radio navigation and communication systems in accordance with Document Reference 5304 - Revision 2 dated April 15, 2005		AFMS referenced 5304. STC Document Reference 5304 Revision 2 dated April 15, 2005	This STC is limited to Piper PA-31T SN 8020037	11/10/2005	Active	10014061
EASA.A.S.01148	MOTORFLUG BADEN-BADEN GmbH			650	Installation of Honeywell CAS-67 ACAS II and Dual MST 67A Mode-S Transponder.		-Airplane Flight Manual Supplement for Cessna 650 Citation III, Doc. No C650-01-0601 Revision 0, dated 17.03.2005 or later approvedrevision.- Instructions for Continuous Airworthiness, Doc. No C650-01-0701, Revision 0, dated 17.03.2005 or later approved revision.		11/04/2005	Active	10014062
EASA.A.S.01149	MOTORFLUG BADEN-BADEN GmbH			650	Installation of Allied Signal Solid State Flight Data Recorder.		-Airplane Flight Manual Supplement for Cessna 650 Citation III, Doc. No C650-02-0601 Revision 0, dated 02.03.2005 or later approvedrevision.- Instructions for Continuous Airworthiness, Doc. No C650-02-0701, Revision 0, dated 02.03.2005 or later approved revision.		11/04/2005	Active	10014063
EASA.A.S.01150	MOTORFLUG BADEN-BADEN GmbH			650	Installation of Allied Signal AR120 Solid State Cockpit Voice Recorder.		-Airplane Flight Manual Supplement for Cessna 650 Citation III, Doc. No C650-03-0601 Revision 0, dated 12.03.2005 or later approvedrevision.- Instructions for Continuous Airworthiness, Doc. No C650-03-0701, Revision 0, dated 12.03.2005 or later approved revision.		11/04/2005	Active	10014064
EASA.A.S.01151	SOCIETE AIR FRANCE S.A.			AIRBUS A320	Cabin passenger seats relocation and floor proximity emergency escape path marking change		Change approval sheet No CAS-A320-05-001 revision 1, dated March 22, 2005		07/04/2005	Active	10014065
EASA.A.S.01154	AVIATION DEFENSE SERVICE	REV. 2		B200 / 200	Installation of an Emergency Locator ELT 96 - 406 MhZ.		Modification File AVD-MB200-23-046A. Supplemental AFM No. 1,3, & 6.	This STC is limited to Beechcraft 200 MSN BB 199, Beechcraft B200 MSN BB920 and Beechcraft 200 s/n BB439.	15/03/2005	Active	10014067
EASA.A.S.01155	AVIATION DEFENSE SERVICE			B200 / 200	Installation of 2 Mode S transponders MST 67A.		Modification AVD-MB200-34-045A, Revision b, dated 20th May 2005 or later EASA-approved revision.Supplemental Maintenance Manual, Edition 4 Revision 2.	1. This STC requires a pre-modification: 2 bottom transponder antennas.2. This STC is limited to Beech s/n BB199 and Beech 200 s/n BB439.	28/07/2005	Active	10014068
EASA.A.S.01157	AVIATION DEFENSE SERVICE			C90, E90	Installation of an Emergency Locator ELT 96-406 MhZ.		-Modification file AVD-MB90-23-042A-Supplemental AFM No 2 &3	This STC is limited to Beechcraft C90 s/n LJ860 and Beechcraft E90 s/n LW251.	28/07/2005	Active	10014069
EASA.A.S.01158	AVIATION DEFENSE SERVICE			C90	Installation of Mode S Transponder MST 67A.		Modification AVD-MB200-34-047A, revision a dated 20 June 2005 or later EASA approved revision.	1. This STC requires a pre-modification: 2 bottom transponders antennas.2. This Modification is limited to Beechcraft C90 s/n LJ860.	22/07/2005	Active	10014070

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01161	DASSAULT FALCON SERVICE			FALCON 10	DFS 1255 dtd. 29.3.06: Installation of two FMS UNS-1L Soft 802.X / B-RNAV & P-RNAV		see Change approval sheet DFS 1255-AFM Supp F10 DFS 32 toDTM 721(A) "Two FMS UNS-1L Operation / DFS 1255 incorporated"-Wiring Diagram DFS 10 600 34-56-01 & DFS 10 600 34-56-11and associated list of affected technical documents	1. This STC is approved only for the configuration as defined in Mod Sheet DFS 1255. Compatibility with other aircraft/ engine configurations shall be determined by the installer	02/05/2006	Active	10014071
EASA.A.S.01163	DASSAULT FALCON SERVICE	REV. 1		FALCON 10	DFS 1252 dtd. 9.6.05: EFIS Universal EFI 550/600		see Change approval sheet DFS 1252-AFM Supp F10 DFS 30 toDTM 721(A) with DFS 1252"concernant utilisation de l'avion equipe d' EFI UNIVERSAL 550/560"-Wiring Diagram DFS 10 600 24-61-01, 34-21-10, 34-21-20 and associated list of affected technical documents	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	11/01/2007	Active	10014072
EASA.A.S.01165	ATLANTIC AEROENGINEERING LIMITED		CAA UK RESPONSIBILITY	JETSTREAM 3100 SERIES	Installation of a Honeywell MK-VI GPWS & Honeywell RT 300 Radio Altimeter		-Atlantic Aeroengineering Definition Document DD/ AAE/418 Issue 2 dated March 10 2005 or later approved revision-AAE Flight manual Supplemetn AAE 6 Issue 1 or later approved revision		06/04/2005	Active	10014073
EASA.A.S.01167	E.I.S.A.	REV 1		FALCON 10	Installation of a TCAS 4000 unit from Rockwell/CollinsInstallation of a TCAS 4000 unit from Rockwell/Collins		- Data List EISA 06 SDL S085 Rev. 7- AFM supplement EISA 06AFM S085 Rev. 4- Antenna Installation according to the EISASTC no. EASA.A.S. 0070- Data List EISA 06 SDL S085 Rev. 7- AFM supplement EISA 06 AFM S085 Rev. 4- Antenna Installation according to the EISA STC no. EASA.A.S. 0070		30/06/2006	Orphaned	10014075
EASA.A.S.01168	EADS SOGERMA	REV 1		AIRBUS A330-243	Cabin configuration for Gulf Air. All documents related to this STC are listed in the Modification SOG-25-1075 iss. 01 (or later EASA-aproved revision).Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.Model: Airbus A330-243 MSN 276, 281, 286,287, 3...		Modification SOG-25-1075 iss. 01 (or later EASA-aproved revision)	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	07/01/2008	Active	10014076
EASA.A.S.01169	EADS SOGERMA	REV 1		AIRBUS A310	Installation of an ATC Mode S EHS. ATC mode S modification for compliance with Enhance Surveillance. Replacement of theRockwell Collins TRP-720 ATC by TRP-901 ATC.Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.		Modification Approval Sheet SOG-34-866 Issue 02. Aircraft Flight Manual Supplement: AFM-34-52-00 Issue A dated 15/07/2004. Compliance Statement CS-34-866-01 Issue A.		07/01/2008	Active	10014077
EASA.A.S.01171	LUFTHANSA TECHNIK AG			BOEING 777-300	Installation of PC Power and PC Data Outlets on the existing B/C Seats and installation of new ECO Class Seats with newP/N and PC-Power/PC-Data Outlets on Boeing 777-300 A/C of Cathay Pacific Airways.		-Supplemental Type Definition Document No STDD25-03/09M, Issue 01/ Rev. 1 or later approved Revisions.		01/03/2005	Active	10014079
EASA.A.S.01172	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	737-300, 737-400, 737-500	Aero Engineering Design Modification 34-1-226.SSR Mode S Enhanced Surveillance		Aero Engineering Design Modification Certificate 34-13-226 Issue 1 dated May 9 2005 or later approved revision		21/06/2005	Active	10014080

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01173	AERO ENGINEERING DESIGN LIMITED		CAA UK RESPONSIBILITY	BAE HS 748	Installation of a Honeywell MK VI EGPWS		-AED Design Modification Certificate 34-22-225 dated Februart 10, 2005 or later approved revision-Aero Engineering Design Flight Manual Supplement AED/748/005 Issue 1 or later approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	02/03/2005	Active	10014081
EASA.A.S.01174	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 737-200	Revised Seating Layout of 124 Seats and 130 Seats using BAC1288 Series Seats		-Bournemouth Aviation (Consultants) Compliance Document BAC/737/035 dated March 3 2005 or later approved revision		17/03/2005	Active	10014082
EASA.A.S.01175	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 737-200	Deactivation of Type III Exits & Installation of a 60 Seat VIP Passenger configuration.		- Bournemouth Aviation Consultants Compliance Document Ref.: BAC/737/036 Top Drawing BAC 1289-01.		03/03/2005	Active	10014083
EASA.A.S.01176	RUAG AEROSPACE SERVICES GmbH	REV. 1		BOMBARDIER CL-600-2B16 (601-3R BOMBARDIER CL-600-2B16 (601-3A BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Upgrade of the two existing Mode-S Transponders ACSS RCZ-852 by ACSS Service Bulletin 8002246-001 for ELS/EHS.Replacement of the Controller, Collins CTL-92 by Mode S Controller, Collins CTL-92E.ACSS Mode-S transponder RCZ-852 ELS/EHS with Collins CTL-92E.		-Master Document List, Doc No 043A-MDL Rev. N/C or later EASA approved Revisions-Airplane Flight Manual Supplement Document No 043A-AFMS, Rev. A or later EASA approved Revisions-RUAG Master Document List No. 191C-MDL Revision A or later approved revision. RUAG Airplane Flight Manual Supplement No. 0...		29/02/2008	Active	10014085
EASA.A.S.01177	JET AVIATION VIENNA GMBH			550	Integration of a TCAS and Upgrade of Mode S Transponders toElementary Surveillance		- 5597/04/1-12 Instructions for Continued Airworthiness-5597/04/1-06 Airplane Flight Manual Supplement		10/03/2005	Active	10014086
EASA.A.S.01179	EADS SOGERMA	REV 1		DC-9-21	ELT Kannad 406 AF modification (SOG-25-1106)Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.		Airplane Flight Manual Supplement ref FMS 25-1106 issue C, dated November 11, 2005	1. This STC is limited to the DC-9 MSN 4708	04/01/2008	Active	10014087
EASA.A.S.01182	BUSINESS AND COMMUTER AIRCRAFT			BEECH C90 A BEECH C90	Installation of Weather Radar RDR-2000		-Modification File No 50/BCA - rev 2 or later approved revision	Modification limited to Beech C90 S/N LJ-684 and Becch C90AS/N LJ-1526	17/03/2005	Active	10014088
EASA.A.S.01185	AVIONIK STRAUBING ENTWICKLUNGS GmbH			501, 551	Installation of Artex ELT C406-1.		EASA-approved Flight Manual Supplement FMS ASR 2005-007-00,Rev. A, or later EASA-approved revision.		28/04/2005	Active	10014089
EASA.A.S.01189	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		CESSNA S550 CESSNA 560 CESSNA 550 CESSNA 500	Installation of Kannad 406 AF ELT		-Engineering Order 2022014 - EO - 02.-AFM Supplement, Doc. No 2022014 - AM - 02.-Continued Airworthiness Report Doc. No2022014 - CA - 02.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	07/04/2005	Active	10014091
EASA.A.S.01190	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 650	Installation of FreeFlight 2101 I/O APPROACH PLUS GPS Navigation System		- Scandinavian Avionics Engineering Order No. 2019034-EO-03, Issue No. 2, dated August 3, 2005-Approved AirplaneFlight Manual Supplement for FreeFlight 2101 I/O APPROACH PLUS GPS Navigation System	-	25/08/2005	Active	10014092

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01191	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 650	Installation of Honeywell CAS 67A TCAS II System, includingDual MST 67A Mode S Transponders		- Scandinavian Avionics Engineering Order No. 2015055-EO-01, Issue 1, dated October 8, 2004-Approved Airplane Flight Manual Supplement for HONEYWELL MST 67A MODE - S Transponder with PS550 Control, Doc. No. 2015055-AM-01B-Approved Airplane Flight Manual Supplement for HONEYWELL CAS 67A AC...	-	25/08/2005	Active	10014093
EASA.A.S.01192	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	STC ST46MOD001 Issue 01: A300-600ST / Data Link System. This controller data link communication based on VDL mode 2 project is led by Eurocontrol. The crew will be able to exchange data and messages with a ground-based station airline operation centre and air traffic services.		Change Approval Sheet No ST46MOD001 issue 01. Supplement Aircraft Flight Manual A300-600ST, dated 24/03/2005.	This STC is approved only for A300F4-608ST.	12/04/2005	Active	10014094
EASA.A.S.01193	SCANDINAVIAN AVIONICS DESIGN ApS			BAE ATP	Installation of Universal Terrain Awareness Warning System (TAWS)		-Engineering Order Doc 2024352-EO-01 Issue 2 or later EASA aproved revisions-AFM Supplement Document No 2024352-AM-01 Issue 2 or later EASA approved revisions -Continued Airworthiness Document No 2024352-CA-01 Issue 1		26/07/2005	Active	10014095
EASA.A.S.01194	SCANDINAVIAN AVIONICS DESIGN ApS			BAE ATP JETSTREAM SERIES 6100	Installation of Universal UNS-1L Flight Management System		-Engineering Order Doc 2024345-EO-02 Issue 2 or later EASA approved revision-AFM Supplement Document No 2024345-AM-02 Issue 2 or later EASA approved revision-Continued Airworthiness Document No 2024345-CA-02	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	26/07/2005	Active	10014096
EASA.A.S.01199	MOTORFLUG BADEN-BADEN GmbH			550, 560	Installation of Allied Signal SSUFDR		Master Document List C550-122401-0107 Rev. 0 or later approved RevisionFlight Manual Supplement C550-122401-0601 Rev. 0or later approved Revision	Certification Basis of the Change: FAR 25 as defined in FAATCDS A22CE Rev. 44	19/04/2006	Active	10014098
EASA.A.S.01200	DASSAULT FALCON SERVICE			FALCON 10	Installation of Collins ATC with flight ID and Gables Control Panel		-Change Approval Sheet DFS 1260 issue original dated 31 March 2005.	STC applicable only to Falcon 10 aircraft equipped with:-2Collins ATC TDR-94D p/n 622-9210-001/002/003 or 004.-and ATC control box Gables G7 130-XX.	11/04/2005	Active	10014099
EASA.A.S.01202	MT-PROPELLER ENTWICKLUNG GmbH			SOCATA TB 21	Installation of MTV-9-B/198-52 hydraulically controlled 3-blade constant speed propeller		-Instructions for Continued Airworthiness and Installation Instructions No E-1189-Airplane Flight Manual Supplement No E-1187-German "Anhang zum Flughandbuch" No E-1186		01/08/2005	Active	10014100
EASA.A.S.01203	AERO-DIENST GMBH & CO. KG			60	Installlation of an Iridium Satelitte ICS-200 System.		Aerodienst Engineering Order No 202-LR, Rev. IR, or later EASA-approved revisions.	For certification basis refer to FAA TCDS A10CE plus FAR 25.1309 at Amdt. 25-41 and FAR 25.1529 at Amdt. 25-54.	28/04/2005	Active	10014101

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01204	AERO-DIENST GMBH & CO. KG			LEARJET 60	Installation of a SSFDR F1000 System.		Aerodienst Engineering Order No 197-LR, Rev.IR, or later EASA-approvedrevisions.	1. The certification basis refers to FAA TCDS A10CE plus FAR 25.1309 atAmdt. 25-41 and FAR 25.1529 at Amdt. 25-542. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine config...	28/04/2005	Active	10043017
EASA.A.S.01206	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	BEECH 400A (HAWKER 400 XP)	Certification for Steep Approaches		-Raytheon Aircraft Services Change SC0252A-Raytheon Aircraft Services AFM Supplement reference 128-59001-167		26/07/2005	Active	10014102
EASA.A.S.01207	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	BAE 125 SERIES 800B	Raytheon Aircraft Services Modification SC0135R. Runway Awareness & Advisory System (RAAS) to the MK VII EGPWS Computer		RAS Certification Plan ASC-C-008-AW1499 Issue 1 dated February 2005 or later approved revision.RAS AFM Supplement 16 Issue 1 to AFM ref HS.1.15		21/06/2005	Active	10014103
EASA.A.S.01208	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	HAWKER HS 125-700B	Installation of a Collins AHS-3000A Attitude Heading Reference System.		Certification Plan ASC-C-007-AV1490 Issue 1, dated February28, 2005 or later EASA approved revisions.Change SC0194U dated May 20, 2005 or later EASA approved Revisions.		13/06/2005	Active	10014104
EASA.A.S.01209	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	HAWKER HS 125-700B	Installation of Traffic Alert & Collision Avoidance System (TCAS-4000), Mode S Elementary Surveillance (Flight ID) and Emergency Locator Transmitter (Artex C406-2)		Certification Plan ASC-C-007-AV1518 Issue 1 Dated February 18 2005 or later approved revision		23/03/2005	Active	10014105
EASA.A.S.01211	AEROTEC & CONCEPT			BEECH 95-B55	Radio and navigation change with BRNAV capacity and STEC 55X automatic pilot steered		Modification File No. AEROTEC STC0505Airplane Flight ManualSupplement No Modification 0505, edition 1, revision 0, dated 31st March 2005 or later approved revision	Modification limited to s/n TC1143AFMS No modification 0505must be on board	26/09/2006	Active	10014106
EASA.A.S.01212	MT-PROPELLER ENTWICKLUNG GmbH			MOONEY M20M	Installation of propeller MTV-14-B/ 185-59b		Anhang zum Flughandbuch Nr. E-1221Airplane Flight Manual Supplement No. E-1222Umruest- und Wartungsanweisung E-1223Instructions for Continued Airworthiness and Installation Instructions E-1224		02/11/2005	Active	10014107
EASA.A.S.01213	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 650	Installation of SATCOM Universal TT-3000		Airplane Flight Manual Supplement Doc. No. 2005-18-8 Rev. Aor later approved RevisionMaintenance Manual Supplement DocNo. 2005-18-10 Revision A		16/11/2005	Active	10014108
EASA.A.S.01214	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 650	Installation of Airshow Entertainer System		Engineering Data Report 2005-17, Rev. BAirplane Flight Manual Supplement Report 2005-17-8, Rev. A or later EASA approved revisionMaintenance Manual Supplement Report 2005-17-10, Rev. A	Part 25 of the Federal Aviation Regulations effective February 1, 1965 as amended by Amendments 25-1 through 25-39; TGMJAA leafletNo. 17Weight and Balance Analysis, Report 2005-17-9, Rev. A	13/03/2006	Active	10014109

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01215	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 550-560-S550	Installation of ACAS II CAS 67A and Dual Mode - S Transponder RCZ-833		Airplane Flight Manual Supplement Cessna C550, S550, C560 with Honeywell CAS 67A and Dual RCZ 833(), Report No. 2005-1-8 Revision A, dated June 20, 2005 or later approved Revision		23/09/2005	Active	10014110
EASA.A.S.01216	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B300 BEECH 300	Installation of Honeywell CAS 67A ACAS/ TCAS II with Dual MST-67A Mode S Transponder		EAS approved Flight Manual Supplement CAS 67A ACAS II System Doc No 2023423-AM-01 Issue 2 or later EASA approved issueEASA approved Flight Manual Supplement MST67A Mode S Transponder with PS 550 Control Doc No 2023423-AM-02 Issue 2 or later EASA approved issue		30/05/2005	Active	10014111
EASA.A.S.01217	ELECTRONIQUE MAINTENANCE AVIATION			BEECH E90 BEECH C90	Allied Signal KT73 ATC Mode S, Kannad 406AF ELT 406 and 2 IDC 570 altimeters installation.		EMA/05/002/BEECH90/ ATC.ELT Revision 1	This STC is limited to Beech C90 MSN LJ667 & Beech E90 MSN LW 278.	13/06/2005	Active	10014112
EASA.A.S.01219	EADS SOGERMA	REV 1		ATR 42-320 SERIES	Pseudo-Lisse configuration; RESSAC configuration and RALI configuration.Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.Model:Aerospatiale ATR 42-320 MSN 078		AFM Supplement for Pseudo-Lisse configuration referred 238/04/SOG/DEV Issue7AFM Supplement for RESSAC configuration referred 239/04/SOG/DEV Issue 2.AFM Supplement for RALI configuration referred 240/04/SOG/DEV Issue 2.Weight & Balance Supplement for Pseudo-Lisse, RESSAC and RALI configurations refer...	1. In RALI configuration:-the mass of under wing POD is limited to 72kg (POD equipped);-the new design for the titanium pin on POD rear attachment must be applied according to the EADS Sogerma Services waiver No. A3002.2. The lighting issues are certified for mechanical and electrical provisio...	04/01/2008	Active	10014113
EASA.A.S.01220	EADS SOGERMA	REV 1		AEROSPATIALE ATR 42-320	ELT Kannad 406 AF ModificationNote: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services. Model: Aerospatiale ATR 42-320 MSN 078		Technical Repercussion Sheet referred SOG-25-1104Master Drawing List MDI-25-1104, Issue No A dated February 2, 2005	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	04/01/2008	Active	10014114
EASA.A.S.01221	MONARCH AIRCRAFT ENGINEERING LTD		CAA UK RESPONSIBILITY	BOEING 737-522	Installation of Honeywell EGPWS		-Monarch Aircraft Engineering Modification MON/737/34/3013 Issue A dated March 3 2005 or later approved revision-Monarch Aircraft Engineering Flight Manual Supplement number 1 Issue 1 reference MON -34-49-2785 or later approved revision		06/04/2005	Active	10014115
EASA.A.S.01222	MONARCH AIRCRAFT ENGINEERING LTD		CAA UK RESPONSIBILITY	BOEING 737-522	Introduction of 131 Passenger Configuration		-Monarch Aircraft Engineering Modification MON/737/25/3016		01/04/2005	Active	10014116
EASA.A.S.01224	DASSAULT FALCON SERVICE			FALCON 10	DFS 1251 dtd. 2.6.05: Installation of a Multi functional display MFD 640		see Change approval sheet DFS 1251-Wiring Diagram DFS 10 600 34-41-21and associated list of affected technical documents	1. This STC is approved only for the configuration as defined in Mod Sheet DFS 1251. Compatibility with other aircraft/ engine configurations shall be determined by the installer	02/05/2006	Active	10014117
EASA.A.S.01225	DASSAULT FALCON SERVICE			MYSTERE FALCON 900	EGPWS Software Evolution (222-222)		Change Approval Sheet DFS 9472 CAS issue Original dated 13-September 05Airplane Flight Manual DTM 20103 DFS Supplement No 21	Applicable to MF900 equipped with EGPWS Mark V soft 212-212installed with DFS 9259 STC	12/12/2005	Active	10014118

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01226	DASSAULT FALCON SERVICE			MYSTERE FALCON 900	Incorporation of RAAS function on EGPWS soft 222-222		Change Approval Sheet DFS 9470 CAS issue Original dated April 14, 2006Airplane Flight Manual DTM 20103 DFS Supplement n°22 dated June 14, 2006	Applicable to MF900 equipped with EGPWS Mark V soft 222-222installed with DFS 9472 STC	06/10/2006	Active	10014119
EASA.A.S.01230	ATS INTERNATIONAL	REV 2		AIRBUS A318-319-320-321	MK V EGPWS System Installation		Master Data List, ref. 0226-01-A-2103 revision 06, dated January 2, 2006 or later EASA approved revisionAirplane FlightManual Supplement (FMS source only), ref. 0226-01-A-2301 revision 03, dated July 21, 2005 or later EASA approved revisionAirplane Flight Manual Supplement (with GPS source), ref. 0...		01/03/2006	Active	10014120
EASA.A.S.01231	BUSINESS AND COMMUTER AIRCRAFT			BEECH C90 A	Skywatch SKY497 TCAS I installation on Beech C90A		Modification file No 68/BCA revision 0 of 15th February 2005	1. AFMS No 68/BCA rev 0 of April 2005 must be used when modification is installed2. Modification is limited to Beech C90A S/N LJ-1526	30/05/2005	Active	10014121
EASA.A.S.01234	E A D AEROSPACE AIRWORTHINESS			AIRBUS A310 AIRBUS A300-600	Modification of ELT ADT406 AF on A300/ A310Installation of ELT ADT 406 AF		-Modification 01029-MDL 01029-EAS-TMD-AFM Supplement 01029-EAS-A-AFM-01 Revision A-MPD Supplement 01029-EAS-A-MPD-01 Revision A		28/07/2005	Active	10014124
EASA.A.S.01236	LUFTHANSA TECHNIK AG			BOEING 747-SP BOEING 747-2B4B	Flight Management System (FMS), Activation of Advisory VNAVModeaccording to Lufthansa Technik Supplemental Type Definition Document STDD34-05/02M, Issue 01, Rev 00, dated April 20, 2005 or laterapproved revision		Airplane Flight Manual supplement A-34-05/221-AFM, revisionIR, dated April 06/05 or later approved revisionInstructions for Continued Airworthiness Doc. No. CS34-0381-01, dated 05.04.2005		30/05/2005	Active	10014126
EASA.A.S.01237	AIRBUS S.A.S.	REV. 1		A321-231	Satcom in accordance with Morification Approval Sheet (MAS)ref. : SOG-00-794 issue 3, dated March 18, 2005.			This STC is limited to A321-231 MSN 1202	04/07/2008	Active	10014127
EASA.A.S.01238	STC TWENTY ONE LIMITED	REV 1	CAA UK RESPONSIBILITY	DC-9-80 (MD-80) SERIES	Introduction of FlightVu Cabin Surveillance System		Aero Engineering Design Modification Certificate 25-77-433 dated April 12,2005 or later approved revision		21/06/2006	Active	10014128
EASA.A.S.01239	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 757-200	Introduction of SSR Mode S Enhanced Surveillance		-Aero Engineering Design Modification Certificate 34-15-233-Aero Enginering Design AFM Supllement AED/B757/004 Issue 1 or later approved revision		30/05/2005	Active	10014129
EASA.A.S.01240	AERO ENGINEERING DESIGN LIMITED		CAA UK RESPONSIBILITY	BOEING 727-200	Installation of Honeywell MK VII EGPWS.		Design Modification Certificate 34-12-237 Issue 1 11/04/2005. AFM-AED/ B727/001.		22/04/2005	Active	10014130
EASA.A.S.01241	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BAE ATP	Rework to Landing Gear Emergency Up-Lock Release Mechanism		STC 21 Master Document List S21.MDL-0013STC21 AFM Supplement S21.FMS-ATP-006		15/11/2005	Active	10014131
EASA.A.S.01242	AERO-DIENST GMBH & CO. KG			HS.125 SERIES 700B	Installation of Traffic Alert Collision and Avoidance System Collins TCAS 4000		Engineering Order Doc No 171-HW Rev 1 or later EASA approved revisionAirplane Flight Manual Supplement Doc No AG352-071Rev IR or later EASA approved revisions		30/05/2005	Active	10014132
EASA.A.S.01244	AZUR AERO ASSISTANCE			CESSNA 500, CITATION	Installation of Radar RDR 2000 Bendix/ King with radar screen KMD 540/850 Bndix/King in accordance with MDL AAA 08/2004 ed 1 Rev 1 dated 10/10/05		AFM Supplemental AAA 08/2004 Ed 1 dated 20/10/2004	This STC is limited to MSN 308.	10/11/2005	Active	10014133

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01245	AZUR AERO ASSISTANCE			CESSNA 500, CITATION	Installation of Mode S Transponder GTX 330 Garmin in accordance with MDL AAA 07/2004 Ed 1 Rev. 1 dated 10/10/2005		AFM Supplement AAA 07/2004 Ed 1 dated 19/10/2004	This STC is limited to MSN 308.	10/11/2005	Active	10014134
EASA.A.S.01246	AZUR AERO ASSISTANCE			500	Installation of GPS GNS 430 GARMIN in accordance with MDL AAA 06/2004 Ed 1 Rev 1 dated 10/10/2005		AFM Supplement AAA 06/2004 Ed 1 dated 19/10/2004	This STC is limited to MSN 308.	10/11/2005	Active	10014135
EASA.A.S.01247	AZUR AERO ASSISTANCE			500	Installation of GPS GNS 530 BRNAV GARMIN in accordance with MDL AAA 05/2004 Ed 1 Rev 1 dated 10/10/2005		AFM Supplement AAA 05/2004 Ed 1 dated 19/10/2004	This STC is limited to MSN 308	10/11/2005	Active	10014136
EASA.A.S.01248	DASSAULT FALCON SERVICE			FALCON 10	DFS 1250 dtd. 22.3.06: Weather Radar Primus 660		see Change approval sheet DFS 1250-Wiring Diagram DFS10 60034-41-21-XXand associated list of affected technical documents	1. This STC is approved only for the configuration as defined in Mod Sheet DFS 1250. Compatibility with other aircraft/ engine configurations shall be determined by the installer	02/05/2006	Active	10014137
EASA.A.S.01253	AIRBUS S.A.S.	REV. 1		A340-541	DA WLAT Qatar Airways Modifications in accordance with Modification Approval Sheet Ref. SOG-01-0648		"Modification Approval Sheet, Doc Ref. SOG-01-0648, Issue 1dated 17 March 2006	The applicability of this STC is limited to MSN 495No more than 10 Laptops equipped with WiFi system are allowed in thecabin	04/07/2008	Active	10014140
EASA.A.S.01254	DASSAULT FALCON SERVICE			MYSTERE FALCON 20-5	Installation of one FMS Universal UNS-1L SOFT 802.X in accordance with the Change Approval Sheet -Original- or later EASA approved revisions.		-Change Approval Sheet DFS 529, dated May 03, 2005-AFM Supplement No 32,Temporary AFMS dated May 12th 2005 or later EASA approved revisions	Operation of the Flight Management System in the Approach Mode is not allowed	19/05/2005	Active	10014141
EASA.A.S.01262	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			LEARJET 55	Installation of Secondary UNS 1F		Engineering Order 2005-3, Rev. A, or later EASA approved revisions, AFMS 2005-3-8, Rev. A, or later EASA approved revisions		23/06/2005	Active	10014144
EASA.A.S.01263	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			LEARJET 55	Installation of ELT 406		Engineering Order 2005-2, Rev. A, or later EASA approved revisions, AFMS 2005-2-8, Rev. A, or later EASA approved revisions		29/06/2005	Active	10014145
EASA.A.S.01265	AVIATION DEFENSE SERVICE			C90	Replacement of Primus 40 weather radar by a Primus weather Radar.		Modification File No. AVD-MB90-34-048A revision A ot 4 July2005 or later EASA approved Revision.	This STC is limited to Beechcraft C90 s/n LJ860.	28/07/2005	Active	10014146
EASA.A.S.0127	SOGERMA SERVICES	REV 1		AIRBUS A320-211	Cabin layout change from 144 pax to 155 pax configuration in accordance with the Master Drawing List ref. MDL-25-861, issue B, dated August 6, 2004 or later EASA approved revision.Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.				07/01/2008	Active	10014149
EASA.A.S.01270	EAD AEROSPACE			A300/310	EGPWS Installation on Airbus A300/A310		Top Master Drawing List 00846-JAA-MDL Rev. D. AFM Supplement DC113-0846 Rev. B. Maintenance Planning Document Supplement DC114-0846-00 rev. A.	Refer to AFM Supplement Ref. Dc113-0846 Rev B and to Maintenance Planning Document Supplement DC114-0846-00 rev A.	28/04/2005	Active	10014150
EASA.A.S.01271	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B300 BEECH B200 BEECH 300 BEECH 200	Installation of Dual GTX 330D Mode S Transponder System.		AFM Supplement Dual GTX 330D Mode S Transponder Doc. No. 2026288--AM-01 Issue 3 or later EASA approved revisions.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	29/06/2005	Active	10014151
EASA.A.S.01273	DASSAULT FALCON SERVICE			FALCON 2000	DFSD066 dtd. 19. October 05: Airview Communication and Security System		see Change approval sheet DFSD066:DFS AFM Supplement F20003 to DTM 537and associated list of affected technical documents	1. This STC is limited to Falcon 2000 S/N 0012. This STC isapproved only for the configuration as defined in Mod SheetDFSD066	08/11/2005	Active	10014152

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01274	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			GULFSTREAM ASTRA/ SPX	Upgrade of Universal UNS-1C to 1C+		Engineering Order Report 2005-4, Rev.A dated 22. March 2005or later EASA approved RevisionsAirplane Flight Manual Supplement Report 2005-4-8, Revision A dated 22. March 2005 or later EASA approved RevisionsMaintenance Manual Supplement Report 2005-4-10		21/09/2005	Active	10014153
EASA.A.S.01275	MARSHALL OF CAMBRIDGE AEROSPACELIMITED		CAA UK RESPONSIBILITY	SOCATA MS 894A	Marshall Aerospace Modification MA 1665. Radio Equipment Upgrade.		Marshall Aerospace Modification MA 1665.Marshall Aerospace AFM Supplement AFMS/ SOC (1665)/05/0556		26/07/2005	Active	10014154
EASA.A.S.01277	MONARCH AIRCRAFT ENGINEERING LTD		CAA UK RESPONSIBILITY	BOEING 767-300	Monarch Aircraft Engineering Modification MON/767/258/2995 Installation of a 38 Premium Class Cabin		Monarch Aircraft Engineering Modification MON/767/25/2995	Subject AFM supplement is associated to Dassault Aviation Mod M1632: "Installation d'un hublot inférieur avec volet de protection",applicable to F20 GF SN 397 only	29/06/2005	Active	10014155
EASA.A.S.01280	DASSAULT FALCON SERVICE			MYSTERE FALCON 200	AFM supplement associated to Dassault Aviation Mod M1632 "Installation d'un hublot inférieur avec volet de protection".		Subject AFM supplement is associated to Dassault Aviation Mod M1632: "Installation d'un hublot inférieur avec volet de protection",applicable to F20 GF SN 397 only	Subject AFM supplement is associated to Dassault Aviation Mod M1632: "Installation d'un hublot inférieur avec volet de protection",applicable to F20 GF SN 397 only	21/06/2005	Active	10014156
EASA.A.S.01283	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	BAE 125 SERIES 800B	Special Interior Refurbishement		- Certification Plan ASC-C-008-AW1476 Issue 1 Dated February 2005 or later approved revision.- Instructions for Continued Airworthiness ASC-008-AW1484 Issue 1 dated April 18, 2005 or later approved revision.- Change number. SC0246A.		28/04/2005	Active	10014157
EASA.A.S.01286	LUFTHANSA TECHNIK AG			BOEING 767-300	B-767- Cabin Layout Change - Air Europe		Supplemenal Type Definition Document Doc. No. STDD 00-05/03M, Issue 1. Instructions for Continued Airworthiness Doc. No. ICA 25-1009-00 dated May 30, 2005 or later approved issue		21/06/2005	Active	10014158
EASA.A.S.01291	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	FALCON 20	FR Aviation Modification Reference DC0032 Introduction of Flight ManualSupplement FRAH/FM/106		Approved Flight Manual Reference DTM918 FR Aviation Flight ManualSupplement FRAH/ FM/106 Revision 0 dated June 2005 or later approvedrevision	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	05/07/2005	Active	10043018
EASA.A.S.01293	RUAG AEROSPACE SERVICES GmbH			BOEING DC-9-83 (MD-83) BOEING DC-9-82 (MD-82)	Installation of Mode S Transponder ACSS XS-950 ELS/EHS withControl Gables G7490-66 including associated Airplane Flight Manual Supplement		RUAG Master Document List Doc No 042A-MDLRUAG Airplane Flight Manual Supplement Doc No 042A-AFMS, Rev N/C dated 1 June 2005		28/06/2005	Active	10014161
EASA.A.S.01294	SCANDINAVIAN AVIONICS DESIGN ApS			BAE 125 -800 SERIES	Installation of a Rockwell Collins TCAS 4000 with dual TDR-94D Mode S Transponder		-Engineering Order Doc No 2025716-EO-01 dated 09.03.2005 Issue 1 or later EASA approved revisions- Airplane Flight Manual Supplement/TCAS 4000 Doc No 2025716-AM-01A issue 2 or later EASA approved revisions- Airplane Flight Manual Supplement/Dual TDR		26/07/2005	Active	10014162

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01296	AIRBUS S.A.S.	REV. 1		A340-541	DA WLAT Qatar Airways Live TV Modifications in accordance with Modification Approval Sheet Ref. SOG-23-690		"Modification Approval Sheet, Doc Ref. SOG-23-690, Issue 1 dated 17 March 2006Master Drawing List, Doc. Ref. MDL MOD SOG-23-690, Issue AAirplane Flight Manual Supplement, Doc. Ref. FM-S MOD-SOG-23-690, Rev. 0 dated 21 September 2005"	The applicability of this STC is limited to MSN 495	04/07/2008	Active	10014164
EASA.A.S.01297	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	AIRBUS A300-600	Installation of a Galley bulkhead.		AIM Aviation (Henshalls) Definition Document DD 1011 Issue New, dated 12, April 2005 or later EASA approved revisions.	1. Viewing of all Placards and signage to be in compliance with CS/FAR 25.791 Weight, Centre Gravity and Weight Distribution to be in Compliance with CS/FAR 25.1519.2. Compliance with CS/FAR 25.785 (d) (3), the elimination of any injuriousabject within striking radius of the head.3. Compliance with...	08/06/2005	Active	10014165
EASA.A.S.01299	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	BOEING 767-300	Installation of Stowage C2.		AIM Aviation (Henshalls) Definitiion Document DD 1009 IssueNew, dated April 5, 2005 or later EASA approved revisions.	1. Viewing of all Placards and signage to be in compliance with CS/FAR 25.791 Weight, Centre Gravity and Weight Distribution to be in Compliance with CS/FAR 25.1519.2. Compliance with CS/FAR 25.785 (d) (3), the elimination of any injuriousabject within striking radius of the head.3. Compliance with...	08/06/2005	Active	10014166
EASA.A.S.01300	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	BOEING 737-500	Installation of Galley 3.		AIM Aviation (Hendshalls) Definition Document DD 1010 IssueNew dated April 11, 2005 or later EASA aproved revisions.	1. Viewing of all Placards and signage to be in compliance with CS/FAR 25.791 Weight, Centre Gravity and Weight Distribution to be in Compliance with CS/FAR 25.1519.2. Compliance with CS/FAR 25.785 (d) (3), the elimination of any injuriousabject within striking radius of the head.3. Compliance with...	14/06/2005	Active	10014167
EASA.A.S.01301	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	BOEING 737-500	Installation of Wardrobe W1.		AIM Aviation (Henshalls) Definitiion Document DD 1015 IssueNew, dated April 25, 2005 or later EASA approved revisions.	1. Viewing of all Placards and signage to be in compliance with CS/FAR 25.791 Weight, Centre Gravity and Weight Distribution to be in Compliance with CS/FAR 25.1519.2. Compliance with CS/FAR 25.785 (d) (3), the elimination of any injuriousabject within striking radius of the head.3. Compliance with...	08/06/2005	Active	10014168
EASA.A.S.01302	EADS SOGERMA	REV 1		AIRBUS A321-200	A321 Livingston - Cabin Modification from 196 Y/C to 210 Y/C with relocation of two attendant seats.Note: This revisionreflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.Model: Airbus A321-200 MSN 1950 & 1970		Modification Approval Sheet (MAS) Ref. SOG-25-1102 Issue 01, dated May 16, 2005	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	04/01/2008	Active	10014169
EASA.A.S.01303	DASSAULT FALCON SERVICE			FALCON 10	Antenna installation		Associated to: see Change approval sheet DFS 1263 associated list of affected technical documents	1. This STC is approved only for the configuration as defined in Mod Sheet DFS 1263.2. Compatibility with other aircraft/ engine configurations shall be determined by the installer.	10/08/2005	Active	10014170

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01304	EADS SOGERMA	REV 1		AIRBUS A330-200	Installation of a Cabin modification from 24B/C - 248Y/C to18B/C - 271Y/C with removal of galley G2 and installation of new partitions for LAUDA AIR fleet. The associated modification Approval sheet is referenced SOG-25-1122 issue1 dated 10/06/05. All documents related to this STC are listed in the...		Technical repercussion sheet reference 25-1122.		04/01/2008	Active	10014171
EASA.A.S.01305	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	Introduction of Pressure Seals for wire runs		-see Change approval sheet DFS 5610 and associated list of affected technical documents	This STC is approved only for the configuration as defined in Mod Sheet DFS 5610.Compatibility with other aircraft/engine configurations shall be determined by the installer.	22/09/2005	Active	10014172
EASA.A.S.01306	UNIAIR			BEECH C90A	Compliance with the B-RNAV requirements for the GPS System Trimble 2000 Approach +		Master Data List UAE. 030.05 Revision 2 dated 21 June 2005.AFMS No. 57/ UAE Revision 2 dated 21 June 2005	1. This STC is limited to aircraft s/n LJ-1303.2. GPS System Trimble 2000 Approach + installation already approved withIFR priviledge.	20/07/2005	Active	10014173
EASA.A.S.01309	AVIONIK STRAUBING ENTWICKLUNGS GmbH			B.65-90, 65-A90, B90, C90, E90 A. C90 A	Installation of Skywatch L3 SKY899, Radar RDR 2000 and EGPWS KGP 560		EASA approved AFM Supplement FMS ASR 2005-020-00 Rev. A 'Skywatch 899', or later EASA approved revisionsEASA approved AFM Supplement FMS ASR 2005-020-01 Rev. A 'RDR2000', or laterEASA approved revisionsEASA approved AFM Supplement FMS ASR2005-020-02 Rev. A 'EGWPS Honeywell KGP 560', or later EASA...		07/10/2005	Active	10014174
EASA.A.S.01312	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	BOEING 747-400	Omnibus Modification for B747 Mid J Project Stretch Embodiment		British Airways Engineering Modification ref. BA-747-25-0007British Airways Engineering Master Data List ref. MDL-0049-06 Rev 00 or later approved revision.		28/02/2007	Active	10014176
EASA.A.S.01313	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	BOEING 777-236					07/05/2009	Active	10028294
EASA.A.S.01314	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	BOEING 747-400	Omnibus Modification for Boeing 747-436 Hi J Project Stretch Embodiment		British Airways Modification BA-747-25-0008		17/11/2006	Active	10014177
EASA.A.S.01315	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOF FICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	BOEING 777-200	Omnibus Modification for B777 4 Class Project Stretch Embodiment.		British Airways Master Data List Reference No. MDL-0055-08 Rev 00 dated 13 June 2008 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	09/09/2008	Active	10014178
EASA.A.S.01316	TMC AERO			AIRBUS A330-243	This STC deals with the installation of a TMC stretcher. All documents related to this STC are listed in the STC form A330-25-23. The associated "Fiche de Modification" from Corsair is referenced 25-137 Rev. 1 (or later EASA-approved revision)			The approval of this modification is limited to the Airbus A330-243. the lmitations and conditions defined in the EASA Datasheet are applicable.	02/06/2005	Active	10014179

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01317	TMC AERO			BOEING 737-400	Temporary Installation of a Stretcher that is fitted on thePassengers Seat Track		-TMC Aero Airplane flight Manual Supplement Doc Ref AFMS25-0317, Rev 1 dated 11th August 2005- TMC Aero "Fiche de Modification", Doc Ref 25-135, Rev 5 dated 11th August	1. Operation of the aircraft with stretcher installed is limited to 100 FH per year2. The limitations as descrabied in the AFM Supplement Doc Ref AFMS25-0317 apply	29/08/2005	Active	10014180
EASA.A.S.01318	TMC AERO			BOEING 747	The installation of stretchers mounted on the seat tracks in passenger cabin of the Boeing 747 for the transport of patients, as described in Corsair Fiche de Modification no. 25-136		- Corsair Note Technique DT/ET/044102/NT- Corsair Fiche de Modification no. 25-136- JTSO F.O. 103 for model TMC 99	1. The maximum number of passengers allowed when two stretchers are installed shall be determined.2. When three or more stretchers are installed transport of passengers is not allowed.	12/07/2005	Active	10014181
EASA.A.S.01319	ATS INTERNATIONAL			BOEING 767-300 BOEING 767-200	Installation of Enhanced Mode S Surveillance		-Master Data List 0213-01-A-2103-R00-AFM Supplement 0213-01-A-2301-R01		25/01/2006	Active	10014182
EASA.A.S.01320	ATS INTERNATIONAL			B757	Installation of emergency Locator Transmitter		ATS International Modification STC 0248-01ATS InternationalMaster Data List 0248-01A-2103-R00	--	16/10/2006	Active	10014183
EASA.A.S.01323	STC TWENTY ONE LIMITED	REV 1	CAA UK RESPONSIBILITY	FOKKER F.27 MARK 600 FOKKER F.27 MARK 500	Use of TRA-45A Display Indicator		- STC Twenty One Modification S21.34-62-1013- STC Twenty One AFM Supplement AED/F27/8 Issue 3 or later approved revision		30/01/2006	Active	10014185
EASA.A.S.01324	AERO ENGINEERING DESIGN Ltd		CAA UK RESPONSIBILITY	BAE 125 800B	Introduction of Rockwell Collins TCAS 4000		Flight Manual Supplement S.21 FMS.125.0004		19/09/2005	Active	10014186
EASA.A.S.01325	AERO ENGINEERING DESIGN Ltd		CAA UK RESPONSIBILITY	MD-80	Aero Engineering Design Modification 34-77-211. Introduction of Honeywell MK VII EGPWS		-Aero Engineering Design Ltd Design Modification Certificate 34-77-211-Aero Engineering Design Ltd AFM Supplement AED/ MD80/001		25/07/2005	Active	10014187
EASA.A.S.01328	AERO ENGINEERING DESIGN Ltd		CAA UK RESPONSIBILITY	MD-80	Aero Engineering Design Modification 34-77-210.Introductiomof Honeywell RDR-4B Weather Radar		Aero Engineering Design Ltd Design Modification Certificate34-77-210		25/07/2005	Active	10014188
EASA.A.S.0133	AIR MEDIC L.L.C.		FAA STC SA7076NM	BAE 14 146 AND AVRO 146 MODELS	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'AD', dated May 18, 1995 (or laterEASA approved Revisions).			1 This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/ engineconfiguration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrev...	16/09/2004	Active	10061355
EASA.A.S.01331	RUAG AEROSPACE SERVICES GmbH			CESSNA 525	Installation of ACAS II System with Dual Mode S Transponder. ELS compliant and EHS capable		AFM Supplement Doc. No. 118A-AFMS, revision 0 or later EASAapproved revision.		18/07/2005	Active	10014189
EASA.A.S.01332	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		CESSNA 550 CITATION II CESSNA 500, CITATION	Dual GARMIN GPS installation: GNS-430A + GNS-530A in accordance with MDL BCA 74-00 rev 6 dated 19/07/05		AFMS SMV BCA74 rev 7 dated 11/01/06AMMS BCA74 rev 0 dated 07/07/05	1. S/N 550-0324 and 500-03612. This STC is approved only for the product configuration as defined in the approveddesign data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	31/01/2007	Active	10014190
EASA.A.S.01334	AERO TECHNICS DESIGN LIMITED		CAA UK RESPONSIBILITY	3. DC-10 SERIES 2. BOEING MD-11 SERIES 1. BOEING 747-400 1. BOEING 747-200 1. BOEING 747-100	Introduction of Horsebox Containers BAC1136-301 and BAC1136-401		ATD0061		26/07/2005	Active	10014192

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01336	MT-PROPELLER ENTWICKLUNG GmbH			PITTS S-2C S-2B	Installation of propeller MTV-9-B-C/ C203-46		Pitts S-2B:- Anhang zum Flughandbuch Nr. E-662, LBA approved 13.12.2000 or later LBA approved revision- UmrüstanweisungNo. E-661Pitts S-2C- Airplane Flight Manual Supplement No. E-1304- Instructions for Continued Airworthiness E-1306- Installation Instructions E-1305		16/08/2006	Active	10014194
EASA.A.S.01337	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER BD-700-1A10	Installation of MicroQAR acc.046A-SD				21/06/2005	Active	10014195
EASA.A.S.01338	LUFTHANSA TECHNIK AG			BOEING 737-500 BOEING 737-400 BOEING 737-300	Navigation - Introduction of ATC Mode S Enhanced Surveillance		-Supplemental Type Definition Document STDD34-05/05M, Issue01 Rev 0 or later approved revision-Airplane Flight Manual Supplement Doc No A-34-05/261-AFM Rev IR dated June 27, 2005or later approved revision- Maintenance Manual Supplement Doc No DR34-		26/07/2005	Active	10014196
EASA.A.S.0134	AIR MEDIC L.L.C.		FAA STC SA7076NM	A330-342/-343 A330-322/-323/-243/-341 A330-202/-301/-223/-321	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref.: AM-2001, Revision 'AN', dated April 15, 2002 (orlater EASA approved Revisions).			1 This SIC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/ engineconfiguration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrev...	16/09/2004	Active	10061353
EASA.A.S.01340	AIRBUS S.A.S.	REV. 1		A330-200 MODELS	Installation of a more powerful air heater (3kg W) inside the private cabin washroom		The associated Modification Approval Sheet is referenced SOG-21-1135 issue 2 dated 15/06/05. All documents related to this STC are listed in the Master Data List Drawing n °MDL-21-1135, Issue N° A (or later EASA approved revision). Technical Repercussion Sheet reference 21-1135 issue B	1.This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.2. The limitations and conditions defined in the EASA Datasheet ar...	04/07/2008	Active	10014197
EASA.A.S.01349	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		BEECH B300 BEECH B200 BEECH 300LW BEECH 300 BEECH 200	Installation of TAWS ST3400 system.Revision of the AFM Supplement related to a Minor Change to EASA.A.S. 01349.Installation of TAWS ST3400 system.Revision of the AFM Supplement related to a Minor Change to EASA.A.S. 01349.		AFM Supplement No. 2022641-AM-03, Issue 3 or later EASA approved revision. Continued Airworthiness Instructions 2022641-CA-03.EASA approved Aircraft Flight Manual Supplement Doc. No. 2022641-AM-03, Issue 4, dated January 2007 or later approved revision.AFM Supplement No. 2022641-AM-03, Issue 3 o...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.This STC is approved only for the product configuration as defined i...	26/02/2007	Active	10014199
EASA.A.S.01350	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 500	Installation of Honeywell KMH 880 Multi-Hazard Awareness System		Airplane Flight Manual Supplement fo rInstallation of Honeywell KMH 880 Multi-Hazard Awareness System Doc No 2027746 AM-01 Issue 1,dated May 2005 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	02/01/2006	Active	10014200

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01351	E A D AEROSPACE AIRWORTHINESS	REV 1		SA 227 SERIES	ELS/EHS installation on SA 227 series aircraft- Removal of existing two ATC transponders and associated trays in forward avionics- Removal of existing ATC Mode S Control Panel from Instrument Panel- Disconnection of ATC 2 Mode S bottom antenna- Installation of two ATC transponders on new trays in re...		Aircraft Flight Manual Supplement:Document 01046-EAS-A-AFM-01 Rev. BMinimum Equipment List Supplement:Document 01046-EAS-A-MEL-01 Rev. AMaintenance Planning Document Supplement:Document 01046-EAS-A-MPD-01 Rev. B	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	27/06/2006	Active	10014201
EASA.A.S.01352	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	ST34MOD027 " Enhanced Surveillance on A300-600ST"		Supplement to A300-600ST Flight Manual referred ST34MOD027 dated 28 March 2006, or any later EASA approved revision		07/04/2006	Active	10014202
EASA.A.S.01354	MT-PROPELLER ENTWICKLUNG GmbH			AVIATION AIRCRAFT A-1B AVIATION AIRCRAFT A-1A AVIATION AIRCRAFT A-1	Installation of propeller MTV-14-B/ 183-301aTake-off- and max. Continuous-power: 126 kw by 2500 min		Anhang zum Flughandbuch Nr. E-1231Airplane Flight Manual Supplement No E-1230Instructions for Continued Airworthiness and Installation Instructions E-1232		04/11/2005	Active	10014203
EASA.A.S.01355	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER DHC-8-400	Installation of VDL 4000/A VHF Data Link Mode 4 (CNS Systems) and installation of a combined VHF/GPS Antenna		Master Document List Doc. No. 045A-MDL Rev. N/C or later EASA approved revisions. Continued Airworthiness Plan Doc. No.045A CAWP		18/07/2005	Active	10014204
EASA.A.S.01356	RUAG AEROSPACE SERVICES GmbH			CESSNA 500, CITATION	Installation of a TWS/RMI Sandel ST 3400 (TAWS Class B)		- Master Document List Doc. No. 152A-MDL- Airplane Flight Manual Supplement Doc. 152A-AFMS		24/08/2005	Active	10014205
EASA.A.S.01357	RUAG AEROSPACE SERVICES GmbH			CESSNA 500, CITATION	Installation of Dual Mode - S Transponder System Garmin GTX-330D - Elementary Surveillance. (Removel of the exising Rockwell Collins TDR-90 transponder). Installation of two additional L-Band Antennas on top of the fuselage.		- Master Document List Doc. No. 152B-MDL- Airplane Flight Manual Supplement Doc. 152B-AFMS		24/08/2005	Active	10014206
EASA.A.S.01358	DAO AVIATION A/ S			PIPER PA-24-400 PIPER PA-24-260 PIPER PA-24-250 PIPER PA-24	Installation of Garmin GNS 430 COM/ NAV/GPS. Approval for B-RNAV, en route IFR and Terminal flights		DFE Design Order Package DO-0011. Garmin installation manual P/N: 190-00140-02 (Rev. L) SLV approved Aircraft Flight Manual supplement DFE-DD-AFMS-01-00.		29/06/2005	Active	10014207
EASA.A.S.01361	STC TWENTY ONE LIMITED	REV 1	CAA UK RESPONSIBIL ITY	BAE ATP	Introduction of Class E Compartment for LFD Modified Aircraft.		STC Twenty One Limited Master Document List S21.MDL-0017, initial issue dated 4th April 2008 or later approved revisions.	1. Flight Manual Supplement S21.FMS-0008;	09/04/2008	Active	10014209
EASA.A.S.01362	STC TWENTY ONE LIMITED	REV 1	CAA UK RESPONSIBIL ITY	BAE ATP	Introduction of Freight Loading & Restraint System for LFD Modified Aircraft.		STC 21 Master Drawing List No. S21.MDL-0018 initial Issue dated 25 January 2008 or later approved revision.STC 21 Airplane Flight Manual Supplement No. S21-FMS-0009 at Initial Issue or later approved revision.	This major change is limited to embodied into a Bae aircraft previously modified for the installation of a large cargo door at the rear of the fuselage in accordance with Bae Service Bulletin ATP-52-036 and with the installation of a main cabin Class 'E' cargo compartment in accordance with STC Twen...	09/04/2008	Active	10014210
EASA.A.S.01363	STC TWENTY ONE LIMITED		CAA UK RESPONSIBIL ITY	BAE ATP	Installation of AAR Freight Loading System		-STC21 Change No S21.25-23-1005-STC21 AFM Supplement SerialNo S21.FMS-atp-0010 Issue No. or later approved revision	This STC may only be embodied into BAe ATP aircraft previously modified for the installation of a large cargo door at the rear of the fuselage, in accordance with British Aerospace Service Bulletin SBATP-52-036 (Modification M60138A), witha barrier net installedin accordance with Fly BE Major Cahng...	30/01/2006	Active	10014211

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01370	AVIATION DEFENSE SERVICE			58	Installation of emergency locator transmitter ELT 96-406 MHz in accordance with modification file AVD-MB58-23-044A.		Airplane Flight Manual Supplement No. 1 / AvDef Beech 58, edition 1 dated 9 May 2005Maintenance Manual Baron 55/58 edition 1, revision 1 dated 19 April 2006	Modification limited to s/n TH-647The AFMS No. 1 / AvDef Beech 58 must be used with this modification.	21/04/2006	Active	10014212
EASA.A.S.01372	AVIONIK STRAUBING ENTWICKLUNGS GmbH			501, 551	Installation of Dual Garmin GNS 430A		EASA approved AFM Supplement EASA2005-032-00 Rev. A, or later EASA approved issues		01/09/2005	Active	10014213
EASA.A.S.01377	LUFTHANSA TECHNIK AG			BOEING 737-300	"Avionics Upgrade by- Installation of TCAS- Installation ofDual Mode S Transponder- Installation of Add. Parameters for Digital FDR- Digital Flight Data Acquisition Unit, Software Upgrade- Installation of Enhanced Ground Proximity WarningSystem"		- Supplemental Typ Definition Document STDD34-05/04M Issue1, Rev. 00 dated Aug 19, 2005 or later approved Revision.- Airplane Flight Manual Supplement Doc. No. A-00-05/322 AFM dated Aug 17, 2005 or later apporved Revision.- Instructions for Continious Airworthiness Doc. No. CS34-0387 ICA, dated July...		01/09/2005	Active	10014216
EASA.A.S.01378	DASSAULT FALCON SERVICE			MYSTERE FALCON 900	Call out evolution with EGPWS Honeywell Mark V 212-212.ThisSTC supersedes the STC F-C163-SF-2107 EASA approved on March 9, 2004 with the reference 2004-2073.		Change Approval Sheet DFS 9447 CAS revision A dated 9 June 2005.AFM supplement DFS n° 17 revision A dated June 9, 2005.	Applicable to all MF900 aircraft with modification DFS 9259	04/07/2005	Active	10014217
EASA.A.S.01381	BUSINESS AND COMMUTER AIRCRAFT			BEECH 1900D	Installation of ACSS TCAS 2000 System.		Doc. Ref. BCA 59/ STC1248 dated Appril 2005, Revision 1.AFMSreferenced BCA59 dated April 2005, Revision 1.		08/07/2005	Active	10014220
EASA.A.S.01383	AERO-DIENST GMBH & CO. KG			BAE.125 SERIES 800B BAE.125 SERIES 800A	Installation of a L-3 F1000 SSFDR		Engineering Order Doc. No. 210-HW Rev. IR or later approvedRevisionsAirplane Flight Manual Supplement L-3 F1000 SSFDR,Doc. No. AG542-071 Rev IR or later EASA approved RevisionsInstruction for Continuous Airworthiness Doc. AG542-085		10/11/2005	Active	10014221
EASA.A.S.01384	AERO-DIENST GMBH & CO. KG			BAE.125 SERIES 800B BAE.125 SERIES 800A	Installation of a Rockwell Collins TCAS 4000 with Dual TDR-94D and Dual RTU-4210 System		Engineering Order Doc. No 206-HW Rev. IR or later EASA approved RevisionsAirplane Flight Manual Supplement/Collins TCAS4000 with Dual TDR-94D and Dual RTU-4210, Doc. No. AG530-071 Rev IR or later EASA approved RevisionsInstruction for Continuous Airworthiness Doc. AG530-085		10/11/2005	Active	10014222
EASA.A.S.01385	AERO-DIENST GMBH & CO. KG			BAE.125 SERIES 800B BAE.125 SERIES 800A	Installation of an Universal Avionics System Corporation Flight Management System UNS-1L		Engineering Order Doc. No. 208-HW Rev. IR or later EASA approved RevisionsAirplane Flight Manual Supplement/UASC UNS-1LFMS, Doc. No. AG573-071 Rev IR or later EASA approved RevisionsInstruction for Continuous Airworthiness Doc. AG537-85		10/11/2005	Active	10014223

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01386	AERO-DIENST GMBH & CO. KG			BAE.125 SERIES 800B BAE.125 SERIES 800A	Installation of an UASC CVR-30B		Engineering Order Doc. No. 209-HW Rev. IR or later EASA approved RevisionsAirplane Flight Manual Supplement/UASC CVR-30B, Doc. No. AG540-071 Rev IR or later EASA approved RevisionsInstruction for Continuous Airworthiness Doc. AG540-085		10/11/2005	Active	10014224
EASA.A.S.01388	LUFTHANSA TECHNIK AG			AIRBUS A321 AIRBUS A320	ATC, System Upgrade for Enhanced Surveillance, acc.: STDD 34-05/06M		AFM Supplement: A-34-05/260-AFMICA: DR34-0379-02	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	22/07/2005	Active	10014225
EASA.A.S.01389	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 400 SERIES CESSNA 300 SERIES	Installation of GNS 430A/530A COMM/ NAV/GPS Systems		Airplane Flight Manual Supplement Doc.: 2027438-AM-02A 'Garmin GNS-430&530 VHF Communications Transceiver/VOR/ILS Receiver/GPS Receiver', Issue 1 or later EASA approved revisionsAirplane Flight Manual Supplement Doc. No.: 2027438-AM-02B 'Ground Communication Provision', Issue 2 or later EASA approve...	none	20/09/2005	Active	10014226
EASA.A.S.01390	LUFTHANSA TECHNIK AG			AIRBUS A330-300	Integration of Lower Deck Mobile Crew Rest		Supplemental Type Definition Document STDD00-04/11M Issue 01Compliance Record List CRL00-04/11 Issue 1Instructions for Continued Airworthiness		14/07/2005	Active	10014227
EASA.A.S.01391	LUFTHANSA TECHNIK AG			AIRBUS A340-300	Integration of Lower Deck Mobile Crew Rest		Supplemental Type Definition Document STDD00-04/15M Issue 01Compliance Record List CRL00-04/15 Issue 1Instructions for Continued Airworthiness		14/07/2005	Active	10014228
EASA.A.S.01392	FINNAIR OYJ			BOEING MD 11	MD11 Cabin Crew Rest Area		Data package containing the following documents, and additional supporting data:1. MD-11 C/A Bunk Airworthiness Compliance Sheet Rev. E2. Cabin Crew Rest Compartment Modifications3. MD-11 C/ A Bunk AYM60 and AYM61 Flight Test Report Rev. B4. MD-11 C/A Bunk AYM60 and AYM61 Ground Test Re...	Emergency evacuation procedures, including the emergency evacuation of an incapacitated occupant from the Crew Rest Area, must be established. All of these procedures must be transmitted to the operator for incorporation into their training programs and appropriate operational manuals.There must beo...	15/08/2006	Active	10014229
EASA.A.S.01393	RECTIMO AVIATION			PIPER PA-28-181, ARCHER III	GNS 430 installation with MD 41-1488 (HSI and AP coupled)Installation of GNS 430 and MD 41-1488 coupled with KI 525A		FACE RECTIMO AVIATION 2005/05-0-FGSMDAFMS "Suplément au manuel de vol approuvé EASA concernant l'utilisation de l'avionéquipé d'un GPS GARMIN GNS 430; Edition Juillet 2007"	Limited to S/N 2843066 F-GSMDGPS use is forbidden for BRNAV and approachAuto Pilot coupling is forbidden under 2000 ftAGL	20/07/2007	Active	10014230

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01394	AIRBUS S.A.S.	REV. 1		A340-212	VIP Cabin and systems upgrade in accordance with Sogerma Modification Approval Sheet (MAS) SOG-00-0977 issue 3 dated 03/02/06		Flight Manual Supplement ref. FM-S MOD-SOG-F4-00-977 issue 6 dated 01/02/2006MPD Supplement ref. MPD-S SOG-F4-00-977 dated 31/01/2006(or later approved revision)	The approval of this modification is limited to the Airbus A340-212 MSN 061	04/07/2008	Active	10014231
EASA.A.S.01395	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	A321	Installation of Koito 24B/C and 148Y seats for Dragonair		BBJ Certification Plan BBJCP015		11/11/2005	Active	10014232
EASA.A.S.01396	AIRBUS S.A.S.	REV. 1		A319-133	Avionics Rack 9100 VU installation		- Modification Approval Sheet (MAS) ref. SOG-00-1056, issue1, dated October 4, 2005-AFM Supplement, ref. FM-S MOD-SOG-00-1056, dated September 21, 2005-MMEL Supplement, ref MMEL-S MOD-SOG-00-1056, dated September 21, 2005	1. This STC is limited to A319-133 CJ MSN 2421	04/07/2008	Active	10014233
EASA.A.S.01397	AIRBUS S.A.S.	REV. 1		A319-133	Live TV system provision		Modification Approval Sheet (MAS) ref SOG-00-1139, issue 1,dated October 4, 2005 MPD Section 9-2 Supplement, ref. MPD-S MOD-MMEL-SMOD-SOG-001139, dated September 21, 2005	This STC is limited to A319-133 CJ MSN 2421	04/07/2008	Active	10014234
EASA.A.S.01398	ATS INTERNATIONAL			BOEING 737-300	ATLAS Standard Galleys Installation.		ATS Master Data List, Doc. Ref. 4011-01-A-2103-R03, Revision 3 dated 31 August 2005		18/10/2005	Active	10014235
EASA.A.S.01399	UNI AIR ENTREPRISE			CORVETTE SN 601 SN 028 & 008	Deviation to SB 34-12 replacement of mount C24-C25 in accordance with MDL UAE 008.05 Rev. 1 dated 8/07/2005. Installation of horizontal mount between frames C24 and C26 instead ofvertical one between frames C24 and C25.		AFMS No. 58	1. This STC applies to MSN 028 and MSN 008 only.2. This STCis approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be	25/07/2005	Active	10014236
EASA.A.S.0140	AIR MEDIC L.L.C.		FAA STC SA3490NM	A300 / A310 SERIES	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'Y', dated March 11, 1987 (or laterEASA approved Revisions)			1. This SIC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orre...	16/09/2004	Active	10061352
EASA.A.S.01400	UNIAIR			CORVETTE SN 601	Deviation to SB 34-12 - replacement of ADF in accordance with MDL UAE 010.05 rev 1 dated 11/07/05.Installation of ADF60according to option 85 aerospatiale instead of ADF 206.Installation of option 85 on second ADF position instead of first position.Idmodel: Airbus Corvette SN 601, MSN 028 and MSN 0...			1. This STC is limited to S/N 028 and S/N 0082. This STC isapproved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	28/07/2005	Active	10014237
EASA.A.S.01403	MT-PROPELLER ENTWICKLUNG GmbH			CESSNA F182-Q CESSNA 182R CESSNA 182Q	Installation of propeller MTV-9-D/203-52		Anhang zum Flughandbuch Nr. E-1242Airplane Flight Manual Supplement No. E-1241Instructions for Continued Airworthiness and Installation Instructions E-1243	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	18/11/2005	Active	10014239

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01404	MT-PROPELLER ENTWICKLUNG GmbH			DIAMOND DA-20-C1	Installation of Propeller MT 175 R 150-2Ca		Airplane Flight Manual Supplement No E-1255Anhang zum Flughandbuch Nr 1256Installation Instructions E-1257Instructions for Continued Airworthiness E-1281		14/03/2006	Active	10014240
EASA.A.S.01406	MT-PROPELLER ENTWICKLUNG GmbH			CESSNA F182-P CESSNA 182P CESSNA 182N CESSNA 182M CESSNA 182L CESSNA 182K CESSNA 182J CESSNA 182H CESSNA 182G CESSNA 182F CESSNA 182E CESSNA 182D CESSNA 182C CESSNA 182B CESSNA 182A 1. CESSNA 182	Installation of propeller MTV-9D/203-52		- Airplane Flight Manual Supplement No. E-1316-Anhang zum Flughandbuch Nr. 1319- Installation Instructions E-1317-Instructions for Continued Airworthiness E-1318		08/06/2006	Active	10014241
EASA.A.S.01451	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA S550 CESSNA 550 CESSNA 500	Installation of GPS400 in center panel with GAD 42 adapter for roll steering		Approved Aircraft Flight Manual Supplement for Garmin GPS 400 GPS System Doc. No. 2027746-AM-02 issue 2, dated August 2005 or laterapproved revision		24/01/2006	Active	10014242
EASA.A.S.01452	DASSAULT FALCON SERVICE			MYSTERE FALCON 20	Deviation to M GE 2 - Pressure seals FR17-18		see Change approval sheet DFS 2561 and associated list of affected technical documents	1. This STC is applicable to Falcon 20S/N 103 only2. This STC is to be applied simultaneously with Dassault Aviation Mod M GE23. Compatibility with other aircraft/ engine configurations shall be determines by the installer	22/09/2005	Active	10014243
EASA.A.S.01454	AERODATA AG			B200	Installation of Aerodata Flight Inspection System AD-FIS-9		- Master Document List MDL-A/C-100 Rev. 1-EASA approved Airplane Flight Manual Supplement for Flight Inspection System, Model AD-FIS-9, in Beech King Air B200, Doc.-No. AFM-081 Rev. 0-Airplane Maintenance Manual Supplement AMM-799		25/01/2006	Active	10014244
EASA.A.S.01455	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 400 SERIES CESSNA 300 SERIES	Installation of GTX 330 Mode S Tansponder		Airplane Flight Manual Supplement Doc.: 2027438-AM-04 'GTX Mode S-Transponder' or later EASA approved revision		20/09/2005	Active	10014245
EASA.A.S.01456	LUFTHANSA TECHNIK AG			BOEING 767-300	ATC, System Upgrade for EHS		Supplemental Type Definition Docuemtn STDD34-04/05M Issue 01, Rev 01 or later approved revisionAirplane Flight Manual Supplement A-34-04/6070-AFM Rev IR or later approved revision	Certification Basis of the Change: CS 25 Change 0, additionally JAA Leaflet No 18 (Mode-S EHS)	10/04/2006	Active	10014246
EASA.A.S.01471	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			LEARJET 55C LEARJET 55	Installation of Flight Data Recorder F1000		-Engineering Order 2003-8, Rev B or later EASA approved revisions		01/08/2005	Active	10014249
EASA.A.S.01473	ELECTRONIQUE MAINTENANCE AVIATION			BEECH 200	406 MHz ELT installation		Airplane Flight Manual supplement No EMA04/002/BE200/ ELT406, rev 1 of July 2005.	Modification applicable on s/n BB616 and BB202 only.	05/08/2005	Active	10014251

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01477	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 757-200	Introduction of Honeywell MKV Enhanced Ground Proximity Warning System (EGPWS)		Master Data List S21.MDL-0001-Issue 2 or later approved revision.AFM Supplement S21.FMS-0001 Issue 1 or later approved revision.		22/09/2005	Active	10014252
EASA.A.S.01478	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 757-200	Introduction of Honeywell GNSSU Receiver		Master Data List S21.MDL-0002-Issue 1 or later approved revision.		22/09/2005	Active	10014253
EASA.A.S.01481	DASSAULT FALCON SERVICE			MYSTERE FALCON 20 FAN JET	DFS 2545 dtd. 12. October 05: Camera and Video Recorder installation		see Change approval sheet DFS 2545 and associated list of affected technical documents	This STC approves the installation only, system activation is not considered.	08/11/2005	Active	10014255
EASA.A.S.01486	LUFTHANSA TECHNIK AG	REV 1		AIRBUS A330-300 AIRBUS A330-200	Structural mounting provision for large antenna and random for Live TV Tailwind 560		Airplane Flight Manual Supplement: A-00-06/136-AFM Rev. IR,or later approved revision.Supplemental Type Definition Document Ref. STDD 53-05/02M, Issue 02 / Rev. 00 dated 7 December 2006Instructions for Continued Airworthiness Ref. R-000-06-0149, Rev. 03 dated 7 December 2006	1. EASA CS25, without Amendment, Certification Specifications for Large Aeroplanes plus FAA Generic Issue Paper A-X "Structural Certification Criteria for Large Antenna Installations".2. This STC is approved only for the product configuration as defined in the approved design data referred to in the...	08/12/2006	Active	10014257
EASA.A.S.01487	LUFTHANSA TECHNIK AG			AIRBUS A330-300 AIRBUS A330-200	Communication - Modification/Upgrade of the In-Flight Entertainment System, Installation of Tailwing 560 Live TV Equipment.		Airplane Flight Manual Supplement: A-00-06/136-AFM Rev. IR,or later approved revision.Instructions for Continued Airworthiness: R-00-06-0149 Rev. IR, or later approved revision.STDD No. "STDD 23-05/05M"	EASA CS25, without Amendment, Certifications Specificationsfor Large Aeroplanes plus JAA INT/POL/25/3 Issue 2, JAA INT/POL/25/4 Issue 3, JAA Leaflet No. 17.	07/04/2006	Active	10014258
EASA.A.S.01488	LUFTHANSA TECHNIK AG	REV 1		BOEING 777-200	Rearrangement of VIP cabin interior (Majlis) & systems and modification of pax entertainment system (IFE) including installation oftailwind 560 Live TV system.		STC Definition Document - STDD00-05/06M issue 01 dated 11 June 2008.(or later approved issue) Compliance Record List CRL00-05/06M issue 1Instructions for Continued Airworthiness – A-00-05/342-ICA rev IR (or later approved issue)EASA CRIsA-01 iss 4 Certification Basis VIP Interior.	1.This modification is limited to a/c serial number MSN29271.2. Occupancy of this zone is limited to Zero Passengers for Taxi, Take-off and Landing, pending substantiation of evacuation through the adjacent compartments	12/06/2008	Active	10014260
EASA.A.S.01489	LUFTHANSA TECHNIK AG			BOEING 777-200	Introduction of Tailwind 550 Antenna and Live TV for VIP B777-200.		STDD53-05/01M issue 01 dated 22 June 2006AFM Supplement – A-00-05/342-AFMInstructions for Continued Airworthiness CS53-0223-2	This modification is limited to a/c serial number MSN29271.	29/06/2006	Active	10014261
EASA.A.S.01490	LUFTHANSA TECHNIK AG			AIRBUS A300	ATC, System Upgrade for EHS		Supplemental Type Definition Document STDD34-05/07M, Issue 1, Rev. 00 or later approved RevisionAirplane Flight Manual Supplement A-34-05/323-AFM Rev. IR, dated Jul 22/05 or laterapproved Revision	Certification Basis of the Change: CS 25, additionaly JAA Leaflet No. 18 (Mod-S EHS)	13/03/2006	Active	10014262
EASA.A.S.01493	DASSAULT FALCON SERVICE			FALCON 20	Installation of two V/UHF AN/ARC210		Associated to: see Change approval sheet DFS 2543 associated list of affected technical documents	1. This STC is applicable to Falcon 20 SN 076 only2. Systemactivation is not considered3. This STC is approved only for the configuration as defined in ModSheet DFS 25434. Compatibility with other aircraft/engine configurations shall bedetermined5. This STC is approved only for the product configur...	09/08/2005	Active	10014263

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01494	AIR FRANCE			B767	Rockwell Collins Aero I SATCOM installation		CAS-B767-05-004 Rev 0		19/12/2005	Active	10014264
EASA.A.S.01496	DASSAULT FALCON SERVICE			MYSTERE FALCON 20	Antenna relocations, skin repairs		see Change approval sheet DFS 2558 and associated list of affected technical documents	1. This STC is only approved for the configuration as defined in Mod Sheet DFS 2558 Issue Original	14/09/2005	Active	10014267
EASA.A.S.01497	AIR ALPHA A/S	REV 1		HS 748 SERIES 2A/2B	Installation of a Honeywell EGPWS MK6 system.		Shadin Fuel/Airdata Computer Installation Manual PN IM2830 Rev. K.Honeywell TRA-45A Installation Manual 34-40-01 Rev.I .Honeywell MK VI Installation Design Guide Dwg. No. 060-4314-150.Ground test for the MK6 EGPWS Dwg No. 060-4167-158 Rev.A.Honeywell Flight Test Procedure 060-4188-041 with maps 060...	1. Existing GPS antenna shall be used with coach splitter.	15/08/2005	Orphaned	10014268
EASA.A.S.01498	LUFTHANSA TECHNIK AG			BOEING 737-700 IGW	Cabin and IFE Modification as defined in Supplemental Type Definition DocumentSTDD00 - 05/05 M, Issue 01, Rev.00		Lufthansa Technik Supplemental Type Definition Doc. No. STDD00 - 05/05 M, Issue 01,Rev. 00 or later approved Revision		25/10/2005	Active	10014269
EASA.A.S.01500	DASSAULT FALCON SERVICE			FALCON 10	GPS Antenna installation		Associated to: see Change approval sheet DFS 2563 and associated list of affected technical documents	1. Applicable to Falcon 20 S/N 103 only.	16/08/2005	Active	10014270
EASA.A.S.01502	CESSNA DUESSELDORF CITATIONSERVIC E CENTER GmbH			CESSNA 551 CESSNA 501	Installation of Honeywell RDS 84 WX System.		MM-Supplement 2004-08-10, Rev. A or later approved revision.		16/08/2005	Active	10014272
EASA.A.S.01506	DASSAULT FALCON SERVICE	REV. 1		MYSTERE-FALCON 20 SN 397 FAN JET	DFS2483A dtd. 12.Mai 2006Under Wing installation of particle measuring systems sensor		see Change approval sheet DFS 2483A:-AFM Supp MF 20 GF 47 Revision 1 Utilisation de l'avion equipe dequatre sondes PMSsous voilure and associated list of affected technicaldocuments	1. This STC is limited to MF 20 GF SN 397.2. Dassault Aviation M2719 to be applied (hard points installation);3. Only symetrical configurations are allowed (1+1 or 2+2).4. MaximumLanding Weight is limited to 11.616kg5. This STC is approved only for the product configuration as defined inthe approve...	15/05/2006	Active	10043014
EASA.A.S.01507	AVIONIK STRAUBING ENTWICKLUNGS GmbH			B90	Installation of Avidyne FM850		-EASA approved AFM Supplement LBA2004-015-00 Rev A or laterEASA approved issues		18/08/2005	Active	10014273
EASA.A.S.01510	DASSAULT FALCON SERVICE			FALCON 20	Time Base Installation.		Associated to:see Change approval sheet DFS 2548 and associated list of affected technical documents	1. This STC is applicable to Falcon 20 SN 076 only 2. System activation is not considered 3. This STC is approved only for the configuration as defined in Mod Sheet DFS 2548 4. Compatibility with other aircraft/ engine configurations shall be determined b	18/08/2005	Active	10014274
EASA.A.S.01511	SERAM - SOCIETE D'ENTRETIEN ETREPARATION AERONAUTIQUE MACONNAISE			CESSNA 337D	Installation of one KX 155A Immunity FM, one GNS430 and GI106A with BRNAV capability		Flight Manual Supplement Rev 0 dated 01/09/2004	1. This STC is limited to Cessna 337D SN 337-1048. 2. Autopilot coupled with GNS 430 forbidden. 3. This STC is approvedonly for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall...	23/08/2005	Active	10014275

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01512	DASSAULT FALCON SERVICE			FALCON 10	Frame 0 Pressure Seal through-fitting modification (enlargepressure seals)		Associated to: see change approval sheet DFS 1272	This STC is approved only for the configuration as defined in Mod Sheet DFS 1272 Issue Original. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	24/08/2005	Active	10014276
EASA.A.S.01513	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV 2	CAA UK RESPONSIBILITY	BAE 146/RJ SERIES BAE 146/AVRO 146 SERIES BAE 146	Installation of PRNAV Compliant UNS-1E FMS		- Bournemouth Aviation (Consultants) Modification BAC/146/062 Issue 1 or later approved revision,- Bournemouth Aviation (Consultants) Modification BAC/146/068,- Bournemouth Aviation (Consultants) AFM Supplement FMS/345/30 Issue 2 or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	08/12/2006	Active	10014277
EASA.A.S.01514	AEROTEC & CONCEPT			PIPER PA-31	Installation of Radio Navigation and Communication Systems-KX 175B, KY 196, KN 53, KN 75, KMA 24 and KN 65 removal- GNS 430, KX 155A, MD 41, RDR 2000, GMA 340, KN 62A, KI 229, GI106A installation		Airplane Flight Manual Supplement:Supplément au manuel de vol Piper PA 31 pour l'utilisation du GPS GNS 430 certifié enmoyen supplémentaire de navigaton IFR/VFR avec la capacité Basic RNAV, installé suivant la modification 3005" dated 10/11/2005.	The approval is limited to MSN 31-367 F-GDPU	20/02/2006	Active	10014278
EASA.A.S.01516	MOTORFLUG BADEN-BADEN GmbH			2. 200, 300, 300LW 1. B200, B300	Installation of Honeywell CAS-67A ACAS-System and Dual MST 67A Dual Mode S Transponder System Enhanced Surveillance (Exchange of existing transponder)		EASA Approved Airplane Flight Manual Supplement B300-123667-0601, Revision 1, dated 20.05.2006 or later EASA approved revision.		13/06/2006	Active	10014279
EASA.A.S.01517	MOTORFLUG BADEN-BADEN GmbH			2. 200, 200C, 300, 300LW 1. B200, B200C, B300	Installation of Dual Mode-S Transponder System Rockwell-Collins TDR-94D and Collins CTL-92E		EASA Approved Airplane Flight Manual Supplement 123567-0601, Revision 1, dated 06.09.2006 or later approved revision		16/11/2006	Active	10014280
EASA.A.S.01520	LUFTHANSA TECHNIK AG			BOEING 757-300	Installation of Zonal Drying System		Supplemental Type Definition Document STDD21-05/02M, Issue 1, Rev. 0, or later approved revisionInstructions for Continued Airworthiness CS21-0142-02, Rev. IR, or later approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	06/11/2007	Active	10014283
EASA.A.S.01521	DASSAULT FALCON SERVICE			MYSTERE FALCON 20	Power Utility		see Change approval sheet DFS 2549 associated list of affected technical documents	System activation is not considered	28/09/2005	Active	10014284
EASA.A.S.01522	TROYES AVIATION S.A.R.L.			CESSNA 340A	FAM n° 47 - Limitation of MTOW to 2699 kg		Flight Manual Supplement "A" Edition 1 Revision 0 dated December 05.	s/n 340A-0451	23/02/2006	Active	10014285
EASA.A.S.01523	AERODISA S.L.			DC-8-62	Revision to the cargo modification on DC-8-62. Compliance with FAA AD 2001-26-04 & AD 2001-26-01.		Documentation referred in Doc. AED2005-01M Issue 01, April 2006.Maintenance Manual Supplement AED2005-01M_SMM Issue 01,April 2006.	Limited to DC-8-62 series airplanes which have been converted from a passenger to a cargo-carrying ("freighter") configuration by FAA STC No. SA1802SO, but with a deviation in themain deck cargo 9g crash barrier that was installed following FAA STC No. SA1377SO.	18/04/2007	Active	10014286

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01529	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH 1900	Installation of Universal Flight Manager System UNS-1L		-AFM Supplement Beechcraft 1900 and series with Universal UNS-1L; Report 2005-23-08-AMM Supplement for Universal UNS-1L; jet Aviation Document 2005-23-10		25/01/2006	Active	10014288
EASA.A.S.01531	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH 200C BEECH 200	Installation of Universal Flight Management System UNS-1L		- Engineering Order Report 2005-12 Rev. A- AFM-Supplement Beechcraft 200 and Series with Universal UNS-1L Report 2005-12-8 Rev. A or later- Maintenance Manual System Beechcraft 200 and Series with Universal UNS-1L Report 2005-12-10 Rev. A		24/10/2006	Active	10014289
EASA.A.S.01532	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			IAI ASTRA SPX	Installation of Universal Cockpit Display System		Engineering Order, Report 2005-8 dated 23 June 2005, Rev. Aor later EASA approved RevisionsAirplane Flight Manual Supplement, Report 2005-8-8 dated 23 June 2005 Rev.A or later EASA approved RevisionsInstruction for Continued Airworthiness, Maintenance Manual Supplement Ref. 2005-8-10	n/a	14/12/2005	Active	10014290
EASA.A.S.01533	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			IAI ASTRA SPX	Installation of Universal Unilink UL-601		Engineering Order, Report 2005-5 dated 16 February 2005, Rev. B or later EASA approved RevisionsAirlpane Flight Manual Supplement, Report 2005-5-8, dated 09 March 2006 Rev. B or later EASA approved RevisionsInstruction for Continued Airworthiness, Maintenance Manual Supplement Rep. 2005-5-10	Certification Basis:FAR Part 25, TGL Leaflet No. 15 and 16	19/04/2006	Active	10014291
EASA.A.S.01535	LUFTHANSA TECHNIK AG	REV 1		BOEING 747-SP	ATC System, Upgrade to Enhanced SurveillanceNote: This Revision expands the application range of the existing STC.		Supplemental Type Definition Document No. STDD34-05/08, M, Issue 2, Rev. 00, dated 15 January 2007 or later approved revision;Airplane Flight Manual Supplement A-34-06/499-AFM, Revision IR, dated 22 Nov 2006 or later approved revision	1. Certification Basis of the change: CS 25 Change O, additionaly JAA Leaflet No. 18 (Mode-S EHS)2. This STC is approved only for the product configuration as defined in theapproved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations...	15/01/2007	Active	10014293
EASA.A.S.01536	DASSAULT FALCON SERVICE			MYSTERE FALCON 20	DFS 2562 dtd 21.Dec 05: Master Mission Function		see Change approval sheet DFS 2562:DFS AFM Supplement F2049 and associated list of affected technical documents	1. This STC is approved only for the configuration as defined in Mod Sheet DFS 25622. Compatibility with other aircraft/ engine configurations shall be determinded by the installer	25/01/2006	Active	10014294

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01537	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH 400A (HAWKER 400 XP)	IInstallation of a Rockwell Collins TCAS 4000 with dual TDR-94D Transponder		Engineering Order Doc. No. 2027113-EO-01 Issue 1 or later EASA approved revisions.Airplane Flight Manual Supplement Rockwell Collins TCAS 4000 Doc. No. 2027113-AM-01A Issue 2 or later EASA approved Revisions.Airplane Flight Manual Supplement Rockwell Collins Dual TDR-94D Mode S Transponder System, D...		15/11/2005	Active	10014295
EASA.A.S.01540	AIR CARAIBES INDUSTRIES			DORNIER 228-202	Flight Data Recorder installation. Installation of SSFDR type flight data recorder following OPS 1.725 implementation.		Pilot's Operating Handbook Dornier 228 MSN 8139 Reg. F-OGOL.Supplement to MOD Air Caraibes Industries DO228-0703, Edition 2 dated 6/04/2005.	1. This STC is limited to MSN 8139, F-OGOL	12/09/2005	Active	10014296
EASA.A.S.01541	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH B200C BEECH B200 BEECH 200C BEECH 200	Installation of Universal Multifunction Display MFD-640		- Engineering Order Reoprt 2005-14 Rev. A - AFM-Supplement Beechcraft 200 and Series with Universal Multifunction Display MFD-640 UNS-1L Report 2005-14-8 Rev. A or later approved revision - Maintenance Manual System Beechcraft 200 and Series with Universal Multifunction Display Report 2005-14-10 R...		31/08/2006	Active	10014297
EASA.A.S.01543	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			GULFSTREAM 100 ASTRA 1125	Installation of Collins TCAS 4000		Engineering Order, Report 2005-28, Revision B dated 24, April 2006 or later approved Revisions.Airplane Flight Manual Supplement, Repport 2005-28-8, Revision B dated 18 July 2006 or later approved Revisions	Certification basis of the change: FAR Part 25, additionally JAA Leaflet No. 8 Rev. 2 (ACAS II), JAA Leaflet No. 13 Rev. 1 (Mode S ELS), JAA Leaflet No. 18 (Mode S EHS)	28/08/2006	Active	10014299
EASA.A.S.01544	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			WESTWIND ASTRA 1125	Installation of Garmin GNC 300XL		Engineering Order, Report 2005-29, Revision B dated 24, April 2006 or later approved Revisions.Airplane Flight Manual Supplement, Report 2005-29-8, Revision B dated 24, April 2006or later approved Revisions.	Certification basis of the change: FAR Part 25, additionally EASA AMC 20-5 (GPS)	28/08/2006	Active	10014300
EASA.A.S.01545	AEROTEC & CONCEPT			C90	Installation of radio communication systemsModel: Beechcraft C90 SN LJ 710		Supplemental AFM for GNS 530 edition 1 of 15 January 2005, revision 2,Supplemental AFM for GNS 430 edition 1 of 15 January 2005, revision 2 andSupplemental AFM for KMD 850 edition1 of 15 January 2005, revision 2	1. This STC is limited to Beechcraft C90 SN LJ 710.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft configurations shall be determined by the installer.	12/09/2005	Active	10014301
EASA.A.S.01548	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH S35	Installation of following equipments: KN63+KDI572+KX165+KI203+KMD150+ AR4401+WX500+ANT NY163		FAM No 299/03 and AFMS for KMD 150 No 2 - Revision 0	This STC is applicable only for the Beechraft S35 - S/N D7498	16/09/2005	Active	10014304
EASA.A.S.01550	AERLYPER S.A.			BEECH 200	Installation of MST67A Transponder Mode S Equipment.		Master Data List AERLYPER DOC N° 100469 Ed. 04Instruction for continuous Airworthiness AERLYPER DOC: N° 100482 Ed. 01		06/12/2007	Active	10014306

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01551	SOGERMA SERVICES	REV 1		ATR 42-320	Additional probes in RALI configuration in accordance with MAS SOG-01-459 issue 1 dated 30/11/05Note: This revision reflects the transfer of this STC from EADS Sogerma Services toSogerma Services.		AFM supplement Ref 240/04/SOG/DEV issue 4	1. MSN 078 Associated STC No.EASA.A.S.01219 Revision 1	04/01/2008	Active	10014307
EASA.A.S.01553	LUFTHANSA TECHNIK AG			AIRBUS A319	Installation of new B/E Aerospace convertible and standard seats and cabin refurbishment to PG-design on Lufthansa's A319 aircrafts		Certification Program CP25-05/20M, issue 03, dated 18 Jan 2006Supplemental Type Definition Document STDD25-05/20M, issue 01 dated 30/01/2006Compliance Record List CRL25-05/20M, issue 01 dated 24/01/2006Applicant's Declaration of Compliancedated 03/02		16/02/2006	Active	10014308
EASA.A.S.01554	LUFTHANSA TECHNIK AG			BOEING 747-400	B747-400 Guggenheim Seat Arrangement Modification from 384 passengers (main deck16 FC, 28 BC, 310 Y) to 398 passengers (main deck 12 FC, 0 BC, 46 Y + 310 Y) according to STD00-05/10M		Interior Arrangement according Design Document "EngineeringBulletin"Doc. No. 747-EB25-1068		24/10/2005	Active	10014309
EASA.A.S.01555	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BAE 146	Change EGPWS Altitude Callouts		"Bournemouth Aviation (Consultants) Ltd Modification BAC/146/057 Issue 1 or later approved revision.		16/03/2006	Active	10014310
EASA.A.S.01556	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525	Installation of SKY497 and TAWS 8000The SKY497 is wired to the new Antenna, existing AM-250 Copilot Altimeter, i-linc MFD and Audio CTL. The TAWS 8000 is wired to theexisting MFD, KLN90B and ADC 200		EASA approved AFM Supplement FMS ASR 2005-023-00 Rev. A, orlater approved revisions		21/06/2006	Active	10014311
EASA.A.S.01558	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	FALCON 20 BASIC,D AND E SERIES	DC-0038: ACAS II and Mode S Installation		see FRA Certification Document CP-0038:AFM Supplement FRAH/FM/108 to AFM UK Supplement DTM918	1. This STC is approved only for the configuration as defined in DC-00382. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the instal...	02/01/2006	Active	10043015
EASA.A.S.01561	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH 400A (HAWKER 400 XP)	Installation of a L3 Digital FDR and Teledyne FDAU		1) Engineering Order Doc. No.2029534-AM-01 Issue 2 or laterEASA approved Revisions.2) Airplane Flight Manual Supplement, Doc. No.2029534-AM-01 Issue 2 or later EASA approved Revisions.3) Instruction for Continuous Airworthiness Doc. No.2029534-CA-01.		22/11/2005	Active	10014313
EASA.A.S.01562	E A D AEROSPACE AIRWORTHINESS	REV. 1		FAIRCHILD SWEARINGEN SA 227 SE	Installation of TCAS II on SA 227 series aircraftTCAS II installation in accordance with EAD Supplemental Type Design Definition Document 01043-EAS-A-STD-01 rev. A :• Removal of existing TCAS and associated tray in forward avionics• Installation of TCAS II processor on a new tray in forward avionics...		Aircraft Flight Manual Supplement :Document 01043-EAS-A-AFM-01 Rev. CMaintenance Planning Document Supplement :Document01043-EAS-A-MPD-01 Rev. B	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	03/04/2006	Active	10014314
EASA.A.S.01563	E A D AEROSPACE AIRWORTHINESS			AEROSPATIALE ATR 42-300 SERIES	Installation of a calibration antenna in accordance with 01050-EAS-A-MDL.		Maintenance Planning Document Supplement ref. 01050-EASA-A-MPD-01.		21/04/2006	Active	10014315

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01567	AERLYPER S.A.			BEECH 200, SUPER KING AIR	Tactical console installation on B-200 aircraft with ARGOS system, tactical communications system and fixed provisions for ASTRA system.		Documentation referred to in Doc. No. 100513 "Documents andDrawings List" Issue 04, 27 November 2006. Doc. No. 100528 "Aircraft Flight Manual Supplement", Issue 1, 27 November 2006 included.	In accordance with Doc. No. 100528 "Aircraft Flight Manual Supplement", Issue 01, 27 November 2006.	31/05/2007	Active	10014317
EASA.A.S.01568	AERLYPER S.A.			BEECH 200	Inmarsat SATCOM installation on board B200.The modificationis optional and fixed. It consists of an Inmarsat SATCOM terminal to be installed in the passenger cabin. A SATCOMantenna is installed on the upper part of the fuselage.		Documentation referred in: Doc 100423 Ed.04: Documents andDrawings List.	In accordance with Doc. No. 100429 AFM Supplement ED. 03.	31/05/2007	Active	10014318
EASA.A.S.01569	AERLYPER S.A.			BEECH 200	Installation of New Avionics Equipment to comply with COM/NAV regulations for IFR and B-RNAV Operation.		Master Data List AERLYPER DOC N° 100542 Ed. 4New Supplementto Aircraft Flight Manual AERLYPER DOC N° 100553 Ed. 00Instructions for Continuous Airworthiness AERLYPER DOC N° 100554Ed. 02		06/12/2007	Active	10014319
EASA.A.S.01573	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	A330	Installation of In Seat Power Supply Korean Air Airbus A330		BBJ Design Services Modification BBJ569		25/01/2006	Active	10014321
EASA.A.S.01577	DAO AVIATION A/S			BEECH 200, SUPER KING AIR	Installation of Honeywell ACAS II system comprising CAS 67Aprocessor, 2 IVA-81D VSIs and 2 ANT-67A antennas.		DFE Design order package DO-0059.Honeywell installation manualAntenna instalation design by Raytheon Aircraft Company Ref. no. JBB/0416-06. Drawing kit P/N 101-4092, rev 1.	MSN BB-309 only.	27/10/2006	Active	10014324
EASA.A.S.01579	LUFTHANSA TECHNIK AG			B737-800	Business Class Installation with Sicma Seats		Supplemental Type Definition Document Ref. STDD 25-05/31M, Issue 2 dated 16 December 2005		13/01/2006	Active	10014326
EASA.A.S.01580	JET AVIATION VIENNA GMBH			S/N 560-0260 AND ON 560	Upgrade of the existing MK V1 Ground Proximity Warning System to MK VIII (Enhanced Ground Proximity Warning System)Cessna 560 Citation Ultra, S/N 560-0260 and on, equipped with Honeywell Integrated Avionics System, Honeywell Primus © II SRZ Integrated Radio System and MK VI GPWS		ARS Engineering Order 5426/05/2	N/A, Demonstration on S/N 0446	13/03/2006	Active	10014327
EASA.A.S.01581	JET AVIATION VIENNA GMBH			560	Integration of a Traffic Alert and Collsision Avoidance System and update of the ATC Mode S Transponders to Elementary Mode SCessna 560 Citation Ultra, S/N 560-0260 and on, equipped with Honeywell Integrated Avionics System, Honeywell Primus © II SRZ Integrated Radio System		ARS Engineering Order 5426/05/1	N/A; Demonstration on S/N 0446	13/03/2006	Active	10014328
EASA.A.S.01582	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 560 (CITATION V)	Installation, Completion of custom Aircraft Interior for BD700-1A10 Global Expressacc.: CDL D954000 Rev. KValidation ofimported TCC STC: SA04-113		AFM Supplement G-FM25004001 Rev N/C or later TCCA approved rev.ICA GC91450000-IFCAAMM Supplement G-TM05104001	Ref. G-FM25004001 Rev. N/C: Limited to S/N 9145	13/03/2006	Active	10014329
EASA.A.S.01585	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 737-200	Installation of Cargo Hold Smoke Detection & Fire Suppression System		Bournemouth Aviation (Consultants) Compliance Document ref.BAC/737/046 issue 1 or alter approved revision		01/12/2005	Active	10014331
EASA.A.S.01586	DASSAULT FALCON SERVICE			FALCON 10	Update ATC Transponder for elementary surveillance DFS 1253issue A		See Change approval sheet DFS 1253 associated list of affected technical documents	This STC is approved only for the configuration as defined in Mod Sheet DFS 1253.	10/10/2005	Active	10014332

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01587	SCANDINAVIAN AVIONICS DESIGN ApS			LETECKE ZAVODY L 410 UVP-E20	Installation of Honeywell CAS 67A TCAS II including dual MST 67A Mode S Transponder		-AFM Supplement Doc 2026472-AM-01A, Issue 2 or later EASA approved revision-AFM Supplement Doc 2026472-AM-01B, Issue 2 or later EASA approved revision-AFM Supplement Doc 2026472-AM-01C, Issue 2 or later EASA approved revision-AFM Supplement Doc 2026472-AM-01D, Issue 2 or later EASA approved revision...		22/02/2006	Active	10014333
EASA.A.S.01589	DASSAULT FALCON SERVICE			FALCON 10	DFS1226 Revision D dated 9 June 2005: Installation of Collins TCAS 4000with one or two TDR-94D		1. See Change approval sheet DFS 1226 associated list of affected technical documents2. AFM Supplement F10 DFS No 34 dtd. 09.06.2005	This STC is approved only for the configuration as defined in Mod Sheet DFS 1226.	10/10/2005	Active	10014334
EASA.A.S.0159	TRANSAIRCO S.A.	REV. 1		PC-12, PC-12/45 AND PC-12/47	Installation of a Garmin GMA-340 Audio Panel. Data required: I)Engineering Order TSAPCI2-23.50.01EO.		- TSA PCI2-23.50.01EO Rev. A dated 10AUG05 and Rev, B dated16JAN06 andlater approved revisions	1. KMA-24H Audio Panel is a pre-requisite installation.2. This installation should not be incorporated in any aeroplanes unlessit is determined that the interrelationship between this installationand any previously approved configuration changes will not introduce anyadverse effect upon the airworth...	03/07/2006	Active	10061993
EASA.A.S.01590	BUSINESS AND COMMUTER AIRCRAFT			BEECH 1900C, AIRLINER	Installation of ACSS TACS 2000 System on Beech 1900C.		AFMS referenced BCA 55 dated April 2005 Revision 3.STC Document referenced BCA55/STC 1241 dated August 2004, Revision 1	This STC is limited to Beech 1900 C SN UC-115	11/10/2005	Active	10014335
EASA.A.S.01591	JET AVIONICS AVIATION & MARINESERVICE CENTER S.r.l.			CESSNA 650 CITATION III	BDI 004-05 Updating to TCAS II & ELT system and installation SSFDR		Master Drawing List No. BDI 004-05-01 dated 18/04/2005Technical Report No. BDI 004-05-02 dated 18/04/2005AFM S for FDR No. BDI 004-05-10 dated 19/04/2005AFMS S for TCAS II CAS 67ANo. BDI 004-05-15 dated 19/04/2005	Applicable only if the STC No ST502CH of 16 may 1996 was previously installed	11/10/2005	Active	10014336
EASA.A.S.01594	SOCIETE AIR FRANCE S.A.			MSN 498, 500, 502, 503, 516, MSN 422, 443, 448, 458, 465, AIRBUS A330-203	Air France A330 "Ulysse" cabin reconfiguration in accordance with Change Approval Sheet No. CAS-A330-04-001 dated 16/09/2005 (or later EASA approved revision)			The approval of this STC is limited to Airbus A330-203 Serial Numbers 422, 443, 448, 458, 465, 481, 498, 500, 502, 503,516, 519. The Limitations and conditions defined in the EASA Datasheet are applicable.A copy of this STC and the CAS must be enclosed in the files of each modified aircraft.	12/10/2005	Active	10014337
EASA.A.S.01596	SOCIETE AIR FRANCE S.A.			BOEING 747-400	Air France B747-400 Big Bins modification. This is a revision to the EASA STC Ref 2004-4528, to extend the applicability to Boeing747-400 , F-GEXA, MSN 24154.The general description is included in the Air France Letter BL.NI 10 003/EB andin the AEO 47-25-2071 Revision 2.Model: B747-400, MSN 24969,...			1. The approval of this modification is limited to the Boeing B747-400 MSN 24969, 24990, 25344, 25600, 25601, 25602, 32868, 32869, 32871, 25238, 25302, 25559, 25628, 25630, 24154,24155.The limitations and conditions defined in the EASA Datasheet are applicable.2. A copy of this STC and of the CAS m...	19/10/2005	Active	10014338

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01597	CESKA LETECKA SERVISNI A.S.			MITSUBISHI MU-2B-36A	Avionics Upgrade in accordance with doc No CLS-05-MU-AC128,Revision 1.3., dated 27/01/2006.		Mitsubishi MU2-B Flight Manual Supplement No AC128-2501, Rev. 3 dated 27/01/2006Mitsubishi MU2-B Maintenance Supplement, No AC128-2701, Rev. 1.1 dated 27/01/2006	Limited to S/N MU2B-36A-718SA.	08/02/2006	Active	10014339
EASA.A.S.01598	AVIONIK STRAUBING ENTWICKLUNGS GmbH			550	Installation of CAS67A (incl. MST67A), Mark VIII, Kannad 406AF and Garmin GPS400		Table of Contents FO E-05 (ASR 2005-042-00) Rev. 0 or laterapproved RevisionFlight Manual Supplement FMS-ASR2005-042-00 Rev. A (TCASII CAS67A) or later approved RevisionFlight Manual Supplement FMS-ASR2005-042-01 Rev. A (XPDR MST67A) or later approved RevisionFlight Manual Supplement FMS-ASR2005-04...	Certification Basis of the Change: CS 25, additionally AMC 20-4 (Basic R-Nav), AMC 20-5 (GPS), JAA Leaflet No. 8, Rev. 2 (ACAS II),JAA Leaflet No. 12 (TAWS), JAA Leaflet No. 13 Rev. 1 (Mode-S ELS), JAA Leaflet No. 18 (Mode-S EHS)	11/04/2006	Active	10014340
EASA.A.S.01601	ELECTRONIQUE MAINTENANCE AVIATION			FAIRCHILD SWEARINGEN SA 226-T(	ATC Mode S, ELT 406 MHz, Altimeter, Turn and Bank annunciator installation		- AFM Supplement "Supplement au Manuel de Vol RBDA"- STC No. EMA/02/003/SA226Serie/ATC.ELT.ALTI.T/B		30/01/2006	Active	10014341
EASA.A.S.01602	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	BEECH 200	Major Avionic Upgrade		Lees Avionics Ltd Modification HL/MOD/673Lees Avionics Ltd AFM Supplements AFMS673001, AFMS673002, AFMS673003 & AFMS673004 all at Issue 1 datedJanuary 23 2006 or later approved revision.		06/04/2006	Active	10014342
EASA.A.S.01603	SCANDINAVIAN AVIONICS DESIGN ApS			PIPER PA-34-220T PIPER PA-34-200T PIPER PA-34-200	Installation of KMD 850 Multi Function Display		AFM Supplement Piper Model PA-34-200, -200T, 220TDoc. 2029789-AM-01, Issue 1		03/04/2006	Active	10014343
EASA.A.S.01606	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	LOCKHEED L1011 - TRISTAR	Introduction of a stand-alone GPS receiver		STC Twenty One AFM Supplement S21.FMS-0007 Issue 1 or laterapproved revision"		22/03/2006	Active	10014344
EASA.A.S.01608	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH B200C BEECH B200 BEECH 200C BEECH 200	Installation of Blue Sky C-1000 SATCOM		- Engineering Order Report 2005-15 Rev. A - AFM Supplementfor Beechcraft 200 and Series with Blue Sky C-1000 SATCOM Report 2005-15-8 Rev. A or later approved revision. - Maintenance Manual System Beechcraft 200 and Series with Blue Sky C-1000 SATCOM Report 2005-15-10 Rev. A		31/08/2006	Active	10014345
EASA.A.S.01609	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH B200C BEECH B200 BEECH 200C BEECH 200	Installation of Universal TAWS		- Engineering Order Report 2005-15 Rev. A - AFM Supplementfor Beechcraft 200 and Series with Universal TAWS Report 2005-13-8 Rev. A or later approved revision		31/08/2006	Active	10014346

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01611	LUFTHANSA TECHNIK AG			AIRBUS A321	Installation of new B/E Aerospace convertible and standard seats and cabin refurbishment to PG-design on Lufthansa's A321 aircrafts		1. Certification Program CP25-05/22M, issue 02, dated 20.01.20062. Supplemental Type Definition Document STDD25-05/22M,issue 01 dated 17.02.20063. Compliance Record List CRL25-05/22M, issue 01 dated 17.02.20064. Applicant's Declaration ofCompliance dated 21.02.2006	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	03/03/2006	Active	10014347
EASA.A.S.01612	SOGERMA SERVICES	REV 1		AIRBUS A340-642	This STC deals with the installation of 4 new double seats in Y class (Kyoto manufacturer)Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.		The associated Modification Approval Sheet is referenced SOG-25-1233 issue 1 dated 30/11/05.All documents related to this STC are listed in the Master Data List Drawing n ° MDL-25-1233, Issue No B. (or later EASA approved revision)TECHNICAL REPERCUSSION SHEET reference 21-1233 issue B.	1. This STC is approved only to allow airline customer to install on a trial basis a few seats on one aircraft (MSN 706).2. The limitations and conditions defined in the EASA Datasheet are applicable.A copy of this STC and of the MAS/MDL must be enclosed in the files of each modified aircraft....	04/01/2008	Active	10014348
EASA.A.S.01614	JET AVIONICS AVIATION & MARINESERVICE CENTER S.r.l.			BEECH 58, BARON	Imrpoving of avionics systems for updating FM immunity 8.33kHz channelling, B-RNAV, Mode S Transponder, TAWS, Weather Radar, Traffic Advisory System, ELT and entertainment system.		Master Drawing List BDI 005-05-01 Rev. 0, dated 09/07/2007.	FM Supplement Sandel SN-3400, dated 09/07/2007.FM Supplement Sandel ST-3400, dated 09/07/2007.FM Supplement Garmin GTX 330, dated 09/07/2007.FM Supplement Garmin GNS 430, dated 09/07/2007.FM Supplement Garmin MX-20, dated 09/07/2007.FM Supplement L3 Sky-497, dated 09/07/2007.FM Supplement AD32 Air D...	08/08/2007	Active	10014349
EASA.A.S.01615	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	BAE 125 -800 SERIES	Steep Approch Capability		Raytheon Aircraft Sercives Certification Plan ASC-C-008-AV1253.Raytheon Aircraft Services AFM Supplements Flight ManualRef. HS.1.16 Supplement 10 Issue 1 & HS1.15 Supplement 15 Issue 1 or laterapproved revisions.		25/10/2005	Active	10014350
EASA.A.S.01616	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			LEARJET 35A LEARJET 35	Installation of Flight Data Recorder F1000		Engineering Order 2003-6, Revision B or later EASA approvedrevisions		26/10/2005	Active	10014351
EASA.A.S.01617	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BAE 146/AVRO 146 SERIES	Installation of BRNAV Compliant GPS		Bournemouth Aviation (Consultants) Modification BAC/146/064Issue 1 or later approved revisionBournemouth Aviation (Consultants) AFM supplement FMS/353/31 Issue 1 dated 25 November 2005 or later approved revision		12/12/2005	Active	10014352
EASA.A.S.01618	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 560 (CITATION V)	Installation of Honeywell EGPWS Mark VIII		Airplane Flight Manual Supplement Cessna C560 Citation V with Honeywell EGPWS Mark VIII, Revision A dated 23.02.2004 or later approved Revision, Jet Aviation Doc.No. 2003-4-8Aircraft Maintenance Manual Supplement Jet Aviation Doc. No. 2003-4-10, Rev.A		02/11/2005	Active	10014353

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01619	LUFTHANSA TECHNIK AG	REV 4		BOMBARDIER CL-600-2B19	CL-600-2B19 - Cabin Completion - 15 PAX – Configuration D.		1. Supplement Type Definition Document STDD00-05/12M, issue 04, dated November 13, 2007, or later approved revision2. Configuration Identification Document CID-15-01619-LHT,issue 03, dated November 2, 2007, or later approved revisionConfiguration A*:Aeroplane Flight Manual Supplement S-804650...	1. Certification Basis of Change: JAR-25 Change 13, additionally:Configuration A and B*:CRI D-01, Side facing Divan (Deviation)CRI F-01, Executive Power Systems (Guidance Material)JAA TGL No. 17, Passenger service and In-Flight Entertainment (IFE) systemsConfiguration C*and D*:CRI D-01, Side faci...	20/11/2007	Active	10014354
EASA.A.S.01620	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	BEECH 200, SUPER KING AIR	Major Avionic System Upgrade		AFMS677001 iss x for GNS530 BRNav complianceAFMS677002 iss x for GNS430 BRNav complianceAFMS677003 iss x for GNX330D Mode S		19/12/2005	Active	10014355
EASA.A.S.01621	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	BOEING 737-400	Installation of Galley 1 & Galley 2 for Futura International Airways		DD 1027: issue new or later approved issue		06/01/2006	Active	10014356
EASA.A.S.01624	LUFTHANSA TECHNIK AG			BOEING 737-300 SERIES	Installation of new Recaro Seating convertible and standardseats and cabin refurbishment to PG-design on Lufthansa's Boeing B737-300 aircraft		"Certification Program CP25-05/23M, issue 01, dated 01.02.2006 Supplemental Type Definition Document STDD25-05/23M Iss.01, Rev. 00, 27.02.06	Certification Basis of the change: FAR25 as defined in FAA TCDS A16WE. The applicant showed compliance to CS 25.0785(h)(2), CS 25.811 (d), (g), CS 25.812€, CS 25.0853(a), (c), (d),(f).	13/03/2006	Active	10014359
EASA.A.S.01625	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH A36	Replacement of existing KI-525A HSI system with new KI-825 EHSI system		AFM Supplement Doc. 2029169-AM-01, issue 2, December 2005, or later EASA approved issue		20/02/2006	Active	10014360
EASA.A.S.01627	AIR FRANCE			BOEING 767-300	Cabin Reconfiguration with an increased seating configuration for LOT Polish Airlines.		Air France Change Approval Sheet CAS-B767-05-006 Revision 0or later approved revision.Air France AFM Supplement MA.PM 133/06 KA Initial Release dated 2006-02-17 or later approvedrevision.		24/04/2006	Active	10014361
EASA.A.S.01631	ATS INTERNATIONAL	REV 1		DC-10 SERIES	Installation of a Honeywell Enhanced Ground Proximity Warning System MK VII.The FAA has processed a similar applicationfor an STC for a similar installation under project n°: ST00536E.		See item 5 of CAA Netherlands approval report STC ref. no. P-EASA.A.S.01631 dated 05/12/2006	1) Approval of this change in type design applies to the above model aircraft equipped with either a Flight Management System (FMS), which meets AC90-45A, a Global Positioning System (GPS) navigational based system or an EGPWS equipped with an internal GPS card and a GPS antenna as defined in the Ma...	20/12/2006	Active	10014363
EASA.A.S.01635	SOGERMA SERVICES	REV 1		A340-642	This STC deals with the installation of a 2 new triple seats in W class (Contour design seats).Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.		The associated Modification Approval Sheet is referenced SOG-25-1217 issue1 dated 30/11/2005.All documents related to this STC are listed in the Master Data List Drawing n° MDL-25-1217, Issue No B. (or later EASA approved revision)TECHNICAL REPERCUSSION SHEET reference 25-1217 issue B.	1. This STC is approved only to allow airline customer to install on a trial basis a few seats on one aircraft (MSN 706).2. The limitations and conditions defined in the EASA Datasheet are applicable.A copy of this STC and of the MAS/MDL must be enclosed in the files of each modified aircraft....	04/01/2008	Active	10014365
EASA.A.S.01636	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA S550 CESSNA 560 CESSNA 550	Installation of Honeywell CAS 81 ACAS and MST 67A Mode-S XPDR		Jet Aviation Engineering Order, Report 2005-6, Rev. AAirplane Flight Manual Supplement, Report 2005-6-8, Rev. A or later approved RevisionMaintenance Manual Supplement, Report 2005-6-10		14/11/2005	Active	10014366

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01637	LUFTHANSA TECHNIK AG			AIRBUS A319	A319 CJ VIP Cabin 34 Pax		Supplemental Type Definitation Document STDD00-05/08M, issue 02 dated 18.07.2006Airplane Flight Manual Supplement A-00-05/343-AFMSApplicant's Declaration of Compliance dated 19.07.2006	1. JAR-25 Change 112. FAR 25.981 (a) (b) Amdt. 102 'Fuel Tank [ignition prevention]'3. 'CRI D-03 'Type III Emergency Exit Access' dated 31. March 20064. CRI F-01 'Dimestic Power' dated 18 May 20065. TGL No. 17 'Passenger Service and In-Flight Entertainment (IFE) Systems'6. TGM/25/10 'In-seat Power s...	21/07/2006	Active	10014367
EASA.A.S.01638	AERODISA S.L.			EMBRAER EMB-120	Structural Permanent element for a Winch installation.		1. Doc. AED2005-02M_MDL “Master Data List”, Ed. 3 Rev. 0, dated 5 October 2008.2. Doc. AED2005-02M_D02 “Aircraft Maintenance Manual Supplement”, Ed. 3 Rev. 0, dated 5 October 2008.3. Doc. AED2005-02M_SWD “Aircraft Wiring Diagram Supplement”, Ed. 3 Rev. 0, dated 5 October 2008.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	04/11/2008	Active	10014368
EASA.A.S.01640	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	737-3M8	Introduction of G2 Stowage Galley		Aerospace Design & engineering Consultants Ltd. Modification MOD-0016	--	06/04/2006	Active	10014369
EASA.A.S.01641	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CONSTRUCCIONES C-212	Installation of CAS 67A ACAS II and dual MST 67A Mode-S XPDR		Engineering Order, Report 2005-37, Rev. B, 17.01.2006Airplane Flight Manual Supplement, Report 2005-37-8, Rev. A, Date 22. December 2005	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	23/02/2006	Active	10014370
EASA.A.S.01649	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH B300 BEECH 300LW BEECH 300	Installation of Universal UNS-1L Softeware 802.XX		AFM Supplement Beechcraft B300 and Series with Universal UNS-1LReport 2005-33-8, Rev. B, or later EASA approved revision	Instructions for Continued Airworthiness, Doc. No. 2005-33-10 Rev. B	13/07/2006	Active	10014374
EASA.A.S.01650	SOCIETE AIR FRANCE S.A.			BOEING 747-300 BOEING 747-200	Suppression of climb inhibition above flight level 300 on TCAS computer in accordance with AEO 47-34-0714 Revision 1 dated 17/10/2005		AEO 47-34-0714 Revision 1 dated 17/10/2005		23/11/2005	Active	10014375
EASA.A.S.01651	BRITISH AIRWAYS PLCt/a BRITISH AIRWAYS ENGINEERING		CAA UK RESPONSIBILITY	BOEING 737-400	Installation of Enhanced Mode S		British Airways Engineering Project Certification Plan Ref.CP-0002-04 Issue 1 or later approved revision.	None	25/11/2005	Active	10014376
EASA.A.S.01652	RUAG AEROSPACE SERVICES GmbH			CESSNA 560	Installation of a Honeywell Solid-State Flight Data Recorder (SSFDR) with Teledyne Controls Mini Flight Data Acquisition Unit (MFDAU)		Engineering Order 148A EO, dated 02.01.2006Aircraft Flight Manual Supplement, Doc. 148A-AFMS, Issue N/C, dated 09.01.2006Maintenance Manual Supplement, Doc. 148A-AMMS, dated 09.01.2006		20/01/2006	Active	10014377
EASA.A.S.01653	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	JETSTREAM 3202	Installation of Dual GNS530 with Dual GI-106A & Dual KNI-582 RMI		Phoenix Aviation Design Services Master Document List PADS/MDL/ 1003/001Phoenix Aviation Design Services AFM Supplement PADS/FMS/ J31-32/001 Revision 0 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/02/2006	Active	10014378

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01658	AIR FRANCE			BOEING 767	Emergency Escape Path Marking System		Air France Industries Modification EA33-B767-05-008 Revision 00 or later approved revision.Air France Industries AFM Supplement reference MA.PM 827/05 CE Initial Release dated December 06 2005 or later approved revision.		08/02/2006	Active	10014380
EASA.A.S.01665	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	PILATUS PC-12/45	Substantiation of Garmin AT GPS400 installation for IFR		Tatenhill Aviation Ltd Modification TAL_TAD 019/05TatenhillAviation AFM Supplement TAL-BRNAVFMS-TAD 019/05 Issue 1 or later approved revision.		20/06/2006	Active	10014381
EASA.A.S.01666	AERO-DIENST GMBH & CO. KG			25C	Collins TCAS-4000 with Dual TDR-94D System Installation		Engineering Order No.: 212-LR Rev. IR with Appendix AAirplane Flight Manual Supplement AG524-071, Revision IR	Certification Basis of Change: FAR 25 as defined in TCDS A10CE issue 55, additionaly JAA Leaflet No. 8, Rev. 2 (ACAS II), JAA Leaflet No. 13, Rev. 1 (Modes S ELS)	03/03/2006	Active	10014382
EASA.A.S.01667	DASSAULT FALCON SERVICE			MYSTERE FALCON 2000EX MYSTERE FALCON 2000	DFS D078 dtd. 5.4.2006: EGPWS Software 222-222		see Change approval sheet DFS D078and associated list of affected technical documents	1. Activation of Runway Awareness Advisory System (RAAS) isnot approved through this STC2. This STC is approved only for the configuration as defined in Mod Sheet DFS D0782. Compatibility with other aircraft/ engine configurations shall bedetermined by the installer	07/07/2006	Active	10014383
EASA.A.S.01669	CRANFIELD AEROSPACE LTD		CAA UK RESPONSIBILITY	JETSTREAM 4100	Installation of a Honeywell Global GNS-XLS		AFM Supplement - Cranfield Supplement No 2 Issue 1Type Design Definition Addendum CA/ DD/E2184 Issue 4DF/ Jetstream41/1232	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	20/02/2006	Active	10014384
EASA.A.S.01671	AERO-DIENST GMBH & CO. KG			HS.125 SERIES 700B	Installation of Honeywell EGPWS Mark VIII System and interface to Honeywell KMD-850 MFD via a KAC-502 EGPWS Module.		Installation in accordance with Aero-Dienst Engineering Order ref 205-HW, Rev. IR, dated 06. Feb. 2006, or later approved revision.To be operated in accordance with Aero-Dienst Airplane Flight Manual Supplement ref AG516-071, Rev IR, dated10 April 2006, or later approved revision.	None.	19/04/2006	Active	10014385
EASA.A.S.01672	AERO-DIENST GMBH & CO. KG			HS.125 SERIES 700B	Installation of Honeywell ART 2000 Weather Radar System anda Honeywell KMD-850 MFD.		Installation in accordance with Aero-Dienst Engineering Order ref. 215-HW, Rev IR, dated 06. Feb. 2006, or later approved revision.To be operated in accordance with Aero-Dienst Airplane Flight Manual Supplement ref AG566-071, Rev IR, dated10 April 2006, or later approved revision.	None.	19/04/2006	Active	10014386
EASA.A.S.01674	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	767-200	Replacement of Aft G4B Galley.		BBJ Design Services Modification BBJ632	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	27/06/2006	Active	10014388

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01676	FLYBE LIMITED		CAA UK RESPONSIBILITY	BAE ATP	Cargo Layout for class "E" compartment (LFD)		-FlyBe Modification DEC-E1000-FlyBe ATPF Flight Manual Supplement Number ATP 1 LFD, Issue 1		30/01/2006	Active	10014390
EASA.A.S.01677	AEROTEC & CONCEPT			M20E	BRNAV capacity with AP Steering		Modification No. 0205/ AérotecAirplane Flight Manual supplement BRNAV Garmin GNS 430 - edition 1 dated 12 october 2005	Modification limited to s/n 28R7931294The AFMS BRNAV Garmin 430 must be used with this modification	04/05/2006	Active	10014391
EASA.A.S.0168	SOGERMA SERVICES	REV. 2		A3IO-304, MSN 537 AND 586	Traffic Alert ahd Cbilisi6hAvoidance System, TCAS change 7 software andtwo ATC Mode Sinstallation in accordance with Modification Approval Sheet SOG 34-879Issue 2 dated 08 July2004			1 This STC is approved only for the product configuration as defined inthe approveddesign data referred to in the paragraph "Description" Compatibilitywith otheraircraft/ engine configuration shall be determined by the installerIhis certificate shall remain valid unless otherwise surrendered orrevoke...	08/09/2004	Active	10043103
EASA.A.S.01683	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH 1900D BEECH 1900C, AIRLINER BEECH 1900	Installation of Universal UNS-1K+		AFM Supplement Report 2005-35-8, Rev. C or later EASA approved revision	Instructions for Continued Airworthiness, Doc. No. 2005-35-10 Rev. B	31/08/2006	Active	10014393
EASA.A.S.01684	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH 1900D BEECH 1900	Installation of Universal TAWS and MFD 640		AFM Supplement Beechcraft 1900 and Series with Universal TAWSand MFD 640, Report 2005-36-8, Rev. B, or later approved revision		28/08/2006	Active	10014394
EASA.A.S.01689	LUFTHANSA TECHNIK AG			AIRBUS A321 AIRBUS A320 AIRBUS A319	Introduction of Link 2000+		Supplement Type Definition Document No. STDD23-05/08M, Issue 01, Rev. 00, dated 20 February 2007 or later approved revisionAirplane Flight Manual Supplement Doc. No. A-23-06/357-AFM, revision IR, dated 29 January 2007 or later approved revision	Certification Basis of the Change: CS 25 Amdt 02	26/02/2007	Active	10014395
EASA.A.S.01690	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BAE JETSTREAM 3100	Installation of Dual Mode S Transponders & Honeywell CAS 67A TCAS II.		DD/AA/397 AAE Supplement 4 issue 1 or later approved revision to Approved AFM Ref. HP4.11		04/01/2006	Active	10014396
EASA.A.S.01691	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	737	Introduction of Three Overhead Liferaft Stowages		Aerospace Design & Engineering Consultants Ltd ModificationSummary MOD-0023	none	06/04/2006	Active	10014397
EASA.A.S.01693	SOCIETE AIR FRANCE S.A.	REV. 1		BOEING 767	Cabin Reconfiguration from Eva Air to Aeroflot Standard		Air France Modification CAS-B767-05-007	FAA STC SA5950NM (Door 2 Aft Galley Installation) is not included in this approval.	17/07/2006	Active	10014399
EASA.A.S.01695	STEINBEIS GmbH & Co. KGFUER TECHNOLOGIETRANSFER			DG LS8-T	LS8-th Hydraulic extension systemExchange of the electric driven engine extension system to a hand-driven hydraulic system		Change of pages in the Flight and Maintenance Handbook	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/07/2006	Active	10014400
EASA.A.S.01696	JET AVIATION GmbH			LEARJET 31	Installation of Bluesky C-1000 SATCOM		Jet Aviation Modification 2004-7 Revision A dated November 14, 2005 or alter approved revision	--	03/08/2006	Active	10014401
EASA.A.S.01697	ATS INTERNATIONAL			BOEING 767-300 SERIES BOEING 767-200 SERIES	TCAS II Change 7 System Installation		ATS International Master Data List 0267-01-A-2103-R00 or later approved revision.ATS International AFM Supplement 0267-01-A-2301-R03 or later approved revision.		22/05/2006	Active	10014402

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.01699	LUFTHANSA TECHNIK AG			BOEING 737-500	Installation of new Recaro Aircraft Seating convertible andstandard seats and cabin refurbishment to PG-design on Lufthansa's Boeing B737-500 aircraft.		Certification Programm CP25-05/25M, issue 01, dated 09.03.2006Supplement Type Definition Document STDD25-05/25M Iss. 1,18.04.2006Compliance Record List CRL25-05/25M Iss. 1, 10.04.2006Applicant's Declaration of Compliance ADoC dated 20.04.2006	Certification Basis of the change: FAR25 as defined in FAA TCDS A16WE.	23/05/2006	Active	10014404
EASA.A.S.01701	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH A36	Title: GARMIN GNS 430/530 upgrade for GPS approachDescription: Upgrade of existing GNS 430/530 for GPS approach and installation of annunciator panel		Aircraft Flight Manual Supplement, Doc. 2031235-AM-01, issue 1 or later EASA approved issue		13/02/2006	Active	10014406
EASA.A.S.01702	RUAG AEROSPACE SERVICES GmbH			CESSNA 550 CITATION II	Honeywell EGPWS Mk VIII		Change Notice No: 170B-CN Rev. N/C or later approved RevisionAirplane Flight Manual Supplement 170B-AFMS Rev. N/C or later approved Revision	Certification Basis of the Change: FAR 25 as defined in TCDS A22CE;Rev. 58, additionally JAA Leaflet No. 12 (TAWS)	24/04/2006	Active	10014407
EASA.A.S.01706	SABENA TECHNICS BGC	REV 1		DC-9-83 (MD-83) DC-9-82 (MD-82)	Elementary and Enhanced Surveillance Installation		MDL 0269-01-A2103-R06AFMS 0269-01-A2301-R05		27/02/2007	Active	10014410
EASA.A.S.01711	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	CESSNA F182-Q	Design data and equipment installation in order to approve the aircraft for IFR.		Flight Manual Supplement TAL-BRNAV FMS-TAD 002/06 Issue 1	--	08/01/2007	Active	10014412
EASA.A.S.01712	FLYBE LIMITED		CAA UK RESPONSIBILITY	BAE ATP	Introduction of Class E Compartment Cargo Layout		FlyBe Modification Statement BE/MOD/E750FlyBe AFM Supplement ATP-AFM-01Aircraft Lodaing Manual Supplement ATP-LM-01Engineering Manual Supplement ATP-EMS-1	Restricted to Aircraft Serial Number 2042 & 2052	17/01/2006	Active	10014413
EASA.A.S.01713	TURNTIME TECHNOLOGIES AB			AIRBUS A321 AIRBUS A320 AIRBUS A319	Installation of Sliding Carpet Loading System in Airbus A319/320/321 in accordance with Telair International AB Master Document List (MDL)		1) Telair International AB document "Master Document List (MDL) No T-D090, revision A, dated December 14, 2005 or laterrevision (A321)2) Telair International AB document "Master Document List (MDL) No T-D065, revision A, dated April 4, 2004 or later revision (A319/320)	N/A	13/02/2006	Active	10014414
EASA.A.S.01714	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	FALCON 20 BASIC, D AND E SERIE	DC-0052 dtd. 7.6.06: Introduction of TAWS Display		see Design Change Statement DC-0052 dtd. 7.6.05:-AFM Supplement FRAJFMll09 dtd. 19.5.06-associated list of affected technical documents	This STC is approved only for the product configuration as defined inthe approved design datareferred to in the paragraph "Description". Compatibility with otheraircraft/ engineconfigurations shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orrevok...	09/06/2006	Active	10043104
EASA.A.S.01715	LUFTHANSA TECHNIK AG			AIRBUS A320	Installation of new B/E Aerospace convertible and standard seats and cabin refurbishment to PG-design on Lufthansa's A320 aircrafts		1. Certification Program CP25-05/21M, issue 02, dated 20.01.20062. Supplemental Type Definition Document STDD25-05/21M,issue 01 dated 07.02.20063. Compliance Record List CRL25-05/21M, issue 01 dated 07.02.20064. Applicant's Declaration ofCompliance dated 14.02.2006		17/02/2006	Active	10014415

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.0173	SOGERMA SERVICES	REV. 1		AIRBUS A340-642	Installation in upper class side facing Britax Malcom seatsequipped with the inflatable restraints, monuments, a bar and a chandelier according to MAS SOG-25-597 issue 4 (dated 02/07/04) and reference documents : Airplane Flight Manual A340-600 1.02.00 P 01. Supplementary Structural Repair Manual...				07/01/2008	Active	10014416
EASA.A.S.01739	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	SHORTS SD3-60	Introduction of ACAS II & Single Mode S Transponders with Elementary Surveillance.		STC Twenty One Modification S21.34-39-1014AFM Supplement S21.FMS-0015	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	13/03/2006	Active	10014418
EASA.A.S.01740	AIRBUS S.A.S.	REV. 1		A320 MODELS	SAT TV Tailwind 550 antenna installation in accordance withMAS SOG-53-1252 issue 2 dated 27/07/06		MPD Supplement MOD SOG-53-1252 dated Feb 01/06	1. The installation is compatible with the installation of a VH3 antenna between Fr 51 and Fr 52, and a Canadian Marconi Aero-H+ antenna betweeen Fr 58 and Fr 61 (separately or simultaneously).2. The installation requires both ACT 1 and 2 be installed on A320 (pre-mod) identical to MSN 2165).3. The...	30/06/2008	Active	10014419
EASA.A.S.01741	AERLYPER S.A.			FAIRCHILD SWEARINGEN SA 227-BC	Garmin GPS 155XL with antenna GA-56, Mid-Continent MD41-448Annunciation control Unit and copilot CDI Mid-Continent MD 40-09L installation for B-RNAV operation		Doc No AI03-081-01 "Plan de Certification" Edition 04Installation Instructions in accordance withDoc No AI03-081-00, "Lista de Documentos y Planos" Edition 05Doc No AI03-081-14, "Decripcion de la Instalacion" Edition 01Doc No AI03-081-15, "Boletin de Servicio" Edicion 02Doc No AI03-081-02, "ProcesoG...	The aircraft is approved for dual pilot B-RNAV operation, subject to the conditions, limitations and procedures contained in Doc NoAI03-081-03 "Flight Manual Supplement", Rev 03	17/01/2006	Active	10014420
EASA.A.S.01742	TRANSAIRCO S.A.		FOCA STC 23-15-001 ISS2	PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12	Aircell 3100 Iridium SATCOM Installation			This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	07/09/2006	Active	10014421
EASA.A.S.02469	A Y M AVIONICS, SL			PA-31-350 (CHIEFTAIN)	Verification of the B-RNAV Capability.Installation of GPS Modes Panel Annunciator.Installation of new XPDR Mode S Garmin GTX-330 and Encoder AK-350.		A&M Avionics PC No. 02/2006 Rev. 0, dated 30/11/2005.	In accordance with Supplement No. SMV 02/06 R0, to the original Flight Manual approved by FAA.SN 31-7952088	21/12/2007	Active	10014424
EASA.A.S.02470	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			208, 208B (208A NOT VALIDATED)	Mount assembly for external side loads for Cessna 208 models		AFM supplement AFS_M02700101_MBO_0322006Instructions for continued airworthiness ICA_M02700101_MBO_0322006		07/06/2006	Active	10014425
EASA.A.S.02474	SOGERMA SERVICES	REV 1		DC-9-21	Modification Janus Phase I: Cancellation of the restrictionof flights in icing conditionsNote: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.		Modification Approval Sheet (MAS), ref. SOG-00-092, issue 3and dated April 12, 2005Airplane Flight Manual Supplement, ref. BD/ 1251/01, issue 17, dated April 11, 2005	1. This STC is limited to the MSN 47308.	04/01/2008	Active	10014428

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02475	RUAG AEROSPACE SERVICES GmbH			CESSNA 550 CITATION II	ACAS II 5CAS67A) with Dual Mode S XPDR MST-67A-EHS		Change Notice No: 170A-CN Rev. N/C or later approved Revision Airplane Flight Manual Supplement 170-AAFMS Rev. N/C or later approved Revision	Certification Basis of the Change: FAR 25 as defined in TCDS A22CE; Rev. 58, additionally JAA Leaflet No. 8, Rev. 2 (ACAS II), JAA Leaflet No. 13, Rev. 1 (Mode-S ELS) and JAA NPA 20-12a (Mode-S EHS)	19/04/2006	Active	10014429
EASA.A.S.02477	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	DORNIER 288-202K	Operational Upgrade		FR Aviation Design Change DC-OOO 1 Issue 1 or later approved revision.FR Aviation AFM Supplement FRAH/FMII 04 Revision 0 or later approvedrevision.	This STC is approved only for the product configuration as defined inthe approved design datareferred to in the paragraph "Description". Compatibility with otheraircraft/ engineconfigurations shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orrevok...	24/01/2006	Active	10043105
EASA.A.S.02478	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	BEECH A36	Installation of Skywatch Traffic Avoidance		Phoenix Aviation Design Services Modification PADS_CP_1041Phoenix Aviation Design Services AFM Supplement PADS/ FMS/436/001 Revision 0 dated March 20 2006 or later approved revision		07/06/2006	Active	10014430
EASA.A.S.02480	MT-PROPELLER ENTWICKLUNG GmbH			PIPER PA-42-1000	Installation of propeller MTV-27-1-E-C-F-R(G)/CFRL250-103 (right),MTV-27-1-E-C-F-R(G)/CFR250-103 (left)		Airplane Flight Manual Supplement No. E-1410Installation Instructions E-1411Instructions for Continued Airworthiness E-1412	--	20/12/2006	Active	10014432
EASA.A.S.02481	DINAN AVIATION			PIPER PA-31T	Modification SIBA MD01_2006Replacement of one ATC mode C byMode S and replacement of an old DME with adding an ATC antenna on the top of frame		None	This STC is limited to: S/N 31T-7920094 F-GPBF	31/08/2006	Active	10014433
EASA.A.S.02483	A Y M AVIONICS, SL			404	Remove Weather Radar Bendix King RDS81. Install Weather Radar Bendix King DRD 2000 with MFD Avidyne EX 500. Reinvestigation of DualGNS530 Installation according to A&M Avionics BINº 017/2006 for B-RNAV Approval, Model: Cessna 404, S/N 404 0614		¿ Design Definition A&M Doc. DDI Nº 03/06 Rev.1 ¿ New Supplements to Aircraft Fligth Manual A&M Avionics Doc. SMV Nº 03/06 Rev.1 and A&M Avionics Doc. SMV Nº 04/06 Rev.1¿ Operating & Service Instructions: A&M Avionics Doc. BI Nº 24/05 Rev.0	1. The design changes to be approved are only applicableto Cessna 404 airplanes with Dual GNS530 Installation according to A&M Avionics BI Nº 017/2006, and EHSI SANDEL SN 3500previously installed and approved as Primary Navigation Display.2. Prior to installation of this modification the ins...	30/01/2009	Active	10014434
EASA.A.S.02484	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		CESSNA S550, (CITIATION S/II) CESSNA 560 (CITATION V) CESSNA 550 CITATION II CESSNA 500, CITATION	Sandel ST3400 TAWS Installation left hand and right hand		Engineering Order 2031680-EO-01 Issue 1 or later approved RevisionsAircraft Flight Manual Supplement 2031680-AM-01 A Issue 4 or later approved RevisionsAircraft Flight Manual Supplement 2031680-AM-01 B Issue 1 or later approved Revisions	Certifications Basis of the Change: CS 25, additionally JAALeaflet No. 12 (TAWS)	02/04/2006	Active	10014435
EASA.A.S.02485	DASSAULT FALCON SERVICE			A320-211/-212	DFS 2568 dtd. 21.Dec 05: DFS AFM Supplement F20 51 to DTM 589/ DTM590/DTM591		see Change approval sheet DFS 2568:- DFS AFM Supplement F20 51 to DTM 589/DTM590/DTM591 and- assosiated list of affected technical documents	1. This STC is approved only for the configuration as defined in Mod Sheet DFS 2568.2. Compatibility with other aircraft/ engine configurations shall be determined by the installer.3. This STC is approved only for the product configuration as defined in the approved design data referred to in the par...	26/01/2006	Active	10014436
EASA.A.S.02487	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BAE 146-200	Layout of Passenger Accomodation (LOPA) for 84, 93, 95 & 96		Bournemouth Aviation (Consultatnts) Ltd Modification BAC/146/066		19/04/2006	Active	10014437

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02488	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 737-400	Installation of 136 (16/120) PAX LOPA		Bournemouth Aviation (Consultans) Ltd Modification BAC/373/049		07/04/2006	Active	10014438
EASA.A.S.02491	MT-PROPELLER ENTWICKLUNG GmbH			CIRRUS SR22	Installation of 3-blade MTV-9-D/198-52 constant speed Propeller		E-1320, Rev. 1MT-Propeller AFM-S Doc. No E-1322, Original issue, approved 06. July 2006, or later EASA approved RevisionMT-Propeller Instructions for ContAW. Doc. No. E-1324, Original issue, or later approved Revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/07/2006	Active	10014441
EASA.A.S.02494	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BAE ATP	Introduction of Rockwell Collins ACAS II and Dual Mode S Transponder System		STC21 Change S21.34-23-1008STC21 AFM Supplement S21.FMS-ATP-0002 Issue 1 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	16/02/2006	Active	10014443
EASA.A.S.02495	SLINGSBY ADVANCED COMPOSITES LTD.	REV. 1	CAA UK RESPONSIBILITY	BEECH 76	Introduction of Bendix/King KCS 55A Compass, KX165 NAV/COM,KR87 ADF, King KN62A DME & KI229 Systems		Singsby Aviation Ltd Modification SAL/MOD/ BE76/01Singsby Aviation Ltd AFM Supplement Slingsby Beech 76-01 Issue 1 or later approved revision.Singsby Aviation Ltd AFM Supplement Slingsby Beech 76-02 Issue 1 or later approved revision.		20/06/2006	Active	10014444
EASA.A.S.02499	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CESSNA 550 CITATION II	Introduction of an AirCell Satellite Telephone System ST 3100 to the aircraft.This modification installs the handset into an arm rest on the rear starboard side of the aircraft. The Satellite Phone Transceiveris installed in the mid cabin drinks stowage on the port side of the aircraft. A circuit br...		Installation: Accomplishment Instruction, Serial No.: S21.ACC-0026, Iss. 1Aircraft Maintenance Manual, Wiring Diagram Manual, Illustrated Parts Catalogue, refer to STC Twenty One Ltd Supplemental Manual S21.TEC-0032.Drawing No. Title11-29-10004 Satcom Placards23-29-10002 Satcom Handse...	This design change should be embodied concurrently with or after the embodiment of STC Twenty One Limited minor design change S21.23-29-1000.	09/06/2006	Active	10014446
EASA.A.S.02500	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 767-200-300	Introduction of SSR Mode S Enhanced Surveillance System.		Master Document List S21.MDL-0049 AFM supplement S21.FMS-0028 Issue 1	Boeing 767-200/300 series.It is a condition of this STC that transponders of different manufacturers must not be intermixed, refer to STC 21 IPC supplement S21.TEC-0033 for further details.	12/10/2007	Active	10014447
EASA.A.S.02501	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-46-310P	Installation of GNS530, with GDC31 Roll Steering Converter		FMS ASR 2006-004-01 Rev. 1, Garmin GNS530FMS ASR 2006-004-02 Rev. 1, DAC GDC31		05/04/2006	Active	10014448
EASA.A.S.02502	LUFTHANSA TECHNIK AG			A320-200	A320 Pax Capacity Increase from 156 to 168 Pax		Supplement Type Definition Document STDD25-06/01M, issue 01dated 25.05.06Applicant's Declaration of Compliamce dated 26.05.2006		29/05/2006	Active	10014449

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02503	E A D AEROSPACE AIRWORTHINESS			B757	ELT antenna installation as provision only		Compliance Check List (reference 01060-EAS-C-CCL-01, Revision A) Certification Program (reference 01060-EAS-C-CPM-01, Revision A) Master Drawing List (reference 01060-EAS-C-MDL, Revision A) Maintenance Planning Document Supplement (reference 01060-EAS-C-MPD-02, Revision A)STC Application Letter (refere...	Maintenance Planning Document Supplement 01060-EAS-C-MPD-02, Revision A	10/03/2006	Active	10014450
EASA.A.S.02504	SOCIETE AIR FRANCE S.A.			BOEING 737-900 BOEING 737-800	KLM 737-800, -900 Recaro Seats Installation		- Certification Programme CP-B737-06-001 Rev2, March 28th 2006- AFSB B737-06-001-25-001 Rev 00, March 24th 2006-04-06	- Compatibility of this design change with other previouslyapproved modifications must be determined by the installer.- The installation is limited to the B 737-800, -900 listed in the CP-B737-06-001 Rev2, March 28th 2006.- As indicated in the doc. CP-B737-06-001 Rev2, March 28th 2006. (Paragraph 8...	11/05/2006	Active	10014451
EASA.A.S.02505	THIELERT AIRCRAFT ENGINES GmbH			CESSNA 172	Installation of Universal Fuel System			This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	07/02/2006	Active	10014452
EASA.A.S.02507	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	BOEING 747-428	Installation of Upper Deck Galley partnr 747AFA01GA00 into a B747-428 passenger to cargo conversion (747-400BCF) as defined in STC Definition Document DD 1022 d.d. 01-06-2006 or later EASA approved revisions.		- AIM Henshalls Component Maintenance Manual 25-36-76- AIM Henshalls Illustrated Parts List 25-36-76		03/05/2007	Active	10014453
EASA.A.S.02508	SOCIETE AIR FRANCE S.A.			BOEING 767-300	Cabin Reconfiguration		Air France Change Approval Sheet No EA33-B767-06-001 rev 0	--	26/06/2006	Active	10014454
EASA.A.S.02509	SCANDINAVIAN AVIONICS DESIGN ApS			BOMBARDIER SD-3-SHERPA BOMBARDIER SD-3-60-SHERPA	Collins TCAS 4000 with dual TDR-94D Transponder Installation		Engineering Order 2026479-EO-01 Issue 2, dated 19.05.2006 or later approved RevisionsAircraft Flight Manual Supplement 2026479-AM-01A Issue 1, dated January 2006 or later approvedRevisionsAircraft Flight Manual Supplement 2026479-AM-01B Issue 1, dated January 2006 or later approved Revisions	Certification Basis of the Change: CS-25, additionally JAA leaflet No. 8 Rev. 2 (ACASII), JAA Leaflet No. 13 Rev. 1 (Mode S ELS)	01/08/2006	Active	10014455
EASA.A.S.02510	SOCIETE AIR FRANCE S.A.			AIRBUS A330-343	Cabin Reconfiguration with the Installation of new B/C Seating Configuration as per Air France Change Approval Sheet n°CAS A330-05-012		- Type Design Document Ref. MF-A330-05-012- Supplements to Instructions for Continued Airworthiness and Airplane Flight Manual according to Modification Airworthiness Section of Doc. Ref. MF-A330-05-012- Air France SB A330-05-012-25-001- Air France SB A330-05-012-25-002		30/04/2007	Active	10014456
EASA.A.S.02511	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 525A CESSNA 525	Installation of EGPWS MARK VIII		AFM Supplement Report 2005-9-8, Rev. D, or later EASA approved revision	Maintenance Manual Supplement 2005-9-10- Rev. B	31/07/2006	Active	10014457

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02515	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 525A CESSNA 525	Installation of Skywatch HP		AFM Supplement Report 2005-10-8, Rev B, or later EASA approved revision	Maintenance Manual Supplement 2005-10-10 Rev B	28/07/2006	Active	10014458
EASA.A.S.02517	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	737-4Y0	Introduction of 8/150 Passenger Configuration and Associated Customisation		- Modification Summary: MOD-0026 Issue C dated 7th September 2006, or later approved revision- Modification Certification Plan: MCP-0026 Issue C dated 7th September 2006, or laterapproved revision.	Compatibility of this design change with other previously approved modifications must be determined by the installer.	20/10/2006	Active	10014459
EASA.A.S.02521	THOMSONFLY LTD.(FORMERLY BRITANNIA AIRWAYS LTD.)		CAA UK RESPONSIBILITY	BOEING 767-300	Introduction of STG Aerospace Photo-Luminescent Passenger Emergency Escape Path Lightning System		Thomsonfly Ltd MOD/ 767/1463 Issue 2 or later approved revision.STG Aerospace AFM Supplement M40-11 Revision A dated August 20 2002 or later approved revision.	Cabin & Exit Lightning levels must be measured for acceptability on each installation in accordance with Thomsonfley Technical Engineering Order TEO/ 767/1463 Issue 2 dated 26 April 2006 or later approved revision.	02/05/2006	Active	10014461
EASA.A.S.02522	ATS INTERNATIONAL	REV 1		A318/A319/A320/A321 ALL MODELS	Mode S Elementary and Enhanced surveillance		Master Data List (MDL) ref. 0264-01-A-2103 revision 05, dated June 19, 2006 of later EASA approved revisionAirplane Flight Manual Supplement (AFM-S) ref. 0264-01-A-2301 revision 04, dated June 19, 2006 of later EASA approved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	30/06/2006	Active	10014462
EASA.A.S.02524	SOCIETE AIR FRANCE S.A.			BOEING 777-200	Air France B777-200 "Ulysse" cabin modification with Contour (CAS B777-04-003) or BEA business class seats (CAS B777-05-015).		Air France Modification B777-04-003Air France service bulletinsB777-04-003-25-001 rev 0 dated February 14 2006B777-04-003-25-002 rev 0 dated February 14 2006B777-04-003-25-003 rev0 dated February 14 2006or later approved revisionsThe Air France Modification number B777-05-015Air France Service Bull...	Limited to Aircraft serial numbers as defined in Air Francedocument CAS B777-04-003 and CAS B777-05-015	03/11/2006	Active	10014463
EASA.A.S.02525	BINDER MOTORENBAU GmbH			ASH 25 E	Modification of outer wing panel with winglets and 27 m wingspan		ASH 25 E Technische Mitteilung Nr. 18/B1		02/03/2006	Active	10014464
EASA.A.S.02526	SOCIETE AIR FRANCE S.A.			AIRBUS A320-211	Photo-luminescent EEPM system installation		Change Approval Sheet (CAS), ref. A320-06-004 revision , dated May 24, 2006 or later EASA approved revisionAirplane Flight Manual Supplement (AFM-S), ref. MA.PM 017/06 CE revision0, dated February 3, 2006 or later EASA approved revision	This STC is limited to the A320 MSN's 211, 215 and 270	06/06/2006	Active	10014465
EASA.A.S.02527	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	BAE 125 SERIES 800B	To indroduce completion of the upgrade to the existing Terrain Awareness Warning System (TAWS) installation to include terrain display.		Raytheon Aircraft Service Modification SC0133JRaytheon (AFMsupp ref H.S. 1.15 Supplement No. 18	Applicable to Aircraft Serial 258208 only	02/05/2006	Active	10014466
EASA.A.S.02528	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	B757-200	Layout of Passenger Accommodation, C2C Seats with new audioIFE & Seat Covers.		Bournemouth Aviation (Consultants) BAC/757/005		20/03/2006	Active	10014467
EASA.A.S.02529	AIR TOURING LIMITED		CAA UK RESPONSIBILITY	441	Installation of Dual GTX330D, RDR2000, MX20, KN63 & KGP-560TAWS		Airtouring Modification AT_MOD_1085Airtouring AFM Supplement AT_FMS_1085-1	--	11/08/2006	Active	10014468

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02530	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA S550, (CITIATION S/II) CESSNA 560 (CITATION V) CESSNA 550 CITATION II CESSNA 500, CITATION	Installation of a Garmin GNS 530A and a Honeywell Marker Beacon KR21, for EU basic RNAV operations		System Description 2032044-DE Iss. 2,Drawing List 2032044-DL Iss. 2,MoC list 2032044,AFM Supplements 2032044-AM-A Iss. 3 and 2032044AM-B Iss. 2	None	13/06/2006	Active	10014469
EASA.A.S.02531	KUERZI AVIATION AG			LEARJET 60	Installation of SSFDR and MFDAUInstallation of a Honeywell Solide State Flight Data Recorder and Teledyne Mini Data Acquisition Unit in Learjet Model 60		Master Document List No. MDL-200514764.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	11/12/2006	Active	10014470
EASA.A.S.02532	BINDER MOTORENBAU GmbH			ASW 22 BLE	Binder Motorenbau Technische Mitteilung ASW 22 BLE B2Changes in engine installation:- Different type of spindle drive- Installation of a primer ball- CFRP gear mount		Binder Motorenbau Technische Mitteilung ASW 22 BLE B2Drawings and Manual pages according to Tech. Note.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	12/04/2006	Active	10014471
EASA.A.S.02533	LUFTHANSA TECHNIK AG	REV 1		AIRBUS A340-300	Installation of CAIR System in A340-300		- Supplemental Type Definition Document, Ref. STDD21-05/01M, Issue 2 dated 18/08/2006- Instructions for Continued Airworthiness, Ref. ICA-21-0150, Rev. 01 dated 01/08/2006		18/08/2006	Active	10014472
EASA.A.S.02534	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 757-200	Layout of Passenger Accommodation - 92 Business & 8 Economy/Crew		Bournmouth Aviation (Consultants) BAC/757/006		20/03/2006	Active	10014473
EASA.A.S.02536	MOTORFLUG BADEN-BADEN GmbH	REV. 1		F27 MARK 500	Change of WXR to RDR 2000 Radar		Data package containing the following documents, and additional supporting data:1. F27-12412302-0103 Rev. 0 Master Document list2. F27-12412302-0101 Rev. 0 Compliance Program3. F27-12412302-0102 Compliance Report/ Checklist4. F27-12412302-0301 Rev. 0 Structural Substantiation Report5.6...		04/08/2006	Active	10014474
EASA.A.S.02536	MOTORFLUG BADEN-BADEN GmbH			F27 MARK 500	Change ofWXR to RDR 2000 Radar		Data package containing the following documents:I.Fokker Services SB F27/28-70: Fuel - Introduction of Fuel ALis andCDCCLs for the F27Mk200/300/400/500/600/700.2.Fokker Services Report SE-671: Fokker 50/60 Fuel ALis and CDCCLs.These reports are based on the fuel tank safety review performed by Fokke...	This STC is approved only for the product configuration as defined inthe approved design datareferred to in the paragraph "Description". Compatibility with otheraircraft/ engineconfigurations shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orrevok...	04/08/2006	Active	10043107
EASA.A.S.02537	AERODISA S.L.			MYSTÈRE-FALCON 20GF	AED2006-01M: TCAS II Installation for Falcon 20.		• Master Data List AED2006-01M_MDL Rev.5 dtd. 26.5.07 orlater EASA approved revision.• FM Supplement AED2006-01M_D03 Rev.2 dtd. 9.5.07 or later EASA approved revision.	1. See FM Supplement AED2006-01M_D03 Section I: LIMITATIONS.2. Certification basis CS 25 Orig issue.3. TGL 8 Rev.2 "ACAS II" complied with.4. TGL 13 Rev. 1 "Elementary Surveillance" complied with.5. Prior to installation of this modification the installer must determine that the interr...	18/07/2007	Active	10014475

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02538	SOGERMA SERVICES	REV 1		AIRBUS A320-211	Cabin modification from 155 to 167 Y/ CNote: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.		Modification Approval Sheet (MAS) ref. SOG-25-1250 issue 1,dated April 14, 2006 or later EASA approved revision	1. This STC is limited to the A320 MSN 615.	04/01/2008	Active	10014476
EASA.A.S.02539	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BAE 146	Introduction of T2 CAS Collision Avoidance & Terrain Awareness System		STC Twenty One Modification S21.34-25-1017STC Twenty One AFM Supplement S21.FMS-0016 Issue 1 or later approved revision	-	22/05/2006	Active	10014477
EASA.A.S.02540	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	CESSNA 441 SERIES	Installation of Two L Band Antennae		Bournemouth Aviation (Consultants) Definition Document ref J379/DD/01 Issue 1 dated March 08 2006	Installation of Aircraft Registered within EASA Member State only	17/05/2006	Active	10014478
EASA.A.S.02542	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	BOEING 767-300	Installation of Galley F4 Part Number 7673FCF4GA00		AIM Aviation (Henshalls) Change Number HEN 1035	Restricted to Aircraft Serial Number 26063 & 26064	29/09/2006	Active	10014479
EASA.A.S.02545	KUERZI AVIATION AG			CESSNA 340A	Avionic Retrofit		Master Document/Drawing List, Doc No. MDL-200514568 Rev. B,dated 18.04.2006AFMS, Doc No. FMS-200514568, Original, dated 06.03.2006	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/04/2006	Active	10014482
EASA.A.S.02547	CTT SYSTEMS AB	REV. 2	CAA NL STC SA0009NL	BOEING 767-300	Replacement of Zonal Dryer related to EASA AD 2006-0140-E.The above reference EASA AD required the de-activation of Zonal Drying Systems installed via CAA NL STC SA 0009 NL due tothe potential for combustion of contaminants in the dryer unit. A new dryer unit has been developed which removes this c...		SB 3000-002-01-AD Initial / SB 3000-000-21-07-AD InitialEASA AD 2006-0140-E or later approved revisionsNote: This revision reflects an amendment to the installation instructions and supersedes STC EASA.A.S.02547Revision 1.	Instruction for the installationInstallation instructions II767-2 and II767B-2, latest issue.KLM MO 21-0476 and Martinair MO 76730MP-003.Instructions for operationNo specific Airplane Flight Manual Supplement is neededPrior to installationof this modification the installer must determine that the i...	14/04/2009	Active	10014485
EASA.A.S.02548	CESKA LETECKA SERVISNI A.S.			LETECKE ZAVODY L 200 D	Avionics upgrade in accordance with the document no;CLS-06-L200-AC 129, dated 23/06/2006		L 200 D Flight Manual Supplemetn, No Do-L200D-1011.1, datedJune 2006	S/N 171206	28/07/2006	Active	10014486
EASA.A.S.02549	PREMIAIR AIRCRAFT ENGINEERING		CAA UK RESPONSIBILITY	BEECH 390	Satellite Telephone Installation		Premiair Aircraft Engineering Modification 06-001		11/05/2006	Active	10014487
EASA.A.S.02552	BINDER MOTORENBAU GmbH			ASH 25	Modification of outer wing panel with winglets and 27 m wingspan		ASH 25 Technische Mitteilung Nr. 17/B1		03/02/2006	Active	10014490
EASA.A.S.02553	MT-PROPELLER ENTWICKLUNG GmbH			PIPER PA-34-220T PIPER PA-34-200T	Installation of Propeller MTV-12-D-C-F/ CF(L)/188-53		Airplane Flight Manual Supplement No E-1274Installation Instructions E-1275Instructions for Continued Airworthiness E-1277		13/03/2006	Active	10014491
EASA.A.S.02554	MT-PROPELLER ENTWICKLUNG GmbH			BEECH B60 BEECH A60 BEECH 60	Installation of 4-blade MTV-14-B-C-F/ CF188-53a full fathering constant speed Propellers		E-1332MT-Propeller AFM-S Doc. No E-1358, Original issue, approved 06. July 2006, or later EASA approved RevisionMT-Propeller Instructions for ContAW. Doc. No. E-1360, Original issue, or later approved Revision	Applicable toDuke 60 and A60 S/N P-3 thru P-597 with Lycoming TIO-541-E1C4 engineDuke B60 S/N P-247 and upDuke B60 S/N P-247 thru P-597 with LBA STC 0662/2040 and 0666/2040all equipped with “System Gomolzig” Silencer B60-606500	10/07/2006	Active	10014492
EASA.A.S.02555	MT-PROPELLER ENTWICKLUNG GmbH			DIAMOND H-36 DIMONA	Installation of 2-blade MTV-1-A/L 160-03 constant speed propeller		Umrüst- und Wartungsanweisung E-1433, including Anhang zum Flughandbuch E-1432	For all serial numbers.	12/12/2006	Active	10014493

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02556	LUFTHANSA TECHNIK AG			BOMBARDIER CL-600-2B19	CL-600-2B19 - Cabin Completion - 16 PAX		Supplemental Type Definition Document STDD00-06/06M, Issue 01, dated March 27, 2007 or later approved revisionsAeroplane Flight Manual Supplement A-00-06/461-AFM, Issue 01, dated January 05, 2007 or later approved revisionsInstructions forContinued Airworthiness A-00-05/9876, Issue 01, dated MarchA...	1. Certification Basis of the Change: JAR-25 Change 13, addtionally: CRI F-01, Executive Power System (Guidance Material)CRI D-01, Side Faching Divans (Deviation)CRI D-04, Door between passenger compartments with integrated blocking functionality (Deviation)CRI D-05, Isolated Compartment (Special Co...	29/03/2007	Active	10014494
EASA.A.S.02559	SCANDINAVIAN AVIONICS DESIGN ApS			DORNIER DO 228-212 DORNIER DO 228-201 DORNIER DO 228-200 DORNIER DO 228-101 DORNIER DO 228-100	Sandel ST3400 TAWS installationInstallation of Class A TAWS/ RMI Indicator in the right hand instrument panel with a remote Annunciator and Switching unit on the left hand instrument panel. Single 3" indicator is used to show compliance		AFM Supplements No. 2032096-AM-A and AM-B, Issue 1	--	22/06/2006	Active	10014496
EASA.A.S.02560	SCANDINAVIAN AVIONICS DESIGN ApS			DORNIER DO 228-212 DORNIER DO 228-201 DORNIER DO 228-200 DORNIER DO 228-101 DORNIER DO 228-100	Installation of Honeywell CAS 67A ACAS II System incl. DualMode S XPDR		EASA approved:AFM Supplemetn Doc. 2032095-AM-A, Issue 2AFM Supplemetn Doc. 2032095-AM-B, Issue 2AFM supplemetn Doc. 2032095-AM-C, Issue 1AFM Supplement Doc. 2032095-AM-D, Issue 1or later EASA approved issues		12/06/2006	Active	10014497
EASA.A.S.02561	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BAE ATP	Installation of No. 2 ECS Pack		Tenencia Modification TEN 460EASA approved Tenencia AFM Supplement 2 Issue 1 or later approved revision.		23/10/2006	Active	10014498
EASA.A.S.02568	SOCIETE AIR FRANCE S.A.			A320	Cabin Reconfiguration in bi-classes on LAN A320		AFSB A320-06-006-25-001 Rev.00MF A320-06-006 Rev.00 or later approved revision	1. Limited to installation on MSN 1304, 1332, 1351 and 1355.2. Compatibility of this design change with other previously approved modifications must be determined by the installer.	30/10/2006	Active	10014501
EASA.A.S.02569	EADS SOGERMA			DC-9-21	JANUS Phase II modification		Master drawing list, ref. MDL 01-S67, issue B, dated March 4, 2005Airplane Flight Manual Supplement, ref. DIITINRJ4084/05, issue 2, datedApril 7, 2005	Eddy current inspections ref. MMSOS-537210 and MM808-53711Oas definedIn theMaintenance Schedule Supplement ref. MS 01-867 issue A, dated February10,2005.This STC is limited to the DC-9 MSN 47308.This STC is approved only for the product configuration as defined inthe approved design datareferred to...	14/12/2006	Active	10043109
EASA.A.S.02570	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	BEECH 200	Mode S Transponder Installation.		Form 1 Modification Statement HL/MOD/706 Issue 4.AFM Supplement AFMS706001 Issue 1.	Beech 200 Series. As per AFMS706001 Issue 1	06/02/2008	Active	10014502
EASA.A.S.02573	SABENA TECHNICS BGC			A300 B4 MODELS A300 B2 MODELS	MK7 EGPWS Installation on A300 B2-B4Config 1: EGPWS with Dual FPI-910Config 2: EGPWS with Dual PPI-4BConfig 3: EGPWS with Dual PPI-4B and reactive Windshear		- Config 1: Master Data List n° 0121-01-A-2103-R06Aircraft Flight Manual Supplement ref. 0121-01-A-2301-R05 or later EASA approved revision- Config 2: Master Data List n° 0121-02-A-2103-R02Aircraft Flight Manual Supplement ref. 0121-02-A-2301-R01 or later EASA approved revision- Config 3: Master Dat...	Instructions for Continued Airworthiness are described in the Airworthiness Data Sheet Supplement ADSS 0121-01 - A-2203-R05 or later EASA approved revision.	03/01/2006	Active	10014503

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02574	LUFTHANSA TECHNIK AG			BOEING 747	Installation of an ATC Mode S - Enhanced Surveillance Upgrade in Boeing 747 series aircraft		The modification is described in Supplemental Type Definition Document Navigation ATC Mode S EHS Upgrade, Lufthansa Technik Document STDD34-06/02M, issue 01, Rev. 00Data package containing the following documents, and additional supportingdata:1. Supplemental Type Definition Document Navigatione...	EASA approved Airplane Flight Manual Supplement, Lufthansa Technik Document A-34-06/135-AFM, Rev IR or later EASA approved revisionis required part of this STC	04/08/2006	Active	10014504
EASA.A.S.02576	SOCATA			TBM 700	STC 34.001.06/Gamin GNS530 TAWS.		Garmin Document 190-00181-00 Rev. EFlight Test Report TBM-00-REV-188/11 December 2007Supplement to FM ref. STC 34-001-06Certification Report.	TBM 700 equipped Garmin GNS 530 only s/n to 433 excepted 269.	30/01/2008	Active	10014506
EASA.A.S.02583	LUFTHANSA TECHNIK AG			AIRBUS A310-300 AIRBUS A300-600	Installation of a new Stretcher for Kuwait Airways.		Supplemental Type Definition Document STDD25-06/06M, Issue 1, Revision 1, dated 19 September 2007,(or any later approved Revision of this document)		15/11/2007	Active	10014509
EASA.A.S.02585	LUFTHANSA TECHNIK AG			AIRBUS A320	Installation of a new Stretcher for Kuwait Airways		¿ Supplemental Type Definition Document, ref. Doc. No. STDD25-06/07M, Issue 1, dated 28.02.08 (*) ¿ LHT Engineering Bulletin ref. Doc. No. A320-EB25-1227, Rev. IR, dated 02.06.2007 (*) or later revisions of the above referenced documents		28/02/2008	Active	10014510
EASA.A.S.02586	LUFTHANSA TECHNIK AG			BOEING 777-200 SERIES	Installation of a stretcher in the passenger compartment for Kuwait Airways		LHT STC Definition Document - STDD25-06/10M issue 01 rev 01dated 19 September 2007, or later approved issue.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	06/11/2007	Active	10014511
EASA.A.S.02587	LUFTHANSA TECHNIK AG			BOEING 747-400	Installation of a new stretcher for Kuwait Airlines B747-400 in accordance with Supplemental Type Definition Document STDD25-06 09MIss. 01, Rev. 01 or later EASA approved revision.		Supplemental Type Definition Document for B747-400 Stretcher installation KAC STDD25-06_09M Iss. 1, Rev. 1*LHT Engineering Bulletin for the Design, Engineering and Installation ofStretcher for Kuwait Airways B747-EB25-1230 Rev. 1*¨*or later approved		09/11/2007	Active	10014512
EASA.A.S.02588	LUFTHANSA TECHNIK AG			AIRBUS A340-300	Installation of a new Stretcher for Kuwait Airways		- Supplemental Type Definition Document, Ref. STDD25-06/08M, Issue 1, Rev. 01 dated 19 September 2007*- LHT Engineering Bulletin, Ref. A340-EB25-1228, Rev. 01 dated 18 September 2007**or later approved revisions of the above referenced documents	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	10/10/2007	Active	10014513
EASA.A.S.02589	TENENCIA Ltd.		CAA UK RESPONSIBILITY	LOCKHEED 188	Installation of Mode S Transponders for Enhanced Surveillance		Tenencia Modification TEN462Tenencia AFM Supplement 12 Issue 1 dated May 2006 or later approved revision	None	11/05/2006	Active	10014514

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02590	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	B200	T AS620 Traffic Advisory System		FR Aviation Modification DC-0066FR Aviation AFM Supplement FRAH/FMIIIO	This STC is approved only for the product configuration as defined inthe approved design datareferred to in the paragraph "Description". Compatibility with otheraircraft/ engineconfigurations shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orrevok...	28/07/2006	Active	10043110
EASA.A.S.02591	AERODATA AG			B300	Installation of Aerodata Flight Inspection System AD-AFIS-0220.		Installation in accordance with Master Document List MDL-A/C-110 Rev 1 or later revisions.Operation in accordance with Flight Manual Supplement AFM-082 Rev 0, or later approved revisionsInstructions for Continued Airworthiness AMM-816, Rev0, or later approved revisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	31/10/2006	Active	10014515
EASA.A.S.02592	AERODATA AG		LBA STC SA 1320	B200	Installation of Normarc Flight Inspection System NM3625B.NOTE: this STC supersedes existing LBA STC SA 1320		Installation in accordance with Master Document Listref MDL-A/C-059 Rev 4 or later approved revisions.Operation in accordance with Flight Manual Supplementref FMS-056 Rev 1, or later approved revisions.Instructions for Continued Airworthinessref HB-A/C-676, Rev 3, or later approved revisions.	None	07/09/2006	Active	10014516
EASA.A.S.02593	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	DFS 5625A dtd. 4.Mai 2006: Equipment installation with 220Vinverter		see Change approval sheet DFS 5625A and associated list of affected technical documents		05/05/2006	Active	10014517
EASA.A.S.02596	DAO AVIATION A/S			PA-46-310T, PA-46-350P	Avionics upgrade with following equipment (DFE-DO-0075-EPL-01 Equipment and Parts List.(Rev. 1)1 GMA 347 Audiopanel Garmin 1 GNS 530 COM/ NAV/ GPS Garmin 1 GNS 430 COM/ NAV/ GPS Garmin GarminCDI		DFE work order package DFE-DO-0075 and Installation Manualsaccording to Reference Document list, DFE-DO-75-ECO-01 page1 and 2.Approved Flight Manual Supplements:DFE-DO-0075-AFMS-430 REV.IR. DFE-DO-0075-AFMS-530 REV.IR. DFE...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	13/07/2006	Active	10014518
EASA.A.S.02601	BBJ DESIGN SERVICES LIMITED	REV. 1	CAA UK RESPONSIBILITY	767-300ER	Installation of a MAS2000E in Flight Entertainment System on Austrian Airlines B767-300ER aircraft		BBJ Design Services Modification Reference BBJ705NO280-D70:Instructions for Continued Airworthiness NO280-D71: Maintenance Manual Supplement	--	02/02/2007	Active	10014520
EASA.A.S.02603	LUFTHANSA TECHNIK AG	REV 1		AIRBUS A300-600	A300-600 Cabin Reconfiguration from Current Continental Version to Intercontinental Layout		Compliance Record List CRL25-06/13M, Issue 2 dated 30 May 2006Supplemental Type Definition Document STDD25-06/13M, Issue 1 dated 6 June 2006	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	22/06/2006	Active	10014521

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02605	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	AIRBUS A310 SERIES	Installation of Honeywell MK V EGPWS.This supplemental TypeCertificate installs a Terrain Awareness Warning System.		Master Document List, ref. S21.MDL-109 Issue 1, dated 31 August 2006 (or later approved revisions of this document are acceptable).Aircraft Flight Manual Supplement, ref. S21.FMS-0017 Issue 1, dated 12 November 2007		28/11/2007	Active	10014522
EASA.A.S.02606	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 727 SERIES	Introduction of Emergency Locator Transmitter		STC21 Modification S21.25-12-1055		15/06/2006	Active	10014523
EASA.A.S.02607	SOCATA			TB 200	Validation of definition specificities of TB200 S/N 1633 aircraft, compared to TB200 GT certified aircraft definition		TB200 S/N 1633 specific supplement to basic TB200 Pilot Operating Handbook	STC 53.001.06 applicable to TB200 s/n 1633 only	20/07/2006	Active	10014524
EASA.A.S.02610	AEROCONSEIL			BOEING 757	Mode S Elementary & Enhanced Surveillance System Installation		ATS International Master Data List 0249-01-A-2103-R00 datedMay 16 2006 or later approved revision.ATS International AFM Supplement ref 0249-01-A-2301-R00 dated May 16 2006 or later approved revision.		01/06/2006	Active	10014525
EASA.A.S.02611	JET AVIATION AG, BASEL			B727-200	ADI/ HIS & FMS upgrade by:removing both existing 329B-8x ADI 329Bremoving both existing 331A-9G HISremoving both LTN-92CDUremoving both ALI 55B Radio Altimeter Indicatorsinstalling two new 5ATI E-ADI, p/n 195000-21installing two new ATI E-HIS, p/n 195000-21installing two new EFI Control Panel, p/ni...		Jet Aviation Declaration of Compliance for the project BACBA008.Master Data List, Doc. No. BACBA008-002, latest approved revision.AFMS for the 5-ATI EFI, Doc. No. BACBA008-201-01,Rev. B or latest approved revision.AFMS for the CMC-900 FMS, Doc. No. BACBA008-201-02, Rev. C or latest approved revisio...	Reg.: A9C-BA, S/N 21824. Valid for this serial number only.	04/09/2007	Active	10014526
EASA.A.S.02614	DASSAULT FALCON SERVICE			FALCON 10	DFS 1274 dtd 5.5.06: Mode S Transponder Enhanced Surveillance		see Change approval sheet DFS 1274-AFM Supp F10 DFS 35 toDTM 721(A) with DFS 1274 incorp "Mode S Transponder Enhanced Surveillance"- Wiring Diagram DFS10 600 34-56-01XX, DFS10 600 34-56-11XX (Optional), DFS10 600 34-42-03XX, DFS10 600 34-16-01XXand associated list of affected technical documents	Applicable to Falcon 10 with DFS 1269B applied previously or simultaneously	05/05/2006	Active	10014529
EASA.A.S.02615	E.I.S.A.			CESSNA 404	Installation of a video under Cessna 404		EISA AFM-S Doc. No S109, Revision 1, dated 13. June 2006, or later EASA approved RevisionEISA STC Type design definition EASA 00 STDD S109 Revision 1 or later EASA approved Revision	Applicable to Cessna 404	04/10/2006	Orphaned	10014530
EASA.A.S.02617	SOCIETE AIR FRANCE S.A.			BOEING 737-500 BOEING 737-300	ATC Mode S-Enhanced Surveillance-Provision and Activation on Boeing 737-300/-50 in accordance with the Modification File MF-B737-06-004, Rev 00, dated 11 October 2006.		- Modification File MF-B737-06-004, Rev 00, dated 11 October 2006.- AFMS-B737-06-004-001 First Issue dated 3 May 2006, or later approved revision- AFMS-B737-06-004-002 First Issuedated 9 May 2006 , or later approved revision- ICA-B737-06-004 Rev 01, or later approved revision.	1. Limited to installation on Boeing 737-300/-500.2. Compatibility of this design change with other previously approvedmodifications must be determined by the installer.	23/10/2006	Active	10014531

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02618	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOMBARDIER DHC-8-100 SERIES	ACS Change 7 Upgrade & Elementary Surveillance Upgrade		Bournemouth Aviation (Consultants) Ltd BAC/ DHC8/006Bournemouth Aviaiton (Consultants) Ltd AFM Supplement FMS/ 397/35 Issue 1 dated 15 June 206 or later approved revisions	--	04/08/2006	Active	10014532
EASA.A.S.02620	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOMBARDIER DHC-8-100 SERIES	Installation of HF System		Bournemouth Aviation (Consultans) Ltd BAC? DHC8/004	--	04/08/2006	Active	10014533
EASA.A.S.02621	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.	REV 1	CAA UK RESPONSIBILITY	BOMBARDIER DHC-8-103 BOMBARDIER DHC-8-102	Installation of Dual UNS-1E Flight Management System.Note: Rev.1 to STC EASA.A.S.02621 adds RNP Approach Capability.		- Bournemouth Aviation (Consultants) Ltd Doc. BAC/DHC8/001, Iss. 6 or later approved revision.- Bournemouth Aviation (Consultants) Ltd Flight Manual Supplement FMS/ 397/33,Iss. 4 or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.2. Prior to installation of this modification the installer...	26/01/2009	Active	10014534
EASA.A.S.02622	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOMBARDIER DHC-8-100 SERIES	Installation of Aircell ST3100 Satellite Telephone System (SATCOM)		Bournemouth Aviation (Consultants) Ltd BAC/ DHC8/003Bournemouth Aviation (Consultants) Ltd AFM Supplement FMS/ 397/36 Issue 1 dated July 6, 2006 or later approved revision	--	04/08/2006	Active	10014535
EASA.A.S.02623	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOMBARDIER DHC-8-100 SERIES	Installation of Universal Terrain Awareness Warning System (TAWS)		Bournemouth Aviaiton (Consultants) Ltd BAC/ DHC8/003Bournemouth Avaition (Consultants) Ltd AFM Supplemtn FMS/ 397/34 Issue 1 dated June 15, 2006 or later approved revision	--	04/08/2006	Active	10014536
EASA.A.S.02626	SCANDINAVIAN AVIONICS DESIGN ApS			MITSUBISHI MU-300	Universal TAWS Installation incl. MFD-640		Engineering Order 20031553-EO-01 Issue 2, dated 20.04.2006 or later approved RevisionsAircraft Flight Manual Supplement2031553-AM-01A Issue 2, dated April 2006 or later approved RevisionsAircraft Flight Manual Supplement 2031553-AM-01B Issue 2, dated April 2006 or later approved Revisions	Certification Basis of the Change: CS 25 Amendment 1, additionally JAA Leaflet No. 12 (TAWS)	27/06/2006	Active	10014539
EASA.A.S.02627	SCANDINAVIAN AVIONICS DESIGN ApS			MITSUBISHI MU-300	Installation of Universal UNS-1L(-1K+) FMS		Engineering Order 20031552-EO-01 Issue 2, dated 20.04.2006 or later approved RevisionsAircraft Flight Manual Supplement2031552-AM-01 Issue 2, dated April 2006 or later approved Revisions	Certification Basis of the Change: CS 25 Amendment 1, additionally JAA Leaflet No. 10 (Precision RNAV), AMC 20-4 (BasicRNAV), AMC 20-5 (GPS)	27/06/2006	Active	10014540
EASA.A.S.02628	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			LEARJET 35A LEARJET 35	Installation of Universal UNS 1L/K+		Engineering Order, Report 2006-3, Revision B dated 10 July,2006 or later approved Revisions,Airplane Flight Manual Supplement, Report 2006-3-8, Revision B dated 10 July, 2006 or later approved Revisions	Certification Basis of the change: FAR Part 25, additionally EASA AMC 20-4 (B-RNAV), EASA AMC 20-5 (GPS), JAA TGL No. 10 Rev. 1 (P-RNAV)	11/09/2006	Active	10014541
EASA.A.S.02632	GULFSTREAM AEROSPACE Ltd.		CAA UK RESPONSIBILITY	GULFSTREAM GV-SP	Certification of FAA Field Approved Modifications to enablethe issue of a Certificate of Airworthiness on the Swiss register. Aircraft Serial No 5040		In accordance with Gulfstream Aerospace Limited Change Leaflet for Change No GAeL 06/02 Issue 2	Aircraft Serial No 5040 Only	24/08/2006	Active	10014545

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02634	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-31P	Installation of COM/NAV/GS/GPS Garmin GNS530/GNS430 (dual installation)		EASA Approved Flight Manual Supplement ASR 2006-025-00 Revision A or later EASA approved revision		11/09/2006	Active	10014546
EASA.A.S.02637	AERO-DIENST GMBH & CO. KG			55	Cockpit Voice Recorder CVR-30B Installation (Universal Avionics System Corp.)		Engineering Order, 220-LR, Rev. IR, or later approved revisionAFM Supplement, AG581-071, Rev. IR, or later approved revision		24/07/2006	Active	10014547
EASA.A.S.02638	AERO-DIENST GMBH & CO. KG			55	Solide State Flight Data Recorder F1000 Installation (L3-AR)		Engineering Order, EO 219-LR, Rev. IR, or later approved revisionAFM Supplement AG583-071, Rev. IR, or later approved revision		24/07/2006	Active	10014548
EASA.A.S.02639	MOTORFLUG BADEN-BADEN GmbH			F27 MARK 500	Installation of Smoke Detection System		Master Document List MDL F27-12412308-0109 Revision 1, dated 23.06.2006Airplane Flight Manual Supplement F27-12412308-0601Declaration of Compliance of Aerotechnic GmbH EASA. 21J.099, dated 11.08.2006	FAR-25 Amdt. 119	14/08/2006	Active	10014549
EASA.A.S.02643	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 551, CITIATIONII CESSNA 501, CITIATION	Installation of Dual Garmin GNS 430A/ 530A and 3rd COMM in Cessna Citation I model 501 and Citation II model 551.		• Engineering Order 2027496-EO-01, issue 3, dated 30 May2007, or later approved revision.• AFM Supplement Doc. 2027496-01A, issue 2, dated 31 May 2007, or later approved revision.	1. Certification basis of the Change CS-23, additionally:2. AMC 20-4 (Basic RNAV), AMC 20-5 (GPS), AMC 25-11 (Electronic Display Systems) and JAA TGL 7, rev.1 (VHF Com 8.33 KHz).3. Prior to installation of this modification the installer must determine that the interrelationship between thi...	20/06/2007	Active	10014550
EASA.A.S.02644	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA S550 (CITATION II) CESSNA 550 CITATION II CESSNA 500, CITATION	Installation of Dual Garmin GNS 430A/ 530A and 3rd COMM in Cessna Citation I model 500 and Citation II model 550, S550.		• Engineering Order 2027496-EO-01, issue 3, dated 30 May2007, or later approved revision.• AFM Supplement Doc. 2027496-01A, issue 2, dated 31 May 2007, or later approved revision.	1. Certification Basis of the Change CS-25 Amdt. 2, additionally:2. AMC 20-4 (Basic RNAV), AMC 20-5 (GPS), AMC 25-11 (Electronic Display Systems) and JAA TGL 7, rev.1 (VHF Com 8.33 KHz)3. Prior to installation of this modificationthe installer must determine that the interrelationship betw...	20/06/2007	Active	10014551
EASA.A.S.02651	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			PIPER PA-46-350P PIPER PA-46-310P	Installation of Garmin GTX 330 or Garmin GTX 330D Transponder		EASA-approved Airplane Flight Manual Supplement,,Report 2004-21-8, Rev.B, dated 01.12.2004, or later EASA-approved editionMaintenance Manual Supplement, Report 2004-21-10, Rev. B		27/04/2006	Active	10014553
EASA.A.S.02652	AEROCONDOR TRANSPORTES AEREOS SGPS			DORNIER 228-202	Installation of Honeywell TCAS system CAS-67A with Diversity Mode S Transponder MST-67A, Control Unit PS-550 and two E-VSI IVA-81A		EASA Approved Aircraft Flight Manual Supplement No. ATA.021J.081.0502.01, Issue 02, dated November 14, 2006, or later approved revisions		21/11/2006	Active	10014554
EASA.A.S.02653	JET AVIATION AG, BASEL			BAE 146/AVRO 146 SERIES	Cabin Interior Outfitting:Introducing a custom passenger cabin with individual interior and seating, VIP lavatory, In-flight Entertainment / Cabin ManagementSystem w/ tail and cockpit camera, Iridium Satcom system, cabin power-outlet system and oxygen overboard discharge / medical power-supply syst...		• Master Data List BRJE1267-001• Flight Manual Supplement BRJE1267-201-01• Instructions for Continued Airworthiness BRJE1267-150-01	1. Reg.: A6-RJK S/N: E1267.2. For limitations refer to Flight Manual Supplement BRJE1267-201-01.	12/04/2007	Active	10014555

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02654	SCANDINAVIAN AVIONICS DESIGN ApS			SD3-60 SHERPA SD3-30, SD3-60, SD3 SHERPA	Honeywell EGPWS MK VI Installation		Engineering Order 2033234-EO, Issue 2, dated 16 May 2006 orlater approved revisionAFRM Supplement Doc. 2033234-AM, issue1, May 2006 or later approved revision	Certification Basis of the Change CS 25, additionally JAA TGL 12 (TAWS)	06/06/2006	Active	10014556
EASA.A.S.02658	SCANDINAVIAN AVIONICS DESIGN ApS			SD3-60 SHERPA SD3-30, 3-60, 3-SHERPA, 360 SH	Trimble TNL-2101 I/O Aproach + GPS System Installation		Engineering Order 2033235-EO, Issue 2, dated 15 May 2006 orlater approved revisionAFM Supplemental Doc. 2033235-AM, Issue 2, May 2006 or later approved revision	Certification Basis of the Change CS 25, additionally EASA AMC 20-4 (BRNAV) and AMC 20-5 (GPS)	06/06/2006	Active	10014559
EASA.A.S.02659	AERO-DIENST GMBH & CO. KG			55	FMS UNS-1L Installation (Universal Avionics System Corp.)		Engineering Order, 218-LR, Rev. IR, or later approved revisionAFM Supplement, AG586-071, Rev. A, or later approved revision		24/07/2006	Active	10014560
EASA.A.S.02661	IBERIA LINEAS AEREAS DE ESPANA			AIRBUS A321-212	Passenger Cabin Lay-Out Modification for Special Flight		IBE DOA0001 Rev 1, Dated 28th June 2006	--	05/09/2006	Active	10014561
EASA.A.S.02662	TELEDYNE Ltd.D/ B/A TELEDYNE CONTROLS FLIGHT DATACOMPANY		CAA UK RESPONSIBILITY	MD80 SERIES	Installation of Optical Quick Access Recorder.		Master Data List MOD-MDL-018-01 dated 6 December 2006 or later EASA approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/07/2007	Surrendered	10014562
EASA.A.S.02664	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOMBARDIER CL-600-2B16 (604)	Introduction of Passenger Cabin Interior		STC Twenty One MDL No. S21.MDL-0131 at Issue 1 or later approved revision. Midcoast Aviation Inc. AFM supplement 34-261M021 or later approved revision		22/06/2006	Active	10014564
EASA.A.S.02665	SCHERDEL ENGINEERING Ltd.			LS1-F	Change of Empty Mass and Ballast Requirements for the Glider LS1-f		Doc Number 06-262-001	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	19/02/2007	Active	10014565
EASA.A.S.02667	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-34-200T, PA-34-220T PA-34-200 (SENECA)	Installation of dual Garmin GNS430 and Dittel FSG 2T in a Piper PA34.		Engineering Order ASR 2006-029-00 Rev. AMaster Drawing ListAFM Supplement ASR 2006-029-01 Rev. AAFM Supplement ASR 2006-029-02 Rev. AICA Garmin GNS 430 duel installationICA DittelFSG 2T installationICA ACK A-30 Altitude DigitizerInstallation Instructions ASR2006-029-00 10	1. Maximum operating altitude 18.000 ft2. GPS is not approved for TERM and APPR NAV3. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be d...	22/05/2006	Active	10014566
EASA.A.S.02668	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	BD-700-1A11	Installation of an Electronic Flight Bag (EFB) on A/C S/N 9089Modification Summary List: BBJ745 issue 1CCL: BBJCCL205 issue 1ADoC: Mod. Sum. Sh. & Certificate of Design iss. 25/10/2006		AFM-Supplement: BBJFMS017 Rev IRInstallation Manual: 929-600040-00 Rev 4	This approval of thie installation does not include any approval of the suitability, integrity, or accuracy of the EFB hardware, software, data base, display, controls or lighting.The capability of the system to "perform its intended function" has not been verified or certified.This approval does no...	03/11/2006	Active	10014567

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02673	KUERZI AVIATION AG			BOMBARDIER DHC-6 SERIES 300	Installation of KMH-880, GPS-400 & KMD-850.		MDL-200615247 Rev. C or later approved revisions.	Limited to S/N 0841.	13/04/2007	Active	10014569
EASA.A.S.02674	SOCIETE AIR FRANCE S.A.			BOEING 767	B767 Cabin Reconfiguration from KLM to Aeroflot.		CAS-B767-06-008		20/07/2007	Active	10014570
EASA.A.S.02675	RUAG AEROSPACE SERVICES GmbH			CITATION C560XLS	Installation of Honeywell Solid-State Flight Data Recorder (SSFDR) withTeledyne Controls Mini Flight Data Acquisition Unit (MFDAU)		Engineering Order, 036A-EO, dated 06/06/2006 or later approved revisionAFM Supplement, 036A-AFMS, dated 10/05/2006 or later approved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	26/06/2006	Active	10014571
EASA.A.S.02676	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			HAWKER 800 SERIES BAE 125 -800	Replacement of Dual FMS UNS-1D by Dual UNS-1F, to allow theaircraft to comply with PR-NAV requirements.		Installation to be in accordance with AIEC Engineering Order ref AI569-062, rev A dated 05.09.2006 or later approved revision.Operation to be in accordance with AIEC Aircraft Flight Manual Supplement ref AI569-071, rev IR dated 14.06.2006 or later approved revision.Continued Airworthiness to be in a...	--	21/09/2006	Active	10014572
EASA.A.S.02677	SABENA TECHNICS DNR			FOKKER F.28 MARK 0100	Fokker 100 VIP Cabin		AFM Supplement FK-25-LAIKA-01-FM REV H	Maximum approved passenger capacity: 19Limited to serial numbers 11368, 11403, 11406.Refer to AFM Supplement.	03/07/2007	Active	10014573
EASA.A.S.02678	LUFTHANSA TECHNIK AG			AIRBUS A319-115	Interior and systems installation incl. convertible cabin configuration		Supplement Type Definition document ref. STDD00-06/04M / Issue 2 / dated January 16, 2007.Airplane Flight Manual Supplement ref. A-00-06/444-AFM revision 02, dated January 9, 2007or later approved revision.	Instruction for Continued Airworthiness, Airworthiness Limitations, Section 4.3, ref. C-AAA000-ICA, issue 2, dated January 12, 2007or later approved revision	26/01/2007	Active	10014574
EASA.A.S.02679	SELL GmbH			BOEING 777-300 BOEING 777-200	Interior Re-configuration of Forward Galley Complex for Emirates airline.		Type Investigation Document MPD1023G-25-01 iss. 1 dated 17 January 2007.	Limited to B777-200/300 models serial numbers 29324 and 29325.	18/01/2007	Active	10014575
EASA.A.S.02681	JET AVIATION AG, BASEL			BOEING 727-200	Cabin interior modification:According to the description inthe Certification Plan, Doc. No. BACBA008-1.		Declaration of Compliance dated 14 March 2007.Master Data List Doc. No. BACBA008-001.AFM Supplement Doc. No. BACBA008-201-12.	Reg.: A9C-BA, S/N: 218424Approval limited to S/N 21824 only.	22/03/2007	Active	10014576
EASA.A.S.02682	JET AVIATION AG, BASEL			B727-200	Stretcher & Medical Equipment installation:According to thedescription in the Certification Plan, Doc. No. BACBA008-3		Declaration of Compliance dated 14 March 2007.Master Data List Doc. No. BACBA008-003.AFM Supplement Doc. No. BACBA008-201-12.	Reg.; A9C-BA, S/N: 21824Approval limited to S/N 21824 only.	22/03/2007	Active	10014577
EASA.A.S.02683	AIR ALPHA A/S			B200	Installation of Trane & Trane Aero-I satcom equipment in accordance with danish STC 03/9Note: This STC superseads SLV STC No. 3/99		Copenhagen Avionics T.O package: "T & T Aero-I Satcom innstallation".AFM Supplement: Trane & Trane Aero-I Satcom system in Beech model B200Danish STC 03/99.		13/07/2006	Orphaned	10014578
EASA.A.S.02684	AIR ALPHA MAINTENANCE A/S			B200	Installation of Trane & Trane Aero-M satcom equipment in accordance with danish STC 04/99Note: This STC superseads SLV STC No. 04/99		Copenhagen Avionics T.O package: "T & T Aero-M Satcom innstallation".AFM Supplement: Trane & Trane Aero-M Satcom system in Beech model B200Danish STC 04/99.		13/07/2006	Orphaned	10014579

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02685	AIR ALPHA MAINTENANCE A/S			B200	Installation of Trane & Trane Aero-C satcom equipment in accordance with danish STC 05/99.Note: This STC superseads SLVSTC No. 05/99		Copenhagen Avionics T.O package: "T & T Aero-C Satcom innstallation".AFM Supplement: Trane & Trane Aero-C Satcom system in Beech model B200Danish STC 05/99.		13/07/2006	Orphaned	10014580
EASA.A.S.02686	AIR ALPHA MAINTENANCE A/S			B200	Installation of Trane & Trane Aero-I, Aero-M and Aero-C satcom equipment in accordance with danish STC 29/99.Note: ThisSTC superseads SLV STC No. 29/99.		Copenhagen Avionics T.O package: "T & T Aero-I, Aero-M andAero-C Satcom innstallation".AFM Supplement: Trane & Trane Aero-I, Aero-M and Aero-C Satcom systems in Beech model B200Danish STC 29/99.		13/07/2006	Orphaned	10014581
EASA.A.S.02688	SCANDINAVIAN AVIONICS DESIGN ApS			HAWKER 800 XP HAWKER 800 BAE 125 -800 SERIES	Installation of an In-flight Entertainment System		Engineering Order, Doc. No. 2031919-EO-01, issue 2, dated 16-May-2006, or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2031919-AM-01, Issue 3, dated 08-Feb-2007, or later approved IssueInstructions for Continued Airworthiness, Doc. No. 2031919-CA-01, Issue 2, dated 0...	This change is limited to airplanes equipped with ARINC 429Interface to GPS / FMS	22/03/2007	Active	10014582
EASA.A.S.02689	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BAE 146/AVRO 146 SERIES BAE 146	Installation of Single or Dual Universal UNS-1L or UNS-1K+ Flight Management System		Tenencia Modification TEN 467AFM Supplement 1 issue 1 (TEN/146/001)AFM Supplement 2 issue 1 (TEN/146/002)AFM Supplement3 issue 1 (TEN/146/003)AFM Supplement 4 issue 1 (TEN/146/004)	RNAV Approaches are not permitted for installation with electronic-mechanical instruments	06/09/2006	Active	10014583
EASA.A.S.02691	AVIATION DEFENSE SERVICE	REV. 1		MYSTÈRE-FALCON 20C5/D5/E5 FAN JET FALCON D AND E	AVD-MDA20-95-054B: Installation of new age Alkan Pylon6075(76)C006		see Change Approval Sheet CAS AVD-MDA20-95-054B Iss.1dtd. 7.4.08 or later approved revisions:-AFM supplement SAFM FALC20 rev 13 dtd. 15.Sep.08 orlater approved revisionsand associated technical documentation	1. Limitations iaw SAFM FALC20 apply for operation with AVDMDA20-95-054B2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthine...	24/11/2008	Active	10014584
EASA.A.S.02692	AVIATION DEFENSE SERVICE			MYSTÈRE-FALCON 20D5/E5	AVD-MDA20-95-055A: Installation of under-wing stores		see Change Approval Sheet CAS AVD-MDA20-95-055A Ed. 01 Rev.00 dtd.07.01.08 or later approved revision-AFM Supplement SAFM-FALC20 Rev.14 dtd. 16.09.08-Instructions for Continued Airworthiness iaw Modification Sheet AVD-MDA20-95-055A Section B.8and associated technical documentation	1. Limitations iaw AFM Supplement SAFM-FALC20 to DTM 918 apply for operation with POD installation iaw AVD-MDA20-95-055A2. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willi...	24/11/2008	Active	10014585
EASA.A.S.02693	AVIATION DEFENSE SERVICE			MYSTÈRE-FALCON 20E5 MYSTÈRE-FALCON 20D5 MYSTÈRE-FALCON 20C5	STRUCTURAL INSTALLATION OF A FUGRO GPS ANTENNA ON THE FUSELAGE		Change Approval Sheet N AVD-MDA20-34-052A Issue 1 or later approved revisions and associated documents	Compatibility with previous approved modifications shall bedetermined by the installer.	23/04/2007	Active	10014586
EASA.A.S.02694	AVIATION DEFENSE SERVICE			MYSTERE FALCON 20	AVD-MDA20-25-050A: Installation of consoles in cabin.		see Change Approval Sheet CAS AVD-MDA20-25-050A Iss. 1 dtd. 13.11.2007 or later approved revision and associated technical documentation.		15/11/2007	Active	10014587

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02695	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 737-200	Installation of 106 Seat LOPA		Bournemouth Aviation (Consultants) Modification BAC/737/056		31/07/2006	Active	10014588
EASA.A.S.02696	PHOENIX AEROSPACE LIMITED	REV. 1	CAA UK RESPONSIBILITY	BN2B-26 ISLANDER	Installation of GNS530, GNS430 & GMA340.		• Phoenix Aviation Design Services Modification PADS/CP/1057• Phoenix Aviation Design Services AFM Supplement PADS/FMS/BN2B/001 Revision 0 or later approved revision & PADS/FMS/BN2B/002 Revision 0 or later approved revisionGNS530•Phoenix Aviation Design Services AFM Supplement PADS/FMS/BN...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	24/04/2007	Active	10014589
EASA.A.S.02702	AIRTOURING LTD		CAA UK RESPONSIBILITY	PA-31-350 (CHIEFTAIN)	Installation of Avionics Upgrade		Airtouring Modification AT_MOD_1096Airtouring AFM Supplement AT_FMS_1096 & AT_FMS_1096-1	--	28/07/2006	Active	10014591
EASA.A.S.02703	SCANDINAVIAN AVIONICS DESIGN ApS			BAE JETSTREAM 3200 BAE JETSTREAM 3100	Sandel ST3400 TAWS installation		Engineering Order 2034126-EO, Issue 2, dated 12 July 2006, or later approved revisionAFM Supplement Doc. 2034126-AM, issue 1, July 2006, or later approved revision	Certification Basis of the Change CS 25, additionally JAA TGL No. 12 (TAWS)	21/07/2006	Active	10014592
EASA.A.S.02704	AMICALE DE VOLTIGE AERIENNE(AVA)			CAP231, CAP231EX, CAP232	Fuselage frames 1,2 & 3 Reinforcement		-SB AVA-BS-2006-0l for CAP232 aircraft-CAP232 AFMS - AVA-STC-2006-01-SB AVA-BS-2006-02 for CAP2311231EX aircraft	I. Fuselage Frames 2 & 3 for CAP232 aircraft and Fuselage Frames 2 forCAP231 andCAP23 1 EX aircraft must be reinforced by Air Menuiserie only.2. This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraph "Description". Compatibility with...	31/07/2006	Active	10043112
EASA.A.S.02710	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	MODFD863 FAN JET & MYSTERE FALCON 20012 APPLICABLE TO FALCON 20 BASIC,	DC~075 Issue 2 dtd. 8.Mar 07 - Enhanced ATC Mode S or laterapprovedrevision: EnhancedATC Mode S.		See Design Change Statement DC-0075 dtd. 8. Mar 07 (includes Master Datalist):- Flight Manual Supplement FRAHIFMllOO Rev. 7 dtd 27.Feb 07 or laterapproved revision- Instructions for Continued Airworthiness ICA-0075 Rev.A or laterapproved revision	1. Certification Basis CS25 initial issue.2. Compliance with TGL 13 and NP A 20-12a has been shown.3. Applicable to Falcon 20 Basic, D & E models Post Mod FD863.4. Not all required Download Parameters/ DAP are provided, the AFMLimitation Sectioncontains the DAPs available.5. This STC is approved only...	13/03/2007	Active	10043113
EASA.A.S.02711	EXECUTIVE JET GROUP LTD		CAA UK RESPONSIBILITY	900	Approval of Cabin Configuration & Changes for the Issue of an EASA C ofA on Aircraft RegG-HMEV			This STC is approved only for the product configuration as defined inthe approved design datareferred to in the paragraph "Description". Compatibility with otheraircraft/ engineconfigurations shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orrevok...	26/06/2006	Active	10043114
EASA.A.S.02713	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOMBARDIER CL-600-2B16 (604)	Omnibus Modification to Support Aircraft Importation.		Bournemounth Aviation (Consultants) Omnibus Modification BAC/CL/001.	Restricted to ASN 5383.	28/11/2006	Active	10014596
EASA.A.S.02717	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BAE ATP	Rework of LH Passenger Door		STC Twenty One Master Drawing List S21.MDL. 0135 Initial Issue dated 16 April 2007 or later approved revision.STC TwentyOne AFM Supplement S21.FMS-0018 Issue 1 or later approved revision.		11/05/2007	Active	10014597

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02720	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (604) BOMBARDIER CL-600-2B16 (601-3R BOMBARDIER CL-600-2B16 (601-3A BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Enhanced Ground Proximity Waning System-EGPWS-MK VII or MKVenhancement with RAAS		RUAG Aerospace Services Modification reference SE-464b/2006/wt069B-RFCRUAG Aerospace AFM Supplement 069B-AFMS Revision N/C dated November 09 2006 or later approved revision		07/02/2007	Active	10014599
EASA.A.S.02722	AERO TECHNICS DESIGN LIMITED	REV 1	CAA UK RESPONSIBILITY	BOEING MD-83	Cabin Reconfiguration from 167Y to 52C/ 22Y Seating		Aero Technics Design Modification ATD0150.Aero Technics Design AFM Supplement ATDFMS0150		28/09/2006	Active	10014600
EASA.A.S.02724	AIR FRANCE			BOEING 767-300	Enhanced Surveillance Dual ATC Mode S Installation		Air France Change Reference CAS-B767-06-007 REV 0Air FranceIndustries AFM Supplement MT.MO 425/06/ESG REV 00Dated 06 June 2006 or later approved revision		23/02/2007	Active	10014601
EASA.A.S.02725	LUFTHANSA TECHNIK AG			BOEING 747-300 BOEING 747-200 BOEING 747-100	Installation of Pneumatic Metric Altimeter		- Supplemental Type Definition Document No. STDD34-06/01M, Issue 1, Rev. 00, dated Aug 22/06 or later approved revision- Airplane Flight Manual Supplement A-34-06/069-AFM, Revision IR, dated Aug 22/06 or later approved revision	Certification Baisis of the Change: CS-25 Amdt. 1	25/08/2006	Active	10014602
EASA.A.S.02726	AVIONES, PIEZAS Y ACCESORIOS, S.L.			421C	Installation GNS-430 and DME KN62AGarmin GNS-430 GPS/NAV/ COMM system, Mid-Continent MD41D Annunciation Control Unit andBendix King KN62 DME installed on Cessna 421CS/N 0272 (GPS approved for IFR and B-RNAV operations).		Doc N° APA 018/03 "Programma de Certificacion", Edicion 1 Revision 0 dated 20 April 2005. Installation Instructions in accordance with:- Doc N° APA 018/03 "Orden Tecnica" Edicion 1 Revision 0- Garmin GNS430 Installation Manual 190-00140-02, Rev. 6- MD41-() series Installation Manual 8018277, Rev. 1-...	1. Restricted to aircraft CESSNA 421C S/N 0272.2. The aircraft is approved for dual pilot B-RNAV operation, subjected to the conditions, limitations and procedures contained in Doc N° APA 018/03 "Supplement Flight Manual", Ed 2 Rev 0	29/06/2006	Active	10014603
EASA.A.S.02728	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 650 CITATION VI CESSNA 650 CITATION III	Installation of Honeywell Multi-Function Radar Display (MFRD) and as an option a Honeywell Primus 400 Radar system.		Installation in accordance with Scandinavian Avionics Engineering Order ref 2034305-EO Issue 2, dated 29.6.2006, or later approved revisions.Operation in accordance with Scandinavian Avionics Flight Manual Supplement ref 2034305-AM Issue 1, dated August 2006, or later approved revisions.Instructions...	This STC is only applicable to Aircraft without EFIS systemand integrated MFD.	11/09/2006	Active	10014605
EASA.A.S.02730	LUFTHANSA TECHNIK AG			BOEING MD 11	Installation of a Rockwell Collins Tailwind 550 Live TV system in Boeing MD-11 as detailed in STDD53-06/19M Supplemental Type Definition Document for Tailwind 550 Live TV installation MD-11		1. A-00-07/510-AFM Airplane Flight Manual Supplement for TW550 Live TV installation, Rev. 01 dated November 06, 20072. R-00-07/535-ICA Instructions for Continued Airworthiness		09/11/2007	Active	10014606

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02735	AERODISA S.L.			SA227-PC SA 226-TC, SA227-AC, SA227-BC	AED2006-04M: TAWS installation on Fairchild SA 226/227		Master Data List AED2006-04M_MDL, Revision 3, dated 18/04/2007 or later EASA approved revision.FM Supplement AED2006-04M_D03, Revision 1, dated 22/03/2007 or later EASA approved revision.	See FM Supplement AED2006-04M_D03 Section II: Limitations.Certification basis per FAA TCDS A8SW: FAR 23 Amdt 6.TGL 12 complied with.	31/05/2007	Active	10014609
EASA.A.S.02737	RUAG AEROSPACE SERVICES GmbH			CESSNA 525	Installation of KLN-90BModel: 525 S/N 0001 up to 0359		Engineering Order 118-EORUAG AFM-S 118-FM, Rev. 0, approved10. March 2004, or later EASA approved RevisionMaintenance Procedures 118-MDL, Rev. 0, or later approved Revision	S/N 525-0001 up to 525-0359This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibilitywith other aircraft/engine configurations shall be determined by the installer.	10/07/2006	Active	10014610
EASA.A.S.02738	SOCIETE AIR FRANCE S.A.			AIRBUS A340-300	THY A340 Cabin Retrofit Modification		Air France Change Approval Sheet n° CAS A340-06-007 Rev. 0		16/05/2007	Active	10014611
EASA.A.S.02741	Aeroservis s.r.o.			CESSNA T210 SERIES	Upgrade of NAV/COM equipment for IFR navigation.		Pilot's operating handbook supplement No. 40, 41, 42, 43, 44, 45, 46, 47.	1. S/N: 210638072. This STC is approved only for the product configuration as defined in the approved design datareferred to in the paragraphs "Description" and “AssociatedTechnical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by the installer....	30/04/2007	Active	10014614
EASA.A.S.02744	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-46-500TP PA-46-310P, PA-46-350P	Installation of COM/NAV/GS/GPS GNS430, with GDC31 Roll Steering Converter.Installation of Diversity Mode S XPDR Garmin GTX330D.Installation of TCAS Avidyne TAS610.		• FMS ASR 2006-041-01, Rev. A Garmin GNS 430• FMS ASR2006-041-02, Rev. A DAC GDC31• FMS ASR 2006-041-03, Rev.A Garmin GTX 330D• FMS ASR 2006-041-04, Rev. A Avidyne TAS 610• FMS ASR 2006-041-05, Rev. A COM 2 GND Clearance Function	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	07/05/2007	Active	10014615
EASA.A.S.02745	BUSINESS AND COMMUTER AIRCRAFT			BEECH 1900D	Installation of VIP configuration in aft ward cabin and passive noise reduction kit		Airplane Flight Manual Supplement, Rev 0, dated 13 July 2006 or later approved revision.Airplane Maintenance Manual Supplement, Rev 0, dated 13 July 2006 or later approved revision.	This modification limits 14 passengers maximum.	09/11/2006	Active	10014616
EASA.A.S.02747	DASSAULT FALCON SERVICE			MYSTERE FALCON 20-5 MYSTERE FALCON 200 MYSTERE FALCON 20 FAN JET	DFS536 Issue A dtd. 29.Sep 06: Honeywell EGPWS Mark Vinstallation with Terrain display in Collins EFIS 86-C14		see Master Document List DFS-DE-17-F3-536 Issue A1 dtd.29.Sep 06 or later approved revisions:-AFM Supplement 33 to DTM30528 Rev. Original or laterapprovoved revisions-associatedlist of affected technical documents	Leaflet TGL 12 "Certification Considerations for the TerrainAwareness Warning System: TAWS" applies	02/10/2006	Active	10014617
EASA.A.S.02751	DASSAULT FALCON SERVICE			MYSTERE FALCON 200 FAN JET	DFS2574: Limitation Removal		'see Change approval sheet DFS2574:- AFM Supp FJF 44 issue4 or later approved revision and associated list of affected technical documents	Applicable to Fan Jet Falcon S/N 328 only	05/09/2006	Active	10014619

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02755	MT-PROPELLER ENTWICKLUNG GmbH	REV 3		DORNIER DO 228-212 DORNIER DO 228-202K DORNIER DO 228-202 DORNIER DO 228-201 DORNIER DO 228-200 DORNIER DO 228-101 DORNIER DO 228-100	- Installation of 5-blade MTV-27-1-E-C-F-R(G) / CFRL250-55b Full Feathering and Reversing Propellers.Revision 1: Extension of STC EASA.A.S.02755 to airplane model Do 228-212.Revision 2 and 3 issued to correct some typos.		- Doc. No. E-1436 “Installation Instructions”- MT-Propeller Instructions for ContAW. Doc. No. E-1437, Revision 1,or later approved Revision- EASA approved Airplane Flight Manual Supplement, Doc. No. E-1435, Revision 2, November 11, 2008 or later approved Revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	04/02/2009	Active	10014621
EASA.A.S.02756	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA S550 (CITATION II) CESSNA 560 (CITATION V) CESSNA 550 CITATION II CESSNA 500, CITATION	Installation of a “Flight Display Systems” Entertainment System: DVD player, Map computer and 2 LCD displays		System Description 2029710-DE,Drawing List 2029710-DL,MoC list 2029710-MOC,Engineering Order 2029710-EO,AFM Supplement 2029710-AM	The IFE sound shall be overrided by the PA system	31/08/2006	Active	10014622
EASA.A.S.02757	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (CL-601 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Honeywell Primus II RCZ-833 () Integrated Radio System – EHS.		RUAG Aerospace Services Master Drawing List 179E-MDL.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	12/01/2007	Active	10014623
EASA.A.S.02758	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (CL-601 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Upgrade Dual Honeywell FMS NZ-2000 / PRNAV.		RUAG Aerospace Services Master Drawing List 179B-MDL.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	12/01/2007	Active	10014624
EASA.A.S.02759	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (601-3A BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Iridium Satcom ST3100.		RUAG Aerospace Services Master Drawing List 179C-MDL.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	12/01/2007	Active	10014625
EASA.A.S.02760	AERODATA AG			650	Installation of TCAS 2000 System including Mode S Transponders		MDL-A/C -074 Rev.5 Master Document ListAFM - 068 Rev. 2 Airplane Flight Manual SupplementHB-A/C-747 Maintenance Manual Supplement	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	20/07/2006	Active	10043030
EASA.A.S.02764	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	HAWKER 800 XP	Installation of a L-3 Avionics F1000 Flight Data Recorder.		Installation in accordance with Lees Avionics Ltd Modification HL/MOD/728 Issue 2 or later approved revisions.Operationto be in accordance with Lees Avionics Flight Manual Supplement AFMS728001 Issue 2 for F1000 Flight Data Recorder Installation, or later approved revisions.Instructions for Continu...	This Installation is intended for compliance with JAR-OPS 1.715. This STC however grants no operational approval to this installation, that will need to be obtained from the Stateof registry for the particular aircraft involved as definedin JAR OPS 1.715(g).	17/10/2006	Active	10014626

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02765	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	BEECH 200	Enhanced Mode S Upgrade.		Master Document List MDL730001 Issue 1AFM Supplements AFMS730001 and AFMS730002.	Beech 200/300 SeriesAFM Supplements AFMS730001 and AFMS730002.	12/03/2008	Active	10014627
EASA.A.S.02766	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BAE 146/AVRO 146 SERIES	Introduction of T2CAS Collsion Avoidance & Terrain Awareness Warning System		STC Twenty One Modification S21.34-86-1041STC Twenty One AFM Supplement S21.FMS-0020 Issue 1 dated 18 October 2006 or alter approved revision	--	03/11/2006	Active	10014628
EASA.A.S.02768	AIM AVIATION (JECCO) LIMITED		CAA UK RESPONSIBILITY	A330-200/A330-300 MODELS	Introduction of flight crew rest facility into A330-200 and-300 aircraft.		Major change MM/ 334/06.SB AIMA330-25-004	MM-358-07 must be installed.	31/05/2007	Active	10014629
EASA.A.S.02770	JET AVIATION AG, BASEL			AIRBUS A319-115	Cabin interior outfittingsee Master Data List BA3192949-001		Flight Manual Supplement BJC02949-201-01	Limited to S/N 2949.	19/07/2007	Active	10014630
EASA.A.S.02773	AEROTECHNIC GMBH			DORNIER DO 228-212	Installation of mission equipment for maritime surveillance.		Compliance Programme DO228-12256201-0101 Rev. 2Master Document List DO228-12256201-0109 Rev. 0AFM-Supplement DO228-12256201-0601 Rev.1	Restricted to S/N 8181, 8183.RUAG changes EASA.A.C.04131 and EASA.A.C.04132 must be installed concurrently.	26/07/2007	Active	10014631
EASA.A.S.02774	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B60 BEECH A60 BEECH 60	Installation of Mode S Transponder Garmin GTX 330D		Engineering Order 2034278-EO, Issue 2, dated 14 July 2006, or later approved revision.Engineering Supplement 2034278-AM, issue 1, dated 6 September 2006, or later approved revision.Continued Airworthiness 2034278-CA, issue 1, dated 22 June2006, or later approved revision.		11/10/2007	Active	10014632
EASA.A.S.02777	AERO-DIENST GMBH & CO. KG			55	Installation of TAWS / RMI ST3400 (Sandel) System		Certification Program E/O 221-LR, rev. 2AFM Supplement AG601-071, rev. A	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	23/01/2007	Active	10014634
EASA.A.S.02782	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	AIRBUS A330	Installation of Quick Access Recorder.		Compliance Document Summary Sheet and Accomplishment Instructions Continuation Sheet, Ref BAC/ABUS/009, Issue 2 dated 19 December 2006.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description & Associated Technical Documentation". Compatibility with other aircraft/engine configurations shall be determined by the installer.	02/01/2007	Active	10014636
EASA.A.S.02783	EAD AEROSPACE	REV 1		BOEING 767	Installation of Panasonic "EFX" Passenger in Flight Entertainment System (IFE).		EAD Aerospace Master Drawing List 01110-EAS-A-MDL at Revision G.Airplane Flight Manual Supplement 01110-EAS-A-AFM-01 atRevision C.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	04/04/2007	Active	10014637

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02784	EAD AEROSPACE			BOEING 737-900 BOEING 737-800 BOEING 737-700 BOEING 737-600	Implementation of Honeywell “Link 2000” Controller-Pilot Data Link Communications (CPDLC) on B 737		- Supplemental Type Design Definition Doc 01106-EAS-A-STD-01 Revision C, or later EASA approved Revision.- MasterDrawing List 01106-EAS-A-MDL Revision E or later EASA approved Revision.- AFM Supplement 01106-EAS-A-AFM-01 RevisionB, or later EASA approved revision.- MEL Supplement 01106...	Compatibility of this design change with other previously approved modifications must be determined by the installer.	09/03/2007	Active	10014638
EASA.A.S.02785	AVIATION DEFENSE SERVICE			MYSTERE FALCON 20	AVD-MDA20-49-053A: Additional Power Bus using APU generation, installation of 2 additional inverters.		see Change Approval Sheet CAS AVD-MDA20-49-053A Iss. 0 dtd. 18.4.06 or later approved revision.-AFM supplement to DTM 918 - AFMS FA20 rev 12 dtd. 10.12.07 or later approved revision and associated technical documentation	Limitations iaw AFM supplement to DTM 918 - AFMS FA20 applyfor operation with additional inverters installed iaw AVD-MDA20-49-053A.	10/01/2008	Active	10014639
EASA.A.S.02789	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	AEROSPATIALE ATR 72 AEROSPATIALE ATR 42	Indraero Siren Cargo Container System installation on ATR42-320 and ATR72-202 aircraft previously converted to Class E Cargo Compartment Freighter.		For installation on ATR42-320 aircraft:Bournemouth AviationBAC/ATR/003 Issue 2 Siren Cargo Loading System InstallationATR42 and• Installation Instructions as per Bournemouth Aviation Accomplishment Instructions BAC/ATR/003 Issue 2 andDrawing BAC-1522-01 Issue B.• Maintenance Instructions as...	This STC is applicable on the following aircraft:Those ATR42-320 previously converted to Class E Cargo Compartment Freighter by the embodiment of the following ATR GIE Service Bulletins:• ATR42-25-0070 Reinforce all floor panels, and• ATR42-25-0063 Modify A/C for Cargo Container Loading, and••...	29/01/2008	Active	10014640
EASA.A.S.02791	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 560 CESSNA 550 BRAVO	Honeywell EGPWS MK VIII Installation		Engineering Order 2035111-EO Issue 1, dated 16/08/2006 or alter approved revisionAircraft Flight Manual Supplement 2035111-AM Issue 1, dated August 2006 or later approved revision	Certification Basis of the Change: CS 25 Amanedment 1m, aditionally JAA Leaflet No. 12 (TAWS)	03/11/2006	Active	10014641
EASA.A.S.02792	TSA TRANSAIRCO S.A.			PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12	AFT Refreshment Galley and OvenRefer to master certification documents list TS PC12-25.30.02MCL		Airplane Flight Manual Supplement TSA PC12-25.30.02AFMS	1. Limited to serial number 321 and later;2. Galley power and microwave oven use is not approved during take-off and landing phases of flight and during emergency or abnormal procedures;3. When aft refreshment galley is installed,the luggage area maximum load is 218lb (100Kg) and limited t...	21/11/2006	Active	10014642
EASA.A.S.02794	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	FAN JET FALCON BASIC, D AND E	DC-0094 Issue 1: Extended RVSM operation<(>,<)>		1. DC-0094 Issue 1 dated 11.12.07 or later approved revision;2. FRA AFM Supplement FRAHIFMIIOO revision 9 or later approved revision.	1. Limited to Fan Jet Falcon with FRA STC EASA.A.S.005l0 embodied;2. This STC does not constitute an operational approval;3. Prior to installation of this modification the installer mustdetermine that theinterrelationship between this modification and any other previouslyinstalledmodification will i...	08/02/2008	Active	10043116

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02795	E.I.S.A.			MYSTERE FALCON 20	Addition of Enhanced Surveillance Capacity on existing TDR 94 Mode S Transponder installation.		Supplemental Type Certificate Data List EISA 05 SDL S114 Rev. 4Aircraft Flight Manual Supplement EISA 05 AFM S114 Rev. 1Aircraft Maintenance Manual Supplement EISA 05 AMMS S114 Rev. 0Or later approved revisions of these documents.	Major Design Change applicable to aircraft Fan Jet Falcon and Falcon 20 equipped with:• Rockwell Collins Proline IV avionics suite.• Mode S Elementary Transponder TDR-94D-008.• FMS-6000.• Air Data Computer ADC-850C.• An Input/Output Concentrator.Aircraft Flight Manual Supplement EISAA...	01/02/2008	Orphaned	10014643
EASA.A.S.02796	JET AVIATION AG, BASEL			AIRBUS A319-100	Installation Of Additional Water Tank		Declaration of Compliance, Document Number BVCCJ003-001, Revision A, dated 16th April 2007, or later EASA approved revision.Master Data List, Document Number BVCCJ003-001, Revision A, dated 16th April 2007, or later EASA approved revision.Instructions for Continued Airworthiness, Document Number BVC...		24/04/2007	Active	10014644
EASA.A.S.02799	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (CL-601	40Ah Battery with Charger.		RUAG Aerospace GmbH Master Drawing List 179F-MDL.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	12/01/2007	Active	10014645
EASA.A.S.02800	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (601-3A	Interior, Aircell Antenna & Miscellaneous Equipment.		RUAG Aerospace Services Master Drawing List 179G-MDL.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	12/01/2007	Active	10014646
EASA.A.S.02802	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			LEARJET 35A LEARJET 35	Installation of Honeywell RDR 2000 and KMD 850.		Report 2006-16, rev. D (or later approved revision).AMM Supplement 2006-16-10, rev.A (or later approved revision)		25/06/2007	Active	10014647
EASA.A.S.02803	RUAG AEROSPACE SERVICES GmbH			CESSNA 560 (CITATION V)	Transpoder Mode S Honeywell Primus II – ELS/EHS, Upgrade ofthe two existing Mode S Transponder RCZ-833K by Honeywell Service Bulletin to implement ELS/EHS transponder capability. Installation of new wires from the FMS and the two Display/Guidance Computer IC-600 to the dual RCZ-833() Com Units.EAS...		RUAG Compliance Check List Doc.-No.:148C-CCL Rev N/C dated 24.08.06, RUAG System Description Doc.-No.:148C-SD Rev. N/C dated 18.08.PATS Aircraft, LLCRUAG AFM Supplement Doc.-No 148C-AFMS	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	15/09/2006	Active	10014648
EASA.A.S.02804	AIM AVIATION (JECCO) LIMITED		CAA UK RESPONSIBILITY	AIRBUS A330-300 A330-200/A330-300 MODELS	Aer Lingus Flight Crew Rest Facility		Change No. MM/ 33/06Operation & Maintenance Manual: Publication 1/07CMM/ AIM Publication 25-70-03		05/02/2007	Active	10014649
EASA.A.S.02805	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			MOONEY M20M	BRNAV capacity modification - Installation of annunciator MD 41, technical description in FAM No. 1147/06/SEAM		Airplane Flight Manual Supplement No. 1/SEAM dated 23rd May2006.	Modification limited to s/n 27-0135	16/03/2007	Active	10014650

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02806	LUFTHANSA TECHNIK AG			AIRBUS A300	A300F4-605R Multi Mode Receiver (MMR) and Global Positioning System (GPS) installation		Supplemental Type Definition Document STDD34-06/04M, Issue 1 dated 12 March 2007Compliance Record List CRL34-06/04M, Issue 1 dated 15 March 2007Aircraft Flight Manual Supplement A-00-06/460-AFM/ISS, Initial Release dated 01 November 2006Master Minimum Equipment List Supplement A-00-06/460-MMEL, Init...		22/03/2007	Active	10014651
EASA.A.S.02810	ACI SYSTEMES			BEECH 200	ATC replacement and Mode S installation.		ACI S007/2006AFMS No ACI 05 AFM S007 Revision 0 or later approved revision	AFMS must be on board when modified	07/05/2007	Orphaned	10014653
EASA.A.S.02811	RUAG AEROSPACE SERVICES GmbH			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Installation of Flight Information System Sirius FD200		Installation in accordance with RUAG Master Document List Document No 178D-MDL and Engineering Order Document No 178D-EO, at the latest approved revision.	None	11/12/2006	Active	10014654
EASA.A.S.02812	RUAG AEROSPACE SERVICES GmbH			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Installation of Honeywell EGPWS Mk VIII.		Installation in accordance with RUAG Master Document List Document No 178B-MDL and Engineering Order Document No 178B-EO, at the latest approved revision.Aircraft to be Operated in accordance with RUAG Aircraft Flight Manual Supplement Document No 178B-AFMS, at the latest approved revision.	None	11/12/2006	Active	10014655
EASA.A.S.02813	RUAG AEROSPACE SERVICES GmbH			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Installation of Honeywell MST-67A Mode S Transponders.		Installation in accordance with RUAG Master Document List Document No 178A-MDL and Engineering Order Document No 178A-EO, at the latest approved revision.Aircraft to be Operated in accordance with RUAG Aircraft Flight Manual Supplement Document No 178A-AFMS, at the latest approved revision.	None	11/12/2006	Active	10014656
EASA.A.S.02814	RUAG AEROSPACE SERVICES GmbH			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Installation of Aircell Iridium Satcom Axxess II		Installation in accordance with RUAG Master Document List Document No 178E-MDL and Engineering Order Document No 178E-EO, at the latest approved revision.Aircraft to be Operated in accordance with RUAG Aircraft Flight Manual Supplement Document No 178E-AFMS, at the latest approved revision.Aircrafto...	None	11/12/2006	Active	10014657
EASA.A.S.02815	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	747-400	Interior changes required on Cathay Pacific Boeing 747-400 aircraft MSN 27132 for BE Aerospace Flight Structures.		MOD BBJ 804		10/05/2007	Active	10014658

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02818	RUAG AEROSPACE SERVICES GmbH			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Installation of modified and refurbished cabin interior		Ruag Master Document List Document No. 178F-MDLEngineering Order Document No. 178F-EO, at the latest approved revision.		12/12/2006	Active	10014661
EASA.A.S.02819	AERO-DIENST GMBH & CO. KG			31A	Enhanced Surveillance Mode S Transponder Upgrade (Honeywell)		EO 222-LR, rev. 1Certification Compliance Sheet AG599-075, rev. AAFM Supplement AG599-071, rev. IRInstructions for Continued Airworthiness AG599-085, rev. A		28/03/2007	Active	10014662
EASA.A.S.02820	SOCIETE AIR FRANCE S.A.	REV 1		BOEING 737-500 BOEING 737-300	Installation of elementary surveillance Dual ATC Mode S on B737-300/-500 in accordance with the Modification File MDF-B737-04-004, Rev 01, dated 11 October 2006.		- Modification Design File MDF-B737-04-004, Rev 01, dated 11th October 2006.- Modification Airworthiness File MAF-B737-04-004 Rev 00, or later approved revisions.- AFBS B737-04-004-34-002 , first Issue- ICA-B737-04-004 Rev 00, or later approved revision.	1. Limited to installation on Boeing 737-300/-500.2. Compatibility of this design change with other previously approvedmodifications must be determined by the installer.	23/10/2006	Active	10014663
EASA.A.S.02821	EAD AEROSPACE			BOEING 757-200 SERIES	Installation of Thales Integrated Standby Flight System		Certification Plan 01109-EAS-A-CPM-01 Rev BMaster Drawing List 01109-EAS-A-MDL Rev CGround Test Plan/Report 01109-EAS-A-GTR-01 Rev BCompliance Checklist 01109-EAS-A-CCL-01 Rev AEAD AFM Supplement 01109-EAS-A-AFM-01 Rev BEAD MEL Supplement 01109-EAS-A-MEL-01 Rev B		11/05/2007	Active	10014664
EASA.A.S.02823	DASSAULT FALCON SERVICE			FALCON 10	MODE S TRANSPONDER WITH ENHANCED SURVEILLANCE CAPACITY		See:Master Document List DFS-DE-17-F1-1278 Issue B1 or later approved revisionsAircraft Flight Manual Supplement DFS Nº36, Rev Original or later approved revisions	1. This STC is approved only for those Falcon 10 aircraft equipped with two Collins TDR-94D(-007) Mode “S” ATC Transponders and “Flight Ident” source.2. Compatibility with previous approved modifications shall be determined by the installer.3. JAA Leaflet TGL 13 Certification of Mode S Transponder S...	05/12/2006	Active	10014666
EASA.A.S.02824	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 757-200 SERIES	Reduction of Over-Wing Emergency Exits from 4 to 2.		AFM Supplement No. S21.FMS.0021.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	22/12/2006	Active	10014667
EASA.A.S.02826	SCANDINAVIAN AVIONICS DESIGN ApS			L-410 UVP-E20	Honeywell EGPWS MK VI Installation.Installation of Honeywell Enhanced Ground Proximity Warning System EGPWS/TAWS.		• AFM Supplement Doc. 2035430-AM, Issue 2, or later EASAapproved Issue• Description of Change: 2035430-DE, Issue1• Engineering Order: 2035430-EO, Issue 2• Technical Order: 2035430-TO, Issue 1	1. This STC is only applicable for aircraft which have all the following equipment already installed:Honeywell (Bendix-King) IN-182 or KMD-850 Radar DisplayKN-53 NAV SystemKRA-405 Radar AltimeterKCS-55A Compass SystemComputer Instruments Corp. 04077 Air Data System2. This STC is...	30/01/2007	Active	10014668

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02827	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	MYSTERE FALCON 200/20 SERIES FAN JET	DC-0088 Rev.I dtd. 22.12.06: Increase to Max Zero Fuel Weight.		DC-0088 Iss.I dtd. 22.12.06 or later approved revision-FRA AFM Supplement FRAHIFMIIOO revision 6 or later approved revision	1. Limited to Falcon 20 acc. DC-0088 Master Document List Section.2. Cert Basis CAR 4b, and (Elect to Comply to) CS25 Arndt 2 paragraphs25.1, 25.25, 25.571<(>,<)>25.1501(b), 25.1519, 25.1581 and 25.1583.3. This STC is approved only for theproduct configuration as defined inthe approved designdata r...	05/01/2007	Active	10043117
EASA.A.S.02828	AERO-DIENST GMBH & CO. KG	REV. 1		HS.125 SERIES 700B	FMS UNS-1L System Installation (UASC)		Installation in accordance with Aero-Dienst Engineering Order ref 223-HW, Rev. 1, dated 21. June 2007, or later approved revision.To be operated in accordance with Aero-Dienst Flight Manual Supplement ref AG623-071, Rev A or later approvedrevision.		07/01/2008	Active	10014669
EASA.A.S.02831	TRANSAIRCO S.A.			PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12	F.D.S.FD932 DVD Player Installation		Master Certification Documents List TSA PC12-23.33.02 MCL	None	08/11/2006	Active	10014671
EASA.A.S.02832	SCANDINAVIAN AVIONICS DESIGN ApS			HAWKER HS 125-700 SERIES HAWKER HS 125-600 SERIES HAWKER 800 BAE 125 -800 SERIES	Installation of a Universal Terrain Awareness Warning System (TAWS).		- Technical Order, Doc. No. 2035674-TO, issue 3, dated 03-Jan-2007, or later approved issue- EASA approved Aircraft Flight Manual Supplement, Doc. No. 2035674-AM-A, Issue 1, datedSeptember 2006, or later approved Issue for operation with FMS display of terrain or- EASA approved Aircraft Flight Manu...	1. This change is limited to following configuration of theaircraft / equipment type:all airplanes equipped with* ARINC 429 Air Data Computers with temperature compensation, and* Rockwell Collins Proline 2 or 4 RADALT, VOR/ILS, and* Display System such as Rockwell Collins EFIS 85...	10/01/2007	Active	10014672
EASA.A.S.02833	SCANDINAVIAN AVIONICS DESIGN ApS			HAWKER HS 125-700 SERIES HAWKER HS 125-600 SERIES HAWKER 800 BAE 125 -800 SERIES	Installation of a Universal UNS-1F and / or UNS-1L Flight Management System for Basic RNAV, Precision RNAV Operations and Non-precision Approaches and also as a primary means of navigation for oceanic/remote operations.		Technical Order, Doc. No. 2035499-TO, issue 2, dated 04-Jan-2007, or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2035499-AM-A, Issue 1, dated October 2006, or later approved Issue, for UNS-1F and UNS-1L FMSEASA approved Aircraft Flight Manual Supplement, Doc. No. 20...	1. This change is limited to following configuration of theaircraft / equipment type:all airplanes equipped with* Rockwell Collins Proline 1 (only NAV receiver), Proline 2 or 4 Navigation Equipment,and* Rockwell Collins analog HSI's or EFIS 85/862. Compliance with CS met or exceeded the ai...	10/01/2007	Active	10014673
EASA.A.S.02834	JET AVIONICS AVIATION & MARINESERVICE CENTER S.r.l.			BOMBARDIER CL-215-6B11	Installation of Radar Altimeter AA-300 System		Master Drawing List BDI 002-06-01AFMS BDI 002-06-14	N/A	01/03/2007	Active	10014674
EASA.A.S.02835	AIRBUS ATLANTIC	REV 1		AIRBUS A320-212 AIRBUS A320-211	Emergency locator transmitter Thales/ Serpe Kannad 406 ATP installation.Note: This revision reflects the transfer of this STC from EADS Sogerma Services to Sogerma Services.		Airplane Flight Manual Supplement ref. FMS 25-967, issue B,dated November 3, 2004 or later EASA approved revision.		04/01/2008	Active	10014675
EASA.A.S.02836	LUFTHANSA TECHNIK AG	REV. 4		AIRBUS A318-112	Structural Floor Panel ReconfigurationThe limitation for divans that they must not be occupied for taxi, take off and landing has been suspended for 1315 FH or 14 monthswhatever occurs first, starting at June 26th, 2008.The modification isdescribed in the Alert Engineering Bulletin A318-EB53-0300 R...		Supplemental Type Definition Document, ref. Doc. No. STDD00-06/09M, issue 08, dated 17. December 2008, or later approved revisionAeroplane Flight Manual Supplement A-00-07/048-AFMrevision 7, dated 09. October 2008, or later approved revisionInstructions for Continued Airworthiness, ref. Doc. No. R-...	1. Side facing divans may not be used for taxi, take off and landing after1315 FH or 14 months whatever occurs first, starting at June 26th, 2008.2. Prior to installation of this modification the installer must determine that the interrelationship between this modificationand any other previousl...	18/12/2008	Active	10013924

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02839	DASSAULT FALCON SERVICE			MYSTERE FALCON 900	MODE S TRANSPONDER WITH ENHANCED SURVEILLANCE CAPACITY		Master Document List DFS-DE-17-F9-9517 Issue B1 or later approved revisionsAircraft Flight Manual Supplement DFS Nº 25,Rev Original or later approved revisions	This STC is approved only for those Mystere Falcon 900B aircraft equipped with two Collins TDR-94D(-007) Mode “S” ATC Transponders and “Flight Ident” source.Compatibility with previous approved modifications shall be determined by the installer.JAA Leaflet TGL 13 Certification of Mode S TransponderS...	30/11/2006	Active	10014678
EASA.A.S.02840	EAD AEROSPACE			B767-300	Installation of Thales Integrated Standby Flight Display (ISFD)		EAD Aerospace 01108-A.Flight Manual Supplement 01108-EAS-A-AFM-01 Rev A or later EASA Approved Revision.		05/03/2007	Active	10014679
EASA.A.S.02841	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			550	Supplemental Type Certificate for Cargo Net Installation onC550 MSN 0001-0626		EO M04600101	CRI A-02; Registration: OE-GAD; S/N C550-0071	12/02/2007	Active	10014680
EASA.A.S.02842	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			551	Supplemental Type Certificate for Cargo Net Installation onC551 MSN 0001-0549		EO M04600101	CRI A-02Registration (if applicable): OE-FADSerial number (if applicable): C551-0496	13/04/2007	Active	10014681
EASA.A.S.02843	DASSAULT FALCON SERVICE			FALCON 10	Extended Function (P-RNAV / RNP 1 Compliance) on Flight Management System (FMS) UNS-1K+ installation		• DFS Master Document List DFS-DE-17-F1-1279 Issue A1.• Aircraft Flight Manual Supplement DFS F10-037 Revision Original or later approved revisions for those Falcon 10 aircraft on which this STC has been embodied.or later approved revisions of these documents.	his STC is applicable to Falcon 10 aircraft equipped with:• Collins Autopilot and Flight Director APS80,• CollinsEFIS 85C-14.• 1 FMS Universal UNS-1K+ with software version 802.2 or laterFMS Universal UNS-1K+ installation has to be embodied through Dassault Falcon Service’s STC DFS 1264 (a...	29/07/2008	Active	10014682
EASA.A.S.02846	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	SD3-60	Introduction of Honeywell MK VI EGPWS		Modification S21_34-39-1047Flight Manual Supplement S21.FMS+-0022 Issue 1		07/12/2006	Active	10014683
EASA.A.S.02847	CARGOLUX AIRLINES INTERNATIONALS.A.			BOEING 747-400 SERIES	Installation of an Artex B406-4 Automatic Fixed Emergency Locator Transmitter on B747-400F in accordance with Cargolux Service Bulletin CLX-SB-747-23-001 and Master Drawing list CLX-STC-06-01.		The publications affected as tabled in the Service Bulletinshall be updated using the information provided in report CLX-STC-06-01Paragraph 7.4, Publication Update		14/03/2007	Active	10014684
EASA.A.S.02848	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	MODE S TRANSPONDER WITH ENHANCED SURVEILLANCE CAPACITY		See:Master Document List DFS-DE-17-5626 Issue A1 or later approved revisionsAircraft Flight Manual Supplement DFS Nº 52, Rev Original or later approved revisions	This STC is approved only for those Mystere Falcon 50 aircraft equipped with:- Two Collins TDR-94D(-007) Mode “S” ATC Transponders and “Flight Ident” source, and- Two Inertial Reference Systems.Compatibility with previous approved modifications shall be determined by the installer.JAA LeafletS...	29/11/2006	Active	10014685

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02850	DASSAULT FALCON SERVICE			MYSTERE FALCON 20-F5 MYSTERE FALCON 20-E5 MYSTERE FALCON 20-D5 MYSTERE FALCON 20-C5 FAN JET FALCON SERIES C	Mode S Transponder with enhanced surveillance capacity.		• Master Document List DFS-DE-17-F3-539 Issue A1 or later approved revisions• Aircraft Flight Manual Supplements:DFS55, for Fan Jet Falcon aircraft, Rev Original or later approved revisionsDFS34, for Mystere Falcon 20-()5, Rev Original or later approved revisions	1. This STC is approved only for those Fan Jet Falcon and Mystere Falcon 20-()5 aircraft equipped with two Collins TDR-94D(-007)Mode “S” ATC Transponders and “Flight Ident” source.2. JAA Leaflet TGL 13 “Certification of Mode S Transponder Systems for Elementary Surveillance” and JAA NPA 20-12a...	18/01/2007	Active	10014687
EASA.A.S.02851	DASSAULT FALCON SERVICE			MYSTERE FALCON 900	CABIN REFURBISHMENT		See:Master Document List DFS-DE-17-F9-9523 Issue A1 or later approved revisions	This STC is approved only for Mystere Falcon 900 Serial Number Aircraft 054.Compatibility with previous approved modifications shall be determined by the installer.	21/12/2006	Active	10014688
EASA.A.S.02852	SCANDINAVIAN AVIONICS DESIGN ApS			BOEING 737-500 BOEING 737-400 BOEING 707-300	Transponder S Mode Elementary and Enhanced Surveillance / Upgrade of existing dual diversity Transponder Mode S Installation		Engineering Order 2035168-EO Issue 2, dated 13.12.2006 or later approved revision.Declaration of Compliance 2035168-JS,dated 20.12.2006.Aircraft Flight Manual Supplement 2035168-JS-AM Issue 1, dated December 2006 or later approved revision.	Certification Basis of the change: CS 25 Amdt. 2, additionally JAA TGL 13 Rev. 1 (Mode S ELS), JAA TGL 18 (Mode S EHS, compliance to JAA NPA 20-12a shown voluntarily.This STC is approved only for the product configuration as defined in theapproved design data referred to in the paragraph "Descripti...	03/01/2007	Active	10014689
EASA.A.S.02853	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 650	Honeywell EGPWS MK VIII Installation		Engineering Order 2035914-EO Issue 2, dated 10-01-2007 or later approved revisions.Aircraft Flight Manual Supplement 2035914-AM Issue 1, dated January 2007 or later approved revisions.	Certification Basis of the Change: CS 25 Amendment 2, additionally JAA Leaflet No. 12 (TAWS).	13/02/2007	Active	10014690
EASA.A.S.02857	AVIONES, PIEZAS Y ACCESORIOS, S.L.			PA-31-325	Installation Dual integrated NAV/COMM/ GPS GARMIN 480 and Transponder GARMIN GTX 33 (APA OT 5001 Rev.1).		Supplement to Aircraft Flight Manual APA Document: SFM 5001Rev. 0Supplement Maintenance & Wiring Manual APA Document: SM&WM 5001 Rev. 0		05/02/2008	Active	10014692
EASA.A.S.02858	MOTORFLUG BADEN-BADEN GmbH			2. 200, 200C, 300, 300LW 1. B200, B200C, B300	Installation of Honeywell MK VI EGPWS and Avidyne TAS-620 TCAD.		To be installed in accordance with Aerotechnic modificationdocument ref 125204-01-1001 Rev 0 dated 15.11.2006 and 125204-01-1002 Rev 0 dated 10.10.2006, or later approved revision.To be operated in accordance with Aerotechnic Flight Manual Supplement ref 125204-01-0601 rev 2 dated 24.11.2006 and 12...		05/12/2006	Active	10014693
EASA.A.S.02861	SCANDINAVIAN AVIONICS DESIGN ApS			HAWKER 800 BAE 125 -800 SERIES	Installation of a Honeywell Class A Enhanced Ground Proximity Warning System EGPWS/TWAS for aircrafts equipped with a compatible MFD or weather radar display.		• Technical Order, Doc. No. 2036070-TO, issue 1, dated 13-Dec-2006, or later approved issue.• EASA approved Aircraft Flight Manual Supplement, Doc. No. 2036070-AM, Issue 2, dated December 2006, or later approved Issue.• Instructions for Continued Airworthiness, Doc. No. 2036070-CA, Issue 1,...	1. This change is limited to following configuration of theaircraft / equipment type:* Rockwell Collins EFIS 85/86 with ARINC 453 interface, and* Airdata system with ARINC 429 interface (TSO-C10b or C106), and* Rockwell Collins VIR-432 with ARINC 429 interface, and* Rockwell Collins ALT...	03/01/2007	Active	10014695
EASA.A.S.02864	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 757-200	Installation of B/C LOPA with standing bar tables		Change Number J438CMM J438/PR/016		08/03/2007	Active	10014697

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02865	SABENA TECHNICS BGC			A340 ALL MODELS	Installation of Aeromobile (ARINC/ Telenor Joint Venture) GSM Connectivity System.		1. Master Data List 0300-01-A-2103-R00;2. Certification Plan 0300-01-A-2101-R00;3. System Technical Specification 0300-01-A-2003-R02;4. Compliance Record 0300-01-A-2104-R01;5. Aircraft Flight Manual Supplement 0300-01-A-2301-R00;6. Instructions for continued A/W 0300-01-A-2211-R01....	1. The applicability of this STC is limited to the Airbus A340-313 and A340-541 and any other A340 shown to the identical A340-313 MSN 139 or A340-541 MSN 457, through the DOA's process as defined within the Document 0001-01-B-0914 (Classification of Modification Change Procedure for GSM Connecti...	05/03/2008	Active	10014698
EASA.A.S.02869	AERO-DIENST GMBH & CO. KG			31	TCAS-4000 / Dual TDR-94D Mode S Transponder Systems Installation (Collins)		EO 225-LR, rev. 2Certification Compliance Sheet AG626-075, rev. AAFM Supplement AG626-071, rev. IRInstructions for Continued Airworthiness AG626-085, rev. A		26/03/2007	Active	10014700
EASA.A.S.02870	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BEECH B200 SUPER KING AIR	Installation of a UASC Flight Management System (FMS) UNS-1L		Installation to be in accordance with AIEC Engineering Order ref CV631-062, rev. B dated 19/01/2007 or later approved revision.Operation to be in accordance with AIEC Aircraft Flight Manual Supplement ref CV631-071, rev IR dated 22/01/2007or later approved revision.Continued Airworthiness to be in...		24/01/2007	Active	10014701
EASA.A.S.02872	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 2		HAWKER HS 125-700 SERIES HAWKER 800 XP HAWKER 800	Mode S Transponder Upgrade for existing Collins transpondersystem.		Upgrade of existing Collins transponder system in accordance with:Document List 2036079 DOC andEngineering Order 2036079-EO.Operation in accordance with :Flight Manual Suppl. 2036079-AM-AFlight Manual Suppl. 2036079-AM-BContinuing Airworthiness 2036079-CA .	1. This STC approves only the installation of the parts contained in the above section “Description of Type Design Change”. This STC grants no operational approval to this installation, that will need to be obtained from the State of registry for the particular aircraft involved as defined in JAR OP...	06/03/2007	Active	10014702
EASA.A.S.02874	SCANDINAVIAN AVIONICS DESIGN ApS			FAIRCHILD SWEARINGEN SA 227-BC FAIRCHILD SWEARINGEN SA 227-AC FAIRCHILD SWEARINGEN SA 227 FAIRCHILD SWEARINGEN SA 226-TC	Installation of a Garmin GPS 400 System with Remote Annunciator Switch Panel in Fairchild Swearingen SA226-TC, SA227-AC, SA227 BC		Technical Order, Doc. No. 2036263-TO, issue 3 or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2036263-AM, Issue 2, dated December 2006, or later approved IssueInstructions for Continued Airworthiness, Doc. No. 2036263-CA, Issue 1, dated 16-Oct-2006, or later released...	This change is limited to following configuration of the aircraft / equipment type:- Airdata system must be either ARINC429, RS232 or Grey code as defined in the GPS 400 installation manual, and- any model of Rockwell Collins VIR-30/31/32 VOR/ILS	14/12/2006	Active	10014703
EASA.A.S.02875	AVIONES, PIEZAS Y ACCESORIOS, S.L.			MU-2B-35	Installation of New Avionics Equipment to comply with COM/NAV regulations for IFR and B-RNAV Operation.		New Supplement to Aircraft Flight Manual APA Document: SFM 6006 Rev. 2 (September 2006).Installation and Service instructionsAPA Document : OT 6006 Rev. 2 (September 2006).		10/12/2007	Active	10014704

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02876	AVIONIK STRAUBING ENTWICKLUNGS GmbH			B.65-90, 65-A90, B90, C90, E90 A. C90A	Dual Installation of COM/NAV/GS/GPS GNS430, with GDC31 RollSteering Converter; Installation of Stormscope WX500 and TCAS Avidyne TAS610.		• Installation must be in accordance with Master Document List Engineering Order No. ASR 2006-067-00 Rev. A dated 07-07-07 or later Approved Revisions.• Operation must be inaccordance with Flight Manual Supplement No. ASR 2006-067-01 to ASR 2006-067-06 Rev. A, or later approvedrevision.• M...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	12/07/2007	Active	10014705
EASA.A.S.02878	AERO-DIENST GMBH & CO. KG			31	FMS UNS-1L System Installation (UASC)		Engineering Order No. 226-LR, Rev. 1, dated 24.01.2007 or later approved revisions.Aircraft Flight Manual Supplement AG627-071, Rev. IR or later approved revisions.	Certification basis of the change FAR 25, additionally JAA Leaflet No. 10, Precision (RNAV), AMC 20-4 (Basic RNAV), AMC20-5 (GPS).	21/03/2007	Active	10014706
EASA.A.S.02882	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BAE 146/RJ SERIES BAE 146/AVRO 146 SERIES	Installation of Cockpit Door Locking System.The modification to the Cockpit Door provides the ability for the Cabin Crew to access the Cockpit in the case of Pilot Incapacitation.		- Tenencia Modification Ten 487 Issue 1.- Tenencia AFM Supplement 5 Issue 1 to the Bae 146/AVRO RJ Flight Manuals ref. TEN/ 146/005.	BAE Systems Modification HCM50303C.	12/12/2006	Active	10014710
EASA.A.S.02883	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BAE 146	Introduction of Hoenywell RDR-4B Weather Radar System		STC Twenty One Modification S21-34-25-1049STC Twenty One Master Document List S21.MDL-0240 Issue 1		10/07/2007	Active	10014711
EASA.A.S.02884	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	DORNIER 228-202K	Installation of Rockwell Collins TCAS 4000 system includingDual Mode SXPDR.		- Installation must be in accordance with Master Document List includedin the DesignChange Statement DC-0090, Iss.I, dated 28th March 2007, or laterapproved Revisions.- Operation must be in accordance with Pilots Operating HandbookSupplement No.FRAHIFMIO 113, Rev. 0, dated 28th March 2007 or later a...	1. Compatibility of this modification with other previouslyapprovedmodifications must bedetermined by the installer.2.This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraphs "Description" and "AssociatedTechnicalDocumentation". Com...	30/03/2007	Active	10043119
EASA.A.S.02885	LUFTHANSA TECHNIK AG			AIRBUS A300 MODEL B4-603	A300B4-603 Cabin Reconfiguration from current versions to Intercontinental LayoutCabin Reconfiguration from current versions (total 280 and 232 Passengers) to Intercontinental Layout (total 217 Passengers).		Compliance Record List CRL25-06/24M, Issue 1 dated 22 January 2007Supplemental Type Definition Document STDD25-06/24M, Issue 2 dated 22 January 2007	This STC is approved only for the product configuration as defined in the approved design data referred to in paragraph‘Description’.Compatibility with other aircraft/engine configurations shall be determined by the installer.	25/01/2007	Active	10014712
EASA.A.S.02887	DASSAULT FALCON SERVICE			FAN JET FALCON SERIES G FAN JET FALCON SERIES F FAN JET FALCON SERIES E FAN JET FALCON SERIES D FAN JET FALCON SERIES C	Incorporation of Runway Awareness and Advisory System (RAAS) Function on EGPWS Honeywell Mark V or Mark VII.		Compliance Checklist DFS2576-CCL Issue A1 or later approvedrevisions.Master Document List DFS-DE-17-F2-2576 Issue A1 or later approved revisions.Airplane Flight Manual SupplementDFS N°53 Revision original or later approved revisions for those aircraft previously incorporating EGPWS equipment not b...	This STC is approved for all Fan Jet Falcon all series and all Mystere Falcon 20-()5 aircraft with EGPWS Mark V or MarkVII software 224-224 and Terrain Database or later.Aircraftavionics required pre-installation as per DFS Change Approval Sheet DFS2576-CAS Issue A1 or later approved revisions.	18/07/2007	Active	10014714

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02890	LUFTHANSA TECHNIK AG			BOEING 767-300	Zonal Drying System Installation		Supplemental Type Definition Document STDD21-06-02M, Issue 01 rev 00, Feb 01/2008.Instructions for Continued Airworthiness CS21-0200-02 Rev IR, Nov 05/2007		11/02/2008	Active	10014715
EASA.A.S.02892	KUERZI AVIATION AG			PILATUS PC-12/45	Honeywell GNS-XLS FMS InstallationBy installing a single GNS-XLS Flight Management System with GPS and DME sensor.		Master Document List, Doc. No. MDL-200616263, Rev. N/CAFMS,Doc. No. FMS-200616263, Rev. N/ CInstructions for Continued Airworthiness, Doc. No. ICA-200616263, Rev. N/C	HB-FPI S/N 551. Valid for this S/N only.	23/04/2007	Active	10014716
EASA.A.S.02893	AIRTOURING LTD		CAA UK RESPONSIBILITY	TB 9, TB 10, TB 20, TB 21 TB 200 INCL. LL GT VERSIONS	Installation of Honeywell KGP560 Class B TAWS		Air Touring Modification AT_MOD_1104Flight Manual Supplement AT_FMS_1104 Issue A	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	12/12/2006	Active	10014717
EASA.A.S.02895	CZECH AIRLINES TECHNICS A.S.			AIRBUS A320-214	Cabin layout modification from 156 pax to 162 pax with seattype change /Removal of the existing seats for 156 passengers and doghouses, installation of new seats for 162 passengers, new doghouses, relocation and addition of PSU's as required, installation of additional attachments for Movable Class...		Modification No. M / 20 – 25 / 0002		19/03/2007	Active	10014718
EASA.A.S.02896	SOCIETE AIR FRANCE S.A.			BOEING 757-200	Installation of ATC Mode S Elementary and Enhanced Surveillance		Modification Definition File, MF-B757-06-001, Rev 00, Date23/03/2007AFM Supplement, AFMS-B757-06-001, Rev 00, 15/01/2007Instructions for Continued Airworthiness, ICA-B757-06-001, Rev 00, 03/01/2007	Certification basis as FAA TCDS A2NMIncluding:TGL 13 Rev 1,01/06/2003EASA AMC-20.13, 02/12/2005JAA TGM 21/07, 01/10/2003.	28/03/2007	Active	10014719
EASA.A.S.02897	LUFTHANSA TECHNIK AG			A330-300	Removal of Antenna and Receiver Transmit System and NetworkServices		- Supplemental Type Definition Document, Ref. STDD06/15M, Issue 1, Rev. 01 dated 31 May 2007Instructions for Continued Airworthiness, Ref. ICA-R-00-07/062, Rev. IR dated 10 April 2007	The AFM Supplement Doc. No. A-00-04/5856 can be removed with the installation of this STC.	31/05/2007	Active	10014720
EASA.A.S.02898	LUFTHANSA TECHNIK AG			AIRBUS A340-300	Removal of Antenna and Receiver Transmit System and NetworkServices		Supplemental Type Definition Document, Ref. STDD00-06/16M, Issue 01, Rev. 00 dated 1 June 2007.Instructions for Continued Airworthiness, Ref. R-00-07/064, Rev. IR dated 10 April 2007.	The AFM Supplement Doc. No. A-00-04/072 can be removed withthe installation of this STC.	19/06/2007	Active	10014721
EASA.A.S.02899	LUFTHANSA TECHNIK AG			AIRBUS A340-600	Removal of Antenna and Receiver Transmit System and NetworkServices.		Supplemental Type Definition Document, Ref. STDD00-06/17M, Issue 01, Rev. 00 dated 1 June 2007.Instructions for Continued Airworthiness, Ref. R-00-07/065, Rev. IR dated 10 April 2007.	The AFM Supplement Doc. No. A-00-04/133 can be removed withthe installation of this STC.	19/06/2007	Active	10014722

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02900	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	FOKKER F.27 MARK 700 FOKKER F.27 MARK 600 FOKKER F.27 MARK 500 FOKKER F.27 MARK 400 FOKKER F.27 MARK 300 FOKKER F.27 MARK 200 FOKKER F.27 MARK 100 FOKKER F.27 MARK 0604 FOKKER F.27 MARK 0502 FOKKER F.27 MARK 050	Introduction of Rockwell Collins Dual ADF-60 System in the F27 Mark 200. This installation replaces the existing BendixDual ADF System.In accordance with STC Twenty One Limited Master Drawing List document S21. MDL-0264 dated 14/12/2006 or later EASA approved revision.		Data Package containing the following documents, and additional supporting data:STC Twenty One Limited Master Drawing List document S21.MDL-0264.Certification Programme STC TwentyOne Limited document S21.PROG-0265.Compliance Record STC Twenty One Limited document S21.COMP-02654Compliance ChecklistE...	Instructions for Continued Airworthiness: STC Tewnty One Limited Change Supplement Manual document S21.TEC-0094 Revision 0, dated 21/03/2002, or later EASA approved revision.	20/06/2007	Active	10014723
EASA.A.S.02901	AVIATION DEFENSE SERVICE			FALCON 10	AVD-MDA10-34-060A: installation of EGPWS Mark VIII		See change approval sheet CAS AVD-MDA10-34-060A Ed. 1 Rev. 2 dtd. 13 November 2007 (configuration per MS AVD-MDA10-34-060A).AFM Supplement to AFM DTM 721, Supavd1 EGPWS FA10 rev. 01 dated June 12, 2007.Associated technical documentation.	Limitations iaw AFM Supplement Supavd1 to DTM 721 apply foroperation with EGPWS installation iaw AVD-MDA10-34-060A.TGL12 complied with.Cert basis FAR 25 Amdt 20.	26/11/2007	Active	10014724
EASA.A.S.02902	FRANCE AVIATION			BEECH F33	Installation and BRNAV approval of Garmin GNS-480.		Installation In accordance with France Aviation Modification ref FA 05/2006, and Technical Specification ref SF-05-2006-001.To be operated in accordance with France Aviation Flight Manual Supplement ref AFM-05-2006-001, Issue 1, dated 3/11/2006 or later approved revisions		05/12/2006	Active	10014725
EASA.A.S.02903	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA C650	Installation of Solid State Flight Data Recorder (SSFDR) F1000		Installation in accordance with Master Document Listref MDL-A/C-067 Rev 3 or later revisions.Operation in accordance with Flight Manual Supplementref AFM-060 Rev 3, or later revisions.Instructions for Continued Airworthinessref HB-A/C-711,Rev 2, or later revisions.		04/05/2007	Active	10014726
EASA.A.S.02906	JET AVIATION VIENNA GMBH			55C	Upgrade of the SSR Transponder System to Elementary (Enhanced) Surveillance)		Certification Program LX-55-ARS-001, initial issue AFM Supplement L55X-ARS34-001-M1-AFM, initial issue	s/n 55-135 and on	08/03/2007	Active	10014728
EASA.A.S.02907	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		CESSNA 560 (CITATION V) CESSNA 550 CITATION II CESSNA 550 BRAVO CESSNA 500, CITATION	Mode-S upgrade for existing Honeywell MST 67A transponder system.		Means of Compliance list 2036715 MOC.AFM Supplements -2036715-AMA for aircraft without Primus 1000 EFIS;2036715-AM B for aircraft with Primus 1000 EFIS.2036715-AM C for aircraft with Primus 1000 EFIS.System Description 2036715-DE,Engineering Order 2036715-EO issue 2 amended with Minor Change 203671...	N/A	03/04/2007	Active	10014729

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02909	AVIATION DEFENSE SERVICE	REV. 1		MYSTÈRE-FALCON 20	AVD-MDA20-95-057A: Activation of the SETHI 2 missionAVD-MDA20-95-054B: RAMHY Project - VHF/UHF Atenna		see Change Approval Sheet CAS AVD-MDA20-95-057A Ed.1 dtd. 21.6.07 or later approved revisions:see Change Approval SheetCAS AVD-MDA20-95-073A issue 1 dtd. 21.11.08 and associated technical documentation- AFM supplement SAFM FALC20 rev 15 dtd. 17.09.08 or later approved revisionsand associated techni...	1. This STC ensures proper isolation of Payload (SETHI Mission Equipment) from / return to - civil configuration in case of inadvertent activation.2. Activated SETHI Mission Equipment is not approved by EASA.3. Limitations iaw AFM Supplement SAFM-FALC20 to DTM 918 apply for operation with SETHI equi...	18/12/2008	Active	10014730
EASA.A.S.02913	COMPAGNIA GENERALE RIPRESEAEREES .p.A. - CGR S.p.A.			REIMS AVIATION CESSNA F-172 CESSNA 172P	CGR P001-00 "Structure & Exhaust System Modification for Camera Installation".		AFM Supplement CGR P001-00 ICA	Applicable to S/N 172-7631 only.	04/06/2008	Active	10014731
EASA.A.S.02914	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	CESSNA 560	Installation of Honeywell EGPWSCessna 560 G-PPLC ASN 560-0059		Phoenix Aviation Design Services Modification PADS/CP/1070.Phoenix Aviation Design Services Master Drawing List PADS/MDL/1070/001 Revision A.Phoenix Aviation Design Services AFM Supplement PADS/FMS/560/001 Revision B.	1. Restricted to G-PPLC ASN 560-00592. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibilitywith other aircraft/ engine configurations shall be determine...	24/01/2007	Active	10014732
EASA.A.S.02915	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	Mode S Transponder with enhanced surveillance capacity.		Master Document List DFS-DE-17-F5-5630 Issue A1 or later approved revisionsAircraft Flight Manual Supplement DFS Nº 56,Rev Original or later approved revisions.	This STC is approved only for those Mystere Falcon 50 aircraft equipped with two Collins TDR-94D(-007) Mode “S” ATC Transponders, “Flight Ident” source and without IRS and with one or two FMS’s.Compatibility with previous approved modifications shall be determined by the installer.JAA Leaflet TGL 13...	08/02/2007	Active	10014733
EASA.A.S.02918	AERODISA S.L.			MYSTERE FALCON 20	AED2006-14M: TAWS installation for Falcon 20.		Master Data List AED2006-14M_MDL Ed. 00, Rev. 3, dated 22-07-2007 or later EASA approved revisions.FM Supplement AED2006-14M_D03 Ed. 00,Rev. 2, dated 12-07-2007 or later EASA approved revisions.	See FM Supplement AED2006-14M_D03 Section II "Limitations".Certification basis: CS25 initial issue.TGL 12 complied with.SANDEL mandatory SB 3400-09 to be incorporated.	26/07/2007	Active	10014735
EASA.A.S.02919	E.I.S.A.	REV 1		CESSNA 525A	Installation of SAT-COM Antenna		EISA 01 SDL S120, EISA 01 STDD S120		24/01/2007	Orphaned	10014736
EASA.A.S.02921	JET AVIATION AG, BASEL			MYSTERE FALCON 50	MK-V EGPWS upgrade.		• Master Data List Doc No: BFA5034462-001.• AFMS Doc No: BFA5034462-201-01.	1. Required Avionics Configuration:• Collins ProLine II• Collins EFIS 84/85/86• Collins WXP 8502. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurat...	04/01/2007	Active	10014738
EASA.A.S.02922	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BEECH B300	Standby Instruments InstallationIn: 2" Revue Thommen Standby Altimeter & 2" Revue Thommen Airspeed Indicator & L3 Communications Standby Attitude Indicator AI-804with Goodrich JET Emergency Power Supply Battery Pack PS-835		CV 596-049		11/05/2007	Active	10014739

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02923	AIRTOURING LTD		CAA UK RESPONSIBILITY	B200	Installation of KGP560 TAWS and Dual GTX330D Mode S		Air Touring Mod Sheet AT_MOD_1105Compliance Record AT_CMRD_1105Flight Manual Supplements AT_FMS_1105 Rev A & AT_FMS_1105-1 Rev A or later EASA approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	05/03/2007	Active	10014740
EASA.A.S.02924	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH 1900D BEECH 1900C WET WING, AIRLINER BEECH 1900	Installation of an Executive Power System (EPS) with Inverter and Power Outlet.		• Installation Procedure: 2006-10-1 Rev. B.• AFM-Supplement: 2006-10-8 Rev.C.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	07/09/2007	Active	10014741
EASA.A.S.02925	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH 1900D BEECH 1900C, AIRLINER BEECH 1900	Installation of a Satcom System for Passenger Communication.		• Installation Procedure: 2006-9-1 Rev. B.• AFM-Supplement: 2006-9-8 Rev. A	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	07/09/2007	Active	10014742
EASA.A.S.02926	LUFTHANSA TECHNIK AG			BOMBARDIER CL-600-2B19	CL-600-2B19 Cabin Completion - 13 PAX		Supplemental Type Definition Document STDD00-06/11M, Issue 01, dated September 18, 2007 or later approved revisionAeroplane Flight Manual Supplement A-00-07/580-AFM, Issue 01, dated June 13, 2007 or later approved revision.Instructions forContinued Airworthiness A-00-07/639, Issue 01, dated AugustA...	1. Certification Basis of Change: JAR-25 Change 13, additionally:CRI D-01, Side-Facing DivanCRI D-04, Door between passenger compartment with integrated blocking functionalityCRI D-05, Isolated compartmentCRI F-01, Executive Power SystemJAA TGM Leaflet No. 17, Passenger Service and In-Flight Enterta...	19/09/2007	Active	10014743
EASA.A.S.02928	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH V35B	Modification d'installation BRNAV.		FAM 1348/06/SEAMAFM Supplement n° 1, revision 0, dated 8 December 2006	AFM Supplement n°1, revision 0, dated 8 December 2006 or any later approved revision must be on board.	14/07/2008	Active	10014745
EASA.A.S.02929	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BAE ATP	Lead Acid Battery Installation.		- TEN 494 Issue 4-Report TEN 494/CR Issue 2- Report TEN 494/1 Compliance Report Issue 1	1. Applicable only to aeroplanes that are fitted with anappropriately approved Class E Cargo Compartment used only for the carriage of cargo.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously...	27/01/2009	Active	10014746
EASA.A.S.02930	ELECTRONIQUE MAINTENANCE AVIATION			FAIRCHILD SWEARINGEN SA 226	Garmin GNS 530A VHF 8.33KHZ, Honeywell KY 196B VHF 8.33 KHZ, BF Goodrich TAS SKY 899 Installation		Airplane Flight Manual Supplement ref. T321-899 revision IR, dated August 19, 2003 or later approved revision.	This STC is limited to the SA226 S/N T312	26/02/2007	Active	10014747

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02933	AERODISA S.L.			MD-80 SERIES	LOPA for MD80 Series 168 Pax/ Layout passenger arrangement to allow 168 passengers capacity.		Master Data List AED 2006-12M_MDL, Ed. 1, Rev. Original, dated 10th May 2007.Maintenance Manual Supplement AED 2006-12M_MMS, Ed. 1, Rev. Original, dated 10th May 2007.InstallationManual AED 2006-12M_DIM, Ed. 1, Rev. Original, dated 10th May 2007.	The installation should not be incorporated in any other aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft.	31/05/2007	Active	10014748
EASA.A.S.02934	E.I.S. AIRCRAFT GmbH			CESSNA 525A CESSNA 525	Avionic Upgrade TO DUAL GTX 330D and installation of SAT-COM Antenna.		52C21000-91501, Rev.01, EASA approved AFM-Supplement "GARMIN GTX 330D Mode S Transponder"52C21001-91501, Rev. 02, EASA approved AFM-Supplement "SAT Antenna Iridium"		23/01/2007	Active	10014749
EASA.A.S.02935	JET AVIATION AG, BASEL			BOEING 727-200	Activation of RAAS on MK-V or MK-VII EGPWS with Softwareversion -218-218 or higher up to -226-226		Declaration of Compliance dated 21.02.2007Master Data List No. BB72734461-001AFM Supplement No. BB72734461-201-01	S/N 21824 as initial installationSTC Valid for B727-200 Series with EGPWS MK-V or MK-VII with Softwareversion -218-218or higher up to -226-226	14/03/2007	Active	10014750
EASA.A.S.02936	TRANSAIRCO S.A.			MYSTERE FALCON 900	MODE S TRANSPONDER WITH ENHANCED SURVEILLANCE CAPACITY		Master Certification Document List TSA F900-34.80.03 MCDL Rev. Original or later approved revisionsAirplane Flight Manual Supplement TSA F900-34.80.03AFMS, Rev. Original or later approved revisionsMaintenance Manual Supplement TSA F900-34.80.03MMS, Rev Original or later approved revisions	This STC is approved only for those Mystere Falcon MF-900 aircraft excluding Falcon 900C version and incorporating at least:• Dual Collins TDR-94D Mode “S” ATC Transponders compliant with Elementary Surveillance and• Single or dual GPS receiver.Compatibility with previous approved modification...	13/02/2007	Active	10014751
EASA.A.S.02940	AEROCONDOR TRANSPORTES AEREOS SGPS			SD3-60	Installation of TAWS		Certification Programme STC ATA0601. Issue: DOAFM - ATA.021J. 081.0601.01	As per AFM	26/03/2007	Active	10014754
EASA.A.S.02942	AERO-DIENST GMBH & CO. KG			BAE.125 SERIES 800B	TAWS ST3400 System Installation (Sandel)		Installation in accordance with Aero-Dienst Engineering Order ref 229-HW, Rev. IR dated 17. Jan. 2007, or later approved revision.To be operated in accordance with Aero-Dienst Airplane Flight Manual Supplement ref AG636-071, Rev IR or later approved revision.		13/04/2007	Active	10014755
EASA.A.S.02943	SCAI TECH (SOUDURE CHAUDRONNERIE ALU INOX)			F150L, F150M, FA150L, FA150M	SCAI-CE150-FM-A Echappement accorde avec silencieux double flux.		-AFM supplement SCAI-CE150-SUPMDV-A dated 4 May 2009.-Maintenance Manual supplement SCAI-CE150-MIM-A dated 4 May 2009.	Limitation to aircraft equipped with engine TCM 0-200-A andpropellerMcCauley 1A102/0CM6948.	02/06/2009	Active	10034639
EASA.A.S.02944	AEROTEC & CONCEPT			208, 208B	Video Mast Installation under Cessna 208.		Installation must be in accordance with Aerotec Master Document List 7606 MDL Rev. 02, dated 22-08-2007, or later approved revisions.Operations must be in accordance with Flight Manual Supplement Aerotec 7606 SAFM Rev. 01, dated 17-08-2007, or later approved revisions.Maintenance must be in accorda...		28/08/2007	Active	10014756

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02947	TENENCIA Ltd.		CAA UK RESPONSIBILITY	AIRBUS A300 MODEL B2 AIRBUS A300 B4	Installation of dual Universal UNS-1L or UNS-1K+ Flight Management System (FMS)This modification allows complying with Precision RNAV operations in designated European airspace.		Certification Report, ref : TEN 495 Issue 3Engineering Order, ref ECS 204775 revision Dor any later approved revisions of these documentsAircraft Flight Manual Supplement, ref : TEN/A300/001 issue 3Instruction for Continued Airworthiness, ref : ECS 205511 revision N/C	The installation of this STC has a prerequisite aircraft configuration.This STC is only applicable on aircraft :1. in which the following modifications have been embodied :- FAA STC ST01113CH, accepted by EASA under the grandfather rights ruling of the CAA UK Airworthiness Approval Notes, ref 27...	22/02/2008	Active	10014758
EASA.A.S.02948	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Upgrade of existing MST-67A Transponder System		Installation in accordance with Scandinavian Avionics Engineering Order ref 2036080-EO Issue 1, dated 22 December 2006,or later approved revisions.Aircraft to be operated in accordance with Scandinavian Avionics Flight Manual Supplement ref 2036080-AM-A or 2036080-AM-B as required, both at issue 1,...	As defined in Scandinavian Avionics Modification ref 2036080.	12/02/2007	Active	10014759
EASA.A.S.02950	AVIATION DEFENSE SERVICE			200	Installation of two 8.33 kHz VHF		None	This STC is limited to the S/N BB199 and BB920	04/04/2007	Active	10014760
EASA.A.S.02951	CESKA LETECKA SERVISNI A.S.			CESSNA 421C	Avionics Upgrade, Proj. No.: CLS-07-C421-AC147Replacement of existing obsolete transponder, altimeters, ELT and COM/NAVwith new that meets the current technical and operating requirements.		- Supplement to Flight Manual of Cessna 421C:Pilot's operating handbook supplement, issue August, 2007		15/10/2007	Active	10014761
EASA.A.S.02952	ATS INTERNATIONAL			A310	Elementary and Enhanced Surveillance installation on A310 aircraft.This STC has been developed for the Mode S elementary/enhanced surveillance installation on A310 aircraft.		System Technical Specification, ref : 0321-01-A-2003-R00Master Data List, ref : 0321-01-A-2103-R00(or any later approved revision)Aircraft Flight Manual Supplement, ref : 0321-01-A-2301-R00Instruction for Continued Airworthiness, ref : 0321-01-A-2211-R00	This STC is approved only for the product configuration as defined in the approved design data referred to in paragraph'Description'.Compatibility with other aircraft/engine configurations shall be determined by the installer.	02/04/2007	Active	10014762
EASA.A.S.02953	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 425	Replacement of one existing Transponder System by a Garmin GTX 330D Mode-S Transponder System		Engineering Order, Doc. No. 2037527-EO, Issue 3, dated 04-May-2007 or later approved issueEASA approved Aircraft FlightManual Supplement, Doc. No. 2037527-AM-A, Issue 1, dated 13-Apr-2007 or later approved issueand, if EHS capability is given:* approved Aircraft Flight Manual Supplement, Doc. No.20...	This change is limited to the configuration of aircraft / equipment type as listed under Item 4. in Engineering Order, Doc. No. 2037527-EO, Issue 3, dated 04-May-2007 or later approved issuePrior to installation of this modification the installer must determine that the interrelationship between thi...	11/05/2007	Active	10014763
EASA.A.S.02955	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BOEING 737	Installation of Mode S Transponders for Enhanced Surveillance.		Tenencia Report TEN 500, Issue 2, dated 4/05/07… Tenencia Report TEN 500/1, Issue 2, dated 4/05/07Flight Manual Supplement TEN/ B737/001, Issue 1	- Limited to installation on Boeing 737-82R S/N 29329 only.- The Operators Minimum Equipment List (MEL) should berevised to include the requirements for Mode S Transpondersand Elementary and Enhanced Surveillance in accordance withBoeing Aircraft Company Master Minimum Equipment List (MMEL)...	31/05/2007	Active	10014765

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02956	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	FAN JET FALCON, FAN JET FALCON	Non Capable Enhanced Mode S CEHS) Transponder Installation.Limitedenhancedsurveillance capacity restricted to a subsetof all required enhancedmode S parameters		• Design Change Statement DC-0097, Issue 2 or later approved revisions.• Airplane Flight Manual Supplement FRAH/FMII 08Revision I or laterapprovedrevisions.• Instructions for Continued Airworthiness ICA-0097 issue B or laterapproved revisions.	I. Fan Jet Falcon and Fan Jet Falcon Series D aircraft withtwo mode StranspondersRockwell Collins TDR-94D on board as per aircraft applicabilitydescribed in DesignChange Statement DC-0097 Issue 2 or later approved revisions.2. JAA LeafletTGL 13 Certification of Mode S Transponder Systems forElemen...	03/07/2007	Active	10043120
EASA.A.S.02957	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	DORNIER 228-202, SIN 8009,8112	Enhanced ATC Mode S: DornierQualification of existing Elementary Mode S A TC systems to EnhancedMode S requirementswithlimited DAP set.		- Design Change Statement: DC-0096 Issue 3- Ground Test Report: GTR-228-34-0020 Issue B/C- EASA approved Pilot's Operating Handbook Supplement No. FRAHIFM/0104Rev. I, forFairchildDomier 228 with FR Aviation Design Change DCOOOI, and DC0096,or laterapproved edition.- EASA approved Pilot's OperatingR...	I. Restricted to SIN 8009, 8112, and 8115.2. This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraphs "Description" and "AssociatedTechnicalDocumentation". Compatibility with other aircraft/engine configurationsshall bedetermined by t...	19/04/2007	Active	10043121
EASA.A.S.02958	RUAG AEROSPACE SERVICES GmbH			CESSNA CITATION 501	Installation of Honeywell Integrated Hazard Avoidance System (IHAS)		Master Doc. List: 162B-MDL, Engineering Order: 162B-EOEASA approved RUAG AFM-S Doc. No. 162B-AFMS, Rev. A, or later approved RevisionRUAG MM-S Doc. No. 162B-AMMS, Original issue, or later approved Revision	This installation does not comply to JAR OPS 1 operationalrequirements (Class B equipment), thus it is up to installer to comply with national commercial operational rules and requirements.	25/06/2007	Active	10014766
EASA.A.S.02959	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA S550, (CITIATION S/II) CESSNA 550 CITATION II CESSNA 500, CITATION	Installation of Honeywell Multi-Function Radar (MFRD) and an optional Honeywell Primus Radar System, if the existing radar is incompatible with the MFRD.		Compliance Record 2036716-EO, Issue 2AFM Supplement 2036716-AM, Issue 2Instructions for Continued Airworthiness 2036716-CA, Issue 1or later approved versions.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	16/02/2009	Active	10014767
EASA.A.S.02960	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	CESSNA 425	Installation of Traffic Advisory System		Lees Avionics Modification HL/MOD/799STC - Definition Document DD 799001 Issue 2AFM - AFMS 799001 Issue 1	As defined in the AFM supplement	08/03/2007	Active	10014768
EASA.A.S.02961	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	CESSNA 425	Installation of Garmin GNS 530 & GTX330		Lees Avionics Modification HL/MOD/800.STC Definition Document for HL/MOD/800.AFM Supplement AFMS 80001 Issue 1 for GNS 530.AFM Supplement AFMS 80002 Issue 1 for GTX 330 Mode S Transponder.	As per AFM Supplements.	08/03/2007	Active	10014769
EASA.A.S.02962	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	747-400	Interior Changes required on Cathay Pacific Boeing 747-400 for BE Aerospace Flight Structures.		BBJ Design Services Modification reference BBJ865.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	02/07/2007	Active	10014770
EASA.A.S.02963	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BOEING 757-200	Installation of Mode S Transponders for Enhanced Surveillance		Installation of Mode S Transponders (ref: TEN 501, Issue 1 20/03/2007) AFM Supplement (TEN/B757/001, Issue 1)	Certification Basis as per TCDS including:JAA TGL 13, revision 1, 01/06/2003EASA AMC 20-13, 22/12/2006	03/04/2007	Active	10014771

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02964	AVIONIK STRAUBING ENTWICKLUNGS GmbH			SA26-AT, SA26-T SA227-AT, SA227-TT SA226-AT, SA226-T, SA226-T(B)	Installation of Mode S XPDR Diversity Garmin GTX 330D with now top Antenna.		Doc. No. ASR 2006-073-MDL-01-00 Amendm. 00 dated 24/08/2007or later approved Revisions.Operation must be in accordancewith Avionik Straubing Flight Manual Supplement No. ASR 2006-073-FMS-05-00 Amendm. 00 dated 27/08/2007 or later approved versions.Maintenance must be in accordance with Avionik Str...	Prior to installation of this modification the installer msut determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	16/10/2007	Active	10014772
EASA.A.S.02965	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A	Installation of one Garmin GNS530 in a Cessna 525.		Installation must be in accordance with Avionik Straubing Master Document List Doc. No. ASR 2008-021-MDL-01-00 Amendm. 00 dated 01.04.08 or later Approved Revisions.Operation mustbe in accordance with Avionik Straubing Flight Manual Supplement No. ASR 2008-021-FMS-05-00 Amendm. 00 dated 26.03.08 or...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	19/09/2008	Active	10014773
EASA.A.S.02966	BBJ DESIGN SERVICES LIMITED		CAA UK RESPONSIBILITY	767-300	Installation of an in-seat power supply system and reconfiguration of business class seating.		BBJ MOD No. BBJ840 Issue 2 or later. Maintenance Manual Supplement BBJ MS057.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	30/05/2007	Active	10014774
EASA.A.S.02973	AIR ALLIANCE GmbH			TBM 700	Installation of Garmin GTX330D Transponder with Top Antenna.		• Installation and Maintenance Manual: 2006_002_2070_500Rev. 0• Flight Manual Supplement: 2006_002_2070_510 Rev.2	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	15/08/2007	Active	10014775
EASA.A.S.02974	AERODISA S.L.			PA-23-250	Upgrade of NAV/COM Equipment for IFR navigation.		Pilot's operating handbook supplement No.14, 15.	S/N: 27-7754134.	18/07/2007	Active	10014776
EASA.A.S.02975	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Installation of Honeywell TRA-45A Terrain Display/ Radio Altimeter Indicator.		Installation in accordance with Scandinavian Avionics Engineering Order Reference 2037690-EO Issue 2, dated 20 April 2007, or laterapproved revisions.Aircraft to be operated in accordance with Scandinavian Avionics Flight Manual SupplementReference 2037690-AM-A and 2037690-AM-B as required, both at...	Aircraft Serial No. 650-0037 with FOCA STC Z34-44-05 installed as defined in Scandinavian Avionics Modification Reference 2037690.	29/05/2007	Active	10014777

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02976	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Installation of Sandel ST3400 TAWS System.		Engineering Order, Doc. No. 2037448-EO, Issue 2, dated 07-March-2007 or later approved issue.EASA approved Aircraft Flight Manual Supplement, Doc. No. 2037448-AM-( ), Issue 2, dated 28 March 2007, or later approved revisions.STC Document List, Doc. No. 2037448 STC, Issue 1, dated 29 March 2007, or l...		04/04/2007	Active	10014778
EASA.A.S.02978	AEROCONDOR TRANSPORTES AEREOS SGPS			DORNIER 228-202	Installation of Honeywell TAWS Mark VI System with GPS Antenna Honeywell KA-92 and OAT Probe.		Definition Document ATA. 21J.81.0603.002.01, Issue 1.AFM Supplement No. ATA.21J.081.0603.010, Issue 1.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	08/08/2007	Active	10014780
EASA.A.S.02979	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	MD-11 EMBRAER ERJ 145 SERIES EMBRAER ERJ 135 SERIES BOEING DC-9 BOEING 767 BOEING 757 BOEING 747 BOEING 737 BOEING 727 BOEING 717 AIRBUS A320 SERIES	Installation of STG Aerospace SafTGlo Photoluminiscent Bulkhead/ Divider Exit Signs.		As listed in SWS Certification Ltd. Design report 3001-DR-001, Issue 1 or later EASA approved issue.	As defined in SWS Certification Ltd. Design report 3001-DR-001, Issue 1 or later EASA approved issue.	19/06/2007	Active	10014781
EASA.A.S.02981	AVIATION DEFENSE SERVICE			MYSTÈRE-FALCON 20 SERIES FAN JET FALCON SERIES	Enhanced Surveillance Mode S Transponder installation.		AvDef Modification Sheet N ° AVD-MDA-20-34-064A, Edition 01 Revision 03 dated 11 January 2008.Falcon 20 AFM Supplement AvDef N°1 Enhanced Mode S Installation issue 0 dated 8th January 2007.Or later approved revisions of these documents	Major change applicaable to aircraft Fan Jet Falcon and Falcon 20 serial numbers 076, 103 and 280 equipped with:- Integrated Collins Proline IV avionics suite.- DFS Elementary Mode S Transponder as per EASA.A.S.00203 STC.- AvDef Minor change EASA.A.C.05646 upgrade of IOC 4000 and upgrade of transpon...	16/01/2008	Active	10014783
EASA.A.S.02985	AERODATA AG			B300	Installation of EGPWS Mark VI Upgrade in B300.		Installation in accordance with Master Document Listref MDL-A/C-117 Rev 3 or later revisions.Operation in accordance with Flight Manual Supplementref AFM-084 Rev 0, or later revisions.Instructions for Continued Airworthinessref AMM-858, Rev 0, or later revisions.	Compatibility of this modification with other previously approved modifications must be determined by the installer.	16/04/2007	Active	10014785
EASA.A.S.02986	E.I.S.A.			FALCON 50	ADDITION OF ENHANCED SURVEILLANCE CAPACITY ON EXISTING ELEMENTARY MODE S TRANSPONDER INSTALLATION		Compliance Checklist EISA 05 CCL S119 Revision 2 or later approved revisions.Supplemental Type Certificate Data List EISA 05 SDL S119 Revision 2 or later approved revisions.Aircraft Flight Manual Supplement EISA 05 AFM S119 Option 1 revision 1 or later approved revisions and Aircraft Maintenance Man...	This STC is approved only for those Mystere Falcon 50 aircraft previously equipped to this modification with:• Option 1: Rockwell Collins Proline IV, FMS FMC-6000 and Mode S Elementary Surveillance Installation with Transponder RockwellCollins TDR 94D version -008, and• Option 2: FMS UNS-1L,s...	29/05/2007	Orphaned	10014786

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02987	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			PIPER PA-24-260	Installation modification B-RNAV Mid Continent MD41-1464A.		FAM SEAM No. 1144/06.AFMS Rev. 0, dated 22-05-2006.	Limited to S/N 24-4847 F-GKDA.	07/11/2007	Active	10014787
EASA.A.S.02988	A Y M AVIONICS, SL			SA226-TC	Installation of New Avionics Equipment.Transponders Mode S Filser Electronics TRT800H.		New Supplement to Aircraft Flight ManualA&M Avionics Document SMV 01/07 R0.Operating & Service InstructionsA&M AvionicsEngineering Bulletin BI 02/07 R0.		08/10/2007	Active	10014788
EASA.A.S.02990	TRANSAIRCO S.A.		FOCA STC 31-31-05	MYSTERE FALCON 20 F5 MYSTERE FALCON 20 C5, D5, E5 FAN JET FALCON SERIES C,D,E,F FAN JET	AVIONICA mini QARAVIONICA mini QUAR P/NNote: This STC supersedes FOCA STC FOCA 31-31-05, dated 09.09.2002		TSA Engineering Order TSA F20-31.62.01EO, Rev. A	1. Valid for Dassault Aviation:- Fan Jet Falcon Basic- Fan Jet Falcon Series C, D, E, F- Mystère-Falcon 20 Series C5, D5, E5, F52. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Docu...	23/01/2007	Active	10014789
EASA.A.S.02991	RUAG AEROSPACE SERVICES GmbH			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Upgrade of two Mode-S transponders Honeywell MST-67A by Honeywell SB to implement ELS/EHS transponder capability.ATC Controller KFS-578A is exchanged by Mode S ControllerPS-578A.New wires from the transponders to the FMS.		Document 185A-RFC	According to EUROCONTROL definition this equipment with approval EASA.A.S.02991 is non-EHS compliant.	05/04/2007	Active	10014790
EASA.A.S.02992	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (601-3R BOMBARDIER CL-600-2B16 (601-3A BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Honeywell MST-67A Transponder Mode-S ELS/EHS		RUAG Aerospace Services Master Drawing List 189A-MDL or later approved revision.RUAG Aerospace Services AFMS 189A-AFMS or later approved revision.		04/04/2007	Active	10014791
EASA.A.S.02993	VITROCISET S.p.A.	REV. 1	EASA.A.S. 02993	500, 550 SERIES	Installation of TAWS/RMI Sandel ST3440 Class A.Note: This STC supersedes EASA.A.S.02993.		AFM Supplement DRW No. 34-97-0105-0800-000 Rev. IR dated 20.12.2006 andsubsequent approved revisions.Master Drawing List DRW No. 34-97-0105-0000-000 Rev. IR dated 26.02.2007andsubsequent approved revisions.	This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraphs "Description" and "AssociatedTechnical Documentation".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This Certificate shall remain v...	07/01/2009	Active	10043122
EASA.A.S.02994	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2A12 (CL-601	Inflight Entertainment System (IFE) Sirius		RUAG Master Document List No. 189B-MDL, Rev A		29/05/2007	Active	10014792
EASA.A.S.02995	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)	REV 1		BEECH 400A	Upgrade of existing FID capable dual TDR-94D Mode S transponder system to enhanced surveillance capability by incorporation of Collins SB 502 and SB 507.		• Master Data List, Doc. No. CV649-049, Revision IR, dated 19 January 2007 or later approved revision.• Airplane Flight Manual Supplement, Doc. No. CV649-071, Revision IR, dated 16 January 2007 or later approved revision.• Engineering Order, Doc. No. CV649-092, Revision A, dated 23 March 20...	1. This change is limited to the configuration of aircraft / equipment type as listed under Item 1.2 in Engineering Order, Doc. No. CV649-062, Revision A, dated 23 March 2007, or later approved issue.2. This STC is approved only for the product configuration as defined in the approved design d...	04/04/2007	Active	10014793
EASA.A.S.02996	AEROTEC & CONCEPT			PA-31T (CHEYENNE)	Installation ATC mode S.		Master Data List ref. "STC groupe 2 n° 1407", revision 0, dated August 2, 2007 or later approved revision.	1. This STC is limited to the S/N: 7720036 and 8020037.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of thei...	10/09/2007	Active	10014794

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.02997	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH 100	Installation of 2 GNS430A, 2 GTX330D XPDR, 1KMR 675 and 1 GAD42.		Installation must be in accordance with S.E.A.M. MDL 1440-06/MDL/SEAM Ed.:1, Rév. 2, dated 29.06.07 or later Approved Revisions.Operation must be in accordance with S.E.A.M. Aircraft Flight Manual Supplement Supplément au Manuel de vol for GNS430 SEAM AFM 1440-06-01, Rev. 1, dated 29.06.07 and Supp...	Installation Limited to Beech B100, S/N. B-199 (F-GEXV).	20/07/2007	Active	10014795
EASA.A.S.02998	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			KING AIR 200	Installation of 2 GNS430A, 2 GTX330D XPDR and 1 GAD42.		Installation must be in accordance with S.E.A.M. MDL 1428-06/MDL/SEAM Ed.:1, Rév. 2, dated 29.06.07 or later Approved Revisions.Operation must be in accordance with S.E.A.M. Aircraft Flight Manual Supplement Supplément au Manuel de vol for GNS430 SEAM AFM 1428-06-01, Rev. 1, dated 29.06.07 and Supp...	Installation Limited to Beech B200, S/N. BL-11 (F-GRSO).	10/07/2007	Active	10014796
EASA.A.S.02999	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH 200	Installation of 2 GNS430A, 2GTX330D XPDR, Akmr, 1KMR 675 and 1 GAD42.		Installation must be in accordanc ewith S.E.A.M. MDL 1441-06/MDL/SEAM. Ed. 1, Rev. 1, dated 04-07-2007 or later approved revisions.Operations must be in accordance with S.E.A.M. Aircraft Flight Manual Supplement for GNS430 SEAM AFM 1441-06-01, Rev. 1, dated 29-06-2007 and Flight Manual Supplement fo...	Installation limited to Beech B200, S/N BB-622 (F-GHSV).	26/07/2007	Active	10014797
EASA.A.S.03002	AEROTEC & CONCEPT			PIPER PA-31T	Modification radio installation.		• Master Data List ref. "STC groupe 2 n° 1507", revision0, dated August 2, 2007 or later approved revision.• Airplane Flight Manual Supplement, ref. 1507-AFMS, revision 0, dated January 25, 2007 or later approved revision.	1. This STC is limited to the S/N 7720036.2. Prior toinstallation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthiness of the product. Thei...	10/09/2007	Active	10014799
EASA.A.S.03003	SCANDINAVIAN AVIONICS DESIGN ApS			SAAB SF340A SAAB 340B	Installation of Universal UNS-1L/K+, FMS-system.		AFM Supplement 2037470-AM, Issue 2, 19/03/2007.Continued Airworthiness 2037470-CA, Issue 1, 26/01/2007.Engineering Order 2037470-EO, Issue 2, 19/02/2007.	N/A	13/04/2007	Active	10014800
EASA.A.S.03004	LUFTHANSA TECHNIK AG			BOEING 737-900 BOEING 737-800 BOEING 737-700	ATC Mode S – Enhanced Surveillance Upgrade		- Supplemental Type Design Definition ST DD34-06/C3M Issue 1, Rev 1, dated 26th February 2007, or later EASA approved revision.- AFM Supplement LHT Doc number A-34-07/004-AFM, or later EASA approved revision.- Instructions for Continued Airworthiness Doc number R-34-07/040.	Compatibility of this design change with other previously approved modifications must be determined by the installer.	02/03/2007	Active	10014801

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03005	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525, 525A	Installation of Garmin GTX330D single/ dual.		Installation must be in accordance with Master Document List Engineering Order No. ASR 2007-006-00 Rev. 00 dated 25-01-07 or later Approved Revisions.Operation must be in accordance with Flight Manual Supplement No. ASR 2007-006-FMS-05.1-00 Rev. 00 dated 25-01-07 or later approvedrevision.	Limited to Cessna 525, SN 0001-0359.Compatibility of this modification with other previously approved modifications must be determined by the installer.	08/02/2007	Active	10014802
EASA.A.S.03006	HAWKER BEECHCRAFT Ltd.	REV. 1	CAA UK RESPONSIBILITY	HAWKER 850 XP	Introduction of Steep Approach Capability.		Modification SC0281A AFMS Hawker Beechcraft Supplement 1 issue 1 or later approved issue.		03/07/2007	Active	10014803
EASA.A.S.03010	KUERZI AVIATION AG			PILATUS PC-12/47	HF 1050 & AFFS Installation by installing a new HF-1050 HF COM System with a PS440 HF Control Panel and a new F5K AFFS (Automated Flight Following System).		Declaration of Compliance, Doc. No. DOC-200616236.Master Document List. Doc. No. MDL-200616236.AFMS for the HF-1050, Doc. No. FMS-200616236.1.AFMS for the F5K AFFS, Doc. No. FMS-200616236.	S/N 795 for initial installation.Approval valid for S/N 795and any other PC-12/47.	22/03/2007	Active	10014806
EASA.A.S.03011	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 551, CITIATIONII CESSNA 501, CITIATION	Installation of a Honeywell CAS 67A ACAS II System and a Dual MST 67A Mode S Transponder System		Engineering Order, Doc. No. 2038224-EO, Issue 2, dated 21-Mar-2007 or later approved issueEASA approved Aircraft FlightManual Supplement, Doc. No. 2038224-AM-A, Issue 1, dated 16-Mar-2007 or later approved issueand one of the following: * EASA approved Aircraft Flight Manual Supplement, Doc. No....	This change is limited to the configuration of aircraft / equipment type as listed under Item 4. in Engineering Order, Doc. No. 2038224-EO, Issue 2, dated 21-Mar-2007 or later approved issue.	03/04/2007	Active	10014807
EASA.A.S.03013	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B300C BEECH B300 BEECH 300LW BEECH 300 BEECH 200C BEECH 200	Installation of Universal UNS-1L (-1K+) FMS		Engineering Order, Doc. No. 2037417-EO, Issue 2, dated 09-Feb-2007 or later approved issueInstallation Document List (Certification Documents), Doc. No. 2037417 STC, Issue 2, dated 12-Feb-2007, or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2037417-AM, Issue 2, dat...	This change is limited to the configuration of aircraft / equipment type as listed under Item 4. in Engineering Order, Doc. No. 2037417-EO, Issue 2, dated 09-Feb-2007 or later approved issue.	13/02/2007	Active	10014809
EASA.A.S.03015	AVIONITEC AG			501	Replacement of XPDR to GARMIN GTX 330D Diversity Mode S andchange of GPS interface		Master Document List 063269-017, latest approved RevisonAvionitec AFM-S Doc. 063269-012 from 14. November 2007, or later EASA approved RevisionAvionitec AFM-S Doc. 063269-011 from7. November 2007, or later EASA approved RevisionAvionitec Instruction for continued airworthiness. 063269-015 from 06....		29/01/2008	Active	10014810

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03016	AVIONIK STRAUBING ENTWICKLUNGS GmbH			525A	Installation of single/ dual Garmin GTX 330DModel: Cessna 525A, S/N 0001 and on		ASR2007-009-TCP-06.00, ASR2007-009-MDL-01-01EASA approved AFM-S Doc. No. ASR2007-009-FMS-05.1-00, Issue 1, or later approved RevisionEASA approved AFM-S Doc. No. ASR2007-009-FMS-05.2-00, Issue 1, or later approved RevisionEASA approved AFM-S Doc. No. ASR2007-009-FMS-05.3-00, Org. Issue, or later app...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	21/06/2007	Active	10014811
EASA.A.S.03019	ELECTRONIQUE MAINTENANCE AVIATION			SA226-T, SA-226-AT,SA226-T(B)	Installation of Avionic Upgrade according EMA/07/001/SA226/VHF8.33-ATC-MFD-RDR		Master Doc. List. EMA/07/001/SA226/VHF8.33-ATC-MFD-RDR	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	30/04/2007	Active	10014812
EASA.A.S.03021	JET AVIATION VIENNA GMBH			560	Mode S Elementary/Enhanced Surveillance Upgrade		Declaration of Compliance C560-ARS34-001-M0-DOC,AFM Supplement C560-ARS34-001-M1-AFM,Compliance Report CR-C560-ARS34-001.	EHS compliance is partial. See AFM Supplement for Limitations.	27/03/2007	Active	10014813
EASA.A.S.03022	STC TWENTY ONE LIMITED	REV 2	CAA UK RESPONSIBILITY	BOMBARDIER CL-600-2B19	Introduction of Passenger Cabin interior.		1. STC 21 Master Document List No. 21.MDL-0316 Issue 1 dated 10 January 2008 or later approved revision.2. STC 21Flight Manual Supplement No. S21.FMS-0033 Issue 1 or later approved revision.	EASA STC No. EASA.IM.A.S. 01752 must be fitted.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The insta...	16/01/2009	Active	10014814
EASA.A.S.03023	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BOMBARDIER CL-600-2B16	Enhanced Surveillance Mode S Transponder Upgrade (Collins)		AEIC Modification AC652-015.AEIC MDL No. AC652-049 at Revision A dated March 7, 2007.AEIC AFM Supplement No. AC652-071 at Revision IR.	N/A	15/03/2007	Active	10014815
EASA.A.S.03024	AEROLITE AG			CL-600-2B16 (604 VARIANT)	3rd Stretcher and Cargo Platform. P/N 604489-501		Flight Manual Supplement: FMS-07-001Instructions for continued airworthiness and operations manual: OPM-07-002	S/N: 5529/5530/5540	20/06/2007	Active	10014816
EASA.A.S.03025	NORTHERN AVIONICS S.R.L.			PIPER PA-31T	Installation of Mode S Diversity XPDR Honeywell MST-67A (Elementary Surveillance).		Installation must be in accordance with Master Document List included in the Northern Avionics Modification Bulletin NAV-324 Rev.0 dated 1st March 2007 or later Approved Revisions.Operation must be in accordance with Northern Avionics Airplane Flight Manual Supplement No. AFM NAV-324 Rev. 0 dated 1s...		13/07/2007	Active	10014817
EASA.A.S.03029	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (CL-604	EASA Recertification of Cabin Modifications.		RUAG Master Document List No. 145G-MDL		18/10/2007	Active	10014819

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03030	DASSAULT FALCON SERVICE			MYSTÈRE-FALCON 200	Elementary and enhanced mode S transponder capabilities on existing dual MST-67A mode S transponder installation.		DFS Master Document List DFS-DE-17-F4-H268 Issue B1Mystere Falcon 200 AFM Supplement DFS 12 Original IssueMaintenance Manual Supplement :• Supplement 5-20/34 Revision 1• SMM34-95-05A2 and SMM 34-95-15A2 Revision 1or later approved revisions of these documents.	This STC is limited to all Mystere Falcon 200 aircraft equipped with two Mode S Transponders Honeywell MST–67A with antenna diversity as part of the original transponder installation plus two FMS Universal UNS-1() and two ADC 80 installed.See:Mystere Falcon 200 AFM Supplement DFS 12 Original IssueMa...	22/04/2008	Active	10014820
EASA.A.S.03031	COMPAGNIE FRANCE AVIATION			R2160	FA 07/2007 Edition 1 - Installation malonnier sur R2160	none	AFM-07 -2007 -003 dated 11 Sept 2008AMM-07 -2007 -001 dated13 Feb 2009	Limited to S/N 154	28/07/2009	Active	10033572
EASA.A.S.03034	SOCIETE AIR FRANCE S.A.			BOEING 767-300	Installation of Elementary Surveillance Dual ATS Mode S.		Air France Change Reference CAS-B767-04-001 Rev 1.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	26/02/2007	Active	10014822
EASA.A.S.03036	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 500, CITATION	Installation of a single diversity Mode-S transponderGarminGTX 330D and a new top antenna.		STC Document List 2036635 STCCompliance Record AMC 2036635-CRAFM Supplement ELS 2036635-AM-AAFM SupplementEHS 2036635-AM-B	According to EUROCONTROL definition this equipment with approval EASA.A.S.03036 is non-EHS compliant.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse...	06/06/2007	Active	10014823
EASA.A.S.03037	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE			BEECH 300C BEECH 300	FMS upgrade from UNS-1K to UNS-1K+ for compliance with P-RNAV		Master Data List, Doc. No. MDL.006.07, Revision 0, dated 03-Mar-2007, or later approved revisionEASA approved Airplane Flight Manual Supplement for Beech 300, Doc. No. UAE-AFMS-07-003, Revision 0, dated 08-Mar-2007, or later approved revision	This change is limited to the following serial numbersB300: S/N FL-111 thru FL-380; and FL-382B300C: S/N FM-9thru FM-11; and FN-2 and subsequentThis change is limited to the configuration of aircraft / equipment type as listed under Item I – ‘Description Detaillee’ in the Compliance Desig...	30/04/2007	Active	10014824
EASA.A.S.03038	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE	REV 1		BEECH 300C BEECH 300	Dual Installation of Collins TDR-94D with CTL-92E for compliance with Enhanced Surveillance capability.		Master Data List, Doc. No. MDL.007.07, Revision 3, dated 07-September-2007, or later approved revision.	This change is limited to the following serial numbers:B300: S/N FL-111 thru FL-380; and FL-382B300C: S/N FM-9 thru FM-11; and FN-2 and subsequent.This change is limited to the configuration of aircraft/equipment type as listed under Item I - Description Detaillee in the Compliance Design Document,P...	11/09/2007	Active	10014825
EASA.A.S.03039	JET AVIATION VIENNA GMBH			650	Mode S Elementary/Enhanced Surveillance Upgrade.		• Certification Report C650-ARS34-001.• Instructions for continued airworthiness C650-ARS34-001M1-IFCA.• AFM Supplement C650-ARS34-001-M1-AFM.• Engineering Bulletin EB-C650-ARS34-001.	1. Serial number : 650-7001 and on2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/ engine configurations shall be determinedy...	29/05/2007	Active	10014826

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03040	JET AVIATION VIENNA GMBH			650	Upgrade of a MkVI GPWS to a MkVII EGPWS		Certification Report C650-ARS34-002Instructions for Continued Airworthiness C650-ARS34-002M1-IFCAAFM Supplement C650-ARS34-002-M1AFM, Rev.1Engineering Bulletin EB-C650-ARS-002	Serial number: 650-7001 and on	29/05/2007	Active	10014827
EASA.A.S.03041	GULFSTREAM AEROSPACE Ltd.		CAA UK RESPONSIBILITY	GULFSTREAM GIV-X	EASA Certification of a number of FAA Major Alterations installed at original delivery.		Installation in accordance with GaeL modification No. GaeL 07/01, latest approved revision.Aircraft to be maintained inaccordance with Instructions for continued Airworthiness ref - CE41801A002 Rev. - 17/9/07, or later approved revisions.To be operated in accordance with the Cabin Operating Manual...	Aircraft GIV-X Serial No. 4004 only.	09/10/2007	Active	10014828
EASA.A.S.03042	MOTORFLUG BADEN-BADEN GmbH			550 BRAVO, 560, 560 XL 500, 550, S550, 560, 560XL	Installation of Honeywell MK VIII EGPWS.		Master Document List 125706-0109, Issue 1, or later approved revision.Instructions for Continued Airworthiness 125706-0701, Rev 0, dated 02.08.2007, or later approved revision.AFMSupplement 125706-0601, Rev 1, dated 17.08.2007, or later approved revision.		07/09/2007	Active	10014829
EASA.A.S.03045	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	BOEING B737-800	Installation of a Satcom Antenna for a GSM system on B737-800		H4A891 issue 3, or later EASA approved revision-H4ACP043 issue 3, or later EASA approved revision-Instruction for continued Airwhorthiness H4ADR259 Issue 1 or later EASA approved revision-Weight and Balance report H4AWB203 Issue 2, or later EASA approved revision.	As in Instrucions for Continued Airworthiness H4ADR259 Issue 1 or later EASA approved revision.	16/01/2008	Active	10014830
EASA.A.S.03046	BUSINESS AND COMMUTER AIRCRAFT			BEECH F90 BEECH E90 BEECH C90	Installation of dual Mode S transponder system (GARMIN GTX-330 or GTX-330D).		Installation in accordance with BCA Master Drawing List BCA95-00, Rev 0, dated 03/02/2007, or later approved revisions.To be operated in accordance with BCA Flight Manual Supplement ref BCA95-05, Rev 1, dated 05/14/2007, or later approved revisions.To be maintained in accordance with BCA Aircraft Ma...		22/05/2007	Active	10014831
EASA.A.S.03048	LUFTHANSA TECHNIK AG			LEARJET 31A	Navigation – Retrofit of Dual FMC		Compliance Record List CRL 34-07/01M, issue 1 (rev. 0)AFM Supplement LBAS310060301, issue IRInstruction for Continued Airworthiness LBAS310071201, issue IR (rev. 0)	None	02/04/2007	Active	10014833

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03050	ELECTRONIQUE MAINTENANCE AVIATION			BEECH 200	Installation of Garmin GTX330D Mode S Transponder.		Installation in accordance with EMA STC Data List Doc-No EMA/07/001/ BE200/ATC Mode S, Rev 1, or later approved RevisionsTo be operated in accordance with EISA Airplane Flight Manual Supplement Doc-No. 05 AFMS S128, Rev 0, or later approvedRevisionsTo be maintained i.a.w. EISA Maintenance Manual Doc...		21/04/2008	Active	10014834
EASA.A.S.03051	BUSINESS AND COMMUTER AIRCRAFT		EASA STC 2004-2474	CESSNA 500	Major Modification: change of a pilot HSI against EHSI ; re-wiring of existing equipment power supply to the emergency bus.Note: This EASA STC supersedes EASA STC 2004-2474.		Description: BCA35 Monopilote Citation I_Rev. 8,AFM Supplement: SMV BCA35_Rev 5,Master Drawing List: BCA35-00_Rev. 5,BCA35-7_Etude des cas de panne_Rev. 1	1. See original STC : DGAC-F nr. F-CIM81-SF-000102. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”.Compatibility with other aircraft/engine configurations shal...	02/03/2007	Active	10014835
EASA.A.S.03054	MT-PROPELLER ENTWICKLUNG GmbH			MOONEY M20J MOONEY M20F MOONEY M20E	Installation of propeller MTV-12-B/ 180-59b.		Airplane Flight Manual Supplement No. E-1469.Installation Instructions E-1470.Instructions to Continued Airworthiness E-1471.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	06/03/2007	Active	10014837
EASA.A.S.03055	NSE			M20K	Modification of radio electric installation for B-RNAV capacity with AP/FD coupling.		Modification file No. STC 18/2007.Flight Manual Supplement No. STC 18/2007 dated 6 March 2007.	Modification limited to serial number 250508AFMS must be onboard for any flight.	31/05/2007	Active	10014838
EASA.A.S.03056	FRANCE AVIATION			BEECH B200	Installation of Honeywell MST-67A Mode S Transponder.		Installation must be in accordance with France Aviation Master Data List Rev. 2, dated 13.06.07 or later Approved Revisions.Operation must be in accordance with France Aviation Aircraft Flight Manual Supplement AFM-01-2007-001 Rev.0 dated 16.04.07 or later approved revision.Maintenance must be in ac...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	18/06/2007	Active	10014839
EASA.A.S.03057	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	BOEING B737-300	TCAS II Installation		- Report JC/ER/1011, Issue 5, dated 23th May 2007 .- AFM Supplement, Report JC/FMS/005, Issue 1.1, dated 23-05-2007.- Instructions for continued airworthiness (ICA), TTF AerospaceDocument TTF-05T026-18 revision new, dated February 13, 2006 or later FAA accepted revision.	Limited to installation on Boeing 737-300 MSN 28740.Compatibility of this design change with other previously approved modifications must be determined by the installer.	29/05/2007	Active	10014840
EASA.A.S.03058	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	BOEING B737-300	Installation of Driessen Galley No 1		- Report JC/ER/1012, Issue 3, dated 15th May 2007	Limited to installation on Boeing 737-300 MSN 28740.Compatibility of this design change with other previously approved modifications must be determined by the installer.	31/05/2007	Active	10014841

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03059	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH B200	Installation of one GTX330D and one TDR94.		Installation must be in accordance with S.E.A.M. MDL 1587-07/MDL/SEAM Ed. 1, Rev. 0 dated 28.05.07 or later Approved Revisions.Operation must be in accordance with S.E.A.M. Aircraft Flight Manual Supplement for GTX330D et TDR94D Rev. 0 dated 28.03.07 or laterapproved revision.	Limited to Beechcraft B200 SN BB-1116, F-GDJS.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The instal...	31/05/2007	Active	10014842
EASA.A.S.03060	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	BOEING 767-306	Interior Changes for the B/E Aerospace First Class Seat Integration in the Forward Passenger Cabin.This modification removes the existing 16 off Weber Business class seats and installs 12 B/E Aerospace First Class Passenger Seats with Ottomans and Sideledges on a Boeing 767-300 for Privatair in the...		Modification Summary No. H4A887, Issue 1, dated 22nd May 2007.	1. Instructions for Continued Airworthiness, Ref. No. H4ADR238.2. This approval is limited to only the installation made in the Boeing Model B767-306, Serial Number 30393 aircraft.3. Prior to installation of this modification the installer must determine that the interrelationship between t...	19/06/2007	Active	10014843
EASA.A.S.03065	VITROCISET S.p.A.	REV. 1	EASA.A.S. 03065	SA 227	GPWS MKVI/VIII replacement with EGPWS MKVIjMKVIII Honeywell.Note: This STC supersedes EASA.A.S.03065.		AFM Supplement DRW No. 34-40-0706-0800-000 Rev. IR dated 09.02.2007 andsubsequent approved revisions.Master Drawing List DRW No. 34-40-0706-0000-000 Rev, IR dated 16.02.2007andsubsequent approved revisions.	This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraphs "Description" and "AssociatedTechnical Documentation".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This Certificate shall remain v...	07/01/2009	Active	10043124
EASA.A.S.03066	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			F500	Installation of a mode S GTX 330D Garmin Transponder.		AFM Supplement SEAM-1588/07 dated 18 July 2007.	Limitation to s/n 500-0319.	10/04/2008	Active	10014845
EASA.A.S.03067	AVIONITEC AG			PA-31T	Replacing of existing avionics by newer generation of avionics in accordance with Unit change overview Nr. 063247-050.		Installation must be in accordance with Avionitec Master Document List No. 63247-017 Rev. 1 dated 19 December 2007 or later approved revisions.Operation must be in accordance withAvionitec Airplane Flight Manual Supplement No. 063247-011 and 063247-012 dated 03 October 2007 and 063247-013 dated 26M...	Limited to S/N 31T-7904014	17/01/2008	Active	10014846
EASA.A.S.03069	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	Incorporation of Runway Awareness and Advisory System (RAAS) function on EGPWS Honeywell MK V.		• Compliance Checklist DFS 5633-CCL Issue A1 or later approved revisions.• Master Document List DFS-DE-17-F5-5633Issue A1 or later approved revisions.• Aircraft Flight Manual Supplement DFS Nº 54, Rev Original or later approved revisions for those aircraft with EGPWS Mk V soft 212-212 inst...	1. This STC is approved only for those Mystere Falcon 50aircraft equipped with a Honeywell EGPWS Mk V with Softwareversion 212-212 or later and with Proline Avionic Suite V6 with Terrain Display available; Terrain Database 435 or later is required (as per applicability detailed on DFS 5633-CAS2...	30/05/2007	Active	10014847
EASA.A.S.03072	AUSTRIAN AIRLINES AG	REV. 1		A320 AND A321 SERIES	Replace Airshow Digital Interface Unit (DIU) Model 210 by Model 420/This design change comprises the removal of Airshow210 Unit (P/N 910030 or P/N 910040) and installation of Airshow 420 Unit (P/N 921000, 921005 or 921006).		¿ Supplemental Type Definition Report, ref. STDR-A32F-23-0008-00, dated 02.08.2007 or later EASA approved revisions ¿ Declaration of Compliance, ref. DC-A32F-23-0008-00, dated 02.08.2007		21/01/2008	Active	10014850

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03076	AIRCRAFT INDUSTRIES, a.s.		CAA CZ STC--010	L 410 UVP-E20	Completion recorded parameters FDR BUR 1-2G for compliance with Brazilian regulation RBHA 135.152.		Supplement No. 81 to Flight Manual of L410 UVP-E20Supplement No. 108 to Maintenance Manual of L410 UVP-E, E9, E20Supplement No. 108 to Wiring Manual of L410 UVP-E, E9, E20	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	22/03/2007	Active	10014852
EASA.A.S.03077	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE			BEECH B300	Installation of a Digital Flight Data Recorder		Master Data List ref. MDL-012-07 revision 1, dated April 20, 2007 or later approved revisionAirplane Flight Manual Supplement ref. UAE-AFMS-07-003 revision IR, dated March 8, 2007or later approved revision	1. This STC is limited to the following S/N:Beech B300 S/N FL-111 through FL-380, FL-382Beech B300C S/N FM-9 throughFM-11, FN-2 and after2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously ins...	06/06/2007	Active	10014853
EASA.A.S.03079	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	767-300	Introduction of 25XF/188Y passenger configuration and associated customisation.		Modification summary (MOD-0187, Revision B, 26/03/2007)	Serial Number 24952 only.	14/06/2007	Active	10014855
EASA.A.S.03080	SELL GmbH	REV. 1		BOEING 777-300	Galley Reconfiguration and Replacement for Emirates Airlines		Sell Type Investigation Document MPD1023G-STC2N issue 1 dated 3 July 2007	Limited to B777-300 serial numbers: 28680, 28687, 29062, 29063, 29064, 29067, 29395, 29396, 32697, 32699, 32700, 32702	31/10/2007	Active	10014856
EASA.A.S.03082	AVIONITEC AG			PA-60-601P (AEROSTAR 601P)	Avionics retrofitOut. Radar system Bendix RDR-150; VHF-COM King KY-196; VHF-NAV King KN-53, Indicators KI-252A, KI-204,and KI-226; ADF system King KR-87 incl. Antenna KA-44B, obsolete ADF antenna Collins ANT-650A and adapter ADA-650, Moving map Eventide Argus-5000; A/P Adapter King KA-118; SlavingI...		AFM supplement No. 073301-011 Garmin GNS-530AFM supplement No. 073301-012 Bendix/ King KMH-880AFM supplement No. 073301-013 Sandel SN-3500	Reg.: HB-LIN S/N: 571-7963248/	08/10/2007	Active	10014858
EASA.A.S.03083	JET AVIATION AG, BASEL			BOMBARDIER BD-700-1A10	W-LAN Activation.By installing:A swivel dipole antenna in the cabin, a WLAN ON/ OFF switch and new wiring between the router, antenna and the HD-710.		• Declaration of Compliance, Doc. No. BGLEX23261.• Master Data List, Doc. No. BGLEX23261-001, Rev. A or latest approved revision.• AFMS, Doc. No. BGLEX23261-201-01, Rev. IR or latest approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	06/11/2007	Active	10014859
EASA.A.S.03084	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (CL-601 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Honeywell EGPWS MK VII		Modification: 076E-CNAFM: 076E-AFMS Rev N/C dated 16/04/07 or later approved revisionMM: 076E-EO		11/05/2007	Active	10014860
EASA.A.S.03085	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-1A11 (CL-600	ACSS Mode-S Transponder RCZ-852 - ELS/EHS		Modification: 076F-CNAFM: 076F-AFMS Rev N/C dated 19/04/2007 or later approved revisionMM: 076F-EO	With this modification now embodied the aircraft is non EHScompliant.	11/05/2007	Active	10014861
EASA.A.S.03086	SOGERMA SERVICES			AIRBUS A300 MODEL B2-1C	Replacement of the obsolete RCA weather radar by a Honeywell RDR-4B colour display radar system with predictive windshear function.		• Modification Approval Sheet, ref: SOG-34-2000 Issue 1,dated 10 May 2007• Aircraft Flight Manual Supplement, ref: AFM-SOG-A0-34-2000 Issue B	1. This STC is limited to the MSN 0032. This STC is approved only for the product configuration as defined in theapproved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/ engine configurations shall be determin...	29/05/2007	Active	10014862

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03088	AVIONITEC Ltd.			M20J	Installation of replaced Avionics according CP No. 073372		According to Avionitec Master Document List Doc. No. 073372-017 Rev. 1, or later RevisionsTo be operated in accordance with approved Avionitec AFM-S Document No. 073372-011, Original issue from 23.05.2008, or later approved RevisionsTo be maintained i.a.w. Avionitec ICA Document No. 073372-015, Orig...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	21/11/2008	Active	10014864
EASA.A.S.03089	SOCIETE AIR FRANCE S.A.			AIRBUS A340-300	A340 FINNAIR Cabin and IFE Upgrade		¿ Certification Program ref. doc. CP-A340-07-005, Rev. 3, dated 15th July 2008¿ Modification File, ref. doc. MF-A340-07-005, Rev. 0 dated 17th September 2008 ¿ Change Approval Sheet, ref. doc. CAS-A340-07-005, dated 17th September 2008 ¿ Instruction for Continued Airworthiness, ref. doc. I...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	18/09/2008	Active	10014865
EASA.A.S.03090	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Dual TAWS Sandel ST3400 - Class A		RUAG Master Document List No. 191D-MDL Revision A or later approved revision.RUAG Airplane Flight Manual Supplement No.191D-AFMS Revision A or later approved revision.		29/02/2008	Active	10014866
EASA.A.S.03091	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	BOEING B737-800	Installation of GSM Phone / SATCOM system on B737-800 aircraft.		Modification Summary Sheet: H4A911 Issue 3 or later EASA approved revision.Airplane Flight Manual Supplement: H4AFMS018 Rev. IR or later EASA approved revision.Additional Instructions for Continued Airworthiness: H4ADR331 or later EASA approved revision.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	12/12/2008	Active	10014867
EASA.A.S.03092	JET AVIATION AG, BASEL			AIRBUS A319-115	Wireless Local Area Network (WLAN) Activation.The modification includes the following:The antenna will be connected andthe WLAN will be activated.A "WLAN OFF" switch will be installed to switch the Wireless LAN functionality 'on' and 'off'.		• Master Data List, ref. BA31923261-001, Rev. IR, dated 08.08.07• Certification Plan, ref. BA31923261, Rev. E, dated 31.07.07• Certification Compliance Sheet, ref. BA31923261-102-01, Rev. A, dated 01.08.07• Airplane Flight Manual Supplement, ref. BA31923261-201-01, Rev. IR, dated 08.08.0...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	13/08/2007	Active	10014868
EASA.A.S.03094	LUFTHANSA TECHNIK AG			BOMBARDIER CL-600-2B19	Cabin Completion - 15 Passengers		- Lufthansa Technik Supplement Type Definition Document No. STD00-07/08M Issue 1 dated 26 February 2008 or later approved revision- Airplane Flight Manual Supplement No. A-00-07/694-AFM Issue 01 or later approved revision	1. Installation of "CL-600-2B19-Installation of Structural Provisions for Cabin Completion" approved with EASA STC No. EASA.A.S. 03097, is required prior to installation of thisSTC.2. The Limitation "Installation of Ferry-Kit M/S TC 601R16990" given on EASA STC No. EASA.A.S. 03097 is no longer...	11/03/2008	Active	10014869

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03095	LUFTHANSA TECHNIK AG			BOMBARDIER CL-600-2B19	Cabin Completion		Lufthansa Technik Supplemental Type Definition Document No.STDD00-07/07M Issue 01 dated 13/02/08 or later approved revision.Airplane Flight Manual Supplement No. A-00-07/693-AFM Issue 01 or later approved revision.	1. Installation of "CL-600-2B19 - Installation of structural provisions for cabin completion", approved with EASA STC No. EASA.A.S. 03097 is required prior to the installation of this STC.2. The limitation "Installation of Ferry-Kit M/S TC 601R16990" given on EASA STC No. EASA.A.S. 03097 is no l...	27/02/2008	Active	10014870
EASA.A.S.03096	LUFTHANSA TECHNIK AG			BOMBARDIER CL-600-2B19	Installation of Structural Provisions for AeroH Antenna system		LHT Declaration of Compliance No. 1613 dated 22 January 2008LHT Supplemental Type Definition Document No. STDD-07/06M dated 22 January 2008	1. For all flights with "Green Aircraft" and "Structural Provisions for AeroH Antenna System" (2,5 [kg]) installed the installationof Ferry-Kit M/S TC 601R16990 (867 [kg]) is necessary.2. With the installation of Ferry-Kit M/S TC 601R16990(867 [kg]) the aircraft will stay in C.G. envelope.3. Instal...	05/02/2008	Active	10014871
EASA.A.S.03097	LUFTHANSA TECHNIK AG			BOMBARDIER CL-600-2B19	Installation of Structural Provisions for Cabin Completion		LHT Declaration of Compliance No. 1611 dated 29 January 2008LHT Supplemental Type Definition Document No. STDD00-07/05M, Issue 1 dated 29 January 2008	11. For all flights with "Green Aircraft" and "Structural Provisions for cabin completion" (293,7 [kg]) installed the installation of Ferry-Kit M/S TC 601R16990 (867 [kg]) is necessary.2. With the installation of Ferry-Kit M/S TC 601R16990 (867 [kg]) the aircraft will stay in C.G. envelope.	05/02/2008	Active	10014872
EASA.A.S.03098	LUFTHANSA TECHNIK AG			AIRBUS A330-200	A330 - Installation of Zonal Drying System /The system is installed to get rid of the humidity between the cabin liningand the fuselage		- Supplemental Type Definition Document, Ref. STDD21-07/05M, Issue 01, dated 25 May 2007- Instructions for Continued Airworthiness, Ref. CS 21-0186-02, Issue 01, dated 17 April 2007		25/05/2007	Active	10014873
EASA.A.S.03099	AIRTOURING LTD		CAA UK RESPONSIBILITY	551	Installation of Avionic Upgrade		Air Touring Limited, Modification Sheet AT_MOD_1111.Flight Manual Supplements: AT_FMS_1111, Issue A and AT_FMS_1111-1, Issue A.Flight Manual Change Sheets: AT_FMC_1111-1, Issue A,AT_FMC_1111-2, Issue A and AT_FMC_1111-3, Issue A.	Requires prior embodiment of Gamma Support Services Minor Change GSSL-MIN-CJ551-202.	27/11/2007	Active	10014874
EASA.A.S.03100	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE			LOCKHEED JETSTAR 1329-A	Upgrade of ATC transponders for elementary surveillance (Mode S). To add elementary surveillance functionality in the ATC transponder and repalce KFS-578A control box by PS-578 tocomply the ECAC airspace requirements in accordance with Master Data List MDL-010-07, dated 11 May, 2007.		Data package containing the following documents, and additional supporting data:MDL-010-07 Master Data List Modification UAE-010-07.DDC-010-07 Compliance Design Document Modification UAE-010-07.UAE-CD-E-0008-07 Ground Test Functional Procedure for a Lockheed Jetstar.UAE-CD-E-0007-07 Flight Test Proc...	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.The installation of this modification by third persons is s...	06/09/2007	Active	10014875
EASA.A.S.03103	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	BOEING 767-300	The cabin reconfiguration of B767-300 Aircraft with Brice B1000S seats for TUI ARKEFLY/This modification removes the existing 260 economy class seats and installs 260 new Brice B1000s economy class seats in an identical passenger layout.		Modification Summary No. BBJ905, Issue 1, dated 16th May May 2007.	Continued Airworthiness Manual, Ref. No. ML3263, Rev. A.This approval is limited to only the installation made in the Boeing Models B767-300, S/N 24477, S/N 24847, S/N 24848 aircraft.	14/06/2007	Active	10014876

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03104	A Y M AVIONICS, SL			500	Installation of New Avionics Equipement.Transponder Mode S GARMIN GTX-330D.		New Supplement to Aircraft Flight Manual A&M Avionics Doucment SMV N ° 08/07 RO.Operating & Service Instructions A&M Avionics Engineering Bulletin BI N° 08/07 RO.		05/02/2008	Active	10014877
EASA.A.S.03105	KUERZI AVIATION AG			PIPER PA-31T	Installation of Dual Mode-S XPDR & TASInstallation of- Dual Mode S Transponder GTX-330D with diversity antenna.- Traffic Advisory System SKY497		Master Document List, Doc No. MDL-200716854	Reg. HB-LNLS/N: 31T-8020083Valid for this S/N only	11/05/2007	Active	10014878
EASA.A.S.03106	VITROCISET S.p.A.	REV. 2	EASA.A.S. 03106	MU-300	Installation of Honeywell MKVI EGPWS.Note: This STC supersedes EASAAS.03106 Revision 1.		- AFM Supplement DRW No. 34-97-0407-0800-000 Rev. IR and subsequentapprovedrevisions.Master Drawing List DRW No. 34-97-0407-0000-000 Rev. IR dated 2 July2007 andsubsequent approved revisions.	1. Leat B.M. No. 15/07 must be applied before the installation.2. Prior to installation of this modification the installer mustdetermine that theinterrelationship between this modification and any other previouslyinstalled modificationwillintroduce no adverse effect upon the airworthiness of the pr...	07/01/2009	Active	10043127
EASA.A.S.03107	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Mode S Upgrade of existing Honeywell Transponder System RCZ-833 to comply with ICAO requirements for Mode S ELS and EHS.Minor change to EASA.A.S. 03107:AFM Supplements for different Downlinked Aircraft Parameters.Mode S Upgrade of existing Honeywell Transponder System RCZ-833 to comply with ICAO requ...		Installation in accordance with Scandinavian Avionics Engineering Order ref 2037689-EO Issue 2, dated 2, May 2007, or later approved revisions.Aircraft to be operated in accordance with Scandinavian Avionics Flight Manual Supplement ref 2037689-AM-A or 2037689-AM-B as required, both at Issue 1, date...	As defined in Scandinavian Avionics Modification ref 2037689.As defined in Scandinavian Avionics Modification ref 2037689.	20/11/2007	Active	10014879
EASA.A.S.03108	RUAG AEROSPACE SERVICES GmbH			CESSNA CITATION CS 551 CESSNA CITATION 501	Installation of Dual Mode S XPDR MST-67A.Model: 501 S/N 0001 and on (Citation I-SP)551 S/N 0001 and on (Citation II-SP)		• Master Doc. List: 204A-MDL, Engineering Order: 204A-EO.• EASA approved RUAG AFM-S Doc. No. 204A-AFMS, Original Issue, or later approved Revision.• RUAG MM-S Doc. No. 204A-AMMS, Original issue, or later approved Revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	21/06/2007	Active	10014880
EASA.A.S.03110	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	737-300	Introduction of 138 Passenger Configuration and Associated Customizations		- Modification Summary MOD-0217 Rev A, dated 02 July 2007, or later EASA approved revision.- Aircraft Flight Manual in accordance with paragraph 3.4 of Modification Summary MOD-0217 Rev A, dated 02 July 2007, or later EASAapproved revision.- Weigh & Balance Manual in accordance with paragraph 3.7 of...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	20/09/2007	Active	10014882
EASA.A.S.03111	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	BOEING 737-500	Implementation of Interior Changes associated with the cabinreconfiguration from 124YC to 126YC.		Mod Summary H4A897 Iss. 2Instructions for Continued Airworthiness Doc. H4ADR383 Iss.1.	Prior to installation of this modification the installer must determine that theinterrelationship between this modification and any other previously installedmodification will introduce no adverse effect upon the airworthiness of theproduct.The installation of this modification by third persons is s...	10/06/2008	Active	10014883

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03113	KORFF LUFTFAHRT - RAINER KORFF			GROB G 109 B GROB G 109	Changes:- at the luggage compartment to be used as basis for instruments,- additional cable routing in the wings- reinforced attachment points at the lower side of both wings for under wing pots- reinforcements of the root tips- operation with external loads (wing gloves, flight log, under wing pods...		• Modification Bulletin "Änderung am Stück: für Grob G 109B, S/N 6219" dated February 15th 2006, prepared by companyKorff Luftfahrt for the STC (Major Change).• Flughandbuch: Anhang II "Messflugzeug" (Flight Manual Annex II)• Wartungshandbuch: Seite 24 (Maintenance Manual: Page 24).	1. Limted to S/N: 62192. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by the insta...	30/04/2007	Active	10014885
EASA.A.S.03114	MT-PROPELLER ENTWICKLUNG GmbH			CESSNA 421	Installation of 4-blade MT-Propeller Model MTV-16-1-E-C- F/CF225-37a propellers on Cessna 421 C.		Installation Instructions Document E-1585Mt-Propeller AFM-SDoc. No. E-1584, Original issue from 23. November 2007, or later EASA approved Revision.MT-Propeller Instructions for ContAW. Doc No. E-1386, Original issue from 23. November 2007, or later approved Revision.	Compliance has also been shown for all combinations (and/or) of following FAA STCs: SA438NW, SA5193NM, SA8352SW, SA00015SE, SA5811SW	18/12/2007	Active	10014886
EASA.A.S.03117	JET AVIATION AG, BASEL			AIRBUS A319-115	Water Tanks Installation/The modification includes the following:Installation of two additional water tanks in the AFT lower lobe area between frame FR62 and frame FR65 on the LH and RH side.		• Master Data List, ref. BA31938121-001, Rev. IR, dated 10.09.07• Certification Plan, ref. CP-BA31938121, Rev. C,dated 16.08.07• Certification Compliance Sheet, ref. BA31938121-102-01, Rev. C, dated 16.08.07• Instruction for Continued Airworthiness, ref. BA31938121-150-01, Rev. IR, date...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	14/09/2007	Active	10014888
EASA.A.S.03119	RUAG AEROSPACE SERVICES GmbH			DORNIER 328-300	Modification of rear-facing seat for use during T/O and Landing.Backrest support of the already certified VIP seats AMP2524..xxx is modified. The seats are now certified for T/O and landing in aft facing condition with a backrest support;ref. TSO-C127 dynamic tests.		Compliance Statement, Doc-Nr.: 155F-CSStress Report U155F530001Airplane Flight Manual Supplement, Doc-Nr.: 155F-AFMS		19/11/2007	Active	10014889
EASA.A.S.03120	RUAG AEROSPACE SERVICES GmbH			DORNIER 328-300	EASA Certification of Installed of Galley and Lavatory Water System.Certified earlier by AvCraft USA.Ref. FAA STC nr. 9993.		Compliance Statement, Doc-Nr.: 155G-CSMaster Document List, Doc-Nr.: 155G-MDLAirplane Flight Manual Supplement, Doc-Nr.: 155G-AFMS		13/11/2007	Active	10014890
EASA.A.S.03121	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2A12 (CL-601	EASA recertification of Cabin Modifications		RUAG Master Document List No. 191A-MDL Revision A or later approved revision.		29/02/2008	Active	10014891
EASA.A.S.03122	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2A12 (CL-601	EASA recertification of Avionics Modification		RUAG Master Document List No. 191B-MDL Initial Issue or later approved revision.RUAG Airplane Flight Manual Supplements:No. 191B-AFMS-TCASNo. 191B-AFMS-FMSNo. 191B-AFMS-COMMNo. 191B-AFMS-HFNo. 191B-AFMS-CVRNo. 191B-AFMS-DFDRat initial issue or later approved revision.		29/02/2008	Active	10014892

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03123	LUFTHANSA TECHNIK AG	REV 1		AIRBUS A319-100	PTU and/or Stretcher Installation on A319-100 /Optional replacement of seats by up to 2 Passenger Transport Units (PTU)and/or up to 4 stretchers.		- Supplemental Type Definition Document, ref. Doc. No. STDD25-07/01M, Issue 1, d ated 20.09.07, or later approvedrevisions- Airplane Flight Manual Supplement, ref. Doc. No. A-00-07/641-AFM, dated 20.09.07,or later approved revisions- Instruction for Continued Airworthiness, ref. Doc. A-...	• Detailed visual inspection of the Oxygen Discharge Plug at an interval of 750 FC (C check), as reported in the document Instruction for Continued Airworthiness, ref. Doc. A-00-07/641-ICA Issue 03, dated 19.09.07	01/10/2007	Active	10014893
EASA.A.S.03124	AIR ALPHA MAINTENANCE A/S			200	Replacement of ATC transponders with Rockwell Collins TDR-94 or TDR-94D Mode S systems for ELS and EHS. Installation oftop Antenna(s) CI110-660 or DMN 150-6.		Air Alpha EO-B200-34-104AFM Supplement: FMS.EO-200-34-104R1		23/07/2007	Orphaned	10014894
EASA.A.S.03125	RUAG AEROSPACE SERVICES GmbH			DORNIER 228-212	Adjustment of Special Fatigue Life.Model: Dornier 228-212, S/N 8181 and 8183		Supplemental Time Limits/ Maintenance Checks Manual for aircraft S/N 8181TM-STLMCM-8181-090707 Issue July 09/2007Supplemental Time Limits/Maintenance Checks Manual for aircraft S/N8183TM-STLMCM-8183-090707 Issue July 09/2007.	1. This STC is only applicable to aircraft S/N: 8181, 8183.2. Prior to installation of this modification the installer must determine that the interrelationship between thismodification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofi...	08/10/2007	Active	10014895
EASA.A.S.03126	AIRCRAFT INDUSTRIES, a.s.			Z-37A	Implementation of VFR-NIGHT kind of operation - installation of additionalm equipment ensuring the extension of currently approved kinds of operation to VFR-NIGHT kind of operation.		Supplement No. 2 to Flight Manual of Z-37A s/n 23-08.	Applicable for s/n 23-08 only.	23/07/2007	Active	10014896
EASA.A.S.03128	SABENA TECHNICS BGC			777-200, 777-300	Installation of Aeomobile GSM connectivity system.		Master Data List 0333-01-A-2103-R00Certification Plan 0333-01-A-2101-R00Compliance Record 0333-01-A-2104-R00Aircraft Flight Manual Supplement 0333-01-A-2301-R00Aircraft Flight Manual Supplement 0333-01-B-2301-R00Instruction for continued Airworthiness A/W 0333-01-A-2211-F01-R00	The applicability of this STC is limited to any Boeing 777-200 or B777-300 shown to be identical to Boeing 777-200 MSN27247 or Boeing 777-300 MSN 29063, through the DOA's process as defined within document 0001-01-B-0914 (Classification ofModification Change procedure for GSM connectivity System)....	26/05/2008	Active	10014898
EASA.A.S.03129	SOGERMA SERVICES			A310-325	Installation of ATC mode S Enhanced Surveillance (EHS)This Supplement Type Certificate consists in the installation of new ATC EHS in order to be compliant with the new ATC mode S'Enhanced Surveillance' regulation.		Modification Approval Sheet, ref : SOG-34-2005 issue 1, dated 13 July 2007AFM Supplement, ref : AFM-SOG-A1-34-2005 issue B, dated 02 May 2007Instruction for operation :Master Minimum Equipment List Supplement	1. This STC is limited to A310-325 aircraft model:- MSN 636- MSN 6442. Prior to installation of this modificationthe installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworth...	19/07/2007	Active	10014899
EASA.A.S.03130	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	737- 600, 700, 800, 900 737-200, 300, 400, 500,	Installation of Cabin Vu-123 Cabin Surveillance System.		MDL S21. MDL-0351 Issue 1, dated 21st January 2008 or laterEASA approved revisions.		23/01/2008	Active	10014900
EASA.A.S.03135	CESKA LETECKA SERVISNI A.S.			CESSNA 172S	Installation of the DME KN 62A, ADF KR-87 and XPDR KT-73		CSL-07-C172S-AC152-S1/4, Dated 27. August 2007CSL-07-C172S-AC152-S2/4, Dated 27. August 2007CSL-07-C172S-AC152-S3/4, Dated 27. August 2007CSL-07-C172S-AC152-S4/4, Dated 27. August2007		10/10/2007	Active	10014901
EASA.A.S.03137	ACI SYSTEMES			REIMS AVIATION CESSNA F 406	ACI-024 - Universal UNS-1L Installation - B-RNAV and P-RNAVCapability.		Flight Manual Supplement ACI-10-AFM-M-024-Rev3, Dated 14 September 2007.	F406 equipped with KCP220 Allied Signal AutoPilot.	10/10/2007	Orphaned	10014902

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03138	NSE			P210N	53/2006 - IFR B-RNAV certification extension of the GNS530 already installed.		Flight Manual Supplement 53/2006-AFMS Ed. 1 Rev. 1 dated 20September 2007.	STC Bayo 36/2006 must be already installed.The aricraft must be equipped with HSI KI525A and S-TEC 55X autopilot.	21/01/2008	Active	10014903
EASA.A.S.03139	JET AVIATION AG, BASEL			GULFSTREAM III	Super FMS Installation by:Removing the existing dual UNS-1Msp Flight Management System (FMS)andInstall a new dual UNS-1L Super Flight Management System (FMS)a DTU-100 Data Transfer Unit.		Master Data List, Doc No. BTAAW028-002, Rev A or latest approved revisionAFMS, Doc NO BTAAW028-201-07, Rev IR or latestapproved revision.	Reg.: TJ-AAW S/N 486Valid for this S/N only.	05/03/2008	Active	10014904
EASA.A.S.03140	ACI SYSTEMES			REIMS AVIATION CESSNA F 406	ACI-030 - Installation of an NAT NTX138 - FM Communication device.		-		08/10/2007	Orphaned	10014905
EASA.A.S.03151	E.I.S.A.			FALCON 10	MODE S TRANSPONDER WITH ENHANCED SURVEILLANCE CAPACITY				31/05/2007	Orphaned	10014908
EASA.A.S.03153	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	CESSNA 500	Approval of a Mode S EHS ATC System.		Tatenhill Aviation Limited Change TAL-TAD 020/07Flight Manual Supplement FMS.02007 Revision A or later EASA approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	10/07/2008	Active	10014909
EASA.A.S.03154	SCANDINAVIAN AVIONICS DESIGN ApS			LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35 LEARJET 31A LEARJET 31	Installation of a SANDEL ST3400 TAWS System (Class A)		See Scandinavian Avionics:• 2040484 STC (STC Document List)Issue 1, dated 12.2.2008• 2040484-EO Engineering Order Issue 2, dated 30.08.2007• 2040484-AM AFM Supplement Issue 2, dtd. 2.10.2007• 2040484-CA Instructions for Continued Airworthiness Issue 1, dtd.18.06.2007	Previous required aircraft configuration:All models equipped with:• Compatible Air Data Computers with ARINC 429 interface, and• Analogue Radio Altimeter interface (except ARINC 552) such asRockwell Collins ALT-50/50A , ALT-55 or HoneywellRT-200/300, and\ \File-2\cert\C1 PRODUCTS \LARGE AEROPLANES\x-...	22/02/2008	Active	10014910
EASA.A.S.03156	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)	REV 1		CESSNA 550 CITATION II	Honeywell ART 2000 Weather Radar transceiver/antenna installation interfacing with KMD 850 MFD to replace the existingRCA P-400 radar, to improve reliability and to add display of terrain and traffic graphics.		Master Data list 679-049,AFM Supplement 679-071,ICA 679-085 ICA.		22/01/2008	Active	10014912
EASA.A.S.03157	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)	REV 1		CESSNA 550 CITATION II	Honeywell EGPWS Mark VIII Sysem Installation,interfacing with KMD 850 MFD, as a replacement of the existing GPWS MK VI.		Master Data list 681-049 Rev. D,AFM Supplement 681-071,ICA 681-085 ICA, Rev. A.		22/01/2008	Active	10014913
EASA.A.S.03159	FRANCE AVIATION			PIPER PA-32	Rudder Hand Control installation for lower Limbs.The "SD1" system consists in a control for rudder that is handled by the pilot while seated in the LH (Left Hand) station. This "SD1" RHC system is mountained on existing manufacturing rudder system. The system can be easily removed (four screws).		Master Data List FA 25/2007 rev. 1 Dated 17/07/2007.Flight Manual Supplement AFM-25-2007-001 rev. 1 dated 17/07/2007.Instructions for Continued Airworthiness ICA-25-2007-001 rev. 0 dated 15/06/2007.		23/11/2007	Active	10014914
EASA.A.S.03160	JET AVIATION AG, BASEL			GV	Installation of bulkheads and door in the mid cabin.		Flight Manual Supplement doc no. GVCES002-201-02.	1. S/N: 669.2. Prior to installation of this modification the installer must determine that the interrelationshipbetween this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modificat...	19/10/2007	Active	10014915

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03162	AVIONITEC Ltd.			PA-28R-201T (TURBO ARROW III)	Replacing of existing avionics by newer generation of avionics in accordance with Unit change overview Nr. 073528-050, Rev 0, dated11.06.07.		Installation must be in accordance with Avionitec Master Document List No. 073528-017 Rev.0 dated 20. Dec. 2007 or later Approved Revisions.Operation must be in accordance with Avionitec Airplane Flight Manual Supplement No. 073528-011 dated 06. July. 2007 or later approved revision.Maintenance must...	Limited to S/N T21059922.	08/05/2008	Active	10014916
EASA.A.S.03163	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BEECH 200	Upgrade of dual Mode S transponder system TDR-94 to TDR-94Dwith ELS capability and diversity		Master Data List, Doc. No. 677-049, Rev. A, dated 09-Aug-2007, or later approved revisionEASA approved Airplane Flight Manual Supplement, Doc. No. 677-071, Initial Revision, dated15-Jun-2007, or later approved revisionInstructions for Continued Airworthiness, Doc. No. 677-085, Initial Revision, dat...	This change is limited to the configuration of aircraft / equipment type as listed under “1.2. Prerequisite Conditions”, in Engineering Order, Doc. No. 677-062, Initial Revision, dated 12-Jun-2007	14/08/2007	Active	10014917
EASA.A.S.03164	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOMBARDIER CL-600-2B16 (604)	Introduction of Passenger Cabin Interior.		STC 21 Master Document List No. S21.MDL-0360 at Issue 1 dated 19 August 2008 or later approved revision.STC 21 Flight Manual Supplement No. S21. FMS-0041 at Issue 1 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	25/08/2008	Active	10014918
EASA.A.S.03165	AIM AVIATION (JECCO) LIMITED		CAA UK RESPONSIBILITY	747-400	Virgin Atlantic Airways B747-400 CoCo Reconfiguration.		Major change MM373-07 Issue A and Appendix 1 Issue C, and, Master Drawing List DR1281-07, Issue 2, or later approved revisions.	The following EASA approved STC's must be installed concurrently with this design change:EASA.A.S. 02860EASA.IM.A.S.02572	09/10/2007	Active	10014919
EASA.A.S.03167	NSE			177RG	STC 42/2007 - Modification of radio electric installation for B-RNAV certification with AP coupling.		Airplane Flight Manual Supplement Ed1 Rev1, dated 20 September, 2007.	1. Aircraft must be equipped with HSI KI525A and S-TEC 60-2 autopilot;2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airwor...	08/02/2008	Active	10014920
EASA.A.S.03168	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Implementation of Automatic Dependant Surveillance – Broadcast in Non Radar Airspace capability (ADS-B NRA) on A300-600ST.This STC provide surveillance services in non-radar airspaces using ADS-B Out.ADS-B NRA is part of the Eurocontrol ‘Cascade’ project.		- Change Approval Sheet, ref: ST34MOD030 Issue 1 (Any later approved revision).- AFM Supplement ref: ST34MOD030, dated 12 November 2008.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	22/12/2008	Active	10014921
EASA.A.S.03169	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 650 CITATION III,VI,VII	Installation of Honeywell CAS-67A and RCZ-833 Mode S transponders.		1. Installed in accordance with Jet Aviation Installation Procedure defined in Engineering Order document ref. 2007-14-1;2. Operated in accordance with Aircraft Flight Manual Supplement (AFMS) ref. 2007-14-8;3. Instructions for continued airworthiness defined in Jet Aviation Document ref. M...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	01/02/2008	Active	10014922

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03170	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	CESSNA 500	Approval of a Mode S EHS ATC System.		Tatenhill Aviation Limited Change TAL-TAD 019/07Flight Manual Supplement FMS.01907 Revision A or later EASA approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	23/09/2008	Active	10014923
EASA.A.S.03173	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BOMBARDIER CL-600-2B16	Replacement of 3 FMS GPS Antennas (UASC)		AIEC Modification Reference AC684-015.AIEC Master Data List. Document Number AC684-049 Revision IR dated 6 July 2007 orlater approved revision.AIEC Instructions for Continued Airworthiness Document Number AC684-085 Revision IR dated 6 July 2007 or later approved revision.		04/09/2007	Active	10014925
EASA.A.S.03176	SOCIETE D'ETUDE ET DE GESTIONAERONAUTIQUE (SEGA)			BEECH 200	Installation of a support base for a stretcher.		Installation in accordance with SEGA Modification ref A-25-02-07-TwinJet, latest approved revision.Operation in accordance with SEGA Supplement Manuel de Vol Beech 200 ref FAM No A-25-02-07-TwinJet, dated May 2007, or later approved revision.		08/10/2007	Active	10014926
EASA.A.S.03177	SOCIETE D'ETUDE ET DE GESTIONAERONAUTIQUE (SEGA)			BEECH 90	Installation of a support base for a stretcher.		installation in accordance with SEGA Modification ref A-25-02-07-TwinJet, latest approved revision.Operation in accordance with SEGA Supplement Manuel de Vol Beech 90 ref. FAM No.A-02-02-07-TwinJet dated May 2007, or later approved revision.		08/10/2007	Active	10014927
EASA.A.S.03181	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BAE 146-200	SSR Mode S Enhanced Surveillance		Mod.No.BAC/146/100 Issue 1AFM FMS/486/42		16/08/2007	Active	10014928
EASA.A.S.03182	RUECKER AEROSPACE GmbH			AIRBUS A340-300	A340-300 new First Class Seats Test Aircraft /Installation of four newly developed First Class Seats in an Airbus A340-300 aircraft for testing.		¿ Master Document List, ref. Doc. No. MDL252-00001-000G,Issue G, dated 25.03.2008 ¿ Compliance Program, ref. Doc.No. CP_252-00001-000I, Issue I, dated 18.03.2008 ¿ Applicant's Declaration of Compliance - dated 25.03.2008		25/03/2008	Active	10014929
EASA.A.S.03184	AERODATA AG	REV. 1		300	Installation of an Aerodata Flight Inspection System AD-AFIS-230		EASA approved Master Document List, Doc. No. MDL-A/C-122, Revision 1, dated 15 October 2007, or later approved revision.EASA approved MOD-Order List, Doc. No. MOL-B300-11.01. Revision 0 dated 20 July 2007, or later approved revision.EASA approved Airplane Flight Manual Supplement, Doc. No. AFM-091,E...	Airplane must be equipped with Collins ProLine II to be eligible for this STC.	26/10/2007	Active	10014930

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03185	E.I.S. AIRCRAFT GmbH			BEECH C90KING AIR BEECH C90 A	Avionics Upgrade to Garmin GTX330D diversity Mode S Transponder.		Installation must be in accordance with EIS Aircraft GmbH Master Document List MDL 90C21002 Issue 06, dated 20.08.07 orlater Approved revisions.Operation must be in accordance with EIS Aircraft GmbH Flight Manual Supplement 90C21002-91501Issue 02, dated 20.08.07 or later approved revision.Maintena...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	21/08/2007	Active	10014931
EASA.A.S.03187	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BAE.125 SERIES 800B BAE.125 SERIES 800A	Upgrade of EGPWS MK V to RAAS capability.		EASA approved Master Data List, Doc. No. 687-049, Revision B, dated 18-Dec-2007, or later approved revisionEASA approved Airplane Flight Manual Supplement, Doc. No. 687-071, Revision A, dated 22-Oct-2007, or later approved revisionInstructions for Continued Airworthiness, Doc. No. 687-085, Revision...	This STC is limited to the configuration of aircraft / equipment type as listed under Item 2.1 Limitation, in Engineering Order, Doc. No. 687- 062, Revision B, dated 18-Dec-2007, or later approved revision.	10/01/2008	Active	10014932
EASA.A.S.03189	LUFTHANSA TECHNIK AG	REV 5		AIRBUS A318-112	A318 ELITE – RAK – Structural Floor Panel – SFP - Retrofit		• Supplemental Type Definition Document, ref. Doc. No. STDD00-07/14M, issue 09, dated 08 April 2009, or later approved revision• Aeroplane Flight Manual Supplement A-00-07/703-AFM revision 5, dated 30. September 2008, or later approved revision• Instructions for Continued Airworthiness, ref...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third pers...	08/04/2009	Active	10014934
EASA.A.S.03190	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-600-2B16 (601-3A	Installation of a Honeywell Bendix/King Radio KTR 909 System.		RUAG Aerospace Services Modifications Reference SE4-623b/2007-mo (078E-RFC).RUAG Aerospace Services Master Document List No. 078E-MDL.RUAG Aerospace Services AFM Supplement No. 078E-AFMS.	Restricted to ASN 5105.	10/10/2007	Active	10014935
EASA.A.S.03195	RUAG AEROSPACE SERVICES GmbH			BOMBARDIER CL-601-3A BOMBARDIER CL-600-1A11 (CL-600	Aircell Iridium Satcom, Axxcess EZ (Magnaster C-2000 replacement).		RUAG Master Document List No. 209B-MDL		21/08/2007	Active	10014938
EASA.A.S.03196	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			PIPER PA-23-250	Modification d'installation Radio/Couplage B-RNAV.Dépose: 2KX 175B+1 B.A. KMA 20+1 ADF KR85 + 1DLE KN65 + 1GPS 155XL + 1ATC KT 76 A.Pose: 1GNS 430 + 1KX 155 + 1B.Q. GMA 340 +1 ADFKR 87 + 1 DME KN 62A + 1 ATC GTX 330 + 1 MD41.		Fiche d'approbation de conception d'une Evolution SEAM N° 1665-07AFM supplément N°1 au manuel de vol, référence SEAM/ SMV/1665/07 révision 0 dated 03/07/07.	Limited to S/N 27-4727 F-GOPR.	07/11/2007	Active	10014939
EASA.A.S.03200	CESSNA ZURICH CITATION SERVICE CENTGMBH			CESSNA 560	EHS integration into Aircraft.By upgrading both existing RCZ-833E to RCZ-833K and integrated Mode S Transponder Module XS-852A to XS-852F, with the Honeywell Service Bulletin No. 7510700-23-6046.		Master Data List, Doc. MDL-055, Rev. IR or latest approved Revision.Flight Manual Supplement, Doc. No. FMS-028, Rev. IRor latest approved revision.Instruction for Continued Airworthiness, Doc. No. ICA-021, Rev. IR or latest approved revision.	Ref.: \-\ S/N:\Prerequisit equipment:- IC-600 CDG, P/N 7017000-80162- IC-600 CDG, P/N 7017000-81162-RCZ-833E ICU, P/N 7510700-866- RM-850 RMU, P/N 7012100-825- GNS-XL FMS, P/N 18355-0101-0101For aircrafts equipped with a CAS-67A TCAS II-TPU 67-A, P/N 066-01146-1211 (Software Change 7 incorporated)....	08/10/2007	Active	10014941

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03202	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.	REV. 1		PIPER PA-28R-201T	Installation modification B-RNAV.Installation of annunciation unit Mid Continent MD 41-1484.		1581-07, Rev. 1	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsL...	07/10/2008	Active	10014944
EASA.A.S.03205	KUERZI AVIATION AG			CESSNA 340A	Installation of a Traffic Advisory System:By installing a SKY497 Skywatch Traffic Advisory System with appropriate antenna. Traffic information will be displayed on existingsystems.		Master Document List, Doc. No. MDL-200717371.Declaration ofCompliance, Doc. No. DOC-200717371.AFMS, Doc. No. FMS-200717371, Rev. N/C or latest approved revision.		28/08/2007	Active	10014945
EASA.A.S.03206	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.	REV. 1	CAA UK RESPONSIBILITY	747-300	Installation of an Elementary Surveillance Mode-S System ina Boeing 747-30.		FMA-0234-031 Rev. 1 Flight Manual Supplement MCN 23410FMA 0234-032 Rev. 1 Flight Manual Supplement MCN 23751	FMA-234-031 Rev. 1 Flight Manual Supplement MCN 23410FMA 0234-032 Ref. Flight Manual Supplement MCN 23751This STC is approved only for the product configuration as defined in the approved design data. Compatibility with other aircraft/ engine configuration shall be determined by the installer.	02/11/2007	Active	10014946
EASA.A.S.03207	AIR ALLIANCE GmbH			PA-42 (CHEYENNE III) PA-42-720 (CHEYENNE IIIA) PA-42-1000 (CHEYENNE 400LS)	Installation of TCAS 9900 BX.		Installation Instruction 2007_009_2063_500 Rev. 0Air Alliance - Einbau Avidyne TAS 620 (9900BX) TCAD System AFM supplement.		06/12/2007	Active	10014947
EASA.A.S.03209	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Elementary/ Enhanced Surveillance Mode S ATC System.		Modification Summary MEO-0235 Rev. A.FMS No. 1 FMA-0235-033Rev. 1, dated 25-07-2007FMS No. 1 FMA-0235-034 Rev. 1, dated 25-07-2007FMS No. 1 FMA-0235-036 Rev. 1, dated 25-07-2007FMS No. 1 FMA-0235-05 Rev. 1, dated 25-07-2007		11/01/2008	Active	10014948
EASA.A.S.03219	RUAG AEROSPACE SERVICES GmbH			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	Honeywell EGPWS Mk VIIDescription: replacement of the existing GPWS Mk VII with a Honeywell EGPWS Mk VII. Terrain presentation on the EFIS MFD.Installation of indicators/switches in the instremental Panel.		Installation in accordance RUAG Master Document List Doc-No. 163C-MDL. Engineering Order Doc-No. 163C-EO, latest approved revisions.To be operated in accordance with RUAG AirplaneFlight Manual Supplement Doc-No. 163C-AFMS, latest approvedrevision.		08/10/2007	Active	10014954
EASA.A.S.03223	AERO-DIENST GMBH & CO. KG			35A	MFD-640 with WX Controller RP-1008 Installation (UASC)		AFM Supplement AG690-071, rev. IR (or later approved revisions)		04/12/2007	Active	10014955
EASA.A.S.03224	AERO-DIENST GMBH & CO. KG			35A	Cockpit Voice Recorder CVR-120 Installation (UASC).		AFM Supplement AG691-071, rev. A (or later approved revisions).		04/12/2007	Active	10014956
EASA.A.S.03227	SCANDINAVIAN AVIONICS DESIGN ApS	REV. 1		MD-90 MD-88 DC-9-87 (MD-87) DC-9-83 DC-9-82 DC-9-81 (MD-81) DC-9-50 SERIES DC-9-40 SERIES DC-9-30 SERIES DC-9-20 SERIES DC-9-10 SERIES	Mode S elementary and enhanced Upgrade of existing dual transponder system.		Certification doucments No. 2040410 DOC Issue 1 dated 27 June 2008AFMS No. 2040410-AM dated 20 February 2008Continued Airworthiness No. 2040410-CA Issue 1 dated 26 June 2008	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	24/07/2008	Active	10014957

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03230	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BAE 125 -800 SERIES	Modification of Collins Transponders to achieve Enhanced Surveillance Capability.		Installation in accordance with AIEC Engineering Order 666-062 latest approved revision.Aircraft to be operated in accordance AIEC Aircraft Flight Manual Supplement, Document ref 666-071 latest approved revision.Aircraft to be Maintained in accordance with AIEC Instructions for Continued Airworthine...	None.	10/09/2007	Active	10014959
EASA.A.S.03231	AIR AMBULANCE TECHNOLOGY GmbH			65-A90, C90	Installation of Air Medical Interior "Quick Conversion" Beech 65-A90, Beech C90, P/N 65-A90-25-20-15.000.		• AFM Beech 90 Supplement, Air Ambulance Equipment Beech90 P/N 65-A90-25-20-15.000, AFM AAT 46.• Component-, Installation-, Operation Manual, illustrated Part Catalog Beech90 Air Ambulance Equipment 90 P/N 90-25-20-15.000,CMM-Beech-AAT63.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	19/12/2007	Active	10014960
EASA.A.S.03232	RUECKER AEROSPACE GmbH			DORNIER 328-100	Installation of s 230VAC Euro standard power socketat both cockpit sidewalls.		MASTER Document List MDL-244-00200-000Compliance document F_DO-019/B of 21 March 2007Change Description numbered 6221070609		22/08/2007	Active	10014961
EASA.A.S.03233	AERO-DIENST GMBH & CO. KG			35A	Dual VHF NAV VIR-30/DME-40 replacement by VIR-32/DME-42 with Dual CTL-32 installation (Collins).		AFM Supplement AG692-071, rev. A (or later approved revisions).	N/A	04/12/2007	Active	10014962
EASA.A.S.03236	RUAG AEROSPACE SERVICES GmbH			BEECH F90	Avionics Installation, consisting of- Dual GNS430A VHF Com/GPS and NAV- Dual GAD42 Adapter for GNS430/RMI- Dual KMR675 Marker Beacon Receiver- EHS GTX330D Diversity Transponder and Transponder Top Antenna- GMX200 Traffic/Radar and JeppviewMFD Display- TAS620 Traffic System with Dual Antenna- Martec...		Installation in accordance with RUAG Master Document List Doc No. 210A MDL, Engineering Order Doc No. 210A EO, latest approved revisions.To be operated in accordance with RUAG Airplane Flight Manual Supplement Doc No. 210A AFMS, latest approved revision.	None.	12/12/2007	Active	10014964
EASA.A.S.03238	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 551 CESSNA 501	Dual installation of Transponder Mode S System, MST 67A with PS 550 or PS 578A Mode S Control Panel, with ELS and EHS capability.		EASA approved Engineering Order, Doc. No. 2041564-EO, Issue2, dated 13-Aug-2007 or later approved issueEASA approved Aircraft Flight Manual Supplement, Doc. No. 2041564-AM-A, Issue 1, dated 13-Aug-2007 or later approved issue for installation with PS 550 Control Panel, ELSEASA approved Aircraft Fli...	This change is limited to the configuration of aircraft / equipment type as listed under Item 4. in EASA approved Engineering Order, Doc. No. 2041564-EO, Issue 2, dated 13-Aug-2007 or later approved issue	26/09/2007	Active	10014965
EASA.A.S.03239	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	BEECH B200	RNA V GNSS Non-Precision Approach.		FR Aviation Design Change DC-O 119.FR Aviation AFM Supplements FRAH/FM/080 Revision I dated 23 August 2007andFRAHIFMIOI07 Revision 1 dated 23 August 2007.	Prior to installation of this modification the installer must determinethat the interrelationshipbetween this modification and any other previously installedmodification will introduce noadverse effect upon the airworthiness of the product. The installationof this modification bythird persons is sub...	06/09/2007	Active	10043129
EASA.A.S.03247	AERO-DIENST GMBH & CO. KG			35A	Enhanced Surveiilance Mode S Transponder modification (Collins).		AFM Supplement AG693-071, rev. A (or later approved revisions).		04/12/2007	Active	10014968
EASA.A.S.03248	AERO-DIENST GMBH & CO. KG			35A	Centre Pedestal Enlargement / Nose Compartment Rearrangement.		N/A		04/12/2007	Active	10014969

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03250	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH F90	Transponder ATC GTX330D, Radio/GPS GNS 530 and Radio/GPS GNS 430 installation.		File modification No 1609-07/FM/SEAM.	Modification limited to SN LA-19.AFMS 1609-07-01, 1609-07-02 and 1609-07-03 must be on board.	21/09/2007	Active	10014970
EASA.A.S.03253	LUFTHANSA TECHNIK AG			AIRBUS A340-212	WLAN InstallationDesign and implementation of Wireless Local Area Network System		¿ Supplemental Type Definition Document, ref. Doc. No. STDD23-07/05M, Issue 1, dated 10.10.07 or later approved revisions ¿ Airplane Flight Manual Supplement, ref. Doc. No. A-00-07/705-AFM, dated 26.09.07 or later approved revisions¿ Instruction for Continued Airworthiness, ref. Doc. CS23-15...		11/10/2007	Active	10014972
EASA.A.S.03258	JET AVIATION AG, BASEL			BOEING 737-700 IGW					15/07/2009	Active	10029053
EASA.A.S.03260	KUERZI AVIATION AG			PILATUS PC-12/47	FMS and DME installation:By installinga new GNS-XLS FMSa new DM-441B DME		Master Document List, Doc. No. MDL-200717475, Rev. N/C or latest approved Revision.AFMS, Doc. No. FMS-200717475, Rev. N/C or latest approved Revision.Instruction for continued Ariworthiness, Doc No. ICA-200717475, Rev. N/C or latest approved Revision.		26/11/2007	Active	10014974
EASA.A.S.03265	JET AVIATION AG, BASEL			MYSTERE FALCON 50	Triple FMS Upgrade to UNS-1F		• Master Data List BOHIT039-002 Rev. E, dated 07th December 2007.• Airplane Flight Manual (AFM) Supplement BOHIT039-201-13, Rev. IR, dated 14th November 2007• Instructions for Continued Airworthiness BOHIT039-150-13, Revision B, dated 09th October 2007• Engineering Order BOHIT039-346200o...	1. Mystere Falcon MF 50 Serial Number 222See:• Airplane Flight Manual (AFM) Supplement BOHIT039-201-13, Rev. IR, dated 14th November 2007.• Instructions for Continued Airworthiness BOHIT039-150-13, Revision B, dated 09th October 2007,Or later approved revisions of these documents2. Prior...	17/12/2007	Active	10014977
EASA.A.S.03267	JET AVIATION AG, BASEL			FALCON MF 50 MYSTERE	Interior Modifications.		Master Data List BOHIT039-001 Rev. DOperation Instructions BOHIT039-202-11 Rev. IRInstructions for Continued Airworthiness BOHIT039-150-11 Revision AEngineering Order BOHIT039-250000 Rev. AOr any later approved revisions ot these documents.	Mystère Falcon MF 50 Serial Number 2222SeeOperations Instructions BOHIT039-202-11 Rev. IRInstructions for Continued Airworthiness BOHIT039-150-11 Revision A	17/10/2007	Active	10014978
EASA.A.S.03269	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	F406	Installation of new Avionics.		Phoenix Aviation Design Services Ltd. Change PADS/CP/1098.Flight Manual Supplements:PADS/FMS/F406/001PADS/FMS/F406/002PADS/FMS/F406/003	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	30/01/2008	Active	10014979

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03272	EADS ELBE FLUGZEUGWERKE GmbH			AIRBUS A310-304	A310-304 Cabin ReconfigurationTransfer of the STC holder, from ASL Aircraft Services Lemwerder GmbH to EADS Elbe Flugzeugwerke GmbH.Former LBA STC ref TA0721Cabin Reconfiguration from 265 seats to 225 seats (18 Business Class + 207 EconomyClass).		Certification Report, ref : ASL CR 310-25-0001, dated 11 April 2003	1. This STC is limited to A310-304 aircraft model MSN 448.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthiness of the prod...	08/10/2007	Active	10014980
EASA.A.S.03273	EADS ELBE FLUGZEUGWERKE GmbH			AIRBUS A310-304	A310-304 Floor Path Marking System installationTransfer of the STC holder, from ASL Aircraft Services Lemwerder GmbH toEADS Elbe Flugzeugwerke GmbH.Former LBA STC ref TA0719The modification related to this supplement concerns the installation of a photoluminescent emergency escape path marking.		Certification Report, ref : ASL CR 310-33-0001, dated 10 April 2003Aircraft Flight Manual Supplement, ref : AFMS310330001, dated 06 March 2003	1. This STC is limited to A310-304 aircraft model MSN 448.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthiness of the prod...	08/10/2007	Active	10014981
EASA.A.S.03274	EADS ELBE FLUGZEUGWERKE GmbH			AIRBUS A320-214	A320-214 Cabin ReconfigurationTransfer of the STC holder, from ASL Aircraft Services Lemwerder GmbH to EADS Elbe Flugzeugwerke GmbH.Former LBA STC ref TA0717 Issue 2Cabin Reconfiguration from 156 seats (90 Business Class + 66 Economic Class) to 180 seats (Economy Class).		Certification Report, ref: ASL CR 320-25-0001 Revision B, dated 20 May 2003	1. This STC is limited to A320-214 aircraft model MSN 1081 and MSN 1370.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthine...	08/10/2007	Active	10014982
EASA.A.S.03275	AEROLITE AG			MD-11	Modification of two SICMA Mono F/C Seat Type 17011(X)1-(XX)as detailed in Lufthansa Supplemental Type Definition Document STDD 25-05/32 R02 and in accordance with Aerolite BucherMaster Document List MDL-06-015 Rev. B for installation in MD-11 MSN48533.		MDL-06-015 Rev. B Master Document ListIM-07-006 Installation Manual VVIP Seat Installation.	It is the responsibility of the installer to make sure thatthis installation is certified for the use in effective aircraft.Compliance with the following Cabin Safety requirements is not covered by this approval:1. FAR/JAR 25.791 Passenger information signs and placards2. FAR/ JAR 25.812(a)(1)...	16/11/2007	Active	10014983
EASA.A.S.03276	CHRISTEN-AIRTECH AG			CESSNA P210N	Avionics RetrofitOut: King KMA-24; Sigtronics SPA-400; DualKing KY-196; Dual King KN-53; King KI-525A; trimble TNL-2000; King KT-76A; ARGUS-5000; BF Goodrich WX-1000In: Garmin GMA-347; Dual Garmin GNS-430; Garmin GTX-330; Garmin GMX-200; L-3 WX-500; Sandel SN-3500 L-3 SKY-497; Avionics Master By-Pa...		Master Document List No.: 207.1603-EOMDL-01-00AFM Supplement GNS-430 No. 1: Doc. No.: 207.1603-FS-01-00AFM Supplement GNS-430 No. 2; Doc.No: 207.1603-FS-02-00	Reg: HB-CZK S/N: P21-00860	24/01/2008	Active	10014984
EASA.A.S.03277	AEROTEC & CONCEPT			BN2T	Survey Capacity on BN-2T		Modification file 7307 according Drawing List No. 7307DL, revision 00, dated 25 August 2007Installation Manual No. 7606-IM, revision 00, dated 5 February 2008Instructions for Continued Airworthiness, revision 00, dated 26 January 2008Supplemental Airplane Maintenance Manual, revision 00, dated 25 J...	Supplemental Airplane Flight Manual, revision 00, dated 17 January 2008, or later approved revision must be on board when modification is installed.Instruction for Continued Airworthiness, revision 00, dated 26 January 2008 and Supplemental Airplane Maintenance Manual, revision 00, dated 25 January...	08/04/2008	Active	10014985
EASA.A.S.03278	AVIONITEC Ltd.	REV. 1		WA 4/21	Avionics TetrofitOut: King Mode A/C Transponder KT-76A, king Audio Panel KMA-24, Autopilot Badin Crouzet.In: Garmin Mode S Transponder GTX-330, Garmin Audio Panel GMA-340, Autopilot S-Tec System 55X.		Master Document List No. 042220-MDL.AFM Supplement No. 042220-AFMS.	Reg.: HB-DCE, S/N 420.	06/09/2007	Active	10014986

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03280	CHRISTEN-AIRTECH AG			CESSNA P210N	Avionics Upgradeby removing:1. GPS-155 GPS2. KX-165 COM/NAV 13. KX-155 COM/NAV 24. WX-8 Stormscope5. KMA-24 Audio Paneland installing:1. GNS-530 COM/NAV/GPS 12. GNS-430 COM/NAV/GPS 23. WX-500 Stormscope4. GMA-347Audio Panel		1. Declaration of Compliance, Doc. No. 207.1599-DC-01-002. Master Document List, Doc. No. 207.1599, Rev. 0 or latest approved Revision3. AFMS, Doc. No. 207.1599-FS-01-01,Rev. 1 or latest approved Revision4. AFMS, Doc. No. 207.1599-FS-02-00, Rev. 0 or latest approved Revision	1. Reg.: HB-CHJ S/N: P210-0522. Valid for this S/N Only.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modificationwill introduce no adverse effect upon the airworthiness of t...	06/11/2007	Active	10014987
EASA.A.S.03281	AIR ALLIANCE GmbH			PA-31T (CHEYENNE/ CHEYENNE II)	Installation of Avionic Upgrade according MDL 2007_019_2029AA Form 1 Rev. 0.		Installation Instruction 2007_019_2039_500, Rev. 2Air Alliance AFM-S Doc. No 2007_019_2039_510, Original issue from 6. November 2007, or later EASA approved RevisionAir Alliance AFM-S Doc. No 2007_019_2039_511, Original issue from 6. November 2007, or later EASA approved RevisionAir Alliance AFM-S D...		10/01/2008	Active	10014988
EASA.A.S.03284	CESKA LETECKA SERVISNI A.S.			LETECKE ZAVODY L-410-UVP-E13	Installation of ACAS II system with XPDR (MST-67A) and ELT defined in document CLS-05-L410-AC125, revision 02 dated 04.11.2005		CLS-05-L410-AC125, revision 02 dated 04.11.2005	This STC is valid only for L410-UVP-E13 aircraft type, registration OK-UDS, S/N 892321	05/11/2007	Active	10014989
EASA.A.S.03285	CESKA LETECKA SERVISNI A.S.			LETECKE ZAVODY L-410-UVP	Installation of NAV/COM/GPS as defined in document CLS-06-6410-AC140, issue 0, revision 2 dated 13.09.2006		CLS-06-6410-AC140, issue 0, revision 2 dated 13.09.2006	1. This STC is valid only for L410-UVP aircraft type.	05/11/2007	Active	10014990
EASA.A.S.03286	CESKA LETECKA SERVISNI A.S.			LETECKE ZAVODY L 410 UVP-E	Installation of- ACAS II (CAS-67) system with one XPDR (MST-67)- EGPWS Mk. VI system- KLN-94 GPS receiver, FA 2100 CVR,C 406-1 ELT- KMA-24H-70, LUN1120 and SAE-5-35as defined in document CLS-06-L410-AC138, issue 0, revision 1 dated 14.04.2006		CLS-06-L410-AC138, issue 0, revision 1 dated 14.04.2006	1. This is valid only for L-410-UVP-E aircraft type.	05/11/2007	Active	10014991
EASA.A.S.03288	AIR SUPPORT INTERNATIONAL S.r.l.			PA-31T (CHEYENNE/ CHEYENNE II)	ASI BMA 04/B/06 “Installation of Garmin GNS 430 & GNS 530, Goodrich WX 500, Garmin MX 20 and Accessories”		AFM Supplement No. BMA 04B06	1. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product. The installation of this modification by third person...	22/10/2008	Active	10014992
EASA.A.S.03292	RUAG AEROSPACE SERVICES GmbH			228-202, -212 228-100, -101, -200, -201	Installation of dual Garmin GBS530AW NAV/COMM/GPS and dual sandel SN4500 E-HS.		POH supplement AS9412, Edition 1Engineering Order: EO-228-234, Rev. 0Continued Airworthiness: TM-TLMCM-090305-ALLChapter 05-21-10	Vertical approach navigation basing on GPS/WAAS is o nly approved in VMC.Restricted to aircraft equipeed with HoneywellKing Silver Crown Series.	17/03/2008	Active	10014995
EASA.A.S.03293	ACI SYSTEMES			BEECH 90	GNS 430 and B-RNAV capability on Beech 90		AFM Supplement ACI-09-AFM-M-047-Rev0	N/A	18/02/2008	Orphaned	10014996
EASA.A.S.03297	STC TWENTY ONE LIMITED	REV 1	CAA UK RESPONSIBILITY	BOEING 767-300 BOEING 767-200	Introduction of CabinVu-123 Cabin Surveillance System		STC 21 MDL S21.MDL-0393, Issue 1, 20/12/2007		20/05/2008	Active	10014997
EASA.A.S.03299	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	AIRBUS 1-11	TAWS Installation.		Flight Manual Supplement FMS/524/44 rev1Modification Document BAC/111/008 issues 4 and 5	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	30/09/2008	Active	10014999

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03300	JET AVIATION AG, BASEL			BOEING 767	Activation of RAAS.		Master Document List Doc. No.: BB7673446-001.AFM supplementDoc. No.: B76734461-210-01		14/09/2007	Active	10015000
EASA.A.S.03301	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BAE 146	Installation of VIP LOPA (Inc. Club 4 Layout).		Modification BAC/ 146/108Instructions for Continued Airworthiness ICA/033/525	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	14/07/2008	Active	10015001
EASA.A.S.03302	FRANCE AVIATION			BEECH F90	Installation of 2 Collins 8.33 KHz COMM System and GTX330D mode S diversity transponder.		Modification file FA 35/2007.	AFMS No. AFM-35-2007-001, dated 26/09/2007 or later approved revision must be used with the modification.	10/12/2007	Active	10015002
EASA.A.S.03303	ACI SYSTEMES			FALCON 900 FALCON 50	Falcon 50 and F900 EHS Mode S Capability		AFM Supplement ACI-05-AFM-M-033-Rev0ACI-05-TD-M-033-Rev0	Applicability for Falcon 50 and F900 which are already ModeA, C and ELS Mode S certified, ACAS certified and equipped with a dual transponder system.	29/10/2007	Orphaned	10015003
EASA.A.S.03305	RUAG AEROSPACE SERVICES GmbH			CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III	FMS Upgrade to Dual Honeywell NZ-2000/PRNAV		Aircraft Flight Manual Supplement, Doc. 223A-AFMS, Rev. IR or later approved revision.Continued Airworthiness, Doc. 223A-CAWP, Rev. IR or later approved revision.	none	16/01/2008	Active	10015005
EASA.A.S.03306	DASSAULT FALCON SERVICE			FALCON 2000EX FALCON 2000	F2000 / F2000EX Incorporation of Runway Awareness and Advisory System (RAAS) Function on EGPWS Honeywell Mk V.		1. DFS Master Document List DFS-DE-17-FD-D100 Issue A1 or later approved revisions.2. DFS Change Approval Sheet DFS-D100-CAS Issue A1 or later approved revisions.3. DFS AFM Supplement DFS-F2000-005 Original Issue or later approvedrevisions.	1. As per applicability defined on DFS Change Approval Sheet DFS-D100-CAS Issue A1 or later approved revisions this STC is limited to those Falcon 2000 and Falcon 2000EX previously equipped with:- Honeywell EGPWS Mk V Soft. 212-212 or later with terrain display in EFIS.- Proline IV Avionics...	21/11/2007	Active	10015006
EASA.A.S.03307	AIM AVIATION (HENSHALLS) LTD		CAA UK RESPONSIBILITY	BOEING 757-200	Installation of Crew Galley in B757-200 Freighter Conversion.		AIM Aviation (Henshalls) STC Definition Document, DD 1090, Issue New, 24/10/2007.Instruction for continued Airworthiness, ICA/PR7001, Rev. New, Nov 2007.		05/02/2008	Active	10015007
EASA.A.S.03308	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA S550 (CITATION II) CESSNA 550 CITATION II CESSNA 500, CITATION	Installation of Honeywell GNS-XLS FMS and L3 Standby horizon Reference System.		Master Document List 2040837 DOC, Issue 1, dated 25/11/2007, or later approved revisions.		28/11/2007	Active	10015008
EASA.A.S.03311	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			400A	Activation of Garmin MX-20 Multifunction Display.		¿ Engineering Order EO-M05200103_SAL_04062008, Rev. 1¿ Airplane Flight Manual Supplement AFS_M05200103_SAL_27092007, Rev. 1 ¿ Instructions for Continued Airworthiness ICA_M05200103_SAL_27092007	None.	13/08/2008	Active	10015009
EASA.A.S.03312	NSE			182J	54/2006 - IFR BRNAV certification extension of the GNS430 without Autopilot coupling.		Flight Manual Supplement 54/2006-AFMS Ed. 1 Rev. 1, dated 23 January 2008.	STC Bayo 27/2006 must be already installed.The Aircraft must be equipped with HSI KI525A.	24/01/2008	Active	10015010

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03315	SOGERMA SERVICES			AIRBUS A340-313	Virgin Atlantic A340 Cabin Modification.		Modification Approval Sheet, ref. S-00-2020, Issue 1, dated10.06.2008Flight Manual Supplement, ref. FMS-F4027-00-01, dated 23.05.2008Instruction for Continued Airworthiness, ref.ICA-F4027-00-01, issue D, dated 02.06.2008	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	12/06/2008	Active	10015013
EASA.A.S.03316	FRANCE AVIATION			BEECH F90	IFR/RNAV classification of the GNS530AW coupled to the autopilot; basic IFR classification of the GNS430AW and Mode S transponder GTX330 installation.		Aircraft Flight Manual Supplement for GTX330/330D, AFM-38-2007-001.Aircraft Flight Manual Supplement for GMX200, AFM-38-2007-002.Aircraft Flight Manual Supplement for GNS530W/AW IFR/ BRNAV/ SIDs/ STARs et approches de non précision AFM-38-2007-003.Aircraft Flight Manual Supplement for GNS430W/...	The following AFMS must be used when modification is applied:Aircraft Flight Manual Supplement for GTX330/330D, AFM-38-2007-001 revision 1, dated 10/04/2008, or later approved revisions.Aircraft Flight Manual Supplement for GMX200, AFM-38-2007-002 revision 1, dated 10/04/2008, or later approvedA...	23/05/2008	Active	10015014
EASA.A.S.03319	RECTIMO AVIATION			PARTENAVIA P68C	Installation of a COM/NAV/GPS GARMIN GNS 430 (BRNAV withoutcoupling to the auto-pilot) a COM/NAV GARMIN SL 30, a stormscope L3 WX 500 and an ELT ARTEX ME 406.		Modification Approval Sheet ref. 2007/40 dated October 8, 2007Airplane Flight Manual Supplement ref. "Edition Octobre 2007" dated October 8, 2007.	This STC is limited to the S/N 279.	22/01/2008	Active	10015015
EASA.A.S.03320	ACI SYSTEMES			CESSNA 550	ACI-045 - DFDR Upgrade.		AFM Supplement ACI-12-AFM-M-045-Rev. 1Maintenance Manual Supplement ACI-12-MPS-M-045-Rev.0.	This STC is only applicable to aircraft equipped with Fairchild F800 FDR.	16/05/2008	Orphaned	10015016
EASA.A.S.03323	MOTORFLUG BADEN-BADEN GmbH			2. B90, C90 1. C90A, C9GT	Installation of AVIDYNE TAS-620 TCAD and EX500 Display, together with necessary antennas		EASA approved Compliance Programme, Doc. No. 126635-0101, Revision 1, dated 13-Dec-2007, or later approved revisionEASAapproved Airplane Flight Manual Supplement, Doc. No. 126635-01-0601, Revision 1, dated 14-Dec-2007, or later approved revisionInstructions for Continued Airworthiness, Doc. No. 126...	Only airplanes complying with the limitations and conditions listed in Chapter 2.1. “Limitations and Conditions forInstallation”, of the Installation Manual, Doc No. 126635-01-1001, Revision 2, dated 12 Dec-2007, or later issued revision, (as also listed in EASA approved Compliance...	19/12/2007	Active	10015017
EASA.A.S.03324	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	CESSNA 550 CESSNA 500, CITATION	Introduction of Dual GNS-430/530		STC Twenty One Ltd Major Change S21.34-29-1085Flight ManualSupplementS21.FMS-0032 Issue 1		05/05/2008	Active	10015018
EASA.A.S.03325	JET AVIATION AG, BASEL			AIRBUS A330	Tailwind 550/560 Antenna and Rack InstallationThe modification includes the following:- Installation of a radome with mechanical antenna located top of the fuselage- Installation of a system rack inside the cabin, above the headliner		¿ Master Data List, ref. Doc. No. BA33053201-001, Rev. D, dated 27th June 2008¿ Certification Compliance Sheet, ref. Doc. No. BA33053201-102-01, Rev. A, dated 6th June 2008 ¿ Instruction for Continued Airworthiness, ref. Doc. No. BA33053201-150-01, Rev. C, dated 18th June 2008 ¿ Declarati...	Applicable A330-220/-300 MSN’s are listed in ref. doc. No. BA3305320-123, “Effectivity Substantiation Report”, Rev. IR, dated 23.04.08	03/07/2008	Active	10015019
EASA.A.S.03326	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 737-500	Layout of Passenger Accommodation.		BAC Modification BAC/ 737/082		19/05/2008	Active	10015020

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03327	E.I.S.A.			CESSNA 525B	S134 - Maximum Takeoff/Landing Weight reduction.		STC Data List (SDL) EISA 00 SDL Rev. 4Aircraft Flight Manual Supplement EISA 00 AFMS S134 Rev. 4	None	05/02/2008	Orphaned	10015021
EASA.A.S.03329	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 767-300	Layout Passenger Accomodation		Modification BAC/767/009.		17/04/2008	Active	10015023
EASA.A.S.03330	GULFSTREAM AEROSPACE Ltd.		CAA UK RESPONSIBILITY	GULFSTREAM GV-SP	Repositioning of Cabin Seat to meet the requirements of JAR25.562(c)(8).		In accordance with Gulfstream Aerospace Limited Change Leaflet for Change No GAeL 07/06 Issue 1, dated 24 October 2007,or later approved revisions.	Aircraft Serial No 5032 Only.	29/10/2007	Active	10015024
EASA.A.S.03333	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BOMBARDIER CL-600-2B19	Dual Electronic Flight Bag Installation (Maxware).		Master Data List 667-049.	Aircraft Flight Manual Supplement 667-071.	11/04/2008	Active	10015026
EASA.A.S.03338	BUSINESS AND COMMUTER AIRCRAFT			BEECH 1900C, AIRLINER	Installation of a toilet cargo aera.		Modification file BCA 103.	Modification limited to Beech 1900C s/n UC-168.	10/01/2008	Active	10015029
EASA.A.S.03340	VITROCISET S.p.A.	REV. 1	EASA.A.S. 03340	550	Installation of Rockwell Collins Mode S Transponder System.Note: This STC supersedes EASA.A.S.03340.		AFM Supplement DRW No. 34-54-1707-800-000 Rev. IR dated 30-07-2007 andsubsequent approved revisions.MDL DRW No. 34-54-1707-000-000 Rev. IR dated 25-10-2007 and subsequentapprovedrevisions.	Prior to installation of this modification the installer must determinethat the interrelationshipbetween this modification and any other previously installedmodification will introduce noadverse effect upon the airworthiness of the product. The installationof this modification bythird persons is sub...	07/01/2009	Active	10043130
EASA.A.S.03342	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)		FOCA 34-45-004	525A	TCAS-400 & dual TDR-94D installation.Change to the FOCA STC34-45-004 "TCAS-4000, Dual TDR-94D, GNS-430 Installation.By:Incorporation of an Gables IST.G7614-() as an alternative ATC/ TCAS controller.		Engineering Order, Doc. No. AF584-062.01		10/10/2007	Active	10015030
EASA.A.S.03344	ALTRAN LABt/a AIRCAD			EMB-120	EMB-120 VIP Cabin Modification is a major change designed by AIRCAD that converts half part of the airliner cabin to a VIP cabin with six VIP seats and two tables on pallets and acurtain dividing the airline and VIP areas. One of the three emergency exits is blocked.		AIRCAD Certification Program CP 07-001.AIRCAD Service Bulletin ACD-SB 07-001.	None.	11/07/2008	Active	10015032
EASA.A.S.03345	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOFFICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	BOEING 757-200	Reconfiguration of Passenger Cabin		British Airways Engineering Master Data List MDL-0054-08, Issue 1, 20/05/2008		13/06/2008	Active	10015033
EASA.A.S.03348	BUCHER LEICHTBAU AG			MD-11	Modification of New Generation Stretcher (NGS) pn. 1120000-201 for installation in a MD-11 on the right hand side of the fuselage, in accordance with Bucher General Arrangement Drawing 1120000-201.		CMM 25-67-015 Component Maintenance Manual NGS p/n 1120000-200/201	This approval is only valid for the modified installation in the MD-11 on the right hand side of the fuselage.All otherinstallations of the New Generation Stretcher are covered by FOCA STC No. Z25-20-60It is the responsibility of the installer to make sure that this installation is certified for th...	06/11/2007	Active	10015035
EASA.A.S.03351	BUSINESS AND COMMUTER AIRCRAFT			BEECH 1900	28-230 volts inverter installation on Beech 1900 series according to modification file BCA102, rev. 0, dated 30-10-2007or later approved revisions.		Airplane flight manual supplement BCA 102, rev. 0, dated 30-10-2007 or later approved revisions.	Airplane flight manual supplement BCA 102, rev. 0, dated 30-10-2007 or later approved revisions must be used when modiifcation is applied.	19/11/2007	Active	10015038

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03352	TENENCIA Ltd.		CAA UK RESPONSIBILITY	AVRO RJ	VIP Interior Installation.		Modification TEN 532, Bae 146 Series VIP Installation, Issue 1 dated 14 May 2008 Tenencia Ltd.Report TEN 532/1.1 Certification Compliance Report, VIP Configuration Installation, Issue 1 dated 28 April 2008, Tenencia Ltd.	S/N E3386 only.	19/05/2008	Active	10015039
EASA.A.S.03353	ACC COLUMBIA Jet Service GmbH			LEARJET 36A LEARJET 35A	Installation of Laser Reflector Dekagon		As per Master Document List MDOCL_17150, rev. 0 (or later approved revisions)	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/08/2008	Active	10015040
EASA.A.S.03357	RUAG AEROSPACE SERVICES GmbH			CESSNA 525A CESSNA 525	Iridium Satcom AirCell ST3100,Description: Replacement to the previously installed AirCell AT.01 Air Telephone System by AirCell ST 3100 satellite Communication System (SATCOM).		1. Installation in accordance with RUAG Master Document List Doc-No. 225B-MDL, Engineering Order Doc-No. 225B-EO, latest approved Revision;2. To be maintained in accordance with RUAG Airplane Maintenance Manual Supplement 225B-AMMS, or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	08/02/2008	Active	10015041
EASA.A.S.03358	JET AVIATION AG, BASEL			GULFSTREAM GV-SP G550	Wireless LAN (WLAN) Activation		Master Drawing List BGLF523261-001 Rev. AAFMS BGLF523261-201-01 Rev. IR		11/03/2008	Active	10015042
EASA.A.S.03359	LUFTHANSA TECHNIK AG			A300B4-603 / -605R	A300B4-603 / -605R Cabin ReconfigurationCabin Reconfiguration from current version (280 MC) to two possible versions (58 CC / 188 MC or 40 CC / 220 MC).		Supplement Type Definition Document STDD25-07/10M Issue 01,dated 29 February 2008.Engineering Orders :- EO 156890 Issue 04- EO 158689 Issue 04- EO 156831 Issue 03(or anylater revision approved revision of this document).	The installation of this STC has a prerequisite aircraft configuration.2. This STC is only applicable on aircraft in association with the EASA STC ref: EASA.A.S.02663.3.The Certification Review Item A-01 has to be considered, inaddition to the EASA Certification Basis. 4. Prior to inst...	04/03/2008	Active	10015043
EASA.A.S.03360	JET AVIONICS AVIATION & MARINESERVICE CENTER S.r.l.			CESSNA 500, CITATION	BDI 004-07 Installation of Mode S Transponder - Elementary Surveillance.		BDI 004-07-01 Master Drawing ListBDI 004-07-01-11 AFMSBDI 004-07-18 MMEL		05/03/2008	Active	10015044
EASA.A.S.03361	ELECTRONIQUE MAINTENANCE AVIATION			BEECH 200	Installation of new COM-NAV-GPS with BRNAV capacity and coupled to AP.		EMA/07/003/BE200Série/ VHF/NAV-GPS, dated November 2007, revision 0AFM Supplement EMA/ 07/003/BE200Série/VHF/ NAV/GPS.	AFM Supplement must be used when the application is applied.Modification limited to sn BB616.	04/08/2008	Active	10015045
EASA.A.S.03362	SABENA TECHNICS BGC			A319-133	Finish Material Change in Private Area on A319CJ MSN 1468 /This modification concerns the change of fabric on part of the existing panels (including seals) in the private office, washroom and conference room in the A319CJ MSN 1468.		¿ Master Data List, ref. No. 7007-03-A-2103-R01, Rev. 01, dated 22.11.07 ¿ Certification Plan, ref. No. 7007-03-A-2101-R01, Rev. 01, dated 22.11.07 ¿ Compliance Records, ref. No. 7007-03-A-2104-R01, Rev. 01, dated 22.11.07¿ Instruction for Continued Airworthiness, ref. No. 7007-03-A-2211-R...	This STC is limited to aircraft Airbus A319-133 MSN 1468.	30/11/2007	Active	10015046

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03363	LUFTHANSA TECHNIK AG			BOEING 767-300	Condor B767 Interior Modification		Supplemental Type Definition Document, STDD00-07/20M, Issue01, Rev 00, July 01/2008	• Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.• The installation of this modification by third...	29/08/2008	Active	10015047
EASA.A.S.03364	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOEING 757 - 200	Installation of revised Passenger Accommodation		Bournemouth Aviation (Consultants) Ltd Compliance Document Summary Sheet and Accomplishment Instructions, BAC/757/014, Issue 3, 22/01/2009.Instruction for Continued Airworthiness Boeing 757 188/200 PAX LOPA, ICA/046/533, Issue 1, 22/10/2008	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	23/01/2009	Active	10015048
EASA.A.S.03366	CARGOLUX AIRLINES INTERNATIONALS .A.			BOEING 747-400F	ICS-220A Iridium sitcom installation on B747-400F airplanesin accordance with Master Drawing List CLX-STC-07-01, dated22 November2007 or later EASA approved revisions.		Data package containing the following documents and additional supporting data:Engineering Data Reprt CLX-STC-07-01, dated 22 November 2007.Master Drawing List CLX-STC-07-01.Drawing CLX-STC-07-01.Boeing SSM and WDM for Satcom and AMU	The Data on Airworthiness Limitations, revisions required of the Maintenance publications etc. arising from the changesassociated with the STC is provided in DWG CLX-STC-07-01: ICS-220A Iridium Satcom Installation on B747-400F Airplanes -ICA and miscellaneous information.	22/04/2008	Active	10015049
EASA.A.S.03369	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	CESSNA 500, CITATION	Upgrade of Mode S Transponder for Enhanced Surveillance		Lees Avionics Major Change HL/MOD/925Lees Avionics AFM SupplementsAFMS925001 Issue 1AFMS925002 Issue 1		05/03/2008	Active	10015050
EASA.A.S.03370	AERO-DIENST GMBH & CO. KG			60	GPWS to EGPWS System Upgrade (Honeywell)		AFM Supplement AG705-071, rev. IR (or later approved revisions)		21/02/2008	Active	10015051
EASA.A.S.03373	SCANDINAVIAN AVIONICS DESIGN ApS			DE HAVILLAND DHC6-310 DE HAVILLAND CANADA DHC6-300	Dual Directional Gyro, Dual EHSI/RMI and audio System.		STG Document List 2043963 STCEngineering order and certification program. 2043963-FOAFM 204-3963-AM	As detailed in the AFM 2043963-AM	05/03/2008	Active	10015052
EASA.A.S.03375	RUAG AEROSPACE SERVICES GmbH			DORNIER DO 228-202K	Increase of Fatigue Life Limit.		Supplemental Time Limits/ Maintenance Checks Manual for Aircraft S/N 8046, TM-STLMCM-8046-180405 Rev. 1.	This STC is only applicable to Aircraft S/N: 8046.	19/12/2007	Active	10015054
EASA.A.S.03376	BRITISH AIRWAYS PLCBRITISH AIRWAYS ENGINEERINGOFFICE OF AIRWORTHINESS		CAA UK RESPONSIBILITY	BOEING 757-200	B757 GPS upgrade to EGPWS.		British Airways Master Data List MDL-0053-07, Issue 00, 12-12-2007.	BA B757 AFM Change Sheet No. 10, Page 1 and 3 (issue 2).	28/03/2008	Active	10015055
EASA.A.S.03378	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	FMS SwitchingThe modification installs the coupling of eachFMC to both FMS CDU and EFIS displays, in order to comply with the B-RNAV requirements in case of one FMC source failure. This modification allows dispatching the serviceable FMC signal on the CDU and EFIS displays affected by the loss of t...		Fiche de Modification n° ST34MOD021, Issue 1(or any later approved revision) MMEL Supplement: Annexe 7 of the Fiche de Modification n° ST34MOD021.	1. The MMEL Supplement associated with this STC is only quoted for information. The STC approval EASA.A.S.03378 does not constituteits approval. The MMEL Supplement approval will be granted separately.2. Prior to installation of this modification the installer must determine that the interrelationsh...	12/03/2008	Active	10015056

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03379	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B300C BEECH B300 BEECH B200C BEECH B200 BEECH 300LW BEECH 300 BEECH 200C BEECH 200	Installation of Garmin GWX 68 / Garmin GMX 200 Weather Radar System.		EASA approved Engineering Order, Doc. No. 2038539-EO, Issue3, dated 24-Jan-2008, or later approved IssueEASA approved Airplane Flight Manual Supplement, Doc. No. 2038539-AM, Issue 1, dated 24-Jan-2008, or later approved IssueInstructions for Continued Airworthiness, Doc. No. 2038539-CA, Issue 1, da...	This change is limited to the configuration of aircraft / equipment type as listed under Item 4. of EASA approved Engineering Order, Doc. No. 2038539-EO, Issue 3, dated 24-Jan-2008 or later approved issue. The system is not approved for operation or condition depending on airborne we...	30/01/2008	Active	10015057
EASA.A.S.03380	BUSINESS AND COMMUTER AIRCRAFT			BEECH 1900C, AIRLINER	Installation of a galley in the FWD right area of the A/C.		1. Installation must be in accordance with BCA 104 Master Data List Rev. 1, dated January 22, 2008 or later ApprovedRevisions;2. Maintenance must be in accordance with BCA 104 Aircraft Maintenance Manual Rev. 1, dated January 22, 2008 or later Approved Revisions.	1. Must be installed on Beech 1900C (S/N UC-1 and after);2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of th...	29/01/2008	Active	10015058
EASA.A.S.03381	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		BEECH 1900C, AIRLINER	Installation of a galley in the FWD right area of the A/C.		Installation must be in accordance with BCA 106 Master DataList Rev. 1, dated January 22, 2008 or later Approved Revisions.Maintenance must be in accordance with BCA 106 AircraftMaintenance Manual Rev. 1, dated January 22, 2008 or later Approved Revisions.	Must be installed on Beech 1900C (S/N UC-1 and after).	29/01/2008	Active	10015059
EASA.A.S.03383	FEDERATION FRANCAISE DE VOL A VOILE (FFVV)			CS11 75, CS75 VTC	Winglet Retrofitting.		Dossier de modificationSupplement aux Manuels de volStatement of conformity.	2.2 Supplemental Flight Manual	01/02/2008	Active	10015060
EASA.A.S.03384	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B300C BEECH B300 BEECH B200C BEECH B200 BEECH 300LW BEECH 300 BEECH 200C BEECH 200	Installation of Garmin GPS 500 System (including compliancewith AMC 20-4, AMC 20-5 and FAA AC20-138A)		EASA approved Engineering Order, Doc. No. 2038540-EO, Issue2, dated 22-Jan-2008, or later approved IssueEASA approved Airplane Flight Manual Supplement, Doc. No. 2038540-AM, Issue 1, dated 03-Dec-2007, or later approved IssueInstructions for Continued Airworthiness, Doc. No. 2038540-CA, Issue 1, da...	This change is limited to the configuration of aircraft / equipment type as listed under Item 4. of EASA approved Engineering Order, Doc. No. 2038540-EO, Issue 2, dated 22-Jan-2008 or later approved issue. The system is not approved for operation or condition depending on airborne we...	30/01/2008	Active	10015061
EASA.A.S.03389	SCANDINAVIAN AVIONICS DESIGN ApS			HS125-700A, HS125-700B	Sandel ST3400 TAWS Installation.		Installed in accordance with 2044235-EO Engineering Order Issue 2 or later approved revision.Operated in accordance with 2044235-AFM AFM supplement Issue 1 or later approved revision.Maintained in accordance with 2044235-CAInstructions forContinued Airworthiness Issue 1 or later approved revision....	None	30/05/2008	Active	10015063

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03390	AVIONITEC Ltd.			T210L	Replacing of existing avionics by newer generation of avionics in accordance with Unit change overview Nr. 073775-050, Rev 0, dated05.12.07.		Installation must be in accordance with Avionitec Master Document List No. 073775-017 Rev.1 dated 14. Feb. 2008 or later Approved Revisions.Operation must be in accordance with Avionitec Airplane Flight Manual Supplement No. 073775-011 dated 08. Jan. 2008 or later approved revision.Maintenance mustr...	Limited to S/N T21059922.	27/02/2008	Active	10015064
EASA.A.S.03391	SOCATA			SOCATA TBM 700	Installation of a multi-functions display Garmin GMX 200 connected to already installed equipments (weather radar, COM/NAV/GPS, Traffic Advisory System).		Definition and Installation:EADS SOCATA Modification Data Sheet (MDS) n' STC.34.001.07, edition 1 revision 0, dated 15/01/2008 or later EASA approved revisions.Operations:EADS SOCATA TBM 700 Pilot Operation Handbook (POH) Supplement n° 46A"Garmin GMX 200 Multi-fuction display" ref. STC 34-001-07-41...	This revision can be installed on TBM 700 s/n to 433 when equipped with EADS SOCATA optional Modifications n° OPT 70-23-019, OPT 70-23-018, OPT 70-34-047 and OPT 70-34-040.The installation can be performed only by EADS SOCATA technical staff according to the MDS here-above referred.	06/02/2008	Active	10015065
EASA.A.S.03392	CHRISTEN-AIRTECH AG			BEECH C90KING AIR	GNS 530A, GNS 430A, GAD 42 installation:Removed equipment:-2 KTR 905 COM 1 & COM 2- 2 KNR 630 NAV 1 & NAV 2- 1 KLN 90BGPS with AK-950 GPS Annunciator- 1 KDM 705A DME with KDI 570 DME IndicatorNew installed equipment:- 1 GNS 530AW COM/NAV/ GPS 1 with GAD 42 Adapter Box and MD-41 Annunciator Unit- 1-...		- Master Document List, Doc. No. 207.1698 Revison 0 or latest approved Revision- GNS 530AW-AFMS, Doc. No. 207.1698-FS-01-00 Rev. 0 or latest aproved Revision- GNS 430AW-AFMS, Doc.No. 207.1698-FS-02-00, Rev. 0 or latest approved Revision	F-GBLU, SN: LJ-822.	10/09/2008	Active	10015066
EASA.A.S.03393	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA S550, (CITIATION S/II) CESSNA 550 CITATION II CESSNA 500, CITATION	Installation of Honeywell ART2100/ KMD850 Weather Radar System.		1. AFM-Supplement: 2044352-AM Issue 1;2. Engineering Order: 2044352-EO Issue 2;3. Continued Airworthiness: 2044352-CA Issue 1.	1. This STC is exclusively applicable for aircraft whichhave the equipment listed in chapter 4 of the Scandinavian Avionics Engineering Order 2044352-EO Issue 2 already installed;2. Prior to installation of this modification the installer must determine that the interrelationship between this...	12/03/2008	Active	10015067
EASA.A.S.03394	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	AIRBUS A321 AIRBUS A320 AIRBUS A319 AIRBUS A318	Introduction of Wingspeed XLLink Communications and Data Management System		1. STC Twenty One Limited Major Change S21.23-02-10392. Flight Manual Supplement S21.FMS-0042 Issue 1	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	29/10/2008	Active	10015068

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03395	CESKA LETECKA SERVISNI A.S.			LETECKE ZAVODY L 200 D LETECKE ZAVODY L 200 A	Installation of new COM, NAV, GPS, XPDR + Encoder, DME, ADFand flight instruments to meet the current technical and operating requirements of IFR category.		Flight manual supplements In Czech language only:AC159-2501-ELTME-406AC159-2502 - Audiopanel GMA-347AC159-2503 - NAV/COM/GPS GNS-430AC159-2504 - Radarový odpovídac GTX-330AC159-2505 - Gyromagnetický kompasový systém KCS-55AAC159-2506 - Meric vzdálenosti KN-63AC159-2507 - Radiokompas KR-87 ¿¿159-2508 -...		04/07/2008	Active	10015069
EASA.A.S.03396	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			PIPER PA-28R-200	Modification d'installation Radio / B-RNAV sans couplage PADépose: 1 boite audio KA 134+1 GPS 150XL+1 VHF/VOR KX 155 + IND KI 208 + 1MKRKR21 + 1 ATC KT 76APose: 1 boite audio/MKR GMA 340 + 1 VHF/VOR/GLD/GPS GNS 430 + IND GI		Fiche d'Approbation de Conception d'une Evolution N°1842-07- Revision 4 du 03/02/2009SUPPLEMENT N°1 AU MANUEL DE VOL - SEAM/SMV/1842/07 - Révision 2 du 03/02/2009	1. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third pers...	02/03/2009	Active	10015070
EASA.A.S.03397	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	Air Data Sensor Installation for non essential systems		DFS Master Document List DFS-DE-17-F5-5657 Issue A1 or later approved revisions.	This STC is limited to all Mystere Falcon 50 aircraft without ARINC 429 air data parameters available.In case the aircraft is RVSM compliant this DFS modification will be applicable only on those aircraft on which Dassault Aviation SB F50-246 have been implemented.	28/03/2008	Active	10015071
EASA.A.S.03402	LUFTHANSA TECHNIK AG			AIRBUS A318-112	A318 ELITE - Project BAA; VIP Cabin completion.		1. Supplemental Type Definition Document, ref. Doc. No. STDD00-07/21M, issue 03, dated 07. November 2008, or later approved revision.2. Aeroplane Flight Manual Supplement A-00-08/697-AFM issue 1, dated 15. October 2008, or later approved revision.3. Instructions for Continued Airworthiness,...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	07/11/2008	Active	10015072
EASA.A.S.03403	MT-PROPELLER ENTWICKLUNG GmbH			AVIAT HUSKY A-1B AVIAT HUSKY A-1A	Installation of Constant Speed 2 Blade propeller MTV-15-B/210-58.This STC is based on LBA STC SA 1314, issued 19.03.2003.		Flight Manual Supplement "Anhang zum Flughandbuch", Doc. No. E-891, Rev. 1 dated 30.11.2007 or later approved revision.Installation Instruction "Umrüstungsanweisung", Doc. No, E-892, Rev. 1, dated 23.11.2007 or later approved revision.Operation and installation Manual E-124, Issue 41 or later approv...		19/12/2007	Active	10015073
EASA.A.S.03404	BUCHER LEICHTBAU AG		FOCA STC: Z 25-20-53	PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12	EMS installation P/N 127001-300This EASA STC extens the validity of FOCA STC Z25-2053 for PC-12 S/N up to 888.		AFMS 127001-300 Rev. C dated 3rd October 2007MDL MDOC-127001-300 Rev. C dated 3rd October 2007	S/N 861-888	19/12/2007	Active	10015074
EASA.A.S.03406	ACI SYSTEMES			BEECH 300 BEECH 200	Installation of a Garmin 400 Series with B-RNAV capability on Beech 200.				05/02/2008	Orphaned	10015075

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03407	AEROSERVIS, S.R.O.			L-200 A	Installation of NAV/COM/GPS device GNS 430		Supplement to AFM (only the Czech language) No. STC AE/079-DLP1 "Doplnek Smernice pro pilota letounu L200A".		25/03/2008	Active	10015076
EASA.A.S.03408	JET AVIATION AG, BASEL			GULFSTREAM III	Iridium SATCOM Installation consisting of-1 ICS-200 IridiumTransceiver- 1ICS Iridium Antenna- 1 Sigma 7 handset- 2 Cordless Handset		Master Data List, Doc. No. BTAAW028-001, Rev. A or latest approved revision.Instructions for Continued Airworthiness, Doc No. BTAAW028-150-09, Rev. Or latest approved revision.	Reg. TJ-AAW S/N 486Valid for this S/N only.	05/03/2008	Active	10015077
EASA.A.S.03410	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	BEECH B300	Introduction of Equipment Associated with Operational Requirements.The introduction of supplementary radio navigation aids to support anavigation calibration systemand items of equipment for EU-OPS operation.		• Installation must be in accordance with Master Document List includedin the Design ChangeStatement DC-0127 Iss.1 dated 28th November 2008 or later ApprovedRevisions.• Operation must be in accordance with Pilots Operating HandbookSupplement No.FRAH/FMS/0115 Rev. 0: Dated 19th November 2008 or later...	1. Prior to installation of this modification the installermustdetermine that the interrelationshipbetween this modification and any other previously installedmodification will introduce noadverse effect upon the airworthiness of the product. The installationof this modification bythird persons isa...	28/11/2008	Active	10043132
EASA.A.S.03411	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK	REV. 1	CAA UK RESPONSIBILITY	BEECH B300	AD-AFIS Equipment Installation.Installation of equipment tosupport operation as an airfieldcalibration aircraft.		• Installation must be in accordance with Master Document List includedin the Design ChangeStatement DC-0128 Iss.1: Dated 28th November 2007 or later ApprovedRevisions.• Operationmust be in accordance with Pilots Operating HandbookSupplement No.FRAH/FMS/0115 Rev. 0: Dated 19th November 2008 or late...	1. Prior to installation of this modification the installermustdetermine that the interrelationshipbetween this modification and any other previously installedmodification will introduce noadverse effect upon the airworthiness of the product. The installationof this modification bythird persons isa...	09/12/2008	Active	10043133
EASA.A.S.03412	SOGERMA SERVICES			AIRBUS A320 SERIES	Installation of passenger entertainment cabin audio system on seatsNote: This STC supersede DGAC France STC 180-SF-0175.		Service Bulletin SOG-DO-23-33-01		04/01/2008	Active	10015078
EASA.A.S.03413	SOGERMA SERVICES		DGAC FRANCE STC 180-SF-0174	AIRBUS A320 SERIES	Sony Video System InstallationNote: This STC supersede DGACFrance STC 180-SF-0174.		Service Bulletin SOG-DO-23-36-01		04/01/2008	Active	10015079
EASA.A.S.03414	SOGERMA SERVICES		DGAC FRANCE STC 072-MJ-0857	AIRBUS A300 MODEL B2-1A	Installation of a GPS/HIS adapterNote: This STC supersede DGAC France STC 072-MJ-0857.		SOG-34-500 issue C		04/01/2008	Active	10015080
EASA.A.S.03415	SOGERMA SERVICES		DGAC STC F-C180-SF-0242; EASA	AIRBUS A320 SERIES	Cabin conversion modificatiom "20 B/C - 148 Y/C"Note: This STC supersede DGAC France STC F-C180-SF-0242 and EASA 2004-9168.		Modification Approval Sheet (MAS) referenced SOG-25-882 issue 2, dated June 25, 2004		04/01/2008	Active	10015081
EASA.A.S.03416	SOGERMA SERVICES		DGAC FRANCE STC F-C072MJ0864;	AIRBUS A300-600	Installation of an ELT 96 emergency locator transmitterNote: This STC supersede DGAC France STC F-C072MJ0864 and EASA 2004-4595.		Modification Approval Sheet SOG-25-070 issue D, dated 31 March 2004		04/01/2008	Active	10015082
EASA.A.S.03417	SOGERMA SERVICES		DGAC FRANCE STC 180-SF-0229; E	AIRBUS A320 SERIES	Cabin conversion from 180 Y/C to 16 B/C + 169 Y/CNote: ThisSTC supersede DGAC France 180-SF-0229 and EASA 2004-3515.		Modification Approval Sheet (MAS) SOG-25-796 issue 2, dated12 March 2004		04/01/2008	Active	10015083
EASA.A.S.03418	SOGERMA SERVICES		DGAC FRANCE STC 180-SF-0221; E	AIRBUS A320 SERIES	Installation of BENNET seat containerNote: This STC supersede DGAC France 180-SF-0221 and EASA 2004-2036.		Modification Approval Sheet (MAS) SOG-25-755 issue 2, dated10 February 2004AFM Supplement ref. AFM-MD050-25-755-01		04/01/2008	Active	10015084
EASA.A.S.03419	SOGERMA SERVICES		DGAC FRANCE STC 072-MJ-0862; E	AIRBUS A300 MODEL B2	SPC antenna modificationNote: This STC supersede DGAC France STC 072-MJ-0862 and EASA 2003-304.		SOG-05-340 issue E	1. Valid only for Airbus B2 MSN 003	04/01/2008	Active	10015085

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03420	SOGERMA SERVICES		DGAC FRANCE STC 072-MJ-0861; E	AIRBUS A300 MODEL B2	Cargo door modification for use of SPC antennaNote: This STC supersede DGAC France STC 072-MJ-0861 and EASA 2003-303.		Modification Approval Sheet (MAS) SOG-52-340 issue E	1. Valid only for MSN 003.	04/01/2008	Active	10015086
EASA.A.S.03421	SOGERMA SERVICES		EASA 2004-2363	AIRBUS A300 MODEL B2	Installation of a ground proximity warning systemNote: ThisSTC supersedes EASA STC 2004-2363.		MAS N SOG-34-576 Issue 3AFMS DIT/M/G/2881/03	1. Only valid for MSN 003.	04/01/2008	Active	10015087
EASA.A.S.03423	JET AVIATION VIENNA GMBH			525	Rockwell Collins MDF-124F (V2) Direction-Finder-System Installation		Certification Report C525-ARS34-004, Rev. 1, 15.02.2008Engineering Bulletin EB-C525-ARS34-004, Rev. 1, 11.02.2008AFM Supplement C525-ARS34-004-M1-AFM, Rev. 1, 07.02.2008Instructions for Continued Airworthiness C525-ARS34-004-M1-IFCA, Rev. 0, 31.01.2008	Refer to AFMS limitation	27/02/2008	Active	10015088
EASA.A.S.03424	SCANDINAVIAN AVIONICS DESIGN ApS			FALCON 10	Dual TDR-94D Transponder Upgrade to provide limited Enhanced Surveillance Transponder Mode S capability (Non EHS Capable).		See Scandinavian Avionics:• 2044753 DOC (Certification Documents) issue 1, dated 12-Feb-08.• 2044753-TO TechnicalOrder (for installation instructions) issue 2, dated 11-Feb-08.• 2044753-AM AFM Supplement issue 1, dated 18-Feb -08.• 2044753-CA Instructions for Continued Airworthiness iss...	Previous required aircraft configuration:• Aircraft equipped with Dual TDR-94D (-007/-008) and installation compliant with Elementary Mode S requisites.• Mode S Transponder Antenna Diversity• Collins TCAS II System• Dual ADC's installation with:o ADC 1 Collins ADC-80 with ARINC 457 in...	22/02/2008	Active	10015089
EASA.A.S.03428	LUFTHANSA TECHNIK AG			A3118	A318 – Ballast Weight Installation		- Supplemental Type Definition Document, ref. Doc. Doc. No. STDD53-08/02M issue 01, dated 11th August 2008 or later approved revisions-Compliance Record List, ref. Doc. No.CRL53-08/02M, issue 01, dated 11th August 2008- Applicant's Declaration of Compliance No. 2147 – A318 Ballast Weight...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	12/08/2008	Active	10015091
EASA.A.S.03429	BUCHER LEICHTBAU AG			PILATUS PC-12	Heavy Duty Floor Panel		(A)FMS 0127470 Rev. N/C or ater CMM E016-19-08 Rev. N/C or later.		19/05/2008	Active	10015092
EASA.A.S.03431	RUAG AEROSPACE SERVICES GmbH			BEECH B200	Dual Collins TDR-94() Upgrade-ELS/EHS and Antenna Diversity.Upgrade of existing Dual Collins TDR-94() Transponders by TDR-94D and Replacement of Control CTL-92 by CTL-92E.Installation of two additional top-mounted L-Band Antennas for antenna diversity.Installation of Interface between Transponders a...		Installation in accordance with RUAG Airplane Flight ManualSupplement Doc-No. 231A-B200-34.80.01AFMS, latest approved revision.	None	08/02/2008	Active	10015094
EASA.A.S.03432	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			CESSNA 210E	STC 1862-08 - Avionic modification for BRNAV navigation andautopilot coupling.		AFM Supplement SEAM/ SMV/1862/08 Revision 2, dated 28 April 2008.	Limited to S/N 58625.	29/04/2008	Active	10015095
EASA.A.S.03439	NSE	REV. 1		SA 226-T	Modification of radio electrical Installation2 VHF 21A, 2VOR/ILS/MKR VIR 30A, 2 ATC TDR 90, 1 RMI 30 removal2GNS 430 W,2 MD 41, 2 A-30 ACK, 2GTX 330D, 1 KA-33, 1 ST3400 Installation		Airplane Flight Manual Supplements:- 64/2007-AFMS TAWS Ed. 1 Rev. 0 Feb. 2008- 64/2007-AFMS GNS 430 W/Limitation-Ed. 1 Rev. 0 Feb? 2008.	The approvam is limited to MSN T-276 F-GLLOGPS use is forbidden for SID/STAR/ ApproachesGPS/Auto Pilot coupling is forbidden below 2000 ft.	05/03/2008	Active	10015098
EASA.A.S.03441	ACI SYSTEMES			BEECH 90	Installation of Garmin 500 Series GPS with B-RNAV capability on Beech 90.		ACI-09-AFM-M-070, Revision 0, dated 15 January 2008Modification file ACI-09-TD-M-070, Revision 0, dated 15 January 2008.	The supplemental Airplane Flight Manual ACI-09-AFM-M-070, revision 0, dated 15 January 2008 must be on board when the modification is installed.	04/04/2008	Orphaned	10015099

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03443	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	PIPER PA-31	Installation of new Avionics		Phoenix Aviation Design Services Limited Design Change PADS/CP/1110 Part BFlight Manual SupplementsPADS/FMS/PA31/001 Revision 1PADS/FMS/PA31/002 Revision 1 or later EASA approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	30/09/2008	Active	10015100
EASA.A.S.03444	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	PIPER PA-39	Validation of Foreign Installed Avionics		Phoenix Aviation Design Services LtdMajor Change PADS/CP/1111Flight Manuals SupplementsPADS/FMS/PA39/001 Rev. APADS/FMS/PA39/002 Rev. A		05/05/2008	Active	10015101
EASA.A.S.03445	AIM AVIATION (JECCO) LIMITED		CAA UK RESPONSIBILITY	A340-313X	Premium Cabins UpgradeAppearance, comfort and maintenance improvement changes to the seats and the window reveals and shades in the First and Business Class cabins.		¿ AIM Major Change, ref. Doc. No. MM385/07, Issue C, dated 1st July 2008 ¿ AIM Certification Plan and Compliance Check List, ref. Doc. Appendix to Major Change MM385/07, Issue C, dated 1st July 2008¿ Declaration of Compliance - page 55 of the Appendix to Major Change MM385/07, dated 4th Augu...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/08/2008	Active	10015102
EASA.A.S.03447	AVIONITEC Ltd.			F90	Avionics replacing: Garmin GTX330D XPDR and Weather Radar System RDR 2000.		Installation must be in accordance with Avionitec Master Document List No. 073839-017 Rev.0 dated 19. Mar. 2008 or later Approved Revisions.Operation must be in accordance with Avionitec Airplane Flight Manual Supplement No. 073839-011 dated 17. Feb. 2008 and No. 073839-012 dated 17. Feb. 2008 or la...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	23/09/2008	Active	10015104
EASA.A.S.03448	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			SOCATA TB 20	Installation of a GNS 430 W for IFR B-RNAV "en route" operations, without coupling to automatic pilot.		- Flight Manual Supplement no. SEAM/SMV/1863/08 revision0 dated 15/02/08- SEAM Modification file no. 1863/08 Edition 1 dated 16/01/08	1. This installation is limited to TB 20 s/n 791.2. Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the produc...	17/04/2009	Active	10015105
EASA.A.S.03449	EAD AEROSPACE			A319	Installation of AMT-3800 High Gain Antenna on A319 Series Aircraft		¿ Master Drawing List, ref. Doc. No. 01227-EAS-A-MDL, Rev. D, dated 14th November 2008 ¿ Supplemental Type Design Document, ref. Doc. No. 01227-EAS-A-STD-01, Rev. B, dated 5th August 2008¿ Maintenance Planning Document, ref. Doc. No. 01227-EAS-A-MPD-01, Rev. D, dated 14th November 2008 ¿ D...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modificationand any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. 2. The installation of this modification b...	17/11/2008	Active	10015106

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03450	LUFTHANSA TECHNIK AG			A300 F4-600R	Structure modification for GPS antennae installationThis STC defines the structural modification for the installation of a dual GPS antennae, in place of the existing Gatelink antenna		Supplement Type Definition Document STDD53-08/03M Issue 01,Revision 1, dated 29 April 2008.Engineering Bulletin : A300-EB53-0292 Issue 03(or any later approved revision of these documents).Instruction for Continued Airworthiness, ref : ICA-53-0292 Issue 1		08/05/2008	Active	10015107
EASA.A.S.03451	DASSAULT FALCON SERVICE	REV. 1		MYSTERE FALCON 50	IFE / Galley Electrical Load Shedding.		1. For Falcon 50:- DFS Master Document List DFS-DE-17-F5-5653 Issue A1 or later approved revisions;- Aircraft Flight Manual Supplement F50-058 Revision Original or later approved revisions;2. For Flacon 50EX:- DFS Master Document List DFS-DE-17-F5-5653 Issue B1 or later approved revis...	1. This STC is applicable to:- All Mystere Falcon MF50 aircraft and;- Falcon 50EX aircraft variant up to serial number aircraft 333 included, on which Dassault Aviation Mod. M2849 “IFE Load Shedding: electrical capability” has notbeen embodied.2. This STC approval does not cover any pos...	26/06/2008	Active	10015108
EASA.A.S.03452	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOMBARDIER CL-600-2B19	Introduction of Passenger Cabin interior.		STC 21 Master Document List No. S21.MDL-0482 Issue 1 dated 3 March 2008 or later approved revisions.STC 21 Flight Manual Supplement No. S21.FMS-0034 at Issue 1 or later approved revision.		07/03/2008	Active	10015109
EASA.A.S.03453	DASSAULT FALCON SERVICE			MYSTERE FALCON 50	Installation of AC Electrical Generation / Distribution compliant with JAA TGM/ 25/10 requisites		DFS Master Document List DFS-DE-17-F5-5651 Issue A1 or later approved revisions.	STC applicable on those Mystere Falcon 50 aircraft on whichSTC EASA.A.S.03451 (Mod. DFS 5653) “IFE / Galley ElectricalLoad Shedding” has been implemented previously or simultaneously.	28/03/2008	Active	10015110
EASA.A.S.03454	BUSINESS AND COMMUTER AIRCRAFT	REV. 1		BEECH BARON 58	Dual Garmin Installation : GNS-530 (GPS approaches and PRNAV approved) + GNS 430 on Baron 58 (EFS 40/50 equipped).		Master Drawing List Ref. BCA 107-00, revision 2, dated 23 April 2008Airplane Flight Manual ref BCA107-06Installation bulletin ref. 337, rev. 2 dated 22 February 2008	Airplane Flight Manual Supplement ref. BCA 107-06, revision2, dated 23 April 2008 or later approved revision must be used when modification is applied in the Aircraft.Modification limited to s/n TH-1510, TH-1515, TH-1537, TH-1701 to TH-1706, TH-1734 and TH-1736.	08/05/2008	Active	10015111
EASA.A.S.03457	JET AVIATION AG, BASEL			B747-400	Interior Modifications		- MDL Doc. No. BAHRM004-001, Rev. BAFMS Doc. No. BAHRM004-201-01. Rev. IROMM Doc. No. VB-06, Rev. B	1. STC limited to Aircraft SIN 26903.2. For other Limitation refer to the AFMS BAHRM004-201-0.3. Prior to installation of this modification the installer mustdetermine that theinterrelationship between this modification and any other previouslyinstalled modificationwill introduce no adverse effect u...	02/06/2009	Active	10043134
EASA.A.S.03459	RECTIMO AVIATION			PIPER PA-28R-201T	Replacement of : King KX155, KI209 and Garmin GPS 155 by Garmin GNS430 coupled to HSI and autopilot. Installation of a RMI KI 229.Removal of King KX155, KI209 and Garmin GPS 155 Installation of King RMI KI 229, Garmin GNS 430 with MD 41 coupled to HSI KI525A and autopilot.		FACE Rectimo Aviation 2008/03.AFMS EASA approved Flight Manual Supplement for aircraft equipped with GPS Garmin GNS 430using GPS GNS 430 in VFR mode coupled to HSI and autopilot,ed. July 2008	Applicable to S/N 7803232 F-GHYY.GPS use is limited to Day VFR flights in sight of ground or water.	22/09/2008	Active	10015112

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03460	SCANDINAVIAN AVIONICS DESIGN ApS			MYSTERE FALCON 20-F5 MYSTERE FALCON 20-E5 MYSTERE FALCON 20-D5 MYSTERE FALCON 20-C5 MYSTERE FALCON 200 FAN JET FALCON SERIES G FAN JET FALCON SERIES F FAN JET FALCON SERIES E FAN JET FALCON SERIES D FAN JET FALCON SERIES C	Dual TDR-94D Transponder Installation Upgrade to provide both Elementary and Enhanced Surveillance Transponder Mode S Capabilities.		See Scandinavian Avionics:• 2045142-STC (Certification Documents) issue 2, dated 04 Jun 08.• 2045142-EO Engineering Order issue 2, dated 11 Feb 08.• 2045142-AM-A AFM Supplement for Mode S Transponder Elementary Surveillance Capability, issue 1 dated 04 Feb 08.• 2045142-AM-B AFM Supplemen...	Previous required aircraft configuration:• Aircraft equipped with Dual TDR-94D installation with Mode S Diversity Antenna installation and Radio Tuning Unit RTU-4220• ADC's with ARINC 429 Interface.• Collins TCAS II System• Collins Proline 4 Avionics Suite.As per Scandinavian Avionics 20...	09/06/2008	Active	10015113
EASA.A.S.03462	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			LEARJET 60	UNS-1B or 1C upgrade to UNS 1C+		Master Data List Doc. No.: 734-049 AFM Supplement Doc. No..734-071		25/04/2008	Active	10015114
EASA.A.S.03466	BOURNEMOUTH AVIATION (CONSULTANTS) Ltd.		CAA UK RESPONSIBILITY	BOMBARDIER CL-600-2B16 (604)	Installation of Electronic Flight Bag		BAC Modification No. BAC/CL/023 Issue 2BAC FMS/535/45 Issue2	Restricted to ASN 5383	06/06/2008	Active	10015117
EASA.A.S.03467	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	HAWKER 800 XP	To upgrade Dual Honeywell NZ-2000 FMS Computers from 5.2 to6.0 software and provide P-RNAV approval.		Hawker Beechcraft Limited Change No. SCO314A – To introduceDual Honeywell NZ-2000 FMS Computers (with V6.0 software) in lieu of NZ-2000 (with V5.2 software) Operation to be in accordance with Hawker Beechcraft Limited Flight Manual Supplement No.4 to Flight Manual ref H.S. 1.22, andASC-Z-GEN-AV3313 "P...	None.	06/10/2008	Active	10015118
EASA.A.S.03468	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	HAWKER 1000	To introduce Dual Honeywell NZ-2000 FMS Computers in lieu of NZ-920 FMS Computers and add a second GPS GNSSU. The existing Data Loader is replaced with Model DL-950.		Certification Plan ASC-C-009-AW3173, Instructions for continued airworthiness ASC-R-009-AV3152. AFM Supplement for Hawker 1000B (HS1.18) Supplement 3 issue 1.Modification ref SC0315A	1. As per AFM Supplement for Hawker 1000B (HS1.18) Supplement 3 issue 1;2. Prior to installation of this modification the installer must determine that the interrelationshipbetween this modification and any other previously installed modification will introduce no adverse effect upon the airw...	25/09/2008	Active	10015119
EASA.A.S.03474	RUAG AEROSPACE SERVICES GmbH	REV. 1		FALCON 20	Dual Universal UNS-1L FMS Installation.		Master Document List 236A-MDL Revision Original.EngineeringOrder 236A-F20-34.60.02EO Revision Original.Airplane FlightManual Supplement 236A-F20-34.60.02AFMS Revision N/CMaintenance Manual Supplement 236A-F20-34.60.02MMS Revision N/COr later approved revisions of these documents.	This STC is limited to Mystere-Falcon 20-C5 aircraft SerialNumber 141.See:Airplane Flight Manual Supplement 236A-F20-34.60.02AFMS Revision N/CMaintenance Manual Supplement 236A-F20-34.60.02MMS Revision N/COr later approved revisions.	01/04/2008	Active	10015124
EASA.A.S.03475	RUAG AEROSPACE SERVICES GmbH	REV. 1		FALCON 20	Dual Collins TDR-94D Enhanced Mode S Transponder Upgrade.		Master Document List 236B-MDL Revision Original.EngineeringOrder 236B-F20-34.80.05EO Revision Original.Airplane FlightManual Supplement 236B-F20-34.80.05AFMS Revision Original	This STC is limited to Mystere-Falcon 20-C5 aircraft SerialNumber 141.See:Airplane Flight Manual Supplement 236B-F20-34.80.05AFMS Revision OriginalOr later approved revisions.	31/03/2008	Active	10015125

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03479	SCANDINAVIAN AVIONICS DESIGN ApS			BOMBARDIER DHC-6 SERIES 300	Honeywell EGPWS MK VI, TRA-45 Display installation.		AFM2045504-AM.Engineering Order 2045504-EO.		28/03/2008	Active	10015128
EASA.A.S.03480	CHRISTEN-AIRTECH AG			CESSNA P210N	Avionics upgradeBy removing:-NSD 360 HISSA-832B Slaving BoxACK A-30 mod 8 Altitude EncoderGMA-340 Audio PanelAnd installingSN-3500 E-HISSAC 7-35 Airdada ComputerKG-102A Remote GyroGMA-347 Audio Panel		Master Document List, Doc. No. 208.1730-AFMS Doc. No. 208.1730-FS-01-00 revision 0 or latest approved revision.AFMS, Doc. No. 208.1730-FS-02-00 revision 0 or latest approved revision.	Reg.: HB-CZB S/N: P-210-0780	05/03/2008	Active	10015129
EASA.A.S.03481	MT-PROPELLER ENTWICKLUNG GmbH			PAC 750XL	Installation Propeller MTV-16-1-E-C-F-R (P)(CFR250-55a on PAC 750XL)		AFM Supplement, Doc. No. E-1641 dated 16.06.2008Instructions for Continued Airworthiness, Doc. No. E-1643 dated 16.06.2008.		22/07/2008	Active	10015130
EASA.A.S.03483	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B300C BEECH B300 BEECH B200C BEECH B200 BEECH 300LW BEECH 300 BEECH 200C BEECH 200	Installation of a Universal CVR-30B or CVR-120 Cockpit Voice Recorder		EASA approved Engineering Order, Doc. No. 2045503-EO, Issue2, dated 23-Apr-2008, or later approved IssueEASA approved Airplane Flight Manual Supplement, Doc. No. 2045503-AM, Issue 2, dated 14-Apr-2008, or later approved IssueInstructions for Continued Airworthiness, Doc. No. 2045503-CA, Issue 2, da...	This change is limited to the configuration of aircraft / equipment type as listed under Item 4. of EASA approved Engineering Order, Doc. No. 2045503-EO, Issue 2, dated 23-Apr-2008 or later approved issue.	05/05/2008	Active	10015132
EASA.A.S.03486	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	HAWKER HS 125-700A	To upgrade Dual UNS-1K FMS to Dual UASC UNS-1Lw in preparation for P-RNAV compliance.		¿ HBL Major Change SC0318A¿ Certification Plan ASC-C-009-AW3264 ¿ HBL Supplement No.7 to Flight Manual H.S.1.9 ¿ ASC-Z-007-AV3270 Instructions for Continued Airworthiness.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	10/11/2008	Active	10015133
EASA.A.S.03488	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH 58	STC 1940-08- Avionic modification for BRNAV navigation and autopilot coupling.		AFM Supplement SEAM/SMV/1940/08 revision 1 dated 20 February 2008	Limitation to s/n TH 1401	06/05/2008	Active	10015135
EASA.A.S.03490	SCANDINAVIAN AVIONICS DESIGN ApS			CESSNA 650 CITATION VII	UPGRADE of existing FMS Universal UNS-1Csp to UNS-1Csp+ to comply with P-RNAV requirements.		2045402-EO Engineering Order Issue 2 or later approved revision. 2045402-AM AFM Supplement Issue 1 or later approved revision. 2045402-CA Instructions for Continued Airworthiness Issue 1 or later approved revision.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	25/08/2008	Active	10015137
EASA.A.S.03491	NSE			SA 226-T	Modification of radio electrical installation: replacement radar indicator by MFD Garmin GMX200 and/or Concord Batteries.		Airplane Flight Manual Supplement: 06/2008-AFMS GMX 200/Limitation-Ed. 1 Rev. 0 Mars 2008.	1. The approval is limited to MSN T-276 F-GLLO;2. Useof GMX 200 limited to radar weather display function;3. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will int...	08/04/2008	Active	10015138
EASA.A.S.03495	SWS CERTIFICATION SERVICES Ltd.		CAA UK RESPONSIBILITY	BAE 146	STG Aerospace Wireless Emergency Primary Power System (WEPPS) Installation.		- Certification Plan 3011-CEP-01.- Compliance Report 3011-COM-01	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	08/12/2008	Active	10015139

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03496	BUSINESS AND COMMUTER AIRCRAFT		DGAC AAC NO. 751	BEECH 1900C, AIRLINER	Installation of a King/ Bendix KLN-90B GPS with B-RNAV capacity.Note: This STC revises DGAC approval AAC No. 751.		STC TRANSAIR No. 524 Revision 6, dated 09-01-2008.	1. The supplemental AFM No. TF524PA must be used when the modification is installed.2. Limited to S/N UC-168, F-GVLC and UC-153, F-GNPM.	28/02/2008	Active	10015140
EASA.A.S.03499	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	CESSNA 208	Installation of Garmin GNS430 and GTX330 Mode "S" Transponder.		Master Document List PADS/MDL/1113/001 Rev. AAFM Supplements PADS/FMS/208/001 Rev. APADS/FMS/208/002 Rev. A.		19/03/2008	Active	10015141
EASA.A.S.03502	LUFTHANSA TECHNIK AG	REV 1	LBA STC LBA. 21E2.TA0270	BOMBARDIER CL-600-2B19	Replacement of Zonal Dryer related to EASA AD 2006-0140-E.The above reference EASA AD required the de-activation of Zonal Drying Systems installed via LBA STC LBA.21E2.TA0270 due to the potential for combustion of contaminants in the dryerunit. A new dryer unit has been developed which removes this...		STDD21-02/01M, Issue 04STDD21-07/06M, Issue 01, CL-600-EB21-0192AD 2006-0140-E	See related STC LBA. 21E2.TA0270	05/08/2008	Active	10015142
EASA.A.S.03503	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			1329-25	Upgraded Avionics systems:- UNS-1D to UNS-1D+ FMS- Dual VHF-20A system to VHF-22C incl CTL-22C Control Head- Dual DME-42 system with 2 CTL-32C Control Head- Dual VIR-30 NAV systemwith 2 CAD-31 Control Adapter- Altimetry system with a IS&SAir Data System containing 2 9D-80130-32 ADDU, 1 9B-81040-17...		- Master Data List, Doc. No. AD741-049, Rev. IR or latest approved revision- Master Data List, Doc. No. AD744-049, Rev.IR or latest approved revision- AFMS, Doc. No. AD744-071, Rev. IR or latest approved revision- AFMS, Doc. No. 03-3510-01/05, Rev. IR or latest approved revision- AFMS, Doc. No. ES1...	Reg.: HB-JGK S/N: 5233Valid for this S/N only.	14/07/2008	Active	10015143
EASA.A.S.03504	LUFTHANSA TECHNIK AG	REV 1	LBA STC LBA. 21E2.0307	BOEING 737-700	Replacement of Zonal Dryer related to EASA AD 2006-0140-EThe above reference EASA AD required the de-activation of Zonal Drying Systems installed via LBA STC LBA.21E2.0307 due to the potential for combustion of contaminants in the dryer unit. A new dryer unit has been developed which removes this co...		STDD00-00/02M, Issue 06STDD21-07/06M, Issue 01, B737-EB21-0193AD 2006-0140-E	See related STC LBA. 21E2.0307	05/08/2008	Active	10015144
EASA.A.S.03505	LUFTHANSA TECHNIK AG	REV 1	LBA STC LBA. 21E2.TA0636	BOEING 737-800	Replacement of Zonal Dryer related to EASA AD 2006-0140-E.The above reference EASA AD required the de-activation of Zonal Drying Systems installed via LBA STC LBA.21E2.TA0636 due to the potential for combustion of contaminants in the dryerunit. A new dryer unit has been developed which removes this...		STDD00-01/07M, Issue 02STDD21-07/06M, Issue 01, B737-EB21-0195AD 2006-0140-E	See related STC LBA. 21E2.TA0636	05/08/2008	Active	10015145
EASA.A.S.03507	LUFTHANSA TECHNIK AG	REV 1	LBA STC LBA. 21E2.TA0609	AIRBUS A330-200	Replacement of Zonal Dryer related to EASA AD 2006-0140-E.The above reference EASA AD required the de-activation of Zonal Drying Systems installed via LBA STC LBA.21E2.TA0609 due to the potential for combustion of contaminants in the dryerunit. A new dryer unit has been developed which removes this...		STDD21-02/03M, Issue 03STDD21-07/06M, Issue 01, A330-EB21-0194AD 2006-0140-E	See related STC LBA. 21E2.TA0609	05/08/2008	Active	10015147
EASA.A.S.03508	E.I.S. AIRCRAFT GmbH			BOEING 737-700	Cabin reconfiguration.		N/A	Applicable for B737-700 MSN 28609.	15/04/2008	Active	10015148
EASA.A.S.03511	AERO-DIENST GMBH & CO. KG			35A	Flight Crew Intercom System (NAT)		As oer Certification Program 243-LR, Rev. IR (or later approved revisions).AFM Supplement AG711-071 Rev IR (or later approved revision).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	10/07/2008	Active	10015150

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03512	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12	Replacement of existing KX 165 COM / NAV, KLN 90B GPS, and GTX 330D Mode S Transponder installation by GNS480 COM / NAV/ GPS and GTX 33D Mode S Transponder installation.		EASA approved Engineering Data, Doc. No. 2007-23, Revision B, dated 25-Jul-2008, or later approved IssueEASA approved Airplane Flight Manual Supplement, Doc. No. 2007-23-8, Revision A, dated 16-Jan-2008, or later approved IssueMaintenance Manual Supplement, Doc. No. 2007-23-10, Revision B, dated 02-...	Limited to single GNS 480 installation per cockpit only.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of theT...	17/10/2008	Active	10015151
EASA.A.S.03513	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12	Installation of AIRCELL SATCOM ST3100		1. EASA approved Engineering Data, Doc. No. 2007-24, Revision C, dated 01-Oct-2008, or later approved Issue.2. EASA approved Airplane Flight Manual Supplement, Doc. No. 2007-24-8,Revision A, dated 11-Jan-2008, or later approved Issue.3. Maintenance Manual Supplement, Doc. No. 2007-24-10, Revision B...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modificationand any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. 2. The installation of this modification b...	14/10/2008	Active	10015152
EASA.A.S.03516	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	HAWKER HS 125-700 SERIES	Dual FMS Upgrade.		¿ Master Document List MDL961001 issue 1 ¿ Modification Statement HL/MOD/961¿ AFM Change Sht AFMS961001 Issue 1¿ AFM Supplement AFMS961002 Issue 1¿ Instructions for Continued Airworthiness ICA961001 issue 1	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. AFM Supplement AFMS961002 Issue 1	14/08/2008	Active	10015153
EASA.A.S.03519	SCHERDEL ENGINEERING Ltd.			SCHEMPP NIMBUS 4M SCHEMPP JANUS CM DG 800A DG 600M DG 500 M DG 400	Alternate fuel lines for Rotax engine powered glider.		Scherdel Engineering, Technical Note TN2-Alternate Fuel Lines for Rotax powered Glider, Doc number08-Alternate Fuel Lines-001, Revision 1	For all serial numbers.	11/06/2008	Active	10015154
EASA.A.S.03520	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			LEARJET 60	Installation of Iridium SAT/COM Antenna (Sensor Systems)		As noted in Master Data List 745-049, rev. IR (or later approved revisions)	Installation of the Iridium SAT/ COM antenna and the antennacoax outlet as covered by this STC does not constitute an approval of the utility system installation or operation.	22/04/2008	Active	10015155
EASA.A.S.03523	UNI AIR ENTREPRISE SASUNI AIR ENTREPRISE			MYSTERE FALCON 20	Installation of a forward partition door between entry areaand cabin		Modification i.a.w Uni Air Enterprise Master Data List MDL-010-08 Revision 1, dated 14th May 08 or later approved revisions;Uni Air Enterprise Airplane Flight Manual Supplement UAE-AFMS-08-001 Edition 01, dated 13th May 2008 or later approved revisions.	Design change applicable to Mystere Falcon 20 aircraft serial number 311.	19/05/2008	Active	10015156
EASA.A.S.03524	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	737-700	Introduction of Seat-track mounted 40 Inch Closet-Boeing 737-700.		Aerospace Design & Engineering Consultants Ltd.ModificationSummary Document MOD-0352 Rev. AAircraft Manual Supplement – MSN28630Aircraft Manual Supplement – MSN28635Component Maintenance Manual (CMM) 25-30-05	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	28/11/2008	Active	10015157

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03526	LUFTHANSA TECHNIK AG			AIRBUS A318-112	A318 ELITE - Project Comlux 2; VIP Cabin completion		Supplemental Type Definition Document, ref. Doc. No. STDD00-08/01M, issue 01, dated 10. December 2008, or later approved revisionAeroplane Flight Manual Supplement A-00-08/772-AFMissue 1, dated 13. November 2008, or later approved revisionInstructions for Continued Airworthiness, ref. Doc. No. A-00...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	12/12/2008	Active	10015158
EASA.A.S.03527	FRANCE AVIATION			BEECH A36	FA 06/2008 Rev. 2 - Avionic change with B-RNAV/SID/STAR/GNSS andconventional non-precision approaches privileges with AP coupling.		None	None	06/07/2009	Active	10033540
EASA.A.S.03528	AVIONIK STRAUBING ENTWICKLUNGS GmbH			C. SA227 CC, SA227 DC B.SA226-TC, SA227 AC, SA227 BC A. SA26-AT, SA26-T, SA226 T(B) A. SA227-AT, SA227-TT A. SA226-AT, SA226-T	Installation of honeywell Mark VI EGPWS - Optional installation of Comant CI401-220 GPS Antenna.		Installation must be in accordance with Avionik Straubing Master Document List Doc. No. ASR 2007-144-MDL-01-00 Amendm. 00 dated 20.12.07 or later Approved Revisions.Operation mustbe in accordance with Avionik Straubing Flight Manual Supplement No. ASR 2007-144-FMS-05-00 Amendm. 00 dated 15.12.07 or...		06/05/2008	Active	10015159
EASA.A.S.03529	TENENCIA Ltd.	REV. 1	CAA UK RESPONSIBILITY	AVRO 146-RJ70	VIP Installation		1. Modification TEN 549.2. BAe 146 Series VIP Installation Issue 1 dated 28 October 2008.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	19/06/2009	Active	10015160
EASA.A.S.03530	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 525A CESSNA 525	Upgrade of existing Dual Honeywell MST 67A Mode-S XPDR Installation to EHS Capabilities		EASA approved Engineering Data, Doc. No. 2007-17, Revision B, dated 01-Jul-2008, or later approved IssueEASA approved Airplane Flight Manual Supplement, Doc. No. 2007-17-8, Revision A, dated 18-Jan-2008, or later approved IssueMaintenance Manual Supplement, Doc. No. 2007-17-10, Revision A, dated 18-...	For variant 525 this change is limited to serial numbers 525 0360 and subsequent	07/07/2008	Active	10015161
EASA.A.S.03534	AVIONITEC Ltd.			PA-46-350P	Avionics upgrade to GNS 430, Removed Equipment:- KX-165 NAV/COM 2- KI-206 NAV 2 IndicatorInstalled Equipment- GNS-430 NAV/COM/GPS 2- GI-106A NAV/GPS Indicator 2- GA-56 GPS 2 Antenna		- Master Document List, Doc. No. 073723-017, Rev. 1- AFMS, Doc. No. 073723-011, Rev. 1	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.Reg.: HB-PPH, S/N: 4636045	30/06/2008	Active	10015163

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03536	AERODATA AG	REV. 1		550	Additional Cockpit Information DisplayThe current STC EASA.A.S.03536 covers the installation of an Aerodata Flight Inspection System (FIS). To further reduce the required verbal communication and therefore the workload of the cockpit crew and the FIS operator an additional optional Information Displ...		Master Document List MDL-A/C-137 Revision 2Airplane Flight Manual Supplement AFM-095 Revision 1Airplane Maintenance Manual Supplement AMM-952 Revision 1	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product. The installation of this modification by th...	26/01/2009	Active	10015166
EASA.A.S.03537	JET AVIATION AG, BASEL			MYSTERE FALCON 20	Installation of a Honeywell MK VIII Enhanced Ground Proximity Warning System (EGPWS).		• Master Data List BDMET063-001, Revision B dated 19th June 2008.• Airplane Flight Manual (AFM) Supplement BDMET063-201-25, Rev. B, dated 19th June 2008• Instructions forContinued Airworthiness BDMET063-150-25, Revision IR, dated01st May 2008• Engineering Order BDMET063-344600, Revisio...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.This STC is limited to Mystere Falcon 20-E5 aircraft ser...	24/06/2008	Active	10015167
EASA.A.S.03538	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	CESSNA 525	Dual Garmin GPS/NAV/COM Upgrade.		Mod. Ref. TAL-TAD 005/08MDL.00508, Rev.AAFM Supplement - FMS.00508 Rev.A.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	26/05/2008	Active	10015168
EASA.A.S.03539	AIRLEC AIR ESPACE			SA226-T(B)	Stretcher Installation: New stretchers installation put in the aircraft with storage place and O2 botle space.		Airplane Flight Manual Supplement: "Supplement Manuel de Vol SA226-T(B) - Installation civiere" Edition 1, Juillet 2008Aircraft Maintenance Manual Supplement: "Supplement Manuel de Maintenance SA-226t(B) - Installation civiere" Edition 1, Juillet 2008.		06/02/2009	Active	10015169
EASA.A.S.03544	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH 400A BEECH 400	Mode S ELS/EHS Upgrade of existing transponder system.		Engineering order 2042065-EO issue 2.AFMS 2042065-AM issue 1.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	10/06/2008	Active	10015170
EASA.A.S.03545	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12	Installation of Honeywell EGPWS MK VI by installing a Honeywell EGPWS MK-VI.		Engineering order, Doc. No. 2007-22, Rev. B or latest approved revision.AFMS, Doc. No. 2007-22-8, Rev. B or latest approved revision.		13/10/2008	Active	10015171
EASA.A.S.03550	J & C ENGINEERING SERVICES Ltd.		CAA UK RESPONSIBILITY	BOEING 767-200	Approval of Galley and Crew Rest Installation.		J&C Engineering Services Modification JC/MOD/1428 Issue 1.1, 10/06/08.		12/06/2008	Active	10015175

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03553	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 737-300	Carriage of Horses & Grooms		¿ Master Document List S21. MDL-0524 Issue 5* ¿ Airplane Flight Manual Supplement S21. FMS-0047 Issue 1* ¿ Instructions for Continued Airworthiness S21. TEC-192 Issue 1**or later approved revisions of those documents.	1. This design change is applicable to Boeing 737-300 aircraft converted under FAA STC SA2968SO, SA2969SO, and SA2970SO & SA2971SO as previously been validated by the UK CAA under Airworthiness Approval Note AAN 24984.2. The certification basis has been amended with the following CRIs:¿ D-0...	07/04/2009	Active	10015176
EASA.A.S.03554	LUFTHANSA TECHNIK AG			AIRBUS A318-112	A318-112 - ELITE - Project HKInstallation of a VIP cabin for a maximum of 19 passengers for commercial and non-commercial operation. The design details are described in General Description S-00-08/731.		• Supplemental Type Definition Document, ref. Doc. No. STDD00-08/03M, issue 01, dated 27 January 2009, or later approved revision• Aeroplane Flight Manual Supplement A-00-08/835-AFM issue 1, dated 16 January 2009, or later approved revision• Instructions for Continued Airworthiness, ref. Do...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	28/01/2009	Active	10015177
EASA.A.S.03556	AIR ALLIANCE GmbH	REV. 1		300	Installation of L3 FDR1000; Collins EGPWS Mark VI; Honeywell CAS 67 & Dual MST 67A Mode S Diversity Transponder; Artex 406-2 ELT		The installation of the equipment shall be done in accordance with Air Alliance Engineering Order 2008_014_A24CE_0500, Revision 00,Issued 20.06.2008, or later EASA approved revision.Operation in accordance with the applicable AFMS as per Air Alliance Engineering Order 2008_014_A24CE_0500, Revision 0...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	20/06/2008	Active	10015178
EASA.A.S.03557	NSE			PA-25-235	Modification of radio electrical installation.Installation of AG-NAV2 GPS spreading guidance system not to be used for navigation, in accordance with "Fiche d'approbation de conception d'une évolution No. 53/2007, rev.3 dated 12/12/08".		None.	Limited to S/N 25-74-05726, 25-3109, 25-3704, 25-3984, 25-4382, 25-3292,25-2400, 25-4445.	21/01/2009	Active	10015179
EASA.A.S.03558	JET AVIATION VIENNA GMBH			550	Upgrade of SSR Transponder System to Enhanced Surveillance.		Certification Report C550-ARS34-003, Rev. 1, 23.06.2008Engineering Bulletin EB-C550-ARS34-003, Rev. 0, 02.05.2008Airplane Flight Manual Supplement C550-ARS34-003-M1-AFM, Rev. 1, 23.06.2008Instruction for Continued Airworthiness C550-ARS34-003-M1-IFCA, Rev. 0, 02.05.2008		26/06/2008	Active	10015180
EASA.A.S.03560	DASSAULT FALCON SERVICE			FALCON 900EX	Falcon 900C and F900EX: Incorporation of Runway Awareness and Advisory System (RAAS) Function software version 224-224 on EGPWS Honeywell Mk V		DFS Master Document List DFS-DE-17-F9-9541 Issue A1 or later approved revisions.DFS Change Approval Sheet DFS9541-CAS Issue A1 or later approved revisions.DFS AFM Supplement F900-027 Original Issue (dated 09th June 2008) or later approved revisions.DFS Maintenance manual Supplement SMM 31-95-11-A2 (...	As per applicability defined on DFS Change Approval Sheet DFS9541-CAS Issue A1 or later approved revisions this STC is limited to those Falcon 900C and Falcon 900EX aircraft previously equipped with:• Honeywell EGPWS Mk V Soft. 212-212 with terrain display on EFIS Honeywell DU-870 with BZ control...	10/06/2008	Active	10015181

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03561	AERODATA AG			PC-12	Modification as surveillance aircraft		1. According to Aerodata Master Document List Doc. No. MDL-A/C-138 Rev. 1, or later Revisions.2. To be operated in accordance with Aerodata AFM-S Document No. AFM-100, Rev. 0, or later approved Revisions.3. To be maintained i.a.w.Aerodata AMM Document No. AMM-983, Rev. 0, or later Revision...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by...	11/11/2008	Active	10015182
EASA.A.S.03563	SCANDINAVIAN AVIONICS DESIGN ApS			114, 114A, 114B, 114TC 112,B, TC, TCA, 114A, B, TC	Replacement of existing COM 1 / 2 and NAV 1 / 2 systems by Garmin GNS 530 (GNS 1) and Garmin GNS 430 (GNS 2)		EASA approved Engineering Order, Doc. No. 2046711-EO, Issue1, dated 21-Apr-2008, or later approved IssueEASA approved Airplane Flight Manual Supplement, Doc. No. 2046711-AM, Issue 1, dated 21-Apr-2008, or later approved IssueInstructions for Continued Airworthiness, Doc. No. 2046711-CA, Issue 1, da...	This change is limited to the configuration of aircraft / equipment type as listed under Item 4. of EASA approved Engineering Order, Doc. No. 2046711-EO, Issue 1, dated 21-Apr-2008 or later approved issue.	17/06/2008	Active	10015183
EASA.A.S.03565	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		CAA UK RESPONSIBILITY	FAN JET FALCON SERIES D AND E FAN JET FALCON BASIC	P-RNAV Compliance Demonstration, as per FR Aviation Design ChangeStatement DC-0133		- FR Aviation Design Change Statement DC-0133 Issue 1 *- FRAviation Flight Manual Supplement FRAH/FM/100, Revision 10*- Instructions for Continued Airworthiness ICA-0l33, Revision A**Or later EASA Approved revisions of these documents.	1. Design Change applicable to those Fan Jet Falcon Basic and Fan JetFalcon series D and Eon which FR Aviation STC EASAAS.00510 (Rockwell Collins Proline 4) havebeenpreviously embodied. 2. Prior to installation of this modification the installer mustdetermine that theinterrelationship between this mo...	02/06/2009	Active	10043135
EASA.A.S.03568	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOMBARDIER BD-700-1A11	Introduction of Passenger Cabin Interior.		- STC Twenty One Ltd Master Document List S21.MDL-0532 dated 09 December 2008 or later approved revision.- STC Twenty One Ltd Flight Manual Supplement S21.FMS-0048 Issue 1 or later approved revision.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	23/12/2008	Active	10015185
EASA.A.S.03570	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	CESSNA 525	Upgrade of Mode S transponders for enhanced surveillance.		Lees Avionics Ltd Modification HL/MOD/941Instructions for Continued Airworthiness ICA941001.Flight Manual SupplementsAFMS941001 Issue 1AFMS941002 Issue 1AFMS941003 Issue 1		13/06/2008	Active	10015186
EASA.A.S.03571	E.I.S. AIRCRAFT GmbH			SOCATA TBM 700	Avionics Upgrade to Garmin GTX330D diversity Mode S Transponder.		Installation must be in accordance with EIS Aircraft GmbH Master Document List MDL 70S21010 Iss.00, dated 27.07.08 or later approved revisions.Operation must be in accordance withEIS Aircraft GmbH Flight Manual Supplement FM 70S21010-91501 Issue 00, dated 01.07.08 or laterapproved revision.Maintena...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	14/08/2008	Active	10015187

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03572	E.I.S. AIRCRAFT GmbH			BEECH C90KING AIR BEECH C90 A	Installation of dual Rockwell/Collins TDR 94D diversity mode-s transponder.		Installation must be in accordance with E.I.S. Aircraft GmbH Master Document List MDL 90C21011 Issue 02, dated 19.12.08or later Approved revisions.Operation must be in accordancewith E.I.S. Aircraft GmbH Flight Manual Supplement 90C21011-91501 Issue 01, dated 01.07.08 or laterapproved revision.Mai...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	19/12/2008	Active	10015188
EASA.A.S.03573	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	BN2 ISLANDER SERIES	Installation of Garmin GNS430		Phoenix Aviation Design Services Limited Major Change PADS/CP/ 1121Flight Manual Supplement PADS/FMS/ BN2/009 Rev A	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.The installation of this modification by third persons i...	13/06/2008	Active	10015189
EASA.A.S.03574	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 525A CESSNA 525	Installation of GARMIN GPS 400 (w) or 500 (w)		¿ EASA approved Engineering Data, Doc. No. 2008-2, Revision B, dated 11-Feb-2009, or later approved Issue¿ EASA approved Airplane Flight Manual Supplement, Doc. No. 2008 2 A8, Revision D, dated 03-Mar-2009, or later approved Issue ¿ Maintenance Manual Supplement, Doc. No. 2008-2-10, Revision...	1. For approved Software Versions refer to Airplane Flight Manual, Section II - Limitations2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse e...	28/04/2009	Active	10015190
EASA.A.S.03575	AVIONITEC Ltd.			114	Avionics RetrofitRemoved Equipment:- KMA 20 Audio Panel- Isocom Intercom- Dual KX 155 COM/NAV- KI 203 NAV 2 Indicator-GPS 1, Garmin GPS 100 incl. Antenna- OEM vacuum Directional Gyro- KT 76A Transponder- Narco ELT 10New installed Equipment:- GMA 340 Audio Panel- Dual GNS 430 COM/NAV/GPS with GA 5...		- Master Document List, Doc. No. PE8100-017, Rev. 1 or latest approved Revision- AFMS Dual GNS 430, Doc. No. PE8100-011, Original Issue or latest approved Revision- AFMS SN3500 HIS, Doc. No. PE8100-012, Original Issue or latest approved Revision- AFMS EX500 MFD, Doc. No. PE8100-013, Original Issue o...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	23/12/2008	Active	10015191
EASA.A.S.03576	AIR AMBULANCE TECHNOLOGY GmbH			BEECH 200 B200 / A100-1	Installation of Air Medical Interior.		Component-, Installation-, Operation-Manual , Illustrated part Catalog Beeck 100/200 Air Ambulance Equipment, P/N 100/200-25-20-15.000, CMM-Beech-AAT67Airplane Flight Manual: Beech 100 Supplement, Air Ambulance Equipment Beech 100 King AirP/N 100-25-20-15.000, AFM AAT 49Beech 200 Supplement, Air Am...		17/06/2008	Active	10015192

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03577	CESKA LETECKA SERVISNI A.S.			CESSNA 414A CESSNA 414	Avionics upgrade		AC172-2501 SUPPLEMENT GARMIN GTX 327 MODE A/C TRANSPONDER (XPDR) AC172-2502 SUPPLEMENT GARMIN GTX 330 MODE STRANSPONDER (XPDR) AC172-2503 SUPPLEMENT ME-406 ELTAC172-2504 SUPPLEMENT Audiopanel GMA-347AC172-2505 SUPPLEMENT NAV/ COM/GPS1 – GNS-430wAC172-2506 SUPPLEMENTAC1...		16/12/2008	Active	10015193
EASA.A.S.03580	SCANDINAVIAN AVIONICS DESIGN ApS			HAWKER HS 125-700 SERIES HAWKER HS 125-600 SERIES BAE 125 -800 SERIES	Installation of a Digital Flight Data Recorder.		Installed in accordance with 2047003-EO Engineering Order Issue 2 or later approved revision.Operated in accordance with 2047003-AM AFM supplement Issue 1 or later approved revision.Maintained in accordance with 2047003-CA Instructions forContinued Airworthiness Issue 1 or later approved revision....	1. Prior to installation of this modification the installermust determine that the interrelationship between this modificationand any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. 2. The installation of this modification b...	15/06/2009	Active	10015194
EASA.A.S.03581	SOCIETE AIR FRANCE S.A.	REV 1		BOEING 777-300 BOEING 777-200	ADS-B Out Activation.		AFMS-B777-07-023CAS_B777_07_023_rev0_11Jul08	None.	05/09/2008	Active	10015195
EASA.A.S.03582	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			PIPER PA-44-180	Modification d'installation B-RNAV : pose Annonciateur DWA 1000		1) Fiche de Modification SEAM 2080/08/FACE/ SEAM Edition :1 Révision 3 du 22/08/08Annexe C1 – Plan d'implantation des équipements +Annexe C2 – Plan électrique Edition 1 Révision1 du 28/07/08Annexe C3 – Supplément No1 au manuel de volAnne...	L'installation de ce STC est limitée au PA44-180 S/N 4479953081 L'utilisation du GPS en approche et sur SID's et STAR est interdite1 Pré-requis: FAM 2004/08 "Pose GNS 430" suivant la modification approuvée EASA.A.C.096471 Avant installation de cette modification, l'installateur doit s'assu...	30/09/2008	Active	10015196
EASA.A.S.03587	AUSTRIAN AIRLINES AG			F28 MARK 0070, F28 MARK 0100	Installation of mechanically timed water faucet in Fokker F28 Mark 0070, Fokker F28 Mark 0100.		Supplemental Type Definition Report Nr: STDR-FKR-38-0001-02.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	31/03/2009	Active	10015197
EASA.A.S.03589	AIRBUS S.A.S.			A320-214	Airbus Corporate Jet Centre Modification CJ0356 Issue 1 –AFM Supplement - VIP Interior: Shining Star No. 2		Modification Approval Sheet ref.: CJ0356 Issue 1, dated 06th June 2008AFM Supplement: FM-S MOD CJ0103, dated 06/06/08		06/06/2008	Active	10015198
EASA.A.S.03590	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	BOEING 767-200	Introduction of Change 7.0 ACAS II and Dual Mode S		STC 21 Master Data List S21.MDL-0543 Initial issue, 12/06/2008		12/06/2008	Active	10015199

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03592	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	A320-232	A320 In Flight Entertainment – IFE – Upgrade		¿ Compliance Plan and Checklist, ref. ADC14/ JN116, Issue3, dated 24th October 2008¿ Master Data List, ref. ADC17/ JN116, Issue 2, dated 23rd October 2008¿ CAANZ Approved Flight Manual Supplement – Airbus A320-232 Panasonic EFX IFEUpgrade, ref. TMA6012503, dated 4th September 2008 ¿ Decla...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.	29/10/2008	Active	10015200
EASA.A.S.03597	JET AVIATION AG, BASEL			GULFSTREAM IV	FMS Upgrade Installation new EHSI 4000. NZ2000 SW 6.0 Installation, NewCDU CD-820.		- Master Data List, doc. no. GHIMY221-001, Rev. IR- AFMS (EHSI), doc. no. GHIMY221-201-06, Rev. IR- AFMS (FMS), doc. no. GHIMY221-201-14, Rev. IR- ICA (EHSI), doc. no. GHIMY221-150-06, Rev. IR- ICA (FMS), doc. no. GHIMY221-150-14, Rev. IR	Reg.: HB-IMY, S/N: 1084	18/05/2009	Active	10043088
EASA.A.S.03598	JET AVIATION AG, BASEL			GULFSTREAM IV	Wireless LAN (WLAN) Activation.		Master Data List Doc. No. BGLF423261-001AFM Supplement Doc.No. BGLF423261-201-01	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	28/08/2008	Active	10015201
EASA.A.S.03599	SCHERDEL ENGINEERING Ltd.			SCHEMPP CIRRUS	Standard Cirrus: Weight of nonlifting parts increase with winglets.Doc. No. 07-278-005, rev. 2.Doc. No. 07-278-006, rev. 3		Flight Manual: pages to be exchanged 2B, 3, 3A, 3,B, 11, 12, 1Aa, 12B, 14, 14A, 18A.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsV...	02/10/2008	Active	10015202
EASA.A.S.03603	MT-PROPELLER ENTWICKLUNG GmbH			M7 AEROSPACE SA26-AT	Installation of 5-blade MT-Propeller Model MTV-27-1-E-C-F-R(G)/CFR210-58a propellers.		According to MT-Propeller Master Drawing List Doc. No. E-1677 and MT-Propeller Installation Instruction Doc. No. E-1665, original issue, or later RevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-1664, original issue, or later approved RevisionsTo be maintained i.a.w. MT-P...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	02/10/2008	Active	10015203
EASA.A.S.03604	MT-PROPELLER ENTWICKLUNG GmbH			PIPER PA-42-720 PIPER PA-42	Installation of 4-blade MT-Propeller Model MTV-16-1-E-C-F-R(P)/CFR230-37b propellers.		According to MT-Propeller Master Document List Doc. No. E-1682 and MT-Propeller Installation Instruction Doc. No. E-1671, original issue, or later RevisionsTo be operated in accordance with MT-Propeller AFM-S Document No. E-1670, original issue, or later approved RevisionsTo be maintained i.a.w. MT-...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	02/10/2008	Active	10015204

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03606	AIR ALLIANCE GmbH			CESSNA 525A 525	Exchange of GPS Navigation System KING KLN 900 against Flight Management System Universal UNS 1Lw		EASA approved Master Document List, Doc. No. 2008_034_A1WI AA Form 2, Revision 1, dated 11-Aug-2008, or later approved RevisionEASA approved Airplane Flight Manual Supplement, Doc. No. 2008_034_A1W1_0506, Revision 1, dated 07-Aug-2008,or later approved revisionAir-Alliance released Instructions fore...	1. This STC is only eligible for aeroplanes equipped with GPS Receiver System KLN 900 and Collins Pro Line 21 Avionic System2.Prior to installation of this modification theinstaller must determine that the interrelationship between this modification and any other previously installed3.Th...	12/08/2008	Active	10015205
EASA.A.S.03619	JET AVIATION AG, BASEL			AIRBUS A319-133	Wireless Local Area Network (WLAN) Activation		¿ Master Data List, ref.Doc. BA31923262-001, Rev. A, dated 13.08.08 ¿ Certification Compliance Sheet, ref. Doc. BA31923262-102-01, Rev. A, dated 12.08.08 ¿ Airplane Flight Manual Supplement, ref. BA31923262-201-01, Rev. IR, EASA approval date 13.08.08¿ Instruction for Continued Airworthine...	None	13/08/2008	Active	10015206
EASA.A.S.03623	SOGERMA SERVICES			DHC-6-300	S-53-2039 Structural Provision for Insrument Panel.		MAS S-53-2039 Issue 3 dated 26 August 2008.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsT...	27/08/2008	Active	10015208
EASA.A.S.03624	JET AVIATION VIENNA GMBH			550	Installation of an L-3, Model F1000 Solid State Flight DataRecorder including accessories.Amendment of Austrian STC ACG.21E.062.		¿ Compliance Report CR-C550-ARS31-001, Rev. 0, 04.06.2008¿ Engineering Bulletin EB-C550-ARS31-001, Rev. 0, 20.05.2008 ¿ Maintenance Manual Supplement C550-ARS31-001-M1-MMS, Rev. 0, 21.05.2008¿ Airplane Flight Manual Supplement C550-ARS31-001-M1-AFM, Rev. 0, 04.06.2008	None.	30/06/2008	Active	10015209
EASA.A.S.03625	AIRBUS S.A.S.		DGAC STC 180-SF-0227	A320 SERIES	Installation of a cabin VIP (Aeroservices) in accordance with the Service Bulletin SOG-WD-00-00-01 (or later approved revision)		Supplement no 180-SF-0227 to data sheet no 180Service Bulletin SOG-WD-00-00-01 (or later approved revision)		04/07/2008	Active	10015210
EASA.A.S.03626	AIRBUS S.A.S.		DGAC FRANCE 180-SF-0187	A320 SERIES	Cabin Conversion of one A319 corporate jet (A319 CJ)		- Sogerma document no SOG-01-128 issue 3, dated February 22, 2002		07/07/2008	Active	10015211
EASA.A.S.03627	AIRBUS S.A.S.		DGAC FRANCE STC 180-SF-0212	A320 SERIES	Cabin Conversion of one A319 Corporate Jet (A319 CJ)		Type Certificate Data Sheet no 180 and its supplement no 180-SF-0212, with deviations identified and listed in the Certification Basis document, CRI G-4102 issue 3, dated November26, 2003Sogerma document no SOG-01-275 issue 5, dated November 27, 2003		07/07/2008	Active	10015212

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03628	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			LEARJET 31	P-RNAV Compliance Demonstration		As per Master Document List EE759-049, rev. IR (or later approved revisions)	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	25/08/2008	Active	10015213
EASA.A.S.03629	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			BEECH 200	Modification d'installation transpondeur Mode S: dépose 2 transpondeurs KXP 755 + Boite de commande + 2 antennes ATC / Pose 2 transpondeurs GTX 330D + 4 antennes ATC		Modification effectuée selon le document S.E.A.M « Fiche demodification 2125/08 », édition 1, révision 0, or later EASA approved revision.Aircraft Flight Manual Supplement document SEAM/SMV/ 2125/08, revision 0, du 30/06/2008, or later EASA approved revision.	1. This modification is valid only for aircraft Beech 200, S/N BB 406.2.2. Prior to installation of this modification the installer must determine that the interrelationshipbetween this modification and any other previously installed modification will introduce no adverse effect upon the airw...	05/08/2008	Active	10015214
EASA.A.S.03630	LUFTHANSA TECHNIK AG			AIRBUS A318-112	A318-112 - ELITE - Project Tanker 1Installation of a VIP cabin for a maximum of 16 passengers for non-commercial operation only. The design details are described in General Description C-AAA024-SPA.		• Supplemental Type Definition Document, ref. Doc. No. STDD00-08/07M, issue 01, dated 18 February 2009, or later approved revision• Aeroplane Flight Manual Supplement A-00-08/873-AFM issue 1, dated 22. January 2009, or later approvedrevision• Instructions for Continued Airworthiness, ref.s...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	20/02/2009	Active	10015215
EASA.A.S.03632	AIR ALPHA MAINTENANCE A/S			B200	Flight Inspection System antenna and equipment interface installation.		- Installation per Air Alpha Accomplishment Instruction AI.EO-B200-25-122 Rev 0 dated 15 October 2008 and Master Drawing List – Antenna & Equipment Interface Installation EO-B200-25-122 dated 6 Nov 2008- Operations per Air Alpha Flight Manual Supplement FMS.EO-B200-25-122 Rev.00 dated 15 Apr 2...	1. The applicability of this STC is limited to B200 S/N:BB-1399.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthine...	17/04/2009	Orphaned	10015217
EASA.A.S.03633	ROEDER PRAEZISION GMBH			CIRRUS SR22 CIRRUS SR20	Installation of Avidyne Iridium MLX770 Two Way Datalink.		- According to Röder Präzision MRL Document No. MR 3400-46-01A, Rev. 3 or later Revisions- To be operated in accordance with approved Röder Präzision AFM-S Document No. 2882AF 3400-46-01A, Original Issue, or later approved Revisions, or- To be operated in accordance with approved Röder Prä...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	03/12/2008	Active	10015218
EASA.A.S.03635	NSE			58	Modification of radio electrical installation for B-RNAV certification with AP coupling		Dossier de Définition STC 43/2007- DEF Révision 3 datée du 05/11/2008Supplément au Manuel de Vol Beech 58 pour l'utilisation du GPS GNS 530 certifié en moyen supplémentaire de navigation IFR/VFR avec la capacité Basic RNAV couplé au piloteautomatique, Installé suivant le STC BAYO No 43/2007 No de s...	The applicability of this STC is limited to the Beech 58 S/N TH-488Navigation on SID and STARs prohibited in Terminal AreaUtilisation of GPS prohibited for approachesPrior to installation of this modification the installer must determine that the interrelationship between this modification and any o...	14/11/2008	Active	10015220

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03636	COMPAGNIA GENERALE RIPRESEAEREES .p.A. - CGR S.p.A.			PARTENAVIA P68C PARTENAVIA P68					17/07/2009	Active	10028772
EASA.A.S.03637	LEES AVIONICS Ltd.		CAA UK RESPONSIBILITY	PA-42	Upgrade of Mode S transponders for enhanced surveillance.		-,,Installation in accordance with Lees Avionics Ltd. Change numberHL/MOD/994-,,AFMS Lees Avionics Ltd. Supplement 994001, Issue 1, or later EASAapproved revision	none	07/05/2009	Active	10043087
EASA.A.S.03643	AIR ALLIANCE GmbH	REV. 1		525, 525A	Installation of Dual GTX 330D as Replacement of Dual KT 70 or KT 71		AirAllianace Master Document List 2008_036_A1WIAA Form 2, in latest approved RevisionTo be operated in accordance with AFM Supplement Document No 2008_036_A1WI_506, Rev 0, or later approved RevisionsTo be maintained i.a.w. ICA Document No 2008_036_A1WI_507, Rev 1, or later approved Revisions	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	05/09/2008	Active	10015226
EASA.A.S.03645	JET AVIATION AG, BASEL			BOMBARDIER CL-600-2B16	Aircell Iridium Antenna P/N. 015-10306-001 Installation		Jet Aviation Declaration of Compliance dated 12 August 2008Jet Aviation Master Data List No. B7REPCUS1044-001, RevisionA dated 12 August 2008	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	13/08/2008	Active	10015228
EASA.A.S.03647	AVIONIK STRAUBING ENTWICKLUNGS GmbH			501, 551	Installation of COM/NAV/GS/GPS Garmin GNS430W (AW) or COM/NAV/GS/GNS530W (AW).		1. According to Avionik Straubing Master Document List Doc. No. ASR-2008-065-MDL-01-00 Rev. 00, or later Revisions. 2. To be operated in accordance with approved Avionik Straubing AFM-S Document No. ASR-2008 -065-FMS -05-00, Rev. 00, or later approved Revisions.3. To be maintained i.a.w. Avi...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	18/11/2008	Active	10015229
EASA.A.S.03648	KUERZI AVIATION AG			PILATUS PC-12/47E	FDR and CVR Installation.		1. MDL-200830253 Rev. A or later approved revision2. FMS-200830253 Rev. N/C or later approved revision3. ICA-200830253 Rev. A or later approved revision	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	31/10/2008	Active	10015230
EASA.A.S.03653	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA CITATION C525	Installation of AIRCELL Iridium Dual Patch Satcom Antenna.		- EASA approved Engineering Data, Doc. No. 2008-3, Revision B, dated 27-Apr-2009, or later approved Issue- Maintenance Manual Supplement, Doc. No. 2008-3-10, Revision B, dated 27-Apr-2009, or later approved Issue	1. Antenna Installation only.2. Prior to installationof this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.3. The installa...	12/05/2009	Active	10015231

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03655	BUSINESS AND COMMUTER AIRCRAFT			BEECH B300 BEECH B200 BEECH 300 BEECH 200	Be 'Mode S / Flight ID' capable Collins TDR-94(D) transponders.		¿ The installation will be made in accordance with Business and Commuter Aircraft document BCA108-00, Revision 0, asof 14.08.2008 or later EASA approved revision. ¿ The Aircraft Flight Manual Supplement applicable to this modification is BCA108-03 document, Revision 0, as of 14.08.1008 or late...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	27/04/2009	Active	10015232
EASA.A.S.03658	AERO-DIENST GMBH & CO. KG			35A	Solid State Flight Data Recorder SSFDR Installation (L-3)		As detailed in Certification Program AG748-080, rev. IR (orlater approved revisions).	Prior to installation of this modification the installer must determine that the nterrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product. The installation of this modification by third person...	04/11/2008	Active	10015233
EASA.A.S.03659	AERO-DIENST GMBH & CO. KG			35A	Cockpit Voice Recorder CVR-30B Installation (UASC).		As detailed in Certification Program AG751-080, rev. IR (orlater approved revisions).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	04/11/2008	Active	10015234
EASA.A.S.03660	AERODATA AG			31A	Installation of Aerodata Flight Inspection System (FIS)		As detailed in Master Document List MDL-A/ C-139, rev. 1 (orlater approved revisions)	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	16/10/2008	Active	10015235
EASA.A.S.03664	JET AVIONICS AVIATION & MARINESERVICE CENTER S.r.l.			CESSNA CITATION 501	Installation of Mode S Transponder.		According to Jet Avionics Master Document List Doc. No. BDI005-08-01 and Jet Avionics Installation Bulletin Doc. No. BDI 005-08-03, original issue, or later Revisions.To be operated in accordance with Jet Avionics AFM-S Document No. BDI 005-08-16, original issue, or later approved Revisions.To be m...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	23/12/2008	Active	10015237
EASA.A.S.03665	SABENA TECHNICS BGC	REV. 1		SN 601	Finish Material Change on Aerospatiale SN 601 'Corvette'This STC concerns the change of finish materials in the cabin such as interior linings, seat foam and cover and floor.		Master Data List, ref : 4187-01-A-2103-R01(or any later approved revision of this document, except for referenced document which are approved separately, as ICA for instance).Instruction for Continued Airworthiness, ref : 4187-01-A-2201-R00	This STC is limited to the SN 601 'Corvette' MSNs : 11, 13,30, 31, and 32.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthin...	25/08/2008	Active	10015238

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03666	BUSINESS AND COMMUTER AIRCRAFT			BEECH F90 BEECH E90 BEECH C90A BEECH C90	BCA 110 Rev. 3 - Garmin GNS-x30WA (GNS-530WA or GNS-430WA) and Sandel SN4500 installation for B-RNAV, P-RNAV and GNSS approaches.		AFM Supplement BCA110-07 rev 2, dated 28 November 2008.AMM Aupplement BCA110-06 rev. 0, dated 22 August 2008.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	09/01/2009	Active	10015239
EASA.A.S.03676	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	767-200	Introduction of 12C/241Y Passenger Cabin Configuration and Associated Floor Structure Changes.		AeroDEC Modification Summary MOD-0477, Revision B	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	11/12/2008	Active	10015242
EASA.A.S.03678	S.E.A.M.SERVICE ELECTRONIC AVIATION MARINES.A.R.L.			CESSNA 182R	MODIFICATION D'INSTALLATION B-RNAV avec couplage au pilote automatique		Supplement manuel de vol SEAM/SMV/2127/08 Rev. 0	Limitation to Cessna 182R S/N 182-68316	30/03/2009	Active	10015243
EASA.A.S.03679	AVIONIK STRAUBING ENTWICKLUNGS GmbH			B. 441 A. 421, 421A, 421B, 421C, 425 A. 411, 411A, 414, 414A A. 402, 402A, 402B, 402C A. 401, 401A, 401B	Installation of Single or Dual Garmin G600 Avionics System and dual Garmin GNS4/530(A)W GPS/COMM/NAV		-Project Description: ASR-2008-104-PRD-04-00, Rev. 00-Instructions for Installation: ASR-2008-104-IFI-10-00, Rev. 00-Instructions for Continued Airworthiness: ASR-2008-104-ICA-11-00, Rev. 00-Flight Manual Supplement: ASR-2008-104-FMS-05-00, Rev. 00	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2) The installation of this modification by third pers...	15/06/2009	Active	10015244
EASA.A.S.03681	SOCIETE AIR FRANCE S.A.			BOEING 747-400	ADS-B Out Installation and Activation as per Air France Service Bulletin B747-08-004-34-001 rev. 0 or later approved revisions.		AFMS B747-08-004 Airplane Flight Manual Supplement for B747-400 ADS-B Out Installation.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	10/12/2008	Active	10015245
EASA.A.S.03683	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	DA 42 M (RESTRICTED)	Banbury Modification 001 - FLIR Installation.		JN147 ADC17 Issue 5 – Master Data List.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	07/11/2008	Active	10015246
EASA.A.S.03684	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	HAWKER 700	Introduction of a Sandel ST3400 Class A terrain awareness warning system.		Installation in accordance with Change statement: HL/MOD/1000 Form 1.Operation in accordance with Flight manual supplement: AFMS 1000-01Instructions for continued airworthiness reference : ICA1000-01	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	15/12/2008	Active	10015247

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03687	BELL TEXTRON PRAGUE, a.s.			L-410 UVP-E	Installation of EGPWS Mark VI.		• Flight Manual Supplements:- No: FM 34 41/01 001 (Multi Functional Display KMD 540), dated Nov 11/08- No: FM 34 43/01 001 (EGPWS Mark VI), dated Nov 11/08- No: FM 34 55/01 001 (Radar Altimeter KRA 405B), dated Nov 11/08• Engineering Bulletin:- No: EB 166, dated 11.11.2008	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	24/11/2008	Active	10015248
EASA.A.S.03696	TENENCIA Ltd.		CAA UK RESPONSIBILITY	EMBRAER EMB-135 SERIES	EMB 135 Electronic Flight Bag installation		TEN 582 Issue 2 dtd. 13.5.09 *)-Flight Manual Supplement TEN/ EMB135/001 Issue 2 *)*) or later approved revisiopn	None	29/05/2009	Active	10015251
EASA.A.S.03697	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			BOMBARDIER CL-600-2B16	P-RNAV Compliance		Master Data List No. AC780-049.AFM Supplement Change Sheet No. AC780-071	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	13/10/2008	Active	10015252
EASA.A.S.036S7	2 EXCEL DESIGN LIMITED		CAA UK RESPONSIBILITY	DC-9-32	110Y LOPA (Removal of one row of seats to improve access totype IIIexits to meet localretroactive requirements).		Master Data List MDL/ JN139, issue 1, dated 14 August 2008.	1. Prior to installation of this modification the installermustdetermine that theinterrelationship between this modification and any other previouslyinstalledmodification will introduce no adverse effect upon the airworthiness oftheproduct. The installation of this modification by third persons iss...	20/08/2008	Active	10043136
EASA.A.S.03701	AEROTEC SARL			TB 20	Installation of L3 Communication Stormscope WX500, Garmin audio systemGMA 340 and Garmin GNS 530 W for IFR B-RNAV en-route navigation.		-,,Aerotec Flight Manual supplement no. AE0841SMV, revision0, dated04/02/09-,,Aerotec Instructions for Continued Airworthiness no. AE0841IPMN,revision 0, dated 04/02/09-,,AerotecMaster Data List no. AE 0841 MDL, revision 1, dated 02/03/09	This installation is limited to aircraft TB 20 s/n 1801 which must beequipped with a third radio-communication or radio-navigation meanindependent from GNS 430 and GNS 530 equipment.	07/05/2009	Active	10043086
EASA.A.S.03707	SOCIETE D'ETUDE ET DE GESTIONAERONAUTIQUE (SEGA)			BEECH 1900	Installation of a galley.		Description: “Installation sur avion Beech 1900 d’une Armoire Self-Service” Ref.: Modification A-25-01-08-TwinJet P-EASA.A.S.03707 Edition 0 dated 13 January 2009Master Document List P-EASA.A.S.03707 Ref.: Modification A-25-01-08-TwinJet_MDoL Edition 0 dated 13 January 2009Installation Procedure : “...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	16/01/2009	Active	10015255
EASA.A.S.03713	RUAG AEROSPACE SERVICES GmbH	REV. 1		DC-9-87 (MD-87)	Cabin Layout ChangeModification of existing Iberia 109 passenger economy seat layout to- 20 B/C + 79 E/C seat layoutfor S/N 49832; 49834;49837; 49838; 49840; 49841 and- 12 B/C + 89 E/C seat layout for S/N 49833; 49839; 49842		1. Engineering Order 211D-EO Revision N/C from 10. Oct. 2008.2. Compliance Statements 211D-CS.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	02/12/2008	Active	10015259

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03718	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)	REV 1		390 (PREMIER I/IA)	Iridium SATCOM System Installation (Sky Connect)		Master Data List, Doc. No. 788-049, Revision B, dated 09-Feb-2009, or later approved revisionEASA approved Pilots Information Sheet, Doc. No. 788-091, Revision A, dated 09-Feb-2009,or later approved revisionInstructions for Continued Airworthiness, Doc. No. 788-085, Initial Revision, dated 15-Oct-20...	This change is limited to the configuration of aircraft / equipment type as listed under 3.1 Mechanical Installations",in Engineering Order, Doc. No. 788-062, Revision A, dated 13-Jan-2009, or later approved revision.1 Prior toinstallation of this modification the installer must determi...	09/02/2009	Active	10015260
EASA.A.S.03720	CHRISTEN-AIRTECH AG			CESSNA 210	Avionics UpgradeBy removing the existing:- COM/NAV 1 + 2- DME- Mode A/C Transponder- Audio PanelAnd install the new Avionics Systems:- GNS 530W COM/NAV/GPS 1- GNS 430W COM/ NAV/GPS2 with GI106A GPS/NAV Indicator- KN 62A DME- GTX 330 Mode S Transponder- GMA 340 Audio PanelModels: 210 Series NON PRES...		-Master Document List, Doc. No. 208.2027, Rev. 0 or latest approved Revision- AFMS GNS 530W COM/NAV/GPS 1, Doc. No. 208.2027-FS-01-00, Rev. 0 or latest approved Revision- AFMS GNS430W COM/NAV/GPS 2, Doc. NO. 208.2027-FS-02-00, Rev. 0 or latest approved Revision- ICA, Doc. No. 208.2027-CA-01-00, Rev...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	11/12/2008	Active	10015262
EASA.A.S.03721	AIR ALLIANCE GmbH			DORNIER 228-202 DORNIER 228-201 DORNIER 228-101	Installation of FMS Universal UNS-1Lw.		- Engineering order: 2008_055_2031B_0500, Rev. 00- Instructions for Continued Airworthiness: 2008_055_2031B_0507, Rev. 01- AFM Supplements: 2008_055_2031B_0506, Rev. 03	1. Restricted to aircrafts which have already installed a LH HSI Honeywell KPI552B and two Shadin ADC's ADC2000.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will i...	23/01/2009	Active	10015263
EASA.A.S.03723	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	CESSNA 310	Introduction of EXP5000 electronic primary flying display and dualGNS430W GPS navigation/communication units.		Lees Avionics Limited Change HL/MOD/ 1031Flight Manual Supplements: AFMS1031-01 Issue 1 and AFMS1031-02 Issue 1	None	27/07/2009	Active	10033770
EASA.A.S.03724	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	CESSNA 310	Introduction of a GDC31 autopilot roll steering converter		Lees Avionics Limited Change HL/MOD/ 1032Flight Manual Supplement AFMS1032-01 Issue 1	None	27/07/2009	Active	10033778
EASA.A.S.03728	DASSAULT FALCON SERVICE			FALCON 900	Installation of two Honeywell 12 or 24 Channels GPS sensors(GNSSU)		- Master Document List DFS-DE-17-F9-9119 Issue HI• Aeroplane Flight Manual Supplement DFS Supplement F900-029 OriginalversionOr later EASA approved revisions of these documents.	1. Prior to installation of this modification the installermustdetermine that theinterrelationship between this modification and any other previouslyinstalled modificationwill introduce no adverse effect upon the airworthiness of the product.The installation ofthis modification by third persons ist...	08/07/2009	Active	10043318
EASA.A.S.03729	DASSAULT FALCON SERVICE			FALCON 900					20/07/2009	Active	10028776

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03733	AVIONIK STRAUBING ENTWICKLUNGS GmbH			PA-34-220T PA34-200, PA34-200T	Dual installation of Garmin GNS430W/ GNS430AW/ GNS 430/ GNS530W/ GNS530AWj GNS530.		Installation must be in accordance with Master Document List EngineeringOrder No. ASR2008-125-MDL-OI-00 Amend. 00 dated3~. Jan. 2009 or later ApprovedRevisions.Operation must be in accordance with Flight Manual Supplement No. ASR2008-125-FMS-05.1-00 Amend. 00 (for GNS430W/530W) or ASR 2008-125-FMS-...	1. Prior to installation of this modification the installermustdetermine that theinterrelationship between this modification and any other previouslyinstalled modificationwill introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third persons...	02/06/2009	Active	10043138
EASA.A.S.03736	DASSAULT FALCON SERVICE			MYSTERE FALCON 900 FALCON 900EX	One or two three-places Sofa installation in the aft part of the Cabin.		DFS Master Document List DFS-DE-17-F9-9549 Issue A1 or later approved revisions.DFS Change Approval Sheet DFS9549-CAS Issue A1 or later approved revisions.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third per...	09/01/2009	Active	10015266
EASA.A.S.03738	CTT SYSTEMS AB		CAA NL STC SA 0003 NL	BOEING MD 11	Replacement of Zonal Dryer related to EASA AD 2006-0140-E.The above reference EASA AD required the de-activation of Zonal Drying Systems installed via CAA NL STC SA 0003 NL due tothe potential for combustion of contaminants in the dryer unit. A new dryer unit has been developed which removes this c...		SB3000-002-21-01- AD InitialEASA AD 2006-0140-E or later approved revisions	Instruction for the installation:Installation instruction IIMD11, latest revision, Swissair Engineering Order 510440.Instructions for operation:Airplane Flight Manual Supplement, AFM-98-02, Rev. 0, dated 3-11-98 or latestrevision.Instructions for continued airworthiness:CAR MR11-01 Rev. IR dated 99-...	15/12/2008	Active	10015267
EASA.A.S.03739	MAP AIRCRAFT PART 21 AS	REV 1		BOEING 737-400	Auxiliary Fuel Tank Removal, B737-400.		Master Drawing MAP019A101 Iss. D.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.	16/02/2009	Active	10015268
EASA.A.S.03741	TENENCIA Ltd.		CAA UK RESPONSIBILITY	BOEING 757	78 Seat Installation / This modification consists of: - Removal of existing 200 Economy Seats, - Installation of 78 First Class Seats including 3 Club 4 installations, 2 at the forward and 1 at the aft end of the cabin.		TEN 591	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	30/03/2009	Active	10015269
EASA.A.S.03745	AERODATA AG			300	Installation of an Aerodata Flight Inspection System AD-AFIS-111		¿ EASA approved Master Document List, Doc. No. MDL-A/C-144, Revision 1, dated 10-Mar-2009, or later approved revision¿ EASA approved Airplane Flight Manual Supplement, Doc. No. AFM 104, Revision 0, dated 20-Nov-2008, or later approved revision¿ EASA accepted Maintenance Manual Supplement, D...	1. Airplane must be equipped as stated in Chapter 1.3.1 of EASA approved Aerodata Certification Program, Doc. No. CP-B300-13.01,Revision 0, dated 12-Jan-2009, or later approvedrevision2. Prior to installation of this modification the installer must determine that the interrelationship between...	13/03/2009	Active	10015270

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03748	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	737-300	Carriage of Horses & Grooms		-,,Master Document List S21.MDL-0612 Issue 1-,,Airplane Flight Manual Supplement S21.FMS-0051 Issue 1-,,Instructions for Continued Airworthiness S21.TEC-0203 Issue 1Or later approved revisions of those documents.	1.,,This design change is applicable to Boeing 737-300 aircraftconverted under FAA STC SA2968SO, SA2969SO, and SA2970SO& SA2971SO aspreviously been validated by the UK CAA under Airworthiness ApprovalNote AAN 24984.	18/05/2009	Active	10043085
EASA.A.S.03751	AIRBUS TRANSPORT INTERNATIONAL SNC			A300F4-608ST	Installation of pressure seals on Frame (FR) 10.7.This STC consists in installing two pressure seals on FR10.7 in ordertoallow future avionicsinstallations.		Change Approval Sheet, ref: ST53MOD011 Issue 1 (Any later approved revision).	1) Prior to installation of this modification the installermustdetermine that theinterrelationship between this modification and any other previouslyinstalledmodification will introduce no adverse effect upon the airworthiness ofthe product.This Certificate shall remain valid unless otherwise surre...	31/07/2009	Active	10043319
EASA.A.S.03753	AIR ALLIANCE GmbH			PIPER PA-31T2 PIPER PA-31T1 PA-31T (CHEYENNE/ CHEYENNE II)	Camera Installation Floor Cut Out		According to AirAlliance Master Document List Doc. No. 2008_058_A8EA AA Form 2, Rev. 0, or later approved Revisions andAirAllianceInstallation Instructions 2008_058_A8EA_500, Rev. 0, or later RevisionsTo be operated in accordance with AirAlliance AFM-S Document No. 2008_058_A8EA_506, Rev. 0, or lat...	1 Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2 The installation of this modificat...	21/01/2009	Active	10015271
EASA.A.S.03754	AERO-DIENST GMBH & CO. KG			55	FMS Upgrade to PRNAV Compliance (UASC).		As detailed in Certification Program AG794-080, rev. IR (orlater approved revisions).	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	02/02/2009	Active	10015272
EASA.A.S.03756	AERODISA S.L.			MYSTÈRE FALCON 900 (MF900)	Upgrade of dual Mode S SSR Transponder installation to provide both Elementary Mode S Surveillance Flight ID and Enhanced Mode S Surveillance capability (EHS Capable).		See Aerodisa documents:• Master Data List AED2008-09_F900_EHS_MDL Revision 04• Flight Manual Supplement AED2008-09_F900_EHS_D03 Revision 03• Maintenance Supplement ManualAED2008-09_F900_EHS_D02 Revision 01• Installation ManualAED2008-09_F900_EHS_D01 Revision 03Or later EASA approved re...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by...	27/03/2009	Active	10015273
EASA.A.S.03767	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH B300C BEECH B300 BEECH B200C BEECH B200 BEECH 300LW BEECH 300 BEECH 200C BEECH 200 BEECH 1900C, AIRLINER	Installation of Sandel SA4550 EADI and Sandel SA4500 EHSI CollinsAHS-1000	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.For the change CS-23 has been elected to comply withThe certificated noise and/ or emissions levels of the original productare unchanged...	- EASA approved Engineering Order, Doc. No. 2050691-EO, issue 1, dated25-May-2009, or later approved issue- EASA approved Aircraft Flight Manual Supplement, Doc. No. 2050691-AM,Issue 1, dated 01-Jun-2009 or later approved issue- Approved Instructions for Continued Airworthiness, Doc. No. 2050691-CA,...	This change is limited to the configuration of aircraft / equipment typeas listed under Item 4. in EASA approved Engineering Order, Doc. No. 2050691-EO, issue 1, dated 25-May-2009,or later approved issue.	01/07/2009	Active	10033781

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03768	SCANDINAVIAN AVIONICS DESIGN ApS			B300C, 1900C B200C, 300, 300LW, B300 200, 200C, B200	Installation of Garmin GNS 430AW/GNS 530AW	The Certification Basis for the original product and the followingadditional or alternative airworthiness requirements are applicable tothis certificate/ approval.For the change CS-23 has been elected to comply with.The certificated noise and/ or emissions levels of the original productare unchanged...	- EASA approved Engineering Order, Doc. No. 2051374-EO, issue 1, dated1O-Jun-2009, or later approved issue- EASA approved Aircraft Flight Manual Supplement, Doc. No. 2051374-AMA, Issue 1, dated 14-May-2009 or later approved issue, togetherwith- EASA approved Aircraft Flight Manual Supplement, Doc.B...	This change is limited to the configuration of aircraft / equipment typeas listed under Item 4. in EASA approved Engineering Order, Doc. No. 20S1374-EO, issue 1, dated 10-Jun-2009,or later approved issue.	01/07/2009	Active	10033782
EASA.A.S.03769	SCANDINAVIAN AVIONICS DESIGN ApS			LEARJET 55	Dual Universal UNS-1F FMS Installation.		As noted in Certification Document List 2051373 DOC, issue 1 (or later approved revisions).	• Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.• The installation of this modification by third...	17/04/2009	Active	10015274
EASA.A.S.03770	KUERZI AVIATION AG			PILATUS PC-12/45	GPS 400W and GMA 347 InstallationRemoved Equipment:- KLM 90B GPS- Existing GPS Antenna- KMA 24H Audio PanelNew Installed Equipment- GPS 400W GPS- GA 35 GPS/WAAS Antenna- GMA 347 Audio Panel		- Master Document List, Doc. No. MDL-200830501, Rev. N/C orlatest approved Revision- Declaration of Compliance, Doc. No. DOC-200830501, Rev. N/C- AFMS, Doc. No. FMS-200830501, Rev. N/C or latest approved Revision- ICA, Doc. No. ICA-200830501, Rev. N/C or latest approved Revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	02/03/2009	Active	10015275
EASA.A.S.03773	LUFTHANSA TECHNIK AG			AIRBUS A318-112	A318-100 - ELITE - Project Comlux3. Green aircraft completion to a VIPcabin configuration		- Supplemental Type Definition Document, ref. Doc. No STDDOO-08/16M,issue 01, dated03. Jul. 2009, or later approved revisions- Airplane Flight Manual Supplement, ref. Doc. No. A-00-08/877-AFM issue01, dated 23.Jun. 2009, or later approved revisions- Instructions for Continued Airworthiness, ref. Doc...	Prior to installation of this modification the installer must determinethat the interrelationshipbetween this modification and any other previously installedmodification will introduce noadverse effect upon the airworthiness of the product. The installationof this modification bythird persons is sub...	07/07/2009	Active	10043320
EASA.A.S.03780	VITROCISET S.p.A.		ENAC STC CS-45	500,550	Installation of Honeywell GPWS Mark VI in accordance with MDL600-1700-000-000 datedJan. 8th 2001 or later EASA approvedrevisions.Note:1. This STC reflects the transfer of ENAC STC CS-45 from LEAT S.r.l. toVITROCISET S.p.A2. This STC supersedes ENAC STC CS-45.		None	AFM Supplement Doc. N. 600-1700-800-000 dated Jan. 8th 2001or laterEASA approvedrevisions.This Certificate shall remain valid unless otherwise surrendered orrevoked.	07/01/2009	Active	10043141
EASA.A.S.03781	VITROCISET S.p.A.		ENAC STC CS-060	402B	Ammodernamento avionica ed installazione GPS KLN 94 per operazioniBRNAV.Note:1. This STC reflects the transfer of ENAC STC CS-060 from LEAT S.r.l. toVITROCISET S.p.A.2. This STC supersedes ENAC STC CS-060.		Doc. DRW 400-0901-000 e successive revisioni approvate.	Aircraft Flight Manual Supplement (Allegato N) 1st Edition 16 July 2001e successive revisioniapprovate.This Certificateshall remain valid unless otherwise surrendered orrevoked.	07/01/2009	Active	10043142
EASA.A.S.03782	VITROCISET S.p.A.		ENAC STC CS-071	ENAC STC CS-071	Installation of EGPWS Universal Avionics Systems with GPS 1000 andMFD640< (>,<)>Note:1. This STC reflects the transfer of ENAC STC CS-071 from LEAT S.r.l. toVITROCISET S.p.A.2. This STC supersedes ENAC STC CS-071.		Master Drawing List No. 700-0202-000-000 IR dated 17.06.2002 and laterapprovedrevisions.	Included in the Supplemental Flight Manual No. 700-0202-800-000 Rev. IRdated 17.06.2002and later approved revisions.This Certificate shall remain valid unless otherwise surrendered orrevoked.	07/01/2009	Active	10043143

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03783	VITROCISET S.p.A.		ENAC STC CS-070	550 CITATION II	Upgrade FDR installation with Installation of Digital SSFDRtype F1000.Note:1. This STC reflects the transfer of ENAC STC CS-070 from LEAT S.r.l. toVITROCISET S.p.A.2. This STC supersedes ENAC STC CS-070.		Master Drawing List No. 900-0402-000-000 IR dated 17.06.2002 and laterapprovedrevisions.	Included in the Supplemental Flight Manual No. 900-0402-800-000 Rev. IRdated 17.06.2002and later approved revisions.This Certificate shall remain valid unless otherwise surrendered orrevoked.	07/01/2009	Active	10043144
EASA.A.S.03784	VITROCISET S.p.A.		ENAC STC CS-062	550	Coupling of GPS Trimble 2101 I/O Approach Plus with Autopilot SPZ 500.Note:1. This STC reflects the transfer of ENAC STC CS-062 from LEAT S.r.l. toVITROCISET S.p.A.2. This STC supersedes ENAC STC CS-062.		MDL DWG No. 100-0502-000-000 dated 24.04.2002 and later approvedrevisions.	Included in the Supplemental Flight Manual No. 100-0502-000-000 dated25.03.2002 andlater approved revisions.This Certificate shall remain valid unless otherwise surrendered orrevoked.	07/01/2009	Active	10043145
EASA.A.S.03785	VITROCISET S.p.A.		ENAC STC CS-091	SA 227	Coupling of GPS GARMIN 155XL with Autopilot.Note:1. This 5TC reflects the transfer of ENAC 5TC CS-091 from LEAT S.r.l. toVITROCISET S.p.A.2. This STC supersedes ENAC STC C5-091.		Doc. No. 100-0203-000-000 Master Drawing List dated 07.07.2003 and laterapprovedrevisions.	Included in the Supplemental Flight Manual No. 100-0203-800-000 dated31.03.2003 andlater approved revisions.This Certificate shall remain valid unless otherwise surrendered orrevoked.	07/01/2009	Active	10043146
EASA.A.S.03786	JET AVIATION BUSINESS JETS AG	REV.1		BOMBARDIER BD-700-1A10	Activation of the Runway Awareness and Advisory System (RAAS)		- Jet Aviation Declaration of Compliance ref BGLEX34461 dated23/02/2009.- Jet Aviation Master Data List No. BGLEX34461-001, Revision IR, dated23/02/2009.- Jet Aviation AFMS No. BGLEX34461-201-01, Revision IR.	Prior to installation of this modification the installer must determinethat the interrelationshipbetween this modification and any other previously installedmodification will introduce noadverse effect upon the airworthiness of the product. The installationof this modification bythird persons is sub...	25/02/2009	Active	10043147
EASA.A.S.03787	GULFSTREAM AEROSPACE Ltd.		CAA UK RESPONSIBILITY	GULFSTREAM GV-SP	Re-placard aft seats “Not for use during Taxi Takeoff & Landing”.		Install in accordance with Gulfstream Aerospace Limited Change Ref GAeL 09/01.	1. Aircraft Serials:- GV Serials 572 and 582;- GVSP Serial 5078.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airwor...	18/02/2009	Active	10015276
EASA.A.S.03789	KUERZI AVIATION AG			PIPER PA-23-250	Dual GNS430W, GMA340, KN 63 InstallationOut: Dual KX-155 COM/NAV systems, Trimble-2000 approach GPS system, KMA-24H Audio system, MKR-101 marker system, KN-65 DME systemIn: Dual GNS-430W system, GMA-340 Audio/MKR system, KN-63 DME system.		¿ Master document list MDL-200830709 Rev. N/C or later approved revisions ¿ AFM supplement FMS-200830709 Rev. N/C or later approved revisions ¿ Instructions for Continued Airworthiness ICA-200830709 Rev. N/C or later approved revisions	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	08/04/2009	Active	10015277
EASA.A.S.03790	SCANDINAVIAN AVIONICS DESIGN ApS			AEROSPATIALE ATR 42-500 AEROSPATIALE ATR 42-400 AEROSPATIALE ATR 42-320 AEROSPATIALE ATR 42-300 AEROSPATIALE ATR 42-200	Installation of Honeywell KLN-90B System with dual CDr		See Scandinavian Avionics Design documents:• Certification Documents 2051746 DOC issue 1• Engineering Order 2051746-EO Issue 2• Aeroplane Flight Manual Supplement 2051746-AM Issue2• Continued Airworthiness 2051746-CA issue 2• Maintenance Manual Supplement 2051746-MM Issue 3Or later EASA Approved re...	1. Prior to installation of this modification the installermustdetermine that theinterrelationship between this modification and any other previouslyinstalled modificationwill introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third persons...	01/07/2009	Active	10043321

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03794	AVIONITEC Ltd.			PA-46-350P	Installation Weather avoidance systems and TAS and ME406 ELT by installation of:- Avidyne MFD EX 500- Avidyne Traffic Advisory system TAS 610- Avidyne Tactical Weather detection System TWX 670- Avidyne Iridium Data Link Transceiver MLX 770- Artex ME406 ELT		¿ Master Document List: PI81151-070¿ Instruction for continued airworthiness: PI81151-015 ¿ Declaration of Compliance: PI81151-060 ¿ AFMS EX500: PI81151-014¿ AFMS MLX770: PI81151-012 ¿ AFMS TAS 610: PI81151-011¿ AFMS TWX670: PI81151-013	Reg.: HB-POY, SN: 4622090	10/03/2009	Active	10015278
EASA.A.S.03801	AERO-DIENST GMBH & CO. KG			LEARJET 35A	Dual FMS UNS-1Lw System Installation (UASC)		As detailed in Engineering Order EO 249-LR, rev. 1 (or later approvedrevisions)	none	26/05/2009	Active	10043084
EASA.A.S.03802	AERODISA S.L.			A310 MODELS	EHS upgrade on Honeywell TRA-67A066-01127-1402This STC upgrades existing transponder sysytem by installing Mode SEnhance surveillance (EHS).		-,,Master Data List, ref. AED2008-10M_MDL Revision 4, dated19 May 2009(or any later approved revision)-,,AFM Supplement, ref. AED2008-10M_D03, dated 20 December 2008	None.	03/07/2009	Active	10030750
EASA.A.S.03804	AEROSPACE DESIGN AND ENGINEERINGCONSULTANTS Ltd.		CAA UK RESPONSIBILITY	A320-200 MODELS	Introduction of 16J/126Y Class Cabin Configuration		• Modification Summary, ref. doc. MOD-0548, Rev. A, dated 8th May 2009• Modification Compliance List, ref. doc. MCL-0548 Rev. A, dated 11th May 2009	1. Prior to installation of this modification the installermust determine that the interrelationship between this modificationand any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. 2. The installation of this modification b...	11/05/2009	Active	10015279
EASA.A.S.03807	JET AVIATION AG, BASEL			FALCON 900EX	Activation of the Runway Awareness and Advisory System (RAAS) i.a.w. JetAviation Master Data List BF9EX34461-001		•,,Jet Aviation Master Data List BF9EX34461-001 Revision B,dated 06thJuly 2009•,,Jet Aviation Aeroplane Flight Manual Supplement BF9EX34461-201-01Revision IR•,,Jet Aviation Engineering Order (installation) BF9EX34461-344600Revision IROr later EASA Approved revisions of these documents.	1.,,Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and anyother previously installed modification willintroduce no adverse effectupon the airworthiness of the product.2.,,The installation of this modification by third pers...	08/07/2009	Active	10035212
EASA.A.S.03812	TENENCIA Ltd.		CAA UK RESPONSIBILITY	737-300	Collins VHF-700B Installation (8.33 kHz)		Tenencia Documents:- Modification TEN 596 Issue 2 dated 11 May 2009- TEN 596/4 Maintenance Manual Supplement	Limited to Boeing 737-300; JY-JAX, s/n 23955; JY-JAN, s/n 23956.	12/05/2009	Active	10043083
EASA.A.S.03824	JET AVIATION AG, BASEL			GULFSTREAM III	Activation of the Runway Awareness and Advisory System (RAAS)EGPWC upgrade to software level 228-228 and activation of the RAAS		Installation in accordance with Jet Aviation Engineering Order BGLF334461 and Master Drawing List Doc No BGLF334461-001Rev IR or later approved revisions.Operation in accordance with Jet Aviation Airplane Flight Manual Supplement ref BGLF334461-201-01 Rev IR or later approved revisions.	None	11/05/2009	Active	10015289
EASA.A.S.03831	AERO-DIENST GMBH & CO. KG			35A	Dual SN4500 EHSI Installation (Sandel)		As detailed in Engineering Order EO 250-LR, rev. 1 (or later approvedrevisions)	none	26/05/2009	Active	10043082

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03834	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			CESSNA 206 SERIES	Dual GNS 430w with TAS 600 SystemsBy installing two GARMIN GNS430W with external 121.5MHz Frequency selection and an Avidyne TAS 600 system		Master Data List: Doc Number 808-049AFMS Dual GNS430W with TAS600: Doc Number 808-071Instruction for continued Airworthiness: Doc Number 808-085	Aspen EFD-1000 Primary Flight Display must be installed in the aircraft.	20/04/2009	Active	10015292
EASA.A.S.03835	AIR SUPPORT INTERNATIONAL S.r.l.			M20K	ASI BMA 01/B/09 “ Installation of Garmin GNS 430W for B-RNAV Operation”		ASI BMA 01/B/09AFMS BMA 01/B/09	1) The approval holder shall fulfil the obligations of Part21, Paragraph 21.A1092) Limited to S/N 25-0862	10/06/2009	Active	10015293
EASA.A.S.03838	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			PIPER PA-34	Pneumatic deicer removal.		SEGA application document no. A-03-09 Deice_DA edition 20 dated 20 March 2009SEGA Flight Manual Supplement no. A-03-09-Deice edition 0 dated 20 March 2009SEGA modification file no. A-03-09-Deice edition 0 dated 20 March 2009	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	21/04/2009	Active	10015294
EASA.A.S.03840	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			CESSNA 650	Installation of dual Honeywell GNS-XLS PRNAV FMS		-Engineering Order 2009-2 Revision D from 12 May 2009-AFM Supplement 2009-2-8 Revision B from 12 May 2009-Maintenance Manual Supplement 2009-2-10 Revision A from 3 March 2009-Declaration of Compliance of project 2009-2 from 20 May 2009or later approved revisions	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2) The installation of this modification by third pers...	27/05/2009	Active	10015295
EASA.A.S.03844	JET AVIATION AG, BASEL	REV 2	FOCA STC Z25-20-77	BOEING 737-700 IGW	CTT Zonal dryer activationReplacement of Zonal Dryer related to EASA AD 2006-0140-E.The above reference EASA AD required the de-activation of Zonal Drying Systems installed via Swiss FOCA STC Z 25-20-77 due to the potential for combustion of contaminants in the dryer unit. A new dryer unit has beenT...		CTT SB 2001-006-21-01-AD InitialEASA AD 2006-0140-E or later approved revisionsMaster Data List BBJ32627-001 Rev. C dated 15.01.2009 or later approved revision	S/N 32627	21/04/2009	Active	10015296
EASA.A.S.03851	AIR ALLIANCE GmbH			B300, B300C	Installation of Honeywell Mark VI EGPWS.		- According to AirAlliance Master Document List Doc. No.2009_006_A24CE AA Form 2, Rev. 0, or later approved Revisions and AirAlliance Installation Instructions 2009_006_A24CE_500, Rev. 0, or later Revisions.- To be operated in accordance with AirAlliance AFM-S Document No. 2009_006_A24CE_506,...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	01/04/2009	Active	10015298
EASA.A.S.03852	AIR ALLIANCE GmbH			PIPER PA-31T2 PIPER PA-31T1 PA-31T (CHEYENNE/ CHEYENNE II)	Installation/ Exchange of Avionics acc. AirAlliance MDL 2008_059_A8EA in latest approved Revision		According to AirAlliance Master Document List Doc. No. 2008_059_A8EA Rev. 0, or later approved Revisions and AirAlliance Engineering Order 2008_059_A8EA-0500, Rev. 0, or later RevisionsTo be operated in accordance with¿ AirAlliance AFM-S Documents No. 2008_059_A8EA_0516, Rev. 0, or later approved...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	01/04/2009	Active	10015299

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03853	AIR ALLIANCE GmbH			PA-31T, PA-31T1, PA-31T2	Installation of Avidyne EX-500, TWX 670 and MLX 770 acc. AirAlliance MDL2009_003_A8EA in latest approved Revision		According to AirAlliance Master Document List Doc. No. 2009_003_A8EARev. 0, or later approved Revisions and AirAllianceEngineering Order2009_003_A8EA-0500, Rev. 0, or later RevisionsTo be operated in accordance with AirAlliance AFM-S Documents No. 2009_003_A8EA_0506, Rev. 0, or later approved Revisi...	none	20/05/2009	Active	10043081
EASA.A.S.03857	BERINGER AERO S.A.S.			R1000, R2000, R3000, HR100, APEX DR 400 TOUS MODELES	New Design of brake Disks		PET-STC-001 Certification ProgramPET-STC-001 Test ReportDrawing AV-ROB-001-01	none	05/05/2009	Active	10043080
EASA.A.S.03858	SCANDINAVIAN AVIONICS DESIGN ApS			BEECH 400, 400A	Installation of various Entertainment Systems acc.: Engineering OrderDoc.: 2051195-EO Compliance Record Doc.: 2051195-COR	CS-25	-AFM Supplement Doc.: 2051195-AM-Instructions for Continuous Airworthiness Doc.: 2051195-CA	None	28/07/2009	Active	10034415
EASA.A.S.03859	H4 AEROSPACE (UK) Ltd.		CAA UK RESPONSIBILITY	AIRBUS A320-232	GUEST/STAFF SEATING AREA RECONFIGURATION & MISC CABIN ITEMSFOR A320-232 AIRCRAFT as defined in H4ACP057.Model: Airbus A320-232 MSN 2403, A6-DLM		• Modification summary and declaration of compliance H4A1196• Flight Manual Supplement H4AFMS019• Instructionsfor Continued Airworthiness H4ADR448	Approval valid only for MSN 2403.The use of the aircraft islimited to non-commercial operation only. For other Limitations refer to Flight Manual Supplement H4AFMS019.	04/05/2009	Active	10015300
EASA.A.S.03862	AMES AEROSPACE & MECHANICAL ENGINEESERVICES ING. WALTER STARZACHER Ges			FALCON 2000	Falcon 2000 MSN209 Interior Refurbishment.		-EO_M088000101_MBO_14042009-ICA_M088000101_MBO_14042009-EB_M088000101_MBO_14042009	1. Limited to A/C Falcon 2000, MSN 209.2. Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product3. The...	11/05/2009	Active	10015301
EASA.A.S.03870	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)				TAS 620 System Installation by installing an Avidyne TAS 620 TrafficAdvisory System	FAR 23	- Master Data List, Doc. No. 801-049, Rev. A or latest approvedrevision- AFMS, Doc. No. 818-071, Rev. A or latest approved revision- ICA, Doc. No. 818-085, Rev. IR or latest approved revision	None	03/07/2009	Active	10033418
EASA.A.S.03873	AEROSERVIS, S.R.O.			SAAB SF340A	Installation of Universal UNS-1Msp Flight management System		-,,AFM Supplement STC AE/092-DLP1-,,Documentation in accordance with Master Documentation List AE 92 000X Rev. E, dated2009-06.25	Valid for Saab SF340A/s/n 340.026 and 340.038 only.	03/07/2009	Active	10030755
EASA.A.S.03881	E A D AEROSPACE AIRWORTHINESS			AIRBUS A320	Installation of AMT-3800 High Gain Antenna on A320		-Master Drawing List, ref. Doc. No. 01273-EAS-A-MDL, Rev. D, dated 23rdJuly 2009-Supplemental Type Design Document, ref. Doc. No. 01273-EAS-A-STD-0I,Rev. B, dated15th May 2009-Maintenance Planning Document, ref. Doc. No. 01273-EAS-A-MPD-01, Rev.C, dated 23rdJuly 2009-Declaration of Compliance - ref....	Limitations and Conditions:1) Prior to installation of thismodification the installer mustdetermine that theinterrelationship between this modification and any other previouslyinstalledmodification will introduce no adverse effect upon the airworthiness ofthe product.2) The installation of this mod...	30/07/2009	Active	10043327

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.03886	JET AVIATION AG, BASEL			FALCON 900	Activation of the Runway Awareness and Advisory System (RAAS) i.a.w. Jet Aviation Master Data List BF90034461-001		-Jet Aviation Master Data List BF90034461-001 Revision A dated 19th May 2009-Jet Aviation Aeroplane Flight Manual Supplement BF90034461-201-01 Revision IR-Jet Aviation EngineeringOrder (installation) BF90034461-344600 Revision IROr later EASA Approved revisions of these documents.	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2) The installation of this modification by third pers...	22/05/2009	Active	10015304
EASA.A.S.03897	RUAG AEROSPACE SERVICES GmbH			EMBRAER EMB-135BJ	Stone Flooring / Replacement of existing floor covering by a stone floor covering in the forward entrance area and in the rear lavatory. This modification will not affect the structural flooring, the stone floor covering is only a decorative component.		Master Document List 289B-MDL Rev. A dtd. 25.May 2009	EASA EWIS Generic Special Condition not applicable for thisSTC	26/05/2009	Active	10015306
EASA.A.S.03899	BUSINESS AND COMMUTER AIRCRAFT			BEECH E90 BEECH C90 BEECH B90	Be 'Mode S / Flight ID' capable Collins TDR-94(D) transponders.		¿ The installation will be made in accordance with Business and Commuter Aircraft document BCA108-00, Revision 0, asof 14.08.2008 or later EASA approved revision. ¿ The Aircraft Flight Manual Supplement applicable to this modification is BCA108-03 document, Revision 0, as of 14.08.1008 or late...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	27/04/2009	Active	10015307
EASA.A.S.03900	BUSINESS AND COMMUTER AIRCRAFT			BEECH F90	Be 'Mode S / Flight ID' capable Collins TDR-94(D) transponders.		¿ The installation will be made in accordance with Business and Commuter Aircraft document BCA108-00, Revision 0, asof 14.08.2008 or later EASA approved revision. ¿ The Aircraft Flight Manual Supplement applicable to this modification is BCA108-03 document, Revision 0, as of 14.08.1008 or late...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	27/04/2009	Active	10015308
EASA.A.S.03911	CESSNA DUESSELDORF CITATIONSERVICE CENTER GmbH			BEECH 1900					15/07/2009	Active	10028549
EASA.A.S.03948	TOST GmbH FLUGZEUGGERAETEBAUMUENCHEN		LBA STC 0326/XXX	HUSKY A-1A, A1-B	Installation of Tow Cable retractor Winch with Guillotine to Husky A-1A,A-1B. Extension of LBA STC 0326/xxx, dated 21 October 1992.This STC is a revision to and supersedes LBA STC0326/xxx, dated 21October 1992.	CS-23.C	-Anhang zum Flughandbuch, LBA approved 24 January 1985 is now valid forHusky A-1A and A-1B: Flug- und BetriebsanweisungfürFlugzeugabschleppseil-Einziehwinde mit Kappvorrichtung für Piper, Husky,Citabria, Maule, Stinson-The following Installation Manual (page 3 point 5) has to be added withHusky A-1...	None	23/06/2009	Active	10033808
EASA.A.S.03983	FMD FLUGDIENST MAGDEBURG GmbH			2. FR172E 1. 172M,172N,172P,172R, 1. 172E,172F,172H,172K, 172L		Installation of vaccine dropping device (SURVIS) (Fuchskoederabwurfanlage).	Pilot's Operating Handbook and Flight Manual Supplement forCessna 172,issued 15 July 2009.	The certificate shall remain valid unless otherwise surrendered orrevoked.	29/07/2009	Active	10041003

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.A.S.C.01065	DASSAULT FALCON SERVICE			MF 20 GF SIN 397	Installation of2 viewing panels on top of the fuselage		-see Change approval sheet DFS 2490:AMM no DFSIDE/5 F2 Al and associated list of affected technicaldocuments	1 .. Applicable only to MF 20 SIN 3972. Ihis STC is approved only for the configwation as defined in ModSheet DFS 24903Ihis SIC is approved only for the plOduct configuration as defined inthe applOved designdata referred to in the paragraph "Description" .. Compatibility withother aircraft/ engineco...	17/08/2005	Active	10043154
EASA.A.S.C.OI066	DASSAULT FALCON SERVICE		EASA A S 00723	MF 20GF S/N 397	Installation of a probe dispenser system and of an UHF antenna		-see Change approval sheet DF S 2485:AMM supplement DFSIDE/5 F2 Al and associated list of affected technicaldocuments	1 . Applicable only to MF 20 SIN 3972. Ihis SIC is approvedonly for the configuration as defined in ModSheet DFS 24853.. This STC is approved only for the product configuration as definedin the approved designdata referred to in the paragraph "Description". Compatibility withother aircraft/ enginec...	17/08/2005	Active	10043155
EASA.BA.S.01001	CAMERON BALLOONS LIMITED		CAA UK RESPONSIBIL ITY	GEFA AS 105 GD (HOT AIR AIRSHI	Introduction of Liquid Pilot Lights.		FMS-C474-STC-Iss 1	None.	30/04/2007	Active	10015309
EASA.E.S.01000	THIELERT AIRCRAFT ENGINES GmbH				Installation of the FADEC G6 in accordance with Installation Manual IM-80-01, Conversion Instruction CI-80-01 and Type Design Definition Doc. No.: TDD-80-01.		Instructions for operation, maintenance and inspection:-Operation & Maintenance Manual Lycoming IO-580-B1A-E Converted Engine, Doc. No.: OM-80-01,- Installation Manual Lycoming IO-580-B1A-E Converted Engine, Doc. No.: IM-80-01,- Conversion Instruction for the Lycoming IO-580-B1A-E Engine	Engines having been converted via this STC may be identified as IO-580-B1A-EThe data in the TCDS EASA.IM.E.027 remains valid, except the following:Weight of the engine equipped with FADEC: 207.49 kg (457.44 lbs) Dimensions:Overall Height: 574.3 mm (22.61 in.) TemperatureM...	03/08/2007	Active	10015310
EASA.IM.A.02449	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC ST10578SC-D	FALCON 900EX	EASA Validation of FAA approved STC ST10578SC-D: Aircraft Compliance forFalcon 900EX serial number aircraft 176 in accordance with Data ListF9EX-07001-D179 Revision A dated 29th May 2007 or later revisionsapproved by EASA in accordance with EASA ED Decision 2004/04/CF (orI.a.w. subsequent revisions...		See those of original FAA STC STl0578SC-D.- Data List F9EX-07001-D179 Revision A dated 29th May 2007;- Airplane Flight Manual Supplement, Report 37159-F9EX-D179, Rev.Original dated 30th May 2007;- Supplemental Maintenance Manual, Report F900EX SN 176, Rev. A dated01st June 2007;or later revisions of...	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modificationwill introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	09/07/2009	Active	10043306
EASA.IM.A.C.01293	PIPER AIRCRAFT INC.			PA-34-220T (SENECA V)	Installation of the Avidyne Entegra System Option (PFD/MFD)into thePA-34-220T (Seneca V).		See EASA.IM.A.090 (TCDS)	See EASA.IM.A.090	26/06/2006	Active	10042554
EASA.IM.A.S.0013	JET CORP		FAA STC ST00704WI	MYSTERE FALCON 900	Installation. of an Allied Signal Enhanced Ground ProximityWarningSystem (EGPWS) with windshear detection and alertingin accordance withJetCorp STC Drawing List 13-327L001<(>,<)> Revision B, dated 20thDecember 2000 (or later EASA approved revision).			1. The installation of the change, subject of this STC, must beassociated with the installation of a change modifying the color greenof the TERRAIN INHIBIT switch. The accepted colors are amber, white orblue.2. EASA approved Airplane Flight Manual Supplement JetCorp N° 13-327B002Revision B<(>,<)> da...	24/06/2004	Active	10069841

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00144	AIR MEDIC L.L.C.		FAA STC SA3333WE	B727-100/-200 SERIES	1 The approval of this change applies basically to the Boeing 727-100and -200 series only.2 This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermin...				07/10/2004	Active	10061359
EASA.IM.A.S.00145	AIR MEDIC L.L.C.		FAA STC SA3334WE	737-400, 737-500 737-100, 737-200, 737-300	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'Z', dated August 12, 1988 (or laterEASA approved Revisions).			1. The approval of this change applies basically to the Boeing 737-100,-200, -300, -400 and -500 series only.2 This STCis approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configuratio...	07/10/2004	Active	10061360
EASA.IM.A.S.00146	AIR MEDIC L.L.C.		FAA STC SA3335WE	2. DC-10-40 1. DC-10-10/-30, MD-11 SERIES	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref.: AM-2001, Revision 'A' dated January 28, 1977 (orlater EASA approved Revisions).			1. The approval of this change applies basically to the Mc DonnellDouglas DC-1020, -30< (>,<)> -40 and MD-11 series only.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engined...	07/10/2004	Active	10061369
EASA.IM.A.S.00147	AIR MEDIC L.L.C.		FAA STC SA3511WE	747SR (US A20WE) 747-300, 747-400 , 747SP 747-100, 747-200B, 747-200C	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref.: AM-2001, Revision 'K' dated February 28,1978 (orlater EASA approved Revisions).			1 the approval of this change applies basically to the Boeing 747 seriespassenger versions only2 This SIC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedet...	07/10/2004	Active	10061362
EASA.IM.A.S.00148	AIR MEDIC L.L.C.		FAA STC SA3489NM	757-200, 757-300	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref.: AM-2001, Revision 'Y', dated March 11, 1987 (or laterEASA approved Revisions).			1. The approval of this change applies basically to the Boeing 757-200and -300 series only2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircrafft engine configuration shall bedetermi...	07/10/2004	Active	10061363
EASA.IM.A.S.00149	AIR MEDIC L.L.C.		FAA STC SA2023NM	B767-200, -300, -400ER SERIES	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'V', October 27, 1983 (or later EASAapproved Revisions).			1. The approval of this change applies basically to the Boeing 767series passenger versions only.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall be...	07/10/2004	Active	10061364
EASA.IM.A.S.0015	ROSEMOUNT AEROSPACE, Inc.			CL-600-2B19	Installation of Rosemount Aerospace Inc. (RMTAERO) Angle ofAttachsensor model 0861 HB, in accordance with Amtech Aeronautical LimitedModification Data Summary MDS317601 (RMTAERO) document number D0020310,Revision 1, dated 27 July 2001, orlater EASA approved revision.			1. Subject to compliance with the provisions of Part 21 Subpart E, thisSTC and associated data shall remain valid untilsurrender, withdrawn orotherwise terminated.2. If transfer of this certificate is requested under Part 21A.116, theSTC will be reissued.3. This STC is approved only for the product...	26/06/2004	Active	10053575

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00150	AIR MEDIC L.L.C.		FAA STC SA3853WE	DC-8-60 SERIES	1 The approval of this change applies basically to the Mc DonnellDouglas DC-8-60 passengers versions only.2 This STC isapproved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configuration s...				07/10/2004	Active	10061370
EASA.IM.A.S.00151	AIR MEDIC L.L.C.		FAA STC SA3623WE	3. DC-9-11/-12/-13/-31 2. DC-9-83, DC-9-87, MD-88 2. DC-9-51, DC-9-81, DC-9-82 2. DC-9-14, DC-9-15, DC-9-21 1. MD-90-30, B717-200	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref.: AM -200I, Revision 'M' dated April 3, 1978 (or laterEASA approved Revisions).			1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/ engineconfiguration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrev...	07/10/2004	Active	10061371
EASA.IM.A.S.00151	AIR MEDIC L.L.C.		FAA STC SA3623WE	3. DC-9-11/-12/-13/-31 2. DC-9-83, DC-9-87, MD-88 2. DC-9-51, DC-9-81, DC-9-82 2. DC-9-32, DC-9-34, DC-9-41 2. DC-9-14, DC-9-15, DC-9-21 1. MD-90-30, B717-200	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref.: AM -2001, Revision 'M" dated April 3, 1978 (or laterEASA approved Revisions).			1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/ engineconfiguration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrev...	07/10/2004	Active	10061368
EASA.IM.A.S.00152	AIR MEDIC L.L.C.		FAA STC SA3512WE	L-1011-385-1 SERIES	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'K' dated February 28,1978 (or laterEASA approved Revisions).			1 The approval of this change applies basically to the LockheedL-1011-385-1 series only2 This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configuration shall bedetermined b...	07/10/2004	Active	10061367
EASA.IM.A.S.00162	LEARJET Inc.		FAA STC ST01606LA-D	BOMBARDIER BD-100-1A10 (CHALLE	The modification consists in the installation of an Executive Interior in accordance with Master Drawing List HC200135001, Rev. E dated July 10, 2004 (or later FAA approved revision).Validation of FAA STC ST01606LA-D.			1. The Maintenance Instructions for Continued Airworthiness are contained in Documents Number HC200135000-IFCA-1. Modification of an aircraft by this STC obligates the aircraftoperator to include the maintenance information provided bythis document inthe operator's Aircraft Maintenance Manual a...	07/10/2004	Active	10015312
EASA.IM.A.S.00166	AIRCRAFT SYSTEMS AND MANUFACTURING,Inc.		FAA STC ST09887 SC	BOEING 727	Installation of RVSM compliant equipment (dual DADS).FAA STC N° ST09887 SC			1. This STC is approved only for the installation of an RVSM compliant Air Data System and does not constitute an approval of RVSM operation.2. This STC is approved only forthe product configuration as defined in the approved designdata referred to in the paragraph "Description". Compatibili...	07/10/2004	Active	10015313

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00199	AIRWORKS		FAA STC ST01432LA	A321-211,-231 A321-111,-112,-131 A320-231,-232,-233 A320-111,-211,-212,-214 A319-114,-131,-132 A319-111 -112,-113	Installation of AirWorks Cockpit Door Surveillance Systems in accordancewith AirWorks Index List Document No IL23001, Revision NC, datedFebruary 5, 2003 or later FAA approved Revision. This STC is avalidation of the FAA-approved STC No ST01432LA.		1. AirWorks Airplane Flight Manual Supplement (AFM-S) Document NoAFMS232010006, Revision Original, FAA approved on February 5, 2003, orlater FAA approved revision, is required as part of this modification.2. This STC is approved only for the product configuration as defined inthe approved design dat...		14/10/2004	Active	10043111
EASA.IM.A.S.0022	MACHINING PROGRAMMING MANUFACTURING Inc.			BD-100-1A10 (CHALLENGER 300)	The modification consists in the installation of folding step ladder toprovide access to the tailcone equipment compartment in accordance withMPM Inc. Aft Ladder Installation Drawing LD001 dated 4th September, 2003(or later EASA approved revision).			1. This STC is approved only for the product configuration as defined inapproved design data referred to in the paragraph "Description".2. Compatibility with other aircraft/ engineconfigurations shall bedetermined by installer.	09/07/2004	Active	10042579
EASA.IM.A.S.00228	FRAKES AVIATION			B300C B300 B200C B200 300LW 300 200C 200 1900D 1900C 1900	Installation of engine exhaust stub in accordance with Frakes AviationInstallation drawing number FA5726, dated September 6, 1985, for the 200series, and drawing FA5601 dated June19, 1995 for the 300 and 1900series, or later EASA-approvedrevision				28/10/2004	Active	10042074
EASA.IM.A.S.00231	S-TEC CORPORATION		SA09202AC-D	CESSNA 172R	Installation of S-TEC System 50 Two Axis Automatic Flight GuidanceSystem, Model ST-184-50 in accordance with FAA STC SA09202AC-D andMaster Drawing List No. 922121, Revision F, dated April 1, 1997 or laterFAA approved revision.			1. German POH and/or AFM Supplement for Cessna Model 172R with S-TECSystem 50 Two Axis Automatic Flight Guidance System, pin 891338, datedSeptember 21<(>,<)> 2004.2 F ANDAS approved POH and/or AFM Supplement for Cessna Modell72R withSTECSystem 50 Two Axis Automatic Flight Guidance System, p/n 891338...	14/10/2004	Active	10067651
EASA.IM.A.S.00244	S-TEC CORPORATION		FAA STC SA5321SW-D	BOEING 767-300ER	Reconfiguration of passenger cabin interior from 204 passengers to 250 passengers in accordance with DER Services Inc. Master Document List (MDL) Report No. MDL-A2004-026-1 dated 15 June 2004, or later EASA approved revisions			1. Subject to compliance with the provisions of Part 21Subpart E, this STC and associated data shall remain valid until surrendered, withdrawn or otherwise terminated.2. If transfer of this Certificate is requested under Part 21A.116, the STC will be reissued.3. This approval is limited...	14/10/2004	Active	10015317
EASA.IM.A.S.00248	RAYTHEON AIRCRAFT COMPANY	REV. 1	FAA STC ST01278SE	B200/B200C/B300/B300C	Group approval for Reduced Vertical Separation Minimum (RVSM) inaccordance with AeroMech Document List No AMI-QD-RAC-0315, rev. 'New',dated September 26, 2003, or later approved revisions ..			1. This STC is issued as result of the validation of the SIC NoSTOI278SE approved by the FAA on October 3rd, 2003.2. The instructions for Initial and Continued Airworthiness, DocumentAMI-STC-B2B3P21<(>,<)> Rev 'New', dated September 26, 2003 or laterapproved revision, is a required part of this STC....	17/12/2004	Active	10069412

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00260	EMPIRE AIRLINES		FAA STC ST01444SE	ATR 42/72	Installation of B/E Aerospace Sweep-On Fullface Crew OxygenMask System on the flight deck of ATR 42/72 series airplanes in accordance with Empire Airlines Document Number 3510, Revision Original dated May 25, 2004, or later FAA-approved revision. This STC is a validation of the FAA approved STC No...			1. Incorporation of Supplemental Type Certificate (STC)ST01189WI, passenger to all-cargo Class E cargo compartmentconversion,must be accomplished prior to or concurrent withthis STC.2. A copy of this Certificate and Empire Airlines Document Number 3510, Revision Original, dated May 25, 200...	07/10/2004	Active	10015319
EASA.IM.A.S.00268	S-TEC CORPORATION	REV. 1	FAA STC SA09290AC-D	PIPER PA-32-300 PIPER PA-32-260	Installation of S-TEC System 20/30 Single Axis and Two AxisAutomatic Flight Guidance Systems Model ST-733-20/30 SA09290AC-D.		Bulletin No.833 dated October 24, 1997 and Master Drawing List No. 921034 dated October 24, 1997 or later FAA Approved RevisionFlight Manual Supplement: Airplane Flight Manual Supplement P/N 891554 dated October 29, 1997 or later FAA Approved Revision for S-TEC System 20 P/N 891556 dated October 29,...	1. Subject to compliance with the provisions of Part 21 Subpart E, this STC and associated data shall remain valid until surrended, withdrawn or otherwise terminated2. If transfer of this Certificate is requested under Part 21A.116 the STC will be reissued3. This STC is approved only for th...	10/09/2008	Active	10015320
EASA.IM.A.S.00275	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	BEECH 400A	Installation of a Honeywell Enhanced Ground Proximity Warning System (EGPWS) Mark VIII in accordance with Elliot Aviation Master Data List 2018-571DL, Revision 4, dated 6 November2003 or later EASA approved revisions.This STC is issued asresult of the validation of the Elliot Aviation Tehnical Pro...			1. AFM Supplement Elliott Aviation Document No. FS2018-571 rev.0 or later EASA approved revisions.2. Instructions for Continued Airworthiness Document No. CA2018-571.3. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragra...	20/10/2004	Active	10015322
EASA.IM.A.S.00280	BALLISTIC RECOVERY SYSTEMS INC (BRS)		FAA STC SA01999CH	182S, 182T , T182, T182T 182M, 182N, 182P, 182Q, 182R, 182G, 182H, 182J, 182K, 182L	BRS-182 Parachute Recovery System FAA STC SA01999CH. In accordance with Balistics Recovery Systems Inc Drawing No 9005 Revision A dated June 11 2004 or later Approved Revision.Flight Manual Supplement Ballistic Recovery Systems AFM Supplement Document Number 9005-AFMS Revision A dated June 7 20...			1. Subject to compliance with the provisions of Part 21 Subpart E, this STC and associated data shall remain valid until surrendered, withdrawn or otherwise terminated.2. If transfer of this Certificate is requested under Part 21A.116, the STC will be reissued.3. This STC is approved onl...	15/10/2004	Active	10015325
EASA.IM.A.S.00281	S-TEC CORPORATION	REV. 1	FAA STC SA09386AC-D	GRUMMAN AA-5B GRUMMAN AA-5A GRUMMAN AA-5	Installation of S-TEC System 30 Single and Two Axis Automatic Flight Guidance System, Model ST-840-30, FAA STC SA09386AC-D		Bulletin No 940 dated September 14 1998 and Master Drawing List No 921115 dated September 14 1998 or later FAA ApprovedRevision.Flight Manual Supplement: FAA/ DAS Approved Supplemental Flight Manual, Part Number 891787 dated September 17 1998 or later FAA approved revision together with CAA Change S...	1. Subject to compliance with the provisions of Part 21 Subpart E, this STC and associated data shall remain valid until surrendered, withdrawn or otherwise terminated.2. If transfer of this certificate is requested under Part 21A.116, theSTC will be reissued	11/09/2008	Active	10015326
EASA.IM.A.S.00289	S-TEC CORPORATION		FAA STC SA09264AC-D	CESSNA F182-Q	Installation of S-TEC System 30 Two Axis Automatic Flight Guidance System, Model ST-718/30, according to Bulletin No. 818, dated July 30, 1997 and Master Drawing List No. 921016, dated July 30, 1997 or later FAA approved revisions of the above data (28 Volt System). This STC is issued as result of t...			1. EASA Approved Pilot's Operating Handbook and/or Airplane Flight Manual Supplement, dated October 21, 2004 is required for Reims-Cessna Model F182Q for S-TEC System 30 or later EASA approved revisions of the above supplement.2. Compatibility of this modification with other previously appr...	28/10/2004	Active	10015327

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00313	G&D AERO PRODUCTS INC		FAA STC SA3759NM	V35, V35A, V35B,36, A36, A36TC F33C, H35, K35, N35, P35, S35, B36TC 35-C33A, E33, E33A, F33, F33A, 35-33, 35-A33, 35-B33, 35-C33,	Installation of acrylic window liners in accordance with FAA approved Report No1, revision B, dated March 15, 1995 or later EASA-approved revision.			1. This installation should not be incorporated in anyaircraft unless it is determined that the interrelationshipbetween this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft.2. This STC is issued as result1...	16/11/2004	Active	10015328
EASA.IM.A.S.00322	LEARJET Inc.		FAA STC ST00151BO	LEARJET 55	Installation of Honeywell CAS-67A TCAS II Software Change 7,0.			1. FAA STC ST00151BO.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	09/11/2004	Active	10015329
EASA.IM.A.S.00331	LEARJET Inc.			60	Installation of an ICG Iridium Satcom System FAA STC ST01599LA-D inaccordance with Learjet Master Document List LC23155000, Revision F, FAAApproved May, 27th 2004, or later FAA Approved revisions.			1. FAA Approved AFM Supplement L-FM23155000 Revision NC dated May 20th, 2004or later FAA Approved revision.2. Subject tocompliance with the provisions of Part 21 Subpart E, thisSTC and associated data shall remain valid until surrendered, withdrawnor otherwise terminated.3. If transfer of this Certi...	25/11/2004	Active	10063408
EASA.IM.A.S.00345	SIMMONDS PRECISION PRODUCTS, Inc		FAA STC ST00089BO	BOEING 727-200 SERIES	Installation of either the Goodrich Corporation Fire Detection and Suppression system, or the Fire Detection only system in accordance with Goodrich Corporation Master Drawing List T3008-MDL-0101, Revision A, dated October 31, 2003 or later FAA-approved revision,-as defined in FAA STC ST00089BO, iss...			1. The suppression feature of Fire Detection and Suppression system has been certified for a maximum of 60 minutes from the activation of the suppression agent. Aircraft diversion time, including landing, should not exceed 60 minutes.2. This STC is approved only for the product configuratione...	30/11/2004	Active	10015331
EASA.IM.A.S.00350	HAWKER BEECHCRAFT Ltd.		CAA UK RESPONSIBILITY	BEECH 1900C, AIRLINER	Defines an all cargo interior using web nets. The all cargointerior is defined by the top drawing of Raytheon AircraftServices No114-0100, no change, dated April 17, 1996, with an "FAA Approved" stamp of April 17, 1996 or later FAA-approved revision.			1. The Airplane Flight Manual Supplement No RAS 114-590021 is required equipment when this STC is installed.2. Compatibility of this design change with previously approved modifications must be determined by the installer.3. This STC is issued as a result of the validation of the Raytheon A...	03/12/2004	Active	10015332
EASA.IM.A.S.00352	RAYTHEON AIRCRAFT SERVICES, INC.		FAA SA00479WI	BEECH 1900C	Installation of a cargo web "Z" net in the forward fuselageand aloaders chair. The "Z" net and loaders chair cannot both be installed inthe airplane at the same time. Installation of the two configurationsare per Raytheon Aircraft Services Top drawing 1900c0100, n/c, dated ofSeptember 20, 1996, and...			1. The FAA approved Airplane Flight Manual Supplement p/n 1900C90021,dated November 6, 1996, or later FAA-approved revision is requiredequipment, when this STC is installed.2. Compatibility of this design change with previously approvedmodifications mut be determined by the installer.3. This STC isA...	07/12/2004	Active	10042555

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00358	BOMBARDIER INC.		TCCA LTD STC C-LSA04-212/D	CL-600-2B16	Installation of Securaplane Camera System Transport Canada Limited STC C-LSA04-212/D in accordance with Aero ConsultingServices Modification Data Summary Notice E091000 Revision n/c or later Transport Canada Approved Revision.			1. Subject to compliance with the provisions of Part 21 Subpart E, this STC and associated data shall remain valid until surrendered, withdrawn or otherwise terminated.2. Iftransfer of this Certificate is requested under Part 21A.116, the STC will be reissued.3. This approval is limited to...	07/12/2004	Active	10015334
EASA.IM.A.S.00360	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST01449CH	BOEING 757-200	Dual GPS Antenna and Coax Cable (FAA STC ST01449CH) as perMaster Data List ECS-200555 revision B dated June 11, 2003 or later FAA-approved revision.			1. Subject to compliance with the provisions of Part 21 Subpart E, this STC and associated data shall remain valid until surrendered, withdrawn or otherwise terminated.2. Iftransfer of this Certificate is requested under Part 21A.116, the STC will be reissued.3. This STC is approved only f...	07/12/2004	Active	10015335
EASA.IM.A.S.00361	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST01839CH	BOEING 757-200	Honeywell MK V Enhanced Ground Proximity Warning System (FAA STC ST01839CH) as per Master Data List ECS-201736 revisionH dated 25 May 2004 or later FAA-approved revision.			1. Subject to compliance with the provisions of Part 21 Subpart E, this STC and associated data shall remain valid until surrendered, withdrawn or otherwise terminated.2. Iftransfer of this Certificate is requested under Part 21A.116, the STC will be reissued.3. This STC is approved only f...	07/12/2004	Active	10015336
EASA.IM.A.S.00373	PRATT & WHITNEY	REV. 2		PILATUS PC-6/B-H2 PILATUS PC-6/B2-H4 PILATUS PC-6/B2-H2 PILATUS PC-6/B1-H2 CESSNA 208B CESSNA 208A CESSNA 208 BEECH C90 BEECH 300 BEECH 200 BEECH 1900 AIR TRACTOR AT-802 A AIR TRACTOR AT-802 AIR TRACTOR AT-503 AIR TRACTOR AT-502 B AIR TRACTOR AT-501 AIR TRACTOR AT-402 A	Installation of Pratt & Whitney Data Acquisition System ADAS+, p/n ADAS-K-010.		Part 23 Approved Model List ADAS-T225-1 dated 19 March 2004Master Document List ADAS-T-100-1 dated 28 March 2005Altair Avionics Corporation Aircraft Flight Manual Document No. ADAS-T-250-1, dated 3 July 2003, Revision C dated 31 March 2005, orlater approved revision	1. Compatibility of this modification with other previously approved modifications must be determined by the installer.2. This Major Change to STC EASA.IM.A.S.00373 is issued as a result of the validation of the Altair Avionics Corporation STC No SA00171BO, revision date 31 March 2005.3. Al...	07/03/2008	Active	10015338
EASA.IM.A.S.00389	AVIATION FABRICATORS, Inc.	REV. 2	FAA SA00635WI	2.A200C, A200CT, B200T, B200CT 2. 200, 200C, 200CT, A200 1. B200, B200C	Installation of aft Jump Seat Kits.		Installation in accordance with Aviation Fabricators, Inc. Drawing List, as defined in the attached AML, or later approved revisions.	1. Installation per the STC Drawing Lists defined in theAML is limited to aircraft with Beech factory installed oxygen system for the jump seat locations. Aircraft configured for more than 14 total occupants must be equipped with a 49 cubic foot or greater oxygen system.	17/04/2008	Active	10015339
EASA.IM.A.S.00392	ROCKWELL COLLINS, Inc.d/b/a AIR TRANSPORT SYSTEMS		FAA STC ST01202WI-D,STC EASA.I	SEE ATTACHED EASA APPROVED TYP	Modification of an existing FAA-approved Collins TPR-720, TPR-900 or TPR-901 Mode S transponder installation in Part 25aircraft.		- FAA STC No ST01202WI-D.- Collins Drawing Index as listed on AML No ST01202WI-D, revision original, or later FAA-approved revisions.	1. Prior installation and approval of a Collins TPR-720, TPR-900 or TPR-901 Mode S transponder is a prerequisite to this STC.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft...	29/03/2005	Active	10015340

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00404	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA A16WE	B737-200, -300, -400, -500	Installation of a Honeywell Enhanced Ground Proximity Warning System inaccordance withElectronic Cable Specialists Master Data List ECS-201532, Revision B,dated March 17, 2003<(>,<)>or later FAA-approved revision.FAA STC ST01798CH amended on 24.n.2004 (original STC for Boeing737-300/400 wasapprovedD...			1. AFM Supplement as listed in Appendix A ofECS Master DataList Rev. TECS201532 FAAapproved 23.11.2004. For configuration 13, GPS antennainstallationmust be accomplished prior with this modification in accordance with FAASTCST09490SC .. 2.ThisSTC is approved only for the product configuration as de...	14/12/2004	Active	10043149
EASA.IM.A.S.00415	AIRCRAFT SYSTEMS AND MANUFACTURING,INC		FAA STC ST09988SC	DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Installation of Universal Avionics Terrain Awareness & Warning System.		- FAA STC ST09988SC dated May 2002.- ASM Top Drawing List 5579-0001-00 rev. D dated 7 May 2002.- Aircraft Flight Manual Supplement No 5579-2160-00 dated 21 May 2002.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	14/12/2004	Active	10015341
EASA.IM.A.S.00416	AIRCRAFT SYSTEMS AND MANUFACTURING,INC		ST09989SC	DC-9-81 (MD-87) DC-9-81 (MD-83) DC-9-81 (MD-82) DC-9-81 (MD-81)	Installation of Universal Avionics Multi Function Display Model 640.		- FAA STC ST09989SC dated 21.05.2002- ASM Top DrawingList No 5580-0001-00 rev. D dated 07.05.2002.- AFM Supplement Doc. No 5580-2160-00 dated 21.05.2002	1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	14/12/2004	Active	10015342
EASA.IM.A.S.00440	AIM AVIATION RENTON, INC.			757-200	Installation of overhead Stowage Bin Doors		- AIM Aviation Inc. Master Data List AIM-DL-10960 Rev. A dated06/12/2004 or later FAA approved revision.	1. Subject to compliance with the provisions of Part 21 Subpart E, thisSTC and associated shall remain valid until surrendered, withdrawn orortherwise terminated.2. If transfer ofthis STC is requested under Part 21A.116, the STC willbe reissued.3. This STC approved for the product configuration asa...	21/12/2004	Active	10071576
EASA.IM.A.S.00442	HONEYWELL INTERNATIONAL INC.	REV 3	FAA STC ST00705SE	BOEING 747-400, 747-200	Installation of the Enhanced Ground Proximity Warning System on a Boeing 747-200/-400 aircraft.		Master Drawing, Enhanced Ground Proximity Warning System Boeing 747 Series Aircraft, Honeywell document 060-4199-094, rev. BC.	1This STC is approved only for the product configuration asdefined in the approved design data referred to in the paragraph ' Description'. Compatibility with other aircraft/ engine configurations shall be determined by the installer.For Boeing B747-2001. In addition to the FAA-approved Aircraftb...	29/01/2007	Active	10015343
EASA.IM.A.S.00444	ROCKWELL COLLINS, Inc.d/b/a AIR TRANSPORT SYSTEMS		FAA STC ST00587WI-D	BOEING 747-400	Modification of Collins ACARS DLM-700B Management Unit (MU)System Installation to Collins ACARS DLM-900 MU System Installation.		- FAA STC ST00587WI-D-Drawing Index 992-4300-001, no revision, dated 9/25/97 and Maintenance Manual Supplement (MMS) ACC-97-131, No revision, dated 10/17/98.	1. Collins ACARS DLM-700B Management Unit System Installation, EASA STC EASA.IM.A.S.00443, is required to be installed prior to or concurrent with using this STC. 2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Descriptio...	21/12/2004	Active	10015344
EASA.IM.A.S.00446	AVIONICS SUPPORT GROUP, Inc.		FAA ST02900AT	747-200, 747-300	T2CAS provisions on Boeing 747-200 & -300 Series Aircraft.		- FAA STC ST02900AT.- Avionics Support group Inc Master Drawing List 24595-MDL Revision IR dated june 22, 2004 orlater approved revision.	1. Subject to compliance with the provisions of Part 21 Subpart E, this STC and associated shall remain valid until surrendered, withdrawn or otherwise terminated.2. If transfer of this STC is requested under Part 21A.116, the STC will be reissued.3. This STC is approved only for the product configu...	21/12/2004	Active	10015345

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00471	SAFRAN CABIN INC.	REV 1	FAA STC ST01056LA	DC-9-87 (MD-87) MD 90-30 DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Installation of Galleys, Closets, Stowages, Lavatories, Bins, Class Divider, (Movable), Sidewall Panels, Ceiling Panels, Coatrooms,and Passenger Service Unites (PSUs) Installationin accordance with C & D Interiors Index List No. A04, Revision A, dated June 26,2000 or later approved revision,OrInst...		- FAA STC No ST01056LA dated 25 May 2004,- Index List No A04, rev. A dated 26 June 2000.- Drawing List No A093000, Rev.C, dated 31 January 2003.- Index List No A09 Rev.B, dated 25 June 2003	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	10/01/2007	Active	10015346
EASA.IM.A.S.00475	C & D INTERIORS	REV. 1		BOEING 737-600	C&D Interiors Stowage S1, Galley S1, Galley G2B, Galley G3B, Stowage S2, Forward lavatory, Passenger Seat Installation,Overhead Stowage Bin Installation, Sidewall Installation, PSU Installation, Passenger Seat Proximity Light installation.		- C&D Interiors Index List A81 Revision B, dated August 28,2003 or later FAA-approved revision.	1. Subject to compliance with the provisions of Part21 Subpart E, this STC and associated data shall remain valid untilsurrendered, revoked or otherwise terminated.2. If transferof this STC Certificate is requested under Part 21A.116, the STC will be reissued.3. This STC is approved only for the p...	17/05/2006	Active	10015347
EASA.IM.A.S.00498	HONEYWELL INTERNATIONAL INC.		FAA STC ST01124SE	BOEING 747-400 SERIES	Installation of the Flight Data Acquisition Management System		- Master Drawing List 756-0082-001, rev A, or later FAA approved revisions. - FAA STC ST01124SE	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer	10/01/2005	Active	10015348
EASA.IM.A.S.00503	ELLIOTT AVIATION	REV. 1	FAA STC SA01352CH	BEECH B300C BEECH B300 BEECH B200T BEECH B200CT BEECH B200C BEECH B200 BEECH 300LW BEECH 300 BEECH 200T BEECH 200CT BEECH 200C BEECH 200	Installation of Dual TDR-94D Transponders with Flight ID inB200/ B200C/B300/B300C Aircraft with Pro Line 21 Avionics, in accordancewith Configuration 3 of Elliott Aviation Master Data List, No 2026-576DL, Revision 2 or later approved revision.		- Airplane Flight Manual Supplement, Elliott Aviation Doc. No. FS2026-344, Revision 0 or later EASA approved revision, is required on board the aircraft	1. Limited to Aircraft equipped with Raytheon Aircraft Company "Collins Pro Line 21 Avionics Suite" major change2. Limited to Configuration 3 of Elliott Aviation FAA STC SA01352CH3. This STC is approved only for the product configuration as defined in the approved design data referred to in...	06/03/2006	Active	10015349
EASA.IM.A.S.00522	AIRCRAFT SYSTEMS AND MANUFACTURING,INC		FAA STC ST09586SC REV 1	DC-9-81 (MD-87) DC-9-81 (MD-83) DC-9-81 (MD-82) DC-9-81 (MD-81)	Installation of Universal UNS Flight Management System withUL-601 Unilink Data Link System		-FAA STC ST09586SC Rev 1-ASM Top Drawing List No 5542-0001-00 Rev T-AFM Supplements Doc. No 5542-2160-00 Rev B and Doc No 5542-2161-00 or later approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	19/01/2005	Active	10015350
EASA.IM.A.S.00531	HARTZELL PROPELLER LLC		FAA SA818CE	K35, M35, P35. 35-C35, E33, F33, 35-33, 35-A33, 35-B33,	Installation of Hartzell PHC-L3YF-1RF/ F8464A-6R or BHC-L2YF-1BF/ F8668ARpropeller.				24/01/2005	Active	10042578
EASA.IM.A.S.00543	SAFTGLO Inc.		FAA STC ST02248AT	A330-300 SERIES A330-200 SERIES	Installation of Saftglo Inc photoluminescent fl0or proximity emergencyescape path marking system. (Validation of FAA approved STC ST02248AT)		- MDL L-68-2 Rev. A dated Nov 15, 2000 or later FAA approved revision.- Flight Manual supplement L68-10 Rev I.R.	1- The approval of this modification is limited to the identifiedaircraft models. The limitations and conditions defined in the EASADatasheet are also applicable. A copy of the STC approval and the MDLmust be enclosed in the files of each modified aircraft.2- This STC is approved only for the produc...	27/01/2005	Active	10043001
EASA.IM.A.S.00563	GULFSTREAM AEROSPACE Corp.		FAA ST09848SC	G200	Installation of side facing divan				09/02/2005	Active	10043020
EASA.IM.A.S.00567	GULFSTREAM AEROSPACE CORPORATION.	REV. 1	FAA STC ST10016SC-D	GULFSTREAM 200	Installation of BE Single (light weight) Seats Arrangement.		-FAA STC ST10016SC-D-Index List GA222088001 Rev. D, dated 27/03/2003, or later FAA approved revision-FAA approved flight manual supplement GA22208M001, Rev. None, dated 27/03/2003or later FAA approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	04/12/2008	Active	10015351

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00568	GULFSTREAM AEROSPACE Corp.		FAA ST10014SC-D	G200	Installation of Stainless Steel Lavatory Wast Ducting System				09/02/2005	Active	10043021
EASA.IM.A.S.00569	GULFSTREAM AEROSPACE Corp.		FAA ST09809SC-D	G200	Installation of Emergency Lighting Exit Signs and FloorpathLightingsystem				09/02/2005	Active	10043022
EASA.IM.A.S.00598	WILCO, Inc.		FAA STC SA00741WI	RAYTHEON 1900D RAYTHEON 1900C BEECH F90 BEECH E90 BEECH C99 BEECH C90A BEECH C90 BEECH B99 BEECH B90 BEECH B300 BEECH B200T BEECH B200C BEECH B200 BEECH B100 BEECH A100 BEECH 99A BEECH 99 BEECH 65-A90 BEECH 65-90 BEECH 300LW BEECH 300 BEECH 200T BEECH 200C BEECH 200 BEECH 1900 BEECH 100	Installation of the Concorde RG-380 E/K Series VRSLA Batteries, as per FAA STC SA00741WI.		- Installation Instructions W3556005.		02/03/2005	Active	10015352
EASA.IM.A.S.00604	SKYTECH, INC.		FAA STC ST01851NY	PA46-310P		Installation of Piper Mirage PA46-350P Pilot's Heated Windshield intoPiper Malibu PA46-310P in accordance with Skytech,Inc. Glass HeatedWindshield Installation. HTW-494-782-00, Revision 1 dated December 1,2003. FAA STC ST01851NY Issued onDecember 31, 2003.	- Glass Heated Windshield Installation Manual.- Instructions for Continued Airworthiness HTW-494-782-100, datedDecember1, 2003.- Airplane Flight Manual Supplement, HTW-494-782-100, Original Issue,dated October 05. 2003.		02/03/2005	Active	10042298
EASA.IM.A.S.00632	ISRAEL AEROSPACE INDUSTRIES, Ltd. (IAI)	REV. 2		BOEING 767-200	Conversion from Boeing 767-200 passenger aircraft to Boeing767-200SF (Special Freighter) configuration, to enable for Carriage of palletised cargo.Revision 1 to approved increased weight limitations		- IAI MDL TR 368-00-00-94100 Revision AR or later EASA approved revision- AFM Supplement 368-00-00-91713 Revision1 or later approved revision	1. Supplementary Data Sheet TCDS.IM.A.S.006322. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	27/06/2007	Active	10015354
EASA.IM.A.S.00640	AIRWORTHINESS RESOURCES CORPORATION	REV. 1	TCCA STC SA00-148	RESTRICTED CATEGORY CL-215-6B11 (CL-415 VARIANT)	Installation of an Integrated Liquid Spray System (ILSS)Relocation of the cockpit control panel for the Integrated Liquid Spray System (ILSS)		• Transport Canada STC No SA00-148 Issue 1 dated 21 December 2000.• AFM Supplement C53790 Rev. C TCCA approved on 14 May or later approved revision.• Modification Data Summary C53700 Rev. A.• Modification Data Summary C53700 Rev. C.• Service Bulletin A65-13-05	1. Operation in accordance with AFM Supplement C53790 Rev. B or later approved revision. AMM Supplement A65-10, orlater approved revision.2. Prior to installation of this modification the installer must determine that the interrelationship between this modificationand any other previouslyt...	22/10/2007	Active	10015355

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00647	JAMCO AMERICA, INC.		FAA STC ST01372SE	BOEING 767-300	New Seats and Interior Reconfiguration		-FAA STC ST01372SE-Jamco America Inc Master Drawing List IA-103MDL Revision A dated March 4 2004 or later FAA aproved revision	1. Limitation on FAA STC in respect of concurrent installation of Thales IFE STC ST0162LA is not applicable2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurat...	17/03/2005	Active	10015356
EASA.IM.A.S.0065	LEARJET Inc.		FAA STC ST01595LA-D	BOMBARDIER BD-100-1A10 (CHALLE	The modification consists in the installation of Control Wheel Lighted Chart Holders, in accordance with Master DrawingList HC33105000, Revision B, dated April 23, 2004 or later FAA approved revision.This STC is the validation of the FAA approved STC No. ST01595LA-D			1. Modification of an aircraft by this supplemental TypeCertificate obligates the aircraft operator to include the maintenance information provided by Document Number HC33105000-IFCA-1 in the operator's Aircraft Maintenance Manual and the operator's Aircraft Scheduled Maintenance Program.2. T...	28/07/2004	Active	10015357
EASA.IM.A.S.00657	DUNCAN AVIATION, INC.		FAA STC ST00515WI	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35	Installation of an Allied Signal CAS 67A Traffic Alert & Collision Avoidance (TCAS II). (STC ST00515WI)		- Duncan Aviation Inc. Document List No. 10048800 Revision B dated March 20, 1997, or later approved revisions.- DuncanAviation Inc. AFM Supplement Document No. 40169100 dated August 9, 2004, or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	04/04/2005	Active	10015358
EASA.IM.A.S.0066	LEARJET Inc.		FAA STC ST01603LA-D	BOMBARDIER BD-100-1A10 (CHALLE	The modification consists in the installation of a Service Panel Lighting System, in accordance with Master Drawing List HC33315000, Revision A, dated june 03, 2004 or later FAA approved revision.This STC is the validation of the FAA approved STC No. ST01603LA-D.			1. Modification of an aircraft by this Supplemental TypeCertificate under -1 Configuration/installation, obligates the aircraftoperator to include the maintenance information provided by Document Number HC33315000-IFCA-1 in the operator's Aircraft Maintenance Manual and the operator's Aircraft S...	28/07/2004	Active	10015359
EASA.IM.A.S.0067	LEARJET Inc.		FAA STC ST01253LA-D	BD-100-1A10 (CHALLENGER 300)	The modification consists in the installation of Cockpit Writing Tables, in accordance with Master Drawing List HC31515000, Revision D, dated December 18, 2003 or later FAA-approved revision.This STC is the validation of the FAA approved STC No. ST01253LA-D.			1. Modification of an aircraft by this Supplemental TypeCertificate obligates the aircraft operator to include the maintenance information provided by Document Number HC31515000-IFCA in the operator's Aircraft Maintenance Manual and the operator's Aircraft Scheduled Maintenance Program.2. Thi...	28/07/2004	Active	10015360
EASA.IM.A.S.00676	S-TEC CORPORATION	REV. 2	FAA STC SA09254AC-D	PIPER PA-28-235 PIPER PA-28-180 PIPER PA-28-160 PIPER PA-28-150 PIPER PA-28-140	Installation of S-Tec System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model ST-711-20/30According FAA-STC SA09254AC-D		Bulletin No. 811, dated 01.07.1997 and Master Document ListNo 921011, dated 01.07.1997 or later approved revision (14 Volt System)FAA approved POH and/ or AFM-Supplement P/N 891448, dated 07.07.1997 or later approved Revision for S-TEC System 20 on Piper PA-28-140, PA-28-150, PA-28-160, PA-28-180 S...	1. Limitation according FAA STC SA09254AC-D2. Compatibilityof this modification with other previously approved modifications must be determined by the installer3. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description...	11/09/2008	Active	10015362

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00677	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST01523SE	BOEING 747-400	1. Configuration 1:Installation of Interior Components in accordance with Delta Engineering Master Data List 0107-05983-2128, Revision A, dated March 26, 2007 or later DAS approved;2. Configuration 2:Installation of Interior Components in accordance with Delta Engineering Master Data List 0107...		1. 707-05808-2128 Rev - May 1, 2006 ICA for Cabin Interior Update;2. 707-05888-2128 Rev - Sept. 8, 2006 ICA for Cabin Interior Update;3. AMM supplement HTM-EG744-MM01 Rev.O Interior installation H9300-1, -3.	1. The approval holder shall fulfill the obligations of Part 21, Paragraph 21 .AI 09;2. Configuration 1:- ThisSTC must be installed concurrent with Jamco America ST01455SE, EJM Aerospace Services ST03078AT, STG Aerospace ST02993AT and Boeing Service Bulletin 747-25-3306, Revision 12 and is...	09/09/2008	Active	10015363
EASA.IM.A.S.00679	E.J. MLYNARCZYK & CO. INC.	REV. 1	FAA STC ST03078AT	BOEING 747-400	Installation of a Panasonic Avionics Corporation System 3000 In-Flight Entertainment System in accordance with Master Drawing List MDL 10413, Rev. F dated 14 September 2005. Validation of FAA STC ST03078AT amended 22 September 2005.		FAA-approved AFM supplement, document No. 14526015, dated 29 March 2005, or later FAA approved revision is a required part of this STC.	1. STC No ST01523SE must be accomplished concurrently withMAS10413-01 and MAS10413-02 installations.2. This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraph "Description". Compatibility with other aircraft/ engine configura...	12/10/2005	Active	10015364
EASA.IM.A.S.0068	LEARJET Inc.		FAA STC ST01254LA-D	BOMBARDIER BD-100-1A10 (CHALLE	The modification consists in the installation of an Artex ELT with Nav Interface in accordance with Master Drawing ListHC25615000,Rev. D dated December 19, 2003 (or later FAA approved revision).This STC is the validation of the FAA approved STC No. ST01254LA-D.			1. The Maintenance Instructions for Continued Airworthiness are contained in Documents Number HC25615000-IFCA. Modification of an aircraft by this STC obligates the aircraft operator to include the maintenance information provided by this document in the operator's Aircraft Scheduled Maintenance2...	28/07/2004	Active	10015365
EASA.IM.A.S.00699	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE	REV. 1	FAA STC STOL925CH	ATR 72-202, -212 ATR 42-200, - 300, -320, -500	Installation of a Honeywell RESCU 406AF Emergency Locator Transmitter (ELT) System in accordance with Armstrong Aerospace Master Data List,Doc. No. DCl04-3016-00, revision B< (>,<)>dated December 9, 2003, orlater FAA-approved revision.Validation of FAA-approved STC STOl925CH		Armstrong Aerospace Master Data List Doc. No DC 104-3016-00. revision B,dated December 9, 2003, or later FAA-approved revision.FAA-approved AFM Supplement, Armstrong Aerospace Doc. No DC303-3016-00,revision-< (>,<)> approved December 31<(>,<)> 2003, or later FAA-approvedrevision, is required on board...	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	26/10/2005	Active	10064928
EASA.IM.A.S.00759	NORTHROP GRUMMAN GUIDANCE ANDELECTRONIC SYSTEMS COMPANY, Inc.	REV 2	FAA STC ST01149LA	AIRBUS A300 MODEL B4-203 AIRBUS A300 MODEL B4-103 AIRBUS A300 MODEL B2-203	Installation of Litton Heading and Attitude System (LHAS) LTR-97.This STC is the result of the FAA STC No. ST01149LA validation.		Top installation Drawing List, Document No. 454170-14 Revision C, dated 27 June 2001.	1. This STC is limited to the installation of three LHAS LTR-97 (triple configuration). 2.The Airplane Flight Manual Supplement, Document No. 434593-EASA dated 25 May 2005 is required as part of this installation.3. This STC is approved only for the product configuration as defined in the approved de...	31/07/2006	Active	10015366
EASA.IM.A.S.00762	HAWKER BEECHCRAFT SERVICES	REV. 1	FAA STC SA00560DE	BEECH 1900C, 1900D	Installation of a L3/ACSS TCAS-2000 (Traffic Alert Collision AvoidanceSystem).Note: This Revision reflects the transferof this STC from Genesis 3 toHawker Beechcraft Services Inc.		Genesis 3 Engineering Master Drawing List, Document No. GEN-040311-002Revision A, dated September 2, 2004 or later EASAapproved revisions.	1. Instructions for Continued Airworthiness Document No.GEN-040311-0116Revision IR dated May 5, 2004 or later EASA approvedrevisions.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other ai...	05/09/2007	Active	10042557

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.00763	NORTHWEST COMPOSITES		FAA STC ST01565SE	BOEING 737-400 BOEING 737-300	Stowage bin Extension.		Northwest Composites Master Drawing List Ref.: A07800 Revision C dated 8th June 2005 or later FAA approved revision.FAASTC No. ST01565SE dated 9th June 2005.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	17/06/2005	Active	10015367
EASA.IM.A.S.0090	ROCKWELL COLLINS, Inc.		FAA STC SA5859NM	A320	Installation of Video Entertainment System in accordance with FAA approved Hugues-Avicom Index list 607278, Revision "A", dated September 24, 1992, or later FAA approved revisions.			1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft configurations shall be determined by the installer.	09/08/2004	Active	10015368
EASA.IM.A.S.0094	STAR AVIATION, Inc.	REV. 1	FAA STC ST02642AT	500/501, 550/551, S550 AND 560	Installation of RVSM Air Data System in accordance with Master Data ListR-34-Y29-041 Rev. S dated 06/12/04 or later EASA-approved revision.Flight Manual Supplements R34-157 Rev. Bor later EASA-approvedrevision. R34-201 Rev. B or later EASA-approved revision.			1. Subject to compliance with the provisions of Part 21 Subpart E, thisSTC and associated data shall remain valid untilsurrendered. withdrawnor otherwise terminated.2. If transfer of this Certificate is requested under Part 21A.116, theSTC will be reissued.3. Where aircraft have an Emergency Bus Ba...	08/08/2006	Active	10048033
EASA.IM.A.S.01007	GOODRICH CORPORATION		FAA ST00174BO	737-400, 737-500 737-200, 737-200C, 737-300	EASA Validation of FAA STC ST00174BO for "Installation of GoodrichCorporation Float Switch Transient Suppression Device" on Boeing 737Classic Aircraft		Master Drawing list for the Float Switch Transient Suppression Device,applicable to Boeing 737-200 through -900 Series Airplanes, Revision F,dated 17th August 2004 or later approved revisionEASA Approval No 2004-11309 for AMOC to FAA AD 2004-15-04 for B737Classic Types	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	17/05/2005	Active	10015369
EASA.IM.A.S.01009	HAWKER BEECHCRAFT CORPORATION (HBC)		FAA STC SA8356SW	HAWKER 1000	Installation of Air Distribution System		-FAA STC SA8356SW-Arkansas Aerospce Inc. Drawing List 1000-015-3 rev B dated June 21 1994 or later approved revision-AFM Supplement ref. 1000-0014 dated June 26 1992 or later approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	11/02/2005	Active	10015370
EASA.IM.A.S.01011	HAWKER BEECHCRAFT GLOBAL CUSTOMERSUPPORT, L.L.C.		FAA SA8350SW	HAWKER 1000	Installation of Cabin Oxygen System		-FAA STC SA8350SW-Arkansas Aerospace Inc. Drawing List 1000-009 rev D dated July 17 1995or later approved revision-FAA Approved Flight Manual Supplement ref 1000-0043 dated 28 July 1995or later approved revision	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	11/02/2005	Active	10042558
EASA.IM.A.S.01012	DECA AVIATION ENGINEERING Ltd.			A330-322	Installation of a 10 Flight Attendant Seat. Validation of TransportCanada approved limited STC No O-LSA02-095/D issue 3. The STC is definedby DECA modification summary MS02180 issue 2. (or later TransportCanada-approved revision)			1. The approval of this modification is limited to the Airbus A330-322MSN 087 and 171 only. The limitations and conditions defined in the EASADatasheet are applicable. A copy of this STC must be enclosed in thefiles of each modified aircraft. Any alteration of the STC definitionmust be made with the...	29/03/2005	Active	10042559

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01013	DECA AVIATION ENGINEERING Ltd.			A330-322	Installation of a passenger cabin reconfiguration, Single class to twoclass Arrangement. This is the validdation of Transport Canada approvedlimited STC No O-LSA04-115/D issue 1. The STC is defined by DECAmodification summary MS04038 issue2. (or later Transport Canadaapproved revision)			1. The approval of this modification is limited to the Airbus A330-322MSN 171 only. The limitations and conditions defined in the EASADatasheet are applicable. A copy of this STC must be enclosed in thefiles of each modified aircraft. Any alteration of the STC definitionmust be made with the written...	29/03/2005	Active	10042560
EASA.IM.A.S.01014	HONEYWELL INTERNATIONAL INC.	REV 1		SEE STC LIST	Installation of Honeywell TFE731-3D-1H or TFE731-3DR-1H Turbofan Engines.		1. Garrett Aviation Services drawing list DL456 dated February 14, 1996;2. AFM Supplement Landmark Aviation document 1013496, Rev. (A), dated August 9, 2007;3. Master Data List DL456, dated July 10, 2007, revision (C),		31/03/2008	Active	10015371
EASA.IM.A.S.01023	GARMIN INTERNATIONAL, Inc.		SA01254WI	DIAMOND DA-40	Installation of Garmin G1000 in the DA40 and DA40F airplane		-Master Drawing List, 005-C0004 Rev U or later approved revision-Required Equipment List, 005-00305 Rev K or later approved revision-EASA Airplane Flight Manual Supplement, 190-00303-81 Rev 1 or later approved revision-G1000 Maintenance Manual, 190-00545-00 or later approved revision	1. Hartzell Propeller STC EASA.IM.A.S.01644 must be installed2. Diamond Aircraft Inductries Modifications listed in Garmin Drawing 005-00304-00 Rev 10 or later approved revision must be installed	11/08/2006	Active	10015372
EASA.IM.A.S.01026	HAWKER BEECHCRAFT CORPORATION (HBC)		SA8348SW	HAWKER 1000	Installation of Honeywell SRZ-8000 Digital Integrated Flight Control System with low speed awareness cue in accordance with Arkansas Aerospace Inc. Drawing List 1000-008		STC Drawing List 1000-008AFMs 1000-0009, 1000-0010, 1000-0015, 1000-0016, 1000-0038, 1000-0046	This STC does not give:PRNAV approvalRVSM approvalCAT II approval	01/02/2007	Active	10015373
EASA.IM.A.S.01042	JET ENGINEERING LLC		FAA STC ST01542LA	DC-9-81/-82/-83/-87, MD-88	FAA STC No. ST01542LAInstallation of JET Engineering, LLC Jet nozzles on the applicablemodels when powered by Praft & Whitney JT8D-217/-219 engines.		JET Enginering Master Drawing List (MDL) No 200-1000; SupplementalMaintenance Manual for the Jet Engineering Jet Nozzles installed onDC-9-80 series aircraft, JET-TR-401;Supplemental Structural Repair Manual to the McDonnell Douglas DC-9-80series aircraft, Structural Repair Manual, JET-TR-210, Revisi...	1. The installation should not be incorporated in any airplane unless itis determined that the Interrelationship between this installation andany previously approved configurationwill not introduce any adverseeffect upon the airworthinessof the airplane. The approval of thismodification applies to...	06/09/2005	Active	10042563
EASA.IM.A.S.01045	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC ST01583LA	737-300, 737-400	Installation of ACSS T2CAS System according to FAA STC ST01583LA dated 20th January 2004.- ACSS Index of Master Data Lists, Document No. 8900034, Revision "A" dated 3rd September 2004, or later FAA approved revision- ACSS Airplane Flight Manual Supplement, Document No. 8002391-001, Revision "A" date...		- ACSS Index of Master Data Lists, Document No. 8900034, Revision "A" dated 3rd September 2004, or later FAA approved revision- ACSS Airplane Flight Manual Supplement, Document No. 8002391-001, Revision "A" dated 21st October 2004, or later FAA approved revision	1. According to limitations section in FAA STC ST01583LA dated 20th January 2004.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined b...	17/08/2005	Active	10015375
EASA.IM.A.S.01049	ROSEMOUNT AEROSPACE, Inc.		FAA STC ST02175CH	BOEING 747-400	Installation of Rosemount Aerospace 8400M Series Cockpit Door Surveillance System		-CAA-NL report IVW/LTB/TCP-05.533157	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015376

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01050	ROSEMOUNT AEROSPACE, Inc.		FAA STC ST02203CH	MD-11	Installation of Rosemount Aerospace 8400M Series Cockpit DoorSurveillance SystemFAA STC ST02203CH		CAA-NL reportnr: IVW/LTB/ TCP-06.531095	1. FAA approved Airplane Flight Manual Supplement, Rosemount AerospaceCDSS AFM Supplement to McDonnell Douglas MD-11, Document D0431158,Revision A, or later FAA approved revision,is required on board ofmodified aircraft.2. This STC is approved only for the product configuration as defined inthe app...	17/02/2006	Active	10042935
EASA.IM.A.S.01051	HONEYWELL INTERNATIONAL INC.	REV 1	FAA STC NO ST02005CH-D	LEARJET 55	Installation of Honeywell N1 Digital Electronic Engine Control (DEEC)Note: This revision reflects the transfer of STC EASA.IM.A.S.01051 from Garrett Aviation Services to HoneywellInternational Inc.		-Garrett Aviation Services Drawing List 1001811 Revision A dated October 5 2004 or later approved revision-AFM Supplement 1002971 Revision A dated October 7 2004 or later approvedrevision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	02/04/2009	Active	10015377
EASA.IM.A.S.01052	GOODRICH CORPORATION			B767-300	Installation of passenger seating arrangement		Tramco in Master Drawing List 96-025 Revision C, dated April 27, 1996 orlater EASA approved revisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	18/07/2005	Active	10042937
EASA.IM.A.S.01055	WILKINSON AIRCRAFT SERVICES, Inc.		FAA STC SA10107SC	PA-46-310P	Installation of a 2 direct drive vacuum pump using the installation instruction document number 0001, revision Original dated 2/2/02 or later FAA approved revision		-FAA STC SA10107SC issued November 12, 2002-Installation Instruction Document number 0001, revision Original dated 2/2/02 or later FAA approved revision-Airplane Flight Manual Supplement document number 0001, revision Original dated 2/2/02 or later FAA approved revision	1. Airplane Flight Manual Supplement document number 0001,revision Original dated 2/2/02 or later FAA approved revision required2. This STC is approved only for the product configuration as defined in the approved design data referred toin the paragraph "Description". Compatibility with other air...	10/03/2005	Active	10015378
EASA.IM.A.S.01058	MICRO AERODYNAMICS, INC.		FAA STC SA00763SE	PIPER PA-39 PIPER PA-30	Installation of Vortex Generators on the Wing leading edge,and vertical fin surfaces.Drawing Package MA2122 Rev. IR dated 25 October 1999, or later approved revision.AFM Supplement for PA-30 & PA-39 dated 13 July 2005.Installation Manual MA2123 Rev. IR dated 8 December 1999 or later approved revisi...			1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	08/08/2005	Active	10015379
EASA.IM.A.S.01060	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST01430CH	A300 B4-2C/B4-103/ B4-203 A300 B2-1A/B2K-3C/ B2-1C/B2-203	Installation of universal Avionics Systems Corporation ElectronicHorizontal Situation Indicators (EHSI)		Master Data List ECS-200389, revision H, dated 04 November 2005 or laterapproved revision	1. Aircraft Flight Manual Supplement ECS 200408 revision B,dated 15November 2005 or later approved revision2. Instruction for Continued Airworthiness ECS 200411, revision B dated1 April 20053. If the holder agrees to permit another personto use this certificateto alter the product, the holdr shall...	20/09/2006	Active	10042938
EASA.IM.A.S.01061	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01256WI-D	SEE EASA APPROVED MODEL LIST	Modification of a Collins TPR-720, TPR-900 or TPR-901 Mode S transpondersystem installation with an ATC/TCAS control panel to an ElementarySurveillance compliant Collins TPR-901 Mode S transponder systeminstallation with a flight ID/ATC/ TCAS control panel in accordance withCollins Drawing Index as l...		FAA STC ST01256WI-D, Approved model list No ST01256WI-D. Collins DrawingIndex RCA-0010-001, Revision E or later approved revisions.	1. In lieu of an AFM Supplement, the required Gables FlightID/ATC/ YCAScontrol panel pilot's guide, as applicable per FAA approved CollinsDrawing Number RCA-2018-001, "Installation Instructions, Mode Transponder and Flight ID/ ATC /TCAS control panel in Part 25 aircraft",revision 1 dated July 23, 20...	06/06/2006	Active	10042939

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01062	ROCKWELL COLLINS, Inc.d/b/a AIR TRANSPORT SYSTEMS		FAA STC ST01713LA	BOEING 747-400	Installation of Rockwell Collins enhanced Total Entertainment System in accordance with FAA STC No ST01713LA issued February 12, 2005		-System List 1309056, Configuration -002, Revision N, datedFebruary 12, 2005 or later FAA approved Revision	1. FAA STC ST01507SE must be installed in conjunction with this installation2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the...	01/03/2005	Active	10015380
EASA.IM.A.S.01064	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA ST02788AT	767-200, 767-300, 767-300F	Installation of Provisions for Terrain and Traffic Collision AvoidanceSystem (TTCAS)This STC is a validation of FAA STCST02788AT.		-EMTEQ Engineering Master Drawing List EMTEQ-025-MDL Revision datedJanuary 27, 2004 or later Faa approved revision-AFM supplement Doc No 8002964-001	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	09/03/2005	Active	10042940
EASA.IM.A.S.01065	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 1	FAA ST001627LA	767-200, 767-300	Installation of T2CAS		-FAA STC ST001627LA-Doc. No. 8900037, Rev A dated 11 May 2004 or later FAA revision.-AFM Doc. No. 8002964-001, Rev "-" dated 27 April 2004, or later FAArevision	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	21/09/2005	Active	10042943
EASA.IM.A.S.01066	S-TEC CORPORATION	REV. 1	FAA STC SA8896SW-D	CESSNA T210R CESSNA T210N CESSNA T210M CESSNA T210L CESSNA 210R CESSNA 210N CESSNA 210M CESSNA 210L	Installation of S-TEC System 55/55X Two Axis Automatic flight Guidance System, Model ST-566, according to Bulletin No 666, Rev 2 dated 1-25-01 or later approved revisions		-S-TEC Master Drawing List No 92734, Rev B, dated 1-25-01, or later approved revision-FAA/DAS approved Supplements to pilot's operating Handbooks and/or Approved Airplane Flight Manual, as defined in the Limitations and Conditions section of FAA STC SA8896SW-D, latest approved revision.Instructions...	1. As defined in the Limitations and Conditions section of FAA STC SA8896SW-D, latest approved revision2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adve...	09/09/2008	Active	10015381
EASA.IM.A.S.01067	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)	REV. 1	FAA STC ST001628LA	757-200	Installation of T2CAS		-FAA STC ST001628LA-ACSS Index of Master Data Lists Document Number 8900036 Revision Bdated May 10 2004 or later FAA approved revision-ACSS Flight Manual Supplement number 8002942-001 revision "-" dated May5 2004 or later FAA approved revision	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	21/09/2005	Active	10042944
EASA.IM.A.S.01069	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01220LA-D	GULFSTREAM GV S/N 641	Aircraft Serial No. 641 completion and cabin interior installation.		Installation in accordance with approved Gulfstream Aerospace Corporation Index List GC52 0008277, Revision "D", dated May 13, 2002or later approved revisions.Operation to be in accordance with Gulfstream Flight Manual Supplement C-7517 AFMS, latest approved revision.	1. GV Serial No. 641 only	17/07/2007	Active	10015382

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.0107	S-TEC CORPORATION	REV. 1		CESSNA 177B CESSNA 177A CESSNA 177	Installation of S-TEC Sysytem 20/30 Single and Two-axis Automatic Flight Guidance Systems.		Installation of S-TEC Sysytem 20/30 Single and Two-axis Automatic Flight Guidance Systems. Model ST-741-20/30. In accordance with Bulletin No 841, dated 11-03-97 and Master Drawing list No 921040, dated 11-03-97 or later FAA Approved revisions as defined in FAA STC SA09295AC-D.Flight Manual Suppleme...	1. Subject to compliance with the provisions of Part 21 Subpart E, this STC and associated data shall remain valid until surrendered, withdrawn or otherwise terminated.2. Iftransfer of this Certificate is requested under Part 21A.116, the STC will be reissued.3. This STC is approved only f...	10/09/2008	Active	10015383
EASA.IM.A.S.01071	VIDEO TECHNOLOGY SERVICES, Inc.		FAA STC ST01089NY	767-200, 767-300					23/03/2005	Active	10042226
EASA.IM.A.S.01072	DUNCAN AVIATION, INC.			CESSNA 750	Installation of an AirCell Iridium ST-3100 Single Channel SATCOM		-Duncan Aviation Drawing List DA0211-01R Revision A dated December 272002 or later approved revision	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	18/03/2005	Active	10042945
EASA.IM.A.S.01073	F. ATLEE DODGE AIRCRAFT SERVICESLLC		FAA STC SA00092SA	PA-22-150, PA-22-160	30.5 Gallon Fuel Tanks manufactured in accordance with Drawing List 30.5GAL TANKS, dated 09/03/1992, and installed in accordance withInstallation Instructions No 3258-1, rev 1, dated 10/02/1994 or laterapproved revisions		-FAA STC No SA00092SA-Installation Instructions No 3258-1-FAA approved Supplemental Flight Manual, dated 16/10/1998, orlater FAAapproved Revision	1. FAA approved Supplemental Flight Manual, dated 16 October 1998, orlater approved revision is a required part of thisinstallation2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other air...	22/08/2005	Active	10042946
EASA.IM.A.S.01075	AIR RADIO SERVICE GMBH			CESSNA 550B	Upgrade of GPWS to EGPWS		- AFM Supplement 5387/04/1-06	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	10/02/2005	Active	10042947
EASA.IM.A.S.01076	ROCKWELL COLLINS AEROSPACEAND ELECTRONICS, Inc.		FAA STC ST01205NY	CL-600-2B19	Installation of Head-Up Guidance System (HGS) model 2100		-FAA STC ST01205NY-STC Master Drawing List No 9701-1085 Revision L dated November 02,2004,configuration 1000-0450-009	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	11/02/2005	Active	10042948
EASA.IM.A.S.01077	LITEAIR AVIATION PRODUCTS Inc.		FAA STC ST01237SE	B757-200, B757-200CB, B757-300	Installation of Lightweight Window Plugs.		-FAA STC ST01237SE.-LiteAir Aviation Products Inc Master Drawing List LAP1005-D01 revisionIR dated May 01, 2003 or later FAA-approved revision.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	22/04/2005	Active	10042949
EASA.IM.A.S.01078	LITEAIR AVIATION PRODUCTS Inc.		FAA STC ST01091SE	BOEING 737-900 BOEING 737-800 BOEING 737-700C BOEING 737-700 BOEING 737-600 BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200C BOEING 737-200 BOEING 737-100	Installation of Lightweight Window Plugs.		-FAA STC No ST01091SE.-LiteAir Aviation Products Inc MasterDrawing List LAP1004-D01 revision A dated July 9, 2003 or later FAA-approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	22/04/2005	Active	10015384

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01079	LITEAIR AVIATION PRODUCTS Inc.	REV 1	FAA STC ST00758SE	BOEING 767-300 SERIES BOEING 767-200 SERIES	Installation of Lightweight Window Plugs		LiteAir Aviation Products Inc master Drawing List LAP1002-D01 revision IR dated October 22, 1999 or later FAA approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	26/03/2009	Active	10015385
EASA.IM.A.S.01080	LITEAIR AVIATION PRODUCTS Inc.		FAA STC ST00638SE	BOEING 747-SR BOEING 747-400D BOEING 747-400 BOEING 747-300 BOEING 747-200C BOEING 747-200B BOEING 747-100B SUD BOEING 747-100	Installation of upper deck lightweight window plugs		LiteAir Aviation Products Inc. Master Drawing List LAP1001-D02 revision IR dated June 13, 1998 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	18/11/2005	Active	10015386
EASA.IM.A.S.01081	LITEAIR AVIATION PRODUCTS Inc.		FAA STC ST00353SE	BOEING 747-SR BOEING 747-400D BOEING 747-400 BOEING 747-300 BOEING 747-200C BOEING 747-200B BOEING 747-100B SUD BOEING 747-100	Installation of Main Deck Lightweight Window Plugs.		-FAA STC No ST00353SE.-LiteAir Aviation Products Inc. Master Drawing List LAP1001-D01 revision D dated June 18, 1996 orlater FAA-approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	22/04/2005	Active	10015387
EASA.IM.A.S.01085	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01671LA-D	GULFSTREAM GV-SP	Cabin Interior Installation		-FAA STC ST01671LA-D and associated documentation-GAC Flight Manual Supplement GCS51605M006	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	25/01/2005	Active	10015388
EASA.IM.A.S.01086	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01376LA-D	GULFSTREAM GV-SP	Installation of Aerospace Technologies Group (ATG) Cabin Window		FAA STC ST01376LA-D and associated documentation	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	25/01/2005	Active	10015389
EASA.IM.A.S.01087	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01373LA-D	GULFSTREAM GV-SP	Installation of Securaplane External Camera System		-FAA STC ST01373LA-D and associated documentation-Gulfstream Flight Manual Supplement GC51501M007	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	25/01/2005	Active	10015390
EASA.IM.A.S.01089	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01375LA-D	GULFSTREAM GV-SP	Installation of Airshow CMS Two System		FAA STC ST01375LA-D and associated documentation	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	25/01/2005	Active	10015391
EASA.IM.A.S.01091	LEARJET Inc.		FAA STC ST01619LA-D	BOMBARDIER BD-100-1A10 (CHALLE	Installation of an Executive Interior in accordance with Master Drawing List HC200335000 Revision D or later FAA approved revision		FAA approved AFM supplements H-FM25285002 rev A dated 29 July 2004.	1. The Maintenance Instructions for Continued Airworthinessare contained in Document Number HC200335000-IFCA-1. Modification of anaircraft by this STC obligates the aircraft operator to include the maintenance information provided by thisdocument in the operator's Aircraft Maintenance Manual and t...	24/01/2005	Active	10015392

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01094	DELTA ENGINEERING CORPORATION	REV. 2	FAA STC ST01507SE	BOEING 747-400	Description of Design Change:Installation of Interior Equipment: 1.ConfigurationInstallation of interior components in accordance with Health Tecna, Inc. Drawing List HPD-DL-55, Rev. BF, dated February 11, 2005 or later approved revision. 2.ConfigurationModification of Seat Tracks in accordance with...		-Heath Techna Inc. Drawing List HPD-DL-55, Rev BF dated February 11, 2005 or later approved revision. 1.0107-05791-2127 Delta Engineering Master Data List2.0107-05879-2127 Master Data List P94 Power Panel3.Instruction for Continued Airworthiness document 0707-05792-2127 Rev. dated March 29, 2006.4.07...	1.This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer. 2.Configuration 1:TThis STC is limited to Interior Kits H2600-271,...	01/11/2007	Active	10015393
EASA.IM.A.S.01095	HARTZELL SERVICE CENTER		SA1105CH	PIPER PA-32-260	Installation of Hartzell HC-C3YR-1RF/ F7693F three bladed propeller on the Piper-PA32-260 per FAA STC SA1105CH		FAA approved AFM supplement PA-32-99-2 dated July 7, 1999 or later FAA approved revision	1. EASA does not consider this modification to increase thenoise level and it was not considered an acoustical change from the HC-C2YK-1F/ F8477-2 Propeller.2. If the holder agrees to permit another person to use this certificate to alterthe product, the holder shall give the other person written3...	30/05/2005	Active	10015394
EASA.IM.A.S.01096	NORTHWEST AEROSPACE TECHNOLOGIESI NC.			BOEING 757-200	Installation of ELS/EHS S system Upgrade		Northwest Aerospace Technologies MDL N0212-D10 Rev A dated June 2005 or later approved revsion.AFM supplement N0212-D80or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	15/08/2005	Active	10015395
EASA.IM.A.S.01098	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		ST02993AT	BOEING 747-400	Installation of SafTGIo Inc. Photoluminescent floor proximity emergency escape path marking system (FPEEPMS) in accordance with SafTGIo MDL Report M39-2, rev. B dated October 11, 2004 or later FAA-approved revision		AFM Supplement SafTGIo Report No M39-11 rev. IR dated September 03, 2004 or later FAA-approved revision.Flight Attendant Manual (FAM) Supplement SafTGIo report No M39-13 rev. A dated October 7, 2004 or later FAA-approved revision.Flight Crew Operating Manual (FCOM) SafTGIo Report M39-14 rev. IR date...	1. The photoluminescent FPEEPMS is only eligible for installation on aircraft model numbers with interior arrangements approved in the SafTGIo MDL, incorporating SafTGIo drawing SG-B747 rev B dated October 7, 2004 or later FAA-approved revision.2. Electrically-lit door exity marker lighting le...	16/03/2005	Active	10015396
EASA.IM.A.S.01099	S-TEC CORPORATION		FAA STC SA09502AC-D	AVIATION AIRCRAFT A-1B AVIATION AIRCRAFT A-1A AVIATION AIRCRAFT A-1	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST-881		-FAA STC SA09502AC-D-Bulletin No 981 Revision 1, dated September 14, 2000 and Master Drawing List no 921193, Revision A, dated September 14, 200 or later FAA approved revision (14/28 Volt Systems) FAA/DAS Approved Airplane Flight Manual Supplement, Part Number 892064 dated September 19, 2000 o...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	01/03/2005	Active	10015397
EASA.IM.A.S.01101	ELECTRONIC CABLE SPECIALISTS, Inc.		ST02126CH	BOEING 757	Installation of elementary & enhanced Mode S Transponders		Electronic cable Specialists Master Data List ECS-202731 revision C dated March 4 2005 or later approved revisionAFM Supplement as listed in Electronic Cable Specialists Master Data List ECS-202731 revision C dated March 4 2005 or later approved revision		26/07/2005	Active	10015398

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01109	AERO ASSOCIATES, Inc.		FAA STC SA00548AT	172 SERIES	Camera Hole Installation		Aero Associates Inc Drawing ED94003 no revision dated march25, 1994 or later FAA approved revison as defined in FAA STC SA00548AT	1. Continued Airworthiness-All new and modified structure that forms part of this STC must be inspected at least annually for damage. Any defects found must be repaired by approved repair scheme.2. This STC is approved only for the productconfiguration as defined in the approved design data referre...	30/05/2005	Active	10015399
EASA.IM.A.S.01110	BLACKHAWK MODIFICATIONS Inc.		FAA SA10341SC	B. C90, E90 A. C90A	Installation of Pratt & Whitney Canada PT6A-135A (de-rated to 550 HP) engines and McCauley 4HFR34C762/94LMA-4 or 4HFR34C768/94LMA-4propellers in accordance with Blackhawk Modifications Inc Drawing No 19005-01 Rev IR, dated 15 March 2004, "Installation Instructions" or later approved revision		AFMS No 19005 Rev IR, dated 24 November 2004 or later approved revisionNote: approved noise level 74.4 dB (A) at 10100 lbs	1. AFMS No 19005, Rev IR 24 November 2004 oe later approvedrevision is required for the Raytheon C90, C90A or E90 airplane with Pratt& Whitney Canada PT6A-135A engines. Note thatthe Horsepower is limited to 550 at 1900 RPM.2. Each enginemount must be removed from the airplane, cleaned and non-des...	29/03/2006	Active	10015400
EASA.IM.A.S.01111	LANDMARK AVIATION		FAA STC ST451CH-D	CESSNA 650	Installation of an AlliedSignal Avionics MK-VII, Enhanced Ground Proximity Warning System		-FAA STC ST451CH-D-Garrett Aviation Services drawing list DL541 revision B dated August 12 1998 or later approved revision-1/ AFM Supplement dated August 21 1998 or later aproved revision-2/AFM Supplement AFMS202 dated January 23 1999 or AFMS204 dated January 25 1999 no revision or later approved r...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	24/03/2005	Active	10015401
EASA.IM.A.S.01112	LANDMARK AVIATION		FAA STC ST451CH-D	CESSNA 650	Installation of a Bendix/King CAS 67A TCAS II System with Dual Bendix/King MST-67A Mode S Transponders		-FAA STC ST451CH-D-Garrett Aviation Services Drawing List DL38102 no revision dated January 19 1995 or later approved revision-1/AFM Supplement dated February 14 1995 no revsion or later approved revision-2/AFM Supplement document 53-8783-001 no revision dated September 13 2000 or later approved re...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	24/03/2005	Active	10015402
EASA.IM.A.S.01113	AVIATION PARTNERS, INC.		FAA ST01411SE	HAWKER 800XP BAE.125 SERIES 800A/ 800B	Installation of Winglets, associated changes in wing and Aileron structures and related systems changes on Raytheon Aircraft Company Model Bae 125 Series 800A, 800B and Hawker 800XP Aircraft, in accordance with FAA STC ST01411SE		Aviation Partners Inc Master Drawing List ref APH-0605, Revision A, dated May 12, 2004 for Models 800A and B, and ref APH-0610, Revision A, dated November 23, 2004 for the Model 800XP, or later approved revisionsAircraft modified in accordance with this STC must be operated in accordance with an FAA...	Installation of this STC on Model Hawker 800XP is limited to Aircraft equipped with the Honeywell DFZ-800 (SPZ-800 avionics) autopilot, the Collins 85/86 (FCC-86E avionics) auto pilot and Collins Pro line 21 (FGC-300 avionics) autopilot, for Category I approachesonlyAirworthiness Limitations, APH-06...	26/10/2005	Active	10015403
EASA.IM.A.S.01114	ROCKWELL COLLINS, Inc.			B737-400, B737-700, B737-800	Installation of a Video Entertainment System		Sony Trans Com Inc. Index List 062-0138, Rev New, or later FAA approvedrevisions	1. B737-400:For Certification basis refer to FAA TCDS A16WEplus JAA TGL No 17, IFESystems2. B737-700, -800:For Certification basis refer to EASA TCDS JAA/ 25/97-018 plus JAA TGL No17, IFE Systems3. This STC is approved only for the productconfiguration as defined inthe approved design data referred...	07/04/2005	Active	10042950

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01117	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA ST01702LA	747-200, 747-300	Installation of ACSS T2CAS		-in accordance with Approval Report DL/LVT/05.532542-FAA approved ACSS Index of Master Data lists, Document No 8900035 revision A, dated 27 October 2004 or later approved revision-FAA approved ACSS Airplane Flight Manual Supplement Document No 8003638-	1. in accordance with Approval Report DL/LVT/05.5325422. T2CAS Airplane Flight Manual Supplement (AFMS), ACSS document number 8003638-001 revision A, approved by the FAA on May 25, 20053. This STC is approved only for the product configuration as defined in the approved design data referred to in th...	01/08/2005	Active	10015406
EASA.IM.A.S.0112	AIRWORKS		FAA STC ST01433	A340-211/-3J 1/-313/-642	This STC deals with the installation of a Cockpit Door SurveillanceSystem. This STC is the validation of the FAA approved STC No ST01433.All documents related to this STC are listed in the Index List DocumentNo IL23005 revision A dated March 25th 2004 (or later EASA approvedrevision).			1.The approval of this modification is limited to the AirbusA340-211/-311/-313/-642. The limitations and conditions defined in theJAA Datasheet are applicable. A copy of this STC and of thissupplemental data sheet must be enclosed in the files of each modifiedaircraft. Any alteration of the STC defi...	12/08/2004	Active	10043108
EASA.IM.A.S.01123	GENERAL AEROSPACE INC		FAA STC ST02902AT	BOEING 767-300 SERIES BOEING 767-200 SERIES	Installation of a honeywell RESCU 406 AF ELT system		General Aerospace Master Drawing List GA672-ELT-MDL revision D dated April 19, 2005 or later FAA approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	30/05/2005	Active	10015409
EASA.IM.A.S.01124	FLIGHT TEST ASSOCIATES, INC		FAA STC ST01524LA	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35 LEARJET 31	Installation of Rosemount Pitot Static Probe Part Numbers 856NA1 & 856NA2		West Star Aviation Inc. Master Drawing List 30A210001 Revision G dated May 20 2004 or later approved revision, for the airplanes equipped with J.E.T. Model FC-200 Autopilots.AFM Supplement 30A040002 Revision B dated August 10 2004 or laterapproved revision.Instructions for continued airworthiness i...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	05/07/2005	Active	10015410
EASA.IM.A.S.01125	FLIGHT TEST ASSOCIATES, INC		FAA STC ST01525LA	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35 LEARJET 31	Installation of Honeywell AZ-252 air data computer, Ba-250 barometric altitude display, AM-250 barometric altimeter, AL-800 altitude alert controller, and Aerosonic standby altimeter.		West Star Aviation Inc. Master Drawing List 30A210002 revision F dated July 12 2004 or later approved revision.For airplanes equipped with J.E.T. model FC-200 autopilots Flight Test Associates AFM supplement 30A040002 revision B dated August 12 2004 or later approved revision. Instructions for conti...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	06/07/2005	Active	10015411
EASA.IM.A.S.01126	FLIGHT TEST ASSOCIATES, INC		FAA STC ST0152LA & ST01525LA	LEARJET 35, 35A, 36, 36A	Aircraft modifications for establishing the approval basis for ReducedVertical Separation Minimum.		FAA STC ST0152LA & ST01525LA dated August 12 2004 or later approvedrevisions.Learjet models 35/35A/36/36A with J.E.T. models FC 200 & FC 350autopilotsAFM Supplement 30A040003 revision B dated August 10 2004 or laterapproved revision. Instructions for continued airworthiness forairplanes equipped wit...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	07/06/2005	Active	10042951

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01128	AMSAFE, Inc.		FAA STC SA01700LA.	3. 206H, T206H 2. 182S, 182T, T182T 1. 172R, 172S	Installation of AMSAFE Aviation Infatable Restraint (AAIR) System.		-FAA STC No SA01700LA.-AMSAFE Inc. Master Data List E208802Revision NC dated November 10, 2004 or later aproved revision.-AFM Supplement E508810 Revision IR dated November 24, 2004 or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	22/04/2005	Active	10015412
EASA.IM.A.S.01130	STERLING AVIATION TECHNOLOGIES Inc.		FAA STC SA01130SE	PA-38-112	Installation of Tomahawk Fatigue Life Extension Wing Spar Modification.FAA STC SA1130SE. Validation is in accordance with EASA CertificationDirectorate Exposition Part 2, Subpart 3 Internal Working ProcedureSupplemental Type Certification (STCP) Issue 1 adopted 27 June 2005para. 4.8 and subsequent s...		·,,FAA STC SA1130SE.·,,Sterling Aviation Installation Instructions SA38-112-500 Revision Ddated February 8 2007.·,,Sterling Aviation Technologies Inc. Drawing List SA500 Revision NCdated September 24 2002 or later approved revision.	1.,,Approval restricted to modifications carried out in accordance withSterling installations SA38-112-500 Revision D dated February 08 2007.Modifications completed to earlier installation instructions are notacceptable.2.,,This STC is approved only for the product configuration as definedin the app...	08/03/2007	Active	10042952
EASA.IM.A.S.01132	GULFSTREAM AEROSPACE SERVICES CORP.d/b/a GULFSTREAM AEROSPACE CORPORATd/b/a GULFSTREAM		FAA STC ST2137CH-T	GULFSTREAM GV-SP	Custom 14 Passenger Interior & Aircraft Completion.		Gulfstream MDL GC522046016 at latest FAA Approved Revision.Flight Manual Supplement GC52204-M005 dated July 14 2005 or later approved revision.	Limited to Gulfstream GV-SP Registration G-JCBC Serial Number 5060.	21/02/2007	Active	10015413
EASA.IM.A.S.01134	BLACKHAWK MODIFICATIONS Inc.	REV. 1	FAA SA10341SC	B. C90, E90 A. C90A	Installation of Pratt & Whitney PT6A-135A engine with:1. Hartzell propellers HC-D4N-3C/D9290(S,K) with a diameter of 93inches (4 blades) in accordance with Blackhawk Modification, Inc.Drawing No 19003-01, Rev B, dated 1st April 2004, "Installation Instructions", or late approved revision. Note: app...		AFMS No 19003-00, Rev A, dated 7th October 2004 or later approved revision	AFMS No 19003-00, Rev a, dated 7th october 2004 or later approved revision is required for the Raytheon C90, C90A or E90 airplane with Pratt & Whitney Canada PT6A-135A engines. Note that the shaft horspower is limited to 550 at 1900 RPMEach engine mount must be removed from the airplane, cleaned and...	20/04/2006	Active	10015414
EASA.IM.A.S.01136	KNH AVIATION SERVICES, Inc.		FAA STC ST09993SC	FAIRCHILD DORNIER DO 328-300	FAA STC ST09993SC; 12 Seats configuration (extended to 14 seats throught minor change, part of Avcraft CN-F 0535)Installation of interior shell, cabinetry ,seats, card tables, monitors, entertainment system, system wiring, and lavatory in accordance with AvCraft Completions Master Document List MD...		FCOM , Temp Rev No 05-11, effective for S/N 3199, AFMS Doc Nr AFMS-D03-011578, RevisionN/C, dated June 10, 2002 or later FAA appropved revision	1. This STC may be installed only in combination with Change Notice CN-F0535, -F0040,-F0125 owned by Avcraft Germany and RUAG minor Changes “In Seat Power Supply and FI Switch” and “Installation of Double Latches on drawers” .2. The water pumping system for the galley and the lavatory sink are i...	20/06/2006	Active	10015415
EASA.IM.A.S.01139	DUNCAN AVIATION, INC.		FAA STC ST00546WI	LEARJET 60	Installation of a Universal Avionics Inc. UNS-1B FMS (Dual).		-FAA STC ST00546WI.-Duncan Aviation Inc. Document List No10049800, May 27, 1997, or later FAA-approved revisions.-Duncan Aviation Inc; Document No 40173300, FAA-approved AFMS, June 13, 1997, or later FAA-approved revisions.	1. For certification basis refer to FAA TCDS A10CE.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	11/04/2005	Active	10015417
EASA.IM.A.S.0114	JET AVIATION ST. LOUIS, Inc.	REV. 1	FAA ST00696WI	CL-600-2B16	Installation of an AlliedSignal MK V Enhanced Ground Proximity System (EGPWS), with Terrain and Obstacle Databases.		Midcoast Aviation Inc., Certification Drawing list No AD980023, RevisionA, dated 01 August 1998 or later FAA approved revisionsFlight Manual Supplement Midcoast Aviation Inc., Report No 32-327M005FAA approved Airplane Flight Manual Supplement dated 24 August 2004 orlater FAA approved revisions.		14/09/2004	Active	10075347

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01140	WIPAIRE Inc.		FAA STC SA00900CH	SEE EASA APPROVED MODEL LIST	Installation of Wipaire Model 2350 Amphibian/Seaplane floats on Cessna172 Models (validation of FAA STC SA00900CH).		Installation in accordance with Wipaire Inc. MDL W-MD100 issue date 25July, 2005 or later approved revisions.	1. Installation on Cessna models 172R and 172S require aircraft fittedwith McCauley Model 1A200/WFA propeller and Textron Lycoming ModelIO-360-L2A engine rated at 180hp and 2700 rpm.2. FAA STC SA332GL is required for models 172I,K,L,M,N and P (Note: FAASTC will require EASA approval).3. NOTE NO OPER...	04/07/2005	Active	10042954
EASA.IM.A.S.01141	AVIATION TECHNICAL SERVICES, Inc.		FAA ST00988SE-D	757-200	Installation of an Interior Arrangement, Avionics & Ozone Converters.		-FAA STC No ST00988SE-D.-Goodrich Master Drawing List 2004-005 Revision A, dated May 4 2004 or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	11/04/2005	Active	10015418
EASA.IM.A.S.01142	S-TEC CORPORATION	REV. 1	FAA SA09130AC-D	PILATUS PC 6 SERIES	Installation of Meggitt Avionics S-TEC Autopilot 55/55X		Master Drawing List ST-598 P/N 92824 Rev C or later approved revisions DWG No 55603 applies for control stick modificationAirplane Flight Manual Supplement S-TEC P/N 891229S rev 2or later approved revisionsInstructions for Continued Airworthiness P/ N 81581 Rev 2 or later approved revisions	1. Limited to PC-6/B1-H2; PC-6/ B2-H2; PC-6/B2-H4 and PC-6/ B2-H4 when modified with underwing fuel tanks2. If stabilizerelectrical-trim interrupt switch S043 is installed, the optional trim wiring in accordance with detail "A" on S-TEC drawing No 99213 Rev C or later approved revisions must be insta...	10/09/2008	Active	10015419
EASA.IM.A.S.01150	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01752LA-D	GULFSTREAM GV-SP	Gulfstream Aerospace Corporation Modification FAA STC ST 01752 LA-D. Aircraft Completion & Custom Cabin Installation. Gulfstream DAS Report Number GC52000K329 Dated 03/08/05 Flight Manual Supplement ref GC 52000M012 Dated 02/08/05 or laterapproved revisions		Gulfstream DAS Report Number GC52000K329 dated 03/08/05Flight Manual Supplement ref GC 52000M012 dated 02/08/05 or later approved revisions	1. Serial 5068 only2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility withother aircraft/engine configurations shall be determined bythe installer.	08/08/2005	Active	10015420
EASA.IM.A.S.01151	DELTA ENGINEERING CORPORATION		FAA STC ST01895NY	MD-88 DC-9-87 (MD-87)	Validation of FAA STC No ST01895NY.Replacement of Dual Transponders with ACSS 7517800-10005 ATDL Transponders with ELS and Gobles G7490-58 Control Head.		-FAA STC No ST01895NY.-Delta Engineering MDL 0158-05307-2076 Rev. A dated 30 April 2004.	1. This installation does not include EHS or ADS-B functionality.The Delta Engineering MMS No 0758-05312-2076 dated 19 April 2004 is required.	22/07/2005	Active	10015421
EASA.IM.A.S.01152	S-TEC CORPORATION			CESSNA 180D, 180E, 180F CESSNA 180, 180A, 180B, 180C	Installation of S-TEC System 40/50 Single & Two Axis automatic flightguidance systems, Model ST-196-40/50		Bulletin No. 296 Revision 8 dated March 22, 1999. Master Drawing ListNo. 92232 Revision H dated March 22, 1999 or laterEASA approvedRevision (14 Volt System).S-TEC AFM SupplementP/N 89484 applicable to system 40 dated July, 191984 or later EASA approved revision and UK CAA Change Sheet 101 Issue1....	1. This STC applies to Cessna Models 180, 180A, 180B, 180C, 180D, 180E,180F (Floatplane or amphibian) & the above models when equipped with FAASTC SA1435WE (Robertson STOL) or FAA STC SA967CE (Horton STOL) and / orFAA STC SA1705WE (Internaltip tanks).2. This STC applies to Cessna Models 180, 180A, 1...	18/07/2005	Active	10042955
EASA.IM.A.S.01153	DAVIS AERO ENGINEERING, Inc.		FAA STC ST01657LA	LEARJET 60	Installation of Rockwell Collins TCAS II.		FAA STC ST01657LA. Davis Aero Engineering MDL Doc. No AG362-MDL, Rev. B, or later FAA-approved revsisions. AFMS AG362-600, Rev. IR, or later FAA-approved revisions.	1. For certification basis refer to FAA TCDS A10CE plus JAATGLs No 8 and 13.	01/04/2005	Active	10015422

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01154	TEXAS SKYWAYS, INC.		FAA STC SA09133SC	CESSNA F182-Q CESSNA F182-P CESSNA 182R CESSNA 182Q CESSNA 182P CESSNA 182N CESSNA 182M CESSNA 182L CESSNA 182K CESSNA 182J CESSNA 182H CESSNA 182G CESSNA 182F CESSNA 182E CESSNA 182D CESSNA 182C CESSNA 182B CESSNA 182A CESSNA 182	Installation of Teledyne Continental Motors IO-550-F engineand Hartzell or McCauley Propeller in acc. with Texas Skyways Spec. TS0028, Rev. 1, or later approved Revision and TS0034		FAA STC SA09133SCTexas Skyways AFM-S FS550182, Rev. 2, or later approved RevisionTexas Skyways TachOpMan TS0037, dated 27 March 1995, or later approved Revision	The approval is only valid in combination with the installation of STC EASA.A.S.01374 (Gomolzig GmbH, Germany)	07/07/2006	Active	10015423
EASA.IM.A.S.01155	TEXAS SKYWAYS, INC.		FAA STC SA10070SC	CESSNA U206G CESSNA U206F CESSNA U206E CESSNA U206D CESSNA U206C CESSNA U206B CESSNA U206A CESSNA U206 CESSNA TU206G CESSNA TU206E CESSNA TU206D CESSNA TU206C CESSNA TP206D CESSNA TP206C CESSNA TP206A CESSNA T210R CESSNA T210N CESSNA T210M CESSNA T210L CESSNA T210K CESSNA T210J CESSNA T210G CESSNA T207A CESSNA T207 CESSNA P210R CESSNA P206E CESSNA P206D CESSNA P206A CESSNA P206 CESSNA F182-Q CESSNA F182-P CESSNA A185F CESSNA A185E CESSNA 210R CESSNA 210N CESSNA 210M CESSNA 210L CESSNA 210K CESSNA 210J CESSNA 210H CESSNA 210G CESSNA 210F CESSNA 210D CESSNA 210C CESSNA 210B CESSNA 210-5 (205) CESSNA 210 CESSNA 208B, CARAVAN I CESSNA 207A CESSNA 207 CESSNA 185E CESSNA 185D CESSNA 185C CESSNA 185B CESSNA 185A CESSNA 185 CESSNA 182R	Installation of Hartzell 3-blade Propeller in acc. with Texas Skyways Doc. 5016-0000, Rev. E, or later approved Revision		FAA STC SA10070SCTexas Skyways AFM-S 5016-180, Rev. IR, or later approved Revision for Cessna 180 seriesTexas Skyways AFM-S 5016-182, Rev. IR, or later approved Revision for Cessna/ Reims 182 seriesTexas Skyways AFM-S 5016-185, Rev. IR, orlater approved Revision for Cessna 185 seriesTexas Skyways A...	The approval is only valid with latest EASA approved Noise Certificate	07/07/2006	Active	10015424

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
				CESSNA 182Q CESSNA 182P CESSNA 182N CESSNA 182M CESSNA 182L CESSNA 182K CESSNA 182J CESSNA 182H CESSNA 182G CESSNA 182F CESSNA 182E CESSNA 182D CESSNA 182B CESSNA 182A CESSNA 182 CESSNA 180K CESSNA 180J CESSNA 180H CESSNA 180F CESSNA 180E CESSNA 180D CESSNA 180C CESSNA 180B CESSNA 180A CESSNA 180						
EASA.IM.A.S.01156	TEXAS SKYWAYS, INC.		FAA STC SA09964SC	CESSNA F182-Q CESSNA F182-P CESSNA 182R CESSNA 182Q CESSNA 182P CESSNA 182N CESSNA 182M CESSNA 182L CESSNA 182K CESSNA 182J CESSNA 182H CESSNA 182G CESSNA 182F CESSNA 182E CESSNA 182D CESSNA 182C CESSNA 182B CESSNA 182A CESSNA 182 CESSNA 180K CESSNA 180J CESSNA 180H CESSNA 180G CESSNA 180F CESSNA 180E CESSNA 180D CESSNA 180C CESSNA 180B CESSNA 180A CESSNA 180	Installation of engine mount heat shields in acc. with Texas Skyways Doc. 5018-101, dated 12 Oct 2001, or later approved Revision		FAA STC SA09964SC		07/07/2006	Active	10015425
EASA.IM.A.S.01160	AVIATION FABRICATORS, Inc.		FAA ST00716WI	2. 501, 551 1. 500, 550, S550, 560	Installation of Shoulder Harness Kit		-Drawing List AF-288 of 29 August 2002 (Rev F)-Structural Report D-10314SA of 03 October 2000-Installation InstructionsD-10252 (D), D-10314 (A) and D-10368-No change in the AFM-FAA STC ST00716Wi dated 02 November 1998		22/07/2005	Active	10015427

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01161	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST02691AT	AIRBUS A310-300 AIRBUS A310-200 AIRBUS A300 MODEL B4 AIRBUS A300 MODEL B2	Installation of SafTGlo photoluminiscent floor proximity emergency escape path marking system (FPEEPMS). - Validation of FAA STC No. ST02691AT).		Master Drawing List No. L66-2 Revision D, dated 16 March 2004 or later FAA approved revision.Aircraft Flight Manual Supplement Document No. EASA L66-11, dated 25 August 2005, or later FAA approved revision.	1. The approval of this STC is limited to the identified aircraft models with interior arrangements approved in the SafTGlo MDL No.L66-2 Revision D, dated 16 MAR 2004, for Airbus A300 incorporating SafTGlo Drawings SGA300 and for A310 incorporating SafTGlo Drawings SGA310. The limitations and condit...	06/09/2005	Active	10015428
EASA.IM.A.S.01163	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST02664AT	AIRBUS A340-300 AIRBUS A340-200	Installation of SafTGlo photoluminescent floor proximity emergency escape path marking system (FPEEPMS) – Validation ofFAA STC N° ST02664AT		- Master Drawing List n° L69-2 Revision A, dated 30 January 2003, or later FAA approvedrevision.- Aircraft Flight Manual Supplement, Document N° EASA L69-11 Revision A, dated07 September 2005, or later FAA approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.2. The approvals of this STC is limited to the identified a...	16/11/2005	Active	10015429
EASA.IM.A.S.01165	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST02637AT	BOEING 717-200	Installation of SaftGlo Inc. Phtoluminescent floor proximity emergency escape path marking system (FPEEPMS)			Cabin and exit lightning levels must be measured for acceptability on each installation in accordance with STG Aerospace Report No.P51-12, Revision A dated November 13, 2002 and P51-10, Revision I.R., dated August 15, 2002 or later approved revisions	26/08/2005	Active	10015431
EASA.IM.A.S.01166	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST01641AT	BOEING 727-200 SERIES BOEING 727-100 SERIES	Installation of a phtoluminiscent Floor Proximity EmergencyEscape Path Marking System according to Diversified Aviation Services Inc FAA STC No. ST01641AT.		STG Aerospace Airplane Flight Manual Supplement Photoluminiscent Aisle Path Marking System Boeing 727-100/-200 Series, Doc No. EASAC51-11 Revision IR		21/09/2005	Active	10015432
EASA.IM.A.S.01168	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST02221AT	BOEING 757-300 BOEING 757-200	Installation of SafTGlo Inc. Phtoluminescent floor proximity emergency escape path marking system (FPEEPMS)		SafGLO MDL Report Number L21-2 Revision IR dated August 22,2000 or later approved revision-AFM Supplement SafGLO Report No L21-11 IR dated October 06, 2000	Cabin and exit lighting levels must be measured for acceptability on each installation in accordance with STG AerospaceReport No. L21-12, Revision I.R. dated September 22, 2000 an L21-10, Revision I.R., dated September 21, 2000 or later approved revisions	26/07/2005	Active	10015433
EASA.IM.A.S.01169	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST02521AT	BOEING 767-300 SERIES BOEING 767-200 SERIES	Installation of SaftGlo Inc. Phtoluminescent floor proximity emergency escape path marking system (FPEEPMS)		-SafGLO MDL Report Number M40-2 Revision C dated May 16, 2002 or later approved revision-AFM Supplement SafGLO Report No M40-11 Rev IR dated May 21, 2002	Cabin and exit lighting levels must be measured for acceptability on each installation in accordance with STG AerospaceReport No. M40-12, Revision A dated October 11, 2001 and M40-10. Revision C, dated May 6. 2002 or later approved revisions	26/07/2005	Active	10015434
EASA.IM.A.S.01170	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST02687AT	BOMBARDIER CL-600-2C10 BOMBARDIER CL-600-2B19	Installation of SaftGlo Inc. Phtoluminescent floor proximity emergency escape path marking system (FPEEPMS)		-STG Aerospace MDL Report Number M41-2 revision D dated November 3, 2004 or later aproved revision-AFM supplement No M41-11, Revision A dated June 24, 2004 or later approved revision	Cabin and exit lighting levels must be measured for acceptability on each installation in accordance with STG AerospaceReport No. M41-12, Revision A dated June 30, 2002 and M41-10, Revision I.R, dated June 5, 2003 or later approved revisions.	28/07/2005	Active	10015435

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01171	DIVERSIFIED AVIATION SERVICES INC.			DC.9-31/-32/-34	Installation of a photo luminiscent floor proximity emergency escapepath marking system.		FAA AFMS DAS Report No. J17-11IR dated 4 October 1999.Dispatch Operating Procedures DAS report No. J17-13IR dated 4 October1999, or later approved revisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	18/07/2005	Active	10042971
EASA.IM.A.S.01172	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA ST01932AT	DC-9-32, DC-9-34 DC-9-31 (NOT CERTIFIED)	Installation of a photo luminiscent floor proximity emergency escape path marking system.		- Flight Manual Supplement AFMS DAS report No. G49-11 IR, dated 7 July 1999.- Dispatch Operating Procedures DAS report No. G49-13 Rev. C dated 7 July 1999 or later approved revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer	13/02/2009	Active	10015436
EASA.IM.A.S.01173	SAF-T-GLO Inc.			DC.9-51	Installation of a photo luminiscent floor proximity emergency escapepath marking system.		Flight Manual Supplement AFMS DAS Report No. H75-11 Rev. IRdated 26July 1999. Dispatch Operating Procedures DAS ReportNo. H75-13 Rev. IRdated 4 October 1999 or later approved revisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	18/07/2005	Active	10042972
EASA.IM.A.S.01174	SAF-T-GLO Inc.			DC.9-83	Installation of a photo luminiscent floor proximity emergency escapepath marking system.		FAA Airplane Flight Manual Supplement (AFMS) DAS Report No.H95-11IR,dated 13 September 1999.Dispatch Operating Procedures DAS Report No. H95-13IR dated 13 September1999, or laterapproved revisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	18/07/2005	Active	10042973
EASA.IM.A.S.01175	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST02131AT	MD-11 DC 10-30 SERIES DC 10-30 CF SERIES DC-10-10 SERIES	Installation of SaftGlo Inc. Photo luminescent floor proximity emergency escape path marking system in accordance with FAA STC ST02131AT		STG Aerospace Revision record SG-DC10 dated 2/18/00 and report No's: K17-14 of Febr. 3, 2003, rev. I.R.; K17-12 of Jan.2, 2001, rev. B; K17-13 of Feb 3, rev. B; K17-2 of Feb. 7, 2003, rev. C; K17-10 of Feb. 3, 2003, rev. B; K17-11 of Jan.19, 2001	1. The Photoluminescent FPEEPM is only eligible for installation on aircraft model numbers with interior arrangements approved in the STG Aerospace document K17-2 Reviosn C, datedFebruary 7, 2003, incorporating STG Aerospace drawing SG-DC10 rev B ISNT DWG, datedFebruary 3, 2003.Electrically-lit doo...	15/11/2005	Active	10015437
EASA.IM.A.S.01176	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST01893AT	BOMBARDIER DHC-7-102 BOMBARDIER DHC-7-100	Installation of SaftGlo Inc. Phtoluminescent floor proximity emergency escape path marking system (FPEEPMS)		-DAS MDL Report Number G34-2 Revision A dated April 18 19990 or later approved revisions-AFM Supplement DAS Report No G34-11, dated April 26, 1999 or later approved revisions	Cabin and exit lighting levels must be measured for acceptability on each installation in accordance with DAS Report No. G34-12, Revision A dated April 16, 1999 and G34-10, Revision A, dated April 17, 1999 or later approved revisions.	28/07/2005	Active	10015438
EASA.IM.A.S.01180	AVIATION FLEET SOLUTIONS, LLC	REV 2	FAA STC ST01649SE	MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Supplemental Operating Configurations MD-80.Addition of engine and part intermix.		MDL AA 1781 (Rev. H), AFM Supplement		26/10/2007	Active	10015440
EASA.IM.A.S.01181	S-TEC CORPORATION		FAA STC SA09018AC-D	CESSNA A185F	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-596. Bulletin No.696 Revision 3dated February 2 2001 & Master Drawing List No. 92801 Revision C dated February 2 2001 or later approved revision (28 volt system). S-TEC AFM Supplement P/N 891191 & 891192 dated A...		Bulletin No 696 Revision 3 dated February 2 2001 & Master Drawing List No 92801 revision C dated February 2 2001 or later approved revision (28 volt system)S-TEC AFM Supplement P/N 891191 & 891192 dated August 25 1995 or later approved revision	Cessna Model A185F & Cessna Model A185F when equipped with STC SA1441WE (Robertson STOL) or STC SA968CE (Horton STOL) and/ or STC SA2529WE (Internal Tip Tanks)	25/07/2005	Active	10015441

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01182	S-TEC CORPORATION		FAA STC SA09195AC-D	COMMANDER 112TCA, 114, 114A COMMANDER 112, 112B, 112TC,	Installation of S-TEC System 55/55X wo Axis Automatic Flight Guidance Ssytem. Model ST-658, in accordance with FAA STC SA09195AC-D.		FAA/DAS approved Pilot's Operating Handbook and/or AirplaneFlight Manual Supplement, P/N 891326, Revision 2, dated 5-23-01 is required for:1. Commander Aircraft models 112, 112B,112TC, 112TCA, 114 and 114A.2. Commander Arcraft models 112and 112B when modified per STC SE5203NM (turbocharger/ interc...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	28/04/2005	Active	10015442
EASA.IM.A.S.01183	DELTA ENGINEERING CORPORATION		FAA STC ST01310NY	AEROSPATIALE ATR 72-212A AEROSPATIALE ATR 72-212 AEROSPATIALE ATR 72-211 AEROSPATIALE ATR 72-202 AEROSPATIALE ATR 72-201 AEROSPATIALE ATR 72-102 AEROSPATIALE ATR 72-101 AEROSPATIALE ATR 42-500 AEROSPATIALE ATR 42-320 AEROSPATIALE ATR 42-300 AEROSPATIALE ATR 42-200	Configuration 1: Installation of Delta Engineering sensors,brackets and wiring harnesses in accordance with Delta Engineering Master Drawing List 0101-04808-2030 revision F datedAugust 5, 2004Configuration 2: Installation of the SFIM Inc. Auxiliary Flight Data Acquisition Unit (AFDAU) to interface...		Delta Engineering Instructions for Continued Airworthiness documentnumber 0701-04812-2030, revision D dated June 24, 2004 for configuration1 and 2	1. Configuration 1; this approval is for structural provisions only2. Configuration1 is required for Configuration 23.This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine co...	30/05/2005	Active	10015443
EASA.IM.A.S.01185	JET AVIATION AG, BASEL		-	AIRBUS A319-115	Cabin interior outfitting		Flight Manual Supplement BCJ02507-201-01	Approval valid for S/N 2507 onlyThe aircraft is certified for private use only. It is prohibited to operate the aircraft for hire or offered for common carriage. The aircraft is aNO SMOKING aircraft. For other limitations, see flight manual supplement BCJ02507-201-01	20/12/2005	Active	10015444
EASA.IM.A.S.01186	JET AVIATION AG, BASEL		-	A320-232	Cabin Modification (Final Completion of VIP Configuration)		Flight Manual Supplement Doc. No BCJ02566-201-01	1) Modification limited to Aircraft S/N 25662) This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	21/12/2005	Active	10015445
EASA.IM.A.S.01187	JET AVIATION AG, BASEL		-	LEARJET 60 LEARJET 55C LEARJET 55B LEARJET 55 LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35 LEARJET 31A LEARJET 31	Activation of the Runway Awareness and Advisory System (RAAS).		Master Data List Doc No BLJ3134461-001FOCA approved AFM SupplementDocument No BLJ3134461-201-01 Rev IR	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	30/05/2005	Active	10015446

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01188	AVIONICS SUPPORT GROUP, Inc.		FAA ST02976AT	737-300, 737-400, 737-500	Installation of ACCS Elementary and Enhanced Surveillance capable Mode S Transponders and Flight ID capable TransponderControl Panel		FAA STC ST02976AT dated 10th November 2004ASG Master Drawing List, Ref 24640, Rev A dated 4th February 2005ASG AirplaneFlight Manual Supplement, Ref 24640-FMS, Rev IR dated 10th November 2004ASG Instruction for Continued Airworthiness, Ref 24640-CAW, Rev IR dated 27th September 2004	1. According to FAA STC No ST02976AT2. This STC is approvedonly for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shallbe determined by the installer.	25/10/2005	Active	10015447
EASA.IM.A.S.01191	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA01129AT-D	RAYTHEON 1900C	Installation and peration of a Lockheed Martin/Fairchild FDR F1000, solid State flight data Recorder installed.Master Drawing List MDL9606 Initial Revision, dated January 10, 1997or later FAA approved revision.		Master Drawing List MDL96060 Initial Revision, dated January 10, 1997 or later FAA approved revision.	1.FAA approved Airplane Flight Manual Supplement AFMS96060,dated 18 APR 1997 or later approved revision, is a requiredpart of this STC.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with ot...	31/08/2005	Active	10015448
EASA.IM.A.S.01192	GULFSTREAM AEROSPACE Corp.		FAA STC ST02883AT-D	GULFSTREAM 200	Installation of Transponder Flight ID		-Gulfstream Aerospace Corporation Index List CEB11268000, Revision NC Dated 24 June 2004, or later FAA approved revision-FAA approved Airplane Flight Manual Supplement CEB1126M000Revision NC Dated 13 July 2004 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	28/06/2005	Active	10015449
EASA.IM.A.S.01194	GENERAL AEROSPACE INC	REV. 1	FAA STC ST03042AT	BOEING 767-300 BOEING 767-200	Installation of Honeywell Aircraft Comunication Addressing & Reporting System (ACARS).		General Aerospace Master Drawing List No. GA67-ACARS-MDL Rev. B		12/06/2008	Active	10015450
EASA.IM.A.S.01195	GENERAL AEROSPACE INC		FAA STC ST03041AT	BOEING 767-300 SERIES BOEING 767-200 SERIES	Installation of a Honeywell ARINC Data Acquisition Management System		General Aerospace Master Drawing List No GA67-DFDR-MDL revison B dated May 7, 2005 or later approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	30/05/2005	Active	10015451
EASA.IM.A.S.01196	GULFSTREAM AEROSPACE CORPORATION		ST01753LA-D	GULFSTREAM GV-SP	Aircraft completion and cabin interior installationGulfstream DAS report No. GC52000K341 dated 13 SEP 2005 or later approved revisions.		Flight Manual Supplement GC52000M014 Aircraft Completion.FAA STC ST01753LA-D	This STC is limited to Gulfstream GV-SP Serial Number 5070 only.	21/09/2005	Active	10015452
EASA.IM.A.S.01198	LIFEPORT, LLC		FAA STC SA01093SE	CESSNA 525A CESSNA 525	Installation and inspection of emergency medical stretcher and base, oxygen system in accordance with FAA STC SA01093SEor later EASA approved revision.		- Approval Report, item 5;- Airplane Flight Manual Supplement EGR-689-11, Reviaion IR, dated May 31, 2002, or later approved revision.		13/02/2007	Active	10015453
EASA.IM.A.S.01199	LIFEPORT, LLC		FAA STC ST00909SE	LEARJET 45	Installation of emergency medical stretchers and bases, oxygen and electrical systems and associated Lifeport Inc. Report No. EGR-644-12 Revision IR dated November 6 2000 & MasterDrawing List EGR-644-00 revision R dated 25 April 2001 or later approved revision		Lifeport Inc. Report No. EGR-644-12 Revision IR dated November 6 2000 & Master Drawing List EGR-644-00 revision U dated7 January 2005 or later EASA approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	21/06/2005	Active	10015454

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01201	S-TEC CORPORATION		FAA STC SA09283AC-D	NAVION H NAVION G NAVION B NAVION A (L-17B)	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance System Model ST-724-20/30 in accordance with FAA STC SA09283AC-D		-FAA/DAS approved Supplemental Flight Manual P/N 891535, Rev 1 for Navion models A, B, D, E, F, G and H when modified by alo Alto Airport Inc or Symon's Engineering Horizontal Stabilizer Angle of Incidence Change with or without tip tanks and the above models when modifid by 285 H.P. engine conversi...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	30/05/2005	Active	10015455
EASA.IM.A.S.01202	GULFSTREAM AEROSPACE Corp.		FAA STC ST10299SC-D	GULFSTREAM 200	Installation of ICG-200 SATCOM System		-Index List GA211038000, Revision B dated 15 February 2005 or later FAA approved revision-FAA approved Airplane Flight Manual Suppplement doc. Number GA21103M000 Rev None dated 16February 2005 or later FAA approved revision	1. Instructions for continued Airworthiness GA24103A000 Revision N/C dated 31 January 2005 or later FAA approved revision is required2. This STC is approved only for the product configuration as defined in the approved design data referredto in the paragraph "Description". Compatibility with other...	28/06/2005	Active	10015456
EASA.IM.A.S.01203	GULFSTREAM AEROSPACE Corp.		FAA STC ST10297SC-D	GULFSTREAM 200	Installation of Executive Cabin Interior		-Gulfstream Aerospace Index List GA220008103, Rev A dated 14 February 2005 or later FAA approved revision-FAA approved Flight Manual Supplement GA21468M103, Rev None dated 14 February 2005 or later FAA approved revision	1. This STC is limited to the installation made in Gulfstream Aerospace LP(Istrael Aircraft Industries, LTD) model Gulfstream 200 serial number 103 only.2. This STC does not permit manufacturing of part for multiple installation3. This STCis approved only for the product configuration as defined in...	28/06/2005	Active	10015457
EASA.IM.A.S.01204	GULFSTREAM AEROSPACE Corp.		FAA STC ST10298SC-D	ROBIN DR 400 RP, DR 120D, DR 140B, DR 180R, DR 200R	Installation of WX-1000E Stormoscope System		-Gulfstream Index List GA212258000 Revision D dated 17 February 2005 or later FAA approved revision-FAA approved FlightManual Supplement GA 21225M000 Rev None dated 17 February 2005 or later FAA approved revision	1. This installation is eligible for airplanes S/N 052 and subsequent with Collins Pro Line 4, version 6.1 avionics system2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/en...	28/06/2005	Active	10015458
EASA.IM.A.S.01205	GULFSTREAM AEROSPACE Corp.		FAA STC ST10050SC-D	GULFSTREAM 200	Installation of Honeywell Laseref V IRS		-Index List GA211138000, Revision B dated 18 August 2004 orlater FAA approved revision -FAA approved Airplane Flight Manual Suppplement doc. Number GA21113M000 Rev None dated 18 August 2004 or later FAA approved revision	1. Compliance with FAA Special Condition 25-263-SC and ACG/ EASA CRI F-06 for HIRF has been demonstrated.2. The aircraftmust be equipped with Rockwell Collins FMS-6100 Flight Management Systems installed in accordance with IAI MOD Nos.7219and 100233. This STC is approved only for the product config...	28/06/2005	Active	10015459
EASA.IM.A.S.01206	GULFSTREAM AEROSPACE Corp.		FAA STC ST10020SC-D	GULFSTREAM 200	Installation of DeCrane/ERDA Cabin Double Seats		-Gulfstream Aerospace Index list GA2220880002, Rev D dated 17 May 2003 or later FAA approved revision-FAA approved Flight Manual Supplement GA22208M002 Rev None dated 17 May 2003 or later FAA approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	28/06/2005	Active	10015460

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01207	MCFARLANE AVIATION, Inc.		FAA STC SA01074WI	CESSNA 207, 210 CESSNA 180, 182, 185, 188, 206 CESSNA 150, 152, 170, 172, 175	Installation of McFarlane Aviation FlapRoller Assembly Service Kit MCSK100 under FAA STC SA01074WI		McFarlane Aviation Drawings 1057 Rev Original & 1058 Rev Original FAA Approved April 22, 2002 or later FAA Approved Revision	1. Cessna Service Bulletin SEB95-3 must be complied with before this STC can be installed2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be dete...	30/05/2005	Active	10015461
EASA.IM.A.S.01209	HONEYWELL INTERNATIONAL INC.		FAA STC ST01298AT	BOEING 767-300 SERIES BOEING 767-200 SERIES	Installation of Flight Data Aquistion & Management System (FDAMS) with Mark II Aircraft Communication & Reporting System (ACARS)		Honeywell International Master Drawing List 699-50117 Revision K dated August 6 2001 or later approved revision.	1. Pitch & Roll Attitude is sampled one per second.2. Pneumatic power is sampled once every 4 seconds.	30/06/2006	Active	10015462
EASA.IM.A.S.01210	JET AVIATION AG, BASEL		-	BOMBARDIER CL-600-1A11 (CL-600	Flight Management System (FMS) Upgrade & Terrain Awareness Warning System (TAWS) Installation		Jet Aviation Master Data List Document Number BOHET004-001 Rev B dated July 14 2005 or later approved revisionJet Aviaiton AFM Supplement BOHET004-201-01 Rev B & BOHET004-201-04 Rev B or later approved revisions	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/07/2005	Active	10015463
EASA.IM.A.S.01213	ROCKWELL COLLINS, Inc.			BEECHCRAFT B300, B300C	Installation of dual Collins TDR-94/94D Mode S Transponder orinstallation of single Collins TDR-94/94D Mode S Transponder and singleTDR-90 Mode C Transponder on Beechcraft B300 & B300C		Dual TDR-94/94D: Collins Drawing Index 992-1972-001 and later approvedrevisions Single TDR-94/94D and Single TDR-90: Collins Drawing Index992-1973-001 and later approved revisions	1. Any bottom doubler-antenna is required pre-modification2. If the holder agrees to permit another person to use this certificateto alter the product, the holder shall give the other person writtenevidence of that permission.3. This STC is approved only for the product configuration as defined inth...	30/05/2005	Active	10042974
EASA.IM.A.S.01214	ROCKWELL COLLINS, Inc.d/b/a AIR TRANSPORT SYSTEMS		SA1930CE-D	BEECH B300C BEECH B300	Installation of Collins TCAS-94 TCAS II System.		Collins Drawing Index 992-1974-001, no revision, dated 16 October 1991.Airplane Flight Manual Supplements and Maintenance Manual Supplements as follows in annex TableApplicability AFM Supplement Maintenance Manual SupplementTCAS-94 (TCAS II) and Collins TVI-920D TA/RA/VSI Indicators - Drawingd...	1. Installation of STC SA1929CE-D, mode S transponder (single or dual) is a prerequisite to this STC. 2.This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations s...	20/08/2005	Active	10015464
EASA.IM.A.S.01217	DASSAULT FALCON JET - WILMINGTON COd/b/a DASSAULT AIRCRAFT SERVICES		FAA STC ST01156NY-D	MYSTERE FALCON 900	Validation of FAA STC ST01156NY-D: Installation of a Honeywell Mark V Enhanced Ground Proximity Warning System (EGPWS) upgrade iaw Master Drawing List 027670321, Rev. - dtd Jan 26, 2001.		Associated to:FAA STC ST01156NY-D- AFM Supplement 027670302, Rev. - FAA-approved Feb. 12, 2001.- MM Supplement (Continued Airworthiness Instructions) 027670315 Rev - dtd Feb. 12, 2002.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	31/05/2005	Active	10015465
EASA.IM.A.S.01218	DASSAULT FALCON JET - WILMINGTON COd/b/a DASSAULT AIRCRAFT SERVICES		FAA STC ST01157NY-D	MYSTERE FALCON 900	Validation of FAA STC No ST01157NY-D: Installation of a Honeywell Electronic Flight Instrument System (EFIS) EDZ-820 Software Upgrade iaw Master Drawing List 027670320, Rev. - dtd. Jan. 26, 2001.		Associated to:FAA STC ST01157NY-D.-AFM supplement 027670324, Rev. - FAA-approved Feb. 12, 2001.- MM Supplement 027670332 Rev.-, dtd Feb. 12, 2001.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	31/05/2005	Active	10015466
EASA.IM.A.S.01219	DASSAULT FALCON JET - WILMINGTON COd/b/a DASSAULT AIRCRAFT SERVICES		FAA STC ST01775NY-D	MYSTERE FALCON 900	Validation of FAA STC No ST01775-NY-D: Update of Dual Rockwell Collins TCR-94 Transponder for Elementary Surveillance iaw Master Drawing List 126980303, Rev.- dtd. Oct. 15, 2004.		Associated to:FAA STC ST01775-NY-D.-AFM supplement 126980302, Rev. -FAA-approved Oct. 18, 2004.-MM Supplement (Cont. Airw. Instructions) 126980307, Rev. - Dtd. Oct. 15, 2004.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	31/05/2005	Active	10015467

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01220	BOMBARDIER AEROSPACE		TCCA C-LSA05-103/D	BD-700-1A10	Cabin Interior Completion.		Doc. Limited Supplemental Type Certificate by TCCA No. C-LSA05-103/DFMS: G-FM25000126 N/CALI: G-TM05100065 N/C, or later approved revisions	1. This STC is limited to Serial Number 9146.2. This STC isapproved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	14/06/2005	Active	10042975
EASA.IM.A.S.01221	F. ATLEE DODGE AIRCRAFT SERVICESLLC		FAA STC SA02115AK	PIPER PA-18S-150 PIPER PA-18AS-150 PIPER PA-18A-150 PIPER PA-18-150 PIPER PA-14 PIPER PA-12S PIPER PA-12	Fabrication and installation of F.Atlee Dodge 30.5 gallon wing fuel tank sight gages		F.Atlee Dodge Master Data List No. 3286MDL Revision A, dated 16 January 2004, or later approved Revisions.FAA STC SA02115AK dated 9 June 1998, revised on 20 January 2004. 3286IM - Installation and Calibration Procedures	1. Any Piper aircraft incorporating this change must be equipped with F. Atlee Dodge 30.5 gallon wing fuel tanks in accordance withFAA STC SA649AL, SA00092SE, or SA5781NM.2.This STC is approved only for the product configuration as definedin the approved design data referred to in the paragraph "De...	09/06/2005	Active	10015468
EASA.IM.A.S.01222	CASCADE AVIATION SERVICES INC.		SA01513SE	BAE JETSTREAM 3201 SERIES	Installation of Sandel Terrain Awareness Warning System (TAWS)		FAA STC SA01513SEMDL: 04CAS328-MDL. Rev DAFM: 04CAS328-D80.Rev C	Limitations as per Flight Manual	09/02/2007	Active	10015469
EASA.IM.A.S.01223	GENERAL AEROSPACE INC		FAA STC ST03002AT	BOEING 767-300 BOEING 767-200	Installation of a Honeywell Enhanced Ground Proximity Warning System.		General Aerospace Master Drawing List No. GA672-EGPWS-MDL Revision B dated May 24, 2005 or later EASA approved Revisions.General Aerospace AFM Supplement GA67-EGPWS-AFMS01 dated December 10, 2004 or later EASA approved revisions.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	14/06/2005	Active	10015470
EASA.IM.A.S.01224	BEECHCRAFT CORPORATION	REV. 3	FAA ST10385SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of a Rockwell Collins CMS-1 Cabin Management System.		1. In accordance with Master Drawing List 800-512 Revision AB, or later approved revision;2. Flight Manual Supplement 800-318 Revision R6 or later approved revision;3. Maintenance Manual Addenda 33-20-10, 33-20-15, 23-30-02.	1. This modification requires installation of STC ST10369SC-D, Installation of an Emergency Light System;	21/05/2008	Active	10015472
EASA.IM.A.S.01225	BEECHCRAFT CORPORATION	REV. 3	FAA STC ST10369SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of an Emergency Light System.		1. In accordance with :Master Drawing List 800-513 Revision L or later approved revision;2. Flight Manual Supplement 800-317 Revision R5 or later approved revision;3. Maintenance Manual Addenda 33-50-05.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	21/05/2008	Active	10015473
EASA.IM.A.S.01226	TRANSAIRCO S.A.		-	MYSTERE FALCON 50	Replacement of existing HONEYWELL MK II GPWS and COLLINS MFD-85 with a UNIVERSAL Terrain Awareness and Warning system (TAWS) and a UNIVERSALMFD-640		Swiss FOCA AFMS UNIVERSAL Terrain Awareness and Warning System and MFD-640 Multi-Function Display TSA F50-31.80.05AFMS dated 23.03.2005 or later approved version.Swiss FOCA Instructions for Continued Airworhtiness (ICA) TSA F50-31.80.05MMSdated 23.03.2005 or later approved version.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.2. Limited to Falcon 50, S/N 159, HB-ISD	19/08/2005	Active	10015474

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01228	GENERAL AEROSPACE INC		FAA STC ST00115AT	BOEING 767-300 BOEING 767-200	Installation of Dual Mode S Transponders & Honeywell Traffic Alert & Collision Avoidance System II - FAA STC ST00115AT		General Aerospace Inc Engineering Reports GA-34-25 Rev B dated 5 August 1993 and GA-GE52/0704/ER Rev B dated 24 May 2005 and MasterDrawing List GA-34-1023 Rev C dated 24 May 2005,or later EASA approved revisions.General Aerospace Inc. AFMSupplements G A 165AFM Rev B dated 11 November 2004 and GA16...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	14/05/2005	Active	10015475
EASA.IM.A.S.01229	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST01532SE	B747-400	Cabin Interior Reconfiguration		Heath Tecna Inc documents for Project P861 & associated Master Drawing List HPD-DL-93 Rev A dated April 15, 2005 or later FAA approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	30/05/2005	Active	10015476
EASA.IM.A.S.01231	BOMBARDIER INC.		C-LSA05-024/ D	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	Installation of Thales Integrated Electronic Standby Instruments for BD700-1A10 Global Express and BD700-1A11 Global 5000Validation of imported TCC STC: SA04-118		AFM Supplement G-FM34004001 Rev B or later TCCA approved rev.	1. ref. G-FM34004001 Rev B2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	08/08/2005	Active	10015477
EASA.IM.A.S.01232	S-TEC CORPORATION	REV. 1	FAA STC SA5112SW-D	PIPER PA-39 PIPER PA-30	Installation of S-TEC System 60 Two Axis Automatic Flight Guidance System Model ST-127. FAA STC SA5112SW-D		Master Drawing List No. 92139 Rev. G dated 06-01-97.Airplane Flight Manual Supplement PN 89157 Rev. 3 dated 23-01-97 orlater approved revisions.	1. This STC is also eligible on the concerned model when modified per STC SA727WE.2. This STC is approved only for the product configuration as defined in the approved design datareferred to in the paragraph "Description". Compatibility with other aircraft configurations shall be determined by the...	09/09/2008	Active	10015478
EASA.IM.A.S.01233	STRUCTURAL INTEGRITY ENGINEERING,P. C., INC.		SA6073NM	BEECH C99 BEECH B99 BEECH 99A BEECH 99	Structural Life Extension of Wing Spars according to FAA STC SA6073NM as amended on 30 December 1993.		FAA Approved Airplane Flight Manual Supplements:Beechcraft C99 with outboard wing main spar assembly (P/N 99-110045) and Centre Section Lower Main Spar Cap (P/N 109-120016-5). Report SIE-12-601Beechcraft 99, 99A and B99 with Kit Nos. 99-4023-1S or 99-4023-3S installed. Report SIE-12-601Instructio...	According to FAA STC SA6073NM and as further defined below.Compliance with the Airworthiness Limitations contained in the above referenced documents extends the existing 20,000 flight hour Beech fatigue life limits for wing spars of Beechcraft 99, 99A, B99 with Kit Nos. 99-4023-1S or 99-4023-3S inst...	02/01/2006	Active	10015479
EASA.IM.A.S.01238	ONBOARD SYSTEMS INTERNATIONAL		FAA STC ST10395SC	MD-11	EASA Validation of FAA STC ST10395SC on “Installation of two non-taxi, take-off and landing (TT7L) courier seats" and associated Airplane Flight Manual Supplement		FAA STC ST10395SC dated 1 April 2005Aerolite Master Document List Ref MDL-407, Revision C, 31 March 2005Airplane FlightManual Supplemnt Ref FMS-411, Revision IR, 1 April 2005	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	31/05/2005	Active	10015480
EASA.IM.A.S.01240	L3 AVIATION PRODUCTS, INC		FAA ST01837AT	757-200	Additional Parameters for Flight Recording SystemsAss.:Flight System Report 98-10-24 Revision C dated December 2004 or later approved revision		Flight Systems Report 98-10-24 Revision C dated December 022004 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	29/11/2005	Active	10015481

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01241	AVCRAFT AEROSPACE GMBH		FAA STC ST09465AC	DORNIER 328-100	Modification of the cabin floor to be the same level through out thecabin, according to FAA STC No ST09465AC, reissued 18 April 2005		-Fairchild Aircraft Report R1530, Revision D dated 20 April1999-FAA STC ST09465AC, reissued 18 April 2005	1. According to the application as forwarded by FAA letter dated 27April 2005, the approval is limited to te aircraft S/N 30952. Furthermore the limitations as referenced in FAA STC ST09465AC,reissued 18 April 2005, apply3. This STC is approved only for the product configuration as defined inthe app...	15/08/2005	Active	10042976
EASA.IM.A.S.01242	KNH AVIATION SERVICES, Inc.		FAA STC ST09468AC	DORNIER D328-100	installation of a corporate/executive interior		-Fairchild Aircraft Engineering Change Package (ECP) 3000, Revision AN dated 26/08/1999-FAA STC ST09468AC, reissued 18 April 2005	1. According to the application as forwarded by FAA letter dated 27 April 2005 and FAA STC ST09468AC, the approval is limited to the aircraft S/N 30952. Furthermore this installation has to be performed in combination with the installationof FAA STC ST09465AC and the limitations as referenced in FA...	15/08/2005	Active	10015482
EASA.IM.A.S.01243	DEVORE AVIATION CORPORATION OFAMERICA		FAA STC ST09191AC	BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200C BOEING 737-200	InInstallation of DeVore Wing Forward Position Light Assembly according to FAA STC ST09191AC		FAA STC No ST09191AC, Date reissued 5 May 2000DeVore TopDrawing No 73700002, Rev E dated 20th August 2003	1. According to Limitations Section of FAA STC ST09191AC2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	25/10/2005	Active	10015483
EASA.IM.A.S.01244	FLIGHT ENVIRONMENTS INC		FAA STC SA01318LA	BEECH 390	Installation of thermal/accoustic insulation kit		-FAA STC No SA01318LA-MM-Supplement 0219.ICA, Rev B or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	26/07/2005	Active	10015484
EASA.IM.A.S.01245	HARTZELL SERVICE CENTER		FAA STC SA02181AK	CESSNA 208, CESSNA 208B	Installation of a Hartzell HC-B3TN-3AF (Y)/T10890CN(K)-2 three bladed propeller and D-4897(P) assembly on the type Cessna 208, 208A and 208B in accordance with the application dated 22 April 2005.FAA STC: SA02181AK		Data package containing the following documents, and additional supporting data:1.Noise test on SE-LZY date April 22th 20062.Noise certificate applied by the Swedish CAA for the SE-LZY, date May 3th 20063.FAR Part 36 Noise Analysis by AeroTwin, Inc. report N. AT00-03-NR4.Structural Analysis by Aero...	--	07/08/2006	Active	10015485
EASA.IM.A.S.01246	JET AVIATION AG, BASEL			B737-700	The installed CTT Zonal Comfort System - CAIR System consists of:Zonal Dryer - (behind aft cargo compartment) Humidifier1 (FWD) - (LH Air Conditioning Mixing Bay)Humidifier 2 (AFT) - (RH Air Conditioning Mixing Bay)Humidifier Control Box -(Center Rack fwd Cargo Compartment)Control Panel - (IFE Cabi...		As per Master Data list BADAS004-001	1. This STC in only valid for Serial Number 298582. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	14/07/2005	Active	10042977
EASA.IM.A.S.01247	LEARJET Inc.		FAA STC ST01720LA-D	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35 LEARJET 31	Dual Honeywell MST-67A Diversity Transponders for Elementary & Enhanced Surveillance		Master Document List BAS35010075 revision F dated April 6, 2005 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	26/07/2005	Active	10015486

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01248	GULFSTREAM SERVICES CORPORATION		FAA STC ST03048AT-D	GULFSTREAM GV-SP	Aircraft completion and installation of a custom cabin interior		In accordance with the FAA STC ST03048AT-D adn Gulfstream Aerospace Corporation Index List No GC520008457 Rev C dated 27 April 2005or later FAA approve revisions.	GV-SP Aircraft Serial Number 5057 Only.1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	01/07/2005	Active	10015487
EASA.IM.A.S.01249	DUNCAN AVIATION, INC.		FAA STC ST00452WI	CESSNA 650 CITATION VII CESSNA 650 CITATION IV CESSNA 650 CITATION III	Installation of the AlliedSignal CAS 67A TCAS II System		Duncan Aviation, Inc., Document List No 10047000, Revision A, dated May 20 1996Duncan Aviaiton, Inc., Document List No 40160000, FAA approved Airplane Flight Manual Supplement, dated May 31, 1996 Revision A, dated May 20, 1996orDocument No40165900, FAA approved AFMS dated February 6, 1997 (Advisori...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	13/03/2006	Active	10015488
EASA.IM.A.S.01251	DECA AVIATION ENGINEERING Ltd.		-	A321-211, SN 675	Interior reconfiguration 20J/152 Y seating arrangement			1. This STC is limited to A321 MSN 675.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	18/07/2005	Active	10015489
EASA.IM.A.S.01252	ASSOCIATED AIR CENTER, L.P.		FAA ST10474SC	A319-133	Installation of an Executive Style Interioracc.: MDL 2300000091 Rev. D		AFM Supplement: 2300021090 Rev. IR or later EASA approved/ accepted revisionsAMM Supplement/Airworthiness Limitations/ICA 2300050090	1) Ref.: 2300021090 Rev. IR2) Limited to S/N 2192Note: The airplane is limited to private use only unless the cabin door is rendered inoperable.	21/11/2005	Active	10015490
EASA.IM.A.S.01253	HONEYWELL INTERNATIONAL INC.		FAA STC ST00961AT	BOEING 757-200 SERIES	Installation of Flight Data Acquisition and Management System (FDAMS), FAA STC ST00961AT.		Honeywell International Inc. Master Drawing List for the Installation of the Honeywell FDAMS in the Boeing 757-200 Series Aircraft,document number 699-50109, Revision K or later FAA approved revision.		29/06/2005	Active	10015491
EASA.IM.A.S.01254	DECA AVIATION ENGINEERING Ltd.		TCCA STC O-LSA04-008/D	A320-232	Passenger Seat Cushion Assembly Replacement on B/E Aerospace, seat typ: D3111F11xx-01 series		Section 1.0 of DECA Modification Summary No. MS03186, revision 1, dated January 27, 2004 or later EASA-approved revision	1. This STC is limited to the A320 MSN 496.	18/10/2005	Active	10015492
EASA.IM.A.S.01255	DECA AVIATION ENGINEERING Ltd.		TCCA STC O-LSA05-018/D	A320-232	Reconfiguration of existing 180 passenger all economy seating arrangement		DECA Aviation Engineering Modification Summary MS05017, Revision 1, dated January 20, 2005 or later EASA approved revision	1. This STC is limited to the A320 MSN 496.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	18/10/2005	Active	10015493
EASA.IM.A.S.01256	DECA AVIATION ENGINEERING Ltd.		TCCA STC O-LSA02-327/D	A320-214, A320-231, A320-232 A319-112, A320-211, A320-212,	Flight Warning Computer Altitude Callout Reconfiguration		Avionics Design Services Ltd. Engineering Order EO02001-1, Revision 7, dated October 14, 2004 or later EASA approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	18/10/2005	Active	10015494

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01257	TIMCO AVIATION SERVICES INC.	REV. 1	FAA STC ST03068AT-D	BOEING 767-300	Cabin Standardization in accordance with TIMCO Master Data List 03T012L001, revision D, dated November 30th, 2006, or later FAA approved revision.			This approval should not be extended to other aircraft of this model on which other previoulsy approved modifications are incorporated unless it is determined by the installer that the interrelationship between this change and any of thoseother previously approved modifications will produce no adve...	01/12/2006	Active	10015495
EASA.IM.A.S.01258	JAMCO AMERICA, INC.		FAA STC ST01121SE	BOEING 767-400ER BOEING 767-300 BOEING 767-200	Installation of a new security flight deck door		JAMCO America America Inc. Master Drawing List IA-082DAL MDL Revision G dated March 18 2003 or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	21/06/2005	Active	10015496
EASA.IM.A.S.01259	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02796AT-D	GV-SP	Gulfstream Aerospace Corporation Modification FAA STC ST 02796AT-D.Installation of wireless LAN system.		Gulfstream DAS Report Number GC51303K007 dated 26/07/05.Flight Manual Supplement ref GC 5I 303M002 dated 06/06/05 - 5O3config &GC51303M003 dated 06/06/05 for - 505 config, or later approvedrevisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	09/08/2005	Active	10042978
EASA.IM.A.S.01260	BOMBARDIER AEROSPACE	REV. 1	TCCA C-LSA05-294/D	CL-600-2B16	Aircraft Completion 9 Passenger Interior Configuration. (ASN 5595)		Aero Consulting Services Modification Data Summary E262000 Revision N/C or later approved revision.Aero Consulting Services AFM Supplement E262070 Revision N/C or later approved revision.	Restricted to Aircraft Serial Number 5595	04/04/2006	Active	10015497
EASA.IM.A.S.01261	BOMBARDIER INC.		C-LSA05-298/ D	BOMBARDIER CL-600-2B16 (CL-604	Aircraft Completion 11 Passenger Interior Configuration		-Aero Consulting Services Modification Data Summary E478000revision N/C or later approved revision-Aero Consulting Services AFM Supplement E478090 revision N/C or later approved revision	Valid only for ASN 5596 Registration OY-SGM	07/09/2005	Active	10015498
EASA.IM.A.S.01262	BOMBARDIER INC.		TCCA STC C-LSA05-321/D	BOMBARDIER CL-600-2B16 (CL-604	Aircraft Completion 9 Passenger Interior Configuration		Aero Consulting Services Ltd. Modification Data Summary E264000 Revision N/C or later approved revision.Aero ConsultingServices Ltd. AFM Supplement E264090 Revision N/C or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	15/11/2005	Active	10015499
EASA.IM.A.S.01263	BOMBARDIER INC.		C-LSA06-022/ D	BOMBARDIER CL-600-2B16 (CL-604	Aircraft Completion, 12 Passenger Interior Configuration		Aero Consulting Ltd Modification Data Summary E267000 Revision N/C or later approved revision.Aero Consulting Services Ltd AFM Supplement E267090 Revision N/C or later approved revision.	Restricted to ASN 5602	20/01/2006	Active	10015500
EASA.IM.A.S.01264	BOMBARDIER INC.			BOMBARDIER BD-100-1A10 (CHALLE	Installation of an Executive interior on aircraft 20047 in accordance with MDL E449000		AFM Supplement E449090	1. This STC is limited to SN 20047.2. Certification Basis: an equivalent Safety Finding has been granted in CRI D-8 forEmergency exit Marker and Locator Signes.A deviation form paragraph 25.785(B) has been granted for personal injury criteria of dynamic testing of side facing single occupancy seats...	07/11/2005	Active	10015501

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01265	BOMBARDIER INC.	REV 1	TCCA C-LSA06-051/D	BOMBARDIER BD-100-1A10 (CHALLE	Aircraft completion, 9 passengers interior configuration inaccordance with Aero Consulting Services Ltd. Modification Data SummaryE840000 Revision N/C		AFM Supplement E840090 rev N/C	1. This STC is limited to SN 200942. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	02/08/2006	Active	10015502
EASA.IM.A.S.01266	DELASTEK AERONAUTIQUE INC.		TCCA STC SA04-116 ISSUE 1	BOMBARDIER CL-600-2B19 (SERIES	Installation of Delastek Bleed Lead Monitoring System p/n DK-329-001.		Transport Canada STC SA04-116 Issue 1 dated November 2004 or later approved revision.Delastek Inc. Master Document ListMDL-DK-329-001 Revision 1 dated 25 October 2004 or later approved revision.	For s/n 7003 through 7212 Bombardier Service Bulletin 601R-30-022 Part C must be integrated prior to the installation.	23/07/2007	Active	10015503
EASA.IM.A.S.01267	ELECTRONIC CABLE SPECIALISTS, Inc.		ST01818CH	DC-9-87 (MD-87), -88, MD90-30 DC-9-83, DC-9-82 (MD-82) DC-9-81 (MD-81) DC-9-51 DC-9-32, -33F, -34, -34F, -41 DC-9-21	Installation of a Honeywell Enhanced Ground Proximity System		Electronic Cable Specialist Master Data List ECS-200489 Rev. AB dated 4 May 2005.Airplane Flight Manual Supplement as listed in Appendix A of Electronic Cable Specialists Master Data List ECS-200489 Rev. AB, limited to the models listed inthe section "applicability" of this document.	None	21/04/2006	Active	10015504
EASA.IM.A.S.01268	DUNCAN AVIATION, INC.		ST00315WI	LEARJET 60	Installation of Collins TCAS-94 i.a.w. Dok List 10045000		AFM 40150000		07/02/2007	Active	10015505
EASA.IM.A.S.0135	AIR MEDIC L.L.C.	REV. 1	FAA STC SA7076NM	A330/-313/-541/-642 A330-211/-311/-212/-312	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'AP', dated April 11, 200.3 (orlater EASA approved Revisions).			1. This SIC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/ engineconfiguration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrev...	16/09/2004	Active	10061354
EASA.IM.A.S.0136	AIR MEDIC L.L.C.		FAA STC SA7076NM	777-200	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref.: AM-2001, Revision 'AE', dated November 4, 1996 (orlater EASA approved Revisions).			1 This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	16/09/2004	Active	10061365
EASA.IM.A.S.0137	AIR MEDIC L.L.C.		FAA STC SA7076NM	737-900 737-600, 737-700, 737-800	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-200l, Revision 'AN', dated April 15, 2002 (or laterEASA approved Revisions).			1 This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	16/09/2004	Active	10061361

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.0138	AIR MEDIC L.L.C.		FAA STC SA7076NM	777-300	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'AF', dated November 4, 1998 (orlater EASA approved Revisions).			1 This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	16/09/2004	Active	10061366
EASA.IM.A.S.01384	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA4899SW	BOMBARDIER CL-600-2B16	Installation of Wulfsberg Flitefone IV/VI Communication System		-Arkansas Modification Center Inc Drawing List No 600-028 rev D2 dated October 9 1990 or later approved revision-AFM Supplement dated January 26 1983 or January 25 1988 or later approved revision for Flitefone IV or AFMS dated September 151990 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/07/2005	Active	10015506
EASA.IM.A.S.01385	RAYTHEON AIRCRAFT SERVICES, INC.		SA5953SW	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	FAA STC SA5953SW. Installation of a nose gear door ground release mechanism		Arkansas Modification Center Inc Drawing List No 600-076 rev F dated July 22 1988 or later approved revision		25/07/2005	Active	10015507
EASA.IM.A.S.01386	RAYTHEON AIRCRAFT SERVICES, INC.		SA7457SW	BOMBARDIER CL-600-2B16	FAA STC SA7457SW. Installation of Sperry LSZ-850 Lightning Sensor System		-Arkansas Modification Center Inc Drawing List No 600-074 rev A dated September 15 1988 or later approved revision-AFM Supplement dated July 22 1988 is required		25/07/2005	Active	10015508
EASA.IM.A.S.01387	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7583SW	BOMBARDIER CL-600-2B16	Installation of Sperry Primus 870 Weather Radar System		-Arkansas Modification Center Inc Drawing List No 600-073 dated March 20 1989 rev A dated April 12 1989 or later approved revison-AFM Supplement dated April 14 1989 or later approved revsion		25/07/2005	Active	10015509
EASA.IM.A.S.01388	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7871SW	BOMBARDIER CL-600-2B16	FAA STC SA7871SW. Installation of air driven generator inspection window		Arkansas Modification Center Inc Drawing List No 600-102 rev A dated August 12 1990 or later approved revision		25/07/2005	Active	10015510
EASA.IM.A.S.01389	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7878SW	BOMBARDIER CL-600-2B16	Installation of a DPI Labs 1800 Membrane Switch Control System		Arkansas Modification Center Inc Drawing List No 600-093 rev A3 dated September 12 1990 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/07/2005	Active	10015511
EASA.IM.A.S.0139	AIR MEDIC L.L.C.		FAA STC SA7076NM	ATR 72-202/-211/-212/-212A ATR 72-101/-201/-102 ATR 42-200/-300/-320/-500	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List REF.: AM-2001, Revision "AN", dated April 15, 2002 (orlater EASA approved Revisions).			1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with otheraircraft/ engineconfiguration shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orre...	16/09/2004	Active	10043007
EASA.IM.A.S.01390	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7881SW	BOMBARDIER CL-600-2B16	FAA STC SA7881SW. Installation of Sensor S67-1572 Global Positioning Antenna		Arkansas Modification Center Inc Drawing List No 600-105 rev A dated August 30 1990 or later approved revision		25/07/2005	Active	10015512

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01391	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7880SW	BOMBARDIER CL-600-2B16	Installation of an alternate location for the refuel panel		Arkansas Modification Center Inc Drawing List No 600-101 rev A2 dated September 07 1990 or later approved revision		25/07/2005	Active	10015513
EASA.IM.A.S.01392	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7873SW	BOMBARDIER CL-600-2B16	FAA STC SA7873SW. Installation of a cockpit Overhead Panel Extension		Arkansas Modification Center Inc Drawing List No 600-099 rev A1 dated August 30 1990 or later approved revision		25/07/2005	Active	10015514
EASA.IM.A.S.01393	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7872SW	BOMBARDIER CL-600-2B16	FAA STC SA7872SW. Installation of a cockpit Center PedestalExtension		Arkansas Modification Center Inc Drawing List No 600-100 rev A1 dated August 31 1990 or later approved revision		25/07/2005	Active	10015515
EASA.IM.A.S.01394	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7869SW	BOMBARDIER CL-600-2B16	FAA STC SA7869SW. Installation of access door		Arkansas Modification Center Inc Drawing List No 600-104 rev A dated August 6 1990 or later approved revision		25/07/2005	Active	10015516
EASA.IM.A.S.01395	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7870SW	BOMBARDIER CL-600-2B16	FAA STC SA7870SW. Installation of a Rosen Sun Visor System		Arkansas Modification Center Inc Drawing List No 600-103 rev A dated August 12 1990 or later approved revision		25/07/2005	Active	10015517
EASA.IM.A.S.01396	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7879SW	BOMBARDIER CL-600-2B16	Installation of a cabin emergency lighting system		Arkansas Modification Center Inc Drawing List No 600-097 rev A2 dated September 10 1990 or later approved revision		25/07/2005	Active	10015518
EASA.IM.A.S.01397	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7886SW	BOMBARDIER CL-600-2B16	Installation of a cabin oxygen system		Arkansas Modification Center Inc Drawing List No. 600-098 Revision A-3 dated September 11 1990 or later approved revision.		11/08/2005	Active	10015519
EASA.IM.A.S.01398	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7887SW	BOMBARDIER CL-600-2B16	Installation of a Cabin Water System		Arkansas Modification Center Inc Drawing List No 600-096 rev A2 dated September 05 1990 or later approved revision		25/07/2005	Active	10015520
EASA.IM.A.S.01399	RAYTHEON AIRCRAFT SERVICES, INC.		SA3703SW	BOMBARDIER CL-600-2B16	FAA STC SA3703 SW. Installation of Thrust Reverser Access Panel in the Lower Nacelle		Arkansas Modification Center Inc Drawing List No 600-7966 dated April 15 1986 or later approved revision		25/07/2005	Active	10015521
EASA.IM.A.S.01400	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA4900SW	BOMBARDIER CL-600-2B16	FAA STC SA4900SW.Installation of Dual Baker M1045 Cockpit Audio Systems with a Baker M1050 Cabin Paging/Chime Amplifier		-Arkansas Modification Center Inc Drawing List No 600-030 rev E dated July 20 1988 or later approved revision-AFM Supplement dated January 26 1983 rev A dated August 3 1988		25/07/2005	Active	10015522
EASA.IM.A.S.01401	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7460SW	BOMBARDIER CL-600-2B16	Installation of Honeywell CG1230AC10 Lasertrack Navigation System		-Arkansas Modification Center Inc Drawing List No 600-086 rev C dated January 23 1990 or later approved revision-AFM Supplement dated July 22 1988 rev B dated February 2 1990 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/07/2005	Active	10015523
EASA.IM.A.S.01402	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA5718SW	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of Airshow 100/200 Cabin Video System		Arkansas Modification Center Inc Drawing List No 600-045 rev J3 dated September 10 1990 or later approved revision		25/07/2005	Active	10015524

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01403	RAYTHEON AIRCRAFT SERVICES, INC.		SA5830SW	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	FAA STC SA5830SW. Installation of Radio Master Switch System		-Arkansas Modification Center Inc Drawing List No 600-062 rev C dated July 15 1988 or later approved revision-AFM Supplement dated July 22 1988 required for -2B16		25/07/2005	Active	10015525
EASA.IM.A.S.01404	RAYTHEON AIRCRAFT SERVICES, INC.		SA7451SW	BOMBARDIER CL-600-2B16	Installation of a Dual EFIS Master Switch System		-Arkansas Modification Center Inc Drawing List No 600-082 rev A dated July 15 1988 or later approved revision-AFM Supplement dated July 22 1988 is required		25/07/2005	Active	10015526
EASA.IM.A.S.01405	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7454SW	BOMBARDIER CL-600-2B16	Installation of Shepherd Security System		Arkansas Modification Center Inc Drawing List No 600-076 rev B1 dated September 13 1990 or later approved revision		25/07/2005	Active	10015527
EASA.IM.A.S.01406	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA7459SW	BOMBARDIER CL-600-2B16	Installation of a Dual FMS Master Switch System		-Arkansas Modification Center Inc Drawing List No 600-083 rev A dated July 16 1988 or later approved revison-AFM Supplement dated July 22 1988 is required	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/07/2005	Active	10015528
EASA.IM.A.S.01408	BOMBARDIER AEROSPACE		FAA SA581NE	CL-600-2B16	Replacement of Total Temperature Sensor			This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/07/2005	Active	10015529
EASA.IM.A.S.0141	AIR MEDIC L.L.C.		FAA STC SA3756WE	B707-100/-100B/-200 SERIES	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'P', dated August 3, 1978 (or laterEASA approved Revisions).			1. This SIC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orre...	16/09/2004	Active	10061356
EASA.IM.A.S.01410	ROCKWELL COLLINS, Inc.d/b/a AIR TRANSPORT SYSTEMS		ST01142WI-D	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Modification of a single or dual Collins TDR-94 or TDR-94D Mode S Transponder System installation with CTL-92 control head to a Flight ID capable Collins TDR-94 or TDR-94D Mode S Transponder installation with CTL-92E control head		Collins Installation Instructions as listed on AML No ST01142WI-D Revision or later approved revision		26/07/2005	Active	10015531
EASA.IM.A.S.01412	LEARJET Inc.		FAA STC ST00190DE-D	CL-600-2B16	Installation of Honeywell FMZ-2000 Flight Management System(FMS) with a Honeywell GNSSU 12 Channel GPS Sensor		Learjet Master Document List 7502481 revision (-) dated October 17, 1995 or later approved revisionAFM Supplement report number BAS63040001 revision (-) dated October 27, 1995 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	26/07/2005	Active	10015532
EASA.IM.A.S.01413	GULFSTREAM AEROSPACE SERVICES CORP.d/b/a GULFSTREAM AEROSPACE CORPORATd/b/a GULFSTREAM		FAA STC ST00640CH	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of the Honeywell Enhanced Ground Proximity Warning System		-Gulfstream Aerospace Corporation Drawing List 601-5161-1, Rev N dated July 22, 2002 or later approved revision-FAA AFMSupplement CL600-AFMS-00023 Rev E dated June 13, 2002 for MK V EGPWS without display		26/07/2005	Active	10015533

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01418	LEARJET Inc.		FAA STC ST01235LA-D	BOMBARDIER CL-600-2B16	Universal Avionics TT-3000 AERO-M Satcom System.Master Drawing List No. DC 23155002 Revision E or later FAA approved revision			This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	09/08/2005	Active	10015534
EASA.IM.A.S.01419	LEARJET Inc.		FAA STC SA8195NM-D	BOMBARDIER CL-600-2B16	Observer Audio Panel Installation.Master Drawing List No. DC23515000 Revision F or later FAA approved revision.		FAA Airplane Flight Manual Supplement listed in the approval Master.Drawing List is required as part of the installation.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	09/08/2005	Active	10015535
EASA.IM.A.S.0142	AIR MEDIC L.L.C.		FAA STC SA3331WE	B707-300/-400 SERIES	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'A', dated January 28, 1977 (orlater EASA approved Revisions).			1 This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configuration shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	16/09/2004	Active	10061357
EASA.IM.A.S.01420	LEARJET Inc.		FAA STC ST01258LA-D	LEARJET 45	Installation of a Universal UMS-1C+ Flight Management System Upgrade from Software Control Number (SCN) 602.X to (SCN) 80X.X with Data Transfer Unit		Learjet Inc Master Document List BAS45010016 revision C dated March 16 2004 or later approved revisions.AFM Supplement BAS45040103 revision NC dated March 16 2004 or later approved revision is required for the - 1 Configuration.AFM Supplement BAS45040104 revision NC dated June 07 2004 or later appro...	1. Universal UNS-1C FMS System must be installed prior to installation of this STC.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be dete...	18/08/2005	Active	10015536
EASA.IM.A.S.01421	LEARJET Inc.		FAA STC ST00412DE-D	LEARJET 45	Installation of UNS-1C Flight Management System (Software Version 604.X)		Learjet Inc Master Document List BAS45010006 revision (-) dated April 7 2000 or later approved revisions.AFM SupplementBAS45040100 revision (-) dated April 07 2000 or later approved revision.	1. Instructions for Continued Airworthiness BAS-45010006-IFCA or BAS-45010006-IFC-2 dated March 28 2000 or later approved revision required for this installation.2. This STCis approved only for the product configuration as defined in the approved design data referred to in the paragraph "Desc...	18/08/2005	Active	10015537
EASA.IM.A.S.01422	INFLIGHT CANADA Inc.	REV. 1	TCCA STC C-LSA95-037/D	AIRBUS A320-232	SONY TRANS COM Passenger Entertainment System installationNote: This STC had to be revised due to a correction to the holder of the original STC.		Modification Data Summery ref. A71200 revision G or later EASA approved revision	1. This STC is limited to the A320 MSN's 496 and 5252. This STC is approved only for the product configuration asdefined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	27/11/2006	Active	10015538

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01424	COMTEK ADVANCED STRUCTURES Ltd.		-	DORNIER D328-100	Replacement of trolley stowage unit panels		Comteck Aircraft Maintenance Manual Supplement COMAMM-030, Rev B, TCCA accepted 30 September 2003 or later approved version for installation/removal.Aircraft Maintenance Manual Supplement COMMAM-031 Rev A, TCCA accepted 30 September 2003 or later approved version for maintenance.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	18/07/2005	Active	10015540
EASA.IM.A.S.01425	GRIMES AEROSPACE COMPANYPRODUCT SUPPORT REPAIR OPERATIONS		ST500CH	BOEING 737-500 BOEING 737-400 BOEING 737-300	Installation of Grimes Aerospace Overwing Emergency/ IceDetection Light Assemblies		- Installation Instructions, Grimes Aerospace Doc. Ref. 30-2471AI, Rev. A dated 10 April 1996- FAA STC ST500CH, dated 22 April 1996	According to FAA STC ST500CH	08/11/2005	Active	10015541
EASA.IM.A.S.01428	AVIATION TECHNICAL SERVICES, Inc.		FAA ST00299SE-D	737-300, 737-400, 737-500	Modification of an 87MCU FMC Tray to accept a 4MCU FMC LRU according to FAA STC ST00299SE-D		BF Goodrich Master Drawing List Ref. 98-055, Rev. C, dated 13 August 2001 or later FAA approved revisionFAA STC ST00299SSE-D, Date reissued 5 July 2005	According to FAA STC ST00299SE-D	29/09/2005	Active	10015543
EASA.IM.A.S.01429	AEROMECH Inc.		FAA ST01456SE	B200, B200C, B300, B300C 200, 200C, 300, 300LW	Group approval for reduced vertical separation minimum.		Aeromech AMI-QD-KAIR-0414, Rev "New", dated 20 AUG 2004.AFMS No. AMI-AFMS-KAIR-0429A, Rev "Original", dated 30 September 2004AFMS No. AMI-AFMS-KAIR-0429B, Rev "Original", dated 30September 2004	1. AFMS No. AMI-AFMS-KAIR-0429A Rev "Original", dated 30September 2004 is required on-board for operation with Beech 200, 200C,B200, B200C, 300 and 300LW series. 2. AFMS No.AMI-AFMS-KAIR-0429B Rev "Original", dated 30 September 2004is required on-board for operation with Beech B300, B300C se...	25/11/2005	Active	10015544
EASA.IM.A.S.0143	AIR MEDIC L.L.C.		FAA STC SA3332WE	B720, 720 B	Installation of Stretcher Carrier in accordance with AIR MEDIC MasterDrawing List Ref: AM-2001, Revision 'A' dated January 28, 1977 (or laterEASA approved Revisions).			1 The approval of this change applies basically to the Boeing 720 and720 B series only2 This SIC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description"Compatibility with other aircraft/engine configuration shall bedetermined by...	16/09/2004	Active	10061358
EASA.IM.A.S.01433	TIMCO AVIATION SERVICES INC.		FAA STC ST03197AT	BOEING 737-800	Complete interior reconfiguration in accordance with TIMCO Aviation Services, Inc MDL, report 04T101L001, revision "C",dated December 07, 2005, or later EASA approved revision		- MDL, report 04T101L001, revision "C", dated December 07, 2005- TIMCO report 04T101R007, Instructions for Continued Airworthiness - Interior reconfiguration, Revision "IR", datedFebruary 9, 2005, or later EASA approved revisions.	1. Compatibility of this design change with other previously approved modifications must be determined by the installer.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraf...	17/07/2006	Active	10015545
EASA.IM.A.S.01437	HEADS UP TECHNOLOGIES, Inc.		FAA STC SA00558DE-D	MSN 3061 DORNIER D328-100 DORNIER 328-100	Installation of a Pilot and Co-Pilot Digital Air Data Unit		Master Data List, document No 34-00-0002-00, Revision IR, dated 23 July 2004 or later approved revisionInstructions forContinued Airwortiness, document 34-02-0002-00, Rev 4.0 dated 16 July 2004 or 34-02-0002-10 Rev 1.0 dated 28 June 2005,or later approved revision	1. Airplane Flight Manual Supplement:AFMS Document 34-07-0002-00, Revision IR, dated 19 August 2004 or Document 34-07-0026-00, Revision IR or later approved revision isrequired onboard for the IS&S ADDU installation,orAFMS Document 34-07-0002-01, Revision IR, dated 19 August 2004 or Document 34-07-...	15/08/2005	Active	10015546

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01438	HONEYWELL INTERNATIONAL INC.		FAA STC SA3122SO	BOEING 747	Honeywell International Inc. of Redmond, Washington, USA has applied for an STC to cover the installation of a CAS81 Traffic Collision Avoidance System (TCAS) II with dual TRA-67 Mode S transponders on Boeing 747-100/200/SP Series aircraft. The FAA has issued STCSA3122SO for this modification.		Refer to Approval Report IVW/LTB/TCP-05.533054	1. Refer to Approval Report IVW/LTB/TCP-05.5330542. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	17/08/2005	Active	10015547
EASA.IM.A.S.01439	JET AVIATION AG, BASEL		-	MYSTERE FALCON 50	Installation of a Honeywell MK VII EGPWS		Master Data List Doc. No.BFA5034461-001AFM Supplement Doc.No.BFA5034461-201-0 1	none	15/11/2005	Active	10015548
EASA.IM.A.S.01443	LEARJET Inc.		FAA STC ST01463SE	LEARJET 31	Group Aircraft Approval for Reduced Vertical Separation Minimum (RVSM)		- Learjet Master Drawing List (MLD) BAS31015030 Revision N/C dated April 15, 2005 or later approved revision.- AeromechAFM Supplement AMI-AFMS-0428 Rev A approved May 09 or laterapproved revision.- Instructions for initial & Continued Airworthiness AMI-IICA-LJ-0432 Revision B dated May 5, 2005 or...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	08/12/2005	Active	10015549
EASA.IM.A.S.01444	AEROSYS Inc.		FAA STC ST01843LA	MD-11F	Installation of the main deck cargo compartment one minute smoke detector in accordance with FAA STC ST01843LA or laterEASA-approved revision.		See item 5 of approval report (attachment)	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph 'Description. Compatibility with other aircraft/ engine configurations shall be determined by the installer.	16/02/2006	Active	10015550
EASA.IM.A.S.01446	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC ST00141AT	BEECH JET 400A	Installation of a Rockwell Collins TCAS 4000		-FAA STC ST00141AT-Raytheon Aircraft Services Master Drawing list No 12436-0, Rev E dated Dec. 26, 2005 or later EASA approved revisions-Airplane Flight Manual Supplement/TCAS 4000, doc. No 12436-16 dated 6/5/01 or later EASA approved Revisions-Instructions for Continued Airworthiness Doc No 12436-I...	Certification Basis: FAA TCDS A16SW and Leaflet No 8 Rev 2	25/01/2006	Active	10015552
EASA.IM.A.S.01449	AVCON DIVISION/ BUTLER NATIONAL CORP		FAA SA2479CE	35, 35A, 36, 36A	Installation of dual openable hatches on the belly of the fuselage.		Avcon Master Drawing List 1054 Revision A dated April 15 2005 or later approved revision.AFM Supplement 6 Change 1 dated June 30 2005 or later approved revision.		20/02/2006	Active	10015553
EASA.IM.A.S.01451	PRATT & WHITNEY	REV. 1	FAA STC SA00196BO	CESSNA 208B CESSNA 208A CESSNA 208 BEECH C90 BEECH 300 BEECH 200 BEECH 1900	Installation of Altair Avionics Corporation Data Transmission Unit in accordance with instructions listed in Approved Model List (AML) DTU-T-225-1, Rev - or later approved revisions. FAA STC SA00196BO refers		Approved Model List (AML) DTU-T-225-1	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	11/04/2008	Active	10015554

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01452	S-TEC CORPORATION	REV. 1	FAA STC SA09147AC-D	CESSNA A152 CESSNA 152	Installation of S-TEC System 40/50 Single and Two Axis Automatic Flight Guidance System, Model ST-628, according to Bulletin No 728, dated 3-29-96 or later approved revisions		-S-TEC Master Drawing List No 92921, dated 3-29-96, or later approved revisions-FAA/DAS Approved Pilot's Operating Handbook and/or Airplane Flight Manual Supplement, P/N 891246, dated 4-03-96 or later approved revisions is required for Cessna Models 152 and A152 for S-TEC System 40-FAA/ DAS Approvede...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/09/2008	Active	10015555
EASA.IM.A.S.01453	S-TEC CORPORATION	REV. 1	FAA STC SA09148AC-D	CESSNA FA-152 CESSNA F152	Installation of S-TEC System 40/50 Single and Two Axis Automatic Flight Guidance System, Model ST-628, according to Bulletin No 728, dated 3-29-96 or later approved revisions		-S-TEC Master Drawing List NO 92921, dated 3-29-96, or alter approved revisions-FAA/DAS Approved Pilot's Operating Handbook and/or Airplane Flight Manual Supplement, P/N 891247, dated 4-03-96 or later approved revisions is required for Reims Aviation S.A Models Cessna F152 and FA152 for S-TEC System...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/09/2008	Active	10015556
EASA.IM.A.S.01454	S-TEC CORPORATION	REV. 1	FAA STC SA5302SW-D	CESSNA 210	Installation of S-TEC System 40/50 Single and Two Axis Automatic Flight Guidance System, Model ST-212-40/50, according to Bulletin No 312, dated 3-21-88 or later approved revisions		-S-TEC Master Drawing List No 92234, rev D, dated 3-21-88, or later approved revisions-FAA Approved Supplements to Pilot's Operating Handbooks and/ or FAA Approved Airplane Flight Manual, as defined in the Limitations and Conditions sectionof FAA STC SA5302SW-D, latest approved revision.- Instruction...	1. As defined in the Limitations and Conditions section of FAA STC SA5302SW-D, latest approved revision2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adve...	09/09/2008	Active	10015557
EASA.IM.A.S.01456	S-TEC CORPORATION		FAA STC SA5242SW-D	AERMACCHI F 260 D AERMACCHI F 260 C AERMACCHI F 260 B	Installation of S-TEC System 40/50, Single and Two Axis Automatic Flight Guidance Systems Model ST-235-40/50FAA STC SA5242SW-D		"Master Drawing List No. 92261 Rev. C dated 21.3.91	1. Only eligible on model F260B when equipped with Aileron Assemblies P/N SF260-02-05-01 (L.H.) and P/N SF260-02-05-02 (R.H.)2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other ai...	13/03/2006	Active	10015559
EASA.IM.A.S.01459	ELECTRONIC CABLE SPECIALISTS, Inc.		ST01404CH	DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (CF6) DC-9-81 (MD-81) DC-9-50 SERIES DC-9-40 SERIES DC-9-30 SERIES DC-9-20 SERIES DC-9-10 SERIES	Installation of Universal Avionics system Corporation Multi-Function Display in accordance with Electronic Cable Specialists MasterData List ECS-2000416 rev. E dated 17.3.2003		Airplane Flight Manual Supplement, Electronic Cable Specialist Doc. No. ECS-200418 rev. A dated 19.9.2002		17/02/2006	Active	10015561
EASA.IM.A.S.01460	PREMIER AIR CENTER, LLCd/b/ a WEST STAR AVIATION		ST01884CH	MYSTERE FALCON 20-F5 MYSTERE FALCON 20-E5 MYSTERE FALCON 20-D5 MYSTERE FALCON 20-C5 MYSTERE FALCON 200 FAN JET FALCON SERIES F FAN JET FALCON SERIES E FAN JET FALCON SERIES D	Installation of a Honeywell Mark VIII Enhanced Ground Proximity Warning System with Terrain Display		See item 5 of approval report (attachment)	1. EASA approved Flight Manual Supplement, Premier Air Center Document 11-327B001, Revision I/R, or later EASA approvedrevision isa required part of this STC (Configuration-01)2.EASA approved Flight Manual Supplement, Premier Air Center Document 11-327B004, Revision I/R, or later EASA approved rev...	29/06/2006	Active	10015562

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01461	BOMBARDIER INC.		TCCA STC Q-LSA05-030/D	BD-700-1A10	Installation of Replacement Cockpit Printer		Master Drawing List MDL05118003 Rev N/ CTime Limits and Maintenance TL05118-004 Rev N/C	1. Installation is limited to S/N 9086Note: All Portable Electronic Equipment/Devices PED, must be unplugge, turned-offand stowed prior taxi, take-off and landing2. This STC is approved only for the product configuration as defined in theapproved design data referred to in the paragraph "Descripti...	12/12/2005	Active	10015563
EASA.IM.A.S.01463	BOMBARDIER AEROSPACE		C-LSA05-181/ D, ISSUE 2	BOMBARDIER BD-100-1A10 (CHALLE	Installation of Equipment Ladder (Aft Equipment Bay) in accordance with MDL380801, rev. 1 dated 11 June 2005 and compliance report BAS68380004		Maintenance Manual Supplement MMS380801 revision IR dated 11 June 2005	1. Limited to: S/N 200132. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibilitywith other aircraft/engine configurations shall be determined by the installer.	23/09/2005	Active	10015564
EASA.IM.A.S.01464	BOMBARDIER AEROSPACE		C-LSA05-212/ D, ISSUE 1	BOMBARDIER BD-100-1A10 (CHALLE	Installation of a Satellite Telephone System Interfaced to an existing Flight Telephone System in accordance with MDL BAS68010010 Revision A dated 30 May 2005 and Compliance Report BAS68380005 dated 10/09/2005		Maintenance Manual Supplement BAS68010010-SMM-1 Revision NCdated 15 April 2005	1. This STC is limited to BD-100-1A10 (Challenger 300) SN 20013	05/10/2005	Active	10015565
EASA.IM.A.S.01474	BOMBARDIER AEROSPACE	REV 1	TCCA STC C-LSA06-015/D ISSUE 2	BOMBARDIER CL-600-2B16	Aircraft Completion		Transport Canada STC C-LSA06-015/D Issue 2 dated September 12, 2006Aero Consulting Services Ltd Modification Data Summary E270000 Revision A or later approved revision.Aero Consulting Services Ltd AFM Supplement E270090 Revision N/C or later approved revision	Restricted to ASN 5605	27/09/2006	Active	10015567
EASA.IM.A.S.01479	HONEYWELL INTERNATIONAL INC.		FAA STC SA00842WI-D	BEECH 1900D	Installation of the Honeywell Mark VI Enhanced Grounfd Proximity Warning System		Master Drawing List 159-08250-000 1 Rev. A dated 15 December 1999Airplane Flight Manual Supplement 006-00875-0000, Rev.A dated April 2001	AFMS 006-00875-0000 is required on-board for operation withBeech 1900 D series	28/11/2005	Active	10015572
EASA.IM.A.S.01480	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC SA4839NM	757-200	Installation and activation of TCAS and the XS-950 Mode S Transponder (including ELS/EHS).		Honeywell Master Data List ML4070373 Revision F dated July 24 1990 or later approved revision.Honeywell AFM Supplement 5140-0885 approved July 14 1990 or later approved revision.		07/11/2005	Active	10015573
EASA.IM.A.S.01484	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST00636SE	BOEING 737-500 BOEING 737-400 BOEING 737-300	Installation of ATIX Interior retrofit Kit according to FAASTC ST00636SE		- Heath Tecna Drawing List HPD-DL-57, Revision F datedt 17 January 2001- FAA STC ST00363SE, Date reissued 17 March 2005	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	01/09/2005	Active	10015574
EASA.IM.A.S.01485	HONEYWELL INTERNATIONAL INC.		FAA STC SA2726SO	DC-9-80 (MD-80) SERIES	Installation of CAS-81 TCAS II SystemFAA STC SA2726SO		Allied Signal Master Drawing List No. 699-50005 Rev. M dated 4 June 2003.Aircraft Flight Manual Supplement No. 699-52554 Rev. C dated October 1999.		02/05/2006	Active	10015575
EASA.IM.A.S.01489	BENZ COMPANIES, LTD.		FAA SA10365SC	PIPER PA-31T1 PIPER PA-31T	FAA STC SA10365SC: Installation of a Benz Airborn System Model 800-0021 torque pressure system.		Benz Engineering Order (Instruction for Installation) SB079-4021-00, Rev. B, dated 19 January 2005.	N/A	19/03/2007	Active	10015578

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01490	GULFSTREAM AEROSPACE Corp.		FAA STC ST09625SC	GULFSTREAM 200	Installation of a Universal Unilink UL-601 Datalink Data Communication System		-Master Drawing List Engineering Document Number 30-1100001, Revision K, dated October 2, 2000 or later approved revision-Aeroplane Flight Manual Supplement Rev 1 dated 27 September 2005, or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015579
EASA.IM.A.S.01491	GULFSTREAM AEROSPACE Corp.		FAA STC ST09628SC	GULFSTREAM 200	Installation of Hard Point Attachments and associated floorstructure		-Galaxy Aerospace STC data list Engineering Document Number30-1100004, revision E dated 15 November 1999, or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015580
EASA.IM.A.S.01492	GULFSTREAM AEROSPACE Corp.		FAA STC ST09629SC	GULFSTREAM 200	Installation of an Artex ELT (110-406 NAV) Emergency Locator Transmitter Sytem with NAV interface		-Engineering Document 30-1100005, Revision K dated June 27,2000 or later approved revision-Aeroplane Flight Manual Supplement docuiment number 30-112004 dated January 14, 2000 orlater approved revision	1. For aircraft imported into the European Union, changes per Gulfstream Aerospace drawing CEB44231001, Rev A are required to be incorporated until Revision L os the Engineering document 30-110005 has been released.2. This STC is approved only for the product configuration as defined in the approved...	06/10/2005	Active	10015581
EASA.IM.A.S.01493	GULFSTREAM AEROSPACE Corp.		FAA STC ST09747SC	GULFSTREAM 200	Installation of a N°2 Allied Signal KHF-950 HF Communication System		-Galaxy Aerosapce STC Data List number 30-1100009, revisionC, dated April 18, 2000, or later approved revision-Airplane Flight Manual Supplement Revision 1, dated 27 September 2005, or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015582
EASA.IM.A.S.01494	GULFSTREAM AEROSPACE Corp.		FAA STC ST09748SC	GULFSTREAM 200	Installation of a second 77 cubic-foot oxygen bottle in nose radome area, above existing bottle		-Galaxy Aerospace STC data list 30-1100010, revision K, dated June 26, 2003, or later approved revision-FAA Airplane Flight Manual Supplement GA22708M001, revision IR dated July 7, 2003 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015583
EASA.IM.A.S.01495	GULFSTREAM AEROSPACE Corp.		FAA STC ST09851SC	GULFSTREAM 200	Installation of interior shell, forward cabinets, card tables, lavatory partitions and door, curtain		-Interior Master Drawing Document number IMDL6600-012, Revision AC, dated August 28, 2002, or later approved revision-Airplane Flight Manual Supplement document number 30-1120014,dated March 12, 2001, or later aproved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015584
EASA.IM.A.S.01496	GULFSTREAM AEROSPACE Corp.		FAA STC ST09953SC	GULFSTREAM 200	Installation of B/E Aerospace, Aircraft Modular Products Forward/Rearward Facing Single Seat, model 2524.546.01 ( )		Gulfstream STC Data List 30-1100018, Revision C, dated November 9, 2001, or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015585
EASA.IM.A.S.01497	GULFSTREAM AEROSPACE Corp.		FAA STC ST09954SC	GULFSTREAM 200	Installation of an Oxygen Filler Panel with Pressure Gauge		Gulfstream STC Data List 30-1100017, Revision C, dated August 22, 2001, or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015586

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01498	DECA AVIATION ENGINEERING Ltd.		TCCA STC O-LSA01-428/D ISS3	A320-232	Emergency exit sign Relocation		DECA Drawing 7SK0439, Revision A, dated April 5, 2001 or later EASA approved revision	1) Limited to the A320 MSN 4962) This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	25/10/2005	Active	10015587
EASA.IM.A.S.01499	S-TEC CORPORATION		FAA STC SA09239AC-D	CESSNA F172-N	Installation of S-TEC System 20/30 Single and tow Axis Automatic Flight Guidance Systems		Bulletin No 774, dated 11 June 1997 and Master drawing listNo 921007, dated 11 June 1997 or later FAA Approved revision of the above data.EASA approved Pilot`s Operating Handbookand/or Airplane Flight Manual Supplement P/N EASA891427, dated 14 June 2005 is required for S-TEC System 20 or later EAS...	Also eligible on the above models when modified by 180 HP Engine conversion. EASA approval of this STC must be ckecked.This STC is issued as result of the validation of the S-TEC Corporation STC No SA09239AC-D approved by the FAA on June 26, 1997.	04/08/2005	Active	10015588
EASA.IM.A.S.01500	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		TCCA/LSTC Q-LSA05-029/D	BOMBARDIER BD-700-1A10	Miscellaneous modifications to cabin interior and installation of Electronic Flight Bag System provisions for BD700-1A10 Global ExpressAcc.: MDL-05103002 Rev. B or later TCCA approved rev.Validation of imported TCCA/LSTC: Q-LSA05-029/D		FCOM Supplement: FOMS05103005 Rev A	1. Limited to S/N 90172. Regarding the installation of the Electronic Flight Bag System the design covers only the mounting device and its connection to the aircraft. The suitability, integrity or accuracy of the EFB hardware, software, database, display, controls and lighting, hasnot been ass...	18/11/2005	Active	10015589
EASA.IM.A.S.01501	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA ST01742CH	747-400F 747-400 BCF 747-400	Installation of Honeywell RESCU 406AF Emergency Locator Transmitter (ELT) system		Armstrong Aerospace master Data List Document DC104-1011-00Revision M dated March 25, 2005 or later approved revisionArmstrong Aerospace AFM Supplement Document number DC303-1011-00 Revision C approved April 20, 2005 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/10/2005	Active	10015590
EASA.IM.A.S.01502	BOMBARDIER INC.		TCCA LIMITED STC C-LSA05-347/D	BOMBARDIER BD-700-1A10	Installation, Aircraft Interior Completion for BD700-1A10 Global Expressacc.: MDS E583000 Rev. N/CValidation of imported TCCA Limited STC: C-LSA05-347/D		AFM Supplement G-FM25000133 Rev. N/C or later TCCA approvedrev.ICA GC91630001-IFCAAMM Supplement/Airworthiness Limitations G-TM05100069	ref. G-FM25000133 Rev. N/C; Limited to S/N 9163Note:1. The airplane is limited to privat use only unless the mid cabin door is rendered inoperable.2. Approval of EFB installation does not constituete operational approval to use EFB function.3. This STC is approved only for the product configurati...	17/11/2005	Active	10015591
EASA.IM.A.S.01504	BOMBARDIER COMPLETION CENTRE INC	REV. 1	TCCA STC C-LSA05-272/D	BOMBARDIER BD-700-1A10	1. Installation, Aircraft Interior Completion for BD700-1A10 Global Express acc MDS E553000 Rev N/C.2. Revision 1: Modification to Interior Completion.		1. AFM Supplement G-FM25000132 Rev N/C or later approvedrevision.2. ICA GC91590001-IFCA.3. AMM Supplement/ Airworthiness Limitations G-TM05100068.4. Revision 1:4.1.Aero Consulting Services Ltd Modification Data Summary No E553000 Revision A dated 16 October 2008 or later approved rev...	1. Ref G-FM25000132 Rev N/C Limited to S/N 9159.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.3. Prior...	26/11/2008	Active	10015592

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01505	BOMBARDIER AEROSPACE		TCCA C-LSA06-002/D	BD-100-1A10	Cabin mod for passenger seat upgrade in accordance with Bombardier MDLBA680100009		None	1. SN 20013, validation of TCCA STC C-LSA06-002/D2. Instructions for continuing airworthiness and supplementalmaintenance information are provided in Amtech Aeronautical Limiteddocuments MMS390201.3. Bombardier Aerospace service bulletin No. 100-53-06 and drawingBAS68030019 must be installed prior t...	04/05/2006	Active	10042979
EASA.IM.A.S.01506	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST399CH	BOMBARDIER CL-600-2B16	Installation of a Honeywell FMZ-2000 Flight Management System		-Gulfstream Aerospace Drawing List No 601-507-5077-2 Revision 1 dated 11 February 2002-Gulfstream AFM Supplement No CL6-AFMS-0015 Revision G dated 11 February 2002	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	12/09/2005	Active	10015593
EASA.IM.A.S.01507	BOMBARDIER Inc.		FAA STC SA556NE	CL-600-2B16	Installation of a Forward Overboard Servicing		I.A.E.L. Modification List ML 13545 Revision A dated January 7 1988 or later approved revision	Limited to Airplane Serial Number 5055	25/10/2005	Active	10015594
EASA.IM.A.S.01508	GULFSTREAM AEROSPACE CORPORATION.		FAA STC SA589GL	BOMBARDIER CL-600-2B16	Installation of Passenger Oxygen System and Modification ofCrew Oxygen System		-K-C Aviation Inc Engineering Drawing List 600-017 RevisionM dated 17 october 1989-AFM Supplement AFMS-26 for option 6dated 27 August 1987	1. Canadair Part Numbers 600-34012-73, located at B.L.6 06,and 600-34012-71, located at B.L.13, 73, must be replaced if any cracksare detected during the inspections required at intervals of 1000 take-off/ landing cycles with this modification installed2. Page 8 of K-C Aviation Instructions for Cont...	12/09/2005	Active	10015595
EASA.IM.A.S.01509	GULFSTREAM AEROSPACE CORPORATION.		FAA STC SA3716SW	BOMBARDIER CL-600-2B16	Installation of a baggage compartment smoke detector system		-K-C Aviation Inc Drawing List No T10-049 Revision C dated 3 September 1987	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	12/09/2005	Active	10015596
EASA.IM.A.S.01510	GULFSTREAM AEROSPACE CORPORATION.		FAA STC SA4372SW	BOMBARDIER CL-600-2B16	Installation of an emergency lighting system		-K-C Aviation Inc Drawing List No T10-010 Revision D	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	12/09/2005	Active	10015597
EASA.IM.A.S.01511	GULFSTREAM AEROSPACE CORPORATION.		FAA STC SA8353SW	BOMBARDIER CL-600-2B16	Installation of a Loral F-1000 Flight Data Recorder		-K-C Aviation Inc Drawing List No T10-075 Revision A dated 17 June 1992-K-C Aviation Inc AFMS-244 Initial Release dated30 June 1992	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	12/09/2005	Active	10015598
EASA.IM.A.S.01535	AIM AVIATION RENTON, INC.		ST01504SE	757-200	Installation of a Flight Deck Galley		AIM Aviation Inc. Master Drawing List AIM-MDL-14492 Revision New dated January 25 2005 or later approved revision		03/04/2006	Active	10015599
EASA.IM.A.S.01537	TIMCO AVIATION SERVICES INC.		FAA STC ST03107AT-D	BOEING 767-300	Interior Reconfiguration		TIMCO Master Data List 04T110L001 Revision IR dated December 08 2005 or later approved revision.		15/12/2005	Active	10015601

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01538	ROCKWELL COLLINS AEROSPACEAND ELECTRONICS, Inc.		ST01205NY	BOMBARDIER CL-600-2B16	Installation of Head Up Guidance System (HGS) Model 2100 (Phase 2)		STC Master Drawing List No. 9701-1085 Revision N or later approved revision.AFM Supplement 9701-1087 Revision D or later approved revision.		15/08/2005	Active	10015602
EASA.IM.A.S.01539	BOMBARDIER AEROSPACE		TCCA STC C-LSA05-314/D	BOMBARDIER CL-600-2B16	Aircraft Completion 11 PassengerInterior Configuration		Aero Consulting Services Modification Data Summary E265000 Revision N/C or later approved revision.Aero Consulting Services AFM Supplement E265090 Revision N/C or later approved revision.	1. Restricted to Aircraft Serial Number 5599.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	28/11/2005	Active	10015603
EASA.IM.A.S.01540	S-TEC CORPORATION	REV. 1	FAA STC SA7209SW-D	CESSNA T337H-SP CESSNA T337H CESSNA T337G CESSNA T337F CESSNA T337E CESSNA T337D CESSNA P337H CESSNA 337H CESSNA 337G CESSNA 337F CESSNA 337E CESSNA 337D	Installation of S-TEC System 60 Two Axis Automatic Flight Guidance System with Optional Autotrim System, Model ST-314, according toBulletin No 414, dated 3-14-90 or later approvedrevision		-S-TEC Master Drawing List No 92503, dated 3-14-90 or laterapproved revision-FAA/DAS Approved Supplemental Flight Manual, Part No 89845, dated 4-06-90 is required for Cessna Models 337D, T337D, 337E, T337E, 337F, T337F, 337G, T337G, 337H,P337H, T337H, and T337H-SP when modified per STC SA1627WE (R...	1. Eligble when above models are modified per FAA STC SA1627WE (Robertson STOL Conversion)2. Eligible when the above models are modified per FAA STC SA937CE (Horton STOL Craft Conversion)3. It is the operator's responsibility to ensure theabove mentioned Horton4. This STC is approved only for the p...	12/09/2008	Active	10015604
EASA.IM.A.S.01541	S-TEC CORPORATION	REV. 1	FAA STC SA7210SW-D	REIMS AVIATION FT-337HP REIMS AVIATION FT-337GP REIMS AVIATION FT-337F REIMS AVIATION FT-337E REIMS AVIATION F-337H REIMS AVIATION F-337G REIMS AVIATION F-337F REIMS AVIATION F-337E	Installation of S-TEC System 60 Two Axis Automatic Flight Guidance System with Optional Autotrim System, Model ST-314, according toBulletin No 414, dated 3-14-90 or later approvedrevisions.		1. S-TEC Master Drawing List No 92503, dated 3-14-90, orlater approved revisions.2. FAA/DAS Approved Supplement Flight Manual, Part No 89847, dated 4-06-90 is required for Reims Aviation S.A. Models F337E, FT337E, F337F, FT337F, F337G, FT337GP, F337H and FT337HP when modified per STC SA1627WE...	1. Eligible when the above models are modified per FAA STC SA1627WE (Robertson STOL Conversion).2. Eligible when the above models are modified per FAA STC SA937CE (Horten STOL Craft Conversion).3. It is the operators responsibility to ensure the above mentioned Horton and Robertson STOL STC...	09/09/2008	Active	10015606
EASA.IM.A.S.01543	JET AVIATION AG, BASEL		-	MYSTERE FALCON 50	GPWS upgrade to EGPWS		Master Data List Doc. No. BEHHS003-001 Revision A or later approved revisions.AFM Supplement Doc. No. BEHHS003-201-01 Revision IR or later approved revisions.ICA Doc. No. BEHHS003-150-01 Revision IR or later revisions.	This STC is limited to Falcon 50 S/N 204.	17/08/2005	Active	10015607
EASA.IM.A.S.01544	HYDRO-AIRE AEROSPACE CORP.		FAA STC SA3339WE	KING AIR 200 BEECH 200, SUPER KING AIR	Installation of Power Brake / Skid Control System		Model 200: Hydro-Aire Drawings No. 13-001 Revision C or later approved revision.Model B200: Hydro-Aire Drawings No. 13-001-100, Revision C or later approved revision.	1. Models 200: Hydro-Aire Airplane Falight Manual Supplement dated on 17 MAY 1977 or later approved revision. 2. Models B200: Hydro-Aire Airplane Flight Manual Supplement No. R13-001-100-05 dated 12 MAY 2005 or later approved revision. 3. This STC is approved only for the product configuration as defi...	02/09/2005	Active	10015608
EASA.IM.A.S.01545	GULFSTREAM AEROSPACE CORPORATION		ST02952AT-D	GULFSTREAM GV-SP	Installation of a Satellite communications system to be used for passenger communications.		Gulfstream DAS Index List ref GC511038022 and report No GC51303K008 dated 8/31/2005 or later approved revisionsFMS GC51103M000FAA STC ref ST02952AT-D.		26/09/2005	Active	10015609

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01546	GULFSTREAM AEROSPACE CORPORATION		ST01824CH-D	MD-88 GULFSTREAM ASTRA/ SPX GULFSTREAM 100	Installation of the Honeywell MK-V EGPWS, with windshear warning and terrain display on the Collins Pro Line 4 EFIS		- FAA STC No. ST01824CH-D- Master Drawing List GA113498001,Rev. B, dated March 30, 2005 or later EASA approved Revisions- Airplane Flight Manual Supplement Report No. GA11349M001, Rev.-, dated June 24 2003 or later EASA approved Revisions- Instruction for Continued Airworthiness Report No. GA1134...		12/10/2005	Active	10015610
EASA.IM.A.S.01547	L3 AVIATION PRODUCTS, INC		FAA ST01554AT	DC-9-34/-34F/-41/-51, MD-88 DC-9-14/-15/-21/-32/-32F/-33F	Increasing data recording parameters to 17/18 parametes on digital flight data recorders (DFDR) for L-3 Com (formerly Loral/Fairchild) DFDR and Allied Signal DFDR		Flight Systems Engineering Inc., Report n° 98-01-05 Rev. J dated 09-5-05		27/01/2006	Active	10015611
EASA.IM.A.S.01550	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01495LA-	GULFSTREAM GV-SP	installation of a Honeywell Satellite TV antenna to providetelevision reception to passenger cabin TV monitors		-Gulfstream DAS Index List ref GC515070029 and report No GC51507K000 daetd 9/1/2005 or later approved revisions-FAA STCref ST01495LA-D	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015612
EASA.IM.A.S.01551	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01378LA-D	GULFSTREAM GV-SP	Installation of a Conduit in the vertical stabiliser to accommodate wiring for the STACOM and SAT TV antennas		-Gulfstream DAS Index List ref GC524988002 and report No GC52498K000 dated 9/1/2005 or later approved revisions-FAA STCref ST01378LA-D	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/10/2005	Active	10015613
EASA.IM.A.S.01553	LIFEPORT, LLC	REV. 1	FAA STC ST01780LA	CESSNA 560 XL	Installation of a Patient Loading and Utility System (PLUS)inaccordance with FAA STC ST01780LA or later EASA approved revisionNote: Revision 1 issued to correct a type in the Original STC number.		Master Drawing List, Nr. MDL-777	Ref. AFM Supplement EGR-777-11, Revision A, dated June 24, 2005, or later FAA approved revision	24/07/2009	Active	10015614
EASA.IM.A.S.01554	ROCKWELL COLLINS, Inc.		FAA STC SA3979NM	B757-200	Installation of Trans Com Video Projection System		Trans Com Index List 062-0128 Revision "-" dated March 10 1989 or later approved revision		20/06/2006	Active	10015615
EASA.IM.A.S.01555	LEARJET Inc.		FAA STC SA8171NM-D	BOMBARDIER BD-700-1A10	Pilot and Co-Pilot Footrests for BF700-1A10 Global Expressacc.: MDL GC2500501 Rev. B or later FAA approved rev.Validation of imported FAA STC: SA8171NM-D				16/11/2005	Active	10015616
EASA.IM.A.S.01569	GULFSTREAM SERVICES CORPORATION		FAA STC ST02915AT-D	GULFSTREAM GV-SP	Lightning Sensor System Installation		-FAA STC ST02915AT-D-AFMS GC51 225M000	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	06/12/2005	Active	10015617
EASA.IM.A.S.01570	GULFSTREAM SERVICES CORPORATION		FAA STC ST03134AT-D	GULFSTREAM GV-SP	Aircraft Completion STC		FAA STC Number ST03134AT-D	Limited to S/N 5080	06/12/2005	Active	10015618
EASA.IM.A.S.01571	ANCRA INTERNATIONAL LLC		ST01748LA	757-200	Installation of a Main Deck Cargo Handling System		Ancra Interantional LLC Controlled Drawing List DL83680 Revision A dated March 5, 2004 or later approved revision		23/12/2005	Active	10015619

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01572	GENERAL AEROSPACE INC		FAA STC ST03138AT	BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200	Installation of Honeywell Enhanced Ground Proximity WarningSystem according to FAA STC ST03138AT		General Aerospace Master Drawing List No. GA37-EGPWS-MDL, dated 20 June 2005Airplane Flight Manual Supplement, Ref. GA37-EGPWS-AFMS01, dated 22 July 2005FAA STC ST03138AT, issued 22 July 2005	According to FAA STC ST03138AT	03/03/2006	Active	10015620
EASA.IM.A.S.01573	TRANSAIRCO S.A.		-	FALCON 20	Incorporation of Mode S EHS capability		Modification TSA F20-34.80.01AFMS F20-34.80.01 AFMS	1. Limited to Falcon 20 S/N 237; 257; 307; 341; 389; 4262. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	14/09/2006	Active	10015621
EASA.IM.A.S.01574	TACA INTERNATIONAL AIRLINEST/A TECHNICAL AND TRAINING SERVICES(TTS)		-	AIRBUS A320-233	Automatic ELT Provisions installlation and activation		Grupo TACA Engineering Order A320MO25-089/99 Revision datedJuly 31, 2000	This STC is limited to A320 MSN 561	20/10/2005	Active	10015622
EASA.IM.A.S.01575	TACA INTERNATIONAL AIRLINEST/A TECHNICAL AND TRAINING SERVICES(TTS)		-	AIRBUS A320-233	Automatic ELT- Provisions installation and activation		Grupo TACA Engineering Order A320MO25-089/99, Revision 3, dated June 7, 2001	This STC is limited to A320-233 MSN 558	20/10/2005	Active	10015623
EASA.IM.A.S.01576	TACA INTERNATIONAL AIRLINES, S.A.			A320-233	Equipment and furnishing - delivery configuration of passenger cabin - 180 pax		Taca Engineering Order A320IN25-122/05, Revision 0, dated August 31, 2005.	This STC is limited to the A320 MSN 561	26/05/2005	Active	10015624
EASA.IM.A.S.01577	TDG AEROSPACE INC		FAA STC SA6042NM	MD-11 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (CF6) DC-9-81 (MD-81)	Installation of NOFOD Overwing Anti-Ice System		TDG Aerospace Drawing List No E93-104, Rev U dated 31 October 2002	1. Flight Manual Supplement TDG Doc No E93-096 Rev D dated 27 September or later approved revision2. Instructions for Continued Airworthiness TDG Doc E93-109 Revision P dated 11 February 20033. This STC is approved only for the product configuration as defined in the approved design data referred to...	05/09/2005	Active	10015625
EASA.IM.A.S.01578	JET AVIATION AG	REV. 2		BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Activation of RAAS		Master Data List No. BCL6134461-001, Rev. D of 12-01-2009 or later approved revision.AFM Supplement Bo. BCL6134462-201-01, Rev. A of 12-01-2009 or later revision.		13/01/2009	Active	10015626
EASA.IM.A.S.01580	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01758LA-D	GULFSTREAM G550	Installation of Executive Cabin Interior and other Completion Related Modifications		-FAA STC No ST01758LA-D-GAC Index List GC52 0008491, Rev D,Jan 10, 2006 or later approved revisions-AFMS GC52000M007, Rev 0, Jan 11, 2006 or later approved revisions	G550 S/N 5078 only	30/01/2006	Active	10015628
EASA.IM.A.S.01581	GULFSTREAM AEROSPACE CORPORATION		ST01503LA-D	GULFSTREAM G550	Installation of an Motorola Satellite Telephone (Iridium) Antenna		-FAA STC ST01503LA-D-GAC Index List GC511038000, Rev D, Dec02, 2003 or later approved revisions	GV-SP (550)	30/01/2006	Active	10015629

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01582	BOMBARDIER INC.	REV. 1	TCCA STC SA04-113	BD-700-1A10	Installation, Completion of custom Aircraft Interior for BD700-1A10 Global Expressacc.: CDL D954000 Rev. KValidation ofimported TCC STC: SA04-113		AFM Supplement G-FM25004001 Rev N/C or later TCCA approved rev.ICA GC91450000-IFCAAMM Supplement G-TM05104001	1. Ref. G-FM25004001 Rev. N/C: Limited to S/N 91452. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	12/09/2005	Active	10015630
EASA.IM.A.S.01584	ROCKWELL COLLINS, Inc.		ST01745CH	HAWKER HS 125-700A	Installation of Rockwell Collins Traffic Alert and Collision Avoidance System (TCAS II) in Raytheon HS 125 Series 700A Aircraft		-Elliott Aviation Master Data List 2004-576DL, Rev 2, datedDecember 10, 2002 or later approved revisions-Airplane Flight Manual Supplement Elliott Aviation Document No FS2004-576, Rev 0, FAA Approval dated December 15, 2002, or later approved revisions-Instructions for Continued Airworthiness, Chap...		06/12/2005	Active	10015631
EASA.IM.A.S.01586	AIRGLAS, Inc.		FAA STC SA02244AK	2. 185E, A185E, A185F 2. 185, 185A, 185B, 185C, 185D 1. 180J, 180K 1. 180E, 180F, 180G, 180H 1. 180, 180A, 180B, 180C, 180D	Fabrication and Installation of Airglas Inc Model LH4000 hydraulically retractable wheel skis.		Installation in accordance with Airglas Inc Drawing No LH3600-1 original issue dated January 25, 2005 and Airglas Inc Installation,Maintenance, Service instructions and Illustrated Parts List, Airglas Inc Manual No LH4000-105, dated January 25, 2005 or later approved revisions.Instructions for conti...	1. This STC is only applicable to aircraft fitted with a Tyre size of 8.50-6, Type III.	28/07/2006	Active	10015632
EASA.IM.A.S.01589	S-TEC CORPORATION		FAA STC SA7805SW-D	PIPER PA-28R-201T PIPER PA-28R-201 PIPER PA-28R-200 PIPER PA-28R-180	Installation of S-TEC Manual Trim System (field installation) i.a.w. MDL 92549 Rev A		-FAA STC SA7805SW-D-AFM Supplement P/N 89940-IFCA, P/N 81322, Rev 2	Limited to Installations without the trim monitor system	30/01/2006	Active	10015633
EASA.IM.A.S.01590	S-TEC CORPORATION		FAA STC SA7815SW-D	PIPER PA-23-160 PIPER PA-23	STC SA7815SW-D, Installation of S-TEC System 60 Two Axis Automatic Flight Guidance System, Model ST-486		FAA STC SA7815SW-DFAA AFMS P/N 89968, Rev. 2,IFCA P/N 81431	1. Eligible on models modified per STC SA504WE and/or STC SA824WE.2. Eligible on models modified per STC SA461SW, SA636SW, SA671SW and 899SW3. Instructions for continued airworthiness acc. Doc. P/n 81431 5. Maintenance Instructions 2.-4. must be performed every 100 flight hours or once every calende...	17/02/2006	Active	10015634
EASA.IM.A.S.01592	TIMCO AVIATION SERVICES INC.		FAA STC ST01929AT-D	BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-100 SERIES	Installation of Flight Data Recorder Expanded Parameters with a Plessey FDAU		Master Data List 99T037L001 Rev. L or later approved revision	Limited to: 99T037C002 for DHC-8-100/20000T029C009 for DHC-8-300Maintenance required: pitch, roll and yaw position transducers and strings have to be detailed visually inspected and checked for smooth operation acc. MRB interval 2C	19/07/2006	Active	10015636
EASA.IM.A.S.01593	TIMCO AVIATION SERVICES INC.		FAA STC ST03135AT-D	BOEING 767-300	Installation of Rockwell Collins ACARS CMU-900		TIMCO Master Data List 05T036L001 Revision IR dated November 21, 2005 or later approved revision		28/11/2005	Active	10015637
EASA.IM.A.S.01602	GENERAL AEROSPACE INC		FAA STC ST03126AT	BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200 BOEING 737-100	Installation of a honeywell RESCU 406AF Emergency locator transmitter (ELT) System according to FAA STC STO3126AT		General Aerospace Master Drawing List Ref. FA373-ELT-MDL, dated 7 May 2005	According to FAA STC ST03126AT	29/11/2005	Active	10015639

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01603	DUNCAN AVIATION, INC.		FAA STC ST0069WI	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of Honeywell TCZ-910 TCAS II & XS-852 Mode S Transponder System		1) Duncan Aviation Inc. Document List No. 10040700 RevisionG dated December 3, 20022) Duncan Avation Inc. AFM Supplement Document Nos 40134800 Revision B & 40141800 Revision B; or later FAA approved revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/10/2005	Active	10015640
EASA.IM.A.S.01605	BOMBARDIER INC.		TCCA STC C-LSA06-014/D	BOMBARDIER BD-700-1A11	Installation 13 Passenger interior completion for BD700-1A11		-Master Drawing List E660000 Rev N/C-Flight Manual Supplement G-FM25000135 Rev N/C-Time Limits and Maintenance GC91680001-TLMC Rev N/C	1. Installation of limited to S/N 91682. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall be determined by the installer.	30/01/2006	Active	10015641
EASA.IM.A.S.01607	BOMBARDIER INC.		TCCA STC NO C-LSA05-382/D	BOMBARDIER BD-700-1A11	Aircraft Completion 13 Passenger Interior Configurationalidation of TCCA Limited STC C-LSA05-382/D to S/N 9170MDL: E810000 Rev A or later approved revisions		FMS: G-FM25000136 Rev A or later approved revisionsIFCA: GC91700001-IFCA		07/04/2006	Active	10015643
EASA.IM.A.S.01608	BEECHCRAFT CORPORATION		FAA ST01342WI-D	HAWKER 800XP	Installation of Collins Integrated Flight Information System (IFIS 5000) and Pro Line 21 Radios		Collins Master Data List AAC-0360-001 Rev - , dated July 8,2004, or later approved revision.Collins airplane Flight Manual Supplement ref. AAC-0366-001, Rev -, dated June 6, 2005, or later approved revision.Collins Maintenance Manual Supplement ref AAC-0367-001 Rev -, dated May 2, 2005, or later ap...	1. Prior to installation and approval of Raytheon Aircraft Company Kit 149-3419-0001 is prerequisite to this STC.2. Prior to installation and approval of Rautheon Aircraft Company Kit 149-3420-0001 is prerequisite to this STC.3. This STC is approved only for the product configuration as def...	19/10/2005	Active	10015644
EASA.IM.A.S.01619	LIFEPORT, INC.		FAA STC SA00635SE	208 208A 208B	Installation of a Patient Loading and Utility System (PLUS)in accordance with FAA STC SA00635SE or later EASA approvedrevision.		See item 5 of approval report (attachment)	1. Airplane Flight Manual supplement EGR-571-11, Revision A, dated January 11, 2002, or later FAA approved revision.	16/02/2006	Active	10015646
EASA.IM.A.S.01622	NEW SYSTEMS ENGINEERING		FAA STC ST09384SC	SAAB 340B SAAB 340	Installation of a single Universal Avionics Flight Management System in SAAB SF340A and SAAB 340BFAA STC ST09384SC, Rev. 2		FAA STC ST09384SC, Rev.2, including New Systems AFM Supplement 227-00-0011, Rev. D, FAA approved February 27, 2006	None	19/04/2006	Active	10015648
EASA.IM.A.S.01624	AERO CONSULTING SERVICES LTD.	REV 1	TCCA STC C-LSA05-303/D ISSUE 2	BOMBARDIER CL-600-2B16	Aircraft Completion 12 Passenger Interior Configuration		- Aero Consulting Services Modification Data Summary E596000 Revision B or later approved revision.- Midcoast Aviation AFM Supplement 34-424M005 Revision N/C or later approved revision.- Midcoast Aviation AFM Supplement 34-261M017Revision N/C or later approved revision.	Restricted to Aircraft Serial Number 5610	25/07/2006	Active	10015649
EASA.IM.A.S.01625	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC SA5061NM	MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Installation of Honeywell Traffic Alert & Collision Avoidance System (TCAS II)		-Honeywell Master Data List No ML40741700 Revision A dated March 21 1991 or later approved revision-Honeywell AFM supplement TCAS-APPS-02494 Revision A dated October 18, 2000 or later approved revision		30/01/2006	Active	10015650

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01626	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC SA5541NM	BOEING 767-300 BOEING 767-200	Installation of Honeywell Traffic Alert & Collision Avoidance System (TCAS)		Honeywell Master Data List No ML4076520 Revision N/C dated July 24 1992 or later approved revision	1. TCAS Airplane Flight Manual Supplement (Change 7) TCAS-APPS-0294, Rev A.2. This STC is approved only for the productconfiguration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the...	12/12/2005	Active	10015651
EASA.IM.A.S.01627	ITOCHU AIRLEASE, INC.		FAA ST10436SC	BOEING 767-300	Reconfiguration of an existing three seating class interiorwith 199 passengers to a two seating class interior (enconomy & business seats) with 232 passengers.		Future Jet Aerodesign LLC Master Data List 1610000 RevisionF dated July 7, 2005 or later approved revision.AFM Supplement Document number 1610000-AFMS Rev IR dated July 15 2005 or later approved revision.		02/11/2005	Active	10015652
EASA.IM.A.S.01628	AERO CONSULTING SERVICES LTD.	REV 1	TRANSPORT CANADA STC C-LSA05-2	BOMBARDIER CL-600-2B16	Aircraft Completion 12 Passenger Interior Configuration		- Aero Consulting Services Modification Data Summary E281000 Revision B or later approved revision.- Midcoast Aviation AFM Supplement 34-424M005 Revision N/C and 34-261M017 Revision N/C or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.2. Restricted to Aircraft Serial Number 5609.	25/07/2006	Active	10015653
EASA.IM.A.S.01629	S-TEC CORPORATION		FAA STC SA8400SW-D	TB20, TB21	Installation of S-TEC System 55/55X Two Axis Automatic Flight GuidanceSystem, Model ST-546		Bulletin No 646 Revision 3, dated 23 August 2001 and Masterdrawing listNo 92695, Revision C, dated 23 August 2001 or later approved revisionsof the above data (14 Volt system)EASA approved Pilot's Operating Handbook and/or Airplane FlightManualSupplement P/N EASA891084 dated 28 November 2005 is re...	1. This STC is issued as result of the validation of the S-TECCorporation STC No SA8400SW-D approved by the FAA on August 23, 20012. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircr...	12/12/2005	Active	10042980
EASA.IM.A.S.01631	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC ST02599AT	HAWKER 700A AND 700B	Installation of a "Upgraded Height Keeping Equipment that complies with Reduced Vertical Separation Minimum (RVSM) Criteria".		In accordance with Master Drawing List MDL RAF02101, Revision 2, dated January 8, 2003 or later approved revisions.FAA approved Airplane Flight Supplements, Document Numbers FMS-RAF02101A and if applicable Document Number FMS-RAF02101B, dated December 18, 2002,orFMS-RAF02101C, dated March 21, 2003,...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engineconfigurations shall be determined by the installer.	19/12/2005	Active	10015655
EASA.IM.A.S.01632	E.J. MLYNARCZYK & CO. INC.		ST01519AT	BOEING DC-9-83 (MD-83) BOEING DC-9-82 (MD-82)	FAA STC ST01519ATInstallation of Dual Canadian Marconi Company CMA-900 Flight Management System		EJM Drawing List 40710010 Rev. G date 15th December 200AFMS40716029 Rev. B dated 21st February 2001Maintenance Advisory 40716031 dated 3 July 1997	Compatibility of this design with previously approved modifications must be determined by the installer.	31/07/2006	Active	10015656

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01633	WIPAIRE Inc.		FAA STC SA00674CH	CESSNA 172 SERIES	Installation of Wipaire Model 2100 Amphibian/Seaplane floats on Cessna/ Reims Aviation 172/F172 Models as defined in theAML.		Installation on accordance with Wipare Inc Installation Drawings as listed on the AML to this STC, at latest approved revision.The appropriate FAA approved Airplane Flight Manual Supplement required for all models with floats installed is contained in the Approved Model List (AML) to this STC, at la...	1. FAA Supplemental Type Certificate SA332GL is required for models 172I, 172J, 172K and 172L when installed in accordance with Wipaire Drawing 10D1-6012.2. FAA Supplemental Type Certificate SA332GL is optional for models 172M, 172N and 172P when installed in accordance with Wipaire Drawing 10D1-601...	21/06/2006	Active	10015657
EASA.IM.A.S.01635	AEROCON ENGINEERING COMPANY		FAA STC ST01825LA	A340-500	Installation of Cabin Interior Noise Reduction Kit in accordance with Aerocon Engineering Company's Master Document List No. AC25-340-1000 revision C dated August 18, 2005. Validation of FAA STC No. ST01825LA dated August 31, 2005				01/02/2006	Active	10015658
EASA.IM.A.S.01637	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST02763AT	BOEING 757-300 BOEING 757-200	Installation of an In-Flight Cabin Video Surveillance System		- Avionics Support Group Inc Master Drawing List 23485-MDL Revision IR dated October 11, 2003 or later approved revision.- Avionics Support Group Inc AFM Supplement reference 23485 Revision IR or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	16/03/2006	Active	10015660
EASA.IM.A.S.01638	JET AVIATION AG, BASEL	REV 1		FALCON 900	1. FMZ-2000 Software Upgrade;2. Application of Honeywell Service Bulletin No. 7018879-34-A6060.		1. Master Data List No. BF90034621 Rev. K or later approved versions;2. AFM Supplement DOC No BF90034621-201-01, Rev. A.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	22/08/2008	Active	10015661
EASA.IM.A.S.01641	ARC AVIONICS Corp.		FAA SA2890AT	SA26 SERIES, SA226 SERIES SA227 SERIES	Installation of a Honeywell Model CAS 67A Traffic Alert andCollision Avoidance System II (TCAS II) with Single Mode-S Transponder MST 67A iaw FAA STC SA02890AT.		¿ ARC-TCAS.001-CAW (Continued Airworthiness) ¿ ARC-TCAS.001-FMS (AFM Supplement)¿ FMS ASR 2006-041-05, Rev. A, COM 2 GND Clearance Function.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/09/2008	Active	10015665
EASA.IM.A.S.01642	RAISBECK ENGINEERING Inc.	REV 3	ST01468SE	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35	Installation of drag reduction system (including outboard trailing edge extension, leading edge vortilons & contoured flap).		1. Raisbeck Engineering Drawing Number 202L-5700 Revision Cdated March 4 2005 or later approved revision.2. Raisbeck Engineering AFM Supplement 204L-5780 Revision IR dated March 4 2005 or later approved revision.		21/08/2006	Active	10015666
EASA.IM.A.S.01643	TACA INTERNATIONAL AIRLINEST/A TECHNICAL AND TRAINING SERVICES(TTS)			AIRBUS A320-233	Equipment and furnishing - Delivery configuration of passenger cabin - 180 pax		Taca Engineering Order A320IN25-121/05, Revision 0, dated August 31, 2005.	This STC is Limited to the A320 MSN 558.	26/10/2005	Active	10015667
EASA.IM.A.S.01644	HARTZELL PROPELLER LLC		FAA STC SA01850CH	DIAMOND DA-40	Installation of Hartzell Two blade propeller HC-C2YR-1BF/F7495S with STC SA01850CH in the Diamond DA40 aeroplane		Hartzell engineering report No. 3085Installation Instruction DA40-NST-EASAFlight Manual Supplement DA40-AFMS-EASA	Diamond Modifications as detailed in the Installation instructions	30/09/2005	Active	10015668

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01645	S-TEC CORPORATION	REV 1	FAA STC SA09214AC-D	CESSNA 172S CESSNA 172R	Installation of S-TEC System 30 ALT Altitude Hold Sytem, Model ST-673, according to Bulletin No 773, Revision 4 dated 9-22-98 or later approved revision		- S-TEC Master Drawing List No 92991, Revision D dated 9-22-98 or later approved revisions- FAA/ DAS Approved Pilot's Operating Handbook and/or Airplane Flight Manual Supplement, P/N 891376, Revision 1, dated 9-25-98 or later approved revisions- Instructions for Continued Airworthiness, Part No 81232...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/09/2008	Active	10015669
EASA.IM.A.S.01647	AERO CONSULTING SERVICES LTD.	REV 1	TCCA STC C-LSA05-317/D ISSUE	BOMBARDIER CL-600-2B16	Aircraft Completion 12 Passenger Interior Configuration		-Transport Canada STC C-LSA05-317/D Issue 2-Aero ConsultingServices Modification Data Summary E611000 Revision A or later approved revision- Midcoast Aviation AFM Supplement 34-261M017 Revision N/C & 34-42M005 Revision N/C or later approved revision	1. Restricted to ASN 5620 only. 2. This STC is approved onlyfor the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	10/08/2006	Active	10015670
EASA.IM.A.S.01649	AERO CONSULTING SERVICES LTD.	REV 1	TCCA C-LSA05-315/D ISSUE 2	BOMBARDIER CL-600-2B16 (CL-604	Aircraft Completion 12 Passenger Interior Configuration		-Transport Canada STC C-LSA05-315/D Issue 2-Aeroconsulting Services Modification Data Summary E613000 Revision A or later approved revision- Midcoast Aviation AFM Supplemetn 34-261M017 Revision N/C & 34-42M005 Revision N/C or later approvedrevision	1. Restricted to ASN 5612 only2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	11/08/2006	Active	10015671
EASA.IM.A.S.01650	AVCON INDUSTRIES, Inc.		ST01195WI	24, 35, 36	Learjet 20 Series RVSMLearjet 35/36 Series RVSM		MDL 1078 Revision AGAFMS, Learjet Model 25D/F, Century III or Century III/Software WingAFMS, Learjet Model 24D, Dee Howard XR ModificationAFMS, Learjet Model 24EAFMS, Learjet Model 24D, Standard Wing with/without AMK 83-4AFMS, Learjet Model 25B/C, Mark II ModificationAFMS, Learjet Model 24D, ECR 151...	As detailed in the AFM	08/03/2007	Active	10015672
EASA.IM.A.S.01651	GULFSTREAM SERVICES CORPORATION		FAA STC ST03142AT-D	GULFSTREAM GV-SP	Aircraft Completion STC		FAA STC Number ST03142AT-D	1. Limited to S/N 50812. This STC is approved only for the product configuration as defined in the approved design datareferred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determinedby the installer.	06/12/2005	Active	10015673
EASA.IM.A.S.01654	BOMBARDIER AEROSPACE	REV 1	TCCA STC C-LSA06-025/D	BOMBARDIER CL-600-2B16	Aircraft Completion, 10 Passenger Interior.		Transport Canada STC C-LSA06-025/D Issue 2 dated August 31 2006 or later approved revision.Aero Consulting Services Modification Data Summary E689000 Revision A or later approved revision.Aero Consulting Services AFM Supplement E689090 Revision N/C or later approved revision.	1. Restricted to ASN 5613.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	26/10/2006	Active	10015674

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01656	BOMBARDIER AEROSPACE		FAA STC ST03065AT	LEARJET 31A	Installation of a Single Universal UNS-1C + or UNS-1E FlightManagement System		Bombardier Aerospace Master Document List BAS31017000 Revision B dated February 22 2005 or later approved revision.Bombardier Aerospace AFM Supplement ref. BAS31047000 Revision NCdated March 14 2005 or later approved revision.		04/01/2006	Active	10015675
EASA.IM.A.S.01657	BOMBARDIER AEROSPACE	REV 1	TCCA STC C-LSA06-023/D ISSUE 3	BOMBARDIER CL-600-2B16	Aircraft Completion, 10 Passenger Interior Configuration		- Transport Canada STC C-LSA06-023/D Issue 3 dated August 25, 2006- Aero Consulting Services Modification Data Summary E271000 Revision B or later approved revision.- Aero Consulting Services AFM Supplement E271090 Revision N/C orlater approved revision.	1. Restricted to ASN 5608	08/09/2006	Active	10015676
EASA.IM.A.S.01658	BOMBARDIER AEROSPACE	REV 1	TCCA STC C-LSA06-024/D ISSUE 2	BOMBARDIER CL-600-2B16	Aircraft Completion, 10 Passenger Interior Configuration		- Transport Canada STC C-LSA06-024/D Issue 2 dated August 3, 2006,- Aero Consulting Services Modification Data Summary E688000 Revision N/C or later approved revision,- Aero Consulting Services AFM Supplement E688090 Revision N/C or later approved revision.	1. Restricted to Aircraft Serial Number 5611.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	08/09/2006	Active	10015677
EASA.IM.A.S.01659	AERO CONSULTING SERVICES LTD.	REV 1	TCCA STC C-LSA05-328/D	BOMBARDIER CL-600-2B16	Aircraft Completion 12 Passenger Interior Configuration		Transport Canada Limited STC C-LSA05-328/D Issue 2 dated October 02 2006.Aero Consulting Servies Modification Data Summary E640000 Revision A or later approved revisionMidcoast Aviation Airplane Flight Supplement 34-424M005 Revision N/C and 34-261M017 Revision N/C or later approved revision	1. Limited to S/N 56172. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	27/10/2006	Active	10015678
EASA.IM.A.S.01660	ELECTRONIC CABLE SPECIALISTS, Inc.		ST01841CH	BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-100	Installation of GPS Antenna Provisions B747 Series in accordance with ST01841CH		Data package containing the following documents, and additional supporting data:1. Drawing 100-91347-1-NC Structural Provisions Installation GPS Antenna Left2. Drawing 100-91347-2-NC Structural Provisions Installation GPS Antenna Right3. ECS-201551-A Master Data List, B747 Seri...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph 5Documentation. Compatibility with other aircraft/engine configurations shall be determined by the installer.2. The Boeing 747SR is not included in the EASA STC.	31/07/2006	Active	10015679
EASA.IM.A.S.01661	ELECTRONIC CABLE SPECIALISTS, Inc.		ST01877CH	BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-200B BOEING 747-100	Installation of a Honeywell Ground proximity Warning Systemin accordance with FAA STC ST01877CH		See item 5 of Approval Report n°: P-LVT-0035-2005 / EASA.IM.A.S.01661 dated 28th March 2006.		19/05/2006	Active	10015680

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01663	JET AVIATION ST. LOUIS, Inc.		FAA STC ST00807WI	HAWKER 1000 BAE.125 SERIES 800A/B BAE.125 SERIES 1000A/B	Installation of Allied Signal MK-V Enhanced Ground Proximity Warning System (EGPWS)		In accordance with Midcoast Certification Drawing List No 26-327G001, Rev B, dated July 26, 1999, or later approved revisions.FAA Approved Midcoast Aircraft Flight Manual Supplement Document No 26-327M001, Rev "Original", dated July 29, 1999, or later approved revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	03/03/2006	Active	10015681
EASA.IM.A.S.01666	ELECTRONIC CABLE SPECIALISTS, Inc.		ST01923CH	LOCKHEED 1011-385-1-15 LOCKHEED 1011-385-1	Installation of a Honeywell Enhanced Ground Proximity Warning System in accordance with ST01923CH		Data package containing the following documents, and additional supporting data:1. Certification Plan L1011, Installation of Honeywell International EGPWS with Terrain Display on Lockheed L1011 Series Aircraft (configuration 1 upgrade),Electronic Cable Specialists Document ECS 204269, Revision N...	1. Airplane Flight Manual Supplement, Electronic Cable Specialists Doc. No. ECS-202314, Revision A, approved September 23, 2005, orlater FAA approved revisions, are required on board the aircraft.2. Airplane Flight Manual Supplement, Electronic Cable Specialists Doc. No. ECS-203895, Revision N/C, ap...	02/08/2006	Active	10015682
EASA.IM.A.S.01667	ELLIOTT AVIATION		FAA STC ST02007CH	BEECH MU-300-10 BEECH MU-300 BEECH 400	Certification for Reduced Vertical Separation Minimum (RVSM) operational capability and installation of Honeywell AZ-252 Air Data Computer and AM-250 Altimeter with optional BA-250 Altitude Indicator and AL-800 Altitude Preselector		- FAA STC ST02007C- Elliott Aviation Master Data List No. 2022-462DL Rev. 3 dated July 07, 2004 or later EASA approved Revisions- Airplane Flight Manual Supplement, Doc. No. FS2022-462 Rev. 1 dated July 20, 2004 or later EASA approved Revisions- Instruction for Continued Airworthiness CA2022-462 Rev...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.2. Certification basis: FAA TCDS A14SW for MU-300; FAA TCDS A16SW...	24/01/2006	Active	10015683
EASA.IM.A.S.01668	ELECTRONIC CABLE SPECIALISTS, Inc.		ST01887CH	MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (CF6) DC-9-81 (MD-81) DC-9-51 DC-9-32	Installation of GPS antenna provisions in accordance with FAA STC ST01887CH		Electronic Cable Specialists Master Data List ECS-202152 Rev A dated 3rd August 2004Instructions for Continued Airworthiness ECS Doc No ECS-202154 dated 9th January 2004	The equipment for which these provisions are intended has not been certified. Additional EASA approval is required for the installation of this equipment	13/03/2006	Active	10015684
EASA.IM.A.S.01670	HONEYWELL INTERNATIONAL INC.		FAA STC SA01116WI-D	PILATUS PC-12/45	Single or Dual Altimeters (FAA STC SA01116WI-D)		For Single Altimeter: PC-12, PC-12/45 only MDL No. 159-08290-0001 Rev. B, dated 18/10/2002For Dual Altimeter: PC-12, PC-12/451. MDL 159-08290-0003 Rev. B, dated 20/02/20042. AFMS No. 006-10318-0000, dated 20/02/2004For Dual Altimeters: PC-12/471. MDL No. 159-08290-0003 Rev. E. dated 26/01/20062. AFM...		15/05/2007	Active	10015685
EASA.IM.A.S.01671	HONEYWELL INTERNATIONAL INC.		FAA STC SA01253WI-D	PILATUS PC-12/45	RVSM (FAA STC SA01253WI-D issue dated 20/02/2007)		PC-12/45:MDL No. 159-08297-0001, Rev. A, dated 28/05/2004.AFMS No. 006-10319-0000, dated 31/08/2004.PC-12/47:MDL No. 159-08297-0001, Rev. E, dated 11/01/2006AFMS No. 006-10319-0000, Rev. D, dated 27/02/2006Later approved revisions to the above listed data are incorporated without revision to the FAA...	PC-12/45: MSN 101 to 835 (except MSN 545)PC-12/47: MSN 684 to 835	15/05/2007	Active	10015686

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01672	AMSAFE, INC.d/b/a AMSAFE AVIATION		SA01701LA	AVIATION AIRCRAFT A-1B AVIAT HUSKY A-1A AVIAT HUSKY A-1	Installation of Am-Safe Aviation Inflatable Restraint System on pilot and copilot seatsValidation of FAA STC SA01701LA Isuued December 06, 2004		- AMSAFE Master Data List E508584, Revision “NC”, dated October 29, 2004 or later approved version-Flight Manual Supplement E508590, Revision NC, dated September 9, 2004 or later approved revisions	The Electronic Module P/N 508358-409 and the Inflator Assembly P/N 508794-401 must be replaced every seven (7) years	30/11/2005	Active	10015687
EASA.IM.A.S.01673	GULFSTREAM AEROSPACE SERVICES CORP.d/b/a GULFSTREAM AEROSPACE CORPORATd/b/a GULFSTREAM		FAA STC ST02229CH-D	GULFSTREAM GIV-X	Installation of Corporate Aircraft Completion STC		In accordance with Gulfstream Aerospace Corporation Master Drawing List GC422046078, Revision A, dated February 28, 2006 or later approved revisionGulfstream Flight Manual Supplement ref GC42 204M021 Rev - dated 28 February 2006, or later approved revision	1. Aircraft Serial Number 4027 only2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	13/03/2006	Active	10015688
EASA.IM.A.S.01674	JET AVIATION AG, BASEL		-	GULFSTREAM IV	Installation of a L3 F2100 Solid State Flight Data Record (FDR) and Teledyne Mini Flight Data Acquisition Unit		Master Data List Doc. GAHHH009-001 Rev. B	1. Limited to Gulfstream IV (S/N. 1011 - A6-HHH)	15/11/2005	Active	10015689
EASA.IM.A.S.01677	BOMBARDIER AEROSPACE/ LEARJET INC		FAA STC ST03023AT	BD-700-1A10	Installation of a Lower Fuselage Canted Drain Mast Validation of FAA STC ST03023AT as Basic STC MDL: BAS67017009		FAA Statement of Compliance (SoC) dated Mar 17, 2006		06/04/2006	Active	10015690
EASA.IM.A.S.01679	ROCKWELL COLLINS, Inc.d/b/a AIR TRANSPORT SYSTEMS	REV. 1	ST02837AT	BOEING 737-900 BOEING 737-800 BOEING 737-700 BOEING 737-600	Installation of a Rockwell Collins CMU-900 Communications Management Unit, VHF-920 VDL Mode 2 Radio and the APM-900 Airplane Personality Module to provide Controller Pilot Data Link Communications (CPDLC) Baseline 1 services		Hollingsead International Master Data List 2755-01, Revision B, dated 27 April 2004, or later approved revision.	In accordance with the 2755-AFM Rev A, dated December 12, 2005, or later EASA approved Revisions.	31/07/2009	Active	10015691
EASA.IM.A.S.01681	ELLIOTT AVIATION		FAA STC ST01486CH	BEECH MU-300 BEECH 400	Installation of a Honeywell Mark VI/VIII EGPWS		FAA STC ST01486CHElliot Aviation Master Data List No. 2024-571DL Rev. 4 dated May 08, 2006 or later EASA approved RevisionsAirplane Flight Manual Supplement for Honeywell MK VI & VIII EGPWS, eport No. FS2024-571 Rev. 2 dated June 02, 2006 or later EASA Approved RevisionsAirplane Flight Manual Supple...	Validation Basis of the Change: FAR 25, additionally JAA Leaflet No. 12 (TAWS)	19/07/2006	Active	10015693
EASA.IM.A.S.01682	GULFSTREAM SERVICES CORPORATION		FAA STC ST03047AT-D	GULFSTREAM GIV-X	Installation of Airshow 4000 (Moving Map and In-Flight Information)		Gulfstream Aerospace Corporation Index List GC41 5048001, Revision D, dated March 14, 2005 or later approved revisions	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engineconfigurations shall be determined by the installer.	08/02/2006	Active	10015694
EASA.IM.A.S.01684	GULFSTREAM SERVICES CORPORATION		FAA STC ST02987AT-D	GULFSTREAM GIV-X	Installation of Interior Emergency Lights		Gulfstream Aerospace Corporation Index List GC41 4868000, Revision E dated March 14, 2005 or later approved revisions	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engineconfigurations shall be determined by the installer.	08/02/2006	Active	10015696
EASA.IM.A.S.01685	GULFSTREAM SERVICES CORPORATION		FAA STC ST02980AT-D	GULFSTREAM GIV-X	Installation of External Camera System (Securaplane)		Gulfstream Aerospace Corporation Index List GC41 5058000, Revision E, dated March 31, 2005 or later approved revisionsFAA approved Flight Manual Supplement, GC41505M003, Revision NC, dated April 1, 2005, or later approved revisions	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engineconfigurations shall be determined by the installer.	08/02/2006	Active	10015697

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01686	GULFSTREAM SERVICES CORPORATION		FAA STC ST02979AT-D	GULFSTREAM GIV-X	Installation of Passenger Oxygen System		Gulfstream Aerospace Corporation Index List GC41 4538000, Revision B dated March 07, 2005 or later approved revisionsFAA approved Flight Manual Supplement, GC41453M000, Revision NC, dated March 17, 2005 or later approved revisions	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	08/02/2006	Active	10015698
EASA.IM.A.S.01687	GULFSTREAM SERVICES CORPORATION		FAA STC ST02948AT-D	GULFSTREAM GIV-X	Installation of Cabin Window Shades		Gulfstream Aerospace Corporation Index List GC41 5068000, Revision C, dated March 14, 2005 or later approved revisionsFAA approved Flight Manual Supplement, GC41506M002, Revision NC, dated March 17, 2005 or later approved revisions	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	08/02/2006	Active	10015699
EASA.IM.A.S.01688	TRANSAIRCO S.A.		-	PC-12, PC-12/45	Structural installation of Honeywell KA-815 TCAS I Antennas		Engineering order TSA PC12-34.84.02EO		09/03/2006	Active	10015700
EASA.IM.A.S.01689	ELECTRONIC CABLE SPECIALISTS, Inc.	REV 1	FAA STC ST02184CH	MD-11 DC 10-30 SERIES DC-10-10 SERIES	Installation of elementary and enhanced surveillance Mode Stransponders In MD-11; MD-11F; DC-10-10; DC-10-15; DC10-30; DC 10-40; DC-10-10F; DC–10-30F; DC-10-40F in accordance with “Electronic Cables Specialists Master Data List ECS-203475”.		1. ECS-203482 Rev. N/C AFM Supplement for McDonnell Douglas MD-11 Series with Enhanced Mode-S Transponder Upgrade with flight IDfrom Transponder Control Panel. 2. ECS-204353 Rev. N/C AFM Supplement for Douglas DC-10 Series Airplane with Mode-S Transponder Upgrade for Elementary Surveillance wit...	1. ECS-203482 Rev. N/C AFM Supplement for McDonnell Douglas MD11 Series with Enhanced Mode-S Transponder Upgrade with Flight ID from Transponder Control Panel.2. ECS 204353 Rev N/C AFM Supplement for Douglas DC-10 Series Airplane with Mode-S Transponder Upgrade for Elementary Surveillance with...	27/11/2007	Active	10015701
EASA.IM.A.S.0169	M7 AEROSPACE L.L.C.	REV. 1		AEROSPATIALE ATR 72-212A AEROSPATIALE ATR 72-212 AEROSPATIALE ATR 72-211 AEROSPATIALE ATR 72-202 AEROSPATIALE ATR 72-201 AEROSPATIALE ATR 72-102 AEROSPATIALE ATR 72-101 AEROSPATIALE ATR 42-500 AEROSPATIALE ATR 42-320 AEROSPATIALE ATR 42-300 AEROSPATIALE ATR 42-200	Passenger to all cargo conversion of ATR-42/-72 series aircraft.ATR-42 is modified in accordance with Worldwide Aircraft Services Master Drawing List DL42-25-001 Rev G dated JAN 22, 2004.ATR-72 is modified in accordance with Worldwide Aircraft Services Master Drawing List DL42-25-001 Rev K dated Au...		AFMS ATR 42-LC dated JAN 23, 2004 for ATR 42 aircraft and AFMS 72-00001-017 Revision IR dated SEP 2, 2005 for ATR 72 aircraft. ICAWDocument Ref 72-00001-003 Revision A dated FEB 14, 2005 for ATR 72		24/11/2005	Active	10015702
EASA.IM.A.S.01690	TACA INTERNATIONAL AIRLINEST/A TECHNICAL AND TRAINING SERVICES(TTS)		-	AIRBUS A320-233	Autoflight - Activate FMGC Nav data base to 400Kwords - Pinprogramming		TACA Engineering Order A320MO22-007/02, revision 1, dated August 29, 2002	1. This STC is limited to the A320 MSN`s 558 and 561	04/11/2005	Active	10015703
EASA.IM.A.S.01691	GODERICH AIRCRAFT Inc.		-	BEECH B300	Artex ELT C406-N Installation.		Avionices Design Services Ltd. Master Drawing List MDL05096Revision N/C dated 16 September 2005 or later approved revision.Avionics Design Services Ltd. For Continued Airworthiness ICA05096-1 Revision N/C dated 15 September 2005 or later approved revision.	Modification limited to s/n FL-175.Maintenance must be in accordance with above Continued Airworthiness document	17/01/2006	Active	10015704

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01692	GODERICH AIRCRAFT Inc.			BEECH B300	Universal UNS 1E Flight Management System Installation.		Avionics Design Services Ltd. Master Drawing List MDL05097 Revision N/C dated 21 September 2005 or later approved revision.Avionics Design Services Ltd. For Continued Airworthiness ICA05097-1 Revision N/C dated 21 September 2005 or later approved revision.	Modification limited to s/n FL-175.Operation must bein accordance with Goderich Aircraft Inc. Flight Mnaual Supplement FMS05097-1 Revision N/C approved 20 September 2005 or later approved revision. Maintenance must be in accordance with above Continued Airworthiness document.	17/01/2006	Active	10015705
EASA.IM.A.S.01696	AVIONICS SUPPORT GROUP, Inc.		FAA STC ST03151AT	737 ALL MODELS	Installation of an Avionica, Inc. Secure LINK System for ground only operation		Avionics Support Group, Inc. Master Data List 25817-MDL, Rev. IR, dated 15th June 2005, or later approved revisions		17/01/2007	Active	10015706
EASA.IM.A.S.01698	JETPROP, LLC.		LBA STC SA1189	PIPER PA-46-350P PIPER PA-46-310P	Installation of the following engines, propellers and associated hardware:Pratt & whitney PT6A-34 engine limited to 560SHP at 2200 RPMPratt & Whitney PT6A-35 engine limited to 560 SHP at 2190 RPMPratt & Whitney PT6A-21 engine limited to 550 SHP at 2200 RPMHartzell HC-E4N-31/E8501B-3.5 propellerHart...		-Airplane Flight Manual Supplement for PA-46-310/350P (JetProp) Rev 7 or later approved revision-JetProp Maintenance Manual Doc No 560.1001, Change 2 or later approved revision-The instructions for the type are applicable as well	1. This STC is valid only in connection with FAA STC SA00859AT (EMZ 0721/1076) 2. This airplane/engine/ propeller combination is life limited. The life limit for the modified airplane shall be detrmined by usingthe minimum value calculated by the following formT = T0 + 0.9 (10145 - T0) Fuselage Life L...	26/10/2005	Active	10015707
EASA.IM.A.S.01701	STAR AVIATION, Inc.	REV 1	FAA STC ST02943AT	BOEING 777-300 BOEING 777-200	Installation of Connexion by Boeing Next Generation Antennaand Satellite Data SystemNote: This Revision reflects the transfer of this STC from Flight Structures, Inc. to Star Aviation, Inc.		- MDL: R44-0211, Revision AM, dated 20th June 2006 or later FAA approved revision,- AFM Supplements R44-0397, Revision B, dated 20th June 2006 for the -200 series or R44-0220, revision B, dated 20th June 2006for the -300 series, orlater FAA approved Revision	11. Airworthiness Limitations Section of the Instructionfor Continuous Airworthiness, document numbers R44-0403, revision B, dated 22nd July 2005 for -200 series, R44-0218, revsion B, dated 20th October 2004 for -300 series, or later FAA approved revisions2. Prior to installation of this modi...	05/09/2007	Active	10015708
EASA.IM.A.S.01702	B/E AEROSPACE, Inc. - FSI		FAA STC ST02944AT	B777-200, B777-300	Installation of Cabin Wireless Local Area Network (CWLAN) Distribution System		MDL: R44-0242, Revision Y, dated 19th April 2006 or later FAA approved revisionAFM Supplement: R44-0316, Revision D, dated 20th June 2006 or later FAA approved revision	Airworthines Limitations Section of the Instruction for Continuous Airworthiness, document numbers F44-0246, revision A, dated 20thOctober 2004 or R44-0406, revision IR, dated 23rd June 2005 or later FAA approved revisions	20/07/2006	Active	10015709
EASA.IM.A.S.01703	LEARJET Inc.		FAA STC ST01181WI-D	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35 LEARJET 31	Installation of Honeywell IHAS-800 Multi-Hazard Awareness System		"Learjet Master document List BAS35015037 Revision L or later approved revision-configuration	Learjet Master Document List BAS35015037 Revision l or later approved revision - configurations -2, -4 and -5 only	22/03/2006	Active	10015710
EASA.IM.A.S.01706	CASCADE AVIATION SERVICES INC.	REV 1	FAA STC ST01630SE	BOEING 737	Installation of Eybrow Window Deletion Kit.FAA STCST01630SE		Master Drawing List 05CAS469-MDL, revision A, dated December 8th, 2005, or later EASA approved revision	Compatibility of this design change with other previously approved modifications must be determined by the installer.	14/03/2007	Active	10015711
EASA.IM.A.S.01709	ELLIOTT AVIATION TECHNICAL PRODUCTSDEVELOPMENT INC		FAA STC ST00875WI	FALCON 10	ST00875WI: Installation of Universal TAWS with optionalUniversal MFD-640 and Allied Signal MKIVV EGPWSwith windshear		Master Data List MDL 2011-571DL Rev. 5 dtd. 2.Jan07--AFM supplement (AFMS) / Instructions for ContinuedAirworthiness (ICAW) as per MDL 2011-571DL:---AFMS FS2011-571, Rev. 1, dtd. 12.Oct 2006 orlater approved revision OR---AFMS FS2011-454, Rev. 1, dtd. 19.Sep 2002 orlater approved revision OR---AFMS FM...	Certification basis iaw CRI A1 IM.A.S.01709	13/02/2007	Active	10015712
EASA.IM.A.S.01710	FOKKER50FREIGHTER STC CORP.	REV 1	FAA STC STO1916LA - EASA.IM.A.	FOKKER F.27 MARK 050					21/05/2008	Active	10015714

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01711	FOKKER50FREIGHTER STC CORP.	REV 1	FAA STC ST00260DE	FOKKER F.27 MARK 050	Installation of Class E Cargo Interior, configuration 24B301-211 in accordance with Branson Aircraft Corporation Drawing List 24A300, revision B dated November 5, 1996, FAA approved November 7, 1996 or later revision approved in accordancewith ED Decision 2004/04/CF dated 10 December 2004.Also conf...		1. Cargo Loading Manual WB-2052 revision or later revisionapproved in accordance with ED Decision 2004/04/CF dated 10December 2004.2. FAA approved Airplane Flight Manual Supplement nr. FMS 232, dated October 30, 2006 or later revision approved in accordance withED Decision 2004/04/CF dated 10 Dec...	1. Cargo Loading Manual WB-2052 Rev. C or later approved revisions shall be used when loading the aircraft. 2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibi...	02/11/2007	Active	10015715
EASA.IM.A.S.01713	ELLIOTT AVIATION		ST02194CH	FALCON 10	ST02194CH: Installation of UNS EFI-890R EFIS		-MDL-2463-000 Rev. E dtd. 2.Jan 2007 or later approvedrevision--AFM supplement(AFMS) as per MDL-2463-000 Rev. E:---AFMSFMS-2651-004 Rev.A - <no date> or later approvedrevision OR---AFMS FMS-2463-000 Rev.B dtd. 1.Dec 2006 or laterapproved revision-Instructions for Continued Airworthiness ICA-2463-00...	Certification basis iaw CRI A1 IM.A.S.01713	13/02/2007	Active	10015716
EASA.IM.A.S.01715	EAD INC.	REV. 1	FAA STC ST03205AT	BOEING DC-9-82 (MD-82)	Installation of Rockwell Collins CMU-900 Communications Management Unit,VHF-920 VDL Mode 2 Radio, Gables Mode 2 VDR Control Panel and ACARS TP4429 Printer to provide Controller Pilot Data Link Communications(CPCDL) Baseline 1 service in accordance with EAD Aerospace Master DataList document number 0...		-EAD Aerospace Aircraft Flight Manual Supplement, Document No.01049-EAS-B-AFM-01 rev. B-FAA STC ST03205AT, reissued 27 January 2009.	None	31/07/2009	Active	10034640
EASA.IM.A.S.01716	TTF AEROSPACE, LLC		FAA STC ST00231BO	BOEING 737-800	Installation of Yokohama forward Lavatory E and Yokohama aft lavatory K and attendant seat in accordance with TTF Aerospace MDL TTF-05T026-01 Rev B, dated February 24, 2006		-TTF Aerospace MDL TTF-05T026-01 Rev B, dated February 24, 2006-Instruction for continued airworthiness (ICA), TTF Aerospace Document TTF-05T026-18 revision new, dated February 13, 2006 or later FAA accepted revision	Limited to installation on Boeing 737-800 S/N 28325, 30470,32277 and 32278 only.Installation of FAA STC 01533LA requiredInstruction for airworthiness 9ICA, TTF Aerospace DocumentTTF-05T026-18 revision new, dated February 13, 2006 or later FAA accepted revisionCompatibility of this design change wi...	06/04/2006	Active	10015718
EASA.IM.A.S.01717	B/E AEROSPACE, Inc. - FSI		FAA STC ST01729SE	B747-400	Business Class Seat Installation		Flight Structures Inc Master Drawing List A5FS513-D01 Revision D dated January 04 2007 or later approved revision.	Boeing Service Bulletin 747-25-3420 dated June 13 2006 mustbe installed concurrently with this STC.	17/01/2007	Active	10015719
EASA.IM.A.S.01720	ELLIOTT AVIATION		FAA STC ST01666CH	FALCON 10	ST01666CH: Installation of a Rockwell Collins TCAS 4000Traffic Alert and Collission Avoidance System (TCAS II)		'-MDL-2010-576DL Rev. 5 dtd. 20.October 2006 or later approvedrevision--AFM supplement(AFMS) / Instructions for ContinuedAirworthiness (ICAW) as per MDL-2010-576DL Rev. 5:---AFMS FMS-2651-002 Rev.B dtd. 20.Oct 2006 or later approvedrevisionOR---AFMS FS2010-576 Rev.1 - <no date> or later approved rev...	1. Certification basis iaw CRI A1 IM.A.S.01720 and TGL Nr. 8	13/02/2007	Active	10015721

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01724	JET AVIATION AG, BASEL		-	AIRBUS A320-232	Cabin Interior OutfittingSee Master Data List B3202403-001		Flight Manual Supplement B3202403201-01Instructions for Continued Airworthiness B3202403-150-01	1. Approval valid only for MSN 2403.2. The aircraft is certified for private use only, not to be operated for commercial air transport.3. The aircraft is a No Smoking aircraft.4. The W-LAN System is limited to Cabin W-LAN, wich is not interfaced to systems other than the SATCOM/HSD system...	06/09/2006	Active	10015722
EASA.IM.A.S.01731	RAYTHEON AIRCRAFT COMPANY		FAA STC SA8351SW	BAE 125-1000A	Installation of Brackets for Cabin Headliner, Window Panelsand Side Panels.		In accordance with Arkansas Aerospace Inc Drawing List 1000-016, dated 06/04/92, or later approved revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and "Associated Technical Documentation". Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	21/02/2007	Active	10015723
EASA.IM.A.S.01733	RAYTHEON AIRCRAFT COMPANY		FAA STC SA8411SW	BAE 125-1000A	Installation of Electronic Equipment Racks.		In accordance with Arkansas Aerospace Inc Drawing List 1000-020, dated 06/21/92, or later approved revisions.		21/02/2007	Active	10015724
EASA.IM.A.S.01737	ARMSTRONG AEROSPACE Inc.		ST02202CH	BOEING 757-200	Installation of Honeywell RESCU 406AF Emergency Locator Transmitter (ELT)		Armstrong Aerospace Master Data List Doc No. DC104-3078-00-Revision B dated November 09 2005 or later approved revision. ArmstrongAerospace AFM Supplement Doc No. DC303-3078-00 Revision - approved November 04 2005 or later approved revision.		26/01/2006	Active	10015725
EASA.IM.A.S.01741	BAYSYS TECHNOLOGIES, LLC		FAA STC ST01939LA	AIRBUS A319-133 AIRBUS A319-115	Direct TV - Installation of a tailwind 55 Satellite direct TV receive system		Master Data List (MDL), ref: 8050-ED-1067, revision L, dated November 20, 2006 or later approved revisions.Airplane Flight Manual Supplement (AFM-S), ref: 8050-AFMS, revision IR, dated November 20, 2006 or later approved revisions	1. Maximum Tekeoff Weight and Maximum Landing Weight shall be reduced as follows:Takeoff 350 lbs (159 Kg)Landing 410 lbs (186 Kg)2. For airplane(s) modified by this STC, prior to the accumulation of 9,200 total flight cycles from the STC modification, the following structural areas must be inspected...	23/11/2006	Active	10015726
EASA.IM.A.S.01748	JET AVIATION AG, BASEL			BOEING 737-700 IGW	Cabin Modification - Aft Lounge Modification - Replacement of IFE/CMS and Installation of Airshow 4000		Master Data List BVBRM024-001Operation Manual Supplement BVBRM024-202-01Instruction for Continued Airworthiness BVBRM024-150-01	Approval valid only for MSN 28976 with FAA STC No. ST09106AC-D installed	15/11/2006	Active	10015729
EASA.IM.A.S.01749	LEARJET Inc.		FAA STC ST00342DE-D	LEARJET 31A	Installation of Single Universal Avionics Corporation UNS-1C FMS		Learjet Inc Master Document List BAS31010008 Rev (-) dated March 5 1998 or later approved revisionAFM Supplement BAS31040105 Revision (-) dated March 5 1998 or later approved revision or Supplement BAS31040008 Revision (-) dated February 16 2000 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	02/01/2006	Active	10015730

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01752	PATS AIRCRAFT L.L.C.d/b/a PATS AIRCRAFT SYSTEMSd/b/a ALOFT AEROARCHITECTS		FAA STC NO. ST00365NY-D	CL-600-2B19	Installation of a two tank Auxiliary Fuel System.		-FAA STC No. ST00365NY-D dated 29 January 2007.- Configuration 3. Installation of structural provisions only, for a two(2) Cell Auxiliary Fuel System within the fuselage pressure vesselforward of the baggage compartment in accordance with PATS Aircraft,LLC. Master Drawing List No. RJA-1-002, Rev. A-...	1. PATS Aircraft, LLC Airplane Flight Manual Supplement No. 200, Rev. IRFAA approved January 5, 2007 is required with configuration 5.2. PATS, Inc. Aircraft Maintenance Manual Supplement No. 1, Report No.TO-417, Revision 3 dated May 23, 1995 or later approved revision, isrequired for continued airwo...	12/06/2007	Active	10042982
EASA.IM.A.S.01753	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		-	AIRBUS A320-200	Installation of Honeywell TCAS II system		Master Data List ref. ML-4075160, revision A, dated September 25, 1992 or later approved revisionAFM supplement ref. TCAS-APPS-0294 revision A or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/11/2005	Active	10015731
EASA.IM.A.S.01755	VENTURA AEROSPACE, Inc.	REV 1	FAA STC ST01806LA	BOEING 737-400	Installation of a 9g Cargo Barrier according to FAA STC ST01806LARevision to existing EASA STC EASA.IM.A.S.01755 (737-400 added).		- Master Data List “Boeing 737-200 / -300 9g Cargo Barrier Installation” Report No. 3168 Rev.E dated 21 June 2005 or later approvedrevision.- Instructions for Continued Airworthiness “Boeing 737 9g Cargo Barrier Installation” Report No. 2210, Rev. B dated 22 June 2005 orlater approved revision.- FAA...	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product. The installation of this modification by third person...	28/05/2008	Active	10015733
EASA.IM.A.S.01757	PIEDMONT HAWTHORNE AVIATION, L.L.C.		FAA STC ST301CH	500, 550, S550, 560	Validation of FAA STC ST301CH - Installation of a HoneywellCAS-67A Traffic Alert and Collision Avoidance System (TCAS II) in accordance with ElectroSonics Top Drawing ES550-100116-01, Rev G, dated January 14, 2004 or later approved revision		AFM supplement ES550-100116-101 Revision C (FAA approved) for STC ST301CH (AFMS E550-200156-18A) ElectroSonics drawings:ES500-200116, -156 and -316.Instructions for continued airworthiness: ICA ES550-200116-200A & ES550-200116-201ATechnical investigation is summarised in CRI P-EASA.IM.A.S.01757 whic...	NoteThis STC complies with requirements for Mode S elementary surveillance.Limitations & ConditionsAs on FAA STC	13/11/2006	Active	10015734
EASA.IM.A.S.01758	ROCKWELL COLLINS, Inc.		FAA STC SA5135NM	B737-800	Installation of Audio Video Entertainment System with Rockwell Collins System No. 1309667-100 and 1310244-001 accordingto FAA STC SA5135NMRemark: Only 1 EASA STC to be issued by Programmes Department to cover both applications (working hours information from Mr. Angulofor IM.A.S. 01758, all others f...		- Rockwell Collins Index List 062-0138-000, Revision “W”dated 19 January 2006 or later EASA approved Revision-Maintenance Instructions for Continued Airworthiness, Rockwell Collins document 070-4328-000	The limitations according to FAA STC SA5135NM apply.	17/08/2006	Active	10015735
EASA.IM.A.S.01760	ANCRA INTERNATIONAL LLC		FAA STC ST01899LA	BOEING 747-400 SERIES	Installation of Main Deck Cargo Loading System		Ancra International LLC Controlled Data List DL84400-10-2 Revision A dated April 28 2006 or later approved revision.	EASA STC EASA.IM.A.S.02040 must be installed in conjunctionwith this installation.	27/06/2006	Active	10015736
EASA.IM.A.S.01761	BOMBARDIER INC.			BOMBARDIER BD-100-1A10	Customised Interior Completion Aircraft 20071, in accordance with Aero Consulting Services Ltd. Modification Data Summary E725000 rev N/C or later approved revision		AFM Supplement E725090 rev N/N or later approved revision	1. S/N 20071	30/01/2006	Active	10015737
EASA.IM.A.S.01762	CONCORDE BATTERY CORPORATION		FAA STC ST00640LA	HAWKER 1000	Installation of Cocorde Battery Model No RG-380E/60K sealedlead acid batteries		In accordance with Master Drawing List No 20, Revision N/C dated March 10, 1998 or later approved revisions	--	06/04/2006	Active	10015738

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01763	ANCRA INTERNATIONAL LLC		ST01644LA	AIRBUS A300-600	EASA validation of FAA STC ST01644LA:revision C to Ancra Controlled Drawing List DL83690STC ST01644LA, cargo Loading Sytem,Project Number SA11805LA-T		the operating Instructions related to the cargo loading system P/N 83690-51 are described in ANCRA report 8928	This STC is only applicable on Airbus A300-600 aircraft converted to freighter in accordanace with EASA.A.S. 00387/FAA STC ST01431NYThe aircraft must be compliant with the instructions for continued airworthiness (see ANCRA reports 8967 revision A and 8284 revision B, or later approved revision)	07/04/2006	Active	10015739
EASA.IM.A.S.01764	NORTHWEST COMPOSITES		FAA STC ST00867SE	DC-9-83 DC-9-82	Stowage Bin ExtensionModification to overhead stowage bin located in the passenger cabin in order to extend the bins for aircraft originally equipped with Heath-Techna Interiors stowage bins.		- Master Drawing List A075000 rev. F dated 20th January 2006 or later approved revision.- Instruction for Continued Airwothiness 25-20-03 rev. 5 dated 3rd November 2005 or later approved revision.	1. Aircraft listed on Master Drawing List A075000 rev. Fdated 20th January or later approved revision.2. This approval of this change in type design applies to the above model aircraft only.3. This approval should not be extendedto other aircraft of this model on which other previously ap...	28/03/2006	Active	10015740
EASA.IM.A.S.01765	NORTHWEST COMPOSITES		FAA STC ST00868SE	DC-9-83 (MD-83) DC-9-82 (CF6)	Stowage Bin ExtensionModification to overhead stowage bin located in the passenger cabin in order to extend the bins for aircraft originally equipped with C&D Interiors stowage bins.FAA STC ST00868SE issue on 21st June 2001		- Master Drawing List A074000 rev. J dated 3rd November 2005 or later approved revision.- Instruction for Continued Airworthiness 25-20-02 rev. 5 dated 3rd November 2005 or later approved revision.	1. Aircraft listed on Master Drawing List A074000 rev. Jdated 3rd November 2005 or later approved revision.This approval of this change in type design applies to the above model aircraft only.This approval should not be extended to other aircaft of this model on which other previously approved m...	16/02/2006	Active	10015741
EASA.IM.A.S.01766	DUNCAN AVIATION, INC.		FAA STC SA00894WI	CESSNA 525	Installation of Honeywell CAS 67A TCAS II System on Cessna 525. FAA Approval of STC Nr. SA00894WI: 08 September 2000.			The call outs and their priority are to be confirmed as part of each installation.	26/01/2006	Active	10015742
EASA.IM.A.S.01767	BOMBARDIER AEROSPACE / LEARJET Inc.		FAA STC ST00393DE-D	LEARJET 31A	Installation of a Honeywell 440, 660 or 880 Radar System		1) Learjet Inc. Master Document List BAS31010014 Revision Bdated July 06, 2000 or later approved revision.2) AFM Supplement BAS31040109 Revision (-) dated October 06, 1999 or later approved revision.	None	20/01/2006	Active	10015743
EASA.IM.A.S.01768	BEECHCRAFT CORPORATION		FAA ST01331WI-D	HAWKER 800XP	Installation of Collins Integrated Flight Information System (IFIS 5000)and Pro Line 21 Radios		Collins Master Data List AAC-0360-001 Rev-, dated July 8, 2004, or laterapproved revision.Collins Airplane Flight Manual Supplement ref. AAC-0366-001 Rev-, datedJune 6, 2005, or later approved revision.Collins Maintenance Manual Supplementref. AAC-0367-001 Rev-, dated May2, 2005, or later approved...	1. Raytheon Aircraft Company Kit 149-3419-0001 is prerequisite prior toinstallation and approval of STC (EASA.IM.A.S.01768).2. Raytheon Aircraft Company Kit 149-3420-0001 is prerequisite prior toinstallation and approval of STC (EASA.IM.A.S.01768).3. This STC is approved only for the product configu...	26/01/2006	Active	10042983
EASA.IM.A.S.01774	VISIONSAFE LLC		FAA STC ST01012WI	BOMBARDIER CL-600-2B19 BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of Emergency Vision Assurance System (EVAS TM)		1) Midcoast MDL 34-416G001, Rev. B, or Vision Safe Corporation MDL 176, Rev. C or later FAA approved revisions2) AFMS to Canadair CL-600 AFM STC No ST01012WI3) FAA STC ST01012WI	1) Certification Basis: applicable requirements of a. r. TCDSs2) This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	22/12/2005	Active	10015744

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01776	HONEYWELL INTERNATIONAL INC.		FAA STC ST00491SE	BOEING MD-90-30 BOEING DC-9-87 (MD-87) BOEING DC-9-83 (MD-83) BOEING DC-9-82 (MD-82) BOEING DC-9-81 (MD-81)	FAA STC ST00491SE "Installation of the Enhanced Ground Proximity Warning System"		Master Drawing List 960-2227-007 Rev. AY dated 7 June 2005AFM as indicated in Master Drawing List 960-2227-007 Rev. AY dated 7 June 2005		05/03/2007	Active	10015745
EASA.IM.A.S.01778	AEROCON ENGINEERING COMPANY		FAA STC ST01086LA	JETSREAM 4100	Installation of Smoke Detection & Fire Suppression Systems for Conversion of Class D Cargo Compartments to Class C		Aerocon Engineering Master Data List AC26-4100 Revision B or later approved revision.Aerocon Engineering AFM Supplement26-4100-4101 dated December 8 2000 or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer	17/02/2006	Active	10015746
EASA.IM.A.S.01781	NATIONAL AIRCRAFT SERVICES, INC.		FAA STC ST01883CH	F4-605R F4-622R C4-605 VAR.F B4-603 B4-620 B4-605R B4-622R AIRBUS A310-304 AIRBUS A310-222 AIRBUS A310 AIRBUS A300 MODEL B4-2C AIRBUS A300 MODEL B4-103 AIRBUS A300 MODEL B2K-3C AIRBUS A300 MODEL B2-203 AIRBUS A300 MODEL B2-1C AIRBUS A300 MODEL B2-1A	EASA validation of FAA STC ST01883CHReinforced Flightdeck Door and Venting SystemInstallation of reinforced flightdeckdoor and venting system defined in Drawing List FDS-DL16, Revision M, dated August 26, 2003, or later FAA approved revisions, in accordance with Cockpit Door System Installation Ma...		The National Aircraft Service, Inc Airplane Flight Manual Supplement Number FDS-19-AFM, FAA apprved on September 15, 2003, or laterEASA Approvved Revisions, is required with this STC.	1. This flightdeck door modification has not been shown to provide smoke penetration and evacuation protection as required by 14 CFR 25.831. An EASA approved smoke barrier/curtain, installed behind the flightdeck bulkhead and in front of the cargo compartment, isrequired as part of the airplane type...	10/04/2006	Active	10015748
EASA.IM.A.S.01782	GULFSTREAM AEROSPACE Corp.	REV 2	FAA STC ST10301SC-D	GULFSTREAM 200	Installation of Executive Cabin Interior in accordance withIndex List GA222048001, Rev A, dated 3-23-2005 or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		Gulfstream Aerospace Index List GA222048001, or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).Approved Flight Manual Supplement GA21204M105, Rev. None, dated 3/23/2005 or later revisions of the...	Compatibility of this design change with previously approved modifications must be determined by the installer.	03/03/2008	Active	10015749
EASA.IM.A.S.01783	GULFSTREAM AEROSPACE Corp.		FAA STC ST10304SC-D	GULFSTREAM 200	Installation of Forward R/H Galley		Gulfstream Aerospace Index List GA2232880000, Rev. E, dated4/8/2005, or later FAA approved revision.FAA approved Flight Manual Supplement GA21328M000, Rev. None, dated 4/8/2005 or later FAA approved revision.	Compatibility of this design change with previously approved modifications must be determined by the installer.	14/03/2006	Active	10015750
EASA.IM.A.S.01784	GULFSTREAM AEROSPACE Corp.		FAA STC ST02847AT-D	GULFSTREAM 200	Installation of Safe Flight Instrument Corp Auto Power Automatic Throttle Control System		Gulfstream Aerospace Index List CEB14348000, Rev. B, dated 6/28/2004, or later FAA approved revision.FAA approved Flight Manual Supplement CEB1434M000, Rev. None, dated 7/2/2004 or later FAA approved revision.	Compatibility of this design change with previously approved modifications must be determined by the installer	14/03/2006	Active	10015751
EASA.IM.A.S.01785	JET AVIATION AG, BASEL		-	BOEING 737-800	Installation of modified customized seats		Flight Manual Supplement Doc No BBJ33473-201-06	1. Modification limited to Aircraft S/N 334732. This STC isapproved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	30/01/2006	Active	10015752

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01786	HAECO AIRFRAME SERVICES, LLC.		FAA STC ST03200AT	BOEING 737-800	Complete interior reconfiguration in accordance with TIMCO Aviation Services, Inc MDL, report 04T101L500, revision “D”,dated December 08, 2005, or later EASA approved revision		- MDL, report 04T101L500, revision "D", dated December 08, 2005.- TIMCO report 04T101R014, Instructions for Continued Airworthiness - Interior reconfiguration, Revision "IR", dated March 01, 2005, or later EASA approved revisions.		20/07/2006	Active	10015753
EASA.IM.A.S.01788	FIELD AVIATION EAST, LTD.	REV 1	SA05-67 ISSUE 1	BOMBARDIER DHC-8-315 BOMBARDIER DHC-8-311 BOMBARDIER DHC-8-103 BOMBARDIER DHC-8-102	Installation of ICARUS Sky Connect Tracker SOP and Satellite Communication System		- FAEL Master Drawing List DDL-1140 Rev. A or later Transport Canada approved revision.- FAEL Maintenance Manual Supplement MMS 20148 Revision IR or later Transport Canada accepted revision.	Thi sapproval is only applicable to the type/model of aeronautical product specified therein. Prior to incorporating thi smodification, the installer shall establish that the interrelationship between this change and any other modification(s) incorporated will not adversely affect the airworthiness...	04/08/2006	Active	10015755
EASA.IM.A.S.01790	HONEYWELL INTERNATIONAL INC.		ST01619SE	BOEING 747-400	Introduction of Honeywell International Inc. Main/Nose Wheel pn. 2615901-1 and Carbon Brake pn. 2615902-1 in accordancewith Honeywell Service Bulletin 2615901-32-001_2615902-32-001 Revision New or later FAA-approved revision as replacement for Goodrich Brake pn.2-1515-1 or 2-1515-2 and/or Wheel pn....		See item 5 of approval report (attachment)		22/03/2006	Active	10015756
EASA.IM.A.S.01791	ELLIOTT AVIATION		FAA STC SA02206CH	BEECH 300C BEECH 300 BEECH 200T BEECH 200CT BEECH 200C BEECH 200	Installation of Honeywell Digital Flight Data Recorder System (DFDR)		In accordance with LJSC Master Document List No. MDL5004-31290, Rev. H, dated November 7, 2005, or later approved revisions.FAA Approved Aircraft Flight Manual Supplement LJSC Doc. No. FMS5004-3129, Rev IR, dated November 3, 2005 or later approved revisions.Instructions for Continued Airworthiness L...	Limited to the aircraft types listed above with Proline 21 Avionics Suite installed.	03/03/2006	Active	10015757
EASA.IM.A.S.01793	ASSOCIATED AIR CENTER		FAA STC ST10546SC	AIRBUS A319-115	VIP Cabin modification		Master Document List (MDL), ref. 2350000000, revision A, dated June 8, 2006 or later EASA approved revision.Airplane Flight Manual Supplement (AFM-S), ref. 2350021090, revision IR, dated June 9, 2006 or later EASA approved revision.Instructions for Continued Airworthiness (ICAW), Chapter 3 "Airworth...	This STC is limited to the A319 CJ MSN 2592.Instructions for Continued Airworthiness (ICAW), Chapter 3 "Airworthiness Limitations" ref. 2350050090, revision A dated June 8, 2006 or later EASA approved revision.	13/06/2006	Active	10015758
EASA.IM.A.S.01795	LAKE CENTRAL AIR SERVICES		TCCA STC SA-05-71	LAKE LA 4/200	Horizontal Stabilizer Attachment Fitting P/N LC-2200-21 TCCA STC SA-05-71 issued on 8th July 2005		- Drawing LC-2200-21, Rev. 0, dated July 06, 2005.- Manufacturing Procedures MP-LC-2200-21, Rev. B, dated July 06, 2005, or later approved revisions.- Services Installation Instructions CI-LC-220-21, Rev. A. dated June 16, 2005, or later approved revisions.- Maintenance Manual Supplement MS-LC-2200-...	- Parts must be manufactured in accordance with Lake Central Air Services Drawing LC-2200-21, Rev. 0, dated July 06, 2005, and LakeCentral Air Services Manufacturing Procedures MP-LC-2200-21, Rev. B, dated July 06, 2005, or later approvedrevisions.- Installation must be performed in accordance wit...	18/04/2006	Active	10015759

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01796	NASCO AIRCRAFT BRAKE, INC.		FAA STC ST01833LA	BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200C BOEING 737-200	Installation of brake components listed on Nasco Aircraft Brake, Inc drawing 737101, Revision , dated August 11, 2005 for use in Goodrich brake assemblies 2-1474-3, -4, -5 and -7 in accordance with Nasco Configuration Control Dawing NCC007, Revision B, dated November 7, 2005 or later approved revisi...		see description	Limited to installation on BOEING 737-200, 200C, -300, -400, -500For use only in Goodrich brake assemblies 2-1474-3, -4, -5 and -7Continued Airworthiness Requirements included in the Goodrich Brake Overhaul Manual 32-40-30Compatibility of this design change with other previously approved modificatio...	31/05/2006	Active	10015760
EASA.IM.A.S.01797	ROCKWELL COLLINS Inc.		FAA STC ST01903LA	BOEING 777-200	Total Entertainment System.Index List 1304641 rev new dated2 August 2006.Modification comprises a software upgrade to the VMOD, re-identification of the VMOD and re-installation in the Video Control Centre.		FAA STC ST01903LA dated 9 August 2006IFE VMOD upgrade, ref Rockwell Collins System List 1310326-001 rev D.Continued Airworthiness Document, 130944 rev AF.	Limited to B777-200 models operated by British Airways plc.	19/01/2007	Active	10015761
EASA.IM.A.S.01798	WIGGINS AIRWAYS, INC.		FAA STC ST00052BO	RAYTHEON 1900D	Validation of FAA STC ST00052BO Incorporation of a RockwellCollins TCAS 94 System (TCAS II) with TTR-921 Change 7.0 R/T, dual TVI-920 TA/RA/VSI Indicators dual TDR-94D Mode S Transponders, CTL-92T TCAS Control and CTL-92 Transponder Control		Wiggins Airways, Inc. Engineering report No. 7065, Revision02 dated November 5, 2000, or later approved revisions.AFM:Wiggins Airways, Inc. Airplane Flight Manual Supplement ref. No 227 Revision 02, dated March 30, 2006 or later approvedrevision.Maintenance Manual: Rockwell Collins Manual for tra...	This STC does not comply with requirements for Mode S elementary surveillance or for Mode S enhanced surveillance.Compatibility of this design change with other previously approved modifications must be determined by the installer	05/04/2006	Active	10015762
EASA.IM.A.S.01803	DASSAULT FALCON JET CORPORATION		SA8279SW-D	FALCON 900EX	Installation of the Auxiliary Battery System		Drawing List Report No. F9EX-01008 Rev. G dated 12-21-2000 or later EASA approved Revisions. FAA approved Airplane Flight Manual Supplement 36500-1, Rev.B dated 2-4-00 or later EASA approved Revisions. Maintenance Manual Supplement 36520& 36606.		08/02/2006	Active	10015765
EASA.IM.A.S.01805	DASSAULT FALCON JET CORPORATION		FAA STC SA8303SW-D	FALCON 900EX	Installation of the Water System Modifications		Drawing List Report No. F9EX-01017 Rev. A dated 11-04-97 orlater EASA approved Revisions	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	08/02/2006	Active	10015766
EASA.IM.A.S.01806	DASSAULT FALCON JET CORPORATION		FAA STC SA8270SW-D	FALCON 900EX	Installation of the Miscellaneous Structures (General / Mechanical)		Drawing List Report No. F9EX-01020 Rev. A dated 01-10-90 orlater EASA approved Revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	08/02/2006	Active	10015767
EASA.IM.A.S.01807	DASSAULT FALCON JET CORPORATION		FAA STC SA8287SW-D	FALCON 900EX	Installation of the Equipment Rack		Drawing List Report No. F9EX-01018 Rev. A dated 02-19-97 orlater EASA approved Revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	08/02/2006	Active	10015768
EASA.IM.A.S.01808	JET AVIATION AG, BASEL		-	FALCON 2000	Cabin Reconfiguration		Flight Manual Supplement Doc. No BOCKN019-201-01	Modification limited to Aircraft S/N 076	09/02/2006	Active	10015769

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01809	SIMMONDS PRECISION PRODUCTS, Inc		FAA STC ST00043BO	BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200 BOEING 737-100	Installation of a Simmonds Precission 50203 series Fuel Quantity Harness in accordance with Simmonds Precision Installation Document N0 E-3203, dated May 24, 1995, or later approved revision		Simmonds Precision Installation Document N0 E-3203, dated May 24, 1995, or later approved revision	Compatibility of this design change with other previously approved modifications must be determined by the installer.	22/01/2007	Active	10015770
EASA.IM.A.S.01810	CHIPPEWA AEROSPACE, Inc.		ST03064AT	BAE JETSTREAM 4101	Installation of Honeywell MK VI Enhanced Ground Proximity Warning System (EGPWS)		Chippewa Aerospace Master Drawing List (MDL) J41-3443-0001 Revision IR dated July 29 2003 or later approved revision.Chippewa Aerospace AFM Supplement Document J41-3443-1012 Revision 1 dated May 22 2006 or later approved revision.		31/05/2006	Active	10015771
EASA.IM.A.S.01811	AIRCRAFT SYSTEMS AND MANUFACTURING,Inc.		FAA STC ST09580SC	BOEING 767-300 BOEING 767-200	Installation of Digital Flight Data Recorder (RFDR) Expanded ParameterUpgrade for Teledyne ARINC 717 DFDAU.		ASM Top Drawing List 5532-0001-00.		20/03/2006	Active	10015772
EASA.IM.A.S.01817	GULFSTREAM SERVICES CORPORATION		FAA STC ST03196AT-D	GULFSTREAM GV-SP	Completion and installation of the custom interior on Aircraft Serial 5094		In accordance with Gulfstream Aerospace Corporation Master Index List GC514915094, Revision E, dated March 31, 2006, orlater approved revisions.FAA approved Flight Manual Supplement, GC51501M014, Revision NC, dated March 31, 2006, or later approved revisions	Aircraft Serial 5094 Only	21/04/2006	Active	10015773
EASA.IM.A.S.01818	JET AVIATION AG, BASEL		-	AIRBUS A320-233 AIRBUS A320-232 AIRBUS A320-231 AIRBUS A320-214 AIRBUS A320-212 AIRBUS A320-211 AIRBUS A320-111	CAIR TM System Installation		Instructions for Continued Airworthiness BA32021701-150-01	The aircraft maximum number of passengers is reduced by 7 (seven) passengers.	30/08/2006	Active	10015774
EASA.IM.A.S.01821	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA01366WI	BEECH 1900C, 1900D	Installation of an ACSS T2CAS in Raytheon Aircraft (Beech) 1900C and 1900D		Master Drawing List, Report No. GEN-041115-002,Revision A, dated 24-May-2005, or later approved revisionAirplane FlightManual Supplement, Report No GEN-041115-020, Rev. “IR”, dated 21-Jul-2005, or later approved revisionInstructions for Continued Airworthiness, Report No. GEN-040311-016, Rev. B, da...	Installation must be done subsequent to or in conjunction with EASA STC EASA.IM.A.S. 00762 (FAA STC SA00560DE)	28/11/2006	Active	10015776
EASA.IM.A.S.01822	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA01366WI	RAYTHEON (BEECH) 1900D	Installation of an IS&S Air Data Display Unit on copilot side in Raytheon Aircraft (Beech) 1900D.		RAS Master Data List RAS1900E020, Rev. D, dated 31-Oct-2005, or later FAA approved revisionAirplane Flight Manual Supplement, RAS1900E022, Rev. -, or later approved revisionInstructions for Continued Airworthiness, RAS1900E024, Rev. B or later released revision.		20/10/2006	Active	10015777

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01823	DASSAULT FALCON JET CORPORATION		SA5611SW	MYSTERE FALCON 200	Installation of the Collins Dual EFIS-85EFIS-85 (Standard II) Instrument & Flight Director System of Collins Dual EFIS-86 Instrument & Flight Director System		Data package containing the following documents, and additional supporting data:1. Collins Dual EFIS Instrument and Flight Director System Drawing List, Falcon Jet Report F20-01010, Rev. E.2. FAA STC SA5611SW.3. Airplane Flight Manual Supplement for Collins Dual EFIS-85 (Standard II) Instru...	1. EASA Approved Airplane Flight Manual Supplement for Collins Dual EFIS-85 (Standard II) Instrument and Flight Director System, Falcon Jet Report 35402-1, Rev. B, or later EASA approved revision is a required part of this STC2. EASA Approved Airplane Flight Manual Supplement for CollinsDual EFIS-56...	02/08/2006	Active	10015778
EASA.IM.A.S.01825	JET AVIATION AG, BASEL		-	GULFSTREAM 1159 (G-II)	Weather Radar Installation		Declaration of Compliance Project BTAAI008Master Data List BTAAI008-001	--	05/05/2006	Active	10015779
EASA.IM.A.S.01826	A.A.E., LTD.	REV. 1	FAA ST01114WI	737-300, 737-400, 737-500	Installation of Smoke Detection and Fire Suppression System		AAE Ltd. Master Drawing List TFA10-0061, Revision H, dated 01 December 2005 or later approved revision.AFM Supplement ref. TFA09-0063, TFA09-0064, TFA09-0065, TFA09-0066 dated 20 November 2002, TFA09-0085, TFA09-0086 dated 29 June 2005, TFA09-0088, TFA09-0089, TFA09-0090 dated 16 December 2005 or l...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	26/11/2002	Active	10015780
EASA.IM.A.S.01827	BOMBARDIER INC.		TCCA LTD STC C-LSA06-132/D	BOMBARDIER BD-700-1A10	Customized Interior Completion ACSN 9173Validation of TCCA Limited STC C-LSA06-132/D to S/N 9173MDL: E776000 Rev. NC orlater TCCA approved revisionsTCCA SoC: C-06-316 dated June 30, 2006		FMS: G-FM25000138 Rev. NC or later TCCA approved revisionsIFCA: GC91730000-IFCA	Aerworthiness Limitations - Camera Sysem Electrical Receptacle Installation - FS806: G-TM05100073 Rev. NC or later TCCAapproved revisions	17/07/2006	Active	10015781
EASA.IM.A.S.01828	BOMBARDIER AEROSPACE		TCCA STC C-LSA06-032/D	BD-700-1A11	Aircraft Completion 12 Passenger Interior ConfigurationValidation of TCCA Limited STC C-LSA06-032/D to S/N 9174MDL: E764000 Rev NC or later TCCA approved revisions		FMS: G-FM25000137 Rev NC or later TCCA approved revisionsIFCA: GC91740001-IFCA	WLAN system is compatible only to IEEE 802 11(b)Use of IEEE802 11(b) compatible TPEDS for interaction with WLAN is subject to operational rules	28/04/2006	Active	10015782
EASA.IM.A.S.01839	S-TEC CORPORATION		FAA STC SA09522AC-D	BEECH E95 BEECH D95A BEECH B95A BEECH 95	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-898.		Installation according Bulletin No.998, dated 2-12-02 and Master Drawing List No. 921214, dated 2-12-02 or later FAA Approved revisions of the above data (28V System).	FAA/DAS Approved Pilot's Operating Handbook and / or FAA Approved Airplane Flight Manual Supplement P/N 892113 dated 2-18-02 or later approved revision, is required for Beech models 95 and B95.FAA/DAS Approved Pilot's Operating Handbook and / or FAA Approved Airplane Flight Manual Supplement P/N 892...	17/10/2006	Active	10015783
EASA.IM.A.S.01840	S-TEC CORPORATION		FAA STC SA8908SW-D	CESSNA 340A CESSNA 340 CESSNA 335	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-575		Installed in accordance with Bulletin No 675, Revision 3, dated 5-24-01 and Master Drawing List No 92752, Revision C, dated 5-24-01or later approved revision.Operation in accordance with FAA/DAS Pilot's Operating Handbook and/or Airplane Flight Manual Supplement P/N 891148, dated 2-24-95 is required...	Eligible to be used on aircraft 340 and 340A when modified per FAA STC SE4327SW (RAM Engine Conversion only if this STChas been EASA approved.	26/09/2006	Active	10015784

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01841	SKY INTERNATIONAL Inc.	REV 1	SA10463SC	AVIAT HUSKY A-1B	Installation of a Lycoming model IO-360-A1D6 engine (derated to 196 HP) and MT Propeller model MTV-15-B/205-58 propeller in accordance with Installation Instructions No 1101, Revision C dated 8 May 2006, or later approved revision		Master Data Drawing List No 1100, Revision C dated 12 May 2006, or later approved revisionInstallation Instructions No 1101, Revision C dated 8 May 2006, or later approved revisionAFMS No 55009-18, Revision IR, dated 8 May 2006, or later approved revision	The engine must be de-rated to 196 HP (see Installation Instructions for details).The Airplane Flight Manual SupplementNo 55009-18, Revision IR or later EASA approved revision, must be used with this modification.The approved Noise Level is 81.6 dB(A).	23/08/2006	Active	10015785
EASA.IM.A.S.01842	S-TEC CORPORATION	REV 1	FAA STC SA09000AC-D	VULCANAIR P68 C-TC VULCANAIR P68 C VULCANAIR P68 B	Installation of S-TEC System 55 two axis automatic flight guidance system, model ST-585, in accordance with FAA STC SA 09000AC-D		FAA/DAS approved POH/ AFM Supplement for Partenavia P68B, P68C and P68C-TC with S-TEC System 55 two axis automatic flight guidancesystem P/N 891160, Revision 1 or later FAA/DAS approved revisions	1. Also eligible on the above models with Camera Port2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	10/09/2008	Active	10015786
EASA.IM.A.S.01843	MASS SYSTEMS,A UNIT OF AMERON GLOBAL, INC.		FAA STC ST01708LA	SD3-60 SHERPA SD3-30 SD3-60 SD3-SHERPA	Installation of MASS Systems' fire extinguisher, P/N M57331-009, as a replacement for the Graviner fire extinguisher, P/N 57331-009in the above-noted airplane model. This fire extinguisher is in accordance with MASS Systems' Drawing No. M57331-009, "Fire Extinguisher, 52 cu-in", Revision B, dated No...		see above	The approval of this change in type design applies to the above-noted airplane model. This approval should not be extended to otherspecific airplanes of these model series on which other than noted previously approved modifications are incorporated, unless it isdetermined that the interrelationship...	16/04/2007	Active	10015787
EASA.IM.A.S.01844	LEARJET Inc.		FAA STC ST00508DE-D	BOMBARDIER CL-600-2B16	Installation of Collins PCD-3000 Data Loader Interface System		Learjet Inc Master Document List BAS63010085 Revision (-) dated January 22, 2002 or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	20/01/2006	Active	10015788
EASA.IM.A.S.01845	ARMSTRONG AEROSPACE Inc.		ST01797CH	AIRBUS A321 AIRBUS A320	Installation of a Honeywell RESCU 406 AF Emergency Locator Transmitter (ELT)		Master Data List (MDL), ref. DC104-1020-00, revision F, dated June 17, 2005 or later EASA approved revision.Airplane Flight Manual Supplement (AFM-S), ref. DC303-1020-00, revisionA, dated February 4, 2004 or later EASA approved revision.	Instructions for Continued Airworthiness (ICA), ref. DC113-1020-00, Section 2, revision D, dated June 17, 2005 or laterEASA approved revision	17/05/2006	Active	10015789
EASA.IM.A.S.01848	LEARJET Inc.		FAA STC ST8139NM-D	BOMBARDIER CL-600-2B16	Installation of a Collins VHF-22C Comm System with CTL-22C.		• FAA STC No. SA8139NM-D.• Learjet Inc. MDL No. BAS63010060, Revision J, dated 9 March 2000 or later approved revision.• Learjet Inc. AFM Supplement No. BAS63040111, Revision A, dated 3 July 1999 or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and "Associated Technical Documentation". Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	07/05/2007	Active	10015790
EASA.IM.A.S.01849	DECA AVIATION ENGINEERING Ltd.		TCCA LSTC O-LSA02-653/ D ISS 3	A318-112, A320-214	Passenger seat leather dress cover replacement		DECA Modification summary n° MS02136, revision 3, dated December 22, 2003 or later EASA approved revision	This STC is limited to: A319 MSN 1846, A319 MSN 1598 and A320 MSN 1686	12/05/2006	Active	10015791

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01851	O&N AIRCRAFT MODIFICATIONS, INC.		FAA STC SA615NE	CESSNA 172P CESSNA 172N CESSNA 172M CESSNA 172L CESSNA 172I CESSNA 172H CESSNA 172G CESSNA 172F	Installation of an 18 gallon fuel tank in the aft baggage compartment, and fuel transfer system.		- Installation in accordance with O & N Installation Drawing List 172100, Report No ON-1012, Revision A, dated June 1 1989, or later approved revision.- Eligible on aircraft serial numbers as identified on the Approved Flight Manual Supplements listed below:-- O & N Supplemental Flig...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	29/08/2006	Active	10015792
EASA.IM.A.S.01852	MASS SYSTEMS,A UNIT OF AMERON GLOBAL, INC.		FAA STC ST00952LA	SAAB 2000 LOCKHEED 1011-385-3 LOCKHEED 1011-385-1-15 BOEING MD-90 BOEING MD-88 BOEING DC-9-87 (MD-87) BOEING DC-9-83 (MD-83) BOEING 777-300 SERIES BOEING 767-300 SERIES AIRBUS A340-312 AIRBUS A340-311 AIRBUS A330-301 AIRBUS A300 MODEL B4-600 AIRBUS A300 MODEL B2K-3C AIRBUS A300 MODEL B2-203 AIRBUS A300 MODEL B2-1C AEROSPATIALE ATR 72-212A AEROSPATIALE ATR 72-212 AEROSPATIALE ATR 72-202 AEROSPATIALE ATR 72-201 AEROSPATIALE ATR 72-102 9.BOEING 747-400 SERIES 8.BOEING 737-200 SERIES 7.BOEING 717-200 6.AIRBUS A340-212 5.AIRBUS A340-211 4.AIRBUS A310-300 3.AIRBUS A310-200 2.AIRBUS A300 MODEL B2-1A 1.AEROSPATIALE ATR 72-101 15.LOCKHEED 1011-385-1 14.BOEING DC-9-81/82 13.BOEING DC-10-10 12.BOEING 777-200 11.BOEING 767-200 SERIES 10.BOEING 757-200 SERIES	Installation of MASS Systems fire extinguisher cartridges as replacement for Walter Kidde Aerospace fire extinguisher cartridge in fire extinguisher bottles		- FAA Approved Model List dated March 10, 2000, or later approved revisions - MASS System Hermetic Cartridges Kidde Master Drawing List No. 30980, Revision A, dated February 16, 2000, or later approved revision	The approval of this change in type design applies to the airplane models noted on the FAA Approved Model ListA copy ofthie STC must be included in the permanent records of the modified aircraft	04/10/2006	Active	10015793

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01853	MASS SYSTEMS,A UNIT OF AMERON GLOBAL, INC.		FAA STC ST00961LA	SIKORSKY S-76B CESSNA S550 CESSNA 560 XL CESSNA 560 CESSNA 550 CESSNA 425 CESSNA 421C CESSNA 421B CESSNA 421A CESSNA 421 CESSNA 414A CESSNA 414 CESSNA 411 CESSNA 402C CESSNA 402B CESSNA 402A CESSNA 401B CESSNA 401A BOMBARDIER CL-600-2B19 (SERIES BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600 BOEING DC-9-51 BOEING DC-9-41 BOEING DC-9-34F BOEING DC-9-34 BOEING DC-9-33F BOEING DC-9-32 BOEING DC-9-21 BOEING DC-9-15 BOEING DC-8-73F BOEING DC-8-73 BOEING DC-8-72 BOEING DC-8-71F BOEING DC-8-63F BOEING DC-8-63 BOEING DC-8-61F BOEING DC-8-61 BELL 412 EP BELL 412 CF BELL 412 BELL 212 BELL 205B BELL 205A-1 BELL 205A AEROSPATIALE ATR 72-212A AEROSPATIALE ATR 72-212 AEROSPATIALE ATR 72-211 AEROSPATIALE ATR 72-202 AEROSPATIALE ATR 72-201 AEROSPATIALE ATR 72-102 AEROSPATIALE ATR 72-101 AEROSPATIALE ATR 42-500 AEROSPATIALE ATR 42-320 AEROSPATIALE ATR 42-300 9.SIKORSKY S-76A 8.SAAB SF340A 7.EMBRAER EMB-120 6.CESSNA 500 5.CESSNA 401 4.BOEING DC-9-14 3.BOEING DC-8-71 2.BELL 204B 1.AEROSPATIALE ATR 42-200	Installation of MASS Systems Fire Extinguisher Cartridge asreplacement for Walter Kidde Aerospace fire extinguisher cartridges in fire extinguisher bottles installed in the airplane models noted on the EASA approved model list dtd 02 April 2008 (which excludes aircraft models not validated by EASA)...		These fire extinguiher cartridges are in accordance with the MAAS Systems Hermetic Cartridges Kidde Master Drawing ListNo. 30980-1"Slug Thrower Cartridges", Rev N/C, dtd 26 June 2000 or later FAA and EASA approved revisions.		08/04/2008	Active	10015794

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01854	MASS SYSTEMS,A UNIT OF AMERON GLOBAL, INC.		FAA STC ST00885LA	DATED 24/01/2007 AS PER APPROVED MODEL LIST	Installation of Mass Systems, Inc. fire extinguisher cartridges as replacements for Pacific Scientific fire extinguisher cartridgesin fire extinguisher bottles installed in the airplane models noted on the EASA Approved Model List dated 24th January.		Mass Systems Hermetic Catridges Master Drawing List No. 30989, Revision B, dated 16th November 1999	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	24/01/2007	Active	10015795
EASA.IM.A.S.01855	LEARJET Inc.		FAA STC ST01717LA-D	BOMBARDIER BD-100-1A10 (CHALLE	installation of a lavatory Seat Modification - Belt replacement,in accordance with Master Drawing List BAS68010002, revC		Maintenance Instructions for Continued Airworthienss ref BAS68010002-IFCA-1	Certification basis: a deviation from 25.789(b) has been granted for personal injury criteria testing of side singlw occupancy seats (Learjet CRI D-3)	07/04/2006	Active	10015796
EASA.IM.A.S.01858	OFEK HOLDING CORPORATION		FAA STC SA01415CH	PIPER PA-31T	Installation of camera provisions in fuselage floor cut-out		CAA-NL report Nr. LTB/ TCP/06.531118	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	30/01/2006	Active	10015797
EASA.IM.A.S.01859	OFEK HOLDING CORPORATION		FAA STC SA01961CH	PIPER PA-31T	Installation OFEK Holding Company camera provisions installed pursuant to STC SA01962CH		CAA-NL report Nr. LTB/ TCP/06.531118		30/01/2006	Active	10015798
EASA.IM.A.S.01863	ELECTRONIC CABLE SPECIALISTS, Inc.	REV 1	FAA STC ST02007LA	BOEING 767-300 SERIES	Installation of Honeywell MCS-6000 SATCOM System		FAA STC ST1193LA-T dated 2 March 2007Master Data List ECS-203976 Revision BFlight Manual Supplement ECS-203980	This installation must be installed in conjunction with Honeywell STC EASA.IM.A.S. 02276 for the installation of the SATCOM High-Gain Antenna and Diplexer / Low Noise Amplifier (D/LNA).	08/03/2007	Active	10015799
EASA.IM.A.S.01864	DELTA AIR LINES, INC		SA3305SO	BOEING 767-200	Installation of a Delta modified forward trunnion bearing housing & a Delta manufactured bearing retainer bolt to allowforced lubrication of the respective joints.		Delta E.O. 1-65641-3 dated August 08 1992 or later approvedrevision.		01/06/2006	Active	10015800
EASA.IM.A.S.01866	S-TEC CORPORATION		FAA STC SA09527AC-D	TWIN COMMANDER AIRCRAFT 690B TWIN COMMANDER AIRCRAFT 690A TWIN COMMANDER AIRCRAFT 690	Installation of S-TEC Digital Flight Control System (autopilot) Part Numbers 01284 or 01298-01-01-002 or 01-304-04-01-008, (MAGIC 2100) (ST-902) in Twin Commander 690, 690A and 690B, also if modified by any of the following STC’s: STC SA236CH (Garrett TPE 331-10T-515 engines), STC SA3861NM ("Q" tip...		Master Data List No. 921219, Rev. B or later FAA approved revision,Installation Instructions ST-902-1, Rev. C, or laterreleased revisionFAA/DAS approved Airplane Flight Manual Supplement No. 89123, Rev. 3, or later approved revisionInstructions for Continued Airworthiness, Doc. No. 81659, Rev. B, o...	If airplane is modified by STC SA236CH (Garrett TPE 331-10T-515 engines), STC SA3861NM ("Q" tip propellers), or STC SA1359GL (winglets), installer must check availability of EASA-approval.	20/10/2006	Active	10015801
EASA.IM.A.S.01867	S-TEC CORPORATION	REV. 1	FAA STC SA09007AC-D	CESSNA 182Q CESSNA 182P	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System Model ST-587.		In accordance with Bulletin No 687, Revision 2, dated 2-15-01 and Master Drawing List No 92785, Revision B, dated 2-15-01 or later approved revisions.FAA/DAS Approved Supplement Flight Manual, Part No 891171, dated 6-01-95 is required for Cessna Models 182P and 182Q, Serial Numbers 18266590 and belo...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/09/2008	Active	10015802

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01868	AIRCRAFT SAFETY EQUIPMENT		SA3278SO	MD-11, MD-11F DC-10-10/-30/-30F	Smoke Barrier Cargo Copmartment McDonnell-Douglas (Boeing) MD-11F, aircraft serial no. 48445.Installation of a modifiedberrier in the Class "E" cargo compartment in accordance with FAA STC SA3278SO, reissued on September 24, 2004		1. Aircraft Safety Equipment, Memphis, TN. Compliance Checklist, Smoke Curtain MD-11 (no date);2. Aircraft Safety Equipment, Memphis, TN. Cargo Compartment Smoke Barrier Smoke Penetration Test Procedure 91250001, dated 31-01-1992;3. Ship Shape Custom Products, Mooresville, NC. Flammability Test Repo...	1. The Aircraft Flight Manual should be amended in order tomake sure that before each flight:(a) the integrity of the smoke barrier is checked:(1) the smoke barrier should be without any tears(2) the OEM crown area smoke barrier should bewithout any tears;(3) all gaps around the smoke barrier shou...	14/11/2006	Active	10015803
EASA.IM.A.S.01869	S-TEC CORPORATION		FAA STC SA09008AC-D	CESSNA F182-Q CESSNA F182-P	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System Model ST-587.		In accordance with Bulletin No. 687 Revision 2, dated 2-15-01 and Master Drawing List No. 92785, Revision B, dated 2-15-01 or laterapproved revisions.FAA/DAS approved Supplement Flight Manual, Part No. 891173, dated 6-01-95 is required forReims Cessna Models F182P and F182Q.FAA/DAS approved Supplem...		26/04/2006	Active	10015804
EASA.IM.A.S.01870	HONEYWELL INTERNATIONAL INC.		FAA STC ST00705SE	BOEING 747-SP BOEING 747-300 BOEING 747-100F BOEING 747-100	Installation of Honeywell Enhanced Ground Proximity WarningSystem (EGPWS).		Master drawing 060-4199-094, revision BF, dated 13-11-2006 or later revisions of the above listed documents approved byEASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		06/09/2007	Active	10015805
EASA.IM.A.S.01871	HONEYWELL INTERNATIONAL INC.		FAA STC ST00140AT	AIRBUS A310-300 AIRBUS A310-200	Installation of MUA-45 Data Link System in Airbus A310-200 / -300 series aircraft.		Master Drawing List, ref: 699-50053, Revision B, dated 05 September 1995.		12/04/2007	Active	10015806
EASA.IM.A.S.01874	HONEYWELL INTERNATIONAL INC.		FAA STC ST00440SE	A310-200, A310-300 A300F4-600 A300B4-200, A300B4-600 A300B2K-3C, A300B4-2C	Installation of Honeywell EGPWS on Airbus A300/A310/A300-600 aircraftmodels.This STC installs a Honeywell Enhanced Ground Proximity Warning System(EGPWS).		-Master Drawing List, ref: 960-2227-005, Revision AE, dated11 October2005 (or any later EASA approved revision).-Aircraft Flight Manual Supplement listed for the installation.-Instruction for Continued Airworthiness listed for the installation.	1. Limitations on the STC EASA.IM.A.S.01874 are the ones defined throughthe original FAA STC ST0440SE, at its latest amendment dated 27 May 2004(or any later EASA approved revision).2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the pa...	24/05/2007	Active	10042984
EASA.IM.A.S.01875	MCCAULEY PROPELLER SYSTEMS		FAA STC SA00798CH	CESSNA FR-182	Installation of a McCauley Propeller Model B3D36C431/80VSA-1 or B3D36C433/80VSA-1, and spinner assembly.		In accordance with McCauley Technical Report No 873, no revision, dated June 26, 1997, and McCauley Drawing No D-60202,no revision, dated July10, 1997, or later approved revisions.	FAA Approved Flight Manual Supplement, Technical Report Number 874, dated August 4, 1997, or later approved revision required.Lycoming engine model O-540-J3C5D is eligible with the McCauley Propeller Model B3D36C433/80VSA-1 (S/N FR18200001through FR18200045) with a maximum continuous and take off r...	08/06/2006	Active	10015807
EASA.IM.A.S.01876	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02050CH-D	GIV-X	Installation of Class B Baggage Compartment.		In accordance with Gulfstream Aerospace Corporation MasterDrawing ListGC425046085, Revision B, dated June 10, 2005, or later approvedrevisions.Gulfstream Flight Manual Supplement ref GC42 504M000 Rev - dated 10June, 2005, or later approved revisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	17/03/2006	Active	10042985

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01877	WORLDWIDE AIRCRAFT SERVICES Inc.D/ B/A WORLDWIDE AIRCRAFT SERVICES		FAA STC ST00798WI	FAIRCHILD SWEARINGEN SA 227-DC FAIRCHILD SWEARINGEN SA 227-CC FAIRCHILD SWEARINGEN SA 227-BC FAIRCHILD SWEARINGEN SA 227-AT FAIRCHILD SWEARINGEN SA 227-AC	Installation of Fairchild Digital Flight Data Recorder F800or F1000 in Fairchild aircraft SA227-AT, -AC, BC, CC, DC inaccordance with Worldwide Aircraft Services Certification Drawing list No; DL227-31-06 Revision A, dated May 14, 1999 or later approved revision.		Worldwide Aircraft Services Certification Drawing List No? DL227-31-06 Revision A, dated May 14, 1999 or later approvedrevision.FAA approved worldwide Aircraft Services Airplane Flight Manual Supplement, dated June 8, 1999, or later approved revision.	The FAA approved Airplane Flight Manual Supplement must be on board the aircraft at all times.This STC is approved onlyfor the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be de...	02/11/2007	Active	10015808
EASA.IM.A.S.01878	SHOWA AIRCRAFT USA INC		ST01621SE	BOEING 747-400	Installation of an Upper Deck Galley on Boeing		Data package containing the following documents, and additional supporting data:1. Drawing List (60305-DL04 Rev A)2. 8110-3 FAA Approvals GAP Galley Inst. B747-4003. FAAconcurrance letter for DF110 oven4. Elec. Load Summary Report (60305-EL04-1 Rev. New)5. FAA Approved Cert Plan GAP...		18/12/2006	Active	10015809
EASA.IM.A.S.01879	KEITH PRODUCTS, L.P.		FAA STC NO ST09494SC	CESSNA T182T CESSNA 182T CESSNA 182S	Installation of an R134a vapour cycle air-conditioning system		Install in accordance with Keith Products L.P. Approved Flight Manual Supplement (Certification Report) Ref No CR-182-9, Revision E, dated August 30, 2005 or later approved revisionOperate in accordance with Keith Products L.P. Approved Flight Manual Supplement (Certification Report) Ref No CR-182-9...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/04/2006	Active	10015810
EASA.IM.A.S.01880	AIR COMM CORPORATION L.L.C		FAA STC SA10144SC	206H, T206H	Installation of an engine driven vapour cycle air-conditioning system		Install in accordance with Keith Products L.P. Master Document List Report Number DL-26-0100, Revision C, dated June 02, 2003 or later approved revisionOperate in accordance with Keith Products L.P. Approved Flight Manual Supplement (Certification Report) Ref No CR-26-9, Revision NC, dated June 20,M...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/04/2006	Active	10015811
EASA.IM.A.S.01881	BOMBARDIER AEROSPACE		TCCA STC SA06-2	BD-700-1A10	Main Entry Door Handrail ModificationValidation of TCCA STCSA06-2MDL: BAS67010036 REV NC or later TCCA approved revisionsTCCA SoC: C-05-1053 SA06-2 dated January 23, 2006		IFCA: MMS387201 IR or later TCCA approved revisions	--	23/01/2007	Active	10015812
EASA.IM.A.S.01882	THE GOODYEAR TIRE & RUBBER COMPANY		FAA STC ST03183AT	2. AIRBUS A340 1. AIRBUS A330	Installation of Goodyear Radial Tire Size 1050x395R16, P/N 109Q89 1 on Airbus A330 and A340 Nose Landing Gear accordingto FAA STC ST03183AT		- FAA STC ST03183AT, dated 26 October 2005,- GoodyearSB, Ref. 2005-32-002 dated 8 June 2005,- Goodyear SB, Ref. 2005-32-003 dated 8 June 2005		19/09/2006	Active	10015813

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01884	LANDMARK AVIATION		SA00987CH	CESSNA 525	Installation of an Allied Signal two tube EFIS-50 on Co-pilot's panel with Honeywell FZ500 Flight Director in accordance with ElectroSonics Drawing No. ES525-720250-01, Revision 1, dated February 2, 1999 or later FAA approved revision.		see above	1. Compatibility of this design change with previously approved modifications must be determined by the installer.2. The aircraft must be maintained in accordance wit FAA ApprovedMaintenance Manual Supplement, document number ES525-720250-200, Initial Release, dated February 02, 1999, or later FAA3...	05/10/2006	Active	10015814
EASA.IM.A.S.01887	BOMBARDIER AEROSPACE		TCCA STC C-LSA06-178/D	BOMBARDIER CL-600-2B16 (CL-604	Aircraft Completion		Aero Consulting Services Modification Sata Summery E921000 Revision N/C or later approved revisionAero Consulting Services AFM supplement E021090 Revision N/C or later approved revision	--	27/06/2006	Active	10015816
EASA.IM.A.S.01888	LEARJET Inc.	REV. 1	FAA ST00203BO	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	EGPWS Software Upgrade Installation of Cockpit Speaker Mute		FAA SOC dated 06 May 2008 and Bombardier Aerospace BusinessAviation Services Master Document List, document number BAS87017015, Revision F, dated May 04, 2007 or later approved revision.	1.The approval for the Master Document List -1 configuration, EGPWS Software Upgrade (-218-218 Software), is contingent on the aircraft being equipped with a previously EASA approved installation of a MK V Honeywell EGPWS with Version -206-206 Software or later approved version.2.The approval for t...	03/06/2008	Active	10015817
EASA.IM.A.S.01889	AIRWORKS		FAA STC ST01576LA	146/AVRO 146 SERIES	Installation of Airworks Cockpit Door Surveillance Systems		FAA STC ST01576LA.AirWorks Index List Document No. IL23003 Revision A dated 15 2004 or later approved revision.AirWorksAFM Supplemet Document No. AFM230017 Revision Original dated January 6 2004 or later approved revision.		04/01/2007	Active	10015818
EASA.IM.A.S.01891	AMSAFE, Inc.		FAA STC ST01866LA	JETSTREAM 4100 SERIES	Installation of AMSAFE Aviation Inflatable Restraint (AAIR)System on Front Row Passenger Seats of the Jetstream 4100 Series		AMSAFE Master Data List E509050 Revision NC dated January 42006 or later approved revision.	Not valid for Jetstream Model 4124	17/05/2006	Active	10015819
EASA.IM.A.S.01892	AEROMECH Inc.		ST01413SE	HAWKER HS 125-700B HAWKER HS 125-700A	Approval of Reduced Vertical Separation Minimum (RVSM).		In accordance with AeroMech Document No AMI-QD-H700-0010 Rev C, dated December 7, 2005, or later approved revisions.Operation to be in accordance with AeroMech Airplane Flight Manual Supplement ref AMI-AFMS-H700-0417 Rev A, dated, May 16,2005, or later approved revisions.	1. Only applicable to Aircraft Serial 257037.2. This STC must be installed after Avionics Mobile STC ref AM/1518. The installation is to be completed by the embodiment of AvionicsMobile Minor change AM/1532 installation of RVSM ADM's.	17/10/2006	Active	10015820
EASA.IM.A.S.01893	GULFSTREAM SERVICES CORPORATION		FAA STC ST01519LA-D	GULFSTREAM GV-SP	Completion and installation of the custom interior on Aircraft Serial No 5040		In accordance with Gulfstream Aerospace Corporation Master Index List GC520008421, Revision E, dated February 11, 2005,or later approved revisions.FAA approved Flight Manual Supplement, GC51 605M005, Revision NC, dated October 26, 2004, or later approved revisions.	Aircraft Serial 5040 Only	24/08/2006	Active	10015821

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01894	COLUMBIA AVIONICS INC.D/ B/A COLUMBIA AVIONICS & AIRCRAFTSERVI CES, Inc.		ST01128	BEECH B300C BEECH B300 BEECH B200T BEECH B200CT BEECH B200 BEECH 300LW BEECH 300 BEECH 200T BEECH 200CT BEECH 200C BEECH 200	Installation of Honeywell MK-VIII Enhanced Ground ProximityWarning System (with or without optional EFIS-85B/14 Display).		Installed in accordance with Columbia Avionics Inc Master Document List No 30141005, Revision 2, dated December 30, 2002, or later approved revisions.Operation in accordance with FAA approved Flight Manual Supplement 30141020, dated January 8, 2003 or later approved revision.		28/09/2006	Active	10015822
EASA.IM.A.S.01896	KELOWNA FLIGHTCRAFT Ltd.		SA04-32	BOMBARDIER CL-215-6B11	TCCA STC SA04-32 issue 3SPZ-4500 Honeywell AFCS and Universal UNS 1K/ 1L FMS		- MDL K 16-00002- AFMS K126-102-014.1A, K126-102-014.2A andK126-102-014.3A		17/07/2006	Active	10015824
EASA.IM.A.S.01897	NORTHROP GRUMMAN GUIDANCE ANDELECTRONIC SYSTEMS COMPANY, Inc.	REV 1	FAA STC SA8027NM	B747-287	Replacement of old inertial navigation equipment with newertechnology		1. Top Installation Drawing LTN-92 INS in B747-287B, Litton Document 454065-09, Rev. N/C.2. Engineering Authorization, Litton Document 464428, Rev. N/ C.3. Flight Manual Supplement to Boeing B747-200 Series Airplane, Litton Document 464427, Rev. N/C.4. FAA Supplemental Type Certificate SA...	Litton Airplane Flight Manual Supplement, Doc No 464427, N/C, FAA approved on August 8, 1994, or later approved revisions, is required as part of this modificationThis STC is approved only for the Boeing 747-287 model airplanes, and it applies only when three (3) Litton LTN-92 INSs have been used to...	28/11/2006	Active	10015825
EASA.IM.A.S.01904	DUNCAN AVIATION, INC.		ST00932WI	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35 LEARJET 31	Installation of Universal Avionics TAWS		Duncan Aviation Document List 10055100 Revision A dated December 14, 2000 or later approved revision.Duncan Aviation AFM Supplement 40010400 dated December 18, 2000 or later approved revision.	None	11/05/2006	Active	10015826
EASA.IM.A.S.01916	S-TEC CORPORATION		FAA STC SA5125SW-D	PIPER PA-28R-201T PIPER PA-28R-201 PIPER PA-28R-200 PIPER PA-28R-180	Installation of S-TEC System 60 Two Axis Automatic Flight Guidance System, Model ST-137, with Optional Autotrim System.		Bulletin No. 237, Rev. 2 or later approved revision,Master Drawing List No. 92160, Rev. B, dated 6-04-90, or later approved revisionAFM-Supplements as mentioned below Instructionsfor Continued Airworthiness, P/ N 81217, Rev. 1 or later	1. FAA Approved Supplement to Pilot's Operating Handbook and / or FAA Approved Airplane Flight Manual, P/N 89176-1, dated 06-21-90,or later approved revision, is required for Piper Models PA-28R-201 and PA-28R-201T.2. FAA Approved Supplement to Pilot's Operating Handbook and / or FAA Approved Airpla...	11/10/2006	Active	10015827
EASA.IM.A.S.01918	UNIVERSAL AVIONICS SYSTEMSCORPO RATION		FAA STC ST00839LA	BOMBARDIER DHC-8-100 SERIES	Installation of GPS Landing System in deHavilland DHC-8 aircraft(Validation of FAA STC ST00839LA amended 27/02/2006)		Master Drawing list MDL-2005-1002 Rev CAircraft Flight Manual Supplement AMFS-2005-1002 Rev IR	The approval is limited to Bombardier/deHavilland DHC-8 100series aircraft	14/07/2006	Active	10015829
EASA.IM.A.S.01919	DECA AVIATION ENGINEERING LIMITED	REV 2	TCCA LSTC O-LSA06-056/ D ISS1	DHC-6-300	Installation of an ASIRAS Radar System in a DHC-6-300 aircraft in accordance with Modification Summary for ASIRIS RadarSystem Installation, DECA Aviation Engineering Limited document DCP 05259, Revision 2, dated 14/12/05 or later EASA approved revision		Data package containing the following documents, and additional supporting data:1. Design Compliance Program for ASIRISRadar System Installation, DECA Aviation Engineering Limited document DCP 05259, Revision 12. Static Strenght and Compliance Requirements, DECA Aviation Engineering Limited Enginee...	1. DECA Aviation Flight Manual Supplement FMS05259, Revision 1, is required	18/07/2007	Active	10015830

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01922	TIMCO AVIATION SERVICES INC.	REV 1	FAA STC ST03372AT	BOEING 767-300	Installation of Lower Lobe Crew Rest Module (CRM) and Main DeckVestibule in in accordance with Timco Master data List 04T104L001, Rev H, dated December 7, 2007 or later approved revisions approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		1. Approved Airplane Flight Manual Supplement TIM-AFM-01044 Rev. A, dated December 14, 20072. Instructions for continued Airworthiness 04T104R007, Rev A, dated November 9, 2006.	1. This approval should not be extended to other Aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between this change and any other previously approved modifications will produce no adverse...	16/01/2008	Active	10015831
EASA.IM.A.S.01925	PRATT & WHITNEY	REV 1	FAA STC ST00228BO	MD-88 DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Installation of P&W JT8D-200 Series Engines incorporating the improved forward Fan Case as described in the P&W SB JT8D6478, Rev.1, dated 1 August 2007.		P&W Service Bulletin JT8D 6478, Rev.1, dated 1 August 2007.	This STC is approved only for the product configuration as defined in the approved design datareferred to in the paragraph "Description". Prior to installation of this modification the installermust determine that the interrelationship between this modification and any other previouslyinstalled modi...	04/10/2007	Active	10015834
EASA.IM.A.S.01926	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA00349WI	BEECH 1900D	Installation of a right hand forward lavatory.		In accordance with United Beechcraft Inc Drawing Nimber RA5009357-1, dated July 28, 1995, or later approved revisions.FAA approved United Beechcraft Inc Aircraft Flight Manual Supplement Manual No. RA5009357FM1, dated July, 1995 or later approved revisions.	None	28/03/2006	Active	10015835
EASA.IM.A.S.01928	AERONCA Inc.		ST09456SC	BOEING 737-500 BOEING 737-400 BOEING 737-300	Manufacture and Installation of Engine Fan Cowl Doors		Manufacture of Engine Fan Cowl Doors in accordance with Aeronca Document No. TM518, "737 Cowl Door Drawing Control Document" Revision A dated February 19, 1998 or later approved revisionInstallation of Engine Fan Cowl Doors in accordance with Aeronca Document No. TM 515, "B737 Fan Cowl Installation,...	Compliance with Aronca Engineering Report Number ER 1904 "Instructions for Continued Airworthiness and Structural Repair Manual" Revision B, dated January 29, 1998, or later approved revision required.	28/07/2006	Active	10015836
EASA.IM.A.S.01931	SAFRAN CABIN INC.		FAA STC ST01880LA	BOEING 747-400	Installation of pantry		C & D Zodiac Inc. drawing list C481000 Revision F dated November 09, 2006 or later approved revision.FAA STC ST01880LA.	--	19/12/2006	Active	10015837
EASA.IM.A.S.01932	AVIATION COMMUNICATION ANDSURVEILLANCE SYSTEMS, L.L.C. (ACSS)		FAA STC SA4882NM	NOT CERT. 747-100B SUD/-SR 747-SP 747-200F, 747-300, 747-400 747-100, 747-200B, 747-200C	Installation of a Honeywell Traffic Alert and Collision Avoidance System (TCAS II) in accordance with FAA approved Honywell Master Data List number ML4071598		Data package containing the following documents, and additional supporting data:1. FAA Letter to Honeywell of approval pertaining to Honeywell previously approved STCs TCAS II installations to be upgraded to TCAS (10004) and to Mode S (10004) as indicated in Honeywell Master Drawing List for foll...	FAA approved Flight Manual Supplement required for this configuration is listed on the appropriate approved Honeywell and ACSS Master Index List.	31/07/2006	Active	10015838

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01933	GULFSTREAM SERVICES CORPORATION		FAA STC ST03224AT-D	GULFSTREAM GV-SP	Completion and installation of the custom interior on Aircraft Serial 5099.		In accordance with Gulfstream Aerospace Corporation Master Index List GC514915099, Revision F, dated May 10, 2006, or later approved revisions.FAA approved Flight Manual Supplement, GC51501M015, Revision N/C, dated May 11, 2006, or later approved revisions.	Aircraft Serial 5099 Only.	06/06/2006	Active	10015839
EASA.IM.A.S.01936	BOMBARDIER INC.		-	BOMBARDIER BD-100-1A10 (CHALLE	Aircraft completion, interior configuration in accordance with Aero Consultung Services Ltd. Modification Data Summary E843000 revision N/C		AFM Supplement E843090 rev N/C	Limited to S/N 20097	17/08/2006	Active	10015841
EASA.IM.A.S.01937	SIERRA INDUSTRIES Ltd.		FAA STC ST09559AC	CESSNA C501	Installation of Williams/ Rolls FJ44-2Aengines in accordance with FAA STC ST09559AC and Sierra Ind. Drawing SI360-000, dated 27.02.2002. or later FAA approved Revision.		Sierra Ind. Drawing SI360-000, dated 27.02.2002, or later FAA approvedRevision.FAA approved Sierra Ind. AFM-S Doc. No. SRW137, dated 14.03.2002 orlater FAA approved Revision.	The installer must determine, if this design is compatible with previously approved modifications. If the holder agreesto permit another person to use this certification to altera product, the holder must give the other person written evidence of that permission.	08/03/2007	Active	10015842
EASA.IM.A.S.01941	DUNCAN AVIATION, INC.		FAA STC SA2405CE-D	GULFSTREAM ASTRA/ SPX GULFSTREAM 1125 WESATRD ASTRA	Installation of Garret Model GTCP36-150 (W) Auxiliary Power Unit used as nonessential Bleed Air source for on board electrical and enviromental systems.		1125 Astra:Duncan Aviation Drawing list No AST 001, dated 15 Sept 88 or later FAA approved revision, Duncan Aviation Inc, FAA approved AFM supplement, dated 16 Sept 88Astra SPX:Duncan Aviation Drawing list No AST 001, dated 5 January 96 orlater FAA approved revision, FAA approved AFM supplement, da...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/10/2006	Active	10015844
EASA.IM.A.S.01945	ROSE UPHOLSTERY, Inc.dba ROSE AIRCRAFT SERVICES, INC.dba ROSE AIRCRAFT INTERIORS, INC.		SA10188SC	BAE JETSTREAM 3201	Cabin Reconfiguration - 12 Passenger Executive Interior		Rose Aircraft Interiors Inc. Master Drawing Lis, Report No.8265.00.09, Revision 2, dated 04-03-2003 or later approved revisionInstructions for Continued Airworthiness, Revision IR, dated 08-08-2003 or later approved revisionAircrat FlightManual Supplement, Report No. 8365.00.10 dated September 2,...		11/04/2006	Active	10015845
EASA.IM.A.S.01946	SIDDHIS AERONAUTICAL DESIGNSCORPORATION	REV 3	TCCA STC SA97-71, ISSUE 6	BOMBARDIER CL-600-2B19 (SERIES BOMBARDIER CL-600-2B16 (604) BOMBARDIER CL-600-2B16 (601-3R BOMBARDIER CL-600-2B16 (601-3A BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of Fin Mounted Radome/ Antenna System (Structural Provisions only).		¿ Transport Canada STC SA97-71 Issue 6 dated March 28, 2007 or later approved revision. ¿ SIDDHIS Aeronautical Design Modification Summary MS05272 Revision 3 or later approved revision.	1. The installation shall be visually inspected for external damage every 1200 hours and for lightning damage every flight in severe weather.2. The total weight of the antenna and the installed equipment shall not exceed 18.1 kg.3. The additional height clearance of 0.17 meters is required4...	29/05/2007	Active	10015846
EASA.IM.A.S.01947	HONEYWELL INTERNATIONAL INC.		FAA STC ST00417SE	BOEING 767-300F BOEING 767-300 BOEING 767-200	Installation of Enhanced Ground Proximity Warning System (EGPWS)		Master Drawing List 960-222 Rev N dated June 2, 2002 or later approved revision	Honeywell International Inc. Airplane Flight Manual Supplements 060-4189-003 Revision B, 060-4189-014 Revision A, 060-4189-008 Revision A, 060-4189-037 Initial Revision, 060-4189-052 Revision A, 060-4189-013 Initial Revision, 060-4189-068 Revision A, 060-4189-077Initial Revision, 060-4189-080 Revisi...	07/04/2006	Active	10015847

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01948	GULFSTREAM AEROSPACE SERVICES CORP.d/b/a GULFSTREAM AEROSPACE CORPORATd/b/a GULFSTREAM		ST10308SC-D	GULFSTREAM ASTRA/ SPX GULFSTREAM 1125 WESATRD ASTRA GULFSTREAM 100	Installation of Dual Universal Avioniks UNS-1C+ Flight Management Systems. FAA STC 010308SC-D		AFMS CEA1118M005IFCA CEA1118A000	This STC is only applicable to A/C with previous installed dual Universal Avionik UNS-1C FMS.	13/07/2006	Active	10015848
EASA.IM.A.S.01950	STAR AVIATION, Inc.		ST02989AT	CESSNA S550 CESSNA 551 CESSNA 550 CESSNA 501 CESSNA 500	The modification will consist of a composite structure witha metal faceplate wich will be fitted over the center of the existing Glareshield. An area of the existing glareshield will be removed to allow for wires to be routed to the annunciators and switches which are relocated to the new Glareshie...		Master Data List R25-0283 Rev. E, dated 17 January 2006AFM Supplement Doc. Nr. R25-342, Rev. IR dated 24 November 2004		12/05/2006	Active	10015850
EASA.IM.A.S.01951	SIERRA INDUSTRIES Ltd.		ST09630AC	CESSNA 501	Installation of Meggitt Engine Instrument Display System according to FAA STC ST09630AC.		Sierra Ind. Drawing SI400-001, Rev. A, dated 17.03.2006, orlater FAA approved Rev.FAA approved Sierra Ind. AFM-S Doc. No. 115-601; Rev. 1, dated 15.10.2004 or later FAA approved Revision for Cessna 501 equipped with Williams FJ44 enginesFAA approved Sierra Ind. AFM-S Doc. No. 115-602, dated 29.03.2...	The installer must determine, if this design is compatible with previously approved modifications. If the holder agreesto permit another person to use this certification to altera product, the holder must give the other person written evidence of that permission.	15/03/2007	Active	10015851
EASA.IM.A.S.01955	LEARJET Inc.		FAA STC ST01186WI-D	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35 LEARJET 31	Installation of Universal UNS-1L Flight Management System.		FAA STC ST01186WI-DLearjet Master Document List BAS35010062Revision H dated September 10 2004 or later approved revision.AFM Supplement ref. BAS35040122 Revision (-) dated February 19 2004 or later approved revision.	Not JAA TGL10 Compliant with present software load.	13/10/2006	Active	10015852
EASA.IM.A.S.01956	PETERSEN AVIATION, INC.		FAA STC SA00328WI	REIMS AVIATION CESSNA F-172N	Operation of airplane on leaded and unleaded automotive gasoline, 91 minimum antiknock index (RON + MON) / 2 per ASTM SpecificationD-439. Intermixing with aviation gasoline also approved.		Petersen Drawing No. RF-172-91 dated January 18, 1995.	Limited to those airplanes equipped with gravity fuel feed to the carburetor and STC certificated or approved engine installation. All engines must have separate approval for operation on automotive gasoline in the form of Supplemental or Type Certificte approval.The original Lycoming 0-320-H2 AD en...	24/04/2006	Active	10015853
EASA.IM.A.S.01957	PETERSEN AVIATION, INC.		FAA STC SA2600CE	CESSNA 172P CESSNA 172N CESSNA 172M CESSNA 172L CESSNA 172K CESSNA 172I CESSNA 172H CESSNA 172G CESSNA 172F CESSNA 172E CESSNA 172D	Operation of airplane on leaded and unleaded automotive gasoline, 91 minimum antiknock index (RON + MON) / 2 per ASTM SpecificationD-439. Intermixing with aviation gasoline also approved.		1. Petersen Drawing No. 172-91 dated February 13, or later apporved revision. 2. Airplane Flight Manual Supplement datedMarch 30, 1990, or later approved revision for 172N, SerialNumber 17270050 & 17271035 thru 17274009 & 172P Models only.	Limited to those airplanes equipped with gravity fuel feed wing fuel tanks as the main fuel supply to the carburetor and certificated (original or STC) or approved engine installations. All engines must have separate approval for operationon automative gasoline in the form of Supplement or Type Cer...	20/04/2006	Active	10015854
EASA.IM.A.S.01958	JET AVIATION ST. LOUIS, Inc.		FAA STC ST01258WI-D	CL-600-2B16 CL-600-1A11, CL-600-2A12	Installation of an Audio International Inc. Articulated Mounting Arm, KGS LT-71(J) Power Suppl & Data Connectivity for an Electronic Flight Bag		Midcoast Aviation Inc Master Data List 34-343G001 Revision A dated July 14, 2004 or later approved revision	The Audio Interantional Articulated Arm Attachmentn is limite dto the weight & CG Envelope Contained in Midcoast Aviation Inc, Weight & Balance Update 34-010E092 Revision A dtaed July 13, 2004 or later approved revision	17/08/2006	Active	10015855

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01960	GULFSTREAM AEROSPACE SERVICES CORP.d/b/a GULFSTREAM AEROSPACE CORPORATd/b/a GULFSTREAM		FAA STC NO ST02237CH-D	GULFSTREAM ASTRA/ SPX GULFSTREAM 100	Installation of a Corporate Aircraft Completion in accordance with Gulfstream Master Drawing List GA122046000, Rev B dated July 19,2006 or later approved revision		IFCA ga11468A000	Limited to S/N 158	11/08/2006	Active	10015856
EASA.IM.A.S.01961	ROSEMOUNT AEROSPACE, Inc.		FAA STC ST00971SE-D	BOEING 737-500 BOEING 737-400 BOEING 737-300	Installation of the Rosemount Aerospace Coockpit Door Surveillance system (CDSS).		1. Rosemount Aerospace Data List, Doc No. D0530888, Revision B, dated February 15, 2006, or later approved revisions. 2.Rosemount Aerospace Doc No. D0530836, Revision A, dated December 16, 2005, or later approved revisions.3. Rosemount Aerospace Instructions for Continued Airworthiness, Doc No. D053...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	20/04/2006	Active	10015857
EASA.IM.A.S.01962	BOMBARDIER INC.		TCCA STC C-LSA06-020/D	BOMBARDIER BD-100-1A10	Aircraft completion, 10 Passenger interior configuration, in accordance with MDS E790000		AFM Supplement E790090	S/N 20079	24/04/2006	Active	10015858
EASA.IM.A.S.01963	MTI POLYFAB Inc.		TCCA STC SA03-19	CL-600-1A11/-2A12/-2B16	Installation of Insulation Blankets		- Transport Canada STC SA03-19 Issue 2 dated February 19, 2003<(>,<)>- Magnifoam Technology Inc. Modification Summary MS16050201, MS 16050202<(>,<)> MS 16050203, MS16050204, MS 160500501 Revision NC or later approved revision.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	08/09/2006	Active	10042986
EASA.IM.A.S.01967	B/E AEROSPACE LIMITED		TCCA STC SA03-43	CL-600-2B19	Installation of Safe Flight Autopower (Autothrottle) System		Transport Canada STC SA03-43 Issue 1 dated May 09, 2003AeroConsulting Services Modification Data Summary D45150Safe Flight AFM Supplemetn R-2827 Revision N/C dated May 09 2003 orlater approved revision	--	14/09/2006	Active	10015859
EASA.IM.A.S.01973	COLUMBIA AVIONICS INC.		FAA STC SA01156WI	CESSNA 551 CESSNA 501	Installation of dual RVSM compliant IS&S or J2 (Kollsman) air data system.		According to Columbia Avionics Master Document List Doc. No. 30141024, Rev. 4 or later FAA approved RevisionsTo be operated in accordance with either of- FAA approved Columbia Avionics AFM-S Document No. 30141039, original issue, or later FAA approved Revisions or- FAA approved Columbia Avioni...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	12/02/2009	Active	10015860
EASA.IM.A.S.01974	BEECHCRAFT CORPORATION	REV. 2	FAA ST10066SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of B.F. Goodrich WX-1000E Stormscope.		1. In accordance with Master Drawing List 800-500 Revision G or later approved revision;2. Airplane Flight ManualSupplement 800-307 Revision R5 or later approved revision;3. Maintenance Manual Addenda: 34-43-10.		20/05/2008	Active	10015861

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01975	BEECHCRAFT CORPORATION	REV. 1	FAA ST10085SC	HAWKER 800XP, HAWKER 850XP	Installation of a Davtron Clock		Master Drawing List 800-503 Revision G or later approved revisionAirplane Flight Manual Supplement 800-309 Revision R2 or later approved revisionMaintenance Manual Addenda: 31-20-45		23/06/2008	Active	10015862
EASA.IM.A.S.01976	BEECHCRAFT CORPORATION	REV. 2	FAA STC ST10108SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of a Cockpit Speaker Volume Recalibration.		In accordance with : Master Drawing List 800-505 Revision IR or later approved revision		20/05/2008	Active	10015863
EASA.IM.A.S.01977	BEECHCRAFT CORPORATION	REV. 2	FAA STC ST10109SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of a Cockpit Speaker Inhibit Switch.		1. In accordance with : Master Drawing List 800-504 Revision L or later approved revision;2. Flight Manual Supplement 800-310 Revision R6 dated September 13, 2007 or later approved revision;3. Maintenance manual addenda 23-50-20.		21/05/2008	Active	10015864
EASA.IM.A.S.01978	BEECHCRAFT CORPORATION	REV. 2	FAA ST10128SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of a Precise Flight Pulselight System Activated by (existing) TCAS.		1. In accordance with : Master Drawing List 800-507 Revision D or later approved revision;2. Flight Manual Supplement 800-313 Rev R5 or later approved revision;3. Maintenance Manual Addenda: 33-40-15.		21/05/2008	Active	10015865
EASA.IM.A.S.01979	BEECHCRAFT CORPORATION		FAA ST10189SC	HAWKER 800XP, HAWKER 850XP	Installation of Digital Passenger Briefing System		Master Drawing List 800-511 Revision F or later approved revisionFlight Manual Supplement 800-316 Revision R2 or later approved revision.Maintenance Manual Addenda 23-33-21	--	18/09/2006	Active	10015866
EASA.IM.A.S.01980	BEECHCRAFT CORPORATION	REV. 2	FAA ST10187SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of a Satellite Communications System.		1. In accordance with : Master Drawing List 800-509 Revision J or later approved revision;2. Flight Manual Supplement 800-314 Revision R5 or later approved revision;3. Maintenance Manual Addenda 23-16-20		21/05/2008	Active	10015867
EASA.IM.A.S.01982	BEECHCRAFT CORPORATION		ST10190SC	HAWKER 800XP, HAWKER 850XP	Installation of CMS 400 Checklist Management System		Master Drawing List 800-510 Revision J or later approved revisionFlight Manual Supplement 800-315 Revision R2 or later approved revision.Maintenance Manual Addenda 23-15-20	--	19/09/2006	Active	10015868
EASA.IM.A.S.01985	BEECHCRAFT CORPORATION	REV. 4	FAA ST09651SC	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of Cabin Interior and Avionics Systems		In accordance with: Master Drawing List 800-181 Revision AYor later approved revision.For Hawker 800XP, Hawker 850XP, Hawker 900XP: Airplane Flight Manual Supplement 800-289 Revision R8 or later approved revision.For Hawker 750: Airplane Flight Manual Supplement 800-350 Revision R3 or later appro...	1. Hawker 750 with 238M530760-0017 and -0019 installations only, are limited to a maximum of 10 passengers.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no...	15/12/2008	Active	10015870

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01986	BEECHCRAFT CORPORATION	REV. 2	FAA SA8063SW	HAWKER 900XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE 125 SERIES 800A	Installation of Cabin Headliner/Window Panel Brackets.		In accordance with Master Drawing List 800-116 Revision D dated May 16, 2006 or later approved revision.		20/05/2008	Active	10015871
EASA.IM.A.S.01987	BEECHCRAFT CORPORATION	REV. 2	FAA SA8062SW	HAWKER 900XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE 125 SERIES 800A	Installation of a Therapeutic Oxygen System.		1. In accordance with Master Drawing List 800-125 Revision B or later approved revision;2. Flight Manual Supplement 125-037 Rev 6 or later approved revision.		20/05/2008	Active	10015872
EASA.IM.A.S.01988	BEECHCRAFT CORPORATION	REV. 2	FAA SA7972SW-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of Airborne Flight Information System (AFIS).		1. In accordance with : Master Drawing List 800-092 Revision S or later approved revision;2. Flight Manual Supplement 800-242 Revision 8 or later approved revision;3. Maintenance Manual Addenda: 34-61-05		20/05/2008	Active	10015873
EASA.IM.A.S.01989	BEECHCRAFT CORPORATION	REV. 2	FAA SA7944SW	HAWKER 900XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE 125 SERIES 800A	Installation of a Cabin Oxygen System.		1. In accordance with Master Drawing List 800-107 Revision D dated August 28, 2006 or later approved revision2. Maintenance Manual Addenda: 35-06-00 & 35-20-05		20/05/2008	Active	10015874
EASA.IM.A.S.01990	BEECHCRAFT CORPORATION	REV. 1	FAA SA3810SW-D	HAWKER 850XP, HAWKER 900XP HAWKER 800, HAWKER 800XP BAE 125 SERIES 800A	Installation of Precise Pulselite Control Unit		1. In accordance with: Master Drawing List 800-048 Revision Y or later approved revision2. Flight Manual Supplement 800-231 Rev R103. Maintenance Manual Addenda: 33-40-05, 33-40-10	1. 103 Installation is for Models Hawker 800XP, Hawker 850XP and Hawker 900XP.2. All installations except -103 is for Models BAe. 125 Series 800A, Hawker 800; Hawker 800XP	19/11/2007	Active	10015875
EASA.IM.A.S.01992	BEECHCRAFT CORPORATION	REV. 2	FAA SA2710SW	HS.125 SERIES 700A HAWKER 900XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE.125 SERIES 800A	Installation of Observer's Jump Seat.		1. In accordance with Master Drawing List 125-008 Revision L or later approved revision;2. Maintenance Manual Addenda: 25-10-15		20/05/2008	Active	10015876
EASA.IM.A.S.01993	BEECHCRAFT CORPORATION	REV. 2	FAA ST01342WI-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of Collins Integral Flight Information System (IFIS 5000) and Proline 21 Radios.		1. In accordance with Master Data List AAC-0404-001 Rev B, or later approved revision;2. AFMS AAC-0406-001 R5, orlater approved revision;3. Maintenance Manual Supplement AAC-0407-001 Rev -, or later approved revision.	1. Prior installation and approval of Kit 149-3419-0001 is a prerequisite;2. Prior installation and approval of Kit 149-3420-0001 is a prerequisite;	20/05/2008	Active	10015877
EASA.IM.A.S.01994	BEECHCRAFT CORPORATION	REV. 2	FAA ST09772SC-D	HAWKER 900XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE.125 SERIES 800A	Installation of a Smoke Detector System.		1. In accordance with : Master Drawing List 800-192 Revision E or later approved revision;2. Airplane Flight Manual Supplement 800-297 Revision R5 or later approved revision;3. Maintenance Manual Addendum 26-11-00.		20/05/2008	Active	10015878
EASA.IM.A.S.01995	BEECHCRAFT CORPORATION		FAA ST0998SC	HAWKER 800XP, HAWKER 850XP	Installation of the Magnastar C-2000 Airborne Telephone System		Master Drawing List 800-501 Revision J or later approved revisionAirplane Flight Manual Supplement 800-305 Revision R2 or later approved revisionMaintenance Manual Addenda: 23-16-05, 23-16-10	--	19/09/2006	Active	10015879

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.01996	BEECHCRAFT CORPORATION	REV. 2	FAA ST09986SC-D	HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of an Airshow System.		1. In accordance with Master Drawing List 800-502 Revision H or later approved revision.2. Airplane Flight ManualSupplement 800-306 Revision R6 or later approved revision3. Maintenance Manual Addenda: 23-33-35, 23-33-40, 23-33-41, 23-33-45, 23-33-50, 23-33-60, 23-33-61.		20/05/2008	Active	10015880
EASA.IM.A.S.02000	JET AVIATION ST. LOUIS, Inc.		FAA STC ST01319WI-D	BOMBARDIER CL-600-2B16 (CL-604	Addition of Runway Awareness & Advisory System-RAAS to Honeywell MK-V & MK-VII Enhanced Ground Proximity Warning System-EGPWS		FAA STC ST01319WI-D dated April 22 2005.Midcoast Aviation Master Data List No. 34-327G003 Revision N/C dated April 22 2005 or later approved revision.	1. Prerequisite: MK V or MK VII EGPWS must be installed at Software Level - 218-218 or greater.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adver...	06/09/2007	Active	10015882
EASA.IM.A.S.02001	JET AVIATION ST. LOUIS, Inc.		FAA STC ST01318WI-D	BOMBARDIER CL-600-2B16	Software upgrade to 218-218 of the Honeywell MK-V Enhanced Ground Proximity Warning System to support Runway Awareness & Advisory System (RAAS).		FAA STC ST01318WI-D, dated 11 April 2005.Midcoast Master Data List No. 34-327G004 Revision N/C dated 11 April 2005 or later approved revision.	Prerequisite: MK V EGPWS must be installed per Bombardier Service Bulletin 604-34-020 or 604-34-025.	06/09/2007	Active	10015883
EASA.IM.A.S.02002	LEARJET Inc.		FAA STC SA8197NM-D	BOMBARDIER CL-600-2B16 (604)	Installation of Oxygen System-Passenger & crew (14500ft)		Learjet Inc Master Document List DC35205000 Revision NC dated April 18, 2002 or later apporved revision.AFM Supplement ref D-FM35205002 Revision NC dated March 12, 2002 or later approved revision.	--	20/06/2006	Active	10015884
EASA.IM.A.S.02003	BOMBARDIER AEROSPACE		TCCA STC SA03-113	CL-600-2B16 (604)	Installation of Complete Custom Aircraft Interior		Transport Canada STC SA03-113Aero Consultin Services Ltd Configuration Definition List D817000 Revision GAero Consulting Services AFM Supplement D817090 Revision N/C or later approved revision	Limited to ASN 5591 only	17/08/2006	Active	10015885
EASA.IM.A.S.02004	GODERICH AIRCRAFT Inc.		O-LSA06-081/ D (LSTC)	BEECH 400A (HAWKER 400 XP)	Cabin Entertainment Equipment Installation.		Cabin Entertainment Equipment Installation according MasterDrawing List MDL06025 Rev. N/C, dated 30 March 2006 or later approved revision.Maintenance must be in accordance with Avionics Design Services Lts. Instructions for Continued Airworthiness ICA06025-1 Rev. N/C, dated 27 March 2006 or later a...	This Installation is limited to the Serial No. RK-37 (Registration SE-DRS).This approval is for electrical/avionics aspects only. Structural aspects of this installation are not included and require separate approval.	09/11/2006	Active	10015886
EASA.IM.A.S.02005	GODERICH AIRCRAFT Inc.		O-LSA06-117/ D (LSTC)	BEECH 400A (HAWKER 400 XP)	Change in interior seating arrangement, addition of sink toexisting rear lavatory, fabrication and installation of RH fwd cabinet,revision of existing LH fwd cabinet, revision tointerior finishing details, and addition of new fuselage antenna.		Installation according Phoenix Aero Aviation Engineering Ltd. Engineering Service Bulletin PA-ESB-06-002 Issue 1, Rev. Original approved 28 April 2006 or later approved revision.Operation must be in accordance with Phoenix Aero Aviation Engineering Ltd. Flight Manual Supplement FMS-PA-06-003 Issue 1...	1. This Installation is limited to the Serial No. RK-37 (Registration SE-DRS).2. Compatibility of this modification with other previously approved modifications must be determinedby the installer.	19/12/2006	Active	10015887

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02007	AVIATION FABRICATORS, Inc.		FAA ST01262WI	650	Installation of a 1, 2 or 3 place side facing Divan		Installation in accordance with Aviation Fabricators STC Data Package AF-263, Rev K, dated June 9, 2004, with an approval date of July 28, 2004, or later approved revision.	Applicable to aircraft serials 650-0023 and subsequent.ThisSTC approves only the installation of the parts contained in the installation documents referenced above. The requirements foraisle width, passenger oxygen systems, seats and safety belts, and upholstery coverings will require a separate EA...	09/01/2007	Active	10015888
EASA.IM.A.S.02008	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC STC02075CH	AIRBUS A300 MODEL B4-2C AIRBUS A300 MODEL B4-203 AIRBUS A300 MODEL B4-103 AIRBUS A300 MODEL B2K-3C AIRBUS A300 MODEL B2-203 AIRBUS A300 MODEL B2-1C AIRBUS A300 MODEL B2-1A	Installation of Universal Avionics Systems Corporation Terrain Awareness and warning System (TAWS)		Master Data List ECS-202603, revision G, dated 12 April 2006 or later approved revision	Aircraft Flight Manual Supplement ECS 202604, revision B, dated 11 October 2005 or later approved revisionInstruction for continued airworthiness ECS 202604, revision B, dated 5 December 2005If the holder agrees to permit another person touse this certificate to alter the product, the holder shallr...	20/09/2006	Active	10015889
EASA.IM.A.S.02009	EMBRAER - EMPRESA BRASILEIRADE AERONAUTICA S.A. - PC 179/4 GEC		CTA STC2006S02-09	EMBRAER EMB-135BJ	CTA STC2006S02-09 "Installation of a 30' LCD monitor and Playstation Entertainment System iaw Avionic Services master drawing list 135-23-001 Rev. D dtd. 28. Nov. 05 or later approved revision		--	1. Limited to EMB-135BJ SN 145000802. Instructions for Continued Airworthiness Report No. 135-23-0008 Rev. 0 dtd. 9.Sep. 05 or later accepted revision.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description"y...	23/01/2007	Active	10015890
EASA.IM.A.S.02011	WIPAIRE Inc.		FAA STC SA610GL	DHC-2, MK1	Installation of Wipaire Model 6000 or 6100 Seaplane or Amphibious Floats		In accordance with Wipaire Master Drawing List ref W-MD115,dated, June 3 1982, or later approved revisions.FAA Approved Flight Manual Supplement dated, June 3, 1982 is required for Amphibious float installations, or later approved revisions.FAA Approved Flight Manual Supplement dated April 1, 1983...		20/06/2006	Active	10015891
EASA.IM.A.S.02013	HONEYWELL INTERNATIONAL INC.		FAA STC ST00446SE	DC-9-80 (MD-80) SERIES	Installation of the Honeywell Solid State Flight Data Recorder		Master Drawing 755-3026-001 Rev. C dated 9-3-2006	--	11/09/2006	Active	10015893
EASA.IM.A.S.02014	ELLIOTT AVIATION		FAA STC SA02264CH	BEECH B300C BEECH B300 BEECH B200CT BEECH B200C BEECH B200 BEECH 300LW BEECH 300	Airworthiness certification of Reduced Vaertical seperationMinimum (RVSM) and installation of Air Data Systems		Installation in accordance with Elliott Aviation Master Drawing List, Report No MDL-2468-000, Revision C, dated Amrch 16, 2006 or later approved revisionOperation in accordance with FAA Approved Airplane Flight Manual Supplement, Elliott Aviaiton Report No FMS-2468-000, Revision IR, approved March 2...	None	09/11/2006	Active	10015894

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02015	COMMUTER AIR TECHNOLOGY Inc.	REV. 1	FAA STC SA00184LA	BEECH B200T BEECH B200CT BEECH B200C BEECH B200 BEECH A200CT BEECH A200C BEECH A200 BEECH 200T BEECH 200CT BEECH 200C BEECH 200	Installation of Alternate Main Landing Gear Tires, MichelinP/N 026-335-0.Revision 1 issued to add models B200GT and B200CGT.		- Installation in accordance with Commuter Air Technology Top Drawing LE10000 Revision NC, dated May 9, 1996 or later approved revisions.- Operation in accordance with Commuter Air Technology Approved Flight Manual Supplement LE-10001, dated May 14, 1996 or later approved revisions.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	10/02/2009	Active	10015895
EASA.IM.A.S.02016	TELEDYNE TECHNOLOGIES INCORPORATED		FAA STC SA1013SO	BEECH F90 BEECH E90 BEECH C90 BEECH B99	Replace existing nickel-cadmium battery with Gill BB638/T series lead-acid battery		Installation instructions for replacing existing nickel-cadmium battery with Gill BB638/T series lead-acid battery, dated May 1, 1992, or later approved revisions.FAA Approved Airplane Flight Manual Supplement, dated August 3, 1978, (C90, E90, B99), or January 21, 1981, (F90), or later approved revi...	1) Beech C90 Serial Numbers LJ590 and after, E90 Serial Numbers LW58 and after, F90 Serial Numbers LA-2 and after, B99 Serial Numbers U146 and U148 through U164.2) FAA approved Airplane Flight Manual Supplement, dated August 3, 1978, (C90,E90, B99), or January 21, 1981, (F90), or later approved rev...	22/05/2006	Active	10015896
EASA.IM.A.S.02017	TELEDYNE TECHNOLOGIES INCORPORATED		SA1016SO	BEECH B300C BEECH B200T BEECH B200C BEECH B200 BEECH 300LW BEECH 300 BEECH 200T BEECH 200CT BEECH 200C BEECH 200	Replace existing nickel-cadmium battery with Teledyne G-6381E lead-acid battery or with Teledyne G-6381ES Sealed Recombinant lead-acid storage battery		Installation instructions for replacing existing nickel-cadmium battery with Teledyne G-6381E lead-acid battery, dated August 3 , 1978, or later approved revisions.Teledyne MasterData List 1016-7, Revision "NC", dated December 13, 2000, or later approved revisions.FAA approved Teledyne Battery Prod...	FAA approved Teledyne Battery Products Airplane Flight Manual Supplement, dated August 3, 1978, for G-6381E battery, orMarch 21, 2001, for G-6381ES battery, or later approved revisions is required as part of this installation.	23/05/2006	Active	10015897
EASA.IM.A.S.02018	TELEDYNE TECHNOLOGIES INCORPORATED		SA1017SO	BEECH E90 BEECH C90 BEECH B90 BEECH A100 BEECH 65-A90-1 BEECH 65-A90 BEECH 65-90	Replace existing nickel-cadmium battery with Teledyne Battery Model No. G-638E, G-6381E or G-6381ES		Teledyne Battery Installation Instruction No. SA 1017SO, Revision A, dated April 7, 1998, or later approved revision.		23/05/2006	Active	10015898
EASA.IM.A.S.02021	SOUTHEAST JET GROUP, INC.		ST00589WI	CESSNA S550, (CITIATION S/II) CESSNA 551, CITIATIONII CESSNA 550 CITATION II CESSNA 501, CITIATION	Installation of Honeywell EDZ-605 Two-Tube Electronic Flight Instrumentation System (EFIS).		Columbia Avionics , Inc. Master Document List No. 313330014, Revision 2, dated November 27, 1996 or later approved revisions.Colmumbia Avionics, Inc. Document No. 3054300005, FAA approved Airplane Flight Manual Supplement, dated October 24, 1997 of Southeast Jet Group, Inc. Document No. 305430005, F...		24/08/2006	Active	10015900
EASA.IM.A.S.02027	S-TEC CORPORATION		FAA STC SA9232AC-D	CESSNA T210J CESSNA T210G CESSNA 210J CESSNA 210H CESSNA 210G	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance System, Model ST-687-20/30		Bulletin No. 787, dated 27 May 1997 and Master Drawing ListNo. 921000, dated 27 May 1997 or later approved revisions of the above data (14 Volt System)	1. Also eligible on Models T210G, T210H and T210J when modified per FAA STC SA2689SW (RAM Modification) 2. FAA/DAS Approved Suppllemental Flight Maual, P/N 891412, dated 30 May 1997, is required for Cessna Models 210G, T210G, 210H, T210H, 210J and T210J and models T210G, T210H and T210J when modified...	27/06/2006	Active	10015901

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02028	S-TEC CORPORATION		FAA STC SA09237AC-D	CESSNA 172N CESSNA 172M	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model ST-674-20/30		Bulletin No. 774, dated 11 June 1997 and Master Drawing List No. 921007, dated 11 June 1997 or later approved revisionsof the above data (14 Volt System).	1) Also eligible on the above models when modified by 180 H.P. Engine Conversion.2) FAA/DAS Approved Supplemental Flight Manual, P/N 891423, dated 16 June 1997 is required for S-TEC System 20 for Cessna Model 172M and the above model when modified by 180 H.P. Engine Conversion or later approved revi...	26/06/2006	Active	10015902
EASA.IM.A.S.02029	BOMBARDIER INC.		TCCA STC Q-LSA06-25/D	BOMBARDIER BD-700-1A10	Installation Acoustic Insulation ACSN 9163Validation of TCCA Limited STC Q-LSA06-25/D to S/N 9163MDL: 26118002 Rev NC or later TCCA approved revisionsTCCA SoC: NAI5012-06-00062 dated June 20, 2006		--	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	25/07/2006	Active	10015903
EASA.IM.A.S.02030	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA LSTC Q-LSA06-026/ D ISS 1	BD-700-1A10	Modification of EGPWS Radar Altimeter Callouts and installationof the IPOD on ACSN 9163Valdiation of TCCA Limited STC Q-LSA06-26/D to S/N 9163MDL: 26126002 Rev NC or later approved revisionsTCCA SoC: NAI5012-06-0063 dated June 20, 2006				28/07/2006	Active	10015904
EASA.IM.A.S.02031	S-TEC CORPORATION		FAA STC SA09313AC-D	BEECH G35 BEECH F35 BEECH E35 BEECH D35 BEECH C35 BEECH B35 BEECH A35	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model ST-757-20/30		Bulletin No. 857, dated 12-01-97 and Master Drawing List No. 921052, dated 12-01-97 or later approved revisions of th eabove data (14 Volt System)	Also eligible on Model 35 when modified per STC SA1-460 (Auxiliary Wing Tip Fuel Tanks).FAA/DAS approved supplemental flight manual, P/N 89160, dated 12-05-97 is required for Beech model 35 and this model when modified per STC SA1-460 (Auxiliary Wing Tip Fuel Tanks) for S-TEC System 20 or later appr...	12/06/2006	Active	10015905
EASA.IM.A.S.02032	ROCKWELL COLLINS, Inc.		ST00525WI-D	SEE APPROVED MODEL LIST	Modification of Collins 618M-3/618m-4 VHF COMM Receiver Transmitter Installation to a 618M-5 VHF COMM Receiver Transmitter Installation with either a Gables G7406-02 or Avtech 7522-1-2-VHF COMM Receiver Transmitter.		Collins Installation Instructions as listed on AML No. ST00525WI-D Revision -, or later approved revision.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	31/07/2006	Active	10015906
EASA.IM.A.S.02033	HARTZELL SERVICE CENTER		SA02092AK	CESSNA 208B CESSNA 208A CESSNA 208	Installation of Hartzell HC-D4N-3R/ D9511F(K) Four Bladed Propeller and D-630-3(P) Spinner		Installation in accordance with Aero Twin Inc Master Descriptive Data List No 208-4BP-D dated April 14, 1997, or later approved revisions.Operation in accordance with FAA approvedFlight Manual Supplement No. 208-4BP-AFMS, dated October 17, 1997, or later approved revisions.This modification is acce...	This approval is limited to Model 208 landplanes only.	13/04/2007	Active	10015907
EASA.IM.A.S.02035	CASCADE AEROSPACE Inc.	REV. 1	TCCA STC SA06-58	B747-400	Design Elementary & Enhanced Surveillance.Validation of a STC SA06-58.		Data package containing the following documents and additionalsupporting data:1. Certification Plan Boeing 747-400 Series Elementary & EnhancedSurveillance Program, Cascade Aerospace Engineering document PR1-3710.1.1, Rev. Nil, or later approved revisions;2. Boeing 747-400 Series Elementary & Enhanc...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	20/11/2006	Active	10042988

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02035	CASCADE AEROSPACE Inc.	REV. 1	TCCA STC SA06-58	BOEING 747-400	Design Elementary & Enhanced Surveillance.Validation of a STC SA06-58.		Data package containing the following documents and additional supporting data:1. Certification Plan Boeing 747-400 Series Elementary & Enhanced Surveillance Program, Cascade Aerospace Engineering document PR 1-3710.1.1, Rev. Nil, or later approved revisions;2. Boeing 747-400 Series Elementary...		20/11/2006	Active	10015908
EASA.IM.A.S.02036	HAWKER BEECHCRAFT CORPORATION (HBC)		ST09250AC	HAWKER 850 XP HAWKER 800 XP HAWKER 800 HAWKER 1000	Installation of a Logo Light on the lower surface of the Horizontal Stabiliser		Installed in accordance with DevOre Top Drawing No 12500003, dated octoober 30, 1996 or later approved revision		21/09/2006	Active	10015909
EASA.IM.A.S.02037	TIMCO AVIATION SERVICES INC.		FAA STC ST03107AT-D	BOEING 767-300	Interior Reconfiguration		- TIMCO Master Data List 04T110L001 Revision C dated May 312005 or later approved revisions- TIMCO Instructions for Continued Airworthiness 04T110R115 Revision IR dated May 12 2006		16/08/2006	Active	10015910
EASA.IM.A.S.02041	BOMBARDIER INC.		C-LSA06-270/ D	BOMBARDIER BD-100-1A10 (CHALLE	Aircraft completion, 10 passenger interior configuration, in accordance with MDS F029000 (Original STC numer: TransportCanada STC C-LSA06-270/D)		AFM Supplement F029090	Limited to S/N 20106	18/10/2006	Active	10015912
EASA.IM.A.S.02042	MILLENNIUM CONCEPTS, INC.	REV. 1	FAA STC SA01160WI	CESSNA 208B CESSNA 208	Installation of Executive Interior in Cessna Models 208, 208B Caravan		In accordance with Millenium Concepts Inc Master Drawing list (MDL) 2015-MDL022, Rev Y, dated May 15 2007, or later approved revisions.		08/02/2008	Active	10015913
EASA.IM.A.S.02044	GULFSTREAM SERVICES CORPORATION		FAA STC ST02920AT-D	GULFSTREAM GV-SP	Installation of Honeywell MCS-7000 SATCOM system		In accordance with Gulfstream Aerospace Corporation Index List GC51 1038013, Revision B, dated January 17, 2005 or later approved revisionFAA approved Flight Manual Supplemetn, GC51 103M004, Revision NC, dated January 20, 2005 or later approved revision	None	21/08/2006	Active	10015914
EASA.IM.A.S.02048	WESTERN AVIONICS		TCCA STC SA04-26 ISSUE 3	FAIRCHILD SWEARINGEN SA 227 SE FAIRCHILD SWEARINGEN SA 226 SE	Installation of Honeywell EGPWS Mark VI/VIII computer, air data computer, circuit breakers, annunciators, flap positionswitch, OATprobe, GPS antenna, cockpit speaker and associated wiring according Transport Canada Supplemental Type Certification SA04-26, Issue3, March 09, 2005		1. Installation is to be done in accordance with Transport Canada approved Western Avionics Engineering Irder 92350-401, Revision 4, dated 05 January 2005, or later Transport Canada approved revision.2. Transport Canada approved Western Avionics Flight Manual Supplement 92350-801, Revision 3, datedo...		23/10/2006	Active	10015916
EASA.IM.A.S.02049	DUNCAN AVIATION, INC.		FAA STC ST00865CH-D	HAWKER 800 XP HAWKER 800 BAE 125 -800 SERIES	Installation of Honeywell MK VII Enhanced Ground Proximity Warning System (EGPWS) to software version -226-226 and Optional RAAS		• Installation in accordance with Duncan Aviation MasterDrawing List KA9807-01R, Revision L, dated January 25, 2005or later approved revisions.• Aircraft to be operated inaccordance with Aircraft Flight Manual Supplement KA9807-04R, Revision F dated December 9, 2004, orlater approved revisi...	1. Only Software standard -226-226 or later is approved for installation.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the air...	10/09/2007	Active	10015917

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02052	LEARJET Inc.		ST01237LA-D	BOMBARDIER CL-600-2B16 (CL-604	Installation of a Complete Custom Interior		FAA STC ST01237LA_DMaster document List DC55325000 RevisionD dated May 23 2003 or alter approved revisionAFM Supplement are listed on Lelectrical Drawing Index TM4500-5117 as listed on approved Master Document List	Modification of an aircraft by this STC obligates the aircraft operator to include the maintenance information TE-55325000-IFCA in the operators Maintenance Manual & the OperatorsScheduled Maintenance ProgramThe equipment for which provisions were provided has not been certified. EASA approval will...	03/11/2006	Active	10015919
EASA.IM.A.S.02053	LEARJET Inc.		FAA STC SA8109NM-D	BOMBARDIER CL-600-2B16	Installation of Honeywell Enhanced Ground Proximity WarningSystem with Runway Awareness & Advisory System (RAAS)		FAA STC SA8109NM-DLearjet Inc. Master Drawing List CA-1072-TUC Revision AC or later approved revision.Learjet Inc. AFM Supplement BAS63047012 Revision NC or later approved revision.		05/07/2007	Active	10015920
EASA.IM.A.S.02054	HONEYWELL INTERNATIONAL INC.		FAA STC ST00389SE	BOEING 737-900 BOEING 737-800 BOEING 737-700 BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200	Installation of the Honeywell Enhanced Ground proximity Warning System (EGPWS) and Runway Awareness & Advisory System (RAAS).		- Master Drawing 960-2227-002, revision CM, dated May 1, 2006, or later EASA approved revisions.	- Approval of this change in type design applies to the BOEING 737-200/ -300/ -400/ -500/ -700/ -800/-900 aircraft equipped with either a flight management system (FMS) or a global positioning system (GPS) based navigation system or an EGPWS equipped with an internal GPS card as defined in the above...	28/02/2007	Active	10015921
EASA.IM.A.S.02055	S-TEC CORPORATION		FAA STC SA09009AC-D	CESSNA 182N CESSNA 182M CESSNA 182L CESSNA 182K CESSNA 182J CESSNA 182H CESSNA 182G CESSNA 182F CESSNA 182E	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-588 in Cessna 182E, 182F, 182G,182H, 182J,182K, 182L, 182M, and 182N, also when modified per STC SA1382WE (Robertson STOL)		Bulletin No. 588, Rev. 6 or later approved revision,Master Drawing List No. 92787, Rev. F, dated 10-23-02, or later approved revisionAFM-Supplements as mentioned belowInstructionsfor Continued Airworthiness, P/N 81293, Rev. 3 or later approved version	FAA/DAS Approved Supplemental Flight Manual, Part No. 891174, Rev. 2, dated 6-11-01, or later approved revisions, is required for Cessna Models 182E, 182F, and 182G.FAA/DAS Approved Supplemental Flight Manual, Part No. 891175, Rev. 2, dated 6-11-01, or later approved revisions, is required for Cessn...	19/10/2006	Active	10015922
EASA.IM.A.S.02058	GULFSTREAM SERVICES CORPORATION		FAA STC ST02905AT-D	GULFSTREAM ASTRA/SPX GULFSTREAM 100	Installation of Collins Transponder with Flight ID for Elementary Surveillance (-501 configuration) or Enhanced Surveillance (-503 configuration).		501 config: AFMS CEA1126M000 / IFCA CEA1126A000503 config: AFMS CEA1126M002 / IFCA CEA1126A002		24/07/2006	Active	10015923
EASA.IM.A.S.02059	ASSOCIATED AIR CENTER, L.P.	REV. 2	FAA ST10593SC	A319-115	Revision to EASA STC reference EASA.IM.A.S.02059 - Introduction of revised Instructions for Continued Airworthiness.STCEASA.IM.A.S.02059 - Installation of an Executive Style Interior (reference FAA STC ST10593SC dated 6 February 2007).First installation is on MSN 2650.Note: This STC supersedes EASA...		- Master Document List, Document Number 2388000000, Revision A, dated 5 February 2007, or later EASA approved revision.- Instructions for Continued Airworthiness, including Airworthiness Limitations Section, Document Number 2388050090, Revision B, dated 5 February 2007, or later EASA approved revisi...	1. The aircraft is limited to Private use only (not to be operated for hire, reward or common carriage).2. This STC is approved only for the product configuration as defined in the above Master Document List.3. Limitations and Conditions specified in FAA STC ST10593SC remain applicable. 4. Prior to i...	14/05/2009	Active	10015924
EASA.IM.A.S.02060	CASCADE AEROSPACE Inc.		SA01-98	BOMBARDIER DHC-8-315 BOMBARDIER DHC-8-311 BOMBARDIER DHC-8-103 BOMBARDIER DHC-8-102	APU Oil Cooler Door Deletionas per TCCA STC SA01-98, Issue 1, Issue Date: 23. August 2001		Conair Aerospace Engineering Order EO 2977, approved on 23.August 2001 or later Transport Canada approved revisionConair Aerospace Maintenance Manual Supplement MMS 2977-1 dated 27. June 2001 or later Transport Canada accepted revisionConair Aerospace Wiring Manual Supplement WMS 2977-1, dated 21.o...	Configuration 1:DHC-8 Series 100/200/300 aircraft modified in accordance withSTC EASA.IM.A.S. 01714Configuration 2:DHC-8 Series 100/200/300 aircraft in accordance with STC EASA.IM.A.S 02061 (equivalent to Bombardier Mod 8/2328 and 8/3330.Conditions: This approval is only applicable to the type/mode...	07/08/2006	Active	10015925

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02061	CASCADE AEROSPACE Inc.		SA01-67	BOMBARDIER DHC-8-315 BOMBARDIER DHC-8-311 BOMBARDIER DHC-8-103 BOMBARDIER DHC-8-102	Screen Door and Ram Air Vent Modificationas per TCCA STC SA01-67, Issue 1, Issue Date: 7. June 2001		Conair Aerospace Engineering Order EO 2979-1, Transport Canada approved on 7. June 2001 or later Transport Canada approved revision)Conair Aerospace Maintenance Manual Supplement MMS 2979-1 dated 27 April 2001 or later Transport Canada accepted revision)	Configuration 1:DHC-8 Series 100/200/300 aircraft with or without Bombardier Standard option Order 8155 APUConfiguration 2:DHC-8 Series 100/200/300 aircraft with or without Bombardier ACM Exhaust Mod. 8/1815Configuration 3:DHC-8 Series 100/200/300 aircraft with combination of 1. and 2. aboveConditio...	07/08/2006	Active	10015926
EASA.IM.A.S.02063	S-TEC CORPORATION	REV. 1	FAA STC SA7199SW-D	BEECH B100 BEECH A100 BEECH 100	Installation of S-TEC Yaw Damper System, Model ST-302		Bulletin No. 402, Revision 1, dated 4/09/1990Master DrawingList No. 92496, Revision A, dated 4/09/1990 and/or later approved revision of the above data (28 Volt System)	1. Also eligible on Models 100 and B1000 when modified per STC SA3823NM (Lower Aft Fuselage Strakes).2. Also eligible on Model A1000 when modified per STC SA3828NM (Lower Aft Fuselage Strakes) with or without STC SA16779SO (750 S.H.P. Engines).3. Flight Manual Supplement, P/N 89828, dated 9-29-89 is...	17/10/2006	Active	10015927
EASA.IM.A.S.02064	S-TEC CORPORATION	REV. 1	FAA STC SA7198W-D	BEECH B100 BEECH A100 BEECH 100	Installation of S-TEC Systems 65 Two Axis Automatic Flight Guidance System, Model ST-301		Bulletin No. 401, Revision 4, dated 5-24-93Master Drawing List No. 92495, Revision D, dated 5-24-93 with Optional Flight Director/Steering Horizon or later approved revisionson the above data (28 Volt Systems).	1. Also eligible on Models 100, A100 and B1000 when modified per STC SA3828NM (Lower Aft Fuselage Strakes).2. Also eligible on Model A100 when modified per STC SA1679SO (750 S.H.P. Engines).3. Airplane Flight Manual Supplement, P/N 89827S,dated 9-29-89 is required or later approved revisions of the...	17/10/2006	Active	10015928
EASA.IM.A.S.02065	GULFSTREAM SERVICES CORPORATION		FAA STC ST03254AT-D	GULFSTREAM GV-SP	Completion and installation of the custom interior on Aircraft Serial 5071		In accordance with Gulfstream Aerospace Corporation Master Index List GC514915071, Revision D, dated July 3, 2006 or later approvedrevisionFAA approved Flight Manual Supplement, GC51 504M001, Revision NC, dated December 22, 2004 or later approved revision	Aircraft Serial 5071 only	21/08/2006	Active	10015929
EASA.IM.A.S.02066	GULFSTREAM SERVICES CORPORATION		FAA STC ST03264AT-D	GULFSTREAM GIV-X	Completion and installation of the custom interior on Aircraft Serial Number 4045.		In accordance with Gulfstream Aerospace Corporation Master Index List GC414914045, Revision D, dated 30 August 2006, orlater approved revisions.	Aircraft Serial Number 4045 Only.	27/10/2006	Active	10015930
EASA.IM.A.S.02068	AAR AIRCRAFT SERVICES INC.		SA7467SW	F27 (MARK TBD)	Installation of dual freon air conditioning systems in accordance with AAR Oklahoma, Inc., Drawing List 19L002, Revision F, dated July 19, 1988, or later FAA approved revision.		AAR Oklahoma, Inc., Drawing List 19L002, Revision F, dated July 19, 1988, or later FAA approved revision.	1. FAA approved flight manual supplement dated August 10, 1988, is required.2. Compatibility of this modification with previously installed equipment must be determined by installer.	13/10/2006	Active	10015931
EASA.IM.A.S.02070	BOMBARDIER AEROSPACE		TCCA STC C-LSA06-304/D	CL-600-2B16	Aircraft Completion		Transport Canada Limited STC C-LSA06-304/D.Aero Consulting Services Modification data Summary F060000 Revision N/C or later approved revision.Aero Consulting Services AFM Supplement F060090 Revision N/C or later approved revision.	Restricted to ASN 5648	16/11/2006	Active	10015932

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02071	BOMBARDIER AEROSPACE		TCCA STC C-LSA06-243-D ISSUE 1	BOMBARDIER CL-600-2B16 (604)	Aircraft Completion		Transport Canada STC C-LSA06-243-D Issue 1.Aero Consulting Services Modification data Summary E933000 Revision N/C or later approved revision.Aero Consulting Services AFM Supplement E993090 Revision N/C or later approved revision.	1. Restricted to ASN 5644.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	19/09/2006	Active	10015933
EASA.IM.A.S.02072	HONEYWELL INTERNATIONAL INC.		FAA STC ST00255DE-D	BAE 146/AVRO 146 SERIES	Installation of Allied Siganl VHF AFIS		FAA STC ST00255DE-DLearjet Inc Master Document List BAS46010001 Revision B dated May 30 1997 or later approved revision	--	26/09/2006	Active	10015934
EASA.IM.A.S.02075	MID-CANADA MOD CENTER		SA03-92	SEE EASA APPROVED MODEL LIST	Cockpit voice recorder replacement with Universal CVR 30 orCVR 120		Avionics Design Services Ltd. Master Drawing List ref. MDL03074 revision B, dated August 6, 2004	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	14/12/2006	Active	10015935
EASA.IM.A.S.02077	GROVE AIRCRAFT LANDING GEAR SYSTEMSINC.		SA01704LA	SEE APPROVED MODEL LIST	Installation of the Grove Disk Brake System in accordance with FAA approved Master Drawing List Number MDL2337-00001, Revision B, dated December 8, 2004, or later FAA approved revision are required as part of this installation		FAA approved Master Drawing List Number MDL2337-00001, Revision B, dated December 8, 2004, or later FAA approved revision	The installation applies only to aircraft that have hydraulic brake systems installed. The installation should not be incorporated in any aircraft unless it is determined that theinterrelationship between this installation any ant previous	04/07/2006	Active	10015936
EASA.IM.A.S.02078	DEVORE AVIATION CORPORATION OFAMERICA	REV 1	FAA STC SA7473SW	BOEING 757	Installation of tail floodlights in accordance with DeVore Drawing No. 75700001, Rev B, dated September 14, 1988, or later FAA approved revision.		Modification FAA STC No. SA7473SW		02/04/2007	Active	10015937
EASA.IM.A.S.02079	DUNCAN AVIATION, INC.		ST01157WI-D	LEARJET 36A LEARJET 35A	Installation of L-3 Communications F1000, SSFDRFAA STC ST01157WI-D		Certification Plan 40415300, rev. - (Model 35A)Certification Plan 40414400, rev. C (Model 35A)Certification Plan 060501017, rev. A (Model 36A)AFM Supplement 40026800, rev. A (Model 35A, 36A)		30/10/2006	Active	10015938
EASA.IM.A.S.02081	GULFSTREAM SERVICES CORPORATION		FAA STC ST01673AT-D	GULFSTREAM GV-SP	Installation of a Honeywell P-880 Radar System		Installed in accordance with Gulfstream Aerospace Corporation Index List GC51 1258001, Revision 02, dated June 20, 1997, or later approved revisions.FAA approved Flight Manual Supplement, GC51 125M001, Revision NC, dated June 30, 1997 or later approved revision is required.Continued airworthiness in...	N/A	15/03/2007	Active	10015939
EASA.IM.A.S.02082	GULFSTREAM SERVICES CORPORATION		FAA STC ST01673AT-D	GULFSTREAM GV-SP	Installation of a Transponder Flight Identification		Installed in accordance with Gulfstream Aerospace Corporation Index List CE51 1268000, Revision NC, dated June 24, 2004, or later approved revisions.FAA approved Flight Manual Supplement, CE51 126M000, Revision NC, dated July 12, 2004 or later approved revision is required for the-501 configuration....	N/A	15/03/2007	Active	10015940

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02083	GULFSTREAM SERVICES CORPORATION		FAA STC ST01388AT-D	GULFSTREAM GV-SP	Installation of a Vacuum Toilet System		Installed in accordance with Gulfstream Aerospace Corporation Index List GC52 4048002, Revision 02, dated July 02, 1997, or later approved revisions.Continued airworthiness instructions as defined in GC52 404A001, Revision NC, dated July 11, 1997, or later approved revision is required.	N/A	15/03/2007	Active	10015941
EASA.IM.A.S.02084	DENEL OPTRONICSA DIVISION OF DENEL PTY LTD		-	CESSNA 208 AND 208B	Installation of Airborne Observation System		--	1. Max operating speed 155 kts IAS2. Observation system must be switched OFF during take-off and landing3. Persons on board during flight: limited to flight crew and operator(s) of observation system	28/07/2006	Active	10015942
EASA.IM.A.S.02085	ROCKWELL COLLINS, Inc.		SA2656CE	BOEING 747-SR BOEING 747-SP BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-200B BOEING 747-100B SUD BOEING 747-100	Collins traffic alert and collision avoidance system (TCAS II)		1. Drawing Index 992-1944-0012. Aircraft Flight Manual Supplement ACC-90-113	1. Installation of Collins Mode S Transponder , per STC SA2636CE (P-EASA. IM.A.S. 02087) is a prerequisite to this modification.2. ACC-90-113, Airplane Flight Manual Supplement3. 992-1944-001, Drawing Index	01/02/2007	Active	10015943
EASA.IM.A.S.02086	ROCKWELL COLLINS, Inc.		SA2676CE	BOEING 747-SR BOEING 747-SP BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-200B BOEING 747-100B SUD BOEING 747-100	Collins traffic alert and collision avoidance system (TCAS II)		Drawing Indexes 992-1978-001, 992-1989-001, and 992-2696-001.Aircraft Flight Manual Supplement ACC-99-042/-43/-44/-45.	Installation of Collins Mode S Transponder, per STC SA2636CE (P-EASA.IM.A.S. 02087) is a prerequisite to this modification.Aircraft Flight Manual Supplement ACC-99-042/-43/-44/-45.Drawing Indexes 992-1978-001, 992-1989-001, and 992-2696-001.	01/02/2007	Active	10015944
EASA.IM.A.S.02087	ROCKWELL COLLINS, Inc.		SA2636CE	BOEING 747-SR BOEING 747-SP BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-200B BOEING 747-100B SUD BOEING 747-100	Dual Collins TPR-720 Mode S Transponder System.		Drawing Indexes 992-2623-001, 992-2949-001, 992-1954, 992-2976, 992-1977 or 992-1988.		01/02/2007	Active	10015945
EASA.IM.A.S.02088	HONEYWELL INTERNATIONAL INC.		FAA STC ST01000SE	BOEING 737-900 BOEING 737-800 BOEING 737-700 BOEING 737-600	Installation of the Mark II Aircraft Communications Addressing and Reporting System (ACARS) in the Boeing 737-600, -700, -800, -900Series Aircraft.		- MDL 756-0124-001, Revision K, dated March 24, 2006, or later EASA approved revisions.	1. Compatibility of this design change with other previously approved modifications must be determined by the installer.	09/10/2006	Active	10015946
EASA.IM.A.S.02089	DEVORE AVIATION CORPORATION OFAMERICA		SA998EA	BOMBARDIER DHC-6 SERIES 300 BOMBARDIER DHC-6 SERIES 200 BOMBARDIER DHC-6 SERIES 100	Installation of Engine Fuel Drain Recirculation System		FAA STC SA998EADevore Aviation Corporation Installation Instruction Manual F-200 Revision B dated April 21, 1975 or later approved revision		18/10/2006	Active	10015947
EASA.IM.A.S.02090	LEARJET Inc.	REV. 1	FAA STC SA8129NM-D	BOMBARDIER CL-600-2B16 (604)	Installation of Ultra Electronics Active Noise & Vibration Control system		FAA STC SA8129NM-Dmaster Drawing List CA-1077-TUC Revision C dated October 08, 1998 or later approved revisionLearjet Inc AFM Supplement C-1085 Revision A dated November 12 1999 or later approved revision	--	14/09/2007	Active	10015948

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02091	HONEYWELL INTERNATIONAL INC.		FAA STC ST01424CH-D	HAWKER 125 -850XP SERIES HAWKER 125 -800 SERIES	Installation of Honeywell N1 Digital Electronic Engine Control (DEEC)		FAA STC ST01424CH-DGarrett Aviation Services Drawing List 43-80027-001 Revision C dated May 112006 or later approved revision.AFM Supplement 47-8027-001 Revision B dated May 11 2006 or later approved revision.For Hawker 800XP/850XP AFM Supplement 43-8027-003 Revision B dated May 11 2006 or later...		04/10/2006	Active	10015949
EASA.IM.A.S.02092	AIRCRAFT SYSTEMS AND MANUFACTURING,INC		ST10084SC	737-100, 737-200, 737-300	Installation of an Innovative Solutions & Support (IS&S) digital air data system consisting of an electric altimeter, Digital Air Data Computer (DADC), Air Data Display Unit (ADDU), and an altitude alerter in accordance with ASM Master Data List 5572-0001-00, Revision C, Dated October 2, 2002 or lat...		- ASM Master Data List 5572-0001-00, Revision C, Dated October 2, 2002 or later EASA approved revision.- AirplaneFlight Manual Supplement No 5572-21600-00, Revision IR, dated October 17, 2002, or later EASA Approved Revision		15/03/2007	Active	10015950
EASA.IM.A.S.02094	BARBARA AND ROBERT WILLIAMS		SA572CE	A150L A150K 150M 150L 150K 150J 150H 150G 150F 150E 150D 150C 150B 150A 150	Replacement of Continental O-200A with Lycoming 150 or 160hp Model O-320 engines		Installation, operation and Maintenance in accordance with the documents and data contained in FAA STC SA572CE at latest approved revision	As defined in FAA STC SA572CEModified engine mounting structure and relocated battery installation must be inspected every 500 flight hours or annually, whichever occurs earlier for any cracking or corrosion and if found rectified with anEASA approved repair scheme	20/09/2006	Active	10015952
EASA.IM.A.S.02095	ANCRA INTERNATIONAL LLC	REV. 1	FAA STC ST01926LA	747-400	Installation of Main Deck Cargo Loading System		FAA STC ST01926LA.Ancra International Controlled Data List DL84400-10-4 Revision A dated October 09 2006 or later approved revision.	EASA STC EASA.IM.A.S.02039 must be installed in conjunctionwith this installation.This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/ en...	12/01/2007	Active	10015953
EASA.IM.A.S.02097	CERTIFICATION DOCUMENTS ANDPRODUCTS (CDP) LLC		FAA STC ST10674SC	CESSNA 750 CITATION X	Installation of an Aerodata AG Automatic Flight Inspection System (AFIS).		Installation in accordance with Master Drawing List FISR00002, Rev A, dated June 5, 2007, or later approved revision.Operation to be in accordance with Approved Airplane Flight Manual Supplement ref. AFISR00011, Rev IR, dated June 28, 2007, or later approved revision.Instructions for continued airwo...	Limited to Aircraft Serial Number 262 only.	15/10/2007	Active	10015954
EASA.IM.A.S.02098	BOMBARDIER COMPLETION CENTRE INC		C-LSA06-256/ D	BOMBARDIER BD-700-1A11	Aircraft Completion, 13 Passenger Interior ConfigurationValidation of TCCA Limited STC C-LSA06-256/D to S/N 9188MDL: E786000 Rev NC or later TCCA approved revisions		SoC: C-06-0642, dated Sep 28, 2006FMS: G-FM25000140 Rev NC or later TCCA approved revisionsIFCA: GC91880000-IFCA	Refer to the Limitations sections of the required FM Supplement WLAN system os compatible only to IEEE 802.11(b).	04/10/2006	Active	10015955

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02100	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA06-291/D	BOMBARDIER BD-700-1A10	Aircraft Completion, 12 Passeger Interior ConfigurationValidation of TCCA Limited STC C-LSA06-291/D to S/N 9189MDL: F015000 Rev NC or later approved revisions		SoC: C-06-0611, dated Nov 24, 2006FMS: G-FM25000143 Rev NC or later approved revisionsIFCA: GC91890000-IFCA IR	Refer to the Limitations sections of the required FM SupplementWLAN system is compatible only to IEEE 802.11 (b)The use of WLAN is subject to operational rules.	30/11/2006	Active	10015957
EASA.IM.A.S.02101	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA06-336/D	BOMBARDIER BD-700-1A11	Aircraft Completion, 13 Passenger Interior ConfigurationValidation of TCCA Limited STC C-LSA06-336/D to S/N 9204MDL: F082000 Rev NC or later approved revisions		SoC: C-06-0896, dated Nov 24, 2006FMS: G-FM25000145 Rev NC or later approved revisionsIFCA: GC92040000-IFCA IR	Refer to Limitation sections of the required FM Supplement	05/12/2006	Active	10015958
EASA.IM.A.S.02102	BOMBARDIER COMPLETION CENTRE INC		C-LSA06-321/D	BOMBARDIER BD-700-1A10	Aircraft Completion, 14 Passenger Interior CompletionValidation of TCCA Limited STC C-LSA06-321/D to S/N 9200MDL: F099000 Rev NC or later TCCA approved revisions		SoC: C-06-0854, dated Dec 18, 2006FMS: G-FM25000147 Rev NC or later TCCA approved revisionsIFCA: GC92000000-IFCA IR	Refer to the Limitations sections of the required FM SupplementWLAN system is compatible only to IEEE 802.11 (b).The useof WLAN is subject to operational rules.	20/12/2006	Active	10015959
EASA.IM.A.S.02103	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA07-015/D	BOMBARDIER BD-700-1A10	Customized Interior Completion - SN 9196.Validation of TCCA STC C-LSA07-015/D.		AFM Supplement G-FM25000148.TCCA SoC letters C-06-0667 dated November 09, 2007.Instructions for Continuous Airworthiness : GC91960000-IFCA.	Refer to the Limitations sections of the required AFM Supplement.WLAN system is compatible only to IEEE 802.11 (b).The use of WLAN is subject to operational rules.	29/11/2007	Active	10015960
EASA.IM.A.S.02106	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA07-013/D	BOMBARDIER BD-700-1A10	Aircraft Completion, 13 Passenger Interior ConfigurationValidation of TCCA Limited STC C-LSA07-013/D to S/N 9202MDL: F018000 Rev NC or later TCCA approved revisions		SoC: C-06-0613 E786 dated Mar 01, 2007FMS: G-FM25000151 Rev NC or later TCCA approved revisionsIFCA: GC92020000-IFCA	Refer to the Limitations sections of the required FM SupplementWLAN system is compatible only to IEEE 802.11 (b).The useof WLAN is subject to operational rules.	21/03/2007	Active	10015961
EASA.IM.A.S.02110	HONEYWELL INTERNATIONAL INC.		FAA STC ST00844SE	BAE 146/AVRO 146 SERIES	Installation of the Flight Data Acquisition Management System (FDAMS)		No change to existing documents	This change is not JAR-OPS-1.715 (EUROCAE ED55) compliant in the following parameters:Parameter 6, Pitch Attitude is only sampled once per second.Parameter 7, Roll Attitude is only sampled once per second.Parameter 23, Ground Spoiler position, Brake Selection is only sampled once per second with a R...	13/12/2006	Active	10015962
EASA.IM.A.S.02112	THE NORDAM GROUP LLC		FAA STC ST10526SC	LEARJET MODEL 45	Replacement of Thrust Reverser Control UnitFAA STC ST10526SC		FAR Compliance Matrix NTR-ER 0403, rev. CJAR Compliance Matrix NTR-ER 0605, rev. AMaster Drawing List NTR-ER 0405, rev.EInstructions for Continued Airworthiness NTR-ER 0406, rev.A		21/03/2007	Active	10015963
EASA.IM.A.S.02113	AIRCRAFT SYSTEMS AND MANUFACTURING,INC		ST09744SC	BAE 146/AVRO 146 SERIES	Installation of a Digital Flight Data Recorder (DFDR) Expanded Parameter Sensor Upgrade on a British Aerospace Avro 146-RJ85A Aircraft		ASM Top Drawing List 5561-0001-00, Revision D, dated July 10, 2000, or later FAA approved revision	None	19/07/2006	Active	10015964
EASA.IM.A.S.02114	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST09639SC	GULFSTREAM 200	Installation of an Allied Signal DFDR i.a.w. MDL30-11000007		AFMS 30-1120011		16/10/2006	Active	10015965
EASA.IM.A.S.02115	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST09945SC	GULFSTREAM 200	Installation of Lead Acid Batteries i.a.w. MDL30-1100014		AFMS 30-1120013		16/10/2006	Active	10015966
EASA.IM.A.S.02118	BOMBARDIER AEROSPACE		TCCA STC C-LSA06-317/D	BOMBARDIER BD-700-1A10	Aircraft Completion, 14 Passenger Interior ConfigurationValidation of TCCA Limited STC C-LSA06-317/D to S/N 9197MDL: F017000 Rev NC or later TCCA approved revisions		SoC: dated Jan 31, 2007FMS: G-FM25000146 Rev NC or later TCCA approved revisionsIFCA: GC91970000-IFCA	Refer to the Limitations sections of the required FM SupplementWLAN system is compatible only to IEEE 802.11 (b).The useof WLAN is subject to operational rules.	31/01/2007	Active	10015967

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02119	CIRRUS DESIGN CORPORATION		SA01355WI-D	CIRRUS SR20	Validation of FAA STC SA01355WI-D – “Installation of Bendix/King KR87 ADF and/ or KN 62A DME”		Installation in accordance with Master Drawing List 159-08310-0001, Rev. C, or later FAA approved Revision	1. The installer must determine, if this design is compatible with previously approved modifications. If the holder agrees to permit another person to use this certification oralter a product, the holder must give the other person written evidence of that permission.2. This STC is approved on...	15/05/2007	Active	10015968
EASA.IM.A.S.02120	GULFSTREAM SERVICES CORPORATION		FAA STC ST03295AT-D	GULFSTREAM GV-SP	Completion and installation of the custom interior on Aircraft Serial 5116		In accordance with Gulfstream Aerospace Corporation Master Index List GC51 4915116, Revision D, dated October 20, 2006,or later approved revisionsFAA approved Flight Manual Supplement, GC51 504M001, Revision NC, dated December 22, 2004, or later approved revisions	Aircraft Serial 5116 OnlyThe following STC's are required to be installed as part of this STC:- FAA STC ST02915AT-D, EASA Approved ref: EASA.IM.A.S. 01569,FAA STC ST02796AT-D, EASA Approved ref: EASA.IM.A.S.01259,FAA STC ST02696AT-D, EASA Approved ref: EASA.IM.A.S.02147,FAA STC ST02715AT-D, ST02697AT-...	09/11/2006	Active	10015969
EASA.IM.A.S.02121	FIRST AIR MAINTENANCE SERVICES		SA06-39	AEROSPATIALE ATR 72-202 AEROSPATIALE ATR 72-201 AEROSPATIALE ATR 72-102 AEROSPATIALE ATR 72-101 AEROSPATIALE ATR 42-320 AEROSPATIALE ATR 42-300	Installation of Dual SAGEM F227 APIRS Attitude and Heading Reference System		Installation must be in accordance with First Air Master Data List MDL-06-001, Revision A, dated 20th November 2006 or later approved revisions.Operation must be in accordance with First Air Flight Manual Supplement AFMS 06-004 Issue 1, 13th March 2006 or later approved revisions.Maintenance must be...	This STC is approved only for the aircraft modelsATR 42-200/ 300 / 320 / 400 / 500ATR 72-101 / 102 / 201 / 202 / 211 / 212 / 212 Afor those serial numbers fitted with the Honeywell AH600 AHRS as per originally manufactured and delivered by ATR (Type Design i.a.w EASA Type Certificate Data Sheets TC...	16/01/2007	Active	10015970
EASA.IM.A.S.02122	L3 AVIATION PRODUCTS, INC		FAA STC ST02111AT	F28 MARK 0100	Addition of three parameter outputs (Control column, control wheel, and ruddel pedals) to the existing Digital flight data recorder(DFDR) to meet requirements for FAR 121.344 (c) and (d)		Flight Systems Engineering Report for the Additional Parameters for Flight Recording System on Fokker, F-100 Aircraft, L3 Communications Document No. FSE 98-06-01, Revision C.	1. n/a	20/12/2006	Active	10015971
EASA.IM.A.S.02123	DUNCAN AVIATION, INC.		FAA STC ST01159WI-D	LEARJET 36A LEARJET 35A LEARJET 31	Installation of Honeywell Mk-VIII EGPWS.FAA STC ST01159WI-D		Certification Plan 060421001, rev.-AFM Supplement 40026700,rev. A.	None.	17/01/2007	Active	10015972
EASA.IM.A.S.02124	AMTECH AERONAUTICAL LIMITED		SA02-132, ISSUE NO.3	382G	Oil Dispersant Spraying System Installation on Lockheed 328G aircraft.		Airplane Flight Manual Supplement FMS243901 Rev. 4 dated November 4, 2005AFI Operating Manual OP2439 Rev. 3 dated August 2005Instructions for Continued Airworthiness as detailed in Amtech ICA996201 Rev. 2, dated October 29, 2004.Maintenance Manual Supplement MMS243901, Rev. 2 dated November 4, 2005...	Operation in accordance with Airplane Flight Manual Supplement FMS243901 Rev. 4 dated November 4, 2005 or later TCCA approved revision in conjunction with AFI Operating Manual OP2439 Rev. 3 dated August 2005 or later TCCA approved revision.Instructions for Continued Airworthiness as detailed in Amte...	01/02/2007	Active	10015973
EASA.IM.A.S.02125	TIMCO AVIATION SERVICES INC.		FAA STC ST03300AT-D	AIRBUS A321	Installation of a doghouse (storage container) in the bulk cargo compartment.		Master Data List, Document Number 05T101L001, Revision a, dated 26 September 2006, or later EASA approved revision.Instructions for Continued Airworthiness, Document Number 05T101R008, Revision IR, dated 06 September 2006, or later EASA approved revision.	Limitations and Conditions specified in FAA STC ST03300AT-Dremain applicable.	18/01/2007	Active	10015974

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02126	ASSOCIATED AIR CENTER, L.P.		FAA STC ST10613SC	A319-115	Executive style interior (validation of FAA STC ST10613SC)		Index List ref.: 2393000001, dated March 8, 2007 or later approved revisionMaster Drawing List, ref.: 2393000030E, dated March 13, 2007 or later approved revisionAirplane Flight Manual Supplement, ref.: 2393021090E, dated March 13, 2007 orlater approved revision	Instruction for Continued Airworthiness, Chapter 3 "Airworthiness Limitation", ref. 2393050090, dated March 8, 2007 or later approved revision	19/03/2007	Active	10015975
EASA.IM.A.S.02128	ELLIOTT AVIATION		FAA ST5990CH-T	FALCON 10	ST02333CH: Installation of a Universal Avionics SystemsCorporation(UASC) UNS-1K+/L FLIGHT MANAGEMENTSYSTEM (FMS), Dual Universal Avionics Radio ControlUnits (RCU), and/or dual Rockwell Collins VIR-32Navigation Receiver		-MDL-2651-000 Rev.C dtd 19.Oct.2006--AFM supplement(AFMS) / Instructions for ContinuedAirworthiness (ICAW) as per MDL-2651-000 Rev.C:---AFMS FMS-2651-000 Rev. IR dtd.18. Jul 2006 or later approvedrevision OR---AFMS FMS-2651-001 Rev. A dtd.19.Oct 2006 or later approvedrevision---ICAW ICA-2651-000 Rev....	1. Certification basis FAR 25 Amdt 117	13/02/2007	Active	10015976
EASA.IM.A.S.02130	ELLIOTT AVIATION		SA01216CH	BEECH B300C BEECH B300 BEECH B200T BEECH B200CT BEECH B200C BEECH B200 BEECH 300LW BEECH 300 BEECH 200CT BEECH 200C BEECH 200	Installation of Honeywell (Allied Signal) MK-VI Enhanced Ground Proximity Warning System, Universal Avionics Systems Corporation Terrain Awareness Warning System and Universal Avionics Systems Multifunction Display		Elliott Aviation Master Document List 2007-571 MDL Rev 2, dated May 4, 2002 or later FAA approved revision.	1. Compatibility of this design change with previously approved modifications must be determined by the installer.2. Airplane Flight Manual Supplement, Elliott Aviation Report No.EGPWS-FMS Rev 1, FAA approved August 23, 2000, or later FAAapproved revision, is required onboard the aircraft modified...	24/08/2006	Active	10015978
EASA.IM.A.S.02131	MICRO AERODYNAMICS, INC.		FAA STC SA00887SE	CESSNA U206G CESSNA U206F CESSNA U206E CESSNA U206D CESSNA U206C CESSNA U206B CESSNA U206A CESSNA U206 CESSNA TU206F CESSNA TU206E CESSNA TU206D CESSNA TU206C CESSNA TU206B CESSNA TU206A CESSNA TP206E CESSNA TP206D CESSNA TP206C CESSNA TP206B CESSNA TP206A CESSNA T207A CESSNA T207 CESSNA T206H CESSNA P206E CESSNA P206D CESSNA P206C CESSNA P206B CESSNA P206A CESSNA P206 CESSNA 207A CESSNA 207 CESSNA 206H CESSNA 206	Installation of vortex generators on the wings, tail surfaces and vertical fin		In accordance with Micro Aerodynamics Drawing Package MA2146, Revision A, dated March 11, 2004 and installed in accordance with Installation Manual MA2147, Revision IR, dated January 25, 2001 (for 206 series) or MA2196, Revision IR, dated March11, 2004 (for 207 series), or later approved revisions....	1. If more than Five vortex generators are damaged or missing, the aircraft is not airworthy2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be d...	20/09/2006	Active	10015979

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02132	DEL-AIR		FAA STC SA5733SW	CESSNA A152 CESSNA 152 CESSNA 150M CESSNA 150L CESSNA 150H CESSNA 150G CESSNA 150F CESSNA 150E CESSNA 150D CESSNA 150C CESSNA 150B CESSNA 150A CESSNA 150	Installation of Longe Range Wing Fuel Tanks		Custom Aircraft Conversions Inc. Drawing List No. C1502-000, revised 05/10/87 and Revision B, dated 02/24/96, or later approved revisions.	1. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall givethe other person written evidence of that permission.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragra...	14/08/2006	Active	10015980
EASA.IM.A.S.02133	HORTON STOL-CRAFT INC.		FAA STC SA989CE	CESSNA 170B CESSNA 170A	Installation of STOL Kit(Wing leading edge cuffs, drooped tips, stall fences and aileron gap seals)		- In accordance with data and drawings called out by STOL-Craft Drawing list 1, or later approved revisions.- Operated in accordance with STOL-Craft Inc FAA approved FlightManual Supplement dated January 29, 1974, or later approvedrevisions.	1. Aircraft to be placarded "Intentional Spins Prohibited".2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer....	04/09/2006	Active	10015981
EASA.IM.A.S.02134	HAWKER BEECHCRAFT CORPORATION (HBC)	REV. 3	FAA STC ST00459NY	HAWKER 900 XP HAWKER 850 XP HAWKER 800 XP HAWKER 800 HAWKER 750	Installation of an Allied Signal (Garrett) GTCP 36-150W gasturbine Auxiliary Power Unit (APU).		1. Installation in accordance with:- PATS, Inc Installation Master drawing List No RH1001, Rev E, dated December 12, 1997, or PATS Inc Master Drawing List No RH1001, Rev G, dated May 31, 2006, and PATS, Inc Master Drawing List RH5001, Rev G, dated June 2, 2006, and PATS, Inc. Installation Inst...		16/06/2008	Active	10015982
EASA.IM.A.S.02135	FIELD AVIATION COMPANY INC.		SA93-81	BOMBARDIER DHC-6 SERIES 300 BOMBARDIER DHC-6 SERIES 200 BOMBARDIER DHC-6	Roof Access Steps Installation		Transport Canada Sa93-81Field Aviaiton Company Inc Engineering Data Summary 112200 Revision A dated April 13, 1993 or alter approved revision	--	13/11/2006	Active	10015983
EASA.IM.A.S.02136	DEL-AIR		FAA STC SA01388SE	CESSNA 172P CESSNA 172N CESSNA 172M CESSNA 172L CESSNA 172K CESSNA 172J CESSNA 172I CESSNA 172H CESSNA 172G CESSNA 172F CESSNA 172E CESSNA 172D CESSNA 172C CESSNA 172B CESSNA 172A CESSNA 172 CESSNA 170B CESSNA 170A	Installation of a 7 Gallon extended range tank in each wing.		Manufactured and installed in accordance with Data List No 11000-6, Rev IR, dated December 23, 2003, Data List No 11000-1, Rev IR, dated December 23, 2003 and installation Instructions DA Report No 152, Rev N/C, dated September 12, 2002, or later approved revisions.Operation in accordance with Airpl...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	18/09/2006	Active	10015984
EASA.IM.A.S.02138	HARTZELL SERVICE CENTER		FAA STC SA01024CH	PIPER PA-28RT-201T PIPER PA-28R-201T	Installation of a Hartzell PHC-C3YF-1RF/ F7663-4T propeller and C-3570(P) spinner in accordance with Hartzell installation instructions HP2834 dated February 3, 1999 or later approved revision (validation of FAA STC SA01024CH)		FAA approved Airplane Flight Manual Supplement HP283-AFMS dated February 11, 1999 or alte approved revision, is required for PA-28R-201T (Turbo Arrow III)FAA approved Airplane Flight Manual Supplement HP284-AFMS dated February 12, 1999 or later approved revision, is required for PA-28RT-201T (Turbo...	The aircraft complies with annex 16, volume I, third edition, amendment 7, chapter 6. The certified noise level is 75.1dB(A) at 2575 rpmThis STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other...	09/11/2006	Active	10015985

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02139	O&N AIRCRAFT MODIFICATIONS, INC.		FAA STC SA1035NE	CESSNA 152 CESSNA 150M CESSNA 150L CESSNA 150K CESSNA 150J CESSNA 150H CESSNA 150G CESSNA 150F	Installation of a 14.6 gallon aft fuselage tank in baggage compartment.		Installation in accordance with drawing list No. ON-1025 rev. B, dated 21-07-92, or later approved revisions.AFM-Supplements as mentioned below	1. FAA Approved Supplement to Pilot's Operating Handbook and / or FAA Approved Airplane Flight Manual, Nr. 19, 20 and 21, dated Jan. 13-93, or later approved revision, is requiredCessna 150F, G, H, J, K ,L & M and 152.2. This installationis not eligible for use with 38-gallon optional long range t...	13/10/2006	Active	10015986
EASA.IM.A.S.02141	DUNCAN AVIATION, INC.		ST02092CH-D	HAWKER 800 XP	Installation of a forward cabin entry door and aft cabin reconfiguration		Installation to be in accordance with Duncan Aviation Master Drawing list 060502016 , Rev A, dated, July 7, 2006 or later approved revision.Continued Airworthiness to be in accordance with Duncan Aviation Instructions for Continued Airworthiness ref doc 060502017 rev 0 dated, 5-19-06 or later approv...	Applicable to Aircraft Serial Number 258645 only	20/09/2006	Active	10015987
EASA.IM.A.S.02142	GULFSTREAM AEROSPACE CORPORATION		ST02048CH-D	GULFSTREAM GV-SP	Installation of the Airshow 4000		Installation in accordance with Gulfstream Master Drawing List GC515046000, Revision D, dated August 2, 2005, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC51 504M000, Revision –, dated 1 June 2005	--	14/12/2006	Active	10015988
EASA.IM.A.S.02144	GULFSTREAM AEROSPACE CORPORATION		ST02047CH-D	GULFSTREAM GV-SP	Installation of Magnastar Radio Telephone System		Installation in accordance with Gulfstream Master Drawing List GC511046000, Revision D, dated August 2, 2005, or later approved revisions.	--	14/12/2006	Active	10015990
EASA.IM.A.S.02145	AVIATION FABRICATORS, Inc.		FAA SA4147SW	HS 125 SERIES 800, 800 XP, 1000	Installation of one, two, three & four-place side facing seat.		Installation of one, two, three & four-place side facing seat according to Custom Aircraft Conversions Drawing 01125 dated 12. June1980, or later approved revision; or Aviation Fabricators STC Drawing List AF-177 dated 06. December 1994 orlater approved revision	This STC grants no operational approval to this installation, that will need to be obtained from the State of registry for the particular aircraft involved as defined in JAR OPS1.	30/10/2006	Active	10015991
EASA.IM.A.S.02146	ELECTRONIC CABLE SPECIALISTS, Inc.		ST00694CH	DC-9-87 (MD-87) DC-9-83 (MD-83) DC-9-82 (MD-82) DC-9-81 (MD-81)	Installation of Dual Honeywell HT9100 GNSS GPS Navigation System.		¿ Master Data List ECS-970034, Rev. R ¿ Summary Compliance Report ECS-206105, Rev. N/C¿ AFM Supplement ECS-970047, Rev. B ¿ Instructions for Continued Airworthiness ECS-204077, Rev. A	1. Limited to configuration III and IV.2. Compatibility of this design change with previously approved modifications must be determined by the installer.3. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Descripti...	21/05/2007	Active	10015992

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02147	GULFSTREAM SERVICES CORPORATION		FAA STC ST02696AT-D	GULFSTREAM GV-SP	Installation of Passenger Oxygen System		In accordance with Gulfstream Aerospace Corporation Index List GC514538000, Revision B, dated August 5, 2003 or later approved revisionFAA approved Flight Manual Supplement. GC51453M003, Revision NC, dated August 19, 2003 or later approvedrevision is required for the -101 configurationFAA approvedi...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	28/08/2006	Active	10015993
EASA.IM.A.S.02148	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST03270AT-D	GULFSTREAM 200	Installation of a proective shroud around the 60Hz inverter		Index List: CEB2 4938000, Rev. B or laterInstructions for Continued Airworthiness: CEB2 493A000		21/11/2006	Active	10015994
EASA.IM.A.S.02151	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02290CH-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion Aircraft Serial 5114.		Install in accordance with Gulfstream Aerospace Report GC522043003, Revision A. and Master Drawing List GC522046037, Revision D, dated November 29, 2006, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52 204M013, Revision A, dated 29 November 2...	Aircraft Serial No 5114 Only.	14/12/2006	Active	10015995
EASA.IM.A.S.02152	S-TEC CORPORATION		FAA STC SA09124AC-D	PIPER PA-60-602P PIPER PA-60-601P	Installation of S-TEC 55/55X two axis automatic flight control system in Aerostar models		- STC SA09124AC-D- AFM Suppl. P/N891204S Rev. 2- IfCA P/N 81319 Rev. 2- S-TEC Bulletin 706 Rev. 2- MDL No. 92812 Rev. B	1. According to AFMS, Section 2 Operating Limitation2. Instructions for continued airworthiness acc. Doc. P/N 81319 Rev. 23. Maintenance Instructions 2.-4. must be performed every 100 flight hours or once every calender year, whichever comes first.4. This STC is approved only for the pro...	29/08/2006	Active	10015996
EASA.IM.A.S.02154	BOMBARDIER INC.		TCCA STC C-LSA07-003/D	BOMBARDIER BD-100-1A10 (CHALLE	Aircraft completion, 10 passenger interior configuration, in accordance with MDS f070000 (Original STC number: Transport Canada STCC-LSA07-003/D)		AFM Supplement F070090.	Limited to S/N 20111.	12/01/2007	Active	10015997
EASA.IM.A.S.02155	TIMCO AVIATION SERVICES INC.		FAA STC ST03342AT-D	BOEING MD-88 BOEING DC-9-87 (MD-87)	Installation of a Door Safety Strap		TIMCO Master data list 06T 005L001, Revision B dated October 11, 2006 or later FAA approved revision	1. TIMCO's Instructions For Continued Airworthiness 06T005R014, Rev. IR dated June 8, 2006, is a required part of this STC.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other airc...	24/10/2006	Active	10015998
EASA.IM.A.S.02157	BOMBARDIER AEROSPACE		TCCA STC SA06-88	CL-600-2B16	Activation of Runway Awareness Advisory System (RAAS) Functionality.		TCCA STC SA06-88, dated 16-11-2006 or later approved revision.Aero Consulting Services Modification Data Summary F036000 Revision N/C or later approved revisions.Aero Consulting Services AFM Supplement F036091 Revision N/C or later approved revisions.		06/09/2007	Active	10015999

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02158	JETPROP, LLC.		ST00541SE	PA-46-350P (MIRAGE) PA-46-310P	Installation of PWC PT6A-34/-35/-21 turboprop engines in any combination withHartzell Propellers:HC-E4N-3I/ E8501B-3.5HC-E4N-3M/E8190KHC-E4N-3N/D8292HC-E4N-3N/D8292 (B,K)-2and MT-Propeller:MTV-16-1-E-C-F-R(P)/CFR206-58aon Piper PA-46-310P and PA-46-350P airplanes		FAA Approved Airplane Flight Manual Supplement, change 20 or later approved change, Document No. 560.1002EASA, including EASA approval sheet, Approval No. EASA.IM.A.S. 02158JetpropDLX Maintenance Manual , Document No. 560.1001, Change 8 orlaterRocket Engineering Master Drawing List 560.00.00, Revis...	PT6A-34, rated at 560 HP, 2200 RPMPT6A-35, rated at 560 HP,2190 RPMPT6A-21, rated at 550 HP, 2200 RPMThis airplane/engine/propeller combination is life limited. The life limit for the modified airplane shall be determined by using the minimum value calculated by the following formulas:T = To + 0.9T...	24/04/2008	Active	10016000
EASA.IM.A.S.02163	TIMCO AVIATION SERVICES INC.		FAA STC ST01216AT-D	AIRBUS A300	Installation of Airshow 210 System		TIMCO Master data list, MDL-01094, Rev. LConfiguration Document, CFG-01105, Rev. E	--	08/10/2006	Active	10016002
EASA.IM.A.S.02164	FIELD AVIATION COMPANY Inc.		O-LSA06-179/ D ISSUE 1	BEECH B200 SUPER KING AIR	Installation of a single Universal UNS-1F Flight ManagementSystem complete with dual Universal GLS-1250 DGPS Receivers(SCAT-1).Transport Canada LSTC O-LSA06-179/D Issue 2.		Configuration AUNS-1F c/w GLS-1250 Electrical and structural Provisions:- Installation of the UNS-1F retrofit modifications must be performed in accordance with FAEL Master Drawingand Data List designatedDDL-1163 Rev IR, or later approved revisions.Installation of the GLS-1250 retrofit modifications...	Aircraft Serial BB-1547 onlyThe UNS-1F Flight Management System is approved for En-route, Terminal and Non Precision Approach Operations only.	05/02/2007	Active	10016003
EASA.IM.A.S.02166	AVIADESIGN Inc.		FAA STC SA3783NM	BEECH B200T, 300, 1900, 1900C BEECH B200, B200C, B200CT BEECH 200, 200C, 200CT, 200T	Installation of upper wing reinforcing kit.		In accordance with FAA sealed Aviadesign Inc Master DrawingListE.O.-B-8808, dated March 10, 1988, or later approved revision.	1. Reinforcing strap and original wing structure covered bythe strap tobe inspected every 1000 flying hours or annually for any signs ofcracking or corrosion.2. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".C...	19/09/2006	Active	10042989
EASA.IM.A.S.02168	AVIATION FABRICATORS, Inc.		FAA ST01139WI	560	Installation of a 39-inch or a 45-inch two-place divan or a24-inch one-place divan per Aviation Fabricators STC Data Package, AF-342, Rev A, dated 12, June, 2003 and stamped "FAAApproved" with an approval date of October 22, 2003 or later approved revision		STC Data Package, AF-342, Rev A, dated 12, June, 2003 and stamped "FAA Approved" with an approval date of October 22, 2003 or laterapproved revision	The STC covers only installation of parts contained in the Description sectionUpholstery, covers, aisle width, oxygen, seat belts are not covered	13/09/2006	Active	10016005
EASA.IM.A.S.02170	CLIPPER AVIATION, Inc.		FAA STC ST02318NY	BOEING 747-400 FREIGHTER	Upper Deck seating arrangement for B747-400BCF as defined in Weber Aircraft installation drawing No. 860014 and ClipperAviation CLI-2006-003 Rev. A, Master Data List B747-400BCF		CLI-2006-007 Airplane Flight Manual Supplement for Boeing 747-400 Special Freighter	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	04/04/2007	Active	10016006
EASA.IM.A.S.02172	VISIONSAFE LLC	REV. 1	FAA STC ST01057W1	BD-700-1A10, BD-700-1A11	Installation of Emergency Vision Assurance System (EVAS) Model: 107STC-191 and 107 STC-192		-MDL: Midcoast Aviation 35-416G001 Rev A or Vision Safe No.206 Rev H-AFM-Supplement: Midcoast Aviation 35-416M001 Rev Original or VisionSafe No. 1, Rev 1or later revisions of theabove listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis de...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	10/02/2009	Active	10016007

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02175	JCM AERODESIGN LIMITED		O-LSA06-268/ D ISSUE 1	BOMBARDIER DHC-8-311	EMS Installation as per TCCA Limited Supplemental Type Certificate O-LSA06 268/D, Issue 1, dated 13 September 2006		Installation must be in accordance with Spectrum Aeromed Inc. Master Document List 6039-1A revision 1 or later TCCA approved revision.Operation must be in accordance with SpectrumAeromed Inc. Flight Manual Supplement 6039-1FMS at Revision1 or later TCCA approved revision.Maintenance must be in acc...	DHC-8-311, S/N. 216	20/12/2006	Active	10016010
EASA.IM.A.S.02176	BOMBARDIER COMPLETION CENTRE INC			BOMBARDIER BD-700-1A11	Aircraft Completion, 13 Passenger Interior ConfigurationValidation of TCCA Limited STC C-LSA06-335/D to S/N 9198MDL: F069000 Rev NC or later approved revisions		SoC: C-06-0891, dated Nov 24, 2006FMS: G-FM25000144 Rev NC or later approved revisionsIFCA: GC91980000-IFCA IR	Refer to Limitation sections of the required FM SupplementWLAN system is compatible only to IEEE 802.11 (b)The use of WLAN is subject to operational rules.	05/12/2006	Active	10016011
EASA.IM.A.S.02178	CESSNA AIRCRAFT COMPANY		ST01399WI	CESSNA 750 CITATION X CESSNA 650 CITATION VII CESSNA 650 CITATION VI CESSNA 650 CITATION III CESSNA 560	Cessna STC ST01399WI, of 21 August 2006.Installation of a Honeywell DL-950 Data Loaderto replace the existing DL-800.		Approved Model List No. CMR-750-115, of 20 June 2006.Installation Instructions No. CMR-750-111, of 27 Oct. 2005No AFM Supplements		05/02/2007	Active	10016012
EASA.IM.A.S.02179	ROCKWELL COLLINS, Inc.		FAA STC SA2685CE	BOEING MD-88 BOEING DC-9-87 (MD-87) BOEING DC-9-83 (MD-83) BOEING DC-9-82 (MD-82) BOEING DC-9-81 (MD-81)	Installation of Collins Traffic Alert and Collision Avoidance System (TCAS II)		STC No. SA2685CEDrawing Index DWG No. 992-1952-001 (Rev. J)AFM Supplement ACC-99-056 (dated 30.September 1999)	Installation of Mode S Transponder System STC EASA.IM.A.S.02180 (SA2684CE) or EASA. IM.A.S. 02181 (SA3082SO) is a prerequisite to this modification.	04/01/2007	Active	10016013
EASA.IM.A.S.02180	ROCKWELL COLLINS, Inc.		FAA STC SA3082SO	BOEING MD-88 BOEING DC-9-83 (MD-83) BOEING DC-9-82 (MD-82) BOEING DC-9-81 (MD-81)	Installation of Dual Collins TPR-720 Mode S Transponders		STC SA3082SO.Master Drawing List MDL-91-47 Rev. C.	None.Registration (if applicable):-Serialnumber (if applicable):-	04/01/2007	Active	10016014
EASA.IM.A.S.02181	ROCKWELL COLLINS, Inc.		FAA STC SA2684CE	DC-9-81 (MD-81) BOEING MD-88 BOEING DC-9-87 (MD-87) BOEING DC-9-83 (MD-83) BOEING DC-9-82 (MD-82) BOEING DC-9-81 (MD-81)	Installation of Dual Collins Mode S Transponders.		STC SA2684CE.Drawing Index DWG No. 992-1953-001 Rev. C.	None.Registration (if applicable):-Serialnumber (if applicable):-	04/01/2007	Active	10016015
EASA.IM.A.S.02182	DASSAULT FALCON JET CORPORATION		ST10461SC-D	FALCON 900	Mid Cabin Door Installation, Enflite		AFMS 37700-1SMM 37681	This STC is Limited to F9EX-01056-501 Installations in Model Falcon 900EX.	27/10/2006	Active	10016016
EASA.IM.A.S.02183	DASSAULT FALCON JET CORPORATION		ST10510SC-D	FALCON 900	Aircraft Compliance for Falcon 900EX S/ N 165.		AFMS 37159-F9EX-D165SMM F900EX-SN165	Limited to S/N 165. No duplicate Installation permitted.	27/10/2006	Active	10016017
EASA.IM.A.S.02184	DASSAULT FALCON JET CORPORATION		ST10253SC-D	FALCON 900EX	Oxygen System Installation.		SMM 37140 and SMM 37347		27/10/2006	Active	10016018
EASA.IM.A.S.02187	GULFSTREAM SERVICES CORPORATION	REV. 1	FAA STC ST03256AT-D	GULFSTREAM GIV-X GIV	Installation of an Enhanced Surveillance Flight Identification Systemwith Collins Radio Tuning UnitsRev. 1: Typo correction		Installed in accordance with Gulfstream Aerospace Corporation Index List CE41 1268003, Revision D, dated November 09, 2006, or later approved revision.FAA approved Flight Manual Supplement, CE41 126M006 Revision B, dated November 10, 2006 or later approved revision is required for the -501 configura...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	15/03/2007	Active	10016021

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02188	SHADIN AVIONICS		ST02115CH	CESSNA S550 CESSNA 560 CESSNA 550 CESSNA 500	Validation of FAA STC ST02115CHInstallation of a dual Shadin "ADC 6000 System RVSM Capable": hardware provisions for RVSM cpability.		Master Data List DN2807A-002, Rev. N of 30 August 2005 or later approved revision and Report 2807A.AFM Supplements: see"Limitations and Conditions"	This STC does not provide RVSM capability to the aircraft (compliance to RVSM airworthiness requirements are not part of this STC):a separate STC has to be applied.Airplane FlightManual Supplement, Shadin Document No. DN2807A-006, Revision B, dated 23 September 2005 or later approved revision,is re...	07/12/2006	Active	10016022
EASA.IM.A.S.02191	TELAIR INTERNATIONAL, LLC	REV. 1	FAA STC ST00837 LA	BOEING 747-400F BOEING 747-400	Installation of a Cargo Handling System on the lower deck of the B747-400, -400F		FAA approved Telair International Index List IL 192100 Rev.C dated May 24, 1999 or later FAA approved revisions.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	12/01/2009	Active	10016023
EASA.IM.A.S.02192	BEECHCRAFT CORPORATION	REV. 2	FAA ST10432SC-D	HAWKER 900 XP HAWKER 850XP, HAWKER 900XP HAWKER 750, HAWKER 800XP	Installation of Mark V Enhance Ground Proximity Warning System (EGPWS) with and without Runway Awareness Advisory System.		1. In accordance with Master Drawing List 800-514 Revision D or later approved revision;2. Flight Manual Supplement 800-329 Revision R6 or later approved revision;3. Maintenance Manual Addenda 34-40-40.	1. The Flight Manual Supplement is not needed for the -101 installation because the aircraft's basic AFM is still applicable.2. When fitted to Hawker 800XP and 850XP this STC is limited to the following aircraft 258541, 258556, 258567 through 258609, 258611 through 258628, 258630 through 25868...	21/05/2008	Active	10016024
EASA.IM.A.S.02193	DASSAULT FALCON JET CORPORATION		ST09296SC-D	FALCON 2000	FAA STC ST09296SC-D: "Service and Indirect Lighting System"		see STC ST09296SC-D : - Drawing List Report F2M-01045 Rev.B dtd 31.Aug.00 or later approved revision		18/12/2006	Active	10016025
EASA.IM.A.S.02194	DASSAULT FALCON JET CORPORATION		SA8267SW-D	FALCON 2000	FAA STC SA8267SW-D: "Auxiliary Battery System"		see STC SA8267SW-D: - Drawing List Report F2M-01038 Rev. Hdtd 5.Jun.01 or later approved revision -AFM Supplement, Report 36482-1, dtd, 9.Aug 96 or later approved revision is required with F2M-01038-501 and -503 installation -AFM Supplement, Report 36482-2,Revision A dtd, 27.Jun 01 or later ap...		20/12/2006	Active	10016026
EASA.IM.A.S.02195	DASSAULT FALCON JET CORPORATION		SA8227SW-D	FALCON 2000	FAA STC SA8227SW-D: Automatic Electrical Load Shed System		see STC SA8227SW-D: - Drawing List Report F2M-01004 Rev. Gdtd 29.Nov.00 or later approved revision -AFM Supplement, Report 3672-1, Rev C dtd, 9.Oct 01 or later approved revision	-Systems or components connected to the shed system must have a separate approval different from STC SA8227SW-D -Shedded componentsare non essential equipment	18/12/2006	Active	10016027
EASA.IM.A.S.02197	LANDMARK AVIATION		ST00939CH-D	FALCON 10	Validation of FAA STC ST00939CH-D: Installation of a Honeywell Enhanced Ground Proximity Warning System (EGPWS) in accordance with Garrett Aviation Drawing List DL939 Revision F, dated 20th January 2005.		See:FAA STC ST00939CH-DAirplane Flight Manual Supplement AFMS201 Rev B for configurations 1,2 and 3Airplane Flight Manual Supplement 1002826 Rev B for configurations 4 and 6Airplane Flight Manual Supplement 1003542 Rev A for configuration 5Maintenance Manual Supplement MMS201 for configurations 1, 2...	Compatibility with previous approved modifications shall bedetermined by the installer.JAA Leaflet TGL 12 Certification Considerations for the Terrain Awareness Warning System: TAWS requisittes have been applied.Configurations 2 and 3 (without Terrain Display) do not qualify for a Class A TAWS equi...	06/02/2007	Active	10016028

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02198	ROCKY MOUNTAIN AIRCRAFT		TCCA STC SA01-30	DHC-6 100, DHC-6 200,DHC-6 300	Removal of Auxiliary Battery		Compliance Checklist C62766.	1. An approved Main Battery Installation with a minimum capacity of 34 Ampere-Hours must be embodied as a pre-requisite.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraf...	22/12/2006	Active	10016029
EASA.IM.A.S.02199	ROCKY MOUNTAIN AIRCRAFT		TCCA STC SA01-17	BOMBARDIER DHC-6 SERIES 300	Cabin Evacuation Lighting Control System Change.		Transport Canada STC SA01-17 Issue 2Master Data List MDL-1298-01Aero Design Ltd Flight Manual Supplement FMS396.02	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	10/10/2008	Active	10016030
EASA.IM.A.S.02200	TELAIR INTERNATIONAL, LLC	REV. 1	FAA STC ST00459LA	BOEING 747-400SF	Installation of a Cargo Handling System on the main deck ofthe B747-400SF inaccordance with FAA approved Telair International Index List ER 193100 Rev. N/Cdated October 21, 1997 or later approved revisions.Validation of FAA STC ST00459LA		Weight & Balance Control And Loading Manual Report Number 25-55-67 Revision –forMain Deck Cargo Handling System System Number 193100	1. The installation of this modification by third persons is subject to writtenpermission of the approval holder2. Prior to installation of this modification the installer must determine that theinterrelationship between this modification and any other previously installedmodification will introduce...	11/12/2008	Active	10016031
EASA.IM.A.S.02201	LANDMARK AVIATION		FAA STC ST01579CH-D	MYSTERE FALCON 20-F5 MYSTERE FALCON 20-E5 MYSTERE FALCON 20-D5 MYSTERE FALCON 20-C5 MYSTERE FALCON 200	Installation of a Honeywell MK-VIII Enhanced Ground Proximity Warning System (EGPWS)		- Garrett Aviation Services drawing List 70-0739-001, Revision -, dated April 11, 2002, or later approved revision;- FAA Approved Airplane Flight Manual Supplement document70-8739-003 revision - dated June 7, 2002, or later approved revision;- FAA Approved Airplane Flight Manual Supplemen...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	16/10/2006	Active	10016032
EASA.IM.A.S.02202	ROCKY MOUNTAIN AIRCRAFT		FAA STC SA02297NY	DE HAVILLAND CANADA DHC6-300 BOMBARDIER DHC-6 SERIES 200 BOMBARDIER DHC-6-100	(1) Installation of a Universal Avionics CVR-30B Cockpit Voice Recorder.(2) Installation of a Fairchild A100S, Honeywell SSCVR, or L3 FA2100 Cockpit Voice Recorder.		(1) Installation in accordance with Amtech Aeronautical Limited Modification, Data Summary MDS977801, Revision 2, datedJanuary 15,2002 or later approved revisions.(2) Installation in accordance with Field Aviation Company Inc Modification, Instruction 199010, Original Issue, dated March 22, 2005 or...	The installation applies only to aircraft not equipped withseparate P.A. microphone.Maintenance must be in accordance with Field Aviation Company Maintenance Manual Supplement Report No 199031, Original Issue, datedDecember 11, 2006, or later approved revisions.	22/10/2007	Active	10016033
EASA.IM.A.S.02203	AVIONICS GROUP INC.		FAA ST02997AT	737-400, 737-500 737-100, 737-200, 737-300	Installation of a Sandal Avionics ST3400 Class A Terrain Awareness and Warning System		Avionics Group, Inc. Master Drawing List AG-34-1111.MDL, Revision IR, dated January 10, 2004, or later approved revision	FAA approved Airplane Flight Manual Supplement for AvionicsGroup, Inc. Sandel Avionics ST3400 Class A Terrain Awareness and Warning System dated December 8, 2004 is a required part of this STC.	31/10/2006	Active	10016034
EASA.IM.A.S.02204	ROSEN SUNVISOR SYSTEMS L.L.C.	REV. 2	FAA STC SA4147NM	HAWKER 900 XP HAWKER 850 XP HAWKER 800 XP HAWKER 1000 BAE 125 SERIES 800A BAE 125 SERIES 1000A	Installation of Cockpit Sun Visors.		In accordance with Rosen drawing List Number RBA-800-00DL, Revision B, dated May 10, 2007, or later approved revisions.		21/05/2008	Active	10016035

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02205	SHADIN AVIONICS		FAA STC SA02098CH	CESSNA 501	Validation of FAA STC SA02098CH – “Installation of dual Shadin ADC 6000 Air Data Computer System” for RVSM capability		Shadin Master Data List Document No. DN2807B-002, Rev. K orlater FAA approved RevisionFAA approved Shadin AFM-S Doc. No. DN2807B-006, Rev. A, dated 01.09.2005 or later FAA approved Revision for aircraft modified with ADC-6000R, P-No 962861-00-00 or 962861-00-01FAA approved Shadin AFM-S Doc. No. DN2...	The installer must determine, if this design is compatible with previously approved modifications. If the holder agreesto permit another person to use this certification or altera product, the holder must give the other person written evidence of that permission.	10/04/2007	Active	10016036
EASA.IM.A.S.02206	LANDMARK AVIATION		FAA STC ST01579CH-D	MYSTERE FALCON 20-F5 MYSTERE FALCON 20-E5 MYSTERE FALCON 20-C5 MYSTERE FALCON 20-5 MYSTERE FALCON 200	Installation of a Honeywell MK-VIII Enhanced Ground Proximity Warning System (EGPWS) in accordance with Garrett Aviation Services Drawing List 70-0739-001 revision G dated 05th October 2005 or later approved revisions.EASA Validation of:Federal Aviation Administration (FAA) STC ST01579CH-D		• FAA STC ST01579CH-D.• Airplane Flight Manual Supplement 70-8739-003 Revision B or later approved revisions for aircraft configuration 01.• Airplane Flight Manual Supplement 69-8039-001 Revision C or later approved revisions for aircraft configuration 02.• Airplane Flight Manual Supplem...	1. JAA Leaflet TGL 12 Certification Considerations for the Terrain Awareness Warning System: TAWS requisites have been applied.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modi...	03/07/2007	Active	10016037
EASA.IM.A.S.02208	DELTA ENGINEERING CORPORATION	REV. 1	FAA STC ST02223NY-D	BOEING 767-200	Heath Tecna NuLook Interior		FAA STC ST02223NY-DMDL 0144-05988-2136 Rev c 12/07/2007.		17/09/2007	Active	10016039
EASA.IM.A.S.02209	JAMCO AMERICA, INC.	REV. 1	FAA STC ST01700SE	BOEING 747-400	Removal of the strengthened flight deck door and modification and reinstallation of luggage bins on the upper deck in accordance with Jamco Aero Design & Engineering Master Drawing List JD-03AC02 Rev. F or later revisions of the above listed documents approved byEASA in accordance with EASA ED decis...		1. JD-03AC02 Rev. F Master Drawing List B747-400 Pax to Freighter upper deck reconfiguration. 2. B747-25-MO5A Rev.F JADE Service Bulletin Pax to Freighter upper deck reconfiguration.	1. This STC is limited to the following aircraft after incorporation of Boeing SB 747-00-2004 Passenger to Freighterconversion:a. RT501 Sn. 24061b. RT506 Sn. 24066c. RT507 Sn. 24226d. RT509 Sn. 249752. This STC is approved only for the product configuration...	02/04/2007	Active	10016040
EASA.IM.A.S.02210	WESTERN AVIONICS		TCCA STC SA01-155 ISSUE 5	DE HAVILLAND CANADA DHC6-300	Installation or Upgrade of a Honeywell MK VI Enhanced Ground Proximity Warning System (EGPWS)		For installation:* Transport Canada approved Western Avionics Engineering Order No. 91429-401, Revision 2, dated 16-Mar-2006, or later approved issueFor Upgrade:* Transport Canada approved Western Avionics Engineering Order No. 91429-402, Revision 2, dated 16-Mar-2006, or later app...	Approval is limited to the CIC Air Data Module.This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/ engine configurations shall be determi...	12/01/2007	Active	10016041
EASA.IM.A.S.02213	HONEYWELL INTERNATIONAL Inc.		FAA STC ST01003CH-D	F3B, F3B/RA, 400A, 400B, 403B, DH. 125 SERIES 1A, 3A, 3A/RA, 600A, 600B, 700A, 700B	Installation of Honeywell N1 Digital Electronic Engine Control (DEEC).		Installation of Honeywell N1 Digital Electronic Engine Control (DEEC) in accordance with Garrett Aviation Services Drawing List DL1003, dated 26. Aug. 1999, no revision, or later approved revisions.Operation to be in accordance with an approved Airplane Flight Manual Supplement, document AFM230 date...	1. Compatibility of this modification with other previously approved modifications must be determined by the installer2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/...	12/12/2006	Active	10016042

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02214	DC AEROSPACE	REV. 1	ST03011AT	BOEING 727-200 SERIES BOEING 727-100 SERIES	Installation of Sandel ST3400 Terrain Awareness and Warning System (TAWS) in Boeing 727 Series Aircraft according to FAA STC ST03011AT dated 22 December 2004		- MDL-2418, Revision H dated 25 July 2005- AFM Supplement FMS-2418-1, Rev. IR dated 23 December 2004- Instructions for Continued Airworthiness ICA-2418, Rev. B dated 17 December 2004or later revisions of the above listed documents approvedby EASA in accordance with EASA ED decision 2004/04/CF (or s...	SANDEL mandatory SB 3400-09 to be incorporatedThe limitations as listed in FAA STC ST03011AT apply.	23/07/2007	Active	10016043
EASA.IM.A.S.02215	DASSAULT FALCON JET CORP.(SERVICE CENTER)		ST09737SC-D	FALCON 900EX	Bracket Installation for Mid Cabin Door i.a.w. Drawing ListReport " F90-01093		None		19/12/2006	Active	10016044
EASA.IM.A.S.02216	VISIONSAFE LLC		FAA STC ST00892LA	AIRBUS A330-343 AIRBUS A330-342 AIRBUS A330-341 AIRBUS A330-323 AIRBUS A330-322 AIRBUS A330-321 AIRBUS A330-301 AIRBUS A330-243 AIRBUS A330-223 AIRBUS A330-203 AIRBUS A330-202 AIRBUS A330-201	Installation of Emergency Vision Assurance System (EVASTM) / EASA Validation of FAA approved Supplemental Type Certificate ST00892LA.1. Boeing 737-600, -700, -700C, -800 and -9002. Airbus 330-201, -202, -203, -223, 243; Airbus 330-301, -321, 322, -323, -341, -342, -343 models		¿ FAA STC ST00892LA ¿ EVAS Compliance Summary for FAA Part 25 and EASA CS 25 dated March 2006¿ Master Drawing List Number 222 for Vision Safe Corporation - EVAS Model 107STC-215 and 107STC-216 - Airbus A330 Series and A340 Series, Revision G dated 4th April 2006 or later FAA approved revisio...	¿ Vision Safe Corporation Instructions for Continued Airworthiness, Rev. 04, dated March 2006.	23/07/2007	Active	10016045
EASA.IM.A.S.02217	HAWKER BEECHCRAFT SERVICES, Inc.	REV. 2	FAA STC SA10478SC	BEECH B300, B300C BEECH B200GT, B200CGT BEECH B200, B200C	Installation of Digital Flight Data Recorder System		Master Data List RAS060500131 Revision 12, 16 April, 2009<(>,<)> orlater approved revision.Airplane Flight Manual Supplement RAS060500132 Revision 2.0, dated 26March, 2009<(>,<)> or later approved revision.	None	16/06/2009	Active	10016046
EASA.IM.A.S.02218	BOMBARDIER AEROSPACE	REV. 1	TCCA SA03-113	CL-600-2B16	Complete Custom Interior		Transport Canada STC SA03-113.Aero Consulting Services Configuration Definition List D817000 Revision W dated November 13, 2006.Aero Consulting Services AFM Supplement D817090 Revision N/C or later approved revision.	Restricted to ASN 5636.	17/01/2007	Active	10016047
EASA.IM.A.S.02220	LIVETV, L.L.C.		FAA STC ST10056SC	AIRBUS A320-232	Installation Of Electronic Equipment Rack		Master Data List, Document Number 2284-001 Revision N, dated 03rd March 2003 or later EASA approved revision.Instructions for Continued Airworthiness, Document Number CD-2002-002,Revision IR, dated 14th August 2002, or later EASA approvedrevision.Aircraft Flight Manual Supplement, Document Number...	As per FAA STC ST10065SC the following STC's must be installed concurrently with this STC:ST00788SE, ST02483AT and ST01447NY.	29/05/2007	Active	10016048

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02221	LIVETV, L.L.C.		FAA STC ST02483AT	AIRBUS A320 SERIES	Installation Of a Cabin Mounted Video Camera System		Master Drawing List, Document Number LVTV-002-MDL Revision D, dated 07th April 2003, or later EASA approved revision.Instructions for Continued Airworthiness, Document Number LVTV-002-CAW, Revision B, dated 22nd February 2002, or later EASA approved revision.Aircraft Flight Manual Supplement, Docume...	As per FAA STC ST10065SC the following STC's must be installed concurrently with this STC:ST10065SC, ST00788SE, and ST01447NY.	29/05/2007	Active	10016049
EASA.IM.A.S.02222	LIVETV, L.L.C.		FAA STC ST00788SE	AIRBUS A320-200	Installation of a Live TV Satellite Television System		Master Drawing List, Document Number LTV933-D01-A320, Revision J, dated 24th May 2005 or later EASA approved revision.	As per FAA STC ST10065SC the following STC's must be installed concurrently with this STC:ST10065SC, ST02483AT and ST01447NY.	29/05/2007	Active	10016050
EASA.IM.A.S.02223	LIVETV, L.L.C.		FAA STC ST01447NY	AIRBUS A320-200	Installation Of Harris Ground Wireless Aircraft Data Link &Partial Power Provisions for Installation of a Cabin Surveillance System		Master Drawing List, Document Number 3092086-MDL, Revision C, dated 29th July 2004, or later EASA approved revision.Instructions for Continued Airworthiness, Document Number 3092085, Revision B, dated 31st January 2002, or later EASA approved revision.	As per FAA STC ST10065SC the following STC's must be installed concurrently with this STC:ST10065SC, ST02483AT and ST00788SE.	29/05/2007	Active	10016051
EASA.IM.A.S.02224	S-TEC CORPORATION		FAA STC SA09262AC-D	CESSNA 182T CESSNA 182R CESSNA 182Q	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance System, Model ST-718-20/30 in Cessna 182Q, 182R and T182, also when modified per STC SA1382WE (Robertson STOL)		Bulletin No. 818, dated 30-Jul-1997 or later approved revisionMaster Drawing List No. 921016, dated 30-Jul-1997, or later approved revisionFAA/DAS Approved Supplemental Flight Manual Supplemental, P/N 891462, dated 04-Aug-1997, or later approved revision, is required for Cessna Model 182Q, S/N 18266...	For 182Q the maximum aft c.g. is limited to 46.0 inches aftof datum when autopilot is installedInstaller must check availability of EASA-approval for Robertson STOL STC No. when aeroplane is modified per that STC	14/12/2006	Active	10016052
EASA.IM.A.S.02225	S-TEC CORPORATION		FAA STC SA09218AC-D	GRUMMAN GA-7	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-661 in Grumman American GA-7		Bulletin No. 761, Rev. 2, dated 19-Mar-2002 or later approved revision,Master Drawing List No. 92986, Rev. B, dated 19-Mar-02, or later approved revisionFAA/DAS Approved Pilot's Operating Handbook and / or Airplane Flight Manual Supplemental, Part No. 891353, dated 19-May-1997, or later approved rev...	--	14/12/2006	Active	10016053
EASA.IM.A.S.02226	S-TEC CORPORATION		FAA STC SA09316AC-D	CESSNA TR182 CESSNA R182	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance System, Model ST-759-20/30 in Cessna R182, and TR182.		- Bulletin No. 859, dated 15-Dec-1997 or later approvedrevision.- Master Drawing List No. 921055, dated 15-Dec-1997, or later approved revision.- FAA/DAS Approved Pilot's Operating Handbook and / or Airplane Flight Manual.Supplemental, P/N 891615, dated 18-Dec-1997, or later approved revi...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	18/12/2006	Active	10016054

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02227	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA07-086/D REV NC	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	Customized Interior Completion - SN 9208Validation of TCCA STC C-LSA07-086/D Rev NC		AFM Supplement G-FM25000154TCCA SoC letter C-06-0614, dated June 12, 2007ICA: GC92080000-IFCA	1. Refer to the Limitations sections of the required FM Supplement2. WLAN system is compatible only to IEEE 802.11(b).3. The use of WLAN is subject to operational rules.	21/06/2007	Active	10016055
EASA.IM.A.S.02233	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA01404WI	BEECH 300, B300C BEECH 200, 200C, B200C,	Installation of Collins IFIS 5000		FAA approved RAS Master Data List, Doc. No. RAS050600021, Revision 5.0, dated 30-Aug-2006 or later approved revisionFAAapproved Airplane Flight Manual Supplement, Doc. No. RAS050600034, dated 19-Sep-2006, or later approved revisionInstructions for Continued Airworthiness, Doc. No. RAS050600032, Rev...	This change is limited to airplanes equipped with Collins Pro Line 21 System and includes the FSU-5010 File Server Unit, CCP-3000 Cursor Control panel and either the XMWR 1000 XM Weather Receiver or VHF 4000/ CMU4000 Universal Weather System and associated antenna.	15/01/2007	Active	10016056
EASA.IM.A.S.02234	AS&T AEROSPACE SYSTEM & TECHNOLOGIEIN C		FAA SA755GL	U206F, U206G 206H, T206H, TU206G	Installation of TKS Ice Protection Systems Components on a no-hazard / no credit basis.		AS&T Drawing List No. 02800-DL, Revision 3, dated 19 December 2003, or later approved revision.“Supplemental Airplane Flight Manual and FAA approved Airplane Flight Manual Supplement”, Doc. No. 02800-FMS, revised May 27, 2003 or later approved revision.	1. This installation is not approved for flight into known icing conditions.2. A placard must be fitted on the upper control panel in front of the pilot, stating “FLIGHT INTO KNOWN ICING CONDITIONS IS PROHIBITED”.3. This installation is approved on a no-hazard / no credit basis.4.This STC is approve...	04/01/2007	Active	10016057
EASA.IM.A.S.02235	AS&T AEROSPACE SYSTEM & TECHNOLOGIEIN C		FAA SA01338WI	2. T182, TR182 2. 182P, 182Q, 182R 1. 182S, 182T, R182, T182T	Installation of TKS Ice Protection Systems Components on a no-hazard / no credit basis		AS&T Master Drawing List No. 12500-DL, Revision 5, dated May 27, 2005 or later approved revision."Supplemental AirplaneFlight Manual and FAA approved Airplane Flight Manual Supplement", Doc. No. 12500-FMS, dated 27-Sep-2005 or later approved revision.	1. This installation is not approved for flight into known icing conditions.2. A placard must be fitted on the upper control panel in front of the pilot, stating "FLIGHTINTO KNOWNICING CONDITIONS IS PROHIBITED".3. Applicable serial numbers: 182P: S/N 18260826 through 18264295; and 182P, 182Q,182R,1...	08/12/2006	Active	10016058
EASA.IM.A.S.02236	ROCKWELL COLLINS, Inc.		ST01580AT-D	BOEING 747-400	Installation of radio panels and Collins VHF transceivers with 8.33 khz spacing in accordance with Collins Master Data List MDL-01237, revision M, dated August 9, 2005, or later FAA approved revisions.		Data package containing the following documents, and additional supporting data:MDL 01237, rev. M: MDL Collins VHF700V/-900B in B747-400.CFG-01296: installation of Collins VHF-700B communications system on B747-400 for Air France.ENG-01664: installation Collins VHF-700B on Boeing 747-400.RPT-01503:...	¿ Data package containing the following documents, and additional supporting data: ¿ MDL 01237, rev. M: MDL Collins VHF700V/ -900B in B747-400.¿ CFG-01296: installation ofCollins VHF-700B communications system on B747-400 for Air France. ¿ ENG-01664: installation Collins VHF-700B on Boein...	08/08/2007	Active	10016059
EASA.IM.A.S.02237	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST02410CH-D	BAE 125 SERIES 800A	Installation of Rockwell Collins Pro Line 21 IDS (Integrated Display System) with IFIS-5000 (Integrated Flight Information System) and Engine Instrument Display.		Installation in accordance with Duncan Aviation Master Drawing List 060912014, Revision G, dated 4/20/07, or later approved revisions.Aircraft to be operated in accordance with Aircraft Flight Manual Supplement, 060912018, Revision Ø dated1/18/07, or later approved revisions.Aircraft to be operated...		28/02/2008	Active	10016060

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02239	DUGANAIR TECHNOLOGIES, INC		FAA STC ST01182SE	737-500 737-200, 737-300, 737-400	Installation of Duganair Security Flight Deck Door as defined in FAA STC ST01182SE		- Duganair Technologies Inc., Index List, QS-00001-3A, Revision B, dated August 27, 2003 or later approved revisions;- FAA Approved Airplane Flight Manual Supplement No. QWC737101-4, Rev. 1, dated December 16, 2004 or later approved revision is required as part of this installation.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	15/11/2006	Active	10016061
EASA.IM.A.S.02240	BOMBARDIER AEROSPACE		TCCA LSTC C-LSA07-044/ D	BOMBARDIER CL-600-2B16	Costumised Interior Completion		Transport Canada LSTC C-LSA07-044/DAero Consulting ServicesModification Data Summary E964000 Revision n/c or later approved revision.Aero Consulting Services AFM Supplement E9640920 Revision n/c or later approved revision.	Restricted to ASN 5659.	11/04/2007	Active	10016062
EASA.IM.A.S.02241	NORTHEAST ENGINEERING & DEVELOPMENTL TD.	REV. 1		CESSNA T207A	STOL Installation.		-Installation must be in accordance with Northeast Engineering &Development Ltd.Master Drawing List MDL No. 040201 Issue 1, dated 29 June 2004 or laterapproved revision.- Placards must be in accordance with Northeast Engineering & DevelopmentLtd. Drawing No. 040202 Issue 1, or later approved revision...	1. This Installation is limited to the Serial No. 20700706 (RegistrationC-FYBZ).2. Compatibility of this modification with other previously approvedmodifications must be determined with the installer.3. This STC is approved only for the product configuration as defined inthe approved design data ref...	20/12/2006	Active	10042990
EASA.IM.A.S.02242	ANCRA INTERNATIONAL LLC		FAA STC ST01551LA	ATR 42-300 AEROSPATIALE ATR 42-320	Installation of Ancra mechanical main deck cargo landing system		- Ancra Controlled Drawing List DL84230, Revision N/ C, dated June 20, 2003		08/12/2006	Active	10016063
EASA.IM.A.S.02244	AEROMECH Inc.		FAA ST01522SE	501, 551	Validation of FAA STC ST01522SE:Group aircraft approval forRVSM capability.		AeroMech Document No. AMI-QD-CS-0311, Rev. B, dated 08 Sept. 2006 or later FAA approved revision.FAA approved AeroMech AFM-S Doc. AMI-AFMS-CS-0708, dated 04/04/2007 or later FAA approved revision.FAA approved AeroMech Instructions for ContAW Doc. No. AMI-IICA-CS-0703, dated 04/04/2007 or later FAA a...	The installer muste determine if this design is compatible with previously approved modifications. If the holder agreesto permit another person to use this certification or altera product, the holder must give the other person written evidence of that permission.	26/04/2007	Active	10016065
EASA.IM.A.S.02245	LEARJET Inc.		FAA STC ST01731LA-D	LEARJET 45	Installation of Honeywell Integrated Communication Unit / Enhanced Surveillance Upgrade (-1 Configuration).		Project Specific Certification Plan BAS45337001, rev. NCJARCompliance Checklist BAS45160014, rev. NCMaster Document List BAS45015013, rev. EAFM Supplement BAS45045008, rev. NCInstructions for Continued Airworthiness BAS45015013-IFCA-1, rev. NC	1. Incorporation of ECR 7598 and Honeywell Service Bulletins 7517400-23-6008, 7510700-23-6044 and 7510700-23-6046 is a prior or concurrent requirement to this installation.2. ThisSTC is approved only for the product configuration as defined in the approved design data referred to in the paragraphsc...	14/03/2007	Active	10016066

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02246	GULFSTREAM SERVICES CORPORATION		FAA STC ST03324AT-D	GULFSTREAM GV-SP	Completion and installation of the custom interior on Aircraft Serial 5127.		In accordance with Gulfstream Aerospace Corporation Master Index List GC51 4915127, Revision E, dated January 22, 2007,or later approved revisions.FAA approved Flight Manual Supplement, GC51 501M017, dated January 26, 2007, or later approved revisions	Aircraft Serial 5127 Only.The following STC's are required to be installed as part of this STC:- FAA STC ST02696AT-D, EASA Approved ref EASA.IM.A.S. 02147.FAA STC ST03290AT-D, EASA Approved ref EASA.IM.A.S.02255FAA ST02697AT-D was approved prior to EASA under the JAA System and are listed in the Gulfs...	05/02/2007	Active	10016067
EASA.IM.A.S.02247	BOMBARDIER AEROSPACE		TCCA LIMITED STC C-LSA06-281/ D	BOMBARDIER BD-700-1A11	Aircraft Completion, 13 Passenger Interior ConfigurationValidation of TCCA Limited STC C-LSA06-281/D to S/N 9186MDL: E915000 Rev A or later approvad revisions		SoC: C-06-0742FMS: G-FM25000141 Rev NC or later approved revisionsIFCA: GC91860000-IFCA IR	Refer to the Limitations Sections of the required FM SupplementWLAN system is compatible only to IEEE 802.11 (b)The use of WLAN is subject to operational rules	23/01/2007	Active	10016068
EASA.IM.A.S.02249	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02316CH	DC-9-80 SERIES	FAA STC ST02316CH - Elementary and Enhanced Mode S.		ECS Master Data List ECS-203350 Rev. G dated July 7, 2006.	Limited to configuration 3 of ECS MDL ECS-203350 Rev. G dated July 7, 2006.This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated TechnicalDocumentation”. Compatibility with other aircraft/ engine con...	28/02/2007	Active	10016069
EASA.IM.A.S.02251	LEARJET Inc.		FAA STC SA8178NM-D	BOMBARDIER BD-700-1A10	Installation of an Artex ELT/NAV Interface SystemValidationof the FAA STC SA8178NM-D		IFCA: GC-25615001-IFCA-1 or -2		21/02/2007	Active	10016070
EASA.IM.A.S.02253	GENERAL AEROSPACE INC		FAA STC ST01792AT	BOEING 757-200	TCAS and Duel Mode-S Transponders Installation.		General Aerospace Master Drawing List GA-RC02/898/ MDL, 12thSeptember 1998AFM Supplement GA-RC02/898/AFMS 31st December1998.		17/10/2007	Active	10016072
EASA.IM.A.S.02255	GULFSTREAM SERVICES CORPORATION		FAA STC ST03290AT-D	GULFSTREAM GV-SP GULFSTREAM GIV-X	Installation of Cabin Window Shades (ATG)		In accordance with Gulfstream Aerospace Corporation Index List GC51 5068000, Revision A, dated November 16, 2006, or later approvedrevisions.FAA approved Flight Manual Supplement,GC41506M004, Revision NC, dated November 21, 2006, for -401, -403, -405, -407, -409, -411, and -413 configurations.FAA a...	None.	23/01/2007	Active	10016073
EASA.IM.A.S.02256	GULFSTREAM SERVICES CORPORATION		FAA STC ST03351AT-D	GULFSTREAM GIV-X	Airplane Completion on Aircraft Serial Number 4060		Installation in accordance with Gulfstream Aerospace Corporation MasterIndex List GC414914060, Revision F, dated 05 January 2007, or laterapproved revision.	Aircraft Serial Number 4060 Only.The following STC's are a required part of this STC:ST02979AT-D, ST02987AT-D, ST03290AT-D, ST03047AT-D, ST02980AT-D andST03027AT-D. It is the Installer's responsibility to ensure these STC'sare all EASA approved.This STC is approved only for the product configuration...	23/01/2007	Active	10016074

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02258	BOMBARDIER AEROSPACE		TCCA LIMITED STC C-LSA07-045D	BOMBARDIER CL-600-2B16	Customized Interior completion - Aircraft 5664.		Transport Canada Limited STC No. C-LSA07-045D dated 8 June 2007.Aero Consulting Services Modification Data Summary FO61000 revision N/C or later approved revision.Aero Consulting Services Airplane Flight Manual Supplement FO61090 version N/C or later approved revision.	Restricted to Aircraft Serial No. 5664.	18/07/2007	Active	10016075
EASA.IM.A.S.02260	EAD INC.		FAA STC ST02267CH	BOEING 747-400	EAD installed Honeywell Weight and Balance System (WBS) on B747-400 in accordance with EAD Master Data List 01021-FAA-A-MDL, rev. E, or later EASA-approved revision.This STC is a validation of FAA STC ST02267CH		Installation of Weight and Balance System on B747-400, Master Data List, EAD document 01021-FAA-A-MDL, Rev. E.Airplane Flight Manual Supplement, EAD document 01021-FAA-A-AFM-01, Rev. D.Installation of Weight and Balance System on B747-400	1. This on board weight and balance system is considered anadvisory systeem and is not certified as the primary means of calculating the aircraft's weight and balance.2. EASA approved Airplane Flight Manual Supplement, EAD document 01021-FAA-A-AFM-01, Rev. D, or later approved revision, is reqiredo...	27/04/2007	Active	10016076
EASA.IM.A.S.02261	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01901LA	B767-200/-300	Installation of ARINC 718A MODE S Transponder Activation ofElementaryand Enhanced Surveillance Capabilities.		Hollingsead International Master Data List 2869-01, Revision B, 13/10/2006.AFM Supplement, Hollingsead International Document 2869-AFM, RevisionNC, 17/10/2006.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	31/07/2009	Active	10042991
EASA.IM.A.S.02261	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01901LA	BOEING 767-300 BOEING 767-200	Installation of ARINC 718A MODE S Transponder Activation ofElementary and Enhanced Surveillance Capabilities.		Hollingsead International Master Data List 2869-01, Revision B, 13/10/2006.AFM Supplement, Hollingsead International Document 2869-AFM, Revision NC, 17/10/2006.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	30/06/2008	Active	10016077
EASA.IM.A.S.02262	BLACKHAWK MODIFICATIONS Inc.		FAA SA10567SC	F90	Installation of Pratt and Whitney PT6A-135A engines in place of PT6A-135 engines.		Installation must be in accordance with Master Drawing ListNo. 19015-00-00 Rev. IR dated 26-06-06 or later Approved Revisions.Operation must be in accordance with Flight Manual Supplement Document No. AFMS19015 Rev. IR dated 18-10-06 or later approved revision.Continued Airworthiness must be in acc...	1. Installation limited to Serial Number LA-2 thru LA-204, except for LA-202.2. Compatibility of this modification with other previously approved modifications must be determined by the installer.3. This STC is approved only for the product configuration as defined in the approved design da...	23/01/2007	Active	10016078
EASA.IM.A.S.02263	BLACKHAWK MODIFICATIONS Inc.	REV. 1	FAA SA00433AT	BEECH 200T 200, 200C, 200CT, 200T	Installation of Pratt and Whitney PT6A-42 engines in place of PT6A-41 engines. This project is to amend EASA TSC No. EASA.IM.A.S. 02263 using the data from the amended FAA-STC SA00433AT dated 22. August 2007 to include Beechcraft Super King Air 200C, 200T and 200CT.		Installation of Pratt & Whitney PT6A-42 engines with Propellers: model HC-B3TN-3(G,N)/T10178(B, NB, K, NK) or Hartzell HC-D4N-3A/D9383K installed in accordance with modifications drawing No. A794-0001, Rev. B, dated 17. July 2007 or later approved revision.Operation must be in accordance with Aircra...		01/04/2008	Active	10016079

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02264	S-TEC CORPORATION		FAA STC SA09201AC-D	CESSNA 172S CESSNA 172R	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-563 in Cessna 172R and 172S		Bulletin No. 663, Revision 5, dated 01-Feb-2001 or later approved revisionMaster Drawing List No. 92732, Revision E, dated 01-Feb-2001, or later approved revisionFAA/DAS Approved Pilot's Operating Handbook and / or Airplane Flight Manual Supplement, P/N 891336, Revision 2, dated 01-Feb-2001, or late...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and "Associated Technical Documentation". Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	16/01/2007	Active	10016080
EASA.IM.A.S.02265	BOMBARDIER AEROSPACE		TCCA C-LSA07-111/D	BD-100-1A10 (CHALLENGER 300)	AIRCRAFT COMPLETION, 9 PASSENGER INTERIOR CONFIGURATIONEASAValidation of:Transport Canada Limited Supplemental Type Certificate C-LSA07-111/D Issue 1 dated 11th May 2007, in accordance with Aero Consulting Services Ltd. Modification Data Summary F111000 Revision N/C.		Transport Canada Limited Supplemental Type Certificate C-LSA07-111/D Issue 1 dated 11th May 2007.Transport Canada Approved Aero Consulting Services Ltd. Airplane Flight Manual Supplement F111090 Revision N/C.Instructions for Continued Airworthiness HC201375000-IFCA-1	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The use of approved data is subjected to permission of t...	15/05/2007	Active	10016081
EASA.IM.A.S.02266	HOLLINGSEAD INTERNATIONAL		FAA STC ST01879LA	BOEING 747-400 SERIES	Installation of B/E Aerospace Air Chiller P/N 470-1		B/E Aerospace Master Data List EC470-9, Revision C, dated November 6, 2006, or later approved revisions	This approval is limited to airplanes on which C&D Zodiac Pantry P/N C481001-101 has been installed in accordance with STC ST01880LA	23/01/2007	Active	10016082
EASA.IM.A.S.02274	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST64049CH-T	GULFSTREAM GV-SP	Completion and installation of the custom interior on Aircraft Serial 5124		In accordance with Gulfstream Aerospace Corporation Master Drawing List GC52 2046051, Revision B, dated January 30, 2007, or later approved revision.FAA approved Flight Manual Supplement, GC52 204MO17, dated February 1, 2007, or later approved revisions.	Aircraft Serial 5124 only.The following STCs are required to be installed as part of this STC:FAA STC ST02696AT-D, EASAapproved EASA.IM.A.S. 02147FAA STC ST02796AT-D, EASA approved EASA.IM.A.S. 01259FAA STC ST02047CH-D, EASA approved EASA.IM.A.S. 02144FAA STC ST02048CH-D, EASA approved EASA.IM.A.S. 021...	19/02/2007	Active	10016087
EASA.IM.A.S.02275	MICRO AERODYNAMICS, INC.		FAA STC SA00831SE	CESSNA P172D CESSNA 175A-C CESSNA 172RG CESSNA 172A-S	Installation of vortex generators on the wings and tail surfaces in accordance with the provisions of AML SA00831SE.		Installation must be in accordance with FAA Sealed Drawing List Nr. MA2138 Rev IR5/3/00 and Installation Instructions MA2139, Rev IR dated 5/22/00.	Approval of this change in type design applies to the aircraft listed on AML SA00831SE only. This approval should not be extended to other aircraft on which other previously approved modification are incorporated unless it is determined that the relationship between this change and any other previou...	13/04/2007	Active	10016088
EASA.IM.A.S.02276	HONEYWELL INTERNATIONAL Inc.		FAA STC SA6086NM	BOEING 767-300	Installation of Honeywell/Racal Aeronautical SATCOM		Master Data List (MDL) ML4078149, Revision AE, dated December 19th, 2006	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	21/12/2006	Active	10016089
EASA.IM.A.S.02277	CENTRI-LUBE TECHNOLOGIES, LLC		FAA STC SA01435LA		Installation of engines, modified with a Firewall Forward Technologies, LLC modified camshaft, into aircraft listed on the EASA approved ATL		FAA approved Firewall Forward Technologies, LLC Installation Instructions FFT-INI-001-AFR, revision -, dated 06-Feb-2003, or later approved revision.Continued Airworthiness Instructions, document number FFT-CAI-001-AFR, revision A, dated 11-Sep-2003 or later released revision	1. This installation must be done concurrently with EASASTC No. EASA.IM.E.S. 01010, which modifies the engine.2. Regardless of the EASA Approved Type List (ATL), installation is only approved if the Airplane Type / Variant itself is EASA approved. 3. This STC is approved only for the product...	12/02/2007	Active	10016090

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02279	TRI-STAR AVIATION INC.		FAA STC ST01897CH & EASA 200	L-1011-385-3	Installation of strengthened flight deck doorNote: This STCsuperseds EASA STC 2004-3731.		Tri-Star Aviaiton Master Data List MDL-501008 Rev. J dated 10/01/2005	1. Limited to S/N 193H-1206, 193H-1248, 293B-1240, 239B-1241, 193W-1189, 193Y-1181, 193Y-1184, 193Y-1185, 193Y-1176,193Y-1194, 193Y-1208, 193H-1202, 193H-1207, 193H-1216 and 193H-12182. This STC is approved only for the product configuration as defined in the approved design data referred toe...	08/01/2007	Active	10016092
EASA.IM.A.S.02283	DELTA ENGINEERING CORPORATION		FAA STC ST02227NY-D	AIRBUS A340-300	Panasonic Aviation Corporation System 3000i IFE Installation /Installation of a Panasonic Avionics Corporation System 3000i In-FlightPassenger Entertainment System with Astronics Empower ® In-Seat PowerSupply System in accordance with Delta Engineering Master Data List 0152-05938-2135 Revision A dat...		¿ FAA STC ST02227NY-D¿ Master data List, Ref. No. 0152-05938-2135, Panasonic Document MDL10497, Rev. A, dated June 18th 2007 ¿ Certification Plan “New STC” Panasonic System 3000i in a Airbus A340-300 Series, Ref. DAS-2135-01, Rev. E, dated March 9th 2007¿ Substantiation Report for Astroni...	¿ Delta Engineering Instructions for Continued Airworthiness, Ref. No. 0752-05945-2135 Revision A, dated March 8th 2007.¿ Delta Engineering Airplane Flight Manual Supplement, Ref. No. 0652-06023-2135, dated June 21st 2007.¿ Cabin configuration must be installed in accordance with AFI LOPA D...	05/07/2007	Active	10016094
EASA.IM.A.S.02285	CASCADE AEROSPACE Inc.		TCCA STC SA07-44	BOMBARDIER CL-600-2B19	Conversion of full cabin class E Cargo Compartment.		¿ Cascade Aerospace Inc. Engineering Master Document List EMDL 3683, Revision 5, dated 03 April 2007 or later approved revision.¿ Cascade Aerospace Inc. Flight Manual Supplement FMS 3683, Revision IR, dated 03 April 2007 or later approved revision.¿ Cascade Aerospace Inc. Maintenance Requir...		11/04/2007	Active	10016096
EASA.IM.A.S.02286	ELISEN TECHNOLOGIES		TCCA STC SA07-9	BOMBARDIER CL-600-2B19	Iridium Antenna Installation		¿ Transport Canada STC SA07-9.¿ Elisen Technologies Inc. Master Data List MDL-29R2-639, Revision NC, dated 21 January 2007 or later Transport Canada approved revision.		31/05/2007	Active	10016097
EASA.IM.A.S.02287	ELISEN TECHNOLOGIES		TCCA STC SA07-3	BOMBARDIER CL-600-2B19	Aft Equipment Bay Steps		¿ Transport Canada STC No. SA07-3.¿ Elisen Technologies Inc. Master Data List MDL-29R2-647, Revision NC, dated 21January 2007 or later Transport Canada approved revision.		31/05/2007	Active	10016098
EASA.IM.A.S.02288	ELISEN TECHNOLOGIES		TCCA STC SA07-4	BOMBARDIER CL-600-2B19	Ladder Stowage		¿ Transport Canada STC SA07-4.¿ Elisen Technologies Inc. Master Data List MDL-29R2-648, Revision NC, dated 21 January 2007, or later Transport Canada approvedrevision.		31/05/2007	Active	10016099
EASA.IM.A.S.02289	ELISEN TECHNOLOGIES		TCCA STC SA07-5	BOMBARDIER CL-600-2B19	Towbar Head Stowage		¿ Transport Canada STC SA07-5.¿ Elisen Technologies Inc. Master Data List MDL-29R2-649, Revision NC, dated 21 January 2007, or later Transport Canada approvedrevision.		31/05/2007	Active	10016100

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02290	ELISEN TECHNOLOGIES		TCCA STC SA07-6	BOMBARDIER CL-600-2B19	Main wheel stowage		¿ Transport Canada STC SA07-6.¿ Elisen Technologies Inc. Master Data List MDL-29R2-653, Revision NC, dated 21 January 2007, or later Transport Canada approvedrevision.		31/05/2007	Active	10016101
EASA.IM.A.S.02292	BOMBARDIER INC.		TCCA C-LSA07-049/D ISSUE 1	BOMBARDIER BD-100-1A10 (CHALLE	AIRCRAFT COMPLETION, 10 PASSENGER INTERIOR CONFIGURATIONEASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA07-049/D Issue 1 dated 19th February 2007, in accordance with Aero Consulting Services Ltd. ModificationData Summary F075000 Revision		Transport Canada Limited Supplemental Type Certificate C-LSA07-049/D Issue 1 dated 19th February 2007Transport Canada Approved Aero Consulting Services Ltd Airplane Flight Manual Supplement F075090 Revision N/C.Instructions for Continued Airworthiness HC201165000-IFCA-1	1. Compatibility with previous approved modifications shallbe determined by the installer.2. This STC is limited to aircraft Bombardier BD100-1A10 Serial Number 20116.	28/02/2007	Active	10016102
EASA.IM.A.S.02293	S-TEC CORPORATION		FAA STC SA09160AC-D	PIPER PA-32R-300 PIPER PA-32-300 PIPER PA-32-260	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-640		Bulletin No. 740, Rev. 2, dated 28-Jun-2001 or later approved revision,Master Drawing List No. 92944, Rev. B, dated 28-Jun-2001, or later approved revision,FAA/DAS Approved Pilot's Operating Handbook, and / or Airplane Flight Manual Supplement, Part No. 891289, Rev. 1, dated 28-Jun-2001, or later ap...		28/02/2007	Active	10016103
EASA.IM.A.S.02294	DUNCAN AVIATION, INC.		FAA STC NO. ST2359CH-D	BAE 125 SERIES 800A	Modification of the existing Collins TDR-94D Transponders and Collins RTU-870 Radio Tuning Units to Enhanced Surveillance capable equipment and aircraft interface requirements.		• Modification to be in accordance with Duncan Aviation Master Drawing List Document No. 061103015, Revision A, dated December 19, 2006, or later approved revision.• Operation to be in accordance with Duncan Flight Manual Supplement Document No. 061103026, Revision A, dated December 8, 2006,or...	1. This STC is only approved where ARINC 429 databus or similar standard is used as an input to the transponders, itdoes not approve the use of Gilham or Grey code as the input to the Mode S transponders. As the applicant has not demonstrated that this STC addresses the EASA AD 2006-02 which wou...	20/08/2007	Active	10016104
EASA.IM.A.S.02295	DUNCAN AVIATION, INC.		FAA STC NO. ST02370CH-D	HAWKER 800XP HAWKER 800 BAE 125 SERIES 800A	Upgrade of the existing dual Universal Avionics Systems Corporation UNS-1D Flight Management System to UNS-1D+ Flight Management System.		Duncan Aviation Master Drawing List 061108001, Revision A, dated December 22, 2006 or later FAA approved revision.	EASA approved Airplane Flight Manual Supplement, 061108004,Revision 0, dated November 10, 2006, EASA approved Jabuary 10, 2007 or later EASA approved revision is required.Compatibility of this design change with previously approved modifications must be determined by the installer.A copy of this ce...	31/05/2007	Active	10016105
EASA.IM.A.S.02296	LEARJET Inc.		FAA ST00222BO	BOMBARDIER CL-600-2B16	Installation of enhanced surveillance modification to Dual Collins TDR-94/94D transponder system.		FAA STC ST00222BO dated 22 November 2005 or later approved revision.BBAS Master Document List BAS 63017005 Revision NC dated 25 octoerb 2005 or later approved revision.BBAS AFM Supplement BAS63047009 Revision NC dated 22 November 2005 or later approved revision.	Installation of emhanced surveillance modificationper this STC requires that a previously EASA approved dual installation of Collins p/n 622-9352-007 (TDR-94) or 622-9210-007 (TDR-94D) or later version has been installed in the aircraft.	31/05/2007	Active	10016106

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02297	EMS TECHNOLOGIES CANADA, Ltd.		TCCA STC SA05-12, ISSUE 3, DAT	SEE EASA APPROVED MODEL LIST	Installation of EMS HSD-64/-128/-X/-400/-400i/-HD-710 High Speed Data Transceiver		EMS HSD-64/-128/-X/-400/-400i/-HD-710 High Speed Data Transceiver, Engineering Report RPT04021 by Avionic Services Ltd	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller	27/06/2007	Active	10016107
EASA.IM.A.S.02298	LEARJET Inc.	REV. 1	FAA STC ST01732LA-D	BOMBARDIER BD-700-1A10	Installation of a Rockwell Collins Integrated Flight Information System (IFIS-5000).		Master Drawing List, ref. Doc. BAS68010011, Rev. G, dated 28/11/2006.Airplane Flight Manual Supplement, ref. Doc. BAS68040003, Rev. N/C, dated 28/11/2006.Maintenance Requirements - Instructions for Continued Airworthiness, ref. Doc. BAS68010011-IFCA-1 (-1 Configuration), dated 19/10/2006.Maintenance...		04/12/2007	Active	10016108
EASA.IM.A.S.02299	CASCADE AVIATION SERVICES INC.		STC ST01181SE	DORNIER 328-300 DORNIER 328-100	Installation of increased security cockpit door		Cascade Aviation, Inc. Master Drawing List (MDL) 02CAS096-MDL, Revision D, dated July 14, 2003 or later approved revision	A copy of this Certificate and Cascade Aviation Services Master Drawing List (MDL) 02CAS096-MDL, Revision D, dated July14, 2003 orlater approved revision must be maintained as part of the permanent records for the modified aircraft	19/01/2007	Active	10016109
EASA.IM.A.S.02300	DUNCAN AVIATION, INC.		US STC NO. ST02371CH-D	HAWKER 800 XP HAWKER 800, 800A	Installation of Aircell Iridium ST-3100 single channel SATCOM system.		Duncan Aviation Master Drawing List 041008020, Revision A, dated December 22, 2006 or later FAA approved revision.	Compatibility of this design change with previously approved modifications must be determined by the installer.If the holder agrees to permit another person to use this certificate to alter the product , the holder shall give the other personwritten evidence of that permission.	31/05/2007	Active	10016110
EASA.IM.A.S.02302	DECA AVIATION ENGINEERING LIMITED		TCCA STC O-LSA02-397/D ISS 2	A320-214	Installation Of 180 Passenger - All Economy Class Seating Arrangement, in accordance with Transport Canada STC O LSA02-397/D Issue 2		Master Drawing List, Document Number MS02071 Revision 1, dated 18th July 2002 or later EASA approved revision.Instructions for Continued Airworthiness, Document Number ICA02071, Revision 1, dated 18th July 2002, or later EASA approved revision.	1. As per Transport Canada STC O-LSA02-397/D Issue 2.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations s...	10/05/2007	Active	10016112
EASA.IM.A.S.02306	HONEYWELL INTERNATIONAL Inc.		FAA STC SA5473NM	BOEING 747-100-400	Installation of Honeywell/Racal Aeronautical Satelite Communication system		- Honeywell Master Data List, Engineering Specification No. ML4075075, Revision B, or later approved revisions of this specification,- Applicable Airplane Flight Manual Supplements are listed in Honeywell Master Data List, called outabove.	Approval of this type design applies only to Boeing 747 series aircraft when:1. Provisions for this SATCOM installation have been installed and approved in accordance with thisSTC, or2. Provisions for this SATCOM installation have been installed and approved in accordance with other STC, or3....	10/04/2007	Active	10016115
EASA.IM.A.S.02307	AVIONICS SUPPORT GROUP, Inc.		FAA ST03071AT	727-200	Installation of Avionics System for Reduced Vertical Separation Minimum (RVSM) Provisions into a Boeing 727-200 aircraft.		Avionics Support Group, Inc Master Drawing List (MDL) No. 23509-MDL Rev A, dated 27/05/2004, or later approved revisions		04/06/2007	Active	10016116

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02309	ENGINE TECHNOLOGIES, Inc.		FAA STC SA10588SC	CIRRUS SR22	Validation of FAA STC SA10588SC "Installation of modified Teledyne Continental Motors IO-550-N engine equipped with turbonormalizing system"		Installation in accordance with Engine Technologies Master Drawing List ETI-G2-1, Rev. NC, dated 1. Nov 2006 or later FAA approved Revision	Installation of STC SE10589SC (EASA.IM.E.S.01013) is requiredAn oxygen system meeting requirements of CS23.1441 through23.1449 must be installed in conjunction with this STCThe installer must determine, if this design is compatible with previously approved modifications. If the holder agrees to per...	11/05/2007	Active	10016117
EASA.IM.A.S.02310	JETTECH, L.L.C.		FAA STC ST01395WI	REIMS AVIATION CESSNA F 177 RG CESSNA 551 CESSNA 550 CESSNA 501 CESSNA 500	Installation of Dual Honeywell AM-250 Digital Altimeter andSkylight Avionics Air Data Interface Adapter ADC-602 AIU and associatedequipment to obtain RVSM approval.		Installation in accordance with Master Document List MDL2703-34254, dated 19 June, 2006 or later approved installation;Compliance Checklist CR2703-34254;AFM Supplement FMS2703-34253-4, Rev. IR, dated 06 June 2007.		04/07/2007	Active	10016118
EASA.IM.A.S.02311	BOMBARDIER AEROSPACE		TCCA SA03-113	CL-600-2B16	Complete Custom Aircraft Interior.		Transport Canada STC SA03-113. Aero Consulting Services Configuration Definition List D817000 Revision AD dated 19 January 2007. Aero Consulting Services AFM Supplement D817090 revision N/C or later approved revision.	Restricted to Serial no. 5655	26/03/2007	Active	10016119
EASA.IM.A.S.02312	BOMBARDIER INC.		TCCA STC NO. C-LSA07-154/D	BOMBARDIER BD-100-1A10 (CHALLE	AIRCRAFT COMPLETION, 10 PASSENGER INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental TypeCertificate C-LSA07-154/DIssue 1dated 15th June 2007, in accordance with Aero Consulting ServicesLtd. Modification DataSummary F311000 Revision N/C.		• Transport Canada Limited Supplemental Type CertificateC-LSA07-154/D Issue 1, dated 15th June 2007.• Transport Canada Approved Aero Consulting Services Ltd. Airplane FlightManual Supplement F311090 Revision N/C.• Instructions for Continued Airworthiness HC201455000-IFCA-1	1. This STC is limited to aircraft Bombardier BD100-1A10Serial Number 20145.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the...	03/07/2007	Active	10016120
EASA.IM.A.S.02314	TDG AEROSPACE INC	REV. 1	FAA STC ST01950LA	BOEING 757-300 BOEING 757-200	Universal Fault Interrupter (UFI) Installation		TDG Aerospace, MDL 10-3200-0009 (rev C, 11th January 2007)AFM Supplement 20-3200-003 (10th January 2007)	The UFI is a Critical Design Control Configuration Limitation (CDCCL) item. Its operation and instructions for maintenance and inspection must be performed in accordance with the TDG Instructions for Continued Airworthiness (document 20-3200-0001, rev. D 11th January 2007) and must be incorporatedTh...	19/04/2007	Active	10016121
EASA.IM.A.S.02315	GULFSTREAM SERVICES CORPORATION			GULFSTREAM GIV-X	Airplane Completion on Aircraft Serial Number 4066.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC41 4914066, Revision D, dated 8 March 2007, orlater approved revision.	Aircraft Serial Number 4066 Only.The following STC's are a required part of this STC:- ST02979AT-D, ST02987AT-D, ST03290AT-D, ST03047AT-D, ST02980AT-D and ST03027AT-D. It is the installers responsibility to ensure these STC's are all EASA approved.	28/03/2007	Active	10016122
EASA.IM.A.S.02317	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02303CH	BOEING 767-200, -300 SERIES	Installation of Enhanced Mode-S Transponder.		Electronic Cable Specialists Master Data List, Document No.ECS-202463, Revision F, dated June 27, 2006 or later approved revision.	The Airplane Flight Manual Supplement as listed in AppendixA of Electronic Cable Specialists Master Data List, Document No. ECS-202463, Revision F, dated June 27, 2006, or later approved revision is required on board the modified aircraft.	14/06/2007	Active	10016124

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02318	VIDEO TECHNOLOGY SERVICES, Inc.		FAA STC ST01998NY	BOEING 767-300	1. Configuration 1: Installation of LCD Monitor System2. Configuration 2: Installation of LCD Monitor System		1. Configuration 1: in accordance with Video Technology Services, Inc. Technical Drawing List Document No. 205-D-334, Revision B, dated August 9, 2004.2. Configuration 2: in accordance with Video Technology Services, Inc. Technical Drawing List Document No. 205-D-368, Revision C, dated June 2, 2006...	1. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall givethe other person written evidence of that permission.2. The aircraft must be maintained in accordance with Video Technology Services, Inc. Instructions for Continued Airworthine...	05/06/2007	Active	10016125
EASA.IM.A.S.02320	AERO DESIGN LTD.		TCCA STC C-LSA05-204/D	PA-31	Installation of Heater Exhaust Extension. / The purpose is to route exhaust from the combustion heater in the aircraft nose to the aft of the wing to prevent fouling of the cameraport.Ref.: Trasnport Canada Limited Supplemental Type Certificate C-LSA05-204/D issue 2.		Aero Design Ltd. Document Control List DLC637 Rev. 0, dated6 April 2005, Listing Engineering Documents, Fabrication Documents and Installation Documents.Aero Design Ltd. Engineering Report ER637.01.01.Air Worthiness Compliance Programme.	Limited to aircraft serial numbers 31-457 and 31-7912028.	28/08/2007	Active	10016126
EASA.IM.A.S.02321	HAWKER BEECHCRAFT CORPORATION (HBC)		FAA STC SA01417WI	RAYTHEON A36	Replace pilot's altimeter with IS&S encoding altimeter.		1. RAS Master Data List Replace RAS230600940, Revision 6.0,dated December 7, 2006, or later approved revisions2. AirplaneFlight Manual Supplement, RAS230600958, dated December 13, 2006, or later approved revisions	Compliance with the following requirements, in addition to the requirements shown on the Type Certificate Data Sheet 3A20, has beenshown:23.303, 23.305, 23.307, 23.321, 23.341, 23.365, 23.601, 23.609, 23.627 effective February 1, 196523.611 as amended through Amendment 23-723.607 as amended through2...	26/02/2007	Active	10016127
EASA.IM.A.S.02322	MCCAULEY PROPELLER SYSTEMS		FAA STC SA496CH	BEECH 23	Installation of McCauley Propeller Model B3D36C429/82NPR-6		In accordance with McCauley Technical Report No. 844, no revision, dated January 15, 2006 and McCauley Drawing No. D-60165, no revision, dated April 1, 1996, or later approved revision.FAA approved Flight Manual Supplement, Technical Report No. 845, dated, April 3, 1996, or later approved revision....	1. Aircraft Specifications are the same as listed on Type Certification Data Sheet A1CE, except as follows:Propeller and Propeller Limits:Propeller: McCauley Constant Speed B3D36C429/82NPA-6Number of blades: 3Blade Angels: At 30" station: Low 10.5 degrees, High 33.8 degreesDiameter: 76 i...	22/05/2007	Active	10016128
EASA.IM.A.S.02324	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		TCCA STC Q-LSA06-018D	BOMBARDIER BD-700-1A10	Re-Locate Electronic Flight Bag and Miscellaneous Cabin Modifications in Cockpit of SN 9145Validation of TCCA Limited STC Q-LSA06-018/D to S/N 9145MDL: 26115002 Rev A orlater TCCA approved revisionsCompliance Plan: CP26115-001		IFCA: TL26115-004 Rev NC or later TCCA approved revisions		22/03/2007	Active	10016130
EASA.IM.A.S.02325	RAISBECK ENGINEERING Inc.		STC ST01724SE DATED JANUARY 5T	LEARJET 31	Installation of a drag reduction system (contoured flap).		AFM supplement 06L-5780, revision IR (or later approved revisions).		22/11/2007	Active	10016131
EASA.IM.A.S.02326	B/E AEROSPACE LIMITED		TCCA SA95-67	DHC-8-300 DHC-8-100, DHC-8-200	Installation of Aero Consulting Services Ltd. "Improved Exhaust Outlet Shroud Assembly" according to Transport Canada STC SA 95-67		The manufacture and installation of the Improved Exhaust Outlet Shroud Assembly is to be completed in accordance with Aero Consulting Services Ltd. Modification Data Summary Number A23820, Revision D, dated March 27, 2001 or later DOT approved revision.Required equipment: Aero consulting Services Lt...		01/03/2007	Active	10016132

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02329	L-3 COMMUNICATIONS INTEGRATEDSYSTEM L.P. WACO OPERATION		FAA STC ST9765SC-D	BOEING 767	Installation of a First-Class Interior/The project installsan all first-class interior in a Swiss registered Boeing 767 aircraft. This interior consists of installing 54seats, a bar and dining area, and upgrades to entertainment system electronics.		The installation of a First-Class Interior in accordance with:¿ L-3 Communications Integrated Systems L.P. Drawing List Section 2.1 of Report 33263-00004, Revision A, dated May 1, 2007.¿ L-3 Airplane Flight Manual Supplement, dated May 1, 2007.	1. Instruction for Continued Airworthiness (ICA) dated May 1, 2007.2. This approval is limited to only the installation made in the Boeing Model B767-306, Serial Number 30393 aircraft.	15/05/2007	Active	10016133
EASA.IM.A.S.02330	DELTA ENGINEERING CORPORATION		FAA ST01767NY	BOEING 747-200	Update of seat components for System 2000E per DAS project DAS-2056-03 on a B747-400.		Data package containing the following documents, and additional supporting data:1 DAS-2056-03 Rev. B Project plan for an update of Panasonic System 2000E in a B747.2 IS 60461 Seatequipment configuration3 WD60461 Seat equipment wiring diragram4 TL10522 System 3000 installation5 WD10397 Rev. B Wiring...	This STC is approved only for the product configuration as defined in the approved design data. Compatibilitty with other aircraft/engine configuraitons shall be determined by theinstaller.	25/03/2008	Active	10016134
EASA.IM.A.S.02331	JET ENGINEERING LLC		FAA STC ST01943LA	DC-9-81 (MD-87) DC-9-81 (MD-83) DC-9-81 (MD-82) DC-9-81 (MD-81)	Installation of a JET Engineering, Ltd. Advanced Jet Nozzles on the above airplane model(s) when powered by Pratt & Whitney JT8D-21JT8D-217, 7A, -217C, 219 engines		FAA STC ST01943LA amended 2/13/07JET Engineering Master Drawing List (MDL) No. 201-1000 Rev. A.Airplane Flight Manual Supplement No. 200-495, Rev. AComplete Data List, JET-CDL-201, Rev. BAdvanced JET Nozzle Installation, JET-205-310, Rev. N/ CWeight and Balance Manual Supplement, JET-TR-505, Rev. N/C...	This installation is done concurrently with STC EASA.IM.E.S.01012, installation of Jet Engineeirng, Ldt. Turbine Exhaust Cone Mixer(TECM), which modifies the Pratt & Whitney JT8D-217, JT8D-217A, -217C, -219 engines.	14/06/2007	Active	10016135
EASA.IM.A.S.02332	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA07-087/D ISSUE 1	BOMBARDIER BD-700-1A10	Customized Interior Completion - SN 9213Validation of TCCA STC C-LSA07-087/D issue 1		AFM Supplement G-FM25000155,TCCA SoC letter C-06-0668, dated June 19, 2007,ICA: GC92130000-IFCA	Refer to the Limitations sections of the required FM Supplement,WLAN system is compatible to IEEE 802.11 (b),The use of WLAN is subject to operational rules,Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previ...	09/07/2007	Active	10016136
EASA.IM.A.S.02333	AIRCRAFT SYSTEMS AND MANUFACTURING,INC		FAA STC NO. ST10606SC	767-200, 767-300, 767-400ER	Installation of Mode S Upgrade, Elementary and Enhanced Surveillance Parameters		ASM Top Drawing List No. 5675-0001-00, Rev C, 08/12/2006		07/03/2008	Active	10016137
EASA.IM.A.S.02334	GULFSTREAM AEROSPACE CORPORATION.	REV. 1	FAA STC ST02873AT-D	GULFSTREAM 200	Installation of a Runway Awareness and Advisory System i.a.w. Index List CEB1 3498000.Note: This Revision corrects a typo in the Original Product Type Certificate Number.		¿ AFMS CEB1 349M001 ¿ AFMS CEB1 349M000	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	04/03/2009	Active	10016138
EASA.IM.A.S.02335	LITEAIR AVIATION PRODUCTS Inc.		FAA STC ST01732SE	BOMBARDIER CL-600-2B19	Installation of light weight window plug.		FAA STC ST01732SELite Air Aviation Products MDL LAP1007-D01, Revision IR dated January 15,, 2007 or later approved revision.	N/A	15/03/2007	Active	10016139
EASA.IM.A.S.02337	GULFSTREAM SERVICES CORPORATION		FAA STC ST02883AT-D	GULFSTREAM 200	Installation of Transponder Flight ID i.a.w. Index List CEB1 1268000, Rev. NC or later FAA approved version,		AFMS CEB1 126M000 for -501 and -503 configuration,AFMS CEB1126M001 for -505 configuration,AFMS CEB1 126M003 for -507 configuration,		20/08/2007	Active	10016141

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02338	GULFSTREAM SERVICES CORPORATION		FAA STC ST03358AT-D	GULFSTREAM 200	Installation of Universal UNS 1C+ Dual FMS Software upgradei.a.w. Index list CEB1 1188000 Rev. B or later approved version.		AFMS CEB1 118M000		20/08/2007	Active	10016142
EASA.IM.A.S.02339	GULFSTREAM SERVICES CORPORATION		FAA STC ST02872AT-D	GULFSTREAM IV	Installation of Gables Flight Identification.		In accordance with Gulfstream Aerospace Corporation Index List CE41 1268004, Revision L, dated June 06, 2007, or later FAA approvedrevision. FAA approved Airplane Flight Manual Supplement, CE41 126M000, Revision NC, dated June 11, 2004, or later FAA approved revision is required for the -501 config...	Compatibility of this design change with previously approved modifications must be determined by the installer. If theholder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence ofthat permission.	19/10/2007	Active	10016143
EASA.IM.A.S.02345	GULFSTREAM AEROSPACE CORPORATION	REV 1	FAA STC ST02228CH-D	GULFSTREAM GV-SP GULFSTREAM GIV-X	Installation of the Heads Up Technologies CMS-400 ChecklistManagement System.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514258000, Revision C dated November 28, 2007,or later FAA Approved revision.Operation to be in accordance with Gulfstream Flight Manual Supplement GC414225M000, Revision B, dated November 28, 2007, or later approve...		10/01/2008	Active	10016144
EASA.IM.A.S.02346	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01931LA-D	GULFSTREAM GV-SP	Aircraft Serial No. 5139 completion and cabin interior installation.		Installation in accordance with Gulfstream Aeropsace Coporation Index List No. GC52 0008566, Revision G, dated 30 May 2007, or later approved revisions.Operation to be in accordance with Gulfstream Flight Manual Supplement GC52000M044, Original release, dated 30 May 2007, or later approved revisions...	GV-SP Serial No. 5139 Only.	14/06/2007	Active	10016145
EASA.IM.A.S.02347	S-TEC CORPORATION		FAA STC SA09397CA-D	PIPER PA-31-350 PIPER PA-31-325 PIPER PA-31-300 PIPER PA-31	Installation of S-TEC System 65 Two Axis Automatic Flight Guidance System with Autotrim, Model ST-849, and with Optional Flight Director/Steering Horizon.		- Bulletin No. 949, Rev. 5, dated 01-Jul-2003 or later approved revision,- Master Drawing List No. 921136, Rev. E, dated 01-Jul-2003, with Optional Flight Director / Steering Horizon, or later approvedrevision- FAA/ DAS Approved Pilot's Operating Handbook, and / or Airplane Flight Manual Sup...	This STC is also eligible on:- PA-31 and PA-31-300 when modified per STC SA970SO,- PA-31-325 when modified per STC SA00048SE,- PA-31-350 when modified per STC SA1151SO and / or any of STC SA5796NW, STC SA00192SE, STC SA00039SE, STC SA00126SE.If airplane is modified per one or more of th...	23/02/2007	Active	10016146
EASA.IM.A.S.02348	AVIATION TECHNICAL SERVICES, Inc.		FAA SA7030NM-D	737-300	Installation of Allied Signal p/n 967-0102-001 Digital Flight Data Acquisition Unit (DFDAU) and necessary sensors and wiring to record Twenty Two (22) Parameters of data per Tramco Incorporated Master Drawing List 95-180 Sheet 1 Revision Adated January 12, 1996 or later FAA-DAS approved revision.		Tramco Incorporated Master Drawing List 95-180 Sheet 1 Revision A, dated January 12, 1996 or later EASA approved revision.	1. Approval of this change in Type Design applies to theabove model aircraft only. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any ofo...	27/02/2007	Active	10016147

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02349	LEARJET Inc.		FAA STC SA8133NM-D	BOMBARDIER CL-600-2B16 (CL-604	Replacement of a Collins TCAS II bottom OMNI-Directional Antenna (Sensor Systems)		FAA STC No. SA8133NM-D Learjet Inc. MDL No, CA-1024C-TUC atRevision A dated 02 February 1999 or later Approved Revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	07/05/2007	Active	10016148
EASA.IM.A.S.02351	DUNCAN AVIATION, INC.		FAA STC NO. ST02091 CH-D	HAWKER 800 XP HAWKER 800 BAE 125 SERIES 800A	Replacement of Existing 3, 4 and 5 auxiliary batteries with Securaplane XL245 lead acid batteries		Duncan Aviation Master Drawing List 060412006, Revision C, dated December 20, 2006 or later approved revision	1. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.	30/04/2007	Active	10016149
EASA.IM.A.S.02352	ASSOCIATED AIR CENTER, L.P.		FAA ST10536SC	A319-115	Installation of an Executive Style Interior in accordance with Master Document List, Document Number 2459000000, Revision IR, dated25 October 2007, or later EASA approved revision.First installation is on MSN 2837		AFM Supplement, Document Number 2459021090, Revision IR, dated 25 October 2007, or later EASA approved revision.Instructions for Continued Airworthiness, including Airworthiness Limitations Section, Document Number 2459050090, Revision B, dated 24 October 2007, or later EASA approved revision.	The aircraft is limited to Private use only (not to be operated for hire, reward or common carriage).This STC is approved only for the product configuration as defined in the above Master Document List.Limitations and Conditions specified in FAA STC ST10536SC D remain applicable	30/10/2007	Active	10016150
EASA.IM.A.S.02353	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC ST03379AT	400, 400A, 400T	Replacement of a Standby Altimeter installation in the Raytheon (Beech) models 400, 400A, 400T aircraft inaccordance with Master Data List (MDL), RAS1106DL004, Revision 1, dated, January 4, 2007, or laterFAA Approved Revision.		see above	This approval should not be extended to other aircraft of this model on which other previously approvedmodifications are incorporated unless it is determined by the installer thatthe interrelationship between thischange and any of those other previously approved modifications will produce no advers...	25/04/2007	Active	10016151
EASA.IM.A.S.02354	AEROCET, INC.		FAA STC SA00137SE	180A, 180H, 180J, 180K	Installation of Aerocet Model 3500 or 3500L seaplane floatson Cessna 180 Aircraft.		Installation must be in accordance with Master Document List 35-10006 Rev. B dated 21 June 1994 or later Approved Revisions.Operation must be in accordance with Flight Manual Supplement No. A-10018 (180A-180F), A-10019 (180G-180H) and A-10020 (180J, 180K)dated 210Oct 1994, or later approved revision...	Those Cessna Model 180G, 180H, 180J and 180Kairplanes equipped with the structural modifications defined in Kenmore AirHarbour STCNo. SA649NW, Amendment dated 14 July 1984, may be operated on Aerocet Model 3500 or 3500L floats at gross weight up to 3190lbs., subject to the limitation specified in A...	09/08/2007	Active	10016152
EASA.IM.A.S.02355	AEROCET, INC.		FAA STC SA5908NM	CESSNA A185F CESSNA A185E CESSNA 185E CESSNA 185D CESSNA 185C CESSNA 185B CESSNA 185A	Installation of Aerocet Model 3500 or 3500L seaplane floatson Cessna 185 Aircraft.		Installation must be in accordance with Master Document List 35-10006 Rev. B dated 21 June 1994 or later Approved Revisions.Operation must be in accordance with Flight Manual Supplement No. A-1001 dated 15 March 1995, or later approved revision.	The airplane must incorporate the Cessna approved seaplane kit referred to Section 7 of the Aerocet AFM. The airplane must be equipped with the Cessna rudder centering device/non-linear rudder centering spring system defined on Aerocet Drawing No. 35-10000, Sheet5 of 5.The installation of this modif...	09/08/2007	Active	10016153

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02356	AEROCET, INC.		FAA STC SA00003SE	U206A THRU U206G TU206A THRU TU206G P206, P206A, TP206A	Installation of Aerocet Model 3500 or 3500L seaplane floats		FAA approved Aerocet Master Drawing List No. 35-10010, Revision H, dated 26-Jan-2006, or later approved revisionFAA approved Aerocet Aircraft Flight Manual Supplement, Doc. No. A 10011, Revision 1, dated 26-Jan-2006, or later approved revisionFAA approved Instructions for Continued Airworthiness, Do...		03/07/2007	Active	10016154
EASA.IM.A.S.02359	BLACKHAWK MODIFICATIONS Inc.	REV. 2	FAA SA01946LA	BEECH F90 BEECH E90 BEECH C90A BEECH C90 BEECH B200T BEECH B200CT BEECH B200C BEECH B200 BEECH A200CT BEECH A200C BEECH A200 BEECH 200T BEECH 200CT BEECH 200C BEECH 200	Installation of Ultra Electronics Engine Instruments.Revision 1: Installation of powerplant indication system. This project is to amend EASA of EASA STC No. EASA.IM.A.S.02359.		- Installation of in accordance with Master Drawing ListNo. 90-000, Rev. C, dated 24. July 2008 or later approved revision.- Operation must be in accordance with Aircraft Flight Manual Supplement No. AFMS 55023-11 Rev B dated 30. Sept 2008 or later approved revision.- Maintenance must be i...	1. Blackhawk Modifications, Inc. STC SA10341SC or SA10364SC is a prerequisite for this modification.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no3...	27/05/2009	Active	10016156
EASA.IM.A.S.02361	JOHN DEERE AGRI SERVICES, Inc.		FAA STC SA00622DE	CESSNA F182P/Q CESSNA F172M/N/P, CESSNA 182P/Q/R, F150L/M, CESSNA 150L/M, 172M/ N/P/Q	Installation of John Deere Agri Services, Inc. JD3 Aerial Imaging System (externally mounted camera / internally mounted computer) for aerial surveying of agricultural fields.		Master Drawing List, Doc. No. JD3MDL, Rev. C, dated 11-Jan-2007, or later approved revisionInstallation Instructions aslisted in the ATL, Doc. No. EASA.IM.A.S.02361-ATL, Rev. 0, dated 26-Apr-2007, or later EASA approved revision.Airplane Flight Manual Supplement as listed in ATL.Instructions for Co...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	04/05/2007	Active	10016157
EASA.IM.A.S.02377	SIMMONDS PRECISION PRODUCTS, Inc		FAA STC ST00235BO	BOEING 737-400	Installation of the Goodrich Corporation Fire Detection (Class “E”)		Goodrich Corporation Master Drawing List T3078-MDL-2001, Revision H, dated May 30, 2006 or later approved revision	1. The installation of this equipment is only applicable on737-400 aircraft modified to full freighter configuration per Pemco STCnumbers SA2968SO, SA2969SO, SA2970SO and SA2971SO inclusively.2. Goodrich Corporation Airplane Flight ManualSupplement T3078-0006-01, Revision D, dated June 5, 2006, or...	07/05/2007	Active	10016158
EASA.IM.A.S.02381	AIRCRAFT TECHNICAL SERVICE, Inc.		FAA STC SA02123LA	200	Installation of a nose mounting truss, bulkhead, camera, electronic backplane and missile seeker head.		Installation in accordance with Aircraft Technical ServiceInc Master Data list 3006, Revision H, dated March 12, 2008, or later approved revisions.Aircraft to be operated in accordance with FAA Approved Airplane Flight Manual Supplement ref Document No ATS Report 2734, RevisionNew, dated March 27,...	This approval is limited to Aircraft Serial Number BB-777 Only.This STC cannot be removed from the subject aircraft (BB-777) without an EASA approved modification that re-establishes it’s conformity to the Type design standard detailed in EASA TCDS ref IM.A.277. This modification will have to includ...	28/04/2008	Active	10016159

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02382	LEARJET Inc.		FAA STC ST01082WI-D	LEARJET 60	Universal UNS-1E/C+ Flight Management SystemFAA STC ST01082WI-D		Design Compliance Report 60-D1810 *MDL M100378ICT ** or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).	1. This approval only applies to the -004, -005, -006, and -010 configurations of the Universal UNS-1C+ Flight Management System2. See also FAA STC ST01082WI-D3. Prior toinstallation of this modification the installer must determine that the interrelationship between this modification andi...	08/08/2007	Active	10016160
EASA.IM.A.S.02383	LP AERO PLASTICS, INC.		FAA STC SA00204NY	BEECH S35 BEECH P35 BEECH N35 BEECH M35 BEECH K35 BEECH J35 BEECH H35 BEECH G35 BEECH F35 BEECH E35 BEECH C35 BEECH B95A BEECH B95 BEECH A35 BEECH 95-B55 BEECH 95-A55 BEECH 95-55 BEECH 95 BEECH 35-C33 BEECH 35-B33 BEECH 35-A33 BEECH 35-33 BEECH 35	Installation of 250”, 312” or 375” thick one piece windshields (two piece windshield to one piece wind shield conversion).		LP Plastic Aero Plastics, Inc., Single Piece Extra Thick Windshield Installation Drawing List: Report No. 271/CON datedApril 27, 1994.	1. This approval should not be incorporated in any aircraft models listed in this STC on which other approved modifcations are incorporated , unless it is determined that the interrelationship between this change and any of those previously incorporated approved modifications will not introduce a...	20/04/2007	Active	10016161
EASA.IM.A.S.02385	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02348CH-D	GULFSTREAM IV	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 1331.		Install in accordance with Gulfstream Aerospace Report CE428043002, Revision NC. And Master Drawing List CE428048000, Revision B, dated May 1, 2007 or later approved revisions.Operate in accorance with Gulfstream Flight Manual Supplement CE42 804M000, Revision -, dated May 3, 2007 or later approveds...	Aircraft S/N 1331 Only.	31/05/2007	Active	10016162
EASA.IM.A.S.02390	LEARJET Inc.		FAA STC SA8100NM-D	BOMBARDIER CL-600-2B16	Installation of an Axle Jack Storage Box Installation		DAS-12-NM Certification PlanCA-3074-TUC Master Drawing ListP030-C-97 Compliance Checklist / MOCSTR-M319 Structures Report		31/05/2007	Active	10016163
EASA.IM.A.S.02391	LEARJET Inc.		FAA STC SA8097NM-D	BOMBARDIER CL-600-2B16	Installation of an Engine Cover Storage - Aft Equipment		DAS-12-NM Certification PlanCA-3073-TUC Master Drawing ListP029-C97 Compliance Checklist / MOCSTR-M311 Structures Report		31/05/2007	Active	10016164
EASA.IM.A.S.02392	LEARJET Inc.		FAA STC SA6003NM-D	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601	Interior Installation/Modification in accordance with DAS approved Learjet Master document list No. CA-1000TUC, Rev "N"dated January 12, 1995 or later approved revision		Learjet Airplaine Manual Supplement C1002, original release, dated March 5, 1993 C1003 original release, dated Febr 23,1993, C1004, original release, dated Febr 23, 1993, C1005, original release, dated March 10, 1993; C1011, original release, dated Oct 12, 1993 or later approved revision	The proper interrelationship between this installation and any previously approved configuration has to be assured.	03/08/2007	Active	10016165

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02393	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA01396WI	BEECH 390	Modification to install a Collins IFIS 5000, a file server unit, cursor control panel, XM weather receiver and antenna		RAS Master Data List: RAS050500169, Rev 2.0, dated 20 June 2006 or later FAA approved RevisionFAA approved RAS AFM-S Doc. No. RAS050500183, dated 7 July 2006, or later FAA approved Revision		03/07/2007	Active	10016166
EASA.IM.A.S.02394	RAYTHEON AIRCRAFT SERVICES, INC.		FAA STC SA01426WI	C90A, C90GT	Installation of replacement static inverters. Data required: 1. RAS Master Data List RAS230600970, Revision 1.0, dated January 30, 2007, or later approved revision.		see above	1. Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.2. This STC is app...	03/05/2007	Active	10016167
EASA.IM.A.S.02395	ELISEN TECHNOLOGIES		TCCA STC SA07-20	BOMBARDIER CL-600-2B19	Miscellaneous Storage Box, Project No. 29R2-707		MDL -29R2-707 rev NC or later approved revision.Instructionfor continued airworthiness ICA-29RD-707 revision NC or later approved revision.		03/07/2007	Active	10016168
EASA.IM.A.S.02396	ELISEN TECHNOLOGIES		TCCA STC SA07-21	BOMBARDIER CL-600-2B19	Towbar Stowage, Project No. 29R2-708.		MDL-29R2-708 revision NC or later approved revision.Instructions for continued Airworthiness ICA-29R2-708 revision NC or later approved revision.		03/07/2007	Active	10016169
EASA.IM.A.S.02397	ELISEN TECHNOLOGIES		TCCA STC SA07-22	BOMBARDIER CL-600-2B19	Equipment Bay Forward Catwalk, Project No. 29R2-709.		MDL-29R2-709 revision NC or later approved revision.Instructions for continued Airworthiness ICA-29R2-709 Revision NC or later approved revision.		03/07/2007	Active	10016170
EASA.IM.A.S.02398	ELISEN TECHNOLOGIES		TCCA STC SA07-23	BOMBARDIER CL-600-2B19	Equipment Bay Stowage Box, Project No. 29R2-710.		MDL-29R2-710 revision NC or later approved revision.Instructions for continued airworthiness ICA-29R2-710 revision NC or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	04/07/2007	Active	10016171
EASA.IM.A.S.02399	BOMBARDIER AEROSPACE		TCCA C-LSA07-204/D	BD-100-1A10 (CHALLENGER 300)	AIRCRAFT COMPLETION, 9 PASSENGERS INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental TypeCertificate C-LSA07-204/DIssue 1 dated 7th September 2007, in accordance with Aero ConsultingServices Ltd. ModificationData Summary F384000 Revision N/C		• Transport Canada Limited Supplemental Type CertificateC-LSA07-204/D Issue 1, dated 7th September 2007.• Transport Canada Approved Aero Consulting Services Ltd. Airplane Flight Manual Supplement F384090 Revision N/C or later Transport Canada approved revision.• Instructions for Continued...	1. This STC is limited to aircraft Bombardier BD100-1A10Serial Number 20149.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the...	24/09/2007	Active	10016172
EASA.IM.A.S.02400	HONEYWELL INTERNATIONAL INC.		FAA STC ST00717WI	BOEING B737-400 BOEING B737-300 BOEING 737-500 BOEING 737-200 SERIES	Installation of the Honeywell Mark II ACARS		Master Drawing List 159-08189-0001, Revision J, dated July 25, 2004, or later approved revisionsAirplane Flight Manual Supplement 756-0182-800 revision "Original", dated September16, 2004, or later approved revision.	Compatibility of this design change with previously approved modifications must be determined by the installer.If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.	21/05/2007	Active	10016173

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02403	S-TEC CORPORATION		FAA STC SA09139AC-D	PIPER PA-44-180	Installation of S-TEC Manual Electric Trim System, Model ST-619, in above mentioned airplane Type / Variant		Bulletin No. 719, Revision IR, dated 05-Mar-1996, or later approved revisionFor field installations: Master Drawing List No. 92898, Initial Revision, dated 05-Mar-1996, or later approved revisionsFor Piper Factory Installations: Master Drawing List No. 92898-1, Initial Revision, dated 05-Mar-1996 or...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	15/06/2007	Active	10016175
EASA.IM.A.S.02405	AVIATION TECHNICAL SERVICES, Inc.		FAA SA5115NM	737-300	Installation of a Collins Traffic Alert and Collision Avoidance System (TCAS II) Transmitter/Receiver with Honeywell TA/RA/IVSI´s.		• FAA STC SA5115NM• ATS, Inc. Top Drawing 90-114, Revision F, dated January 05, 1995• Airplane Flight Manual Supplement D2000-163 approved February 22, 2001- or later revisions of the above documents approved by EASA in accordancewith EASA ED decision 2004/04/CF (or subsequent revisions of...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	22/04/2009	Active	10016176
EASA.IM.A.S.02406	AVIATION TECHNICAL SERVICES, Inc.		FAA SA4978NM	737-300	Installation of Traffic Alert and Collision Avoidance System (TCAS) provisions		Tramco Top Drawing 90-078 Revision A dated August 20, 1990,or later approved revision	This approval is applicable only to the electrical provisions for TCAS and does not approve the actual TCAS installation or any TCAS equipment.	12/07/2007	Active	10016177
EASA.IM.A.S.02407	SIERRA INDUSTRIES Ltd.		FAA STC SA29NW	CESSNA 402 CESSNA 401	Robertson STOL ModificationInstallation of fowler flaps, flap actuated droop ailerons, flap actuated trim and anti-servo rudder trim tab in accordance with Drawing List No. 24		As referred in FAA STC SA29NWFAA approved Robertson AFM-S, or later FAA approved RevisionsRobertson Drawing List No. 24	As referred in FAA STC SA29NW:Max. Flap Extension Speed VFE: 10° Flap 195 mph (CAS) 30° Flap 145 mph (CAS)Min. SingleEngine Control Speed VMC : 10° Flap 83 mph (CAS) Flap up (...	19/03/2008	Active	10016178
EASA.IM.A.S.02408	BEECHCRAFT CORPORATION	REV. 2	FAA ST09955SC-D	HAWKER 900 XP HAWKER 800XP, HAWKER 850XP HAWKER 750, HAWKER 800 BAE.125 SERIES 800A	Installation of a Divan Cargo Net Assembly.			1. In accordance with Master Drawing List 800-197, Revision D, or later approved revision.2. Maintenance Manual Addenda 25-50-05,	20/05/2008	Active	10016179
EASA.IM.A.S.02410	SAFRAN CABIN GALLEYS US, INC.		FAA STC ST00826LA	AIRBUS A340-300	Installation of Lower Deck Mobile Crewrest.		-• FAA STC ST00826LA dated 15 April 2003• Master DataList, Ref. MDL-101682, Rev. C, dated April 1st 2002.• Component Maintenance Manual with Illustrated Part List, Ref. 25-70 03, dated 30th September 2001• or later revisions of the above listed documents approved by EASA in accordance w...	1. The limitations and conditions as referenced in FAA STC ST00826LA apply.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the a...	22/08/2007	Active	10016181
EASA.IM.A.S.02411	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10021SC	GULFSTREAM 200	Installation of an executive cabin interior on Gulfstream 200 S/N 065 including miscellaneous mechanical and electricalmodifications to S/N 065.		Index list GA220008065, rev. A, dated 17/05/2003*FAA approved Flight Manual Supplement GA 21468M065, Rev.-, dated 17/05/2003*Misc Mech Mod List GA244680065Misc Elec Mod List GA214680065* or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CFv...	This approval is limited to Gulfstream G200 S/N 065 only.	15/08/2007	Active	10016182

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02412	CHIPPEWA AEROSPACE, Inc.		FAA STC ST 03080 AT	SD3-60 SHORTS	Installation of a Honeywell AAK VI EGPWS.		• FAA STC ST03080AT. MDL SD3-60-3443-0001 Rev 1 dated 03/28/05.• AFMS SD3-60-3443-1012. Instruction for continuedairworthiness SD3-60-3443-0002.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	03/07/2007	Active	10016183
EASA.IM.A.S.02413	CHIPPEWA AEROSPACE, Inc.		FAA STC ST 02898 AT	BOMBARDIER CL-600-2C10 BOMBARDIER CL-600-2B19	Installation of a Honeywell MK V EGPWS. (FAA STC ST 02898 AT).		FAA STC No. ST02898AT, dated 30 July 2004.FAA Statement of Compliance, dated 3 April 2007.Chippewa Aerospace Master Drawing List (MDL) No. 601-3441-0001 Rev. IR, dated 17 May 2004or later approved revision.Chippewa Aerospace Airplane Flight Manual Supplement No. 601-3442-1012, dated 30 July 2004 or...		07/04/2008	Active	10016184
EASA.IM.A.S.02414	CHIPPEWA AEROSPACE, Inc.		FAA STC ST 03336 AT	BOMBARDIER CL-600-2B19	Installation of Protective Covers for K4XD Relay. Traffic Alert and Collision Avoidance Systems (TCAS) Processor and Horizontal Stabilizer Control Unit (HSTCU).		FAA STC ST03336AT.	N/A	29/05/2007	Active	10016185
EASA.IM.A.S.02415	CHIPPEWA AEROSPACE, Inc.		FAA STC ST 03099 AT	BOMBARDIER CL-600-2B19	Installation of a replacement landing gear wiring harness.		FAA STC 03099AT	N/A	29/05/2007	Active	10016186
EASA.IM.A.S.02416	GULFSTREAM AEROSPACE CORPORATION		US FAA STC NO. ST01775LA-D	GULFSTREAM GV-SP	Installation of an Avionica Inc Miniature Quick Access DataRecorder (Mini QAR)		Installation in accordance with Gulfstream Aerospace Corporation Index List No. GC51 4208000, Revision C, dated 27 September 2006, or later approved revisions.		21/06/2007	Active	10016187
EASA.IM.A.S.02417	GULFSTREAM SERVICES CORPORATION		FAA STC ST03409AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4004.		Install in accordance Custom Engineering Index List, Airplane Custom Interior STC CE425006000 Rev-, dated August 24, 2007, or laterapproved revisions.	Aircraft Serial Number 4004 only.The following STCs are a required part of this STC:- ST02979AT-DST02987AT-DST02948AT-DIt is the installers responsibility to ensure these STCs are all EASA approved.	09/10/2007	Active	10016188
EASA.IM.A.S.02418	HOLLINGSEAD INTERNATIONAL		FAA STC ST00740LA-D	BOEING 737-300	Installation of Smoke Detection and Fire Suppression Systems Provisions, Lower Cargo Compartments.		Hollingsead International, Inc. Drawing No. 90446 (-506/-507) Rev A dated 5/19/99 and Drawing List 12114 Revision A dated 5, 24/99 or later EASA approved revisions.		09/10/2007	Active	10016189
EASA.IM.A.S.02429	B/E AEROSPACE LIMITED		TCCA SA01-65, ISSUE 4	DHC-8-300 DHC-8-100, DHC-8-200	Addition of filtration to Cabin Recirculation Air.Addition of recirculation air filter reduces potential blockage of the condenser mixer and promotes peak performance of the ECS system. TCCA STC SA01-65, Issue 4, dated 24 June 2005.		Aero Consulting Services Modification Data Summary No. C46000 Revision D or later approved revisions for DHC-8-100 and DHC-8-200 series or S46030 Revision C or later TCCA approved revisions for DHC-8-300 series.Maintenance Manual Supplement (MMS) C46071 abd Parts Manual Supplement (PMS) C46073 for...	1. Applicable to DHC-8-100 series with 1990 (Post-Mod 8/1127*) cabin interior, all DHC-8-200 series and DHC-8-300 series with 1990 (Post-Mod 8/1128*) cabin interior.*Including Hunting and CD interior.2. Prior to installation of this modification the installer must determine that the interrelat...	06/07/2007	Active	10016192

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02430	CANARD AEROSPACE CORPORATION		FAA STC ST01106CH	BOEING 747-SR BOEING 747-SP BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-200B BOEING 747-100B SUD BOEING 747-100	Installation of Digital Flight Data Recorder Expanded Parameters in accordance with Canard Aerospace Corporation Document Control Drawing No. 30010, Rev. G. dated 6 October 2003, or later FAA approved revisions, FAA STC number ST01106CH.		Data package containing the following documents, and additional supporting data:1. Certification Plan 31-3314-01 Rev. B2. Top level Documents Control Drawing No. 30010 Rev. G. for747-100 Series; 747-100B series, 747-100B SUD series; 747-200B Series;747-200C Series; 747-200 F Series; 747-300 Series;...	This STC is approved only for the product configuration as defined in the approved design data. Compatibility with other aircraft/engine configurations shall be determined by the installer.	29/10/2007	Active	10016193
EASA.IM.A.S.02431	S-TEC CORPORATION		FAA STC SA8886SW-D	CESSNA U206G CESSNA U206F CESSNA U206E CESSNA U206D CESSNA U206C CESSNA U206B CESSNA U206 CESSNA TU206G CESSNA TU206E CESSNA TU206D CESSNA TU206C CESSNA TU206B CESSNA TP206D CESSNA TP206C CESSNA P206E CESSNA P206D CESSNA P206A CESSNA P206 CESSNA 206	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-556 in above mentioned airplaneTypes / Variants, also when modified per STC as listed in 3.5 (Limitations and Conditions)		Bulletin No. 656, Revision 3, dated 08-Mar-2001, or later approved revisionMaster Drawing List No. 92722, Revision C, dated 08-Mar-2001, or later approved revision (28 Volt System)FAA/DAS Approved Pilot's Operating Handbook and/or AirplaneFlight Manual Supplement, P/N 891110, Revision 1, dated 13-M...	This STC is also eligible on variants 206, P206, U206, P206A, TP206A, U206A, TU206A, P206B, TP206B, U206B, TU206B, P206C, TP206C, U206C, TU206C, P206D, TP206D, U206D, TU206D, P206E, TP206E, U206E, TU206E, U206F, and TU206F when converted to 28 Volt electrical system, and U206G, and TU206G (landplane...	05/07/2007	Active	10016194
EASA.IM.A.S.02433	HONEYWELL INTERNATIONAL Inc.		FAA STC ST00361LA	GULFSTREAM IV	Installation of the Honeywell HUD-2020 Head up Display System on Gulfstream G-IV aircraft for Category II approach criteria.		In accordance with Master Data List Spec No 5220-0697, Revision G dated July 26, 1997 or later approved revisions.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	18/02/2009	Active	10016195
EASA.IM.A.S.02434	S-TEC CORPORATION		FAA STC SA09352AC-D	MXT-7-180,MXT-7-180A, MT-7-235 MX-7-180, M-7-235, M-7-235A MX-7-180A,MX-7-180B, MX-7-180C M-7-260, M-7-260C M-7-235B, M-7-235C, MX-7-235 M-5-210C, M-5-235C, M-6-235,	Installation of S-TEC System, Model 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model ST-810		FAA approved S-TEC Bulletin No.910, Revision 4, dated 26-Dec-2000, or later approved revisionFAA approved S-TEC Master Drawing List No. 921085, Revision D, dated 26-Dec-2000, or later approved revision.FAA/DAS Approved Pilot's Operating Handbook and/or Airplane Flight Manual Supplement, P/N 891691S,...	This STC is eligible on variants M-5-210C, M-5-235C, M-6-235, MX-7-180, M-7-235, M-7-235A, M-7-235B, M-7-235C and MX-7-235 in landplane, floatplane, or amphibian configuration.This STC is eligible on variants MX-7-180A, MX-7-180B, MX-7-180C, MXT-7-180, MXT-7-180A, and MT-7-235 in landplane configura...	03/07/2007	Active	10016196
EASA.IM.A.S.02437	BOMBARDIER INC.		TCCA STC C-LSA07-288/D	BOMBARDIER BD-100-1A10 (CHALLE	Aircraft Completion, 10 passengers interior configuration:EASA Validation of:Transport Canada Limited Supplemental TypeCertificate C-LSA07-288/D, issue 1dated 22nd October 2007, in accordance with Aeoro Consulting Services Ltd. Modification Data Summary F494000 Revision A dated 25.10.2007.		Transport Canada Limited Supplemental Type Certificate C-LSA07-288/D Issue 1, dated 22nd October 2007.Transport Canada Approved Aero Consulting Services Ltd. Airplane Flight Manual Supplement F494090 Revision N/C or later Transport Canada approved revision.Instruction for continued Ariworthiness ref...	This STC is limited to aircraft Bombardier BD100-1A10 Serial Number 20155.	31/10/2007	Active	10016197

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02438	PEMCO WORLD AIR SERVICES	REV. 2	FAA STC SA2968SO	BOEING 737-400	Modification of floor in accordance with Pemco World Air Services, Inc. Master Data list, Report No. 2316, revision “K”, dated June15, 2006, or later EASA approved revision.		- Master Data list, Report No. 2316, revision “K”, datedJune 15, 2006, or later EASA approved revision.- Instructions for Continued Airworthiness (ICA), Pemco Report No 2917, Revision C, dated January 18, 2006, or later EASA approved revision, is also a required part of this STC, and should b...	Instructions for Continued Airworthiness (ICA), Pemco Report No 2917, Revision C, dated January 18, 2006, or later EASAapproved revision, is a required part of this STC, and mustbe incorporated into the operator’s maintenance program.	24/06/2008	Active	10016198
EASA.IM.A.S.02439	PEMCO WORLD AIR SERVICES	REV. 2	FAA STC SA2969SO	BOEING 737-400	Installation of a cargo door in accordance with Pemco WorldAir Services, Inc. Master Data list, Report No. 2373, revision “T”, dated June 15, 2006, or later EASA approved revision.		- Master Data list, Report No. 2373, revision “T”, datedJune 15, 2006, or later EASA approved revision- AirplaneFlight manual Supplement (AFMS), Report P03-003FM Rev 7, orlater EASA approved revision.- Instructions for Continued Airworthiness (ICA), Pemco Report No 2917, Revision C, date...	- Airplane Flight manual Supplement (AFMS), Report P03-003FM Rev 7, or later EASA approved revision.- Instructions for Continued Airworthiness (ICA), Pemco Report No 2917, Revision C, dated January 18, 2006, or later EASA approved revision, is also a required part of this STC , and should be i...	24/06/2008	Active	10016199
EASA.IM.A.S.02440	PEMCO WORLD AIR SERVICES		FAA STC SA2970SO	BOEING 737-400	Installation of a Class “E” Cargo Compartment and passengerinterior configuration in accordance with with Pemco World Air Services, Inc. Master Data list, Report No. 2374, revision “S”, dated June 15, 2006, or later EASA approved revision.		- Master Data list, Report No. 2374, revision “S”, datedJune 15, 2006, or later EASA approved revision- AirplaneFlight manual Supplement (AFMS), Report P03-003FM Rev 7, dated April 27th 2007 or later EASA approved revision.- Instructions for Continued Airworthiness (ICA), Pemco Report Nod...	- Airplane Flight manual Supplement (AFMS), Report P03-003FM Rev 7, dated April 27th 2007 or later EASA approved revision.- Instructions for Continued Airworthiness (ICA), Pemco Report No 2917, Revision C, dated January 18, 2006, or later EASA approved revision, is also a required part of this...	07/05/2007	Active	10016200
EASA.IM.A.S.02443	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01508LA-D	GULFSTREAM GV-SP	Aircraft S/N 5142 completion and cabin interior installation.		Installation in accordance with Gulfstream Aerospace Corporation Index List No. GC52 2046058, Rev. A, dated 9 July 2007, or later approved revisions.Operations to be in accordancewith Gulfstream Flight Manual Supplement GC52 204M019, original release, dated 17 July 2007, or later approved revisions...	GV-SP S/N 5142 only.	26/07/2007	Active	10016201
EASA.IM.A.S.02444	ROCKWELL COLLINS, Inc.		FAA STC SA01267WI-D	BEECH B300C BEECH B300 BEECH 300	Installation of Collins Pro Line 21 Avionics System.		Installation in accordance with:-Collins Master Drawing List ref RCA-0020-001, Revision G, dated 23 July 2008, or laterapproved revisions.Operation in accordance with:-Collins Flight Manual Supplement ref RCA-0030, Revision C, dated 21 July 2008, or later approved revisions, or:-In accordance withC...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	02/10/2008	Active	10016202

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02445	S-TEC CORPORATION		FAA STC SA09287AC-D	PIPER PA-28R-201T PIPER PA-28R-200 PIPER PA-28R-180 PIPER 31 AND SERIES	Installation of S-TEC System, Model 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model ST-729		• S-TEC Bulletin No.829, dated 08-Oct-1997, Initial Issue, or later approved revision• S-TEC Master Drawing List No. 921031, dated 08-Oct-1997, Initial Issue or later approved revision• FAA/DAS Approved Pilot's Operating Handbook and/or Airplane Flight Manual Supplement, P/N 891541, dated 1...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	26/07/2007	Active	10016203
EASA.IM.A.S.02446	COMMUTER AIR TECHNOLOGY Inc.		FAA STC SA10370SC	E90, H90 65-A90, B90, C90, C90A	Installation of exhaust gas extractors on Pratt & Whitney Canada PT6A-21, -27, -28, -29, -34, -34B, -135, or 135A turboprop engines.		Installation in accordance with Commuter Air Technology Drawing List No. DL02001, Rev. 8, dated October 8, 2004, or later approved revision.	Note that the airspeed and shaft horsepower limits listed in the original Airplane Flight Manuals are still applicable (see TC DataSheet No. 3A20). Compatibility of this design change with previously approved modifications must be determined by the installer. Ifthe holder agrees to permit another pe...	21/05/2007	Active	10016204
EASA.IM.A.S.02447	GULFSTREAM SERVICES CORPORATION		FAA STC ST01508LA-D	GULFSTREAM GV-SP	Aircraft S/N 5022 completion and cabin interior installation.		Installation in accordance with Gulfstream Aerospace Corporation Index List No. GC52 0008129, Revision J, dated 16 June2004, or later approved revisions.Operations to be in accordance with Gulfstream Flight Manual Supplement CE1605M000, original release dated 28 June 2007, or later approved revisio...	GV-SP S/N 5022 only.	26/07/2007	Active	10016205
EASA.IM.A.S.02450	UNIVERSAL AVIONICS SYSTEMSCORPORATION		FAA STC ST01879LA	BOMBARDIER CL-600-2B16 (601-3A	Universal Avionics Vision-1tm Synthetic System installed inCanadair Challenger CL600 Series.		Universal Avionics Master Drawing List MDL-2005-1003 Revision C dated 22 May 2006 or later approved revision.Universal Avionics Airplane Flight Manual Supplement AFMS-2005-1003 Revision IR dated 17 May 2006 or later approved revision.		23/11/2007	Active	10016206
EASA.IM.A.S.02452	GOODRICH CORPORATION		FAA STC ST02551CH	BOEING 747-400F	Installation of Centerline Restraint System on the main cargo deck of a B747-400F in accordance with Master Data List MDL 7M39300. Validation of FAA STC ST02551CH.		MD2522 Weight and balance control and loading manual supplement.MD2521 Aircraft cargo loading manual supplement.MD2535 Aircraft maintenance manual supplement.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	02/07/2008	Active	10016207
EASA.IM.A.S.02454	BOMBARDIER AEROSPACE		TCCA SA03-113	CL-600-2B16	Complete Custom Aircraft Interior.		TCCA STC SA03-113.Aero Consulting Services Configuration Definition List D817000 Revision P, dated 4-07-2007.Aero Consulting Services AFM D817090 Revision N/C or later approved revisions..	Restricted to ASN 5628.	06/09/2007	Active	10016208
EASA.IM.A.S.02455	LANDMARK AVIATION		FAA STC ST01136CH-D	HS125 SE.600A, HS125 SE.-700A DH125 SE. 3A/RA,DH125 SE. 400A DH125 SE.-1A, DH125 SE.-3A BH125 SE.400A, BH125 SE.-600A	Installation of a Senior Flexonics Inc. Signal Conditioner Unit		Garrett Aviation Services drawing list 38-0136-001, dated January 28, 2000, Revision 0, or later approved revision.	Compatibility of this design change with previously approved modifications must be determined by the installer.If the holder agrees to permit another person to use this certifcateto alter the product, the holder shall give the other person evidence of that permission.	31/05/2007	Active	10016209

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02456	AERO MEDICAL PRODUCTS MFG. Inc.		FAA STC SA1035GL	PA-31, PA-31-300, PA-31-325 PA-31-350 (CHIEFTAIN)	FAA STC SA 1035GL "Aircraft Stretcher System - Installationof Air Ambulance Stretcher P/N 125 Kit P/N 800, Medical Oxygen System Kit P/N 807 (FAA approved option), Inverter/ PumpKit P/N 812 in accordance with Drawing List Report 001 Rev.C or later approved revision.		- AFM Supplement EA Form FMS FAA Approved 09-02-2004 or later approved revision.- AMM Supplement EA Forms MMS FAAApproved 10-02-2004 or later approved revision.- Installation and Operating Instructions EA Form 109P FAA approved 23-10-2001 or later approved revision.- Maintenance Require...	1. Prior to the first flight of each modified aircraft, and after each exchange to any of the Communication, Navigational or MedPack Equipment, a ground EMI test must be conducted in accordance with EA form 173 dated 15-11-1993. A copy of the EA form 173 mustbe kept with the aircraft records.	01/02/2008	Active	10016210
EASA.IM.A.S.02458	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA ST02404CH	A318, A319, A320, A321	Activation of Honeywell Runway Awareness and Advisory System (RAAS).		FAA STC ST02404CH, issued 4th April 2007Armstrong AerospaceMaster Data List, ref. Document No. DC104-4042-00, dated 21.03.07 or later revisions approved by EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).Airplane Flight Manual Supplement, Armstrong Aer...		31/10/2007	Active	10016211
EASA.IM.A.S.02460	ROCKWELL COLLINS, Inc.		FAA STC ST01119WI-D	MYSTERE FALCON 50 HAWKER HS 125-700B HAWKER HS 125-700A GULFSTREAM IV GULFSTREAM 1159 (G-II) GULFSTREAM 1159 B (G-II) GULFSTREAM 1159 A (G-II) FALCON 900EX FALCON 900 FALCON 10 CESSNA 750	Modification of Collins TDR-94 or TDR-94D Mode S Transponder System installation with stand-alone Collins TRU-4210 or RTU-4220 Radio Tuning Unit(s) to a Flight ID capable Collins TDR-94 or TDR-94D Mode S Transponder System installation with stand-alone Collins RTU-4210 or RTU-4220.		In accordance with Collins Installation Instructions as listed on AML N°. ST01119WI-D, Revision-, or later approved revision.	(1) Approval of this change in type design applies to the above model aircraft only.(2) Compatibility of this design change with previously approved modifications must be determined by the installer.(3) A copy of this Certificate and FAA Approved Model List (AML) N°. ST01119WI-D issued October 29, 2...	26/10/2007	Active	10016212
EASA.IM.A.S.02461	FLYHT AEROSPACE SOLUTIONS Ltd.		TCCA STC SA07-47	BOEING 757-200	AFIRS 220 Automated Flight Information Reporting System Installation with Optional Gobal Voice and Global Text Satellite Communication.		AMS Installation Instructions, 151-0024, Rev. --, 27/03/2007.Instructions for Continued Airworthiness, 153-0030, Rev. --, 01/12/2006.		13/09/2007	Active	10016213
EASA.IM.A.S.02462	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA02-251/D	BOMBARDIER BD-700-1A10	Customized Interior Completion - SN 9084Validation of TCCA STC C-LSA02-251/D issue 2		AFM Supplements G-FM25000029A / BTCCA SoC letters C-03-0390 dated Sep 26 and Oct 04, 2007Time limits and MaintenanceChecks : G-TM05200018	Refer to the Limitations sections of the required AFM Supplemen	05/10/2007	Active	10016214
EASA.IM.A.S.02464	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA8312SW-D	FALCON 50	Installation of the Automatic Cabin Electrical Load Shed System in accordance with Drawing List Report No. F50-01182 Revision A, dated 27th September 1999 or later approved revisions.		• FAA STC No. SA8312SW-D• FAA Approved Airplane Flight Manual Supplement Report No. 36627-1 dated 18th February 1998 or later approved revision is required for the -501 installation.• FAA Approved Airplane Flight Manual SupplementReport No. 36627-2 dated 30th September 1998 or later approv...	1. As per FAA STC No. SA8312SW-D2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any otherpreviously installed modification will introduce no adverseeffect upon the airworthiness of the product. The installati...	19/07/2007	Active	10016216

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02465	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA8299SW-D	FALCON 50	Installation of Auxiliary Battery System in accordance withDrawing List Report No. F50-01173, Revision E dated 19th September 2001or later approved revisions.		• FAA STC No. SA8299SW-D.• FAA Approved Airplane Flight Manual Supplement Report No. 36567-1 dated 3rd June 1997 or later approved revision is required for the -501 installation of the Drawing List.• FAA Approved Airplane Flight Manual Supplement Report No. 36567-2 dated 18th August 2000 or...	1. As per FAA STC No. SA8299SW-D.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installat...	09/07/2007	Active	10016217
EASA.IM.A.S.02466	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA8222SW-D	FALCON 50	Installation of the GWS Satellite Data Communication Systemin accordance with Drawing List Report No. F50-01159, Revision NC, dated 21st July 1993 or later approved revisions.		FAA STC No. SA8222SW-D.	1. As per FAA STC No. SA8222SW-D.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installat...	19/07/2007	Active	10016218
EASA.IM.A.S.02467	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA7300SW-D	FALCON 50	Installation of the Service and Indirect Lighting System inaccordance with Drawing List Report No. F50-01145, RevisionL, dated 25October 2000 or later approved revisions.		FAA STC No. SA7300SW-D.	1. As per FAA STC No. SA7300SW-D.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installat...	17/07/2007	Active	10016219
EASA.IM.A.S.02468	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC ST09316SC-D	FALCON 50	Installation of the Standby Instrument Systemn in accordance with Drawing List Report No. F50-01172, Revision B, dated 12th October2000 or later approved revisions.		• FAA STC No. ST09316SC-D• FAA Approved Airplane Flight Manual Supplement, Report No. 36606, Revision A, dated 4th May 2000 or later approved revision isrequired when -501 or -503 installations are used.	1. FAA STC No. ST09316SC-D2. Limited to Falcon 50EX version aircraft.3. Prior to installation of this modification the installer must determine that the interrelationshipbetween this modification and any other previously installed modification will introduce no adverse effect upon the airw...	19/07/2007	Active	10016220
EASA.IM.A.S.02469	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA7260SW-D	FALCON 50	Installation of the Auxiliary Equipment Rack in accordance with Drawing List Report No. F50-01116, Revision N, dated 2nd June 1993 or later approved revisions.		FAA STC No. SA7260SW-D	1. As per FAA STC No. SA7260SW-D2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any otherpreviously installed modification will introduce no adverseeffect upon the airworthiness of the product. The installati...	19/07/2007	Active	10016221
EASA.IM.A.S.02470	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA7069SW-D	FALCON 50	Installation of the Centralized Water System in accordance with Drawing List Report No. F50-01095-2, Revision A, dated 6th September 1999 or later approved revisions.		• FAA STC No. SA7069SW-D.• Airplane Maintenance Manual Supplement Report 35699 Revision A or later approved revisions is applicable to those aircraft modified i.a.w. with this STC and having the heated belly drain modification installed as per drawing F50-41813.	1. As per FAA STC No. SA7069SW-D.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installat...	19/07/2007	Active	10016222

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02472	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC ST10423SC-D	FALCON 900EX	Installation of the Service and Indirect Lighting System (EMTEQ) in accordance with Data List Report No. F9EX-01048 Revision A dated 07th October 2005 or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF(or i.a.w. subsequent revisions of th...		FAA STC ST10423SC-DMaintenance Manual Supplement, Report 37498 Revision B dated 26th September 2005, or later revisionsapproved by EASA in accordancewith EASA ED Decision 2004/04/CF (or i.a.w. subsequent revisions of this decision).	1. As per FAA STC ST10423SC-D.2. Applicable to Falcon900EX EASy aircraft version.3. F900EX EASy designation does not correspond to a new MF900 model designation but is acommercial designation for airplanes onwhich the specific Dassault modifications as listed on EASA TCDSs EASA.A.062 have...	26/09/2007	Active	10016224
EASA.IM.A.S.02476	FIELD AVIATION COMPANY INC.		TCCA C-LSA07-021/D	BOMBARDIER CL-600-2B19	Installation of Corporate Shuttle Interior.		STC C-LSA07-021/D, Issue 1 dated 16 September 2007.Installation of the corporate shuttle interior must be in accordancewith Transport Canada Civil Aviation (TCCA), approved FieldAviation Company inc. (FACi) Modification instruction 204910, Revision A, dated August 31, 2007, or later TCCA approvedO...	Limited to serial no. 8049	09/10/2007	Active	10016225
EASA.IM.A.S.02478	LEARJET Inc.		FAA STC SA8101NM-D	BOMBARDIER CL-600-2B16 (CL-604	FAA STC SA8101NM-D, NAV Lights RelocationThis STC supersedes LBA TA0136.		Bombardier Aircraft Services MDL No. CA-3017-TUC at Revision F dated 05 June 2002 or later approved revision		31/05/2007	Active	10016226
EASA.IM.A.S.02480	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD		TCCA STC Q-LSA07-029/D	BD-700-1A11	Installation of Photosmart printer and installation of additional handset for in the aft lhs of SN 9204Validation of TCCA Limited STC Q-LSA07-029/D to S/N 9204		Compliance plan: CP27116-001.		21/01/2008	Active	10016228
EASA.IM.A.S.02485	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10314SC-D	GULFSTREAM G500	Installation of a Satcom Antenna.		IFCA:GA34103A000		09/10/2007	Active	10016229
EASA.IM.A.S.02492	HAWKER BEECHCRAFT CORPORATION (HBC)		FAA STC SA0859WI	BEECH 1900D	Installation of EROS MAGIC (Mask and Goggles Integrated Concept) Quick Donning Masks.		Installation in accordance with Raytheon Aircraft Services Master Drawing List 148-100057, Revision A, dated January 27, 2000, or later approved revision.		17/07/2007	Active	10016230
EASA.IM.A.S.02494	HAWKER BEECHCRAFT CORPORATION (HBC)		FAA STC SA0876WI	BEECH 1900D	Installation of an Allied Signal CAS 67A Traffic Alert and Collision Avoidance System (TCAS II)		Raytheon Aircraft Services STC Master Drawing List No.148-100040, Revision C, or later approved revision.Raytheon Aircraft Services Airplane Flight Manual Supplement, Document No.FMS002193UE363, dated April 27, 2000, or later approved revision.		17/07/2007	Active	10016231
EASA.IM.A.S.02496	GULFSTREAM SERVICES CORPORATION		FAA STC ST02848AT-D	GIV, GV	Installation of the Runway Awareness and Advisory System (RAAS) Software for the Honeywell MK V Enhanced Ground Proximity Warning System (EGPWS).Installation of the Runway Awareness and Advisory System (RAAS) Software for the Honeywell MK V Enhanced Ground Proximity Warning System (EGPWS).		Installation in accordance with Gulfstream Index List CE413498050, revision F dated February 21, 2008 or later FAA approved revision.Operation to be in accordance with Gulfstream Flight Manual Supplements CE41349M008, Original Release, dated February 21, 2008, orlater approved revisions for the mod...	1. Applies to models G-IV and GV aircraft equipped with Honeywell EGPWS with version -210-210 or later approved software.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modificati...	19/07/2007	Active	10016232

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02497	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03428AT-D	GULFSTREAM GV-SP	Cabin Interior and Aircraft Completion STC on Aircraft Serial Number 5150.		• Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC51 4915150, Rev. C, dated August 21, 2007or later approved revision.• To be operated in accordance with FAA approved Airplane Flight Manual Supplement ref, GC51501M022, Rev. NC, dated 08/27/07, orlater appro...	1. Aircraft Serial Number 5150 only.2. The following STC's are a required part of this STC: ST02696AT-D, ST02697AT-D and ST03290AT-D. It is the installer's responsibility toensure these STC's are all EASA approved.3. Prior to installation of this modification the installer must determine t...	10/09/2007	Active	10016233
EASA.IM.A.S.02498	GULFSTREAM AEROSPACE CORPORATION		STC ST03414AT-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5153.		Installation in accordance Gulfstream Aerospace CorporationMaster Index List, GC514915153 Rev. B, dated September 4, 2007, or later approved revisions.	Aircraft Serial Number 5153 only.The following STCs are a required part of this STC:- ST02696AT-DST02697AT-DST03290AT-DST02715AT-DST02796AT-Dand ST00892LA.It is the installer responsability to ensure these STCs are all EASA approved.	09/10/2007	Active	10016234
EASA.IM.A.S.02499	DUNCAN AVIATION, INC.		FAA STC ST00858WI	LEARJET 36A LEARJET 36 LEARJET 35A LEARJET 35	Installation of Collins TCAS-94 TCAS II System.		AFM Supplement 40003000, ref	This installation is not to be used in airspace where Elementary Surveillance (ELS) or enhanced surveillance (EHS) is required.	19/12/2007	Active	10016235
EASA.IM.A.S.02500	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST01937LA-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5151.		Install in accordance with Gulfstream Aerospace Report GC5000K477, Rev. N/C and Index List GC520008576 Rev. K, dated 06September 07, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M045, Revision N/C, dated 06 September 07, or laterapprove...	Aircraft Serial Number 5151 only.	09/10/2007	Active	10016236
EASA.IM.A.S.02501	BOMBARDIER AEROSPACE		TCCA C-LSA07-366/D	BD-100-1A10 (CHALLENGER 300)	AIRCRAFT COMPLETION, 10 PASSENGERS INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA07-366/DIssue 1 dated 20th December 2007, in accordance with Aero ConsultingServices Ltd. Modification Data Summary F576000 Revision N/C.		Transport Canada Limited Supplemental Type Certificate C-LSA07-366/D Issue 1, dated 20th December 2007. .TransportCanada Approved Aero Consulting Services Ltd. Modification Data Summary ref. F576000 dated 20th December 2007, RevisionN/C or later Transport Canada approved revision.Transport Ca...	This STC is limited to aircraft Bombardier BD100-1A10 Serial Number 20169.	10/01/2008	Active	10016237
EASA.IM.A.S.02502	BOMBARDIER AEROSPACE		TCCA C-LSA07-320/D	BD-100-1A10 (CHALLENGER 300)	AIRCRAFT COMPLETION, 10 PASSENGERS INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA07-320/DIssue 1 dated 20th November 2007,in accordance with Aero ConsultingServices Ltd. Modification Data Summary F522000 Revision N/C dated19.11.07		¿ Transport Canada Limited Supplemental Type Certificate C-LSA07-320/D Issue 1, dated 20th November 2007. ¿ Transport Canada Approved Aero Consulting Services Ltd. Airplane Flight Manual Supplement F522090 Revision N/C or later Transport Canada approved revision. ¿ Instructions for Contin...	This STC is limited to aircraft Bombardier BD100-1A10 Serial Number 20159.	26/11/2007	Active	10016238

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02512	BUTLER NATIONAL CORPORATION		FAA STC NO. ST00846SE	BOEING 747-300 BOEING 747-200 BOEING 747-100	Installation of Model 840037-108, 840037-112, and 840037-113 transient Suppression Device on Boeing 747-100, 747-200, 747-300 SP and SR series airplanes fitted with Honeywell Analog Fuel quantity Indication System in accordance with ButlerNational Corporation document No. TSD BN 0031, Drawing Packa...		-	This STC is approved only for the product configuration as defined in the approved design data. Compatibility with other aicraft/engine configuraitons shall be determined by the installer.	15/10/2007	Active	10016240
EASA.IM.A.S.02515	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA05-60	BOMBARDIER BD-700-1A11	Customized Interior Completion - SN 9182.Validation of TCCA STC SA05-60.via SoC limited to SN 9182.Configuration acc: CDL E25000 Rev N		AFM Supplements: see TCCA STC SA05-60TCCA SoC letterC-06-0571 dated Oct 12, 2007Time limits and Maintenance Checks : see TCCA STC SA05-60	Refer to the Limitations sections of the required AFM Supplement	24/10/2007	Active	10016242
EASA.IM.A.S.02517	ROCKWELL COLLINS Inc.		FAA STC ST02055LA	AIRBUS A330-203	IFE VMOD upgrade per System List 1310929-001/IFE VMOD Upgrade consists of removing the existing VMOD and re-installing an upgraded VMOD in the Video Control Center (VCC).		FAA STC ST02055LASystem List, Air France A330-203 VMOD Upgrade, ref. 1310929 Rev. A, dated 21.02.2007 or later approved revisionsIndex List, Total Entertainment System A330 Aircraft, ref.1304681, Rev. NEW or later approved revisions		20/11/2007	Active	10016243
EASA.IM.A.S.02518	ROCKWELL COLLINS Inc.		FAA STC ST02056LA	AIRBUS A340-313 AIRBUS A340-311	IFE VMOD upgrade per System List 1310930-001/IFE VMOD Upgrade consists of removing the existing VMOD and re-installing an upgraded VMOD in the Video Control Center (VCC).		FAA STC ST02056LA-System List, Air France A340-311/313 – VMOD Upgrade, ref. 1310930-001 Rev. B, dated 21.02.2007 or later approved revisions-Index List, Total Entertainment System – A340 Aircraft, ref.1304684, Rev. – or later approved revisions	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	04/10/2007	Active	10016244
EASA.IM.A.S.02520	GULFSTREAM AEROSPACE CORPORATION			GULFSTREAM GIV-X	Aircraft Serial No 4092 completion and cabin interior installation.		Installation in accordance with Gulfstream Aerospace Corporation Index List No. GC422046119, Revision B, Dated November16, 2007, or later approved revisions.Operation to be in accordance with Gulfstream Flight Manual Supplement GC42204M033, Original release, dated November 20, 2007, or later approv...	GIV-X Serial No. 4092 Only.	10/01/2008	Active	10016245
EASA.IM.A.S.02524	HAWKER BEECHCRAFT SERVICES		FAA STC ST02619AT	BEECH 400A BEECH 400	Installation of a Battery Low Voltage Warning / Shutoff System on Raytheon Aircraft 400 and 400A.		Master Drawing Lisst MDL RAF01106A, dated 10 June 2002 or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		28/08/2007	Active	10016247
EASA.IM.A.S.02525	HAWKER BEECHCRAFT SERVICES		FAA STC SA03292AT	BEECH 390	Modification to install an Auxiliary Gound Heating System.		RAS Master Data List: RAS110500103, Rev B, dated 21 June 2006 or later FAA approved Revision.FAA approved RAS AFM-S Doc. RAS110500111, dated 29 August 2005, or later approved Revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification to third persons i...	18/10/2007	Active	10016248

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02526	ROCKWELL COLLINS, Inc.		FAA STC ST00040WI-D	AIRBUS A320-232 AIRBUS A320-231 AIRBUS A320-212 AIRBUS A320-211 AIRBUS A320-111	Installation of Collins Traffic Alert and Collision Avoidance System (TCAS II).		FAA STC ST00040WI-DCollins Drawing Index, ref. Doc 992-1979-001, Rev. N. Dated 01.10.2007*Collins Airplane Flight Manual Supplement (AFMS), ref. Doc. ACC-02-009, Rev. A, dated 01.12.03*Collins Maintenance Manual Supplement (MMS) ref. Doc ACC-98-013, Rev. A. Dated 30.08.98.** or later revisions of th...	Installation of a Collins TPR-720, TPR 900 or TPR-901 Mode S Transponder is a prerequisite to this modification.	15/10/2007	Active	10016249
EASA.IM.A.S.02527	HAWKER BEECHCRAFT SERVICES		FAA STC NUMBER ST01441WI	HAWKER 800 XP HAWKER 800	Hawker Beechcraft Corporation Installation of upper and lower LED beacons, wingtip LED navigation lights and wingtip strobe lights.		installation as defined in Hawker Beechcraft Master Data List RAS050600152 rev 3.0, dated May 11,2007, or later approved revisions.Instructions for Continued Airworthiness as defined in: - Hawker Beechcraft (ICA) document ref. RAS050600161, latest approved revision.		10/10/2007	Active	10016250
EASA.IM.A.S.02528	BOMBARDIER INC.		TCCA STC C-LSA08-012/D	BOMBARDIER BD-100-1A10 (CHALLE	AIRCRAFT COMPLETION, 10 PASSENGERS INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA08-012/DIssue 1 dated 11th January 2008,in accordance with Aero ConsultingServices Ltd. Modification Data Summary F579000.		¿ Transport Canada Limited Supplemental Type CertificateC-LSA0-012/D Issue 1, dated 11th January 2008. .¿ Transport Canada Approved Aero Consulting Services Ltd. Modification Data Summary ref. F579000 dated 22nd January 2008, Revision A or later Transport Canada approved revision.¿ Tr...	1. This STC is limited to aircraft Bombardier BD100-1A10Serial Number 20172;2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the...	25/01/2008	Active	10016251
EASA.IM.A.S.02529	ELLIOTT AVIATION		FAA STC SA02447CH	BEECH 300C BEECH 300 BEECH 200T BEECH 200CT BEECH 200C BEECH 200	Installation of a Rockwell Collins IFIS-5000 Integrated Flight Information system.		Installation must be in accordance with Elliott Aviation Master Data List No. MDL-2707-000 Rev. A, dated 26.June.07 or later Approved Revisions.Operation must be in accordance with Elliott Aviation Flight Manual Supplement FMS-2707-00 Rev.IR dated 09.July.07 or later approved revision.Maintenance m...		27/02/2008	Active	10016252
EASA.IM.A.S.02531	UNIVERSAL AVIONICS SYSTEMSCORPORATION	REV. 2	FAA STC ST02070 LA	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Universal Avionics UNS-1Fw with embedded WAAS. MDL -4 Config (TripleUNS-1Fw FMS with P/N 10709 3 GPS-WAAS/Sirius Antenna)	EASA.IM.A.023	-EASA STC No. EASA.IM.A.S.02531-FAA STC No. ST02070LA-Universal Avionics MDL No. MDL-2007-1003 Revision 11 dated 11 January2009 or later approved revision-Universal Avionics AFM Supplement No. AFMS-2007-1005 Revision 00 dated31 January 2008 or later approved revision	None	06/07/2009	Active	10016253

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02532	ELLIOTT AVIATION		FAA STC ST02431CH	FALCON 10	EASA Validation of FAA STC ST02431CHEASA Validation is limited to Provisions for Installation of a Universal Avionics Application Server Unit (ASU) on Falcon 10		Installation in accordance with:• Elliott Aviation Master Data List, Report No. MDL-2710-000 Revision A, dated 15th may 2007, and with• Elliott Aviation drawing No. 300-2710-E0455-001 Rev. IR dated 06th May 2008 for the deactivation of the ASU System and for theprovisions for installation.Spec...	The aircraft must be equipped with Universal Avionics EFI-890R Electronic Flight Instrument System (EFIS) as installed by Elliott Aviation's STC EASA.IM.A.S.01713.This EASA Approval is limited to provisions for installation only with the ASU System deactivated. A placard indicating the ASU System is...	13/05/2008	Active	10016254
EASA.IM.A.S.02533	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST01780SE	B747-400	Installation of interior components in accordance with Heath Tecna Inc. Drawing List HPD-DL-105		Heath Tecna Inc. Drawing List HPD-DL-105, Revision B, datedJuly 25, 2007FAA STC ST01780SEor later revisions of the above listed documents approved by EASA in accordance with ED Decision 2004/04/CF (or subsequent revions of this decision).	Modification of the aircraft per Boeing Service Bulletin 747-00-2004, conversion from passenger to freighter configuration must be performed concurrently with this STC.	29/08/2007	Active	10016255
EASA.IM.A.S.02534	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST008700SE	B737-330	Installation of galley supports structure and jumper wire provisions in accordance with Health Tecna Drawing List HPD-DL-76, Revision B, dated 16, January 2004 or later approved revision.		Health Tecna Drawing List HPD-DL-76, Revision B, dated 16,January 2001 or later approved revision.Weight & Balance Supplement WR-1027 SW, dated May 16, 2001 or later approved revision.	Approval of this change in type design applies to the abovemodel aircraft only. This approval should not be extended to aircraft on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously appr...	24/10/2007	Active	10016256
EASA.IM.A.S.02535	AS&T AEROSPACE SYSTEM & TECHNOLOGIEIN C		FAA SA01328WI	2.PA-32R-301T (TURBO SARATOGA) 2. PA-32R-301 (SARATOGA SP) 1. PA-32-301XTC (PIPER 6XT) 1. PA-32-301FT (PIPER 6X)	Installation of TKS Ice Protection Systems Components on no-hazard / no credit basis.		Installation must be in accordance with AS&T Master DrawingList No. 12700DL, Revision 3, dated March 7, 2005 or later approved revision.Operation must be in accordance with Supplemental Airplane Flight Manual and FAA approved Airplane Flight Manual Supplement, Doc. No. 12700-FMS, dated 13-May-2005...	1. This installation is not approved for flight into known icing conditions.2. A placard must be fitted on the upper control panel in front of the pilot, stating "FLIGHT INTO KNOWN ICING CONDITIONS IS PROHIBITED".3. This installation is approved on a no-hazard / no credit basis.	27/08/2007	Active	10016257
EASA.IM.A.S.02537	NEW FLIGHT COOPERATION		FAA STC SA4954NM	CITATION 550-0001 TO -0800	Gross Weight Increases based on Banson Aircraft Corp. STC.LBA STC Nr. 2048, 05 June1996;Spanish STC No. S325-I, 06 Febr. 2003.		New Flight Corporation Drawing List Doc. 90A890, Rev. A or later approved revision;AFM Supplements FMS-972 and (metric) 2BRA;Maintenance Manual Supplements MMS-921 (S/N's 0001-0626) MMA-923 (S/N's 0627-0800)		19/11/2007	Active	10016258
EASA.IM.A.S.02538	BOMBARDIER COMPLETION CENTRE INC	REV. 1	TCCA SA04-113 ISSUE 1 (CDL REV	BD-700-1A10	Cabin Interior Door Modifications - ASN 9167.	EASA.IM.A.009	EASA STC No. EASA.IM.A.S.02538 dated 18 October 2007.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.TCCA SoC ref. C-09-0419 dated 18 June 2009.Aero Consulting Services Ltd Configuration Definition List No. 0954000Revision CX ,: dated 01 May 2009.Bombardier Airplane Flight Manual Supplement G-FM...	Restricted to ASN 9167.	20/12/2007	Active	10016259

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02540	JET AVIATION ST. LOUIS, Inc.		FAA STC ST4837WI-T	BOMBARDIER CL-600-2B16	Installation of an Audio International Articulated MountingArm and Data Connectivity for an Electronic Flight Bag		FAA STC No. ST02544CH-D dated 07 March 2008.Midcoast Aviation, Inc. Master Data List 41-343G001 Revision C, dated March07, 2008, or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsT...	03/10/2008	Active	10016261
EASA.IM.A.S.02541	HOLLINGSEAD INTERNATIONAL		FAA STC ST00404LA-D	BOEING 737-400	Installation of Smoke Detection and Fire Suppression Systems Provisions, Lower Cargo Compartments.		Drawing No 90437 (-506&-507) Rev N/C dated 03/23/99, and MDL 12111 Rev. G, dated 15 may 2002Drawing No. 90437 (-508&-509) Rev. A dated 10/15/99, and MDL 12111 Rev. D, dated 05/02/00FAA approved Aircraft Flight Manual Supplement 20673 Rev.B dated 02/28/00Or later approved revisions of the above lis...		14/01/2008	Active	10016262
EASA.IM.A.S.02544	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10317SC-D	GULFSTREAM G150	Installation of a Collins IFIS 5000 EFB System.		AFMS: GA31120M000 or GA31120M001IFCA: GA31120A000		10/10/2007	Active	10016264
EASA.IM.A.S.02545	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10321SC-D	GULFSTREAM G150	Installation of a WX-1000 Stormscope		AFMS: GA31225M000IFCA: GA31225A000		09/10/2007	Active	10016265
EASA.IM.A.S.02547	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10327SC-D	GULFSTREAM G150	Installation of a Collins DBU 5000 System.		AFMS: GA31320M000IFCA: GA31320A000		09/10/2007	Active	10016266
EASA.IM.A.S.02548	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10324SC-D	GULFSTREAM G150	Installation of a second ADF.		AFMS: GA31214M000IFCA: GA31214A000		05/12/2007	Active	10016267
EASA.IM.A.S.02549	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10326SC-D	GULFSTREAM G150	Installation of a Honeywell FDR.		AFMS: GA31420M000IFCA: GA31420A000		09/10/2007	Active	10016268
EASA.IM.A.S.02552	HAWKER BEECHCRAFT SERVICES		FAA STC ST03405AT	BEECH 400A BEECH 400	Replacement of a Standby Altimeter installation in the Raytheon (Beech) models 400, 400A aircraft.This STC is a duplicate of STC ST03379AT, EASA.IM.A.S.02353		Installation in accordance with Master Data List (MDL), RAS1106DL004, Revision 1, dated January 4, 2007 or later approved revision.		04/09/2007	Active	10016269
EASA.IM.A.S.02554	B/E AEROSPACE LIMITED		TCCA C-LSA07-190/D ISSUE 2	767-300	Upgrade to Honeywell Mark V EGPWS.		Aero Consulting Services Modification Data Summary F379000,rev B.Flight Manual Supplement, F379091, rev N/ C.Instructions for Continued Airworthiness, F379071, rev N/C.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	02/11/2007	Active	10016270
EASA.IM.A.S.02555	COLUMBIA AVIONICS INC.		FAA STC ST01149WI	CESSNA S550 CESSNA 560 CESSNA 550 CESSNA 500	Installation of IS&S or J2 (Kollsman) Air Data Systemwith Reduced Vertical Separation Minimum (RVSM)		Master Doc. List 30140946 of May 10, 2005 and either one of30140961,IS&S Air Data Flight Manual Supplement -500/S550 of03/12/200330140986,IS&S Air Data Flight Manual Supplement –550/560 of 03/12/200330141197,IS&S Air Data Flight Manual Sup. for KFC-325 of 03/27/200330141660,J2 Air Data Flight Manua...		27/08/2007	Active	10016271

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02557	COLUMBIA AVIONICS INC.		FAA STC ST01252WI	CESSNA S550 CESSNA 560	Vertical Separation Minimum (RVSM) group airworthiness approval of Cessna Modell S550 and 560 Citation Aircraft		Master Doc. List 30141243, Rev. 3 of June 4, 2003Instructions for initial and continued airworthiness, Doc. 30141246, Rev. A of April 23, 2004,or later FAA approved revisions to these two documents.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	27/08/2007	Active	10016272
EASA.IM.A.S.02558	ROCKWELL COLLINS, Inc.d/b/a AIR TRANSPORT SYSTEMS		FAA ST00392AT	BOEING 767-300 SERIES BOEING 767-200 SERIES	Installation of Collins Duel TPR-720 Mode S Transponders.		Collins Master Drawing List, MDL-93-38, rev. F, 22/03/2000.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	02/11/2007	Active	10016273
EASA.IM.A.S.02560	CORPORATION LOGIC AIR Inc.	REV 1	TC STC C-LSA07-205/D ISSUE 2	BOEING 767-300	Installation of In-Flight Entertainment System.		1. Aero Consulting Services Modification Data Summary F371000, rev A. 2. Instruction for Continued Airworthiness:-F371071, rev NC for S/N 27957 and 26263;-F371072, rev NC for S/N 27135 and 37136.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	10/04/2008	Active	10016274
EASA.IM.A.S.02562	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01470LA-D	737-800, 737-900 737-600, 737-700	Installation of Rockwell Collins WXR-2100 Multi-scan (TM) Weather RadarSystem(Revision to the existing STC EASA.IM.A.S.02562 to change the STC holdername and to add more models and correct the equipment reference name)	i.a.w. TCDS	Hollingsead International Inc. Master Data List No 2736-01,Revision A,dated 28-03-04, or later approved revision.	None.	08/07/2008	Active	10016275
EASA.IM.A.S.02565	AIRCRAFT SYSTEMS AND MANUFACTURING,INC		FAA STC ST10268SC	DC-8-71/-71F/-72/-73/-73F DC-8-61/-61F/-62/-62F/-63/-63F	FAA STC ST10268SC "installation of Universal Avionics Terrain Awareness Warning Ststem (TAWS)".		Aircraft Systems & Manufacturing Top drawing List 5643-0001-00A dated 20 July 2004.AFM Supplement No. 5643-2160-00 Rev.IR dated 22 July 2004.	1. TGL 12 complied with.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of th...	10/10/2007	Active	10016276
EASA.IM.A.S.02566	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		Q-LSA07-035/D	BD-700-1A11	Miscellaneous Cabin Modifications on SN 9188Validation of TCCA Limited STC Q-LSA07-035/D to S/N 9188MDL: MDL27124002Compliance Plan: CP27124-001 Rev. A		IFCA: TL27124-004Soc: NIA5012-07-0128, dated August 28, 2008		12/10/2007	Active	10016277
EASA.IM.A.S.02567	S-TEC CORPORATION		FAA STC SA09251AC-D	PIPER PA-28-236 PIPER PA-28-181 PIPER PA-28-161	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model ST-703-20/30.		FAA approved S-TEC Bulletin No. 803, Revision 0, dated 23-Jun-1997, or later approved revisionFAA approved Master Drawing List No. 921009,Revision 0, dated 23-Jun-1997, or later approved revisionFAA / DAS approved Pilot's Operating Handbook and / or Airplane Flight Manual Supplement, P/N 891438, dat...	This STC is also eligible on: - PA-28-151 when modified per STC SA2969SW (180 HP Engine Conversion)If airplane is modified per the above mentioned STC, installer must check availability of EASA-approval.	22/10/2007	Active	10016278
EASA.IM.A.S.02568	UNIVERSAL AVIONICS SYSTEMSCORPORATION		FAA STC ST01763CH-D	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of Universal Avionics EFI-890R Flat Panel Displays and MFD-640.		Universal Avionics Master Drawing List MDL-2007-1001 Revision 00 dated 20 April 2007.Duncan Aviation Airplane Flight Manual Supplement No. 040510022 Revision B dated 20 January 2006?		23/11/2007	Active	10016279

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02572	DELTA ENGINEERING CORPORATION		FAA STC ST02393NY-D	BOEING 747-400	Installation of Heath Tecna Cabin Interior		Master data list 0107-06068-2152, Rev A, and instructions for Continued Airworthiness 0707-06050-2152, Rev A, or later approved revisions.	1. TGL 12 complied with.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of th...	09/10/2007	Active	10016280
EASA.IM.A.S.02574	HAWKER BEECHCRAFT SERVICES	REV. 1	FAA STC ST01369AT	BEECH 300	Installation of a 70% Ground Idle Stop Dropout System.Installs cams and switches on the existing aircraft's power leversystem to allow the propeller system to transition from Ground Idle to Flight Idle when both Power levers are advances above 70 %. This allows the propellers to attain the propero...		Installation in accordance with Raytheon Aircraft Services Master Drawing List Number MDL-TAF96106, Original Revision, dated February 12, 1997, or later FAA approved revision.Operation in accordance with Raytheon Aircraft Services AircraftFlight Manual Supplement, dated May 29, 1997.Maintenance inn...		19/10/2007	Active	10016281
EASA.IM.A.S.02577	GULFSTREAM SERVICES CORPORATION		FAA STC ST03476AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4093.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC14914093 Rev. D, dated November 26, 2007, or laterapproved revisions.	Aircraft Serial Number 4093 only.The following STCs are a required part of this STC:ST03027AT-DST03047AT-DST02980AT-DST02979AT-DST02987AT-DST03290AT-D	18/12/2007	Active	10016282
EASA.IM.A.S.02578	CORPORATION LOGIC AIR Inc.		TCCA SA07-210/D ISSUE 1	BOEING 767-300	Installation of 270 Pax Interior Configuration.		Aero Consulting Services Modification Data Summary F276000,rev N.Instruction for Continued Airworthiness, F276071, revNC.		02/11/2007	Active	10016283
EASA.IM.A.S.02579	CORPORATION LOGIC AIR Inc.	REV 1	TCCA STC SA07-12 ISSUE 2	BOEING 767	Tire pressure Indication System De-activation, Boeing 767-300.		1. Aero Consulting Services Modification Data Summary E909000, rev. A; 2. Instructions for Continued Airworthinesscontained in Maintenance Manual Supplement E909071, rev. C.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	07/08/2008	Active	10016284
EASA.IM.A.S.02580	CORPORATION LOGIC AIR Inc.		TCCA STC C-LSA07-091/D	BOEING 767-300	installation of Mode S ATC Transponder with Elementary and Enhanced Surveillance Modes.		Aero Consulting Services Modification Data Summary F278000,rev N/C.Flight Manual Supplement F278092, rev N/C.Instructions for Continued Airworthiness Supplement E278071, rev N/C		02/11/2007	Active	10016285
EASA.IM.A.S.02581	ROCKY MOUNTAIN AIRCRAFT	REV. 1	TCCA STC SA02-119; EASA STC.IM	VIKING AIR LIMITED (DCH) DHC-6	Dual or Single Garmin GNS530 or GNS430 installation.		Installation in accordance with Field Aviation Company inc.Modification Instruction 181811, original Issue or later approved revision for single GNS-430 or GNS-530 Installation; 181813, original Issue or later approved revision for singleGNS-430W or GNS-530W Installation; 181810, Rev. B or later a...	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	21/11/2008	Active	10016286

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02582	ROCKWELL COLLINS, Inc.	REV. 1	FAA STC ST01927LA	BOEING 757-300 BOEING 757-200	Installation of ARINC Characteristics 718A for Mode S Transponder Activation of Elementary and Enhanced Surveillance Capabilities.		• Hollingsead International Master Data List 2894-01, Revision NC, 10th October 2006.• AFM Supplement 2894-AFM, Revision Original, 24th October 2006.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	15/10/2007	Active	10016287
EASA.IM.A.S.02583	LIFEPORT, LLC		FAA STC SA02060LA	BEECH 1900D	Emergency Medical System		FAA approved Master Drawing List, Doc. No. MDL-822-00, Rev.E, dated 09-Jul-2007, or later approved revisionFAA approved Airplane Flight Manual Supplement, Doc. No. EGR-822-11, Rev. A, dated 31-Jul-2007, or later approved revisionInstructions for Continued Airworthiness, Doc. No. EGR-822-12, Rev. A,...	The installer of this STC must ensure that, if the life vests have been removed with the seats, a life vest for the occupant of thelitter system is installed and available to the occupant.	04/10/2007	Active	10016288
EASA.IM.A.S.02584	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST0194LA-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5162.		Install in accordance with Gulfstream Aerospace Report GC52000K511, Rev. N/C and Index List GC520008584, Rev. G, dated 11/30/07,Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M056, revision N/C, dated 11/30/07,	Aircraft Serial Number 5162 only.	18/12/2007	Active	10016289
EASA.IM.A.S.02585	CORPORATION LOGIC AIR Inc.		C-LSA03-498/ D	BOEING 767-300	Changes to Altitude Callout Configuration, Honeywell Mark VEGPWS.		Aero Consulting Services Modification Data Summary D799000,rev B.Instructions for Continued Airworthiness Supplement D799071, rev N/C.		02/11/2007	Active	10016290
EASA.IM.A.S.02586	PETERSEN AVIATION, INC.		FAA STC SA2660CE	PA-28-180, PA-28-181 PA-28-160, PA-28-161,	Operation of Piper airplanes with automotive gasoline in accordance with FAA STC SA2660CE, dated April 29, 2005.		• Airplane Flight Manual Supplement No.2, Revision B, dated July 25, 2007.• Drawing List 28-TL-2, Rev. (F), datedApril 22, 1991.• Drawing List 28-TL-3, Rev. (X), dated July 25, 2007.	1. Limitations as established in FAA STC SA2660CE, datedApril 29, 2005 are applicable.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effec...	10/09/2007	Active	10016291
EASA.IM.A.S.02589	BOMBARDIER INC.		TCCA STC SA06-84	BOMBARDIER BD-100-1A10 (CHALLE	Improved Hinge Design, Toilet Seat and Lid / Modification of existing toilet seat installation which allows both toiletseat and lid to remain in the up position without falling.EASA Validation of Transport Canada Supplemental Type Certificate SA06-84, Issue 1 dated 3rd November 2006 in accordance w...		-Transport Canada Supplemental Type Certificate SA06-84 Issue 1, dated 3rd November 2006.-Aero Consulting Modification Data Summary, ref. No. F062000 Revision A, dated 02.08.2007.	-Decrane Aircraft Service Bulletin "Bombardier C300 Lavatory Seat Lid/Hinge Assembly", ref. SB06008, Revision G, dated23rd July 2007.	05/11/2007	Active	10016293
EASA.IM.A.S.02591	NORTHEAST ENGINEERING & DEVELOPMENTL TD.		TCCA LSTC NO. O-LSA05-321/D IS	PILATUS PC-12/45	Installation of GNS 430 (COMM/NAV/ GPS), GNS 530 (COM/NAV/GPS), KDR 510 (Data link Weather Receiver), KGS SS50 (Static Inverter), XMRadio Receiver with XM Radio Display & Control Head (Cabin), and necessary antennas.		Installation of GNS 430 (COMM/NAV/GPS), GNS 530 (COM/NAV/GPS), KDR 510 (Data link Weather Receiver), KGS SS50 (Static Inverter), XMRadio Receiver with XM Radio Display & Control Head (Cabin), and necessary antennas.Transport Canada approved Master Drawing List, Doc. 053701, Issue 2, dated 14 AugustT...	This STC is limited to Pilatus PC-12/45, Serial number 659Prior to the installation of this modification the installer must determine that the interrelationship between this modification and any over previously installed modifications willintroduce no adverse effect upon the airworthiness of the pr...	16/10/2007	Active	10016294

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02593	S.I.P. TECHNICAL SERVICES	REV. 1	FAA STC ST09367SC	DC-9-83 DC-9-82 DC-9-81 (MD-81)	Installation of dual Canadian Marconi CMA 900 FMS with GPS sensor (This is a revision of the STC ST09367SC already validated by ENAC on 2 December 1997 and amended on 5 May 1998 to implement the PRNAV capability.)		Airplane Flight Manual Supplement No. 3209-FM-001.Rev. C dated 20 april 2007.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	20/12/2007	Active	10016296
EASA.IM.A.S.02594	S.I.P. TECHNICAL SERVICES		FAA STC ST09389SC	DC-9-83 DC-9-82	Installation of Single Canadian Marconi CMA 900 FMS with GPS Sensor.		1. AFM Supplement No. 3218-FM-001 dated 13 December 1997;2. Master Drawing List No. 3218-DL-001-501 Rev. B.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/03/2008	Active	10016297
EASA.IM.A.S.02595	ARC AVIONICS Corp.		FAA ST03458AT	737-300, 737-400, 737-500	Installation upgrade to replace the existing system with either Honeywell or Collins Dual Enhanced Mode S Transponder system. The existing Omni directional antenna is compatible with the new system and will not be replaced. The two Honeywell TRA-67A or Collins TPR901 transponders will utilize the ex...		- ARC Avionics Master Data List 750-030806, rev H, dated march 30, 2007 or later EASA approved revision in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this Decision).- AFM Document, ARC Avionics Document 730-030806, for Boeing 737-300, -400, -500 series aircraft, dated 2...	- AFM Document, ARC Avionics Document 730-030806, for Boeing 737-300, -400, -500 series aircraft, dated 2 July 2007, orlater EASA approved revision.	10/01/2008	Active	10016298
EASA.IM.A.S.02596	FIELD AVIATION COMPANY INC.		TCCA STC C-LSA07-322/D	BOMBARDIER CL-600-2B19	Installation of Life Rafts.		Field Aviation Company Inc. (FACI) Modification Instructions 213610, Revision -original issue-, dated September 7, 2007or later approved revision.TCCA LSTC No. C-LSA07-322/D	Aircraft Serial No. 8049 only	12/10/2007	Active	10016299
EASA.IM.A.S.02597	HOLLINGSEAD INTERNATIONAL		FAA STC ST02147LA	BOEING 777-200 SERIES	Installation of B/E Aerospace air Chiller P/N 470-1		FAA Letter 150L-08-184 dated June 17, 2008.	Applicable only to A/C with C&D Zodiac pantry installation P/N C801001-101 and C801001-103 covered by FAA STC ST02144LAand EASA STC P-EASA.A.S.02421.	18/06/2008	Active	10016300
EASA.IM.A.S.02598	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA08-019/D	BOMBARDIER BD-700-1A11	Customized interior Completion - ACSN 9257		1. Transport Canada STC No. C-LSA08-019/D Issue 1 dated February 22 2008. Transport Canada Statement of Compliance C-07-0907 dated 12 March 2008;2. Aero Consulting Services Modification Data Summary F528000 Revision N/C;3. Airplane Flight Manual Supplement G-FM25000167 Revision NC;4. Ins...	1. Restricted to ASN 9257;2. WLAN System in only compatible to IEEE802.11(b);3. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect uponi...	20/03/2008	Active	10016301
EASA.IM.A.S.02599	BOMBARDIER COMPLETION CENTRE INC		TCCA LIMITED STC C-LSA07-284/D	BOMBARDIER BD-700-1A10	Customized Interior Completion - ACSN 9235		TCCA STC C-LSA07-284/D, Issue 1, dated 30-11-2007.TCCA SOC letter C-07-0765, dated 7-12-2007.Aero Consulting Services Modification Data Summary F460000 Revision N/C dated 30-11-2007.Bombardier Airplane Flight Manual Supplement G-FM25000165, Revision N/C.Instructions for Continued Airworthiness GC923...	Refer to the limitations section of the required AFM Supplement and to the referenced FCOMS.WLAN system is compatible only to IEEE 802.11 (B).	21/12/2007	Active	10016302

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02600	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA07-286/D FOR CAB	BOMBARDIER BD-700-1A10	Customised Interior Completion -ACSN 9238.		TCCA SOC letter C-07-0767 dated 17 January 2008.Aero Consulting Services Modification Data Summary F462000 Revisoin N/ Cdated 10 December 2007.Bombardier Airplane Flight Manual Supplement G-FM25000164 Revision N/C.Instructions for Continued Airworthiness GC92380000-IFCA.	Restricted to ASN 9238 and Refer to the limitations sections of the required AFM supplement and to the referenced FCOMS.WLAN System is compatible only to IEEE 802.11(b).	21/01/2008	Active	10016303
EASA.IM.A.S.02602	BOMBARDIER COMPLETION CENTRE INC		TCCA STC (SA05-60) FOR CABIN	BOMBARDIER BD-700-1A11	Customised Interior Completion - ACSN 9241		TCCA SOC letter C-08-365 dated 30 April 2008.Aero Consulting Services Configuration Definition List E025000 Revision AKdated 29 November 2007.Bombardier Airplane Flight Manual Supplement G-FM25004051 Revision N/C or later approved revision.Instruction for continued Airworthiness GC92410000-IFCA.	Restricted to ASN 9241 and1. Refer to the Limitations sections of the required AFM Supplement.	07/05/2008	Active	10016305
EASA.IM.A.S.02603	BOMBARDIER COMPLETION CENTRE INC		TCCA LIMITED STC C-LSA07-278/ D	BOMBARDIER BD-700-1A11	Customized Interior Completion - ACSN 9243.		TCCA STC C-LSA07-278/ D, Issue 1, dated 05-12-2007.TCCA SOC letter C-07-0704 dated 7-12-2007.Aero Consulting Services Modification Data Summary F4570000 Revision N/C dated 06-12-2007.Bombardier Airplane Flight Manual Supplement G-FM25000162, Revision N/ C.Instructions for Continued Airworthiness GC924...	Refer to the limitations section of the required AFM Supplement and to the referenced FCOMS.WLAN system is compatible only to IEEE 802.11 (B).	21/12/2007	Active	10016306
EASA.IM.A.S.02604	JAMCO AMERICA, INC.		FAA STC ST01459SE	BOEING 767-300	Oxygen Module Installation.		JAMCO Master Drawing List IA-122MDL, Revision C, 31/08/2004.	Reconfiguration of Passenger seats as per FAA STC SA7032NM-D must be installed concurrently. This FAA STC must be approved by EASAdirectly or by Grandfather Rights before installation on a EASA member state aircraft.	10/01/2008	Active	10016307
EASA.IM.A.S.02610	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10312SC-D	G150	Installation of a VHF COM Antenna.		IFCA: GA34300A000.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.The installation of this modification by third persons is s...	22/11/2007	Active	10016308
EASA.IM.A.S.02611	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10315SC-D	GULFSTREAM G150	Installation of a 3rd VHF COM with Data link.		IFCA: GA31300A000AFMS: GA31300M000	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	22/11/2007	Active	10016309
EASA.IM.A.S.02612	ELISEN TECHNOLOGIES		TRANSPORT CANADA STC NO. SA07-	BOMBARDIER CL-600-2B19	Lockable Fuels Caps.		Elipsen Technologies Inc. Master Data List MDL-29R2-70C revision NC dated 18 April 2007.		21/11/2007	Active	10016310

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02614	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA 03-113	BOMBARDIER CL-600-2B16 (604)	Installation, complete Custom Interior		Transports Canada STC SA 03-113 Issue 1 dated December 19 2003 Aero Consulting Services Ltd. Configuration Definition List D817000 Revision AI.Aero Consulting Services Ltd AFM SupplementD817090 Revision A or later approved revision.	Restricted to ASN 5623.	02/11/2007	Active	10016311
EASA.IM.A.S.02617	L-3 COMMUNICATIONS INTEGRATEDSYSTEM L.P. WACO OPERATION		FAA STC ST09101AC-D	BOEING 737-700 IGW	Modification of aircraft environmental control system.		Raytheon Systems Company "Type Design Data List" Report no. 98010304-000.	Raytheon Systems Company "Type Design Data List" Report no.98010304-000.	11/02/2008	Active	10016313
EASA.IM.A.S.02618	L-3 COMMUNICATIONS INTEGRATEDSYSTEM L.P. WACO OPERATION		FAA STC ST09102AC-D	BOEING 737-700 IGW	Installation of passenger gaseous oxygen equipment.		Raytheon Systems Company 'Type Design Data List' Report no. 98010204-000/	Raytheon Systems Company "Type Design Data List" Report no.98010204-000.	11/02/2008	Active	10016314
EASA.IM.A.S.02620	CONCORDE BATTERY CORPORATION		FAA STC NO. ST01173WI	LEARJET 45	Installation of Concorde RG-443 Lead Acid Battery.		None		05/02/2008	Active	10016315
EASA.IM.A.S.02623	S-TEC CORPORATION	REV. 1	FAA STC SA09001AC-D	CESSNA T310R CESSNA T310Q CESSNA T310P CESSNA 310R CESSNA 310Q CESSNA 310P CESSNA 310N CESSNA 310L CESSNA 310K CESSNA 310J CESSNA 310I	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-594, also when modified per FAASTC as listed in 3.5 (Limitations and Conditions).		FAA approved Bulletin No. 694, Revision 4, dated 11-May-2001, or later approved revisionFAA approved Master Drawing List No. 92794, Revision D, dated 11-May-2001, or later approved revision (28 Volt System)FAA/DAS Approved Supplemental Flight Manual, P/N 891178, Revision 1, dated 11-May-2001, or lat...	This STC is also eligible on variants 310K, 310L, and 310N when modified per STC SA412SO (300 H.P. Colemill Conversion).This STC is also eligible on variants T310P, and T310Q when modified per STC SA2750SW (RAM Modification.Installer must check availability of EASA-approval for one or more menti...	22/11/2007	Active	10016317
EASA.IM.A.S.02629	COLUMBIA AVIONICS INC.	REV. 1	FAA STC ST01162WI	CESSNA 551 CESSNA 550 CESSNA 501 CESSNA 500	Vertical Separation Minimum (RVSM) group airworthiness approval of Cessna Models 500, 501, 550 and 551 Citation Aircraft		¿ FAA STC ST01162WI ¿ Master Document List 30140986, revision 11 ¿ Airplane Flight Manual Supplements30141699, revision N/C (Model 500, 501, 551)30141700, revision 1 (Model550) 30141701, revision 1 (Model 550)30141702, revision 1 (Model 500) ¿ Instructions for Initial and Continued Airworth...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	19/03/2009	Active	10016320
EASA.IM.A.S.02630	COLUMBIA AVIONICS INC.		FAA STC ST01084WI	HS125 SERIES 700A/B HS125 SE. 403B, F400B, -F403B HS125 SE.400B/1, -401B, -403AC HS125 600B/2, -600B/3, -F600B HS125 600A, -600B, -600B/1 DH125 SE.400A, HS125 SE. 400B BH125 SE. 400A/600A	Installation of Collins TCAS-4000 TCAS II System (with or without optional Avidyne Flight Max 800 MFD.		Installation in accordance with Columbia Avionics, Inc. Master Document List No. 30140855, Revision 2, dated May 31, 2002; or laterapproved revisions.Operation in accordance with FAA approved Manual Supplement 30140871, dated June 7, 2002 or later Approved Revisions.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.	03/06/2008	Active	10016321
EASA.IM.A.S.02631	GULFSTREAM SERVICES CORPORATION		FAA STC ST03533AT-D	GULFSTREAM GV-SP	Installation of AirCell Axxess II Iridium Satellite Telephone.		Installation in accordance with Gulfstream Aerospace Corporation Index List GC512038002, Rev. C, dated 2 April 2008, orlater FAA approved revision.	Aircraft Serial 5180 and subsequent.	26/05/2008	Active	10016322

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02632	GULFSTREAM SERVICES CORPORATION		FAA STC ST03522AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4104.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC414914104 Rev. C, dated February 27, 2008, or later approved revisions in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).	1. Aircraft Serial number 4104 only;2. The following STCs are a required part of this STC:- ST03027AT-D- ST03047AT-D- ST02980AT-D- ST02979AT-D- ST02987AT-D- ST03290AT-D- ST03238AT-D3. It is the installers responsibility to ensure these STCs are all EASA approved;4. P...	26/03/2008	Active	10016323
EASA.IM.A.S.02633	GULFSTREAM SERVICES CORPORATION		FAA STC ST03532AT-D	GULFSTREAM GIV-X	Installation of AirCell Axxess II Iridium Satellite Telephone.		Install in accordance with Gulfstream Aerospace CorporationIndex List, GC412038004 Rev C, dated April 14, 2008, or later approved revisions.		05/05/2008	Active	10016324
EASA.IM.A.S.02634	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02519CH-D	GULFSTREAM GV-SP	Aircraft Serial No 5176 completion and cabin interior installation		Installation in accordance with Gulfstream Aerospace Corporation Index List No. GC52 2046083, Revision A, dated March 24, 2008, or later approved revisions.Operation to be in accordance with Gulfstream Flight Manual Supplement GC52 204M027, Original release, dated March 24, 2008, or later approved r...	GV-SP Serial No. 5176 Only	13/05/2008	Active	10016325
EASA.IM.A.S.02635	THE BOEING COMPANY - WICHITA DIVISION		FAA STC SA2123CE-D AMENDED 19	BOEING 747-2B5B	Conversion of Passenger Airplane to dedicated Special Freighter with Main Deck Side Cargo Door in accordance with Boeing Drawing List document D3-8857, Section V, Appendix 31, Rev.CN		D6-13703.3B5 Airplane Flight Manual SupplementD6-30680-34 B747-200 Cargo Loading Manual	This approval is limited to ariplane model B747-200B S/N 22482 and S/N 22485.Boeing Commercial Airplane Groupe - Wichita Dvision, Airplane Flight Manual Supplement dated 9 September 1991 or revision for AFM D6-13703.3B5 or later approved revisions of this document approved by EASA in accordance with...	28/01/2008	Active	10016326
EASA.IM.A.S.02636	ROYAL ATLANTIC AVIATION, INC.		FAA STC SA02636AT	CESSNA 441 SERIES	Ground Recognition Strobe Light System		Installation iaw. Master Drawing List MDL RAA-MDL-1, Rev. A, or later FAA approved Revisions and RAA-INST-1, Rev. B, orlater approved RevisionsTo be maintained iaw. Document No RAA-ICA-1, Rev. IR, or later approved Revisions	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	22/09/2008	Active	10016327
EASA.IM.A.S.02637	B&B PARTNERS		FAA ST03483AT	SEE EASA APPROVED MODEL LIST	Installation of a portable beverage dispensing system,P/N B43-FA 001		- FAA STC ST03483AT dated 24 September 2007- B&b Partners Assembly Drawing B43-FA, dated 21 December 2006- Master Document List No. 6009, dated 14 August 2007- Instructions for Continued Airworthiness for P/N B43-FA-001, Rev. Adated 9 August 2007- Drawing No. 1178 on “Galley Interfac...	1. This STC is applicable to the aircraft types as listed in the Approved Model List for FAA STC ST03483AT2. ThisSTC is to be installed in accordance with the Galley Interface Criteria defined in Drawing No. 1178.3. The limitations as defined in FAA STC ST03483AT are applicable	06/02/2008	Active	10016328
EASA.IM.A.S.02638	DELTA ENGINEERING CORPORATION		FAA STC ST02630NY	BOEING 777-200	Heath Tecnica Interior		FAA STC ST02630NYDelta Engineering Master Data List 0143-06294-2159 Revision A dated November 25, 2008 or later approved revisions	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	15/12/2008	Active	10016329

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02639	BOMBARDIER COMPLETION CENTRE INC		TCCA 0-LSA01-007 ISSUE 6	BOMBARDIER BD-700-1A10	Interior and Avionics Installation.		TCCA SoC 5010-0-07-0746 dated 13 May 2008Deca Aviation Engineering Ltd MDL No. MDL9004, Revision E, dated 10 Aprii 20021. The following DECA Aviation Engineering Ltd Fiight Manual Supplements! are required:A. interior and Avionics I n sial lai ions, FMS000041-1, Rev. A, dated April 10,2001.B.R...	1. Limited to AS N90042. Compliance with Bombardier Aerospace Airworthiness Limitations GC-90045000-AWL, dated July 15, 2002, is mandatory.3. Occupancy• Maximum numberof passengers Twelve (12)• Maximum number of occupants including flight crew Sixteen (16)4. The Public AddressJ...	22/05/2008	Active	10016330
EASA.IM.A.S.02640	S.I.P. TECHNICAL SERVICES		FAA STC NO. ST9949SC	BOEING DC-9-83 (MD-83) BOEING DC-9-82 (MD-82) BOEING DC-9-81 (MD-81)	Installation of required sensor and interface for existing DFDR and FDAU to meet FAR 121.344.		Master Data List 3273-DL-001-501 Rev. D dated December 5, 2002		10/06/2008	Active	10016331
EASA.IM.A.S.02642	BOMBARDIER INC.		TCCA STC NO. SA04-112 ISSUE 3.	BOMBARDIER BD-100-1A10 (CHALLE	AIRCRAFT COMPLETION, 10 PASSENGERS INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA07-411/DIssue 1 dated 5th December 2007, in accordance with Aero ConsultingServices Ltd. ModificationData Summary F637000 Revision N/C dated05.12.2007		¿ Transport Canada Limited Supplemental Type Certificate C-LSA07-411/ D Issue 1, dated 5th December 2007. ¿ Transport Canada Approved Aero Consulting Services Ltd. Modification Data Summary F637000, Revision N/C or later Transport Canada approved revision. ¿ Transport Canada Approved Aeroo...	This STC is limited to aircraft Bombardier BD100-1A10 Serial Number 20141.	18/12/2007	Active	10016333
EASA.IM.A.S.02643	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST09823SC-D	GULFSTREAM 200	Installation of Dual UNS 1C + upgraded FMS i.a.w. Index List CEB11188001		1. AFMS CEB1118M0012. IFCA CEB1118A001	1. For A/C S/N004 through 051 only.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The install...	18/12/2007	Active	10016334
EASA.IM.A.S.02644	THOMMEN AIRCRAFT EQUIPMENT AG		FAA STC ST10685SC	LEARJET 60	Installation of Revue Thommen 3A43 Standby Altimeter.		As noted in MDL3460003, rev A.		12/03/2008	Active	10016335
EASA.IM.A.S.02645	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10329SC-D	GULFSTREAM 200	Installation of a forward RH Galley with a convertible highTemp Oven/Microwave Oven Configuration.		Installation of FWD right hand Galley with a convertible high Tep Oven/ Microwave oven configuration in accordance with Index list GA223288002,Instruction for continued Airworthiness GA22328A001, dated 19.07.2007.	A prerequisite to the convertible Oven confirguration is the installation of the Galley Multiple STC ST10304SC-D; installation limited to Gulfstream G200, S/N 163 only.	17/04/2008	Active	10016336
EASA.IM.A.S.02646	THOMMEN AIRCRAFT EQUIPMENT AG		FAA STC ST10684SC	LEARJET 45	Installation of Revue Thommen 3A43 Standby Altimeter.		As noted in MDL3445002, rev A (or later approved revisions).		12/03/2008	Active	10016337
EASA.IM.A.S.02647	SIMMONDS PRECISION PRODUCTS, Inc		FAA STC ST00092BO	AIRBUS A300	In-Tank Fuel Quantity Indicating System (FAA STC ST00092BO validation). This STC installs, within the aircraft fuel tanks, a new FQIS sensors and the associated wire harnesses.		Master Drawing List, ref : T3012-MDL-0101 Revision D, dated20 March 2007.(or any later EASA approved revision)Instruction for Continued Airworthiness, ref : T3012-0005-0101 Revision A, dated 07 February 2007.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	02/10/2008	Active	10016338

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02649	SIERRA INDUSTRIES Ltd.		FAA STC SA80RM	CESSNA 550	Installation of Extended Range Fuel Tank and relocation of Aft Pressure Bulkhead.		MDL 91800 – Master Drawing and Data List,Document FMS-912 – Airplane Flight Manual Supplement for Citation 550Document MMS-911 – Maintenance Manual Supplement for Citation 550Document WB-9122 – Weight and Balance Data for Citation 550	Cessna Service Bulletin 34-15 or 34-23 (ref. Note 7 in TCDSA22CE, latest rev.) must be incorporated unless modified aircraft with full cabin tank fuel, minimum crew and required ballast is within maximum zero fuel weight and C.G. limits.	11/06/2008	Active	10016339
EASA.IM.A.S.02650	SIERRA INDUSTRIES Ltd.		FAA STC SA174RM	CESSNA 550	Installation of an extended width cabin door.		Master Doc. List MDL 91500,Report 151-1 “Cessna Citation Extended Door Structural Analysis”, Rev. A dated 2-25-88		03/07/2008	Active	10016340
EASA.IM.A.S.02654	AERODYME CORPORATION		FAA STC SA00246BO	114, 114A	Installation of Lycoming IO-540-T4B5 engine.		FAA approved Aerodyme IO-540 engine Supersedure Installation Instructions, Doc. No. AD725-01, dated 02 November 2006 orlater approved version.FAA approved Aerodyme IO-540 Engine Supersedure Instructions for Continued Airworthiness, Doc. No. AD726-01, dated 02 November 2006or later approved version....		27/11/2007	Active	10016341
EASA.IM.A.S.02656	DECA AVIATION ENGINEERING Ltd.d/b/a PAL AEROSPACE	REV. 1	TCCA SA00-98 ISSUE 4	BD-700-1A10	Baggage Door Locking System Modification.		Transport Canada STC SA00-98 Issue 4, dated 3 October 2007.Transport Canada Statement of Compliance reference 5010-O-07-0698, dated 8 May 2008.DECA Aviation Modification Summary No. MS0009938, Section 1, Issue B, dated 24 November 2000 or later approved revisions.		23/04/2008	Active	10016342
EASA.IM.A.S.02659	FLYHT AEROSPACE SOLUTIONS Ltd.		TCCA STC SA07-7	BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-100 SERIES	Aeromechanical Services AFIRS (Automated Flight InformationReporting System) 220 installation with optional Global Voice and Global Text Satellite Communication.		AMS Master Document List, 121-0036, Rev. A. 1. November 2007AMS Installation Instructions, 151-0023, Rev. B, 1 December2006AMS Instructions for Continued Airworthiness, 153-0031,Rev. A. 1. December 2006		21/01/2008	Active	10016343
EASA.IM.A.S.02660	FLYHT AEROSPACE SOLUTIONS Ltd.	REV. 2	TCCA STC SA07-8	BOEING 737-800 SERIES BOEING 737-700 SERIES BOEING 737-600 SERIES BOEING 737-500 SERIES BOEING 737-400 SERIES BOEING 737-300 SERIES BOEING 737-200 SERIES	AFIRS 220 Automated Flight Information Reporting System installation with Optional Global Voice and Global Text Satellite Communication.		AFMS, Wiring Diagram Manual or later revisions of this document approved by EASA in accordance with EASA ED Decision 2004102ICF (orsubsequent revisions of this decision).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	22/05/2008	Active	10016344
EASA.IM.A.S.02662	CHIPPEWA AEROSPACE, Inc.		FAA STC ST2685AT	SAAB SF340A SAAB 340B	Installation of FA2100CVF Cockpit Voice Recorder in Saab 340 series.		FAA STC ST02685AT	N/A	22/02/2008	Active	10016345
EASA.IM.A.S.02663	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10313SC-D	G150	Installation of an XM Antenna.		ICA GA34607A00	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	05/02/2008	Active	10016346

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02671	B&C SPECIALITY PRODUCTS		FAA SA00846WI	T210L, T210M, T210N 210L, 210M, 210N, P210N	Addition of Vacuum Pump drive alternator and regulator withassociated controls.			Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	28/11/2007	Active	10016351
EASA.IM.A.S.02672	HAWKER BEECHCRAFT SERVICES		FAA STC SA01414WI	HAWKER BEECHCRAFT G58 (BARON)	Modification to install a Honeywell KR 87 Automatic Direction Finder (ADF) System and the Honeywell KA-44B Antenna interfaced with the previously installed Garmin 1000 Avionics System.		Hawker Beechcraft Services:• Master Drawing List No. RAS050600064 Revision 1.0 dated 11 Oct. 2006 or later FAA approved revisions• Airplane Flight Manual Supplement RAS050600079 dated 6 Oct. 2006 or later FAA approved revision.	None	27/05/2009	Active	10016352
EASA.IM.A.S.02673	HAWKER BEECHCRAFT SERVICES		FAA STC SA01455WI	HAWKER BEECHCRAFT G36 (BONANZA	Modification to install a Honeywell KR 87 Automatic Direction Finder (ADF) System and the Honeywell KA-44B Antenna interfaced with the previously installed Garmin 1000 Avionics System.		Hawker Beechcraft Services:• Master Drawing List No. 002-3450-L01-00 Revision 1.0 dated 26 Sept. 2007 or later FAA approved revisions• Airplane Flight Manual Supplement 002-3450-A01-00 dated 15 Oct. 2007 or later FAA approved revision.	None	27/05/2009	Active	10016353
EASA.IM.A.S.02675	MICRO AERODYNAMICS, INC.		FAA STC SA00941SE	CESSNA T210N CESSNA T210M CESSNA T210L CESSNA T210K CESSNA T210J, T210H CESSNA T210G CESSNA P210N CESSNA 210G,H,J,K,L,M,N,	Installation of vortex generators on the wing and tail surfaces.		Installation must be in accordance with Drawing Package MA2156 Rev. IR dated 18-April-2001 and Instalation Manual MA2157 Rev. IR dated 03-July-2001, or later Approved Revisions.Maintenance must be in accordance with Micro AeroDynamics, IncInstruction for Continued Airworthiness related to the FAA S...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	27/02/2008	Active	10016354
EASA.IM.A.S.02676	BOMBARDIER COMPLETION CENTRE INC		TCCA O-LSA07-261/D ISSUE 1 07/	BOMBARDIER BD-700-1A10	Cabine Floor Structure Modification & Decompression Panel Relocation.		TCCA Statement of compliance reference 5010-O-07-0790 dated24 April 2008.DECA Aviation Modification Summary MS07159 Revision 1 dated 18 September 2007 or later approved revision.Instruction for Continued Airworthiness ICA07159 Revision 1 dated 22 October 2007 or later approved revision.		05/05/2008	Active	10016355
EASA.IM.A.S.02678	LEARJET Inc.		FAA SA8191NM-D	BOMBARDIER CL-600-2B16 (604)	Installation of a Safe Flight Enhanced Autopower System.		Learjet Inc. MDL No. DC22305001 at revision U, dated 26 April 2007*Learjet Inc. AFMS No. BA563040125 at revision NC, dated 26 April 2007* required for -3 configuration.*or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent rev...	The -3 configuration requires the installation of FAA STC SA8191NM-D -2 configuration.	21/08/2007	Active	10016356

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02679	CASCADE AEROSPACE Inc.		TCCA STC SA 08-08 ISSUE 1, MAR	BOMBARDIER DHC-8-400 SERIES	Forward Baggage Compartment Installation.		Engineering Order EO 4049, Rev, IR, dated 14 February 2008Master Document List MDL 4049, Rev IR, dated 14 February 2008Maintenance Manual Supplement MMS 4049 Rev. IR, dated 14, February 2008Maintenance Requirements Manual Supplement MRMS 4049, Rev. IR, dated February 14, 2008		12/03/2008	Active	10016357
EASA.IM.A.S.02680	CASCADE AEROSPACE Inc.		TCCA STC SA08-9, ISSUE 1, 4 FE	BOMBARDIER DHC-8-400 SERIES	G4 Galley Installation.		Engineering Order EO 4050, Rev IR, dated January 23, 2008Master Document List MDL 4050, Rev IR, dated January 2, 2008Maintenance Manual Supplement MMS 4050, Rev IR, dated January 23, 2008Maintenance Requirements Manual Supplement MRMS 4050, Rev IR, dated January 23, 2008,		08/02/2008	Active	10016358
EASA.IM.A.S.02681	CASCADE AEROSPACE Inc.		TCCA STC SA08-10, ISSUE 1, 4 F	BOMBARDIER DHC-8-400 SERIES	Right AFT Draft Bulkhead InstallationTCCA STC Number: SA08-10, Issue 1, 04 February 2008		Engineering Order EO 4051, Rev IR, dated January 23, 2008.Master document list MDL 4051 Rev IR, dated January 23, 2008Maintenance Manual Supplement MMS 4051, Rev IR, dated January23, 2008Maintenance Requirements Manual Supplement MRMS 4051, Rev IR dated Juanuary 23, 2008		08/02/2008	Active	10016359
EASA.IM.A.S.02682	CASCADE AEROSPACE Inc.		TCCA STC SA 08-11 ISSUE 1 4 FE	BOMBARDIER DHC-8-400 SERIES	72 Passenger Seat Reconfiguration		Engineering Order EO 4052, Rev IR, dated January 23, 2008.Master Document List MDL 4052 Rev IR, dated January 23, 2008Maintenance Requirements Manual Supplement MRMS 4052, Rev IR,dated January 23, 2008.		08/02/2008	Active	10016360
EASA.IM.A.S.02683	CASCADE AEROSPACE Inc.		TCCA STC SA 08-12 ISSUE 1 4 FE	BOMBARDIER DHC-8-400 SERIES	G3 Galley Modification.		Engineering Order EO 4053, Rev IR, dated January 23, 2008.Master Document List MDL 4053, Rev IR, dated January 23, 2008Maintenance Manual Supplement MMS 4053, Rev IR Dated January23, 2008Maintenance requirements Manual Supplement MRMS 4053, Rev IR dated January 23, 2008.		08/02/2008	Active	10016361

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02684	BOMBARDIER AEROSPACE		TCCA C-LSA08-014/D	BD-100-1A10	AIRCRAFT COMPLETION, 10 PASSENGERS INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA08-014/DIssue 1 dated 20th February 2008, in accordance with Aero ConsultingServices Ltd. Modification Data Summary F586000 Revision N/C.		¿ Transport Canada Limited Supplemental Type CertificateC-LSA08-014/D Issue 1, dated 20th February 2008. . ¿Transport Canada Approved Aero Consulting Services Ltd. Modification Data Summary ref. F586000 dated 20th February 2008, Revision N/C or later Transport Canada approved revision. ¿,...	This STC is limited to aircraft Bombardier BD100-1A10 Serial Number 20179.	25/02/2008	Active	10016362
EASA.IM.A.S.02685	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA ST02501CH	AIRBUS B4-605R A300 B4-603	Activation of Honeywell Runway Awareness and Advisory System (RAAS) (Validation of the FAA STC n° ST02501CH)This STC consists in activating the RAAS function on EGPWS		Master Data List, ref : DC104-5029-00 Revision B, dated 08 November 2007. (or any later approved revision of this document).Certification Review Item F-01, issue IR, dated 18 February 2008Aircraft Flight Manual Supplement, ref : DC303-5029-00, dated 16 November 2007Instruction for Continued Airworth...	This STC is only applicable on Honeywell EGPWS P/N identified through the 'Associated Technical Documentation' fitted with the Hardware/Software configuration up to ref : 226/226	13/05/2008	Active	10016363
EASA.IM.A.S.02686	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10319SC-D	G150	Installation of Laserref V IRS.		ICA Ga31313A000AFMS GA31313M000	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	25/03/2008	Active	10016364
EASA.IM.A.S.02687	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10320SC-D	G150	Installation of 115 cubic foot oxygen cylinder in accordance with Index list GA327088000, Rev B, dated 15.09.2006 or later revisions of the above listed documents approved by EASAin accordance with EASA ED Decision 2007/04/CF (or subsequent revisions of this decision).		Instruction for Continued Airworthiness for Installation ofA 115 cubic Foot Long range Oxygen Cylinder.Weight and Balance Statement G150-Instl of Long Range Oxygen Tank.		07/04/2008	Active	10016365
EASA.IM.A.S.02688	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC ST02122LA	A320 SERIES	Installation of Aerocon Engineering Company (AEC) On-Board Airstair		¿ FAA STC ST02122LA, issued 4th March 2008 ¿ Aerocon Engineering Co. Master Drawing List, ref. Document No. AC25-A320-1200, Rev. A, dated 21.12.07 or later revisions approvedby EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).¿ Aerocon Engineeri...		14/03/2008	Active	10016366
EASA.IM.A.S.02689	HAWKER BEECHCRAFT CORPORATION (HBC)		FAA STC SA01798SE	BEECH 300C BEECH 300 BEECH 200CT BEECH 200C BEECH 200	Reduced Vertical Separation Minimum Qualification Document Group Aircraft Classification Hawker Beechcraft Models B200/B200C/B200GT/B200CGT/ B300/ B300C (Super King Air)		Aero-Mech AMI-AFMS-KAIR-0719 Airplane Flight Manual Supplement for Hawker Beechcraft Models B200/B200C/B200GT/ B200CGTAero-Mech AMI-AFMS-KAIR-0722 Airplane Flight Manual Supplement for Hawker Beechcraft Models B300/B300C		18/04/2008	Active	10016367

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02691	GULFSTREAM SERVICES CORPORATION		FAA STC ST03531AT-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5178.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514915178, Rev. D, dated 1 May 2008, or later approved revisions.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsA...	26/05/2008	Active	10016368
EASA.IM.A.S.02692	GULFSTREAM SERVICES CORPORATION		FAA STC ST03523AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4103.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC414914103 Rev F, dated March 31, 2008,or later approved revisions.	Aircraft Serial Number 4103 only.The following STCs are a required part of this STC:ST03027AT-D,ST02987AT-D,ST03047AT-D,ST02980AT-D,ST03290AT-Dand ST02979AT-D.It is the installersresponsibility to ensure these STCs are all EASA approved.	05/05/2008	Active	10016369
EASA.IM.A.S.02693	GULFSTREAM SERVICES CORPORATION		FAA STC ST03524AT-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5174.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514915174, Rev. E, dated 19 March 2008 or later approved revision.To be operated in accordancewith FAA approved Airplane Flight Manual Supplement, ref. GC51501M025, Rev. NC, dated 18 March 2008, or later approved r...	Aircraft Serial Number 5174 only.The following STCs are a required part of this STC:ST02697AT-D, ST-03290-AT-D, ST02696AT-D.It is the installers responsibility to ensure that these STCs are all EASA approved.	07/04/2008	Active	10016370
EASA.IM.A.S.02694	GULFSTREAM SERVICES CORPORATION		FAA STC ST03525AT-D	GULFSTREAM GV-SP	Airplane Completion STC on Aricraft Serial Number 5167.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List CG514915167, Rev C, dated January 7,2008	Aircraft Serial Number 5167 only.The following STC's are a required part of this STC: ST02696AT-D	21/01/2008	Active	10016371
EASA.IM.A.S.02695	GULFSTREAM SERVICES CORPORATION		FAA STC ST03526AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4099.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC414914099 Rev E, dated December 18, 2007, or laterapproved revisions.	Aircraft Serial Number 4099 only.The following STCs are a required part of this STC:-ST03027AT-DST03047AT-DST02980AT-DST02979AT-DST02987AT-DST03290AT-D.It is the installers responsibility to ensure these STCs are all EASA approved.	10/01/2008	Active	10016372
EASA.IM.A.S.02696	GULFSTREAM SERVICES CORPORATION		FAA STC ST03479AT-D	GULFSTREAM GV-SP	Airplane Completion STC on Aircraft Serial Number 5166.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514915166, Rev. C, dated January 10, 2008 or later approved revisions.To be operated in accordance with FAA approved Airplane Flight Manual Supplement, ref GC51501M024, Rev NC dated 01/11/2008, or later approved rev...	Aircraft Serial Number 5166 only.The following STC's are a required part of this STC:ST02696AT-D,ST02697AT-D,ST03290AT-D.It is the installers responsibility to ensure these STC's are all EASA approved.	24/01/2008	Active	10016373
EASA.IM.A.S.02697	GULFSTREAM AEROSPACE CORPORATION		FAA STC NO. ST01945LA-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5172.		Install in accordance with Gulfstream Aerospace Report GC52000K524 Rev. N/C and Index List GC520008597 Rev. J, dated 3 March 2008, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M069 Revision N/C, dated 3 March 2008.	Aircraft Serial Number 5172 only.	17/03/2008	Active	10016374

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02698	UNIVERSAL AVIONICS SYSTEMSCORPORATION		FAA STC ST01640LA	BOMBARDIER CL-600-2B16 (601-3A	Installation of Universal Avionoics Radio Control Units (RCU)		Universal Avionics Master Document List, Drawing No. MDL-2004-1003, Revision "A", dated May 25, 2004 or later approved revision. Universal Avionics Airplane Flight Manual Supplement Document No. AFMS-2004-1003, Revision IR, dated June 2004, or later approved revision.	Restricted to ASN 5042.	03/06/2008	Active	10016375
EASA.IM.A.S.02699	B/E AEROSPACE LIMITED	REV. 1	TCCA LSTC C-LSA07-342/D	BD-700-1A11	Installation, Side Facing Divan, S/N 9229 Configuration.		Transport Canada Statement of Compliance C-07-0946 dated 22January 2008. Transport Canada LSTC No. LS707-342/D Issue 1dated 06 December 2007.Aero Consulting Services Ltd. Modification Data Summary No. F545000 Revision N/C or later approved revision.Aero Consulting Services Ltd. Airplane Flight Man...	Restricted to ASN 9229.	05/03/2008	Active	10016376
EASA.IM.A.S.02701	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA04-113	BOMBARDIER BD-700-1A10	Customized interior Completion - ACSN 9254.		TCCA SOC Letter C-08-0342 dated 06 May 2008;Aero ConsultingServices Configuration Deviation List D954000 Revision BK dated 11 April 2008.Bombardier Airplane Flight Manual Supplement G-FM25004001 Revision N/C.Instruction for Continued Airworthiness GC92540000-IFCA.	Restricted to ASN 9254 and1. Refer to limitations sections of the required AFM Supplement and to the reference FCOMS.WLAN system is compatible only to IEEE 802.11 (b).	08/05/2008	Active	10016377
EASA.IM.A.S.02702	ROCKWELL COLLINS, Inc.		FAA STC ST01454WI-D	BOMBARDIER CL-600-2D24 BOMBARDIER CL-600-2D15 BOMBARDIER CL-600-2C10 BOMBARDIER CL-600-2B19	Modification of a Collins Control Display Unit, Installation, Type CDU-4100		FAA Statement of Compliance ref. L115W-08-522 dated 21 July2008FAA STC No. ST01454WI-D dated 25 September 2007RockwellCollins Drawing Index No. RCA-0113-001, Rev.-, dated July 31, 2007, or later approved revision.	1. Prior installation and approval of a Collins Control Display Unit, type CDU-4100, is a prerequisite to this STC.2. Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification andany other previously installed modification will intro...	28/07/2008	Active	10016378
EASA.IM.A.S.02704	BASIC AIRCRAFT PRODUCTS, INC.		FAA ST00702AT	210	Installation of Basic Type mBAE-14/28 Model 2025 DeployableAir Driven Alternator System		Basic Aircraft Products, inc. Installation Kit No. 45-2025-OPL, Rev. A, dated 26-09-1994 and Installation Manual No. 80-2025-101, dated 24-06-1994 or later approved revisions.	This approval should not be extended to other aircraft of this moel on which other previously approved modifcations will produce noadverse effect upon the airworthiness of that aircrat. EASA approved Supplemental Airplane Flight Manual or EASA approved Airplane Flight Manual Supplement, dated 28-03-...	18/01/2008	Active	10016380
EASA.IM.A.S.02706	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA01-156	BOMBARDIER BD-700-1A10	Multi-Function Ladder Installation.		Transport Canada Statement of Compliance ref. NAI 5012-01-0610Transport Canada STC No. SA01-156 Issue 1 dated 10 December 2001Elisen Technologies Inc. Master Data List No. MDL-02GX-117 Revision A dated 20 December 2001 or later approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	16/07/2008	Active	10016382

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02707	GULFSTREAM AEROSPACE CORPORATION		ST02084LA-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5175.		Install in accordance with Gulfstream Aerospace Report GC52000K534. Rev. N/C and Index List GC520008599, Rev. J, datedApril 18,2008, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M071 Revision Original, dated April 18, 2008, or later ap...	Aircraft Serial Number 5175 only.	13/05/2008	Active	10016383
EASA.IM.A.S.02708	GOODRICH LIGHTING SYSTEMS GmbH		FAA STC ST02050LA	2. DC-10-15/-40/-40F, MD-10 1. MD-11/-11F 1. DC-10-10/-30/-30F	Anticollision Recognition Lighting System (ARLS) in accordance with, Master Drawing List, Issue No. R-366-00 dated 5 December 2007 or later EASA-approved revision.		Data package containing the following documents, and additional supporting data:1. FAA ST02050LA2. FAA Letter dated 27th April 20073. Project Specific Certification Plan R-366 Project no. ST11125LA-Td.d. 12 May 20064. Master Drawing List R-366-00 d.d. 5 December 20075. E/O Installatio...	. This STC is approved only for the product configuration as defined in the approved design data. Compatibility with other aircraft/engine configurations shall be determinedby the installer.	24/04/2008	Active	10016384
EASA.IM.A.S.02711	FLYHT AEROSPACE SOLUTIONS Ltd.		TCCA STC SA07-84	BOMBARDIER CL-600-2B19 (SERIES	AFIRS 220 Automated Flight Information Reporting System installation with Optional Global Voice and Global Text Satellite Communication		TCCA Statement of Compliance ref. C-07-0944 dated 02 July 2008AMS Master Document List, Ref. 121-0032 Rev.- dated 29 June 2007 or later approved revisionAMS Installation Instructions, Ref. 151-0027 Rev.- dated 27 March 2007 or later approved revision	AMS Instructions for Continued Airworthiness, Ref. 153-0036Rev. A or later approved revision. Compliance with the approved Airworthiness Limitations contained therein is mandatory.	03/07/2008	Active	10016385
EASA.IM.A.S.02714	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC SA01527CH	PILATUS PC-12/47 PILATUS PC-12/45 PILATUS PC-12	Installation of a Honeywell KMH 880 Multi-Hazard Awareness System or a Honeywell KTA 870 Traffic Advisory System.		FAA approved Electronic Cable Specialists Master Data List PC-12, PC-12/45, PC-12/47, Installation of IHAS, ECS-200836,Revision L,dated August 29, 2006, or later FAA approved revision.FAA approved Airplane Flight Manual Supplement as listed in Appendix A of Electronic Cable Specialist Master Data/...	Limitations as per Master Data List PC-12, PC-12/45, PC-12/47, Installation of IHAS, ECS-200836 Revision L, dated August 29, 2006, or later FAA approved revision, Part III. Limitations	10/03/2008	Active	10016386
EASA.IM.A.S.02716	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST01479CH	BOEING 737-300-900 SERIES	Installation of a Smiths Industries Flight Management System Data Bus Portable Computing Device Recorder.		Master Data List, Doc. No. ECS-200447, Revision K dated June 26, 2007Airplane Flight Manual Supplement Doc. No. ECS-200675, Revision B, approved October 5, 2007 is required on board for MDL configuration 1, 2, and 3Airplane Flight Manual Supplement Doc. No. ECS-205138, Revision N/C, approved October...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	17/07/2008	Active	10016388

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02718	SIERRACIN/ SYLMAR CORPORATION		FAA STC ST01840NY	BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-100 SERIES	Installation of Sierracin/Sylmar Windshield Assembly P/N 802600-11/-12, Ref.: FAA STC ST01840NY.		Installation must be performed iaw Aero Cponsulting Services Ltd. Modification Data Summary D641000, Revision N/C, dated 4 November2003*Instructions for Continued Airworthiness/ Maintenance to be performed iaw with Component Maintenance Manual 56-10-12, Rev. A, dated3 September 2003**) or later revi...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	14/08/2008	Active	10016389
EASA.IM.A.S.02719	SIERRACIN/ SYLMAR CORPORATION	REV. 1	FAA STC ST01839NY	BOMBARDIER DHC-8-400 SERIES BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-100 SERIES	Installation of Sierracin/Sylmar Windshield Assembly P/N 802600-09/-10, Ref. FAA STC ST01839NY		Installation must be performed iaw Aero Consulting ServicesLtd. Modification Data Summary D626000, Revision N/C, dated27 October 2003*Instructions for Continued Airworthiness/ Maintenance to be performed iaw with Component Maintenance Manual 56-10-12, Rev. A, dated3 September 2003**) or later revi...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	15/08/2008	Active	10016390
EASA.IM.A.S.02720	GULFSTREAM SERVICES CORPORATION		FAA STC ST03530AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4106.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC414914106 Rev. E, dated 26 March 2008,or later approved revisions.	Applicable to Aircraft Serial Number 4106 only.The following STCs are required as part of this STC: FAA STC ST03027AT-D, ST03047AT-D, ST02980AT-D, ST02979AT-D, ST02987AT-D, ST03290AT-D, ST03238AT-D.	07/04/2008	Active	10016391
EASA.IM.A.S.02721	DUNCAN AVIATION, INC.		FAA STC ST00914WI-D	LOCKHEED 1011-385-1	Installation of Dual IS&S Air Data/ Altimeter System along with two inch standby pneumatic altimeter (FAA STC ST00914WI-D).		Master Document List 10055000, Rev. PSupplement to AircraftFlight Manual (AFM) DOC. 40008200, Rev. D.Supplement to AFM(S/N 5086 only) Doc 050822006, Rev. 0.Instructions for Continuous Airworthiness Doc 44505300, Rev. A.	approval may be extended to aircraft models Lockheed 1329-23, previously modified iaw FAA STC SA2326SW, when this STC has been EASAvalidated.Lockheed 1329-25 Group Approval for RVSM requirements can be shown in conjunction with FAA STC ST01082SE (AeroMech Incorporated).Prior to installation of this...	26/05/2008	Active	10016392
EASA.IM.A.S.02722	DUNCAN AVIATION, Inc.		FAA STC ST01059WI	LOCKHEED 1011-385-1	Installation of Honeywell MK VII Enhanced Ground Proximity Warning System (EGPWS). FAA STC ST01059WI.		Master Document List 10057500, Rev. C.Supplement to Aircraft Flight Manual (AFM) Doc. 40018500, Rev. A.Instructions forContinuous Airworthiness Doc. 44509200.	This Design Approval may be extended to Airplanes Model Lockheed 13-29-23, previously modified iaw FAA STC SA2326SW, when validatedby EASA.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed m...	13/10/2008	Active	10016393
EASA.IM.A.S.02724	ROCKWELL COLLINS, Inc.		FAA STC ST01452WI-D	G200, G150, HAWKER 800XP BD-100-1A10, CL-600-2B16	Modification of Collins FMS-5000 or FMS 6000 and installation in Part 25 Airplanes i.a.w. Drawing index as listed in AML Nr. ST01452WI-D Rev- pr mater approved revisions approved by EASA i.a.w. EASA ED decision 2004/04/CF (or subsequent revision of this decision).		Approved model List No. ST01452WI-DInstallation instructions RCA-2447.	A prior installation and approval of a Collins FMS type FMS-5000 or FMS 6000 is a prerequisite to this STC. Refer to Collins Installation Instructions RCA-2447 in its latest revision for approved FMC substitues.	25/03/2008	Active	10016395

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02725	ROCKWELL COLLINS, Inc.		FAA STC ST00643WI-D	BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-200B	Modification of Collins 618M-3A VHF COMM R/T System Installation to Collins VHF-900B VHF COMM R/T System.		Data package containing the following documents, and additional supporting data: 1. Collins Drawing Index 992-4304-001 2. FAA STC ST00643WI-D 3. Rockwell-Collins document R98047: STC Certification Plan for Collins VHF-900B 8.33 kHz VHF Communications Receiver/ transmitter for Boeing 747-200B and -300...	This STC is approved only for the product configuration as defined in the approved design data. Compatibility with other aircraft/engine configurations shall be determined by the installer.	20/03/2008	Active	10016396
EASA.IM.A.S.02727	ROCKWELL COLLINS, Inc.		FAA STC SA01453WI-D	PIAGGIO P 180 CESSNA 525B CESSNA 525A CESSNA 525 BEECH B300C BEECH B300 BEECH B200 BEECH 390 BEECH 300	Modification of a Collins Flight Management System type FMS-3000 Installed in Part 23 Aircraft.		Installation in accordance with Collins Drawing Index as listed in AML No EASA.IM.A.S.02727 at latest approved revision.Operation in accordance with Collins Flight Manual Supplement as listed in AML No EASA.IM.A.S.02727 at latest approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product. (1) Prior installation and approval of ae...	06/11/2008	Active	10016398
EASA.IM.A.S.02728	PLANE POWER, LTD.		FAA STC SA10682SC	SEE EASA APPROVED MODEL LIST	Replacement of generator and mechanical voltage regulator with alternator and electronic voltage regulator		FAA approved Master Drawing List, Doc. No. 14-0000, Rev. B,dated 31-Jul-2007, or later approved revisionFAA approved Airplane Flight Manual Supplement, Doc. No. AFMS 001, Original Release, dated 25-Jul-2007, or later approved revision forConversion Kit SAL12-70 and SAL12-70CFAA approved Airplane F...	The approval holder shall fulfil the obligations of Part 21, Paragraph 21.A109	13/05/2008	Active	10016399
EASA.IM.A.S.02730	LEARJET Inc.		FAA ST00163BO	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	Installation of a main entry door rain deflector channel.		FAA STC ST00163BO dated 21 November 2007.FAA SOC dated 06 may 2008.Bombardier Aerospace MDL No. BAS67017003, Revision A, dated 11 November 2007 or later approved revision.		08/05/2008	Active	10016401
EASA.IM.A.S.02731	HONEYWELL INTERNATIONAL INC.		FAA STC ST00381SE	BOEING 757	Installation of Enhanced Ground Proximity Warning System inB-757 Series Aircraft.Approval applies to aircraft equippedwith a flight management system, which meets AC90-45A, or an EGPWS with a GPS based navigation system or an EGPWS equipped with an internal GPS and a GPS antenna as defined in Mast...		Flight Manual Supplements approved by FAA*060-4189-002, 060-4189-015, 060-4189-029, 060-4189-022060-4189-055, 060-4189-054, 060-4189-066, 060-4189-065060-4189-081, 060-4189-082, 060-4189-079, 060-4189-117Operating & Service Instructions*: 060-4199-180(*) See Applicable documents in Honeywell STC ST...	1. Approval of this change in type design applies to theabove model aircraft equipped with either a flight management system (FMS), which meets AC90-45A, or an EGPWS with a global positioning system (GPS) based navigation system or an EGPWS equipped with an internal GPS and a GPS antenna as defi...	11/04/2008	Active	10016402

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02733	SAVANNAH AIR CENTER, L.L.C.		FAA STC ST03528AT	BOMBARDIER BD-700-1A11	Installation, Complete Custom Interior, s/n 9229 Configuration.		FAA statement of Compliance dated 14 March 2008Savannah AirCenter Master Drawing List Number G5K9229-MDL-2500001, Revision "A", dated December 1, 2007Instruction for continued Airworthiness, Bombardier Global 5000 Document number G5K9229-IFCS-0001, Revision "IR", dated November 5,2007	Restricted to ASN 9229.	01/04/2008	Active	10016404
EASA.IM.A.S.02734	S-TEC CORPORATION		FAA STC SA09298AC-D	PIPER PA-31-325 PIPER PA-31	Installation of S-TEC SYSTEM 55/55X Two Axis Automatic Flight Guidance System, Model ST-751, also when modified per FAASTC as listed in 3.5 (Limitations and Conditions).		FAA approved Bulletin No. 851, Revision 3, dated 3-12-01 orlater FAA approved revisions (28 Volt System)FAA approved Master Drawing List No. 921041, Rev. C, dated 3-12-01 or later FAA approved revisions (28 Volt System)FAA/DAS Approved Pilot's Operating Handbook and/or Airplane Flight Manual Supple...	This STC is also eligible on Models PA-31 when modified perSTC SA970SO (350 hp Colemill Conversion)This STC is also eligible on Model PA-31-325 when modified per STC SA00048SE (Vortex Generators System).Prior to installation of this modification the installer must determine that the interrelati...	22/05/2008	Active	10016405
EASA.IM.A.S.02735	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10334SC-D	G150	Installation of a Lavatory Smoke Detection system.		ICA GA331455A000AFMS GA31455M000	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	18/03/2008	Active	10016406
EASA.IM.A.S.02737	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		TCCA STC Q-LSA08-001/D	BOMBARDIER BD-700-1A10	Replacement of conference table in aircraft S/N 9197, aft cabin.		Transport Canada LSTC No. LSA08-001/D Issue 1 dated 15 January 2008.Transport Canada Statement of Compliance ref: NAI5012-08-0003 dated 18 January 2008MDL27142002, Master DocumentList - Conference Table Replacement on Aircraft S/N 9197, revision NC, dated January 15, 2008.TL27142-004, Time Limits a...	Restricted to ASN 9197With this modification incorporated Aft LSH forward facing double seats must not be occuped durint taxi take off and landing.	19/03/2008	Active	10016407
EASA.IM.A.S.02739	ANCRA INTERNATIONAL LLC		FAA STC ST01388LA	747-200, 747-300, 747-400 3.777-200, 777-300 2. 767-200, 767-300, 767-400ER	Installation of Power Drive Unit (Cargo System).		747 Series Ancra Controlled Data Lists, DL92001, Revision E, 02/07/2007 DL92002, Revision E, 02/07/2007 DL92003, Revision B, 02/07/2007767 Series Ancra Controlled Data List, DL92001, Revision E, 02/07/2007777 Series Ancra Controlled Data List, DL92001, Revision E, 0...		31/03/2008	Active	10016408
EASA.IM.A.S.02743	JET AVIATION ST. LOUIS, Inc.		FAA STC ST00754WI	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of Emergency Lighting System.		Midcoast Aviation Certification Drawing List 34-415-G001 Revision E dated March 20, 1999 or later approved revisions.	This STC must be installed with Cabin interior arrangement per EASA STC No. EASA.IM.A.S. 02745 and an oxygen system per EASA STC EASA.IM.A.S. 02744 or other approved interior arrangement and oxugen system.	20/03/2008	Active	10016411

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02744	JET AVIATION ST. LOUIS, Inc.		FAA STC ST00755WI	BOMBARDIER CL-600-2B16	Installation of Passenger Oxygen System.		Midcoast Aviation Certification Drawing List 34-261G001 Revision B dated March 15, 1999, or	This STC must be installed with Cabin interior arrangement per EASA STC No. EASA.IM.A.S. 02745 and an emergency lightingper EASA STC. No. IM.A.S.02743 or other approved interior arrangement and emergency lighting system.	20/03/2008	Active	10016412
EASA.IM.A.S.02745	JET AVIATION ST. LOUIS, Inc.		FAA STC ST00756WI	BOMBARDIER CL-600-2B16 (604) BOMBARDIER CL-600-2B16 (601-3R BOMBARDIER CL-600-2B16 (601-3A	Cabin Interior Arrangement.		Midcoast Aviation Certification Drawing List 34-299G001, Revision D, dated 18 March 1999, or later approved revision.	This STC must be installed concurrent with an emergency lighting system per EASA STC No. EASA.IM.A.S.02743 and an oxygen system perEASA.IM.A.S.02744 or other approved emergency lighting and oxygen system.	20/03/2008	Active	10016413
EASA.IM.A.S.02746	JET AVIATION ST. LOUIS, Inc.		FAA STC ST00812WI	BOMBARDIER CL-600-2B16 (604) BOMBARDIER CL-600-2B16 (601-3R BOMBARDIER CL-600-2B16 (601-3A	Installation of the Allied Signal MK-V Enhanced Ground Proximity Warning System (EGPWS).		Midcoast Certification Drawing List No. 34-327G001 RevisionD, dated August 24, 1999,Midcoast Airplane Flight Manual Supplement, Document No. 34-327M001, Revision "Original", dated August 24, 1999, or later Approved Revisions to (1) or (2).<	Gama Support Services Modification No. GSSL-MIN-CL604-226 (Including Gama Support Services Flight Manual Change Sheet No. GSS-FMS-CL604-226 EASA approval number EASA.A.A.01831), or equivalent EASA approved modification, is a prerequisite for the EASA approval of this STC and must be incorporated.	03/06/2008	Active	10016414
EASA.IM.A.S.02747	AMERICAN PROPELLER SERVICE		FAA STC SA5896NM	210L, 210M 210F, 210G, 210H, 210J, 210K	Installation of a McCauley D3A34C404/80VA-0 Propeller.		Installation in accordance with American Propeller Service,Installation Instructions AP404-1, dated June 1, 1992, or later approved revisions.Operation in accordance with American Propeller Service, Flight Manual Supplement for SA5896NM,dated January 14, 1993, or later approved revisions.	As defined in FAA STC SA5896NM1 Prior to installation ofthis modification the installer must determine that theinterrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	02/10/2008	Active	10016415
EASA.IM.A.S.02749	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA08-089/D	BOMBARDIER BD-100-1A10 (CHALLE	AIRCRAFT COMPLETION, 10 PASSENGERS INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA08-089/DIssue 1 dated 21st April 2008, in accordance with Aero ConsultingServices Ltd. Modification Data Summary F791000 Revision N/C.		¿ Transport Canada Limited Supplemental Type CertificateC-LSA08-089/D Issue 1, dated 21st April 2008.¿ TransportCanada Approved Aero Consulting Services Ltd. Modification Data Summary ref. F791000 dated 21st April 2008, RevisionN/Cor later Transport Canada approved revision. ¿ Transport C...	This STC is limited to aircraft Bombardier BD100-1A10 Serial Number 20189.	23/04/2008	Active	10016416
EASA.IM.A.S.02750	FIELD AVIATION COMPANY INC.		TCCA STC SA05-73	BOMBARDIER DHC-8-311	Intallation of a Artex C406-2 or C406-N Three Frequency Emergency Locator Transmitter (ELT).		Maintenance Manual Supplement 200331.		11/06/2008	Active	10016417
EASA.IM.A.S.02751	FIELD AVIATION COMPANY INC.		TCCA STC SA00-2	BOMBARDIER DHC-8-315 BOMBARDIER DHC-8-311 BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES	Ultra Electronics ANVC-Active Noise and Vibration Control System and PBMS – Propeller Balancing and Monitoring SystemRef. TCCA STC SA00-2, Issue 4, dated 24 October 2004		Configuration A - Ultra ElectronicsANVC - Active Noise and Vibration Control System, fitted with a Post 1990Heath Techna Interior (Structural and Electrical Provisions Only)PBMS - Propeller Balancing and Monitoring System (Structural and Electrical Provisions Only)DHC-8-300 SeriesInstallation must b...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	25/08/2008	Active	10016418

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02756	GULFSTREAM SERVICES CORPORATION		FAA STC ST03543AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4113.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List, GC414914113, rev. D, dated 19 May 2008, or later approved revisions.	Aircraft Serial Number 4113 only.The following STCs are required part of this STC:ST03027AT-DST02987AT-DST03047AT-DST02980AT-DST03290AT-DST03532AT-DST02979AT-DIt is the installersresponsibility to ensure these STCs are all EASA approved.Prior to installation of this modification the installer must...	23/05/2008	Active	10016420
EASA.IM.A.S.02757	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03410AT-D	GULFSTREAM GIV-X	Installation of a Aft Lavatory Multiple STC		Install in accordance with Gulfstream Aerospace CorporationIndex List, GC420000478, Rev N, dated January 29, 2009, or later FAA approved revision.	1. This Aft Lavatory Multiple STC, (FAA ref ST03410AT-D), does not approve the entire airplane completion and interior installationand has the following limitations as defined in document GC414680145, “Guidance for Follow on Installation, Aft Lavatory Multiple STC”:1. A complete airplane interior...	08/06/2009	Active	10016421
EASA.IM.A.S.02759	GENERAL AEROSPACE INC		FAA STC SA3169SO	B737-400, B737-500 B737-200, B737-300	Installation of a Collins Traffic Alert an Collision Avoidance Systemand Dual Mode-S Transponders.	As defined in TCDS	General Aerospace Master Drawing List GA-34-1002 Rev. EFAA approved AFM Supplement GA135AFM dated NOV 23, 1993 orFAA approved AFM Supplement GA136AFM dated SEP 15, 1998and EASA AFM Supplement GA37-ELS/ EHS-AFMS01 Issue IRor later revision of the above documents approved by EASA in accordancewith EASA...	A copy of this STC must be included in the permanent recordof theaircraft.	30/07/2009	Active	10035023
EASA.IM.A.S.02762	ROSEMOUNT AEROSPACE, Inc.		FAA STC ST02712CH	BOEING 747-400	Installation of Rosemount Aerospace 8700C2-6 Series Laptop Docking Station (LDS) - Electronic Flight Bag (EFB) Systems Provisions in accordance with Rosemount Aerospace Master Data List, Doc. No. D06402649 Revision C, dated April 3, 2009 or later FAA approved revision.		Airplane Flight Manual Supplement for B747-400, Doc. No. D06402687 Rev. A.	1. FAA approved Airplane Flight Manual Supplement, Rosemount Aerospace Doc. No. D06402687, Revision A, approved April 2, 2009 orlater FAA approved revision, is required on board of the modified aircraft.2. This installation approval does not include the Electronic Flight Bag computers. The ope...	23/04/2009	Active	10016424
EASA.IM.A.S.02763	S-TEC CORPORATION		FAA STC SA09132AC-D	CESSNA 172N CESSNA 172M	Installation of S-TEC System 55/55X Two Axis Automatic Flight Guidance System, Model ST-612 in Cessna 172M and 172N.		Bulletin No. 712, Revision 2, dated 28-Feb-2001 or later approved revision.Master Drawing List No. 92827, Revision B, dated 28-Feb-2001, or later approved revision (14 Volt System).FAA/DAS Approved or Airplane Flight Manual Supplement, P/ N891218 Revision 1, dated 28-Feb-2001, required for Cessna Mo...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsI...	08/05/2008	Active	10016425

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02765	PRATT & WHITNEY		FAA STC SA00095BO, LBA SA 1346	BEECH B300C BEECH B300 BEECH B200T BEECH B200CT BEECH B200C BEECH B200 BEECH A200CT BEECH A200C BEECH A200 BEECH 300LW BEECH 300 BEECH 200T BEECH 200CT BEECH 200C BEECH 200 BEECH 1900D BEECH 1900C, AIRLINER BEECH 1900	Installation of Pratt & Whitney Engine Services, Inc. Twin Engine Aircraft Data Acquisition System ADAS/ADAS+ Upgrade, P/N TWIN-K-010		Pratt & Whitney Engine Services, Inc. Installation Manual, Document No. TWIN-I-010-1, Revision J, dated November 8, 2002, or later approved revision	1. Pratt & Whitney Engine Services,Inc. Aircraft Flight Manual Supplement for Raytheon Aircraft Company Models 200, 200C, 200CT, 200T, A200, A200C, A200CT, B200, B200C, B200CT, B200T, 300, 300LW, B300C, 1900, 1900C, 1900D, Document No. TWIN-T-250-1, Revision C, approved on May 21, 2003, or later app...	07/03/2008	Active	10016426
EASA.IM.A.S.02766	BOMBARDIER INC.		TCCA STC C-LSA08-145/D ISSUE 1	BOMBARDIER BD-100-1A10 (CHALLE	CUSTOMIZED INTERIOR COMPLETION – AIRCRAFT 2020310 passengerseats interior configurationEASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA08-145/DIssue 1 dated 18th August 2008, in accordance with Aero ConsultingServices Ltd. Modification Data Summary F827000 Revision N/...		¿ Transport Canada Limited Supplemental Type Certificate C-LSA08-145/D Issue 1, dated 18th August 2008.¿ Transport Canada Approved Aero Consulting Services Ltd. Modification Data Summary ref. F827000 dated 28th July 2008, Revision N/C or later Transport Canada approved revision. ¿ Transp...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.1 The installation of this modification by third pers...	20/08/2008	Active	10016427
EASA.IM.A.S.02767	G&D AERO PRODUCTS INC.		FAA STC SA7063NM	BEECH 300 BEECH 200	Installation of Acrylic window liners		In accordance with FAA approved drawing lists, drawing lists are detailed in the attached AML to this STC at latest approved revision.	None	05/03/2008	Active	10016428
EASA.IM.A.S.02768	B/E AEROSPACE LIMITED		TCCA C-LSA08-017/D ISSUE 2	BD-700-1A10	Cabin Electronics Upgrade.		Transport Canada Limited STC No. C-LSA08-017/D dated 06 February 2008Transport Canada Statement of Compliance ref C-08-0114 dated 04 July 2008Aero Consulting Services ModificationData Summary No. F60200 Revision NC or later approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	09/07/2008	Active	10016429
EASA.IM.A.S.02771	DECA AVIATION ENGINEERING LIMITED	REV 1	TCCA STC O-LSA07-260/D ISSUE 2	BOMBARDIER BD-700-1A10	Cabin Interior Reconfiguration.		TCCA STC No. O-LSA07-260/D Issue 3 dated 18 August 2008.TCCA SoC reference 5010-O-08-0543 dated 06 November 2008.DECA Aviation Modification Summary MS07158 revision 2 or later approved revision.DECA Instructions for Continued AirworthinessICA07158 Revision 2 or later approved revision.DECA Flight M...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	12/11/2008	Active	10016431
EASA.IM.A.S.02772	FIELD AVIATION COMPANY INC.		TCCA STC O-LSA08-023/D	BOMBARDIER DHC-8-311	VHF Comm Replacement for 8.33 kHz Spacing, ref. TCCA LST C-LSA08-023/D.		¿ Installation iaw modification instruction 215610.¿ Maintenance must be performed iaw Maintenance Manual Supplement 215631.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	15/08/2008	Active	10016432

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02775	THUNDER BAY AVIATION Ltd.		TCCA STC SA04-55	BOMBARDIER DHC-6	Double and Single Utility Seats for DHC-6.		Transport Canada approved Thunder Bay Aviation Master Drawing List, Doc. No. MDL013, Revision B, dated 27-Feb-2006, or later approved revisionTAG Aerospace Maintenance Manual Supplement, Doc. No. 033002-07, Revision A, dated 08-Jun-2004, or later revision		19/03/2008	Active	10016435
EASA.IM.A.S.02777	BOMBARDIER COMPLETION CENTRE INC		TCCA C-LSA08-062/D ISSUE 1	BOMBARDIER BD-700-1A10	Customized Interior Completion - ACSN 9250.		TCCA STC No. C-LSA08-062/D Issue 1 dated 26 June 2008.TCCA SOC letter C-08-0147 dated 03 July 2008.Aero Consulting Services Modification Data Summary F632000 Revision N/C dated 26June 2008.Bombardier Airplane Flight Manual Supplement G-FM25000169 Revision N/C.Instructions for Continued Airworthines...	Restricted to ASN 9250 and1. Refer to the Limitations sections of the required AFM Supplement and to the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).3. Prior to installation of this modification the installer must determine that the interrelationship between this modificatio...	17/07/2008	Active	10016436
EASA.IM.A.S.02778	CHIPPEWA AEROSPACE, Inc.		FAA STC ST03336AT	BOMBARDIER CL-600-2D24 BOMBARDIER CL-600-2D15 BOMBARDIER CL-600-2C10 BOMBARDIER CL-600-2B19	Installs of Protective Covers for the 1K4XD, TCAS and HSTU Processor.		FAA STC No. ST03336AT dated 29 September 2006 FAA Statementof Compliance (undated).Chippewa Aerospace Master Drawing List (MDL) No. 601-2451-01-0001, Rev 1, dated December 07, 2006, or later approved revision.		09/04/2008	Active	10016437
EASA.IM.A.S.02779	BOMBARDIER COMPLETION CENTRE INC		C-LSA08-065/ D ISSUE 1	BOMBARDIER BD-700-1A11	Customized Interior Completion - ACSN 9269		Transport Canada STC No. C-LSA08-065/D issue 1 dated 1 May 2008.Transport Canada Statement of Compliance C-08-0157 dated 9 May 2008.Aero Consulting Services Modification Data Summary F731000 Revision N/C.Airplane Flight Manual Supplement G-FM25000171 Revision NC or later approved revision.Instructio...	Restricted to ASN 9269.WLAN System is only compatible to 1EEE802.11 (b).	22/05/2008	Active	10016438
EASA.IM.A.S.02780	GULFSTREAM SERVICES CORPORATION		FAA STC ST03546AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4115.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC41 4914115 Rev. D, dated May 22, 2008 or later approved revisions.	Aircraft Serial Number 4115 only.The following STC's are a required part of this STC:ST03027AT-DST02987AT-DST03047AT-DST02980AT-DST03290AT-DST03532AT-DST02228CH-DST02979AT-D	29/05/2008	Active	10016439
EASA.IM.A.S.02787	S-TEC CORPORATION		FAA STC SA09233AC-D	PIPER PA-28-236 PIPER PA-28-181 PIPER PA-28-161	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST 684 (28 Volt System)		FAA approved S-TEC Bulletin No.784, dated 29-May-1997, Initial Issue, or later approved revisionFAA approved S-TEC Master Drawing List No. 92998, dated 29-May-1997, Initial Issue or later approved revisionFAA/DAS Approved Pilot's OperatingHandbook and/or Airplane Flight Manual Supplement, P/N 89141...	The approval holder shall fulfil the obligations of Part 21, Paragraph 21.A109	13/05/2008	Active	10016442

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02788	SIERRA INDUSTRIES Ltd.		FAA STC SA1689WE	CESSNA 172P	Installation of drooped ailerons in flaps down mode, contoured wing leading edges, except for 172M, 172N, and 172P), and wing stallfences.		In accordance with FAA sealed Robertson Aircraft Drawing List No 10.	1. Floatplane Models 172A thru 172H are only eligible with Franklin Engines 6A-350-C1 per STC SA340NW (215HP) or 6A-350-C2 per STC SA1334WE (180 HP).2. Fixed tabs as shown on R/STOL Systems, Inc. Drawing 10-100 required on FloatplaneModel 172E. The remaining 172 Series Floatplane Models must...	13/05/2008	Active	10016443
EASA.IM.A.S.02790	GULFSTREAM SERVICES CORPORATION		FAA STC ST02085LA-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5179.		Installa in accordance with Gulfstream Aerospace with Gulfstream Aerospace Report GC52000K555, Rev. N/C and Index List GC520008601 Rev. L, dated 1 May 2008, or later approved revisions.Operate in accordance with Gulfstream Aerospace FlightManual Supplement GC52000M072, Revision N/C, dated 1 May 200...	Aircraft Serial Number 5179 only.	30/05/2008	Active	10016444
EASA.IM.A.S.02791	LEARJET Inc.		FAA STC ST02023 LA-D	BOMBARDIER CL-600-2B16	Installation of a Mid-Cabin Interior Modification.		Bombardier Aerospace Master Document List BAS63010121, Revision "F", dated February 7, 2008 or later approved revision.Installation for Continued Airworthiness (ICA) for the -1 Configuration/Installation are contained in Document Nmuber BAS63010121-IFCA-1, datedJanuary 18, 2008 or later approved re...	A prior or concurrent requirement for the installation of the -1 Configuration is the incorporation of EASA STC No. EASA.IM.A.S.02392 for the interior/Modification Installation.	07/05/2008	Active	10016445
EASA.IM.A.S.02792	BOMBARDIER INC.		STC C-LSA08-107/D	BOMBARDIER BD-100-1A10 (CHALLE	AIRCRAFT COMPLETION, 10 PASSENGERS INTERIOR CONFIGURATION /EASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA08-107/DIssue 1 dated 19th March 2008, in accordance with Aero ConsultingServices Ltd. Modification Data Summary F786000 Revision N/C.		¿ Transport Canada Limited Supplemental Type CertificateC-LSA08-107/D Issue 1, dated 19th March 2008. .¿ Transport Canada Approved Aero Consulting Services Ltd. Modification Data Summary ref. F786000 dated 19th March 2008, RevisionN/C or later Transport Canada approved revision. ¿ Tran...	This STC is limited to aircraft Bombardier BD100-1A10 Serial Number 20123.	28/03/2008	Active	10016446
EASA.IM.A.S.02794	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA04-113	BOMBARDIER BD-700-1A10	Customized Interior Completion - ACSN 9262		TCCA STC No. SA04-113 Issue 1 dated 28 October2004.TCCA SOCletter C-08-0419 dated 28 May 2008.Aero Consulting ServicesConfiguration Deviation List D954000 Revision BN dated 09 May 2008.Bombardier Airplane Flight Manual Supplement G-FM25004001 Revision N/C.Instructions for Continued Airworthiness G...	Restricted to ASN 9262 and1.Refer to the Limitations sections of the required AFM Supplement and to the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).3.Priorto installation of this modification the installer must determine that the interrelationship between this modification a...	09/06/2008	Active	10016448

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02795	BOMBARDIER COMPLETION CENTRE INC			BOMBARDIER BD-700-1A11	Customized Interior Completion - ACSN 9273.		TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.TCCA SOC letter C-08-0626 dated 02 September 2008.Aero Consulting Services Modification Data Summary E025000 Revision AW dated 29 August 2008.Bombardier Airplane Flight Manual Supplement G-FM25004501 Revision N/C.Instructions for Continued Airworthines...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	10/09/2008	Active	10016449
EASA.IM.A.S.02796	TDG AEROSPACE INC		FAA STC ST02076LA	BOEING 737-900 BOEING 737-800 BOEING 737-700C BOEING 737-700 BOEING 737-600	Universal Fault Interrupter Installation Kit for B737NG.		FAA approved Airplane Flight Manual Supplement (Ref. TDG document 20-3202-0003), Aircraft Maintenance Manual (Ref. TDG document 20-3202-0001), Aircraft Wiring Diagrams Manual (Ref. TDG document 20-3202-0005), Aircraft Illustrated Parts Catalogue (Ref. TDG document 20-3202-0006) or later FAA approved...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	25/08/2008	Active	10016450
EASA.IM.A.S.02797	PANASONIC AVIONICS CORPORATION		-	BOEING 757-200 SERIES	Installation of a Matsuhita Avionics Audio System on a Boeing 757-200 Aircraft.		E.J. Mlynarczyk Drawing List DL10053, Revision H, 26/09/1994	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	18/07/2008	Active	10016451
EASA.IM.A.S.02798	GODERICH AIRCRAFT Inc.		TCCA STC O-LSA08-056/D ISSUE 3	FALCON 10	EASA Validation of Transport Canada Limited STC O-LSA08-056/D Issue 3:Cabin Entertainment Equipment Upgrade for Falcon 10 serial number 161 aircraft in accordance with Avionics Design Services Ltd. Master Drawing List MDL08009 Revision B, dated 31st March 2008 or later revisions approved by EASA in0...		See those of original Transport Canada Limited STC O-LSA08-056/D Issue 3:Avionics Design Services Ltd. Master Drawing List MDL08009 Revision B, Issue 1, dated 31st March 2008.Goderich Aircraft Inc. Maintenance Manual Supplement MMS-PA-08-009 Revision A, Issue 1, dated 31st March 2008.or later revisi...	EASA STC limited to Falcon 10 serial number 161 aircraftSeeoriginal Transport Canada Limited STC O-LSA08-056/D Issue 3See:Avionics Design Services Ltd. Master Drawing List MDL08009 Revision B, Issue 1, dated 31st March 2008.Goderich Aircraft Inc. Maintenance Manual Supplement MMS-PA-08-009 Revision...	21/04/2008	Active	10016452
EASA.IM.A.S.02799	TTF AEROSPACE, LLC		FAA STC ST01195SE	BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-100 SERIES	Installation of a Reinforced Flight Deck Door.		TTF Aerospace, LLC Master Data List (MDL), TTF-MDL-02T011, Rev. J, dated 05.10.2007.Or later approved revisions of the above doucment approved by EASA in accordance with EASA ED Decision 2004/04/CF or subsequent revisions of this decision.		16/06/2008	Active	10016453

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02800	JAZZ AVIATION LP		TC STC SA03-70	BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-100 SERIES	Cockpit Door Electronic Strike System.		TTF Aerospace, LLC Master Drawing List (MDL), TTF-03T002-01, Rev. E, dated 13.06.2007 *)TTF Aerospace, LLC AFM Supplement TTF-03T002-15, Rev. New, dated 09.09.2003 *)TTF Aerospace, LLC Maintenance Manual Supplement TTF-03T002-12, Rev. E, date 07.05.2007 *)TTF Aerospace, LLC W&B Report, TTF-03T002-20...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.This AFM Supplement is applicable only when used in conj...	30/06/2008	Active	10016454
EASA.IM.A.S.02801	FLYING INVESTMENTS, LLC		FAA STC ST01349WI	MYSTERE FALCON 20-F5 MYSTERE FALCON 20-E5 MYSTERE FALCON 20-D5 MYSTERE FALCON 20-C5 FAN JET FALCON SERIES G FAN JET FALCON SERIES F FAN JET FALCON SERIES E FAN JET FALCON SERIES D FAN JET FALCON SERIES C FAN JET	Reduced Vertical Separation Minimum (RVSM) group airworthiness approval of specific Dassault Aviation Fan Jet Falcon and Mystere-Falcon 20 aircraft in accordance with Flying Investments LLC Master Drawing List MDL1017, Revision G, dated 19th February 2008 or later EASA approved Revisions.		Flying Investments LLC Master Drawing List MDL1017, Revision G, dated 19th February 2008Applicable Flight Manual Supplements:• Flying Investments LLC AFM Supplement KSR-0302202Revision C dated 24th January 2008 for Fan Jet Falcon, Fan Jet Falcon SeriesD, E and F and Mystere Falcon 20-C5, D5, E5o...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons•...	22/07/2008	Active	10016455
EASA.IM.A.S.02802	FLYING INVESTMENTS, LLC		FAA STC ST00571DE	MYSTERE FALCON 20-F5 MYSTERE FALCON 20-E5 MYSTERE FALCON 20-D5 MYSTERE FALCON 20-C5 FAN JET FALCON SERIES G FAN JET FALCON SERIES F FAN JET FALCON SERIES E FAN JET FALCON SERIES D FAN JET FALCON SERIES C FAN JET	Installation of an Innovative Solutions & Supports (IS&S) Dual Air Data Display Units (ADDU), an Analog Interface Unit or Air Data Sensor and Goodrich Dual Pitot-Static Probes, inaccordance with Flying Investments Master Data List GEN-031217-001, Revision K, dated 04th December 2007 or later EASA a...		Master Data List GEN-031217-001, Revision K, dated 04th December 2007Applicable Flight Manual Supplements:• Flying Investments LLC AFM Supplement GEN-031217-038 Revision C dated 28th September 2007 for Fan Jet Falcon, Fan Jet Falcon Series C, D, E and F and Mystere Falcon 20-C5, D5, E5 and F5 air...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsT...	22/07/2008	Active	10016456
EASA.IM.A.S.02803	BOMBARDIER COMPLETION CENTRE INC		TCCA C-LSA08-081/D	BOMBARDIER BD-700-1A10	Interior Completion, BD-700-1A10 serial number 9252		1. TCCA STC No.C-LSA08-081/D Issue 1 dated 22 October 2008.2. TCCA SoC reference C-08-0201 dated 30 October 2008.3. Aero Consulting Services Modification Data Summary F745000 Revision N/C or later approved revision.4. Bombardier Flight Manual Supplement G-FM25000172 Revision NC or later5...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	07/11/2008	Active	10016457

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02805	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA08-082/D	BOMBARDIER BD-700-1A10	Interior Completion, BD-700-1A10 serial number 9256.		1. TCCA STC No. C-LSA08-082/D, Issue 1 dated 10 October 2008.2. TCCA SOC Reference C-08-0202 dated 23 October 2008.3. Aero Consulting Services Modification Data Summary F746000 Revision N/C*4. Bombardier Flight Manual Supplement G-FM25000168 Revision NC*5. GC92560000-IFCA Instructions...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product. The installation of this modification by third person...	28/10/2008	Active	10016459
EASA.IM.A.S.02809	SIERRA INDUSTRIES Ltd.		FAA STC SA8437SW	CESSNA S550 (CITATION II) CESSNA 550 CITATION II	Installation of radome quick release mechanism.FAA STC SA8437SW.		Sierra Industries Inc. Drawing List No. SI160-000, Rev. B, dated 13 July 1992 or later approved revisions of this document approvedby EASA in accordance with EASA ED Decision 2004/02/CF (or subsequent revisions of this decision).This STC extends the applicability of LBA STC Nr. TA009, dated 26 Augus...		28/03/2008	Active	10016463
EASA.IM.A.S.02812	GENERAL AEROSPACE INC		FAA STC ST03486AT	BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200	Installation of a Haneywell ARINC 717 Flight Data Acquisition Management System (FDAMS).		FAA letter of compliance with EASA Certification Basis dated 12 March 2008.Master Drawing List No. GA37-DFDAU-MDL01, Revision A, dated 24 April 2007 or later revision of the abovelisted documents approved by EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decisi...		19/03/2008	Active	10016466
EASA.IM.A.S.02813	CAV AEROSPACE Inc.		FAA STC SA01435WI	LC41-550FG (C400)	Installation of TKS Ice Protection System Components.Model:LC41-550FG (C400)		According to AS&T or CAV Master Drawing List No. 12200-DL, Rev. 2 or later FAA approved RevisionsTo be operated and maintained in accordance withFAA approved AS&T or CAV AFM-S Document No. 12200-FMS, original issue, or later FAA approved Revisions	1. Prohibited for operations in known icing conditions2. Prior to installation of this modification the installermust determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the p...	24/04/2009	Active	10016467
EASA.IM.A.S.02814	DASSAULT FALCON JET CORPORATION		FAA STC ST09733SC-D	FALCON 2000	Installation of Cabin Master Switch. Validation of FAA STC ST09733SC-D.		Dassault Falcon Jet Drawing List Report No. F2M-01055, Revision B dated 25th May 2002.AFM Supplement Report No. 37023-1, Revision A dated 25th July 2002 is required when F2M-01055-501 and -503 installation is required.AFM Supplement ReportNo. 37023-2, Revision NC dated 04th October 2002 is required...	See those of original FAA STC ST09733SC-D Revision 2 dated 04th October 2002,AFM Supplement Report No. 37023-1, Revision A dated 25th July 2002 for F2M-01055-501 and -503 installations.AFM Supplement Report No. 37023-2, Revision NC dated 04th October 2002 for F2M-01055-505 installation.Or later revi...	20/05/2008	Active	10016468
EASA.IM.A.S.02815	DASSAULT FALCON JET CORPORATION		FAA STC SA8228W-D	FALCON 2000	Installation of the Airborne Flight Information System.Validation of FAA STC SA8228SW-D.		Dassault Falcon Jet Drawing List Report No. F2M-1005, Revision B dated 20th May 1999 or later revisions approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision)	See those of original FAA STC SA8228SW-D Revision 2 dated 21st May 1999 or later revisions approved by EASA in accordance with EASAED Decision 2004/04/CF (or subsequent revisions of this decision).	20/05/2008	Active	10016469

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02816	B/E AEROSPACE LIMITED		TCCA C-LSA08-143/D	GIV	Installation of Interior Modifications.		Installation in accordance with Aero Consulting Services Ltd Modification Data Summary F610000 Rev N/C or later approved revisions.Maintenance in accordance with Aero Consulting Services Ltd Mandatory Maintenance Manual Supplement F610071 Rev N/C and F610070 Instructions for Continued Airworthiness...	Aircraft Serial Number 1109 Only.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverseeffect upon the airworthiness of the product.	02/06/2008	Active	10016470
EASA.IM.A.S.02817	B/E AEROSPACE LIMITED		TCCA C-LSA08-151/D	GIV	Installation of Rockwell Collins Radio Tuning Units RTU-4210 and Rockwell Collins TDR-94D (ELS/EHS) Transponder.		Installation in accordance with Aero Consulting Services Ltd. Modification Data Summary F77300 Rev N/C or later approved revisions.Maintenance in accordance with Aero Consulting Services Ltd Mandatory Maintenance Manual Supplement F773073 Rev N/C, and instructions for Continued Airworthiness F773071...	Application to Aircraft Serial Number 1109 only,The operator is responsible for th einclusion of a 24 month check in their maintenance schedule of the Mode S transponder system toensure correct operation of the 24BIT address and the required DAPs IAW ACS MM 34-53-00For limitations refer to the Airwo...	11/06/2008	Active	10016471
EASA.IM.A.S.02818	BJAC BUSINESS JET AIRCRAFTCOMPLETIONS		FAA SA07-129 ISSUE 1	BD-700-1A10, BD-700-1A11	Goodrich Class III Electronic Flight Bag.		TCCA STC No. SA07-129 Issue 1 dated 20 November 2007.TCCA SOC 5010-O-08-0020 dated 08 October 2008.Avionics Design Services Ltd. Master Drawing List MDL06079 Revision N/C, dated 2November 2007, or later approved revision.BJAC Services Flight Manual Supplement FMS06079-1 Revision N/C, approved 20 No...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	14/10/2008	Active	10016472
EASA.IM.A.S.02819	ANCRA INTERNATIONAL LLC		FAA STC ST00680DE	737-400	Installation of mechanical cargo loading system Part Number84980-10 & -20 on B737-400 aircraft		FAA STC ST00680DE issued February 25, 2009ANCRA Controlled Data List DL84980 Rev. B dated October 16, 2008ANCRA Instructions for Continued Airworthiness, Doc No. 9138 Rev. B datedJune 11, 2008- or later revisions of the above documents approved by EASA in accordance with EASA ED decision 2004/04/CF...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	02/03/2009	Active	10016473
EASA.IM.A.S.02822	ELLIOTT AVIATION		FAA STC ST02548CH	FALCON 10	EASA Validation of FAA STC ST02548CHInstallation of an International Communications Group ICS-120 Iridium Satellite Telephone System		Installation in accordance with Elliott Aviation Master Data List, Report No. MDL-2837-111 Revision B, dated 06th March2008,FAA AFM Supplement Elliott Aviation report No. FMS-2837-111; Revision IR, approved 14th March 2008 is required on board the aircraft.Modified aircraft must be maintained in ac...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsI...	26/05/2008	Active	10016474

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02823	ELLIOTT AVIATION		FAA STC ST02547CH	FALCON 10	EASA Validation of FAA STC ST02547CHInstallation of a Universal Avionics Systems Corporation UL-701 UniLink System		Installation in accordance with Elliott Aviation Master Data List, Report No. MDL-2836-114 Revision D, dated 23rd April2008, or later revisions of this document approved by EASA in accordance with EASA ED Decision 2004/04/CF (or i.a.w. subsequent revisions of this decision)Specific EASA AFM Supplem...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsO...	26/05/2008	Active	10016475
EASA.IM.A.S.02831	AIRWORKS		FAA STC ST02150LA	DC-9-87 AND BOEING MD-88 DC-9-81, DC-9-82, DC-9-83	Installation of a Cockpit Door Surveillance System (CDSS).		As per FAA approved Air Works Master Data list, document N°MDL23019, rev. B, dated 20 June 2008.	This STC may not be installed after 7th June 2010, unless:- previously approved electrical wiring interconnection system (EWIS) instructions for onctined airworthiness (ICA) have been evaluated and determined to be adequate for this installation by FAA, or- revised EWIS ICA have been approved by the...	10/07/2008	Active	10016479
EASA.IM.A.S.02832	PENTASTAR AVIATION, L.L.C.		FAA STC ST01759CH	FALCON 900EX FALCON 900 FALCON 50	EASA Validation of FAA approved STC ST01759CHUpgrade of a Rockwell Collins SAT-906 SATCOM system by modification of Rockwell Collins SDU-906 Satellite Data Unit and HPA-901A High Power Amplifier and the installation of a Rockwell Collins HST-900 High Speed Data Transceiver in accordance with Pentast...		Pentastar Aviation Engineering Report No. 02ER-004, Revision IR, dated 17th December 2002Instructions for Continued Airworthiness. Pentastar Aviation Maintenance Supplement No. 02CA-004 Original Issue dated 28th October2002Or later revisions of this document approved by EASA in accordance with EASA...	1. See those of original FAA STC ST01759CH.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduceno adverse effect upon the airworthiness of the product. The...	01/04/2009	Active	10016480
EASA.IM.A.S.02833	PREMIER AIR CENTER, LLC		FAA STC ST02388CH	BD-100-1A10 (CHALLENGER 300)	Installation of a Rockwell Collins IFIS-5000 Integrated FlightInformation System with display on the existing Rockwell Collins Proline21 Continuum Electronic Flight Instrument System (EFIS) / EASAValidation of FAA STC ST02388CH		- Master Data List, ref. doc. 09-385L001, Rev. A- Airplane Flight Manual Supplements, ref. doc. 09-385B001, Rev. I/R &ref. doc. 09-385B003, Rev. I/R- Maintenance Requirements - Instructions for Continued Airworthiness,ref. doc. 09-385B002,Rev.A	1. Prior to Installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	01/07/2009	Active	10043311
EASA.IM.A.S.02834	LEARJET Inc.		FAA STC ST01730LA-D	BOMBARDIER CL-600-2B16 (604)	FAA STC ST01730LA-D, Installation of an Aircell Axxess II Iridium Satcom System.		FAA STC ST01730LA-D dated 15 August 2006.Bombardier Aerospace Master Document List BAS63017007, Revision B, dated August 15, 2006, or later Approved revision.The Maintenance Instructions for Continued Airworthiness (IFCA) for the -1 Configuration / Installation are contained in Document Number BAS63...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	24/06/2008	Active	10016481
EASA.IM.A.S.02836	DECA AVIATION ENGINEERING LIMITED		TC STC O-LSA08-069/D	BOMBARDIER DHC-6-300	Radar System Installation.		Installation in accordance with DECA Aviation Engineering Ltd Modification Summary MS 07099 Rev 1 or later Transport Canada approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsM...	12/11/2008	Active	10016482

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02837	LIFEPORT, LLC		FAA STC ST02119LA	CESSNA 750 CITATION X	Emergency Medical System		Master Drawing List, MDL-833-00, Revision DAirplane Flight Manual EGR 833-11, Revision AInstructions for Continued Airworthiness, EGR 833-12-A	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	30/07/2008	Active	10016483
EASA.IM.A.S.02838	AVIATION PARTNERS BOEINGWINGLETS COMPANY, LLC		FAA ST01219SE	737-300, 737-500					15/07/2009	Active	10029056
EASA.IM.A.S.02839	BLACKHAWK MODIFICATIONS Inc.		FAA SA10824SC	B. B200T B. 200, 200C, 200CT, 200T A. B200, B200C, B200CT	Upgrade Super King Air 200, A200 and B200 Series King Airs to Pratt and Whitney Canada PT6A-52 engines.		Installation of Pratt & Whitney Pratt and Whitney Pratt & Whitney Canada PT6A-52 in accordance with Blackhawk Modifications Inc. Master Drawing List No. 05210050, Rev. IR, dated 15. Nov. 2007 or later approved revision.Operation must be inaccordance with Blackhawk Modifications Inc. Aircraft Flight...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	25/08/2008	Active	10016484
EASA.IM.A.S.02840	GOODRICH LIGHTING SYSTEMS, INC		FAA STC ST10742SC	A318, A319, A320, A321	Forward LED Navigation Lighting System Installation		• FAA STC ST10742SC• Aircraft Systems and Manufacturing Top Drawing List, ref. 5685-0001-00, Rev. C dated 19.07.2007• Instruction for Continued Airworthiness, ref. R-398-13, Rev. A, dated 15.11.2007		09/06/2008	Active	10016485
EASA.IM.A.S.02842	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10296SC-D	GULFSTREAM 200	Installation of a Cabin interior		Index List GA220008102; rev A dated 1/12/2005 ;Flight manual supplement GA21468M102, Rev Noneor later revisions of the above documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).	G-200, S/N 102, The compatibility of this design change with previously approved modifications must be determined by the installer .	08/07/2008	Active	10016486
EASA.IM.A.S.02843	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10295SC-D	GULFSTREAM 200	Installation of a 3rd FMS 6100 Flight Management System i.a.w.Index List GA213188000, Rev C or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		AFMS GA21318M000 Rev - or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsE...	28/05/2008	Active	10016487
EASA.IM.A.S.02844	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10294SC-D	GULFSTREAM 200	Installation of a Pedestal Extension in a Gulfstream G200.		Index List GA220048000, Rev A or later revision of the above document approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	08/07/2008	Active	10016488

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02845	LIFEPORT, LLC		FAA STC SA00096LA	HAWKER HS 125-700A HAWKER 800 XP HAWKER 800 HAWKER 1000 BAE 125 SERIES 800B BAE 125 SERIES 800A BAE 125 SERIES 1000B BAE 125 SERIES 1000A	Installation of a Patient Loading and Utility System.		Installation in accordance with LifePort Inc. Master Drawing List as defined in AML No. EASA.IM.A.S. 02845 to this STC. Dated 30 July 2008 or later approved revisions.Operation in accordance with LifePort Inc. Manual Supplement for LifePortPLUS System No. 39 as defined in AML No. EASA.IM.A.S.02845 t...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	30/07/2008	Active	10016489
EASA.IM.A.S.02846	STG AEROSPACE Inc.AKA SAFTGLO, Inc.		FAA STC ST01829AT	BOEING 737-900 BOEING 737-800 BOEING 737-700 BOEING 737-600 BOEING 737-500 BOEING 737-400 BOEING 737-300 BOEING 737-200 BOEING 737-100	Installation of the SAFTGLO Non-electrical PhotoluminescentEscape Path Marking System to include all 737 models.		¿ FAA STC ST01829AT ¿ DAS/ SafTGlo MDL Report Number E74-2, Revision I.R., dated 9 February 1999*. ¿ SafTGlo MDLReport Number E74-2, revision G, dated 13 June 2002* for installations occurring after 1 July 2002.*or any later revision of the above listed documents approved in accordance withs...	The photo luminescent Floor Proximity Emergency Escape PathMarking System is only eligible for installation on aircraft model numbers with interior arrangements approved in the SafTGlo MDL No. E74-2, Rev. I.R. for the B 737 incorporating SafTGlo Drawing SG-B737 Rev B dated June 11, 1998 or later ap...	14/04/2008	Active	10016490
EASA.IM.A.S.02853	EJM AEROSPACE SERVICES		FAA STC ST02534AT	BOEING 747-400	Installation of a Matsushita Avionics Systems Corporation System 3000 In-Flight Entertainement System on a Singapore Airlines Boeing 747-400 in accordance with Master Drawing ListMDL 10321, Rev. H. dated 29/04/2003, or later FAA approved revision.		FAA approved Airplane Flight Manual Supplement, Document number 14526002, dated June 06, 2002 or later FAA approved revision.	This STC is approved only for the product configuration as defined in the approved design data. Compatibilty with otheraircraft/engine configurations shall be determined by the installer.	18/08/2008	Active	10016491
EASA.IM.A.S.02854	LIFEPORT, LLC		FAA STC ST00154SE	CESSNA S550 CESSNA 560 CESSNA 550 CESSNA 500	Emergency Medical System		Certification Plan EGR-700-10-A of 03 April 2002Instructions for Continued Airworthiness EGR-700-12 of 04 April 2002.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	27/08/2008	Active	10016492
EASA.IM.A.S.02855	BOMBARDIER AEROSPACE		TCCA C-LSA08-097/D ISSUE 1	CL-600-2B16	Installation of Club Seating		TCCA STC No. C-LSA08-097/D, Issue 1, dated 20 March 2008.Amtech Aeronautical Limited (AAL) Master Data List MDL418501.Revision IR dated 2008 March 18.AAL Instructions for Continued Airworthiness document ICA418501, Revision IR dated 2008March 18 or later approved revision.		05/05/2008	Active	10016493
EASA.IM.A.S.02856	BOMBARDIER AEROSPACE		TCCA C-LSA07-418/D ISSUE 1	BOMBARDIER CL-600-2B16 (604)	Installation of EMS High Speed Data System		Transport Canada STC No C-LSA07-418/D Issue 1 dated 31 December 2007.Bombardier Master Document List BAS63010116, Revision A dated 14 March 2008 or later approved revision.Bombardier Instructions for Continued Airworthiness (IFCA) documentBAS63010116-IFCA-1, Revision A or later accepted (AWL subdoc...	1. Restricted to ASN 54642. Limitation: This approval is limited to 1,500 flight cycles or 12 months from the approval date, whichever comes first until theAirworthiness Limitations subdocument BAS63010116-AWL-1 of Bombardier IFCA BAS63010116-IFCA-1 is approved.3. Prior to installation of this modif...	28/07/2008	Active	10016494

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02858	DELTA ENGINEERING CORPORATION		FAA STC ST02403NY-D	BOEING 747-400	Installation of Seat In-Flight Entertainment Components andSoftware update in accordance with Delta Engineering MasterData List 0107-06195-2172 Revision A, dated 4 April 2008. Validation of FAA STC ST02403NY-D.		0107-06195-2172 Rev. A Master Data List for Panasonic Avionics IF System 3000.44-25-72 Aircraft Maintenance Manual Supplement B747-4000707-06201-2172 Rev. A Instruction for Continued Airworthiness for System 3000 IFE installation in B747-400.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsC...	14/08/2008	Active	10016496
EASA.IM.A.S.02859	BASIC AIRCRAFT PRODUCTS, INC.		FAA SA02747AT	182	Stand-by Alternator – Installation of Basic Type BAE-14/28 Deployable Air Driven Alternator System.		The installation will be done in accordance with Basic Aircraft Products document “INSTALLATION MANUAL NO. 80-2625-101A”, issued July 5, 2003 or later FAA approved revision.The applicable AFMS as per Basic Aircraft Products document BAE-14/28 Air Driven Alternator installed on Cessna 182 : “FAA Appr...	As per FAA STC SA02747AT limitations.	29/08/2008	Active	10016497
EASA.IM.A.S.02860	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02523CH-D	GULFSTREAM GV-SP	Aircraft Serial No 5186 completion and cabin interior installation.		Installation in accordance with Gulfstream Aerospace Corporation Master Drawing List No. GC52 2046093, Revision A, dated July 8, 2008*.Operation to be in accordance with Gulfstream Flight Manual Supplement GC52 204M032, Original Release, dated July 15*.*or later revisions of the above listed documen...	1. GV-SP Serial No. 5186 Only2. Prior to installationof this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation...	29/07/2008	Active	10016498
EASA.IM.A.S.02861	HOLLINGSEAD INTERNATIONAL		FAA STC 01835LA	BOEING 767-300 BOEING 767-200	Installation of mounting provisions and electrical provisions for electronic flight bags.		Hollingsead Internaitonal Master Data List 2813-01, Revision D, February 20, 2007	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.	02/06/2008	Active	10016499
EASA.IM.A.S.02862	ASTRONICS ADVANCED ELECTRONICSYSTEMS		FAA ST02535AT	747-400	Installation of a General Dynamics EmPower AC In-Seat powerSupply System on a Boeing 747-400 type aircraft in accordance with Master Drawing list MDL1091-3, Rev. C, dated August 6, 2002, or later FAA approved revision		FAA approved Airplane Flight Manual Supplement Document Number D1091-517-8, dated June 6, 2002 or later approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsF...	23/07/2008	Active	10016500
EASA.IM.A.S.02865	BOMBARDIER AEROSPACE		TCCA C-LSA08-237/D	BD-100-1A10	CUSTOMIZED INTERIOR COMPLETION – AIRCRAFT 2021210 passengerseats interior configurationEASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA08-237/DIssue 1 dated 24th September 2008, in accordance with Aero ConsultingServices Ltd. Modification Data Summary F925000 Revision...		¿ Transport Canada Limited Supplemental Type Certificate C-LSA08-237/D Issue 1, dated 24th September 2008. ¿ Transport Canada Approved Aero Consulting Services Ltd. Modification Data Summary ref. F925000 dated 24th September 2008,Revision N/C or later Transport Canada approved revision. ¿rt...	1 Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.1 The installation of this modification by third...	09/10/2008	Active	10016502

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02867	LIVETV, L.L.C.		FAA STC ST03177AT	EMBRAER ERJ 190-100 ECJ	FAA STC ST03177AT: Installation of LiveTV LTV 2000 In-Flight Entertainment System		-MDL J1901TK0010-MDL, Revision E, dated June 14,2006 *)- AFMSupplement J1901TR0010-AFM dtd. October 18, 2005 *)- Instructions for Continued Airworthiness J1901TR0010-ICA Rev. IR dtd August 3,2005 *)*) or later approved revision iaw EASA ED Decision 2007/001/C or later revisions ofthis Decision	Installation based on EMBRAER provisions	05/09/2008	Active	10016503
EASA.IM.A.S.02868	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02092LA-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5191.		Install in accordance with Gulfstream Aerospace Report GC52000K574, Rev. N/C and Index List GC520008319 Rev. L, dated 2September 2008, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M078, Revision A, dated 2 September 2008.	1. Aircraft Serial Number 5191 only.2. Prior to installation of this modification the installer must determine that theinterrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation...	11/09/2008	Active	10016504
EASA.IM.A.S.02870	CHIPPEWA AEROSPACE, Inc.		FAA STC ST03573AT	BOMBARDIER CL-600-2D24 BOMBARDIER CL-600-2D15 BOMBARDIER CL-600-2C10 BOMBARDIER CL-600-2B19	Installs the electrical provisions for Goodrich 8730A2 Class 2 Elect. Flt. Bag.		FAA Statement of Compliance dated 29 May 2008.FAA STC No. ST03573AT dated 25 April 2008.Chippewa Aerospace MDL No. 601-4620-01-0001 revision IR dated 29 January 2008 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.This modification may not be installed after June 7, 201...	24/06/2008	Active	10016506
EASA.IM.A.S.02872	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST01683CH	747-300, 747SR 747-200B, 747-200C, 747-200F	Installation of Universal Avionics Systems Corporation Multi-FunctionDisplay in accordance with Electronic Cable Specialists Master Data ListECS-200663 Rev. G dated April 18, 2009or later FAA approved revision.		Airplane Flight Manual supplement as listed in Appendix A of ElectronicCable Specialists Master Data List ECS-200663 Rev. G, dated April 18,2009 or later approved revision, is required on board the aircraft.	1. Airplane Flight Manual supplement as listed in Appendix A ofElectronic Cable Specialists Master Data List ECS-200663Rev. G, datedApril 18, 2009 or later approved revision, is required on board theaircraft.2. Prior to installation of this modification the installer mustdetermine that the interrel...	02/06/2009	Active	10043063
EASA.IM.A.S.02873	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02182CH	BOEING 747-SR BOEING 747-400F BOEING 747-400D BOEING 747-400 BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-200B BOEING 747-100	Installation of Elementary or Enhanced Surveillance Mode S Transponder iaw Electronic Cable Specialists Master Data List ECS-202128, rev. AB, 7 January 2008 or later approved revision.		Electronic Cable Specialists AFM supplement as listed in Appendix A of Electronic Cable Specialists Master Data List ECS-202128, rev. AB, 7 January 2008 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.0 The installation of this modification b...	20/10/2008	Active	10016507
EASA.IM.A.S.02875	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD.		TCCA Q-LSA08-021/D	BOMBARDIER CL-600-2B16 (CL-604	Cabin Finishing Refurbish on aircraft S/N 5442.		1. TCCA STC No. Q-LSA08-021/D Issue 3 dated 11 June 2008.2.Innotech Aviation Master Document List MDL28103002 revisionB dated 11 June 2008.	1. Restricted to ASN 5442.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this mo...	06/10/2008	Active	10016508

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02876	L-3 COMMUNICATIONS / AVIATIONRECORDERS		FAA STC ST03560AT	DC-9-87, MD-88 DC-9-81, DC-9-82, DC-9-83,	Installation of L3 Communications Aviation Recorder Mirco Quick Access Recorder (uQAR).		Master Drawing List No. 905-E4310-20 Rev. D dated 26.02.2008Instructions for continued Airworthiness No. 905-E4311-20 Rev. A Dated 23.10.2007	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	21/07/2008	Active	10016509
EASA.IM.A.S.02877	AIRCRAFT ENGINEERING &INSTALLATION SERVICES Inc.		FAA STC ST02974AT	767-200	Installation of the KANNAD 406 ATP Emergency Locator Transmitter		Aircraft Engineering and Installation Services Master Drawing List 234-04-0025, Revision B, 111th October 2004	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.	03/06/2008	Active	10016510
EASA.IM.A.S.02878	ROCKY MOUNTAIN AIRCRAFT	REV. 1	TCCA STC SA08-38	BOMBARDIER DHC-6 SERIES 200 BOMBARDIER DHC-6-300 BOMBARDIER DHC-6-100	Installation of Pitot Heat Indication system.		Installation in accordance with Transport Canada STC SA08-38, issue 1, April 07, 2008, or later Transport Canada approved revision.The applicable manuals are as follows:Airplane Flight Manual Supplement : TCCA approved FMS-1270-01, Issue 1, dated 29 February 2008, or later Transport Canada approvede...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	11/11/2008	Active	10016511
EASA.IM.A.S.02879	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02524CH-D	GULFSTREAM GIV-X	Aircraft completion and cabin interior installation Serial No 4119.		1. Installation in accordance with Gulfstream Aerospace Corporation Master Drawing List No. GC42 2046129, Revision C, dated July25, 2008, or later approved revisions;2. Operation to be in accordance with Gulfstream Flight Manual Supplement GC42 204M036, Original Release, dated July 28, 2008, o...	1. GIV-X Serial No. 4119 Only;2. Prior to installation of this modification the installer must determine that theinterrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation...	07/08/2008	Active	10016512
EASA.IM.A.S.02882	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02583CH-D	GULFSTREAM GV-SP	Aircraft Serial No 5197 completion and cabin interior installation.		1. Installation in accordance with Gulfstream Aerospace Corporation Master Drawing List No. GC52 2046103, Revision A, dated September 23, 2008, or later approved revisions.2. Operation to be in accordance with Gulfstream Flight Manual Supplement GC52 204M034, Original Release, dated September 29, 20...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product. The installation of this modification by third person...	27/10/2008	Active	10016513

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02884	GULFSTREAM SERVICES CORPORATION		FAA STC ST03570AT	GULFSTREAM 200	Installation of an Auxiliary Power Unit (APU) Surge ControlValve Modification.		Install in accordance with Gulfstream Aerospace CorporationIndex List, CEB24428000, rev D. dated April 3, 2008, or later approved revisions.Operation in accordance with Civil Airworthiness Authority of Israël (CAAI) and FAA Approved Gulfstream 200 Flight Manual Section 1Limitations, APU Limitations...		02/07/2008	Active	10016514
EASA.IM.A.S.02886	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02578CH-D	GULFSTREAM GV-SP	Aircraft Serial No 5189 completion and cabin interior installation.		Installation in accordance with Gulfstream Aerospace Corporation Master Drawing List No. GC52 2046096, Revision A, dated August 26,2008, or later approved revisions.Operation to be in accordance with Gulfstream Flight Manual Supplement GC52 204M031, Original Release, dated August 26, 2008, or later...	1. GV-SP Serial No. 5189 Only2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this...	17/09/2008	Active	10016515
EASA.IM.A.S.02887	HARTZELL SERVICE CENTER		FAA STC SA2078CH	CESSNA R172K	Installation of a Hartzell Propeller Inc. 75” Diameter 3-Blade Propellermodel (P)HC-C3YF-1RF/F7392 with A-2295-1(P) spinneror model (P)HC-G3YF-1RF/F7392 with C-4582-(P) spinneron a Cessna R172K (Hawk XP) Landplane aircraft.		STC No. SA02078CH, dated December 3, 2004;Hartzell DocumentHP-R172K-NST, “Instructions for Installation of a Hartzell (P)HC-G3YF-1RF/F7392 propeller with C-4582-(P) spinneror (P)HC-C3YF-1RF/F7392 with A-2295-1(P) spinner on Cessna R172K “Hawk XP” aircraft” dated October 28, 2004, FAA accepted Novem...	This STC is compatible with STC SA1437CE that installs the TCM IO-360-K, or –KB, engine as modified by STC SE1436CE. The re-rated engine is designated IO-360-KC, or –KBC, which increases the power rating to 210hp@2800 rpm for five minutesat takeoff and 195hp@2600 rpm maximum continuous1 Prior t...	05/08/2008	Active	10016516
EASA.IM.A.S.02891	THE BOEING COMPANY - WICHITA DIVISION			B747-200B	Conversion of Passenger Airplane to Main Deck Side Cargo Door Dedicated Special Freighter as defined by FAA approved Boeing Document D800-10610-7, Revision New or later FAA approved revisions. (Validation of FAA STC ST00252WI-D)		FAA Approved Airplane Flight Manual Supplement to Airplane Flight Manual D6-35747 for Boeing Model 747-200B.D6-30680 B747-200 Cargo Loading Manual.	FAA Approved Airplane Flight Manual Supplement to Airplane Flight Manual D6-35747 for Boeing Model 747-200B is requiredto support this modification of applicable airplanes as identified in table 1 of Boeing Doc. D800-10610-7, Rev. New or later FAA approved revisions.Cargo Loading Manual D6-30680 is...	06/10/2008	Active	10016519
EASA.IM.A.S.02892	GULFSTREAM SERVICES CORPORATION		FAA STC ST03565AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4122.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC414914122 Rev. F, dated August 1, 2008or later approved revisions.	Aircraft Serial Number 4122 only.The following STC's are a required part of this STC:ST03027AT-DST02987AT-DST03047AT-DST02980AT-DST03290AT-DST03532AT-DST03238AT-DST02979AT-DIt is the installer's responsability to ensure these STC's are allEASA approved.	06/08/2008	Active	10016520

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02893	GULFSTREAM SERVICES CORPORATION		FAA STC ST03449AT-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5155.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514915155, Rev. F, dated September25, 2007 orlater FAA approved revision.	Aircraft Serial Number 5155 only:the following STC's are a required part of this STC:ST02796AT-DST02697AT-DST02715AT-DST03290AT-DST01775LA-DST02696AT-DST00892LAIn addition, this STC must be installed in conjunction with Cabin Modification STC ST02089LA-D to fully meet EASA Requirements.It is the ins...	05/08/2008	Active	10016521
EASA.IM.A.S.02895	FLYHT AEROSPACE SOLUTIONS Ltd.		TCCA STC SA07-124	BOEING 767-300 BOEING 767-200	AFIRS 220 Automated Flight Information Reporting System installation with Optional Global Voice and Global Satellite Communication		AMS Master Document List, Ref. 121-0039 Rev. B, Dated 3 July 2008.AMS Installation Instructions, Ref. 151-0030 Rev. A, Dated 12 November 2007	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	19/08/2008	Active	10016522
EASA.IM.A.S.02897	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA7049SW-D	MYSTERE FALCON 900	Installation of Electrical FeedThru in Pressure Vessel.		FAA STC: SA7049SW-D, Revision 10, dated 05 Aug 1994.DrawingList No.: F90-01048, Revision N, dated 19 July 1994.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016524
EASA.IM.A.S.02898	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA7056SW-D	MYSTERE FALCON 900	Installation of Automatic Cabin Electrical Load Shed System.		FAA STC: SA7056SW-D, Revision 6, dated 17 Dec 2000.Drawing List No.: F90-01012, Revision K, dated 12 Dec 2000.For 501 Installation -AFM Supplement No.: 35888-1, Revision B, dated06 Jan 1988.For 503 or 505 Installation -AFM Supplement No.: 35888-2, Revision A, dated 17 Dec 2000.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016525
EASA.IM.A.S.02899	DASSAULT FALCON JET CORP.(SERVICE CENTER)	REV 1	FAA STC SA7060SW-D	MYSTERE FALCON 900	Installation of Basic Interior Furnishings.		FAA STC: SA7060SW-D, Revision 68, dated 07 Dec 1996Drawing List No.: F90-01007, Revision F, dated 06 Dec 1996Maintenance of Pocket Door Assembly: 36343 dated 28 Feb 1994.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016526
EASA.IM.A.S.02900	DASSAULT FALCON JET CORP.(SERVICE CENTER)	REV 1	FAA STC SA7062SW-D	MYSTERE FALCON 900	Installation of Basic Oxygen System.		FAA STC: SA7062SW-D, Revision 4, dated 07 Dec 1996Drawing List No.: F90-01009, Revision R, dated 04 Dec 1996.AFM Supplement No.: 36103-1, dated 20 Jan 1989.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016527
EASA.IM.A.S.02901	DASSAULT FALCON JET CORP.(SERVICE CENTER)	REV 1	FAA STC SA7085SW-D	MYSTERE FALCON 900	Installation of Avionics Rack.		FAA STC: SA7085SW-D, Revision 13, dated 19 Oct 1994Drawing List No.: F90-01020, Revision AC, dated 21 July 1994.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016528

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02902	DASSAULT FALCON JET CORP.(SERVICE CENTER)	REV 1	FAA STC SA7123SW-D	MYSTERE FALCON 900	Installation of APU Fault Panel Installation.		FAA STC: SA7123SW-D, Revision 1, dated 20 Sep 1991.Drawing List No.: F90-01024, Revision C, dated 12 Aug 1991.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016529
EASA.IM.A.S.02903	DASSAULT FALCON JET CORP.(SERVICE CENTER)	REV 1	FAA STC SA7239SW-D	MYSTERE FALCON 900	Installation of Emergency Power Supply System.		FAA STC: SA7239SW-D, Revision 3, dated 08 Nov 2000.Drawing List No.: F90-01036, Revision E, dated 03 Nov 2000.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016530
EASA.IM.A.S.02904	DASSAULT FALCON JET CORP.(SERVICE CENTER)	REV 1	FAA STC SA7227SW-D	MYSTERE FALCON 900	Installation of Air Distribution System Modification.		FAA STC: SA7227SW-D, Revision 4, dated 09 Sep 1991.Drawing List No.: F90-01031, Revision T, dated 26 Jun 1991.AFM Supplement No.: 36098-1, dated 20 Jan 1989.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	23/06/2008	Active	10016531
EASA.IM.A.S.02905	DASSAULT FALCON JET CORP.(SERVICE CENTER)	REV 1	FAA STC ST09308SC-D	MYSTERE FALCON 900	Installation of FMZ-2000 Flight Management System.		FAA STC: ST09308SC-D, Revision 2, dated 25 Aug 2003Drawing List No.: F90-01082, Revision C, dated 15 Jul 2003For 501 Installation -AFM Supplement No.: 36729-1, dated 13 Dec 1999For 503 Installation -AFM Supplement No.: 36729-2, dated 16 Oct 2001For 505 Installation -AFM Supplement No.: 36729-3, d...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016532
EASA.IM.A.S.02906	DASSAULT FALCON JET CORP.(SERVICE CENTER)	REV 1	FAA STC ST09309SC-D	MYSTERE FALCON 900	Installation of Universal Bracket Attachments.		FAA STC: ST09309SC-D, Revision 0, dated 26 Jan 2000.DrawingList No.: F90-01081, Revision A, dated 20 Jan 2000.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	23/06/2008	Active	10016533
EASA.IM.A.S.02907	WESTERN PROPELLER (PACIFIC) Ltd.		FAA TC A37CE	CESSNA 208A, 208B	Installation of a modified McCauley 3GFR34C703 Propeller incorporating aZero Latch System.	CS-23.B NSC	Installation accordance with Cessna Manual P/N D2077-13.Operation must be in accordance with Western Propeller Company Ltd.Aircraft Flight Manual Supplement WPL-C703-5 Re. A, dated 7th May 2001or later approved revision.	none	23/07/2009	Active	10029049
EASA.IM.A.S.02911	GULFSTREAM SERVICES CORPORATION		FAA STC ST03579AT-D	GULFSTREAM GIV-X	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 4123.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List GC414914123 Rev. C, dated July 31, 2008 or later approved revisions.	1. Aircraft Serial Number 4123 only:2. The following STCs are a required part of this STC:- ST03027AT-D- ST02987AT-D- ST03047AT-D- ST02980AT-D- ST03290AT-D- ST03532AT-D- ST03238AT-D- ST02979AT-DIt is the installer's responsibility to ensure that these STCs are all EASA3...	07/08/2008	Active	10016534

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02913	SAVANNAH AIR CENTER, L.L.C.		FAA STC SA02683AT, CAA UK AAN	GULFSTREAM IV	Installation of L3 Communications Digital Flight Data Recorder With Teledyne Digital Flight Data Acquisition Unit.		To be operated in accordance with Approved Flight Manual supplemet ref GIV1132-AFMS-001, dated July 9, 2003, or later approved revision	Only approved for Aircraft manufactured before 18 August 2000	03/06/2008	Active	10016536
EASA.IM.A.S.02914	MACHINING PROGRAMMING MANUFACTURIN GInc.		FAA STC SA01033WI	SEE EASA APPROVED MODEL LIST	Replacement of original main landing gear doors with one piece monolithic machined gear doors.		Installation in accordance with FAA approved, MPM Inc, Installation Drawing ref. LG-DR002 revision "none" or later approved revisions	1. The attached AML is applicable only on aircraft serial numbers called out in MPM Inc Drawing No AML-LG-DR002-1, -2, -3 and -4for installation and applicability.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and...	05/06/2008	Active	10016537
EASA.IM.A.S.02915	MACHINING PROGRAMMING MANUFACTURIN GInc.		FAA STC SA00902WI	SEE EASA APPROVED MODEL LIST	Replacement of original main landing gear doors with monolithic machined gear doors.		Installation in accordance with FAA approved, MPM Inc, Installation Drawing ref. LG-DR0021 and Installation Instructions MPMI-103 on aircraft listed in the attached Approved ModelList (AML) in MPM Inc, Drawing Number AML-LG-DR0001, Rev A,dated November 27, 2000, or later approved revision.	1. The attached AML is applicable only on aircraft serial numbers called out in MPM Inc Drawing No. AML-LG-DR0011. The attached AML is applicable only on aircraft serial numbers called out in MPM Inc Drawing No. AML-LG-DR001.2. Priorto installation of this modification the installer must dete...	10/06/2008	Active	10016538
EASA.IM.A.S.02916	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02089LA-D	GULFSTREAM GV-SP	Installation of Cabin Interior Modification for Aircraft Serial 5155.		Install in accordance with Gulfstream Aerospace Report GC52000K569, Rev. N/C dated 29 July 2008 and Index List GC520008627 Rev. D, dated 28 July 2008, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M091, Revision N/C, dated 28 July 2008.	Aircraft Serial Number 5155 only.	04/08/2008	Active	10016539
EASA.IM.A.S.02917	DELTA ENGINEERING CORPORATION		FAA STC ST02402NY-D	AIRBUS A320	Panasonic IFE a eFXInstallation of Panasonic eFX systemEASAvalidation of FAA STC No. ST02402NY-D from 28. March 2008.		FAA STC No. ST02402NY-D, from 28. March 2008Delta Engineering Master Data List 0164-06179-2165 Revision -, from 15. March 2008, applicable for A320-200 seriesor later revisions ofthe above listed documents approved by EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of t...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.1 The installation of this modification by third pers...	16/07/2008	Active	10016540
EASA.IM.A.S.02919	JAMCO AMERICA, INC.		FAA STC ST00240SE ; P. GILLESP	BOEING 747-200	Installation of Jamco Galley in accordance with Jamco America Inc. Master Drawing List IA-036, Rev. A dated September 1, 1995, or later approved revisions.		None.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The interior re-arrangement, along with required placard...	16/01/2009	Active	10016541

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02920	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA04-113	BOMBARDIER BD-700-1A10	Interior Completion - ACSN 9234		TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.TCCA SOC letter C-07-0590 dated 03 July 2008.Aero Consulting Services Modification Data Summary D954000 Revision AY dated 15 November 2007.Bombardier Airplane Flight Manual Supplement G-FM25004001 Revision B.Instructions for Continued Airworthiness...	Restricted to ASN 9234 and1. Refer to the Limitations sections of the required AFM Supplement and to the referenced FCOMS.2. WLAN system is compatible only to IEEE 802.11(b).3. Prior to installation of this modification the installer must determine that the interrelationship between this modificatio...	28/07/2008	Active	10016542
EASA.IM.A.S.02921	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA06-43 ISSUE 2	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	Installation of XM Satellite Radio Antenna.		Transport Canada STC No. S06-43 Issue 2 dated 10 November 2006. Transport Canada Statement of Compliance ref. C-06-0865 dated 21 July 2008.Aero Consulting Services Modification Data Summary no. E821000 Revision C dated 20 October 2006 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	22/08/2008	Active	10016543
EASA.IM.A.S.02924	EAD INC.		FAA STC ST01481CH	BOEING 737-400 SERIES	TCAS/Mode-S Activation on Boeing 737-400 Series as approvedunder the STC FAA ST01481CH.		1. Europe Aero Design Master Data List, Doc. No. DC104-0245-00 Rev.2 dated June 26, 2001*2. FAA approved AirplaneFlight Manual Supplement, Europe Aero Design Doc. No. DC353-1493-00 Rev.0 approved June 27, 2001**or later revisions ofthe above listed documents approved by EASA in accordance wi...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	02/10/2008	Active	10016545
EASA.IM.A.S.02925	CANARD AEROSPACE CORPORATION		FAA STC ST01117CH	BOEING 747-SR BOEING 747-SP BOEING 747-300 BOEING 747-200F BOEING 747-200C BOEING 747-200 BOEING 747-100B SUD BOEING 747-100	Option 1: Installation of Honeywell Classic Navigator system in accordance with Canard Aerospace Corporation Control Drawing Nr. 30011, Rev. NC, dated November 25, 2002, Appendix A, or later FAA approved revision.Option 2: Installation of a CMA-900 Flight Management System and Inertial Reference Sys...		Option 1:34-3249-04-NC34-3249-09-NCOption 2: 34-3275-04-B 34-3275-08-E 34-3275-10-NCOption 3:34-3404-06-NC34-3404-07-NCAirplane Flight Manual Supplement Airplane Maintenance Manual SupplementAirplane Flight Manual Supplement Instruction for Continued Airworthiness Airplane Maintenance Manual Supplem...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	12/11/2008	Active	10016546
EASA.IM.A.S.02926	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02091LA-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5193.		Install in accordance with Gulfstream Aerospace Report GC52000K581, Rev. N/C and Index List GC520008613 Rev. H, dated 20 August 2008, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M082, Revision N/C, dated 20 August 2008.	Aircraft Serial Number 5193 only.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of th...	02/09/2008	Active	10016547

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02927	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02093LA-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5198.		Install in accordance with Gulfstream Aerospace Report GC52000K595, Rev. A and Index List GC520008618 Rev. L, dated 11 September 2008, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M084, Revision A, dated 11 September 2008	1. Aircraft Serial Number 5198 only.2. Prior to installation of this modification the installer must determine that theinterrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation...	30/09/2008	Active	10016548
EASA.IM.A.S.02930	HAWKER BEECHCRAFT SERVICES		FAA STC ST01191WI	BEECH 1900D	Installation of Cargo Conversion Modifications.		Installation in accordance with Raytheon Aircraft Services Master Drawing List RAS 0422-1, Revision N, dated July, 1 2003 or later approved revisions.Operation in accordance with Raytheon Aircraft Services Airplane Flight Manual SupplementNumber 05-422, dated August 26, 2003 or later approved revis...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	03/09/2008	Active	10016550
EASA.IM.A.S.02931	HAWKER BEECHCRAFT SERVICES	REV. 1	FAA STC ST00589LA	HAWKER 1000	Installation of AlliedSignal Enhanced Gound Proximity Warning System (EGPWS).		Raytheon Aircraft Services Master Data List for Allied Signal Enhanced Gound Proximity Warning System Installation on Hawker 100A AircraftReport No. RAY-R3-002, Revision "A" datedApril 3, 1998.To determine wihcih configuration(s) or the EGPWS have been approved, refer to the appropriate sections of...	The installation should not be incorporated in any aircraftunless it is determined that the relationship between this installationand any previously approved configuration will not introduce any adverse effect upon the Airworthiness of the Aircraft. The approval of this modification applies to thei...	04/07/2008	Active	10016551
EASA.IM.A.S.02932	SAFRAN CABIN GALLEYS US, INC.			BOEING 747-200C BOEING 747-200B	Installation of a TBO Container.		Driessen Aircraft Interior Systems Data List MDL-101969, Revision "C" dated April 14, 1998.	The installation should not be incorporated in any aircraftunless it is determined that the relationship between this installationand any previously approved configuration will not introduce any adverse effect upon the Airworthiness of the Aircraft. The approval of this modification applies to thei...	04/07/2008	Active	10016552
EASA.IM.A.S.02935	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA ST01837CH	747-300 747-200B, 747-200C, 747-200F	Installation of Honeywell RESCU 406AF/ AFN Emergency LocatorTransmitter (ELT) System.		Armstrong Aerospace Master Data List, Doc. No. DC104-1003-00, Rev. R, dated 20 December 2007 or later approved revision.	Airplane Flight Manual Supplements Armstrong Aerospace Doc.No. DC303-1003-00, Rev.C, approved 4 February 2008 or laterapproved revision is required on board of the modified aircraft.Instruction for Continued Airworthiness, Armstron Aerospace Doc. No. DC133-1003-00, Section 2, rev. H, dated 20 Dece...	12/09/2008	Active	10016553

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02936	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA ST02536CH	A330-341, A330-342, A330-343 A330-321, A330-322, A330-323 A330-301, A330-302, A330-303	Activation of Honeywell Runway Awareness and Advisory System (RAAS).		• FAA STC ST02536CH, issued 17th March 2008• Armstrong Aerospace Master Data List, ref. Doc. No. DC104-5030-00, Rev. A, dated 4th February 2008 or later revisions approvedbyEASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).• Airplane Flight Manu...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.	03/09/2008	Active	10016554
EASA.IM.A.S.02937	ARMSTRONG AEROSPACE Inc.dba ASTRONICS ARMSTRONG AEROSPACE		FAA ST02537CH	A340-642 A340-311, A340-312, A340-313	Activation of Honeywell Runway Awareness and Advisory System(RAAS)		• FAA STC ST02537CH, issued 17th March 2008• Armstrong Aerospace Master Data List, ref. Doc. No. DC104-5031-00, Rev. A, dated 4th February 2008 or later revisions approvedbyEASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).• Airplane Flight Manu...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	08/01/2009	Active	10016555
EASA.IM.A.S.02940	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10338SC-D	GULFSTREAM G150	Installation of an Emergency Power/ Annunciator System i.a.w. Gulfstream Index List GA313318000, Rev. B or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		ICA GA34331A000AFMS GA31331M000	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	29/07/2008	Active	10016556
EASA.IM.A.S.02941	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10303SC-D	GULFSTREAM 200	Installation of an XM Satellite Radio System i.a.w. Index list GA216078000, Rev. A. or later approved revisions of the aforementioned document approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of thisdecision).		ICA GA 24607A000	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	29/07/2008	Active	10016557
EASA.IM.A.S.02942	MICRO AERODYNAMICS, INC.	REV 1	FAA STC SA00834SE	CESSNA TR182 CESSNA T182T CESSNA R182 CESSNA R172E/F/G/H/J/K CESSNA FR-182 CESSNA FR-172-K CESSNA FR-172-J CESSNA FR-172-H CESSNA FR-172-G CESSNA FR-172-F CESSNA FR-172-E CESSNA F182-Q CESSNA F182-P CESSNA 182T CESSNA 182S CESSNA 182R CESSNA 182Q CESSNA 182P CESSNA 182N CESSNA 182M CESSNA 182L CESSNA 182K CESSNA 182J CESSNA 182H CESSNA 182G CESSNA 182F CESSNA 182E CESSNA 182D CESSNA 182C	Installation of vortex generators on the wings and tail surfaces in accordance with the provisions of AML SA00834SE.		Approval of this change in type design applies to the aircraft listed on AML SA00834SE only. This approval should not be extended to other aircraft on which other previously approved modification are incorporated unless it is determined that the relationship between this change and any other previou...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modificationand any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. 2. The installation of this modification b...	27/10/2008	Active	10016558

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02945	GULFSTREAM SERVICES CORPORATION		FAA STC ST03587AT-D	GULFSTREAM GIV-X	Installation of an Airplane Interior for Aircraft Serial 4130.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC414914130 Rev E, dated October 1, 2008, or later approved revisions.	Aircraft Serial Number 4130 only.The following STCs are a required part of this STC:ST03027AT-DST02987AT-DST03047AT-DST02980AT-DST03290AT-DST03532AT-DST02979AT-DIt is the installers responsibility to ensure these STCs are all EASA approved.Prior to installation of this modification the installer mus...	16/10/2008	Active	10016560
EASA.IM.A.S.02946	GULFSTREAM SERVICES CORPORATION		FAA STC ST03592AT-D	GULFSTREAM GV-SP	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5201.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514915201, Rev. G, dated October 22, 2008 or later approved revision.To be operated in accordance with FAA approved Airplane Flight Manual Supplement, refGC51501M029, Rev NC, dated 22 October 2008 orlater approved...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsA...	04/11/2008	Active	10016561
EASA.IM.A.S.02948	INFINION CERTIFICATION ENGINEERING	REV. 1	TCCA STC SA06-30	BAE JETSTREAM 3100	Concorde RG-380 Battery Installation.		• Master Data List: MDL-1090-01;• Installation Instructions EO-1090-01;• Flight Manual Supplement FMS01090-01;• Technical Note: Substantiation of Battery Replacement. TN-1063-01;• Compliance Program: CP-1090-01;• Maintenance Manual Supplement MMS-1090-01.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	16/09/2008	Active	10016562
EASA.IM.A.S.02954	CASCADE AEROSPACE Inc.		TCCA STC NUMBER SA08-91	BOMBARDIER DHC-8-400 SERIES	DHC-8-400 Conversion to Bulk FreighterTCCA STC Number SA08-91, Issue 1, dated 31 December 2008		Installation of the freighter conversion must be in accordance with Cascade Aerospace Inc. EO 4079, Rev. 2, TCCA approved 12 December 2008 and Master Document List MDL 4079, Rev.2, TCCA approved 24 December 2008 *).Operation of the aircraft must be in accordance with Cascade Aerospace Inc. Flight Ma...	1 Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.1 The installation of this modificat...	29/01/2009	Active	10016563
EASA.IM.A.S.02955	B/E AEROSPACE, Inc. - FSI		FAA ST00386SE	747-200	This design change relocates the E/E Bay Acces Hatch on themain deck floor and Installs Gari o Handling System Provisions for a 30pallet main deck cargo configuration per Flight Structures, Inc.		Master Drawing list 96fS624-D01 at Revision E dated September 18, 2003, or later FAA approved revisions.	This STC can only be installed in aircraft with FAA STC SA2725CE-D or STC ST00255WI-D or STC ST00252WI-D or STC ST00214SE installed.	18/09/2008	Active	10016564
EASA.IM.A.S.02957	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA03-372/D	BOMBARDIER BD-700-1A10	Aircraft Completion, 13 Passenger Interior Configuration		Transport Canada SoC ref. C-08-0754 dated 13 November 2008.Transport Canada STC No. C-LSA03-372/D Issue 2 dated 13 November 2008.Aero Consulting Services Modification Data SummaryD583000 Revision A dated 13 November 2008 or later approvedrevision.Required Flight Manual SupplementsThe following app...	1. Restricted to ASN 9120.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this mo...	15/12/2008	Active	10016566

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02958	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA01-417/D	BOMBARDIER BD-700-1A10	Approval of Side Facing Divan Limitations.		Transport Canada STC No. C-LSA01-417/D Issue 2 dated 16 January 2004.TCCA SOC reference C-04-0040 dated 16 September 2008.Aero Consulting Services Modification Data Summary No. D14000 Revision A or later approved revision.Aero Consulting Services Flight Manual Supplement D14091 Rev A or later approv...	Restricted to ASN 9016.Required Equipment:Previous installation of corresponding EASA STC No. EASA.IM.A.S.01252 (FAA STC SA8164NM-D).Prior to installation of this modification theinstaller must determine that the interrelationship betweenthis modification and any other previously installed modific...	19/09/2008	Active	10016567
EASA.IM.A.S.02959	GULFSTREAM SERVICES CORPORATION		FAA STC ST03007AT-D	GV	Installation of Honeywell Integrate Avionics Computers (IAC) with Software Version NZ 6.0.		Installation of Honeywell Integrated Avionics Computers (IAC) with Software Version NZ 6.0 for -501 and -503 configurations in accordance with Gulfstream Aerospace Corporation Index List CE51 1188001 Rev. D or later approved.Operation in accordance with Gulfstream Airplane Flight Manual Supplement C...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	02/10/2008	Active	10016568
EASA.IM.A.S.02960	GULFSTREAM SERVICES CORPORATION		FAA STC ST03074AT-D	GV	Installation of Honeywell NZ-2000 Third FMS Computer with Software Version NZ 6.0.		Installation of Honeywell NZ-2000 Third FMS Computer with Software Version NZ 6.0 in accordance with Gulfstream Aerospace Coporation Index List CE51 3088000 Rev C or later approved.Operation to be in accordance with Gulfstream Airplane Flight Manual Supplement CE51 308M000 Rev. NC Dated April 15, 20...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	02/10/2008	Active	10016569
EASA.IM.A.S.02963	COMTRAN INTERNATIONAL, INC.		FAA STC SA00664DE	DORNIER 328-300	Cabin Interior Re-Configuration Domier 328-300		-STC FAA ST00664DEComtram International Documents:-Master Document List 001-MDL001, Rev. C dated March 20, 2008*-MasterDocument List 001-MDL002, Rev. A dated March 28, 2008*-Flight Manual Supplement 001-FM001, Rev. IR FAA approved May, 222008*-Instructions for Continued Airworthiness OOI-ICAOOI an...	None	29/07/2009	Active	10034405
EASA.IM.A.S.02967	LEARJET Inc.		FAA STC ST00994WI-D	LEARJET 60	Cockpit Speaker Mute FunctionFAA STC ST00994WI-D		As per Master Document List M100339ICT, rev. G (or later approved revisions)	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	06/10/2008	Active	10016570

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02970	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA03-334/D	BOMBARDIER BD-700-1A10	Installation of interior furnishings and cabin systems, applicable to BD-700-1A10 serial number 9112 only.		TCCA STC No. C-LSA03-334/D Issue 2 dated 06 October 2003.TCCA SOC Reference C-08-0755 dated 16 September 2008.Aero Consulting Services Modification Data Summary D42500 Revision B or later approved revision.The following Flight Manual Supplements are required:G-FM24000039 Rev N/C* Cabin Ma...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product. The installation of this modification by third person...	02/10/2008	Active	10016572
EASA.IM.A.S.02971	BOMBARDIER COMPLETION CENTRE INC		TCCA STC C-LSA05-100/D	BOMBARDIER BD-700-1A10	Relocation of Aft Toilet Compressor.		Transport Canada STC No. C-LSA05-100/D Issue 1 dated 17 March 2005.TCCA SOC reference C-08-0755 dated 16 September 2008.Aero Consulting Services Modification Data Summary No. E395000 Revision N/C dated 17 March 2005 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	19/09/2008	Active	10016573
EASA.IM.A.S.02972	LEARJET Inc.		FAA STC ST01421WI-D	LEARJET 60	Airshow 410 System		As per Master Data List M100475ICT, rev. P. (or later approved revisions).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	16/09/2008	Active	10016574
EASA.IM.A.S.02973	LEARJET Inc.		FAA STC ST01424WI-D	LEARJET 60	Emergency power supply 1		As per master Data List M100487ICT, rev. M (or later approved revisions).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	16/09/2008	Active	10016575
EASA.IM.A.S.02975	HAWKER BEECHCRAFT CORPORATION (HBC)		FAA STC ST02113LA	BEECH 400A	Rockwell Collins dual Attitude Heading Reference system (AHRS).		None.	Cutter aviation Master Data List Document No. 02A-2406-201,Revision “B” dated December 5, 2007 or later approved revisions.	12/09/2008	Active	10016577
EASA.IM.A.S.02983	RAISBECK ENGINEERING Inc.		FAA STC SA2939NM	BEECH C90A BEECH C90 BEECH B90 BEECH 65-A90 BEECH 65-90	Installation of nacelle overwing storage lockers and lower flap fairing.		1. Installation Manual 006-1007 Rev. B, dated December 12th, 2007;2. Installation Manual 006-1008 Rev. A, dated October 4th, 2006;3. Installation Manual 85-1007 Rev. I., dated April 27, 2007;4. Approved Flight Manual Supplement85-101 Rev. E dated January 18, 2008;5. Instruction for c...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/08/2008	Active	10016579
EASA.IM.A.S.02985	RAISBECK ENGINEERING Inc.		FAA STC SA3831NM	BEECH B200T BEECH B200CT BEECH B200C BEECH B200 BEECH A200CT BEECH A200C BEECH A200 BEECH 200CT BEECH 200C BEECH 200	Installation of improved leading edge consisting of inboardleading edges, deice boots, leading edge ducts, leading edge to nacellefairing, and associated hardware.		1. Installed in accordance with Raisbeck installation manual Installation Manual R81-1022, Rev. F, dated January 30th 2008;2. Instructions for Continued Airworthiness Ref. Raisbeck Maintenance Manual 85-120 Rev. G. dated January 2008;3. IPC 85-119 dated April 2004,Or later approved revision...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/08/2008	Active	10016581

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02988	RAISBECK ENGINEERING Inc.		FAA STC SA3366NM	B200T B200GT B200CT B200CGT B200C B200 A200CT A200C A200 200T 200CT 200C 200	Installation of Ram Air Recovery System.		1. Installed in accordance with Raisbeck installation manual Installation Manual R81-1021 Rev. I, dated February 8, 2006;2. Approved Flight Manual Supplement 99-117 RevisionA, dated February 1, 2008;3. Instruction for Continued Airworthiness ref. Raisbeck Maintenance Manual 85-120 Rev. G.4...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsT...	05/08/2008	Active	10016583
EASA.IM.A.S.02989	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10035SC-D	GULFSTREAM 200	Installation of Executive Cabin Interior i.a.w. Gulfstream Index List GA220008063, Rev. A or later revisions of this document approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		ICA GA22801A063AFMS GA21468M063	Limited to S/N 063	20/08/2008	Active	10016584
EASA.IM.A.S.02990	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC SA8271SW-D	FALCON 900EX	EASA Validation of FAA STC SA8271SW-DInstallation of the APU Fault Panel Installation i.a.w. Drawing List Report No. F9EX-01007 dated 08th October 1996 or later revisions approvedby EASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or subsequent revisions to these decisions)		See those of original FAA STC SA8271SW-Dor later revisions of these documents approved by EASA i.a.w. EASA ED Decisions2007/001/C and 2004/04/CF (or subsequent revisions to thesedecisions).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of theproduct.¿ The installation of this modification by thirdd...	27/03/2009	Active	10016585
EASA.IM.A.S.02991	DASSAULT FALCON JET CORPORATION		FAA STC ST09313SC-D	FALCON 900EX	EASA Validation of FAA STC ST09313SC-D Revision 1, 01st October 2002Installation of Standby Horizon System Modifications in accordance with Drawing List Report No. F9EX-01035 Revision B dated 25 September 2002 or later revisions approved by EASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or...		EASA Approved Airplane Flight Manual Supplement, Report No.37037-1, Revision Original dated 01st October 2002 for the F9EX-01035-503 installation.In addition see those of original FAA STC ST09313SC-D Revision 1 as amended on 01st October 2002.or later revisions of these documents approved by EASA i...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	02/04/2009	Active	10016586
EASA.IM.A.S.02992	DASSAULT FALCON JET CORPORATION		FAA STC ST09311SC-D	FALCON 900EX	EASA Validation of FAA STC ST09311SC-DInstallation of the Inertial Reference System Modification in accordance with Drawing List Report No. F9EX-01033 Revision NC dated 04th May 2000 or later revisions approved by EASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or subsequent revisions to th...		See those of original FAA STC ST09311SC-D.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	20/03/2009	Active	10016587
EASA.IM.A.S.02994	DASSAULT FALCON JET CORPORATION		FAA STC SA8291SW-D	FALCON 900EX	EASA Validation of FAA STC SA8291SW-DInstallation of the Battery Installations i.a.w. Drawing List Report No. F9EX-010003 Revision F dated 14 September 2000 or later revisions approved by EASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or subsequent revisions to these decisions)		EASA Approved Airplane Flight Manual Supplement, Report No.36558-1, dated 01st May 1997 and Airplane Maintenance Manual Supplement, Report No. 36575 dated 09th June 1997, for theF9EX-01003-501 installation.EASA Approved Airplane Flight Manual Supplement, Report No. 36558-2, dated 15th October 1999...	1. The F9EX-01003-503 and F9EX-01003-507 installations are limited to aircraft serial number 049.2. Prior to installation of this modification the installer must determine that the interrelationship between this modificationand any other previously installed modification will introduce no ad...	18/03/2009	Active	10016588

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.02995	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC ST09312SC-D	FALCON 900EX	EASA Validation of FAA STC ST09312SC-DInstallation of the Engine Instrument Display System Modification in accordance with Drawing List Report No. F9EX-1034 Revision NC dated 04thMay 2000 or later revisions approved by EASA i.a.w. EASA EDDecisions 2007/001/C and 2004/04/CF (or subsequent revisions...		See those of original FAA STC ST09312SC-Dor later revisionsof these documents approved by EASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or subsequent revisions to these decisions).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	24/03/2009	Active	10016589
EASA.IM.A.S.02998	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC SA8275SW-D	FALCON 900EX					16/07/2009	Active	10028777
EASA.IM.A.S.03001	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA04-113	BOMBARDIER BD-700-1A10	Customized Interior Completion - ACSN 9270.		TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.TCCA SOC reference C-08-0433 dated 17 November 2008.Aero ConsultingServices Configuration Deviation List D954000 Revision BX dated 14 November 2008.Instructions for Continued Airworthiness GC92700000-IFCA.	Restricted to ASN 9270 and1. Refer to the Limitations sections of the required AFM Supplement and to the referenced FCOMS.2.WLAN system is compatible only to IEEE 802.11(b).3.Prior to installation of this modification the installer must determine that the interrelationship between this modificationn...	21/11/2008	Active	10016591
EASA.IM.A.S.03003	FLINT AERO, INC.			CESSNA TR182 CESSNA T182, T182T CESSNA R182 CESSNA 182T CESSNA 182S CESSNA 182R CESSNA 182Q CESSNA 182P CESSNA 182N CESSNA 182M CESSNA 182K CESSNA 182J CESSNA 182G CESSNA 182F CESSNA 182E CESSNA 182D CESSNA 182C CESSNA 182B CESSNA 182A CESSNA 182	Auxiliary Internal Wing Fuel Tanks.This STC is a revision of LBA STC SA 1305, dated 14 January 2003.		None.	None.	15/08/2008	Active	10016592
EASA.IM.A.S.03004	BOMBARDIER COMPLETION CENTRE INC	REV. 1	TCCA STC SA07-019	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	Waterproofing and Spill Management, Interior Modifications		TCCA STC No. SA07-19 Issue 3 dated 25 July 2008.TCCA SoC reference NAI5012-07-0177 dated 27 February 2009.Kmlex Aviation Inc. Master Document List - Water Proofing and Spill Management, Interior Modifications - Bombardier BD-700 Aircraft, Document No. MDL26141002, Revision F, dated 27 January 2009 o...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	16/03/2009	Active	10016593
EASA.IM.A.S.03005	U.S. TECHNICAL CONSULTANTS, INC.		FAA STC ST02409CH-D	DC-9-87 (MD-87) DC-9-83 (MD-83)	FAA STC No. ST02409CH-D “NavAero t-BagC22 Electronic FlightBag”		MDL 4696-23-000 Rev. F dated 13 August 2007FM Supplement U10-0163 dated 6 November 2007	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	16/01/2009	Active	10016594

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03006	MITSUBISHI HEAVY INDUSTRIES AMERICAINC.		FAA STC SA1751SW	MU-2B, -10, -15, -20, -25, -26 -60 -26A, -30, -35, -36, -36A, -40	Flight Crew Restraint System.		FAA STC SA1751SW	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	22/09/2008	Active	10016595
EASA.IM.A.S.03007	GULFSTREAM SERVICES CORPORATION		FAA STC ST03610AT-D	GULFSTREAM GV-SP GULFSTREAM G550	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5204.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514915204, Rev. F, dated November 4, 2008 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsA...	24/11/2008	Active	10016596
EASA.IM.A.S.03009	GULFSTREAM SERVICES CORPORATION		FAA STC ST03511AT-D	GULFSTREAM G150	Installation of Concorde Valve Regulated Lead Acid Main Batteries.		- Install in accordance with Gulfstream Aerospace Corporation Index List, CEC1 4448000 Rev C, dated December 13, 2007, or later approved revisions.- Operation in accordance with Gulfstream Aerospace Corporation Airplane Flight ManualSupplement, CEC1 444M000 Rev NC, dated January 03, 2008, or...	None.	18/02/2009	Active	10016597
EASA.IM.A.S.03013	LEARJET Inc.		FAA STC ST10380SC	BOMBARDIER BD-700-1A10	Replacement of Low Back Seats with High Back Seats.		- FAA SoC dated 22 December 2008.- FAA STC No. ST10380SC Issue 1 dated 14 February 2005.- Learjet Inc. Master Document List, Document Number BAS67010032, Revision NC, dated 11 February 2005 or later approved revision.- Learjet Inc. Airplane Flight Manual Supplement, Document Number BAS67...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	23/12/2008	Active	10016600
EASA.IM.A.S.03015	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST01154SE	B747-200B	Installation of interior components in accordance with Britax Heath Tecna Inc. (BHT) Drawing List HPD-DL-81 Revision B,dated December 12, 2002 or later FAA approved revisions		Instructions for Continued Airworthines Britax Heath Tecna Inc. HTM857	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	16/03/2009	Active	10016601
EASA.IM.A.S.03016	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02097LA-D	GULFSTREAM G550	Installation of Custom Cabin Interior and Aircraft Completion for Aircraft Serial 5203.		Install in accordance with Gulfstream Aerospace Report GC52000K607 Rev. - , and Index List GC520008622 Rev. J, dated 17Nov 08, or later approved revisions.Operate in accordance with Gulfstream Aerospace Flight Manual Supplement GC52000M086 Revision - , dated 17 Nov 08.	1. Aircraft Serial Number 5203 only.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The instal...	02/12/2008	Active	10016602

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03017	FIELD AVIATION COMPANY INC.		TCCA STC SA01-55	BOMBARDIER DHC-8-402 BOMBARDIER DHC-8-401 BOMBARDIER DHC-8-400 SERIES	Installation of Variable Position Cabin Class Divider.		1. Bin Mount Type :- Installation in accordance with Field Aviation Company Inc. Drawing 17342505, Original Issue, dated 5 April 2001 *);- Maintenance must be performed in accordance with Field Aviation Company Inc. Component Maintenance Manual Supplement 173432, Revision A, dated 7 Mai 200...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product;2. The installation of this modification by thi...	28/08/2008	Active	10016603
EASA.IM.A.S.03019	S-TEC CORPORATION		FAA STC SA09257AC-D	PIPER PA-28-235 PIPER PA-28-180 PIPER PA-28-160 PIPER PA-28-150 PIPER PA-28-140	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST-712 (14 Volt System)		FAA approved S-TEC Bulletin No.812, dated 08-July-1997, Initial Issue, or later approved revisionFAA approved S-TEC Master Drawing List No. 921012, dated 08-July-1997, Initial Issue or later approved revisionFAA/DAS Approved Pilot's Operating Handbook and/or Airplane Flight Manual Supplement, P/N 89...	1 Prior to installation of this modification the installer must verify the availability of EASA approval for one or more mentioned STC(s) when the product is modified per that/ those STC(s).1 Prior to installation of this modificationthe installer must determine that the interrelationshipn...	14/01/2009	Active	10016604
EASA.IM.A.S.03022	B/E AEROSPACE LIMITED		TCCA SA00-109, ISSUE 4	DHC-8-200 DHC-8-102, DHC-8-103	Installation of Enviromental Control System, Low Temperature Limit System (Cold Clamp)Ref. TCCA STC SA00-109, Issue 4, dated 19. October 2000		Modification has to be completed in accordance with ACS Modifcation Data Summary, C 46400, Rev. G, dated 05. July 2008*ACS Maintenance Manual Supplement , C46481, Rev. A, dated 15. January 2001*or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 200...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	19/12/2008	Active	10016605
EASA.IM.A.S.03023	B/E AEROSPACE LIMITED		TCCA SA02-4, ISSUE 1	CL-600-2B19	Installation of NAI part C93602 Solid State Logo Light		Transport Canada STC No. SA02-4 Issue 1 dated 9 January 2002.Transport Canada SOC Reference C-07-0114 dated 9 October 2008.Aero Consulting Services Modification Data Summary No. C93600 Revision B or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	14/10/2008	Active	10016606
EASA.IM.A.S.03024	GULFSTREAM SERVICES CORPORATION		FAA STC ST03617AT-D	GULFSTREAM GIV-X	Installation of Export Modifications for Aircraft Serial 4091.		Install in accordance with Gulfstream Aerospace CorporationExport Modifications Index List, GC420008128, Rev C, dated October 7, 2008, or later approved revisions.	1. Aircraft Serial Number 4091 only.2. This STC must be installed in conjunction with Airplane Completion STC ST03477AT-D (EASA.IM.A.S. 03025) to fully meet EASA requirements.3. Itis the installers' responsibility to ensure these STC's areall EASA approved.4. Prior to installation of this modificat...	15/10/2008	Active	10016607
EASA.IM.A.S.03025	GULFSTREAM SERVICES CORPORATION		FAA STC ST03477AT-D	GULFSTREAM GIV-X	Airplane Completion and Custom Cabin Installation for Aircraft Serial 4091.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC414914091 Rev C, dated October 30, 2007, or later approved revisions.	Aircraft Serial Number 4091 only.The following STCs are a required part of this STC:ST03027AT-DST02987AT-DST03047AT-DST02980AT-DST03290AT-DST02979AT-DST00892LAAdditionally, this STC must be installed in conjunction with Export ModificationSTC ST03617AT-D (EASA.IM.A.S.03024) to fully meet EASA requi...	15/10/2008	Active	10016608

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03029	INFLIGHT CANADA Inc.		TCCA STC O-LSA03-127/D	BOMBARDIER CL-600-2B19	Honeywell SCS-1000 Mini-M Aero SATCOM System and Securaplane Camera Installation.		- Transport Canada SoC ref. 5010-O-08-0561 dated 22 October2008.- Transport Canada STC No. O-LSA-03-127/D Issue 3 dated 16 October 2004.	1. DECA Aviation / Inflight Canada Modification Summary MS03055, Revision 4, dated 16 October 2004, or later approved revision.2. DECA Aviation / Inflight Canada Instructions for Continued Airworthiness ICA03055, Revision 2, dated 12October 2004, or later accepted revision.3. Prior to inst...	04/12/2008	Active	10016609
EASA.IM.A.S.03031	LEARJET Inc.		FAA STC ST01370WI-D	LEARJET 60	Honeywell HF Communication System.		As per Master Document List M100457ICT, rev. V or later revisions approved by EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).	1. Prior to installation of this modification the installermust determine that the interrelationship between this modificationand any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. 2. The installation of this modification b...	27/10/2008	Active	10016611
EASA.IM.A.S.03032	THUNDER AVIATION SERVICES INC.		FAA STC ST01659LA	MYSTERE-FALCON 20-E5, F5 MYSTERE-FALCON 20-C5, 2-D5 FAN JET FALCON SERIES C, D, E FAN JET FALCON	EASA Validation of FAA STC ST01659LAInstallation of Rosemount Pitot-Static Probes, Part Numbers 0856LR1 and0856LR2 and Honeywell Air Data System comprised of dual AZ-252 Air DataComputers, dual BA-250 Altimeter Displays and AL-800 AltitudeAlerteri.a.w. Thunder Aviation N.A. Inc Master Drawing List...		·,,FAA STC ST01659LA, as per FAA amendment 04th September 2007 *·,,Thunder Aviation N.A. Inc Master Drawing List 20-0100 Revision Ldated 17th May 2007 *·,,For Aeroplanes equipped with Collins Model AP-105 Autopilot see *:-,,EASA Approved Thunder Aviation Aeroplane Flight Manual SupplementsFTA-TH-002...	none	18/05/2009	Active	10043078
EASA.IM.A.S.03033	B/E AEROSPACE LIMITED		TCCA C-LSA08-268/D	BD-700-1A10	Installation, Side Facing Divan, S/N 9260 Configuration		TCCA STC No. C-LSA08-268/D Issue 1 dated 18 September 2008.TCCA SoC ref. C-08-0759 dated 28 November 2008.Aero Consulting Services Ltd. Modification Data Summary Number F957000 Revision N/C or later approved revision.Aero Consulting Services Ltd. Airplane Flight Manual Supplement F957090 Revision N/...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	13/03/2009	Active	10016612
EASA.IM.A.S.03038	GULFSTREAM SERVICES CORPORATION		FAA STC ST03643AT-D	GULFSTREAM GV-SP	Aircraft completion and Installation of Airplane Interior for Aircraft Serial 5210.		Installation in accordance with Gulfstream Aerospace Corporation Master Index List GC514915210, Rev. G, dated December 10, 2008 or later FAA approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsA...	08/01/2009	Active	10016613
EASA.IM.A.S.03039	ROSEMOUNT AEROSPACE, Inc.		FAA STC ST01474CH	MD-11, MD-11F	Installation of Rosemount Aerospace Model 1833D Pressure Transducer inaccordance with Rosemount Aerospace Master Data List, Document nr.D0130401, Revision C, dated June 1,2001 or later FAA approved revision.		None.	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	04/12/2008	Active	10043061

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03040	UNIVERSAL AVIONICS SYSTEMSCORPORATION	REV. 1	FAA STC ST02012LA	CL-600-2B16 CL-600-2A12 (CL-601) CL-600-1A11 (CL-600)	Installation of Universal Avionics Application Server Unit (ASU). Minorrevision to ASU FAA STC ST02012LA, ESTC EASA.IM.A.S.03040	EASA.IM.A.023	-EASA STC No. EASA.IM.A.S.03040-FAA STC ST02012LA-UniversalAvionics Systems Master Drawing List, Document No.MDL-2006-1004, Revision E, dated 15 January 2009, or later approvedrevision.	Restricted to the following MDL Configurations:-3 Application Server Unit (ASU) (ETSO EASA.IM.210.708) with Dual CursorControl Panels (CCP) (ETSO EASA.IM.210.708) displayed on EFI-890RNavigation Display (ETSO EASA.IM.210.344).-4 Application Server Unit (ASU) (ETSO EASA.IM.210.708) displayed ondual U...	06/07/2009	Active	10016614
EASA.IM.A.S.03041	UNIVERSAL AVIONICS SYSTEMSCORPORATION		FAA STC ST01303LA	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of Universal Avionics UNS-1F/L and optional UniLink communication system		FAA STC No. ST01303LA dated 25 August 2008.Universal Avionics Systems Master Drawing List, Document No. MDL-8054, Revision G, dated 25 September 2007 or later approved revision.	1. Restricted to the following configurations:-3 Config: UL-701 with SCN 22.X-4 Config: UNS-1F with SCN 802.X and A702 Maps2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification wi...	07/01/2009	Active	10016615
EASA.IM.A.S.03042	UNIVERSAL AVIONICS SYSTEMSCORPORATION		FAA STC ST01141LA	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 (CL-601 BOMBARDIER CL-600-1A11 (CL-600	Installation of Universal Avionics Terrain Awareness Warning System (TAWS)		FAA STC No. ST01141LA dated 22 February 2008.Universal Avionics Master Drawing List, MDL-8068, Revision G, dated 20 November 2008, or later approved revision.Airplane Flight Manual Supplement UASC TAWS, Document No. 20346, Revision C or later approved revision.	1. Restricted to the following configuration:-4 Config: Terrain Awareness and Warning System (TAWS) operating software SCN 11.X (ETSO EASA.IM.21O.0170) displayed on MFD-640 (ETSO EASA.IM. 21O.905)2. Prior to installation of this modification the installer must determine that the interrelationship bet...	07/01/2009	Active	10016616
EASA.IM.A.S.03049	LEARJET Inc.		FAA STC ST01402WI-D	LEARJET 60	Collins Pro Line 21 Avionics InstallationFAA STC ST01402WI-D		As per Master Data List AAC-0497-001, rev. L (or later approved revisions)	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	13/11/2008	Active	10016618
EASA.IM.A.S.03050	LEARJET Inc.		FAA STC ST01422WI-D	LEARJET 60	Interior Upgrade (Floor Plans A, B, C & D)FAA STC ST01422WI-D		As per Master Document List M100471ICT, rev. BH (or later approved revisions)	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of theproduct.The installation of this modification by third perso...	13/11/2008	Active	10016619
EASA.IM.A.S.03051	RAISBECK ENGINEERING Inc.		FAA STC SA00752SE	SEE ATTACHED EASA APPROVED TYP BEECH 200	This change applies only to the above listed model aircraftin accordance with Raisbeck Engineering Master Drawing List99-1500, Revision D, dated May 13, 2008 or later approved revisions.		Operation in accordance with FAA Approved Flight Manual Supplement 99-126, Revision A, dated January 10, 2000, 99-126H,dated October 4, 2007, or 08-B200GT-126, Revision IR, datedMay 13, 2008, or later approved revisions.	Requires the prior incorporation of Raisbeck STC's ref:- SA4175NM (when equipped with High Floatation gear) SA3366NMSA3831NMSA3519 NMIt is the installers responsibility to ensure allthese referenced STC's are EASA approved.	15/12/2008	Active	10016620

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03052	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02632CH-D	GULFSTREAM GV-SP	Aircraft completion and cabin interior installation for Serial No 5212.		Installation in accordance with Gulfstream Aerospace Corporation Master Drawing List No. GC52 2046121, Revision B, dated February 5, 2009, or later approved revisions.Operation tobe in accordance with Gulfstream Flight Manual Supplement GC52 204M038, Original Release, dated February 10, 2009, or la...	1. Serial No. 5212 Only2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modification will introduce no adverse effect upon theairworthiness of the product. The installation of this modif...	02/03/2009	Active	10016621
EASA.IM.A.S.03053	LITEAIR AVIATION PRODUCTS Inc.		FAA STC ST01872SE	BOMBARDIER DHC-8-402 BOMBARDIER DHC-8-401 BOMBARDIER DHC-8-400 SERIES	Installation of lightweight window plug.Ref. FAA STC ST01872SE, dated 09 September 2008.		1. Installation in accordance with LiteAir Aviation Products Inc. Master Drawing List LAP1008-D01, Original Issue, dated 01 August 2008 *).2. Maintenance must be performed in accordance with Light Weight Window Plug Installation, Document LAP2008, Original Issue, dated 07 August 2008 *).*) or...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	26/11/2008	Active	10016622
EASA.IM.A.S.03054	AVIATION CONSULTING & ENGINEERINGSOLUTIONS, INC.		FAA STC SA01282WI	525	Installation of Replacement of Seat Cushions.		- Cushions must be installed iaw. to Aviation Consultingand Engineering Solutions Master Data List Doc. No. A08190404 stamped “FAA Approved” from 21 Oct 2004, or later FAA approved Revisions.- Installation only approved on seat assemblies as listed in FAA STC SA01282WI.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	03/12/2008	Active	10016623
EASA.IM.A.S.03057	DECRANE AEROSPACE PATS AIRCRAFT,LLC		FAA STC ST01713NY-D	BOEING 737-800	Installation of Auxiliary Fuel Tank System in the forward and aft cargo compartments.		Configuration 1: Installation of a Four-Cell Auxiliary FuelSystem in the forward and aft cargo compartment in accordance with PATSAircraft LLC Kit Installation Drawing 5140-2811-103 as listed in the Master Drawing List 5140-2800-001, revision B dated February 6, 2006Configuration 2: Installation of...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	16/04/2009	Active	10016624
EASA.IM.A.S.03063	NASCO AIRCRAFT BRAKE, INC.		FAA STC ST02159LA	BOEING 767-200 SERIES	STC Validation - FAA STC ST02159LA		NASCO Configuration Control Report, Number NCC 008, Revision NC, 13th August 2008.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.	13/11/2008	Active	10016628
EASA.IM.A.S.03064	B/E AEROSPACE LIMITED		TCCA C-LSA09-087/D	GIV	Refurbishment and Installation of Cabin Interior Modifications.		Installation in accordance with Aero Consulting Services Ltd Modification Data Summary G040000 Rev N/C or later approved revisions.Maintenance in accordance with Aero Consulting Services Ltd Instructions for Continued Airworthiness G040071Rev NC or later approved revisions.	Aircraft Serial Number 1202 OnlyPrior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	08/04/2009	Active	10016629

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03065	B/E AEROSPACE LIMITED		TCCA C-LSA09-086/D	GIV	Installation of Rockwell Collins Radio Tuning Units RTU-4210 and Rockwell Collins TDR-94D (ELS/EHS) Transponder.		Installation in accordance with Aero Consulting Services Ltd Modification Data Summary G039000 Rev N/C or later approved revisions.Maintenance in accordance with Aero Consulting Services Ltd Instructions for Continued Airworthiness F773071Rev A and F773072 Rev A or later approved revisions.Operatio...	Aircraft Serial Number 1202 OnlyThe operator is responsiblefor the inclusion of a 24 month check in their maintenance schedule of the Mode S transponder system toensure correct operation of the 24BIT address and the required DAPs IAW ACS MM 34 53 00.	08/04/2009	Active	10016630
EASA.IM.A.S.03068	BOMBARDIER AEROSPACE		TCCA C-LSA08-275/D ISSUE 1	BD-100-1A10	Customized Interior Completion - Aircraft 200659 passenger seats interior configuration.EASA Validation of:Transport Canada Limited Supplemental Type Certificate C-LSA08-275/DIssue 1 dated 21st October 2008, in accordance with Aero ConsultingServices Ltd. Modification Data Summary G006000 dated 21st...		¿ Transport Canada Limited Supplemental Type CertificateC-LSA08-275/D Issue 1, dated 21st October 2008¿ Transport Canada Approved Aero Consulting Services Ltd. ModificationData Summary ref. G006000 dated 21st October 2008, RevisionN/C or later Transport Canada approved revision. ¿ Transpo...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	06/11/2008	Active	10016631
EASA.IM.A.S.03069	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10291SC-D	GULFSTREAM 200	Installation of Satcom High Speed Data Antenna i.a.w. IndexList GA243038000 Rev. D or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		IFCA: GA24303A000	1 Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product1 The Installation of this modification by thirdd...	21/01/2009	Active	10016632
EASA.IM.A.S.03070	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10290SC-D	GULFSTREAM 200	Relocation of AFIS/VHF Comm No. 1 Antenna i.a.w. Index ListGA243068000 Rev. C or later revisions of the above listed documents approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		IFCA: GA24306A000	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the productThe Installation of this modification by third persons is...	22/01/2009	Active	10016633
EASA.IM.A.S.03071	GULFSTREAM AEROSPACE CORPORATION.		FAA STC ST10292SC-D	GULFSTREAM 200	Installation of Thrane & Thrane Aero HSD + Satcom System i.a.w. Index List GA213038000 Rev. D or later revisions of the above listeddocuments approved by EASA in accordance with EASA ED Decision 2004/04/CF (or subsequent revisions of this decision).		IFCA: GA21303A000AFMS: GA21303M000	1 Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product1 The Installation of this modification by thirdd...	22/01/2009	Active	10016634
EASA.IM.A.S.03074	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA04-113 ISSUE 1	BOMBARDIER BD-700-1A10	Installation, Complete Custom Aircraft Interior / Installation of cabin systems and custom furnishings - ACSN 9291		- TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.- TCCA SOC reference C-09-0047 dated 16 January 2009.- Aero Consulting Services Configuration Deviation List D954000Revision CE dated 12 January 2009.- Instructions for Continued Airworthiness GC92910000-IFCA.	1. Restricted to ASN 9291.2. Refer to the Limitationssections of the required AFM Supplement and to the referenced FCOMS.3. WLAN system is compatible only to IEEE 802.11(b).4. Prior to installation of this modification the installer must determine that the interrelationship between this...	20/01/2009	Active	10016635

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03076	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC ST01635 LA	737-700, 737-800	- Installation of Cabin Interior Noise Reduction Kit.- Validation of FAA ST01635LA.		Aerocon Engineering Company Master Document List No. AC-BBJ-7370 Rev. C dated December 11, 2006 or later revisions of the above listed documents approved by EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	20/01/2009	Active	10016636
EASA.IM.A.S.03077	CESSNA AIRCRAFT COMPANY		FAA STC SA01519WI	CESSNA 525	Installation of an observer seat/3rd audio station/ExtendedRange Comm.		1. According to Cessna Master Document List Doc. No. CF90094 Rev. B, or later Revisions.2. To be operated in accordance with FAA approved Cessna AFM-S Document No. FM90940, Original Issue, or later approved Revisions.3. To be maintained in addition to basic aircraft maintenance manuals i.a....	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	28/11/2008	Active	10016637
EASA.IM.A.S.03078	AMTECH AERONAUTICAL LIMITED		TCCA STC C-LSA06-378/D	LEARJET MODEL 45	AirCell Axxess II Iridium SatcomTCCA LSTC C-LSA06-378/D		As per Master Document List BAS45010021, rev. E (or later approved revisions)	1 Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2 The installation of this modification by third...	06/01/2009	Active	10016638
EASA.IM.A.S.03079	GULFSTREAM AEROSPACE CORPORATION		FAA FAA STC ST02636CH-D	GULFSTREAM GV-SP	Aircraft Serial No 5220 completion and cabin interior installation.		Installation in accordance with Gulfstream Aerospace Corporation Master Drawing List No. GC52 2046129, Revision A, dated March 26, 2009, or later approved revisions.Operation to be in accordance with Gulfstream Flight Manual Supplement GC52 204M040, Original Release, dated March 26, 2009, or later a...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsG...	08/04/2009	Active	10016639
EASA.IM.A.S.03080	DASSAULT FALCON JET CORPORATION		FAA STC ST09293SC-D	FALCON 900EX	EASA Validation of FAA STC ST09293SC-D Revision 10, 22nd December 2004Installation of the FMZ-2000 Flight Management System in accordance with Data List Report No. F9EX-01026 Revision G dated 20 December 2004 or later revisions approved byEASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (ors...		See these originally FAA Approved:• Airplane Flight Manual Supplement Report No. 36628-1, dated 07 April 1998 for the F9EX-01026-501 installation.• Airplane Flight Manual Supplement Report No. 36628-2, dated 31 January 2000 for the F9EX-01026-503 installation.• Airplane Flight Manual Supple...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third pers...	07/04/2009	Active	10016640
EASA.IM.A.S.03081	DASSAULT AIRCRAFT SERVICES CORP.		FAA STC ST09736SC-D	FALCON 900EX	EASA Validation of FAA STC ST09736SC-DInstallation of a Cabin Master Switch System i.a.w. Drawing List ReportNo. F9EX-1041		- FAA STC ST09736SC-D original 06th September 2002- EASA Approved Drawing List Report No. F9EX-1041 Revision B dated 29thAugust 2002- EASA Approved Aeroplane Flight Manual Supplement Report No. 37026-1,Revision NC dated 06th September 2002or later revisions of these documents approved by EASA i.a.w....	none	20/05/2009	Active	10043077

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03082	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC ST09301SC-D	FALCON 900EX	EASA Validation of FAA STC ST09301SC-DInstallation of the Service and Indirect Lighting System in accordance with Drawing List report No. F9EX-01027, Revision B dated 28September 2000 or later revisions approved by EASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or subsequent revisions to t...		See those of original FAA STC ST09301SC-D, originally issued issued on 28th January 1999 and amended as per Revision 1 on 30 September 2000or later revisions of these documents approved by EASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or subsequent revisions to these decisions).	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	31/03/2009	Active	10016641
EASA.IM.A.S.03083	DASSAULT FALCON JET CORP.(SERVICE CENTER)		FAA STC ST09738SC-D	FALCON 900EX	EASA Validation of FAA STC ST09738SC-DInstallation of the HF Radio Master System in accordance with Drawing List ReportNo. F9EX-01044 Revision NC dated 16 September 2002 or laterrevisions approved by EASA i.a.w. EASA ED Decisions 2007/001/C and 2004/04/CF (or subsequent revisions to these decision...		See those of original FAA STC ST09738SC-D originally issued01st October 2002 andEASA Approved Airplane Flight Manual Supplement, Report No. 37035-1, dated 01st October 2002 for the F9EX-01044-501 installation.or later revisions of these documents approved by EASA i.a.w. EASA ED Decisions 2007/001/C...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	31/03/2009	Active	10016642
EASA.IM.A.S.03084	DASSAULT FALCON JET CORPORATION		FAA STC ST09715SC-D	FALCON 900EX	- EASA Validation of FAA STC ST09715SC-D- Installation of the Control Wheel Modifications in accordance with Drawing List Report No. F9EX-01032		- FAA STC ST09715SC-D Revision 1, 03rd September 2002*- Drawing List Report No. F9EX-01032 Revision C dated 01st August 2002*- EASA Approved Airplane Flight Manual Supplement, Report No. 37039-1, dated 03rd September 2002 for the F9EX-01032-505 installation*- EASA Approved Airplane Maint...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third pers...	11/05/2009	Active	10016643
EASA.IM.A.S.03085	THE BOEING COMPANY - WICHITA DIVISION	REV. 1	FAA STC SA2124CE-D	BOEING 747-200B	Conversion of Passenger Airplane to Main Deck Side Cargo Door Dedicated Special Freighter in accordance with Boeing Drawing List document D3-8857, Section V, Appendix 33, Rev. CS.		Boeing Commercial Airplane Group - Wichita Division, Airplane Flight Manual Supplement dated 9 September 1992 or later revision approved in accordance with ED Decision 2004/04/CF dated 10 December 2004.D6-30680-7 Cargo Loading Manual	1. Prior to installation of this modification the installermust determine that theinterrelationship between this modification and any other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third pers...	09/02/2009	Active	10016644
EASA.IM.A.S.03088	AIRCRAFT TECHNICAL DEVELOPMENT Inc.d/b/a AEROCON ENGINEERING COMPANY		FAA STC ST01568LA	737-700	- Installation of Cabin Interior Noise Reduction Kit.- Validation of FAA ST01568LA.		Aerocon Engineering Company Master Document List No. AC-BBJ-1000 Rev. B dated November 18, 2003 or later revisions of the above listed documents approved by EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	20/01/2009	Active	10016645
EASA.IM.A.S.03091	B/E AEROSPACE LIMITED		TCCA C-LSA09-088/D	GIV	Installation of L3 Communications MicroQAR Quick Access Recorder.		Installation in accordance with Aero Consulting Services Ltd Modification Data Summary G052000 Rev N/C or later approved revisions.Maintenance in accordance with Aero Consulting Services Ltd Instructions for Continued Airworthiness G052071Rev NC or later approved revisions.	Aircraft Serial Number 1202 OnlyPrior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	08/04/2009	Active	10016647

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03095	GULFSTREAM SERVICES CORPORATION		FAA STC ST03542AT-D	GULFSTREAM GIV-X	Installation of an Aft Galley/Galley Annex Multiple STC.		Install in accordance with Gulfstream Aerospace CorporationIndex List, GC415408000 Rev L, dated February 04, 2009, or later FAA approved revision.	1. This Aft Galley/Galley Annex Multiple STC, (FAA ref ST03542AT-D), does not approve the entire airplane interior installation andhas the following limitations as defined in document GC415400266.“Guidance for Follow on Installation, Aft Galley/Galley Annex Multiple STC”:i. A complete airplane in...	10/06/2009	Active	10016650
EASA.IM.A.S.03097	DELTA ENGINEERING CORPORATION		FAA STC ST00740NY-D	B747-400	Installation of Matsushita Avionics Systems Corporation 2000E CabinEntertainment System<(>,<)> in accordance with DeltaEngineering, L.P.Master Drawing list 156-03918-250, Revision B<(>,<)> dated Dec. 22,1998.Validation of FAA STC ST00740NY-D.		Maintenance Manual Supplement for 747-400 with Matsushita AvionicsSystems Corporation 2000E Cabin Entertainment System,Delta EngineeringDoc. No. 768-03925-250, Dec. 15<(>,<)>1998.	1. Maintenance Manual Supplement for 747-400 with Matsushita AvionicsSystems Corporation 2000E Cabin Entertainment System, Delta EngineeringDoc. No. 768-03925-250, Dec. 15, 1998 must be incorporated into theoperator's maintenance instructions.2. Prior to installation of this modification the install...	03/06/2009	Active	10043059
EASA.IM.A.S.03098	DELTA ENGINEERING CORPORATION		FAA STC ST00988NY-D	BOEING 747-400	Installation of Matsushita Avionics Systems Corporation 2000E with AVOD1.5 Cabin Entertainment System in accordance with Delta Engineering,L.P. Master Drawing List 107-04323-250, Revision C, dated Sept. 24, 1999or later FAA approved revisions.Validation of FAA STC ST00988NY-D	Per FAA TCDS A20WE	Maintenance Manual Supplement for 747-400 with Matsushita AvionicsSystems Corporation 2000E Cabin Entertainment System,Delta EngineeringDoc. No. 707-04403-250, May 28, 2003	Maintenance Manual Supplement for 747-400 with Matsushita AvionicsSystems Corporation 2000E Cabin Entertainment System,Delta EngineeringDoc. No. 707-04403-250, must be incorporated into the operator’smaintenance instructions.	30/07/2009	Active	10033596
EASA.IM.A.S.03100	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA05-60	BOMBARDIER BD-700-1A11	Customized Interior Completion - ACSN 9293		TCCA STC No. SA05-60 Issue 1 dated 14 June 2005.TCCA SOC letter C-08-0874 dated 18 December 2008.Aero Consulting Services Modification Data Summary E025000 Revision BE dated 12 December 2008.Bombardier Airplane Flight Manual Supplement G-FM25004501 Revision N/C.Instructions for Continued Airworthine...	Restricted to ASN 9293 and1. Refer to the Limitations sections of the required AFM Supplement and to the referenced FCOMS.2.2. WLAN system is compatible only to IEEE 802.11 (b).3.Prior to installation of this modification the installer must determine that the interrelationship between this modifica...	14/01/2009	Active	10016652
EASA.IM.A.S.03101	ELECTRONIC CABLE SPECIALISTS, Inc.		FAA STC ST02626CH	A321-213/-231/-232 A321-111/-112/-131/-211/-212 A320-214/-231/-232/ A320-111/-211/-212/-214/ A319-131/-132/-133 A319-111/-112/-113/-114/-115 A318111/-112/-121/-122	·,,Electronic Cable Specialists Master Data List, ref. doc.ECS-206919,Revision E, dated 9th September 2008 (*) ·,,Airplane Flight Manual Supplement, ref. doc. ECS-206922, RevisionN/C, dated 29th September 2008 (*)·,,Instructions for Continued Airworthiness, ref. doc. ECS-206923,Revision A, dated 28t...	Installation of an EZMount™ Tilt Mechanical Mounting Assembly		None	02/06/2009	Active	10028835
EASA.IM.A.S.03102	BOMBARDIER COMPLETION CENTRE INC			BOMBARDIER BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9286		Transport Canada Limited STC No. C-LSA09-003/D dated 07 January 2009.Transport Canada SoC reference C-08-0994 dated 21 January 2009.Aero Consulting Services Modification Data Summary F990000 Revision N/C or later approved revision.Bombardier Flight Manual Supplement G-FM25000175 Revision NC or later...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	26/01/2009	Active	10016653

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03104	ROSEMOUNT AEROSPACE, Inc.			BOEING MD 11F	Installation of Rosemount Aerospace 8700C2-8 Series Laptop Docking Station (LDS) - Electronic Flight Bag (EFB) System Provisions inaccordance with Rosemount Aerospace Master Data List, Doc. No. D06403165, Revision D, dated April 3, 2009 orlater FAA approved revision. These provisions include Electr...		Airplane Flight Manual Supplement for MD-11 series AircraftRosemount Document No. D06403253 Rev. B	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2) FAA approved Airplane Flight Manual Supplement, Ros...	10/06/2009	Active	10016655
EASA.IM.A.S.03105	BOMBARDIER COMPLETION CENTRE INC		SA05-60	BOMBARDIER BD-700-1A11	Installation, Complete Custom Aircraft Interior		Transport Canada STC No. SA05-60 Issue 1 dated 14 June 2005.Transport Canada SoC ref. C-09-0200 dated 31 March 2009.Aero Consulting Services Ltd. Configuration Definition List E025000 Revision BG or later approved revision.Aero Consulting Services Ltd. Airplane Flight Manual Supplement G-FM25004501G...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	02/04/2009	Active	10016656
EASA.IM.A.S.03117	BOMBARDIER AEROSPACE		TCCA C-LSA09-0002/D ISSUE 1	BOMBARDIER CL-600-2B16	Main & Nose Wheel Storage Modifications.		- TCCA STC No. C-LSA09-002/D Issue 1 dated 15 January 2009.- Aero Consulting Services Modification Data Summary Number G150000 Revision N/C*- Instructions for Continued Airworthiness G150070-ICA Revision N/C**Or any later revisions of the above listed documents approved by EASA in accordanc...	1. Restricted to ASN 5426.2. Prior to installation ofthis modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of...	20/01/2009	Active	10016657
EASA.IM.A.S.03124	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA01838SE	LC41-550FG (C400)	Installation of Sunvisor.		According to Rosen Sunvisor System, LLC Master Drawing ListNo. 1381000-00DL, Rev. B or later FAA approved Revisions.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	23/04/2009	Active	10016661
EASA.IM.A.S.03125	B/E AEROSPACE LIMITED		TCCA C-LSA08-317/D	CL-600-2B16	Installation, Complete Custom Aircraft Interior		TCCA STC No.C-LSA08-317/D Issue 1 dated 12 December 2008.Aero Consulting Services Ltd. Modification Data Summary G048000 Revision NC or later approved revision.Midcoast Aviation Inc. Airplane Flight Manual Supplement for the Complete Custom Aircraft Interior Installation, 41-299M004 Revision NC or l...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	19/02/2009	Active	10016662

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03126	MICRO AERODYNAMICS, INC.	REV 1	FAA STC SA01646SE	CESSNA A185F CESSNA A185E CESSNA 185E CESSNA 185D CESSNA 185C CESSNA 185B CESSNA 185A CESSNA 185 CESSNA 182B CESSNA 182A CESSNA 182 CESSNA 180K CESSNA 180J CESSNA 180H CESSNA 180G CESSNA 180F CESSNA 180E CESSNA 180D CESSNA 180C CESSNA 180B CESSNA 180A CESSNA 180 CESSNA 175 CESSNA 172	Installation of vortex generators on the wings and tail surfaces in accordance with the provisions of AML SA01646SE.		Option 1: Installation of vortex generators on the wings, horizontal and vertical tail surfaces of the above model Aircraft in accordance with Micro AeroDynamics Drawing Package MA2208, Revision IR, dated 17 January 2006 and Installation Manual MA2209, Revision IR, dated 27 January 2006 or later EAS...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	17/03/2009	Active	10016663
EASA.IM.A.S.03129	B/E AEROSPACE LIMITED		TCCA C-LSA09-022/D	CL-600-2B16	Installation, Complete Custom Aircraft Interior.		- TCCA STC No. C-LSA09-022/D Issue 1 dated 03 April 2009.- Aero Consulting Services Ltd. Modification Data Summary G101000 Revision NC*- Midcoast Aviation Inc. Airplane Flight Manual Supplement for the Complete Custom Aircraft Interior Installation, 41-299M006 Rev NC*- Aero Consulting Se...	1. Restricted to ASN 5734.2. Prior to installation ofthis modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.3. The installatio...	14/04/2009	Active	10016664
EASA.IM.A.S.03138	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03666AT-D	GULFSTREAM GV-SP	Installation of an Airplane Interior and Completion for Aircraft Serial5225.		- Install in accordance with Gulfstream Aerospace Corporation MasterIndex List, GC514915225 Rev C, dated May 05, 2009 or later FAA approvedrevision.- To be operated in accordance with FAA approved Airplane Flight ManualSupplement, ref. GC51468M004, Rev. NC dated May 05,2009, or later FAAapproved rev...	Aircraft Serial Number 5225 only.	20/05/2009	Active	10043073
EASA.IM.A.S.03139	GULFSTREAM SERVICES CORPORATION		FAA STC ST03668AT-D	GULFSTREAM GIV-X	Installation of an Airplane Interior and completion for Aircraft Serial 4148.		Install in accordance with Gulfstream Aerospace CorporationMaster Index List, GC414914148 Rev E, dated March 17, 2009,or later FAA approved revision.To be operated in accordancewith FAA approved Airplane Flight Manual Supplement, ref. GC41204M002, Rev. NC dated 03/17/09, or later FAA approved rev...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsA...	07/04/2009	Active	10016666
EASA.IM.A.S.03140	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA06-34	BOMBARDIER BD-700-1A11 BOMBARDIER BD-700-1A10	Installation of CMS-400 Digital Voice Checklist System.		- Transport Canada STC No. SA06-34 Issue 1 dated 23 May 2006.- Transport Canada SoC ref. C-09-0335 dated 15 April2009.- Aero Consulting Services Ltd. Modification Data Summary no. E938000 Revision A or later approved revision.- Bombardier Aerospace FMS No. G-FM31404001 Revision N/C or l...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	27/04/2009	Active	10016667

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03141	BOMBARDIER COMPLETION CENTRE INC		TCCA STC SA04-113 ISSUE 1	BOMBARDIER BD-700-1A10	Interior Completion, BD-700-1A10 - ASN 9281		Transport Canada SoC reference C-09-0174 dated 09 March 2009.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.Aero Consulting Services Configuration Definition List D954000 Revision CB dated 11 December 2008.Instructions for Continued Airworthiness GC92810000-IFCA.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	10/03/2009	Active	10016668
EASA.IM.A.S.03145	BOMBARDIER INC.		TCCA STC SA08-86	BD-700-1A10	Ground Service Mode DC Cabin Power Distribution Modification	EASA TCDS IM.A.009	-TCCA STC No. SA08-86 Issue 1 dated 08 December 2008-TCCA SoC reference C-09-0423 dated 24 June 2009Aero Consulting Services Modification Data Summary No F928000 RevisionN/C or later approved revision-BAS67050010-ICA Instructions for Continued Airworthiness	None	23/07/2009	Active	10033779
EASA.IM.A.S.03149	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST02105LA-D	GV-SP (G550)	Installation of Custom Cabin Interior and Aircraft Completion forAircraft Serial 5221.		- Install in accordance with Gulfstream Aerospace Report GC52000K633,Rev. N/C and Index List GC520008643 Rev. G, dated 20 April 2009, orlater approved revisions.- Operate in accordance with Gulfstream Aerospace Flight ManualSupplement GC52000M096, revision N/C, dated 20 April 2009, or laterapproved...	Aircraft Serial Number 5221 only	07/05/2009	Active	10043072
EASA.IM.A.S.03153	ROSS FRESNO LLBD/B/A CORPORATE AIRCRAFT			CESSNA 441 SERIES					15/07/2009	Active	10028673
EASA.IM.A.S.03156	ROCKWELL COLLINS Inc.		FAA STC NO. SA5098NM	AIRBUS A320-232	Installation of Sony Trans Com Inc. Video Entertainment System		• FAA STC SA5098NM• Sony Trans Com Inc. Index List, ref. doc. 062-0130, Revision AA, dated 12th May 2004 (*)• Instruction for Continued Airworthiness, ref. doc. 070-4328-000, Revision BF, dated 16th December 2005 (*)(*) or later revisions approved by EASA in accordance with EASA ED decision...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modificationand any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. 2. The installation of this modification b...	29/04/2009	Active	10016670
EASA.IM.A.S.03161	BOMBARDIER AEROSPACE		TCCA SA09-16	BD-100-1A10	Installation of KGS Electronic SS200 Static InverterEASA Validation of:Transport Canada Supplemental Type Certificate SA09-16, Issue 2 dated19th March 2009 in accordance with AeroConsulting Services Ltd. Modification Data Summary G072000 Revision B.		• Transport Canada Supplemental Type Certificate SA09-16, Issue 2 dated 19th March 2009 ¿ Aero Consulting Modification Data Summary, ref. No. G072000 Revision B, dated 26th February 2009 or later Transport Canada approved revision ¿Instructions for Continued Airworthiness, ref. No. G072071-I...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	06/04/2009	Active	10016671

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03163	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9294		- Transport Canada SoC reference C-09-0213 dated 15 May 2009.- TCCA STC No. SA04-113 Issue 1 dated 28 October 2004.- Aero Consulting Services Configuration Definition List D954000Revision CL dated 20 March 2009.- Instructions for ContinuedAirworthiness GC92940000-IFCA.	1. Restricted to ASN 9294.2. Refer to the Limitations sections of the required AFM Supplement andto the referenced FCOMS.3. WLAN system is compatible only to IEEE 802.11(b).4. Prior to installation of this modification the installer mustdetermine that the interrelationship between this modificationo...	02/06/2009	Active	10043058
EASA.IM.A.S.03166	O&N AIRCRAFT MODIFICATIONS, INC.		FAA STC SA02277CE	M20C, M20D, M20E, M20G	Installation of Fuel Bladder Cells in wet wing fuel cavities.		Installation and maintenance i.a.w. to- Configuration 1: Brentwing Engineering, Inc. Installation Drawing ListB-700 and/ or O<(>&<) >N Aircraft Modifications, Inc. InstallationInstructions B-900 and O<(>&<)>N Aircraft Modifications, Inc.Maintenance Instructions B-901, all in latest approved Revisions...	none	07/05/2009	Active	10043071
EASA.IM.A.S.03167	O&N AIRCRAFT MODIFICATIONS, INC.		FAA STC SA02277CE	M20F, M20J	Installation of Fuel Bladder Cells in wet wing fuel cavities.		Installation and maintenance i.a.w. to- Configuration 1: Brentwing Engineering, Inc. Installation Drawing ListB-400 and/ or Installation Instructions Report B-200 and MaintenanceInstructions Report B-300, all in latest approved Revisions- Configuration 3: O<(>&<) >N Aircraft Modifications, Inc. Insta...	none	07/05/2009	Active	10043070
EASA.IM.A.S.03172	A.A.E., LTD.	REV. 1	FAA STC ST01077WI	A320	Installation of AAE's smoke detection and fire suppression System in thelower Class C Cargo compartments.		- FAA STC STOIO77WI- Master Drawing List, ref. doc. TFAIO-0057, Revision U, dated 11thMarch 2009 *- Airplane Flight manual Supplement ref. doc. TFA09-0062/ doc.TFA09-0088/ doc. TFA09-0089, Revision IR, dated 4th November 2008*- Instructionfor Continued Airworthiness, ref. doc. TFA18-0142,Revision C...	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	23/06/2009	Active	10043324
EASA.IM.A.S.03173	ROSEN SUNVISOR SYSTEMS L.L.C.		FAA STC SA4339NM	DHC-8-401, -402 DHC-8-301, -311, -314, -315 DHC-8-201, 202 DHC-8-120, -103, -106	Sunvisor SystemFAA STC SA43339NM dated October 31. 2008		Installation in accordance with Rosen Drawing List 201R0000, Revision D*) or later revisions of the above listed documents approved by EASA inaccordance with EASA ED Decision 2004/04/CF (or subsequent revisions ofthis decision).	None	08/05/2009	Active	10028843
EASA.IM.A.S.03174	AVIDYNE CORPORATION		FAA SA02013CH	SR20, SR22	Installation of Avidyne Model 9900BX/ TAS 600 Series Traffic Advisory System (TAS)		According to Avidyne Master Document List Doc. No. DC1029-1Rev. 12, or later FAA approved RevisionsTo be operated in accordance with Avidyne AFM-S Documents No. 32-2353C, Rev. 6,or later FAA approved RevisionsTo be maintained i.a.w. ICA Document No. ICAW010807C, Rev. 12, or later approved Revision...	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2) The installation of this modification by third pers...	27/05/2009	Active	10016672

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03176	BOMBARDIER AEROSPACE		TCCA SA04-69 ISSUE 1	BD-100-1A10	Installation of 115 VAC TIA Wavejet Microwave Oven in Forward RH Galley.EASA Validation of:Transport Canada Supplemental Type Certificate SA04-69, Issue 1 dated 4th June 2004 in accordance with Aero Consulting Services Ltd. Modification Data Summary E027000 Revision N/C.		• Transport Canada Supplemental Type Certificate SA04-69, Issue 1 dated 4th June 2004 ¿ Aero Consulting Modification Data Summary, ref. No. E027000 Revision N/C, dated 28th May 2004 or later Transport Canada approved revision ¿ Bombardier Aerospace Supplemental Maintenance Manual ref. doc. E0...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	04/05/2009	Active	10016673
EASA.IM.A.S.03177	B/E AEROSPACE LIMITED	REV. 1	TCCA SA91-97	DHC-8-314, DHC-8-315 DHC-8-301, DHC-8-311 DHC-8-201, DHC-8-202 DHC-8-102, DHC-8-103,DHC-8-106	Safety Catch Mechanism on the Rear Baggage DoorRef. TCCA STC SA91-97, Issue 3, dated 18.11.2003Note: This STC supersedes EASA.IM.A.S.03177.		Installation in accordance to ACS TCCA approved Modification Data Summary Report 956900, Rev. E, dated 28.06.2007*).Maintenance in accordance with ACS Maintenance Manual Supplement, 956971, Rev. B, dated 08 November 2006*).*) or later revisions of the above listed documents approved by EASA in a...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	14/05/2009	Active	10016674
EASA.IM.A.S.03182	DELTA ENGINEERING CORPORATION		FAA STC ST02215NY-D	BOEING 747-400 SERIES	Installation of Panasonic Avionics Corporation System 3000iIn-Flight Entertainment System in accordance with Delta Engineering Master Data List 0107-05809-2121 Rev. A dated Nov. 15, 2006 or later approved revisionsValidation of FAA STC ST02215NY-D		Delta Engineering 0707-05814-2121 Rev. A Instructions for Continued Airworthiness	1. Delta Engineering Instructions for Continued Airworthiness 0707-05814-2121 Rev. A dated Aug 31, 2006 are required with this installation.2. The cabin configuration of the seatsinstalled in accordance with KLM LOPA KLM3H112780 Revision ORG is required for this installation of the STC. The seats a...	18/06/2009	Active	10016675
EASA.IM.A.S.03189	BOMBARDIER AEROSPACE		FAA STC ST02683CH	BOEING 747-400 SERIES	Installation of EZMount (TM) mechanical mounting assembly on lower frame of cockpit sliding windows in accordance with Electronic Cable Specialists Master Data List ECS-206728 Rev. E, dated April 8, 2009, or later FAA approved revisions.Validation of FAA STC ST02683CH		AFM Supplement as listed in Appendix A of ECS Master Data List ECS-206728 Rev. E	1. AFM Supplement as listed in Appendix A of Electronic Cable Specialists Master Data List ECS-206728, Rev. E, dated April 8, 2009 or later FAA approved revision, is required on board the modified aircraft.2. The equipment for which these provisions are intended is not part of this approval. Additio...	18/06/2009	Active	10016676
EASA.IM.A.S.03190	BAUMANN FLOATS LLC		FAA STC SA01491CH	M-7-235B,MX-7-235,MT-7-235 M-5-235C,M-6-235,M-7-235	Installation of BF2750A amphibious float installation		According to Baumann Master Document / Drawing List Doc. No. BF2750A-02Rev. F, or later FAA approved RevisionsTo be operated in accordance with Baumann AFM-S Documents No. BF2750A,rev. E, or later FAA approved RevisionsTo be maintained i.a.w. ICA Document No. BAUMANN FLOATS MODEL BF2150A,BF2550A & B...	none	27/05/2009	Active	10043069
EASA.IM.A.S.03193	ROCKWELL COLLINS AEROSPACE &ELECTRONICS, Inc.		FAA STC ST00129SE	BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-100 SERIES	Validation of the FAA STC ST00129SE for the HGS 2800 on theDash 8-100/200/300 Series Aircraft (editorial change).		German LBA STC (TA0092)Austrian AustroControl STC (ACG. 21NE.046)	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	27/04/2009	Active	10016677

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03195	DELTA ENGINEERING CORPORATION		FAA STC ST01482NY	BOEING 747-400 SERIES					21/07/2009	Active	10029013
EASA.IM.A.S.03196	DELTA ENGINEERING CORPORATION		FAA STC ST01483NY	BOEING 747-400 SERIES					23/07/2009	Active	10029011
EASA.IM.A.S.03197	DELTA ENGINEERING CORPORATION		FAA STC ST01519NY	BOEING 747-400 SERIES					23/07/2009	Active	10029012
EASA.IM.A.S.03203	GULFSTREAM AEROSPACE CORPORATION		FAA STC ST03647AT-D	GIV-X	Installation of a Forward Galley-Vestibule Area-Forward Lavatory-Flight Deck Multiple STC		Install in accordance with Gulfstream Aerospace CorporationIndex List, GC421048004 Rev D, dated January 30, 2009, or later FAA approved revision.	1. The Forward Galley-Vestibule Area-Forward Lavatory-Flight Deck Multiple STC, (FAA ref ST03647AT-D), does not approvethe entire airplane completion and interior installation and has the following limitations as defined in document GC421040019, “Guidance for Follow on Installation, Forward Galley-...	08/06/2009	Active	10016680
EASA.IM.A.S.03204	GULFSTREAM SERVICES CORPORATION		FAA STC ST03649AT-D	GULFSTREAM GIV-X	Installation of a Flight Deck-Forward Vestibule-Forward Lavatory Multiple STC		Install in accordance with Gulfstream Aerospace CorporationIndex List, GC421048003 Rev E, dated February 04, 2009, or later FAA approved revision.	1. This Flight Deck-Forward Vestibule-Forward Lavatory Multiple STC, (FAA ref ST03649AT-D), does not approve the entireairplane completion and interior installation and has the following limitations as defined in document GC421040020“Guidance for Follow on Installation, Flight Deck-Forward Vestibul...	10/06/2009	Active	10016681
EASA.IM.A.S.03205	LEARJET Inc.		FAA STC ST00604WI	LEARJET 31A	Installation of stand-alone Garmin GPS-165 Global Positioning System (VFR Navigation Only).		• FAA STC ST00604WI• Master Document List, ref. doc. No. M100229ICT, Rev. B, dated 2 December 1997 or later revisions approved by EASA in accordance with EASA ED decision 2004/04/CF (or subsequent revisions of this decision).• Airplane Flight Manual Supplement, ref. doc. AFMS-W1455, dated 1...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	28/04/2009	Active	10016682
EASA.IM.A.S.03210	HONEYWELL INTERNATIONAL INC.		ST01208SE	BOEING 747-400F BOEING 747-400					16/07/2009	Active	10028540
EASA.IM.A.S.03216	BOMBARDIER INC.		TCCA STC SA04-113	BD-700-1A10	Installation, Complete Custom Aircraft Interior - ASN 9283		Transport Canada SoC reference C-09-0274 dated 12 June 2009.TCCA STC No. SA04-113 Issue 1 dated 28 October 2004. Aero ConsultingServices Configuration Definition List D954000 Revision DA dated 29 May2009 or later approved revision.Bombardier Aerospace Airplane Flight Manual Supplement G-FM25004001Re...	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product. The installation of thismodification by third persons i...	16/06/2009	Active	10043057
EASA.IM.A.S.03228	AIRWELD, INC.			707-300C	Vapor Cycle Air Conditioning System Installation (Validation of FAA STCSA5008NM)		-,,FAA STC SA5008NM, date reissued 10 April 2009-,,World Auxiliary Power Company (WAPCO) Drawing List Number 50000,Revision “A” dated 10 June 1990 or any later revision approved by EASAin accordance with EASA ED decision 2004/04/CF (or subsequent revisionsof this decision)	The limitations of FAA STC SA5008NM apply	14/07/2009	Active	10030747

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03230	PRATT & WHITNEY		FAA STC ST00262BO	GULFSTREAM 200					17/07/2009	Active	10028632
EASA.IM.A.S.03231	PRATT & WHITNEY ENGINE SERVICES, IN		FAA STC ST00263BO	680	Valdiation of FAA STC No. ST00263BOData Transmission Unit (DTU) for Cessna Model 680	Certification Basis as per EASA TCDS IM.A.033 Issue 1 from 31 March2005.	Master Document List DTU-T-100-6 Revision F from 23 July 2009Instructions for Continued Airworthiness DTU-G-260-5 Revision B from 09April 2008Installation Instructions DTU-G-01 0-5 Revision B from 09 April 2008or later revisions of the above listed documents approved by EASA inaccordancewith EASA ED...		29/07/2009	Active	10036215
EASA.IM.A.S.03233	MICRO AERODYNAMICS, INC.		FAA STC NO SA01555SE	A24, A24R, B24R, C24R A23-19, A23-24, B23, C23 19A, B19, M19A, 23, A23, A23A	Installation of Vortex Generators on the wings and tail surfaces		FAA approved Drawing Package, Doc. No. MA2204, Rev. IR, dated07-Apr-2005, or later approved revisionFAA approved Installation Manual, Doc. No. MA2205, Rev. IR, dated04-May-2005, or later approved revisionInstruction for Continued Airworthiness, stated on VG Operating Placard, MA8001	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	02/07/2009	Active	10043329
EASA.IM.A.S.03234	CASCADE AVIATION SERVICES INC.		FAA ST01629SE	BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-100 SERIES					02/07/2009	Active	10028834
EASA.IM.A.S.03238	RS ENTERPRISES			DHC 8-301, -311, -314, -315 DHC 8-103, -106, -201, -202 BOMBARDIER DHC 8-101, -102	Installation of Cockpit Window Shades.Ref. TCCA STC SA00-71, Issue 2, dated July 27, 2000.		Installation must be performed in accordance with InstallationInstructions Document R.S.01-2000 Rev. 0 or later revisions of the abovelisted documents approved by EASA in accordance with EASA ED Decision2004/02/CF (or subsequent revisions of this decision).	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	21/07/2009	Active	10027149
EASA.IM.A.S.03247	BOMBARDIER AEROSPACE		TCCA STC SA07-110	CHALLENGER 300 BOMBARDIER BD-100-1A10	Installation of AVS-470 Tail Camera System. EASA Validationof:Transport Canada Supplemental Type Certificate SA07-110,Issue 1 dated3rd August 2007 in accordance with Aero Consulting Services Ltd.Modification Data Summary F161001.		- Transport Canada Supplemental Type Certificate SA07-110, Issue 1 dated3rd August 2007- Aero Consulting Services Modification Data Summary, ref. No. F161001Revision B, dated 13thJuly 2009 or later Transport Canada approvedrevision- Instructions for Continued Airworthiness, ref. No.RAL-BV100-5104-I...		23/07/2009	Active	10036042
EASA.IM.A.S.03253	LEARJET INC.		FAA STC ST01735LA-D	BOMBARDIER CL-600-2B16 BOMBARDIER CL-600-2A12 BOMBARDIER CL-600-1A11	FAA STC ST01735LA-D, Installation of a Kidde Aerospace Smoke Detector inthe Aft Baggage Compartment, as a replacement for Walter Kidde PIN473052.	EASA.IM.A.023	FAA STC No. ST01735LA-D dated 13 March 2007.Bombardier Aerospace Master Document List BAS6301 0115 Revision A dated13 March 2007 or later approved revision.Bombardier Aerospace Airplane Flight Manual Supplement BAS63040218Revision NC dated13 March 2007 or later approved revision is requiredfor theT...	An EASA approved Walter Kidde Smoke Detector System for PIN473052 is aprerequisite l concurrent requirement for the installation of this STC.	02/07/2009	Active	10036055

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.A.S.03263	SAFRAN CABIN BELLINGHAM, INC.		FAA STC ST01061SE	BOEING 747-400	Installation of Airshow 420 News and Weather Information System kit inaccordance with Britax Heath Tecna Drawing List HPD-DL-78, Revision A,dated February 25, 2002 or later FAA approved revisions. Validation ofFAA STC01061SE.			Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	27/07/2009	Active	10028538
EASA.IM.A.S.C.01002	WESTERN AVIONICS		TCCA STC SA03-13; EASA.IM.A.S.	BOMBARDIER DHC-8-315 BOMBARDIER DHC-8-311 BOMBARDIER DHC-8-300 SERIES BOMBARDIER DHC-8-200 SERIES BOMBARDIER DHC-8-103 BOMBARDIER DHC-8-102 BOMBARDIER DHC-8-100 SERIES	Installation ((Upgrade)) of a Single or Dual Universal Avionics UNS-1C+ or UNS-1E Flight Management System (FMS)		-Top Document List 91846-400, Revision 5 dated 29 September2004 Western Avionics AFM Supplement 71967-803, Revision 1 dated 05 August 2003 (EMS) or 71967-804, Initial Issue dated05 August 2003 (EFIS), ((AFM Supplement 71967, Revision 1 dated 05 August 2003 (EMS) of AFM Supplement 71967-804, Initia...	1. Installation (Upgrade) of the Single or Dual Universal Avionics UNS-1+ or UNS-1E Flight Management System (FMS) is to be done inaccoedance with Transport Canada approved Western Avionics Engineering Orders 71967-401 Revision 5 dated 17 September 2004 (91846-402 Revision 1 dated 17 september 2004)...	20/05/2005	Active	10016683
EASA.IM.A.S.C.01060	AIRWORKS		FAA STC ST01443LA	BOEING 737-900 SERIES BOEING 737-600/-700/-800 BOEING 737-300/-400/-500	Installation of AirWrks Cockpit Door Surveillance Systems		- AirWorks Master Data List MDL230096, Revision A dated 11/11/2004 or later FAA approved Revision- AirWorks AirplaneFlight Manual Supplement Document No. AFMS230096, Revision Original dated 11/02/2005 or later FAA approved revision- FAA STC No. ST01443LA amend 8/4/2005	1. Limitatons according to FAA STC No. ST01443LA amended8/4/2005.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the ins...	08/08/2005	Active	10016685
EASA.IM.BA.S.01000	HEAD BALLOONS, INC.		SL2263SO	HEAD BALLOONS AX9-118 HEAD BALLOONS AX8-88B HEAD BALLOONS AX8-88 HEAD BALLOONS AX8-105 HEAD BALLOONS AX7-77B HEAD BALLOONS AX7-77	Installiopn of Aerostar (Raven) Models CW and RW baskets.		FAA STC SL2263SO. Head Ballonns Drawing No. R-1b, revised April 10, 1993; No. R2b, revised April 10, 1993; No. R-3a dated September16, 1991; and No. R-4 dated April 10, 1993 or later FAA approved revisions.Flight Manual Supplements:Head AX7-77 Balloon Flight Manual Supplement dated 25 Feb 1988Head A...	The following Aerostar burners are approved for usewith theabove Head envelope / Aerostar basket configuration:Rally HP burner PN 13180HP II Dual burner PN 17395HP II Single burner PN 17398Rally HP II burner PN 17399HP III Dual burner part number 52350HP III Single burner PN 52370-01	13/04/2007	Active	10016686
EASA.IM.BA.S.01001	HEAD BALLOONS, INC.		FAA STC SB00463AT	HEAD BALLOONS AX9-118 HEAD BALLOONS AX8-88B HEAD BALLOONS AX8-88 HEAD BALLOONS AX8-105 HEAD BALLOONS AX7-77B HEAD BALLOONS AX7-77	Installation of Cameron Balloons Ltd. baskets and burners underneath Head Balloons, Inc. envelopes		Balloon Flight Manual (BFM) Supplements per model:- BFM supplement for Head Balloons AX7-77 w/Parachute top, revision 1, dated OCT 21 2008- BFM supplement for Head Balloons AX7-77b w/ Parachute top, revision 1, dated OCT 21 2008- BFM supplement for Head Balloons AX8-88 w/ Parachute top, revis...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The Cameron Balloons Ltd. baskets and burner...	19/11/2008	Active	10016687

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.E.S.01000	TEXAS SKYWAYS, INC.		FAA STC SE09131SC	IO-550-F	Removal of fuel injection system and induction system and installation of carburetor in accordance with Texas Skyways, Inc. Specification TS0030, dated 01 May 1995 or FAA later approved revision, based on FAA Supplemental Type Certificate Number SE09131SC		Texas Skyways, Inc. Specification TS0030, dated 01 May 1995or later approved revision.	Approval of this change in type design applies to the aboveengine model only. Compatibility of this modification with previously approved modifications must be determined by the installer. A copy of this Certificate must be maintained as part of the permanent records for the modified engine.The lim...	06/04/2006	Active	10016688
EASA.IM.E.S.01001	AVIATION FLEET SOLUTIONS, LLC	REV 1	FAA STC SE01650SE	JT8D-217, JT8D-217A JT8D-217C, JT8D-219,	Supplemental Noise Configuration: noise addition of normal TO Thrust + Automatic Reserve Thrust System and Landing Flap28o.The previous FAA STC SE01650SE dated 21.03.2006 was approved under EASA approval EASA.IM.E.S.01001 dated 6 June 2006.		FAA approved AFM Supplement AFMS-MD80-1, Rev. A, dated 3 August 2006 for Airplane models MD-81/-82/-83/-88.FAA approvedAFM Supplement AFMS-MD87-3, Rev. A, dated 3 August 2006 forAirplane models MD-87.FAA approved AFM Supplement AFMS-MD80-9 (normal TO + ARTS), Rev. IR, dated 3 August 2006 for Airpl...	1. See above AFM Supplements2. This STC is approved only for the product configuration as defined in the approveddesign data referred to in the paragraphs "Description" and“Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by the...	12/02/2007	Active	10016689
EASA.IM.E.S.01002	PETERSEN AVIATION, INC.		FAA STC SE00663WI	LYCOMING ENGINES O-540-F1B5	Addthe following approved fuel: Leaded and unleaded automotive gasoline,91 minimum antiknock index (RON+MON)/2 per ASTMSpecification D-439,D-4814 or per European Norm Standard EN228.Intermixing with aviation gasoline is also approved.		Petersen Drawing No. 540-2 dated July 10, 1990, or later approved revisions	1. This STC is limited to engine installations on Robinson Model R44Helicopters only. The manifold pressure and RPM limitations in the FAAApproved Robinson R44 Flight Manual must be maintained. Maximum Take offpower is limited to 225 BHP.2. If the holder agrees to permit another person to use this c...	23/02/2006	Active	10016690
EASA.IM.E.S.01005	CENTRI-LUBE TECHNOLOGIES, LLC		FAA STC SE00584DE	TIO541A, -E SE., TIGO541E SE.	Installation of modified Oil Fitter Adapter, an increased opening pressure spring for filter bypass, and modified filter stud in accordance with Firewall Forward Technologies. Inc. Master Document List No. FFT-MDOCLST-OILSTUD-001, Rev. B, dated August 8, 2005 or later FAA approved revision.		Installation Instructions FFT-INILYC-OILSTUD-001Continued Airworthiness Instructions FFT-CAILYC-OILSTUD-001	Compatibility of this design change with previously approved modifications must be determined by the installer.If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permissionRefer to original equip...	18/01/2007	Active	10016691
EASA.IM.E.S.01006	PRATT & WHITNEY		FAA STC SE00033EN	CFM56-3B1	Installation of Pratt & Whitney (P&W) Global Material Solutions (GMS) CFM56-3 High Pressure Compressor Module in accordance with P&W GMS Drawing List 880500-01C dated May 06, 2008or later EASA-approved revisionEASA Certification Basis:1. Airworthiness Standards:JAR-E Change 2 (BCAR Issue 9 dated...		Refer to P&W GMS Service Bulletin PWGMS 72-2 Revision 2, dated December 17, 2008, and later approved revision.	Limitations:1. The limitations of the EASA Engine Type Certificate Data Sheet E.066 issue 1, dated November 28, 2008apply to this Supplemental Type Certificate.2. Life limits for the parts approved by this Supplemental Type Certificate are published in the Airworthiness Limitations section of...	22/12/2008	Active	10016692
EASA.IM.E.S.01007	PRATT & WHITNEY		FAA STC SE00034EN	CFM56-3B1	Installation of Pratt & Whitney (P&W) Global Material Solutions (GMS) CFM56-3 High Pressure Turbine Module in accordance with P&W GMS Drawing List 880500-01D dated May 06, 2008 orlater EASA-approved revisionEASA Certification Basis:1. Airworthiness Standards:JAR-E Change 2 (BCAR Issue 9 dated 18...		Refer to P&W GMS Service Bulletin PWGMS 72-3 revision 2, dated December 17, 2008, and later approved revision.	Limitations:1. The limitations of the EASA Engine Type Certificate Data Sheet E.066 issue 1, dated November 28, 2008apply to this Supplemental Type Certificate.2. Life limits for the parts approved by this Supplemental Type Certificate are published in the Airworthiness Limitations section of...	22/12/2008	Active	10016693

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.E.S.01008	PRATT & WHITNEY		FAA STC SE00035EN	CFM56-3B1	Installation of Pratt & Whitney (P&W) Global Material Solutions (GMS) CFM56-3 Low Pressure Turbine Module in accordancewith P&W GMS Drawing List 880500-01E dated May 06, 2008 or later EASA-approved revisionEASA Certification Basis:1. Airworthiness Standards:JAR-E Change 2 (BCAR Issue 9 dated 18J...		Refer to P&W GMS Service Bulletin PWGMS 72-4 revision 2, dated December 17, 2008, and later approved revision.	Limitations:1. The limitations of the EASA Engine Type Certificate Data Sheet E.066 issue 1, dated November 28, 2008apply to this Supplemental Type Certificate.2. Life limits for the parts approved by this Supplemental Type Certificate are published in the Airworthiness Limitations section of...	22/12/2008	Active	10016694
EASA.IM.E.S.01009	PRATT & WHITNEY		FAA STC SE00032EN	CFM56-3B1	Installation of Pratt & Whitney (P&W) Global Material Solutions (GMS) CFM56-3 Fan and Booster Module in accordance withP&W GMS Drawing List 880500-01B dated March 14, 2008 or later EASA-approved revisionEASA Certification Basis:1. Airworthiness Standards:JAR-E Change 2 (BCAR Issue 9 dated 18 Aug...		Refer to P&W GMS Service Bulletin PWGMS 72-1 revision 2, dated December 17, 2008, and later approved revision.	Limitations:1. The limitations of the EASA Engine Type Certificate Data Sheet E.066 issue 1, dated November 28, 2008apply to this Supplemental Type Certificate.2. Life limits for the parts approved by this Supplemental Type Certificate are published in the Airworthiness Limitations section of...	22/12/2008	Active	10016695
EASA.IM.E.S.01010	CENTRI-LUBE TECHNOLOGIES, LLC		FAA STC SE01436LA	TIO-541A, -E SE., TIGO-541-E S O/IO/AEIO-540, TIO/ LTIO-540	Installation of Firewall Forward Technologies, LLC modifiedcamshaft in accordance with Master Drawing List FWF-MDL-ST9721 LA-E, revision G, dated 2/14/03 or later FAA approved revision.		Installation Instructions FFT-INI-001Continued Airworthiness Instructions FFT-CAI-001	This installation must be done concurrently with EASA STC No. EASA.IM.A.S.02277, which modifies the airplane installation.Compatibility of this design change with previously approved modifications must he determined by the installer. The installation should not be incorporated in any engine unless i...	06/02/2007	Active	10016696
EASA.IM.E.S.01011	CENTRI-LUBE TECHNOLOGIES, LLC	REV. 1	FAA STC SE00590DE	SEE FAA AML SE00590DE O/LO/HO/IO/LIO-360 AIO/AEIO/HIO/TIO/ TO-360 AEIO-/AIO-/IO-/O-/ LIO-320	Installation of a Lubricated Camshaft in accordance with Master Drawing List FFT-MDL-ST3370DE-E, Revision IR dated September 9, 2005, FAA approved September 26, 2005, or later FAAapproved revision.		Installation Instructions FFT-INI-002Continued Airworthiness Instructions FFT-CAI-002	1. All engine installation criteria and limitations are unchanged and remain in effect. Installation of engines modified by this STC must be in accordance with the original aircraft installation criteria.2. Instructions for Continued Airworthiness, Firewall Forward LLC Report FFT-CA1-002, Revision I...	05/02/2007	Active	10016697
EASA.IM.E.S.01012	JET ENGINEERING LLC		FAA STC ST01944LA	PRATT & WHITNEY JT8D-219 PRATT & WHITNEY JT8D-217C PRATT & WHITNEY JT8D-217A PRATT & WHITNEY JT8D-217	Installation of a JET Engineering, Ltd. Turbine Exhaust Cone Mixer (TECM)		- JET Engineering Master Drawing List (MDL) No. 205-1000, Rev. D, dated January 17, 2007, or later approved revisions.- JET-TR-805 "Supplemental Structural Inspection Requirements", Revision N/ C, dated April 27, 2004, or later approved revisions	This installation must be done concurrently with STC EASA.IM.A.S.02331, installation of Jet Engineering, Ltd. Advanced Jet Nozzles which modifies the airplane engine installation.Approval of this change in type design applies to the above engine model(s) only and must have United Technologies/P & Wl...	05/03/2007	Active	10016698
EASA.IM.E.S.01013	ENGINE TECHNOLOGIES, Inc.		SE10589SC	TELEDYNE IO-550-N	Installation of turbonormalizing system in accordance with Engine Technologies, Inc. Master Drawing List Number ETI-G2-1, Rev. NC, dated November 1, 2006, or later FAA approved revision.		Pilot's Operating Handbook and FAA Approved Airplane FlightManual Supplement for Tornado Alley Turbonormalizing System	1. Approval of this change in type design applies to the above model engine only. This approval should not be extended to enginesof this model on which other previously approvedmodifications are incorporated unless it is determined thatthe interrelationship between this change and any of those o...	02/04/2007	Active	10016699
EASA.IM.E.S.01016	AERODYME CORPORATION		FAA STC SE00242BO	IO-580-B1A	Installation of induction intake pipes in accordance with Aerodyme 114/A/B/TC 320 HP Engine Conversion Installation Instructions, dated July 20th 2006,or later revisions of the above listed document approved by EASA in accordance with ED decision 2004/04/CF (or subsequent revisionsof this decission)...		Instructions for operation, maintenance and inspection:Doc.No. AD526-01: 114/A/B/TC 320HP Engine Conversion – Instructions for Continued Airworthiness	1. This STC must be installed concurrently with STC EASA.IM.A.S.02653.2. If the holder agrees to permit another person to use this certificate to alter a product, the holdermust give the other person written evidence of that permission.	04/03/2008	Active	10016701

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.E.S.01017	PRATT & WHITNEY		FAA STC SE00026EN	ROLLS-ROYCE 250-C20S ROLLS-ROYCE 250-C20R/2 ROLLS-ROYCE 250-C20R/1 ROLLS-ROYCE 250-C20J ROLLS-ROYCE 250-C20F ROLLS-ROYCE 250-C20B ROLLS-ROYCE 250-C20 ROLLS-ROYCE 250-C18A ROLLS-ROYCE 250-C18	Installation of Pratt & Whitney Engine Services, Inc. IntelliStart Plus +TM Electronic Control Unit (ECU), P/N DPU-K-010 on the specified 250 engine models.		Airframe installation of the Altair Avionics Corporation - AlliedSignal Aerospace IntelliStart Plus +TM to be accomplished in accordance with applicable airframe STC.	1. The IntelliStart Plus +TM ECU is desinged to limit starttemperatures and to provide an electronic aid for recordingengine trend and cycle data.2. The IntelliStart Plus +TM ECU is designed as non-essential, ground use only equipment and cannot be used to replace pilot monitoring during start asF...	14/03/2008	Active	10016702
EASA.IM.E.S.01018	PRATT & WHITNEY		FAA STC SE00029EN, LBA EN0034	HONEYWELL INT. T5317 HONEYWELL INT. T5313B	Installation of Pratt & Whitney Engine Services, Inc. SmartCycle Plus Engine Monitoring System, P/N EMU-K-010-1 on the specified T53 engine models			1. SmartCycle Plus Engine MonitoringSystem is designed as an electronic aid for recording engine trend and cycle data.This system does not eliminate any scheduled maintenance or parts replacement based on time or any engine Instructions for Continued Airworthiness monitoring requirements. Nor does i...	04/03/2008	Active	10016703
EASA.IM.E.S.01019	PRATT & WHITNEY		FAA STC SE00027EN	ROLLS RROYCE 250-C	Installation of Pratt & Whitney Engine Services, Inc. IntelliStart Plus +TM Electronic Control Unit (ECU), P/N DPU-K-010 on the specified engine models		Airframe installation of the Pratt & Whitney Engine Services, Inc. InstelliStarat Pluy +TM to be accomplished in accordance with applicable airframe STCs.	1. The IntelStart Plus +TM ECU is desinged to limit start temperatures and to provide an electronic aid for recording engine trend and cycle data.2. The IntelliSTart Plus +TM ECU is designed as non-essential, ground use only equipment and cannot be used to replace pilot monitoring during start as re...	14/03/2008	Active	10016704
EASA.IM.P.S.01003	WESTERN PROPELLER (PACIFIC) Ltd.		TCCA STC SP96-1	3GFR34C703	Installation of a Zero Stop Latch AssemblyTo hold the propeller in zero pitch during engine start to prevent float and ski equipped aircraft from surging forward during transitionfrom feather to beta range. In accordance with the data contained in Western Propeller Master Document List No. WPL-C703...		- Transport Canada STC No. SP96-1, Issue 3 dated 14.4.08- FAA STC No. SP00519NY dated 9.10.1996- FAA TCDS No. P60GL, Rev. 3 dated 30.5.06- WPL-C703-6 Zero Latch Assembly, Rev. B dated 7 May 2001 incl.: - WPL-C703-1 Zero Stop Latch Assembly, Rev. B dated 7.5.08 - WPL-C703-2 C-5013 WPL Piston Mo...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.This approval is only applicable to the type...	23/01/2009	Active	10016705
EASA.IM.R.S.0030	INTEC HELICOPTERS Inc.			BELL 407 BELL 206 A,B,B1, L-1, L-3, L-4	Installation of Engine air filter in accordance with INTEC MasterDrawing List No. 1206 No. 1206-1001 Revision F1, dated30 JAN 2004 (orlater EASA Approved revision).			1. A copy of this STC and the appropriate approved Flight ManualSupplement (see INTEC Master Drawing List N° 1206-1001)must bemaintained as part of the permanent records for the modified aircraft.Additionally, for Bell Model 206-A, B and B1 aircraft, a copy of BellHelicopter Flight Manual Supplemen...	09/07/2004	Active	10043056
EASA.IM.R.S.0039	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE			MD900	Installation of Apical Industries, Inc. Emergency Floats and 6-man LifeRaft Kits, Part Number 20754-100, or -200, in accordance with II900-2,Installation Instructions MD900 Emergency Float Kits, Revision E, dated1 April 2002 or later EASA-approved revision.			1. This approval requires the inspections and overhaul schedules to beperformed as mandated by the Instructions for Continued Airworthiness,ICA 900-2, dated 25 July 2001, or laterEASA approved revision.2. The Rotorcraft Flight Manual Supplement FMS900-3 is required whenoperating with the installed3...	13/07/2004	Active	10061996

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.0048	PRATT & WHITNEY	REV. 1	N 2004-6170	BELL 412 EP BELL 412 BELL 222U BELL 222B BELL 222 BELL 212 AGUSTA AB-412EP AGUSTA AB-412	Installation of Pratt & Whitney Engine Services, Inc. SmartCycle monitoring and recording system		Installation Manual Instruction for Continued Airworthinessas listed in document ref. AML SR00170BO, or later approvedrevision	1. Required maintenance, as prescribed in the applicable airframe or engine Instructions for Continued Airworthiness, shall not be predicted on the data obtained from Pratt & Whitney Engine Services, Inc., monitoring/recording system.2. This system shall not be used to supersede or replace the pilo...	25/03/2008	Active	10016707
EASA.IM.R.S.00548	BELL HELICOPTER TEXTRON, Inc.		FAA SR02381AT	427	Manufacture and Installation of Passenger Sliding Door for Bell 427 Model Helicopters (FAA STC SR02381AT dated 19/09/2002).		-AAI Master Drawing List Report AA-98094 dated 14/04/1999.-Installation Instructions AA-98085 Revision B dated 29/11/2001.-Rotorcraft Flight Manual Supplement AA-99080 dated 2/10/2001.-Instructions for Continued Airworthiness AA-99043 dated 5/12/2001.	1. Rotorcraft Flight Manual Supplement dated 7/09/2001, is a required part of this STC.2. 'Instruction for Continued Airworthiness', AAI Report No. AA-99043, Revision A dated 6/10/2000 is also a required part of this STC.3. This STC is approved only for the product configuration as defi...	26/01/2005	Active	10016708
EASA.IM.R.S.00550	AERONAUTICAL ACCESSORIES, INC		FAA STC SR02196AT	BELL MODEL 427	Manufacture and Installation of Flitestep/ Floatstep for Bell 427 ModelHelicopters (FAA STC SR02196AT)		- AAI Master Drawing List Report AA-98149 dated 31/08/2000.- Installation instructions to Floatstep Kit P/N 427-303-001.	1. Inspection and Maintenance Requirements are listed in AeronauticalAccessories, Inc. Report No. AA-99048, revision B dated 23/02/2000 orlater FAA approved revision.2 This STC isapproved only for the product configuration as defined inthe approved design data referred to in the paragraph "Descript...	26/01/2005	Active	10077592
EASA.IM.R.S.00619	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR00470LA	AS 350 B/D/BA/B1/B2/B3	Emergency Flotation Kit installation according to FAA STC No. SR00470LA issued on November 17, 1997 and reissued December 22, 1998.		- EASA-approved AS 350 Flight Manual and RFM Supplement Apical FMS-350(2) dated October 15, 1997, or later FAA-approvedrevisions are required.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	14/04/2005	Active	10016710
EASA.IM.R.S.00623	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01166SE	EUROCOPTER FRANCE AS 350 B3	Cargo Hook Kit installation, in accordance with FAA STC No.SR1166SE issued January 22, 2003.		- AS 350 B3 Flight Manual and RFM Supplement Onboard No. 121-014-00 dated January 15, 2003, and revised on July 23, 2004 or later approved revisions.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	15/03/2005	Active	10016711
EASA.IM.R.S.00624	INTEC HELICOPTERS Inc.			EC 120 B	Installation of an Engine Air Filter, in accordance with FAA STC No.SR01191SE, issued on March 17, 2003		Definition: INTEC Master Drawing List No. 1120-1001, Revision B datedMay 06, 2003, or later approved revisionsInstallation: INTEC Installation Instructions 1120-INST-1 Revision Bdated May 06, 2003 or later approved revisionsInspection and Maintenance: INTEC Document 1120 Series-ICA-1 Revision IRdate...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	15/03/2005	Active	10061559
EASA.IM.R.S.00696	EAGLE COPTERS MAINTENANCE Ltd.		TCCA STC NO. SH93-34	3) 205A-1 2) 214B, 214B-1 1) 212, 412, 412CF, 412EP	Validation of Transport Canada STC No. SH93-34 issue 2.External Cargo Hook Release System for Co-Pilot Position		Airworthiness Compliance Report ACR-D412-704-1 Rev. A	1. Installation Instruction INN-D412-704 Rev. A2. Instruction for Continued Airworthiness ICA-D412-704 Rev. 13. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurat...	22/04/2005	Active	10070190

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.00709	EAGLE COPTERS MAINTENANCE Ltd.		TCCA STC NO. SH92-43	412, 412 CF, 412 EP 212, 214B, 214B-1 204, 205A-1, 205B	TC STC SH92-43, Serviceable Kit: Auxiliary Cow. Latches, Cockpit DoorSupport Kit, Cabin Door Handles and Modified Roller System for slidingcabin door (configuration 2)		-Dart Aerospace Ltd. Installation Instruction IIN-D412-698 Rev. B orlater approved revision-Instruction for Continued Airworthiness ICA-D412-698, Revision 1 orlater approved revision	1. This approval is limited to configuration 2 only.2. ThisSTC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	10/05/2005	Active	10070188
EASA.IM.R.S.00710	DART AEROSPACE Ltd.	REV. 1	TCCA STC SH04-7	BELL 412 EP BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1 BELL 205A	Installation of D412-702 Shoulder Harness Kits. Transport Canada STC No SH04-7 issue 1 dated 6th February 2004. The purpose of these kits is to add shoulder harnesses to existing seats that are only equipped with lap belts.		¿ MDL-D412-702 – Master Drawing List, Revision E dated 27-April-2007 or later approved revision;¿ IIN-D412-702 – Installation Instruction, Revision D dated 12-April-2007 or later approved revision;¿ ICA-D412-702 – Maintenance Manual Supplement, Revision 3 dated 12-April-2007 or later approv...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	09/08/2007	Active	10016712
EASA.IM.R.S.00712	DART AEROSPACE Ltd.		TCCA STC NO. SH04-25	212, 412, 412 CF, 412 EF	Installation of Twin Park E-Z Access Kit - STC SH04-25		Dart Aerospace Ltd. Installation instruction IIN-D412-705 Rev. A datedFebruary 20, 2004 or later Transport Canada approved revisionInstruction of Continued Airworthiness ICA-D412-705, Initial issue datedMarch 9, 2004 or later revision are required with this installation.	1. This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	13/06/2005	Active	10070189
EASA.IM.R.S.00713	HELIPOD USA LLC			R44, R44II	validation of FAA STC SR01418SE for the Single or Dual Installation ofExtemal Cargo Pods on Robinson R44 and R44II.		Master Drawing List MDL .NW011-HP-25-005 Rev. I dated 02.06.2004 orlater EASAapproved revisions.Installation Instruc;tionsNW011-HP-25-005 dated 05.02.2004 or later EASAapprovedrevisions..Instructions for Continued Airworthiness NW011-HP-25-005 dated03.05.2004 or later EASAapproved revisions.FAA appr...	1. The installation of the Helipod External Cargo Pods isnotcoll1patible with any FloatsInstallations.2. This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraph "Description". Compatibility withother aircraft/ engineconfigurations shal...	27/06/2005	Active	10051161
EASA.IM.R.S.0078	SIMPLEX MANUFACTURING CO.		FAA STC SR00684SE, DGAC SPAIN	EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of Simplex anti-fire system Model 310-900, 310-1100 and 310-1200			1. This STC is approved only for the product configuration as defined in the approved design data referred to in theparagraph “Description”. Compatibility with other aircraft/engine configurations shall be determined by the installer.	06/10/2004	Active	10016713
EASA.IM.R.S.01010	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR00836NY	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Cargo Compartment Baggage Liner.		-FAA STC SR00836NY.-Keystone Helicopter Cor. Installation Drawing IDL00081, Revision A, dated January 29, 1998.	1. Keystone Helicopter Corp. Maintenance Manual S-76A, B&C Baggage Liner, Report No MM00081 dated February 17, 1997, asrequired.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other airc...	11/04/2005	Active	10016716

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01011	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01131NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Luminescent Systems Helicopter Emergency Egress System (HEELS)		-FAA STC SR01131NY-D.-Keytech Installation Drawing List IDL00565 Revision A dated April 12 2002 or later approved revision.-RFM Supplement No FM00565, no revision, approved December 10 2002.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	19/04/2005	Active	10016717
EASA.IM.R.S.01012	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01593NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Keystone Helicopter Utility Interior Panels		-FAA STC No SR01593NY-D.-Keytech Installation Drawing List (DL00569 Revision B dated July 13 2004 or later approved revision).	1. Keystone Helicopter Instructions for Continued Airworthiness Report No IC00735 Rev_dated June 11, 2004 or later approved revision. 2. It is a prerequisite to have previously approved brackets installed for each individual panel installation as denoted in Keystone Helicopter IM00569, "Installation3...	22/04/2005	Active	10016718
EASA.IM.R.S.01013	APICAL INDUSTRIES, Inc.		FAA STC SR00780LA	EC 120 B	Installation of Apical Emergency Float Kit, p/n 20498.The present STC is the validation of the FAA STC n° SR00780LA issued on 19/03/1999.		-FAA STC No SR00780LA issued on 19/03/1999.-Definition: Master Document List MD120-1, revision D dated March 18, 1999 approved by FAA or later FAA-approved revisions.-Installation: Installation and Packing Instructions II120-100, revision C dated May 12, 1999 approved by FAA or later FAA-approvedrev...	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	11/04/2005	Active	10016719
EASA.IM.R.S.01014	AEROLITE AG		-	A109E	Installation of Medical Oxygen Cabinet P/ N 109111-501		-Installation Manual IM-502	1. No Smoking when Medical Oxygen Cabinet is installed2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	18/05/2005	Active	10016720
EASA.IM.R.S.01016	GEOTECH Ltd.		-	AS 350 SERIE	Survey System Installation (Structural & Electrical Power provisions)		-DECA Aviation Engineering Ltd Modification Summary MS04193Revision 1 dated December 2, 2004 or later approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	31/05/2005	Active	10016721
EASA.IM.R.S.01018	ISOLAIR Inc., ISOLAIR HELICOPTER SY		FAA STC SR01410NY	AS350 B1, -B2, -B3, -BA	Installation of Isolair spray system model 3900-350B2.		- DECA Aviation Flight Manual Supplement No. 4849-02, Rev. 2, dated 22August 2000, or later approved revisions.- DECA Aviation Modifications Summary List No. MS0006907, Issue 3, dated5 April 2001, or later approved revisions.- Isolair Instructions for Continued Airworthiness no. 3900-350B2ICA,Rev. B...	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	16/06/2009	Active	10041184
EASA.IM.R.S.01019	AEROLITE AG		-	MD900, MD902	External Hoist Mirror Installation P/N 9005024-501, P/N 9005024-502, P/N 9005024-503, P/N 9005024-504.Flight Manual Supplement FMS-404.		Flight Manual Supplement FMS-404.	1. Only for VFR operations.2. Only approved configurations to be installed.3. This STC is approved only for the productconfiguration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the...	08/07/2005	Active	10016722

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01021	DART AEROSPACE Ltd.		SH04-31	BELL 412 EP BELL 412 CF BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1	Installation of Replacement Window Kits		Installation must be in accordance with Dart Aerospace Installation Instruction IIN-D412-709rev A or later approved revisionMaintenance must be in accordance with Dart Aerospace Instruction for Continued Airworthiness ICA-D412-709 Rev A TCCA accepted or later approved revision		02/01/2006	Active	10016723
EASA.IM.R.S.01022	AIRBUS HELICOPTERS CANADA LIMITED	REV. 1	TCCA STC SH96-39	AS 350 BA, AS 350 B2,AS 350 B3	Two place forward passenger seat (RH)		Refer to Master Drawing List MDL-96-004 issue I and associated installation procedure and maintenance instructions.	1. Refer to Flight manual supplement attached to STC SH96-39 issue 5 approved 12 April 1996 or later approved revision.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft...	19/12/2005	Active	10016724
EASA.IM.R.S.01028	HERITAGE AVIATION LIMITED		FAA STC SR09407RC	EUROCOPTER FRANCE EC 155 B1	Installation of Forward and Aft Facing Passenger Couch		Heritage Aviation Master Drawing List 700-13000 Revision _ dated April 29, 2004 or later approved revision.Instructionsfor continued Airworthiness for Three/Four Place Passenger Couch Installation, Heritage Aviation Ltd. Document No. 708-73000 dated April 2, 2004 or later accepted revision.		20/07/2005	Active	10016727
EASA.IM.R.S.01032	TECH-TOOL PLASTICS, Inc.		FAA STC NO SR03016AT	BELL 407	Installation of windows for Bell 407 Model Helicopters in accordance with:-the FAA STC SR03016AT dated 7/1/2005.-MasterDrawing List 407-1000-100, dated 23/2/2004.		Window installation 407-2000 dated 11/2/2004Window Assy, Windshield 407-1001 dated 10/10/2003Window Assy, Lower Nose 407-1002 dated 10/7/2003Window Assy, Lower Nose Quick Change 407QC-1002 dated 9/10/2003Window Assy, Skylight 407-1003 dated 10/10/1003Window Assy, Forward Door 407-1004 dated 17/10/2...	1. The compatibility of this design change with other previously approved modifications must be determined by the installer.2. This STC is approved only for the product configuration as defined in the approved design data referred toin the paragraph "Description". Compatibility with other air...	20/09/2005	Active	10016729
EASA.IM.R.S.01048	ASTEC HELICOPTER SERVICES AS		-	S-61N	Installation of Honeywell MST 67A Mode S Transponder		1) Master Drawing List reference AHSE-51550 rev - or later approved revisions.2) Aircraft Flight Manual Supplement No AHS-042 dated 16.03.05 or later approved revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	22/11/2005	Active	10016730
EASA.IM.R.S.01057	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR00033NY	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Grease Fittings.		-FAA STC n° SR00033NY.-Keytech Corporation Installation Drawing List Report No IDL93-32 revision B dated January 18, 1999 or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	22/04/2006	Active	10016733

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01058	SIKORSKY GLOBAL HELICOPTERS Inc.		SR01596NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Universal Avionics Systems Corporation UNS-1 Multi-Mission Management Systems (MMMS) with SCN 901.X Software		Keytech Installation drawing list No. IDL00668 Rev D Dated October 17 2003 or later approved revision.Keystone Helicopter Corp. RFM Supplement No. FM00668 Revision 1 dated February 2006 or later approved revision.		06/03/2006	Active	10016734
EASA.IM.R.S.01059	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01132NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Honeywell KTA870 Traffic Advisory (TAS) displayes on a Honeywell KD550 Multifunctional Display (MFD)Ass.:Report ER00566Certification PlanRFM Supplement FM00566		Report ER00566 Certification PlanRFM Supplement FM00566	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	18/11/2005	Active	10016735
EASA.IM.R.S.01060	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01608NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Aircell ST 3100 Satellite Telephone System		Keystone Helicopter installation drawing list IDL00783, Revision A dated 5/18/04 or later approved revisionKeystone Helicopter AFM Supplement No FM00783 Rev 1 dated 24 August 2005or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	23/02/2006	Active	10016736
EASA.IM.R.S.01061	SAFRAN ELECTRONICS & DEFENSE,AVIONICS USA, LLC		SR09291RC-D	EUROCOPTER FRANCE EC 130 B4	Original STC nbr: FAA STC SR09291RC-D, amended 06-Oct-2006Installation of a two-axis VFR auto-pilot		- Definition and Installation:Heritage Aviation Ltd., Master Drawing List 130A82-8014 revision H, dated June 26, 2006, approved by FAA or later FAA approved revisions- Inspection and Maintenance:Instructions for Continued Airworthiness (maintenance manual supplement) PA85-130MMS-001 revision C...		08/12/2006	Active	10016737
EASA.IM.R.S.01063	TEST INSTRUMENTATION Inc.		FAA STC SR00052SE	R44, R44 11	Installation of Classic Aircraft products Cargo Hook SystemCH-800 in accordance with FAA STC SR00052SE		EASA approved Rotorcraft Flight Manual No 44-510EU	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	21/04/2006	Active	10016738
EASA.IM.R.S.01064	AEROMETALS INC.		FAA STC SH3756NM	MD HELICOPTERS 369HS 369H, 369HE, 369HS	Installation of Aerometals tailboom P/N 369X3500-505 or Yehnert tailboom P/N YH-203.The present STC is the validation of the FAA STC SH3756NM amended on 30/11/99, limited to MDHI 369H, HS and HE models.		Aerometals Tailboom P/N 369X3500-505:- Installation Instructions: Aerometals Master Drawing List (MDL) No 25, revision B dated 22/10/99 approved by FAA or later FAA-approved revision.- Instructions for Continued Airworthiness: Aerometals Instructions for Continued Airworthiness AMI-14 dated 04/05/99...	1. Service life of the Aerometals and Yehnert referenced tailbooms is established according to FAR 27.571 (e) at 10000 flight hours, with periodic inspections required at 2450 flight hours and each 2450 flight hours thereafter.2. Inspections of the Aerometals and Yehnert referenced tailbooms shall b...	30/05/2005	Active	10016739
EASA.IM.R.S.01065	AEROMETALS INC.		FAA STC SH5055NM	369D, 369E, 369FF	Installation of- Aerometals tailboom:- P/N 369X23500-505 asreplacement of MDHI tailboom P/N 369D23500-505, or-P/N 369X23500-507 as replacement of MDHI tailboom P/N 369D2300-507, or- Yehnert tailboom :- P/N YH-228-1 as replacement of MDHI tailboom P/N 369D23500-101, orP/N YH-228-3 as replacement ofP...		Installation Instructions and Instructions for Continued Airworthiness: see table in the paragraph "Limitations and Conditions" herafter.	1.Service life of the Aerometals and Yehnert referenced tailbooms is established according to FAR 27.571 (e) at 10300 flight hours,with periodic inspections required at 7300 flight hours and each 1000 flight hours hereafter.2. Inspections of- the Aerometals referenced tailbooms shall be conducted in...	17/05/2005	Active	10016740

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01068	AEROLITE AG	REV. 1		AB139	Installation of Aerolite EMS equipment P/N 139001-501, 139001-502		Rotorcraft Flight Manual Supplement FMS-502, FMS-510Operational Maintenance Manual OPM-501MDL-405 rev A	1. No smoking permitted when the Oxygen system is installed.2. The occupant of the LH forward Aft facing seat must wear a helmet.3. For the installation of the EMS equipment the following Agustaequipment must be installed:-the EMSElectrical System Dwg No. 3G2564W00101 to supply the EMS sys...	19/06/2006	Active	10016742
EASA.IM.R.S.01069	DEVORE AVIATION CORPORATION OFAMERICA		FAA STC SH4694SW	S-76A/B/C	Installation of Under Fuselage forward facing recognitionn lights and rotor disc lights		Top Drawing 07600002 Revision C dated August 16, 2004 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	31/05/2006	Active	10016743
EASA.IM.R.S.01070	DEVORE AVIATION CORPORATION OFAMERICA		FAA STC SH5867SW	AS 365N/N1/N2, EC 155B/B1	Installation of Tail Floodlights and Associated Technical Documentation Devore Drawing List 36500001 Revision J dated March 16 1999DCN F-1 dated February 8 1989 & DCN L-1 dated October 22 2001 or later approved revision		Devore Drawing List 36500001 Revision J dated March 16 1999DCN F-1 dated February 8 1989 & DCN L-1 dated October 22 2001 or later approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	21/06/2005	Active	10016744
EASA.IM.R.S.01071	DEVORE AVIATION CORPORATION OFAMERICA		FAA STC SH5866SW	AS 365N/N1/N2, EC 155B/B1	Installation of Forward Facing Recognition Lights		Devore Drawing List 36500002 Revision C dated July 2 2001 or later approved revision. Devore Aviation Corportalon RFM Supplement dated June 10 2002 or later approved revision.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	21/06/2005	Active	10016745
EASA.IM.R.S.01072	DEVORE AVIATION CORPORATION OFAMERICA		FAA STC SH7579SW	AS 365N1/N2/N3, EC 155B/B1	Installation of a rotor disc light and associated DeVore Aviation Corporation Top Drawing-Rotor Disc Light Inspection; AerospatialeDauphin Drawing 36500003 revision E dated August21 2001 or later approved revision DeVore Aviation Corporation RFM Supplemetn dated June 10 2002 or later approved rev...		Devore Aviation Corporation Top Drawing-Rotor Disc Light InspectionAerospatiale Dauphin Drawing 36500003 revision E dated August 21 2001 or later approved revisionDevore Aviation Corporation RFM Supplement dated June 10 2002 or later approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	22/06/2005	Active	10016746
EASA.IM.R.S.01074	DART AEROSPACE Ltd.		TCCA STC SH04-30, ISSUE 2	ROBINSON R22 BETA ROBINSON R22 ALPHA	Validation of TCCA STC SH04-30 for the installation of Cabin Floor Protectors.		Installation Instructions IIN-D022-720, Revision A dated 6.04.2004 or later TCCA approved revisions.Instructions for Continued Airworthiness ICA-D022-720 Revision 0 or later TCCA accepted revisions.	1. Installation and Maintenance in accordance with the above referenced Technical Documentation.2. This STC is approvedonly for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall...	14/06/2005	Active	10016748
EASA.IM.R.S.01075	DART AEROSPACE Ltd.		TCCA STC SH04-40, ISSUE 1	ROBINSON R44 II ROBINSON R44	Validation of TCCA STC SH04-40 for the installation of Cabin Floor Protectors.		Installation Instructions IIN-D044-719, Revision A dated 4.06.2004 or later TCCA approved revisions.Instructions for Continued Airworthiness ICA-D044-719 Revision 0 or later TCCA accepted revisions.	1. Installation must be performed in accordance with Installation Instructions IIN-D044-719.2. Maintenance in accordance with Instructions for Continued Airworthiness ICA-D044-719.3. This STC is approved only for the product configuration as defined in the approved design data referred to in the par...	14/06/2005	Active	10016749

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01076	DART AEROSPACE Ltd.		TCCA STC SH05-7, ISSUE 1	ROBINSON R44 II ROBINSON R44	Validation of TCCA STC SH05-7 for the Installation of a Cold Weather Baffle Kit for Cold Weather operation of Robinson R44 and R44II.		Installation Instrutions IIN-D044-717 Rev. B TCCA Approved 25. 01.2005 or later TCCA approved revisions. Instructions for Continued Airworthiness ICA-D044-717 Rev. O TCCA accepted 01.02.2005 or later TCCA accepted revisions.	1. Installation must be performed in accordance with Installation Instructions IIN-D044-717.2. Maintenance in accordance with Instructions for Continued Airworthiness ICA-D044-717.3. This STC is approved only for the product configuration as defined in the approved design data referred to in the par...	14/06/2005	Active	10016750
EASA.IM.R.S.01078	HELI-LYNX		TCCA STC SH05-8, ISSUE 1	EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E	Installation of Anticipator of Govenor CablesAss.Refer to installation manual IM, PA 04 015 91 01 issue 1 or later approved		Refer to installation manual IM, PA 04 015 91 01 issue 1 or later approved.	1. Refer to instructions for continued airworthiness ICAPA 04 015 05 01 issue 1 or later approved and associated maintenance instructions.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility...	10/10/2005	Active	10016751
EASA.IM.R.S.01079	HELI-LYNX		SH04-27	EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1	Heli-Lynx AS 355 FX System modifications, as per Transport Canada STC n° SH04-27		Heli-Lynx Helicopter Services Master Drawing MDL-PA-03-007-91-01, Issue 19, TCCA approved September 27th, 2004, or later TCCA approved revisions.InstallationHeli-Lynx Helicopter Services Installation Manual IM-PA-03-007-91-01, Issue 3, revision C, TCCA approved September 27th, 2004, or later TCCA ap...		04/04/2007	Active	10016752
EASA.IM.R.S.01082	SIKORSKY GLOBAL HELICOPTERS Inc.		SR00688NY	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Medical Interior		Keystone Helicopter Installation Drawing List IDL00136 Revision C dated March 15, 1999 or later approved revisionKeyston Helicopter RFM Supplement FM00136, FM00136.2 & FM00136.4 dated September 26, 1997 or later approved revision for Sikorsky S-76 A, B & C Models is required for this installation on...		12/05/2006	Active	10016753
EASA.IM.R.S.01083	METRO AVIATION, Inc.		FAA STC SH3880SW	EUROCOPTER DEUTSCHLAND MBB-BK	Installation of a Vapor Cycle Air Conditioner in accordancewith FA STC SH3880SW		FAA approved Flight Manual Supplement EC145 AC FMS	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	31/05/2005	Active	10016754
EASA.IM.R.S.01084	BELL HELICOPTER TEXTRON, Inc.		FAA SR09397RC	206A, 206B	STC ST09397RCIncrease in takeoff weight from 1.451 Kg (3200lbs) to 1.520 Kg (3350 lbs when modified in accordance withBell Model 206 Series Service Instructions BHT-206-SI-129 dated July 12, 2004, or later FAA approved revision.		Rotorcraft Flight Manual Supplement for Increased Internal Gross Weight to 3350 lbs., BHT-206B3-FMS-37, Bell HelicopterTextron Inc., Original Revision, dated July 12, 2004.Instructions for Continued Airworthiness (ICA) for Bell Model 206Bseries helicopters are incorporated in Bell Helicopter Textr...	Aircraft effectivity is as follows: • This STC is limited to 206A or 206B aircraft that are qualified for and configured with the 65 inch diameter tail rotor. • 206A S/N 4 thru 660, and 672 thru 715 if modified to a Model 206B by incorporation of Service Instruction BHT-206-SI-80, 250-C20 Engi...	01/02/2006	Active	10016755

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01085	DART AEROSPACE Ltd.		SH05-10, ISSUE 1	BELL 412 EP BELL 412 CF BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B	Spacedoor Installation		Installation must be in accordance with Dart Aerospace Installation Instruction IIN-D412-694 rev A or later approved revisionMaintenance must be in accordance with Dart Aerospace instruction for Continued Airworthiness ICA-D412-694 Rev A TCCA accepted or later approved revision		02/01/2006	Active	10016756
EASA.IM.R.S.01086	DART AEROSPACE Ltd.		SH94-38, ISSUE 2	SIKORSKY S-76C SIKORSKY S-76A	Installation of Cargo Mirrors		Dart Aerospace Ltd. Drawing No IIN-D076-612 Revision A dated June 26, 2002 or later approved revision		25/01/2006	Active	10016757
EASA.IM.R.S.01087	DART AEROSPACE Ltd.		TCCA STC SH05-14	ROBINSON R22 BETA ROBINSON R22 ALPHA	Installation of Replacement Window Kits in accordance with TCCA STC SH05-14.		Installation Instructions IIN-D022-714, Revision A approved26.09.2004 or later approved revisions.Instructions for Continued Airworthiness ICA-D022-714 Revision 0 Transport Canada accepted 18.03.2005 or later Transport Canada accepted revisions.Flight Manual Supplement FMS-D022-714 Rev. A Transport...	1. Installation, Operation and Maintenance must be held in accordance with the above referenced Technical Documentation. 2. This STC is approved only for the product configurationas defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/eng...	14/06/2005	Active	10016758
EASA.IM.R.S.01088	DART AEROSPACE Ltd.		TCCA STC SH05-13	ROBINSON R44 II ROBINSON R44	Installation of Replacement Window Kit in accordance with TCCA STC SH05-13.		TCCA approved Flight Manual Supplement FMS-D044-713.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	13/06/2005	Active	10016759
EASA.IM.R.S.01089	AIRBUS HELICOPTERS, Inc.		FAA STC SR09281RC-D	EC 155 B1	American Eurocopter LLC Modification FAA STC SR09281RC-D.Installation of a Garmin Global Positioning System (GPS) - GPS500.		AEC Drawing List 155A82-8001 revision E dated April 24 2003or later approved revision. RFM Supplement 155FMS-003 datedApril 29 2003 or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	15/08/2005	Active	10016760
EASA.IM.R.S.01090	AIRBUS HELICOPTERS, Inc.		FAA STC SR09290RC-D	EC 155 B1	Installation of horizontal tip position/anti-collision strobe lights		AE Drawing List 155A82-8007 Revision B dated April 22, 2004or later EASA approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	20/07/2005	Active	10016761
EASA.IM.R.S.01091	BELL HELICOPTER TEXTRON, Inc.		FAA SR09324RC-D	407	Installaton of Passenger photo Window for Bell 407 Model Helicopters in accordance with:-the FAA STC SR09324RC-D dated 22/9/2003-AAI Master Drawing List Report AA-01095, Revision B, dated 19/3/2003.		Instructions for continued airworthiness AA-01093 revision B dated 5/12/2001. Installation instructions Passenger Window Kit AA-01091 dated 18/9/2003, Drawing list AA-1095 dated 3/7/2001.	1. The compatibility of this design change with other previously approved modifications must be determined by the installer.2. This STC is approved only for the product configuration as defined in the approved design data referred toin the paragraph "Description". Compatibility with other air...	22/08/2005	Active	10016762

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01092	HOWARD J. FULLER, JR.		FAA STC SR00081BO	SCHWEIZER 269 C-1	Operation of rotorcraft on unleaded and leaded automotive gasoline, 93 minimum antiknock index (RON+MON)/2 per ASTM Specification D-439 or D-4814 as noted on placard to be installed in accordance with H.J.Fuller Jr. Installation Instructions No. HFJ97269, dated March4, 1997, or later approved revis...		Howard J. Fuller Jr. Rotorcraft Flight Manual Supplement No. 269-1 Revision 2 dated July, 2nd 2004 or later approved revisions.Installation Instructions No. HFJ97269, dated March 4, 1997 or later approved revisions.	1. This STC is limited to those model helicopters equipped with Lycoming HO-360-C1A engines, modified in accordance with FAA STC No. SE2563CE.2. Howard J. Fuller, Jr. Rotorcraft Flight Manual Supplement No. 269-1, Rev 2 dated July 2, 2004,or later approved revisions is required and must be carried3...	23/11/2005	Active	10016763
EASA.IM.R.S.01097	AGUSTAWESTLAND PHILADELPHIACORPORATION		TCCA STC SH284NE	A109A, A109AII	Installation of Alternate Static Pressure Source		Configuration A: in accordance with Agusta drawings 109-A720-14 and 109-A310-55-77 all dated 27-7-84.Configuration B: Agusta kit No. 109-A720-14, in accordance with Agusta ServiceInstruction No. 109-A-005 dated 11 February 1985.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.Configuration A is eligible only on aircraft S/N 7266.When altern...	04/07/2005	Active	10016766
EASA.IM.R.S.01098	BELL HELICOPTER TEXTRON, Inc.		FAA SR01450LA	407	Installation of Apical Industries, Inc. Emergency Float Assemply, Part number 604.9501 for Bell 407 Model Helicopters in accordancewith:-the FAA STC SR01450LA dated 27/5/2003.-Master document List MD407-11 Revision C, dated 28/4/2003.		Apical Industries, Inc. Rotorcraft Flight Manual SupplementFMS 407 (11) FAA approved on 13/5/2003.Instructions for continued airworthiness ICA407-11 Revision A dated 19/5/2003.Approvel landing gears for Apical Emergency Floats kit. ReportNo AI407-18 dated 22/5/2003.Installation Instruction Lightwe...	1. The compatibility of this design change with other previously approved modifications must be determined by the installer.2. This STC is approved only for the product configuration as defined in the approved design data referred toin the paragraph "Description". Compatibility with other air...	22/08/2005	Active	10016767
EASA.IM.R.S.01099	HERITAGE AVIATION LIMITED		FAA STC SR00530NY	EUROCOPTER FRANCE EC 155 B1	Installation of a Cocoon wall panel system		Advanced Flight Systems Inc. Installation Drawing List Report No. 913-030-001 Original Revision dated 15 June 2001 or later approved revisions.	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	18/07/2005	Active	10016768
EASA.IM.R.S.01100	AIRBUS HELICOPTERS, Inc.		FAA STC SR09282RC-D	EC 155 B1	American Eurocopter LLC Modification FAA STC SR09282RC-D. Installation of a Honeywell Enhanced Ground Proximity WarningSystem.		ABC Drawing List 155A82-8004 revision C dated April 17 2003or later approved revision.RFM Supplement 155FMS-005 dated April 22 2003 or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	11/08/2005	Active	10016769
EASA.IM.R.S.01102	BELL HELICOPTER TEXTRON, Inc.		FAA SR09239RC	407	Installation of a Steerable Landing Light.		FOO-12001 Revision B dated 15 October 1999 or later approved revision - Premier Aviation Master Drawing List.F09-62003 Revision - dated 16 March 2000 or later approved revision - Premier Aviation FMS.F08-72000 Revision - dated 2 April 1998or later accepted revision - Premier Aviation ICA:	None	10/05/2007	Active	10016770
EASA.IM.R.S.01105	BELL HELICOPTER TEXTRON, Inc.		FAA SR01849AT	212, 412, 412 EP	Light weight nitrogen reservoir kit/ Replacement of nitrogencylinder for emergency flotation system kit.		AA-98143 Rev F. dated. Master Drawing list report or later approved revision.AA-98142 installation instruction report and time limited parts.		20/12/2007	Active	10016771

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01108	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01958NY-D	SIKORSKY S-76C	Installation of Rockwell Collins TDR-94D Transponder with Elementary Surveillance		Installation Drawing List IDL00926 rev A dated May 11, 2005or later approved revisionFlight Manual Supplement FM00926 rev - dated May 20, 2005 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	13/03/2006	Active	10016773
EASA.IM.R.S.01109	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01960NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of baggage access panel (ground use only), forward facing seat, seat pan and wet floor.		Installation Drawing List IDL00921 rev " " dated May 16, 2005 or later approved revisionFlight Manual Supplement FM00921 rev - dated May 24, 2005 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	13/03/2006	Active	10016774
EASA.IM.R.S.01110	KEYSTONE HELICOPTER SERVICES		FAA STC SR01959NY-D	S76A/B/C	Installation of Grimes Search Lights		Installation Drawing List IDL00928 rev A dated May 10, 2005or laterapproved revision;Flight Manual Supplement FM00928 rev - dated May 24, 2005 or laterapproved revision.	This SIC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	13/03/2006	Active	10043055
EASA.IM.R.S.01111	KEYSTONE HELICOPTER SERVICES		FAA STC SRO1961NY-D	S76C	Installation of a Vertical Visibility Door Window in the pilot's door		Installation Drawing List IDL00929 rev A dated May 4, 2005 or laterapproved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	13/03/2006	Active	10043053
EASA.IM.R.S.01112	KEYSTONE HELICOPTER SERVICES		FAA STC SRO1962NY-D	S76B/C	Installation of Rockwell Collins MDF-124F (V2) Direction Finder System		Installation Drawing List IDL00895 rev" " dated May 10, 2005 or laterapproved revisionFlight Manual Supplement FM00895 rev - dated May 24, 2005 or laterapproved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	13/03/2006	Active	10043052
EASA.IM.R.S.01113	KEYSTONE HELICOPTER SERVICES		FAA STC SR01963NY-D	S76B/C	Installation of the WesCam I2DS200 Camera System		Installation Drawing List IDL00896 rev" " dated May 10, 2005 or laterapproved revisionFlight Manual Supplement FM00896 rev - dated May 24, 2005 or laterapproved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	13/03/2006	Active	10043051

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01114	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR00831LA	AS 355 E/F/F1/F2/N AS 350 D/B/B1/B2/B3/BA,	Installation of Apical Emergency Float kit, Part Number 20416, in accordance with the following FAA approved Apical Industries, Inc., Master Document List and Rotorcraft Flight Manual Supplement :- For AS 350 series : MDL n ° MD350(4) rev. I, dated December 1st, 2004 or later FAA approved revision,...		-Apical AS 350 RFMS n° FMS-350(4), rev. B dated 15/11/05 orlater EASA approved revision.-Apical AS 355 RFMS n° FMS-355 (2) rev. B dated 15/11/05 or later EASA approved revision.-Apical Installation and Packing Instructions n° II355-100 rev. E, dated October 26th, 2004, or later FAA approved revision...	1. This approval requires the inspection and overhaul schedules to be performed as mandated by the Apical Instructions for Continued Airworthiness n° ICA 355-1, rev. G, dated December 3rd, 2004 or later FAA approved revision. 2. This installation should not be incorporated in any aircraft unless it i...	15/11/2005	Active	10016775
EASA.IM.R.S.01115	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR01687LA	EC 130 B4	Installation of Apical Emergency Float kit p/n 604-0018-100or Emergency Float kit with Liferaft p/n 604-0018-300.		Definition:Apical Master Document List n0 MD130-1, revisionJ, dated 04/28/05, or later FAA approved revisions,Installation:Apical Installation Instructions for EC 130 B4 Emergency Float kit n0 11130-1, revision D, dated 12/20/04, or laterrevisionsApical Installation Instructions for EC 130 B4 Emer...	This StC is the EASA validation of FAA STC n0 SR01687LA, dated March 22nd, 2005.	25/04/2008	Active	10016776
EASA.IM.R.S.01116	BELL HELICOPTER TEXTRON, Inc.		FAA SR02074AT	427	Manufacture of Automatic Door Opener for Bell 427 Model Helicopters in accordance with the FAA STC SR02074AT. AAI Master Drawing List Report AA-98109 dated 30/10/1998. FAA STC SR 02047AT dated 14/02/2000 (Atlanta Aircraft Certification Office).		- PMA No. PQ1058CE dated 15/02/2000- Instructions for continues airworthiness AA-99043 dated 05/12/2001- Crew door opener kit AA-98099 dated 29/04/1999- Passenger door opener kit AA-98100 dated 12/12/2002- Baggage door opener kit AA-98105 dated 24/06/2002	1. The compatibility of this design change with other previously approved modifications must be determined by the installer.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/...	15/07/2005	Active	10016777
EASA.IM.R.S.01117	AIRBUS HELICOPTERS, Inc.		FAA STC SH8804SW-D	EC 155 B1	Installation of a Universal Navigation UNS- 1F Flight Management System for IFR enroute & non-precision approaches.		AEC Drawing List 365a73-9063 Revision B dated September 13 1996 or later approved revision.RFM Flight Manual Supplement(RFMS 65fms-026 dated November 15 1996 or later approved revision).		10/10/2005	Active	10016778
EASA.IM.R.S.01118	AIRBUS HELICOPTERS, Inc.		FAA STC SR09295RC-D	EC 155 B1	Installation of navigation, communications & various electrical equipment		American Eurocopter Drawing List 155A82-8008 revision A dated May 30 2005 or later approved revision.Rotorcraft Flight Manual Supplement dated July 8 2005 or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/10/2005	Active	10016779
EASA.IM.R.S.01120	METRO AVIATION, Inc.		FAA STC SR01606NY-D	EUROCOPTER DEUTSCHLAND MBB-BK	Installation of Spectrolab SX-5 Starbust searchlight according to FAA STC SR01606NY-D		Flight Manual Supplement FM00703, Rev IR, FAA approved April 15, 2004Installaiton Drawing List IDL00703Instructions forContinued Airworthiness IC00703	None	13/09/2006	Active	10016780
EASA.IM.R.S.01122	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SH1262NW	EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Electronic Model E-69 Cargo Hook Load Cell System p/n 200-295-00, in accordance with Onboard Systems Master Drawing List n° 155-010-00, revision 10 dated 15/06/04 approved by FAA,or later FAA approved revision.		- Installation Instructions : Onboard Systems Owners Manual n° 120-114-00, revision 0 dated 15/06/04 approved by FAA, or later FAA approved revision- Instructions for Continued Airworthiness : section 4 of Onboard Systems Owners Manual n° 120-114-00, revision 0 dated 15/06/04approved by FAA, o...	1 - The present STC is the validation of the FAA STC SH1262NW last amended on 15/03/05, limited to Eurocopter AS 350 B,BA, B1, B2,and D models.2 – The system covered by this STC can be installed on AS 350 helicopters equipped with Eurocopter sling systems, or on Eurocopter AS 350 B2 or earlier swin...	10/01/2007	Active	10016781

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01123	AERO DESIGN LTD.		TCCA STC SH02-26, ISSUE 2	AS 350 B / AS 355 E	Installation of DynaNav Seisbag System.		Definition and installation:AERO Design Ltd. Document Control List DCL444, Revision 2, or later Transport Canada (TCCA)approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	25/01/2008	Active	10016782
EASA.IM.R.S.01124	JCM AERODESIGN LIMITED	REV. 2	TCCA STC SH02-2	EUROCOPTER FRANCE AS 350 B3	Installation of Optech Inc. Airborne Laser Terrain Mapper ALTM 1225 or ALTM 3033 in Eurocopter AS 350B1 and AS 350B2 rotorcraft (approved under EASA.IM.R.S.01124 – initial issue).Installation of Optech Inc. Airborne Laser Terrain Mapper ALTM 3100 in Eurocopter AS 350B1, AS 350B2, and AS 350B3 rotorc...		Definition and installation: JCM Aerodesign Limited dwg. No. JCM-013078 Revision E or later approved revisions.Inspection and maintenance: JCM Aerodesign Limited Maintenance Manual Supplement No. 013078MMS Issue 5.1 or later approved revisions.Operation: JCM Aerodesign Limited FLIGHT MANUAL SUPPLEME...	1. This STC is not approved for AS350 B3 aircraft when equipped with Eurocopter Mod OP-3369 (2370 kg certified weight extension).2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed mo...	22/05/2008	Active	10016783
EASA.IM.R.S.01125	AIR COMM CORPORATION L.L.C		SR00491DE	EC 120 B	Installation of Cabin Air Conditioning system.The present STC is the validation of the FAA STC n°SR00491DE.		Definition: Air Comm Corporation Master Drawing List reportn°DL-EC120, revision D, dated December 26, 2002 approved byFAA or later approved revisionsInstallation: Air Comm Corporation Master Drawing List report n°DL-EC120, revision D, dated December 26, 2002 approved by FAA or later approved revis...		24/01/2006	Active	10016784
EASA.IM.R.S.01126	DART AEROSPACE USA, Inc.		FAA STC SR01583SE	BELL 412 EP BELL 412 CF BELL 412 BELL 212 BELL 205B BELL 205A-1 BELL 205A AGUSTA AB-412EP AGUSTA AB-412	Installation of DART D412-742 Float Skidtubes (FAA STC SR01583SE issued on 29 July 2005)		-Master Drawing List MDL-D412-742, Rev. D dated 27 January 2006 or later approved revision-Airworthiness Compliance Document ACP-D412-742-1 Rev. B dated 26 May 2005-Instruction for continued airworthiness ICA-D412-742 Rev. 1 dated 3 October 2005 or later approved revision	Installation Insttruction IIN-D412-742 Rev. B dated 3 October 2005 or later approved document.This approval should not be extended to other rotorcraft of this model on which otherpreviously approved modifications are incorporated unless it is determined by the installer that the relationship betwee...	12/05/2006	Active	10016785
EASA.IM.R.S.01129	CARSON HELICOPTERS, INC.		FAA STC SR01585NY	SIKORSKY S-61NM SIKORSKY S-61N	Installation of Carson Helicopters Inc. composite main rotor blades, p/n163-101-1 as replacement for the Sikorsky metalblade and with noperformance improvement: i.e. performance equal to that of the Sikorskybasic RFM and associated Sikorsky RFM Supplements 15 and 16.		- Instructions for Continued Airworthiness for CHI Composite Main RotorBlade, Part number 163-101-1. Report CH-MR-ICA Rev 0 dated Jan 13th 2003or later approved revision.- CHI Installation Instructions CSI install-l Rev A dated July 23rd 2002or later approved revision.- CHI RFM - Rotorcraft Flight M...	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	08/06/2009	Active	10043050

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01132	AIR COMM CORPORATION L.L.C		SR00463DE	A119	Air Conditioning System for Agusta A 119FAA STC SR00463DE issued on 11th January 2002 and amended on 24th January 2006		- Flight Manual Supplement Doc. N° A119-1 rev. 3 dated 14thJuly 2005 or later approved revision.- Instruction for Continued Airworthiness Doc. N° A119-206M-1 rev. 1 dated 29th August 2005 or later approved revision.- Master Drawing List Doc. N° DL-A119 rev. B dated 26th December 2001 or later appro...	This approval should not be extended to rotorcraft of this model on which other previously approved modifications are incorporated unless it is determinded that the interrelationship between this change and any of those other previously approved modifications, including changes in type design, will...	02/03/2006	Active	10016787
EASA.IM.R.S.01135	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR01535LA	206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1	Installation of Apical Industries Inc. Emergency Float Kits.		- MDPHI-1 – Master Document List;- FMSPHI-1, revisionB dated May 13, 2005 – Rotorcraft Flight Manual Supplement;- ICAPHI-1, revision G dated 15 April, 2005 – Instructions for Continued Airworthiness;- ICAPHI-2, revision A dated 15 April, 2005 – Instructions for Continued Airworthiness;-...	1. This installation of Apical Industries Inc. EmergencyFloat Kit requires prior installation of high landing gear with provision for float installation as defined in Apical Industries Inc. Approved Landing Gears for Apical Emergency Float Kit, AIPHI-8, revision A, dated 3 August, 2003 or later2...	16/01/2007	Active	10016788
EASA.IM.R.S.01136	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SH4908NM	MD HELICOPTERS 369E MD HELICOPTERS 369D	Installation of Model E-51 Cargo Hook Load Cell System PN 200-034-00. This STC is the validation of the FAA STC SH4908NM amended on05/11/1990 and limited to MDHI 369 D and E models		Master Drawing List (MDL) Onboard Systems MDL No. 155-014-00 Revision 1 dated 10/10/1990 approved by FAA or later FAA approved revision.Installation Intructions Onboard Systems Owners Manual No. 120-017-00 Revision 1 dated 10/10/1990 approved by FAA or later FAA approved revision.Inspection: Section...	1. This STC is to be installed on aircraft models specifiedin "applicability" section above, equipped with MDHI Cargo Hook Kit No.369H90072, using MDHI cargo hook manual release PN 14323-2 only.2. Installation, Inspection and Operation must be done in accordance with the documents specified in thee...	12/10/2005	Active	10016789
EASA.IM.R.S.01137	SKYTRAC SYSTEMS LTD.	REV. 2	TCCA STC SH05-42	SEE APPROVED MODEL LIST	SkyTrac ISAT-100 Airborne Position/Data Communicator SystemInstallation.TCCA STC SH05-42 Issue no 1 dated 12 September2005		SkyTrac Sytems Inc. Master Document List 250-50097-00 Rev. 01, dated April 13, 2006, or later approved revisions.Supplement Instructions for Continued Airworthiness are provided in SkyTrac Document 270-50097-00 Rev. 00, dated September 1, 2005,or later approved revisions.	1. Equipment configuration: ISAT-100 (no mod.)/mod A, orlater TCCA approved major mod.2. This STC references specified interfacing equipment that is approved via this data.The ISAT-100 equipempment is capable of being interfaced toadditional aircraft systems for wich approval is beyond thep...	13/02/2006	Active	10016790
EASA.IM.R.S.01138	CARSON HELICOPTERS, INC.		FAA STC SH639NE	S61 N	Installation of 11,000 pound capacity Cargo Sling in accordance withCarson Services, Inc., Drawing List Report No S61N-1A Revision D datedJanuary 10, 2005		-Carson Services, Inc. FAA approved Flight Manual Supplement No 1, asapproved February 2, 2001 (or later approved revision) to FAA approvedSikorsky Flight Manual Supplement No. 15-Carson Services, Inc. FAA approved Flight Manual SupplementNo. 1, asapproved February 2, 2001 (or later approved revisi...	None	06/07/2009	Active	10032448

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01139	BELL HELICOPTER TEXTRON, Inc.		FAA SR01411AI	407	Manufacture and Installation of console assembly		In accordance with Aeronautical Accessories Inc Drawing List Report No AA-97037, Rev A, dated April 23, 1997, and installation report No AA-96181, Rev A, dated March 6, 1997, or later approved revision.		26/01/2006	Active	10016791
EASA.IM.R.S.01140	FUGRO AIRBORNE SURVEYS		TCCA STC SH 98-37	EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of Fugro Airborne Surveys Electro-MagnetometerBoom & Geosurvey Equipment installation		STC SH 98-37 installation instructions.Installation must bein accordance with DECA Aviation Modification Summary No. MS9805650 Issue 3, dated July 17, 2000 TCCA approved, or later TCCA approved revisions.	1. STC SH 98-37 Supplemental Flight Manual 4537-01 Revision01 approved 18 July 2000 or later approved revisions.2. DECA Aviation Flight Manual Supplement No. 453707 Revision 1, dated 18 July 2000 or later approved revision3. This STC is approved only for the product configuration as defined in the...	11/10/2005	Active	10016792
EASA.IM.R.S.01148	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR00627LA	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of Utility floats in accordance with FAA STC SR00627LA issued May 08, 1998, reissued December 22, 1998 andamended September 14, 1998.		Installation in accordance with FAA approved Apical Industries Inc Master Document List MD 350(3), Revision H, dated August 11, 1998 or later FAA approved revisions.FAA approved Apical Industries Inc Rotorcraft Fligt Manual Supplement FMS-350(3) dated May 05, 1997 or later FAA approved revision.	This approval requires the inspections and overhaul schedules to be performed as mandated by the Instruction for Continued Airworthiness, ICA350-2 dated 2, 1997 or later FAA approved revision.	20/06/2006	Active	10016795
EASA.IM.R.S.01150	BUCHER LEICHTBAU AG			EUROCOPTER DEUTSCHLAND BO-105	Ambulance Rescue SystemThe FOCA STC Z 25-20-49 (ambulance rescue system) was validated by the LBA under the number 0589/3025 dated 24 February 1995, approving installation onto the BO105SThis STC is re-issued as EASA STC to extend applicability to BO105LS.		Flight Manual Supplement FMS-10-66	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	11/11/2005	Active	10016797
EASA.IM.R.S.01157	PRATT & WHITNEY	REV. 1		BELL 412 EP BELL 412 BELL 212 AGUSTA AB-412EP AGUSTA AB-412	Installation of Pratt & Whitney Engine Services , Inc. DataTransmission Unit		Instructions for Continued Airworthiness (ICA) as listed indocument ref AML DTU-T-225-4 Rev. A, dated September 29th, 2005 or later approved revision.		07/03/2008	Active	10016799
EASA.IM.R.S.01158	AIRFILM CAMERA SYSTEMS, INC		FAA STC SR01784LA	AS 350 MODELS // AS 355 MODELS	Installation of Down Post Utility Bracket AFDP-1 that attaches to the aircraft for attachment of a payload device		AFDP-010 rev N/C dated 17 Feb 2005 - Master Drawing ListAFDP-006 rev N/C dated 25 March 2005 - Installation InstructionsFlight Manual Supplement rev N/C dated 9 May 2005	This STC approves the installation of the Down Post UtilityBracket AFDP-1 and physical installation of payloads that meet the RFM restrictions. Any electrical installations must receive further EASA approval.	13/07/2006	Active	10016800

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01163	PRATT & WHITNEY	REV. 1		SCHWEIZER AIRCRAFT 269D	Installation of Pratt & Whitney Engine Services, Inc. IntelliStart+ Electronic Control System and Gine Trend Monitor P/N DPU-K-010-14		Pratt & Whitney Engine Services, Inc. IntelliStart+ Installation Instructions DPU-I-010-6, Revision A, dated October 12, 2005, or later approved revisions.Pratt & Whitney Engine Services, Inc. Rotorcraft Flight Manual DPU-T-250-4, dated November 1, 2005 or later approved revisions.Pratt & Whitney En...	1. Engine must be modified in accordance with STC SE00027EN, which must be EASA approved or accepted prior to installation.2. Reference STC SE0027EN for any additional limitationsapplicable to the engine installation3. This system is designed as an electronic aid for engine "hot start" prevention a...	14/03/2008	Active	10016803
EASA.IM.R.S.01164	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01588SE	EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	ONBOARD SYSTEMS fuel drain guard kit for Eurocopter AS 350 series helicopter.Validation of FAA STC SR01588SE		Refer to installation instructions, inspection and maintenance instructions listed in FAA STC SR01588SE reissued September 29, 2005	Refer to FAA STC SR01588SE reissued September 29, 2005	06/03/2006	Active	10016804
EASA.IM.R.S.01166	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR00369SE	BELL 407 BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206L	Cargo hook installation n. 200-215-00		- FAA approved Onboard Systems Master Drawing List n. 155-029-00 dated June 26, 2000 or later FAA approved revision, -FAA approved Onboard Systems Owner's manual n. 120-046-00 dated June 26, 2000, or later FAA approved revision, - FAA approved Onboard Systems Service Manual n. 122-001-00 dated Jun...	Approval of this change in type design applies to only those Bell model rotorcraft listed above, which were previously equipped with an FAA approved installation of Bell cargo hook suspension systems 206-706-341-5, 206-706-341-101; 206-706-341-109 and either Breeze-Eastern cargo hooks 17149-2 or 17...	27/09/2006	Active	10016806
EASA.IM.R.S.01167	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR00892SE	MD HELICOPTERS 500N MD HELICOPTERS 369HS MD HELICOPTERS 369HM MD HELICOPTERS 369HE MD HELICOPTERS 369FF MD HELICOPTERS 369F MD HELICOPTERS 369E MD HELICOPTERS 369D	Installation of Onboard Systems Model 200-264-00 Cargo Hookkit.EASA validation of FAA STC n0 SR00892SE, amended January 13th, 2003, or later approved revision.This STC is classified 'Basic' by the FAA and is approved under the post type Validation Principles (PTVP).		Onboard Systems Master Drawing List n0155-061-00, revision 7 dated June 18th, 2008 or later approved revision.Onboard Systems Owner's Manual n0120-096-00, revisiona dated September 22nd, 2005 or later approved revision.Onboard Systems Instruction for Continued Airworthiness n0123-003-00, revision 2....	This cargo hook is not approved for human external load.Approval of this installation applies to the above listed modelrotorcraft only, which were previously equipped with an approved installation of McDonnell Douglas cargo hook suspension systems and cargo hooks shown ¡n the table below, or Onboar...	08/07/2008	Active	10016807
EASA.IM.R.S.01168	LUFTTRANSPORT AS		-	EUROCOPTER FRANCE AS 365N SERI	Mast Measurement System / System for Measurement of ground stations fixed radio antenna for correct frequencies as signal effects		Master Drawing LDO-2500-1-001 and Design Report LDO-2500-1-002Lufttransport A/S "Flight Manual Supplement SA 365 Series, External Mounted Antenna Model SXH 009A" No. LDO-2500-1-011	None	12/06/2006	Active	10016808
EASA.IM.R.S.01169	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR00557SE	ROBINSON R22 MARINER ROBINSON R22 BETA ROBINSON R22 ALPHA ROBINSON R22	Cargo Hook Suspension System		FAA approved Onboard Rotorcraft Flight Manual Supplement No121-022-00, dated September 29, 2005 or later approved revisionFAA approved Onboard Systems Owner's Manual No 120-070-00, dated October 11, 2004 or later approved revision		02/01/2006	Active	10016809

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01171	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC SR01064SE	ROBINSON R44 II ROBINSON R44	Cargo hook suspension system i.a.w. US STC SR001064SE.Note:Revision 1 of this STC is made for correction of FAA original STC reference. This supersedes previous issuance of the STC.		- FAA approved Onboard Systems Rotorcraft Flight Manual Supplement No. 121-007-00, dated April 22, 2005 or later approved revision for the Robinson R44 rotorcraft- FAA approved Onboard Systems Rotorcraft Flight Manual Supplement No. 121-017-00, dated April 22, 2005 or later approved revision f...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	29/04/2009	Active	10016811
EASA.IM.R.S.01173	AIR COMM CORPORATION L.L.C		FAA STC SR00222DE	407	Installation of a vapour cycle air conditioning system		Master drawing ListDL-407EC rev ZFlight Manual Supplement 407EC-1 rev NC	None	30/06/2006	Active	10016812
EASA.IM.R.S.01174	HERTELENDY RESEARCH ASSOCIATES		FAA STC SR09066RC	BELL 47, 47B,47B3, 47D, 47D1, 47E, 47G, 47G-2, 47H-1, 47J...	Bell 47 Composite Tail Rotor.		1. Master Drawing and Document List QA. 001-47-400-2 Rev.19 dated 1 April 2008;2. Installation and Maintenance Manual: QA-001-47-400-1 Rev. 6 dated 1 April 2008;3. HAC Flight Manual Supplement QA-FM-SUB-REQ-FAA-1-10-06-00;4. Tail Rotor Pre-flight Inspection Card-QA-GEN-PREFLT-1-01-21-00....	1. Bell 47 Series Rotorcraft equipped with Bell 47-641-170 hub and associated Bell 47-640-075 gear box only;2. ECN 07-07 dated 16 July 2007 'Installation of lighting protection grounding straps' must be installed.3. Blade life 4000 hours.4. Prior to installation of this modification then...	13/05/2008	Active	10016813
EASA.IM.R.S.01179	DART AEROSPACE Ltd.		TCCA STC SH01-5 ISSUE 2	BELL 407 BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206L BELL 206A	Landing Gear Crosstubes		ACP-D206-667 rev BACP-D407-667 rev AACR-D206-667-1 rev A	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	03/07/2006	Active	10016814
EASA.IM.R.S.01180	DART AEROSPACE Ltd.		SH04-54 ISSUE1	BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1 BELL 205A BELL 204B	Installation of Fuel Purge Canister		Installation Instructions: IIN-D412-706 Revision A, dated November 30, 2004 or later approved revision.Instructions forContinued Airworthiness: ICA-D412-706, dated November 30, 2004 or later appoved revision.		26/04/2007	Active	10016815
EASA.IM.R.S.01181	DART AEROSPACE Ltd.		SH05-11	BELL 412 EP BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205A-1 BELL 205A BELL 204B	D212-722 Avionics Console		ACR-D212-722-1 rev AICA-D212-722 rev 0IIN-D212-722 rev ADR-D212-722 rev C	None	30/06/2006	Active	10016816
EASA.IM.R.S.01183	HELI-LYNX		SH05-41	EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E	Installation of One or Two Concorde RG 355 Laed-Acid Batteries accorging to TCCA STC SH05-41 issue N°2 approved September 09, 2005		Installatio Manual IM-PA-04-021-91-01 issue 1 Rev A, FlightManual Supllement FMS-PA-04-021-91-01 Issue 1 Rev A, Instruction for continued airworthiness ICA-PA-04-021-05-01 Issue 1 Rev A, all approved 09 September 2005 or later approved	Refer to STC SH05-41 and Flight Manual Supplement	16/03/2006	Active	10016818

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01184	HELI-LYNX		SH05-40	EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E	Installation of Purolator De-icing Fuel Filter p/n 1743640-01		Heli-Lynx Helicopter Services Master Drawing List n0 MDL-PA-04-012-91 -01 Issue 1, Rev. A, approved by Transport Canada(TCCA) on September 3rd, 2005, or later TCCA approved revisions,Installation Manual Report n* IM'PA-04-012-91-01 Issue 2, Rev. A, approved by TCCA on September 3rd, 2005, or laterv...	This STC is the EASA validation of Transport Canada STC n0 SH05-40, issue 1, dated September 9*, 2005,	25/04/2008	Active	10016819
EASA.IM.R.S.01185	AEROLITE AG		-	EC135	"EMS Equipment P/N 135138-502This major modification coversan EMS equipment inculding medical seats, stretcher, oxygencylinder rack, stowage cabinet and Oxylog and Propaq retainersSome components, indentified in the equipment list EQL-06-003 and already approved under Swedish Civil Aviaiton Admini...		Flight manual supplement FMS-06-003	1. Limited to S/N 01052. No Smoking when Medical Oxygen cabinet is installed3. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the...	22/03/2006	Active	10016820
EASA.IM.R.S.01186	SIKORSKY GLOBAL HELICOPTERS Inc.		SR01134NY-D	SIKORSKY S-76C	Installation of Bristow Helicopter's Ltd Automatic floatingDeployement System (AFDS) in accordance with Keytech Installation drawing list IDL00601 Rev. dated 11/27/02		Keystone helicopter Corp. FAA approved rotorcraft flight manual Supplement No. FM00601, no revision, FAA approved December 10, 2002, is required with this modification	This STC is valid only for S76C Sikorsky helicopter model from S/N 760511 and subsequentThis STC should not be incorporated in any aircraft of this specific model on which other approved modifications are incorporated, unless is determined that the interrelationship between this change and any of t...	29/03/2006	Active	10016821
EASA.IM.R.S.01187	DART AEROSPACE Ltd.		SH05-44	BELL 407 BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206A	D206/407-728 Skid tube wear plates.		MDL-D407-728-Master Drawing List, Revision A dated 3 August2005 or later approved revision;IIN-D407-728 – InstallationInstruction, Revision A dated 3 August 2005 or later approved revision;ICA-D407-728 – Instructions for continued Airworthiness, Revision 0 dated 3 August 2005 or later approved rev...		09/10/2007	Active	10016822
EASA.IM.R.S.01188	METRO AVIATION, Inc.	REV. 1	FAA STC SR09163RC	EUROCOPTER EC 135	Installation of mechanically driven vapor cycle air condition system i.a.w. FAA STC SR09163RC as amended by 18-06-2007.Major change to EASA STC EASA.IM.R.S.01188, addition of models and incorporation of technical modifications.		¿ Flight Manual Supplement 135AC-7, Revision D, dated 4 May 2006 or later approved revision or¿ Flight Manual Supplement 135AC-8, Revision IR, dated 18 June 2007 or later approved revision¿ Instructions for Continued Airworthinessdated 6 May 1997 or later accepted revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	14/04/2008	Active	10016823

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01194	AIRWOLF AEROSPACE L.L.C.		SR01215CH	R44	Installation of Apollo Spray system DTM-4 agricultural sprayer onto Robinson R44 helicopter. EASA validation of FAA STCSR01215CH		Apollo spray systems Document DTM-4-510 ,FAA approved Rotorcraft flight manual supplement (Metric version), dated 21 April 2006, orlater FAA approved revisionsApollo Spray system Drawing List DTM-4-MDL, No rev, dated December 8, 1999, or later FAA approved revisionsInstallation instructions DTM-4-II...	Certified in restricted category.All limitations of RFM supplement apply.	12/02/2007	Active	10016824
EASA.IM.R.S.01195	AIRBUS HELICOPTERS CANADA LIMITED		TCCA STC SH00-1 ISSUE 3	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of high visibility main and aft cabin doorsrefer to TCCA STC SH00-1 issue N°3, July 25, 2003		ECL installation procedure IP-ECL-42 rev 6 TCCA approved July 25, 2003 or later approved .ECL Maintenance Manual Supplement ECL-35 rev 0, TCCA approved August 12, 2002 or later TCCA approved	Refer to TCCA STC SH00-1 issue N°3, July 25, 2003	12/05/2006	Active	10016825
EASA.IM.R.S.01196	PARAVION TECHNOLOGY, INC.		FAA STC SR00338DE	BELL 407	Installation of Anti-Torque Extention Adjustment System		Master Drawing List DL-407PX-100 rev B	None	30/06/2006	Active	10016826
EASA.IM.R.S.01197	PRATT & WHITNEY	REV. 1		AGUSTA A-109 E	Installation of a Pratt & Whitney Engine Services, Inc. Digital Aircraft Data Acquisition System ADASd		Pratt & Whitney Engine Services, Inc. Aircraft Flight Manual Supplement, Document No. DAAS-T-250-3, Revision A, dated February 21, 2006, or later FAA-approved revision-Instruction for Continued Airworthiness (ICA) as listed in AML DAAS-T-225-1 Rev. A dated 21 February 2006	1. Required maintenance, as prescribed in the applicable airframe or engine Instructions for Continued Airworthiness, shall not be predicated on the data obtained from the Pratt &Whitney Engine Services, Inc. monioring/recording system. 2.This system shall not be used to supersede or replace the pi...	11/03/2008	Active	10016827
EASA.IM.R.S.01201	STARFLEX L.L.C.		FAA STC SH7962SW-D	EUROCOPTER FRANCE AS 355F2	Installation of two Allison 250-C20R engines and enhanced anti-torque system in accordance with AHC drawing list 355A82-1755 Revision D dated November 5, 1990 or later FAA approved revision		Instructions for Continued Airworthiness: Starflex LLC document reference C20RF2MMS, edition 1 amendment 0 dated 11 January 2007, or later revision.Operation: AHC Rotorcraft Flight Manual Supplement reference 355-FMS-011, dated 01 February1991 approved by FAA, or later FAA approved revision.	1. The present STC is the validation of the FAA STC SH7962SW-D, last amended on 01 February 2006.2. Compatibility of this modification with previously approved modifications of the aircraft must be determined by the installer.	16/01/2007	Active	10016830
EASA.IM.R.S.01202	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR01459LA	412, 412EP	Installation of Emergency Mid-Float with 10-man Liferaft KitsInstallation of Apical EMERGENDY Mid-Float with 10-man Liferaft Kits		Master Document List MD-412-31, Rev K, dated 3 February 2006 or alter approved revisionInstruction for continued Airworthiness ICA-412-31 Rev E, dated 13 April 2005 or later approved revisionRotorcraft Flight Manual Supplements FMS-412-31 Rev D, dated 9 February 2006 or later approved revision	Bell Helicopter Textron, Inc. Emergency Float Kit Part Number 412-706-004-137, or 412-706-004-143, or 412-706-004-149 or Apical Industries, Inc. Emergency Float Kit, Part Number 604.9601 per FAA STCSR01648LA, when approved by EASA must be installed prior to the installation of this STC.This approval...	04/09/2006	Active	10016831

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01203	STARFLEX L.L.C.		SH7961SW-D	AS 355 F1	Installation of two Allison 250-C20R engines in accordance with AHC drawing list 355A82-1753 Revision H dated November 5, 1990 or later FAA approved revision		Instructions for Continued Airworthiness: Starflex LLC document reference C20RF1MMS, edition 1 amendment 0 dated 11 January 2007, or later revision.Operation: AHC Rotorcraft Flight Manual Supplement reference 355-FMS-010, dated 01 February1991 approved by FAA, or later Faa approved revision.	1. The present STC is the validation of the FAA STC SH7961SW-D, last amended on 01 February 2006.2. Compatibility of this modification with previously approved modifications of the aircraft must be determined by the installer.	16/01/2007	Active	10016832
EASA.IM.R.S.01204	DART AEROSPACE Ltd.		SH96-69	BELL 412 EP BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1 BELL 205A	Installation of Heli Access Steps i.a.w. Transport Canada STC SH96-69, issue 7		- Flight Manual Supplement FMS-D412-630, Rev. D, dated 15.12.2005- Installation Instructions D412-630, Rev. J, dated 08.12.2005- Instructions for Continued Airworthiness ICA-D412-630, Rev. 1, dated 12.12.2005		02/06/2006	Active	10016833
EASA.IM.R.S.01205	AIRBUS HELICOPTERS, Inc.		FAA STC SH7339SW-D	SA 365 N, SA 365 N1 SA 365N1 AS 365 N2, AS 365 N3	Installation of an extended radome and FLIR 2000 infrared imaging system, in accordance with AEC Drawing List n° 365A73-9037, revision H dated 09 October 2000, or later FAA approved revision.		Rotorcraft Flight Manual Supplement 365FMS-010, dated 12 October 2000, or later FAA approved revision.		28/08/2006	Active	10016834
EASA.IM.R.S.01206	AIRBUS HELICOPTERS, Inc.		FAA STC SH7338SW-D	SA 365 N1 AS 365 N2, AS 365 N3	Installation of an AFT mounted retractable Nightsun Searchlight System, in accordance with AEC Drawing List n° 365A73-9036, revision F dated 19 March 1999, or later FAA approved revision.		Rotorcraft Flight Manual Supplement 365FMS-009, dated 27 April 1999, or later FAA approved revision.		28/08/2006	Active	10016835
EASA.IM.R.S.01207	AIRBUS HELICOPTERS, Inc.		FAA STC SH7022SW-D	SA 365 N1 AS 365 N2, AS 365 N3	Installation of Radio Master switch, in accordance with AECDrawing List No. 365A73-9034, revision B dated 25 April 2002, or later EASA approved revision		--	Compatibility of this modification with previously approvedmodifications must be determined by the installer.	20/07/2006	Active	10016836
EASA.IM.R.S.01208	AIRBUS HELICOPTERS, Inc.		SH7014SW-D	SA 365 N1 AS 365 N2, AS 365 N3	Installation ofvertical fin anti-collision light, in accordance with AEC Drawing List No. 365A73-9027, revision E dated09 June 2003, or later EASA approved revision		--	Compatibility of this modification with previously approvedmodifications must be determined by the installer.	20/07/2006	Active	10016837
EASA.IM.R.S.01209	AIRBUS HELICOPTERS, Inc.		SH5499SW-D	SA 365 N1 AS 365 N2, AS 365 N3	Installation of supplement strobe light, in accordance withAEC Drawing List No. H365-64-2D-101, revision L dated 06 June 2003, or later EASA approved revision		--	Compatibility of this modification with previously approvedmodifications must be determined by the installer.	20/07/2006	Active	10016838
EASA.IM.R.S.01210	AIRBUS HELICOPTERS, Inc.		SH8790SW-D	AS 365 N2, SA 365 N1	Installatino of a Bendix/King GPS KLN 90B or KLN 900 for IFR en route operations in accordance with AEC Drawing List 365A73-9060, revision C, dated 02/03/2005, or later EASA approved revision.		AEC RFM Supplement No. 365FMS-047, original issue or later EASA approved revision.		07/12/2006	Active	10016839
EASA.IM.R.S.01211	BELL HELICOPTER TEXTRON, Inc.		FAA SR01844AT	A109E, A109K2, A119 A109, A109A, A109A II, A109C	Installation of Tail Rotor Lockout Kit for Agusta A109, A109A, A109AII, A109C, A109E, A109K2, A119 Model Helicopter		- Compliance Checklist, Agusta A109/119 Tail Rotor Pedal Lockout Kit- Report No. AA-93088, Rev. N, 2-21-02, "Drawing List for Tail RotorPedal Lockout Kit on Bell 206A, B, L, L-1, L-3, L-4, 407, OH-58, 427 Model helicopters, Agusta A109A, A109AII, A109C, A109K2, A109E, A119 Model Helicopters"- Report...	Compatibilty of this design change with previously approvedmodifications must be determined by the installer. If the holder agreesto permit another person to use this certificateto alter the product, the holder shall give the other person written evidence of that permission	06/04/2006	Active	10016840

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01213	HELIPOD USA LLC		FAA STC SR00038BO	R22	Installation of externally mounted cargo carrying pods in accordancewith FAA STC SR00038BO Issued January 21, 1995, reissued January 28,2004and amended May 25, 2006.		Installation of Helipod Cargo containers in accordance withHelipod USAmaster Drawing list HSL-A-027-MDL, rev. 1, datedmarch 31, 2005 or laterFAA approved revision. Weight andbalance for the installation of 18 pounds per Helipod at longitudinalarm of 99.0 inches and a lateral arm of +/- 26.6 inches...	1. Helipod USA pilot's operating Handbook Supplement No1 , rev A dated23 march 2005, for Robinson R22 helicopters is required and must becarried during all flights2. The approval should not be extended to other aircraft of these modelsor which other previously approved modifications are incorporated...	26/06/2006	Active	10043049
EASA.IM.R.S.01214	AERO SEATS AND SYSTEMS, INC		SR09455RC	S-76A	Installation of External Liferaft Deployment System		CHC Scotia Report Number CHCE-2500-006 mod asi 500-100 01/02 Revision - dated January 18, 2006 or later approved revision.RFM Supplement S-76-500-FMS Revision IR dated March 1, 2006 or later approved revision.	Approval limited to Sikorsky S-76A registration G-BVCX Serial number 760183	11/05/2006	Active	10016841
EASA.IM.R.S.01218	AERO SEATS AND SYSTEMS, INC		SR09355RC	S-76A, S-76B, S-76C	Installation of Passenger Seats		ASI-6409 - Installation Instructions	None	10/05/2006	Active	10016842
EASA.IM.R.S.01219	HELI-TRADE CORPORATION		SR01592SE	BELL 412 BELL 214ST BELL 212 BELL 205B BELL 205A-1	Installation and Maintenance of Goodrich Internal HoistFAA STC SR01592SE		Master Drawing List Ht-415-MDL dated August 10, 2005 or later approval revision;RFM Supplement FMS-415-29.1581 dated August 12, 2005 or later approved revision	In order to operate the internal hoist in the referenced airframes, the following provision kits must be installed:HOIST P/N BELL PROVISION KIT BELL SERVICE INSTRUCTION HELICOPTER S/N EFFECTIVITYHTC-42305A 205-706-091-1 BHT-205-SI-44 205A-1 30001-30228HTC-42305A 205-70...	03/10/2006	Active	10016843
EASA.IM.R.S.01220	AERO SEATS AND SYSTEMS, INC		FAA STC SR09011RC	S-76A, S-76B, S-76C	Installation of Emergency Exit Window in Passenger Door		ASI-7611-MDL dated 5/8/1995 Master Drawing ListASI-95-002 rev A dated 5/8/1995 Evacuation Demonstration reportASI-7611-SI rev A dated 5/9/1995 Service Instruction	Configurations with forward facing seats only	27/07/2006	Active	10016844
EASA.IM.R.S.01221	AIRBUS HELICOPTERS CANADA LIMITED		TCCA STC SH05-18	AS 350 B/ B1/ B2/ B3/ BA/ D/D1	Installation of Forward Short High-visibility Doors (350-202414).		Installation must be in accordance with Eurocopter Canada Limited Installation Procedure n. IP-ECL-112, Rev. 0, TCCA approved April1, 2005 or later TCCA approved revisions.Configuration must be in accordance with Eurocopter Canada Limited Master Drawing List N. MDL-04-007, Iss. C, TCCA approved Apri...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/07/2007	Active	10016845
EASA.IM.R.S.01223	AIR CRUISERS COMPANY		FAA STC SR01842NY	EC 120 B	Installation of Air Cruisers Company Emergency Flotation System. (STC Classified as Basic by the FAA)		EDR 20-1367 rev C dated 10 December 2003 - Installation Data ListEDN 2925 rec IR dated 17 December 2003 - Flight ManualSupplementEDN 2921 rev B dated 8 August 2003 - Instructions for Continued Airworthiness.	This installation is for the Air Cruisers Company Mechanical Activation System to the Eurocopter Emergency Flotation System installed per Eurocopter Service Bulletin Optional No. 25.001, Revision O, dated January 27, 1999 or later approvedrevision.	08/03/2007	Active	10016847
EASA.IM.R.S.01224	PRATT & WHITNEY	REV. 1		AGUSTA A-109 E	Installation of a Pratt & Whitney Engine Services, Inc. DtaTransmission Unit Data Transmission UnitDTU-K-010-7		Instructions for Continued Airworthiness as listed in AML DTU-T-225-5, Revision, dated March 27, 2006, or later approved revision	1. 109E with Pr & W: 206C Engine;	07/03/2008	Active	10016848

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01225	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR00856LA	BO105 A/C/S	Installation of Apical Emergency Float Kits, Part Number 20430Description: Installation of Emergency Float Kit in accordance with FAA STC SR00856LA. Apical MDL MD105-2 provies fortwo differentinstallations either with liferafts or without.Note: the recommendation for approval is given based on a re...		For installation i.a.w. MD105-2 Rev. B/ 8-18-1999;Instructions for continued airworthiness: ICA 105-2, Rev A.Flight Manual Supplement FMS-105(2) Rev. AFor installation i.a.w. MDL MD 105-2 Rev. F/ 12-08-2004:Instructions for continued airworthiness: ICA105-501, Rev. N/ CFMS-105-501 Rev. A	The installation is not approved for helicopters equipped with high skid landing gear.	07/03/2008	Active	10016849
EASA.IM.R.S.01226	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR00932LA	369HS/HM/HE/D/E/FF, 500N	Installation of Apical Emergency Roat kit p/n 20491 -1.		Definition:Apical Master Document Listnû MD500-10, revisionH, dated 10/12/05, or later FAA approved revisions.Installation:Apical Installation Instructions n011500-10, revision D, dated 08/03/05, or later revisionsOperation:Apical Flight Manual supplement n0 FMS-SOOÍIO), revision C, dated Aprii 18t...	This STC is the EASA validation of FAA STC ne SR00932LA dated February 23rd, 2006.	25/04/2008	Active	10016850
EASA.IM.R.S.01227	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR01420LA	AS 332 C/L/L1	Installation of Apical Industries, Inc. Emergency float assemblies, P/N 20729-100, 207300-100 and 2073, and inflation cylinders, P/N 20330-2		FAA approved Apical Industries, Inc. Master Drawing List MDL332-1, rev. J dated September 18, 200, or later FAA approved revision.FAA approved Apical Industries Inc. Instructions for Continued Airworthiness ICA332-1, rev A dated January 31, 2006 or later FAA approved revision.	1 Aerazur's emergency float assemblies P/N 158820, 158565 and 158566, and inflation cylinders P/N 158562 (i.e. parts oforiginal emergency floatation kit approved on Eurocopter AS332C, L and L1 models) must be installed prior to applying this STC.The intermixed installation configuration between the...	13/05/2008	Active	10016851
EASA.IM.R.S.01228	TELEDYNE TECHNOLOGIES INCORPORATED		SR01406LA	BELL 206L-3 BELL 206L-1 BELL 206L BELL 206B BELL 206A	Aircraft Battery Replacement with Alternative Designs – Replace existing nickel-cadmium batteries with Teledyne BatteryProducts Model G-641S battery		Master Data List Document Revision No. NC dated March 12, 2002 or later approved revisionFlight Manual Supplement Document No 206-3 Revision NC dated October 21, 2002 or later approved revision	--	14/09/2006	Active	10016852
EASA.IM.R.S.01229	TELEDYNE TECHNOLOGIES INCORPORATED		SR01427LA	MD HELICOPTERS 600N MD HELICOPTERS 500N MD HELICOPTERS 369HS MD HELICOPTERS 369HM MD HELICOPTERS 369H MD HELICOPTERS 369FF MD HELICOPTERS 369F MD HELICOPTERS 369E MD HELICOPTERS 369D MD HELICOPTERS 369A	Aircraft Battery Replacement with Alternative Designs		Master Data List Document No. 0500-02, revision Adated Dec 20, 2002 or later approved revision.FAA Approved Pilots Operating Handbook Supplement and Flight Manual Supplement No. MD500-03 FM dated February 27, 2003 or later approved revision		07/06/2006	Active	10016853
EASA.IM.R.S.01230	L-3 WESCAM INC.	REV. 1	TCCA STC SH04-29	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	MX-15 camera installation (structural provisions only).Note: The revision extends the applicability of STC EASA.IM.R.S.01230 to AS355N.		Installation/Operating Data,• Installation must be done in accordance with DECA Aviation Engineering Modification Summary MS02146, Revision 3, or later approved revisions.• The installation must be maintained in accordance with DECA Aviation Engineering Instructions for Continued Airworthiness...		21/01/2008	Active	10016854

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01231	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01140NY-D	SIKORSKY S-76C	Installation of a Cyclic Control Stick Guard		Keytech Installation Drawing List IDL00644 Revision - datedApril 17 2003 or later approved revision.Keystone Helicopter AFM Supplement 00644 no Revision dated April 25 2003 or later approved revision.		21/11/2006	Active	10016855
EASA.IM.R.S.01232	AIR CRUISERS COMPANY		FAA STC SR02166NY	AS355 F1, AS355 F2, AS355 N AS350 B, AS350 B1, AS350 B2 AS350 B3, AS350 BA	Pneumatic Activation System to the Eurocopter Emergency Flotation System.According to FAA STC n. SR02166NY		Installation Data List n. EDR 20-1400 rev. E dated February15, 2006 or later approved revisionsInstructions for continued airworthiness n. EDN 3067 rev. A, dated October 24, 2005or later FAA approved revisions.Flight Manual Supplement n.• EDN 3075 rev. A dated March 28, 2006 for AS 350 B1, B2,•...	Applicable to :AS 350 B, B1, B2, BA and B3 a/c equipped with Eurocopter Emergency Flotation System installed per Eurocopter Service Bulletin Optional n. 25.00.35, Rev 3, dated November 23, 1999AS 355 F1, F2 and N a/c equipped with Eurocopter Emergency Flotation System installed per Eurocopter Servic...	16/03/2007	Active	10016856
EASA.IM.R.S.01233	AIRFILM CAMERA SYSTEMS, INC		FAA STC SR01058LA	AS 350 MODELS // AS 355 MODELS	Utility Mount		Installation of the Airfilm Camera Systems camera mount system in accordance with Master Drawing List AF200-010, Revision A, dated June 27, 2000:for AF200-1 Mount, Installation Document AF200-006 Revision N/C, dated June 1, 2000 or later FAA approved revisionsfor AF200-2 mount, Installation Document...		18/04/2007	Active	10016857
EASA.IM.R.S.01235	PRECISE FLIGHT, Inc.		FAA STC SA00701SE	ROBINSON R22 & R44	Installation of Precise Flight Pulslite System in accordance with Precise Flight, Inc. Engineering drawings 590P0001, Rev. -, dated26 January, 1999 and 590P0002, Rev. -, dated 26 January 1999 or later approved revision in Robinson R22 model or R44 model helicopters.		RFMS: Precise Flight, Inc. FAA approved Rotorcraft Flight Manual Supplement, dated May 18, 1999 or later approved revisions.Installation Instructions and Instructions for Continued Airworthiness "Installation Instructions No.: PPRI-3000" Revision 9 or later revision.		20/07/2007	Active	10016859
EASA.IM.R.S.01236	BELL HELICOPTER TEXTRON, Inc.		FAA SR00235AT	206L-3, 206L-4, 407 206A, 206B, 206L, 206L-1,	Installation of Headset Retention Brackets		Report No. AA-93041, Rev C, 4-18-06, Drawing List Headset Bracket Assembly for Bell Helicopter Textron Model 206A, B, L, L-1, L-3, L-4, 407 Model Helicopters.Report No AA-93042, Rev C, 10-02-00, Installation Instructions for Headset Bracket Assembly Installation Kit on Bell 206A, B, L, L-1, L-3, L-4...	None	29/08/2006	Active	10016860
EASA.IM.R.S.01237	NTT ENTERPRISES INC.	REV. 1	FAA STC SR01272LA	R44, R44 II	Installation of Tyler ROB-001 Universal Mount		1. Flight Manual Supplement ROB-RFM-001 Rev B, dated 28/11/2001 or laterFAA approved revision. 2. Installation Manual R44INST-001, Rev. B dated 28/11/2007 or later FAAapproved Revision.3. Tyler Camera Systems Master Drawing List No. TCS R-44-001, Rev. Bdated 05/07/2001 or later FAA approved revision....		04/12/2007	Active	10016861

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01238	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01164SE	EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Fabrication and Installation of Onboard Systems Model 200-280-01 Cargo Hook Swing Suspension System		- FAA STC SR01164SE dated October 26, 2004;- Master Drawing List STC SR01164SE Doc. Number 155-086-00 dated Septemeber 29, 2004 Revision 10;- Owner's Manual for the CargoHook Swing Suspensions system on the Eurocopter AS350 Series System, Part Number 200-280-01, Manual Number 120-104-01, S...	1. Approval of this change in Type Design applies only fo those Eurocopter AS350 model rotorcraft listed above;2.This approval should not be extended to other rotorcraft ofthese models on which other previously approved modifications areincorporated unless it is determined by the installer t...	26/07/2006	Active	10016862
EASA.IM.R.S.01239	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01135NY-D	SIKORSKY S-76C	Installation of a Chadwick-Helmuth Vibration Monitoring System		Keystone Helicopter Installation Drawing List IDL00571 Revision -, dated January 13, 2003 or later approved revision		26/09/2006	Active	10016863
EASA.IM.R.S.01240	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02110NY-D	SIKORSKY S-76C SIKORSKY S-76A	Installation of a Honeywell Chadwick Model 15175 VXP System		Keystone Helicopter Installation Drawing List IDL00892 Revision A dated November 21, 2005 or later approved revision		26/09/2006	Active	10016864
EASA.IM.R.S.01241	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE	REV. 1	FAA STC SR01902LA	S-76 A, B, C	Installation of Apical Industries Inc. Liferaft Kit.		MD76-2, revision E dated 19 May, 2006 – Master Document ListRFMS-76, revision N/C dated 28 June, 2006 – Rotorcraft Flight Manual SupplementICA76-2, revision A dated 12 June, 2006 – Instructions for Continued Airworthiness	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraphs "Description" and"Associated Technical Documentation".Compatibility with other aircraft/engine configurations shallbedetermined by the installer.This certificate shall remainr...	16/05/2007	Active	10016865
EASA.IM.R.S.01242	DART AEROSPACE Ltd.		TCCA STC SH96-120	BELL 412 EP BELL 412 CF BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1 BELL 205A BELL 204	D205-541 Heli-Utility Basket in accordance with Transport Canada STC SH96-120, Issue 3, dated May 16, 2006		- FMS-D412-541 for Bell 412 Models Revision A dated May 16, 2006 or later approved revision;- FMS-D205-541 for Bell 205/210/212 Models revision E dated May 16, 2006 or laterapproved revision;- FMS-D214-541 for Bell 214 models Revision A dated May 16, 2006 or later approved revision;- In...	1. VFR Only;2. Doors to be closed at all times duringflight;3. Maximum Load 136 kg (300 lb) or 100kg (220lb) if middle support is not installed;4. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". C...	29/09/2006	Active	10016866
EASA.IM.R.S.01244	HELICOPTER TECHNOLOGY COMPANY,LIMITED PARTNERSHIP		FAA STC SR01282LA	MD HELICOPTERS 369HS MD HELICOPTERS 369HM MD HELICOPTERS 369HE MD HELICOPTERS 369H MD HELICOPTERS 369FF MD HELICOPTERS 369E MD HELICOPTERS 369D MD HELICOPTERS 369A	Installation of a Tail Rotor Blade Assembly. (STC Classified as Basic by the FAA).		Models 369A, H, HE, HM, HS:MDL-3300-01 rev N/C dated 7 April 2001 – Master Document ListModels 369D, EMDL-3100-01 rev Fdated 7 April 2001 – Master Document ListModel 369FFMDL-3500-01 rev N/C dated 7 April 2001 – Master Document List	N/A	15/03/2007	Active	10016868
EASA.IM.R.S.01245	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR00649SE	BELL 206B BELL 206A	Cargo Hook Suspension Kit for Bell 206A and 206B		200-233-00 or 200-235-00 (without load weigh). 200-234-00 or200-236-00 (with load weigh).MDL 155-041-00 rev 1 dated November 20, 1998 or later approved revision.Owners Manual 120-076-00 revision 1 dated November 20, 1998 or later approvedrevision.Flight Manual Supplement 120-076-00 dated December...	None	21/12/2006	Active	10016869

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01247	AIR METHODS CORPORATION		FAA STC SR00032DE-D	AB412 / 412	Installation of Air Methods Corporation Emergency Medical System interior that provides 3 patient locations to be configured one oftwo ways using an Intensive Care Transport Litter (ICTL) and Ferno stretchers.		MDL 141-9009 rev B dated 10 June 1993.	1. Single and dual patient configurations are to be installed in strict accordance with Air Methods Corporation Maintenance Manual AMMS 050-0110 rev N/C dated 156 April 1993 or later approved revision and FAA approved Rotorcraft FlightManual Supplement RFMS 080-0114 rev N/C date 18 June 1993.2....	11/01/2007	Active	10016871
EASA.IM.R.S.01248	BELL HELICOPTER TEXTRON, Inc.		FAA SR02070AT	427	Installation of Baggage Floor Protector		Report No AA-98097, Rev E, 5-31-06, Drawing List Baggage Floor Protector on Bell Helicopter Textron Canada Limited 427 Model Helicopters.Report No AA-98091, Rev D, 5-5-06, Installation Instructions for Baggage Floor Protector kit and Supplemental Baggage Floor Protector kit on Bell Helicopter Textro...		25/10/2006	Active	10016872
EASA.IM.R.S.01249	AAR COMPOSITES, INC.		FAA STC SR01934LA	S-92A	Installation of Partial Search and Rescue Interior Configuration.		Install in accordance with AAR Composites Master Data List SAR-620-010, Revision M dated 1/31/2007, or later approved revisions.Maintenance in accordance with AAR Composites Document Number AAR-ER-1169, Sikorsky S-92A SAR Search and Rescue (SAR) Interior Continued Airworthiness Document, Revision A...	No passengers permitted in the main cabin until the complete interior arrangement has been EASA or cognizant National AirworthinessAuthority approved.	07/05/2007	Active	10016873
EASA.IM.R.S.01250	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR00920SE	ROBINSON R22 MARINER ROBINSON R22 BETA ROBINSON R22 ALPHA ROBINSON R22	Cargo Hook Suspension Kit i.a. with FAA STC SR00920SE		Rotorcraft Flight Manual Supplement No. 121-004-00, Rev. 1,FAA approved: June 9, 2006 or later FAA approved revisionOwner's Manual No. 120-095-00, Rev. 0, dated January 12, 2001,or later approved revisionService Manual No. 122-012-00, Rev. 1, dated January 4, 2006, or later approved revisionMaster...	--	20/12/2006	Active	10016874
EASA.IM.R.S.01252	PARAVION TECHNOLOGY, INC.		FAA STC SR00375DE	BELL 206L-4 BELL 206A/B/L/L-1/L-3/ L-4	Laser Mapping Installation		Master Drawing List DL-206LM-100 rev N/C dated March 5, 1999, or later approved revisionFlight Manual Supplement PR-206LM-110B dated April 12, 1999, or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	15/09/2006	Active	10016875
EASA.IM.R.S.01253	DART AEROSPACE Ltd.		TCCA STC SH04-17	ROBINSON R44	Installation of D044-715 Cargo Mirrors i.a: with TCCA STC SH04-17		- Installation Instructions IIN-D044-715, Rev. A, dated 20 01 2004.- Instructions for Continued Airworthiness ICA-D044-715, Rev. 0, dated 05.02.2004	None	11/12/2006	Active	10016876
EASA.IM.R.S.01254	DART AEROSPACE Ltd.		TCCA STC SH04-12	ROBINSON R22 BETA ROBINSON R22 ALPHA	Installation of D022-716 Cargo Mirrors i.a. with TCCA STC SH04-12		- Installation Instructions IIN-D022-716, Rev. A, dated 20.01.2004- Instructions for Continued Airworthiness ICA-D022-716, Rev. 1, dated 12.05.2004.		12/12/2006	Active	10016877

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01257	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02411NY-D	SIKORSKY S-92A	WESCAM MX-15i FLIR Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01232, rev. B or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01232, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016880
EASA.IM.R.S.01258	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02412NY-D	SIKORSKY S-92A	Saab airborne Transponder System Installation in a SikorskyS-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01233, rev. B or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01233, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016881
EASA.IM.R.S.01259	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02403NY-D	SIKORSKY S-92A	Chelton Tetra Tranceiver Provision Installation in a Sikorsky S92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01234, rev. B or later approved revisions.Instructions for Continued Airworthiness in accordance with Keystone Document Reference IC01234, rev. - or later approved revisions.		02/05/2007	Active	10016882
EASA.IM.R.S.01260	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02400NY-D	SIKORSKY S-92A	Helicopter Emergency Egress Lighting System (HEELS) Installation in a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01236, rev. - or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01236, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016883
EASA.IM.R.S.01261	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02404NY-D	SIKORSKY S-92A	Scene Lights Installation in a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01237, rev. - or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01237, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016884
EASA.IM.R.S.01262	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02133NY-D	SIKORSKY S-92A	Side Facing Utility Seat Installation in a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01238, rev. B or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01238, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016885

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01263	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02414NY-D	SIKORSKY S-92A	GKN Sliding Entry Door Installation in a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01270, rev. A or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01270 Rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keystone...		02/05/2007	Active	10016886
EASA.IM.R.S.01264	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02405NY-D	SIKORSKY S-92A	Logo Light Installation in a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01272, rev. - or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01272, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016887
EASA.IM.R.S.01265	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02407NY-D	SIKORSKY S-92A	Auxiliary DC Power System Installation in a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01299, rev. - or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM-1299, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016888
EASA.IM.R.S.01266	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02121NY-D	SIKORSKY S-92A	Shelf Installation in Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01334, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keystone Document Reference IC01334, rev. - or later approved revisions.		02/05/2007	Active	10016889
EASA.IM.R.S.01267	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02132NY-D	SIKORSKY S-92A	Ramp Gap Bridge Installation in a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01342, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keystone Document Reference IC01342, rev. - or later approved revisions.		02/05/2007	Active	10016890
EASA.IM.R.S.01268	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02124NY-D	SIKORSKY S-92A	Jettisonable Cabin Window Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01229, rev. D or later approved revisions.Instructions for Continued Airworthiness in accordance with Keystone Document Reference IC01229, rev. A or later approved revisions.		02/05/2007	Active	10016891

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01269	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02401NY-D	SIKORSKY S-92A	SAR Operators Seat Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01230, rev. A or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01230, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016892
EASA.IM.R.S.01270	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02413NY-D	SIKORSKY S-92A	Wulfsberg Flexcomm II Communications Management System Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01221, rev. A or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01221, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016893
EASA.IM.R.S.01271	SIKORSKY GLOBAL HELICOPTERS Inc.	REV. 1	FAA STC SR02433NY-D	SIKORSKY S-92A	NAT Loudhailer System Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01222, rev. A or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01222, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		29/10/2007	Active	10016894
EASA.IM.R.S.01272	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02406NY-D	SIKORSKY S-92A	Honeywell Primus 701A Weather Radar Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01224, rev. A or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01224, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016895
EASA.IM.R.S.01273	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02410NY-D	SIKORSKY S-92A	SAR Audio System Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01223, rev. C or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01223, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016896

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01274	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02126NY-D	SIKORSKY S-92A	Skytrac System ISAT-100 Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01225, rev. B or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01225, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016897
EASA.IM.R.S.01275	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02409NY-D	SIKORSKY S-92A	Polycon Wireless Intercom System Installation on a SikorskyS-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01226, rev. - or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01226, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016898
EASA.IM.R.S.01276	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02415NY-D	SIKORSKY S-92A	Chelton 935-2 VHF Direction Finder Installation on a Sikorsky S-92 Helicopter.		Installation in accordance with Keystone Document ReferenceIDL01227, rev. - or later approved revisions.Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM01227, rev. - or later approved revisions.Instructions for Continued Airworthiness in accordance with Keyston...		02/05/2007	Active	10016899
EASA.IM.R.S.01279	BELL HELICOPTER TEXTRON, Inc.		FAA SR01687AT	407	Manufacture of crew and passenger emergency push out windows		In accordance with Aeronautical Accessories, Inc. Drawing List Report No. AA-97167, no revision, dated February 4, 1998, and installation per Report No. AA-97142, no revision, dated January 23, 1998, or later approved revisions		16/11/2006	Active	10016902
EASA.IM.R.S.01281	EATON AEROSPACE GLENOLDEN		-	S-76A, S-76C	Installation of Eaton Aerospace/Tedeco Products Zapper pulsed electric chip detector system 1K7707 on Sikorsky Helicopter S-76A andC Models with Turbomeca Arriel 1S, 1S1, 2S1 and 2S2 Engines in accordance with Installation Drawing List IDL00508, Rev. B, dated May 11, 2006.Note: This STC supersedes...		see above	1. For the Sikorsky S-76 helicopters fitted with Arriel 1S1engines - the Arriel 1S and 1S1 engines must be equipped with TU 208 and TU 232 prior to the installation of the 1K7707Zapper System.2. Eaton Aerospace. Rotorcraft Flight Manual Supplement, Document FM 00508, Revision 1, FAA approved May...	07/11/2006	Active	10016904
EASA.IM.R.S.01282	VIH AEROSPACE Inc.		TCCA STC SH06-36	S-92A	Bubble Window Installation.		Installed in accordance with VIH Aerospace Master Drawing ListVS92-0611-MDL, Revision 0, or later approved revisions.Maintenance in accordance with VIH Aerospace Instructions for Continuedairworthiness VS92-06l I-ICA, Revision 0, or later approved revisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraphs "Description" and"Associated Technical Documentation".Compatibility with other aircraft/engine configurations shallbedetermined by the installer.This certificate shall remainr...	10/05/2007	Active	10043048

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01284	EAGLE COPTERS MAINTENANCE Ltd.		TCCA STC SH92-28	BELL 205A-1 BELL 205A BELL 204B	Dual Cargo Hook Mechanical release Kit.		A20468DCL1 - Document Control List, Revision 0 dated 28 August 1991 or later approved revision;EA204-68-18 - Service Instruction, Revision 0 dated 29 August 1991 or later approvedrevision.		09/10/2007	Active	10016905
EASA.IM.R.S.01285	EAGLE COPTERS MAINTENANCE Ltd.		TCCA STC SH92-30	BELL 204B	Vertical Reference Door.		A20469DCL1 - Document Control List, Revision 9 dated 18 June 2007 or later approved revision;EA204-69-19 - Service Instruction, Revision 4 dated 28 April 1998 or later approved revision;EA204-69-20 - Flight Manual Supplement, Revision 1 dated 3 September 1992 or later approved revision.	Day VFR Only;Minimum Flight Crew - 1 in left crew seat;Crewrestricted to:- Flight Crew- Flight Crew under Training- Persons essential for the type of operationDual controls must be installed per Bell Helicopter Service Instruction 206-6 for Model 204B;Approved Mechanical cargo release must be insta...	09/10/2007	Active	10016906
EASA.IM.R.S.01287	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR00711SE	SCHWEIZER 269 SERIES	Validation of FAA STCSR00711SE , amended January 13, 2003, or later approved versions.		Fabrication of Onboard Systems Model 200-244-00 cargo hook kit i.a.w. FAA approved onboard system MDL No 155-045-00, dated 3 May 1999,or later approved revision.Installation of this replacement cargo hook i.a.w. FAA approved Onboard Systemowner's manual No 120-081-00, dated 3 May 1999,or later appr...	Approval of this STC apply only to those Schweizer 269C which were previously equipped with FAA approved installation of Schweizer cargo hook kit P/N 269A4971-27.Modified rotorcraft must be operated i.a.w. FAA approved Rotorcraft Flight manual Supplement (RFMS) N0 120-081-00 dated June 30, 1999, orA...	09/07/2007	Active	10016907
EASA.IM.R.S.01288	VIH AEROSPACE Inc.		TCCA STC NO. SH06-41	S-92A	Sea Tray Installation.		Installed in accordance with VIH Aerospace Master Drawing ListVS92-0608-MDL, Revision 0, or later approved revisions.Maintenance in accordance with VIH Aerospace Instructions for Continuedairworthiness VS92-0608-ICA, Revision 0, or later approved revisions.	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraphs "Description" and"Associated Technical Documentation".Compatibility with other aircraft/engine configurations shallbedetermined by the installer.This certificate shall remainr...	10/05/2007	Active	10043047
EASA.IM.R.S.01290	DART AEROSPACE Ltd.		TCCA STC SH93-97	AS355NP AS355F1, AS355F2, AS355N, AS 350 D1, AS355E, ES355F, AS 350 B, AS 350 B1, AS 350 BA , AS 350 D, AS 350 B2 , AS 350 B3,	D350-602 Helicopter Utility Pod – Validation of Transport Canada STC SH93-97.		Compliance Report - ACR-D350-602-1 Rev AInstructions for Continued Airworthiness - ICA-D350-602 Rev 0 or later approvedrevisionFlight Manual Supplement - FMS-D350-602 Rev C or later approved revisionMaster Document List - MDL-D350-602 RevA or later approved revisionInstallation - D350-602 Rev E or...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.AS355 helicopters fitted with this STC are incompatibled...	02/06/2008	Active	10016909
EASA.IM.R.S.01291	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02129NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Keystone Helicopter Corporation "Silencer" Wall panel System. Classified as Basic STC by FAA.		IDL00916 rev – dated 15 February 2007 – Installation Drawing ListIC00916 rev – dated 18 April 2006 – Instructions for Continued Airworthiness	Compliance with FAR 29.812 has not been established for theinstallation of this system. An approved emergency lightingsystem is required.Compliance with FAR 29.783(c)(e), 29.803(a)(b), 29.807(a)(b), 29.809(c), 29.811, 29.813(a), 29.1301(a)(d) and 29.1557(a)(d) has notbeen established for the insta...	15/03/2007	Active	10016910

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01292	DART AEROSPACE Ltd.	REV. 1	TCCA STC SH93-88	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Spacepod Installations(Validation of Canadian STC Number SH93-88)		D350-600Installation Manual : IIN-D350-600, Revision BMaintenance Instructions : ICA-D350-600, Revision 3Flight Manual Supplement : FMS-D355-600, Revision D		09/04/2008	Active	10016911
EASA.IM.R.S.01293	AERO SEATS AND SYSTEMS, INC		FAA STC SR09211RC	S-76A, S-76B, S-76C	Installation of External Mounted Life Raft Deployment System[Identified as “Basic STC” by the FAA and approved using the FAA/JAA/EASA type validation principles (TVP)]		ASI-500-100 Revision E dated 4/14/1999 Installation manualS76-501-FMS Revision IR dated 1/11/2007 Flight Manual SupplementS-76-500-01 Revision 3 dated 12/21/2006 Instructions for Continued Airworthiness	Installation of external mounted life raft deployment system, with optional deployment handles in passenger compartment, in accordance with Aero Seats and Systems Inc. Installation manual ASI-500-100-01/02, revision H, dated December 5, 2005 or later approved revision is required.	15/01/2007	Active	10016912
EASA.IM.R.S.01294	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02131NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Keystone Helicopter Corporation Deluxe VIP Interior.		• IDL01217 rev – Installation Drawing List – dated 17 February 2007 or later approved revision• IC01217 rev – Instructions for Continued Airworthiness – dated 8 May 2006 or later approved revision• FM01217 rev – Flight Manual Supplement – dated 18 February 2007 or later approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	26/07/2007	Active	10016913
EASA.IM.R.S.01295	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02130NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Garmin GMX 200 Multi Function Display. ThisSTC has been classified as "BASIC" by the FAA and has been approved under the PTVP. The flight manual has been reviewedand is acceptable.		IDL01357 rev – dated 11 February 2007 – Installation Drawing List or later approved revisionIC01357 rev – dated 21 August 2006 – Instructions for Continued Airworthiness or later approved revisionFM01357 rev 2 dated 18 June 2007 – Flight Manual Supplement or later approved revision		03/07/2007	Active	10016914
EASA.IM.R.S.01296	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02123NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Provisions for a EuroAvionics EuroNav IV System. STC SR02123NY-D classified as Basic by the FAA throughFAA Order 8110.52.		IDL01318 rev B dated 22 December 2006 – Installation Drawing ListIC01318 rev – dated 22 August 2006 – Instructions for Continued Airworthiness	The FAA has not certified, and EASA has not validated, the equipment for which these provisions are intended. Additional approvals are required to install this equipment. The equipment installation must be evaluated to ensure that it complies with the applicable Certification Specifications.	19/03/2007	Active	10016915

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01297	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02122NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of High Intensity Strobe Lights. STC Classified as Basic by FAA.		IDL01319 rev B dated 15 December 2006 – Installation Drawing ListIC01319 rev – dated 27 July 2006 – Instructions for Continued AirworthinessFM01319 rev – dated 21 December 2006 – Flight Manual Supplement		15/03/2007	Active	10016916
EASA.IM.R.S.01303	DART AEROSPACE Ltd.		TCCA STC SH96-88	BELL 412 EP BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1 BELL 205A BELL 204B	Skidtube Installation		• For all interested products:MDL-D205-634 Revision A dated 13 April 2006 or later approved revision - Master Document List;• Bell 204D204-635 Revision C dated 30 March 2006or later approved revision - Installation Instructions.ICA-D204-635 Revision 0 dated 30 March 2006 or later approved rev...	1. Operation of the Bell 214B and 214B-1 model types with Dart D205-634-011 skidtubes and the required Dart D212-664-101/201 Crosstube installation as incorporated by EASA STC No. IM.R.S.01304 (Canadian STC SH01-9) is limited to a maximum take off and landing weight of 11900 lbs. Longitudinal cen...	27/06/2007	Active	10016918
EASA.IM.R.S.01304	DART AEROSPACE Ltd.		TCCA STC SH01-9	BELL 412 EP BELL 412 CF BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1 BELL 205A BELL 204B	Cross Tube Installation in accordance with Transport CanadaSTC SH01-9, Issue 3, dated 8 June 2005. Revision to LBA STCRC 1181 dated 15 January 2002		For Bell 214B and 214 B-1 models only FMS-D214-664 RevisionA dated 8 June 2005 or later approved revision;Master Document List MDL-D212-664 revision A dated 8 June 2005 or later approved revision;Installation Instructions IIN-D212-664 revision 2 dated 17 January 2005 or later approved revision;Inst...	Bell 214B and 214B-1 models onlyOperation of the Bell 214B and 214B-1 model types with the cross tube installation is limited to a maximum take off and landing weight of 5403 kg (11,900 lbs). Longitudinal centre of gravity limits have changed accordingly and are provided in Dart Aerospace FMS-D214-6...	06/03/2007	Active	10016919
EASA.IM.R.S.01305	BELL HELICOPTER TEXTRON, Inc.		FAA SR09373RC-D	412, 412EP	Bell Helicopter Vibration monitor (BHVM) System		¿ AA-04118 original issue dated 22 June 2005 or later approved revision - Drawing List¿ AA-04049, Revision A, dated 14 June, 2005, or later approved revisions - Instructionsfor Continued Airworthiness. ¿ AA-04118 Original issue dated 22 June 2005 or later approved revisions - Flight Manual...		31/05/2007	Active	10016920
EASA.IM.R.S.01306	BELL HELICOPTER TEXTRON, Inc.		FAA SR09347RC-D	212, 412, 412 EP	Helicopter Emergency Egress Lighting (Heel) System. This STC is classified as "Basic" by the FAA and is approved under the Post Type Validation Principles (PTVP).		Aeronautical Accessories, Inc. Drawing List Report No. AA-02027, Revision A, dated September 5, 2002, or later FAA/ DASapproved revision.Instructions for Continued Airworthiness provided in Aeronautical Accessories Inc. Report AA-02029, Revision C, dated 1 July 2005 or later AEG accepted revision.A...		25/04/2007	Active	10016921
EASA.IM.R.S.01307	BELL HELICOPTER TEXTRON, Inc.		FAA SR01278NY-D	412 EP	L-3 Communications FA2300 Series Combined Cockpit Voice Recorder and Flight Data Recorder Kit. This STC is classified as “BASIC” bythe FAA and is approved under the Post Type Validation Principles (PTVP).		AA-05062 Revision H dated 16 June 2006 or later approved revision – Drawing ListAA-05153 Revision F dated 16 June 2006 or later approved revision – Installation ReportAA-05063 Original issue dated 27 July 2006 or later approved revision – Flight Manual SupplementAA-05064 Revision A dated 23 June 200...	No credit is given for operational requirements that require both a CVR and FDR.	04/05/2007	Active	10016922

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01308	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR01949LA	AB139, AW139	Installation of Apical Industries, Inc. Liferaft Kit.		RFMS APICAL AW139 Liferaft Kit original issue, rev. A, dated 12-10-2007, or later FAA approved revisions.Master Document List MD139-1, Rev. B, dated 21-12-2006, or later FAA approved revisions.Instructions for Continued Airworthiness ICA,139-1, rev. N/C, dated 27-07-2006, or later FAA approved rev...	1. This approval requires the inspections and overhaul schedules to be performed as mandated by the Instruction for Continued Airworthiness, ICA139-1, Revision N/C, dated July 27,2006, or later approved revision.	19/10/2007	Active	10016923
EASA.IM.R.S.01309	AERO SEATS AND SYSTEMS, INC		FAA STC SR09453RC	412, 412EP	Installation of Cabin Seats		Aero Seats and Systems, Inc., Master Installation List L412-2520-002, Revision E, dated May 9, 2006, or later approved revision.Rotorcraft Flight Manual Supplement, ASI-6409-412-300, Revision A, dated May 18, 2006 or later approved revisionInstructions foe Continued Airworthiness (ICA) contained in...		15/03/2007	Active	10016924
EASA.IM.R.S.01311	BELL HELICOPTER TEXTRON, Inc.		FAA SR01474NY	412 EP	Installation of Honeywell Mark XXII EGPWS for Bell Helicopter Textron 412EP helicopters.Validation of FAA STC SR01474NYdated January 9, 2007		AAI drawing list report 4123401-MDL01, revision F, dated 01-03-07 or later approved revisionAAI Rotorcraft Flight Manual Supplement document 4123401-FMS01, Rev C dated 06 June 2007, or later approved revisionsInstruction for continued airworthiness report 4123401-RMM01 dated 01-03-2007 or later ap...		20/06/2007	Active	10016925
EASA.IM.R.S.01312	THE NORDAM GROUP LLC		FAA STC SH2554NM / EASA STC 20	369D/E/FF/H/HM/HE, 500N, 600N	Installation of modified front window canopy.Note: This STCsupersedes EASA. STC.2004-112.		Platinum Aviation Group Inc Master Drawing List TV 500-600 Revision A dated February 24, 2001 & Platinum Aviation GroupInc. Installation Instructions TV 500-600 True Vision Kit Revision Original dated April 21, 2000 or later approved revision.		24/01/2007	Active	10016926
EASA.IM.R.S.01313	SKYTRAC SYSTEMS LTD.		TCAA STC SH03-30 ISSUE 5	EUROCOPTER FRANCE EC 155B EUROCOPTER FRANCE AS 365N EUROCOPTER FRANCE AS 365C1 EUROCOPTER FRANCE AS 365C	Installation of SkyTrac ISAT-100 Airborne Position/ Data Communication System Note: This application is to amend an existing EASA STC (Ref P-EASA.IM.R.S. 001151 Rev. 1) to add theSA 365 C,C1,N, EC 155B helicopter models		- Installation in accordance with Sky Trac System Installation Master Document List 250-50064-00, Rev 07 dated May 16th. 2006,or later approved revisions.- Instructions for Continued Airworthiness provided in SkyTrac Document 270-50152-00,Rev 00, dated May 16th.2006, or later approvedrevisions.SkyT...	This STC references specific interfacing equipment that is approved via this data. The ISAT 100 equipment is capable of being interfaced to additional aircraft systems for which approval is beyond the scope of this STC. Such interfaces may need further approval.Cockpit labels shall be in accordance...	21/03/2007	Active	10016927
EASA.IM.R.S.01314	TELEDYNE TECHNOLOGIES INCORPORATED		FAA STC ST1186SO	BELL 412 EP BELL 412 BELL 212	Validation of FAA STC SH1186SO Aircraft Battery Replacementwith Alternative Designs		Master Part List TBPA-06-S-05 dated 21 October 1980 or Drawing Control Sheet 3708 dated 1 April 1987.Rotorcraft Flight Manual Supplement dated 25 September 1987 or later approved revisions.		20/06/2007	Active	10016928

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01316	BELL HELICOPTER TEXTRON, Inc.		FAA SR00790NY	407	Installation of a SFIM Automatic Flight Control System (AFCS) on Bell 407 helicopters.EASA validation of FAA STC SR00760NY dated July 27, 2007This STC is classified 'Basic' by theFAA and is approved under the post type Validation Principles (PTVP)		HAS Installation drawing list document MDL97-06-02, rev H, dated July 16, 2006 or later approved revisionHAS Installation instructions report No. IM-97-06-02, rev H, dated July 17, 2006 or later approved revisionAeronautical Accessories, Inc. Rotorcraft Flight Manual Supplement AA-04126, rev B, date...	This approval is for VFR operations only.If the holder agrees to permit another person to use this certificate to alterthe product, the holder shall give the other person writtenevidence of that permission.Installation of SFIM Force trimsystem in accordance with FAA STC SR00760NY (EASA.IM.RS.013...	07/04/2008	Active	10016930
EASA.IM.R.S.01317	AEROMETALS INC.		FAA STC SR01524SE	369HE, 369HM, 369HS	Horizontal stabilizer, P/N AM369A3600-603Validation of FAA STC SRSR01524SE reissued June 28, 2006		Master Drawing List MDL-AMC-008, revision initial release, dated August 6, 2004 or later FAA approved revisionsAMC installation instructions MI03003, revision initial release, dated December 15, 2003 or later FAA approved revisions	Limited to MDHI (Hughes) models 369HM, 369HS, 369HEall other limitation and conditions listed in FAA STC SRSR01524SE reissued June 28, 2006 apply	31/05/2007	Active	10016931
EASA.IM.R.S.01318	AAR COMPOSITES, INC.		FAA STC SR03370AT	S-92A	Structural provisions for a composite ramp floor panel.		Install in accordance with AAR Composites Master Data List SRP-620-010, Revision B dated 18 December 2006, or later approved revisions.Maintenance in accordance with AAR Composites Document Number AAR-ER-1180, Revision A, dated December 7,2006 or later approved revision.	MDL items under this STC meet Part 29.853. The installer isresponsible for panel sealant and all fasteners as well as for structural provisions to the aircraft ramp door. User must not exceed the maximum load per surface area of the ramp panel as specified by the TC holder.	07/05/2007	Active	10016932
EASA.IM.R.S.01319	LIFEPORT, LLC		FAA STC SR01948LA	SIKORSKY S-92A	Installation of a triple litter stacking system		Master Drawing List for the Triple Litter Stacking Installation, MDL-811-00, Revision D, dated December 14, 2006 or later approvedrevisionAirplane Flight Manual Supplement No. EGR-811-11, dated January 3, 2007, or later approved revision is required as part of this installation	The installation should not be incorporated in any aircraftunless it is determined that the interrelationship between this installation and any previously approved configurationswill not introduce any adverse effect upon the airworthiness of the aircraft.The approval of this modification applies t...	02/05/2007	Active	10016933
EASA.IM.R.S.01320	DART AEROSPACE USA, Inc.	REV. 1	FAA STC SA00475SE	BELL 407 BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206L BELL 206B BELL 206A BELL 206	Replacement of the original landing gear skid tubes and saddles with DART Aerospace Model D206-642 skid tubes and saddles. This TV modifies STC EASA.IM.R.S.01320		MDL-D206-642 revision Q dated 8 March 2007 or later approved revision – Master Drawing List;D206-642 revision K dated 25 September 2006 or later approved revision – Installation Instructions;ICA-D206-642 revision 0 dated 7 March 2007 or later approved revision – Instructions for continued Airworthin...		10/09/2007	Active	10016934
EASA.IM.R.S.01321	AIRBUS HELICOPTERS CANADA LIMITED		TCCA STC SH97-34 ISSUE 3	AS 355 E/F/F1/F2/N AS 350 B/ B1/ B2/ B3/ BA/ D	Installation of Forward Opening Rear Cargo Doors.(Modification approved by TCCA under STC SH97-34 Issue 3).		Definition and installationECL Master Drawing List No. MDL-06-002 Issue AInspection and maintenance:ECL Instructions for Continued Airworthiness No. ICA-ECL-141 Rev. 0	1; This STC is approved only for the production configuration as defined in the approved design data referred to in theparagraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.Installation of the Forward Opening Rear Cargo Doors on AS350B...	18/10/2007	Active	10016935

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01322	RSG PRODUCTS, Inc.D/B/A INTEGRATED FLIGHT SYSTEMS, IN		FAA STC SH5947SW	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E	Installation of freon air conditioner system with single ordouble condenser blower arrangement.		1. Single blower configuration defined by Drawing List Report DL-8, Revision A or later FAA approved revision;2. Double blower configuration defined by Drawing List Report DL-8-1, Revision N/C or later FAA approved revision;3. Flight Manual Supplement dated July 14, 1993 or later FAA approv...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	07/07/2008	Active	10016936
EASA.IM.R.S.01326	HELI-LYNX		TCCA STC SH05-20 ISSUE 2	EUROCOPTER FRANCE AS 355 SERIE EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 C EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350B EUROCOPTER FRANCE AS 350	AS350/AS355 Rear Shoulder Harness Installation.(Modiciationapproved by TCCA under STC SH05-20 Issue 2.)		Definition and Installation:Master Drawing List No. MDL-PA-04-014-91-01, issue 6, rev. A.Installation Manual No. IM-PA-04-014-91-01, issue 4, rev. A.Inspection and Maintenance:Instructions for Continued Airworthiness No. ICA-PA-04-014-05-01, issue 2, rev. B.	Installation of a Rear Shoulder Harness on AS350B3 with themodification OP-3369 incorporated is not approved.	04/09/2007	Active	10016938
EASA.IM.R.S.01327	AIR COMM CORPORATION L.L.C		FAA STC SH4057NM	S-76A, S-76B, S-76C	Installation of bleed air cabin heater and windshield defrost system.Note: STC SH4057NM was originally approved by the UK CAA under Airworthiness Approval note NO. 25242. This approval adds models S76A and S76B to the approval. This STC supersedes UK CAA Airworthiness Approval note NO. 25242.		DL-S76H revision H dated 15 December 1995 or later approvedrevision – Drawing ListS76H-100 dated 16 December 1994 or later approved revision – FMS for Bleed Air Cabin Heat.S-76H-102 dated 31 December 1997 or later approved revision – FMS for S76C without windshield defrost system installed.S76H-104...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	08/05/2007	Active	10016939
EASA.IM.R.S.01332	ALTAIR AVIONICS CORPORATION		FAA STC SR00170BO	MBB-BK117 C-1 MBB-BK117 B-1/-2 MBB-BK117 A-1/-3/-4 3. AB412 2. 222, 222B, 222U 1. 212, 412, 412EP	Monitoring System "Altair Avionics SmartCycle"		Flight Manual Supplement FMS EMU-G-250-2 Revision B, dated 20/08/2003.	This STC supersedes EASA STC 2004-1554 by adding model Bell412 EP to the applicability list.	18/05/2007	Active	10016940
EASA.IM.R.S.01334	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR02049LA	R44, R44 II	Pop Out Floats Kit: Installation of Apical Industries, Inc.Pop Out Floats Kit (also titled as "Emergency Floats Kit") in accordance with approved Apical Industries, Inc. Master Document List MD44-1, rev. D, dated 12-04-2007, or later approved revision based on FAA STC SR02049LA.		Flight Manual Supplement RFMS R44-2, Rev. N/C, FAA approved19-10-2007 or later approved revision.Installation Instructions: II44-1, Rev. B, dated 26-03-2007 or later approved revision.Instructions for Continued Airworthiness ICA44-1, Rev. A., dated 01-05-2007 or later approved revision.	N/A	27/11/2007	Active	10016941

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01335	DART AEROSPACE Ltd.		TCCA STC SH02-8;	ROBINSON R44 II ROBINSON R44	D044-662 Bearpaws.Revision to DGAC STC IM225-SI-0026, DGAC approved 30/04/2003, with addition of R44II aircraft model and larger Bearpaw Kits.		Dart Aerospace Ltd. Installation Instructions IIN-D044-662,rev. D, dated 14/02/2007 or later approved revisions.Dart Aerospace Ltd. Instruction for Continued Airworthiness ICA-D044-662, Rev. 1 dated 14/02/2007 or later approved revisions.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/engine configurations shall be determined by theinstaller.	31/05/2007	Active	10016942
EASA.IM.R.S.01337	AIRBUS HELICOPTERS, Inc.		FAA STC SH8803SW-D	SA 365 N, SA 365 N1 AS 365 N2	Installation of combination position lights and strobe lights with supplemental anti-collision lights replacing the red, green and white position lights..		365A73-9062 Revision C dated 12 September 1996 or later approved revision - AEC Drawing List.	Compatibility of this modification with previously approvedmodifications must be determined by the installer.	13/06/2007	Active	10016943
EASA.IM.R.S.01338	AIRBUS HELICOPTERS, Inc.		FAA STC SH7018SW-D	AS 365 N2, SA 365 N1	Installation of 4.0 inch Footwell in the passenger cabin ofthe Model SA365A73-9022.		365A73-9022 revision C dated 18 February 1991 or later revision - AEC Drawing List.	Compatibility of this modification with previously approvedmodifications must be determined by the installer.	13/06/2007	Active	10016944
EASA.IM.R.S.01339	DART AEROSPACE USA, Inc.		TCCA STC SH98-14	BELL 407 BELL 206L BELL 206B BELL 206A	D206-628 Heli Access Steps. This STC has been classified as“BASIC” by the FAA and is approved under the Type Validation Principles.		MDL-D206-628 – Master Drawing List, Revision A dated 10 December 1997 or later approved revision;IIN-D206-628 – Installation Instruction, Revision A dated 28 November 1997 or later approved revision;MMS-D206-628 – Maintenance Manual Supplement, Revision A dated 27 November 1997 or later approved rev...		26/07/2007	Active	10016945
EASA.IM.R.S.01340	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR01976NY-D	SIKORSKY S-92A	Installation of Keystone Helicopter Auxiliary Gauges and Relocation of Fill Ports for the Low Float Pressure Warning System.		• Installation in accordance with Keystone Document Reference IDL00972 rev C dated 8/29/2005, or later approved revisions.• Operation in accordance with Keystone Rotorcraft Flight Manual Supplement Reference FM00972, rev. – dated 12-19-2005, or laterapproved revisions.• Instructions for Con...		29/06/2007	Active	10016946
EASA.IM.R.S.01341	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SH7685SW	BO 105 C/S	Replacement of the MBB Oil Cooler Fairing, MBB P/N 105-61802		FAA STC SH 7685SWInstallation in accordance with ERA Drawing 10579-100-001, dated September 27, 1989, or later approvedrevision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	15/08/2007	Active	10016947
EASA.IM.R.S.01344	PARAVION TECHNOLOGY, INC.		FAA STC SR00489SE	BELL 407	Installation of Cabin Air Conditioner System.		DL-407AC-110 revision A dated 24 November 1997 or later approved Revision – Master Drawing List.PR-407AC-110M revision 3 dated 24 July 2003 or later approved revision – RotorcraftFlight Manual Supplement.PR-407AC-120M revision 7 dated 1 August 2006 or later approved Revision – Instructions for Cont...		21/08/2007	Active	10016949

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01345	PARAVION TECHNOLOGY, INC.		FAA STC SR00280DE	BELL 407	Installation of Bleed Air Cabin Heater System.		DL-407H-100 revision D dated 24 February 1997 or later approved Revision – Master Drawing List.PR-407H-100M revision 2 dated 18 April 2002 or later approved revision – Rotorcraft Flight Manual Supplement.PR0407H-120 M revision N/C dated 14 April 1997 or later approved revision – Instructions for Cont...		21/08/2007	Active	10016950
EASA.IM.R.S.01346	ISOLAIR Inc., ISOLAIR HELICOPTER SY		FAA STC SH4796NM	BELL 206B	Installation of Isolair 3900-206 Spray System consisting ofa fibreglass 130 gallon belly tank and spray booms for agricultural applications.		39206INS revision B dated 22 August 2006 or later approved revision – Installation Manual; 3900-206 revision IR dated 14August 2006 or later approved revision – Master Drawing List;3900ICA revision A dated 6 August 2006 or later approved revision – Maintenance Instructions;39206FMS revision B dated...	Bell 206B High Skid Landing Gear must be installed.An aircraft with this STC installed will be operating in the Restricted Category.Essential crew required for the mission only;Vne is 90 KIAS;Spaying at airspeeds below 17 KIAS is prohibited; andSpraying prohibited whilst hovering or in sideways or r...	06/03/2008	Active	10016951
EASA.IM.R.S.01348	PARAVION TECHNOLOGY, INC.		FAA STC SR00025DE	BELL 206A/B/L/L-1/L-3/ L-4, 407	Installation of an Equipment Tray.		DL-206/407ET-100 revision N/C dated 27 July 1999 or later approved Revision – Master Drawing List.	This approval is for a shelf only. The shelf is rated for a15 pound load and must be placarded as shown in drawing 206ET-1000, Revision B dated 9 February 1993 or later approved revision.On 206A and B models, this approval is for serial numbers 154 and subsequent due to airframe differences.	21/08/2007	Active	10016952
EASA.IM.R.S.01349	PARAVION TECHNOLOGY, INC.		FAA STC SR00335DE	BELL 407	Snow Pads Installation.		- DL-407SP-100 revision A dated 22 January 1998 or later approved Revision – Master Drawing List.- PR-407SP-100M dated 2 February 1998 or later approved revision – Rotorcraft Flight Manual Supplement		21/08/2007	Active	10016953
EASA.IM.R.S.01350	PARAVION TECHNOLOGY, INC.		FAA STC SR00344DE	BELL 407	Installation of External Mirror. (This STC has been classified as “BASIC” by the FAA in accordance with FAA Order 8110.52 and has been approved using the PTVP Procedures.)		DL-407EM-100 revision N/ CA dated 9 January 1998 or later approved Revision – Master Drawing List.		06/09/2007	Active	10016954
EASA.IM.R.S.01351	PARAVION TECHNOLOGY, INC.		FAA STC SR00011DE	BELL 206B/L/L-1/L-3/L-4, 407	Provision for Mount of a Video Monitor Placed on Left or Right Instrument Panel Console.		DL-206/407MM-110 revision N/C dated 27 July 1999 or later approved Revision – Master Drawing List.	This approval is for the Mount Assembly only. The monitor installed must meet the requirements shown in drawings approved under theMaster Drawing List No. DL-206/407MM-110 revision N/ C dated 27 July 1999 or later approved revision.On Bell 206B models, this approval is for serial numbers 914 and subs...	21/08/2007	Active	10016955

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01352	PARAVION TECHNOLOGY, INC.		FAA STC SR00486DE	BELL 407	Installation of mounting hardware and approval for the aircraft to be operated by a single pilot from the left crew seat.		DL-407LS-100 revision N/C dated 1 April 2002 or later approved Revision – Master Drawing List.PR-407LS-100M revision 1 dated 3 March 2003 or later approved revision – Rotorcraft Flight Manual Supplement.PR-407LS-120 M revision 0 dated 5 December 2002 or later approved Revision – Instructions for Cont...	For left seat operation of equipment originally intended tobe operated by the pilot from the right crew seat, provisions must be made to ensure that such equipment can be equallyoperable from the left crew seat with similar controls.	21/08/2007	Active	10016956
EASA.IM.R.S.01353	PARAVION TECHNOLOGY, INC.		FAA STC SR00411DE	BELL 407	Installation of Mounting Hardware to Support Blade Folding Kit.		DL-407BF-100 revision N/C dated 30 November 1999 or later approved Revision - Master Drawing List.PR-407BF-120 revision N/C dated 2 February 2000 or later approved Revision - Instructions for Continued Airworthiness.		10/09/2007	Active	10016957
EASA.IM.R.S.01355	AIRGLAS, Inc.		FAA STC SH709AL	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of Airglas, Inc. P/N L2700-AS350 skis on Eurocopter AS350 series helicopters.This STC is a validation of FAA STC SH709AL issued on January 29, 1981 and last amended on November 13, 2000		Definition, installation, and maintenance:Descriptive Data List No. L2700-AS350, Rev. C dated August 22, 2007 approved by FAA, or later FAA approved revisions.Operation:AS350 B FAAapproved Rotorcraft Flight Manual Supplement, dated March 11, 1982, or later FAA approved revisionAS350B1 FAA approved R...	1. Installation of Airglas, Inc. P/N L2700-AS350 ski kit isapproved on AS350B, AS350B1, AS350B2, AS350B3, AS350BA, andAS350D helicopters which are equipped with Eurocopter standard or high skid landing gear.2. Installation and operation of the kit on AS350B3 with the modification OP-3369 incorpora...	21/09/2007	Active	10016958
EASA.IM.R.S.01361	DART AEROSPACE Ltd.		TCCA STC SH07-37	BELL 412 EP BELL 412 CF BELL 412 BELL 212 BELL 205B BELL 205A-1 BELL 205A	D412-760 Cabin Floor Protectors.		MDL-D412-760 – Master Drawing List, Revision A dated 29 June 2007 or later approved revision;IIN-D412-760 – Installation Instruction, Revision A dated 8 June 2007 or later approved revision;ICA-D412-760 – Maintenance Manual Supplement, Revision 0 dated 29 June 2007 or later approved revision		06/09/2007	Active	10016962
EASA.IM.R.S.01363	LIFEPORT, LLC		FAA STC SR02054LA	AGUSTA AW-139 AGUSTA AB-139	Installation of an Emergency Medical System		Master Drawing List MDL-831-100, Revision J dated June 12, 2007 or later FAA approved revisionApproved Rotorcraft Flight Manual Supplement for Emergency Medical System in the Agusta AB139 and AW139 Helicopter, document EGR-831-11 approved by FAA June 15, 2007 or later approved revision.	1. The installer of this STC must be ensure that, if thelife vests have been removed with the seats, a life vest for the occupant of the litter system is installed and available to the occupant.	19/09/2007	Active	10016963

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01365	PARAVION TECHNOLOGY, INC.		FAA STC SR00574DE	BELL 407	Installation of 407FL-100 FADEC/Check instrument auxiliary annunciation system. (This STC has been classified as “BASIC” by the FAAin accordance with FAA Order 8110.52 and has been approved using the PTVP Procedures.)		DL-407FL-100 revision A dated 7 September 2004 or later approved Revision – Master Drawing List.PR-407FL-100M revision Original dated 26 January 2005 or later approved revision – Rotorcraft Flight Manual Supplement.PR-407FL-120 M revision 1dated 7 September 2004 or later approved Revision – Instruct...		06/09/2007	Active	10016964
EASA.IM.R.S.01366	PARAVION TECHNOLOGY, INC.	REV. 1	FAA STC SR00349DE	BELL 407	Installation of a Searchlight. This STC has been classifiedas “BASIC” by the FAA and has been approved under the PTVP.		DL-407SX-100 revision A dated 27 April 1998 or later approved revision – Master Document ListPR-407SX-100M revision 0 dated 26 June 1998 or later approved revision – Flight manualSupplement.		19/03/2008	Active	10016965
EASA.IM.R.S.01367	PARAVION TECHNOLOGY, INC.		FAA STC SR00348DE	BELL 407	Infrared Imaging System Installation. This STC has been classified as “BASIC” by the FAA and has been approved under the PTVP.		DL-407IR-100 revision A dated 21 May 1998 or later approvedrevision – Master Document List;PR-407IR-100M revision 4 dated 8 July 2005 or later approved revision – Rotorcraft Flight Manual Supplement.	None.	22/05/2008	Active	10016966
EASA.IM.R.S.01368	BELL HELICOPTER TEXTRON, Inc.		FAA SR00778AT	206L-3, 206L-4 206A, 206B, 206L, 206L-1	Expanded Instrument Panel. This STC is classified as “BASIC” by the FAA and is approved under the Post Type Validation Principles (PTVP).		AA-95023 – Drawing List, revision E, dated 23 February 2006or later approved revision;AA-94004 – Installation Instructions, revision B, dated 1 March 2000 or later approved revision.		16/11/2007	Active	10016967
EASA.IM.R.S.01369	ACROHELIPRO GLOBAL SERVICES, INC		FAA STC SR02292AK	BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206L BELL 206B BELL 206A BELL 206	Sagem ICDS and Crossbow AHRS Installation. Consists of two 8 inch integrated cockpit display units (one PFD and one MFD) including engine instruments and an attitude and heading reference system. This STC is classified as "BASIC" by the FAA and is approved under the Post Type Validation Principles (...		HP 206-34-33-102 – Certification Data List – revision A dated 3 July 2007 or later approved revision;HP 206-34-33-251 -Instructions for Continued Airworthiness - revision N/C dated 3 February 2007 or later approved revision;Addendum to ICA HP 206-34-33-251 revision N/C dated 12 July 2007 or later a...	Maximum ambient operating temperature of 40 degrees Celsius(103 degrees Fahrenheit)	31/10/2007	Active	10016968
EASA.IM.R.S.01370	BELL HELICOPTER TEXTRON, Inc.		FAA SH2616SO	206L-3, 206L-4 206A, 206B, 206L, 206L-1	Lower Console Assembly. This STC is classified as "BASIC" by the FAA and is approved under the Post Type Validation Principles (PTVP).		AA-88094 - Drawing List, no revision, dated 8 August 1989 or later approved revision;AA-00132 - Instructions for Continued Airworthiness, no revision, dated 25 October 2000 or later approved revision.		09/10/2007	Active	10016969
EASA.IM.R.S.01371	BELL HELICOPTER TEXTRON, Inc.		FAA SR01075AT	407	Crew and Passenger Wedge Windows.		AA-96053 - Drawing List, no revision, dated 16 May 1996 or later approved revision;AA-96054 - Installation Instructions, no revision, dated 16 May 1996 or later approved revision;AA-96055 - Instructions for continued Airworthiness, no revision, dated 16 April 1998 or later approved revision.		09/10/2007	Active	10016970

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01372	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR02065LA	AS 355 E/F/F1/F2/N AS 350 B/B1/B2/B3/BA/D	350-31 Lower Front Fairing Assembly.		Instructions for Continued Airworthiness, ICA350-31, Revision B, dated 3rd January 2007, or later approved revision.	1. This approval requires the inspections and overhaul schedules to be performed as defined by Apical Industries Inc's Instructions for Continued Airworthiness, ICA350-31, Revision B, dated 3rd January 2007, or later approved revision.2. Prior to installation of this modification the installer...	23/01/2009	Active	10016971
EASA.IM.R.S.01375	GENEVA AVIATION Inc.		FAA STC SR00242SE	EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 C EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of a new instrument panel and pedestal per MDLGA162.		¿ Master Drawing List GA162 at Rev. Level B dated 11/15/96 or later EASA approved revisions ¿ Installation Instructions GA162-2 Rev -- dated 8/23/95 or later EASA approved revisions ¿ Compliance Checklist CCL-162 Rev -- dated August14, 2007 or later EASA approved revisions	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	11/12/2008	Active	10016974
EASA.IM.R.S.01376	GENEVA AVIATION Inc.		FAA STC SH5119 NM	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 C EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Rear Bench Seat Modification per MDL GA141		Master Drawing List GA141 Rev. C dated 3/22/95 or latter approved revisionsRotorcraft Flight Manual Supplement GA141-3 Revision C dated January 19, 2001 or latter approved revisionsCompliance Checklist CCL-141 Rev -- dated August 17, 2007 or latter approved revisions		03/04/2008	Active	10016975
EASA.IM.R.S.01377	METRO AVIATION, Inc.		FAA STC SR09230RC	EUROCOPTER DEUTSCHLAND EC-135	Installation of landing gear skid extensions		Flight Manual Supplement FLMS 135-110, Rev. B, dated 15.03.2007 or later approved revision.Installation according to Metro Aviation Master Drawing DL 135-110, Revision IR, dated 23.04.1999 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	26/11/2007	Active	10016976
EASA.IM.R.S.01379	EAGLE COPTERS MAINTENANCE Ltd.		TCCA STC SH00-37	BELL 204B	DCL 361 Tailboom Vertical Fin Spar Reinforcement.New STC for modification of tailboom vertical fin spar to comply with requirements of FAA AD 99-17-03.		DCL361 - Aero Design Ltd. Document Control List - revision 5 dated 10 October 2000 or later approved revision;MMS361.03- Eagle Copters Ltd. Maintenance Manual Supplement - revision 2 dated 10 October 2000 or later approved revision.	This approval supports an Alternative Means of Compliance (AMOC) for satisfying FAA AD99-17-03. An EASA AMOC authority is required in addition to this STC.	15/11/2007	Active	10016977

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01381	LIFEPORT, LLC		FAA STC SR09082RC	BELL 230 BELL 222	Air medical System. This STC has been classified as "BASIC'by the FAA and has been approved under the PTVP.		530-2220 revision Z dated 10 Augsut 2007 or later approved refvision drawing List;EGR-814-11 Revision A dated 12 September 2007 or later approved revision - Rotorcraft Flight Manual Supplement.		05/03/2008	Active	10016978
EASA.IM.R.S.01382	LIFEPORT, LLC		FAA STC SR00360DE	BELL 230 BELL 222U BELL 222B BELL 222	Medical System. This STC has been classified as "BASIC" by the FAA and has been approved under the PTVP.		EGR-515-00 revision S dated 10 August 2007 or later approved revision - Master Drawing List;EGR-515-12 revision A dated12 September 2007 or later approved revision - Flight Manual Supplement;EGR-515-15 revision B dated 2 July 2007 or later approved revisionInstruction for continued Airworthiness		05/03/2008	Active	10016979
EASA.IM.R.S.01383	EAGLE COPTERS MAINTENANCE Ltd.	REV. 1	TCCA STC SH03-14	BELL 412 EP BELL 412 CF BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1 BELL 204B	D412-758 GPS receiver Gimbal Mount		1) Master Document List MDL-D412-758 Revision D dated 8 April 20082) Installation Instructions IIN-D412-758 Revision B dated 8 April 20083) Instructions for Continued Airworthiness ICA-D412-758 Revision 2 dated 7 April 2008	1) Eligible GPS receivers are listed in Installation Instructions IIN-D412-758 Revision B dated 8 April 20082) GPS operation is limited to VFR use only	21/04/2008	Active	10016980
EASA.IM.R.S.01384	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02417NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of Honeywell KHF 1050 HF Communication System.		Installation Drawing List IDL01407.	Refer to FAA STC SR02417NY-D.	04/12/2007	Active	10016981
EASA.IM.R.S.01386	SIKORSKY GLOBAL HELICOPTERS Inc.	REV. 1	FAA STC SR02125NY-D	SIKORSKY S-92A	Installation of a Cockpit Pressure Refuelling Control in a SikorskyS-92A.		IDL01367 Drawing List Revision B dated 9 January 2007 or later approved revision;FM01367 Flight Manual Supplement Revision dated 9 January 2007 or later approved revision;IC01367 Instructions for Continued Airworthiness dated 8 December 2006 or later approved revision.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.The installation of this modification by third persons is s...	09/11/2007	Active	10016982
EASA.IM.R.S.01387	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02426NY-D	SIKORSKY S-76C SIKORSKY S-76B SIKORSKY S-76A	Installation of a Replacement Concorde Lead Acid Battery.		Installation Drawing List IDL01379 Rev. RFM FM01379.		05/02/2008	Active	10016983
EASA.IM.R.S.01390	BELL HELICOPTER TEXTRON, Inc.		FAA SR00760NY	407	Installation of SFIM Force Trim System on Bell 407 helicopters.This STC is classified 'Basic' by the FAA and is approved under the post type Validation Principles (PTVP)		HAS Master drawing list document MDL97-05-01, rev G, dated October 12, 2006 or later approved revisionHAS Corporation Rotorcraft Flight Manual Supplement HAS-FMS-97-05, rev A, dated July 27, 2007 or later approved revisionInstructions for continued Airworthiness HAS document MM97-09-02, rev A, dated...		07/04/2008	Active	10016985

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01391	BELL HELICOPTER TEXTRON, Inc.		FAA SR01285AT-D	407	Rubber mounted replacement chin window. This STC is classified as "BASIC" by the FAA and is approved under the Post Type ValidationPrinciples (PTVP).		AA-96122 – Drawing List, revision H, dated 1 May 2007 or later approved revision;AA-96156 – Installation Instructions, revision J, dated 26 April 2007 or later approved revision; orAA 03112 – Installation Instructions, revision C, dated 1 May 2007 or later approved revisionAA-05051 – Instructions fo...		04/12/2007	Active	10016986
EASA.IM.R.S.01393	BRISTOL AEROSPACE LTD.		TCCA STC SH91-15; FAA STC SH26	BELL 430 BELL 230 BELL 222U BELL 222B BELL 222	Installation of Wire Strike Protection System.		The installation is to be done in accordance with Bristol Aerospace Ltd. Drawing List EM103457 Issue E, DOT approved June 12, 2001 or later DOT approved Revision.		10/03/2008	Active	10016987
EASA.IM.R.S.01395	AIRWOLF AEROSPACE L.L.C.		FAA STC SR02491CH	R44, R44 II R22, R22 ALPHA/BETA/ MARINER	Airwolf Rotor Blade Protective Tape.Installation of a leading edge protective tape for Robinson R22 and R44 helicopter models according to FAA STC SR02491CHNote: The recommendation for approval is given based on a review performed in accordance with the Type Validation/Post Type Validation Principle...		Installation instructions:Airwolf Aerospace, LLC Installation Manual RPBT-100. Rev. A dated October 20, 2007 or later FAA approved revisions.		07/02/2008	Active	10016989
EASA.IM.R.S.01396	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC SR00407SE	MD HELICOPTERS 500N MD HELICOPTERS 369HS MD HELICOPTERS 369HM MD HELICOPTERS 369HE MD HELICOPTERS 369FF MD HELICOPTERS 369F MD HELICOPTERS 369E MD HELICOPTERS 369D	Onboard Systems Model 200-187-00 cargo hook on helicopters 369D, 369E, 369FF. 369HE, 369HM, 369HS, 500NEASA validation of FAA STC SR00407SE , amended 2 October 2007, or later approved 07This STC is classified 'Basic' by the FAA and is approved under the post type Validation Principles (PTVP		Fabrication of kit in accordance with FAA Approved Onboard Systems Master Drawing List No. 155-030-00, Revision 12, dated February 22, 2008, or later FAA approved revision;Installation of this replacement cargo hook in accordance with FAA approved Onboard Systems Owner's Manual No. 120-047-00, Revis...	Approval of this change in type design applies to only those McDonnell Douglas model rotorcraft listed above, which were previouslyequipped with an FAA approved installation of McDonnell Douglas cargo hook suspension systems and Breeze-Eastern cargo hooks shown in the following table:A copy of thisC...	18/03/2008	Active	10016990
EASA.IM.R.S.01398	DART AEROSPACE Ltd.		TCCA STC SH92-20, ISSUE 2; FAA	BELL 205A-1 BELL 205A BELL 204B	D204-575/D205-576 Cabin Heating Systems, Transport Canada STC SH92-20 Issue 2 dated 14 May 1992		Bell 205A and 205A-1 aircraft:Dart Aerospace Drawing 205-576 Rev D dated 21 August 2008Dart Aerospace Installation Instructions IIN-D205-576 Rev D dated 21 August 2008.Flight Manual Supplement No FMS D205-576 Rev D dated 21 August 2008Maintenance Manual Supplement MMS-D205-576 Rev B dated 25 January...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsN...	03/09/2008	Active	10016991
EASA.IM.R.S.01402	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01795SE	EUROCOPTER FRANCE EC 120 B	Installation of Cargo Hook Suspension Kit P/N 200 - 308 – 00.		1. Definition and Installation in accordance with:- Onboard Systems Model 200-308-00,Cargo Hook Suspension Kit;- Onboard Systems Master Drawing List 155-115-00,Revision 1, dated October 22,2007 or later approved Revision;- Onboard Systems Owner's Manual 120-123-00,Revision 1, dated Octo...	1. All limitations of RFM supplement apply;2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduceno adverse effect upon the airworthiness of the product. The...	22/01/2008	Active	10016993

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01403	ASI SERVICES		FAA SH296NM	BELL 206L-1	Installation of a Rolls Royce model 250-C30P engine and associated airframe and tail rotor control modifications similar to the Model 206L-3. This STC has been classified as “BASIC” by the FAA and has been approved under the PTVP.		Air Services International FAA Sealed Master Drawing List;ASI-206L-30P revision 8 dated 20 June 2002 or later approved revision – Air Services International Installation Manual;ASI-206L-1-FM revision 15 dated 3 January 2006 or later approved revision – Rotorcraft Flight Manual	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product. The installation of this modification by th...	06/06/2008	Active	10016994
EASA.IM.R.S.01404	DIAMOND J, Inc.		FAA STC NO. SR00031LB DATED MA	BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206L BELL 206B	Installation of Analog/Digital Turbine Outlet Temperature (TOT) Indicator with Exceedance logging Capability. This STC has been classified as "Basic" by FAA and has been approved under the PTVP.		See attached sheet.		05/03/2008	Active	10016995
EASA.IM.R.S.01406	SIKORSKY GLOBAL HELICOPTERS Inc.	REV. 1	FAA STC SR02436NY-D	SIKORSKY S-92A	Installation of a High Intensity Strobe Lights. This STC has been classified as BASIC by the FAA and has been approved under the PTVP.		FM01368 revision dated 24 January 2008 or later approved revision Flight manual Supplement;IC01368 revision dated 20November 2006 or later approved revision Instructions for Continued Airworthiness;IDL 01368 revision A dated 11 January 2008 or later approved revision Installation Drawing List;...		19/03/2008	Active	10016997
EASA.IM.R.S.01408	PARAVION TECHNOLOGY, INC.		FAA STC SH2726NM	269A, 269B, 269C	Cabin Heater Installation.		Drawing list DL-269H, rev. D, or later approved revisionFlight Manual Supplement dated November 22, 1985, or later approved revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	24/09/2008	Active	10016998
EASA.IM.R.S.01409	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01778SE	MD HELICOPTERS 500N MD HELICOPTERS 369HS MD HELICOPTERS 369HM MD HELICOPTERS 369HE MD HELICOPTERS 369FF MD HELICOPTERS 369F MD HELICOPTERS 369E MD HELICOPTERS 369D	Onboard Systems Model 200-300-00 talon LC Hydraulic Cargo Hook Kit without load weight, Model 200-301-00 talon LC Hydraulic Cargo Hook Kit with load weight on helicopters 369D, 369E, 369FF. 369HE, 369HM, 369HS, 500N		Onboard Systems Master Drawing List No. 155-112-00, Revision 2, dated 4 March 2008, or later approved revision;Onboard Systems Owner’s Manual (for 200-300-00 Cargo Hook Kit) No. 120-119-00, Revision 1, dated 13 July 2007, or later approvedrevisions.Onboard Systems Owner’s Manual (for 200-301-00 Car...	This cargo hook is not approved for human external loadApproval of this change in type design applies to only those McDonnell Douglas model rotorcraft listed above, which were previouslyequipped with• Onboard system model 200-187-00 cargo hook (approvals FAA STC SR00407SE and EASA.IM.R.S01396), o...	08/07/2008	Active	10016999
EASA.IM.R.S.01410	AIRBUS HELICOPTERS CANADA LIMITED		TCCA STC SH03-33	EC 130 B4	Cargo Pods Installation		Definition and installation:ECL Master Drawing List MDL-03-013 Issue CECL Installation Procedure IP-ECL-109 Revision 1Inspection and maintenance:ECL Instructions for Continued Airworthiness ICA-ECL-123 Revision 2Compliance:Compliance Program CP-0253 Issue D		12/06/2008	Active	10017000

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01412	DART AEROSPACE USA, Inc.		FAA STC SR00211SE	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 C EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350B	D350-764 Shoulder Harness Kits. This STC has been classified as "BASIC" by the FAA and has been approved under the PTVP.		GA 159 Revision A dated 14 June 1995 or later approved revision- Geneva Aviation Master Drawing Lst;MDL-D350-764 Revision C dated 18 December 2007 or later approved revision - Dart Aerospace USA Master Document List;IIN-D350-764 revision Bdated 16 October 2007 or later approved revision - Dart Aero...		05/03/2008	Active	10017001
EASA.IM.R.S.01415	GENEVA AVIATION Inc.		FAA STC SH5120NM	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 C EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of a two place front seat.		GA142-3 revision C dated 7 July 2000 or later approved revision – Flight manual Supplement;GA142-2 revision G dated 16 November 1995 or later approved revision – Installation Instructions;GA142 revision K dated 29 July 1995 or later approved revision – Top Drawing List;	Copilot dual controls may not be installed with this STC;Number of occupants increased to 7 (1 pilot and 6 passengers) with this STC installed.The following placard to be installed on the instrument panel in front of the pilot:AIRCRAFT IS BALLASTED TO ALLOW HEAVY CABIN LOADING. CHECK WEIGHT AND BALA...	20/03/2008	Active	10017004
EASA.IM.R.S.01417	PRATT & WHITNEY		FAA STC SR00125BO	MD HELICOPTERS 500N MD HELICOPTERS 369HS MD HELICOPTERS 369HM MD HELICOPTERS 369HE MD HELICOPTERS 369H MD HELICOPTERS 369FF MD HELICOPTERS 369F MD HELICOPTERS 369E MD HELICOPTERS 369D MD HELICOPTERS 369A	Installation of a Pratt & Whitney Engine Services. Inc.-Honeywell IntelliStart Plus +TM Electronic Control System P/N DPU-K-010Note: This STC reflects the transfer from Altair Avionics Corporation to Pratt & Whitney Engine Services, Inc.		Pratt & Whitney Engine Services, Inc-Honeywell InstallationManual, DPU-I-010-3, Revision A, dated July 18, 2000, or later approvedrevisions.	1. Aircraft must have Engine modified in accordance withEASA STC EASA.IM.E.S. 01019, FAA STC SE00027EN. 2. Pratt &Whitney Engine Services, Inc. Rotorcraft Flight Manual DPPU-T-250-2 dated July 27, 2000 or later approved revision, is required.3. This system is designed as an electronic aid f...	14/03/2008	Active	10017005

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01418	PRATT & WHITNEY		FAA STC SR00113BO	BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206L BELL 206B BELL 206A	Installation of a Pratt & Whitney Engine Services, Inc. - AlliedSignal Aerospace IntelliStart Plus + TM Electronic Control System P/N DPU-K-010Note: This STC reflects the transfer from Altair Avionics Corporation to Pratt & Whitney EngineServices, Inc.		Pratt & Whitney Engine Services, Inc. - AlliedSignal Aerospace Installation Manual, DPU-I-010-2, Revision E, dated January 14, 2000, or later approved revisions	1. Aircraft must have engine modified in accordance withEASA STC EASA.IM.E.S. 01017, FAA STC SE00026EN. 2. Compatibility of this design change with previously approved modifications must be determined by the installer.3. Pratt & Whitney Engine Services, Inc. Rotorcraft Flight Manual DPU-T-25...	14/03/2008	Active	10017006
EASA.IM.R.S.01419	PRATT & WHITNEY	REV. 1	FAA STC SR00169BO, LBA RC1237	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B EUROCOPTER DEUTSCHLAND BO-105D EUROCOPTER DEUTSCHLAND BO-105	Installation of Pratt & Whitney Engine Services, Inc. SmartCycle+ monitoring and recording system		AML SR00169BO	1. Required maintenance, as prescribed in the applicable airframe or engine Instructions for Continued Airworthiness, shall not be predicted on the data obtained from the Pratt & Whitney Engine Services, Inc. monitoring/recording system.2. This system shall not be used to supersede or replace the p...	25/03/2008	Active	10017007
EASA.IM.R.S.01420	PRATT & WHITNEY		FAA STC SR00126BO AND LBA RC 1	BELL 205A-1	Installation of a Pratt & Whitney Engine Services, Inc. SmartCycle Plus System P/N EMU-K-010-2		Pratt & Whitney Engine Services, Inc. Installation Manual, EMU-I-010-2, Revision B, dated August 22, 2000 or later approved revisions	1. Pratt & Whitney Engine Services, Inc. Rotorcraft Flight Manual EMU-T-250-1 dated August 31, 2000 or later approved revision, is required.2. This system is designed as an electronic aid for recording engine trend and cycle data. This system does not eliminate any scheduled maintenance or parts rep...	03/03/2008	Active	10017008
EASA.IM.R.S.01421	PRATT & WHITNEY		FAA STC SR00118BO, LBA STC RC	EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of Pratt & Whitney Engine Services, Inc. SmartCycle Engine Monitoring System,Part no. CYCLE-K-010		Pratt & Whitney Engine Services, Inc. Installation Manual, Doc. No CYCLE-I-010-1, Revision C, dated March 29, 2000, or later approved revision	1. Pratt & Whitney Engine Services, Inc. Aircraft Flight Manual Supplement for Eurocopter France, Models, AS-350B, AS-350B1, AS-350B2, AS-350BA, and AS-350B3, Doc. No. Cycle-T-250-1, Revision-, approved April 11, 2000, or later approved revision, is required with this modification.2. The SmartCycl...	04/03/2008	Active	10017009
EASA.IM.R.S.01423	PRATT & WHITNEY		FAA STC SR00136BO, LBA RC1176	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E	Installation of a Pratt & Whitney Engine Services, Inc. SmartCycle Twin Engine Monitoring System Part No. CYCLE-K-010-4for AS355N and -5 for AS355E, AS355-F, AS355F1, AS355F2		Pratt & Whitney Engine Services, Inc. Installation Manual, Doc. No CYCLE-I-010-3, Revision D, dated November 30, 2000, or later approved revisions	1. Pratt & Whitney Engine Services, Inc., Aircraft Flight Manual Supplement for Eurocopter France, Models AS355E, AS355-F, AS355-F1, AS355F2, and AS355N, Doc. No. CYCLE-T-250-2, Revision-, approved May 22, 2001, or later approved revision,is required with this modification.2. The SmartCycle Twin En...	04/03/2008	Active	10017010

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01424	PRATT & WHITNEY		FAA STC ST00049BO, LBA RC 1048	ROBINSON R22 BETA ROBINSON R22 ALPHA ROBINSON R22	Installation of a Pratt & Whitney Engine Services, Inc. Health Usage Monitoring System (HUMS) Model 1022, P/N HUMS-A-030-1		HUMS Installation Instructions, HUMS-I-030-1, Version 1.3, dated December 8, 1995, or later approved revisions	1. Federal Aviation Administration approval of the HUMS installation was determined on a non-interference basis. Operation of maintenance must not be predicated on the HUMS.	04/03/2008	Active	10017011
EASA.IM.R.S.01425	PRATT & WHITNEY		FAA STC SR00067BO, LBA STC RC	EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of a Pratt & Whitney Engine Services, Inc. Health Usage Monitoring System (HUMS) Model 1122, P/N HUMS-A-070-I, Revision B		HUMS Installation Instructions, HUMS-I-07003, HUMS-I-070-3,Version 1.4, dated November 13, 1996, or llater approved revisions.	1. Federal Aviation Administration approval of the HUMS installation was determined on a non-interference basis. Operation of maintenance must not be predicated on the HUMS.	04/03/2008	Active	10017012
EASA.IM.R.S.01430	AEROMETALS INC.		FAA STC SR00981LA	369HM, 369HS, 500N 369D, 369E, 369FF, 369HE	Strut Assy - Landing Gear, p/n 369XH6001, EASA validation of FAA approved PMA part.		Instructions for Continued Airworthiness 369XH6001 Rev 03/18/05 or later FAA approved revision.Master Drawing List No. 28 Rev G 07/19/05 or later FAA approved revision.		29/04/2008	Active	10017013
EASA.IM.R.S.01431	AEROMETALS INC.		FAA STC SR00766LA	369HM, 369HS 369D, 369E, 369FF, 369HE	Skid Tube Position Light Assys., p/n 369XH92041, EASA validation of FAA approved PMA part.		Aerometals Instructions for Continued Airworthiness AMI-11 Rev A 02/16/99 or later FAA approved revision.Master DrawingList No. 18 Rev A 11/11/99 or later FAA approved revision.		29/04/2008	Active	10017014
EASA.IM.R.S.01432	AEROMETALS INC.		FAA STC SR01062LA	369HM, 369HS, 500N 369A, 369D, 369E, 369HE	Exhaust Tailpipe Outlet hangar Assys., p/n 369X8236, EASA validation of FAA approved PMA part.		Aerometals Instructions for Continued Airworthiness AMI-18 Rev C 08/11/03 or later FAA approved revision.Master DrawingList No. 30 03/26/02 or later FAA approved revision.		29/04/2008	Active	10017015
EASA.IM.R.S.01433	AEROMETALS INC.		FAA STC ST01550SE	369D, 369E, 369FF, 500N	Scavenge Air Elbow Assy., p/n AM369D290135, EASA validationof FAA approved PMA part.		Installation Instructions AMC MI-04003 Rev IR 10/06/04 or later FAA approved revision.Master Drawing List MDL-AMC-019 Rev IR 10/06/04 or later FAA approved revision.		29/04/2008	Active	10017016
EASA.IM.R.S.01435	APICAL INDUSTRIES, Inc.d/b/a DART AEROSPACE		FAA STC SR02108LA	AB139, AW139	Nose Landing Gear Doors Kit on Agusta AB139, AW139.		Master Document List MD139-2, Revision B, dated November 8,2007, or later approved revision.Instructions for ContinuedAirworthiness, ICA139-2, Revision A, dated August 6, 2008, or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	29/01/2009	Active	10017017
EASA.IM.R.S.01437	AEROMETALS INC.		FAA STC SR01136SE	500N 369FF, 369HE, 369HM, 369HS 369A, 369D, 369E, 369F	Landing Gear Fillet Fairings p/n AM369A6200-45, -46, -57, -58; and Landing Gear Fairing Guides p/n AM369H6200-73, -74.EASA validation of FAA approved PMA part.		MDHI AMM CSP-HMI-2 Rev 21 or later FAA approved revision.Master Drawing List AMC-003 Rev A 08/29/02 or later FAA approved revision.MDHI Service & Maintenance Instructions:- CSP-HMI-2 Section 32-10-00 (Models 369D, E, F & 500N)- CSP-H2 Section 6 (Models 369A, HM, HS, HE)		29/04/2008	Active	10017019

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01439	BELL HELICOPTER TEXTRON, Inc.		FAA SH8713SW	230	Replacement of the cabin door with right hand sliding door.This STC has been classified as “BASIC” by the FAA and has been approved under the PTVP.		230-530-102 Revision A dated 28 April 1994 or later approved revision – Sliding Door Installation R.H.; 230-530-116 Revision IR dated 1 August 1994 or later approved revision – Sliding Door Installation L.H.;BHT-230-FMS-24 Reissue 0 dated 29 September 1995 or later approved revision – Flight Manual S...		08/05/2008	Active	10017021
EASA.IM.R.S.01440	APICAL INDUSTRIES, Inc.		FAA SR01439LA	407	Emergency Float Assemblies.		MD407-1 Revision C dated 5 February 2003 or later approved revisions – Master Document List;ICA407-1 Revision N/C dated12 June 2002 or later approved revision – Instructions for Continued Airworthiness	Bell Helicopter Textron Canada Limited Emergency Float Kit P/N 407-350-300-101 and/or 407-350-301-101 and/or 407-350-302-101 must be installed prior to the installation of this STC;The intermixed installation configuration between the following Apical Industries Inc. and Bell Helicopter Textron Cana...	13/03/2008	Active	10017022
EASA.IM.R.S.01441	APICAL INDUSTRIES, Inc.		FAA SR01392LA	A119, AW119MKII	Emergency Float Kits FAA STC SR01392LA dated 21 December 2007.		Master Document List MD A119-1 Rev. T dated 19 November 2007 or later approved revision.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsR...	12/06/2008	Active	10017023
EASA.IM.R.S.01442	EAGLE COPTERS MAINTENANCE Ltd.		FAA STC SR00600NY	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 C EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	D350-721 Lightweight Heli Utility Basket Installations.		IIN-D350-721 revision A dated 18 November 2004 or later approved revision – Installation Instructions;FMS-D350-721 revision B dated 3 June 2008 or later approved revision – FlightManual Supplement;ICA-D350-721 dated 22 November 2004 or later approved revision – Instructions for Continued Airworthin...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.	05/06/2008	Active	10017024
EASA.IM.R.S.01444	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01815SE	EUROCOPTER FRANCE EC 130 B4	Installation of Model 200-321-00 Cargo Hook Swing Suspension Kit and Model 200-322-00 Cargo Hook Sling Suspension Kit.		• Definition and installation:¿• Definition and installation: ¿ Onboard Systems Master Drawing List No. 155-121-00, Rev. 1 dated February 6, 2008 or later EASA approved revisions ¿ Onboard Systems Owner’s Manual No. 120-131-00 Rev. 1 dated February 4, 2008 or later EASA approved revisions•...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	27/03/2009	Active	10017025

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01445	DEVORE AVIATION CORPORATION OFAMERICA		FAA STC SH3754SW		Installation of DeVore forward facing recognitions lights		DeVore Top Drawing 10900002 Rev. C dated 17 May 2004 or later FAA approved revision.DeVore DR-317	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	01/07/2008	Active	10017026
EASA.IM.R.S.01446	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01812SE	EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of Cargo Hook Kit P/N 200-297-00 and installation of Cargo Hook Kit P/N 200-298-00This STC is the validation of FAA STC SR01812SE		Definition and installation:Onboard Systems Master Drawing List Doc. No. 155-110-00, Rev. 1, dated September 27, 2006, or later EASA approved revisionsOnboard Systems Owner's Manual No. 120-115-00, Rev. 0 dated April 25, 2005, or later EASA approved revisions (for Cargo Hook Kit P/N 200-297-00).Onbo...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	21/11/2008	Active	10017027
EASA.IM.R.S.01448	HERITAGE AVIATION LIMITED		FAA STC SH7733SW	MD HELICOPTERS 600N MD HELICOPTERS 500N MD HELICOPTERS 369FF MD HELICOPTERS 369E	Installation of enlarged instrument paqnel and slant console. This STC has been classified as "BASIC" by the FAA and has been approved under the PTVP.		A00-13003 revision B dated 14 June 2007 or later approved revision – Master Drawing List;A09-63001 revision Original dated 2 July 2007 or later approved revision – Flight manual Supplement;A04-73003 revision Original dated 22 March 2007 orlater approved revision – Instructions for Continued Airwort...	Not compatible with the MDHI optional centre seat installation.	01/04/2008	Active	10017029
EASA.IM.R.S.01449	DART AEROSPACE Ltd.	REV. 1	TC STC SH05-45	BELL 206B BELL 206A	D206-746 Shroud Air Flow Heater System.		IIN-D206-746 Revision A dated 16 May 2006 or later approvedrevision – Installation Instructions;MDL-D206-746 Revision G dated 11 February 2008 or later approved revision – MasterDocument List;MMS-D206-746 Revision A dated 16 March 2006 or later approved revision – Maintenance Manual Supplement;FMS...		16/04/2008	Active	10017030
EASA.IM.R.S.01451	DART AEROSPACE Ltd.		TCCA STC SH99-221 ISSUE 1	EUROCOPTER FRANCE EC 120 B	D120 -638 Bearpaw Installation.		¿ Definition and Installation in accordance with: Dart Aerospace Ltd. Installation instructions IIN-D120-638, revision A, dated July 7, 1999, or later approved revision. ¿ Inspection and Maintenance in accordance with: Dart Aerospace Ltd. Maintenance Manual Supplement MMS-D120-638, Revision A,d...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	13/08/2008	Active	10017031

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01452	DART AEROSPACE Ltd.		TCCA STC SH01-25 ISSUE 1	EUROCOPTER FRANCE EC 120 B	D120 -639 Wearplate Installation.		¿ Definition and Installation in accordance with: Dart Aerospace Ltd. Installation instructions IIN-D120-639, revision A, dated December 11, 2000, or later approved revision. ¿ Inspection and Maintenance in accordance with: Dart Aerospace Ltd. Instruction for Continued Airworthiness ICA-D120-63...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	13/08/2008	Active	10017032
EASA.IM.R.S.01453	DART AEROSPACE Ltd.		TCCA STC SH02-33	2. AS355 E, F, F1, F2, N 1. (OP-3369 OPTION EXCLUDED) 1. AS350 D, B, B1, B2, BA, B3	Installation of Dual High Back Seat, Left Forward Position (Modificationapproved by TCCA under STC SH02-33 issue 1)		- Dart Aerospace Limited Installation Instructions IIN-D350-689, rev Adated May 30, 2001 or later EASA approved revisions. .- Flight Manual Supplement FMS-D350-689, rev A dated June 6, 2001 orlater EASA approved revisions.- Instructions for Continued Airworthiness ICA-D350-689, rev 0 dated May1, 200...	None	03/06/2009	Active	10034637
EASA.IM.R.S.01456	DART AEROSPACE Ltd.		TCCA STC SH08-5	EUROCOPTER FRANCE AS 355NP EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D1 EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	D350-766 interior Trim Kit Installations		IIN-D350-766 revision A dated 3 March 2008 or later approved revision – Installation Instructions;MDL-D350-766 revisionA dated 3 March 2008 or later approved revision – Master Document List;ICA-D350-766 revision 0 dated 3 March 2008 or later approved revision – Instructions for Continued Airworthin...		30/04/2008	Active	10017033
EASA.IM.R.S.01458	DART AEROSPACE USA, Inc.		FAA STC SR00948SE	AGUSTA AW-119 MKII AGUSTA A-119	FAA STC SR00948SE “D119-675 Heli-Access-Step”.		Drawin List D119-675 Rev. DDart Aerospace Installation Instructions D119-675 Rev. BInstruction for Continued Airworthiness D119-675 Rev. 1		18/04/2008	Active	10017034
EASA.IM.R.S.01459	FILTRATION DEVELOPMENT CORPORATION		FAA STC SR01616SE	SIKORSKY S-76C+ SIKORSKY S-76C SIKORSKY S-76A++ SIKORSKY S-76A	Installation of an Engine Air Filter System for Sikorsky S-76 models, A+, A++ and C & C+		- FDC/aerofilter Rotorcraft Flight Manual Supplement 1076-1200-105 (for S-76A +/A++/C)- FDC/aerofilter Rotorcraft Flight Manual Supplement 1076-1200-101 (for S-76C +)- FDC/aerofilter 'Documentation Package' 1076-SERIES-DPG-1 Rev IRor subsequent, including 'Installation Instructions' 1076-I...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	05/02/2009	Orphaned	10017035

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01460	HELI-ONE USA		FAA STC SH8601SW	BELL 230	Installation of EDZ-705 EFIS four tube flight instrument System. (This STC was classified as Basic by the FAA and is approved usingthe Post Type Validation Principles.)		HD230-00-0002 rev I/R dated 22 December 1992 or later approved revision – Drawing List;HDD-92-91 dated 8 February 1993 or later approved revision – Flight Manual Supplement		13/05/2008	Active	10017036
EASA.IM.R.S.01461	ONBOARD SYSTEMS INTERNATIONAL		FAA STC SR01394SE	EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of Cargo Hook Sling Suspension Kit P/N 200-287-00This STC is the validation of FAA STC SR01394SE		Definition and installation: ¿ Onboard Systems Master Drawing List Doc. No. 155-096-00, Rev. 5, dated March 4, 2008, or later EASA approved revisions.¿ Onboard Systems Owner's Manual for the Cargo Hook Sling Suspension System RetrofitKit for the Eurocopter AS350 Series, SystemP/N 200-287-00, D...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	06/11/2008	Active	10017037
EASA.IM.R.S.01462	PARAVION TECHNOLOGY, INC.		FAA STC SR00401DE	BELL 206L/L1/L3/L4 AND 407	Snow deflector Installation.		DL-206/407SD-200 revision C Dated 8 January 2007 or later approved revision – Drawing List;PR-206/407SD-120M revision 3dated 12 December 2005 or later approved revision – Instructions for Continued Airworthiness		18/07/2008	Active	10017038
EASA.IM.R.S.01464	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02435NY-D	SIKORSKY S-92A	Installation of a Rockwell Collins SAR-126 Direction FinderSystem. This STC has been classified as "BASIC" by the FAA and has beenapproved under the PTVP.		FM01366 revision – dated 4 January 2008 or later approved revision – Flight manual Supplement;IC01366 revision B dated 30 September 2007 or later approved revision – Instructions for Continued Airworthiness;IDL 01366 revision C dated 26 November 2007 or later approved revision – Installation Drawing...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	10/07/2008	Active	10017040
EASA.IM.R.S.01465	PARAVION TECHNOLOGY, INC.		FAA STC SR00334DE	BELL 407	Pneumatic Door Opener (PDO). This STC has been classified as "BASIC" by the FAA and has been approved under the PTVP.		DL-407PDO-100 revision (-) dated 22 October 1997 or later approved revision – Master Drawing List;PR-407PDO-120M revision 1 dated 12 December 2005 or later approved revision – Instructions for Continued Airworthiness		09/06/2008	Active	10017041
EASA.IM.R.S.01466	HELI-ONE USA		FAA STC SH5880SW REV2	BELL 230	Installation of SPZ-7000 DAFCS System.		HD230-00-0001 revision I/R dated 22 December 1992 or later approved revision – Heli-Dyne Drawing List.HDD-92-24 dated 8February 1993 or later approved revision – Flight Manual Supplement.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	05/06/2008	Active	10017042
EASA.IM.R.S.01467	BELL HELICOPTER TEXTRON, Inc.		FAA SH8421SW	206B, 206L-3, 206L-4	Steerable Nose Landing Light. This STC is classified as "BASIC" by the FAA and is approved under the Post Type Validation Principles (PTVP).		100-12005 revision N dated 11 February 2008 or later approved revision – Drawing List;AA-04025 no revision dated 13 February 2004 or later approved revision – Instructions for Continued Airworthiness		09/07/2008	Active	10017043

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01468	AIR COMM CORPORATION L.L.C		FAA STC SH5226NM	222, 222B, 222U, 230, 430	Installation of a bleed air cabin heating system.		230H-100M-7 revision 2 dated 28 October 1993, or later approved revision – Flight Manual Supplement;DL-222H revision J dated 26 August 1991, or later approved revision – Master Drawing List;222H-200M revision B dated 2 August 1993, or later approved revision – Installation Instructions and Instruct...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	02/09/2008	Active	10017044
EASA.IM.R.S.01469	DART AEROSPACE USA, Inc.	REV. 1	FAA STC SR00910SE	EUROCOPTER DEUTSCHLAND BO-105 EUROCOPTER CANADA BO-105 LS A-	D105-674 Skidtube Installation i.a. with FAA STC SR00910SE		- Dart Master Drawing List MDL-D105-674, Rev B, dated 1st June 2005 or later approved revisions- Dart Instructions for Continued Airworthiness ICA-D105-674, dated 17th March 2000 or later approved revisions		07/01/2009	Active	10017045
EASA.IM.R.S.01470	AIR CRUISERS COMPANY		FAA STC SR02345NY	AS350 B, AS350 B1, AS350 B2 AS350 B3, AS350 BA, AS350 D	Fuselage Mounted Liferaft System (FMLR) installation.		Installation Data List EDR 01-1438 Rev. B, dated October 30, 2007 or later approved revisions;Flight Manual Supplement EDN 3259, Rev. "-" or later approved revisions;Instructions for Continued Airworthiness ICA-25-62-37 Rev. "-" dated September 18, 2007 or later approved revisions.	Installation of DART Aerospace Spacepod, P/N D350-600-(042,142, 242) side cargo compartment extender iaw STC EASA.IM.R.S.01292 rev. 1 issued on 07 May, 2008 is required prior to the installation of the Fuselage Mounted Liferaft System;Prior to installation of this modification the installer must de...	18/07/2008	Active	10017046
EASA.IM.R.S.01471	BELL HELICOPTER TEXTRON, Inc.		FAA SH3316SO	212, 412, 412EP	Pushout Window Assembly		AA-92063 revision F dated 11 May 2000 or later approved revision – Drawing List;AA-92057 revision K dated 7 January 2004 or later approved revision – Installation Instructions forBell 412EP S/N 36191 and subsAA-98179 revision D dated 30 July 2002 or later approved revision – Installation Instructio...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	18/06/2008	Active	10017047
EASA.IM.R.S.01472	HERITAGE AVIATION LIMITED		FAA STC SR09483RC	MD HELICOPTERS 600N MD HELICOPTERS 500N MD HELICOPTERS 369FF MD HELICOPTERS 369E	Heritage Aviation, Ltd. STC SR09483RC; Replacement Instrument Panel (including pedestal, shrouds and glare shield) on applicable MDHI 369E, 369FF, 500N & 600N helicopters.		- Compliance Checklist; E07-1241 Rev.A or subsequent approved revision.- Master Drawing List; A00-13001 Rev.C or subsequent approved revision.- Instructions for Cont.A/w;A04-73001 Rev.- (26.4.07) or subsequent approved revision.	1. Applicable to MDHI 369E, 369FF, 500N and 600N helicopters.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness o...	19/03/2009	Active	10017048
EASA.IM.R.S.01473	HERITAGE AVIATION LIMITED		FAA STC SR09484RC	MD HELICOPTERS 500N MD HELICOPTERS 369FF MD HELICOPTERS 369E	Heritage Aviation, Ltd. STC SR09484RC; Chelton EFIS installation on applicable MDHI 369E, 369FF & 500N helicopters.		- Compliance Checklist; E07-1242 Rev A or subsequent approved revision.- Master Drawing List; A00-14002 Rev.D or subsequent approved revision.- Instructions for Cont.A/w;A04-74002 Rev.- (7.5.07) or subsequent approved revision.- RFM Supplement; A09-54004 Revision B or subsequent approve...	1. Applicable to MDHI 369E, 369FF, 500N.2. Operation with the Chelton EFIS is limited to VFR only.3. (See limitations specified in RFM Supplement)4. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any otheri...	19/03/2009	Active	10017049

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01475	BELL HELICOPTER TEXTRON, Inc.		FAA SR09379RC-D	412 EP	Pilot heater failure monitor kit (412-081-001/002), Stand by attitude battery monitor kit (412-080-001), Crew flashlight holder kit(412-086-001).		- SR09379RC-D "Optional Accessories Kits"- RFM Supplements:• AA-07147, dated 14.04.2008 or later approved revision;• AA-08008, dated 14.04.2008 or later approved revision.- Instructions for Continued Airworthiness: Aeronautical Accessories, Inc., Report No. AA-07142, Rev. A, dated 02....	1. Applicable to Registration Marks I-OTEL.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduceno adverse effect upon the airworthiness of the product.3. d...	05/03/2009	Active	10017051
EASA.IM.R.S.01476	VIH AEROSPACE Inc.		TCCA STC SH08-29	S92A		HS Crew Bubble Window Installation	- VS92-0803-MDL revision 0 dated 16 May 2008 or later EASA approvedrevision - Master Drawing List;- VS92-0803-FMS revision 0 dated 16 May 2008 or later EASA approvedrevision - Flight manual Supplement;- VS92-0803-ICA revision 0 dated 16 May 2008 or later EASA acceptedrevision - Instructions for Cont...	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.This Certificate shall remain valid unless otherwise surren...	25/02/2009	Active	10043045
EASA.IM.R.S.01477	DART AEROSPACE USA, Inc.		FAA STC SR00914SE	EUROCOPTER FRANCE SA 315B	Installation of DART Bearpaws P/N D315-670-011 - Validationof FAA STC SR00914SE.		DART Aerospace Drawing List MDL-D315-670, revision B, dated1-June-2005, or later approved revisionsDart Aerospace Installation Instructions IIN-D315-670, revision C, dated 4-April-2000, or later approved revisions.Dart Aerospace Maintenance Manual MMS-D-315-670, revision B, dated 4-April-2000, or l...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	06/02/2009	Active	10017052
EASA.IM.R.S.01478	DART AEROSPACE USA, Inc.		FAA STC SR00848SE	EUROCOPTER FRANCE SA 315B	Installation of Dart Aerospace Skidtube P/N D315-668-011 (LH) and -012 (RH). Validation of FAA STC SR00848SE.		DART Aerospace Installation Instructions IIN-D315-668, Revision A, dated 20-Sept-1999, or later approved revisions.DARTAerospace Maintenance Manual Supplement MMS-D315-668, Revision A, dated 13-Sept-1999, or later approved revisions.DART Aerospace Master Drawing List MDL-D315-668, Revision E, dated...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	06/02/2009	Active	10017053
EASA.IM.R.S.01482	GENEVA AVIATION Inc.		FAA STC SH4776NM	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of replacement transmission cowling panels i.a.w. MasterDrawing List GA119.This STC is the validation of FAA STC SH4776NM (issued on October 06,1989).		-,,Master Drawing List GA119 Rev. B dated 8/17/07 or later revisions ofthe above listed documents approved by EASA in accordance with EASA EDDecision 2004/04/CF (or subsequent revisions of this decision.	1.,,Prior to installation of this modification the installer mustdetermine that the interrelationship between this modification and anyother previously installed modification willintroduce no adverse effectupon the airworthiness of the product.2.,,The installation of this modification by third pers...	17/02/2009	Active	10030234

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01483	GENEVA AVIATION Inc.		FAA STC SR00191SE	EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 C EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of a single place pilot/copilot seat in accordance with MDL GA156		Master Drawing List GA156 Rev. B dated 23 August, 2007, or later approved revisionsCompliance Checklist CCL-156 Rev -- dated May 6, 2008 or latter approved revisions	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	27/08/2008	Active	10017054
EASA.IM.R.S.01486	AERO PACIFIC	REV. 1	FAA STC STC SR01521LA	AS350 B, AS350 B1, AS350 B2 AS350 BA, AS350 B3, AS350 D	Installation of a Belly Utility Mount.Note: This STC supersedes EASA.IM.R.S. 01486.		- Aero Pacific Master Data List Doc. No. 350UM02 30, Rev. 1 dated 24 January 2006 or later EASA approved revisions.- Aero Pacific Rotorcraft Flight Manual Supplement Doc. No. 350UM02 10, initial issue, dated 16 July 2003 or later EASA approvedrevisions.	1. This STC provides approval for structural provisions for installation of other equipment. This other equipment for which these provisions are intended has not been certified. A separate EASA approval is required for the installation of this equipment.2. Prior to installation of this modific...	04/03/2009	Active	10017055
EASA.IM.R.S.01487	PARAVION TECHNOLOGY, INC.			BELL 206, BELL 407	Vent Control Certification.		206VC-100 revision NC dated 22 November 2006 or later approved revision – Master Drawing List.PR-206VC-120M revision 0 dated 22 September 2006 or later approved revision – Instructions for Continued Airworthiness.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	11/08/2008	Active	10017056
EASA.IM.R.S.01492	DART AEROSPACE Ltd.	REV. 1	TCCA STC SH08-40	BELL 412 EP BELL 412 BELL 212	Replacement Glareshield Installation.		- IIN-D412-776-Rev. B, INSTALLATION INSTRUCTIONS or later approved revision- MDL-D412-776-Rev. B, MASTER DOCUMENTLIST or later approved revision- ICA-D412-776-Rev. 0, INSTRUCTIONS FOR CONTINUED AIRWORTHINESS or later accepted revision	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third per...	04/05/2009	Active	10017059
EASA.IM.R.S.01494	PRECISE FLIGHT, Inc.		FAA STC SR01821SE	R22, R22 ALPHA, R22 BETA R22 MARINER	Installation of a Precise Light HID Aviation Lighting System according to FAA STC SR01821SE.		1. Engineering Drawing List (Manufacturing) 020H0000 Rev. C2. Engineering Drawing List (Installation) 590H0000 Rev. B3. Instructions for Continued Airworthiness 590HMAN0002 Rev. A	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	14/11/2008	Active	10017060

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01496	PARAVION TECHNOLOGY, INC.		FAA STC SR00654DE	BELL 206A, 206B, 206L, 206L-1, 206L-3, 206L-4, BELL 407	Rotary Latch Belts Installation.		DL-407SB-100 revision A dated 1 November 2007 or later approved revision – Master Drawing List;PR-407SB-120M revision 1dated 2 November 2007 or later approved revision – Instructions for Continued Airworthiness	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	03/09/2008	Active	10017061
EASA.IM.R.S.01497	BELL TEXTRON CANADA LIMITED		TCCA SH05-2	212, 412, 412EP	TCCA SH05-2 “Cold Weather Use of Kerosene Fuels”.		1. Model 212: BHT-212-FMS-31 Issue 0, dated 24 January 2005.2. Model 412: BHT-412-FMS-23.1/-23.2/-23.3 Issue 0, dated 24 January 2005.3. Model 412EP: BHT-412-FMS-23.4 Issue 0, dated 24 January 2005.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	24/11/2008	Active	10017062
EASA.IM.R.S.01502	SIMPLEX MANUFACTURING CO.		FAA STC SR00889SE	EUROCOPTER FRANCE AS 355 SERIE	Installation of an agricultural spray system. (This STC hasbeen classified as “BASIC” by the FAA in accordance with FAA Order 8110.52 and has been approved using the PTVP Procedures.)		MDL-210 revision B dated 9 February 2001 or later EASA approved revision – Master Drawing List; 210-102005-001 revision I/R dated 21 December 2000 or later approved EASA revision –Maintenance Manual;210-102003-002 dated 14 March 2001 or later EASA approved revision – Flight Manual Supplement.	Rotorcraft to be equipped with an EASA approved high skid landing gear; Essential Crew only; Day/Night VFR only; and Airspeed Limitations per Flight Manual Supplement.Prior to installation of this modification the installer must determine that the interrelationship between this modifica...	26/09/2008	Active	10017066
EASA.IM.R.S.01504	HERITAGE AVIATION LIMITED		FAA STC SR09481RC	MD HELICOPTERS 600N MD HELICOPTERS 500N MD HELICOPTERS 369FF MD HELICOPTERS 369F MD HELICOPTERS 369E	Heritage Aviation, Ltd. STC SR09481RC; Installation of noseshelf on applicable MDHI 369E, 369F, 369FF, 500N & 600N helicopters.		Compliance Checklist; E07-1240 Rev.A or subsequent approvedrevision.Master Drawing List; A00-13002 Rev.B or subsequentapproved revision.Instructions for Cont.A/w; A04-73002 Rev.-(26.4.07) or subsequent approved revision.	1. Applicable to MDHI 369E, 369F, 369FF, 500N and 600N. 2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of thei...	19/03/2009	Active	10017068
EASA.IM.R.S.01505	AEROQUEST INTERNATIONAL		TCCA STC SH97-63;	AS355 F, AS355 F1, AS355 F2 AS350 B, AS350 B1, AS350 B2 AS350 BA, AS350 D, AS355 E	AS350/AS355 Aeroquest Survey Installation		IM-PA-06-040-91-01 issue 1 revision D dated 29 April 2008 or later approved revision – Installation manual;MDL-PA-06-040-91-01 issue 1 revision D dated 22 April 2008 or later approved revision – Master Drawing list;FMS-PA-06-040 issue 1 revision G dated 30 April 2008 or later approved revision – Fli...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by thi...	28/05/2009	Active	10017069
EASA.IM.R.S.01506	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02577NY-D	SIKORSKY S-76C	Keystone Helicopters STC SR02577NY-D; Introduction of a cockpit digital video recorder system to meet JAR-OPS 3 flight data recorder requirements on applicable Sikorsky S-76C series aircraft.		¿ Keystone Rotorcraft Flight Manual Supplement FM01394 Rev.1*¿ Cert. Plan ER01394 Rev.A* ¿ Drawing Lists IDL 01394 Rev.A & RDL 01394 Rev.-*¿ Instructions for Cont.A/w; IC01394 Rev.A**or later approved revisions of the above documents	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	19/02/2009	Active	10017070

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01513	AEROQUEST INTERNATIONAL		TCCA STC SH08-52 ISSUE 1	SA 315 B	Installation of Aeroquest Survey Modification - Validation of Transport Canada (TCCA) STC No. SH08-52.		JCM Aerodesign Limited Flight Manual Supplement 0630025FMS,dated 9-Oct.-2008 or later approved revisions.JCM Aerodesign Limited Maintenance Manual Supplement 0630025MMS, dated 9-Oct.-2008 or later accepted revisions.JCM Aerodesign LimitedMaster Drawing List 0630025MDL, issue 3 or later approved re...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	06/02/2009	Active	10017073
EASA.IM.R.S.01514	SIMPLEX MANUFACTURING CO.		FAA STC SR00890SE	AS 350 D AS 350 BA AS 350 B3 AS 350 B2 AS 350 B1 AS 350 B	Model 210 Spray System - Installation of an agricultural spray tanksystem		- Simplex Master Drawing List MDL-210, Revision B, dated February 9,2001, or later EASA approved revision.- Simplex Installation Document Nº 210-102 002-001, Revision I/R, datedDecember 21, 2000, or later EASA approved revision.- Simplex Maintenance Document Nº 210-102 005-001, Revision I/R, datedDe...	Rotorcraft modified in accordance with this STC must be operated inaccordance withEASA approved Rotorcraft Flight Manual (RFMS), Simplex Document Nº210-102003-002 / EASA, dated 20, May 2009, or later EASA approved revision.	28/05/2009	Active	10027140
EASA.IM.R.S.01518	DART AEROSPACE Ltd.		TC STC SH08-37 ISSUE 1	BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1	D205-778 Comfort Seat Installation		MDL-D205-778 revision A dated 9 September 2008 or later EASA approved revision – Master Document ListIIN-D205-778 revision A dated 25 April 2008 or later EASA approved revision – Installation InstructionsICA-D205-778 revision 0 dated 25 April 2008 or later EASA approved revision – Instructions for C...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.The installation of this modification by third p...	09/01/2009	Active	10017075
EASA.IM.R.S.01519	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02573NY-D	SIKORSKY S-92A	Installation of Main Rotor Blade Recognition Lights.		- IDL01701 revision – dated 9 October 2008 or later EASAapproved revisions – Installation Drawing List;- ICO1701revision – dated 14 March 2008 or later EASA approved revision – Instructions for continued Airworthiness;- FM01701 revision – dated 23 October 2008 or later EASA approved revis...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	02/12/2008	Active	10017076
EASA.IM.R.S.01528	DART AEROSPACE Ltd.		TCCA STC SH08-08	BELL 205A-1 BELL 205A	Replacement Engine Mount Installation (kit 205-770)		¿ IIN-D205-770 revision A dated 1 November 2008 or laterEASA approved revision – Installation Instructions;¿ MDL-D205-770 revision B dated 24 November 2008 or later EASA approved revision – Master Document List; ¿ ICA-D205-770 revision 0 dated 24 November 2008 or later EASA accepted revisio...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.	26/02/2009	Active	10017078

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01529	DART AEROSPACE Ltd.		TCCA STC SH08-53	BELL 412 EP BELL 412 BELL 214B-1 BELL 214B BELL 212 BELL 205B BELL 205A-1 BELL 204B AGUSTA AB-412EP AGUSTA AB-412	Procedure Trim Installations (kit D412-775).		IIN-D412-775 revision A dated 14 November 2008 or later EASA approved revision – Installation Instructions;MDL-D412-775revision A dated 1 December 2008 or later EASA approved revision – Master Document List;ICA-D412-775 revision 0 dated 14 November 2008 or later EASA approved revision – Instruction...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.	25/02/2009	Active	10017079
EASA.IM.R.S.01530	ONBOARD SYSTEMS INTERNATIONAL	REV. 1	FAA STC SR00525SE	500N, 600N 369HE, 369HM, 369HS 369D, 369E, 369F, 369FF	Installation of Onboard Systems Model 200-231-00, 200-231-01, 200-231-02and 200-231-03 Cargo Hook Attachment Point Kitsin accordance withOnboard Systems Master Drawing List No. 155-038-00, Rev. 11 datedOctober 26, 2012	The Certification Basis (CB) for the original product remains applicableto this certificate/ approval.The requirements for environmental protection and the associatedcertified noise and/ or emissions levels of the original product areunchanged and remain applicable to this certificate/ approval.	- Installation: Installation of the 200-231-00 and 200-231-01 Cargo HookAttachment Point Kits must be done in accordance with FAA approvedOnboard Systems Owner's Manual No. 120-073-00 Rev.7 dated October 20,2010 and installation of the 200-231-02 and 200-231-03 Cargo HookAttachment Point Kits must b...	Prior to installation of this design change it must be determined thatthe interrelationship between this design change and any otherpreviously installed design change and/ or repair will introduce noadverse effect upon the airworthiness ofthe product.	08/06/2009	Active	10043044
EASA.IM.R.S.01533	PARAVION TECHNOLOGY, INC.			AW119MKII A109 A/-C/-E/-K2/S, A119	Installation for fixed receivers for ground handling blade folding kit		- PR-A109BF1, Rev. N/C dated 18 June 2008- PR-A109BF-6, Rev. N/C dated 16 July 2008- PR-A109BF-2, Rev. N/C dated 16 July 2008- PR-A109BF-5, Rev. N/C dated 21 July 2008- DL-A109BF-109BF-120M, Rev. 1 dared 17 Novem...	none	11/05/2009	Active	10043067
EASA.IM.R.S.01534	APICAL INDUSTRIES, Inc.		FAA SR02180LA	AS 350 B, AS 350 B1, AS 350 B2 AS 350 B3, AS 350 BA, AS 350 D	Installation of a Cable Cutter Kit.		• Apical Master Document List MD350-61, Rev. A dated November 25, 2008, later EASA approved revision• Instructions for Continued Airworthiness for AS350 Cable Cutters Kit P/N 646.4001 & AS350 Wiper Deflector Kit P/N 646.4002 forEurocopter Model AS350 Helicopters, Report No.: ICA350-61, Rev. A...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	23/03/2009	Active	10017081
EASA.IM.R.S.01536	KEYSTONE HELICOPTER CORPORATION		FAA STC SR02430NY-D	S-76C	Installation of a Honeywell Chadwick EVXP Vibration Monitoring System		- Report Document List RDL01449 Rev A or latter approved revision.- Instruction for Continued Airworthiness IC01449 RevA.- Flight Manual Supplement FM0I729 Rev-	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	16/06/2009	Active	10043043
EASA.IM.R.S.01537	AIR COMM CORPORATION LLC		FAA STC SR00643DE	EUROCOPTER FRANCE AS 350					24/07/2009	Active	10027970

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01538	CERTIFIED TECHNOLOGY, INC		FAA STC SR00409SE	369H, 500N, 600N 369D, 369E, 369FF	Rapid Door Removal System Hinges.		- Certification Plan and Regulation Checklist MASOO-001, rev. NC, datedApril 16, 2009.- Drawing List CT9602, rev. H, dated April 30, 2009.- Installation Instructions CT9602-1, rev. E, dated January 9,2009.- Instructions for Continued Airworthiness CT9602-2, rev. -, dated April16,2009.	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	16/06/2009	Active	10043042
EASA.IM.R.S.01540	AAR COMPOSITES, INC.		FAA STC NO. SR03077 AT	S-92A	S-92A Structural Provisions for a Composite Passenger CabinVIP Interior.		• S92-620-011 revision L dated 22 February 2008 or laterapproved revision – Master Document List• AAR-ER-1116 revision E dated 25 January 2008 or later approved revision – Instructions for Continued Airworthiness• AAR-ER-1264 revision IR dated 21 February 2008 or later approved revision –...	1. The installer is responsible for the addition of decorative finish to continue to comply with JAR 29.853.AAR bulkheads are for interior partitions only and are not intended means of compliance for cargo or smoke retention that the installer must ensure is covered by other design approvals.The2...	23/04/2009	Active	10017082
EASA.IM.R.S.01541	DART AEROSPACE Ltd.		TCCA SH 08-60	407 206, L, L-1, L-3, L-4, 206, A, A-1, B, B-1,	D407-781 Interior Trim Panel Installations.		- IIN-D407-781 revision A dated 22 October 2008 or later approvedrevision - Installation Instructions;- MDL-D407-781 revision A dated 19 December 2008 or later approvedrevision - Master Document List;- ICA-D407-781 revision 0 dated 20 November 2008 or later approvedrevision - Instructions for Contin...	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	05/06/2009	Active	10043041
EASA.IM.R.S.01549	AIR COMM CORPORATION LLC		FAA.SR00066 DE	BELL 412	Bell Helicopter 412 air Conditioning System.		- DL-412AC Revision E dated 2 July 1997 or later approved revision -Master Drawing List;- 412AC-100 dated 10 July 1997 - flight manual supplement is requiredfor Air Comm Corporation drawing 412AC-100 configuration (no temperaturecontrol);- 412AC-104 dated 10 July 1997 or later approved revision - f...	none	15/05/2009	Active	10043066
EASA.IM.R.S.01550	SIKORSKY GLOBAL HELICOPTERS Inc.		FAA STC SR02208NY-D	SIKORSKY S-92A	Installation of lavatory.		¿ IDL00845 revision A dated 19 December 2005 or later approved revisions – Installation Drawing List – Configuration1; ¿ IDL00845.1 revision A dated 19 May 2006 or later approved revisions – Installation Drawing List – Configuration 2; ¿ IC00845 revision – dated 31 October 2005 or later appr...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	30/04/2009	Active	10017083
EASA.IM.R.S.01551	DART AEROSPACE USA, Inc.		FAA STC SR01043SE	AGUSTA A119	Cargo Mirror Installation.Note: This STC supersedes ENAC STC N-CS-014 being the validation of FAA STC SR01043SE dated 25 January 2002.		- IIN-D119-696 Rev. A Installation Instructions or laterapproved revision- MDL-D119-696 Rev. C Master Document List or later approved revision- ICA-D119-696 Rev. 0 Instructions for Continued Airworthiness or later approved revision- FMS-D119-696 Rev. A Rotorcraft FM Supplement or later...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	11/05/2009	Active	10017084

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.IM.R.S.01558	FR AVIATION Ltd.D/B/A COBHAM AVIATION SERVICES UK		FAA STC SH2735NM	MD 369HS, 500N, 600N MD 369D, 369E, 369H, 369HE	Pneumatic Door Opener (PDO)This EASA STC supersedes and is a revision of LBA STC 0426/3036.	CS-27	-Master Drawing List: DL-369PDO-100 Rev. E or later approved revision-Instructions for Continued Airworthiness: PR-369DA-120M Rev. O or laterapproved revision-Summary Document (including Cert. Basis): Paravion letter to EASA of5th August 2008	None	23/06/2009	Active	10033806
EASA.IM.R.S.01560	DART AEROSPACE Ltd.		TCCA STC SH92-18	AS350B, BA, B1, B2, B3, D, D1	D350-567 Vertical Reference Window Installations. Addition of AS350Dl tolist of models.This STC revises and supersedes DGAC France STC 84-5[1103, dated 27September 2002.		- MDL-D350-567 revision A dated 23 January 2009 or later approvedrevision - Master Document List;- D350-567 revision D dated 8 July 2008 or later approved revision - Installation Instructions;- ICA-D350-567 revision 0 dated 20 January 2009 or later approvedrevision - Instructions for Continued Airwor...	None	17/07/2009	Active	10034634
EASA.IM.R.S.01561	DART AEROSPACE Ltd.		TCCA STC SH92-18	AS355E, F, F1, F2, N, NP	D350-567 Vertical Reference Window Installations.This STC is a revision of and supersedes DGAC-F STC 168-511104 dated 27September 2002 for addition of AS355N and NP to list of models.		- MDL-D350-567 revision A dated 23 January 2009 or later approvedrevision - Master Document List;- D350-567 revision D dated 8 July 2008 or later approved revision - Installation Instructions- ICA-D350-567 revision 0 dated 20 January 2009 or later approvedrevision - Instructions for Continued Airwort...	None	31/07/2009	Active	10034636
EASA.R.S.00247	AEROSPACE DESIGN FACILITIES Ltd.		CAA UK RESPONSIBILITY	AS 350 B	Installation of an utility boom mout in accordance with Document ListADF 2003-1 dated 17 December 2003 or later EASA approved revision.				14/10/2004	Active	10043024
EASA.R.S.00465	AIR AMBULANCE TECHNOLOGY GmbH	REV. 2		205A-1	Installation of Air Ambulance Equipment		AR04/951. Component-, Installation-, Operation-Manual, illustrated PartCatalogBell 205, AB 205 Air Ambulance EquipmentPIN 205-25-20-1000"One Patient Configuration" CMM-BELL205-AA T3"Two Patient Configuration" CMM-BELL205-AATI82. Flight Manual Bell 205 series AB 205 series Supplement, Air Ambulance...	Prior to installation of this modification the installer must determinethat the interrelationshipbetween this modification and any other previously installedmodification will introduce noadverse effect upon the airworthiness of the product. The installationof this modification bythird persons is sub...	03/08/2007	Active	10042963
EASA.R.S.00469	AIR AMBULANCE TECHNOLOGY GmbH	REV. 1		AS 355 MODELS	Installation of Air Ambulance Equipment		AR 11/971. Component-, Installation-, Operation-Manual, illustrated PartCatalog AS 355 Air Ambulance Equipment PIN 355-25-24-1000, CMM-AS-AATOlissue 0411995, IM-AS355-AAT01, CMM-AS355-AAT25, CMM-AS355-AAT412. Flight manual AS 355 Supplement, Air Ambulance Equipment PIN355-25-24-1000, FMS 10.AAT4. A...	1. Compatibility of this installation with previous installed equipmentmust be determined bythe installer.2. Subject tocompliance with the provisions of EC 1702/2003PART 21Subpart E, thisCertificate and associated data shall remain validuntil surrendered,withdrawn or otherterminated. 3. This STCa...	21/04/2005	Active	10042966

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.00491	MOTORFLUG BADEN-BADEN GmbH			430	Installation of Weather Radar RDR 2000		Flight Manual Supplement Doc. No. Bell 430-01-0601 Revision0 or laterEASA approved revision.Bell 430-01-0101 or later EASA approved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	14/01/2004	Active	10057640
EASA.R.S.00492	AEROTECHNIC GMBH			BELL 430	Installation of Cockpit Voice Recorder Universal CVR-120		- Bell 430-03-0101 or later EASA approved Revision.- FlightManual Supplement Doc. No. Bell 430-03-0601 Revision 0 or laterEASA approved Revision.	1.,,This STC is approved only for the product configurationas definedin the approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	10/01/2004	Active	10043016
EASA.R.S.00541	AIR AMBULANCE TECHNOLOGY GmbH			MD900, MD902	Installation of Air Ambulance Equipment.		AR 015/03:1. Component-, Installation-, Operation-Manual, illustrated PartCatalog MD 900 AirAmbulance Equipment PIN 900-25-24-32.000 CMM-MD900-AAT47.2. Flight Manual MD 900 Supplement, Air Ambulance Equipment PIN900-25-24-32.000 FMSAAT35.	1. This STC is approved only for the product configuration as defined inthe approved designdata referred to in the paragraph "Description". Compatibility withother aircraft/ engineconfigurations shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orre...	20/01/2005	Active	10042967
EASA.R.S.00621	NSE			SA 365 N	Modification of Aircraft Avionics Installation of two COMINAV/GPS GARMINGNS 430, ofan Audio Box KMA24H70, a MKR receiver KR 21, an ELT KANNAD 406AFH and aTransponder GTX 327, in accordance with BA YO FAM No. 33/2003, OriginalEdition datedFebruary 9, 2005.		- Rotorcraft Flight Manual Supplement BA YO No. 33/2003, OriginalEdition dated February2005.	I. The installation of this STC is limited to the AS 365N HelicopterSerial Number 6100.2. When equipped with the STC, the helicopter is limited to VFR flightsonly.3. A copy of this STC and the BA YO Flight Manual SupplementNo. 33/2003,OriginalEdition, dated February 2005, or later EASA approved revi...	15/03/2005	Active	10043131
EASA.R.S.00684	SCANDINAVIAN AVIONICS DESIGN GMBH			AS355 E/F/F1/F2/N AS350 B/1/2/3/A, AS350 D	Installation of Bendix/King KRA 405B Radar Altimeter		EASA-approved AFM Supplement 2022177-AM-01, issue 1 or later EASAapproved revision	This STC is approved only for the product configuration as defined inthe approved design data referred to the paragraph"Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.	11/04/2005	Active	10053190
EASA.R.S.00697	BUCHER LEICHTBAU AG	REV. 2		EUROCOPTER DEUTSCHLAND EC-135-	Ambulance and rescue equipment P/N ARA-EC135-AC65 in accordance with master document list MDOC-AC65 rev D or later approved revision.Revision 1: Change of Converter from ARA-EC135-AC65.Revision 2: Inclusion of models P2+ and T2+		• Rotocraft Flight Manual Supplement No. FMS-AC65 rev c or later approved revision.• Master document list MDOC-AC65 rev D.	1. No smoking is allowed in the rotorcraft cabin.2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraphs "Description" and “Associated Technical Documentation”. Compatibility with other aircraft/ engine configurations shall...	12/01/2007	Active	10017089
EASA.R.S.00730	AIR AMBULANCE TECHNOLOGY GmbH			S-76A	Installation of Air Ambulance Equipment		AR 14/011. Operation-Manual, Installation, Operation Manual, Illustrated partCatalog Air AmbulanceEquipment SIKORSKY S-76A "quick conversion" P/N 76-25-20-34.00,CMM-S76-AAT342. Flight manual supplement, Air Ambulance Equipment P/ N75-25-20-34.000, FMS-AAT22	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall bedetermined by the installer.This certificate shall remain valid unless otherwise surrendered orrevo...	20/05/2005	Active	10042968

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.00732	AIR AMBULANCE TECHNOLOGY GmbH			A109	Installation of Air Ambulance Equipment		AR 16/021. Component-<(>,<)>Installation-<(>,<)>Operation-Manual, IllustratedPart Catalog A 109 Series CMM-A-AAT41 Air Ambulance Equipment PIN109-25-20-35,0002. Flight Manual Supplement, Air Ambulance Equipment PIN109-25-20-35.000 FMS AAT 31	1. This STC is approved only for the productconfiglIrationas defined inthe approved designdata referred to in the paragraph "Description". Compatibility withother aircraft/ engineconfigurations shall be determined by the installer.This certificate shall remain valid unless otherwise surrendered orrev...	26/07/2005	Active	10042969
EASA.R.S.01002	ASTEC HELICOPTER SERVICES AS	REV. 1		AS 332 L, AS 332 L1, AS 332 L2	Skywatch SKY-497 Traffic Advisory System		-Design Report AHSE-51151, Master Drawing AHSE-51150. Rev A, or later approved revision-Flight Manual Supplement AHS-014	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	18/11/2005	Active	10017091
EASA.R.S.01003	ASTEC HELICOPTER SERVICES AS	REV. 1		AS 332 L, AS 332 L1, AS 332 L2	Techtest CPI-503 ELT		Design Report AHSE-51501, Master Drawing List AHSE-51500 Revision F, Flight Manual Supplement AHS-034Service Bulletin AHSB-2566-031, latest approved revision	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	15/11/2005	Active	10017092
EASA.R.S.01011	ESG ELEKTRONIKSYSTEM-UND LOGISTIK-GmbH			EC635 T2+ EC635 P2+ EC635 EC135 T2 (CPDS) EC135 T1 (CPDS) EC135 T1 (CDS) EC135 P2 (CPDS) EC135 P1 (CPDS) EC135 P1 (CDS)	FLIR Mission Work Station EC135Optional installation of an operator station in the cabin for theoperation of mission equipment. The installation is based on ESGEngineering Order 1RPA-ZL-EO_00l in accordance with ESG Master DrawingList 1RPA-MDL-036-01 Issue 1 or later approved revision.		EC135 Flight Manual Supplement:- EC135 Flight Manual Supplement, 1RPA-FMS-025, Issue 1 Revision 2 orlater approved revision.Installation Instructions and Instructions for Continued Airworthiness:- Installation Instruction Order, Doc. No. 1RPA IIO-024, Issue 1 orlater approved revision.- Wartungshand...	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	04/06/2009	Active	10043040
EASA.R.S.01017	SAS MAT AVIATION			EUROCOPTER FRANCE EC 120 B	Upgraded Avionics configuration		Definition:- installation of the following equipment: GARMIN GNS 480 GPS/ Com/NAV/ with remote ATC GTX32; MFD MX20; TCAD9900 BX; AHRS APIRS F201 with its magnetometer; PFD/ND ICDS2000 system; standby horizon 4300-433; intercom PMA 7000B; CD audio system PXE 7300; additional strobe lights A650PG/R-2...	1. Limited to aircraft EC120B s/n 1049, F-GRAE only2.This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	22/08/2005	Active	10017096
EASA.R.S.01020	BRISTOW HELICOPTERS Ltd.		CAA UK RESPONSIBILITY	AS 332 L2	Installation of FLIR Ultraforce II system		Bristow Helicopters Modification MOD/ 332/25.5502Bristow Helicopters RFM Supplement 3 Revision 1 or later approved revision	Restricted to Aircraft Serial Number 2616 G-REDN only	27/07/2006	Active	10017097
EASA.R.S.01022	AERODATA AG	REV. 1		MBB-BK117 C MBB-BK117 B	- Cockpit Arrangement for ADAC BK 117 Fleet for IFR operation- Re-arrangement of Cockpit Instruments for a harmonized Cockpit Layout of several BK 117 Helicopters. Furthermore integration of a dual Garmin GNS430 equipment and GTX330 Mode S Transponder		- Master Document List MDL-A/C-092 Rev. 6 or later- BK117 Flight Manual Supplement:Rotorcraft Flight Manual Supplement “Cockpit Modification BK117Modification Number BK117-2.05”, AFM-078 Rev, 1- Instructions for continued airworthiness “Avionics Manual Supplement”, AMM-789 Rev. 1- Instal...	1 Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.1 The installation of this modificat...	10/02/2009	Active	10017098

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01023	ECMS AVIATION SYSTEMS GMBH			EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BB EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of External Load Box ELB01		-Installation Instructions ELB01_inst, issue 04.10.2005 or later approved revision-Flight Manual Supplement ELB01, issue 16.09.2005 or later EASA approved revision-Maintenance Manual ELB01_mm, issue 24.01.2006 or later approved revision	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	30/01/2006	Active	10017099
EASA.R.S.01073	AERLYPER S.A.			EC135 P2	Microwave Transmission System on EC-135 Helicopters		Documentation referred in: Doc No. 100189: Documents and Drawings List	In accordance with Doc No 100198: RFM Supplemt Ed. 3	14/02/2006	Active	10017103
EASA.R.S.01075	AERLYPER S.A.			BO105 C, BO105 S	ASTRA System installation on BO-105 C/ S Helicopters		-Documentation referred in Doc No 100130: Documents and Drawings List	In accordance with Doc No 100137: RFM Supplement Ed.4	30/01/2006	Active	10017104
EASA.R.S.01076	AERLYPER S.A.			EC135 P2	Installation of Image Recorder System UM III and Options System		Documentation referred in Doc: No 100052: Documents and Drawings List	Doc No 100059: RFM Supplement Ed. 3	08/02/2006	Active	10017105
EASA.R.S.01081	MOTORFLUG BADEN-BADEN GmbH			MD900	Installation of a Standby Altitude Indicator and a KANNAD 406 ELT in a MDHI MD900		Flight Manual Supplement Stby Altitude Gyro, MD900-01-0601 Rev:1. Flight Manual Supplement MD900 KANNAD 406 AF-H ELT MD900-01-0602 Rev:1	Installation is restricted to "VFR only"	22/06/2005	Active	10017106
EASA.R.S.01082	TENENCIA Ltd.		CAA UK RESPONSIBILITY	AS 355 F, AS 355 N	Installation of a Gyron 935 Camera mounted on the centerline of the aircraft in front of the nose		Tenencia modification report: TEN 428		05/04/2006	Active	10017107
EASA.R.S.01084	NORTHERN AVIONICS S.R.L.			AGUSTA A-109 C AGUSTA A-109 AII AGUSTA A-109 A	NAV 277 "Installation of an alternate static system on board to rotorcraft A 109 A/AII/C"		Continous Airworthiness InstructionRotorcraft Flight ManualSupplement AFM NAV 277 Rev. 0		19/01/2006	Active	10017108
EASA.R.S.01085	ROTORTECH LIMITED		CAA UK RESPONSIBILITY	EUROCOPTER FRANCE EC 155 B1	Compendium Modification. Compilation of 22 individual modifications associated with the installation of equipment and systems enabling the transfer of EC 155B1 S/N 6642 from FAA register (N84AZ) to the UK register (G-NIVA).		Rotortech Assignment Report P446/155/MO dated June 9 2005 or later approved revision.Rotortech RFM Supplement.EC155B1/01 Issue 1 WX-500 Stormscope Weather Mapping Sensor,EC155B1/02 Issue 1 UNS UL-701 Unilink Communication Management SystemEC155B1/03 Issue 1 Inflight Entertainment Power Cut-off Switc...	1. This STC is applicable to EC155B1 S/N 6642 only2. This STC is approved only for the product configuration as definedin the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	22/09/2005	Active	10017109
EASA.R.S.01087	PREMIAIR AIRCRAFT ENGINEERING		CAA UK RESPONSIBILITY	AS 365N2	Premiair Aircraft Engineering Modification 05-010.KLN 900 GPS Receiver Installation.		Premiair Aircraft Engineering Modification Summary Sheet 05-010.Premiair Aircraft Engineering AFM Supplement 05-AS365N2-01 Issue 1 dated July 01 2005 or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	10/08/2005	Active	10017110
EASA.R.S.01088	PREMIAIR AIRCRAFT ENGINEERING		CAA UK RESPONSIBILITY	AS 365N2	Premiair Aircraft Engineering Modifications 05-007 & 05-009. Modifications embodied, since manufacture, in Brazil & South Africa. Also modifications embodied to meet EASA & JAR OPS-3 requirements.		Premiair Aircraft Engineering Modifications 05-007 & 05-009. Primiair Aircraft Engineering AFM Supplments 05AS365N2-04 Issue 1. 05-AS365N2-03 Issue 1 & 05-AS365N2-02 Issue 1 or later approved revisions.	1. Aircraft Serial No. 6393 Only2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description".Compatibility with other aircraft/engine configurations shall be determined by the installer.	11/08/2005	Active	10017111

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01089	AIR AMBULANCE TECHNOLOGY GmbH			407	Mission Equipment Bell 407 – Several racks to install a camera equipment for TV productions		1. Certification Base for model 407 FAR part 27, dated October 2, 1964 Amendment 27-1 through 27-30;2. Flight Manual Supplement FMS AAT40 to Rotorcraft Flight Manual BHT-407-FM-13. AAT test report No. 092/05 (Compliance, Analysis and Test, Data Sheets, COG)4. CMM-Bell407-AAT58 (Component...	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	02/11/2005	Active	10017112
EASA.R.S.01097	NORTHERN AVIONICS S.R.L.			AGUSTA AB-412EP	Installation of an EGPWS Honeywell MK XXI.		RFMS No. RFM NAV-229	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	08/08/2005	Active	10017115
EASA.R.S.01098	POLICE AVIATION SERVICES Ltd.		CAA UK RESPONSIBILITY	BELL 412 EP	Installation of an L-3 Modular Airborne Data Recording/Acquisition System (MADRAS) combined CVR & FDR		PAS Rotorcraft Flight Manual Supplement FMS/ 465-008		03/05/2006	Active	10017116
EASA.R.S.01099	AEROSPACE DESIGN FACILITIES Ltd.		CAA UK RESPONSIBILITY	AS 355 ALL MODELS	Installation of Wescam nose mount		Aerospace Design Facilitis Modification Summary Sheet ADF 2004-001 Issue 3 dated July2 2005 or later approved revision.Aerospace Design Facilitis AFM Supploement 7 & 8, Issue 2, Dated June 2005 or later approved revision.	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer.	18/08/2005	Active	10017117
EASA.R.S.01200	ALIDAUNIA S.R.L.			AGUSTA A-109 AII AGUSTA A-109	MOD No. 010/ALI/2005 - Rotorcraft Flight Manual Supplement- New Emergency Procedures to apply in case of both generators failure.		Supplement No. FMS/ALI/ 010 Rev. 0 for Type "A" avionics configurationSupplement No. FMS/ALI/010a Rev, 0 for Type "B" and "C" avionics configuration	1. FMS/ALI/010 is applicable to A109A SN 72272. FMS/ALI/ 010a is applicable to A109All SN 7354 and SN 73843. This STC isapproved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configuratio...	15/09/2005	Active	10017119
EASA.R.S.01205	AERODATA AG			MBB-BK117 C-2 MBB-BK117 B-2, MBB-BK117 C-1 MBB-BK117 A-4, MBB-BK117 B-1 MBB-BK117 A-1, MBB-BK117 A-3	Installation of AeroPhone IRIDIUM SATCOMInstallation of satellite telephone system AeroPhone on helicopter		Master Document List MDL-A/C-093 Rev. 1 or laterInstallation and Testing Instructions REP-A/C-1258 Rev. 0 or laterFlight Manual Supplement AFM-079 Rev. 0 or laterContinued Airworthiness Instructions AMM-791 Rev. 0 or later	This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engineconfigurations shall be determined by the installer	31/08/2005	Active	10017120
EASA.R.S.01208	PREMIAIR AIRCRAFT ENGINEERING		CAA UK RESPONSIBILITY	AS 355N	IFR Upgrade with EFIS 40 Installation		1. Modification Summary Sheet & Declaration of Compliance 04-024 EFIS 40 & Single Pilot IFR Certification2. AFM Supplements 04-AS355N-3 Issue 1, 04-AS355N-4 Issue 1	1. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/ engine configurations shall be determined by the installer.	16/11/2005	Active	10017121

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01209	NSE			AS 365 N2, AS 365 N3	BAYO avionics modification no. 16/2005: installation of- two NAV/COM/GPS GNS 430 for IFR B-RNAV operations, with their associated MD 41 annunciators, A-30 ACK altitude encoders and KA 33cooling system,- a Garmin GTX 330 mode S transponder,- two Bendix-King KMA 24H-70 audio systems,- a Bendix-King KM...		Definition and installation:BAYO definition file n 16/2005-DEF, revision 0, dated December 19th, 2005, or later EASA approved revision.Operation:BAYO RFM supplement no. 16-2005-AFMS: Edition , Revision 0, dated December 19th, 2005, or later EASA approved revision.Inspection and Maintenance:Refer to...	This STC can be installed only by BAYO technical personal in accordance with BAYO STC definition file n°16/2005-DEF, revision 0, dated December 19th 2005 or later EASA approved revision	19/01/2006	Active	10017122
EASA.R.S.01210	MAP AIRCRAFT PART 21 AS			EUROCOPTER FRANCE AS 332L2	Installation of Polycon wireless communication system in AS332L2 helicopter		Polycon AS332L2 Installation Master Drawing - MAP001A101 Issue Cpolycon Communication Processing Unit Master Configuration List - 004-RLI Issue BAircraft Flight Manual Supplement - MAP001FMS Issue BService Bulletin - Polycon SB-03 Issue B	Service Bulletin Polycon SB-03 Issue B shall be implementedbefore installing this STC	04/12/2006	Active	10017123
EASA.R.S.01211	AIR ALPHA MAINTENANCE A/S		DANISH STC NO.51/2002	EC 120 B	Installation of Flying Pictures Model BSS 400 Camera Systemin accordance with Danish STC No. 51/2002		FT Engineering Drawings No.: 500-00-001 dated 1 April 2004 Version 3.FT Engineering HFM Supplement ST 51/2002 dated April 2004 as SLV approved 16 April 2004	1. This STC does not include the Videolink System with its Antenna, Antenna Actuator, Power Supply, Remote Control, andAmplifier.Concerning the transfer:CAA-Denmark confirms thatthe new STC holder, Air Alpha Maintenance A/S, has receivedall necessary data.CAA-Denmark confirms that Air Alpha Maint...	04/01/2006	Orphaned	10017124
EASA.R.S.01212	AIRTOURING LTD		CAA UK RESPONSIBILITY	A109C	Installation of Dual GNS430, GTX330 and PMA700B		Flight Manual Supplement AT_FMS_1078 Issue A		02/11/2005	Active	10017125
EASA.R.S.01214	MBH TECHNIC'S			SA 365 N S/N 6100	Installation of EMS cabin configuration, in accordance withMBH Technic's STC file n ° 01 MBHT-05, original issue dated 29/03/2005, or later EASA approved revision.		Installation:MBH Technic's STC file n° 01 MBHT-05, originalissue dated 29/03/2005, or later EASA approved revision.Instruction for continued airworthinessMBH Technic's maintenance manual supplement n° 365MBHT01052510, edition 1 dated 06/06, or later.Operation:MBH Technic's RFM supplement n° 365MB...	This STC is limited to SA 365 N s/n 6100 and can be installed only by MBH Technic's technical staff in accordance with MBH Technic's STC file n° 01 MBHT-05, original issue dated 29/03/2005, or later EASA approved revision.	27/02/2007	Active	10017126
EASA.R.S.01215	RTERESEAU DE TRANSPORT D'ELECTRICITE	REV. 1		AS 355N	New pilot/co-pilot manual quick release pyrotechnic sub-system, P/N JD3448AB00100-A0, for approved HEC devices ref: 01-STH-001 and 01-STH-002 and AAN 24527		Refer to RTE-STH technical file ref. 2005-STH-001&002, ind. 2Definition:based on PyroAlliance design file RDD 0 JD3448AB00100 01Installation, Inspection and Maintenance:in accordance with PyroAlliance document STU 0 JD3448AB00100, evolutionA, Rev 1Operation:Flight Manuals Supplements approved for de...	1. Limited to the following AS 355 N aircrafts:-S/N 5649, F-GSTH equipped with DGAC-F approved design changes ref. 01-STH-001 or 01-STH-002-S/N 5543, F-GJAX equipped with DGAC-F approved design change ref. 01-STH-001-S/N 5566, G-LINE equipped with CAA-UK approved design change ref. AAN 24527 ad. 12.r...	08/08/2006	Active	10017127

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01216	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 355 N	Integration of minor and major changes to Storm Light, 406MHz ELT, STBY Altimeter, Exhaust heat shield, Autopilot, ADI,COM/NAV, Transponder, Audiopanel, GNS 530, Compass System and Instrument Panel		-MCH/A/355/691	1. Limited to AS355N, S/N 5708 OE-XDM2. This STC is approved only for the product configuration as defined in the approved design data referred to in the paragraph "Description". Compatibility with other aircraft/engine configurations shall be determined by the installer.	13/10/2005	Active	10017128
EASA.R.S.01225	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	AGUSTA A-109 C	Design Data for Compliance with UK CAA Generic requirement 4 by Installation of a battery Low Voltage Indicator		Tatenhill Aviation Ltd Modification TAL-TAD 025/05TatenhillAviation Ltd RFM supplemetn TAL-TAD FMS 3		07/04/2006	Active	10017132
EASA.R.S.01227	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	AGUSTA A-109 AII	Approval of Low Voltage Warning Light and Associated FlightManual Supplement		Flight Manual Supplement: TAL - TAD FMS-2Major Change Design Forms: TAL - TAD 024/05, issue 1 or later approved revision	Agusta A109AII Series	31/08/2006	Active	10017133
EASA.R.S.01228	AIR SERVICE CENTER S.R.L.			A119	ASC 119-01-00 “Helibasket Kit” / Installation of External Basket		¿ Report Helibasket ASC 119-01-00 ED. 1 dated 23 June 2006Part. 1A) Description of modificationPart. 1B) DrawingsPart. 1C) Weight & Balance¿ Report Helibasket ASC 119-01-00 Part. 3 “Manuale dell’Utente” composed of:Chapter 1) ServiceBullettin Ed. 1 dated 23 June 2006Chapter 2) Maintenance Ins...	Report Helibasket ASC 119-01-00 Part.3 Chapter 4 RFM Supplement Ed.2 dated 21 August 2006	24/10/2006	Active	10017134
EASA.R.S.01231	AERLYPER S.A.			BO 105 C, BO 105 S	Digital microwave transmission system installation on boardBO-105 C/S.		Doc. No. 100388 "Master Data List", issue 3, June 2008.Doc. No. 100589 "Aircraft Flight Manual Supplement", issue 1, April 2008.Doc. No. 100590 "Continuing Airworthiness Instructions", issue 00, February 2008.	In accordance with Doc. No. 100589 "Aircraft Flight Manual Supplement", issue 1, April 2008.Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect u...	01/07/2008	Active	10017137
EASA.R.S.01237	SCANDINAVIAN AVIONICS DESIGN ApS			EUROCOPTER DEUTSCHLAND BO-105	Installation of Bendix/King Radar Altimeter System KRA 405/405B		RFM Supplement Model BO 105 series, Doc 2021602-AM-01, Issue 3, April 2006 or later EASA approved issue		21/04/2006	Active	10017138
EASA.R.S.01240	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	EUROCOPTER DEUTSCHLAND MBB-BK	Installation of Skywatch Traffic Avoidance		Phoenix Aviation Design Services Modification PADS/CP/1040Phoenix Aviation Design Services AFM Supplement PADS/ FMS/BK117/001Revision 0 or later approved revision		22/05/2006	Active	10017139
EASA.R.S.01243	ACS FRANCE			AS 355 N AS 355 F, AS 355 F1, AS 355 F2	Installation of Thales AGILE 2 external camera and associated cabin electronic control unit.		1. Definition: AIRWORK Conformity Demonstration File n°.AWF.001.05A revision A dated April 2007.2. Installation and continued airworthiness: AIRWORK Instructions for Installation and Continued Airworthiness n°. IICA-AWF-01A,edition 1 dated April 2007.3. Operation: AIRWORK Rotorcraft Flight...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	27/11/2008	Active	10017141

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01244	ACS FRANCE			AS 350 B, AS 350 BA AS 350 B3 AS 350 B1, AS 350 B2	Installation of Thales AGILE 2 external camera and associated cabin electronic control unit, in accordance with AIRWORKSTC file n°AWF.001.05 revision A, dated January 2007, or later EASA approved revision.		Installation:AIRWORK Instructions for Installation and Continued Airworthiness ref. IICA-AWF-01, edition 1 dated January 2007, or later revision.Continued Airworthiness:AIRWORK Instructions for Installation and Continued Airworthiness ref.IICA-AWF-01, edition 1 dated January 2007, or later revision...		27/02/2007	Active	10017142
EASA.R.S.01246	ING. MIROSLAV RUSINAK S.R.O.			BELL 427	Installation of the articulated patient loading system intoBell 427 rotorcraft.		06042101rRFMS dated 8 February 2007 – flight manual supplement06042401rMDS dated 31 January 2007 – Manufacturers Data Supplement06052301rMM dated 21 April 2006 – Maintenance Manual	427-706-020-101 – Bell Helicopter Textron Cabin Hardpoints Provision Kit must be installed (BHT-427-II-27 rev 0 dated 16 September 2004) prior to installation of this STC.STC EASA.IM.R.S.00548 or EASA.IM.R.S.00577 (FAA STC SR02381AT) – Installation of Passenger Sliding Doors – must be installed prio...	19/02/2007	Active	10017143
EASA.R.S.01247	HELIKOPTER AIR TRANSPORT GmbH			EC 135	Installation of Laser Scannig Equipment		EO 85-001-AFM Supplement Doc. No. 9.2-85-001, Rev. 0 or later approved revision-Instruction for continued airworthinessDoc. No. EO 85-001 chapter 16. Rev. 0 or later approved revision-Installation manual Doc. No. IM 85-001, Rev. 0 or later approved revision	Limited to SN 025, 050, 053, 072, 097, 127, 128, 160, 168, 181, 182, 187, 196, 199, 205, 210, 220, 221, 305, 308, 325, 359, 368 and387.	01/06/2006	Active	10017144
EASA.R.S.01248	AEROTEC & CONCEPT			EC 120 B	Modification des sources d'attitude, d'écart de cap et GPS du système pilote automatique PA85 SAGEM(change of sensors sources for attitudes retention, heading error select and GPSsteerings of Sagem PA85 Automatic Pilot system)		-Definition and Installation:according to AEROTEC technicalfile ref. 1106 rev.1-Inspection and Maintenance:refer to EASA.IM.R.S.1056 Rev.1 and EASA.R.C.01912 and EASA.R.C.01913 changes whose maintenance directives remain unchanged	Limited to aircraft EC120B s/n1327, F-GJIR only, when equipped with EASA.IM.R.S. 1056 Rev.1 and EASA.R.C. 01912 and EASA.R.C.01913 changes	19/01/2007	Active	10017145
EASA.R.S.01249	ELECTRONIQUE MAINTENANCE AVIATION			EUROCOPTER FRANCE AS 355N EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1 EUROCOPTER FRANCE AS 355F EUROCOPTER FRANCE AS 355E	Installation of SAFE FLIGHT Power Line Detector p/n 7101-5,in accordance with EMA STC file n° 06/001/AS355Serie/PLD revision 0, dated January 2006, or later EASA approved revision.		Installation and Continued Airworthiness:SAFE FLIGHT installation manual ref. R2925Operation:EMA RFM supplement ref. 06/001/AS355Serie/PLD revision 0, dated January 2006 or later EASA approved revision.		27/02/2007	Active	10017146
EASA.R.S.01250	AEROSPACE DESIGN FACILITIES Ltd.		CAA UK RESPONSIBILITY	AS 350 ALL MODELS	|nstallation of Wescam combined nose and side mount		Aerospace Design Facilities Ltd Flight Manual Supplement 9	Approval limited to nose mount only	01/03/2006	Active	10017147
EASA.R.S.01254	MECAER AVIATION GROUP S.p.A.	REV. 1		AB139/ AW139	SAT-COM Installation P/N 6AB1EL018-001The change consists in the installation of a Satellite Telephone Systemon passenger cabin.This STC supersedes EASA STC EASA.R.S. 01254.	The Certification Basis for the original product remains applicable tothis certificate/ approvalThe certificated noise and/ or emissions levels of the original productare unchanged and remain applicable to this certificate/ approval.	None	The change in type design applies only to those AB139 Rotorcraft previously equipped with Agusta SAT-COM provision P/N 3G2310F00411	19/06/2006	Active	10017151

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01260	AIR SERVICE CENTER S.R.L.			A119	ASC 119-02-00 External self moving mirror kit/installation of external mirror in accordance with "Certification Report"Edition 0 dated 5 February 2007 Rev. 1 dated 19 March 2007.		• User Manual, Chapter 1 "Installation Bulletin" Ed. 0 dated 05.02.2007 Rev.1 dated 19 March 2007• User Manual, Chapter 2 "Maintenance Program" Ed. 0 dated 05.02.2007• User Manual, Chapter 3 "IPC" Ed. 0 dated 05.02.2007• User Manual, Chapter 4 "Supplement RFM" Ed. 0 dated 05.02.2007 Rev....	This installation should not be incorporated in any aircraft unless it is determined that the interrelationship betweenthis installation and any previously approved configurationwill not introduce any adverse effect upon the airworthiness of the aircraft.	30/04/2007	Active	10017154
EASA.R.S.01266	CALEDONIAN AIRBORNE SYSTEMS LTD		CAA UK RESPONSIBILITY	SIKORSKY S-76	AF-ADELT improved installation on S-76		Flight Manual Supplement F014/208/001 Issue ASTC F006/208/001 definition document	STC requires minor change F012/208/001 to be incorporated.	25/01/2007	Active	10017158
EASA.R.S.01267	AVIATION SUPPORT GmbH			269D 269A, 269B, 269C, 269C-1	Installation of Clipboard/Tablet-PC rack		Flight Manual Supplement: "Ergänzung zum Flughandbuch FMS-ASE-90416"Installation Instructions: "Montageanleitung ASE-90416/6" and "Installationsanleitung ASE-90416/7"	--	30/01/2007	Active	10017159
EASA.R.S.01268	PREMIAIR AIRCRAFT ENGINEERING		CAA UK RESPONSIBILITY	AS 355 F1	Install a Honeywell KLN90B GPS		Premiair Aircraft Engineering Modification 06-014Premiair Aircraft Engineering RFM Supplement 06-AS355F1-01 Issue A or alter approved revision	--	07/07/2006	Active	10017160
EASA.R.S.01272	AEROLITE AG			EC135	Installation of EMS equipment Aerolite P/N 135570-501		Flight Manual Supplement FMS-06-004, Issue N/C dated 22.05.2006 or later EASA approvaed revisionOperaions Manual OPM-06-006Installation per Drawing List DWL-06-005	Only S/N 0041	15/06/2006	Active	10017164
EASA.R.S.01273	RTERESEAU DE TRANSPORT D'ELECTRICITE		DGAC-F TC N ° 168	AS 355 N	Personnel transport aboard hooked baskets as rotorcraft-load combinations for human external cargo (HEC).		-Definition:according to Master Drawing List DT-IMR-CNER-STH-PAMM-06-01059 ind.3, dated 12/07/07-Installation:accordingto ITM document (Instructions Techniques de Montage) GUI-IMR-CNER-STH-PAMM-07-00535 ind.1, dated 24/08/07-Inspection and Maintenance:according to Maintenance Manual NT-IMR-CNER-STH...	This STC is also applicable on AS355N when equipped with EASA.R.S.01366.	18/10/2007	Active	10017165
EASA.R.S.01274	ECT INDUSTRIES			AS 350 B3	Installation of ECT Industries DMS ARINC data recorder p/n REC-AR0-TT-OO		ECT Industries definition file n° DD-0074-XX-82, revision 03, dated 20/10/2006, or later EASA approved revision.Installation:ECT Industries installation instructions n° IM-0078-XX-82-FR, revision 00, dated 28/11/2006, or later revision.Instructions for Continued AirworthinessECT Industries maintenan...		04/04/2007	Active	10017166

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01275	AIR MACH S.R.L.			AS 350 B2	Kit Air Mach ELIRAI TV-99-Internal Rack/ Installation of electronic equipment for radio bridge		Master Drawing List MDL-INT-001 Rev. 0 Dated 26 April 2006Instruction for ContinuesAirworthiness ICA-001 Rev. 0 Dated 26 April 2006Part List Electronic Equipment PL-TV-99 Rev. 0 Dated 26 April 2006 RFM Supplement S-RFM-001 Rev. 0 Dated 26 April 2006	This installation should not be incorporated in any aircraft unless it is determined that the interrelationship betweenthis installation and any previously approved configurationwill not introduce any adverse effefct upon the airworthiness of the aircraft	10/05/2006	Active	10017167
EASA.R.S.01276	AIR MACH S.R.L.			AS 355 F1, AS 355 F2	Kit Air Mach ELIRAI TV-99-Internal Rack/ Installation of electronic equipment for radio bridge		Master Drawing List MDL-INT-001 Rev. 0 Dated 26 April 2006Instruction for ContinuesAirworthiness ICA-001 Rev. 0 Dated 26 April 2006Part List Electronic Equipment PL-TV-99 Rev. 0 Dated 26 April 2006 RFM Supplement S-RFM-001 Rev. 0 Dated 26 April 2006	This installation should not be incorporated in any aircraft unless it is determined that the interrelationship betweenthis installation and any previously approved configurationwill not introduce any adverse effefct upon the airworthiness of the aircraft	10/05/2006	Active	10017168
EASA.R.S.01277	AEROTEC & CONCEPT			EC 120 B	Improvement of "VG Fail" alarm for EASA.R.S.01017 and EASA.IM.R.S. 01056 installations		Definition and Installation:AEROTEC technical file ref. FAM2906Inspection and Maintenance:according to STCs EASA.R.S.01017 and EASA.IM.R.S.01056 directives that remain unchangedOperation:revision 1 dated 24/07/2006 of MAT Aviation's French flight manual supplement, ref STC Group2 - No EASA.R.S.0101...	Limited to aircraft EC120B S/N 1049, G-VIPR only, when equipped with EASA.R.S.01017 and EASA.IM.R.S.01056	04/08/2006	Active	10017169
EASA.R.S.01295	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	MBB-BK	Variable External Playload Configuration		MHL BK 117 C-2 RFM Supplement No. 2 (Wescam MX-15)MHL BK 117 C-2 RFM Supplement No. 3 (NAT Skyshout)	Refer to above RFM Supplements	16/03/2007	Active	10017177
EASA.R.S.01303	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	EUROCOPTER FRANCE AS 365N1	Installation for KLN90B GPS, UNS-1K Flight Management System, Devore Recognition Light System and Whelen Strobe.		Phoenix Aviaion Design Services Ltd. Change PADS/CP/1065.Master Document List PADS/MDL/ 1065/001 Rev. B.Flight Manual Supplements PADS/FMS/SA365/001, PADS/FMS/SA365/002, PADS/FMS/SA365/003.	AS365 NI, S/N 6309.	27/08/2007	Active	10017180
EASA.R.S.01304	ALIDAUNIA S.R.L.			A109 E	Installation of a Ginevri Incubator Type "Baby Shuttle Intensive Care" P/N 7634B complete of the attachment fittings		Alidaunia Flight Manual Supplement No. FMS/ALI/ 07Alidaunia Modification Bulletin No. 07/ALI/2005	Agusta A109E equipped with Agusta Kit EMS P/N 109-0326-69-103.	14/08/2006	Active	10017181
EASA.R.S.01306	HELI-ONE (NORWAY) AS			SA 366 G1 SA 365 N/N1 AS 365 N2/N3	Installation of Penny & Giles D51615 MPFR CVFDR.		- Definition:Heli-One Master Drawing ref. AHSE-53500 revision A, dated 13 January2007, or later EASA approved revision.- Installation:Engineering Order ref. EOM-3130-26597, Revision A dated 21/08/06, orlater revision.- Instructions for continued airworthiness Maintenance requirementsreport ref. AHSE...	This STC is approved only for the product configuration as defined inthe approved design data referred to in the paragraphs "Description" and"Associated Technical Documentation".Compatibility with other aircraft/engine configurations shallbedetermined by the installer.This certificate shall remainr...	09/03/2007	Active	10043033

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01315	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			EUROCOPTER FRANCE AS 355F1	Installation of rack and sending/reception antennae.		H-25-02-06-LIVE TOOLS Annex 2 dated May 2008 or later approved revision – Dossier Vol de ControleH-25-02-06-LIVE TOOLS Annex 3 Edition 0 dated 21 May 2008 or later approved revision – Supplement Manuel de VolH-25-02-06-LIVE TOOLS Annex 4 date May 2008 or later approved revision – Plans de Definition...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.VNE limited to 120 kts Do not deploy ante...	12/06/2008	Active	10017182
EASA.R.S.01318	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	AS 355 F1	Introduction of Skylark 2 Radar.		Modification - S21.25-10-1115.Maintenance Manual - S21.TEC-0104.AFM Supplement - S21.FMS-0024.		01/02/2007	Active	10017185
EASA.R.S.01321	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	SIKORSKY S-61N	Rescue Hoist Fatigue Life Extension		STC Twenty One Modification S21.53-88-1006STC Twenty One Maintenance Programme (Instructions for Continued Airworthiness) S21.TEC-0073	--	14/12/2006	Active	10017186
EASA.R.S.01325	SCANDINAVIAN AVIONICS DESIGN ApS			EUROCOPTER FRANCE EC 120 B	VHF COMM, XPDR, ICS, Directional Gyro and Attitude Indicator.		1. Installation instructions:- Technical Order for installation 2029510-TO-01 Iss. 2, dated 27/03/2006.2. Instructions for continued Airworthiness:- Continued Airworthiness 2029510-CA-01 Iss. Dated 30/09/2005.	1. The installation of this STC is not approved for Night VFR approved aircraft.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect uponi...	09/10/2007	Active	10017188
EASA.R.S.01326	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	EUROCOPTER DEUTSCHLAND BK117 C	Installation of Honeywell AR30 Cockpit Voice Recorder		Phoenix Aviation Design Services Modification PADS/CP/1067Phoenix Aviation Design Services AFM Supplement PADS/FMS/BK117/002 Revision B	--	11/01/2007	Active	10017189
EASA.R.S.01327	ACS FRANCE			AS 350 B, AS 350 B1 AS 350 B3 AS 350 B2, AS 350 BA	Nouveau système de prises de vues frontales (Front Mounted Camera Installation).		DDC AWF 002.06Flight Manual Supplement AFMS-AWF-01		16/06/2008	Active	10017190
EASA.R.S.01328	ACS FRANCE			AS 355 F2, AS 255 N, AS 355 NP AS 355 E, AS 355 F, AS 355 F1	Nouveau System de Prises de Vues Frontales(Front Mounted Camera Installation)		DDC.AWF.002.06Flight Manual Supplement AFMS – AWF – 02 dated June 2008 or later EASA approved revision	This STC is not approved for Category A operations.	16/06/2008	Active	10017191
EASA.R.S.01329	BUCHER LEICHTBAU AG	REV. 1		EC135 P1, T1, P2, T2, P2+, T2+	EMS-Equipment ARA-EC135-AC66Minor change to STC EASA.R.S.01329 to incorporate:- new mattress for the stretcher- dead end stop for the stretcher installation- additionnal stud to the center cabinet- medical equipment retainers.	JAR-27	-Master Document List E034-01-06, Rev. G-Rotorcraft Flight Manual Supplement FMS -AC6, Rev. C-Operational and Maintenance Manual E014-01-06 Rev. 2	None	24/07/2009	Active	10017192
EASA.R.S.01330	AEROTEC & CONCEPT			SA 365 N	AEROTEC avionics modification n° 6306: installation of:two NAV/COM/GPS GARMIN GNS 430 for IFR B-RNAV "En route" operations, with their associated GARMIN GA 56 GPS antenna,two MID CONTINENT MD 41 Annunciation Control Units,an ALLIED SIGNAL KA 33 cooling blower,a GARMIN GAD 42 RMI adaptor,in accordanc...		Installation:AEROTEC STC Implementation File n °6306, revision 1 dated 26/10/06, or later revision.Operation:AEROTEC Flight Manual Supplement n°6306-AFMS, edition 1 revision 0, dated January 29th 2007 or later approved revision.Inspection and maintenance:Refer to individual equipment Manuals.	This STC is limited to SA 365 N s/n 6218 and can be installed only by AERTOTEC technical staff in accordance with AEROTEC STC Implementation File n°6306, revision 1 dated 26/10/06, or later revision.AEROTEC minor modification n°6206, approved under EASA.R.C.01981, has to be installed as a provision...	12/02/2007	Active	10017193

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01333	S.A.M. - S.R.L - SOCIETA AEREA MERIDIONALE			EUROCOPTER FRANCE AS 355F2 EUROCOPTER FRANCE AS 355F1	SAM/002/2005: Archimede System "Digital acquisition and transmission of visible and infrared images"		Flight Manual Supplement No. FMS/ SAM-335/002_355		09/11/2006	Active	10017195
EASA.R.S.01334	S.A.M. - S.R.L - SOCIETA AEREA MERIDIONALE			EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	SAM/002/2005: Archimede System "Digital acquisition and transmission of visible and infrared images"		Flight Manual Supplement No. FMS/SAM/002_350		09/11/2006	Active	10017196
EASA.R.S.01335	AVIATION SUPPORT GmbH			MD900	Installation of swiveling speaker system MD900 (ALS-ausfahrbaresLautsprecher-System MD 900)	JAR 27	- EASA approved Flight Manual Supplement FMS-ASE-90304, Rev. -- Maintenance Manual Supplement MMS-ASE-90304, Rev. -,- Master Document List MDL-ASE-90304, Rev. -,	none	23/06/2009	Active	10033427
EASA.R.S.01338	AERLYPER S.A.	REV. 1		EC-135-P2 (CPDS) EC-135-P2+	UM-III HD Camera System & Microwave Transmission System Installation Onboard EC135.		¿ Master Data List Aerlyper DOC No. 100961 Ed. 03;¿ Supplement to Rotorcraft Flight Manual (RFM) Aerlyper Doc No. 100973 Ed. 01; ¿ Instructions for Continuous Airworthiness Aerlyper Doc No. 100974 Ed. 01.	1. Master Data List and RFM Supplement mentioned above.	13/05/2008	Active	10017197
EASA.R.S.01347	HELI-ONE (NORWAY) AS			SIKORSKY S-61N	AHSE-53880 Breeze 29700 Stand by Rescue hoist installation.		- RFMS AHS-077 dated 26.06.2008 or later approved revision.- Master Drawing AHSE 53880 28.08.2008 or later approved revision.- Continued Airworthiness Supplement AHSE-53888 Rev A dated 20.06.2008or later approved revision.	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modificationwill introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	24/09/2008	Active	10043037
EASA.R.S.01348	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T2	Installation of Honeywell Avionics MKXXII EGPWS		Design Report MCH/A/ 135/986 Rev BAFM Supplement No.34 to EC135T2 AFM Rev B	As defined in the AFM Supplement No. 34	03/04/2007	Active	10017199
EASA.R.S.01350	ECMS AVIATION SYSTEMS GMBH	REV. 1	EASA STC 1025	EUROCOPTER DEUTSCHLAND BK117 C	“External Abseil Device EAD01”Provides attachment provisions on rotorcraft for fast roping / rappelling and Human External Cargo operations.This STC is a revision of the previous EASA STC No. 1025, dated 24.11.2003The Technical Changes areas follows:- the system is extendable, not fixed- the...		• Flight Manual Supplement for Fixed External Abseil Device on EC145 (BK 117 C-2), Revision 2. dated 01.01.2007.•Maintenance Manual/User Guide EAD01_MM, Revision 1 dated 01.01.2007.	1. The scope of this STC is limited to attachment provisions for rappelling / fast roping and HEC operations. It does not include all the necessary equipment like ropes and personal carrying device. It does not establish all the procedures necessary for safe operation. It does not constitute an a...	30/01/2007	Active	10017201
EASA.R.S.01352	B/E AEROSPACE FISCHER GMBH			427	Installation of floor mounted F+E Medical Seats 230/305 into Bell 427 cabin by use of installation racks attached to forward and aft cabin bulkhead fittings		Flight Manual Supplement D0704-021 revision - dated 17 July2007 or later approved revisionMaintenance Manual Supplement D0704 - 020 revision 0 dated 30 March 2007 or later approved revisionInstallation Instructions are contained in the Maintenance Manual SupplementList of Compliance Documents D0704...		20/07/2007	Active	10017203
EASA.R.S.01353	POLICE AVIATION SERVICES Ltd.		CAA UK RESPONSIBILITY	MD HELICOPTERS MD902	MTWA Increase with PAS External Stores and Surveillance Equipment		FMS/496-002.	Only those in the above F/M Supplement.	03/04/2007	Active	10017204

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01357	FRANCE AVIATION			EUROCOPTER DEUTSCHLAND EC-135	Installation of Avidyne Adivsory System TAS-620.		Definition and Installation:- France Aviation Master Data List ref. FA 03/2007, revision 1, dated 23/03/2007, or later approved revision.- Avidyne TAS-620 Installation manual p/n 32-2351Operation:Flight Manual Supplement ref. AFM-003-2007-001 revision 2, dated 26/11/2007 or later EASA approved revisi...	Installation limited to EC 135 T2 s/n 274.	30/11/2007	Active	10017205
EASA.R.S.01358	BRISTOW HELICOPTERS Ltd.		CAA UK RESPONSIBILITY	S-92A	Installation of Additional Cargo Compartment Baggage Shelf.		• FMS No 1, Initial Issue dated 19 July or later approved revision.• Maintenance Manual Addendum for Mod/ S92/25.5643, Initial Issue dated 19 May 2007 or later approved revision.• Maintenance Manual Supplement for Mod/ S92/25.5638, Initial Issue dated 19 July 2007 or later approved revision....	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	20/07/2007	Active	10017206
EASA.R.S.01359	TENENCIA Ltd.		CAA UK RESPONSIBILITY	EUROCOPTER FRANCE AS 350 SERIE	Gyron 935 camera installation on the AS 350 series a/c.		Installation according to report n. TEN 428Flight Manual Supplement TEN/ EUROCOPTERAS350/FM/ SUPP/001Maintenance Manual Supplement TEN/ EUROCOPTER/MM/SUPP/ 001		06/03/2007	Active	10017207
EASA.R.S.01360	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	AGUSTA A-109 AII	Approval of replacement “TOT” gauges		¿ Master Document List MDL.01007, Rev A, dated 02.03.2009¿ Flight Manual Supplement FMS 01007, Revision A, dated 07.08.2008	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	06/03/2009	Active	10017208
EASA.R.S.01361	AEROLITE AG			AB139, AW139	P/N 139086-501.The equipment contains a specific cabin floor layer, 2 medical seats installed in the aft part of the cabin, one or 2 stretchers, amedical supply cabinet and various stowage compartments.		1. Flight Manual Supplement: FMS-07-0062. ICA and Operations manual: OPM-07-006.	1. When oxygen is installed No smoking permitted.2. The occupant of the LH FWD Aft facing seat must wear a helmet. 3. When the secondary stretcher is occupied the head protection pad must be installed between the stretchers.4. Following equipment must be installed:- Agusta EMS electric...	21/11/2007	Active	10017209
EASA.R.S.01366	RTERESEAU DE TRANSPORT D'ELECTRICITE		DGAC FRANCE STC FAM 98STH0595	AS 355 N	Helicopter equipped with ARRIUS 1A modified namedARRIUS 1E.DGAC-F approved design change 98STH0595 relates toinstallation of two modified ARRIUS 1A engines on the AS355N helicopter. This installation allows increased engine performance required to perform maintenance on high voltage overhead lines o...		• Manuel d’installation ARRIUS 1E : X319 HS 0011• Supplement au manuel de vol: DT-ETUD-CNER-STH-PAMM-07-00315 revI.• Additif au Manuel d’entretien Turbomoteur GBF 124• Original DGAC approval FAM 98 5TH 0595	• Engine operating limitations as defined in the “Installation Manual” reference X319 HS 0011.• Engine maintenance requirements defined in Manuel d’entretien Turbomoteur GBF124.	23/03/2007	Surrendered	10017210
EASA.R.S.01367	BUCHER LEICHTBAU AG			EUROCOPTER DEUTSCHLAND EC-135-	EMS Instalaltion ARA-EC135-AC61This change introduces the following new items not included in FOCA STC FOCA 25-20-108:alternative side cabinet LH (p/ n 1359270)new center cabinet (p/n 1359701)alternative seat installation (p/n 1353040).		Flight Manual Supplement: FMS-AC61.Master Document List MDOC-AC6,1 Revision DOperation and Maintenance Manual: E014-04-04	Smoking is not permitted in the rotorcraft cabin.	29/05/2007	Active	10017211

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01368	STC TWENTY ONE LIMITED		CAA UK RESPONSIBILITY	R44 II R44	Installation of removable crop spraying equipment onto Robinson R 44 & R 44 II helicopters		- STC Twenty One Limited Rotorcraft Flight Manual Supplement S 21.FMS-0029 dtd. 27 July 2007 or later approved revisions- STC Twenty One Limited Major Change Design Change S21.25-74-1172- STC Twenty One Limited Master Document List S21.MDL-0325- STC Twenty One Limited Supplement Manual...	1. Certified in Restricted Category2. All limitation of RFM supplement apply3. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon t...	01/08/2007	Active	10017212
EASA.R.S.01371	AEROLITE AG			EC635 T1, EC635 P2+, EC635 T2+ EC135 P2+, EC135 T2+	Armasuisse1 LH Stretcher Installation. P/N 135586-501.		• Flight Manual Supplement FMS-07-002.• Operational manual OPM-07-003.• Installation Manual IM-07-001.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	03/07/2007	Active	10017214
EASA.R.S.01372	AEROLITE AG			EC635 T1, EC635 P2+, EC635 T2+ EC135 P2+, EC135 T2+	Armasuisse 2 RH Stretcher Installation P/N 135587-501.		• Flight Manual Supplement FMS-07-003.• Operational Manual OPM-07-004.• Installation Manual IM-07-002.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	03/07/2007	Active	10017215
EASA.R.S.01373	AEROLITE AG			EUROCOPTER DEUTSCHLAND EC-635 EC135 AND EC635	Life Support Module installation:P/N 135588-501. The installation consists of a stowage provision for up to three oxygen bottles. The is module installed in the forward part of the passenger cabine.		Flight manual supplement: FMS-07-004Instruction for continued airworthiness and operations manual: OPM-07-005.		31/10/2007	Active	10017216
EASA.R.S.01375	BOGGI S.R.L.			AS 365 N3	KIT MDS365-P001-00, Additional seat fitting for Eurocopter AS365N3 Helicopter in Hems configuration.		Boggi S.R.L. Master Drawing List and Master Parts List, KitP/N MDS365-P-001-00 Technical Report Part 1B, issue 1, dtd. 18-10-2007.Installation in accordance with Boggi S.R.L. Installation Service Bullertin Kit P/N MDS365-P-001-00 Technical Report Part 3, chapter 1, issue 1, dtd. 18-10-2007.Instruct...	Limited to AS 365N3 S/N 6609 and 6356, previously modifiedby the kit Bucher P/N ARA-AS365N2-AC50.	04/12/2007	Active	10017218
EASA.R.S.01376	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 365 N3	Re-Instatement of approval for Category A Operations reference FAR 29 Amendment 16		EASA STC 2005-988. UKCAA AAN28812.McAlpine Helicopters Change Reference MCH/A/365/726McAlpine Helicopters Project 0223 AS365N3 Serial Number 6646.McAlpine Helicopters RFM Supplement No.6 Honeywell CDS-R Cockpit Display System		13/04/2007	Active	10017219
EASA.R.S.01377	TATENHILL AVIATION Ltd.		CAA UK RESPONSIBILITY	AGUSTA A-109	Dessign data compliance with Generic Requirement No. 4.		Tatenhill Aviation Master Document List TAL-TAD 015/07.Tatenhill Aviation AFM Supplement TAL-TAD FMS 18 Revision A.	As per AFM Supplement TAL-TAD FMS 18 Revision A.	26/07/2007	Active	10017220

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01381	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			MBB-BK 117 B-2	Avionics Retrofit.Out: ADF System King KDF-806; Dual VHF-COM System Becker AR-3202;VHF-NAV System King KNS-81; VHF-NAV System Becker NR-3300-2.In: Dual VHF-COM/NAV System King KX-165; Marker System King KR-21; ADFSystem King KR-87; Transponder Mode S King KT-73 relocation andAutopilot Control Panel...		- Master Data List MDL Doc. No. 662-049.- Rotorcraft FlightManual Supplement Doc. 662-071 Rev. IR or laterapproved revisions.	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product. The installation of this modificationby third persons is s...	12/11/2007	Active	10043036
EASA.R.S.01393	AIR AMBULANCE TECHNOLOGY GmbH			AS 332 L2	VIP interior, quick conversion P/N 332-25-24-3000-901.		• Definition: Drawings list ref. 332-25-24-3000-901 dated 02/08/2007 as appended in report n °101/07 or later approved revision.• Installation and Maintenance: document CMM-AS332-AAT62, rev.0 dated August 2007 or later revision.• Operation: flight manual supplement FMS AAT 45, rev.0 dated Au...	1. STC applicable only on individual AS332L2 aircraft equipped with approved VIP salon consisting of Eurocopter furniture:Forward Lounge: 4 face-to-face VIP seats with 2 VIP tables in the middle based on Eurocopter Dwg 332V851329.Rear Lounge: 8 comfort seats and 1 purser seat and utilities cabine...	17/08/2007	Active	10017225
EASA.R.S.01397	PREMIAIR AIRCRAFT ENGINEERING		CAA UK RESPONSIBILITY	S-76B	Traffic Advisory System Installation.		Premiar Aircraft Engineering Limited Modification 07-019Premiar Aircraft Engineering Limited Rotorcraft Flight Manual Supplement Nr: 07-S76B-04 Issue 1.		26/05/2008	Active	10017227
EASA.R.S.01400	AEROLITE AG			MBB-BK 117-C2	EMS Stretcher Installation Police Thüringen (Aerolite P/N 145285-501).		Flight Manual Supplement FMS-07-009, Rev. N/C, dated 1 September 2008.Operational Manual OPM-07-011		12/11/2008	Active	10017229
EASA.R.S.01411	PREMIAIR AIRCRAFT ENGINEERING		CAA UK RESPONSIBILITY	AS 355 N	Installation of a Honeywell KMD850 Multifunction Display replacing the existing IN812A Radar Indicator plus GC360 RadarGraphics Computer and Interfacing with an existing Honeywell RDR2000.		Engineering Modification 07-022.FMS : 07-AS355N-01.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	05/11/2007	Active	10017233
EASA.R.S.01412	SCANDINAVIAN AVIONICS DESIGN ApS			EUROCOPTER FRANCE EC 120 B	Installation of Avionics System Garmin GNS 480 / HoneywellKY-96A / Garmin GTX 33 as defined in Engineering Order 2042580-EO .		- Definition and Installation in accordance with:-Scandinavian Avionics Design Engineering Order 2042580 - EO, issue 1, dated 25 .01.2008.- Inspection and Maintenance in accordance with:- Scandinavian Avionics Design Instruction forContinued Airworthiness 2042580-CA, issue 1, dated 08.11.2...		19/03/2008	Active	10017234
EASA.R.S.01413	SCANDINAVIAN AVIONICS DESIGN ApS			EUROCOPTER FRANCE EC 120 B	Installation of several avionics system as definened into Engineering.Order No. 2042316 – EO issue 2		¿ Scandinavian Avionics Design GmbH Engineering Order No. 2042316 – EO issue 2 .¿ Scandinavian Avionics Design GmbH Drawing List No. 2042316 – DL issue 1 dated 01.02.2008. ¿ Scandinavian Avionics Design GmbH RFM Supplement ref. 2042316 - AM issue 1. dated 20.10.2007 ¿ Scandinavian Avio...	This change is limited to Rotorcraft equipped with Garmin GNS 480 Installation.	04/04/2008	Active	10017235

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01423	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			EUROCOPTER FRANCE AS 350	Modification H-25-04-07-SFP - installation of deployable antenna mounted on landing gear.		Definition, installation, and inspection & maintenance:INSTALLATION SUR HELICOPTERE ECUREUIL AS350D'UNE ANTENNE DE RETRANSMISSION D'IMAGESMODIFICATION H-25-04-07-SFP: ¿ Dossier de Modification - Janvier 2008¿ Annexe 1 - Dossier Justificatif - Janvier 2008¿ Annexe 2 - Plans de Definition et P...	This STC provides approval for the installation and deployment of the antenna. A separate approval is required for the installationand operation of any equipment transmitting through the antenna.The installation of this modification by third persons is subject to written permission of the approv...	25/09/2008	Active	10017237
EASA.R.S.01424	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			EUROCOPTER FRANCE AS 355 SERIE	Modification H-25-04-07-SFP - installation of deployable antenna mounted on landing gear.		Definition, installation, and inspection & maintenance:INSTALLATION SUR HELICOPTERE ECUREUIL AS355D'UNE ANTENNE DE RETRANSMISSION D'IMAGESMODIFICATION H-25-04-07-SFP: ¿ Dossier de Modification - Janvier 2008¿ Annexe 1 - Dossier Justificatif - Janvier 2008¿ Annexe 2 - Plans de Definition et P...	This STC provides approval for the installation and deployment of the antenna. A separate approval is required for the installationand operation of any equipment transmitting through the antenna.Prior to installation of this modification the installer must determine that the interrelationship be...	25/09/2008	Active	10017238
EASA.R.S.01425	KUERZI AVIATION AG			EUROCOPTER FRANCE SA 315B	NVIS Conversion.Includes Rad. Altimeter and Mode S ELS Transponder installation.		Master Document List MDL-200717179 Rev. B or later approvedrevision.Flight Manual Supplement FMS-200717179 Rev. B or later approved revisions.	Reg.: HB-XII S/N: 2551Mode S Transponder system alleviationof flight status according JAA TGL-13 note 10 granted.	06/08/2008	Active	10017239
EASA.R.S.01436	ALIDAUNIA S.R.L.			MBB-BK 117 C-1	MB 018/ALI/2008 "Installation of GPS/ Satellite System usable to locate the helicopter position.		FM Supplement No. FMS/ ALI/018 dated 4 January 2008.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	18/07/2008	Active	10017242
EASA.R.S.01441	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			A 109 K2	Replacement Euronav III by Euronav V (Euroavionics)By removing- the existing RN 5 Euronav III Map Generatorand installing- a new RN 6 Euronav V Digital Map Generator		- Master Data List, Doc. No. 725-049, Rev. IR or latest approved revision- RFMS, Doc. No. 725-071, Rev. IR or latest approved revision	Prerequisite conditions:- Dual GNS-530A installation- RN 5 Euronav III Map Generator installed with interface to the GNS-530A 2- CLN.14-3.0 Control Unit installed- DYNT64-2.0 Display installed	28/04/2008	Active	10017244
EASA.R.S.01442	PHOENIX AEROSPACE LIMITED		CAA UK RESPONSIBILITY	BK117	Installation of Power Line Detector System.		Master Document List PADS/MDL/1112/001RFM Supplement PADS/FMS/ BK117/003.	Eurocopter Deutschland BK117 Series.RFM Supplement PADS/ FMS/BK117/003	05/03/2008	Active	10017245
EASA.R.S.01443	AVIONES, PIEZAS Y ACCESORIOS, S.L.			AS 355 ALL MODELS	HD I. Ponti Radio Digital video, audio & data Transmission System.		0108002 revision 0 or later approved revision – Master Document List;0108002 revision 0 or later approved revision – Design Configuration;SFM 0108002 Revision 0 or later approved revision – Flight Manual Supplement;ICA 0108002 Revision 0 or later approved revision – Instructions for Continued Airwor...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	08/09/2008	Active	10017246

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01445	GAMA ENGINEERING Ltd.		CAA UK RESPONSIBILITY	BELL 412	Installation of a dual electronic horizontal situation indicator (EHSI) system.		RFMS879001 Issue 1 dated 19 May 2008 or later approved revision – Rotorcraft Flight Manual Supplement;HL/MOD/900 Issue 1 or later approved revision – Modification Statement;ICA879001 Issue 1 or later approved revision – Instructions for Continued Airworthiness.	1. The EHSI system must have a minimum software level ofEight (8) installed in the symbol generators.2. The YELLOW symbol generator “SG” flag or display unit “DU” flag mustnot be visible prior to departure.3. Autopilot coupled ADF tracking is not approved4. Autopilot operation in HDG,I...	22/05/2008	Active	10017247
EASA.R.S.01448	AEROLITE AG			AB139, AW139	EMS Multi-Mission KitInstallation of the EMS Multimission Kit Aerolite-P/N 139124-501 into cabin of AgustaWestland rotorcraft model AB/AW 139.The Kit covers EMS equipment (ref. Aerolite-P/N 139086-501) certified per EASA.R.S. 01361 adding anew so-called Multimission Floor and its related utility sea...		(R)FMS-08-003 Rev N/C, dated February 28th, 2008OPM-08-003 Rev. N/C, dated January 23rd, 2008	Rotorcraft Operational Limitations: (ref. (R) FMS-08-003 RevN/C)-When oxygen is installed no smoking permitted-When equipment rack is installed occupant of LH FWD aft-facing seat must wear a helmet-When secondary stretcher is occupied headprotection pad must be installed	04/04/2008	Active	10017249
EASA.R.S.01449	SCANDINAVIAN AVIONICS DESIGN ApS			EUROCOPTER FRANCE AS 365N3 EUROCOPTER FRANCE AS 365N2 EUROCOPTER FRANCE AS 365N1 EUROCOPTER FRANCE AS 365N					25/06/2009	Active	10031822
EASA.R.S.01451	ECMS AVIATION SYSTEMS GMBH			EUROCOPTER FRANCE SA 365C2 EUROCOPTER FRANCE EC 155 B1 EUROCOPTER FRANCE EC 155B EUROCOPTER FRANCE AS 365N3	External Load Attachment Device EDX02.		Flight Manual Supplement EDX02_FMS-EASA, Original Issue, 01.05.2005installation Instructions EDX02_INST_EASA;Maintenance Manual & user Guide EDX02_MM_UG_EASA.	The scope of this STC is limited to technical provisions tothe helicopter. It does not include ropes and personal equipment, training aspects and operation procedures necessary for the fast roping operation. These procedures must be established by the operator and approved by national authorities....	18/07/2008	Active	10017250
EASA.R.S.01456	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 365 N3	Installation of NAT 611-014 Voice Warning Generator (AVAD).		- Eurocopter UK. Change Number: MHL/365/1110, Installation of NAT 611-014 Voice Generator (AVAD)- Eurocopter UK. Design Report Number: DR/ 3651110-001 issue A, dated February14th.2008.- Eurocopter UK FMS AS365N3 Number 30,dated February 14th.2008.- Instructions for Continued Airworthines...		22/04/2008	Active	10017253
EASA.R.S.01457	AIR AMBULANCE TECHNOLOGY GmbH			W-3AS	Installation of Air Ambulance Equipment "quick conversion P/N W-3A-25-20-33.000.		Flight Manual Supplement AAT 47, Revision 0, dated March 2008Component-, installation-, Operation-Manual, CMM-PZL W-3A-AAT66, Revision 0, dated March 2008.		17/04/2008	Active	10017254
EASA.R.S.01463	AIRBUS HELICOPTERS UK LIMITED	REV. 1	CAA UK RESPONSIBILITY	EC135 T2+	Installation of FreeFlight 2101 I/O Approach Plus GPS with navigation information interfaced to the aircraft FCDS and the aircraft AFCS for coupled autopilot operations, iaw Drawing No. A3/1351114-100.		¿ Flight Manual Supplement FMS "EC UK EC135T2+ FMS No. 36" Issue 1¿ Installation Instructions, Instructions for Continued Airworthiness: Maintenance Requirements Document MR/ 1351114-001 Issue A,dated 18 March 2008 or later revisions.¿ Master Drawing No. A3/1351114-100 Issue A, Maintenance R...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	11/12/2008	Active	10017256

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01464	AERODATA AG			EC135 T2, EC135 T2+	Airborne observation Platform (AOP) Integration in EC135. Installation of a Star Safire HD FLIR on the right skid and an operator station in the passenger compartment based on Aerodata change no. EC135-3.02 iaw MDL-A/C-132 Rev. 1 or later approved revisions.		Flight Manual Supplement AFM-096, Rev. 1.Maintenance ManualSupplement AMM-956, Rev. 0.Installation Instruction HB-A/C-957, Rev. 1.	None.	29/08/2008	Active	10017257
EASA.R.S.01469	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T2+	Installation of honeywell EGPWS Mk XXII. Installation of Honeywell EGPWS XXII iaw drwg. no. A3/1351134-100 with aural and display based on ECUK modification MHL/135/1134.		Flight Manual Supplement FMS Nr. 40 "Honeywell Mk XXII EGPWS", issue 1.Maintenance Requirements Doucument MR/1351134-001, issue C, dated 14-07-2008 or later approved revision.Master Drawing no. A3-1351134-100, latest revision.	ECUK modifcation MCH/A/135/1075 must be installed as prerequisite.	01/09/2008	Active	10017260
EASA.R.S.01471	KUERZI AVIATION AG			BELL 206B	Radar altimeter installation including adapter plate.		• FMS-200718268 original issue dated 17 December 2008 orlater EASA approved revision – Flight Manual Supplement;• ICA-200718268 revision N/C dated 28 November 2008 or laterEASA approved revision – Instructions for Continued Airworthiness;• MDL-200718268 revision N/C dated 1 December 2008...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	18/12/2008	Active	10017262
EASA.R.S.01474	AEROLITE AG	REV. 1		AB139, AW139	EMS Provisions Kit. Revision of STC for incorporation of PAX seat configurations Aerolite P/N 139117-505; 139117-506 and 139117-507of 12, 14 and 15 PAX seats		FMS-08-002 Revision AMDL-08-005 Revision AOPM-08-002 Revision A	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.The installation of this modification by third persons i...	30/03/2009	Active	10017263
EASA.R.S.01475	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T2+, EC135 P2+	Installation of STAR SAFIRE HD FLIR (based on EC UK modification MHL/135/1116)..		• Flight Manual Supplement:o EC UK EC135T2+ EC135P2+ FMS No. 44 Issue 1o If in addition the Retractable Digital Microwave Downlink Antenna, i.a.w. Eurocopter UK Ltd Change No. MCH/A/135/791 is installed:EC UK EC135T2+ EC135P2+ FMSNo. 42 Issue 1• Installation Instructions, Instructions f...	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	14/11/2008	Active	10017264
EASA.R.S.01481	AEROLITE AG			EC135	EC135 EMS Equipment.Update of (R) FMS-401 for EMS equipment P/N 135545-501 with validation for all EC135 models up to S/N 0337.Introduction of new EMS equipment variant P/N 135545-502 with new (R)FMS-08-006 and OPM-08-006 valid for all EC135 models from S/N 0337 on.		(R)FMS-401 Rev.B or later (R)FMS-08-006 Rev.A or laterOPM-08-006 Rev. A or laterMDL-401 Rev.B or later	Helicopter shall be operated as per limititations section of FMS.Placards as per limitations section of FMS shall be installed.No smoking permitted when Oxygen is installed.Prior to installation of this modification the installer must determine that the interrelationship between this modification an...	24/06/2008	Active	10017266
EASA.R.S.01488	AVIONICS INTEGRATION & ENGINEERINGCORPORATION AG (AIEC)			EC-135-T2	COM/NAV/ATC Avionics System Installation.		AIEC Master Data List ED743-049, Rev. B or later approved Revision.	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	04/02/2009	Active	10017268

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01489	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 355 NP	Installation of a Leo II FLIR System		Flight Manual Supplement No 18 – Leo II FLIR System – issue1 or later EASA approved revision;Maintenance Manual Supplement MMS/ 3551127-001 issue A dated 5 June 2008 or later EASAaccepted revision;Top Level Installation Drawing A3/3551127-100	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness ofthe product.1 The installation of this modification b...	13/01/2009	Active	10017269
EASA.R.S.01490	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 355 NP	Installation of SFIM 85T31 3 Axis Autopilot System		Flight Manual Supplement No 29 – SFIM 85T31 (3 Axis) Autopilot VFR – Issue 1 or later EASA approved revision;Maintenance Requirements Document MR/3651130-001 issue 1 or later EASAapproved revision;A3/3551130-100 – GA of 3 Axis Autopilot System – Issue A	0 Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.0 The installation of this modificat...	14/01/2009	Active	10017270
EASA.R.S.01491	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	AS 355 NP	Installation of an alternate Pitot System		Eurocopter UK Ltd. AS355NP Flight Manual Supplement No.28 dated 3 November 2008 or later EASA approved revision.Eurocopter UK Ltd. AS355NP drawing A3/3551133-100-1 – GA of Alternate Pitot Sysem – Issue AEurocopter UK Ltd. AS355NP report MR/ 3551133-001 issue B dated 22 October 2008 or later EASA appr...	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third personsa...	11/12/2008	Active	10017271
EASA.R.S.01493	AIR ALPHA MAINTENANCE A/S			EC-135	GARMIN 530 COM/NAV/GPS Installation: Optional installation of a GARMINGNS530 unit to an existing GNS430 unit and replacing Bendix/King KY196BVHF COM unit. The installation isin accordance with EO-EC135-34-131 Rev. 0 or later approved revision.		- EC135 Flight Manual Supplements: EC135 Flight Manual Supplement,FMS.EU-EC135-34-131 Rev. 4, dated 06.05.2009, or later approved revision- Technical Instructions: Installation and Maintenance Manual, SMMATP34.0120, Rev. 0	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modification will introduce no adverse effectupon the airworthiness of the product.2. The installation of this modification by third person...	08/06/2008	Orphaned	10043035
EASA.R.S.01506	AEROLITE AG			MBB-BK 117-C2	Installation of EMS equipment P/N 145268-501 including: 3 medical seats, a primary patient system, medical supply unit,bottle rack, medical stowage cabinet, EMS electrical installation, medical equipment retainers, tie down web and stretcher stowage provisions.		1. Flight manual supplement FMS-08-007 issued 1st September2008 or later approved version.2. OPM-08-008 dated 8 September 2008 or later approved version.	Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third persons...	14/10/2008	Active	10017274
EASA.R.S.01509	BUCHER LEICHTBAU AG		FOCA STC 25-20-64	EC-135-T2, EC-135-T2+ EC-135-P2+, EC-135-T1 EC-135-P1, EC-135-P2,	Installation of VIP-EC135-AC63 Bucher VIP Equipment(Revision of FOCA STC FOCA Z 25-20-64 Issue 3)		- (R)FM Supplement FMA-3 Rev. A or later approved revision-OMM VIP-EC135-AC63 Revison N/C- Master Document List MDOC-AC63 Revision D- FOCA STC Data sheet Z 25-20-64 Issue 3or later revisions of the above listed documents approved by EASA	Not applicable	14/11/2008	Active	10017275
EASA.R.S.01512	AEROSPACE DESIGN FACILITIES Ltd.		CAA UK RESPONSIBILITY	AS 355N AS 355F, AS 355F1, AS 355F2	ADF2003-001 Utility Pole Mount.This STC supersedes EASA approval 2004-1997, dated 5 March 2004.		Flight Manual Supplements: ¿ ADF2003-001 FM4 (AS355N)¿ADF2003-001 FM5 (AS355Fseries)	None.	21/08/2008	Active	10017276

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01513	AVIATION SUPPORT GmbH			EC135	Installation of High Definition (HD) Broadcasting System	CS-27	1. Flight Manual Supplement FMS-ASE-90818 High Definition BroadcastSystem (HDBS) Eurocopter EC 135 Series2. MAINTENANCEMANUAL SUPPLEMENT MMS-ASE-90818 HD Broadcasting System EC135 series3. Installationsanleitung REP-ASE-90818-4 HD Broadcasting System EC 135series(Note: This document is only availab...	With HDBS camera system installed: VMC DAY ONLY; Category "A" operationprohibited.Antenna Actuator: Minimum height to deploy antenna: 50ft AGL Maximumflight speed to deploy antenna is 75 KIAS until antenna is fullydeployed.	06/07/2009	Active	10033443
EASA.R.S.01523	AERODATA AG			EC135 T1, EC135 T2 EC135 P2+, EC135 T2+ EC135 P1, EC135 P2	1. Title: Installation of AeroPhone IRIDIUM SATCOM in EC135.2. Description: Installation of an AeroPhone IRIDIUM SATCOM system in EC135 based on AERODATA change no. AD-IRI-3.02 i.a.w. the MDL MDL-A/C-093 Rev.3 or later approved revision.		1. Flight Manual Supplement:• Flight Manual Supplement AFM-079 Rev. 12. Installation Instruction, Instructionsfor Continued Airworthiness:• Maintenance Manual Supplement AMM-791 Rev. 0• Installation and Testing InstructionsREP-A/C-1258 Rev. 2	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. The installation of this modification by third pe...	13/11/2008	Active	10017277
EASA.R.S.01529	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T2+, EC135 P2+	FSI STAR SAFIRE FLIR SKID MOUNTEDOptional installation of an external FLIR camera FSI Star Safire on the right hand multifunction carrier. The installation is basedon EC UK changeMHL/135/1155 and in accordance with drawing number A4/1351155-100-1 Issue A or later approved revision.		¿ Flight Manual Supplement:o EC UK EC135T2+ EC135P2+ FMS No. 50 Issue 1 ¿ Installation Instructions, Instructions for Continued Airworthiness:o Maintenance RequirementsDocument MR/1351155-001 Iss. A, or later approved revisiono Master Drw. No. A3/1351155-100-1 Issue A or later approve...	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2) The installation of this modification by third pers...	09/06/2009	Active	10017281
EASA.R.S.01531	ECMS AVIATION SYSTEMS GMBH			EUROCOPTER FRANCE AS 350 D EUROCOPTER FRANCE AS 350 BB EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B3 EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350B	External Antenna for Transceiver System ATS01 installation on the ldg gear crosstube.		FM Supplement for Aerial for Transceiver System ATS01 – doc. No. ATS01_FMS_EASA_R0, issue dated 01.01.2009Installation Instructions for the ATS01 system for AS350 – doc. No. ATS01_INST_EASA_R0	1. This STC provides approval for structural and electrical provisions only. Installation and operation of any equipment to be connected to the external antenna shall be covered by separate approval. 2. Prior to installation of this modification the installer must determine that the interrelati...	03/03/2009	Active	10017283
EASA.R.S.01533	DRF STIFTUNG LUFTRETTUNGG EMEINNÜTZIGE AG			EUROCOPTER DEUTSCHLAND BK117 B	Title: Installation of a L-3 SSCVR Cockpit Voice RecorderDescription: Optional Installation of a Cockpit Voice Recorder. The installation is in accordance with DRF change no. 135,MDL MD-117-31-32-00001.		Flight Manual Supplement:• BK117 B-2 Flight Manual Supplement FMS 10-DRF-001 Rev. AInstallation Instructions / Instructions for Continued Airworthiness:• Installation Manual IM-117-31-32-00001• Instructions for Continued Airworthiness CA-117-31-32-00001	1. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by thi...	04/05/2009	Active	10017285

List of EASA Supplemental Type Certificates

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01536	SAFRAN HELICOPTER ENGINES		DGAC FRANCE STC NO 84-SF-1122	EUROCOPTER FRANCE AS 350 BA EUROCOPTER FRANCE AS 350 B2 EUROCOPTER FRANCE AS 350 B1 EUROCOPTER FRANCE AS 350 B	Installation of HESIS thermic camera system manufactured bySAGEM		- Definition: CGTM technical note NT 0339/PR/fc – 25/02 dated 20.06.2002.- Installation: CGTM technical instruction IT 0339/JYC/fc – 43/01 dated 21.05.2002 and SAGEM Note, HESIS-GN/5100/Doc/007/SAG.- Maintenance: CGTM technical note NT 0333/JYC/fc/ - 75/01 dated from 13.12.2001.- Operat...	1. Only Turbomeca personal or specifically trained mechanics are allowed to install fixed parts and components of the HESIS kit.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification andany other previously installed modific...	05/01/2009	Active	10017287
EASA.R.S.01537	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	MBB BK117 C-2	- Installation of a MX 15 FLIR, Skid Mounted (Meeker Mount)- Installation of a MX 15 FLIR in combination with theinstallation of EASA.IM.R.S.01489. The installation is based on EC UK MHL/145/1157 i.a.w. Drw. No. A2/1451157-100.		- Rotorcraft Flight Manual Supplement:• Supplement No. 05 "WESCAM MX15 FLIR Surveillance System", Issue No. 1 or later approved revision- Instructions for Continued Airworthiness and Installation Instructions:• Maintenance Requirements Document, MR/1451157-001, Issue A or later approved...	1. The EC UK change ¿¿¿/¿/145/1001 must be installed prior to the installation of MHL/145/1157.2. Prior to installation of this modification the installer must determine that the interrelationship between this modification and any other previously installed modification will introduce no adver...	31/03/2009	Active	10017288
EASA.R.S.01539	AIRLIFT A/S			AS 365 N3	EMS kit installation		-Installation in accordance with Airlift AS Engineering Order EO-365-25-103 Rev 0 or later approved revisions.-Airlift AS Instruction for Continued Airworthiness ICA - 365-25-103 Rev.1 or later approved revisions.-Airlift AS Flight Manual Supplement FMS-365-25-103 Rev. 2 or later approved revisions....	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2) The installation of this modification by third pers...	27/05/2009	Active	10017289
EASA.R.S.01556	AEROLITE AG			AB412	Quick change EMS Kit		- (R)FMS-09-003 Rev. NC-OPM-09-005 Initial Issue, dated March 19, 2009-MDL-09-004 Rev. N/C-EQL-09-004 Rev. NC	1. Prior to installation of this modification the installermustdetermine that the interrelationship between this modification and anyother previously installed modificationwill introduce no adverse effect upon the airworthiness of the product.2. The installation of this modification by third person...	24/07/2009	Active	10043393
EASA.R.S.01560	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			EUROCOPTER FRANCE AS 355 SERIE					31/07/2009	Active	10028679
EASA.R.S.01561	SOCIETE D'ETUDE ET DE GESTIONAERON AUTIQUE (SEGA)			EUROCOPTER FRANCE AS 350 SERIE					31/07/2009	Active	10028678
EASA.R.S.01562	ALIDAUNIA S.R.L.			A109 S	Sat phone system usable for transmission of voice, data andGPSposition.		- BM No. 021/ALI/2008 Rev. 0- SFM FMS/ALI/021/Rev. 0	none	15/05/2009	Active	10043065

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01563	DRF STIFTUNG LUFTRETTUNGG EMEINNÜTZIGE AG			BK117 C-1	Title: Installation of Modular Airborne Data Recording/AcquisitionSystem (MADRAS)Description: Optional Installation of a Cockpit Voice and Flight DataRecorder System. The installation is in accordance with DRF change no.111< (>,<)> MOL MD-117-31-32-00003 Rev. A or later approved revision.	CS-29 Amdt. 2	- Installation in accordance with DRF change no. 111, MDLMD-117-31-32-00003 Rev. AFlight Manual/Flight Manual Supplement:- BK117 C-1 Flight Manual Supplement FMS 10-0RF-002 Rev. ATechnical Instructions:- Installation ManualIM-117-31-32-00002 Rev. A- Instructions for Continued Airworthiness CA-117-31...	None	23/06/2009	Active	10033429
EASA.R.S.01566	ECMS AVIATION SYSTEMS GMBH			BELL 206L-4 BELL 206L-3 BELL 206L-1 BELL 206L BELL 206B-1 BELL 206B BELL 206A-1 BELL 206A	Installation of Bifilar Cargo System		Flight Manual Supplement:Doc. No. BCS01_FMS_EASA_R0, dated 06.04.2009	1) Prior to installation of this modification the installermust determine that the interrelationship between this modification andany other previously installed modification willintroduce no adverse effect upon the airworthiness of the product.2) The installation of this modification by third pers...	08/06/2009	Active	10017293
EASA.R.S.01574	AIRLIFT A/S			EC 225, AS 332, SA 330 MODELS	Installation of Latitude SkyNode Satcom and Tracking System		Master Document List 332-23-106, Revision 0, dated July 6th, 2009	The SkyNode Satcom and Tracking System installed on the helicopter hasto be operated in accordance with the Flight manual SupplementFMS-332-23-106 Revision 1.	08/07/2009	Active	10030710
EASA.R.S.01578	AIRBUS HELICOPTERS UK LIMITED		CAA UK RESPONSIBILITY	EC135 T2, EC135 P2+, EC135 T2+ EC135 T1, EC135 T1 (CPDS)	Bucher 16g Stretcher InstallationInstallation of Bucher Leichtbau 16g Stretchers and Associated Equipment in the Rear Cabin. The installation is based on EC UK Major Change MCH/A/98/480H, in accordance with Master Drawing No. A0/98480-100 Issue B.This STC supersedes CAA UK AAN 26855 at Issue 2.		Flight Manual Supplements:- When installed in EC135 T1 (CDS), T1(CPDS): McAlpine Helicopters Ltd. Supplement No. 5, Bucher 16g Stretcher Installation, Issue 1 or later approved revision- When installed in in EC135 T2(CPDS): McAlpine Helicopters Ltd. Supplement No. 12, Bucher 16g Stretcher Insta...	1. Prior to installation of this modification the installermust determine that the interrelationship between this modificationand any other previously installed modification will introduce no adverse effect upon the airworthiness of the product. 2. The installation of this modification b...	15/06/2009	Active	10017294
EASA.R.S.01579	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	EC135 P2(CPDS),- P2+,-T2+	NAT Skyshout Speaker System InstallationOptional installation and integration of the NAT PA700 Skyshout system.The modification is based on EC UK change MCH/A/135/720 in accordancewith Master Drawing A2/135720-100 at Issue H or later approved revision.The change to the STC extends the applicability....		Flight Manual Supplements:- When installed in in EC135 P2 (CPDS): McAlpine Helicopters Ltd.Supplement No. 1, NAT PA700 Skyshout External Loudspeakers, Issue 1 orlater approved revision- When installed in EC135 T2+/P2+: Eurocopter UK Ltd. Supplement No. 51,NAT PA700 Skyshout External Loudspeakers, Iss...	none	15/06/2009	Active	10043090
EASA.R.S.01581	HELI-ONE (NORWAY) AS		CAA UK AAN 25867 ISSUE 2	SIKORSKY S-61N	Installation of Automatically Deployable Emergency Locator Transmitter(ADELT)		- Bond Modification No. 1731- Flight Manual Bond SupplementNo.5 or later approved revisionsNote: This STC reflects thetransfer of CAA UK AAN 25867 Issue 2 fromBond Helicopters Ltd. to Heli-One Norway AS	Prior to installation of this modification the installer must determinethat the interrelationship between this modification and any otherpreviously installed modification will introduce no adverse effect uponthe airworthiness of the product.,,This Certificate shall remain valid unless otherwise surr...	09/07/2009	Active	10043034

List of EASA Supplemental Type Certificates

easa.europa.eu

EASA STC no.	STC Holder	Rev. level	Foreign/NAA STC ref.	Models	Description	Certification basis	Associated Technical Documentation	Limitations/Conditions	Date of Issue	Status	System Record
EASA.R.S.01592	EUROCOPTER UK Ltd.		CAA UK RESPONSIBILITY	EC135T2+ EC135P2+, EC135T1, EC135T2	Installation Martin Baker Swivelling passenger SeatsNote: This STC was issued to extend UK CAA AAN 27085 issued to McAlpineHelicopters Ltd. to the models EC135 P2+ and EC135 T2+.		Eurocopter UK Supplement 6 issue 1 part of Eurocopter UK changereferenced MCH/A/99/496HUK CAA AAN No 27085 Issue 3 provided original approval. EASA STC to beissued to include addition of T2+ and P2+ variants.	none	29/06/2009	Active	10043089
LBA.21E.TA0742/ NO.709	LUFTHANSA TECHNIK AG			A321-211	Having regard to the technical visa granted by LBA (Germany) andreferenced to as "STC Nr LBA.21 E2.1:'A0742", as described in Annex IZonal Drying System Installation	Having regard to the technical visa granted by LBA (Germany) andreferenced to as "STC Nr LBA. 21 E2.1:'A0742", as described in Annex IThe STC Certification Basis is established at LBA Certification ReviewItem CRI A-100, Issue 1, dated June 06, 2003.	Having regard to the technical visa granted by LBA (Germany) andreferenced to as "STC Nr LBA.21 E2.1:'A0742", as described in Annex ILufthansa Supplemental Type Definition Doe. STDD21-03/02M issue 00 dd.Oct. 28, 2003	Having regard to the technical visa granted by LBA (Germany) andreferenced to as "STC Nr LBA.21 E2.1:'A0742", as described in Annex ICompatibility of this installation with previously installed equipmentmust be determined by the installer.Subject to compliance with the provisions of Regulation (EC)P...	05/11/2003	Active	10084485
LBA RC1063 / EASA.IM.R.S.0037	THE NORDAM GROUP LLC		FAA STC SR09036RC	MD900	Installation of a sliding window in cabin sliding door		Nordam Transparency Division of Texas drawing number 9004951, revisionD, dated April 24, 1996 orlater EASA-approved revision.	1. The Rotorcraft Flight Manual Supplement dated August 24,1995 isrequired whenoperating with the installed sliding window in cabin sliding door.2. This STC is approved only for the configuration as defined in theapproved design data referred to in the paragraph "Description".Compatibility with oth...	13/07/2004	Active	10076260
LBA RC1064 / EASA.IM.R.S.0041	THE NORDAM GROUP LLC		FAA STC SR09165RC	MD900	Installation of a cockpit door sliding window		NORDAM drawing 9004952<(>,<)> Revision B, dated September 42002<(>,<)>or later EASA approved Revisions, and Installation Instructions NTDTSTC-006, Revision B, dated August 28 2002, or later EASA approvedRevisions.	1. Continued Airworthiness must be maintained in accordancewith MDHelicopters, Inc.Maintenance Manual CSP-900RMM-2, Revision 17, dated 27/09/2002, or laterEASAapproved Revision.2. If the holder agrees to permit another person to use this certificateto alter the product, theholder shall give the oth...	13/07/2004	Active	10076261
LBA SA1357 (2004-248)	AIR PLAINS SERVICES, CORPORATION		FAA STC SA4428SW	CESSNA 172R	The installation of 180 horsepower lycoming 0-360-A3A or IO-360-L2A andpropellerMcCauley IA170/CFA7660	see Certification Basis of STC SA4428SW	Drawing List 1728803 Sh 1 & Sh 2 and 1728806·3, FAA-approved on June 12,1988 or later FAA approved revision	Cessna Model 172R limited to IO-360-L2A engine only	13/01/2004	Active	10067574
P-EASA.IM.A.S.03168	INNOTECH AVIATIONA DIVISION OF IMP GROUP LTD			BOMBARDIER BD-700-1A10					03/07/2009	Active	10028833
P-EASA.R.S.01559	POLICE AVIATION SERVICES Ltd.		CAA UK RESPONSIBILITY							Surrendered	10026893